URS

April 26, 2013

Mr. Steven F. Nightingale, P.E.
Manager, Permit Section
Illinois Environmental Protection Agency
Bureau of Land
1021 North Grand Avenue East
Springfield, Illinois 62794

**Subject:** **Soil Vapor Sampling and SVE Monitoring Report – 1st Quarter 2013**
**Roxana, Illinois**
**119115002 – Madison County**
**Equilon Enterprises LLC d/b/a Shell Oil Products US**
**Log No. B-43R**

Dear Mr. Nightingale:

On behalf of Shell Oil Products US, URS Corporation is submitting the enclosed report for your review. This report includes information required by Condition 3 of Illinois Environmental Protection Agency's (IEPA) letter dated August 5, 2010, and Condition 13 of IEPA's letter dated September 13, 2012.

If you have any questions during your review, please contact Kevin Dyer, SOPUS Principal Program Manager, at kevin.dyer@shell.com (618/288-7237), or me at robert.mooshegian@urs.com (314/743-4106).

Sincerely,
URS Corporation, on behalf of Shell Oil Products US

Kelly Hurst
Senior Environmental Scientist

Robert Mooshegian, CHMM
Senior Project Manager

Enclosures: RCRA Corrective Action Certification and Report (original plus 2 copies)

Cc: Kevin Dyer, SOPUS
Marty Reynolds, Village of Roxana (Repository)
Eric Petersen, ConocoPhillips
David Webb, IDPH
Jim Moore, IEPA, Springfield
Repository - Roxana Public Library
Gina Search – IEPA, Collinsville

1001 Highland Plaza Drive West, Suite 300
St. Louis, MO 63110
Phone: 314.429.0100
Fax: 314.429.0462

# ILLINOIS EPA RCRA CORRECTIVE ACTION CERTIFICATION

***This certification must accompany any document submitted to Illinois EPA in accordance with the corrective action requirements set forth in a facility's RCRA permit. The original and two copies of all documents submitted must be provided.***

**1.0 FACILITY IDENTIFICATION**

Name: WRB Refining LP - Wood River Refinery

Street Address: 900 South Central Ave.

City: Roxana, IL 62084

County: Madison

Site No. (IEPA): 1191150002

Site No. (USEPA): ILD 080 012 305

**2.0 OWNER INFORMATION**

Name: Not Applicable

Mailing Address:

Contact Name:

Contact Title:

Phone No.:

**3.0 OPERATOR INFORMATION**

Equilon Enterprises LLC d/b/a Shell Oil Products US

17 Junction Drive, PMB #399

Glen Carbon, IL 62034

Kevin Dyer

Principal Program Manager

618-288-7237

**4.0 TYPE OF SUBMISSION** (check applicable item and provide requested information, as applicable)

☐ RFI Phase I Workplan/Report
☐ RFI Phase II Workplan/Report
☐ CMP Report; Phase _____
☒ Other (describe):
Soil Vapor Sampling and SVE Monitoring Report – 1st Quarter 2013
Date of Submittal April 26, 2013

IEPA Permit Log No. B-43R
Date of Last IEPA Letter on Project 4/8/13
Log No. of Last IEPA Letter on Project B-43R-CA-41
Does this submittal include groundwater information: ☒ Yes ☐ No

**5.0 DESCRIPTION OF SUBMITTAL**: (briefly describe what is being submitted and its purpose)

Soil Vapor Sampling and SVE Monitoring report for the 1st Quarter 2013 in the project area located in the Village of Roxana.

**6.0 DOCUMENTS SUBMITTED** (identify all documents in submittal, including cover letter; give dates of all documents)

Cover letter, RCRA Corrective Action Certification and Soil Vapor Sampling and SVE Monitoring Report – 1st Quarter 2013

**7.0 CERTIFICATION STATEMENT** - ***(This statement is part of the overall certification being provided by the owner/operator, professional and laboratory in Items 7.1, 7.2 and 7.3 below).*** The activities described in the subject submittals have been carried out in accordance with procedures approved by Illinois EPA. I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gather and evaluate the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations.

**7.1** **OWNER/OPERATOR CERTIFICATION** (Must be completed for all submittals. Certification and signature requirements are set forth in 35 IAC 702.126.) All submittals pertaining to the corrective action requirements set forth in a RCRA Permit must be signed by the person designated below (or by a duly authorized representative of that person):

1. For a Corporation, by a principal executive officer of at least the level of vice-president.
2. For a Partnership or Sole Proprietorship, by a general partner or the proprietor, respectively.
3. For a Governmental Entity, by either a principal executive officer or a ranking elected official.

A person is a duly authorized representative only if:

1. the authorization is made in writing by a person described above; and
2. the written authorization is provided with this submittal (a copy of a previously submitted authorization can be used).

Owner Signature: _____ _____ (Date)

Title: _____

Operator Signature: Kevin Eadon 4/23/13 (Date)

Title: Principal Program Manager

7.2 **PROFESSIONAL CERTIFICATION** ***(if necessary)*** - Work carried out in this submittal or the regulations may also be subject to other laws governing professional services, such as the Illinois Professional Land Surveyor Act of 1989, the Professional Engineering Practice Act of 1989, the Professional Geologist Licensing Act, and the Structural Engineering Licensing Act of 1989. No one is relieved from compliance with these laws and the regulations adopted pursuant to these laws. All work that falls within the scope and definitions of these laws must be performed in compliance with them. The Illinois EPA may refer any discovered violation of these laws to the appropriate regulating authority.

Professional's Signature: Robert B Billman Date: 4/25/13

Professional's Name: Robert B. Billman

Professional's Address: URS Corporation
1001 Highlands Plaza Drive West
St. Louis, MO 63110

Professional's Phone No.: 314-743-4108

Professional's Seal:



**7.3** **LABORATORY CERTIFICATION** ***(if necessary)*** - The sample collection, handling, preservation, preparation and analysis efforts for which this laboratory was responsible were carried out in accordance with procedures approved by Illinois EPA.

Name of Laboratory Eurofins Air Toxics, Inc.

Signature of Laboratory Responsible Officer — Date: 4-18-13

Heidi Hayes, Technical Director
Name and Title of Laboratory Responsible Officer

Mailing Address of Laboratory

180 Blue Ravine Rd. Suite B.
Folsom, CA 95630

**REPORT**

# SOIL VAPOR SAMPLING AND SVE MONITORING– 1ST QUARTER 2013

## Roxana, Illinois

*Prepared for:*

Shell Oil Products US
17 Junction Drive
PMB#399
Glen Carbon, Illinois 62034

April 2013

URS Corporation
1001 Highlands Plaza Drive West, Suite 300
St. Louis, MO 63110
(314) 429-0100
**Project 21562850**

# TABLE OF CONTENTS

VOLUME 1

SECTION 1 INTRODUCTION ..... 1-1

SECTION 2 DESCRIPTION OF SUBSURFACE CONDITIONS ..... 2-1

2.1 Geology ..... 2-1
2.2 Hydrogeology ..... 2-2

SECTION 3 SOIL VAPOR SAMPLING AND ANALYTICAL PROCEDURES ..... 3-1

3.1 Vapor Monitoring Port Sampling ..... 3-1
3.2 Health & Safety, Decontamination and Investigation Derived Waste .... 3-5
3.3 Sample Handling and Laboratory Testing ..... 3-6
3.4 Data Quality Review and Data Management ..... 3-7

SECTION 4 SOIL VAPOR SAMPLING RESULTS ..... 4-1

4.1 Data Quality Review Results ..... 4-1
4.2 Soil Vapor Analytical Results ..... 4-1
4.3 Conceptual Site Model ..... 4-3

SECTION 5 SOIL VAPOR EXTRACTION SYSTEM MONITORING ..... 5-1

5.1 SVE System Operations ..... 5-1
5.2 SVE Maintenance Activities and Modifications ..... 5-2
5.3 SVE System Monitoring Results ..... 5-3
5.4 SVE Operation Evaluation ..... 5-4
5.5 SVE System Modification Recommendations ..... 5-6

SECTION 6 CONCLUSIONS ..... 6-1

SECTION 7 REFERENCES ..... 7-1

List of Tables

Table 1 Cumulative Groundwater Monitoring Well Gauging Results
Table 2 Soil VMP Depths
Table 3 Soil Vapor Sampling – Tedlar Sampling Data
Table 4 Soil Vapor Screening Criteria
Table 5 Cumulative Summary of Soil Vapor Analytical Detections and Screening Results: Village - VOCs
Table 6 Cumulative Summary of Soil Vapor Analytical Detections and Screening Results: Public Works Yard and WRR - VOCs
Table 7 Cumulative Summary of Soil Vapor Analytical Results - Natural Gases
Table 8 Tedlar Sampling Data for VMP-1 and VMP-47
Table 9 SVE System Monthly Monitoring – SVE Sampling Data
Table 10 SVE System Monthly Monitoring – VMP Sampling Data
Table 11 SVE System Header and Exhaust Analytical Data

# TABLE OF CONTENTS

List of Figures


| | |
|---|---|
| Figure 1 | 1Q13 Investigation Area Location Map |
| Figure 2 | 1Q13 Vapor Monitoring Point Sampling Locations |
| Figure 3 | 1Q13 Groundwater Contours |
| Figure 4 | 1Q13 Vapor Port Screen Comparison to Groundwater Elevations |
| Figure 5 | 1Q13 Summary of Benzene Soil Vapor Analytical Results-Village of Roxana |
| Figure 6 | 1Q13 Summary of Benzene Soil Vapor Analytical Results-Roxana Public Works Yard Area |
| Figure 7 | 1Q13 Summary of Benzene Soil Vapor Analytical Results-WRR |
| Figure 8 | 1Q13 Cross-Section with Benzene Soil Vapor Analytical Results-Chaffer Street |
| Figure 9 | 1Q13 Benzene Soil Vapor Distribution-5 ft bgs |
| Figure 10 | 1Q13 Benzene Soil Vapor Distribution-10 ft bgs |
| Figure 11 | 1Q13 Benzene Soil Vapor Distribution-25 ft bgs |
| Figure 12 | 1Q13 Dissolved Phase Benzene Concentrations in Groundwater |
| Figure 13 | 1Q13 Thickness of LNAPL |
| Figure 14 | 1Q13 SVE System Layout |


VOLUME II

List of Appendices


| | |
|---|---|
| Appendix A | Data Review and Laboratory Analytical Reports |
| Appendix B | SVE System Leg Flow Rates |
| Appendix C | Total Header Hydrocarbon Concentrations |
| Appendix D | SVE System Flow Rates |

Shell Oil Products US (SOPUS) has been conducting a subsurface investigation in the Village of Roxana in the area generally bounded by the alley north of East First Street, the Roxana Public Works Yard, Illinois Route 111 and the property boundary (a/k/a West Fenceline) of the WRB Refining, LP (WRB)[1] Wood River Refinery (WRR) (**Figure 1**). Additional investigation has been conducted inside the WRR; this work was conducted in cooperation with WRB/Phillips 66 (P66)[2]. For the purposes of presentation in this report only, the combined area is collectively referred to as the "Investigation Area." The Investigation Area includes a portion of a residential area in the Village of Roxana, Roxana Public Works Yard, and the adjoining portions of the WRR. For the purposes of this report, the term "Village" is used to denote the residential area generally bounded by the alley north of East 1st Street (north), 8th Street (south), Chaffer Street (east) and Illinois Route 111 (South Central Avenue) (west).

SOPUS has been investigating and delineating soil vapor in the Investigation Area through the installation, development, and sampling of vapor monitoring ports (VMPs). Vapor monitoring locations (VMP-1 through VMP-16) were installed based on a work plan submitted to the Illinois Environmental Protection Agency (IEPA) on behalf of SOPUS on January 21, 2009. IEPA approved the work plan with conditions on May 12, 2009 (IEPA, 2009). The results of the vapor investigation and delineation efforts were presented in the *Dissolved Phase Groundwater Investigation and P-60 Free Phase Product Delineation Report*, dated February 18, 2010 (URS, 2010a). Based on recommendations contained in that report, an additional four vapor monitoring ports were installed, developed, and sampled at one existing (VMP-3) and three new vapor monitoring locations (VMP-17 through VMP-19) in the Spring/Summer 2010, with results presented in the *Addendum to February 2010 Report – Supplemental Investigation Activities*, dated September 20, 2010 (URS, 2010b).

IEPA provided comments to the February 18, 2010 report in a letter to SOPUS dated August 5, 2010 (IEPA, 2010). In particular, Comment Number 3 required quarterly soil vapor sampling and reporting, and Comment Number 2 described the need to further delineate the extent of soil vapors beneath the area. Six VMPs (VMP-20 through VMP-25) were installed and added to the quarterly sampling program beginning with 1st Quarter 2011 (1Q11).

IEPA provided further comments in a March 16, 2011 letter (IEPA, 2011) to SOPUS approving the *Soil Vapor Extraction (SVE) Pilot Test Workplan*. In particular, Comment Number 2

[1] WRB, formed January 1, 2007, is a 50/50 joint venture between ConocoPhillips (COP) and EnCana US Refineries, LLC (now known as Cenovus Energy, Inc.).

[2] ConocoPhillips Company announced the separation of the Refining and Marketing business from the Exploration & Production business on July 14, 2011. The separation included an ownership change as well as a name change that became effective May 1, 2012. Phillips 66 is now the operator of the WRB WRR.

required that quarterly soil vapor sampling continue at the 25 VMP locations, and Comment Number 9 requested an updated report, including a discussion of the geology, extent of groundwater impact, and distribution of impacted soil vapor. These items/comments were included in the 1Q11 Soil Vapor Report (URS, 2011a), and have been updated for this report.

As a result of a meeting between SOPUS and the IEPA on February 8, 2012, the quarterly soil vapor sampling program was expanded to include six additional soil VMPs (VMP-31, VMP-32, and VMP-42 through VMP-45). VMP-31 and VMP-32 were installed in 2nd Quarter 2011 (2Q11) to monitor soil vapor during operation of the Internal Combustion Engines (ICE) located near 4th and Chaffer Street. VMP-42 through VMP-45 were installed during the 3rd Quarter 2011 (3Q11) and 4th Quarter 2011 (4Q11) in conjunction with the SVE System installation to monitor soil vapor concentrations. Monitoring of these VMPs commenced with the 2nd Quarter 2012 (2Q12) sampling event.

Based on the September 13, 2012 letter (IEPA, 2012), VMP-29, VMP-30, and VMP-41 located within the Roxana Public Works yard were added to the quarterly sampling program during 3Q12. VMP-29 and VMP-30 were installed to monitor the SVE pilot test within the Roxana Public Works Yard in 2Q11. VMP-41 was installed during the 3Q11 in conjunction with the SVE System installation to monitor soil vapor concentrations within the Roxana Public Works Yard. Additional VMPs (VMP-47 through VMP-55) were installed during the 4th Quarter 2012 (4Q12) in the Village. Monitoring of these VMPs commenced in the 1st Quarter 2013 (1Q13) sampling event. The locations of these VMPs in the soil vapor sampling network are presented on **Figure 2**.

In the September 13, 2012 letter, IEPA also requested development of a quarterly report documenting the results of monitoring and remedial efforts associated with operating the SVE system. These results were added to the 4Q12 Soil Vapor Sampling and SVE Monitoring report. Results of SVE system monitoring and remedial efforts are presented in **Section 5**.

This section summarizes the current understanding of the Investigation Area geology and hydrogeology.

## 2.1 GEOLOGY

The Investigation Area is located approximately 1.5 miles east of the Mississippi River within the American Bottoms floodplain. The surface topography is generally flat; however it slopes downward to the west-southwest in the southwestern portion of the Village, with a total drop in elevation of approximately 15 feet across the area.

The ground surface in the Village within the Investigation Area, where not developed with structures, is primarily grass covered with paved (i.e. chip and seal, asphalt, etc.) alleys and streets. Beneath any man-made fill material, the subsurface conditions generally consist of silty clay underlain by sands to the depths investigated.

Subsurface stratigraphy within the Investigation Area generally consists of the following materials, from the ground surface down:

- Fill - (mainly clay, some gravel and cinders, etc.) Extends from the surface to approximately six feet below ground surface (bgs).
- Clay/Silt - Primarily silty clay. Where present, the clay generally extends from the base of the fill to approximately 12 feet bgs.
- Sand - Consisting primarily of fine to medium grained (which coarsens with depth) sand with some silt and clay, especially at the shallower depths. The sand begins at the base of the clay (or base of the fill if the clay is not present) and extends to the total depth of the borings.

Discontinuous lower permeability lenses of clay with some silt and sand are occasionally present. These lenses vary in thickness from 1 inch to a few feet and do not appear to be laterally (or vertically) extensive.

Cross-sections depicting the underlying geology were previously presented in the *Dissolved Phase Groundwater Investigation and P-60 Free Phase Product Delineation Report*, dated February 18, 2010 (URS, 2010a). These cross-sections were developed based on information provided on cone penetration test (CPT) logs and soil boring logs. A modified cross-section presenting analytical data is discussed in **Section 4.3** of this report.

## 2.2 HYDROGEOLOGY

Groundwater in the sand underlying the Investigation Area is the primary source for large volume water production in the area (e.g., industrial and municipal supply). Prior to development in the area, the natural movement of groundwater was toward the west (toward the Mississippi River). Since development in the area, groundwater pumping has altered the groundwater flow in the area to flow toward nearby pumping wells (e.g. WRR, BP, etc.).

The water table encountered during 1Q13 was at a depth of approximately 28 to 47 feet bgs (approximate elevation 399 to 402 feet above sea level). The variation in depth of groundwater from the ground surface is partially due to a change in surface elevation across the study area. As a result, there is generally a 15 to 30 foot thick vadose (unsaturated) zone in the sand. Groundwater gauging data from 1Q13 indicates that the groundwater has dropped up to 1 or 2 feet along the WRR West Fenceline since 4Q12. Water level measurements collected during the 1Q13 groundwater gauging event and historical water level measurements collected over the past three years are provided in **Table 1**. Depth to product (if present) and depth to water were noted in electronic format using Panasonic Toughbook® technology (Toughbook®) and on groundwater field gauging sheets.

There are discontinuous low permeability clay lenses above the water table (approximately 20 feet bgs) mixed with silt and sand. These clay lenses are isolated and limited in occurrence. There are additional discontinuous clay lenses at a depth of approximately 40 to 45 feet bgs localized in the area of East 3rd Street and Chaffer Street. These may be above or below the water table depending on groundwater conditions. As a result, the groundwater contours displayed on **Figure 3** show a slight mounding in this area.

The potentiometric surface observed during the 1Q13 comprehensive groundwater monitoring well gauging[3] (**Figure 3**) illustrates groundwater flow within the Village and WRR. **Figure 4** provides the groundwater potentiometric surface for the Investigation Area with respect to the deepest vapor ports. The gauging results indicate that some of these vapor ports were submerged beneath the water table during this event. This is further discussed in **Section 3.1**.

[3] 1Q13 groundwater gauging performed January 2-4 and 7-8, 2013.

The 1Q13 soil vapor sampling event was performed in accordance with applicable URS site-specific Standard Operating Procedures (SOPs) that incorporate previous IEPA comments, conditions, and/or modifications. The 1Q13 VMP sampling event was conducted January 21 through February 18, and March 6, 2013.

## 3.1 VAPOR MONITORING PORT SAMPLING

The soil vapor sampling network currently consists of 55 VMP locations (**Figure 2**), of which 43 locations are currently being utilized for quarterly sampling. VMPs are generally screened at four depths[4] at each location. The individual VMPs are labeled and color-coded in the field from shallow to deep by using the color scheme of yellow (first interval), blue (second interval), green (third interval), and red (fourth interval). Additional VMPs installed as part of a supplemental sampling event in 2nd Quarter 2010 (2Q10) are color-coded white (10-foot depth). Vapor ports installed during 3Q11 and 4Q11 do not have the shallow (5-foot depth) port included, and begin with the blue interval port. Soil VMP depths are provided in **Table 2**.

### VMP Sampling

VMP sampling activities were attempted at each designated location within the Investigation Area. The sampling was performed in accordance with SOP No. 44R4 – Soil Vapor Purging and Sampling and ASTM D-7663-12.

Prior to VMP sampling, an initial stainless-steel canister vacuum check was performed. A designated pressure gauge provided by the laboratory was attached to the stainless-steel canister inlet, and the stainless-steel canister valve was opened completely. The pressure gauge reading was recorded as "Initial Vacuum Reading" on the stainless-steel canister tag and the field form. This ensured that the canister showed a vacuum of approximately 26 to 30 inches of mercury (Hg). If the canister displayed an initial vacuum of less than 26 inches of Hg, the canister was set aside and returned to the laboratory.

In addition, each flow controller was subjected to an isolated vacuum check to ensure that connectors did not leak. This was conducted by attaching a plug to one end of the flow controller and a barbed connector to the other. A 15 mL hand pump with a vacuum gauge was then attached to the barb. The hand pump evacuated the air inside the flow controller until a vacuum of at least 10 inches Hg was achieved. If the vacuum change over five minutes was equal to or less than 0.5 inches of Hg, the controller was considered acceptable for sampling use.

The following steps were used to collect each VMP sample:

[4] With the exception of single shallow ports at VMP-17, 18, 19, three ports at VMP 41 through VMP 45, and five ports at VMP-3.

- Upon arrival at a sampling location, the sampling crew would open the vapor port vault to visually check integrity of each individual soil VMP. This included checking that each port was closed with either a Swagelok® stainless-steel reducer and plug or a 4-way stopcock in place, and each VMP was properly labeled to identify the proper depth.
- The sample train was set up as shown in the photo below. After removing the stainless steel reducer or 4-way stopcock, a hose barb connector on the sample train was connected directly to the monitoring port using compression ferrule connections. A flow controller, provided by the laboratory, was then connected to the stainless-steel canister inlet. Flow controllers were not reused during the sampling event. Each flow controller is pre-set by the laboratory to collect the sample over a half-hour period. For a 1-Liter stainless-steel canister, one half-hour is a standard collection time (~28 ml/min). Once the sample train was assembled, a vacuum leak check was performed in accordance with SOP No. 44R4 – Soil Vapor Purging and Sampling.
- An enclosure was then placed over the VMP and assembled sample train as shown in the photo below. The enclosure has openings for:
  - The introduction of tracer gas (i.e., helium);
  - Pressure relief to the atmosphere and access for a tracer gas monitoring device;
  - Tygon® tubing to connect to the peristaltic pump for Valve #1 (out) and Valve #2 (out and in).



- The enclosure has sufficient glove access to open or close all valves within. The enclosure was sealed to the ground at each location with a hydrated bentonite seal.
- Helium gas was introduced into the enclosure until the atmosphere reached a concentration of approximately 50% Helium; the regulator on the helium tank was manually controlled to maintain that range.
- Three well volumes were purged from each VMP prior to sampling using a 15 mL hand pump[5]. If the pump gauge held a vacuum, the VMP was presumed to be saturated with water and no sample was collected. VMP water saturation was compared against the groundwater measurements from the initial gauging event for confirmation.
- After purging was completed a Tedlar bag sample was collected using a peristaltic pump. A Dielectric Technologies MGD-2002 field analyzer was then used to detect possible helium within the Tedlar bag sample. This check verifies the vacuum check for the sample train and integrity of the sample port. If the helium reading was $\geq$10% concentration of the helium in the enclosure, the Tedlar bag sample was additionally analyzed using a Landtec landfill gas detector to obtain a direct methane reading. The presence of methane can cause a false positive helium reading on the MGD-2002 field analyzer.
- Once the initial helium leak check was completed, the stainless-steel canister valve was opened to collect a sample for approximately 30 minutes or until a vacuum gauge reading of 5 inches Hg was observed. After sample completion, the stainless-steel canister valve was closed (isolating it from the sample train) and soil vapor was bypassed to the second Tedlar bag sample.
- A second Tedlar bag was filled following the completion of the stainless-steel canister sampling. Soil vapor readings were taken from the Tedlar bag sample for total volatile organics with a photoionization detector (PID) and a Thermo Scientific TVA 1000 Vapor Analyzer - Flame Ionization Detector (FID); and for carbon dioxide ($CO_{2)}$, methane ($CH_4$), lower explosive limit (LEL), and oxygen ($O_2$) with a Landtec GEM 2000 landfill gas meter. Readings were also obtained and recorded for helium with a MGD-2002 field analyzer. This check was used to verify the sample train integrity during and at the completion of sampling.

[5] The purge volume was calculated using the following assumptions: vapor port tubing (1/8-in diameter): 2.41 ml/foot (single volume) and sample train assembly (1/4-in diameter): 9.65 mL/foot (single volume).

- At the completion of sampling, the stainless-steel canister and flow controller were removed and separated from the sample train and a final vacuum reading was taken with a designated pressure gauge provided by the laboratory. The stainless-steel canisters were then maintained in a safe location to minimize temperature change and protect from damage prior to shipping.
- At the completion of sampling, either the VMP plug was reinstalled or the 4-way stopcock was closed to maintain port integrity.
- Field data pertaining to canister identification data (ID), start and finish time, initial and final vacuum readings, purge volumes, and leak checks for each VMP was recorded electronically using a touchpad in a Soil Vapor Sampling – Canister Sampling Data database. Data from portable field analyzers, such as, a PID, a FID, a landfill gas meter, and a helium gas detector were recorded electronically in the field by using a Toughbook.
- Field duplicates were collected by including an additional T-connection in the sample train and attaching a second stainless-steel canister with a separate flow controller. Both the original and duplicate samples were started at the same time.

Field measurements from this event and previous three years of consecutive quarterly events are presented on **Table 3.**

Additional Notes on VMP Sampling

***Saturated VMP Screens*** **-** The groundwater monitoring well gauging results indicated that some of the VMP screens were submerged beneath the water table during 1Q13. However, purging was attempted at each of the ports with a 15 mL hand pump to verify the VMP screens were submerged.

A total of four 4th interval VMPs held a vacuum or produced water when purged with a 15 mL hand pump indicating the VMPs were most likely submerged beneath the water table. Three of the four VMPs are located in the Public Works Yard. One 1st interval VMP and two 2nd interval VMPs were also found to be submerged. Three of the seven submerged screens were present at VMP-55, which was sampled for the first time in 1Q13. Three attempts were made to develop VMP-55-5, VMP-55-10, and VMP-55-30; however, all ports remained submerged after each development attempt. VMPs that were submerged and could not be sampled during 1Q13 are identified on **Figures 5 and 6**.

***Resamples*** **–** VMP-9-5 and VMP-51-20 were resampled on February 15, 2013 after the samples collected on January 25, 2013 and February 1, 2013, respectively, were discovered to have leaking valve fittings at the laboratory. VMP-3-39 and VMP-6-5 were resampled on February

12, 2013 after the samples collected on February 7, 2013 yielded a final vacuum of zero (0) inches of Hg on field pressure gauges. VMP-20-5 was resampled on February 7, 2013 after the sample collected on January 22, 2013 yielded a final vacuum of zero (0) inches of Hg at the laboratory. The field data for these samples are provided on **Table 3**.

***Helium Leaks –*** Fourteen VMPs failed to pass the helium leak check in the field when sampling was initially attempted. Sampling was reattempted at twelve of these VMPs: VMP-2-8.5, VMP-3-5, VMP-7-5, VMP-7-29.5, VMP-7-38.5, VMP-12-5, VMP-12-11.5, VMP-16-31, VMP-24-10, VMP-31-10, VMP-43-10, and VMP-44-30. Valid samples were obtained, except for VMP-3-5, VMP-7-5, VMP-7-29.5, VMP-7-38.5, VMP-43-10, and VMP-44-30 due to three consecutive helium leak check failures in the field. These VMPs are being evaluated for possible replacement. VMP-1-23.5 and VMP-1-38.5 were not reattempted as described in **Section 5.2**. The field data for these samples are provided on **Table 3**.

## 3.2 HEALTH & SAFETY, DECONTAMINATION, AND INVESTIGATION DERIVED WASTE

### Health & Safety

The quarterly sampling activities were performed and governed by the *Roxana / Route 111, WRR, and Rand Avenue Investigation and Remediation Health and Safety Plan*, dated January 2013 (URS, 2013a), as prepared by URS.

Prior to beginning site work and at the start of work each day, a daily safety meeting was held. The purpose of this meeting was to discuss the day's planned activities and to address any potential health and safety concerns. As a part of the daily safety meeting, job safety analyses (JSAs) were reviewed to address task specific safety concerns.

URS field personnel primarily wore U.S. Environmental Protection Agency (USEPA) modified Level D personal protective equipment (PPE), which included hard hat, steel-toed boots, safety glasses, etc. In addition, work within the WRR was performed wearing flame retardant clothing (FRCs) per WRR requirements (in areas where required**)**.

A PID with a 10.6 electron volt (eV) probe, combustible gas indicator (CGI), UltraRAE with benzene specific measuring tubes, and individual hydrogen sulfide gas detectors (for locations inside WRR) were used as needed during the field activities to monitor air quality. Field instruments were calibrated prior to use each day in accordance with the manufacturer's specifications.

### Decontamination

Field personnel and equipment underwent decontamination procedures to ensure the health and safety of those present, to maintain sample integrity, and to minimize cross contamination. Non-

disposable/reusable sampling equipment (e.g., compression fittings) was decontaminated prior to the collection of each analytical sample by spraying with Alconox or Liquinox and distilled water. For vapor sampling equipment, a 15 mL hand pump was attached to the sampling apparatus and ambient air was pumped into the sampling apparatus to remove any internal dust particles or moisture. Personnel and small equipment decontamination was performed at the sample locations.

### Investigation Derived Waste

Investigation derived waste (IDW) for this sampling event included PPE and expendable materials (e.g., gloves and tubing), which has a low probability of impact. The expendable materials were collected in trash bags and disposed with municipal waste.

## 3.3 SAMPLE HANDLING AND LABORATORY TESTING

### Sample Handling

Stainless-steel canisters were labeled with a sample ID, site name, sampler initials, sample date and time, the parameters that were to be analyzed, and pre- and post- vacuum readings. After collection, the samples were logged on a chain of custody (COC) form and packaged in a UN certified box to prevent damage during shipment. The samples were then delivered under the proper COC documentation to the laboratory. Due to the potential flammable nature of the vapor in the stainless-steel canisters, some soil vapor samples were shipped as hazardous materials according to applicable International Civil Aviation Organization (ICAO) regulations.

### Laboratory Testing

Eurofins Air Toxics, Inc. (Eurofins) of Folsom, California conducted the laboratory testing and the following test methods were utilized during this scope of work:

- Volatile Organic Compounds (VOCs) via Modified USEPA Total Organic-15 (TO-15) (including butane and isopentane) for soil vapor, and
- Natural gases (defined for purposes of this report as oxygen, nitrogen, carbon monoxide, methane, carbon dioxide, ethane, and ethene) via Modified ASTM D-1946 + Helium and/or ASTM D-1945 (expanded natural gas analyte list) for soil vapor.

URS worked with the laboratory to attain reporting limits for compounds that have screening criteria so that, to the extent possible, they were less than the screening criteria. In some cases, this necessitated reporting results between the method detection limit (MDL) and reporting limit (RL). Although results reported in this range are "J"-flagged as estimated, these data may be beneficial in cases where analytes would otherwise be reported as non-detect at RLs above

screening levels. The laboratory provided URS with a list of their "base" RL capability for target analytes. Sample RLs are a product of base RL, pressurization dilution factor, and analytical dilution factor. Thus the sample RL will increase with increases in dilution factor. Results that were reported below the RLs but above the MDL were "J"-flagged as estimated concentrations by the laboratory.

## 3.4 DATA QUALITY REVIEW AND DATA MANAGEMENT

Laboratory data were provided in electronic form, and analytical data were independently reviewed and qualified by URS. One hundred percent of the data were subjected to a data quality review (Level 3 review). Evaluation of the data followed procedures outlined in the USEPA National Functional Guidelines for Superfund Organic Methods Data Review (USEPA, 2008). Specific criteria reviewed included sample receipt condition and holding times, method blanks, surrogate spike recoveries, laboratory control samples, results reported from dilutions, and field duplicate results. The laboratory assigned data qualifiers on the basis of their quality control or to indicate sample analysis information (e.g., dilutions). Data qualifiers were also added by URS, as appropriate, and are included on the data tables and laboratory result pages. Laboratory data reports along with data reviews are included in **Appendix A**.

The screening values used were presented in IEPA's proposed amendments to Tiered Approach to Corrective Action Objectives (TACO) Title 35 – Part 742; Appendix B, Table H: Tier 1 Soil Gas and Groundwater Remediation Objectives for the Indoor Inhalation Exposure Route – Diffusion and Advection for soil vapor dated November 9, 2010 and are shown on **Table 4.** Not all TO-15 Method constituents have TACO screening criteria.

Field data and documentation collected as part of this scope of work became part of the project file. URS maintains the files for the site and the database management system.

The following documentation was completed and supplements the COC records, excluding SVE system data which are described in **Section 5**:

- Field logbooks;
- Groundwater field gauging sheets;
- Soil vapor sample collection sheets;
- Field sample collection data via electronic Toughbook®; and
- Safety documentation

## 4.1 DATA QUALITY REVIEW RESULTS

A total of 149 investigative and 15 field duplicate samples were collected from VMPs for analysis of VOCs (TO-15 analytes) and natural gases. Compounds qualified by URS due to method blank contamination, field duplicate results, and quality control sample recoveries are specified in the data reviews (**Appendix A**). Based on method blanks, laboratory control sample recoveries, results reported from dilutions, and field duplicate results, soil vapor results reported for the analyses performed were accepted for their intended use.

## 4.2 SOIL VAPOR ANALYTICAL RESULTS

The following TO-15 analytes were detected at concentrations at or above the reporting limit in soil vapor during the 1Q13 sampling event:

TO-15 Detections

| | |
|---|---|
| Acetone | Isopropylbenzene (Cumene) |
| Benzene | 4-Methyl-2-pentanone |
| Bromodichloromethane | Methyl tert Butyl Ether (MTBE) |
| Butane | n-Propylbenzene |
| 2-Butanone | 2-Propanol |
| Carbon disulfide | Tetrachloroethene |
| Chloroform | Tetrahydrofuran |
| Cyclohexane | Toluene |
| 1,2-Dichloropropane | 1,1,1-Trichloroethane |
| Dichloromethane (Methylene chloride) | Trichloroethene |
| Ethanol | Trichlorofluoromethane |
| Ethylbenzene | 1,2,4-Trimethylbenzene |
| 4-Ethyltoluene | 1,3,5-Trimethylbenzene |
| Heptane | 2,2,4-Trimethylpentane |
| Hexane | m,p-Xylene |
| Isopentane | o-Xylene |

Italicized analytes were detected at or above the reporting limit for the first time this quarter. Additionally, several compounds were detected at concentrations estimated below the reporting limit.

Cumulative tabular summaries of the analytical results for the Village are presented in **Table 5** and the Roxana Public Works Yard and WRR are presented in **Table 6.** Analytical results were compared to the previously mentioned screening values. Sample results from VMP-1 through VMP-9, VMP-18 through VMP-24, VMP-31, VMP-32, VMP-42 through VMP-45, and VMP-47 through 54 (located near residences in the Village) were compared against the proposed residential screening criteria. Samples from VMP-10 through VMP-17, VMP-25, VMP-29,

VMP-30, VMP-41, and VMP-55 (located at or near the Public Works Yard or WRR) were compared against the proposed industrial/commercial screening criteria. A cumulative tabular summary of the results for natural gases are presented in **Table 7.** The laboratory analytical reports for the soil vapor samples collected during 1Q13 sampling event can be viewed in **Appendix A.**

Data from VMP-1 and VMP-47 are included on the data tables and figures; however, based on the integrity assessment this data is not believed to be representative. VMP-1 has been replaced and VMP-47 will be replaced in 2Q13. For additional information refer to **Section 5.2**.

Benzene was selected as the key analyte to characterize soil vapor, in the paragraphs below.

Village

Benzene detected concentrations from locations within the Village ranged from an estimated 0.00077 mg/m$^3$ (VMP-24-10) to 92 mg/m$^3$ (VMP-50-30). The results of screening for samples collected in the Village against the proposed residential screening criterion indicate that seven of the sample locations had at least one port with a benzene concentration above the proposed residential screening criterion (0.37 mg/m$^3$) during this sampling event. The cumulative results for benzene in soil vapor for samples collected in the Village are depicted on **Figure 5**.

Analytical results also identified an exceedance of the proposed residential screening criterion for m,p-Xylene and o-Xylenes at VMP-4-39. Exceedances of m,p-Xylene and o-Xylenes has been observed at VMP-4-39 in prior sampling events. VMP-50-30 had exceedances of m,p-Xylene and o-Xylenes for the first time in 1Q13. Exceedances of Dichloromethane and 1,2,4-Trichlorobenzene were observed at VMP-2-42, which had previously been submerged since 2009.

Roxana Public Works Yard

Benzene concentrations from locations within the Roxana Public Works Yard ranged from an estimated 0.0017 mg/m$^3$ (VMP-10-5) to an estimated 13,000/54,000 (sample/duplicate) mg/m$^3$ (VMP-14-29). Samples from at least one port at four of the locations within the Roxana Public Works Yard exceeded the proposed commercial/industrial screening criterion (2.8 mg/m$^3$) for benzene. The cumulative results for benzene in soil vapor for samples collected in the Roxana Public Works Yard are depicted on **Figure 6**.

WRR

Benzene concentrations from the locations sampled within the WRR ranged from an estimated 0.0008 mg/m$^3$ (VMP-12-11.5) to 4,100 mg/m$^3$ (VMP-12-39). Samples from at least one port at the two locations within the WRR exceeded the proposed commercial/industrial screening

criterion (2.8 mg/m$^3$) for benzene. The cumulative results for benzene in soil vapor for samples collected in the WRR are depicted on **Figure 7**.

Natural Gas Data

Natural gas data indicate that the concentration of methane increases from shallow to deep sample depths, but oxygen concentrations decrease from shallow to deep sample depths (methane and oxygen are generally inversely correlated in soil vapor). In general, the trend in oxygen levels in most VMPs has been upward since the SVE system has been operating. Higher oxygen levels (>5%) with lower methane levels indicate an environment capable of supporting aerobic biodegradation (Ririe et al., 1998). Oxygen levels appear to be increasing in VMPs closer to the SVE system (e.g. along Chaffer Street) in the Village. A summary of the natural gas results is presented in **Table 7.**

## 4.3 CONCEPTUAL SITE MODEL

Vapor Intrusion

The primary concern for shallow soil gas is the potential for intrusion through basement and/or building slabs. In September 2011, SOPUS began installation of a full scale SVE system to address the source of these vapors. The system became operational on January 31, 2012 following the completion of the 1Q12 sampling effort. The objective of the SVE system is to mitigate vapors along the West Fenceline of the WRR and in the vicinity of the Roxana Public Works Yard. Construction of the Roxana Public Works Yard portion of the SVE system was completed during 4Q12, and this portion became operational on December 3, 2012. Refer to **Section 5.1** for further discussion on SVE system operation. **Figure 8** presents a cross-section along Chaffer Street with a vertical distribution of the benzene concentrations superimposed.

At most locations, oxygen is present in the shallow depths and little or no aromatic hydrocarbons (e.g., BTEX) are present. Carbon dioxide levels are relatively high throughout the soil column at many locations, which supports that degradation of petroleum hydrocarbons is occurring via aerobic biodegradation. There is up to 30 feet of open vadose zone which allows for biological degradation of constituents in soil vapor as they slowly diffuse upwards.

C Tech Development Corporation's Environmental Visualization System PRO, Version 9.52 (EVS-PRO) was used to model the estimated distribution of benzene in the soil vapor. **Figure 9, Figure 10,** and **Figure 11** present a horizontal distribution of benzene at 5, 10, and 25 feet bgs, respectively.

Groundwater Monitoring Well Gauging and Sampling

The results for groundwater monitoring well gauging and sample are presented in the *Interim Groundwater Monitoring Program – 1st Quarter 2013* report (URS, 2013b). **Figure 12** presents the estimated distribution of dissolved phase benzene in the groundwater. Light non-aqueous phase liquids (LNAPL) thicknesses observed during the 1Q13 comprehensive monitoring well gauging is presented in **Table 1** and shown on **Figure 13**.

As requested in the SVE system approval letter from IEPA, 2012 (Condition Number 13), this section addresses operation of the SVE system. As such, the discussion in this section will address operation of the SVE system from start-up through the end of the quarter that this report represents.

As presented in the June 2011 *Conceptual/Final Design Report* (URS, 2011b), the May 2012 *SVE System Construction Completion Report* (URS, 2012), and the February 2013 *SVE System Construction Completion Report Addendum* (URS, 2013c), URS designed and constructed a SVE system along the West Fenceline and within the Public Works Yard. The SVE system was installed to reduce the potential for vapors from LNAPL and impacted soil and groundwater within WRR to migrate into the Village.

The SVE system consists of 34 SVE wells, 25 of which are located along the West Fenceline, three are located in the Village along East 4th Street west of Chaffer Avenue, and 6 are located in the Public Works Yard. The SVE wells are connected via 4-inch piping to vapor/liquid separators (VLS) and a rotary lobe positive displacement blower housed within a customized intermodal freight container ("conex") (**Figure 14**). Piping from the SVE wells feeds into the conex, where vapor moves through the VLS', before traveling through the blower and a baffle connected to a Regenerative Thermal Oxidizer (RTO). A second blower, located on the RTO side of the baffle, pushes the vapor into the RTO and adds fresh air to dilute the vapor stream as necessary.

## 5.1 SVE SYSTEM OPERATIONS

System start-up was initiated on January 31, 2012. Five individual header lines are connected to specific sets of SVE wells along the West Fenceline and or in the Village at 4$^{th}$ Street. These lines carry vapors to the RTO and the relationship between the SVE wells and the lines that they are connected is shown on **Figure 14**. As the system was starting up, vapor removal from specific sets of wells were brought on line in a systematic order. The line connected to wells SVE-3, SVE-4, and SVE-25 was brought online first systematically followed by the others until all lines and wells were in operation.

Full scale operations commenced on April 1, 2012, with all lines and all SVE wells in operation, except for those located inside the Public Works Yard. Only one of the SVE wells (SVE-20/located outside of the Public Works Yard) on that line was operational during the first three quarters of the year. Lack of access prevented SVE wells inside the Public Works Yard from being connected until December of 2012. The remaining SVE wells inside the Public Works boundary (SVE-21 through SVE-24, SVE-26, and SVE-27) connected to a 6$^{th}$ line were brought online December 2012 when construction of that section was completed.

Sampling of VMP-1 through VMP-46 commenced during or prior to 3Q12 (mentioned in Condition Number 9 in the IEPA, 2012 letter). In addition, sampling of VMP-47 through VMP-55 commenced in 1Q13.

## 5.2 SVE MAINTENANCE ACTIVITES AND MODIFICATIONS

URS personnel have performed scheduled system maintenance as outlined in the manufacturers' suggested operations and maintenance (O&M) documents. The scheduled maintenance includes routine lubrication, and inspection of belts, oil levels, and emergency stops, along with water levels and associated switches with the vapor liquid separators (VLSs). Timing and frequency of maintenance activities is dependent on the designated intervals. Checking and cleaning of filters and components exposed to dirt and/or the elements were performed as part of a routine weekly inspection. System SVE wells and associated vaults inspections were also conducted on a weekly basis. The last scheduled 800 hour maintenance event was performed by Anguil on March 22, 2013 and included among other things changing the VLS and manual dilution line air inlet filters.

In addition to routine maintenance, the following maintenance and repairs were performed on the system.

- **February 4, 2013** – Blower motor cover gasket replaced.
- **March 22, 2013 –** Flame igniter replaced on RTO unit.

Activities associated with system maintenance were appropriately documented both in the field maintenance log maintained on site and in the office central (electronic) file.

### System Modifications

Based on anomalous field screening results during the monthly SVE system monitoring of VMP-1 on January 16, 2013 and data also obtained from nearby VMP-47 on January 19, 2013, the integrity of these VMPs was evaluated during 1Q13. Tedlar sampling was initiated daily on January 19, 2013 for VMP-1 and VMP-47 to evaluate the conditions at these VMPs. Daily Tedlar sampling data for VMP-1 and VMP-47 can be found in **Table 8**. On January 23, 2013, all four VMP depths at VMP-1 and VMP-47 were sampled with grab canisters. On January 28, 2013, adjustments were made to the SVE system to increase the vacuum in this area. Vacuum pressure communication tests were then conducted on each port at VMP-1 and VMP-47 on February 12, 2013 and February 14, 2013 to check for potential integrity issues. Based on the data at VMP-1 (vacuum pressures were detected in the shallow port when applied to the deep port and vice versa), it appeared there was communication between the ports suggesting a loss of integrity at VMP-1. Because of this finding, resampling of VMP-1 was not reattempted, as

described in **Section 3.1**. Based on the vacuum pressure communication test for VMP-47, it was not clear there was communication between the ports at different depths; however, based on further evaluation of the screening data it appears there may be communication between the upper and lower ports. .

VMP-1 was replaced on March 6, 2013 and VMP-47 will be replaced during 2Q13. The construction information for VMP-1 and VMP-47 will be provided in a separate submittal.

## 5.3 SVE SYSTEM MONITORING RESULTS

The results of field screening samples collected monthly from SVE wells and VMPs can be found in **Tables 9 and 10**, respectively. The results of the header and RTO exhaust analytical data can be found in **Table 11**. Data reviews and laboratory analytical reports for the headers and RTO exhaust data can be found in **Appendix A**. The data required pursuant to Condition Number 11 of the IEPA, 2012 letter are contained in those tables.

**SVE Well & VMP Tedlar Sampling Details:**

- 34 SVE wells were sampled monthly. SVE wells are shown on **Figure 14**.
  - SVE-3, SVE-4, and SVE-25 are located in the Village
  - SVE-5 through SVE-20 and SVE-26 through SVE-36 are located on WRR North Property
  - SVE-21 through SVE-24, SVE-26, and SVE-27 are located on Roxana Public Works Property
- 38 VMPs were sampled this quarter (VMP-1 through VMP-7, VMP-9, VMP-12, VMP-17, VMP-19, VMP-26 through VMP-28, VMP-31 through VMP-40, and VMP-42 through VMP-55)
- With the exception of VMP-17 and VMP-19, VMP locations contain either 3 or 4 screen depths between 5 feet and 42 feet bgs. Locations VMP-17 and VMP-19 contain only one. Soil VMP depths are provided in **Table 2**.

**SVE System Monitoring Results:**

- The reduction in hydrocarbons has improved due to daily monitoring and adjustments of the SVE system (addition of Roxana Public Works SVE wells and continued reduction of dilution air). See mass removal calculation discussion details in **Section 5.4**.
- Vacuum measurements were obtained monthly at all of the SVE wells and selected VMPs within the Village and WRR. Vacuum data can be found in **Table 9 and 10**.
- Differential pressure data collected from each SVE leg located at the RTO were obtained and can be found in **Appendix B**.

Trends related to hydrocarbon concentrations monitored in the field are expected to continue, and these numbers are expected to improve as the system is operated and/or optimized.

## 5.4 SYSTEM OPERATION EVALUATION

A key focus of the system operation thus far has been stability and consistency. The system has been more than 96% operational since its start-up. For the months of January, February, and March 2013, the system operational time has been 98.9%, 94%, and 99.4% respectively.

The demonstrated consistency of subsurface vacuum levels, not only in SVE wells, but also in the VMP's, reflects well on the status of the system operation to this point. The system will be operating under optimal vacuum conditions when all supplemental and engineered dilution is eliminated from the RTO intake. Due to high soil vapor concentrations, supplementary dilution air to the RTO unit has been required in order to maintain optimal operating temperatures and conditions within the RTO. In order to achieve optimal influence of the system vacuum, the dilution air must be eliminated. Currently, only the engineered manual dilution valve located above the system blower is in use. As the manual dilution air is eliminated from the system, both vacuum and radius of influence within the system area are expected to increase.

### Hydrocarbon Mass Removal

The total hydrocarbon mass of soil vapor removed by the SVE system was estimated by measuring the total hydrocarbon concentrations of the extracted soil vapors and the soil vapor flow rates into the SVE system. The results of the header and RTO exhaust analytical data can be found in **Table 11**. A flame ionization detector (FID) calibrated with methane was used to measure total hydrocarbon concentrations in samples collected from the West Fenceline Header and the Public Works Header. Total header hydrocarbon concentrations are included in **Appendix C**.

Total soil vapor flow rates were determined by calculating flow rates for the individual SVE legs that carry vapors from the SVE wells to the SVE system. Pressure, differential pressure, and temperature were measured in each leg. This data and Equation 2.7 and Equation 2.8 from USEPA Test Method 2 "Determination of Stack Gas Velocity and Volumetric Flow Rate (Type S Pitot Tube)" (Method 2) were used to calculate flow rates for each leg. The flow rates for the appropriate legs were summed to determine flow rates in the West Fenceline Header and the Public Works Header. Flow rates are included in **Appendix D**. Only flow rates and concentrations samples taken on the same day were used to calculate mass removal.

At times, supplemental ports added dilution air to the soil vapors flowing into RTO. The dilution value settings were documented for the periods during sample collection. In order to account for the dilution air's contribution to the flow in the header, dilution air measurements were obtained

for each dilution valve setting documented using the method described in the paragraph above. These dilution measurements were added to the appropriate header flow rates in order to estimate the total flow through the header during each concentration sampling event.

Hydrocarbon mass removed for the period between each concentration sample was calculated using the following equation:

$$M_{THC} = Q \times 60 \times \varphi \times \frac{M_c}{385.1 \times 10^6} \times h \div 2000$$

$Where$:

$M_{THC} = Hydrocarbon\ mass\ removed\ for\ the\ period\ (tons)$

$Q = Total\ header\ flowrate\ (SCFM)$

$\varphi = Total\ hydrocarbon\ concentration\ (ppmv)$

$M_C = Molecular\ weight\ of\ total\ hydrocarbons\ \left({}^{lb}/_{lb-mole}\right)$

$h = Period\ SVE\ operating\ hours\ (hours)$

$Unit\ conversions$:

$60\ minutes\ per\ hour$

$\frac{M_c}{385.1 \times 10^6}\ converts\ (ppmv) to\ \left({}^{lb}/_{SCF}\right)$

$2000\ pounds\ per\ tons$

Header samples from **Table 11** were used to estimate molecular weights for the west fence line and public works headers. These molecular weights from an average of the header samples in 1Q13 based on detected TO-15 analytes, 29.5 lb/lb-mole and 20.3 lb/lb-mole respectively, were used to convert header hydrocarbon volume concentrations (ppmv) to mass concentrations (lb/SCF). The conversion from volume concentration (ppmv) to mass concentrations (lb/SCF) was taken from the USEPA document *AP-42 Compilation of Air Pollutant Emission Factors, Volume 1: Stationary Point and Area Sources*, Fifth Edition, Appendix A (USEPA, 1995). The total hydrocarbon mass removed during each period was summed to determine the quarterly total hydrocarbon mass removed. The mass removed is summarized in the table below.

**Quarterly Total Hydrocarbon Mass Removed**

| | WRR West Fenceline Mass (tons) | Public Works Mass (tons)[6] | Quarterly Mass (tons) | Total Mass (tons) |
|---|---|---|---|---|
| 2Q12 | 183 | 53 | 237 | 237 |
| 3Q12 | 141 | 34 | 175 | 412 |
| 4Q12 | 78 | 33 | 110 | 522 |
| 1Q13 | 58 | 18 | 76 | 598 |

## 5.5 SVE SYSTEM MODIFICATION RECOMMENDATIONS

A key focus of the system operators is public and worker safety.. Operation of the SVE system will continue maintenance and system optimization activities. Future monitoring and sampling results from data points associated with the SVE system will be the primary driver of optimization efforts. Optimization efforts could include reduction in dilution air, valve adjustment of individual SVE wells and legs of the SVE system to direct more or less vacuum to areas.

[6] Public works mass is based on concentrations in the public works header, which contains vapors from the teal line including SVE-20 located in the WRR.

URS conducted the 1Q13 soil vapor sampling and SVE monitoring efforts on behalf of SOPUS in the Village, Roxana Public Works Yard, and adjoining portions of the WRR. The following conclusions are based on the data collected during 1Q13:

- Soil vapor samples were collected from 43 locations and 149 ports during 1Q13. The locations of higher soil vapor concentrations generally coincide with areas of the higher observed groundwater impact.
- Benzene concentrations within the Village range from parts per billion (ppb) in the shallow samples to tens of parts per million (ppm) in deeper samples. The proposed residential screening criterion was exceeded in at least one port at VMP-1, VMP-3, VMP-4, VMP-19, VMP-44, VMP-49, and VMP-50. Of these VMPs, only three shallow ports (<10 ft depth) exceeded the residential screening criterion, which include VMP-1-5, VMP-19-5, and VMP-44-10. As indicated earlier, data from the VMP-1 grab sample was judged not to be representative based on the integrity assessment conducted during 1Q13.
- Benzene concentrations within Roxana Public Works Yard and WRR range from ppb in the shallow samples to tens of thousands of ppm in deeper samples. The proposed commercial/industrial screening criterion was exceeded in at least one port at VMP-13, VMP-14, and VMP-25 within Roxana Public Works Yard and VMP-12 and VMP-16 within WRR.
- VMP-1 was replaced on March 6, 2013 due to loss of integrity, which was based on the vacuum pressure communication test conducted during 1Q13. VMP-47 will be replaced during 2Q13.
- As presented in detail above, the SVE system continues to operate efficiently and effectively.

Illinois Environmental Protection Agency (IEPA), 2009; (IEPA 2009); *Letter providing approval with comments and modifications of the SOPUS*, 2009B work plan. Issued to Shell Oil Products US (SOPUS), dated May 12, 2009.

Illinois Environmental Protection Agency (IEPA), 2010; (IEPA 2010); *Letter providing approval with comments the SOPUS 2010 Delineation Report*. Issued to Shell Oil Products US (SOPUS), dated August 5, 2010.

Illinois Environmental Protection Agency (IEPA), 2011; (IEPA, 2011); *Response to December 31, 2010 submittal*. Issued to Shell Oil Products US (SOPUS), dated March 16, 2011.

Illinois Environmental Protection Agency (IEPA), 2012; (IEPA, 2012); *Response to June 13, 2011; July 20, 2011; September 28, 2011, and May 31, 2012 submittals*. Issued to Shell Oil Products US (SOPUS), dated September 13, 2012.

Ririe, G. T., R. Sweeney, S. Daugherty, and P. Peuron. 1998. A Vapor Transport Model That is Consistent with Field and Laboratory Data. In: *Proceedings of the Petroleum Hydrocarbons and Organic Chemicals in Ground Water Conference*, American Petroleum Institute and the national Ground Water Association, Houston, TX.

URS Corporation (URS), 2010; (URS, 2010a); *Dissolved Phase Groundwater Investigation and P-60 Free Phase Product Delineation Report - Roxana, Illinois*; Prepared for Shell Oil Products US (SOPUS); dated February 2010.

URS Corporation (URS), 2010; (URS, 2010b); *Addendum to February 2010 Report - Supplemental Investigation Activities - Roxana, Illinois*; Prepared for Shell Oil Products US (SOPUS); dated September 20, 2010.

URS Corporation (URS), 2011; (URS, 2011a); *Soil Vapor Sampling – 1st Quarter 2011 - Roxana, Illinois*; Prepared for Shell Oil Products US (SOPUS); dated June 2011.

URS Corporation (URS), 2011; (URS, 2011b); *Conceptual/Final Design Report – Roxana, Illinois*; Prepared for Shell Oil Products US (SOPUS); dated June 2011.

URS Corporation (URS), 2012; (URS, 2012); *SVE System Construction Completion Report – Roxana, Illinois*; Prepared for Shell Oil Products US (SOPUS); dated May 2012.

URS Corporation (URS), 2013 (URS, 2013a); *Roxana / Route 111, WRR, and Rand Avenue Investigation and Remediation Health and Safety Plan*; Prepared for Shell Oil Products US (SOPUS); dated January 2013.

URS Corporation (URS), 2013; (URS, 2013b); *Interim Groundwater Monitoring Program – 1st Quarter 2013 - Roxana, Illinois*; Prepared for Shell Oil Products US (SOPUS); dated January 2013.

URS Corporation (URS), 2013; (URS, 2013c); *SVE System Construction Completion Report Addendum – Roxana, Illinois*; Prepared for Shell Oil Products US (SOPUS); dated February 2013.

US Environmental Protection Agency (USEPA), January 1995; (USEPA, 1995); *AP-42 Compilation of Air Pollutant Emission Factors, Volume 1: Stationary Point and Area Sources*, Fifth Edition,

US Environmental Protection Agency (USEPA), June 2008; (USEPA, 2008); *Contract Laboratory Program National Functional Guidelines for Superfund Organic Methods Data Review*.

SEE LAST PAGE OF TABLE FOR NOTES

**TABLE 1**
**CUMULATIVE GROUNDWATER MONITORING WELL GAUGING RESULTS**

| WELL ID | TOP OF CASING (elev.[1]) | DATE GAUGED | DEPTH TO PRODUCT (ft btoc) | DEPTH TO WATER (ft btoc) | WATER-PRODUCT INTERFACE (elev.[1]) | PRODUCT (elev.[1]) | PRODUCT THICKNESS (ft) | CORRECTED WATER LEVEL[2] (elev.[1]) | SCREENED INTERVAL (elev.[1]) (ft btoc) | COMMENTS |
|---|---|---|---|---|---|---|---|---|---|---|
| **MW-01** | | | | | | | | | | |
| 4Q10 | 442.86 | 11/12/2010 | NE | 36.91 | NA | NA | NA | 405.95 | 399.45 - 384.45 (43.41 - 58.41) | * |
| 1Q11 | 442.86 | 1/13/2011 | NE | 37.58 | NA | NA | NA | 405.28 | | * |
| 2Q11 | 442.86 | 4/25/2011 | NE | 38.38 | NA | NA | NA | 404.48 | | * |
| 3Q11 | 442.86 | 7/5/2011 | NE | 35.77 | NA | NA | NA | 407.09 | | * |
| | 442.86 | 9/19/2011 | NE | 35.15 | NA | NA | NA | 407.71 | | * |
| 4Q11 | 442.86 | 10/5/2011 | NE | 35.48 | NA | NA | NA | 407.38 | | * |
| 1Q12 | 442.65 | 1/3/2012 | NE | 37.65 | NA | NA | NA | 405.00 | 392.67 - 382.67 (49.98 - 59.98) | *1" Piezometer replaced with a 2" groundwater monitoring well |
| 2Q12 | 442.65 | 4/2/2012 | NE | 38.85 | NA | NA | NA | 403.80 | | * |
| 3Q12 | 442.65 | 7/2/2012 | NE | 39.12 | NA | NA | NA | 403.53 | | * |
| 4Q12 | 442.65 | 10/1/2012 | NE | 40.92 | NA | NA | NA | 401.73 | | * |
| 1Q13 | 442.65 | 1/3/2013 | NE | 41.95 | NA | NA | NA | 400.70 | | * |
| **MW-02** | | | | | | | | | | |
| 4Q10 | 443.93 | 11/12/2010 | NE | 38.12 | NA | NA | NA | 405.81 | 396.74 - 381.74 (47.19 - 62.19) | * |
| 1Q11 | 443.93 | 1/13/2011 | NE | 38.67 | NA | NA | NA | 405.26 | | * |
| 2Q11 | 443.93 | 4/25/2011 | NE | 39.61 | NA | NA | NA | 404.32 | | * |
| 3Q11 | 443.93 | 7/5/2011 | NE | 37.04 | NA | NA | NA | 406.89 | | * |
| | 443.93 | 9/19/2011 | NE | 36.36 | NA | NA | NA | 407.57 | | * |
| 4Q11 | 443.93 | 10/5/2011 | NE | 36.65 | NA | NA | NA | 407.28 | | * |
| 1Q12 | 443.77 | 1/3/2012 | NE | 38.88 | NA | NA | NA | 404.89 | 392.45 - 382.45 (51.32 - 61.32) | *1" Piezometer replaced with a 2" groundwater monitoring well |
| 2Q12 | 443.77 | 4/2/2012 | NE | 40.04 | NA | NA | NA | 403.73 | | * |
| 3Q12 | 443.77 | 7/2/2012 | NE | 40.32 | NA | NA | NA | 403.45 | | * |
| 4Q12 | 443.77 | 10/1/2012 | NE | 42.10 | NA | NA | NA | 401.67 | | * |
| 1Q13 | 443.77 | 1/3/2013 | NE | 43.10 | NA | NA | NA | 400.67 | | * |
| **MW-03** | | | | | | | | | | |
| 4Q10 | 430.36 | 11/12/2010 | NE | 24.05 | NA | NA | NA | 406.31 | 399.38 - 384.38 (30.98 - 45.98) | * |
| 1Q11 | 430.36 | 1/13/2011 | NE | 24.92 | NA | NA | NA | 405.44 | | * |
| 2Q11 | 430.36 | 4/25/2011 | NE | 25.42 | NA | NA | NA | 404.94 | | * |
| 3Q11 | 430.36 | 7/5/2011 | NE | 22.72 | NA | NA | NA | 407.64 | | * |
| | 430.36 | 9/19/2011 | NE | 22.40 | NA | NA | NA | 407.96 | | * |
| 4Q11 | 430.36 | 10/5/2011 | NE | 22.76 | NA | NA | NA | 407.60 | | * |
| 1Q12 | 430.08 | 1/3/2012 | NE | 24.84 | NA | NA | NA | 405.24 | 395.41 - 385.41 (34.67 - 44.67) | *1" Piezometer replaced with a 2" groundwater monitoring well |
| 2Q12 | 430.08 | 4/2/2012 | NE | 26.04 | NA | NA | NA | 404.04 | | * |
| 3Q12 | 430.08 | 7/2/2012 | NE | 26.30 | NA | NA | NA | 403.78 | | * |
| 4Q12 | 430.08 | 10/1/2012 | NE | 28.13 | NA | NA | NA | 401.95 | | * |
| 1Q13 | 430.08 | 1/3/2013 | NE | 29.22 | NA | NA | NA | 400.86 | | * |
| **MW-04** | | | | | | | | | | |
| 4Q10 | 441.58 | 11/12/2010 | NE | 35.38 | NA | NA | NA | 406.20 | 398.95 - 383.95 (42.63 - 57.63) | * |
| 1Q11 | 441.58 | 1/13/2011 | NE | 36.04 | NA | NA | NA | 405.54 | | * |
| 2Q11 | 441.58 | 4/25/2011 | NE | 36.74 | NA | NA | NA | 404.84 | | * |
| 3Q11 | 441.58 | 7/5/2011 | NE | 34.15 | NA | NA | NA | 407.43 | | * |
| | 441.58 | 9/19/2011 | NE | 33.65 | NA | NA | NA | 407.93 | | * |
| 4Q11 | 441.58 | 10/5/2011 | NE | 33.99 | NA | NA | NA | 407.59 | | * |
| 1Q12 | 441.14 | 1/3/2012 | NE | 35.97 | NA | NA | NA | 405.17 | 395.08 - 385.08 (46.06 - 56.06) | *1" Piezometer replaced with a 2" groundwater monitoring well |
| 2Q12 | 441.14 | 4/2/2012 | NE | 37.11 | NA | NA | NA | 404.03 | | * |
| 3Q12 | 441.14 | 7/2/2012 | NE | 37.43 | NA | NA | NA | 403.71 | | * |
| 4Q12 | 441.14 | 10/1/2012 | NE | 39.27 | NA | NA | NA | 401.87 | | * |
| 1Q13 | 441.14 | 1/3/2013 | NE | 40.27 | NA | NA | NA | 400.87 | | * |
| **MW-05** | | | | | | | | | | |
| 4Q10 | 429.73 | 11/12/2010 | NE | 23.32 | NA | NA | NA | 406.41 | 398.60 - 383.60 (31.13 - 46.13) | * |
| 1Q11 | 429.73 | 1/13/2011 | NE | 24.15 | NA | NA | NA | 405.58 | | * |
| 2Q11 | 429.73 | 4/25/2011 | NE | 24.65 | NA | NA | NA | 405.08 | | * |
| 3Q11 | 429.73 | 7/5/2011 | NE | 22.00 | NA | NA | NA | 407.73 | | * |
| | 429.73 | 9/19/2011 | NE | 21.72 | NA | NA | NA | 408.01 | | * |
| 4Q11 | 429.73 | 10/5/2011 | NE | 22.06 | NA | NA | NA | 407.67 | | * |
| 1Q12 | 429.80 | 1/3/2012 | NE | 24.45 | NA | NA | NA | 405.35 | 395.83 - 385.83 (33.97 - 43.97) | *1" Piezometer replaced with a 2" groundwater monitoring well |
| 2Q12 | 429.80 | 4/2/2012 | NE | 25.65 | NA | NA | NA | 404.15 | | * |
| 3Q12 | 429.80 | 7/2/2012 | NE | 25.91 | NA | NA | NA | 403.89 | | * |
| 4Q12 | 429.80 | 10/1/2012 | NE | 27.80 | NA | NA | NA | 402.00 | | * |
| 1Q13 | 429.80 | 1/3/2013 | NE | 28.86 | NA | NA | NA | 400.94 | | * |
| **MW-06A** | | | | | | | | | | |
| 4Q10 | 432.42 | 11/12/2010 | NE | 25.62 | NA | NA | NA | 406.80 | 400.44 - 385.44 (31.98 - 46.98) | * |
| 1Q11 | 432.42 | 1/13/2011 | NE | 26.36 | NA | NA | NA | 406.06 | | * |
| 2Q11 | 432.42 | 4/25/2011 | NE | 26.78 | NA | NA | NA | 405.64 | | * |
| 3Q11 | 432.42 | 7/5/2011 | NE | 24.21 | NA | NA | NA | 408.21 | | * |
| | 432.42 | 9/19/2011 | NE | 24.07 | NA | NA | NA | 408.35 | | * |
| 4Q11 | 432.42 | 10/5/2011 | NE | 24.44 | NA | NA | NA | 407.98 | | * |
| 1Q12 | 432.14 | 1/3/2012 | NE | 26.34 | NA | NA | NA | 405.80 | 397.31 - 387.31 (34.83 - 44.83) | *1" Piezometer replaced with a 2" groundwater monitoring well |
| 2Q12 | 432.14 | 4/2/2012 | NE | 27.57 | NA | NA | NA | 404.57 | | * |
| 3Q12 | 432.14 | 7/2/2012 | NE | 27.88 | NA | NA | NA | 404.26 | | * |
| 4Q12 | 432.14 | 10/1/2012 | NE | 28.81 | NA | NA | NA | 403.33 | | * |
| 1Q13 | 432.14 | 1/3/2013 | NE | 30.80 | NA | NA | NA | 401.34 | | * |

**TABLE 1**
**CUMULATIVE GROUNDWATER MONITORING WELL GAUGING RESULTS**

| WELL ID | TOP OF CASING (elev.[1]) | DATE GAUGED | DEPTH TO PRODUCT (ft btoc) | DEPTH TO WATER (ft btoc) | WATER-PRODUCT INTERFACE (elev.[1]) | PRODUCT (elev.[1]) | PRODUCT THICKNESS (ft) | CORRECTED WATER LEVEL[2] (elev.[1]) | SCREENED INTERVAL (elev.[1]) (ft btoc) | COMMENTS |
|---|---|---|---|---|---|---|---|---|---|---|
| **MW-06B** | | | | | | | | | | |
| 4Q10 | 432.29 | 11/12/2010 | NE | 25.47 | NA | NA | NA | 406.82 | 368.24 - 363.24 (64.05 - 69.05) | * |
| 1Q11 | 432.29 | 1/13/2011 | NE | 26.21 | NA | NA | NA | 406.08 | | * |
| 2Q11 | 432.29 | 4/25/2011 | NE | 26.65 | NA | NA | NA | 405.64 | | * |
| 3Q11 | 432.29 | 7/5/2011 | NE | 24.08 | NA | NA | NA | 408.21 | | * |
| 4Q11 | 432.29 | 10/5/2011 | NE | 24.28 | NA | NA | NA | 408.01 | | * |
| 1Q12 | 432.29 | 1/3/2012 | NE | 26.40 | NA | NA | NA | 405.89 | | * |
| 2Q12 | 432.29 | 4/2/2012 | NE | 27.61 | NA | NA | NA | 404.68 | | * |
| 3Q12 | 432.29 | 7/2/2012 | NE | 27.92 | NA | NA | NA | 404.37 | | * |
| 4Q12 | 432.29 | 10/1/2012 | NE | 29.86 | NA | NA | NA | 402.43 | | * |
| 1Q13 | 432.29 | 1/3/2013 | NE | 30.87 | NA | NA | NA | 401.42 | | * |
| **MW-06C** | | | | | | | | | | |
| 4Q10 | 432.11 | 11/12/2010 | NE | 25.25 | NA | NA | NA | 406.86 | 347.16 - 342.16 (84.95 - 89.95) | * |
| 1Q11 | 432.11 | 1/13/2011 | NE | 25.97 | NA | NA | NA | 406.14 | | * |
| 2Q11 | 432.11 | 4/25/2011 | NE | 26.73 | NA | NA | NA | 405.38 | | * |
| 3Q11 | 432.11 | 7/5/2011 | NE | 23.80 | NA | NA | NA | 408.31 | | * |
| 4Q11 | 432.11 | 10/5/2011 | NE | 24.03 | NA | NA | NA | 408.08 | | * |
| 1Q12 | 432.11 | 1/3/2012 | NE | 26.17 | NA | NA | NA | 405.94 | | * |
| 2Q12 | 432.11 | 4/2/2012 | NE | 27.40 | NA | NA | NA | 404.71 | | * |
| 3Q12 | 432.11 | 7/2/2012 | NE | 27.71 | NA | NA | NA | 404.40 | | * |
| 4Q12 | 432.11 | 10/1/2012 | NE | 29.70 | NA | NA | NA | 402.41 | | * |
| 1Q13 | 432.11 | 1/3/2013 | NE | 30.65 | NA | NA | NA | 401.46 | | * |
| **MW-06D** | | | | | | | | | | |
| 4Q10 | 431.99 | 11/12/2010 | NE | 25.13 | NA | NA | NA | 406.86 | 327.27 - 322.27 (104.72 - 109.72) | * |
| 1Q11 | 431.99 | 1/13/2011 | NE | 25.87 | NA | NA | NA | 406.12 | | * |
| 2Q11 | 431.99 | 4/25/2011 | NE | 26.30 | NA | NA | NA | 405.69 | | * |
| 3Q11 | 431.99 | 7/5/2011 | NE | 23.67 | NA | NA | NA | 408.32 | | * |
| 4Q11 | 431.99 | 10/5/2011 | NE | 23.95 | NA | NA | NA | 408.04 | | * |
| 1Q12 | 431.99 | 1/3/2012 | NE | 26.05 | NA | NA | NA | 405.94 | | * |
| 2Q12 | 431.99 | 4/2/2012 | NE | 27.46 | NA | NA | NA | 404.53 | | * |
| 3Q12 | 431.99 | 7/2/2012 | NE | 27.58 | NA | NA | NA | 404.41 | | * |
| 4Q12 | 431.99 | 10/1/2012 | NE | 29.51 | NA | NA | NA | 402.48 | | * |
| 1Q13 | 431.99 | 1/3/2013 | NE | 30.51 | NA | NA | NA | 401.48 | | * |
| **MW-07** | | | | | | | | | | |
| 4Q10 | 443.10 | 11/12/2010 | NE | 36.93 | NA | NA | NA | 406.17 | 400.18 - 390.18 (42.92 - 52.92) | * |
| 1Q11 | 443.10 | 1/13/2011 | NE | 37.52 | NA | NA | NA | 405.58 | | * |
| 2Q11 | 443.10 | 4/25/2011 | NE | 38.18 | NA | NA | NA | 404.92 | | * |
| 3Q11 | 443.10 | 7/5/2011 | NE | 35.65 | NA | NA | NA | 407.45 | | * |
| | 443.10 | 9/19/2011 | NE | 35.22 | NA | NA | NA | 407.88 | | * |
| 4Q11 | 443.10 | 10/5/2011 | NE | 25.52 | NA | NA | NA | 417.58 | | * |
| 1Q12 | 443.10 | 1/3/2012 | NE | 37.79 | NA | NA | NA | 405.31 | | * |
| 2Q12 | 443.10 | 4/2/2012 | NE | 38.91 | NA | NA | NA | 404.19 | | * |
| 3Q12 | 443.10 | 7/2/2012 | NE | 39.23 | NA | NA | NA | 403.87 | | * |
| 4Q12 | 443.10 | 10/1/2012 | NE | 41.10 | NA | NA | NA | 402.00 | | * |
| 1Q13 | 443.10 | 1/3/2013 | NE | 42.10 | NA | NA | NA | 401.00 | | * |
| **MW-08** | | | | | | | | | | |
| 4Q10 | 434.11 | 11/12/2010 | NE | 27.84 | NA | NA | NA | 406.27 | 400.51 - 390.51 (33.60 - 43.60) | * |
| 1Q11 | 434.11 | 1/13/2011 | NE | 28.59 | NA | NA | NA | 405.52 | | * |
| 2Q11 | 434.11 | 4/25/2011 | NE | 29.15 | NA | NA | NA | 404.96 | | * |
| 3Q11 | 434.11 | 7/5/2011 | NE | 26.55 | NA | NA | NA | 407.56 | | * |
| 4Q11 | 434.11 | 10/5/2011 | NE | 26.57 | NA | NA | NA | 407.54 | | * |
| 1Q12 | 434.11 | 1/3/2012 | NE | 28.84 | NA | NA | NA | 405.27 | | * |
| 2Q12 | 434.11 | 4/2/2012 | NE | 30.01 | NA | NA | NA | 404.10 | | * |
| 3Q12 | 434.11 | 7/2/2012 | NE | 30.29 | NA | NA | NA | 403.82 | | * |
| 4Q12 | 434.11 | 10/1/2012 | NE | 32.17 | NA | NA | NA | 401.94 | | * |
| 1Q13 | 434.11 | 1/3/2013 | NE | 33.21 | NA | NA | NA | 400.90 | | * |
| **MW-09** | | | | | | | | | | |
| 4Q10 | 445.20 | 11/12/2010 | NE | 39.00 | NA | NA | NA | 406.20 | 398.75 - 388.75 (46.45 - 56.45) | * |
| 1Q11 | 445.20 | 1/13/2011 | NE | 39.62 | NA | NA | NA | 405.58 | | * |
| 2Q11 | 445.20 | 4/25/2011 | NE | NM | NA | NA | NA | NA | | Area flooded; unable to access to well |
| 3Q11 | 445.20 | 7/5/2011 | NE | 38.06 | NA | NA | NA | 407.14 | | * |
| | 445.20 | 9/19/2011 | NE | 37.27 | NA | NA | NA | 407.93 | | * |
| 4Q11 | 445.20 | 10/5/2011 | NE | 37.56 | NA | NA | NA | 407.64 | | * |
| 1Q12 | 445.20 | 1/3/2012 | NE | 39.50 | NA | NA | NA | 405.70 | | * |
| 2Q12 | 445.20 | 4/2/2012 | NE | 40.77 | NA | NA | NA | 404.43 | | * |
| 3Q12 | 445.20 | 7/2/2012 | NE | 40.07 | NA | NA | NA | 405.13 | | * |
| 4Q12 | 445.20 | 10/1/2012 | NE | 42.75 | NA | NA | NA | 402.45 | | * |
| 1Q13 | 445.20 | 1/2/2013 | NE | 43.92 | NA | NA | NA | 401.28 | | * |
| **MW-10** | | | | | | | | | | |
| 4Q10 | 445.03 | 11/12/2010 | NE | 38.97 | NA | NA | NA | 406.06 | 400.60 - 390.60 (44.43 - 54.43) | * |
| 1Q11 | 445.03 | 1/13/2011 | NE | 39.40 | NA | NA | NA | 405.63 | | * |
| 2Q11 | 445.03 | 4/25/2011 | NE | 40.26 | NA | NA | NA | 404.77 | | * |
| 3Q11 | 445.03 | 7/5/2011 | NE | 38.01 | NA | NA | NA | 407.02 | | * |
| | 445.03 | 9/19/2011 | NE | 37.24 | NA | NA | NA | 407.79 | | * |
| 4Q11 | 445.03 | 10/5/2011 | NE | 37.47 | NA | NA | NA | 407.56 | | * |
| 1Q12 | 445.03 | 1/3/2012 | NE | 39.39 | NA | NA | NA | 405.64 | | * |
| 2Q12 | 445.03 | 4/2/2012 | NE | 40.58 | NA | NA | NA | 404.45 | | * |
| 3Q12 | 445.03 | 7/2/2012 | NE | 40.92 | NA | NA | NA | 404.11 | | * |
| 4Q12 | 445.03 | 10/1/2012 | NE | 42.69 | NA | NA | NA | 402.34 | | * |
| 1Q13 | 445.03 | 1/2/2013 | NE | 43.81 | NA | NA | NA | 401.22 | | * |

SEE LAST PAGE OF TABLE FOR NOTES

**TABLE 1**
**CUMULATIVE GROUNDWATER MONITORING WELL GAUGING RESULTS**

| WELL ID | TOP OF CASING (elev.[1]) | DATE GAUGED | DEPTH TO PRODUCT (ft btoc) | DEPTH TO WATER (ft btoc) | WATER-PRODUCT INTERFACE (elev.[1]) | PRODUCT (elev.[1]) | PRODUCT THICKNESS (ft) | CORRECTED WATER LEVEL[2] (elev.[1]) | SCREENED INTERVAL (elev.[1]) (ft btoc) | COMMENTS |
|---|---|---|---|---|---|---|---|---|---|---|
| **MW-11** | | | | | | | | | | |
| 4Q10 | 442.33 | 11/12/2010 | NE | 36.39 | NA | NA | NA | 405.94 | 400.67 - 390.67 (41.66 - 51.66) | * |
| 1Q11 | 442.33 | 1/13/2011 | NE | 37.15 | NA | NA | NA | 405.18 | | * |
| 2Q11 | 442.33 | 4/25/2011 | NE | 38.00 | NA | NA | NA | 404.33 | | * |
| 3Q11 | 442.33 | 7/5/2011 | NE | 35.46 | NA | NA | NA | 406.87 | | * |
| | 442.33 | 9/19/2011 | NE | 34.68 | NA | NA | NA | 407.65 | | * |
| 4Q11 | 442.33 | 10/5/2011 | NE | 34.07 | NA | NA | NA | 408.26 | | * |
| 1Q12 | 442.33 | 1/3/2012 | NE | 37.21 | NA | NA | NA | 405.12 | | * |
| 2Q12 | 442.33 | 4/2/2012 | NE | 38.44 | NA | NA | NA | 403.89 | | * |
| 3Q12 | 442.33 | 7/2/2012 | NE | 38.68 | NA | NA | NA | 403.65 | | * |
| 4Q12 | 442.33 | 10/1/2012 | NE | 40.42 | NA | NA | NA | 401.91 | | * |
| 1Q13 | 442.33 | 1/2/2013 | NE | 41.49 | NA | NA | NA | 400.84 | | * |
| **MW-12** | | | | | | | | | | |
| 4Q10 | 442.60 | 11/12/2010 | NE | 36.63 | NA | NA | NA | 405.97 | 400.68 - 390.68 (41.92 - 51.92) | * |
| 1Q11 | 442.60 | 1/13/2011 | NE | 37.42 | NA | NA | NA | 405.18 | | * |
| 2Q11 | 442.60 | 4/25/2011 | NE | 38.20 | NA | NA | NA | 404.40 | | * |
| 3Q11 | 442.60 | 7/5/2011 | NE | 35.55 | NA | NA | NA | 407.05 | | * |
| | 442.60 | 9/19/2011 | NE | 34.88 | NA | NA | NA | 407.72 | | * |
| 4Q11 | 442.60 | 10/5/2011 | NE | 35.20 | NA | NA | NA | 407.40 | | * |
| 1Q12 | 442.60 | 1/3/2012 | NE | 37.57 | NA | NA | NA | 405.03 | | * |
| 2Q12 | 442.60 | 4/2/2012 | NE | 38.75 | NA | NA | NA | 403.85 | | * |
| 3Q12 | 442.60 | 7/2/2012 | NE | 39.01 | NA | NA | NA | 403.59 | | * |
| 4Q12 | 442.60 | 10/1/2012 | NE | 40.78 | NA | NA | NA | 401.82 | | * |
| 1Q13 | 442.60 | 1/3/2013 | NE | 41.86 | NA | NA | NA | 400.74 | | * |
| **MW-13** | | | | | | | | | | |
| 1Q11 | 430.27 | 1/13/2011 | NE | 24.28 | NA | NA | NA | 405.99 | 404.70 - 394.70 (25.57 - 35.57) | * |
| 2Q11 | 430.27 | 4/25/2011 | NE | 24.47 | NA | NA | NA | 405.80 | | * |
| 3Q11 | 430.27 | 7/5/2011 | NE | 21.67 | NA | NA | NA | 408.60 | | * |
| | 430.27 | 9/19/2011 | NE | 21.88 | NA | NA | NA | 408.39 | | * |
| 4Q11 | 430.27 | 10/6/2011 | NE | 21.20 | NA | NA | NA | 409.07 | | * |
| 1Q12 | 430.27 | 1/3/2012 | NE | 24.35 | NA | NA | NA | 405.92 | | * |
| 2Q12 | 430.27 | 4/2/2012 | NE | 25.48 | NA | NA | NA | 404.79 | | * |
| 3Q12 | 430.27 | 7/3/2012 | NE | 25.95 | NA | NA | NA | 404.32 | | |
| 4Q12 | 430.27 | 10/1/2012 | NE | 40.44 | NA | NA | NA | 389.83 | | |
| | 430.27 | 10/2/2012 | NE | 27.99 | NA | NA | NA | 402.28 | | |
| 1Q13 | 430.27 | 1/7/2013 | NE | 29.07 | NA | NA | NA | 401.20 | | |
| **MW-14** | | | | | | | | | | |
| 1Q12 | 434.44 | 1/3/2012 | NM | NM | NA | NA | NA | NA | 401.02 - 391.02 (33.42 - 43.42) | Restricted Area |
| 2Q12 | 434.44 | 4/2/2012 | NM | NM | NA | NA | NA | NA | | Restricted Area |
| 3Q12 | 434.44 | 7/5/2012 | NE | 29.87 | NA | NA | NA | 404.57 | | * |
| 4Q12 | 434.44 | 10/2/2012 | NE | 31.86 | NA | NA | NA | 402.58 | | * |
| 1Q13 | 434.44 | 1/7/2013 | NE | 32.71 | NA | NA | NA | 401.73 | | * |
| **MW-16** | | | | | | | | | | |
| 1Q13 | 443.39 | 1/23/2013 | NE | 43.05 | NA | NA | NA | 400.34 | 406.33 - 396.33 (37.43 - 47.43) | Installed during 4Q12 |
| **MW-17** | | | | | | | | | | |
| 1Q13 | 441.57 | 2/11/2013 | NE | 41.75 | NA | NA | NA | 399.82 | 407.28 - 392.28 (34.55 - 49.55) | Installed during 4Q12 |
| **MW-18** | | | | | | | | | | |
| 1Q13 | 442.04 | 2/11/2013 | NE | 42.25 | NA | NA | NA | 399.79 | 407.12 - 392.12 (35.25 - 50.25) | Installed during 4Q12 |
| **MW-19** | | | | | | | | | | |
| 1Q13 | 442.77 | 2/11/2013 | NE | 42.88 | NA | NA | NA | 399.89 | 406.43 - 391.43 (36.70 - 51.70) | Installed during 4Q12 |
| **MW-20** | | | | | | | | | | |
| 1Q13 | 443.67 | 2/11/2013 | NE | 43.66 | NA | NA | NA | 400.01 | 407.79 - 392.79 (36.23 - 51.23) | Installed during 4Q12 |
| **MW-21** | | | | | | | | | | |
| 1Q13 | 443.81 | 2/11/2013 | NE | 43.53 | NA | NA | NA | 400.28 | 408.80 - 393.80 (35.30 - 50.30) | Installed during 4Q12 |
| **MW-22** | | | | | | | | | | |
| 1Q13 | 442.16 | 1/23/2013 | NE | 41.80 | NA | NA | NA | 400.36 | 404.28 - 394.28 (38.21 - 48.21) | Installed during 4Q12 |
| **P-01** | | | | | | | | | | |
| 2Q10 | 442.56 | 4/1/2010 | NE | 30.11 | NA | NA | NA | 412.45 | 380.61 - 375.61 (61.95 - 66.95) | * |
| 3Q10 | 442.56 | 7/1/2010 | NE | 29.49 | NA | NA | NA | 413.07 | | * |
| 4Q10 | 442.56 | 10/1/2010 | NE | 27.86 | NA | NA | NA | 414.70 | | * |
| 1Q11 | 442.56 | 1/1/2011 | NE | 28.52 | NA | NA | NA | 414.04 | | * |
| 2Q11 | 442.56 | 4/1/2011 | NE | 27.30 | NA | NA | NA | 415.26 | | * |
| 3Q11 | 442.56 | 7/5/2011 | NE | 25.51 | NA | NA | NA | 417.05 | | * |
| | 442.56 | 9/19/2011 | NE | 27.75 | NA | NA | NA | 414.81 | | * |
| 4Q11 | 442.56 | 10/6/2011 | NE | 28.15 | NA | NA | NA | 414.41 | | * |
| 1Q12 | 442.56 | 1/3/2012 | NE | 28.93 | NA | NA | NA | 413.63 | | * |
| 2Q12 | 442.56 | 4/2/2012 | NE | 29.38 | NA | NA | NA | 413.18 | | * |
| 3Q12 | 442.56 | 7/2/2012 | NE | 30.60 | NA | NA | NA | 411.96 | | * |
| 4Q12 | 442.56 | 10/1/2012 | NE | 32.35 | NA | NA | NA | 410.21 | | * |
| 1Q13 | 442.56 | 1/3/2013 | NE | 33.96 | NA | NA | NA | 408.60 | | * |

**TABLE 1**
**CUMULATIVE GROUNDWATER MONITORING WELL GAUGING RESULTS**

| WELL ID | TOP OF CASING (elev.[1]) | DATE GAUGED | DEPTH TO PRODUCT (ft btoc) | DEPTH TO WATER (ft btoc) | WATER-PRODUCT INTERFACE (elev.[1]) | PRODUCT (elev.[1]) | PRODUCT THICKNESS (ft) | CORRECTED WATER LEVEL[2] (elev.[1]) | SCREENED INTERVAL (elev.[1]) (ft btoc) | COMMENTS |
|---|---|---|---|---|---|---|---|---|---|---|
| **P-4U** | | | | | | | | | | |
| 2Q10 | 442.50 | 4/1/2010 | NE | 32.06 | NA | NA | NA | 410.44 | 361.35 - 359.35 (81.15 - 83.15) | * |
| 3Q10 | 442.50 | 7/1/2010 | NE | 31.00 | NA | NA | NA | 411.50 | | * |
| 4Q10 | 442.50 | 10/1/2010 | NE | 29.68 | NA | NA | NA | 412.82 | | * |
| 1Q11 | 442.50 | 1/1/2011 | NE | 29.81 | NA | NA | NA | 412.69 | | * |
| 2Q11 | 442.50 | 4/1/2011 | NE | 29.10 | NA | NA | NA | 413.40 | | * |
| 3Q11 | 442.50 | 7/5/2011 | NE | 27.02 | NA | NA | NA | 415.48 | | * |
| | 442.50 | 9/19/2011 | NE | 28.71 | NA | NA | NA | 413.79 | | * |
| 4Q11 | 442.50 | 10/6/2011 | NE | 29.17 | NA | NA | NA | 413.33 | | * |
| 1Q12 | 442.50 | 1/3/2012 | NE | 40.32 | NA | NA | NA | 402.18 | | * |
| 2Q12 | 442.50 | 4/2/2012 | NE | 30.80 | NA | NA | NA | 411.70 | | * |
| 3Q12 | 442.50 | 7/2/2012 | NE | 31.70 | NA | NA | NA | 410.80 | | * |
| 4Q12 | 442.50 | 10/1/2012 | NE | 33.65 | NA | NA | NA | 408.85 | | * |
| 1Q13 | 442.50 | 1/3/2013 | NE | 35.10 | NA | NA | NA | 407.40 | | * |
| **P-5L** | | | | | | | | | | |
| 2Q10 | 443.79 | 4/1/2010 | NE | 32.79 | NA | NA | NA | 411.00 | 301.89 - 299.89 (141.90 - 143.90) | * |
| 3Q10 | 443.79 | 7/1/2010 | NE | 30.30 | NA | NA | NA | 413.49 | | * |
| 4Q10 | 443.79 | 10/1/2010 | NE | 29.21 | NA | NA | NA | 414.58 | | * |
| 1Q11 | 443.79 | 1/1/2011 | NE | 29.55 | NA | NA | NA | 414.24 | | * |
| 2Q11 | 443.79 | 4/1/2011 | NE | 28.10 | NA | NA | NA | 415.69 | | * |
| 3Q11 | 443.79 | 7/5/2011 | NE | 25.87 | NA | NA | NA | 417.92 | | * |
| | 443.79 | 9/19/2011 | NE | 28.47 | NA | NA | NA | 415.32 | | * |
| 4Q11 | 443.79 | 10/6/2011 | NE | 29.16 | NA | NA | NA | 414.63 | | * |
| 1Q12 | 443.79 | 1/3/2012 | NE | 30.42 | NA | NA | NA | 413.37 | | * |
| 2Q12 | 443.79 | 4/2/2012 | NE | 30.56 | NA | NA | NA | 413.23 | | * |
| 3Q12 | 443.79 | 7/2/2012 | NE | 31.60 | NA | NA | NA | 412.19 | | * |
| 4Q12 | 443.79 | 10/1/2012 | NE | 33.60 | NA | NA | NA | 410.19 | | * |
| 1Q13 | 443.79 | 1/3/2013 | NE | 35.17 | NA | NA | NA | 408.62 | | * |
| **P-5U** | | | | | | | | | | |
| 2Q10 | 444.15 | 4/1/2010 | NE | 30.97 | NA | NA | NA | 413.18 | 313.52 - 311.52 (130.63 - 132.63) | * |
| 3Q10 | 444.15 | 7/1/2010 | NE | 31.95 | NA | NA | NA | 412.20 | | * |
| 4Q10 | 444.15 | 10/1/2010 | NE | 30.82 | NA | NA | NA | 413.33 | | * |
| 1Q11 | 444.15 | 1/1/2011 | NE | 30.96 | NA | NA | NA | 413.19 | | * |
| 2Q11 | 444.15 | 4/1/2011 | NE | 29.91 | NA | NA | NA | 414.24 | | * |
| 3Q11 | 444.15 | 7/5/2011 | NE | 27.80 | NA | NA | NA | 416.35 | | * |
| | 444.15 | 9/19/2011 | NE | 29.84 | NA | NA | NA | 414.31 | | * |
| 4Q11 | 444.15 | 10/6/2011 | NE | 30.41 | NA | NA | NA | 413.74 | | * |
| 1Q12 | 444.15 | 1/3/2012 | NE | 30.42 | NA | NA | NA | 413.73 | | * |
| 2Q12 | 444.15 | 4/2/2012 | NE | 31.96 | NA | NA | NA | 412.19 | | * |
| 3Q12 | 444.15 | 7/2/2012 | NE | 32.80 | NA | NA | NA | 411.35 | | * |
| 4Q12 | 444.15 | 10/1/2012 | NE | 35.00 | NA | NA | NA | 409.15 | | * |
| 1Q13 | 444.15 | 1/3/2013 | NE | 36.41 | NA | NA | NA | 407.74 | | * |
| **P-6L** | | | | | | | | | | |
| 4Q11 | 443.20 | 10/6/2011 | NE | 28.92 | NA | NA | NA | 414.28 | Unknown | |
| 1Q12 | 443.20 | 1/3/2012 | NE | 30.21 | NA | NA | NA | 412.99 | | |
| 2Q12 | 443.20 | 4/2/2012 | NE | 30.38 | NA | NA | NA | 412.82 | | |
| 3Q12 | 443.20 | 7/2/2012 | NE | 31.18 | NA | NA | NA | 412.02 | | * |
| 4Q12 | 443.20 | 10/1/2012 | NE | 33.45 | NA | NA | NA | 409.75 | | * |
| 1Q13 | 443.20 | 1/3/2013 | NE | 35.00 | NA | NA | NA | 408.20 | | * |
| **P-6U** | | | | | | | | | | |
| 2Q10 | 443.35 | 4/1/2010 | NE | 32.49 | NA | NA | NA | 410.86 | 362.85 - 360.85 (80.50 - 82.50) | * |
| 3Q10 | 443.35 | 7/1/2010 | NE | 31.43 | NA | NA | NA | 411.92 | | * |
| 4Q10 | 443.35 | 10/1/2010 | NE | 30.33 | NA | NA | NA | 413.02 | | * |
| 1Q11 | 443.35 | 1/1/2011 | NE | 30.53 | NA | NA | NA | 412.82 | | * |
| 2Q11 | 443.35 | 4/1/2011 | NE | 29.57 | NA | NA | NA | 413.78 | | * |
| 3Q11 | 443.35 | 7/5/2011 | NE | 27.35 | NA | NA | NA | 416.00 | | * |
| | 443.35 | 9/19/2011 | NE | 29.26 | NA | NA | NA | 414.09 | | * |
| 4Q11 | 443.35 | 10/6/2011 | NE | 29.78 | NA | NA | NA | 413.57 | | * |
| 1Q12 | 443.35 | 1/3/2012 | NE | 30.97 | NA | NA | NA | 412.38 | | * |
| 2Q12 | 443.35 | 4/2/2012 | NE | 31.42 | NA | NA | NA | 411.93 | | * |
| 3Q12 | 443.35 | 7/2/2012 | NE | 32.25 | NA | NA | NA | 411.10 | | * |
| 4Q12 | 443.35 | 10/1/2012 | NE | 30.40 | NA | NA | NA | 412.95 | | * |
| 1Q13 | 443.35 | 1/3/2013 | NE | 35.86 | NA | NA | NA | 407.49 | | * |
| **P-7L** | | | | | | | | | | |
| 4Q11 | 443.42 | 10/6/2011 | NE | 29.57 | NA | NA | NA | 413.85 | Unknown | |
| 1Q12 | 443.42 | 1/3/2012 | NE | 30.91 | NA | NA | NA | 412.51 | | |
| 2Q12 | 443.42 | 4/2/2012 | NE | 31.28 | NA | NA | NA | 412.14 | | |
| 3Q12 | 443.42 | 7/2/2012 | NE | 32.60 | NA | NA | NA | 410.82 | | * |
| 4Q12 | 443.42 | 10/1/2012 | NE | 33.98 | NA | NA | NA | 409.44 | | * |
| 1Q13 | 443.42 | 1/3/2013 | NE | 35.77 | NA | NA | NA | 407.65 | | * |
| **P-7U** | | | | | | | | | | |
| 2Q10 | 443.80 | 4/1/2010 | NE | 32.49 | NA | NA | NA | 411.31 | 382.72 - 380.72 (61.08 - 63.08) | * |
| 3Q10 | 443.80 | 7/1/2010 | NE | 31.63 | NA | NA | NA | 412.17 | | * |
| 4Q10 | 443.80 | 10/1/2010 | NE | 30.65 | NA | NA | NA | 413.15 | | * |
| 1Q11 | 443.80 | 1/1/2011 | NE | 30.70 | NA | NA | NA | 413.10 | | * |
| 2Q11 | 443.80 | 4/1/2011 | NE | 29.66 | NA | NA | NA | 414.14 | | * |
| 3Q11 | 443.80 | 7/5/2011 | NE | 27.30 | NA | NA | NA | 416.50 | | * |
| | 443.80 | 9/19/2011 | NE | 29.51 | NA | NA | NA | 414.29 | | * |
| 4Q11 | 443.80 | 10/6/2011 | NE | 30.02 | NA | NA | NA | 413.78 | | * |
| 1Q12 | 443.80 | 1/3/2012 | NE | 31.23 | NA | NA | NA | 412.57 | | * |
| 2Q12 | 443.80 | 4/2/2012 | NE | 31.63 | NA | NA | NA | 412.17 | | * |
| 3Q12 | 443.80 | 7/2/2012 | NE | 31.86 | NA | NA | NA | 411.94 | | * |
| 4Q12 | 443.80 | 10/1/2012 | NE | 34.55 | NA | NA | NA | 409.25 | | * |
| 1Q13 | 443.80 | 1/3/2013 | NE | 36.12 | NA | NA | NA | 407.68 | | * |

**TABLE 1**
**CUMULATIVE GROUNDWATER MONITORING WELL GAUGING RESULTS**

| WELL ID | TOP OF CASING (elev.[1]) | DATE GAUGED | DEPTH TO PRODUCT (ft btoc) | DEPTH TO WATER (ft btoc) | WATER-PRODUCT INTERFACE (elev.[1]) | PRODUCT (elev.[1]) | PRODUCT THICKNESS (ft) | CORRECTED WATER LEVEL[2] (elev.[1]) | SCREENED INTERVAL (elev.[1]) (ft btoc) | COMMENTS |
|---|---|---|---|---|---|---|---|---|---|---|
| **P-8L** | | | | | | | | | | |
| 4Q11 | 443.10 | 10/6/2011 | NE | 31.01 | NA | NA | NA | 412.09 | | |
| 1Q12 | 443.10 | 1/3/2012 | NE | 30.92 | NA | NA | NA | 412.18 | | |
| 2Q12 | 443.10 | 4/2/2012 | NE | 31.22 | NA | NA | NA | 411.88 | Unknown | |
| 3Q12 | 443.10 | 7/2/2012 | NE | 31.81 | NA | NA | NA | 411.29 | | * |
| 4Q12 | 443.10 | 10/1/2012 | NE | 33.74 | NA | NA | NA | 409.36 | | * |
| 1Q13 | 443.10 | 1/3/2013 | NE | 35.49 | NA | NA | NA | 407.61 | | * |
| **P-8U** | | | | | | | | | | |
| 2Q10 | 441.87 | 4/1/2010 | NE | 33.69 | NA | NA | NA | 408.18 | | |
| 3Q10 | 441.87 | 7/1/2010 | NE | 32.28 | NA | NA | NA | 409.59 | | |
| 4Q10 | 441.87 | 10/1/2010 | NE | 31.14 | NA | NA | NA | 410.73 | Unknown | |
| 1Q11 | 443.70 | 1/1/2011 | NE | 30.79 | NA | NA | NA | 412.91 | | |
| 2Q11 | 443.70 | 4/1/2011 | NE | 30.50 | NA | NA | NA | 413.20 | | |
| 3Q11 | 441.87 | 7/5/2011 | NE | 28.20 | NA | NA | NA | 413.67 | | * |
| | 441.87 | 9/19/2011 | NE | 29.46 | NA | NA | NA | 412.41 | | * |
| 4Q11 | 441.87 | 10/6/2011 | NE | 29.86 | NA | NA | NA | 412.01 | | * |
| 1Q12 | 441.87 | 1/3/2012 | NE | 30.99 | NA | NA | NA | 410.88 | 381.77 - 379.77 (60.10 - 62.10) | * |
| 2Q12 | 441.87 | 4/2/2012 | NE | 31.73 | NA | NA | NA | 410.14 | | * |
| 4Q12 | 441.87 | 10/1/2012 | NE | 34.77 | NA | NA | NA | 407.10 | | * |
| 1Q13 | 441.87 | 1/3/2013 | NE | 35.97 | NA | NA | NA | 405.90 | | * |
| **P-9L** | | | | | | | | | | |
| 4Q11 | 444.41 | 10/6/2011 | NE | 33.58 | NA | NA | NA | 410.83 | | |
| 1Q12 | 444.41 | 1/3/2012 | NE | 34.82 | NA | NA | NA | 409.59 | | |
| 2Q12 | 444.41 | 4/2/2012 | NE | 35.95 | NA | NA | NA | 408.46 | Unknown | |
| 3Q12 | 444.41 | 7/2/2012 | NE | 36.48 | NA | NA | NA | 407.93 | | * |
| 4Q12 | 444.41 | 10/1/2012 | NE | 38.22 | NA | NA | NA | 406.19 | | * |
| 1Q13 | 444.41 | 1/3/2013 | NE | 39.98 | NA | NA | NA | 404.43 | | * |
| **P-9U** | | | | | | | | | | |
| 2Q10 | 444.91 | 4/1/2010 | NE | 39.62 | NA | NA | NA | 405.29 | | * |
| 3Q10 | 444.91 | 7/1/2010 | NE | 38.85 | NA | NA | NA | 406.06 | | * |
| 4Q10 | 444.91 | 10/1/2010 | NE | 38.71 | NA | NA | NA | 406.20 | | * |
| 1Q11 | 444.91 | 1/13/2011 | NE | 36.87 | NA | NA | NA | 408.04 | | * |
| 2Q11 | 444.91 | 4/1/2011 | NE | 35.71 | NA | NA | NA | 409.20 | | * |
| 3Q11 | 444.91 | 7/5/2011 | NE | 34.92 | NA | NA | NA | 409.99 | | * |
| | 444.91 | 9/19/2011 | NE | 34.52 | NA | NA | NA | 410.39 | 344.32 - 342.32 (100.59 - 102.59) | * |
| 4Q11 | 444.91 | 10/6/2011 | NE | 34.56 | NA | NA | NA | 410.35 | | * |
| 1Q12 | 444.91 | 1/3/2012 | NE | 34.52 | NA | NA | NA | 410.39 | | * |
| 2Q12 | 444.91 | 4/2/2012 | NE | 36.34 | NA | NA | NA | 408.57 | | * |
| 3Q12 | 444.91 | 7/2/2012 | NE | 36.81 | NA | NA | NA | 408.10 | | * |
| 4Q12 | 444.91 | 10/1/2012 | NE | 38.59 | NA | NA | NA | 406.32 | | * |
| 1Q13 | 444.91 | 1/3/2013 | NE | 40.11 | NA | NA | NA | 404.80 | | * |
| **P-11L** | | | | | | | | | | |
| 2Q10 | 442.80 | 4/1/2010 | NE | 34.58 | NA | NA | NA | 408.22 | | * |
| 3Q10 | 442.80 | 7/1/2010 | NE | 33.22 | NA | NA | NA | 409.58 | | * |
| 4Q10 | 442.80 | 10/1/2010 | NE | 31.80 | NA | NA | NA | 411.00 | | * |
| 1Q11 | 442.80 | 1/1/2011 | NE | 31.62 | NA | NA | NA | 411.18 | | * |
| 2Q11 | 442.80 | 4/1/2011 | NE | 31.28 | NA | NA | NA | 411.52 | | * |
| 3Q11 | 442.80 | 7/5/2011 | NE | 29.34 | NA | NA | NA | 413.46 | | * |
| | 442.80 | 9/19/2011 | NE | 30.37 | NA | NA | NA | 412.43 | 332.59 - 330.59 (110.21 - 112.21) | * |
| 4Q11 | 442.80 | 10/6/2011 | NE | 30.67 | NA | NA | NA | 412.13 | | * |
| 1Q12 | 442.80 | 1/3/2012 | NE | 31.77 | NA | NA | NA | 411.03 | | * |
| 2Q12 | 442.80 | 4/2/2012 | NE | 32.68 | NA | NA | NA | 410.12 | | * |
| 3Q12 | 442.80 | 7/2/2012 | NE | 33.52 | NA | NA | NA | 409.28 | | * |
| 4Q12 | 442.80 | 10/1/2012 | NE | 35.56 | NA | NA | NA | 407.24 | | * |
| 1Q13 | 442.80 | 1/3/2013 | NE | 37.20 | NA | NA | NA | 405.60 | | * |
| **P-11U** | | | | | | | | | | |
| 2Q10 | 443.09 | 4/1/2010 | NE | 35.20 | NA | NA | NA | 407.89 | | * |
| 3Q10 | 443.09 | 7/1/2010 | NE | 33.83 | NA | NA | NA | 409.26 | | * |
| 4Q10 | 443.09 | 10/1/2010 | NE | 32.45 | NA | NA | NA | 410.64 | | * |
| 1Q11 | 443.09 | 1/1/2011 | NE | 32.21 | NA | NA | NA | 410.88 | | * |
| 2Q11 | 443.09 | 4/1/2011 | NE | 31.92 | NA | NA | NA | 411.17 | | * |
| 3Q11 | 443.09 | 7/5/2011 | NE | 29.95 | NA | NA | NA | 413.14 | | * |
| | 443.09 | 9/19/2011 | NE | 31.03 | NA | NA | NA | 412.06 | 343.17 - 341.17 (99.92 - 101.92) | * |
| 4Q11 | 443.09 | 10/6/2011 | NE | 31.12 | NA | NA | NA | 411.97 | | * |
| 1Q12 | 443.09 | 1/3/2012 | NE | 32.35 | NA | NA | NA | 410.74 | | * |
| 2Q12 | 443.09 | 4/2/2012 | NE | 33.34 | NA | NA | NA | 409.75 | | * |
| 3Q12 | 443.09 | 7/2/2012 | NE | 34.15 | NA | NA | NA | 408.94 | | * |
| 4Q12 | 443.09 | 10/1/2012 | NE | 36.19 | NA | NA | NA | 406.90 | | * |
| 1Q13 | 443.09 | 1/3/2013 | NE | 37.80 | NA | NA | NA | 405.29 | | * |
| **P-14** | | | | | | | | | | |
| 2Q10 | 442.65 | 4/1/2010 | NE | 30.20 | NA | NA | NA | 412.45 | | * |
| 3Q10 | 442.65 | 7/1/2010 | NE | 29.56 | NA | NA | NA | 413.09 | | * |
| 4Q10 | 442.65 | 10/1/2010 | NE | 27.94 | NA | NA | NA | 414.71 | | * |
| 1Q11 | 442.65 | 1/1/2011 | NE | 28.57 | NA | NA | NA | 414.08 | | * |
| 2Q11 | 442.65 | 4/1/2011 | NE | 27.38 | NA | NA | NA | 415.27 | | * |
| 3Q11 | 442.65 | 7/5/2011 | NE | 25.57 | NA | NA | NA | 417.08 | | * |
| | 442.65 | 9/19/2011 | NE | 27.77 | NA | NA | NA | 414.88 | 395.32 - 385.32 (47.33 - 57.33) | * |
| 4Q11 | 442.65 | 10/6/2011 | NE | 28.20 | NA | NA | NA | 414.45 | | * |
| 1Q12 | 442.65 | 1/3/2012 | NE | 28.98 | NA | NA | NA | 413.67 | | * |
| 2Q12 | 442.65 | 4/2/2012 | NE | 29.42 | NA | NA | NA | 413.23 | | * |
| 3Q12 | 442.65 | 7/2/2012 | NE | 30.55 | NA | NA | NA | 412.10 | | * |
| 4Q12 | 442.65 | 10/1/2012 | NE | 32.39 | NA | NA | NA | 410.26 | | * |
| 1Q13 | 442.65 | 1/3/2013 | NE | 34.01 | NA | NA | NA | 408.64 | | * |

**TABLE 1**
**CUMULATIVE GROUNDWATER MONITORING WELL GAUGING RESULTS**

| WELL ID | TOP OF CASING (elev.[1]) | DATE GAUGED | DEPTH TO PRODUCT (ft btoc) | DEPTH TO WATER (ft btoc) | WATER-PRODUCT INTERFACE (elev.[1]) | PRODUCT (elev.[1]) | PRODUCT THICKNESS (ft) | CORRECTED WATER LEVEL[2] (elev.[1]) | SCREENED INTERVAL (elev.[1]) (ft btoc) | COMMENTS |
|---|---|---|---|---|---|---|---|---|---|---|
| **P-15** | | | | | | | | | | |
| 2Q10 | 443.35 | 4/1/2010 | NE | 32.80 | NA | NA | NA | 410.55 | 397.90 - 387.90 (45.45 - 55.45) | * |
| 3Q10 | 443.35 | 7/1/2010 | NE | 31.68 | NA | NA | NA | 411.67 | | * |
| 4Q10 | 443.35 | 10/1/2010 | NE | 30.43 | NA | NA | NA | 412.92 | | * |
| 1Q11 | 443.35 | 1/1/2011 | NE | 30.55 | NA | NA | NA | 412.80 | | * |
| 2Q11 | 443.35 | 4/1/2011 | NE | 29.80 | NA | NA | NA | 413.55 | | * |
| 3Q11 | 443.35 | 7/5/2011 | NE | 27.75 | NA | NA | NA | 415.60 | | * |
| | 443.35 | 9/19/2011 | NE | 29.45 | NA | NA | NA | 413.90 | | * |
| 4Q11 | 443.35 | 10/6/2011 | NE | 29.93 | NA | NA | NA | 413.42 | | * |
| 1Q12 | 443.35 | 1/3/2012 | 31.05 | 31.06 | 412.29 | 412.30 | 0.01 | 412.30 | | * |
| 2Q12 | 443.35 | 4/2/2012 | NE | 31.55 | NA | NA | NA | 411.80 | | * |
| 3Q12 | 443.35 | 7/2/2012 | NE | 32.40 | NA | NA | NA | 410.95 | | * |
| 4Q12 | 443.35 | 10/1/2012 | NE | 34.35 | NA | NA | NA | 409.00 | | * |
| 1Q13 | 443.35 | 1/3/2013 | NE | 35.81 | NA | NA | NA | 407.54 | | * |
| **P-16** | | | | | | | | | | |
| 2Q10 | 442.31 | 4/1/2010 | NE | 31.43 | NA | NA | NA | 410.88 | 396.57 - 386.57 (45.74 - 55.74) | * |
| 3Q10 | 442.31 | 7/1/2010 | NE | 30.32 | NA | NA | NA | 411.99 | | * |
| 4Q10 | 442.31 | 10/1/2010 | NE | 29.21 | NA | NA | NA | 413.10 | | * |
| 1Q11 | 442.31 | 1/1/2011 | NE | 29.40 | NA | NA | NA | 412.91 | | * |
| 2Q11 | 442.31 | 4/1/2011 | NE | 28.54 | NA | NA | NA | 413.77 | | * |
| 3Q11 | 442.31 | 7/5/2011 | NE | 26.34 | NA | NA | NA | 415.97 | | * |
| | 442.31 | 9/19/2011 | NE | 28.26 | NA | NA | NA | 414.05 | | * |
| 4Q11 | 442.31 | 10/6/2011 | NE | 28.77 | NA | NA | NA | 413.54 | | * |
| 1Q12 | 442.31 | 1/3/2012 | NE | 30.00 | NA | NA | NA | 412.31 | | * |
| 3Q12 | 442.31 | 7/6/2012 | NE | 31.16 | NA | NA | NA | 411.15 | | * |
| 4Q12 | 442.31 | 10/4/2012 | NE | 33.35 | NA | NA | NA | 408.96 | | * |
| 1Q13 | 442.31 | 1/3/2013 | NE | 34.80 | NA | NA | NA | 407.51 | | * |
| **P-43** | | | | | | | | | | |
| 2Q10 | 444.07 | 4/1/2010 | NE | 36.02 | NA | NA | NA | 408.05 | 380.51 - 370.51 (63.56 - 73.56) | * |
| 3Q10 | 444.07 | 7/1/2010 | NE | 34.68 | NA | NA | NA | 409.39 | | * |
| 4Q10 | 444.07 | 10/1/2010 | NE | 33.29 | NA | NA | NA | 410.78 | | * |
| 1Q11 | 444.07 | 1/1/2011 | NE | 33.09 | NA | NA | NA | 410.98 | | * |
| 2Q11 | 444.07 | 4/1/2011 | NE | 32.75 | NA | NA | NA | 411.32 | | * |
| 3Q11 | 444.07 | 7/5/2011 | NE | 30.78 | NA | NA | NA | 413.29 | | * |
| | 444.07 | 9/19/2011 | NE | 31.87 | NA | NA | NA | 412.20 | | * |
| 4Q11 | 444.07 | 10/6/2011 | NE | 32.18 | NA | NA | NA | 411.89 | | * |
| 1Q12 | 444.07 | 1/3/2012 | NE | 33.24 | NA | NA | NA | 410.83 | | * |
| 2Q12 | 444.07 | 4/2/2012 | NE | 34.17 | NA | NA | NA | 409.90 | | * |
| 3Q12 | 444.07 | 7/2/2012 | NE | 34.95 | NA | NA | NA | 409.12 | | * |
| 4Q12 | 444.07 | 10/1/2012 | NE | 36.80 | NA | NA | NA | 407.27 | | * |
| 1Q13 | 444.07 | 1/3/2013 | NE | 38.21 | NA | NA | NA | 405.86 | | * |
| **P-53** | | | | | | | | | | |
| 2Q10 | 446.23 | 4/1/2010 | NE | 42.17 | NA | NA | NA | 404.06 | 407.73 - 382.73 (38.50 - 63.50) | |
| 3Q10 | 446.23 | 7/1/2010 | NE | 40.83 | NA | NA | NA | 405.40 | | |
| 4Q10 | 446.23 | 10/1/2010 | NE | 39.33 | NA | NA | NA | 406.90 | | |
| 1Q11 | 446.23 | 1/13/2011 | NE | 39.46 | NA | NA | NA | 406.77 | | |
| 2Q11 | 446.23 | 4/1/2011 | NE | 39.99 | NA | NA | NA | 406.24 | | |
| 3Q11 | 446.23 | 7/5/2011 | NE | 38.28 | NA | NA | NA | 407.95 | | * |
| | 446.23 | 9/19/2011 | NE | 37.39 | NA | NA | NA | 408.84 | | * |
| 4Q11 | 446.23 | 10/5/2011 | NE | 37.58 | NA | NA | NA | 408.65 | | * |
| 1Q12 | 446.23 | 1/3/2012 | NE | 38.73 | NA | NA | NA | 407.50 | | |
| 2Q12 | 446.23 | 4/2/2012 | NE | NM | NA | NA | NA | NA | | |
| 3Q12 | 446.23 | 7/2/2012 | NE | 40.46 | NA | NA | NA | 405.77 | | |
| 4Q12 | 446.23 | 10/1/2012 | NE | 41.88 | NA | NA | NA | 404.35 | | |
| 1Q13 | 446.23 | 1/2/2013 | NE | 43.06 | NA | NA | NA | 403.17 | | |
| **P-54** | | | | | | | | | | |
| 2Q10 | 442.18 | 4/1/2010 | NE | 38.53 | NA | NA | NA | 403.65 | 404.18 - 379.18 (38.00 - 63.00) | |
| 3Q10 | 442.18 | 7/1/2010 | NE | 37.33 | NA | NA | NA | 404.85 | | * |
| 4Q10 | 442.18 | 11/12/2010 | NE | 36.43 | NA | NA | NA | 405.75 | | * |
| 1Q11 | 442.18 | 1/13/2011 | NE | 37.24 | NA | NA | NA | 404.94 | | * |
| 2Q11 | 442.18 | 4/25/2011 | NE | 38.00 | NA | NA | NA | 404.18 | | |
| 3Q11 | 442.18 | 7/5/2011 | NE | 35.38 | NA | NA | NA | 406.80 | | * |
| | 442.18 | 9/19/2011 | NE | 34.78 | NA | NA | NA | 407.40 | | * |
| 4Q11 | 442.18 | 10/5/2011 | NE | 35.01 | NA | NA | NA | 407.17 | | * |
| 1Q12 | 442.18 | 1/3/2012 | NE | 37.17 | NA | NA | NA | 405.01 | | * |
| 2Q12 | 442.18 | 4/2/2012 | NE | 38.48 | NA | NA | NA | 403.70 | | |
| 3Q12 | 442.18 | 7/2/2012 | NE | 38.73 | NA | NA | NA | 403.45 | | |
| 4Q12 | 442.18 | 10/1/2012 | NE | 40.44 | NA | NA | NA | 401.74 | | |
| 1Q13 | 442.18 | 1/3/2013 | NE | 41.62 | NA | NA | NA | 400.56 | | |
| **P-55** | | | | | | | | | | |
| 2Q10 | 445.95 | 4/1/2010 | NE | 42.69 | NA | NA | NA | 403.26 | 406.13 - 381.13 (39.82 - 64.82) | |
| 3Q10 | 445.95 | 7/1/2010 | NE | 41.81 | NA | NA | NA | 404.14 | | |
| 4Q10 | 445.95 | 11/12/2010 | NE | 40.50 | NA | NA | NA | 405.45 | | |
| 1Q11 | 445.95 | 1/13/2011 | NE | 40.56 | NA | NA | NA | 405.39 | | |
| 2Q11 | 445.95 | 4/25/2011 | 41.52 | 41.54 | 404.41 | 404.43 | 0.02 | 404.43 | | |
| 3Q11 | 445.95 | 7/5/2011 | 39.41 | 39.42 | 406.53 | 406.54 | 0.01 | 406.54 | | * |
| | 445.95 | 9/19/2011 | NE | 38.57 | NA | NA | NA | 407.38 | | * |
| 4Q11 | 445.95 | 10/6/2011 | NE | 38.61 | NA | NA | NA | 407.34 | | * |
| 1Q12 | 445.95 | 1/4/2012 | NE | 40.71 | NA | NA | NA | 405.24 | | |
| 2Q12 | 445.95 | 4/2/2012 | NE | 42.04 | NA | NA | NA | 403.91 | | |
| 3Q12 | 445.95 | 7/2/2012 | NE | 42.33 | NA | NA | NA | 403.62 | | |
| 4Q12 | 445.95 | 10/1/2012 | NE | 44.17 | NA | NA | NA | 401.78 | | |
| 1Q13 | 443.78 | 1/8/2013 | NE | 45.24 | NA | NA | NA | 400.71 | 403.35 - 393.35 (40.43 - 50.43) | Replaced P-55 during 4Q12 |

**TABLE 1**
**CUMULATIVE GROUNDWATER MONITORING WELL GAUGING RESULTS**

| WELL ID | TOP OF CASING (elev.[1]) | DATE GAUGED | DEPTH TO PRODUCT (ft btoc) | DEPTH TO WATER (ft btoc) | WATER-PRODUCT INTERFACE (elev.[1]) | PRODUCT (elev.[1]) | PRODUCT THICKNESS (ft) | CORRECTED WATER LEVEL[2] (elev.[1]) | SCREENED INTERVAL (elev.[1]) (ft btoc) | COMMENTS |
|---|---|---|---|---|---|---|---|---|---|---|
| **P-56** | | | | | | | | | | |
| 2Q10 | 446.02 | 4/1/2010 | NE | 42.71 | NA | NA | NA | 403.31 | 405.20 - 380.20 (40.82 - 65.82) | |
| 3Q10 | 446.02 | 7/1/2010 | NE | 41.99 | NA | NA | NA | 404.03 | | |
| 4Q10 | 446.02 | 11/11/2010 | NE | 40.94 | NA | NA | NA | 405.08 | | |
| 1Q11 | 446.02 | 1/13/2011 | NE | 41.03 | NA | NA | NA | 404.99 | | |
| 2Q11 | 446.02 | 4/25/2011 | NE | 42.16 | NA | NA | NA | 403.86 | | |
| 3Q11 | 446.02 | 7/5/2011 | NE | 39.63 | NA | NA | NA | 406.39 | | * |
| | 446.02 | 9/19/2011 | NE | 38.88 | NA | NA | NA | 407.14 | | * |
| 4Q11 | 446.02 | 10/6/2011 | NE | 39.10 | NA | NA | NA | 406.92 | | * |
| 1Q12 | 446.02 | 1/4/2012 | NE | 41.51 | NA | NA | NA | 404.51 | | |
| 2Q12 | 446.02 | 4/3/2012 | NE | 42.88 | NA | NA | NA | 403.14 | | |
| 3Q12 | 446.02 | 7/5/2012 | NE | 43.01 | NA | NA | NA | 403.01 | | |
| 4Q12 | 446.02 | 10/2/2012 | NE | 44.76 | NA | NA | NA | 401.26 | | |
| 1Q13 | 446.02 | 1/4/2013 | NE | 45.65 | NA | NA | NA | 400.37 | | |
| **P-57** | | | | | | | | | | |
| 2Q10 | 446.53 | 4/1/2010 | NE | 42.73 | NA | NA | NA | 403.80 | 406.07 - 381.07 (40.46 - 65.46) | |
| 3Q10 | 446.53 | 7/1/2010 | NE | 41.60 | NA | NA | NA | 404.93 | | |
| 4Q10 | 446.53 | 11/12/2010 | NE | 40.64 | NA | NA | NA | 405.89 | | |
| 1Q11 | 446.53 | 1/13/2011 | NE | 41.04 | NA | NA | NA | 405.49 | | |
| 2Q11 | 446.53 | 4/25/2011 | NE | 41.88 | NA | NA | NA | 404.65 | | |
| 3Q11 | 446.53 | 7/5/2011 | NE | 39.48 | NA | NA | NA | 407.05 | | * |
| | 446.53 | 9/19/2011 | NE | 39.92 | NA | NA | NA | 406.61 | | * |
| 4Q11 | 446.53 | 10/6/2011 | NE | 39.20 | NA | NA | NA | 407.33 | | * |
| 1Q12 | 446.53 | 2/13/2012 | NE | 42.13 | NA | NA | NA | 404.40 | | |
| 2Q12 | 446.53 | 4/4/2012 | NE | 42.61 | NA | NA | NA | 403.92 | | |
| 3Q12 | 446.53 | 7/5/2012 | NE | 43.00 | NA | NA | NA | 403.53 | | |
| 4Q12 | 446.53 | 10/1/2012 | NE | 44.78 | NA | NA | NA | 401.75 | | |
| 1Q13 | 446.53 | 1/4/2013 | NE | 45.82 | NA | NA | NA | 400.71 | | |
| **P-58** | | | | | | | | | | |
| 2Q10 | 444.92 | 4/1/2010 | NE | 40.76 | NA | NA | NA | 404.16 | 404.70 - 379.70 (40.21 - 65.21) | Oily film observed on probe but no product response observed from probe or product paste. |
| 3Q10 | 444.92 | 7/1/2010 | 39.42 | 39.46 | 405.46 | 405.50 | 0.04 | 405.49 | | *Product confirmed on interface probe. |
| 4Q10 | 444.92 | 11/12/2010 | NE | 38.51 | NA | NA | NA | 406.41 | | * |
| 1Q11 | 444.92 | 1/13/2011 | NE | 39.10 | NA | NA | NA | 405.82 | | *No tone; produt paste turned |
| 2Q11 | 444.92 | 4/25/2011 | NE | 39.78 | NA | NA | NA | 405.14 | | *No tone; produt paste turned |
| 3Q11 | 444.92 | 7/5/2011 | NE | 37.42 | NA | NA | NA | 407.50 | | * |
| | 444.92 | 9/19/2011 | NE | 37.02 | NA | NA | NA | 407.90 | | * |
| 4Q11 | 444.92 | 10/6/2011 | NE | 37.31 | NA | NA | NA | 407.61 | | * |
| 1Q12 | 444.92 | 1/4/2012 | NE | 39.41 | NA | NA | NA | 405.51 | | * |
| 2Q12 | 444.92 | 4/3/2012 | NE | 40.81 | NA | NA | NA | 404.11 | | |
| 3Q12 | 444.92 | 7/5/2012 | NE | 41.04 | NA | NA | NA | 403.88 | | |
| 4Q12 | 444.92 | 10/2/2012 | NE | 42.90 | NA | NA | NA | 402.02 | | |
| 1Q13 | 444.92 | 1/4/2013 | NE | 43.80 | NA | NA | NA | 401.12 | | |
| **P-59** | | | | | | | | | | |
| 2Q10 | 446.78 | 4/1/2010 | NE | 43.59 | NA | NA | NA | 403.19 | 398.87 - 373.87 (47.91 - 72.91) | *Oily film observed on probe but no product response observed from probe or product paste. |
| 3Q10 | 446.78 | 7/1/2010 | 43.21 | 43.23 | 403.55 | 403.57 | 0.02 | 403.57 | | *Product confirmed on interface probe. |
| 4Q10 | 446.78 | 11/12/2010 | NE | 42.13 | NA | NA | NA | 404.65 | | * |
| 1Q11 | 446.78 | 1/13/2011 | NE | 42.16 | NA | NA | NA | 404.62 | | *No tone; product paste turned |
| 2Q11 | 446.78 | 4/25/2011 | 43.25 | 43.26 | 403.52 | 403.53 | 0.01 | 403.53 | | *No tone; product paste turned |
| 3Q11 | 446.78 | 7/5/2011 | NE | 41.44 | NA | NA | NA | 405.34 | | * |
| | 446.78 | 9/19/2011 | NE | 40.56 | NA | NA | NA | 406.22 | | * |
| 4Q11 | 446.78 | 10/6/2011 | NE | 40.77 | NA | NA | NA | 406.01 | | * |
| 1Q12 | 446.78 | 1/4/2012 | NE | 42.61 | NA | NA | NA | 404.17 | | * |
| 2Q12 | 446.78 | 4/4/2012 | NE | 43.82 | NA | NA | NA | 402.96 | | * |
| 3Q12 | 446.78 | 7/5/2012 | NE | 44.00 | NA | NA | NA | 402.78 | | * |
| 4Q12 | 446.78 | 10/2/2012 | NE | 45.83 | NA | NA | NA | 400.95 | | * |
| 1Q13 | 446.78 | 1/4/2013 | NE | 46.54 | NA | NA | NA | 400.24 | | * |
| **P-60** | | | | | | | | | | |
| 2Q10 | 446.57 | 4/1/2010 | 43.45 | 43.73 | 402.84 | 403.12 | 0.28 | 403.07 | 403.12 - 383.12 (43.45 - 63.45) | Product confirmed on interface probe. |
| 3Q10 | 446.57 | 7/1/2010 | 42.61 | 43.18 | 403.39 | 403.96 | 0.57 | 403.85 | | *Product confirmed on interface probe. |
| 4Q10 | 446.57 | 11/11/2010 | 41.40 | 41.44 | 405.13 | 405.17 | 0.04 | 405.16 | | * |
| 1Q11 | 446.57 | 1/14/2011 | 41.68 | 41.72 | 404.85 | 404.89 | 0.04 | 404.88 | | * |
| 2Q11 | 446.57 | 4/25/2011 | 42.72 | 43.18 | 403.39 | 403.85 | 0.46 | 403.76 | | * |
| 3Q11 | 446.57 | 7/5/2011 | 40.41 | 40.77 | 405.80 | 406.16 | 0.36 | 406.09 | | * |
| | 446.57 | 9/19/2011 | 39.54 | 39.89 | 406.68 | 407.03 | 0.35 | 406.96 | | * |
| 4Q11 | 446.57 | 10/6/2011 | 39.72 | 40.06 | 406.51 | 406.85 | 0.34 | 406.79 | | * |
| 1Q12 | 446.57 | 1/4/2012 | NE | 41.98 | NA | NA | NA | 404.59 | | * |
| 2Q12 | 446.57 | 4/3/2012 | 43.46 | 43.48 | 403.09 | 403.11 | 0.02 | 403.11 | | |
| 3Q12 | 446.57 | 7/5/2012 | 43.51 | 43.55 | 403.02 | 403.06 | 0.04 | 403.05 | | |
| 4Q12 | 446.57 | 10/2/2012 | 45.33 | 45.44 | 401.13 | 401.24 | 0.11 | 401.22 | | |
| 1Q13 | 446.57 | 1/4/2013 | NE | 46.19 | NA | NA | NA | 400.38 | | |
| **P-60-11** | | | | | | | | | | |
| 4Q10 | 443.39 | 11/11/2010 | NE | 40.91 | NA | NA | NA | 402.48 | Unknown | |
| 1Q11 | 443.39 | 1/14/2011 | NE | 41.14 | NA | NA | NA | 402.25 | | |
| 2Q11 | 443.39 | 4/25/2011 | NE | 42.22 | NA | NA | NA | 401.17 | | |
| 3Q11 | 446.18 | 7/5/2011 | NE | 39.97 | NA | NA | NA | 406.21 | 413.03 - 383.03 (33.15 - 63.15) | |
| | 446.18 | 9/19/2011 | NE | 39.07 | NA | NA | NA | 407.11 | | |
| 4Q11 | 446.18 | 10/6/2011 | NE | 39.25 | NA | NA | NA | 406.93 | | |
| 1Q12 | 446.18 | 1/4/2012 | NE | 41.22 | NA | NA | NA | 404.96 | | |
| 2Q12 | 446.18 | 4/3/2012 | NE | 42.65 | NA | NA | NA | 403.53 | | |
| 3Q12 | 446.18 | 7/5/2012 | NE | 42.64 | NA | NA | NA | 403.54 | | |
| 4Q12 | 446.18 | 10/2/2012 | 44.32 | 44.41 | 401.77 | 401.86 | 0.09 | 401.84 | | |
| 1Q13 | 446.18 | 1/4/2013 | NE | 45.06 | NA | NA | NA | 401.12 | | |

**TABLE 1**
**CUMULATIVE GROUNDWATER MONITORING WELL GAUGING RESULTS**

| WELL ID | TOP OF CASING (elev.[1]) | DATE GAUGED | DEPTH TO PRODUCT (ft btoc) | DEPTH TO WATER (ft btoc) | WATER-PRODUCT INTERFACE (elev.[1]) | PRODUCT (elev.[1]) | PRODUCT THICKNESS (ft) | CORRECTED WATER LEVEL[2] (elev.[1]) | SCREENED INTERVAL (elev.[1]) (ft btoc) | COMMENTS |
|---|---|---|---|---|---|---|---|---|---|---|
| **P-60-12** | | | | | | | | | | |
| 4Q10 | 443.31 | 11/11/2010 | NE | 38.19 | NA | NA | NA | 405.12 | 383.31 - 373.31 (60.00 - 70.00) | * |
| 1Q11 | 443.31 | 1/14/2011 | NE | 38.51 | NA | NA | NA | 404.80 | | * |
| 2Q11 | 443.31 | 4/25/2011 | NE | 39.63 | NA | NA | NA | 403.68 | | * |
| 3Q11 | 443.31 | 7/5/2011 | NE | 37.27 | NA | NA | NA | 406.04 | | * |
| | 443.31 | 9/19/2011 | NE | 36.41 | NA | NA | NA | 406.90 | | * |
| 4Q11 | 443.31 | 10/6/2011 | NE | 36.53 | NA | NA | NA | 406.78 | | * |
| 1Q12 | 443.31 | 1/4/2012 | NE | 38.76 | NA | NA | NA | 404.55 | | * |
| 2Q12 | 443.31 | 4/3/2012 | NE | 40.25 | NA | NA | NA | 403.06 | | * |
| 3Q12 | 443.31 | 7/5/2012 | NE | 40.23 | NA | NA | NA | 403.08 | | * |
| 4Q12 | 443.31 | 10/2/2012 | NE | 44.15 | NA | NA | NA | 399.16 | | * |
| 1Q13 | 443.31 | 1/4/2013 | NE | 42.97 | NA | NA | NA | 400.34 | | * |
| **P-60-12S** | ***(PERCHED WELL)*** | | | | | | | | | |
| 4Q10 | 443.33 | 11/11/2010 | NE | 23.36 | NA | NA | NA | 419.97 | 429.49 - 419.49 (13.84 - 23.84) | |
| 1Q11 | 443.33 | 1/14/2011 | NE | NE | NA | NA | NA | NA | | |
| 2Q11 | 443.33 | 4/25/2011 | NE | 21.84 | NA | NA | NA | 421.49 | | |
| 3Q11 | 443.33 | 7/5/2011 | 21.10 | 21.11 | 422.22 | 422.23 | 0.01 | 422.23 | | |
| 4Q11 | 443.33 | 10/6/2011 | NE | 23.36 | NA | NA | NA | 419.97 | | |
| 1Q12 | 443.33 | 1/4/2012 | NE | 22.81 | NA | NA | NA | 420.52 | | |
| 2Q12 | 443.33 | 4/3/2012 | NE | 20.21 | NA | NA | NA | 423.12 | | |
| 3Q12 | 443.33 | 7/5/2012 | NE | 19.48 | NA | NA | NA | 423.85 | | |
| 4Q12 | 443.33 | 10/2/2012 | NE | 19.04 | NA | NA | NA | 424.29 | | |
| 1Q13 | 443.33 | 1/4/2013 | NE | 19.35 | NA | NA | NA | 423.98 | | |
| **P-60-13** | | | | | | | | | | |
| 4Q10 | 442.43 | 11/11/2010 | 37.50 | 37.87 | 404.56 | 404.93 | 0.37 | 404.86 | 402.43 - 382.43 (40.00 - 60.00) | * |
| 1Q11 | 442.43 | 1/14/2011 | 37.73 | 37.74 | 404.69 | 404.70 | 0.01 | 404.70 | | * |
| 2Q11 | 442.43 | 4/25/2011 | 38.80 | 39.10 | 403.33 | 403.63 | 0.30 | 403.57 | | * |
| 3Q11 | 442.43 | 7/5/2011 | 36.85 | 36.99 | 405.44 | 405.58 | 0.14 | 405.55 | | * |
| | 442.43 | 9/19/2011 | NE | 35.72 | NA | NA | NA | 406.71 | | * |
| 4Q11 | 442.43 | 10/6/2011 | NE | 35.86 | NA | NA | NA | 406.57 | | * |
| 1Q12 | 442.43 | 1/4/2012 | NE | 37.82 | NA | NA | NA | 404.61 | | * |
| 2Q12 | 442.43 | 4/3/2012 | NE | 39.21 | NA | NA | NA | 403.22 | | * |
| 3Q12 | 442.43 | 7/5/2012 | NE | 39.37 | NA | NA | NA | 403.06 | | * |
| 4Q12 | 442.43 | 10/2/2012 | NE | 40.61 | NA | NA | NA | 401.82 | | |
| 1Q13 | 442.43 | 1/4/2013 | NE | 41.55 | NA | NA | NA | 400.88 | | |
| **P-60-13S** | ***(PERCHED WELL)*** | | | | | | | | | |
| 4Q10 | 442.39 | 11/11/2010 | NE | 13.36 | NA | NA | NA | 429.03 | 432.39 - 422.39 (10.00 - 20.00) | |
| 1Q11 | 442.39 | 1/14/2011 | NE | NE | NA | NA | NA | NA | | |
| 2Q11 | 442.39 | 4/25/2011 | NE | 17.45 | NA | NA | NA | 424.94 | | |
| 3Q11 | 442.39 | 7/5/2011 | NE | 17.08 | NA | NA | NA | 425.31 | | |
| 4Q11 | 442.39 | 10/6/2011 | NE | 18.44 | NA | NA | NA | 423.95 | | |
| 1Q12 | 442.39 | 1/4/2012 | NE | 17.66 | NA | NA | NA | 424.73 | | |
| 2Q12 | 442.39 | 4/3/2012 | NE | 17.58 | NA | NA | NA | 424.81 | | |
| 3Q12 | 442.39 | 7/5/2012 | NE | 17.87 | NA | NA | NA | 424.52 | | |
| 4Q12 | 442.39 | 10/2/2012 | NE | 17.97 | NA | NA | NA | 424.42 | | |
| 1Q13 | 442.39 | 1/4/2013 | NE | NE | NA | NA | NA | NA | | Well dry |
| **P-60-S** | | | | | | | | | | |
| 3Q11 | 446.98 | 7/5/2011 | NE | 40.81 | NA | NA | NA | 406.17 | 410.50 - 395.50 (36.48 - 51.48) | |
| | | 9/19/2011 | 39.40 | 39.61 | 407.37 | 407.58 | 0.21 | 407.54 | | |
| 1Q12 | 446.98 | 1/4/2012 | 41.39 | 41.90 | 405.08 | 405.59 | 0.51 | 405.49 | | |
| 2Q12 | 446.98 | 4/3/2012 | 42.85 | 43.28 | 403.70 | 404.13 | 0.43 | 404.04 | | |
| 3Q12 | 446.98 | 7/5/2012 | 43.12 | 43.26 | 403.72 | 403.86 | 0.14 | 403.83 | | |
| 4Q12 | 446.98 | 10/4/2012 | 43.94 | 45.84 | 401.14 | 403.04 | 1.90 | 402.66 | | |
| 1Q13 | 446.98 | 1/4/2013 | 45.34 | 45.95 | 401.03 | 401.64 | 0.61 | 401.52 | | |
| **P-61** | | | | | | | | | | |
| 2Q10 | 444.27 | 4/1/2010 | 41.97 | 42.09 | 402.18 | 402.30 | 0.12 | 402.27 | 398.59 - 373.59 (45.68 - 70.68) | *Product confirmed on interface probe. |
| 3Q10 | 444.27 | 7/1/2010 | 41.04 | 41.18 | 403.09 | 403.23 | 0.14 | 403.20 | | *Product confirmed on interface probe. |
| 4Q10 | 444.27 | 11/11/2010 | 39.91 | 40.03 | 404.24 | 404.36 | 0.12 | 404.33 | | * |
| 1Q11 | 444.27 | 1/13/2011 | 38.81 | 38.94 | 405.33 | 405.46 | 0.13 | 405.43 | | * |
| 2Q11 | 444.27 | 4/25/2011 | NE | 40.93 | NA | NA | NA | 403.34 | | * |
| 3Q11 | 444.27 | 7/5/2011 | 37.58 | 37.59 | 406.68 | 406.69 | 0.01 | 406.69 | | * |
| | 444.27 | 9/19/2011 | NE | 37.36 | NA | NA | NA | 406.91 | | * |
| 4Q11 | 444.27 | 10/6/2011 | NE | 37.63 | NA | NA | NA | 406.64 | | * |
| 1Q12 | 444.27 | 1/3/2012 | NE | 40.34 | NA | NA | NA | 403.93 | | * |
| 2Q12 | 444.27 | 4/3/2012 | NE | 41.50 | NA | NA | NA | 402.77 | | * |
| 3Q12 | 444.27 | 7/3/2012 | NE | 41.53 | NA | NA | NA | 402.74 | | * |
| 4Q12 | 444.27 | 10/2/2012 | NE | 43.36 | NA | NA | NA | 400.91 | | * |
| 1Q13 | 444.27 | 1/4/2013 | 43.82 | 45.95 | 398.32 | 400.45 | 2.13 | 400.02 | | * |
| **P-62** | | | | | | | | | | |
| 2Q10 | 442.32 | 4/1/2010 | 39.56 | 40.90 | 401.42 | 402.76 | 1.34 | 402.50 | 400.85 - 375.85 (41.47 - 66.47) | *Product confirmed on interface probe. |
| 3Q10 | 442.32 | 7/1/2010 | 38.51 | 39.96 | 402.36 | 403.81 | 1.45 | 403.52 | | *Product confirmed on interface probe. |
| 4Q10 | 442.32 | 11/11/2010 | 37.14 | 38.57 | 403.75 | 405.18 | 1.43 | 404.90 | | * |
| 1Q11 | 442.32 | 1/13/2011 | 36.39 | 37.81 | 404.51 | 405.93 | 1.42 | 405.65 | | * |
| 2Q11 | 442.32 | 4/25/2011 | NE | 38.18 | NA | NA | NA | 404.14 | | * |
| 3Q11 | 442.32 | 7/5/2011 | 35.62 | 35.63 | 406.69 | 406.70 | 0.01 | 406.70 | | * |
| | 442.32 | 9/19/2011 | 35.39 | 35.41 | 406.91 | 406.93 | 0.02 | 406.93 | | * |
| 4Q11 | 442.32 | 10/6/2011 | NE | 35.64 | NA | NA | NA | 406.68 | | * |
| 1Q12 | 442.32 | 1/3/2012 | 37.68 | 37.71 | 404.61 | 404.64 | 0.03 | 404.64 | | * |
| 2Q12 | 442.32 | 4/3/2012 | NE | 30.94 | NA | NA | NA | 411.38 | | *Result is suspect |
| 3Q12 | 442.32 | 7/3/2012 | 39.13 | 39.15 | 403.17 | 403.19 | 0.02 | 403.19 | | * |
| 4Q12 | 442.32 | 10/1/2012 | 40.61 | 42.35 | 399.97 | 401.71 | 1.74 | 401.37 | | * |
| 1Q13 | 442.32 | 1/8/2013 | NE | 30.39 | NA | NA | NA | 411.93 | | *Result is suspect |

**TABLE 1**
**CUMULATIVE GROUNDWATER MONITORING WELL GAUGING RESULTS**

| WELL ID | TOP OF CASING (elev.[1]) | DATE GAUGED | DEPTH TO PRODUCT (ft btoc) | DEPTH TO WATER (ft btoc) | WATER-PRODUCT INTERFACE (elev.[1]) | PRODUCT (elev.[1]) | PRODUCT THICKNESS (ft) | CORRECTED WATER LEVEL[2] (elev.[1]) | SCREENED INTERVAL (elev.[1]) (ft btoc) | COMMENTS |
|---|---|---|---|---|---|---|---|---|---|---|
| **P-63** | | | | | | | | | | |
| 2Q10 | 445.75 | 4/1/2010 | 43.53 | 43.72 | 402.03 | 402.22 | 0.19 | 402.18 | 398.46 - 373.46 (47.29 - 72.29) | *Product confirmed on interface probe. |
| 3Q10 | 445.75 | 7/1/2010 | 42.32 | 42.52 | 403.23 | 403.43 | 0.20 | 403.39 | | *Product confirmed on interface probe. |
| 4Q10 | 445.75 | 10/1/2010 | 40.58 | 40.79 | 404.96 | 405.17 | 0.21 | 405.13 | | *Product confirmed on interface probe. |
| 1Q11 | 445.75 | 1/13/2011 | 39.48 | 39.68 | 406.07 | 406.27 | 0.20 | 406.23 | | * |
| 2Q11 | 445.75 | 4/1/2011 | NE | 41.11 | NA | NA | NA | 404.64 | | * |
| 3Q11 | 445.75 | 7/5/2011 | NE | 38.56 | NA | NA | NA | 407.19 | | * |
| | 445.75 | 9/19/2011 | NE | 39.12 | NA | NA | NA | 406.63 | | * |
| 4Q11 | 445.75 | 10/6/2011 | NE | 39.20 | NA | NA | NA | 406.55 | | * |
| 1Q12 | 445.75 | 1/3/2012 | NE | 40.65 | NA | NA | NA | 405.10 | | * |
| 2Q12 | 445.75 | 4/3/2012 | NE | 42.09 | NA | NA | NA | 403.66 | | * |
| 3Q12 | 445.75 | 7/3/2012 | NE | 42.94 | NA | NA | NA | 402.81 | | * |
| 4Q12 | 445.75 | 10/1/2012 | NE | 44.55 | NA | NA | NA | 401.20 | | * |
| 1Q13 | 445.75 | 1/4/2013 | NE | 46.03 | NA | NA | NA | 399.72 | | * |
| **P-64** | | | | | | | | | | |
| 2Q10 | 446.52 | 4/1/2010 | 44.61 | 44.70 | 401.82 | 401.91 | 0.09 | 401.89 | 399.29 - 374.29 (47.23 - 72.23) | *Product confirmed on interface probe. |
| 3Q10 | 446.52 | 7/1/2010 | 43.46 | 43.61 | 402.91 | 403.06 | 0.15 | 403.03 | | *Product confirmed on interface probe. |
| 4Q10 | 446.52 | 10/1/2010 | 41.45 | 41.56 | 404.96 | 405.07 | 0.11 | 405.05 | | *Product confirmed on interface probe. |
| 1Q11 | 446.52 | 1/13/2011 | 40.14 | 40.46 | 406.06 | 406.38 | 0.32 | 406.32 | | * |
| 2Q11 | 446.52 | 4/1/2011 | 41.77 | 41.86 | 404.66 | 404.75 | 0.09 | 404.73 | | * |
| 3Q11 | 446.52 | 7/5/2011 | 39.25 | 39.42 | 407.10 | 407.27 | 0.17 | 407.24 | | * |
| | 446.52 | 9/19/2011 | 40.10 | 41.10 | 405.42 | 406.42 | 1.00 | 406.22 | | * |
| 4Q11 | 446.52 | 10/6/2011 | 40.35 | 40.53 | 405.99 | 406.17 | 0.18 | 406.13 | | * |
| 1Q12 | 446.52 | 1/3/2012 | 41.68 | 41.75 | 404.77 | 404.84 | 0.07 | 404.83 | | * |
| 2Q12 | 446.52 | 4/3/2012 | 43.18 | 43.19 | 403.33 | 403.34 | 0.01 | 403.34 | | * |
| 3Q12 | 446.52 | 7/3/2012 | 44.40 | 44.41 | 402.11 | 402.12 | 0.01 | 402.12 | | * |
| 4Q12 | 446.52 | 10/1/2012 | 45.62 | 45.68 | 400.84 | 400.90 | 0.06 | 400.89 | | * |
| 1Q13 | 446.52 | 1/4/2013 | NE | 47.84 | NA | NA | NA | 398.68 | | |
| **P-65** | | | | | | | | | | |
| 2Q10 | 444.53 | 4/1/2010 | 41.33 | 41.34 | 403.19 | 403.20 | 0.01 | 403.20 | 396.91 - 371.91 (47.62 - 72.62) | *Product confirmed on interface probe. |
| 3Q10 | 444.53 | 7/1/2010 | 44.34 | 44.35 | 400.18 | 400.19 | 0.01 | 400.19 | | *Product confirmed on interface probe. |
| 4Q10 | 444.53 | 10/1/2010 | 38.61 | 38.63 | 405.90 | 405.92 | 0.02 | 405.92 | | *Product confirmed on interface probe. |
| 1Q11 | 444.53 | 1/13/2011 | 37.73 | 37.74 | 406.79 | 406.80 | 0.01 | 406.80 | | * |
| 2Q11 | 444.53 | 4/1/2011 | NE | 39.20 | NA | NA | NA | 405.33 | | * |
| 3Q11 | 444.53 | 7/5/2011 | NE | 36.87 | NA | NA | NA | 407.66 | | * |
| | 444.53 | 9/19/2011 | NE | 37.54 | NA | NA | NA | 406.99 | | * |
| 4Q11 | 444.53 | 10/6/2011 | NE | 37.67 | NA | NA | NA | 406.86 | | * |
| 1Q12 | 444.53 | 1/3/2012 | NE | 39.15 | NA | NA | NA | 405.38 | | * |
| 2Q12 | 444.53 | 4/3/2012 | NE | 40.76 | NA | NA | NA | 403.77 | | * |
| 3Q12 | 444.53 | 7/3/2012 | NE | 41.76 | NA | NA | NA | 402.77 | | * |
| 4Q12 | 444.53 | 10/1/2012 | NE | 43.00 | NA | NA | NA | 401.53 | | * |
| 1Q13 | 444.53 | 1/4/2013 | NE | 44.61 | NA | NA | NA | 399.92 | | * |
| **P-66** | | | | | | | | | | |
| 2Q10 | 436.70 | 4/1/2010 | NE | 32.30 | NA | NA | NA | 404.40 | 401.98 - 376.98 (34.72 - 59.72) | * |
| 3Q10 | 436.70 | 7/1/2010 | 30.81 | 30.83 | 405.87 | 405.89 | 0.02 | 405.89 | | *Product confirmed on interface probe. |
| 4Q10 | 436.70 | 11/12/2010 | NE | 30.02 | NA | NA | NA | 406.68 | | * |
| 1Q11 | 436.70 | 1/13/2011 | NE | 30.70 | NA | NA | NA | 406.00 | | * |
| 2Q11 | 436.70 | 4/25/2011 | NE | 31.26 | NA | NA | NA | 405.44 | | * |
| 3Q11 | 436.70 | 7/5/2011 | NE | 28.87 | NA | NA | NA | 407.83 | | * |
| | 436.70 | 9/19/2011 | NE | 28.64 | NA | NA | NA | 408.06 | | * |
| 4Q11 | 436.70 | 10/5/2011 | NE | 28.92 | NA | NA | NA | 407.78 | | * |
| 1Q12 | 436.70 | 1/3/2012 | NM | NM | NA | NA | NA | NA | | Restricted Area |
| 2Q12 | 436.70 | 4/2/2012 | NM | NM | NA | NA | NA | NA | | Restricted Area |
| 3Q12 | 436.70 | 7/5/2012 | 32.60 | 32.61 | 404.09 | 404.10 | 0.01 | 404.10 | | * |
| 4Q12 | 436.70 | 10/2/2012 | NE | 34.55 | NA | NA | NA | 402.15 | | * |
| 1Q13 | 436.70 | 1/2/2013 | NE | 35.40 | NA | NA | NA | 401.30 | | |
| **P-67** | | | | | | | | | | |
| 2Q10 | 444.13 | 4/1/2010 | 38.78 | 38.80 | 405.33 | 405.35 | 0.02 | 405.35 | 402.16 - 377.16 (41.98 - 66.98) | *Product confirmed on interface probe. |
| 3Q10 | 444.13 | 7/1/2010 | 37.27 | 37.46 | 406.67 | 406.86 | 0.19 | 406.82 | | *Product confirmed on interface probe. |
| 4Q10 | 444.13 | 10/1/2010 | 36.27 | 36.31 | 407.82 | 407.86 | 0.04 | 407.85 | | *Product confirmed on interface probe. |
| 1Q11 | 444.13 | 1/13/2011 | 36.75 | 36.78 | 407.35 | 407.38 | 0.03 | 407.37 | | * |
| 2Q11 | 444.13 | 4/1/2011 | NE | 37.24 | NA | NA | NA | 406.89 | | * |
| 3Q11 | 444.13 | 7/5/2011 | NE | 35.17 | NA | NA | NA | 408.96 | | * |
| | 444.13 | 9/19/2011 | NE | 35.16 | NA | NA | NA | 408.97 | | * |
| 4Q11 | 444.13 | 10/5/2011 | NE | 35.38 | NA | NA | NA | 408.75 | | * |
| 1Q12 | 444.13 | 1/4/2012 | NE | 37.08 | NA | NA | NA | 407.05 | | * |
| 2Q12 | 444.13 | 4/3/2012 | NE | 38.50 | NA | NA | NA | 405.63 | | * |
| 3Q12 | 444.13 | 7/2/2012 | NE | 38.90 | NA | NA | NA | 405.23 | | * |
| 4Q12 | 444.13 | 10/2/2012 | NE | 40.81 | NA | NA | NA | 403.32 | | * |
| 1Q13 | 444.13 | 1/2/2013 | NE | 41.69 | NA | NA | NA | 402.44 | | * |

SEE LAST PAGE OF TABLE FOR NOTES

**TABLE 1**
**CUMULATIVE GROUNDWATER MONITORING WELL GAUGING RESULTS**

| WELL ID | TOP OF CASING (elev.[1]) | DATE GAUGED | DEPTH TO PRODUCT (ft btoc) | DEPTH TO WATER (ft btoc) | WATER-PRODUCT INTERFACE (elev.[1]) | PRODUCT (elev.[1]) | PRODUCT THICKNESS (ft) | CORRECTED WATER LEVEL[2] (elev.[1]) | SCREENED INTERVAL (elev.[1]) (ft btoc) | COMMENTS |
|---|---|---|---|---|---|---|---|---|---|---|
| **P-68** | | | | | | | | | | |
| 2Q10 | 445.07 | 4/1/2010 | 40.94 | 48.15 | 396.92 | 404.13 | 7.21 | 402.69 | 399.81 - 374.81 (45.26 - 70.26) | *Product confirmed on interface probe. |
| 3Q10 | 445.07 | 7/1/2010 | 40.50 | 44.65 | 400.42 | 404.57 | 4.15 | 403.74 | | *Product confirmed on interface probe. |
| 4Q10 | 445.07 | 11/12/2010 | 39.32 | 43.42 | 401.65 | 405.75 | 4.10 | 404.93 | | * |
| 1Q11 | 445.07 | 1/13/2011 | 39.15 | 43.18 | 401.89 | 405.92 | 4.03 | 405.12 | | * |
| 2Q11 | 445.07 | 4/25/2011 | 41.42 | 41.51 | 403.56 | 403.65 | 0.09 | 403.63 | | * |
| 3Q11 | 445.07 | 7/5/2011 | 39.06 | 39.13 | 405.94 | 406.01 | 0.07 | 406.00 | | * |
| | 445.07 | 9/19/2011 | 39.01 | 39.03 | 406.04 | 406.06 | 0.02 | 406.06 | | * |
| 4Q11 | 445.07 | 10/6/2011 | 38.53 | 38.58 | 406.49 | 406.54 | 0.05 | 406.53 | | * |
| 1Q12 | 445.07 | 1/4/2012 | 40.53 | 40.61 | 404.46 | 404.54 | 0.08 | 404.52 | | * |
| 2Q12 | 445.07 | 4/3/2012 | NE | 42.08 | NA | NA | NA | 402.99 | | * |
| 3Q12 | 445.07 | 7/5/2012 | 42.08 | 42.12 | 402.95 | 402.99 | 0.04 | 402.98 | | * |
| 4Q12 | 445.07 | 10/2/2012 | 43.85 | 44.04 | 401.03 | 401.22 | 0.19 | 401.18 | | * |
| 1Q13 | 445.07 | 1/7/2013 | 44.55 | 44.95 | 400.12 | 400.52 | 0.40 | 400.44 | | * |
| **P-69** | | | | | | | | | | |
| 2Q10 | 443.18 | 4/1/2010 | 40.39 | 40.42 | 402.76 | 402.79 | 0.03 | 402.79 | 402.36 - 377.36 (40.82 - 65.82) | *Product confirmed on interface probe. |
| 3Q10 | 443.18 | 7/1/2010 | NE | 40.14 | NA | NA | NA | 403.04 | | * |
| 4Q10 | 443.18 | 11/11/2010 | 38.99 | 39.02 | 404.16 | 404.19 | 0.03 | 404.19 | | * |
| 1Q11 | 443.18 | 1/13/2011 | 38.62 | 38.63 | 404.55 | 404.56 | 0.01 | 404.56 | | * |
| 2Q11 | 443.18 | 4/25/2011 | NE | 39.98 | NA | NA | NA | 403.20 | | * |
| 3Q11 | 443.18 | 7/5/2011 | NE | 37.41 | NA | NA | NA | 405.77 | | * |
| | 443.18 | 9/19/2011 | NE | 36.62 | NA | NA | NA | 406.56 | | * |
| 4Q11 | 443.18 | 10/6/2011 | NE | 36.77 | NA | NA | NA | 406.41 | | * |
| 1Q12 | 443.18 | 1/4/2012 | NE | 39.18 | NA | NA | NA | 404.00 | | * |
| 2Q12 | 443.18 | 4/3/2012 | NE | 40.59 | NA | NA | NA | 402.59 | | * |
| 3Q12 | 443.18 | 7/5/2012 | NE | 40.61 | NA | NA | NA | 402.57 | | * |
| 4Q12 | 443.18 | 10/2/2012 | NE | 42.46 | NA | NA | NA | 400.72 | | |
| 1Q13 | 443.18 | 1/4/2013 | NE | 43.85 | NA | NA | NA | 399.33 | | |
| **P-70** | | | | | | | | | | |
| 2Q10 | 442.83 | 4/1/2010 | 40.21 | 40.67 | 402.16 | 402.62 | 0.46 | 402.53 | 398.16 - 373.16 (44.67 - 69.67) | *Product confirmed on interface probe. |
| 3Q10 | 442.83 | 7/1/2010 | 39.42 | 39.86 | 402.97 | 403.41 | 0.44 | 403.32 | | *Product confirmed on interface probe. |
| 4Q10 | 442.83 | 11/11/2010 | 38.20 | 38.69 | 404.14 | 404.63 | 0.49 | 404.53 | | * |
| 1Q11 | 442.83 | 1/13/2011 | 37.48 | 37.90 | 404.93 | 405.35 | 0.42 | 405.27 | | * |
| 2Q11 | 442.83 | 4/25/2011 | 39.20 | 39.22 | 403.61 | 403.63 | 0.02 | 403.62 | | * |
| 3Q11 | 442.83 | 7/5/2011 | 36.42 | 36.43 | 406.40 | 406.41 | 0.01 | 406.41 | | * |
| | 442.83 | 9/19/2011 | NE | 35.98 | NA | NA | NA | 406.85 | | * |
| 4Q11 | 442.83 | 10/6/2011 | NE | 36.25 | NA | NA | NA | 406.58 | | * |
| 1Q12 | 442.83 | 1/3/2012 | NE | 38.62 | NA | NA | NA | 404.21 | | * |
| 2Q12 | 442.83 | 4/3/2012 | NE | 39.80 | NA | NA | NA | 403.03 | | * |
| 3Q12 | 442.83 | 7/3/2012 | NE | 39.83 | NA | NA | NA | 403.00 | | * |
| 4Q12 | 442.83 | 10/1/2012 | NE | 41.67 | NA | NA | NA | 401.16 | | * |
| 1Q13 | 442.83 | 1/4/2013 | NE | 42.72 | NA | NA | NA | 400.11 | | * |
| **P-71** | | | | | | | | | | |
| 2Q10 | 444.83 | 4/1/2010 | NE | 41.31 | NA | NA | NA | 403.52 | 402.22 - 377.22 (42.61 - 67.61) | * |
| 3Q10 | 444.83 | 7/1/2010 | NE | 40.20 | NA | NA | NA | 404.63 | | * |
| 4Q10 | 444.83 | 11/11/2010 | NE | 38.92 | NA | NA | NA | 405.91 | | * |
| 1Q11 | 444.83 | 1/13/2011 | NE | 38.32 | NA | NA | NA | 406.51 | | * |
| 2Q11 | 444.83 | 4/25/2011 | NE | 39.52 | NA | NA | NA | 405.31 | | * |
| 3Q11 | 444.83 | 7/5/2011 | NE | 37.91 | NA | NA | NA | 406.92 | | * |
| | 444.83 | 9/19/2011 | NE | 37.71 | NA | NA | NA | 407.12 | | * |
| 4Q11 | 444.83 | 10/6/2011 | NE | 47.31 | NA | NA | NA | 397.52 | | |
| 1Q12 | 444.83 | 1/3/2012 | NE | 38.91 | NA | NA | NA | 405.92 | | * |
| 2Q12 | 444.83 | 4/3/2012 | NE | 40.34 | NA | NA | NA | 404.49 | | * |
| 3Q12 | 444.83 | 7/3/2012 | NE | 40.90 | NA | NA | NA | 403.93 | | * |
| 4Q12 | 444.83 | 10/2/2012 | 42.69 | 42.75 | 402.08 | 402.14 | 0.06 | 402.13 | | |
| 1Q13 | 444.83 | 1/4/2013 | NE | 43.83 | NA | NA | NA | 401.00 | | |
| **P-72** | | | | | | | | | | |
| 2Q10 | 444.43 | 4/1/2010 | 40.36 | 40.39 | 404.04 | 404.07 | 0.03 | 404.06 | 398.66 - 373.66 (45.77 - 70.77) | *Product confirmed on interface probe. |
| 3Q10 | 444.43 | 7/1/2010 | NM | NM | NA | NA | NA | NA | | Tank yard flooded, unable to access. |
| 4Q10 | 444.43 | 11/11/2010 | 38.01 | 38.06 | 406.37 | 406.42 | 0.05 | 406.41 | | * |
| 1Q11 | 444.43 | 1/13/2011 | 37.65 | 37.66 | 406.77 | 406.78 | 0.01 | 406.78 | | * |
| 2Q11 | 444.43 | 4/25/2011 | 38.78 | 38.80 | 405.63 | 405.65 | 0.02 | 405.65 | | * |
| 3Q11 | 444.43 | 7/5/2011 | 37.02 | 37.03 | 407.40 | 407.41 | 0.01 | 407.41 | | * |
| | 444.43 | 9/19/2011 | NE | 36.60 | NA | NA | NA | 407.83 | | * |
| 4Q11 | 444.43 | 10/6/2011 | NE | 36.82 | NA | NA | NA | 407.61 | | * |
| 1Q12 | 444.43 | 1/3/2012 | NE | 38.43 | NA | NA | NA | 406.00 | | * |
| 2Q12 | 444.43 | 4/3/2012 | NE | 39.58 | NA | NA | NA | 404.85 | | * |
| 3Q12 | 444.43 | 7/3/2012 | NE | 40.30 | NA | NA | NA | 404.13 | | * |
| 4Q12 | 444.43 | 10/1/2012 | NE | 41.88 | NA | NA | NA | 402.55 | | * |
| 1Q13 | 444.43 | 1/4/2013 | NE | 43.27 | NA | NA | NA | 401.16 | | * |

**TABLE 1**
**CUMULATIVE GROUNDWATER MONITORING WELL GAUGING RESULTS**

| WELL ID | TOP OF CASING (elev.[1]) | DATE GAUGED | DEPTH TO PRODUCT (ft btoc) | DEPTH TO WATER (ft btoc) | WATER-PRODUCT INTERFACE (elev.[1]) | PRODUCT (elev.[1]) | PRODUCT THICKNESS (ft) | CORRECTED WATER LEVEL[2] (elev.[1]) | SCREENED INTERVAL (elev.[1]) (ft btoc) | COMMENTS |
|---|---|---|---|---|---|---|---|---|---|---|
| **P-73** | | | | | | | | | | |
| 2Q10 | 443.76 | 4/1/2010 | NE | 40.15 | NA | NA | NA | 403.61 | 402.17 - 377.17 (41.60 - 66.60) | * |
| 3Q10 | 443.76 | 7/1/2010 | 40.24 | 41.26 | 402.50 | 403.52 | 1.02 | 403.32 | | *Product confirmed on interface probe. |
| 4Q10 | 443.76 | 11/11/2010 | NE | 38.10 | NA | NA | NA | 405.66 | | * |
| 1Q11 | 443.76 | 1/13/2011 | NE | 38.10 | NA | NA | NA | 405.66 | | * |
| 2Q11 | 443.76 | 4/25/2011 | NE | 39.13 | NA | NA | NA | 404.63 | | * |
| 3Q11 | 443.76 | 7/5/2011 | NE | 36.88 | NA | NA | NA | 406.88 | | * |
| | 443.76 | 9/19/2011 | NE | 36.38 | NA | NA | NA | 407.38 | | * |
| 4Q11 | 443.76 | 10/6/2011 | NE | 36.68 | NA | NA | NA | 407.08 | | * |
| 1Q12 | 443.76 | 1/4/2012 | NE | 38.68 | NA | NA | NA | 405.08 | | * |
| 2Q12 | 443.76 | 4/3/2012 | NE | 40.03 | NA | NA | NA | 403.73 | | * |
| 3Q12 | 443.76 | 7/5/2012 | NE | 40.28 | NA | NA | NA | 403.48 | | * |
| 4Q12 | 443.76 | 10/2/2012 | NE | 42.02 | NA | NA | NA | 401.74 | | |
| 1Q13 | 443.76 | 1/4/2013 | NE | 43.04 | NA | NA | NA | 400.72 | | |
| **P-74** | | | | | | | | | | |
| 2Q10 | 442.63 | 4/1/2010 | NE | 39.07 | NA | NA | NA | 403.56 | 398.20 - 373.20 (44.43 - 69.43) | * |
| 3Q10 | 442.63 | 7/1/2010 | NE | 38.88 | NA | NA | NA | 403.75 | | * |
| 4Q10 | 442.63 | 11/12/2010 | NE | 38.29 | NA | NA | NA | 404.34 | | * |
| 1Q11 | 442.63 | 1/13/2011 | NE | 37.94 | NA | NA | NA | 404.69 | | * |
| 2Q11 | 442.63 | 4/25/2011 | NE | 39.18 | NA | NA | NA | 403.45 | | * |
| 3Q11 | 442.63 | 7/5/2011 | NE | 36.51 | NA | NA | NA | 406.12 | | * |
| | 442.63 | 9/19/2011 | NE | 35.86 | NA | NA | NA | 406.77 | | * |
| 4Q11 | 442.63 | 10/6/2011 | NE | 36.26 | NA | NA | NA | 406.37 | | * |
| 1Q12 | 442.63 | 1/4/2012 | NE | 38.56 | NA | NA | NA | 404.07 | | * |
| 2Q12 | 442.63 | 4/3/2012 | NE | 39.94 | NA | NA | NA | 402.69 | | * |
| 3Q12 | 442.63 | 7/5/2012 | NE | 40.00 | NA | NA | NA | 402.63 | | * |
| 4Q12 | 442.63 | 10/2/2012 | NE | 41.78 | NA | NA | NA | 400.85 | | * |
| 1Q13 | 442.63 | 1/4/2013 | NE | 42.55 | NA | NA | NA | 400.08 | | * |
| **P-75** | | | | | | | | | | |
| 2Q10 | 446.32 | 4/1/2010 | 42.01 | 42.30 | 404.02 | 404.31 | 0.29 | 404.26 | 403.19 - 378.19 (43.13 - 68.13) | *Product confirmed on interface probe. |
| 3Q10 | 446.32 | 7/1/2010 | 40.58 | 40.87 | 405.45 | 405.74 | 0.29 | 405.69 | | *Product confirmed on interface probe. |
| 4Q10 | 446.32 | 11/11/2010 | 39.72 | 40.00 | 406.32 | 406.60 | 0.28 | 406.55 | | * |
| 1Q11 | 446.32 | 1/13/2011 | 40.04 | 40.43 | 405.89 | 406.28 | 0.39 | 406.21 | | * |
| 2Q11 | 446.32 | 4/25/2011 | 40.81 | 40.83 | 405.49 | 405.51 | 0.02 | 405.51 | | * |
| 3Q11 | 446.32 | 7/5/2011 | 38.57 | 38.59 | 407.73 | 407.75 | 0.02 | 407.75 | | * |
| | 446.32 | 9/19/2011 | NE | 38.31 | NA | NA | NA | 408.01 | | * |
| 4Q11 | 446.32 | 10/5/2011 | 38.52 | 38.53 | 407.79 | 407.80 | 0.01 | 407.80 | | * |
| 1Q12 | 446.32 | 1/4/2012 | NE | 40.48 | NA | NA | NA | 405.84 | | * |
| 2Q12 | 446.32 | 4/4/2012 | NE | 41.62 | NA | NA | NA | 404.70 | | * |
| 3Q12 | 446.32 | 7/2/2012 | 42.14 | 42.14 | 404.18 | 404.18 | 0.00 | 404.18 | | * |
| 4Q12 | 446.32 | 10/2/2012 | 44.10 | 44.20 | 402.12 | 402.22 | 0.10 | 402.20 | | |
| 1Q13 | 446.32 | 1/2/2013 | NE | 44.87 | NA | NA | NA | 401.45 | | |
| **P-82A** | | | | | | | | | | |
| 2Q10 | 434.69 | 4/1/2010 | NE | 26.62 | NA | NA | NA | 408.07 | 401.48 - 386.48 (33.21 - 48.21) | * |
| 3Q10 | 434.69 | 7/1/2010 | NE | 25.00 | NA | NA | NA | 409.69 | | * |
| 4Q10 | 434.69 | 10/1/2010 | NE | 24.07 | NA | NA | NA | 410.62 | | * |
| 1Q11 | 434.69 | 1/13/2011 | NE | 25.29 | NA | NA | NA | 409.40 | | * |
| 2Q11 | 434.69 | 4/1/2011 | NE | 25.12 | NA | NA | NA | 409.57 | | * |
| 3Q11 | 434.69 | 7/5/2011 | NE | 23.01 | NA | NA | NA | 411.68 | | * |
| | 434.69 | 9/19/2011 | NE | 23.62 | NA | NA | NA | 411.07 | | * |
| 4Q11 | 434.69 | 10/5/2011 | NE | 24.00 | NA | NA | NA | 410.69 | | * |
| 1Q12 | 434.69 | 1/3/2012 | NE | 25.50 | NA | NA | NA | 409.19 | | * |
| 2Q12 | 434.69 | 4/2/2012 | NE | 26.82 | NA | NA | NA | 407.87 | | * |
| 3Q12 | 434.69 | 7/2/2012 | NE | 27.34 | NA | NA | NA | 407.35 | | * |
| 4Q12 | 434.69 | 10/2/2012 | NE | 29.07 | NA | NA | NA | 405.62 | | * |
| 1Q13 | 434.69 | 1/3/2013 | NE | 30.09 | NA | NA | NA | 404.60 | | * |
| **P-82B** | | | | | | | | | | |
| 2Q10 | 434.44 | 4/1/2010 | NE | 26.33 | NA | NA | NA | 408.11 | 370.84 - 368.84 (63.60 - 65.60) | * |
| 3Q10 | 434.44 | 7/1/2010 | NE | 24.71 | NA | NA | NA | 409.73 | | * |
| 4Q10 | 434.44 | 10/1/2010 | NE | 23.78 | NA | NA | NA | 410.66 | | * |
| 1Q11 | 434.44 | 1/13/2011 | NE | 25.01 | NA | NA | NA | 409.43 | | * |
| 2Q11 | 434.44 | 4/1/2011 | NE | 24.85 | NA | NA | NA | 409.59 | | * |
| 3Q11 | 434.44 | 7/5/2011 | NE | 22.71 | NA | NA | NA | 411.73 | | * |
| | 434.44 | 9/19/2011 | NE | 23.36 | NA | NA | NA | 411.08 | | * |
| 4Q11 | 434.44 | 10/5/2011 | NE | 23.73 | NA | NA | NA | 410.71 | | * |
| 1Q12 | 434.44 | 1/3/2012 | NE | 25.21 | NA | NA | NA | 409.23 | | * |
| 2Q12 | 434.44 | 4/2/2012 | NE | 26.55 | NA | NA | NA | 407.89 | | * |
| 3Q12 | 434.44 | 7/2/2012 | NE | 27.07 | NA | NA | NA | 407.37 | | * |
| 4Q12 | 434.44 | 10/2/2012 | NE | 28.81 | NA | NA | NA | 405.63 | | * |
| 1Q13 | 434.44 | 1/3/2013 | NE | 29.82 | NA | NA | NA | 404.62 | | * |
| **P-82C** | | | | | | | | | | |
| 2Q10 | 434.16 | 4/1/2010 | NE | 26.05 | NA | NA | NA | 408.11 | 351.39 - 349.39 (82.77 - 84.77) | * |
| 3Q10 | 434.16 | 7/1/2010 | NE | 25.47 | NA | NA | NA | 408.69 | | * |
| 4Q10 | 434.16 | 10/1/2010 | NE | 23.49 | NA | NA | NA | 410.67 | | * |
| 1Q11 | 434.16 | 1/13/2011 | NE | 24.73 | NA | NA | NA | 409.43 | | * |
| 2Q11 | 434.16 | 4/1/2011 | NE | 24.87 | NA | NA | NA | 409.29 | | * |
| 3Q11 | 434.16 | 7/5/2011 | NE | 22.75 | NA | NA | NA | 411.41 | | * |
| | 434.16 | 9/19/2011 | NE | 23.40 | NA | NA | NA | 410.76 | | * |
| 4Q11 | 434.16 | 10/5/2011 | NE | 23.81 | NA | NA | NA | 410.35 | | * |
| 1Q12 | 434.16 | 1/3/2012 | NE | 25.26 | NA | NA | NA | 408.90 | | * |
| 2Q12 | 434.16 | 4/2/2012 | NE | 26.61 | NA | NA | NA | 407.55 | | * |
| 3Q12 | 434.16 | 7/2/2012 | NE | 27.11 | NA | NA | NA | 407.05 | | * |
| 4Q12 | 434.16 | 10/2/2012 | NE | 28.85 | NA | NA | NA | 405.31 | | * |
| 1Q13 | 434.16 | 1/3/2013 | NE | 29.86 | NA | NA | NA | 404.30 | | * |

**TABLE 1**
**CUMULATIVE GROUNDWATER MONITORING WELL GAUGING RESULTS**

| WELL ID | TOP OF CASING (elev.[1]) | DATE GAUGED | DEPTH TO PRODUCT (ft btoc) | DEPTH TO WATER (ft btoc) | WATER-PRODUCT INTERFACE (elev.[1]) | PRODUCT (elev.[1]) | PRODUCT THICKNESS (ft) | CORRECTED WATER LEVEL[2] (elev.[1]) | SCREENED INTERVAL (elev.[1]) (ft btoc) | COMMENTS |
|---|---|---|---|---|---|---|---|---|---|---|
| **P-82D** | | | | | | | | | | |
| 2Q10 | 434.85 | 4/1/2010 | NE | 26.82 | NA | NA | NA | 408.03 | 323.43 - 321.43 (111.42 - 113.42) | * |
| 3Q10 | 434.85 | 7/1/2010 | NE | 25.20 | NA | NA | NA | 409.65 | | * |
| 4Q10 | 434.85 | 10/1/2010 | NE | 24.26 | NA | NA | NA | 410.59 | | * |
| 1Q11 | 434.85 | 1/13/2011 | NE | 25.48 | NA | NA | NA | 409.37 | | * |
| 2Q11 | 434.85 | 4/1/2011 | NE | 25.63 | NA | NA | NA | 409.22 | | * |
| 3Q11 | 434.85 | 7/5/2011 | NE | 23.54 | NA | NA | NA | 411.31 | | * |
| | 434.85 | 9/19/2011 | NE | 24.16 | NA | NA | NA | 410.69 | | * |
| 4Q11 | 434.85 | 10/5/2011 | NE | 24.56 | NA | NA | NA | 410.29 | | * |
| 1Q12 | 434.85 | 1/3/2012 | NE | 26.06 | NA | NA | NA | 408.79 | | * |
| 2Q12 | 434.85 | 4/2/2012 | NE | 27.37 | NA | NA | NA | 407.48 | | * |
| 3Q12 | 434.85 | 7/2/2012 | NE | 27.91 | NA | NA | NA | 406.94 | | * |
| 4Q12 | 434.85 | 10/2/2012 | NE | 29.62 | NA | NA | NA | 405.23 | | * |
| 1Q13 | 434.85 | 1/3/2013 | NE | 30.65 | NA | NA | NA | 404.20 | | * |
| **P-83A** | | | | | | | | | | |
| 2Q10 | 445.23 | 4/1/2010 | NE | 42.05 | NA | NA | NA | 403.18 | 398.58 - 383.58 (46.65 - 61.65) | * |
| 3Q10 | 445.23 | 7/1/2010 | NE | 40.64 | NA | NA | NA | 404.59 | | * |
| 4Q10 | 445.23 | 10/1/2010 | NE | 38.82 | NA | NA | NA | 406.41 | | * |
| 1Q11 | 445.23 | 1/13/2011 | NE | 37.93 | NA | NA | NA | 407.30 | | * |
| 2Q11 | 445.23 | 4/1/2011 | NE | 38.42 | NA | NA | NA | 406.81 | | * |
| 3Q11 | 445.23 | 7/5/2011 | NE | 36.25 | NA | NA | NA | 408.98 | | * |
| | 445.23 | 9/19/2011 | NE | 37.21 | NA | NA | NA | 408.02 | | * |
| 4Q11 | 445.23 | 10/6/2011 | NE | 37.41 | NA | NA | NA | 407.82 | | * |
| 1Q12 | 445.23 | 1/3/2012 | NE | 38.31 | NA | NA | NA | 406.92 | | * |
| 2Q12 | 445.23 | 4/2/2012 | NE | 39.85 | NA | NA | NA | 405.38 | | * |
| 3Q12 | 445.23 | 7/2/2012 | NE | 40.50 | NA | NA | NA | 404.73 | | * |
| 4Q12 | 445.23 | 10/1/2012 | NE | 42.29 | NA | NA | NA | 402.94 | | * |
| 1Q13 | 445.23 | 1/3/2013 | NE | 43.85 | NA | NA | NA | 401.38 | | * |
| **P-83B** | | | | | | | | | | |
| 2Q10 | 445.47 | 4/1/2010 | NE | 42.31 | NA | NA | NA | 403.16 | 375.82 - 373.82 (69.65 - 71.65) | * |
| 3Q10 | 445.47 | 7/1/2010 | NE | 40.91 | NA | NA | NA | 404.56 | | * |
| 4Q10 | 445.47 | 10/1/2010 | NE | 39.08 | NA | NA | NA | 406.39 | | * |
| 1Q11 | 445.47 | 1/13/2011 | NE | 38.20 | NA | NA | NA | 407.27 | | * |
| 2Q11 | 445.47 | 4/1/2011 | NE | 38.69 | NA | NA | NA | 406.78 | | * |
| 3Q11 | 445.47 | 7/5/2011 | NE | 36.57 | NA | NA | NA | 408.90 | | * |
| | 445.47 | 9/19/2011 | NE | 37.48 | NA | NA | NA | 407.99 | | * |
| 4Q11 | 445.47 | 10/6/2011 | NE | 37.68 | NA | NA | NA | 407.79 | | * |
| 1Q12 | 445.47 | 1/3/2012 | NE | 38.58 | NA | NA | NA | 406.89 | | * |
| 2Q12 | 445.47 | 4/2/2012 | NE | 40.13 | NA | NA | NA | 405.34 | | * |
| 3Q12 | 445.47 | 7/2/2012 | NE | 40.85 | NA | NA | NA | 404.62 | | * |
| 4Q12 | 445.47 | 10/1/2012 | NE | 42.57 | NA | NA | NA | 402.90 | | * |
| 1Q13 | 445.47 | 1/3/2013 | NE | 44.13 | NA | NA | NA | 401.34 | | * |
| **P-83C** | | | | | | | | | | |
| 2Q10 | 445.64 | 4/1/2010 | NE | 42.46 | NA | NA | NA | 403.18 | 353.25 - 351.25 (92.39 - 94.39) | * |
| 3Q10 | 445.64 | 7/1/2010 | NE | 41.08 | NA | NA | NA | 404.56 | | * |
| 4Q10 | 445.64 | 10/1/2010 | NE | 39.24 | NA | NA | NA | 406.40 | | * |
| 1Q11 | 445.64 | 1/13/2011 | NE | 38.68 | NA | NA | NA | 406.96 | | * |
| 2Q11 | 445.64 | 4/1/2011 | NE | 38.85 | NA | NA | NA | 406.79 | | * |
| 3Q11 | 445.64 | 7/5/2011 | NE | 37.02 | NA | NA | NA | 408.62 | | * |
| | 445.64 | 9/19/2011 | NE | 37.94 | NA | NA | NA | 407.70 | | * |
| 4Q11 | 445.64 | 10/6/2011 | NE | 38.15 | NA | NA | NA | 407.49 | | * |
| 1Q12 | 445.64 | 1/3/2012 | NE | 39.05 | NA | NA | NA | 406.59 | | * |
| 2Q12 | 445.64 | 4/2/2012 | NE | 40.61 | NA | NA | NA | 405.03 | | * |
| 3Q12 | 445.64 | 7/2/2012 | NE | 40.96 | NA | NA | NA | 404.68 | | * |
| 4Q12 | 445.64 | 10/1/2012 | NE | 43.04 | NA | NA | NA | 402.60 | | * |
| 1Q13 | 445.64 | 1/3/2013 | NE | 44.59 | NA | NA | NA | 401.05 | | * |
| **P-83D** | | | | | | | | | | |
| 2Q10 | 445.55 | 4/1/2010 | NE | 42.40 | NA | NA | NA | 403.15 | 311.84 - 309.84 (133.71 - 135.71) | * |
| 3Q10 | 445.55 | 7/1/2010 | NE | 41.00 | NA | NA | NA | 404.55 | | * |
| 4Q10 | 445.55 | 10/1/2010 | NE | 39.11 | NA | NA | NA | 406.44 | | * |
| 1Q11 | 445.55 | 1/13/2011 | NE | 38.59 | NA | NA | NA | 406.96 | | * |
| 2Q11 | 445.55 | 4/1/2011 | NE | 38.31 | NA | NA | NA | 407.24 | | * |
| 3Q11 | 445.55 | 7/5/2011 | NE | 36.98 | NA | NA | NA | 408.57 | | * |
| | 445.55 | 9/19/2011 | NE | 37.87 | NA | NA | NA | 407.68 | | * |
| 4Q11 | 445.55 | 10/6/2011 | NE | 38.07 | NA | NA | NA | 407.48 | | * |
| 1Q12 | 445.55 | 1/3/2012 | NE | 39.01 | NA | NA | NA | 406.54 | | * |
| 2Q12 | 445.55 | 4/2/2012 | NE | 40.53 | NA | NA | NA | 405.02 | | * |
| 3Q12 | 445.55 | 7/2/2012 | NE | 40.12 | NA | NA | NA | 405.43 | | * |
| 4Q12 | 445.55 | 10/1/2012 | NE | 42.98 | NA | NA | NA | 402.57 | | * |
| 1Q13 | 445.55 | 1/3/2013 | NE | 44.54 | NA | NA | NA | 401.01 | | * |
| **P-84A** | | | | | | | | | | |
| 2Q10 | 446.39 | 4/1/2010 | NE | 42.91 | NA | NA | NA | 403.48 | 392.57 - 377.57 (53.82 - 68.82) | * |
| 3Q10 | 446.39 | 7/1/2010 | NE | 41.55 | NA | NA | NA | 404.84 | | * |
| 4Q10 | 446.39 | 11/11/2010 | NE | 39.95 | NA | NA | NA | 406.44 | | * |
| 1Q11 | 446.39 | 1/13/2011 | NE | 39.55 | NA | NA | NA | 406.84 | | * |
| 2Q11 | 446.39 | 4/25/2011 | NE | 40.11 | NA | NA | NA | 406.28 | | * |
| 3Q11 | 446.39 | 7/5/2011 | NE | 38.58 | NA | NA | NA | 407.81 | | * |
| 4Q11 | 446.39 | 10/6/2011 | NE | 34.36 | NA | NA | NA | 412.03 | | * |
| 1Q12 | 446.39 | 1/5/2012 | NE | 39.49 | NA | NA | NA | 406.90 | | * |
| 2Q12 | 446.39 | 4/3/2012 | NE | 40.70 | NA | NA | NA | 405.69 | | * |
| 3Q12 | 446.39 | 7/5/2012 | NE | 41.40 | NA | NA | NA | 404.99 | | * |
| 4Q12 | 446.39 | 10/2/2012 | NE | 43.10 | NA | NA | NA | 403.29 | | * |
| 1Q13 | 446.39 | 1/4/2013 | NE | 44.20 | NA | NA | NA | 402.19 | | * |

**TABLE 1**
**CUMULATIVE GROUNDWATER MONITORING WELL GAUGING RESULTS**

| WELL ID | TOP OF CASING (elev.[1]) | DATE GAUGED | DEPTH TO PRODUCT (ft btoc) | DEPTH TO WATER (ft btoc) | WATER-PRODUCT INTERFACE (elev.[1]) | PRODUCT (elev.[1]) | PRODUCT THICKNESS (ft) | CORRECTED WATER LEVEL[2] (elev.[1]) | SCREENED INTERVAL (elev.[1]) (ft btoc) | COMMENTS |
|---|---|---|---|---|---|---|---|---|---|---|
| **P-84B** | | | | | | | | | | |
| 2Q10 | 446.10 | 4/1/2010 | NE | 42.61 | NA | NA | NA | 403.49 | 372.60 - 370.60 (73.50 - 75.50) | * |
| 3Q10 | 446.10 | 7/1/2010 | NE | 41.28 | NA | NA | NA | 404.82 | | * |
| 4Q10 | 446.10 | 11/11/2010 | NE | 39.67 | NA | NA | NA | 406.43 | | * |
| 1Q11 | 446.10 | 1/13/2011 | NE | 39.27 | NA | NA | NA | 406.83 | | * |
| 2Q11 | 446.10 | 4/25/2011 | NE | 39.85 | NA | NA | NA | 406.25 | | * |
| 3Q11 | 446.10 | 7/5/2011 | NE | 38.32 | NA | NA | NA | 407.78 | | * |
| 4Q11 | 446.10 | 10/6/2011 | NE | 38.09 | NA | NA | NA | 408.01 | | * |
| 1Q12 | 446.10 | 1/5/2012 | NE | 39.23 | NA | NA | NA | 406.87 | | * |
| 2Q12 | 446.10 | 4/3/2012 | NE | 40.43 | NA | NA | NA | 405.67 | | * |
| 3Q12 | 446.10 | 7/5/2012 | NE | 41.43 | NA | NA | NA | 404.67 | | * |
| 4Q12 | 446.10 | 10/2/2012 | NE | 42.84 | NA | NA | NA | 403.26 | | * |
| 1Q13 | 446.10 | 1/4/2013 | NE | 43.92 | NA | NA | NA | 402.18 | | * |
| **P-84C** | | | | | | | | | | |
| 2Q10 | 446.13 | 4/1/2010 | NE | 42.65 | NA | NA | NA | 403.48 | 352.08 - 350.08 (94.05 - 96.05) | * |
| 3Q10 | 446.13 | 7/1/2010 | NE | 41.32 | NA | NA | NA | 404.81 | | * |
| 4Q10 | 446.13 | 11/11/2010 | NE | 39.68 | NA | NA | NA | 406.45 | | * |
| 1Q11 | 446.13 | 1/13/2011 | NE | 39.29 | NA | NA | NA | 406.84 | | * |
| 2Q11 | 446.13 | 4/25/2011 | NE | 39.86 | NA | NA | NA | 406.27 | | * |
| 3Q11 | 446.13 | 7/5/2011 | NE | 38.64 | NA | NA | NA | 407.49 | | * |
| 4Q11 | 446.13 | 10/6/2011 | NE | 38.41 | NA | NA | NA | 407.72 | | * |
| 1Q12 | 446.13 | 1/5/2012 | NE | 39.53 | NA | NA | NA | 406.60 | | * |
| 2Q12 | 446.13 | 4/3/2012 | NE | 40.75 | NA | NA | NA | 405.38 | | * |
| 3Q12 | 446.13 | 7/5/2012 | NE | 41.45 | NA | NA | NA | 404.68 | | * |
| 4Q12 | 446.13 | 10/2/2012 | NE | 43.15 | NA | NA | NA | 402.98 | | * |
| 1Q13 | 446.13 | 1/4/2013 | NE | 44.39 | NA | NA | NA | 401.74 | | * |
| **P-84D** | | | | | | | | | | |
| 2Q10 | 446.14 | 4/1/2010 | NE | 42.63 | NA | NA | NA | 403.51 | 324.99 - 322.99 (121.15 - 123.15) | * |
| 3Q10 | 446.14 | 7/1/2010 | NE | 41.34 | NA | NA | NA | 404.80 | | * |
| 4Q10 | 446.14 | 11/11/2010 | NE | 39.69 | NA | NA | NA | 406.45 | | * |
| 1Q11 | 446.14 | 1/13/2011 | NE | 39.31 | NA | NA | NA | 406.83 | | * |
| 2Q11 | 446.14 | 4/25/2011 | NE | 39.87 | NA | NA | NA | 406.27 | | * |
| 3Q11 | 446.14 | 7/5/2011 | NE | 38.68 | NA | NA | NA | 407.46 | | * |
| 4Q11 | 446.14 | 10/6/2011 | NE | 38.43 | NA | NA | NA | 407.71 | | * |
| 1Q12 | 446.14 | 1/5/2012 | NE | 39.55 | NA | NA | NA | 406.59 | | * |
| 2Q12 | 446.14 | 4/3/2012 | NE | 40.77 | NA | NA | NA | 405.37 | | * |
| 3Q12 | 446.14 | 7/5/2012 | NE | 41.46 | NA | NA | NA | 404.68 | | * |
| 4Q12 | 446.14 | 10/2/2012 | NE | 43.18 | NA | NA | NA | 402.96 | | * |
| 1Q13 | 446.14 | 1/4/2013 | NE | 44.41 | NA | NA | NA | 401.73 | | * |
| **P-88A** | | | | | | | | | | |
| 2Q10 | 443.12 | 4/1/2010 | NE | 33.22 | NA | NA | NA | 409.90 | 404.72 - 389.72 (38.40 - 53.40) | * |
| 3Q10 | 443.12 | 7/1/2010 | NE | 31.80 | NA | NA | NA | 411.32 | | * |
| 4Q10 | 443.12 | 10/1/2010 | NE | 30.65 | NA | NA | NA | 412.47 | | * |
| 1Q11 | 443.12 | 1/14/2011 | NE | 31.16 | NA | NA | NA | 411.96 | | * |
| 2Q11 | 443.12 | 4/1/2011 | NE | 31.36 | NA | NA | NA | 411.76 | | * |
| 3Q11 | 443.12 | 7/5/2011 | NE | 29.78 | NA | NA | NA | 413.34 | | * |
| | 443.12 | 9/19/2011 | NE | 29.72 | NA | NA | NA | 413.40 | | * |
| 4Q11 | 443.12 | 10/5/2011 | NE | 29.92 | NA | NA | NA | 413.20 | | * |
| 1Q12 | 443.12 | 1/4/2012 | NE | 31.18 | NA | NA | NA | 411.94 | | * |
| 2Q12 | 443.12 | 4/3/2012 | NE | 32.55 | NA | NA | NA | 410.57 | | * |
| 3Q12 | 443.12 | 7/2/2012 | NE | 32.97 | NA | NA | NA | 410.15 | | * |
| 4Q12 | 443.12 | 10/2/2012 | NE | 34.58 | NA | NA | NA | 408.54 | | * |
| 1Q13 | 443.12 | 1/2/2013 | NE | 35.80 | NA | NA | NA | 407.32 | | * |
| **P-88B** | | | | | | | | | | |
| 2Q10 | 443.17 | 4/1/2010 | NE | 33.28 | NA | NA | NA | 409.89 | 370.62 - 368.62 (72.55 - 74.55) | * |
| 3Q10 | 443.17 | 7/1/2010 | NE | 31.86 | NA | NA | NA | 411.31 | | * |
| 4Q10 | 443.17 | 10/1/2010 | NE | 30.87 | NA | NA | NA | 412.30 | | * |
| 1Q11 | 443.17 | 1/14/2011 | NE | 31.37 | NA | NA | NA | 411.80 | | * |
| 2Q11 | 443.17 | 4/1/2011 | NE | 31.42 | NA | NA | NA | 411.75 | | * |
| 3Q11 | 443.17 | 7/5/2011 | NE | 29.71 | NA | NA | NA | 413.46 | | * |
| | 443.17 | 9/19/2011 | NE | 29.64 | NA | NA | NA | 413.53 | | * |
| 4Q11 | 443.17 | 10/5/2011 | NE | 29.86 | NA | NA | NA | 413.31 | | * |
| 1Q12 | 443.17 | 1/4/2012 | NE | 31.16 | NA | NA | NA | 412.01 | | * |
| 2Q12 | 443.17 | 4/3/2012 | NE | 32.50 | NA | NA | NA | 410.67 | | * |
| 3Q12 | 443.17 | 7/2/2012 | NE | 33.01 | NA | NA | NA | 410.16 | | * |
| 4Q12 | 443.17 | 10/2/2012 | NE | 34.56 | NA | NA | NA | 408.61 | | * |
| 1Q13 | 443.17 | 1/2/2013 | NE | 35.82 | NA | NA | NA | 407.35 | | * |
| **P-88C** | | | | | | | | | | |
| 2Q10 | 443.16 | 4/1/2010 | NE | 33.25 | NA | NA | NA | 409.91 | 350.86 - 348.86 (92.30 - 94.30) | * |
| 3Q10 | 443.16 | 7/1/2010 | NE | 31.85 | NA | NA | NA | 411.31 | | * |
| 4Q10 | 443.16 | 10/1/2010 | NE | 30.67 | NA | NA | NA | 412.49 | | * |
| 1Q11 | 443.16 | 1/14/2011 | NE | 31.17 | NA | NA | NA | 411.99 | | * |
| 2Q11 | 443.16 | 4/1/2011 | NE | 31.38 | NA | NA | NA | 411.78 | | * |
| 3Q11 | 443.16 | 7/5/2011 | NE | 30.02 | NA | NA | NA | 413.14 | | * |
| | 443.16 | 9/19/2011 | NE | 29.95 | NA | NA | NA | 413.21 | | * |
| 4Q11 | 443.16 | 10/5/2011 | NE | 30.14 | NA | NA | NA | 413.02 | | * |
| 1Q12 | 443.16 | 1/4/2012 | NE | 31.44 | NA | NA | NA | 411.72 | | * |
| 2Q12 | 443.16 | 4/3/2012 | NE | 32.78 | NA | NA | NA | 410.38 | | * |
| 3Q12 | 443.16 | 7/2/2012 | NE | 33.15 | NA | NA | NA | 410.01 | | * |
| 4Q12 | 443.16 | 10/2/2012 | NE | 34.83 | NA | NA | NA | 408.33 | | * |
| 1Q13 | 443.16 | 1/2/2013 | NE | 36.10 | NA | NA | NA | 407.06 | | * |

**TABLE 1**
**CUMULATIVE GROUNDWATER MONITORING WELL GAUGING RESULTS**

| WELL ID | TOP OF CASING (elev.[1]) | DATE GAUGED | DEPTH TO PRODUCT (ft btoc) | DEPTH TO WATER (ft btoc) | WATER-PRODUCT INTERFACE (elev.[1]) | PRODUCT (elev.[1]) | PRODUCT THICKNESS (ft) | CORRECTED WATER LEVEL[2] (elev.[1]) | SCREENED INTERVAL (elev.[1]) (ft btoc) | COMMENTS |
|---|---|---|---|---|---|---|---|---|---|---|
| **P-88D** | | | | | | | | | | |
| 2Q10 | 443.23 | 4/1/2010 | NE | 33.33 | NA | NA | NA | 409.90 | 329.53 - 327.53 (113.70 - 115.70) | * |
| 3Q10 | 443.23 | 7/1/2010 | NE | 31.87 | NA | NA | NA | 411.36 | | * |
| 4Q10 | 443.23 | 10/1/2010 | NE | 30.73 | NA | NA | NA | 412.50 | | * |
| 1Q11 | 443.23 | 1/14/2011 | NE | 31.35 | NA | NA | NA | 411.88 | | * |
| 2Q11 | 443.23 | 4/1/2011 | NE | 31.81 | NA | NA | NA | 411.42 | | * |
| 3Q11 | 443.23 | 7/5/2011 | NE | 30.08 | NA | NA | NA | 413.15 | | * |
| | 443.23 | 9/19/2011 | NE | 30.03 | NA | NA | NA | 413.20 | | * |
| 4Q11 | 443.23 | 10/5/2011 | NE | 30.25 | NA | NA | NA | 412.98 | | * |
| 1Q12 | 443.23 | 1/4/2012 | NE | 31.57 | NA | NA | NA | 411.66 | | * |
| 2Q12 | 443.23 | 4/3/2012 | NE | 32.91 | NA | NA | NA | 410.32 | | * |
| 3Q12 | 443.23 | 7/2/2012 | NE | 33.41 | NA | NA | NA | 409.82 | | * |
| 4Q12 | 443.23 | 10/2/2012 | NE | 34.99 | NA | NA | NA | 408.24 | | * |
| 1Q13 | 443.23 | 1/2/2013 | NE | 36.23 | NA | NA | NA | 407.00 | | * |
| **T-37** | | | | | | | | | | |
| 2Q10 | 447.15 | 4/1/2010 | NE | 41.10 | NA | NA | NA | 406.05 | 398.30 - 378.30 (48.86 - 68.86) | * |
| 3Q10 | 447.15 | 7/1/2010 | NE | 39.78 | NA | NA | NA | 407.37 | | * |
| 4Q10 | 447.15 | 10/1/2010 | NE | 38.12 | NA | NA | NA | 409.03 | | * |
| 1Q11 | 447.15 | 1/13/2011 | NE | 37.61 | NA | NA | NA | 409.54 | | * |
| 2Q11 | 447.15 | 4/1/2011 | NE | 37.63 | NA | NA | NA | 409.52 | | * |
| 3Q11 | 447.15 | 7/5/2011 | NE | 35.84 | NA | NA | NA | 411.31 | | * |
| 4Q11 | 447.15 | 10/6/2011 | NE | 36.90 | NA | NA | NA | 410.25 | | * |
| 1Q12 | 447.15 | 1/3/2012 | NE | 37.95 | NA | NA | NA | 409.20 | | * |
| 2Q12 | 447.15 | 4/2/2012 | NE | 39.12 | NA | NA | NA | 408.03 | | * |
| 3Q12 | 447.15 | 7/2/2012 | NE | 39.91 | NA | NA | NA | 407.24 | | * |
| 4Q12 | 447.15 | 10/1/2012 | NE | 41.44 | NA | NA | NA | 405.71 | | * |
| 1Q13 | 447.15 | 1/3/2013 | NE | 43.07 | NA | NA | NA | 404.08 | | * |
| **P-89B** | | | | | | | | | | |
| 2Q10 | 447.35 | 4/1/2010 | NE | 41.29 | NA | NA | NA | 406.06 | 369.99 - 367.99 (77.36 - 79.36) | * |
| 3Q10 | 447.35 | 7/1/2010 | NE | 39.97 | NA | NA | NA | 407.38 | | * |
| 4Q10 | 447.35 | 10/1/2010 | NE | 38.29 | NA | NA | NA | 409.06 | | * |
| 1Q11 | 447.35 | 1/14/2011 | NE | 37.78 | NA | NA | NA | 409.57 | | * |
| 2Q11 | 447.35 | 4/1/2011 | NE | 37.80 | NA | NA | NA | 409.55 | | * |
| 3Q11 | 447.35 | 7/5/2011 | NE | 35.99 | NA | NA | NA | 411.36 | | * |
| | 447.35 | 9/19/2011 | NE | 36.81 | NA | NA | NA | 410.54 | | * |
| 4Q11 | 447.35 | 10/6/2011 | NE | 37.05 | NA | NA | NA | 410.30 | | * |
| 1Q12 | 447.35 | 1/3/2012 | NE | 38.10 | NA | NA | NA | 409.25 | | * |
| 2Q12 | 447.35 | 4/2/2012 | NE | 39.30 | NA | NA | NA | 408.05 | | * |
| 3Q12 | 447.35 | 7/2/2012 | NE | 40.09 | NA | NA | NA | 407.26 | | * |
| 4Q12 | 447.35 | 10/1/2012 | NE | 41.62 | NA | NA | NA | 405.73 | | * |
| 1Q13 | 447.35 | 1/3/2013 | NE | 43.23 | NA | NA | NA | 404.12 | | * |
| **P-89C** | | | | | | | | | | |
| 2Q10 | 447.68 | 4/1/2010 | NE | 41.63 | NA | NA | NA | 406.05 | 350.05 - 348.05 (97.63 - 99.63) | * |
| 3Q10 | 447.68 | 7/1/2010 | NE | 40.32 | NA | NA | NA | 407.36 | | * |
| 4Q10 | 447.68 | 10/1/2010 | NE | 38.64 | NA | NA | NA | 409.04 | | * |
| 1Q11 | 447.68 | 1/14/2011 | NE | 38.10 | NA | NA | NA | 409.58 | | * |
| 2Q11 | 447.68 | 4/1/2011 | NE | 38.14 | NA | NA | NA | 409.54 | | * |
| 3Q11 | 447.68 | 7/5/2011 | NE | 36.33 | NA | NA | NA | 411.35 | | * |
| | 447.68 | 9/19/2011 | NE | 37.13 | NA | NA | NA | 410.55 | | * |
| 4Q11 | 447.68 | 10/6/2011 | NE | 37.39 | NA | NA | NA | 410.29 | | * |
| 1Q12 | 447.68 | 1/3/2012 | NE | 38.42 | NA | NA | NA | 409.26 | | * |
| 2Q12 | 447.68 | 4/2/2012 | NE | 39.63 | NA | NA | NA | 408.05 | | * |
| 3Q12 | 447.68 | 7/2/2012 | NE | 40.42 | NA | NA | NA | 407.26 | | * |
| 4Q12 | 447.68 | 10/1/2012 | NE | 41.94 | NA | NA | NA | 405.74 | | * |
| 1Q13 | 447.68 | 1/3/2013 | NE | 43.58 | NA | NA | NA | 404.10 | | * |
| **P-89D** | | | | | | | | | | |
| 2Q10 | 447.54 | 4/1/2010 | NE | 41.66 | NA | NA | NA | 405.88 | 307.20 - 305.20 (140.34 - 142.34) | * |
| 3Q10 | 447.54 | 7/1/2010 | NE | 40.30 | NA | NA | NA | 407.24 | | * |
| 4Q10 | 447.54 | 10/1/2010 | NE | 38.61 | NA | NA | NA | 408.93 | | * |
| 1Q11 | 447.54 | 1/14/2011 | NE | 38.11 | NA | NA | NA | 409.43 | | * |
| 2Q11 | 447.54 | 4/1/2011 | NE | 38.12 | NA | NA | NA | 409.42 | | * |
| 3Q11 | 447.54 | 7/5/2011 | NE | 36.23 | NA | NA | NA | 411.31 | | * |
| | 447.54 | 9/19/2011 | NE | 37.04 | NA | NA | NA | 410.50 | | * |
| 4Q11 | 447.54 | 10/6/2011 | NE | 37.35 | NA | NA | NA | 410.19 | | * |
| 1Q12 | 447.54 | 1/3/2012 | NE | 38.47 | NA | NA | NA | 409.07 | | * |
| 2Q12 | 447.54 | 4/2/2012 | NE | 39.56 | NA | NA | NA | 407.98 | | * |
| 3Q12 | 447.54 | 7/2/2012 | NE | 40.36 | NA | NA | NA | 407.18 | | * |
| 4Q12 | 447.54 | 10/1/2012 | NE | 41.94 | NA | NA | NA | 405.60 | | * |
| 1Q13 | 447.54 | 1/3/2013 | NE | 43.52 | NA | NA | NA | 404.02 | | * |
| **P-91A** | | | | | | | | | | |
| 2Q10 | 447.19 | 4/1/2010 | 46.08 | 46.58 | 400.61 | 401.11 | 0.50 | 401.01 | 395.68 - 380.68 (51.52 - 66.52) | *Product confirmed on interface probe. |
| 3Q10 | 447.19 | 7/1/2010 | 44.85 | 45.36 | 401.83 | 402.34 | 0.51 | 402.24 | | *Product confirmed on interface probe. |
| 4Q10 | 447.19 | 10/1/2010 | 42.70 | 43.19 | 404.00 | 404.49 | 0.49 | 404.39 | | *Product confirmed on interface probe. |
| 1Q11 | 447.19 | 1/14/2011 | 41.19 | 41.64 | 405.55 | 406.00 | 0.45 | 405.91 | | * |
| 2Q11 | 447.19 | 4/1/2011 | NE | 43.10 | NA | NA | NA | 404.09 | | * |
| 3Q11 | 447.19 | 7/5/2011 | NE | 40.42 | NA | NA | NA | 406.77 | | * |
| | 447.19 | 9/19/2011 | NE | 41.69 | NA | NA | NA | 405.50 | | * |
| 4Q11 | 447.19 | 10/6/2011 | NE | 41.63 | NA | NA | NA | 405.56 | | * |
| 1Q12 | 447.19 | 1/3/2012 | NE | 42.91 | NA | NA | NA | 404.28 | | * |
| 2Q12 | 447.19 | 4/3/2012 | NE | 44.31 | NA | NA | NA | 402.88 | | * |
| 3Q12 | 447.19 | 7/2/2012 | NE | 45.76 | NA | NA | NA | 401.43 | | * |
| 4Q12 | 447.19 | 10/1/2012 | NE | 46.72 | NA | NA | NA | 400.47 | | * |
| 1Q13 | 447.19 | 1/4/2013 | NE | 48.92 | NA | NA | NA | 398.27 | | * |

**TABLE 1**
**CUMULATIVE GROUNDWATER MONITORING WELL GAUGING RESULTS**

| WELL ID | TOP OF CASING (elev.[1]) | DATE GAUGED | DEPTH TO PRODUCT (ft btoc) | DEPTH TO WATER (ft btoc) | WATER-PRODUCT INTERFACE (elev.[1]) | PRODUCT (elev.[1]) | PRODUCT THICKNESS (ft) | CORRECTED WATER LEVEL[2] (elev.[1]) | SCREENED INTERVAL (elev.[1]) (ft btoc) | COMMENTS |
|---|---|---|---|---|---|---|---|---|---|---|
| **P-91B** | | | | | | | | | | |
| 2Q10 | 447.26 | 4/1/2010 | NE | 46.21 | NA | NA | NA | 401.05 | 372.57 - 370.57 (74.69 - 76.69) | * |
| 3Q10 | 447.26 | 7/1/2010 | NE | 45.08 | NA | NA | NA | 402.18 | | * |
| 4Q10 | 447.26 | 10/1/2010 | NE | 42.87 | NA | NA | NA | 404.39 | | * |
| 1Q11 | 447.26 | 1/14/2011 | NE | 41.41 | NA | NA | NA | 405.85 | | * |
| 2Q11 | 447.26 | 4/1/2011 | NE | 43.28 | NA | NA | NA | 403.98 | | * |
| 3Q11 | 447.26 | 7/5/2011 | NE | 40.62 | NA | NA | NA | 406.64 | | * |
| | 447.26 | 9/19/2011 | NE | 41.78 | NA | NA | NA | 405.48 | | * |
| 4Q11 | 447.26 | 10/6/2011 | NE | 41.53 | NA | NA | NA | 405.73 | | * |
| 1Q12 | 447.26 | 1/3/2012 | NE | 43.00 | NA | NA | NA | 404.26 | | * |
| 2Q12 | 447.26 | 4/3/2012 | NE | 44.11 | NA | NA | NA | 403.15 | | * |
| 3Q12 | 447.26 | 7/2/2012 | NE | 45.74 | NA | NA | NA | 401.52 | | * |
| 4Q12 | 447.26 | 10/1/2012 | NE | 46.79 | NA | NA | NA | 400.47 | | * |
| 1Q13 | 447.26 | 1/4/2013 | NE | 49.10 | NA | NA | NA | 398.16 | | * |
| **P-91C** | | | | | | | | | | |
| 2Q10 | 447.02 | 4/1/2010 | NE | 46.08 | NA | NA | NA | 400.94 | 352.29 - 350.29 (94.73 - 96.73) | * |
| 3Q10 | 447.02 | 7/1/2010 | NE | 44.83 | NA | NA | NA | 402.19 | | * |
| 4Q10 | 447.02 | 10/1/2010 | NE | 42.57 | NA | NA | NA | 404.45 | | * |
| 1Q11 | 447.02 | 1/14/2011 | NE | 41.18 | NA | NA | NA | 405.84 | | * |
| 2Q11 | 447.02 | 4/1/2011 | NE | 43.00 | NA | NA | NA | 404.02 | | * |
| 3Q11 | 447.02 | 7/5/2011 | NE | 40.35 | NA | NA | NA | 406.67 | | * |
| | 447.02 | 9/19/2011 | NE | 41.51 | NA | NA | NA | 405.51 | | * |
| 4Q11 | 447.02 | 10/6/2011 | NE | 41.47 | NA | NA | NA | 405.55 | | * |
| 1Q12 | 447.02 | 1/3/2012 | NE | 42.74 | NA | NA | NA | 404.28 | | * |
| 2Q12 | 447.02 | 4/3/2012 | NE | 44.11 | NA | NA | NA | 402.91 | | * |
| 3Q12 | 447.02 | 7/2/2012 | NE | 45.53 | NA | NA | NA | 401.49 | | * |
| 4Q12 | 447.02 | 10/1/2012 | NE | 46.54 | NA | NA | NA | 400.48 | | * |
| 1Q13 | 447.02 | 1/4/2013 | NE | 48.84 | NA | NA | NA | 398.18 | | * |
| **P-91D** | | | | | | | | | | |
| 2Q10 | 447.02 | 4/1/2010 | NE | 46.03 | NA | NA | NA | 400.99 | 278.70 - 276.70 (168.32 - 170.32) | * |
| 3Q10 | 447.02 | 7/1/2010 | NE | 44.77 | NA | NA | NA | 402.25 | | * |
| 4Q10 | 447.02 | 10/1/2010 | NE | 42.52 | NA | NA | NA | 404.50 | | * |
| 1Q11 | 447.02 | 1/14/2011 | NE | 41.14 | NA | NA | NA | 405.88 | | * |
| 2Q11 | 447.02 | 4/1/2011 | NE | 42.97 | NA | NA | NA | 404.05 | | * |
| 3Q11 | 447.02 | 7/5/2011 | NE | 40.27 | NA | NA | NA | 406.75 | | * |
| | 447.02 | 9/19/2011 | NE | 41.49 | NA | NA | NA | 405.53 | | * |
| 4Q11 | 447.02 | 10/6/2011 | NE | 41.44 | NA | NA | NA | 405.58 | | * |
| 1Q12 | 447.02 | 1/3/2012 | NE | 42.73 | NA | NA | NA | 404.29 | | * |
| 2Q12 | 447.02 | 4/3/2012 | NE | 44.35 | NA | NA | NA | 402.67 | | * |
| 3Q12 | 447.02 | 7/2/2012 | NE | 45.55 | NA | NA | NA | 401.47 | | * |
| 4Q12 | 447.02 | 10/1/2012 | NE | 46.53 | NA | NA | NA | 400.49 | | * |
| 1Q13 | 447.02 | 1/4/2013 | NE | 48.82 | NA | NA | NA | 398.20 | | * |
| **P-92A** | | | | | | | | | | |
| 2Q10 | 446.12 | 4/1/2010 | 43.43 | 43.63 | 402.49 | 402.69 | 0.20 | 402.65 | 398.55 - 383.55 (47.57 - 62.57) | *Product confirmed on interface probe. |
| 3Q10 | 446.12 | 7/1/2010 | 42.43 | 42.63 | 403.49 | 403.69 | 0.20 | 403.65 | | *Product confirmed on interface probe. |
| 4Q10 | 446.12 | 10/1/2010 | 40.50 | 40.70 | 405.42 | 405.62 | 0.20 | 405.58 | | *Product confirmed on interface probe. |
| 1Q11 | 446.12 | 1/14/2011 | 39.43 | 39.57 | 406.55 | 406.69 | 0.14 | 406.66 | | * |
| 2Q11 | 446.12 | 4/1/2011 | NE | 41.02 | NA | NA | NA | 405.10 | | * |
| 3Q11 | 446.12 | 7/5/2011 | 38.55 | 38.59 | 407.53 | 407.57 | 0.04 | 407.56 | | * |
| | 446.12 | 9/19/2011 | 39.62 | 39.67 | 406.45 | 406.50 | 0.05 | 406.49 | | * |
| 4Q11 | 446.12 | 10/6/2011 | 39.70 | 39.76 | 406.36 | 406.42 | 0.06 | 406.41 | | * |
| 1Q12 | 446.12 | 1/4/2012 | 41.05 | 41.07 | 405.05 | 405.07 | 0.02 | 405.07 | | * |
| 2Q12 | 446.12 | 4/3/2012 | NE | 42.77 | NA | NA | NA | 403.35 | | * |
| 3Q12 | 446.12 | 7/3/2012 | 44.06 | 44.08 | 402.04 | 402.06 | 0.02 | 402.06 | | * |
| 4Q12 | 446.12 | 10/1/2012 | NE | 45.04 | NA | NA | NA | 401.08 | | * |
| 1Q13 | 446.12 | 1/4/2013 | 46.83 | 46.84 | 399.28 | 399.29 | 0.01 | 399.29 | | * |
| **P-92B** | | | | | | | | | | |
| 2Q10 | 446.07 | 4/1/2010 | NE | 43.44 | NA | NA | NA | 402.63 | 372.42 - 370.42 (73.65 - 75.65) | * |
| 3Q10 | 446.07 | 7/1/2010 | NE | 42.43 | NA | NA | NA | 403.64 | | * |
| 4Q10 | 446.07 | 10/1/2010 | NE | 40.51 | NA | NA | NA | 405.56 | | * |
| 1Q11 | 446.07 | 1/14/2011 | NE | 39.41 | NA | NA | NA | 406.66 | | * |
| 2Q11 | 446.07 | 4/1/2011 | NE | 40.92 | NA | NA | NA | 405.15 | | * |
| 3Q11 | 446.07 | 7/5/2011 | NE | 38.51 | NA | NA | NA | 407.56 | | * |
| | 446.07 | 9/19/2011 | NE | 39.61 | NA | NA | NA | 406.46 | | * |
| 4Q11 | 446.07 | 10/6/2011 | NE | 39.68 | NA | NA | NA | 406.39 | | * |
| 1Q12 | 446.07 | 1/4/2012 | NE | 41.02 | NA | NA | NA | 405.05 | | * |
| 2Q12 | 446.07 | 4/3/2012 | NE | 42.74 | NA | NA | NA | 403.33 | | * |
| 3Q12 | 446.07 | 7/3/2012 | NE | 44.02 | NA | NA | NA | 402.05 | | * |
| 4Q12 | 446.07 | 10/1/2012 | NE | 44.97 | NA | NA | NA | 401.10 | | * |
| 1Q13 | 446.07 | 1/4/2013 | NE | 46.80 | NA | NA | NA | 399.27 | | * |
| **P-92C** | | | | | | | | | | |
| 2Q10 | 445.98 | 4/1/2010 | NE | 43.17 | NA | NA | NA | 402.81 | 352.54 - 350.54 (93.44 - 95.44) | * |
| 3Q10 | 445.98 | 7/1/2010 | NE | 42.30 | NA | NA | NA | 403.68 | | * |
| 4Q10 | 445.98 | 10/1/2010 | NE | 40.38 | NA | NA | NA | 405.60 | | * |
| 1Q11 | 445.98 | 1/14/2011 | NE | 39.32 | NA | NA | NA | 406.66 | | * |
| 2Q11 | 445.98 | 4/1/2011 | NE | 40.77 | NA | NA | NA | 405.21 | | * |
| 3Q11 | 445.98 | 7/5/2011 | NE | 38.33 | NA | NA | NA | 407.65 | | * |
| | 445.98 | 9/19/2011 | NE | 39.50 | NA | NA | NA | 406.48 | | * |
| 4Q11 | 445.98 | 10/6/2011 | NE | 39.63 | NA | NA | NA | 406.35 | | * |
| 1Q12 | 445.98 | 1/4/2012 | NE | 39.95 | NA | NA | NA | 406.03 | | * |
| 2Q12 | 445.98 | 4/3/2012 | NE | 42.61 | NA | NA | NA | 403.37 | | * |
| 3Q12 | 445.98 | 7/3/2012 | NE | 44.07 | NA | NA | NA | 401.91 | | * |
| 4Q12 | 445.98 | 10/1/2012 | NE | 45.04 | NA | NA | NA | 400.94 | | * |
| 1Q13 | 445.98 | 1/4/2013 | NE | 46.83 | NA | NA | NA | 399.15 | | * |

**TABLE 1**
**CUMULATIVE GROUNDWATER MONITORING WELL GAUGING RESULTS**

| WELL ID | TOP OF CASING (elev.[1]) | DATE GAUGED | DEPTH TO PRODUCT (ft btoc) | DEPTH TO WATER (ft btoc) | WATER-PRODUCT INTERFACE (elev.[1]) | PRODUCT (elev.[1]) | PRODUCT THICKNESS (ft) | CORRECTED WATER LEVEL[2] (elev.[1]) | SCREENED INTERVAL (elev.[1]) (ft btoc) | COMMENTS |
|---|---|---|---|---|---|---|---|---|---|---|
| **P-92D** | | | | | | | | | | |
| 2Q10 | 445.90 | 4/1/2010 | NE | 43.24 | NA | NA | NA | 402.66 | 304.90 - 302.90 (141.00 - 143.00) | * |
| 3Q10 | 445.90 | 7/1/2010 | NE | 42.31 | NA | NA | NA | 403.59 | | * |
| 4Q10 | 445.90 | 10/1/2010 | NE | 40.37 | NA | NA | NA | 405.53 | | * |
| 1Q11 | 445.90 | 1/14/2011 | NE | 39.24 | NA | NA | NA | 406.66 | | * |
| 2Q11 | 445.90 | 4/1/2011 | NE | 40.73 | NA | NA | NA | 405.17 | | * |
| 3Q11 | 445.90 | 7/5/2011 | NE | 38.33 | NA | NA | NA | 407.57 | | * |
| | 445.90 | 9/19/2011 | NE | 39.46 | NA | NA | NA | 406.44 | | * |
| 4Q11 | 445.90 | 10/6/2011 | NE | 39.57 | NA | NA | NA | 406.33 | | * |
| 1Q12 | 445.90 | 1/4/2012 | NE | 39.89 | NA | NA | NA | 406.01 | | * |
| 2Q12 | 445.90 | 4/3/2012 | NE | 42.67 | NA | NA | NA | 403.23 | | * |
| 3Q12 | 445.90 | 7/3/2012 | NE | 43.96 | NA | NA | NA | 401.94 | | * |
| 4Q12 | 445.90 | 10/1/2012 | NE | 44.82 | NA | NA | NA | 401.08 | | * |
| 1Q13 | 445.90 | 1/4/2013 | NE | 46.72 | NA | NA | NA | 399.18 | | * |
| **P-93A** | | | | | | | | | | |
| 2Q10 | 446.58 | 4/1/2010 | NE | 42.67 | NA | NA | NA | 403.91 | 398.41 - 383.41 (48.17 - 63.17) | * |
| 3Q10 | 446.58 | 7/1/2010 | NE | 41.47 | NA | NA | NA | 405.11 | | * |
| 4Q10 | 446.58 | 11/11/2010 | NE | 40.75 | NA | NA | NA | 405.83 | | * |
| 1Q11 | 446.58 | 1/14/2011 | NE | 40.97 | NA | NA | NA | 405.61 | | * |
| 2Q11 | 446.58 | 4/25/2011 | NE | 41.80 | NA | NA | NA | 404.78 | | * |
| 3Q11 | 446.58 | 7/5/2011 | NE | 39.40 | NA | NA | NA | 407.18 | | * |
| | 446.58 | 9/19/2011 | NE | 38.86 | NA | NA | NA | 407.72 | | * |
| 4Q11 | 446.58 | 10/6/2011 | NE | 39.16 | NA | NA | NA | 407.42 | | * |
| 1Q12 | 446.58 | 1/4/2012 | NE | 41.32 | NA | NA | NA | 405.26 | | * |
| 2Q12 | 446.58 | 4/3/2012 | NE | 42.72 | NA | NA | NA | 403.86 | | * |
| 3Q12 | 446.58 | 7/5/2012 | NE | 42.95 | NA | NA | NA | 403.63 | | * |
| 4Q12 | 446.58 | 10/2/2012 | NE | 44.72 | NA | NA | NA | 401.86 | | * |
| 1Q13 | 446.58 | 1/8/2013 | NE | 45.73 | NA | NA | NA | 400.85 | | * |
| **P-93B** | | | | | | | | | | |
| 2Q10 | 446.46 | 4/1/2010 | NE | 42.56 | NA | NA | NA | 403.90 | 371.86 - 369.86 (74.60 - 76.60) | * |
| 3Q10 | 446.46 | 7/1/2010 | NE | 41.38 | NA | NA | NA | 405.08 | | * |
| 4Q10 | 446.46 | 11/11/2010 | NE | 40.73 | NA | NA | NA | 405.73 | | * |
| 1Q11 | 446.46 | 1/14/2011 | NE | 41.03 | NA | NA | NA | 405.43 | | * |
| 2Q11 | 446.46 | 4/25/2011 | NE | 41.69 | NA | NA | NA | 404.77 | | * |
| 3Q11 | 446.46 | 7/5/2011 | NE | 39.44 | NA | NA | NA | 407.02 | | * |
| | 446.46 | 9/19/2011 | NE | 38.91 | NA | NA | NA | 407.55 | | * |
| 4Q11 | 446.46 | 10/6/2011 | NE | 39.19 | NA | NA | NA | 407.27 | | * |
| 1Q12 | 446.46 | 1/4/2012 | NE | 41.38 | NA | NA | NA | 405.08 | | * |
| 2Q12 | 446.46 | 4/3/2012 | NE | 42.80 | NA | NA | NA | 403.66 | | * |
| 3Q12 | 446.46 | 7/5/2012 | NE | 42.86 | NA | NA | NA | 403.60 | | * |
| 4Q12 | 446.46 | 10/2/2012 | NE | 44.80 | NA | NA | NA | 401.66 | | * |
| 1Q13 | 446.46 | 1/8/2013 | NE | 45.77 | NA | NA | NA | 400.69 | | * |
| **P-93C** | | | | | | | | | | |
| 2Q10 | 446.51 | 4/1/2010 | NE | 42.59 | NA | NA | NA | 403.92 | 352.26 - 350.26 (94.26 - 96.26) | * |
| 3Q10 | 446.51 | 7/1/2010 | NE | 41.42 | NA | NA | NA | 405.09 | | * |
| 4Q10 | 446.51 | 11/11/2010 | NE | 40.69 | NA | NA | NA | 405.82 | | * |
| 1Q11 | 446.51 | 1/14/2011 | NE | 40.91 | NA | NA | NA | 405.60 | | * |
| 2Q11 | 446.51 | 4/25/2011 | NE | 41.70 | NA | NA | NA | 404.81 | | * |
| 3Q11 | 446.51 | 7/5/2011 | NE | 39.32 | NA | NA | NA | 407.19 | | * |
| | 446.51 | 9/19/2011 | NE | 38.79 | NA | NA | NA | 407.72 | | * |
| 4Q11 | 446.51 | 10/6/2011 | NE | 39.15 | NA | NA | NA | 407.36 | | * |
| 1Q12 | 446.51 | 1/4/2012 | NE | 41.27 | NA | NA | NA | 405.24 | | * |
| 2Q12 | 446.51 | 4/3/2012 | NE | 42.62 | NA | NA | NA | 403.89 | | * |
| 3Q12 | 446.51 | 7/5/2012 | NE | 42.98 | NA | NA | NA | 403.53 | | * |
| 4Q12 | 446.51 | 10/2/2012 | NE | 44.68 | NA | NA | NA | 401.83 | | * |
| 1Q13 | 446.51 | 1/8/2013 | NE | 45.66 | NA | NA | NA | 400.85 | | * |
| **P-93D** | | | | | | | | | | |
| 2Q10 | 446.89 | 4/1/2010 | NE | 42.51 | NA | NA | NA | 404.38 | Unknown | |
| 3Q10 | 446.89 | 7/1/2010 | NE | 41.32 | NA | NA | NA | 405.57 | | |
| 4Q10 | 446.36 | 11/11/2010 | NE | 40.59 | NA | NA | NA | 405.77 | | |
| 1Q11 | 446.36 | 1/14/2011 | NE | 40.81 | NA | NA | NA | 405.55 | | |
| 2Q11 | 446.89 | 4/25/2011 | NE | 41.84 | NA | NA | NA | 405.05 | 321.14 - 319.14 (125.75 - 127.75) | * |
| 3Q11 | 446.89 | 7/5/2011 | NE | 39.46 | NA | NA | NA | 407.43 | | * |
| | 446.89 | 9/19/2011 | NE | 38.94 | NA | NA | NA | 407.95 | | * |
| 4Q11 | 446.89 | 10/6/2011 | NE | 39.22 | NA | NA | NA | 407.67 | | * |
| 1Q12 | 446.89 | 1/4/2012 | NE | 41.41 | NA | NA | NA | 405.48 | | * |
| 2Q12 | 446.89 | 4/3/2012 | NE | 42.81 | NA | NA | NA | 404.08 | | * |
| 3Q12 | 446.89 | 7/5/2012 | NE | 43.02 | NA | NA | NA | 403.87 | | * |
| 4Q12 | 446.89 | 10/2/2012 | NE | 44.43 | NA | NA | NA | 402.46 | | * |
| 1Q13 | 446.89 | 1/8/2013 | NE | 45.84 | NA | NA | NA | 401.05 | | * |
| **P-94** | | | | | | | | | | |
| 2Q10 | 444.65 | 4/1/2010 | NE | 37.55 | NA | NA | NA | 407.10 | 398.80 - 383.80 (45.85 - 60.85) | * |
| 3Q10 | 444.65 | 7/1/2010 | NE | 36.11 | NA | NA | NA | 408.54 | | * |
| 4Q10 | 444.65 | 10/1/2010 | NE | 35.13 | NA | NA | NA | 409.52 | | * |
| 1Q11 | 444.65 | 1/13/2011 | NE | 34.66 | NA | NA | NA | 409.99 | | * |
| 2Q11 | 444.65 | 4/1/2011 | NE | 34.27 | NA | NA | NA | 410.38 | | * |
| 3Q11 | 444.65 | 7/5/2011 | NE | 32.14 | NA | NA | NA | 412.51 | | * |
| | 444.65 | 9/19/2011 | NE | 33.17 | NA | NA | NA | 411.48 | | * |
| 4Q11 | 444.65 | 10/6/2011 | NE | 33.53 | NA | NA | NA | 411.12 | | * |
| 1Q12 | 444.65 | 1/3/2012 | NE | 34.75 | NA | NA | NA | 409.90 | | * |
| 2Q12 | 444.65 | 4/2/2012 | NE | 35.68 | NA | NA | NA | 408.97 | | * |
| 3Q12 | 444.65 | 7/2/2012 | NE | 36.20 | NA | NA | NA | 408.45 | | * |
| 4Q12 | 444.65 | 10/1/2012 | NE | 38.02 | NA | NA | NA | 406.63 | | * |
| 1Q13 | 444.65 | 1/3/2013 | NE | 39.75 | NA | NA | NA | 404.90 | | * |

**TABLE 1**
**CUMULATIVE GROUNDWATER MONITORING WELL GAUGING RESULTS**

| WELL ID | TOP OF CASING (elev.[1]) | DATE GAUGED | DEPTH TO PRODUCT (ft btoc) | DEPTH TO WATER (ft btoc) | WATER-PRODUCT INTERFACE (elev.[1]) | PRODUCT (elev.[1]) | PRODUCT THICKNESS (ft) | CORRECTED WATER LEVEL[2] (elev.[1]) | SCREENED INTERVAL (elev.[1]) (ft btoc) | COMMENTS |
|---|---|---|---|---|---|---|---|---|---|---|
| **P-95** | | | | | | | | | | |
| 2Q10 | 443.44 | 4/1/2010 | NE | 31.77 | NA | NA | NA | 411.67 | 406.92 - 391.92 (36.52 - 51.52) | * |
| 3Q10 | 443.44 | 7/1/2010 | NE | 30.42 | NA | NA | NA | 413.02 | | * |
| 4Q10 | 443.44 | 10/1/2010 | NE | 29.31 | NA | NA | NA | 414.13 | | * |
| 1Q11 | 443.44 | 1/13/2011 | NE | 29.68 | NA | NA | NA | 413.76 | | * |
| 2Q11 | 443.44 | 4/1/2011 | NE | 29.75 | NA | NA | NA | 413.69 | | * |
| 3Q11 | 443.44 | 7/5/2011 | NE | 28.12 | NA | NA | NA | 415.32 | | * |
| 4Q11 | 443.44 | 10/5/2011 | NE | 28.24 | NA | NA | NA | 415.20 | | * |
| 1Q12 | 443.44 | 1/5/2012 | NE | 29.50 | NA | NA | NA | 413.94 | | * |
| 2Q12 | 443.44 | 4/3/2012 | NE | 30.58 | NA | NA | NA | 412.86 | | * |
| 3Q12 | 443.44 | 7/3/2012 | NE | 31.04 | NA | NA | NA | 412.40 | | * |
| 4Q12 | 443.44 | 10/2/2012 | NE | 32.52 | NA | NA | NA | 410.92 | | * |
| 1Q13 | 443.44 | 1/2/2013 | NE | 33.87 | NA | NA | NA | 409.57 | | * |
| **P-102** | | | | | | | | | | |
| 2Q10 | 444.91 | 4/1/2010 | NE | 35.31 | NA | NA | NA | 409.60 | 402.16 - 382.16 (42.75 - 62.75) | * |
| 3Q10 | 444.91 | 7/1/2010 | NE | 33.97 | NA | NA | NA | 410.94 | | * |
| 4Q10 | 444.91 | 10/1/2010 | NE | 33.62 | NA | NA | NA | 411.29 | | * |
| 1Q11 | 444.91 | 1/3/2011 | NE | 32.61 | NA | NA | NA | 412.30 | | * |
| 2Q11 | 444.91 | 4/1/2011 | NE | 32.41 | NA | NA | NA | 412.50 | | * |
| 3Q11 | 444.91 | 7/5/2011 | NE | 30.91 | NA | NA | NA | 414.00 | | * |
| | 444.91 | 9/19/2011 | NE | 31.18 | NA | NA | NA | 413.73 | | * |
| 4Q11 | 444.91 | 10/6/2011 | NE | 31.47 | NA | NA | NA | 413.44 | | * |
| 1Q12 | 444.91 | 1/4/2012 | NE | 32.45 | NA | NA | NA | 412.46 | | * |
| 2Q12 | 444.91 | 4/3/2012 | NE | 33.41 | NA | NA | NA | 411.50 | | * |
| 3Q12 | 444.91 | 7/2/2012 | NE | 34.10 | NA | NA | NA | 410.81 | | * |
| 4Q12 | 444.91 | 10/2/2012 | NE | 35.69 | NA | NA | NA | 409.22 | | * |
| 1Q13 | 444.91 | 1/2/2013 | NE | 36.98 | NA | NA | NA | 407.93 | | * |
| **P-114** | | | | | | | | | | |
| 2Q10 | 432.41 | 4/1/2010 | NE | 27.05 | NA | NA | NA | 405.36 | 399.73 - 379.73 (32.67 - 52.67) | * |
| 3Q10 | 432.41 | 7/1/2010 | NE | 25.00 | NA | NA | NA | 407.41 | | * |
| 4Q10 | 432.41 | 11/12/2010 | NE | 24.66 | NA | NA | NA | 407.75 | | * |
| 1Q11 | 432.41 | 1/13/2011 | NE | 26.84 | NA | NA | NA | 405.57 | | * |
| 2Q11 | 432.41 | 4/25/2011 | NE | 26.61 | NA | NA | NA | 405.80 | | * |
| 3Q11 | 432.41 | 7/5/2011 | NE | 23.48 | NA | NA | NA | 408.93 | | * |
| | 432.41 | 9/19/2011 | NE | 24.20 | NA | NA | NA | 408.21 | | * |
| 4Q11 | 432.41 | 10/5/2011 | NE | 24.59 | NA | NA | NA | 407.82 | | * |
| 1Q12 | 432.41 | 1/3/2012 | NE | 26.88 | NA | NA | NA | 405.53 | | * |
| 2Q12 | 432.41 | 4/2/2012 | NE | 28.33 | NA | NA | NA | 404.08 | | * |
| 3Q12 | 432.41 | 7/3/2012 | NE | 28.39 | NA | NA | NA | 404.02 | | * |
| 4Q12 | 432.41 | 10/2/2012 | NE | 30.51 | NA | NA | NA | 401.90 | | * |
| 1Q13 | 432.41 | 1/7/2013 | NE | 30.22 | NA | NA | NA | 402.19 | | * |
| **P-115** | | | | | | | | | | |
| 2Q10 | 433.31 | 4/1/2010 | NE | 27.77 | NA | NA | NA | 405.54 | 401.01 - 381.01 (32.30 - 52.30) | * |
| 3Q10 | 433.31 | 7/1/2010 | NE | 25.59 | NA | NA | NA | 407.72 | | * |
| 4Q10 | 433.31 | 11/11/2010 | NE | 25.41 | NA | NA | NA | 407.90 | | * |
| 1Q11 | 433.31 | 1/13/2011 | NE | 27.88 | NA | NA | NA | 405.43 | | * |
| 2Q11 | 433.31 | 4/25/2011 | NE | 27.38 | NA | NA | NA | 405.93 | | * |
| 3Q11 | 433.31 | 7/5/2011 | NE | NM | NA | NA | NA | NA | | Not Accessible |
| | 433.31 | 9/19/2011 | NE | 25.10 | NA | NA | NA | 408.21 | | * |
| 4Q11 | 433.31 | 10/6/2011 | NE | 25.67 | NA | NA | NA | 407.64 | | * |
| 1Q12 | 433.31 | 1/3/2012 | NE | 27.86 | NA | NA | NA | 405.45 | | * |
| 2Q12 | 433.31 | 4/2/2012 | NE | 29.30 | NA | NA | NA | 404.01 | | * |
| 3Q12 | 433.31 | 7/3/2012 | NE | 29.35 | NA | NA | NA | 403.96 | | * |
| 4Q12 | 433.31 | 10/2/2012 | NE | 31.51 | NA | NA | NA | 401.80 | | * |
| 1Q13 | 433.31 | 1/7/2013 | NE | 32.60 | NA | NA | NA | 400.71 | | |
| **P-116** | | | | | | | | | | |
| 2Q10 | 436.45 | 4/1/2010 | NE | 31.05 | NA | NA | NA | 405.40 | 399.01 - 379.01 (37.44 - 57.44) | * |
| 3Q10 | 436.45 | 7/1/2010 | NE | 28.82 | NA | NA | NA | 407.63 | | * |
| 4Q10 | 436.45 | 11/11/2010 | NE | 28.76 | NA | NA | NA | 407.69 | | * |
| 1Q11 | 436.45 | 1/13/2011 | NE | 31.35 | NA | NA | NA | 405.10 | | * |
| 2Q11 | 436.45 | 4/25/2011 | NE | 30.76 | NA | NA | NA | 405.69 | | * |
| 3Q11 | 436.45 | 7/5/2011 | NE | 27.41 | NA | NA | NA | 409.04 | | * |
| | 436.45 | 9/19/2011 | NE | 28.52 | NA | NA | NA | 407.93 | | * |
| 4Q11 | 436.45 | 10/5/2011 | NE | 28.96 | NA | NA | NA | 407.49 | | * |
| 1Q12 | 436.45 | 1/3/2012 | NE | 31.35 | NA | NA | NA | 405.10 | | * |
| 2Q12 | 436.45 | 4/2/2012 | NE | 32.72 | NA | NA | NA | 403.73 | | * |
| 3Q12 | 436.45 | 7/3/2012 | NE | 32.80 | NA | NA | NA | 403.65 | | * |
| 4Q12 | 436.45 | 10/2/2012 | NE | 34.97 | NA | NA | NA | 401.48 | | * |
| 1Q13 | 436.45 | 1/7/2013 | NE | 36.10 | NA | NA | NA | 400.35 | | * |
| **P-117** | | | | | | | | | | |
| 2Q10 | 432.67 | 4/1/2010 | NE | 27.19 | NA | NA | NA | 405.48 | 399.74 - 379.74 (32.93 - 52.93) | * |
| 3Q10 | 432.67 | 7/1/2010 | NE | 24.91 | NA | NA | NA | 407.76 | | * |
| 4Q10 | 432.67 | 11/11/2010 | NE | 24.11 | NA | NA | NA | 408.56 | | * |
| 1Q11 | 432.67 | 1/13/2011 | NE | 27.62 | NA | NA | NA | 405.05 | | * |
| 2Q11 | 432.67 | 4/25/2011 | NE | 26.96 | NA | NA | NA | 405.71 | | * |
| 3Q11 | 432.67 | 7/5/2011 | NE | 23.54 | NA | NA | NA | 409.13 | | * |
| | 432.67 | 9/19/2011 | NE | 24.71 | NA | NA | NA | 407.96 | | * |
| 4Q11 | 432.67 | 10/5/2011 | NE | 25.16 | NA | NA | NA | 407.51 | | * |
| 1Q12 | 432.67 | 1/3/2012 | NE | 27.56 | NA | NA | NA | 405.11 | | * |
| 2Q12 | 432.67 | 4/2/2012 | NE | 29.00 | NA | NA | NA | 403.67 | | * |
| 3Q12 | 432.67 | 7/3/2012 | NE | 29.00 | NA | NA | NA | 403.67 | | * |
| 4Q12 | 432.67 | 10/2/2012 | NE | 31.19 | NA | NA | NA | 401.48 | | * |
| 1Q13 | 432.67 | 1/7/2013 | NE | 32.45 | NA | NA | NA | 400.22 | | * |

**TABLE 1**
**CUMULATIVE GROUNDWATER MONITORING WELL GAUGING RESULTS**

| WELL ID | TOP OF CASING (elev.[1]) | DATE GAUGED | DEPTH TO PRODUCT (ft btoc) | DEPTH TO WATER (ft btoc) | WATER-PRODUCT INTERFACE (elev.[1]) | PRODUCT (elev.[1]) | PRODUCT THICKNESS (ft) | CORRECTED WATER LEVEL[2] (elev.[1]) | SCREENED INTERVAL (elev.[1]) (ft btoc) | COMMENTS |
|---|---|---|---|---|---|---|---|---|---|---|
| **P-118** | | | | | | | | | | |
| 2Q10 | 431.32 | 4/1/2010 | NE | 25.81 | NA | NA | NA | 405.51 | 400.20 - 384.27 (31.12 - 47.05) | * |
| 3Q10 | 431.32 | 7/1/2010 | NE | 23.27 | NA | NA | NA | 408.05 | | * |
| 4Q10 | 431.32 | 10/1/2010 | NE | 23.80 | NA | NA | NA | 407.52 | | * |
| 1Q11 | 431.32 | 1/13/2011 | NE | 26.95 | NA | NA | NA | 404.37 | | * |
| 2Q11 | 431.32 | 4/1/2011 | NE | 25.75 | NA | NA | NA | 405.57 | | * |
| 3Q11 | 431.32 | 7/5/2011 | NE | 22.11 | NA | NA | NA | 409.21 | | * |
| | 431.32 | 9/19/2011 | NE | 23.78 | NA | NA | NA | 407.54 | | * |
| 4Q11 | 431.32 | 10/5/2011 | NE | 34.28 | NA | NA | NA | 397.04 | | |
| 1Q12 | 431.32 | 1/3/2012 | NE | 26.78 | NA | NA | NA | 404.54 | | * |
| 2Q12 | 431.32 | 4/2/2012 | NE | 28.13 | NA | NA | NA | 403.19 | | * |
| 3Q12 | 431.32 | 7/3/2012 | NE | 28.12 | NA | NA | NA | 403.20 | | * |
| 4Q12 | 431.32 | 10/2/2012 | NE | 30.40 | NA | NA | NA | 400.92 | | * |
| 1Q13 | 431.32 | 1/7/2013 | NE | 31.60 | NA | NA | NA | 399.72 | | |
| **P-119** | | | | | | | | | | |
| 2Q10 | 431.92 | 4/1/2010 | NE | 26.49 | NA | NA | NA | 405.43 | 401.25 - 385.32 (30.67 - 46.60) | * |
| 3Q10 | 431.92 | 7/1/2010 | NE | 24.71 | NA | NA | NA | 407.21 | | * |
| 4Q10 | 431.92 | 11/11/2010 | NE | 24.93 | NA | NA | NA | 406.99 | | * |
| 1Q11 | 431.92 | 1/13/2011 | NE | 25.64 | NA | NA | NA | 406.28 | | * |
| 2Q11 | 431.92 | 4/25/2011 | NE | 25.77 | NA | NA | NA | 406.15 | | * |
| 3Q11 | 431.92 | 7/5/2011 | NE | 23.06 | NA | NA | NA | 408.86 | | * |
| | 431.92 | 9/19/2011 | NE | 23.40 | NA | NA | NA | 408.52 | | * |
| 4Q11 | 431.92 | 10/5/2011 | NE | 23.70 | NA | NA | NA | 408.22 | | * |
| 1Q12 | 431.92 | 1/3/2012 | NE | 29.80 | NA | NA | NA | 402.12 | | * |
| 2Q12 | 431.92 | 4/2/2012 | NE | 27.21 | NA | NA | NA | 404.71 | | * |
| 3Q12 | 431.92 | 7/3/2012 | NE | 27.40 | NA | NA | NA | 404.52 | | * |
| 4Q12 | 431.92 | 10/2/2012 | NE | 29.45 | NA | NA | NA | 402.47 | | * |
| 1Q13 | 431.92 | 1/7/2013 | NE | 30.46 | NA | NA | NA | 401.46 | | * |
| **P-120** | | | | | | | | | | |
| 2Q10 | 432.78 | 4/1/2010 | NE | 26.60 | NA | NA | NA | 406.18 | 401.40 - 385.47 (31.38 - 47.31) | * |
| 3Q10 | 432.78 | 7/1/2010 | NE | 24.53 | NA | NA | NA | 408.25 | | * |
| 4Q10 | 432.78 | 10/1/2010 | NE | 24.13 | NA | NA | NA | 408.65 | | * |
| 1Q11 | 432.78 | 1/13/2011 | NE | 26.14 | NA | NA | NA | 406.64 | | * |
| 2Q11 | 432.78 | 4/1/2011 | NE | 25.82 | NA | NA | NA | 406.96 | | * |
| 3Q11 | 432.78 | 7/5/2011 | NE | 22.85 | NA | NA | NA | 409.93 | | * |
| | 432.78 | 9/19/2011 | NE | 23.82 | NA | NA | NA | 408.96 | | * |
| 4Q11 | 432.78 | 10/5/2011 | NE | 24.15 | NA | NA | NA | 408.63 | | * |
| 1Q12 | 432.78 | 1/3/2012 | NE | 26.22 | NA | NA | NA | 406.56 | | * |
| 2Q12 | 432.78 | 4/4/2012 | NE | 27.58 | NA | NA | NA | 405.20 | | * |
| 3Q12 | 432.78 | 7/3/2012 | NE | 27.84 | NA | NA | NA | 404.94 | | * |
| 4Q12 | 432.78 | 10/2/2012 | NE | 29.90 | NA | NA | NA | 402.88 | | * |
| 1Q13 | 432.78 | 1/7/2013 | NE | 31.00 | NA | NA | NA | 401.78 | | * |
| **P-129** | | | | | | | | | | |
| 2Q10 | 432.46 | 4/1/2010 | NE | 27.11 | NA | NA | NA | 405.35 | 400.49 - 384.56 (31.97 - 47.90) | * |
| 3Q10 | 432.46 | 7/1/2010 | NE | 23.82 | NA | NA | NA | 408.64 | | * |
| 4Q10 | 432.46 | 10/1/2010 | NE | 25.46 | NA | NA | NA | 407.00 | | * |
| 1Q11 | 432.46 | 1/1/2011 | NE | 29.82 | NA | NA | NA | 402.64 | | * |
| 2Q11 | 432.46 | 4/1/2011 | NE | 26.85 | NA | NA | NA | 405.61 | | * |
| 3Q11 | 432.46 | 7/5/2011 | NE | 22.74 | NA | NA | NA | 409.72 | | * |
| 4Q11 | 432.46 | 10/5/2011 | NE | 26.57 | NA | NA | NA | 405.89 | | * |
| 1Q12 | 432.46 | 1/5/2012 | NE | 29.31 | NA | NA | NA | 403.15 | | * |
| 2Q12 | 432.46 | 4/2/2012 | NE | 30.31 | NA | NA | NA | 402.15 | | * |
| 3Q12 | 432.46 | 7/3/2012 | NE | 30.33 | NA | NA | NA | 402.13 | | * |
| 4Q12 | 432.46 | 10/2/2012 | NE | 32.84 | NA | NA | NA | 399.62 | | |
| 1Q13 | 432.46 | 1/7/2013 | NE | 34.12 | NA | NA | NA | 398.34 | | |
| **GP-9-PZ** | | | | | | | | | | |
| 4Q10 | 442.41 | 11/11/2010 | NE | 37.38 | NA | NA | NA | 405.03 | 404.81 - 394.81 (37.60 - 47.60) | * |
| 1Q11 | 442.41 | 1/14/2011 | NE | 37.53 | NA | NA | NA | 404.88 | | * |
| 2Q11 | 442.41 | 4/25/2011 | NE | 38.85 | NA | NA | NA | 403.56 | | |
| 3Q11 | 442.41 | 7/5/2011 | NE | NM | NA | NA | NA | NA | | |
| | 442.41 | 9/19/2011 | NE | 35.44 | NA | NA | NA | 406.97 | | * |
| 4Q11 | 442.41 | 10/6/2011 | NE | 36.65 | NA | NA | NA | 405.76 | | * |
| 1Q12 | 442.41 | 1/4/2012 | NE | 38.13 | NA | NA | NA | 404.28 | | |
| 2Q12 | 442.41 | 4/3/2012 | NE | 39.51 | NA | NA | NA | 402.90 | | |
| 3Q12 | 442.41 | 7/5/2012 | NE | 39.62 | NA | NA | NA | 402.79 | | |
| 4Q12 | 442.41 | 10/2/2012 | NE | 41.32 | NA | NA | NA | 401.09 | | |
| 1Q13 | 442.41 | 1/4/2013 | NE | 42.21 | NA | NA | NA | 400.20 | | |
| **ROST-3-MW (ROST-3-PZ)** | | | | | | | | | | |
| 4Q10 | 442.29 | 11/12/2010 | NE | 36.60 | NA | NA | NA | 405.69 | 402.29 - 392.29 (40.00 - 50.00) | * |
| 1Q11 | 442.29 | 1/13/2011 | NE | 37.29 | NA | NA | NA | 405.00 | | * |
| 2Q11 | 442.29 | 4/25/2011 | NE | 38.21 | NA | NA | NA | 404.08 | | * |
| 3Q11 | 442.29 | 7/5/2011 | NE | 35.83 | NA | NA | NA | 406.46 | | * |
| | 442.29 | 9/19/2011 | NE | 34.89 | NA | NA | NA | 407.40 | | * |
| 4Q11 | 442.29 | 10/5/2011 | NE | 35.18 | NA | NA | NA | 407.11 | | * |
| 1Q12 | 442.29 | 1/3/2012 | NE | 37.33 | NA | NA | NA | 404.96 | | * |
| 2Q12 | 442.29 | 4/2/2012 | NE | 38.57 | NA | NA | NA | 403.72 | | * |
| 3Q12 | 442.29 | 7/2/2012 | NE | 38.84 | NA | NA | NA | 403.45 | | * |
| 4Q12 | 442.29 | 10/1/2012 | NE | 40.55 | NA | NA | NA | 401.74 | | |
| 1Q13 | 442.29 | 1/2/2013 | NE | 41.50 | NA | NA | NA | 400.79 | 404.48 - 394.48 (38.18-48.18) | Replaced ROST-3-PZ during 4Q12 with 2" well |

**TABLE 1**
**CUMULATIVE GROUNDWATER MONITORING WELL GAUGING RESULTS**

| WELL ID | TOP OF CASING (elev.[1]) | DATE GAUGED | DEPTH TO PRODUCT (ft btoc) | DEPTH TO WATER (ft btoc) | WATER-PRODUCT INTERFACE (elev.[1]) | PRODUCT (elev.[1]) | PRODUCT THICKNESS (ft) | CORRECTED WATER LEVEL[2] (elev.[1]) | SCREENED INTERVAL (elev.[1]) (ft btoc) | COMMENTS |
|---|---|---|---|---|---|---|---|---|---|---|
| **ROST-4-PZ** | | | | | | | | | | |
| 4Q10 | 442.27 | 11/12/2010 | NE | 36.48 | NA | NA | NA | 405.79 | Unknown | 3/4" Piezometer |
| 1Q11 | 442.27 | 1/13/2011 | NE | 36.97 | NA | NA | NA | 405.30 | | 3/4" Piezometer |
| 2Q11 | 442.13 | 4/25/2011 | NE | 37.69 | NA | NA | NA | 404.44 | 407.20 - 397.20 (34.93 - 44.93) | 2" Well Installed |
| 3Q11 | 442.13 | 7/5/2011 | NE | 35.85 | NA | NA | NA | 406.28 | | |
| 1Q12 | 442.13 | 1/3/2012 | NE | 36.62 | NA | NA | NA | 405.51 | | |
| 2Q12 | 442.13 | 4/2/2012 | 37.81 | 37.84 | 404.29 | 404.32 | 0.03 | 404.31 | | |
| 3Q12 | 442.13 | 7/2/2012 | NE | 38.24 | NA | NA | NA | 403.89 | | |
| 4Q12 | 442.13 | 10/1/2012 | NE | 39.52 | NA | NA | NA | 402.61 | | |
| 1Q13 | 442.13 | 1/2/2013 | NE | 40.52 | NA | NA | NA | 401.61 | | |
| **ROST-4-PZ(A)** | | | | | | | | | | |
| 2Q11 | 442.11 | 4/25/2011 | NE | 37.18 | NA | NA | NA | 404.93 | 407.34 - 397.34 (34.77 - 44.77) | |
| 3Q11 | 442.11 | 7/5/2011 | NE | 35.21 | NA | NA | NA | 406.90 | | |
| 1Q12 | 442.11 | 1/3/2012 | NE | 35.92 | NA | NA | NA | 406.19 | | |
| 2Q12 | 442.11 | 4/2/2012 | NE | 37.17 | NA | NA | NA | 404.94 | | |
| 3Q12 | 442.11 | 7/2/2012 | NE | 38.64 | NA | NA | NA | 403.47 | | |
| 4Q12 | 442.11 | 10/1/2012 | NE | 38.95 | NA | NA | NA | 403.16 | | |
| 1Q13 | 442.11 | 1/2/2013 | NE | 40.60 | NA | NA | NA | 401.51 | | |
| **ROST-4-PZ(B)** | | | | | | | | | | |
| 2Q11 | 442.38 | 4/25/2011 | NE | 37.80 | NA | NA | NA | 404.58 | 407.33 - 397.33 (35.05 - 45.05) | |
| 3Q11 | 442.38 | 7/5/2011 | NE | 35.93 | NA | NA | NA | 406.45 | | |
| 1Q12 | 442.38 | 1/3/2012 | NE | 36.65 | NA | NA | NA | 405.73 | | |
| 2Q12 | 442.38 | 4/2/2012 | NE | 37.87 | NA | NA | NA | 404.51 | | |
| 3Q12 | 442.38 | 7/2/2012 | NE | 38.28 | NA | NA | NA | 404.10 | | |
| 4Q12 | 442.38 | 10/1/2012 | NE | 39.62 | NA | NA | NA | 402.76 | | |
| 1Q13 | 442.38 | 1/2/2013 | NE | 40.61 | NA | NA | NA | 401.77 | | |
| **ROST-4-PZ(C)** | | | | | | | | | | |
| 2Q11 | 442.66 | 4/25/2011 | NE | 38.52 | NA | NA | NA | 404.14 | 407.71 - 397.71 (34.95 - 44.95) | |
| 3Q11 | 442.66 | 7/5/2011 | NE | 36.62 | NA | NA | NA | 406.04 | | |
| 1Q12 | 442.66 | 1/3/2012 | NE | 37.40 | NA | NA | NA | 405.26 | | |
| 2Q12 | 442.66 | 4/2/2012 | NE | 38.62 | NA | NA | NA | 404.04 | | |
| 3Q12 | 442.66 | 7/2/2012 | NE | 39.09 | NA | NA | NA | 403.57 | | |
| 4Q12 | 442.66 | 10/1/2012 | NE | 40.43 | NA | NA | NA | 402.23 | | |
| 1Q13 | 442.66 | 1/2/2013 | NE | 41.42 | NA | NA | NA | 401.24 | | |
| **ROST-4-PZ(D)** | | | | | | | | | | |
| 2Q11 | 442.98 | 4/25/2011 | NE | 38.41 | NA | NA | NA | 404.57 | 408.01 - 398.01 (34.97 - 44.97) | |
| 3Q11 | 442.98 | 7/5/2011 | NE | 36.58 | NA | NA | NA | 406.40 | | |
| 1Q12 | 442.98 | 1/3/2012 | 37.23 | 37.68 | 405.30 | 405.75 | 0.45 | 405.66 | | |
| 2Q12 | 442.98 | 4/2/2012 | 38.57 | 38.59 | 404.39 | 404.41 | 0.02 | 404.41 | | |
| 3Q12 | 442.98 | 7/2/2012 | NE | 39.99 | NA | NA | NA | 402.99 | | sheen; lock not tight |
| 4Q12 | 442.98 | 10/1/2012 | NE | NE | NA | NA | NA | NA | | Well dry; Integrity Suspect |
| 1Q13 | 442.98 | 1/2/2013 | NE | NE | NA | NA | NA | NA | | Well dry |
| **ROST-4-PZ(E)** | | | | | | | | | | |
| 2Q11 | 441.96 | 4/25/2011 | NE | 37.63 | NA | NA | NA | 404.33 | 407.21 - 397.21 (34.75 - 44.75) | |
| 3Q11 | 441.96 | 7/5/2011 | NE | 35.81 | NA | NA | NA | 406.15 | | |
| 1Q12 | 441.96 | 1/3/2012 | 36.48 | 36.92 | 405.04 | 405.48 | 0.44 | 405.39 | | |
| 2Q12 | 441.96 | 4/2/2012 | 37.72 | 38.11 | 403.85 | 404.24 | 0.39 | 404.16 | | |
| 3Q12 | 441.96 | 7/2/2012 | 38.13 | 38.19 | 403.77 | 403.83 | 0.06 | 403.82 | | |
| 4Q12 | 441.96 | 10/1/2012 | 39.28 | 39.31 | 402.65 | 402.68 | 0.03 | 402.67 | | |
| 1Q13 | 441.96 | 1/2/2013 | NE | 40.02 | NA | NA | NA | 401.94 | | |
| **ROST-4-PZ(F)** | | | | | | | | | | |
| 2Q11 | 442.12 | 4/25/2011 | NE | 37.87 | NA | NA | NA | 404.25 | 407.59 - 397.59 (34.53 - 44.53) | |
| 3Q11 | 442.12 | 7/5/2011 | NE | 35.99 | NA | NA | NA | 406.13 | | |
| 1Q12 | 442.12 | 1/3/2012 | NE | 36.83 | NA | NA | NA | 405.29 | | |
| 2Q12 | 442.12 | 4/2/2012 | NE | 37.96 | NA | NA | NA | 404.16 | | |
| 3Q12 | 442.12 | 7/2/2012 | NE | 38.29 | NA | NA | NA | 403.83 | | |
| 4Q12 | 442.12 | 10/1/2012 | NE | 39.46 | NA | NA | NA | 402.66 | | |
| 1Q13 | 442.12 | 1/2/2013 | NE | 40.30 | NA | NA | NA | 401.82 | | |
| **ROST-4-PZ(G)** | | | | | | | | | | |
| 2Q11 | 442.13 | 4/25/2011 | NE | 38.08 | NA | NA | NA | 404.05 | 407.85 - 397.85 (34.28 - 44.28) | |
| 3Q11 | 442.13 | 7/5/2011 | NE | 35.76 | NA | NA | NA | 406.37 | | |
| 1Q12 | 442.13 | 1/3/2012 | NE | 37.44 | NA | NA | NA | 404.69 | | |
| 2Q12 | 442.13 | 4/2/2012 | NE | 38.61 | NA | NA | NA | 403.52 | | |
| 3Q12 | 442.13 | 7/2/2012 | NE | 38.79 | NA | NA | NA | 403.34 | | |
| 4Q12 | 442.13 | 10/1/2012 | NE | 40.54 | NA | NA | NA | 401.59 | | |
| 1Q13 | 442.13 | 1/2/2013 | NE | 41.49 | NA | NA | NA | 400.64 | | |
| **ROST-5-PZ** | ***(PERCHED WELL)*** | | | | | | | | | |
| 4Q10 | 442.22 | 11/12/2010 | NE | NE | NA | NA | NA | NA | 429.02 - 419.02 (13.20 - 23.20) | Well Dry |
| 1Q11 | 442.22 | 1/13/2011 | NE | NE | NA | NA | NA | NA | | Well Dry |
| 2Q11 | 442.22 | 4/25/2011 | NE | NE | NA | NA | NA | NA | | Well Dry |
| 3Q11 | 442.22 | 7/5/2011 | NE | NE | NA | NA | NA | NA | | Well Dry |
| | 442.22 | 9/19/2011 | NE | NE | NA | NA | NA | NA | | Well Dry |
| 4Q11 | 442.22 | 10/5/2011 | NE | NE | NA | NA | NA | NA | | Well Dry |
| 1Q12 | 442.22 | 1/3/2012 | NE | NE | NA | NA | NA | NA | | Well Dry |
| 2Q12 | 442.22 | 4/2/2012 | NE | NE | NA | NA | NA | NA | | Well Dry |
| 3Q12 | 442.22 | 7/2/2012 | NE | NE | NA | NA | NA | NA | | Well Dry |
| 4Q12 | 442.22 | 10/1/2012 | NE | NE | NA | NA | NA | NA | | Well Dry |
| 1Q13 | 442.22 | 1/2/2013 | NE | NE | NA | NA | NA | NA | | Well Dry |

**TABLE 1**
**CUMULATIVE GROUNDWATER MONITORING WELL GAUGING RESULTS**

| WELL ID | TOP OF CASING (elev.[1]) | DATE GAUGED | DEPTH TO PRODUCT (ft btoc) | DEPTH TO WATER (ft btoc) | WATER-PRODUCT INTERFACE (elev.[1]) | PRODUCT (elev.[1]) | PRODUCT THICKNESS (ft) | CORRECTED WATER LEVEL[2] (elev.[1]) | SCREENED INTERVAL (elev.[1]) (ft btoc) | COMMENTS |
|---|---|---|---|---|---|---|---|---|---|---|
| **ROST-7-PZ** | ***(PERCHED WELL)*** | | | | | | | | | |
| 4Q10 | 442.19 | 11/12/2010 | NE | 22.93 | NA | NA | NA | 419.26 | 422.19 - 412.19 (20.00 - 30.00) | |
| 1Q11 | 442.19 | 1/13/2011 | NE | 23.74 | NA | NA | NA | 418.45 | | |
| 2Q11 | 442.19 | 4/25/2011 | NE | 23.72 | NA | NA | NA | 418.47 | | |
| 3Q11 | 442.19 | 7/5/2011 | NE | 22.05 | NA | NA | NA | 420.14 | | |
| | 442.19 | 9/19/2011 | NE | 22.63 | NA | NA | NA | 419.56 | | |
| 4Q11 | 442.19 | 10/5/2011 | NE | 22.52 | NA | NA | NA | 419.67 | | |
| 1Q12 | 442.19 | 1/3/2012 | NE | 23.64 | NA | NA | NA | 418.55 | | |
| 2Q12 | 442.19 | 4/2/2012 | NE | 24.08 | NA | NA | NA | 418.11 | | |
| 3Q12 | 442.19 | 7/2/2012 | NE | 23.33 | NA | NA | NA | 418.86 | | |
| 4Q12 | 442.19 | 10/1/2012 | NE | 23.86 | NA | NA | NA | 418.33 | | |
| 1Q13 | 442.19 | 1/3/2013 | NM | NM | NA | NA | NA | NA | | Well inaccessible |
| **ROST-10-PZ** | ***(PERCHED WELL)*** | | | | | | | | | |
| 4Q10 | 444.51 | 11/12/2010 | NE | NE | NA | NA | NA | NA | 434.51 - 424.51 (10.00 - 20.00) | Well Dry |
| 1Q11 | 444.51 | 1/13/2011 | NE | NE | NA | NA | NA | NA | | Well Dry |
| 2Q11 | 444.51 | 4/25/2011 | NE | NE | NA | NA | NA | NA | | Well Dry |
| 3Q11 | 444.51 | 7/5/2011 | NE | 19.67 | NA | NA | NA | 424.84 | | |
| | 444.51 | 9/19/2011 | NE | 19.88 | NA | NA | NA | 424.63 | | |
| 4Q11 | 444.51 | 10/5/2011 | NE | NE | NA | NA | NA | NA | | Well Dry |
| 1Q12 | 444.51 | 1/3/2012 | NE | NE | NA | NA | NA | NA | | Well Dry |
| 2Q12 | 444.51 | 4/2/2012 | NE | NE | NA | NA | NA | NA | | Well Dry |
| 3Q12 | 444.51 | 7/2/2012 | NE | NE | NA | NA | NA | NA | | Well Dry |
| 4Q12 | 444.51 | 10/1/2012 | NE | NE | NA | NA | NA | NA | | Well Dry |
| 1Q13 | 444.51 | 1/3/2013 | NE | NE | NA | NA | NA | NA | | Well Dry |
| **ROST-21-PZ** | ***(PERCHED WELL)*** | | | | | | | | | |
| 4Q10 | 443.72 | 11/12/2010 | NE | 19.30 | NA | NA | NA | 424.42 | 433.72 - 423.72 (10.00 - 20.00) | |
| 1Q11 | 443.72 | 1/13/2011 | NE | 19.59 | NA | NA | NA | 424.13 | | |
| 2Q11 | 443.72 | 4/25/2011 | NE | 19.04 | NA | NA | NA | 424.68 | | |
| 3Q11 | 443.72 | 7/5/2011 | NE | 18.37 | NA | NA | NA | 425.35 | | |
| | 443.72 | 9/19/2011 | NE | 19.26 | NA | NA | NA | 424.46 | | |
| 4Q11 | 443.72 | 10/5/2011 | NE | NE | NA | NA | NA | NA | | Well Dry |
| 1Q12 | 443.72 | 1/3/2012 | NE | 19.81 | NA | NA | NA | 423.91 | | |
| 2Q12 | 443.72 | 4/2/2012 | NE | NE | NA | NA | NA | NA | | Well Dry |
| 3Q12 | 443.72 | 7/2/2012 | NE | 19.34 | NA | NA | NA | 424.38 | | |
| 4Q12 | 443.72 | 10/1/2012 | NE | NE | NA | NA | NA | NA | | Well Dry |
| 1Q13 | 443.72 | 1/3/2013 | NE | NE | NA | NA | NA | NA | | Well Dry |
| **S-1** | | | | | | | | | | |
| 2Q10 | 443.79 | 4/1/2010 | 39.38 | 44.32 | 399.47 | 404.41 | 4.94 | 403.42 | Unknown | Product confirmed on interface probe. |
| 3Q10 | 443.79 | 7/1/2010 | 38.27 | 43.29 | 400.50 | 405.52 | 5.02 | 404.52 | | Product confirmed on interface probe. |
| 4Q10 | 443.79 | 11/11/2010 | 36.96 | 41.91 | 401.88 | 406.83 | 4.95 | 405.84 | | |
| 1Q11 | 443.79 | 1/13/2011 | 36.41 | 41.33 | 402.46 | 407.38 | 4.92 | 406.40 | | |
| 2Q11 | 443.79 | 4/25/2011 | 38.70 | 38.73 | 405.06 | 405.09 | 0.03 | 405.08 | | |
| 3Q11 | 443.79 | 7/5/2011 | 36.50 | 36.54 | 407.25 | 407.29 | 0.04 | 407.28 | | |
| | 443.79 | 9/19/2011 | NE | 36.42 | NA | NA | NA | 407.37 | | |
| 4Q11 | 443.79 | 10/6/2011 | NE | 36.68 | NA | NA | NA | 407.11 | | |
| 1Q12 | 443.79 | 1/3/2012 | NE | 38.36 | NA | NA | NA | 405.43 | | |
| 2Q12 | 443.79 | 4/3/2012 | NE | 39.83 | NA | NA | NA | 403.96 | | |
| 3Q12 | 443.79 | 7/3/2012 | NE | 40.38 | NA | NA | NA | 403.41 | | |
| 4Q12 | 443.79 | 10/1/2012 | NE | 41.93 | NA | NA | NA | 401.86 | | |
| 1Q13 | 443.79 | 1/4/2013 | NE | 43.35 | NA | NA | NA | 400.44 | | |
| **T-1** | | | | | | | | | | |
| 2Q10 | 444.55 | 4/1/2010 | NE | 45.51 | NA | NA | NA | 399.04 | 396.92 - 373.00 (47.63 - 71.55) | |
| 3Q10 | 444.55 | 7/1/2010 | NM | NM | NA | NA | NA | NA | | Area flooded, unable to access. |
| 4Q10 | 444.55 | 11/11/2010 | NE | 39.08 | NA | NA | NA | 406.32 | | * |
| 1Q11 | 444.55 | 1/13/2011 | NE | 41.02 | NA | NA | NA | 403.53 | | * |
| 2Q11 | 444.55 | 4/25/2011 | NE | 46.65 | NA | NA | NA | 397.90 | | |
| 3Q11 | 444.55 | 7/5/2011 | NE | 35.99 | NA | NA | NA | 408.56 | | * |
| | 444.55 | 9/19/2011 | NE | 51.50 | NA | NA | NA | 393.05 | | |
| 4Q11 | 444.55 | 10/6/2011 | NE | 50.83 | NA | NA | NA | 393.72 | | |
| 1Q12 | 445.40 | 1/3/2012 | NE | NM | NA | NA | NA | NA | 398.40 - 388.40 (43.91 - 53.91) | Well Could Not Be Opened |
| 2Q12 | 445.40 | 4/2/2012 | NE | 40.09 | NA | NA | NA | 405.31 | | * |
| 3Q12 | 445.40 | 7/2/2012 | NE | 41.19 | NA | NA | NA | 404.21 | | * |
| 4Q12 | 445.40 | 10/1/2012 | NE | 42.90 | NA | NA | NA | 402.50 | | * |
| 1Q13 | 445.40 | 1/3/2013 | NE | 44.17 | NA | NA | NA | 401.23 | | * |
| **T-2** | | | | | | | | | | |
| 2Q10 | 443.13 | 4/1/2010 | NE | 40.35 | NA | NA | NA | 402.78 | 392.63 - 372.48 (50.50 - 70.65) | * |
| 3Q10 | 443.13 | 7/1/2010 | NE | 39.16 | NA | NA | NA | 403.97 | | * |
| 4Q10 | 443.13 | 11/11/2010 | NE | 37.51 | NA | NA | NA | 405.62 | | * |
| 1Q11 | 443.13 | 1/13/2011 | NE | 36.97 | NA | NA | NA | 406.16 | | * |
| 2Q11 | 443.13 | 4/25/2011 | NE | 38.03 | NA | NA | NA | 405.10 | | * |
| 3Q11 | 443.13 | 7/5/2011 | NE | 35.89 | NA | NA | NA | 407.24 | | * |
| | 443.13 | 9/19/2011 | NE | 35.80 | NA | NA | NA | 407.33 | | * |
| 4Q11 | 443.13 | 10/6/2011 | NE | 35.97 | NA | NA | NA | 407.16 | | * |
| 1Q12 | 443.13 | 1/3/2012 | NE | 34.44 | NA | NA | NA | 408.69 | | * |
| 2Q12 | 443.13 | 4/2/2012 | NE | 38.68 | NA | NA | NA | 404.45 | | * |
| 3Q12 | 443.13 | 7/2/2012 | NE | 39.15 | NA | NA | NA | 403.98 | | * |
| 4Q12 | 443.13 | 10/1/2012 | NE | 41.11 | NA | NA | NA | 402.02 | | * |
| 1Q13 | 443.13 | 1/3/2013 | NE | 43.39 | NA | NA | NA | 399.74 | | * |

**TABLE 1**
**CUMULATIVE GROUNDWATER MONITORING WELL GAUGING RESULTS**

| WELL ID | TOP OF CASING (elev.[1]) | DATE GAUGED | DEPTH TO PRODUCT (ft btoc) | DEPTH TO WATER (ft btoc) | WATER-PRODUCT INTERFACE (elev.[1]) | PRODUCT (elev.[1]) | PRODUCT THICKNESS (ft) | CORRECTED WATER LEVEL[2] (elev.[1]) | SCREENED INTERVAL (elev.[1]) (ft btoc) | COMMENTS |
|---|---|---|---|---|---|---|---|---|---|---|
| **T-3** | | | | | | | | | | |
| 2Q10 | 450.91 | 4/1/2010 | NE | 48.84 | NA | NA | NA | 402.07 | 403.65 - 388.65 (47.26 - 62.26) | |
| 3Q10 | 450.91 | 7/1/2010 | NE | 48.07 | NA | NA | NA | 402.84 | | |
| 4Q10 | 450.91 | 10/1/2010 | NE | 45.66 | NA | NA | NA | 405.25 | | * |
| 1Q11 | 450.91 | 1/13/2011 | NE | 44.64 | NA | NA | NA | 406.27 | | * |
| 2Q11 | 450.91 | 4/1/2011 | NE | 46.50 | NA | NA | NA | 404.41 | | * |
| 3Q11 | 450.91 | 7/5/2011 | NE | 43.85 | NA | NA | NA | 407.06 | | * |
| | 450.91 | 9/19/2011 | NE | 44.60 | NA | NA | NA | 406.31 | | * |
| 4Q11 | 450.91 | 10/6/2011 | NE | 45.68 | NA | NA | NA | 405.23 | | * |
| 1Q12 | 450.91 | 1/4/2012 | NE | 45.83 | NA | NA | NA | 405.08 | | * |
| 2Q12 | 450.91 | 4/2/2012 | NE | 47.09 | NA | NA | NA | 403.82 | | * |
| 3Q12 | 450.91 | 7/2/2012 | NE | 48.00 | NA | NA | NA | 402.91 | | |
| 4Q12 | 450.91 | 10/1/2012 | NE | 50.04 | NA | NA | NA | 400.87 | | |
| 1Q13 | 450.91 | 1/4/2013 | NE | 51.55 | NA | NA | NA | 399.36 | | |
| **T-4** | | | | | | | | | | |
| 2Q10 | 447.95 | 4/1/2010 | NE | 46.44 | NA | NA | NA | 401.51 | 398.24 - 383.24 (49.71 - 64.71) | * |
| 3Q10 | 447.95 | 7/1/2010 | NE | 45.22 | NA | NA | NA | 402.73 | | * |
| 4Q10 | 447.95 | 10/1/2010 | NE | 42.99 | NA | NA | NA | 404.96 | | * |
| 1Q11 | 447.95 | 1/13/2011 | NE | 41.38 | NA | NA | NA | 406.57 | | * |
| 2Q11 | 447.95 | 4/1/2011 | NE | 42.23 | NA | NA | NA | 405.72 | | * |
| 3Q11 | 447.95 | 7/5/2011 | NE | 39.83 | NA | NA | NA | 408.12 | | * |
| | 447.95 | 9/19/2011 | NE | 41.97 | NA | NA | NA | 405.98 | | * |
| 4Q11 | 447.95 | 10/6/2011 | NE | 42.04 | NA | NA | NA | 405.91 | | * |
| 1Q12 | 447.95 | 1/3/2012 | NE | 43.35 | NA | NA | NA | 404.60 | | * |
| 2Q12 | 447.95 | 4/3/2012 | NE | 45.47 | NA | NA | NA | 402.48 | | * |
| 3Q12 | 447.95 | 7/3/2012 | NE | 46.57 | NA | NA | NA | 401.38 | | * |
| 4Q12 | 447.95 | 10/1/2012 | NE | 46.78 | NA | NA | NA | 401.17 | | * |
| 1Q13 | 447.95 | 1/4/2013 | NE | 48.60 | NA | NA | NA | 399.35 | | * |
| **T-5** | | | | | | | | | | |
| 2Q10 | 443.46 | 4/1/2010 | NE | 39.28 | NA | NA | NA | 404.18 | 395.13 - 378.58 (48.33 - 64.88) | * |
| 3Q10 | 443.46 | 7/1/2010 | NM | NM | NA | NA | NA | NA | | Tank yard flooded, unable to access. |
| 4Q10 | 443.46 | 10/1/2010 | NE | 36.59 | NA | NA | NA | 406.87 | | * |
| 1Q11 | 443.46 | 1/1/2011 | NE | 36.09 | NA | NA | NA | 407.37 | | * |
| 2Q11 | 443.46 | 4/1/2011 | NE | 37.30 | NA | NA | NA | 406.16 | | * |
| 3Q11 | 443.46 | 7/5/2011 | NE | 35.28 | NA | NA | NA | 408.18 | | * |
| 4Q11 | 443.46 | 10/6/2011 | NE | 35.84 | NA | NA | NA | 407.62 | | * |
| 1Q12 | 443.46 | 1/3/2012 | NE | 37.31 | NA | NA | NA | 406.15 | | * |
| 2Q12 | 443.46 | 4/3/2012 | NE | 38.87 | NA | NA | NA | 404.59 | | * |
| 3Q12 | 443.46 | 7/6/2012 | NE | 39.81 | NA | NA | NA | 403.65 | | * |
| 4Q12 | 443.46 | 10/1/2012 | NE | 41.08 | NA | NA | NA | 402.38 | | * |
| 1Q13 | 443.46 | 1/4/2013 | NE | 42.57 | NA | NA | NA | 400.89 | | * |
| **T-6** | | | | | | | | | | |
| 2Q10 | 446.55 | 4/1/2010 | NE | 42.83 | NA | NA | NA | 403.72 | 394.79 - 380.54 (51.76 - 66.01) | * |
| 3Q10 | 446.55 | 7/1/2010 | NE | 41.74 | NA | NA | NA | 404.81 | | * |
| 4Q10 | 446.55 | 11/12/2010 | NE | 40.77 | NA | NA | NA | 405.78 | | * |
| 1Q11 | 446.55 | 1/13/2011 | NE | 41.07 | NA | NA | NA | 405.48 | | * |
| 2Q11 | 446.55 | 4/25/2011 | NE | 42.01 | NA | NA | NA | 404.54 | | * |
| 3Q11 | 446.55 | 7/5/2011 | NE | 39.58 | NA | NA | NA | 406.97 | | * |
| | 446.55 | 9/19/2011 | NE | 38.95 | NA | NA | NA | 407.60 | | * |
| 4Q11 | 446.55 | 10/6/2011 | NE | 39.26 | NA | NA | NA | 407.29 | | * |
| 1Q12 | 446.55 | 1/4/2012 | NE | 41.46 | NA | NA | NA | 405.09 | | * |
| 2Q12 | 446.55 | 4/3/2012 | NE | 42.88 | NA | NA | NA | 403.67 | | * |
| 3Q12 | 446.55 | 7/5/2012 | NE | 43.06 | NA | NA | NA | 403.49 | | * |
| 4Q12 | 446.55 | 10/2/2012 | NE | 44.86 | NA | NA | NA | 401.69 | | * |
| 1Q13 | 446.55 | 1/4/2013 | NE | 45.84 | NA | NA | NA | 400.71 | | * |
| **T-7** | | | | | | | | | | |
| 2Q10 | 444.01 | 4/1/2010 | 38.74 | 38.89 | 405.12 | 405.27 | 0.15 | 405.24 | 395.29 - 380.29 (48.72 - 63.72) | *Product confirmed on interface probe. |
| 3Q10 | 444.01 | 7/1/2010 | 37.21 | 37.37 | 406.64 | 406.80 | 0.16 | 406.77 | | *Product confirmed on interface probe. |
| 4Q10 | 444.01 | 10/1/2010 | 36.24 | 36.40 | 407.61 | 407.77 | 0.16 | 407.74 | | *Product confirmed on interface probe. |
| 1Q11 | 444.01 | 1/13/2011 | 36.74 | 36.87 | 407.14 | 407.27 | 0.13 | 407.24 | | * |
| 2Q11 | 444.01 | 4/1/2011 | 37.20 | 37.25 | 406.76 | 406.81 | 0.05 | 406.80 | | * |
| 3Q11 | 444.01 | 7/5/2011 | 35.08 | 35.16 | 408.85 | 408.93 | 0.08 | 408.91 | | * |
| | 444.01 | 9/19/2011 | 35.14 | 35.19 | 408.82 | 408.87 | 0.05 | 408.86 | | * |
| 4Q11 | 444.01 | 10/5/2011 | 35.36 | 35.43 | 408.58 | 408.65 | 0.07 | 408.64 | | * |
| 1Q12 | 444.01 | 1/4/2012 | 37.05 | 37.08 | 406.93 | 406.96 | 0.03 | 406.95 | | * |
| 2Q12 | 444.01 | 4/3/2012 | 38.45 | 38.45 | 405.56 | 405.56 | 0.00 | 405.56 | | * |
| 3Q12 | 444.01 | 7/2/2012 | 38.90 | 38.96 | 405.05 | 405.11 | 0.06 | 405.10 | | * |
| 4Q12 | 444.01 | 10/2/2012 | 40.80 | 40.83 | 403.18 | 403.21 | 0.03 | 403.20 | | * |
| 1Q13 | 444.01 | 1/2/2013 | 41.66 | 41.67 | 402.34 | 402.35 | 0.01 | 402.35 | | * |
| **T-12** | | | | | | | | | | |
| 2Q10 | 444.69 | 4/1/2010 | NE | 41.59 | NA | NA | NA | 403.10 | 398.23 - 372.23 (46.46 - 72.46) | * |
| 3Q10 | 444.69 | 7/1/2010 | NE | 41.21 | NA | NA | NA | 403.48 | | * |
| 4Q10 | 444.69 | 11/12/2010 | NE | 40.35 | NA | NA | NA | 404.34 | | * |
| 1Q11 | 444.69 | 1/13/2011 | NE | 40.30 | NA | NA | NA | 404.39 | | * |
| 2Q11 | 444.69 | 4/25/2011 | NE | 41.40 | NA | NA | NA | 403.29 | | * |
| 3Q11 | 444.69 | 7/5/2011 | NE | 39.07 | NA | NA | NA | 405.62 | | * |
| | 444.69 | 9/19/2011 | NE | 38.06 | NA | NA | NA | 406.63 | | * |
| 4Q11 | 444.69 | 10/6/2011 | NE | 38.23 | NA | NA | NA | 406.46 | | * |
| 1Q12 | 444.69 | 1/4/2012 | NE | 40.64 | NA | NA | NA | 404.05 | | * |
| 2Q12 | 444.69 | 4/3/2012 | NE | 42.06 | NA | NA | NA | 402.63 | | * |
| 3Q12 | 444.69 | 7/5/2012 | NE | 42.05 | NA | NA | NA | 402.64 | | * |
| 4Q12 | 444.69 | 10/2/2012 | NE | 43.86 | NA | NA | NA | 400.83 | | * |
| 1Q13 | 444.69 | 1/4/2013 | NE | 44.65 | NA | NA | NA | 400.04 | | * |

**TABLE 1**
**CUMULATIVE GROUNDWATER MONITORING WELL GAUGING RESULTS**

| WELL ID | TOP OF CASING (elev.[1]) | DATE GAUGED | DEPTH TO PRODUCT (ft btoc) | DEPTH TO WATER (ft btoc) | WATER-PRODUCT INTERFACE (elev.[1]) | PRODUCT (elev.[1]) | PRODUCT THICKNESS (ft) | CORRECTED WATER LEVEL[2] (elev.[1]) | SCREENED INTERVAL (elev.[1]) (ft btoc) | COMMENTS |
|---|---|---|---|---|---|---|---|---|---|---|
| **T-13** | | | | | | | | | | |
| 2Q10 | 443.46 | 4/1/2010 | NE | 40.02 | NA | NA | NA | 403.44 | 396.46 - 370.46 (47.00 - 73.00) | * |
| 3Q10 | 443.46 | 7/1/2010 | NE | 38.72 | NA | NA | NA | 404.74 | | * |
| 4Q10 | 443.46 | 11/11/2010 | NE | 37.37 | NA | NA | NA | 406.09 | | * |
| 1Q11 | 443.46 | 1/13/2011 | NE | 37.57 | NA | NA | NA | 405.89 | | * |
| 2Q11 | 443.46 | 4/25/2011 | NE | 38.25 | NA | NA | NA | 405.21 | | * |
| 3Q11 | 443.46 | 7/5/2011 | NE | NM | NA | NA | NA | NA | | |
| | 443.46 | 9/19/2011 | NE | 37.54 | NA | NA | NA | 405.92 | | * |
| 4Q11 | 443.46 | 10/5/2011 | NE | 35.78 | NA | NA | NA | 407.68 | | * |
| 1Q12 | 443.46 | 1/3/2012 | NE | 37.42 | NA | NA | NA | 406.04 | | * |
| 2Q12 | 443.46 | 4/2/2012 | NE | 38.69 | NA | NA | NA | 404.77 | | * |
| 3Q12 | 443.46 | 7/2/2012 | NE | 39.09 | NA | NA | NA | 404.37 | | * |
| 4Q12 | 443.46 | 10/2/2012 | NE | 40.81 | NA | NA | NA | 402.65 | | * |
| 1Q13 | 443.46 | 1/2/2013 | NE | 41.96 | NA | NA | NA | 401.50 | | * |
| **T-15** | | | | | | | | | | |
| 2Q10 | 445.03 | 4/1/2010 | NE | 42.39 | NA | NA | NA | 402.64 | 396.99 - 370.99 (48.04 - 74.04) | * |
| 3Q10 | 445.03 | 7/1/2010 | NE | 41.07 | NA | NA | NA | 403.96 | | * |
| 4Q10 | 445.03 | 10/1/2010 | NE | 39.31 | NA | NA | NA | 405.72 | | * |
| 1Q11 | 445.03 | 1/13/2011 | NE | 38.39 | NA | NA | NA | 406.64 | | * |
| 2Q11 | 445.03 | 4/1/2011 | NE | 39.55 | NA | NA | NA | 405.48 | | * |
| 3Q11 | 445.03 | 7/5/2011 | NE | 37.35 | NA | NA | NA | 407.68 | | * |
| | 445.03 | 9/19/2011 | NE | 37.59 | NA | NA | NA | 407.44 | | * |
| 4Q11 | 445.03 | 10/6/2011 | NE | 37.79 | NA | NA | NA | 407.24 | | * |
| 1Q12 | 445.03 | 1/3/2012 | NE | 38.97 | NA | NA | NA | 406.06 | | * |
| 2Q12 | 445.03 | 4/2/2012 | NE | 40.28 | NA | NA | NA | 404.75 | | * |
| 3Q12 | 445.03 | 7/2/2012 | NE | 40.90 | NA | NA | NA | 404.13 | | * |
| 4Q12 | 445.03 | 10/1/2012 | NE | 42.81 | NA | NA | NA | 402.22 | | * |
| 1Q13 | 445.03 | 1/3/2013 | NE | 44.24 | NA | NA | NA | 400.79 | | * |
| **T-17** | | | | | | | | | | |
| 2Q10 | 445.90 | 4/1/2010 | NE | 41.12 | NA | NA | NA | 404.78 | 401.80 - 375.80 (44.10 - 70.10) | * |
| 3Q10 | 445.90 | 7/1/2010 | NE | 39.60 | NA | NA | NA | 406.30 | | * |
| 4Q10 | 445.90 | 10/1/2010 | NE | 38.11 | NA | NA | NA | 407.79 | | * |
| 1Q11 | 445.90 | 1/13/2011 | NE | 37.11 | NA | NA | NA | 408.79 | | * |
| 2Q11 | 445.90 | 4/1/2011 | NE | 37.30 | NA | NA | NA | 408.60 | | * |
| 3Q11 | 445.90 | 7/5/2011 | NE | 35.17 | NA | NA | NA | 410.73 | | * |
| | 445.90 | 9/19/2011 | NE | 35.90 | NA | NA | NA | 410.00 | | * |
| 4Q11 | 445.90 | 10/6/2011 | NE | 36.23 | NA | NA | NA | 409.67 | | * |
| 1Q12 | 445.90 | 1/3/2012 | NE | 37.37 | NA | NA | NA | 408.53 | | * |
| 2Q12 | 445.90 | 4/2/2012 | NE | 38.79 | NA | NA | NA | 407.11 | | * |
| 3Q12 | 445.90 | 7/2/2012 | NE | 39.29 | NA | NA | NA | 406.61 | | * |
| 4Q12 | 445.90 | 10/1/2012 | NE | 40.92 | NA | NA | NA | 404.98 | | * |
| 1Q13 | 445.90 | 1/3/2013 | NE | 42.70 | NA | NA | NA | 403.20 | | * |
| **T-19** | | | | | | | | | | |
| 2Q10 | 446.71 | 4/1/2010 | 44.64 | 46.11 | 400.60 | 402.07 | 1.47 | 401.78 | 395.94 - 369.94 (50.77 - 76.77) | *Product confirmed on interface probe. |
| 3Q10 | 446.71 | 7/1/2010 | 43.47 | 44.91 | 401.80 | 403.24 | 1.44 | 402.95 | | *Product confirmed on interface probe. |
| 4Q10 | 446.71 | 10/1/2010 | 41.39 | 42.73 | 403.98 | 405.32 | 1.34 | 405.05 | | *Product confirmed on interface probe. |
| 1Q11 | 446.71 | 1/13/2011 | 39.78 | 41.15 | 405.56 | 406.93 | 1.37 | 406.66 | | * |
| 2Q11 | 446.71 | 4/1/2011 | 40.88 | 40.90 | 405.81 | 405.83 | 0.02 | 405.83 | | * |
| 3Q11 | 446.71 | 7/5/2011 | 38.47 | 38.50 | 408.21 | 408.24 | 0.03 | 408.23 | | * |
| | 446.71 | 9/19/2011 | 40.60 | 40.64 | 406.07 | 406.11 | 0.04 | 406.10 | | * |
| 4Q11 | 446.71 | 10/6/2011 | 40.65 | 40.69 | 406.02 | 406.06 | 0.04 | 406.05 | | * |
| 1Q12 | 446.71 | 1/3/2012 | 41.97 | 41.98 | 404.73 | 404.74 | 0.01 | 404.74 | | * |
| 2Q12 | 446.71 | 4/3/2012 | NE | 44.09 | NA | NA | NA | 402.62 | | * |
| 3Q12 | 446.71 | 7/3/2012 | NE | 45.36 | NA | NA | NA | 401.35 | | * |
| 4Q12 | 446.71 | 10/1/2012 | NE | 45.41 | NA | NA | NA | 401.30 | | * |
| 1Q13 | 446.71 | 1/4/2013 | NE | 47.44 | NA | NA | NA | 399.27 | | * |
| **T-21** | | | | | | | | | | |
| 2Q10 | 444.00 | 4/1/2010 | NE | 32.11 | NA | NA | NA | 411.89 | 412.04 - 386.04 (31.96 - 57.96) | |
| 3Q10 | 444.00 | 7/1/2010 | NE | 30.79 | NA | NA | NA | 413.21 | | * |
| 4Q10 | 444.00 | 10/1/2010 | NE | 29.65 | NA | NA | NA | 414.35 | | * |
| 1Q11 | 444.00 | 1/13/2011 | NE | 29.96 | NA | NA | NA | 414.04 | | * |
| 2Q11 | 444.00 | 4/1/2011 | NE | 29.83 | NA | NA | NA | 414.17 | | * |
| 3Q11 | 444.00 | 7/5/2011 | NE | 28.17 | NA | NA | NA | 415.83 | | * |
| | 444.00 | 9/19/2011 | NE | 28.24 | NA | NA | NA | 415.76 | | * |
| 4Q11 | 444.00 | 10/5/2011 | NE | 28.41 | NA | NA | NA | 415.59 | | * |
| 1Q12 | 444.00 | 1/4/2012 | NE | 29.56 | NA | NA | NA | 414.44 | | * |
| 2Q12 | 444.00 | 4/3/2012 | NE | 30.65 | NA | NA | NA | 413.35 | | * |
| 3Q12 | 444.00 | 7/2/2012 | NE | 31.14 | NA | NA | NA | 412.86 | | * |
| 4Q12 | 444.00 | 10/2/2012 | NE | 32.62 | NA | NA | NA | 411.38 | | |
| 1Q13 | 444.00 | 1/2/2013 | NE | 33.96 | NA | NA | NA | 410.04 | | |
| **T-22** | | | | | | | | | | |
| 2Q10 | 442.21 | 4/1/2010 | NE | 32.69 | NA | NA | NA | 409.52 | 410.66 - 384.96 (31.55 - 57.25) | |
| 3Q10 | 442.21 | 7/1/2010 | NE | 31.11 | NA | NA | NA | 411.10 | | * |
| 4Q10 | 442.21 | 10/1/2010 | NE | 30.12 | NA | NA | NA | 412.09 | | * |
| 1Q11 | 442.21 | 1/13/2011 | NE | 31.04 | NA | NA | NA | 411.17 | | * |
| 2Q11 | 442.21 | 4/1/2011 | NE | 30.96 | NA | NA | NA | 411.25 | | * |
| 3Q11 | 442.21 | 7/5/2011 | NE | 29.00 | NA | NA | NA | 413.21 | | * |
| | 442.21 | 9/19/2011 | NE | 29.26 | NA | NA | NA | 412.95 | | * |
| 4Q11 | 442.21 | 10/5/2011 | NE | 29.51 | NA | NA | NA | 412.70 | | * |
| 1Q12 | 442.21 | 1/4/2012 | NE | 30.91 | NA | NA | NA | 411.30 | | * |
| 2Q12 | 442.21 | 4/3/2012 | NE | 32.34 | NA | NA | NA | 409.87 | | |
| 3Q12 | 442.21 | 7/2/2012 | NE | 32.81 | NA | NA | NA | 409.40 | | |
| 4Q12 | 442.21 | 10/2/2012 | NE | 34.45 | NA | NA | NA | 407.76 | | |
| 1Q13 | 442.21 | 1/2/2013 | NE | 35.62 | NA | NA | NA | 406.59 | | |

**TABLE 1**
**CUMULATIVE GROUNDWATER MONITORING WELL GAUGING RESULTS**

| WELL ID | TOP OF CASING (elev.[1]) | DATE GAUGED | DEPTH TO PRODUCT (ft btoc) | DEPTH TO WATER (ft btoc) | WATER-PRODUCT INTERFACE (elev.[1]) | PRODUCT (elev.[1]) | PRODUCT THICKNESS (ft) | CORRECTED WATER LEVEL[2] (elev.[1]) | SCREENED INTERVAL (elev.[1]) (ft btoc) | COMMENTS |
|---|---|---|---|---|---|---|---|---|---|---|
| **T-23** | | | | | | | | | | |
| 2Q10 | 432.64 | 4/1/2010 | NE | 25.00 | NA | NA | NA | 407.64 | 405.41 - 379.41 (27.23 - 53.23) | * |
| 3Q10 | 432.64 | 7/1/2010 | NE | 23.35 | NA | NA | NA | 409.29 | | * |
| 4Q10 | 432.64 | 10/1/2010 | NE | 22.41 | NA | NA | NA | 410.23 | | * |
| 1Q11 | 432.64 | 1/13/2011 | NE | 23.83 | NA | NA | NA | 408.81 | | * |
| 2Q11 | 432.64 | 4/1/2011 | NE | 23.40 | NA | NA | NA | 409.24 | | * |
| 3Q11 | 432.64 | 7/5/2011 | NE | 21.22 | NA | NA | NA | 411.42 | | * |
| | 432.64 | 9/19/2011 | NE | 27.83 | NA | NA | NA | 404.81 | | |
| 4Q11 | 432.64 | 10/5/2011 | NE | 22.21 | NA | NA | NA | 410.43 | | * |
| 1Q12 | 432.64 | 1/3/2012 | NE | 23.75 | NA | NA | NA | 408.89 | | * |
| 2Q12 | 432.64 | 4/2/2012 | NE | 25.10 | NA | NA | NA | 407.54 | | * |
| 3Q12 | 432.64 | 7/2/2012 | NE | 25.60 | NA | NA | NA | 407.04 | | * |
| 4Q12 | 432.64 | 10/2/2012 | NE | 27.37 | NA | NA | NA | 405.27 | | |
| 1Q13 | 432.64 | 1/3/2013 | NE | 28.35 | NA | NA | NA | 404.29 | | |
| **T-24** | | | | | | | | | | |
| 2Q10 | 443.72 | 4/1/2010 | 41.25 | 41.55 | 402.17 | 402.47 | 0.30 | 402.41 | 402.22 - 376.57 (41.50 - 67.15) | *Product confirmed on interface probe. |
| 3Q10 | 443.72 | 7/1/2010 | 40.36 | 40.68 | 403.04 | 403.36 | 0.32 | 403.29 | | *Product confirmed on interface probe. |
| 4Q10 | 443.72 | 11/11/2010 | 39.07 | 39.38 | 404.34 | 404.65 | 0.31 | 404.59 | | * |
| 1Q11 | 443.72 | 1/13/2011 | 38.60 | 38.92 | 404.80 | 405.12 | 0.32 | 405.05 | | * |
| 2Q11 | 443.72 | 4/25/2011 | NE | 39.98 | NA | NA | NA | 403.74 | | * |
| 3Q11 | 443.72 | 7/5/2011 | NE | 37.53 | NA | NA | NA | 406.19 | | * |
| | 443.72 | 9/19/2011 | NE | 35.08 | NA | NA | NA | 408.64 | | * |
| 4Q11 | 443.72 | 10/6/2011 | NE | 37.29 | NA | NA | NA | 406.43 | | * |
| 1Q12 | 443.72 | 1/3/2012 | NE | 38.36 | NA | NA | NA | 405.36 | | * |
| 2Q12 | 443.72 | 4/3/2012 | NE | 40.56 | NA | NA | NA | 403.16 | | * |
| 3Q12 | 443.72 | 7/3/2012 | NE | 40.45 | NA | NA | NA | 403.27 | | * |
| 4Q12 | 443.72 | 10/1/2012 | 42.02 | 44.87 | 398.85 | 401.70 | 2.85 | 401.13 | | |
| 1Q13 | 443.72 | 1/7/2013 | 43.10 | 45.60 | 398.12 | 400.62 | 2.50 | 400.12 | | |
| **T-28** | | | | | | | | | | |
| 2Q10 | 444.22 | 4/1/2010 | NE | 40.94 | NA | NA | NA | 403.28 | Unknown | |
| 3Q10 | 444.22 | 7/1/2010 | NM | NM | NA | NA | NA | NA | | Area regraded; equipment staging yard; unable to locate. |
| 4Q10 | 444.22 | 10/1/2010 | NE | 37.65 | NA | NA | NA | 406.57 | | |
| 1Q11 | 444.22 | 1/13/2011 | NE | 36.53 | NA | NA | NA | 407.69 | | |
| 2Q11 | 444.22 | 4/1/2011 | NE | 37.18 | NA | NA | NA | 407.04 | | |
| 3Q11 | 444.22 | 7/5/2011 | NE | 34.89 | NA | NA | NA | 409.33 | | |
| | 444.22 | 9/19/2011 | NE | 35.75 | NA | NA | NA | 408.47 | | |
| 4Q11 | 444.22 | 10/6/2011 | NE | 35.98 | NA | NA | NA | 408.24 | | |
| 1Q12 | 444.22 | 1/3/2012 | NE | 36.98 | NA | NA | NA | 407.24 | | |
| 2Q12 | 444.22 | 4/2/2012 | NE | 38.68 | NA | NA | NA | 405.54 | | |
| 3Q12 | 444.22 | 7/2/2012 | NE | 39.28 | NA | NA | NA | 404.94 | | * |
| 4Q12 | 444.22 | 10/1/2012 | NE | 40.88 | NA | NA | NA | 403.34 | | * |
| 1Q13 | 444.22 | 1/3/2013 | NE | 42.56 | NA | NA | NA | 401.66 | | * |
| **T-38** | | | | | | | | | | |
| 2Q10 | 445.62 | 4/1/2010 | NE | 38.35 | NA | NA | NA | 407.27 | 396.48 - 376.48 (49.14 - 69.14) | * |
| 3Q10 | 445.62 | 7/1/2010 | NE | 37.00 | NA | NA | NA | 408.62 | | * |
| 4Q10 | 445.62 | 10/1/2010 | NE | 35.45 | NA | NA | NA | 410.17 | | * |
| 1Q11 | 445.62 | 1/1/2011 | NE | 35.38 | NA | NA | NA | 410.24 | | * |
| 3Q11 | 445.62 | 7/5/2011 | NE | NM | NA | NA | NA | NA | | |
| 4Q11 | 445.62 | 10/6/2011 | NE | 34.38 | NA | NA | NA | 411.24 | | * |
| 1Q12 | 445.62 | 1/3/2012 | NE | 35.40 | NA | NA | NA | 410.22 | | * |
| 2Q12 | 445.62 | 4/2/2012 | NE | 36.25 | NA | NA | NA | 409.37 | | * |
| 3Q12 | 445.62 | 7/3/2012 | NE | 37.00 | NA | NA | NA | 408.62 | | * |
| 4Q12 | 445.62 | 10/1/2012 | NE | 38.61 | NA | NA | NA | 407.01 | | * |
| 1Q13 | 445.62 | 1/3/2013 | NE | 40.06 | NA | NA | NA | 405.56 | | * |
| **T-62** | | | | | | | | | | |
| 2Q10 | 431.73 | 4/1/2010 | NE | 25.98 | NA | NA | NA | 405.75 | 412.02 - 382.02 (19.71 - 49.71) | |
| 3Q10 | 431.73 | 7/1/2010 | NE | 23.99 | NA | NA | NA | 407.74 | | |
| 4Q10 | 431.73 | 11/11/2010 | NE | 23.49 | NA | NA | NA | 408.24 | | |
| 1Q11 | 431.73 | 1/13/2011 | NE | 25.48 | NA | NA | NA | 406.25 | | |
| 2Q11 | 431.73 | 4/25/2011 | NE | 25.33 | NA | NA | NA | 406.40 | | |
| 3Q11 | 431.73 | 7/5/2011 | NE | 22.37 | NA | NA | NA | 409.36 | | |
| | 431.73 | 9/19/2011 | NE | 23.12 | NA | NA | NA | 408.61 | | |
| 4Q11 | 431.73 | 10/5/2011 | NE | 23.46 | NA | NA | NA | 408.27 | | |
| 1Q12 | 431.73 | 1/3/2012 | NE | 25.62 | NA | NA | NA | 406.11 | | |
| 2Q12 | 431.73 | 4/2/2012 | NE | 27.08 | NA | NA | NA | 404.65 | | |
| 3Q12 | 431.73 | 7/3/2012 | NE | 27.20 | NA | NA | NA | 404.53 | | |
| 4Q12 | 431.73 | 10/2/2012 | NE | 29.28 | NA | NA | NA | 402.45 | | |
| 1Q13 | 431.73 | 1/7/2013 | NE | 30.39 | NA | NA | NA | 401.34 | | |
| **T-63** | | | | | | | | | | |
| 2Q10 | 431.24 | 4/1/2010 | NE | 25.42 | NA | NA | NA | 405.82 | 411.26 - 381.26 (19.98 - 49.98) | |
| 3Q10 | 431.24 | 7/1/2010 | NE | 23.23 | NA | NA | NA | 408.01 | | |
| 4Q10 | 431.24 | 11/11/2010 | NE | 23.03 | NA | NA | NA | 408.21 | | |
| 1Q11 | 431.24 | 1/13/2011 | NE | 25.45 | NA | NA | NA | 405.79 | | |
| 2Q11 | 431.24 | 4/25/2011 | NE | NM | NA | NA | NA | NA | | Unable to open. |
| 3Q11 | 431.24 | 7/5/2011 | NE | NM | NA | NA | NA | NA | | |
| | 431.24 | 9/19/2011 | NE | 22.88 | NA | NA | NA | 408.36 | | |
| 4Q11 | 431.24 | 10/5/2011 | NE | 23.28 | NA | NA | NA | 407.96 | | |
| 1Q12 | 431.24 | 1/3/2012 | NE | 25.60 | NA | NA | NA | 405.64 | | |
| 2Q12 | 431.24 | 4/2/2012 | NE | NM | NA | NA | NA | NA | | |
| 3Q12 | 431.24 | 7/3/2012 | NE | 27.08 | NA | NA | NA | 404.16 | | |
| 4Q12 | 431.24 | 10/2/2012 | NE | 29.19 | NA | NA | NA | 402.05 | | |
| 1Q13 | 431.24 | 1/7/2013 | NE | 30.45 | NA | NA | NA | 400.79 | | |

**TABLE 1**
**CUMULATIVE GROUNDWATER MONITORING WELL GAUGING RESULTS**

| WELL ID | TOP OF CASING (elev.[1]) | DATE GAUGED | DEPTH TO PRODUCT (ft btoc) | DEPTH TO WATER (ft btoc) | WATER-PRODUCT INTERFACE (elev.[1]) | PRODUCT (elev.[1]) | PRODUCT THICKNESS (ft) | CORRECTED WATER LEVEL[2] (elev.[1]) | SCREENED INTERVAL (elev.[1]) (ft btoc) | COMMENTS |
|---|---|---|---|---|---|---|---|---|---|---|
| **T-64** | | | | | | | | | | |
| 2Q10 | 428.80 | 4/1/2010 | NE | 22.91 | NA | NA | NA | 405.89 | 408.99 - 378.99 (19.81 - 49.81) | |
| 3Q10 | 428.80 | 7/1/2010 | NE | 20.46 | NA | NA | NA | 408.34 | | |
| 4Q10 | 428.80 | 11/11/2010 | NE | 20.76 | NA | NA | NA | 408.04 | | |
| 1Q11 | 428.80 | 1/13/2011 | NE | 23.84 | NA | NA | NA | 404.96 | | |
| 3Q11 | 428.80 | 7/5/2011 | NE | 19.06 | NA | NA | NA | 409.74 | | * |
| | 428.80 | 9/19/2011 | NE | 21.86 | NA | NA | NA | 406.94 | | |
| 4Q11 | 428.80 | 10/5/2011 | NE | 21.36 | NA | NA | NA | 407.44 | | |
| 1Q12 | 428.80 | 1/3/2012 | NE | 23.86 | NA | NA | NA | 404.94 | | |
| 2Q12 | 428.80 | 4/2/2012 | NE | 25.10 | NA | NA | NA | 403.70 | | |
| 3Q12 | 428.80 | 7/3/2012 | NE | 25.24 | NA | NA | NA | 403.56 | | |
| 4Q12 | 428.80 | 10/2/2012 | NE | 27.44 | NA | NA | NA | 401.36 | | |
| 1Q13 | 428.80 | 1/7/2013 | NE | 28.89 | NA | NA | NA | 399.91 | | |
| **PZ-1-101** | | | | | | | | | | |
| 4Q11 | 445.52 | 10/5/2011 | NE | 37.83 | NA | NA | NA | 407.69 | 354.52 - 344.52 (91.00 - 101.00) | * |
| 1Q12 | 445.52 | 1/3/2012 | NE | 39.73 | NA | NA | NA | 405.79 | | * |
| 2Q12 | 445.52 | 4/4/2012 | NE | 41.14 | NA | NA | NA | 404.38 | | * |
| 3Q12 | 445.52 | 7/2/2012 | NE | 41.28 | NA | NA | NA | 404.24 | | * |
| 4Q12 | 445.52 | 10/1/2012 | NE | 42.95 | NA | NA | NA | 402.57 | | * |
| 1Q13 | 445.52 | 1/3/2013 | NE | 44.21 | NA | NA | NA | 401.31 | | * |
| **PZ-1-85** | | | | | | | | | | |
| 4Q11 | 445.50 | 10/5/2011 | NE | 37.85 | NA | NA | NA | 407.65 | 369.70 - 359.70 (75.80 - 85.80) | * |
| 1Q12 | 445.50 | 1/3/2012 | NE | 39.80 | NA | NA | NA | 405.70 | | * |
| 2Q12 | 445.50 | 4/4/2012 | NE | 41.05 | NA | NA | NA | 404.45 | | * |
| 3Q12 | 445.50 | 7/2/2012 | NE | 41.35 | NA | NA | NA | 404.15 | | * |
| 4Q12 | 445.50 | 10/1/2012 | NE | 43.06 | NA | NA | NA | 402.44 | | * |
| 1Q13 | 445.50 | 1/3/2013 | NE | 44.35 | NA | NA | NA | 401.15 | | * |
| **PZ-2-70.5** | | | | | | | | | | |
| 4Q11 | 443.15 | 10/5/2011 | NE | 35.74 | NA | NA | NA | 407.41 | 382.65 - 372.65 (60.50 - 70.50) | * |
| 1Q12 | 443.15 | 1/3/2012 | NE | 38.14 | NA | NA | NA | 405.01 | | * |
| 2Q12 | 443.15 | 4/4/2012 | NE | 39.43 | NA | NA | NA | 403.72 | | * |
| 3Q12 | 443.15 | 7/2/2012 | NE | 39.57 | NA | NA | NA | 403.58 | | * |
| 4Q12 | 443.15 | 10/1/2012 | NE | 41.32 | NA | NA | NA | 401.83 | | * |
| 1Q13 | 443.15 | 1/3/2013 | NE | 42.40 | NA | NA | NA | 400.75 | | * |
| **PZ-2-84** | | | | | | | | | | |
| 4Q11 | 443.12 | 10/5/2011 | NE | 35.71 | NA | NA | NA | 407.41 | 371.12 - 359.12 (72.00 - 84.00) | * |
| 1Q12 | 443.12 | 1/3/2012 | NE | 38.05 | NA | NA | NA | 405.07 | | * |
| 2Q12 | 443.12 | 4/4/2012 | NE | 39.37 | NA | NA | NA | 403.75 | | * |
| 3Q12 | 443.12 | 7/2/2012 | NE | 39.48 | NA | NA | NA | 403.64 | | * |
| 4Q12 | 443.12 | 10/1/2012 | NE | 41.21 | NA | NA | NA | 401.91 | | * |
| 1Q13 | 443.12 | 1/3/2013 | NE | 42.32 | NA | NA | NA | 400.80 | | * |

**NOTES:**
1) Elevations presented in this table are relative to the 1988 USGS datum.
2) The Corrected W.L. Elevations presented in this table were corrected by a specific gravity of 0.80 for the wells in which LNAPL was identified.
3) NA = Not Applicable; NE = Not Encountered; NM = Not Measured
4) * Indicates that the LNAPL and/or water level is above the top of the screened zone of the well.
5) Table includes comprehensive groundwater monitoring well gauging data from the combined Village of Roxana Interim Groundwater Monitoring Program and the WRB Refining LP Wood River Refinery Program.

**TABLE 2**
**SOIL VMP DEPTHS**

| | Yellow 1st Interval | White 10 foot Depth | Blue 2nd Interval | Green 3rd Interval | Red 4th Interval | Notes: |
|---|---|---|---|---|---|---|
| **VMP-1** | 5 | | 8.5 | 23.5 | 38.5 | Village of Roxana - 1st Street |
| **VMP-2** | 5 | | 8.5 | 22 | 42 | Village of Roxana - Alley Between 3rd and 4th Street |
| **VMP-3** | 5 | 10 | 22 | 31.5 | 39 | Village of Roxana - Alley Between 2nd and 3rd Street |
| **VMP-4** | 5 | | 12 | 23.5 | 39 | Village of Roxana - Alley Between 4th and 5th Street |
| **VMP-5** | 5 | | 12.5 | 31 | 40 | Village of Roxana - Alley Between 5th and 6th Street |
| **VMP-6** | 5 | | 10 | 31.5 | 39 | Village of Roxana - Alley Between 6th and 7th Street |
| **VMP-7** | 5 | | 13.5 | 29.5 | 38 | Village of Roxana - 7th Street |
| **VMP-8** | 5 | | 9.5 | 23.5 | 35.5 | Village of Roxana - Alley Between 7th and 8th Street |
| **VMP-9** | 5 | | 11.5 | 25.5 | 38.5 | Village of Roxana - Alley Between 7th and 8th Street |
| **VMP-10** | 5 | | 10 | 20 | 30 | Public Works Yard |
| **VMP-11** | 5 | | 8 | 29 | 38 | Public Works Yard |
| **VMP-12** | 5 | | 11.5 | 25 | 39 | WRR- North Property |
| **VMP-13** | 5 | | 10.5 | 21.5 | 29.5 | Public Works Yard |
| **VMP-14** | 5 | | 11.5 | 20 | 29 | Public Works Yard |
| **VMP-15** | 5 | | 21.5 | 25.5 | 29 | Village of Roxana - SE of Route 111 and Rand Avenue |
| **VMP-16** | 5 | | 13.5 | 19 | 31 | WRR- Main Property |
| **VMP-17** | 5 | | | | | Public Works Yard |
| **VMP-18** | 8.5 | | | | | Village of Roxana - 8th Street |
| **VMP-19** | 5 | | | | | Village of Roxana - 8th Street |
| **VMP-20** | 5 | | 10 | 25 | 39.5 | Village of Roxana - Alley Between 2nd and 3rd Street |
| **VMP-21** | 5 | | 10 | 25 | 33 | Village of Roxana - Alley Between 3rd and 4th Street |
| **VMP-22** | 5 | | 10 | 18 | 38 | Village of Roxana - Alley Between 4th and 5th Street |
| **VMP-23** | 5 | | 10 | 25 | 40 | Village of Roxana - Alley Between 5th and 6th Street |
| **VMP-24** | 5 | | 10 | 22 | 34 | Village of Roxana - 7th Street |
| **VMP-25** | 5 | | 9.5 | 21 | 31 | Village of Roxana - Corner of Rand Avenue and Route 111 |
| **VMP-26** | 10 | | 20 | 30 | 40 | WRR - North Property |
| **VMP-27** | 10 | | 20 | 30 | 40 | WRR - North Property |
| **VMP-28** | 10 | | 20 | 30 | 40 | WRR - North Property |
| **VMP-29** | 10 | | 20 | 30 | 40 | Public Works Yard |
| **VMP-30** | 10 | | 20 | 30 | 40 | Public Works Yard |
| **VMP-31** | 5 | | 10 | 20 | 30 | Village of Roxana - Corner of Chaffer Street and 4th Street |
| **VMP-32** | 5 | | 10 | 20 | 30 | Village of Roxana - 4th Street |
| **VMP-33** | | | 10 | 20 | 30 | WRR - North Property |
| **VMP-34** | | | 10 | 20 | 30 | WRR - North Property |
| **VMP-35** | | | 10 | 20 | 30 | WRR - North Property |
| **VMP-36** | | | 10 | 20 | 30 | WRR - North Property |
| **VMP-37** | | | 10 | 20 | 30 | WRR - North Property |
| **VMP-38** | | | 10 | 20 | 30 | WRR - North Property |
| **VMP-39** | | | 10 | 20 | 30 | WRR - North Property |
| **VMP-40** | | | 10 | 20 | 30 | WRR - North Property |
| **VMP-41** | | | 10 | 20 | 30 | Public Works Yard |
| **VMP-42** | | | 10 | 20 | 30 | Village of Roxana - Corner of Chaffer Street and 3rd Street |
| **VMP-43** | | | 10 | 20 | 30 | Village of Roxana - Corner of Chaffer Street and 4th Street |
| **VMP-44** | | | 10 | 20 | 30 | Village of Roxana - Corner of Chaffer Street and 5th Street |
| **VMP-45** | | | 10 | 20 | 30 | Village of Roxana - Corner of Chaffer Street and 6th Street |
| **VMP-46** | | | 10 | 20 | 30 | WRR - North Property |
| **VMP-47** | 5 | | 10 | 20 | 30 | Village of Roxana - Corner of Chaffer Street and Alley Between 1st and 2nd Street |
| **VMP-48** | 5 | | 10 | 20 | 30 | Village of Roxana - Alley Between 2nd and 3rd Street |
| **VMP-49** | 5 | | 10 | 20 | 30 | Village of Roxana - Alley Between 3rd and 4th Street |
| **VMP-50** | 5 | | 10 | 20 | 30 | Village of Roxana - Alley Between 4th and 5th Street |
| **VMP-51** | 5 | | 10 | 20 | 30 | Village of Roxana - Alley Between 5th and 6th Street |
| **VMP-52** | 5 | | 10 | 20 | 30 | Village of Roxana - Alley Between 6th and 7th Street |
| **VMP-53** | 5 | | 10 | 20 | 30 | Village of Roxana - Alley Between 7th and 8th Street |
| **VMP-54** | 5 | | 10 | 20 | 30 | Village of Roxana - Alley Between 7th and 8th Street |
| **VMP-55** | 5 | | 10 | 20 | 30 | Public Works Yard Area; Route 111 Right-of-Way |

SEE LAST PAGE OF TABLE FOR NOTES

**TABLE 3**
**SOIL VAPOR SAMPLING - TEDLAR SAMPLING DATA**

| Reading Location | | | Shroud | Tedlar Bag 1 | | Shroud | Tedlar Bag 2 | | | | | | | | | | | Tedlar Bag 3 |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| Instrument | | | Dielectric | | Landtec | Dielectric | | FID | PID | Multi-gas | | | | Landtec | | | | Dielectric |
| Location | Depth | Date | Helium in Shroud Before | Helium Before | CH4 (%) | Helium in Shroud After | Helium After | FID (ppm) | PID (ppm) | CO (ppm) | H2S (ppm) | LEL (%) | O2 (%) | CH4 (%) | LEL (%) | CO2 (%) | O2 (%) | Direct Port Reading After |
| VMP-1 | 5 ft | 08/25/10 | 51.9% | 0.0% | | 67.0% | 2.1% | 0.0 | 0.0 | 2.0 | 0.0 | 0.0 | 14.2 | 0.2 | 4.0 | 1.2 | 19.6 | N/A |
| | | 11/17/10 | 52.8% | 2.3% | | 58.0% | 5.7% | 0.2 | 0.6 | 5.0 | 0.0 | 0.0 | 19.4 | 0.1 | 2.0 | 1.3 | 20.1 | N/A |
| | | 02/04/11 | 51.2% | 0.0% | N/A | 60.8% | 2.7% | 275 | 66.0 | 0.0 | 0.0 | 11.0 | 2.6 | 2.2 | 44.0 | 9.1 | 2.2 | N/A |
| | | 04/12/11 | 62.0% | 0.0% | N/A | 74.5% | 2.5% | 0.0 | 1.0 | 0.0 | 0.0 | 0.0 | 17.9 | 0.0 | 0.0 | 1.9 | 18.1 | N/A |
| | | 08/01/11 | 53.9% | 0.0% | N/A | 59.5% | 0.0% | 132 | 8.8 | 0.1 | 2.0 | 0.0 | 9.2 | 0.1 | 0.0 | 8.9 | 12.0 | N/A |
| | | 11/03/11 | 50.3% | 0.0% | N/A | 52.7% | 0.0% | 27400 | 216.5 | 0.0 | 0.0 | 42.0 | 6.5 | 43.1 | OVR | 11.6 | 0.4 | N/A |
| | | 01/30/12 | 53.5% | 0.0% | N/A | 70.1% | 0.0% | 16460 | 168 | 4.0 | 0.0 | 24.0 | 7.4 | 37.3 | OVR | 11.8 | 0.8 | N/A |
| | | 04/13/12 | 59.9% | 0.0% | N/A | 74.1% | 0.2% | 0.0 | 1.01 | NM | NM | NM | NM | 0.0 | 0.0 | 2.4 | 18.9 | N/A |
| | | 07/16/12 | 51.7% | 0.0% | N/A | 53.4% | 2.4% | 9.7 | 1.2 | NM | NM | NM | NM | 0.0 | 0.0 | 2.2 | 20.1 | N/A |
| | | 10/11/12 | 57.4% | 0.0% | N/A | 55.9% | 0.0% | 2.0 | 1.0 | NM | NM | NM | NM | 0.0 | 0.0 | 0.4 | 19.7 | N/A |
| | | 01/21/13 | 50.0% | 0.0% | N/A | 54.0% | 0.5% | 93.70 | 4.8 | NM | NM | NM | NM | 0.0 | 0.0 | 0.3 | 20.6 | N/A |
| | | 01/23/13[16] | N/A | N/A | N/A | N/A | N/A | 35300 | 77.25 | NM | NM | NM | NM | 21.4 | OVR | 3.6 | 15.7 | N/A |
| | 8.5ft | 08/25/10 | 50.1% | 3.3% | | 50.2% | 4.3% | 3561 | 2.6 | 0.0 | 0.0 | 2.0 | 0.0 | 0.3 | 6.0 | 7.0 | 9.0 | N/A |
| | | 11/17/10 | 68.9% | 3.2% | | 77.4% | 1.3% | 8.6 | 2.5 | 0.0 | 0.0 | 0.0 | 7.9 | 0.1 | 2.0 | 7.1 | 8.4 | N/A |
| | | 02/04/11 | 57.3% | 0.0% | N/A | 54.5% | 0.0% | 720 | 101 | 23.0 | 0.0 | 20.0 | 0.6 | 7.0 | OVR | 11.1 | 0.5 | N/A |
| | | 04/12/11 | 56.0% | 0.0% | N/A | 87.0% | 0.0% | 0.0 | 1.6 | 0.0 | 0.0 | 0.0 | 7.8 | 0.0 | 0.0 | 5.3 | 8.3 | N/A |
| | | 08/01/11 | 53.2% | 0.0% | N/A | 59.8% | 0.0% | 51600 | 114.9 | 7.0 | 1.0 | 90.0 | 21.6 | 29.7 | OVR | 13.1 | 0.4 | N/A |
| | | 11/03/11 | 52.9% | 0.0% | N/A | 53.5% | 0.0% | 42200 | 206.6 | 0.0 | 0.0 | 60.0 | 4.8 | OVR | OVR | 12.1 | 0.4 | N/A |
| | | 01/30/12 | 69.2% | 0.0% | 4.2% | 52.5% | 0.0% | 17840 | 195.7 | 2.0 | 0.0 | 30.0 | 5.5 | 43.7 | OVR | 11.9 | 0.6 | N/A |
| | | 04/16/12 | 62.1% | 0.0% | N/A | 52.6% | 0.2% | 0.0 | 0.5 | NM | NM | NM | NM | 0.0 | 0.0 | 4.2 | 17.1 | N/A |
| | | 07/16/12 | 53.0% | 0.0% | N/A | 55.0% | 0.1% | 3.7 | 1.4 | NM | NM | NM | NM | 0.3 | 0.0 | 3.8 | 16.7 | N/A |
| | | 10/11/12 | 55.2% | 0.0% | N/A | 46.3% | 0.0% | 2.0 | 0.8 | NM | NM | NM | NM | 0.0 | 0.0 | 1.7 | 18.2 | N/A |
| | | 01/21/13 | 62.0% | 0.3% | 9.2% | 51.0% | 0.2% | 26600 | 105 | NM | NM | NM | NM | 31.9 | OVR | 0.9 | 18.9 | N/A |
| | | 01/23/13[16] | N/A | N/A | N/A | N/A | N/A | 1225 | 18.28 | NM | NM | NM | NM | 0.4 | 8 | 3.8 | 16.2 | N/A |
| | 23.5 ft | 08/30/10 | 50.8% | 2.3% | | 47.3% | 3.1% | 1990000 | 0.0 | 190 | 7.0 | OVR | 0.0 | 0.0 | OVR | 7.8 | 0.2 | N/A |
| | | 11/18/10 | 59.2% | 0.1% | | 65.4% | 4.3% | 38.7 | 0.5 | 0.0 | 0.0 | 0.0 | 16.4 | 0.2 | 4.0 | 2.9 | 17.1 | N/A |
| | | 02/04/11 | 50.2% | 0.0% | N/A | 40.2% | 0.0% | 1260000 | 69.5 | 45.0 | 3.0 | OVR | 0.5 | OVR | OVR | 8.6 | 0.4 | N/A |
| | | 04/12/11 | 52.0% | 0.0% | N/A | 62.0% | 0.0% | 42500 | 78.3 | 8.0 | 1.0 | 34.0 | 0.5 | 22.1 | OVR | 10.0 | 1.0 | N/A |
| | | 08/01/11 | 54.7% | 2.4% | OVR | 59.5% | 2.7% | 442000 | 196.6 | 35.0 | 6.0 | 100 | 21.7 | OVR | OVR | 8.7 | 0.3 | N/A |
| | | 11/03/11 | 62.6% | 1.3% | OVR | 50.1% | 1.5% | | 144.1 | 0.0 | 1.0 | OVR | 4.8 | OVR | OVR | 10.6 | 0.3 | N/A |
| | | 01/31/12 | 56.8% | 1.4% | OVR | 60.2% | 1.4% | 100000 | 107.0 | 0.0 | 2.0 | OVR | 4.0 | OVR | OVR | 11.4 | 0.3 | N/A |
| | | 04/16/12 | 57.2% | 0.0% | N/A | 76.2% | 0.0% | 2340 | 79.4 | NM | NM | NM | NM | 2.1 | 43.0 | 10.8 | 2.5 | N/A |
| | | 07/16/12 | 53.2% | 1.3% | OVR | 55.6% | 1.4% | 95000 | 49.0 | NM | NM | NM | NM | OVR | OVR | 8.2 | 4.1 | N/A |
| | | 10/24/12[9] | 50.0% | 1.8% | N/A | 49.3% | 2.9% | 187000 | 36.67 | NM | NM | NM | NM | OVR | OVR | 4.0 | 12.7 | N/A |
| | | 01/21/13[17] | 52.0% | 2.1% | 0.5% | 48.8% | 2.8% | 965 | 9.5 | NM | NM | NM | NM | 0.1 | 2 | 5.1 | 12.2 | N/A |
| | | 01/23/13[16] | N/A | N/A | N/A | N/A | N/A | 180000 | 79.8 | NM | NM | NM | NM | OVR | OVR | 8.4 | 5.7 | N/A |
| | 38.5 ft | 08/30/10 | NS | NS | | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS |
| | | 11/17/10 | NS | NS | | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS |
| | | 02/04/11 | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS |
| | | 04/12/11 | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS |
| | | 08/01/11 | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS |
| | | 11/03/11 | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS |
| | | 01/27/12 | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS |
| | | 04/16/12 [10] | 56.8% | 2.9% | N/A | 50.8% | 11.1% | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS |
| | | 07/31/12 | 63.1% | 0.0% | N/A | 54.7% | 0.4% | 3.5 | 1.3 | NM | NM | NM | NM | 0.0 | 0.0 | 1.8 | 14.0 | N/A |
| | | 10/26/12 | 54.2% | 1.0% | 49.8 | 46.1% | 2.5% | 24700 | 100 | NM | NM | NM | NM | 40.4 | OVR | 0.9 | 19.5 | N/A |
| | | 01/21/13[17] | 52.0% | 2.9% | 0.0% | 57.80% | 2.9% | 32.9 | 3.1 | NM | NM | NM | NM | 0.0 | 0.0 | 0.1 | 20.0 | N/A |
| | | 01/23/13[16] | N/A | N/A | N/A | N/A | N/A | 110000 | 71.45 | NM | NM | NM | NM | OVR | OVR | 3.5 | 14.2 | N/A |

SEE LAST PAGE OF TABLE FOR NOTES

**TABLE 3**
**SOIL VAPOR SAMPLING - TEDLAR SAMPLING DATA**

| Reading Location | | | Shroud | Tedlar Bag 1 | | Shroud | Tedlar Bag 2 | | | | | | | | | | | Tedlar Bag 3 |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| Instrument | | | Dielectric | | Landtec | Dielectric | | FID | PID | Multi-gas | | | | Landtec | | | | Dielectric |
| Location | Depth | Date | Helium in Shroud Before | Helium Before | CH4 (%) | Helium in Shroud After | Helium After | FID (ppm) | PID (ppm) | CO (ppm) | H2S (ppm) | LEL (%) | O2 (%) | CH4 (%) | LEL (%) | CO2 (%) | O2 (%) | Direct Port Reading After |
| VMP-2 | 5 ft | 08/31/10 | 50.3% | 0.0% | | 48.8% | 0.5% | 42780 | 98.9 | 24.0 | 1.0 | 35.0 | 0.0 | 63.9 | OVR | 11.4 | 0.2 | N/A |
| | | 11/16/10 | 53.4% | 0.1% | | 57.6% | 0.1% | 7729 | 231 | 10.0 | 0.0 | OVR | 0.3 | OVR | OVR | 12.1 | 1.0 | N/A |
| | | 02/04/11 | 53.6% | 0.0% | 7.6% | 56.8% | 0.0% | 1862 | 155 | 1.0 | 0.0 | 48.0 | 0.7 | 12.6 | OVR | 12.8 | 0.4 | N/A |
| | | 04/13/11 | 52.3% | 0.0% | N/A | 54.0% | 0.1% | 353 | 0.4 | 0.0 | 0.0 | 0.0 | 15.2 | 0.0 | 0.0 | 4.0 | 16.3 | N/A |
| | | 08/02/11 | 51.0% | 0.0% | N/A | 62.4% | 0.0% | 70700 | 397.4 | 57.0 | 2.0 | 17.0 | 0.0 | 99.9 | OVR | 11.7 | 0.4 | N/A |
| | | 11/04/11 | 58.5% | 0.0% | N/A | 51.6% | 0.0% | | 0.0 | 0.0 | 0.0 | 0.0 | 18.0 | 0.0 | 0.0 | 6.4 | 9.6 | N/A |
| | | 01/25/12 | 65.2% | 0.0% | N/A | 62.9% | 0.0% | 2720 | 84.3 | 0.0 | 0.0 | 10.0 | 5.4 | 0.0 | 0.0 | 12.7 | 2.0 | N/A |
| | | 4/25/12[9] | 67.6% | 0.0% | N/A | 58.5% | 0.1% | 0.0 | 4.6 | NM | NM | NM | NM | 0.0 | 0.0 | 6.7 | 11.7 | N/A |
| | | 07/16/12 | 53.1% | 0.0% | N/A | 66.7% | 0.2% | 5.8 | 1.2 | NM | NM | NM | NM | 0.1 | 0.0 | 1.3 | 20.1 | N/A |
| | | 10/24/12[9] | 52.5% | 0.0% | N/A | 50.6% | 0.5% | 2.0 | 1.0 | NM | NM | NM | NM | 0.0 | 0.0 | 0.3 | 20.2 | N/A |
| | | 01/31/13 | 51.6% | 0.0% | N/A | 37.0% | 1.2% | 1.81 | 0.3 | NM | NM | NM | NM | 0.0 | 0.0 | 0.3 | 20.5 | N/A |
| | 8.5 ft | 08/31/10 | 59.3% | 0.7% | | 46.7% | 1.3% | 1440000 | 48.8 | 48.0 | 2.0 | OVR | 0.0 | 99.9 | OVR | 0.1 | 0.0 | N/A |
| | | 11/16/10 | 63.2% | 0.0% | | 55.0% | 0.2% | 11900 | 180 | 28.0 | 0.0 | OVR | 0.6 | OVR | OVR | 11.4 | 0.8 | N/A |
| | | 02/04/11 | 51.0% | 0.0% | 17.7% | 64.0% | 0.0% | 4189 | 137 | 0.0 | 0.0 | OVR | 0.4 | 20.7 | OVR | 12.3 | 0.2 | N/A |
| | | 04/13/11 | 53.2% | 0.0% | N/A | 61.0% | 0.0% | 42750 | 74.1 | 0.0 | 0.0 | 0.0 | 0.0 | 0.2 | 4.0 | 11.6 | 1.8 | N/A |
| | | 08/02/11 | 53.1% | 1.0% | >>> | 53.8% | 0.8% | 148000 | 279.9 | 22.0 | 2.0 | OVR | 0.0 | OVR | OVR | 10.5 | 1.3 | N/A |
| | | 11/04/11 | 54.1% | 0.0% | N/A | 52.4% | 0.0% | | 23.9 | 0.0 | 0.0 | 0.0 | 12.2 | 0.0 | 0.0 | 11.0 | 3.1 | N/A |
| | | 01/26/12 | 63.0% | 0.0% | N/A | 63.5% | 0.0% | 17000 | 136.5 | 0.0 | 0.0 | 9.0 | 15.3 | 0.0 | 0.0 | 12.6 | 0.9 | N/A |
| | | 04/16/12 | 55.0% | 0.0% | N/A | 54.6% | 0.6% | 0.0 | 0.5 | NM | NM | NM | NM | 0.0 | 0.0 | 2.1 | 18.1 | N/A |
| | | 07/16/12 | 50.5% | 0.0% | N/A | 63.2% | 0.1% | 4.7 | 1.5 | NM | NM | NM | NM | 0.0 | 0.0 | 5.9 | 16.0 | N/A |
| | | 10/23/12 | 64.6% | 0.0% | N/A | 54.5% | 0.1% | 1.0 | 0.4 | NM | NM | NM | NM | 0.0 | 0.0 | 0.9 | 19.9 | N/A |
| | | 02/05/13[9] | 52.3% | 0.0% | N/A | 53.2% | 0.0% | 1.23 | 0.3 | NM | NM | NM | NM | 0.0 | 0.0 | 0.8 | 19.3 | N/A |
| | 22 ft | 08/31/10 | 59.7% | 2.5% | | 53.9% | 2.5% | 1160000 | 62.0 | 0.0 | 2.0 | OVR | 0.0 | 99.9 | OVR | 0.0 | 0.0 | N/A |
| | | 11/16/10 | 52.8% | 2.1% | | 51.0% | 1.9% | 13400 | 176 | 30.0 | 1.0 | OVR | 0.5 | OVR | OVR | 10.8 | 1.1 | N/A |
| | | 02/04/11 | 52.4% | 0.0% | 34.7% | 64.0% | 0.0% | 4189 | 137 | 0.0 | 0.0 | OVR | 0.4 | 39.9 | OVR | 12.3 | 0.4 | N/A |
| | | 04/13/11 | 52.0% | 0.0% | N/A | 70.0% | 0.5% | 57210 | 94.0 | 0.0 | 0.0 | 77.0 | 0.0 | 18.9 | OVR | 10.8 | 0.3 | N/A |
| | | 08/02/11 | 55.6% | 1.0% | OVR | 51.8% | 1.4% | 216000 | 211.4 | 59.0 | 2.0 | OVR | 0.0 | OVR | OVR | 9.9 | 0.7 | N/A |
| | | 11/04/11 | 53.4% | 0.0% | N/A | 53.8% | 0.0% | | 136.6 | 62.0 | 2.0 | 75.0 | 1.0 | 23.8 | OVR | 11.9 | 0.3 | N/A |
| | | 01/25/12 | 54.2% | 0.0% | N/A | 76.2% | 0.0% | 38800 | 118.7 | 0.0 | 0.0 | 54.0 | 4.6 | 14.1 | OVR | 12.1 | 0.5 | N/A |
| | | 04/27/12 | 52.4% | 0.0% | N/A | 63.1% | 0.0% | 1.0 | 0.8 | NM | NM | NM | NM | 0.0 | 0.0 | 6.5 | 15.1 | NS |
| | | 07/16/12 | 51.0% | 0.0% | N/A | 62.1% | 0.1% | 8.3 | 1.6 | NM | NM | NM | NM | 1.0 | 0.0 | 5.7 | 14.7 | N/A |
| | | 10/23/12 | 61.5% | 0.0% | N/A | 59.8% | 0.1% | 1.0 | 0.5 | NM | NM | NM | NM | 0.0 | 0.0 | 3.9 | 17.6 | N/A |
| | | 01/31/13 | 57.2% | 0.0% | N/A | 50.7% | 0.0% | 1.14 | 0.2 | NM | NM | NM | NM | 0.0 | 0.0 | 2.4 | 18.8 | N/A |
| | 42 ft | 08/31/10 | NS | NS | | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS |
| | | 11/16/10 | NS | NS | | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS |
| | | 02/04/11 | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS |
| | | 04/13/11 | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS |
| | | 08/02/11 | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS |
| | | 11/04/11 | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS |
| | | 01/26/12 | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS |
| | | 4/11/2012 [13] | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS |
| | | 7/16/12 [13] | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS |
| | | 10/24/12[13] | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS |
| | | 01/31/13 | 56.2% | 5.0% | OVR | 46.1% | 5.2% | 400000 | 58.77 | NM | NM | NM | NM | OVR | OVR | 5.9 | 6.4 | N/A |

SEE LAST PAGE OF TABLE FOR NOTES

**TABLE 3**
**SOIL VAPOR SAMPLING - TEDLAR SAMPLING DATA**

| Reading Location | | | Shroud | Tedlar Bag 1 | | Shroud | Tedlar Bag 2 | | | | | | | | | | | Tedlar Bag 3 |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| Instrument | | | Dielectric | | Landtec | Dielectric | | FID | PID | Multi-gas | | | | Landtec | | | | Dielectric |
| Location | Depth | Date | Helium in Shroud Before | Helium Before | CH4 (%) | Helium in Shroud After | Helium After | FID (ppm) | PID (ppm) | CO (ppm) | H2S (ppm) | LEL (%) | O2 (%) | CH4 (%) | LEL (%) | CO2 (%) | O2 (%) | Direct Port Reading After |
| VMP-3 | 5 ft | 09/09/10 | 52.6% | 2.8% | | 51.7% | 5.6% | 2280000 | 137 | 104 | 4.0 | OVR | 0.0 | OVR | OVR | 12.3 | 0.0 | 10.5% |
| | | 11/22/10 | 51.9% | 4.1% | | 62.9% | 7.1% | 1.9 | 200 | 321 | 5.0 | OVR | 3.4 | OVR | OVR | 9.0 | 3.2 | 8.6% |
| | | 02/09/11 | 67.1% | 1.1% | N/A | 68.5% | 11.0% | 3370 | 134 | 35.0 | 0.0 | 19.0 | 2.3 | 73.4 | OVR | 4.9 | 3.0 | 25.0% |
| | | 04/14/11 | 57.8% | 3.8% | OVR | 56.1% | 5.1% | 2850000 | 180 | 15.7 | 13.0 | 18.1 | 0.0 | OVR | OVR | 9.4 | 1.5 | N/A |
| | | 08/02/11 | 55.0% | 0.0% | N/A | 52.6% | 0.0% | 36.52 | 8.9 | 0.0 | 1.0 | 0.0 | 22.3 | 0.1 | 0.0 | 0.3 | 22.09 | N/A |
| | | 11/04/11 | 55.2% | 0.0% | N/A | 54.9% | 0.3% | 0.0 | 0.4 | 0.0 | 0.0 | 0.0 | 16.6 | 0.0 | 0.0 | 3.3 | 16.4 | N/A |
| | | 01/27/12 | 52.5% | 0.0% | N/A | 72.5% | 0.0% | 2350 | 38.6 | 0.0 | 0.0 | 6.0 | 13.7 | 3.5 | 70.0 | 2.2 | 13.6 | N/A |
| | | 04/19/12 | 68.4% | 0.0% | N/A | 58.0% | 0.0% | 0.0 | 0.5 | NM | NM | NM | NM | 0.0 | 0.0 | 1.0 | 18.9 | N/A |
| | | 7/27/12 [9] | 54.3% | 0.0% | N/A | 64.6% | 4.6% | 8.3 | 0.5 | NM | NM | NM | NM | 0.0 | 0.0 | 0.5 | 18.2 | N/A |
| | | 10/24/12[10] | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS |
| | | 02/07/13[10] | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS |
| | 10 ft | 06/21/10 | 48.1% | 0.0% | | 18.5% | 0.2% | | 109.0 | 237 | 0.0 | OVR | 0.9 | | | OVR | | N/A |
| | | 09/10/10 | 59.1% | 10.3% | | 58.0% | 9.2% | OVR | 10.9 | 511 | 15.0 | OVR | 0.0 | OVR | OVR | 9.7 | 0.0 | 10.1% |
| | | 09/20/10 | 51.1% | 6.7% | | 44.3% | 2.5% | OVR | 142 | 0.0 | 10.0 | OVR | 0.3 | OVR | OVR | 9.0 | 1.3 | 8.1% |
| | | 11/22/10 | 57.0% | 8.1% | | 61.3% | 8.5% | 78600 | 160 | 425 | 3.0 | OVR | 0.6 | OVR | OVR | 8.6 | 0.9 | 8.1% |
| | | 02/08/11 | 50.3% | 0.0% | N/A | 52.1% | 0.0% | 2700000 | 159 | 2.0 | 0.0 | OVR | 0.5 | OVR | OVR | 8.8 | 0.1 | N/A |
| | | 04/13/11 | 52.0% | 4.7% | OVR | 73.0% | 6.0% | 5130000 | 119 | 300 | 9.0 | OVR | 0.0 | OVR | OVR | 7.3 | 0.7 | N/A |
| | | 08/02/11 | 62.4% | 0.0% | N/A | 42.6% | 0.0% | 16900 | 164.2 | 7.0 | 1.0 | 14 | 0.0 | 3.5 | 73.0 | 15.8 | 0.8 | N/A |
| | | 11/04/11 | 52.6% | 0.0% | N/A | 52.9% | 0.0% | 68.0 | 5.8 | 0.0 | 0.0 | 0.0 | 5.1 | 0.0 | 0.0 | 5.8 | 5.5 | N/A |
| | | 01/27/12 | 55.4% | 0.0% | N/A | 65.2% | 0.0% | 385 | 17.4 | 0.0 | 0.0 | 0.0 | 10.3 | 0.2 | 4.0 | 3.6 | 10.7 | N/A |
| | | 04/19/12 | 60.5% | 0.0% | N/A | 66.0% | 0.0% | 0.0 | 0.6 | NM | NM | NM | NM | 0.0 | 0.0 | 1.9 | 18.1 | N/A |
| | | 07/23/12 | 53.7% | 0.0% | N/A | 41.2% | 0.0% | 11.0 | 1.7 | N/A | N/A | N/A | N/A | 0.0 | 0.0 | 1.9 | 19.0 | N/A |
| | | 10/18/12 | 47.5% | 0.0% | N/A | 36.7% | 0.0% | 7.0 | 1.0 | NM | NM | NM | NM | 0.0 | 0.0 | 0.7 | 20.1 | N/A |
| | | 02/06/13 | 68.4% | 0.0% | N/A | 59.1% | 0.3% | 1.30 | 0.2 | NM | NM | NM | NM | 0.0 | 0.0 | 0.5 | 20.8 | N/A |
| | 22 ft | 09/20/10 | 51.2% | 4.6% | | 51.0% | 4.6% | OVR | 51.2 | 0.0 | 39.0 | OVR | 0.7 | OVR | OVR | 8.8 | 6.7 | 5.1% |
| | | 11/22/10 | 51.2% | 9.5% | | 59.6% | 10.1% | 129200 | 153.0 | 691 | 17.0 | OVR | 0.5 | OVR | OVR | 7.8 | 1.0 | 9.8% |
| | | 02/08/11 | 51.2% | 0.0% | N/A | 40.5% | 0.0% | 5960000 | 145.0 | 244 | 15.0 | OVR | 0.4 | OVR | OVR | 8.2 | 0.4 | N/A |
| | | 04/15/11 | 71.2% | 7.0% | OVR | 55.0% | 8.1% | OVR | 153.0 | 406 | 20.0 | OVR | 0.0 | OVR | OVR | 8.2 | 2.7 | N/A |
| | | 08/06/11 | 72.2% | 0.0% | N/A | 59.9% | 0.4% | 10400 | 39.7 | 6.0 | 0.0 | 19.0 | 13.0 | 2.2 | 42.0 | 2.6 | 13.0 | N/A |
| | | 11/04/11 | 53.2% | 0.0% | N/A | 53.8% | 0.0% | 76.0 | 3.7 | 0.0 | 0.0 | 0.0 | 18.2 | 0.0 | 0.0 | 1.8 | 18.2 | N/A |
| | | 01/30/12 | 51.3% | 0.0% | N/A | 71.8% | 0.0% | 66.0 | 5.1 | 0.0 | 0.0 | 0.0 | 18.7 | 0.0 | 0.0 | 7.5 | 10.1 | N/A |
| | | 04/19/12 | 64.2% | 0.0% | N/A | 61.0% | 0.0% | 20.1 | 0.6 | NM | NM | NM | NM | 0.0 | 0.0 | 1.3 | 20.7 | N/A |
| | | 07/23/12 | 53.7% | 0.0% | N/A | 44.8% | 0.0% | 7.9 | 1.3 | N/A | N/A | N/A | N/A | 0.0 | 0.0 | 0.9 | 19.7 | N/A |
| | | 10/18/12 | 49.9% | 0.0% | N/A | 35.0% | 0.0% | 2.0 | 0.4 | NM | NM | NM | NM | 0.0 | 0.0 | 3.2 | 18.0 | N/A |
| | | 02/06/13 | 51.4% | 0.0% | N/A | 54.4% | 0.0% | 2.63 | 0.3 | NM | NM | NM | NM | 0.2* | 3* | 2.9 | 18.6 | N/A |
| | 31.5 ft | 09/09/10 | 57.8% | 18.2% | | 37.6% | 17.0% | OVR | 14.9 | 1033.0 | 9.0 | OVR | 0.0 | OVR | OVR | 4.6 | 0.0 | 17.7% |
| | | 11/22/10 | 51.2% | 16.3% | | 62.4% | 16.0% | OVR | 232 | OVR | 12.0 | OVR | 0.4 | OVR | OVR | 4.7 | 0.9 | 15.4% |
| | | 02/09/11 | 59.3% | 0.0% | N/A | 48.3% | 12.4% | OVR | 93.8 | 144 | 0.0 | OVR | 0.5 | OVR | OVR | 8.0 | 0.0 | N/A |
| | | 04/14/11 | 57.0% | 6.1% | OVR | 89.0% | 12.1% | OVR | 199 | 214 | 8.6 | 20.0 | 0.0 | OVR | OVR | 5.3 | 1.3 | N/A |
| | | 08/02/11 | 70.5% | 14.0% | OVR | 26.7% | 15.9% | OVR | 239 | 1000 | 8.0 | OVR | 0.0 | OVR | OVR | 4.3 | 0.7 | N/A |
| | | 11/04/11 | 50.3% | 7.5% | OVR | 60.5% | 6.9% | OVR | 230.9 | 961 | 5.0 | 100 | 2.1 | OVR | OVR | 5.4 | 2.5 | N/A |
| | | 01/27/12 | 53.5% | 2.0% | OVR | 87.2% | 4.0% | 815000 | 128.6 | 0.0 | 0.0 | OVR | 5.0 | OVR | OVR | 6.6 | 3.6 | N/A |
| | | 04/19/12 | 69.1% | 6.7% | OVR | 63.0% | 6.9% | OVR | 106 | NM | NM | NM | NM | OVR | OVR | 6.7 | 0.3 | N/A |
| | | 07/23/12 | 50.1% | 0.0% | N/A | 45.2% | 0.0% | 171000 | 75.9 | N/A | N/A | N/A | N/A | OVR | OVR | 8.0 | 2.8 | N/A |
| | | 10/19/12 | 63.2% | 0.0% | N/A | 56.4% | 0.2% | 2400 | 51 | NM | NM | NM | NM | 0.6 | 12 | 2.9 | 17.4 | N/A |
| | | 02/07/13 | 41.2% | 0.0% | OVR | 53.5% | 0.3% | 29200 | 180 | NM | NM | NM | NM | 93.4 | OVR | 10.4 | 3.4 | N/A |
| | 39 ft | 09/09/10 | NS | NS | | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS |
| | | 11/22/10 | NS | NS | | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS |
| | | 02/09/11 | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS |
| | | 04/14/11 | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS |
| | | 08/02/11 | 97.3% | 86.2% | 2.4% | 92.1% | 55.2% | 0.0 | 2.2 | 2.0 | 0.0 | 3.0 | 0.0 | 0.7 | 25.0 | 0.0 | 1.8 | N/A |
| | | 11/04/11 | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS |
| | | 01/27/12 | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS |
| | | 4/19/2012 [13] | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS |
| | | 7/23/12 [13] | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS |
| | | 10/19/12 | 52.6% | 0.0% | N/A | 52.8% | 2.3% | 684000 | 144 | NM | NM | NM | NM | OVR | OVR | 8.3 | 2.7 | N/A |
| | | 02/12/13[12] | 57.2% | 2.0% | N/A | 55.2% | 1.9% | 185000 | 149 | NM | NM | NM | NM | OVR | OVR | 9.0 | 0.9 | N/A |

SEE LAST PAGE OF TABLE FOR NOTES

**TABLE 3**
**SOIL VAPOR SAMPLING - TEDLAR SAMPLING DATA**

| Reading Location | | | Shroud | Tedlar Bag 1 | | Shroud | Tedlar Bag 2 | | | | | | | | | | | Tedlar Bag 3 |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| Instrument | | | Dielectric | | Landtec | Dielectric | | FID | PID | Multi-gas | | | | Landtec | | | | Dielectric |
| Location | Depth | Date | Helium in Shroud Before | Helium Before | CH4 (%) | Helium in Shroud After | Helium After | FID (ppm) | PID (ppm) | CO (ppm) | H2S (ppm) | LEL (%) | O2 (%) | CH4 (%) | LEL (%) | CO2 (%) | O2 (%) | Direct Port Reading After |
| VMP-4 | 5 ft | 08/25/10 | 50.1% | 0.0% | | 46.6% | 2.3% | 0.0 | 26.7 | 305 | 7.0 | OVR | 0.8 | 99.8 | OVR | 0.0 | 0.2 | N/A |
| | | 11/22/10 | 52.9% | 5.1% | | 50.5% | 5.2% | 27800 | 165 | 376 | 11.0 | OVR | 0.6 | OVR | OVR | 13.7 | 0.8 | 5.1% |
| | | 02/14/11 | 52.3% | 0.0% | N/A | 42.7% | 13.1% | 1045 | 406 | 20.0 | 2.0 | 28.0 | 7.9 | 21.6 | OVR | 5.9 | 7.8 | 11.2% |
| | | 04/19/11 | 76.8% | 0.0% | N/A | 54.0% | 0.0% | 26.0 | 304 | 16.0 | 34.0 | OVR | 0.2 | OVR | OVR | 11.3 | 3.3 | N/A |
| | | 08/03/11 | 52.3% | 0.0% | N/A | 52.3% | 0.0% | 99.0 | 39.5 | 2.0 | 0.0 | 0.0 | 4.0 | 0.0 | 0.0 | 11.0 | 8.07 | N/A |
| | | 11/09/11 | 71.0% | 0.0% | N/A | 55.6% | 0.2% | | 0.3 | 0.0 | 0.0 | 0.0 | 20.9 | 0.0 | 0.0 | 0.1 | 21.5 | N/A |
| | | 01/30/12 | 54.2% | 0.0% | N/A | 64.5% | 0.1% | 1200 | 255.4 | 0.0 | 0.0 | 0.0 | 14.2 | 1.3 | 26.0 | 10.1 | 0.4 | N/A |
| | | 4/25/2012[9] | 61.2% | 0.3% | N/A | 58.9% | 0.6% | 0.0 | 2.2 | NM | NM | NM | NM | 0.0 | 0.0 | 0.5 | 20.4 | N/A |
| | | 7/25/12 [9] | 57.0% | 0.0% | N/A | 53.2% | 0.5% | 3.0 | 1.1 | NM | NM | NM | NM | 0.0 | 0.0 | 2.1 | 18.0 | N/A |
| | | 10/18/12 | 61.4% | 0.0% | N/A | 41.3% | 0.0% | 1.0 | 0.5 | NM | NM | NM | NM | 0.0 | 0.0 | 0.9 | 20.1 | N/A |
| | | 02/07/13 | 64.4% | 0.0% | N/A | 52.1% | 0.2% | 0.77 | 0.1 | NM | NM | NM | NM | 0.0 | 0.0 | 0.2 | 20.7 | N/A |
| | 12 ft | 08/25/10 | 57.4% | 3.4% | | 54.0% | 4.6% | 0.0 | 77.8 | 452 | 25.0 | OVR | 0.0 | 99.8 | OVR | 13.5 | 0.2 | N/A |
| | | 11/23/10 | 58.7% | 3.3% | | 52.4% | 3.0% | 16900 | 112 | 40.0 | 0.0 | OVR | 0.7 | OVR | OVR | 13.6 | 1.4 | 2.5% |
| | | 02/14/11 | 50.4% | 1.3% | OVR | 44.8% | 1.7% | 6169 | 276 | 30.0 | 1.0 | 27.0 | 3.4 | OVR | OVR | 9.5 | 3.3 | 1.4% |
| | | 04/19/11 | 57.2% | 2.5% | OVR | 54.2% | 4.7% | 28.4 | 242 | 554 | 40.0 | OVR | 3.0 | OVR | OVR | 7.7 | 7.3 | N/A |
| | | 08/03/11 | 71.2% | 4.1% | OVR | 48.9% | 2.2% | 113000 | 198 | 25.0 | 10.0 | OVR | 0.0 | 91.2 | OVR | 14.7 | 1.6 | N/A |
| | | 11/09/11 | 63.5% | 8.0% | 2.2% | 57.8% | 3.0% | | 300.6 | 7.0 | 0.0 | 9.0 | 6.0 | 2.3 | 46.0 | 8.9 | 5.6 | N/A |
| | | 01/30/12 | 56.0% | 0.0% | N/A | 67.7% | 0.2% | 8240 | 464.1 | 0.0 | 0.0 | 0.0 | 15.1 | 14.6 | OVR | 11.2 | 0.5 | N/A |
| | | 04/13/12 | 56.4% | 0.0% | N/A | 60.3% | 0.2% | 4.0 | 0.75 | NM | NM | NM | NM | 0.0 | 0.0 | 2.6 | 17.5 | N/A |
| | | 07/23/12 | 50.3% | 0.8% | 1.0% | 67.7% | 0.7% | 4.9 | 1.3 | NM | NM | NM | NM | 0.0 | 0.0 | 2.7 | 16.3 | N/A |
| | | 10/18/12 | 53.0% | 0.0% | N/A | 45.0% | 0.5% | 1.0 | 0.8 | NM | NM | NM | NM | 0.0 | 0.0 | 1.3 | 19.6 | N/A |
| | | 02/07/13 | 60.1% | 0.0% | N/A | 63.6% | 0.2% | 3.46 | 0.3 | NM | NM | NM | NM | 0.1* | 1* | 0.9 | 20.6 | N/A |
| | 23.5 ft | 08/31/10 | 54.5% | 12.7% | | 37.8% | 14.3% | OVR | 2.3 | 1006.0 | 70.0 | OVR | 0.0 | OVR | OVR | 5.7 | 0.7 | 12.7% |
| | | 11/23/10 | 59.9% | 17.3% | | 62.2% | 17.5% | 150300 | 124 | 800 | 0.0 | OVR | 0.5 | OVR | OVR | 7.0 | 0.9 | 17.0% |
| | | 02/14/11 | 55.7% | 15.1% | OVR | 45.4% | 14.6% | OVR | 166 | OVR | 16.0 | OVR | 0.3 | OVR | OVR | 6.1 | 0.8 | 11.7% |
| | | 04/20/11 | 53.5% | 3.8% | OVR | 50.0% | 6.7% | OVR | 121 | OVR | 44.0 | OVR | 0.0 | OVR | OVR | 5.7 | 0.6 | N/A |
| | | 08/06/11 | 56.0% | 16.0% | OVR | 61.6% | 16.2% | OVR | 238 | OVR | 11.0 | 100 | 0.1 | OVR | OVR | 5.1 | 0.4 | N/A |
| | | 11/09/11 | 51.0% | 4.5% | OVR | 55.8% | | OVR | 309 | 280 | 34.0 | OVR | 1.6 | OVR | OVR | 6.7 | 1.6 | N/A |
| | | 01/30/12 | 52.0% | 2.2% | OVR | 62.2% | 2.3% | 263000 | 202.4 | 4.0 | 5.0 | OVR | 6.2 | OVR | OVR | 7.9 | 0.8 | N/A |
| | | 04/13/12 | 74.8% | 0.0% | N/A | 53.4% | 0.1% | 98300 | 560 | NM | NM | NM | NM | OVR | OVR | 10.8 | 0.8 | N/A |
| | | 07/23/12 | 50.2% | 0.0% | N/A | 50.2% | 0.0% | 54500 | 305 | NM | NM | NM | NM | OVR | OVR | 11.8 | 0.2 | N/A |
| | | 10/18/12 | 52.4% | 0.0% | N/A | 62.2% | 0.0% | 6890 | 618 | NM | NM | NM | NM | 20.6 | OVR | 8.9 | 12.7 | N/A |
| | | 02/07/13 | 64.4% | 0.0% | N/A | 60.3% | 0.0% | 1750 | 145 | NM | NM | NM | NM | 2.5 | 51 | 6.7 | 15.6 | N/A |
| | 39 ft | 08/31/10 | NS | NS | | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS |
| | | 01/23/10 | NS | NS | | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS |
| | | 02/14/11 | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS |
| | | 04/21/11 | 54.8% | 11.3% | OVR | 62.4% | 1.4% | OVR | 119 | OVR | 50.0 | OVR | 0.2 | OVR | OVR | 4.9 | 0.6 | N/A |
| | | 08/06/11 | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS |
| | | 11/09/11 | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS |
| | | 01/30/12 | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS |
| | | 04/13/12 | 56.6% | 0.0% | N/A | 50.5% | 0.1% | 195000 | 471 | NM | NM | NM | NM | OVR | OVR | 10.4 | 0.4 | N/A |
| | | 07/23/12 | 62.7% | 0.0% | N/A | 59.8% | 0.0% | 74000 | 230 | NM | NM | NM | NM | OVR | OVR | 12.2 | 0.4 | N/A |
| | | 10/18/12 | 51.5% | 0.4% | OVR | 52.5% | 0.0% | 82000 | 468 | NM | NM | NM | NM | OVR | OVR | 7.7 | 12.5 | N/A |
| | | 02/07/13 | 51.4% | 0.0% | N/A | 63.9% | 0.1% | 61400 | 538 | NM | NM | NM | NM | OVR | OVR | 9.1 | 13.2 | N/A |

SEE LAST PAGE OF TABLE FOR NOTES

**TABLE 3**
**SOIL VAPOR SAMPLING - TEDLAR SAMPLING DATA**

| Reading Location | | | Shroud | Tedlar Bag 1 | | Shroud | Tedlar Bag 2 | | | | | | | | | | | Tedlar Bag 3 |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| Instrument | | | Dielectric | | Landtec | Dielectric | | FID | PID | Multi-gas | | | | Landtec | | | | Dielectric |
| Location | Depth | Date | Helium in Shroud Before | Helium Before | CH4 (%) | Helium in Shroud After | Helium After | FID (ppm) | PID (ppm) | CO (ppm) | H2S (ppm) | LEL (%) | O2 (%) | CH4 (%) | LEL (%) | CO2 (%) | O2 (%) | Direct Port Reading After |
| VMP-5 | 5 ft | 09/09/10 | 63.6% | 0.8% | | 61.5% | 0.9% | 79110 | 331 | 426 | 11.0 | OVR | 0.0 | OVR | OVR | 12.4 | 1.6 | N/A |
| | | 11/22/10 | 55.8% | 0.0% | | 36.0% | 1.6% | 11600 | 149 | 199 | 0.0 | OVR | 1.9 | OVR | OVR | 12.5 | 1.4 | N/A |
| | | 02/16/11 | 65.3% | 0.0% | N/A | 58.1% | 0.2% | 2950 | 25.2 | 0.0 | 0.0 | 4.0 | 11.4 | 0.6 | 14.0 | 9.9 | 10.6 | N/A |
| | | 04/21/11 | 54.2% | 0.0% | N/A | 56.4% | 0.4% | 0.0 | 0.3 | 0.0 | 0.0 | 0.0 | 18.5 | 0.0 | 0.0 | 7.5 | 19.0 | N/A |
| | | 08/05/11 | 51.1% | 0.0% | N/A | 50.0% | 0.0% | 2760 | 74.8 | 7.0 | 0.0 | 6.0 | 1.2 | 0.8 | 17.0 | 15.3 | 1.0 | N/A |
| | | 11/11/11 | 52.4% | 0.0% | N/A | 58.4% | 0.0% | 0.0 | 3.9 | 0.0 | 0.0 | 0.0 | 4.3 | 0.0 | 0.0 | 14.2 | 4.4 | N/A |
| | | 01/30/12 | 50.5% | 0.0% | N/A | 39.8% | 0.0% | 4.0 | 0.7 | 10 | 0.0 | 0.0 | 11.6 | 0.0 | 0.0 | 8.4 | 11.4 | N/A |
| | | 04/11/12 | 59.4% | 0.0% | 0.0% | 60.2% | 5.1% | 1.0 | 1.3 | NM | NM | NM | NM | 0.0 | 0.0 | 0.4 | 19.7 | N/A |
| | | 07/13/12 | 50.1% | 0.0% | 0.0% | 61.4% | 2.7% | 4.0 | 0.5 | NM | NM | NM | NM | 0.0 | 0.0 | 0.4 | 20.1 | N/A |
| | | 10/12/12[9] | 53.1% | 0.0% | N/A | 40.2% | 1.8% | 2.0 | 0.9 | NM | NM | NM | NM | 0.0 | 0.0 | 0.2 | 20.7 | N/A |
| | | 01/25/13 | 61.2% | 0.0% | N/A | 41.9% | 0.5% | 0.57 | 0.4 | NM | NM | NM | NM | 0.0 | 0.0 | 0.1 | 20.1 | N/A |
| | 12.5 ft | 09/09/10 | 54.6% | 0.9% | | 53.1% | 0.6% | 1590000 | 276.0 | 244 | 14.0 | OVR | 0.0 | OVR | OVR | 14.3 | 0.0 | N/A |
| | | 11/23/10 | 53.3% | 0.0% | | 50.6% | 0.0% | 205 | 79.9 | 4.0 | 0.0 | 55.0 | 4.4 | 1.5 | 32.0 | 13.2 | 3.6 | N/A |
| | | 02/16/11 | 60.2% | 0.0% | N/A | 60.2% | 0.0% | 2750 | 111 | 21.0 | 0.0 | 22.0 | 0.7 | 11.0 | 44.0 | 13.1 | 0.7 | N/A |
| | | 04/21/11 | 59.0% | 0.0% | N/A | 51.1% | 0.0% | 0.0 | 0.7 | 0.0 | 0.0 | 0.0 | 9.5 | 0.0 | 0.0 | 8.3 | 10.3 | N/A |
| | | 08/05/11 | 51.5% | 0.0% | N/A | 64.5% | 1.6% | 315000 | 128.5 | 400 | 4.0 | 100 | 0.1 | OVR | OVR | 13.1 | 0.1 | N/A |
| | | 11/11/11 | 53.0% | 0.0% | N/A | 56.5% | 0.0% | 0.0 | 1.0 | 0.0 | 0.0 | 0.0 | 3.5 | 0.0 | 0.0 | 14.7 | 3.8 | N/A |
| | | 01/30/12 | 51.3% | 0.0% | N/A | 43.6% | 0.0% | 3.0 | 0.5 | 4.0 | 0.0 | 0.0 | 11.0 | 0.0 | 0.0 | 8.5 | 11.0 | N/A |
| | | 04/11/12 | 53.7% | 0.1% | 0.0% | 55.5% | 0.3% | 1.0 | 0.9 | NM | NM | NM | NM | 0.0 | 0.0 | 0.7 | 20.9 | N/A |
| | | 07/12/12 | 70.7% | 0.0% | N/A | 50.0% | 0.0% | 5.0 | 1.3 | N/A | N/A | N/A | N/A | 0.0 | 0.0 | 0.7 | 19.4 | N/A |
| | | 10/11/12 | 61.5% | 0.8% | N/A | 36.1% | 1.2% | 2.0 | 0.7 | NM | NM | NM | NM | 0.0 | 0.0 | 0.2 | 20.2 | N/A |
| | | 01/24/13 | 47.4% | 0.0% | N/A | 51.8% | 0.0% | 0.87 | 0.2 | NM | NM | NM | NM | 0.0 | 0.0 | 0.2 | 21.1 | N/A |
| | 31 ft | 09/09/10 | 48.0% | 9.2% | | 46.2% | 10.2% | OVR | 0.0 | 875 | 21.0 | OVR | 0.0 | OVR | OVR | 9.4 | 0.0 | 7.1% |
| | | 11/23/10 | 53.6% | 9.6% | | 50.0% | 9.0% | 87100 | 148 | 1500 | 0.0 | OVR | 0.7 | OVR | OVR | 9.6 | 0.9 | 9.0% |
| | | 02/16/11 | 50.9% | 0.0% | N/A | 55.4% | 7.7% | 45000 | 226 | OVR | 9.0 | OVR | 0.9 | OVR | OVR | 8.7 | 0.7 | 8.2% |
| | | 04/21/11 | 53.0% | 8.7% | OVR | 70.0% | 5.8% | OVR | 204 | 600 | 18.0 | OVR | 0.0 | OVR | OVR | 8.9 | 0.4 | N/A |
| | | 08/05/11 | 84.0% | 3.8% | N/A | 70.0% | 9.0% | OVR | 215.8 | OVR | 10.0 | 100 | 0.1 | OVR | OVR | 8.8 | 0.2 | N/A |
| | | 11/11/11 | 52.0% | 0.0% | N/A | 58.8% | 0.0% | 350000 | 200.5 | 66.0 | 32.0 | OVR | 0.5 | OVR | OVR | 9.3 | 0.9 | N/A |
| | | 01/30/12 | 52.7% | 1.5% | N/A | 43.1% | 1.2% | 129000 | 391.3 | 697 | 17.0 | 0.0 | 0.2 | OVR | OVR | 11.2 | 0.3 | N/A |
| | | 04/11/12 | 60.8% | 0.0% | 0.0% | 77.6% | 0.0% | 261 | 28.0 | NM | NM | NM | NM | 0.0 | 1.0 | 12.6 | 0.0 | N/A |
| | | 07/12/12 | 55.1% | 0.0% | N/A | 30.0% | 0.0% | 14.8 | 3.3 | N/A | N/A | N/A | N/A | 0.0 | 0.0 | 6.9 | 13.9 | N/A |
| | | 10/11/12 | 87.6% | 0.0% | N/A | 48.9% | 0.2% | 4.0 | 1.5 | NM | NM | NM | NM | 0.0 | 0.0 | 4.1 | 17.4 | N/A |
| | | 01/24/13 | 44.9% | 0.0% | N/A | 40.0% | 0.0% | 6.45 | 0.6 | NM | NM | NM | NM | 0.0 | 0.0 | 4.0 | 18.0 | N/A |
| | 40 ft | 09/09/10 | NS | NS | | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS |
| | | 11/23/10 | NS | NS | | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS |
| | | 02/16/11 | NS | NS | N/A | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS |
| | | 04/21/11 | 56.5% | 5.7% | OVR | 51.0% | 5.3% | OVR | 229 | 632 | 18.0 | OVR | 0.0 | OVR | OVR | 8.8 | 0.2 | N/A |
| | | 08/05/11 | NS | NS | N/A | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS |
| | | 11/11/11 | NS | NS | N/A | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS |
| | | 01/30/12 | 51.8% | 1.2% | OVR | 52.7% | 1.3% | 81220 | 313.9 | 609 | 24.0 | 0.0 | 0.1 | OVR | OVR | 11.4 | 0.2 | N/A |
| | | 04/11/12 | 52.9% | 0.0% | 0.3% | 83.4% | 0.0% | 863 | 59.5 | NM | NM | NM | NM | 0.3 | 7.0 | 12.9 | 0.2 | N/A |
| | | 07/12/12 | 51.6% | 0.0% | N/A | 47.2% | 0.0% | 137 | 7.0 | N/A | N/A | N/A | N/A | 0.0 | 1.0 | 6.7 | 14.4 | N/A |
| | | 10/11/12 | 66.8% | 0.0% | N/A | 40.0% | 0.7% | 22.0 | 2.2 | NM | NM | NM | NM | 0.0 | 0.0 | 4.4 | 17.6 | N/A |
| | | 01/25/13 | 48.0% | 0.0% | N/A | 42.8% | 0.0% | 16.67 | 0.9 | NM | NM | NM | NM | 0.0 | 0.0 | 4.0 | 18.1 | N/A |

SEE LAST PAGE OF TABLE FOR NOTES

**TABLE 3**
**SOIL VAPOR SAMPLING - TEDLAR SAMPLING DATA**

| Reading Location | | | Shroud | Tedlar Bag 1 | | Shroud | Tedlar Bag 2 | | | | | | | | | | | Tedlar Bag 3 |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| Instrument | | | Dielectric | | Landtec | Dielectric | | FID | PID | Multi-gas | | | | Landtec | | | | Dielectric |
| Location | Depth | Date | Helium in Shroud Before | Helium Before | CH4 (%) | Helium in Shroud After | Helium After | FID (ppm) | PID (ppm) | CO (ppm) | H2S (ppm) | LEL (%) | O2 (%) | CH4 (%) | LEL (%) | CO2 (%) | O2 (%) | Direct Port Reading After |
| VMP-6 | 5 ft | 09/08/10 | 59.3% | 0.0% | | 56.4% | 0.1% | 35760 | 327 | 76.0 | 3.0 | 27.0 | 0.0 | 12.8 | OVR | 15.3 | 0.0 | N/A |
| | | 11/16/10 | 50.8% | 0.0% | | 58.0% | 0.8% | 4426 | 606 | 53.0 | 4.0 | OVR | 0.4 | 65.1 | OVR | 15.2 | 1.5 | N/A |
| | | 02/07/11 | 50.2% | 0.5% | N/A | 54.6% | 2.0% | 271 | 0.7 | 0.0 | 0.0 | 0.0 | 16.9 | 0.0 | 1.0 | 2.3 | 19.3 | N/A |
| | | 04/08/11 | 54.0% | 0.2% | 0.2% | 64.0% | 0.5% | 5.1 | 0.2 | 0.0 | 0.0 | 0.0 | 14.1 | 0.1 | 2.0 | 4.4 | 14.1 | N/A |
| | | 08/04/11 | 68.1% | 0.0% | N/A | 57.4% | 19.4% | 21.0 | 0.7 | 1.0 | 0.0 | 0.0 | 13.4 | 0.0 | 0.0 | 3.9 | 13.8 | N/A |
| | | 11/09/11 | 51.8% | 0.1% | 0.0% | 59.5% | 2.7% | 0.0 | 0.0 | 0.0 | 0.0 | 0.0 | 16.2 | 0.0 | 0.0 | 3.6 | 16.9 | N/A |
| | | 01/31/12 | 59.9% | 0.0% | N/A | 63.2% | 0.0% | 0.0 | 1.7 | 0.0 | 0.0 | 0.0 | 10.2 | 0.0 | 0.0 | 10.5 | 8.5 | N/A |
| | | 4/12/2012[9] | 54.6% | 0.0% | N/A | 61.5% | 0.4% | 1.8 | 0.6 | NM | NM | NM | NM | 0.0 | 0.0 | 0.6 | 20.7 | N/A |
| | | 07/16/12 | 50.4% | 0.0% | N/A | 45.6% | 0.4% | 5.9 | 1.6 | N/A | N/A | N/A | N/A | 0.0 | 0.0 | 0.5 | 20.2 | N/A |
| | | 10/10/12 | 54.6% | 0.0% | N/A | 51.7% | 3.9% | 1.0 | 0.9 | NM | NM | NM | NM | 0.0 | 0.0 | 0.1 | 19.4 | N/A |
| | | 02/12/13[12] | 55.2% | 0.1% | N/A | 47.5% | 0.5% | 4.91 | 0.6 | NM | NM | NM | NM | 0.1* | 0.2* | 0.1 | 21.0 | N/A |
| | 10 ft | 09/08/10 | 51.6% | 0.5% | | 37.9% | 0.7% | 79370 | 356 | 138 | 6.0 | 50.0 | 0.0 | 38.3 | OVR | 14.8 | 0.0 | N/A |
| | | 11/17/10 | 51.3% | 0.0% | | 60.9% | 0.9% | 6.3 | 0.2 | 0.0 | 0.0 | 0.0 | 7.2 | 0.4 | 9.0 | 11.3 | 6.4 | N/A |
| | | 02/07/11 | 51.2% | 0.5% | N/A | 45.3% | 0.4% | 98 | 0.6 | 0.0 | 0.0 | 0.0 | 7.9 | 0.1 | 1.0 | 10.0 | 8.6 | N/A |
| | | 04/08/11 | 53.0% | 0.0% | N/A | 63.0% | 0.0% | 111 | 12.5 | 2.0 | 0.0 | 0.0 | 1.9 | 0.2 | 4.0 | 10.8 | 3.7 | N/A |
| | | 08/04/11 | 50.1% | 0.0% | N/A | 53.8% | 0.3% | 34650 | 325.8 | 283 | 5.0 | 56.0 | 0.2 | 47.5 | OVR | 17.2 | 0.3 | N/A |
| | | 11/09/11 | 54.8% | 0.0% | N/A | 52.6% | 0.0% | 0.35 | 0.3 | 0.0 | 0.0 | 0.0 | 7.9 | 0.0 | 0.0 | 10.1 | 7.9 | N/A |
| | | 01/31/12 | 55.8% | 0.0% | N/A | 63.6% | 0.0% | 17100 | 304.6 | 2.0 | 0.0 | 21.0 | 3.6 | 9.3 | OVR | 14.8 | 0.6 | N/A |
| | | 04/12/12 | 66.2% | 0.0% | N/A | 57.8% | 0.1% | 0.8 | 0.6 | NM | NM | NM | NM | 0.0 | 0.0 | 2.2 | 19.6 | N/A |
| | | 07/16/12 | 61.8% | 0.0% | N/A | 45.7% | 0.2% | 4.6 | 1.5 | N/A | N/A | N/A | N/A | 0.0 | 0.0 | 1.9 | 19.3 | N/A |
| | | 10/11/12 | 51.7% | 0.0% | N/A | 42.6% | 0.4% | 2.0 | 0.9 | NM | NM | NM | NM | 0.0 | 0.0 | 0.6 | 20.0 | N/A |
| | | 02/05/13 | 51.7% | 0.9% | N/A | 50.5% | 2.0% | 2.23 | 0.2 | NM | NM | NM | NM | 0.0 | 0.0 | 0.4 | 20.5 | N/A |
| | 31.5 ft | 09/08/10 | 56.6% | 2.7% | | 46.9% | 2.6% | 3210000 | 380 | 711 | 41.0 | OVR | 0.0 | OVR | OVR | 12.9 | 0.0 | 2.3% |
| | | 11/17/10 | 66.5% | 1.5% | | 59.8% | 1.9% | 1.2 | 462 | 753 | 10.0 | OVR | 2.1 | OVR | OVR | 13.3 | 2.3 | N/A |
| | | 02/07/11 | 51.3% | 0.0% | N/A | 38.0% | 0.0% | 60660 | 318 | 62.0 | 8.0 | OVR | 0.5 | OVR | OVR | 15.1 | 0.3 | N/A |
| | | 04/11/11 | 53.4% | 0.0% | N/A | 68.5% | 0.0% | 10000 | 416 | 1211 | 76.0 | OVR | 0.0 | OVR | OVR | 13.2 | 0.6 | N/A |
| | | 08/04/11 | 55.5% | 1.5% | N/A | 54.1% | 1.9% | OVR | 327.3 | 1387 | 33.0 | 100.0 | 0.3 | OVR | OVR | 14.5 | 0.3 | N/A |
| | | 11/09/11 | 55.1% | 0.0% | N/A | 54.1% | 0.0% | 88200 | 281.8 | 411 | 29.0 | OVR | 0.0 | OVR | OVR | 13.7 | 0.4 | N/A |
| | | 01/31/12 | 56.1% | 0.1% | OVR | 68.1% | 0.2% | 127000 | 312.7 | 61.0 | 6.0 | 72.0 | 1.6 | OVR | OVR | 13.9 | 0.4 | N/A |
| | | 04/12/12 | 51.6% | 0.0% | N/A | 51.5% | 0.0% | 2950 | 375 | NM | NM | NM | NM | 2.8 | 57.0 | 12.4 | 0.2 | N/A |
| | | 07/16/12 | 50.3% | 0.0% | N/A | 40.0% | 0.0% | 90.3 | 5.8 | N/A | N/A | N/A | N/A | 0.0 | 0.0 | 8.6 | 7.9 | N/A |
| | | 10/11/12 | 51.3% | 0.0% | N/A | 44.0% | 0.0% | 21.0 | 1.7 | NM | NM | NM | NM | 0.0 | 0.0 | 5.7 | 12.3 | N/A |
| | | 02/05/13 | 53.1% | 0.0% | N/A | 48.6% | 0.0% | 40.0 | 0.3 | NM | NM | NM | NM | 0.0 | 0.0 | 8.9 | 10.3 | N/A |
| | 39 ft | 09/08/10 | NS | NS | | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS |
| | | 11/16/10 | NS | NS | | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS |
| | | 02/07/11 | NS | NS | N/A | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS |
| | | 04/11/11 | 53.0% | 0.0% | N/A | 91.8% | 0.0% | 11300 | 420 | 1222 | 100 | OVR | 0.5 | OVR | OVR | 12.8 | 0.5 | N/A |
| | | 08/04/11 | NS | NS | N/A | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS |
| | | 11/09/11 | NS | NS | N/A | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS |
| | | 01/31/12 | 51.9% | 0.7% | OVR | 68.2% | 0.9% | 146000 | 350.9 | 9.0 | 11.0 | 91.0 | 4.4 | OVR | OVR | 13.9 | 0.5 | N/A |
| | | 04/12/12 | 54.3% | 0.0% | N/A | 60.1% | 0.0% | 4070 | 477 | NM | NM | NM | NM | 5.1 | OVR | 12.5 | 0.3 | N/A |
| | | 07/16/12 | 51.4% | 0.0% | N/A | 55.6% | 0.0% | 138 | 7.3 | N/A | N/A | N/A | N/A | 0.0 | 0.0 | 10.4 | 4.8 | N/A |
| | | 10/11/12 | 50.6% | 0.0% | N/A | 44.6% | 0.0% | 77.0 | 7.8 | NM | NM | NM | NM | 0.0 | 0.0 | 9.7 | 6.1 | N/A |
| | | 02/05/13 | 51.8% | 0.0% | N/A | 49.5% | 0.0% | 14.7 | 0.6 | NM | NM | NM | NM | 0.0 | 0.0 | 12.3 | 6.1 | N/A |

SEE LAST PAGE OF TABLE FOR NOTES

**TABLE 3**
**SOIL VAPOR SAMPLING - TEDLAR SAMPLING DATA**

| Reading Location | | | Shroud | Tedlar Bag 1 | | Shroud | Tedlar Bag 2 | | | | | | | | | | | Tedlar Bag 3 |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| Instrument | | | Dielectric | | Landtec | Dielectric | | FID | PID | Multi-gas | | | | Landtec | | | | Dielectric |
| Location | Depth | Date | Helium in Shroud Before | Helium Before | CH4 (%) | Helium in Shroud After | Helium After | FID (ppm) | PID (ppm) | CO (ppm) | H2S (ppm) | LEL (%) | O2 (%) | CH4 (%) | LEL (%) | CO2 (%) | O2 (%) | Direct Port Reading After |
| VMP-7 | 5ft | 08/26/10 | 56.6% | 1.7% | | 56.3% | 1.5% | 28.7 | 0.0 | 0.0 | 1.0 | 0.0 | 0.8 | 0.0 | 0.0 | 4.5 | 13.4 | N/A |
| | | 11/19/10 | 50.2% | 0.9% | | 66.7% | 0.5% | 61.5 | 4.5 | 5.0 | 0.0 | 10.0 | 2.9 | 0.2 | 2.0 | 15.3 | 2.6 | N/A |
| | | 02/07/11 | 52.8% | 0.0% | 0.0% | 45.0% | 0.2% | 291 | 0.3 | 0.0 | 0.0 | 0.0 | 16.5 | 0.0 | 0.0 | 3.6 | 17.7 | N/A |
| | | 04/07/11 | 61.6% | 0.0% | 0.0% | 53.8% | 0.0% | 34.2 | 0.1 | 0.0 | 0.0 | 0.0 | 12.6 | 0.0 | 0.0 | 6.6 | 12.8 | N/A |
| | | 08/02/11 | 59.8% | 0.2% | N/A | 58.3% | 0.5% | 34750 | 198 | 269 | 0.0 | 23.0 | 5.0 | 16.6 | OVR | 14.8 | 0.4 | N/A |
| | | 11/10/11 | 52.1% | 0.0% | N/A | 50.3% | 0.0% | 0.0 | 0.4 | 0.0 | 0.0 | 0.0 | 5.6 | 0.0 | 0.0 | 13.3 | 5.5 | N/A |
| | | 01/31/12 | 51.7% | 0.0% | N/A | 56.0% | 0.0% | 0.0 | 0.4 | 0.0 | 0.0 | 0.0 | 5.0 | 0.0 | 0.0 | 11.0 | 5.1 | N/A |
| | | 04/12/12 | 52.4% | 0.0% | 0.0% | 86.9% | 0.3% | 1.0 | 0.07 | NM | NM | NM | NM | 0.0 | 0.0 | 0.4 | 20.9 | N/A |
| | | 7/31/12 [9] | 53.8% | 0.0% | N/A | 49.8% | 2.7% | 3.4 | 0.8 | NM | NM | NM | NM | 0.0 | 0.0 | 0.5 | 19.5 | N/A |
| | | 10/10/12 | 68.2% | 0.0% | N/A | 45.9% | 0.1% | 1.0 | 0.6 | NM | NM | NM | NM | 0.0 | 0.0 | 0.5 | 21.4 | N/A |
| | | 02/13/13[10] | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS |
| | 13.5 ft | 08/26/10 | 50.8% | 0.0% | | 56.2% | 0.0% | 5130 | 62.8 | 2.0 | 2.0 | 16.0 | 0.0 | 1.1 | 22.0 | 16.7 | 0.4 | N/A |
| | | 11/19/10 | 53.8% | 0.0% | | 51.0% | 0.0% | 2157 | 58.8 | 3.0 | 0.0 | 38.0 | 0.7 | 3.4 | 68.0 | 16.3 | 0.7 | N/A |
| | | 02/07/11 | 54.2% | 0.0% | 0.0% | 54.1% | 0.0% | 240 | 0.4 | 0.0 | 0.0 | 0.0 | 8.4 | 0.0 | 0.0 | 10.9 | 9.0 | N/A |
| | | 04/07/11 | 57.5% | 0.0% | 0.0% | 62.8% | 0.0% | 45.0 | 0.3 | 0.0 | 0.0 | 0.0 | 8.4 | 0.0 | 0.0 | 10.2 | 8.3 | N/A |
| | | 08/02/11 | 56.0% | 0.0% | N/A | 68.5% | 0.3% | 31200 | 234 | 362 | 0.0 | 40 | 9.5 | 10.8 | OVR | 16.7 | 0.1 | N/A |
| | | 11/10/11 | 62.1% | 0.0% | N/A | 66.2% | 0.0% | 0.0 | 0.8 | 0.0 | 0.0 | 0.0 | 2.2 | 0.0 | 0.0 | 16.0 | 2.2 | N/A |
| | | 01/31/12 | 52.5% | 0.0% | N/A | 61.4% | 0.0% | 235 | 15.4 | 0.0 | 0.0 | 3.0 | 1.0 | 0.0 | 0.0 | 14.0 | 0.7 | N/A |
| | | 04/12/12 | 59.5% | 0.1% | 0.0% | 60.8% | 0.2% | 1.0 | 0.6 | NM | NM | NM | NM | 0.0 | 0.0 | 0.6 | 20.7 | N/A |
| | | 07/20/12 | 51.0% | 0.0% | N/A | 54.0% | 0.0% | 5.1 | 2.0 | NM | NM | NM | NM | 0.0 | 0.0 | 1.6 | 19.4 | N/A |
| | | 10/10/12 | 65.2% | 0.0% | N/A | 57.5% | 0.0% | 0.0 | 1.2 | NM | NM | NM | NM | 0.0 | 0.0 | 0.5 | 21.7 | N/A |
| | | 02/13/13[9] | 52.8% | 0.1% | N/A | 51.6% | 0.1% | 1.75 | 0.2 | NM | NM | NM | NM | 0.0 | 0.0 | 0.1 | 20.9 | N/A |
| | 29.5 ft | 08/31/10 | 50.4% | 0.9% | | 48.3% | 0.8% | 73090 | 234 | 187 | 10.0 | 0.0 | 0.0 | 57.1 | OVR | 15.0 | 0.3 | N/A |
| | | 11/19/10 | 53.7% | 0.0% | | 69.3% | 0.0% | 4264 | 120 | 32.0 | 1.0 | OVR | 0.5 | 19.0 | OVR | 15.9 | 0.8 | N/A |
| | | 02/07/11 | 56.7% | 0.0% | 26.8% | 56.2% | 0.0% | 17840 | 910 | 4.0 | 12.0 | 56.0 | 3.4 | 27.6 | OVR | 17.1 | 0.4 | N/A |
| | | 04/07/11 | 59.2% | 0.0% | 19.8% | 57.6% | 0.0% | 28300 | 430 | 2.0 | 5.0 | 25.0 | 0.4 | 23.4 | OVR | 15.1 | 0.2 | N/A |
| | | 08/02/11 | 50.0% | 0.5% | N/A | 54.0% | 0.6% | 79000 | 307 | 66.0 | 1.0 | 57.0 | 4.9 | 68.2 | OVR | 14.5 | 0.2 | N/A |
| | | 11/11/11 | 52.0% | 0.0% | N/A | 70.1% | 0.0% | 23400 | 409.7 | 0.0 | 8.0 | 16.0 | 0.4 | 29.9 | OVR | 16.3 | 0.8 | N/A |
| | | 01/31/12 | 52.0% | 0.0% | N/A | 61.5% | 0.0% | 17800 | 347.4 | 0.0 | 2.0 | 28.0 | 9.8 | 16.0 | OVR | 16.0 | 0.2 | N/A |
| | | 04/12/12 | 53.6% | 0.0% | 0.0% | 56.2% | 0.0% | 25.0 | 5.3 | NM | NM | NM | NM | 0.0 | 0.0 | 9.2 | 11.3 | N/A |
| | | 07/20/12 | 51.5% | 0.0% | N/A | 51.5% | 0.0% | 3.1 | 3.1 | NM | NM | NM | NM | 0.0 | 0.0 | 5.9 | 16.8 | N/A |
| | | 10/10/12 | 63.0% | 0.0% | N/A | 40.1% | 0.0% | 2.0 | 1.0 | NM | NM | NM | NM | 0.0 | 0.0 | 4.8 | 17.8 | N/A |
| | | 02/13/13[10] | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS |
| | 38 ft | 08/31/10 | NS | NS | | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS |
| | | 11/19/10 | NS | NS | | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS |
| | | 02/07/11 | 62.2% | 0.1% | 32.9% | 51.0% | 0.0% | 21220 | 944 | 0.0 | 35.0 | 58.0 | 1.8 | 33.7 | OVR | 16.5 | 0.1 | N/A |
| | | 04/07/11 | 76.5% | 0.0% | 25.1% | 43.2% | 0.0% | 31250 | 448 | 8.0 | 6.0 | 35.0 | 0.5 | 25.9 | OVR | 14.9 | 0.4 | N/A |
| | | 08/02/11 | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS |
| | | 11/11/11 | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS |
| | | 01/31/12 | 51.6% | 0.0% | N/A | 60.5% | 0.0% | 20700 | 400.8 | 0.0 | 9.0 | 34.0 | 0.6 | 21.9 | OVR | 16.3 | 0.5 | N/A |
| | | 04/12/12 [11] | 54.7% | 0.3% | 0.0% | 80.8% | 0.4% | 90.0 | 24.8 | NM | NM | NM | NM | 0.0 | 0.0 | 10.7 | 9.4 | N/A |
| | | 04/25/12 | 53.5% | 0.0% | N/A | 64.1% | 0.0% | 31.4 | 11.6 | NM | NM | NM | NM | 0.2 | 5.0 | 6.4 | 14.4 | N/A |
| | | 7/31/12 [10] | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS |
| | | 10/11/12 | 66.3% | 0.0% | N/A | 42.0% | 0.2% | 2.0 | 0.8 | NM | NM | NM | NM | 0.0 | 0.0 | 1.5 | 20.5 | N/A |
| | | 02/13/13[10] | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS |

SEE LAST PAGE OF TABLE FOR NOTES

**TABLE 3**
**SOIL VAPOR SAMPLING - TEDLAR SAMPLING DATA**

| Reading Location | | | Shroud | Tedlar Bag 1 | | Shroud | Tedlar Bag 2 | | | | | | | | | | Tedlar Bag 3 |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| Instrument | | | Dielectric | | Landtec | Dielectric | | FID | PID | Multi-gas | | | | Landtec | | | | Dielectric |
| Location | Depth | Date | Helium in Shroud Before | Helium Before | CH4 (%) | Helium in Shroud After | Helium After | FID (ppm) | PID (ppm) | CO (ppm) | H2S (ppm) | LEL (%) | O2 (%) | CH4 (%) | LEL (%) | CO2 (%) | O2 (%) | Direct Port Reading After |
| VMP-8 | 5 ft | 08/30/10 | 52.0% | 0.0% | | 58.6% | 0.1% | 55.0 | 0.4 | 0.0 | 0.0 | 0.0 | 6.4 | 0.0 | 0.0 | 7.3 | 13.4 | N/A |
| | | 11/18/10 | 62.8% | 0.0% | | 65.5% | 0.0% | 617 | 2.6 | 4.0 | 0.0 | 5.0 | 14.1 | 0.2 | 4.0 | 2.6 | 19.4 | N/A |
| | | 02/10/11 | 51.2% | 0.0% | 0.0% | 40.5% | 0.0% | 153 | 0.0 | 1.0 | 0.0 | 0.0 | 14.8 | 0.0 | 0.0 | 4.7 | 15.0 | N/A |
| | | 04/07/11 | 53.0% | 0.0% | N/A | 82.0% | 0.3% | | 0.3 | 0.0 | 0.0 | 0.0 | 18.5 | 0.0 | 0.0 | 3.0 | 19.0 | N/A |
| | | 07/27/11 | 61.7% | 0.0% | N/A | 50.8% | 0.0% | 0.0 | 5.1 | 0.0 | 0.0 | 0.0 | 9.4 | 0.0 | 0.0 | 8.9 | 12.9 | N/A |
| | | 11/03/11 | 67.1% | 0.0% | N/A | 60.0% | 0.1% | 4.35 | 0.2 | 0.0 | 0.0 | 0.0 | 18.6 | 0.0 | 0.0 | 1.2 | 16.4 | N/A |
| | | 01/23/12 | 55.4% | 0.0% | N/A | 52.3% | 2.4% | 1.0 | 0.1 | 0.0 | 0.0 | 0.0 | 19.2 | 0.0 | 0.0 | 1.4 | 20.0 | N/A |
| | | 04/10/12 | 51.4% | 0.0% | N/A | 60.3% | 0.1% | 1.7 | 0.5 | NM | NM | NM | NM | 0.0 | 0.0 | 2.8 | 17.3 | N/A |
| | | 07/13/2012[11] | 51.7% | 0.0% | N/A | 51.3% | 0.1% | 5.1 | 5.1 | N/A | N/A | N/A | N/A | 0.0 | 0.0 | 3.6 | 18.1 | N/A |
| | | 07/31/12 | 58.2% | 0.0% | N/A | 50.7% | 0.1% | 2.9 | 0.6 | N/A | N/A | N/A | N/A | 0.0 | 0.0 | 3.4 | 18.2 | N/A |
| | | 10/04/12 | 51.6% | 0.0% | N/A | 51.9% | 0.1% | 1.0 | 0.5 | NM | NM | NM | NM | 0.0 | 0.0 | 2.0 | 18.1 | N/A |
| | | 01/24/13 | 59.9% | 0.0% | N/A | 53.3% | 0.0% | 2.46 | 0.2 | NM | NM | NM | NM | 0.0 | 0.0 | 0.7 | 19.7 | N/A |
| | 9.5 ft | 08/30/10 | 56.2% | 0.0% | | 48.9% | 0.0% | 66.2 | 0.2 | 0.0 | 0.0 | 0.0 | 0.0 | 0.0 | 0.0 | 9.2 | 10.1 | N/A |
| | | 11/18/10 | 63.7% | 0.0% | | 100.0% | 0.1% | 27.2 | 2.1 | 4.0 | 0.0 | 7.0 | 12.2 | 0.3 | 6.0 | 9.6 | 12.5 | N/A |
| | | 02/10/11 | 51.0% | 0.0% | 0.0% | 61.0% | 0.0% | 103 | 0.0 | 0.0 | 0.0 | 0.0 | 12.5 | 0.0 | 0.0 | 9.0 | 11.6 | N/A |
| | | 04/07/11 | 54.0% | 0.0% | N/A | 67.0% | 0.0% | | 0.1 | 0.0 | 0.0 | 0.0 | 12.6 | 0.1 | 2.0 | 7.0 | 13.4 | N/A |
| | | 07/27/11 | 53.5% | 0.0% | N/A | 53.8% | 0.0% | 0.0 | 4.1 | 5.0 | 0.0 | 0.0 | 11.0 | 0.0 | 0.0 | 6.1 | 14.4 | N/A |
| | | 11/03/11 | 51.8% | 0.0% | N/A | 55.2% | 0.0% | 3.9 | 0.3 | 0.0 | 0.0 | 0.0 | 18.6 | 0.0 | 0.0 | 7.2 | 13.7 | N/A |
| | | 01/23/12 | 63.0% | 0.0% | N/A | 49.0% | 0.0% | 0.0 | 0.5 | 0.0 | 0.0 | 0.0 | 14.6 | 0.0 | 0.0 | 6.7 | 15.3 | N/A |
| | | 04/10/12 | 64.7% | 0.0% | N/A | 57.3% | 0.0% | 1.3 | 0.6 | NM | NM | NM | NM | 0.0 | 0.0 | 5.7 | 15.4 | N/A |
| | | 07/13/12 | 51.6% | 0.0% | N/A | 50.0% | 0.0% | 3.9 | 3.9 | N/A | N/A | N/A | N/A | 0.0 | 0.0 | 6.0 | 15.5 | N/A |
| | | 10/04/12 | 59.6% | 0.0% | N/A | 40.0% | 0.0% | 1.0 | 0.8 | NM | NM | NM | NM | 0.0 | 0.0 | 4.6 | 16.4 | N/A |
| | | 01/24/13 | 67.8% | 0.0% | N/A | 74.5% | 0.1% | 1.07 | 0.3 | NM | NM | NM | NM | 0.0 | 0.0 | 3.4 | 17.8 | N/A |
| | 23.5 ft | 08/30/10 | 55.2% | 0.0% | | 60.0% | 0.0% | 34.2 | 0.0 | 1.0 | 0.0 | 3.0 | 0.0 | 0.0 | 0.0 | 9.3 | 9.9 | N/A |
| | | 11/19/10 | 57.8% | 0.0% | | 59.8% | 0.0% | 3.6 | 1.6 | 0.0 | 0.0 | 6.0 | 10.5 | 0.0 | 0.0 | 10.1 | 11.0 | N/A |
| | | 02/10/11 | 52.0% | 0.0% | 0.0% | 69.3% | 0.0% | 112 | 0.0 | 0.0 | 0.0 | 0.0 | 11.5 | 0.0 | 0.0 | 10.1 | 11.7 | N/A |
| | | 04/07/11 | 55.0% | 0.0% | N/A | 85.0% | 0.0% | | 0.0 | 0.0 | 0.0 | 0.0 | 12.0 | 0.0 | 0.0 | 8.6 | 12.0 | N/A |
| | | 07/27/11 | 55.7% | 0.0% | N/A | 56.3% | 0.0% | 0.0 | 3.1 | 2.0 | 0.0 | 0.0 | 8.2 | 0.1 | 2.0 | 8.9 | 11.3 | N/A |
| | | 11/06/11 | 74.5% | 0.0% | N/A | 70.2% | 0.0% | | 0.3 | 0.0 | 0.0 | 0.0 | 13.6 | 0.0 | 0.0 | 8.7 | 12.6 | N/A |
| | | 01/23/12 | 54.0% | 0.0% | N/A | 91.5% | 0.0% | 1.4 | 0.5 | 0.0 | 0.0 | 0.0 | 13.7 | 0.0 | 0.0 | 8.1 | 14.0 | N/A |
| | | 04/10/12 | 60.6% | 0.0% | N/A | 66.3% | 0.1% | 1.5 | 0.5 | NM | NM | NM | NM | 0.0 | 0.0 | 6.5 | 14.6 | N/A |
| | | 07/13/12 | 57.2% | 0.0% | N/A | 40.0% | 0.0% | 4.7 | 4.7 | NM | NM | NM | NM | 0.0 | 0.0 | 6.3 | 14.6 | N/A |
| | | 10/04/12 | 53.2% | 0.0% | N/A | 63.0% | 0.0% | 4.0 | 1.1 | NM | NM | NM | NM | 0.0 | 0.0 | 5.5 | 15.9 | N/A |
| | | 01/24/13 | 56.6% | 0.0% | N/A | 51.0% | 0.0% | 1.0 | 0.3 | NM | NM | NM | NM | 0.0 | 0.0 | 4.7 | 16.5 | N/A |
| | 35.5 ft | 08/30/10 | NS | NS | | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS |
| | | 11/19/10 | NS | NS | | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS |
| | | 02/10/11 | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS |
| | | 04/07/11 | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS |
| | | 07/27/11 | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS |
| | | 11/06/11 | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS |
| | | 01/23/12 | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS |
| | | 4/10/12 [13] | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS |
| | | 7/13/12 [13] | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS |
| | | 10/4/12[13] | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS |
| | | 01/24/13[13] | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS |

SEE LAST PAGE OF TABLE FOR NOTES

**TABLE 3**
**SOIL VAPOR SAMPLING - TEDLAR SAMPLING DATA**

| Reading Location | | | Shroud | Tedlar Bag 1 | | Shroud | Tedlar Bag 2 | | | | | | | | | | | Tedlar Bag 3 |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| Instrument | | | Dielectric | | Landtec | Dielectric | | FID | PID | Multi-gas | | | | Landtec | | | | Dielectric |
| Location | Depth | Date | Helium in Shroud Before | Helium Before | CH4 (%) | Helium in Shroud After | Helium After | FID (ppm) | PID (ppm) | CO (ppm) | H2S (ppm) | LEL (%) | O2 (%) | CH4 (%) | LEL (%) | CO2 (%) | O2 (%) | Direct Port Reading After |
| VMP-9 | 5 ft | 08/26/10 | 50.2% | 0.0% | | 45.6% | 0.0% | 36.7 | 0.0 | 2.0 | 0.0 | 3.0 | 0.4 | 0.4 | 8.0 | 11.6 | 4.7 | N/A |
| | | 11/19/10 | 66.3% | 0.0% | | 65.7% | 0.0% | 4.0 | 2.1 | 1.0 | 0.0 | 0.0 | 20.1 | 0.1 | 1.0 | 0.8 | 20.1 | N/A |
| | | 02/08/11 | 67.4% | 0.0% | 0.0% | 51.0% | 0.0% | 352 | 0.0 | 0.0 | 0.0 | 0.0 | 19.2 | 0.0 | 0.0 | 1.8 | 19.1 | N/A |
| | | 04/06/11 | 50.3% | 0.0% | N/A | 62.2% | 0.0% | 0.0 | 1.6 | 0.0 | 0.0 | 0.0 | 0.4 | 0.0 | 0.0 | 1.1 | 5.8 | N/A |
| | | 08/02/11 | 52.5% | 0.0% | N/A | 55.6% | 0.4% | 7550 | 92.3 | 4.0 | 0.0 | 13.0 | 0.5 | 0.9 | 19.0 | 14.9 | 0.5 | N/A |
| | | 11/04/11 | 53.8% | 0.0% | N/A | 53.8% | 0.0% | | 0.5 | 0.0 | 0.0 | 0.0 | 18.4 | 0.0 | 0.0 | 3.8 | 16.7 | N/A |
| | | 01/26/12 | 55.1% | 0.0% | N/A | 66.2% | 0.0% | 0.0 | 0.5 | 0.0 | 0.0 | 0.0 | 17.7 | 0.1 | 2.0 | 13.8 | 2.2 | N/A |
| | | 04/11/12 | 55.6% | 0.0% | N/A | 50.5% | 0.0% | 0.8 | 0.2 | NM | NM | NM | NM | 0.0 | 0.0 | 0.6 | 20.2 | N/A |
| | | 07/13/12 | 68.7% | 0.0% | 0.0% | 59.9% | 0.0% | 3.2 | 0.4 | NM | NM | NM | NM | 0.0 | 0.0 | 0.6 | 19.7 | N/A |
| | | 10/10/12 | 54.20% | 0.0% | N/A | 47.3% | 0.0% | 1.0 | 0.6 | NM | NM | NM | NM | 0.0 | 0.0 | 0.3 | 20.6 | N/A |
| | | 02/15/13[11] | 51.7% | 0.0% | N/A | 51.7% | 0.1% | 0.97 | 0.3 | NM | NM | NM | NM | 0.0 | 0.0 | 0.2 | 20.4 | N/A |
| | 11.5 ft | 08/26/10 | 54.2% | 0.0% | | 34.7% | 0.3% | 19620 | 36.7 | 8.0 | 0.0 | 42.0 | 0.0 | 3.2 | 64.0 | 13.7 | 0.5 | N/A |
| | | 11/19/10 | 57.5% | 0.0% | | 57.8% | 0.0% | 1714 | 23.6 | 74.0 | 0.0 | 21.0 | 0.9 | 1.7 | 35.0 | 15.8 | 0.8 | N/A |
| | | 02/09/11 | 62.7% | 0.0% | 0.0% | 50.9% | 0.0% | 30.8 | 0.4 | 3.0 | 0.0 | 0.0 | 3.1 | 0.0 | 1.0 | 14.8 | 3.4 | N/A |
| | | 04/06/11 | 53.7% | 0.0% | N/A | 56.3% | 0.0% | 60.8 | 0.0 | 0.0 | 0.0 | 0.0 | 0.0 | 0.0 | 0.0 | 10.4 | 1.4 | N/A |
| | | 08/02/11 | 58.6% | 0.8% | 5.6% | 57.2% | 0.9% | 37600 | 68.9 | 41.0 | 0.0 | 0.0 | 0.2 | 6 | OVR | 13.4 | 0.3 | N/A |
| | | 11/04/11 | 57.1% | 0.0% | N/A | 51.7% | 0.0% | | 0.7 | 0.0 | 0.0 | 0.0 | 14.9 | 0.0 | 0.0 | 10.0 | 9.8 | N/A |
| | | 01/26/12 | 54.0% | 0.4% | N/A | 72.5% | 0.0% | 0.0 | 0.6 | 0.0 | 0.0 | 0.0 | 14.6 | 0.0 | 1.0 | 14.4 | 1.5 | N/A |
| | | 04/11/12 | 55.4% | 0.0% | N/A | 50.5% | 0.1% | 0.6 | 0.2 | NM | NM | NM | NM | 0.0 | 0.0 | 1.4 | 19.6 | N/A |
| | | 07/13/12 | 72.4% | 0.4% | 0.0% | 60.1% | 0.9% | 2.9 | 0.2 | NM | NM | NM | NM | 0.0 | 0.0 | 1.2 | 19.4 | N/A |
| | | 10/10/12 | 46.6% | 0.0% | N/A | 40.6% | 0.5% | 2.0 | 3.2 | NM | NM | NM | NM | 0.0 | 0.0 | 0.6 | 20.6 | N/A |
| | | 01/25/13 | 66.4% | 0.0% | N/A | 34.0% | 0.0% | 0.87 | 0.5 | NM | NM | NM | NM | 0.0 | 0.0 | 0.4 | 21.6 | N/A |
| | 25.5 ft | 08/26/10 | 50.2% | 0.4% | | 47.6% | 1.0% | 46560 | 153 | 32.0 | 12.0 | Neg | 0.0 | 19.4 | 388 | 13.8 | 0.0 | N/A |
| | | 11/19/10 | 51.0% | 0.0% | | 55.8% | 0.2% | 3594 | 66.6 | 232 | 8.0 | 73.0 | 0.5 | 6.2 | OVR | 15.4 | 0.4 | N/A |
| | | 02/09/11 | 64.9% | 0.0% | N/A | 40.5% | 0.0% | 7530 | 103 | 4.0 | 5.0 | 44.0 | 0.7 | 3.0 | 53.0 | 18.7 | 0.7 | N/A |
| | | 04/08/11 | 54.0% | 0.0% | N/A | 80.0% | 0.0% | | 45.0 | 0.0 | 2.0 | 14.0 | 0.0 | 1.5 | 31.0 | 15.8 | 0.6 | N/A |
| | | 08/02/11 | 56.1% | 0.3% | N/A | 58.1% | 0.5% | 46300 | 87.2 | 76.0 | 13.0 | 74.0 | 0.3 | 11.7 | OVR | 12.8 | 0.4 | N/A |
| | | 11/04/11 | 60.7% | 0.0% | N/A | 50.2% | 0.0% | | 165.8 | 0.0 | 3.0 | 22.0 | 0.8 | 2.0 | 40.0 | 15.5 | 0.2 | N/A |
| | | 01/26/12 | 54.5% | 0.0% | N/A | 67.1% | 0.0% | 5200 | 62.3 | 2.0 | 0.0 | 9.0 | 10.0 | 0.9 | 18.0 | 15.7 | 0.7 | N/A |
| | | 04/11/12 | 61.0% | 0.0% | N/A | 60.1% | 0.3% | 0.7 | 0.3 | NM | NM | NM | NM | 0.0 | 0.0 | 3.8 | 18.0 | N/A |
| | | 07/13/12 | 53.2% | 0.0% | 0.0% | 59.6% | 0.1% | 3.7 | 0.6 | NM | NM | NM | NM | 0.0 | 0.0 | 2.6 | 18.7 | N/A |
| | | 10/10/12 | 53.5% | 0.0% | N/A | 43.5% | 0.0% | 0.0 | 0.7 | NM | NM | NM | NM | 0.0 | 0.0 | 1.9 | 19.7 | N/A |
| | | 01/30/13 | 66.5% | 0.0% | N/A | 60.4% | 0.0% | 0.55 | 0.4 | NM | NM | NM | NM | 0.0 | 0.0 | 1.4 | 20.1 | N/A |
| | 38.5 ft | 08/26/10 | 62.5% | NS | | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS |
| | | 11/19/10 | NS | NS | | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS |
| | | 02/09/11 | 50.9% | 0.0% | N/A | 50.0% | 0.0% | 10650 | 226 | 2.0 | 3.0 | 38.0 | 0.6 | 6.3 | OVR | 19.4 | 0.3 | N/A |
| | | 04/08/11 | 52.0% | 0.0% | N/A | 55.0% | 0.0% | | 169 | 0.0 | 7.0 | 20.0 | 0.0 | 3.6 | 81.0 | 17.9 | 0.3 | N/A |
| | | 08/02/11 | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS |
| | | 11/04/11 | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS |
| | | 01/26/12 | 51.5% | 0.0% | N/A | 61.9% | 0.0% | 5900 | 202.1 | 0.0 | 2.0 | 10.0 | 7.4 | 1.5 | 31.0 | 16.0 | 0.4 | N/A |
| | | 04/11/12 | 50.5% | 0.0% | N/A | 51.4% | 0.0% | 2.6 | 1.1 | NM | NM | NM | NM | 0.0 | 0.0 | 8.9 | 13.1 | N/A |
| | | 07/13/12 | 69.1% | 0.0% | 0.0% | 45.1% | 0.3% | 4.7 | 0.7 | NM | NM | NM | NM | 0.0 | 0.0 | 4.9 | 16.2 | N/A |
| | | 10/10/12 | 55.4% | 0.0% | N/A | 46.7% | 0.0% | 95.0 | 14.35 | NM | NM | NM | NM | 0.0 | 0.0 | 6.4 | 14.0 | N/A |
| | | 01/30/13 | 49.4% | 0.0% | N/A | 42.6% | 0.0% | 1.22 | 0.4 | NM | NM | NM | NM | 0.0 | 0.0 | 6.7 | 15.5 | N/A |

SEE LAST PAGE OF TABLE FOR NOTES

**TABLE 3**
**SOIL VAPOR SAMPLING - TEDLAR SAMPLING DATA**

| Reading Location | | | Shroud | Tedlar Bag 1 | | Shroud | Tedlar Bag 2 | | | | | | | | | | Tedlar Bag 3 |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| Instrument | | | Dielectric | | Landtec | Dielectric | | FID | PID | Multi-gas | | | | Landtec | | | | Dielectric |
| Location | Depth | Date | Helium in Shroud Before | Helium Before | CH4 (%) | Helium in Shroud After | Helium After | FID (ppm) | PID (ppm) | CO (ppm) | H2S (ppm) | LEL (%) | O2 (%) | CH4 (%) | LEL (%) | CO2 (%) | O2 (%) | Direct Port Reading After |
| VMP-10 | 5 ft | 09/07/10 | 60.2% | 0.0% | | 35.8% | 0.0% | 0.0 | 0.1 | 0.0 | 0.0 | 0.0 | 0.0 | 0.0 | 0.0 | 6.4 | 14.0 | N/A |
| | | 11/18/10 | 56.5% | 0.0% | | 52.4% | 0.0% | 26.8 | 0.5 | 0.0 | 0.0 | 0.0 | 17.7 | 0.0 | 1.0 | 3.7 | 18.4 | N/A |
| | | 02/10/11 | 50.5% | 0.0% | N/A | 44.0% | 0.0% | 213 | 0.4 | 0.0 | 0.0 | 0.0 | 16.2 | 0.0 | 0.0 | 4.5 | 17.8 | N/A |
| | | 04/05/11 | 62.6% | 0.0% | N/A | 62.7% | 0.1% | 28.8 | 3.2 | 0.0 | 0.0 | 0.0 | 19.0 | 0.0 | 0.0 | 0.9 | 19.8 | N/A |
| | | 07/29/11 | 57.7% | 0.0% | N/A | 48.4% | 0.0% | 0.0 | 1.0 | 1.0 | 0.0 | 0.0 | 16.0 | 0.0 | 0.0 | 4.4 | 17.4 | N/A |
| | | 11/04/11 | 56.0% | 0.0% | N/A | 52.0% | 0.0% | | 0.6 | 0.0 | 0.0 | 0.0 | 18.7 | 0.0 | 0.0 | 3.1 | 17 | N/A |
| | | 01/25/12 | 76.6% | 0.0% | N/A | 63.1% | 0.4% | 1.0 | 1.7 | 0.0 | 0.0 | 0.0 | 20.9 | 0.0 | 0.0 | 0.0 | 20.9 | N/A |
| | | 04/11/12 | 62.5% | 0.0% | N/A | 51.4% | 0.1% | 0.5 | 0.9 | NM | NM | NM | NM | 0.0 | 0.0 | 3.5 | 17.7 | N/A |
| | | 07/13/12 | 50.8% | 0.0% | N/A | 47.1% | 0.0% | 3.2 | 0.2 | NM | NM | NM | NM | 0.0 | 0.0 | 2.2 | 18.3 | N/A |
| | | 10/16/12 | 59.0% | 0.0% | N/A | 53.6% | 0.0% | 0.0 | 0.5 | NM | NM | NM | NM | 0.0 | 0.0 | 1.9 | 17.8 | N/A |
| | | 01/29/13 | 52.6% | 0.0% | N/A | 52.1% | 0.1% | 1.22 | 0.3 | NM | NM | NM | NM | 0.0 | 0.0 | 0.0 | 20.8 | N/A |
| | 10 ft | 09/07/10 | 53.4% | 0.0% | | 25.5% | 0.0% | 0.0 | 0.0 | 0.0 | 0.0 | 0.0 | 0.0 | 0.0 | 0.0 | 9.0 | 11.9 | N/A |
| | | 11/18/10 | 54.4% | 0.0% | | 49.4% | 0.1% | 41.2 | 0.7 | 4.0 | 0.0 | 0.0 | 15.4 | 0.0 | 1.0 | 6.1 | 15.9 | N/A |
| | | 02/11/11 | 54.5% | 0.0% | N/A | 65.5% | 0.0% | 67.4 | 0.1 | 0.0 | 0.0 | 0.0 | 14.9 | 0.0 | 0.0 | 5.5 | 14.7 | N/A |
| | | 04/06/11 | 55.7% | 0.0% | N/A | 59.4% | 0.1% | 38.9 | 0.0 | 0.0 | 0.0 | 0.0 | 18.7 | 0.0 | 0.0 | 0.0 | 19.6 | N/A |
| | | 07/29/11 | 52.8% | 0.0% | N/A | 49.8% | 0.2% | 0.0 | 2.8 | 1.0 | 0.0 | 0.0 | 12.3 | 0.0 | 0.0 | 6.0 | 15.3 | N/A |
| | | 11/04/11 | 57.8% | 0.0% | N/A | 60.0% | 0.0% | | 0.7 | 0.0 | 0.0 | 0.0 | 17.6 | 0.0 | 0.0 | 4.4 | 15.8 | N/A |
| | | 01/25/12 | 53.2% | 0.0% | N/A | 36.0% | 0.0% | 1.6 | 1.8 | 0.0 | 0.0 | 0.0 | 20.9 | 0.0 | 0.0 | 4.1 | 16.3 | N/A |
| | | 04/11/12 | 55.4% | 0.0% | N/A | 56.5% | 0.0% | 0.5 | 0.8 | NM | NM | NM | NM | 0.0 | 0.0 | 4.4 | 16.4 | N/A |
| | | 07/13/12 | 50.4% | 0.0% | N/A | 40.7% | 0.0% | 4.1 | 0.8 | NM | NM | NM | NM | 0.0 | 0.0 | 3.2 | 17.2 | N/A |
| | | 10/16/12 | 53.6% | 0.0% | N/A | 35.8% | 0.0% | 1.0 | 0.6 | NM | NM | NM | NM | 0.0 | 0.0 | 2.4 | 17.2 | N/A |
| | | 01/29/13 | 51.7% | 0.0% | N/A | 55.8% | 0.1% | 0.86 | 0.3 | NM | NM | NM | NM | 0.0 | 0.0 | 0.1 | 20.8 | N/A |
| | 20 ft | 09/07/10 | 51.8% | 0.0% | | 32.9% | 0.0% | 0.0 | 0.0 | 0.0 | 0.0 | 0.0 | 0.0 | 0.0 | 0.0 | 12.3 | 9.4 | N/A |
| | | 11/18/10 | 58.1% | 0.0% | | 41.0% | 0.0% | 85.7 | 0.7 | 4.0 | 0.0 | 0.0 | 13.2 | 0.0 | 0.0 | 9.1 | 13.2 | N/A |
| | | 02/11/11 | 52.6% | 0.0% | N/A | 55.8% | 0.4% | 51.5 | 0.3 | 0.0 | 0.0 | 0.0 | 12.9 | 0.0 | 0.0 | 7.4 | 13.1 | N/A |
| | | 04/06/11 | 53.5% | 0.0% | N/A | 54.7% | 0.2% | 50.0 | 0.6 | 0.0 | 0.0 | 0.0 | 17.7 | 0.0 | 0.0 | 2.7 | 17.6 | N/A |
| | | 07/29/11 | 62.7% | 0.0% | N/A | 45.9% | 0.4% | 0.0 | 3.3 | 2.0 | 0.0 | 0.0 | 9.7 | 0.0 | 0.0 | 7.3 | 13.2 | N/A |
| | | 11/04/11 | 62.1% | 0.0% | N/A | 63.8% | 0.0% | | 0.6 | 0.0 | 0.0 | 0.0 | 16.0 | 0.0 | 0.0 | 6.2 | 14.2 | N/A |
| | | 01/25/12 | 57.2% | 0.0% | N/A | 58.1% | 0.0% | 2.0 | 0.0 | 0.0 | 0.0 | 0.0 | 14.1 | 0.0 | 0.0 | 6.2 | 14.4 | N/A |
| | | 04/11/12 | 56.2% | 0.0% | N/A | 50.5% | 0.1% | 1.4 | 1.1 | NM | NM | NM | NM | 0.0 | 0.0 | 5.5 | 14.6 | N/A |
| | | 07/16/12 | 50.6% | 0.0% | N/A | 46.6% | 0.0% | 1.8 | 0.8 | NM | NM | NM | NM | 0.0 | 0.0 | 5.2 | 15.9 | N/A |
| | | 10/16/12 | 57.6% | 0.0% | N/A | 39.7% | 0.0% | 0.0 | 0.5 | NM | NM | NM | NM | 0.0 | 0.0 | 4.2 | 15.4 | N/A |
| | | 01/29/13 | 55.7% | 0.0% | N/A | 63.6% | 0.1% | 0.99 | 0.4 | NM | NM | NM | NM | 0.0 | 0.0 | 0.4 | 20.4 | N/A |
| | 30 ft | 09/07/10 | NS | NS | | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS |
| | | 11/18/10 | NS | NS | | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS |
| | | 02/11/11 | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS |
| | | 04/06/11 | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS |
| | | 07/29/11 | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS |
| | | 11/04/11 | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS |
| | | 01/25/12 | 71.3% | 0.2% | N/A | 58.9% | 0.2% | 21 | 1.7 | 0.0 | 0.0 | 0.0 | 10.2 | 0.0 | 0.0 | 0.1 | 11.8 | N/A |
| | | 04/11/12 | 51.0% | 0.0% | N/A | 55.7% | 0.0% | 6.7 | 0.9 | NM | NM | NM | NM | 0.0 | 0.0 | 6.5 | 13.1 | N/A |
| | | 07/16/12 | 55.3% | 0.0% | N/A | 50.2% | 0.0% | 2.8 | 0.8 | NM | NM | NM | NM | 0.0 | 0.0 | 6.1 | 14.5 | N/A |
| | | 10/16/12 | 55.8% | 0.0% | N/A | 35.0% | 0.4% | 1.0 | 0.7 | NM | NM | NM | NM | 0.0 | 0.0 | 6.1 | 13.1 | N/A |
| | | 01/29/13 | 52.7% | 0.0% | N/A | 62.3% | 0.1% | 0.62 | 0.4 | NM | NM | NM | NM | 0.0 | 0.0 | 2.6 | 18.9 | N/A |

SEE LAST PAGE OF TABLE FOR NOTES

**TABLE 3**
**SOIL VAPOR SAMPLING - TEDLAR SAMPLING DATA**

| Reading Location | | | Shroud | Tedlar Bag 1 | | Shroud | Tedlar Bag 2 | | | | | | | | | | Tedlar Bag 3 |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| Instrument | | | Dielectric | | Landtec | Dielectric | | FID | PID | Multi-gas | | | | Landtec | | | | Dielectric |
| Location | Depth | Date | Helium in Shroud Before | Helium Before | CH4 (%) | Helium in Shroud After | Helium After | FID (ppm) | PID (ppm) | CO (ppm) | H2S (ppm) | LEL (%) | O2 (%) | CH4 (%) | LEL (%) | CO2 (%) | O2 (%) | Direct Port Reading After |
| VMP-11 | 5 ft | 09/07/10 | 57.9% | 0.0% | | 44.3% | 0.0% | 0.0 | 0.1 | 2.0 | 0.0 | 0.0 | 0.0 | 0.0 | 0.0 | 9.9 | 10.3 | N/A |
| | | 11/22/10 | 56.5% | 0.0% | | 75.0% | 0.0% | 6.6 | 1.3 | 5.0 | 0.0 | 0.0 | 8.6 | 0.0 | 0.0 | 11.0 | 8.2 | N/A |
| | | 02/11/11 | 52.9% | 0.0% | N/A | 45.9% | 0.0% | 12.8 | 0.8 | 0.0 | 0.0 | 0.0 | 9.4 | 0.0 | 0.0 | 9.5 | 9.9 | N/A |
| | | 04/06/11 | 55.3% | 0.0% | 0.0% | 48.9% | 0.0% | 3.4 | 0.7 | 0.0 | 0.0 | 0.0 | 10.6 | 0.0 | 0.0 | 8.5 | 10.5 | N/A |
| | | 08/07/11 | 68.2% | 0.0% | N/A | 47.5% | 0.0% | 0.0 | 4.3 | 0.0 | 0.0 | 0.0 | 13.6 | 0.0 | 0.0 | 7.5 | 13.1 | N/A |
| | | 11/11/11 | 53.2% | 0.0% | N/A | 67.0% | 0.0% | 0.0 | 1.1 | 0.0 | 0.0 | 0.0 | 7.5 | 0.0 | 0.0 | 11.1 | 8.0 | N/A |
| | | 01/26/12 | 75.8% | 0.0% | N/A | 75.8% | 0.0% | 0.0 | 0.7 | 0.0 | 0.0 | 0.0 | 7.2 | 0.0 | 0.0 | 10.7 | 7.2 | N/A |
| | | 04/19/12 | 82.4% | 0.0% | 0.0% | 62.7% | 0.0% | 0.0 | 2.6 | NM | NM | NM | NM | 0.0 | 0.0 | 5.9 | 16.3 | N/A |
| | | 07/19/12 | 54.0% | 0.0% | 0.0% | 50.0% | 0.0% | 3.6 | 1.3 | NM | NM | NM | NM | 0.0 | 0.0 | 2.4 | 18.0 | N/A |
| | | 10/16/12 | 52.7% | 0.0% | N/A | 45.6% | 0.0% | 2.0 | 0.4 | N/A | N/A | N/A | N/A | 0.0 | 0.0 | 5 | 14.6 | N/A |
| | | 01/29/13 | 65.3% | 0.0% | N/A | 60.8% | 0.1% | 19.58 | 3.0 | NM | NM | NM | NM | 0.0 | 0.0 | 0.5 | 19.9 | N/A |
| | 8 ft | 09/08/10 | 52.3% | 0.0% | | 37.6% | 0.0% | 10.5 | 0.0 | 0.0 | 0.0 | 0.0 | 0.0 | 0.0 | 0.0 | 9.5 | 11.0 | N/A |
| | | 11/22/10 | 55.0% | 0.0% | | 57.5% | 0.0% | 8.0 | 1.8 | 4.0 | 0.0 | 0.0 | 7.8 | 0.0 | 0.0 | 11.4 | 7.6 | N/A |
| | | 02/11/11 | 54.3% | 0.0% | N/A | 43.7% | 0.0% | 27.7 | 0.9 | 0.0 | 0.0 | 0.0 | 8.6 | 0.0 | 0.0 | 10.1 | 9.0 | N/A |
| | | 04/06/11 | 73.8% | 0.0% | 0.0% | 70.0% | 0.0% | 3.0 | 0.8 | 0.0 | 0.0 | 0.0 | 10.5 | 0.0 | 0.0 | 8.3 | 10.1 | N/A |
| | | 08/07/11 | 53.0% | 0.0% | N/A | 35.1% | 0.0% | 0.0 | 2.3 | 4.0 | 0.0 | 0.0 | 8.0 | 0.1 | 1.0 | 9.9 | 7.9 | N/A |
| | | 11/14/11 | 54.2% | 0.0% | N/A | 62.1% | 0.0% | | 0.4 | 0.0 | 0.0 | 0.0 | 3.7 | 0.0 | 0.0 | 10.5 | 8.2 | N/A |
| | | 01/26/12 | 76.2% | 0.0% | N/A | 76.2% | 0.0% | 0.0 | 0.7 | 0.0 | 0.0 | 0.0 | 7.7 | 0.0 | 0.0 | 10.6 | 7.6 | N/A |
| | | 04/19/12 | 50.5% | 0.0% | 0.0% | 65.7% | 0.1% | 0.0 | 2.1 | NM | NM | NM | NM | 0.0 | 0.0 | 4.0 | 16.6 | N/A |
| | | 07/20/12 | 50.4% | 0.0% | N/A | 40.0% | 0.0% | 32.9 | 1.4 | N/A | N/A | N/A | N/A | 0.0 | 0.1 | 4.0 | 16.7 | N/A |
| | | 10/16/12 | 55.6% | 0.0% | N/A | 43.1% | 0.0% | 1.0 | 0.4 | N/A | N/A | N/A | N/A | 0.0 | 0.0 | 4.5 | 15.6 | N/A |
| | | 01/29/13 | 71.2% | 0.0% | N/A | 57.1% | 0.0% | 3.66 | 1.5 | NM | NM | NM | NM | 0.0 | 0.0 | 1.1 | 19.0 | N/A |
| | 29 ft | 09/08/10 | 63.8% | 0.0% | | 40.0% | 0.0% | 1400 | 97.3 | 1.0 | 0.0 | 5.0 | 0.0 | 0.0 | 1.0 | 14.7 | 0.0 | N/A |
| | | 11/22/10 | 57.5% | 0.0% | | 46.3% | 0.0% | 785 | 58.7 | 3.0 | 0.0 | 3.0 | 0.8 | 0.2 | 5.0 | 14.7 | 0.8 | N/A |
| | | 02/14/11 | 55.5% | 0.0% | N/A | 36.9% | 0.0% | 7.2 | 0.0 | 0.0 | 0.0 | 0.0 | 1.6 | 0.0 | 0.0 | 15.3 | 1.7 | N/A |
| | | 04/06/11 | 63.8% | 0.0% | 0.0% | 66.0% | 0.0% | 3.9 | 1.1 | 0.0 | 0.0 | 0.0 | 0.2 | 0.1 | 2.0 | 14.6 | 0.8 | N/A |
| | | 08/25/11 | 53.7% | 0.0% | 0.0% | 47.5% | 0.0% | 0.0 | 0.3 | 2.0 | 0.0 | 0.0 | 0.9 | 0.0 | 0.0 | 14.0 | 0.5 | N/A |
| | | 11/14/11 | 54.3% | 0.0% | N/A | 62.8% | 0.0% | | 0.6 | 0.0 | 0.0 | 0.0 | 0.0 | 0.0 | 0.0 | 14.9 | 1.5 | N/A |
| | | 01/26/12 | 52.8% | 0.0% | N/A | 52.1% | 0.0% | 0.0 | 0.5 | 0.0 | 0.0 | 0.0 | 1.3 | 0.0 | 0.0 | 15.3 | 1.2 | N/A |
| | | 04/19/12 [12] | 60.7% | 0.0% | 0.0% | 60.7% | 0.1% | 0.0 | 2.1 | NM | NM | NM | NM | 0.0 | 0.0 | 12.9 | 2.8 | N/A |
| | | 04/27/12 | 54.8% | 0.0% | N/A | 51.1% | 0.0% | 0.0 | 0.7 | NM | NM | NM | NM | 0.0 | 0.0 | 11.9 | 7.1 | N/A |
| | | 07/23/12 | 50.5% | 0.0% | N/A | 66.5% | 0.0% | 2.4 | 1.1 | NM | NM | NM | NM | 0.0 | 0.0 | 9.8 | 8.3 | N/A |
| | | 10/16/12 | 50.1% | 0.0% | N/A | 41.3% | 0.0% | 1.0 | 0.7 | NM | NM | NM | NM | 0.0 | 0.0 | 7.5 | 12.4 | N/A |
| | | 01/29/13 | 70.5% | 0.0% | N/A | 46.1% | 0.0% | 0.52 | 0.4 | NM | NM | NM | NM | 0.0 | 0.0 | 3.5 | 18.4 | N/A |
| | 38 ft | 09/08/10 | NS | NS | | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS |
| | | 11/22/10 | NS | NS | | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS |
| | | 02/14/11 | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS |
| | | 04/06/11 | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS |
| | | 08/07/11 | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS |
| | | 11/14/11 | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS |
| | | 01/26/12 | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS |
| | | 04/23/12 | 66.5% | 0.0% | N/A | 56.8% | 0.0% | 732 | 289 | NM | NM | NM | NM | 0.0 | 0.0 | 15.9 | 1.0 | N/A |
| | | 07/23/12 | 51.0% | 0.0% | N/A | 58.5% | 0.0% | 400 | 112 | NM | NM | NM | NM | 0.0 | 0.0 | 15.9 | 0.3 | N/A |
| | | 10/16/12 | 67.0% | 0.0% | N/A | 40.3% | 0.0% | 38.0 | 1.0 | NM | NM | NM | NM | 0.0 | 0.0 | 12.9 | 7.0 | N/A |
| | | 01/30/13 | 50.7% | 0.0% | N/A | 51.9% | 0.0% | 7.55 | 0.7 | NM | NM | NM | NM | 0.0 | 0.0 | 8.3 | 13.6 | N/A |

SEE LAST PAGE OF TABLE FOR NOTES

**TABLE 3**
**SOIL VAPOR SAMPLING - TEDLAR SAMPLING DATA**

| Reading Location | | | Shroud | Tedlar Bag 1 | | Shroud | Tedlar Bag 2 | | | | | | | | | | | Tedlar Bag 3 |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| Instrument | | | Dielectric | | Landtec | Dielectric | | FID | PID | Multi-gas | | | | Landtec | | | | Dielectric |
| Location | Depth | Date | Helium in Shroud Before | Helium Before | CH4 (%) | Helium in Shroud After | Helium After | FID (ppm) | PID (ppm) | CO (ppm) | H2S (ppm) | LEL (%) | O2 (%) | CH4 (%) | LEL (%) | CO2 (%) | O2 (%) | Direct Port Reading After |
| VMP-12 | 5 ft | 09/03/10 | 48.7% | 10.4% | | 45.7% | 11.1% | OVR | 22.5 | 145 | 23.0 | OVR | 0.0 | OVR | OVR | 14.5 | 0.7 | 10.1% |
| | | 12/03/10 | 55.3% | 1.1% | | 57.0% | 1.1% | 4986 | 21.7 | 220 | 0.0 | 73.0 | 0.7 | 9.9 | OVR | 13.5 | 1.1 | N/A |
| | | 02/15/11 | 62.7% | 3.3% | 80.1% | 62.6% | 2.5% | 2630000 | 86.7 | 0.0 | 0.0 | OVR | 0.2 | 86.7 | OVR | 8.1 | 0.0 | N/A |
| | | 04/19/11 | 52.0% | 7.7% | OVR | 59.0% | 7.9% | 69.5 | 71.8 | 9.0 | 11.0 | OVR | 0.0 | OVR | OVR | 7.7 | 0.4 | N/A |
| | | 08/04/11 | 57.4% | 8.2% | OVR | 38.1% | 5.1% | OVR | 89.8 | 49.0 | 8.0 | 0.0 | 0.0 | OVR | OVR | 12.3 | 1.0 | N/A |
| | | 11/16/11 | 78.1% | 0.0% | N/A | 61.5% | 0.0% | 20.0 | 8.9 | 0.0 | 0.0 | 0.0 | 14.0 | 0.0 | 0.0 | 8.2 | 16.3 | N/A |
| | | 01/24/12 | 53.6% | 0.6% | N/A | 50.0% | 1.8% | 17.0 | 46.9 | 0.0 | 0.0 | 0.0 | 19.2 | 0.1 | 2.0 | 3.6 | 19.2 | N/A |
| | | 04/19/12 | 54.2% | 0.0% | N/A | 52.8% | 0.1% | 3.0 | 3.2 | NM | NM | NM | NM | 0.0 | 0.0 | 5.1 | 12.8 | N/A |
| | | 07/26/12 | 55.6% | 0.0% | 0.0% | 79.6% | 2.1% | 5.7 | 0.4 | NM | NM | NM | NM | 0.0 | 0.0 | 0.1 | 20.1 | N/A |
| | | 10/24/12 | 56.1% | 0.0% | N/A | 39.0% | 0.1% | 2.0 | 0.7 | NM | NM | NM | NM | 0.0 | 0.0 | 0.1 | 20.4 | N/A |
| | | 02/18/13[9] | 54.9% | 0.3% | 0.0% | 42.2% | 0.5% | 2.61 | 0.2 | NM | NM | NM | NM | 0.0 | 0.0 | 0.1 | 20.8 | N/A |
| | 11.5 ft | 09/03/10 | 54.1% | 9.6% | | 33.4% | 10.1% | OVR | 44.1 | 293 | 15.0 | Off | 0.0 | OVR | OVR | 15.2 | 0.6 | 11.4% |
| | | 12/03/10 | 67.1% | 5.8% | | 58.6% | 6.5% | 50100 | 48.7 | 78.0 | 7.0 | OVR | 0.6 | OVR | OVR | 12.7 | 0.9 | 6.9% |
| | | 02/15/11 | 51.0% | 5.1% | OVR | 56.3% | 5.4% | OVR | 122 | 168 | 21.0 | OVR | 0.3 | OVR | OVR | 9.6 | 0.0 | N/A |
| | | 04/19/11 | 51.0% | 8.7% | OVR | 58.3% | 9.4% | 80.8 | 78.0 | 50.0 | 19.0 | OVR | 0.0 | OVR | OVR | 9.5 | 0.2 | N/A |
| | | 08/04/11 | 51.2% | 5.2% | OVR | 27.7% | 8.0% | OVR | 193.8 | 62.0 | 19.0 | OVR | 0.0 | OVR | OVR | 11.5 | 1.0 | N/A |
| | | 11/16/11 | 71.5% | 0.0% | N/A | 56.5% | 0.2% | 27100 | 36.2 | 0.0 | 0.0 | 51.0 | 1.1 | 3.0 | 61.0 | 11.0 | 6.4 | N/A |
| | | 01/24/12 | 53.1% | 0.0% | N/A | 46.5% | 1.0% | 79000 | 282.5 | 0.0 | 0.0 | 91.0 | 2.1 | 12.4 | OVR | 10.7 | 1.4 | N/A |
| | | 04/19/12 | 70.1% | 0.0% | N/A | 50.8% | 0.9% | 46500 | 13.8 | NM | NM | NM | NM | 5.4 | OVR | 8.1 | 6.3 | N/A |
| | | 7/26/2012[11] | 58.3% | 1.1% | N/A | 50.2% | 2.0% | NM | NM | NM | NM | NM | NM | 0.0 | 0.0 | 0.3 | 20.3 | N/A |
| | | 08/20/12 | 54.6% | 0.0% | N/A | 41.9% | 0.2% | 4.8 | 1.1 | NM | NM | NM | NM | 0.0 | 0.0 | 0.1 | 20.8 | N/A |
| | | 10/26/12[9] | 54.5% | 0.0% | N/A | 48.1% | 0.1% | 2.0 | 0.3 | NM | NM | NM | NM | 0.0 | 0.0 | 0.2 | 20.2 | N/A |
| | | 02/18/13[9] | 54.7% | 0.0% | 0.0% | 58.5% | 0.8% | 4.97 | 0.3 | NM | NM | NM | NM | 0.0 | 0.0 | 0.3 | 20.0 | N/A |
| | 25 ft | 09/03/10 | 52.6% | 11.6% | | 34.9% | 10.6% | OVR | 441 | 379 | 7.0 | OVR | 0.0 | OVR | OVR | 15.3 | 0.5 | 10.8% |
| | | 12/03/10 | 54.4% | 8.8% | | 53.1% | 9.1% | 61100 | 64.7 | 134 | 2.0 | OVR | 0.6 | OVR | OVR | 13.9 | 0.6 | 9.5% |
| | | 02/15/11 | 54.6% | 3.9% | OVR | 72.1% | 4.8% | OVR | 242 | 248 | 9.0 | OVR | 0.0 | OVR | OVR | 13.6 | 0.0 | N/A |
| | | 04/19/11 | 53.0% | 8.8% | OVR | 75.0% | 9.3% | 76.0 | 133 | 90.0 | 9.0 | OVR | 0.0 | OVR | OVR | 12.3 | 0.8 | N/A |
| | | 08/04/11 | 92.6% | 11.6% | OVR | 31.3% | 8.1% | OVR | 244.6 | 4.0 | 11.0 | OVR | 0.0 | OVR | OVR | 11.8 | 0.9 | N/A |
| | | 11/16/11 | 82.5% | 11.2% | OVR | 57.8% | 0.4% | OVR | 140 | 104 | 0.0 | OVR | 0.0 | OVR | OVR | 12.7 | 0.6 | N/A |
| | | 01/24/12 | 57.0% | 8.1% | OVR | 47.9% | 7.6% | 848000 | 1525 | 0.0 | 0.0 | OVR | 3.7 | OVR | OVR | 12.7 | 0.3 | N/A |
| | | 04/19/12 | 54.9% | 5.1% | N/A | 53.7% | 9.0% | 900000 | 48.5 | NM | NM | NM | NM | OVR | OVR | 10.2 | 0.8 | N/A |
| | | 07/26/12 | 50.5% | 0.6% | 28.4% | 53.2% | 0.5% | 46700 | 100 | NM | NM | NM | NM | 19.7 | OVR | 9.8 | 5.4 | N/A |
| | | 10/25/12[12] | 56.6% | 0.0% | N/A | 60.5% | 0.0% | 8350 | 130 | NM | NM | NM | NM | 3.5 | 70 | 13.3 | 1.3 | N/A |
| | | 02/15/13 | 62.2% | 2.3% | 33.0% | 42.0% | 2.3% | 164000 | 28.99 | NM | NM | NM | NM | 40 | OVR | 12.2 | 2.8 | N/A |
| | 39 ft | 09/03/10 | NS | NS | | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS |
| | | 12/03/10 | NS | NS | | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS |
| | | 02/15/11 | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS |
| | | 04/19/11 | 51.0% | 12.0% | OVR | 53.0% | 11.2% | 96.7 | 131 | 85.0 | 17.0 | OVR | 0.0 | OVR | OVR | 13.0 | 0.7 | N/A |
| | | 08/04/11 | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS |
| | | 11/16/11 | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS |
| | | 01/24/12 | 50.5% | 15.5% | OVR | 36.1% | 9.4% | OVR | 1416 | 0.0 | 6.0 | OVR | 1.2 | OVR | OVR | 13.2 | 0.0 | N/A |
| | | 04/19/12 | 65.5% | 5.2% | N/A | 60.9% | 9.2% | OVR | 62.0 | NM | NM | NM | NM | OVR | OVR | 11.5 | 0.7 | N/A |
| | | 07/26/12 | 60.7% | 4.2% | OVR | 59.2% | 5.3% | 375000 | 1850 | NM | NM | NM | NM | OVR | OVR | 11.9 | 1.2 | N/A |
| | | 10/24/12 | 52.7% | 2.7% | OVR | 42.4% | 2.9% | 179000 | 71.44 | NM | NM | NM | NM | 83.6 | OVR | 12.4 | 2.3 | N/A |
| | | 02/15/13 | 54.0% | 4.5% | OVR | 40.0% | 4.4% | 488000 | 91.23 | NM | NM | NM | NM | OVR | OVR | 14.1 | 2.1 | N/A |

SEE LAST PAGE OF TABLE FOR NOTES

**TABLE 3**
**SOIL VAPOR SAMPLING - TEDLAR SAMPLING DATA**

| Reading Location | | | Shroud | Tedlar Bag 1 | | Shroud | Tedlar Bag 2 | | | | | | | | | | Tedlar Bag 3 |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| Instrument | | | Dielectric | | Landtec | Dielectric | | FID | PID | Multi-gas | | | | Landtec | | | | Dielectric |
| Location | Depth | Date | Helium in Shroud Before | Helium Before | CH4 (%) | Helium in Shroud After | Helium After | FID (ppm) | PID (ppm) | CO (ppm) | H2S (ppm) | LEL (%) | O2 (%) | CH4 (%) | LEL (%) | CO2 (%) | O2 (%) | Direct Port Reading After |
| VMP-13 | 5 ft | 09/13/10 | 56.7% | 0.0% | | 46.7% | 0.0% | 35.3 | 0.0 | 0.0 | 0.0 | 0.0 | 0.0 | 0.0 | 0.0 | 6.8 | 9.0 | N/A |
| | | 12/01/10 | 43.4% | 0.1% | | 51.5% | 0.0% | 0.6 | 1.8 | 5.0 | 0.0 | 0.0 | 11.6 | 0.1 | 2.0 | 6.4 | 12.6 | N/A |
| | | 02/18/11 | 50.9% | 0.0% | N/A | 50.9% | 0.0% | 0.0 | 1.0 | 0.0 | 0.0 | 0.0 | 14.8 | 0.0 | 0.0 | 3.3 | 15.8 | N/A |
| | | 04/05/11 | 70.2% | 0.0% | N/A | 82.6% | 0.0% | 50.9 | 5.9 | 0.0 | 0.0 | 0.0 | 15.3 | 0.0 | 0.0 | 3.7 | 17.4 | N/A |
| | | 08/09/11 | 57.9% | 0.0% | N/A | 44.0% | 0.0% | | 7.0 | 2.0 | 0.0 | 0.0 | 4.0 | 0.0 | 1.0 | 11.2 | 4.7 | N/A |
| | | 11/14/11 | 54.5% | 0.0% | N/A | 60.3% | 0.0% | | 0.6 | 0.0 | 0.0 | 0.0 | 8.0 | 0.0 | 0.0 | 6.3 | 11.6 | N/A |
| | | 01/27/12 | 53.8% | 0.0% | N/A | 57.7% | 0.0% | 0.0 | 0.8 | 0.0 | 0.0 | 0.0 | 12.3 | 0.0 | 0.0 | 5.6 | 13.0 | N/A |
| | | 04/20/12 | 79.8% | 0.0% | 0.0% | 51.2% | 0.0% | 0.0 | 0.2 | NM | NM | NM | NM | 0.0 | 0.0 | 3.7 | 17.4 | N/A |
| | | 07/19/12 | 54.2% | 0.0% | N/A | 51.4% | 0.0% | 2.7 | 1.1 | NM | NM | NM | NM | 0.0 | 0.0 | 4.2 | 16.3 | N/A |
| | | 10/09/12 | 60.7% | 0.0% | N/A | 45.5% | 0.0% | 2.0 | 1.0 | NM | NM | NM | NM | 0.0 | 0.0 | 2.9 | 19.2 | N/A |
| | | 01/29/13 | 53.1% | 0.0% | N/A | 55.0% | 0.1% | 1.09 | 0.4 | NM | NM | NM | NM | 0.0 | 0.0 | 0.2 | 20.7 | N/A |
| | 10.5 ft | 09/13/10 | 53.2% | 0.0% | | 30.3% | 0.0% | 1460 | 1.0 | 2.0 | 2.0 | 5.0 | 0.0 | 0.2 | 1.0 | 8.6 | 0.7 | N/A |
| | | 12/01/10 | 41.2% | 0.0% | | 42.7% | 0.0% | 0.6 | 2.2 | 2.0 | 0.0 | 0.0 | 5.1 | 0.0 | 1.0 | 10.4 | 5.0 | N/A |
| | | 02/18/11 | 50.4% | 0.0% | N/A | 47.9% | 0.0% | 2550 | 192 | 0.0 | 0.0 | 16.0 | 1.7 | 0.1 | 16.0 | 6.8 | 10.6 | N/A |
| | | 04/05/11 | 50.2% | 0.0% | N/A | 72.8% | 0.0% | 30.5 | 4.4 | 1.0 | 0.0 | 0.0 | 10.6 | 0.0 | 0.0 | 3.3 | 12.1 | N/A |
| | | 08/09/11 | 58.5% | 0.0% | N/A | 49.9% | 0.0% | | 46.0 | 31.0 | 0.0 | 11.0 | 0.5 | 0.7 | 15.0 | 12.4 | 1.3 | N/A |
| | | 11/14/11 | 56.4% | 0.0% | N/A | 60.5% | 0.0% | | 0.5 | 0.0 | 0.0 | 0.0 | 4.9 | 0.0 | 0.0 | 7.6 | 9.3 | N/A |
| | | 01/27/12 | 63.5% | 0.0% | N/A | 60.1% | 0.0% | 0.0 | 0.5 | 0.0 | 0.0 | 0.0 | 9.8 | 0.0 | 0.0 | 7.1 | 10.1 | N/A |
| | | 04/20/12 | 71.2% | 0.0% | 0.0% | 72.3% | 0.0% | 0.0 | 0.4 | NM | NM | NM | NM | 0.0 | 0.0 | 4.7 | 14.7 | N/A |
| | | 07/19/12 | 53.4% | 0.0% | N/A | 46.1% | 0.0% | 3.1 | 1.5 | NM | NM | NM | NM | 0.0 | 0.0 | 6.0 | 12.7 | N/A |
| | | 10/09/12 | 58.9% | 0.0% | N/A | 40.8% | 0.0% | 1.0 | 1.7 | NM | NM | NM | NM | 0.0 | 0.0 | 4.2 | 17.2 | N/A |
| | | 01/30/13 | 62.6% | 0.0% | N/A | 52.6% | 0.0% | 0.85 | 0.3 | NM | NM | NM | NM | 0.0 | 0.0 | 0.8 | 20.7 | N/A |
| | 21.5 ft | 09/13/10 | 56.7% | 0.1% | | 27.9% | 0.0% | 35600 | 1869 | 7.0 | 0.0 | 30.0 | 0.0 | 2.4 | 49.0 | 12.2 | 0.0 | N/A |
| | | 12/01/10 | 43.5% | 0.2% | | 46.7% | 0.3% | 1928 | 255 | 2.0 | 0.0 | 26.0 | 0.6 | 2.1 | 43.0 | 13.4 | 0.6 | N/A |
| | | 02/18/11 | 55.4% | 0.0% | N/A | 53.1% | 0.0% | 3050 | 372 | 0.0 | 0.0 | 21.0 | 1.4 | 1.8 | 37.0 | 12.7 | 0.6 | N/A |
| | | 04/05/11 | 50.2% | 0.0% | N/A | 50.2% | 0.0% | 18220 | OVR | 0.0 | 0.0 | 17.0 | 4.4 | 0.0 | 34.0 | 0.1 | 10.4 | N/A |
| | | 08/09/11 | 54.2% | 0.0% | N/A | 48.0% | 0.0% | | 202.3 | 11.0 | 0.0 | 40.0 | 0.3 | 2.4 | 48.0 | 11.7 | 0.9 | N/A |
| | | 11/14/11 | 56.8% | 0.0% | N/A | 64.7% | 0.0% | | 293.5 | 0.0 | 0.0 | 20.0 | 0.0 | 1.2 | 24.0 | 11.8 | 0.8 | N/A |
| | | 01/27/12 | 52.0% | 0.0% | N/A | 48.2% | 0.0% | 6600 | 217.6 | 0.0 | 0.0 | 14.0 | 0.5 | 0.6 | 12.0 | 12.5 | 0.3 | N/A |
| | | 04/20/12 | 67.0% | 0.0% | 0.0% | 68.0% | 0.0% | 1110 | 6.5 | NM | NM | NM | NM | 0.0 | 0.0 | 12.8 | 0.4 | N/A |
| | | 07/19/12 | 47.6% | 0.0% | N/A | 53.2% | 0.0% | 69.0 | 3.0 | NM | NM | NM | NM | 0.0 | 0.0 | 13.8 | 1.3 | N/A |
| | | 10/09/12 | 59.2% | 0.0% | N/A | 43.7% | 0.0% | 47.0 | 6.4 | NM | NM | NM | NM | 0.0 | 0.0 | 14.6 | 1.4 | N/A |
| | | 01/30/13 | 52.6% | 0.0% | N/A | 51.9% | 0.0% | 0.97 | 0.3 | NM | NM | NM | NM | 0.0 | 0.0 | 1.8 | 20.2 | N/A |
| | 29.5 ft | 09/13/10 | NS | NS | | NS | NS | NS | NS | 0.0 | NS | NS | NS | NS | NS | NS | NS | NS |
| | | 12/01/10 | NS | NS | | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS |
| | | 02/18/11 | 52.1% | 0.0% | N/A | 49.2% | 0.0% | 8300 | OVR | 64.0 | 2.0 | 8.0 | 1.0 | 1.5 | 25.0 | 3.5 | 16.3 | N/A |
| | | 04/05/11 | 63.9% | 0.0% | N/A | 47.9% | 0.0% | 50220 | OVR | 1.0 | 0.0 | 22.0 | 3.4 | 0.0 | 55.0 | 0.0 | 19.8 | N/A |
| | | 08/09/11 | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS |
| | | 11/14/11 | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS |
| | | 01/30/12 | 51.7% | 0.0% | N/A | 91.8% | 0.0% | 12700 | 5964 | 4.0 | 3.0 | 0.0 | 0.4 | 1.1 | 23.0 | 12.6 | 0.6 | N/A |
| | | 04/20/12 | 70.8% | 0.0% | 0.3% | 61.8% | 0.0% | 8700 | 1450 | NM | NM | NM | NM | 0.3 | 7.0 | 12.1 | 1.2 | N/A |
| | | 07/19/12 | 56.3% | 0.0% | N/A | 50.9% | 0.0% | 13100 | 1850 | NM | NM | NM | NM | 0.3 | 7.0 | 13.5 | 1.3 | N/A |
| | | 10/09/12 | 72.8% | 0.0% | N/A | 41.7% | 0.0% | 4400 | 780 | NM | NM | NM | NM | 0.5 | 9 | 15.0 | 1.3 | N/A |
| | | 01/30/13 | 53.2% | 0.0% | N/A | 52.6% | 0.0% | 540 | 245 | NM | NM | NM | NM | 0.0 | 0.0 | 5.1 | 15.9 | N/A |

SEE LAST PAGE OF TABLE FOR NOTES

**TABLE 3**
**SOIL VAPOR SAMPLING - TEDLAR SAMPLING DATA**

| Reading Location | | | Shroud | Tedlar Bag 1 | | Shroud | Tedlar Bag 2 | | | | | | | | | | | Tedlar Bag 3 |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| Instrument | | | Dielectric | | Landtec | Dielectric | | FID | PID | Multi-gas | | | | Landtec | | | | Dielectric |
| Location | Depth | Date | Helium in Shroud Before | Helium Before | CH4 (%) | Helium in Shroud After | Helium After | FID (ppm) | PID (ppm) | CO (ppm) | H2S (ppm) | LEL (%) | O2 (%) | CH4 (%) | LEL (%) | CO2 (%) | O2 (%) | Direct Port Reading After |
| VMP-14 | 5 ft | 09/10/10 | 53.6% | 3.8% | | 51.4% | 4.0% | 2320000 | 1.6 | 0.0 | 0.0 | OVR | 0.0 | 17.9 | OVR | 20.1 | 0.0 | 3.2% |
| | | 12/01/10 | 42.6% | 0.5% | | 33.5% | 0.7% | 3.0 | 1.6 | 2.0 | 0.0 | 0.0 | 12.7 | 0.1 | 2.0 | 2.7 | 13.5 | N/A |
| | | 02/17/11 | 54.1% | 0.0% | 0.0% | 68.1% | 0.0% | 155 | 1.0 | 3.0 | 0.0 | 3.0 | 2.9 | 0.2 | 3.0 | 2.4 | 2.6 | N/A |
| | | 04/05/11 | 59.6% | 0.0% | N/A | 54.9% | 0.2% | 0.0 | 0.5 | 0.0 | 0.0 | 0.0 | 19.2 | 0.0 | 0.0 | 2.7 | 19.0 | N/A |
| | | 08/08/11 | 59.0% | 1.0% | N/A | 61.5% | 1.0% | 49000 | 38 | 17 | 0.0 | 5.0 | 0.3 | 6.8 | OVR | 18.2 | 0.1 | N/A |
| | | 11/14/11 | 61.1% | 0.0% | N/A | 62.7% | 0.0% | | 0.9 | 0.0 | 0.0 | 0.0 | 12.7 | 0.0 | 0.0 | 8.2 | 15.1 | N/A |
| | | 01/26/12 | 50.6% | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS |
| | | 04/20/12 | 52.0% | 0.0% | N/A | 66.6% | 0.0% | 0.0 | 0.2 | NM | NM | NM | NM | 0.0 | 0.0 | 3.3 | 19.8 | N/A |
| | | 07/23/12 | 52.0% | 0.0% | N/A | 70.2% | 0.0% | 2.1 | 2.0 | N/A | N/A | N/A | N/A | 0.0 | 0.0 | 9.0 | 9.1 | N/A |
| | | 10/10/12 | 56.0% | 0.0% | N/A | 40.5% | 0.8% | 0.0 | 0.9 | NM | NM | NM | NM | 0.0 | 0.0 | 1.3 | 21.7 | N/A |
| | | 01/31/13 | 50.8% | 0.0% | N/A | 46.0% | 0.6% | 1.76 | 0.3 | NM | NM | NM | NM | 0.0 | 0.0 | 0.1 | 21.3 | N/A |
| | 11.5 ft | 09/10/10 | 52.3% | 7.0% | | 47.2% | 7.3% | 7410000 | 10.4 | 42.0 | 75.0 | OVR | 0.0 | OVR | OVR | 16.5 | 0.0 | 6.8% |
| | | 12/02/10 | 53.5% | 0.0% | | 50.7% | 2.0% | 7494 | 1.1 | 251 | 10.0 | 5.0 | 0.6 | 18.3 | OVR | 4.6 | 0.5 | N/A |
| | | 02/17/11 | 55.0% | 0.0% | 0.0% | 80.0% | 0.0% | 86.2 | 95.8 | 4.0 | 0.0 | 4.0 | 3.6 | 0.5 | 10.0 | 3.8 | 3.7 | N/A |
| | | 04/05/11 | 90.0% | 0.0% | N/A | 49.8% | 0.0% | 766 | 118.5 | 0.0 | 0.0 | 0.0 | 8.6 | 0.3 | 6.0 | 12.0 | 8.6 | N/A |
| | | 08/08/11 | 57.0% | 6.6% | OVR | 59.0% | 6.7% | 253000 | 104 | 163 | 36.0 | 100 | 0.3 | OVR | OVR | 16.3 | 0.3 | N/A |
| | | 11/15/11 | 75.8% | 1.0% | OVR | 60.1% | 0.6% | 42000 | 103.2 | 15.0 | 0.0 | 66.0 | 0.0 | 9.2 | OVR | 14.2 | 2.2 | N/A |
| | | 01/26/12 | 68.4% | 1.0% | N/A | 55.1% | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS |
| | | 04/23/12 | 55.0% | 0.0% | N/A | 59.3% | 0.0% | 0.0 | 0.6 | NM | NM | NM | NM | 0.0 | 0.0 | 4.9 | 9.6 | N/A |
| | | 07/25/12 | 59.3% | 0.0% | N/A | 65.9% | 0.0% | 22900 | 18.3 | N/A | N/A | N/A | N/A | 4.8 | 96.0 | 16.2 | 0.6 | N/A |
| | | 10/10/12 | 67.8% | 0.0% | N/A | 53.5% | 0.0% | 1.0 | 0.7 | NM | NM | NM | NM | 0.0 | 0.0 | 8.2 | 19.1 | N/A |
| | | 01/31/13 | 49.4% | 0.0% | N/A | 42.5% | 0.1% | 0.91 | 0.2 | NM | NM | NM | NM | 0.0 | 0.0 | 0.5 | 21.0 | N/A |
| | 20 ft | 09/10/10 | 63.8% | 7.8% | | 50.5% | 7.7% | OVR | 56.8 | 186 | 0.0 | OVR | 0.0 | OVR | OVR | 17.2 | 0.0 | 6.6% |
| | | 12/02/10 | 54.5% | 6.2% | | 45.6% | 6.6% | 25400 | 264 | 148 | 0.0 | OVR | 0.5 | OVR | OVR | 19.2 | 0.5 | 6.1% |
| | | 02/18/11 | 53.0% | 2.8% | OVR | 53.1% | 2.6% | 58370 | 1282 | 305 | 4.0 | OVR | 1.6 | OVR | OVR | 16.8 | 0.4 | N/A |
| | | 04/05/11 | 60.1% | 1.2% | OVR | 53.6% | 2.2% | 233000 | 856.7 | 71.0 | 2.0 | OVR | 0.3 | OVR | OVR | 16.5 | 0.3 | N/A |
| | | 08/08/11 | 58.2% | 8.2% | N/A | 53.2% | 6.6% | 810000 | 351 | 402 | 3.0 | 100 | 0.3 | OVR | OVR | 15.4 | 0.2 | N/A |
| | | 11/15/11 | 85.2% | 4.5% | OVR | 61.1% | 3.8% | 425000 | 297 | 240 | 0.0 | OVR | 0.0 | OVR | OVR | 17.1 | 1.3 | N/A |
| | | 01/26/12 | 50.5% | 3.2% | N/A | 87.7% | 3.2% | 220000 | 1004 | 303 | 4.0 | OVR | 0.3 | OVR | OVR | 17.9 | 0.4 | N/A |
| | | 04/20/12 | 56.6% | 1.1% | 84.2% | 63.3% | 1.3% | 136000 | 1049 | NM | NM | NM | NM | 84.8 | OVR | 15.0 | 0.7 | N/A |
| | | 07/25/12 | 63.7% | 0.7% | 83.8% | 50.3% | 1.0% | 120000 | 365 | N/A | N/A | N/A | N/A | 83.5 | OVR | 15.8 | 0.8 | N/A |
| | | 10/16/12 | 60.4% | 1.2% | NM | 35.4% | 0.8% | 110000 | 775 | NM | NM | NM | NM | 75.4 | OVR | 18.0 | 1.0 | N/A |
| | | 01/31/13 | 50.4% | 0.0% | N/A | 40.6% | 0.0% | 72200 | 1280 | NM | NM | NM | NM | 35.3 | OVR | 13.4 | 3.4 | N/A |
| | 29 ft | 09/10/10 | NS | NS | | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS |
| | | 12/01/10 | NS | NS | | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS |
| | | 02/18/11 | 54.0% | 6.8% | 86.0% | 66.4% | 2.5% | 85560 | 1502 | 624 | 8.0 | OVR | 0.4 | OVR | OVR | 16.5 | 0.3 | N/A |
| | | 04/05/11 | 58.1% | 2.1% | OVR | 48.8% | 2.4% | 276000 | 1420 | 100 | 5.0 | OVR | 0.2 | OVR | OVR | 15.7 | 0.3 | N/A |
| | | 08/08/11 | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS |
| | | 11/15/11 | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS |
| | | 01/26/12 | 55.2% | 3.1% | N/A | 42.3% | 2.5% | 233000 | 935 | 391 | 3.0 | OVR | 0.3 | OVR | OVR | 17.4 | 0.5 | N/A |
| | | 04/20/12 | 56.4% | 1.0% | >>> | 55.7% | 1.1% | 170000 | 1482.0 | NM | NM | NM | NM | OVR | OVR | 14.8 | 0.8 | N/A |
| | | 07/25/12 | 58.0% | 0.9% | 83.5% | 50.1% | 0.8% | 141000 | 500 | N/A | N/A | N/A | N/A | 83.8 | OVR | 15.2 | 0.9 | N/A |
| | | 10/16/12 | 53.3% | 1.0% | NM | 47.7% | 1.1% | 103000 | 935 | NM | NM | NM | NM | 82.0 | OVR | 16.8 | 1.1 | N/A |
| | | 01/31/13 | 53.0% | 0.0% | N/A | 43.8% | 0.0% | 126000 | 1400 | NM | NM | NM | NM | 95.8 | OVR | 16.6 | 0.4 | N/A |

SEE LAST PAGE OF TABLE FOR NOTES

**TABLE 3**
**SOIL VAPOR SAMPLING - TEDLAR SAMPLING DATA**

| Reading Location | | | Shroud | Tedlar Bag 1 | | Shroud | Tedlar Bag 2 | | | | | | | | | | | Tedlar Bag 3 |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| Instrument | | | Dielectric | | Landtec | Dielectric | | FID | PID | Multi-gas | | | | Landtec | | | | Dielectric |
| Location | Depth | Date | Helium in Shroud Before | Helium Before | CH4 (%) | Helium in Shroud After | Helium After | FID (ppm) | PID (ppm) | CO (ppm) | H2S (ppm) | LEL (%) | O2 (%) | CH4 (%) | LEL (%) | CO2 (%) | O2 (%) | Direct Port Reading After |
| VMP-15 | 5 ft | 09/14/10 | 64.4% | 0.0% | | 49.9% | 0.0% | 0.0 | 0.0 | 0.0 | 0.0 | 5.0 | 0.0 | 0.0 | 0.0 | 17.0 | 0.3 | N/A |
| | | 11/30/10 | 47.9% | 0.3% | | 41.5% | 0.5% | 1058 | 29.6 | 1.0 | 0.0 | 22.0 | 1.5 | 1.9 | 38.0 | 15.2 | 1.4 | N/A |
| | | 02/16/11 | 55.1% | 0.0% | 0.3% | 63.7% | 0.0% | 214 | 50.2 | 2.0 | 0.0 | 4.0 | 3.6 | 0.5 | 9.0 | 11.0 | 3.9 | N/A |
| | | 04/20/11 | 55.0% | 0.0% | N/A | 61.0% | 0.0% | 662 | 35.8 | 0.0 | 0.0 | 5.0 | 1.9 | 0.2 | 5.0 | 15.4 | 2.9 | N/A |
| | | 08/08/11 | 64.0% | 0.0% | N/A | 63.9% | 0.0% | 0.0 | 2.4 | 3.0 | 0.0 | 0.0 | 1.4 | 0.0 | 0.0 | 18.1 | 1.2 | N/A |
| | | 11/15/11 | 82.0% | 0.0% | N/A | 55.4% | 0.0% | 0.0 | 1.6 | 0.0 | 0.0 | 0.0 | 2.6 | 0.0 | 0.0 | 11.4 | 7.3 | N/A |
| | | 02/01/12 | 55.0% | 0.0% | N/A | 70.9% | 0.0% | 0.0 | 1.4 | 0.0 | 0.0 | 0.0 | 9.9 | 0.0 | 0.0 | 9.7 | 10.2 | N/A |
| | | 04/24/12 | 53.7% | 0.0% | N/A | 73.7% | 0.0% | 301 | 6.3 | NM | NM | NM | NM | 0.0 | 0.0 | 11.4 | 4.2 | N/A |
| | | 07/25/12 | 50.7% | 0.0% | N/A | 45.0% | 0.0% | 1.8 | 1.5 | NM | NM | NM | NM | 0.0 | 0.0 | 11.9 | 10.0 | N/A |
| | | 10/25/12 | 55.4% | 0.0% | N/A | 54.0% | 0.0% | 1.0 | 0.6 | NM | NM | NM | NM | 0.0 | 0.0 | 8.3 | 12.5 | N/A |
| | | 02/05/13 | 66.1% | 0.0% | N/A | 40.2% | 0.0% | 0.95 | 0.2 | NM | NM | NM | NM | 0.0 | 0.0 | 6.4 | 11.0 | N/A |
| | 21.5 ft | 09/14/10 | 50.1% | 3.9% | | 28.1% | 3.6% | 1960000 | 9.5 | 5.0 | 92.0 | OVR | 0.0 | 30.8 | OVR | 19.1 | 0.0 | 3.4% |
| | | 11/30/10 | 42.2% | 2.2% | | 47.5% | 2.8% | 10700 | 26.1 | 0.0 | 8.0 | OVR | 0.5 | 17.8 | OVR | 19.2 | 0.5 | N/A |
| | | 02/16/11 | 52.5% | 0.7% | 13.0% | 47.9% | 0.6% | 14310 | 89.0 | 3.0 | 66.0 | 72.0 | 2.1 | 15.3 | OVR | 18.7 | 0.5 | N/A |
| | | 04/20/11 | 52.3% | 1.0% | 19.5% | 50.3% | 1.5% | 1320000 | 96.6 | 0.0 | 2.0 | OVR | 0.0 | 24.8 | OVR | 19.1 | 0.0 | N/A |
| | | 08/08/11 | 52.5% | 5.0% | N/A | 50.8% | 4.8% | 280000 | 43.5 | 24.0 | 94.0 | 100 | 0.2 | 31 | OVR | 17.4 | 0.2 | N/A |
| | | 11/15/11 | 56.2% | 0.4% | 6.5% | 72.7% | 0.6% | 41500 | 106.2 | 3.0 | 0.0 | 15.0 | 0.0 | 6.9 | OVR | 16.5 | 0.7 | N/A |
| | | 02/01/12 | 60.2% | 0.0% | N/A | 63.9% | 0.1% | 31200 | 143.9 | 0.0 | 0.0 | 44.0 | 2.0 | 6.3 | OVR | 18.1 | 0.5 | N/A |
| | | 04/24/12 | 57.2% | 0.0% | N/A | 85.5% | 0.0% | 19500 | 57.5 | NM | NM | NM | NM | 1.8 | 36 | 17.1 | 0.6 | N/A |
| | | 07/25/12 | 50.1% | 0.0% | N/A | 49.2% | 0.0% | 15900 | 50.0 | NM | NM | NM | NM | 2.5 | 53.0 | 15.7 | 1.8 | N/A |
| | | 10/25/12 | 65.8% | 0.0% | N/A | 43.8% | 0.0% | 14700 | 41.25 | NM | NM | NM | NM | 1.9 | 37 | 3.2 | 5.9 | N/A |
| | | 02/07/13 | 55.2% | 0.0% | N/A | 55.0% | 0.5% | 570 | 2.5 | NM | NM | NM | NM | 0.1 | 2 | 14.7 | 4.8 | N/A |
| | 25.5 ft | 09/14/10 | 50.3% | 6.3% | | 30.9% | 8.1% | 11780 | 29.9 | 1.0 | 0.0 | 15.0 | 0.0 | 1.6 | 32.0 | 7.7 | 11.1 | 4.1% |
| | | 12/02/10 | 62.4% | 0.6% | | 62.2% | 9.2% | 20.0 | 1.9 | 1.0 | 0.0 | 0.0 | 14.3 | 0.1 | 2.0 | 4.1 | 14.8 | 10.7% |
| | | 02/16/11 | 52.7% | 4.1% | 3.5% | 55.7% | 4.8% | 1850 | 89.6 | 2.0 | 27.0 | 41.0 | 7.0 | 1.9 | 40.0 | 8.6 | 6.2 | N/A |
| | | 04/20/11 | 52.0% | 8.3% | 2.0% | 50.0% | 5.9% | 10000 | 17.6 | 0.0 | 0.0 | 10.0 | 10.7 | 3.0 | 21.0 | 5.2 | 9.9 | N/A |
| | | 08/08/11 | 57.3% | 4.3% | N/A | 57.5% | 8.6% | 67.2 | 11.9 | 3.0 | 0.0 | 0.0 | 5.0 | 0.0 | 0.0 | 13.9 | 4.8 | N/A |
| | | 11/15/11 | 59.2% | 3.2% | 0.6% | 51.5% | 5.8% | | 80.7 | 0.0 | 0.0 | 13 | 6.5 | 0.6 | 13.0 | 7.1 | 10.6 | N/A |
| | | 02/01/12 | 62.5% | NS | N/A | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS |
| | | 04/24/12 [10] | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS |
| | | 07/31/12 | 55.9% | 0.0% | 0.2% | 50.5% | 0.0% | 2450 | 25.5 | NM | NM | NM | NM | 0.2 | 4.0 | 3.2 | 18.8 | N/A |
| | | 10/25/12 | 62.3% | 0.4% | 0.3 | 42.1% | 1.2% | 2030 | 22.01 | NM | NM | NM | NM | 0.4 | 7 | 5.2 | 13.5 | N/A |
| | | 02/12/13 | 49.6% | 0.0% | N/A | 88.5% | 0.0% | 7000 | 55.0 | NM | NM | NM | NM | 1.5 | 30 | 13.2 | 4.6 | N/A |
| | 29 ft | 09/14/10 | 56.1% | 10.1% | | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS |
| | | 12/02/10 | NS | NS | | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS |
| | | 02/16/11 | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS |
| | | 04/20/11 | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS |
| | | 08/08/11 | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS |
| | | 11/15/11 | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS |
| | | 02/01/12 | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS |
| | | 04/24/12 [13] | 52.1% | 5.1% | 0.3% | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS |
| | | 07/31/12 | 54.6% | 0.0% | 0.2% | 50.1% | 0.1% | 2300 | 29.5 | NM | NM | NM | NM | 0.2 | 5.0 | 3.5 | 18.5 | N/A |
| | | 10/25/12 | 52.1% | 0.1% | 0.4% | 48.5% | 1.6% | 1340 | 23.00 | NM | NM | NM | NM | 0.3 | 6.0 | 4.1 | 14.1 | N/A |
| | | 02/12/13 | 51.2% | 0.5% | N/A | 54.5% | 0.7% | 653 | 9.0 | NM | NM | NM | NM | 0.1 | 2.0 | 4.1 | 15.2 | N/A |

SEE LAST PAGE OF TABLE FOR NOTES

**TABLE 3**
**SOIL VAPOR SAMPLING - TEDLAR SAMPLING DATA**

| Reading Location | | | Shroud | Tedlar Bag 1 | | Shroud | Tedlar Bag 2 | | | | | | | | | | | Tedlar Bag 3 |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| Instrument | | | Dielectric | | Landtec | Dielectric | | FID | PID | Multi-gas | | | | Landtec | | | | Dielectric |
| Location | Depth | Date | Helium in Shroud Before | Helium Before | CH4 (%) | Helium in Shroud After | Helium After | FID (ppm) | PID (ppm) | CO (ppm) | H2S (ppm) | LEL (%) | O2 (%) | CH4 (%) | LEL (%) | CO2 (%) | O2 (%) | Direct Port Reading After |
| VMP-16 | 5 ft | 09/02/10 | 61.2% | 15.1% | | 23.1% | 12.1% | OVR | 6.2 | 167 | 9.0 | OVR | 0.0 | OVR | OVR | 19.4 | 0.6 | 14.0% |
| | | 11/29/10 | 50.0% | 15.0% | | 47.8% | 12.7% | 86300 | 29.4 | 13.0 | 0.0 | OVR | 0.6 | OVR | OVR | 18.1 | 1.5 | 12.6% |
| | | 02/15/11 | 52.6% | 5.4% | OVR | 75.3% | 5.5% | OVR | 119 | 31.0 | 2.0 | OVR | 2.1 | OVR | OVR | 14.3 | 0.0 | N/A |
| | | 04/22/11 | 52.4% | 11.8% | OVR | 54.0% | 12.6% | OVR | 76.7 | 27.0 | 3.0 | OVR | 0.0 | OVR | OVR | 17.3 | 0.4 | N/A |
| | | 08/05/11 | 52.3% | 2.3% | 3.0% | 57.3% | 4.9% | OVR | 220.6 | 6.0 | 0.0 | 26.0 | 0.0 | 20.7 | OVR | 12.7 | 1.9 | N/A |
| | | 11/16/11 | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS |
| | | 02/01/12 | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS |
| | | 04/25/12 | 54.1% | 0.2% | OVR | 51.0% | 4.3% | 375000 | 81.5 | NM | NM | NM | NM | OVR | OVR | 14.0 | 2.0 | N/A |
| | | 07/30/12 | 57.6% | 0.0% | N/A | 53.2% | 0.0% | 46000 | 141 | NM | NM | NM | NM | OVR | OVR | 20.3 | 0.1 | N/A |
| | | 10/25/12 | 52.8% | 0.0% | 20.4 | 50.4% | 0.0% | 20100 | 279 | NM | NM | NM | NM | 22.2 | OVR | 15.0 | 1.5 | N/A |
| | | 02/14/13 | 56.4% | 0.0% | N/A | 73.5% | 1.5% | 620 | 77.49 | NM | NM | NM | NM | 0.3 | 8.0 | 5.1 | 15.6 | N/A |
| | 13.5 ft | 09/02/10 | 51.2% | 13.6% | | 31.2% | 13.6% | OVR | 32.6 | 170 | 10.0 | OVR | 0.0 | OVR | OVR | 19.4 | 0.1 | 16.2% |
| | | 11/29/10 | 52.5% | 14.6% | | 42.1% | 16.0% | 128300 | 32.8 | 15.0 | 4.0 | OVR | 0.7 | OVR | OVR | 18.6 | 0.8 | 16.4% |
| | | 02/16/11 | 36.1% | 6.1% | OVR | 73.4% | 5.7% | 2530000 | 92.3 | 66.0 | 4.0 | OVR | 0.3 | OVR | OVR | 14.3 | 0.2 | N/A |
| | | 04/22/11 | 62.0% | 14.0% | OVR | 70.0% | 11.4% | OVR | 80.2 | 0.0 | 4.0 | OVR | 0.0 | OVR | OVR | 17.0 | 1.8 | N/A |
| | | 08/05/11 | 67.8% | 9.6% | 1.0% | 61.5% | 6.6% | 70800 | 32.1 | 33.0 | 1.0 | 25.0 | 0.0 | 32.4 | OVR | 13.9 | 2.0 | N/A |
| | | 11/16/11 | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS |
| | | 02/01/12 | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS |
| | | 04/25/12 | 63.1% | 8.9% | OVR | 50.1% | 10.1% | OVR | 50.0 | NM | NM | NM | NM | OVR | OVR | 14.1 | 1.3 | N/A |
| | | 07/30/12 | 64.0% | 0.0% | N/A | 53.5% | 6.4% | 666000 | 53.0 | NM | NM | NM | NM | OVR | OVR | 16.4 | 0.6 | N/A |
| | | 10/25/12 | 51.7% | 4.9% | OVR | 48.8% | 7.3% | 544000 | 99.0 | NM | NM | NM | NM | OVR | OVR | 15.5 | 1.6 | N/A |
| | | 02/14/13 | 57.5% | 2.7% | N/A | 47.5% | 2.5% | 168000 | 180 | NM | NM | NM | NM | OVR | OVR | 13.8 | 1.4 | N/A |
| | 19 ft | 09/02/10 | 51.9% | 11.4% | | 20.7% | 16.8% | OVR | 0.0 | 162 | 12.0 | Off | 0.0 | OVR | OVR | 18.5 | 0.0 | 15.6% |
| | | 11/29/10 | 56.3% | 14.3% | | 49.3% | 14.6% | 126100 | 36.1 | 12.0 | 2.0 | OVR | 0.9 | OVR | OVR | 18.5 | 0.8 | 15.0% |
| | | 02/16/11 | 54.6% | 5.1% | OVR | 60.0% | 4.8% | 2640000 | 87.5 | 93.0 | 5.0 | OVR | 0.3 | OVR | OVR | 14.6 | 0.2 | N/A |
| | | 04/27/11 | 51.3% | 10.6% | OVR | 67.3% | 27.8% | 4390000 | 111 | 3.0 | 0.0 | OVR | 1.6 | OVR | OVR | 11.7 | 1.8 | N/A |
| | | 08/05/11 | 57.2% | 7.7% | 3.6% | 41.6% | 13.3% | 1800 | 171.2 | 6.0 | 0.0 | 8.0 | 0.0 | 0.3 | 6.0 | 4.7 | 15.7 | N/A |
| | | 11/16/11 | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS |
| | | 02/01/12 | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS |
| | | 04/25/12 | 65.0% | 9.6% | OVR | 58.5% | 12.6% | OVR | 53.42 | NM | NM | NM | NM | OVR | OVR | 14.3 | 0.7 | N/A |
| | | 07/30/12 | 61.2% | 0.0% | N/A | 55.0% | 3.9% | OVR | 50.5 | NM | NM | NM | NM | OVR | OVR | 15.7 | 0.3 | N/A |
| | | 10/25/12 | 52.3% | 7.9% | OVR | 68.4% | 9.4% | 583000 | 100 | NM | NM | NM | NM | OVR | OVR | 15.0 | 1.5 | N/A |
| | | 02/14/13 | 42.3% | 7.0% | N/A | 60.3% | 2.6% | 605000 | 77.32 | NM | NM | NM | NM | OVR | OVR | 13.9 | 1.4 | N/A |
| | 31 ft | 09/03/10 | 50.2% | 15.1% | | 41.2% | 14.8% | 131 | 1.3 | 2.0 | 0.0 | 36.0 | 2.4 | 0.0 | 0.0 | 0.3 | 15.5 | 14.6% |
| | | 11/29/10 | 51.5% | 14.4% | | 35.2% | 14.4% | 83500 | 37.1 | 12.0 | 3.0 | OVR | 0.6 | OVR | OVR | 18.9 | 0.7 | 13.9% |
| | | 02/16/11 | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS |
| | | 04/22/11 | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS |
| | | 08/05/11 | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS |
| | | 11/16/11 | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS |
| | | 02/01/12 | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS |
| | | 04/25/12 | 67.0% | 10.5% | OVR | 51.5% | 11.9% | OVR | 58.46 | NM | NM | NM | NM | OVR | OVR | 14.0 | 1.0 | N/A |
| | | 07/30/12 | 55.4% | 11.0% | N/A | 50.3% | 8.1% | OVR | 48.9 | NM | NM | NM | NM | OVR | OVR | 15.6 | 0.0 | N/A |
| | | 10/25/12 | 51.9% | 9.5% | OVR | 50.1% | 9.5% | 933000 | 83.0 | NM | NM | NM | NM | OVR | OVR | 15.5 | 1.6 | N/A |
| | | 02/18/13[9] | 54.0% | 9.8% | OVR | 48.9% | 7.9% | 917000 | 61.25 | NM | NM | NM | NM | OVR | OVR | 14.7 | 1.0 | N/A |

SEE LAST PAGE OF TABLE FOR NOTES

**TABLE 3**
**SOIL VAPOR SAMPLING - TEDLAR SAMPLING DATA**

| Reading Location | | | Shroud | Tedlar Bag 1 | | Shroud | Tedlar Bag 2 | | | | | | | | | | | Tedlar Bag 3 |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| Instrument | | | Dielectric | | Landtec | Dielectric | | FID | PID | Multi-gas | | | | Landtec | | | | Dielectric |
| Location | Depth | Date | Helium in Shroud Before | Helium Before | CH4 (%) | Helium in Shroud After | Helium After | FID (ppm) | PID (ppm) | CO (ppm) | H2S (ppm) | LEL (%) | O2 (%) | CH4 (%) | LEL (%) | CO2 (%) | O2 (%) | Direct Port Reading After |
| VMP-17 | 5 ft | 06/21/10 | 48.8% | 0.0% | | 36.1% | 0.0% | | 0.0 | 4.0 | 0.0 | 0.0 | 11.9 | | | OVR | | N/A |
| | | 09/01/10 | 64.5% | 0.0% | | 55.2% | 0.0% | 0.0 | 0.0 | 2.0 | 0.0 | 0.0 | 0.0 | 0.6 | 12.0 | 8.1 | 11.0 | N/A |
| | | 11/22/10 | 60.0% | 0.0% | | 47.1% | 0.0% | 9.1 | 1.8 | 5.0 | 0.0 | 0.0 | 15.1 | 0.0 | 0.0 | 5.6 | 15.2 | N/A |
| | | 02/07/11 | 51.7% | 0.0% | 0.0% | 49.6% | 0.0% | 295 | 0.3 | 2.0 | 0.0 | 0.0 | 18.2 | 0.0 | 0.0 | 3.0 | 18.1 | N/A |
| | | 04/06/11 | 62.5% | 0.0% | 0.1% | 33.6% | 0.0% | 3.9 | 0.7 | 0.0 | 0.0 | 0.0 | 17.1 | 0.1 | 2.0 | 2.8 | 17.1 | N/A |
| | | 08/01/11 | 52.8% | 0.0% | N/A | 31.8% | 0.0% | 0.0 | 5.0 | 3.0 | 0.0 | 0.0 | 10.2 | 0.0 | 0.0 | 6.6 | 13.5 | N/A |
| | | 11/07/11 | 60.7% | 0.0% | N/A | 61.0% | 0.0% | | 0 | 0.0 | 0.0 | 0.0 | 17.1 | 0.0 | 0.0 | 3.6 | 17.0 | N/A |
| | | 01/26/12 | 53.4% | 0.0% | N/A | 52.8% | 0.0% | 2.0 | 1.1 | 1.0 | 0.0 | 0.0 | 17.2 | 0.0 | 0.0 | 3.0 | 17.5 | N/A |
| | | 04/11/12 | 55.1% | 0.0% | N/A | 71.9% | 0.1% | 2.0 | 0.4 | NM | NM | NM | NM | 0.0 | 0.0 | 1.3 | 20.0 | N/A |
| | | 07/11/12 | 81.2% | 0.0% | 0.0% | 64.2% | 0.0% | 2.2 | 0.8 | NM | NM | NM | NM | 0.0 | 0.0 | 0.5 | 20.2 | N/A |
| | | 10/09/12 | 52.8% | 0.0% | N/A | 41.4% | 0.1% | 2.0 | 1.4 | NM | NM | NM | NM | 0.0 | 0.0 | 0.6 | 20.4 | N/A |
| | | 01/31/13 | 64.5% | 0.0% | N/A | 61.4% | 0.2% | 2.82 | 0.4 | NM | NM | NM | NM | 0.0 | 0.0 | 0.2 | 21.1 | N/A |
| VMP-18 | 8.5 ft | 06/18/10 | 47.8% | 0.0% | . | 34.8% | 0.0% | | 0.3 | 4.0 | 0.0 | 6.0 | 12.6 | | | OVR | | N/A |
| | | 09/07/10 | 63.7% | 0.0% | | 63.7% | 0.1% | 0.0 | 0.0 | 0.0 | 0.0 | 0.0 | 0.0 | 0.0 | 0.0 | 11.2 | 12.4 | N/A |
| | | 11/19/10 | 55.2% | 0.0% | | 67.2% | 0.1% | 4.3 | 3.1 | 4.0 | 0.0 | 9.0 | 10.4 | 0.3 | 6.0 | 9.9 | 10.6 | N/A |
| | | 02/09/11 | 61.3% | 0.0% | N/A | 42.9% | 0.0% | 196 | 0.9 | 0.0 | 0.0 | 0.0 | 14.6 | 0.1 | 2.0 | 7.1 | 15.4 | N/A |
| | | 04/07/11 | 58.1% | 0.1% | N/A | 61.3% | 0.4% | 14.0 | 1.0 | 0.0 | 0.0 | 0.0 | 13.4 | 0.0 | 0.0 | 6.4 | 13.1 | N/A |
| | | 07/28/11 | 54.2% | 0.0% | N/A | 70.7% | 0.0% | 0.0 | 5.6 | 0.0 | 0.0 | 0.0 | 8.0 | 0.0 | 0.0 | 8.3 | 12.5 | N/A |
| | | 11/07/11 | 51.4% | 0.0% | N/A | 52.8% | 0.0% | | 0.0 | 0.0 | 0.0 | 0.0 | 13.3 | 0.0 | 0.0 | 8.2 | 13.3 | N/A |
| | | 01/23/12 | 56.1% | 0.0% | N/A | 52.0% | 0.0% | 0.0 | 0.2 | 0.0 | 0.0 | 0.0 | 15.7 | 0.0 | 0.0 | 5.7 | 16.1 | N/A |
| | | 04/10/12 | 67.9% | 0.0% | N/A | 57.9% | 0.1% | 2.0 | 0.6 | NM | NM | NM | NM | 0.0 | 0.0 | 5.4 | 17.4 | N/A |
| | | 07/12/12 | 51.6% | 0.0% | 0.0% | 48.1% | 0.0% | 4.1 | 1.5 | NM | NM | NM | NM | 0.0 | 0.0 | 4.6 | 18.4 | N/A |
| | | 10/09/12 | 55.4% | 0.0% | N/A | 43.4% | 0.0% | 1.0 | 1.1 | NM | NM | NM | NM | 0.0 | 0.0 | 4.7 | 18.3 | N/A |
| | | 01/23/13 | 54.0% | 0.0% | N/A | 53.0% | 0.0% | 0.48 | 0.3 | NM | NM | NM | NM | 0.0 | 0.0 | 1.3 | 20.1 | N/A |
| VMP-19 | 5 ft | 06/18/10 | 46.8% | 0.0% | | 11.8% | 0.0% | | 0.3 | 10.0 | 0.0 | 0.0 | 12.6 | | | OVR | | N/A |
| | | 09/01/10 | 52.0% | 0.0% | | 58.6% | 1.1% | 22.8 | 1.1 | 2.0 | 0.0 | 0.0 | 0.0 | 0.7 | 12.0 | 10.7 | 8.5 | N/A |
| | | 11/15/10 | 57.4% | 0.0% | | 63.4% | 0.0% | 0.0 | 0.0 | 0.0 | 0.0 | 8.0 | 11.0 | 0.0 | 0.0 | 8.6 | 4.4 | N/A |
| | | 02/09/11 | 57.5% | 0.3% | N/A | 42.5% | 0.4% | 554 | 1.3 | 0.0 | 0.0 | 3.0 | 15.5 | 0.1 | 1.0 | 6.9 | 16.4 | N/A |
| | | 04/07/11 | 52.3% | 0.0% | N/A | 68.0% | 0.2% | | 0.2 | 0.0 | 0.0 | 0.0 | 15.0 | 0.2 | 3.0 | 5.3 | 15.4 | N/A |
| | | 08/09/11 | 57.1% | 0.0% | N/A | 59.3% | 0.3% | | 5.0 | 23.0 | 0.0 | 0.0 | 10.8 | 0.0 | 1.0 | 9.8 | 10.3 | N/A |
| | | 11/08/11 | 75.8% | 0.0% | N/A | 54.7% | 0.0% | 0.0 | 0.3 | 0.0 | 0.0 | 0.0 | 14.3 | 0.0 | 0.0 | 6.5 | 14.3 | N/A |
| | | 01/26/12 | 89.6% | 0.0% | N/A | 69.1% | 0.0% | 2.0 | 0.4 | 0.0 | 0.0 | 0.0 | 15.6 | 0.0 | 0.0 | 5.0 | 15.4 | N/A |
| | | 04/10/12 | 59.5% | 0.0% | N/A | 72.7% | 0.3% | 1.9 | 0.6 | NM | NM | NM | NM | 0.0 | 0.0 | 2.2 | 19.8 | N/A |
| | | 07/11/12 | 54.5% | 0.0% | 0.0% | 60.0% | 0.0% | 3.7 | 1.3 | NM | NM | NM | NM | 0.0 | 0.0 | 0.8 | 20.3 | N/A |
| | | 10/09/12 | 54.3% | 0.0% | N/A | 53.4% | 0.1% | 1.0 | 1.2 | NM | NM | NM | NM | 0.0 | 0.0 | 0.5 | 20.7 | N/A |
| | | 01/31/13 | 65.4% | 0.0% | N/A | 48.7% | 0.0% | 3.11 | 0.5 | NM | NM | NM | NM | 0.0 | 0.0 | 0.2 | 21.3 | N/A |

SEE LAST PAGE OF TABLE FOR NOTES

**TABLE 3**
**SOIL VAPOR SAMPLING - TEDLAR SAMPLING DATA**

| Reading Location | | | Shroud | Tedlar Bag 1 | | Shroud | Tedlar Bag 2 | | | | | | | | | | | Tedlar Bag 3 |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| Instrument | | | Dielectric | | Landtec | Dielectric | | FID | PID | Multi-gas | | | | Landtec | | | | Dielectric |
| Location | Depth | Date | Helium in Shroud Before | Helium Before | CH4 (%) | Helium in Shroud After | Helium After | FID (ppm) | PID (ppm) | CO (ppm) | H2S (ppm) | LEL (%) | O2 (%) | CH4 (%) | LEL (%) | CO2 (%) | O2 (%) | Direct Port Reading After |
| VMP-20 | 5 ft | 03/14/11 | 53.4% | 0.0% | N/A | 60.9% | 0.0% | 0.0 | 2.1 | 10.0 | 0.0 | 0.0 | 7.0 | 0.0 | 0.0 | 10.3 | 7.6 | N/A |
| | | 04/15/11 | 52.0% | 0.0% | N/A | 80.0% | 0.0% | | 0.2 | 8.0 | 0.0 | 0.0 | 5.4 | 0.0 | 0.0 | 8.7 | 8.9 | N/A |
| | | 07/25/11 | 52.4% | 0.0% | N/A | 51.0% | 0.0% | 0.0 | 0.4 | 0.0 | 0.0 | 0.0 | 3.5 | 0.0 | 0.0 | 14.9 | 6.9 | N/A |
| | | 11/01/11 | 70.0% | 0.0% | N/A | 58.4% | 0.0% | | 0.6 | 0.0 | 0.0 | 0.0 | 18.5 | 0.0 | 0.0 | 8.3 | 13.6 | N/A |
| | | 01/23/12 | 58.4% | 0.0% | N/A | 56.8% | 0.0% | 1.0 | 0.1 | 0.0 | 0.0 | 0.0 | 17.2 | 0.0 | 0.0 | 4.5 | 16.9 | N/A |
| | | 04/10/12 | 74.5% | 0.0% | 0.0% | 76.6% | 0.0% | 2.0 | 0.6 | NM | NM | NM | NM | 0.0 | 0.0 | 6.1 | 16 | N/A |
| | | 07/11/2012[11] | 57.7% | 0.0% | N/A | 61.5% | 0.2% | 2.2 | 1.0 | N/A | N/A | N/A | N/A | 0.0 | 0.0 | 10.2 | 11.9 | N/A |
| | | 07/31/12 | 51.4% | 0.0% | N/A | 68.4% | 0.0% | 13.2 | 1.1 | NM | NM | NM | NM | 0.0 | 0.0 | 10.5 | 11.2 | N/A |
| | | 10/04/12 | 63.4% | 0.0% | N/A | 49.0% | 0.0% | 1.0 | 0.4 | NM | NM | NM | NM | 0.0 | 0.0 | 6.4 | 15.5 | N/A |
| | | 02/07/13[11] | 76.2% | 0.0% | N/A | 58.5% | 0.0% | 0.46 | 0.3 | NM | NM | NM | NM | 0.0 | 0.0 | 3.9 | 17.6 | N/A |
| | 10 ft | 03/14/11 | 52.1% | 0.0% | N/A | 36.4% | 0.0% | 0.0 | 0.7 | 0.0 | 0.0 | 0.0 | 8.0 | 0.0 | 0.0 | 9.4 | 7.0 | N/A |
| | | 04/15/11 | 56.0% | 0.0% | N/A | 94.3% | 0.0% | | 5.0 | 2.0 | 0.0 | 0.0 | 5.4 | 0.0 | 0.0 | 8.4 | 8.5 | N/A |
| | | 07/25/11 | 56.2% | 0.0% | N/A | 51.6% | 0.0% | 0.0 | 2.6 | 0.0 | 0.0 | 0.0 | 2.6 | 0.1 | 0.0 | 8.2 | 7.0 | N/A |
| | | 11/01/11 | 68.9% | 0.0% | N/A | 51.1% | 0.0% | | 0.6 | 0.0 | 0.0 | 0.0 | 15.4 | 0.0 | 0.0 | 8.6 | 9.6 | N/A |
| | | 01/23/12 | 61.3% | 0.0% | N/A | 58.2% | 0.0% | 0.0 | 0.1 | 0.0 | 0.0 | 0.0 | 15.4 | 0.0 | 0.0 | 6.2 | 14.7 | N/A |
| | | 04/10/12 | 61.8% | 0.0% | 0.0% | 72.6% | 0.0% | 2.0 | 0.6 | NM | NM | NM | NM | 0.0 | 0.0 | 6.3 | 13.3 | N/A |
| | | 07/11/12 | 52.4% | 0.0% | N/A | 60.4% | 0.0% | 1.4 | 1.0 | N/A | N/A | N/A | N/A | 0.0 | 0.0 | 7.8 | 13.2 | N/A |
| | | 10/04/12 | 60.0% | 0.0% | N/A | 49.7% | 0.0% | 1.0 | 0.6 | NM | NM | NM | NM | 0.0 | 0.0 | 8.0 | 14 | N/A |
| | | 01/22/13 | 69.8% | 0.0% | N/A | 69.7% | 0.2% | 0.86 | 0.2 | NM | NM | NM | NM | 0.0 | 0.0 | 4.1 | 19.2 | N/A |
| | 25 ft | 03/14/11 | 52.0% | 0.0% | N/A | 38.5% | 0.0% | 0.0 | 1.4 | 0.0 | 0.0 | 0.0 | 2.2 | 0.0 | 0.0 | 10.0 | 2.2 | N/A |
| | | 04/15/11 | 52.0% | 0.0% | N/A | 60.4% | 0.0% | | 2.5 | 3.0 | 0.0 | 3.0 | 0.0 | 0.1 | 1.0 | 10.5 | 2.1 | N/A |
| | | 07/26/11 | 51.8% | 0.1% | N/A | 39.8% | 0.0% | 4200 | 113.9 | 4.0 | 0.0 | 7.0 | 0.0 | 1.0 | 20.0 | 8.6 | 1.0 | N/A |
| | | 11/01/11 | 51.5% | 0.0% | N/A | 53.0% | 0.0% | | 0.5 | 0.0 | 0.0 | 0.0 | 5.6 | 0.0 | 0.0 | 9.3 | 2.2 | N/A |
| | | 01/23/12 | 63.8% | 0.0% | N/A | 56.2% | 0.0% | 0.0 | 0.2 | 0.0 | 0.0 | 0.0 | 7.3 | 0.0 | 0.0 | 0.1 | 21.0 | N/A |
| | | 04/10/12 | 65.9% | 0.0% | 0.0% | 80.4% | 0.0% | 3.0 | 0.5 | NM | NM | NM | NM | 0.0 | 0.0 | 7.4 | 8.3 | N/A |
| | | 07/11/12 | 51.5% | 0.0% | N/A | 50.0% | 0.0% | 2.0 | 1.1 | N/A | N/A | N/A | N/A | 0.0 | 0.0 | 6.9 | 10.4 | N/A |
| | | 10/04/12 | 63.8% | 0.0% | N/A | 39.0% | 0.0% | 2.0 | 0.9 | NM | NM | NM | NM | 0.1 | 2 | 6.8 | 13.1 | N/A |
| | | 01/22/13 | 52.5% | 0.0% | N/A | 37.2% | 0.0% | 0.20 | 0.20 | NM | NM | NM | NM | 0.0 | 0.0 | 6.7 | 15.8 | N/A |
| | 39.5 ft | 03/14/11 | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS |
| | | 04/15/11 | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS |
| | | 07/26/11 | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS |
| | | 11/01/11 | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS |
| | | 01/23/12 | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS |
| | | 4/10/2012 [13] | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS |
| | | 7/12/12 [13] | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS |
| | | 10/04/12 | 62.9% | 0.0% | N/A | 45.7% | 0.0% | 3000 | 184 | NM | NM | NM | NM | 1.2 | 26.0 | 9.4 | 2.2 | N/A |
| | | 01/23/13 | 56.4% | 0.0% | N/A | 33.5% | 0.0% | 850 | 110 | NM | NM | NM | NM | 0.5 | 11.0 | 9.7 | 2.0 | N/A |

SEE LAST PAGE OF TABLE FOR NOTES

**TABLE 3**
**SOIL VAPOR SAMPLING - TEDLAR SAMPLING DATA**

| Reading Location | | | Shroud | Tedlar Bag 1 | | Shroud | Tedlar Bag 2 | | | | | | | | | | | Tedlar Bag 3 |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| Instrument | | | Dielectric | | Landtec | Dielectric | | FID | PID | Multi-gas | | | | Landtec | | | | Dielectric |
| Location | Depth | Date | Helium in Shroud Before | Helium Before | CH4 (%) | Helium in Shroud After | Helium After | FID (ppm) | PID (ppm) | CO (ppm) | H2S (ppm) | LEL (%) | O2 (%) | CH4 (%) | LEL (%) | CO2 (%) | O2 (%) | Direct Port Reading After |
| VMP-21 | 5 ft | 02/09/11 | 73.4% | 0.0% | N/A | 53.8% | 1.9% | 11780 | 273.0 | 0.0 | 0.0 | 30.0 | 9.1 | 43.4 | OVR | 6.5 | 9.2 | N/A |
| | | 04/13/11 | 70.1% | 0.0% | N/A | 52.8% | 0.2% | 0.0 | 0.9 | 0.0 | 0.0 | 0.0 | 16.7 | 0.0 | 0.0 | 1.9 | 16.9 | N/A |
| | | 07/25/11 | 55.4% | 0.0% | N/A | 49.7% | 0.0% | 0.0 | 3.7 | 0.0 | 0.0 | 0.0 | 2.0 | 0.0 | 0.0 | 14.5 | 7.1 | N/A |
| | | 11/01/11 | 77.6% | 0.0% | N/A | 47.8% | 0.0% | | 0.6 | 0.0 | 0.0 | 0.0 | 18.3 | 0.0 | 0.0 | 4.5 | 17.1 | N/A |
| | | 01/23/12 | 58.6% | 0.0% | N/A | 62.1% | 0.0% | 0.0 | 0.2 | 0.0 | 0.0 | 0.0 | 19.9 | 0.0 | 0.0 | 1.5 | 19.8 | N/A |
| | | 4/9/2012 [11] | 60.7% | 0.7% | 0.0% | 74.0% | 0.0% | 1.2 | 0.8 | NM | NM | NM | NM | 0.0 | 0.0 | 2.8 | 16.3 | N/A |
| | | 04/24/12 | 64.2% | 0.0% | N/A | 55.9% | 0.2% | 4.3 | 0.7 | NM | NM | NM | NM | 0.0 | 0.0 | 3.2 | 16.7 | N/A |
| | | 07/10/12 | 55.2% | 0.0% | N/A | 50.0% | 0.0% | 2.2 | 0.6 | N/A | N/A | N/A | N/A | 0.0 | 0.0 | 8.3 | 13.3 | N/A |
| | | 10/04/12 | 55.6% | 0.0% | N/A | 48.1% | 0.0% | 1.0 | 0.5 | NM | NM | NM | NM | 0.0 | 0.0 | 4.1 | 16.9 | N/A |
| | | 02/06/13 | 50.5% | 0.0% | N/A | 60.3% | 0.1% | 1.31 | 0.2 | NM | NM | NM | NM | 0.0 | 0.0 | 1.0 | 20.1 | N/A |
| | 10 ft | 02/10/11 | 64.5% | 0.0% | N/A | 59.5% | 0.0% | 8350 | 533 | 9.0 | 0.0 | 27.0 | 8.1 | 24.9 | OVR | 7.5 | 8.7 | N/A |
| | | 04/13/11 | 65.2% | 0.0% | N/A | 57.7% | 0.4% | 263 | 40.2 | 0.0 | 0.0 | 0.0 | 8.2 | 0.1 | 3.0 | 6.7 | 8.3 | N/A |
| | | 07/25/11 | 55.0% | 0.0% | N/A | 49.2% | 0.3% | 0.0 | 3.7 | 0.0 | 0.0 | 0.0 | 2.6 | 0.0 | 0.0 | 7.5 | 8.1 | N/A |
| | | 11/01/11 | 60.7% | 0.0% | N/A | 50.1% | 0.0% | | 0.6 | 0.0 | 0.0 | 0.0 | 14.8 | 0.0 | 0.0 | 8.0 | 12.7 | N/A |
| | | 01/23/12 | 59.0% | 0.0% | N/A | 61.8% | 0.1% | 0.0 | 0.2 | 0.0 | 0.0 | 0.0 | 17.4 | 0.0 | 0.0 | 5.6 | 16.2 | N/A |
| | | 04/09/12 | 61.5% | 0.0% | 0.0% | 61.0% | 0.0% | 2.0 | 1.0 | NM | NM | NM | NM | 0.0 | 0.0 | 4.5 | 16.2 | N/A |
| | | 07/10/12 | 71.4% | 0.0% | N/A | 58.6% | 0.0% | 3.1 | 0.7 | N/A | N/A | N/A | N/A | 0.0 | 0.0 | 6.1 | 13.1 | N/A |
| | | 10/04/12 | 50.9% | 0.0% | N/A | 47.2% | 0.1% | 3.0 | 0.9 | NM | NM | NM | NM | 0.0 | 0.0 | 6.5 | 14.7 | N/A |
| | | 02/05/13 | 60.7% | 0.0% | N/A | 48.3% | 0.0% | 0.81 | 0.2 | NM | NM | NM | NM | 0.0 | 0.0 | 3.8 | 17.7 | N/A |
| | 25 ft | 02/10/11 | 50.7% | 0.0% | N/A | 54.5% | 0.0% | 48340 | 227 | 35.0 | 1.0 | OVR | 0.4 | OVR | OVR | 7.0 | 0.2 | N/A |
| | | 04/14/11 | 55.0% | 0.0% | N/A | 66.0% | 0.2% | 102000 | 459 | 61.0 | 11.0 | 18.0 | 0.0 | OVR | OVR | 6.3 | 0.5 | N/A |
| | | 07/26/11 | 61.6% | 0.0% | N/A | 59.2% | 0.4% | 102000 | 398.5 | 138 | 3.0 | 73.0 | 0.0 | OVR | OVR | 6.2 | 0.1 | N/A |
| | | 11/01/11 | 65.7% | 0.0% | N/A | 64.7% | 0.0% | | 348.4 | 17.0 | 4.0 | 11 | 0.6 | 3.3 | 67.0 | 9.3 | 0.3 | N/A |
| | | 01/24/12 | 67.5% | 1.4% | 0.0% | 64.6% | 5.3% | 192 | 7.9 | 0.0 | 0.0 | 3.0 | 4.1 | 0.0 | 0.0 | 11.4 | 1.3 | N/A |
| | | 04/09/12 | 51.3% | 0.0% | 0.0% | 74.0% | 0.0% | 20.0 | 1.3 | NM | NM | NM | NM | 0.0 | 0.0 | 12.1 | 2.1 | N/A |
| | | 07/11/12 | 55.0% | 0.0% | N/A | 58.6% | 0.0% | 2.2 | 1.4 | N/A | N/A | N/A | N/A | 0.0 | 0.0 | 10.7 | 5.3 | N/A |
| | | 10/04/12 | 54.9% | 0.0% | N/A | 77.7% | 0.0% | 2.0 | 0.6 | NM | NM | NM | NM | 0.0 | 0.0 | 8.6 | 10.1 | N/A |
| | | 02/05/13 | 57.1% | 0.0% | N/A | 47.5% | 0.0% | 0.66 | 0.3 | NM | NM | NM | NM | 0.0 | 0.0 | 8.9 | 9.6 | N/A |
| | 33 ft | 02/10/11 | 51.9% | 0.0% | N/A | 51.2% | 0.4% | 63640 | 434 | 42.0 | 7.0 | OVR | 0.4 | OVR | OVR | 4.9 | 5.2 | N/A |
| | | 04/14/11 | 59.9% | 0.0% | N/A | 59.9% | 0.9% | 98820 | 385 | 8.0 | 15.0 | 36.0 | 0.0 | OVR | OVR | 6.0 | 0.8 | N/A |
| | | 07/26/11 | NS | NS | N/A | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS |
| | | 11/01/11 | 53.4% | 0.0% | N/A | 51.1% | 0.0% | | 259.7 | 0.0 | 0.0 | 5.0 | 3.4 | 1.5 | 31.0 | 7.9 | 0.1 | N/A |
| | | 01/24/12 | 55.5% | 0.0% | 0.0% | 60.3% | 0.0% | 623 | 47.7 | 0.0 | 0.0 | 4.0 | 3.8 | 0.0 | 0.0 | 11.7 | 0.9 | N/A |
| | | 4/9/2012 [12] | 51.7% | 0.0% | 0.0% | 67.1% | 0.0% | 619 | 16.95 | NM | NM | NM | NM | 0.0 | 1.0 | 12.4 | 0.5 | N/A |
| | | 04/24/12 | 52.3% | 0.0% | N/A | 57.0% | 0.0% | 18.0 | 1.3 | NM | NM | NM | NM | 0.0 | 0.0 | 12.3 | 1.1 | N/A |
| | | 07/11/12 | 51.6% | 0.0% | N/A | 50.2% | 0.0% | 5.7 | 1.7 | N/A | N/A | N/A | N/A | 0.0 | 0.0 | 12.0 | 2.6 | N/A |
| | | 10/04/12 | 53.9% | 0.0% | N/A | 42.8% | 0.1% | 2.0 | 0.7 | NM | NM | NM | NM | 0.0 | 0.0 | 10.8 | 6.9 | N/A |
| | | 02/05/13 | 67.5% | 0.0% | N/A | 61.6% | 0.0% | 0.99 | 0.2 | NM | NM | NM | NM | 0.0 | 0 | 10.1 | 8.4 | N/A |

SEE LAST PAGE OF TABLE FOR NOTES

**TABLE 3**
**SOIL VAPOR SAMPLING - TEDLAR SAMPLING DATA**

| Reading Location | | | Shroud | Tedlar Bag 1 | | Shroud | Tedlar Bag 2 | | | | | | | | | | | Tedlar Bag 3 |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| Instrument | | | Dielectric | | Landtec | Dielectric | | FID | PID | Multi-gas | | | | Landtec | | | | Dielectric |
| Location | Depth | Date | Helium in Shroud Before | Helium Before | CH4 (%) | Helium in Shroud After | Helium After | FID (ppm) | PID (ppm) | CO (ppm) | H2S (ppm) | LEL (%) | O2 (%) | CH4 (%) | LEL (%) | CO2 (%) | O2 (%) | Direct Port Reading After |
| VMP-22 | 5 ft | 02/11/11 | 53.4% | 0.0% | 0.1% | 52.4% | 0.0% | 105 | 26.4 | 2.0 | 0.0 | 0.0 | 7.3 | 0.0 | 0.0 | 9.0 | 6.5 | N/A |
| | | 04/18/11 | 57.0% | 0.0% | N/A | 58.1% | 0.0% | 0.0 | 0.0 | 0.0 | 0.0 | 0.0 | 7.9 | 0.1 | 0.0 | 6.8 | 11.1 | N/A |
| | | 07/26/11 | 55.5% | 0.0% | N/A | 65.0% | 0.0% | 0.0 | 3.1 | 7.0 | 0.0 | 2.0 | 8.1 | 0.0 | 0.0 | 7.6 | 11.9 | N/A |
| | | 11/01/11 | 69.4% | 0.0% | N/A | 50.7% | 0.0% | | 0.7 | 0.0 | 0.0 | 0.0 | 19.4 | 0.0 | 0.0 | 2.7 | 18.4 | N/A |
| | | 01/24/12 | 53.0% | 0.0% | N/A | 54.5% | 0.0% | 0.0 | 0.2 | 0.0 | 0.0 | 0.0 | 20.4 | 0.0 | 0.0 | 0.8 | 19.8 | N/A |
| | | 04/09/12 | 60.6% | 0.0% | N/A | 50.8% | 0.1% | 2.0 | 1.0 | NM | NM | NM | NM | 0.0 | 0.0 | 1.1 | 19.6 | N/A |
| | | 07/09/12 | 55.5% | 0.0% | N/A | 50.2% | 0.0% | 3.1 | 1.2 | NM | NM | NM | NM | 0.0 | 0.0 | 3.0 | 18.5 | N/A |
| | | 10/03/12 | 90.7% | 1.2% | N/A | 53.7% | 0.1% | 1.0 | 0.3 | NM | NM | NM | NM | 0.0 | 0.0 | 1.4 | 19.5 | N/A |
| | | 01/24/13 | 52.0% | 0.0% | N/A | 31.9% | 0.3% | 1.18 | 0.2 | NM | NM | NM | NM | 0.0 | 0.0 | 0.4 | 20.6 | N/A |
| | 10 ft | 02/11/11 | 52.1% | 0.0% | 0.1% | 80.2% | 0.0% | 40.6 | 17.6 | 0.0 | 0.0 | 0.0 | 4.5 | 0.1 | 2.0 | 10.6 | 4.8 | N/A |
| | | 04/18/11 | 51.0% | 0.0% | N/A | 49.5% | 0.0% | 0.0 | 0.0 | 0.0 | 0.0 | 0.0 | 6.4 | 0.0 | 1.8 | 8.4 | 6.8 | N/A |
| | | 07/26/11 | 54.5% | 0.0% | N/A | 39.2% | 0.0% | 2.9 | 2.7 | 8.0 | 0.0 | 0.0 | 0.0 | 0.0 | 0.0 | 10.5 | 4.5 | N/A |
| | | 11/01/11 | 62.2% | 0.0% | N/A | 56.5% | 0.0% | 0.0 | 0.6 | 0.0 | 0.0 | 0.0 | 18.5 | 0.0 | 0.0 | 5.9 | 15 | N/A |
| | | 01/24/12 | 54.2% | 0.0% | N/A | 70.5% | 0.0% | 0.0 | 0.1 | 0.0 | 0.0 | 0.0 | 19.3 | 0.0 | 0.0 | 2.4 | 19.1 | N/A |
| | | 04/09/12 | 56.0% | 0.0% | N/A | 51.7% | 0.0% | 0.0 | 1.0 | NM | NM | NM | NM | 0.0 | 0.0 | 1.6 | 18.9 | N/A |
| | | 07/09/12 | 60.0% | 0.0% | N/A | 47.8% | 0.0% | 1.5 | 0.9 | NM | NM | NM | NM | 0.0 | 0.0 | 3.2 | 17.7 | N/A |
| | | 10/03/12 | 64.3% | 0.0% | N/A | 54.0% | 0.3% | 2.0 | 0.5 | NM | NM | NM | NM | 0.0 | 0.0 | 1.6 | 19.3 | N/A |
| | | 01/24/13 | 51.6% | 0.0% | N/A | 31.9% | 0.0% | 0.92 | 0.2 | NM | NM | NM | NM | 0.0 | 0.0 | 0.7 | 20.3 | N/A |
| | 18 ft | 02/11/11 | 52.0% | 0.0% | 30.2% | 44.3% | 0.0% | 17430 | 326 | 2.0 | 1.0 | 54.0 | 0.9 | 31.5 | OVR | 12.0 | 0.0 | N/A |
| | | 04/18/11 | 51.0% | 0.0% | N/A | 44.3% | 0.0% | 29430 | 258 | 3.0 | 6.0 | 24.0 | 0.0 | 21.7 | OVR | 10.7 | 0.3 | N/A |
| | | 07/26/11 | 56.2% | 0.0% | N/A | 55.7% | 0.0% | 15800 | 205.8 | 27.0 | 3.0 | 24.0 | 0.0 | 11.5 | OVR | 10.5 | 0.8 | N/A |
| | | 11/01/11 | 71.4% | 0.0% | N/A | 60.0% | 0.0% | | 0.8 | 0.0 | 0.0 | 0.0 | 2.2 | 0.0 | 0.0 | 14.5 | 1.1 | N/A |
| | | 01/24/12 | 58.0% | 0.0% | N/A | 77.1% | 0.0% | 0.0 | 0.2 | 0.0 | 0.0 | 0.0 | 14.1 | 0.0 | 0.0 | 10.6 | 8.8 | N/A |
| | | 04/09/12 | 54.0% | 0.0% | N/A | 56.6% | 0.1% | 1.0 | 0.2 | NM | NM | NM | NM | 0.0 | 0.0 | 6.5 | 13.6 | N/A |
| | | 07/09/12 | 62.5% | 0.0% | N/A | 68.1% | 0.1% | 2.3 | 1.5 | NM | NM | NM | NM | 0.0 | 0.0 | 4.2 | 16.8 | N/A |
| | | 10/4/12[9] | 55.2% | 0.0% | N/A | 51.6% | 0.0% | 0.0 | 0.3 | NM | NM | NM | NM | 0.0 | 0.0 | 3.1 | 19.2 | N/A |
| | | 01/24/13 | 61.0% | 0.0% | N/A | 39.5% | 0.0% | 1.10 | 0.2 | NM | NM | NM | NM | 0.0 | 0.0 | 2.3 | 19.1 | N/A |
| | 38 ft | 02/11/11 | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS |
| | | 04/18/11 | 55.0% | 0.0% | N/A | 50.0% | 0.0% | 60850 | 290 | 0.0 | 9.0 | OVR | 0.0 | OVR | OVR | 10.8 | 0.3 | N/A |
| | | 07/26/11 | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS |
| | | 11/01/11 | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS |
| | | 01/24/12 | 62.0% | 0.0% | N/A | 51.0% | 0.0% | 142 | 40.1 | 0.0 | 0.0 | 0.0 | 3.2 | 0.0 | 0.0 | 16.4 | 0.8 | N/A |
| | | 04/09/12 | 69.7% | 0.0% | N/A | 58.0% | 0.0% | 2.0 | 1.0 | NM | NM | NM | NM | 0.0 | 0.0 | 12.1 | 6.5 | N/A |
| | | 07/09/12 | 54.8% | 0.0% | N/A | 58.9% | 0.0% | 1.2 | 1.0 | NM | NM | NM | NM | 0.0 | 0.0 | 6.4 | 14.8 | N/A |
| | | 10/04/12 | 67.3% | 0.0% | N/A | 40.0% | 0.0% | 0.0 | 0.4 | NM | NM | NM | NM | 0.0 | 0.0 | 5.2 | 16.3 | N/A |
| | | 01/24/13 | 71.0% | 0.0% | N/A | 32.8% | 0.0% | 0.88 | 0.3 | NM | NM | NM | NM | 0.0 | 0.0 | 5.1 | 17.1 | N/A |

SEE LAST PAGE OF TABLE FOR NOTES

**TABLE 3**
**SOIL VAPOR SAMPLING - TEDLAR SAMPLING DATA**

| Reading Location | | | Shroud | Tedlar Bag 1 | | Shroud | Tedlar Bag 2 | | | | | | | | | | | Tedlar Bag 3 |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| Instrument | | | Dielectric | | Landtec | Dielectric | | FID | PID | Multi-gas | | | | Landtec | | | | Dielectric |
| Location | Depth | Date | Helium in Shroud Before | Helium Before | CH4 (%) | Helium in Shroud After | Helium After | FID (ppm) | PID (ppm) | CO (ppm) | H2S (ppm) | LEL (%) | O2 (%) | CH4 (%) | LEL (%) | CO2 (%) | O2 (%) | Direct Port Reading After |
| VMP-23 | 5 ft | 02/15/11 | 62.3% | 0.0% | N/A | 80.3% | 0.7% | 7.0 | 0.5 | 0.0 | 0.0 | 0.0 | 18.4 | 18.6 | 11.0 | 0.3 | 19.9 | N/A |
| | | 04/21/11 | 60.0% | 0.0% | N/A | 52.3% | 0.0% | 0.0 | 0.7 | 23.0 | 0.0 | 0.0 | 14.7 | 0.0 | 2.0 | 5.5 | 15.1 | N/A |
| | | 07/27/11 | 62.8% | 0.0% | N/A | 53.7% | 0.0% | 0.0 | 4.9 | 2.0 | 0.0 | 0.0 | 5.3 | 0.0 | 0.0 | 8.8 | 9.2 | N/A |
| | | 11/02/11 | 61.4% | 0.0% | N/A | 55.6% | 0.1% | 0.0 | 1.1 | 0.0 | 0.0 | 0.0 | 17.5 | 0.0 | 0.0 | 3.1 | 16.6 | N/A |
| | | 01/25/12 | 59.0% | 0.0% | N/A | 66.0% | 0.1% | 0.6 | 0.3 | 0.0 | 0.0 | 0.0 | 19.1 | 0.0 | 0.0 | 2.3 | 18.8 | N/A |
| | | 04/09/12 | 70.0% | 0.0% | N/A | 59.3% | 0.1% | 4.0 | 0.7 | NM | NM | NM | NM | 0.0 | 0.0 | 0.9 | 19.8 | N/A |
| | | 07/09/12 | 56.2% | 0.0% | N/A | 67.1% | 0.2% | 5.9 | 1.5 | NM | NM | NM | NM | 0.0 | 0.0 | 1.7 | 19.0 | N/A |
| | | 10/03/12 | 62.5% | 0.0% | N/A | 40.0% | 0.1% | 5.0 | 0.5 | NM | NM | NM | NM | 0.0 | 0.0 | 0.7 | 20.2 | N/A |
| | | 01/24/13 | 53.5% | 0.0% | N/A | 45.0% | 0.0% | 2.29 | 0.2 | NM | NM | NM | NM | 0.0 | 0.0 | 0.2 | 20.9 | N/A |
| | 10 ft | 02/15/11 | 52.0% | 0.0% | N/A | 55.1% | 0.0% | 0.0 | 0.4 | 0.0 | 0.0 | 0.0 | 10.0 | 13.1 | OVR | 2.3 | 19.0 | N/A |
| | | 04/21/11 | 52.3% | 0.0% | N/A | 58.2% | 0.0% | 0.0 | 1.2 | 16.0 | 0.0 | 0.0 | 11.8 | 0.2 | 6.0 | 6.5 | 12.1 | N/A |
| | | 07/27/11 | 66.8% | 0.0% | N/A | 49.8% | 0.0% | 0.0 | 2.9 | 21.0 | 0.0 | 0.0 | 0.0 | 0.0 | 0.0 | 9.5 | 6.3 | N/A |
| | | 11/02/11 | 71.0% | 0.0% | N/A | 59.8% | 0.0% | 0.0 | 1.2 | 0.0 | 0.0 | 0.0 | 11.6 | 0.0 | 0.0 | 7.3 | 10.1 | N/A |
| | | 01/25/12 | 59.6% | 0.0% | N/A | 74.2% | 0.0% | 0.3 | 0.3 | 0.0 | 0.0 | 0.0 | 14.6 | 0.0 | 0.0 | 5.7 | 14.4 | N/A |
| | | 04/09/12 | 59.7% | 0.0% | N/A | 53.7% | 0.1% | 2.0 | 0.7 | NM | NM | NM | NM | 0.0 | 0.0 | 1.0 | 19.5 | N/A |
| | | 07/09/12 | 55.0% | 0.0% | N/A | 50.1% | 0.0% | 4.9 | 1.9 | NM | NM | NM | NM | 0.0 | 0.0 | 1.6 | 19.1 | N/A |
| | | 10/03/12 | 60.2% | 0.0% | N/A | 41.0% | 0.0% | 3.0 | 0.6 | NM | NM | NM | NM | 0.0 | 0.0 | 0.9 | 19.8 | N/A |
| | | 01/24/13 | 45.4% | 0.0% | N/A | 47.5% | 0.0% | 1.20 | 0.2 | NM | NM | NM | NM | 0.0 | 0.0 | 0.4 | 20.7 | N/A |
| | 25 ft | 02/15/11 | 54.5% | 0.0% | N/A | 51.9% | 0.0% | 0.0 | 1.2 | 0.0 | 0.0 | 0.0 | 2.1 | 0.0 | 1.0 | 14.9 | 0.6 | N/A |
| | | 04/21/11 | 58.2% | 0.0% | N/A | 53.6% | 0.0% | 0.0 | 0.6 | 13.0 | 0.0 | 0.0 | 2.2 | 0.2 | 0.0 | 13.7 | 2.4 | N/A |
| | | 07/27/11 | 58.7% | 0.0% | N/A | 45.2% | 0.0% | 7.0 | 4.4 | 22.0 | 0.0 | 0.0 | 0.0 | 0.0 | 0.0 | 11.9 | 1.3 | N/A |
| | | 11/02/11 | 59.3% | 0.0% | N/A | 53.6% | 0.0% | | 0.6 | 0.0 | 0.0 | 0.0 | 8.2 | 0.0 | 0.0 | 12.6 | 2.6 | N/A |
| | | 01/25/12 | 52.4% | 0.0% | N/A | NS | 0.0% | 235000 | 0.3 | 1.0 | 0.0 | 0.0 | 5.9 | 0.0 | 0.0 | 11.8 | 6.0 | N/A |
| | | 04/09/12 | 60.0% | 0.0% | N/A | 50.3% | 0.1% | 2.0 | 2.0 | NM | NM | NM | NM | 0.0 | 0.0 | 5.5 | 15.0 | N/A |
| | | 07/10/12 | 55.0% | 0.0% | N/A | 50.0% | 0.0% | 3.2 | 1.5 | N/A | N/A | N/A | N/A | 0.0 | 0.0 | 4.8 | 16.0 | N/A |
| | | 10/03/12 | 62.4% | 0.0% | N/A | 40.0% | 0.0% | 2.0 | 0.7 | NM | NM | NM | NM | 0.0 | 0.0 | 4.0 | 17.5 | N/A |
| | | 01/24/13 | 43.7% | 0.0% | N/A | 45.6% | 0.0% | 0.77 | 0.2 | NM | NM | NM | NM | 0.0 | 0.0 | 3.5 | 18.5 | N/A |
| | 40 ft | 02/15/11 | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS |
| | | 04/21/11 | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS |
| | | 07/27/11 | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS |
| | | 11/02/11 | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS |
| | | 01/25/12 | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS |
| | | 04/09/12 [13] | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS |
| | | 7/10/2012 [11] | 53.1% | 0.0% | N/A | 51.8% | 0.0% | 4.1 | 0.6 | N/A | N/A | N/A | N/A | 0.0 | 0.0 | 6.0 | 12.4 | N/A |
| | | 07/31/12 [13] | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS |
| | | 10/03/12 | 63.4% | 0.0% | N/A | 43.0% | 0.0% | 2.0 | 1.1 | NM | NM | NM | NM | 0.0 | 0.0 | 6.5 | 15.3 | N/A |
| | | 01/24/13 | 67.2% | 0.0% | N/A | 42.0% | 0.6% | 0.82 | 0.2 | NM | NM | NM | NM | 0.0 | 0.0 | 5.9 | 16.8 | N/A |

SEE LAST PAGE OF TABLE FOR NOTES

**TABLE 3**
**SOIL VAPOR SAMPLING - TEDLAR SAMPLING DATA**

| Reading Location | | | Shroud | Tedlar Bag 1 | | Shroud | Tedlar Bag 2 | | | | | | | | | | | Tedlar Bag 3 |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| Instrument | | | Dielectric | | Landtec | Dielectric | | FID | PID | Multi-gas | | | | Landtec | | | | Dielectric |
| Location | Depth | Date | Helium in Shroud Before | Helium Before | CH4 (%) | Helium in Shroud After | Helium After | FID (ppm) | PID (ppm) | CO (ppm) | H2S (ppm) | LEL (%) | O2 (%) | CH4 (%) | LEL (%) | CO2 (%) | O2 (%) | Direct Port Reading After |
| VMP-24 | 5 ft | 02/16/11 | 50.9% | 0.0% | N/A | 50.5% | 0.0% | 0.0 | 0.9 | 3.0 | 0.0 | 0.0 | 16.0 | 0.0 | 0.0 | 6.9 | 13.9 | N/A |
| | | 04/08/11 | 53.5% | 0.0% | N/A | 53.1% | 0.1% | 41.7 | 0.7 | 0.0 | 0.0 | 0.0 | 15.0 | 0.0 | 0.0 | 4.9 | 15.9 | N/A |
| | | 07/28/11 | 73.3% | 0.0% | N/A | 73.3% | 0.0% | 0.0 | 4.2 | 0.0 | 0.0 | 0.0 | 13.5 | 0.0 | 0.0 | 7.7 | 15.6 | N/A |
| | | 11/02/11 | 75.6% | 0.0% | N/A | 52.4% | 0.0% | 0.0 | 1.0 | 0.0 | 0.0 | 0.0 | 14.2 | 0.0 | 0.0 | 8.7 | 12.8 | N/A |
| | | 01/25/12 | 55.5% | 0.0% | N/A | 59.8% | 0.0% | 2.3 | 3.8 | 0.0 | 0.0 | 0.0 | 18.4 | 0.0 | 0.0 | 4.2 | 17.4 | N/A |
| | | 04/09/12 | 69.9% | 0.0% | N/A | 59.8% | 0.1% | 2.8 | 1.5 | NM | NM | NM | NM | 0.0 | 0.0 | 5.2 | 17.5 | N/A |
| | | 07/12/12 | 51.3% | 0.0% | 0.0% | 55.2% | 0.0% | 4.3 | 1.5 | NM | NM | NM | NM | 0.0 | 0.0 | 5.4 | 16.6 | N/A |
| | | 10/19/12[11] | 67.2% | 0.0% | N/A | 37.2% | 0.1% | 1.0 | 0.4 | NM | NM | NM | NM | 0.0 | 0.0 | 4.0 | 18.2 | N/A |
| | | 01/23/13 | 56.5% | 0.0% | N/A | 31.8% | 0.0% | 1.67 | 0.3 | NM | NM | NM | NM | 0.0 | 0.0 | 3.9 | 17.6 | N/A |
| | 10 ft | 02/17/11 | 51.0% | 0.0% | N/A | 59.5% | 0.0% | 0.0 | 0.3 | 0.0 | 0.0 | 0.0 | 20.9 | 0.0 | 0.0 | 0.0 | 19.9 | N/A |
| | | 04/11/11 | 55.5% | 0.0% | N/A | 77.0% | 0.0% | 32.4 | 0.7 | 0.0 | 0.0 | 0.0 | 13.9 | 0.0 | 0.0 | 7.1 | 13.8 | N/A |
| | | 07/28/11 | 63.1% | 0.0% | N/A | 50.7% | 0.0% | 0.0 | 5.2 | 0.0 | 0.0 | 0.0 | 8.6 | 0.0 | 0.0 | 0.1 | 22.6 | N/A |
| | | 11/02/11 | 70.7% | 0.0% | N/A | 48.9% | 0.0% | 0.0 | 0.8 | 0.0 | 0.0 | 0.0 | 13.8 | 0.0 | 0.0 | 9.5 | 12.3 | N/A |
| | | 01/25/12 | 54.3% | 0.0% | N/A | 53.2% | 0.0% | 1.0 | 1.2 | 0.0 | 0.0 | 0.0 | 15.7 | 0.0 | 0.0 | 8 | 13.8 | N/A |
| | | 04/10/12 | 59.1% | 0.0% | NS | 63.8% | 0.0% | 0.0 | 0.5 | NM | NM | NM | NM | 0.0 | 0.0 | 6.4 | 15.9 | N/A |
| | | 07/12/12 | 55.9% | 0.0% | 0.0% | 51.2% | 0.0% | 3.6 | 1.6 | NM | NM | NM | NM | 0.0 | 0.0 | 6.4 | 15.0 | N/A |
| | | 10/09/12 | 43.4% | 0.0% | N/A | 41.0% | 0.0% | 1.0 | 0.6 | NM | NM | NM | NM | 0.0 | 0.0 | 7.4 | 16.0 | N/A |
| | | 01/23/13[9] | 56.9% | 0.0% | N/A | 30.5% | 0.0% | 0.97 | 0.2 | NM | NM | NM | NM | 0.0 | 0.0 | 5.8 | 16.4 | N/A |
| | 22 ft | 02/17/11 | 52.5% | 0.0% | N/A | 50.5% | 0.0% | 0.0 | 0.9 | 4.0 | 0.0 | 0.0 | 11.9 | 0.0 | 2.0 | 10.3 | 10.6 | N/A |
| | | 04/11/11 | 67.8% | 0.0% | N/A | 67.8% | 0.0% | 47.3 | 0.3 | 0.0 | 0.0 | 3.0 | 11.9 | 0.0 | 0.0 | 8.8 | 10.8 | N/A |
| | | 07/28/11 | 52.0% | 0.0% | N/A | 42.6% | 0.0% | 0.0 | 4.3 | 0.0 | 0.0 | 0.0 | 8.4 | 0.0 | 0.0 | 9.7 | 12.4 | N/A |
| | | 11/06/11 | 52.5% | 0.0% | N/A | 50.5% | 0.0% | | 0.2 | 0.0 | 0.0 | 0.0 | 18.3 | 0.0 | 0.0 | 10.1 | 11.8 | N/A |
| | | 01/25/12 | 57.8% | 0.0% | N/A | 72.4% | 0.0% | 25.0 | 3.0 | 0.0 | 0.0 | 0.0 | 18.7 | 0.0 | 0.0 | 8.9 | 13.2 | N/A |
| | | 04/10/12 | 64.3% | 0.0% | N/A | 67.1% | 0.0% | 0.5 | 0.7 | NM | NM | NM | NM | 0.0 | 0.0 | 8.2 | 14.2 | N/A |
| | | 07/12/12 | 52.4% | 0.0% | 0.0% | 53.4% | 0.0% | 2.9 | 1.0 | NM | NM | NM | NM | 0.0 | 0.0 | 6.2 | 14.8 | N/A |
| | | 10/09/12 | 50.3% | 0.0% | N/A | 53.2% | 0.0% | 2.0 | 0.9 | NM | NM | NM | NM | 0.0 | 0.0 | 7.9 | 15.3 | N/A |
| | | 01/23/13 | 52.4% | 0.0% | N/A | 31.9% | 0.0% | 0.48 | 0.2 | NM | NM | NM | NM | 0.0 | 0.0 | 6.5 | 15.9 | N/A |
| | 34 ft | 02/17/11 | 52.2% | 0.0% | N/A | 60.1% | 0.0% | 0.0 | 1.9 | 30.0 | 0.0 | 0.0 | 10.9 | 0.2 | 3.0 | 10.6 | 10.5 | N/A |
| | | 04/11/11 | 70.9% | 0.0% | N/A | 74.4% | 0.0% | 40.5 | 0.1 | 0.0 | 0.0 | 2.0 | 11.1 | 0.0 | 0.0 | 9.2 | 11.0 | N/A |
| | | 07/28/11 | 52.6% | 0.0% | N/A | 38.1% | 0.0% | 0.0 | 5.8 | 2.0 | 0.0 | 0.0 | 8.1 | 0.0 | 0.0 | 9.7 | 12.5 | N/A |
| | | 11/06/11 | 66.1% | 0.0% | N/A | 60.2% | 0.0% | | 0.2 | 0.0 | 0.0 | 0.0 | 15.0 | 0.0 | 0.0 | 8.6 | 12.9 | N/A |
| | | 01/25/12 | 72.1% | 0.0% | N/A | 50.3% | 0.0% | 22.0 | 0.9 | 0.0 | 0.0 | 0.0 | 16.0 | 0.0 | 0.0 | 7.6 | 13.9 | N/A |
| | | 04/10/12 | 60.3% | 0.0% | N/A | 62.3% | 0.1% | 2.0 | 0.9 | NM | NM | NM | NM | 0.0 | 0.0 | 5.6 | 16.6 | N/A |
| | | 07/12/12 | 51.3% | 0.0% | 0% | 59.4% | 0.0% | 3.4 | 1.4 | NM | NM | NM | NM | 0.0 | 0.0 | 5.7 | 16.5 | N/A |
| | | 10/09/12 | 53.0% | 0.0% | N/A | 43.2% | 0.0% | 2.0 | 0.9 | NM | NM | NM | NM | 0.0 | 0.0 | 7.1 | 15.5 | N/A |
| | | 01/23/13 | 53.6% | 0.0% | N/A | 34.2% | 0.0% | 0.52 | 0.2 | NM | NM | NM | NM | 0.0 | 0.0 | 5.2 | 16.7 | N/A |

SEE LAST PAGE OF TABLE FOR NOTES

**TABLE 3**
**SOIL VAPOR SAMPLING - TEDLAR SAMPLING DATA**

| Reading Location | | | Shroud | Tedlar Bag 1 | | Shroud | Tedlar Bag 2 | | | | | | | | | | | Tedlar Bag 3 |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| Instrument | | | Dielectric | | Landtec | Dielectric | | FID | PID | Multi-gas | | | | Landtec | | | | Dielectric |
| Location | Depth | Date | Helium in Shroud Before | Helium Before | CH4 (%) | Helium in Shroud After | Helium After | FID (ppm) | PID (ppm) | CO (ppm) | H2S (ppm) | LEL (%) | O2 (%) | CH4 (%) | LEL (%) | CO2 (%) | O2 (%) | Direct Port Reading After |
| VMP-25 | 5 ft | 03/15/11 | 55.9% | 0.0% | N/A | 53.4% | 0.0% | 159 | 88.2 | 0.0 | 0.0 | 0.0 | 2.0 | 0.0 | 0.0 | 5.0 | 1.8 | N/A |
| | | 04/08/11 | 75.0% | 0.0% | N/A | 51.9% | 0.0% | 95.0 | 1.9 | 0.0 | 0.0 | 3.0 | 0.9 | 0.1 | 2.0 | 7.5 | 1.0 | N/A |
| | | 08/09/11 | 66.0% | 0.0% | 0.0% | 45.2% | 0.0% | 27900 | 2.4 | 4.0 | 0.0 | 0.0 | 16.8 | 0.0 | 0.0 | 16.0 | 2.8 | N/A |
| | | 11/17/11 | 63.9% | 0.0% | N/A | | | 13.0 | 0.4 | 0.0 | 0.0 | 0.0 | 7.2 | 0.0 | 0.0 | 3.4 | 11.4 | N/A |
| | | 01/31/12 | 54.0% | 0.0% | N/A | 53.0% | 0.0% | 0.0 | 0.3 | 0.0 | 0.0 | 0.0 | 11.2 | 0.0 | 0.0 | 2.5 | 11.0 | N/A |
| | | 04/25/12 | 55.2% | 0.0% | N/A | 51.6% | 0.0% | 2.0 | 0.5 | NM | NM | NM | NM | 0.0 | 0.0 | 5.2 | 12.0 | N/A |
| | | 07/26/12 | 60.7% | 0.0% | 0.0% | 55.2% | 0.1% | 2.1 | 0.4 | NM | NM | NM | NM | 0.0 | 0.0 | 10.5 | 6.7 | N/A |
| | | 10/26/12 | 56.9% | 0.0% | N/A | 55.4% | 0.0% | 3.0 | 0.5 | NM | NM | NM | NM | 0.0 | 0.0 | 5.0 | 13.2 | N/A |
| | | 03/06/13 | 55.3% | 0.0% | N/A | 53.2% | 0.0% | 1.16 | 0.2 | NM | NM | NM | NM | 0.0 | 0.0 | 1.9 | 16.1 | N/A |
| | 9.5 ft | 03/15/11 | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS |
| | | 04/08/11 | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS |
| | | 08/09/11 | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS |
| | | 11/17/11 | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS |
| | | 01/31/12 | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS |
| | | 4/25/2012 [13] | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS |
| | | 7/26/12 [13] | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS |
| | | 10/26/12[13] | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS |
| | | 03/06/13[13] | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS |
| | 21 ft | 03/15/11 | 59.6% | 8.2% | OVR | 38.3% | 8.9% | OVR | 268.3 | 182 | 39.0 | OVR | 0.2 | OVR | OVR | 15.3 | 0.6 | 8.6% |
| | | 04/08/11 | 72.4% | 4.1% | OVR | 54.3% | 4.6% | 632000 | 150.0 | OVR | 54.0 | OVR | 0.8 | OVR | OVR | 14.4 | 0.8 | N/A |
| | | 08/09/11 | 58.3% | 11.4% | OVR | 56.9% | 10.2% | OVR | 175.9 | 605 | 68.0 | OVR | 0.0 | OVR | OVR | 14.9 | 1.0 | N/A |
| | | 11/17/11 | 60.3% | 3.6% | OVR | 50.7% | 4.6% | OVR | 125.2 | 380 | 0.0 | OVR | 0.0 | OVR | OVR | 14.4 | 1.1 | N/A |
| | | 01/31/12 | 62.0% | 7.5% | OVR | 52.7% | 8.6% | OVR | 140.2 | 210 | 103 | OVR | 0.9 | OVR | OVR | 14.2 | 0.7 | N/A |
| | | 04/25/12 | 70.2% | 9.3% | OVR | 57.3% | 10.3% | OVR | 83.9 | NM | NM | NM | NM | OVR | OVR | 11.8 | 1.3 | N/A |
| | | 07/26/12 | 71.0% | 8.8% | OVR | 66.0% | 6.9% | OVR | 59.6 | NM | NM | NM | NM | OVR | OVR | 11.7 | 1.6 | N/A |
| | | 10/26/12 | 54.0% | 9.7% | OVR | 54.3% | 9.0% | OVR | 74.85 | NM | NM | NM | NM | OVR | OVR | 14.2 | 4.7 | N/A |
| | | 03/06/13 | 56.4% | 5.6% | OVR | 52.7% | 6.3% | OVR | 45.93 | NM | NM | NM | NM | OVR | OVR | 12.0 | 4.3 | N/A |
| | 31 ft | 03/15/11 | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS |
| | | 04/08/11 | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS |
| | | 08/09/11 | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS |
| | | 11/17/11 | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS |
| | | 01/31/12 | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS |
| | | 4/25/2012 [13] | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS |
| | | 7/26/12 [13] | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS |
| | | 10/26/12[13] | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS |
| | | 03/06/13 | 57.5% | 5.8% | OVR | 54.0% | 7.2% | OVR | 52.14 | NM | NM | NM | NM | OVR | OVR | 12.7 | 1.7 | N/A |

SEE LAST PAGE OF TABLE FOR NOTES

**TABLE 3**
**SOIL VAPOR SAMPLING - TEDLAR SAMPLING DATA**

| Reading Location | | | Shroud | Tedlar Bag 1 | | Shroud | Tedlar Bag 2 | | | | | | | | | | | Tedlar Bag 3 |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| Instrument | | | Dielectric | | Landtec | Dielectric | | FID | PID | Multi-gas | | | | Landtec | | | | Dielectric |
| Location | Depth | Date | Helium in Shroud Before | Helium Before | CH4 (%) | Helium in Shroud After | Helium After | FID (ppm) | PID (ppm) | CO (ppm) | H2S (ppm) | LEL (%) | O2 (%) | CH4 (%) | LEL (%) | CO2 (%) | O2 (%) | Direct Port Reading After |
| VMP-29 | 10 ft | 07/30/12 | 61.9% | 0.0% | N/A | 57.8% | 0.0% | 6.8 | 2.5 | NM | NM | NM | NM | 0.0 | 0.0 | 8.8 | 9.2 | N/A |
| | | 10/08/12 | 52.9% | 0.0% | N/A | 40.5% | 0.0% | 1.0 | 1.7 | NM | NM | NM | NM | 0.0 | 0.0 | 8.1 | 10.6 | N/A |
| | | 02/06/13 | 76.5% | 0.0% | N/A | 63.2% | 0.0% | 0.91 | 0.4 | NM | NM | NM | NM | 0.0 | 0.0 | 1.5 | 19.3 | N/A |
| | 20 ft | 07/30/12 | 65.0% | 0.0% | N/A | 65.5% | 0.1% | 105 | 31.2 | NM | NM | NM | NM | 0.0 | 0.0 | 9.3 | 8.1 | N/A |
| | | 10/08/12 | 54.1% | 0.0% | N/A | 45.6% | 0.0% | 10.0 | 7.3 | NM | NM | NM | NM | 0.0 | 0.0 | 8.8 | 9.4 | N/A |
| | | 02/06/13 | 57.7% | 0.0% | N/A | 66.9% | 0.1% | 2.95 | 0.4 | NM | NM | NM | NM | 0.0 | 0.0 | 0.9 | 19.8 | N/A |
| | 30 ft | 07/30/12 | 68.1% | 0.0% | N/A | 49.6% | 0.0% | 75.0 | 17.2 | NM | NM | NM | NM | 0.0 | 0.0 | 10.3 | 5.7 | N/A |
| | | 10/08/12 | 58.6% | 0.0% | N/A | 48.2% | 0.0% | 13.0 | 10.84 | NM | NM | NM | NM | 0.0 | 0.0 | 11.2 | 6.5 | N/A |
| | | 02/06/13 | 58.7% | 0.0% | N/A | 37.1% | 0.3% | 3.83 | 0.8 | NM | NM | NM | NM | 0.0 | 0.0 | 2.3 | 18.5 | N/A |
| | 40 ft | 7/30/12 [13] | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS |
| | | 10/08/12[13] | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS |
| | | 02/06/13[13] | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS |
| VMP-30 | 10 ft | 07/30/12 | 59.5% | 0.0% | N/A | 54.4% | 0.6% | 27.5 | 19.6 | NM | NM | NM | NM | 0.0 | 0.0 | 4.6 | 14.2 | N/A |
| | | 10/08/12 | 61.8% | 0.0% | N/A | 50.9% | 0.0% | 1.0 | 0.9 | NM | NM | NM | NM | 0.0 | 0.0 | 3.0 | 17.1 | N/A |
| | | 02/06/13 | 52.6% | 0.0% | N/A | 58.8% | 0.0% | 0.39 | 0.1 | NM | NM | NM | NM | 0.0 | 0.0 | 0.1 | 20.9 | N/A |
| | 20 ft | 07/30/12 | 51.2% | 0.0% | N/A | 40.8% | 0.0% | 113 | 40.1 | NM | NM | NM | NM | 0.0 | 0.0 | 11.7 | 3.9 | N/A |
| | | 10/08/12 | 71.5% | 0.0% | N/A | 45.8% | 0.0% | 35.0 | 19.27 | NM | NM | NM | NM | 0.0 | 0.0 | 10.8 | 8.2 | N/A |
| | | 02/06/13 | 53.0% | 0.0% | N/A | 42.4% | 0.0% | 1.39 | 0.2 | NM | NM | NM | NM | 0.0 | 0.0 | 0.8 | 20.2 | N/A |
| | 30 ft | 07/30/12 | 50.4% | 0.0% | N/A | 49.5% | 0.0% | 257 | 105 | NM | NM | NM | NM | 0.0 | 0.0 | 11.7 | 2.6 | N/A |
| | | 10/08/12 | 65.9% | 0.0% | N/A | 40.2% | 0.0% | 42.0 | 21.33 | NM | NM | NM | NM | 0.0 | 0.0 | 13.4 | 5.5 | N/A |
| | | 02/06/13 | 55.5% | 0.0% | N/A | 44.7% | 0.0% | 5.29 | 2.1 | NM | NM | NM | NM | 0.0 | 0.0 | 0.9 | 19.0 | N/A |
| | 40 ft | 7/30/12 [13] | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS |
| | | 10/08/12[13] | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS |
| | | 02/06/13[13] | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS |
| VMP-31 | 5 ft | 04/25/12 | 55.1% | 0.0% | N/A | 63.6% | 0.2% | 3.8 | NS | NM | NM | NM | NM | 0.0 | 0.0 | 0.9 | 18.3 | N/A |
| | | 07/20/12 | 52.8% | 0.0% | N/A | 45.2% | 0.0% | 4.3 | 0.9 | N/A | N/A | N/A | N/A | 0.0 | 0.0 | 0.8 | 18.7 | N/A |
| | | 10/26/12[9] | 53.2% | 0.0% | N/A | 51.7% | 1.1% | 2.0 | 0.4 | NM | NM | NM | NM | 0.0 | 0.0 | 0.7 | 20.2 | N/A |
| | | 02/11/13 | 62.7% | 0.0% | N/A | 54.1% | 0.0% | 0.99 | 0.2 | NM | NM | NM | NM | 0.0 | 0.0 | 0.2 | 20.8 | N/A |
| | 10 ft | 04/24/12 | 52.2% | 0.0% | N/A | 56.4% | 0.4% | 4.2 | NS | NM | NM | NM | NM | 0.0 | 0.0 | 0.9 | 18.2 | N/A |
| | | 7/26/2012[9] | 50.7% | 0.0% | N/A | 59.5% | 0.0% | 6.9 | 0.7 | NM | NM | NM | NM | 0.0 | 0.0 | 1.1 | 19.7 | N/A |
| | | 10/26/12[9] | 54.3% | 1.7% | N/A | 49.0% | 2.7% | 2.0 | 1.0 | NM | NM | NM | NM | 0.0 | 0.0 | 0.6 | 19.9 | N/A |
| | | 02/13/13[9] | 52.9% | 0.0% | 0.0% | 77.2% | 0.2% | 1.56 | 0.2 | NM | NM | NM | NM | 0.0 | 0.0 | 0.1 | 20.4 | N/A |
| | 20 ft | 4/24/2012 [13] | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS |
| | | 7/20/12 [13] | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS |
| | | 10/19/12 | 64.2% | 0.0% | N/A | 56.5% | 0.0% | 2970 | 463 | NM | NM | NM | NM | 3.4 | 71 | 8.4 | 9.5 | N/A |
| | | 02/11/13 | 64.8% | 0.0% | N/A | 53.4% | 0.0% | 255 | 41.45 | NM | NM | NM | NM | 0.5 | 5.0 | 3.4 | 16.5 | N/A |
| | 30 ft | 04/24/12 | 52.5% | 0.0% | N/A | 51.7% | 0.0% | 15000 | NS | NM | NM | NM | NM | 7.7 | OVR | 10.7 | 1.3 | N/A |
| | | 07/20/12 | 57.4% | 0.0% | N/A | 40.0% | 0.0% | 851 | 20.2 | N/A | N/A | N/A | N/A | 0.2 | 6.0 | 9.6 | 6.4 | N/A |
| | | 10/19/12 | 51.2% | 0.0% | N/A | 56.7% | 0.0% | 204 | 19.0 | NM | NM | NM | NM | 0.2 | 3 | 2.8 | 18.5 | N/A |
| | | 02/11/13 | 64.2% | 0.0% | N/A | 52.3% | 0.0% | 4100 | 185 | NM | NM | NM | NM | 11.6 | OVR | 14.2 | 3.7 | N/A |
| VMP-32 | 5 ft | 04/16/12 [9] | 54.2% | 0.0% | 0.0% | 58.2% | 49.5% | NS | NS | NM | NM | NM | NM | NS | NS | NS | NS | N/A |
| | | 04/25/12 | 54.9% | 0.2% | N/A | 52.5% | 1.2% | 0.0 | 0.8 | NM | NM | NM | NM | 0.0 | 0.0 | 0.1 | 20.8 | N/A |
| | | 07/20/12 | 69.4% | 0.0% | 0.0% | 48.1% | 2.0% | 4.1 | 1.3 | NM | NM | NM | NM | 0.0 | 0.0 | 1.2 | 19.4 | N/A |
| | | 10/18/12 | 75.1% | 0.0% | N/A | 50.0% | 0.1% | 2.0 | 0.6 | NM | NM | NM | NM | 0.0 | 0.0 | 0.9 | 18.5 | N/A |
| | | 02/05/13 | 56.4% | 0.0% | N/A | 55.6% | 0.1% | 0.76 | 0.3 | NM | NM | NM | NM | 0.0 | 0.0 | 0.2 | 20.7 | N/A |
| | 10 ft | 04/16/12 | 60.8% | 0.2% | 0.0% | 50.0% | 0.3% | 0.0 | 1.1 | NM | NM | NM | NM | 0.0 | 0.0 | 2.6 | 18.5 | N/A |
| | | 07/20/12 | 58.6% | 0.0% | 0.0% | 48.9% | 1.2% | 2.3 | 1.3 | NM | NM | NM | NM | 0.0 | 0.0 | 3.7 | 16.4 | N/A |
| | | 10/18/12 | 64.9% | 0.0% | N/A | 51.2% | 0.0% | 1.0 | 0.7 | NM | NM | NM | NM | 0.0 | 0.0 | 3.5 | 17.0 | N/A |
| | | 02/05/13 | 48.3% | 0.0% | N/A | 50.0% | 0.0% | 1.4 | 0.2 | NM | NM | NM | NM | 0.0 | 0.0 | 2.7 | 18.3 | N/A |
| | 20 ft | 04/16/12 | 55.5% | 0.0% | 0.0% | 60.8% | 0.2% | 117 | 21.29 | NM | NM | NM | NM | 0.0 | 0.0 | 3.7 | 16.1 | N/A |
| | | 07/20/12 | 55.2% | 0.0% | 0.0% | 52.2% | 0.1% | 2.8 | 1.6 | NM | NM | NM | NM | 0.0 | 0.0 | 4.5 | 15.0 | N/A |
| | | 10/18/12 | 77.5% | 0.0% | N/A | 57.4% | 0.0% | 2.0 | 0.5 | NM | NM | NM | NM | 0.0 | 0.0 | 5.0 | 16.5 | N/A |
| | | 02/05/13 | 50.6% | 0.0% | N/A | 69.7% | 0.0% | 0.4 | 0.3 | NM | NM | NM | NM | 0.0 | 0.0 | 3.9 | 17.1 | N/A |

SEE LAST PAGE OF TABLE FOR NOTES

**TABLE 3**
**SOIL VAPOR SAMPLING - TEDLAR SAMPLING DATA**

| Reading Location | | | Shroud | Tedlar Bag 1 | | Shroud | Tedlar Bag 2 | | | | | | | | | | | Tedlar Bag 3 |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| Instrument | | | Dielectric | | Landtec | Dielectric | | FID | PID | Multi-gas | | | | Landtec | | | | Dielectric |
| Location | Depth | Date | Helium in Shroud Before | Helium Before | CH4 (%) | Helium in Shroud After | Helium After | FID (ppm) | PID (ppm) | CO (ppm) | H2S (ppm) | LEL (%) | O2 (%) | CH4 (%) | LEL (%) | CO2 (%) | O2 (%) | Direct Port Reading After |
| VMP-41 | 30 ft | 04/16/12 | 53.8% | 0.0% | 0.0% | 60.4% | 0.0% | 36660 | 529 | NM | NM | NM | NM | OVR | OVR | 10.5 | 1.0 | N/A |
| | | 07/20/12 | 52.3% | 0.0% | 18.0% | 63.1% | 0.0% | 6000 | 385 | NM | NM | NM | NM | 25.2 | OVR | 9.8 | 1.8 | N/A |
| | | 10/18/12 | 60.2% | 0.0% | N/A | 53.2% | 0.0% | 206 | 13.03 | NM | NM | NM | NM | 0.0 | 1 | 11.1 | 5.5 | N/A |
| | | 02/05/13 | 48.5% | 0.0% | N/A | 60.0% | 0.0% | 165.5 | 37.2 | NM | NM | NM | NM | 0.1 | 3.0 | 12.7 | 3.7 | N/A |
| | 10 ft | 07/27/12 | 58.6% | 0.0% | N/A | 78.0% | 0.1% | 15.1 | 0.4 | NM | NM | NM | NM | 0.0 | 0.0 | 5.1 | 15.0 | N/A |
| | | 10/09/12 | 46.7% | 0.0% | N/A | 42.6% | 0.0% | 1.0 | 0.9 | NM | NM | NM | NM | 0.0 | 0.0 | 4.8 | 15.0 | N/A |
| | | 01/29/13 | 51.1% | 0.0% | N/A | 46.1% | 0.1% | 0.94 | 0.4 | NM | NM | NM | NM | 0.0 | 0.0 | 0.3 | 20.5 | N/A |
| | 20 ft | 07/27/12 | 62.0% | 0.0% | N/A | 62.5% | 0.0% | 2.6 | 0.4 | NM | NM | NM | NM | 0.0 | 0.0 | 7.2 | 12.4 | N/A |
| | | 10/09/12 | 50.6% | 0.0% | N/A | 40.7% | 0.0% | 1.0 | 1.3 | NM | NM | NM | NM | 0.0 | 0.0 | 6.7 | 12.7 | N/A |
| | | 01/29/13 | 55.6% | 0.0% | N/A | 30.3% | 0.0% | 0.52 | 0.3 | NM | NM | NM | NM | 0.0 | 0.0 | 0.8 | 20.2 | N/A |
| | 30 ft | 07/27/12 | 53.2% | 0.0% | N/A | 50.2% | 0.0% | 4.2 | 0.6 | NM | NM | NM | NM | 0.0 | 0.0 | 8.1 | 11.0 | N/A |
| | | 10/09/12 | 46.8% | 0.0% | N/A | 40.5% | 0.0% | 1.0 | 0.7 | NM | NM | NM | NM | 0.0 | 0.0 | 8.8 | 10.0 | N/A |
| | | 01/29/13 | 65.4% | 0.0% | N/A | 41.5% | 0.0% | 0.66 | 0.3 | NM | NM | NM | NM | 0.0 | 0.0 | 2.0 | 19.0 | N/A |
| VMP-42 | 10 ft | 04/18/12 | 52.7% | 0.0% | N/A | 69.5% | 0.1% | 3.0 | 0.6 | NM | NM | NM | NM | 0.0 | 0.0 | 3.5 | 18.0 | N/A |
| | | 07/19/12 | 51.5% | 0.0% | N/A | 72.0% | 0.1% | 1.2 | 0.7 | NM | NM | NM | NM | 0.0 | 0.0 | 1.6 | 19.4 | N/A |
| | | 10/12/12 | 49.2% | 0.0% | N/A | 52.6% | 0.0% | 2.0 | 4.6 | NM | NM | NM | NM | 0.0 | 0.0 | 1.1 | 20.4 | N/A |
| | | 01/31/13 | 52.8% | 0.0% | N/A | 41.9% | 0.0% | 0.68 | 0.2 | NM | NM | NM | NM | 0.0 | 0.0 | 0.6 | 20.6 | N/A |
| | 20 ft | 04/18/12 | 51.5% | 0.0% | N/A | 66.8% | 0.0% | 837 | 39.5 | NM | NM | NM | NM | 0.0 | 0.0 | 10.8 | 5.8 | N/A |
| | | 07/19/12 | 54.0% | 0.0% | N/A | 69.5% | 0.0% | 1.4 | 0.8 | NM | NM | NM | NM | 0.0 | 0.0 | 6.7 | 14.2 | N/A |
| | | 10/12/12 | 64.2% | 0.0% | N/A | 83.0% | 0.2% | 1.0 | 0.9 | NM | NM | NM | NM | 0.0 | 0.0 | 4.1 | 17.7 | N/A |
| | | 01/31/13 | 52.4% | 0.0% | N/A | 41.7% | 0.0% | 0.39 | 0.2 | NM | NM | NM | NM | 0.0 | 0.0 | 3.2 | 18.0 | N/A |
| | 30 ft | 04/19/12 | 54.6% | 0.0% | N/A | 68.5% | 0.0% | 9330 | 160 | NM | NM | NM | NM | 11.5 | OVR | 12.3 | 0.2 | N/A |
| | | 07/19/12 | 51.8% | 0.0% | 0.2% | 64.7% | 0.0% | 550 | 29.4 | NM | NM | NM | NM | 0.3 | 6.0 | 9.2 | 5.4 | N/A |
| | | 10/12/12 | 51.6% | 0.0% | N/A | 65.8% | 0.0% | 15.0 | 2.2 | NM | NM | NM | NM | 0.0 | 0.0 | 8.6 | 12.0 | N/A |
| | | 01/31/13 | 51.5% | 0.0% | N/A | 46.0% | 0.0% | 3.37 | 0.4 | NM | NM | NM | NM | 0.0 | 0.0 | 7.0 | 14.9 | N/A |
| VMP-43 | 10 ft | 04/16/12 | 53.5% | 0.0% | 0.0% | 53.5% | 4.2% | 2.0 | 0.8 | NM | NM | NM | NM | 0.0 | 0.0 | 0.0 | 20.9 | N/A |
| | | 07/19/12 | 67.2% | 0.0% | 0.0% | 65.4% | 2.5% | 2.5 | 0.6 | NM | NM | NM | NM | 0.0 | 0.0 | 1.0 | 19.7 | N/A |
| | | 10/16/12 | 66.3% | 0.0% | N/A | 40.1% | 0.0% | 1.0 | 0.5 | NM | NM | NM | NM | 0.0 | 0.0 | 0.4 | 18.5 | N/A |
| | | 01/24/13[10] | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS |
| | 20 ft | 04/16/12 | 52.5% | 0.0% | 0.1% | 86.0% | 0.1% | 338 | 33.48 | NM | NM | NM | NM | 0.0 | 1.0 | 4.3 | 15.1 | N/A |
| | | 07/19/12 | 67.0% | 0.0% | 0.0% | 50.7% | 0.1% | 37.8 | 7.7 | NM | NM | NM | NM | 0.0 | 0.0 | 2.7 | 17.9 | N/A |
| | | 10/18/12 | 72.1% | 0.0% | N/A | 55.1% | 0.0% | 13.0 | 1.6 | NM | NM | NM | NM | 0.0 | 0.0 | 2.8 | 18.3 | N/A |
| | | 01/24/13 | 52.4% | 0.0% | N/A | 33.5% | 0.0% | 6.75 | 0.5 | NM | NM | NM | NM | 0.0 | 0.0 | 3.0 | 17.4 | N/A |
| | 30 ft | 4/23/2012[9] | 61.2% | 0.0% | N/A | 82.2% | 0.0% | 36.3 | 26.0 | NM | NM | NM | NM | 0.0 | 0.0 | 4.3 | 16.1 | N/A |
| | | 07/19/12 | 66.7% | 0.0% | 0.0% | 52.0% | 0.0% | 10.3 | 1.6 | NM | NM | NM | NM | 0.0 | 0.0 | 2.4 | 18.0 | N/A |
| | | 10/18/12 | 66.5% | 0.0% | N/A | 59.0% | 0.0% | 2.0 | 0.5 | NM | NM | NM | NM | 0.0 | 0.0 | 1.6 | 19.4 | N/A |
| | | 01/24/13 | 51.3% | 0.0% | N/A | 42.5% | 0.0% | 2.25 | 0.3 | NM | NM | NM | NM | 0.0 | 0.0 | 2.0 | 18.8 | N/A |
| VMP-44 | 10 ft | 04/19/12 | 51.5% | 0.0% | N/A | 61.3% | 0.0% | 15900 | 770 | NM | NM | NM | NM | 52.1 | OVR | 9.2 | 5.5 | N/A |
| | | 07/20/12 | 51.0% | 0.0% | N/A | 50.2% | 0.0% | 9340 | 500 | NM | NM | NM | NM | 30.0 | OVR | 14.6 | 3.7 | N/A |
| | | 8/10/2012[14] | 51.6% | 0.0% | N/A | 62.0% | 0.0% | 9450 | 437 | NM | NM | NM | NM | 29.4 | OVR | 13.9 | 5.5 | N/A |
| | | 10/12/12 | 66.7% | 0.8% | NM | 35.0% | 0.7% | 1370 | 245 | NM | NM | NM | NM | 0.9 | 20 | 5.4 | 13.0 | N/A |
| | | 01/25/13 | 76.9% | 0.0% | N/A | 40.5% | 0.1% | 590 | 110 | NM | NM | NM | NM | 1.1 | 18 | 7.6 | 7.7 | N/A |
| | 20 ft | 04/19/12 | 51.0% | 0.0% | N/A | 57.1% | 0.0% | 5420 | 432 | NM | NM | NM | NM | 8.6 | OVR | 11.5 | 1.3 | N/A |
| | | 07/25/12 | 58.2% | 0.0% | N/A | 52.8% | 0.3% | 5200 | 420 | N/A | N/A | N/A | N/A | 9.5 | OVR | 16.1 | 2.2 | N/A |
| | | 10/12/12 | 58.3% | 0.0% | N/A | 52.3% | 0.0% | 1800 | 223 | NM | NM | NM | NM | 1.6 | 32.0 | 7.6 | 12.8 | N/A |
| | | 01/25/13 | 57.0% | 0.0% | N/A | 43.8% | 0.0% | 381 | 48.0 | NM | NM | NM | NM | 0.1 | 3.0 | 9.8 | 7.4 | N/A |
| | 30 ft | 04/19/12 | 63.0% | 0.0% | N/A | 55.8% | 0.0% | 1760 | 140 | NM | NM | NM | NM | 0.5 | 10.0 | 10.2 | 2.1 | N/A |
| | | 07/25/12 | 58.6% | 0.0% | N/A | 52.9% | 0.0% | 127 | 18.3 | N/A | N/A | N/A | N/A | 1.0 | 1.0 | 9.0 | 9.5 | N/A |
| | | 10/15/12 | 60.8% | 0.0% | N/A | 40.2% | 1.8% | 290 | 42.49 | NM | NM | NM | NM | 0.2 | 4 | 5.7 | 15.1 | N/A |
| | | 01/25/13[10] | 52.5% | 1.0% | N/A | 61.0% | 0.1% | 42.90 | 5.5 | NM | NM | NM | NM | 0.0 | 0.0 | 1.5 | 19.2 | N/A |

SEE LAST PAGE OF TABLE FOR NOTES

**TABLE 3**
**SOIL VAPOR SAMPLING - TEDLAR SAMPLING DATA**

| Reading Location | | | Shroud | Tedlar Bag 1 | | Shroud | Tedlar Bag 2 | | | | | | | | | | | Tedlar Bag 3 |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| Instrument | | | Dielectric | | Landtec | Dielectric | | FID | PID | Multi-gas | | | | Landtec | | | | Dielectric |
| Location | Depth | Date | Helium in Shroud Before | Helium Before | CH4 (%) | Helium in Shroud After | Helium After | FID (ppm) | PID (ppm) | CO (ppm) | H2S (ppm) | LEL (%) | O2 (%) | CH4 (%) | LEL (%) | CO2 (%) | O2 (%) | Direct Port Reading After |
| VMP-45 | 10 ft | 04/19/12 | 61.9% | 0.0% | 0.0% | 80.9% | 0.5% | 4.0 | 1.6 | NM | NM | NM | NM | 0.0 | 0.0 | 0.9 | 19.9 | N/A |
| | | 07/19/12 | 65.0% | 0.0% | N/A | 69.7% | 0.4% | 1.0 | 0.6 | NM | NM | NM | NM | 0.0 | 0.0 | 0.7 | 19.6 | N/A |
| | | 10/15/12 | 76.7% | 0.0% | N/A | 43.8% | 0.1% | 1.0 | 0.3 | NM | NM | NM | NM | 0.0 | 0.0 | 0.4 | 20.9 | N/A |
| | | 01/30/13 | 45.9% | 0.0% | N/A | 49.4% | 0.0% | 0.2 | 0.2 | NM | NM | NM | NM | 0.0 | 0.0 | 0.2 | 20.9 | N/A |
| | 20 ft | 04/19/12 | 60.2% | 0.0% | 0.0% | 59.2% | 0.0% | 1300 | 206 | NM | NM | NM | NM | 0.5 | 11.0 | 5.9 | 13.2 | N/A |
| | | 07/19/12 | 67.1% | 0.0% | N/A | 47.6% | 0.0% | 220 | 46.5 | NM | NM | NM | NM | 0.0 | 1.0 | 4.3 | 15.9 | N/A |
| | | 10/15/12 | 51.1% | 1.3% | N/A | 50.5% | 0.1% | 26.0 | 7.0 | NM | NM | NM | NM | 0.0 | 0.0 | 2.6 | 18.7 | N/A |
| | | 01/30/13 | 49.5% | 0.0% | N/A | 59.4% | 0.0% | 17.1 | 1.2 | NM | NM | NM | NM | 0.0 | 0.0 | 2.1 | 18.8 | N/A |
| | 30 ft | 04/19/12 | 52.3% | 0.0% | 9.3% | 51.3% | 0.0% | 9030 | 826 | NM | NM | NM | NM | 17.4 | OVR | 9.9 | 3.9 | N/A |
| | | 07/19/12 | 51.5% | 0.0% | N/A | 51.8% | 0.0% | 610 | 210 | NM | NM | NM | NM | 0.4 | 8.0 | 7.6 | 8.4 | N/A |
| | | 10/15/12 | 54.2% | 0.0% | N/A | 52.2% | 0.1% | 41.0 | 17.9 | NM | NM | NM | NM | 0.0 | 0.0 | 4.2 | 16.4 | N/A |
| | | 01/30/13 | 50.3% | 0.0% | N/A | 37.8% | 0.0% | 55.40 | 10.3 | NM | NM | NM | NM | 0.0 | 0.0 | 3.7 | 17.3 | N/A |
| VMP-47 | 5 ft | 01/21/13 | 65.9% | 0.0% | N/A | 44.0% | 0.0% | 0.48 | 0.3 | NM | NM | NM | NM | 0.0 | 0.0 | 7.9 | 12.6 | N/A |
| | | 01/23/13[16] | N/A | N/A | N/A | N/A | N/A | 62400 | 79.1 | NM | NM | NM | NM | 69.9 | OVR | 11.4 | 2.1 | N/A |
| | 10 ft | 01/21/13 | 73.8% | 0.0% | N/A | 65.1% | 0.0% | 0.98 | 0.3 | NM | NM | NM | NM | 0.0 | 0.0 | 12.8 | 6.6 | N/A |
| | | 01/23/13[16] | N/A | N/A | N/A | N/A | N/A | 0.9 | 36.3 | NM | NM | NM | NM | 0.4 | 8.0 | 12.7 | 2.0 | N/A |
| | 20 ft | 01/21/13 | 64.0% | 0.0% | N/A | 37.0% | 0.0% | 6700 | 108 | NM | NM | NM | NM | 5.6 | OVR | 13.6 | 2.2 | N/A |
| | | 01/23/13[16] | N/A | N/A | N/A | N/A | N/A | 34700 | 92.9 | NM | NM | NM | NM | 43.0 | OVR | 12.6 | 0.8 | N/A |
| | 30 ft | 01/21/13 | 61.5% | 0.0% | N/A | 32.2% | 0.0% | 21600 | 64.2 | NM | NM | NM | NM | 6.7 | OVR | 11.4 | 1.4 | N/A |
| | | 01/23/13[16] | N/A | N/A | N/A | N/A | N/A | 77000 | 73.8 | NM | NM | NM | NM | 82 | OVR | 12.1 | 0.9 | N/A |
| VMP-48 | 5 ft | 02/01/13 | 80.7% | 0.0% | N/A | 47.6% | 0.1% | 0.3 | 0.2 | NM | NM | NM | NM | 0.0 | 0.0 | 0.3 | 20.2 | N/A |
| | 10 ft | 02/01/13 | 62.0% | 0.0% | N/A | 43.0% | 0.0% | 0.5 | 0.4 | NM | NM | NM | NM | 0.0 | 0.0 | 3.1 | 18.0 | N/A |
| | 20 ft | 02/01/13 | 57.0% | 0.0% | N/A | 31.1% | 0.1% | 0.7 | 0.5 | NM | NM | NM | NM | 0.0 | 0.0 | 4.3 | 17.0 | N/A |
| | 30 ft | 02/01/13 | 52.7% | 0.0% | N/A | 40.0% | 0.0% | 35.7 | 3.5 | NM | NM | NM | NM | 0.0 | 0.0 | 11.9 | 0.0 | N/A |
| VMP-49 | 5 ft | 02/01/13 | 48.7% | 0.0% | N/A | 44.9% | 0.1% | 0.4 | 0.2 | NM | NM | NM | NM | 0.0 | 0.0 | 0.8 | 19.9 | N/A |
| | 10 ft | 02/01/13 | 57.6% | 0.0% | N/A | 51.4% | 0.1% | 0.6 | 0.4 | NM | NM | NM | NM | 0.0 | 0.0 | 0.7 | 19.6 | N/A |
| | 20 ft | 02/01/13 | 50.9% | 0.8% | N/A | 51.6% | 0.9% | 0.8 | 0.4 | NM | NM | NM | NM | 0.0 | 0.0 | 0.4 | 20.0 | N/A |
| | 30 ft | 02/01/13 | 58.3% | 0.0% | N/A | 49.4% | 0.0% | 1100 | 26.2 | NM | NM | NM | NM | 0.2 | 4.0 | 13.0 | 2.5 | N/A |
| VMP-50 | 5 ft | 02/01/13 | 49.5% | 0.0% | N/A | 40.8% | 0.4% | 4.4 | 0.3 | NM | NM | NM | NM | 0.0 | 0.0 | 1.1 | 19.9 | N/A |
| | 10 ft | 02/01/13 | 51.3% | 0.0% | N/A | 60.1% | 0.0% | 5.2 | 0.2 | NM | NM | NM | NM | 0.0 | 0.0 | 4.4 | 16.9 | N/A |
| | 20 ft | 02/01/13 | 52.2% | 0.0% | N/A | 58.1% | 0.0% | 242 | 52.0 | NM | NM | NM | NM | 0.2 | 4.0 | 14.1 | 5.3 | N/A |
| | 30 ft | 02/01/13 | 52.6% | 0.0% | N/A | 70.2% | 0.0% | 20800 | 570 | NM | NM | NM | NM | 31.3 | OVR | 8.0 | 14.1 | N/A |
| VMP-51 | 5 ft | 02/01/13 | 50.9% | 0.0% | N/A | 56.0% | 0.0% | 0.5 | 0.2 | NM | NM | NM | NM | 0.0 | 0.0 | 0.4 | 20.2 | N/A |
| | 10 ft | 02/01/13 | 55.5% | 0.0% | N/A | 54.4% | 3.3% | 0.6 | 0.2 | NM | NM | NM | NM | 0.0 | 0.0 | 0.8 | 19.4 | N/A |
| | 20 ft | 02/15/13[11] | 53.2% | 0.0% | N/A | 63.4% | 0.1% | 0.9 | 0.2 | NM | NM | NM | NM | 0.0 | 0.0 | 3.3 | 18.8 | N/A |
| | 30 ft | 02/04/13 | 52.3% | 0.0% | N/A | 53.9% | 0.2% | 0.4 | 0.1 | NM | NM | NM | NM | 0.0 | 0.0 | 4.3 | 18.4 | N/A |
| VMP-52 | 5 ft | 02/04/13 | 52.0% | 0.0% | N/A | 48.0% | 0.0% | 2.1 | 0.1 | NM | NM | NM | NM | 0.0 | 0.0 | 1.1 | 18.3 | N/A |
| | 10 ft | 02/04/13 | 54.3% | 0.0% | N/A | 54.9% | 0.0% | 4.6 | 0.2 | NM | NM | NM | NM | 0.0 | 0.0 | 2.7 | 14.9 | N/A |
| | 20 ft | 02/04/13 | 61.0% | 0.0% | N/A | 52.7% | 0.0% | 5.6 | 0.4 | NM | NM | NM | NM | 0.0 | 0.0 | 6.5 | 13.0 | N/A |
| | 30 ft | 02/04/13 | 55.6% | 0.0% | N/A | 51.3% | 0.0% | 9.9 | 0.6 | NM | NM | NM | NM | 0.0 | 0.0 | 7.2 | 12.0 | N/A |
| VMP-53 | 5 ft | 02/05/13 | 61.2% | 0.0% | N/A | 60.7% | 0.0% | 1.5 | 0.2 | NM | NM | NM | NM | 0.0 | 0.0 | 0.7 | 20.5 | N/A |
| | 10 ft | 02/05/13 | 53.1% | 0.0% | N/A | 52.9% | 0.1% | 0.32 | 0.2 | NM | NM | NM | NM | 0.0 | 0.0 | 0.7 | 20.3 | N/A |
| | 20 ft | 02/05/13 | 55.6% | 0.0% | N/A | 41.8% | 0.1% | 2.3 | 0.3 | NM | NM | NM | NM | 0.0 | 0.0 | 2.2 | 20.1 | N/A |
| | 30 ft | 02/05/13 | 48.6% | 0.0% | N/A | 38.2% | 0.0% | 0.5 | 0.3 | NM | NM | NM | NM | 0.0 | 0.0 | 0.1 | 20.6 | N/A |

SEE LAST PAGE OF TABLE FOR NOTES

**TABLE 3**
**SOIL VAPOR SAMPLING - TEDLAR SAMPLING DATA**

| Reading Location | | | Shroud | Tedlar Bag 1 | | Shroud | Tedlar Bag 2 | | | | | | | | | | | Tedlar Bag 3 |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| Instrument | | | Dielectric | | Landtec | Dielectric | | FID | PID | Multi-gas | | | | Landtec | | | | Dielectric |
| Location | Depth | Date | Helium in Shroud Before | Helium Before | CH4 (%) | Helium in Shroud After | Helium After | FID (ppm) | PID (ppm) | CO (ppm) | H2S (ppm) | LEL (%) | O2 (%) | CH4 (%) | LEL (%) | CO2 (%) | O2 (%) | Direct Port Reading After |
| VMP-54 | 5 ft | 02/06/13 | 60.4% | 0.0% | N/A | 63.4% | 0.1% | 1.8 | 0.2 | NM | NM | NM | NM | 0.1* | 1* | 1.6 | 18.7 | N/A |
| | 10 ft | 02/06/13 | 61.4% | 0.0% | N/A | 60.2% | 0.1% | 0.5 | 0.2 | NM | NM | NM | NM | 0.1* | 1.0* | 3.0 | 17.1 | N/A |
| | 20 ft | 02/06/13 | 64.8% | 0.0% | N/A | 50.2% | 0.1% | 0.5 | 0.2 | NM | NM | NM | NM | 0.1* | 1.0* | 4.6 | 15.1 | N/A |
| | 30 ft | 02/06/13 | 51.0% | 0.0% | N/A | 42.0% | 0.0% | 0.4 | 0.1 | NM | NM | NM | NM | 0.1* | 4.0* | 5.4 | 15.4 | N/A |
| VMP-55 | 5 ft | 02/15/13[13] | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS |
| | 10 ft | 02/15/13[13] | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS |
| | 20 ft | 02/15/13 | 50.8% | 2.5% | OVR | 49.8% | 3.1% | 195000 | 48.6 | NM | NM | NM | NM | OVR | OVR | 17.5 | 1.4 | N/A |
| | 30 ft | 02/15/13[13] | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS | NS |

Notes:
1. November 2009 Sampling and the June 2010 Supplemental utilized a MuitiRAE IR for CO2 readings. Any CO2 over 5% resulted in a "OVR" reading. No direct CH4 or secondary LEL and 02 readings were collected.
2. Flame ionization detection (FID) was not used during the November 2009 Sampling or the June 2010 Supplemental.
3. OVR is used to indicate a reading over range for the FID or MultiRAE.
4. The Landtec landfill gas analyzer displays "OVR" for any results calculated higher than 99.9% for an individual reading.
5. N/A is used to indicate that a reading was not collected because it was unnecessary (i.e., a direct port for helium if the helium leak check was successful).
6. NS is used to indicate that a reading was not collected because the port could not be sampled.
7. NM is used to indicate a reading that was not collected because the MultiGas meter was not used beginning 2Q12.
8. FID readings were taken with a TVA-1000. Due to oxygen concentrations less than 16% a dilution tip was used when analyzing samples. The dilution tip introduced ambient air in a 10:1 ration with the sample, which required the sample readings to be multiplied by 10 to get the actual reading. The FID readings in this spreadsheet illustrate the actual FID values that were represented in each sample.
9. VMP sample port successfully resampled after helium leak check failure.
10. VMP sample port unsuccessfully sampled after three attempts due to helium leak check failures.
11. VMP sample port resampled due to issues with the canister after analyzed by the laboratory.
12. VMP sample port resampled due to issues with the canister in the field.
13. VMP sample port not sampled because screen submerged below water table.
14. VMP sample port resampled to verify results from the laboratory.
15. Negative readings on the FID are recorded as zero.
16. Helium not used to obtain sample.
17. VMP sample port unsuccessfully resampled after integrity issue discovered.
18. * Sample result is suspect.

**TABLE 4**
**SOIL VAPOR SCREENING CRITERIA**

| Chemical | Residential ($mg/m^3$) | Industrial/ Commercial ($mg/m^3$) |
|---|---|---|
| **TO-15 Analytes** | | |
| Acetone | 750,000 | 750,000 |
| Benzene | 0.37 | 2.8 |
| Bromodichloromethane | 450,000 | 450,000 |
| Bromoform | 11.0 | 52.0 |
| Bromomethane | 6.9 | 42.0 |
| 1,3-Butadiene | | |
| 2-Butanone | 6,400 | 40,000 |
| Carbon disulfide | 780 | 5,300 |
| Carbon tetrachloride | 0.21 | 1.5 |
| Chlorobenzene | 69.0 | 420 |
| Chlorodibromomethane | 57,000 | 57,000 |
| Chloroethane | | |
| Chloroform | 0.11 | 0.92 |
| Chloromethane | | |
| Allyl chloride (3-Chloropropene) | | |
| alpha-Chlorotoluene | | |
| Cyclohexane | | |
| 1,2-Dibromo-3-chloropropane (DBCP) | 0.0012 | 0.0062 |
| 1,2-Dibromoethane | 0.011 | 0.06 |
| 1,2-Dichlorobenzene | 290 | 1,700 |
| 1,3-Dichlorobenzene | | |
| 1,4-Dichlorobenzene | 1,200 | 6,800 |
| 1,1-Dichloroethane | 690 | 4,200 |
| 1,2-Dichloroethane | 0.099 | 0.81 |
| 1,1-Dichloroethene | 240 | 1,600 |
| cis-1,2-Dichloroethene | 1,100,000 | 1,100,000 |
| trans-1,2-Dichloroethene | 85.0 | 510 |
| Dichloromethane (Methylene chloride) | 5.6 | 45.0 |
| 1,2-Dichloropropane | 0.062 | 0.46 |
| cis-1,3-Dichloropropene | 0.9 | 6.2 |
| trans-1,3-Dichloropropene | 0.9 | 6.2 |
| 1,4-Dioxane | 0.2 | 2.3 |
| Ethanol | | |
| Ethylbenzene | 1,400 | 8,300 |
| 4-Ethyltoluene | | |
| Freon 11 | | |
| Freon 12 | | |
| Freon 113 | | |
| Freon 114 | | |
| Heptane | | |
| Hexachlorobutadiene | | |
| Hexane | | |
| 2-Hexanone (Methyl N-Butyl Ketone) | | |
| Isopropylbenzene (Cumene) | 600 | 3,500 |
| 4-Methyl-2-pentanone (Methyl Isobutyl Ketone) | | |
| Methyl tert-Butyl Ether (MTBE) | 3,400 | 23,000 |
| n-Propylbenzene | | |
| 2-Propanol | | |
| Styrene | 1,400 | 8,500 |
| Tetrachloroethene | 0.55 | 4.0 |
| 1,1,2,2-Tetrachloroethane | | |
| Tetrahydrofuran | | |
| Toluene | 6,200 | 40,000 |
| 1,2,4-Trichlorobenzene | 11.0 | 50.0 |
| Trichloroethene | 1.5 | 12.0 |
| 1,1,1-Trichloroethane (Methyl chloroform) | 6,600 | 41,000 |
| 1,1,2-Trichloroethane | 170,000 | 170,000 |
| Trichloroflouromethane | 860 | 5,600 |
| 1,2,4-Trimethylbenzene | | |
| 1,3,5-Trimethylbenzene | | |
| 2,2,4-Trimethylpentane | | |
| Vinyl chloride | 0.29 | 4.8 |
| Xylenes (total) | 140 | 840 |
| m,p-Xylene | 130 | 820 |
| o-Xylenes | 120 | 790 |

Note:
1. Screening criteria source: Illinois Pollution Control Board, Notice of Proposed Amendments - Tiered Approach to Corrective Action (TACO) Title 35 - Part 742. Table H: Tier 1 Indoor Inhalation Remediation Objectives for Residential and Industrial/Commercial Properties for the Diffusion and Advection Exposure Route, November 9, 2010.

SEE LAST PAGE OF TABLE FOR NOTES

**TABLE 5**
**CUMULATIVE SUMMARY OF SOIL VAPOR ANALYTICAL DETECTIONS AND SCREENING RESULTS: VILLAGE - VOCS**

| Location | Depth | Sample ID | Sample Date | Acetone | | | alpha-Chlorotoluene | | | Benzene | | | Bromodichloromethane | | | Bromoform | | | Bromomethane | | | 1,3-Butadiene | | | Butane | | | 2-Butanone | | | Carbon disulfide | | | Carbon tetrachloride | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | 750000 | | | | | | 0.37 | | | 450000 | | | 11 | | | 6.9 | | | | | | | | | 6400 | | | 780 | | | 0.21 | | |
| | | | | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals |
| VMP-1 | 5 ft | VMP-1-5-082510 | 8/25/2010 | 0.068 | | | <0.022 | U | | 0.044 | | | <0.028 | U | | <0.044 | U | | <0.016 | U | | <0.0094 | U | | | | | 0.0066 | J | | 0.0035 | J | | <0.027 | U | |
| | | VMP-1-5-111710 | 11/17/2010 | 0.019 | J | | <0.027 | U | | 0.0069 | J | | <0.034 | U | | <0.053 | U | | <0.02 | U | | <0.011 | U | | | | | <0.015 | U | | <0.016 | U | | <0.032 | U | |
| | | VMP-1-5-020411 | 2/4/2011 | 0.42 | J | | <0.52 | U | | 0.14 | J | | <0.68 | U | | <1 | U | | <0.39 | U | | <0.22 | U | | | | | <0.3 | U | | <0.31 | U | | <0.64 | U | |
| | | VMP-1-5-041211 | 4/12/2011 | 0.012 | J | | <0.0068 | U | | 0.6 | | | <0.0088 | U | | <0.014 | U | | <0.0051 | U | | <0.0029 | U | | 0.033 | | | 0.0018 | J | | 0.004 | J | | <0.0083 | U | |
| | | VMP-1-5-080111 | 8/1/2011 | <0.012 | U | | <0.0068 | U | | 0.051 | | | <0.0088 | U | | <0.014 | U | | <0.0051 | U | | <0.0029 | U | | 0.21 | | | 0.017 | | | 0.0086 | J | | <0.0083 | U | |
| | | VMP-1-5-110311 | 11/3/2011 | 110 | | | <18 | U | | <11 | U | | <23 | U | | <36 | U | | <14 | U | | <7.7 | U | | 2000 | | | 3.1 | J | | <44 | U | | <22 | U | |
| | | VMP-1-5-013012 | 1/30/2012 | <2.8 | U | | <1.5 | U | | 0.28 | J | J | <2 | U | | <3 | U | | <1.1 | U | | <0.64 | U | | 3400 | | | <3.4 | U | | <0.91 | U | | <1.8 | U | |
| | | VMP-1-5-041312 | 4/13/2012 | 0.017 | J | | <0.0046 | U | | 0.014 | | | <0.006 | U | | <0.0092 | U | | <0.035 | U | | <0.002 | U | | 0.008 | J | | 0.0065 | J | | <0.011 | J | U | <0.0056 | U | |
| | | VMP-1-5-071612 | 7/16/2012 | 0.078 | | | <0.0047 | U | | 0.084 | | | 0.0018 | J | | <0.0094 | U | | <0.036 | U | UJ | <0.002 | U | | 0.018 | | | 0.068 | | | <0.011 | J | U | <0.0058 | U | |
| | | VMP-1-5-101112 | 10/11/2012 | 0.028 | J | | <0.012 | U | | <0.0073 | U | | <0.015 | U | | <0.024 | U | | <0.0089 | U | | <0.0051 | U | | 2.7 | | | <0.027 | U | | 0.0076 | J | | <0.014 | U | |
| | | [A]VMP-1-5-012113 | 1/21/2013 | 0.32 | J | | <0.13 | U | | 0.015 | J | | <0.17 | U | | <0.27 | U | | 0.074 | J | | <0.057 | U | | 17 | | | <0.3 | U | | <0.32 | U | | <0.16 | U | |
| | | [A]VMP-1-5-012313-R | 1/23/2013 | <11 | U | | <6 | U | | 4.7 | | | <7.8 | U | | <12 | U | | <4.5 | U | | <2.6 | U | | 5900 | | | <14 | U | | <3.6 | U | | <7.3 | U | |
| | 8.5 ft | VMP-1-8.5-082510 | 8/25/2010 | 0.054 | J | | <0.066 | U | | 0.0079 | J | | <0.086 | U | | <0.13 | U | | <0.05 | U | | <0.028 | U | | | | | <0.038 | U | | 0.019 | J | | <0.081 | U | |
| | | VMP-1-8.5-111710 | 11/17/2010 | 0.024 | | | <0.013 | U | | 0.0035 | J | | <0.016 | U | | <0.026 | U | | <0.0096 | U | | <0.0055 | U | | | | | 0.0048 | J | | <0.0077 | U | | <0.016 | U | |
| | | VMP-1-8.5-111710-Dup | 11/17/2010 | 0.016 | J | | <0.013 | U | | 0.0034 | J | | <0.016 | U | | <0.026 | U | | <0.0096 | U | | <0.0055 | U | | | | | 0.0037 | J | | <0.0077 | U | | <0.016 | U | |
| | | VMP-1-8.5-020411 | 2/4/2011 | 0.31 | J | | <1 | U | | 0.26 | J | | <1.3 | U | | <2 | U | | <0.77 | U | | <0.44 | U | | | | | <0.58 | U | | <0.62 | U | | <1.2 | U | |
| | | VMP-1-8.5-041211 | 4/12/2011 | 0.011 | J | | <0.009 | U | | 0.31 | | | <0.012 | U | | <0.018 | U | | <0.0068 | U | | <0.0038 | U | | 0.026 | | | <0.02 | U | | 0.0022 | J | | <0.011 | U | |
| | | VMP-1-8.5-080111 | 8/1/2011 | <6.8 | U | | <3.7 | U | | <2.3 | U | | <4.8 | U | | <7.4 | U | | <2.8 | U | | <1.6 | U | | 840 | | | <8.5 | U | | <2.2 | U | | <4.5 | U | |
| | | VMP-1-8.5-080111-Dup | 8/1/2011 | <6.7 | U | | <3.6 | U | | 6.2 | | | <4.7 | U | | <7.3 | U | | <2.7 | U | | <1.6 | U | | 780 | | | <8.3 | U | | <2.2 | U | | <4.4 | U | |
| | | VMP-1-8.5-110311 | 11/3/2011 | 240 | | | <42 | U | | <26 | U | | <54 | U | | <83 | U | | <31 | U | | <18 | U | | 4800 | | | <95 | U | | 7.3 | J | | <51 | U | |
| | | VMP-1-8.5-013012 | 1/30/2012 | 1.4 | J | | <9 | U | | <5.6 | U | | <12 | U | | <18 | U | | <6.8 | U | | <3.9 | U | | 3600 | | | <21 | U | | <5.4 | U | | <11 | U | |
| | | VMP-1-8.5-041612 | 4/16/2012 | 0.022 | J | | 0.0015 | J | | 0.0083 | | | <0.0071 | U | | <0.011 | U | | <0.041 | U | | <0.0023 | U | | 0.12 | | | 0.0059 | J | | <0.013 | J | U | <0.0067 | U | |
| | | VMP-1-8.5-041612-Dup | 4/16/2012 | 0.02 | J | | <0.0053 | U | | 0.0072 | | | <0.0069 | U | | <0.011 | U | | <0.04 | U | | <0.0023 | U | | 0.12 | | | 0.0054 | J | | <0.013 | J | U | <0.0065 | U | |
| | | VMP-1-8.5-071612 | 7/16/2012 | 0.06 | | | <0.0048 | U | | 0.058 | | | <0.0062 | U | | <0.0095 | U | UJ | <0.002 | U | | <0.0087 | U | | 0.053 | | | <0.011 | J | U | <0.0058 | U | |
| | | VMP-1-8.5-101112 | 10/11/2012 | 0.0066 | J | | <0.0073 | U | | 0.0037 | J | | <0.0094 | U | | <0.014 | U | | <0.055 | U | | <0.0031 | U | | 0.07 | | | <0.017 | U | | <0.018 | J | U | <0.0089 | U | |
| | | [A]VMP-1-8.5-012113 | 1/21/2013 | <0.6 | U | | <0.13 | U | | <0.08 | U | | <0.17 | U | | <0.26 | U | | <0.97 | U | | <0.055 | U | | 57 | | | <0.3 | U | | <0.31 | U | | <0.16 | U | |
| | | [A]VMP-1-8.5-012313-R | 1/23/2013 | <0.22 | U | | <0.12 | U | | 0.05 | J | | <0.16 | U | | <0.24 | U | | <0.09 | U | | <0.052 | U | | 260 | | | <0.27 | U | | <0.072 | U | | <0.15 | U | |
| | 23.5 ft | VMP - 1 - 23.5 - 083010 | 8/30/2010 | <4.3 | U | | <2.3 | U | | 1.4 | | | <3 | U | | <4.6 | U | | <1.7 | U | | <0.99 | U | | | | | <1.3 | U | | <1.4 | U | | <2.8 | U | |
| | | VMP-1-23.5-111810 | 11/17/2010 | 0.011 | J | | <0.0064 | U | | 0.0014 | J | | <0.0083 | U | | <0.013 | U | | <0.0048 | U | | <0.0027 | U | | | | | 0.0012 | J | | <0.0038 | U | | 0.0013 | J | |
| | | VMP-1-23.5-020411 | 2/4/2011 | 3 | J | | <6 | U | | <3.7 | U | | <7.8 | U | | <12 | U | | <4.5 | U | | <2.6 | U | | | | | <3.4 | U | | <3.6 | U | | <7.3 | U | |
| | | VMP-1-23.5-041211 | 4/12/2011 | 9.8 | J | | <9.8 | U | | <6.1 | U | | <13 | U | | <20 | U | | <7.4 | U | | <4.2 | U | | 1300 | | | <22 | U | | 5.1 | J | | <12 | U | |
| | | VMP-1-23.5-041211-DUP | 4/12/2011 | 8 | J | | <12 | U | | <7.7 | U | | <16 | U | | <25 | U | | <9.3 | U | | <5.3 | U | | 1700 | | | <28 | U | | 4.2 | J | | <15 | U | |
| | | VMP-1-23.5-080111 | 8/1/2011 | <120 | U | | <67 | U | | <41 | U | | <86 | U | | <130 | U | | <50 | U | | <28 | U | | 25000 | | | <150 | U | | 6.2 | J | | <81 | U | |
| | | VMP-1-23.5-110611 | 11/6/2011 | 9.5 | J | | <16 | U | | <9.7 | U | | <20 | U | | 3.9 | J | | <12 | U | | <6.7 | U | | 9400 | | | 6 | J | | 7.6 | J | | <19 | U | |
| | | VMP-1-23.5-013112 | 1/31/2012 | <57 | U | | <120 | U | | <19 | U | | <40 | U | | <250 | U | | <23 | U | | <13 | U | | 7200 | | | <71 | U | | <19 | U | | <38 | U | |
| | | VMP-1-23.5-041612 | 4/16/2012 | 0.68 | J | | <2.5 | U | | <1.5 | U | | <3.2 | U | | <4.9 | U | | <1.8 | U | | <1 | U | | 800 | | | <5.6 | U | | <1.5 | U | | <3 | U | |
| | | VMP-1-23.5-071612 | 7/16/2012 | <57 | U | | <31 | U | | <19 | U | | <40 | U | | <62 | U | | <23 | U | | <13 | U | | 11000 | | | <71 | U | | <19 | U | | <38 | U | |
| | | VMP-1-23.5-102412 | 10/24/2012 | <110 | U | | <62 | U | | <38 | U | | <81 | U | | <120 | U | | <47 | U | | <27 | U | | 4200 | | | <140 | U | | <38 | U | | <76 | U | |
| | | [A]VMP-1-23.5-012113 | 1/21/2013 | <0.32 | U | UJ | <0.07 | U | UJ | 0.0088 | J | J | <0.09 | U | UJ | <0.14 | U | UJ | <0.52 | U | UJ | <0.03 | U | UJ | 12 | | J | <0.16 | U | UJ | <0.17 | U | UJ | <0.085 | U | UJ |
| | | [A]VMP-1-23.5-012313-R | 1/23/2013 | <150 | U | | <83 | U | | 14 | J | | <110 | U | | <170 | U | | <62 | U | | <36 | U | | 33000 | | | <190 | U | | <50 | U | | <100 | U | |
| | 38.5 ft | VMP-1-38.5-073112 | 7/31/2012 | 0.14 | | | <0.0048 | U | | 0.042 | | | <0.0063 | U | | <0.0097 | U | | <0.036 | U | | <0.0021 | U | | 0.0028 | J | | 0.022 | | | <0.012 | U | | <0.0059 | U | |
| | | VMP-1-38.5-102612 | 10/26/2012 | <6.2 | U | | <3.4 | U | | 0.71 | J | | <4.4 | U | | <6.7 | U | | <2.5 | U | | <1.4 | U | | 4200 | | | <7.7 | U | | <2 | U | | <4.1 | U | |
| | | [A]VMP-1-38.5-012113 | 1/21/2013 | 0.02 | J | J | <0.046 | U | UJ | 0.01 | J | J | <0.059 | U | UJ | <0.091 | U | UJ | 0.024 | J | J | <0.019 | U | UJ | 9.2 | | J | <0.1 | U | UJ | <0.11 | U | UJ | <0.055 | U | UJ |
| | | [A]VMP-1-38.5-012313-R | 1/23/2013 | <110 | U | | <62 | U | | 11 | J | | <80 | U | | <120 | U | | <46 | U | | <26 | U | | 21000 | | | <140 | U | | <37 | U | | <75 | U | |
| VMP-2 | | VMP - 2 - 5 - 083110 | 8/31/2010 | <4.3 | U | | <2.3 | U | | 0.89 | J | | <3 | U | | <4.6 | U | | <1.7 | U | | <0.99 | U | | | | | <1.3 | U | | <1.4 | U | | <2.8 | U | |
| | 5 ft | VMP-2-5-111610 | 11/16/2010 | <6.3 | U | | <3.4 | U | | <2.1 | U | | <4.4 | U | | <6.8 | U | | <2.6 | U | | <1.5 | U | | | | | <1.9 | U | | <2 | U | | <4.2 | U | |
| | | VMP-2-5-020411 | 2/4/2011 | 0.45 | J | | <0.89 | U | | <0.55 | U | | <1.2 | U | | <1.8 | U | | <0.67 | U | | <0.38 | U | | | | | <0.51 | U | | <0.54 | U | | <1.1 | U | |
| | | VMP-2-5-041311 | 4/13/2011 | 0.012 | J | | <0.0072 | U | | 0.33 | | | <0.0093 | U | | <0.014 | U | | <0.0054 | U | | <0.0031 | U | | 0.1 | | | <0.016 | U | | 0.0038 | J | | <0.0087 | U | |
| | | VMP-2-5-080211 | 8/2/2011 | <14 | U | | <7.5 | U | | <4.6 | U | | <9.7 | U | | <15 | U | | <5.6 | U | | <3.2 | U | | 2200 | | | <17 | U | | <4.5 | U | | <9.1 | U | |
| | | VMP-2-5-110711 | 11/7/2011 | 0.02 | | | <0.0044 | U | | 0.0025 | J | | <0.0057 | U | | <0.0088 | J | U | <0.0033 | U | | <0.0019 | U | | <0.0081 | U | | 0.0051 | J | | <0.011 | J | U | <0.0054 | U | |
| | | VMP-2-5-012512 | 1/25/2012 | 3.8 | | | <0.5 | U | | 0.23 | J | | <0.65 | U | | <1 | U | | <0.38 | U | | <0.21 | U | | <0.92 | U | | 0.98 | J | | 2.3 | | | <0.61 | U | |
| | | VMP-2-5-042512 | 4/25/2012 | 0.055 | J | | <0.02 | U | | 0.18 | | | <0.026 | U | | <0.039 | U | | <0.15 | U | | <0.0084 | U | | 0.066 | | | 0.047 | | | 0.0075 | J | | <0.024 | U | |
| | | VMP-2-5-071612 | 7/16/2012 | 0.12 | | | <0.0048 | U | | 0.067 | | | <0.0062 | U | | <0.0096 | U | | <0.036 | U | UJ | <0.002 | U | | 0.4 | | | 0.066 | | | <0.012 | J | U | <0.0058 | U | |
| | | VMP-2-5-102412 | 10/24/2012 | 0.077 | | | <0.0074 | U | | 0.17 | | | <0.0096 | U | | <0.015 | U | | <0.056 | U | | <0.0032 | U | | 0.012 | J | | 0.034 | | | <0.018 | J | U | <0.009 | U | |
| | | VMP-2-5-013113 | 1/31/2013 | 0.013 | J | | <0.0071 | U | | 0.0026 | J | | <0.0092 | U | | <0.014 | U | | <0.054 | U | | <0.003 | U | | 0.023 | | | <0.016 | U | | <0.017 | J | U | <0.0087 | U | |
| | 8.5 ft | VMP-2-8.5-083110 | 8/31/2010 | <4.4 | U | | <2.4 | U | | 1.4 | | | <3.1 | U | | <4.8 | U | | <1.8 | U | | <1 | U | | | | | <1.4 | U | | <1.4 | U | | <2.9 | U | |
| | | VMP-2-8.5-111610 | 11/16/2010 | <12 | U | | <6.5 | U | | <4 | U | | <8.4 | U | | <13 | U | | <4.9 | U | | <2.8 | U | | | | | <3.7 | U | | <3.9 | U | | <7.9 | U | |
| | | VMP-2-8.5-020411 | 2/4/2011 | 0.56 | J | | <2.2 | U | | <1.4 | U | | <2.9 | U | | <4.4 | U | | <1.7 | U | | <0.95 | U | | | | | <1.3 | U | | <1.3 | U | | <2.7 | U | |
| | | VMP-2-8.5-041311 | 4/13/2011 | <1.2 | U | | <0.68 | U | | 1.1 | | | <0.88 | U | | <1.4 | U | | 0.24 | J | | <0.29 | U | | 1.5 | | | <1.6 | U | | 0.36 | J | | 0.12 | J | J |
| | | VMP-2-8.5-080211 | 8/2/2011 | 12 | J | | <27 | U | | <17 | U | | <36 | U | | <55 | U | | <20 | U | | <12 | U | | 4200 | | | <62 | U | | 8 | J | | <33 | U | |
| | | VMP-2-8.5-110711 | 11/7/2011 | <0.11 | U | | <0.059 | U | | <0.036 | U | | <0.076 | U | | <0.12 | U | | <0.044 | U | | <0.025 | U | | <0.11 | U | | <0.13 | U | | <0.14 | U | | <0.072 | U | |
| | | VMP-2-8.5-012612 | 1/26/2012 | <4.8 | U | | <10 | U | | 0.53 | J | | <3.4 | U | | <21 | U | | <2 | U | | <1.1 | U | | 320 | | | <6 | U | | <1.6 | U | | <3.2 | U | |
| | | VMP-2-8.5-012612-DUP | 1/26/2012 | 0.37 | J | J | <10 | U | | 0.79 | J | | <3.4 | U | | <21 | U | | <2 | U | | <1.1 | U | | 370 | | J | <6 | U | | <1.6 | U | | <3.2 | U | |
| | | VMP-2-8.5-041612 | 4/16/2012 | 0.018 | J | | <0.0051 | U | | 0.012 | | | <0.0066 | U | | <0.01 | U | | <0.038 | U | | <0.0022 | U | | 0.03 | | J | 0.0056 | J | | <0.012 | J | U | <0.0062 | U | |
| | | VMP-2-8.5-041612-Dup | 4/16/2012 | 0.032 | | | <0.0052 | U | | 0.013 | | | <0.0067 | U | | <0.01 | U | | <0.039 | U | | <0.0022 | U | | 0.0096 | | J | 0.0062 | J | | <0.012 | J | U | <0.0063 | U | |
| | | VMP-2-8.5-071612 | 7/16/2012 | 0.047 | | | <0.0058 | U | | 0.087 | | | <0.0075 | U | | <0.012 | U | | <0.043 | U | UJ | <0.0025 | U | | 0.077 | | J | 0.024 | | | <0.014 | J | U | <0.007 | U | |
| | | VMP-2-8.5-071612-Dup | 7/16/2012 | 0.071 | | | <0.0048 | U | | 0.084 | | | <0.0062 | U | | <0.0095 | U | | 0.0039 | J | J | <0.002 | U | | 0.02 | | J | 0.028 | | | <0.011 | J | U | <0.0058 | U | |
| | | VMP-2-8.5-102312 | 10/23/2012 | 0.052 | | | <0.0075 | U | | 0.014 | | | <0.0097 | U | | <0.015 | U | | <0.056 | U | | <0.0032 | U | | 0.58 | | | 0.01 | J | | <0.018 | U | | <0.0092 | U | |
| | | VMP-2-8.5-020513 | 2/5/2013 | 0.006 | J | | <0.0077 | U | | 0.0022 | J | | <0.0099 | U | | <0.015 | U | | <0.057 | U | | <0.0033 | U | | 0.038 | | | <0.017 | U | | <0.018 | J | U | <0.0093 | U | |
| | 22 ft | VMP-2-22-083110 | 8/31/2010 | <6.7 | U | | <3.6 | U | | 1.7 | J | | <4.7 | U | | <7.3 | U | | <2.7 | U | | <1.6 | U | | | | | <2.1 | U | | <2.2 | U | | <4.4 | U | |
| | | VMP-2-22-111610 | 11/16/2010 | <12 | U | | <6.8 | U | | <4.2 | U | | <8.8 | U | | <14 | U | | <5.1 | U | | <2.9 | U | | | | | <3.9 | U | | <4.1 | U | | <8.3 | U | |
| | | VMP-2-22-020411 | 2/4/2011 | 1.4 | J | | <3.1 | U | | 0.75 | J | | <4 | U | | <6.2 | U | | <2.3 | U | | <1.3 | U | | | | | <1.8 | U | | <1.8 | U | | <3.7 | U | |
| | | VMP-2-22-041311 | 4/13/2011 | <16 | U | | <9 | U | | 1 | J | | <12 | U | | <18 | U | | <6.8 | U | | <3.9 | U | | 410 | | | <20 | U | | <22 | U | | <11 | U | |
| | | VMP-2-22-080211 | 8/2/2011 | <67 | U | | <36 | U | | <22 | U | | <47 | U | | <73 | U | | <27 | U | | <16 | U | | 4900 | | | <83 | U | | <22 | U | | <44 | U | |
| | | VMP-2-22-110711 | 11/7/2011 | 29 | | J | <1.9 | U | | 0.24 | J | | <2.5 | U | | <3.9 | U | | <1.4 | U | | <0.83 | U | | 230 | | | 0.37 | J | | <4.6 | U | | <2.4 | U | |
| | | VMP-2-22-012612 | 1/26/2012 | <7.4 | U | | <16 | U | | 0.74 | J | J | <5.2 | U | | <32 | U | | <3 | U | | <1.7 | U | | 500 | | J | <9.1 | U | | <2.4 | U | | <4.9 | U | |
| | | VMP-2-22-042712 | 4/27/2012 | 0.014 | J | | 0.00074 | J | | 0.079 | | | <0.0054 | U | | <0.0083 | U | | 0.0056 | J | | <0.0018 | U | | 0.0086 | | | 0.015 | | | <0.01 | J | U | <0.0051 | U | |
| | | VMP-2-22-071612 | 7/16/2012 | 0.13 | | | <0.0049 | U | | 0.19 | | | <0.0064 | U | | <0.0098 | U | | 0.0012 | J | J | <0.0021 | U | | 0.042 | | | 0.054 | | | <0.012 | J | U | <0.006 | U | |
| | | VMP-2-22-102312 | 10/23/2012 | 0.055 | | | <0.0075 | U | | 0.0066 | | | <0.0097 | U | | <0.015 | U | | <0.056 | U | | <0.0032 | U | | 0.079 | | | 0.006 | J | | <0.018 | J | U | <0.0092 | U | |
| | | VMP-2-22-013113 | 1/31/2013 | 0.01 | J | | <0.007 | U | | 0.0018 | J | | <0.009 | U | | <0.014 | U | | <0.052 | U | | <0.003 | U | | 0.0043 | J | | <0.016 | U | | 0.002 | J | | <0.0085 | U | |
| | 42 ft | VMP-2-42-013113 | 1/31/2013 | 350 | | | 22 | J | | <42 | U | | <87 | U | | <130 | U | | <500 | U | | <29 | U | | 20000 | | | <150 | U | | 30 | J | | <82 | U | |

SEE LAST PAGE OF TABLE FOR NOTES

**TABLE 5**
**CUMULATIVE SUMMARY OF SOIL VAPOR ANALYTICAL DETECTIONS AND SCREENING RESULTS: VILLAGE - VOCS**

| Location | Depth | Sample ID | Sample Date | Acetone | | | alpha-Chlorotoluene | | | Benzene | | | Bromodichloromethane | | | Bromoform | | | Bromomethane | | | 1,3-Butadiene | | | Butane | | | 2-Butanone | | | Carbon disulfide | | | Carbon tetrachloride | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | 750000 | | | | | | 0.37 | | | 450000 | | | 11 | | | 6.9 | | | | | | | | | 6400 | | | 780 | | | 0.21 | | |
| | | | | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals |
| VMP-3 | 5 ft | VMP-3-5-090910 | 9/9/2010 | <13 | U | | <6.9 | U | | 7.8 | | | <8.9 | U | | <14 | U | | <5.2 | U | | <2.9 | U | | | | | <3.9 | U | | <4.1 | U | | <8.4 | U | |
| | | VMP-3-5-112210 | 11/22/2010 | 3.1 | J | | <7 | U | | 2.8 | J | | <9 | U | | <14 | U | | <5.2 | U | | <3 | U | | | | | <4 | U | | <4.2 | U | | 3.7 | J | |
| | | VMP-3-5-020911 | 2/9/2011 | <5.7 | U | | <3.1 | U | | <1.9 | U | | <4 | U | | <6.2 | U | | <2.3 | U | | <1.3 | U | | | | | <1.8 | U | | <1.9 | U | | <3.8 | U | |
| | | VMP-3-5-041411 | 4/14/2011 | <62 | U | | <34 | U | | <21 | U | | <44 | U | | <67 | U | | <25 | U | | <14 | U | | 9600 | | | <77 | U | | <20 | U | | <41 | U | |
| | | VMP-3-5-080211 | 8/2/2011 | <0.015 | U | | <0.008 | U | | 0.15 | | | <0.01 | U | | <0.016 | U | | <0.006 | U | | <0.0034 | U | | 0.1 | | | 0.018 | | | 0.007 | J | | <0.0098 | U | |
| | | VMP-3-5-110811 | 11/8/2011 | 0.025 | | | <0.0044 | U | | 0.00065 | J | | <0.0057 | U | | <0.0088 | U | | <0.0033 | U | | <0.0019 | U | | <0.0081 | U | | 0.0046 | J | | <0.011 | U | | <0.0054 | U | |
| | | VMP-3-5-110811-DUP | 11/8/2011 | 0.018 | | | <0.0045 | U | | 0.0006 | J | | <0.0059 | U | | <0.009 | U | | <0.0034 | U | | <0.0019 | U | | 0.0091 | | | 0.0036 | J | | <0.011 | U | | <0.0055 | U | |
| | | VMP-3-5-012712 | 1/27/2012 | <4.2 | U | | <9 | U | | 0.63 | J | | <2.9 | U | | <18 | U | | <1.7 | U | | <0.97 | U | | 460 | | | <5.2 | U | | <1.4 | U | | <2.8 | U | |
| | | VMP-3-5-041912 | 4/19/2012 | 0.078 | | | <0.0049 | U | | 0.086 | | | <0.0064 | U | | <0.0099 | U | | <0.037 | U | | <0.0021 | U | | 0.007 | J | | 0.068 | | | <0.012 | J | U | <0.006 | U | |
| | | VMP-3-5-072712 | 7/27/2012 | 0.11 | | | <0.0052 | U | | 0.13 | | | 0.00097 | J | | <0.01 | U | | <0.039 | U | | <0.0022 | U | | 0.0047 | J | | 0.026 | | | 0.013 | | J | 0.0032 | J | |
| | 10 ft | VMP-3-10 | 6/21/2010 | <14 | U | | <7.8 | U | | 8.6 | | | <10 | U | | <16 | U | | <5.9 | U | | <3.4 | U | | | | | <4.5 | U | | <4.7 | U | | <9.5 | U | |
| | | VMP-3-10-091010 | 9/10/2010 | 8.9 | J | | <22 | U | | 14 | | | <28 | U | | <44 | U | | <16 | U | | <9.4 | U | | | | | <12 | U | | <13 | U | | <27 | U | |
| | | VMP-3-10-092010 | 9/20/2010 | <29 | U | | <16 | U | | 9 | J | | <21 | U | | <32 | U | | <12 | U | | <6.8 | U | | | | | <9.1 | U | | <9.6 | U | | <20 | U | |
| | | VMP-3-10-112210 | 11/22/2010 | <12 | U | | <6.8 | U | | 18 | | | <8.8 | U | | <14 | U | | <5.1 | U | | <2.9 | U | | | | | <3.9 | U | | <4.1 | U | | <8.3 | U | |
| | | VMP-3-10-112210-Dup | 11/22/2010 | <17 | U | | <9.5 | U | | 15 | | | <12 | U | | <19 | U | | <7.1 | U | | <4.1 | U | | | | | <5.4 | U | | <5.7 | U | | <12 | U | |
| | | VMP-3-10-020811 | 2/8/2011 | 6.7 | J | | <10 | U | | 13 | | | <13 | U | | <20 | U | | <7.5 | U | | <4.3 | U | | | | | <5.7 | U | | <6 | U | | <12 | U | |
| | | VMP-3-10-041311 | 4/13/2011 | <110 | U | | <58 | U | | <36 | U | | <75 | U | | <120 | U | | <44 | U | | <25 | U | | 19000 | | | <130 | U | | <35 | U | | <71 | U | |
| | | VMP-3-10-080311 | 8/3/2011 | <0.13 | U | | <0.074 | U | | 0.068 | | | <0.095 | U | | <0.15 | U | | <0.055 | U | | <0.031 | U | | 26 | E | J | <0.17 | U | | 0.038 | J | | <0.089 | U | |
| | | VMP-3-10-110811 | 11/8/2011 | 0.068 | | J | <0.006 | U | | 0.0011 | J | | <0.0078 | U | | <0.012 | U | | 0.002 | J | | <0.0026 | U | | 0.31 | | | 0.0056 | J | | 0.013 | J | | <0.0073 | U | |
| | | VMP-3-10-012712 | 1/27/2012 | <0.08 | J | U | <0.17 | U | | 0.091 | | | <0.056 | U | | <0.35 | U | | <0.033 | U | | <0.018 | U | | 6.9 | | | <0.099 | U | | <0.026 | U | | <0.053 | U | |
| | | VMP-3-10-042012 | 4/20/2012 | 0.023 | | | <0.0044 | J | U | 0.027 | | | <0.0057 | J | U | 0.0019 | J | | <0.033 | U | | <0.0019 | U | | 0.047 | | | 0.025 | | | <0.011 | J | U | <0.0054 | U | |
| | | VMP-3-10-072312 | 7/23/2012 | 0.078 | | | <0.0052 | J | U | 0.0049 | | | <0.0067 | U | | <0.01 | U | | <0.039 | U | | <0.0022 | U | | 0.06 | | | 0.013 | | | <0.012 | U | | <0.0063 | U | |
| | | VMP-3-10-101812 | 10/18/2012 | 0.029 | J | | <0.0078 | U | | 0.066 | | | <0.01 | U | | <0.016 | U | | <0.059 | U | | <0.0034 | U | | 0.0048 | J | | 0.008 | J | | <0.019 | U | | <0.0095 | U | |
| | | VMP-3-10-020613 | 2/6/2013 | 0.012 | J | | <0.0073 | U | | <0.0045 | U | | <0.0094 | U | | <0.014 | U | | <0.055 | U | | <0.0031 | U | | <0.013 | U | | <0.017 | U | | <0.018 | J | U | <0.0089 | U | |
| | 22 ft | VMP-3-22-092010 | 9/20/2010 | <39 | U | | <21 | U | | 34 | | | <27 | U | | <42 | U | | <16 | U | | <9 | U | | | | | <12 | U | | <13 | U | | <26 | U | |
| | | VMP-3-22-112210 | 11/22/2010 | <44 | U | | <24 | U | | 36 | | | <31 | U | | <48 | U | | <18 | U | | <10 | U | | | | | <14 | U | | <14 | U | | <29 | U | |
| | | VMP-3-22-020811 | 2/8/2011 | 14 | J | | <12 | U | | 26 | | | <15 | U | | <24 | U | | <8.9 | U | | <5.1 | U | | | | | <6.8 | U | | <7.1 | U | | <14 | U | |
| | | VMP-3-22-041511 | 4/15/2011 | <120 | U | | <64 | U | | 26 | J | | <83 | U | | <130 | U | | <48 | U | | <27 | U | | 24000 | | | <150 | U | | <39 | U | | <78 | U | |
| | | VMP-3-22-080611 | 8/6/2011 | 0.075 | J | | <0.1 | U | | 0.22 | | | <0.13 | U | | <0.2 | U | | <0.077 | U | | <0.044 | U | | 18 | | | <0.23 | U | | <0.062 | U | | <0.12 | U | |
| | | VMP-3-22-110811 | 11/8/2011 | 0.037 | | J | <0.0045 | U | | 0.003 | | | <0.0059 | U | | <0.009 | U | | <0.0034 | U | | <0.0019 | U | | 0.13 | | | 0.0051 | J | | <0.011 | U | | <0.0055 | U | |
| | | VMP-3-22-013012 | 1/30/2012 | 0.033 | | | <0.018 | U | | 0.12 | | | <0.023 | U | | <0.036 | U | | <0.014 | U | | <0.0077 | U | | 1.9 | | | 0.018 | J | | <0.044 | J | U | <0.022 | U | |
| | | VMP-3-22-042012 | 4/20/2012 | 0.025 | | | <0.0045 | J | U | 0.028 | | | <0.0059 | U | | <0.009 | U | | <0.034 | J | U | <0.0019 | U | | 0.052 | | | 0.025 | | | <0.011 | J | U | <0.0055 | U | |
| | | VMP-3-22-072312 | 7/23/2012 | 0.051 | | | <0.0051 | J | U | 0.0093 | | | <0.0066 | U | | <0.01 | U | | <0.038 | U | | <0.0022 | U | | 0.012 | | | 0.0079 | J | | <0.012 | U | | <0.0062 | U | |
| | | VMP-3-22-101812 | 10/18/2012 | 0.034 | J | | <0.0077 | U | | 0.14 | | | <0.0099 | U | | <0.015 | U | | <0.057 | U | | <0.0033 | U | | 0.018 | | | 0.013 | J | | <0.018 | U | | <0.0093 | U | |
| | | VMP-3-22-020613 | 2/6/2013 | 0.019 | J | | <0.0075 | U | | 0.052 | | | <0.0097 | U | | <0.015 | U | | <0.056 | U | | <0.0032 | U | | 0.006 | J | | <0.017 | U | | <0.018 | J | U | <0.0091 | U | |
| | 31.5 ft | VMP-3-31.5-090910 | 9/9/2010 | <72 | U | | <39 | U | | 210 | | | <51 | U | | <78 | U | | <30 | U | | <17 | U | | | | | <22 | U | | <24 | U | | <48 | U | |
| | | VMP-3-31.5-112210 | 11/22/2010 | <50 | U | | <27 | U | | 180 | | | <36 | U | | <55 | U | | <20 | U | | <12 | U | | | | | <16 | U | | <16 | U | | <33 | U | |
| | | VMP-3-31.5-020911 | 2/9/2011 | <48 | U | | <26 | U | | 100 | | | <34 | U | | <52 | U | | <20 | U | | <11 | U | | | | | <15 | U | | <16 | U | | <32 | U | |
| | | VMP-3-31.5-041411 | 4/14/2011 | <400 | U | | <220 | U | | 100 | J | | <280 | U | | <430 | U | | <160 | U | | <92 | U | | 68000 | | | <490 | U | | <130 | U | | <260 | U | |
| | | VMP-3-31.5-041411-DUP | 4/14/2011 | <400 | U | | <220 | U | | 89 | J | | <280 | U | | <430 | U | | <160 | U | | <92 | U | | 63000 | | | <490 | U | | <130 | U | | <260 | U | |
| | | VMP-3-31.5-080211 | 8/2/2011 | <890 | U | | <490 | U | | 86 | J | | <630 | U | | <970 | U | | <360 | U | | <210 | U | | 98000 | | | <1100 | U | | <290 | U | | <590 | U | |
| | | VMP-3-31.5-080211-Dup | 8/2/2011 | <520 | U | | <280 | U | | 110 | J | | <370 | U | | <570 | U | | <210 | U | | <120 | U | | 91000 | | | <650 | U | | <170 | U | | <350 | U | |
| | | VMP-3-31.5-110811 | 11/8/2011 | 180 | | J | <11 | U | | 5.9 | J | | <15 | U | | <23 | U | | <8.5 | U | | <4.8 | U | | 3300 | | | 5 | J | | 13 | J | | <14 | U | |
| | | VMP-3-31.5-012712 | 1/27/2012 | 12 | J | J | <290 | U | | 27 | J | J | <93 | U | | <570 | U | | <54 | U | | <31 | U | J | 13000 | | | <160 | U | | <43 | U | | <87 | U | |
| | | VMP-3-31.5-041912 | 4/19/2012 | <230 | U | | <120 | U | | <76 | U | | <160 | U | | <250 | U | | <93 | U | | <53 | U | | 44000 | | | <280 | U | | <74 | U | | <150 | U | |
| | | VMP-3-31.5-041912-Dup | 4/19/2012 | <220 | U | | <120 | U | | <73 | U | | <150 | U | | <240 | U | | <89 | U | | <51 | U | | 47000 | | | <270 | U | | <71 | U | | <140 | U | |
| | | VMP-3-31.5-072312 | 7/23/2012 | <54 | U | | <30 | U | | <18 | U | | <38 | U | | <59 | U | | <22 | U | | <13 | U | | 14000 | | | <67 | U | | <18 | U | | <36 | U | |
| | | VMP-3-31.5-101912 | 10/19/2012 | <4.4 | U | | <2.4 | U | | 0.32 | J | | <3.1 | U | | <4.8 | U | | <1.8 | U | | <1 | U | | 100 | | | <5.4 | U | | <1.4 | U | | <2.9 | U | |
| | | VMP-3-31.5-020713 | 2/7/2013 | <24 | U | | <13 | U | | <8.2 | U | | <17 | U | | <27 | U | | <10 | U | | <5.7 | U | | 3000 | | | <30 | U | | 1.3 | J | | <16 | U | |
| | 39.5 ft | VMP-3-39-101912 | 10/19/2012 | <440 | U | | <240 | U | | 47 | J | | <310 | U | | <480 | U | | <180 | U | | <100 | U | | 22000 | | | <540 | U | | <140 | U | | <290 | U | |
| | | VMP-3-39-021213 | 2/12/2013 | <120 | U | | <68 | U | | 20 | J | | <88 | U | | <140 | U | | <51 | U | | <29 | U | | 18000 | | | <160 | U | | <41 | U | | <83 | U | |
| VMP-4 | 5 ft | VMP-4-5-082510 | 8/25/2010 | <0.68 | U | | <0.37 | U | | 0.27 | | | <0.48 | U | | <0.74 | U | | <0.28 | U | | <0.16 | U | | | | | <0.21 | U | | <0.22 | U | | <0.45 | U | |
| | | VMP-4-5-112210 | 11/22/2010 | <26 | U | | <14 | U | | 41 | | | <18 | U | | <28 | U | | <10 | U | | <6 | U | | | | | <7.9 | U | | <8.4 | U | | <17 | U | |
| | | VMP-4-5-021411 | 2/14/2011 | <1.5 | U | | <0.82 | U | | 2.3 | | | <1 | U | | <1.6 | U | | <0.61 | U | | <0.35 | U | | | | | <0.46 | U | | <0.49 | U | | <0.99 | U | |
| | | VMP-4-5-041911 | 4/19/2011 | <69 | U | | <38 | U | | 22 | J | | <48 | U | | <75 | U | | <28 | U | | <16 | U | | 7000 | | | <86 | U | | <22 | U | | <46 | U | |
| | | VMP-4-5-080311 | 8/3/2011 | <0.15 | U | | <0.08 | U | | 0.1 | | | <0.1 | U | | <0.16 | U | | <0.06 | U | | <0.034 | U | | 1.3 | | | <0.18 | U | | <0.19 | U | | <0.098 | U | |
| | | VMP-4-5-110911 | 11/9/2011 | 0.03 | | J | <0.0044 | U | | 0.0018 | J | | <0.0057 | U | | <0.0088 | U | | <0.0033 | U | | <0.0019 | U | | 0.011 | | | 0.0024 | J | | <0.011 | U | | <0.0054 | U | |
| | | VMP-4-5-013012 | 1/30/2012 | 0.12 | J | J | <0.23 | U | | 0.23 | | J | <0.29 | U | | <0.45 | U | | <0.17 | U | | <0.097 | U | | 14 | | J | <0.52 | U | | <0.14 | U | | <0.28 | U | |
| | | VMP-4-5-042512 | 4/25/2012 | 0.04 | | | <0.0056 | U | | 0.31 | | | <0.0073 | U | | <0.011 | U | | <0.042 | U | | <0.0024 | U | | 0.071 | | | 0.035 | | | <0.014 | J | U | <0.0068 | U | |
| | | VMP-4-5-072512 | 7/25/2012 | 0.12 | | | <0.0055 | U | | 0.28 | | | <0.0072 | U | | <0.011 | U | | <0.042 | U | | <0.0024 | U | | 0.012 | | | 0.034 | | | 0.014 | | J | <0.0067 | U | |
| | | VMP-4-5-101812 | 10/18/2012 | 0.022 | J | | <0.008 | U | | 0.31 | | | <0.01 | U | | <0.016 | U | | <0.06 | U | | <0.0034 | U | | 0.0038 | J | | 0.007 | J | | <0.019 | U | | <0.0098 | U | |
| | | VMP-4-5-020713 | 2/7/2013 | 0.0076 | J | | <0.0064 | U | | 0.0057 | | | <0.0083 | U | | <0.013 | U | | <0.048 | U | | <0.0027 | U | | 0.0068 | J | | <0.014 | U | | <0.015 | J | U | <0.0078 | U | |
| | 12 ft | VMP-4-12-082510 | 8/25/2010 | <12 | U | | <6.5 | U | | 28 | | | <8.4 | U | | <13 | U | | <4.9 | U | | <2.8 | U | | | | | <3.7 | U | | <3.9 | U | | <7.9 | U | |
| | | VMP-4-12-112310 | 11/23/2010 | <12 | U | | <6.7 | U | | 15 | | | <8.6 | U | | <13 | U | | <5 | U | | <2.8 | U | | | | | <3.8 | U | | <4 | U | | <8.1 | U | |
| | | VMP-4-12-021411 | 2/14/2011 | <3.1 | U | | <1.7 | U | | 5.2 | | | <2.2 | U | | <3.3 | U | | <1.2 | U | | <0.72 | U | | | | | <0.96 | U | | <1 | U | | <2 | U | |
| | | VMP-4-12-041911 | 4/19/2011 | <59 | U | | <32 | U | | 38 | | | <42 | U | | <65 | U | | <24 | U | | <14 | U | | 7200 | | | <74 | U | | <19 | U | | <39 | U | |
| | | VMP-4-12-080311 | 8/3/2011 | <6.8 | U | | <3.7 | U | | 8.4 | | | <4.8 | U | | <7.4 | U | | <2.8 | U | | <1.6 | U | | 1400 | | | <8.5 | U | | <2.2 | U | | <4.5 | U | |
| | | VMP-4-12-080311-Dup | 8/3/2011 | <14 | U | | <7.5 | U | | 6.4 | | | <9.7 | U | | <15 | U | | <5.6 | U | | <3.2 | U | | 1200 | | | <17 | U | | <4.5 | U | | <9.1 | U | |
| | | VMP-4-12-110911 | 11/9/2011 | 15 | | J | <1.1 | U | | 0.46 | J | | <1.5 | U | | <2.3 | U | | <0.85 | U | | <0.48 | U | | 100 | | | <2.6 | U | | <2.7 | U | | <1.4 | U | |
| | | VMP-4-12-013012 | 1/30/2012 | <4.2 | U | | <2.3 | U | | 3.4 | | | <3 | U | | <4.6 | U | | <1.7 | U | | <0.99 | U | | 280 | | | <5.3 | U | | <1.4 | U | | <2.8 | U | |
| | | VMP-4-12-041812 | 4/18/2012 | 0.04 | | | <0.0052 | U | | 0.068 | | | <0.0067 | U | | <0.01 | U | | <0.039 | U | | <0.0022 | U | | 0.0056 | J | | 0.058 | | | <0.012 | J | U | <0.0063 | U | |
| | | VMP-4-12-072312 | 7/23/2012 | 0.066 | J | | <0.025 | U | | 0.02 | | | <0.033 | U | | <0.05 | U | | <0.19 | U | | <0.011 | U | | 0.19 | | | <0.057 | U | | <0.061 | U | | <0.031 | U | |
| | | VMP-4-12-101812 | 10/18/2012 | 0.038 | | | <0.0078 | U | | 0.004 | J | | <0.01 | U | | <0.016 | U | | <0.059 | U | | <0.0034 | U | | 0.011 | J | | 0.0043 | J | | <0.019 | U | | <0.0095 | U | |
| | | VMP-4-12-101812-Dup | 10/18/2012 | 0.035 | J | | <0.008 | U | | 0.0038 | J | | <0.01 | U | | <0.016 | U | | <0.06 | U | | <0.0034 | U | | 0.011 | J | | <0.018 | U | | 0.0066 | J | | <0.0098 | U | |
| | | VMP-4-12-020713 | 2/7/2013 | 0.0077 | J | | <0.007 | U | | 0.0069 | | | <0.009 | U | | <0.014 | U | | <0.052 | U | | <0.003 | U | | 0.025 | | | <0.016 | U | | <0.017 | J | U | <0.0085 | U | |
| | | VMP-4-12-020713-DUP | 2/7/2013 | 0.012 | J | | <0.0071 | U | | 0.013 | | | <0.0092 | U | | <0.014 | U | | <0.054 | U | | <0.003 | U | | 0.03 | | | <0.016 | U | | <0.017 | J | U | <0.0087 | U | |
| | 23.5 ft | VMP - 4 - 23.5 - 083110 | 8/31/2010 | <14 | U | | <7.5 | U | | 490 | | J | <9.7 | U | | <15 | U | | <5.6 | U | | <3.2 | U | | | | | <4.3 | U | | <4.5 | U | | <9.1 | U | |
| | | VMP-4-23.5-112310 | 11/23/2010 | <140 | U | | <75 | U | | 510 | | | <97 | U | | <150 | U | | <56 | U | | <32 | U | | | | | <43 | U | | <45 | U | | <92 | U | |
| | | VMP-4-23.5-021411 | 2/14/2011 | <5 | U | | <2.7 | U | | 340 | | J | <3.6 | U | | <5.5 | U | | <2 | U | | <1.2 | U | | | | | <1.6 | U | | <1.6 | U | | <3.3 | U | |
| | | VMP-4-23.5-042011 | 4/20/2011 | <320 | U | | <170 | U | | 440 | | | <220 | U | | <350 | U | | <130 | U | | <74 | U | | 72000 | | | <400 | U | | <100 | U | | <210 | U | |
| | | VMP-4-23.5-042011-DUP | 4/20/2011 | 58 | J | | <170 | U | | 410 | | | <220 | U | | <350 | U | | <130 | U | | <74 | U | | 70000 | | | <400 | U | | <100 | U | | <210 | U | |
| | | VMP-4-23.5-080611 | 8/6/2011 | <13 | U | | <7.3 | U | | 280 | | | <9.4 | U | | <14 | U | | <5.4 | U | | <3.1 | U | | 56000 | | | <16 | U | | <4.4 | U | | <8.8 | U | |
| | | VMP-4-23.5-110911 | 11/9/2011 | 1800 | | J | <22 | U | | 89 | | | <28 | U | | <43 | U | | <16 | U | | <9.3 | U | | 25000 | | | <50 | U | | <52 | U | | <26 | U | |
| | | VMP-4-23.5-013012 | 1/30/2012 | <85 | U | | <46 | U | | 570 | | J | <60 | U | | <92 | U | | <35 | U | | <20 | U | | 16000 | | J | <100 | U | | <28 | U | | <56 | U | |
| | | VMP-4-23.5-013012-DUP | 1/30/2012 | <59 | U | | <32 | U | | 420 | | J | <42 | U | | <65 | U | | <24 | U | | <14 | U | | 15000 | | | <74 | U | | <19 | U | | <39 | U | |
| | | VMP-4-23.5-041912 | 4/19/2012 | 5.4 | J | | <10 | U | | 44 | | | <13 | U | | <20 | U | | <7.6 | U | | <4.3 | U | | 1500 | | | <23 | U | | 2 | J | | <12 | U | |
| | | VMP-4-23.5-072312 | 7/23/2012 | <8.9 | U | | <4.9 | U | | 56 | | | <6.3 | U | | <9.7 | U | | <3.6 | U | | <2.1 | U | | 770 | | | <11 | U | | <2.9 | U | | <5.9 | U | |
| | | VMP-4-23.5-101812 | 10/18/2012 | <9.8 | U | | <5.3 | U | | 1.6 | J | | <6.9 | U | | <11 | U | | <4 | U | | <2.3 | U | | 150 | | | <12 | U | | <3.2 | U | | <6.5 | U | |
| | | VMP-4-23.5-020713 | 2/7/2013 | <3.1 | U | | <1.7 | U | | 0.28 | J | | <2.2 | U | | <3.4 | U | | <1.3 | U | | <0.73 | U | | 150 | | | <3.9 | U | | <1 | U | | <2.1 | U | |
| | 39 ft | VMP-4-39-042111 | 4/21/2011 | <400 | U | | <220 | U | | 470 | | | <280 | U | | <430 | U | | <160 | U | | <93 | U | | 69000 | | | <500 | U | | <130 | U | | <260 | U | |
| | | VMP-4-39-041912 | 4/19/2012 | <9.5 | U | | <5.2 | U | | 67 | | | <6.7 | U | | <10 | U | | <3.9 | U | | <2.2 | U | | 3900 | | | <12 | U | | <3.1 | U | | <6.3 | U | |
| | | VMP-4-39-072312 | 7/23/2012 | <14 | U | | <7.8 | U | | 50 | | J | <10 | U | | <16 | U | | <5.9 | U | | <3.3 | U | | 1800 | | J | <18 | U | | <4.7 | U | | <9.5 | U | |
| | | VMP-4-39-101812 | 10/18/2012 | <180 | U | | <98 | U | | 28 | J | | <130 | U | | <200 | U | | <74 | U | | <42 | U | | 3900 | | | <220 | U | | <59 | U | | <120 | U | |
| | | VMP-4-39-101812-Dup | 10/18/2012 | <160 | U | | <89 | U | | 26 | J | | <120 | U | | <180 | U | | <67 | U | | <38 | U | | 3900 | | | <200 | U | | <54 | U | | <110 | U | |
| | | VMP-4-39-020713 | 2/7/2013 | <26 | U | | <14 | U | | 25 | | | <18 | U | | <28 | U | | <10 | U | | <6 | U | | 2500 | | | <32 | U | | 3.2 | J | | <17 | U | |

SEE LAST PAGE OF TABLE FOR NOTES

**TABLE 5**
**CUMULATIVE SUMMARY OF SOIL VAPOR ANALYTICAL DETECTIONS AND SCREENING RESULTS: VILLAGE - VOCS**

| Location | Depth | Sample ID | Sample Date | Acetone | | | alpha-Chlorotoluene | | | Benzene | | | Bromodichloromethane | | | Bromoform | | | Bromomethane | | | 1,3-Butadiene | | | Butane | | | 2-Butanone | | | Carbon disulfide | | | Carbon tetrachloride | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | 750000 | | | | | | 0.37 | | | 450000 | | | 11 | | | 6.9 | | | | | | | | | 6400 | | | 780 | | | 0.21 | | |
| | | | | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals |
| VMP-5 | 5 ft | VMP-5-5-090910 | 9/9/2010 | <25 | U | | <14 | U | | 7.6 | J | | <18 | U | | <27 | U | | <10 | U | | <5.8 | U | | | | | <7.8 | U | | <8.2 | U | | <17 | U | |
| | | VMP-5-5-112210 | 11/22/2010 | <6.1 | U | | <3.3 | U | | 8.6 | | | <4.3 | U | | <6.7 | U | | <2.5 | U | | <1.4 | U | | | | | <1.9 | U | | <2 | U | | <4 | U | |
| | | VMP-5-5-021611 | 2/16/2011 | <0.039 | U | | <0.021 | U | | 0.024 | | J | <0.028 | U | | <0.042 | U | | <0.016 | U | | <0.0091 | U | | | | | <0.012 | U | | 0.0081 | J | J | <0.026 | U | |
| | | VMP-5-5-042111 | 4/21/2011 | <0.12 | U | | <0.068 | U | | 0.88 | | | <0.088 | U | | <0.14 | U | | <0.051 | U | | <0.029 | U | | 0.064 | J | | <0.16 | U | | <0.041 | U | | <0.083 | U | |
| | | VMP-5-5-080511 | 8/5/2011 | 0.084 | | | <0.0065 | U | | 0.015 | | | <0.0084 | U | | <0.013 | U | | <0.0049 | U | | <0.0028 | U | | 0.86 | | | 0.028 | | | 0.0037 | J | | <0.0079 | U | |
| | | VMP-5-5-111111 | 11/11/2011 | 0.15 | | | <0.0048 | U | | 0.03 | | | <0.0062 | U | | <0.0096 | U | | <0.0036 | U | | <0.002 | U | | 0.05 | | | 0.0024 | J | | 0.0024 | J | | <0.0058 | U | |
| | | VMP-5-5-013012 | 1/30/2012 | 0.18 | | | <0.048 | U | | 9.1 | | | <0.063 | U | | <0.097 | U | | <0.036 | U | | <0.021 | U | | 2.4 | | | 0.076 | J | | 0.12 | | | <0.059 | U | |
| | | VMP-5-5-041112 | 4/11/2012 | 0.04 | | | <0.0047 | U | | 0.017 | | | <0.0061 | U | | <0.0094 | U | | <0.036 | U | | <0.002 | U | | <0.0087 | U | | 0.051 | | | 0.002 | J | J | 0.00094 | J | |
| | | VMP-5-5-071312 | 7/13/2012 | 0.24 | | | <0.0052 | U | | 0.0028 | J | | <0.0068 | U | | <0.01 | U | | <0.039 | U | UJ | <0.0022 | U | | <0.0096 | U | | 0.016 | | | <0.013 | J | U | <0.0064 | U | |
| | | VMP-5-5-101212 | 10/12/2012 | 0.047 | | | <0.0065 | U | | 0.0043 | | | <0.0084 | U | | <0.013 | U | | <0.049 | U | | <0.0028 | U | | 0.0047 | J | | 0.0032 | J | | <0.016 | U | | <0.0079 | U | |
| | | VMP-5-5-012513 | 1/25/2013 | 0.012 | J | | <0.0068 | U | | 0.014 | | | <0.0088 | U | | <0.014 | U | | <0.051 | U | | <0.0029 | U | | <0.012 | U | | <0.016 | U | | <0.016 | U | | <0.0083 | U | |
| | 12.5 ft | VMP-5-12.5-090910 | 9/9/2010 | 7.6 | J | | <6.8 | U | | 11 | | | <8.8 | U | | <14 | U | | <5.1 | U | | <2.9 | U | | | | | <3.9 | U | | <4.1 | U | | <8.3 | U | |
| | | VMP-5-12.5-112310 | 11/23/2010 | <0.63 | U | | <0.34 | U | | 0.54 | | | <0.44 | U | | <0.68 | U | | <0.26 | U | | <0.15 | U | | | | | <0.19 | U | | <0.2 | U | | <0.42 | U | |
| | | VMP-5-12.5-021611 | 2/16/2011 | <1.9 | U | | <1 | U | | <0.63 | U | | <1.3 | U | | <2 | U | | <0.77 | U | | <0.44 | U | | | | | <0.58 | U | | <0.62 | U | | <1.2 | U | |
| | | VMP-5-12.5-042111 | 4/21/2011 | <0.13 | U | | <0.073 | U | | 0.71 | | | <0.094 | U | | <0.14 | U | | <0.055 | U | | <0.031 | U | | 0.11 | J | | <0.17 | U | | <0.044 | U | | <0.089 | U | |
| | | VMP-5-12.5-080611 | 8/6/2011 | <12 | U | | <6.4 | U | | 4.6 | | | <8.3 | U | | <13 | U | | <4.8 | U | | <2.7 | U | | 7600 | | | <15 | U | | <3.9 | U | | <7.8 | U | |
| | | VMP-5-12.5-111111 | 11/11/2011 | 0.0085 | | | <0.0046 | U | | 0.0064 | | | <0.0059 | U | | <0.0091 | U | | <0.0034 | J | U | <0.0019 | U | | 0.0035 | J | | 0.0022 | J | | 0.0023 | J | | <0.0055 | U | |
| | | VMP-5-12.5-013012 | 1/30/2012 | 0.066 | | | <0.015 | U | | 2.4 | | | <0.019 | U | | <0.03 | U | | <0.011 | U | | <0.0063 | U | | 0.8 | | | 0.054 | | | <0.036 | J | U | <0.018 | U | |
| | | VMP-5-12.5-041112 | 4/11/2012 | 0.026 | | | <0.0045 | U | | 0.033 | | | <0.0059 | U | | <0.009 | U | | <0.034 | U | | <0.0019 | U | | <0.0083 | U | | 0.035 | | | <0.011 | U | | <0.0055 | U | |
| | | VMP-5-12.5-071212 | 7/12/2012 | 0.048 | | | <0.0053 | U | UJ | 0.0018 | J | | <0.0069 | U | | <0.011 | U | | <0.04 | U | | <0.0023 | U | | <0.0098 | U | | 0.004 | J | | <0.013 | U | | <0.0065 | U | |
| | | VMP-5-12.5-101112 | 10/11/2012 | 0.02 | J | | <0.013 | U | | 0.015 | | | <0.016 | U | | <0.025 | U | | <0.095 | U | | <0.0054 | U | | <0.023 | U | | <0.029 | U | | <0.03 | J | U | <0.015 | U | |
| | | VMP-5-12.5-012413 | 1/24/2013 | 0.024 | J | | <0.0067 | U | | 0.0021 | J | | <0.0086 | U | | <0.013 | U | | <0.05 | U | | <0.0028 | U | | <0.012 | U | | <0.015 | U | | <0.016 | U | | <0.0081 | U | |
| | 31 ft | VMP-5-31-090910 | 9/9/2010 | <52 | U | | <28 | U | | 200 | | | <37 | U | | <57 | U | | <21 | U | | <12 | U | | | | | <16 | U | | <17 | U | | <35 | U | |
| | | VMP-5-31-112310 | 11/23/2010 | <33 | U | | <18 | U | | 180 | | | <23 | U | | <36 | U | | <13 | U | | <7.6 | U | | | | | <10 | U | | <11 | U | | <22 | U | |
| | | VMP-5-31-021611 | 2/16/2011 | <13 | U | | <7.1 | U | | 74 | | | <9.2 | U | | <14 | U | | <5.4 | U | | <3 | U | | | | | <4.1 | U | | <4.3 | U | | <8.7 | U | |
| | | VMP-5-31-042111 | 4/21/2011 | <200 | U | | <110 | U | | 66 | | | <140 | U | | <210 | U | | <80 | U | | <46 | U | | 34000 | | | <240 | U | | <64 | U | | <130 | U | |
| | | VMP-5-31-080611 | 8/6/2011 | <110 | U | | <60 | U | | 64 | | | <78 | U | | <120 | U | | <45 | U | | <26 | U | | 38000 | | | <140 | U | | 6.4 | J | | <73 | U | |
| | | VMP-5-31-111111 | 11/11/2011 | <56 | U | | <30 | U | | 12 | J | | <39 | U | | <60 | U | | <23 | U | | <13 | U | | 19000 | | | <69 | U | | <73 | U | | <37 | U | |
| | | VMP-5-31-013012 | 1/30/2012 | 4.4 | J | | <15 | U | | 10 | | | <20 | U | | <31 | U | | <12 | U | | <6.6 | U | | 6900 | | | <35 | U | | <9.3 | U | | <19 | U | |
| | | VMP-5-31-041112 | 4/11/2012 | 0.03 | J | | <0.049 | U | | 0.08 | | | <0.064 | U | | <0.099 | U | | <0.037 | U | | <0.021 | U | | 4.3 | | | 0.023 | J | | <0.03 | U | | <0.06 | U | |
| | | VMP-5-31-071212 | 7/12/2012 | 0.11 | | | <0.0052 | U | UJ | 0.0044 | | | <0.0067 | U | | <0.01 | U | | <0.039 | U | | <0.0022 | U | | 0.26 | | | 0.014 | | | 0.0076 | J | | <0.0063 | U | |
| | | VMP-5-31-101112 | 10/11/2012 | 0.082 | | | <0.0073 | U | | 0.0078 | | | <0.0094 | U | | <0.014 | U | | <0.055 | U | | <0.0031 | U | | 0.075 | | | 0.0042 | J | | <0.018 | J | U | <0.0089 | U | |
| | | VMP-5-31-012413 | 1/24/2013 | 0.049 | J | | <0.072 | U | | <0.045 | U | | <0.094 | U | | <0.14 | U | | <0.54 | U | | <0.031 | U | | 0.14 | | | <0.16 | U | | <0.17 | U | | <0.088 | U | |
| | 40 ft | VMP-5-40-042111 | 4/21/2011 | <200 | U | | <110 | U | | 64 | J | | <140 | U | | <220 | U | | <84 | U | | <48 | U | | 27000 | | | <250 | U | | <67 | U | | <140 | U | |
| | | VMP-5-40-013012 | 1/30/2012 | 6 | J | | <32 | U | | 6.8 | J | | <42 | U | | <65 | U | | <24 | U | | <14 | U | | 6400 | | | <74 | U | | <19 | U | | <39 | U | |
| | | VMP-5-40-041212 | 4/12/2012 | 0.053 | J | | <0.048 | U | | 0.15 | | | <0.063 | U | | <0.097 | U | | <0.036 | U | | <0.021 | U | | 21 | | | 0.055 | J | | 0.021 | J | | <0.059 | U | |
| | | VMP-5-40-071212 | 7/12/2012 | 0.49 | | | <0.052 | U | UJ | <0.032 | U | | <0.067 | U | | <0.1 | U | | <0.39 | U | | <0.022 | U | | 0.63 | | | <0.12 | U | | <0.12 | U | | <0.063 | U | |
| | | VMP-5-40-101112 | 10/11/2012 | 0.028 | J | | <0.0077 | U | | 0.011 | | | <0.0099 | U | | <0.015 | U | | <0.057 | U | | <0.0033 | U | | 0.27 | | | <0.017 | U | | <0.018 | J | U | <0.0093 | U | |
| | | VMP-5-40-012513 | 1/25/2013 | 0.35 | | | <0.022 | U | | 0.0037 | J | | <0.029 | U | | <0.044 | U | | <0.17 | U | | <0.0095 | U | | 0.21 | | J | <0.051 | U | | <0.054 | U | | <0.027 | U | |
| | | VMP-5-40-012513-Dup | 1/25/2013 | 0.36 | | | <0.022 | U | | 0.0037 | J | | <0.028 | U | | <0.043 | U | | <0.16 | U | | <0.0093 | U | | 0.1 | | J | <0.05 | U | | <0.052 | U | | <0.026 | U | |
| VMP-6 | 5 ft | VMP-6-5-090810 | 9/8/2010 | <2.1 | U | | <1.1 | U | | 1 | | | <1.5 | U | | <2.3 | U | | <0.85 | U | | <0.49 | U | | | | | <0.65 | U | | <0.68 | U | | <1.4 | U | |
| | | VMP-6-5-111610 | 11/16/2010 | <13 | U | | <7.1 | U | | 9 | | | <9.2 | U | | <14 | U | | <5.4 | U | | <3 | U | | | | | <4.1 | U | | <4.3 | U | | <8.7 | U | |
| | | VMP-6-5-020711 | 2/7/2011 | 0.014 | | | <0.0062 | U | | 0.0033 | J | | <0.008 | U | | <0.012 | U | | <0.0046 | U | | <0.0026 | U | | | | | 0.0015 | J | | <0.0037 | U | | <0.0075 | U | |
| | | VMP-6-5-040811 | 4/8/2011 | 0.055 | | | <0.013 | U | | 2.4 | | | <0.017 | U | | <0.027 | U | | <0.01 | U | | <0.0057 | U | | 0.083 | | | <0.03 | U | | <0.0098 | U | | <0.016 | U | |
| | | VMP-6-5-080411 | 8/4/2011 | <0.64 | U | | <0.35 | U | | 0.74 | | | <0.45 | U | | <0.69 | U | | <0.26 | U | | <0.15 | U | | 160 | | | <0.79 | U | | <0.21 | U | | <0.42 | U | |
| | | VMP-6-5-110911 | 11/9/2011 | 0.015 | | J | <0.0042 | U | | 0.015 | | | <0.0054 | U | | <0.0083 | U | | <0.0031 | U | | <0.0018 | U | | 0.028 | | | 0.0027 | J | | <0.01 | U | | <0.0051 | U | |
| | | VMP-6-5-013112 | 1/31/2012 | 0.13 | | | <0.049 | U | | 0.096 | | | <0.064 | U | | <0.098 | U | | <0.037 | U | | <0.021 | U | | 6.2 | | | 0.035 | J | | 0.073 | J | | <0.06 | U | |
| | | VMP-6-5-041212 | 4/12/2012 | 0.02 | J | | <0.0052 | U | | 0.01 | | | <0.0067 | U | | <0.01 | U | | <0.039 | U | | <0.0022 | U | | <0.0096 | U | | 0.0029 | J | | <0.012 | J | U | <0.0063 | U | |
| | | VMP-6-5-071612 | 7/16/2012 | 0.075 | | | <0.0052 | U | | 0.0097 | | | <0.0067 | U | | <0.01 | U | | <0.039 | U | UJ | <0.0022 | U | | <0.0096 | U | | 0.008 | J | | <0.012 | J | U | <0.0063 | U | |
| | | VMP-6-5-101012 | 10/10/2012 | 0.041 | | | <0.0071 | U | | 0.003 | J | | <0.0092 | U | | <0.014 | U | | <0.054 | U | | <0.003 | U | | <0.013 | U | | <0.016 | U | | <0.017 | J | U | <0.0087 | U | |
| | | VMP-6-5-021213 | 2/12/2013 | 1.8 | | | <0.0064 | U | | 0.037 | | | <0.0083 | U | | <0.013 | U | | <0.048 | U | | <0.0027 | U | | 0.11 | | | <0.014 | U | | <0.015 | J | U | <0.0078 | U | |
| | 10 ft | VMP-6-10-090810 | 9/8/2010 | <2.3 | U | | <1.2 | U | | 2.9 | | J | <1.6 | U | | <2.5 | U | | <0.92 | U | | <0.53 | U | | | | | <0.7 | U | | <0.74 | U | | <1.5 | U | |
| | | VMP-6-10-111710 | 11/17/2010 | 0.012 | J | | <0.0067 | U | | 0.0053 | | | 0.0025 | J | | <0.013 | U | | <0.005 | J | U | <0.0028 | U | | | | | 0.0022 | J | | <0.004 | U | | 0.0011 | J | |
| | | VMP-6-10-020711 | 2/7/2011 | 0.0038 | J | | <0.0065 | U | | 0.0084 | | | <0.0084 | U | | <0.013 | U | | <0.0049 | U | | <0.0028 | U | | | | | <0.0037 | U | | <0.0039 | U | | <0.0079 | U | |
| | | VMP-6-10-040811 | 4/8/2011 | 0.54 | | | <0.16 | U | | 2 | | | <0.2 | U | | <0.31 | U | | <0.12 | U | | <0.067 | U | | <0.29 | U | | 0.12 | J | | 0.19 | J | | <0.19 | U | |
| | | VMP-6-10-080411 | 8/4/2011 | <2 | U | | <1.1 | U | | 1.7 | | | <1.4 | U | | <2.2 | U | | <0.83 | U | | <0.47 | U | | 400 | | | <2.5 | U | | <0.67 | U | | <1.3 | U | |
| | | VMP-6-10-111011 | 11/10/2011 | 0.017 | | J | <0.0043 | U | | 0.012 | | | <0.0056 | U | | <0.0087 | U | | <0.0033 | U | | <0.0018 | U | | 0.033 | | | 0.0026 | J | | <0.01 | U | | <0.0053 | U | |
| | | VMP-6-10-013112 | 1/31/2012 | <1.4 | U | | <3.1 | U | | 0.51 | | J | <1 | U | | <6.2 | U | | <0.58 | U | | <0.33 | U | | 120 | | J | <1.8 | U | | <0.46 | U | | <0.94 | U | |
| | | VMP-6-10-041212 | 4/12/2012 | 0.039 | | | <0.005 | U | | 0.007 | | | <0.0065 | U | | <0.01 | U | | <0.038 | U | | <0.0022 | U | | <0.0093 | U | | 0.0057 | J | | <0.012 | J | U | <0.0061 | U | |
| | | VMP-6-10-071612 | 7/16/2012 | 0.051 | | | <0.0068 | U | | 0.0081 | | | <0.0088 | J | U | <0.014 | U | | <0.051 | U | UJ | <0.0029 | U | | <0.012 | U | | 0.0096 | J | | <0.016 | J | U | <0.0083 | U | |
| | | VMP-6-10-101112 | 10/11/2012 | 0.0085 | J | | <0.0075 | U | | 0.0066 | | | <0.0097 | U | | <0.015 | U | | <0.056 | U | | <0.0032 | U | | <0.014 | U | | <0.017 | U | | <0.018 | J | U | <0.0091 | U | |
| | | VMP-6-10-020513 | 2/5/2013 | 0.009 | J | | <0.0071 | U | | 0.046 | | | <0.0092 | U | | <0.014 | U | | <0.054 | U | | <0.003 | U | | 0.0036 | J | | <0.016 | U | | <0.017 | J | U | <0.0087 | U | |
| | 31.5 ft | VMP-6-31.5-090810 | 9/8/2010 | <15 | U | | <8.3 | U | | 29 | | | <11 | U | | <17 | U | | <6.2 | U | | <3.6 | U | | | | | <4.7 | U | | <5 | U | | <10 | U | |
| | | VMP-6-31.5-111710 | 11/17/2010 | <24 | U | | <13 | U | | 30 | | | <17 | U | | <26 | U | | <9.8 | U | | <5.6 | U | | | | | <7.4 | U | | <7.8 | U | | <16 | U | |
| | | VMP-6-31.5-020711 | 2/7/2011 | 13 | J | | <12 | U | | 30 | | | <16 | U | | <25 | U | | <9.4 | U | | <5.4 | U | | | | | <7.1 | U | | <7.5 | U | | <15 | U | |
| | | VMP-6-31.5-041111 | 4/11/2011 | 12 | J | | <9.7 | U | | 18 | | | <12 | U | | <19 | U | | <7.3 | U | | <4.1 | U | | 1200 | | | <22 | U | | 3.8 | J | | <12 | U | |
| | | VMP-6-31.5-080411 | 8/4/2011 | <13 | U | | <7.2 | U | | 11 | | | <9.3 | U | | <14 | U | | <5.4 | U | | <3.1 | U | | 1100 | | | <16 | U | | <4.3 | U | | <8.7 | U | |
| | | VMP-6-31.5-111011 | 11/10/2011 | 110 | | J | <11 | U | | 8.8 | | | <14 | U | | <22 | U | | <8.3 | U | | <4.7 | U | | 1300 | | | 6.4 | J | | 34 | | | <13 | U | |
| | | VMP-6-31.5-013112 | 1/31/2012 | <8.1 | U | | <18 | U | | 8.1 | | J | <5.7 | U | | <35 | U | | <3.3 | U | | <1.9 | U | | 700 | | J | <10 | U | | <2.7 | U | | <5.4 | U | |
| | | VMP-6-31.5-041212 | 4/12/2012 | 0.12 | J | | <0.59 | U | | <0.36 | U | | <0.77 | U | | <1.2 | U | | <0.44 | U | | <0.25 | U | | 32 | | | <1.4 | U | | <0.36 | U | | <0.72 | U | |
| | | VMP-6-31.5-071612 | 7/16/2012 | 0.098 | | | <0.0094 | U | | 0.016 | | | <0.012 | U | | <0.019 | U | | <0.07 | U | UJ | <0.004 | U | | 0.05 | | | 0.012 | J | | 0.017 | J | J | <0.011 | U | |
| | | VMP-6-31.5-101112 | 10/11/2012 | 0.014 | J | | <0.0073 | U | | 0.0049 | | | <0.0094 | U | | <0.014 | U | | <0.055 | U | | <0.0031 | U | | 0.018 | | | <0.017 | U | | <0.018 | J | U | <0.0089 | U | |
| | | VMP-6-31.5-020513 | 2/5/2013 | 0.0095 | J | | <0.0067 | U | | 0.004 | J | | <0.0086 | U | | <0.013 | U | | <0.05 | U | | <0.0028 | U | | 0.03 | | | <0.015 | U | | <0.016 | J | U | <0.0081 | U | |
| | 39 ft | VMP-6-39-041111 | 4/11/2011 | 12 | J | | <12 | U | | 16 | | | <15 | U | | <23 | U | | <8.7 | U | | <4.9 | U | | 1200 | | | 3.6 | J | | 3.4 | J | | <14 | U | |
| | | VMP-6-39-013112 | 1/31/2012 | <8.1 | U | | <18 | U | | 8.3 | | J | <5.7 | U | | <35 | U | | <3.3 | U | | <1.9 | U | | 900 | | J | <10 | U | | <2.7 | U | | <5.4 | U | |
| | | VMP-6-39-041212 | 4/12/2012 | <0.8 | U | | <0.43 | U | | 1.7 | | | <0.56 | U | | <0.87 | U | | <0.33 | U | | <0.18 | U | | 53 | | | <0.99 | U | | <0.26 | U | | <0.53 | U | |
| | | VMP-6-39-071612 | 7/16/2012 | 0.052 | J | | <0.02 | U | | 0.02 | | | <0.026 | U | | <0.041 | U | | <0.15 | U | UJ | <0.0087 | U | | 0.069 | | | <0.046 | U | | 0.011 | J | J | <0.025 | U | |
| | | VMP-6-39-071612-Dup | 7/16/2012 | 0.057 | J | | <0.021 | U | | 0.016 | | | <0.027 | U | | <0.041 | U | | <0.15 | U | UJ | <0.0088 | U | | 0.062 | | | <0.047 | U | | 0.012 | J | J | <0.025 | U | |
| | | VMP-6-39-101112 | 10/11/2012 | 0.03 | J | | <0.014 | U | | 0.0082 | J | | <0.018 | U | | <0.028 | U | | <0.1 | U | | <0.006 | U | | <0.026 | U | | <0.032 | U | | <0.034 | J | U | <0.017 | U | |
| | | VMP-6-39-020513 | 2/5/2013 | 0.014 | J | | <0.0068 | U | | 0.066 | | | <0.0088 | U | | <0.014 | U | | <0.051 | U | | <0.0029 | U | | <0.012 | U | | <0.016 | U | | <0.016 | J | U | <0.0083 | U | |

SEE LAST PAGE OF TABLE FOR NOTES

**TABLE 5**
**CUMULATIVE SUMMARY OF SOIL VAPOR ANALYTICAL DETECTIONS AND SCREENING RESULTS: VILLAGE - VOCS**

| Location | Depth | Sample ID | Sample Date | Acetone | | | alpha-Chlorotoluene | | | Benzene | | | Bromodichloromethane | | | Bromoform | | | Bromomethane | | | 1,3-Butadiene | | | Butane | | | 2-Butanone | | | Carbon disulfide | | | Carbon tetrachloride | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | 750000 | | | | | | 0.37 | | | 450000 | | | 11 | | | 6.9 | | | | | | | | | 6400 | | | 780 | | | 0.21 | | |
| | | | | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals |
| VMP-7 | 5 ft | VMP-7-5-082610 | 8/26/2010 | 0.026 | | | <0.0068 | U | | 0.012 | | | <0.0088 | U | | <0.014 | U | | <0.0051 | U | | <0.0029 | U | | | | | 0.006 | | | 0.0028 | J | | <0.0083 | U | |
| | | VMP-7-5-111910 | 11/19/2010 | 0.014 | | | <0.0062 | U | | 0.001 | J | | <0.008 | U | | <0.012 | U | | <0.0046 | U | | <0.0026 | U | | | | | 0.0022 | J | | <0.0037 | U | | <0.0075 | U | |
| | | VMP-7-5-020711 | 2/7/2011 | 0.027 | | | <0.0067 | U | | 0.041 | | | <0.0086 | U | | <0.013 | U | | <0.005 | U | | <0.0028 | U | | | | | <0.0038 | U | | <0.004 | U | | <0.0081 | U | |
| | | VMP-7-5-040711 | 4/7/2011 | 0.0076 | J | | <0.0094 | U | | 1.6 | | | <0.012 | U | | <0.019 | U | | <0.0071 | U | | <0.004 | U | | 0.012 | J | | <0.021 | U | | <0.023 | J | U | <0.011 | U | |
| | | VMP-7-5-080211 | 8/2/2011 | <1.7 | U | | <0.93 | U | | 1.3 | | | <1.2 | U | | <1.9 | U | | <0.7 | U | | <0.4 | U | | 110 | | | <2.1 | U | | <0.56 | U | | <1.1 | U | |
| | | VMP-7-5-111011 | 11/10/2011 | 0.0078 | J | | <0.0044 | U | | 0.005 | | | <0.0057 | U | | <0.0088 | U | | <0.0033 | U | | <0.0019 | U | | <0.0081 | U | | 0.0013 | J | | <0.011 | U | | <0.0054 | U | |
| | | VMP-7-5-111011-DUP | 11/10/2011 | 0.01 | | | <0.0042 | U | | 0.0048 | | | <0.0054 | U | | <0.0083 | U | | <0.0031 | U | | <0.0018 | U | | <0.0076 | U | | <0.0095 | U | | <0.01 | U | | <0.0051 | U | |
| | | VMP-7-5-013112 | 1/31/2012 | 0.026 | | | <0.0045 | U | | 0.0055 | | | <0.0059 | U | | <0.009 | U | | <0.0034 | U | | <0.0019 | U | | <0.0083 | U | | 0.045 | | | <0.011 | J | U | <0.0055 | U | |
| | | VMP-7-5-041212 | 4/12/2012 | 0.045 | | | <0.0049 | U | | 0.0089 | | | <0.0064 | U | | <0.0098 | U | | <0.037 | U | | <0.0021 | U | | <0.009 | U | | 0.046 | | | 0.011 | J | | <0.006 | U | |
| | | VMP-7-5-073112 | 7/31/2012 | 0.073 | | | <0.013 | U | | 0.12 | | | <0.016 | U | | <0.025 | U | | <0.095 | U | | <0.0054 | U | | 0.013 | J | | 0.027 | J | | <0.03 | U | | <0.015 | U | |
| | | VMP-7-5-101012 | 10/10/2012 | 0.037 | | | <0.0077 | U | | 0.0024 | J | | <0.0099 | U | | <0.015 | U | | <0.057 | U | | <0.0033 | U | | <0.014 | U | | <0.017 | U | | 0.0034 | J | | <0.0093 | U | |
| | 13.5 ft | VMP-7-13.5-082610 | 8/26/2010 | <0.27 | U | | <0.15 | U | | 0.15 | | | <0.19 | U | | <0.3 | U | | <0.11 | U | | <0.064 | U | | | | | <0.085 | U | | <0.09 | U | | <0.18 | U | |
| | | VMP-7-13.5-111910 | 11/19/2010 | <1.9 | U | | <1 | U | | 1.3 | | J | <1.4 | U | | <2.1 | U | | <0.78 | U | | <0.44 | U | | | | | <0.59 | U | | <0.63 | U | | <1.3 | U | |
| | | VMP-7-13.5-020711 | 2/7/2011 | 0.011 | J | | <0.0064 | U | | 0.027 | | | <0.0083 | U | | <0.013 | U | | <0.0048 | U | | <0.0027 | U | | | | | <0.0036 | U | | <0.0038 | U | | <0.0078 | U | |
| | | VMP-7-13.5-040711 | 4/7/2011 | 0.012 | J | | <0.011 | U | | 1.7 | | | <0.014 | U | | <0.022 | U | | <0.0084 | U | | <0.0048 | U | | 0.016 | J | | <0.025 | U | | <0.027 | J | U | <0.014 | U | |
| | | VMP-7-13.5-080311 | 8/3/2011 | <2.3 | U | | <1.2 | U | | 1.1 | | | <1.6 | U | | <2.5 | U | | <0.94 | U | | <0.53 | U | | 67 | | | <2.8 | U | | <0.75 | U | | <1.5 | U | |
| | | VMP-7-13.5-111011 | 11/10/2011 | 0.053 | | J | <0.0041 | U | | 0.0037 | | | <0.0053 | U | | <0.0082 | U | | <0.0031 | U | | <0.0017 | U | | 0.31 | | | 0.0018 | J | | <0.0098 | U | | <0.005 | U | |
| | | VMP-7-13.5-013112 | 1/31/2012 | 0.026 | J | J | <0.23 | U | | 0.048 | | J | <0.075 | U | | <0.46 | U | | <0.043 | U | | <0.025 | U | | 1.5 | | J | 0.024 | J | J | <0.035 | U | | <0.07 | U | |
| | | VMP-7-13.5-013112-DUP | 1/31/2012 | 0.059 | J | J | <0.24 | U | | 0.088 | | J | <0.077 | U | | <0.47 | U | | <0.044 | U | | <0.025 | U | | 1.5 | | J | 0.02 | J | J | <0.036 | U | | <0.072 | U | |
| | | VMP-7-13.5-041212 | 4/12/2012 | 0.02 | J | | <0.0047 | U | | 0.022 | | | <0.0061 | U | | <0.0094 | U | | <0.036 | U | | <0.002 | U | | 0.0062 | J | | 0.016 | | | <0.011 | J | U | <0.0058 | U | |
| | | VMP-7-13.5-041212-DUP | 4/12/2012 | 0.019 | J | | <0.005 | U | | 0.019 | | | <0.0065 | U | | <0.01 | U | | <0.037 | U | | <0.0021 | U | | <0.0092 | U | | 0.016 | | | <0.012 | J | U | <0.0061 | U | |
| | | VMP-7-13.5-072012 | 7/20/2012 | 0.041 | | | <0.0048 | J | U | 0.0087 | | | <0.0063 | U | | <0.0097 | U | | <0.036 | U | | <0.0021 | U | | <0.0089 | U | | 0.012 | | | <0.012 | U | | <0.0059 | U | |
| | | VMP-7-13.5-101012 | 10/10/2012 | 0.065 | | | <0.0071 | U | | 0.0058 | | | <0.0092 | U | | <0.014 | U | | <0.054 | U | | <0.003 | U | | <0.013 | U | | 0.0066 | J | | 0.0042 | J | | <0.0087 | U | |
| | | VMP-7-13.5-021313 | 2/13/2013 | 0.024 | J | | <0.0071 | U | | 0.002 | J | | <0.0092 | U | | <0.014 | U | | <0.054 | U | | <0.003 | U | | <0.013 | U | | <0.016 | U | | <0.017 | J | U | <0.0087 | U | |
| | 29.5 ft | VMP-7-29.5-083110 | 8/31/2010 | <3.9 | U | | <2.1 | U | | 86 | | J | <2.8 | U | | <4.2 | U | | <1.6 | U | | <0.91 | U | | | | | <1.2 | U | | <1.3 | U | | <2.6 | U | |
| | | VMP-7-29.5-111910 | 11/19/2010 | <5.9 | U | | <3.2 | U | | 62 | | J | <4.2 | U | | <6.4 | U | | <2.4 | U | | <1.4 | U | | | | | <1.8 | U | | <1.9 | U | | <3.9 | U | |
| | | VMP-7-29.5-020711 | 2/7/2011 | <6.1 | U | | <3.3 | U | | 60 | | | <4.3 | U | | <6.7 | U | | <2.5 | U | | <1.4 | U | | | | | <1.9 | U | | <2 | U | | <4 | U | |
| | | VMP-7-29.5-040711 | 4/7/2011 | <1.5 | U | | <0.81 | U | | 40 | | J | <1 | U | | <1.6 | U | | <0.61 | U | | <0.35 | U | | 94 | | J | <1.8 | U | | <0.49 | U | | <0.98 | U | |
| | | VMP-7-29.5-080311 | 8/3/2011 | <3.5 | U | | <1.9 | U | | 40 | | | <2.5 | U | | <3.8 | U | | <1.4 | U | | <0.82 | U | | 200 | | | <4.4 | U | | <1.2 | U | | <2.3 | U | |
| | | VMP-7-29.5-111111 | 11/11/2011 | 38 | | | <3.8 | U | | 16 | | | <4.8 | U | | <7.5 | U | | <2.8 | U | | <1.6 | U | | 110 | | | 4.9 | J | | 8.5 | J | | <4.6 | U | |
| | | VMP-7-29.5-020112 | 2/1/2012 | <1.4 | U | | <3 | U | | 15 | | J | <0.98 | U | | <6 | U | | <0.57 | U | | <0.32 | U | | 61 | | J | <1.7 | U | | <0.45 | U | | <0.92 | U | |
| | | VMP-7-29.5-041312 | 4/13/2012 | 0.033 | | | <0.0047 | U | | 0.0078 | | | <0.0061 | U | | <0.0094 | U | | 0.0013 | J | | <0.002 | U | | 0.023 | | | 0.021 | | | 0.0077 | J | | <0.0058 | U | |
| | | VMP-7-29.5-072012 | 7/20/2012 | 0.036 | | | <0.0048 | U | | 0.031 | | | <0.0063 | U | | <0.0097 | U | | <0.036 | U | | 0.0013 | J | | 0.0094 | | | 0.0061 | J | | 0.0088 | J | | <0.0059 | U | |
| | | VMP-7-29.5-072012-Dup | 7/20/2012 | 0.03 | | | <0.0048 | J | U | 0.032 | | | <0.0063 | U | | <0.0097 | U | | <0.036 | U | | <0.0021 | U | | 0.0086 | J | | 0.0067 | J | | 0.012 | | | <0.0059 | U | |
| | | VMP-7-29.5-101012 | 10/10/2012 | 0.064 | | | <0.0075 | U | | 0.0098 | | | <0.0097 | U | | <0.015 | U | | <0.056 | U | | <0.0032 | U | | 0.0052 | J | | 0.0031 | J | | 0.0093 | J | | <0.0091 | U | |
| | 38 ft | VMP-7-38-020711 | 2/7/2011 | 1.8 | J | | <4.5 | U | | 57 | | | <5.8 | U | | <8.9 | U | | <3.4 | U | | <1.9 | U | | | | | <2.6 | U | | <2.7 | U | | <5.4 | U | |
| | | VMP-7-38-040711 | 4/7/2011 | <2.1 | U | | <1.1 | U | | 24 | | J | <1.5 | U | | <2.3 | U | | <0.85 | U | | <0.49 | U | | 120 | | J | <2.6 | U | | <0.68 | U | | <1.4 | U | |
| | | VMP-7-38-020112 | 2/1/2012 | <2 | U | | <4.3 | U | | 15 | | J | <1.4 | U | | <8.7 | U | | <0.82 | U | | <0.46 | U | | 63 | | J | <2.5 | U | | <0.65 | U | | <1.3 | U | |
| | | VMP-7-38-042512 | 4/25/2012 | 0.015 | J | | <0.0047 | U | | 0.48 | | | <0.0061 | U | | <0.0094 | U | | <0.036 | U | | <0.002 | U | | 0.019 | | | 0.015 | | | <0.011 | J | U | <0.0058 | U | |
| | | VMP-7-38-042512-Dup | 4/25/2012 | 0.056 | | | <0.0047 | U | | 0.54 | | | <0.0061 | U | | <0.0094 | U | | <0.036 | U | | <0.002 | U | | 0.026 | | | 0.023 | | | <0.011 | J | U | <0.0058 | U | |
| | | VMP-7-38-101112 | 10/11/2012 | 0.021 | J | | <0.007 | U | | 0.012 | | | <0.009 | U | | <0.014 | U | | <0.052 | U | | <0.003 | U | | <0.013 | U | | <0.016 | U | | <0.017 | J | U | <0.0085 | U | |
| VMP-8 | 5 ft | VMP-8-5-083010 | 8/30/2010 | 0.043 | | | 0.0018 | J | J | 0.021 | | | <0.009 | U | | <0.014 | U | | 0.008 | | | <0.003 | U | | | | | 0.015 | | | 0.0032 | J | | <0.0085 | U | |
| | | VMP-8-5-111810 | 11/17/2010 | 0.012 | | | <0.006 | U | | <0.0037 | U | | 0.0012 | J | | <0.012 | U | | <0.0045 | U | | <0.0026 | U | | | | | 0.0017 | J | | 0.0011 | J | | 0.0014 | J | |
| | | VMP-8-5-021011 | 2/10/2011 | 0.0072 | J | | <0.0064 | U | | 0.014 | | | <0.0083 | U | | <0.013 | U | | <0.0048 | U | | <0.0027 | U | | | | | <0.0036 | U | | 0.0011 | J | | <0.0078 | U | |
| | | VMP-8-5-040711 | 4/7/2011 | 0.055 | | | <0.0071 | U | | 1.2 | | | <0.0092 | U | | <0.014 | U | | <0.0054 | U | | <0.003 | U | | <0.013 | U | | 0.0024 | J | | <0.017 | J | U | <0.0087 | U | |
| | | VMP-8-5-072711 | 7/27/2011 | 0.037 | | | <0.0077 | U | | 0.11 | | | <0.0099 | U | | <0.015 | U | | <0.0057 | U | | <0.0033 | U | | <0.014 | U | | 0.042 | | | 0.0036 | J | | <0.0093 | U | |
| | | VMP-8-5-110311 | 11/3/2011 | 0.037 | | | <0.0044 | U | | 0.0072 | | | <0.0057 | U | | <0.0088 | U | | <0.0033 | U | | <0.0019 | U | | 0.0057 | J | | 0.0027 | J | | 0.0022 | J | | <0.0054 | U | |
| | | VMP-8-5-012312 | 1/23/2012 | 0.0082 | J | | <0.0055 | U | | 0.023 | | | <0.0071 | U | | <0.011 | U | | <0.0041 | U | | <0.0023 | U | | 0.0072 | J | | 0.0073 | J | | <0.013 | J | U | <0.0067 | U | |
| | | VMP-8-5-041012 | 4/10/2012 | 0.014 | J | | 0.00086 | J | | 0.0025 | J | | <0.0064 | U | | <0.0099 | U | | <0.037 | U | | <0.0021 | U | | <0.0091 | U | | 0.0029 | J | | <0.012 | U | | <0.006 | U | |
| | | VMP-8-5-071312 | 7/13/2012 | 0.052 | | | <0.0042 | U | UJ | 0.00084 | J | | <0.0054 | U | | <0.0083 | U | | <0.031 | U | | <0.0018 | U | | <0.0076 | U | | 0.0086 | J | | <0.01 | U | | <0.0051 | U | |
| | | VMP-8-5-073112 | 7/31/2012 | 0.078 | | | <0.0053 | U | | 0.064 | | | <0.0069 | U | | <0.011 | U | | <0.04 | U | | <0.0023 | U | | <0.0098 | U | | 0.047 | | | 0.0082 | J | | <0.0065 | U | |
| | | VMP-8-5-100412 | 10/4/2012 | 0.019 | J | | <0.0071 | U | | 0.0031 | J | | <0.0092 | U | | <0.014 | U | | <0.054 | U | | <0.003 | U | | <0.013 | U | | <0.016 | U | | <0.017 | U | | <0.0087 | U | |
| | | VMP-8-5-100412-Dup | 10/4/2012 | 0.027 | J | | <0.0068 | U | | 0.0038 | J | | <0.0088 | U | | <0.014 | U | | <0.051 | U | | <0.0029 | U | | <0.012 | U | | <0.016 | U | | <0.016 | U | | <0.0083 | U | |
| | | VMP-8-5-012413 | 1/24/2013 | 0.06 | | | <0.007 | U | | 0.00077 | J | | <0.009 | U | | <0.014 | U | | <0.052 | U | | <0.003 | U | | <0.013 | U | | 0.041 | | | 0.0044 | J | | <0.0085 | U | |
| | 9.5 ft | VMP-8-9.5 | 11/10/2009 | <0.011 | U | | <0.005 | U | | <0.003 | U | | <0.007 | U | | <0.012 | U | | <0.004 | U | | <0.002 | U | | | | | <0.003 | U | | <0.003 | U | | <0.007 | U | |
| | | VMP-8-9.5-083010 | 8/30/2010 | 0.04 | | | <0.0063 | U | | 0.015 | | J | <0.0081 | U | | <0.012 | U | | 0.0068 | | | <0.0027 | U | | | | | 0.0061 | | | 0.0012 | J | | <0.0076 | U | |
| | | VMP-8-9.5-083010-DUP | 8/30/2010 | 0.041 | | | <0.0064 | U | | 0.012 | | J | <0.0083 | U | | <0.013 | U | | 0.0079 | | | <0.0027 | U | | | | | 0.0097 | | | 0.0012 | J | | <0.0078 | U | |
| | | VMP-8-9.5-111810 | 11/17/2010 | 0.0095 | J | | <0.0063 | U | | 0.0025 | J | | 0.0017 | J | | <0.012 | U | | <0.0047 | U | | <0.0027 | U | | | | | 0.0013 | J | | <0.0038 | U | | 0.0014 | J | |
| | | VMP-8-9.5-021011 | 2/10/2011 | 0.015 | | | <0.0065 | U | | <0.004 | U | | <0.0084 | U | | <0.013 | U | | <0.0049 | U | | <0.0028 | U | | | | | <0.0037 | U | | <0.0039 | U | | <0.0079 | U | |
| | | VMP-8-9.5-040711 | 4/7/2011 | 0.0089 | J | | <0.0071 | U | | 0.93 | | | <0.0092 | U | | <0.014 | U | | <0.0054 | U | | <0.003 | U | | <0.013 | U | | 0.0023 | J | | 0.0015 | J | | <0.0087 | U | |
| | | VMP-8-9.5-072711 | 7/27/2011 | 0.035 | | | <0.0055 | U | | 0.19 | | | <0.0071 | U | | <0.011 | U | | <0.0041 | U | | <0.0024 | U | | 0.012 | | | 0.038 | | | 0.0032 | J | | <0.0067 | U | |
| | | VMP-8-9.5-110311 | 11/3/2011 | 0.021 | | | <0.0043 | U | | 0.0053 | | | <0.0056 | U | | <0.0087 | U | | <0.0033 | U | | <0.0018 | U | | 0.0058 | J | | 0.002 | J | | 0.003 | J | | <0.0053 | U | |
| | | VMP-8-9.5-012312 | 1/23/2012 | 0.026 | | | <0.0052 | U | | 0.0026 | J | | <0.0068 | U | | <0.01 | U | | <0.0039 | U | | <0.0022 | U | | <0.0096 | U | | 0.0023 | J | | <0.013 | J | U | <0.0064 | U | |
| | | VMP-8-9.5-041012 | 4/10/2012 | 0.012 | J | | <0.0049 | U | | 0.0046 | | | 0.00078 | J | | <0.0099 | U | | <0.037 | U | | <0.0021 | U | | <0.0091 | U | | <0.011 | U | | 0.0019 | J | J | <0.006 | U | |
| | | VMP-8-9.5-071312 | 7/13/2012 | 0.011 | J | | <0.0048 | U | UJ | <0.003 | U | | <0.0063 | U | | <0.0097 | U | | <0.036 | U | | <0.0021 | U | | <0.0089 | U | | <0.011 | U | | <0.012 | U | | <0.0059 | U | |
| | | VMP-8-9.5-071312-Dup | 7/13/2012 | 0.0094 | J | | <0.0046 | U | UJ | <0.0028 | U | | <0.006 | U | | <0.0092 | U | | <0.035 | U | | <0.002 | U | | <0.0085 | U | | <0.01 | U | | <0.011 | U | | <0.0056 | U | |
| | | VMP-8-9.5-100412 | 10/4/2012 | 0.035 | J | | <0.0078 | U | | 0.021 | | | <0.01 | U | | <0.016 | U | | <0.059 | U | | <0.0034 | U | | <0.014 | U | | <0.018 | U | | <0.019 | U | | <0.0095 | U | |
| | | VMP-8-9.5-012413 | 1/24/2013 | 0.0078 | J | | <0.0065 | U | | 0.0011 | J | | <0.0084 | U | | <0.013 | U | | <0.049 | U | | <0.0028 | U | | <0.012 | U | | <0.015 | U | | <0.016 | U | | <0.0079 | U | |
| | | VMP-8-9.5-012413-Dup | 1/24/2013 | 0.0022 | J | | <0.007 | U | | <0.0043 | U | | <0.009 | U | | <0.014 | U | | <0.052 | U | | <0.003 | U | | <0.013 | U | | <0.016 | U | | <0.017 | U | | <0.0085 | U | |
| | 23.5 ft | VMP-8-23.5-083010 | 8/30/2010 | 0.02 | | | <0.0068 | U | | 0.013 | | | <0.0088 | U | | <0.014 | U | | <0.0051 | U | | <0.0029 | U | | | | | 0.0044 | | | 0.0015 | J | | 0.0009 | J | |
| | | VMP-8-23.5-111910 | 11/19/2010 | 0.033 | | | <0.0065 | U | | 0.0029 | J | | <0.0084 | U | | <0.013 | U | | <0.0049 | U | | <0.0028 | U | | | | | 0.0068 | | | <0.0039 | U | | <0.0079 | U | |
| | | VMP-8-23.5-021011 | 2/10/2011 | <0.013 | U | | <0.007 | U | | 0.0079 | | | <0.009 | U | | <0.014 | U | | <0.0052 | U | | <0.003 | U | | | | | <0.004 | U | | <0.0042 | U | | <0.0085 | U | |
| | | VMP-8-23.5-040711 | 4/7/2011 | 0.01 | J | | <0.0065 | U | | 1.2 | | J | <0.0084 | U | | <0.013 | U | | <0.0049 | U | | <0.0028 | U | | <0.012 | U | | <0.015 | U | | 0.0024 | J | | <0.0079 | U | |
| | | VMP-8-23.5-040711-DUP | 4/7/2011 | 0.0093 | J | | <0.01 | U | | 0.73 | | J | <0.013 | U | | <0.021 | U | | <0.0078 | U | | <0.0044 | U | | <0.019 | U | | <0.024 | U | | 0.0025 | J | | <0.012 | U | |
| | | VMP-8-23.5-081011 | 8/10/2011 | 0.043 | | | <0.0068 | J | U | 0.18 | | | <0.0088 | U | | <0.014 | U | | <0.0051 | U | | <0.0029 | U | | 0.02 | | | 0.012 | J | | <0.016 | J | U | <0.0083 | U | |
| | | VMP-8-23.5-110611 | 11/6/2011 | 0.019 | | | <0.0049 | U | | 0.0031 | | | <0.0064 | U | | <0.0099 | J | U | <0.0037 | U | | <0.0021 | U | | <0.0091 | U | | 0.0053 | J | | <0.012 | J | U | <0.006 | U | |
| | | VMP-8-23.5-012312 | 1/23/2012 | 0.0068 | J | | <0.0055 | U | | 0.0068 | | | <0.0071 | U | | <0.011 | U | | <0.0041 | U | | <0.0023 | U | | <0.01 | U | | 0.0039 | J | | <0.013 | J | U | <0.0067 | U | |
| | | VMP-8-23.5-041012 | 4/10/2012 | 0.032 | | | 0.00082 | J | | 0.0056 | | | <0.0063 | U | | <0.0097 | U | | <0.036 | U | | <0.0021 | U | | <0.0089 | U | | <0.011 | U | | <0.012 | U | | <0.0059 | U | |
| | | VMP-8-23.5-071312 | 7/13/2012 | 0.025 | | | <0.0053 | U | UJ | 0.0028 | J | | <0.0069 | U | | <0.011 | U | | <0.04 | U | | <0.0023 | U | | <0.0098 | U | | <0.012 | U | | <0.013 | U | | <0.0065 | U | |
| | | VMP-8-23.5-100412 | 10/4/2012 | 0.036 | | | <0.0075 | U | | 0.018 | | | <0.0097 | U | | <0.015 | U | | <0.056 | U | | <0.0032 | U | | <0.014 | U | | <0.017 | U | | <0.018 | U | | <0.0091 | U | |
| | | VMP-8-23.5-012413 | 1/24/2013 | 0.0064 | J | | <0.0075 | U | | 0.01 | | | <0.0097 | U | | <0.015 | U | | <0.056 | U | | <0.0032 | U | | <0.014 | U | | <0.017 | U | | <0.018 | J | U | <0.0091 | U | |

SEE LAST PAGE OF TABLE FOR NOTES

**TABLE 5**
**CUMULATIVE SUMMARY OF SOIL VAPOR ANALYTICAL DETECTIONS AND SCREENING RESULTS: VILLAGE - VOCS**

| Location | Depth | Sample ID | Sample Date | Acetone | | | alpha-Chlorotoluene | | | Benzene | | | Bromodichloromethane | | | Bromoform | | | Bromomethane | | | 1,3-Butadiene | | | Butane | | | 2-Butanone | | | Carbon disulfide | | | Carbon tetrachloride | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | 750000 | | | | | | 0.37 | | | 450000 | | | 11 | | | 6.9 | | | | | | | | | 6400 | | | 780 | | | 0.21 | | |
| | | | | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals |
| VMP-9 | 5 ft | VMP-9-5-082610 | 8/26/2010 | 0.029 | | | <0.0059 | U | | 0.0088 | | | <0.0076 | U | | <0.012 | U | | <0.0044 | U | | <0.0025 | U | | | | | 0.0053 | | | 0.0019 | J | | <0.0072 | U | |
| | | VMP-9-5-111910 | 11/19/2010 | 0.014 | | | <0.0062 | U | | <0.0038 | U | | <0.008 | U | | <0.012 | U | | <0.0046 | U | | <0.0026 | U | | | | | <0.0035 | U | | <0.0037 | U | | <0.0075 | U | |
| | | VMP-9-5-020811 | 2/8/2011 | 0.013 | | | <0.0057 | U | | <0.0035 | U | | <0.0074 | U | | <0.011 | U | | <0.0043 | U | | <0.0024 | U | | | | | 0.0015 | J | | <0.0034 | U | | <0.0069 | U | |
| | | VMP-9-5-040611 | 4/6/2011 | 0.026 | J | | <0.016 | U | | 0.11 | | | <0.02 | U | | <0.031 | U | | <0.012 | U | | <0.0067 | U | | <0.029 | U | | 0.0029 | J | | <0.038 | J | U | <0.019 | U | |
| | | VMP-9-5-080211 | 8/2/2011 | <0.56 | U | | <0.3 | U | | <0.19 | U | | <0.4 | U | | <0.61 | U | | <0.23 | U | | <0.13 | U | | 0.23 | J | | <0.7 | U | | <0.73 | U | | <0.37 | U | |
| | | VMP-9-5-110411 | 11/4/2011 | 0.014 | | | <0.0045 | J | U | 0.0021 | J | | <0.0059 | U | | <0.009 | U | | <0.0034 | U | | <0.0019 | U | | 0.0059 | J | | 0.0048 | J | | <0.011 | J | U | <0.0055 | U | |
| | | VMP-9-5-012612 | 1/26/2012 | 0.012 | | | <0.0038 | U | | 0.011 | | | <0.005 | U | | <0.0077 | U | | <0.0029 | U | | <0.0016 | U | | 0.11 | | | 0.0086 | J | | 0.001 | J | | <0.0047 | U | |
| | | VMP-9-5-041112 | 4/11/2012 | 0.011 | J | | <0.0046 | U | | 0.0075 | | | <0.006 | U | | <0.0092 | U | | <0.035 | U | | <0.002 | U | | <0.0085 | U | | 0.0014 | J | | <0.011 | U | | <0.0056 | U | |
| | | VMP-9-5-071312 | 7/13/2012 | 0.074 | | | <0.0049 | U | UJ | 0.067 | | | <0.0064 | U | | <0.0099 | U | | <0.037 | U | | <0.0021 | U | | 0.0055 | J | | 0.024 | | | <0.012 | U | | <0.006 | U | |
| | | VMP-9-5-101012 | 10/10/2012 | 0.026 | J | | <0.0075 | U | | 0.0037 | J | | <0.0097 | U | | <0.015 | U | | <0.056 | U | | <0.0032 | U | | <0.014 | U | | <0.017 | U | | <0.018 | J | U | <0.0091 | U | |
| | | [4]VMP-9-5-012513 | 1/25/2013 | 0.0061 | J | J | <0.0073 | U | UJ | 0.0046 | | J | <0.0094 | U | UJ | <0.014 | U | UJ | <0.055 | U | UJ | <0.0031 | U | UJ | <0.013 | U | UJ | <0.017 | U | UJ | <0.018 | J | UJ | <0.0089 | U | UJ |
| | | VMP-9-5-021513 | 2/15/2013 | 0.0078 | J | | <0.0071 | U | | 0.012 | | | <0.0092 | U | | <0.014 | U | | <0.054 | U | | <0.003 | U | | 0.0098 | J | | <0.016 | U | | <0.017 | U | | <0.0087 | U | |
| | 11.5 ft | VMP-9-11.5-082610 | 8/26/2010 | <0.24 | U | | <0.13 | U | | 0.16 | | | <0.17 | U | | <0.26 | U | | <0.1 | U | | <0.057 | U | | | | | <0.076 | U | | <0.08 | U | | <0.16 | U | |
| | | VMP-9-11.5-111910 | 11/19/2010 | <0.71 | U | | <0.38 | U | | 0.11 | J | | <0.5 | U | | <0.77 | U | | <0.29 | U | | <0.16 | U | | | | | <0.22 | U | | <0.23 | U | | <0.47 | U | |
| | | VMP-9-11.5-020911 | 2/9/2011 | 0.0074 | J | | <0.007 | U | | <0.0043 | U | | <0.009 | U | | <0.014 | U | | <0.0052 | U | | <0.003 | U | | | | | <0.004 | U | | <0.0042 | U | | <0.0085 | U | |
| | | VMP-9-11.5-020911-DUP | 2/9/2011 | 0.0088 | J | | <0.0054 | U | | <0.0033 | U | | <0.007 | U | | <0.011 | U | | <0.004 | U | | <0.0023 | U | | | | | <0.0031 | U | | <0.0032 | U | | <0.0066 | U | |
| | | VMP-9-11.5-040611 | 4/6/2011 | 0.026 | J | | <0.02 | U | | 0.025 | | | <0.026 | U | | <0.041 | U | | <0.015 | U | | <0.0087 | U | | 0.009 | J | | 0.0044 | J | | <0.049 | J | U | <0.025 | U | |
| | | VMP-9-11.5-080211 | 8/2/2011 | <0.84 | U | | <0.46 | U | | 0.48 | | | <0.59 | U | | <0.91 | U | | <0.34 | U | | <0.19 | U | | 4.8 | | | <1 | U | | <0.27 | U | | <0.55 | U | |
| | | VMP-9-11.5-110411 | 11/4/2011 | 0.017 | | | <0.0045 | U | | 0.013 | | | <0.0059 | U | | <0.009 | U | | <0.0034 | U | | <0.0019 | U | | 0.061 | | | 0.0087 | J | | <0.011 | J | U | <0.0055 | U | |
| | | VMP-9-11.5-012612 | 1/26/2012 | 0.024 | | | <0.004 | U | | 0.0024 | J | | <0.0052 | U | | <0.008 | U | | <0.003 | U | | <0.0017 | U | | 0.026 | | | 0.015 | | | <0.0096 | J | U | <0.0049 | U | |
| | | VMP-9-11.5-041112 | 4/11/2012 | 0.012 | J | | <0.0047 | U | | 0.0074 | | | 0.0012 | J | | <0.0094 | U | | <0.036 | U | | <0.002 | U | | <0.0087 | U | | 0.0026 | J | | <0.011 | U | | <0.0058 | U | |
| | | VMP-9-11.5-071312 | 7/13/2012 | 0.089 | | | <0.0053 | U | UJ | 0.017 | | | <0.0069 | U | | <0.011 | U | | <0.04 | U | | <0.0023 | U | | <0.0098 | U | | 0.023 | | | <0.013 | U | | <0.0065 | U | |
| | | VMP-9-11.5-101012 | 10/10/2012 | 0.051 | | | <0.0071 | U | | 0.0066 | | | <0.0092 | U | | <0.014 | U | | <0.054 | U | | <0.003 | U | | <0.013 | U | | <0.016 | U | | <0.017 | J | U | <0.0087 | U | |
| | | VMP-9-11.5-012513 | 1/25/2013 | 0.012 | J | | <0.006 | U | | 0.002 | J | | <0.0078 | U | | <0.012 | U | | <0.045 | U | | <0.0026 | U | | 0.025 | | J | <0.014 | U | | <0.014 | J | U | <0.0073 | U | |
| | | VMP-9-11.5-012513-DUP | 1/25/2013 | 0.006 | J | | <0.0065 | U | | 0.0015 | J | | <0.0084 | U | | <0.013 | U | | <0.049 | U | | <0.0028 | U | | 0.052 | | J | <0.015 | U | | <0.016 | J | U | <0.0079 | U | |
| | 25.5 ft | VMP-9-25.5-082610 | 8/26/2010 | <1.9 | U | | <1 | U | | 3.2 | | | <1.4 | U | | <2.1 | U | | <0.78 | U | | <0.44 | U | | | | | <0.59 | U | | <0.63 | U | | <1.3 | U | |
| | | VMP-9-25.5-082610-DUP | 8/26/2010 | <2 | U | | <1.1 | U | | 3.3 | | | <1.4 | U | | <2.2 | U | | <0.84 | U | | <0.48 | U | | | | | <0.64 | U | | <0.67 | U | | <1.4 | U | |
| | | VMP-9-25.5-111910 | 11/19/2010 | <2.2 | U | | <1.2 | U | | 1.9 | | | <1.5 | U | | <2.4 | U | | <0.89 | U | | <0.51 | U | | | | | <0.68 | U | | <0.72 | U | | <1.4 | U | |
| | | VMP-9-25.5-020911 | 2/9/2011 | <1.2 | U | | <0.65 | U | | 0.079 | J | | <0.84 | U | | <1.3 | U | | <0.49 | U | | <0.28 | U | | | | | <0.37 | U | | <0.39 | U | | <0.79 | U | |
| | | VMP-9-25.5-040811 | 4/8/2011 | 0.69 | | | <0.33 | U | | 0.82 | | | <0.43 | U | | <0.66 | U | | <0.25 | U | | <0.14 | U | | 2.4 | | | <0.75 | U | | 0.42 | J | | <0.4 | U | |
| | | VMP-9-25.5-080211 | 8/2/2011 | <1.3 | U | | <0.73 | U | | 0.68 | | J | <0.94 | U | | <1.4 | U | | <0.55 | U | | <0.31 | U | | 35 | | J | <1.7 | U | | <0.44 | U | | <0.89 | U | |
| | | VMP-9-25.5-110711 | 11/7/2011 | 1.4 | | | <0.64 | U | | 0.19 | J | | <0.83 | U | | 0.18 | J | | <0.48 | U | | <0.28 | U | | 4.4 | | | 1 | J | | 1.1 | J | | <0.78 | U | |
| | | VMP-9-25.5-110711-DUP | 11/7/2011 | 1.6 | | | <0.56 | U | | 0.19 | J | | <0.72 | U | | 0.13 | J | | <0.42 | U | | <0.24 | U | | 6.1 | | | 1.3 | | | 1.3 | J | | <0.68 | U | |
| | | VMP-9-25.5-012612 | 1/26/2012 | <0.3 | U | | <0.67 | U | | 0.24 | | J | <0.22 | U | | <1.3 | U | | <0.12 | U | | <0.071 | U | | 10 | | J | <0.38 | U | | <0.1 | U | | <0.2 | U | |
| | | VMP-9-25.5-041112 | 4/11/2012 | 0.011 | J | | 0.00074 | J | | 0.0038 | | | 0.0022 | J | | <0.0094 | U | | <0.036 | U | | <0.002 | U | | <0.0087 | U | | 0.0022 | J | | 0.002 | J | J | <0.0058 | U | |
| | | VMP-9-25.5-071312 | 7/13/2012 | 0.1 | | | <0.0051 | U | | 0.062 | | | <0.0066 | U | | <0.01 | U | | <0.038 | U | UJ | <0.0022 | U | | <0.0094 | U | | 0.032 | | | <0.012 | J | U | <0.0062 | U | |
| | | VMP-9-25.5-071312-Dup | 7/13/2012 | 0.1 | | | <0.0049 | U | | 0.061 | | | <0.0064 | U | | <0.0099 | U | | <0.037 | U | UJ | <0.0021 | U | | <0.0091 | U | | 0.032 | | | <0.012 | J | U | <0.006 | U | |
| | | VMP-9-25.5-101012 | 10/10/2012 | 0.019 | J | | <0.0068 | U | | 0.005 | | | <0.0088 | U | | <0.014 | U | | <0.051 | U | | <0.0029 | U | | <0.012 | U | | <0.016 | U | | <0.016 | J | U | <0.0083 | U | |
| | | VMP-9-25.5-013013 | 1/30/2013 | 0.02 | J | | <0.0073 | U | | 0.0018 | J | | <0.0094 | U | | <0.014 | U | | <0.055 | U | | <0.0031 | U | | <0.013 | U | | <0.017 | U | | 0.0028 | J | | <0.0089 | U | |
| | 38.5 ft | VMP-9-38.5-020911 | 2/9/2011 | <2 | U | | <1.1 | U | | 0.89 | | | <1.4 | U | | <2.2 | U | | <0.81 | U | | <0.46 | U | | | | | <0.62 | U | | <0.65 | U | | <1.3 | U | |
| | | VMP-9-38.5-040811 | 4/8/2011 | 2.4 | J | | <1.4 | U | | 4 | | | <1.9 | U | | <2.9 | U | | <1.1 | U | | <0.62 | U | | 39 | | | <3.3 | U | | 1.8 | J | | <1.7 | U | |
| | | VMP-9-38.5-012612 | 1/26/2012 | <0.4 | U | | <0.87 | U | | 1.1 | | J | <0.28 | U | | <1.7 | U | | <0.16 | U | | <0.093 | U | | 12 | | J | <0.5 | U | | <0.13 | U | | <0.26 | U | |
| | | VMP-9-38.5-041112 | 4/11/2012 | 0.019 | J | | <0.0042 | U | | 0.01 | | | 0.0012 | J | | <0.0083 | U | | <0.031 | U | | <0.0018 | U | | <0.0076 | U | | 0.0026 | J | | 0.0038 | J | J | <0.0051 | U | |
| | | VMP-9-38.5-071312 | 7/13/2012 | 0.11 | | | <0.0055 | U | | 0.21 | | | <0.0071 | U | | <0.011 | U | | <0.041 | J | UJ | <0.0023 | U | | 0.0066 | J | | 0.041 | | | <0.013 | J | U | <0.0067 | U | |
| | | VMP-9-38.5-101012 | 10/10/2012 | 0.019 | J | | <0.02 | U | | 1.2 | | | <0.026 | U | | <0.041 | U | | <0.15 | U | | <0.0087 | U | | 0.23 | | | <0.046 | U | | <0.049 | J | U | <0.025 | U | |
| | | VMP-9-38.5-013013 | 1/30/2013 | 0.015 | J | | <0.0073 | U | | 0.0018 | J | | <0.0094 | U | | <0.014 | U | | <0.055 | U | | <0.0031 | U | | 0.0068 | J | | <0.017 | U | | <0.018 | J | U | <0.0089 | U | |
| VMP-18 | 8.5 ft | VMP-18-8.5 | 6/18/2010 | 0.042 | | | <0.007 | U | | 0.0048 | | | <0.009 | U | | <0.015 | U | | <0.005 | U | | <0.003 | U | | | | | 0.0044 | | | <0.004 | J | U | <0.009 | U | |
| | | VMP-18-8.5-090710 | 9/7/2010 | 0.013 | | | <0.0067 | J | U | 0.093 | | | 0.0027 | J | | <0.013 | U | | <0.005 | J | U | <0.0028 | U | | | | | 0.0032 | J | | 0.0069 | | | 0.0012 | J | |
| | | VMP-18-8.5-111910 | 11/19/2010 | 0.0077 | J | | <0.0056 | U | | <0.0034 | U | | <0.0072 | U | | <0.011 | U | | <0.0042 | U | | <0.0024 | U | | | | | 0.0013 | J | | <0.0034 | U | | <0.0068 | U | |
| | | VMP-18-8.5-020711 | 2/7/2011 | 0.18 | | J | <0.0062 | U | | 0.0024 | J | | <0.008 | U | | <0.012 | U | | <0.0046 | U | | <0.0026 | U | | | | | 0.0049 | | | <0.0037 | J | U | <0.0075 | U | |
| | | VMP-18-8.5-020711-DUP | 2/7/2011 | 0.012 | | J | <0.0059 | U | | 0.0013 | J | | <0.0077 | U | | <0.012 | U | | <0.0044 | U | | <0.0025 | U | | | | | 0.0016 | J | | <0.0036 | U | | <0.0072 | U | |
| | | VMP-18-8.5-040711 | 4/7/2011 | 0.015 | | | <0.0066 | J | U | 0.084 | | | <0.0086 | U | | <0.013 | U | | <0.005 | U | | <0.0028 | U | | 0.0069 | J | | 0.0023 | J | | <0.016 | J | U | <0.0081 | U | |
| | | VMP-18-8.5-072811 | 7/28/2011 | 0.075 | | | <0.0071 | U | | 0.096 | | | <0.0092 | U | | <0.014 | U | | <0.0054 | U | | <0.003 | U | | <0.013 | U | | 0.025 | | | <0.017 | U | | <0.0087 | U | |
| | | VMP-18-8.5-110711 | 11/7/2011 | 0.015 | | | <0.0046 | U | | 0.00097 | J | | <0.006 | U | | <0.0092 | U | | <0.0035 | U | | <0.002 | U | | <0.0085 | U | | 0.0065 | J | | <0.011 | U | | <0.0056 | U | |
| | | VMP-18-8.5-012312 | 1/23/2012 | 0.0081 | J | | <0.005 | U | | 0.0012 | J | | <0.0065 | U | | <0.01 | U | | <0.0038 | U | | <0.0021 | U | | <0.0092 | U | | 0.007 | J | | <0.012 | J | U | <0.0061 | U | |
| | | VMP-18-8.5-041012 | 4/10/2012 | 0.056 | | | <0.0052 | U | | 0.039 | | | <0.0067 | U | | <0.01 | U | | <0.039 | U | | <0.0022 | U | | 0.0047 | J | | 0.071 | | | <0.012 | U | | <0.0063 | U | |
| | | VMP-18-8.5-071212 | 7/12/2012 | 0.079 | | | <0.0051 | U | UJ | 0.12 | | | <0.0066 | U | | <0.01 | U | | <0.038 | U | | <0.0022 | U | | 0.0046 | J | | 0.032 | | | <0.012 | U | | <0.0062 | U | |
| | | VMP-18-8.5-100912 | 10/9/2012 | 0.1 | | | <0.0068 | U | | 0.0064 | | | <0.0088 | U | | <0.014 | U | | <0.051 | U | | <0.0029 | U | | <0.012 | U | | 0.013 | J | | <0.016 | U | | <0.0083 | U | |
| | | VMP-18-8.5-012313 | 1/23/2013 | 0.0051 | J | | <0.0075 | U | | 0.025 | | | <0.0097 | U | | <0.015 | U | | <0.056 | U | | <0.0032 | U | | <0.014 | U | | <0.017 | U | | <0.018 | U | | <0.0091 | U | |
| VMP-19 | 5 ft | VMP-19-5 | 6/18/2010 | 0.042 | | | <0.007 | U | | 0.02 | | | <0.009 | U | | <0.014 | U | | <0.005 | U | | <0.003 | U | | | | | 0.0054 | | | <0.004 | J | U | <0.008 | U | |
| | | VMP-19-5-090110 | 9/1/2010 | 0.044 | | | <0.0067 | U | | 0.019 | | | <0.0086 | U | | <0.013 | U | | <0.005 | U | | <0.0028 | U | | | | | 0.013 | | | <0.004 | J | U | <0.0081 | U | |
| | | VMP-19-5-111510 | 11/15/2010 | 0.02 | | | <0.0071 | U | | 0.0092 | | | <0.0092 | U | | <0.014 | U | | <0.0054 | J | U | <0.003 | U | | | | | 0.0013 | J | | 0.0013 | J | | <0.0087 | U | |
| | | VMP-19-5-020411 | 2/4/2011 | 0.0091 | J | | <0.0063 | J | U | 0.015 | | | <0.0081 | U | | <0.012 | U | | <0.0047 | U | | <0.0027 | U | | | | | <0.0036 | U | | <0.0038 | J | U | <0.0076 | U | |
| | | VMP-19-5-040711 | 4/7/2011 | 0.01 | J | | <0.007 | U | | 0.76 | | | <0.009 | U | | <0.014 | U | | <0.0052 | U | | <0.003 | U | | 0.0052 | J | | 0.0017 | J | | 0.0013 | J | | <0.0085 | U | |
| | | VMP-19-5-080911 | 8/9/2011 | 0.07 | | J | <0.0077 | J | U | 0.48 | | | <0.0099 | U | | <0.015 | J | U | <0.0057 | U | | <0.0033 | U | | 0.068 | | J | 0.017 | J | | <0.018 | J | U | <0.0093 | U | |
| | | VMP-19-5-080911-DUP | 8/9/2011 | 0.054 | | J | <0.0073 | J | U | 0.41 | | | <0.0094 | U | | <0.014 | U | | <0.0055 | U | | <0.0031 | U | | 0.043 | | J | 0.018 | | | <0.018 | J | U | <0.0089 | U | |
| | | VMP-19-5-110811 | 11/8/2011 | 0.018 | | | <0.0051 | U | | 0.0066 | | | <0.0066 | U | | <0.01 | U | | <0.0038 | U | | <0.0022 | U | | 0.015 | | | 0.0036 | J | | <0.012 | U | | <0.0062 | U | |
| | | VMP-19-5-012612 | 1/26/2012 | 0.0089 | | | <0.0044 | U | | 0.001 | J | | <0.0057 | U | | <0.0088 | U | | <0.0033 | U | | <0.0019 | U | | 0.0061 | J | | 0.0012 | J | | <0.011 | U | | <0.0054 | U | |
| | | VMP-19-5-041012 | 4/10/2012 | 0.031 | | | <0.0051 | U | | 0.028 | | | <0.0066 | U | | <0.01 | U | | <0.038 | U | | <0.0022 | U | | 0.0037 | J | | 0.06 | | | <0.012 | U | | <0.0062 | U | |
| | | VMP-19-5-071112 | 7/11/2012 | 0.085 | | | <0.0058 | U | UJ | 0.082 | | | <0.0075 | U | | <0.012 | U | | <0.043 | U | | <0.0025 | U | | <0.011 | U | | 0.03 | | | <0.014 | U | | <0.007 | U | |
| | | VMP-19-5-100912 | 10/9/2012 | 0.032 | J | | <0.0077 | U | | 0.0033 | J | | <0.0099 | U | | <0.015 | U | | <0.057 | U | | <0.0033 | U | | <0.014 | U | | <0.017 | U | | 0.0028 | J | | <0.0093 | U | |
| | | VMP-19-5-013113 | 1/31/2013 | 0.023 | J | | <0.0067 | U | | 1.5 | | | <0.0086 | U | | <0.013 | U | | <0.05 | U | | <0.0028 | U | | 0.057 | | | <0.015 | U | | <0.016 | J | U | <0.0081 | U | |

**TABLE 5**
**CUMULATIVE SUMMARY OF SOIL VAPOR ANALYTICAL DETECTIONS AND SCREENING RESULTS: VILLAGE - VOCS**

| Location | Depth | Sample ID | Sample Date | Acetone | | | alpha-Chlorotoluene | | | Benzene | | | Bromodichloromethane | | | Bromoform | | | Bromomethane | | | 1,3-Butadiene | | | Butane | | | 2-Butanone | | | Carbon disulfide | | | Carbon tetrachloride | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | 750000 | | | | | | 0.37 | | | 450000 | | | 11 | | | 6.9 | | | | | | | | | 6400 | | | 780 | | | 0.21 | | |
| | | | | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals |
| VMP-20 | 5 ft | VMP-20-5-031411 | 3/14/2011 | 0.032 | | | <0.0063 | U | | 0.27 | | | <0.0081 | U | | <0.012 | U | | <0.0047 | U | | <0.0027 | U | | | | | 0.0026 | J | | 0.1 | | | <0.0076 | U | |
| | | VMP-20-5-041511 | 4/15/2011 | 0.019 | J | | <0.069 | U | | 0.037 | J | | <0.089 | U | | <0.14 | U | | <0.052 | U | | <0.029 | U | | 17 | | | <0.16 | U | | 0.024 | J | | <0.084 | U | |
| | | VMP-20-5-072511 | 7/25/2011 | 0.036 | | | <0.0073 | U | UJ | 0.038 | | | <0.0094 | U | | <0.014 | U | | <0.0055 | U | | <0.0031 | U | | <0.013 | U | | 0.016 | | | 0.011 | J | | <0.0089 | U | |
| | | VMP-20-5-110111 | 11/1/2011 | 0.017 | | | <0.0042 | U | | 0.015 | | | <0.0054 | U | | <0.0083 | U | | <0.0031 | U | | <0.0018 | U | | 0.004 | J | | 0.0037 | J | | <0.01 | J | U | <0.0051 | U | |
| | | VMP-20-5-012312 | 1/23/2012 | 0.012 | J | | <0.02 | U | | 0.19 | | | <0.026 | U | | <0.04 | U | | <0.015 | U | | <0.0086 | U | | 0.14 | | | 0.0054 | J | | 0.0058 | J | | <0.024 | U | |
| | | VMP-20-5-041012 | 4/10/2012 | 0.07 | | | <0.0045 | U | | 0.0043 | | | <0.0059 | U | | <0.009 | U | | <0.034 | U | | <0.0019 | U | | 0.0037 | J | | 0.031 | | | <0.011 | U | | <0.0055 | U | |
| | | VMP-20-5-071112 | 7/11/2012 | 0.031 | | | <0.006 | U | UJ | <0.0037 | U | | <0.0078 | U | | <0.012 | U | | <0.045 | U | | <0.0026 | U | | <0.011 | U | | 0.0039 | J | | 0.012 | J | | <0.0073 | U | |
| | | VMP-20-5-073112 | 7/31/2012 | 0.15 | | | <0.0051 | U | | 0.048 | | | <0.0066 | U | | <0.01 | U | | <0.038 | U | | <0.0022 | U | | <0.0093 | U | | 0.023 | | | <0.012 | U | | <0.0062 | U | |
| | | VMP-20-5-100412 | 10/4/2012 | 0.021 | J | | <0.0075 | U | | 0.0082 | | | <0.0097 | U | | <0.015 | U | | <0.056 | U | | <0.0032 | U | | <0.014 | U | | <0.017 | U | | 0.0047 | J | J | <0.0091 | U | |
| | | VMP-20-5-020713 | 2/7/2013 | 0.024 | J | | <0.0064 | U | | 0.035 | | | <0.0083 | U | | <0.013 | U | | <0.048 | U | | <0.0027 | U | | 0.51 | | | 0.0028 | J | | <0.015 | J | U | <0.0078 | U | |
| | 10 ft | VMP-20-10-031411 | 3/14/2011 | 0.021 | | | <0.0063 | U | | 0.21 | | | 0.0023 | J | | <0.012 | U | | <0.0047 | U | | <0.0027 | U | | | | | 0.0035 | J | | 0.0041 | J | | <0.0076 | U | |
| | | VMP-20-10-041511 | 4/15/2011 | 0.015 | J | | <0.063 | U | | 0.046 | | | <0.081 | U | | <0.12 | U | | <0.047 | U | | <0.027 | U | | 1.1 | | | <0.14 | U | | <0.038 | U | | <0.076 | U | |
| | | VMP-20-10-072511 | 7/25/2011 | 0.022 | | | <0.0067 | U | UJ | 0.015 | | | 0.0015 | J | | <0.013 | U | | <0.005 | U | | <0.0028 | U | | <0.012 | U | | 0.018 | | | <0.016 | J | U | <0.0081 | U | |
| | | VMP-20-10-110111 | 11/1/2011 | 0.023 | | | <0.0044 | U | | 0.0018 | J | | <0.0057 | U | | <0.0088 | U | | <0.0033 | U | | <0.0019 | U | | <0.0081 | U | | 0.0019 | J | | <0.011 | J | U | <0.0054 | U | |
| | | VMP-20-10-012312 | 1/23/2012 | 0.0099 | | | <0.0046 | U | | 0.045 | | | <0.006 | U | | <0.0092 | U | | <0.0035 | U | | <0.002 | U | | <0.0085 | U | | 0.0029 | J | | <0.011 | J | U | <0.0056 | U | |
| | | VMP-20-10-041012 | 4/10/2012 | 0.086 | | | <0.0044 | U | | 0.0043 | | | <0.0057 | U | | <0.0088 | U | | <0.033 | U | | <0.0019 | U | | 0.0033 | J | | 0.06 | | | 0.0015 | J | J | <0.0054 | U | |
| | | VMP-20-10-071112 | 7/11/2012 | 0.035 | | | <0.0051 | U | UJ | 0.0033 | | | <0.0066 | U | | <0.01 | U | | <0.038 | U | | <0.0022 | U | | <0.0093 | U | | 0.0077 | J | | 0.0045 | J | | <0.0062 | U | |
| | | VMP-20-10-100412 | 10/4/2012 | 0.017 | J | | <0.007 | U | | 0.005 | | | <0.009 | U | | <0.014 | U | | <0.052 | U | | <0.003 | U | | <0.013 | U | | <0.016 | U | | <0.017 | U | | <0.0085 | U | |
| | | VMP-20-10-012213 | 1/22/2013 | 0.012 | J | | <0.0064 | U | | 0.0018 | J | | <0.0083 | U | | <0.013 | U | | <0.048 | U | | <0.0027 | U | | <0.012 | U | | <0.014 | U | | <0.015 | J | U | <0.0078 | U | |
| | 25 ft | VMP-20-25-031411 | 3/14/2011 | 0.01 | J | | <0.0062 | U | | 0.35 | | | <0.008 | U | | <0.012 | U | | <0.0046 | U | | <0.0026 | U | | | | | 0.0011 | J | | <0.015 | J | U | <0.0075 | U | |
| | | VMP-20-25-041511 | 4/15/2011 | <0.13 | U | | <0.071 | U | | <0.044 | U | | <0.092 | U | | <0.14 | U | | <0.054 | U | | <0.03 | U | | 0.58 | | | <0.16 | U | | <0.043 | U | | <0.087 | U | |
| | | VMP-20-25-072611 | 7/26/2011 | <0.87 | U | | <0.48 | U | UJ | 0.18 | J | | <0.62 | U | | <0.95 | U | | <0.36 | U | | <0.2 | U | | <0.87 | U | | <1.1 | U | | <0.29 | U | | <0.58 | U | |
| | | VMP-20-25-110511 | 11/5/2011 | 0.042 | | | <0.0043 | U | | 0.004 | | | <0.0056 | U | | <0.0087 | J | U | <0.0033 | U | | <0.0018 | U | | <0.008 | U | | 0.0085 | J | | <0.01 | J | U | <0.0053 | U | |
| | | VMP-20-25-012312 | 1/23/2012 | 0.0091 | | | <0.0048 | U | | 0.0042 | | | <0.0063 | U | | <0.0097 | U | | <0.0036 | U | | <0.0021 | U | | <0.0089 | U | | 0.0042 | J | | <0.012 | J | U | <0.0059 | U | |
| | | VMP-20-25-041012 | 4/10/2012 | 0.055 | | | <0.0045 | U | | 0.004 | | | <0.0059 | U | | <0.009 | U | | <0.034 | U | | <0.0019 | U | | 0.0074 | J | | 0.039 | | | <0.011 | U | | <0.0055 | U | |
| | | VMP-20-25-041012-Dup | 4/10/2012 | 0.054 | | | <0.0046 | U | | 0.0041 | | | <0.006 | U | | <0.0092 | U | | <0.035 | U | | <0.002 | U | | 0.0067 | J | | 0.037 | | | <0.011 | U | | <0.0056 | U | |
| | | VMP-20-25-071112 | 7/11/2012 | 0.034 | | | <0.0052 | U | UJ | 0.001 | J | | <0.0067 | U | | <0.01 | U | | <0.039 | U | | <0.0022 | U | | <0.0096 | U | | 0.006 | J | | 0.0068 | J | | <0.0063 | U | |
| | | VMP-20-25-100412 | 10/4/2012 | 0.033 | J | | <0.0077 | U | | 0.0014 | J | | <0.0099 | U | | <0.015 | U | | <0.057 | U | | <0.0033 | U | | <0.014 | U | | <0.017 | U | | <0.018 | U | | <0.0093 | U | |
| | | VMP-20-25-012213 | 1/22/2013 | 0.011 | J | | <0.0064 | U | | <0.0039 | U | | <0.0083 | U | | <0.013 | U | | <0.048 | J | U | <0.0027 | U | | 0.003 | J | | <0.014 | U | | <0.015 | J | U | <0.0078 | U | |
| | 39.5 ft | VMP-20-39.5-100412 | 10/4/2012 | 44 | | | <1.9 | U | | 0.28 | J | | <2.4 | U | | <3.7 | U | | <14 | U | | <0.8 | U | | 1.5 | J | | <4.2 | U | | 4.2 | J | | <2.3 | U | |
| | | VMP-20-39.5-012313 | 1/23/2013 | <2 | U | | <1.1 | U | | 0.24 | J | | <1.4 | U | | <2.1 | U | | <0.8 | U | | <0.46 | U | | 12 | | | <2.4 | U | | <0.64 | U | | <1.3 | U | |
| VMP-21 | 5 ft | VMP-21-5-020911 | 2/9/2011 | <4.4 | U | | <2.4 | U | | <1.5 | U | | <3.1 | U | | <4.8 | U | | <1.8 | U | | <1 | U | | | | | <1.4 | U | | <1.4 | U | | <2.9 | U | |
| | | VMP-21-5-020911-DUP | 2/9/2011 | <7.6 | U | | <4.1 | U | | <2.5 | U | | <5.3 | U | | <8.2 | U | | <3.1 | U | | <1.8 | U | | | | | <2.3 | U | | <2.5 | U | | <5 | U | |
| | | VMP-21-5-041311 | 4/13/2011 | 0.0092 | J | | 0.001 | J | | 0.84 | | | <0.0088 | U | | <0.014 | U | | <0.0051 | U | | <0.0029 | U | | 0.41 | | | 0.0021 | J | | 0.0064 | J | | <0.0083 | U | |
| | | VMP-21-5-072511 | 7/25/2011 | 0.029 | | | <0.0071 | U | UJ | 0.019 | | | <0.0092 | U | | <0.014 | U | | <0.0054 | U | | <0.003 | U | | <0.013 | U | | 0.02 | | | <0.017 | J | U | <0.0087 | U | |
| | | VMP-21-5-110111 | 11/1/2011 | 0.017 | | | <0.0059 | U | | 0.011 | | | <0.0076 | U | | <0.012 | U | | <0.0044 | U | | <0.0025 | U | | <0.011 | U | | 0.0039 | J | | <0.014 | J | U | <0.0072 | U | |
| | | VMP-21-5-012312 | 1/23/2012 | 0.008 | J | | <0.005 | U | | 0.00067 | J | | <0.0065 | U | | <0.01 | U | | <0.0038 | U | | <0.0021 | U | | <0.0092 | U | | 0.0034 | J | | <0.012 | J | U | <0.0061 | U | |
| | | VMP-21-5-012312-DUP | 1/23/2012 | 0.0092 | | | <0.0046 | U | | 0.00091 | J | | <0.006 | U | | <0.0092 | U | | <0.0035 | U | | <0.002 | U | | <0.0085 | U | | 0.0034 | J | | <0.011 | J | U | <0.0056 | U | |
| | | VMP-21-5-042412 | 4/24/2012 | 0.023 | J | | <0.0095 | U | | 0.58 | | | <0.012 | U | | <0.019 | U | | <0.071 | U | | <0.004 | U | | 0.025 | | | 0.01 | J | | <0.023 | J | U | <0.012 | U | |
| | | VMP-21-5-071012 | 7/10/2012 | 0.12 | | | <0.0055 | U | UJ | 0.003 | J | | <0.0071 | U | | <0.011 | U | | <0.041 | U | | <0.0023 | U | | <0.01 | U | | 0.02 | | | <0.013 | U | | <0.0067 | U | |
| | | VMP-21-5-100412 | 10/4/2012 | 0.023 | J | | <0.008 | U | | 0.0018 | J | | <0.01 | U | | <0.016 | U | | <0.06 | U | | <0.0034 | U | | <0.015 | U | | 0.006 | J | | <0.019 | U | | <0.0098 | U | |
| | | VMP-21-5-020613 | 2/6/2013 | 0.012 | J | | <0.0073 | U | | 0.002 | J | | <0.0094 | U | | <0.014 | U | | <0.055 | U | | <0.0031 | U | | <0.013 | U | | 0.0027 | J | | <0.018 | J | U | <0.0089 | U | |
| | 10 ft | VMP-21-10-021011 | 2/10/2011 | <4 | U | | <2.2 | U | | <1.3 | U | | <2.8 | U | | <4.3 | U | | <1.6 | U | | <0.93 | U | | | | | <1.2 | U | | <1.3 | U | | <2.6 | U | |
| | | VMP-21-10-041311 | 4/13/2011 | 0.14 | J | | <0.27 | U | | 0.066 | J | | <0.36 | U | | <0.55 | U | | <0.2 | U | | <0.12 | U | | 7.6 | | | 0.046 | J | | 0.065 | J | | <0.33 | U | |
| | | VMP-21-10-072511 | 7/25/2011 | 0.083 | | | <0.015 | U | UJ | 0.012 | | | <0.02 | U | | <0.03 | U | | <0.011 | J | U | <0.0065 | U | | <0.028 | U | | 0.01 | J | | <0.036 | J | U | <0.018 | U | |
| | | VMP-21-10-110111 | 11/1/2011 | 0.015 | | | <0.0044 | U | | 0.0023 | J | | <0.0057 | U | | <0.0088 | U | | <0.0033 | U | | <0.0019 | U | | <0.0081 | U | | 0.0043 | J | | <0.011 | J | U | <0.0054 | U | |
| | | VMP-21-10-012312 | 1/23/2012 | 0.022 | | | <0.005 | U | | 0.017 | | | <0.0065 | U | | <0.01 | U | | <0.0038 | U | | <0.0021 | U | | <0.0092 | U | | 0.0041 | J | | <0.012 | J | U | <0.0061 | U | |
| | | VMP-21-10-040912 | 4/9/2012 | 0.028 | | | <0.0045 | U | | 0.041 | | | <0.0059 | U | | <0.009 | U | | <0.034 | U | | <0.0019 | U | | 0.008 | J | | 0.0077 | J | | 0.0018 | J | J | <0.0055 | U | |
| | | VMP-21-10-071012 | 7/10/2012 | 0.055 | | | <0.0052 | U | UJ | 0.0018 | J | | <0.0067 | U | | <0.01 | U | | <0.039 | U | | <0.0022 | U | | <0.0096 | U | | 0.0065 | J | | 0.0043 | J | | <0.0063 | U | |
| | | VMP-21-10-100412 | 10/4/2012 | 0.024 | J | | <0.0073 | U | | 0.0076 | | | <0.0094 | U | | <0.014 | U | | <0.055 | U | | <0.0031 | U | | <0.013 | U | | 0.0065 | J | | <0.018 | U | | <0.0089 | U | |
| | | VMP-21-10-020513 | 2/5/2013 | 0.0065 | J | | <0.007 | U | | 0.041 | | | <0.009 | U | | <0.014 | U | | <0.052 | U | | <0.003 | U | | <0.013 | U | | <0.016 | U | | <0.017 | J | U | <0.0085 | U | |
| | | VMP-21-10-020513-DUP | 2/5/2013 | 0.0063 | J | | <0.0065 | U | | 0.035 | | | <0.0084 | U | | <0.013 | U | | <0.049 | U | | <0.0028 | U | | <0.012 | U | | <0.015 | U | | <0.016 | J | U | <0.0079 | U | |
| | 25 ft | VMP-21-25-021011 | 2/10/2011 | <11 | U | | <6 | U | | 1.7 | J | | <7.8 | U | | <12 | U | | <4.5 | U | | <2.6 | U | | | | | <3.4 | U | | <3.6 | U | | <7.3 | U | |
| | | VMP-21-25-041411 | 4/14/2011 | 12 | J | | <21 | U | | <13 | U | | <27 | U | | <42 | U | | <16 | U | | <9 | U | | 5400 | | | <48 | U | | <13 | U | | <26 | U | |
| | | VMP-21-25-041411-DUP | 4/14/2011 | 5.2 | J | | <21 | U | | <13 | U | | <27 | U | | <42 | U | | <16 | U | | <9 | U | | 5400 | | | <48 | U | | <13 | U | | <26 | U | |
| | | VMP-21-25-072611 | 7/26/2011 | <12 | U | | <6.8 | U | UJ | 1.3 | J | | <8.8 | U | | <14 | U | | <5.1 | U | | <2.9 | U | | | | | <16 | U | | <4.1 | U | | <8.3 | U | |
| | | VMP-21-25-110511 | 11/5/2011 | 5 | J | | <4.3 | U | | 0.5 | J | | <5.6 | U | | <8.7 | U | | <3.3 | U | | <1.8 | U | | 290 | | | 4.1 | J | | 4.5 | J | | <5.3 | U | |
| | | VMP-21-25-012412 | 1/24/2012 | <0.11 | J | U | <0.24 | U | | 0.027 | J | | <0.078 | U | | <0.48 | U | | <0.045 | U | | <0.026 | U | | 0.047 | J | | <0.14 | U | | <0.036 | U | | <0.073 | U | |
| | | VMP-21-25-040912 | 4/9/2012 | 0.09 | | | <0.0047 | U | | 0.048 | | | <0.0061 | U | | <0.0094 | U | | <0.036 | U | UJ | <0.002 | U | | <0.0087 | U | | <0.011 | U | | 0.0028 | J | | <0.0058 | U | |
| | | VMP-21-25-071112 | 7/11/2012 | 0.028 | | | <0.0047 | U | UJ | 0.00098 | J | | <0.0061 | U | | <0.0094 | U | | <0.036 | U | | <0.002 | U | | 0.011 | | | 0.004 | J | | 0.0046 | J | | <0.0058 | U | |
| | | VMP-21-25-100412 | 10/4/2012 | 0.027 | J | | <0.0075 | U | | 0.0078 | | | <0.0097 | U | | <0.015 | U | | <0.056 | U | | <0.0032 | U | | 0.0075 | J | | 0.0074 | J | | <0.018 | U | | <0.0091 | U | |
| | | VMP-21-25-020513 | 2/5/2013 | 0.011 | J | | <0.0067 | U | | 0.035 | | | <0.0086 | U | | <0.013 | U | | <0.05 | U | | <0.0028 | U | | 0.0031 | J | | <0.015 | U | | <0.016 | J | U | <0.0081 | U | |
| | | VMP-21-25-020513-DUP | 2/5/2013 | 0.0077 | J | | <0.007 | U | | 0.043 | | | <0.009 | U | | <0.014 | U | | <0.052 | U | | <0.003 | U | | <0.013 | U | | <0.016 | U | | <0.017 | J | U | <0.0085 | U | |
| | 33 ft | VMP-21-33-021011 | 2/10/2011 | <11 | U | | <6 | U | | 1.8 | J | | <7.8 | U | | <12 | U | | <4.5 | U | | <2.6 | U | | | | | <3.4 | U | | <3.6 | U | | <7.3 | U | |
| | | VMP-21-33-041411 | 4/14/2011 | 8.8 | J | | <20 | U | | <12 | U | | <26 | U | | <41 | U | | <15 | U | | <8.7 | U | | 5200 | | | <46 | U | | <12 | U | | <25 | U | |
| | | VMP-21-33-110511 | 11/5/2011 | 1.2 | J | | <0.99 | U | | 0.14 | J | | <1.3 | U | | 0.27 | J | | <0.74 | U | | <0.42 | U | | 20 | | | 0.93 | J | | 1.1 | J | | <1.2 | U | |
| | | VMP-21-33-012412 | 1/24/2012 | <0.26 | U | | <0.57 | U | | 0.13 | | J | <0.18 | U | | <1.1 | U | | <0.11 | U | | <0.06 | U | | 0.48 | | J | <0.32 | U | | <0.085 | U | | <0.17 | U | |
| | | VMP-21-33-042412 | 4/24/2012 | 0.011 | J | | <0.0048 | U | | 0.41 | | | <0.0063 | U | | <0.0097 | U | | <0.036 | U | | <0.0021 | U | | 0.086 | | | 0.0055 | J | | <0.012 | J | U | <0.0059 | U | |
| | | VMP-21-33-071112 | 7/11/2012 | 0.044 | | | <0.0051 | U | UJ | 0.0011 | J | | <0.0066 | U | | <0.01 | U | | <0.038 | U | | <0.0022 | U | | 0.019 | | | 0.007 | J | | 0.0042 | J | | <0.0062 | U | |
| | | VMP-21-33-100412 | 10/4/2012 | 0.026 | J | | <0.0073 | U | | 0.012 | | | <0.0094 | U | | <0.014 | U | | <0.055 | U | | <0.0031 | U | | 0.006 | J | | 0.0074 | J | | <0.018 | U | | <0.0089 | U | |
| | | VMP-21-33-020513 | 2/5/2013 | 0.0058 | J | | <0.0068 | U | | 0.0024 | J | | <0.0088 | U | | <0.014 | U | | <0.051 | U | | <0.0029 | U | | <0.012 | U | | <0.016 | U | | <0.016 | J | U | <0.0083 | U | |

SEE LAST PAGE OF TABLE FOR NOTES

**TABLE 5**
**CUMULATIVE SUMMARY OF SOIL VAPOR ANALYTICAL DETECTIONS AND SCREENING RESULTS: VILLAGE - VOCS**

| Location | Depth | Sample ID | Sample Date | Acetone | | | alpha-Chlorotoluene | | | Benzene | | | Bromodichloromethane | | | Bromoform | | | Bromomethane | | | 1,3-Butadiene | | | Butane | | | 2-Butanone | | | Carbon disulfide | | | Carbon tetrachloride | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | 750000 | | | | | | 0.37 | | | 450000 | | | 11 | | | 6.9 | | | | | | | | | 6400 | | | 780 | | | 0.21 | | |
| | | | | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals |
| VMP-22 | 5 ft | VMP-22-5-021111 | 2/11/2011 | <0.24 | U | | <0.13 | U | | 0.029 | J | | <0.17 | U | | <0.26 | U | | <0.1 | U | | <0.057 | U | | | | | <0.076 | U | | <0.08 | U | | <0.16 | U | |
| | | VMP-22-5-041811 | 4/18/2011 | <0.12 | U | | <0.065 | U | | 0.024 | J | | <0.084 | U | | <0.13 | U | | <0.049 | U | | <0.028 | U | | 0.17 | | | <0.15 | U | | <0.039 | U | | <0.079 | U | |
| | | VMP-22-5-072611 | 7/26/2011 | 0.026 | | | <0.0077 | U | UJ | 0.12 | | | <0.0099 | U | | <0.015 | U | | <0.0057 | J | U | <0.0033 | U | | 0.22 | | | 0.017 | J | | <0.018 | J | U | <0.0093 | U | |
| | | VMP-22-5-110111 | 11/1/2011 | 0.032 | | | <0.0043 | U | | 0.012 | | | <0.0056 | U | | <0.0087 | U | | <0.0033 | U | | <0.0018 | U | | <0.008 | U | | 0.0063 | J | | <0.01 | J | U | <0.0053 | U | |
| | | VMP-22-5-012412 | 1/24/2012 | 0.021 | | J | <0.0046 | U | | 0.11 | | J | <0.0059 | U | | <0.0091 | U | | <0.0034 | U | | <0.002 | U | | 0.024 | | J | 0.0047 | J | J | <0.011 | J | U | <0.0056 | U | |
| | | VMP-22-5-040912 | 4/9/2012 | 0.033 | | | <0.0051 | U | | 0.0085 | | | <0.0066 | U | | <0.01 | U | | 0.039 | J | J | <0.0022 | U | | 0.014 | | | <0.012 | U | | 0.0047 | J | | <0.0062 | U | |
| | | VMP-22-5-070912 | 7/9/2012 | 0.034 | | | <0.0056 | U | UJ | 0.0012 | J | | <0.0073 | U | | <0.011 | U | | <0.042 | U | | <0.0024 | U | | <0.01 | U | | 0.0037 | J | | 0.0074 | J | | <0.0068 | U | |
| | | VMP-22-5-100312 | 10/3/2012 | 0.031 | | | <0.0065 | U | | 0.0025 | J | | <0.0084 | U | | <0.013 | U | | <0.049 | U | | <0.0028 | U | | 0.0051 | J | | 0.0044 | J | | <0.016 | U | | <0.0079 | U | |
| | | VMP-22-5-100312-Dup | 10/3/2012 | 0.04 | | | <0.0059 | U | | 0.0045 | | | <0.0077 | U | | <0.012 | U | | <0.044 | U | | <0.0025 | U | | 0.0072 | J | | 0.0079 | J | | <0.014 | U | | <0.0072 | U | |
| | | VMP-22-5-012413 | 1/24/2013 | 0.014 | J | | <0.0067 | U | | 0.0093 | | | <0.0086 | U | | <0.013 | U | | <0.05 | U | | <0.0028 | U | | <0.012 | U | | <0.015 | U | | <0.016 | J | U | <0.0081 | U | |
| | 10 ft | VMP-22-10-021111 | 2/11/2011 | <0.12 | U | | <0.063 | U | | 0.021 | J | | <0.082 | U | | <0.13 | U | | <0.047 | U | | <0.027 | U | | | | | <0.036 | U | | <0.038 | U | | <0.077 | U | |
| | | VMP-22-10-041811 | 4/18/2011 | <0.12 | U | | 0.068 | U | | 0.12 | | | <0.087 | U | | <0.13 | U | | <0.051 | U | | <0.029 | U | | 0.086 | J | | <0.15 | U | | <0.041 | U | | <0.082 | U | |
| | | VMP-22-10-072611 | 7/26/2011 | 0.015 | | J | <0.0078 | U | UJ | 0.03 | | | <0.01 | U | | <0.016 | U | | <0.0059 | J | U | <0.0034 | U | | 0.018 | | J | 0.011 | J | | <0.019 | J | U | <0.0095 | U | |
| | | VMP-22-10-072611-DUP | 7/26/2011 | 0.052 | | J | <0.0092 | U | UJ | 0.03 | | | <0.012 | U | | <0.018 | U | | <0.0069 | U | | <0.0039 | U | | 0.059 | | J | 0.023 | | | <0.022 | J | U | <0.011 | U | |
| | | VMP-22-10-110211 | 11/2/2011 | 0.013 | | | <0.0044 | U | | 0.006 | | | <0.0057 | U | | <0.0088 | U | | <0.0033 | U | | <0.0019 | U | | <0.0081 | U | | 0.0033 | J | | <0.011 | J | U | <0.0054 | U | |
| | | VMP-22-10-012412 | 1/24/2012 | 0.0061 | J | | <0.005 | U | | 0.02 | | | <0.0065 | U | | <0.01 | U | | <0.0038 | U | | <0.0021 | U | | <0.0092 | U | | 0.011 | J | | <0.012 | J | U | <0.0061 | U | |
| | | VMP-22-10-040912 | 4/9/2012 | 0.031 | | | <0.005 | U | | 0.0068 | | | <0.0065 | U | | <0.01 | U | | <0.037 | U | UJ | <0.0021 | U | | <0.0092 | U | | <0.011 | U | | 0.0032 | J | | <0.0061 | U | |
| | | VMP-22-10-070912 | 7/9/2012 | 0.017 | J | | <0.0056 | U | UJ | <0.0035 | U | | <0.0073 | U | | <0.011 | U | | <0.042 | U | | <0.0024 | U | | <0.01 | U | | <0.013 | U | | <0.014 | U | | <0.0068 | U | |
| | | VMP-22-10-070912-Dup | 7/9/2012 | 0.021 | J | | <0.0055 | U | UJ | <0.0034 | U | | <0.0071 | U | | <0.011 | U | | <0.041 | U | | <0.0023 | U | | <0.01 | U | | <0.012 | U | | <0.013 | U | | <0.0067 | U | |
| | | VMP-22-10-100312 | 10/3/2012 | 0.03 | | | <0.0063 | U | | 0.015 | | | <0.0081 | U | | <0.012 | U | | <0.047 | U | | <0.0027 | U | | 0.0048 | J | | <0.014 | U | | <0.015 | U | | <0.0076 | U | |
| | | VMP-22-10-012413 | 1/24/2013 | <0.033 | U | | <0.0071 | U | | 0.0018 | J | | <0.0092 | U | | <0.014 | U | | <0.054 | U | | <0.003 | U | | <0.013 | U | | <0.016 | U | | <0.017 | J | U | <0.0087 | U | |
| | 18 ft | VMP-22-18-021111 | 2/11/2011 | <2 | U | | <1.1 | U | | 0.67 | J | | <1.4 | U | | <2.2 | U | | <0.82 | U | | <0.47 | U | | | | | <0.63 | U | | <0.66 | U | | <1.3 | U | |
| | | VMP-22-18-041811 | 4/18/2011 | 1.1 | J | | <4.6 | U | | 1 | J | | <6 | U | | <9.3 | U | | <3.5 | U | | <2 | U | | 620 | | | <11 | U | | <2.8 | U | | <5.7 | U | |
| | | VMP-22-18-072611 | 7/26/2011 | <4.4 | U | | <2.4 | U | UJ | 0.42 | J | | <3.1 | U | | <4.8 | U | | <1.8 | U | | <1 | U | | 470 | | | <5.4 | U | | <1.4 | U | | <2.9 | U | |
| | | VMP-22-18-110511 | 11/5/2011 | 0.012 | | | <0.0047 | U | | 0.009 | | | <0.0061 | J | U | <0.0094 | J | U | <0.0036 | U | | <0.002 | U | | 0.012 | | | 0.0058 | J | | <0.011 | J | U | 0.0007 | J | |
| | | VMP-22-18-012412 | 1/24/2012 | <0.08 | J | U | <0.17 | U | | 0.012 | J | J | <0.056 | U | | <0.35 | U | | <0.033 | U | | <0.018 | U | | 0.045 | J | J | <0.099 | U | | <0.026 | U | | <0.053 | U | |
| | | VMP-22-18-040912 | 4/9/2012 | 0.022 | J | | <0.0052 | U | | 0.0062 | | | 0.0017 | J | | <0.01 | U | | <0.039 | U | UJ | <0.0022 | U | | <0.0096 | U | | <0.012 | U | | 0.0039 | J | | <0.0063 | U | |
| | | VMP-22-18-070912 | 7/9/2012 | 0.036 | | | <0.0055 | U | UJ | 0.029 | | | <0.0071 | U | | <0.011 | U | | <0.041 | U | | <0.0023 | U | | <0.01 | U | | <0.012 | U | | <0.013 | U | | <0.0067 | U | |
| | | VMP-22-18-100412 | 10/4/2012 | 0.021 | J | | <0.0075 | U | | 0.0036 | J | | <0.0097 | U | | <0.015 | U | | <0.056 | U | | <0.0032 | U | | <0.014 | U | | <0.017 | U | | <0.018 | U | | <0.0091 | U | |
| | | VMP-22-18-012413 | 1/24/2013 | <0.033 | J | U | <0.0071 | U | | 0.002 | J | | <0.0092 | U | | <0.014 | U | | <0.054 | U | | <0.003 | U | | <0.013 | U | | <0.016 | U | | <0.017 | J | U | <0.0087 | U | |
| | 38 ft | VMP-22-38-041811 | 4/18/2011 | <26 | U | | <14 | U | | <8.8 | U | | <18 | U | | <28 | U | | <11 | U | | <6.1 | U | | 3900 | | | <32 | U | | <8.6 | U | | <17 | U | |
| | | VMP-22-38-012512 | 1/25/2012 | <0.08 | U | | <0.043 | U | | 0.04 | | | <0.056 | U | | <0.087 | U | | <0.033 | U | | <0.018 | U | | 0.28 | | | <0.099 | U | | <0.1 | U | | <0.053 | U | |
| | | VMP-22-38-040912 | 4/9/2012 | 0.039 | | | <0.005 | U | | 0.012 | | | 0.0048 | J | | <0.01 | U | | <0.038 | U | UJ | <0.0022 | U | | <0.0093 | U | | <0.012 | U | | 0.0045 | J | | <0.0061 | U | |
| | | VMP-22-38-070912 | 7/9/2012 | 0.05 | | | <0.0053 | U | UJ | 0.074 | | | 0.0039 | J | | <0.011 | U | | <0.04 | U | | <0.0023 | U | | <0.0098 | U | | 0.0055 | J | | <0.013 | U | | <0.0065 | U | |
| | | VMP-22-38-100412 | 10/4/2012 | 0.02 | J | | <0.0078 | U | | 0.0096 | | | 0.0028 | J | | <0.016 | U | | <0.059 | U | | <0.0034 | U | | <0.014 | U | | <0.018 | U | | <0.019 | J | U | <0.0095 | U | |
| | | VMP-22-38-012413 | 1/24/2013 | 0.012 | J | | <0.007 | U | | 0.0026 | J | | <0.009 | U | | <0.014 | U | | <0.052 | U | | <0.003 | U | | <0.013 | U | | <0.016 | U | | <0.017 | J | U | <0.0085 | U | |
| VMP-23 | 5 ft | VMP-23-5-021511 | 2/15/2011 | 0.01 | J | | <0.0068 | U | | 0.023 | | | <0.0088 | U | | <0.014 | U | | <0.0051 | U | | <0.0029 | U | | | | | 0.0012 | J | | <0.0041 | J | U | <0.0083 | U | |
| | | VMP-23-5-042111 | 4/21/2011 | 0.024 | J | | <0.059 | U | | <0.036 | U | | <0.077 | U | | <0.12 | U | | <0.044 | U | | <0.025 | U | | <0.11 | U | | <0.14 | U | | <0.036 | U | | <0.072 | U | |
| | | VMP-23-5-072711 | 7/27/2011 | 0.062 | | | <0.0068 | U | | 0.18 | | | <0.0088 | U | | <0.014 | U | | <0.0051 | U | | <0.0029 | U | | 0.024 | | | 0.072 | | | 0.0032 | J | | <0.0083 | U | |
| | | VMP-23-5-110211 | 11/2/2011 | 0.035 | | | <0.0048 | U | | 0.016 | | | <0.0063 | U | | <0.0097 | U | | <0.0036 | U | | <0.0021 | U | | <0.0089 | U | | <0.011 | U | | <0.012 | J | U | <0.0059 | U | |
| | | VMP-23-5-012512 | 1/25/2012 | 0.019 | | | <0.0041 | U | | 0.023 | | | 0.0015 | J | | <0.0082 | U | | <0.0031 | U | | <0.0017 | U | | 0.002 | J | | 0.0048 | J | | <0.0098 | U | | <0.005 | U | |
| | | VMP-23-5-040912 | 4/9/2012 | 0.032 | | | <0.0049 | U | | 0.0089 | | | <0.0064 | U | | <0.0099 | U | | <0.037 | U | UJ | <0.0021 | U | | <0.0091 | U | | 0.024 | | | 0.0074 | J | | <0.006 | U | |
| | | VMP-23-5-070912 | 7/9/2012 | 0.1 | | | <0.0044 | U | UJ | 0.0024 | J | | <0.0057 | U | | <0.0088 | U | | 0.0017 | J | | <0.0019 | U | | 0.0039 | J | | 0.01 | | | 0.0042 | J | | <0.0054 | U | |
| | | VMP-23-5-100312 | 10/3/2012 | 0.05 | | | <0.0075 | U | | 0.011 | | | <0.0097 | U | | <0.015 | U | | <0.056 | U | | <0.0032 | U | | <0.014 | U | | 0.006 | J | | <0.018 | J | U | <0.0091 | U | |
| | | VMP-23-5-012413 | 1/24/2013 | 0.0056 | J | | <0.0064 | U | | 0.0019 | J | | <0.0083 | U | | <0.013 | U | | <0.048 | U | | <0.0027 | U | | 0.011 | J | | <0.014 | U | | <0.015 | J | U | <0.0078 | U | |
| | 10 ft | VMP-23-10-021511 | 2/15/2011 | 0.009 | J | | 0.0012 | J | | 0.0014 | J | | 0.0023 | J | | <0.014 | U | | <0.0053 | U | | <0.003 | U | | | | | <0.004 | U | | <0.0042 | U | | <0.0086 | U | |
| | | VMP-23-10-042111 | 4/21/2011 | <0.13 | U | | <0.071 | U | | 0.28 | | | <0.092 | U | | <0.14 | U | | <0.054 | U | | <0.03 | U | | 1.7 | | | <0.16 | U | | <0.043 | U | | <0.087 | U | |
| | | VMP-23-10-072711 | 7/27/2011 | <0.012 | U | | <0.0065 | U | | <0.004 | U | | <0.0084 | U | | <0.013 | U | | <0.0049 | U | | <0.0028 | U | | <0.012 | U | | <0.015 | U | | <0.016 | U | | <0.0079 | U | |
| | | VMP-23-10-110211 | 11/2/2011 | 0.029 | | | <0.0047 | U | | 0.021 | | | <0.0061 | U | | <0.0094 | U | | <0.0036 | U | | <0.002 | U | | <0.0087 | U | | 0.0083 | J | | <0.011 | J | U | <0.0058 | U | |
| | | VMP-23-10-012512 | 1/25/2012 | 0.0099 | | | <0.004 | U | | 0.068 | | | <0.0052 | U | | <0.008 | U | | <0.003 | U | | <0.0017 | U | | 0.0094 | | | 0.0033 | J | | <0.0096 | U | | <0.0049 | U | |
| | | VMP-23-10-040912 | 4/9/2012 | 0.025 | | | <0.005 | U | | 0.002 | J | | <0.0065 | U | | <0.01 | U | | <0.038 | U | UJ | <0.0022 | U | | <0.0093 | U | | 0.0068 | J | | 0.0049 | J | | <0.0061 | U | |
| | | VMP-23-10-040912-Dup | 4/9/2012 | 0.043 | | | <0.0051 | U | | 0.0041 | | | 0.0021 | J | | <0.01 | U | | <0.038 | U | UJ | <0.0022 | U | | 0.0072 | J | | 0.012 | | | 0.0042 | J | | 0.0021 | J | |
| | | VMP-23-10-070912 | 7/9/2012 | 0.065 | | | <0.004 | U | UJ | 0.0014 | J | | <0.0052 | U | | <0.008 | U | | <0.03 | U | | <0.0017 | U | | <0.0074 | U | | 0.0061 | J | | <0.0096 | U | | <0.0049 | U | |
| | | VMP-23-10-100312 | 10/3/2012 | 0.064 | | | <0.008 | U | | 0.011 | | | <0.01 | U | | <0.016 | U | | <0.06 | U | | <0.0034 | U | | 0.0053 | J | | <0.018 | U | | <0.019 | J | U | <0.0098 | U | |
| | | VMP-23-10-012413 | 1/24/2013 | 0.0072 | J | | <0.0064 | U | | <0.0039 | U | | <0.0083 | U | | <0.013 | U | | <0.048 | U | | <0.0027 | U | | <0.012 | U | | <0.014 | U | | <0.015 | J | U | <0.0078 | U | |
| | 25 ft | VMP-23-25-021511 | 2/15/2011 | 0.011 | J | | <0.0065 | U | | 0.018 | | | <0.0084 | U | | <0.013 | U | | <0.0049 | U | | <0.0028 | U | | | | | <0.0037 | U | | <0.0039 | U | | <0.0079 | U | |
| | | VMP-23-25-042111 | 4/21/2011 | 0.035 | J | | <0.067 | U | | 1.6 | | | <0.086 | U | | <0.13 | U | | <0.05 | U | | <0.028 | U | | 8.2 | | | <0.15 | U | | <0.04 | U | | <0.081 | U | |
| | | VMP-23-25-072711 | 7/27/2011 | 0.05 | | | <0.0075 | U | | 0.15 | | | <0.0097 | U | | <0.015 | U | | <0.0056 | U | | <0.0032 | U | | <0.014 | U | | 0.032 | | | 0.0077 | J | | <0.0091 | U | |
| | | VMP-23-25-110511 | 11/5/2011 | 0.041 | | | <0.0047 | U | | 0.002 | J | | <0.0061 | J | U | <0.0094 | J | U | <0.0036 | U | | <0.002 | U | | <0.0087 | U | | 0.014 | | | <0.011 | J | U | <0.0058 | U | |
| | | VMP-23-25-012512 | 1/25/2012 | 0.0065 | J | | <0.0042 | U | | 0.058 | | | <0.0055 | U | | <0.0085 | U | | <0.0032 | U | | <0.0018 | U | | 0.0046 | J | | 0.0047 | J | | <0.01 | U | | <0.0052 | U | |
| | | VMP-23-25-040912 | 4/9/2012 | 0.14 | | | <0.0049 | U | | 0.022 | | | <0.0064 | U | | <0.0099 | U | | 0.067 | J | J | <0.0021 | U | | <0.0091 | U | | 0.06 | | | 0.0076 | J | | <0.006 | U | |
| | | VMP-23-25-070912 | 7/9/2012 | 0.15 | | | <0.0063 | U | UJ | 0.0027 | J | | <0.0082 | U | | <0.013 | U | | <0.047 | U | | <0.0027 | U | | <0.012 | U | | 0.013 | J | | <0.015 | U | | <0.0077 | U | |
| | | VMP-23-25-100312 | 10/3/2012 | 0.086 | | | <0.0078 | U | | 0.0095 | | | <0.01 | U | | <0.016 | U | | <0.059 | U | | <0.0034 | U | | <0.014 | U | | 0.0052 | J | | <0.019 | J | U | <0.0095 | U | |
| | | VMP-23-25-012413 | 1/24/2013 | 0.0073 | J | | <0.0065 | U | | <0.004 | U | | <0.0084 | U | | <0.013 | U | | <0.049 | U | | <0.0028 | U | | 0.0059 | J | | <0.015 | U | | <0.016 | J | U | <0.0079 | U | |
| | 40 ft | VMP-23-40-071012 | 7/10/2012 | 0.18 | | | <0.0053 | U | UJ | 0.0081 | | | <0.0069 | U | | <0.011 | U | | 0.0039 | J | | <0.0023 | U | | 0.0065 | J | | 0.016 | | | <0.013 | U | | <0.0065 | U | |
| | | VMP-23-40-100312 | 10/3/2012 | 0.09 | | | <0.0073 | U | | 0.018 | | | <0.0094 | U | | <0.014 | U | | 0.0046 | J | | <0.0031 | U | | <0.013 | U | | 0.0041 | J | | <0.018 | J | U | <0.0088 | U | |
| | | VMP-23-40-012413 | 1/24/2013 | 0.012 | J | | <0.0067 | U | | <0.0041 | U | | <0.0086 | U | | <0.013 | U | | <0.05 | U | | <0.0028 | U | | 0.0045 | J | | 0.0024 | J | | <0.016 | J | U | <0.0081 | U | |

SEE LAST PAGE OF TABLE FOR NOTES

**TABLE 5**
**CUMULATIVE SUMMARY OF SOIL VAPOR ANALYTICAL DETECTIONS AND SCREENING RESULTS: VILLAGE - VOCS**

| Location | Depth | Sample ID | Sample Date | Acetone | | | alpha-Chlorotoluene | | | Benzene | | | Bromodichloromethane | | | Bromoform | | | Bromomethane | | | 1,3-Butadiene | | | Butane | | | 2-Butanone | | | Carbon disulfide | | | Carbon tetrachloride | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | 750000 | | | | | | 0.37 | | | 450000 | | | 11 | | | 6.9 | | | | | | | | | 6400 | | | 780 | | | 0.21 | | |
| | | | | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals |
| VMP-24 | 5 ft | VMP-24-5-021611 | 2/16/2011 | 0.019 | | | <0.0073 | U | | 0.019 | | | <0.0094 | U | | <0.014 | U | | <0.0055 | U | | <0.0031 | U | | | | | <0.0042 | U | | <0.0044 | J | U | <0.0089 | U | |
| | | VMP-24-5-040811 | 4/8/2011 | <0.14 | U | | <0.078 | U | | 5 | | | <0.1 | U | | <0.16 | U | | <0.058 | U | | <0.033 | U | | 5.6 | | | <0.18 | U | | 0.042 | J | | <0.095 | U | |
| | | VMP-24-5-072811 | 7/28/2011 | 0.047 | | | <0.0073 | U | | 0.093 | | | <0.0094 | U | | <0.014 | U | | <0.0055 | U | | <0.0031 | U | | 0.031 | | | 0.021 | | | 0.037 | | | <0.0089 | U | |
| | | VMP-24-5-110211 | 11/2/2011 | 0.013 | | | <0.0048 | U | | 0.018 | | | <0.0063 | U | | <0.0097 | U | | <0.0036 | U | | <0.0021 | U | | 0.0063 | J | | <0.011 | U | | <0.012 | J | U | <0.0059 | U | |
| | | VMP-24-5-110211-DUP | 11/2/2011 | 0.016 | | | <0.0067 | U | | 0.018 | | | <0.0087 | U | | <0.013 | U | | <0.005 | U | | <0.0029 | U | | 0.013 | | | 0.0048 | J | | <0.016 | J | U | <0.0082 | U | |
| | | VMP-24-5-012512 | 1/25/2012 | 0.009 | | | <0.0042 | U | | 0.0013 | J | | 0.00082 | J | | <0.0083 | U | | <0.0031 | U | | <0.0018 | U | | 0.0032 | J | | 0.0045 | J | | <0.01 | U | | <0.0051 | U | |
| | | VMP-24-5-040912 | 4/9/2012 | 0.11 | | | <0.0049 | U | | 0.024 | | | <0.0064 | U | | <0.0099 | U | | <0.062 | J | UJ | <0.0021 | U | | 0.0049 | J | | 0.038 | | | 0.007 | J | | <0.006 | U | |
| | | VMP-24-5-071212 | 7/12/2012 | 0.052 | | | <0.0047 | U | UJ | 0.043 | | | <0.0061 | U | | <0.0094 | U | | <0.036 | U | | <0.002 | U | | <0.0087 | U | | 0.012 | | | <0.011 | U | | <0.0058 | U | |
| | | VMP-24-5-101912 | 10/19/2012 | 0.025 | J | | <0.0073 | U | | 0.081 | | | <0.0095 | U | | <0.015 | U | | <0.055 | U | | <0.0031 | U | | 0.0086 | J | | <0.017 | U | | <0.018 | J | U | <0.0089 | U | |
| | | VMP-24-5-012313 | 1/23/2013 | 0.025 | J | | <0.0065 | U | | 0.0088 | | | <0.0084 | U | | <0.013 | U | | <0.049 | U | | <0.0028 | U | | <0.012 | U | | <0.015 | U | | <0.016 | J | U | <0.0079 | U | |
| | 10 ft | VMP-24-10-021711 | 2/17/2011 | 0.01 | J | | <0.007 | U | | 1.4 | | | <0.009 | U | | <0.014 | U | | <0.0052 | U | | <0.003 | U | | | | | <0.004 | U | | <0.0042 | J | U | <0.0085 | U | |
| | | VMP-24-10-041111 | 4/11/2011 | 0.012 | J | | <0.013 | U | | 2.5 | | | <0.017 | U | | <0.026 | U | | <0.0098 | U | | <0.0056 | U | | 0.54 | | | <0.03 | U | | 0.0049 | J | | <0.016 | U | |
| | | VMP-24-10-072811 | 7/28/2011 | 0.048 | | | <0.0071 | U | | 0.11 | | | <0.0092 | U | | <0.014 | U | | <0.0054 | U | | <0.003 | U | | <0.013 | U | | 0.023 | | | 0.0037 | J | | <0.0087 | U | |
| | | VMP-24-10-110211 | 11/2/2011 | 0.015 | | | <0.0042 | U | | 0.002 | J | | <0.0055 | U | | <0.0085 | U | | <0.0032 | U | | <0.0018 | U | | <0.0078 | U | | 0.0069 | J | | <0.01 | J | U | <0.0052 | U | |
| | | VMP-24-10-012512 | 1/25/2012 | 0.0073 | | | <0.004 | U | | 0.00061 | J | | 0.00074 | J | | <0.008 | U | | <0.003 | U | | <0.0017 | U | | <0.0074 | U | | 0.0032 | J | | <0.0096 | U | | <0.0049 | U | |
| | | VMP-24-10-041012 | 4/10/2012 | 0.054 | | | <0.0047 | U | | <0.0029 | J | U | <0.0061 | U | | <0.0094 | U | | <0.036 | J | UJ | <0.002 | U | | <0.0087 | U | | 0.012 | | | <0.011 | U | | <0.0058 | U | |
| | | VMP-24-10-071212 | 7/12/2012 | 0.088 | | | <0.0055 | U | UJ | 0.0078 | | | <0.0071 | U | | <0.011 | U | | <0.041 | U | | <0.0023 | U | | <0.01 | U | | 0.02 | | | <0.013 | U | | <0.0067 | U | |
| | | VMP-24-10-100912 | 10/9/2012 | 0.016 | J | | <0.0068 | U | | 0.00099 | J | | <0.0088 | U | | <0.014 | U | | <0.051 | U | | <0.0029 | U | | <0.012 | U | | <0.016 | U | | <0.016 | U | | <0.0083 | U | |
| | | VMP-24-10-012313 | 1/23/2013 | <0.033 | J | U | <0.0071 | U | | 0.0072 | | | <0.0092 | U | | <0.014 | U | | <0.054 | U | | <0.003 | U | | <0.013 | U | | <0.016 | U | | <0.017 | J | U | <0.0087 | U | |
| | 22 ft | VMP-24-22-021711 | 2/17/2011 | 0.0064 | J | | <0.007 | U | | 0.95 | | | <0.009 | U | | <0.014 | U | | <0.0052 | U | | <0.003 | U | | | | | <0.004 | U | | <0.0042 | J | U | <0.0085 | U | |
| | | VMP-24-22-041111 | 4/11/2011 | 0.011 | J | | <0.0065 | U | | 0.013 | | | <0.0084 | U | | <0.013 | U | | <0.0049 | U | | <0.0028 | U | | <0.012 | U | | <0.015 | U | | 0.00074 | J | | <0.0079 | U | |
| | | VMP-24-22-072811 | 7/28/2011 | 0.022 | | | <0.0065 | U | | 0.047 | | | <0.0084 | U | | <0.013 | U | | <0.0049 | U | | <0.0028 | U | | <0.012 | U | | 0.012 | J | | 0.003 | J | | <0.0079 | U | |
| | | VMP-24-22-072811-Dup | 7/28/2011 | 0.015 | | | <0.0075 | U | | 0.046 | | | <0.0097 | U | | <0.015 | U | | <0.0056 | U | | <0.0032 | U | | <0.014 | U | | 0.007 | J | | 0.0028 | J | | <0.0091 | U | |
| | | VMP-24-22-110611 | 11/6/2011 | 0.018 | | | <0.0045 | U | | 0.01 | | | <0.0059 | U | | <0.009 | J | U | <0.0034 | U | | <0.0019 | U | | <0.0083 | U | | 0.0033 | J | U | <0.0055 | U | | <0.0055 | U | |
| | | VMP-24-22-012512 | 1/25/2012 | 0.012 | | | <0.0042 | U | | 0.00079 | J | | 0.00069 | J | | <0.0085 | U | | <0.0032 | U | | <0.0018 | U | | <0.0078 | U | | 0.0046 | J | | <0.01 | U | | <0.0052 | U | |
| | | VMP-24-22-041012 | 4/10/2012 | 0.067 | | | <0.0046 | U | | 0.0037 | | | <0.006 | U | | <0.0092 | U | | <0.035 | J | UJ | <0.002 | U | | 0.0074 | J | | 0.022 | | | 0.002 | J | | <0.0056 | U | |
| | | VMP-24-22-071212 | 7/12/2012 | 0.073 | | | <0.0056 | U | UJ | 0.033 | | | <0.0073 | U | | <0.011 | U | | <0.042 | U | | <0.0024 | U | | <0.01 | U | | 0.014 | | | <0.014 | U | | <0.0068 | U | |
| | | VMP-24-22-100912 | 10/9/2012 | 0.014 | J | | <0.007 | U | | 0.0013 | J | | <0.009 | U | | <0.014 | U | | <0.052 | U | | <0.003 | U | | <0.013 | U | | <0.016 | U | | <0.017 | U | | <0.0085 | U | |
| | | VMP-24-22-012313 | 1/23/2013 | 0.0069 | J | | <0.0073 | U | | <0.0045 | U | | <0.0094 | U | | <0.014 | U | | <0.055 | U | | <0.0031 | U | | 0.022 | | | <0.017 | U | | <0.018 | J | U | <0.0089 | U | |
| | 34 ft | VMP-24-34-021711 | 2/17/2011 | 0.014 | | | <0.007 | U | | 0.0084 | | | <0.009 | U | | <0.014 | U | | <0.0052 | U | | <0.003 | U | | | | | 0.0025 | J | | <0.0042 | J | U | <0.0085 | U | |
| | | VMP-24-34-041111 | 4/11/2011 | 0.014 | | | <0.0063 | U | | 0.0072 | | | <0.0081 | U | | <0.012 | U | | <0.0047 | U | | <0.0027 | U | | 0.0031 | J | | <0.014 | U | | <0.015 | U | | <0.0076 | U | |
| | | VMP-24-34-072811 | 7/28/2011 | 0.031 | | | <0.0055 | U | | 0.077 | | | <0.0071 | U | | <0.011 | U | | <0.0041 | U | | <0.0024 | U | | <0.01 | U | | 0.012 | J | | 0.0042 | J | | <0.0067 | U | |
| | | VMP-24-34-110611 | 11/6/2011 | 0.025 | | | <0.0035 | U | | 0.0095 | | | <0.0046 | U | | <0.007 | J | U | <0.0026 | U | | <0.0015 | U | | 0.0033 | J | | 0.016 | | | <0.0085 | J | U | <0.0043 | U | |
| | | VMP-24-34-012512 | 1/25/2012 | 0.0075 | J | | <0.0043 | U | | 0.00051 | J | | 0.001 | J | | <0.0087 | U | | <0.0033 | U | | <0.0018 | U | | <0.008 | U | | 0.0065 | J | | <0.01 | U | | <0.0053 | U | |
| | | VMP-24-34-041012 | 4/10/2012 | 0.06 | | | <0.0048 | U | | 0.037 | | | <0.0063 | U | | <0.0097 | U | | <0.036 | J | UJ | <0.0021 | U | | 0.0037 | J | | 0.015 | | | 0.0021 | J | | <0.0059 | U | |
| | | VMP-24-34-071212 | 7/12/2012 | 0.074 | | | <0.0046 | U | UJ | 0.1 | | | <0.006 | U | | <0.0092 | U | | <0.035 | U | | <0.002 | U | | 0.0033 | J | | 0.021 | | | <0.011 | U | | <0.0056 | U | |
| | | VMP-24-34-100912 | 10/9/2012 | 0.015 | J | | <0.0071 | U | | 0.0067 | | | <0.0092 | U | | <0.014 | U | | <0.054 | U | | <0.003 | U | | <0.013 | U | | <0.016 | U | | <0.017 | U | | <0.0087 | U | |
| | | VMP-24-34-012313 | 1/23/2013 | 0.009 | J | | <0.0075 | U | | 0.0068 | | | <0.0097 | U | | <0.015 | U | | <0.056 | U | | <0.0032 | U | | <0.014 | U | | <0.017 | U | | <0.018 | J | U | <0.0091 | U | |
| VMP-31 | 5 ft | VMP-31-5-042512 | 4/25/2012 | 0.057 | | | <0.0049 | U | | 0.29 | | | <0.0064 | U | | <0.0099 | U | | <0.037 | U | | <0.0021 | U | | <0.0091 | U | | 0.027 | | | 0.0085 | J | | <0.006 | U | |
| | | VMP-31-5-072012 | 7/20/2012 | 0.17 | | | <0.0049 | U | | 0.0043 | | | <0.0064 | U | | <0.0099 | U | | <0.037 | U | | <0.0021 | U | | <0.0091 | U | | 0.023 | | | 0.045 | | | <0.006 | U | |
| | | VMP-31-5-102612 | 10/26/2012 | 0.15 | | | 0.0022 | J | | 0.015 | | | <0.0092 | U | | <0.014 | U | | <0.054 | U | | <0.003 | U | | 0.23 | | | 0.045 | | | <0.017 | U | | <0.0087 | U | |
| | | VMP-31-5-021113 | 2/11/2013 | 0.064 | | | <0.0067 | U | | 0.0017 | J | | <0.0086 | U | | <0.013 | U | | <0.05 | J | U | <0.0028 | U | | 0.0096 | J | | 0.0039 | J | | <0.016 | J | U | <0.0081 | U | |
| | 10 ft | VMP-31-10-042512 | 4/25/2012 | 0.048 | | | <0.0066 | U | | 0.54 | | | <0.0085 | U | | <0.013 | U | | <0.05 | U | | <0.0028 | U | | 0.067 | | | 0.022 | | | <0.016 | J | U | <0.008 | U | |
| | | VMP-31-10-072612 | 7/26/2012 | 0.033 | | | <0.005 | U | | 0.0026 | J | | <0.0076 | U | | <0.01 | U | | 0.0015 | J | J | <0.0022 | U | | <0.0093 | U | | 0.014 | | | <0.012 | U | U | <0.0061 | U | |
| | | VMP-31-10-102612 | 10/26/2012 | 0.036 | | | <0.0077 | U | | 0.02 | | | <0.0099 | U | | <0.015 | U | | <0.057 | U | | <0.0033 | U | | 0.1 | | | 0.0089 | J | | <0.018 | U | | <0.0093 | U | |
| | | VMP-31-10-021313 | 2/13/2013 | 0.018 | J | | <0.0073 | U | | 0.024 | | | <0.0094 | U | | <0.014 | U | | 0.0039 | J | | <0.0031 | U | | 0.1 | | | 0.0037 | J | | <0.018 | U | | <0.0089 | U | |
| | 20 ft | VMP-31-20-101912 | 10/19/2012 | <13 | U | | <7.1 | U | | 0.64 | J | | <9.2 | U | | <14 | U | | <5.4 | U | | <3 | U | | 2.3 | J | | <16 | U | | <4.3 | U | | <8.7 | U | |
| | | VMP-31-20-021113 | 2/11/2013 | 0.045 | J | | <0.1 | U | | <0.063 | U | | <0.13 | U | | <0.2 | U | | <0.076 | U | | <0.044 | U | | 1.5 | | | <0.23 | U | | <0.061 | U | | <0.12 | U | |
| | 30 ft | VMP-31-30-042512 | 4/25/2012 | <4.6 | U | | <10 | U | | 9.9 | | | <3.3 | U | | <5.1 | U | | <1.9 | U | | <1.1 | U | | 970 | | | <5.8 | U | | 0.58 | J | | <3.1 | U | |
| | | VMP-31-30-042512-Dup | 4/25/2012 | <4.6 | U | | <10 | U | | 12 | | | <3.3 | U | | <5.1 | U | | <1.9 | U | | <1.1 | U | | 1100 | | | <5.8 | U | | 0.61 | J | | <3.1 | U | |
| | | VMP-31-30-072012 | 7/20/2012 | <2.3 | U | | <0.49 | U | | <0.3 | U | | <0.64 | U | | <0.99 | U | | <3.7 | U | | <0.21 | U | | 52 | | | <1.1 | U | | <1.2 | U | | <0.6 | U | |
| | | VMP-31-30-101912 | 10/19/2012 | <0.82 | U | | <0.44 | U | | 0.044 | J | | <0.58 | U | | <0.89 | U | | <0.33 | U | | <0.19 | U | | 19 | | | <1 | U | | 0.025 | J | | <0.54 | U | |
| | | VMP-31-30-021113 | 2/11/2013 | <13 | U | | <7.3 | U | | <4.5 | U | | <9.4 | U | | <14 | U | | <5.5 | U | | <3.1 | U | | 1000 | | | 2.6 | J | | <4.4 | U | | <8.9 | U | |
| VMP-32 | 5 ft | VMP-32-5-042512 | 4/25/2012 | 0.095 | | | <0.0048 | U | | 0.047 | | | <0.0063 | U | | <0.0097 | U | | <0.036 | U | | <0.0021 | U | | <0.0089 | U | | 0.029 | | | <0.012 | J | U | <0.0059 | U | |
| | | VMP-32-5-072012 | 7/20/2012 | 0.12 | | | <0.0043 | U | | 0.091 | | | <0.0056 | U | | <0.0087 | U | | <0.033 | U | | <0.0018 | U | | 0.0068 | J | | 0.0061 | J | | 0.0036 | J | | <0.0053 | U | |
| | | VMP-32-5-101812 | 10/18/2012 | 0.08 | | | <0.0082 | U | | 0.0037 | J | | <0.011 | U | | <0.016 | U | | <0.062 | U | | <0.0035 | U | | <0.015 | U | | 0.0072 | J | | <0.02 | U | | <0.01 | U | |
| | | VMP-32-5-020513 | 2/5/2013 | 0.011 | J | | <0.0065 | U | | 0.0042 | | | <0.0084 | U | | <0.013 | U | | <0.049 | U | | <0.0028 | U | | <0.012 | U | | <0.015 | U | | <0.016 | J | U | <0.0079 | U | |
| | 10 ft | VMP-32-10-041612 | 4/16/2012 | 0.034 | | | <0.0044 | U | | 0.0032 | | | <0.0057 | U | | <0.0088 | U | | <0.033 | U | | <0.0019 | U | | 0.007 | J | | 0.024 | | | <0.011 | J | U | <0.0054 | U | |
| | | VMP-32-10-072012 | 7/20/2012 | 0.087 | | | <0.0051 | U | | 0.044 | | | <0.0066 | U | | <0.01 | U | | 0.0032 | J | | <0.0022 | U | | <0.0093 | U | | 0.0081 | J | | <0.012 | U | | <0.0062 | U | |
| | | VMP-32-10-101812 | 10/18/2012 | 0.047 | | | <0.0077 | U | | 0.026 | | | <0.0099 | U | | <0.015 | U | | <0.057 | U | | <0.0033 | U | | 0.0045 | J | | <0.017 | U | | 0.007 | J | | <0.0093 | U | |
| | | VMP-32-10-020513 | 2/5/2013 | 0.0092 | J | | <0.0065 | U | | 0.0051 | | | <0.0084 | U | | <0.013 | U | | <0.049 | U | | <0.0028 | U | | <0.012 | U | | <0.015 | U | | <0.016 | J | U | <0.0079 | U | |
| | 20 ft | VMP-32-20-041612 | 4/16/2012 | 0.49 | | | <0.1 | U | | 0.034 | J | | <0.13 | U | | <0.2 | U | | <0.76 | U | | <0.043 | U | | <0.19 | U | | <0.23 | U | | 0.34 | | | <0.12 | U | |
| | | VMP-32-20-072012 | 7/20/2012 | 0.13 | | | <0.0049 | U | | 0.0085 | | | <0.0064 | U | | <0.0099 | U | | <0.037 | U | | <0.0021 | U | | <0.0091 | U | | 0.0075 | J | | <0.012 | U | | <0.006 | U | |
| | | VMP-32-20-101812 | 10/18/2012 | 0.051 | | | <0.0071 | U | | 0.0014 | J | | <0.0092 | U | | <0.014 | U | | <0.054 | U | | <0.003 | U | | <0.013 | U | | <0.016 | U | | <0.017 | U | | <0.0087 | U | |
| | | VMP-32-20-020513 | 2/5/2013 | 0.0099 | J | | <0.0073 | U | | 0.0027 | J | | <0.0094 | U | | <0.014 | U | | <0.055 | U | | <0.0031 | U | | <0.013 | U | | <0.017 | U | | <0.018 | J | U | <0.0089 | U | |
| | 30 ft | VMP-32-30-041612 | 4/16/2012 | <4.4 | U | | <2.4 | U | | 35 | | | <3.1 | U | | <4.8 | U | | <1.8 | U | | <1 | U | | 1200 | | | <5.5 | U | | <1.4 | U | | <2.9 | U | |
| | | VMP-32-30-072012 | 7/20/2012 | <9.2 | U | | <5 | U | | 16 | | | <6.5 | U | | <10 | U | | <3.7 | U | | <2.1 | U | | 500 | | | <11 | U | | <3 | U | | <6.1 | U | |
| | | VMP-32-30-101812 | 10/18/2012 | <0.52 | U | | <0.28 | U | | 0.074 | J | | <0.37 | U | | <0.57 | U | | <0.21 | U | | <0.12 | U | | 0.15 | J | | <0.65 | U | | <0.17 | U | | <0.35 | U | |
| | | VMP-32-30-020513 | 2/5/2013 | <0.54 | U | | <0.29 | U | | <0.18 | U | | <0.38 | U | | <0.58 | U | | <0.22 | U | | <0.12 | U | | <0.54 | U | | <0.67 | U | | <0.18 | U | | <0.36 | U | |

**TABLE 5**
**CUMULATIVE SUMMARY OF SOIL VAPOR ANALYTICAL DETECTIONS AND SCREENING RESULTS: VILLAGE - VOCS**

| Location | Depth | Sample ID | Sample Date | Acetone | | | alpha-Chlorotoluene | | | Benzene | | | Bromodichloromethane | | | Bromoform | | | Bromomethane | | | 1,3-Butadiene | | | Butane | | | 2-Butanone | | | Carbon disulfide | | | Carbon tetrachloride | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | 750000 | | | | | | 0.37 | | | 450000 | | | 11 | | | 6.9 | | | | | | | | | 6400 | | | 780 | | | 0.21 | | |
| | | | | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals |
| VMP-42 | 10 ft | VMP-42-10-041812 | 4/18/2012 | 0.041 | | | <0.0044 | U | | 0.026 | | J | <0.0057 | U | | <0.0088 | U | | <0.033 | J | U | <0.0019 | U | | 0.0099 | | | 0.027 | | | <0.011 | J | U | <0.0054 | U | |
| | | VMP-42-10-041812-Dup | 4/18/2012 | 0.034 | | | <0.0045 | U | | 0.02 | | J | <0.0059 | U | | <0.009 | U | | <0.034 | U | | <0.0019 | U | | 0.0064 | J | | 0.026 | | | <0.011 | J | U | <0.0055 | U | |
| | | VMP-42-20-041812 | 4/18/2012 | 13 | | | 0.54 | J | | 0.4 | J | | <3 | U | | <4.6 | U | | <17 | U | | <0.99 | U | | 320 | | | <5.3 | U | | 8.6 | | | <2.8 | U | |
| | | VMP-42-10-071912 | 7/19/2012 | 0.053 | | | <0.0049 | U | UJ | 0.038 | | | <0.0064 | U | | <0.0099 | U | | <0.037 | U | | <0.0021 | U | | 0.0052 | J | J | 0.03 | | | 0.0063 | J | | <0.006 | U | |
| | | VMP-42-10-101212 | 10/12/2012 | 0.017 | J | | <0.008 | U | | 0.046 | | | <0.01 | U | | <0.016 | U | | <0.06 | U | | <0.0034 | U | | <0.015 | U | | 0.0067 | J | | <0.019 | U | | <0.0097 | U | |
| | | VMP-42-10-013113 | 1/31/2013 | 0.0045 | J | | <0.0073 | U | | 0.0023 | J | | <0.0094 | U | | <0.014 | U | | <0.055 | U | | <0.0031 | U | | <0.013 | U | | <0.017 | U | | <0.018 | J | U | <0.0089 | U | |
| | 20 ft | VMP-42-20-071912 | 7/19/2012 | 0.028 | | | <0.0048 | U | UJ | 0.038 | | | <0.0063 | U | | <0.0097 | U | | <0.036 | U | | <0.0021 | U | | 0.0073 | J | J | 0.016 | | | 0.0068 | J | | <0.0059 | U | |
| | | VMP-42-20-101212 | 10/12/2012 | 0.013 | J | | <0.0071 | U | | 0.0067 | | | <0.0091 | U | | <0.014 | U | | <0.053 | U | | <0.003 | U | | <0.013 | U | | <0.016 | U | | <0.017 | U | | <0.0086 | U | |
| | | VMP-42-20-101212-Dup | 10/12/2012 | 0.024 | J | | <0.0071 | U | | 0.008 | | | <0.0092 | U | | <0.014 | U | | <0.054 | U | | <0.003 | U | | 0.0049 | J | | 0.0054 | J | | <0.017 | U | | <0.0087 | U | |
| | | VMP-42-20-013113 | 1/31/2013 | 0.0073 | J | | <0.0067 | U | | 0.0063 | | | <0.0086 | U | | <0.013 | U | | <0.05 | U | | <0.0028 | U | | 0.012 | J | | <0.015 | U | | <0.016 | J | U | <0.0081 | U | |
| | 30 ft | VMP-42-30-041912 | 4/19/2012 | <8.9 | U | | <4.8 | U | | 3.1 | | | <3.6 | U | | <9.7 | U | | <3.6 | U | | <2.1 | U | | 1400 | | | <11 | U | | <2.9 | U | | <5.9 | U | |
| | | VMP-42-30-071912 | 7/19/2012 | 0.047 | | J | <0.0045 | U | UJ | 0.077 | | J | <0.0059 | U | | <0.009 | U | | <0.034 | U | | <0.0019 | U | | 35 | J | J | 0.031 | | J | 0.03 | | J | <0.0055 | U | |
| | | VMP-42-30-101212 | 10/12/2012 | 0.031 | J | | <0.0075 | U | | 0.011 | | | <0.0097 | U | | <0.015 | U | | <0.056 | U | | <0.0032 | U | | 0.56 | | | 0.005 | J | | 0.018 | | | <0.0091 | U | |
| | | VMP-42-30-101212-Dup | 10/12/2012 | 0.021 | J | | <0.0075 | U | | 0.0072 | | | <0.0097 | U | | <0.015 | U | | <0.056 | U | | <0.0032 | U | | 0.54 | | | <0.017 | U | | 0.018 | | | <0.0091 | U | |
| | | VMP-42-30-013113 | 1/31/2013 | 0.0062 | J | | <0.0071 | U | | <0.0044 | U | | <0.0092 | U | | <0.014 | U | | <0.054 | U | | <0.003 | U | | 0.33 | | | <0.016 | U | | 0.0061 | J | | <0.0087 | U | |
| VMP-43 | 10 ft | VMP-43-10-041612 | 4/16/2012 | 0.073 | | | <0.0051 | U | | 0.56 | | | <0.0066 | U | | <0.01 | U | | 0.007 | J | | <0.0022 | U | | 0.011 | | | 0.045 | | | 0.02 | | | <0.0062 | U | |
| | | VMP-43-10-071912 | 7/19/2012 | 0.097 | | | <0.0097 | U | | 0.044 | | | <0.012 | U | | <0.019 | U | | <0.073 | U | | <0.0041 | U | | 0.11 | J | J | 0.028 | | | 0.0059 | J | | <0.012 | U | |
| | | VMP-43-10-101612 | 10/16/2012 | 0.04 | | | <0.0082 | U | | 0.022 | | | <0.011 | U | | <0.016 | U | | <0.062 | U | | <0.0035 | U | | <0.015 | U | | <0.019 | U | | 0.015 | J | | <0.01 | U | |
| | 20 ft | VMP-43-20-041612 | 4/16/2012 | 0.093 | | | <0.049 | U | | 0.091 | | | <0.064 | U | | <0.099 | U | | <0.037 | U | | <0.021 | U | | 15 | | | 0.019 | J | | 0.086 | | | <0.06 | U | |
| | | VMP-43-20-071912 | 7/19/2012 | 0.1 | | | <0.018 | U | | 0.077 | | | <0.023 | U | | <0.036 | U | | <0.13 | U | | <0.0076 | U | | 0.36 | J | J | 0.024 | J | | 0.018 | J | | <0.022 | U | |
| | | VMP-43-20-101812 | 10/18/2012 | 0.29 | | | <0.0068 | U | | 0.0026 | J | | <0.0088 | U | | <0.014 | U | | <0.051 | U | | <0.0029 | U | | 0.032 | | | 0.006 | J | | <0.016 | U | | <0.0083 | U | |
| | | VMP-43-20-012413 | 1/24/2013 | 0.01 | J | | <0.0068 | U | | 0.0021 | J | | <0.0088 | U | | <0.014 | U | | <0.051 | U | | <0.0029 | U | | 0.016 | | | <0.016 | U | | <0.016 | J | U | <0.0083 | U | |
| | 30 ft | VMP-43-30-042312 | 4/23/2012 | 0.05 | J | | <0.18 | U | | 0.84 | | | <0.059 | U | | <0.09 | U | | <0.034 | U | | <0.019 | U | | 0.13 | | | 0.02 | J | | 0.012 | J | | <0.055 | U | |
| | | VMP-43-30-071912 | 7/19/2012 | 0.064 | | | <0.0049 | U | | 0.063 | | | <0.0064 | U | | <0.0099 | U | | <0.037 | J | U | <0.0021 | U | | 0.072 | J | J | 0.017 | | | 0.011 | J | | <0.006 | U | |
| | | VMP-43-30-101812 | 10/18/2012 | 0.02 | J | | <0.0071 | U | | 0.29 | | | 0.0018 | J | | <0.014 | U | | <0.054 | U | | <0.003 | U | | 0.0087 | J | | <0.018 | U | | <0.017 | U | | <0.0087 | U | |
| | | VMP-43-30-012413 | 1/24/2013 | 0.0055 | J | | <0.007 | U | | 0.012 | | | <0.009 | U | | <0.014 | U | | <0.052 | U | | <0.003 | U | | 0.004 | J | | <0.016 | U | | <0.017 | J | U | <0.0085 | U | |
| VMP-44 | 10 ft | VMP-44-10-041912 | 4/19/2012 | 0.38 | J | | <2.4 | U | | <1.5 | U | | <3.1 | U | | <4.7 | U | | <1.8 | U | | <1 | U | | 110 | | | <5.4 | U | | <1.4 | U | | <2.9 | U | |
| | | VMP-44-10-072012 | 7/20/2012 | <1.4 | U | | <0.79 | U | | 4.2 | | J | <1 | U | | <1.6 | U | | <0.6 | U | | <0.34 | U | | 26 | | J | <1.8 | U | | <0.48 | U | | <0.96 | U | |
| | | VMP-44-10-081012 | 8/10/2012 | <0.87 | U | | <0.47 | U | | 3.3 | | J | <0.61 | U | | <0.94 | U | | <0.36 | U | | <0.2 | U | | 18 | | J | <1.1 | U | | <0.28 | U | | <0.58 | U | |
| | | VMP-44-10-101212 | 10/12/2012 | <2.7 | U | | <1.4 | U | | 1.1 | | | <1.9 | U | | <2.9 | U | | <1.1 | U | | <0.62 | U | | <2.7 | U | | <3.3 | U | | <0.88 | U | | <1.8 | U | |
| | | VMP-44-10-012513 | 1/25/2013 | <1.1 | U | | <0.6 | U | | 0.53 | | | <0.77 | U | | <1.2 | U | | <0.45 | U | | <0.25 | U | | 3.1 | | | <1.4 | U | | <0.36 | U | | <0.72 | U | |
| | 20 ft | VMP-44-20-041912 | 4/19/2012 | 0.53 | J | | <0.52 | U | | 4.1 | | | <0.67 | U | | <1 | U | | <0.39 | U | | <0.22 | U | | 130 | | | <1.2 | U | | 0.35 | | | <0.63 | U | |
| | | VMP-44-20-072512 | 7/25/2012 | <1.6 | U | | <0.89 | U | | 3 | | J | <1.1 | U | | <1.8 | U | | <0.67 | U | | <0.38 | U | | 75 | | J | <2 | U | | 0.061 | J | J | <1.1 | U | |
| | | VMP-44-20-101212 | 10/12/2012 | <5.4 | U | | <3 | U | | 1.5 | J | | <3.8 | U | | <5.9 | U | | <2.2 | U | | <1.3 | U | | 9.4 | | | <6.7 | U | | <1.8 | U | | <3.6 | U | |
| | | VMP-44-20-012513 | 1/25/2013 | <0.4 | U | | <0.22 | U | | 0.065 | J | | <0.28 | U | | <0.43 | U | | <0.16 | U | | <0.092 | U | | 0.46 | | | <0.49 | U | | <0.13 | U | | <0.26 | U | |
| | 30 ft | VMP-44-30-041912 | 4/19/2012 | 0.53 | J | | <0.3 | U | | 32 | | | <0.39 | U | | <0.6 | U | | <0.23 | U | | <0.13 | U | | 77 | | | <0.69 | U | | 0.038 | J | | <0.37 | U | |
| | | VMP-44-30-072512 | 7/25/2012 | 0.072 | J | | <0.051 | U | | 14 | | | <0.066 | U | | <0.1 | U | | <0.038 | U | | <0.022 | U | | 7.4 | | | 0.012 | J | | 0.28 | | | <0.062 | U | |
| | | VMP-44-30-072512-Dup | 7/25/2012 | 0.06 | J | | <0.051 | U | | 14 | | | <0.066 | U | | <0.1 | U | | <0.038 | U | | <0.022 | U | | 7.3 | | | 0.016 | J | | 0.28 | | | <0.062 | U | |
| | | VMP-44-30-101512 | 10/15/2012 | <1.4 | U | | <0.31 | U | | 4 | | | <0.4 | U | | <0.62 | U | | <2.3 | U | | <0.13 | U | | 7 | | | <0.71 | U | | <0.75 | U | | <0.38 | U | |
| | | VMP-44-30-101512-Dup | 10/15/2012 | <1.3 | U | | <0.29 | U | | 3.9 | | | <0.38 | U | | <0.58 | U | | <2.2 | U | | <0.12 | U | | 6.9 | | | <0.67 | U | | 0.22 | J | J | <0.36 | U | |
| | | VMP-44-30-012513 | 1/25/2013 | 15 | | J | <0.075 | U | UJ | 0.037 | J | J | <0.097 | U | UJ | <0.15 | U | UJ | <0.056 | U | UJ | <0.032 | U | UJ | 0.042 | J | J | <0.17 | U | UJ | <0.045 | U | UJ | <0.092 | U | UJ |
| VMP-45 | 10 ft | VMP-45-10-041912 | 4/19/2012 | 0.029 | | | <0.0047 | U | | 0.052 | | | <0.0061 | U | | <0.0094 | U | | <0.036 | U | | <0.002 | U | | <0.0087 | U | | 0.023 | | | <0.011 | J | U | <0.0058 | U | |
| | | VMP-45-10-071912 | 7/19/2012 | 0.047 | | | <0.0048 | U | | 0.005 | | | <0.0063 | U | | <0.0097 | U | | <0.036 | U | | <0.0021 | U | | (ppbV) | J | J | 0.042 | | | 0.0055 | J | | <0.0059 | U | |
| | | VMP-45-10-101512 | 10/15/2012 | 0.015 | J | | <0.0075 | U | | 0.0036 | J | | <0.0097 | U | | <0.015 | U | | <0.056 | U | | <0.0032 | U | | <0.014 | U | | <0.017 | U | | <0.018 | J | U | <0.0092 | U | |
| | | VMP-45-10-013013 | 1/30/2013 | 0.018 | J | | <0.0065 | U | | 0.016 | | | <0.0084 | U | | <0.013 | U | | <0.049 | U | | <0.0028 | U | | 0.005 | J | | <0.015 | U | | <0.016 | J | U | <0.0079 | U | |
| | 20 ft | VMP-45-20-041912 | 4/19/2012 | 0.072 | J | | <0.3 | U | | 0.63 | | | <0.38 | U | | <0.59 | U | | <0.22 | U | | <0.13 | U | | 0.72 | | | <0.67 | U | | <0.18 | U | | <0.36 | U | |
| | | VMP-45-20-071912 | 7/19/2012 | 0.47 | | | <0.092 | U | | 0.018 | J | | <0.12 | U | | <0.18 | U | | <0.69 | U | | <0.039 | U | | 0.21 | J | J | 0.032 | J | | 0.26 | | | <0.11 | U | |
| | | VMP-45-20-101512 | 10/15/2012 | 0.016 | J | | <0.0071 | U | | 0.0053 | | | <0.0092 | U | | <0.014 | U | | <0.054 | U | | <0.003 | U | | 0.048 | | | <0.016 | U | | <0.017 | U | | <0.0087 | U | |
| | | VMP-45-20-013013 | 1/30/2013 | 0.024 | J | | <0.0068 | U | | <0.0042 | U | | <0.0088 | U | | <0.014 | U | | <0.051 | U | | <0.0029 | U | | 0.021 | | | 0.0036 | J | | <0.016 | J | U | <0.0083 | U | |
| | 30 ft | VMP-45-30-041912 | 4/19/2012 | 0.078 | J | J | <0.2 | U | | <0.12 | U | | <0.26 | U | | <0.39 | U | | <0.15 | U | | <0.084 | U | | 4.9 | | J | <0.45 | U | | 0.036 | J | J | <0.24 | U | |
| | | VMP-45-30-071912 | 7/19/2012 | <0.091 | U | | <0.049 | U | | <0.03 | U | | <0.064 | U | | <0.099 | U | | <0.037 | U | | <0.021 | U | | 0.08 | J | | <0.11 | U | | <0.03 | U | | <0.06 | U | |
| | | VMP-45-30-101512 | 10/15/2012 | 0.025 | J | | <0.0071 | U | | 0.0052 | | | <0.0092 | U | | <0.014 | U | | <0.054 | U | | <0.003 | U | | 0.034 | | | 0.0064 | J | | <0.017 | U | | <0.0087 | U | |
| | | VMP-45-30-101512-Dup | 10/15/2012 | 0.013 | J | | <0.0071 | U | | 0.0051 | | | <0.0091 | U | | <0.014 | U | | <0.053 | U | | <0.003 | U | | 0.04 | | | <0.016 | U | | <0.017 | J | U | <0.0086 | U | |
| | | VMP-45-30-013013 | 1/30/2013 | 0.052 | J | | <0.012 | U | | 0.0058 | J | | <0.016 | U | | <0.025 | U | | <0.094 | U | | <0.0054 | U | | 0.011 | J | | <0.028 | U | | <0.03 | J | U | <0.015 | U | |

SEE LAST PAGE OF TABLE FOR NOTES

**TABLE 5**
**CUMULATIVE SUMMARY OF SOIL VAPOR ANALYTICAL DETECTIONS AND SCREENING RESULTS: VILLAGE - VOCS**

| Location | Depth | Sample ID | Sample Date | Acetone | | | alpha-Chlorotoluene | | | Benzene | | | Bromodichloromethane | | | Bromoform | | | Bromomethane | | | 1,3-Butadiene | | | Butane | | | 2-Butanone | | | Carbon disulfide | | | Carbon tetrachloride | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | 750000 | | | | | | 0.37 | | | 450000 | | | 11 | | | 6.9 | | | | | | | | | 6400 | | | 780 | | | 0.21 | | |
| | | | | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals |
| VMP-47 | 5 ft | VMP-47-5-012113 | 1/21/2013 | 0.026 | J | | 0.001 | J | | 0.0018 | J | | <0.0097 | U | | <0.015 | U | | <0.056 | J | U | <0.0032 | U | | 0.058 | | | 0.0059 | J | | <0.018 | U | | <0.0091 | U | |
| | | [1]VMP-47-5-012313-R | 1/23/2013 | <46 | U | | <25 | U | | <15 | U | | <32 | U | | <50 | U | | <19 | U | | <11 | U | | 4900 | | | <57 | U | | <15 | U | | <30 | U | |
| | 10 ft | VMP-47-10-012113 | 1/21/2013 | 0.0084 | J | | <0.0071 | U | | 0.0051 | | | <0.0092 | U | | <0.014 | U | | <0.054 | J | U | <0.003 | U | | 0.007 | J | | <0.016 | U | | <0.017 | U | | <0.0087 | U | |
| | | [1]VMP-47-10-012313-R | 1/23/2013 | <1.1 | U | | <0.63 | U | | 0.11 | J | | <0.81 | U | | <1.2 | U | | <0.47 | U | | <0.27 | U | | 460 | | | <1.4 | U | | <0.38 | U | | <0.76 | U | |
| | 20 ft | VMP-47-20-012113 | 1/21/2013 | <12 | U | | <6.5 | U | | <4 | U | | <8.4 | U | | <13 | U | | <4.9 | U | | <2.8 | U | | 1200 | | | <15 | U | | <3.9 | U | | <7.9 | U | |
| | | [1]VMP-47-20-012313-R | 1/23/2013 | <28 | U | | <15 | U | | <9.5 | U | | <20 | U | | <31 | U | | <12 | U | | <6.6 | U | | 4100 | | | <35 | U | | <9.3 | U | | <19 | U | |
| | 30 ft | VMP-47-30-012113 | 1/21/2013 | <8.7 | U | | <4.8 | U | | <2.9 | U | | <6.2 | U | | <9.5 | U | | <3.6 | U | | <2 | U | | 1300 | | | <11 | U | | <2.9 | U | | <5.8 | U | |
| | | [1]VMP-47-30-012313-R | 1/23/2013 | <45 | U | | <25 | U | | <15 | U | | <32 | U | | <49 | U | | <18 | U | | <10 | U | | 4800 | | | <56 | U | | <15 | U | | <30 | U | |
| VMP-48 | 5 ft | VMP-48-5-020113 | 2/1/2013 | 0.01 | J | | <0.0066 | U | | 0.0048 | | | <0.0086 | U | | <0.013 | U | | <0.05 | U | | <0.0028 | U | | 0.012 | J | | <0.015 | U | | <0.018 | J | U | <0.0081 | U | |
| | 10 ft | VMP-48-10-020113 | 2/1/2013 | 0.01 | J | | <0.0069 | U | | 0.0087 | | | <0.0089 | U | | <0.014 | U | | <0.052 | U | | <0.0029 | U | | <0.013 | U | | <0.016 | U | | <0.016 | J | U | <0.0084 | U | |
| | 20 ft | VMP-48-20-020113 | 2/1/2013 | 0.013 | J | | <0.0066 | U | | 0.002 | J | | <0.0085 | U | | <0.013 | U | | <0.05 | U | | <0.0028 | U | | 0.092 | | | 0.0026 | J | | <0.016 | J | U | <0.008 | U | |
| | 30 ft | VMP-48-30-020113 | 2/1/2013 | 0.0059 | J | J | <0.0068 | U | | 0.097 | | | <0.0087 | U | | <0.013 | U | | <0.051 | U | | <0.0029 | U | | 0.3 | | | <0.015 | U | | 0.024 | | | <0.0082 | U | |
| | | VMP-48-30-020113-DUP | 2/1/2013 | <0.12 | U | UJ | <0.027 | U | | 0.12 | | | <0.035 | U | | <0.054 | U | | <0.2 | U | | <0.012 | U | | 0.36 | | | <0.061 | U | | 0.027 | J | | <0.033 | U | |
| VMP-49 | 5 ft | VMP-49-5-020113 | 2/1/2013 | 0.027 | J | | <0.007 | U | | <0.0043 | U | | <0.009 | U | | <0.014 | U | | <0.052 | U | | <0.003 | U | | <0.013 | U | | 0.0055 | J | | <0.017 | J | U | <0.0085 | U | |
| | 10 ft | VMP-49-10-020113 | 2/1/2013 | 0.0084 | J | | <0.0068 | U | | 0.033 | | | <0.0088 | U | | <0.014 | U | | <0.051 | U | | <0.0029 | U | | 0.0048 | J | | <0.016 | U | | <0.016 | J | U | <0.0083 | U | |
| | 20 ft | VMP-49-20-020113 | 2/1/2013 | 0.014 | J | | <0.0067 | U | | <0.0041 | U | | <0.0086 | U | | <0.013 | U | | <0.05 | U | | <0.0028 | U | | 0.0078 | J | | <0.015 | U | | <0.016 | J | U | <0.0081 | U | |
| | 30 ft | VMP-49-30-020113 | 2/1/2013 | 1 | J | | <0.32 | U | | 0.4 | | | <0.41 | U | | <0.64 | U | | <2.4 | U | | <0.14 | U | | 6.5 | | | <0.72 | U | | 0.12 | J | | <0.39 | U | |
| VMP-50 | 5 ft | VMP-50-5-020113 | 2/1/2013 | 0.007 | J | | <0.0065 | U | | 0.0017 | J | | <0.0084 | U | | <0.013 | U | | <0.049 | U | | <0.0028 | U | | 0.23 | | | <0.015 | U | | <0.016 | J | U | <0.0079 | U | |
| | 10 ft | VMP-50-10-020113 | 2/1/2013 | 0.0062 | J | | <0.0071 | U | | 0.0026 | J | | 0.0053 | J | | <0.014 | U | | <0.054 | U | | <0.003 | U | | 0.058 | | | <0.016 | U | | 0.0024 | J | | <0.0087 | U | |
| | 20 ft | VMP-50-20-020113 | 2/1/2013 | 0.021 | J | | <0.028 | U | | 0.011 | J | | <0.036 | U | | <0.055 | U | | <0.21 | U | | <0.012 | U | | 0.069 | | | <0.063 | U | | 0.014 | J | | <0.034 | U | |
| | 30 ft | VMP-50-30-020113 | 2/1/2013 | 16 | J | | <6.7 | U | | 92 | | | <8.7 | U | | <13 | U | | <50 | U | | <2.9 | U | | 440 | | | <15 | U | | 2.8 | J | | <8.1 | U | |
| VMP-51 | 5 ft | VMP-51-5-020113 | 2/1/2013 | 0.0077 | J | | <0.0071 | U | | <0.0044 | U | | <0.0091 | U | | <0.014 | U | | <0.053 | U | | <0.003 | U | | <0.013 | U | | <0.016 | U | | <0.017 | J | U | <0.0086 | U | |
| | 10 ft | VMP-51-10-020113 | 2/1/2013 | 0.0061 | J | | <0.0071 | U | | <0.0044 | U | | <0.0092 | U | | <0.014 | U | | <0.054 | U | | <0.003 | U | | <0.013 | U | | <0.016 | U | | <0.017 | J | U | <0.0087 | U | |
| | 20 ft | VMP-51-20-021513-R | 2/15/2013 | 0.013 | J | | <0.0068 | U | | 0.0053 | | | <0.0088 | U | | <0.014 | U | | <0.051 | U | | <0.0029 | U | | <0.012 | U | | <0.016 | U | | <0.016 | U | | <0.0083 | U | |
| | 30 ft | VMP-51-30-020413 | 2/4/2013 | 0.0062 | J | | <0.0075 | U | | 0.056 | | | <0.0097 | U | | <0.015 | U | | <0.056 | U | | <0.0032 | U | | 0.0071 | J | | <0.017 | U | | <0.018 | J | U | <0.0091 | U | |
| | | VMP-51-30-020413-DUP | 2/4/2013 | 0.01 | J | | <0.0073 | U | | 0.091 | | | <0.0094 | U | | <0.014 | U | | <0.054 | U | | <0.0031 | U | | 0.012 | J | | <0.016 | U | | <0.018 | J | U | <0.0088 | U | |
| VMP-52 | 5 ft | VMP-52-5-020413 | 2/4/2013 | 0.011 | J | | <0.0065 | U | | 0.073 | | | <0.0084 | U | | <0.013 | U | | <0.049 | U | | <0.0028 | U | | 0.005 | J | | 0.0028 | J | | <0.016 | J | U | <0.0079 | U | |
| | 10 ft | VMP-52-10-020413 | 2/4/2013 | 0.006 | J | | <0.0062 | U | | <0.0038 | U | | <0.008 | U | | <0.012 | U | | <0.047 | U | | <0.0026 | U | | 0.027 | | | <0.014 | U | | 0.023 | | | <0.0076 | U | |
| | 20 ft | VMP-52-20-020413 | 2/4/2013 | 0.013 | J | | <0.0069 | U | | 0.076 | | J | <0.009 | U | | <0.014 | U | | 0.0025 | J | | <0.003 | U | | 0.082 | | | 0.0047 | J | | 0.0092 | J | | <0.0084 | U | |
| | | VMP-52-20-020413-DUP | 2/4/2013 | 0.0058 | J | | <0.0066 | U | | 0.012 | | J | <0.0086 | U | | <0.013 | U | | <0.05 | U | | <0.0028 | U | | 0.069 | | | <0.015 | U | | 0.0088 | J | | <0.0081 | U | |
| | 30 ft | VMP-52-30-020413 | 2/4/2013 | 0.088 | | | <0.0073 | U | | 0.0017 | J | | <0.0094 | U | | <0.014 | U | | <0.054 | U | | <0.0031 | U | | 0.082 | | | <0.016 | U | | <0.018 | J | U | <0.0088 | U | |
| VMP-53 | 5 ft | VMP-53-5-020513 | 2/5/2013 | 0.015 | J | | <0.0067 | U | | <0.0041 | U | | <0.0086 | U | | <0.013 | U | | <0.05 | U | | <0.0028 | U | | 0.0032 | J | | <0.015 | U | | <0.016 | J | U | <0.0081 | U | |
| | 10 ft | VMP-53-10-020513 | 2/5/2013 | 0.0094 | J | | <0.0068 | U | | 0.059 | | | <0.0088 | U | | <0.014 | U | | <0.051 | U | | <0.0029 | U | | 0.0051 | J | | <0.016 | U | | <0.016 | J | U | <0.0083 | U | |
| | | VMP-53-10-020513-DUP | 2/5/2013 | 0.0096 | J | | <0.0064 | U | | 0.017 | | | <0.0083 | U | | <0.013 | U | | <0.048 | U | | <0.0027 | U | | 0.0032 | J | | <0.014 | U | | <0.015 | J | U | <0.0078 | U | |
| | 20 ft | VMP-53-20-020513 | 2/5/2013 | 0.011 | J | | <0.0068 | U | | 0.086 | | | <0.0088 | U | | <0.014 | U | | <0.051 | U | | <0.0029 | U | | <0.012 | U | | <0.016 | U | | <0.016 | J | U | <0.0083 | U | |
| | 30 ft | VMP-53-30-020513 | 2/5/2013 | 0.0076 | J | | <0.007 | U | | <0.0043 | U | | <0.009 | U | | <0.014 | U | | <0.052 | U | | <0.003 | U | | <0.013 | U | | <0.016 | U | | <0.017 | J | U | <0.0085 | U | |
| VMP-54 | 5 ft | VMP-54-5-020613 | 2/6/2013 | 0.0092 | J | | <0.0071 | U | | 0.0024 | J | | <0.0092 | U | | <0.014 | U | | <0.054 | U | | <0.003 | U | | 0.025 | | | <0.016 | U | | <0.017 | J | U | <0.0087 | U | |
| | 10 ft | VMP-54-10-020613 | 2/6/2013 | 0.0094 | J | | <0.0073 | U | | <0.0045 | U | | <0.0094 | U | | <0.014 | U | | <0.055 | U | | <0.0031 | U | | 0.0051 | J | | <0.017 | U | | <0.018 | J | U | <0.0089 | U | |
| | 20 ft | VMP-54-20-020613 | 2/6/2013 | 0.029 | J | | <0.0071 | U | | 0.0028 | J | | <0.0092 | U | | <0.014 | U | | <0.054 | U | | <0.003 | U | | 0.0049 | J | | 0.005 | J | | <0.017 | J | U | <0.0087 | U | |
| | | VMP-54-20-020613-DUP | 2/6/2013 | 0.023 | J | | <0.0071 | U | | 0.036 | | | <0.0092 | U | | <0.014 | U | | <0.054 | U | | <0.003 | U | | 0.0061 | J | | 0.0033 | J | | <0.017 | J | U | <0.0087 | U | |
| | 30 ft | VMP-54-30-020613 | 2/6/2013 | 0.012 | J | | <0.0077 | U | | 0.014 | | J | <0.0099 | U | | <0.015 | U | | <0.057 | U | | <0.0033 | U | | <0.014 | U | | <0.017 | U | | <0.018 | J | U | <0.0093 | U | |
| | | VMP-54-30-020613-DUP | 2/6/2013 | 0.013 | J | | <0.0077 | U | | 0.0045 | J | J | <0.0099 | U | | <0.015 | U | | <0.057 | U | | <0.0033 | U | | <0.014 | U | | <0.017 | U | | <0.018 | J | U | <0.0093 | U | |

SEE LAST PAGE OF TABLE FOR NOTES

**TABLE 5**
**CUMULATIVE SUMMARY OF SOIL VAPOR ANALYTICAL DETECTIONS AND SCREENING RESULTS: VILLAGE - VOCS**

| Location | Depth | Sample ID | Sample Date | Chlorobenzene | | | Chlorodibromomethane | | | Chloroethane | | | Chloroform | | | Chloromethane | | | Cyclohexane | | | 1,2-Dibromoethane | | | 1,2-Dichlorobenzene | | | 1,3-Dichlorobenzene | | | 1,4-Dichlorobenzene | | | Dichlorodifluoromethane | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | 69 | | | 57000 | | | | | | 0.11 | | | | | | | | | 0.011 | | | 290 | | | | | | 1200 | | | | | |
| | | | | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals |
| VMP-1 | 5 ft | VMP-1-5-082510 | 8/25/2010 | <0.02 | U | | <0.036 | U | | <0.011 | U | | <0.021 | U | | <0.035 | U | | 0.02 | | | <0.033 | U | | <0.026 | U | | <0.026 | U | | <0.026 | U | | 0.0028 | J | |
| | | VMP-1-5-111710 | 11/17/2010 | <0.024 | U | | <0.044 | U | | <0.014 | U | | <0.025 | U | | <0.042 | U | | 0.14 | | | <0.04 | U | | <0.031 | U | | <0.031 | U | | <0.031 | U | | <0.025 | U | |
| | | VMP-1-5-020411 | 2/4/2011 | <0.46 | U | | <0.86 | U | | <0.27 | U | | <0.49 | U | | <0.83 | U | | 8.1 | | | <0.78 | U | | <0.61 | U | | <0.61 | U | | <0.61 | U | | <0.5 | U | |
| | | VMP-1-5-041211 | 4/12/2011 | <0.0061 | J | U | 0.0023 | J | | <0.014 | U | | <0.0064 | U | | <0.011 | U | | 0.21 | | | <0.01 | U | | <0.0079 | U | | <0.0079 | U | | <0.0079 | J | U | 0.002 | J | |
| | | VMP-1-5-080111 | 8/1/2011 | <0.0061 | U | | <0.011 | U | | <0.014 | U | | <0.0064 | U | | <0.011 | U | | 0.0083 | | | <0.01 | U | | <0.0079 | U | | 0.0014 | J | | 0.0024 | J | | 0.0023 | J | |
| | | VMP-1-5-110311 | 11/3/2011 | <16 | U | | <30 | U | | <37 | U | | <17 | U | | <29 | U | | 4.8 | J | | <27 | U | | <21 | U | | <21 | U | | <21 | U | | <17 | U | |
| | | VMP-1-5-013012 | 1/30/2012 | <1.3 | U | | <2.5 | U | | <3.1 | U | | <1.4 | U | | <2.4 | U | | 23 | | J | <2.2 | U | | <1.8 | U | | <1.8 | U | | <1.8 | U | | <1.4 | U | |
| | | VMP-1-5-041312 | 4/13/2012 | <0.0041 | J | U | <0.0076 | U | | <0.0094 | U | | <0.0044 | U | | <0.018 | U | | <0.0031 | J | U | <0.0069 | U | | <0.0054 | U | | <0.0054 | U | | <0.0054 | J | U | 0.0024 | J | |
| | | VMP-1-5-071612 | 7/16/2012 | <0.0042 | J | U | <0.0078 | U | | <0.0096 | U | | 0.002 | J | | <0.019 | U | | 0.036 | | | <0.007 | U | | <0.0055 | U | | <0.0055 | U | | <0.0055 | J | U | 0.0026 | J | |
| | | VMP-1-5-101112 | 10/11/2012 | <0.01 | U | | <0.02 | U | | <0.024 | U | | <0.011 | U | | <0.047 | U | | 0.13 | | | <0.018 | U | | <0.014 | U | | <0.014 | U | | <0.014 | U | | 0.0025 | J | |
| | | [x]VMP-1-5-012113 | 1/21/2013 | <0.12 | U | | <0.22 | U | | <0.27 | U | | <0.12 | U | | <0.53 | U | | 0.88 | | | <0.2 | U | | <0.16 | U | | <0.16 | U | | 0.02 | J | | <0.13 | U | |
| | | [x]VMP-1-5-012313-R | 1/23/2013 | <5.4 | U | | <9.9 | U | | <12 | U | | <5.7 | U | | <9.6 | U | | 33 | | | <9 | U | | <7 | U | | <7 | U | | <7 | U | | <5.8 | U | |
| | 8.5 ft | VMP-1-8.5-082510 | 8/25/2010 | <0.059 | U | | <0.11 | U | | <0.034 | U | | <0.063 | U | | <0.11 | U | | <0.044 | U | | <0.099 | U | | <0.077 | U | | <0.077 | U | | <0.077 | U | | <0.064 | U | |
| | | VMP-1-8.5-111710 | 11/17/2010 | <0.011 | U | | <0.021 | U | | <0.0065 | U | | <0.012 | U | | <0.02 | U | | 0.043 | | | <0.019 | U | | <0.015 | U | | <0.015 | U | | <0.015 | U | | 0.0023 | J | |
| | | VMP-1-8.5-111710-Dup | 11/17/2010 | <0.011 | U | | <0.021 | U | | <0.0065 | U | | <0.012 | U | | <0.02 | U | | 0.034 | | | <0.019 | U | | <0.015 | U | | <0.015 | U | | <0.015 | U | | 0.0024 | J | |
| | | VMP-1-8.5-020411 | 2/4/2011 | <0.91 | U | | <1.7 | U | | <0.52 | U | | <0.97 | U | | <1.6 | U | | 9.2 | | | <1.5 | U | | <1.2 | U | | <1.2 | U | | <1.2 | U | | <0.98 | U | |
| | | VMP-1-8.5-041211 | 4/12/2011 | <0.008 | J | U | <0.015 | U | | <0.018 | U | | <0.0085 | U | | <0.014 | U | | 0.067 | | | <0.013 | U | | <0.01 | U | | <0.01 | U | | <0.01 | J | U | 0.002 | J | |
| | | VMP-1-8.5-080111 | 8/1/2011 | <3.3 | U | | <6.1 | U | | <7.6 | U | | <3.5 | U | | <5.9 | U | | 7.1 | | | <5.5 | U | | <4.3 | U | | <4.3 | U | | <4.3 | U | | <3.6 | U | |
| | | VMP-1-8.5-080111-Dup | 8/1/2011 | <3.2 | U | | <6 | U | | <7.4 | U | | <3.4 | U | | <5.8 | U | | 11 | | | <5.4 | U | | <4.2 | U | | <4.2 | U | | <4.2 | U | | <3.5 | U | |
| | | VMP-1-8.5-110311 | 11/3/2011 | <37 | U | | <68 | U | | <85 | U | | <39 | U | | <66 | U | | 11 | J | | <62 | U | | <48 | U | | <48 | U | | <48 | U | | <40 | U | |
| | | VMP-1-8.5-013012 | 1/30/2012 | <8 | U | | <15 | U | | <18 | U | | <8.5 | U | | <14 | U | | 19 | | | <13 | U | | <10 | U | | <10 | U | | <10 | U | | <8.6 | U | |
| | | VMP-1-8.5-041612 | 4/16/2012 | <0.0049 | U | | <0.009 | U | | <0.011 | U | | <0.0052 | U | | <0.022 | U | | 0.0093 | | | 0.0023 | J | | <0.0064 | U | | <0.0064 | U | | <0.0064 | J | U | 0.0028 | J | |
| | | VMP-1-8.5-041612-Dup | 4/16/2012 | <0.0047 | U | | <0.0088 | U | | <0.011 | U | | <0.005 | U | | <0.021 | U | | 0.0076 | | | 0.0018 | J | | <0.0062 | U | | <0.0062 | U | | <0.0062 | J | U | 0.003 | J | |
| | | VMP-1-8.5-071612 | 7/16/2012 | <0.0042 | J | U | <0.0078 | U | | <0.0097 | U | | 0.00077 | J | | <0.019 | U | | 0.0032 | | | <0.0071 | U | | <0.0055 | U | | <0.0055 | U | | <0.0055 | J | U | 0.0026 | J | |
| | | VMP-1-8.5-101112 | 10/11/2012 | <0.0065 | U | | <0.012 | U | | <0.015 | U | | <0.0069 | U | | <0.029 | U | | 0.073 | | | <0.011 | U | | <0.0085 | U | | <0.0085 | J | U | <0.0085 | J | U | 0.0021 | J | |
| | | [x]VMP-1-8.5-012113 | 1/21/2013 | <0.12 | U | | <0.21 | U | | <0.26 | U | | <0.12 | U | | <0.52 | U | | 0.62 | | | <0.19 | U | | <0.15 | U | | <0.15 | U | | <0.15 | U | | <0.12 | U | |
| | | [x]VMP-1-8.5-012313-R | 1/23/2013 | <0.11 | U | | <0.2 | U | | <0.24 | U | | <0.11 | U | | <0.19 | U | | 1.4 | | | <0.18 | U | | <0.14 | U | | <0.14 | U | | <0.14 | U | | <0.12 | U | |
| | 23.5 ft | VMP - 1 - 23.5 - 083010 | 8/30/2010 | <2.1 | U | | <3.8 | U | | <1.2 | U | | <2.2 | U | | <3.7 | U | | 130 | | | <3.4 | U | | <2.7 | U | | <2.7 | U | | <2.7 | U | | <2.2 | U | |
| | | VMP-1-23.5-111810 | 11/17/2010 | <0.0057 | U | | <0.01 | U | | <0.0032 | U | | 0.00066 | J | | <0.01 | U | | 0.0082 | | | <0.0095 | U | | <0.0074 | U | | <0.0074 | U | | <0.0074 | U | | 0.0023 | J | |
| | | VMP-1-23.5-020411 | 2/4/2011 | <5.4 | U | | <9.9 | U | | <3.1 | U | | <5.7 | U | | <9.6 | U | | 150 | | | <9 | U | | <7 | U | | <7 | U | | <7 | U | | <5.8 | U | |
| | | VMP-1-23.5-041211 | 4/12/2011 | <8.7 | U | | <16 | U | | 4.4 | J | | <9.3 | U | | <16 | U | | 3.2 | J | | <15 | U | | <11 | U | | <11 | U | | <11 | U | | <9.4 | U | |
| | | VMP-1-23.5-041211-DUP | 4/12/2011 | <11 | U | | <20 | U | | <25 | U | | <12 | U | | <20 | U | | 5.3 | J | | <18 | U | | <14 | U | | <14 | U | | <14 | U | | <12 | U | |
| | | VMP-1-23.5-080111 | 8/1/2011 | <59 | U | | <110 | U | | <140 | U | | <63 | U | | <110 | U | | 110 | | | <99 | U | | <78 | U | | <78 | U | | <78 | U | | <64 | U | |
| | | VMP-1-23.5-110611 | 11/6/2011 | 6.6 | J | | <26 | U | | <32 | U | | <15 | U | | <25 | U | | 38 | | | <23 | U | | <18 | U | | <18 | U | | <18 | U | | <15 | U | |
| | | VMP-1-23.5-013112 | 1/31/2012 | <28 | U | | <51 | U | | <63 | U | | <29 | U | | <50 | U | | 32 | | | <46 | U | | <36 | U | | <36 | U | | <36 | U | | <30 | U | |
| | | VMP-1-23.5-041612 | 4/16/2012 | <2.2 | U | | <4.1 | U | | <5 | U | | <2.3 | U | | <3.9 | U | | 6.6 | | | <3.7 | U | | <2.9 | U | | <2.9 | U | | <2.9 | U | | <2.4 | U | |
| | | VMP-1-23.5-071612 | 7/16/2012 | <28 | U | | <51 | U | | <64 | U | | <29 | U | | <50 | U | | 37 | | | <46 | U | | <36 | U | | <36 | U | | <36 | U | | <30 | U | |
| | | VMP-1-23.5-102412 | 10/24/2012 | <55 | U | | <100 | U | | <130 | U | | <59 | U | | <100 | U | | 23 | J | | <92 | U | | <72 | U | | <72 | U | | <72 | U | | <60 | U | |
| | | [x]VMP-1-23.5-012113 | 1/21/2013 | <0.062 | U | UJ | <0.11 | U | UJ | <0.14 | U | UJ | <0.066 | U | UJ | <0.28 | U | UJ | 0.64 | | J | <0.1 | U | UJ | <0.081 | U | UJ | <0.081 | U | UJ | <0.081 | U | UJ | <0.066 | U | UJ |
| | | [x]VMP-1-23.5-012313-R | 1/23/2013 | <74 | U | | <140 | U | | <170 | U | | <79 | U | | <130 | U | | 160 | | | <120 | U | | <97 | U | | <97 | U | | <97 | U | | <80 | U | |
| | 38.5 ft | VMP-1-38.5-073112 | 7/31/2012 | <0.0043 | U | | <0.008 | U | | <0.0099 | U | | 0.0011 | J | | 0.022 | | | <0.0032 | U | | <0.0072 | U | | <0.0056 | U | | <0.0056 | U | | <0.0056 | U | | 0.0025 | J | |
| | | VMP-1-38.5-102612 | 10/26/2012 | <3 | U | | <5.5 | U | | <6.9 | U | | <3.2 | U | | <5.4 | U | | 20 | | | <5 | U | | <3.9 | U | | <3.9 | U | | <3.9 | U | | <3.2 | U | |
| | | [x]VMP-1-38.5-012113 | 1/21/2013 | <0.04 | U | UJ | <0.075 | U | UJ | <0.093 | U | UJ | <0.043 | U | UJ | <0.18 | U | UJ | 0.62 | | J | <0.068 | U | UJ | <0.053 | U | UJ | <0.053 | U | UJ | <0.053 | U | UJ | <0.044 | U | UJ |
| | | [x]VMP-1-38.5-012313-R | 1/23/2013 | <55 | U | | <100 | U | | <120 | U | | <58 | U | | <98 | U | | 94 | | | <91 | U | | <72 | U | | <72 | U | | <72 | U | | <59 | U | |
| VMP-2 | 5 ft | VMP - 2 - 5 - 083110 | 8/31/2010 | <2.1 | U | | <3.8 | U | | <1.2 | U | | <2.2 | U | | <3.7 | U | | 28 | | | <3.4 | U | | <2.7 | U | | <2.7 | U | | <2.7 | U | | <2.2 | U | |
| | | VMP-2-5-111610 | 11/16/2010 | <3 | U | | <5.6 | U | | <1.7 | U | | <3.2 | U | | <5.4 | U | | <2.3 | U | | <5.1 | U | | <4 | U | | <4 | U | | <4 | U | | <3.3 | U | |
| | | VMP-2-5-020411 | 2/4/2011 | <0.79 | U | | <1.5 | U | | <0.46 | U | | <0.84 | U | | <1.4 | U | | 4.9 | | | <1.3 | U | | <1 | U | | <1 | U | | <1 | U | | <0.85 | U | |
| | | VMP-2-5-041311 | 4/13/2011 | <0.0064 | J | U | <0.012 | U | | <0.015 | U | | <0.0068 | U | | <0.011 | U | | 0.044 | | | <0.011 | U | | <0.0084 | U | | <0.0084 | U | | <0.0084 | J | U | 0.0022 | J | |
| | | VMP-2-5-080211 | 8/2/2011 | <6.6 | U | | <12 | U | | <15 | U | | <7 | U | | <12 | U | | 35 | | | <11 | U | | <8.7 | U | | <8.7 | U | | <8.7 | U | | <7.1 | U | |
| | | VMP-2-5-110711 | 11/7/2011 | <0.0039 | J | U | <0.0073 | U | | <0.009 | U | | <0.0042 | U | | <0.0071 | U | | <0.0029 | U | | <0.0066 | U | | <0.0051 | U | | <0.0051 | U | | <0.0051 | U | | 0.0031 | J | |
| | | VMP-2-5-012512 | 1/25/2012 | 0.17 | J | | <0.83 | U | | <1 | U | | <0.47 | U | | <0.8 | U | | 0.27 | J | | <0.74 | U | | <0.58 | U | | <0.58 | U | | <0.58 | U | | <0.48 | U | |
| | | VMP-2-5-042512 | 4/25/2012 | 0.0077 | J | | <0.032 | U | | <0.04 | U | | <0.019 | U | | <0.079 | U | | 0.092 | | | <0.029 | U | | <0.023 | U | | <0.023 | U | | <0.023 | U | | 0.003 | J | |
| | | VMP-2-5-071612 | 7/16/2012 | <0.0043 | J | U | <0.0079 | U | | <0.0098 | U | | 0.0067 | | | <0.019 | U | | 0.0064 | | | <0.0071 | U | | <0.0056 | U | | <0.0056 | U | | <0.0056 | J | U | 0.0023 | J | |
| | | VMP-2-5-102412 | 10/24/2012 | <0.0066 | J | U | <0.012 | U | | <0.015 | U | | <0.007 | U | | <0.03 | U | | <0.0049 | U | | <0.011 | U | | <0.0086 | U | | <0.0086 | U | | <0.0086 | U | | 0.0028 | J | |
| | | VMP-2-5-013113 | 1/31/2013 | <0.0064 | U | | <0.012 | U | | <0.014 | U | | <0.0067 | U | | <0.028 | U | | <0.0048 | U | | <0.011 | U | | <0.0083 | U | | <0.0083 | U | | <0.0083 | U | | 0.0021 | J | |
| | 8.5 ft | VMP-2-8.5-083110 | 8/31/2010 | <2.1 | U | | <3.9 | U | | <1.2 | U | | <2.2 | U | | <3.8 | U | | 57 | | | <3.5 | U | | <2.8 | U | | <2.8 | U | | <2.8 | U | | <2.3 | U | |
| | | VMP-2-8.5-111610 | 11/16/2010 | <5.8 | U | | <11 | U | | <3.3 | U | | <6.2 | U | | <10 | U | | <4.3 | U | | <9.7 | U | | <7.6 | U | | <7.6 | U | | <7.6 | U | | <6.2 | U | |
| | | VMP-2-8.5-020411 | 2/4/2011 | <2 | U | | <3.7 | U | | <1.1 | U | | <2.1 | U | | <3.6 | U | | 9.6 | | | <3.3 | U | | <2.6 | U | | <2.6 | U | | <2.6 | U | | <2.1 | U | |
| | | VMP-2-8.5-041311 | 4/13/2011 | 0.098 | J | | <1.1 | U | | <1.4 | U | | 0.11 | J | | <1.1 | U | | 0.14 | J | | <1 | U | | <0.79 | U | | <0.79 | U | | <0.79 | U | | <0.65 | U | |
| | | VMP-2-8.5-080211 | 8/2/2011 | <24 | U | | <45 | U | | <56 | U | | <26 | U | | <44 | U | | 52 | | | <41 | U | | <32 | U | | <32 | U | | <32 | U | | <26 | U | |
| | | VMP-2-8.5-110711 | 11/7/2011 | <0.052 | U | | <0.097 | U | | <0.12 | U | | <0.056 | U | | <0.094 | U | | <0.039 | U | | <0.088 | U | | <0.068 | U | | <0.068 | U | | <0.068 | U | | <0.056 | U | |
| | | VMP-2-8.5-012612 | 1/26/2012 | <2.3 | U | | <4.3 | U | | <5.3 | U | | <2.5 | U | | <4.2 | U | | 4.1 | | | <3.9 | U | | <3 | U | | <3 | U | | <3 | U | | <2.5 | U | |
| | | VMP-2-8.5-012612-DUP | 1/26/2012 | <2.3 | U | | <4.3 | U | | <5.3 | U | | <2.5 | U | | <4.2 | U | | 5.4 | | J | <3.9 | U | | <3 | U | | <3 | U | | <3 | U | | <2.5 | U | |
| | | VMP-2-8.5-041612 | 4/16/2012 | <0.0045 | U | | <0.0083 | U | | <0.01 | U | | <0.0048 | U | | <0.02 | U | | 0.0096 | | | <0.0075 | U | | <0.0059 | U | | <0.0059 | U | | <0.0059 | J | U | 0.0029 | J | |
| | | VMP-2-8.5-041612-Dup | 4/16/2012 | <0.0046 | U | | <0.0086 | U | | <0.011 | U | | <0.0049 | U | | 0.00093 | J | | 0.0094 | | | 0.0017 | J | | <0.006 | U | | <0.006 | U | | <0.006 | J | U | 0.003 | J | |
| | | VMP-2-8.5-071612 | 7/16/2012 | <0.0049 | | U | <0.0095 | U | | <0.012 | U | | 0.0068 | | | <0.023 | U | | <0.0038 | J | U | <0.0086 | J | U | <0.0067 | J | U | <0.0067 | J | U | <0.0067 | J | U | 0.0029 | J | |
| | | VMP-2-8.5-071612-Dup | 7/16/2012 | <0.0042 | J | U | <0.0078 | U | | <0.0097 | U | | 0.0063 | | | <0.019 | U | | 0.0015 | J | | <0.0071 | U | | <0.0055 | U | | <0.0055 | U | | <0.0055 | J | U | 0.0032 | J | |
| | | VMP-2-8.5-102312 | 10/23/2012 | <0.0067 | J | U | <0.012 | U | | <0.015 | U | | <0.0071 | U | | <0.03 | U | | 0.04 | | | <0.011 | U | | <0.0087 | U | | <0.0087 | U | | <0.0087 | U | | 0.0025 | J | |
| | | VMP-2-8.5-020513 | 2/5/2013 | <0.0068 | U | | <0.013 | U | | <0.016 | U | | <0.0072 | U | | <0.03 | U | | 0.0071 | | | <0.011 | U | | <0.0089 | U | | <0.0089 | U | | <0.0089 | U | | 0.0023 | J | |
| | 22 ft | VMP-2-22-083110 | 8/31/2010 | <3.2 | U | | <6 | U | | <1.9 | U | | <3.4 | U | | <5.8 | U | | 81 | | | <5.4 | U | | <4.2 | U | | <4.2 | U | | <4.2 | U | | <3.5 | U | |
| | | VMP-2-22-111610 | 11/16/2010 | <6.1 | U | | <11 | U | | <3.5 | U | | <6.4 | U | | <11 | U | | <4.5 | U | | <10 | U | | <7.9 | U | | <7.9 | U | | <7.9 | U | | <6.5 | U | |
| | | VMP-2-22-020411 | 2/4/2011 | <2.7 | U | | <5.1 | U | | <1.6 | U | | <2.9 | U | | <4.9 | U | | 29 | | | <4.6 | U | | <3.6 | U | | <3.6 | U | | <3.6 | U | | <2.9 | U | |
| | | VMP-2-22-041311 | 4/13/2011 | 0.89 | J | | <15 | U | | <18 | U | | <8.5 | U | | <14 | U | | 4.2 | J | | <13 | U | | <10 | U | | <10 | U | | <10 | U | | <8.6 | U | |
| | | VMP-2-22-080211 | 8/2/2011 | <32 | U | | <60 | U | | <74 | U | | <34 | U | | <58 | U | | 57 | | | <54 | U | | <42 | U | | <42 | U | | <42 | U | | <35 | U | |
| | | VMP-2-22-110711 | 11/7/2011 | <1.7 | U | | <3.2 | U | | <3.9 | U | | <1.8 | U | | <3.1 | U | | 1.1 | J | | <2.9 | U | | <2.2 | U | | <2.2 | U | | <2.2 | U | | <1.8 | U | UJ |
| | | VMP-2-22-012612 | 1/26/2012 | <3.6 | U | | <6.6 | U | | <8.2 | U | | <3.8 | U | | <6.4 | U | | 6.4 | | J | <6 | U | | <4.6 | U | | <4.6 | U | | <4.6 | U | | <3.8 | U | |
| | | VMP-2-22-042712 | 4/27/2012 | <0.0037 | J | U | <0.0068 | U | | <0.0085 | U | | 0.0065 | | | <0.017 | U | | 0.0033 | | | <0.0062 | U | | <0.0048 | U | | <0.0048 | U | | <0.0048 | J | U | 0.0026 | J | |
| | | VMP-2-22-071612 | 7/16/2012 | <0.0044 | J | U | <0.0081 | U | | <0.01 | U | | 0.006 | | | <0.02 | U | | 0.0087 | | | <0.0073 | U | | <0.0057 | J | U | <0.0057 | J | U | <0.0057 | J | U | 0.0029 | J | |
| | | VMP-2-22-102312 | 10/23/2012 | <0.0067 | J | U | <0.012 | U | | <0.015 | U | | <0.0071 | U | | <0.03 | U | | 0.01 | | | <0.011 | U | | <0.0087 | U | | <0.0087 | U | | <0.0087 | U | | 0.0028 | J | |
| | | VMP-2-22-013113 | 1/31/2013 | <0.0062 | U | | <0.011 | U | | <0.014 | U | | <0.0066 | U | | <0.028 | U | | <0.0046 | U | | <0.01 | U | | <0.0081 | U | | <0.0081 | U | | <0.0081 | U | | 0.0025 | J | |
| | 42 ft | VMP-2-42-013113 | 1/31/2013 | <60 | U | | <110 | U | | <140 | U | | <63 | U | | <270 | U | | 150 | | | <100 | U | | 24 | J | | 27 | J | | 32 | J | | <64 | U | |

SEE LAST PAGE OF TABLE FOR NOTES

**TABLE 5**
**CUMULATIVE SUMMARY OF SOIL VAPOR ANALYTICAL DETECTIONS AND SCREENING RESULTS: VILLAGE - VOCS**

| Location | Depth | Sample ID | Sample Date | Chlorobenzene | | | Chlorodibromomethane | | | Chloroethane | | | Chloroform | | | Chloromethane | | | Cyclohexane | | | 1,2-Dibromoethane | | | 1,2-Dichlorobenzene | | | 1,3-Dichlorobenzene | | | 1,4-Dichlorobenzene | | | Dichlorodifluoromethane | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | 69 | | | 57000 | | | | | | 0.11 | | | | | | | | | 0.011 | | | 290 | | | | | | 1200 | | | | | |
| | | | | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals |
| VMP-3 | 5 ft | VMP-3-5-090910 | 9/9/2010 | <6.1 | U | | <11 | U | | <3.5 | U | | <6.5 | U | | <11 | U | | 210 | | | <10 | U | | <8 | U | | <8 | U | | <8 | U | | <6.6 | U | |
| | | VMP-3-5-112210 | 11/22/2010 | <6.2 | U | | <11 | U | | <3.5 | U | | <6.6 | U | | <11 | U | | 340 | | | <10 | U | | <8.1 | U | | <8.1 | U | | <8.1 | U | | <6.6 | U | |
| | | VMP-3-5-020911 | 2/9/2011 | <2.8 | U | | <5.2 | U | | <1.6 | U | | <3 | U | | <5 | U | | 77 | | | <4.6 | U | | <3.6 | U | | <3.6 | U | | <3.6 | U | | <3 | U | |
| | | VMP-3-5-041411 | 4/14/2011 | <30 | U | | <55 | U | | <69 | U | | <32 | U | | <54 | U | | 210 | | | <50 | U | | <39 | U | | <39 | U | | <39 | U | | <32 | U | |
| | | VMP-3-5-080211 | 8/2/2011 | <0.0072 | U | | <0.013 | U | | <0.016 | U | | <0.076 | U | | <0.013 | U | | 0.0084 | | | <0.012 | U | | <0.0093 | U | | <0.0093 | U | | <0.0093 | U | | <0.0077 | U | |
| | | VMP-3-5-110811 | 11/8/2011 | <0.0039 | U | | <0.0073 | U | | <0.009 | U | | <0.0042 | U | | <0.0071 | U | | <0.0029 | U | | <0.0066 | U | | <0.0051 | U | | <0.0051 | U | | <0.0051 | U | | 0.0019 | J | |
| | | VMP-3-5-110811-DUP | 11/8/2011 | <0.004 | U | | <0.0074 | U | | <0.0092 | U | | <0.0043 | U | | <0.0072 | U | | <0.003 | U | | <0.0067 | U | | <0.0053 | U | | <0.0053 | U | | <0.0053 | U | | 0.002 | J | |
| | | VMP-3-5-012712 | 1/27/2012 | <2 | U | | <3.7 | U | | <4.6 | U | | <2.1 | U | | <3.6 | U | | 5.2 | | | <3.4 | U | | <2.6 | U | | <2.6 | U | | <2.6 | U | | <2.2 | U | |
| | | VMP-3-5-041912 | 4/19/2012 | <0.0044 | U | | <0.0081 | U | | <0.01 | U | | <0.0047 | U | | <0.02 | U | | 0.015 | | | 0.002 | J | | <0.0057 | U | | <0.0057 | J | U | <0.0057 | J | U | 0.0031 | J | |
| | | VMP-3-5-072712 | 7/27/2012 | <0.0046 | J | U | <0.0086 | U | | <0.011 | U | | 0.0072 | | | <0.021 | U | | 0.00067 | J | | <0.0077 | U | | <0.006 | J | U | <0.006 | J | U | <0.006 | J | U | 0.0029 | J | |
| | 10 ft | VMP-3-10 | 6/21/2010 | <7 | U | | <13 | U | | <4 | U | | <7.4 | U | | <12 | U | | 1000 | | | <12 | U | | <9.1 | U | | <9.1 | U | | <9.1 | U | | <7.5 | U | |
| | | VMP-3-10-091010 | 9/10/2010 | <20 | U | | <36 | U | | <11 | U | | <21 | U | | <35 | U | | 970 | | | <33 | U | | <26 | U | | <26 | U | | <26 | U | | <21 | U | |
| | | VMP-3-10-092010 | 9/20/2010 | <14 | U | | <26 | U | | <8.2 | U | | <15 | U | | <26 | U | | 840 | | | <24 | U | | <19 | U | | <19 | U | | <19 | U | | <15 | U | |
| | | VMP-3-10-112210 | 11/22/2010 | <6.1 | U | | <11 | U | | <3.5 | U | | <6.4 | U | | <11 | U | | 1300 | | | <10 | U | | <7.9 | U | | <7.9 | U | | <7.9 | U | | <6.5 | U | |
| | | VMP-3-10-112210-Dup | 11/22/2010 | <8.5 | U | | <16 | U | | <4.8 | U | | <9 | U | | <15 | U | | 1100 | | | <14 | U | | <11 | U | | <11 | U | | <11 | U | | <9.1 | U | |
| | | VMP-3-10-020811 | 2/8/2011 | <8.9 | U | | <16 | U | | <5.1 | U | | <9.5 | U | | <16 | U | | 930 | | | <15 | U | | <12 | U | | <12 | U | | <12 | U | | <9.6 | U | |
| | | VMP-3-10-041311 | 4/13/2011 | <52 | U | | <96 | U | | <120 | U | | <55 | U | | <93 | U | | 570 | | | <86 | U | | <68 | U | | <68 | U | | <68 | U | | <56 | U | |
| | | VMP-3-10-080311 | 8/3/2011 | 0.13 | | | <0.12 | U | | <0.15 | U | | <0.069 | U | | <0.12 | U | | 3.6 | | | <0.11 | U | | <0.085 | U | | <0.085 | U | | <0.085 | U | | <0.07 | U | |
| | | VMP-3-10-110811 | 11/8/2011 | <0.0054 | U | | <0.0099 | U | | <0.012 | U | | 0.018 | | | <0.0096 | U | | 0.012 | | | <0.009 | U | | <0.007 | U | | <0.007 | U | | <0.007 | U | | 0.0022 | J | J |
| | | VMP-3-10-012712 | 1/27/2012 | <0.039 | U | | <0.072 | U | | <0.089 | U | | <0.041 | U | | <0.069 | U | | 0.4 | | | <0.064 | U | | <0.05 | U | | <0.05 | U | | <0.05 | U | | <0.042 | U | |
| | | VMP-3-10-042012 | 4/20/2012 | <0.0039 | J | U | <0.0073 | U | | <0.009 | U | | 0.002 | J | | <0.018 | U | | 0.0056 | | | 0.0032 | J | | <0.0051 | J | U | <0.0051 | J | U | <0.0051 | J | U | 0.003 | J | |
| | | VMP-3-10-072312 | 7/23/2012 | <0.0046 | U | | <0.0086 | U | | <0.011 | U | | 0.0056 | | | <0.021 | U | | 0.0051 | | | <0.0077 | U | | <0.006 | U | | <0.006 | U | | <0.006 | U | | 0.0027 | J | |
| | | VMP-3-10-101812 | 10/18/2012 | <0.007 | U | | <0.013 | U | | <0.016 | U | | <0.0074 | U | | <0.031 | U | | 0.1 | | | <0.012 | U | | <0.0091 | U | | <0.0091 | U | | <0.0091 | U | | 0.0025 | J | |
| | | VMP-3-10-020613 | 2/6/2013 | <0.0065 | U | | <0.012 | U | | <0.015 | U | | <0.0069 | U | | <0.029 | U | | <0.0048 | U | | <0.011 | U | | <0.0085 | U | | <0.0085 | U | | <0.0085 | U | | 0.0025 | J | |
| | 22 ft | VMP-3-22-092010 | 9/20/2010 | <19 | U | | <35 | U | | <11 | U | | <20 | U | | <34 | U | | 1100 | | | <31 | U | | <24 | U | | <24 | U | | <24 | U | | <20 | U | |
| | | VMP-3-22-112210 | 11/22/2010 | <21 | U | | <40 | U | | <12 | U | | <23 | U | | <38 | U | | 1300 | | | <36 | U | | <28 | U | | <28 | U | | <28 | U | | <23 | U | |
| | | VMP-3-22-020811 | 2/8/2011 | <10 | U | | <20 | U | | <6 | U | | <11 | U | | <19 | U | | 890 | | | <18 | U | | <14 | U | | <14 | U | | <14 | U | | <11 | U | |
| | | VMP-3-22-041511 | 4/15/2011 | <57 | U | | <100 | U | | <130 | U | | <60 | U | | <100 | U | | 760 | | | <95 | U | | <74 | U | | <74 | U | | <74 | U | | <61 | U | |
| | | VMP-3-22-080611 | 8/6/2011 | <0.091 | U | | <0.17 | U | | <0.21 | U | | <0.096 | U | | <0.16 | U | | 0.78 | | | <0.15 | U | | <0.12 | U | | <0.12 | U | | <0.12 | U | | <0.098 | U | |
| | | VMP-3-22-110811 | 11/8/2011 | <0.004 | U | | <0.0074 | U | | <0.0092 | U | | <0.0043 | U | | <0.0072 | U | | 0.0038 | | | <0.0067 | U | | <0.0053 | U | | <0.0053 | U | | <0.0053 | U | | 0.0019 | J | |
| | | VMP-3-22-013012 | 1/30/2012 | <0.016 | J | U | <0.03 | U | | <0.037 | U | | <0.017 | U | | <0.029 | U | | 0.39 | | | <0.027 | U | | <0.021 | U | | <0.021 | U | | <0.021 | U | | <0.017 | U | |
| | | VMP-3-22-042012 | 4/20/2012 | <0.004 | J | U | <0.0074 | U | | <0.0092 | U | | 0.00067 | J | | <0.018 | U | | 0.0072 | | | 0.0021 | J | | <0.0053 | J | U | <0.0053 | J | U | <0.0053 | J | U | 0.0027 | J | |
| | | VMP-3-22-072312 | 7/23/2012 | <0.0045 | U | | <0.0083 | U | | <0.01 | U | | <0.0048 | U | | <0.02 | U | | <0.0034 | U | | <0.0075 | U | | <0.0059 | U | | <0.0059 | U | | <0.0059 | U | | 0.0026 | J | |
| | | VMP-3-22-101812 | 10/18/2012 | <0.0068 | U | | <0.013 | U | | <0.016 | U | | 0.033 | | | <0.03 | U | | 0.0035 | J | | <0.011 | U | | <0.0089 | U | | <0.0089 | U | | <0.0089 | U | | 0.0024 | J | |
| | | VMP-3-22-020613 | 2/6/2013 | <0.0066 | U | | <0.012 | U | | <0.015 | U | | 0.078 | | | <0.03 | U | | <0.005 | U | | <0.011 | U | | <0.0087 | U | | <0.0087 | U | | <0.0087 | U | | 0.0026 | J | |
| | 31.5 ft | VMP-3-31.5-090910 | 9/9/2010 | <35 | U | | <65 | U | | <20 | U | | <37 | U | | <63 | U | | 1100 | | | <58 | U | | <46 | U | | <46 | U | | <46 | U | | <38 | U | |
| | | VMP-3-31.5-112210 | 11/22/2010 | <24 | U | | <45 | U | | <14 | U | | <26 | U | | <44 | U | | 1400 | | | <41 | U | | <32 | U | | <32 | U | | <32 | U | | <26 | U | |
| | | VMP-3-31.5-020911 | 2/9/2011 | <23 | U | | <43 | U | | <13 | U | | <25 | U | | <42 | U | | 1000 | | | <39 | U | | <30 | U | | <30 | U | | <30 | U | | <25 | U | |
| | | VMP-3-31.5-041411 | 4/14/2011 | <190 | U | | <350 | U | | <440 | U | | <200 | U | | <340 | U | | 910 | | | <320 | U | | <250 | U | | <250 | U | | <250 | U | | <200 | U | |
| | | VMP-3-31.5-041411-DUP | 4/14/2011 | <190 | U | | <350 | U | | <440 | U | | <200 | U | | <340 | U | | 830 | | | <320 | U | | <250 | U | | <250 | U | | <250 | U | | <200 | U | |
| | | VMP-3-31.5-080211 | 8/2/2011 | <430 | U | | <800 | U | | <990 | U | | <460 | U | | <780 | U | | 1000 | | | <720 | U | | <560 | U | | <560 | U | | <560 | U | | <460 | U | |
| | | VMP-3-31.5-080211-Dup | 8/2/2011 | <250 | U | | <470 | U | | <580 | U | | <270 | U | | <450 | U | | 1400 | | | <420 | U | | <330 | U | | <330 | U | | <330 | U | | <270 | U | |
| | | VMP-3-31.5-110811 | 11/8/2011 | <10 | U | | <19 | U | | <23 | U | | <11 | U | | <18 | U | | 49 | | | <17 | U | | <13 | U | | <13 | U | | <13 | U | | <11 | U | |
| | | VMP-3-31.5-012712 | 1/27/2012 | <64 | U | | <120 | U | | <150 | U | | <68 | U | | <110 | U | | 210 | | J | <110 | U | | <83 | U | | <83 | U | | <83 | U | | <68 | U | |
| | | VMP-3-31.5-041912 | 4/19/2012 | <110 | U | | <200 | U | | <250 | U | | <120 | U | | <200 | U | | 580 | | | <180 | U | | <140 | U | | <140 | U | | <140 | U | | <120 | U | |
| | | VMP-3-31.5-041912-Dup | 4/19/2012 | <100 | U | | <200 | U | | <240 | U | | <110 | U | | <190 | U | | 590 | | | <180 | U | | <140 | U | | <140 | U | | <140 | U | | <110 | U | |
| | | VMP-3-31.5-072312 | 7/23/2012 | <26 | U | | <49 | U | | <60 | U | | <28 | U | | <47 | U | | 120 | | | <44 | U | | <34 | U | | <34 | U | | <34 | U | | <28 | U | |
| | | VMP-3-31.5-101912 | 10/19/2012 | <2.1 | U | | <3.9 | U | | <4.8 | U | | <2.2 | U | | <3.8 | U | | 6.8 | | | <3.5 | U | | <2.8 | U | | <2.8 | U | | <2.8 | U | | <2.3 | U | |
| | | VMP-3-31.5-020713 | 2/7/2013 | <12 | U | | <22 | U | | <27 | U | | <12 | U | | <21 | U | | <8.9 | U | | <20 | U | | <16 | U | | <16 | U | | <16 | U | | <13 | U | |
| | 39.5 ft | VMP-3-39-101912 | 10/19/2012 | <210 | U | | <390 | U | | <480 | U | | <220 | U | | <380 | U | | 340 | | | <350 | U | | <280 | U | | <280 | U | | <280 | U | | <230 | U | |
| | | VMP-3-39-021213 | 2/12/2013 | <61 | U | | <110 | U | | <140 | U | | <64 | U | | <110 | U | | <45 | U | | <100 | U | | <79 | U | | <79 | U | | <79 | U | | <65 | U | |
| VMP-4 | 5 ft | VMP-4-5-082510 | 8/25/2010 | <0.33 | U | | <0.61 | U | | <0.19 | U | | <0.35 | U | | <0.59 | U | | 40 | | | <0.55 | U | | <0.43 | U | | <0.43 | U | | <0.43 | U | | <0.36 | U | |
| | | VMP-4-5-112210 | 11/22/2010 | <12 | U | | <23 | U | | <7.1 | U | | <13 | U | | <22 | U | | 1200 | | | <21 | U | | <16 | U | | <16 | U | | <16 | U | | <13 | U | |
| | | VMP-4-5-021411 | 2/14/2011 | <0.72 | U | | <1.3 | U | | <0.42 | U | | <0.77 | U | | <1.3 | U | | 120 | | | <1.2 | U | | <0.95 | U | | <0.95 | U | | <0.95 | U | | <0.78 | U | |
| | | VMP-4-5-041911 | 4/19/2011 | <33 | U | | <62 | U | | <76 | U | | <35 | U | | <60 | U | | 770 | | | <56 | U | | <44 | U | | <44 | U | | <44 | U | | <36 | U | |
| | | VMP-4-5-080311 | 8/3/2011 | 0.02 | J | | <0.13 | U | | <0.16 | U | | <0.076 | U | | <0.13 | U | | 0.2 | | | <0.12 | U | | <0.093 | U | | <0.093 | U | | <0.093 | U | | <0.077 | U | |
| | | VMP-4-5-110911 | 11/9/2011 | <0.0039 | U | | <0.0073 | U | | <0.009 | U | | <0.0042 | U | | 0.0014 | J | | 0.0092 | | | <0.0066 | U | | <0.0051 | U | | <0.0051 | U | | <0.0051 | U | | 0.0019 | J | |
| | | VMP-4-5-013012 | 1/30/2012 | <0.2 | U | | <0.37 | U | | <0.46 | U | | <0.21 | U | | <0.36 | U | | 6.2 | | J | <0.34 | U | | <0.26 | U | | <0.26 | U | | <0.26 | U | | <0.22 | U | |
| | | VMP-4-5-042512 | 4/25/2012 | <0.005 | J | U | <0.0092 | U | | <0.011 | U | | <0.0053 | U | | <0.022 | U | | 0.17 | | | 0.0022 | J | | <0.0065 | J | U | <0.0065 | J | U | <0.0065 | J | U | 0.0026 | J | |
| | | VMP-4-5-072512 | 7/25/2012 | <0.0049 | J | U | <0.0091 | U | | <0.011 | U | | 0.0019 | J | | <0.022 | U | | 0.0087 | | | <0.0082 | U | | <0.0064 | U | | <0.0064 | J | U | <0.0064 | J | U | 0.0028 | J | |
| | | VMP-4-5-101812 | 10/18/2012 | <0.0072 | U | | <0.013 | U | | <0.016 | U | | <0.0076 | U | | <0.032 | U | | 0.0012 | J | | <0.012 | U | | <0.0093 | U | | <0.0093 | U | | <0.0093 | U | | 0.0032 | J | |
| | | VMP-4-5-020713 | 2/7/2013 | <0.0057 | U | | <0.01 | U | | <0.013 | U | | <0.006 | U | | <0.026 | U | | <0.0042 | U | | <0.0095 | U | | <0.0074 | U | | <0.0074 | U | | <0.0074 | U | | 0.0022 | J | |
| | 12 ft | VMP-4-12-082510 | 8/25/2010 | <5.8 | U | | <11 | U | | <3.3 | U | | <6.2 | U | | <10 | U | | 880 | | | <9.7 | U | | <7.6 | U | | <7.6 | U | | <7.6 | U | | <6.2 | U | |
| | | VMP-4-12-112310 | 11/23/2010 | <5.9 | U | | <11 | U | | <3.4 | U | | <6.3 | U | | <11 | U | | 760 | | | <9.9 | U | | <7.8 | U | | <7.8 | U | | <7.8 | U | | <6.4 | U | |
| | | VMP-4-12-021411 | 2/14/2011 | <1.5 | U | | <2.8 | U | | <0.85 | U | | <1.6 | U | | <2.7 | U | | 280 | | | <2.5 | U | | <1.9 | U | | <1.9 | U | | <1.9 | U | | <1.6 | U | |
| | | VMP-4-12-041911 | 4/19/2011 | <29 | U | | <53 | U | | <66 | U | | <30 | U | | <52 | U | | 860 | | | <48 | U | | <38 | U | | <38 | U | | <38 | U | | <31 | U | |
| | | VMP-4-12-080311 | 8/3/2011 | <3.3 | U | | <6.1 | U | | <7.6 | U | | <3.5 | U | | <5.9 | U | | 230 | | | <5.5 | U | | <4.3 | U | | <4.3 | U | | <4.3 | U | | <3.6 | U | |
| | | VMP-4-12-080311-Dup | 8/3/2011 | <6.6 | U | | <12 | U | | <15 | U | | <7 | U | | <12 | U | | 210 | | | <11 | U | | <8.7 | U | | <8.7 | U | | <8.7 | U | | <7.1 | U | |
| | | VMP-4-12-110911 | 11/9/2011 | <1 | U | | <1.9 | U | | <2.3 | U | | <1.1 | U | | <1.8 | U | | 16 | | | <1.7 | U | | <1.3 | U | | <1.3 | U | | <1.3 | U | | <1.1 | U | UJ |
| | | VMP-4-12-013012 | 1/30/2012 | <2.1 | U | | <3.8 | U | | <4.7 | U | | <2.2 | U | | <3.7 | U | | 100 | | | <3.4 | U | | <2.7 | U | | <2.7 | U | | <2.7 | U | | <2.2 | U | |
| | | VMP-4-12-041812 | 4/18/2012 | <0.0046 | U | | <0.0086 | U | | <0.011 | U | | <0.0049 | U | | 0.0028 | J | | 0.0096 | | | 0.0019 | J | | <0.006 | U | | <0.006 | J | U | <0.006 | J | U | 0.003 | J | |
| | | VMP-4-12-072312 | 7/23/2012 | <0.022 | U | | <0.041 | U | | <0.051 | U | | <0.024 | U | | <0.1 | U | | 0.1 | | | <0.037 | U | | <0.029 | U | | <0.029 | U | | <0.029 | U | | <0.024 | U | |
| | | VMP-4-12-101812 | 10/18/2012 | <0.007 | U | | <0.013 | U | | <0.016 | U | | <0.0074 | U | | 0.002 | J | | 0.002 | J | | <0.012 | U | | <0.0091 | U | | <0.0091 | U | | <0.0091 | U | | <0.0075 | U | |
| | | VMP-4-12-101812-Dup | 10/18/2012 | <0.0072 | U | | <0.013 | U | | <0.016 | U | | <0.0076 | U | | 0.0071 | J | | 0.0024 | J | | <0.012 | U | | <0.0093 | U | | <0.0093 | U | | <0.0093 | U | | 0.0023 | J | |
| | | VMP-4-12-020713 | 2/7/2013 | <0.0062 | U | | <0.011 | U | | <0.014 | U | | <0.0066 | U | | <0.028 | U | | 0.0033 | J | | <0.01 | U | | <0.0081 | U | | <0.0081 | U | | <0.0081 | U | | 0.0026 | J | |
| | | VMP-4-12-020713-DUP | 2/7/2013 | <0.0064 | U | | <0.012 | U | | <0.014 | U | | <0.0067 | U | | <0.028 | U | | <0.0048 | U | | <0.011 | U | | <0.0083 | U | | <0.0083 | U | | <0.0083 | U | | 0.0025 | J | |
| | 23.5 ft | VMP - 4 - 23.5 - 083110 | 8/31/2010 | <6.6 | U | | <12 | U | | <3.8 | U | | <7 | U | | <12 | U | | 3000 | | J | <11 | U | | <8.7 | U | | <8.7 | U | | <8.7 | U | | <7.1 | U | |
| | | VMP-4-23.5-112310 | 11/23/2010 | <67 | U | | <120 | U | | <38 | U | | <71 | U | | <120 | U | | 2900 | | | <110 | U | | <87 | U | | <87 | U | | <87 | U | | <72 | U | |
| | | VMP-4-23.5-021411 | 2/14/2011 | <2.4 | U | | <4.5 | U | | <1.4 | U | | <2.6 | U | | <4.4 | U | | 1700 | | J | <4.1 | U | | <3.2 | U | | <3.2 | U | | <3.2 | U | | <2.6 | U | |
| | | VMP-4-23.5-042011 | 4/20/2011 | <160 | U | | <290 | U | | <360 | U | | <160 | U | | <280 | U | | 2600 | | | <260 | U | | <200 | U | | <200 | U | | <200 | U | | <170 | U | |
| | | VMP-4-23.5-042011-DUP | 4/20/2011 | <160 | U | | <290 | U | | <360 | U | | <160 | U | | <280 | U | | 2400 | | | <260 | U | | <200 | U | | <200 | U | | <200 | U | | <170 | U | |
| | | VMP-4-23.5-080611 | 8/6/2011 | <6.5 | U | | <12 | U | | <15 | U | | <6.9 | U | | <12 | U | | 1900 | | | <11 | U | | <8.4 | U | | <8.4 | U | | <8.4 | U | | <6.9 | U | |
| | | VMP-4-23.5-110911 | 11/9/2011 | <19 | U | | <36 | U | | <44 | U | | <20 | U | | <35 | U | | 940 | | | <32 | U | | <25 | U | | <25 | U | | <25 | U | | <21 | U | |
| | | VMP-4-23.5-013012 | 1/30/2012 | <41 | U | | <76 | U | | <94 | U | | <44 | U | | <74 | U | | 3400 | | J | <69 | U | | <54 | U | | <54 | U | | <54 | U | | <44 | U | |
| | | VMP-4-23.5-013012-DUP | 1/30/2012 | <29 | U | | <53 | U | | <66 | U | | <30 | U | | <52 | U | | 2500 | | J | <48 | U | | <38 | U | | <38 | U | | <38 | U | | <31 | U | |
| | | VMP-4-23.5-041912 | 4/19/2012 | <9 | U | | <17 | U | | <21 | U | | <9.6 | U | | <16 | U | | 1500 | | | <15 | U | | <12 | U | | <12 | U | | <12 | U | | <9.7 | U | |
| | | VMP-4-23.5-072312 | 7/23/2012 | <4.3 | U | | <8 | U | | <9.9 | U | | <4.6 | U | | <7.8 | U | | 540 | | | <7.2 | U | | <5.6 | U | | <5.6 | U | | <5.6 | U | | <4.6 | U | |
| | | VMP-4-23.5-101812 | 10/18/2012 | <4.7 | U | | <8.8 | U | | <11 | U | | <5 | U | | <8.5 | U | | 52 | | | <7.9 | U | | <6.2 | U | | <6.2 | U | | <6.2 | U | | <5.1 | U | |
| | | VMP-4-23.5-020713 | 2/7/2013 | <1.5 | U | | <2.8 | U | | <3.5 | U | | <1.6 | U | | <2.7 | U | | <1.1 | U | | <2.5 | U | | <2 | U | | <2 | U | | <2 | U | | <1.6 | U | |
| | 39 ft | VMP-4-39-042111 | 4/21/2011 | <190 | U | | <360 | U | | <440 | U | | <200 | U | | <350 | U | | 2400 | | | <320 | U | | <250 | U | | <250 | U | | <250 | U | | <210 | U | |
| | | VMP-4-39-041912 | 4/19/2012 | <4.6 | U | | <8.6 | U | | <11 | U | | <4.9 | U | | <8.3 | U | | 2300 | | | <7.7 | U | | <6 | U | | <6 | U | | <6 | U | | <5 | U | |
| | | VMP-4-39-072312 | 7/23/2012 | <7 | U | | <13 | U | | <16 | U | | <7.4 | U | | <12 | U | | 1400 | | J | <12 | U | | <9.1 | U | | <9.1 | U | | <9.1 | U | | <7.5 | U | |
| | | VMP-4-39-101812 | 10/18/2012 | <87 | U | | <160 | U | | <200 | U | | <92 | U | | <160 | U | | 710 | | | <140 | U | | <110 | U | | <110 | U | | <110 | U | | <94 | U | |
| | | VMP-4-39-101812-Dup | 10/18/2012 | <79 | U | | <150 | U | | <180 | U | | <84 | U | | <140 | U | | 670 | | | <130 | U | | <100 | U | | <100 | U | | <100 | U | | <85 | U | |
| | | VMP-4-39-020713 | 2/7/2013 | <12 | U | | <23 | U | | <28 | U | | <13 | U | | <22 | U | | <9.2 | U | | <21 | U | | <16 | U | | <16 | U | | <16 | U | | <13 | U | |

SEE LAST PAGE OF TABLE FOR NOTES

**TABLE 5**
**CUMULATIVE SUMMARY OF SOIL VAPOR ANALYTICAL DETECTIONS AND SCREENING RESULTS: VILLAGE - VOCS**

| Location | Depth | Sample ID | Sample Date | Chlorobenzene | | | Chlorodibromomethane | | | Chloroethane | | | Chloroform | | | Chloromethane | | | Cyclohexane | | | 1,2-Dibromoethane | | | 1,2-Dichlorobenzene | | | 1,3-Dichlorobenzene | | | 1,4-Dichlorobenzene | | | Dichlorodifluoromethane | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | 69 | | | 57000 | | | | | | 0.11 | | | | | | | | | 0.011 | | | 290 | | | | | | 1200 | | | | | |
| | | | | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals |
| VMP-5 | 5 ft | VMP-5-5-090910 | 9/9/2010 | <12 | U | | <22 | U | | <7 | U | | <13 | U | | <22 | U | | 400 | | | <20 | U | | <16 | U | | <16 | U | | <16 | U | | <13 | U | |
| | | VMP-5-5-112210 | 11/22/2010 | <3 | U | | <5.5 | U | | <1.7 | U | | <3.1 | U | | <5.3 | U | | 450 | | | <5 | U | | <3.9 | U | | <3.9 | U | | <3.9 | U | | <3.2 | U | |
| | | VMP-5-5-021611 | 2/16/2011 | <0.019 | U | | <0.035 | U | | <0.011 | U | | <0.02 | U | | <0.034 | U | | 4.4 | | | <0.032 | U | | <0.025 | U | | <0.025 | U | | <0.025 | U | | <0.02 | U | |
| | | VMP-5-5-042111 | 4/21/2011 | <0.061 | U | | <0.11 | U | | <0.14 | U | | <0.064 | U | | <0.11 | U | | 0.033 | J | | <0.1 | U | | <0.079 | U | | <0.079 | U | | <0.079 | U | | <0.065 | U | |
| | | VMP-5-5-080511 | 8/5/2011 | <0.0058 | U | | <0.011 | U | | <0.013 | U | | 0.0015 | J | | <0.01 | U | | 0.035 | | | <0.0097 | U | | <0.0076 | U | | <0.0076 | U | | <0.0076 | U | | 0.0024 | J | |
| | | VMP-5-5-111111 | 11/11/2011 | <0.0043 | U | | <0.0079 | U | | <0.0098 | U | | <0.0045 | U | | <0.0077 | U | | 0.25 | | | <0.0071 | U | | <0.0056 | U | | <0.0056 | U | | <0.0056 | U | | 0.0015 | J | |
| | | VMP-5-5-013012 | 1/30/2012 | 0.014 | J | | <0.08 | U | | <0.099 | U | | <0.046 | U | | <0.077 | U | | 0.44 | | | 0.0073 | J | | <0.056 | U | | <0.056 | U | | <0.056 | U | | <0.046 | U | |
| | | VMP-5-5-041112 | 4/11/2012 | <0.0042 | U | | <0.0078 | U | | <0.0096 | U | | 0.0024 | J | | <0.019 | U | | 0.0012 | J | | <0.007 | U | | <0.0055 | U | | 0.00098 | J | | 0.0021 | J | | 0.0024 | J | |
| | | VMP-5-5-071312 | 7/13/2012 | <0.0047 | J | U | <0.0086 | U | | <0.011 | U | | <0.005 | J | U | <0.021 | U | | <0.0035 | J | U | <0.0078 | U | | <0.0061 | U | | <0.0061 | J | U | <0.0061 | J | U | 0.0024 | J | |
| | | VMP-5-5-101212 | 10/12/2012 | <0.0058 | U | | <0.011 | U | | <0.013 | U | | <0.0062 | U | | <0.026 | U | | <0.0043 | U | | <0.0097 | U | | <0.0076 | U | | <0.0076 | U | | <0.0076 | U | | 0.0025 | J | |
| | | VMP-5-5-012513 | 1/25/2013 | <0.0061 | U | | <0.011 | U | | <0.014 | U | | <0.0064 | U | | <0.027 | U | | <0.0045 | U | | <0.01 | U | | <0.0079 | U | | <0.0079 | U | | <0.0079 | U | | 0.0018 | J | |
| | 12.5 ft | VMP-5-12.5-090910 | 9/9/2010 | <6.1 | U | | <11 | U | | <3.5 | U | | <6.4 | U | | <11 | U | | 360 | | | <10 | U | | <7.9 | U | | <7.9 | U | | <7.9 | U | | <6.5 | U | |
| | | VMP-5-12.5-112310 | 11/23/2010 | <0.3 | U | | <0.56 | U | | <0.17 | U | | <0.32 | U | | <0.54 | U | | 14 | | | <0.51 | U | | <0.4 | U | | <0.4 | U | | <0.4 | U | | <0.33 | U | |
| | | VMP-5-12.5-021611 | 2/16/2011 | <0.91 | U | | <1.7 | U | | <0.52 | U | | <0.97 | U | | <1.6 | U | | 36 | | | <1.5 | U | | <1.2 | U | | <1.2 | U | | <1.2 | U | | <0.98 | U | |
| | | VMP-5-12.5-042111 | 4/21/2011 | <0.065 | U | | <0.12 | U | | <0.15 | U | | <0.069 | U | | <0.12 | U | | 0.023 | J | | <0.11 | U | | <0.085 | U | | <0.085 | U | | <0.085 | U | | <0.07 | U | |
| | | VMP-5-12.5-080611 | 8/6/2011 | <5.7 | U | | <10 | U | | <13 | U | | <6 | U | | <10 | U | | 180 | | | <9.5 | U | | <7.4 | U | | <7.4 | U | | <7.4 | U | | <6.1 | U | |
| | | VMP-5-12.5-111111 | 11/11/2011 | <0.004 | U | | <0.0075 | U | | <0.0093 | U | | 0.021 | | | <0.0073 | U | | 0.0019 | J | | <0.0068 | U | | <0.0053 | U | | <0.0053 | U | | <0.0053 | U | | 0.0017 | J | |
| | | VMP-5-12.5-013012 | 1/30/2012 | <0.013 | J | U | <0.024 | U | | <0.03 | U | | 0.012 | J | | <0.024 | U | | 0.14 | | | <0.022 | U | | <0.017 | U | | <0.017 | U | | <0.017 | U | | <0.014 | U | |
| | | VMP-5-12.5-041112 | 4/11/2012 | <0.004 | U | | <0.0074 | U | | <0.0092 | U | | <0.0043 | U | | <0.018 | U | | 0.0022 | J | | <0.0067 | U | | <0.0053 | U | | 0.0011 | J | | 0.0016 | J | | 0.0027 | J | |
| | | VMP-5-12.5-071212 | 7/12/2012 | <0.0047 | U | | <0.0088 | U | | <0.011 | U | | 0.0015 | J | | <0.021 | U | | <0.0035 | U | | <0.0079 | U | | <0.0062 | U | | <0.0062 | U | | <0.0062 | U | | 0.0022 | J | |
| | | VMP-5-12.5-101112 | 10/11/2012 | <0.011 | U | | <0.021 | U | | <0.026 | U | | <0.012 | U | | <0.05 | U | | <0.0084 | U | | <0.019 | U | | <0.015 | U | | <0.015 | U | | <0.015 | U | | 0.0022 | J | |
| | | VMP-5-12.5-012413 | 1/24/2013 | <0.0059 | U | | <0.011 | U | | <0.014 | U | | <0.0063 | U | | <0.027 | U | | <0.0044 | U | | <0.0099 | U | | <0.0078 | U | | <0.0078 | U | | <0.0078 | U | | <0.0064 | U | |
| | 31 ft | VMP-5-31-090910 | 9/9/2010 | <25 | U | | <47 | U | | <14 | U | | <27 | U | | <45 | U | | 1600 | | | <42 | U | | <33 | U | | <33 | U | | <33 | U | | <27 | U | |
| | | VMP-5-31-112310 | 11/23/2010 | <16 | U | | <29 | U | | <9.1 | U | | <17 | U | | <28 | U | | 2200 | | | <26 | U | | <21 | U | | <21 | U | | <21 | U | | <17 | U | |
| | | VMP-5-31-021611 | 2/16/2011 | <6.4 | U | | <12 | U | | <3.6 | U | | <6.7 | U | | <11 | U | | 1300 | | | <11 | U | | <8.3 | U | | <8.3 | U | | <8.3 | U | | <6.8 | U | |
| | | VMP-5-31-042111 | 4/21/2011 | <95 | U | | <180 | U | | <220 | U | | <100 | U | | <170 | U | | 1600 | | | <160 | U | | <120 | U | | <120 | U | | <120 | U | | <100 | U | |
| | | VMP-5-31-080611 | 8/6/2011 | <53 | U | | <99 | U | | <120 | U | | <57 | U | | <96 | U | | 1400 | | | <89 | U | | <70 | U | | <70 | U | | <70 | U | | <57 | U | |
| | | VMP-5-31-111111 | 11/11/2011 | <27 | U | | <50 | U | | <62 | U | | <28 | U | | <48 | U | | 670 | | | <45 | U | | <35 | U | | <35 | U | | <35 | U | | <29 | U | |
| | | VMP-5-31-013012 | 1/30/2012 | <14 | U | | <25 | U | | <32 | U | | <14 | U | | <25 | U | | 480 | | | <23 | U | | <18 | U | | <18 | U | | <18 | U | | <15 | U | |
| | | VMP-5-31-041112 | 4/11/2012 | <0.044 | U | | <0.081 | U | | <0.1 | U | | <0.047 | U | | <0.079 | U | | 0.46 | | | <0.073 | U | | <0.057 | U | | <0.057 | U | | <0.057 | U | | <0.047 | U | |
| | | VMP-5-31-071212 | 7/12/2012 | <0.0046 | J | U | <0.0086 | U | | <0.011 | U | | 0.023 | | | <0.021 | U | | 0.025 | | | <0.0077 | U | | <0.006 | U | | <0.006 | U | | <0.006 | U | | 0.0017 | J | |
| | | VMP-5-31-101112 | 10/11/2012 | <0.0065 | U | | <0.012 | U | | <0.015 | U | | 0.01 | | | <0.029 | U | | 0.0041 | J | | <0.011 | U | | <0.0085 | U | | <0.0085 | U | | <0.0085 | U | | 0.0023 | J | |
| | | VMP-5-31-012413 | 1/24/2013 | <0.064 | U | | <0.12 | U | | <0.15 | U | | 0.024 | J | | <0.29 | U | | 0.015 | J | | <0.11 | U | | <0.084 | U | | <0.084 | U | | <0.084 | U | | <0.069 | U | |
| | 40 ft | VMP-5-40-042111 | 4/21/2011 | <99 | U | | <180 | U | | <230 | U | | <100 | U | | <180 | U | | 1400 | | | <160 | U | | <130 | U | | <130 | U | | <130 | U | | <110 | U | |
| | | VMP-5-40-013012 | 1/30/2012 | <29 | U | | <53 | U | | <66 | U | | <30 | U | | <52 | U | | 410 | | | <48 | U | | <38 | U | | <38 | U | | <38 | U | | <31 | U | |
| | | VMP-5-40-041212 | 4/12/2012 | <0.043 | U | | <0.08 | U | | <0.099 | U | | <0.046 | U | | <0.077 | U | | 1.7 | | | <0.072 | U | | <0.056 | U | | <0.056 | U | | <0.056 | U | | <0.046 | U | |
| | | VMP-5-40-071212 | 7/12/2012 | <0.046 | U | | <0.086 | U | | <0.11 | U | | 0.046 | J | | <0.21 | U | | 0.016 | J | | <0.077 | U | | <0.06 | U | | <0.06 | U | | <0.06 | U | | <0.05 | U | |
| | | VMP-5-40-101112 | 10/11/2012 | <0.0068 | U | | <0.013 | U | | <0.016 | U | | 0.025 | | | <0.03 | U | | 0.003 | J | | <0.011 | U | | <0.0089 | U | | <0.0089 | U | | <0.0089 | U | | 0.0021 | J | |
| | | VMP-5-40-012513 | 1/25/2013 | <0.02 | U | | <0.037 | U | | <0.045 | U | | 0.04 | | | <0.089 | U | | 0.018 | | | <0.033 | U | | <0.026 | U | | <0.026 | U | | <0.026 | U | | <0.021 | U | |
| | | VMP-5-40-012513-Dup | 1/25/2013 | <0.019 | U | | <0.036 | U | | <0.044 | U | | 0.043 | | | <0.087 | U | | 0.0059 | J | | <0.032 | U | | <0.025 | U | | <0.025 | U | | <0.025 | U | | <0.021 | U | |
| VMP-6 | 5 ft | VMP-6-5-090810 | 9/8/2010 | <1 | U | | <1.9 | U | | <0.58 | U | | <1.1 | U | | <1.8 | U | | 76 | | | <1.7 | U | | <1.3 | U | | <1.3 | U | | <1.3 | U | | <1.1 | U | |
| | | VMP-6-5-111610 | 11/16/2010 | <6.4 | U | | <12 | U | | <3.6 | U | | <6.7 | U | | <11 | U | | 600 | | | <11 | U | | <8.3 | U | | <8.3 | U | | <8.3 | U | | <6.8 | U | |
| | | VMP-6-5-020711 | 2/7/2011 | <0.0055 | U | | <0.01 | U | | <0.0031 | U | | <0.0058 | U | | <0.0098 | U | | 0.013 | | | <0.0091 | U | | <0.0072 | J | U | <0.0072 | J | U | <0.0072 | J | U | 0.0025 | J | |
| | | VMP-6-5-040811 | 4/8/2011 | <0.012 | U | | <0.022 | U | | <0.027 | U | | <0.013 | U | | <0.021 | U | | 0.099 | | | <0.016 | U | | <0.016 | J | U | <0.016 | J | U | <0.016 | J | U | 0.0029 | J | |
| | | VMP-6-5-080411 | 8/4/2011 | <0.31 | U | | <0.57 | U | | <0.71 | U | | <0.33 | U | | <0.55 | U | | 5.1 | | | <0.51 | U | | <0.4 | U | | <0.4 | U | | <0.4 | U | | <0.33 | U | |
| | | VMP-6-5-110911 | 11/9/2011 | <0.0037 | U | | <0.0068 | U | | <0.0085 | U | | <0.0039 | U | | <0.0066 | U | | 0.016 | | | <0.0062 | U | | <0.0048 | U | | <0.0048 | U | | <0.0048 | U | | 0.0019 | J | J |
| | | VMP-6-5-013112 | 1/31/2012 | 0.016 | J | | <0.081 | U | | <0.1 | U | | <0.046 | U | | <0.078 | U | | 0.42 | | | <0.073 | U | | <0.057 | U | | 0.0069 | J | | <0.057 | U | | <0.047 | U | |
| | | VMP-6-5-041212 | 4/12/2012 | <0.0046 | J | U | <0.0086 | U | | <0.011 | U | | <0.0049 | J | U | <0.021 | U | | 0.0041 | | | <0.0077 | U | | <0.006 | U | | <0.006 | J | U | <0.006 | J | U | 0.0024 | J | |
| | | VMP-6-5-071612 | 7/16/2012 | <0.0046 | J | U | <0.0086 | U | | <0.011 | U | | 0.00086 | J | | <0.021 | U | | 0.0015 | J | | <0.0077 | U | | <0.006 | U | | <0.006 | J | U | <0.006 | J | U | 0.0029 | J | |
| | | VMP-6-5-101012 | 10/10/2012 | <0.0064 | U | | <0.012 | U | | <0.014 | U | | <0.0067 | U | | <0.028 | U | | <0.0048 | U | | <0.011 | U | | <0.0083 | U | | <0.0083 | U | | <0.0083 | U | | 0.0022 | J | |
| | | VMP-6-5-021213 | 2/12/2013 | <0.0057 | U | | <0.01 | U | | <0.013 | U | | <0.006 | U | | <0.026 | U | | 0.0019 | J | | <0.0095 | U | | <0.0074 | U | | <0.0074 | U | | <0.0074 | U | | 0.0026 | J | |
| | 10 ft | VMP-6-10-090810 | 9/8/2010 | <1.1 | U | | <2 | U | | <0.63 | U | | <1.2 | U | | <2 | U | | 240 | | J | <1.8 | U | | <1.4 | U | | <1.4 | U | | <1.4 | U | | <1.2 | U | |
| | | VMP-6-10-111710 | 11/17/2010 | <0.0059 | U | | <0.011 | U | | <0.0034 | U | | <0.0063 | U | | <0.011 | U | | 0.0046 | | | <0.0099 | U | | <0.0078 | U | | <0.0078 | U | | <0.0078 | U | | 0.002 | J | |
| | | VMP-6-10-020711 | 2/7/2011 | <0.0058 | U | | <0.011 | U | | <0.0033 | U | | <0.0062 | U | | <0.01 | U | | 0.0029 | J | | <0.0097 | U | | <0.0076 | J | U | <0.0076 | J | U | <0.0076 | J | U | 0.0021 | J | |
| | | VMP-6-10-040811 | 4/8/2011 | <0.14 | U | | <0.26 | U | | <0.32 | U | | <0.15 | U | | <0.25 | U | | <0.1 | U | | <0.23 | U | | <0.18 | U | | <0.18 | U | | <0.18 | U | | <0.15 | U | |
| | | VMP-6-10-080411 | 8/4/2011 | <0.98 | U | | <1.8 | U | | <2.2 | U | | <1 | U | | <1.8 | U | | 220 | | | <1.6 | U | | <1.3 | U | | <1.3 | U | | <1.3 | U | | <1 | U | |
| | | VMP-6-10-111011 | 11/10/2011 | <0.0039 | U | | <0.0072 | U | | <0.0089 | U | | <0.0041 | U | | <0.0069 | U | | 0.0013 | J | | <0.0064 | U | | <0.005 | U | | <0.005 | U | | <0.005 | U | | 0.0014 | J | J |
| | | VMP-6-10-013112 | 1/31/2012 | <0.68 | U | | <1.3 | U | | <1.6 | U | | <0.73 | U | | <1.2 | U | | 52 | | J | <1.1 | U | | <0.9 | U | | <0.9 | U | | <0.9 | U | | <0.74 | U | |
| | | VMP-6-10-041212 | 4/12/2012 | 0.0029 | J | | <0.0083 | U | | <0.01 | U | | <0.0048 | U | | <0.02 | U | | 0.0037 | | | <0.0075 | U | | <0.0059 | U | | <0.0059 | J | U | <0.0059 | J | U | 0.0024 | J | |
| | | VMP-6-10-071612 | 7/16/2012 | <0.006 | | U | <0.011 | U | | <0.014 | U | | <0.0064 | J | U | <0.027 | U | | 0.0035 | J | | <0.01 | U | | <0.0079 | J | U | <0.0079 | J | U | <0.0079 | J | U | 0.0025 | J | |
| | | VMP-6-10-101112 | 10/11/2012 | <0.0066 | U | | <0.012 | U | | <0.015 | U | | <0.007 | U | | <0.03 | U | | 0.0025 | J | | <0.011 | U | | <0.0087 | U | | <0.0087 | U | | <0.0087 | U | | 0.0025 | J | |
| | | VMP-6-10-020513 | 2/5/2013 | <0.0064 | U | | <0.012 | U | | <0.014 | U | | <0.0067 | U | | <0.028 | U | | <0.0048 | U | | <0.011 | U | | <0.0083 | U | | <0.0083 | U | | <0.0083 | U | | 0.0023 | J | |
| | 31.5 ft | VMP-6-31.5-090810 | 9/8/2010 | <7.4 | U | | <14 | U | | <4.2 | U | | <7.9 | U | | <13 | U | | 1000 | | | <12 | U | | <9.7 | U | | <9.7 | U | | <9.7 | U | | <8 | U | |
| | | VMP-6-31.5-111710 | 11/17/2010 | <12 | U | | <21 | U | | <6.6 | U | | <12 | U | | <21 | U | | 1500 | | | <19 | U | | <15 | U | | <15 | U | | <15 | U | | <12 | U | |
| | | VMP-6-31.5-020711 | 2/7/2011 | <11 | U | | <21 | U | | <6.4 | U | | <12 | U | | <20 | U | | 1200 | | | <18 | U | | <14 | U | | <14 | U | | <14 | U | | <12 | U | |
| | | VMP-6-31.5-041111 | 4/11/2011 | <8.6 | U | | <16 | U | | <20 | U | | <9.2 | U | | <15 | U | | 580 | | | <14 | U | | <11 | U | | <11 | U | | 1.1 | J | | <9.3 | U | |
| | | VMP-6-31.5-080411 | 8/4/2011 | <6.4 | U | | <12 | U | | <15 | U | | <6.8 | U | | <11 | U | | 770 | | | <11 | U | | <8.4 | U | | <8.4 | U | | <8.4 | U | | <6.9 | U | |
| | | VMP-6-31.5-111011 | 11/10/2011 | <9.8 | U | | <18 | U | | <22 | U | | <10 | U | | <18 | U | | 530 | | | <16 | U | | <13 | U | | <13 | U | | <13 | U | | <10 | U | |
| | | VMP-6-31.5-013112 | 1/31/2012 | <3.9 | U | | <7.3 | U | | <9 | U | | <4.2 | U | | <7.1 | U | | 550 | | J | <6.6 | U | | <5.1 | U | | <5.1 | U | | <5.1 | U | | <4.2 | U | |
| | | VMP-6-31.5-041212 | 4/12/2012 | <0.53 | U | | <0.98 | U | | <1.2 | U | | <0.56 | U | | <0.94 | U | | 26 | | | <0.88 | U | | <0.69 | U | | <0.69 | U | | <0.69 | U | | <0.57 | U | |
| | | VMP-6-31.5-071612 | 7/16/2012 | <0.0083 | J | U | <0.015 | U | | <0.019 | U | | 0.0055 | J | | <0.037 | U | | 0.037 | | | <0.014 | U | | <0.011 | U | | <0.011 | J | U | <0.011 | J | U | 0.0022 | J | |
| | | VMP-6-31.5-101112 | 10/11/2012 | <0.0065 | U | | <0.012 | U | | <0.015 | U | | 0.0047 | J | | <0.029 | U | | 0.0018 | J | | <0.011 | U | | <0.0085 | U | | <0.0085 | U | | <0.0085 | U | | 0.0025 | J | |
| | | VMP-6-31.5-020513 | 2/5/2013 | <0.0059 | U | | <0.011 | U | | <0.014 | U | | 0.0043 | J | | <0.027 | U | | <0.0044 | U | | <0.0099 | U | | <0.0078 | U | | <0.0078 | U | | <0.0078 | U | | 0.0026 | J | |
| | 39 ft | VMP-6-39-041111 | 4/11/2011 | <10 | U | | <19 | U | | <24 | U | | <11 | U | | <18 | U | | 620 | | | <17 | U | | <13 | U | | <13 | U | | <13 | U | | <11 | U | |
| | | VMP-6-39-013112 | 1/31/2012 | <3.9 | U | | <7.3 | U | | <9 | U | | <4.2 | U | | <7.1 | U | | 690 | | J | <6.6 | U | | <5.1 | U | | <5.1 | U | | <5.1 | U | | <4.2 | U | |
| | | VMP-6-39-041212 | 4/12/2012 | <0.39 | U | | <0.72 | U | | <0.89 | U | | <0.41 | U | | <0.69 | U | | 64 | | | <0.64 | U | | <0.5 | U | | <0.5 | U | | <0.5 | U | | <0.42 | U | |
| | | VMP-6-39-071612 | 7/16/2012 | 0.016 | J | | <0.034 | U | | <0.042 | U | | <0.019 | U | | <0.081 | U | | 0.1 | | | <0.03 | U | | <0.024 | U | | 0.0079 | J | | <0.024 | U | | 0.0025 | J | |
| | | VMP-6-39-071612-Dup | 7/16/2012 | 0.013 | J | | <0.034 | U | | <0.042 | U | | <0.019 | U | | <0.082 | U | | 0.11 | | | <0.03 | U | | <0.024 | U | | <0.024 | U | | <0.024 | U | | 0.003 | J | |
| | | VMP-6-39-101112 | 10/11/2012 | <0.012 | U | | <0.023 | U | | <0.028 | U | | <0.013 | U | | <0.056 | U | | 0.0032 | J | | <0.021 | U | | <0.016 | U | | <0.016 | U | | <0.016 | U | | 0.0028 | J | |
| | | VMP-6-39-020513 | 2/5/2013 | <0.0061 | U | | <0.011 | U | | <0.014 | U | | <0.0064 | U | | <0.027 | U | | 0.01 | | | <0.01 | U | | <0.0079 | U | | <0.0079 | U | | <0.0079 | U | | 0.0023 | J | |

SEE LAST PAGE OF TABLE FOR NOTES

**TABLE 5**
**CUMULATIVE SUMMARY OF SOIL VAPOR ANALYTICAL DETECTIONS AND SCREENING RESULTS: VILLAGE - VOCS**

| Location | Depth | Sample ID | Sample Date | Chlorobenzene | | | Chlorodibromomethane | | | Chloroethane | | | Chloroform | | | Chloromethane | | | Cyclohexane | | | 1,2-Dibromoethane | | | 1,2-Dichlorobenzene | | | 1,3-Dichlorobenzene | | | 1,4-Dichlorobenzene | | | Dichlorodifluoromethane | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | 69 | | | 57000 | | | | | | 0.11 | | | | | | | | | 0.011 | | | 290 | | | | | | 1200 | | | | | |
| | | | | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals |
| VMP-7 | 5 ft | VMP-7-5-082610 | 8/26/2010 | <0.0061 | U | | <0.011 | U | | <0.0035 | U | | <0.0064 | U | | <0.011 | U | | 0.016 | | | <0.01 | U | | <0.0079 | U | | <0.0079 | U | | <0.0079 | U | | 0.003 | J | |
| | | VMP-7-5-111910 | 11/19/2010 | <0.0055 | U | | <0.01 | U | | <0.0031 | U | | <0.0058 | U | | <0.0098 | U | | 0.0054 | | | <0.0091 | U | | <0.0072 | U | | <0.0072 | U | | <0.0072 | U | | <0.0059 | U | |
| | | VMP-7-5-020711 | 2/7/2011 | <0.0059 | U | | <0.011 | U | | <0.0034 | U | | <0.0063 | U | | <0.011 | U | | 0.0018 | J | | <0.0099 | U | | <0.0078 | J | U | <0.0078 | U | | <0.0078 | J | U | 0.0025 | J | |
| | | VMP-7-5-040711 | 4/7/2011 | <0.0084 | U | | <0.016 | U | | <0.019 | U | | <0.0089 | U | | <0.015 | U | | 0.0081 | | | <0.014 | U | | <0.011 | U | | <0.011 | U | | <0.011 | U | | 0.0014 | J | |
| | | VMP-7-5-080211 | 8/2/2011 | <0.83 | U | | <1.5 | U | | <1.9 | U | | <0.88 | U | | <1.5 | U | | 45 | | | <1.4 | U | | <1.1 | U | | <1.1 | U | | <1.1 | U | | <0.89 | U | |
| | | VMP-7-5-111011 | 11/10/2011 | <0.0039 | U | | <0.0073 | U | | <0.009 | U | | <0.0042 | U | | <0.0071 | U | | <0.0029 | U | | <0.0066 | U | | <0.0051 | U | | <0.0051 | U | | <0.0051 | U | | 0.0011 | J | |
| | | VMP-7-5-111011-DUP | 11/10/2011 | <0.0037 | U | | <0.0068 | U | | <0.0085 | U | | <0.0039 | U | | <0.0066 | U | | <0.0028 | U | | <0.0062 | U | | <0.0048 | U | | <0.0048 | U | | <0.0048 | U | | 0.0014 | J | J |
| | | VMP-7-5-013112 | 1/31/2012 | <0.004 | J | U | <0.0074 | U | | <0.0092 | U | | <0.0043 | U | | <0.0072 | U | | <0.003 | U | | <0.0067 | U | | <0.0053 | U | | <0.0053 | J | U | <0.0053 | U | | 0.0022 | J | |
| | | VMP-7-5-041212 | 4/12/2012 | <0.0044 | J | U | <0.0081 | U | | <0.01 | U | | <0.0046 | U | | <0.02 | U | | <0.0033 | J | U | <0.0073 | U | | <0.0057 | U | | <0.0057 | J | U | <0.0057 | J | U | 0.0022 | J | |
| | | VMP-7-5-073112 | 7/31/2012 | 0.0037 | J | | <0.021 | U | | <0.026 | U | | <0.012 | U | | 0.0034 | J | | 0.016 | | | <0.019 | U | | <0.015 | U | | <0.015 | U | | <0.015 | U | | <0.012 | U | |
| | | VMP-7-5-101012 | 10/10/2012 | <0.0068 | U | | <0.013 | U | | <0.016 | U | | <0.0072 | U | | <0.03 | U | | <0.0051 | U | | <0.011 | U | | <0.0089 | U | | <0.0089 | U | | <0.0089 | U | | 0.0026 | J | |
| | 13.5 ft | VMP-7-13.5-082610 | 8/26/2010 | <0.13 | U | | <0.25 | U | | <0.076 | U | | <0.14 | U | | <0.24 | U | | <0.099 | U | | <0.22 | U | | <0.17 | U | | <0.17 | U | | <0.17 | U | | <0.14 | U | |
| | | VMP-7-13.5-111910 | 11/19/2010 | <0.93 | U | | <1.7 | U | | <0.53 | U | | <0.98 | U | | <1.7 | U | | 26 | | J | <1.5 | U | | <1.2 | U | | <1.2 | U | | <1.2 | U | | <1 | U | |
| | | VMP-7-13.5-020711 | 2/7/2011 | <0.0057 | U | | <0.01 | U | | <0.0032 | U | | <0.006 | U | | <0.01 | U | | 0.0013 | J | | <0.0095 | J | U | <0.0074 | J | U | <0.0074 | J | U | <0.0074 | J | U | 0.0019 | J | |
| | | VMP-7-13.5-040711 | 4/7/2011 | <0.0099 | U | | <0.018 | U | | <0.023 | U | | <0.01 | U | | <0.018 | U | | 0.0091 | | | <0.016 | U | | <0.013 | U | | <0.013 | U | | <0.013 | U | | <0.011 | U | |
| | | VMP-7-13.5-080311 | 8/3/2011 | <1.1 | U | | <2 | U | | <2.5 | U | | <1.2 | U | | <2 | U | | 9.4 | | | <1.8 | U | | <1.4 | U | | <1.4 | U | | <1.4 | U | | <1.2 | U | |
| | | VMP-7-13.5-111011 | 11/10/2011 | <0.0036 | U | | <0.0067 | U | | <0.0083 | U | | <0.0038 | U | | <0.0065 | U | | 0.013 | | | <0.0061 | U | | <0.0047 | U | | <0.0048 | U | | <0.0048 | U | | 0.0013 | J | J |
| | | VMP-7-13.5-013112 | 1/31/2012 | <0.052 | U | | <0.095 | U | | <0.12 | U | | <0.055 | U | | <0.092 | U | | 1.7 | | J | <0.086 | U | | <0.067 | U | | <0.067 | U | | <0.067 | U | | <0.055 | U | |
| | | VMP-7-13.5-013112-DUP | 1/31/2012 | <0.053 | U | | <0.098 | U | | <0.12 | U | | <0.056 | U | | <0.094 | U | | 1.6 | | J | <0.088 | U | | <0.069 | U | | <0.069 | U | | <0.069 | U | | <0.057 | U | |
| | | VMP-7-13.5-041212 | 4/12/2012 | <0.0042 | J | U | <0.0078 | U | | <0.0096 | U | | <0.0045 | J | U | <0.019 | U | | 0.013 | | | <0.007 | U | | <0.0055 | U | | <0.0055 | U | | <0.0055 | J | U | 0.0024 | J | |
| | | VMP-7-13.5-041212-DUP | 4/12/2012 | <0.0044 | J | U | <0.0082 | U | | <0.01 | U | | <0.0047 | J | U | <0.02 | U | | 0.0064 | | | <0.0074 | U | | <0.0058 | U | | <0.0058 | U | | <0.0058 | J | U | 0.0023 | J | |
| | | VMP-7-13.5-072012 | 7/20/2012 | <0.0043 | U | | <0.008 | U | | <0.0099 | U | | 0.0066 | | | <0.019 | U | | <0.0032 | U | | <0.0072 | U | | <0.0056 | U | | <0.0056 | U | | <0.0056 | U | | 0.0026 | J | |
| | | VMP-7-13.5-101012 | 10/10/2012 | <0.0064 | U | | <0.012 | U | | <0.014 | U | | <0.0067 | U | | <0.028 | U | | <0.0048 | U | | <0.011 | U | | <0.0083 | U | | <0.0083 | U | | <0.0083 | U | | 0.0026 | J | |
| | | VMP-7-13.5-021313 | 2/13/2013 | <0.0064 | U | | <0.012 | U | | <0.014 | U | | 0.002 | J | | <0.028 | U | | <0.0048 | U | | <0.011 | U | | <0.0083 | U | | <0.0083 | U | | <0.0083 | U | | 0.0026 | J | |
| | 29.5 ft | VMP-7-29.5-083110 | 8/31/2010 | <1.9 | U | | <3.5 | U | | <1.1 | U | | <2 | U | | <3.4 | U | | 540 | | J | <3.2 | U | | <2.5 | U | | <2.5 | U | | <2.5 | U | | <2 | U | |
| | | VMP-7-29.5-111910 | 11/19/2010 | <2.8 | U | | <5.3 | U | | <1.6 | U | | <3 | U | | <5.1 | U | | 410 | | J | <4.8 | U | | <3.7 | U | | <3.7 | U | | <3.7 | U | | <3.1 | U | |
| | | VMP-7-29.5-020711 | 2/7/2011 | <3 | U | | <5.5 | U | | <1.7 | U | | <3.1 | U | | <5.3 | U | | 440 | | | <5 | U | | <3.9 | U | | <3.9 | U | | <3.9 | U | | <3.2 | U | |
| | | VMP-7-29.5-040711 | 4/7/2011 | <0.72 | U | | <1.3 | U | | <1.6 | U | | <0.76 | U | | <1.3 | U | | 280 | | J | <1.2 | U | | <0.94 | U | | <0.94 | U | | <0.94 | U | | <0.77 | U | |
| | | VMP-7-29.5-080311 | 8/3/2011 | <1.7 | U | | <3.2 | U | | <3.9 | U | | <1.8 | U | | <3 | U | | 470 | | | <2.8 | U | | <2.2 | U | | <2.2 | U | | <2.2 | U | | <1.8 | U | |
| | | VMP-7-29.5-111111 | 11/11/2011 | 3.5 | | | <6.2 | U | | <7.6 | U | | <3.5 | U | | <6 | U | | 190 | | | <5.6 | U | | <4.4 | U | | <4.4 | U | | <4.4 | U | | <3.6 | U | |
| | | VMP-7-29.5-020112 | 2/1/2012 | <0.67 | U | | <1.2 | U | | 0.18 | J | J | <0.71 | U | | <1.2 | U | | 220 | | J | <1.1 | U | | <0.88 | U | | <0.88 | U | | <0.88 | U | | <0.72 | U | |
| | | VMP-7-29.5-041312 | 4/13/2012 | <0.0042 | J | U | <0.0078 | U | | <0.0096 | U | | <0.0045 | U | | <0.019 | U | | 0.085 | | | <0.007 | U | | <0.0055 | U | | <0.0055 | U | | <0.0055 | J | U | 0.0025 | J | |
| | | VMP-7-29.5-072012 | 7/20/2012 | <0.0043 | U | | <0.008 | U | | <0.0099 | U | | 0.0011 | J | | 0.0058 | J | | 0.003 | J | | <0.0072 | U | | <0.0056 | U | | <0.0056 | U | | <0.0056 | U | | 0.0024 | J | |
| | | VMP-7-29.5-072012-Dup | 7/20/2012 | 0.00099 | J | | <0.008 | U | | <0.0099 | U | | 0.001 | J | | 0.0067 | J | | 0.003 | J | | <0.0072 | U | | <0.0056 | U | | <0.0056 | U | | <0.0056 | U | | 0.0027 | J | |
| | | VMP-7-29.5-101012 | 10/10/2012 | <0.0066 | U | | <0.012 | U | | <0.015 | U | | <0.007 | U | | <0.03 | U | | <0.005 | U | | <0.011 | U | | <0.0087 | U | | <0.0087 | U | | <0.0087 | J | U | 0.0023 | J | |
| | 38 ft | VMP-7-38-020711 | 2/7/2011 | <4 | U | | <7.4 | U | | <2.3 | U | | <4.2 | U | | <7.1 | U | | 390 | | | <6.6 | U | | <5.2 | U | | <5.2 | U | | <5.2 | U | | <4.3 | U | |
| | | VMP-7-38-040711 | 4/7/2011 | <1 | U | | <1.9 | U | | <2.3 | U | | <1.1 | U | | <1.8 | U | | 350 | | J | <1.7 | U | | <1.3 | U | | <1.3 | U | | <1.3 | U | | <1.1 | U | |
| | | VMP-7-38-020112 | 2/1/2012 | <0.97 | U | | <1.8 | U | | <2.2 | U | | <1 | U | | <1.7 | U | | 260 | | J | <1.6 | U | | <1.3 | U | | <1.3 | U | | <1.3 | U | | <1 | U | |
| | | VMP-7-38-042512 | 4/25/2012 | <0.0049 | | U | <0.0078 | U | | <0.0096 | U | | <0.0045 | U | | <0.019 | U | | 0.012 | | | <0.007 | U | | <0.0055 | U | | <0.0055 | J | U | <0.0055 | J | U | 0.0025 | J | |
| | | VMP-7-38-042512-Dup | 4/25/2012 | <0.0045 | | U | <0.0078 | U | | <0.0096 | U | | <0.0045 | J | U | <0.019 | U | | 0.012 | | | <0.007 | U | | <0.0055 | U | | <0.0055 | J | U | <0.0055 | J | U | 0.0026 | J | |
| | | VMP-7-38-101112 | 10/11/2012 | <0.0062 | U | | <0.011 | U | | <0.014 | U | | <0.0066 | U | | <0.028 | U | | <0.0046 | U | | <0.01 | U | | <0.0081 | U | | <0.0081 | U | | <0.0081 | U | | 0.0027 | J | |
| VMP-8 | 5 ft | VMP-8-5-083010 | 8/30/2010 | 0.0032 | J | | <0.011 | U | | <0.0035 | U | | 0.0039 | J | | <0.011 | U | | <0.0046 | U | | 0.0015 | J | | 0.0034 | J | | 0.0038 | J | | 0.0046 | J | | 0.0026 | J | |
| | | VMP-8-5-111810 | 11/17/2010 | <0.0054 | U | | <0.0099 | U | | <0.0031 | U | | 0.001 | J | | <0.0096 | U | | <0.004 | U | | <0.009 | U | | <0.007 | U | | <0.007 | U | | <0.007 | U | | 0.0027 | J | |
| | | VMP-8-5-021011 | 2/10/2011 | <0.0057 | U | | <0.01 | U | | <0.0032 | U | | <0.006 | U | | <0.01 | U | | 0.0012 | J | | <0.0095 | U | | <0.0074 | U | | <0.0074 | U | | <0.0074 | U | | <0.0061 | U | |
| | | VMP-8-5-040711 | 4/7/2011 | <0.0064 | U | | 0.0023 | J | | <0.014 | U | | 0.00094 | J | | <0.011 | U | | 0.0014 | J | | <0.011 | U | | <0.0083 | J | U | <0.0083 | U | | <0.0083 | J | U | 0.0026 | J | |
| | | VMP-8-5-072711 | 7/27/2011 | <0.0068 | U | | <0.013 | U | | <0.016 | U | | <0.0072 | U | | <0.012 | U | | 0.0014 | J | | <0.011 | U | | <0.0089 | U | | 0.0013 | J | | 0.0023 | J | |
| | | VMP-8-5-110311 | 11/3/2011 | <0.0039 | U | | <0.0073 | U | | <0.009 | U | | <0.0042 | U | | <0.0071 | U | | <0.0029 | U | | <0.0066 | U | | <0.0051 | U | | <0.0051 | U | | <0.0051 | U | | 0.0024 | J | |
| | | VMP-8-5-012312 | 1/23/2012 | <0.0049 | J | U | <0.009 | U | | <0.011 | U | | <0.0052 | U | | <0.0088 | U | | <0.0036 | U | | <0.0081 | U | | <0.0064 | U | | <0.0064 | J | U | <0.0064 | U | | 0.0039 | J | |
| | | VMP-8-5-041012 | 4/10/2012 | <0.0044 | U | | <0.0081 | U | | <0.01 | U | | 0.0011 | J | | <0.02 | U | | 0.0044 | | | <0.0073 | U | | <0.0057 | U | | <0.0057 | U | | 0.0012 | J | | 0.0021 | J | |
| | | VMP-8-5-071312 | 7/13/2012 | <0.0047 | U | | <0.0088 | U | | <0.011 | U | | <0.005 | U | | <0.021 | U | | <0.0035 | U | | <0.0079 | U | | <0.0062 | U | | <0.0062 | U | | <0.0062 | U | | 0.0026 | J | |
| | | VMP-8-5-073112 | 7/31/2012 | <0.0047 | U | | <0.0088 | U | | <0.011 | U | | <0.005 | U | | <0.021 | U | | 0.0028 | J | | <0.0079 | U | | <0.0062 | U | | <0.0062 | U | | <0.0062 | U | | 0.0026 | J | |
| | | VMP-8-5-100412 | 10/4/2012 | <0.0064 | U | | <0.012 | U | | <0.014 | U | | <0.0067 | U | | <0.028 | U | | <0.0048 | U | | <0.011 | U | | <0.0083 | U | | <0.0083 | J | U | <0.0083 | J | U | 0.002 | J | |
| | | VMP-8-5-100412-Dup | 10/4/2012 | <0.0061 | U | | <0.011 | U | | <0.014 | U | | <0.0064 | U | | <0.027 | U | | <0.0045 | U | | <0.01 | U | | <0.0079 | U | | <0.0079 | U | | <0.0079 | J | U | 0.002 | J | |
| | | VMP-8-5-012413 | 1/24/2013 | <0.0062 | U | | <0.011 | U | | <0.014 | U | | <0.0066 | U | | <0.028 | U | | <0.0046 | U | | <0.01 | U | | <0.0081 | U | | <0.0081 | U | | <0.0081 | J | U | 0.0025 | J | |
| | 9.5 ft | VMP-8-9.5 | 11/10/2009 | <0.005 | U | | <0.009 | U | | <0.003 | U | | <0.005 | U | | <0.009 | U | | <0.003 | U | | <0.008 | U | | <0.006 | U | | <0.006 | U | | <0.006 | U | | <0.005 | U | |
| | | VMP-8-9.5-083010 | 8/30/2010 | 0.0027 | J | | <0.01 | U | | <0.0032 | U | | <0.0059 | U | | <0.01 | U | | <0.0042 | U | | <0.0093 | U | | <0.0073 | U | | 0.0025 | J | | 0.0029 | J | | 0.0024 | J | |
| | | VMP-8-9.5-083010-DUP | 8/30/2010 | 0.0028 | J | | <0.01 | U | | <0.0032 | U | | 0.00094 | J | | <0.01 | U | | <0.0042 | U | | <0.0095 | U | | <0.0074 | U | | 0.0021 | J | | 0.0026 | J | | 0.0024 | J | |
| | | VMP-8-9.5-111810 | 11/17/2010 | <0.0056 | U | | <0.01 | U | | <0.0032 | U | | <0.0059 | U | | <0.01 | U | | 0.0011 | J | | <0.0093 | U | | <0.0073 | U | | <0.0073 | U | | <0.0073 | U | | 0.0024 | J | |
| | | VMP-8-9.5-021011 | 2/10/2011 | <0.0058 | U | | <0.011 | U | | <0.0033 | U | | <0.0062 | U | | <0.01 | U | | <0.0043 | U | | <0.0097 | U | | <0.0076 | U | | <0.0076 | U | | <0.0076 | U | | 0.0019 | J | |
| | | VMP-8-9.5-040711 | 4/7/2011 | <0.0064 | U | | <0.012 | U | | <0.014 | U | | <0.0067 | U | | <0.011 | U | | 0.00079 | J | | <0.011 | U | | <0.0083 | U | | <0.0083 | U | | 0.00092 | J | | 0.0016 | J | |
| | | VMP-8-9.5-072711 | 7/27/2011 | <0.0049 | U | | <0.0091 | U | | <0.011 | U | | <0.0052 | U | | <0.0088 | U | | 0.0014 | J | | <0.0082 | U | | <0.0064 | U | | <0.0064 | U | | 0.0011 | J | | 0.0019 | J | |
| | | VMP-8-9.5-110311 | 11/3/2011 | <0.0039 | U | | <0.0072 | U | | <0.0089 | U | | <0.0041 | U | | <0.0069 | U | | <0.0029 | U | | <0.0064 | U | | <0.005 | U | | <0.005 | U | | <0.005 | U | | 0.0019 | J | |
| | | VMP-8-9.5-012312 | 1/23/2012 | <0.0047 | J | U | <0.0086 | U | | <0.011 | U | | <0.005 | U | | <0.0084 | U | | 0.0026 | J | | <0.0078 | U | | <0.0061 | U | | <0.0061 | U | | <0.0061 | U | | 0.004 | J | |
| | | VMP-8-9.5-041012 | 4/10/2012 | <0.0044 | U | | <0.0081 | U | | <0.01 | U | | <0.0047 | U | | <0.02 | U | | 0.0056 | | | <0.0073 | U | | <0.0057 | U | | 0.002 | J | | 0.0012 | J | | 0.0024 | J | |
| | | VMP-8-9.5-071312 | 7/13/2012 | <0.0043 | U | | <0.008 | U | | <0.0099 | U | | <0.0046 | U | | <0.019 | U | | <0.0032 | U | | <0.0072 | U | | <0.0056 | U | | <0.0056 | U | | <0.0056 | U | | 0.0024 | J | |
| | | VMP-8-9.5-071312-Dup | 7/13/2012 | <0.0041 | U | | <0.0076 | U | | <0.0094 | U | | <0.0044 | U | | <0.018 | U | | <0.0031 | U | | <0.0069 | U | | <0.0054 | U | | <0.0054 | U | | <0.0054 | U | | 0.0021 | J | |
| | | VMP-8-9.5-100412 | 10/4/2012 | <0.007 | U | | <0.013 | U | | <0.016 | U | | <0.0074 | U | | <0.031 | U | | 0.0039 | J | | <0.012 | U | | <0.0091 | U | | <0.0091 | U | | <0.0091 | J | U | 0.0022 | J | |
| | | VMP-8-9.5-012413 | 1/24/2013 | <0.0058 | U | | <0.011 | U | | <0.013 | U | | <0.0062 | U | | <0.026 | U | | 0.0015 | J | | <0.0097 | U | | <0.0076 | U | | <0.0076 | U | | <0.0076 | J | U | 0.0027 | J | |
| | | VMP-8-9.5-012413-Dup | 1/24/2013 | <0.0062 | U | | <0.011 | U | | <0.014 | U | | <0.0066 | U | | <0.028 | U | | 0.0012 | J | | <0.01 | U | | <0.0081 | U | | <0.0081 | U | | <0.0081 | U | | 0.0029 | J | |
| | 23.5 ft | VMP-8-23.5-083010 | 8/30/2010 | 0.003 | J | | <0.011 | U | | <0.0035 | U | | <0.0064 | U | | <0.011 | U | | 0.002 | J | | <0.01 | U | | <0.0079 | U | | 0.0021 | J | | 0.0026 | J | | 0.0028 | J | |
| | | VMP-8-23.5-111910 | 11/19/2010 | <0.0058 | U | | <0.011 | U | | <0.0033 | U | | <0.0062 | U | | <0.01 | U | | 0.0018 | J | | <0.0097 | U | | <0.0076 | U | | <0.0076 | U | | <0.0076 | U | | <0.0062 | U | |
| | | VMP-8-23.5-021011 | 2/10/2011 | <0.0062 | U | | <0.011 | U | | <0.0035 | U | | <0.0066 | U | | <0.011 | U | | <0.0046 | U | | <0.01 | U | | <0.0081 | U | | <0.0081 | U | | <0.0081 | U | | 0.0022 | J | |
| | | VMP-8-23.5-040711 | 4/7/2011 | <0.0058 | U | | 0.0021 | J | | <0.013 | U | | <0.0062 | U | | <0.01 | U | | 0.001 | J | | <0.0097 | U | | <0.0076 | U | | <0.0076 | U | | <0.0076 | U | | 0.0023 | J | |
| | | VMP-8-23.5-040711-DUP | 4/7/2011 | <0.0092 | U | | 0.0033 | J | | <0.021 | U | | <0.0098 | U | | <0.016 | U | | 0.0027 | J | | <0.015 | U | | <0.012 | U | | 0.0016 | J | | 0.0017 | J | | 0.0017 | J | |
| | | VMP-8-23.5-081011 | 8/10/2011 | <0.0061 | J | U | <0.011 | U | | <0.014 | U | | <0.0064 | U | | <0.011 | U | | 0.012 | | | <0.01 | U | | <0.0079 | J | U | <0.0079 | J | U | <0.0079 | J | U | 0.0027 | J | |
| | | VMP-8-23.5-110611 | 11/6/2011 | <0.0044 | J | U | <0.0081 | U | | <0.01 | U | | <0.0047 | U | | <0.0079 | U | | <0.0033 | U | | <0.0073 | U | | <0.0057 | U | | <0.0057 | U | | 0.003 | J | | 0.003 | J | |
| | | VMP-8-23.5-012312 | 1/23/2012 | <0.0049 | J | U | <0.009 | U | | <0.011 | U | | 0.001 | J | | <0.0088 | U | | 0.0017 | J | | <0.0081 | U | | <0.0064 | U | | <0.0064 | J | U | <0.0064 | U | | 0.0033 | J | |
| | | VMP-8-23.5-041012 | 4/10/2012 | <0.0043 | U | | <0.008 | U | | <0.0099 | U | | <0.0046 | U | | <0.019 | U | | 0.0048 | | | <0.0072 | U | | <0.0056 | U | | 0.0012 | J | | 0.001 | J | | 0.0019 | J | |
| | | VMP-8-23.5-071312 | 7/13/2012 | <0.0047 | U | | <0.0088 | U | | <0.011 | U | | <0.005 | U | | <0.021 | U | | <0.0035 | U | | <0.0079 | U | | <0.0062 | U | | <0.0062 | U | | <0.0062 | U | | 0.0026 | J | |
| | | VMP-8-23.5-100412 | 10/4/2012 | <0.0066 | U | | <0.012 | U | | <0.015 | U | | <0.007 | U | | <0.03 | U | | 0.0042 | J | | <0.011 | U | | <0.0087 | U | | 0.0017 | J | | 0.00075 | J | | 0.0026 | J | |
| | | VMP-8-23.5-012413 | 1/24/2013 | <0.0066 | U | | <0.012 | U | | <0.015 | U | | <0.007 | U | | <0.03 | U | | <0.005 | U | | <0.011 | U | | <0.0087 | U | | <0.0087 | U | | <0.0087 | U | | 0.0032 | J | |

SEE LAST PAGE OF TABLE FOR NOTES

**TABLE 5**
**CUMULATIVE SUMMARY OF SOIL VAPOR ANALYTICAL DETECTIONS AND SCREENING RESULTS: VILLAGE - VOCS**

| Location | Depth | Sample ID | Sample Date | Chlorobenzene | | | Chlorodibromomethane | | | Chloroethane | | | Chloroform | | | Chloromethane | | | Cyclohexane | | | 1,2-Dibromoethane | | | 1,2-Dichlorobenzene | | | 1,3-Dichlorobenzene | | | 1,4-Dichlorobenzene | | | Dichlorodifluoromethane | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | 69 | | | 57000 | | | | | | 0.11 | | | | | | | | | 0.011 | | | 290 | | | | | | 1200 | | | | | |
| | | | | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals |
| VMP-9 | 5 ft | VMP-9-5-082610 | 8/26/2010 | <0.0052 | U | | <0.0097 | U | | <0.003 | U | | <0.0056 | U | | <0.0094 | U | | 0.011 | | | <0.0088 | U | | <0.0068 | U | | <0.0068 | U | | <0.0068 | U | | 0.003 | J | |
| | | VMP-9-5-111910 | 11/19/2010 | <0.0055 | U | | <0.01 | U | | <0.0031 | U | | <0.0058 | U | | <0.0098 | U | | <0.0041 | U | | <0.0091 | U | | <0.0072 | U | | <0.0072 | U | | <0.0072 | U | | <0.0059 | U | |
| | | VMP-9-5-020811 | 2/8/2011 | <0.0051 | U | | <0.0094 | U | | <0.0029 | U | | <0.0054 | U | | <0.0091 | U | | 0.00097 | J | | <0.0084 | U | | <0.0066 | J | U | <0.0066 | U | | <0.0066 | J | U | 0.0028 | J | |
| | | VMP-9-5-040611 | 4/6/2011 | <0.014 | U | | <0.026 | U | | <0.032 | U | | <0.015 | U | | <0.025 | U | | <0.01 | U | | <0.023 | U | | <0.018 | J | U | <0.018 | J | U | <0.018 | J | U | 0.0025 | J | |
| | | VMP-9-5-080211 | 8/2/2011 | <0.27 | U | | <0.5 | U | | <0.62 | U | | <0.29 | U | | <0.49 | U | | 0.14 | J | | <0.45 | U | | <0.35 | U | | <0.35 | U | | <0.35 | U | | <0.29 | U | |
| | | VMP-9-5-110411 | 11/4/2011 | <0.004 | U | | <0.0074 | U | | <0.0092 | U | | <0.0043 | U | | 0.0016 | J | | <0.003 | U | | <0.0067 | J | U | <0.0053 | J | U | <0.0053 | J | U | <0.0053 | J | U | 0.0021 | J | |
| | | VMP-9-5-012612 | 1/26/2012 | <0.0034 | J | U | <0.0063 | U | | <0.0079 | U | | <0.0036 | U | | <0.0062 | U | | 0.01 | | | <0.0057 | U | | <0.0045 | U | | <0.0045 | J | U | <0.0045 | J | U | 0.0038 | | |
| | | VMP-9-5-041112 | 4/11/2012 | <0.0041 | U | | <0.0076 | U | | <0.0094 | U | | <0.0044 | U | | <0.018 | U | | 0.0084 | | | <0.0069 | U | | <0.0054 | U | | <0.0054 | U | | <0.0054 | U | | 0.002 | J | |
| | | VMP-9-5-071312 | 7/13/2012 | <0.0044 | U | | <0.0081 | U | | <0.01 | U | | <0.0047 | U | | <0.02 | U | | <0.0033 | U | | <0.0073 | U | | <0.0057 | U | | <0.0057 | U | | <0.0057 | U | | 0.0021 | J | |
| | | VMP-9-5-101012 | 10/10/2012 | <0.0066 | U | | <0.012 | U | | <0.015 | U | | <0.007 | U | | <0.03 | U | | <0.005 | U | | <0.011 | U | | <0.0087 | U | | <0.0087 | U | | <0.0087 | U | | 0.0025 | J | |
| | | [4]VMP-9-5-012513 | 1/25/2013 | <0.0065 | U | UJ | <0.012 | U | UJ | <0.015 | U | UJ | <0.0069 | U | UJ | <0.029 | U | UJ | <0.0048 | U | UJ | <0.011 | U | UJ | <0.0085 | U | UJ | <0.0085 | U | UJ | <0.0085 | U | UJ | 0.0028 | J | J |
| | | VMP-9-5-021513 | 2/15/2013 | <0.0064 | U | | <0.012 | U | | <0.014 | U | | <0.0067 | U | | <0.028 | U | | 0.003 | J | | <0.011 | U | | <0.0083 | U | | <0.0083 | U | | <0.0083 | J | U | 0.0023 | J | |
| | 11.5 ft | VMP-9-11.5-082610 | 8/26/2010 | <0.12 | U | | <0.22 | U | | <0.068 | U | | <0.12 | U | | <0.21 | U | | 1.2 | | | <0.2 | U | | <0.15 | U | | <0.15 | U | | <0.15 | U | | <0.13 | U | |
| | | VMP-9-11.5-111910 | 11/19/2010 | <0.34 | U | | <0.63 | U | | <0.2 | U | | <0.36 | U | | <0.62 | U | | <0.26 | U | | <0.57 | U | | <0.45 | U | | <0.45 | U | | <0.45 | U | | <0.37 | U | |
| | | VMP-9-11.5-020911 | 2/9/2011 | <0.0062 | U | | <0.011 | U | | <0.0035 | U | | <0.0066 | U | | <0.011 | U | | <0.0046 | U | | <0.01 | U | | <0.0081 | U | | <0.0081 | U | | <0.0081 | U | | <0.0066 | U | |
| | | VMP-9-11.5-020911-DUP | 2/9/2011 | <0.0048 | U | | <0.0089 | U | | <0.0028 | U | | <0.0051 | U | | <0.0086 | U | | 0.0021 | J | | <0.008 | U | | <0.0063 | U | | <0.0063 | U | | <0.0063 | U | | 0.0013 | J | |
| | | VMP-9-11.5-040611 | 4/6/2011 | <0.018 | U | | <0.034 | U | | <0.042 | U | | <0.019 | U | | <0.032 | U | | 0.0033 | J | | <0.03 | U | | <0.024 | J | U | <0.024 | U | | <0.024 | J | U | <0.02 | U | |
| | | VMP-9-11.5-080211 | 8/2/2011 | <0.4 | U | | <0.75 | U | | <0.93 | U | | <0.43 | U | | <0.73 | U | | 2.5 | | | <0.68 | U | | <0.53 | U | | <0.53 | U | | <0.53 | U | | <0.44 | U | |
| | | VMP-9-11.5-110411 | 11/4/2011 | <0.004 | U | | <0.0074 | U | | <0.0092 | U | | <0.0043 | U | | <0.0072 | U | | 0.0018 | J | | <0.0067 | U | | <0.0053 | U | | <0.0053 | U | | <0.0053 | J | U | 0.0025 | J | |
| | | VMP-9-11.5-012612 | 1/26/2012 | 0.0019 | J | | <0.0066 | U | | <0.0082 | U | | <0.0038 | U | | <0.0064 | U | | 0.00079 | J | | <0.006 | J | U | <0.0046 | J | U | <0.0046 | J | U | <0.0046 | J | U | 0.0033 | J | |
| | | VMP-9-11.5-041112 | 4/11/2012 | <0.0042 | U | | <0.0078 | U | | <0.0096 | U | | 0.0025 | J | | <0.019 | U | | 0.0072 | | | <0.007 | U | | <0.0055 | U | | <0.0055 | U | | <0.0055 | U | | 0.0021 | J | |
| | | VMP-9-11.5-071312 | 7/13/2012 | <0.0047 | U | | <0.0088 | U | | <0.011 | U | | 0.009 | | | <0.021 | U | | 0.00079 | J | | <0.0079 | U | | <0.0062 | U | | <0.0062 | U | | <0.0062 | U | | 0.0021 | J | |
| | | VMP-9-11.5-101012 | 10/10/2012 | <0.0064 | U | | <0.012 | U | | <0.014 | U | | 0.0048 | J | | <0.028 | U | | 0.0021 | J | | <0.011 | U | | <0.0083 | U | | <0.0083 | U | | <0.0083 | U | | 0.0028 | J | |
| | | VMP-9-11.5-012513 | 1/25/2013 | <0.0054 | U | | <0.0099 | U | | <0.012 | U | | 0.0079 | | | <0.024 | U | | 0.0077 | | | <0.009 | U | | <0.007 | U | | <0.007 | J | U | <0.007 | J | U | 0.0025 | J | |
| | | VMP-9-11.5-012513-DUP | 1/25/2013 | <0.0058 | U | | <0.011 | U | | <0.013 | U | | 0.0075 | | | <0.026 | U | | 0.01 | | | <0.0097 | U | | <0.0076 | U | | <0.0076 | J | U | <0.0076 | J | U | 0.003 | J | |
| | 25.5 ft | VMP-9-25.5-082610 | 8/26/2010 | <0.93 | U | | <1.7 | U | | <0.53 | U | | <0.98 | U | | <1.7 | U | | 31 | | | <1.5 | U | | <1.2 | U | | <1.2 | U | | <1.2 | U | | <1 | U | |
| | | VMP-9-25.5-082610-DUP | 8/26/2010 | <0.99 | U | | <1.8 | U | | <0.57 | U | | <1 | U | | <1.8 | U | | 32 | | | <1.6 | U | | <1.3 | U | | <1.3 | U | | <1.3 | U | | <1.1 | U | |
| | | VMP-9-25.5-111910 | 11/19/2010 | <1 | U | | <2 | U | | <0.61 | U | | <1.1 | U | | <1.9 | U | | 20 | | | <1.8 | U | | <1.4 | U | | <1.4 | U | | <1.4 | U | | <1.1 | U | |
| | | VMP-9-25.5-020911 | 2/9/2011 | <0.58 | U | | <1.1 | U | | <0.33 | U | | <0.62 | U | | <1 | U | | 3 | | | <0.97 | U | | <0.76 | U | | <0.76 | U | | <0.76 | U | | <0.62 | U | |
| | | VMP-9-25.5-040811 | 4/8/2011 | <0.29 | U | | <0.54 | U | | 0.26 | J | | <0.31 | U | | <0.53 | U | | 0.88 | | | <0.49 | U | | <0.38 | U | | <0.38 | U | | <0.38 | U | | <0.32 | U | |
| | | VMP-9-25.5-080211 | 8/2/2011 | <0.65 | U | | <1.2 | U | | <1.5 | U | | <0.69 | U | | <1.2 | U | | 32 | | J | <1.1 | U | | <0.85 | U | | <0.85 | U | | <0.85 | U | | <0.7 | U | |
| | | VMP-9-25.5-110711 | 11/7/2011 | 0.35 | J | | <1.1 | U | | <1.3 | U | | <0.61 | U | | <1 | U | | 1.8 | | | <0.96 | U | | <0.75 | U | | 0.079 | J | | <0.75 | U | | <0.62 | U | |
| | | VMP-9-25.5-110711-DUP | 11/7/2011 | 0.31 | J | | <0.92 | U | | <1.1 | U | | <0.52 | U | | <0.89 | U | | 1.7 | | | <0.83 | U | | <0.65 | U | | 0.069 | J | | <0.65 | U | | <0.53 | U | |
| | | VMP-9-25.5-012612 | 1/26/2012 | <0.15 | U | | <0.27 | U | | <0.34 | U | | <0.16 | U | | <0.26 | U | | 4.3 | | J | <0.25 | U | | <0.19 | U | | <0.19 | U | | <0.19 | U | | <0.16 | U | |
| | | VMP-9-25.5-041112 | 4/11/2012 | <0.0042 | U | | <0.0078 | U | | <0.0096 | U | | 0.0009 | J | | <0.019 | U | | 0.0055 | | | <0.007 | U | | <0.0055 | U | | 0.00089 | J | | <0.0055 | U | | 0.002 | J | |
| | | VMP-9-25.5-071312 | 7/13/2012 | <0.0045 | J | U | <0.0084 | U | | <0.01 | U | | 0.0068 | | | <0.02 | U | | <0.0034 | J | U | <0.0076 | U | | <0.0059 | J | U | <0.0059 | J | U | <0.0059 | J | U | 0.0029 | J | |
| | | VMP-9-25.5-071312-Dup | 7/13/2012 | <0.0044 | J | U | <0.0081 | U | | <0.01 | U | | 0.0058 | | | <0.02 | U | | <0.0033 | J | U | <0.0073 | U | | <0.0057 | J | U | <0.0057 | J | U | <0.0057 | J | U | 0.0027 | J | |
| | | VMP-9-25.5-101012 | 10/10/2012 | <0.0061 | U | | <0.011 | U | | <0.014 | U | | 0.015 | | | <0.027 | U | | <0.0045 | U | | <0.01 | U | | <0.0079 | U | | <0.0079 | U | | <0.0079 | U | | 0.0027 | J | |
| | | VMP-9-25.5-013013 | 1/30/2013 | <0.0065 | U | | <0.012 | U | | <0.015 | U | | 0.0095 | | | <0.029 | U | | <0.0048 | U | | <0.011 | U | | <0.0085 | U | | <0.0085 | U | | <0.0085 | U | | 0.0025 | J | |
| | 38.5 ft | VMP-9-38.5-020911 | 2/9/2011 | <0.96 | U | | <1.8 | U | | <0.55 | U | | <1 | U | | <1.7 | U | | 18 | | | <1.6 | U | | <1.2 | U | | <1.2 | U | | <1.2 | U | | <1 | U | |
| | | VMP-9-38.5-040811 | 4/8/2011 | <1.3 | U | | <2.4 | U | | 0.73 | J | | <1.4 | U | | <2.3 | U | | 23 | | | <2.1 | U | | <1.7 | U | | <1.7 | U | | <1.7 | U | | <1.4 | U | |
| | | VMP-9-38.5-012612 | 1/26/2012 | <0.19 | U | | <0.36 | U | | <0.44 | U | | <0.2 | U | | <0.35 | U | | 9.8 | | J | <0.32 | U | | <0.25 | U | | <0.25 | U | | <0.25 | U | | <0.21 | U | |
| | | VMP-9-38.5-041112 | 4/11/2012 | <0.0037 | U | | <0.0068 | U | | <0.0085 | U | | 0.0015 | J | | <0.017 | U | | 0.0056 | | | <0.0062 | U | | <0.0048 | U | | <0.0048 | U | | <0.0048 | U | | 0.002 | J | |
| | | VMP-9-38.5-071312 | 7/13/2012 | <0.0049 | J | U | <0.009 | U | | <0.011 | U | | 0.0073 | | | <0.022 | U | | <0.0036 | J | U | <0.0081 | U | | <0.0064 | U | | <0.0064 | J | U | <0.0064 | J | U | 0.0025 | J | |
| | | VMP-9-38.5-101012 | 10/10/2012 | <0.018 | U | | <0.034 | U | | <0.042 | U | | <0.019 | U | | <0.081 | U | | 0.02 | | | <0.03 | U | | <0.024 | U | | <0.024 | U | | <0.024 | U | | <0.019 | U | |
| | | VMP-9-38.5-013013 | 1/30/2013 | <0.0065 | U | | <0.012 | U | | <0.015 | U | | 0.0059 | J | | <0.029 | U | | <0.0048 | U | | <0.011 | U | | <0.0085 | U | | <0.0085 | U | | <0.0085 | U | | 0.0028 | J | |
| VMP-18 | 8.5 ft | VMP-18-8.5 | 6/18/2010 | <0.006 | U | | <0.012 | U | | <0.003 | U | | <0.007 | U | | <0.012 | U | | <0.005 | U | | <0.011 | U | | <0.008 | U | | <0.008 | U | | <0.008 | U | | 0.0025 | J | |
| | | VMP-18-8.5-090710 | 9/7/2010 | <0.0059 | U | | <0.011 | U | | <0.0034 | U | | 0.00097 | J | | <0.011 | U | | 0.0063 | | | <0.0099 | U | | <0.0078 | J | U | <0.0078 | J | U | <0.0078 | J | U | 0.0028 | J | |
| | | VMP-18-8.5-111910 | 11/19/2010 | <0.005 | U | | <0.0092 | U | | <0.0028 | U | | <0.0053 | U | | <0.0089 | U | | 0.0041 | | | <0.0083 | U | | <0.0065 | U | | <0.0065 | U | | <0.0065 | U | | <0.0053 | U | |
| | | VMP-18-8.5-020711 | 2/7/2011 | <0.0055 | U | | <0.01 | U | | <0.0031 | U | | <0.0058 | U | | <0.0098 | U | | 0.022 | | J | <0.0091 | U | | <0.0072 | J | U | <0.0072 | J | U | <0.0072 | J | U | 0.0022 | J | |
| | | VMP-18-8.5-020711-DUP | 2/7/2011 | <0.0053 | U | | <0.0098 | U | | <0.003 | U | | <0.0056 | U | | <0.0094 | U | | 0.0092 | | J | <0.0088 | U | | <0.0069 | J | U | <0.0069 | J | U | <0.0069 | J | U | 0.0022 | J | |
| | | VMP-18-8.5-040711 | 4/7/2011 | <0.0059 | J | U | 0.0023 | J | | <0.014 | U | | <0.0063 | U | | <0.011 | U | | 0.0062 | | | <0.0099 | U | | <0.0077 | J | U | <0.0077 | J | U | <0.0077 | J | U | 0.0019 | J | |
| | | VMP-18-8.5-072811 | 7/28/2011 | <0.0064 | U | | <0.012 | U | | <0.014 | U | | <0.0067 | U | | <0.011 | U | | <0.0048 | U | | <0.011 | U | | <0.0083 | U | | <0.0083 | U | | <0.0083 | U | | 0.0027 | J | |
| | | VMP-18-8.5-110711 | 11/7/2011 | <0.0041 | U | | <0.0076 | U | | <0.0094 | U | | <0.0044 | U | | <0.0074 | U | | <0.0031 | U | | <0.0069 | U | | <0.0054 | U | | <0.0054 | U | | <0.0054 | U | | 0.0018 | J | |
| | | VMP-18-8.5-012312 | 1/23/2012 | <0.0045 | J | U | <0.0083 | U | | <0.01 | U | | <0.0047 | U | | <0.008 | U | | <0.0033 | U | | <0.0074 | U | | <0.0058 | U | | <0.0058 | U | | <0.0058 | U | | 0.0028 | J | |
| | | VMP-18-8.5-041012 | 4/10/2012 | <0.0046 | U | | <0.0086 | U | | <0.011 | U | | <0.0049 | U | | <0.021 | U | | 0.0099 | | | <0.0077 | U | | <0.006 | U | | <0.006 | U | | <0.006 | J | U | 0.002 | J | |
| | | VMP-18-8.5-071212 | 7/12/2012 | <0.0045 | U | | <0.0083 | U | | <0.01 | U | | <0.0048 | U | | <0.02 | U | | 0.0025 | J | | <0.0075 | U | | <0.0059 | U | | <0.0059 | U | | <0.0059 | U | | 0.0017 | J | |
| | | VMP-18-8.5-100912 | 10/9/2012 | <0.0061 | U | | <0.011 | U | | <0.014 | U | | <0.0064 | U | | <0.027 | U | | <0.0045 | U | | <0.01 | U | | <0.0079 | U | | <0.0079 | U | | <0.0079 | J | U | 0.0024 | J | |
| | | VMP-18-8.5-012313 | 1/23/2013 | <0.0066 | U | | <0.012 | U | | <0.015 | U | | <0.007 | U | | <0.03 | U | | <0.005 | U | | <0.011 | U | | <0.0087 | U | | <0.0087 | U | | <0.0087 | U | | 0.0027 | J | |
| VMP-19 | 5 ft | VMP-19-5 | 6/18/2010 | <0.006 | U | | <0.012 | U | | <0.003 | U | | 0.00085 | J | | <0.011 | U | | 0.0025 | J | | <0.01 | U | | <0.008 | U | | <0.008 | U | | <0.008 | U | | 0.0021 | J | |
| | | VMP-19-5-090110 | 9/1/2010 | <0.0059 | J | U | <0.011 | U | | <0.0034 | U | | 0.00094 | J | | <0.011 | U | | 0.049 | | | <0.0099 | U | | 0.0019 | J | | <0.0078 | J | U | <0.0078 | J | U | 0.0028 | J | |
| | | VMP-19-5-111510 | 11/15/2010 | <0.0064 | U | | <0.012 | U | | <0.0036 | U | | <0.0067 | U | | <0.011 | U | | 0.0012 | J | | <0.011 | U | | <0.0083 | U | | <0.0083 | U | | <0.0083 | U | | 0.0023 | J | |
| | | VMP-19-5-020411 | 2/4/2011 | <0.0056 | U | | <0.01 | U | | <0.0032 | U | | <0.0059 | U | | <0.01 | U | | 0.0065 | | | <0.0093 | J | U | <0.0073 | J | U | <0.0073 | J | U | <0.0073 | J | U | 0.0028 | J | |
| | | VMP-19-5-040711 | 4/7/2011 | 0.00072 | J | | <0.012 | U | | <0.014 | U | | <0.0066 | U | | <0.011 | U | | 0.0043 | J | | 0.0012 | J | | 0.00068 | J | | <0.0081 | U | | 0.00088 | J | | 0.0021 | J | |
| | | VMP-19-5-080911 | 8/9/2011 | <0.0068 | J | U | <0.013 | U | | <0.016 | U | | <0.0072 | U | | <0.012 | U | | 0.05 | | J | <0.011 | J | U | <0.0089 | J | U | <0.0089 | J | U | <0.0089 | J | U | 0.0027 | J | |
| | | VMP-19-5-080911-DUP | 8/9/2011 | <0.0065 | J | U | <0.012 | U | | <0.015 | U | | <0.0069 | U | | <0.012 | U | | 0.035 | | J | <0.011 | J | U | <0.0085 | J | U | <0.0085 | J | U | <0.0085 | J | U | 0.0026 | J | |
| | | VMP-19-5-110811 | 11/8/2011 | <0.0045 | U | | <0.0083 | U | | <0.01 | U | | <0.0048 | U | | <0.0081 | U | | <0.0034 | U | | <0.0075 | U | | <0.0059 | U | | <0.0059 | U | | <0.0059 | U | | 0.0019 | J | |
| | | VMP-19-5-012612 | 1/26/2012 | <0.0039 | U | | <0.0073 | U | | <0.009 | U | | <0.0042 | U | | <0.0071 | U | | <0.0029 | U | | <0.0066 | U | | <0.0051 | U | | <0.0051 | U | | <0.0051 | U | | 0.0026 | J | |
| | | VMP-19-5-041012 | 4/10/2012 | <0.0045 | U | | <0.0083 | U | | <0.01 | U | | <0.0048 | U | | <0.02 | U | | 0.0046 | | | <0.0075 | U | | <0.0059 | U | | <0.0059 | U | | <0.0059 | J | U | 0.002 | J | |
| | | VMP-19-5-071112 | 7/11/2012 | <0.0051 | U | | <0.0095 | U | | <0.012 | U | | <0.0054 | U | | <0.023 | U | | <0.0038 | U | | <0.0086 | U | | <0.0067 | U | | <0.0067 | U | | <0.0067 | U | | <0.0055 | U | |
| | | VMP-19-5-100912 | 10/9/2012 | <0.0068 | U | | <0.013 | U | | <0.016 | U | | <0.0072 | U | | <0.03 | U | | <0.0051 | U | | <0.011 | U | | <0.0089 | U | | <0.0089 | U | | <0.0089 | J | U | 0.0028 | J | |
| | | VMP-19-5-013113 | 1/31/2013 | <0.0059 | U | | <0.011 | U | | <0.014 | U | | <0.0063 | U | | <0.027 | U | | 0.012 | | | <0.0099 | U | | <0.0078 | U | | <0.0078 | U | | <0.0078 | U | | 0.0023 | J | |

SEE LAST PAGE OF TABLE FOR NOTES

**TABLE 5**
**CUMULATIVE SUMMARY OF SOIL VAPOR ANALYTICAL DETECTIONS AND SCREENING RESULTS: VILLAGE - VOCS**

| Location | Depth | Sample ID | Sample Date | Chlorobenzene | | | Chlorodibromomethane | | | Chloroethane | | | Chloroform | | | Chloromethane | | | Cyclohexane | | | 1,2-Dibromoethane | | | 1,2-Dichlorobenzene | | | 1,3-Dichlorobenzene | | | 1,4-Dichlorobenzene | | | Dichlorodifluoromethane | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | 69 | | | 57000 | | | | | | 0.11 | | | | | | | | | 0.011 | | | 290 | | | | | | 1200 | | | | | |
| | | | | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals |
| VMP-20 | 5 ft | VMP-20-5-031411 | 3/14/2011 | 0.038 | | | <0.01 | U | | <0.013 | U | | 0.031 | | | <0.01 | U | | 0.052 | | | <0.0093 | U | | <0.0073 | U | | <0.0073 | U | | <0.0073 | U | | 0.003 | J | |
| | | VMP-20-5-041511 | 4/15/2011 | <0.061 | U | | <0.11 | U | | <0.14 | U | | <0.065 | U | | <0.11 | U | | 1.2 | | | <0.1 | U | | <0.08 | U | | <0.08 | U | | <0.08 | U | | <0.066 | U | |
| | | VMP-20-5-072511 | 7/25/2011 | <0.0065 | U | | <0.012 | U | | <0.015 | U | | 0.0012 | J | | 0.0036 | J | | <0.0048 | U | | <0.011 | J | U | <0.0085 | U | | 0.0013 | J | | <0.0085 | J | U | 0.0022 | J | |
| | | VMP-20-5-110111 | 11/1/2011 | <0.0037 | U | | <0.0068 | U | | <0.0085 | U | | <0.0039 | U | | 0.014 | | | 0.0011 | J | | <0.0062 | U | | <0.0048 | U | | <0.0048 | U | | <0.0048 | U | | 0.002 | J | |
| | | VMP-20-5-012312 | 1/23/2012 | <0.018 | J | U | <0.033 | U | | <0.041 | U | | <0.019 | U | | <0.032 | U | | 0.48 | | | <0.03 | U | | <0.023 | U | | <0.023 | U | | <0.023 | U | | <0.019 | U | |
| | | VMP-20-5-041012 | 4/10/2012 | <0.004 | U | | <0.0074 | U | | <0.0092 | U | | <0.0043 | U | | 0.007 | J | | 0.0093 | | | <0.0067 | U | | <0.0053 | U | | <0.0053 | U | | <0.0053 | U | | 0.0018 | J | |
| | | VMP-20-5-071112 | 7/11/2012 | <0.0054 | U | | <0.0099 | U | | <0.012 | U | | <0.0057 | U | | <0.024 | U | | <0.004 | U | | <0.009 | U | | <0.007 | U | | <0.007 | U | | <0.007 | U | | <0.0058 | U | |
| | | VMP-20-5-073112 | 7/31/2012 | <0.0045 | U | | <0.0083 | U | | <0.01 | U | | <0.0048 | U | | 0.0016 | J | | 0.0018 | J | | <0.0075 | U | | <0.0059 | U | | <0.0059 | U | | <0.0059 | U | | 0.0024 | J | |
| | | VMP-20-5-100412 | 10/4/2012 | <0.0066 | U | | <0.012 | U | | <0.015 | U | | <0.007 | U | | <0.03 | U | | <0.005 | U | | <0.011 | U | | <0.0087 | U | | <0.0087 | U | | <0.0087 | U | | 0.0023 | J | |
| | | VMP-20-5-020713 | 2/7/2013 | <0.0057 | U | | <0.01 | U | | <0.013 | U | | <0.006 | U | | <0.026 | U | | <0.0042 | U | | <0.0095 | U | | <0.0074 | U | | <0.0074 | U | | <0.0074 | U | | 0.0028 | J | |
| | 10 ft | VMP-20-10-031411 | 3/14/2011 | <0.0056 | U | | <0.01 | U | | <0.013 | U | | 0.0049 | J | | <0.01 | U | | 0.0041 | | | <0.0093 | U | | <0.0073 | U | | <0.0073 | U | | <0.0073 | U | | 0.0028 | J | |
| | | VMP-20-10-041511 | 4/15/2011 | <0.056 | U | | <0.1 | U | | <0.13 | U | | <0.059 | U | | <0.1 | U | | 0.27 | | | <0.093 | U | | <0.073 | U | | <0.073 | U | | <0.073 | U | | <0.06 | U | |
| | | VMP-20-10-072511 | 7/25/2011 | 0.00079 | J | | <0.011 | U | | <0.014 | U | | 0.0033 | J | | <0.011 | U | | <0.0044 | U | | <0.0099 | U | | 0.0014 | J | | 0.0019 | J | | 0.0018 | J | | 0.0025 | J | |
| | | VMP-20-10-110111 | 11/1/2011 | <0.0039 | U | | <0.0073 | U | | <0.009 | U | | <0.0042 | U | | <0.0071 | U | | <0.0029 | U | | <0.0066 | U | | <0.0051 | U | | <0.0051 | U | | <0.0051 | U | | 0.0025 | J | |
| | | VMP-20-10-012312 | 1/23/2012 | <0.0041 | J | U | <0.0076 | U | | <0.0094 | U | | <0.0044 | U | | <0.0074 | U | | 0.0046 | | | <0.0069 | U | | <0.0054 | U | | <0.0054 | J | U | <0.0054 | U | | 0.0033 | J | |
| | | VMP-20-10-041012 | 4/10/2012 | <0.0039 | U | | <0.0073 | U | | <0.009 | U | | <0.0042 | U | | 0.0051 | J | | 0.012 | | | <0.0066 | U | | <0.0051 | U | | <0.0051 | U | | <0.0051 | U | | 0.0022 | J | |
| | | VMP-20-10-071112 | 7/11/2012 | <0.0045 | U | | <0.0083 | U | | <0.01 | U | | <0.0048 | U | | 0.0031 | J | | <0.0034 | U | | <0.0075 | U | | <0.0059 | U | | <0.0059 | U | | <0.0059 | U | | 0.0019 | J | |
| | | VMP-20-10-100412 | 10/4/2012 | <0.0062 | U | | <0.011 | U | | <0.014 | U | | <0.0066 | U | | <0.028 | U | | <0.0046 | U | | <0.01 | U | | <0.0081 | U | | <0.0081 | J | U | <0.0081 | J | U | 0.0027 | J | |
| | | VMP-20-10-012213 | 1/22/2013 | <0.0057 | U | | <0.01 | U | | <0.013 | U | | <0.006 | U | | <0.026 | U | | <0.0042 | U | | <0.0095 | U | | <0.0074 | U | | <0.0074 | J | U | <0.0074 | J | U | 0.0026 | J | |
| | 25 ft | VMP-20-25-031411 | 3/14/2011 | <0.0055 | U | | <0.01 | U | | <0.013 | U | | <0.0058 | U | | <0.0099 | U | | 0.0019 | J | | <0.0092 | U | | <0.0072 | U | | <0.0072 | U | | <0.0072 | U | | 0.0032 | J | |
| | | VMP-20-25-041511 | 4/15/2011 | <0.064 | U | | <0.12 | U | | <0.14 | U | | <0.067 | U | | <0.11 | U | | 0.23 | | | <0.11 | U | | <0.083 | U | | <0.083 | U | | <0.083 | U | | <0.068 | U | |
| | | VMP-20-25-072611 | 7/26/2011 | <0.42 | U | | <0.78 | U | | <0.97 | U | | <0.45 | U | | <0.76 | U | | <0.32 | U | | <0.71 | U | | <0.55 | U | | <0.55 | U | | <0.55 | U | | <0.45 | U | |
| | | VMP-20-25-110511 | 11/5/2011 | <0.0039 | J | U | <0.0072 | U | | <0.0089 | U | | <0.0041 | U | | <0.0069 | U | | <0.0029 | U | | <0.0064 | U | | <0.005 | U | | <0.005 | U | | <0.005 | U | | 0.0026 | J | |
| | | VMP-20-25-012312 | 1/23/2012 | <0.0043 | J | U | <0.008 | U | | <0.0099 | U | | <0.0046 | U | | <0.0077 | U | | <0.0032 | U | | <0.0072 | U | | <0.0056 | U | | <0.0056 | U | | <0.0056 | U | | 0.0031 | J | |
| | | VMP-20-25-041012 | 4/10/2012 | <0.004 | U | | <0.0074 | U | | <0.0092 | U | | <0.0043 | U | | <0.018 | U | | 0.0021 | J | | <0.0067 | U | | <0.0053 | U | | <0.0053 | U | | <0.0053 | U | | 0.0021 | J | |
| | | VMP-20-25-041012-Dup | 4/10/2012 | <0.0041 | U | | <0.0076 | U | | <0.0094 | U | | <0.0044 | U | | <0.018 | U | | 0.0021 | J | | <0.0069 | U | | <0.0054 | U | | <0.0054 | U | | <0.0054 | U | | 0.0026 | J | |
| | | VMP-20-25-071112 | 7/11/2012 | <0.0046 | U | | <0.0086 | U | | <0.011 | U | | <0.0049 | U | | <0.021 | U | | 0.0011 | J | | <0.0077 | U | | <0.006 | U | | <0.006 | U | | <0.006 | U | | 0.0025 | J | |
| | | VMP-20-25-100412 | 10/4/2012 | <0.0068 | U | | <0.013 | U | | <0.016 | U | | <0.0072 | U | | <0.03 | U | | <0.0051 | U | | <0.011 | U | | <0.0089 | U | | <0.0089 | U | | <0.0089 | U | | 0.0025 | J | |
| | | VMP-20-25-012213 | 1/22/2013 | <0.0057 | U | | <0.01 | U | | <0.013 | U | | <0.006 | U | | <0.026 | U | | <0.0042 | U | | <0.0095 | U | | <0.0074 | U | | <0.0074 | J | U | <0.0074 | J | U | 0.0026 | J | |
| | 39.5 ft | VMP-20-39.5-100412 | 10/4/2012 | <1.7 | U | | <3.1 | U | | <3.8 | U | | <1.8 | U | | 1.5 | J | | <1.2 | U | | <2.8 | U | | <2.2 | U | | <2.2 | U | | 0.29 | J | | <1.8 | U | |
| | | VMP-20-39.5-012313 | 1/23/2013 | <0.95 | U | | <1.8 | U | | <2.2 | U | | <1 | U | | <1.7 | U | | <0.71 | U | | <1.6 | U | | <1.2 | U | | <1.2 | U | | <1.2 | U | | <1 | U | |
| VMP-21 | 5 ft | VMP-21-5-020911 | 2/9/2011 | <2.1 | U | | <4 | U | | <1.2 | U | | <2.3 | U | | <3.8 | U | | 94 | | | <3.6 | U | | <2.8 | U | | <2.8 | U | | <2.8 | U | | <2.3 | U | |
| | | VMP-21-5-020911-DUP | 2/9/2011 | <3.6 | U | | <6.8 | U | | <2.1 | U | | <3.9 | U | | <6.6 | U | | 77 | | | <6.1 | U | | <4.8 | U | | <4.8 | U | | <4.8 | U | | <3.9 | U | |
| | | VMP-21-5-041311 | 4/13/2011 | <0.0061 | J | U | <0.011 | U | | <0.014 | U | | <0.0064 | U | | <0.011 | U | | 0.4 | | | <0.01 | U | | <0.0079 | U | | <0.0079 | U | | <0.0079 | J | U | 0.0025 | J | |
| | | VMP-21-5-072511 | 7/25/2011 | <0.0064 | J | U | <0.012 | U | | <0.014 | U | | <0.0067 | U | | <0.011 | U | | <0.0048 | U | | <0.011 | U | | <0.0083 | U | | 0.0013 | J | | <0.0083 | J | U | 0.0023 | J | |
| | | VMP-21-5-110111 | 11/1/2011 | <0.0052 | U | | <0.0097 | U | | <0.012 | U | | <0.0056 | U | | <0.0094 | U | | 0.0095 | | | <0.0088 | U | | <0.0068 | U | | <0.0068 | U | | <0.0068 | U | | 0.0022 | J | |
| | | VMP-21-5-012312 | 1/23/2012 | <0.0045 | J | U | <0.0083 | U | | <0.01 | U | | <0.0047 | U | | <0.008 | U | | <0.0033 | U | | <0.0074 | U | | <0.0058 | U | | <0.0058 | J | U | <0.0058 | U | | 0.0035 | J | |
| | | VMP-21-5-012312-DUP | 1/23/2012 | <0.0041 | J | U | <0.0076 | U | | <0.0094 | U | | <0.0044 | U | | <0.0074 | U | | <0.0031 | U | | <0.0069 | U | | <0.0054 | U | | <0.0054 | J | U | <0.0054 | U | | 0.0031 | J | |
| | | VMP-21-5-042412 | 4/24/2012 | <0.0084 | J | U | <0.016 | U | | <0.019 | U | | <0.0089 | U | | <0.038 | U | | 0.041 | | | <0.014 | U | | <0.011 | U | | <0.011 | U | | <0.011 | J | U | 0.0028 | J | |
| | | VMP-21-5-071012 | 7/10/2012 | <0.0049 | J | U | <0.009 | U | | <0.011 | U | | <0.0052 | U | | <0.022 | U | | 0.028 | | | <0.0081 | U | | <0.0064 | U | | <0.0064 | U | | <0.0064 | U | | 0.0021 | J | |
| | | VMP-21-5-100412 | 10/4/2012 | <0.0072 | U | | <0.013 | U | | <0.016 | U | | <0.0076 | U | | <0.032 | U | | <0.0054 | U | | <0.012 | U | | <0.0093 | U | | <0.0093 | U | | <0.0093 | U | | 0.002 | J | |
| | | VMP-21-5-020613 | 2/6/2013 | <0.0065 | U | | <0.012 | U | | <0.015 | U | | <0.0069 | U | | <0.029 | U | | <0.0048 | U | | <0.011 | U | | <0.0085 | U | | <0.0085 | U | | <0.0085 | U | | 0.0029 | J | |
| | 10 ft | VMP-21-10-021011 | 2/10/2011 | <1.9 | U | | <3.6 | U | | <1.1 | U | | <2 | U | | <3.5 | U | | 72 | | | <3.2 | U | | <2.5 | U | | <2.5 | U | | <2.5 | U | | <2.1 | U | |
| | | VMP-21-10-041311 | 4/13/2011 | <0.24 | U | | <0.45 | U | | <0.56 | U | | <0.26 | U | | <0.44 | U | | 0.5 | | | <0.41 | U | | <0.32 | U | | <0.32 | U | | <0.32 | U | | <0.26 | U | |
| | | VMP-21-10-072511 | 7/25/2011 | <0.013 | J | U | <0.025 | U | | <0.031 | U | | <0.014 | U | | <0.024 | U | | <0.01 | U | | <0.022 | J | U | <0.018 | J | U | 0.0033 | J | | <0.018 | J | U | 0.0025 | J | |
| | | VMP-21-10-110111 | 11/1/2011 | <0.0039 | U | | <0.0073 | U | | <0.009 | U | | <0.0042 | U | | <0.0071 | U | | <0.0029 | U | | <0.0066 | U | | <0.0051 | U | | <0.0051 | U | | <0.0051 | U | | 0.0022 | J | |
| | | VMP-21-10-012312 | 1/23/2012 | <0.0045 | J | U | <0.0083 | U | | <0.01 | U | | <0.0047 | U | | <0.008 | U | | 0.00092 | J | | <0.0074 | U | | <0.0058 | U | | <0.0058 | U | | <0.0058 | U | | 0.0026 | J | |
| | | VMP-21-10-040912 | 4/9/2012 | <0.004 | U | | <0.0074 | U | | <0.0092 | U | | <0.0043 | U | | <0.018 | U | | 0.11 | | | <0.0067 | U | | <0.0053 | U | | <0.0053 | U | | <0.0053 | U | | 0.0023 | J | |
| | | VMP-21-10-071012 | 7/10/2012 | <0.0046 | U | | <0.0086 | U | | <0.011 | U | | <0.0049 | U | | <0.021 | U | | 0.00068 | J | | <0.0077 | U | | <0.006 | U | | <0.006 | U | | <0.006 | U | | <0.005 | U | |
| | | VMP-21-10-100412 | 10/4/2012 | <0.0065 | U | | <0.012 | U | | <0.015 | U | | <0.0069 | U | | <0.029 | U | | 0.0015 | J | | <0.011 | U | | <0.0085 | U | | <0.0085 | U | | <0.0085 | U | | 0.0021 | J | |
| | | VMP-21-10-020513 | 2/5/2013 | <0.0062 | U | | <0.011 | U | | <0.014 | U | | <0.0066 | U | | <0.028 | U | | 0.0036 | J | | <0.01 | U | | <0.0081 | U | | <0.0081 | U | | <0.0081 | U | | 0.0022 | J | |
| | | VMP-21-10-020513-DUP | 2/5/2013 | <0.0058 | U | | <0.011 | U | | <0.013 | U | | <0.0062 | U | | <0.026 | U | | 0.0043 | J | | <0.0097 | U | | <0.0076 | U | | <0.0076 | U | | <0.0076 | U | | 0.0024 | J | |
| | 25 ft | VMP-21-25-021011 | 2/10/2011 | <5.4 | U | | <9.9 | U | | <3.1 | U | | <5.7 | U | | <9.6 | U | | 370 | | | <9 | U | | <7 | U | | <7 | U | | <7 | U | | <5.8 | U | |
| | | VMP-21-25-041411 | 4/14/2011 | <19 | U | | <35 | U | | <43 | U | | <20 | U | | <34 | U | | 300 | | | <31 | U | | <24 | U | | <24 | U | | <24 | U | | <20 | U | |
| | | VMP-21-25-041411-DUP | 4/14/2011 | <19 | U | | <35 | U | | <43 | U | | <20 | U | | <34 | U | | 300 | | | <31 | U | | <24 | U | | <24 | U | | <24 | U | | <20 | U | |
| | | VMP-21-25-072611 | 7/26/2011 | <6.1 | U | | <11 | U | | <14 | U | | <6.4 | U | | <11 | U | | 290 | | | <10 | U | | <7.9 | U | | <7.9 | U | | <7.9 | U | | <6.5 | U | |
| | | VMP-21-25-110511 | 11/5/2011 | 2 | J | | <7.2 | U | | <8.9 | U | | <4.1 | U | | <6.9 | U | | 6.2 | | | <6.4 | U | | <5 | U | | <5 | U | | <5 | U | | <4.2 | U | |
| | | VMP-21-25-012412 | 1/24/2012 | <0.053 | U | | <0.099 | U | | <0.12 | U | | <0.057 | U | | <0.096 | U | | 0.0057 | J | | <0.089 | U | | <0.07 | U | | <0.07 | U | | <0.07 | U | | <0.057 | U | |
| | | VMP-21-25-040912 | 4/9/2012 | <0.0042 | U | | <0.0078 | U | | <0.0096 | U | | <0.0045 | U | | <0.019 | U | | 0.12 | | | <0.007 | U | | <0.0055 | U | | <0.0055 | U | | <0.0055 | U | | 0.0042 | J | |
| | | VMP-21-25-071112 | 7/11/2012 | <0.0042 | U | | <0.0078 | U | | <0.0096 | U | | <0.0045 | U | | <0.019 | U | | 0.0011 | J | | <0.007 | U | | <0.0055 | U | | <0.0055 | U | | <0.0055 | U | | 0.0022 | J | |
| | | VMP-21-25-100412 | 10/4/2012 | <0.0066 | U | | <0.012 | U | | <0.015 | U | | <0.007 | U | | <0.03 | U | | 0.0022 | J | | <0.011 | U | | <0.0087 | U | | <0.0087 | U | | <0.0087 | U | | 0.0026 | J | |
| | | VMP-21-25-020513 | 2/5/2013 | <0.0059 | U | | <0.011 | U | | <0.014 | U | | <0.0063 | U | | <0.027 | U | | 0.0035 | J | | <0.0099 | U | | <0.0078 | U | | <0.0078 | U | | <0.0078 | U | | 0.0025 | J | |
| | | VMP-21-25-020513-DUP | 2/5/2013 | <0.0062 | U | | <0.011 | U | | <0.014 | U | | <0.0066 | U | | <0.028 | U | | 0.004 | J | | <0.01 | U | | <0.0081 | U | | <0.0081 | U | | <0.0081 | U | | 0.0027 | J | |
| | 33 ft | VMP-21-33-021011 | 2/10/2011 | <5.4 | U | | <9.9 | U | | <3.1 | U | | <5.7 | U | | <9.6 | U | | 410 | | | <9 | U | | <7 | U | | <7 | U | | <7 | U | | <5.8 | U | |
| | | VMP-21-33-041411 | 4/14/2011 | <18 | U | | <34 | U | | <42 | U | | <19 | U | | <32 | U | | 290 | | | <30 | U | | <24 | U | | <24 | U | | <24 | U | | <19 | U | |
| | | VMP-21-33-110511 | 11/5/2011 | 0.52 | J | | <1.6 | U | | <2 | U | | <0.93 | U | | <1.6 | U | | 0.38 | J | | <1.5 | U | | <1.1 | U | | <1.1 | U | | <1.1 | U | | <0.94 | U | |
| | | VMP-21-33-012412 | 1/24/2012 | <0.12 | U | | <0.23 | U | | <0.29 | U | | <0.13 | U | | <0.22 | U | | 0.38 | | J | <0.21 | U | | <0.16 | U | | <0.16 | U | | <0.16 | U | | <0.14 | U | |
| | | VMP-21-33-042412 | 4/24/2012 | <0.0043 | J | U | <0.008 | U | | <0.0099 | U | | <0.0046 | U | | <0.019 | U | | 0.0051 | | | <0.0072 | U | | <0.0056 | U | | <0.0056 | U | | <0.0056 | J | U | 0.0029 | J | |
| | | VMP-21-33-071112 | 7/11/2012 | <0.0045 | U | | <0.0083 | U | | <0.01 | U | | <0.0048 | U | | <0.02 | U | | <0.0034 | U | | <0.0075 | U | | <0.0059 | U | | <0.0059 | U | | <0.0059 | U | | 0.0031 | J | |
| | | VMP-21-33-100412 | 10/4/2012 | <0.0065 | U | | <0.012 | U | | <0.015 | U | | <0.0069 | U | | <0.029 | U | | 0.0026 | J | | <0.011 | U | | <0.0085 | U | | <0.0085 | U | | <0.0085 | U | | 0.0028 | J | |
| | | VMP-21-33-020513 | 2/5/2013 | <0.0061 | U | | <0.011 | U | | <0.014 | U | | <0.0064 | U | | <0.027 | U | | <0.0045 | U | | <0.01 | U | | <0.0079 | U | | <0.0079 | U | | <0.0079 | U | | 0.0026 | J | |

SEE LAST PAGE OF TABLE FOR NOTES

**TABLE 5**
**CUMULATIVE SUMMARY OF SOIL VAPOR ANALYTICAL DETECTIONS AND SCREENING RESULTS: VILLAGE - VOCS**

| Location | Depth | Sample ID | Sample Date | Chlorobenzene | | | Chlorodibromomethane | | | Chloroethane | | | Chloroform | | | Chloromethane | | | Cyclohexane | | | 1,2-Dibromoethane | | | 1,2-Dichlorobenzene | | | 1,3-Dichlorobenzene | | | 1,4-Dichlorobenzene | | | Dichlorodifluoromethane | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | 69 | | | 57000 | | | | | | 0.11 | | | | | | | | | 0.011 | | | 290 | | | | | | 1200 | | | | | |
| | | | | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals |
| VMP-22 | 5 ft | VMP-22-5-021111 | 2/11/2011 | <0.12 | U | | <0.22 | U | | <0.068 | U | | <0.12 | U | | <0.21 | U | | <0.088 | U | | <0.2 | U | | <0.15 | U | | <0.15 | U | | <0.15 | U | | <0.13 | U | |
| | | VMP-22-5-041811 | 4/18/2011 | <0.058 | U | | <0.11 | U | | <0.13 | U | | <0.062 | U | | <0.1 | U | | <0.043 | U | | <0.097 | U | | <0.076 | U | | <0.076 | U | | <0.076 | U | | <0.062 | U | |
| | | VMP-22-5-072611 | 7/26/2011 | <0.0068 | J | U | <0.013 | U | | <0.016 | U | | <0.0072 | U | | <0.012 | U | | 0.021 | | | <0.011 | J | U | 0.0033 | J | | <0.0089 | J | U | 0.0023 | J | | 0.0023 | J | |
| | | VMP-22-5-110111 | 11/1/2011 | <0.0039 | U | | <0.0072 | U | | <0.0089 | U | | 0.0018 | J | | 0.0018 | J | | <0.0029 | U | | <0.0064 | U | | <0.005 | U | | <0.005 | U | | <0.005 | U | | 0.0021 | J | |
| | | VMP-22-5-012412 | 1/24/2012 | <0.0041 | J | U | <0.0075 | U | | <0.0093 | U | | <0.0043 | U | | <0.0073 | U | | 0.29 | | J | <0.0068 | U | | <0.0053 | U | | <0.0053 | J | U | <0.0053 | U | | 0.0031 | J | J |
| | | VMP-22-5-040912 | 4/9/2012 | <0.0045 | U | | <0.0083 | U | | <0.01 | U | | <0.0048 | U | | <0.02 | U | | 0.021 | | | <0.0075 | U | | <0.0059 | U | | <0.0059 | U | | <0.0059 | U | | 0.0028 | J | |
| | | VMP-22-5-070912 | 7/9/2012 | <0.005 | U | | <0.0092 | U | | <0.011 | U | | <0.0053 | U | | <0.022 | U | | <0.0037 | U | | <0.0083 | U | | <0.0065 | U | | <0.0065 | U | | <0.0065 | U | | 0.002 | J | |
| | | VMP-22-5-100312 | 10/3/2012 | <0.0058 | U | | <0.011 | U | | <0.013 | U | | <0.0062 | U | | <0.026 | U | | <0.0043 | U | | <0.0097 | U | | <0.0076 | U | | <0.0076 | U | | <0.0076 | U | | 0.0024 | J | |
| | | VMP-22-5-100312-Dup | 10/3/2012 | <0.0053 | U | | <0.0098 | U | | <0.012 | U | | <0.0056 | U | | <0.024 | U | | 0.0018 | J | | <0.0088 | U | | <0.0069 | U | | <0.0069 | U | | <0.0069 | U | | 0.0026 | J | |
| | | VMP-22-5-012413 | 1/24/2013 | <0.0059 | U | | <0.011 | U | | <0.014 | U | | <0.0063 | U | | <0.027 | U | | <0.0044 | U | | <0.0099 | U | | <0.0078 | U | | <0.0078 | J | U | <0.0078 | U | | 0.0025 | J | |
| | 10 ft | VMP-22-10-021111 | 2/11/2011 | <0.056 | U | | <0.1 | U | | <0.032 | U | | <0.06 | U | | <0.1 | U | | 0.19 | | | <0.094 | U | | <0.073 | U | | <0.073 | U | | <0.073 | U | | <0.06 | U | |
| | | VMP-22-10-041811 | 4/18/2011 | <0.06 | U | | <0.11 | U | | <0.14 | U | | <0.064 | U | | <0.11 | U | | <0.045 | U | | <0.1 | U | | <0.078 | U | | <0.078 | U | | <0.078 | U | | <0.064 | U | |
| | | VMP-22-10-072611 | 7/26/2011 | <0.007 | J | U | <0.013 | U | | <0.016 | U | | 0.012 | | | <0.012 | U | | 0.0046 | J | | <0.012 | J | U | <0.0091 | J | U | 0.0028 | J | | <0.0091 | J | U | 0.0023 | J | |
| | | VMP-22-10-072611-DUP | 7/26/2011 | <0.0082 | J | U | <0.015 | U | | <0.019 | U | | 0.012 | | | <0.015 | U | | 0.0063 | | | <0.014 | J | U | <0.011 | J | U | 0.0027 | J | | <0.011 | J | U | 0.0019 | J | |
| | | VMP-22-10-110211 | 11/2/2011 | <0.0039 | U | | <0.0073 | U | | <0.009 | U | | 0.014 | | | <0.0071 | U | | <0.0029 | U | | <0.0066 | U | | <0.0051 | U | | <0.0051 | U | | <0.0051 | U | | 0.0024 | J | |
| | | VMP-22-10-012412 | 1/24/2012 | <0.0045 | J | U | <0.0083 | U | | <0.01 | U | | 0.0071 | | | <0.008 | U | | 0.001 | J | | <0.0074 | U | | <0.0058 | U | | <0.0058 | J | U | <0.0058 | U | | 0.0032 | J | |
| | | VMP-22-10-040912 | 4/9/2012 | <0.0044 | U | | <0.0082 | U | | <0.01 | U | | 0.0024 | J | | <0.02 | U | | 0.013 | | | <0.0074 | U | | <0.0058 | U | | <0.0058 | U | | <0.0058 | U | | 0.0031 | J | |
| | | VMP-22-10-070912 | 7/9/2012 | <0.005 | U | | <0.0092 | U | | <0.011 | U | | 0.0011 | J | | <0.022 | U | | <0.0037 | U | | <0.0083 | U | | <0.0065 | U | | <0.0065 | U | | <0.0065 | U | | 0.0021 | J | |
| | | VMP-22-10-070912-Dup | 7/9/2012 | <0.0049 | U | | <0.009 | U | | <0.011 | U | | 0.0011 | J | | <0.022 | U | | <0.0036 | U | | <0.0081 | U | | <0.0064 | U | | <0.0064 | U | | <0.0064 | U | | 0.0017 | J | |
| | | VMP-22-10-100312 | 10/3/2012 | <0.0056 | U | | <0.01 | U | | <0.013 | U | | <0.0059 | U | | <0.025 | U | | 0.0032 | J | | <0.0093 | U | | <0.0073 | U | | <0.0073 | J | U | <0.0073 | J | U | 0.0024 | J | |
| | | VMP-22-10-012413 | 1/24/2013 | <0.0064 | U | | <0.012 | U | | <0.014 | U | | <0.0067 | U | | <0.028 | U | | <0.0048 | U | | <0.011 | U | | <0.0083 | U | | <0.0083 | J | U | <0.0083 | U | | 0.0029 | J | |
| | 18 ft | VMP-22-18-021111 | 2/11/2011 | <0.98 | U | | <1.8 | U | | <0.56 | U | | <1 | U | | <1.8 | U | | 65 | | | <1.6 | U | | <1.3 | U | | <1.3 | U | | <1.3 | U | | <1 | U | |
| | | VMP-22-18-041811 | 4/18/2011 | <4.1 | U | | <7.7 | U | | <9.5 | U | | <4.4 | U | | <7.4 | U | | 58 | | | <6.9 | U | | <5.4 | U | | <5.4 | U | | <5.4 | U | | <4.4 | U | |
| | | VMP-22-18-072611 | 7/26/2011 | <2.1 | U | | <3.9 | U | | <4.8 | U | | <2.2 | U | | <3.8 | U | | 39 | | | <3.5 | U | | <2.8 | U | | <2.8 | U | | <2.8 | U | | <2.3 | U | |
| | | VMP-22-18-110511 | 11/5/2011 | <0.0042 | J | U | <0.0078 | U | | <0.0096 | U | | 0.094 | | | <0.0076 | U | | <0.0031 | U | | <0.007 | U | | <0.0055 | U | | <0.0055 | U | | <0.0055 | U | | 0.0024 | J | |
| | | VMP-22-18-012412 | 1/24/2012 | <0.039 | U | | <0.072 | U | | <0.089 | U | | <0.041 | U | | <0.069 | U | | <0.029 | U | | <0.064 | U | | <0.05 | U | | <0.05 | U | | <0.05 | U | | <0.042 | U | |
| | | VMP-22-18-040912 | 4/9/2012 | <0.0046 | U | | <0.0086 | U | | <0.011 | U | | 0.089 | | | <0.021 | U | | 0.008 | | | <0.0077 | U | | <0.006 | U | | <0.006 | U | | <0.006 | U | | 0.0027 | J | |
| | | VMP-22-18-070912 | 7/9/2012 | <0.0049 | U | | <0.009 | U | | <0.011 | U | | 0.049 | | | <0.022 | U | | <0.0036 | U | | <0.0081 | U | | <0.0064 | U | | <0.0064 | U | | <0.0064 | U | | 0.002 | J | |
| | | VMP-22-18-100412 | 10/4/2012 | <0.0066 | U | | <0.012 | U | | <0.015 | U | | 0.013 | | | <0.03 | U | | <0.005 | U | | <0.011 | U | | <0.0087 | U | | <0.0087 | J | U | <0.0087 | J | U | 0.0022 | J | |
| | | VMP-22-18-012413 | 1/24/2013 | <0.0064 | U | | <0.012 | U | | <0.014 | U | | 0.015 | | | <0.028 | U | | <0.0048 | U | | <0.011 | U | | <0.0083 | U | | <0.0083 | U | | <0.0083 | U | | 0.0029 | J | |
| | 38 ft | VMP-22-38-041811 | 4/18/2011 | <13 | U | | <24 | U | | <29 | U | | <13 | U | | <23 | U | | 240 | | | <21 | U | | <16 | U | | <16 | U | | <16 | U | | <14 | U | |
| | | VMP-22-38-012512 | 1/25/2012 | <0.039 | U | | <0.072 | U | | <0.089 | U | | <0.041 | U | | <0.069 | U | | <0.029 | U | | <0.064 | U | | <0.05 | U | | <0.05 | U | | <0.05 | U | | <0.042 | U | |
| | | VMP-22-38-040912 | 4/9/2012 | <0.0045 | U | | <0.0083 | U | | <0.01 | U | | 0.35 | | | <0.02 | U | | 0.014 | | | <0.0075 | U | | <0.0059 | U | | <0.0059 | U | | <0.0059 | U | | 0.003 | J | |
| | | VMP-22-38-070912 | 7/9/2012 | <0.0047 | U | | <0.0088 | U | | <0.011 | U | | 0.31 | | | <0.021 | U | | 0.00078 | J | | <0.0079 | U | | <0.0062 | U | | <0.0062 | U | | <0.0062 | U | | <0.0051 | U | |
| | | VMP-22-38-100412 | 10/4/2012 | <0.007 | U | | <0.013 | U | | <0.016 | U | | 0.075 | | | <0.031 | U | | 0.0012 | J | | <0.012 | U | | <0.0091 | U | | <0.0091 | J | U | <0.0091 | J | U | 0.0026 | J | |
| | | VMP-22-38-012413 | 1/24/2013 | <0.0062 | U | | <0.011 | U | | <0.014 | U | | 0.062 | | | <0.028 | U | | <0.0046 | U | | <0.01 | U | | <0.0081 | U | | <0.0081 | U | | <0.0081 | U | | 0.0025 | J | |
| VMP-23 | 5 ft | VMP-23-5-021511 | 2/15/2011 | <0.0061 | U | | <0.011 | U | | <0.0035 | U | | 0.0013 | J | | <0.011 | U | | 0.0054 | | | <0.01 | U | | <0.0079 | U | | <0.0079 | J | U | <0.0079 | J | U | 0.0021 | J | |
| | | VMP-23-5-042111 | 4/21/2011 | <0.053 | U | | <0.098 | U | | <0.12 | U | | <0.056 | U | | <0.094 | U | | <0.039 | U | | <0.088 | U | | <0.069 | U | | <0.069 | U | | <0.069 | U | | <0.057 | U | |
| | | VMP-23-5-072711 | 7/27/2011 | <0.0061 | U | | <0.011 | U | | <0.014 | U | | <0.0064 | U | | <0.011 | U | | 0.0068 | | | <0.01 | U | | <0.0079 | U | | <0.0079 | U | | <0.0079 | U | | 0.0016 | J | |
| | | VMP-23-5-110211 | 11/2/2011 | <0.0043 | U | | <0.008 | U | | <0.0099 | U | | <0.0046 | U | | <0.0077 | U | | <0.0032 | U | | <0.0072 | U | | <0.0056 | U | | <0.0056 | U | | <0.0056 | U | | 0.002 | J | |
| | | VMP-23-5-012512 | 1/25/2012 | <0.0036 | U | | <0.0067 | U | | <0.0083 | U | | 0.0022 | J | | <0.0065 | U | | 0.0022 | J | | <0.0061 | U | | <0.0047 | U | | <0.0048 | U | | 0.0012 | J | | 0.0027 | J | |
| | | VMP-23-5-040912 | 4/9/2012 | <0.0044 | U | | <0.0081 | U | | <0.01 | U | | <0.0047 | U | | <0.02 | U | | 0.0031 | J | | <0.0073 | U | | <0.0057 | U | | <0.0057 | U | | <0.0057 | U | | 0.0033 | J | |
| | | VMP-23-5-070912 | 7/9/2012 | <0.0039 | J | U | <0.0073 | U | | <0.009 | U | | <0.0042 | U | | 0.0044 | J | | 0.0022 | J | | <0.0066 | U | | <0.0051 | U | | <0.0051 | U | | <0.0051 | U | | 0.0021 | J | |
| | | VMP-23-5-100312 | 10/3/2012 | <0.0066 | J | U | <0.012 | U | | <0.015 | U | | <0.007 | U | | <0.03 | U | | 0.0019 | J | | <0.011 | U | | <0.0087 | U | | <0.0087 | J | U | <0.0087 | J | U | 0.0022 | J | |
| | | VMP-23-5-012413 | 1/24/2013 | <0.0057 | U | | <0.01 | U | | <0.013 | U | | <0.006 | U | | <0.026 | U | | <0.0042 | U | | <0.0095 | U | | <0.0074 | U | | <0.0074 | U | | <0.0074 | U | | 0.0023 | J | |
| | 10 ft | VMP-23-10-021511 | 2/15/2011 | <0.0063 | J | U | <0.012 | U | | <0.0036 | U | | 0.0015 | J | | <0.011 | U | | 0.0044 | J | | <0.01 | U | | 0.0024 | J | | <0.0082 | J | U | <0.0082 | J | U | <0.0068 | U | |
| | | VMP-23-10-042111 | 4/21/2011 | <0.064 | U | | <0.12 | U | | <0.14 | U | | <0.067 | U | | <0.11 | U | | 0.94 | | | <0.11 | U | | <0.083 | U | | <0.083 | U | | <0.083 | U | | <0.068 | U | |
| | | VMP-23-10-072711 | 7/27/2011 | <0.0058 | U | | <0.011 | U | | <0.013 | U | | <0.0062 | U | | <0.01 | U | | <0.0043 | U | | <0.0097 | U | | <0.0076 | U | | <0.0076 | U | | <0.0076 | U | | <0.0062 | U | |
| | | VMP-23-10-110211 | 11/2/2011 | <0.0042 | U | | <0.0078 | U | | <0.0096 | U | | <0.0045 | U | | <0.0076 | U | | <0.0031 | U | | <0.007 | U | | <0.0055 | U | | <0.0055 | U | | <0.0055 | U | | 0.0019 | J | |
| | | VMP-23-10-012512 | 1/25/2012 | <0.0036 | U | | <0.0066 | U | | <0.0082 | U | | 0.0067 | | | <0.0064 | U | | 0.2 | | | <0.006 | U | | <0.0046 | U | | <0.0046 | U | | <0.0046 | U | | 0.0023 | J | |
| | | VMP-23-10-040912 | 4/9/2012 | <0.0045 | U | | <0.0083 | U | | <0.01 | U | | <0.0048 | U | | <0.02 | U | | <0.0034 | U | | <0.0075 | U | | <0.0059 | U | | <0.0059 | U | | <0.0059 | U | | 0.0035 | J | |
| | | VMP-23-10-040912-Dup | 4/9/2012 | <0.0045 | U | | <0.0083 | U | | <0.01 | U | | 0.0034 | J | | 0.014 | J | | 0.0017 | J | | <0.0075 | U | | <0.0059 | U | | <0.0059 | U | | <0.0059 | U | | 0.0034 | J | |
| | | VMP-23-10-070912 | 7/9/2012 | <0.0036 | J | U | <0.0066 | U | | <0.0082 | U | | 0.0012 | J | | 0.0036 | J | | 0.00069 | J | | <0.006 | U | | <0.0046 | U | | <0.0046 | U | | <0.0046 | U | | 0.0022 | J | |
| | | VMP-23-10-100312 | 10/3/2012 | <0.0072 | J | U | <0.013 | U | | <0.016 | U | | <0.0076 | U | | 0.0082 | J | | 0.0063 | | | <0.012 | U | | <0.0093 | U | | <0.0093 | J | U | <0.0093 | J | U | 0.0026 | J | |
| | | VMP-23-10-012413 | 1/24/2013 | <0.0057 | U | | <0.01 | U | | <0.013 | U | | 0.0016 | J | | <0.026 | U | | <0.0042 | U | | <0.0095 | U | | <0.0074 | U | | <0.0074 | U | | <0.0074 | U | | 0.0025 | J | |
| | 25 ft | VMP-23-25-021511 | 2/15/2011 | <0.0058 | U | | <0.011 | U | | <0.0033 | U | | <0.0062 | U | | <0.01 | U | | 0.0032 | J | | <0.0097 | U | | <0.0076 | U | | <0.0076 | U | | 0.0012 | J | | <0.0062 | U | |
| | | VMP-23-25-042111 | 4/21/2011 | <0.059 | U | | <0.11 | U | | <0.14 | U | | <0.063 | U | | <0.11 | U | | 1.2 | | | <0.099 | U | | <0.078 | U | | <0.078 | U | | <0.078 | U | | <0.064 | U | |
| | | VMP-23-25-072711 | 7/27/2011 | <0.0066 | U | | <0.012 | U | | <0.015 | U | | <0.007 | U | | <0.012 | U | | 0.0026 | J | | 0.0026 | J | | 0.003 | J | | 0.0035 | J | | 0.0043 | J | | <0.0071 | U | |
| | | VMP-23-25-110511 | 11/5/2011 | <0.0042 | J | U | <0.0078 | U | | <0.0096 | U | | <0.0045 | U | | <0.0076 | U | | <0.0031 | U | | <0.007 | U | | <0.0055 | U | | <0.0055 | U | | <0.0055 | U | | 0.0015 | J | |
| | | VMP-23-25-012512 | 1/25/2012 | <0.0038 | U | | <0.0086 | U | | <0.0086 | U | | 0.0027 | J | | <0.0068 | U | | 0.15 | | | <0.0063 | U | | <0.0049 | U | | <0.0049 | U | | <0.0049 | U | | 0.002 | J | |
| | | VMP-23-25-040912 | 4/9/2012 | <0.0044 | U | | <0.0081 | U | | <0.01 | U | | 0.0034 | J | | 0.017 | J | | 0.007 | | | <0.0073 | U | | <0.0057 | U | | <0.0057 | U | | <0.0057 | U | | 0.0032 | J | |
| | | VMP-23-25-071012 | 7/10/2012 | <0.0056 | J | U | <0.01 | U | | <0.013 | U | | 0.0055 | J | | 0.015 | J | | 0.0018 | J | | <0.0094 | U | | <0.0073 | U | | <0.0073 | U | | <0.0073 | U | | 0.0024 | J | |
| | | VMP-23-25-100312 | 10/3/2012 | <0.007 | J | U | <0.013 | U | | <0.016 | U | | 0.0046 | J | | <0.031 | U | | 0.0064 | | | <0.012 | U | | <0.0091 | U | | <0.0091 | J | U | <0.0091 | J | U | 0.0021 | J | |
| | | VMP-23-25-012413 | 1/24/2013 | <0.0058 | U | | <0.011 | U | | <0.013 | U | | 0.017 | | | <0.026 | U | | <0.0043 | U | | <0.0097 | U | | <0.0076 | U | | <0.0076 | U | | <0.0076 | U | | 0.0024 | J | |
| | 40 ft | VMP-23-40-071012 | 7/10/2012 | <0.0047 | J | U | <0.0088 | U | | <0.011 | U | | <0.005 | U | | <0.021 | U | | 0.0025 | J | | <0.0079 | U | | <0.0062 | U | | <0.0062 | U | | <0.0062 | U | | 0.0015 | J | |
| | | VMP-23-40-100312 | 10/3/2012 | <0.0065 | J | U | <0.012 | U | | <0.015 | U | | <0.0069 | U | | <0.029 | U | | 0.0068 | | | <0.011 | U | | <0.0084 | U | | <0.0084 | J | U | <0.0084 | J | U | 0.0025 | J | |
| | | VMP-23-40-012413 | 1/24/2013 | <0.0059 | U | | <0.011 | U | | <0.014 | U | | 0.0069 | | | <0.027 | U | | <0.0044 | U | | <0.0099 | U | | <0.0078 | U | | <0.0078 | U | | <0.0078 | U | | 0.0026 | J | |

SEE LAST PAGE OF TABLE FOR NOTES

**TABLE 5**
**CUMULATIVE SUMMARY OF SOIL VAPOR ANALYTICAL DETECTIONS AND SCREENING RESULTS: VILLAGE - VOCS**

| Location | Depth | Sample ID | Sample Date | Chlorobenzene | | | Chlorodibromomethane | | | Chloroethane | | | Chloroform | | | Chloromethane | | | Cyclohexane | | | 1,2-Dibromoethane | | | 1,2-Dichlorobenzene | | | 1,3-Dichlorobenzene | | | 1,4-Dichlorobenzene | | | Dichlorodifluoromethane | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | 69 | | | 57000 | | | | | | 0.11 | | | | | | | | | 0.011 | | | 290 | | | | | | 1200 | | | | | |
| | | | | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals |
| VMP-24 | 5 ft | VMP-24-5-021611 | 2/16/2011 | <0.0065 | U | | <0.012 | U | | <0.0037 | U | | <0.0069 | U | | <0.012 | U | | 0.0032 | J | | <0.011 | U | | <0.0085 | J | U | <0.0085 | J | U | <0.0085 | J | U | 0.0017 | J | |
| | | VMP-24-5-040811 | 4/8/2011 | <0.069 | U | | <0.13 | U | | <0.16 | U | | <0.073 | U | | <0.12 | U | | 0.71 | | | <0.12 | U | | <0.09 | U | | <0.09 | U | | <0.09 | U | | <0.074 | U | |
| | | VMP-24-5-072811 | 7/28/2011 | <0.0065 | U | | <0.012 | U | | <0.015 | U | | <0.0069 | U | | 0.0049 | J | | 0.004 | J | | 0.0024 | J | | 0.0021 | J | | 0.0027 | J | | 0.0036 | J | | 0.002 | J | |
| | | VMP-24-5-110211 | 11/2/2011 | <0.0043 | U | | <0.008 | U | | <0.0099 | U | | <0.0046 | U | | <0.0077 | U | | <0.0032 | U | | <0.0072 | U | | <0.0056 | U | | <0.0056 | U | | <0.0056 | U | | 0.0024 | J | |
| | | VMP-24-5-110211-DUP | 11/2/2011 | <0.006 | U | | <0.011 | U | | <0.014 | U | | <0.0063 | U | | <0.011 | U | | <0.0045 | U | | <0.01 | U | | <0.0078 | U | | <0.0078 | U | | <0.0078 | J | U | 0.0023 | J | |
| | | VMP-24-5-012512 | 1/25/2012 | <0.0037 | U | | <0.0068 | U | | <0.0085 | U | | <0.0039 | U | | <0.0066 | U | | <0.0028 | U | | <0.0062 | U | | <0.0048 | U | | <0.0048 | U | | <0.0048 | U | | 0.0026 | J | |
| | | VMP-24-5-040912 | 4/9/2012 | <0.0044 | U | | <0.0081 | U | | <0.01 | U | | <0.0047 | U | | 0.011 | J | | 0.0016 | J | | <0.0073 | U | | <0.0057 | U | | <0.0057 | U | | <0.0057 | U | | 0.0032 | J | |
| | | VMP-24-5-071212 | 7/12/2012 | <0.0042 | U | | <0.0078 | U | | <0.0096 | U | | <0.0045 | U | | 0.0016 | J | | 0.0019 | J | | <0.007 | U | | <0.0055 | U | | <0.0055 | U | | <0.0055 | U | | 0.0021 | J | |
| | | VMP-24-5-101912 | 10/19/2012 | <0.0065 | J | U | <0.012 | U | | <0.015 | U | | <0.0069 | U | | <0.029 | U | | 0.0015 | J | | <0.011 | U | | <0.0085 | U | | <0.0085 | J | U | <0.0085 | J | U | 0.0025 | J | |
| | | VMP-24-5-012313 | 1/23/2013 | <0.0058 | U | | <0.011 | U | | <0.013 | U | | <0.0062 | U | | <0.026 | U | | <0.0043 | U | | <0.0097 | U | | <0.0076 | U | | <0.0076 | U | | <0.0076 | U | | 0.0024 | J | |
| | 10 ft | VMP-24-10-021711 | 2/17/2011 | <0.0062 | U | | <0.011 | U | | <0.0035 | U | | <0.0066 | U | | <0.011 | U | | 0.11 | | | <0.01 | U | | <0.0081 | U | | <0.0081 | U | | <0.0081 | U | | 0.0025 | J | |
| | | VMP-24-10-041111 | 4/11/2011 | <0.012 | U | | <0.021 | U | | <0.026 | U | | <0.012 | U | | <0.021 | U | | 0.15 | | | <0.019 | U | | <0.015 | U | | <0.015 | U | | <0.015 | U | | 0.0013 | J | |
| | | VMP-24-10-072811 | 7/28/2011 | <0.0064 | U | | <0.012 | U | | <0.014 | U | | <0.0067 | U | | <0.011 | U | | 0.0016 | J | | 0.0015 | J | | 0.0014 | J | | <0.0083 | U | | 0.0023 | J | | 0.0019 | J | |
| | | VMP-24-10-110211 | 11/2/2011 | <0.0038 | U | | <0.007 | U | | <0.0086 | U | | <0.004 | U | | 0.0016 | J | | <0.0028 | U | | <0.0063 | U | | <0.0049 | U | | <0.0049 | U | | <0.0049 | U | | 0.0022 | J | |
| | | VMP-24-10-012512 | 1/25/2012 | <0.0036 | U | | <0.0066 | U | | <0.0082 | U | | <0.0038 | U | | <0.0064 | U | | <0.0027 | U | | <0.006 | U | | <0.0046 | U | | <0.0046 | U | | <0.0046 | U | | 0.0024 | J | |
| | | VMP-24-10-041012 | 4/10/2012 | <0.0042 | U | | <0.0078 | U | | <0.0096 | U | | <0.0045 | U | | <0.019 | U | | 0.0022 | J | | <0.007 | U | | <0.0055 | U | | <0.0055 | U | | <0.0055 | U | | 0.0036 | J | |
| | | VMP-24-10-071212 | 7/12/2012 | <0.0049 | U | | <0.009 | U | | <0.011 | U | | <0.0052 | U | | 0.0097 | J | | <0.0036 | U | | <0.0081 | U | | <0.0064 | U | | <0.0064 | U | | <0.0064 | U | | 0.0023 | J | |
| | | VMP-24-10-100912 | 10/9/2012 | <0.0061 | U | | <0.011 | U | | <0.014 | U | | <0.0064 | U | | <0.027 | U | | <0.0045 | U | | <0.01 | U | | <0.0079 | U | | <0.0079 | U | | <0.0079 | J | U | 0.0026 | J | |
| | | VMP-24-10-012313 | 1/23/2013 | <0.0064 | U | | <0.012 | U | | <0.014 | U | | <0.0067 | U | | <0.028 | U | | <0.0048 | U | | <0.011 | U | | <0.0083 | U | | <0.0083 | U | | <0.0083 | U | | 0.0025 | J | |
| | 22 ft | VMP-24-22-021711 | 2/17/2011 | <0.0062 | U | | <0.011 | U | | <0.0035 | U | | <0.0066 | U | | <0.011 | U | | 0.067 | | | <0.01 | U | | <0.0081 | U | | <0.0081 | U | | <0.0081 | U | | 0.0026 | J | |
| | | VMP-24-22-041111 | 4/11/2011 | <0.0058 | U | | <0.011 | U | | <0.013 | U | | <0.0062 | U | | 0.0039 | J | | <0.0043 | U | | <0.0097 | U | | <0.0076 | U | | <0.0076 | U | | <0.0076 | U | | 0.0032 | J | |
| | | VMP-24-22-072811 | 7/28/2011 | <0.0058 | U | | <0.011 | U | | <0.013 | U | | <0.0062 | U | | <0.01 | U | | <0.0043 | U | | 0.0016 | J | | 0.001 | J | | <0.0076 | U | | 0.0016 | J | | 0.0024 | J | |
| | | VMP-24-22-072811-Dup | 7/28/2011 | <0.0066 | U | | <0.012 | U | | <0.015 | U | | <0.007 | U | | <0.012 | U | | <0.005 | U | | <0.011 | U | | 0.001 | J | | <0.0087 | U | | 0.002 | J | | 0.0019 | J | |
| | | VMP-24-22-110611 | 11/6/2011 | <0.004 | J | U | <0.0074 | U | | <0.0092 | U | | <0.0043 | J | U | <0.0072 | U | | 0.0011 | J | | <0.0067 | U | | <0.0053 | U | | <0.0053 | U | | <0.0053 | U | | 0.0029 | J | |
| | | VMP-24-22-012512 | 1/25/2012 | <0.0038 | U | | <0.007 | U | | <0.0086 | U | | <0.004 | U | | <0.0068 | U | | <0.0028 | U | | <0.0063 | U | | <0.0049 | U | | <0.0049 | U | | <0.0049 | U | | 0.0026 | J | |
| | | VMP-24-22-041012 | 4/10/2012 | <0.0041 | U | | <0.0076 | U | | <0.0094 | U | | <0.0044 | U | | 0.011 | J | | 0.0082 | | | <0.0069 | U | | <0.0054 | U | | <0.0054 | U | | <0.0054 | U | | 0.0031 | J | |
| | | VMP-24-22-071212 | 7/12/2012 | <0.005 | U | | <0.0092 | U | | <0.011 | U | | <0.0053 | U | | 0.0026 | J | | 0.001 | J | | <0.0083 | U | | <0.0065 | U | | <0.0065 | U | | <0.0065 | U | | <0.0054 | U | |
| | | VMP-24-22-100912 | 10/9/2012 | <0.0062 | U | | <0.011 | U | | <0.014 | U | | <0.0056 | U | | <0.028 | U | | <0.0046 | U | | <0.01 | U | | <0.0081 | U | | <0.0081 | U | | <0.0081 | U | | 0.0027 | J | |
| | | VMP-24-22-012313 | 1/23/2013 | <0.0065 | U | | <0.012 | U | | <0.015 | U | | <0.0069 | U | | <0.029 | U | | <0.0048 | U | | <0.011 | U | | <0.0085 | U | | <0.0085 | U | | <0.0085 | U | | 0.0029 | J | |
| | 34 ft | VMP-24-34-021711 | 2/17/2011 | <0.0062 | U | | <0.011 | U | | <0.0035 | U | | <0.0066 | U | | 0.0036 | J | | 0.0024 | J | | <0.01 | U | | <0.0081 | U | | <0.0081 | U | | <0.0081 | U | | 0.0022 | J | |
| | | VMP-24-34-041111 | 4/11/2011 | <0.0056 | U | | 0.0027 | J | | <0.013 | U | | 0.00071 | J | | <0.01 | U | | 0.0018 | J | | <0.0093 | U | | <0.0073 | U | | <0.0073 | U | | <0.0073 | U | | 0.0021 | J | |
| | | VMP-24-34-072811 | 7/28/2011 | <0.0049 | U | | <0.0091 | U | | <0.011 | U | | <0.0052 | U | | <0.0088 | U | | 0.00092 | J | | <0.0082 | U | | <0.0064 | U | | <0.0064 | U | | 0.0015 | J | | 0.0016 | J | |
| | | VMP-24-34-110611 | 11/6/2011 | <0.0031 | J | U | <0.0058 | U | | <0.0072 | U | | <0.0033 | U | | <0.0056 | U | | 0.0009 | J | | <0.0052 | U | | <0.0041 | U | | <0.0041 | U | | <0.0041 | U | | 0.0028 | J | |
| | | VMP-24-34-012512 | 1/25/2012 | <0.0039 | U | | <0.0072 | U | | <0.0089 | U | | 0.00092 | J | | <0.0069 | U | | <0.0029 | U | | <0.0064 | U | | <0.005 | U | | 0.0011 | J | | 0.0013 | J | | 0.0031 | J | |
| | | VMP-24-34-041012 | 4/10/2012 | <0.0043 | U | | <0.008 | U | | <0.0099 | U | | <0.0046 | U | | 0.01 | J | | 0.0072 | | | <0.0072 | U | | <0.0056 | U | | <0.0056 | U | | <0.0056 | U | | 0.0033 | J | |
| | | VMP-24-34-071212 | 7/12/2012 | <0.0041 | U | | <0.0076 | U | | <0.0094 | U | | <0.0044 | U | | <0.018 | U | | 0.0022 | J | | <0.0069 | U | | <0.0054 | U | | <0.0054 | U | | <0.0054 | U | | 0.0018 | J | |
| | | VMP-24-34-100912 | 10/9/2012 | <0.0064 | U | | <0.012 | U | | <0.014 | U | | <0.0067 | U | | <0.028 | U | | 0.0018 | J | | <0.011 | U | | <0.0083 | U | | <0.0083 | U | | <0.0083 | U | | 0.0024 | J | |
| | | VMP-24-34-012313 | 1/23/2013 | <0.0066 | U | | <0.012 | U | | <0.015 | U | | <0.007 | U | | <0.03 | U | | <0.005 | U | | <0.011 | U | | <0.0087 | U | | <0.0087 | U | | <0.0087 | U | | 0.0027 | J | |
| VMP-31 | 5 ft | VMP-31-5-042512 | 4/25/2012 | <0.0044 | J | U | <0.0081 | U | | <0.01 | U | | <0.0047 | U | | <0.02 | U | | <0.0033 | U | | <0.0073 | U | | <0.0057 | U | | <0.0057 | U | | <0.0057 | J | U | 0.0027 | J | |
| | | VMP-31-5-072012 | 7/20/2012 | <0.0044 | U | | <0.0081 | U | | <0.01 | U | | <0.0047 | U | | 0.0036 | J | | <0.0033 | U | | <0.0073 | U | | <0.0057 | U | | <0.0057 | U | | <0.0057 | U | | 0.0026 | J | |
| | | VMP-31-5-102612 | 10/26/2012 | 0.0015 | J | | <0.012 | U | | <0.014 | U | | <0.0067 | U | | 0.004 | J | | 0.014 | | | <0.011 | U | | <0.0083 | U | | <0.0083 | U | | <0.0083 | U | | 0.0021 | J | |
| | | VMP-31-5-021113 | 2/11/2013 | <0.0059 | U | | <0.011 | U | | <0.014 | U | | <0.0063 | U | | <0.027 | U | | 0.0032 | J | | <0.0099 | U | | <0.0078 | U | | <0.0078 | J | U | <0.0078 | J | U | 0.0022 | J | |
| | 10 ft | VMP-31-10-042512 | 4/25/2012 | <0.0059 | J | U | <0.011 | U | | <0.013 | U | | <0.0062 | U | | <0.026 | U | | 0.018 | | | <0.0098 | U | | <0.0077 | U | | <0.0077 | J | U | <0.0077 | J | U | 0.0025 | J | |
| | | VMP-31-10-072612 | 7/26/2012 | <0.0045 | J | U | <0.0083 | U | | <0.01 | U | | 0.0031 | J | | <0.02 | U | | <0.0034 | U | | <0.0075 | U | | <0.0059 | U | | <0.0059 | J | U | <0.0059 | J | U | 0.0035 | J | |
| | | VMP-31-10-102612 | 10/26/2012 | <0.0068 | U | | <0.013 | U | | <0.016 | U | | <0.0072 | U | | <0.03 | U | | 0.0022 | J | | <0.011 | U | | <0.0089 | U | | <0.0089 | U | | <0.0089 | U | | 0.0023 | J | |
| | | VMP-31-10-021313 | 2/13/2013 | <0.0065 | U | | <0.012 | U | | <0.015 | U | | <0.0069 | U | | <0.029 | U | | 0.004 | J | | <0.011 | U | | <0.0085 | U | | <0.0085 | J | U | 0.0021 | J | | | | |
| | 20 ft | VMP-31-20-101912 | 10/19/2012 | <6.4 | U | | <12 | U | | <14 | U | | <6.7 | U | | <11 | U | | 4.4 | J | | <11 | U | | <8.3 | U | | <8.3 | U | | <8.3 | U | | <6.8 | U | |
| | | VMP-31-20-021113 | 2/11/2013 | <0.091 | U | | <0.17 | U | | <0.21 | U | | <0.096 | U | | <0.16 | U | | <0.068 | U | | <0.15 | U | | <0.12 | U | | <0.12 | U | | <0.12 | U | | <0.097 | U | |
| | 30 ft | VMP-31-30-042512 | 4/25/2012 | <2.2 | U | | <4.2 | U | | <5.2 | U | | <2.4 | U | | <4 | U | | 34 | | | <3.8 | U | | <2.9 | U | | <2.9 | U | | <2.9 | U | | <2.4 | U | |
| | | VMP-31-30-042512-Dup | 4/25/2012 | <2.2 | U | | <4.2 | U | | <5.2 | U | | <2.4 | U | | <4 | U | | 38 | | | <3.8 | U | | <2.9 | U | | <2.9 | U | | <2.9 | U | | <2.4 | U | |
| | | VMP-31-30-072012 | 7/20/2012 | <0.44 | U | | <0.81 | U | | <1 | U | | <0.47 | U | | <2 | U | | 0.4 | | | <0.73 | U | | <0.57 | U | | <0.57 | U | | <0.57 | U | | <0.47 | U | |
| | | VMP-31-30-101912 | 10/19/2012 | <0.4 | U | | <0.73 | U | | <0.91 | U | | <0.42 | U | | <0.71 | U | | 0.42 | | | <0.66 | U | | <0.52 | U | | <0.52 | U | | <0.52 | U | | <0.42 | U | |
| | | VMP-31-30-021113 | 2/11/2013 | <6.5 | U | | <12 | U | | <15 | U | | <6.9 | U | | <12 | U | | <4.8 | U | | <11 | U | | <8.5 | U | | <8.5 | U | | <8.5 | U | | <7 | U | |
| VMP-32 | 5 ft | VMP-32-5-042512 | 4/25/2012 | <0.0043 | J | U | <0.008 | U | | <0.0099 | U | | <0.0046 | U | | <0.019 | U | | 0.00091 | J | | <0.0072 | U | | 0.0012 | J | | <0.0056 | J | U | <0.0056 | J | U | 0.003 | J | |
| | | VMP-32-5-072012 | 7/20/2012 | 0.0014 | J | | <0.0072 | U | | <0.0089 | U | | <0.0041 | U | | 0.0022 | J | | 0.0034 | | | <0.0064 | U | | <0.005 | U | | <0.005 | U | | <0.005 | U | | 0.0025 | J | |
| | | VMP-32-5-101812 | 10/18/2012 | 0.0044 | J | | <0.014 | U | | <0.017 | U | | <0.0078 | U | | <0.033 | U | | 0.016 | | | <0.012 | U | | <0.0096 | U | | <0.0096 | U | | <0.0096 | U | | <0.0079 | U | |
| | | VMP-32-5-020513 | 2/5/2013 | <0.0058 | U | | <0.011 | U | | <0.013 | U | | <0.0062 | U | | <0.026 | U | | <0.0043 | U | | <0.0097 | U | | <0.0076 | U | | <0.0076 | J | U | <0.0076 | J | U | 0.0024 | J | |
| | 10 ft | VMP-32-10-041612 | 4/16/2012 | <0.0039 | U | | <0.0073 | U | | <0.009 | U | | <0.0042 | U | | 0.0016 | J | | 0.0024 | J | | <0.0066 | U | | <0.0051 | U | | <0.0051 | U | | <0.0051 | J | U | 0.0027 | J | |
| | | VMP-32-10-072012 | 7/20/2012 | 0.0019 | J | | <0.0083 | U | | <0.01 | U | | <0.0048 | U | | 0.0013 | J | | 0.0022 | J | | <0.0075 | U | | <0.0059 | U | | <0.0059 | U | | <0.0059 | U | | 0.0022 | J | |
| | | VMP-32-10-101812 | 10/18/2012 | 0.0025 | J | | <0.013 | U | | <0.016 | U | | <0.0072 | U | | 0.003 | J | | 0.012 | | | <0.011 | U | | <0.0089 | U | | <0.0089 | U | | <0.0089 | U | | 0.0025 | J | |
| | | VMP-32-10-020513 | 2/5/2013 | <0.0058 | U | | <0.011 | U | | <0.013 | U | | <0.0062 | U | | <0.026 | U | | <0.0043 | U | | <0.0097 | U | | <0.0076 | U | | <0.0076 | U | | <0.0076 | U | | 0.0026 | J | |
| | 20 ft | VMP-32-20-041612 | 4/16/2012 | <0.09 | U | | <0.17 | U | | <0.21 | U | | <0.096 | U | | <0.4 | U | | 0.21 | | | <0.15 | U | | 0.041 | J | | 0.05 | J | | 0.058 | J | | <0.097 | U | |
| | | VMP-32-20-072012 | 7/20/2012 | <0.0044 | U | | <0.0081 | U | | <0.01 | U | | <0.0047 | U | | 0.0064 | J | | <0.0033 | U | | <0.0073 | U | | <0.0057 | U | | <0.0057 | U | | <0.0057 | U | | 0.0027 | J | |
| | | VMP-32-20-101812 | 10/18/2012 | 0.0025 | J | | <0.012 | U | | <0.014 | U | | <0.0067 | U | | <0.028 | U | | 0.0076 | | | <0.011 | U | | <0.0083 | U | | <0.0083 | U | | <0.0083 | U | | 0.0026 | J | |
| | | VMP-32-20-020513 | 2/5/2013 | <0.0065 | U | | <0.012 | U | | <0.015 | U | | 0.0013 | J | | <0.029 | U | | <0.0048 | U | | <0.011 | U | | <0.0085 | U | | <0.0085 | U | | <0.0085 | U | | 0.0024 | J | |
| | 30 ft | VMP-32-30-041612 | 4/16/2012 | <2.2 | U | | <4 | U | | <4.9 | U | | <2.3 | U | | <3.9 | U | | 360 | | | <3.6 | U | | <2.8 | U | | <2.8 | U | | <2.8 | U | | <2.3 | U | |
| | | VMP-32-30-072012 | 7/20/2012 | <4.4 | U | | <8.2 | U | | <10 | U | | <4.7 | U | | <8 | U | | 200 | | | <7.4 | U | | <5.8 | U | | <5.8 | U | | <5.8 | U | | <4.8 | U | |
| | | VMP-32-30-101812 | 10/18/2012 | <0.25 | U | | <0.47 | U | | <0.58 | U | | <0.27 | U | | <0.45 | U | | 0.44 | | | <0.42 | U | | <0.33 | U | | <0.33 | U | | <0.33 | U | | <0.27 | U | |
| | | VMP-32-30-020513 | 2/5/2013 | <0.26 | U | | <0.48 | U | | <0.6 | U | | <0.28 | U | | <0.47 | U | | <0.19 | U | | <0.43 | U | | <0.34 | U | | <0.34 | U | | <0.34 | U | | <0.28 | U | |

SEE LAST PAGE OF TABLE FOR NOTES

**TABLE 5**
**CUMULATIVE SUMMARY OF SOIL VAPOR ANALYTICAL DETECTIONS AND SCREENING RESULTS: VILLAGE - VOCS**

| Location | Depth | Sample ID | Sample Date | Chlorobenzene | | | Chlorodibromomethane | | | Chloroethane | | | Chloroform | | | Chloromethane | | | Cyclohexane | | | 1,2-Dibromoethane | | | 1,2-Dichlorobenzene | | | 1,3-Dichlorobenzene | | | 1,4-Dichlorobenzene | | | Dichlorodifluoromethane | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | 69 | | | 57000 | | | | | | 0.11 | | | | | | | | | 0.011 | | | 290 | | | | | | 1200 | | | | | |
| | | | | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals |
| VMP-42 | 10 ft | VMP-42-10-041812 | 4/18/2012 | <0.0039 | U | | <0.0073 | U | | <0.009 | U | | 0.0035 | J | | <0.018 | U | | 0.047 | | J | <0.0066 | U | | <0.0051 | U | | <0.0051 | U | | <0.0051 | J | U | 0.0028 | J | |
| | | VMP-42-10-041812-Dup | 4/18/2012 | <0.004 | U | | <0.0074 | U | | <0.0092 | U | | <0.0043 | U | | <0.018 | U | | 0.036 | | J | <0.0067 | U | | <0.0053 | U | | <0.0053 | U | | <0.0053 | J | U | 0.0027 | J | |
| | | VMP-42-20-041812 | 4/18/2012 | <2.1 | U | | <3.8 | U | | <4.7 | U | | <2.2 | U | | <9.2 | U | | 3 | | | <3.4 | U | | <2.7 | U | | 0.92 | J | | 0.98 | J | | <2.2 | U | |
| | | VMP-42-10-071912 | 7/19/2012 | <0.0044 | U | | <0.0081 | U | | <0.01 | U | | 0.0022 | J | | <0.02 | U | | 0.0028 | J | | <0.0073 | U | | <0.0057 | U | | <0.0057 | U | | <0.0057 | U | | 0.0028 | J | |
| | | VMP-42-10-101212 | 10/12/2012 | <0.0071 | U | | <0.013 | U | | <0.016 | U | | <0.0075 | U | | <0.032 | U | | <0.0053 | U | | <0.012 | U | | <0.0093 | U | | <0.0093 | U | | <0.0093 | J | U | 0.0024 | J | |
| | | VMP-42-10-013113 | 1/31/2013 | <0.0065 | U | | <0.012 | U | | <0.015 | U | | <0.0069 | U | | <0.029 | U | | <0.0048 | U | | <0.011 | U | | <0.0085 | U | | <0.0085 | U | | <0.0085 | U | | 0.0025 | J | |
| | 20 ft | VMP-42-20-071912 | 7/19/2012 | <0.0043 | U | | <0.008 | U | | <0.0099 | U | | 0.1 | | | <0.019 | J | U | 0.013 | | | <0.0072 | U | | <0.0056 | U | | <0.0056 | U | | <0.0056 | J | U | 0.0025 | J | |
| | | VMP-42-20-101212 | 10/12/2012 | <0.0063 | U | | <0.012 | U | | <0.014 | U | | 0.035 | | | <0.028 | U | | <0.0047 | U | | <0.01 | U | | <0.0082 | U | | <0.0082 | U | | <0.0082 | U | | 0.0023 | J | |
| | | VMP-42-20-101212-Dup | 10/12/2012 | <0.0064 | U | | <0.012 | U | | <0.014 | U | | 0.036 | | | <0.028 | U | | 0.0011 | J | | <0.011 | U | | <0.0083 | U | | <0.0083 | U | | <0.0083 | U | | 0.0023 | J | |
| | | VMP-42-20-013113 | 1/31/2013 | <0.0059 | U | | <0.011 | U | | <0.014 | U | | 0.025 | | | <0.027 | U | | <0.0044 | U | | <0.0099 | U | | <0.0078 | U | | <0.0078 | U | | <0.0078 | U | | 0.002 | J | |
| | 30 ft | VMP-42-30-041912 | 4/19/2012 | <4.3 | U | | <8 | U | | <9.9 | U | | <4.6 | U | | <7.7 | U | | 22 | | | <7.2 | U | | <5.6 | U | | <5.6 | U | | <5.6 | U | | <4.6 | U | |
| | | VMP-42-30-071912 | 7/19/2012 | <0.004 | U | | <0.0074 | U | | <0.0092 | U | | <0.0043 | U | | <0.018 | U | | 0.23 | | J | <0.0067 | U | | <0.0053 | U | | <0.0053 | U | | <0.0053 | U | | 0.0029 | J | J |
| | | VMP-42-30-101212 | 10/12/2012 | <0.0066 | U | | <0.012 | U | | <0.015 | U | | 0.005 | J | | 0.0085 | J | | 0.009 | | | <0.011 | U | | <0.0087 | U | | <0.0087 | U | | <0.0087 | U | | 0.0022 | J | |
| | | VMP-42-30-101212-Dup | 10/12/2012 | <0.0066 | U | | <0.012 | U | | <0.015 | U | | 0.0051 | J | | 0.0091 | J | | 0.0093 | | | <0.011 | U | | <0.0087 | U | | <0.0087 | U | | <0.0087 | U | | 0.0024 | J | |
| | | VMP-42-30-013113 | 1/31/2013 | <0.0064 | U | | <0.012 | U | | <0.014 | U | | 0.0079 | | | <0.028 | U | | 0.0022 | J | | <0.011 | U | | <0.0083 | U | | <0.0083 | U | | <0.0083 | U | | 0.002 | J | |
| VMP-43 | 10 ft | VMP-43-10-041612 | 4/16/2012 | <0.0045 | U | | <0.0083 | U | | <0.01 | U | | <0.0048 | U | | 0.0024 | J | | 0.011 | | | <0.0075 | U | | <0.0059 | U | | <0.0059 | U | | <0.0059 | J | U | 0.0025 | J | |
| | | VMP-43-10-071912 | 7/19/2012 | <0.0086 | U | | <0.016 | U | | <0.02 | U | | 0.0018 | J | | <0.039 | U | | 0.01 | | | <0.014 | U | | <0.011 | U | | <0.011 | U | | <0.011 | U | | 0.0021 | J | |
| | | VMP-43-10-101612 | 10/16/2012 | <0.0073 | U | | <0.014 | U | | <0.017 | U | | <0.0078 | U | | <0.033 | U | | <0.0055 | U | | <0.012 | U | | <0.0096 | U | | <0.0096 | U | | <0.0096 | U | | 0.0022 | J | |
| | 20 ft | VMP-43-20-041612 | 4/16/2012 | <0.044 | U | | <0.081 | U | | <0.1 | U | | <0.047 | U | | <0.079 | U | | 0.55 | | | <0.073 | U | | <0.057 | U | | <0.057 | U | | <0.057 | U | | <0.047 | U | |
| | | VMP-43-20-071912 | 7/19/2012 | <0.016 | U | | <0.029 | U | | <0.036 | U | | 0.0031 | J | | <0.071 | U | | 0.0097 | J | | <0.026 | U | | <0.021 | U | | <0.021 | U | | <0.021 | U | | 0.0046 | J | |
| | | VMP-43-20-101812 | 10/18/2012 | <0.0061 | U | | <0.011 | U | | <0.014 | U | | 0.0053 | J | | <0.027 | U | | <0.0045 | U | | <0.01 | U | | <0.0079 | U | | <0.0079 | U | | <0.0079 | U | | 0.0031 | J | |
| | | VMP-43-20-012413 | 1/24/2013 | <0.0061 | U | | <0.011 | U | | <0.014 | U | | 0.0022 | J | | <0.027 | U | | <0.0045 | U | | <0.01 | U | | <0.0079 | U | | <0.0079 | U | | <0.0079 | U | | 0.0031 | J | |
| | 30 ft | VMP-43-30-042312 | 4/23/2012 | <0.04 | U | | <0.074 | U | | <0.092 | U | | <0.043 | U | | <0.072 | U | | 0.0054 | J | | <0.067 | U | | <0.053 | U | | <0.053 | U | | <0.053 | U | | <0.043 | U | |
| | | VMP-43-30-071912 | 7/19/2012 | <0.0044 | U | | <0.0081 | U | | <0.01 | U | | 0.0017 | J | | <0.02 | J | U | 0.0052 | | | <0.0073 | U | | <0.0057 | U | | 0.0011 | J | | 0.003 | J | | | | |
| | | VMP-43-30-101812 | 10/18/2012 | <0.0064 | U | | <0.012 | U | | <0.014 | U | | 0.0082 | | | <0.028 | U | | 0.0025 | J | | <0.011 | U | | <0.0083 | U | | <0.0083 | U | | 0.0025 | J | | | | |
| | | VMP-43-30-012413 | 1/24/2013 | <0.0062 | U | | <0.011 | U | | <0.014 | U | | <0.0066 | U | | <0.028 | U | | <0.0046 | U | | <0.01 | U | | <0.0081 | U | | <0.0081 | U | | 0.0026 | J | | | | |
| VMP-44 | 10 ft | VMP-44-10-041912 | 4/19/2012 | <2.1 | U | | <3.9 | U | | <4.8 | U | | <2.2 | U | | <3.8 | U | | 220 | | | <3.5 | U | | <2.8 | U | | <2.8 | U | | <2.8 | U | | <2.3 | U | |
| | | VMP-44-10-072012 | 7/20/2012 | <0.71 | U | | <1.3 | U | | <1.6 | U | | <0.75 | U | | <1.3 | U | | <0.53 | U | | <1.2 | U | | <0.92 | U | | <0.92 | U | | <0.92 | U | | <0.76 | U | |
| | | VMP-44-10-081012 | 8/10/2012 | <0.42 | U | | <0.78 | U | | <0.96 | U | | <0.45 | U | | <0.76 | U | | <0.31 | U | | <0.7 | U | | <0.55 | U | | <0.55 | U | | <0.55 | U | | <0.45 | U | |
| | | VMP-44-10-101212 | 10/12/2012 | <1.3 | U | | <2.4 | U | | <3 | U | | <1.4 | U | | <2.3 | U | | 13 | | | <2.2 | U | | <1.7 | U | | <1.7 | U | | <1.7 | U | | <1.4 | U | |
| | | VMP-44-10-012513 | 1/25/2013 | <0.53 | U | | <0.98 | U | | <1.2 | U | | <0.56 | U | | <0.95 | U | | 9.3 | | | <0.88 | U | | <0.69 | U | | <0.69 | U | | <0.69 | U | | <0.57 | U | |
| | 20 ft | VMP-44-20-041912 | 4/19/2012 | <0.46 | U | | <0.86 | U | | <1.1 | U | | <0.49 | U | | <0.83 | U | | 110 | | | <0.77 | U | | <0.6 | U | | <0.6 | U | | <0.6 | U | | <0.5 | U | |
| | | VMP-44-20-072512 | 7/25/2012 | <0.79 | U | | <1.5 | U | | <1.8 | U | | <0.84 | U | | <1.4 | U | | 120 | | J | <1.3 | U | | <1 | U | | <1 | U | | <1 | U | | <0.85 | U | |
| | | VMP-44-20-101212 | 10/12/2012 | <2.6 | U | | <4.8 | U | | <6 | U | | <2.8 | U | | <4.7 | U | | 29 | | | <4.4 | U | | <3.4 | U | | <3.4 | U | | <3.4 | U | | <2.8 | U | |
| | | VMP-44-20-012513 | 1/25/2013 | <0.19 | U | | <0.35 | U | | <0.44 | U | | <0.2 | U | | <0.34 | U | | 3.2 | | | <0.32 | U | | <0.25 | U | | <0.25 | U | | <0.25 | U | | <0.2 | U | |
| | 30 ft | VMP-44-30-041912 | 4/19/2012 | <0.27 | U | | <0.5 | U | | <0.62 | U | | <0.28 | U | | <0.48 | U | | 13 | | | <0.45 | U | | <0.35 | U | | <0.35 | U | | <0.35 | U | | <0.29 | U | |
| | | VMP-44-30-072512 | 7/25/2012 | <0.045 | U | | <0.083 | U | | <0.1 | U | | <0.048 | U | | <0.081 | U | | 2.1 | | | <0.075 | U | | <0.059 | U | | <0.059 | U | | <0.059 | U | | <0.048 | U | |
| | | VMP-44-30-072512-Dup | 7/25/2012 | <0.045 | U | | <0.083 | U | | <0.1 | U | | <0.048 | U | | <0.081 | U | | 2.1 | | | <0.075 | U | | <0.059 | U | | <0.059 | U | | <0.059 | U | | <0.048 | U | |
| | | VMP-44-30-101512 | 10/15/2012 | <0.28 | U | | <0.52 | U | | <0.64 | U | | <0.3 | U | | <1.2 | U | | 5.9 | | | <0.46 | U | | <0.36 | U | | <0.36 | U | | <0.36 | U | | <0.3 | U | |
| | | VMP-44-30-101512-Dup | 10/15/2012 | <0.26 | U | | <0.48 | U | | <0.6 | U | | <0.28 | U | | <1.2 | U | | 5.7 | | | <0.43 | U | | <0.34 | U | | <0.34 | U | | <0.34 | U | | <0.28 | U | |
| | | VMP-44-30-012513 | 1/25/2013 | <0.067 | U | UJ | <0.12 | U | UJ | <0.15 | U | UJ | <0.071 | U | UJ | <0.12 | U | UJ | 0.022 | J | J | <0.11 | U | UJ | <0.087 | U | UJ | <0.087 | U | UJ | <0.087 | U | UJ | <0.072 | U | UJ |
| VMP-45 | 10 ft | VMP-45-10-041912 | 4/19/2012 | <0.0042 | U | | <0.0078 | U | | <0.0096 | U | | <0.0045 | U | | <0.019 | U | | 0.0012 | J | | <0.007 | U | | <0.0055 | U | | <0.0055 | U | | <0.0055 | U | | 0.0028 | J | |
| | | VMP-45-10-071912 | 7/19/2012 | <0.0043 | U | | <0.008 | U | | <0.0099 | U | | 0.0022 | J | | <0.019 | J | U | 0.0018 | J | | <0.0072 | U | | <0.0056 | U | | <0.0056 | U | | <0.0056 | U | | 0.0026 | J | |
| | | VMP-45-10-101512 | 10/15/2012 | <0.0067 | U | | <0.012 | U | | <0.015 | U | | 0.0052 | J | | <0.03 | U | | 0.00093 | J | | <0.011 | U | | <0.0087 | U | | <0.0087 | U | | <0.0087 | U | | 0.0021 | J | |
| | | VMP-45-10-013013 | 1/30/2013 | <0.0058 | U | | <0.011 | U | | <0.013 | U | | <0.0062 | U | | <0.026 | U | | <0.0043 | U | | <0.0097 | U | | <0.0076 | U | | <0.0076 | U | | <0.0076 | U | | 0.0022 | J | |
| | 20 ft | VMP-45-20-041912 | 4/19/2012 | <0.26 | U | | <0.48 | U | | <0.6 | U | | <0.28 | U | | <0.47 | U | | 2.4 | | | <0.44 | U | | <0.34 | U | | <0.34 | U | | <0.34 | U | | <0.28 | U | |
| | | VMP-45-20-071912 | 7/19/2012 | <0.082 | U | | <0.15 | U | | <0.19 | U | | 0.013 | J | | <0.37 | U | | 0.22 | | | <0.14 | U | | <0.11 | U | | <0.11 | U | | <0.11 | U | | <0.088 | U | |
| | | VMP-45-20-101512 | 10/15/2012 | <0.0064 | U | | <0.012 | U | | <0.014 | U | | 0.016 | | | <0.028 | U | | 0.0064 | | | <0.011 | U | | <0.0083 | U | | <0.0083 | U | | <0.0083 | U | | 0.0023 | J | |
| | | VMP-45-20-013013 | 1/30/2013 | <0.0061 | U | | <0.011 | U | | <0.014 | U | | 0.011 | | | <0.027 | U | | <0.0045 | U | | <0.01 | U | | <0.0079 | U | | <0.0079 | U | | <0.0079 | U | | 0.0024 | J | |
| | 30 ft | VMP-45-30-041912 | 4/19/2012 | <0.18 | U | | <0.32 | U | | <0.4 | U | | <0.19 | U | | <0.32 | U | | 3.4 | | J | <0.29 | U | | <0.23 | U | | <0.23 | U | | <0.23 | U | | <0.19 | U | |
| | | VMP-45-30-071912 | 7/19/2012 | <0.044 | U | | <0.081 | U | | <0.1 | U | | <0.047 | U | | <0.079 | U | | 0.072 | | | <0.073 | U | | <0.057 | U | | <0.057 | U | | <0.057 | U | | <0.047 | U | |
| | | VMP-45-30-101512 | 10/15/2012 | <0.0064 | U | | <0.012 | U | | <0.014 | U | | 0.02 | | | <0.028 | U | | 0.0071 | | | <0.011 | U | | <0.0083 | U | | <0.0083 | U | | <0.0083 | J | U | 0.0025 | J | |
| | | VMP-45-30-101512-Dup | 10/15/2012 | <0.0063 | U | | <0.012 | U | | <0.014 | U | | 0.021 | | | <0.028 | U | | 0.0075 | | | <0.01 | U | | <0.0082 | U | | <0.0082 | U | | <0.0082 | U | | 0.003 | J | |
| | | VMP-45-30-013013 | 1/30/2013 | <0.011 | U | | <0.021 | U | | <0.026 | U | | 0.0086 | J | | <0.05 | U | | <0.0083 | U | | <0.018 | U | | <0.014 | U | | <0.014 | U | | <0.014 | U | | 0.0018 | J | |

SEE LAST PAGE OF TABLE FOR NOTES

**TABLE 5**
**CUMULATIVE SUMMARY OF SOIL VAPOR ANALYTICAL DETECTIONS AND SCREENING RESULTS: VILLAGE - VOCS**

| Location | Depth | Sample ID | Sample Date | Chlorobenzene | | | Chlorodibromomethane | | | Chloroethane | | | Chloroform | | | Chloromethane | | | Cyclohexane | | | 1,2-Dibromoethane | | | 1,2-Dichlorobenzene | | | 1,3-Dichlorobenzene | | | 1,4-Dichlorobenzene | | | Dichlorodifluoromethane | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | 69 | | | 57000 | | | | | | 0.11 | | | | | | | | | 0.011 | | | 290 | | | | | | 1200 | | | | | |
| | | | | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals |
| VMP-47 | 5 ft | VMP-47-5-012113 | 1/21/2013 | <0.0066 | U | | <0.012 | U | | <0.015 | U | | <0.007 | U | | <0.03 | U | | 0.0025 | J | | <0.011 | U | | <0.0087 | U | | 0.0015 | J | | 0.0022 | J | | 0.003 | J | |
| | | [4]VMP-47-5-012313-R | 1/23/2013 | <22 | U | | <41 | U | | <51 | U | | <24 | U | | <40 | U | | 33 | | | <37 | U | | <29 | U | | <29 | U | | <29 | U | | <24 | U | |
| | 10 ft | VMP-47-10-012113 | 1/21/2013 | <0.0064 | U | | <0.012 | U | | <0.014 | U | | <0.0067 | U | | <0.028 | U | | <0.0048 | U | | <0.011 | U | | <0.0083 | U | | <0.0083 | J | U | <0.0083 | J | | 0.0035 | J | |
| | | [4]VMP-47-10-012313-R | 1/23/2013 | <0.56 | U | | <1 | U | | <1.3 | U | | <0.59 | U | | <1 | U | | 3.5 | | | <0.93 | U | | <0.73 | U | | <0.73 | U | | <0.73 | U | | <0.6 | U | |
| | 20 ft | VMP-47-20-012113 | 1/21/2013 | <5.8 | U | | <11 | U | | <13 | U | | <6.2 | U | | <10 | U | | <4.3 | U | | <9.7 | U | | <7.6 | U | | <7.6 | U | | <7.6 | U | | <6.2 | U | |
| | | [4]VMP-47-20-012313-R | 1/23/2013 | <14 | U | | <25 | U | | <31 | U | | <14 | U | | <24 | U | | 27 | | | <23 | U | | <18 | U | | <18 | U | | <18 | U | | <15 | U | |
| | 30 ft | VMP-47-30-012113 | 1/21/2013 | <4.2 | U | | <7.8 | U | | <9.7 | U | | <4.5 | U | | <7.6 | U | | <3.2 | U | | <7.1 | U | | <5.5 | U | | <5.5 | U | | <5.5 | U | | <4.5 | U | |
| | | [4]VMP-47-30-012313-R | 1/23/2013 | <22 | U | | <40 | U | | <50 | U | | <23 | U | | <39 | U | | 33 | | | <36 | U | | <29 | U | | <29 | U | | <29 | U | | <24 | U | |
| VMP-48 | 5 ft | VMP-48-5-020113 | 2/1/2013 | <0.0059 | U | | <0.011 | U | | <0.014 | U | | <0.0063 | U | | <0.026 | U | | <0.0044 | U | | <0.0099 | U | | <0.0077 | U | | <0.0077 | U | | <0.0077 | U | | 0.0019 | J | |
| | 10 ft | VMP-48-10-020113 | 2/1/2013 | <0.0061 | U | | <0.011 | U | | <0.014 | U | | 0.0014 | J | | <0.027 | U | | <0.0046 | U | | <0.01 | U | | <0.008 | U | | <0.008 | U | | <0.008 | U | | 0.0024 | J | |
| | 20 ft | VMP-48-20-020113 | 2/1/2013 | <0.0059 | U | | <0.011 | U | | <0.013 | U | | <0.0062 | U | | <0.026 | U | | <0.0044 | U | | <0.0098 | U | | <0.0077 | U | | <0.0077 | U | | <0.0077 | U | | 0.0021 | J | |
| | 30 ft | VMP-48-30-020113 | 2/1/2013 | <0.006 | U | | <0.011 | U | | <0.014 | U | | <0.0064 | U | | <0.027 | U | | <0.0045 | U | | <0.01 | U | | <0.0078 | U | | <0.0078 | U | | <0.0078 | U | | 0.0031 | J | J |
| | | VMP-48-30-020113-DUP | 2/1/2013 | <0.024 | U | | <0.044 | U | | <0.055 | U | | <0.025 | U | | <0.11 | U | | <0.018 | U | | <0.04 | U | | <0.031 | U | | <0.031 | U | | <0.031 | U | | <0.026 | U | UJ |
| VMP-49 | 5 ft | VMP-49-5-020113 | 2/1/2013 | <0.0062 | U | | <0.011 | U | | <0.014 | U | | <0.0066 | U | | <0.028 | U | | <0.0046 | U | | <0.01 | U | | <0.0081 | U | | <0.0081 | U | | <0.0081 | U | | 0.0021 | J | |
| | 10 ft | VMP-49-10-020113 | 2/1/2013 | <0.0061 | U | | <0.011 | U | | <0.014 | U | | <0.0064 | U | | <0.027 | U | | <0.0045 | U | | <0.01 | U | | <0.0079 | U | | <0.0079 | U | | <0.0079 | U | | 0.0021 | J | |
| | 20 ft | VMP-49-20-020113 | 2/1/2013 | <0.0059 | U | | <0.011 | U | | <0.014 | U | | <0.0063 | U | | <0.027 | U | | <0.0044 | U | | <0.0099 | U | | <0.0078 | U | | <0.0078 | U | | <0.0078 | U | | 0.0024 | J | |
| | 30 ft | VMP-49-30-020113 | 2/1/2013 | <0.28 | U | | <0.52 | U | | <0.65 | U | | <0.3 | U | | <1.3 | U | | 0.54 | | | <0.47 | U | | <0.37 | U | | <0.37 | U | | <0.37 | U | | <0.3 | U | |
| VMP-50 | 5 ft | VMP-50-5-020113 | 2/1/2013 | <0.0058 | U | | <0.011 | U | | <0.013 | U | | 0.0014 | J | | <0.026 | U | | <0.0043 | U | | <0.0097 | U | | <0.0076 | U | | <0.0076 | J | U | <0.0076 | J | U | 0.0027 | J | |
| | 10 ft | VMP-50-10-020113 | 2/1/2013 | <0.0064 | U | | <0.012 | U | | <0.014 | U | | 0.043 | | | <0.028 | U | | <0.0048 | U | | <0.011 | U | | <0.0083 | U | | <0.0083 | U | | <0.0083 | U | | 0.0022 | J | |
| | 20 ft | VMP-50-20-020113 | 2/1/2013 | <0.025 | U | | <0.046 | U | | <0.056 | U | | <0.026 | U | | <0.11 | U | | 0.16 | | | <0.041 | U | | <0.032 | U | | <0.032 | U | | <0.032 | U | | <0.026 | U | |
| | 30 ft | VMP-50-30-020113 | 2/1/2013 | <6 | U | | <11 | U | | <14 | U | | <6.3 | U | | <27 | U | | 370 | | | <10 | U | | <7.8 | U | | 1 | J | | <7.8 | U | | <6.4 | U | |
| VMP-51 | 5 ft | VMP-51-5-020113 | 2/1/2013 | <0.0063 | U | | <0.012 | U | | <0.014 | U | | 0.0038 | J | | <0.028 | U | | <0.0047 | U | | <0.01 | U | | <0.0082 | U | | <0.0082 | U | | <0.0082 | U | | 0.0021 | J | |
| | 10 ft | VMP-51-10-020113 | 2/1/2013 | <0.0064 | U | | <0.012 | U | | <0.014 | U | | 0.011 | | | <0.028 | U | | <0.0048 | U | | <0.011 | U | | <0.0083 | U | | <0.0083 | U | | <0.0083 | U | | 0.0022 | J | |
| | 20 ft | VMP-51-20-021513-R | 2/15/2013 | <0.0061 | U | | <0.011 | U | | <0.014 | U | | 0.02 | | | <0.027 | U | | 0.0014 | J | | <0.01 | U | | <0.0079 | U | | <0.0079 | J | U | <0.0079 | J | | 0.0026 | J | |
| | 30 ft | VMP-51-30-020413 | 2/4/2013 | <0.0066 | U | | <0.012 | U | | <0.015 | U | | 0.016 | | | <0.03 | U | | 0.0049 | | | <0.011 | U | | <0.0087 | U | | <0.0087 | U | | <0.0087 | U | | 0.002 | J | |
| | | VMP-51-30-020413-DUP | 2/4/2013 | <0.0065 | U | | <0.012 | U | | <0.015 | U | | 0.015 | | | <0.029 | U | | 0.0087 | | | <0.011 | U | | <0.0084 | U | | <0.0084 | U | | <0.0084 | U | | 0.0022 | J | |
| VMP-52 | 5 ft | VMP-52-5-020413 | 2/4/2013 | <0.0058 | U | | <0.011 | U | | <0.013 | U | | <0.0062 | U | | <0.026 | U | | <0.0043 | U | | <0.0097 | U | | <0.0076 | U | | <0.0076 | J | U | <0.0076 | J | U | 0.0024 | J | |
| | 10 ft | VMP-52-10-020413 | 2/4/2013 | <0.0055 | U | | <0.01 | U | | <0.013 | U | | 0.002 | J | | <0.025 | U | | <0.0041 | U | | <0.0092 | U | | <0.0072 | U | | <0.0072 | U | | <0.0072 | U | | 0.0026 | J | |
| | 20 ft | VMP-52-20-020413 | 2/4/2013 | <0.0062 | U | | <0.011 | U | | <0.014 | U | | 0.0025 | J | | <0.028 | U | | 0.023 | | | <0.01 | U | | <0.008 | J | U | <0.008 | J | U | <0.008 | J | U | 0.0028 | J | |
| | | VMP-52-20-020413-DUP | 2/4/2013 | <0.0059 | U | | <0.011 | U | | <0.014 | U | | 0.0023 | J | | <0.026 | U | | 0.018 | | | <0.0099 | U | | <0.0077 | U | | <0.0077 | J | U | <0.0077 | J | U | 0.0022 | J | |
| | 30 ft | VMP-52-30-020413 | 2/4/2013 | <0.0065 | U | | <0.012 | U | | <0.015 | U | | <0.0069 | U | | <0.029 | U | | 0.023 | | | <0.011 | U | | <0.0084 | U | | <0.0084 | U | | <0.0084 | U | | 0.0024 | J | |
| VMP-53 | 5 ft | VMP-53-5-020513 | 2/5/2013 | <0.0059 | U | | <0.011 | U | | <0.014 | U | | <0.0063 | U | | <0.027 | U | | <0.0044 | U | | <0.0099 | U | | <0.0078 | U | | <0.0078 | U | | <0.0078 | U | | 0.0022 | J | |
| | 10 ft | VMP-53-10-020513 | 2/5/2013 | <0.0061 | U | | <0.011 | U | | <0.014 | U | | <0.0064 | U | | <0.027 | U | | 0.0043 | J | | <0.01 | U | | <0.0079 | U | | <0.0079 | U | | <0.0079 | U | | 0.0028 | J | |
| | | VMP-53-10-020513-DUP | 2/5/2013 | <0.0057 | U | | <0.01 | U | | <0.013 | U | | <0.006 | U | | <0.026 | U | | <0.0042 | U | | <0.0095 | U | | <0.0074 | U | | <0.0074 | U | | <0.0074 | U | | 0.0024 | J | |
| | 20 ft | VMP-53-20-020513 | 2/5/2013 | <0.0061 | U | | <0.011 | U | | <0.014 | U | | 0.0051 | J | | <0.027 | U | | <0.0045 | U | | <0.01 | U | | <0.0079 | U | | <0.0079 | U | | <0.0079 | U | | 0.0026 | J | |
| | 30 ft | VMP-53-30-020513 | 2/5/2013 | <0.0062 | U | | <0.011 | U | | <0.014 | U | | 0.012 | | | <0.028 | U | | <0.0046 | U | | <0.01 | U | | <0.0081 | U | | <0.0081 | U | | <0.0081 | U | | 0.0026 | J | |
| VMP-54 | 5 ft | VMP-54-5-020613 | 2/6/2013 | <0.0064 | U | | <0.012 | U | | <0.014 | U | | <0.0067 | U | | <0.028 | U | | 0.0026 | J | | <0.011 | U | | <0.0083 | U | | <0.0083 | U | | <0.0083 | U | | 0.0021 | J | |
| | 10 ft | VMP-54-10-020613 | 2/6/2013 | <0.0065 | U | | <0.012 | U | | <0.015 | U | | <0.0069 | U | | <0.029 | U | | <0.0048 | U | | <0.011 | U | | <0.0085 | U | | <0.0085 | U | | <0.0085 | U | | 0.0028 | J | |
| | 20 ft | VMP-54-20-020613 | 2/6/2013 | <0.0064 | U | | <0.012 | U | | <0.014 | U | | <0.0067 | U | | <0.028 | U | | <0.0048 | U | | <0.011 | U | | <0.0083 | U | | <0.0083 | J | U | <0.0083 | J | U | 0.0028 | J | |
| | | VMP-54-20-020613-DUP | 2/6/2013 | <0.0064 | U | | <0.012 | U | | <0.014 | U | | <0.0067 | U | | <0.028 | U | | 0.0026 | J | | <0.011 | U | | <0.0083 | U | | <0.0083 | J | U | <0.0083 | J | U | 0.0023 | J | |
| | 30 ft | VMP-54-30-020613 | 2/6/2013 | <0.0068 | U | | <0.013 | U | | <0.016 | U | | <0.0072 | U | | <0.03 | U | | <0.0051 | U | | <0.011 | U | | <0.0089 | U | | <0.0089 | U | | <0.0089 | U | | 0.0026 | J | |
| | | VMP-54-30-020613-DUP | 2/6/2013 | <0.0068 | U | | <0.013 | U | | <0.016 | U | | <0.0072 | U | | <0.03 | U | | <0.0051 | U | | <0.011 | U | | <0.0089 | U | | <0.0089 | U | | <0.0089 | U | | 0.0025 | J | |

SEE LAST PAGE OF TABLE FOR NOTES

**TABLE 5**
**CUMULATIVE SUMMARY OF SOIL VAPOR ANALYTICAL DETECTIONS AND SCREENING RESULTS: VILLAGE - VOCS**

| Location | Depth | Sample ID | Sample Date | 1,1-Dichloroethane | | | 1,2-Dichloroethane | | | 1,1-Dichloroethene | | | cis-1,2-Dichloroethene | | | trans-1,2-Dichloroethene | | | Dichloromethane (Methylene chloride) | | | 1,2-Dichloropropane | | | cis-1,3-Dichloropropene | | | trans-1,3-Dichloropropene | | | 1,4-Dioxane | | | Ethanol | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | 690 | | | 0.099 | | | 240 | | | 1100000 | | | 85 | | | 5.6 | | | 0.062 | | | 0.9 | | | 0.9 | | | 0.22 | | | | | |
| | | | | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals |
| VMP-1 | 5 ft | VMP-1-5-082510 | 8/25/2010 | <0.017 | U | | <0.017 | U | | <0.017 | U | | <0.017 | U | | <0.017 | U | | <0.015 | U | | <0.02 | U | | <0.019 | U | | <0.019 | U | | 0.015 | J | | 0.03 | J | |
| | | VMP-1-5-111710 | 11/17/2010 | <0.021 | U | | <0.021 | U | | <0.02 | U | | <0.02 | U | | <0.02 | U | | <0.018 | U | | <0.024 | U | | <0.023 | U | | <0.023 | U | | <0.074 | U | | 0.0087 | J | |
| | | VMP-1-5-020411 | 2/4/2011 | <0.41 | U | | <0.41 | U | | <0.4 | U | | <0.4 | U | | <0.4 | U | | <0.35 | U | | <0.47 | U | | <0.46 | U | | <0.46 | U | | <1.4 | U | | <0.76 | U | |
| | | VMP-1-5-041211 | 4/12/2011 | <0.0053 | U | | <0.0053 | U | | <0.0052 | U | | <0.0052 | U | | <0.0052 | U | | 0.0012 | J | | <0.0061 | U | | <0.006 | U | | <0.006 | U | | <0.019 | U | | <0.0099 | U | |
| | | VMP-1-5-080111 | 8/1/2011 | <0.0053 | U | | <0.0053 | U | | <0.0052 | U | | <0.0052 | U | | <0.0052 | U | | 0.0098 | | | <0.0061 | U | | <0.006 | U | | <0.006 | U | | <0.019 | U | | 0.078 | | |
| | | VMP-1-5-110311 | 11/3/2011 | <14 | U | | <14 | U | | <14 | U | | <14 | U | | <14 | U | | 2.9 | J | | <16 | U | | <16 | U | | <16 | U | | <50 | U | | <26 | U | |
| | | VMP-1-5-013012 | 1/30/2012 | <1.2 | U | | <1.2 | U | | <1.2 | U | | <1.2 | U | | <1.2 | U | | 0.37 | J | J | <1.3 | U | | <1.3 | U | | <1.3 | U | | <4.2 | U | | <2.2 | U | |
| | | VMP-1-5-041312 | 4/13/2012 | <0.0036 | U | | <0.0036 | U | | <0.0035 | U | | <0.0035 | U | | <0.0035 | U | | <0.031 | J | U | <0.0041 | U | | <0.0041 | U | | <0.0041 | U | | <0.013 | U | | 0.02 | | |
| | | VMP-1-5-071612 | 7/16/2012 | <0.0037 | U | | <0.0037 | U | | <0.0036 | U | | <0.0036 | U | | <0.0036 | U | | 0.0028 | J | | <0.0042 | U | | <0.0042 | U | | <0.0042 | U | | <0.013 | U | | 0.16 | | |
| | | VMP-1-5-101112 | 10/11/2012 | <0.0093 | U | | <0.0093 | U | | <0.0091 | U | | <0.0091 | U | | <0.0091 | U | | 0.0025 | J | | <0.011 | U | | <0.01 | U | | <0.01 | U | | <0.033 | UJ | UJ | 0.0033 | J | J |
| | | [A]VMP-1-5-012113 | 1/21/2013 | <0.1 | U | | <0.1 | U | | <0.1 | U | | <0.1 | U | | <0.1 | U | | <0.9 | U | | <0.12 | U | | <0.12 | U | | <0.12 | U | | <0.37 | U | | 0.14 | J | |
| | | [A]VMP-1-5-012313-R | 1/23/2013 | <4.7 | U | | <4.7 | U | | <4.6 | U | | <4.6 | U | | <4.6 | U | | <4 | U | | <5.4 | U | | <5.3 | U | | <5.3 | U | | <17 | U | | <8.8 | U | |
| | 8.5 ft | VMP-1-8.5-082510 | 8/25/2010 | <0.052 | U | | <0.052 | U | | <0.051 | U | | <0.051 | U | | <0.051 | U | | <0.045 | U | | <0.059 | U | | <0.058 | U | | <0.058 | U | | <0.18 | U | | <0.097 | U | |
| | | VMP-1-8.5-111710 | 11/17/2010 | <0.01 | U | | <0.01 | U | | <0.0098 | U | | <0.0098 | U | | <0.0098 | U | | <0.0086 | U | | <0.011 | U | | <0.011 | U | | <0.011 | U | | <0.036 | U | | 0.011 | J | |
| | | VMP-1-8.5-111710-Dup | 11/17/2010 | <0.01 | U | | <0.01 | U | | <0.0098 | U | | <0.0098 | U | | <0.0098 | U | | <0.0086 | U | | <0.011 | U | | <0.011 | U | | <0.011 | U | | <0.036 | U | | 0.009 | J | |
| | | VMP-1-8.5-020411 | 2/4/2011 | <0.8 | U | | <0.8 | U | | <0.79 | U | | <0.79 | U | | <0.79 | U | | <0.69 | U | | <0.92 | U | | <0.9 | U | | <0.9 | U | | <2.9 | U | | 2.1 | | |
| | | VMP-1-8.5-041211 | 4/12/2011 | <0.007 | U | | 0.0012 | J | | <0.0069 | U | | <0.0069 | U | | <0.0069 | U | | <0.006 | U | | <0.008 | U | | <0.0079 | U | | <0.0079 | U | | <0.025 | U | | <0.013 | J | U |
| | | VMP-1-8.5-080111 | 8/1/2011 | <2.9 | U | | <2.9 | U | | <2.8 | U | | <2.8 | U | | <2.8 | U | | <2.5 | U | | <3.3 | U | | <3.3 | U | | <3.3 | U | | <10 | U | | <5.4 | U | |
| | | VMP-1-8.5-080111-Dup | 8/1/2011 | <2.8 | U | | <2.8 | U | | <2.8 | U | | <2.8 | U | | <2.8 | U | | <2.4 | U | | <3.2 | U | | <3.2 | U | | <3.2 | U | | <10 | U | | <5.3 | U | |
| | | VMP-1-8.5-110311 | 11/3/2011 | <32 | U | | <32 | U | | <32 | U | | <32 | U | | <32 | U | | <28 | U | | <37 | U | | <36 | U | | <36 | U | | <120 | U | | <61 | U | |
| | | VMP-1-8.5-013012 | 1/30/2012 | <7.1 | U | | <7.1 | U | | <6.9 | U | | <6.9 | U | | <6.9 | U | | 1.9 | J | | <8.1 | U | | <7.9 | U | | <7.9 | U | | <25 | U | | <13 | U | |
| | | VMP-1-8.5-041612 | 4/16/2012 | <0.0043 | U | | 0.0035 | J | | <0.0042 | U | | <0.0042 | U | | <0.0042 | U | | <0.037 | J | U | <0.0049 | U | | <0.0048 | U | | 0.0018 | J | | <0.015 | U | | 0.0089 | | J |
| | | VMP-1-8.5-041612-Dup | 4/16/2012 | <0.0042 | U | | 0.0015 | J | | <0.0041 | U | | <0.0041 | U | | <0.0041 | U | | <0.036 | J | U | <0.0048 | U | | <0.0047 | U | | 0.0014 | J | | <0.015 | U | | 0.013 | | J |
| | | VMP-1-8.5-071612 | 7/16/2012 | <0.0037 | U | | <0.0037 | U | | <0.0036 | U | | <0.0036 | U | | <0.0036 | U | | <0.032 | J | U | <0.0042 | U | | <0.0042 | U | | <0.0042 | U | | <0.013 | U | | 0.13 | | |
| | | VMP-1-8.5-101112 | 10/11/2012 | <0.0057 | U | | <0.0057 | U | | <0.0056 | U | | <0.0056 | U | | <0.0056 | U | | <0.049 | J | U | <0.0065 | U | | <0.0064 | U | | <0.0064 | U | | <0.02 | UJ | UJ | 0.0026 | J | J |
| | | [A]VMP-1-8.5-012113 | 1/21/2013 | <0.1 | U | | <0.1 | U | | <0.099 | U | | <0.099 | U | | <0.099 | U | | <0.87 | U | | <0.12 | U | | <0.11 | U | | <0.11 | U | | <0.36 | U | | <0.19 | U | |
| | | [A]VMP-1-8.5-012313-R | 1/23/2013 | <0.094 | U | | <0.094 | U | | <0.092 | U | | <0.092 | U | | <0.092 | U | | <0.081 | U | | <0.11 | U | | <0.1 | U | | <0.1 | U | | <0.34 | U | | <0.18 | U | |
| | 23.5 ft | VMP - 1 - 23.5 - 083010 | 8/30/2010 | <1.8 | U | | <1.8 | U | | <1.8 | U | | <1.8 | U | | <1.8 | U | | <1.6 | U | | <2.1 | U | | <2 | U | | <2 | U | | <6.5 | U | | <3.4 | U | |
| | | VMP-1-23.5-111810 | 11/17/2010 | <0.005 | U | | <0.005 | U | | <0.0049 | U | | <0.0049 | U | | <0.0049 | U | | 0.00074 | J | | 0.0014 | J | | <0.0056 | U | | <0.0056 | U | | <0.018 | U | | 0.0087 | J | |
| | | VMP-1-23.5-020411 | 2/4/2011 | <4.7 | U | | <4.7 | U | | <4.6 | U | | <4.6 | U | | <4.6 | U | | <4 | U | | <5.4 | U | | <5.3 | U | | <5.3 | U | | <17 | U | | <8.8 | U | |
| | | VMP-1-23.5-041211 | 4/12/2011 | <7.7 | U | | <7.7 | U | | <7.5 | U | | <7.5 | U | | <7.5 | U | | 2.6 | J | | <8.8 | U | | <8.6 | U | | <8.6 | U | | <27 | U | | 4.9 | J | |
| | | VMP-1-23.5-041211-DUP | 4/12/2011 | <9.7 | U | | <9.7 | U | | <9.5 | U | | <9.5 | U | | <9.5 | U | | 1.5 | J | | <11 | U | | <11 | U | | <11 | U | | <34 | U | | <18 | U | |
| | | VMP-1-23.5-080111 | 8/1/2011 | <52 | U | | <52 | U | | <51 | U | | <51 | U | | <51 | U | | <45 | U | | <60 | U | | <58 | U | | <58 | U | | <180 | U | | <97 | U | |
| | | VMP-1-23.5-110611 | 11/6/2011 | <12 | U | | <12 | U | | <12 | U | | <12 | U | | <12 | U | | 3 | J | | <14 | U | | <14 | U | | <14 | U | | <44 | U | | <23 | U | |
| | | VMP-1-23.5-013112 | 1/31/2012 | <24 | U | | <24 | U | | <24 | U | | <24 | U | | <24 | U | | <21 | U | | <28 | U | | <27 | U | | <27 | U | | <86 | U | | <45 | U | |
| | | VMP-1-23.5-041612 | 4/16/2012 | <1.9 | U | | <1.9 | U | | <1.9 | U | | <1.9 | U | | <1.9 | U | | <1.6 | U | | 3.3 | | | <2.2 | U | | <2.2 | U | | <6.9 | U | | <3.6 | U | |
| | | VMP-1-23.5-071612 | 7/16/2012 | <24 | U | | <24 | U | | <24 | U | | <24 | U | | <24 | U | | <21 | U | | <28 | U | | <27 | U | | <27 | U | | <87 | U | | <45 | U | |
| | | VMP-1-23.5-102412 | 10/24/2012 | <49 | U | | <49 | U | | <48 | U | | <48 | U | | <48 | U | | <42 | U | | <56 | U | | <55 | U | | <55 | U | | <170 | U | | <91 | U | |
| | | [A]VMP-1-23.5-012113 | 1/21/2013 | <0.054 | U | UJ | <0.054 | U | UJ | <0.053 | U | UJ | <0.053 | U | UJ | <0.053 | U | UJ | <0.47 | U | UJ | <0.062 | U | UJ | <0.061 | U | UJ | <0.061 | U | UJ | <0.19 | U | UJ | 0.027 | J | J |
| | | [A]VMP-1-23.5-012313-R | 1/23/2013 | <65 | U | | <65 | U | | <64 | U | | <64 | U | | <64 | U | | <56 | U | | <74 | U | | <73 | U | | <73 | U | | <230 | U | | <120 | U | |
| | 38.5 ft | VMP-1-38.5-073112 | 7/31/2012 | <0.0038 | U | | <0.0038 | U | | <0.0037 | U | | <0.0037 | U | | <0.0037 | U | | <0.032 | J | U | <0.0043 | U | | <0.0042 | U | | <0.0042 | U | | <0.013 | U | | 0.053 | | |
| | | VMP-1-38.5-102612 | 10/26/2012 | <2.6 | U | | <2.6 | U | | <2.6 | U | | <2.6 | U | | <2.6 | U | | 0.22 | J | | <3 | U | | <3 | U | | <3 | U | | <9.4 | U | | <4.9 | U | |
| | | [A]VMP-1-38.5-012113 | 1/21/2013 | <0.036 | U | UJ | <0.036 | U | UJ | <0.035 | U | UJ | <0.035 | U | UJ | <0.035 | U | UJ | <0.3 | U | UJ | <0.041 | U | UJ | <0.04 | U | UJ | <0.04 | U | UJ | <0.13 | U | UJ | <0.066 | U | UJ |
| | | [A]VMP-1-38.5-012313-R | 1/23/2013 | <48 | U | | <48 | U | | <47 | U | | <47 | U | | <47 | U | | <41 | U | | <55 | U | | <54 | U | | <54 | U | | <170 | U | | <90 | U | |
| VMP-2 | 5 ft | VMP - 2 - 5 - 083110 | 8/31/2010 | <1.8 | U | | <1.8 | U | | <1.8 | U | | <1.8 | U | | <1.8 | U | | <1.6 | U | | <2.1 | U | | <2 | U | | <2 | U | | <6.5 | U | | <3.4 | U | |
| | | VMP-2-5-111610 | 11/16/2010 | <2.7 | U | | <2.7 | U | | <2.6 | U | | <2.6 | U | | <2.6 | U | | <2.3 | U | | <3 | U | | <3 | U | | <3 | U | | <9.5 | U | | <5 | U | |
| | | VMP-2-5-020411 | 2/4/2011 | <0.7 | U | | <0.7 | U | | <0.68 | U | | <0.68 | U | | <0.68 | U | | <0.6 | U | | <0.8 | U | | <0.78 | U | | <0.78 | U | | <2.5 | U | | <1.3 | U | |
| | | VMP-2-5-041311 | 4/13/2011 | <0.0056 | U | | <0.0056 | U | | <0.0055 | U | | <0.0055 | U | | <0.0055 | U | | 0.00083 | J | | <0.0064 | U | | <0.0063 | U | | <0.0063 | U | | <0.02 | U | | 0.0071 | J | |
| | | VMP-2-5-080211 | 8/2/2011 | <5.8 | U | | <5.8 | U | | <5.7 | U | | <5.7 | U | | <5.7 | U | | <5 | U | | <6.7 | U | | <6.6 | U | | <6.6 | U | | <21 | U | | <11 | U | |
| | | VMP-2-5-110711 | 11/7/2011 | <0.0035 | U | | <0.0035 | U | | <0.0034 | U | | <0.0034 | U | | <0.0034 | U | | 0.0012 | J | | 0.0005 | J | | <0.0039 | U | | <0.0039 | U | | <0.012 | U | | 0.036 | | |
| | | VMP-2-5-012512 | 1/25/2012 | <0.39 | U | | <0.39 | U | | <0.38 | U | | <0.38 | U | | <0.38 | U | | 1 | | | <0.45 | U | | <0.44 | U | | <0.44 | U | | <1.4 | U | | 0.93 | | |
| | | VMP-2-5-042512 | 4/25/2012 | <0.015 | U | | <0.015 | U | | <0.015 | U | | <0.015 | U | | <0.015 | U | | <0.13 | U | | <0.018 | U | | <0.017 | U | | <0.017 | U | | <0.055 | U | | 0.1 | | |
| | | VMP-2-5-071612 | 7/16/2012 | <0.0038 | U | | <0.0038 | U | | <0.0037 | U | | <0.0037 | U | | <0.0037 | U | | 0.0022 | J | | <0.0043 | U | | <0.0042 | U | | <0.0042 | U | | 0.016 | | | 0.14 | | |
| | | VMP-2-5-102412 | 10/24/2012 | <0.0058 | U | | <0.0058 | U | | <0.0057 | U | | <0.0057 | U | | <0.0057 | U | | <0.05 | J | U | <0.0066 | U | | <0.0065 | U | | <0.0065 | U | | <0.021 | U | | 0.073 | | |
| | | VMP-2-5-013113 | 1/31/2013 | <0.0056 | U | | <0.0056 | U | | <0.0055 | U | | <0.0055 | U | | <0.0055 | U | | <0.048 | U | | <0.0064 | U | | <0.0063 | U | | <0.0063 | U | | <0.02 | U | | 0.004 | J | |
| | 8.5 ft | VMP-2-8.5-083110 | 8/31/2010 | <1.9 | U | | <1.9 | U | | <1.8 | U | | <1.8 | U | | <1.8 | U | | <1.6 | U | | <2.1 | U | | <2.1 | U | | <2.1 | U | | <6.6 | U | | <3.5 | U | |
| | | VMP-2-8.5-111610 | 11/16/2010 | <5.1 | U | | <5.1 | U | | <5 | U | | <5 | U | | <5 | U | | <4.4 | U | | <5.8 | U | | <5.7 | U | | <5.7 | U | | <18 | U | | <9.5 | U | |
| | | VMP-2-8.5-020411 | 2/4/2011 | <1.7 | U | | <1.7 | U | | <1.7 | U | | <1.7 | U | | <1.7 | U | | <1.5 | U | | <2 | U | | <2 | U | | <2 | U | | <6.2 | U | | <3.2 | U | |
| | | VMP-2-8.5-041311 | 4/13/2011 | <0.53 | U | | 0.1 | J | | 0.076 | J | | <0.52 | U | | <0.52 | U | | <0.46 | U | | <0.61 | U | | <0.6 | U | | <0.6 | U | | <1.9 | U | | <0.99 | U | |
| | | VMP-2-8.5-080211 | 8/2/2011 | <21 | U | | <21 | U | | <21 | U | | <21 | U | | <21 | U | | <18 | U | | <24 | U | | <24 | U | | <24 | U | | <76 | U | | <40 | U | |
| | | VMP-2-8.5-110711 | 11/7/2011 | <0.046 | U | | <0.046 | U | | <0.045 | U | | <0.045 | U | | <0.045 | U | | <0.04 | U | | <0.053 | U | | <0.052 | U | | <0.052 | U | | <0.16 | U | | 0.035 | J | |
| | | VMP-2-8.5-012612 | 1/26/2012 | <2 | U | | <2 | U | | <2 | U | | <2 | U | | <2 | U | | <1.8 | U | | <2.3 | U | | <2.3 | U | | <2.3 | U | | <7.3 | U | | <3.8 | U | |
| | | VMP-2-8.5-012612-DUP | 1/26/2012 | <2 | U | | <2 | U | | <2 | U | | <2 | U | | <2 | U | | <1.8 | U | | <2.3 | U | | <2.3 | U | | <2.3 | U | | <7.3 | U | | <3.8 | U | |
| | | VMP-2-8.5-041612 | 4/16/2012 | <0.004 | U | | 0.0013 | J | | <0.0039 | U | | <0.0039 | U | | <0.0039 | U | | <0.034 | J | U | <0.0045 | U | | <0.0044 | U | | <0.0044 | U | | <0.014 | U | | 0.012 | | J |
| | | VMP-2-8.5-041612-Dup | 4/16/2012 | <0.0041 | U | | 0.0011 | J | | <0.004 | U | | <0.004 | U | | <0.004 | U | | <0.035 | J | U | <0.0046 | U | | <0.0046 | U | | 0.0013 | J | | <0.014 | U | | 0.0094 | | J |
| | | VMP-2-8.5-071612 | 7/16/2012 | <0.0045 | U | | 0.0006 | J | | <0.0044 | U | | <0.0044 | U | | <0.0044 | J | U | <0.039 | J | U | <0.0052 | U | | <0.0051 | J | U | 0.002 | J | | <0.016 | U | | 0.12 | | |
| | | VMP-2-8.5-071612-Dup | 7/16/2012 | <0.0037 | U | | <0.0037 | U | | <0.0036 | U | | <0.0036 | U | | <0.0036 | U | | 0.0022 | J | | <0.0042 | U | | <0.0042 | U | | <0.0042 | U | | <0.013 | U | | 0.1 | | |
| | | VMP-2-8.5-102312 | 10/23/2012 | <0.0059 | U | | <0.0059 | U | | <0.0058 | U | | <0.0058 | U | | <0.0058 | U | | <0.05 | U | | <0.0067 | U | | <0.0066 | U | | <0.0066 | U | | <0.021 | U | | 0.011 | | |
| | | VMP-2-8.5-020513 | 2/5/2013 | <0.006 | U | | <0.006 | U | | <0.0059 | U | | <0.0059 | U | | <0.0059 | U | | <0.051 | J | U | <0.0068 | U | | <0.0067 | U | | <0.0067 | U | | <0.021 | U | | 0.0026 | J | |
| | 22 ft | VMP-2-22-083110 | 8/31/2010 | <2.8 | U | | <2.8 | U | | <2.8 | U | | <2.8 | U | | <2.8 | U | | <2.4 | U | | <3.2 | U | | <3.2 | U | | <3.2 | U | | <10 | U | | <5.3 | U | |
| | | VMP-2-22-111610 | 11/16/2010 | <5.3 | U | | <5.3 | U | | <5.2 | U | | <5.2 | U | | <5.2 | U | | <4.6 | U | | <6.1 | U | | <6 | U | | <6 | U | | <19 | U | | <9.9 | U | |
| | | VMP-2-22-020411 | 2/4/2011 | <2.4 | U | | <2.4 | U | | <2.4 | U | | <2.4 | U | | <2.4 | U | | <2.1 | U | | <2.7 | U | | <2.7 | U | | <2.7 | U | | <8.6 | U | | <4.5 | U | |
| | | VMP-2-22-041311 | 4/13/2011 | <7.1 | U | | <7.1 | U | | <6.9 | U | | <6.9 | U | | <6.9 | U | | <6.1 | U | | <8.1 | U | | <7.9 | U | | <7.9 | U | | <25 | U | | <13 | U | |
| | | VMP-2-22-080211 | 8/2/2011 | <28 | U | | <28 | U | | <28 | U | | <28 | U | | <28 | U | | <24 | U | | <32 | U | | <32 | U | | <32 | U | | <100 | U | | <53 | U | |
| | | VMP-2-22-110711 | 11/7/2011 | <1.5 | U | | 0.42 | J | | <1.5 | U | | <1.5 | U | | <1.5 | U | | <1.3 | U | | <1.7 | U | | <1.7 | U | | <1.7 | U | | <5.4 | U | | 0.68 | J | |
| | | VMP-2-22-012612 | 1/26/2012 | <3.1 | U | | <3.1 | U | | <3.1 | U | | <3.1 | U | | <3.1 | U | | <2.7 | U | | <3.6 | U | | <3.5 | U | | <3.5 | U | | <11 | U | | <5.8 | U | |
| | | VMP-2-22-042712 | 4/27/2012 | <0.0032 | U | | <0.0032 | U | | <0.0032 | U | | <0.0032 | U | | <0.0032 | U | | <0.028 | J | U | <0.0037 | U | | <0.0036 | U | | <0.0036 | U | | <0.012 | U | | 0.017 | | |
| | | VMP-2-22-071612 | 7/16/2012 | <0.0038 | U | | <0.0038 | U | | <0.0038 | U | | <0.0038 | U | | <0.0038 | U | | 0.0026 | J | | <0.0044 | U | | <0.0043 | U | | <0.0043 | J | U | <0.014 | U | | 0.28 | | |
| | | VMP-2-22-102312 | 10/23/2012 | <0.0059 | U | | <0.0059 | U | | <0.0058 | U | | <0.0058 | U | | <0.0058 | U | | <0.05 | J | U | <0.0067 | U | | <0.0066 | U | | <0.0066 | U | | <0.021 | U | | 0.012 | | |
| | | VMP-2-22-013113 | 1/31/2013 | <0.0054 | U | | <0.0054 | U | | <0.0053 | U | | <0.0053 | U | | <0.0053 | U | | <0.047 | U | | <0.0062 | U | | <0.0061 | U | | <0.0061 | U | | <0.019 | U | | 0.0042 | J | |
| | 42 ft | VMP-2-42-013113 | 1/31/2013 | <53 | U | | <53 | U | | <52 | U | | <52 | U | | <52 | U | | 80 | J | | <60 | U | | <59 | U | | <59 | U | | <190 | U | | 72 | J | |

SEE LAST PAGE OF TABLE FOR NOTES

**TABLE 5**
**CUMULATIVE SUMMARY OF SOIL VAPOR ANALYTICAL DETECTIONS AND SCREENING RESULTS: VILLAGE - VOCS**

| Location | Depth | Sample ID | Sample Date | 1,1-Dichloroethane | | | 1,2-Dichloroethane | | | 1,1-Dichloroethene | | | cis-1,2-Dichloroethene | | | trans-1,2-Dichloroethene | | | Dichloromethane (Methylene chloride) | | | 1,2-Dichloropropane | | | cis-1,3-Dichloropropene | | | trans-1,3-Dichloropropene | | | 1,4-Dioxane | | | Ethanol | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | 690 | | | 0.099 | | | 240 | | | 1100000 | | | 85 | | | 5.6 | | | 0.062 | | | 0.9 | | | 0.9 | | | 0.22 | | | | | |
| | | | | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals |
| VMP-3 | 5 ft | VMP-3-5-090910 | 9/9/2010 | <5.4 | U | | <5.4 | U | | <5.3 | U | | <5.3 | U | | <5.3 | U | | <4.6 | U | | <6.1 | U | | <6 | U | | <6 | U | | <19 | U | | <10 | U | |
| | | VMP-3-5-112210 | 11/22/2010 | <5.4 | U | | <5.4 | U | | <5.3 | U | | <5.3 | U | | <5.3 | U | | 14 | | | <6.2 | U | | <6.1 | U | | <6.1 | U | | <19 | U | | <10 | U | |
| | | VMP-3-5-020911 | 2/9/2011 | <2.4 | U | | <2.4 | U | | <2.4 | U | | <2.4 | U | | <2.4 | U | | <2.1 | U | | <2.8 | U | | <2.7 | U | | <2.7 | U | | <8.7 | U | | <4.6 | U | |
| | | VMP-3-5-041411 | 4/14/2011 | <26 | U | | <26 | U | | <26 | U | | <26 | U | | <26 | U | | <22 | U | | <30 | U | | <30 | U | | <30 | U | | <94 | U | | <49 | U | |
| | | VMP-3-5-080211 | 8/2/2011 | <0.0063 | U | | <0.0063 | U | | <0.0062 | U | | <0.0062 | U | | <0.0062 | U | | 0.0018 | J | | <0.0072 | U | | <0.007 | U | | <0.007 | U | | <0.022 | U | | 0.18 | | |
| | | VMP-3-5-110811 | 11/8/2011 | <0.0035 | U | | <0.0035 | U | | <0.0034 | U | | <0.0034 | U | | <0.0034 | U | | 0.003 | | | <0.004 | U | | <0.0039 | U | | <0.0039 | U | | <0.012 | U | | 0.014 | | |
| | | VMP-3-5-110811-DUP | 11/8/2011 | <0.0035 | U | | <0.0035 | U | | <0.0035 | U | | <0.0035 | U | | <0.0035 | U | | 0.001 | J | | <0.004 | U | | <0.004 | U | | <0.004 | U | | <0.013 | U | | 0.016 | | |
| | | VMP-3-5-012712 | 1/27/2012 | <1.8 | U | | <1.8 | U | | <1.7 | U | | <1.7 | U | | <1.7 | U | | 0.68 | J | | <2 | U | | <2 | U | | <2 | U | | <6.3 | U | | <3.3 | U | |
| | | VMP-3-5-041912 | 4/19/2012 | <0.0039 | U | | <0.0039 | J | U | <0.0038 | U | | <0.0038 | U | | <0.0038 | U | | <0.033 | J | U | <0.0044 | U | | <0.0043 | U | | 0.0011 | J | | 0.041 | | | 0.025 | | J |
| | | VMP-3-5-072712 | 7/27/2012 | <0.0041 | U | | <0.0041 | U | | <0.004 | U | | <0.004 | U | | <0.004 | U | | 0.0024 | J | | 0.00081 | J | | <0.0046 | U | | <0.0046 | U | | <0.014 | U | | 0.072 | | |
| | 10 ft | VMP-3-10 | 6/21/2010 | <6.1 | U | | <6.1 | U | | <6 | U | | <6 | U | | <6 | U | | <5.3 | U | | <7 | U | | <6.9 | U | | <6.9 | U | | <22 | U | | <11 | U | |
| | | VMP-3-10-091010 | 9/10/2010 | <17 | U | | <17 | U | | <17 | U | | <17 | U | | <17 | U | | <15 | U | | <20 | U | | <19 | U | | <19 | U | | <61 | U | | <32 | U | |
| | | VMP-3-10-092010 | 9/20/2010 | <12 | U | | <12 | U | | <12 | U | | <12 | U | | <12 | U | | <11 | U | | <14 | U | | <14 | U | | <14 | U | | <45 | U | | <23 | U | |
| | | VMP-3-10-112210 | 11/22/2010 | <5.3 | U | | <5.3 | U | | <5.2 | U | | <5.2 | U | | <5.2 | U | | <4.6 | U | | <6.1 | U | | <6 | U | | <6 | U | | <19 | U | | <9.9 | U | |
| | | VMP-3-10-112210-Dup | 11/22/2010 | <7.4 | U | | <7.4 | U | | <7.3 | U | | <7.3 | U | | <7.3 | U | | <6.4 | U | | <8.5 | U | | <8.4 | U | | <8.4 | U | | <26 | U | | <14 | U | |
| | | VMP-3-10-020811 | 2/8/2011 | <7.8 | U | | <7.8 | U | | <7.7 | U | | <7.7 | U | | <7.7 | U | | <6.7 | U | | <9 | U | | <8.8 | U | | <8.8 | U | | <28 | U | | <15 | U | |
| | | VMP-3-10-041311 | 4/13/2011 | <46 | U | | <46 | U | | <45 | U | | <45 | U | | <45 | U | | <39 | U | | <52 | U | | <51 | U | | <51 | U | | <160 | U | | <85 | U | |
| | | VMP-3-10-080311 | 8/3/2011 | <0.057 | U | | <0.057 | U | | <0.056 | U | | <0.056 | U | | <0.056 | U | | <0.049 | U | | <0.066 | U | | <0.064 | U | | <0.064 | U | | <0.2 | U | | 0.1 | J | |
| | | VMP-3-10-110811 | 11/8/2011 | <0.0047 | U | | <0.0047 | U | | <0.0046 | U | | <0.0046 | U | | <0.0046 | U | | <0.004 | J | U | <0.0054 | U | | <0.0053 | U | | <0.0053 | U | | <0.017 | U | | 0.01 | | |
| | | VMP-3-10-012712 | 1/27/2012 | <0.034 | U | | <0.034 | U | | <0.033 | U | | <0.033 | U | | <0.033 | U | | <0.029 | U | | <0.039 | U | | <0.038 | U | | <0.038 | U | | <0.12 | U | | 0.018 | J | |
| | | VMP-3-10-042012 | 4/20/2012 | <0.0035 | U | | <0.0035 | J | U | <0.0034 | U | | <0.0034 | J | U | 0.0012 | J | | <0.03 | J | U | 0.00088 | J | | <0.0039 | J | U | <0.0039 | J | U | <0.012 | U | | 0.021 | | |
| | | VMP-3-10-072312 | 7/23/2012 | <0.0041 | U | | <0.0041 | U | | <0.004 | U | | <0.004 | U | | <0.004 | U | | 0.0032 | J | | <0.0046 | U | | <0.0046 | U | | <0.0046 | U | | <0.014 | U | | 0.018 | | |
| | | VMP-3-10-101812 | 10/18/2012 | <0.0061 | U | | <0.0061 | U | | <0.006 | U | | <0.006 | U | | <0.006 | U | | <0.053 | U | | <0.007 | U | | <0.0069 | U | | <0.0069 | U | | <0.022 | U | | 0.02 | | |
| | | VMP-3-10-020613 | 2/6/2013 | <0.0057 | U | | <0.0057 | U | | <0.0056 | U | | <0.0056 | U | | <0.0056 | U | | <0.049 | J | U | <0.0065 | U | | <0.0064 | U | | <0.0064 | U | | <0.02 | U | | 0.0023 | J | |
| | 22 ft | VMP-3-22-092010 | 9/20/2010 | <16 | U | | <16 | U | | <16 | U | | <16 | U | | <16 | U | | <14 | U | | <19 | U | | <18 | U | | <18 | U | | <58 | U | | <31 | U | |
| | | VMP-3-22-112210 | 11/22/2010 | <19 | U | | <19 | U | | <18 | U | | <18 | U | | <18 | U | | 19 | | | <22 | U | | <21 | U | | <21 | U | | <67 | U | | <35 | U | |
| | | VMP-3-22-020811 | 2/8/2011 | <9.3 | U | | <9.3 | U | | <9.1 | U | | <9.1 | U | | <9.1 | U | | <8 | U | | <10 | U | | <10 | U | | <10 | U | | <33 | U | | <17 | U | |
| | | VMP-3-22-041511 | 4/15/2011 | <50 | U | | <50 | U | | <49 | U | | <49 | U | | <49 | U | | <43 | U | UJ | <57 | U | | <56 | U | | <56 | U | | <180 | U | | <93 | U | |
| | | VMP-3-22-080611 | 8/6/2011 | <0.08 | U | | <0.08 | U | | <0.078 | U | | <0.078 | U | | <0.078 | U | | <0.069 | U | | <0.091 | U | | <0.09 | U | | <0.09 | U | | <0.28 | U | | 0.16 | | |
| | | VMP-3-22-110811 | 11/8/2011 | <0.0035 | U | | <0.0035 | U | | <0.0035 | U | | <0.0035 | U | | <0.0035 | U | | 0.0021 | J | | <0.004 | U | | <0.004 | U | | <0.004 | U | | <0.013 | U | | 0.12 | | |
| | | VMP-3-22-013012 | 1/30/2012 | <0.014 | U | | <0.014 | U | | <0.014 | U | | <0.014 | U | | <0.014 | U | | <0.012 | U | | <0.016 | U | | <0.016 | U | | <0.016 | U | | 0.013 | J | | <0.026 | U | |
| | | VMP-3-22-042012 | 4/20/2012 | <0.0035 | U | | 0.00068 | J | | <0.0035 | U | | <0.0035 | J | U | <0.0035 | U | | <0.03 | J | U | <0.004 | U | | <0.004 | U | | <0.004 | J | U | <0.013 | U | | 0.022 | | |
| | | VMP-3-22-072312 | 7/23/2012 | <0.004 | U | | <0.004 | U | | <0.0039 | U | | <0.0039 | U | | <0.0039 | U | | 0.0015 | J | | <0.0045 | U | | <0.0044 | U | | <0.0044 | U | | <0.014 | U | | 0.013 | | |
| | | VMP-3-22-101812 | 10/18/2012 | <0.006 | U | | <0.006 | U | | <0.0059 | U | | <0.0059 | U | | <0.0059 | U | | <0.051 | U | | <0.0068 | U | | <0.0067 | U | | <0.0067 | U | | <0.021 | U | | 0.0042 | J | |
| | | VMP-3-22-020613 | 2/6/2013 | <0.0058 | U | | <0.0058 | U | | <0.0057 | U | | <0.0057 | U | | <0.0057 | U | | <0.05 | J | U | <0.0067 | U | | <0.0066 | U | | <0.0066 | U | | <0.021 | U | | 0.0042 | J | |
| | 31.5 ft | VMP-3-31.5-090910 | 9/9/2010 | <31 | U | | <31 | U | | <30 | U | | <30 | U | | <30 | U | | <26 | U | | <35 | U | | <34 | U | | <34 | U | | <110 | U | | <57 | U | |
| | | VMP-3-31.5-112210 | 11/22/2010 | <21 | U | | <21 | U | | <21 | U | | <21 | U | | <21 | U | | <18 | U | | <24 | U | | <24 | U | | <24 | U | | <76 | U | | <40 | U | |
| | | VMP-3-31.5-020911 | 2/9/2011 | <20 | U | | <20 | U | | <20 | U | | <20 | U | | <20 | U | | <18 | U | | <23 | U | | <23 | U | | <23 | U | | <73 | U | | <38 | U | |
| | | VMP-3-31.5-041411 | 4/14/2011 | <170 | U | | <170 | U | | <160 | U | | <160 | U | | <160 | U | | <140 | U | | <190 | U | | <190 | U | | <190 | U | | <600 | U | | <310 | U | |
| | | VMP-3-31.5-041411-DUP | 4/14/2011 | <170 | U | | <170 | U | | <160 | U | | <160 | U | | <160 | U | | <140 | U | | <190 | U | | <190 | U | | <190 | U | | <600 | U | | <310 | U | |
| | | VMP-3-31.5-080211 | 8/2/2011 | <380 | U | | <380 | U | | <370 | U | | <370 | U | | <370 | U | | <330 | U | | <430 | U | | <430 | U | | <430 | U | | <1400 | U | | <710 | U | |
| | | VMP-3-31.5-080211-Dup | 8/2/2011 | <220 | U | | <220 | U | | <220 | U | | <220 | U | | <220 | U | | <190 | U | | <250 | U | | <250 | U | | <250 | U | | <790 | U | | <410 | U | |
| | | VMP-3-31.5-110811 | 11/8/2011 | <8.9 | U | | 6.9 | J | | <8.7 | U | | <8.7 | U | | <8.7 | U | | <7.6 | U | | <10 | U | | <9.9 | U | | <9.9 | U | | <32 | U | | 5.7 | J | |
| | | VMP-3-31.5-012712 | 1/27/2012 | <56 | U | | <56 | U | | <55 | U | | <55 | U | | <55 | U | | 14 | J | J | <64 | U | | <63 | U | | <63 | U | | <200 | U | | <100 | U | |
| | | VMP-3-31.5-041912 | 4/19/2012 | <97 | U | | <97 | U | | <95 | U | | <95 | U | | <95 | U | | <83 | U | | <110 | U | | <110 | U | | <110 | U | | <340 | U | | <180 | U | |
| | | VMP-3-31.5-041912-Dup | 4/19/2012 | <93 | U | | <93 | U | | <91 | U | | <91 | U | | <91 | U | | <80 | U | | <100 | U | | <100 | U | | <100 | U | | <330 | U | | <170 | U | |
| | | VMP-3-31.5-072312 | 7/23/2012 | <23 | U | | <23 | U | | <23 | U | | <23 | U | | <23 | U | | <20 | U | | <26 | U | | <26 | U | | <26 | U | | <82 | U | | <43 | U | |
| | | VMP-3-31.5-101912 | 10/19/2012 | <1.9 | U | | <1.9 | U | | <1.8 | U | | <1.8 | U | | <1.8 | U | | <1.6 | U | | <2.1 | U | | <2.1 | U | | <2.1 | U | | <6.6 | U | | <3.5 | U | |
| | | VMP-3-31.5-020713 | 2/7/2013 | <10 | U | | <10 | U | | <10 | U | | <10 | U | | <10 | U | | <9 | U | | <12 | U | | <12 | U | | <12 | U | | <37 | U | | <19 | U | |
| | 39.5 ft | VMP-3-39-101912 | 10/19/2012 | <190 | U | | <190 | U | | <180 | U | | <180 | U | | <180 | U | | <160 | U | | <210 | U | | <210 | U | | <210 | U | | <660 | U | | <350 | U | |
| | | VMP-3-39-021213 | 2/12/2013 | <53 | U | | <53 | U | | <52 | U | | <52 | U | | <52 | U | | <46 | U | | <61 | U | | <60 | U | | <60 | U | | <190 | U | | <99 | U | |
| VMP-4 | 5 ft | VMP-4-5-082510 | 8/25/2010 | <0.29 | U | | <0.29 | U | | <0.28 | U | | <0.28 | U | | <0.28 | U | | <0.25 | U | | <0.33 | U | | <0.33 | U | | <0.33 | U | | <1 | U | | <0.54 | U | |
| | | VMP-4-5-112210 | 11/22/2010 | <11 | U | | <11 | U | | <11 | U | | <11 | U | | <11 | U | | <9.3 | U | | <12 | U | | <12 | U | | <12 | U | | <39 | U | | <20 | U | |
| | | VMP-4-5-021411 | 2/14/2011 | <0.64 | U | | <0.64 | U | | <0.62 | U | | <0.62 | U | | <0.62 | U | | <0.55 | U | | <0.73 | U | | <0.71 | U | | <0.71 | U | | <2.3 | U | | <1.2 | U | |
| | | VMP-4-5-041911 | 4/19/2011 | <29 | U | | <29 | U | | <29 | U | | <29 | U | | <29 | U | | <25 | U | | <34 | U | | <33 | U | | <33 | U | | <100 | U | | <55 | U | |
| | | VMP-4-5-080311 | 8/3/2011 | <0.063 | U | | <0.063 | U | | <0.062 | U | | <0.062 | U | | <0.062 | U | | <0.054 | U | | <0.072 | U | | <0.07 | U | | <0.07 | U | | <0.22 | U | | 0.22 | | |
| | | VMP-4-5-110911 | 11/9/2011 | <0.0035 | U | | <0.0035 | U | | <0.0034 | U | | <0.0034 | U | | <0.0034 | U | | <0.003 | J | U | <0.004 | U | | <0.0039 | U | | <0.0039 | U | | <0.012 | U | | 0.028 | | |
| | | VMP-4-5-013012 | 1/30/2012 | <0.18 | U | | <0.18 | U | | <0.17 | U | | <0.17 | U | | <0.17 | U | | 0.19 | | J | <0.2 | U | | <0.2 | U | | <0.2 | U | | <0.63 | U | | <0.33 | U | |
| | | VMP-4-5-042512 | 4/25/2012 | <0.0044 | U | | <0.0044 | U | | <0.0043 | U | | <0.0043 | U | | <0.0043 | U | | <0.038 | J | U | <0.005 | U | | <0.0049 | U | | <0.0049 | J | U | <0.016 | U | | 0.089 | | |
| | | VMP-4-5-072512 | 7/25/2012 | <0.0043 | U | | <0.0043 | U | | <0.0042 | U | | <0.0042 | U | | <0.0042 | U | | 0.0026 | J | | <0.0049 | U | | <0.0048 | U | | <0.0048 | U | | <0.015 | U | | 0.095 | | |
| | | VMP-4-5-101812 | 10/18/2012 | <0.0063 | U | | <0.0063 | U | | <0.0062 | U | | <0.0062 | U | | <0.0062 | U | | <0.054 | U | | <0.0072 | U | | <0.007 | U | | <0.007 | U | | <0.022 | U | | 0.041 | | |
| | | VMP-4-5-020713 | 2/7/2013 | <0.005 | U | | <0.005 | U | | <0.0049 | U | | <0.0049 | U | | <0.0049 | U | | 0.0032 | J | | <0.0057 | U | | <0.0056 | U | | <0.0056 | U | | <0.018 | U | | 0.0034 | J | |
| | 12 ft | VMP-4-12-082510 | 8/25/2010 | <5.1 | U | | <5.1 | U | | <5 | U | | <5 | U | | <5 | U | | <4.4 | U | | <5.8 | U | | <5.7 | U | | <5.7 | U | | <18 | U | | <9.5 | U | |
| | | VMP-4-12-112310 | 11/23/2010 | <5.2 | U | | <5.2 | U | | <5.1 | U | | <5.1 | U | | <5.1 | U | | <4.5 | U | | <6 | U | | <5.8 | U | | <5.8 | U | | <18 | U | | <9.7 | U | |
| | | VMP-4-12-021411 | 2/14/2011 | <1.3 | U | | <1.3 | U | | <1.3 | U | | <1.3 | U | | <1.3 | U | | <1.1 | U | | <1.5 | U | | <1.5 | U | | <1.5 | U | | <4.7 | U | | <2.4 | U | |
| | | VMP-4-12-041911 | 4/19/2011 | <25 | U | | <25 | U | | <25 | U | | <25 | U | | <25 | U | | <22 | U | | <29 | U | | <28 | U | | <28 | U | | <90 | U | | <47 | U | |
| | | VMP-4-12-080311 | 8/3/2011 | <2.9 | U | | <2.9 | U | | <2.8 | U | | <2.8 | U | | <2.8 | U | | <2.5 | U | | <3.3 | U | | <3.3 | U | | <3.3 | U | | <10 | U | | <5.4 | U | |
| | | VMP-4-12-080311-Dup | 8/3/2011 | <5.8 | U | | <5.8 | U | | <5.7 | U | | <5.7 | U | | <5.7 | U | | <5 | U | | <6.7 | U | | <6.6 | U | | <6.6 | U | | <21 | U | | <11 | U | |
| | | VMP-4-12-110911 | 11/9/2011 | <0.89 | U | | <0.89 | U | | <0.87 | U | | <0.87 | U | | <0.87 | U | | <0.76 | U | | <1 | U | | <0.99 | U | | <0.99 | U | | <3.2 | U | | <1.6 | U | |
| | | VMP-4-12-013012 | 1/30/2012 | <1.8 | U | | <1.8 | U | | <1.8 | U | | <1.8 | U | | <1.8 | U | | <1.6 | U | | <2.1 | U | | <2 | U | | <2 | U | | <6.4 | U | | <3.4 | U | |
| | | VMP-4-12-041812 | 4/18/2012 | <0.0041 | U | | <0.0041 | J | U | <0.004 | U | | <0.004 | U | | <0.004 | U | | <0.035 | J | U | <0.0046 | U | | <0.0046 | U | | <0.0046 | U | | <0.014 | U | | 0.03 | | J |
| | | VMP-4-12-072312 | 7/23/2012 | <0.02 | U | | <0.02 | U | | <0.019 | U | | <0.019 | U | | <0.019 | U | | <0.17 | U | | <0.022 | U | | <0.022 | U | | <0.022 | U | | <0.07 | U | | 0.06 | | |
| | | VMP-4-12-101812 | 10/18/2012 | <0.0061 | U | | <0.0061 | U | | <0.006 | U | | <0.006 | U | | <0.006 | U | | 0.0064 | J | | <0.007 | U | | <0.0069 | U | | <0.0069 | U | | <0.022 | U | | 0.019 | | |
| | | VMP-4-12-101812-Dup | 10/18/2012 | <0.0063 | U | | <0.0063 | U | | <0.0062 | U | | <0.0062 | U | | <0.0062 | U | | <0.054 | U | | <0.0072 | U | | <0.007 | U | | <0.007 | U | | <0.022 | U | | 0.012 | | |
| | | VMP-4-12-020713 | 2/7/2013 | <0.0054 | U | | <0.0054 | U | | <0.0053 | U | | <0.0053 | U | | <0.0053 | U | | <0.047 | J | U | <0.0062 | U | | <0.0061 | U | | <0.0061 | U | | <0.019 | U | | 0.0031 | J | |
| | | VMP-4-12-020713-DUP | 2/7/2013 | <0.0056 | U | | <0.0056 | U | | <0.0055 | U | | <0.0055 | U | | <0.0055 | U | | <0.048 | U | | <0.0064 | U | | <0.0063 | U | | <0.0063 | U | | <0.02 | U | | 0.0037 | J | |
| | 23.5 ft | VMP - 4 - 23.5 - 083110 | 8/31/2010 | <5.8 | U | | <5.8 | U | | <5.7 | U | | <5.7 | U | | <5.7 | U | | <5 | U | | <6.7 | U | | <6.6 | U | | <6.6 | U | | <21 | U | | <11 | U | |
| | | VMP-4-23.5-112310 | 11/23/2010 | <59 | U | | <59 | U | | <58 | U | | <58 | U | | <58 | U | | <50 | U | | <67 | U | | <66 | U | | <66 | U | | <210 | U | | <110 | U | |
| | | VMP-4-23.5-021411 | 2/14/2011 | <2.1 | U | | <2.1 | U | | <2.1 | U | | <2.1 | U | | <2.1 | U | | <1.8 | U | | <2.4 | U | | <2.4 | U | | <2.4 | U | | <7.6 | U | | <4 | U | |
| | | VMP-4-23.5-042011 | 4/20/2011 | <140 | U | | <140 | U | | <130 | U | | <130 | U | | <130 | U | | <120 | U | | <160 | U | | <150 | U | | <150 | U | | <480 | U | | 65 | J | |
| | | VMP-4-23.5-042011-DUP | 4/20/2011 | <140 | U | | <140 | U | | <130 | U | | <130 | U | | <130 | U | | 53 | J | | <160 | U | | <150 | U | | <150 | U | | <480 | U | | <250 | U | |
| | | VMP-4-23.5-080611 | 8/6/2011 | <5.7 | U | | <5.7 | U | | <5.6 | U | | <5.6 | U | | <5.6 | U | | <4.9 | U | | <6.5 | U | | <6.4 | U | | <6.4 | U | | <20 | U | | <10 | U | |
| | | VMP-4-23.5-110911 | 11/9/2011 | <17 | U | | 13 | J | | <17 | U | | <17 | U | | <17 | U | | <14 | U | | <19 | U | | <19 | U | | <19 | U | | <60 | U | | <32 | U | |
| | | VMP-4-23.5-013012 | 1/30/2012 | <36 | U | | <36 | U | | <35 | U | | <35 | U | | <35 | U | | <31 | U | | <41 | U | | <41 | U | | <41 | U | | <130 | U | | <67 | U | |
| | | VMP-4-23.5-013012-DUP | 1/30/2012 | <25 | U | | <25 | U | | <25 | U | | <25 | U | | <25 | U | | <22 | U | | <29 | U | | <28 | U | | <28 | U | | <90 | U | | <47 | U | |
| | | VMP-4-23.5-041912 | 4/19/2012 | <7.9 | U | | <7.9 | U | | <7.8 | U | | <7.8 | U | | <7.8 | U | | <6.8 | U | | <9 | U | | <8.9 | U | | <8.9 | U | | <28 | U | | <15 | U | |
| | | VMP-4-23.5-072312 | 7/23/2012 | <3.8 | U | | <3.8 | U | | <3.7 | U | | <3.7 | U | | <3.7 | U | | <3.3 | U | | <4.3 | U | | <4.3 | U | | <4.3 | U | | <14 | U | | <7.1 | U | |
| | | VMP-4-23.5-101812 | 10/18/2012 | <4.2 | U | | <4.2 | U | | <4.1 | U | | <4.1 | U | | <4.1 | U | | <3.6 | U | | <4.8 | U | | <4.7 | U | | <4.7 | U | | <15 | U | | <7.8 | U | |
| | | VMP-4-23.5-020713 | 2/7/2013 | <1.3 | U | | <1.3 | U | | <1.3 | U | | <1.3 | U | | <1.3 | U | | <1.1 | U | | <1.5 | U | | <1.5 | U | | <1.5 | U | | <4.8 | U | | <2.5 | U | |
| | 39 ft | VMP-4-39-042111 | 4/21/2011 | <170 | U | | <170 | U | | <170 | U | | <170 | U | | <170 | U | | <140 | U | | <190 | U | | <190 | U | | <190 | U | | <600 | U | | <320 | U | |
| | | VMP-4-39-041912 | 4/19/2012 | <4.1 | U | | <4.1 | U | | <4 | U | | <4 | U | | <4 | U | | <3.5 | U | | <4.6 | U | | <4.6 | U | | <4.6 | U | | <14 | U | | <7.6 | U | |
| | | VMP-4-39-072312 | 7/23/2012 | <6.1 | U | | <6.1 | U | | <6 | U | | <6 | U | | <6 | U | | <5.2 | U | | <7 | U | | <6.8 | U | | <6.8 | U | | <22 | U | | <11 | U | |
| | | VMP-4-39-101812 | 10/18/2012 | <77 | U | | <77 | U | | <75 | U | | <75 | U | | <75 | U | | <66 | U | | <88 | U | | <86 | U | | <86 | U | | <270 | U | | <140 | U | |
| | | VMP-4-39-101812-Dup | 10/18/2012 | <70 | U | | <70 | U | | <68 | U | | <68 | U | | <68 | U | | <60 | U | | <80 | U | | <78 | U | | <78 | U | | <250 | U | | <130 | U | |
| | | VMP-4-39-020713 | 2/7/2013 | <11 | U | | <11 | U | | <11 | U | | <11 | U | | <11 | U | | <9.3 | U | | <12 | U | | <12 | U | | <12 | U | | <39 | U | | <20 | U | |

SEE LAST PAGE OF TABLE FOR NOTES

**TABLE 5**
**CUMULATIVE SUMMARY OF SOIL VAPOR ANALYTICAL DETECTIONS AND SCREENING RESULTS: VILLAGE - VOCS**

| Location | Depth | Sample ID | Sample Date | 1,1-Dichloroethane | | | 1,2-Dichloroethane | | | 1,1-Dichloroethene | | | cis-1,2-Dichloroethene | | | trans-1,2-Dichloroethene | | | Dichloromethane (Methylene chloride) | | | 1,2-Dichloropropane | | | cis-1,3-Dichloropropene | | | trans-1,3-Dichloropropene | | | 1,4-Dioxane | | | Ethanol | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | 690 | | | 0.099 | | | 240 | | | 1100000 | | | 85 | | | 5.6 | | | 0.062 | | | 0.9 | | | 0.9 | | | 0.22 | | | | | |
| | | | | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals |
| VMP-5 | 5 ft | VMP-5-5-090910 | 9/9/2010 | <11 | U | | <11 | U | | <10 | U | | <10 | U | | <10 | U | | <9.2 | U | | <12 | U | | <12 | U | | <12 | U | | <38 | U | | <20 | U | |
| | | VMP-5-5-112210 | 11/22/2010 | <2.6 | U | | <2.6 | U | | <2.6 | U | | <2.6 | U | | <2.6 | U | | <2.2 | U | | <3 | U | | <2.9 | U | | <2.9 | U | | <9.3 | U | | <4.9 | U | |
| | | VMP-5-5-021611 | 2/16/2011 | <0.017 | U | | <0.017 | U | | <0.016 | U | | <0.016 | U | | <0.016 | U | | <0.014 | U | | <0.019 | U | | <0.019 | U | | <0.019 | U | | <0.059 | U | | <0.031 | U | |
| | | VMP-5-5-042111 | 4/21/2011 | <0.053 | U | | <0.053 | U | | <0.052 | U | | <0.052 | U | | <0.052 | U | | <0.046 | U | | <0.061 | U | | <0.06 | U | | <0.06 | U | | <0.19 | U | | <0.099 | U | |
| | | VMP-5-5-080511 | 8/5/2011 | <0.0051 | U | | <0.0051 | U | | <0.005 | U | | <0.005 | U | | <0.005 | U | | 0.0075 | | | <0.0058 | U | | <0.0057 | U | | <0.0057 | U | | <0.018 | U | | 0.073 | | |
| | | VMP-5-5-111111 | 11/11/2011 | <0.0038 | U | | <0.0038 | U | | <0.0037 | U | | <0.0037 | U | | <0.0037 | U | | 0.0023 | J | | <0.0043 | U | | <0.0042 | U | | <0.0042 | U | | <0.013 | U | | 0.014 | | |
| | | VMP-5-5-013012 | 1/30/2012 | <0.038 | U | | <0.038 | U | | <0.037 | U | | <0.037 | U | | <0.037 | U | | 0.042 | | | <0.043 | U | | <0.042 | U | | <0.042 | U | | <0.13 | U | | 0.088 | | |
| | | VMP-5-5-041112 | 4/11/2012 | <0.0037 | U | | <0.0037 | U | | <0.0036 | U | | <0.0036 | U | | <0.0036 | U | | 0.0011 | J | | 0.0014 | J | | <0.0042 | U | | <0.0042 | U | | 0.0029 | J | | 0.018 | | |
| | | VMP-5-5-071312 | 7/13/2012 | <0.0041 | U | | <0.0041 | U | | <0.004 | U | | <0.004 | U | | <0.004 | U | | <0.035 | J | U | <0.0047 | U | U | <0.0046 | U | | <0.0046 | J | U | <0.015 | U | | 0.035 | | |
| | | VMP-5-5-101212 | 10/12/2012 | <0.0051 | U | | <0.0051 | U | | <0.005 | U | | <0.005 | U | | <0.005 | U | | <0.044 | J | U | <0.0058 | U | | <0.0057 | U | | <0.0057 | U | | <0.018 | U | | 0.0034 | J | |
| | | VMP-5-5-012513 | 1/25/2013 | <0.0053 | U | | <0.0053 | U | | <0.0052 | U | | <0.0052 | U | | <0.0052 | U | | <0.046 | U | | <0.0061 | U | | <0.006 | U | | <0.006 | U | | <0.019 | U | | 0.0047 | J | |
| | 12.5 ft | VMP-5-12.5-090910 | 9/9/2010 | <5.3 | U | | <5.2 | U | | <5.2 | U | | <5.2 | U | | <5.2 | U | | <4.6 | U | | <6.1 | U | | <6 | U | | <6 | U | | <19 | U | | <9.9 | U | |
| | | VMP-5-12.5-112310 | 11/23/2010 | <0.27 | U | | <0.27 | U | | <0.26 | U | | <0.26 | U | | <0.26 | U | | <0.23 | U | | <0.3 | U | | <0.3 | U | | <0.3 | U | | <0.95 | U | | <0.5 | U | |
| | | VMP-5-12.5-021611 | 2/16/2011 | <0.8 | U | | <0.8 | U | | <0.79 | U | | <0.79 | U | | <0.79 | U | | <0.69 | U | | <0.92 | U | | <0.9 | U | | <0.9 | U | | <2.9 | U | | <1.5 | U | |
| | | VMP-5-12.5-042111 | 4/21/2011 | <0.057 | U | | <0.057 | U | | <0.056 | U | | <0.056 | U | | <0.056 | U | | <0.049 | U | | <0.065 | U | | <0.064 | U | | <0.064 | U | | <0.2 | U | | <0.11 | U | |
| | | VMP-5-12.5-080611 | 8/6/2011 | <5 | U | | <5 | U | | <4.9 | U | | <4.9 | U | | <4.9 | U | | <4.3 | U | | <5.7 | U | | <5.6 | U | | <5.6 | U | | <18 | U | | <9.3 | U | |
| | | VMP-5-12.5-111111 | 11/11/2011 | <0.0036 | U | | <0.0036 | U | | <0.0035 | U | | 0.0012 | J | | <0.0035 | U | | 0.0024 | J | | <0.0041 | U | | <0.004 | U | | <0.004 | U | | <0.013 | U | | 0.011 | | |
| | | VMP-5-12.5-013012 | 1/30/2012 | <0.012 | U | | <0.012 | U | | <0.011 | U | | <0.011 | U | | <0.011 | U | | <0.01 | U | | <0.013 | U | | <0.013 | U | | <0.013 | U | | <0.041 | U | | 0.032 | | |
| | | VMP-5-12.5-041112 | 4/11/2012 | <0.0035 | U | | 0.00075 | J | | <0.0035 | U | | <0.0035 | U | | <0.0035 | U | | <0.03 | U | | 0.00088 | J | | <0.004 | U | | <0.004 | U | | <0.013 | U | | 0.043 | | |
| | | VMP-5-12.5-071212 | 7/12/2012 | <0.0042 | U | | <0.0042 | U | | <0.0041 | U | | <0.0041 | U | | <0.0041 | U | | <0.036 | U | | <0.0048 | U | | <0.0047 | U | | <0.0047 | U | | <0.015 | U | | 0.011 | | |
| | | VMP-5-12.5-101112 | 10/11/2012 | <0.0099 | U | | <0.0099 | U | | <0.0097 | U | | <0.0097 | U | | <0.0097 | U | | 0.0047 | J | | <0.011 | U | | <0.011 | U | | <0.011 | U | | <0.035 | UJ | UJ | 0.015 | J | J |
| | | VMP-5-12.5-012413 | 1/24/2013 | <0.0052 | U | | <0.0052 | U | | <0.0051 | U | | <0.0051 | U | | <0.0051 | U | | <0.045 | U | | <0.006 | U | | <0.0058 | U | | <0.0058 | U | | <0.018 | U | | 0.0043 | J | |
| | 31 ft | VMP-5-31-090910 | 9/9/2010 | <22 | U | | <22 | U | | <22 | U | | <22 | U | | <22 | U | | <19 | U | | <25 | U | | <25 | U | | <25 | U | | <79 | U | | <41 | U | |
| | | VMP-5-31-112310 | 11/23/2010 | <14 | U | | <14 | U | | <14 | U | | <14 | U | | <14 | U | | <12 | U | | <16 | U | | <16 | U | | <16 | U | | <50 | U | | <26 | U | |
| | | VMP-5-31-021611 | 2/16/2011 | <5.6 | U | | <5.6 | U | | <5.5 | U | | <5.5 | U | | <5.5 | U | | <4.8 | U | | <6.4 | U | | <6.3 | U | | <6.3 | U | | <20 | U | | <10 | U | |
| | | VMP-5-31-042111 | 4/21/2011 | <83 | U | | <82 | U | | <82 | U | | <82 | U | | <82 | U | | <72 | U | | <95 | U | | <93 | U | | <93 | U | | <300 | U | | <160 | U | |
| | | VMP-5-31-080611 | 8/6/2011 | <47 | U | | <47 | U | | <46 | U | | <46 | U | | <46 | U | | <40 | U | | <54 | U | | <53 | U | | <53 | U | | <170 | U | | <87 | U | |
| | | VMP-5-31-111111 | 11/11/2011 | <24 | U | | 12 | J | | <23 | U | | <23 | U | | <23 | U | | <20 | U | | <27 | U | | <26 | U | | <26 | U | | <84 | U | | <44 | U | |
| | | VMP-5-31-013012 | 1/30/2012 | <12 | U | | <12 | U | | <12 | U | | <12 | U | | <12 | U | | 3 | J | | <14 | U | | <14 | U | | <14 | U | | <43 | U | | <22 | U | |
| | | VMP-5-31-041112 | 4/11/2012 | <0.039 | U | | <0.039 | U | | <0.038 | U | | <0.038 | U | | <0.038 | U | | <0.033 | U | | <0.044 | U | | <0.043 | U | | <0.043 | U | | <0.14 | U | | <0.072 | U | |
| | | VMP-5-31-071212 | 7/12/2012 | <0.0041 | U | | <0.0041 | U | | <0.004 | U | | <0.004 | U | | <0.004 | U | | 0.0013 | J | | <0.0046 | U | | <0.0046 | U | | <0.0046 | U | | <0.014 | U | | 0.021 | | |
| | | VMP-5-31-101112 | 10/11/2012 | <0.0057 | U | | <0.0057 | U | | <0.0056 | U | | <0.0056 | U | | <0.0056 | U | | 0.0024 | J | | <0.0065 | U | | <0.0064 | U | | <0.0064 | U | | <0.02 | UJ | UJ | 0.0055 | J | J |
| | | VMP-5-31-012413 | 1/24/2013 | <0.057 | U | | <0.057 | U | | <0.056 | U | | <0.056 | U | | <0.056 | U | | <0.49 | U | | <0.065 | U | | <0.064 | U | | <0.064 | U | | <0.2 | U | | <0.1 | U | |
| | 40 ft | VMP-5-40-042111 | 4/21/2011 | <87 | U | | <87 | U | | <85 | U | | <85 | U | | <85 | U | | <75 | U | | <100 | U | | <98 | U | | <98 | U | | <310 | U | | <160 | U | |
| | | VMP-5-40-013012 | 1/30/2012 | <25 | U | | <25 | U | | <25 | U | | <25 | U | | <25 | U | | 6.2 | J | | <29 | U | | <28 | U | | <28 | U | | <90 | U | | <47 | U | |
| | | VMP-5-40-041212 | 4/12/2012 | <0.038 | U | | <0.038 | U | | <0.037 | U | | <0.037 | U | | <0.037 | U | | <0.032 | U | | <0.043 | U | | <0.042 | U | | <0.042 | U | | <0.13 | U | | <0.07 | U | |
| | | VMP-5-40-071212 | 7/12/2012 | <0.041 | U | | <0.041 | U | | <0.04 | U | | <0.04 | U | | <0.04 | U | | <0.35 | U | | <0.046 | U | | <0.046 | U | | <0.046 | U | | <0.14 | U | | <0.076 | U | |
| | | VMP-5-40-101112 | 10/11/2012 | <0.006 | U | | <0.006 | U | | <0.0059 | U | | <0.0059 | U | | <0.0059 | U | | 0.0049 | J | | <0.0068 | U | | <0.0067 | U | | <0.0067 | U | | <0.021 | U | UJ | 0.0075 | J | J |
| | | VMP-5-40-012513 | 1/25/2013 | <0.017 | U | | <0.017 | U | | <0.017 | U | | <0.017 | U | | <0.017 | U | | 0.014 | J | | <0.02 | U | | <0.02 | U | | <0.02 | U | | <0.062 | U | | <0.032 | U | |
| | | VMP-5-40-012513-Dup | 1/25/2013 | <0.017 | U | | <0.017 | U | | <0.017 | U | | <0.017 | U | | <0.017 | U | | 0.0054 | J | | <0.019 | U | | <0.019 | U | | <0.019 | U | | <0.06 | U | | <0.032 | U | |
| VMP-6 | 5 ft | VMP-6-5-090810 | 9/8/2010 | <0.89 | U | | <0.89 | U | | <0.87 | U | | <0.87 | U | | <0.87 | U | | <0.76 | U | | <1 | U | | <1 | U | | <1 | U | | <3.2 | U | | <1.6 | U | |
| | | VMP-6-5-111610 | 11/16/2010 | <5.6 | U | | <5.6 | U | | <5.5 | U | | <5.5 | U | | <5.5 | U | | <4.8 | U | | <6.4 | U | | <6.3 | U | | <6.3 | U | | <20 | U | | <10 | U | |
| | | VMP-6-5-020711 | 2/7/2011 | <0.0048 | U | | <0.0048 | U | | <0.0047 | U | | <0.0047 | U | | <0.0047 | U | | <0.0041 | U | | <0.0055 | U | | <0.0054 | U | | <0.0054 | U | | <0.017 | U | | 0.0051 | J | |
| | | VMP-6-5-040811 | 4/8/2011 | <0.01 | U | | <0.01 | U | | <0.01 | U | | <0.01 | U | | <0.01 | U | | 0.0043 | J | | <0.012 | U | | <0.012 | U | | <0.012 | U | | <0.037 | U | | 0.02 | | |
| | | VMP-6-5-080411 | 8/4/2011 | <0.27 | U | | <0.27 | U | | <0.26 | U | | <0.26 | U | | <0.26 | U | | <0.23 | U | | <0.31 | U | | <0.3 | U | | <0.3 | U | | <0.96 | U | | <0.5 | U | |
| | | VMP-6-5-110911 | 11/9/2011 | <0.0032 | U | | <0.0032 | U | | <0.0032 | U | | <0.0032 | U | | <0.0032 | U | | <0.0028 | J | U | <0.0037 | U | | <0.0036 | U | | <0.0036 | U | | <0.012 | U | | 0.034 | | |
| | | VMP-6-5-013112 | 1/31/2012 | <0.038 | U | | <0.038 | U | | <0.038 | U | | <0.038 | U | | <0.038 | U | | 0.03 | J | | <0.044 | U | | <0.043 | U | | <0.043 | U | | <0.14 | U | | 0.076 | | |
| | | VMP-6-5-041212 | 4/12/2012 | <0.0041 | U | | <0.0041 | U | | <0.004 | U | | <0.004 | U | | <0.004 | U | | <0.035 | J | U | <0.0046 | U | | <0.0046 | U | | <0.0046 | U | | <0.014 | U | | 0.0053 | J | |
| | | VMP-6-5-071612 | 7/16/2012 | <0.0041 | U | | <0.0041 | U | | <0.004 | U | | <0.004 | U | | <0.004 | U | | <0.035 | J | U | <0.0046 | U | | <0.0046 | U | | <0.0046 | J | U | <0.014 | U | | 0.012 | | |
| | | VMP-6-5-101012 | 10/10/2012 | <0.0056 | U | | <0.0056 | U | | <0.0055 | U | | <0.0055 | U | | <0.0055 | U | | <0.048 | J | U | <0.0064 | U | | <0.0063 | U | | <0.0063 | U | | <0.02 | UJ | UJ | 0.0028 | J | J |
| | | VMP-6-5-021213 | 2/12/2013 | <0.005 | U | | <0.005 | U | | <0.0049 | U | | <0.0049 | U | | <0.0049 | U | | <0.043 | U | | <0.0057 | U | | <0.0056 | U | | <0.0056 | U | | <0.018 | U | | 0.004 | J | |
| | 10 ft | VMP-6-10-090810 | 9/8/2010 | <0.96 | U | | <0.96 | U | | <0.94 | U | | <0.94 | U | | <0.94 | U | | <0.83 | U | | <1.1 | U | | <1.1 | U | | <1.1 | U | | <3.4 | U | | <1.8 | U | |
| | | VMP-6-10-111710 | 11/17/2010 | <0.0052 | U | | <0.0052 | U | | <0.0051 | U | | <0.0051 | U | | <0.0051 | U | | <0.0045 | U | | <0.006 | U | | <0.0058 | U | | <0.0058 | U | | <0.018 | U | | 0.0037 | J | |
| | | VMP-6-10-020711 | 2/7/2011 | <0.0051 | U | | <0.0051 | U | | <0.005 | U | | <0.005 | U | | <0.005 | U | | <0.0044 | U | | <0.0058 | U | | <0.0057 | U | | <0.0057 | U | | <0.018 | U | | <0.0095 | U | |
| | | VMP-6-10-040811 | 4/8/2011 | <0.12 | U | | <0.12 | U | | <0.12 | U | | <0.12 | U | | <0.12 | U | | 0.12 | | | <0.14 | U | | <0.14 | U | | <0.14 | U | | <0.44 | U | | 0.12 | J | |
| | | VMP-6-10-080411 | 8/4/2011 | <0.87 | U | | <0.87 | U | | <0.85 | U | | <0.85 | U | | <0.85 | U | | <0.74 | U | | <0.99 | U | | <0.97 | U | | <0.97 | U | | <3.1 | U | | <1.6 | U | |
| | | VMP-6-10-111011 | 11/10/2011 | <0.0034 | U | | <0.0034 | U | | <0.0033 | U | | <0.0033 | U | | <0.0033 | U | | <0.0029 | J | U | <0.0039 | U | | <0.0038 | U | | <0.0038 | U | | <0.012 | U | | 0.024 | | |
| | | VMP-6-10-013112 | 1/31/2012 | <0.6 | U | | <0.6 | U | | <0.59 | U | | <0.59 | U | | <0.59 | U | | <0.52 | U | | <0.69 | U | | <0.68 | U | | <0.68 | U | | <2.1 | U | | <1.1 | U | |
| | | VMP-6-10-041212 | 4/12/2012 | <0.0039 | U | | <0.0039 | U | | <0.0039 | U | | <0.0039 | U | | <0.0039 | U | | <0.034 | J | U | <0.0045 | U | | <0.0044 | U | | <0.0044 | J | U | <0.014 | U | | 0.011 | | |
| | | VMP-6-10-071612 | 7/16/2012 | <0.0053 | U | | <0.0053 | U | | <0.0052 | U | | <0.0052 | U | | <0.0052 | U | | <0.046 | J | U | <0.0061 | U | | <0.006 | J | U | <0.006 | J | U | <0.019 | U | | 0.0094 | J | |
| | | VMP-6-10-101112 | 10/11/2012 | <0.0058 | U | | <0.0058 | U | | <0.0057 | U | | <0.0057 | U | | <0.0057 | U | | <0.05 | J | U | <0.0067 | U | | <0.0066 | U | | <0.0066 | U | | <0.021 | UJ | UJ | 0.0037 | J | J |
| | | VMP-6-10-020513 | 2/5/2013 | <0.0056 | U | | <0.0056 | U | | <0.0055 | U | | <0.0055 | U | | <0.0055 | U | | <0.048 | J | U | <0.0064 | U | | <0.0063 | U | | <0.0063 | U | | <0.02 | U | | 0.0017 | J | |
| | 31.5 ft | VMP-6-31.5-090810 | 9/8/2010 | <6.5 | U | | <6.5 | U | | <6.4 | U | | <6.4 | U | | <6.4 | U | | <5.6 | U | | <7.4 | U | | <7.3 | U | | <7.3 | U | | <23 | U | | <12 | U | |
| | | VMP-6-31.5-111710 | 11/17/2010 | <10 | U | | <10 | U | | <10 | U | | <10 | U | | <10 | U | | <8.8 | U | | <12 | U | | <11 | U | | <11 | U | | <36 | U | | <19 | U | |
| | | VMP-6-31.5-020711 | 2/7/2011 | <9.8 | U | | <9.8 | U | | <9.6 | U | | <9.6 | U | | <9.6 | U | | <8.4 | U | | <11 | U | | <11 | U | | <11 | U | | <35 | U | | <18 | U | |
| | | VMP-6-31.5-041111 | 4/11/2011 | <7.6 | U | | <7.6 | U | | <7.4 | U | | <7.4 | U | | <7.4 | U | | 5.8 | J | | <8.7 | U | | <8.5 | U | | <8.5 | U | | <27 | U | | 3.2 | J | |
| | | VMP-6-31.5-080411 | 8/4/2011 | <5.6 | U | | <5.6 | U | | <5.5 | U | | <5.5 | U | | <5.5 | U | | <4.8 | U | | <6.4 | U | | <6.3 | U | | <6.3 | U | | <20 | U | | <10 | U | |
| | | VMP-6-31.5-111011 | 11/10/2011 | <8.7 | U | | 10 | | | <8.5 | U | | <8.5 | U | | <8.5 | U | | <7.4 | U | | <9.9 | U | | <9.7 | U | | <9.7 | U | | <31 | U | | 6.2 | J | |
| | | VMP-6-31.5-013112 | 1/31/2012 | <3.5 | U | | <3.5 | U | | <3.4 | U | | <3.4 | U | | <3.4 | U | | <3 | U | | <4 | U | | <3.9 | U | | <3.9 | U | | <12 | U | | <6.4 | U | |
| | | VMP-6-31.5-041212 | 4/12/2012 | <0.46 | U | | <0.46 | U | | <0.45 | U | | <0.45 | U | | <0.45 | U | | <0.4 | U | | <0.53 | U | | <0.52 | U | | <0.52 | U | | <1.6 | U | | 0.29 | J | |
| | | VMP-6-31.5-071612 | 7/16/2012 | <0.0073 | U | | <0.0073 | U | | <0.0072 | U | | <0.0072 | U | | <0.0072 | U | | 0.0024 | J | | <0.0084 | U | | <0.0082 | U | | <0.0082 | U | | <0.026 | U | | 0.043 | | |
| | | VMP-6-31.5-101112 | 10/11/2012 | <0.0057 | U | | <0.0057 | U | | <0.0056 | U | | <0.0056 | U | | <0.0056 | U | | 0.0028 | J | | <0.0065 | U | | <0.0064 | U | | <0.0064 | U | | <0.02 | UJ | UJ | 0.0073 | J | J |
| | | VMP-6-31.5-020513 | 2/5/2013 | <0.0052 | U | | <0.0052 | U | | <0.0051 | U | | <0.0051 | U | | <0.0051 | U | | 0.005 | J | | <0.006 | U | | <0.0058 | U | | <0.0058 | U | | <0.018 | U | | <0.0097 | U | |
| | 39 ft | VMP-6-39-041111 | 4/11/2011 | <9 | U | | <9 | U | | <8.9 | U | | <8.9 | U | | <8.9 | U | | 3.7 | J | | <10 | U | | <10 | U | | <10 | U | | <32 | U | | <17 | U | |
| | | VMP-6-39-013112 | 1/31/2012 | <3.5 | U | | <3.5 | U | | <3.4 | U | | <3.4 | U | | <3.4 | U | | <3 | U | | <4 | U | | <3.9 | U | | <3.9 | U | | <12 | U | | <6.4 | U | |
| | | VMP-6-39-041212 | 4/12/2012 | <0.34 | U | | <0.34 | U | | <0.33 | U | | <0.33 | U | | <0.33 | U | | <0.29 | U | | <0.39 | U | | <0.38 | U | | <0.38 | U | | <1.2 | U | | <0.63 | U | |
| | | VMP-6-39-071612 | 7/16/2012 | <0.016 | U | | <0.016 | U | | <0.016 | U | | <0.016 | U | | <0.016 | U | | <0.14 | U | | <0.018 | U | | <0.018 | U | | <0.018 | U | | <0.057 | U | | 0.019 | J | |
| | | VMP-6-39-071612-Dup | 7/16/2012 | <0.016 | U | | <0.016 | U | | <0.016 | U | | <0.016 | U | | <0.016 | U | | 0.0026 | J | | <0.018 | U | | <0.018 | U | | <0.018 | U | | <0.057 | U | | 0.022 | J | |
| | | VMP-6-39-101112 | 10/11/2012 | <0.011 | U | | <0.011 | U | | <0.011 | U | | <0.011 | U | | <0.011 | U | | 0.0032 | J | | <0.012 | U | | <0.012 | U | | <0.012 | U | | <0.039 | UJ | UJ | <0.02 | U | UJ |
| | | VMP-6-39-020513 | 2/5/2013 | <0.0053 | U | | <0.0053 | U | | <0.0052 | U | | <0.0052 | U | | <0.0052 | U | | <0.046 | J | U | <0.0061 | U | | <0.006 | U | | <0.006 | U | | <0.019 | U | | 0.0042 | J | |

SEE LAST PAGE OF TABLE FOR NOTES

**TABLE 5**
**CUMULATIVE SUMMARY OF SOIL VAPOR ANALYTICAL DETECTIONS AND SCREENING RESULTS: VILLAGE - VOCS**

| Location | Depth | Sample ID | Sample Date | 1,1-Dichloroethane | | | 1,2-Dichloroethane | | | 1,1-Dichloroethene | | | cis-1,2-Dichloroethene | | | trans-1,2-Dichloroethene | | | Dichloromethane (Methylene chloride) | | | 1,2-Dichloropropane | | | cis-1,3-Dichloropropene | | | trans-1,3-Dichloropropene | | | 1,4-Dioxane | | | Ethanol | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | 690 | | | 0.099 | | | 240 | | | 1100000 | | | 85 | | | 5.6 | | | 0.062 | | | 0.9 | | | 0.9 | | | 0.22 | | | | | |
| | | | | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals |
| VMP-7 | 5 ft | VMP-7-5-082610 | 8/26/2010 | <0.0053 | U | | <0.0053 | U | | <0.0052 | U | | <0.0052 | U | | <0.0052 | U | | 0.0023 | J | | <0.0061 | U | | <0.006 | U | | <0.006 | U | | <0.019 | U | | 0.007 | J | |
| | | VMP-7-5-111910 | 11/19/2010 | <0.0048 | U | | <0.0048 | U | | <0.0047 | U | | <0.0047 | U | | <0.0047 | U | | <0.0041 | U | | <0.0055 | U | | <0.0054 | U | | <0.0054 | U | | 0.0093 | J | | 0.0031 | J | |
| | | VMP-7-5-020711 | 2/7/2011 | <0.0052 | U | | <0.0052 | U | | <0.0051 | U | | <0.0051 | U | | <0.0051 | U | | 0.0013 | J | | <0.006 | U | | <0.0058 | U | | <0.0058 | U | | <0.018 | U | | 0.0087 | J | |
| | | VMP-7-5-040711 | 4/7/2011 | <0.0074 | U | | <0.0074 | U | | <0.0072 | U | | <0.0072 | U | | <0.0072 | U | | <0.0063 | J | U | <0.0084 | U | | <0.0083 | U | | <0.0083 | U | | <0.026 | U | | 0.0034 | J | |
| | | VMP-7-5-080211 | 8/2/2011 | <0.73 | U | | <0.73 | U | | <0.72 | U | | <0.72 | U | | <0.72 | U | | <0.63 | U | | <0.83 | U | | <0.82 | U | | <0.82 | U | | <2.6 | U | | <1.4 | U | |
| | | VMP-7-5-111011 | 11/10/2011 | <0.0035 | U | | <0.0035 | U | | <0.0034 | U | | <0.0034 | U | | <0.0034 | U | | 0.0024 | J | J | <0.004 | U | | <0.0039 | U | | <0.0039 | U | | <0.012 | U | | 0.0096 | | |
| | | VMP-7-5-111011-DUP | 11/10/2011 | <0.0032 | U | | <0.0032 | U | | <0.0032 | U | | <0.0032 | U | | <0.0032 | U | | 0.01 | | J | <0.0037 | U | | <0.0036 | U | | <0.0036 | U | | <0.012 | U | | 0.018 | | |
| | | VMP-7-5-013112 | 1/31/2012 | <0.0035 | U | | <0.0035 | U | | <0.0035 | U | | <0.0035 | U | | <0.0035 | U | | 0.003 | | | <0.004 | U | | <0.004 | U | | <0.004 | J | U | <0.013 | U | | 0.039 | | |
| | | VMP-7-5-041212 | 4/12/2012 | <0.0038 | U | | <0.0038 | U | | <0.0038 | U | | <0.0038 | U | | <0.0038 | U | | <0.033 | J | U | <0.0044 | U | | <0.0043 | U | | <0.0043 | U | | <0.014 | U | | 0.036 | | |
| | | VMP-7-5-073112 | 7/31/2012 | <0.0099 | U | | <0.0099 | U | | <0.0097 | U | | <0.0097 | U | | <0.0097 | U | | <0.085 | J | U | <0.011 | U | | <0.011 | U | | <0.011 | U | | <0.035 | U | | 0.047 | | |
| | | VMP-7-5-101012 | 10/10/2012 | <0.006 | U | | <0.006 | U | | <0.0059 | U | | <0.0059 | U | | <0.0059 | U | | 0.0034 | J | | <0.0068 | U | | <0.0067 | U | | <0.0067 | U | | <0.021 | U | | 0.004 | J | |
| | 13.5 ft | VMP-7-13.5-082610 | 8/26/2010 | <0.12 | U | | <0.12 | U | | <0.11 | U | | <0.11 | U | | <0.11 | U | | <0.1 | U | | <0.13 | U | | <0.13 | U | | <0.13 | U | | <0.42 | U | | <0.22 | U | |
| | | VMP-7-13.5-111910 | 11/19/2010 | <0.82 | U | | <0.82 | U | | <0.8 | U | | <0.8 | U | | <0.8 | U | | 0.91 | | J | <0.93 | U | | <0.91 | U | | <0.91 | U | | <2.9 | U | | <1.5 | U | |
| | | VMP-7-13.5-020711 | 2/7/2011 | <0.005 | U | | <0.005 | U | | <0.0049 | U | | <0.0049 | U | | <0.0049 | U | | <0.0043 | U | | <0.0057 | U | | <0.0056 | U | | <0.0056 | U | | <0.018 | U | | <0.0093 | U | |
| | | VMP-7-13.5-040711 | 4/7/2011 | <0.0087 | U | | <0.0087 | U | | <0.0086 | U | | <0.0086 | U | | <0.0086 | U | | <0.0075 | J | U | <0.01 | U | | <0.0098 | U | | <0.0098 | U | | <0.031 | U | | <0.016 | U | |
| | | VMP-7-13.5-080311 | 8/3/2011 | <0.98 | U | | <0.98 | U | | <0.96 | U | | <0.96 | U | | <0.96 | U | | <0.84 | U | | <1.1 | U | | <1.1 | U | | <1.1 | U | | <3.5 | U | | <1.8 | U | |
| | | VMP-7-13.5-111011 | 11/10/2011 | <0.0032 | U | | <0.0032 | U | | <0.0031 | U | | <0.0031 | U | | <0.0031 | U | | 0.0031 | | | <0.0036 | U | | <0.0036 | U | | <0.0036 | U | | <0.011 | U | | 0.017 | | |
| | | VMP-7-13.5-013112 | 1/31/2012 | <0.045 | U | | <0.045 | U | | <0.044 | U | | <0.044 | U | | <0.044 | U | | <0.039 | U | | <0.052 | U | | <0.051 | U | | <0.051 | U | | <0.16 | U | | 0.094 | | J |
| | | VMP-7-13.5-013112-DUP | 1/31/2012 | <0.046 | U | | <0.046 | U | | <0.045 | U | | <0.045 | U | | <0.045 | U | | <0.04 | U | | <0.053 | U | | <0.052 | U | | <0.052 | U | | <0.16 | U | | 0.12 | | J |
| | | VMP-7-13.5-041212 | 4/12/2012 | <0.0037 | U | | <0.0037 | U | | <0.0036 | U | | <0.0036 | U | | <0.0036 | U | | <0.032 | J | U | <0.0042 | U | | <0.0042 | U | | <0.0042 | U | | <0.013 | U | | 0.044 | | |
| | | VMP-7-13.5-041212-DUP | 4/12/2012 | <0.0039 | U | | <0.0039 | U | | <0.0038 | U | | <0.0038 | U | | <0.0038 | U | | <0.034 | J | U | <0.0044 | U | | <0.0044 | U | | <0.0044 | U | | <0.014 | U | | 0.033 | | |
| | | VMP-7-13.5-072012 | 7/20/2012 | <0.0038 | U | | <0.0038 | U | | <0.0037 | U | | <0.0037 | U | | <0.0037 | U | | 0.0013 | J | | <0.0043 | U | | <0.0042 | U | | <0.0042 | U | | <0.013 | U | | 0.024 | | |
| | | VMP-7-13.5-101012 | 10/10/2012 | <0.0056 | U | | <0.0056 | U | | <0.0055 | U | | <0.0055 | U | | <0.0055 | U | | 0.0041 | J | | <0.0064 | U | | <0.0063 | U | | <0.0063 | U | | <0.02 | U | | 0.011 | | |
| | | VMP-7-13.5-021313 | 2/13/2013 | <0.0056 | U | | <0.0056 | U | | <0.0055 | U | | <0.0055 | U | | <0.0055 | U | | 0.00061 | J | | <0.0064 | U | | <0.0063 | U | | <0.0063 | U | | <0.02 | U | | 0.0068 | J | |
| | 29.5 ft | VMP-7-29.5-083110 | 8/31/2010 | <1.7 | U | | <1.7 | U | | <1.6 | U | | <1.6 | U | | <1.6 | U | | <1.4 | U | | <1.9 | U | | <1.9 | U | | <1.9 | U | | <5.9 | U | | <3.1 | U | |
| | | VMP-7-29.5-111910 | 11/19/2010 | <2.5 | U | | <2.5 | U | | <2.4 | U | | <2.4 | U | | <2.4 | U | | <2.2 | U | | <2.9 | U | | <2.8 | U | | <2.8 | U | | <8.9 | U | | <4.7 | U | |
| | | VMP-7-29.5-020711 | 2/7/2011 | <2.6 | U | | <2.6 | U | | <2.6 | U | | <2.6 | U | | <2.6 | U | | <2.2 | U | | <3 | U | | <2.9 | U | | <2.9 | U | | <9.3 | U | | <4.9 | U | |
| | | VMP-7-29.5-040711 | 4/7/2011 | <0.63 | U | | <0.63 | U | | <0.62 | U | | <0.62 | U | | <0.62 | U | | <0.54 | U | | <0.72 | U | | <0.71 | U | | <0.71 | U | | <2.2 | U | | <1.2 | U | |
| | | VMP-7-29.5-080311 | 8/3/2011 | <1.5 | U | | <1.5 | U | | <1.5 | U | | <1.5 | U | | <1.5 | U | | <1.3 | U | | <1.7 | U | | <1.7 | U | | <1.7 | U | | <5.3 | U | | <2.8 | U | |
| | | VMP-7-29.5-111111 | 11/11/2011 | 0.71 | J | | 5.3 | | | <2.9 | U | | <2.9 | U | | <2.9 | U | | <2.5 | U | | <3.4 | U | | <3.3 | U | | <3.3 | U | | <10 | U | | 3.3 | J | |
| | | VMP-7-29.5-020112 | 2/1/2012 | <0.59 | U | | <0.59 | U | | <0.58 | U | | <0.58 | U | | <0.58 | U | | <0.51 | U | | <0.67 | U | | <0.66 | U | | <0.66 | U | | <2.1 | U | | <1.1 | U | |
| | | VMP-7-29.5-041312 | 4/13/2012 | <0.0037 | U | | <0.0037 | U | | <0.0036 | U | | <0.0036 | U | | <0.0036 | U | | <0.032 | J | U | <0.0042 | U | | <0.0042 | U | | <0.0042 | U | | <0.013 | U | | 0.021 | | |
| | | VMP-7-29.5-072012 | 7/20/2012 | <0.0038 | U | | <0.0038 | U | | <0.0037 | U | | <0.0037 | U | | <0.0037 | U | | 0.0015 | J | | <0.0043 | U | | <0.0042 | U | | <0.0042 | U | | <0.013 | U | | 0.025 | | |
| | | VMP-7-29.5-072012-Dup | 7/20/2012 | <0.0038 | U | | <0.0038 | U | | <0.0037 | U | | <0.0037 | U | | <0.0037 | U | | 0.0012 | J | | <0.0043 | U | | <0.0042 | U | | <0.0042 | U | | <0.013 | U | | 0.016 | | |
| | | VMP-7-29.5-101012 | 10/10/2012 | <0.0058 | U | | <0.0058 | U | | <0.0057 | U | | <0.0057 | U | | <0.0057 | U | | 0.0023 | J | | <0.0067 | U | | <0.0066 | U | | 0.0017 | J | | <0.021 | UJ | UJ | 0.0076 | J | J |
| | 38 ft | VMP-7-38-020711 | 2/7/2011 | <3.5 | U | | <3.5 | U | | <3.4 | U | | <3.4 | U | | <3.4 | U | | <3 | U | | <4 | U | | <3.9 | U | | <3.9 | U | | <12 | U | | <6.5 | U | |
| | | VMP-7-38-040711 | 4/7/2011 | <0.89 | U | | <0.89 | U | | <0.87 | U | | <0.87 | U | | <0.87 | U | | <0.76 | U | | <1 | U | | <1 | U | | <1 | U | | <3.2 | U | | <1.6 | U | |
| | | VMP-7-38-020112 | 2/1/2012 | <0.85 | U | | <0.85 | U | | <0.83 | U | | <0.83 | U | | <0.83 | U | | <0.73 | U | | <0.97 | U | | <0.95 | U | | <0.95 | U | | <3 | U | | <1.6 | U | |
| | | VMP-7-38-042512 | 4/25/2012 | <0.0037 | U | | <0.0037 | U | | <0.0036 | U | | <0.0036 | U | | <0.0036 | U | | <0.032 | J | U | <0.0042 | U | | <0.0042 | U | | <0.0042 | U | | <0.013 | U | | 0.026 | | |
| | | VMP-7-38-042512-Dup | 4/25/2012 | <0.0037 | U | | <0.0037 | U | | <0.0036 | U | | <0.0036 | U | | <0.0036 | U | | <0.032 | J | U | <0.0042 | U | | <0.0042 | U | | <0.0042 | U | | <0.013 | U | | 0.028 | | |
| | | VMP-7-38-101112 | 10/11/2012 | <0.0054 | U | | <0.0054 | U | | <0.0053 | U | | <0.0053 | U | | <0.0053 | U | | 0.002 | J | | <0.0062 | U | | <0.0061 | U | | <0.0061 | U | | <0.019 | UJ | UJ | 0.006 | J | J |
| VMP-8 | 5 ft | VMP-8-5-083010 | 8/30/2010 | 0.00069 | J | | 0.00092 | J | | <0.0053 | U | | 0.0012 | J | | <0.0053 | U | | 0.0026 | J | | <0.0062 | U | | <0.0061 | U | | <0.0061 | U | | <0.019 | U | | <0.01 | U | |
| | | VMP-8-5-111810 | 11/17/2010 | <0.0047 | U | | <0.0047 | U | | <0.0046 | U | | <0.0046 | U | | <0.0046 | U | | 0.00071 | J | | <0.0054 | U | | <0.0053 | U | | <0.0053 | U | | <0.017 | U | | 0.0073 | J | |
| | | VMP-8-5-021011 | 2/10/2011 | <0.005 | U | | <0.005 | U | | <0.0049 | U | | <0.0049 | U | | <0.0049 | U | | <0.0043 | U | | <0.0057 | U | | <0.0056 | U | | <0.0056 | U | | <0.018 | U | | <0.0093 | U | |
| | | VMP-8-5-040711 | 4/7/2011 | <0.0056 | U | | <0.0056 | U | | <0.0055 | U | | <0.0055 | U | | <0.0055 | U | | <0.0048 | U | | <0.0064 | U | | <0.0063 | U | | <0.0063 | U | | 0.0057 | J | | <0.01 | U | |
| | | VMP-8-5-072711 | 7/27/2011 | <0.006 | U | | <0.006 | U | | <0.0059 | U | | <0.0059 | U | | <0.0059 | U | | <0.0051 | U | | <0.0068 | U | | <0.0067 | U | | <0.0067 | U | | <0.021 | U | | 0.037 | | |
| | | VMP-8-5-110311 | 11/3/2011 | <0.0035 | U | | <0.0035 | U | | <0.0034 | U | | <0.0034 | U | | <0.0034 | U | | <0.003 | J | U | <0.004 | U | | <0.0039 | U | | <0.0039 | U | | <0.012 | U | | 0.052 | | |
| | | VMP-8-5-012312 | 1/23/2012 | <0.0043 | U | | <0.0043 | U | | <0.0042 | U | | <0.0042 | U | | <0.0042 | U | | <0.0037 | J | U | <0.0049 | U | | <0.0048 | U | | <0.0048 | J | U | <0.015 | U | | 0.023 | | |
| | | VMP-8-5-041012 | 4/10/2012 | <0.0039 | U | | <0.0039 | U | | <0.0038 | U | | <0.0038 | U | | <0.0038 | U | | 0.0012 | J | | 0.0013 | J | | <0.0043 | U | | 0.0044 | | | <0.014 | U | | <0.0072 | U | |
| | | VMP-8-5-071312 | 7/13/2012 | <0.0032 | U | | <0.0032 | U | | <0.0032 | U | | <0.0032 | U | | <0.0032 | U | | 0.0015 | J | | 0.0017 | J | | <0.0036 | U | | <0.0036 | U | | <0.012 | U | | 0.0086 | | |
| | | VMP-8-5-073112 | 7/31/2012 | <0.0042 | U | | <0.0042 | U | | <0.0041 | U | | <0.0041 | U | | <0.0041 | U | | <0.036 | J | U | <0.0048 | U | | <0.0047 | U | | <0.0047 | U | | <0.015 | U | | 0.061 | | |
| | | VMP-8-5-100412 | 10/4/2012 | <0.0056 | U | | <0.0056 | U | | <0.0055 | U | | <0.0055 | U | | <0.0055 | U | | <0.048 | J | U | <0.0064 | U | | <0.0063 | U | | <0.0063 | U | | <0.02 | U | | <0.01 | U | |
| | | VMP-8-5-100412-Dup | 10/4/2012 | <0.0053 | U | | <0.0053 | U | | <0.0052 | U | | <0.0052 | U | | <0.0052 | U | | <0.046 | J | U | <0.0061 | U | | <0.006 | U | | <0.006 | U | | <0.019 | U | | <0.0099 | U | |
| | | VMP-8-5-012413 | 1/24/2013 | <0.0054 | U | | <0.0054 | U | | <0.0053 | U | | <0.0053 | U | | <0.0053 | U | | <0.047 | J | U | <0.0062 | U | | <0.0061 | U | | <0.0061 | U | | <0.019 | U | | 0.0038 | J | |
| | 9.5 ft | VMP-8-9.5 | 11/10/2009 | <0.004 | U | | <0.004 | U | | <0.004 | U | | <0.004 | U | | <0.004 | U | | <0.003 | U | | <0.005 | U | | <0.005 | U | | <0.005 | U | | <0.016 | U | | 0.03 | | J |
| | | VMP-8-9.5-083010 | 8/30/2010 | 0.00048 | J | | <0.0049 | U | | <0.0048 | U | | 0.00059 | J | | <0.0048 | U | | 0.005 | | | <0.0056 | U | | <0.0055 | U | | <0.0055 | U | | <0.017 | U | | 0.016 | | |
| | | VMP-8-9.5-083010-DUP | 8/30/2010 | 0.00041 | J | | 0.0007 | J | | <0.0049 | U | | <0.0049 | U | | <0.0049 | U | | 0.0013 | J | | 0.00099 | J | | <0.0056 | U | | <0.0056 | U | | <0.018 | U | | 0.013 | | |
| | | VMP-8-9.5-111810 | 11/17/2010 | <0.0049 | U | | <0.0049 | U | | <0.0048 | U | | <0.0048 | U | | <0.0048 | U | | <0.0042 | U | | <0.0056 | U | | <0.0055 | U | | <0.0055 | U | | 0.0021 | J | | 0.01 | | |
| | | VMP-8-9.5-021011 | 2/10/2011 | <0.0051 | U | | <0.0051 | U | | <0.005 | U | | <0.005 | U | | <0.005 | U | | <0.0044 | U | | <0.0058 | U | | <0.0057 | U | | <0.0057 | U | | <0.018 | U | | 0.0028 | J | |
| | | VMP-8-9.5-040711 | 4/7/2011 | <0.0056 | U | | <0.0056 | U | | <0.0055 | U | | <0.0055 | U | | <0.0055 | U | | 0.00097 | J | | <0.0064 | U | | <0.0063 | U | | <0.0063 | U | | <0.02 | U | | 0.0074 | J | |
| | | VMP-8-9.5-072711 | 7/27/2011 | <0.0043 | U | | <0.0043 | U | | <0.0042 | U | | <0.0042 | U | | <0.0042 | U | | 0.0065 | | | <0.0049 | U | | <0.0048 | U | | <0.0048 | U | | <0.015 | U | | 0.082 | | |
| | | VMP-8-9.5-110311 | 11/3/2011 | <0.0034 | U | | <0.0034 | U | | <0.0033 | U | | <0.0033 | U | | <0.0033 | U | | <0.0029 | J | U | <0.0039 | U | | <0.0038 | U | | <0.0038 | U | | 0.0045 | J | | 0.029 | | |
| | | VMP-8-9.5-012312 | 1/23/2012 | <0.0041 | U | | <0.0041 | U | | <0.004 | U | | <0.004 | U | | <0.004 | U | | <0.0035 | J | U | <0.0047 | U | | <0.0046 | U | | <0.0046 | U | | <0.015 | U | | 0.012 | | |
| | | VMP-8-9.5-041012 | 4/10/2012 | <0.0039 | U | | <0.0039 | U | | <0.0038 | U | | <0.0038 | U | | <0.0038 | U | | 0.0014 | J | | <0.0044 | U | | <0.0043 | U | | 0.0065 | | | <0.014 | U | | <0.0072 | U | |
| | | VMP-8-9.5-071312 | 7/13/2012 | <0.0038 | U | | <0.0038 | U | | <0.0037 | U | | <0.0037 | U | | <0.0037 | U | | <0.032 | U | | <0.0043 | U | | <0.0042 | U | | <0.0042 | U | | <0.013 | U | | 0.0025 | J | |
| | | VMP-8-9.5-071312-Dup | 7/13/2012 | <0.0036 | U | | <0.0036 | U | | <0.0035 | U | | <0.0035 | U | | <0.0035 | U | | 0.001 | J | | <0.0041 | U | | <0.0041 | U | | <0.0041 | U | | <0.013 | U | | <0.0067 | U | |
| | | VMP-8-9.5-100412 | 10/4/2012 | <0.0061 | U | | <0.0061 | U | | <0.006 | U | | <0.006 | U | | <0.006 | U | | 0.0046 | J | | <0.007 | U | | <0.0069 | U | | <0.0069 | U | | <0.022 | U | | <0.011 | U | |
| | | VMP-8-9.5-012413 | 1/24/2013 | <0.0051 | U | | <0.0051 | U | | <0.005 | U | | <0.005 | U | | <0.005 | U | | <0.044 | J | U | <0.0058 | U | | <0.0057 | U | | <0.0057 | U | | <0.018 | U | | <0.0095 | U | |
| | | VMP-8-9.5-012413-Dup | 1/24/2013 | <0.0054 | U | | <0.0054 | U | | <0.0053 | U | | <0.0053 | U | | <0.0053 | U | | <0.047 | J | U | <0.0062 | U | | <0.0061 | U | | 0.00081 | J | | <0.019 | U | | <0.01 | U | |
| | 23.5 ft | VMP-8-23.5-083010 | 8/30/2010 | <0.0053 | U | | 0.00085 | J | | <0.0052 | U | | 0.00085 | J | | <0.0052 | U | | 0.0015 | J | | <0.0061 | U | | <0.006 | U | | <0.006 | U | | <0.019 | U | | 0.0069 | J | |
| | | VMP-8-23.5-111910 | 11/19/2010 | <0.0051 | U | | <0.0051 | U | | <0.005 | U | | <0.005 | U | | <0.005 | U | | <0.0044 | U | | <0.0058 | U | | <0.0057 | U | | <0.0057 | U | | <0.018 | U | | 0.0076 | J | |
| | | VMP-8-23.5-021011 | 2/10/2011 | <0.0054 | U | | <0.0054 | U | | <0.0053 | U | | <0.0053 | U | | <0.0053 | U | | <0.0047 | U | | <0.0062 | U | | <0.0061 | U | | <0.0061 | U | | <0.019 | U | | <0.01 | U | |
| | | VMP-8-23.5-040711 | 4/7/2011 | <0.0051 | U | | <0.0051 | U | | <0.005 | U | | <0.005 | U | | <0.005 | U | | 0.0066 | | | <0.0058 | U | | <0.0057 | U | | <0.0057 | U | | <0.018 | U | | 0.0075 | J | |
| | | VMP-8-23.5-040711-DUP | 4/7/2011 | <0.0081 | U | | 0.0014 | J | | <0.0079 | U | | <0.0079 | U | | <0.0079 | U | | 0.0021 | J | | <0.0092 | U | | <0.0091 | U | | <0.0091 | U | | <0.029 | U | | 0.0073 | J | |
| | | VMP-8-23.5-081011 | 8/10/2011 | <0.0053 | U | | <0.0053 | U | | <0.0052 | U | | <0.0052 | U | | <0.0052 | U | | 0.0021 | J | | <0.0061 | U | | <0.006 | U | | <0.006 | J | U | <0.019 | U | | 0.052 | | |
| | | VMP-8-23.5-110611 | 11/6/2011 | <0.0039 | U | | <0.0039 | U | | <0.0038 | U | | <0.0038 | U | | <0.0038 | U | | 0.0021 | J | | <0.0044 | U | | <0.0043 | U | | <0.0043 | U | | 0.0013 | J | | 0.027 | | |
| | | VMP-8-23.5-012312 | 1/23/2012 | <0.0043 | U | | <0.0043 | U | | <0.0042 | U | | <0.0042 | U | | <0.0042 | U | | <0.0037 | J | U | <0.0049 | U | | <0.0048 | U | | <0.0048 | U | | <0.015 | U | | 0.016 | | |
| | | VMP-8-23.5-041012 | 4/10/2012 | <0.0038 | U | | <0.0038 | U | | <0.0037 | U | | <0.0037 | U | | <0.0037 | U | | 0.00077 | J | | 0.0022 | J | | <0.0042 | U | | 0.0071 | | | <0.013 | U | | <0.007 | U | |
| | | VMP-8-23.5-071312 | 7/13/2012 | <0.0042 | U | | <0.0042 | U | | <0.0041 | U | | <0.0041 | U | | <0.0041 | U | | <0.036 | U | | <0.0048 | U | | <0.0047 | U | | <0.0047 | U | | <0.015 | U | | 0.0046 | J | |
| | | VMP-8-23.5-100412 | 10/4/2012 | <0.0058 | U | | <0.0058 | U | | <0.0057 | U | | <0.0057 | U | | <0.0057 | U | | 0.0028 | J | | <0.0067 | U | | <0.0066 | U | | <0.0066 | U | | <0.021 | U | | 0.0076 | J | |
| | | VMP-8-23.5-012413 | 1/24/2013 | <0.0058 | U | | <0.0058 | U | | <0.0057 | U | | <0.0057 | U | | <0.0057 | U | | <0.05 | J | U | <0.0067 | U | | <0.0066 | U | | <0.0066 | U | | <0.021 | U | | <0.011 | U | |

SEE LAST PAGE OF TABLE FOR NOTES

**TABLE 5**
**CUMULATIVE SUMMARY OF SOIL VAPOR ANALYTICAL DETECTIONS AND SCREENING RESULTS: VILLAGE - VOCS**

| Location | Depth | Sample ID | Sample Date | 1,1-Dichloroethane | | | 1,2-Dichloroethane | | | 1,1-Dichloroethene | | | cis-1,2-Dichloroethene | | | trans-1,2-Dichloroethene | | | Dichloromethane (Methylene chloride) | | | 1,2-Dichloropropane | | | cis-1,3-Dichloropropene | | | trans-1,3-Dichloropropene | | | 1,4-Dioxane | | | Ethanol | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | 690 | | | 0.099 | | | 240 | | | 1100000 | | | 85 | | | 5.6 | | | 0.062 | | | 0.9 | | | 0.9 | | | 0.22 | | | | | |
| | | | | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals |
| VMP-9 | 5 ft | VMP-9-5-082610 | 8/26/2010 | <0.0046 | U | | <0.0046 | U | | <0.0045 | U | | <0.0045 | U | | <0.0045 | U | | 0.0072 | | | <0.0053 | U | | <0.0052 | U | | <0.0052 | U | | 0.008 | J | | 0.015 | | |
| | | VMP-9-5-111910 | 11/19/2010 | <0.0048 | U | | <0.0048 | U | | <0.0047 | U | | <0.0047 | U | | <0.0047 | U | | <0.0041 | J | U | <0.0055 | U | | <0.0054 | U | | <0.0054 | U | | <0.017 | U | | 0.0071 | J | |
| | | VMP-9-5-020811 | 2/8/2011 | <0.0044 | U | | <0.0044 | U | | <0.0044 | U | | <0.0044 | U | | <0.0044 | U | | 0.0013 | J | | <0.0051 | U | | <0.005 | U | | <0.005 | U | | <0.016 | U | | <0.0083 | U | |
| | | VMP-9-5-040611 | 4/6/2011 | <0.012 | U | | <0.012 | U | | <0.012 | U | | <0.012 | U | | <0.012 | U | | 0.011 | | | <0.014 | U | | <0.014 | U | | <0.014 | U | | <0.044 | U | | 0.02 | J | |
| | | VMP-9-5-080211 | 8/2/2011 | <0.24 | U | | <0.24 | U | | <0.23 | U | | <0.23 | U | | <0.23 | U | | <0.2 | U | | <0.27 | U | | <0.27 | U | | <0.27 | U | | <0.85 | U | | <0.44 | U | |
| | | VMP-9-5-110411 | 11/4/2011 | <0.0035 | U | | <0.0035 | U | | <0.0035 | U | | <0.0035 | U | | <0.0035 | U | | 0.0041 | | | <0.004 | U | | <0.004 | U | | <0.004 | J | U | 0.0018 | J | | 0.012 | | |
| | | VMP-9-5-012612 | 1/26/2012 | <0.003 | U | | <0.003 | J | U | <0.003 | U | | <0.003 | U | | <0.003 | U | | <0.0026 | J | U | <0.0034 | U | | <0.0034 | U | | <0.0034 | J | U | <0.011 | U | | 0.0061 | | |
| | | VMP-9-5-041112 | 4/11/2012 | <0.0036 | U | | <0.0036 | U | | <0.0035 | U | | <0.0035 | U | | <0.0035 | U | | 0.00082 | J | | 0.0011 | J | | <0.0041 | U | | <0.0041 | U | | <0.013 | U | | <0.0067 | U | |
| | | VMP-9-5-071312 | 7/13/2012 | <0.0039 | U | | <0.0039 | U | | <0.0038 | U | | <0.0038 | U | | <0.0038 | U | | 0.0018 | J | | <0.0044 | U | | <0.0043 | U | | <0.0043 | U | | <0.014 | U | | 0.12 | | |
| | | VMP-9-5-101012 | 10/10/2012 | <0.0058 | U | | <0.0058 | U | | <0.0057 | U | | <0.0057 | U | | <0.0057 | U | | 0.0029 | J | | <0.0067 | U | | <0.0066 | U | | <0.0066 | U | | <0.021 | UJ | UJ | 0.0025 | J | J |
| | | [4]VMP-9-5-012513 | 1/25/2013 | <0.0057 | U | UJ | <0.0057 | U | UJ | <0.0056 | U | UJ | <0.0056 | U | UJ | <0.0056 | U | UJ | 0.0058 | J | J | <0.0065 | U | UJ | <0.0064 | U | UJ | <0.0064 | U | UJ | <0.02 | U | UJ | 0.005 | J | J |
| | | VMP-9-5-021513 | 2/15/2013 | <0.0056 | U | | <0.0056 | U | | <0.0055 | U | | <0.0055 | U | | <0.0055 | U | | <0.048 | U | | <0.0064 | U | | <0.0063 | U | | <0.0063 | J | U | <0.02 | U | | <0.01 | U | |
| | 11.5 ft | VMP-9-11.5-082610 | 8/26/2010 | <0.1 | U | | <0.1 | U | | <0.1 | U | | <0.1 | U | | <0.1 | U | | <0.089 | U | | <0.12 | U | | <0.12 | U | | <0.12 | U | | <0.37 | U | | <0.19 | U | |
| | | VMP-9-11.5-111910 | 11/19/2010 | <0.3 | U | | <0.3 | U | | <0.3 | U | | <0.3 | U | | <0.3 | U | | 0.32 | | | 0.34 | J | | <0.34 | U | | <0.34 | U | | <1.1 | U | | <0.56 | U | |
| | | VMP-9-11.5-020911 | 2/9/2011 | <0.0054 | U | | <0.0054 | U | | <0.0053 | U | | <0.0053 | U | | <0.0053 | U | | <0.0047 | U | | <0.0062 | U | | <0.0061 | U | | <0.0061 | U | | <0.019 | U | | 0.0059 | J | |
| | | VMP-9-11.5-020911-DUP | 2/9/2011 | <0.0042 | U | | <0.0042 | U | | <0.0041 | U | | <0.0041 | U | | <0.0041 | U | | <0.0036 | U | | <0.0048 | U | | <0.0047 | U | | <0.0047 | U | | <0.015 | U | | 0.009 | | |
| | | VMP-9-11.5-040611 | 4/6/2011 | <0.016 | U | | <0.016 | U | | <0.016 | U | | <0.016 | U | | <0.016 | U | | 0.0069 | J | | <0.018 | U | | <0.018 | U | | <0.018 | U | | <0.057 | U | | 0.017 | J | |
| | | VMP-9-11.5-080211 | 8/2/2011 | <0.36 | U | | <0.36 | U | | <0.35 | U | | <0.35 | U | | <0.35 | U | | <0.3 | U | | <0.41 | U | | <0.4 | U | | <0.4 | U | | <1.3 | U | | <0.66 | U | |
| | | VMP-9-11.5-110411 | 11/4/2011 | <0.0035 | U | | <0.0035 | U | | <0.0035 | U | | <0.0035 | U | | <0.0035 | U | | <0.003 | J | U | <0.004 | U | | <0.004 | U | | <0.004 | U | | <0.013 | U | | 0.014 | | |
| | | VMP-9-11.5-012612 | 1/26/2012 | <0.0031 | U | | <0.0031 | J | U | <0.0031 | U | | <0.0031 | U | | <0.0031 | U | | <0.0027 | J | U | <0.0036 | U | | <0.0035 | J | U | <0.0035 | J | U | <0.011 | U | | 0.026 | | |
| | | VMP-9-11.5-041112 | 4/11/2012 | <0.0037 | U | | <0.0037 | U | | <0.0036 | U | | <0.0036 | U | | <0.0036 | U | | 0.0012 | J | | 0.00078 | J | | <0.0042 | U | | 0.00098 | J | | <0.013 | U | | <0.0069 | U | |
| | | VMP-9-11.5-071312 | 7/13/2012 | <0.0042 | U | | <0.0042 | U | | <0.0041 | U | | <0.0041 | U | | <0.0041 | U | | <0.036 | U | | <0.0048 | U | | <0.0047 | U | | <0.0047 | U | | <0.015 | U | | 0.15 | | |
| | | VMP-9-11.5-101012 | 10/10/2012 | <0.0056 | U | | <0.0056 | U | | <0.0055 | U | | <0.0055 | U | | <0.0055 | U | | 0.0022 | J | | <0.0064 | U | | <0.0063 | U | | <0.0063 | U | | <0.02 | UJ | UJ | 0.011 | | J |
| | | VMP-9-11.5-012513 | 1/25/2013 | <0.0047 | U | | <0.0047 | U | | <0.0046 | U | | <0.0046 | U | | <0.0046 | U | | <0.04 | U | | <0.0054 | U | | <0.0053 | U | | <0.0053 | U | | <0.017 | U | | 0.0036 | J | |
| | | VMP-9-11.5-012513-DUP | 1/25/2013 | <0.0051 | U | | <0.0051 | U | | <0.005 | U | | <0.005 | U | | <0.005 | U | | <0.044 | J | U | <0.0058 | U | | <0.0057 | U | | <0.0057 | U | | <0.018 | U | | <0.0095 | U | |
| | 25.5 ft | VMP-9-25.5-082610 | 8/26/2010 | <0.82 | U | | <0.82 | U | | <0.8 | U | | <0.8 | U | | <0.8 | U | | <0.7 | U | | <0.93 | U | | <0.91 | U | | <0.91 | U | | <2.9 | U | | <1.5 | U | |
| | | VMP-9-25.5-082610-DUP | 8/26/2010 | <0.87 | U | | <0.87 | U | | <0.86 | U | | <0.86 | U | | <0.86 | U | | <0.75 | U | | <1 | U | | <0.98 | U | | <0.98 | U | | <3.1 | U | | <1.6 | U | |
| | | VMP-9-25.5-111910 | 11/19/2010 | <0.93 | U | | <0.93 | U | | <0.91 | U | | <0.91 | U | | <0.91 | U | | 0.44 | J | | <1.1 | U | | <1 | U | | <1 | U | | <3.3 | U | | <1.7 | U | |
| | | VMP-9-25.5-020911 | 2/9/2011 | <0.51 | U | | <0.51 | U | | <0.5 | U | | <0.5 | U | | <0.5 | U | | <0.44 | U | | <0.58 | U | | <0.57 | U | | <0.57 | U | | <1.8 | U | | <0.95 | U | |
| | | VMP-9-25.5-040811 | 4/8/2011 | <0.26 | U | | <0.26 | U | | <0.25 | U | | <0.25 | U | | <0.25 | U | | 0.13 | J | | <0.3 | U | | <0.29 | U | | <0.29 | U | | <0.92 | U | | 0.29 | J | |
| | | VMP-9-25.5-080211 | 8/2/2011 | <0.57 | U | | <0.57 | U | | <0.56 | U | | <0.56 | U | | <0.56 | U | | <0.49 | U | | <0.65 | U | | <0.64 | U | | <0.64 | U | | <2 | U | | <1.1 | U | |
| | | VMP-9-25.5-110711 | 11/7/2011 | <0.5 | U | | <0.5 | U | | <0.49 | U | | <0.49 | U | | <0.49 | U | | 0.53 | | | <0.58 | U | | <0.56 | U | | <0.56 | U | | <1.8 | U | | 0.49 | J | |
| | | VMP-9-25.5-110711-DUP | 11/7/2011 | <0.44 | U | | <0.44 | U | | <0.43 | U | | <0.43 | U | | <0.43 | U | | 0.58 | | | <0.5 | U | | <0.49 | U | | <0.49 | U | | <1.5 | U | | 0.56 | J | |
| | | VMP-9-25.5-012612 | 1/26/2012 | <0.13 | U | | <0.13 | U | | <0.13 | U | | <0.13 | U | | <0.13 | U | | <0.11 | U | | <0.15 | U | | <0.15 | U | | <0.15 | U | | <0.46 | U | | <0.24 | U | |
| | | VMP-9-25.5-041112 | 4/11/2012 | <0.0037 | U | | <0.0037 | U | | <0.0036 | U | | <0.0036 | U | | <0.0036 | U | | <0.032 | U | | 0.0013 | J | | <0.0042 | U | | 0.0011 | J | | <0.013 | U | | <0.0069 | U | |
| | | VMP-9-25.5-071312 | 7/13/2012 | <0.004 | U | | <0.004 | J | U | <0.0039 | U | | <0.0039 | U | | <0.0039 | U | | 0.0027 | J | | <0.0046 | U | | <0.0045 | U | | <0.0045 | J | U | <0.014 | U | | 0.09 | | J |
| | | VMP-9-25.5-071312-Dup | 7/13/2012 | <0.0039 | U | | <0.0039 | U | | <0.0038 | U | | <0.0038 | U | | <0.0038 | U | | <0.033 | J | U | <0.0044 | U | | <0.0043 | U | | <0.0043 | J | U | <0.014 | U | | 0.18 | | J |
| | | VMP-9-25.5-101012 | 10/10/2012 | <0.0053 | U | | <0.0053 | U | | <0.0052 | U | | <0.0052 | U | | <0.0052 | U | | <0.046 | J | U | <0.0061 | U | | <0.006 | U | | <0.006 | U | | <0.019 | UJ | UJ | 0.0043 | J | J |
| | | VMP-9-25.5-013013 | 1/30/2013 | <0.0057 | U | | <0.0057 | U | | <0.0056 | U | | <0.0056 | U | | <0.0056 | U | | <0.049 | J | U | <0.0065 | U | | <0.0064 | U | | <0.0064 | U | | <0.02 | U | | <0.011 | U | |
| | 38.5 ft | VMP-9-38.5-020911 | 2/9/2011 | <0.85 | U | | <0.84 | U | | <0.83 | U | | <0.83 | U | | <0.83 | U | | <0.73 | U | | <0.96 | U | | <0.95 | U | | <0.95 | U | | <3 | U | | <1.6 | U | |
| | | VMP-9-38.5-040811 | 4/8/2011 | <1.1 | U | | <1.1 | U | | <1.1 | U | | <1.1 | U | | <1.1 | U | | 0.53 | J | | <1.3 | U | | <1.3 | U | | <1.3 | U | | <4 | U | | 1.4 | J | |
| | | VMP-9-38.5-012612 | 1/26/2012 | <0.17 | U | | <0.17 | U | | <0.17 | U | | <0.17 | U | | <0.17 | U | | <0.14 | U | | <0.19 | U | | <0.19 | U | | <0.19 | U | | <0.6 | U | | <0.32 | U | |
| | | VMP-9-38.5-041112 | 4/11/2012 | <0.0032 | U | | <0.0032 | U | | <0.0032 | U | | <0.0032 | U | | <0.0032 | U | | 0.017 | J | | 0.001 | J | | <0.0036 | U | | 0.001 | J | | <0.012 | U | | 0.019 | | |
| | | VMP-9-38.5-071312 | 7/13/2012 | <0.0043 | U | | <0.0043 | U | | <0.0042 | U | | <0.0042 | U | | <0.0042 | U | | <0.037 | J | U | <0.0049 | U | | <0.0048 | U | | <0.0048 | U | | <0.015 | U | | 0.19 | | |
| | | VMP-9-38.5-101012 | 10/10/2012 | <0.016 | U | | <0.016 | U | | <0.016 | U | | <0.016 | U | | <0.016 | U | | <0.14 | U | | <0.018 | U | | <0.018 | U | | <0.018 | U | | <0.057 | UJ | UJ | <0.03 | U | UJ |
| | | VMP-9-38.5-013013 | 1/30/2013 | <0.0057 | U | | <0.0057 | U | | <0.0056 | U | | <0.0056 | U | | <0.0056 | U | | <0.049 | J | U | <0.0065 | U | | <0.0064 | U | | <0.0064 | U | | <0.02 | U | | 0.0038 | J | |
| VMP-18 | 8.5 ft | VMP-18-8.5 | 6/18/2010 | <0.005 | U | | <0.005 | U | | <0.005 | U | | <0.005 | U | | <0.005 | U | | 0.0012 | J | | <0.006 | U | | <0.006 | U | | <0.006 | U | | <0.021 | U | | 0.011 | | |
| | | VMP-18-8.5-090710 | 9/7/2010 | <0.0052 | U | | 0.0011 | J | | <0.0051 | U | | <0.0051 | U | | <0.0051 | U | | <0.0045 | U | | <0.006 | U | | <0.0058 | U | | <0.0058 | U | | <0.018 | U | | 0.011 | | |
| | | VMP-18-8.5-111910 | 11/19/2010 | <0.0044 | U | | <0.0044 | U | | <0.0043 | U | | <0.0043 | U | | <0.0043 | U | | <0.0038 | U | | <0.005 | U | | <0.0049 | U | | <0.0049 | U | | 0.0054 | J | | 0.0017 | J | |
| | | VMP-18-8.5-020711 | 2/7/2011 | <0.0048 | U | | <0.0048 | U | | <0.0047 | U | | <0.0047 | U | | <0.0047 | U | | <0.0041 | U | | <0.0055 | U | | <0.0054 | U | | <0.0054 | U | | 0.0023 | J | | 0.022 | | |
| | | VMP-18-8.5-020711-DUP | 2/7/2011 | <0.0046 | U | | <0.0046 | U | | <0.0045 | U | | <0.0045 | U | | <0.0045 | U | | <0.004 | U | | <0.0053 | U | | <0.0052 | U | | <0.0052 | U | | <0.016 | U | | 0.01 | | |
| | | VMP-18-8.5-040711 | 4/7/2011 | <0.0052 | U | | <0.0052 | U | | <0.0051 | U | | <0.0051 | U | | <0.0051 | U | | 0.0021 | J | | 0.0033 | J | | <0.0058 | U | | <0.0058 | U | | 0.0043 | J | | 0.012 | | |
| | | VMP-18-8.5-072811 | 7/28/2011 | <0.0056 | U | | <0.0056 | U | | <0.0055 | U | | <0.0055 | U | | <0.0055 | U | | <0.0048 | U | | <0.0064 | U | | <0.0063 | U | | <0.0063 | U | | <0.02 | U | | 0.079 | | |
| | | VMP-18-8.5-110711 | 11/7/2011 | <0.0036 | U | | <0.0036 | U | | <0.0035 | U | | <0.0035 | U | | <0.0035 | U | | <0.0031 | J | U | <0.0041 | U | | <0.0041 | U | | <0.0041 | U | | <0.013 | U | | 0.021 | | |
| | | VMP-18-8.5-012312 | 1/23/2012 | <0.0039 | U | | <0.0039 | U | | <0.0038 | U | | <0.0038 | U | | <0.0038 | U | | <0.0034 | J | U | <0.0045 | U | | <0.0044 | U | | <0.0044 | U | | <0.014 | U | | 0.012 | | |
| | | VMP-18-8.5-041012 | 4/10/2012 | <0.0041 | U | | <0.0041 | U | | <0.004 | U | | <0.004 | U | | <0.004 | U | | <0.035 | J | U | 0.00094 | J | | <0.0046 | U | | <0.0046 | J | U | <0.014 | U | | 0.014 | | |
| | | VMP-18-8.5-071212 | 7/12/2012 | <0.004 | U | | <0.004 | U | | <0.0039 | U | | <0.0039 | U | | <0.0039 | U | | 0.0066 | J | | <0.0045 | U | | <0.0044 | U | | <0.0044 | U | | <0.014 | U | | 0.12 | | |
| | | VMP-18-8.5-100912 | 10/9/2012 | <0.0053 | U | | <0.0053 | U | | <0.0052 | U | | <0.0052 | U | | <0.0052 | U | | 0.014 | J | | <0.0061 | U | | <0.006 | U | | <0.006 | U | | <0.019 | U | | 0.022 | | |
| | | VMP-18-8.5-012313 | 1/23/2013 | <0.0058 | U | | <0.0058 | U | | <0.0057 | U | | <0.0057 | U | | <0.0057 | U | | <0.05 | J | U | <0.0067 | U | | <0.0066 | U | | <0.0066 | U | | <0.021 | U | | <0.011 | U | |
| VMP-19 | 5 ft | VMP-19-5 | 6/18/2010 | <0.005 | U | | <0.005 | U | | <0.005 | U | | <0.005 | U | | <0.005 | U | | 0.0011 | J | | <0.006 | U | | <0.006 | U | | <0.006 | U | | <0.02 | U | | 0.0064 | J | |
| | | VMP-19-5-090110 | 9/1/2010 | <0.0052 | U | | <0.0052 | U | | <0.0051 | U | | <0.0051 | U | | <0.0051 | U | | <0.0045 | J | U | <0.006 | U | | <0.0058 | U | | <0.0058 | U | | <0.018 | U | | 0.01 | | |
| | | VMP-19-5-111510 | 11/15/2010 | <0.0056 | U | | <0.0056 | U | | <0.0055 | U | | <0.0055 | U | | <0.0055 | U | | 0.0012 | J | | <0.0064 | U | | <0.0063 | U | | <0.0063 | U | | <0.02 | U | | 0.024 | | |
| | | VMP-19-5-020411 | 2/4/2011 | <0.0049 | U | | 0.0009 | J | | <0.0048 | U | | <0.0048 | U | | <0.0048 | U | | <0.0042 | U | | <0.0056 | U | | <0.0055 | U | | <0.0055 | U | | <0.017 | U | | 0.015 | | |
| | | VMP-19-5-040711 | 4/7/2011 | <0.0055 | U | | <0.0055 | U | | <0.0054 | U | | <0.0054 | U | | <0.0054 | U | | 0.00093 | J | | <0.0062 | U | | <0.0061 | U | | <0.0061 | U | | <0.019 | U | | 0.0058 | J | |
| | | VMP-19-5-080911 | 8/9/2011 | <0.006 | U | | <0.006 | J | U | <0.0059 | U | | <0.0059 | U | | <0.0059 | U | | <0.0051 | U | | <0.0068 | U | | <0.0067 | U | | <0.0067 | J | U | <0.021 | U | | 0.047 | | J |
| | | VMP-19-5-080911-DUP | 8/9/2011 | <0.0057 | U | | <0.0057 | J | U | <0.0056 | U | | <0.0056 | U | | <0.0056 | U | | 0.0016 | J | | <0.0065 | U | | <0.0064 | U | | <0.0064 | J | U | <0.02 | U | | 0.078 | | J |
| | | VMP-19-5-110811 | 11/8/2011 | <0.004 | U | | <0.004 | U | | <0.0039 | U | | <0.0039 | U | | <0.0039 | U | | 0.0084 | | | <0.0045 | U | | <0.0044 | U | | <0.0044 | U | | <0.014 | U | | 0.021 | | |
| | | VMP-19-5-012612 | 1/26/2012 | <0.0035 | U | | <0.0035 | U | | <0.0034 | U | | <0.0034 | U | | <0.0034 | U | | 0.0035 | | | <0.004 | U | | <0.0039 | U | | <0.0039 | U | | <0.012 | U | | 0.013 | | |
| | | VMP-19-5-041012 | 4/10/2012 | <0.004 | U | | <0.004 | U | | <0.0039 | U | | <0.0039 | U | | <0.0039 | U | | <0.034 | J | U | 0.0011 | J | | <0.0044 | U | | <0.0044 | J | U | <0.014 | U | | 0.031 | | |
| | | VMP-19-5-071112 | 7/11/2012 | <0.0045 | U | | <0.0045 | U | | <0.0044 | U | | <0.0044 | U | | <0.0044 | U | | 0.0012 | J | | <0.0052 | U | | <0.0051 | U | | <0.0051 | U | | <0.016 | U | | 0.038 | | |
| | | VMP-19-5-100912 | 10/9/2012 | <0.006 | U | | <0.006 | U | | <0.0059 | U | | <0.0059 | U | | <0.0059 | U | | 0.0029 | J | | <0.0068 | U | | <0.0067 | U | | <0.0067 | J | U | <0.021 | U | | <0.011 | U | |
| | | VMP-19-5-013113 | 1/31/2013 | <0.0052 | U | | <0.0052 | U | | <0.0051 | U | | <0.0051 | U | | <0.0051 | U | | <0.045 | J | U | <0.006 | U | | <0.0058 | U | | <0.0058 | U | | <0.018 | U | | 0.022 | | |

SEE LAST PAGE OF TABLE FOR NOTES

**TABLE 5**
**CUMULATIVE SUMMARY OF SOIL VAPOR ANALYTICAL DETECTIONS AND SCREENING RESULTS: VILLAGE - VOCS**

| Location | Depth | Sample ID | Sample Date | 1,1-Dichloroethane | | | 1,2-Dichloroethane | | | 1,1-Dichloroethene | | | cis-1,2-Dichloroethene | | | trans-1,2-Dichloroethene | | | Dichloromethane (Methylene chloride) | | | 1,2-Dichloropropane | | | cis-1,3-Dichloropropene | | | trans-1,3-Dichloropropene | | | 1,4-Dioxane | | | Ethanol | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | 690 | | | 0.099 | | | 240 | | | 1100000 | | | 85 | | | 5.6 | | | 0.062 | | | 0.9 | | | 0.9 | | | 0.22 | | | | | |
| | | | | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals |
| VMP-20 | 5 ft | VMP-20-5-031411 | 3/14/2011 | <0.0049 | U | | <0.0049 | U | | <0.0048 | U | | <0.0048 | U | | <0.0048 | U | | <0.0042 | J | U | <0.0056 | U | | <0.0055 | U | | <0.0055 | U | | <0.017 | U | | 0.11 | J | J |
| | | VMP-20-5-041511 | 4/15/2011 | <0.054 | U | | <0.054 | U | | <0.053 | U | | <0.053 | U | | <0.053 | U | | <0.046 | U | UJ | <0.061 | U | | <0.06 | U | | <0.06 | U | | <0.19 | U | | <0.1 | U | |
| | | VMP-20-5-072511 | 7/25/2011 | <0.0057 | U | | <0.0057 | U | | <0.0056 | U | | <0.0056 | U | | <0.0056 | U | UJ | <0.0049 | U | | <0.0065 | U | | <0.0064 | U | | <0.0064 | J | U | 0.0052 | J | | 0.018 | | |
| | | VMP-20-5-110111 | 11/1/2011 | <0.0032 | U | | <0.0032 | U | | <0.0032 | U | | <0.0032 | U | | <0.0032 | U | | <0.0028 | J | U | <0.0037 | U | | <0.0036 | U | | <0.0036 | U | | <0.012 | U | | 0.033 | | |
| | | VMP-20-5-012312 | 1/23/2012 | <0.016 | U | | <0.016 | U | | <0.015 | U | | <0.015 | U | | <0.015 | U | | <0.013 | U | | <0.018 | U | | <0.018 | U | | <0.018 | U | | <0.056 | U | | 0.021 | J | |
| | | VMP-20-5-041012 | 4/10/2012 | <0.0035 | U | | <0.0035 | U | | <0.0035 | U | | <0.0035 | U | | <0.0035 | U | | <0.03 | J | U | 0.00084 | J | | <0.004 | U | | <0.004 | U | | 0.0038 | J | | 0.05 | | |
| | | VMP-20-5-071112 | 7/11/2012 | <0.0047 | U | | <0.0047 | U | | <0.0046 | U | | <0.0046 | U | | <0.0046 | U | | 0.0016 | J | | <0.0054 | U | | <0.0053 | U | | <0.0053 | U | | <0.017 | U | | 0.0061 | J | |
| | | VMP-20-5-073112 | 7/31/2012 | <0.004 | U | | <0.004 | U | | <0.0039 | U | | <0.0039 | U | | <0.0039 | U | | <0.034 | J | U | <0.0045 | U | | <0.0044 | U | | <0.0044 | U | | <0.014 | U | | 0.037 | | |
| | | VMP-20-5-100412 | 10/4/2012 | <0.0058 | U | | <0.0058 | U | | <0.0057 | U | | <0.0057 | U | | <0.0057 | U | | <0.05 | J | U | <0.0067 | U | | <0.0066 | U | | <0.0066 | U | | <0.021 | U | | <0.011 | U | |
| | | VMP-20-5-020713 | 2/7/2013 | <0.005 | U | | <0.005 | U | | <0.0049 | U | | <0.0049 | U | | <0.0049 | U | | <0.043 | J | U | <0.0057 | U | | <0.0056 | U | | <0.0056 | U | | <0.018 | U | | 0.0064 | J | |
| | 10 ft | VMP-20-10-031411 | 3/14/2011 | <0.0049 | U | | <0.0049 | U | | <0.0048 | U | | <0.0048 | U | | <0.0048 | U | | <0.0042 | U | | <0.0056 | U | | <0.0055 | U | | <0.0055 | U | | <0.017 | U | | 0.0034 | J | J |
| | | VMP-20-10-041511 | 4/15/2011 | <0.049 | U | | <0.049 | U | | <0.048 | U | | <0.048 | U | | <0.048 | U | | 0.018 | J | J | <0.056 | U | | <0.055 | U | | <0.055 | U | | <0.17 | U | | 0.012 | J | |
| | | VMP-20-10-072511 | 7/25/2011 | <0.0052 | U | | <0.0052 | U | | <0.0051 | U | | <0.0051 | U | | <0.0051 | U | | <0.0045 | J | U | <0.006 | U | | <0.0058 | U | | <0.0058 | J | UJ | <0.018 | U | | 0.013 | | |
| | | VMP-20-10-110111 | 11/1/2011 | <0.0035 | U | | <0.0035 | U | | <0.0034 | U | | <0.0034 | U | | <0.0034 | U | | 0.0037 | | | <0.004 | U | | <0.0039 | U | | <0.0039 | U | | <0.012 | U | | 0.01 | | |
| | | VMP-20-10-012312 | 1/23/2012 | <0.0036 | U | | <0.0036 | U | | <0.0035 | U | | <0.0035 | U | | <0.0035 | U | | <0.0031 | J | U | <0.0041 | U | | <0.0041 | U | | <0.0041 | J | U | <0.013 | U | | 0.016 | | |
| | | VMP-20-10-041012 | 4/10/2012 | <0.0035 | U | | <0.0035 | U | | <0.0034 | U | | <0.0034 | U | | <0.0034 | U | | <0.03 | J | U | 0.001 | J | | <0.0039 | U | | <0.0039 | U | | <0.012 | U | | 0.071 | | |
| | | VMP-20-10-071112 | 7/11/2012 | <0.004 | U | | <0.004 | U | | <0.0039 | U | | <0.0039 | U | | <0.0039 | U | | 0.0014 | J | | <0.0045 | U | | <0.0044 | U | | <0.0044 | U | | <0.014 | U | | 0.0053 | J | |
| | | VMP-20-10-100412 | 10/4/2012 | <0.0054 | U | | <0.0054 | U | | <0.0053 | U | | <0.0053 | U | | <0.0053 | U | | <0.047 | J | U | <0.0062 | U | | <0.0061 | U | | <0.0061 | U | | <0.019 | U | | <0.01 | U | |
| | | VMP-20-10-012213 | 1/22/2013 | <0.005 | U | | <0.005 | U | | <0.0049 | U | | <0.0049 | U | | <0.0049 | U | | <0.043 | J | U | <0.0057 | U | | <0.0056 | U | | <0.0056 | U | | <0.018 | U | | 0.004 | J | |
| | 25 ft | VMP-20-25-031411 | 3/14/2011 | <0.0048 | U | | <0.0048 | U | | <0.0047 | U | | <0.0047 | U | | <0.0047 | U | | <0.0042 | U | | <0.0055 | U | | <0.0054 | U | | <0.0054 | U | | <0.017 | U | | 0.0045 | J | J |
| | | VMP-20-25-041511 | 4/15/2011 | <0.056 | U | | <0.056 | U | | <0.055 | U | | <0.055 | U | | <0.055 | U | | <0.048 | U | UJ | <0.064 | U | | <0.063 | U | | <0.063 | U | | <0.2 | U | | <0.1 | U | |
| | | VMP-20-25-072611 | 7/26/2011 | <0.37 | U | | <0.37 | U | | <0.36 | U | | <0.36 | U | | <0.36 | U | | <0.32 | U | | <0.42 | U | | <0.42 | U | | <0.42 | U | UJ | <1.3 | U | | <0.69 | U | |
| | | VMP-20-25-110511 | 11/5/2011 | <0.0034 | U | | <0.0034 | U | | <0.0033 | U | | <0.0033 | U | | <0.0033 | U | | 0.0017 | J | | <0.0039 | U | | <0.0038 | U | | <0.0038 | U | | <0.012 | U | | 0.011 | | |
| | | VMP-20-25-012312 | 1/23/2012 | <0.0038 | U | | <0.0038 | U | | <0.0037 | U | | <0.0037 | U | | <0.0037 | U | | <0.0032 | J | U | <0.0043 | U | | <0.0042 | U | | <0.0042 | U | | <0.013 | U | | 0.022 | | |
| | | VMP-20-25-041012 | 4/10/2012 | <0.0035 | U | | <0.0035 | U | | <0.0035 | U | | <0.0035 | U | | <0.0035 | U | | <0.03 | J | U | <0.004 | U | | <0.004 | U | | <0.004 | U | | <0.013 | U | | 0.047 | | J |
| | | VMP-20-25-041012-Dup | 4/10/2012 | <0.0036 | U | | <0.0036 | U | | <0.0035 | U | | <0.0035 | U | | <0.0035 | U | | 0.0009 | J | | <0.0041 | U | | <0.0041 | U | | <0.0041 | U | | <0.013 | U | | 0.03 | | J |
| | | VMP-20-25-071112 | 7/11/2012 | <0.0041 | U | | <0.0041 | U | | <0.004 | U | | <0.004 | U | | <0.004 | U | | <0.035 | U | | <0.0046 | U | | <0.0046 | U | | <0.0046 | U | | <0.014 | U | | 0.017 | | |
| | | VMP-20-25-100412 | 10/4/2012 | <0.006 | U | | <0.006 | U | | <0.0059 | U | | <0.0059 | U | | <0.0059 | U | | <0.051 | J | U | <0.0068 | U | | <0.0067 | U | | <0.0067 | U | | <0.021 | U | | 0.011 | J | |
| | | VMP-20-25-012213 | 1/22/2013 | <0.005 | U | | <0.005 | U | | <0.0049 | U | | <0.0049 | U | | <0.0049 | U | | <0.043 | J | U | <0.0057 | U | | <0.0056 | U | | <0.0056 | U | | <0.018 | U | | <0.0093 | U | |
| | 39.5 ft | VMP-20-39.5-100412 | 10/4/2012 | <1.5 | U | | <1.5 | U | | <1.4 | U | | <1.4 | U | | <1.4 | U | | 1 | J | | <1.7 | U | | <1.6 | U | | <1.6 | U | | <5.2 | U | | <2.7 | U | |
| | | VMP-20-39.5-012313 | 1/23/2013 | <0.84 | U | | <0.84 | U | | <0.82 | U | | <0.82 | U | | <0.82 | U | | 0.13 | J | | <0.95 | U | | <0.94 | U | | <0.94 | U | | <3 | U | | <1.6 | U | |
| VMP-21 | 5 ft | VMP-21-5-020911 | 2/9/2011 | <1.9 | U | | <1.9 | U | | <1.8 | U | | <1.8 | U | | <1.8 | U | | <1.6 | U | | <2.2 | U | | <2.1 | U | | <2.1 | U | | <6.7 | U | | <3.5 | U | |
| | | VMP-21-5-020911-DUP | 2/9/2011 | <3.2 | U | | <3.2 | U | | <3.2 | U | | <3.2 | U | | <3.2 | U | | <2.8 | U | | <3.7 | U | | <3.6 | U | | <3.6 | U | | <11 | U | | <6 | U | |
| | | VMP-21-5-041311 | 4/13/2011 | <0.0053 | U | | <0.0053 | U | | <0.0052 | U | | <0.0052 | U | | <0.0052 | U | | 0.00076 | J | | <0.0061 | U | | <0.006 | U | | <0.006 | U | | <0.019 | U | | <0.0099 | J | U |
| | | VMP-21-5-072511 | 7/25/2011 | <0.0056 | U | | <0.0056 | U | | <0.0055 | U | | <0.0055 | U | | <0.0055 | U | | <0.0048 | J | U | <0.0064 | U | | <0.0063 | J | UJ | 0.0076 | J | | 0.017 | | |
| | | VMP-21-5-110111 | 11/1/2011 | <0.0046 | U | | <0.0046 | U | | <0.0045 | U | | <0.0045 | U | | <0.0045 | U | | <0.004 | J | U | <0.0053 | U | | <0.0052 | U | | <0.0052 | U | | <0.016 | U | | 0.019 | | |
| | | VMP-21-5-012312 | 1/23/2012 | 0.0034 | J | | <0.0039 | U | | <0.0038 | U | | <0.0038 | U | | <0.0038 | U | | <0.0034 | J | U | <0.0045 | U | | <0.0044 | U | | <0.0044 | J | U | <0.014 | U | | 0.017 | | |
| | | VMP-21-5-012312-DUP | 1/23/2012 | 0.00082 | J | | <0.0036 | U | | <0.0035 | U | | <0.0035 | U | | <0.0035 | U | | <0.0031 | J | U | <0.0041 | U | | <0.0041 | U | | <0.0041 | U | | <0.013 | U | | 0.0088 | | |
| | | VMP-21-5-042412 | 4/24/2012 | <0.0074 | U | | <0.0074 | U | | <0.0072 | U | | <0.0072 | U | | <0.0072 | U | | <0.064 | J | U | <0.0084 | U | | <0.0083 | U | | <0.0083 | U | | <0.026 | U | | 0.04 | | |
| | | VMP-21-5-071012 | 7/10/2012 | <0.0043 | U | | <0.0043 | U | | <0.0042 | U | | <0.0042 | U | | <0.0042 | U | | <0.037 | U | | <0.0049 | U | | <0.0048 | U | | <0.0048 | U | | <0.015 | U | | 0.15 | | |
| | | VMP-21-5-100412 | 10/4/2012 | <0.0063 | U | | <0.0063 | U | | <0.0062 | U | | <0.0062 | U | | <0.0062 | U | | <0.054 | J | U | <0.0072 | U | | <0.007 | U | | <0.007 | U | | <0.022 | U | | 0.018 | | |
| | | VMP-21-5-020613 | 2/6/2013 | <0.0057 | U | | <0.0057 | U | | <0.0056 | U | | <0.0056 | U | | <0.0056 | U | | <0.049 | U | | <0.0065 | U | | <0.0064 | U | | <0.0064 | U | | <0.02 | U | | 0.0062 | J | |
| | 10 ft | VMP-21-10-021011 | 2/10/2011 | <1.7 | U | | <1.7 | U | | <1.7 | U | | <1.7 | U | | <1.7 | U | | <1.4 | U | | <1.9 | U | | <1.9 | U | | <1.9 | U | | <6 | U | | <3.2 | U | |
| | | VMP-21-10-041311 | 4/13/2011 | <0.21 | U | | <0.21 | U | | <0.21 | U | | <0.21 | U | | <0.21 | U | | 0.072 | J | | <0.24 | U | | <0.24 | U | | <0.24 | U | | <0.76 | U | | <0.4 | U | |
| | | VMP-21-10-072511 | 7/25/2011 | <0.012 | U | | <0.012 | U | | <0.012 | U | | <0.012 | U | | <0.012 | U | | 0.0093 | J | | <0.014 | U | | <0.013 | U | | <0.013 | J | UJ | <0.042 | U | | 0.085 | | |
| | | VMP-21-10-110111 | 11/1/2011 | <0.0035 | U | | <0.0035 | U | | <0.0034 | U | | <0.0034 | U | | <0.0034 | U | | 0.0038 | | | <0.004 | U | | <0.0039 | U | | <0.0039 | U | | <0.012 | U | | 0.025 | | |
| | | VMP-21-10-012312 | 1/23/2012 | <0.0039 | U | | <0.0039 | U | | <0.0038 | U | | <0.0038 | U | | <0.0038 | U | | 0.0047 | | | <0.0045 | U | | <0.0044 | U | | <0.0044 | J | U | <0.014 | U | | 0.015 | | |
| | | VMP-21-10-040912 | 4/9/2012 | <0.0035 | U | | <0.0035 | U | | <0.0035 | U | | <0.0035 | U | | <0.0035 | U | | 0.017 | J | | 0.0012 | J | | <0.004 | U | | <0.004 | U | | <0.013 | U | | 0.031 | | |
| | | VMP-21-10-071012 | 7/10/2012 | <0.0041 | U | | <0.0041 | U | | <0.004 | U | | <0.004 | U | | <0.004 | U | | 0.0014 | J | | <0.0046 | U | | <0.0046 | U | | <0.0046 | U | | <0.014 | U | | 0.0075 | | |
| | | VMP-21-10-100412 | 10/4/2012 | <0.0057 | U | | <0.0057 | U | | <0.0056 | U | | <0.0056 | U | | <0.0056 | U | | <0.049 | J | U | <0.0065 | U | | <0.0064 | U | | <0.0064 | U | | <0.02 | U | | 0.025 | | |
| | | VMP-21-10-020513 | 2/5/2013 | <0.0054 | U | | <0.0054 | U | | <0.0053 | U | | <0.0053 | U | | <0.0053 | U | | <0.047 | J | U | <0.0062 | U | | <0.0061 | U | | <0.0061 | U | | <0.019 | U | | 0.0033 | J | |
| | | VMP-21-10-020513-DUP | 2/5/2013 | <0.0051 | U | | <0.0051 | U | | <0.005 | U | | <0.005 | U | | <0.005 | U | | <0.044 | J | U | <0.0058 | U | | <0.0057 | U | | <0.0057 | U | | <0.018 | U | | 0.002 | J | |
| | 25 ft | VMP-21-25-021011 | 2/10/2011 | <4.7 | U | | <4.7 | U | | <4.6 | U | | <4.6 | U | | <4.6 | U | | <4 | U | | <5.4 | U | | <5.3 | U | | <5.3 | U | | <17 | U | | <8.8 | U | |
| | | VMP-21-25-041411 | 4/14/2011 | <16 | U | | <16 | U | | <16 | U | | <16 | U | | <16 | U | | <14 | U | UJ | <19 | U | | <18 | U | | <18 | U | | <59 | U | | <31 | U | |
| | | VMP-21-25-041411-DUP | 4/14/2011 | <16 | U | | <16 | U | | <16 | U | | <16 | U | | <16 | U | | <14 | U | UJ | <19 | U | | <18 | U | | <18 | U | | <59 | U | | <31 | U | |
| | | VMP-21-25-072611 | 7/26/2011 | <5.3 | U | | <5.3 | U | | <5.2 | U | | <5.2 | U | | <5.2 | U | | <4.6 | U | | <6.1 | U | | <6 | U | | <6 | U | UJ | <19 | U | | <9.9 | U | |
| | | VMP-21-25-110511 | 11/5/2011 | <3.4 | U | | <3.4 | U | | <3.3 | U | | <3.3 | U | | <3.3 | U | | 2.4 | J | | <3.9 | U | | <3.8 | U | | <3.8 | U | | <12 | U | | 2.9 | J | |
| | | VMP-21-25-012412 | 1/24/2012 | <0.047 | U | | <0.047 | U | | <0.046 | U | | <0.046 | U | | <0.046 | U | | <0.04 | U | | <0.054 | U | | <0.053 | U | | <0.053 | U | | <0.17 | U | | <0.087 | J | U |
| | | VMP-21-25-040912 | 4/9/2012 | <0.0037 | U | | <0.0037 | U | | <0.0036 | U | | <0.0036 | U | | <0.0036 | U | | <0.032 | U | | <0.0042 | U | | <0.0042 | U | | <0.0042 | U | | <0.013 | U | | 0.018 | | |
| | | VMP-21-25-071112 | 7/11/2012 | <0.0037 | U | | <0.0037 | U | | <0.0036 | U | | <0.0036 | U | | <0.0036 | U | | 0.0029 | J | | <0.0042 | U | | <0.0042 | U | | <0.0042 | U | | <0.013 | U | | 0.016 | | |
| | | VMP-21-25-100412 | 10/4/2012 | <0.0058 | U | | <0.0058 | U | | <0.0057 | U | | <0.0057 | U | | <0.0057 | U | | <0.05 | U | | <0.0067 | U | | <0.0066 | U | | <0.0066 | U | | <0.021 | U | | 0.018 | | |
| | | VMP-21-25-020513 | 2/5/2013 | <0.0052 | U | | <0.0052 | U | | <0.0051 | U | | <0.0051 | U | | <0.0051 | U | | <0.045 | J | U | <0.006 | U | | <0.0058 | U | | <0.0058 | U | | <0.018 | U | | 0.0044 | J | |
| | | VMP-21-25-020513-DUP | 2/5/2013 | <0.0054 | U | | <0.0054 | U | | <0.0053 | U | | <0.0053 | U | | <0.0053 | U | | <0.047 | J | U | <0.0062 | U | | <0.0061 | U | | <0.0061 | U | | <0.019 | U | | 0.0037 | J | |
| | 33 ft | VMP-21-33-021011 | 2/10/2011 | <4.7 | U | | <4.7 | U | | <4.6 | U | | <4.6 | U | | <4.6 | U | | <4 | U | | <5.4 | U | | <5.3 | U | | <5.3 | U | | <17 | U | | <8.8 | U | |
| | | VMP-21-33-041411 | 4/14/2011 | <16 | U | | <16 | U | | <16 | U | | <16 | U | | <16 | U | | <14 | U | UJ | <18 | U | | <18 | U | | <18 | U | | <57 | U | | 3.8 | J | |
| | | VMP-21-33-110511 | 11/5/2011 | <0.77 | U | | <0.77 | U | | <0.76 | U | | <0.76 | U | | <0.76 | U | | 0.54 | J | | <0.88 | U | | <0.87 | U | | <0.87 | U | | <2.8 | U | | 0.5 | J | |
| | | VMP-21-33-012412 | 1/24/2012 | <0.11 | U | | <0.11 | U | | <0.11 | U | | <0.11 | U | | <0.11 | U | | <0.095 | U | | <0.13 | U | | <0.12 | U | | <0.12 | U | | <0.39 | U | | <0.21 | U | |
| | | VMP-21-33-042412 | 4/24/2012 | <0.0038 | U | | <0.0038 | U | | <0.0037 | U | | <0.0037 | U | | <0.0037 | U | | <0.032 | J | U | <0.0043 | U | | <0.0042 | U | | <0.0042 | U | | <0.013 | U | | 0.013 | | |
| | | VMP-21-33-071112 | 7/11/2012 | <0.004 | U | | <0.004 | U | | <0.0039 | U | | <0.0039 | U | | <0.0039 | U | | 0.0013 | J | | <0.0045 | U | | <0.0044 | U | | <0.0044 | U | | <0.014 | U | | 0.0067 | J | |
| | | VMP-21-33-100412 | 10/4/2012 | <0.0057 | U | | <0.0057 | U | | <0.0056 | U | | <0.0056 | U | | <0.0056 | U | | <0.049 | J | U | <0.0065 | U | | <0.0064 | U | | <0.0064 | U | | <0.02 | U | | 0.021 | | |
| | | VMP-21-33-020513 | 2/5/2013 | <0.0053 | U | | <0.0053 | U | | <0.0052 | U | | <0.0052 | U | | <0.0052 | U | | <0.046 | J | U | <0.0061 | U | | <0.006 | U | | <0.006 | U | | <0.019 | U | | <0.0099 | U | |

SEE LAST PAGE OF TABLE FOR NOTES

**TABLE 5**
**CUMULATIVE SUMMARY OF SOIL VAPOR ANALYTICAL DETECTIONS AND SCREENING RESULTS: VILLAGE - VOCS**

| Location | Depth | Sample ID | Sample Date | 1,1-Dichloroethane | | | 1,2-Dichloroethane | | | 1,1-Dichloroethene | | | cis-1,2-Dichloroethene | | | trans-1,2-Dichloroethene | | | Dichloromethane (Methylene chloride) | | | 1,2-Dichloropropane | | | cis-1,3-Dichloropropene | | | trans-1,3-Dichloropropene | | | 1,4-Dioxane | | | Ethanol | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | 690 | | | 0.099 | | | 240 | | | 1100000 | | | 85 | | | 5.6 | | | 0.062 | | | 0.9 | | | 0.9 | | | 0.22 | | | | | |
| | | | | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals |
| VMP-22 | 5 ft | VMP-22-5-021111 | 2/11/2011 | <0.1 | U | | <0.1 | U | | <0.1 | U | | <0.1 | U | | <0.1 | U | | <0.089 | U | | <0.12 | U | | <0.12 | U | | <0.12 | U | | <0.37 | U | | <0.19 | U | |
| | | VMP-22-5-041811 | 4/18/2011 | <0.051 | U | | <0.051 | U | | <0.05 | U | | <0.05 | U | | <0.05 | U | | <0.044 | U | UJ | <0.058 | U | | <0.057 | U | | <0.057 | U | | <0.18 | U | | <0.095 | U | |
| | | VMP-22-5-072611 | 7/26/2011 | <0.006 | U | | <0.006 | J | U | <0.0059 | U | | <0.0059 | U | | <0.0059 | U | | 0.0022 | J | | <0.0068 | U | | <0.0067 | U | | <0.0067 | J | UJ | <0.021 | U | | 0.029 | | |
| | | VMP-22-5-110111 | 11/1/2011 | <0.0034 | U | | <0.0034 | U | | <0.0033 | U | | <0.0033 | U | | <0.0033 | U | | <0.0029 | J | U | <0.0039 | U | | <0.0038 | U | | <0.0038 | U | | 0.07 | | | 0.023 | | |
| | | VMP-22-5-012412 | 1/24/2012 | <0.0036 | U | | <0.0036 | U | | <0.0035 | U | | <0.0035 | U | | <0.0035 | U | | <0.0031 | J | U | <0.0041 | U | | <0.004 | U | | <0.004 | J | U | <0.013 | U | | 0.0094 | | J |
| | | VMP-22-5-040912 | 4/9/2012 | <0.004 | U | | <0.004 | U | | <0.0039 | U | | <0.0039 | U | | <0.0039 | U | | 0.012 | J | | <0.0045 | U | | <0.0044 | U | | <0.0044 | U | | <0.014 | U | | <0.0074 | U | |
| | | VMP-22-5-070912 | 7/9/2012 | <0.0044 | U | | <0.0044 | U | | <0.0043 | U | | <0.0043 | U | | <0.0043 | U | | <0.038 | U | | <0.005 | U | | <0.0049 | U | | <0.0049 | U | | <0.016 | U | | 0.0053 | J | |
| | | VMP-22-5-100312 | 10/3/2012 | <0.0051 | U | | <0.0051 | U | | <0.005 | U | | <0.005 | U | | <0.005 | U | | <0.044 | U | | <0.0058 | U | | <0.0057 | U | | <0.0057 | U | | <0.018 | U | | 0.016 | | J |
| | | VMP-22-5-100312-Dup | 10/3/2012 | <0.0046 | U | | <0.0046 | U | | <0.0045 | U | | <0.0045 | U | | <0.0045 | U | | <0.04 | J | U | <0.0053 | U | | <0.0052 | U | | <0.0052 | U | | <0.016 | U | | 0.056 | | J |
| | | VMP-22-5-012413 | 1/24/2013 | <0.0052 | U | | <0.0052 | U | | <0.0051 | U | | <0.0051 | U | | <0.0051 | U | | <0.045 | J | U | <0.006 | U | | <0.0058 | U | | <0.0058 | U | | <0.018 | U | | 0.0021 | J | |
| | 10 ft | VMP-22-10-021111 | 2/11/2011 | <0.049 | U | | <0.049 | U | | <0.048 | U | | <0.048 | U | | <0.048 | U | | <0.042 | U | | <0.056 | U | | <0.055 | U | | <0.055 | U | | <0.18 | U | | <0.092 | U | |
| | | VMP-22-10-041811 | 4/18/2011 | <0.053 | U | | <0.053 | U | | <0.052 | U | | <0.052 | U | | <0.052 | U | | <0.045 | U | UJ | <0.06 | U | | <0.059 | U | | <0.059 | U | | <0.19 | U | | <0.098 | U | |
| | | VMP-22-10-072611 | 7/26/2011 | <0.0061 | U | | <0.0061 | U | | <0.006 | U | | <0.006 | U | | <0.006 | U | | <0.0053 | J | U | <0.007 | U | | <0.0069 | U | | <0.0069 | J | UJ | <0.022 | U | | 0.056 | | |
| | | VMP-22-10-072611-DUP | 7/26/2011 | <0.0072 | U | | <0.0072 | U | | <0.007 | U | | <0.007 | U | | <0.007 | U | | <0.0062 | J | U | <0.0082 | U | | <0.0081 | U | | <0.0081 | J | UJ | <0.026 | U | | 0.039 | | |
| | | VMP-22-10-110211 | 11/2/2011 | <0.0035 | U | | <0.0035 | U | | <0.0034 | U | | <0.0034 | U | | <0.0034 | U | | <0.003 | J | U | <0.004 | U | | <0.0039 | U | | <0.0039 | U | | <0.012 | U | | 0.01 | | |
| | | VMP-22-10-012412 | 1/24/2012 | <0.0039 | U | | <0.0039 | U | | <0.0038 | U | | <0.0038 | U | | <0.0038 | U | | <0.0034 | J | U | <0.0045 | U | | <0.0044 | U | | <0.0044 | J | U | <0.014 | U | | 0.023 | | |
| | | VMP-22-10-040912 | 4/9/2012 | <0.0039 | U | | <0.0039 | U | | <0.0038 | U | | <0.0038 | U | | <0.0038 | U | | 0.011 | J | | <0.0044 | U | | <0.0044 | U | | <0.0044 | U | | <0.014 | U | | <0.0073 | U | |
| | | VMP-22-10-070912 | 7/9/2012 | <0.0044 | U | | <0.0044 | U | | <0.0043 | U | | <0.0043 | U | | <0.0043 | U | | <0.038 | U | | <0.005 | U | | <0.0049 | U | | <0.0049 | U | | <0.016 | U | | 0.0062 | J | |
| | | VMP-22-10-070912-Dup | 7/9/2012 | <0.0043 | U | | <0.0043 | U | | <0.0042 | U | | <0.0042 | U | | <0.0042 | U | | <0.037 | U | | <0.0049 | U | | <0.0048 | U | | <0.0048 | U | | <0.015 | U | | 0.0072 | J | |
| | | VMP-22-10-100312 | 10/3/2012 | <0.0049 | U | | <0.0049 | U | | <0.0048 | U | | <0.0048 | U | | <0.0048 | U | | <0.042 | J | U | <0.0056 | U | | <0.0055 | U | | <0.0055 | U | | <0.017 | U | | 0.042 | | |
| | | VMP-22-10-012413 | 1/24/2013 | <0.0056 | U | | <0.0056 | U | | <0.0055 | U | | <0.0055 | U | | <0.0055 | U | | <0.048 | J | U | <0.0064 | U | | <0.0063 | U | | <0.0063 | U | | <0.02 | U | | 0.0022 | J | |
| | 18 ft | VMP-22-18-021111 | 2/11/2011 | <0.86 | U | | <0.86 | U | | <0.84 | U | | <0.84 | U | | <0.84 | U | | <0.74 | U | | <0.98 | U | | <0.96 | U | | <0.96 | U | | <3.1 | U | | <1.6 | U | |
| | | VMP-22-18-041811 | 4/18/2011 | <3.6 | U | | <3.6 | U | | <3.6 | U | | <3.6 | U | | <3.6 | U | | <3.1 | U | UJ | <4.2 | U | | <4.1 | U | | <4.1 | U | | <13 | U | | <6.8 | U | |
| | | VMP-22-18-072611 | 7/26/2011 | <1.9 | U | | <1.9 | U | | <1.8 | U | | <1.8 | U | | <1.8 | U | | <1.6 | U | | <2.1 | U | | <2.1 | U | | <2.1 | U | UJ | <6.6 | U | | <3.5 | U | |
| | | VMP-22-18-110511 | 11/5/2011 | <0.0037 | U | | <0.0037 | U | | <0.0036 | U | | <0.0036 | U | | <0.0036 | U | | 0.0018 | J | | <0.0042 | U | | <0.0042 | U | | <0.0042 | U | | 0.0014 | J | | 0.012 | | |
| | | VMP-22-18-012412 | 1/24/2012 | <0.034 | U | | <0.034 | U | | <0.033 | U | | <0.033 | U | | <0.033 | U | | <0.029 | U | | <0.039 | U | | <0.038 | U | | <0.038 | U | | <0.12 | U | | <0.063 | U | |
| | | VMP-22-18-040912 | 4/9/2012 | <0.0041 | U | | <0.0041 | U | | <0.004 | U | | <0.004 | U | | <0.004 | U | | <0.035 | U | | <0.0046 | U | | <0.0046 | U | | <0.0046 | U | | <0.014 | U | | <0.0076 | U | |
| | | VMP-22-18-070912 | 7/9/2012 | <0.0043 | U | | <0.0043 | U | | <0.0042 | U | | <0.0042 | U | | <0.0042 | U | | <0.037 | U | | <0.0049 | U | | <0.0048 | U | | <0.0048 | U | | <0.015 | U | | 0.0036 | J | |
| | | VMP-22-18-100412 | 10/4/2012 | <0.0058 | U | | <0.0058 | U | | <0.0057 | U | | <0.0057 | U | | <0.0057 | U | | <0.05 | J | U | <0.0067 | U | | <0.0066 | U | | <0.0066 | U | | <0.021 | U | | 0.0087 | J | |
| | | VMP-22-18-012413 | 1/24/2013 | <0.0056 | U | | <0.0056 | U | | <0.0055 | U | | <0.0055 | U | | <0.0055 | U | | <0.048 | J | U | <0.0064 | U | | <0.0063 | U | | <0.0063 | U | | <0.02 | U | | 0.0024 | J | |
| | 38 ft | VMP-22-38-041811 | 4/18/2011 | <11 | U | | <11 | U | | <11 | U | | <11 | U | | <11 | U | | <9.6 | U | UJ | <13 | U | | <12 | U | | <12 | U | | <40 | U | | <21 | U | |
| | | VMP-22-38-012512 | 1/25/2012 | <0.034 | U | | <0.034 | U | | <0.033 | U | | <0.033 | U | | <0.033 | U | | <0.029 | U | | <0.039 | U | | <0.038 | U | | <0.038 | U | | <0.12 | U | | <0.063 | U | |
| | | VMP-22-38-040912 | 4/9/2012 | <0.0039 | U | | <0.0039 | U | | <0.0039 | U | | <0.0039 | U | | <0.0039 | U | | <0.034 | U | | <0.0045 | U | | <0.0044 | U | | <0.0044 | U | | <0.014 | U | | <0.0073 | U | |
| | | VMP-22-38-070912 | 7/9/2012 | <0.0042 | U | | <0.0042 | U | | <0.0041 | U | | <0.0041 | U | | <0.0041 | U | | 0.0012 | J | | <0.0048 | U | | <0.0047 | U | | <0.0047 | U | | <0.015 | U | | 0.006 | J | |
| | | VMP-22-38-100412 | 10/4/2012 | <0.0061 | U | | <0.0061 | U | | <0.006 | U | | <0.006 | U | | <0.006 | U | | 0.0036 | J | | <0.007 | U | | <0.0069 | U | | 0.0026 | J | | <0.022 | U | | <0.011 | U | |
| | | VMP-22-38-012413 | 1/24/2013 | <0.0054 | U | | <0.0054 | U | | <0.0053 | U | | <0.0053 | U | | <0.0053 | U | | <0.047 | U | | <0.0062 | U | | <0.0061 | U | | <0.0061 | U | | <0.019 | U | | 0.0029 | J | |
| VMP-23 | 5 ft | VMP-23-5-021511 | 2/15/2011 | <0.0053 | U | | <0.0053 | U | | <0.0052 | U | | <0.0052 | U | | <0.0052 | U | | <0.0046 | U | | <0.0061 | U | | <0.006 | U | | <0.006 | U | | <0.019 | U | | 0.014 | | |
| | | VMP-23-5-042111 | 4/21/2011 | <0.046 | U | | <0.046 | U | | <0.045 | U | | <0.045 | U | | <0.045 | U | | <0.04 | U | | <0.053 | U | | <0.052 | U | | <0.052 | U | | <0.16 | U | | <0.086 | U | |
| | | VMP-23-5-072711 | 7/27/2011 | <0.0053 | U | | <0.0053 | U | | <0.0052 | U | | <0.0052 | U | | <0.0052 | U | | 0.0063 | | | <0.0061 | U | | <0.006 | U | | <0.006 | U | | 0.0088 | J | | 0.058 | | |
| | | VMP-23-5-110211 | 11/2/2011 | <0.0038 | U | | <0.0038 | U | | <0.0037 | U | | <0.0037 | U | | <0.0037 | U | | <0.0032 | J | U | <0.0043 | U | | <0.0042 | U | | <0.0042 | U | | <0.013 | U | | 0.025 | | |
| | | VMP-23-5-012512 | 1/25/2012 | <0.0032 | U | | <0.0032 | U | | <0.0031 | U | | <0.0031 | U | | <0.0031 | U | | 0.0015 | J | | <0.0036 | U | | <0.0036 | U | | <0.0036 | U | | <0.011 | U | | 0.013 | | |
| | | VMP-23-5-040912 | 4/9/2012 | <0.0039 | U | | <0.0039 | U | | <0.0038 | U | | <0.0038 | U | | <0.0038 | U | | 0.0096 | J | | <0.0044 | U | | <0.0043 | U | | <0.0043 | U | | <0.014 | U | | 0.01 | | |
| | | VMP-23-5-070912 | 7/9/2012 | <0.0035 | U | | <0.0035 | U | | <0.0034 | U | | <0.0034 | U | | <0.0034 | U | | 0.0048 | J | | <0.004 | U | | <0.0039 | U | | <0.0039 | U | | <0.012 | U | | <0.0064 | U | |
| | | VMP-23-5-100312 | 10/3/2012 | <0.0058 | U | | <0.0058 | U | | <0.0057 | U | | <0.0057 | U | | <0.0057 | U | | 0.0029 | J | | <0.0067 | U | | <0.0066 | U | | 0.013 | | | <0.021 | U | | 0.0065 | J | |
| | | VMP-23-5-012413 | 1/24/2013 | <0.005 | U | | <0.005 | U | | <0.0049 | U | | <0.0049 | U | | <0.0049 | U | | <0.043 | J | U | <0.0057 | U | | <0.0056 | U | | <0.0056 | U | | <0.018 | U | | 0.0016 | J | |
| | 10 ft | VMP-23-10-021511 | 2/15/2011 | <0.0055 | U | | <0.0055 | U | | <0.0054 | U | | <0.0054 | U | | <0.0054 | U | | <0.0047 | U | | <0.0063 | U | | <0.0062 | U | | <0.0062 | U | | <0.018 | U | | 0.0028 | J | | <0.01 | U | |
| | | VMP-23-10-042111 | 4/21/2011 | <0.056 | U | | <0.056 | U | | <0.055 | U | | <0.055 | U | | <0.055 | U | | <0.048 | U | | <0.064 | U | | <0.063 | U | | <0.063 | U | | <0.2 | U | | <0.1 | U | | <0.1 | U | |
| | | VMP-23-10-072711 | 7/27/2011 | <0.0051 | U | | <0.0051 | U | | <0.005 | U | | <0.005 | U | | <0.005 | U | | <0.0044 | U | | <0.0058 | U | | <0.0057 | U | | <0.0057 | U | | <0.018 | U | | <0.0095 | U | | | |
| | | VMP-23-10-110211 | 11/2/2011 | <0.0037 | U | | <0.0037 | U | | <0.0036 | U | | <0.0036 | U | | <0.0036 | U | | <0.0032 | U | | <0.0042 | U | | <0.0042 | U | | <0.0042 | U | | <0.013 | U | | 0.03 | | | | |
| | | VMP-23-10-012512 | 1/25/2012 | <0.0031 | U | | <0.0031 | U | | <0.0031 | U | | <0.0031 | U | | <0.0031 | U | | 0.0037 | | | <0.0036 | U | | <0.0035 | U | | <0.0035 | U | | <0.011 | U | | 0.016 | | | | |
| | | VMP-23-10-040912 | 4/9/2012 | <0.0039 | U | | <0.0039 | U | | <0.0039 | U | | <0.0039 | U | | <0.0039 | U | | 0.013 | J | | <0.0045 | U | | <0.0044 | U | | <0.0044 | U | | <0.014 | U | | 0.018 | | | | |
| | | VMP-23-10-040912-Dup | 4/9/2012 | <0.004 | U | | 0.0028 | J | | 0.002 | J | | <0.0039 | U | | <0.0039 | U | | 0.027 | J | | <0.0045 | U | | <0.0044 | U | | <0.0044 | U | | <0.014 | U | | 0.013 | | | | |
| | | VMP-23-10-070912 | 7/9/2012 | <0.0031 | U | | <0.0031 | U | | <0.0031 | U | | <0.0031 | U | | <0.0031 | U | | 0.0071 | J | | <0.0036 | U | | <0.0035 | U | | <0.0035 | U | | <0.011 | U | | 0.0068 | | | | |
| | | VMP-23-10-100312 | 10/3/2012 | <0.0063 | U | | <0.0063 | U | | <0.0062 | U | | <0.0062 | U | | <0.0062 | U | | 0.0038 | J | | <0.0072 | U | | <0.007 | U | | <0.007 | U | | <0.022 | U | | <0.012 | U | | | |
| | | VMP-23-10-012413 | 1/24/2013 | <0.005 | U | | <0.005 | U | | <0.0049 | U | | <0.0049 | U | | <0.0049 | U | | <0.043 | J | U | <0.0057 | U | | <0.0056 | U | | <0.0056 | U | | <0.018 | U | | 0.0029 | J | | | |
| | 25 ft | VMP-23-25-021511 | 2/15/2011 | <0.0051 | U | | <0.0051 | U | | <0.005 | U | | <0.005 | U | | <0.005 | U | | <0.0044 | U | | <0.0058 | U | | <0.0057 | U | | <0.0057 | U | | <0.018 | U | | <0.0095 | U | | | |
| | | VMP-23-25-042111 | 4/21/2011 | <0.052 | U | | <0.052 | U | | <0.051 | U | | <0.051 | U | | <0.051 | U | | <0.045 | U | | <0.06 | U | | <0.058 | U | | <0.058 | U | | <0.18 | U | | <0.097 | U | | | |
| | | VMP-23-25-072711 | 7/27/2011 | <0.0058 | U | | <0.0058 | U | | <0.0057 | U | | <0.0057 | U | | <0.0057 | U | | <0.005 | U | | <0.0067 | U | | <0.0066 | U | | <0.0066 | U | | 0.0057 | J | | 0.036 | | | | |
| | | VMP-23-25-110511 | 11/5/2011 | <0.0037 | U | | <0.0037 | U | | <0.0036 | U | | <0.0036 | U | | <0.0036 | U | | 0.0052 | | | <0.0042 | U | | <0.0042 | U | | <0.0042 | U | | <0.013 | U | | 0.016 | | | | |
| | | VMP-23-25-012512 | 1/25/2012 | <0.0033 | U | | <0.0033 | U | | <0.0032 | U | | <0.0032 | U | | <0.0032 | U | | 0.0015 | J | | <0.0038 | U | | <0.0037 | U | | <0.0037 | U | | <0.012 | U | | 0.01 | | | | |
| | | VMP-23-25-040912 | 4/9/2012 | <0.0039 | U | | <0.0039 | U | | <0.0038 | U | | <0.0038 | U | | <0.0038 | U | | 0.018 | J | | <0.0044 | U | | <0.0043 | U | | <0.0043 | U | | <0.014 | U | | 0.18 | | | | |
| | | VMP-23-25-071012 | 7/10/2012 | <0.0049 | U | | <0.0049 | U | | <0.0048 | U | | <0.0048 | U | | <0.0048 | U | | 0.0017 | J | | <0.0056 | U | | <0.0055 | U | | <0.0055 | U | | <0.018 | U | | <0.0092 | U | | | |
| | | VMP-23-25-100312 | 10/3/2012 | <0.0061 | U | | <0.0061 | U | | <0.006 | U | | <0.006 | U | | <0.006 | U | | 0.0039 | J | | <0.007 | U | | <0.0069 | U | | <0.0069 | U | | <0.022 | U | | 0.006 | J | | | |
| | | VMP-23-25-012413 | 1/24/2013 | <0.0051 | U | | <0.0051 | U | | <0.005 | U | | <0.005 | U | | <0.005 | U | | <0.044 | J | U | <0.0058 | U | | <0.0057 | U | | <0.0057 | U | | <0.018 | U | | 0.0033 | J | | | |
| | 40 ft | VMP-23-40-071012 | 7/10/2012 | <0.0042 | U | | <0.0042 | U | | <0.0041 | U | | <0.0041 | U | | <0.0041 | U | | 0.0014 | J | | <0.0048 | U | | <0.0047 | U | | <0.0047 | U | | <0.015 | U | | <0.0078 | U | | | |
| | | VMP-23-40-100312 | 10/3/2012 | <0.0057 | U | | <0.0057 | U | | <0.0056 | U | | <0.0056 | U | | <0.0056 | U | | 0.0035 | J | | <0.0065 | U | | <0.0064 | U | | <0.0064 | U | | <0.02 | U | | 0.011 | | | | |
| | | VMP-23-40-012413 | 1/24/2013 | <0.0052 | U | | <0.0052 | U | | <0.0051 | U | | <0.0051 | U | | <0.0051 | U | | <0.045 | U | | <0.006 | U | | <0.0058 | U | | <0.0058 | U | | <0.018 | U | | 0.0013 | J | | | |

SEE LAST PAGE OF TABLE FOR NOTES

**TABLE 5**
**CUMULATIVE SUMMARY OF SOIL VAPOR ANALYTICAL DETECTIONS AND SCREENING RESULTS: VILLAGE - VOCS**

| Location | Depth | Sample ID | Sample Date | 1,1-Dichloroethane | | | 1,2-Dichloroethane | | | 1,1-Dichloroethene | | | cis-1,2-Dichloroethene | | | trans-1,2-Dichloroethene | | | Dichloromethane (Methylene chloride) | | | 1,2-Dichloropropane | | | cis-1,3-Dichloropropene | | | trans-1,3-Dichloropropene | | | 1,4-Dioxane | | | Ethanol | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | 690 | | | 0.099 | | | 240 | | | 1100000 | | | 85 | | | 5.6 | | | 0.062 | | | 0.9 | | | 0.9 | | | 0.22 | | | | | |
| | | | | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals |
| VMP-24 | 5 ft | VMP-24-5-021611 | 2/16/2011 | <0.0057 | U | | <0.0057 | U | | <0.0056 | U | | <0.0056 | U | | <0.0056 | U | | 0.0018 | J | | <0.0065 | U | | <0.0064 | U | | <0.0064 | U | | <0.02 | U | | 0.0093 | J | J |
| | | VMP-24-5-040811 | 4/8/2011 | <0.061 | U | | <0.061 | U | | <0.06 | U | | <0.06 | U | | <0.06 | U | | 0.011 | J | | <0.07 | U | | <0.068 | U | | <0.068 | U | | <0.22 | U | | <0.11 | U | |
| | | VMP-24-5-072811 | 7/28/2011 | <0.0057 | U | | <0.0057 | U | | <0.0056 | U | | <0.0056 | U | | <0.0056 | U | | <0.0049 | U | | <0.0065 | U | | <0.0064 | U | | <0.0064 | U | | <0.02 | U | | 0.04 | | |
| | | VMP-24-5-110211 | 11/2/2011 | <0.0038 | U | | <0.0038 | U | | <0.0037 | U | | <0.0037 | U | | <0.0037 | U | | <0.0032 | J | U | <0.0043 | U | | <0.0042 | U | | <0.0042 | U | | <0.013 | U | | 0.016 | | |
| | | VMP-24-5-110211-DUP | 11/2/2011 | <0.0053 | U | | <0.0053 | U | | <0.0052 | U | | <0.0052 | U | | <0.0052 | U | | 0.0034 | J | | <0.006 | U | | <0.0059 | U | | <0.0059 | U | | <0.019 | U | | 0.017 | | |
| | | VMP-24-5-012512 | 1/25/2012 | <0.0032 | U | | <0.0032 | U | | <0.0032 | U | | <0.0032 | U | | <0.0032 | U | | 0.0011 | J | | <0.0037 | U | | <0.0036 | U | | <0.0036 | U | | <0.012 | U | | 0.007 | | |
| | | VMP-24-5-040912 | 4/9/2012 | <0.0039 | U | | <0.0039 | U | | <0.0038 | U | | <0.0038 | U | | <0.0038 | U | | <0.033 | U | | <0.0044 | U | | <0.0043 | U | | <0.0043 | U | | <0.014 | U | | 0.087 | | |
| | | VMP-24-5-071212 | 7/12/2012 | <0.0037 | U | | <0.0037 | U | | <0.0036 | U | | <0.0036 | U | | <0.0036 | U | | 0.0018 | J | | <0.0042 | U | | <0.0042 | U | | <0.0042 | U | | <0.013 | U | | <0.0069 | U | |
| | | VMP-24-5-101912 | 10/19/2012 | <0.0057 | U | | <0.0057 | U | | <0.0056 | U | | <0.0056 | U | | <0.0056 | U | | <0.049 | U | | <0.0065 | U | | <0.0064 | U | | <0.0064 | U | | <0.02 | U | | 0.01 | J | |
| | | VMP-24-5-012313 | 1/23/2013 | <0.0051 | U | | <0.0051 | U | | <0.005 | U | | <0.005 | U | | <0.005 | U | | <0.044 | U | | <0.0058 | U | | <0.0057 | U | | <0.0057 | U | | <0.018 | U | | 0.0048 | J | |
| | 10 ft | VMP-24-10-021711 | 2/17/2011 | <0.0054 | U | | <0.0054 | U | | <0.0053 | U | | <0.0053 | U | | <0.0053 | U | | <0.0047 | U | | <0.0062 | U | | <0.0061 | U | | <0.0061 | U | | <0.019 | U | | 0.024 | J | J |
| | | VMP-24-10-041111 | 4/11/2011 | <0.01 | U | | <0.01 | U | | <0.01 | U | | <0.01 | U | | <0.01 | U | | 0.0022 | J | | <0.012 | U | | <0.011 | U | | <0.011 | U | | <0.036 | U | | 0.0097 | J | |
| | | VMP-24-10-072811 | 7/28/2011 | <0.0056 | U | | <0.0056 | U | | <0.0055 | U | | <0.0055 | U | | <0.0055 | U | | 0.0062 | | | <0.0064 | U | | <0.0063 | U | | 0.002 | J | | <0.02 | U | | 0.059 | | |
| | | VMP-24-10-110211 | 11/2/2011 | <0.0033 | U | | <0.0033 | U | | <0.0032 | U | | <0.0032 | U | | <0.0032 | U | | <0.0028 | J | U | <0.0038 | U | | <0.0037 | U | | <0.0037 | U | | <0.012 | U | | 0.0081 | | |
| | | VMP-24-10-012512 | 1/25/2012 | <0.0031 | U | | <0.0031 | U | | <0.0031 | U | | <0.0031 | U | | <0.0031 | U | | 0.006 | | | <0.0036 | U | | <0.0035 | U | | <0.0035 | U | | <0.011 | U | | 0.0088 | | |
| | | VMP-24-10-041012 | 4/10/2012 | <0.0037 | U | | <0.0037 | U | | <0.0036 | U | | <0.0036 | U | | <0.0036 | U | | <0.032 | U | | <0.0042 | U | | <0.0042 | U | | <0.0042 | U | | <0.013 | U | | 0.027 | | |
| | | VMP-24-10-071212 | 7/12/2012 | <0.0043 | U | | <0.0043 | U | | <0.0042 | U | | <0.0042 | U | | <0.0042 | U | | <0.037 | U | | <0.0049 | U | | <0.0048 | U | | <0.0048 | U | | <0.015 | U | | 0.042 | | |
| | | VMP-24-10-100912 | 10/9/2012 | <0.0053 | U | | <0.0053 | U | | <0.0052 | U | | <0.0052 | U | | <0.0052 | U | | 0.0028 | J | | <0.0061 | U | | <0.006 | U | | <0.006 | U | | <0.019 | U | | 0.036 | | |
| | | VMP-24-10-012313 | 1/23/2013 | <0.0056 | U | | <0.0056 | U | | <0.0055 | U | | <0.0055 | U | | <0.0055 | U | | <0.048 | J | U | <0.0064 | U | | <0.0063 | U | | <0.0063 | U | | <0.02 | U | | 0.0076 | J | |
| | 22 ft | VMP-24-22-021711 | 2/17/2011 | <0.0054 | U | | <0.0054 | U | | <0.0053 | U | | <0.0053 | U | | <0.0053 | U | | <0.0047 | U | | <0.0062 | U | | <0.0061 | U | | <0.0061 | U | | <0.019 | U | | 0.024 | J | J |
| | | VMP-24-22-041111 | 4/11/2011 | <0.0051 | U | | <0.0051 | U | | <0.005 | U | | <0.005 | U | | <0.005 | U | | 0.0023 | J | | <0.0058 | U | | <0.0057 | U | | <0.0057 | U | | <0.018 | U | | <0.0095 | J | U |
| | | VMP-24-22-072811 | 7/28/2011 | <0.0051 | U | | <0.0051 | U | | <0.005 | U | | <0.005 | U | | <0.005 | U | | <0.0044 | U | | <0.0058 | U | | <0.0057 | U | | <0.0057 | U | | <0.018 | U | | 0.034 | | |
| | | VMP-24-22-072811-Dup | 7/28/2011 | <0.0058 | U | | <0.0058 | U | | <0.0057 | U | | <0.0057 | U | | <0.0057 | U | | <0.005 | U | | <0.0067 | U | | <0.0066 | U | | <0.0066 | U | | <0.021 | U | | 0.028 | | |
| | | VMP-24-22-110611 | 11/6/2011 | <0.0035 | U | | <0.0035 | U | | <0.0035 | U | | <0.0035 | U | | <0.0035 | U | | 0.0082 | | | <0.004 | U | | <0.004 | U | | <0.004 | U | | <0.013 | U | | 0.031 | | |
| | | VMP-24-22-012512 | 1/25/2012 | <0.0033 | U | | <0.0033 | U | | <0.0032 | U | | <0.0032 | U | | <0.0032 | U | | 0.001 | J | | <0.0038 | U | | <0.0037 | U | | <0.0037 | U | | <0.012 | U | | 0.023 | | |
| | | VMP-24-22-041012 | 4/10/2012 | <0.0036 | U | | <0.0036 | U | | <0.0035 | U | | <0.0035 | U | | <0.0035 | U | | 0.009 | J | | <0.0041 | U | | <0.0041 | U | | <0.0041 | U | | <0.013 | U | | 0.03 | | |
| | | VMP-24-22-071212 | 7/12/2012 | <0.0044 | U | | <0.0044 | U | | <0.0043 | U | | <0.0043 | U | | <0.0043 | U | | <0.038 | U | | <0.005 | U | | <0.0049 | U | | <0.0049 | U | | 0.015 | J | | 0.033 | | |
| | | VMP-24-22-100912 | 10/9/2012 | <0.0054 | U | | <0.0054 | U | | <0.0053 | U | | <0.0053 | U | | <0.0053 | U | | 0.0024 | J | | <0.0062 | U | | <0.0061 | U | | <0.0061 | U | | <0.019 | U | | <0.01 | U | |
| | | VMP-24-22-012313 | 1/23/2013 | <0.0057 | U | | <0.0057 | U | | <0.0056 | U | | <0.0056 | U | | <0.0056 | U | | <0.049 | J | U | <0.0065 | U | | <0.0064 | U | | <0.0064 | U | | <0.02 | U | | 0.0039 | J | |
| | 34 ft | VMP-24-34-021711 | 2/17/2011 | <0.0054 | U | | <0.0054 | U | | <0.0053 | U | | <0.0053 | U | | <0.0053 | U | | <0.0047 | U | | <0.0062 | U | | <0.0061 | U | | <0.0061 | U | | <0.019 | U | | 0.032 | J | J |
| | | VMP-24-34-041111 | 4/11/2011 | <0.0049 | U | | <0.0049 | U | | <0.0048 | U | | <0.0048 | U | | <0.0048 | U | | 0.004 | J | | <0.0056 | U | | <0.0055 | U | | <0.0055 | U | | <0.017 | U | | 0.011 | | |
| | | VMP-24-34-072811 | 7/28/2011 | <0.0043 | U | | <0.0043 | U | | <0.0042 | U | | <0.0042 | U | | <0.0042 | U | | 0.0018 | J | | <0.0049 | U | | <0.0048 | U | | <0.0048 | U | | <0.015 | U | | 0.034 | | |
| | | VMP-24-34-110611 | 11/6/2011 | <0.0028 | U | | <0.0028 | U | | <0.0027 | U | | <0.0027 | U | | <0.0027 | U | | 0.0023 | J | | <0.0031 | U | | <0.0031 | U | | <0.0031 | U | | <0.0098 | U | | 0.038 | | |
| | | VMP-24-34-012512 | 1/25/2012 | <0.0034 | U | | <0.0034 | U | | <0.0033 | U | | <0.0033 | U | | <0.0033 | U | | 0.0013 | J | | <0.0039 | U | | <0.0038 | U | | <0.0038 | U | | <0.012 | U | | 0.016 | | |
| | | VMP-24-34-041012 | 4/10/2012 | <0.0038 | U | | <0.0038 | U | | <0.0037 | U | | <0.0037 | U | | <0.0037 | U | | <0.032 | U | | <0.0043 | U | | <0.0042 | U | | <0.0042 | U | | <0.013 | U | | 0.048 | | |
| | | VMP-24-34-071212 | 7/12/2012 | <0.0036 | U | | <0.0036 | U | | <0.0035 | U | | <0.0035 | U | | <0.0035 | U | | <0.031 | U | | <0.0041 | U | | <0.0041 | U | | <0.0041 | U | | <0.013 | U | | 0.06 | | |
| | | VMP-24-34-100912 | 10/9/2012 | <0.0056 | U | | <0.0056 | U | | <0.0055 | U | | <0.0055 | U | | <0.0055 | U | | 0.0017 | J | | <0.0064 | U | | <0.0063 | U | | <0.0063 | U | | <0.02 | U | | 0.0059 | J | |
| | | VMP-24-34-012313 | 1/23/2013 | <0.0058 | U | | <0.0058 | U | | <0.0057 | U | | <0.0057 | U | | <0.0057 | U | | <0.05 | J | U | <0.0067 | U | | <0.0066 | U | | <0.0066 | U | | <0.021 | U | | 0.0022 | J | |
| VMP-31 | 5 ft | VMP-31-5-042512 | 4/25/2012 | <0.0039 | U | | <0.0039 | U | | <0.0038 | U | | <0.0038 | U | | <0.0038 | U | | <0.033 | J | U | <0.0044 | U | | <0.0043 | U | | <0.0043 | J | U | <0.014 | U | | 0.083 | | |
| | | VMP-31-5-072012 | 7/20/2012 | <0.0039 | U | | <0.0039 | U | | <0.0038 | U | | <0.0038 | U | | <0.0038 | U | | 0.0021 | J | | <0.0044 | U | | <0.0043 | U | | <0.0043 | U | | <0.014 | U | | 0.033 | | |
| | | VMP-31-5-102612 | 10/26/2012 | <0.0056 | U | | <0.0056 | U | | <0.0055 | U | | <0.0055 | U | | <0.0055 | U | | <0.048 | U | | <0.0064 | U | | <0.0063 | U | | <0.0063 | U | | <0.02 | U | | 0.04 | | |
| | | VMP-31-5-021113 | 2/11/2013 | <0.0052 | U | | <0.0052 | U | | <0.0051 | U | | <0.0051 | U | | <0.0051 | U | | <0.045 | U | | <0.006 | U | | <0.0058 | U | | <0.0058 | U | | <0.018 | U | | 0.018 | | |
| | 10 ft | VMP-31-10-042512 | 4/25/2012 | <0.0052 | U | | <0.0052 | U | | <0.005 | U | | <0.005 | U | | <0.005 | U | | <0.044 | J | U | <0.0059 | U | | <0.0058 | U | | <0.0058 | U | | <0.018 | U | | 0.083 | | |
| | | VMP-31-10-072612 | 7/26/2012 | <0.0039 | U | | <0.0039 | U | | <0.0038 | U | | <0.0039 | U | | <0.0039 | U | | <0.034 | J | U | <0.0045 | U | | <0.0044 | U | | <0.0044 | U | | <0.014 | U | | 0.012 | | |
| | | VMP-31-10-102612 | 10/26/2012 | <0.006 | U | | <0.006 | U | | <0.0059 | U | | <0.0059 | U | | <0.0059 | U | | <0.051 | J | U | <0.0068 | U | | <0.0067 | U | | <0.0067 | U | | <0.021 | U | | 0.049 | | |
| | | VMP-31-10-021313 | 2/13/2013 | <0.0057 | U | | <0.0057 | U | | <0.0056 | U | | <0.0056 | U | | <0.0056 | U | | <0.049 | J | U | <0.0065 | U | | <0.0064 | U | | <0.0064 | J | U | <0.02 | U | | 0.0079 | J | |
| | 20 ft | VMP-31-20-101912 | 10/19/2012 | <5.6 | U | | <5.6 | U | | <5.5 | U | | <5.5 | U | | <5.5 | U | | <4.8 | U | | <6.4 | U | | <6.3 | U | | <6.3 | U | | <20 | U | | <10 | U | |
| | | VMP-31-20-021113 | 2/11/2013 | <0.08 | U | | <0.08 | U | | <0.078 | U | | <0.078 | U | | <0.078 | U | | <0.068 | U | | <0.091 | U | | <0.089 | U | | <0.089 | U | | 0.05 | J | | 0.42 | | |
| | 30 ft | VMP-31-30-042512 | 4/25/2012 | <2 | U | | <2 | U | | <1.9 | U | | <1.9 | U | | <1.9 | U | | <1.7 | U | | <2.3 | U | | <2.2 | U | | <2.2 | U | | <7.1 | U | | <3.7 | U | |
| | | VMP-31-30-042512-Dup | 4/25/2012 | <2 | U | | <2 | U | | <1.9 | U | | <1.9 | U | | <1.9 | U | | <1.7 | U | | <2.3 | U | | <2.2 | U | | <2.2 | U | | <7.1 | U | | <3.7 | U | |
| | | VMP-31-30-072012 | 7/20/2012 | <0.39 | U | | <0.39 | U | | <0.38 | U | | <0.38 | U | | <0.38 | U | | <3.3 | U | | <0.44 | U | | <0.43 | U | | <0.43 | U | | <1.4 | U | | <0.72 | U | |
| | | VMP-31-30-101912 | 10/19/2012 | <0.35 | U | | <0.35 | U | | <0.34 | U | | <0.34 | U | | <0.34 | U | | <0.3 | U | | <0.4 | U | | <0.39 | U | | <0.39 | U | | <1.2 | U | | <0.65 | U | |
| | | VMP-31-30-021113 | 2/11/2013 | <5.7 | U | | <5.7 | U | | <5.6 | U | | <5.6 | U | | <5.6 | U | | <4.9 | U | | <6.5 | U | | <6.4 | U | | <6.4 | U | | <20 | U | | <11 | U | |
| VMP-32 | 5 ft | VMP-32-5-042512 | 4/25/2012 | <0.0038 | U | | <0.0038 | J | U | <0.0037 | U | | <0.0037 | U | | <0.0037 | U | | <0.032 | J | U | <0.0043 | U | | <0.0042 | U | | <0.0042 | J | U | <0.013 | U | | 0.08 | | |
| | | VMP-32-5-072012 | 7/20/2012 | <0.0034 | U | | <0.0034 | U | | <0.0033 | U | | <0.0033 | U | | <0.0033 | U | | 0.0012 | J | | <0.0039 | U | | <0.0038 | U | | <0.0038 | U | | <0.012 | U | | <0.0063 | U | |
| | | VMP-32-5-101812 | 10/18/2012 | <0.0064 | U | | <0.0064 | U | | <0.0063 | U | | <0.0063 | U | | <0.0063 | U | | <0.055 | J | U | <0.0074 | U | | <0.0072 | U | | <0.0072 | U | | <0.023 | U | | 0.0073 | J | |
| | | VMP-32-5-020513 | 2/5/2013 | <0.0051 | U | | <0.0051 | U | | <0.005 | U | | <0.005 | U | | <0.005 | U | | <0.044 | J | U | <0.0058 | U | | <0.0057 | U | | <0.0057 | U | | <0.018 | U | | 0.012 | | |
| | 10 ft | VMP-32-10-041612 | 4/16/2012 | <0.0035 | U | | <0.0035 | J | U | <0.0034 | U | | <0.0034 | U | | <0.0034 | U | | <0.03 | J | U | <0.004 | U | | <0.0039 | U | | <0.0039 | U | | <0.012 | U | | 0.017 | | J |
| | | VMP-32-10-072012 | 7/20/2012 | <0.004 | U | | <0.004 | U | | <0.0039 | U | | <0.0039 | U | | <0.0039 | U | | 0.0014 | J | | <0.0045 | U | | <0.0044 | U | | <0.0044 | U | | 0.0079 | J | | 0.012 | | |
| | | VMP-32-10-101812 | 10/18/2012 | <0.006 | U | | <0.006 | U | | <0.0059 | U | | <0.0059 | U | | <0.0059 | U | | <0.051 | U | | <0.0068 | U | | <0.0067 | U | | <0.0067 | U | | <0.021 | U | | 0.0059 | J | |
| | | VMP-32-10-020513 | 2/5/2013 | <0.0051 | U | | <0.0051 | U | | <0.005 | U | | <0.005 | U | | <0.005 | U | | <0.044 | J | U | <0.0058 | U | | <0.0057 | U | | <0.0057 | U | | <0.018 | U | | 0.014 | | |
| | 20 ft | VMP-32-20-041612 | 4/16/2012 | <0.079 | U | | <0.079 | U | | <0.078 | U | | <0.078 | U | | <0.078 | U | | 0.073 | J | | <0.09 | U | | <0.089 | U | | <0.089 | U | | <0.28 | U | | 0.18 | | J |
| | | VMP-32-20-072012 | 7/20/2012 | <0.0039 | U | | <0.0039 | U | | <0.0038 | U | | <0.0038 | U | | <0.0038 | U | | 0.0014 | J | | <0.0044 | U | | <0.0043 | U | | <0.0043 | U | | <0.014 | U | | <0.0072 | U | |
| | | VMP-32-20-101812 | 10/18/2012 | <0.0056 | U | | <0.0056 | U | | <0.0055 | U | | <0.0055 | U | | <0.0055 | U | | <0.048 | U | | <0.0064 | U | | <0.0063 | U | | <0.0063 | U | | <0.02 | U | | 0.0054 | J | |
| | | VMP-32-20-020513 | 2/5/2013 | <0.0057 | U | | <0.0057 | U | | <0.0056 | U | | <0.0056 | U | | <0.0056 | U | | <0.049 | J | U | <0.0065 | U | | <0.0064 | U | | <0.0064 | U | | <0.02 | U | | 0.0035 | J | |
| | 30 ft | VMP-32-30-041612 | 4/16/2012 | <1.9 | U | | <1.9 | U | | <1.8 | U | | <1.8 | U | | <1.8 | U | | <1.6 | U | | <2.2 | U | | <2.1 | U | | <2.1 | U | | <6.7 | U | | <3.5 | U | |
| | | VMP-32-30-072012 | 7/20/2012 | <3.9 | U | | <3.9 | U | | <3.8 | U | | <3.8 | U | | <3.8 | U | | <3.4 | U | | <4.4 | U | | <4.4 | U | | <4.4 | U | | <14 | U | | <7.3 | U | |
| | | VMP-32-30-101812 | 10/18/2012 | <0.22 | U | | <0.22 | U | | <0.22 | U | | <0.22 | U | | <0.22 | U | | <0.19 | U | | <0.25 | U | | <0.25 | U | | <0.25 | U | | <0.79 | U | | <0.41 | U | |
| | | VMP-32-30-020513 | 2/5/2013 | <0.23 | U | | <0.23 | U | | <0.22 | U | | <0.22 | U | | <0.22 | U | | 0.1 | J | | <0.26 | U | | <0.26 | U | | <0.26 | U | | <0.81 | U | | <0.42 | U | |

SEE LAST PAGE OF TABLE FOR NOTES

**TABLE 5**
**CUMULATIVE SUMMARY OF SOIL VAPOR ANALYTICAL DETECTIONS AND SCREENING RESULTS: VILLAGE - VOCS**

| Location | Depth | Sample ID | Sample Date | 1,1-Dichloroethane | | | 1,2-Dichloroethane | | | 1,1-Dichloroethene | | | cis-1,2-Dichloroethene | | | trans-1,2-Dichloroethene | | | Dichloromethane (Methylene chloride) | | | 1,2-Dichloropropane | | | cis-1,3-Dichloropropene | | | trans-1,3-Dichloropropene | | | 1,4-Dioxane | | | Ethanol | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | 690 | | | 0.099 | | | 240 | | | 1100000 | | | 85 | | | 5.6 | | | 0.062 | | | 0.9 | | | 0.9 | | | 0.22 | | | | | |
| | | | | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals |
| VMP-42 | 10 ft | VMP-42-10-041812 | 4/18/2012 | <0.0035 | U | | <0.0035 | J | U | <0.0034 | U | | <0.0034 | U | | <0.0034 | U | | 0.0012 | J | | <0.004 | U | | <0.0039 | U | | <0.0039 | U | | <0.012 | U | | 0.022 | | J |
| | | VMP-42-10-041812-Dup | 4/18/2012 | <0.0035 | U | | <0.0035 | J | U | <0.0035 | U | | <0.0035 | U | | <0.0035 | U | | <0.03 | J | U | <0.004 | U | | <0.004 | U | | <0.004 | U | | <0.013 | U | | 0.048 | | J |
| | | VMP-42-20-041812 | 4/18/2012 | <1.8 | U | | <1.8 | U | | <1.8 | U | | <1.8 | U | | <1.8 | U | | 1.6 | J | | <2.1 | U | | <2 | U | | <2 | U | | <6.4 | U | | 4.4 | | J |
| | | VMP-42-10-071912 | 7/19/2012 | <0.0039 | U | | <0.0039 | U | | <0.0038 | U | | <0.0038 | U | | <0.0038 | U | | 0.003 | J | | <0.0044 | U | | <0.0043 | U | | <0.0043 | U | | <0.014 | U | | 0.061 | | |
| | | VMP-42-10-101212 | 10/12/2012 | <0.0062 | U | | <0.0062 | U | | <0.0061 | U | | <0.0061 | U | | <0.0061 | U | | <0.054 | J | U | <0.0071 | U | | <0.007 | U | | <0.007 | U | | <0.022 | U | | 0.036 | | |
| | | VMP-42-10-013113 | 1/31/2013 | <0.0057 | U | | <0.0057 | U | | <0.0056 | U | | <0.0056 | U | | <0.0056 | U | | <0.049 | U | | <0.0065 | U | | <0.0064 | U | | <0.0064 | U | | <0.02 | U | | 0.0022 | J | |
| | 20 ft | VMP-42-20-071912 | 7/19/2012 | <0.0038 | U | | <0.0038 | U | | <0.0037 | U | | <0.0037 | U | | <0.0037 | U | | 0.0029 | J | | <0.0043 | U | | <0.0042 | U | | <0.0042 | J | U | <0.013 | U | | 0.053 | | |
| | | VMP-42-20-101212 | 10/12/2012 | <0.0055 | U | | <0.0055 | U | | <0.0054 | U | | <0.0054 | U | | <0.0054 | U | | 0.02 | J | | <0.0063 | U | | <0.0062 | U | | <0.0062 | U | | <0.02 | U | | 0.0091 | J | J |
| | | VMP-42-20-101212-Dup | 10/12/2012 | <0.0056 | U | | <0.0055 | U | | <0.0055 | U | | <0.0055 | U | | <0.0055 | U | | <0.048 | J | U | <0.0064 | U | | <0.0063 | U | | <0.0063 | U | | <0.02 | U | | 0.036 | | J |
| | | VMP-42-20-013113 | 1/31/2013 | <0.0052 | U | | <0.0052 | U | | <0.0051 | U | | <0.0051 | U | | <0.0051 | U | | 0.0053 | J | | <0.006 | U | | <0.0058 | U | | <0.0058 | U | | <0.018 | U | | 0.0045 | J | |
| | 30 ft | VMP-42-30-041912 | 4/19/2012 | <3.8 | U | | <3.8 | U | | <3.7 | U | | <3.7 | U | | <3.7 | U | | <3.2 | U | | <4.3 | U | | <4.2 | U | | <4.2 | U | | <13 | U | | <7 | U | |
| | | VMP-42-30-071912 | 7/19/2012 | <0.0035 | U | | <0.0035 | U | | <0.0035 | U | | <0.0035 | U | | <0.0035 | U | | <0.03 | U | | <0.004 | U | | <0.004 | U | | <0.004 | U | | <0.013 | U | | 0.074 | | J |
| | | VMP-42-30-101212 | 10/12/2012 | <0.0058 | U | | <0.0058 | U | | <0.0057 | U | | <0.0057 | U | | <0.0057 | U | | <0.05 | J | U | <0.0067 | U | | <0.0066 | U | | <0.0066 | U | | <0.021 | U | | 0.011 | | |
| | | VMP-42-30-101212-Dup | 10/12/2012 | <0.0058 | U | | <0.0058 | U | | <0.0057 | U | | <0.0057 | U | | <0.0057 | U | | 0.0037 | J | | <0.0067 | U | | <0.0066 | U | | <0.0066 | U | | <0.021 | U | | 0.01 | J | |
| | | VMP-42-30-013113 | 1/31/2013 | <0.0056 | U | | <0.0056 | U | | <0.0055 | U | | <0.0055 | U | | <0.0055 | U | | <0.048 | U | | <0.0064 | U | | <0.0063 | U | | <0.0063 | U | | <0.02 | U | | 0.0038 | J | |
| VMP-43 | 10 ft | VMP-43-10-041612 | 4/16/2012 | <0.004 | U | | <0.004 | J | U | <0.0039 | U | | <0.0039 | U | | <0.0039 | U | | <0.034 | J | U | <0.0045 | U | | <0.0044 | U | | <0.0044 | J | U | <0.014 | U | | 0.05 | | J |
| | | VMP-43-10-071912 | 7/19/2012 | <0.0076 | U | | <0.0076 | U | | <0.0074 | U | | <0.0074 | U | | <0.0074 | U | | <0.065 | J | U | <0.0086 | U | | <0.0085 | U | | <0.0085 | U | | <0.027 | U | | 0.064 | | |
| | | VMP-43-10-101612 | 10/16/2012 | <0.0064 | U | | <0.0064 | U | | <0.0063 | U | | <0.0063 | U | | <0.0063 | U | | <0.055 | U | | <0.0074 | U | | <0.0072 | U | | <0.0072 | U | | <0.023 | U | | 0.0081 | J | |
| | 20 ft | VMP-43-20-041612 | 4/16/2012 | <0.039 | U | | <0.039 | U | | <0.038 | U | | <0.038 | U | | <0.038 | U | | <0.033 | U | | <0.044 | U | | <0.043 | U | | <0.043 | U | | <0.14 | U | | <0.072 | U | |
| | | VMP-43-20-071912 | 7/19/2012 | <0.014 | U | | <0.014 | U | | <0.014 | U | | <0.014 | U | | <0.014 | U | | 0.003 | J | | <0.016 | U | | <0.016 | U | | <0.016 | U | | <0.05 | U | | 0.13 | | |
| | | VMP-43-20-101812 | 10/18/2012 | <0.0053 | U | | <0.0053 | U | | <0.0052 | U | | <0.0052 | U | | <0.0052 | U | | <0.046 | J | U | <0.0061 | U | | <0.006 | U | | <0.006 | U | | <0.019 | U | | 0.063 | | |
| | | VMP-43-20-012413 | 1/24/2013 | <0.0053 | U | | <0.0053 | U | | <0.0052 | U | | <0.0052 | U | | <0.0052 | U | | <0.046 | U | | <0.0061 | U | | <0.006 | U | | <0.006 | U | | <0.019 | U | | 0.0037 | J | |
| | 30 ft | VMP-43-30-042312 | 4/23/2012 | <0.035 | U | | <0.035 | U | | <0.035 | U | | <0.035 | U | | <0.035 | U | | <0.03 | U | | <0.04 | U | | <0.04 | U | | <0.04 | U | | <0.13 | U | | 0.14 | | |
| | | VMP-43-30-071912 | 7/19/2012 | <0.0039 | U | | <0.0039 | U | | <0.0038 | U | | <0.0038 | U | | <0.0038 | U | | 0.0022 | J | | <0.0044 | U | | <0.0043 | U | | <0.0043 | U | | <0.014 | U | | 0.087 | | |
| | | VMP-43-30-101812 | 10/18/2012 | <0.0056 | U | | <0.0056 | U | | <0.0055 | U | | <0.0055 | U | | <0.0055 | U | | <0.048 | U | | <0.0064 | U | | <0.0063 | U | | <0.0063 | U | | <0.02 | U | | 0.014 | | |
| | | VMP-43-30-012413 | 1/24/2013 | <0.0054 | U | | <0.0054 | U | | <0.0053 | U | | <0.0053 | U | | <0.0053 | U | | <0.047 | J | U | <0.0062 | U | | <0.0061 | U | | <0.0061 | U | | <0.019 | U | | 0.0066 | J | |
| VMP-44 | 10 ft | VMP-44-10-041912 | 4/19/2012 | <1.8 | U | | <1.8 | U | | <1.8 | U | | <1.8 | U | | <1.8 | U | | <1.6 | U | | <2.1 | U | | <2.1 | U | | <2.1 | U | | <6.6 | U | | <3.4 | U | |
| | | VMP-44-10-072012 | 7/20/2012 | <0.62 | U | | <0.62 | U | | <0.61 | U | | <0.61 | U | | <0.61 | U | | <0.53 | U | | <0.71 | U | | <0.7 | U | | <0.7 | U | | <2.2 | U | | <1.2 | U | |
| | | VMP-44-10-081012 | 8/10/2012 | <0.37 | U | | <0.37 | U | | <0.36 | U | | <0.36 | U | | <0.36 | U | | <0.32 | U | | <0.42 | U | | <0.42 | U | | <0.42 | U | | <1.3 | U | | <0.69 | U | |
| | | VMP-44-10-101212 | 10/12/2012 | <1.1 | U | | <1.1 | U | | <1.1 | U | | <1.1 | U | | <1.1 | U | | <0.98 | U | | <1.3 | U | | <1.3 | U | | <1.3 | U | | <4.1 | U | | <2.1 | U | |
| | | VMP-44-10-012513 | 1/25/2013 | <0.46 | U | | <0.46 | U | | <0.46 | U | | <0.46 | U | | <0.46 | U | | 0.077 | J | | <0.53 | U | | <0.52 | U | | <0.52 | U | | <1.6 | U | | <0.87 | U | |
| | 20 ft | VMP-44-20-041912 | 4/19/2012 | <0.41 | U | | <0.41 | U | | <0.4 | U | | <0.4 | U | | <0.4 | U | | <0.35 | U | | <0.46 | U | | <0.46 | U | | <0.46 | U | | <1.4 | U | | <0.76 | U | |
| | | VMP-44-20-072512 | 7/25/2012 | <0.69 | U | | <0.69 | U | | <0.68 | U | | <0.68 | U | | <0.68 | U | | <0.6 | U | | <0.79 | U | | <0.78 | U | | <0.78 | U | | <2.5 | U | | <1.3 | U | |
| | | VMP-44-20-101212 | 10/12/2012 | <2.3 | U | | <2.3 | U | | <2.3 | U | | <2.2 | U | | <2.2 | U | | <2 | U | | <2.6 | U | | <2.6 | U | | <2.6 | U | | <8.2 | U | | 0.68 | J | |
| | | VMP-44-20-012513 | 1/25/2013 | <0.17 | U | | <0.17 | U | | <0.16 | U | | <0.16 | U | | <0.16 | U | | 0.036 | J | | <0.19 | U | | <0.19 | U | | <0.19 | U | | <0.6 | U | | <0.31 | U | |
| | 30 ft | VMP-44-30-041912 | 4/19/2012 | <0.24 | U | | <0.24 | U | | <0.23 | U | | <0.23 | U | | <0.23 | U | | <0.2 | U | | <0.27 | U | | <0.26 | U | | <0.26 | U | | <0.84 | U | | <0.44 | U | |
| | | VMP-44-30-072512 | 7/25/2012 | <0.04 | U | | <0.04 | U | | <0.039 | U | | <0.039 | U | | <0.039 | U | | <0.034 | U | | <0.045 | U | | <0.044 | U | | <0.044 | U | | <0.14 | U | | 0.094 | J | J |
| | | VMP-44-30-072512-Dup | 7/25/2012 | <0.04 | U | | <0.04 | U | | <0.039 | U | | <0.039 | U | | <0.039 | U | | <0.034 | U | | <0.045 | U | | <0.044 | U | | <0.044 | U | | <0.14 | U | | 0.092 | J | J |
| | | VMP-44-30-101512 | 10/15/2012 | <0.24 | U | | <0.24 | U | | <0.24 | U | | <0.24 | U | | <0.24 | U | | <2.1 | U | | <0.28 | U | | <0.27 | U | | <0.27 | U | | <0.87 | U | | <0.46 | U | |
| | | VMP-44-30-101512-Dup | 10/15/2012 | <0.23 | U | | <0.23 | U | | <0.22 | U | | <0.22 | U | | <0.22 | U | | <2 | U | | <0.26 | U | | <0.26 | U | | <0.26 | U | | <0.81 | U | | <0.42 | U | |
| | | VMP-44-30-012513 | 1/25/2013 | <0.059 | U | UJ | <0.059 | U | UJ | <0.058 | U | UJ | <0.058 | U | UJ | <0.058 | U | UJ | <0.05 | J | UJ | <0.067 | U | UJ | <0.066 | U | UJ | <0.066 | U | UJ | <0.21 | U | UJ | <0.11 | J | UJ |
| VMP-45 | 10 ft | VMP-45-10-041912 | 4/19/2012 | <0.0037 | U | | <0.0037 | J | U | <0.0036 | U | | <0.0036 | U | | <0.0036 | U | | <0.032 | J | U | <0.0042 | U | | <0.0042 | U | | <0.0042 | U | | <0.013 | U | | 0.019 | | J |
| | | VMP-45-10-071912 | 7/19/2012 | <0.0038 | U | | <0.0038 | U | | <0.0037 | U | | <0.0037 | U | | <0.0037 | U | | <0.032 | J | U | <0.0043 | U | | <0.0042 | U | | <0.0042 | U | | 0.0034 | J | | 0.042 | | |
| | | VMP-45-10-101512 | 10/15/2012 | <0.0059 | U | | <0.0059 | U | | <0.0059 | U | | <0.0058 | U | | <0.0058 | U | | <0.05 | U | | <0.0067 | U | | <0.0066 | U | | <0.0066 | U | | <0.021 | U | | <0.011 | U | |
| | | VMP-45-10-013013 | 1/30/2013 | <0.0051 | U | | <0.0051 | U | | <0.005 | U | | <0.005 | U | | <0.005 | U | | <0.044 | U | | <0.0058 | U | | <0.0057 | U | | <0.0057 | U | | <0.018 | U | | 0.022 | | |
| | 20 ft | VMP-45-20-041912 | 4/19/2012 | <0.23 | U | | <0.23 | U | | <0.23 | U | | <0.22 | U | | <0.22 | U | | <0.2 | U | | <0.26 | U | | <0.26 | U | | <0.26 | U | | <0.82 | U | | 0.18 | J | |
| | | VMP-45-20-071912 | 7/19/2012 | <0.072 | U | | <0.072 | U | | <0.07 | U | | <0.07 | U | | <0.07 | U | | 0.6 | J | | <0.082 | U | | <0.081 | U | | <0.081 | U | | <0.26 | U | | 0.4 | | |
| | | VMP-45-20-101512 | 10/15/2012 | <0.0056 | U | | <0.0056 | U | | <0.0055 | U | | <0.0055 | U | | <0.0055 | U | | <0.048 | U | | <0.0064 | U | | <0.0063 | U | | <0.0063 | U | | <0.02 | U | | 0.0044 | J | |
| | | VMP-45-20-013013 | 1/30/2013 | <0.0053 | U | | <0.0053 | U | | <0.0052 | U | | <0.0052 | U | | <0.0052 | U | | <0.046 | U | | <0.0061 | U | | <0.006 | U | | <0.006 | U | | <0.019 | U | | 0.0035 | J | |
| | 30 ft | VMP-45-30-041912 | 4/19/2012 | <0.15 | U | | <0.15 | U | | <0.15 | U | | <0.15 | U | | <0.15 | U | | <0.13 | U | | <0.18 | U | | <0.17 | U | | <0.17 | U | | <0.55 | U | | <0.29 | U | |
| | | VMP-45-30-071912 | 7/19/2012 | <0.039 | U | | <0.039 | U | | <0.038 | U | | <0.038 | U | | <0.038 | U | | <0.033 | U | | <0.044 | U | | <0.043 | U | | <0.043 | U | | <0.14 | U | | <0.072 | U | |
| | | VMP-45-30-101512 | 10/15/2012 | <0.0056 | U | | <0.0056 | U | | <0.0055 | U | | <0.0055 | U | | <0.0055 | U | | <0.048 | U | | <0.0064 | U | | <0.0063 | U | | <0.0063 | U | | <0.02 | U | | 0.0035 | J | |
| | | VMP-45-30-101512-Dup | 10/15/2012 | <0.0055 | U | | <0.0055 | U | | <0.0054 | U | | <0.0054 | U | | <0.0054 | U | | <0.047 | J | U | <0.0063 | U | | <0.0062 | U | | <0.0062 | U | | <0.02 | U | | <0.01 | U | |
| | | VMP-45-30-013013 | 1/30/2013 | <0.0098 | U | | <0.0098 | U | | <0.0096 | U | | <0.0096 | U | | <0.0096 | U | | <0.084 | U | | <0.011 | U | | <0.011 | U | | <0.011 | U | | <0.035 | U | | 0.016 | J | |

SEE LAST PAGE OF TABLE FOR NOTES

**TABLE 5**
**CUMULATIVE SUMMARY OF SOIL VAPOR ANALYTICAL DETECTIONS AND SCREENING RESULTS: VILLAGE - VOCS**

| Location | Depth | Sample ID | Sample Date | 1,1-Dichloroethane | | | 1,2-Dichloroethane | | | 1,1-Dichloroethene | | | cis-1,2-Dichloroethene | | | trans-1,2-Dichloroethene | | | Dichloromethane (Methylene chloride) | | | 1,2-Dichloropropane | | | cis-1,3-Dichloropropene | | | trans-1,3-Dichloropropene | | | 1,4-Dioxane | | | Ethanol | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | 690 | | | 0.099 | | | 240 | | | 1100000 | | | 85 | | | 5.6 | | | 0.062 | | | 0.9 | | | 0.9 | | | 0.22 | | | | | |
| | | | | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals |
| VMP-47 | 5 ft | VMP-47-5-012113 | 1/21/2013 | <0.0058 | U | | <0.0058 | U | | <0.0057 | U | | <0.0057 | U | | <0.0057 | U | | <0.05 | U | | <0.0067 | U | | <0.0066 | U | | <0.0066 | U | | <0.021 | U | | 0.01 | J | |
| | | [4]VMP-47-5-012313-R | 1/23/2013 | <20 | U | | <20 | U | | <19 | U | | <19 | U | | <19 | U | | <17 | U | | <22 | U | | <22 | U | | <22 | U | | <70 | U | | <36 | U | |
| | 10 ft | VMP-47-10-012113 | 1/21/2013 | <0.0056 | U | | <0.0056 | U | | <0.0055 | U | | <0.0055 | U | | <0.0055 | U | | 0.0037 | J | | <0.0064 | U | | <0.0063 | U | | <0.0063 | U | | <0.02 | U | | 0.01 | | |
| | | [4]VMP-47-10-012313-R | 1/23/2013 | <0.49 | U | | <0.49 | U | | <0.48 | U | | <0.48 | U | | <0.48 | U | | <0.42 | U | | <0.56 | U | | <0.55 | U | | <0.55 | U | | <1.7 | U | | <0.91 | U | |
| | 20 ft | VMP-47-20-012113 | 1/21/2013 | <5.1 | U | | <5.1 | U | | <5 | U | | <5 | U | | <5 | U | | <4.4 | U | | <5.8 | U | | <5.7 | U | | <5.7 | U | | <18 | U | | <9.5 | U | |
| | | [4]VMP-47-20-012313-R | 1/23/2013 | <12 | U | | <12 | U | | <12 | U | | <12 | U | | <12 | U | | <10 | U | | <14 | U | | <14 | U | | <14 | U | | <43 | U | | <22 | U | |
| | 30 ft | VMP-47-30-012113 | 1/21/2013 | <3.7 | U | | <3.7 | U | | <3.6 | U | | <3.6 | U | | <3.6 | U | | <3.2 | U | | <4.2 | U | | <4.2 | U | | <4.2 | U | | <13 | U | | <6.9 | U | |
| | | [4]VMP-47-30-012313-R | 1/23/2013 | <19 | U | | <19 | U | | <19 | U | | <19 | U | | <19 | U | | <16 | U | | <22 | U | | <22 | U | | <22 | U | | <69 | U | | <36 | U | |
| VMP-48 | 5 ft | VMP-48-5-020113 | 2/1/2013 | <0.0052 | U | | <0.0052 | U | | <0.0051 | U | | <0.0051 | U | | <0.0051 | U | | <0.045 | J | U | <0.0059 | U | | <0.0058 | U | | <0.0058 | U | | <0.018 | U | | 0.0046 | J | |
| | 10 ft | VMP-48-10-020113 | 2/1/2013 | <0.0054 | U | | <0.0054 | U | | <0.0053 | U | | <0.0053 | U | | <0.0053 | U | | <0.046 | J | U | <0.0061 | U | | <0.006 | U | | <0.006 | U | | <0.019 | U | | 0.0053 | J | |
| | 20 ft | VMP-48-20-020113 | 2/1/2013 | <0.0052 | U | | <0.0052 | U | | <0.005 | U | | <0.005 | U | | <0.005 | U | | <0.044 | U | | <0.0059 | U | | <0.0058 | U | | <0.0058 | U | | <0.018 | U | | 0.0068 | J | |
| | 30 ft | VMP-48-30-020113 | 2/1/2013 | <0.0053 | U | | <0.0053 | U | | <0.0052 | U | | <0.0052 | U | | <0.0052 | U | | <0.045 | U | | <0.006 | U | | <0.0059 | U | | <0.0059 | U | | <0.019 | U | | <0.0098 | U | |
| | | VMP-48-30-020113-DUP | 2/1/2013 | <0.021 | U | | <0.021 | U | | <0.021 | U | | <0.021 | U | | <0.021 | U | | <0.18 | U | | <0.024 | U | | <0.024 | U | | <0.024 | U | | <0.075 | U | | <0.039 | U | |
| VMP-49 | 5 ft | VMP-49-5-020113 | 2/1/2013 | <0.0054 | U | | <0.0054 | U | | <0.0053 | U | | <0.0053 | U | | <0.0053 | U | | <0.047 | U | | <0.0062 | U | | <0.0061 | U | | <0.0061 | U | | <0.019 | U | | 0.0033 | J | |
| | 10 ft | VMP-49-10-020113 | 2/1/2013 | <0.0053 | U | | <0.0053 | U | | <0.0052 | U | | <0.0052 | U | | <0.0052 | U | | <0.046 | J | U | <0.0061 | U | | <0.006 | U | | <0.006 | U | | <0.019 | U | | <0.0099 | U | |
| | 20 ft | VMP-49-20-020113 | 2/1/2013 | <0.0052 | U | | <0.0052 | U | | <0.0051 | U | | <0.0051 | U | | <0.0051 | U | | <0.045 | J | U | <0.006 | U | | <0.0058 | U | | <0.0058 | U | | <0.018 | U | | 0.0024 | J | |
| | 30 ft | VMP-49-30-020113 | 2/1/2013 | <0.25 | U | | <0.25 | U | | <0.24 | U | | <0.24 | U | | <0.24 | U | | 0.24 | J | | <0.28 | U | | <0.28 | U | | <0.28 | U | | <0.89 | U | | 0.19 | J | |
| VMP-50 | 5 ft | VMP-50-5-020113 | 2/1/2013 | <0.0051 | U | | <0.0051 | U | | <0.005 | U | | <0.005 | U | | <0.005 | U | | <0.044 | J | U | <0.0058 | U | | <0.0057 | U | | <0.0057 | U | | <0.018 | U | | 0.0037 | J | |
| | 10 ft | VMP-50-10-020113 | 2/1/2013 | <0.0056 | U | | <0.0056 | U | | <0.0055 | U | | <0.0055 | U | | <0.0055 | U | | 0.0019 | J | | <0.0064 | U | | <0.0063 | U | | <0.0063 | U | | <0.02 | U | | 0.0027 | J | |
| | 20 ft | VMP-50-20-020113 | 2/1/2013 | <0.022 | U | | <0.022 | U | | <0.021 | U | | <0.021 | U | | <0.021 | U | | <0.18 | U | | <0.025 | U | | <0.024 | U | | <0.024 | U | | <0.077 | U | | 0.0066 | J | |
| | 30 ft | VMP-50-30-020113 | 2/1/2013 | <5.2 | U | | <5.2 | U | | <5.1 | U | | <5.1 | U | | <5.1 | U | | 4.6 | J | | <6 | U | | <5.9 | U | | <5.9 | U | | <19 | U | | 3.6 | J | |
| VMP-51 | 5 ft | VMP-51-5-020113 | 2/1/2013 | <0.0055 | U | | <0.0055 | U | | <0.0054 | U | | <0.0054 | U | | <0.0054 | U | | <0.047 | J | U | <0.0063 | U | | <0.0062 | U | | <0.0062 | U | | <0.02 | U | | 0.0015 | J | |
| | 10 ft | VMP-51-10-020113 | 2/1/2013 | <0.0056 | U | | <0.0056 | U | | <0.0055 | U | | <0.0055 | U | | <0.0055 | U | | <0.048 | U | | <0.0064 | U | | <0.0063 | U | | <0.0063 | U | | <0.02 | U | | 0.0029 | J | |
| | 20 ft | VMP-51-20-021513-R | 2/15/2013 | <0.0053 | U | | <0.0053 | U | | <0.0052 | U | | <0.0052 | U | | <0.0052 | U | | <0.046 | J | U | <0.0061 | U | | <0.006 | U | | <0.006 | U | | <0.019 | U | | 0.0054 | J | |
| | 30 ft | VMP-51-30-020413 | 2/4/2013 | <0.0058 | U | | <0.0058 | U | | <0.0057 | U | | <0.0057 | U | | <0.0057 | U | | <0.05 | U | | <0.0067 | U | | <0.0066 | U | | <0.0066 | U | | <0.021 | U | | 0.0023 | J | |
| | | VMP-51-30-020413-DUP | 2/4/2013 | <0.0057 | U | | <0.0057 | U | | <0.0056 | U | | <0.0056 | U | | <0.0056 | U | | <0.049 | U | | <0.0065 | U | | <0.0064 | U | | <0.0064 | U | | <0.02 | U | | 0.0021 | J | |
| VMP-52 | 5 ft | VMP-52-5-020413 | 2/4/2013 | <0.0051 | U | | <0.0051 | U | | <0.005 | U | | <0.005 | U | | <0.005 | U | | <0.044 | J | U | <0.0058 | U | | <0.0057 | U | | <0.0057 | U | | <0.018 | U | | 0.0039 | J | |
| | 10 ft | VMP-52-10-020413 | 2/4/2013 | <0.0048 | U | | <0.0048 | U | | <0.0048 | U | | <0.0048 | U | | <0.0048 | U | | <0.042 | U | | <0.0055 | U | | <0.0054 | U | | <0.0054 | U | | <0.017 | U | | 0.0032 | J | |
| | 20 ft | VMP-52-20-020413 | 2/4/2013 | <0.0054 | U | | <0.0054 | U | | <0.0053 | U | | <0.0053 | U | | <0.0053 | U | | <0.046 | J | U | <0.0062 | U | | <0.0061 | U | | <0.0061 | U | | <0.019 | U | | 0.0027 | J | |
| | | VMP-52-20-020413-DUP | 2/4/2013 | <0.0052 | U | | <0.0052 | U | | <0.0051 | U | | <0.0051 | U | | <0.0051 | U | | <0.045 | J | U | <0.0059 | U | | <0.0058 | U | | <0.0058 | U | | <0.018 | U | | 0.0034 | J | |
| | 30 ft | VMP-52-30-020413 | 2/4/2013 | <0.0057 | U | | <0.0057 | U | | <0.0056 | U | | <0.0056 | U | | <0.0056 | U | | <0.049 | U | | <0.0065 | U | | <0.0064 | U | | <0.0064 | U | | <0.02 | U | | <0.01 | U | |
| VMP-53 | 5 ft | VMP-53-5-020513 | 2/5/2013 | <0.0052 | U | | <0.0052 | U | | <0.0051 | U | | <0.0051 | U | | <0.0051 | U | | <0.045 | U | | <0.006 | U | | <0.0058 | U | | <0.0058 | U | | <0.018 | U | | 0.0027 | J | |
| | 10 ft | VMP-53-10-020513 | 2/5/2013 | <0.0053 | U | | <0.0053 | U | | <0.0052 | U | | <0.0052 | U | | <0.0052 | U | | <0.046 | U | | <0.0061 | U | | <0.006 | U | | <0.006 | U | | <0.019 | U | | 0.0018 | J | |
| | | VMP-53-10-020513-DUP | 2/5/2013 | <0.005 | U | | <0.005 | U | | <0.0049 | U | | <0.0049 | U | | <0.0049 | U | | <0.043 | U | | <0.0057 | U | | <0.0056 | U | | <0.0056 | U | | <0.018 | U | | <0.0093 | U | |
| | 20 ft | VMP-53-20-020513 | 2/5/2013 | <0.0053 | U | | <0.0053 | U | | <0.0052 | U | | <0.0052 | U | | <0.0052 | U | | <0.046 | U | | <0.0061 | U | | <0.006 | U | | <0.006 | U | | <0.019 | U | | 0.0032 | J | |
| | 30 ft | VMP-53-30-020513 | 2/5/2013 | <0.0054 | U | | <0.0054 | U | | <0.0053 | U | | <0.0053 | U | | <0.0053 | U | | <0.047 | U | | <0.0062 | U | | <0.0061 | U | | <0.0061 | U | | <0.019 | U | | <0.01 | U | |
| VMP-54 | 5 ft | VMP-54-5-020613 | 2/6/2013 | <0.0056 | U | | <0.0056 | U | | <0.0055 | U | | <0.0055 | U | | <0.0055 | U | | <0.048 | U | | <0.0064 | U | | <0.0063 | U | | <0.0063 | U | | <0.02 | U | | 0.0037 | J | |
| | 10 ft | VMP-54-10-020613 | 2/6/2013 | <0.0057 | U | | <0.0057 | U | | <0.0056 | U | | <0.0056 | U | | <0.0056 | U | | <0.049 | J | U | <0.0065 | U | | <0.0064 | U | | <0.0064 | U | | <0.02 | U | | 0.0022 | J | |
| | 20 ft | VMP-54-20-020613 | 2/6/2013 | <0.0056 | U | | <0.0056 | U | | <0.0055 | U | | <0.0055 | U | | <0.0055 | U | | <0.048 | U | | <0.0064 | U | | <0.0063 | U | | <0.0063 | U | | <0.02 | U | | 0.0032 | J | |
| | | VMP-54-20-020613-DUP | 2/6/2013 | <0.0056 | U | | <0.0056 | U | | <0.0055 | U | | <0.0055 | U | | <0.0055 | U | | 0.00092 | J | | <0.0064 | U | | <0.0063 | U | | <0.0063 | U | | <0.02 | U | | 0.005 | J | |
| | 30 ft | VMP-54-30-020613 | 2/6/2013 | <0.006 | U | | <0.006 | U | | <0.0059 | U | | <0.0059 | U | | <0.0059 | U | | 0.00097 | J | | <0.0068 | U | | <0.0067 | U | | <0.0067 | U | | <0.021 | U | | 0.0027 | J | |
| | | VMP-54-30-020613-DUP | 2/6/2013 | <0.006 | U | | <0.006 | U | | <0.0059 | U | | <0.0059 | U | | <0.0059 | U | | <0.051 | U | | <0.0068 | U | | <0.0067 | U | | <0.0067 | U | | <0.021 | U | | 0.0035 | J | |

**TABLE 5**
**CUMULATIVE SUMMARY OF SOIL VAPOR ANALYTICAL DETECTIONS AND SCREENING RESULTS: VILLAGE - VOCS**

| Location | Depth | Sample ID | Sample Date | Ethylbenzene 1400 | | | 4-Ethyltoluene | | | Freon 113 | | | Freon 114 | | | Heptane | | | Hexachlorobutadiene | | | Hexane | | | 2-Hexanone (Methyl N-Butyl Ketone) | | | Isopentane | | | Isopropylbenzene (Cumene) 600 | | | 4-Methyl-2-pentanone (Methyl Isobutyl Ketone) | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals |
| VMP-1 | 5 ft | VMP-1-5-082510 | 8/25/2010 | <0.018 | U | | <0.021 | U | | <0.032 | U | | <0.03 | U | | <0.017 | U | | <0.18 | U | | 0.025 | | | <0.07 | U | | | | | <0.021 | U | | <0.017 | U | |
| | | VMP-1-5-111710 | 11/17/2010 | 0.0052 | J | | <0.025 | U | | <0.039 | U | | <0.036 | U | | 0.16 | | | <0.22 | U | | 0.4 | | | <0.084 | U | | | | | <0.025 | U | | <0.021 | U | |
| | | VMP-1-5-020411 | 2/4/2011 | <0.44 | U | | <0.5 | U | | <0.77 | U | | <0.71 | U | | <0.41 | U | | <4.3 | U | | 9.4 | | | <1.6 | U | | | | | <0.5 | U | | <0.41 | U | |
| | | VMP-1-5-041211 | 4/12/2011 | 0.017 | | | 0.0018 | J | | <0.01 | U | | <0.0092 | U | | 0.45 | | | <0.056 | U | | 0.53 | | | <0.022 | U | | 0.099 | | | 0.0019 | J | | <0.0054 | U | |
| | | VMP-1-5-080111 | 8/1/2011 | 0.0026 | J | | 0.0026 | J | | <0.01 | U | | <0.0092 | U | | 0.012 | | | <0.056 | U | | 0.037 | | | 0.0024 | J | | 0.45 | | | 0.03 | | | 0.081 | | |
| | | VMP-1-5-110311 | 11/3/2011 | <15 | U | | <17 | U | | <27 | U | | <24 | U | | <14 | U | | <150 | U | | 13 | | | <57 | U | | 2100 | | | <17 | U | | <14 | U | |
| | | VMP-1-5-013012 | 1/30/2012 | <1.3 | U | | <1.4 | U | | <2.2 | U | | <2 | U | | 11 | | J | <12 | U | | 66 | | J | <4.8 | U | | 3000 | | J | <1.4 | U | | <1.2 | U | |
| | | VMP-1-5-041312 | 4/13/2012 | 0.0015 | J | | <0.0044 | U | | <0.0068 | U | | <0.0062 | U | | 0.0098 | | | <0.038 | U | | 0.0078 | | | <0.015 | U | | 0.011 | | | 0.007 | | | 0.025 | | |
| | | VMP-1-5-071612 | 7/16/2012 | 0.014 | | | 0.0048 | | | <0.007 | U | | <0.0064 | U | | 0.093 | | | <0.039 | U | | 0.085 | | | 0.0041 | J | | 0.042 | | | 0.062 | | | 0.3 | | |
| | | VMP-1-5-101112 | 10/11/2012 | <0.01 | U | | <0.011 | U | | <0.018 | U | | <0.016 | U | | 0.021 | | | <0.098 | U | | 0.16 | | | <0.038 | UJ | UJ | 4.8 | | | <0.011 | U | | <0.0094 | U | |
| | | [A]VMP-1-5-012113 | 1/21/2013 | <0.11 | U | | <0.13 | U | | <0.2 | U | | <0.18 | U | | 0.14 | | | <1.1 | U | | 2.7 | | | <0.42 | U | | 22 | | | <0.13 | U | | 0.024 | J | |
| | | [A]VMP-1-5-012313-R | 1/23/2013 | 1.5 | J | | 1.9 | J | | <8.9 | U | | <8.1 | U | | 25 | | | <50 | U | | 130 | | | <19 | U | | 2600 | | | <5.7 | U | | <4.8 | U | |
| | 8.5 ft | VMP-1-8.5-082510 | 8/25/2010 | <0.056 | U | | <0.063 | U | | <0.098 | U | | <0.09 | U | | <0.053 | U | | <0.55 | U | | <0.045 | U | | <0.21 | U | | | | | <0.063 | U | | <0.053 | U | |
| | | VMP-1-8.5-111710 | 11/17/2010 | 0.0048 | J | | <0.012 | U | | <0.019 | U | | <0.017 | U | | 0.075 | | | <0.1 | U | | 0.088 | | | <0.04 | U | | | | | <0.012 | U | | <0.01 | U | |
| | | VMP-1-8.5-111710-Dup | 11/17/2010 | 0.0031 | J | | <0.012 | U | | <0.019 | U | | <0.017 | U | | 0.06 | | | <0.1 | U | | 0.076 | | | <0.04 | U | | | | | <0.012 | U | | <0.01 | U | |
| | | VMP-1-8.5-020411 | 2/4/2011 | <0.86 | U | | <0.98 | U | | <1.5 | U | | <1.4 | U | | <0.81 | U | | <8.5 | U | | 11 | | | <3.2 | U | | | | | <0.98 | U | | <0.81 | U | |
| | | VMP-1-8.5-041211 | 4/12/2011 | 0.01 | | | 0.0023 | J | | <0.013 | U | | <0.012 | U | | 0.17 | | | <0.074 | U | | 0.14 | | | <0.028 | U | | 0.046 | | | 0.0013 | J | | <0.0071 | U | |
| | | VMP-1-8.5-080111 | 8/1/2011 | <3.1 | U | | <3.5 | U | | <5.5 | U | | <5 | U | | <3 | U | | <31 | U | | 5.1 | | | <12 | U | | 1300 | | | <3.5 | U | | <2.9 | U | |
| | | VMP-1-8.5-080111-Dup | 8/1/2011 | <3.1 | U | | <3.5 | U | | <5.4 | U | | <4.9 | U | | <2.9 | U | | <30 | U | | 17 | | | <12 | U | | 1300 | | | <3.5 | U | | <2.9 | U | |
| | | VMP-1-8.5-110311 | 11/3/2011 | <35 | U | | <40 | U | | <62 | U | | <56 | U | | <33 | U | | <340 | U | | 36 | | | <130 | U | | 4500 | | | <40 | U | | <33 | U | |
| | | VMP-1-8.5-013012 | 1/30/2012 | <7.6 | U | | <8.6 | U | | <13 | U | | <12 | U | | 10 | | | <75 | U | | 58 | | | <29 | U | | 3200 | | J | <8.6 | U | | <7.2 | U | |
| | | VMP-1-8.5-041612 | 4/16/2012 | 0.0039 | J | | <0.0052 | U | | <0.0081 | U | | <0.0074 | U | | 0.0094 | | | <0.045 | U | | 0.0059 | | | <0.017 | U | | 0.1 | | J | 0.0094 | | | 0.024 | | |
| | | VMP-1-8.5-041612-Dup | 4/16/2012 | 0.0036 | J | | 0.00098 | J | | <0.0079 | U | | <0.0072 | U | | 0.009 | | | <0.044 | U | | 0.0061 | | | <0.017 | U | | 0.19 | | J | 0.0097 | | | 0.022 | | |
| | | VMP-1-8.5-071612 | 7/16/2012 | 0.0072 | | | 0.0032 | J | | <0.007 | U | | <0.0064 | U | | 0.016 | | | <0.039 | U | | 0.01 | | | 0.0033 | J | | 0.0055 | J | | 0.067 | | | 0.26 | | |
| | | VMP-1-8.5-101112 | 10/11/2012 | <0.0061 | U | | <0.0069 | U | | <0.011 | U | | <0.0098 | U | | 0.14 | | | <0.06 | U | | 0.14 | | | <0.023 | UJ | UJ | 0.22 | | | <0.0069 | U | | <0.0058 | U | |
| | | [A]VMP-1-8.5-012113 | 1/21/2013 | <0.11 | U | | <0.12 | U | | <0.19 | U | | <0.18 | U | | 0.12 | | | <1.1 | U | | 1.8 | | | <0.41 | U | | 36 | | | <0.12 | U | | <0.1 | U | |
| | | [A]VMP-1-8.5-012313-R | 1/23/2013 | <0.1 | U | | <0.11 | U | | <0.18 | U | | <0.16 | U | | 0.96 | | | <0.99 | U | | 5.4 | | | <0.38 | U | | 99 | | | <0.11 | U | | <0.095 | U | |
| | 23.5 ft | VMP - 1 - 23.5 - 083010 | 8/30/2010 | <1.9 | U | | <2.2 | U | | <3.4 | U | | <3.1 | U | | 44 | | | <19 | U | | 260 | | | <7.3 | U | | | | | <2.2 | U | | <1.8 | U | |
| | | VMP-1-23.5-111810 | 11/17/2010 | 0.0015 | J | | <0.0061 | U | | <0.0095 | U | | <0.0086 | U | | 0.015 | | | <0.053 | U | | 0.016 | | | <0.02 | U | | | | | <0.0061 | U | | <0.005 | U | |
| | | VMP-1-23.5-020411 | 2/4/2011 | <5 | U | | <5.7 | U | | <8.9 | U | | <8.1 | U | | <4.8 | U | | <50 | U | | 300 | | | <19 | U | | | | | <5.7 | U | | <4.8 | U | |
| | | VMP-1-23.5-041211 | 4/12/2011 | 0.93 | J | | <9.3 | U | | <14 | U | | <13 | U | | 4.2 | J | | <81 | U | | 9.7 | | | <31 | U | | 900 | | J | <9.3 | U | | <7.8 | U | |
| | | VMP-1-23.5-041211-DUP | 4/12/2011 | 1.3 | J | | <12 | U | | <18 | U | | <17 | U | | 6.8 | J | | <100 | U | | 14 | | | <39 | U | | 1300 | | J | <12 | U | | <9.8 | U | |
| | | VMP-1-23.5-080111 | 8/1/2011 | <56 | U | | <63 | U | | <99 | U | | <90 | U | | 49 | J | | <550 | U | | 320 | | | <210 | U | | 16000 | | | <63 | U | | <53 | U | |
| | | VMP-1-23.5-110611 | 11/6/2011 | <13 | U | | <15 | U | | <23 | U | | <21 | U | | 18 | | | <130 | U | | 58 | | | <50 | U | | 6000 | | | <15 | U | | <12 | U | |
| | | VMP-1-23.5-013112 | 1/31/2012 | <26 | U | | <29 | U | | <46 | U | | <42 | U | | 11 | J | | <260 | U | | 92 | | | <98 | U | | 5600 | | | <29 | U | | <24 | U | |
| | | VMP-1-23.5-041612 | 4/16/2012 | <2.1 | U | | <2.3 | U | | <3.6 | U | | <3.3 | U | | <2 | U | | <20 | U | | 7 | | | <7.8 | U | | 940 | | | 1.7 | J | | <2 | U | |
| | | VMP-1-23.5-071612 | 7/16/2012 | <26 | U | | <30 | U | | <46 | U | | <42 | U | | <25 | U | | <260 | U | | 180 | | | <99 | U | | 6500 | | | <30 | U | | <25 | U | |
| | | VMP-1-23.5-102412 | 10/24/2012 | <52 | U | | <59 | U | | <92 | U | | <84 | U | | <49 | U | | <510 | U | | 96 | | | <200 | U | | 2100 | | | <59 | U | | <49 | U | |
| | | [A]VMP-1-23.5-012113 | 1/21/2013 | <0.058 | U | UJ | <0.066 | U | UJ | <0.1 | U | UJ | <0.094 | U | UJ | 0.14 | | J | <0.57 | U | UJ | 1 | | J | <0.22 | U | UJ | 14 | | J | <0.066 | U | UJ | <0.055 | U | UJ |
| | | [A]VMP-1-23.5-012313-R | 1/23/2013 | <70 | U | | <79 | U | | <120 | U | | <110 | U | | 84 | | | <690 | U | | 510 | | | <260 | U | | 15000 | | | <79 | U | | <66 | U | |
| | 38.5 ft | VMP-1-38.5-073112 | 7/31/2012 | 0.0018 | J | | 0.00085 | J | | <0.0072 | U | | <0.0065 | U | | 0.0024 | J | | <0.04 | U | | <0.0033 | U | | 0.0024 | J | | 0.0088 | J | | 0.032 | | | 0.069 | | |
| | | VMP-1-38.5-102612 | 10/26/2012 | <2.8 | U | | <3.2 | U | | <5 | U | | <4.5 | U | | 18 | | | <28 | U | | 98 | | | <11 | U | | 1700 | | | <3.2 | U | | <2.7 | U | |
| | | [A]VMP-1-38.5-012113 | 1/21/2013 | <0.038 | U | UJ | <0.043 | U | UJ | <0.067 | U | UJ | <0.062 | U | UJ | 0.17 | | J | <0.38 | U | UJ | 0.94 | | J | <0.14 | U | UJ | 7.4 | | J | <0.043 | U | UJ | <0.036 | U | UJ |
| | | [A]VMP-1-38.5-012313-R | 1/23/2013 | <52 | U | | <58 | U | | <91 | U | | <83 | U | | 69 | | | <510 | U | | 390 | | | <190 | U | | 8200 | | | <58 | U | | <49 | U | |
| VMP-2 | 5 ft | VMP - 2 - 5 - 083110 | 8/31/2010 | <1.9 | U | | <2.2 | U | | <3.4 | U | | <3.1 | U | | <1.8 | U | | <19 | U | | <1.6 | U | | <7.3 | U | | | | | <2.2 | U | | <1.8 | U | |
| | | VMP-2-5-111610 | 11/16/2010 | <2.9 | U | | <3.2 | U | | <5 | U | | <4.6 | U | | <2.7 | U | | <28 | U | | 42 | | | <11 | U | | | | | <3.2 | U | | <2.7 | U | |
| | | VMP-2-5-020411 | 2/4/2011 | <0.75 | U | | <0.85 | U | | <1.3 | U | | <1.2 | U | | <0.71 | U | | <7.4 | U | | 2.7 | | | <2.8 | U | | | | | <0.85 | U | | <0.71 | U | |
| | | VMP-2-5-041311 | 4/13/2011 | 0.0096 | | | 0.0011 | J | | <0.011 | U | | <0.0097 | U | | 0.13 | | | <0.059 | U | | 0.087 | | | <0.023 | U | | 0.1 | | | 0.0013 | J | | <0.0057 | U | |
| | | VMP-2-5-080211 | 8/2/2011 | <6.3 | U | | <7.1 | U | | <11 | U | | <10 | U | | <5.9 | U | | <62 | U | | 32 | | | <24 | U | | 6800 | | | <7.1 | U | | <5.9 | U | |
| | | VMP-2-5-110711 | 11/7/2011 | 0.00091 | J | | 0.0012 | J | | <0.0066 | U | | <0.006 | U | | 0.0019 | J | | <0.036 | U | | <0.003 | J | U | 0.00074 | J | | <0.01 | U | | 0.0044 | | | 0.033 | | |
| | | VMP-2-5-012512 | 1/25/2012 | 0.058 | J | | <0.48 | U | | <0.74 | U | | <0.68 | U | | <0.4 | U | | <4.1 | U | | 0.57 | | | <1.6 | U | | 2.3 | | | <0.48 | U | | <0.4 | U | |
| | | VMP-2-5-042512 | 4/25/2012 | 0.0056 | J | | <0.019 | U | | <0.029 | U | | <0.027 | U | | 0.15 | | | <0.16 | U | | 0.32 | | | <0.062 | U | | 0.31 | | | 0.033 | | | 0.27 | | |
| | | VMP-2-5-071612 | 7/16/2012 | 0.008 | | | 0.0052 | | | <0.0071 | U | | <0.0065 | U | | 0.02 | | | <0.04 | U | | 0.024 | | | 0.0046 | J | | 0.22 | | | 0.079 | | | 0.31 | | |
| | | VMP-2-5-102412 | 10/24/2012 | 0.0017 | J | | <0.007 | U | | <0.011 | U | | <0.01 | U | | 0.0024 | J | | <0.061 | U | | 0.003 | J | | <0.023 | U | | 0.019 | | | 0.052 | | | 0.11 | | |
| | | VMP-2-5-013113 | 1/31/2013 | <0.006 | U | | <0.0068 | J | U | <0.01 | U | | <0.0096 | U | | <0.0056 | U | | <0.059 | U | | 0.00093 | J | | <0.023 | U | | 0.0044 | J | | <0.0068 | U | | 0.002 | J | |
| | 8.5 ft | VMP-2-8.5-083110 | 8/31/2010 | <2 | U | | <2.3 | U | | <3.5 | U | | <3.2 | U | | <1.9 | U | | <20 | U | | 38 | | | <7.5 | U | | | | | <2.3 | U | | <1.9 | U | |
| | | VMP-2-8.5-111610 | 11/16/2010 | <5.5 | U | | <6.2 | U | | <9.6 | U | | <8.8 | U | | <5.2 | U | | <54 | U | | 54 | | | <21 | U | | | | | <6.2 | U | | <5.2 | U | |
| | | VMP-2-8.5-020411 | 2/4/2011 | <1.9 | U | | <2.1 | U | | <3.3 | U | | <3 | U | | <1.8 | U | | <18 | U | | 6.1 | | | <7 | U | | | | | <2.1 | U | | <1.8 | U | |
| | | VMP-2-8.5-041311 | 4/13/2011 | <0.57 | U | | <0.65 | U | | <1 | U | | <0.92 | U | | 0.38 | J | | <5.6 | U | | 0.16 | J | | <2.2 | U | | 3.5 | | | 0.18 | J | | 0.18 | J | |
| | | VMP-2-8.5-080211 | 8/2/2011 | <23 | U | | <26 | U | | <41 | U | | <37 | U | | <22 | U | | <230 | U | | 56 | | | <87 | U | | 8300 | | | <26 | U | | <22 | U | |
| | | VMP-2-8.5-110711 | 11/7/2011 | <0.049 | U | | <0.056 | U | | <0.087 | U | | <0.08 | U | | <0.047 | U | | <0.49 | U | | <0.04 | U | | <0.19 | U | | <0.13 | U | | <0.056 | U | | 0.017 | J | |
| | | VMP-2-8.5-012612 | 1/26/2012 | <2.2 | U | | <2.5 | U | | <3.9 | U | | <3.5 | U | | <2.1 | U | | <22 | U | | 1.7 | J | | <8.3 | U | | 860 | | | <2.5 | U | | <2.1 | U | |
| | | VMP-2-8.5-012612-DUP | 1/26/2012 | <2.2 | U | | <2.5 | U | | <3.9 | U | | <3.5 | U | | <2.1 | U | | <22 | U | | 2.3 | | J | <8.3 | U | | 1000 | | J | <2.5 | U | | <2.1 | U | |
| | | VMP-2-8.5-041612 | 4/16/2012 | 0.0043 | | | 0.0014 | J | | <0.0075 | U | | <0.0068 | U | | 0.006 | | | <0.042 | U | | 0.0037 | | | <0.016 | U | | 0.032 | | | 0.0084 | | | 0.028 | | |
| | | VMP-2-8.5-041612-Dup | 4/16/2012 | 0.0047 | | | 0.0011 | J | | <0.0077 | U | | <0.007 | U | | 0.0053 | | | <0.043 | U | | 0.0037 | | | <0.016 | U | | 0.012 | | | 0.0088 | | | 0.028 | | |
| | | VMP-2-8.5-071612 | 7/16/2012 | 0.0067 | | | 0.0049 | J | | <0.0086 | U | | <0.0078 | U | | 0.0048 | | | <0.048 | U | | 0.0083 | | | 0.0038 | J | | 0.056 | | J | 0.032 | | | 0.13 | | |
| | | VMP-2-8.5-071612-Dup | 7/16/2012 | 0.0084 | | | 0.0092 | | | <0.007 | U | | <0.0064 | U | | 0.0059 | | | <0.039 | U | | 0.0085 | | | 0.0052 | J | | 0.02 | | J | 0.035 | | | 0.13 | | |
| | | VMP-2-8.5-102312 | 10/23/2012 | 0.0056 | J | | 0.0059 | J | | <0.011 | U | | <0.01 | U | | 0.075 | | | <0.062 | U | | 0.18 | | | <0.024 | U | | 0.75 | | | 0.0015 | J | | 0.0077 | | |
| | | VMP-2-8.5-020513 | 2/5/2013 | 0.0025 | J | | <0.0073 | U | | <0.011 | U | | <0.01 | U | | 0.009 | | | <0.063 | U | | 0.015 | | | <0.024 | U | | 0.059 | | | <0.0073 | U | | 0.0015 | J | |
| | 22 ft | VMP-2-22-083110 | 8/31/2010 | <3.1 | U | | <3.5 | U | | <5.4 | U | | <4.9 | U | | <2.9 | U | | <30 | U | | 63 | | | <12 | U | | | | | <3.5 | U | | <2.9 | U | |
| | | VMP-2-22-111610 | 11/16/2010 | <5.7 | U | | <6.5 | U | | <10 | U | | <9.2 | U | | <5.4 | U | | <56 | U | | 78 | | | <22 | U | | | | | <6.5 | U | | <5.4 | U | |
| | | VMP-2-22-020411 | 2/4/2011 | <2.6 | U | | <2.9 | U | | <4.6 | U | | <4.2 | U | | <2.4 | U | | <25 | U | | 35 | | | <9.7 | U | | | | | <2.9 | U | | <2.4 | U | |
| | | VMP-2-22-041311 | 4/13/2011 | <7.6 | U | | <8.6 | U | | <13 | U | | <12 | U | | <7.2 | U | | <74 | U | | 1.7 | J | | <28 | U | | 1400 | | | <8.6 | U | | 1.6 | J | |
| | | VMP-2-22-080211 | 8/2/2011 | <31 | U | | <35 | U | | <54 | U | | <49 | U | | <29 | U | | <300 | U | | 59 | | | <120 | U | | 8600 | | | <35 | U | | <29 | U | |
| | | VMP-2-22-110711 | 11/7/2011 | <1.6 | U | | <1.8 | U | | <2.9 | U | | <2.6 | U | | <1.5 | U | | <16 | U | | 0.47 | J | | <6.1 | U | | 560 | | | <1.8 | U | | <1.5 | U | |
| | | VMP-2-22-012612 | 1/26/2012 | <3.4 | U | | <3.8 | U | | <5.9 | U | | <5.4 | U | | <3.2 | U | | <33 | U | | 3.6 | | J | <13 | U | | 1200 | | J | <3.8 | U | | <3.2 | U | |
| | | VMP-2-22-042712 | 4/27/2012 | 0.002 | J | | 0.0012 | J | | <0.0062 | U | | <0.0056 | U | | 0.0032 | J | | <0.034 | U | | 0.0051 | | | <0.013 | U | | 0.031 | | | 0.0088 | | | 0.077 | | |
| | | VMP-2-22-071612 | 7/16/2012 | 0.01 | | | 0.0077 | | | <0.0073 | U | | <0.0066 | U | | 0.028 | | | <0.04 | U | | 0.034 | | | 0.0058 | J | | 0.04 | | | 0.065 | | | 0.29 | | |
| | | VMP-2-22-102312 | 10/23/2012 | <0.0063 | U | | <0.0072 | U | | <0.011 | U | | <0.01 | U | | 0.014 | | | <0.062 | U | | 0.037 | | | <0.024 | U | | 0.13 | | | <0.0072 | U | | 0.003 | J | |
| | | VMP-2-22-013113 | 1/31/2013 | <0.0058 | U | | <0.0066 | J | U | <0.01 | U | | <0.0094 | U | | <0.0055 | U | | <0.057 | U | | 0.00088 | J | | <0.022 | U | | 0.0044 | J | | <0.0066 | U | | <0.0055 | U | |
| | 42 ft | VMP-2-42-013113 | 1/31/2013 | <56 | U | | 13 | J | | <100 | U | | <91 | U | | 100 | | | 53 | J | | 620 | | | <210 | U | | 14000 | | | <64 | U | | 35 | J | |

SEE LAST PAGE OF TABLE FOR NOTES

**TABLE 5**
**CUMULATIVE SUMMARY OF SOIL VAPOR ANALYTICAL DETECTIONS AND SCREENING RESULTS: VILLAGE - VOCS**

| Location | Depth | Sample ID | Sample Date | Ethylbenzene 1400 | | | 4-Ethyltoluene | | | Freon 113 | | | Freon 114 | | | Heptane | | | Hexachlorobutadiene | | | Hexane | | | 2-Hexanone (Methyl N-Butyl Ketone) | | | Isopentane | | | Isopropylbenzene (Cumene) 600 | | | 4-Methyl-2-pentanone (Methyl Isobutyl Ketone) | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals |
| VMP-3 | 5 ft | VMP-3-5-090910 | 9/9/2010 | <5.8 | U | | <6.5 | U | | <10 | U | | <9.3 | U | | 4.8 | J | | <57 | U | | 110 | | | <22 | U | | | | | <6.5 | U | | <5.4 | U | |
| | | VMP-3-5-112210 | 11/22/2010 | <5.8 | U | | <6.6 | U | | <10 | U | | <9.4 | U | | <5.5 | U | | <57 | U | | 150 | | | <22 | U | | | | | <6.6 | U | | <5.5 | U | |
| | | VMP-3-5-020911 | 2/9/2011 | <2.6 | U | | <3 | U | | <4.6 | U | | <4.2 | U | | <2.5 | U | | <26 | U | | 25 | | | <9.9 | U | | | | | <3 | U | | <2.5 | U | |
| | | VMP-3-5-041411 | 4/14/2011 | <28 | U | | <32 | U | | <50 | U | | <45 | U | | <27 | U | | <280 | U | | 240 | | | <110 | U | | 12000 | | | <32 | U | | <27 | U | |
| | | VMP-3-5-080211 | 8/2/2011 | 0.0028 | J | | 0.0019 | J | | <0.012 | U | | <0.011 | U | | 0.0027 | J | | <0.066 | U | | 0.022 | | | 0.0035 | J | | 0.3 | | | 0.021 | | | 0.092 | | |
| | | VMP-3-5-110811 | 11/8/2011 | <0.0037 | U | | 0.00043 | J | | <0.0066 | U | | <0.006 | U | | <0.0035 | U | | <0.036 | U | | <0.003 | U | | 0.00045 | J | | 0.0033 | J | | 0.0039 | J | | 0.021 | | |
| | | VMP-3-5-110811-DUP | 11/8/2011 | <0.0038 | U | | 0.00045 | J | | <0.0067 | U | | <0.0061 | U | | 0.0023 | J | | <0.037 | U | | 0.0025 | J | | 0.00046 | J | | 0.0044 | J | | 0.0034 | J | | 0.019 | | |
| | | VMP-3-5-012712 | 1/27/2012 | <1.9 | U | | <2.2 | U | | <3.4 | U | | <3 | U | | <1.8 | U | | <19 | U | | 58 | | | <7.2 | U | | 1100 | | | <2.2 | U | | <1.8 | U | |
| | | VMP-3-5-041912 | 4/19/2012 | 0.0074 | | | 0.0037 | J | | <0.0073 | U | | <0.0067 | U | | 0.011 | | | <0.041 | U | | 0.009 | | | <0.016 | U | | 0.017 | | | 0.043 | | | 0.48 | | |
| | | VMP-3-5-072712 | 7/27/2012 | <0.0044 | J | U | 0.0028 | J | | <0.0077 | U | | <0.007 | U | | 0.0029 | J | | <0.043 | U | | 0.022 | | | 0.0036 | J | | 0.009 | J | | 0.015 | | | 0.059 | | |
| | 10 ft | VMP-3-10 | 6/21/2010 | <6.6 | U | | 3.1 | J | | <12 | U | | <10 | U | | 86 | | | <65 | U | | 1300 | | | <25 | U | | | | | 2.8 | J | | <6.2 | U | |
| | | VMP-3-10-091010 | 9/10/2010 | <18 | U | | <21 | U | | <32 | U | | <30 | U | | 87 | | | <180 | U | | 1100 | | | <70 | U | | | | | 5 | J | | <17 | U | |
| | | VMP-3-10-092010 | 9/20/2010 | <13 | U | | <15 | U | | <24 | U | | <22 | U | | 48 | | | <130 | U | | 660 | | | <51 | U | | | | | <15 | U | | <13 | U | |
| | | VMP-3-10-112210 | 11/22/2010 | <5.7 | U | | <6.5 | U | | <10 | U | | <9.2 | U | | 86 | | | <56 | U | | 1200 | | | <22 | U | | | | | 7.8 | | | <5.4 | U | |
| | | VMP-3-10-112210-Dup | 11/22/2010 | <8 | U | | <9 | U | | <14 | U | | <13 | U | | 82 | | | <78 | U | | 1100 | | | <30 | U | | | | | 5.4 | J | | <7.5 | U | |
| | | VMP-3-10-020811 | 2/8/2011 | <8.4 | U | | <9.5 | U | | <15 | U | | <14 | U | | <8 | U | | <83 | U | | 690 | | | <32 | U | | | | | <9.5 | U | | <7.9 | U | |
| | | VMP-3-10-041311 | 4/13/2011 | <49 | U | | <55 | U | | <86 | U | | <79 | U | | <46 | U | | <480 | U | | 560 | | | <180 | U | | 21000 | | | <55 | U | | <46 | U | |
| | | VMP-3-10-080311 | 8/3/2011 | <0.062 | U | | <0.07 | U | | <0.11 | U | | <0.099 | U | | <0.058 | U | | <0.6 | U | | 0.1 | | | <0.23 | U | | 100 | E | J | 0.048 | J | | <0.058 | U | |
| | | VMP-3-10-110811 | 11/8/2011 | <0.005 | U | | <0.0057 | U | | <0.0089 | U | | <0.0081 | U | | <0.0048 | U | | <0.05 | U | | 0.0022 | J | | <0.019 | J | U | 0.96 | | | 0.0037 | J | | 0.027 | | |
| | | VMP-3-10-012712 | 1/27/2012 | 0.023 | J | | 0.041 | J | | <0.064 | U | | <0.059 | U | | 0.32 | | | <0.36 | U | | 1.7 | | | <0.14 | U | | 7.9 | | | 0.016 | J | | 0.042 | | |
| | | VMP-3-10-042012 | 4/20/2012 | 0.002 | J | | 0.0013 | J | | <0.0066 | U | | <0.006 | U | | 0.0039 | | | <0.036 | U | | 0.015 | | | <0.014 | U | | 0.068 | | | 0.013 | | | 0.12 | | |
| | | VMP-3-10-072312 | 7/23/2012 | <0.0044 | U | | 0.00078 | J | | <0.0077 | U | | <0.007 | U | | <0.0041 | U | | <0.043 | U | | 0.015 | | | 0.0053 | J | | 0.15 | | | 0.0011 | J | | 0.059 | | |
| | | VMP-3-10-101812 | 10/18/2012 | 0.012 | | | 0.011 | | | <0.012 | U | | <0.01 | U | | 0.2 | | | <0.065 | U | | 0.46 | | | <0.025 | U | | 0.085 | | | 0.0017 | J | | 0.024 | | |
| | | VMP-3-10-020613 | 2/6/2013 | <0.0061 | U | | <0.0069 | U | | <0.011 | U | | <0.0098 | U | | <0.0058 | U | | <0.06 | U | | <0.005 | U | | <0.023 | U | | <0.017 | U | | <0.0069 | U | | <0.0058 | U | |
| | 22 ft | VMP-3-22-092010 | 9/20/2010 | 9.4 | J | | 7.7 | J | | <31 | U | | <28 | U | | 130 | | | <170 | U | | 1500 | | | <67 | U | | | | | 14 | J | | <17 | U | |
| | | VMP-3-22-112210 | 11/22/2010 | <20 | U | | <23 | U | | <36 | U | | <32 | U | | 140 | | | <200 | U | | 2000 | | | <76 | U | | | | | 20 | J | | <19 | U | |
| | | VMP-3-22-020811 | 2/8/2011 | 3.6 | J | | <11 | U | | <18 | U | | <16 | U | | <9.4 | U | | <98 | U | | 1400 | | | <38 | U | | | | | 9.9 | J | | <9.4 | U | |
| | | VMP-3-22-041511 | 4/15/2011 | <54 | U | | <61 | U | | <95 | U | | <87 | U | | 50 | | | <530 | U | | 850 | | | <200 | U | | 24000 | | | <61 | U | | <51 | U | |
| | | VMP-3-22-080611 | 8/6/2011 | 0.025 | J | | <0.097 | U | | <0.15 | U | | <0.14 | U | | 0.51 | | | <0.84 | U | | 3 | | | <0.32 | U | | 24 | | | 0.059 | J | | 0.15 | | |
| | | VMP-3-22-110811 | 11/8/2011 | <0.0038 | U | | <0.0043 | J | U | <0.0067 | U | | <0.0061 | U | | <0.0036 | U | | <0.037 | U | | 0.0014 | J | | <0.014 | U | | 0.32 | | | 0.00078 | J | | 0.0093 | | |
| | | VMP-3-22-013012 | 1/30/2012 | 0.0087 | J | | <0.017 | U | | <0.027 | U | | <0.024 | U | | 0.45 | | | <0.15 | U | | 1.2 | | | <0.057 | U | | 2.8 | | | 0.0065 | J | | 0.046 | | |
| | | VMP-3-22-042012 | 4/20/2012 | 0.0015 | J | | 0.001 | J | | <0.0067 | U | | <0.0061 | U | | 0.004 | | | <0.037 | U | | 0.012 | | | <0.014 | U | | 0.28 | | | 0.013 | | | 0.1 | | |
| | | VMP-3-22-072312 | 7/23/2012 | <0.0042 | U | | <0.0048 | U | | <0.0075 | U | | <0.0068 | U | | 0.0012 | J | | <0.042 | U | | 0.00096 | J | | <0.016 | U | | <0.012 | U | | 0.0014 | J | | 0.013 | | |
| | | VMP-3-22-101812 | 10/18/2012 | <0.0064 | U | | <0.0073 | U | | <0.011 | U | | <0.01 | U | | 0.0078 | | | <0.063 | U | | 0.0042 | J | | <0.024 | U | | 0.028 | | | <0.0073 | U | | 0.043 | | |
| | | VMP-3-22-020613 | 2/6/2013 | <0.0063 | U | | <0.0071 | U | | <0.011 | U | | <0.01 | U | | <0.0059 | U | | <0.062 | U | | 0.0012 | J | | <0.024 | U | | 0.0087 | J | | <0.0071 | U | | <0.0059 | U | |
| | 31.5 ft | VMP-3-31.5-090910 | 9/9/2010 | 57 | | | 53 | | | <58 | U | | <53 | U | | 1100 | | | <320 | U | | 25000 | | | <120 | U | | | | | <37 | U | | <31 | U | |
| | | VMP-3-31.5-112210 | 11/22/2010 | 50 | | | 17 | J | | <41 | U | | <37 | U | | 1200 | | | <230 | U | | 20000 | | | <87 | U | | | | | <26 | U | | <22 | U | |
| | | VMP-3-31.5-020911 | 2/9/2011 | 33 | | | <25 | U | | <39 | U | | <35 | U | | 480 | | | <220 | U | | 6400 | | | <83 | U | | | | | <25 | U | | <21 | U | |
| | | VMP-3-31.5-041411 | 4/14/2011 | <180 | U | | <200 | U | | <320 | U | | <290 | U | | 510 | | | <1800 | U | | 9600 | | | <680 | U | | 52000 | | | <200 | U | | <170 | U | |
| | | VMP-3-31.5-041411-DUP | 4/14/2011 | <180 | U | | <200 | U | | <320 | U | | <290 | U | | 450 | | | <1800 | U | | 8800 | | | <680 | U | | 48000 | | | <200 | U | | <170 | U | |
| | | VMP-3-31.5-080211 | 8/2/2011 | <410 | U | | <460 | U | | <720 | U | | <660 | U | | 860 | | | <4000 | U | | 18000 | | | <1500 | U | | 80000 | | | <460 | U | | <380 | U | |
| | | VMP-3-31.5-080211-Dup | 8/2/2011 | <240 | U | | <270 | U | | <420 | U | | <380 | U | | 1200 | | | <2300 | U | | 27000 | | | <900 | U | | 120000 | | | <270 | U | | <220 | U | |
| | | VMP-3-31.5-110811 | 11/8/2011 | <9.5 | U | | <11 | U | | <17 | U | | <15 | U | | 55 | | | <93 | U | | 720 | | | <36 | U | | 3200 | | | <11 | U | | <9 | U | |
| | | VMP-3-31.5-012712 | 1/27/2012 | <60 | U | | <68 | U | | <110 | U | J | <97 | U | | 88 | | J | <590 | U | | 1700 | | J | <230 | U | | 16000 | | J | <68 | U | | <57 | U | |
| | | VMP-3-31.5-041912 | 4/19/2012 | <100 | U | | <120 | U | | <180 | U | J | <170 | U | | 240 | | J | <1000 | U | | 6500 | | | <390 | U | | 53000 | | | <120 | U | | <98 | U | |
| | | VMP-3-31.5-041912-Dup | 4/19/2012 | <99 | U | | <110 | U | | <180 | U | J | <160 | U | | 180 | | J | <980 | U | | 6600 | | | <380 | U | | 54000 | | | <110 | U | | <94 | U | |
| | | VMP-3-31.5-072312 | 7/23/2012 | <25 | U | | <28 | U | | <44 | U | | <40 | U | | <23 | U | | <240 | U | | 620 | | | <94 | U | | 18000 | | | <28 | U | | <23 | U | |
| | | VMP-3-31.5-101912 | 10/19/2012 | <2 | U | | <2.3 | U | | <3.5 | U | | <3.2 | U | | <1.9 | U | | <20 | U | | 14 | | | <7.5 | U | | 240 | | | <2.3 | U | | <1.9 | U | |
| | | VMP-3-31.5-020713 | 2/7/2013 | <11 | U | | <13 | U | | <20 | U | | <18 | U | | <10 | U | | <110 | U | | 280 | | | <42 | U | UJ | 4200 | | | <13 | U | | <42 | U | |
| | 39.5 ft | VMP-3-39-101912 | 10/19/2012 | 31 | J | | <230 | U | | <350 | U | | <320 | U | | <190 | U | | <2000 | U | | 1200 | | | <750 | U | | 19000 | | | <230 | U | | <190 | U | |
| | | VMP-3-39-021213 | 2/12/2013 | 13 | J | | <65 | U | | <100 | U | | <92 | U | | <54 | U | | <560 | U | | 2100 | | | <220 | U | UJ | 18000 | | | <65 | U | | <220 | U | |
| VMP-4 | 5 ft | VMP-4-5-082510 | 8/25/2010 | <0.31 | U | | 0.061 | J | | <0.55 | U | | <0.5 | U | | 1.7 | | | <3.1 | U | | 13 | | | <1.2 | U | | | | | 0.048 | J | | <0.29 | U | |
| | | VMP-4-5-112210 | 11/22/2010 | 21 | | | 6.2 | J | | <21 | U | | <19 | U | | 580 | | | <110 | U | | 1300 | | | <44 | U | | | | | 6.6 | J | | <11 | U | |
| | | VMP-4-5-021411 | 2/14/2011 | <0.68 | U | | <0.77 | U | | <1.2 | U | | <1.1 | U | | 30 | | | <6.7 | U | | 88 | | | <2.6 | U | | | | | <0.77 | U | | <0.64 | U | |
| | | VMP-4-5-041911 | 4/19/2011 | <31 | U | | <36 | U | | <56 | U | | <51 | U | | 380 | | | <310 | U | | 1200 | | | <120 | U | | 11000 | | | <36 | U | | <30 | U | |
| | | VMP-4-5-080311 | 8/3/2011 | <0.068 | U | | <0.076 | U | | <0.12 | U | | <0.11 | U | | 0.054 | J | | <0.66 | U | | 0.6 | | | 0.0083 | J | | 19 | E | J | 0.072 | J | | <0.064 | U | |
| | | VMP-4-5-110911 | 11/9/2011 | 0.00078 | J | | <0.0042 | J | U | <0.0066 | U | | <0.006 | U | | 0.0018 | J | | <0.036 | U | | 0.0032 | | | <0.014 | U | | 0.04 | | | 0.0021 | J | | <0.0035 | U | |
| | | VMP-4-5-013012 | 1/30/2012 | <0.19 | U | | <0.22 | U | | <0.34 | U | | <0.3 | U | | 2.2 | | J | <1.9 | U | | 12 | | J | <0.72 | U | | 100 | | J | <0.22 | U | | <0.18 | U | |
| | | VMP-4-5-042512 | 4/25/2012 | 0.0082 | | | 0.0041 | J | | <0.0083 | U | | <0.0076 | U | | 0.22 | | | <0.046 | U | | 0.58 | | | 0.004 | J | | 0.43 | | | 0.054 | | | 0.22 | | |
| | | VMP-4-5-072512 | 7/25/2012 | 0.021 | | | 0.0093 | | | <0.0082 | U | | <0.0075 | U | | 0.03 | | | <0.046 | U | | 0.012 | | | 0.0053 | J | | 0.027 | | | 0.073 | | | 0.32 | | |
| | | VMP-4-5-101812 | 10/18/2012 | <0.0068 | U | | <0.0076 | U | | <0.012 | U | | <0.011 | U | | 0.0018 | J | | <0.066 | U | | <0.0055 | U | | <0.025 | U | | 0.0051 | J | | 0.025 | | | 0.048 | | |
| | | VMP-4-5-020713 | 2/7/2013 | <0.0054 | U | | 0.0024 | J | | <0.0095 | U | | <0.0086 | U | | <0.0051 | U | | <0.053 | U | | 0.0017 | J | | <0.02 | U | | 0.0088 | J | | <0.0061 | U | | <0.005 | U | |
| | 12 ft | VMP-4-12-082510 | 8/25/2010 | 7.8 | | | 3.6 | J | | <9.6 | U | | <8.8 | U | | 420 | | | <54 | U | | 1200 | | | <21 | U | | | | | 3.6 | J | | <5.2 | U | |
| | | VMP-4-12-112310 | 11/23/2010 | 1.7 | J | | 4.7 | J | | <9.9 | U | | <9 | U | | 240 | | | <55 | U | | 690 | | | <21 | U | | | | | <6.3 | U | | <5.3 | U | |
| | | VMP-4-12-021411 | 2/14/2011 | <1.4 | U | | 0.97 | J | | <2.5 | U | | <2.3 | U | | 24 | | | <14 | U | | 160 | | | <5.3 | U | | | | | <1.6 | U | | <1.3 | U | |
| | | VMP-4-12-041911 | 4/19/2011 | 33 | | | 11 | J | | <48 | U | | <44 | U | | 480 | | | <270 | U | | 1300 | | | <100 | U | | 11000 | | | <31 | U | | <26 | U | |
| | | VMP-4-12-080311 | 8/3/2011 | <3.1 | U | | <3.5 | U | | <5.5 | U | | <5 | U | | 41 | | | <31 | U | | 170 | | | <12 | U | | 3100 | | | <3.5 | U | | <2.9 | U | |
| | | VMP-4-12-080311-Dup | 8/3/2011 | <6.3 | U | | <7.1 | U | | <11 | U | | <10 | U | | 36 | | | <62 | U | | 150 | | | <24 | U | | 3400 | | | <7.1 | U | | <5.9 | U | |
| | | VMP-4-12-110911 | 11/9/2011 | <0.95 | U | | <1.1 | U | | <1.7 | U | | <1.5 | U | | 1.6 | | | <9.3 | U | | 11 | | | <3.6 | U | | 260 | | | <1.1 | U | | <0.9 | U | |
| | | VMP-4-12-013012 | 1/30/2012 | 0.46 | J | | <2.2 | U | | <3.4 | U | | <3.1 | U | | 95 | | | <19 | U | | 260 | | | <7.3 | U | | 980 | | J | <2.2 | U | | <1.8 | U | |
| | | VMP-4-12-041812 | 4/18/2012 | 0.0042 | J | | <0.0049 | U | | <0.0077 | U | | <0.007 | U | | 0.0064 | | | <0.043 | U | | 0.011 | | | <0.016 | U | | 0.011 | J | | 0.07 | | | 0.38 | | |
| | | VMP-4-12-072312 | 7/23/2012 | 0.09 | | | <0.024 | U | | <0.037 | U | | <0.034 | U | | 0.48 | | | <0.21 | U | | 0.2 | | | <0.08 | U | | 0.25 | | | 0.036 | | | 0.13 | | |
| | | VMP-4-12-101812 | 10/18/2012 | 0.019 | | | 0.0012 | J | | <0.012 | U | | <0.01 | U | | 0.014 | | | <0.065 | U | | 0.0032 | J | | <0.025 | U | | 0.019 | | | 0.0015 | J | | 0.0038 | J | |
| | | VMP-4-12-101812-Dup | 10/18/2012 | 0.023 | | | 0.0019 | J | | <0.012 | U | | <0.011 | U | | 0.016 | | | <0.066 | U | | 0.0032 | J | | <0.025 | U | | 0.012 | J | | 0.0014 | J | | 0.0044 | J | |
| | | VMP-4-12-020713 | 2/7/2013 | <0.0058 | U | | 0.007 | | | <0.01 | U | | <0.0094 | U | | <0.0055 | U | | <0.057 | U | | <0.0047 | U | | <0.022 | U | | 0.044 | | | <0.0066 | U | | <0.0055 | U | |
| | | VMP-4-12-020713-DUP | 2/7/2013 | <0.006 | U | | <0.0068 | J | U | <0.01 | U | | <0.0096 | U | | <0.0056 | U | | <0.059 | U | | 0.0027 | J | | <0.023 | U | | 0.045 | | | <0.0068 | U | | <0.0056 | U | |
| | 23.5 ft | VMP - 4 - 23.5 - 083110 | 8/31/2010 | 960 | | J | 230 | | J | <11 | U | | <10 | U | | 4100 | | J | <62 | U | | 13000 | | J | <24 | U | | | | | 38 | | J | <5.9 | U | |
| | | VMP-4-23.5-112310 | 11/23/2010 | 630 | | | 58 | J | | <110 | U | | <100 | U | | 3900 | | | <620 | U | | 15000 | | | <240 | U | | | | | <72 | U | | <60 | U | |
| | | VMP-4-23.5-021411 | 2/14/2011 | 93 | | J | 1.2 | J | J | <4.1 | U | | <3.7 | U | | 1700 | | J | <23 | U | | 12000 | | | <8.7 | U | | | | | <2.6 | U | | <2.2 | U | |
| | | VMP-4-23.5-042011 | 4/20/2011 | 530 | | | 69 | J | | <260 | U | | <240 | U | | 2900 | | | <1400 | U | | 13000 | | | <1400 | U | | 81000 | | | <160 | U | | <1400 | U | |
| | | VMP-4-23.5-042011-DUP | 4/20/2011 | 490 | | | 69 | J | | <260 | U | | <240 | U | | 2800 | | | <1400 | U | | 13000 | | | <1400 | U | | 78000 | | | <160 | U | | <1400 | U | |
| | | VMP-4-23.5-080611 | 8/6/2011 | 180 | | | 21 | | | <11 | U | | <9.8 | U | | 2200 | | | <60 | U | | 11000 | | | <23 | U | | 69000 | | | 6.6 | J | | <5.8 | U | |
| | | VMP-4-23.5-110911 | 11/9/2011 | 4 | J | | <21 | U | | <32 | U | | <29 | U | | 740 | | | <180 | U | | 6200 | | | <69 | U | | 37000 | | | <21 | U | | <17 | U | |
| | | VMP-4-23.5-013012 | 1/30/2012 | 140 | | J | <44 | U | | <68 | U | | <62 | U | | 4700 | | J | <380 | U | | 14000 | | J | <150 | U | | 32000 | | J | <44 | U | | <37 | U | |
| | | VMP-4-23.5-013012-DUP | 1/30/2012 | 52 | | J | <31 | U | | <48 | U | | <44 | U | | 3200 | | J | <270 | U | | 11000 | | | <100 | U | | 34000 | | J | <31 | U | | <26 | U | |
| | | VMP-4-23.5-041912 | 4/19/2012 | 16 | | | <9.6 | U | | <15 | U | | <14 | U | | 2400 | | | <84 | U | | 4800 | | | <32 | U | | 4700 | | | <9.6 | U | | <8 | U | |
| | | VMP-4-23.5-072312 | 7/23/2012 | 110 | | | 15 | | | <7.2 | U | | <6.6 | U | | 1700 | | | <40 | U | | 1500 | | | <15 | U | | 1900 | | | <4.6 | U | | <3.8 | U | |
| | | VMP-4-23.5-101812 | 10/18/2012 | 3.9 | J | | <5.1 | U | | <7.9 | U | | <7.2 | U | | 65 | | | <44 | U | | 140 | | | <17 | U | | 320 | | | <5.1 | U | | <4.2 | U | |
| | | VMP-4-23.5-020713 | 2/7/2013 | <1.4 | U | | <1.6 | U | | <2.5 | U | | <2.3 | U | | <1.4 | U | | <14 | U | | 82 | | | <5.4 | U | UJ | 630 | | | <1.6 | U | | <5.4 | U | UJ |
| | 39 ft | VMP-4-39-042111 | 4/21/2011 | 420 | | | 51 | J | | <320 | U | | <290 | U | | 2700 | | | <1800 | U | | 13000 | | | <1700 | U | | 77000 | | | <210 | U | | <1700 | U | |
| | | VMP-4-39-041912 | 4/19/2012 | 120 | | | 12 | | | <7.7 | U | | <7 | U | | 3200 | | | <43 | U | | 10000 | | | <16 | U | | 11000 | | | 3.4 | J | | <4.1 | U | |
| | | VMP-4-39-072312 | 7/23/2012 | 170 | | J | 18 | | J | <12 | U | | <10 | U | | 3800 | | J | <64 | U | | 2700 | | J | <25 | U | | 3000 | | J | <7.4 | U | | <6.2 | U | |
| | | VMP-4-39-101812 | 10/18/2012 | 110 | | | <93 | U | | <140 | U | | <130 | U | | 1400 | | | <810 | U | | 2200 | | | <310 | U | | 6400 | | | <93 | U | | <78 | U | |
| | | VMP-4-39-101812-Dup | 10/18/2012 | 100 | | | <85 | U | | <130 | U | | <120 | U | | 1400 | | | <740 | U | | 2200 | | | <280 | U | | 6400 | | | <85 | U | | <71 | U | |
| | | VMP-4-39-020713 | 2/7/2013 | 450 | | | 58 | | | <21 | U | | <19 | U | | 2300 | | | <110 | U | | 4500 | | | <44 | U | UJ | 5300 | | | 5.5 | J | | <44 | U | UJ |

SEE LAST PAGE OF TABLE FOR NOTES

**TABLE 5**
**CUMULATIVE SUMMARY OF SOIL VAPOR ANALYTICAL DETECTIONS AND SCREENING RESULTS: VILLAGE - VOCS**

| Location | Depth | Sample ID | Sample Date | Ethylbenzene 1400 | | | 4-Ethyltoluene | | | Freon 113 | | | Freon 114 | | | Heptane | | | Hexachlorobutadiene | | | Hexane | | | 2-Hexanone (Methyl N-Butyl Ketone) | | | Isopentane | | | Isopropylbenzene (Cumene) 600 | | | 4-Methyl-2-pentanone (Methyl Isobutyl Ketone) | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals |
| VMP-5 | 5 ft | VMP-5-5-090910 | 9/9/2010 | <11 | U | | 20 | | | <20 | U | | <18 | U | | 140 | | | <110 | U | | 1500 | | | <43 | U | | | | | <13 | U | | <11 | U | |
| | | VMP-5-5-112210 | 11/22/2010 | <2.8 | U | | <3.2 | U | | <4.9 | U | | <4.5 | U | | 120 | | | <28 | U | | 1400 | | | <10 | U | | | | | <3.2 | U | | <2.6 | U | |
| | | VMP-5-5-021611 | 2/16/2011 | 0.0041 | J | J | <0.02 | U | | <0.032 | U | | <0.029 | U | | <0.017 | U | | <0.18 | U | | <0.014 | U | | <0.067 | U | | | | | <0.02 | U | | <0.017 | U | |
| | | VMP-5-5-042111 | 4/21/2011 | <0.057 | U | | <0.065 | U | | <0.1 | U | | <0.092 | U | | <0.054 | U | | <0.56 | U | | 0.035 | J | | <0.54 | U | | 0.25 | | | <0.065 | U | | <0.54 | U | |
| | | VMP-5-5-080511 | 8/5/2011 | 0.0032 | J | | 0.0022 | J | | <0.0096 | U | | <0.0088 | U | | 0.047 | | | <0.054 | U | | 0.083 | | | <0.021 | U | | 0.32 | | | 0.01 | | | 0.072 | | |
| | | VMP-5-5-111111 | 11/11/2011 | 0.002 | J | | 0.0024 | J | | <0.0071 | U | | <0.0065 | U | | 0.23 | | | <0.04 | U | | 0.11 | | | <0.015 | U | | 0.24 | | | 0.025 | | | 0.021 | | |
| | | VMP-5-5-013012 | 1/30/2012 | 0.036 | J | | 0.02 | J | | <0.072 | U | | <0.065 | U | | 0.1 | | | <0.4 | U | | 0.63 | | | <0.15 | U | | 4.9 | | | 0.0069 | J | | 0.028 | J | |
| | | VMP-5-5-041112 | 4/11/2012 | 0.0041 | | | 0.0019 | J | | 0.0018 | J | | <0.0064 | U | | 0.0028 | J | | <0.039 | U | | 0.0019 | J | | <0.015 | U | | 0.0036 | J | | 0.03 | | | 0.17 | | |
| | | VMP-5-5-071312 | 7/13/2012 | <0.0044 | J | U | 0.0023 | J | | <0.0078 | U | | <0.0071 | U | | 0.0029 | J | | <0.043 | U | | <0.0036 | J | U | <0.017 | U | | 0.0069 | J | | <0.005 | J | U | <0.0048 | | U |
| | | VMP-5-5-101212 | 10/12/2012 | <0.0055 | U | | <0.0062 | U | | <0.0096 | U | | <0.0088 | U | | <0.0052 | U | | <0.054 | U | | 0.0019 | J | | <0.021 | U | | 0.0062 | J | | <0.0062 | U | | <0.0052 | U | |
| | | VMP-5-5-012513 | 1/25/2013 | <0.0057 | U | | <0.0065 | U | | <0.01 | U | | <0.0092 | U | | <0.0054 | U | | <0.056 | U | | <0.0046 | U | | <0.022 | U | | 0.0029 | J | | <0.0065 | U | | <0.0054 | U | |
| | 12.5 ft | VMP-5-12.5-090910 | 9/9/2010 | <5.7 | U | | 9.2 | | | <10 | U | | <9.2 | U | | 120 | | | <56 | U | | 1300 | | | <22 | U | | | | | <5.4 | U | | <6.5 | U | |
| | | VMP-5-12.5-112310 | 11/23/2010 | 0.1 | J | | <0.32 | U | | <0.5 | U | | <0.46 | U | | <0.27 | U | | <2.8 | U | | 15 | | | <1.1 | U | | | | | <0.32 | U | | <0.27 | U | |
| | | VMP-5-12.5-021611 | 2/16/2011 | <0.86 | U | | <0.98 | U | | <1.5 | U | | <1.4 | U | | 5.8 | | | <8.5 | U | | 110 | | | <3.2 | U | | | | | <0.98 | U | | <0.81 | U | |
| | | VMP-5-12.5-042111 | 4/21/2011 | <0.061 | U | | <0.069 | U | | <0.11 | U | | <0.098 | U | | <0.058 | U | | <0.6 | U | | 0.03 | J | | <0.58 | U | | 0.2 | | | <0.069 | U | | <0.58 | U | |
| | | VMP-5-12.5-080611 | 8/6/2011 | <5.4 | U | | <6.1 | U | | <9.5 | U | | <8.7 | U | | 27 | | | <53 | U | | 340 | | | <20 | U | | 10000 | | | <6.1 | U | | <5.1 | U | |
| | | VMP-5-12.5-111111 | 11/11/2011 | 0.001 | J | | 0.00067 | J | | <0.0067 | U | | <0.0062 | U | | 0.0024 | J | | <0.038 | U | | 0.0018 | J | | <0.014 | U | | 0.0029 | J | | 0.0024 | J | | 0.022 | | |
| | | VMP-5-12.5-013012 | 1/30/2012 | 0.0032 | J | | 0.0024 | J | | <0.022 | U | | <0.02 | U | | 0.035 | | | <0.12 | U | | 0.18 | | | <0.047 | U | | 1.5 | | | 0.0043 | J | | 0.02 | | |
| | | VMP-5-12.5-041112 | 4/11/2012 | 0.0026 | J | | 0.0015 | J | | <0.0067 | U | | <0.0061 | U | | 0.0027 | J | | <0.037 | U | | 0.0053 | | | <0.014 | U | | 0.13 | | | 0.022 | | | 0.14 | | |
| | | VMP-5-12.5-071212 | 7/12/2012 | 0.0043 | | | 0.012 | | | <0.0079 | U | | <0.0072 | U | | 0.0017 | J | | <0.044 | U | | 0.0012 | J | | <0.017 | U | | 0.0047 | J | | <0.0051 | U | | <0.0042 | J | U |
| | | VMP-5-12.5-101112 | 10/11/2012 | <0.011 | U | | <0.012 | U | | <0.019 | U | | <0.017 | U | | <0.01 | U | | <0.1 | U | | 0.0016 | J | | <0.04 | UJ | UJ | 0.011 | J | | <0.012 | U | | 0.0033 | J | |
| | | VMP-5-12.5-012413 | 1/24/2013 | <0.0056 | U | | <0.0063 | U | | <0.0099 | U | | <0.009 | U | | <0.0053 | U | | <0.055 | U | | <0.0045 | U | | <0.021 | U | | 0.0021 | J | | <0.0063 | U | | <0.0053 | U | |
| | 31 ft | VMP-5-31-090910 | 9/9/2010 | <24 | U | | <27 | U | | <42 | U | | <38 | U | | 1300 | | | <230 | U | | 7700 | | | <90 | U | | | | | <27 | U | | <22 | U | |
| | | VMP-5-31-112310 | 11/23/2010 | <15 | U | | <17 | U | | <26 | U | | <24 | U | | 1700 | | | <150 | U | | 8200 | | | <57 | U | | | | | <17 | U | | <14 | U | |
| | | VMP-5-31-021611 | 2/16/2011 | <6 | U | | <6.8 | U | | <10 | U | | <9.6 | U | | 950 | | | <59 | U | | 5600 | | | <23 | U | | | | | <6.8 | U | | <5.6 | U | |
| | | VMP-5-31-042111 | 4/21/2011 | <89 | U | | <100 | U | | <160 | U | | <140 | U | | 900 | | | <880 | U | | 6200 | | | <840 | U | | 44000 | | | <100 | U | | <840 | U | |
| | | VMP-5-31-080611 | 8/6/2011 | <50 | U | | <57 | U | | <89 | U | | <81 | U | | 780 | | | <490 | U | | 5800 | | | <190 | U | | 43000 | | | <57 | U | | <48 | U | |
| | | VMP-5-31-111111 | 11/11/2011 | <25 | U | | <29 | U | | <45 | U | | <41 | U | | 220 | | | <250 | U | | 2200 | | | <96 | U | | 24000 | | | <29 | U | | <24 | U | |
| | | VMP-5-31-013012 | 1/30/2012 | <13 | U | | <15 | U | | <23 | U | | <21 | U | | 82 | | | <130 | U | | 740 | | | <49 | U | | 13000 | | J | <15 | U | | <12 | U | |
| | | VMP-5-31-041112 | 4/11/2012 | <0.041 | U | | <0.047 | U | | <0.073 | U | | <0.067 | U | | 0.062 | | | <0.41 | U | | 0.32 | | | <0.16 | U | | 12 | | | 0.016 | J | | 0.088 | | |
| | | VMP-5-31-071212 | 7/12/2012 | <0.0044 | U | | <0.0049 | J | U | <0.0077 | U | | <0.007 | U | | 0.017 | | | <0.043 | U | | 0.057 | | | <0.016 | U | | 0.47 | | | <0.0049 | J | U | 0.016 | | |
| | | VMP-5-31-101112 | 10/11/2012 | <0.0061 | U | | <0.0069 | U | | <0.011 | U | | <0.0098 | U | | 0.0039 | J | | <0.06 | U | | 0.015 | | | <0.023 | UJ | UJ | 0.13 | | | <0.0069 | U | | <0.0058 | U | |
| | | VMP-5-31-012413 | 1/24/2013 | <0.061 | U | | <0.069 | U | | <0.11 | U | | <0.098 | U | | <0.057 | U | | <0.6 | U | | 0.036 | J | | <0.23 | U | | 0.19 | | | <0.069 | U | | <0.057 | U | |
| | 40 ft | VMP-5-40-042111 | 4/21/2011 | <94 | U | | <100 | U | | <160 | U | | <150 | U | | 730 | | | <920 | U | | 4900 | | | <880 | U | | 35000 | | | <100 | U | | <880 | U | |
| | | VMP-5-40-013012 | 1/30/2012 | <27 | U | | <31 | U | | <48 | U | | <44 | U | | 53 | | | <270 | U | | 560 | | | <100 | U | | 12000 | | J | <31 | U | | <26 | U | |
| | | VMP-5-40-041212 | 4/12/2012 | 0.0073 | J | | 0.0078 | J | | <0.072 | U | | <0.065 | U | | 0.21 | | | <0.4 | U | | 1.5 | | | <0.15 | U | | 100 | | | 0.044 | J | | 0.23 | | |
| | | VMP-5-40-071212 | 7/12/2012 | <0.044 | U | | <0.049 | U | | <0.077 | U | | <0.07 | U | | <0.041 | U | | <0.43 | U | | 0.02 | J | | <0.16 | U | | 7.6 | | | <0.049 | U | | <0.041 | U | |
| | | VMP-5-40-101112 | 10/11/2012 | <0.0064 | U | | <0.0073 | U | | <0.011 | U | | <0.01 | U | | 0.0031 | J | | <0.063 | U | | 0.0076 | | | <0.024 | U | UJ | 1.2 | | | 0.0017 | J | | 0.014 | | |
| | | VMP-5-40-012513 | 1/25/2013 | <0.019 | U | | <0.021 | U | | <0.033 | U | | <0.03 | U | | 0.01 | J | | <0.18 | U | | 0.026 | | | <0.07 | U | | 0.7 | | | <0.021 | U | | <0.018 | U | |
| | | VMP-5-40-012513-Dup | 1/25/2013 | <0.018 | U | | <0.021 | U | | <0.032 | U | | <0.029 | U | | <0.017 | U | | <0.18 | U | | 0.013 | J | | <0.069 | U | | 0.53 | | | <0.021 | U | | <0.017 | U | |
| VMP-6 | 5 ft | VMP-6-5-090810 | 9/8/2010 | <0.96 | U | | 1 | J | | <1.7 | U | | <1.5 | U | | 43 | | | <9.4 | U | | 130 | | | <3.6 | U | | | | | <1.1 | U | | <0.9 | U | |
| | | VMP-6-5-111610 | 11/16/2010 | 5.5 | J | | <6.8 | U | | <10 | U | | <9.6 | U | | 600 | | | <59 | U | | 1100 | | | <23 | U | | | | | 4.2 | J | | <5.6 | U | |
| | | VMP-6-5-020711 | 2/7/2011 | 0.013 | | | 0.0071 | J | | <0.0091 | U | | <0.0083 | U | | 0.03 | | | <0.051 | U | | 0.022 | | | <0.019 | U | | | | | 0.0024 | J | | <0.0049 | U | |
| | | VMP-6-5-040811 | 4/8/2011 | <0.011 | U | | <0.013 | U | | <0.02 | U | | <0.018 | U | | <0.011 | U | | <0.11 | U | | <0.00091 | U | | <0.042 | U | | 0.44 | | | <0.013 | U | | <0.011 | U | |
| | | VMP-6-5-080411 | 8/4/2011 | 0.1 | J | | <0.33 | U | | <0.51 | U | | <0.47 | U | | 3.7 | | | <2.8 | U | | 32 | | | <1.1 | U | | 250 | | | <0.33 | U | | <0.27 | U | |
| | | VMP-6-5-110911 | 11/9/2011 | 0.075 | | | 0.025 | | | <0.0062 | U | | <0.0056 | U | | 0.045 | | | <0.034 | U | | 0.055 | | | <0.013 | U | | 0.065 | | | 0.014 | | | 0.022 | | |
| | | VMP-6-5-013112 | 1/31/2012 | 0.0078 | J | | 0.0065 | J | | <0.073 | U | | <0.066 | U | | 0.43 | | | <0.4 | U | | 1.3 | | | <0.16 | U | | 5.6 | | | 0.0092 | J | | 0.068 | | |
| | | VMP-6-5-041212 | 4/12/2012 | 0.0019 | J | | <0.0049 | U | | <0.0077 | U | | <0.007 | U | | 0.009 | | | <0.043 | U | | 0.0094 | | | <0.016 | U | | 0.0076 | J | | <0.0049 | U | | <0.0041 | U | |
| | | VMP-6-5-071612 | 7/16/2012 | <0.0044 | J | U | 0.0019 | J | | <0.0077 | U | | <0.007 | U | | 0.0025 | J | | <0.043 | U | | 0.0037 | | | <0.016 | U | | <0.012 | U | | <0.0049 | J | U | 0.0029 | J | |
| | | VMP-6-5-101012 | 10/10/2012 | <0.006 | U | | <0.0068 | U | | <0.01 | U | | <0.0096 | U | | <0.0056 | U | | <0.059 | U | | <0.0049 | U | | <0.023 | UJ | UJ | 0.0025 | J | | <0.0068 | U | | <0.0056 | U | |
| | | VMP-6-5-021213 | 2/12/2013 | <0.0054 | U | | <0.0061 | J | U | <0.0095 | U | | <0.0086 | U | | 0.0019 | J | | <0.053 | U | | 0.015 | | | <0.02 | U | | 0.12 | | | <0.0061 | U | | 0.0018 | J | |
| | 10 ft | VMP-6-10-090810 | 9/8/2010 | 0.68 | J | J | 0.9 | J | J | <1.8 | U | | <1.7 | U | | 160 | | J | <10 | U | | 400 | | J | <3.9 | U | | | | | 0.54 | J | J | <0.97 | U | |
| | | VMP-6-10-111710 | 11/17/2010 | 0.0014 | J | | <0.0063 | U | | <0.0099 | U | | <0.009 | U | | 0.0043 | J | | <0.055 | U | | 0.013 | | | <0.021 | U | | | | | <0.0063 | U | | <0.0053 | U | |
| | | VMP-6-10-020711 | 2/7/2011 | <0.0055 | U | | <0.0062 | U | | <0.0096 | U | | <0.0088 | U | | 0.0018 | J | | <0.054 | U | | 0.0038 | J | | <0.021 | U | | | | | <0.0062 | U | | <0.0052 | U | |
| | | VMP-6-10-040811 | 4/8/2011 | 0.028 | J | | <0.15 | U | | <0.23 | U | | <0.21 | U | | <0.12 | U | | <1.3 | U | | <0.11 | U | | <0.5 | U | | <0.36 | U | | <0.15 | U | | <0.12 | U | |
| | | VMP-6-10-080411 | 8/4/2011 | 0.18 | J | | <1 | U | | <1.6 | U | | <1.5 | U | | 76 | | | <9.1 | U | | 210 | | | <3.5 | U | | 770 | | | <1 | U | | <0.88 | U | |
| | | VMP-6-10-111011 | 11/10/2011 | <0.0036 | U | | <0.0041 | U | | <0.0064 | U | | <0.0059 | U | | 0.0016 | J | | <0.036 | U | | 0.0081 | | | <0.014 | U | | 0.062 | | | 0.0018 | J | | 0.022 | | |
| | | VMP-6-10-013112 | 1/31/2012 | <0.65 | U | | <0.73 | U | | <1.1 | U | | <1 | U | | 24 | | J | <6.4 | U | | 98 | | J | <2.4 | U | | 220 | | J | <0.73 | U | | <0.61 | U | |
| | | VMP-6-10-041212 | 4/12/2012 | 0.0024 | J | | 0.0015 | J | | <0.0075 | U | | <0.0068 | U | | 0.0064 | | | <0.042 | U | | 0.0068 | | | <0.016 | U | | 0.005 | J | | <0.0048 | J | U | <0.004 | U | |
| | | VMP-6-10-071612 | 7/16/2012 | <0.0057 | J | U | 0.0015 | J | | <0.01 | U | | <0.0092 | U | | <0.0054 | J | U | <0.056 | U | | 0.0027 | J | | <0.022 | U | | 0.0043 | J | | <0.0065 | J | U | 0.0076 | | |
| | | VMP-6-10-101112 | 10/11/2012 | <0.0063 | U | | <0.0071 | U | | <0.011 | U | | <0.01 | U | | 0.0026 | J | | <0.062 | U | | 0.0022 | J | | <0.024 | UJ | UJ | 0.0057 | J | | <0.0071 | U | | <0.0059 | U | |
| | | VMP-6-10-020513 | 2/5/2013 | <0.006 | U | | <0.0068 | U | | <0.01 | U | | <0.0096 | U | | <0.0056 | U | | <0.059 | U | | 0.0014 | J | | <0.023 | U | | 0.0032 | J | | <0.0068 | U | | <0.0056 | U | |
| | 31.5 ft | VMP-6-31.5-090810 | 9/8/2010 | 160 | | | 16 | | | <12 | U | | <11 | U | | 1900 | | | <69 | U | | 3200 | | | <26 | U | | | | | 19 | | | <6.6 | U | |
| | | VMP-6-31.5-111710 | 11/17/2010 | 150 | | | 13 | | | <19 | U | | <18 | U | | 2200 | | | <110 | U | | 3400 | | | <41 | U | | | | | 19 | | | <10 | U | |
| | | VMP-6-31.5-020711 | 2/7/2011 | 180 | | | 23 | | | <18 | U | | <17 | U | | 1900 | | | <100 | U | | 3000 | | | <40 | U | | | | | 26 | | | <9.9 | U | |
| | | VMP-6-31.5-041111 | 4/11/2011 | 84 | | | 9.4 | | | <14 | U | | <13 | U | | 1100 | | | <80 | U | | 2200 | | | <31 | U | | 1700 | | | 10 | | | <7.7 | U | |
| | | VMP-6-31.5-080411 | 8/4/2011 | 20 | | | <6.8 | U | | <11 | U | | <9.7 | U | | 1000 | | | <59 | U | | 2000 | | | <23 | U | | 1700 | | | 2 | J | | <5.7 | U | |
| | | VMP-6-31.5-111011 | 11/10/2011 | 2.7 | J | | <10 | U | | <16 | U | | <15 | U | | 570 | | | <91 | U | | 1500 | | | <35 | U | | 2000 | | | <10 | U | | <8.8 | U | |
| | | VMP-6-31.5-013112 | 1/31/2012 | 8.3 | | J | <4.2 | U | | <6.6 | U | | <6 | U | | 680 | | J | <36 | U | | 1400 | | J | <14 | U | | 1300 | | J | <4.2 | U | | <3.5 | U | |
| | | VMP-6-31.5-041212 | 4/12/2012 | 0.38 | J | | <0.56 | U | | <0.88 | U | | <0.8 | U | | 8.6 | | | <4.9 | U | | 19 | | | <1.9 | U | | 68 | | | 0.16 | J | | <0.47 | U | |
| | | VMP-6-31.5-071612 | 7/16/2012 | <0.0078 | J | U | 0.0058 | J | | <0.014 | U | | <0.013 | U | | <0.0074 | U | | <0.077 | U | | 0.019 | | | <0.03 | U | | 0.06 | | | <0.0089 | J | U | 0.0055 | J | |
| | | VMP-6-31.5-101112 | 10/11/2012 | <0.0061 | U | | <0.0069 | U | | <0.011 | U | | <0.0098 | U | | <0.0058 | U | | <0.06 | U | | 0.0017 | J | | <0.023 | UJ | UJ | 0.0094 | J | | <0.0069 | U | | 0.0024 | J | |
| | | VMP-6-31.5-020513 | 2/5/2013 | <0.0056 | U | | <0.0063 | U | | <0.0099 | U | | <0.009 | U | | <0.0053 | U | | <0.055 | U | | 0.00091 | J | | <0.021 | U | | 0.008 | J | | <0.0063 | U | | <0.0053 | U | |
| | 39 ft | VMP-6-39-041111 | 4/11/2011 | 120 | | | 14 | | | <17 | U | | <16 | U | | 1200 | | | <95 | U | | 2300 | | | <37 | U | | 1700 | | | 12 | | | <9.2 | U | |
| | | VMP-6-39-013112 | 1/31/2012 | 19 | | J | <4.2 | U | | <6.6 | U | | <6 | U | | 800 | | | <36 | U | | 1700 | | J | <14 | U | | 1600 | | J | 1.4 | J | J | <3.5 | U | |
| | | VMP-6-39-041212 | 4/12/2012 | 7.1 | | | <0.41 | U | | <0.64 | U | | <0.59 | U | | 21 | | | <3.6 | U | | 52 | | | <1.4 | U | | 100 | | | 0.6 | | | <0.34 | U | |
| | | VMP-6-39-071612 | 7/16/2012 | 0.0038 | J | | <0.019 | U | | <0.03 | U | | <0.028 | U | | <0.016 | U | | <0.17 | U | | 0.034 | | | <0.064 | U | | 0.098 | | | 0.0029 | J | | <0.016 | U | |
| | | VMP-6-39-071612-Dup | 7/16/2012 | <0.017 | U | | <0.02 | U | | <0.03 | U | | <0.028 | U | | <0.016 | U | | <0.17 | U | | 0.033 | | | <0.065 | U | | 0.11 | | | <0.02 | U | | <0.016 | U | |
| | | VMP-6-39-101112 | 10/11/2012 | <0.012 | U | | <0.013 | U | | <0.021 | U | | <0.019 | U | | <0.011 | U | | <0.11 | U | | 0.0021 | J | | <0.044 | UJ | UJ | 0.0059 | J | | <0.013 | U | | <0.011 | U | |
| | | VMP-6-39-020513 | 2/5/2013 | 0.034 | | | 0.012 | | | <0.01 | U | | <0.0092 | U | | 0.027 | | | <0.056 | U | | 0.0051 | | | <0.022 | U | | 0.0082 | J | | 0.0056 | J | | <0.0054 | U | |

SEE LAST PAGE OF TABLE FOR NOTES

**TABLE 5**
**CUMULATIVE SUMMARY OF SOIL VAPOR ANALYTICAL DETECTIONS AND SCREENING RESULTS: VILLAGE - VOCS**

| Location | Depth | Sample ID | Sample Date | Ethylbenzene 1400 | | | 4-Ethyltoluene | | | Freon 113 | | | Freon 114 | | | Heptane | | | Hexachlorobutadiene | | | Hexane | | | 2-Hexanone (Methyl N-Butyl Ketone) | | | Isopentane | | | Isopropylbenzene (Cumene) 600 | | | 4-Methyl-2-pentanone (Methyl Isobutyl Ketone) | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals |
| VMP-7 | 5 ft | VMP-7-5-082610 | 8/26/2010 | <0.0057 | U | | <0.0065 | U | | <0.01 | U | | <0.0092 | U | | 0.0044 | J | | <0.056 | U | | 0.016 | | | <0.022 | U | | | | | <0.0065 | U | | <0.0054 | U | |
| | | VMP-7-5-111910 | 11/19/2010 | 0.00077 | J | | <0.0058 | U | | <0.0091 | U | | <0.0083 | U | | 0.0039 | J | | <0.051 | U | | 0.0047 | | | <0.019 | U | | | | | <0.0058 | U | | <0.0049 | U | |
| | | VMP-7-5-020711 | 2/7/2011 | <0.0056 | U | | <0.0063 | U | | <0.0099 | U | | <0.009 | U | | 0.0041 | J | | <0.055 | U | | 0.0024 | J | | <0.021 | U | | | | | <0.0063 | U | | <0.0053 | U | |
| | | VMP-7-5-040711 | 4/7/2011 | <0.0079 | U | | <0.0089 | U | | <0.014 | U | | <0.013 | U | | 0.0074 | | | <0.078 | U | | 0.016 | | | <0.03 | U | | 0.019 | J | | <0.0089 | U | | <0.0074 | U | |
| | | VMP-7-5-080211 | 8/2/2011 | <0.78 | U | | <0.89 | U | | <1.4 | U | | <1.3 | U | | 4.5 | | | <7.7 | U | | 12 | | | <3 | U | | 520 | | | <0.89 | U | | <0.74 | U | |
| | | VMP-7-5-111011 | 11/10/2011 | <0.0037 | U | | <0.0042 | U | | <0.0066 | U | | <0.006 | U | | <0.0035 | U | | <0.036 | U | | <0.003 | U | | <0.014 | U | | <0.01 | U | | 0.0018 | J | | 0.0099 | | |
| | | VMP-7-5-111011-DUP | 11/10/2011 | <0.0035 | U | | <0.004 | U | | <0.0062 | U | | <0.0056 | U | | <0.0033 | U | | <0.034 | U | | <0.0028 | U | | <0.013 | U | | 0.0076 | J | | 0.0016 | J | | 0.0084 | | |
| | | VMP-7-5-013112 | 1/31/2012 | 0.0012 | J | | <0.0043 | J | U | <0.0067 | U | | <0.0061 | U | | 0.00073 | J | | <0.037 | U | | <0.0031 | J | U | 0.00059 | J | | <0.01 | U | | 0.0027 | J | | 0.017 | | |
| | | VMP-7-5-041212 | 4/12/2012 | 0.0046 | | | 0.0025 | J | | <0.0073 | U | | <0.0066 | U | | 0.0078 | | | <0.04 | U | | 0.0046 | | | <0.016 | U | | 0.0049 | J | | 0.04 | | | 0.11 | | |
| | | VMP-7-5-073112 | 7/31/2012 | 0.0038 | J | | <0.012 | U | | <0.019 | U | | <0.017 | U | | <0.01 | U | | <0.1 | U | | 0.0031 | J | | <0.04 | U | | 0.1 | | | 0.037 | U | | 0.12 | | |
| | | VMP-7-5-101012 | 10/10/2012 | <0.0064 | U | | <0.0073 | U | | <0.011 | U | | <0.01 | U | | <0.0061 | U | | <0.063 | U | | 0.0012 | J | | <0.024 | U | | <0.017 | U | | <0.0073 | U | | <0.0061 | U | |
| | 13.5 ft | VMP-7-13.5-082610 | 8/26/2010 | <0.12 | U | | <0.14 | U | | <0.22 | U | | <0.2 | U | | <0.12 | U | | <1.2 | U | | 0.035 | J | | <0.47 | U | | | | | 0.015 | J | | <0.12 | U | |
| | | VMP-7-13.5-111910 | 11/19/2010 | <0.87 | U | | <0.99 | U | | <1.5 | U | | <1.4 | U | J | 4.9 | | J | <8.6 | U | | 8.9 | | J | <3.3 | U | | | | | <0.99 | U | | <0.82 | U | |
| | | VMP-7-13.5-020711 | 2/7/2011 | <0.0054 | U | | <0.0061 | U | | <0.0095 | U | | <0.0086 | U | | 0.0011 | J | | <0.053 | U | | 0.0013 | J | | <0.02 | U | | | | | <0.0061 | U | | <0.005 | U | |
| | | VMP-7-13.5-040711 | 4/7/2011 | <0.0094 | U | | <0.011 | U | | <0.016 | U | | <0.015 | U | | 0.0064 | J | | <0.092 | U | | 0.022 | | | <0.035 | U | | 0.024 | J | | <0.011 | U | | <0.0088 | U | |
| | | VMP-7-13.5-080311 | 8/3/2011 | <1 | U | | <1.2 | U | | <1.8 | U | | <1.7 | U | | <0.99 | U | | <10 | U | | 2.7 | | | <3.9 | U | | 310 | | | <1.2 | U | | <0.99 | U | |
| | | VMP-7-13.5-111011 | 11/10/2011 | 0.013 | | | 0.0037 | J | | <0.006 | U | | <0.0055 | U | | 0.026 | | | <0.034 | U | | 0.012 | | | <0.013 | U | | 0.8 | | | 0.0083 | | | 0.022 | | |
| | | VMP-7-13.5-013112 | 1/31/2012 | <0.049 | U | | <0.055 | U | | <0.086 | U | | <0.078 | U | | <0.046 | U | | <0.48 | U | | 1.1 | | J | <0.18 | U | | 7.2 | | J | <0.055 | U | | <0.046 | U | |
| | | VMP-7-13.5-013112-DUP | 1/31/2012 | <0.05 | U | | <0.056 | U | | <0.088 | U | | <0.08 | U | | <0.047 | U | | <0.49 | U | | 1 | | J | <0.19 | U | | 6.9 | | J | <0.056 | U | | <0.047 | U | |
| | | VMP-7-13.5-041212 | 4/12/2012 | 0.0026 | J | | 0.0016 | J | | <0.007 | U | | <0.0064 | U | | 0.015 | | | <0.039 | U | | 0.022 | | | <0.015 | U | | 0.026 | | J | 0.024 | | | 0.033 | | |
| | | VMP-7-13.5-041212-DUP | 4/12/2012 | 0.0028 | J | | 0.0015 | J | | <0.0074 | U | | <0.0067 | U | | 0.0086 | | | <0.041 | U | | 0.011 | | | <0.016 | U | | 0.49 | | J | 0.026 | | | 0.036 | | |
| | | VMP-7-13.5-072012 | 7/20/2012 | 0.003 | J | | 0.001 | J | | <0.0072 | U | | <0.0065 | U | | 0.0063 | | | <0.04 | U | | 0.00095 | J | | 0.0013 | J | | <0.011 | U | | 0.033 | | | 0.13 | | |
| | | VMP-7-13.5-101012 | 10/10/2012 | <0.006 | U | | <0.0068 | U | | <0.01 | U | | <0.0096 | U | | 0.0027 | J | | <0.059 | U | | 0.0035 | J | | <0.023 | U | | 0.0033 | J | | <0.0068 | U | | <0.0056 | U | |
| | | VMP-7-13.5-021313 | 2/13/2013 | <0.006 | U | | <0.0068 | U | | <0.01 | U | | <0.0096 | U | | <0.0056 | U | | <0.059 | U | | 0.0012 | J | | <0.023 | U | | 0.0018 | J | | <0.0068 | U | | <0.0056 | U | |
| | 29.5 ft | VMP-7-29.5-083110 | 8/31/2010 | <1.8 | U | | <2 | U | | <3.2 | U | | <2.9 | U | | 420 | | J | <18 | U | | 420 | | J | <6.7 | U | | | | | 6 | | J | <1.7 | U | |
| | | VMP-7-29.5-111910 | 11/19/2010 | <2.7 | U | | <3 | U | | <4.8 | U | | <4.3 | U | | 300 | | J | <26 | U | | 270 | | | <10 | U | | | | | 4.8 | | J | <2.5 | U | |
| | | VMP-7-29.5-020711 | 2/7/2011 | <2.8 | U | | 0.77 | J | | <4.9 | U | | <4.5 | U | | 350 | | | <28 | U | | 320 | | | <10 | U | | | | | 10 | | | <2.6 | U | |
| | | VMP-7-29.5-040711 | 4/7/2011 | <0.68 | U | | 0.23 | J | J | <1.2 | U | | <1.1 | U | | 220 | | J | <6.7 | U | | 190 | | J | <2.6 | U | | 380 | | J | 3.4 | | J | <0.64 | U | |
| | | VMP-7-29.5-080311 | 8/3/2011 | <1.6 | U | | <1.8 | U | | <2.8 | U | | <2.6 | U | | 350 | | | <16 | U | | 360 | | | <6.1 | U | | 850 | | | 1.6 | J | | <1.5 | U | |
| | | VMP-7-29.5-111111 | 11/11/2011 | 2.7 | J | | 1.6 | J | | <5.6 | U | | <5.1 | U | | 110 | | | <31 | U | | 130 | | | <12 | U | | 500 | | | <3.6 | U | | <3 | U | |
| | | VMP-7-29.5-020112 | 2/1/2012 | <0.63 | U | | <0.72 | U | | <1.1 | U | | <1 | U | | 150 | | J | <6.2 | U | | 160 | | J | <2.4 | U | | 360 | | J | 0.54 | J | J | <0.6 | U | |
| | | VMP-7-29.5-041312 | 4/13/2012 | 0.0017 | J | | 0.0051 | | | <0.007 | U | | <0.0064 | U | | 0.012 | | | <0.039 | U | | 0.02 | | | <0.015 | U | | 0.21 | | | 0.018 | | | 0.024 | | |
| | | VMP-7-29.5-072012 | 7/20/2012 | 0.0031 | J | | 0.00088 | J | | <0.0072 | U | | <0.0065 | U | | 0.0043 | | | <0.04 | U | | 0.005 | | | <0.015 | U | | <0.011 | U | | 0.0052 | | | 0.025 | | |
| | | VMP-7-29.5-072012-Dup | 7/20/2012 | 0.003 | J | | 0.00093 | J | | <0.0072 | U | | <0.0065 | U | | 0.0036 | J | | <0.04 | U | | 0.0048 | | | <0.015 | U | | <0.011 | U | | 0.0061 | | | 0.027 | | |
| | | VMP-7-29.5-101012 | 10/10/2012 | <0.0063 | U | | <0.0071 | U | | <0.011 | U | | <0.01 | U | | <0.0059 | U | | <0.062 | U | | 0.0029 | J | | <0.024 | UJ | UJ | 0.0057 | J | | <0.0071 | U | | <0.0059 | U | |
| | 38 ft | VMP-7-38-020711 | 2/7/2011 | <3.8 | U | | <4.2 | U | | <6.6 | U | | <6 | U | | 210 | | | <37 | U | | 280 | | | <14 | U | | | | | 6.8 | | | <3.5 | U | |
| | | VMP-7-38-040711 | 4/7/2011 | <0.96 | U | | <1.1 | U | | <1.7 | U | | <1.5 | U | | 110 | | J | <9.4 | U | | 150 | | J | <3.6 | U | | 500 | | J | 0.56 | J | J | <0.9 | U | |
| | | VMP-7-38-020112 | 2/1/2012 | <0.91 | U | | <1 | U | | <1.6 | U | | <1.5 | U | | 180 | | J | <9 | U | | 180 | | J | <3.4 | U | | 390 | | J | 0.55 | J | J | <0.86 | U | |
| | | VMP-7-38-042512 | 4/25/2012 | 0.0051 | | | 0.002 | J | | <0.007 | U | | <0.0064 | U | | 0.0096 | | | <0.039 | U | | 0.018 | | J | <0.015 | U | | 0.043 | | | 0.019 | | | 0.047 | | |
| | | VMP-7-38-042512-Dup | 4/25/2012 | 0.0036 | J | | <0.0045 | U | | <0.007 | U | | <0.0064 | U | | 0.01 | | | <0.039 | U | | 0.024 | | J | <0.015 | U | | 0.058 | | | 0.02 | | | 0.047 | | |
| | | VMP-7-38-101112 | 10/11/2012 | <0.0058 | U | | <0.0066 | U | | <0.01 | U | | <0.0094 | U | | <0.0055 | U | | <0.057 | U | | 0.0017 | J | | <0.022 | UJ | UJ | 0.0033 | J | | <0.0066 | U | | 0.003 | J | |
| VMP-8 | 5 ft | VMP-8-5-083010 | 8/30/2010 | <0.0058 | U | | 0.0014 | J | | 0.0019 | J | | <0.0094 | U | | 0.0019 | J | | <0.057 | U | | 0.0032 | J | | 0.0029 | J | | | | | <0.0066 | U | | <0.0055 | U | |
| | | VMP-8-5-111810 | 11/17/2010 | <0.005 | J | U | <0.0057 | U | | 0.0017 | J | | <0.0081 | U | | 0.0025 | J | | <0.05 | U | | 0.0019 | J | | <0.019 | U | | | | | <0.0057 | U | | <0.0048 | U | |
| | | VMP-8-5-021011 | 2/10/2011 | <0.0054 | U | | <0.0061 | U | | <0.0095 | U | | <0.0086 | U | | <0.0051 | U | | <0.053 | U | | 0.0011 | J | | <0.02 | U | | | | | <0.0061 | U | | <0.005 | U | |
| | | VMP-8-5-040711 | 4/7/2011 | <0.006 | U | | <0.0068 | U | | <0.01 | U | | <0.0096 | U | | <0.0056 | U | | <0.059 | U | | <0.0049 | U | | <0.023 | U | | 0.0037 | J | | <0.0068 | U | | <0.0056 | U | |
| | | VMP-8-5-072711 | 7/27/2011 | 0.0026 | J | | 0.0033 | J | | <0.011 | U | | <0.01 | U | | 0.0021 | J | | <0.063 | U | | 0.0026 | J | | 0.0054 | J | | <0.017 | U | | 0.05 | | | 0.24 | | |
| | | VMP-8-5-110311 | 11/3/2011 | 0.0033 | J | | 0.00052 | J | | <0.0066 | U | | <0.006 | U | | 0.0026 | J | | <0.036 | U | | 0.0033 | | | 0.0006 | J | | 0.017 | | | 0.0028 | J | | 0.015 | | |
| | | VMP-8-5-012312 | 1/23/2012 | 0.00052 | J | | 0.00067 | J | | <0.0081 | U | | <0.0074 | U | | 0.0016 | J | | <0.045 | U | | 0.0024 | J | | <0.017 | U | | 0.0092 | J | | 0.003 | J | | 0.058 | | |
| | | VMP-8-5-041012 | 4/10/2012 | 0.0034 | J | | 0.0014 | J | | <0.0073 | U | | <0.0067 | U | | 0.0064 | | | <0.041 | U | | 0.0073 | | | <0.016 | U | | 0.063 | | | 0.0017 | J | | <0.0039 | U | |
| | | VMP-8-5-071312 | 7/13/2012 | <0.0035 | U | | <0.004 | J | U | <0.0062 | U | | <0.0056 | U | | <0.0033 | U | | <0.034 | U | | 0.00072 | J | | <0.013 | J | U | 0.0022 | J | | <0.004 | U | | <0.0033 | J | U |
| | | VMP-8-5-073112 | 7/31/2012 | 0.0044 | | | 0.00067 | J | | <0.0079 | U | | <0.0072 | U | | 0.011 | | | <0.044 | U | | 0.002 | J | | 0.0025 | J | | 0.011 | J | | 0.057 | | | 0.2 | | |
| | | VMP-8-5-100412 | 10/4/2012 | <0.006 | U | | <0.0068 | U | | <0.01 | U | | <0.0096 | U | | 0.0019 | J | | 0.0076 | J | | 0.0026 | J | | <0.023 | U | | 0.0031 | J | | <0.0068 | U | | <0.0056 | U | |
| | | VMP-8-5-100412-Dup | 10/4/2012 | <0.0057 | U | | <0.0065 | U | | <0.01 | U | | <0.0092 | U | | 0.0019 | J | | <0.056 | U | | 0.003 | J | | <0.022 | U | | 0.0028 | J | | <0.0065 | U | | <0.0054 | U | |
| | | VMP-8-5-012413 | 1/24/2013 | <0.0058 | U | | <0.0066 | U | | <0.01 | U | | <0.0094 | U | | <0.0055 | U | | <0.057 | U | | <0.0047 | U | | <0.022 | U | | <0.016 | U | | <0.0066 | U | | 0.0028 | J | |
| | 9.5 ft | VMP-8-9.5 | 11/10/2009 | <0.004 | U | | <0.005 | U | | <0.008 | U | | <0.007 | U | | 0.0046 | | | <0.048 | U | | 0.0042 | | | <0.018 | U | | | | | <0.005 | U | | <0.004 | U | |
| | | VMP-8-9.5-083010 | 8/30/2010 | <0.0052 | U | | 0.0011 | J | | 0.0011 | J | | <0.0084 | U | | 0.0017 | J | | <0.052 | U | | 0.0055 | | | 0.0013 | J | | | | | <0.0059 | U | | <0.005 | U | |
| | | VMP-8-9.5-083010-DUP | 8/30/2010 | <0.0054 | U | | <0.0061 | U | | 0.001 | J | | <0.0086 | U | | 0.0016 | J | | <0.053 | U | | 0.0034 | J | | 0.0017 | J | | | | | <0.0061 | U | | <0.005 | U | |
| | | VMP-8-9.5-111810 | 11/17/2010 | <0.0052 | J | U | <0.0059 | U | | 0.0018 | J | | <0.0084 | U | | <0.005 | U | | <0.052 | U | | 0.0017 | J | | <0.02 | U | | | | | <0.0059 | U | | <0.005 | U | |
| | | VMP-8-9.5-021011 | 2/10/2011 | <0.0055 | U | | <0.0062 | U | | <0.0096 | U | | <0.0088 | U | | <0.0052 | U | | <0.054 | U | | <0.0044 | U | | <0.021 | U | | | | | <0.0062 | U | | <0.0052 | U | |
| | | VMP-8-9.5-040711 | 4/7/2011 | <0.006 | U | | <0.0068 | U | | <0.01 | U | | <0.0096 | U | | <0.0056 | U | | <0.059 | U | | 0.0012 | J | | <0.023 | U | | 0.0031 | J | | <0.0068 | U | | <0.0056 | U | |
| | | VMP-8-9.5-072711 | 7/27/2011 | 0.0028 | J | | 0.0032 | J | | <0.0082 | U | | <0.0074 | U | | 0.0039 | J | | <0.045 | U | | 0.0048 | | | 0.0048 | J | | 0.02 | | | 0.045 | | | 0.13 | | |
| | | VMP-8-9.5-110311 | 11/3/2011 | 0.0044 | | | 0.0011 | J | | <0.0064 | U | | <0.0059 | U | | 0.0021 | J | | <0.036 | U | | 0.0018 | J | | 0.00037 | J | | 0.011 | | | 0.0014 | J | | 0.0088 | | |
| | | VMP-8-9.5-012312 | 1/23/2012 | 0.0014 | J | | 0.00079 | J | | <0.0078 | U | | <0.0071 | U | | 0.005 | | | <0.043 | U | | 0.0064 | | | <0.017 | U | | 0.019 | | | 0.0026 | J | | 0.0061 | | |
| | | VMP-8-9.5-041012 | 4/10/2012 | 0.00077 | J | | <0.0047 | U | | <0.0073 | U | | <0.0067 | U | | 0.002 | J | | <0.041 | U | | 0.012 | | | <0.016 | U | | 0.051 | | | <0.0047 | U | | <0.0039 | U | |
| | | VMP-8-9.5-071312 | 7/13/2012 | <0.004 | U | | <0.0046 | U | | <0.0072 | U | | <0.0065 | U | | <0.0038 | U | | <0.04 | U | | <0.0033 | U | | <0.015 | U | | <0.011 | U | | <0.0046 | U | | <0.0038 | U | |
| | | VMP-8-9.5-071312-Dup | 7/13/2012 | <0.0039 | U | | <0.0044 | U | | <0.0068 | U | | <0.0062 | U | | <0.0037 | U | | <0.038 | U | | <0.0032 | U | | <0.015 | U | | <0.01 | U | | <0.0044 | U | | <0.0037 | U | |
| | | VMP-8-9.5-100412 | 10/4/2012 | 0.0024 | J | | <0.0074 | U | | <0.012 | U | | <0.01 | U | | 0.0061 | J | | <0.065 | U | | 0.0088 | | | <0.025 | U | | 0.024 | | | <0.0074 | U | | <0.0062 | U | |
| | | VMP-8-9.5-012413 | 1/24/2013 | <0.0055 | U | | <0.0062 | U | | <0.0096 | U | | <0.0088 | U | | <0.0052 | U | | <0.054 | U | | 0.0018 | J | | <0.021 | U | | 0.0077 | J | | <0.0062 | U | | <0.0052 | U | |
| | | VMP-8-9.5-012413-Dup | 1/24/2013 | <0.0058 | U | | <0.0066 | U | | <0.01 | U | | <0.0094 | U | | <0.0055 | U | | <0.057 | U | | <0.0047 | U | | <0.022 | U | | 0.0062 | J | | <0.0066 | U | | <0.0055 | U | |
| | 23.5 ft | VMP-8-23.5-083010 | 8/30/2010 | <0.0057 | U | | <0.0065 | U | | 0.0014 | J | | <0.0092 | U | | 0.0021 | J | | <0.056 | U | | 0.0024 | J | | 0.0011 | J | | | | | <0.0065 | U | | <0.0054 | U | |
| | | VMP-8-23.5-111910 | 11/19/2010 | 0.0015 | J | | <0.0062 | U | | <0.0096 | U | | <0.0088 | U | | 0.0015 | J | | <0.054 | U | | 0.0018 | J | | <0.021 | U | | | | | <0.0062 | U | | <0.0052 | U | |
| | | VMP-8-23.5-021011 | 2/10/2011 | <0.0058 | U | | <0.0066 | U | | <0.01 | U | | <0.0094 | U | | <0.0055 | U | | <0.057 | U | | <0.0047 | U | | <0.022 | U | | | | | <0.0066 | U | | <0.0055 | U | |
| | | VMP-8-23.5-040711 | 4/7/2011 | 0.00066 | J | | <0.0062 | U | | <0.0096 | U | | <0.0088 | U | | <0.0052 | U | | <0.054 | U | | 0.0027 | J | | <0.021 | U | | 0.003 | J | | <0.0062 | U | | <0.0052 | U | |
| | | VMP-8-23.5-040711-DUP | 4/7/2011 | <0.0087 | U | | <0.0098 | U | | <0.015 | U | | <0.014 | U | | <0.0082 | U | | <0.085 | U | | 0.0028 | J | | <0.033 | U | | 0.0049 | J | | <0.0098 | U | | <0.0082 | U | |
| | | VMP-8-23.5-081011 | 8/10/2011 | 0.0023 | J | | <0.0065 | J | U | <0.01 | U | | <0.0092 | U | | 0.012 | | | <0.056 | U | | 0.033 | | | 0.0022 | J | | 0.069 | | | 0.019 | | | 0.1 | | |
| | | VMP-8-23.5-110611 | 11/6/2011 | 0.001 | J | | 0.0012 | J | | <0.0073 | U | | <0.0067 | U | | 0.0013 | J | | <0.041 | U | | 0.0028 | J | | 0.0015 | J | | <0.011 | U | | 0.0052 | | | 0.035 | | |
| | | VMP-8-23.5-012312 | 1/23/2012 | 0.00079 | J | | 0.00098 | J | | <0.0081 | U | | <0.0074 | U | | 0.0023 | J | | <0.045 | U | | 0.0023 | J | | 0.00075 | J | | 0.017 | | | 0.002 | J | | 0.024 | | |
| | | VMP-8-23.5-041012 | 4/10/2012 | 0.0015 | J | | 0.00077 | J | | <0.0072 | U | | <0.0065 | U | | 0.0022 | J | | <0.04 | U | | 0.012 | | | <0.015 | U | | 0.062 | | | 0.00051 | J | | <0.0038 | U | |
| | | VMP-8-23.5-071312 | 7/13/2012 | <0.0045 | U | | <0.0051 | U | | <0.0079 | U | | <0.0072 | U | | <0.0042 | U | | <0.044 | U | | <0.0036 | U | | <0.017 | U | | 0.001 | J | | <0.0051 | U | | <0.0042 | U | |
| | | VMP-8-23.5-100412 | 10/4/2012 | <0.0063 | U | | <0.0071 | U | | <0.011 | U | | <0.01 | U | | 0.0059 | | | <0.062 | U | | 0.0082 | | | <0.024 | U | | 0.015 | J | | <0.0071 | U | | <0.0059 | U | |
| | | VMP-8-23.5-012413 | 1/24/2013 | <0.0063 | U | | <0.0071 | U | | <0.011 | U | | <0.01 | U | | <0.0059 | U | | <0.062 | U | | <0.0051 | U | | <0.024 | U | | <0.017 | U | | <0.0071 | U | | <0.0059 | U | |

SEE LAST PAGE OF TABLE FOR NOTES

**TABLE 5**
**CUMULATIVE SUMMARY OF SOIL VAPOR ANALYTICAL DETECTIONS AND SCREENING RESULTS: VILLAGE - VOCS**

| Location | Depth | Sample ID | Sample Date | Ethylbenzene | | | 4-Ethyltoluene | | | Freon 113 | | | Freon 114 | | | Heptane | | | Hexachlorobutadiene | | | Hexane | | | 2-Hexanone (Methyl N-Butyl Ketone) | | | Isopentane | | | Isopropylbenzene (Cumene) | | | 4-Methyl-2-pentanone (Methyl Isobutyl Ketone) | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | 1400 | | | | | | | | | | | | | | | | | | | | | | | | | | 600 | | | | | |
| | | | | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals |
| VMP-9 | 5 ft | VMP-9-5-082610 | 8/26/2010 | 0.00048 | J | | <0.0056 | U | | <0.0087 | U | | <0.008 | U | | 0.0055 | | | <0.049 | U | | 0.016 | | | <0.019 | U | | | | | <0.0056 | U | | <0.0047 | U | |
| | | VMP-9-5-111910 | 11/19/2010 | 0.001 | J | | <0.0058 | U | | <0.0091 | U | | <0.0083 | U | | 0.0016 | J | | <0.051 | U | | 0.0014 | J | | <0.019 | U | | | | | <0.0058 | U | | <0.0049 | U | |
| | | VMP-9-5-020811 | 2/8/2011 | <0.0048 | U | | <0.0054 | U | | <0.0084 | U | | <0.0077 | U | | <0.0045 | U | | <0.047 | U | | <0.0039 | U | | <0.018 | U | | | | | <0.0054 | U | | <0.0045 | U | |
| | | VMP-9-5-040611 | 4/6/2011 | <0.013 | U | | <0.015 | U | | <0.023 | U | | <0.021 | U | | <0.012 | U | | <0.13 | U | | 0.0064 | J | | <0.05 | U | | 0.013 | J | | <0.015 | U | | <0.012 | U | |
| | | VMP-9-5-080211 | 8/2/2011 | <0.26 | U | | <0.29 | U | | <0.45 | U | | <0.41 | U | | <0.24 | U | | <2.5 | U | | <0.21 | U | | <0.97 | U | | 6.1 | | | 0.06 | J | | 0.32 | | |
| | | VMP-9-5-110411 | 11/4/2011 | <0.0038 | U | | <0.0043 | J | U | <0.0067 | U | | <0.0061 | U | | 0.003 | J | | <0.037 | U | | 0.0027 | J | | 0.0013 | J | | 0.0024 | J | | <0.0043 | J | U | 0.022 | | |
| | | VMP-9-5-012612 | 1/26/2012 | <0.0032 | J | U | 0.00052 | J | | <0.0057 | U | | <0.0052 | U | | 0.0078 | | | <0.032 | U | | 0.0049 | | | <0.012 | U | | 0.29 | | | 0.008 | | | 0.039 | | |
| | | VMP-9-5-041112 | 4/11/2012 | 0.0042 | | | 0.0011 | J | | <0.0068 | U | | <0.0062 | U | | 0.012 | | | <0.038 | U | | 0.018 | | | <0.015 | U | | 0.016 | | | 0.0015 | J | | <0.0037 | U | |
| | | VMP-9-5-071312 | 7/13/2012 | 0.0023 | J | | <0.0047 | J | U | <0.0073 | U | | <0.0067 | U | | 0.0019 | J | | <0.041 | U | | 0.0028 | J | | <0.016 | J | U | 0.009 | J | | 0.017 | | | 0.17 | | |
| | | VMP-9-5-101012 | 10/10/2012 | <0.0063 | U | | <0.0071 | U | | <0.011 | U | | <0.01 | U | | <0.0059 | U | | <0.062 | U | | <0.0051 | U | | <0.024 | UJ | UJ | 0.0021 | J | | <0.0071 | U | | <0.0059 | U | |
| | | [a]VMP-9-5-012513 | 1/25/2013 | <0.0061 | U | UJ | <0.0069 | U | UJ | <0.011 | U | UJ | <0.0098 | U | UJ | <0.0058 | U | UJ | <0.06 | U | UJ | 0.0024 | J | J | <0.023 | U | UJ | 0.0022 | J | J | <0.0069 | U | UJ | <0.0058 | U | UJ |
| | | VMP-9-5-021513 | 2/15/2013 | 0.0027 | J | | 0.0032 | J | | <0.01 | U | | <0.0096 | U | | <0.0056 | U | | <0.059 | U | | 0.004 | J | | <0.023 | U | | 0.044 | | | 0.0032 | J | | <0.0056 | U | |
| | 11.5 ft | VMP-9-11.5-082610 | 8/26/2010 | <0.11 | U | | <0.13 | U | | <0.2 | U | | <0.18 | U | | <0.1 | U | | <1.1 | U | | <0.09 | U | | <0.42 | U | | | | | <0.13 | U | | <0.1 | U | |
| | | VMP-9-11.5-111910 | 11/19/2010 | <0.32 | U | | <0.37 | U | | <0.57 | U | | <0.52 | U | | <0.3 | U | | <3.2 | U | | <0.26 | U | | <1.2 | U | | | | | <0.37 | U | | <0.3 | U | |
| | | VMP-9-11.5-020911 | 2/9/2011 | <0.0058 | U | | <0.0066 | U | | <0.01 | U | | <0.0094 | U | | <0.0055 | U | | <0.057 | U | | <0.0047 | U | | <0.022 | U | | | | | <0.0066 | U | | <0.0055 | U | |
| | | VMP-9-11.5-020911-DUP | 2/9/2011 | <0.0045 | U | | <0.0051 | U | | <0.008 | U | | <0.0073 | U | | 0.0025 | J | | <0.044 | U | | <0.0037 | U | | <0.017 | U | | | | | <0.0051 | U | | <0.0043 | U | |
| | | VMP-9-11.5-040611 | 4/6/2011 | <0.017 | U | | <0.019 | U | | <0.03 | U | | <0.028 | U | | 0.0035 | J | | <0.17 | U | | 0.0079 | J | | <0.065 | U | | 0.0091 | J | | <0.019 | U | | <0.016 | U | |
| | | VMP-9-11.5-080211 | 8/2/2011 | <0.38 | U | | <0.43 | U | | <0.67 | U | | <0.62 | U | | <0.36 | U | | <3.8 | U | | <0.31 | U | | <1.4 | U | | 54 | | | <0.43 | U | | <0.36 | U | |
| | | VMP-9-11.5-110411 | 11/4/2011 | <0.0038 | U | | <0.0043 | J | U | <0.0067 | U | | <0.0061 | U | | 0.0021 | J | | <0.037 | U | | 0.0029 | J | | 0.001 | J | | 0.066 | | | <0.0043 | J | U | 0.035 | | |
| | | VMP-9-11.5-012612 | 1/26/2012 | <0.0034 | J | U | <0.0038 | U | | <0.0059 | U | | <0.0054 | U | | 0.0014 | J | | <0.033 | U | | 0.0014 | J | | <0.013 | U | | 0.084 | | | 0.0083 | | | 0.052 | | |
| | | VMP-9-11.5-041112 | 4/11/2012 | <0.004 | U | | <0.0045 | U | | <0.007 | U | | <0.0064 | U | | 0.0037 | J | | <0.039 | U | | 0.013 | | | <0.015 | U | | 0.011 | | | <0.0045 | U | | <0.0037 | U | |
| | | VMP-9-11.5-071312 | 7/13/2012 | 0.0037 | J | | <0.0051 | J | U | <0.0079 | U | | <0.0072 | U | | 0.002 | J | | <0.044 | U | | 0.0013 | J | | <0.017 | J | U | 0.0036 | J | | 0.035 | | | 0.17 | | |
| | | VMP-9-11.5-101012 | 10/10/2012 | 0.0011 | J | | <0.0068 | U | | <0.01 | U | | <0.0096 | U | | 0.0021 | J | | <0.059 | U | | 0.0021 | J | | <0.023 | UJ | UJ | 0.0071 | J | | <0.0068 | U | | <0.0056 | U | |
| | | VMP-9-11.5-012513 | 1/25/2013 | 0.0013 | J | | <0.0057 | U | | <0.0089 | U | | <0.0081 | U | | 0.0035 | J | | <0.05 | U | | 0.0079 | | | <0.019 | U | | 0.049 | | J | <0.0057 | U | | <0.0048 | U | |
| | | VMP-9-11.5-012513-DUP | 1/25/2013 | 0.0016 | J | | <0.0062 | J | U | <0.0096 | U | | <0.0088 | U | | 0.0046 | J | | <0.054 | U | | 0.012 | | | <0.021 | U | | 0.093 | | J | <0.0062 | U | | <0.0052 | U | |
| | 25.5 ft | VMP-9-25.5-082610 | 8/26/2010 | <0.87 | U | | <0.99 | U | | <1.5 | U | | <1.4 | U | | 1.1 | | | <8.6 | U | | 3.2 | | | <3.3 | U | | | | | 0.13 | J | | <0.82 | U | |
| | | VMP-9-25.5-082610-DUP | 8/26/2010 | <0.94 | U | | <1.1 | U | | <1.6 | U | | <1.5 | U | | 1.1 | | | <9.2 | U | | 3.2 | | | <3.5 | U | | | | | 0.13 | J | | <0.88 | U | |
| | | VMP-9-25.5-111910 | 11/19/2010 | <1 | U | | <1.1 | U | | <1.8 | U | | <1.6 | U | | <0.94 | U | | <9.8 | U | | 1.8 | | | <3.8 | U | | | | | <1.1 | U | | <0.94 | U | |
| | | VMP-9-25.5-020911 | 2/9/2011 | <0.55 | U | | <0.62 | U | | <0.96 | U | | <0.88 | U | | <0.52 | U | | <5.4 | U | | 0.24 | J | | <2.1 | U | | | | | <0.62 | U | | <0.52 | U | |
| | | VMP-9-25.5-040811 | 4/8/2011 | <0.28 | U | | <0.31 | U | | <0.49 | U | | <0.45 | U | | <0.26 | U | | <2.7 | U | | <0.22 | U | | <1 | U | | 35 | | | 0.029 | J | | <0.26 | U | |
| | | VMP-9-25.5-080211 | 8/2/2011 | <0.61 | U | | <0.69 | U | | <1.1 | U | | <0.98 | U | | 0.82 | | J | <6 | U | | 2.8 | | J | <2.3 | U | | 460 | | | <0.69 | U | | <0.58 | U | |
| | | VMP-9-25.5-110711 | 11/7/2011 | <0.54 | U | | <0.61 | U | | <0.95 | U | | <0.87 | U | | <0.51 | U | | <5.3 | U | | 0.62 | | | <2 | U | | 87 | | | <0.61 | U | | <0.51 | U | |
| | | VMP-9-25.5-110711-DUP | 11/7/2011 | <0.47 | U | | <0.53 | U | | <0.82 | U | | <0.75 | U | | <0.44 | U | | <4.6 | U | | 0.68 | | | <1.8 | U | | 87 | | | <0.53 | U | | <0.44 | U | |
| | | VMP-9-25.5-012612 | 1/26/2012 | <0.14 | U | | <0.16 | U | | <0.25 | U | | <0.22 | U | | <0.13 | U | | <1.4 | U | | 1 | | J | <0.53 | U | | 81 | | J | <0.16 | U | | <0.13 | U | |
| | | VMP-9-25.5-041112 | 4/11/2012 | 0.0049 | | | 0.0013 | J | | <0.007 | U | | <0.0064 | U | | 0.012 | | | <0.039 | U | | 0.0085 | | | <0.015 | U | | 0.0095 | J | | 0.0017 | J | | <0.0037 | U | |
| | | VMP-9-25.5-071312 | 7/13/2012 | 0.0054 | | | 0.004 | J | | <0.0075 | U | | <0.0069 | U | | 0.0031 | J | | <0.042 | U | | <0.0035 | J | U | 0.0046 | J | | <0.012 | U | | 0.053 | | | 0.17 | | |
| | | VMP-9-25.5-071312-Dup | 7/13/2012 | 0.0054 | | | 0.0037 | J | | <0.0073 | U | | <0.0067 | U | | <0.0039 | J | U | <0.041 | U | | 0.0025 | J | | 0.0036 | J | | 0.0056 | J | | 0.049 | | | 0.17 | | |
| | | VMP-9-25.5-101012 | 10/10/2012 | <0.0057 | U | | <0.0065 | U | | <0.01 | U | | <0.0092 | U | | <0.0054 | U | | <0.056 | U | | <0.0046 | U | | <0.022 | UJ | UJ | <0.016 | U | | <0.0065 | U | | <0.0054 | U | |
| | | VMP-9-25.5-013013 | 1/30/2013 | <0.0061 | U | | <0.0069 | U | | <0.011 | U | | <0.0098 | U | | <0.0058 | U | | <0.06 | U | | 0.00088 | J | | <0.023 | U | | 0.0036 | J | | <0.0069 | U | | 0.0017 | J | |
| | 38.5 ft | VMP-9-38.5-020911 | 2/9/2011 | <0.91 | U | | <1 | U | | <1.6 | U | | <1.5 | U | | <0.86 | U | | <8.9 | U | | 1.9 | | | <3.4 | U | | | | | 0.22 | J | | <0.86 | U | |
| | | VMP-9-38.5-040811 | 4/8/2011 | <1.2 | U | | <1.4 | U | | <2.1 | U | | <1.9 | U | | <1.1 | U | | <12 | U | | <0.98 | U | | <4.6 | U | | 230 | | | 0.2 | J | | <1.1 | U | |
| | | VMP-9-38.5-012612 | 1/26/2012 | <0.18 | U | | <0.21 | U | | <0.32 | U | | <0.29 | U | | <0.17 | U | | <1.8 | U | | 3.2 | | J | <0.69 | U | | 91 | | J | 0.045 | J | J | <0.17 | U | |
| | | VMP-9-38.5-041112 | 4/11/2012 | 0.0015 | J | | <0.004 | U | | <0.0062 | U | | <0.0056 | U | | 0.0024 | J | | <0.034 | U | | 0.013 | | | <0.013 | U | | 0.97 | | | <0.004 | U | | <0.0033 | U | |
| | | VMP-9-38.5-071312 | 7/13/2012 | 0.0046 | J | | 0.0036 | J | | <0.0081 | U | | <0.0074 | U | | 0.0032 | J | | <0.045 | U | | 0.0018 | J | | 0.0051 | J | | 0.0084 | J | | 0.052 | | | 0.19 | | |
| | | VMP-9-38.5-101012 | 10/10/2012 | <0.017 | U | | <0.019 | U | | <0.03 | U | | <0.028 | U | | <0.016 | U | | <0.17 | U | | 0.0052 | J | | <0.064 | UJ | UJ | 2.6 | | | <0.019 | U | | <0.016 | U | |
| | | VMP-9-38.5-013013 | 1/30/2013 | <0.0061 | U | | <0.0069 | U | | <0.011 | U | | <0.0098 | U | | <0.0058 | U | | <0.06 | U | | 0.0014 | J | | <0.023 | U | | 0.004 | J | | <0.0069 | U | | <0.0058 | U | |
| VMP-18 | 8.5 ft | VMP-18-8.5 | 6/18/2010 | <0.006 | U | | <0.007 | U | | <0.011 | U | | <0.01 | U | | 0.0013 | J | | <0.062 | U | | 0.0021 | J | | <0.024 | U | | | | | <0.007 | U | | <0.005 | U | |
| | | VMP-18-8.5-090710 | 9/7/2010 | <0.0056 | J | U | <0.0063 | U | | 0.002 | J | | <0.009 | U | | 0.0015 | J | | <0.055 | J | U | 0.0016 | J | | <0.021 | U | | | | | <0.0063 | J | U | <0.0053 | U | |
| | | VMP-18-8.5-111910 | 11/19/2010 | <0.0047 | U | | <0.0053 | U | | <0.0083 | U | | <0.0076 | U | | 0.0026 | J | | <0.046 | U | | 0.0031 | J | | <0.018 | U | | | | | <0.0053 | U | | <0.0044 | U | |
| | | VMP-18-8.5-020711 | 2/7/2011 | 0.013 | | | 0.0055 | J | | <0.0091 | U | | <0.0083 | U | | 0.045 | | J | <0.051 | U | | 0.056 | | J | <0.019 | U | | | | | 0.0014 | J | | <0.0049 | U | |
| | | VMP-18-8.5-020711-DUP | 2/7/2011 | 0.004 | J | | 0.0016 | J | | <0.0088 | U | | <0.008 | U | | 0.015 | | J | <0.049 | U | | 0.026 | | J | <0.019 | U | | | | | <0.0056 | U | | <0.0047 | U | |
| | | VMP-18-8.5-040711 | 4/7/2011 | <0.0056 | U | | <0.0063 | J | U | <0.0098 | U | | <0.009 | U | | 0.012 | | | <0.055 | U | | 0.0049 | | | <0.021 | U | | 0.012 | J | | 0.0064 | | | <0.0053 | U | |
| | | VMP-18-8.5-072811 | 7/28/2011 | 0.0023 | J | | <0.0068 | U | | <0.01 | U | | <0.0096 | U | | <0.0056 | U | | <0.059 | U | | 0.0018 | J | | 0.0039 | J | | <0.016 | U | | 0.036 | | | 0.1 | | |
| | | VMP-18-8.5-110711 | 11/7/2011 | <0.0039 | U | | <0.0044 | J | U | <0.0068 | U | | <0.0062 | U | | <0.0037 | U | | <0.038 | U | | <0.0032 | U | | 0.00089 | J | | 0.0026 | J | | 0.0018 | J | | 0.013 | | |
| | | VMP-18-8.5-012312 | 1/23/2012 | 0.00054 | J | | <0.0048 | U | | <0.0074 | U | | <0.0068 | U | | 0.0012 | J | | <0.041 | U | | 0.0012 | J | | 0.00068 | J | | <0.011 | U | | 0.0026 | J | | 0.057 | | |
| | | VMP-18-8.5-041012 | 4/10/2012 | 0.0055 | | | <0.0049 | U | | <0.0077 | U | | <0.007 | U | | 0.0054 | | | <0.043 | U | | 0.0044 | | | 0.0025 | J | | 0.0058 | J | | 0.062 | | | 0.16 | | |
| | | VMP-18-8.5-071212 | 7/12/2012 | 0.0028 | J | | <0.0048 | J | U | <0.0075 | U | | <0.0068 | U | | 0.0028 | J | | <0.042 | U | | 0.0017 | J | | <0.016 | J | U | 0.0079 | J | | 0.025 | | | 0.19 | | |
| | | VMP-18-8.5-100912 | 10/9/2012 | <0.0057 | U | | <0.0065 | U | | <0.01 | U | | <0.0092 | U | | 0.0027 | J | | <0.056 | U | | 0.002 | J | | <0.022 | U | | 0.0056 | J | | <0.0065 | U | | <0.0054 | U | |
| | | VMP-18-8.5-012313 | 1/23/2013 | <0.0063 | U | | <0.0071 | U | | <0.011 | U | | <0.01 | U | | <0.0059 | U | | <0.062 | U | | <0.0051 | U | | <0.024 | U | | <0.017 | U | | <0.0071 | U | | <0.0059 | U | |
| VMP-19 | 5 ft | VMP-19-5 | 6/18/2010 | <0.005 | U | | <0.006 | U | | <0.01 | U | | <0.009 | U | | 0.0012 | J | | <0.058 | U | | 0.0048 | | | <0.022 | U | | | | | <0.006 | U | | <0.005 | U | |
| | | VMP-19-5-090110 | 9/1/2010 | 0.0086 | | J | <0.0063 | U | | <0.0099 | U | U | <0.009 | U | | 0.088 | | | <0.055 | U | UJ | 0.34 | | | 0.0038 | J | J | | | | <0.0063 | U | | <0.0053 | U | |
| | | VMP-19-5-111510 | 11/15/2010 | 0.003 | J | | <0.0068 | U | | <0.01 | U | | <0.0096 | U | | <0.0056 | U | | <0.059 | U | | 0.0033 | J | | <0.023 | U | | | | | <0.0068 | U | | <0.0056 | U | |
| | | VMP-19-5-020411 | 2/4/2011 | 0.00074 | J | | <0.0059 | U | | <0.0093 | U | | <0.0084 | U | | <0.005 | U | | <0.052 | J | U | 0.0093 | | | <0.02 | U | | | | | <0.0059 | U | | <0.005 | U | |
| | | VMP-19-5-040711 | 4/7/2011 | 0.00086 | J | | <0.0066 | U | | <0.01 | U | | <0.0094 | U | | <0.0055 | U | | <0.058 | U | | <0.0048 | U | | <0.022 | U | | 0.025 | | | <0.0066 | U | | <0.0055 | U | |
| | | VMP-19-5-080911 | 8/9/2011 | 0.0051 | J | | <0.0073 | J | U | <0.011 | U | | <0.01 | U | | 0.036 | | | <0.063 | U | | 0.12 | | J | <0.024 | U | | 0.21 | | J | 0.045 | | | 0.16 | | |
| | | VMP-19-5-080911-DUP | 8/9/2011 | 0.0051 | J | | <0.0069 | U | | <0.011 | U | | <0.0098 | U | | 0.032 | | | <0.06 | U | | 0.085 | | J | <0.023 | U | | 0.14 | | J | 0.044 | | | 0.16 | | |
| | | VMP-19-5-110811 | 11/8/2011 | <0.0042 | U | | <0.0048 | U | | <0.0075 | U | | <0.0068 | U | | <0.004 | U | | <0.042 | U | | 0.00093 | J | | 0.00042 | J | | 0.0097 | J | | 0.0012 | J | | 0.0087 | | |
| | | VMP-19-5-012612 | 1/26/2012 | 0.003 | J | | <0.0042 | U | | <0.0066 | U | | <0.006 | U | | 0.0024 | J | | <0.036 | U | | 0.0024 | J | | <0.014 | U | | 0.0027 | J | | 0.0039 | J | | 0.0036 | | |
| | | VMP-19-5-041012 | 4/10/2012 | 0.0031 | J | | <0.0048 | U | | <0.0075 | U | | <0.0068 | U | | 0.0037 | J | | <0.042 | U | | 0.0014 | J | | 0.0027 | J | | 0.0078 | J | | 0.052 | | | 0.14 | | |
| | | VMP-19-5-071112 | 7/11/2012 | 0.0032 | J | | <0.0055 | J | U | <0.0085 | U | | <0.0078 | U | | 0.0014 | J | | <0.048 | U | | 0.00098 | J | | <0.018 | J | U | 0.0059 | J | | 0.042 | | | 0.22 | | |
| | | VMP-19-5-100912 | 10/9/2012 | <0.0064 | U | | <0.0073 | U | | <0.011 | U | | <0.01 | U | | <0.0061 | U | | <0.063 | U | | 0.00097 | J | | <0.024 | U | | <0.017 | U | | <0.0073 | U | | <0.0061 | U | |
| | | VMP-19-5-013113 | 1/31/2013 | 0.042 | | | 0.092 | | | <0.0099 | U | | <0.009 | U | | 0.0096 | | | <0.055 | U | | 0.019 | | | <0.021 | U | | 0.12 | | | 0.063 | | | <0.0053 | U | |

SEE LAST PAGE OF TABLE FOR NOTES

**TABLE 5**
**CUMULATIVE SUMMARY OF SOIL VAPOR ANALYTICAL DETECTIONS AND SCREENING RESULTS: VILLAGE - VOCS**

| Location | Depth | Sample ID | Sample Date | Ethylbenzene | | | 4-Ethyltoluene | | | Freon 113 | | | Freon 114 | | | Heptane | | | Hexachlorobutadiene | | | Hexane | | | 2-Hexanone (Methyl N-Butyl Ketone) | | | Isopentane | | | Isopropylbenzene (Cumene) | | | 4-Methyl-2-pentanone (Methyl Isobutyl Ketone) | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | 1400 | | | | | | | | | | | | | | | | | | | | | | | | | | 600 | | | | | |
| | | | | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals |
| VMP-20 | 5 ft | VMP-20-5-031411 | 3/14/2011 | 0.014 | | | 0.0028 | J | | <0.0093 | U | | <0.0084 | U | | 0.01 | | | <0.052 | U | | 0.016 | | | <0.02 | U | | | | | 0.0032 | J | | <0.005 | U | |
| | | VMP-20-5-041511 | 4/15/2011 | <0.058 | U | | <0.065 | U | | <0.1 | U | | <0.093 | U | | 0.24 | | | <0.57 | U | | 2.4 | | | <0.22 | U | | 22 | | | <0.065 | U | | <0.054 | U | |
| | | VMP-20-5-072511 | 7/25/2011 | 0.0015 | J | | <0.0069 | U | | <0.011 | U | | <0.0098 | U | | 0.00085 | J | | <0.06 | U | | 0.0013 | J | | <0.023 | U | UJ | <0.017 | U | | 0.026 | | | 0.11 | | |
| | | VMP-20-5-110111 | 11/1/2011 | 0.003 | J | | <0.004 | J | U | <0.0062 | U | | <0.0056 | U | | 0.0023 | J | | <0.034 | U | | 0.0047 | | | <0.013 | U | | 0.0064 | J | | <0.004 | J | U | 0.019 | | |
| | | VMP-20-5-012312 | 1/23/2012 | 0.0073 | J | | <0.019 | U | | <0.03 | U | | <0.027 | U | | 0.37 | | | <0.16 | U | | 1.3 | | | <0.063 | U | | 1.7 | | | 0.0021 | J | | 0.022 | | |
| | | VMP-20-5-041012 | 4/10/2012 | 0.0011 | J | | <0.0043 | U | | <0.0067 | U | | <0.0061 | U | | 0.004 | | | <0.037 | U | | 0.0048 | | | <0.014 | U | | 0.0054 | J | | 0.014 | | | 0.076 | | |
| | | VMP-20-5-071112 | 7/11/2012 | <0.005 | U | | <0.0057 | J | U | <0.0089 | U | | <0.0081 | U | | <0.0048 | U | | <0.05 | U | | <0.0041 | U | | <0.019 | J | U | 0.0013 | J | | <0.0057 | U | | <0.0048 | U | |
| | | VMP-20-5-073112 | 7/31/2012 | 0.0027 | J | | 0.00076 | J | | <0.0075 | U | | <0.0068 | U | | 0.0057 | | | <0.042 | U | | 0.0018 | J | | 0.0029 | J | | <0.012 | U | | 0.026 | | | 0.091 | | |
| | | VMP-20-5-100412 | 10/4/2012 | <0.0063 | U | | <0.0071 | U | | <0.011 | U | | <0.01 | U | | <0.0059 | U | | <0.062 | U | | 0.0012 | J | | <0.024 | U | | 0.0032 | J | | <0.0071 | U | | <0.0059 | U | |
| | | VMP-20-5-020713 | 2/7/2013 | 0.002 | J | | 0.017 | | | <0.0095 | U | | <0.0086 | U | | 0.002 | J | | <0.053 | U | | 0.027 | | | <0.02 | U | | 0.53 | | | 0.0021 | J | | <0.005 | U | |
| | 10 ft | VMP-20-10-031411 | 3/14/2011 | 0.0089 | | | 0.0026 | J | | <0.0093 | U | | <0.0084 | U | | 0.0034 | J | | <0.052 | U | | 0.0049 | | | <0.02 | U | | | | | 0.0025 | J | | <0.005 | U | |
| | | VMP-20-10-041511 | 4/15/2011 | <0.052 | U | | <0.059 | U | | <0.093 | U | | <0.084 | U | | 0.14 | | | <0.52 | U | | 0.81 | | | <0.2 | U | | 1.6 | | | <0.059 | U | | <0.05 | U | |
| | | VMP-20-10-072511 | 7/25/2011 | 0.0014 | J | | 0.0023 | J | | <0.0099 | U | | <0.009 | U | | 0.00069 | J | | <0.055 | U | | <0.0045 | U | | <0.021 | U | UJ | <0.015 | U | | 0.025 | | | 0.12 | | |
| | | VMP-20-10-110111 | 11/1/2011 | <0.0037 | U | | <0.0042 | U | | <0.0066 | U | | <0.006 | U | | <0.0035 | U | | <0.036 | U | | <0.003 | U | | <0.014 | U | | <0.01 | U | | <0.0042 | J | U | 0.012 | | |
| | | VMP-20-10-012312 | 1/23/2012 | 0.0024 | J | | 0.001 | J | | <0.0068 | U | | <0.0062 | U | | 0.0091 | | | <0.038 | U | | 0.006 | | | <0.015 | U | | 0.0066 | J | | 0.0019 | J | | 0.015 | | |
| | | VMP-20-10-041012 | 4/10/2012 | 0.0015 | J | | <0.0042 | U | | <0.0066 | U | | <0.006 | U | | 0.0048 | | | <0.036 | U | | 0.004 | | | <0.014 | U | | 0.0056 | J | | 0.022 | | | 0.12 | | |
| | | VMP-20-10-071112 | 7/11/2012 | <0.0042 | U | | <0.0048 | J | U | <0.0075 | U | | <0.0068 | U | | <0.004 | U | | <0.042 | U | | <0.0034 | U | | <0.016 | J | U | 0.0048 | J | | <0.0048 | U | | <0.004 | U | |
| | | VMP-20-10-100412 | 10/4/2012 | <0.0058 | U | | <0.0066 | U | | <0.01 | U | | <0.0094 | U | | 0.0017 | J | | <0.057 | U | | 0.002 | J | | <0.022 | U | | 0.0042 | J | | <0.0066 | U | | 0.0011 | J | |
| | | VMP-20-10-012213 | 1/22/2013 | <0.0054 | U | | <0.0061 | U | | <0.0095 | U | | <0.0086 | U | | <0.0051 | U | | <0.053 | U | | 0.0009 | J | | <0.02 | U | | 0.002 | J | | <0.0061 | U | | <0.005 | U | |
| | 25 ft | VMP-20-25-031411 | 3/14/2011 | <0.0052 | U | | <0.0059 | U | | <0.0092 | U | | <0.0084 | U | | 0.0022 | J | | <0.051 | U | | 0.0017 | J | | <0.02 | U | | | | | <0.0059 | U | | <0.0049 | U | |
| | | VMP-20-25-041511 | 4/15/2011 | <0.06 | U | | <0.068 | U | | <0.1 | U | | <0.096 | U | | 0.12 | | | <0.59 | U | | 0.84 | | | <0.23 | U | | 1 | | | <0.068 | U | | <0.056 | U | |
| | | VMP-20-25-072611 | 7/26/2011 | <0.4 | U | | <0.45 | U | | <0.7 | U | | <0.64 | U | | <0.38 | U | | <3.9 | U | | <0.32 | U | | <1.5 | U | UJ | 0.38 | J | | <0.45 | U | | <0.38 | U | |
| | | VMP-20-25-110511 | 11/5/2011 | 0.0011 | J | | 0.0013 | J | | <0.0064 | U | | <0.0059 | U | | <0.0034 | U | | <0.036 | U | | <0.003 | J | U | 0.00072 | J | | <0.0099 | U | | 0.0027 | J | | 0.016 | | |
| | | VMP-20-25-012312 | 1/23/2012 | 0.0006 | J | | <0.0046 | U | | <0.0072 | U | | <0.0065 | U | | 0.0012 | J | | <0.04 | U | | 0.0018 | J | | <0.015 | U | | <0.011 | U | | 0.0021 | J | | 0.017 | | |
| | | VMP-20-25-041012 | 4/10/2012 | 0.0016 | J | | 0.001 | J | | <0.0067 | U | | <0.0061 | U | | 0.0058 | | | <0.037 | U | | 0.004 | | | <0.014 | U | | 0.0039 | J | | 0.027 | | | 0.12 | | |
| | | VMP-20-25-041012-Dup | 4/10/2012 | 0.0015 | J | | <0.0044 | U | | <0.0068 | U | | <0.0062 | U | | 0.0033 | J | | <0.038 | U | | 0.0038 | | | <0.015 | U | | 0.0073 | J | | 0.028 | | | 0.12 | | |
| | | VMP-20-25-071112 | 7/11/2012 | <0.0044 | U | | <0.0049 | J | U | <0.0077 | U | | <0.007 | U | | 0.0032 | J | | <0.043 | U | | <0.0035 | U | | <0.016 | U | | 0.0055 | J | | <0.0049 | U | | <0.0041 | U | |
| | | VMP-20-25-100412 | 10/4/2012 | <0.0064 | U | | <0.0073 | U | | <0.011 | U | | <0.01 | U | | <0.0061 | U | | <0.063 | U | | 0.0012 | J | | <0.024 | U | | <0.017 | U | | <0.0073 | U | | <0.0061 | U | |
| | | VMP-20-25-012213 | 1/22/2013 | <0.0054 | U | | <0.0061 | U | | <0.0095 | U | | <0.0086 | U | | <0.0051 | U | | <0.053 | U | | <0.0044 | U | | <0.02 | U | | 0.0021 | J | | <0.0061 | U | | <0.005 | U | |
| | 39.5 ft | VMP-20-39.5-100412 | 10/4/2012 | <1.6 | U | | <1.8 | U | | <2.8 | U | | <2.5 | U | | <1.5 | U | | <15 | U | | <1.3 | U | | <5.9 | U | | 1.7 | J | | <1.8 | U | | <1.5 | U | |
| | | VMP-20-39.5-012313 | 1/23/2013 | <0.9 | U | | <1 | U | | <1.6 | U | | <1.4 | U | | <0.85 | U | | <8.8 | U | | 0.068 | J | | <3.4 | U | | 7.1 | | | <1 | U | | <0.84 | U | |
| VMP-21 | 5 ft | VMP-21-5-020911 | 2/9/2011 | <2 | U | | <2.3 | U | | <3.6 | U | | <3.2 | U | | 16 | | | <20 | U | | 150 | | | <7.6 | U | | | | | <2.3 | U | | <1.9 | U | |
| | | VMP-21-5-020911-DUP | 2/9/2011 | <3.4 | U | | <3.9 | U | | <6.1 | U | | <5.6 | U | | 12 | | | <34 | U | | 120 | | | <13 | U | | | | | <3.9 | U | | <3.2 | U | |
| | | VMP-21-5-041311 | 4/13/2011 | 0.0099 | | | 0.0014 | J | | <0.01 | U | | <0.0092 | U | | 0.63 | | | <0.056 | U | | 1.4 | | | <0.022 | U | | 0.74 | | | 0.0014 | J | | <0.0054 | U | |
| | | VMP-21-5-072511 | 7/25/2011 | 0.0017 | J | | 0.0018 | J | | <0.01 | U | | <0.0096 | U | | 0.0025 | J | | <0.059 | U | | 0.0019 | J | | 0.0034 | J | J | <0.016 | U | | 0.04 | | | 0.17 | | |
| | | VMP-21-5-110111 | 11/1/2011 | 0.028 | | | 0.03 | | | <0.0087 | U | | <0.008 | U | | 0.0049 | | | <0.049 | U | | 0.0056 | | | <0.019 | U | | 0.0039 | J | | 0.0064 | | | 0.024 | | |
| | | VMP-21-5-012312 | 1/23/2012 | 0.00056 | J | | 0.00074 | J | | <0.0074 | U | | <0.0068 | U | | 0.0011 | J | | <0.041 | U | | 0.001 | J | | <0.016 | U | | <0.011 | U | | 0.0026 | J | | 0.013 | | |
| | | VMP-21-5-012312-DUP | 1/23/2012 | 0.00066 | J | | 0.00086 | J | | <0.0068 | U | | <0.0062 | U | | 0.00068 | J | | <0.038 | U | | 0.001 | J | | <0.015 | U | | <0.01 | U | | 0.0024 | J | | 0.013 | | |
| | | VMP-21-5-042412 | 4/24/2012 | 0.0027 | J | | <0.009 | U | | <0.014 | U | | <0.013 | U | | <0.0075 | U | | <0.078 | U | | 0.0084 | | | <0.03 | U | | 0.35 | | | 0.013 | | | 0.042 | | |
| | | VMP-21-5-071012 | 7/10/2012 | 0.036 | | | 0.025 | | | <0.0081 | U | | <0.0074 | U | | 0.0027 | J | | <0.045 | U | | 0.0035 | J | | <0.017 | J | U | 0.0065 | J | | 0.0027 | J | | <0.0043 | J | U |
| | | VMP-21-5-100412 | 10/4/2012 | <0.0068 | U | | <0.0076 | J | U | <0.012 | U | | <0.011 | U | | 0.0022 | J | | <0.066 | U | | 0.0012 | J | | <0.025 | U | | <0.018 | U | | 0.021 | | | 0.11 | | |
| | | VMP-21-5-020613 | 2/6/2013 | <0.0061 | U | | <0.0069 | U | | <0.011 | U | | <0.0098 | U | | <0.0058 | U | | <0.06 | U | | <0.005 | U | | <0.023 | U | | <0.017 | U | | <0.0069 | U | | <0.0058 | U | |
| | 10 ft | VMP-21-10-021011 | 2/10/2011 | <1.8 | U | | <2.1 | U | | <3.2 | U | | <2.9 | U | | 14 | | | <18 | U | | 130 | | | <6.9 | U | | | | | <2.1 | U | | <1.7 | U | |
| | | VMP-21-10-041311 | 4/13/2011 | <0.23 | U | | <0.26 | U | | <0.41 | U | | <0.37 | U | | <0.22 | U | | <2.3 | U | | 0.16 | J | | <0.87 | U | | 50 | | | <0.26 | U | | <0.22 | U | |
| | | VMP-21-10-072511 | 7/25/2011 | <0.013 | U | | <0.014 | U | | <0.022 | U | | <0.02 | U | | 0.008 | J | | <0.12 | U | | 0.0041 | J | | <0.048 | U | UJ | 0.087 | | | 0.027 | | | 0.045 | | |
| | | VMP-21-10-110111 | 11/1/2011 | <0.0037 | U | | <0.0042 | U | | <0.0066 | U | | <0.006 | U | | <0.0035 | U | | <0.036 | U | | <0.003 | U | | <0.014 | U | | 0.0055 | J | | <0.0042 | J | U | 0.021 | | |
| | | VMP-21-10-012312 | 1/23/2012 | 0.00084 | J | | 0.00064 | J | | <0.0074 | U | | <0.0068 | U | | 0.0017 | J | | <0.041 | U | | 0.0015 | J | | <0.016 | U | | <0.011 | U | | 0.0021 | J | | 0.016 | | |
| | | VMP-21-10-040912 | 4/9/2012 | 0.0041 | | | 0.0011 | J | | <0.0067 | U | | <0.0061 | U | | 0.022 | | | <0.037 | U | | 0.028 | | | <0.014 | U | | 1.2 | | | 0.0093 | | | 0.024 | | |
| | | VMP-21-10-071012 | 7/10/2012 | <0.0044 | U | | <0.0049 | U | | <0.0077 | U | | <0.007 | U | | <0.0041 | U | | <0.043 | U | | <0.0035 | U | | <0.016 | U | | 0.0043 | J | | <0.0049 | U | | <0.0041 | U | |
| | | VMP-21-10-100412 | 10/4/2012 | 0.0029 | J | | <0.0069 | J | U | <0.011 | U | | <0.0098 | U | | 0.0044 | J | | <0.06 | U | | 0.002 | J | | <0.023 | U | | 0.0075 | J | | 0.025 | | | 0.15 | | |
| | | VMP-21-10-020513 | 2/5/2013 | <0.0058 | U | | <0.0066 | U | | <0.01 | U | | <0.0094 | U | | 0.0019 | J | | <0.057 | U | | 0.0028 | J | | <0.022 | U | | 0.0066 | J | | <0.0066 | U | | <0.0055 | U | |
| | | VMP-21-10-020513-DUP | 2/5/2013 | <0.0055 | U | | <0.0062 | U | | <0.0096 | U | | <0.0088 | U | | 0.0021 | J | | <0.054 | U | | 0.0021 | J | | <0.021 | U | | 0.0027 | J | | <0.0062 | U | | <0.0052 | U | |
| | 25 ft | VMP-21-25-021011 | 2/10/2011 | <5 | U | | <5.7 | U | | <8.9 | U | | <8.1 | U | | 380 | | | <50 | U | | 1200 | | | <19 | U | | | | | <5.7 | U | | <4.8 | U | |
| | | VMP-21-25-041411 | 4/14/2011 | <18 | U | | <20 | U | | <31 | U | | <28 | U | | 310 | | | <170 | U | | 820 | | | <67 | U | | 9200 | | | <20 | U | | <17 | U | |
| | | VMP-21-25-041411-DUP | 4/14/2011 | <18 | U | | <20 | U | | <31 | U | | <28 | U | | 320 | | | <170 | U | | 820 | | | <67 | U | | 9200 | | | <20 | U | | <17 | U | |
| | | VMP-21-25-072611 | 7/26/2011 | <5.7 | U | | <6.5 | U | | <10 | U | | <9.2 | U | | 230 | | | <56 | U | | 680 | | | <22 | U | UJ | | | | <6.5 | U | | <5.4 | U | |
| | | VMP-21-25-110511 | 11/5/2011 | <3.6 | U | | <4.1 | U | | <6.4 | U | | <5.9 | U | | 3.4 | J | | <36 | U | | 5.8 | | | <14 | U | | 770 | | | <4.1 | U | | <3.4 | U | |
| | | VMP-21-25-012412 | 1/24/2012 | <0.05 | U | | <0.057 | U | | <0.089 | U | | <0.081 | U | | <0.048 | U | | <0.49 | U | | <0.041 | U | | <0.19 | U | | 0.35 | | | <0.057 | U | | <0.048 | U | |
| | | VMP-21-25-040912 | 4/9/2012 | 0.003 | J | | <0.0045 | U | | 0.0063 | J | | <0.0064 | U | | 0.02 | | | <0.039 | U | | 0.028 | | | <0.015 | U | | 0.12 | | | 0.01 | | | 0.024 | | |
| | | VMP-21-25-071112 | 7/11/2012 | <0.004 | U | | <0.0045 | J | U | <0.007 | U | | <0.0064 | U | | 0.0019 | J | | <0.039 | U | | <0.0032 | U | | <0.015 | U | | 0.012 | | | <0.0045 | J | U | 0.0035 | J | |
| | | VMP-21-25-100412 | 10/4/2012 | <0.0063 | U | | <0.0071 | U | | <0.011 | U | | <0.01 | U | | 0.0021 | J | | <0.062 | U | | 0.0013 | J | | <0.024 | U | | 0.013 | J | | 0.02 | | | 0.095 | | |
| | | VMP-21-25-020513 | 2/5/2013 | <0.0056 | U | | <0.0063 | U | | <0.0099 | U | | <0.009 | U | | 0.0015 | J | | <0.055 | U | | 0.0033 | J | | <0.021 | U | | 0.0083 | J | | <0.0063 | U | | <0.0053 | U | |
| | | VMP-21-25-020513-DUP | 2/5/2013 | <0.0058 | U | | <0.0066 | U | | <0.01 | U | | <0.0094 | U | | 0.0017 | J | | <0.057 | U | | 0.0028 | J | | <0.022 | U | | 0.011 | J | | <0.0066 | U | | 0.0016 | J | |
| | 33 ft | VMP-21-33-021011 | 2/10/2011 | <5 | U | | <5.7 | U | | <8.9 | U | | <8.1 | U | | 530 | | | <50 | U | | 1400 | | | <19 | U | | | | | <5.7 | U | | <4.8 | U | |
| | | VMP-21-33-041411 | 4/14/2011 | <17 | U | | <19 | U | | <30 | U | | <28 | U | | 330 | | | <170 | U | | 880 | | | <64 | U | | 9500 | | | <19 | U | | <16 | U | |
| | | VMP-21-33-110511 | 11/5/2011 | <0.83 | U | | <0.94 | U | | <1.5 | U | | <1.3 | U | | 0.34 | J | | <8.1 | U | | 0.62 | J | | <3.1 | U | | 93 | | | <0.94 | U | | <0.78 | U | |
| | | VMP-21-33-012412 | 1/24/2012 | <0.12 | U | | <0.13 | U | | <0.21 | U | | <0.19 | U | | <0.11 | U | | <1.2 | U | | 0.62 | | J | <0.45 | U | | 3.9 | | J | <0.13 | U | | <0.11 | U | |
| | | VMP-21-33-042412 | 4/24/2012 | 0.0021 | J | | 0.0014 | J | | <0.0072 | U | | <0.0065 | U | | <0.0038 | U | | <0.04 | U | | 0.0072 | | | <0.015 | U | | 0.29 | | | 0.0091 | | | 0.033 | | |
| | | VMP-21-33-071112 | 7/11/2012 | <0.0042 | U | | <0.0048 | U | | <0.0075 | U | | <0.0068 | U | | <0.004 | U | | <0.042 | U | | <0.0034 | U | | <0.016 | J | U | 0.0091 | J | | <0.0048 | U | | <0.004 | U | |
| | | VMP-21-33-100412 | 10/4/2012 | 0.0028 | J | | <0.0069 | J | U | <0.011 | U | | <0.0098 | U | | 0.0044 | J | | <0.06 | U | | 0.0025 | J | | <0.023 | U | | 0.012 | J | | 0.02 | | | 0.093 | | |
| | | VMP-21-33-020513 | 2/5/2013 | <0.0057 | U | | <0.0065 | U | | <0.01 | U | | <0.0092 | U | | <0.0054 | U | | <0.056 | U | | 0.0012 | J | | <0.022 | U | | 0.0042 | J | | <0.0065 | U | | <0.0054 | U | |

SEE LAST PAGE OF TABLE FOR NOTES

**TABLE 5**
**CUMULATIVE SUMMARY OF SOIL VAPOR ANALYTICAL DETECTIONS AND SCREENING RESULTS: VILLAGE - VOCS**

| Location | Depth | Sample ID | Sample Date | Ethylbenzene | | | 4-Ethyltoluene | | | Freon 113 | | | Freon 114 | | | Heptane | | | Hexachlorobutadiene | | | Hexane | | | 2-Hexanone (Methyl N-Butyl Ketone) | | | Isopentane | | | Isopropylbenzene (Cumene) | | | 4-Methyl-2-pentanone (Methyl Isobutyl Ketone) | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | 1400 | | | | | | | | | | | | | | | | | | | | | | | | | | 600 | | | | | |
| | | | | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals |
| VMP-22 | 5 ft | VMP-22-5-021111 | 2/11/2011 | <0.11 | U | | <0.13 | U | | <0.2 | U | | <0.18 | U | | <0.1 | U | | <1.1 | U | | <0.09 | U | | <0.42 | U | | | | | <0.13 | U | | <0.1 | U | |
| | | VMP-22-5-041811 | 4/18/2011 | <0.055 | U | | <0.062 | U | | <0.096 | U | | <0.088 | U | | <0.052 | U | | <0.54 | U | | <0.044 | U | | <0.21 | U | | 0.13 | J | | <0.062 | U | | <0.052 | U | |
| | | VMP-22-5-072611 | 7/26/2011 | 0.0022 | J | | <0.0073 | U | | <0.011 | U | | <0.01 | U | | 0.017 | | | <0.063 | J | U | 0.059 | | | <0.024 | U | UJ | 0.67 | | | 0.023 | | | 0.12 | | |
| | | VMP-22-5-110111 | 11/1/2011 | 0.00096 | J | | <0.0041 | U | | <0.0064 | U | | <0.0059 | U | | <0.0034 | U | | <0.036 | U | | <0.003 | U | | <0.014 | U | | <0.0099 | U | | <0.0041 | J | U | 0.032 | | |
| | | VMP-22-5-012412 | 1/24/2012 | 0.0079 | | J | 0.00079 | J | J | <0.0068 | U | | <0.0062 | U | | 0.28 | | J | <0.038 | U | | 0.7 | | J | <0.014 | U | | 0.38 | | J | 0.0018 | J | J | 0.014 | | J |
| | | VMP-22-5-040912 | 4/9/2012 | <0.0042 | U | | <0.0048 | U | | 0.0016 | J | | <0.0068 | U | | 0.018 | | | <0.042 | U | | 0.05 | | | <0.016 | U | | 0.038 | | | <0.0048 | U | | 0.0025 | J | |
| | | VMP-22-5-070912 | 7/9/2012 | 0.0052 | | | <0.0053 | U | | <0.0083 | U | | <0.0076 | U | | 0.003 | J | | <0.046 | U | | <0.0038 | U | | <0.018 | U | | 0.0017 | J | | <0.0053 | U | | <0.0044 | U | |
| | | VMP-22-5-100312 | 10/3/2012 | <0.0055 | U | | <0.0062 | U | | <0.0096 | U | | <0.0088 | U | | <0.0052 | U | | <0.054 | U | | 0.0023 | J | | <0.021 | U | | 0.0047 | J | | <0.0062 | U | | <0.0052 | U | |
| | | VMP-22-5-100312-Dup | 10/3/2012 | <0.005 | U | | <0.0056 | U | | <0.0088 | U | | <0.008 | U | | 0.0036 | J | | <0.049 | U | | 0.0062 | | | 0.0018 | J | | 0.01 | J | | <0.0056 | U | | <0.0047 | U | |
| | | VMP-22-5-012413 | 1/24/2013 | <0.0056 | U | | <0.0063 | J | U | <0.0099 | U | | <0.009 | U | | <0.0053 | U | | <0.055 | U | | <0.0045 | U | | <0.021 | U | | <0.015 | U | | <0.0063 | U | | <0.0053 | U | |
| | 10 ft | VMP-22-10-021111 | 2/11/2011 | <0.053 | U | | <0.06 | U | | <0.094 | U | | <0.085 | U | | <0.05 | U | | <0.52 | U | | 0.084 | | | <0.2 | U | | | | | <0.06 | U | | <0.05 | U | |
| | | VMP-22-10-041811 | 4/18/2011 | <0.057 | U | | <0.064 | U | | <0.1 | U | | <0.091 | U | | <0.053 | U | | <0.56 | U | | <0.046 | U | | <0.21 | U | | 0.12 | J | | <0.064 | U | | <0.053 | U | |
| | | VMP-22-10-072611 | 7/26/2011 | 0.0017 | J | | <0.0074 | U | | <0.012 | U | | <0.01 | U | | 0.0051 | J | | <0.065 | U | | <0.0053 | U | UJ | <0.025 | U | UJ | 0.053 | | | 0.027 | | | 0.079 | | |
| | | VMP-22-10-072611-DUP | 7/26/2011 | 0.0017 | J | | 0.0027 | J | | <0.014 | U | | <0.012 | U | | <0.0073 | U | | <0.076 | U | | 0.022 | | J | 0.0057 | J | J | 0.17 | | | 0.025 | | | 0.084 | | |
| | | VMP-22-10-110211 | 11/2/2011 | <0.0037 | U | | <0.0042 | U | | <0.0066 | U | | <0.006 | U | | <0.0035 | U | | <0.036 | U | | <0.003 | U | | <0.014 | U | | <0.01 | U | | <0.0042 | J | U | 0.022 | | |
| | | VMP-22-10-012412 | 1/24/2012 | 0.001 | J | | 0.00057 | J | | <0.0074 | U | | <0.0068 | U | | 0.0028 | J | | <0.041 | U | | 0.0019 | J | | <0.016 | U | | <0.011 | U | | 0.0038 | J | | 0.081 | | |
| | | VMP-22-10-040912 | 4/9/2012 | 0.0023 | J | | <0.0047 | U | | 0.0042 | J | | <0.0067 | U | | 0.01 | | | <0.041 | U | | 0.032 | | | <0.016 | U | | 0.025 | | | <0.0047 | U | | <0.004 | U | |
| | | VMP-22-10-070912 | 7/9/2012 | <0.0047 | U | | <0.0053 | U | | <0.0083 | U | | <0.0076 | U | | <0.0044 | U | | <0.046 | U | | <0.0038 | U | | <0.018 | U | | <0.013 | U | | <0.0053 | U | | <0.0044 | U | |
| | | VMP-22-10-070912-Dup | 7/9/2012 | <0.0046 | U | | <0.0052 | U | | <0.0081 | U | | <0.0074 | U | | 0.0028 | J | | <0.045 | U | | 0.0015 | J | | <0.017 | U | | 0.00098 | J | | <0.0052 | U | | <0.0043 | U | |
| | | VMP-22-10-100312 | 10/3/2012 | <0.0052 | U | | <0.0059 | U | | <0.0093 | U | | <0.0084 | U | | 0.0031 | J | | <0.052 | U | | 0.0047 | | | <0.02 | U | | 0.014 | J | | <0.0059 | U | | <0.005 | U | |
| | | VMP-22-10-012413 | 1/24/2013 | <0.006 | U | | <0.0068 | J | U | <0.01 | U | | <0.0096 | U | | <0.0056 | U | | <0.059 | U | | <0.0049 | U | | <0.023 | U | | <0.016 | U | | <0.0068 | U | | <0.0056 | U | |
| | 18 ft | VMP-22-18-021111 | 2/11/2011 | <0.92 | U | | <1 | U | | <1.6 | U | | <1.5 | U | | <0.87 | U | | <9.1 | U | | 17 | | | <3.5 | U | | | | | <1 | U | | <0.87 | U | |
| | | VMP-22-18-041811 | 4/18/2011 | <3.9 | U | | <4.4 | U | | <6.9 | U | | <6.3 | U | | 3.9 | | | <38 | U | | 31 | | | <15 | U | | 1900 | | | <4.4 | U | | <3.7 | U | |
| | | VMP-22-18-072611 | 7/26/2011 | <2 | U | | <2.3 | U | | <3.5 | U | | <3.2 | U | | <1.9 | U | | <20 | U | | 26 | | | <7.5 | U | UJ | 1300 | | | <2.3 | U | | <1.9 | U | |
| | | VMP-22-18-110511 | 11/5/2011 | <0.004 | U | | 0.001 | J | | <0.007 | U | | <0.0064 | U | | 0.00074 | J | | <0.039 | U | | <0.0032 | J | U | 0.00084 | J | | 0.012 | | | 0.002 | J | | 0.016 | | |
| | | VMP-22-18-012412 | 1/24/2012 | <0.036 | U | | <0.041 | U | | <0.064 | U | | <0.059 | U | | <0.034 | U | | <0.36 | U | | <0.03 | U | | <0.14 | U | | 0.34 | | J | <0.041 | U | | <0.034 | U | |
| | | VMP-22-18-040912 | 4/9/2012 | <0.0044 | U | | <0.0049 | U | | <0.0077 | U | | <0.007 | U | | 0.0061 | | | <0.043 | U | | 0.018 | | | <0.016 | U | | 0.0082 | J | | <0.0049 | U | | 0.002 | J | |
| | | VMP-22-18-070912 | 7/9/2012 | <0.0046 | U | | <0.0052 | U | | <0.0081 | U | | <0.0074 | U | | <0.0043 | U | | <0.045 | U | | <0.0037 | U | | <0.017 | U | | 0.002 | J | | <0.0052 | U | | <0.0043 | U | |
| | | VMP-22-18-100412 | 10/4/2012 | <0.0063 | U | | <0.0071 | U | | <0.011 | U | | <0.01 | U | | <0.0059 | U | | <0.062 | U | | <0.0051 | U | | <0.024 | U | | 0.0053 | J | | <0.0071 | U | | <0.0059 | U | |
| | | VMP-22-18-012413 | 1/24/2013 | <0.006 | U | | <0.0068 | J | U | <0.01 | U | | <0.0096 | U | | <0.0056 | U | | <0.059 | U | | <0.0049 | U | | <0.023 | U | | <0.016 | U | | <0.0068 | U | | <0.0056 | U | |
| | 38 ft | VMP-22-38-041811 | 4/18/2011 | <12 | U | | <14 | U | | <21 | U | | <19 | U | | 55 | | | <120 | U | | 390 | | | <45 | U | | 6100 | | | <14 | U | | <11 | U | |
| | | VMP-22-38-012512 | 1/25/2012 | <0.036 | U | | <0.041 | U | | <0.064 | U | | <0.059 | U | | 0.026 | J | | <0.36 | U | | 0.033 | | | <0.14 | U | | 0.73 | | | 0.0051 | J | | <0.034 | U | |
| | | VMP-22-38-040912 | 4/9/2012 | <0.0042 | U | | <0.0048 | U | | 0.0032 | J | | <0.0068 | U | | 0.0075 | | | <0.042 | U | | 0.03 | | | <0.016 | U | | 0.17 | | | <0.0048 | U | | <0.004 | U | |
| | | VMP-22-38-070912 | 7/9/2012 | <0.0045 | U | | <0.0051 | U | | <0.0079 | U | | <0.0072 | U | | 0.0013 | J | | <0.044 | U | | 0.0011 | J | | <0.017 | U | | 0.007 | J | | <0.0051 | U | | <0.0042 | U | |
| | | VMP-22-38-100412 | 10/4/2012 | <0.0066 | U | | <0.0074 | U | | <0.012 | U | | <0.01 | U | | 0.0018 | J | | <0.065 | U | | 0.0025 | J | | <0.025 | U | | 0.0083 | J | | <0.0074 | U | | <0.0062 | U | |
| | | VMP-22-38-012413 | 1/24/2013 | <0.0058 | U | | <0.0066 | J | U | <0.01 | U | | <0.0094 | U | | <0.0055 | U | | <0.057 | U | | <0.0047 | U | | <0.022 | U | | 0.0022 | J | | <0.0066 | U | | <0.0055 | U | |
| VMP-23 | 5 ft | VMP-23-5-021511 | 2/15/2011 | 0.003 | J | | <0.0065 | U | | <0.01 | U | | <0.0092 | U | | 0.0049 | J | | <0.056 | U | | 0.0087 | | | <0.022 | U | | | | | <0.0065 | U | | <0.0054 | U | |
| | | VMP-23-5-042111 | 4/21/2011 | <0.05 | U | | <0.056 | U | | <0.088 | U | | <0.08 | U | | <0.047 | U | | <0.49 | U | | 0.013 | J | | <0.47 | U | | 0.044 | J | | <0.056 | U | | <0.47 | U | |
| | | VMP-23-5-072711 | 7/27/2011 | 0.0024 | J | | <0.0065 | U | | <0.01 | U | | <0.0092 | U | | 0.0083 | | | <0.056 | U | | 0.011 | | | 0.006 | J | | 0.14 | | | 0.037 | | | 0.25 | | |
| | | VMP-23-5-110211 | 11/2/2011 | <0.004 | U | | <0.0046 | U | | <0.0072 | U | | <0.0065 | U | | <0.0038 | U | | <0.04 | U | | 0.0012 | J | | 0.001 | J | | <0.011 | U | | 0.005 | | | 0.034 | | |
| | | VMP-23-5-012512 | 1/25/2012 | <0.0034 | U | | 0.0016 | J | | <0.006 | U | | <0.0055 | U | | 0.0019 | J | | <0.034 | U | | 0.0024 | J | | <0.013 | U | | 0.0045 | J | | 0.0033 | J | | 0.017 | | |
| | | VMP-23-5-040912 | 4/9/2012 | 0.0051 | | | <0.0047 | U | | <0.0073 | U | | <0.0067 | U | | 0.0033 | J | | <0.041 | U | | 0.011 | | | <0.016 | U | | 0.0021 | J | | 0.012 | | | 0.041 | | |
| | | VMP-23-5-070912 | 7/9/2012 | <0.0037 | U | | 0.0023 | J | | <0.0066 | U | | <0.006 | U | | 0.0023 | J | | <0.036 | U | | 0.0048 | | | <0.014 | U | | 0.023 | | | <0.0042 | U | | <0.0035 | J | U |
| | | VMP-23-5-100312 | 10/3/2012 | <0.0063 | U | | <0.0071 | U | | <0.011 | U | | <0.01 | U | | <0.0059 | U | | <0.062 | U | | 0.0016 | J | | <0.024 | U | | 0.0037 | J | | <0.0071 | U | | <0.0059 | U | |
| | | VMP-23-5-012413 | 1/24/2013 | <0.0054 | U | | <0.0061 | U | | <0.0095 | U | | <0.0086 | U | | <0.0051 | U | | <0.053 | U | | 0.0011 | J | | <0.02 | U | | 0.015 | | | <0.0061 | U | | <0.005 | U | |
| | 10 ft | VMP-23-10-021511 | 2/15/2011 | 0.0058 | J | | 0.0024 | J | | <0.01 | U | | <0.0095 | U | | 0.0088 | | | <0.058 | J | U | 0.013 | | | <0.022 | U | | | | | <0.0067 | U | | <0.0056 | U | |
| | | VMP-23-10-042111 | 4/21/2011 | 0.16 | | | 0.022 | J | | <0.1 | U | | <0.096 | U | | 1.5 | | | <0.59 | U | | 3.4 | | | <0.56 | U | | 3.5 | | | <0.068 | U | | <0.56 | U | |
| | | VMP-23-10-072711 | 7/27/2011 | <0.0055 | U | | <0.0062 | U | | <0.0096 | U | | <0.0088 | U | | <0.0052 | U | | <0.054 | U | | <0.0044 | U | | <0.021 | U | | <0.015 | U | | <0.0062 | U | | <0.0052 | U | |
| | | VMP-23-10-110211 | 11/2/2011 | 0.0013 | J | | <0.0045 | J | U | <0.007 | U | | <0.0064 | U | | <0.0037 | U | | <0.039 | U | | 0.0014 | J | | 0.0016 | J | | <0.011 | U | | 0.0074 | | | 0.064 | | |
| | | VMP-23-10-012512 | 1/25/2012 | 0.0038 | | | <0.0038 | U | | <0.0059 | U | | <0.0054 | U | | 0.2 | | | <0.033 | U | | 0.44 | | | <0.013 | U | | 0.17 | | | 0.0024 | J | | 0.01 | | |
| | | VMP-23-10-040912 | 4/9/2012 | 0.0019 | J | | 0.0012 | J | | <0.0075 | U | | <0.0068 | U | | <0.004 | U | | <0.042 | U | | 0.0056 | | | <0.016 | U | | 0.0023 | J | J | 0.015 | | | 0.024 | | |
| | | VMP-23-10-040912-Dup | 4/9/2012 | 0.002 | J | | 0.001 | J | | 0.0042 | J | | <0.0068 | U | | 0.0019 | J | | <0.042 | U | | 0.0079 | | | <0.016 | U | | 0.045 | | J | 0.015 | | | 0.024 | | |
| | | VMP-23-10-070912 | 7/9/2012 | <0.0034 | U | | <0.0038 | J | U | <0.0059 | U | | <0.0054 | U | | <0.0032 | U | | <0.033 | U | | <0.0027 | U | | <0.013 | U | | 0.0043 | J | | <0.0038 | J | U | <0.0032 | U | |
| | | VMP-23-10-100312 | 10/3/2012 | <0.0068 | U | | <0.0076 | U | | <0.012 | U | | <0.011 | U | | 0.0018 | J | | <0.066 | U | | 0.0032 | J | | <0.025 | U | | 0.0082 | J | | <0.0076 | U | | <0.0064 | U | |
| | | VMP-23-10-012413 | 1/24/2013 | <0.0054 | U | | <0.0061 | U | | <0.0095 | U | | <0.0086 | U | | <0.0051 | U | | <0.053 | U | | 0.001 | J | | <0.02 | U | | 0.002 | J | | <0.0061 | U | | <0.005 | U | |
| | 25 ft | VMP-23-25-021511 | 2/15/2011 | <0.0055 | U | | <0.0062 | U | | <0.0096 | U | | <0.0088 | U | | 0.0021 | J | | <0.054 | U | | 0.0035 | J | | <0.021 | U | | | | | <0.0062 | U | | <0.0052 | U | |
| | | VMP-23-25-042111 | 4/21/2011 | <0.056 | U | | <0.063 | U | | <0.099 | U | | <0.09 | U | | 0.68 | | | <0.55 | U | | 4.2 | | | <0.53 | U | | 15 | | | <0.063 | U | | <0.53 | U | |
| | | VMP-23-25-072711 | 7/27/2011 | 0.0027 | J | | 0.003 | J | | <0.011 | U | | <0.01 | U | | 0.0034 | J | | 0.0054 | J | | 0.0031 | J | | <0.024 | U | | <0.017 | U | | 0.024 | | | 0.12 | | |
| | | VMP-23-25-110511 | 11/5/2011 | 0.00075 | J | | 0.00094 | J | | <0.007 | U | | <0.0064 | U | | 0.0015 | J | | <0.039 | U | | <0.0032 | J | U | 0.0008 | J | | 0.0052 | J | | 0.0024 | J | | 0.018 | | |
| | | VMP-23-25-012512 | 1/25/2012 | 0.0032 | J | | <0.004 | U | | <0.0063 | U | | <0.0057 | U | | 0.16 | | | <0.035 | U | | 0.3 | | | <0.013 | U | | 0.06 | | | 0.0017 | J | | 0.048 | | |
| | | VMP-23-25-040912 | 4/9/2012 | 0.0081 | | | 0.0016 | J | | 0.002 | J | | <0.0067 | U | | 0.0044 | | | <0.041 | U | | 0.023 | | | <0.016 | U | | 5.2 | E | J | 0.024 | | | 0.073 | | |
| | | VMP-23-25-071012 | 7/10/2012 | <0.0053 | U | | <0.006 | J | U | <0.0094 | U | | <0.0085 | U | | <0.005 | U | | <0.052 | U | | 0.0019 | J | | <0.02 | U | | 0.0078 | J | | <0.006 | J | U | <0.005 | J | U |
| | | VMP-23-25-100312 | 10/3/2012 | <0.0066 | U | | <0.0074 | U | | <0.012 | U | | <0.01 | U | | <0.0062 | U | | <0.065 | U | | 0.0019 | J | | <0.025 | U | | 0.0074 | J | | <0.0074 | U | | <0.0062 | U | |
| | | VMP-23-25-012413 | 1/24/2013 | <0.0055 | U | | <0.0062 | U | | <0.0096 | U | | <0.0088 | U | | <0.0052 | U | | <0.054 | U | | <0.0044 | U | | <0.021 | U | | 0.0076 | J | | <0.0062 | U | | <0.0052 | U | |
| | 40 ft | VMP-23-40-071012 | 7/10/2012 | <0.0045 | U | | <0.0051 | J | U | <0.0079 | U | | <0.0072 | U | | <0.0042 | U | | <0.044 | U | | 0.0023 | J | | <0.017 | J | U | 0.023 | | | <0.0051 | J | U | <0.0042 | J | U |
| | | VMP-23-40-100312 | 10/3/2012 | <0.0061 | U | | <0.0069 | U | | <0.011 | U | | <0.0098 | U | | 0.0017 | J | | <0.06 | U | | 0.0032 | J | | <0.023 | U | | 0.0055 | J | | <0.0069 | U | | <0.0058 | U | |
| | | VMP-23-40-012413 | 1/24/2013 | <0.0056 | U | | <0.0063 | U | | <0.0099 | U | | <0.009 | U | | <0.0053 | U | | <0.055 | U | | 0.0012 | J | | <0.021 | U | | 0.01 | J | | <0.0063 | U | | <0.0053 | U | |

SEE LAST PAGE OF TABLE FOR NOTES

**TABLE 5**
**CUMULATIVE SUMMARY OF SOIL VAPOR ANALYTICAL DETECTIONS AND SCREENING RESULTS: VILLAGE - VOCS**

| Location | Depth | Sample ID | Sample Date | Ethylbenzene | | | 4-Ethyltoluene | | | Freon 113 | | | Freon 114 | | | Heptane | | | Hexachlorobutadiene | | | Hexane | | | 2-Hexanone (Methyl N-Butyl Ketone) | | | Isopentane | | | Isopropylbenzene (Cumene) | | | 4-Methyl-2-pentanone (Methyl Isobutyl Ketone) | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | 1400 | | | | | | | | | | | | | | | | | | | | | | | | | | 600 | | | | | |
| | | | | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals |
| VMP-24 | 5 ft | VMP-24-5-021611 | 2/16/2011 | <0.0061 | U | | <0.0069 | U | | <0.011 | U | | <0.0098 | U | | 0.004 | J | | <0.06 | U | | 0.0099 | | | <0.023 | U | | | | | <0.0069 | J | U | <0.0058 | U | |
| | | VMP-24-5-040811 | 4/8/2011 | <0.065 | U | | <0.074 | U | | <0.12 | U | | <0.1 | U | | 0.18 | | | <0.64 | U | | 0.94 | | | <0.25 | U | | 11 | | | <0.074 | U | | <0.062 | U | |
| | | VMP-24-5-072811 | 7/28/2011 | 0.0035 | J | | 0.0043 | J | | <0.011 | U | | <0.0098 | U | | 0.0054 | J | | <0.06 | U | | 0.011 | | | 0.0051 | J | | 0.063 | | | 0.029 | | | 0.071 | | |
| | | VMP-24-5-110211 | 11/2/2011 | 0.0013 | J | | <0.0046 | J | U | <0.0072 | U | | <0.0065 | U | | 0.0017 | J | | <0.04 | U | | 0.0038 | | | 0.00092 | J | | 0.0077 | J | | 0.0058 | | | 0.024 | | J |
| | | VMP-24-5-110211-DUP | 11/2/2011 | 0.0015 | J | | 0.0068 | | | <0.01 | U | | <0.0091 | U | | <0.0053 | U | | <0.055 | U | | 0.0069 | | | <0.021 | U | | 0.015 | J | | 0.0061 | J | | 0.012 | | J |
| | | VMP-24-5-012512 | 1/25/2012 | 0.0023 | J | | <0.004 | U | | <0.0062 | U | | <0.0056 | U | | <0.0033 | U | | <0.034 | U | | <0.0028 | U | | <0.013 | U | | 0.0037 | J | | 0.0044 | | | 0.018 | | |
| | | VMP-24-5-040912 | 4/9/2012 | 0.0059 | | | 0.0037 | J | | <0.0073 | U | | <0.0067 | U | | 0.0027 | J | | <0.041 | U | | 0.017 | | | <0.016 | U | | 0.012 | | | 0.032 | | | 0.054 | | |
| | | VMP-24-5-071212 | 7/12/2012 | 0.0022 | J | | 0.0042 | J | | <0.007 | U | | <0.0064 | U | | 0.0022 | J | | <0.039 | U | | 0.0028 | J | | <0.015 | U | | 0.0092 | J | | 0.019 | | | 0.074 | | |
| | | VMP-24-5-101912 | 10/19/2012 | 0.0012 | J | | <0.007 | U | | <0.011 | U | | <0.0099 | U | | <0.0058 | U | | <0.06 | U | | 0.0033 | J | | <0.023 | U | | 0.015 | J | | <0.007 | U | | <0.0058 | U | |
| | | VMP-24-5-012313 | 1/23/2013 | <0.0055 | U | | <0.0062 | U | | <0.0096 | U | | <0.0088 | U | | <0.0052 | U | | <0.054 | U | | <0.0044 | U | | <0.021 | U | | <0.015 | U | | <0.0062 | U | | <0.0052 | U | |
| | 10 ft | VMP-24-10-021711 | 2/17/2011 | 0.0028 | J | | <0.0066 | U | | <0.01 | U | | <0.0094 | U | | <0.0055 | U | | <0.057 | U | | 0.18 | | | <0.022 | U | | | | | <0.0066 | J | U | <0.0055 | U | |
| | | VMP-24-10-041111 | 4/11/2011 | <0.011 | U | | <0.012 | U | | <0.019 | U | | <0.018 | U | | 0.055 | | | <0.11 | U | | 0.19 | | | <0.041 | U | | 1 | | | <0.012 | U | | <0.01 | U | |
| | | VMP-24-10-072811 | 7/28/2011 | 0.0026 | J | | 0.0032 | J | | <0.01 | U | | <0.0096 | U | | 0.0039 | J | | <0.059 | U | | 0.0031 | J | | 0.0047 | J | | 0.046 | | | 0.033 | | | 0.1 | | |
| | | VMP-24-10-110211 | 11/2/2011 | <0.0036 | U | | <0.004 | J | U | <0.0063 | U | | <0.0057 | U | | <0.0034 | U | | <0.035 | U | | <0.0029 | U | | 0.0013 | J | | <0.0097 | U | | <0.0044 | | U | 0.028 | | |
| | | VMP-24-10-012512 | 1/25/2012 | 0.0033 | J | | <0.0038 | U | | <0.0059 | U | | <0.0054 | U | | 0.00083 | J | | <0.033 | U | | <0.0027 | U | | <0.013 | U | | 0.0015 | J | | 0.0037 | J | | 0.013 | | |
| | | VMP-24-10-041012 | 4/10/2012 | 0.0012 | J | | <0.0045 | U | | <0.007 | U | | <0.0064 | U | | 0.0023 | J | | <0.039 | U | | 0.002 | J | | <0.015 | U | | 0.071 | | | <0.0045 | U | | <0.0037 | U | |
| | | VMP-24-10-071212 | 7/12/2012 | 0.003 | J | | <0.0052 | J | U | <0.0081 | U | | <0.0074 | U | | <0.0043 | U | | <0.045 | U | | <0.0037 | U | | <0.017 | J | U | 0.0051 | J | | 0.038 | | | 0.16 | | |
| | | VMP-24-10-100912 | 10/9/2012 | <0.0057 | U | | <0.0065 | U | | <0.01 | U | | <0.0092 | U | | <0.0054 | U | | <0.056 | U | | 0.00099 | J | | <0.022 | U | | 0.0071 | J | | <0.0065 | U | | <0.0054 | U | |
| | | VMP-24-10-012313 | 1/23/2013 | <0.006 | U | | <0.0068 | U | | <0.01 | U | | <0.0096 | U | | <0.0056 | U | | <0.059 | U | | <0.0049 | U | | <0.023 | U | | 0.0034 | J | | <0.0068 | U | | <0.0056 | U | |
| | 22 ft | VMP-24-22-021711 | 2/17/2011 | 0.0059 | | | 0.0026 | J | | <0.01 | U | | <0.0094 | U | | 0.053 | | | <0.057 | U | | 0.11 | | | <0.022 | U | | | | | <0.0066 | J | U | <0.0055 | U | |
| | | VMP-24-22-041111 | 4/11/2011 | <0.0055 | U | | <0.0062 | U | | <0.0096 | U | | <0.0088 | U | | <0.0052 | U | | <0.054 | U | | 0.0018 | J | | <0.021 | U | | 0.0062 | J | | <0.0062 | U | | <0.0052 | U | |
| | | VMP-24-22-072811 | 7/28/2011 | 0.0013 | J | | 0.0019 | J | | <0.0096 | U | | <0.0088 | U | | <0.0052 | U | | <0.054 | U | | 0.00091 | J | | <0.021 | U | | <0.015 | U | | 0.019 | | | 0.042 | | |
| | | VMP-24-22-072811-Dup | 7/28/2011 | 0.0015 | J | | <0.0071 | U | | <0.011 | U | | <0.01 | U | | <0.0059 | U | | <0.062 | U | | 0.00098 | J | | <0.024 | U | | <0.017 | U | | 0.018 | | | 0.041 | | |
| | | VMP-24-22-110611 | 11/6/2011 | 0.001 | J | | 0.00058 | J | | <0.0067 | U | | <0.0061 | U | | 0.0021 | J | | <0.037 | U | | 0.0027 | J | | <0.014 | U | | 0.08 | | | 0.0028 | J | | 0.021 | | |
| | | VMP-24-22-012512 | 1/25/2012 | <0.0036 | U | | <0.004 | U | | <0.0063 | U | | <0.0057 | U | | <0.0034 | U | | <0.035 | U | | <0.0029 | U | | <0.013 | U | | <0.0097 | U | | 0.005 | | | 0.018 | | |
| | | VMP-24-22-041012 | 4/10/2012 | 0.0018 | J | | <0.0044 | U | | <0.0068 | U | | <0.0062 | U | | 0.0074 | | | 0.012 | J | | 0.015 | | | <0.015 | U | | 0.11 | | | <0.0044 | U | | 0.0018 | J | |
| | | VMP-24-22-071212 | 7/12/2012 | 0.0019 | J | | <0.0053 | J | U | <0.0083 | U | | <0.0076 | U | | 0.0016 | J | | <0.046 | U | | 0.0019 | J | | <0.018 | J | U | 0.0052 | J | | 0.023 | | | 0.1 | | |
| | | VMP-24-22-100912 | 10/9/2012 | <0.0058 | U | | <0.0066 | U | | <0.01 | U | | <0.0094 | U | | <0.0055 | U | | <0.057 | U | | 0.0011 | J | | <0.022 | U | | <0.016 | U | | <0.0066 | U | | <0.0055 | U | |
| | | VMP-24-22-012313 | 1/23/2013 | <0.0061 | U | | <0.0069 | U | | <0.011 | U | | <0.0098 | U | | <0.0058 | U | | <0.06 | U | | <0.005 | U | | <0.023 | U | | 0.011 | J | | <0.0069 | U | | <0.0058 | U | |
| | 34 ft | VMP-24-34-021711 | 2/17/2011 | <0.0058 | U | | <0.0066 | U | | <0.01 | U | | <0.0094 | U | | 0.0022 | J | | <0.057 | U | | 0.0018 | J | | <0.022 | U | | | | | <0.0066 | U | | <0.0055 | U | |
| | | VMP-24-34-041111 | 4/11/2011 | <0.0052 | U | | <0.0059 | U | | <0.0093 | U | | <0.0084 | U | | <0.005 | U | | <0.052 | U | | 0.0016 | J | | <0.02 | U | | 0.0049 | J | | <0.0059 | U | | <0.005 | U | |
| | | VMP-24-34-072811 | 7/28/2011 | 0.0017 | J | | 0.002 | J | | <0.0082 | U | | <0.0074 | U | | 0.0016 | J | | <0.045 | U | | 0.0019 | J | | <0.017 | U | | <0.012 | U | | 0.016 | | | 0.053 | | |
| | | VMP-24-34-110611 | 11/6/2011 | 0.0011 | J | | 0.0013 | J | | <0.0052 | U | | <0.0048 | U | | 0.0017 | J | | <0.029 | U | | <0.0024 | | U | 0.00049 | J | | 0.012 | | | 0.0016 | J | | 0.012 | | |
| | | VMP-24-34-012512 | 1/25/2012 | <0.0036 | U | | <0.0041 | U | | <0.0064 | U | | <0.0059 | U | | <0.0034 | U | | <0.036 | U | | <0.003 | U | | <0.014 | U | | 0.0029 | J | | 0.0063 | | | 0.035 | | |
| | | VMP-24-34-041012 | 4/10/2012 | 0.004 | J | | <0.0046 | U | | <0.0072 | U | | <0.0065 | U | | 0.012 | | | <0.04 | U | | 0.0065 | | | <0.015 | U | | 0.013 | | | 0.016 | | | 0.045 | | |
| | | VMP-24-34-071212 | 7/12/2012 | 0.0027 | J | | <0.0044 | J | U | <0.0068 | U | | <0.0062 | U | | 0.0023 | J | | <0.038 | U | | 0.0028 | J | | 0.0022 | J | | 0.007 | J | | 0.024 | | | 0.12 | | |
| | | VMP-24-34-100912 | 10/9/2012 | <0.006 | U | | <0.0068 | U | | <0.01 | U | | <0.0096 | U | | 0.003 | J | | <0.059 | U | | 0.0034 | J | | <0.023 | U | | 0.013 | J | | <0.0068 | U | | <0.0056 | U | |
| | | VMP-24-34-012313 | 1/23/2013 | <0.0063 | U | | <0.0071 | U | | <0.011 | U | | <0.01 | U | | <0.0059 | U | | <0.062 | U | | <0.0051 | U | | <0.024 | U | | <0.017 | U | | <0.0071 | U | | <0.0059 | U | |
| VMP-31 | 5 ft | VMP-31-5-042512 | 4/25/2012 | 0.0043 | | | 0.0022 | J | | <0.0073 | U | | <0.0067 | U | | 0.0026 | J | | <0.041 | U | | 0.0015 | J | | <0.016 | U | | 0.0029 | J | | 0.021 | | | 0.079 | | |
| | | VMP-31-5-072012 | 7/20/2012 | <0.0041 | U | | <0.0047 | U | | <0.0073 | U | | <0.0067 | U | | <0.0039 | U | | <0.041 | U | | <0.0034 | U | | 0.0016 | J | | <0.011 | U | | 0.0022 | J | | 0.017 | | |
| | | VMP-31-5-102612 | 10/26/2012 | <0.006 | U | | 0.00084 | J | | <0.01 | U | | <0.0096 | U | | 0.011 | | | <0.059 | U | | 0.021 | | | <0.023 | U | | 0.2 | | | 0.026 | | | 0.09 | | |
| | | VMP-31-5-021113 | 2/11/2013 | 0.012 | | | 0.018 | | | <0.0099 | U | | <0.009 | U | | 0.0071 | | | <0.055 | U | | 0.011 | | | <0.021 | U | | 0.017 | | | 0.0022 | J | | 0.0029 | J | |
| | 10 ft | VMP-31-10-042512 | 4/25/2012 | 0.0035 | J | | 0.002 | J | | <0.0098 | U | | <0.0089 | U | | 0.01 | | | <0.054 | U | | 0.0021 | | | <0.021 | U | | 0.13 | | | 0.019 | | | 0.072 | | |
| | | VMP-31-10-072612 | 7/26/2012 | 0.004 | J | | 0.0022 | J | | <0.0075 | U | | <0.0068 | U | | 0.0037 | J | | <0.042 | U | | 0.0013 | J | | <0.016 | U | | <0.012 | U | | 0.04 | | | 0.04 | | |
| | | VMP-31-10-102612 | 10/26/2012 | <0.0064 | U | | <0.0073 | U | | <0.011 | U | | <0.01 | U | | <0.0061 | U | | <0.063 | U | | 0.0019 | J | | <0.024 | U | | 0.057 | | | 0.02 | | | 0.11 | | |
| | | VMP-31-10-021313 | 2/13/2013 | 0.013 | | | 0.012 | | | <0.011 | U | | <0.0098 | U | | 0.0075 | | | <0.06 | U | | 0.016 | | | <0.023 | U | | 0.12 | | | 0.0026 | J | | 0.0033 | J | |
| | 20 ft | VMP-31-20-101912 | 10/19/2012 | <6 | U | | <6.8 | U | | <10 | U | | <9.6 | U | | <5.6 | U | | <59 | U | | 2 | J | | <23 | U | | 25 | | | <6.8 | U | | <5.6 | U | |
| | | VMP-31-20-021113 | 2/11/2013 | <0.086 | U | | <0.097 | U | | <0.15 | U | | <0.14 | U | | <0.081 | U | | <0.84 | U | | <0.069 | U | | <0.32 | U | | 13 | | | <0.097 | U | | <0.32 | U | |
| | 30 ft | VMP-31-30-042512 | 4/25/2012 | 3 | | | 0.54 | J | | <3.8 | U | | <3.4 | U | | 16 | | | <21 | U | | 180 | | | <8 | U | | 1100 | | | 0.66 | J | | <2 | U | |
| | | VMP-31-30-042512-Dup | 4/25/2012 | 3.2 | | | 0.6 | J | | <3.8 | U | | <3.4 | U | | 19 | | | <21 | U | | 210 | | | <8 | U | | 1200 | | | 0.75 | J | | <2 | U | |
| | | VMP-31-30-072012 | 7/20/2012 | <0.41 | U | | <0.47 | U | | <0.73 | U | | <0.67 | U | | <0.39 | U | | <4.1 | U | | 2.6 | | | <1.6 | U | | 46 | | | <0.47 | U | | <0.39 | U | |
| | | VMP-31-30-101912 | 10/19/2012 | <0.37 | U | | <0.42 | U | | <0.66 | U | | <0.6 | U | | <0.35 | U | | <3.7 | U | | 0.28 | J | | <1.4 | U | | 34 | | | <0.42 | U | | <0.35 | U | |
| | | VMP-31-30-021113 | 2/11/2013 | <6.1 | U | | <6.9 | U | | <11 | U | | <9.8 | U | | <5.8 | U | | <60 | U | | <5 | U | | <23 | U | | 1400 | | | <6.9 | U | | <23 | U | |
| VMP-32 | 5 ft | VMP-32-5-042512 | 4/25/2012 | 0.0034 | J | | 0.0023 | J | | <0.0072 | U | | <0.0065 | U | | 0.0034 | J | | <0.04 | U | | 0.0029 | J | | <0.015 | U | | <0.011 | U | | 0.026 | | | 0.11 | | |
| | | VMP-32-5-072012 | 7/20/2012 | <0.0036 | U | | 0.0011 | J | | <0.0064 | U | | <0.0059 | U | | 0.0031 | J | | <0.036 | U | | 0.0021 | J | | 0.00074 | J | | <0.0099 | U | | 0.00057 | J | | 0.0029 | J | |
| | | VMP-32-5-101812 | 10/18/2012 | <0.0069 | U | | <0.0078 | U | | <0.012 | U | | <0.011 | U | | 0.022 | | | <0.068 | U | | 0.01 | | | <0.026 | U | | 0.014 | J | | 0.0015 | J | | <0.0065 | U | |
| | | VMP-32-5-020513 | 2/5/2013 | <0.0055 | U | | <0.0062 | J | U | <0.0096 | U | | <0.0088 | U | | <0.0052 | U | | <0.054 | U | | <0.0044 | U | | <0.021 | U | | 0.0023 | J | | <0.0062 | U | | <0.0052 | U | |
| | 10 ft | VMP-32-10-041612 | 4/16/2012 | 0.0017 | J | | 0.00093 | J | | <0.0066 | U | | <0.006 | U | | 0.0015 | J | | <0.036 | U | | 0.24 | | | <0.014 | U | | 0.025 | | | 0.018 | | | 0.056 | | |
| | | VMP-32-10-072012 | 7/20/2012 | <0.0042 | U | | <0.0048 | U | | <0.0075 | U | | <0.0068 | U | | 0.0023 | J | | <0.042 | U | | 0.0017 | J | | 0.0012 | J | | <0.012 | U | | <0.0048 | U | | 0.0014 | J | |
| | | VMP-32-10-101812 | 10/18/2012 | <0.0064 | U | | <0.0073 | U | | <0.011 | U | | <0.01 | U | | 0.012 | | | <0.063 | U | | 0.0056 | | | <0.024 | U | | 0.02 | | | <0.0073 | U | | <0.0061 | U | |
| | | VMP-32-10-020513 | 2/5/2013 | <0.0055 | U | | <0.0062 | J | U | <0.0096 | U | | <0.0088 | U | | <0.0052 | U | | <0.054 | U | | <0.0044 | U | | <0.021 | U | | <0.015 | U | | <0.0062 | U | | <0.0052 | U | |
| | 20 ft | VMP-32-20-041612 | 4/16/2012 | 0.04 | J | | <0.096 | U | | <0.15 | U | | <0.14 | U | | 0.068 | J | | <0.84 | U | | 0.07 | | | <0.32 | U | | 0.24 | | | 0.016 | J | | 0.079 | J | |
| | | VMP-32-20-072012 | 7/20/2012 | <0.0041 | U | | 0.00052 | J | | <0.0073 | U | | <0.0067 | U | | <0.0039 | U | | <0.041 | U | | <0.0034 | U | | 0.0011 | J | | <0.011 | U | | <0.0047 | U | | 0.0014 | J | |
| | | VMP-32-20-101812 | 10/18/2012 | <0.006 | U | | <0.0068 | U | | <0.01 | U | | <0.0096 | U | | 0.0094 | | | <0.059 | U | | 0.0039 | J | | <0.023 | U | | 0.0033 | J | | 0.0043 | J | | 0.012 | | |
| | | VMP-32-20-020513 | 2/5/2013 | <0.0061 | U | | <0.0069 | U | | <0.011 | U | | <0.0098 | U | | <0.0058 | U | | <0.06 | U | | <0.005 | U | | <0.023 | U | | <0.017 | U | | <0.0069 | U | | 0.0033 | J | |
| | 30 ft | VMP-32-30-041612 | 4/16/2012 | 8.6 | | | 1.3 | J | | <3.6 | U | | <3.3 | U | | 400 | | | <20 | U | | 1100 | | | <7.7 | U | | 3700 | | | 0.49 | J | | <1.9 | U | |
| | | VMP-32-30-072012 | 7/20/2012 | <4.2 | U | | <4.7 | U | | <7.4 | U | | <6.7 | U | | 230 | | | <41 | U | | 470 | | | <16 | U | | 1500 | | | <4.7 | U | | <4 | U | |
| | | VMP-32-30-101812 | 10/18/2012 | <0.24 | U | | <0.27 | U | | <0.42 | U | | <0.38 | U | | <0.22 | U | | <2.3 | U | | 0.16 | J | | <0.9 | U | | 1.7 | | | <0.27 | U | | <0.22 | U | |
| | | VMP-32-30-020513 | 2/5/2013 | <0.24 | U | | <0.28 | U | | <0.43 | U | | <0.39 | U | | <0.23 | U | | <2.4 | U | | <0.2 | U | | <0.92 | U | | 0.18 | J | | <0.28 | U | | <0.92 | U | |

SEE LAST PAGE OF TABLE FOR NOTES

**TABLE 5**
**CUMULATIVE SUMMARY OF SOIL VAPOR ANALYTICAL DETECTIONS AND SCREENING RESULTS: VILLAGE - VOCS**

| Location | Depth | Sample ID | Sample Date | Ethylbenzene 1400 | | | 4-Ethyltoluene | | | Freon 113 | | | Freon 114 | | | Heptane | | | Hexachlorobutadiene | | | Hexane | | | 2-Hexanone (Methyl N-Butyl Ketone) | | | Isopentane | | | Isopropylbenzene (Cumene) 600 | | | 4-Methyl-2-pentanone (Methyl Isobutyl Ketone) | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals |
| VMP-42 | 10 ft | VMP-42-10-041812 | 4/18/2012 | 0.0046 | | | 0.0011 | J | | <0.0066 | U | | <0.006 | U | | 0.026 | | | <0.036 | U | | 0.051 | | J | <0.014 | U | | 0.036 | | | 0.026 | | | 0.2 | | |
| | | VMP-42-10-041812-Dup | 4/18/2012 | 0.0046 | | | <0.0043 | U | | <0.0067 | U | | <0.0061 | U | | 0.02 | | | <0.037 | U | | 0.02 | | J | <0.014 | U | | 0.024 | | | 0.025 | | | 0.2 | | |
| | | VMP-42-20-041812 | 4/18/2012 | 0.77 | J | | <2.2 | U | | <3.4 | U | | <3.1 | U | | <1.8 | U | | <19 | U | | 9.3 | | | <7.3 | U | | 340 | | | <2.2 | U | | <1.8 | U | |
| | | VMP-42-10-071912 | 7/19/2012 | 0.0043 | | | 0.0027 | J | | <0.0073 | U | | <0.0067 | U | | 0.0076 | | | <0.041 | U | | 0.0065 | | | 0.0027 | J | | 0.016 | | | 0.026 | | | 0.14 | | |
| | | VMP-42-10-101212 | 10/12/2012 | <0.0067 | U | | <0.0076 | U | | <0.012 | U | | <0.011 | U | | <0.0063 | U | | <0.066 | U | | <0.0054 | U | | <0.025 | U | | <0.018 | U | | 0.0044 | J | | 0.06 | | |
| | | VMP-42-10-013113 | 1/31/2013 | <0.0061 | U | | <0.0069 | J | U | <0.011 | U | | <0.0098 | U | | <0.0058 | U | | <0.06 | U | | 0.00093 | J | | <0.023 | U | | <0.017 | U | | <0.0069 | U | | <0.0058 | U | |
| | 20 ft | VMP-42-20-071912 | 7/19/2012 | 0.0087 | | | 0.0042 | J | | <0.0072 | U | | <0.0065 | U | | 0.039 | | | <0.04 | U | | 0.03 | | | <0.015 | U | | 0.022 | | | 0.022 | | | 0.11 | | |
| | | VMP-42-20-101212 | 10/12/2012 | <0.0059 | U | | <0.0067 | U | | <0.01 | U | | <0.0095 | U | | <0.0056 | U | | <0.058 | U | | <0.0048 | U | | <0.022 | U | | 0.0035 | J | | <0.0067 | U | | 0.0054 | J | |
| | | VMP-42-20-101212-Dup | 10/12/2012 | <0.006 | U | | <0.0069 | U | | <0.01 | U | | <0.0096 | U | | <0.0056 | U | | <0.059 | U | | 0.0018 | J | | <0.023 | U | | 0.03 | | | <0.0068 | U | | 0.0054 | J | |
| | | VMP-42-20-013113 | 1/31/2013 | <0.0056 | U | | <0.0063 | J | U | <0.0099 | U | | <0.009 | U | | 0.0039 | J | | <0.055 | U | | 0.0045 | | | <0.021 | U | | 0.0051 | J | | <0.0063 | U | | <0.0053 | U | |
| | 30 ft | VMP-42-30-041912 | 4/19/2012 | <4 | U | | <4.6 | U | | <7.2 | U | | <6.5 | U | | <3.8 | U | | <40 | U | | 51 | | | <15 | U | | 1700 | | | <4.6 | U | | <3.8 | U | |
| | | VMP-42-30-071912 | 7/19/2012 | 0.0073 | | J | 0.0099 | | J | <0.0067 | U | | <0.0061 | U | | <0.0036 | U | | <0.037 | U | | 0.077 | | J | <0.014 | U | | 55 | | | 0.036 | | J | 0.2 | | J |
| | | VMP-42-30-101212 | 10/12/2012 | <0.0063 | U | | <0.0071 | U | | <0.011 | U | | <0.01 | U | | 0.0036 | J | | <0.062 | U | | 0.06 | | | <0.024 | U | | 0.42 | | | <0.0071 | U | | 0.0094 | | |
| | | VMP-42-30-101212-Dup | 10/12/2012 | <0.0063 | U | | <0.0071 | U | | <0.011 | U | | <0.01 | U | | 0.0031 | J | | <0.062 | U | | 0.057 | | | <0.024 | U | | 0.4 | | | <0.0071 | U | | 0.01 | | |
| | | VMP-42-30-013113 | 1/31/2013 | <0.006 | U | | <0.0068 | U | | <0.01 | U | | <0.0096 | U | | 0.0013 | J | | <0.059 | U | | 0.0018 | J | | <0.023 | U | | 0.1 | | | <0.0068 | U | | <0.0056 | U | |
| VMP-43 | 10 ft | VMP-43-10-041612 | 4/16/2012 | 0.0036 | J | | 0.0022 | J | | <0.0075 | U | | <0.0068 | U | | 0.019 | | | <0.042 | U | | 0.03 | | | 0.0035 | J | | 0.02 | | | 0.029 | | | 0.22 | | |
| | | VMP-43-10-071912 | 7/19/2012 | 0.009 | | | 0.0042 | J | | <0.014 | U | | <0.013 | U | | 0.024 | | | <0.08 | U | | 0.021 | | | 0.0039 | J | | 0.014 | J | | 0.03 | | | 0.14 | | |
| | | VMP-43-10-101612 | 10/16/2012 | <0.0069 | U | | <0.0078 | U | | <0.012 | U | | <0.011 | U | | <0.0065 | U | | <0.068 | U | | <0.0056 | U | | <0.026 | U | | 0.0017 | J | | 0.0042 | J | | 0.0089 | | |
| | 20 ft | VMP-43-20-041612 | 4/16/2012 | 0.014 | J | | 0.017 | J | | <0.073 | U | | <0.067 | U | | 0.24 | | | <0.41 | U | | 1.9 | | | <0.16 | U | | 21 | | | 0.021 | J | | 0.068 | | |
| | | VMP-43-20-071912 | 7/19/2012 | 0.0065 | J | | <0.017 | U | | <0.026 | U | | <0.024 | U | | 0.0063 | J | | <0.15 | U | | 0.024 | | | <0.056 | U | | 0.69 | | | 0.027 | | | 0.14 | | |
| | | VMP-43-20-101812 | 10/18/2012 | <0.0057 | U | | <0.0065 | U | | <0.01 | U | | <0.0092 | U | | <0.0054 | U | | <0.056 | U | | <0.0046 | U | | <0.022 | U | | 0.034 | | | 0.0038 | J | | 0.0072 | | |
| | | VMP-43-20-012413 | 1/24/2013 | <0.0057 | U | | <0.0065 | U | | <0.01 | U | | <0.0092 | U | | <0.0054 | U | | <0.056 | U | | <0.0046 | U | | <0.022 | U | | 0.004 | J | | <0.0065 | U | | 0.0018 | J | |
| | 30 ft | VMP-43-30-042312 | 4/23/2012 | <0.038 | U | | <0.043 | U | | <0.067 | U | | <0.061 | U | | <0.036 | U | | <0.37 | U | | 0.12 | | | <0.14 | U | | 0.14 | | | 0.02 | J | | 0.12 | | |
| | | VMP-43-30-071912 | 7/19/2012 | 0.0075 | | | 0.0052 | | | <0.0073 | U | | <0.0067 | U | | 0.013 | | | <0.041 | U | | 0.015 | | | 0.0036 | J | | 0.02 | | | 0.016 | | | 0.087 | | |
| | | VMP-43-30-101812 | 10/18/2012 | <0.006 | U | | <0.0068 | U | | <0.01 | U | | <0.0096 | U | | <0.0056 | U | | <0.059 | U | | 0.0046 | J | | <0.023 | U | | 0.032 | | | 0.00086 | J | | 0.002 | J | |
| | | VMP-43-30-012413 | 1/24/2013 | <0.0058 | U | | <0.0066 | U | | <0.01 | U | | <0.0094 | U | | <0.0055 | U | | <0.057 | U | | <0.0047 | U | | <0.022 | U | | 0.0048 | J | | <0.0066 | U | | <0.0055 | U | |
| VMP-44 | 10 ft | VMP-44-10-041912 | 4/19/2012 | <2 | U | | <2.2 | U | | <3.5 | U | | <3.2 | U | | 39 | | | <20 | U | | 86 | | | <7.5 | U | | 610 | | | <2.2 | U | | <1.9 | U | |
| | | VMP-44-10-072012 | 7/20/2012 | 0.1 | J | J | 0.51 | J | J | <1.2 | U | | <1.1 | U | | 73 | | J | <6.5 | U | | 120 | | J | <2.5 | U | | 300 | | J | <0.75 | U | | <0.63 | U | |
| | | VMP-44-10-081012 | 8/10/2012 | 0.24 | J | J | 0.4 | J | J | <0.7 | U | | <0.64 | U | | 61 | | J | <3.9 | U | | 110 | | J | <1.5 | U | | 250 | | J | 0.076 | J | J | <0.37 | U | |
| | | VMP-44-10-101212 | 10/12/2012 | 0.19 | J | | <1.4 | U | | <2.2 | U | | <2 | U | | 7.8 | | | <12 | U | | 10 | | | <4.6 | U | | 11 | | | <1.4 | U | | <1.2 | U | |
| | | VMP-44-10-012513 | 1/25/2013 | <0.5 | U | | <0.56 | U | | <0.88 | U | | <0.8 | U | | <0.47 | U | | <4.9 | U | | 5.1 | | | <1.9 | U | | 8.4 | | | <0.56 | U | | <0.47 | U | |
| | 20 ft | VMP-44-20-041912 | 4/19/2012 | 1.1 | | | 0.33 | J | J | <0.77 | U | | <0.7 | U | | 110 | | | <4.3 | U | | 270 | | | <1.6 | U | | 580 | | | 0.2 | J | | <0.41 | U | |
| | | VMP-44-20-072512 | 7/25/2012 | <0.74 | U | | <0.84 | U | | <1.3 | U | | <1.2 | U | | 100 | | J | <7.3 | U | | 250 | | J | <2.8 | U | | 500 | | | <0.84 | U | | <0.7 | U | |
| | | VMP-44-20-101212 | 10/12/2012 | <2.5 | U | | <2.8 | U | | <4.4 | U | | <4 | U | | 1.7 | J | | <24 | U | | 21 | | | <9.3 | U | | 180 | | | <2.8 | U | | <2.3 | U | |
| | | VMP-44-20-012513 | 1/25/2013 | <0.18 | U | | <0.2 | U | | <0.32 | U | | <0.29 | U | | <0.17 | U | | <1.8 | U | | 0.38 | | | <0.68 | U | | 16 | | | <0.2 | U | | <0.17 | U | |
| | 30 ft | VMP-44-30-041912 | 4/19/2012 | 1.6 | | | 0.52 | J | J | <0.45 | U | | <0.41 | U | | 3.3 | | | <2.5 | U | | 16 | | | <0.96 | U | | 140 | | | 0.19 | J | | 0.48 | | |
| | | VMP-44-30-072512 | 7/25/2012 | 0.82 | | | 0.17 | | | <0.075 | U | | <0.068 | U | | 0.94 | | | <0.42 | U | | 3.3 | | | <0.16 | U | | 11 | | | 0.077 | | | <0.04 | U | |
| | | VMP-44-30-072512-Dup | 7/25/2012 | 0.83 | | | 0.16 | | | <0.075 | U | | <0.068 | U | | 0.96 | | | <0.42 | U | | 3.3 | | | <0.16 | U | | 12 | | | 0.08 | | | <0.04 | U | |
| | | VMP-44-30-101512 | 10/15/2012 | <0.26 | U | | <0.3 | U | | <0.46 | U | | <0.42 | U | | 0.63 | | | <2.6 | U | | 4.8 | | | <0.99 | U | | 40 | | | <0.3 | U | | <0.25 | U | |
| | | VMP-44-30-101512-Dup | 10/15/2012 | <0.24 | U | | <0.28 | U | | <0.43 | U | | <0.39 | U | | 0.6 | | | <2.4 | U | | 4.7 | | | <0.92 | U | | 39 | | | <0.28 | U | | <0.23 | U | |
| | | VMP-44-30-012513 | 1/25/2013 | <0.063 | U | UJ | <0.072 | U | UJ | <0.11 | U | UJ | <0.1 | U | UJ | <0.06 | U | UJ | <0.62 | U | UJ | 0.017 | J | J | <0.24 | U | UJ | 0.061 | J | J | <0.072 | U | UJ | <0.06 | U | UJ |
| VMP-45 | 10 ft | VMP-45-10-041912 | 4/19/2012 | 0.0017 | J | | <0.0045 | U | | <0.007 | U | | <0.0064 | U | | 0.0022 | J | | <0.039 | U | | 0.0041 | | | <0.015 | U | | 0.0025 | J | | 0.032 | | | 0.18 | | |
| | | VMP-45-10-071912 | 7/19/2012 | 0.0055 | | | 0.0019 | J | | <0.0072 | U | | <0.0065 | U | | 0.013 | | | <0.04 | U | | 0.001 | J | | 0.0032 | J | | 0.002 | J | | 0.044 | | | 0.25 | | |
| | | VMP-45-10-101512 | 10/15/2012 | <0.0063 | U | | <0.0072 | U | | <0.011 | U | | <0.01 | U | | <0.006 | U | | <0.062 | U | | 0.001 | J | | <0.024 | U | | 0.0068 | J | | <0.0072 | U | | <0.006 | U | |
| | | VMP-45-10-013013 | 1/30/2013 | <0.0055 | U | | <0.0062 | U | | <0.0096 | U | | <0.0088 | U | | 0.0012 | J | | <0.054 | U | | 0.002 | J | | <0.021 | U | | 0.0025 | J | | <0.0062 | U | | 0.0011 | J | |
| | 20 ft | VMP-45-20-041912 | 4/19/2012 | 3.8 | | | 0.7 | | | <0.44 | U | | <0.4 | U | | <0.23 | U | | <2.4 | U | | 0.73 | | | <0.93 | U | | 4.7 | | | 0.18 | J | | <0.23 | U | |
| | | VMP-45-20-071912 | 7/19/2012 | 0.022 | J | | <0.088 | U | | <0.14 | U | | <0.12 | U | | 0.074 | | | <0.76 | U | | 0.06 | J | | <0.29 | U | | 0.98 | | | 0.028 | J | | <0.073 | U | |
| | | VMP-45-20-101512 | 10/15/2012 | <0.006 | U | | <0.0068 | U | | <0.01 | U | | <0.0096 | U | | 0.0018 | J | | <0.059 | U | | 0.0039 | J | | <0.023 | U | | 0.054 | | | <0.0068 | J | U | 0.0076 | | |
| | | VMP-45-20-013013 | 1/30/2013 | <0.0057 | U | | <0.0065 | U | | <0.01 | U | | <0.0092 | U | | <0.0054 | U | | <0.056 | U | | <0.0046 | U | | <0.022 | U | | 0.0051 | J | | <0.0065 | U | | <0.0054 | U | |
| | 30 ft | VMP-45-30-041912 | 4/19/2012 | <0.16 | U | | 0.052 | J | J | <0.29 | U | | <0.27 | U | | 3.1 | | J | <1.6 | U | | 0.57 | | J | <0.62 | U | | 4.5 | | J | 0.23 | | J | <0.16 | U | |
| | | VMP-45-30-071912 | 7/19/2012 | <0.041 | U | | <0.047 | U | | <0.073 | U | | <0.067 | U | | <0.039 | U | | <0.41 | U | | <0.034 | U | | <0.16 | U | | 0.13 | | | 0.05 | | | 0.12 | | |
| | | VMP-45-30-101512 | 10/15/2012 | <0.006 | U | | <0.0068 | U | | <0.01 | U | | <0.0096 | U | | <0.0056 | U | | <0.059 | U | | 0.0044 | J | | <0.023 | U | | 0.039 | | | <0.0068 | U | | <0.0056 | U | |
| | | VMP-45-30-101512-Dup | 10/15/2012 | <0.0059 | U | | <0.0067 | U | | <0.01 | U | | <0.0095 | U | | <0.0056 | U | | <0.058 | U | | 0.0035 | J | | <0.022 | U | | 0.044 | | | <0.0067 | U | | <0.0056 | U | |
| | | VMP-45-30-013013 | 1/30/2013 | <0.01 | U | | <0.012 | U | | <0.018 | U | | <0.017 | U | | <0.0099 | U | | <0.1 | U | | 0.0028 | J | | <0.04 | U | | 0.0078 | J | | <0.012 | U | | <0.0099 | U | |

SEE LAST PAGE OF TABLE FOR NOTES

**TABLE 5**
**CUMULATIVE SUMMARY OF SOIL VAPOR ANALYTICAL DETECTIONS AND SCREENING RESULTS: VILLAGE - VOCS**

| Location | Depth | Sample ID | Sample Date | Ethylbenzene | | | 4-Ethyltoluene | | | Freon 113 | | | Freon 114 | | | Heptane | | | Hexachlorobutadiene | | | Hexane | | | 2-Hexanone (Methyl N-Butyl Ketone) | | | Isopentane | | | Isopropylbenzene (Cumene) | | | 4-Methyl-2-pentanone (Methyl Isobutyl Ketone) | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | 1400 | | | | | | | | | | | | | | | | | | | | | | | | | | 600 | | | | | |
| | | | | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals |
| VMP-47 | 5 ft | VMP-47-5-012113 | 1/21/2013 | <0.0063 | U | | <0.0071 | U | | <0.011 | U | | <0.01 | U | | <0.0059 | U | | <0.062 | U | | 0.0019 | J | | <0.024 | U | | 0.089 | | | <0.0071 | U | | <0.0059 | U | |
| | | [1]VMP-47-5-012313-R | 1/23/2013 | <21 | U | | <24 | U | | <37 | U | | <34 | U | | <20 | U | | <210 | U | | <17 | U | | <79 | U | | 4700 | | | <24 | U | | <20 | U | |
| | 10 ft | VMP-47-10-012113 | 1/21/2013 | <0.006 | U | | <0.0068 | U | | <0.01 | U | | <0.0096 | U | | <0.0056 | U | | <0.059 | U | | <0.0049 | U | | <0.023 | U | | 0.0052 | J | | <0.0068 | U | | <0.0056 | U | |
| | | [1]VMP-47-10-012313-R | 1/23/2013 | <0.52 | U | | <0.59 | U | | <0.93 | U | | <0.84 | U | | <0.5 | U | | <5.2 | U | | 1.7 | | | <2 | U | | 560 | | | <0.59 | U | | <0.5 | U | |
| | 20 ft | VMP-47-20-012113 | 1/21/2013 | <5.5 | U | | <6.2 | U | | <9.6 | U | | <8.8 | U | | <5.2 | U | | <54 | U | | <4.4 | U | | <21 | U | | 1200 | | | <6.2 | U | | <5.2 | U | |
| | | [1]VMP-47-20-012313-R | 1/23/2013 | <13 | U | | <15 | U | | <23 | U | | <21 | U | | <12 | U | | <130 | U | | 20 | | | <49 | U | | 3500 | | | <15 | U | | <12 | U | |
| | 30 ft | VMP-47-30-012113 | 1/21/2013 | <4 | U | | <4.5 | U | | <7 | U | | <6.4 | U | | <3.8 | U | | <39 | U | | <3.2 | U | | <15 | U | | 1100 | | | <4.5 | U | | <3.8 | U | |
| | | [1]VMP-47-30-012313-R | 1/23/2013 | <21 | U | | <23 | U | | <36 | U | | <33 | U | | <20 | U | | <200 | U | | <17 | U | | <78 | U | | 4600 | | | <23 | U | | <19 | U | |
| VMP-48 | 5 ft | VMP-48-5-020113 | 2/1/2013 | <0.0056 | U | | <0.0063 | J | U | <0.0098 | U | | <0.009 | U | | <0.0053 | U | | <0.055 | U | | <0.0045 | U | | <0.021 | U | | 0.0026 | J | | <0.0063 | U | | <0.0053 | U | |
| | 10 ft | VMP-48-10-020113 | 2/1/2013 | <0.0058 | U | | <0.0065 | U | | <0.01 | U | | <0.0093 | U | | <0.0054 | U | | <0.057 | U | | 0.00089 | J | | <0.022 | U | | 0.0028 | J | | <0.0065 | U | | <0.0054 | U | |
| | 20 ft | VMP-48-20-020113 | 2/1/2013 | <0.0055 | U | | <0.0063 | U | | <0.0098 | U | | <0.0089 | U | | <0.0052 | U | | <0.054 | U | | 0.0018 | J | | <0.021 | U | | 0.022 | | | <0.0063 | U | | <0.0052 | U | |
| | 30 ft | VMP-48-30-020113 | 2/1/2013 | 0.0021 | J | J | 0.012 | | | <0.01 | U | | <0.0091 | U | | 0.01 | | | <0.056 | U | | 0.015 | | | <0.021 | U | | 0.22 | | | 0.00088 | J | | <0.0053 | U | |
| | | VMP-48-30-020113-DUP | 2/1/2013 | <0.022 | U | UJ | 0.012 | J | | <0.04 | U | | <0.036 | U | | 0.0087 | J | | <0.22 | U | | 0.017 | J | | <0.085 | U | | 0.22 | | | <0.026 | U | | <0.021 | U | |
| VMP-49 | 5 ft | VMP-49-5-020113 | 2/1/2013 | <0.0058 | U | | <0.0066 | U | | <0.01 | U | | <0.0094 | U | | <0.0055 | U | | <0.057 | U | | <0.0047 | U | | <0.022 | U | | <0.016 | U | | <0.0066 | U | | 0.0013 | J | |
| | 10 ft | VMP-49-10-020113 | 2/1/2013 | <0.0057 | J | U | <0.0065 | J | U | <0.01 | U | | <0.0092 | U | | <0.0054 | U | | <0.056 | U | | 0.0016 | J | | <0.022 | U | | 0.002 | J | | <0.0065 | J | U | <0.0054 | U | |
| | 20 ft | VMP-49-20-020113 | 2/1/2013 | <0.0056 | U | | <0.0063 | U | | <0.0099 | U | | <0.009 | U | | 0.0014 | J | | <0.055 | U | | 0.0021 | J | | <0.021 | U | | 0.0029 | J | | <0.0063 | U | | <0.0053 | U | |
| | 30 ft | VMP-49-30-020113 | 2/1/2013 | <0.27 | U | | <0.3 | U | | <0.47 | U | | <0.43 | U | | <0.25 | U | | <2.6 | U | | 0.073 | J | | <1 | U | | 47 | | | <0.3 | U | | 0.11 | J | |
| VMP-50 | 5 ft | VMP-50-5-020113 | 2/1/2013 | <0.0055 | U | | <0.0062 | J | U | <0.0096 | U | | <0.0088 | U | | 0.0012 | J | | <0.054 | U | | 0.004 | J | | <0.021 | U | | 0.12 | | | <0.0062 | U | | <0.0052 | U | |
| | 10 ft | VMP-50-10-020113 | 2/1/2013 | <0.006 | U | | <0.0068 | J | U | <0.01 | U | | <0.0096 | U | | <0.0056 | U | | <0.059 | U | | 0.0021 | J | | <0.023 | U | | 0.042 | | | <0.0068 | U | | <0.0056 | U | |
| | 20 ft | VMP-50-20-020113 | 2/1/2013 | 0.017 | J | | 0.0095 | J | | <0.041 | U | | <0.037 | U | | 0.16 | | | <0.23 | U | | 0.061 | | | <0.088 | U | | 0.13 | | | 0.0048 | J | | <0.022 | U | |
| | 30 ft | VMP-50-30-020113 | 2/1/2013 | 370 | | | 88 | | | <9.9 | U | | <9 | U | | 570 | | | <55 | U | | 1100 | | | <21 | U | | 1100 | | | 19 | | | <5.3 | U | |
| VMP-51 | 5 ft | VMP-51-5-020113 | 2/1/2013 | <0.0059 | U | | <0.0067 | U | | <0.01 | U | | <0.0095 | U | | <0.0056 | U | | <0.058 | U | | 0.0011 | J | | <0.022 | U | | 0.0019 | J | | <0.0067 | U | | <0.0056 | U | |
| | 10 ft | VMP-51-10-020113 | 2/1/2013 | <0.006 | U | | <0.0068 | U | | <0.01 | U | | <0.0096 | U | | <0.0056 | U | | <0.059 | U | | 0.0013 | J | | <0.023 | U | | <0.016 | U | | <0.0068 | U | | <0.0056 | U | |
| | 20 ft | VMP-51-20-021513-R | 2/15/2013 | 0.0045 | J | | 0.0019 | J | | <0.01 | U | | <0.0092 | U | | <0.0054 | U | | <0.056 | U | | 0.0012 | J | | <0.022 | U | | 0.0086 | J | | 0.0028 | J | | <0.0054 | U | |
| | 30 ft | VMP-51-30-020413 | 2/4/2013 | <0.0063 | U | | <0.0071 | U | | <0.011 | U | | <0.01 | U | | 0.0026 | J | | <0.062 | U | | 0.0052 | | | <0.024 | U | | 0.016 | J | | <0.0071 | U | | <0.0059 | U | |
| | | VMP-51-30-020413-DUP | 2/4/2013 | <0.0061 | U | | <0.0069 | U | | <0.011 | U | | <0.0098 | U | | 0.0038 | J | | <0.06 | U | | 0.007 | | | <0.023 | U | | 0.032 | | | <0.0069 | U | | <0.0058 | U | |
| VMP-52 | 5 ft | VMP-52-5-020413 | 2/4/2013 | <0.0055 | U | | <0.0062 | J | U | <0.0096 | U | | <0.0088 | U | | <0.0052 | U | | <0.054 | U | | 0.0014 | J | | <0.021 | U | | 0.005 | J | | <0.0062 | U | | 0.0099 | | |
| | 10 ft | VMP-52-10-020413 | 2/4/2013 | <0.0052 | U | | <0.0059 | U | | <0.0092 | U | | <0.0084 | U | | <0.0049 | U | | <0.051 | U | | 0.001 | J | | <0.02 | U | | 0.0047 | J | | <0.0059 | U | | <0.0049 | U | |
| | 20 ft | VMP-52-20-020413 | 2/4/2013 | <0.0058 | U | | <0.0066 | J | U | <0.01 | U | | <0.0094 | U | | 0.0043 | J | | <0.057 | J | U | 0.01 | | | <0.022 | U | | 0.053 | | | <0.0066 | U | | <0.0055 | U | |
| | | VMP-52-20-020413-DUP | 2/4/2013 | <0.0056 | U | | <0.0063 | J | U | <0.0098 | U | | <0.009 | U | | <0.0053 | U | | <0.055 | U | | 0.0052 | | | <0.021 | U | | 0.03 | | | <0.0063 | U | | <0.0053 | U | |
| | 30 ft | VMP-52-30-020413 | 2/4/2013 | <0.0061 | U | | <0.0069 | U | | <0.011 | U | | <0.0098 | U | | 0.0013 | J | | <0.06 | U | | 0.011 | | | <0.023 | U | | 0.043 | | | <0.0069 | U | | <0.0058 | U | |
| VMP-53 | 5 ft | VMP-53-5-020513 | 2/5/2013 | <0.0056 | U | | <0.0063 | U | | <0.0099 | U | | <0.009 | U | | <0.0053 | U | | <0.055 | U | | 0.00092 | J | | <0.021 | U | | 0.0017 | J | | <0.0063 | U | | <0.0053 | U | |
| | 10 ft | VMP-53-10-020513 | 2/5/2013 | <0.0057 | U | | <0.0065 | U | | <0.01 | U | | <0.0092 | U | | 0.0016 | J | | <0.056 | U | | 0.004 | J | | <0.022 | U | | 0.013 | J | | <0.0065 | U | | <0.0054 | U | |
| | | VMP-53-10-020513-DUP | 2/5/2013 | <0.0054 | U | | <0.0061 | U | | <0.0095 | U | | <0.0086 | U | | 0.0013 | J | | <0.053 | U | | 0.0021 | J | | <0.02 | U | | 0.0065 | J | | <0.0061 | U | | <0.005 | U | |
| | 20 ft | VMP-53-20-020513 | 2/5/2013 | <0.0057 | U | | <0.0065 | U | | <0.01 | U | | <0.0092 | U | | <0.0054 | U | | <0.056 | U | | 0.0016 | J | | <0.022 | U | | 0.006 | J | | <0.0065 | U | | <0.0054 | U | |
| | 30 ft | VMP-53-30-020513 | 2/5/2013 | <0.0058 | U | | <0.0066 | U | | <0.01 | U | | <0.0094 | U | | <0.0055 | U | | <0.057 | U | | 0.00081 | J | | <0.022 | U | | <0.016 | U | | <0.0066 | U | | <0.0055 | U | |
| VMP-54 | 5 ft | VMP-54-5-020613 | 2/6/2013 | 0.011 | | | 0.043 | | | <0.01 | U | | <0.0096 | U | | 0.005 | J | | <0.059 | U | | 0.006 | | | <0.023 | U | | 0.028 | | | <0.0068 | J | U | <0.0056 | U | |
| | 10 ft | VMP-54-10-020613 | 2/6/2013 | 0.0034 | J | | 0.0064 | J | | <0.011 | U | | <0.0098 | U | | 0.0013 | J | | <0.06 | U | | 0.0017 | J | | <0.023 | U | | 0.0039 | J | | <0.0069 | U | | <0.0058 | U | |
| | 20 ft | VMP-54-20-020613 | 2/6/2013 | <0.006 | U | | <0.0068 | J | U | <0.01 | U | | <0.0096 | U | | 0.004 | J | | <0.059 | U | | 0.004 | J | | <0.023 | U | | 0.003 | J | | <0.0068 | U | | <0.0056 | U | |
| | | VMP-54-20-020613-DUP | 2/6/2013 | <0.006 | U | | <0.0068 | J | U | <0.01 | U | | <0.0096 | U | | 0.0048 | J | | <0.059 | U | | 0.0064 | | | <0.023 | U | | 0.012 | J | | <0.0068 | U | | <0.0056 | U | |
| | 30 ft | VMP-54-30-020613 | 2/6/2013 | <0.0064 | U | | <0.0073 | U | | <0.011 | U | | <0.01 | U | | <0.0061 | U | | <0.063 | U | | 0.0016 | J | | <0.024 | U | | 0.0045 | J | | <0.0073 | U | | <0.0061 | U | |
| | | VMP-54-30-020613-DUP | 2/6/2013 | <0.0064 | U | | <0.0073 | U | | <0.011 | U | | <0.01 | U | | <0.0061 | U | | <0.063 | U | | 0.0016 | J | | <0.024 | U | | 0.0023 | J | | <0.0073 | U | | <0.0061 | U | |

SEE LAST PAGE OF TABLE FOR NOTES

**TABLE 5**
**CUMULATIVE SUMMARY OF SOIL VAPOR ANALYTICAL DETECTIONS AND SCREENING RESULTS: VILLAGE - VOCS**

| Location | Depth | Sample ID | Sample Date | Methyl tert-Butyl Ether (MTBE) | | | 2-Propanol | | | n-Propylbenzene | | | Styrene | | | 1,1,2,2-Tetrachloroethane | | | Tetrachloroethene | | | Tetrahydrofuran | | | Toluene | | | 1,2,4-Trichlorobenzene | | | 1,1,1-Trichloroethane (Methyl chloroform) | | | 1,1,2-Trichloroethane | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | 3400 | | | | | | | | | 1400 | | | | | | 0.55 | | | | | | 6200 | | | 11 | | | 6600 | | | 170000 | | |
| | | | | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals |
| VMP-1 | 5 ft | VMP-1-5-082510 | 8/25/2010 | <0.015 | U | | <0.042 | U | | <0.021 | U | | <0.018 | U | | <0.029 | U | | <0.029 | U | | <0.012 | U | | 0.0031 | J | | <0.13 | U | | <0.023 | U | | <0.023 | U | |
| | | VMP-1-5-111710 | 11/17/2010 | <0.018 | U | | <0.051 | U | | <0.025 | U | | 0.0059 | J | | <0.035 | U | | <0.035 | U | | <0.015 | U | | <0.019 | U | | <0.15 | U | | <0.028 | U | | <0.028 | U | |
| | | VMP-1-5-020411 | 2/4/2011 | <0.36 | U | | 1.9 | | | <0.5 | U | | <0.43 | U | | <0.69 | U | | <0.68 | U | | <0.3 | U | | <0.38 | U | | <3 | U | | <0.55 | U | | <0.55 | U | |
| | | VMP-1-5-041211 | 4/12/2011 | <0.0048 | U | | 0.0032 | J | | 0.0038 | J | | <0.0056 | U | | <0.0091 | U | | 0.002 | J | | <0.0039 | U | | 0.0024 | J | | <0.039 | J | U | <0.0072 | U | | <0.0072 | U | |
| | | VMP-1-5-080111 | 8/1/2011 | <0.0048 | U | | 0.026 | | | 0.0013 | J | | 0.0021 | J | | <0.0091 | U | | <0.009 | U | | 0.0016 | J | | 0.032 | | | <0.039 | U | | <0.0072 | U | | <0.0072 | U | |
| | | VMP-1-5-110311 | 11/3/2011 | <13 | U | | <34 | U | | <17 | U | | <15 | U | | <24 | U | | <24 | U | | <10 | U | | <13 | U | | <100 | U | | <19 | U | | <19 | U | |
| | | VMP-1-5-013012 | 1/30/2012 | <1 | U | | <2.9 | U | | <1.4 | U | | <1.2 | U | | <2 | U | | <2 | U | | <0.86 | U | | <1.1 | U | | <8.6 | U | | <1.6 | U | | <1.6 | U | |
| | | VMP-1-5-041312 | 4/13/2012 | <0.0032 | U | | 0.04 | | | <0.0044 | U | | <0.0038 | U | | <0.0061 | U | | <0.0061 | J | U | <0.0026 | J | U | 0.0073 | | | <0.026 | U | | <0.0049 | U | | <0.0049 | U | |
| | | VMP-1-5-071612 | 7/16/2012 | <0.0033 | U | | 0.13 | | | 0.0027 | J | | 0.0038 | J | | <0.0063 | U | | 0.0039 | J | | <0.0027 | U | | 0.14 | | | <0.027 | U | | <0.005 | J | U | <0.005 | U | |
| | | VMP-1-5-101112 | 10/11/2012 | <0.0083 | U | | <0.023 | U | | <0.011 | U | | <0.0098 | U | | <0.016 | U | | <0.016 | U | | <0.0068 | U | | 0.0014 | J | | <0.068 | U | | <0.012 | U | | <0.012 | U | |
| | | [A]VMP-1-5-012113 | 1/21/2013 | <0.093 | U | | 0.15 | J | | <0.13 | U | | 0.021 | J | | <0.18 | U | | <0.18 | U | | <0.076 | U | | 0.025 | J | | <0.76 | U | | <0.14 | U | | <0.14 | U | |
| | | [A]VMP-1-5-012313-R | 1/23/2013 | <4.2 | U | | <11 | U | | <5.7 | U | | <5 | U | | <8 | U | | <7.9 | U | | <3.4 | U | | 4 | J | | <34 | U | | <6.4 | U | | <6.4 | U | |
| | 8.5 ft | VMP-1-8.5-082510 | 8/25/2010 | <0.046 | U | | <0.13 | U | | <0.063 | U | | <0.055 | U | | <0.088 | U | | <0.087 | U | | <0.038 | U | | <0.048 | U | | <0.38 | U | | <0.07 | U | | <0.07 | U | |
| | | VMP-1-8.5-111710 | 11/17/2010 | <0.0089 | U | | <0.024 | U | | 0.0022 | J | | 0.0034 | J | | <0.017 | U | | <0.017 | U | | <0.0073 | U | | <0.0093 | U | | <0.073 | U | | <0.013 | U | | <0.013 | U | |
| | | VMP-1-8.5-111710-Dup | 11/17/2010 | 0.00094 | J | | 0.015 | J | | 0.0021 | J | | 0.0022 | J | | <0.017 | U | | <0.017 | U | | <0.0073 | U | | 0.002 | J | | <0.073 | U | | <0.013 | U | | <0.013 | U | |
| | | VMP-1-8.5-020411 | 2/4/2011 | <0.72 | U | | <2 | U | | <0.98 | U | | <0.84 | U | | <1.4 | U | | <1.3 | U | | <0.58 | U | | <0.75 | U | | <5.9 | U | | <1.1 | U | | <1.1 | U | |
| | | VMP-1-8.5-041211 | 4/12/2011 | <0.0063 | U | | <0.017 | U | | 0.0025 | J | | <0.0074 | U | | <0.012 | U | | 0.00097 | J | | <0.0051 | U | | 0.0022 | J | | <0.052 | J | U | <0.0095 | U | | <0.0095 | U | |
| | | VMP-1-8.5-080111 | 8/1/2011 | <2.6 | U | | <7.1 | U | | <3.5 | U | | <3.1 | U | | <4.9 | U | | <4.9 | U | | <2.1 | U | | <2.7 | U | | <21 | U | | <3.9 | U | | <3.9 | U | |
| | | VMP-1-8.5-080111-Dup | 8/1/2011 | <2.5 | U | | <6.9 | U | | <3.5 | U | | <3 | U | | <4.8 | U | | <4.8 | U | | <2.1 | U | | <2.6 | U | | <21 | U | | <3.8 | U | | <3.8 | U | |
| | | VMP-1-8.5-110311 | 11/3/2011 | <29 | U | | <79 | U | | <40 | U | | <34 | U | | <55 | U | | <55 | U | | <24 | U | | <30 | U | | <240 | U | | <44 | U | | <44 | U | |
| | | VMP-1-8.5-013012 | 1/30/2012 | <6.3 | U | | <17 | U | | <8.6 | U | | <7.4 | U | | <12 | U | | <12 | U | | <5.2 | U | | <6.6 | U | | <52 | U | | <9.5 | U | | <9.5 | U | |
| | | VMP-1-8.5-041612 | 4/16/2012 | <0.0038 | U | | 0.021 | | | 0.00093 | J | | <0.0045 | U | | <0.0073 | U | | <0.0072 | U | | <0.0031 | U | | 0.012 | | | <0.031 | J | U | <0.0058 | U | | <0.0058 | U | |
| | | VMP-1-8.5-041612-Dup | 4/16/2012 | <0.0037 | U | | 0.022 | | | 0.00083 | J | | <0.0044 | U | | <0.0071 | U | | <0.007 | U | | <0.003 | U | | 0.014 | | | <0.03 | J | U | <0.0056 | J | U | <0.0056 | U | |
| | | VMP-1-8.5-071612 | 7/16/2012 | <0.0033 | U | | 0.097 | | | <0.0045 | J | U | 0.0034 | J | | <0.0063 | U | | 0.0035 | J | | 0.0049 | | | 0.11 | | | <0.027 | U | | <0.005 | J | U | <0.005 | U | |
| | | VMP-1-8.5-101112 | 10/11/2012 | <0.0051 | U | | 0.0012 | J | | <0.0069 | U | | <0.006 | U | | <0.0097 | U | | <0.0096 | U | | <0.0042 | U | | 0.0014 | J | | <0.042 | J | U | <0.0077 | U | | <0.0077 | U | |
| | | [A]VMP-1-8.5-012113 | 1/21/2013 | <0.09 | U | | <0.25 | U | | <0.12 | U | | <0.11 | U | | <0.17 | U | | <0.17 | U | | <0.074 | U | | <0.094 | U | | <0.74 | UJ | UJ | <0.14 | U | | <0.14 | U | |
| | | [A]VMP-1-8.5-012313-R | 1/23/2013 | <0.084 | U | | <0.23 | U | | <0.11 | U | | <0.099 | U | | <0.16 | U | | <0.16 | U | | <0.069 | U | | 0.018 | J | | <0.69 | U | | <0.13 | U | | <0.13 | U | |
| | 23.5 ft | VMP - 1 - 23.5 - 083010 | 8/30/2010 | <1.6 | U | | <4.4 | U | | <2.2 | U | | <1.9 | U | | <3.1 | U | | <3 | U | | <1.3 | U | | <1.7 | U | | <13 | U | | <2.4 | U | | <2.4 | U | |
| | | VMP-1-23.5-111810 | 11/17/2010 | 0.00052 | J | | 0.0052 | J | | <0.0061 | U | | 0.003 | J | | <0.0085 | U | | <0.0084 | J | U | <0.0036 | U | | 0.001 | J | | <0.037 | U | | <0.0067 | U | | <0.0067 | U | |
| | | VMP-1-23.5-020411 | 2/4/2011 | <4.2 | U | | <11 | U | | <5.7 | U | | <5 | U | | <8 | U | | <7.9 | U | | <3.4 | U | | <4.4 | U | | <34 | U | | <6.4 | U | | <6.4 | U | |
| | | VMP-1-23.5-041211 | 4/12/2011 | <6.8 | U | | 12 | J | | <9.3 | U | | <8.1 | U | | <13 | U | | <13 | U | | <5.6 | U | | 1.9 | J | | <56 | U | | <10 | U | | <10 | U | |
| | | VMP-1-23.5-041211-DUP | 4/12/2011 | <8.6 | U | | 8.1 | J | | <12 | U | | <10 | U | | <16 | U | | <16 | U | | <7.1 | U | | <9 | U | | <71 | U | | <13 | U | | <13 | U | |
| | | VMP-1-23.5-080111 | 8/1/2011 | <46 | U | | 14 | J | | <63 | U | | <55 | U | | <88 | U | | <88 | U | | <38 | U | | <49 | U | | <380 | U | | <70 | U | | <70 | U | |
| | | VMP-1-23.5-110611 | 11/6/2011 | <11 | U | | <30 | U | | <15 | U | | <13 | U | | <21 | U | | 5.4 | J | | <9 | U | | 5.1 | J | | <90 | U | | <17 | U | | <17 | U | |
| | | VMP-1-23.5-013112 | 1/31/2012 | <22 | U | | <59 | U | | <29 | U | | <26 | U | | <41 | U | | <41 | U | | <18 | U | | <23 | U | | <180 | U | | <33 | U | | <33 | U | |
| | | VMP-1-23.5-041612 | 4/16/2012 | <1.7 | U | | <4.7 | U | | <2.3 | U | | <2 | U | | <3.3 | U | | <3.2 | U | | <1.4 | U | | <1.8 | U | | <14 | U | | <2.6 | U | | <2.6 | U | |
| | | VMP-1-23.5-071612 | 7/16/2012 | <22 | U | | <59 | U | | <30 | U | | <26 | U | | <41 | U | | <41 | U | | <18 | U | | <23 | U | | <180 | U | | <33 | U | | <33 | U | |
| | | VMP-1-23.5-102412 | 10/24/2012 | <43 | U | | <120 | U | | <59 | U | | <51 | U | | <83 | U | | <82 | U | | <36 | U | | 12 | J | | <360 | U | | <66 | U | | <66 | U | |
| | | [A]VMP-1-23.5-012113 | 1/21/2013 | <0.048 | U | UJ | <0.13 | U | UJ | <0.066 | U | UJ | <0.057 | U | UJ | <0.092 | U | UJ | <0.091 | U | UJ | <0.04 | U | UJ | <0.051 | U | UJ | <0.4 | UJ | UJ | <0.073 | U | UJ | <0.073 | U | UJ |
| | | [A]VMP-1-23.5-012313-R | 1/23/2013 | <58 | U | | <160 | U | | <79 | U | | <68 | U | | <110 | U | | <110 | U | | <47 | U | | 27 | J | | <480 | U | | <88 | U | | <88 | U | |
| | 38.5 ft | VMP-1-38.5-073112 | 7/31/2012 | 0.0004 | J | | 0.013 | | | 0.00058 | J | | 0.0021 | J | | <0.0064 | U | | <0.0063 | U | | 0.001 | J | | 0.049 | | | <0.028 | U | | <0.0051 | U | | <0.0051 | U | |
| | | VMP-1-38.5-102612 | 10/26/2012 | <2.3 | U | | <6.4 | U | | <3.2 | U | | <2.8 | U | | <4.5 | U | | <4.4 | U | | <1.9 | U | | <2.4 | U | | <19 | U | UJ | <3.5 | U | | <3.5 | U | |
| | | [A]VMP-1-38.5-012113 | 1/21/2013 | <0.032 | U | UJ | <0.086 | U | UJ | <0.043 | U | UJ | <0.037 | U | UJ | <0.06 | U | UJ | <0.06 | U | UJ | <0.026 | U | UJ | <0.033 | U | UJ | <0.26 | U | UJ | <0.048 | U | UJ | <0.048 | U | UJ |
| | | [A]VMP-1-38.5-012313-R | 1/23/2013 | <43 | U | | <120 | U | | <58 | U | | <51 | U | | <82 | U | | <81 | U | | <35 | U | | 22 | J | | <350 | U | | <65 | U | | <65 | U | |
| VMP-2 | 5 ft | VMP - 2 - 5 - 083110 | 8/31/2010 | <1.6 | U | | <4.4 | U | | <2.2 | U | | <1.9 | U | | <3.1 | U | | <3 | U | | <1.3 | U | | <1.7 | U | | <13 | U | | <2.4 | U | | <2.4 | U | |
| | | VMP-2-5-111610 | 11/16/2010 | <2.4 | U | | <6.5 | U | | <3.2 | U | | <2.8 | U | | <4.5 | U | | <4.5 | U | | <1.9 | U | | <2.5 | U | | <20 | U | | <3.6 | U | | <3.6 | U | |
| | | VMP-2-5-020411 | 2/4/2011 | <0.62 | U | | <1.7 | U | | <0.85 | U | | <0.73 | U | | <1.2 | U | | <1.2 | U | | <0.51 | U | | <0.65 | U | | <5.1 | U | | <0.94 | U | | <0.94 | U | |
| | | VMP-2-5-041311 | 4/13/2011 | 0.00046 | J | | <0.014 | U | | 0.0022 | J | | <0.0059 | U | | <0.0095 | U | | 0.0042 | J | | <0.0041 | U | | 0.0046 | J | | <0.041 | U | | <0.0076 | U | | <0.0076 | U | |
| | | VMP-2-5-080211 | 8/2/2011 | <5.2 | U | | <14 | U | | <7.1 | U | | <6.2 | U | | <9.9 | U | | <9.8 | U | | <4.3 | U | | <5.4 | U | | <43 | U | | <7.9 | U | | <7.9 | U | |
| | | VMP-2-5-110711 | 11/7/2011 | <0.0031 | U | | 0.016 | | | 0.00028 | J | | <0.0036 | U | | <0.0059 | U | | <0.0058 | J | U | <0.0025 | U | | 0.01 | | | <0.025 | U | | <0.0047 | U | | <0.0047 | U | |
| | | VMP-2-5-012512 | 1/25/2012 | <0.35 | U | | 0.75 | J | | <0.48 | U | | <0.41 | U | | <0.66 | U | | <0.66 | U | | <0.29 | U | | 1.3 | | | <2.9 | U | | <0.53 | U | | <0.53 | U | |
| | | VMP-2-5-042512 | 4/25/2012 | <0.014 | U | | 0.04 | | | <0.019 | U | | <0.016 | U | | <0.026 | U | | 0.0065 | J | | <0.011 | U | | 0.038 | | | <0.11 | U | | <0.021 | U | | <0.021 | U | |
| | | VMP-2-5-071612 | 7/16/2012 | <0.0034 | U | | 0.1 | | | <0.0046 | J | U | 0.0041 | | | <0.0064 | U | | 0.004 | J | | 0.0048 | | | 0.13 | | | <0.028 | U | | <0.0051 | J | U | <0.0051 | U | |
| | | VMP-2-5-102412 | 10/24/2012 | <0.0052 | U | | 0.044 | | | <0.007 | U | | <0.0061 | U | | <0.0098 | U | | 0.0051 | J | | 0.0038 | J | | 0.013 | | | <0.042 | U | | <0.0078 | U | | <0.0078 | U | |
| | | VMP-2-5-013113 | 1/31/2013 | <0.005 | U | | 0.039 | | | <0.0068 | J | U | <0.0059 | U | | <0.0095 | U | | <0.0094 | J | U | <0.0041 | U | | <0.0052 | J | U | <0.041 | U | | <0.0075 | U | | <0.0075 | U | |
| | 8.5 ft | VMP-2-8.5-083110 | 8/31/2010 | <1.6 | U | | <4.5 | U | | <2.3 | U | | <2 | U | | <3.2 | U | | <3.1 | U | | <1.4 | U | | <1.7 | U | | <14 | U | | <2.5 | U | | <2.5 | U | |
| | | VMP-2-8.5-111610 | 11/16/2010 | <4.5 | U | | <12 | U | | <6.2 | U | | <5.4 | U | | <8.6 | U | | <8.5 | U | | <3.7 | U | | <4.7 | U | | <37 | U | | <6.9 | U | | <6.9 | U | |
| | | VMP-2-8.5-020411 | 2/4/2011 | <1.6 | U | | <4.2 | U | | <2.1 | U | | <1.8 | U | | <3 | U | | <2.9 | U | | <1.3 | U | | <1.6 | U | | <13 | U | | <2.3 | U | | <2.3 | U | |
| | | VMP-2-8.5-041311 | 4/13/2011 | <0.47 | U | | <1.3 | U | | <0.65 | U | | <0.56 | U | | <0.9 | U | | <0.89 | U | | <0.39 | U | | 0.035 | J | | <3.9 | U | | 0.078 | J | | <0.72 | U | |
| | | VMP-2-8.5-080211 | 8/2/2011 | <19 | U | | 11 | J | | <26 | U | | <22 | U | | <36 | U | | <36 | U | | <16 | U | | <20 | U | | <160 | U | | <29 | U | | <29 | U | |
| | | VMP-2-8.5-110711 | 11/7/2011 | <0.041 | U | | <0.11 | U | | <0.056 | U | | <0.048 | U | | <0.078 | U | | <0.077 | U | | <0.034 | U | | 0.01 | J | | <0.34 | U | | <0.062 | U | | <0.062 | U | |
| | | VMP-2-8.5-012612 | 1/26/2012 | <1.8 | U | | <5 | U | | <2.5 | U | | <2.2 | U | | <3.5 | U | | <3.4 | U | | <1.5 | U | | <1.9 | U | | <15 | U | | <2.8 | U | | <2.8 | U | |
| | | VMP-2-8.5-012612-DUP | 1/26/2012 | <1.8 | U | | <5 | U | | <2.5 | U | | <2.2 | U | | <3.5 | U | | <3.4 | U | | <1.5 | U | | <1.9 | U | | <15 | U | | <2.8 | U | | <2.8 | U | |
| | | VMP-2-8.5-041612 | 4/16/2012 | <0.0035 | U | | 0.023 | | | 0.00091 | J | | 0.00085 | J | | <0.0067 | U | | <0.0066 | U | | <0.0029 | U | | 0.012 | | | <0.029 | U | | <0.0053 | J | U | <0.0053 | U | |
| | | VMP-2-8.5-041612-Dup | 4/16/2012 | <0.0036 | U | | 0.024 | | | 0.00098 | J | | 0.00089 | J | | <0.0069 | U | | <0.0068 | U | | <0.003 | U | | 0.012 | | | <0.03 | U | | <0.0055 | J | U | <0.0055 | U | |
| | | VMP-2-8.5-071612 | 7/16/2012 | <0.004 | U | | 0.065 | | | <0.0055 | J | U | 0.0031 | J | | <0.0077 | U | | <0.0076 | J | U | 0.0037 | | | 0.057 | | | <0.033 | U | | <0.0061 | U | | <0.0061 | U | |
| | | VMP-2-8.5-071612-Dup | 7/16/2012 | <0.0033 | U | | 0.062 | | | <0.0045 | J | U | 0.0028 | J | | <0.0063 | U | | 0.0043 | J | | 0.0033 | | | 0.059 | | | <0.027 | U | | <0.005 | J | U | <0.005 | U | |
| | | VMP-2-8.5-102312 | 10/23/2012 | <0.0052 | U | | 0.0032 | J | | <0.0072 | J | U | <0.0062 | U | | <0.01 | U | | 0.0046 | J | | <0.0043 | U | | 0.017 | | | <0.043 | U | | <0.0079 | U | | <0.0079 | U | |
| | | VMP-2-8.5-020513 | 2/5/2013 | <0.0053 | U | | 0.01 | J | | <0.0073 | U | | <0.0063 | U | | <0.01 | U | | <0.01 | J | U | <0.0044 | U | | 0.0073 | | | <0.044 | U | | <0.0081 | U | | <0.0081 | U | |
| | 22 ft | VMP-2-22-083110 | 8/31/2010 | <2.5 | U | | <6.9 | U | | <3.5 | U | | <3 | U | | <4.8 | U | | <4.8 | U | | <2.1 | U | | <2.6 | U | | <21 | U | | <3.8 | U | | <3.8 | U | |
| | | VMP-2-22-111610 | 11/16/2010 | <4.8 | U | | <13 | U | | <6.5 | U | | <5.6 | U | | <9.1 | U | | <9 | U | | <3.9 | U | | <5 | U | | <39 | U | | <7.2 | U | | <7.2 | U | |
| | | VMP-2-22-020411 | 2/4/2011 | <2.1 | U | | <5.8 | U | | <2.9 | U | | <2.5 | U | | <4.1 | U | | <4 | U | | <1.8 | U | | <2.2 | U | | <18 | U | | <3.2 | U | | <3.2 | U | |
| | | VMP-2-22-041311 | 4/13/2011 | <6.3 | U | | <17 | U | | <8.6 | U | | <7.4 | U | | <12 | U | | <12 | U | | <5.1 | U | | <6.6 | U | | <52 | U | | <9.5 | U | | <9.5 | U | |
| | | VMP-2-22-080211 | 8/2/2011 | <25 | U | | <69 | U | | <35 | U | | <30 | U | | <48 | U | | <48 | U | | <21 | U | | <26 | U | | <210 | U | | <38 | U | | <38 | U | |
| | | VMP-2-22-110711 | 11/7/2011 | <1.3 | U | | <3.7 | U | | <1.8 | U | | <1.6 | U | | <2.6 | U | | 0.81 | J | | <1.1 | U | | 1.4 | | | <11 | U | | <2 | U | | <2 | U | |
| | | VMP-2-22-012612 | 1/26/2012 | <2.8 | U | | <7.6 | U | | <3.8 | U | | <3.3 | U | | <5.3 | U | | <5.2 | U | | <2.3 | U | | <2.9 | U | | <23 | U | | <4.2 | U | | <4.2 | U | |
| | | VMP-2-22-042712 | 4/27/2012 | <0.0029 | U | | 0.02 | | | <0.004 | U | | 0.00081 | J | | <0.0055 | U | | 0.0028 | J | | 0.0029 | | | 0.013 | | | <0.024 | U | | <0.0044 | U | | <0.0044 | U | |
| | | VMP-2-22-071612 | 7/16/2012 | <0.0034 | U | | 0.2 | | | <0.0047 | J | U | 0.0037 | J | | <0.0065 | U | | 0.0035 | J | | 0.0062 | | | 0.11 | | | <0.028 | U | | <0.0052 | U | | <0.0052 | U | |
| | | VMP-2-22-102312 | 10/23/2012 | <0.0052 | U | | 0.002 | J | | <0.0072 | U | | <0.0062 | U | | <0.01 | U | | 0.0066 | J | | <0.0043 | U | | <0.0055 | J | U | <0.043 | U | | 0.00061 | J | | <0.0079 | U | |
| | | VMP-2-22-013113 | 1/31/2013 | <0.0048 | U | | 0.0057 | J | | <0.0066 | U | | <0.0057 | U | | <0.0092 | U | | <0.0091 | J | U | <0.004 | U | | <0.0051 | U | | <0.04 | U | | <0.0073 | U | | <0.0073 | U | |
| | 42 ft | VMP-2-42-013113 | 1/31/2013 | <47 | U | | 90 | J | | 9.5 | J | | 22 | J | | 16 | J | | <88 | U | | <38 | U | | 19 | J | | 92 | J | | <71 | U | | <71 | U | |

SEE LAST PAGE OF TABLE FOR NOTES

**TABLE 5**
**CUMULATIVE SUMMARY OF SOIL VAPOR ANALYTICAL DETECTIONS AND SCREENING RESULTS: VILLAGE - VOCS**

| Location | Depth | Sample ID | Sample Date | Methyl tert-Butyl Ether (MTBE) 3400 | | | 2-Propanol 1400 | | | n-Propylbenzene | | | Styrene | | | 1,1,2,2-Tetrachloroethane | | | Tetrachloroethene 0.55 | | | Tetrahydrofuran | | | Toluene 6200 | | | 1,2,4-Trichlorobenzene 11 | | | 1,1,1-Trichloroethane (Methyl chloroform) 6600 | | | 1,1,2-Trichloroethane 170000 | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals |
| VMP-3 | 5 ft | VMP-3-5-090910 | 9/9/2010 | <4.8 | U | | <13 | U | | <6.5 | U | | <5.7 | U | | <9.1 | U | | <9 | U | | <3.9 | U | | <5 | U | | <39 | U | | <7.2 | U | | <7.2 | U | |
| | | VMP-3-5-112210 | 11/22/2010 | <4.8 | U | | 2.1 | J | | <6.6 | U | | <5.7 | U | | <9.2 | U | | 4.5 | J | | <4 | U | | 3.2 | J | | <40 | U | | <7.3 | U | | <7.3 | U | |
| | | VMP-3-5-020911 | 2/9/2011 | <2.2 | U | | <5.9 | U | | <3 | U | | <2.6 | U | | <4.2 | U | | <4.1 | U | | <1.8 | U | | <2.3 | U | | <18 | U | | <3.3 | U | | <3.3 | U | |
| | | VMP-3-5-041411 | 4/14/2011 | <23 | U | | <64 | UJ | UJ | <32 | U | | <28 | U | | <45 | U | | <44 | U | | <19 | U | | <24 | U | | <190 | U | | <35 | U | | <35 | U | |
| | | VMP-3-5-080211 | 8/2/2011 | <0.0056 | U | | 0.019 | | | <0.0076 | U | | <0.0037 | U | | 0.0021 | J | | <0.011 | U | | 0.0015 | J | | 0.02 | | | <0.046 | U | | <0.0085 | U | | <0.0085 | U | |
| | | VMP-3-5-110811 | 11/8/2011 | <0.0031 | U | | 0.0094 | | | <0.0042 | U | | <0.0036 | U | | <0.0059 | U | | <0.0058 | U | | <0.0025 | U | | 0.0094 | | | <0.025 | U | | <0.0047 | U | | <0.0047 | U | |
| | | VMP-3-5-110811-DUP | 11/8/2011 | <0.0032 | U | | 0.0093 | | | <0.0043 | U | | <0.0037 | U | | <0.006 | U | | <0.0059 | U | | <0.0026 | U | | 0.0085 | | | <0.026 | U | | <0.0048 | U | | <0.0048 | U | |
| | | VMP-3-5-012712 | 1/27/2012 | <1.6 | U | | <4.3 | U | | <2.2 | U | | <1.9 | U | | <3 | U | | <3 | U | | <1.3 | U | | <1.6 | U | | <13 | U | | <2.4 | U | | <2.4 | U | |
| | | VMP-3-5-041912 | 4/19/2012 | <0.0034 | U | | 0.1 | | | 0.0013 | J | | 0.0018 | J | | <0.0066 | U | | <0.0065 | U | | 0.012 | | | 0.033 | | | <0.028 | U | | <0.0052 | J | U | <0.0052 | U | |
| | | VMP-3-5-072712 | 7/27/2012 | <0.0036 | U | | 0.055 | | | 0.0011 | J | | 0.0029 | J | | <0.0069 | U | | <0.0068 | U | | 0.005 | | | 0.024 | | | <0.03 | U | | <0.0055 | U | | <0.0055 | U | |
| | 10 ft | VMP-3-10 | 6/21/2010 | <5.5 | U | | 3.8 | J | | 5.6 | J | | <6.4 | U | | <10 | U | | <10 | U | | <4.5 | U | | <5.7 | U | | <45 | U | | <8.3 | U | | <8.3 | U | |
| | | VMP-3-10-091010 | 9/10/2010 | <15 | U | | <42 | U | | 7.2 | J | | <18 | U | | <29 | U | | <29 | U | | <12 | U | | <16 | U | | <130 | U | | <23 | U | | <23 | U | |
| | | VMP-3-10-092010 | 9/20/2010 | <11 | U | | <30 | U | | 4.4 | J | | <13 | U | | <21 | U | | <21 | U | | <9.1 | U | | 9.9 | J | | <92 | U | | <17 | U | | <17 | U | |
| | | VMP-3-10-112210 | 11/22/2010 | <4.8 | U | | <13 | U | | 11 | | | <5.6 | U | | <9.1 | U | | <9 | U | | <3.9 | U | | 2.1 | J | | <39 | U | | <7.2 | U | | <7.2 | U | |
| | | VMP-3-10-112210-Dup | 11/22/2010 | <6.6 | U | | <18 | U | | 7.9 | J | | <7.8 | U | | <13 | U | | <12 | U | | <5.4 | U | | 2 | J | | <55 | U | | <10 | U | | <10 | U | |
| | | VMP-3-10-020811 | 2/8/2011 | <7 | U | | <19 | U | | <9.5 | U | | <8.3 | U | | <13 | U | | <13 | U | | <5.7 | U | | <7.3 | U | | <58 | U | | <10 | U | | <10 | U | |
| | | VMP-3-10-041311 | 4/13/2011 | <40 | U | | <110 | UJ | UJ | <55 | U | | <48 | U | | <77 | U | | <76 | U | | <33 | U | | <42 | U | | <330 | U | | <61 | U | | <61 | U | |
| | | VMP-3-10-080311 | 8/3/2011 | <0.051 | U | | 0.044 | J | | 0.022 | J | | <0.06 | U | | <0.097 | U | | <0.096 | U | | <0.042 | U | | 0.028 | J | | <0.42 | U | | <0.077 | U | | <0.077 | U | |
| | | VMP-3-10-110811 | 11/8/2011 | <0.0042 | U | | 0.015 | | | <0.0057 | U | | <0.005 | U | | <0.008 | U | | <0.0079 | U | | <0.0034 | U | | 0.013 | | | <0.034 | U | | <0.0064 | U | | <0.0064 | U | |
| | | VMP-3-10-012712 | 1/27/2012 | <0.03 | U | | 0.017 | J | | 0.015 | J | | <0.036 | U | | <0.058 | U | | <0.057 | U | | <0.025 | U | | 0.026 | J | | <0.25 | U | | <0.046 | U | | <0.046 | U | |
| | | VMP-3-10-042012 | 4/20/2012 | <0.0031 | U | | 0.018 | | | <0.0042 | J | U | 0.0011 | J | | <0.0059 | U | | <0.0058 | J | U | 0.0044 | | | 0.015 | | | <0.025 | U | | 0.00048 | J | | <0.0047 | U | |
| | | VMP-3-10-072312 | 7/23/2012 | <0.0036 | U | | 0.014 | | | <0.0049 | U | | 0.00037 | J | | <0.0069 | U | | <0.0068 | U | | <0.003 | U | | 0.008 | | | <0.03 | U | | <0.0055 | U | | <0.0055 | U | |
| | | VMP-3-10-101812 | 10/18/2012 | <0.0055 | U | | 0.012 | J | | 0.0011 | J | | <0.0064 | U | | <0.01 | U | | <0.01 | U | | <0.0045 | U | | 0.022 | | | <0.11 | U | UJ | <0.0083 | U | | <0.0083 | U | |
| | | VMP-3-10-020613 | 2/6/2013 | <0.0051 | U | | 0.0035 | J | | <0.0069 | U | | <0.006 | U | | <0.0097 | U | | 0.0088 | J | | <0.0042 | U | | <0.0053 | J | U | <0.042 | U | | <0.0077 | U | | <0.0077 | U | |
| | 22 ft | VMP-3-22-092010 | 9/20/2010 | <15 | U | | <40 | U | | 29 | | | <17 | U | | <28 | U | | <28 | U | | <12 | U | | 37 | | | <120 | U | | <22 | U | | <22 | U | |
| | | VMP-3-22-112210 | 11/22/2010 | <17 | U | | <46 | U | | 40 | | | <20 | U | | <32 | U | | <32 | U | | <14 | U | | <18 | U | | <140 | U | | <25 | U | | <25 | U | |
| | | VMP-3-22-020811 | 2/8/2011 | <8.2 | U | | <22 | U | | 20 | | | <9.8 | U | | <16 | U | | <16 | U | | <6.8 | U | | 4.3 | J | | <68 | U | | <12 | U | | <12 | U | |
| | | VMP-3-22-041511 | 4/15/2011 | <45 | U | | <120 | UJ | UJ | <61 | U | | <53 | U | | <85 | U | | <84 | U | | <36 | U | UJ | <47 | U | | <370 | U | | <68 | U | | <68 | U | |
| | | VMP-3-22-080611 | 8/6/2011 | <0.071 | U | | 0.11 | J | | <0.097 | U | | <0.084 | U | | <0.14 | U | | <0.13 | U | | <0.058 | U | | 0.087 | | | <0.59 | U | | <0.11 | U | | <0.11 | U | |
| | | VMP-3-22-110811 | 11/8/2011 | <0.0032 | U | | 0.032 | | | <0.0043 | U | | <0.0037 | U | | <0.006 | U | | <0.0059 | U | | 0.0024 | J | | 0.016 | | | <0.026 | U | | <0.0048 | U | | <0.0048 | U | |
| | | VMP-3-22-013012 | 1/30/2012 | <0.013 | U | | 0.054 | | | 0.0015 | J | | <0.015 | U | | <0.024 | U | | <0.024 | U | | <0.01 | U | | 0.03 | | | <0.1 | U | | <0.019 | U | | <0.019 | U | |
| | | VMP-3-22-042012 | 4/20/2012 | <0.0032 | U | | 0.017 | | | <0.0043 | J | U | <0.0037 | U | | <0.006 | U | | <0.0059 | J | U | 0.0044 | | | 0.014 | | | <0.026 | U | | <0.0048 | U | | <0.0048 | U | |
| | | VMP-3-22-072312 | 7/23/2012 | <0.0035 | U | | 0.0087 | J | | <0.0048 | U | | <0.0042 | U | | <0.0067 | U | | <0.0066 | U | | <0.0029 | U | | 0.0057 | | | <0.029 | U | | <0.0053 | U | | <0.0053 | U | |
| | | VMP-3-22-101812 | 10/18/2012 | <0.0053 | U | | 0.0032 | J | | <0.0073 | U | | <0.0063 | U | | <0.01 | U | | <0.01 | U | | <0.0044 | U | | 0.084 | | | <0.11 | U | UJ | <0.0081 | U | | <0.0081 | U | |
| | | VMP-3-22-020613 | 2/6/2013 | <0.0052 | U | | 0.0022 | J | | <0.0071 | U | | <0.0062 | U | | <0.0099 | U | | <0.0098 | J | U | <0.0043 | J | U | 0.00056 | J | | <0.043 | J | U | <0.0079 | U | | <0.0079 | U | |
| | 31.5 ft | VMP-3-31.5-090910 | 9/9/2010 | <27 | U | | <75 | U | | 17 | J | | <32 | U | | <52 | U | | <52 | U | | <22 | U | | 17 | J | | <220 | U | | <41 | U | | <41 | U | |
| | | VMP-3-31.5-112210 | 11/22/2010 | <19 | U | | <52 | U | | 9.8 | J | | <22 | U | | <36 | U | | <36 | U | | <16 | U | | 19 | J | | <160 | U | | <29 | U | | <29 | U | |
| | | VMP-3-31.5-020911 | 2/9/2011 | <18 | U | | <50 | U | | <25 | U | | <22 | U | | <35 | U | | <34 | U | | <15 | U | | 40 | | | <150 | U | | <28 | U | | <28 | U | |
| | | VMP-3-31.5-041411 | 4/14/2011 | <150 | U | | <410 | UJ | UJ | <200 | U | | <180 | U | | <280 | U | | <280 | U | | <120 | U | | <160 | U | | <1200 | U | | <230 | U | | <230 | U | |
| | | VMP-3-31.5-041411-DUP | 4/14/2011 | <150 | U | | <410 | UJ | UJ | <200 | U | | <180 | U | | <280 | U | | <280 | U | | <120 | U | | <160 | U | | <1200 | U | | <230 | U | | <230 | U | |
| | | VMP-3-31.5-080211 | 8/2/2011 | <340 | U | | <920 | U | | <460 | U | | <400 | U | | <640 | U | | 1100 | | | <280 | U | | <350 | U | | <2800 | U | | <510 | U | | <510 | U | |
| | | VMP-3-31.5-080211-Dup | 8/2/2011 | <200 | U | | <540 | U | | <270 | U | | <230 | U | | <380 | U | | <370 | U | | <160 | U | | <210 | U | | <1600 | U | | <300 | U | | <300 | U | |
| | | VMP-3-31.5-110811 | 11/8/2011 | <7.9 | U | | <22 | U | | <11 | U | | <9.3 | U | | <15 | U | | <15 | U | | <6.4 | U | | 23 | | | <65 | U | | <12 | U | | <12 | U | |
| | | VMP-3-31.5-012712 | 1/27/2012 | <50 | U | | <140 | U | | <68 | U | | <59 | U | | <95 | U | | <94 | U | | <41 | U | | <52 | U | | <410 | U | | <76 | U | | <76 | U | |
| | | VMP-3-31.5-041912 | 4/19/2012 | <86 | U | | <230 | U | | <120 | U | | <100 | U | | <160 | U | | <160 | U | | <70 | U | | <90 | U | | <710 | U | | <130 | U | | <130 | U | |
| | | VMP-3-31.5-041912-Dup | 4/19/2012 | <82 | U | | <220 | U | | <110 | U | | <98 | U | | <160 | U | | <160 | U | | <68 | U | | <86 | U | | <680 | U | | <120 | U | | <120 | U | |
| | | VMP-3-31.5-072312 | 7/23/2012 | <21 | U | | <56 | U | | <28 | U | | <24 | U | | <39 | U | | <39 | U | | <17 | U | | <22 | U | | <170 | U | | <31 | U | | <31 | U | |
| | | VMP-3-31.5-101912 | 10/19/2012 | <1.6 | U | | <4.5 | U | | <2.3 | U | | <2 | U | | <3.2 | U | | <3.1 | U | | <1.4 | U | | 0.3 | J | | <14 | U | | <2.5 | U | | <2.5 | U | |
| | | VMP-3-31.5-020713 | 2/7/2013 | <9.3 | U | | <25 | U | | <13 | U | | <11 | U | | <18 | U | | <18 | U | | <7.6 | U | | <9.7 | U | | <76 | U | | <14 | U | | <14 | U | |
| | 39.5 ft | VMP-3-39-101912 | 10/19/2012 | <160 | U | | <450 | U | | <230 | U | | <200 | U | | <320 | U | | <310 | U | | <140 | U | | 23 | J | | <1400 | U | | <250 | U | | <250 | U | |
| | | VMP-3-39-021213 | 2/12/2013 | <48 | U | | <130 | U | | <65 | U | | <56 | U | | <91 | U | | <90 | U | | <39 | U | | <50 | U | | <390 | U | | <72 | U | | <72 | U | |
| VMP-4 | 5 ft | VMP-4-5-082510 | 8/25/2010 | <0.26 | U | | <0.71 | U | | 0.058 | J | | <0.31 | U | | <0.49 | U | | <0.49 | U | | <0.21 | U | | <0.27 | U | | <2.1 | U | | <0.39 | U | | <0.39 | U | |
| | | VMP-4-5-112210 | 11/22/2010 | <9.7 | U | | <26 | U | | 8.4 | J | | <11 | U | | <18 | U | | <18 | U | | <7.9 | U | | 2.8 | J | | <80 | U | | <15 | U | | <15 | U | |
| | | VMP-4-5-021411 | 2/14/2011 | <0.57 | U | | <1.5 | U | | <0.77 | U | | <0.67 | U | | <1.1 | U | | <1.1 | U | | <0.46 | U | | 0.49 | J | | <4.7 | U | | <0.86 | U | | <0.86 | U | |
| | | VMP-4-5-041911 | 4/19/2011 | <26 | U | | <71 | UJ | UJ | <36 | U | | <31 | U | | <50 | U | | <49 | U | | <21 | U | | <27 | U | | <220 | U | | <40 | U | | <40 | U | |
| | | VMP-4-5-080311 | 8/3/2011 | <0.056 | U | | 0.044 | J | | <0.076 | U | | <0.066 | U | | <0.11 | U | | <0.1 | U | | <0.046 | U | | 0.03 | J | | <0.46 | U | | <0.085 | U | | <0.085 | U | |
| | | VMP-4-5-110911 | 11/9/2011 | <0.0031 | U | | 0.012 | | | 0.00081 | J | | <0.0036 | U | | <0.0059 | U | | <0.0058 | U | | 0.00057 | J | | 0.0059 | | | <0.025 | U | | <0.0047 | U | | <0.0047 | U | |
| | | VMP-4-5-013012 | 1/30/2012 | <0.16 | U | | 0.044 | J | J | <0.22 | U | | <0.19 | U | | <0.3 | U | | <0.3 | U | | <0.13 | U | | 0.059 | J | J | <1.3 | U | | <0.24 | U | | <0.24 | U | |
| | | VMP-4-5-042512 | 4/25/2012 | <0.0039 | U | | 0.035 | | | <0.0053 | J | U | 0.0027 | J | | <0.0074 | U | | <0.0074 | J | U | <0.0032 | U | | 0.039 | | | <0.032 | U | | <0.0059 | U | | <0.0059 | U | |
| | | VMP-4-5-072512 | 7/25/2012 | <0.0038 | U | | 0.11 | | | 0.0024 | J | | 0.0051 | | | <0.0073 | U | | 0.0024 | J | | 0.0027 | J | | 0.12 | | | <0.032 | U | | <0.0058 | U | | <0.0058 | U | |
| | | VMP-4-5-101812 | 10/18/2012 | <0.0056 | U | | 0.01 | J | | <0.0076 | U | | <0.0066 | U | | <0.011 | U | | <0.01 | U | | <0.0046 | U | | 0.0062 | | | <0.12 | U | UJ | <0.0085 | U | | <0.0085 | U | |
| | | VMP-4-5-020713 | 2/7/2013 | <0.0044 | U | | 0.0043 | J | | <0.0061 | J | U | <0.0053 | U | | <0.0085 | U | | <0.0084 | U | | <0.0036 | U | | 0.0016 | J | | <0.037 | U | | <0.0067 | U | | <0.0067 | U | |
| | 12 ft | VMP-4-12-082510 | 8/25/2010 | <4.5 | U | | <12 | U | | 4.2 | J | | <5.4 | U | | <8.6 | U | | <8.5 | U | | <3.7 | U | | <4.7 | U | | <37 | U | | <6.9 | U | | <6.9 | U | |
| | | VMP-4-12-112310 | 11/23/2010 | <4.6 | U | | <13 | U | | <6.3 | U | | <5.5 | U | | <8.8 | U | | <8.8 | U | | <3.8 | U | | <4.9 | U | | <38 | U | | <7 | U | | <7 | U | |
| | | VMP-4-12-021411 | 2/14/2011 | <1.2 | U | | <3.2 | U | | <1.6 | U | | <1.4 | U | | <2.2 | U | | <2.2 | U | | <0.96 | U | | 1.1 | J | | <9.6 | U | | <1.8 | U | | <1.8 | U | |
| | | VMP-4-12-041911 | 4/19/2011 | <22 | U | | <61 | UJ | UJ | <31 | U | | <27 | U | | <43 | U | | <42 | U | | <18 | U | | 20 | J | | <180 | U | | <34 | U | | <34 | U | |
| | | VMP-4-12-080311 | 8/3/2011 | <2.6 | U | | <7.1 | U | | <3.5 | U | | <3.1 | U | | <4.9 | U | | <4.9 | U | | <2.1 | U | | <2.7 | U | | <21 | U | | <3.9 | U | | <3.9 | U | |
| | | VMP-4-12-080311-Dup | 8/3/2011 | <5.2 | U | | <14 | U | | <7.1 | U | | <6.2 | U | | <9.9 | U | | <9.8 | U | | <4.3 | U | | <5.4 | U | | <43 | U | | <7.9 | U | | <7.9 | U | |
| | | VMP-4-12-110911 | 11/9/2011 | <0.79 | U | | <2.2 | U | | <1.1 | U | | <0.93 | U | | <1.5 | U | | <1.5 | U | | <0.64 | U | | <0.82 | U | | <6.5 | U | | <1.2 | U | | <1.2 | U | |
| | | VMP-4-12-013012 | 1/30/2012 | <1.6 | U | | <4.4 | U | | <2.2 | U | | <1.9 | U | | <3.1 | U | | <3 | U | | <1.3 | U | | 3.2 | | | <13 | U | | <2.4 | U | | <2.4 | U | |
| | | VMP-4-12-041812 | 4/18/2012 | <0.0036 | U | | 0.075 | | | 0.0011 | J | | 0.0014 | J | | <0.0069 | U | | 0.011 | | | <0.003 | U | | 0.049 | | | <0.03 | U | | <0.0055 | U | | <0.0055 | U | |
| | | VMP-4-12-072312 | 7/23/2012 | <0.018 | U | | 0.014 | J | | 0.012 | J | | <0.021 | U | | <0.033 | U | | <0.033 | U | | <0.014 | U | | 0.17 | | | <0.14 | U | | <0.026 | U | | <0.026 | U | |
| | | VMP-4-12-101812 | 10/18/2012 | <0.0055 | U | | 0.0098 | J | | 0.00085 | J | | <0.0064 | U | | <0.01 | U | | <0.01 | U | | <0.0045 | U | | 0.031 | | | <0.11 | U | UJ | <0.0083 | U | | <0.0083 | U | |
| | | VMP-4-12-101812-Dup | 10/18/2012 | <0.0056 | U | | 0.004 | J | | 0.0011 | J | | <0.0066 | U | | <0.011 | U | | <0.01 | U | | <0.0046 | U | | 0.033 | | | <0.12 | U | UJ | <0.0085 | U | | <0.0085 | U | |
| | | VMP-4-12-020713 | 2/7/2013 | <0.0048 | U | | 0.0073 | J | | <0.0066 | J | U | <0.0057 | U | | <0.0092 | U | | <0.0091 | U | | <0.004 | U | | <0.0051 | J | U | <0.04 | U | | <0.0073 | U | | <0.0073 | U | |
| | | VMP-4-12-020713-DUP | 2/7/2013 | <0.005 | U | | 0.0054 | J | | <0.0068 | U | | <0.0059 | U | | <0.0095 | U | | <0.0094 | U | | <0.0041 | U | | <0.0052 | J | U | <0.041 | U | | <0.0075 | U | | <0.0075 | U | |
| | 23.5 ft | VMP - 4 - 23.5 - 083110 | 8/31/2010 | <5.2 | U | | <14 | U | | 69 | | J | <6.2 | U | | <9.9 | U | | <9.8 | U | | <4.3 | U | | 2000 | | J | <43 | U | | <7.9 | U | | <7.9 | U | |
| | | VMP-4-23.5-112310 | 11/23/2010 | <52 | U | | <140 | U | | 22 | J | | <62 | U | | <100 | U | | <99 | U | | <43 | U | | 1600 | | | <430 | U | | <79 | U | | <79 | U | |
| | | VMP-4-23.5-021411 | 2/14/2011 | <1.9 | U | | <5.2 | U | | <2.6 | U | | <2.2 | U | | <3.6 | U | | <3.6 | U | | <1.6 | U | | 600 | | J | <16 | U | | <2.9 | U | | <2.9 | U | |
| | | VMP-4-23.5-042011 | 4/20/2011 | <120 | U | | <330 | U | | <160 | U | | <1400 | U | | <230 | U | | <230 | U | | <99 | U | | 820 | | | <1000 | U | | <180 | U | | <180 | U | |
| | | VMP-4-23.5-042011-DUP | 4/20/2011 | <120 | U | | <330 | U | | <160 | U | | <1400 | U | | <230 | U | | <230 | U | | <99 | U | | 790 | | | <1000 | U | | <180 | U | | <180 | U | |
| | | VMP-4-23.5-080611 | 8/6/2011 | <5.1 | U | | <14 | U | | 7.6 | | | <6 | U | | <9.6 | U | | <9.5 | U | | <4.1 | U | | 390 | | | <42 | U | | <7.7 | U | | <7.7 | U | |
| | | VMP-4-23.5-110911 | 11/9/2011 | <15 | U | | <41 | U | | <21 | U | | <18 | U | | <29 | U | | <28 | U | | <12 | U | | 44 | | | <120 | U | | <23 | U | | <23 | U | |
| | | VMP-4-23.5-013012 | 1/30/2012 | <32 | U | | <88 | U | | <44 | U | | <38 | U | | <61 | U | | <61 | U | | <26 | U | | 580 | | J | <260 | U | | <49 | U | | <49 | U | |
| | | VMP-4-23.5-013012-DUP | 1/30/2012 | <22 | U | | <61 | U | | <31 | U | | <27 | U | | <43 | U | | <42 | U | | <18 | U | | 320 | | J | <180 | U | | <34 | U | | <34 | U | |
| | | VMP-4-23.5-041912 | 4/19/2012 | <7.1 | U | | 3.6 | J | | <9.6 | U | | <8.3 | U | | <13 | U | | <13 | U | | <5.8 | U | | 110 | | | <58 | U | | <11 | U | | <11 | U | |
| | | VMP-4-23.5-072312 | 7/23/2012 | <3.4 | U | | <9.2 | U | | 6 | | | <4 | U | | <6.4 | U | | <6.4 | U | | <2.8 | U | | 420 | | | <28 | U | | <5.1 | U | | <5.1 | U | |
| | | VMP-4-23.5-101812 | 10/18/2012 | <3.7 | U | | <10 | U | | <5.1 | U | | <4.4 | U | | <7.1 | U | | <7 | U | | <3 | U | | 6.6 | | | <30 | U | | <5.6 | U | | <5.6 | U | |
| | | VMP-4-23.5-020713 | 2/7/2013 | <1.2 | U | | <3.2 | U | | <1.6 | U | | <1.4 | U | | <2.3 | U | | <2.2 | U | | <0.97 | U | | 0.27 | J | | <9.8 | U | | <1.8 | U | | <1.8 | U | |
| | 39 ft | VMP-4-39-042111 | 4/21/2011 | <150 | U | | <410 | U | | <210 | U | | <1800 | U | | <290 | U | | <280 | U | | <120 | U | | 440 | | | <1200 | U | | <230 | U | | <230 | U | |
| | | VMP-4-39-041912 | 4/19/2012 | <3.6 | U | | <9.9 | U | | 4.4 | J | | <4.3 | U | | <6.9 | U | | <6.8 | U | | <3 | U | | 200 | | | <30 | U | | <5.5 | U | | <5.5 | U | |
| | | VMP-4-39-072312 | 7/23/2012 | <5.4 | U | | <15 | U | | 8.3 | | J | <6.4 | U | | <10 | U | | <10 | U | | <4.4 | U | | 590 | | J | <45 | U | | <8.2 | U | | <8.2 | U | |
| | | VMP-4-39-101812 | 10/18/2012 | <68 | U | | <190 | U | | <93 | U | | <81 | U | | <130 | U | | <130 | U | | <56 | U | | 480 | | | <560 | U | | <100 | U | | <100 | U | |
| | | VMP-4-39-101812-Dup | 10/18/2012 | <62 | U | | <170 | U | | <85 | U | | <73 | U | | <120 | U | | <120 | U | | <51 | U | | 480 | | | <510 | U | | <94 | U | | <94 | U | |
| | | VMP-4-39-020713 | 2/7/2013 | <9.7 | U | | <26 | U | | 3 | J | | <11 | U | | <18 | U | | <18 | U | | <7.9 | U | | 610 | | | <80 | U | | <15 | U | | <15 | U | |

SEE LAST PAGE OF TABLE FOR NOTES

**TABLE 5**
**CUMULATIVE SUMMARY OF SOIL VAPOR ANALYTICAL DETECTIONS AND SCREENING RESULTS: VILLAGE - VOCS**

| Location | Depth | Sample ID | Sample Date | Methyl tert-Butyl Ether (MTBE) 3400 | | | 2-Propanol | | | n-Propylbenzene | | | Styrene 1400 | | | 1,1,2,2-Tetrachloroethane | | | Tetrachloroethene 0.55 | | | Tetrahydrofuran | | | Toluene 6200 | | | 1,2,4-Trichlorobenzene 11 | | | 1,1,1-Trichloroethane (Methyl chloroform) 6600 | | | 1,1,2-Trichloroethane 170000 | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals |
| VMP-5 | 5 ft | VMP-5-5-090910 | 9/9/2010 | <9.5 | U | | <26 | U | | 4.8 | J | | <11 | U | | <18 | U | | <18 | U | | <7.8 | U | | <9.9 | U | | <78 | U | | <14 | U | | <14 | U | |
| | | VMP-5-5-112210 | 11/22/2010 | <2.3 | U | | <6.3 | U | | <3.2 | U | | <2.7 | U | | <4.4 | U | | <4.4 | U | | <1.9 | U | | <2.4 | U | | <19 | U | | <3.5 | U | | <3.5 | U | |
| | | VMP-5-5-021611 | 2/16/2011 | <0.015 | U | | 0.3 | | J | <0.02 | U | | <0.018 | U | | <0.028 | U | | <0.028 | U | | <0.012 | U | | 0.0078 | J | J | <0.12 | U | | <0.022 | U | | <0.022 | U | |
| | | VMP-5-5-042111 | 4/21/2011 | <0.048 | U | | <0.13 | U | | <0.065 | U | | <0.56 | U | | <0.091 | U | | 0.078 | J | | <0.039 | U | | <0.05 | U | | <0.39 | U | | <0.072 | U | | <0.072 | U | |
| | | VMP-5-5-080511 | 8/5/2011 | <0.0045 | U | | 0.07 | | | 0.00075 | J | | 0.0024 | J | | <0.0086 | U | | 0.0031 | J | | <0.0037 | U | | 1.3 | | | <0.037 | U | | <0.0069 | J | U | <0.0069 | U | |
| | | VMP-5-5-111111 | 11/11/2011 | <0.0034 | U | | 0.014 | | | 0.018 | | | <0.004 | U | | <0.0064 | U | | <0.0063 | U | | <0.0027 | U | | 0.0096 | | | <0.028 | U | | <0.0051 | U | | <0.0051 | U | |
| | | VMP-5-5-013012 | 1/30/2012 | <0.034 | U | | 0.25 | | | 0.007 | J | | 0.0053 | J | | <0.064 | U | | <0.063 | U | | <0.028 | U | | 0.071 | | | <0.28 | U | | <0.051 | U | | <0.051 | U | |
| | | VMP-5-5-041112 | 4/11/2012 | <0.0033 | U | | 0.057 | | | 0.00078 | J | | 0.0011 | J | | <0.0063 | U | | 0.0021 | J | | 0.02 | | | 0.022 | | | <0.027 | U | | <0.005 | U | | <0.005 | U | |
| | | VMP-5-5-071312 | 7/13/2012 | <0.0036 | U | | 0.54 | | | <0.005 | U | | <0.0043 | U | | <0.007 | U | | <0.0069 | J | U | <0.003 | U | | 0.0038 | | | <0.03 | U | | <0.0055 | U | | <0.0055 | U | |
| | | VMP-5-5-101212 | 10/12/2012 | <0.0045 | U | | <0.012 | U | | <0.0062 | U | | <0.0054 | U | | <0.0086 | U | | <0.0085 | U | | <0.0037 | U | | 0.002 | J | | <0.037 | U | | <0.0069 | U | | <0.0069 | U | |
| | | VMP-5-5-012513 | 1/25/2013 | <0.0048 | U | | 0.2 | | | <0.0065 | U | | <0.0056 | U | | <0.0091 | U | | <0.009 | U | | <0.0039 | U | UJ | <0.005 | U | | <0.039 | U | UJ | <0.0072 | U | | <0.0072 | U | |
| | 12.5 ft | VMP-5-12.5-090910 | 9/9/2010 | <4.8 | U | | <13 | U | | 2.1 | J | | <5.6 | U | | <9.1 | U | | <9 | U | | <3.9 | U | | <5 | U | | <39 | U | | <7.2 | U | | <7.2 | U | |
| | | VMP-5-12.5-112310 | 11/23/2010 | <0.24 | U | | <0.65 | U | | <0.32 | U | | <0.28 | U | | <0.45 | U | | <0.45 | U | | <0.19 | U | | 0.5 | | | <2 | U | | <0.36 | U | | <0.36 | U | |
| | | VMP-5-12.5-021611 | 2/16/2011 | <0.72 | U | | <2 | U | | <0.98 | U | | <0.84 | U | | <1.4 | U | | <1.3 | U | | <0.58 | U | | <0.75 | U | | <5.9 | U | | <1.1 | U | | <1.1 | U | |
| | | VMP-5-12.5-042111 | 4/21/2011 | <0.051 | U | | <0.14 | U | | <0.069 | U | | <0.6 | U | | <0.097 | U | | <0.096 | U | | <0.042 | U | | <0.053 | U | | <0.42 | U | | <0.077 | U | | <0.077 | U | |
| | | VMP-5-12.5-080611 | 8/6/2011 | <4.5 | U | | <12 | U | | <6.1 | U | | <5.3 | U | | <8.5 | U | | <8.4 | U | | <3.6 | U | | 1 | J | | <37 | U | | <6.8 | U | | <6.8 | U | |
| | | VMP-5-12.5-111111 | 11/11/2011 | <0.0032 | U | | 0.0091 | | | 0.00082 | J | | <0.0037 | U | | <0.006 | U | | <0.006 | U | | <0.0026 | U | | 0.0094 | | | <0.026 | U | | <0.0048 | U | | <0.0048 | U | |
| | | VMP-5-12.5-013012 | 1/30/2012 | <0.01 | U | | 0.032 | | | <0.014 | J | U | <0.012 | U | | <0.02 | U | | <0.019 | U | | <0.0085 | U | | 0.016 | | | <0.085 | U | | <0.016 | U | | <0.016 | U | |
| | | VMP-5-12.5-041112 | 4/11/2012 | <0.0032 | U | | 0.049 | | | 0.00051 | J | | 0.0016 | J | | <0.006 | U | | 0.0023 | J | | 0.0055 | | | 0.025 | | | <0.026 | U | | <0.0048 | U | | <0.0048 | U | |
| | | VMP-5-12.5-071212 | 7/12/2012 | <0.0037 | U | | 0.01 | | | 0.0033 | J | | <0.0044 | J | U | <0.0071 | U | | <0.007 | U | | <0.003 | U | | 0.0039 | | | <0.03 | U | | <0.0056 | U | | <0.0056 | U | |
| | | VMP-5-12.5-101112 | 10/11/2012 | <0.0088 | U | | 0.012 | J | | <0.012 | U | | <0.01 | U | | <0.017 | U | | 0.0018 | J | | <0.0072 | U | | 0.0054 | J | | <0.072 | U | | <0.013 | U | | <0.013 | U | |
| | | VMP-5-12.5-012413 | 1/24/2013 | <0.0046 | U | | 0.27 | | | <0.0063 | U | | <0.0055 | U | | <0.0088 | U | | <0.0088 | U | | <0.0038 | U | UJ | 0.00074 | J | | <0.038 | U | UJ | <0.007 | U | | <0.007 | U | |
| | 31 ft | VMP-5-31-090910 | 9/9/2010 | <20 | U | | <54 | U | | <27 | U | | <23 | U | | <38 | U | | <37 | U | | <16 | U | | 4.3 | J | | <160 | U | | <30 | U | | <30 | U | |
| | | VMP-5-31-112310 | 11/23/2010 | <12 | U | | <34 | U | | <17 | U | | <15 | U | | <24 | U | | <23 | U | | <10 | U | | 8.2 | J | | <100 | U | | <19 | U | | <19 | U | |
| | | VMP-5-31-021611 | 2/16/2011 | <5 | U | | <14 | U | | <6.8 | U | | <5.9 | U | | <9.5 | U | | <9.4 | U | | <4.1 | U | | 2.5 | J | | <41 | U | | <7.5 | U | | <7.5 | U | |
| | | VMP-5-31-042111 | 4/21/2011 | <74 | U | | <200 | U | | <100 | U | | <880 | U | | <140 | U | | <140 | U | | <61 | U | | <78 | U | | <610 | U | | <110 | U | | <110 | U | |
| | | VMP-5-31-080611 | 8/6/2011 | <42 | U | | 34 | J | | <57 | U | | <49 | U | | <80 | U | | <79 | U | | <34 | U | | <44 | U | | <340 | U | | <63 | U | | <63 | U | |
| | | VMP-5-31-111111 | 11/11/2011 | <21 | U | | <58 | U | | <29 | U | | <25 | U | | <40 | U | | <40 | U | | <17 | U | | 14 | J | | <170 | U | | <32 | U | | <32 | U | |
| | | VMP-5-31-013012 | 1/30/2012 | <11 | U | | <29 | U | | <15 | U | | <13 | U | | <20 | U | | <20 | U | | <8.8 | U | | <11 | U | | <89 | U | | <16 | U | | <16 | U | |
| | | VMP-5-31-041112 | 4/11/2012 | <0.034 | U | | 0.031 | J | | <0.047 | U | | <0.041 | U | | <0.066 | U | | <0.065 | U | | <0.028 | U | | 0.039 | | | <0.28 | U | | <0.052 | U | | <0.052 | U | |
| | | VMP-5-31-071212 | 7/12/2012 | <0.0036 | U | | 0.015 | | | <0.0049 | J | U | <0.0043 | U | | <0.0069 | U | | <0.0068 | U | | <0.003 | U | | 0.0082 | | | <0.03 | U | | <0.0055 | U | | <0.0055 | U | |
| | | VMP-5-31-101112 | 10/11/2012 | <0.0051 | U | | 0.0027 | J | | <0.0069 | U | | <0.006 | U | | <0.0097 | U | | <0.0096 | U | | <0.0042 | U | | 0.0042 | J | | <0.042 | U | | <0.0077 | U | | <0.0077 | U | |
| | | VMP-5-31-012413 | 1/24/2013 | <0.05 | U | | 7.5 | | | <0.069 | U | | <0.06 | U | | <0.096 | U | | <0.095 | U | | <0.041 | U | | <0.053 | U | | <0.42 | U | UJ | <0.076 | U | | <0.076 | U | |
| | 40 ft | VMP-5-40-042111 | 4/21/2011 | <78 | U | | <210 | U | | <100 | U | | <920 | U | | <150 | U | | <150 | U | | <64 | U | | <81 | U | | <640 | U | | <120 | U | | <120 | U | |
| | | VMP-5-40-013012 | 1/30/2012 | <22 | U | | <61 | U | | <31 | U | | <27 | U | | <43 | U | | <42 | U | | <18 | U | | <24 | U | | <180 | U | | <34 | U | | <34 | U | |
| | | VMP-5-40-041212 | 4/12/2012 | <0.034 | U | | 0.088 | J | | <0.046 | U | | <0.04 | U | | <0.064 | U | | <0.063 | U | | <0.028 | U | | 0.092 | | | <0.28 | U | | <0.051 | U | | <0.051 | U | |
| | | VMP-5-40-071212 | 7/12/2012 | <0.036 | U | | <0.099 | U | | <0.049 | U | | <0.043 | U | | <0.069 | U | | <0.068 | U | | <0.03 | U | | <0.038 | U | | <0.3 | U | | <0.055 | U | | <0.055 | U | |
| | | VMP-5-40-101112 | 10/11/2012 | <0.0053 | U | | 0.0081 | J | | <0.0073 | U | | <0.0063 | U | | <0.01 | U | | 0.0016 | J | | <0.0044 | U | | 0.0046 | J | | <0.044 | U | | <0.0081 | U | | <0.0081 | U | |
| | | VMP-5-40-012513 | 1/25/2013 | <0.016 | U | | 1.9 | | | <0.021 | U | | <0.018 | U | | <0.03 | U | | <0.029 | U | | <0.013 | U | | <0.016 | U | | <0.13 | U | | <0.023 | U | | <0.023 | U | |
| | | VMP-5-40-012513-Dup | 1/25/2013 | <0.015 | U | | 2 | | | <0.021 | U | | <0.018 | U | | <0.029 | U | | <0.028 | U | | <0.012 | U | | <0.016 | U | | <0.12 | U | | <0.023 | U | | <0.023 | U | |
| VMP-6 | 5 ft | VMP-6-5-090810 | 9/8/2010 | <0.79 | U | | <2.2 | U | | <1.1 | U | | <0.94 | U | | <1.5 | U | | <1.5 | U | | <0.65 | U | | <0.83 | U | | <6.5 | U | | <1.2 | U | | <1.2 | U | |
| | | VMP-6-5-111610 | 11/16/2010 | <5 | U | | <14 | U | | 7.7 | | | <5.9 | U | | <9.5 | U | | <9.4 | U | | <4.1 | U | | <5.2 | U | | <41 | U | | <7.5 | U | | <7.5 | U | |
| | | VMP-6-5-020711 | 2/7/2011 | <0.0043 | U | | 0.027 | | | 0.0034 | J | | <0.0051 | U | | <0.0082 | U | | <0.0081 | U | | <0.0035 | U | | 0.015 | | | <0.035 | J | U | <0.0065 | U | | <0.0065 | U | |
| | | VMP-6-5-040811 | 4/8/2011 | <0.0093 | U | | 0.054 | | | <0.013 | U | | <0.011 | U | | <0.018 | U | | <0.018 | U | | <0.0076 | U | | 0.0037 | J | | <0.077 | U | | <0.014 | U | | <0.014 | U | |
| | | VMP-6-5-080411 | 8/4/2011 | <0.24 | U | | <0.66 | U | | <0.33 | U | | <0.28 | U | | <0.46 | U | | <0.45 | U | | <0.2 | U | | 0.53 | | | <2 | U | | <0.36 | U | | <0.36 | U | |
| | | VMP-6-5-110911 | 11/9/2011 | <0.0029 | U | | 0.13 | | | 0.018 | | | 0.00069 | J | | <0.0055 | U | | <0.0055 | U | | <0.0024 | U | | 0.026 | | | <0.024 | U | | <0.0044 | U | | <0.0044 | U | |
| | | VMP-6-5-013112 | 1/31/2012 | <0.034 | U | | 0.082 | J | | 0.0034 | J | | <0.04 | U | | <0.065 | U | | <0.064 | U | | <0.028 | U | | 0.054 | | | <0.28 | U | | <0.052 | U | | <0.052 | U | |
| | | VMP-6-5-041212 | 4/12/2012 | <0.0036 | U | | 0.015 | | | <0.0049 | U | | 0.00098 | J | | <0.0069 | U | | <0.0068 | J | U | <0.003 | J | U | 0.013 | | | <0.03 | U | | <0.0055 | U | | <0.0055 | U | |
| | | VMP-6-5-071612 | 7/16/2012 | <0.0036 | U | | 0.0098 | | | <0.0049 | J | U | <0.0043 | U | | <0.0069 | U | | <0.0068 | U | | 0.0015 | J | | 0.0045 | | | <0.03 | U | | <0.0055 | U | | <0.0055 | U | |
| | | VMP-6-5-101012 | 10/10/2012 | <0.005 | U | | 0.012 | J | | <0.0068 | U | | <0.0059 | U | | <0.0095 | U | | <0.0094 | U | | <0.0041 | U | | 0.00077 | J | | <0.041 | U | | <0.0075 | U | | <0.0075 | U | |
| | | VMP-6-5-021213 | 2/12/2013 | <0.0044 | U | | 0.0073 | J | | <0.0061 | U | | <0.0053 | U | | <0.0085 | U | | <0.0084 | U | | <0.0036 | U | | <0.0046 | J | U | <0.037 | U | | <0.0067 | U | | <0.0067 | U | |
| | 10 ft | VMP-6-10-090810 | 9/8/2010 | <0.86 | U | | <2.3 | U | | 0.73 | J | J | <1 | U | | <1.6 | U | | <1.6 | U | | <0.7 | U | | <0.9 | U | | <7.1 | U | | <1.3 | U | | <1.3 | U | |
| | | VMP-6-10-111710 | 11/17/2010 | 0.00056 | J | | 0.0073 | J | | <0.0063 | U | | 0.0022 | J | | <0.0088 | U | | 0.0081 | J | | <0.0038 | U | | 0.001 | J | | <0.038 | U | | 0.0014 | J | | <0.007 | U | |
| | | VMP-6-10-020711 | 2/7/2011 | <0.0045 | U | | 0.0045 | J | | <0.0062 | J | U | <0.0054 | U | | <0.0086 | U | | 0.0013 | J | | <0.0037 | U | | 0.0029 | J | | <0.037 | J | U | <0.0069 | U | | <0.0069 | U | |
| | | VMP-6-10-040811 | 4/8/2011 | <0.11 | U | | 0.53 | | | <0.15 | U | | 0.093 | J | | <0.21 | U | | <0.2 | U | | 0.15 | | | 0.043 | J | | <0.9 | U | | <0.16 | U | | <0.16 | U | |
| | | VMP-6-10-080411 | 8/4/2011 | <0.77 | U | | <2.1 | U | | <1 | U | | <0.91 | U | | <1.5 | U | | <1.4 | U | | <0.63 | U | | 0.26 | J | | <6.4 | U | | <1.2 | U | | <1.2 | U | |
| | | VMP-6-10-111011 | 11/10/2011 | <0.003 | U | | 0.19 | | | <0.0041 | U | | <0.0036 | U | | <0.0058 | U | | <0.0057 | U | | <0.0025 | U | | 0.0052 | | | <0.025 | U | | <0.0046 | U | | <0.0046 | U | |
| | | VMP-6-10-013112 | 1/31/2012 | <0.54 | U | | <1.5 | U | | <0.73 | U | | <0.63 | U | | <1 | U | | <1 | U | | <0.44 | U | | <0.56 | U | | <4.4 | U | | <0.81 | U | | <0.81 | U | |
| | | VMP-6-10-041212 | 4/12/2012 | <0.0035 | U | | 0.015 | | | <0.0048 | J | U | <0.0042 | U | | <0.0067 | U | | <0.0066 | J | U | <0.0029 | U | | 0.019 | | | <0.029 | U | | <0.0053 | U | | <0.0053 | U | |
| | | VMP-6-10-071612 | 7/16/2012 | <0.0048 | U | | 0.013 | J | | <0.0065 | J | U | <0.0056 | U | | <0.0091 | U | | <0.009 | J | U | <0.0039 | J | U | 0.0051 | | | <0.039 | U | | <0.0072 | J | U | <0.0072 | U | |
| | | VMP-6-10-101112 | 10/11/2012 | <0.0052 | U | | 0.0037 | J | | <0.0071 | U | | <0.0062 | U | | <0.0099 | U | | <0.0098 | U | | <0.0043 | U | | 0.0027 | J | | <0.043 | U | | <0.0079 | U | | <0.0079 | U | |
| | | VMP-6-10-020513 | 2/5/2013 | <0.005 | U | | 0.01 | J | | <0.0068 | U | | <0.0059 | U | | <0.0095 | U | | <0.0094 | J | U | <0.0041 | U | | <0.0052 | J | U | <0.041 | J | U | <0.0075 | U | | <0.0075 | U | |
| | 31.5 ft | VMP-6-31.5-090810 | 9/8/2010 | <5.8 | U | | 4 | J | | 42 | | | <6.8 | U | | <11 | U | | <11 | U | | <4.7 | U | | <6.1 | U | | <48 | U | | <8.8 | U | | <8.8 | U | |
| | | VMP-6-31.5-111710 | 11/17/20010 | <9.1 | U | | <25 | U | | 43 | | | <11 | U | | <17 | U | | <17 | U | | <7.4 | U | | <9.5 | U | | <75 | U | | <14 | U | | <14 | U | |
| | | VMP-6-31.5-020711 | 2/7/2011 | <8.7 | U | | 4.7 | J | | 75 | | | <10 | U | | <17 | U | | <16 | U | | <7.1 | U | | 2.8 | J | | <72 | U | | <13 | U | | <13 | U | |
| | | VMP-6-31.5-041111 | 4/11/2011 | <6.8 | U | | 13 | J | | 27 | | | 3 | J | | <13 | U | | 1 | J | | <5.5 | U | | 1.4 | J | | <56 | U | | <10 | U | | <10 | U | |
| | | VMP-6-31.5-080411 | 8/4/2011 | <5 | U | | <14 | U | | 3.1 | J | | <5.9 | U | | <9.5 | U | | <9.4 | U | | <4.1 | U | | 1.5 | J | | <41 | U | | <7.6 | U | | <7.6 | U | |
| | | VMP-6-31.5-111011 | 11/10/2011 | <7.7 | U | | <21 | U | | <10 | U | | <9.1 | U | | <15 | U | | <14 | U | | <6.3 | U | | 20 | | | <64 | U | | <12 | U | | <12 | U | |
| | | VMP-6-31.5-013112 | 1/31/2012 | <3.1 | U | | <8.4 | U | | 1.2 | J | J | <3.6 | U | | <5.9 | U | | <5.8 | U | | <2.5 | U | | <3.2 | U | | <25 | U | | <4.7 | U | | <4.7 | U | |
| | | VMP-6-31.5-041212 | 4/12/2012 | <0.41 | U | | 0.098 | J | | 0.27 | J | | <0.49 | U | | <0.79 | U | | <0.78 | U | | <0.34 | U | | 0.47 | | | <3.4 | U | | <0.62 | U | | <0.62 | U | |
| | | VMP-6-31.5-071612 | 7/16/2012 | <0.0065 | U | | 0.078 | | | <0.0089 | J | U | <0.0077 | U | | <0.012 | U | | 0.0074 | J | | <0.0053 | U | | 0.029 | | | <0.054 | U | | <0.0099 | U | | <0.0099 | U | |
| | | VMP-6-31.5-101112 | 10/11/2012 | <0.0051 | U | | 0.0059 | J | | <0.0069 | U | | <0.006 | U | | <0.0097 | U | | <0.0096 | U | | <0.0042 | U | | 0.0016 | J | | <0.042 | U | | <0.0077 | U | | <0.0077 | U | |
| | | VMP-6-31.5-020513 | 2/5/2013 | <0.0046 | U | | 0.11 | | | <0.0063 | U | | <0.0055 | U | | <0.0088 | U | | <0.0088 | J | U | <0.0038 | U | | <0.0049 | J | U | <0.038 | U | | <0.007 | U | | <0.007 | U | |
| | 39 ft | VMP-6-39-041111 | 4/11/2011 | <8 | U | | 7.5 | J | | 30 | | | 2.6 | J | | <15 | U | | <15 | U | | <6.6 | U | | 2.3 | J | | <66 | U | | <12 | U | | <12 | U | |
| | | VMP-6-39-013112 | 1/31/2012 | <3.1 | U | | <8.4 | U | | 1.7 | J | J | <3.6 | U | | <5.9 | U | | <5.8 | U | | <2.5 | U | | <3.2 | U | | <25 | U | | <4.7 | U | | <4.7 | U | |
| | | VMP-6-39-041212 | 4/12/2012 | <0.3 | U | | <0.82 | U | | 1 | | | <0.36 | U | | <0.58 | U | | <0.57 | U | | <0.25 | U | | 0.17 | J | | <2.5 | U | | <0.46 | U | | <0.46 | U | |
| | | VMP-6-39-071612 | 7/16/2012 | <0.014 | U | | 0.011 | J | | <0.019 | U | | <0.017 | U | | <0.027 | U | | <0.027 | U | | <0.012 | U | | 0.0092 | J | | <0.12 | U | | <0.021 | U | | <0.021 | U | |
| | | VMP-6-39-071612-Dup | 7/16/2012 | <0.014 | U | | 0.0071 | J | | <0.02 | U | | <0.017 | U | | <0.027 | U | | <0.027 | U | | <0.012 | U | | 0.0067 | J | | <0.12 | U | | <0.022 | U | | <0.022 | U | |
| | | VMP-6-39-101112 | 10/11/2012 | <0.0097 | U | | 0.0071 | J | | <0.013 | U | | <0.011 | U | | <0.018 | U | | <0.018 | U | | <0.0079 | U | | 0.0035 | J | | <0.08 | U | | <0.015 | U | | <0.015 | U | |
| | | VMP-6-39-020513 | 2/5/2013 | <0.0048 | U | | 0.011 | J | | 0.012 | | | <0.0056 | U | | <0.0091 | U | | <0.009 | J | U | <0.0039 | U | | <0.005 | J | U | <0.039 | U | | <0.0072 | U | | <0.0072 | U | |

SEE LAST PAGE OF TABLE FOR NOTES

**TABLE 5**
**CUMULATIVE SUMMARY OF SOIL VAPOR ANALYTICAL DETECTIONS AND SCREENING RESULTS: VILLAGE - VOCS**

| Location | Depth | Sample ID | Sample Date | Methyl tert-Butyl Ether (MTBE) 3400 | | | 2-Propanol | | | n-Propylbenzene | | | Styrene 1400 | | | 1,1,2,2-Tetrachloroethane | | | Tetrachloroethene 0.55 | | | Tetrahydrofuran | | | Toluene 6200 | | | 1,2,4-Trichlorobenzene 11 | | | 1,1,1-Trichloroethane (Methyl chloroform) 6600 | | | 1,1,2-Trichloroethane 170000 | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals |
| VMP-7 | 5 ft | VMP-7-5-082610 | 8/26/2010 | <0.0048 | U | | 0.0064 | J | | <0.0065 | U | | <0.0056 | U | | <0.0091 | U | | <0.009 | U | | <0.0039 | U | | 0.0012 | J | | <0.039 | U | | <0.0072 | U | | <0.0072 | U | |
| | | VMP-7-5-111910 | 11/19/2010 | <0.0043 | U | | 0.0053 | J | | <0.0058 | U | | <0.0051 | U | | <0.0082 | U | | <0.0081 | U | | <0.0035 | U | | <0.0045 | U | | <0.035 | U | | <0.0065 | U | | <0.0065 | U | |
| | | VMP-7-5-020711 | 2/7/2011 | <0.0046 | U | | 0.0059 | J | | <0.0063 | U | | <0.0055 | U | | <0.0088 | U | | <0.0088 | U | | <0.0038 | U | | 0.001 | J | | <0.038 | J | U | <0.007 | U | | <0.007 | U | |
| | | VMP-7-5-040711 | 4/7/2011 | <0.0066 | U | | <0.018 | U | | <0.0089 | U | | <0.0078 | U | | <0.012 | U | | <0.012 | U | | <0.0054 | U | | 0.0025 | J | | <0.054 | U | | <0.0099 | U | | <0.0099 | U | |
| | | VMP-7-5-080211 | 8/2/2011 | <0.65 | U | | <1.8 | U | | <0.89 | U | | <0.77 | U | | <1.2 | U | | <1.2 | U | | <0.53 | U | | <0.68 | U | | <5.4 | U | | <0.98 | U | | <0.98 | U | |
| | | VMP-7-5-111011 | 11/10/2011 | <0.0031 | U | | 0.042 | | | <0.0042 | U | | <0.0036 | U | | <0.0059 | U | | <0.0058 | U | | <0.0025 | U | | 0.0037 | | | <0.025 | U | | <0.0047 | U | | <0.0047 | U | |
| | | VMP-7-5-111011-DUP | 11/10/2011 | <0.0029 | U | | 0.04 | | | <0.004 | U | | <0.0034 | U | | <0.0055 | U | | <0.0055 | U | | <0.0024 | U | | 0.0047 | | | <0.024 | U | | <0.0044 | U | | <0.0044 | U | |
| | | VMP-7-5-013112 | 1/31/2012 | <0.0032 | U | | 0.027 | | | <0.0043 | J | U | 0.00053 | J | | <0.006 | U | | <0.0059 | U | | 0.04 | | | 0.011 | | | <0.026 | U | | <0.0048 | U | | <0.0048 | U | |
| | | VMP-7-5-041212 | 4/12/2012 | <0.0034 | U | | 0.059 | | | <0.0047 | J | U | 0.0013 | J | | <0.0065 | U | | <0.0064 | J | U | 0.0062 | | | 0.027 | | | <0.028 | U | | <0.0052 | U | | <0.0052 | U | |
| | | VMP-7-5-073112 | 7/31/2012 | <0.0068 | U | | 0.05 | | | 0.00095 | J | | 0.0015 | J | | <0.017 | U | | <0.017 | U | | 0.0047 | J | | 0.1 | | | <0.073 | U | | <0.013 | U | | <0.013 | U | |
| | | VMP-7-5-101012 | 10/10/2012 | <0.0053 | U | | <0.014 | U | | <0.0073 | U | | <0.0063 | U | | <0.01 | U | | <0.01 | U | | <0.0044 | U | | 0.0011 | J | | <0.044 | U | | <0.0081 | U | | <0.0081 | U | |
| | 13.5 ft | VMP-7-13.5-082610 | 8/26/2010 | <0.1 | U | | <0.28 | U | | <0.14 | U | | <0.12 | U | | <0.2 | U | | <0.2 | U | | <0.085 | U | | <0.11 | U | | <0.86 | U | | <0.16 | U | | <0.16 | U | |
| | | VMP-7-13.5-111910 | 11/19/2010 | <0.73 | U | | <2 | U | | <0.99 | U | | <0.86 | U | | <1.4 | U | | <1.4 | U | | <0.59 | U | | <0.76 | U | | <6 | U | | <1.1 | U | | <1.1 | U | |
| | | VMP-7-13.5-020711 | 2/7/2011 | <0.0044 | U | | 0.0086 | J | | <0.0061 | U | | <0.0053 | U | | <0.0085 | U | | <0.0084 | U | | <0.0036 | U | | <0.0046 | U | | <0.037 | J | U | <0.0067 | U | | <0.0067 | U | |
| | | VMP-7-13.5-040711 | 4/7/2011 | <0.0078 | U | | <0.021 | U | | <0.011 | U | | <0.0092 | U | | <0.015 | U | | <0.015 | U | | <0.0064 | U | | 0.0016 | J | | <0.064 | U | | <0.012 | U | | <0.012 | U | |
| | | VMP-7-13.5-080311 | 8/3/2011 | <0.87 | U | | <2.4 | U | | <1.2 | U | | <1 | U | | <1.6 | U | | <1.6 | U | | <0.71 | U | | <0.91 | U | | <7.2 | U | | <1.3 | U | | <1.3 | U | |
| | | VMP-7-13.5-111011 | 11/10/2011 | <0.0028 | U | | 0.01 | | | 0.018 | | | <0.0034 | U | | <0.0054 | U | | <0.0054 | U | | <0.0023 | U | | 0.007 | | | <0.023 | U | | <0.0043 | U | | <0.0043 | U | |
| | | VMP-7-13.5-013112 | 1/31/2012 | <0.04 | U | | 0.11 | J | J | <0.055 | U | | <0.048 | U | | <0.077 | U | | <0.076 | U | | <0.033 | U | | 0.017 | J | J | <0.33 | U | | <0.061 | U | | <0.061 | U | |
| | | VMP-7-13.5-013112-DUP | 1/31/2012 | <0.041 | U | | 0.2 | | J | <0.056 | U | | <0.049 | U | | <0.079 | U | | <0.078 | U | | <0.034 | U | | <0.043 | U | | <0.34 | U | | <0.062 | U | | <0.062 | U | |
| | | VMP-7-13.5-041212 | 4/12/2012 | <0.0033 | U | | 0.018 | | | <0.0045 | U | | 0.00086 | J | | <0.0063 | U | | <0.0062 | J | U | 0.0064 | | J | 0.02 | | | <0.027 | U | | <0.005 | U | | <0.005 | U | |
| | | VMP-7-13.5-041212-DUP | 4/12/2012 | <0.0035 | U | | 0.016 | | | <0.0047 | U | | 0.0018 | J | | <0.0066 | U | | <0.0065 | J | U | 0.0052 | | J | 0.035 | | | <0.029 | U | | <0.0053 | U | | <0.0053 | U | |
| | | VMP-7-13.5-072012 | 7/20/2012 | <0.0034 | U | | 0.041 | | | 0.00059 | J | | 0.0012 | J | | <0.0064 | U | | <0.0063 | U | | 0.00095 | J | | 0.076 | | | <0.028 | U | | <0.0051 | U | | <0.0051 | U | |
| | | VMP-7-13.5-101012 | 10/10/2012 | <0.005 | U | | <0.014 | U | | <0.0068 | U | | <0.0059 | U | | <0.0095 | U | | <0.0094 | U | | <0.0041 | U | | 0.0011 | J | | <0.041 | U | | <0.0075 | U | | <0.0075 | U | |
| | | VMP-7-13.5-021313 | 2/13/2013 | <0.005 | U | | 0.0039 | J | | <0.0068 | U | | <0.0059 | U | | <0.0095 | U | | <0.0094 | U | | <0.0041 | U | | <0.0052 | J | U | <0.041 | J | U | <0.0075 | U | | <0.0075 | U | |
| | 29.5 ft | VMP-7-29.5-083110 | 8/31/2010 | <1.5 | U | | <4 | U | | 5 | | J | <1.8 | U | | <2.8 | U | | <2.8 | U | | <1.2 | U | | 1 | J | J | <12 | U | | <2.2 | U | | <2.2 | U | |
| | | VMP-7-29.5-111910 | 11/19/2010 | <2.2 | U | | <6.1 | U | | 3.9 | | J | <2.6 | U | | <4.2 | U | | <4.2 | U | | <1.8 | U | | <2.3 | U | | <18 | U | | <3.4 | U | | <3.4 | U | |
| | | VMP-7-29.5-020711 | 2/7/2011 | <2.3 | U | | <6.3 | U | | 9.8 | | | <2.7 | U | | <4.4 | U | | <4.4 | U | | <1.9 | U | | <2.4 | U | | <19 | U | | <3.5 | U | | <3.5 | U | |
| | | VMP-7-29.5-040711 | 4/7/2011 | <0.56 | U | | <1.5 | U | | 2.5 | | J | <0.67 | U | | <1.1 | U | | <1.1 | U | | <0.46 | U | | <0.59 | U | | <4.6 | U | | <0.85 | U | | <0.85 | U | |
| | | VMP-7-29.5-080311 | 8/3/2011 | <1.3 | U | | <3.6 | U | | 1.1 | J | | <1.6 | U | | <2.5 | U | | <2.5 | U | | <1.1 | U | | <1.4 | U | | <11 | U | | <2 | U | | <2 | U | |
| | | VMP-7-29.5-111111 | 11/11/2011 | <2.6 | U | | 3.2 | J | | 0.84 | J | | 0.62 | J | | <5 | U | | <4.9 | U | | <2.1 | U | | 16 | | | <22 | U | | <4 | U | | <4 | U | |
| | | VMP-7-29.5-020112 | 2/1/2012 | <0.53 | U | | <1.4 | U | | 0.32 | J | J | <0.62 | U | | <1 | U | | <0.99 | U | | <0.43 | U | | <0.55 | U | | <4.3 | U | UJ | <0.8 | U | | <0.8 | U | |
| | | VMP-7-29.5-041312 | 4/13/2012 | <0.0033 | J | U | 0.015 | | | <0.0045 | J | U | 0.0012 | J | | <0.0063 | U | | <0.0062 | U | | <0.0027 | J | U | 0.016 | | | <0.027 | U | | <0.005 | U | | <0.005 | U | |
| | | VMP-7-29.5-072012 | 7/20/2012 | <0.0034 | U | | 0.042 | | J | 0.0005 | J | | 0.00076 | J | | 0.003 | J | | <0.0063 | U | | 0.0016 | J | | 0.017 | | | <0.028 | U | | <0.0051 | U | | <0.0051 | U | |
| | | VMP-7-29.5-072012-Dup | 7/20/2012 | <0.0034 | U | | 0.02 | | J | 0.00086 | J | | 0.00078 | J | | <0.0064 | U | | <0.0063 | U | | <0.0028 | U | | 0.018 | | | <0.028 | U | | <0.0051 | U | | <0.0051 | U | |
| | | VMP-7-29.5-101012 | 10/10/2012 | <0.0052 | U | | 0.0026 | J | | <0.0071 | U | | <0.0062 | U | | <0.0099 | U | | <0.0098 | U | | <0.0043 | U | | 0.0013 | J | | <0.043 | J | U | <0.0079 | U | | <0.0079 | U | |
| | 38 ft | VMP-7-38-020711 | 2/7/2011 | <3.1 | U | | <8.5 | U | | 4.6 | | | <3.7 | U | | <5.9 | U | | <5.9 | U | | <2.6 | U | | <3.2 | U | | <26 | U | | <4.7 | U | | <4.7 | U | |
| | | VMP-7-38-040711 | 4/7/2011 | <0.79 | U | | <2.2 | U | | 0.43 | J | J | <0.94 | U | | <1.5 | U | | <1.5 | U | | <0.65 | U | | <0.83 | U | | <6.5 | U | | <1.2 | U | | <1.2 | U | |
| | | VMP-7-38-020112 | 2/1/2012 | <0.76 | U | | <2.1 | U | | 0.33 | J | J | <0.89 | U | | <1.4 | U | | <1.4 | U | | <0.62 | U | | <0.79 | U | | <6.2 | U | UJ | <1.1 | U | | <1.1 | U | |
| | | VMP-7-38-042512 | 4/25/2012 | <0.0033 | U | | 0.018 | | | <0.0045 | U | | <0.0039 | U | | <0.0063 | U | | <0.0062 | J | U | <0.0027 | U | | 0.014 | | | <0.027 | U | | <0.005 | U | | <0.005 | U | |
| | | VMP-7-38-042512-Dup | 4/25/2012 | <0.0033 | U | | 0.017 | | | <0.0045 | U | | 0.0011 | J | | <0.0063 | U | | <0.0062 | J | U | <0.0027 | U | | 0.013 | | | <0.027 | U | | <0.005 | U | | <0.005 | U | |
| | | VMP-7-38-101112 | 10/11/2012 | <0.0048 | U | | 0.0039 | J | | <0.0066 | U | | <0.0057 | U | | <0.0092 | U | | <0.0091 | U | | <0.004 | U | | 0.0022 | J | | <0.04 | U | | <0.0073 | U | | <0.0073 | U | |
| VMP-8 | 5 ft | VMP-8-5-083010 | 8/30/2010 | 0.00052 | J | | 0.013 | J | | <0.0066 | U | | <0.0057 | U | | <0.0092 | U | | 0.0048 | J | | <0.004 | U | | 0.0011 | J | | 0.015 | J | | 0.00087 | J | | 0.0009 | J | |
| | | VMP-8-5-111810 | 11/17/2010 | 0.00055 | J | | 0.0026 | J | | <0.0057 | U | | 0.0024 | J | | <0.008 | U | | 0.0026 | J | | <0.0034 | U | | 0.00096 | J | | <0.034 | U | | 0.0009 | J | | <0.0064 | U | |
| | | VMP-8-5-021011 | 2/10/2011 | <0.0044 | U | | 0.008 | J | | <0.0061 | U | | <0.0053 | U | | <0.0085 | U | | <0.0084 | U | | <0.0036 | U | | <0.0046 | U | | <0.037 | U | | <0.0067 | U | | <0.0067 | U | |
| | | VMP-8-5-040711 | 4/7/2011 | <0.005 | U | | <0.014 | U | | <0.0068 | U | | <0.0059 | U | | <0.0095 | U | | <0.0094 | J | U | <0.0041 | U | | 0.0016 | J | | <0.041 | J | U | <0.0075 | U | | <0.0075 | U | |
| | | VMP-8-5-072711 | 7/27/2011 | <0.0053 | U | | 0.075 | | | 0.00084 | J | | 0.0015 | J | | <0.01 | U | | 0.0028 | J | | <0.0044 | U | | 0.023 | | | <0.044 | U | | <0.0081 | U | | <0.0081 | U | |
| | | VMP-8-5-110311 | 11/3/2011 | <0.0031 | U | | 0.014 | | | <0.0042 | U | | <0.0036 | U | | <0.0059 | U | | <0.0058 | U | | 0.00065 | J | | 0.023 | | | <0.025 | U | | <0.0047 | U | | <0.0047 | U | |
| | | VMP-8-5-012312 | 1/23/2012 | <0.0038 | U | | 0.014 | | | <0.0052 | J | U | <0.0045 | U | | <0.0073 | U | | 0.0029 | J | | 0.0016 | J | | 0.0047 | | | <0.031 | J | U | <0.0058 | U | | <0.0058 | U | |
| | | VMP-8-5-041012 | 4/10/2012 | <0.0034 | U | | 0.0039 | J | | 0.0048 | | | 0.00077 | J | | <0.0066 | U | | 0.0016 | J | | <0.0028 | U | | 0.0076 | | | <0.028 | U | | <0.0052 | U | | <0.0052 | U | |
| | | VMP-8-5-071312 | 7/13/2012 | <0.0029 | U | | 0.0044 | J | | <0.004 | J | U | <0.0034 | U | | <0.0055 | U | | <0.0055 | U | | <0.0024 | U | | <0.003 | J | U | <0.024 | U | | <0.0044 | U | | <0.0044 | U | |
| | | VMP-8-5-073112 | 7/31/2012 | <0.0037 | U | | 0.064 | | | 0.00054 | J | | 0.0019 | J | | <0.0071 | U | | 0.0028 | J | | 0.0048 | | | 0.14 | | | <0.03 | U | | <0.0056 | U | | <0.0056 | U | |
| | | VMP-8-5-100412 | 10/4/2012 | <0.005 | U | | <0.014 | U | | <0.0068 | J | U | <0.0059 | U | | <0.0095 | U | | <0.0094 | U | | <0.0041 | U | | 0.0013 | J | | 0.0061 | J | | <0.0075 | U | | <0.0075 | U | |
| | | VMP-8-5-100412-Dup | 10/4/2012 | <0.0048 | U | | <0.013 | U | | <0.0065 | U | | <0.0056 | U | | <0.0091 | U | | <0.009 | U | | <0.0039 | U | | 0.0015 | J | | <0.039 | U | | <0.0072 | U | | <0.0072 | U | |
| | | VMP-8-5-012413 | 1/24/2013 | <0.0048 | U | | 0.0066 | J | | <0.0066 | U | | <0.0057 | U | | <0.0092 | U | | <0.0091 | U | | 0.0041 | | | 0.0014 | J | | <0.04 | U | | <0.0073 | U | | <0.0073 | U | |
| | 9.5 ft | VMP-8-9.5 | 11/10/2009 | <0.004 | U | | <0.011 | U | | <0.005 | U | | <0.004 | U | | <0.007 | U | | <0.007 | U | | <0.003 | U | | <0.004 | U | | <0.033 | U | | <0.006 | U | | <0.006 | U | |
| | | VMP-8-9.5-083010 | 8/30/2010 | 0.00039 | J | | 0.029 | | | <0.0059 | U | | <0.0052 | U | | <0.0083 | U | | 0.0045 | J | | <0.0036 | U | | 0.0033 | J | | 0.01 | J | | <0.0066 | U | | 0.00075 | J | |
| | | VMP-8-9.5-083010-DUP | 8/30/2010 | <0.0044 | U | | 0.0068 | J | | <0.0061 | U | | 0.0011 | J | | <0.0085 | U | | 0.0043 | J | | <0.0036 | U | | 0.0007 | J | | <0.037 | U | | 0.00072 | J | | 0.00084 | J | |
| | | VMP-8-9.5-111810 | 11/17/2010 | 0.00054 | J | | 0.0073 | J | | <0.0059 | U | | 0.0018 | J | | <0.0083 | U | | 0.0098 | | | <0.0036 | U | | 0.001 | J | | <0.036 | U | | 0.0015 | J | | <0.0066 | U | |
| | | VMP-8-9.5-021011 | 2/10/2011 | <0.0045 | U | | 0.0036 | J | | <0.0062 | U | | <0.0054 | U | | <0.0086 | U | | 0.0042 | J | | <0.0037 | U | | 0.0011 | J | | <0.037 | U | | <0.0069 | U | | <0.0069 | U | |
| | | VMP-8-9.5-040711 | 4/7/2011 | <0.005 | U | | 0.0043 | J | | <0.0068 | U | | <0.0059 | U | | <0.0095 | U | | 0.0046 | J | | <0.0041 | U | | 0.0012 | J | | <0.041 | U | | <0.0075 | U | | <0.0075 | U | |
| | | VMP-8-9.5-072711 | 7/27/2011 | <0.0038 | U | | 0.04 | | | 0.00094 | J | | 0.0022 | J | | <0.0073 | U | | 0.0025 | J | | <0.0031 | U | | 0.02 | | | <0.032 | U | | <0.0058 | U | | <0.0058 | U | |
| | | VMP-8-9.5-110311 | 11/3/2011 | <0.003 | U | | 0.0091 | | | 0.00063 | J | | <0.0036 | U | | <0.0058 | U | | <0.0057 | U | | 0.00073 | J | | 0.023 | | | <0.025 | U | | <0.0046 | U | | <0.0046 | U | |
| | | VMP-8-9.5-012312 | 1/23/2012 | <0.0036 | U | | 0.0049 | J | | <0.005 | J | U | <0.0043 | U | | <0.007 | U | | 0.0037 | J | | 0.0014 | J | | 0.0046 | | | <0.03 | U | | <0.0055 | U | | <0.0055 | U | |
| | | VMP-8-9.5-041012 | 4/10/2012 | <0.0034 | U | | 0.014 | | | <0.0047 | U | | 0.00097 | J | | <0.0066 | U | | 0.0014 | J | | <0.0028 | U | | 0.012 | | | <0.028 | U | | <0.0052 | U | | <0.0052 | U | |
| | | VMP-8-9.5-071312 | 7/13/2012 | <0.0034 | U | | 0.0039 | J | | <0.0046 | U | | <0.004 | U | | <0.0064 | U | | <0.0063 | U | | <0.0028 | U | | <0.0035 | U | | <0.028 | U | | <0.0051 | U | | <0.0051 | U | |
| | | VMP-8-9.5-071312-Dup | 7/13/2012 | <0.0032 | U | | 0.0026 | J | | <0.0044 | U | | <0.0038 | U | | <0.0061 | U | | <0.0061 | U | | <0.0026 | U | | <0.0034 | U | | <0.026 | U | | <0.0049 | U | | <0.0049 | U | |
| | | VMP-8-9.5-100412 | 10/4/2012 | <0.0055 | U | | <0.015 | U | | <0.0074 | U | | <0.0064 | U | | <0.01 | U | | <0.01 | U | | <0.0045 | U | | 0.0043 | J | | <0.045 | U | | <0.0083 | U | | <0.0083 | U | |
| | | VMP-8-9.5-012413 | 1/24/2013 | <0.0045 | U | | 0.0032 | J | | <0.0062 | U | | <0.0054 | U | | <0.0086 | U | | <0.0085 | J | U | <0.0037 | U | | <0.0047 | U | | <0.037 | U | | <0.0069 | U | | <0.0069 | U | |
| | | VMP-8-9.5-012413-Dup | 1/24/2013 | <0.0048 | U | | <0.013 | U | | <0.0066 | U | | <0.0057 | U | | <0.0092 | U | | <0.0091 | J | U | <0.004 | U | | <0.0051 | U | | <0.04 | U | | <0.0073 | U | | <0.0073 | U | |
| | 23.5 ft | VMP-8-23.5-083010 | 8/30/2010 | 0.00037 | J | | 0.0046 | J | | <0.0065 | U | | <0.0056 | U | | <0.0091 | U | | 0.0038 | J | | <0.0039 | U | | 0.00063 | J | | <0.039 | U | | 0.00084 | J | | 0.001 | J | |
| | | VMP-8-23.5-111910 | 11/19/2010 | <0.0045 | U | | 0.0063 | J | | <0.0062 | U | | 0.0024 | J | | <0.0086 | U | | 0.0041 | J | | <0.0037 | U | | 0.0013 | J | | <0.037 | U | | <0.0069 | U | | <0.0069 | U | |
| | | VMP-8-23.5-021011 | 2/10/2011 | <0.0048 | U | | 0.0076 | J | | <0.0066 | U | | <0.0057 | U | | <0.0092 | U | | 0.0041 | J | | <0.004 | U | | <0.0051 | U | | <0.04 | U | | <0.0073 | U | | <0.0073 | U | |
| | | VMP-8-23.5-040711 | 4/7/2011 | <0.0045 | U | | <0.012 | U | | <0.0062 | U | | <0.0054 | U | | <0.0086 | U | | 0.0045 | J | | <0.0037 | U | | 0.0015 | J | | 0.002 | J | | <0.0069 | U | | <0.0069 | U | |
| | | VMP-8-23.5-040711-DUP | 4/7/2011 | 0.00068 | J | | <0.02 | U | | <0.0098 | U | | <0.0085 | U | | <0.014 | U | | 0.0052 | J | | <0.0059 | U | | 0.0014 | J | | 0.0048 | J | | <0.011 | U | | 0.0025 | J | |
| | | VMP-8-23.5-081011 | 8/10/2011 | <0.0048 | U | | 0.025 | | | <0.0065 | J | U | 0.0012 | J | | <0.0091 | U | | 0.0022 | J | | <0.0039 | U | | 0.015 | | | <0.039 | J | U | <0.0072 | U | | <0.0072 | U | |
| | | VMP-8-23.5-110611 | 11/6/2011 | <0.0034 | U | | 0.016 | | | 0.00033 | J | | <0.0041 | U | | <0.0066 | U | | <0.0065 | J | U | <0.0028 | U | | 0.012 | | | <0.028 | U | | <0.0052 | U | | <0.0052 | U | |
| | | VMP-8-23.5-012312 | 1/23/2012 | <0.0038 | U | | 0.0094 | J | | <0.0052 | J | U | <0.0045 | U | | <0.0073 | U | | 0.0033 | J | | <0.0031 | U | | 0.0046 | | | <0.031 | U | | <0.0058 | U | | <0.0058 | U | |
| | | VMP-8-23.5-041012 | 4/10/2012 | <0.0034 | U | | 0.016 | | | 0.0013 | J | | <0.004 | U | | <0.0064 | U | | 0.0017 | J | | <0.0028 | U | | 0.018 | | | <0.028 | U | | <0.0051 | U | | <0.0051 | U | |
| | | VMP-8-23.5-071312 | 7/13/2012 | <0.0037 | U | | 0.0054 | J | | <0.0051 | U | | <0.0044 | U | | <0.0071 | U | | <0.007 | U | | <0.003 | U | | <0.0039 | J | U | <0.03 | U | | <0.0056 | U | | <0.0056 | U | |
| | | VMP-8-23.5-100412 | 10/4/2012 | <0.0052 | U | | <0.014 | U | | <0.0071 | U | | <0.0062 | U | | <0.0099 | U | | <0.0098 | U | | <0.0043 | U | | 0.0028 | J | | <0.043 | U | | <0.0079 | U | | <0.0079 | U | |
| | | VMP-8-23.5-012413 | 1/24/2013 | <0.0052 | U | | <0.014 | U | | <0.0071 | U | | <0.0062 | U | | <0.0099 | U | | 0.0034 | J | | <0.0043 | U | | <0.0054 | U | | <0.043 | U | | <0.0079 | U | | <0.0079 | U | |

SEE LAST PAGE OF TABLE FOR NOTES

**TABLE 5**
**CUMULATIVE SUMMARY OF SOIL VAPOR ANALYTICAL DETECTIONS AND SCREENING RESULTS: VILLAGE - VOCS**

| Location | Depth | Sample ID | Sample Date | Methyl tert-Butyl Ether (MTBE) 3400 | | | 2-Propanol | | | n-Propylbenzene | | | Styrene 1400 | | | 1,1,2,2-Tetrachloroethane | | | Tetrachloroethene 0.55 | | | Tetrahydrofuran | | | Toluene 6200 | | | 1,2,4-Trichlorobenzene 11 | | | 1,1,1-Trichloroethane (Methyl chloroform) 6600 | | | 1,1,2-Trichloroethane 170000 | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals |
| VMP-9 | 5 ft | VMP-9-5-082610 | 8/26/2010 | <0.0041 | U | | 0.012 | | | <0.0056 | U | | <0.0048 | U | | <0.0078 | U | | 0.0023 | J | | <0.0034 | U | | 0.0036 | J | | <0.034 | U | | <0.0062 | U | | <0.0062 | U | |
| | | VMP-9-5-111910 | 11/19/2010 | <0.0043 | U | | 0.028 | | | <0.0058 | U | | 0.0017 | J | | <0.0082 | U | | 0.016 | | | <0.0035 | U | | 0.00064 | J | | <0.035 | U | | <0.0065 | U | | <0.0065 | U | |
| | | VMP-9-5-020811 | 2/8/2011 | <0.004 | U | | 0.0021 | J | | <0.0054 | U | | <0.0047 | U | | <0.0076 | U | | 0.001 | J | | <0.0032 | U | | 0.0035 | J | | <0.033 | J | U | <0.006 | U | | <0.006 | U | |
| | | VMP-9-5-040611 | 4/6/2011 | <0.011 | U | | <0.03 | U | | <0.015 | U | | <0.013 | U | | <0.021 | U | | 0.0058 | J | | <0.0089 | U | | 0.0019 | J | | <0.09 | J | U | <0.016 | U | | <0.016 | U | |
| | | VMP-9-5-080211 | 8/2/2011 | <0.21 | U | | <0.58 | U | | <0.29 | U | | <0.25 | U | | <0.4 | U | | <0.4 | U | | <0.17 | U | | 0.048 | J | | <1.8 | U | | <0.32 | U | | <0.32 | U | |
| | | VMP-9-5-110411 | 11/4/2011 | <0.0032 | U | | 0.0073 | J | | <0.0043 | J | U | <0.0037 | U | | <0.006 | U | | <0.0059 | U | | <0.0026 | U | | 0.0076 | | | <0.026 | J | U | <0.0048 | U | | <0.0048 | U | |
| | | VMP-9-5-012612 | 1/26/2012 | <0.0027 | U | | 0.0072 | | | <0.0037 | U | | <0.0032 | U | | <0.0051 | U | | <0.005 | J | U | <0.0022 | U | | 0.0058 | | | <0.022 | J | U | <0.0041 | U | | <0.0041 | U | |
| | | VMP-9-5-041112 | 4/11/2012 | <0.0032 | U | | 0.0037 | J | | 0.0034 | J | | <0.0038 | U | | <0.0061 | U | | 0.0013 | J | | <0.0026 | U | | 0.0047 | | | <0.026 | U | | <0.0049 | U | | <0.0049 | U | |
| | | VMP-9-5-071312 | 7/13/2012 | <0.0034 | U | | 0.074 | | | <0.0047 | J | U | <0.0041 | J | U | <0.0066 | U | | <0.0065 | U | | 0.0024 | J | | 0.047 | | | <0.028 | U | | <0.0052 | U | | <0.0052 | U | |
| | | VMP-9-5-101012 | 10/10/2012 | <0.0052 | U | | 0.0039 | J | | <0.0071 | U | | <0.0062 | U | | <0.0099 | U | | <0.0098 | U | | <0.0043 | U | | 0.0005 | J | | <0.043 | U | | <0.0079 | U | | <0.0079 | U | |
| | | [4]VMP-9-5-012513 | 1/25/2013 | <0.0051 | U | UJ | 0.021 | | J | <0.0069 | U | UJ | <0.006 | U | UJ | <0.0097 | U | UJ | <0.0096 | J | UJ | <0.0042 | U | UJ | <0.0053 | J | UJ | <0.042 | U | UJ | <0.0077 | U | UJ | <0.0077 | U | UJ |
| | | VMP-9-5-021513 | 2/15/2013 | 0.0012 | J | | 0.016 | | | 0.0076 | | | <0.0059 | U | | <0.0095 | U | | <0.0094 | U | | <0.0041 | U | | 0.00082 | J | | <0.041 | U | | <0.0075 | U | | <0.0075 | U | |
| | 11.5 ft | VMP-9-11.5-082610 | 8/26/2010 | <0.093 | U | | <0.25 | U | | <0.13 | U | | <0.11 | U | | <0.18 | U | | <0.17 | U | | <0.076 | U | | <0.097 | U | | <0.76 | U | | <0.14 | U | | <0.14 | U | |
| | | VMP-9-11.5-111910 | 11/19/2010 | <0.27 | U | | <0.73 | U | | <0.37 | U | | <0.32 | U | | <0.51 | U | | <0.5 | U | | <0.22 | U | | <0.28 | U | | <2.2 | U | | <0.41 | U | | <0.41 | U | |
| | | VMP-9-11.5-020911 | 2/9/2011 | <0.0048 | U | | 0.0094 | J | J | <0.0066 | U | | <0.0057 | U | | <0.0092 | U | | 0.0039 | J | | <0.004 | U | | <0.0051 | U | | <0.04 | U | | <0.0073 | U | | <0.0073 | U | |
| | | VMP-9-11.5-020911-DUP | 2/9/2011 | <0.0038 | U | | 0.049 | | J | <0.0051 | U | | <0.0044 | U | | <0.0072 | U | | 0.0037 | J | | <0.0031 | U | | 0.0029 | J | | <0.031 | U | | <0.0057 | U | | <0.0057 | U | |
| | | VMP-9-11.5-040611 | 4/6/2011 | <0.014 | U | | <0.039 | U | | <0.019 | U | | <0.017 | U | | <0.027 | U | | 0.0037 | J | | <0.012 | U | | <0.015 | U | | <0.12 | J | U | <0.022 | U | | <0.022 | U | |
| | | VMP-9-11.5-080211 | 8/2/2011 | <0.32 | U | | <0.86 | U | | <0.43 | U | | <0.37 | U | | <0.6 | U | | <0.6 | U | | <0.26 | U | | <0.33 | U | | <2.6 | U | | <0.48 | U | | <0.48 | U | |
| | | VMP-9-11.5-110411 | 11/4/2011 | <0.0032 | U | | 0.017 | | | <0.0043 | J | U | <0.0037 | U | | <0.006 | U | | <0.0059 | U | | <0.0026 | U | | 0.012 | | | <0.026 | J | U | <0.0048 | U | | <0.0048 | U | |
| | | VMP-9-11.5-012612 | 1/26/2012 | <0.0028 | U | | 0.012 | | | <0.0038 | U | | 0.00049 | J | | <0.0053 | U | | <0.0052 | J | U | 0.0025 | | | 0.009 | | | <0.023 | J | U | <0.0042 | U | | <0.0042 | U | |
| | | VMP-9-11.5-041112 | 4/11/2012 | <0.0033 | U | | 0.0045 | J | | <0.0045 | U | | <0.0039 | U | | <0.0063 | U | | 0.0018 | J | | <0.0027 | U | | 0.02 | | | <0.027 | U | | <0.005 | U | | <0.005 | U | |
| | | VMP-9-11.5-071312 | 7/13/2012 | <0.0037 | U | | 0.086 | | | <0.0051 | J | U | <0.0044 | J | U | <0.0071 | U | | 0.0021 | J | | 0.0024 | J | | 0.069 | | | <0.03 | U | | <0.0056 | U | | <0.0056 | U | |
| | | VMP-9-11.5-101012 | 10/10/2012 | <0.005 | U | | 0.063 | | | <0.0068 | U | | <0.0059 | U | | <0.0095 | U | | <0.0094 | U | | 0.0014 | J | | 0.0031 | J | | <0.041 | U | | <0.0075 | U | | <0.0075 | U | |
| | | VMP-9-11.5-012513 | 1/25/2013 | <0.0042 | U | | 0.018 | | J | <0.0057 | U | | <0.005 | U | | <0.008 | U | | <0.0079 | J | U | 0.0013 | J | | 0.0012 | J | | <0.034 | J | U | <0.0064 | U | | <0.0064 | U | |
| | | VMP-9-11.5-012513-DUP | 1/25/2013 | <0.0045 | U | | 0.0045 | J | J | <0.0062 | U | | <0.0054 | U | | <0.0086 | U | | <0.0085 | J | U | <0.0037 | U | | 0.0028 | J | | <0.037 | J | U | <0.0069 | U | | <0.0069 | U | |
| | 25.5 ft | VMP-9-25.5-082610 | 8/26/2010 | <0.73 | U | | <2 | U | | 0.14 | J | | <0.86 | U | | <1.4 | U | | <1.4 | U | | <0.59 | U | | <0.76 | U | | <6 | U | | <1.1 | U | | <1.1 | U | |
| | | VMP-9-25.5-082610-DUP | 8/26/2010 | <0.78 | U | | <2.1 | U | | <1.1 | U | | <0.92 | U | | <1.5 | U | | <1.5 | U | | <0.64 | U | | <0.81 | U | | <6.4 | U | | <1.2 | U | | <1.2 | U | |
| | | VMP-9-25.5-111910 | 11/19/2010 | <0.83 | U | | <2.3 | U | | <1.1 | U | | <0.98 | U | | <1.6 | U | | <1.6 | U | | <0.68 | U | | <0.87 | U | | <6.8 | U | | <1.2 | U | | <1.2 | U | |
| | | VMP-9-25.5-020911 | 2/9/2011 | <0.45 | U | | <1.2 | U | | <0.62 | U | | <0.54 | U | | <0.86 | U | | <0.85 | U | | <0.37 | U | | <0.47 | U | | <3.7 | U | | <0.69 | U | | <0.69 | U | |
| | | VMP-9-25.5-040811 | 4/8/2011 | <0.23 | U | | 1 | | | <0.31 | U | | 0.084 | J | | <0.44 | U | | <0.43 | U | | <0.19 | U | | 0.089 | J | | <1.9 | U | | <0.35 | U | | <0.35 | U | |
| | | VMP-9-25.5-080211 | 8/2/2011 | <0.51 | U | | <1.4 | U | | <0.69 | U | | <0.6 | U | | <0.97 | U | | <0.96 | U | | <0.42 | U | | 0.13 | J | J | <4.2 | U | | <0.77 | U | | <0.77 | U | |
| | | VMP-9-25.5-110711 | 11/7/2011 | <0.45 | U | | 0.41 | J | | <0.61 | U | | <0.53 | U | | <0.85 | U | | 0.28 | J | | <0.37 | U | | 0.55 | | | 0.24 | J | | <0.68 | U | | <0.68 | U | |
| | | VMP-9-25.5-110711-DUP | 11/7/2011 | <0.39 | U | | 0.58 | J | | <0.53 | U | | <0.46 | U | | <0.74 | U | | 0.19 | J | | <0.32 | U | | 0.57 | | | <3.2 | U | | <0.59 | U | | <0.59 | U | |
| | | VMP-9-25.5-012612 | 1/26/2012 | <0.12 | U | | <0.32 | U | | <0.16 | U | | <0.14 | U | | <0.22 | U | | <0.22 | U | | <0.095 | U | | 0.048 | J | J | <0.96 | U | | <0.18 | U | | <0.18 | U | |
| | | VMP-9-25.5-041112 | 4/11/2012 | <0.0033 | U | | <0.009 | U | | 0.004 | J | | <0.0039 | U | | <0.0063 | U | | 0.0014 | J | | <0.0027 | U | | 0.053 | | | <0.027 | U | | <0.005 | U | | <0.005 | U | |
| | | VMP-9-25.5-071312 | 7/13/2012 | <0.0036 | U | | 0.093 | | | <0.0048 | J | U | 0.0027 | J | | <0.0068 | U | | <0.0067 | J | U | 0.0036 | | | 0.077 | | | <0.029 | U | | <0.0054 | J | U | <0.0054 | U | |
| | | VMP-9-25.5-071312-Dup | 7/13/2012 | <0.0034 | U | | 0.11 | | | <0.0047 | J | U | 0.003 | J | | <0.0066 | U | | <0.0065 | J | U | 0.004 | | | 0.075 | | | <0.028 | U | | <0.0052 | U | | <0.0052 | U | |
| | | VMP-9-25.5-101012 | 10/10/2012 | <0.0048 | U | | 0.0087 | J | | <0.0065 | U | | <0.0056 | U | | <0.0091 | U | | <0.009 | U | | <0.0039 | U | | 0.0012 | J | | <0.039 | U | | <0.0072 | U | | <0.0072 | U | |
| | | VMP-9-25.5-013013 | 1/30/2013 | <0.0051 | U | | 0.012 | J | | <0.0069 | U | | <0.006 | U | | <0.0097 | U | | <0.0096 | J | U | <0.0042 | U | | <0.0053 | J | U | <0.042 | J | U | <0.0077 | U | | <0.0077 | U | |
| | 38.5 ft | VMP-9-38.5-020911 | 2/9/2011 | <0.75 | U | | <2 | U | | <1 | U | | <0.89 | U | | <1.4 | U | | <1.4 | U | | <0.62 | U | | <0.79 | U | | <6.2 | U | | <1.1 | U | | <1.1 | U | |
| | | VMP-9-38.5-040811 | 4/8/2011 | <1 | U | | 4.5 | | | <1.4 | U | | 0.24 | J | | <1.9 | U | | <1.9 | U | | <0.82 | U | | 0.67 | J | | <8.2 | U | | <1.5 | U | | <1.5 | U | |
| | | VMP-9-38.5-012612 | 1/26/2012 | <0.15 | U | | <0.41 | U | | <0.21 | U | | <0.18 | U | | <0.29 | U | | <0.28 | U | | <0.12 | U | | 0.051 | J | J | <1.2 | U | | <0.23 | U | | <0.23 | U | |
| | | VMP-9-38.5-041112 | 4/11/2012 | <0.0029 | U | | 0.0078 | J | | <0.004 | U | | 0.00065 | J | | <0.0055 | U | | <0.0055 | U | | <0.0024 | U | | 0.1 | | | <0.024 | U | | <0.0044 | U | | <0.0044 | U | |
| | | VMP-9-38.5-071312 | 7/13/2012 | 0.0075 | | | 0.088 | | | <0.0052 | J | U | 0.0037 | J | | <0.0073 | U | | <0.0072 | J | U | 0.0044 | | | 0.07 | | | <0.031 | U | | <0.0058 | U | | <0.0058 | U | |
| | | VMP-9-38.5-101012 | 10/10/2012 | <0.014 | U | | 0.004 | J | | <0.019 | U | | <0.017 | U | | <0.027 | U | | <0.027 | U | | <0.012 | U | | 0.0023 | J | | <0.12 | U | | <0.021 | U | | <0.021 | U | |
| | | VMP-9-38.5-013013 | 1/30/2013 | <0.0051 | U | | 0.011 | J | | <0.0069 | U | | <0.006 | U | | <0.0097 | U | | <0.0096 | J | U | <0.0042 | U | | <0.0053 | J | U | <0.042 | J | U | <0.0077 | U | | <0.0077 | U | |
| VMP-18 | 8.5 ft | VMP-18-8.5 | 6/18/2010 | <0.005 | U | | 0.012 | J | | <0.007 | U | | <0.006 | U | | <0.009 | U | | <0.009 | U | | 0.0072 | | | 0.0014 | J | | <0.043 | U | | <0.007 | U | | <0.007 | U | |
| | | VMP-18-8.5-090710 | 9/7/2010 | 0.00046 | J | | 0.014 | | | <0.0063 | J | U | <0.0055 | U | | <0.0088 | J | U | <0.0088 | J | U | <0.0038 | U | | 0.0021 | J | | <0.038 | J | U | 0.0011 | J | | <0.007 | U | |
| | | VMP-18-8.5-111910 | 11/19/2010 | <0.0039 | U | | 0.0036 | J | | <0.0053 | U | | <0.0046 | U | | <0.0074 | U | | <0.0073 | U | | <0.0032 | U | | <0.0041 | U | | <0.032 | U | | <0.0059 | U | | <0.0059 | U | |
| | | VMP-18-8.5-020711 | 2/7/2011 | <0.0043 | U | | 0.091 | | J | 0.0029 | J | | <0.0051 | U | | <0.0082 | U | | <0.0081 | U | | <0.0035 | U | | 0.013 | | J | <0.035 | J | U | <0.0065 | U | | <0.0065 | U | |
| | | VMP-18-8.5-020711-DUP | 2/7/2011 | <0.0041 | U | | 0.012 | | J | 0.0017 | J | | <0.0049 | U | | <0.0079 | U | | <0.0078 | U | | <0.0034 | U | | 0.0031 | J | J | <0.034 | J | U | <0.0062 | U | | <0.0062 | U | |
| | | VMP-18-8.5-040711 | 4/7/2011 | <0.0046 | U | | <0.013 | U | | 0.01 | | | <0.0055 | U | | <0.0088 | U | | 0.0036 | J | | <0.0038 | U | | 0.0011 | J | | <0.038 | J | U | <0.007 | U | | <0.007 | U | |
| | | VMP-18-8.5-072811 | 7/28/2011 | <0.005 | U | | 0.03 | | | 0.001 | J | | 0.0021 | J | | <0.0095 | U | | <0.0094 | U | | 0.0013 | J | | 0.012 | | | <0.041 | U | | <0.0075 | U | | <0.0075 | U | |
| | | VMP-18-8.5-110711 | 11/7/2011 | <0.0032 | U | | 0.012 | | | <0.0044 | U | | <0.0038 | U | | <0.0061 | U | | <0.0061 | U | | <0.0026 | U | | 0.01 | | | <0.026 | U | | <0.0049 | U | | <0.0049 | U | |
| | | VMP-18-8.5-012312 | 1/23/2012 | <0.0035 | U | | 0.035 | | | <0.0048 | U | | <0.0041 | U | | <0.0066 | U | | 0.0026 | J | | <0.0029 | U | | 0.0042 | | | <0.029 | U | | <0.0053 | U | | <0.0053 | U | |
| | | VMP-18-8.5-041012 | 4/10/2012 | <0.0036 | U | | 0.14 | | | <0.0049 | J | U | <0.0043 | J | U | <0.0069 | U | | <0.0068 | J | U | 0.01 | | | 0.036 | | | <0.03 | U | | <0.0055 | U | | <0.0055 | U | |
| | | VMP-18-8.5-071212 | 7/12/2012 | <0.0035 | U | | 0.088 | | | <0.0048 | J | U | <0.0042 | J | U | <0.0067 | U | | <0.0066 | U | | 0.0024 | J | | 0.05 | | | <0.029 | U | | <0.0053 | U | | <0.0053 | U | |
| | | VMP-18-8.5-100912 | 10/9/2012 | <0.0048 | U | | 0.038 | | | <0.0065 | U | | <0.0056 | U | | <0.0091 | U | | <0.009 | U | | <0.0039 | U | | 0.0045 | J | | <0.039 | U | | <0.0072 | U | | <0.0072 | U | |
| | | VMP-18-8.5-012313 | 1/23/2013 | <0.0052 | U | | 0.0069 | J | | <0.0071 | U | | <0.0062 | U | | <0.0099 | U | | <0.0098 | U | | <0.0043 | U | | <0.0054 | U | | <0.043 | U | | <0.0079 | U | | <0.0079 | U | |
| VMP-19 | 5 ft | VMP-19-5 | 6/18/2010 | <0.004 | U | | 0.024 | | | <0.006 | U | | <0.005 | U | | <0.009 | U | | <0.009 | J | U | <0.004 | U | | <0.005 | U | | <0.04 | U | | <0.007 | U | | <0.007 | U | |
| | | VMP-19-5-090110 | 9/1/2010 | <0.0046 | U | | 0.58 | | | <0.0063 | J | U | <0.0055 | U | | <0.0088 | U | | <0.0088 | J | U | <0.0038 | U | | <0.0049 | U | | <0.038 | J | UJ | <0.007 | U | | <0.007 | U | |
| | | VMP-19-5-111510 | 11/15/2010 | 0.0007 | J | | 0.0034 | J | | <0.0068 | U | | 0.0065 | | | <0.0095 | U | | 0.0013 | J | | <0.0041 | U | | 0.0014 | J | | <0.041 | U | | 0.0014 | J | | <0.0075 | U | |
| | | VMP-19-5-020411 | 2/4/2011 | <0.0044 | U | | 0.0076 | J | | <0.0059 | U | | <0.0052 | U | | <0.0083 | U | | <0.0082 | U | | <0.0036 | U | | 0.0018 | J | | <0.036 | J | U | <0.0066 | U | | <0.0066 | U | |
| | | VMP-19-5-040711 | 4/7/2011 | <0.0049 | U | | <0.013 | U | | <0.0066 | U | | <0.0058 | U | | <0.0093 | U | | 0.0015 | J | | <0.004 | U | | 0.0014 | J | | 0.0031 | J | | <0.0074 | U | | <0.0074 | U | |
| | | VMP-19-5-080911 | 8/9/2011 | <0.0053 | U | | 0.026 | | | <0.0073 | J | U | <0.0063 | J | U | <0.01 | U | | <0.01 | J | U | <0.0044 | U | | 0.032 | | | <0.044 | J | U | <0.0081 | U | | <0.0081 | U | |
| | | VMP-19-5-080911-DUP | 8/9/2011 | <0.0051 | U | | 0.028 | | | <0.0069 | J | U | <0.006 | J | U | <0.0097 | U | | <0.0096 | J | U | <0.0042 | U | | 0.027 | | | <0.042 | J | U | <0.0077 | U | | <0.0077 | U | |
| | | VMP-19-5-110811 | 11/8/2011 | <0.0035 | U | | 0.0078 | J | | <0.0048 | U | | <0.0042 | U | | <0.0067 | U | | <0.0066 | U | | <0.0029 | U | | 0.014 | | | <0.029 | U | | <0.0053 | U | | <0.0053 | U | |
| | | VMP-19-5-012612 | 1/26/2012 | <0.0031 | U | | 0.01 | | | <0.0042 | U | | <0.0036 | U | | <0.0059 | U | | <0.0058 | U | | <0.0025 | U | | 0.0061 | | | <0.025 | U | | <0.0047 | U | | <0.0047 | U | |
| | | VMP-19-5-041012 | 4/10/2012 | <0.0035 | U | | 0.076 | | | <0.0048 | J | U | <0.0042 | J | U | <0.0067 | U | | <0.0066 | J | U | 0.0071 | | | 0.029 | | | <0.029 | U | | <0.0053 | U | | <0.0053 | U | |
| | | VMP-19-5-071112 | 7/11/2012 | <0.004 | U | | <0.011 | U | | <0.0055 | J | U | <0.0047 | J | U | <0.0076 | U | | <0.0076 | U | | 0.0017 | J | | 0.059 | | | <0.033 | U | | <0.0061 | U | | <0.0061 | U | |
| | | VMP-19-5-100912 | 10/9/2012 | <0.0053 | U | | 0.085 | | | <0.0073 | U | | <0.0063 | U | | <0.01 | U | | <0.01 | U | | <0.0044 | U | | <0.0056 | U | | <0.044 | U | | <0.0081 | U | | <0.0081 | U | |
| | | VMP-19-5-013113 | 1/31/2013 | <0.0046 | U | | 0.083 | | | 0.049 | | | <0.0055 | U | | <0.0088 | U | | 0.00099 | J | | <0.0038 | U | | 0.005 | | | <0.038 | J | U | <0.007 | U | | <0.007 | U | |

SEE LAST PAGE OF TABLE FOR NOTES

**TABLE 5**
**CUMULATIVE SUMMARY OF SOIL VAPOR ANALYTICAL DETECTIONS AND SCREENING RESULTS: VILLAGE - VOCS**

| Location | Depth | Sample ID | Sample Date | Methyl tert-Butyl Ether (MTBE) 3400 | | | 2-Propanol | | | n-Propylbenzene | | | Styrene 1400 | | | 1,1,2,2-Tetrachloroethane | | | Tetrachloroethene 0.55 | | | Tetrahydrofuran | | | Toluene 6200 | | | 1,2,4-Trichlorobenzene 11 | | | 1,1,1-Trichloroethane (Methyl chloroform) 6600 | | | 1,1,2-Trichloroethane 170000 | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals |
| VMP-20 | 5 ft | VMP-20-5-031411 | 3/14/2011 | <0.0044 | U | | <0.012 | U | | 0.0024 | J | | <0.0052 | U | | <0.0083 | U | | 0.055 | | | <0.0036 | U | | 0.046 | | | <0.036 | U | UJ | <0.0066 | U | | <0.0066 | U | |
| | | VMP-20-5-041511 | 4/15/2011 | <0.048 | U | | <0.13 | UJ | UJ | <0.065 | U | | <0.057 | U | | <0.091 | U | | <0.09 | U | | <0.039 | U | UJ | <0.05 | U | | <0.39 | U | | <0.072 | U | | <0.072 | U | |
| | | VMP-20-5-072511 | 7/25/2011 | <0.0051 | U | | 0.032 | | | <0.0069 | U | | <0.006 | J | U | <0.0097 | U | | <0.0096 | U | UJ | <0.0042 | U | | 0.014 | | | <0.042 | U | | <0.0077 | U | | <0.0077 | U | |
| | | VMP-20-5-110111 | 11/1/2011 | <0.0029 | U | | 0.0083 | | | <0.004 | J | U | <0.0034 | U | | <0.0055 | U | | <0.0055 | U | | 0.0012 | J | | 0.019 | | | <0.024 | U | | <0.0044 | U | | <0.0044 | U | |
| | | VMP-20-5-012312 | 1/23/2012 | <0.014 | U | | 0.016 | J | | <0.019 | U | | <0.016 | U | | <0.026 | U | | <0.026 | U | | <0.011 | U | | 0.03 | | | <0.11 | U | | <0.021 | U | | <0.021 | U | |
| | | VMP-20-5-041012 | 4/10/2012 | <0.0032 | U | | 0.18 | | | <0.0043 | U | | <0.0037 | U | | <0.006 | U | | <0.0059 | U | | 0.027 | | | 0.024 | | | <0.026 | U | | <0.0048 | U | | <0.0048 | U | |
| | | VMP-20-5-071112 | 7/11/2012 | <0.0042 | U | | 0.0061 | J | | <0.0057 | U | | <0.005 | U | | <0.008 | U | | <0.0079 | U | | <0.0034 | U | | 0.0024 | J | | <0.034 | U | | <0.0064 | U | | <0.0064 | U | |
| | | VMP-20-5-073112 | 7/31/2012 | <0.0035 | U | | 0.87 | | | 0.0004 | J | | 0.0016 | J | | <0.0067 | U | | <0.0066 | U | | 0.0011 | J | | 0.072 | | | <0.029 | U | | <0.0053 | U | | <0.0053 | U | |
| | | VMP-20-5-100412 | 10/4/2012 | <0.0052 | U | | <0.014 | U | | <0.0071 | U | | <0.0062 | U | | <0.0099 | U | | <0.0098 | U | | <0.0043 | U | | 0.0013 | J | | <0.043 | U | | <0.0079 | U | | <0.0079 | U | |
| | | VMP-20-5-020713 | 2/7/2013 | <0.0044 | U | | 0.0057 | J | | 0.006 | | | <0.0053 | U | | <0.0085 | U | | <0.0084 | J | U | <0.0036 | U | | <0.0046 | J | U | <0.037 | U | | <0.0067 | U | | <0.0067 | U | |
| | 10 ft | VMP-20-10-031411 | 3/14/2011 | <0.0044 | U | | <0.012 | U | | 0.0023 | J | | <0.0052 | U | | <0.0083 | U | | 0.0089 | J | | 0.0018 | J | | 0.0084 | | | <0.036 | U | UJ | <0.0066 | U | | <0.0066 | U | |
| | | VMP-20-10-041511 | 4/15/2011 | <0.044 | U | | <0.12 | UJ | UJ | 0.023 | J | | <0.052 | U | | <0.083 | U | | <0.082 | U | | <0.036 | U | UJ | <0.046 | U | | <0.36 | U | | <0.066 | U | | <0.066 | U | |
| | | VMP-20-10-072511 | 7/25/2011 | <0.0046 | U | | 0.026 | | | <0.0063 | U | | 0.0017 | J | | <0.0088 | U | | <0.0088 | U | UJ | <0.0038 | U | | 0.015 | | | 0.0043 | J | | <0.007 | U | | <0.007 | U | |
| | | VMP-20-10-110111 | 11/1/2011 | <0.0031 | U | | 0.0066 | J | | <0.0042 | U | | <0.0036 | U | | <0.0059 | U | | <0.0058 | U | | <0.0025 | U | | 0.0095 | | | <0.025 | U | | <0.0047 | U | | <0.0047 | U | |
| | | VMP-20-10-012312 | 1/23/2012 | <0.0032 | U | | 0.0092 | | | <0.0044 | J | U | <0.0038 | U | | <0.0061 | U | | 0.00098 | J | | <0.0026 | U | | 0.0082 | | | <0.026 | U | | <0.0049 | U | | <0.0049 | U | |
| | | VMP-20-10-041012 | 4/10/2012 | <0.0031 | U | | 0.19 | | | <0.0042 | U | | 0.0012 | J | | <0.0059 | U | | <0.0058 | U | | 0.045 | | | 0.028 | | | <0.025 | U | | <0.0047 | U | | <0.0047 | U | |
| | | VMP-20-10-071112 | 7/11/2012 | <0.0035 | U | | 0.01 | | | <0.0048 | J | U | <0.0042 | U | | <0.0067 | U | | <0.0066 | U | | 0.00078 | J | | 0.005 | | | <0.029 | U | | <0.0053 | U | | <0.0053 | U | |
| | | VMP-20-10-100412 | 10/4/2012 | <0.0048 | U | | <0.013 | U | | <0.0066 | U | | <0.0057 | U | | <0.0092 | U | | <0.0091 | U | | <0.004 | U | | 0.0019 | J | | <0.04 | U | | <0.0073 | U | | <0.0073 | U | |
| | | VMP-20-10-012213 | 1/22/2013 | <0.0044 | U | | 0.008 | J | | <0.0061 | U | | <0.0053 | U | | <0.0085 | U | | <0.0084 | J | U | <0.0036 | U | | <0.0046 | J | U | <0.037 | J | U | <0.0067 | U | | <0.0067 | U | |
| | 25 ft | VMP-20-25-031411 | 3/14/2011 | <0.0043 | U | | <0.012 | U | | <0.0059 | U | | <0.0051 | U | | <0.0082 | U | | 0.0068 | J | | <0.0035 | U | | 0.0015 | J | | <0.035 | U | UJ | <0.0065 | U | | <0.0065 | U | |
| | | VMP-20-25-041511 | 4/15/2011 | <0.05 | U | | <0.14 | UJ | UJ | <0.068 | U | | <0.059 | U | | <0.095 | U | | <0.094 | U | | <0.041 | U | UJ | <0.052 | U | | <0.41 | U | | <0.075 | U | | <0.075 | U | |
| | | VMP-20-25-072611 | 7/26/2011 | <0.33 | U | | <0.9 | U | | <0.45 | U | | <0.39 | U | | <0.63 | U | | <0.62 | U | UJ | <0.27 | U | | <0.35 | U | | <2.7 | U | | <0.5 | U | | <0.5 | U | |
| | | VMP-20-25-110511 | 11/5/2011 | <0.003 | U | | 0.0075 | J | | 0.00026 | J | | 0.00044 | J | | <0.0058 | U | | <0.0057 | J | U | <0.0025 | U | | 0.015 | | | <0.025 | U | | <0.0046 | U | | <0.0046 | U | |
| | | VMP-20-25-012312 | 1/23/2012 | <0.0034 | U | | 0.011 | | | <0.0046 | J | U | <0.004 | U | | <0.0064 | U | | 0.001 | J | | <0.0028 | U | | 0.0064 | | | <0.028 | U | | <0.0051 | U | | <0.0051 | U | |
| | | VMP-20-25-041012 | 4/10/2012 | <0.0032 | U | | 0.15 | | | <0.0043 | U | | 0.0007 | J | | <0.006 | U | | <0.0059 | U | | 0.031 | | | 0.036 | | | <0.026 | U | | <0.0048 | U | | <0.0048 | U | |
| | | VMP-20-25-041012-Dup | 4/10/2012 | <0.0032 | U | | 0.16 | | | 0.00046 | J | | 0.00062 | J | | <0.0061 | U | | <0.0061 | U | | 0.033 | | | 0.038 | | | <0.026 | U | | <0.0049 | U | | <0.0049 | U | |
| | | VMP-20-25-071112 | 7/11/2012 | <0.0036 | U | | 0.084 | | | <0.0049 | J | U | <0.0043 | U | | <0.0069 | U | | <0.0068 | U | | <0.003 | U | | 0.014 | | | <0.03 | U | | <0.0055 | U | | <0.0055 | U | |
| | | VMP-20-25-100412 | 10/4/2012 | <0.0053 | U | | <0.014 | U | | <0.0073 | U | | <0.0063 | U | | <0.01 | U | | <0.01 | U | | <0.0044 | U | | 0.0017 | J | | <0.044 | U | | <0.0081 | U | | <0.0081 | U | |
| | | VMP-20-25-012213 | 1/22/2013 | <0.0044 | U | | 0.0095 | J | | <0.0061 | U | | <0.0053 | U | | <0.0085 | U | | <0.0084 | J | U | <0.0036 | U | | <0.0046 | J | U | <0.037 | J | U | <0.0067 | U | | <0.0067 | U | |
| | 39.5 ft | VMP-20-39.5-100412 | 10/4/2012 | <1.3 | U | | 1.4 | J | | <1.8 | U | | 0.23 | J | | <2.5 | U | | <2.4 | U | | <1.1 | U | | 1.7 | | | <11 | U | | <2 | U | | <2 | U | |
| | | VMP-20-39.5-012313 | 1/23/2013 | <0.74 | U | | 0.18 | J | | <1 | U | | <0.88 | U | | <1.4 | U | | 0.52 | J | | <0.61 | U | | <0.78 | U | | <6.1 | U | | <1.1 | U | | <1.1 | U | |
| VMP-21 | 5 ft | VMP-21-5-020911 | 2/9/2011 | <1.7 | U | | <4.6 | U | | <2.3 | U | | <2 | U | | <3.2 | U | | <3.2 | U | | <1.4 | U | | <1.8 | U | | <14 | U | | <2.5 | U | | <2.5 | U | |
| | | VMP-21-5-020911-DUP | 2/9/2011 | <2.9 | U | | <7.8 | U | | <3.9 | U | | <3.4 | U | | <5.4 | U | | <5.4 | U | | <2.3 | U | | <3 | U | | <24 | U | | <4.3 | U | | <4.3 | U | |
| | | VMP-21-5-041311 | 4/13/2011 | <0.0048 | U | | <0.013 | U | | 0.0016 | J | | <0.0056 | U | | <0.0091 | U | | 0.011 | | | <0.0039 | U | | 0.0027 | J | | <0.039 | J | U | <0.0072 | U | | <0.0072 | U | |
| | | VMP-21-5-072511 | 7/25/2011 | <0.005 | U | | 0.026 | | | <0.0068 | J | U | 0.0023 | J | | <0.0095 | U | | 0.0058 | J | J | <0.0041 | U | | 0.026 | | | <0.041 | U | | <0.0075 | U | | <0.0075 | U | |
| | | VMP-21-5-110111 | 11/1/2011 | <0.0041 | U | | 0.012 | | | 0.016 | | | <0.0048 | U | | <0.0078 | U | | <0.0077 | U | | 0.0011 | J | | 0.0074 | | | <0.034 | U | | <0.0062 | U | | <0.0062 | U | |
| | | VMP-21-5-012312 | 1/23/2012 | <0.0035 | U | | 0.0048 | J | | <0.0048 | J | U | 0.00053 | J | | <0.0066 | U | | 0.001 | J | | <0.0029 | U | | 0.0052 | | | <0.029 | J | U | 0.0032 | J | | <0.0053 | U | |
| | | VMP-21-5-012312-DUP | 1/23/2012 | <0.0032 | U | | 0.0056 | J | | <0.0044 | J | U | <0.0038 | U | | <0.0061 | U | | 0.00076 | J | | <0.0026 | U | | 0.0057 | | | <0.026 | U | | 0.0012 | J | | <0.0049 | U | |
| | | VMP-21-5-042412 | 4/24/2012 | <0.0066 | U | | 0.025 | | | <0.009 | U | | <0.0078 | U | | <0.012 | U | | <0.012 | U | | <0.0054 | U | | 0.011 | | | <0.054 | U | | <0.01 | U | | <0.01 | U | |
| | | VMP-21-5-071012 | 7/10/2012 | <0.0038 | U | | 0.21 | | | 0.0084 | | | 0.0015 | J | | <0.0073 | U | | <0.0072 | U | | 0.02 | | | 0.01 | | | <0.031 | U | | <0.0058 | U | | <0.0058 | U | |
| | | VMP-21-5-100412 | 10/4/2012 | <0.0056 | U | | 0.014 | J | | <0.0076 | U | | <0.0066 | U | | <0.011 | U | | 0.0055 | J | | <0.0046 | U | | 0.013 | | | <0.046 | U | | <0.0085 | U | | <0.0085 | U | |
| | | VMP-21-5-020613 | 2/6/2013 | <0.0051 | U | | 0.0033 | J | | <0.0069 | U | | <0.006 | U | | <0.0097 | U | | <0.0096 | J | U | <0.0042 | U | | <0.0053 | J | U | <0.042 | J | U | <0.0077 | U | | <0.0077 | U | |
| | 10 ft | VMP-21-10-021011 | 2/10/2011 | <1.5 | U | | <4.1 | U | | <2.1 | U | | <1.8 | U | | <2.9 | U | | <2.8 | U | | <1.2 | U | | <1.6 | U | | <12 | U | | <2.3 | U | | <2.3 | U | |
| | | VMP-21-10-041311 | 4/13/2011 | <0.19 | U | | 0.16 | J | | <0.26 | U | | 0.051 | J | | <0.36 | U | | 0.051 | J | | <0.16 | U | | <0.2 | U | | <1.6 | U | | <0.29 | U | | <0.29 | U | |
| | | VMP-21-10-072511 | 7/25/2011 | <0.01 | U | | 0.013 | J | | <0.014 | U | | <0.012 | J | U | <0.02 | U | | 0.0087 | J | J | <0.0086 | U | | 0.031 | | | <0.087 | U | | <0.016 | U | | <0.016 | U | |
| | | VMP-21-10-110111 | 11/1/2011 | <0.0031 | U | | 0.014 | | | <0.0042 | U | | <0.0036 | U | | <0.0059 | U | | 0.0059 | | | 0.0045 | | | 0.0073 | | | <0.025 | U | | <0.0047 | U | | <0.0047 | U | |
| | | VMP-21-10-012312 | 1/23/2012 | <0.0035 | U | | 0.009 | J | | <0.0048 | J | U | 0.00052 | J | | <0.0066 | U | | 0.0035 | J | | <0.0029 | U | | 0.0062 | | | <0.029 | U | | <0.0053 | U | | <0.0053 | U | |
| | | VMP-21-10-040912 | 4/9/2012 | <0.0032 | U | | 0.037 | | | 0.0006 | J | | 0.0029 | J | | <0.006 | U | | <0.0059 | U | | <0.0026 | U | | 0.059 | | | <0.026 | U | | <0.0048 | U | | <0.0048 | U | |
| | | VMP-21-10-071012 | 7/10/2012 | <0.0036 | U | | 0.0022 | J | | <0.0049 | U | | <0.0043 | U | | <0.0069 | U | | 0.0025 | J | | 0.0038 | | | <0.0038 | J | U | <0.03 | U | | <0.0055 | U | | <0.0055 | U | |
| | | VMP-21-10-100412 | 10/4/2012 | <0.0051 | U | | 0.024 | | | <0.0069 | J | U | <0.006 | U | | <0.0097 | U | | 0.0074 | J | | <0.0042 | U | | 0.016 | | | <0.042 | U | | <0.0077 | U | | <0.0077 | U | |
| | | VMP-21-10-020513 | 2/5/2013 | <0.0048 | U | | 0.0061 | J | | <0.0066 | U | | <0.0057 | U | | <0.0092 | U | | 0.01 | | | <0.004 | U | | <0.0051 | J | U | <0.04 | U | | <0.0073 | U | | <0.0073 | U | |
| | | VMP-21-10-020513-DUP | 2/5/2013 | <0.0045 | U | | 0.006 | J | | <0.0062 | U | | <0.0054 | U | | <0.0086 | U | | 0.0096 | | | <0.0037 | U | | <0.0047 | J | U | <0.037 | U | | <0.0069 | U | | <0.0069 | U | |
| | 25 ft | VMP-21-25-021011 | 2/10/2011 | <4.2 | U | | <11 | U | | <5.7 | U | | <5 | U | | <8 | U | | <7.9 | U | | <3.4 | U | | <4.4 | U | | <34 | U | | <6.4 | U | | <6.4 | U | |
| | | VMP-21-25-041411 | 4/14/2011 | <15 | U | | <40 | UJ | UJ | <20 | U | | <17 | U | | <28 | U | | <28 | U | | <12 | U | UJ | <15 | U | | <120 | U | | <22 | U | | <22 | U | |
| | | VMP-21-25-041411-DUP | 4/14/2011 | <15 | U | | <40 | UJ | UJ | <20 | U | | <17 | U | | <28 | U | | <28 | U | | <12 | U | UJ | <15 | U | | <120 | U | | <22 | U | | <22 | U | |
| | | VMP-21-25-072611 | 7/26/2011 | <4.8 | U | | <13 | U | | <6.5 | U | | <5.6 | U | | <9.1 | U | | <9 | U | UJ | <3.9 | U | | <5 | U | | <39 | U | | <7.2 | U | | <7.2 | U | |
| | | VMP-21-25-110511 | 11/5/2011 | <3 | U | | 2.2 | J | | <4.1 | U | | <3.6 | U | | <5.8 | U | | 1.5 | J | | <2.5 | U | | 2.4 | J | | <25 | U | | <4.6 | U | | <4.6 | U | |
| | | VMP-21-25-012412 | 1/24/2012 | <0.042 | U | | <0.11 | U | | <0.057 | U | | <0.049 | U | | <0.08 | U | | <0.079 | U | | <0.034 | U | | <0.044 | U | | <0.34 | U | | <0.063 | U | | <0.063 | U | |
| | | VMP-21-25-040912 | 4/9/2012 | <0.0033 | U | | 0.012 | | | <0.0045 | U | | <0.0039 | U | | <0.0063 | U | | 0.0074 | | | 0.0014 | J | | 0.017 | | | <0.027 | U | | <0.005 | U | | <0.005 | U | |
| | | VMP-21-25-071112 | 7/11/2012 | <0.0033 | U | | 0.015 | | | <0.0045 | J | U | <0.0039 | U | | <0.0063 | U | | 0.0091 | | | 0.0013 | J | | 0.0067 | | | <0.027 | U | | <0.005 | U | | <0.005 | U | |
| | | VMP-21-25-100412 | 10/4/2012 | <0.0052 | U | | 0.014 | J | | <0.0071 | U | | <0.0062 | U | | <0.0099 | U | | 0.039 | | | <0.0043 | U | | 0.0092 | | | <0.043 | U | | <0.0079 | U | | <0.0079 | U | |
| | | VMP-21-25-020513 | 2/5/2013 | <0.0046 | U | | 0.0083 | J | | <0.0063 | U | | <0.0055 | U | | <0.0088 | U | | 0.1 | | | <0.0038 | U | | <0.0049 | J | U | <0.038 | U | | <0.007 | U | | <0.007 | U | |
| | | VMP-21-25-020513-DUP | 2/5/2013 | <0.0048 | U | | 0.0084 | J | | <0.0066 | U | | <0.0057 | U | | <0.0092 | U | | 0.11 | | | <0.004 | U | | <0.0051 | J | U | <0.04 | U | | <0.0073 | U | | <0.0073 | U | |
| | 33 ft | VMP-21-33-021011 | 2/10/2011 | <4.2 | U | | <11 | U | | <5.7 | U | | <5 | U | | <8 | U | | <7.9 | U | | <3.4 | U | | <4.4 | U | | <34 | U | | <6.4 | U | | <6.4 | U | |
| | | VMP-21-33-041411 | 4/14/2011 | <14 | U | | <39 | UJ | UJ | <19 | U | | <17 | U | | <27 | U | | <27 | U | | <12 | U | UJ | 8.9 | J | | <120 | U | | <21 | U | | <21 | U | |
| | | VMP-21-33-110511 | 11/5/2011 | <0.69 | U | | 0.4 | J | | <0.94 | U | | <0.81 | U | | <1.3 | U | | 0.35 | J | | <0.56 | U | | 0.55 | J | | <5.7 | U | | <1 | U | | <1 | U | |
| | | VMP-21-33-012412 | 1/24/2012 | <0.099 | U | | <0.27 | U | | <0.13 | U | | <0.12 | U | | <0.19 | U | | <0.18 | U | | <0.081 | U | | 0.033 | J | J | <0.81 | U | | <0.15 | U | | <0.15 | U | |
| | | VMP-21-33-042412 | 4/24/2012 | <0.0034 | U | | 0.015 | | | <0.0046 | U | | 0.00092 | J | | <0.0064 | U | | 0.012 | | | <0.0028 | U | | 0.0082 | | | <0.028 | U | | <0.0051 | U | | <0.0051 | U | |
| | | VMP-21-33-071112 | 7/11/2012 | <0.0035 | U | | 0.0034 | J | | <0.0048 | U | | <0.0042 | U | | <0.0067 | U | | 0.0022 | J | | 0.0017 | J | | <0.0037 | J | U | <0.029 | U | | <0.0053 | U | | <0.0053 | U | |
| | | VMP-21-33-100412 | 10/4/2012 | <0.0051 | U | | 0.027 | | | <0.0069 | U | | <0.006 | J | U | <0.0097 | U | | 0.01 | | | <0.0042 | U | | 0.012 | | | <0.042 | U | | <0.0077 | U | | <0.0077 | U | |
| | | VMP-21-33-020513 | 2/5/2013 | <0.0048 | U | | 0.029 | | | <0.0065 | U | | <0.0056 | U | | <0.0091 | U | | 0.034 | | | <0.0039 | U | | <0.005 | U | | <0.039 | U | | <0.0072 | U | | <0.0072 | U | |

SEE LAST PAGE OF TABLE FOR NOTES

**TABLE 5**
**CUMULATIVE SUMMARY OF SOIL VAPOR ANALYTICAL DETECTIONS AND SCREENING RESULTS: VILLAGE - VOCS**

| Location | Depth | Sample ID | Sample Date | Methyl tert-Butyl Ether (MTBE) 3400 | | | 2-Propanol | | | n-Propylbenzene | | | Styrene 1400 | | | 1,1,2,2-Tetrachloroethane | | | Tetrachloroethene 0.55 | | | Tetrahydrofuran | | | Toluene 6200 | | | 1,2,4-Trichlorobenzene 11 | | | 1,1,1-Trichloroethane (Methyl chloroform) 6600 | | | 1,1,2-Trichloroethane 170000 | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals |
| VMP-22 | 5 ft | VMP-22-5-021111 | 2/11/2011 | <0.093 | U | | <0.25 | U | | <0.13 | U | | <0.11 | U | | <0.18 | U | | <0.17 | U | | <0.076 | U | | <0.097 | U | | <0.76 | U | | <0.14 | U | | <0.14 | U | |
| | | VMP-22-5-041811 | 4/18/2011 | <0.045 | U | | <0.12 | UJ | UJ | <0.062 | U | | <0.054 | U | | <0.086 | U | | <0.085 | U | | <0.037 | U | UJ | <0.047 | U | | <0.37 | U | | <0.069 | U | | <0.069 | U | |
| | | VMP-22-5-072611 | 7/26/2011 | <0.0053 | U | | 0.04 | | | 0.0016 | J | | <0.0063 | J | U | <0.01 | U | | <0.01 | J | UJ | <0.0044 | U | | 0.016 | | | <0.044 | J | U | <0.0081 | U | | <0.0081 | U | |
| | | VMP-22-5-110111 | 11/1/2011 | <0.003 | U | | 0.012 | | | <0.0041 | U | | <0.0036 | U | | <0.0058 | U | | <0.0057 | U | | <0.0025 | U | | 0.011 | | | <0.025 | U | | <0.0046 | U | | <0.0046 | U | |
| | | VMP-22-5-012412 | 1/24/2012 | <0.0032 | U | | 0.0081 | J | J | <0.0044 | J | U | <0.0038 | U | | <0.0061 | U | | <0.006 | U | | <0.0026 | U | | 0.023 | | J | <0.026 | U | | <0.0048 | U | | <0.0048 | U | |
| | | VMP-22-5-040912 | 4/9/2012 | <0.0035 | U | | 0.012 | | | <0.0048 | U | | <0.0042 | U | | <0.0067 | U | | <0.0066 | U | | <0.0029 | U | | 0.0058 | | | <0.029 | U | | <0.0053 | U | | <0.0053 | U | |
| | | VMP-22-5-070912 | 7/9/2012 | <0.0039 | U | | 0.0083 | J | | <0.0053 | J | U | <0.0046 | U | | <0.0074 | U | | <0.0074 | U | | <0.0032 | U | | 0.01 | | | <0.032 | U | | <0.0059 | U | | <0.0059 | U | |
| | | VMP-22-5-100312 | 10/3/2012 | <0.0045 | U | | 0.0082 | J | | <0.0062 | U | | <0.0054 | U | | <0.0086 | U | | <0.0085 | U | | <0.0037 | U | | 0.0018 | J | | <0.037 | U | | <0.0069 | U | | <0.0069 | U | |
| | | VMP-22-5-100312-Dup | 10/3/2012 | <0.0041 | U | | 0.029 | | | <0.0056 | U | | <0.0049 | U | | <0.0079 | U | | <0.0078 | U | | <0.0034 | U | | 0.0066 | | | <0.034 | U | | <0.0062 | U | | <0.0062 | U | |
| | | VMP-22-5-012413 | 1/24/2013 | <0.0046 | U | | 0.0011 | J | | <0.0063 | U | | <0.0055 | U | | <0.0088 | U | | <0.0088 | J | U | <0.0038 | U | | <0.0049 | J | U | <0.038 | J | U | <0.007 | U | | <0.007 | U | |
| | 10 ft | VMP-22-10-021111 | 2/11/2011 | <0.044 | U | | <0.12 | U | | <0.06 | U | | <0.052 | U | | <0.084 | U | | <0.083 | U | | <0.036 | U | | <0.046 | U | | <0.36 | U | | <0.068 | U | | <0.066 | U | |
| | | VMP-22-10-041811 | 4/18/2011 | <0.047 | U | | <0.13 | UJ | UJ | <0.064 | U | | <0.056 | U | | <0.09 | U | | <0.088 | U | | <0.038 | U | UJ | <0.049 | U | | <0.39 | U | | <0.071 | U | | <0.071 | U | |
| | | VMP-22-10-072611 | 7/26/2011 | <0.0055 | U | | 0.016 | | | 0.001 | J | | 0.0029 | J | | <0.01 | U | | <0.01 | J | UJ | <0.0045 | U | | 0.013 | | | <0.045 | J | U | <0.0083 | U | | <0.0083 | U | |
| | | VMP-22-10-072611-DUP | 7/26/2011 | <0.0064 | U | | 0.018 | | | 0.0012 | J | | 0.0028 | J | | <0.012 | U | | <0.012 | U | UJ | <0.0052 | U | | 0.012 | | | <0.053 | J | U | <0.0097 | U | | <0.0097 | U | |
| | | VMP-22-10-110211 | 11/2/2011 | <0.0031 | U | | 0.009 | | | <0.0042 | U | | <0.0036 | U | | <0.0059 | U | | <0.0058 | U | | <0.0025 | U | | 0.006 | | | <0.025 | U | | <0.0047 | U | | <0.0047 | U | |
| | | VMP-22-10-012412 | 1/24/2012 | <0.0035 | U | | 0.011 | | | <0.0048 | J | U | <0.0041 | U | | <0.0066 | U | | 0.0033 | J | | 0.0014 | J | | 0.0071 | | | <0.029 | U | | <0.0053 | U | | <0.0053 | U | |
| | | VMP-22-10-040912 | 4/9/2012 | <0.0035 | U | | 0.012 | | | 0.0028 | J | | <0.0041 | U | | <0.0066 | U | | <0.0065 | U | | <0.0028 | U | | 0.0052 | | | <0.029 | U | | <0.0053 | U | | <0.0053 | U | |
| | | VMP-22-10-070912 | 7/9/2012 | <0.0039 | U | | 0.0054 | J | | <0.0053 | U | | <0.0046 | U | | <0.0074 | U | | <0.0074 | U | | <0.0032 | U | | <0.0041 | J | U | <0.032 | U | | <0.0059 | U | | <0.0059 | U | |
| | | VMP-22-10-070912-Dup | 7/9/2012 | <0.0038 | U | | 0.0066 | J | | <0.0052 | U | | <0.0045 | U | | <0.0073 | U | | <0.0072 | U | | <0.0031 | U | | 0.0022 | J | | <0.031 | U | | <0.0058 | U | | <0.0058 | U | |
| | | VMP-22-10-100312 | 10/3/2012 | <0.0044 | U | | 0.021 | | | <0.0059 | U | | <0.0052 | U | | <0.0083 | U | | <0.0082 | U | | <0.0036 | U | | 0.0063 | | | <0.036 | U | | <0.0066 | U | | <0.0066 | U | |
| | | VMP-22-10-012413 | 1/24/2013 | <0.005 | U | | 0.0052 | J | | <0.0068 | U | | <0.0059 | U | | <0.0095 | U | | <0.0094 | U | | <0.0041 | U | | <0.0052 | J | U | <0.041 | J | U | <0.0075 | U | | <0.0075 | U | |
| | 18 ft | VMP-22-18-021111 | 2/11/2011 | <0.77 | U | | <2.1 | U | | <1 | U | | <0.9 | U | | <1.4 | U | | <1.4 | U | | <0.63 | U | | 0.34 | J | | <6.3 | U | | <1.2 | U | | <1.2 | U | |
| | | VMP-22-18-041811 | 4/18/2011 | <3.2 | U | | <8.8 | UJ | UJ | <4.4 | U | | <3.8 | U | | <6.2 | U | | <6.1 | U | | <2.6 | U | UJ | <3.4 | U | | <27 | U | | <4.9 | U | | <4.9 | U | |
| | | VMP-22-18-072611 | 7/26/2011 | <1.6 | U | | <4.5 | U | | <2.3 | U | | <2 | U | | <3.2 | U | | <3.1 | U | UJ | <1.4 | U | | <1.7 | U | | <14 | U | | <2.5 | U | | <2.5 | U | |
| | | VMP-22-18-110511 | 11/5/2011 | <0.0033 | U | | 0.0073 | J | | 0.00027 | J | | <0.0039 | U | | <0.0063 | U | | <0.0062 | J | U | <0.0027 | U | | 0.012 | | | <0.027 | U | | <0.005 | U | | <0.005 | U | |
| | | VMP-22-18-012412 | 1/24/2012 | <0.03 | U | | 0.029 | J | J | <0.041 | U | | <0.036 | U | | <0.058 | U | | <0.057 | U | | <0.025 | U | | <0.032 | U | | <0.25 | U | | <0.046 | U | | <0.046 | U | |
| | | VMP-22-18-040912 | 4/9/2012 | <0.0036 | U | | <0.0099 | U | | 0.0013 | J | | <0.0043 | U | | <0.0069 | U | | <0.0068 | U | | <0.003 | U | | 0.0038 | | | <0.03 | U | | <0.0055 | U | | <0.0055 | U | |
| | | VMP-22-18-070912 | 7/9/2012 | <0.0038 | U | | 0.0074 | J | | <0.0052 | U | | <0.0045 | U | | <0.0073 | U | | <0.0072 | U | | <0.0031 | U | | 0.0029 | J | | <0.031 | U | | <0.0058 | U | | <0.0058 | U | |
| | | VMP-22-18-100412 | 10/4/2012 | <0.0052 | U | | 0.033 | | | <0.0071 | U | | <0.0062 | U | | <0.0099 | U | | <0.0098 | U | | 0.0066 | | | 0.0017 | J | | <0.043 | U | | <0.0079 | U | | <0.0079 | U | |
| | | VMP-22-18-012413 | 1/24/2013 | <0.005 | U | | 0.0073 | J | | <0.0068 | U | | <0.0059 | U | | <0.0095 | U | | <0.0094 | J | U | <0.0041 | U | | <0.0052 | J | U | <0.041 | U | | <0.0075 | U | | <0.0075 | U | |
| | 38 ft | VMP-22-38-041811 | 4/18/2011 | <10 | U | | <27 | UJ | UJ | <14 | U | | <12 | U | | <19 | U | | <19 | U | | <8.1 | U | UJ | <10 | U | | <82 | U | | <15 | U | | <15 | U | |
| | | VMP-22-38-012512 | 1/25/2012 | <0.03 | U | | <0.082 | U | | <0.041 | U | | <0.036 | U | | <0.058 | U | | <0.057 | U | | <0.025 | U | | <0.032 | U | | <0.25 | U | | <0.046 | U | | <0.046 | U | |
| | | VMP-22-38-040912 | 4/9/2012 | <0.0035 | U | | 0.01 | | | <0.0048 | U | | <0.0042 | U | | <0.0067 | U | | <0.0066 | U | | 0.0012 | J | | 0.013 | | | <0.029 | U | | <0.0053 | U | | <0.0053 | U | |
| | | VMP-22-38-070912 | 7/9/2012 | <0.0037 | U | | 0.011 | | | <0.0051 | U | | <0.0044 | U | | <0.0071 | U | | <0.007 | U | | <0.003 | U | | 0.0028 | J | | <0.03 | U | | <0.0056 | U | | <0.0056 | U | |
| | | VMP-22-38-100412 | 10/4/2012 | <0.0055 | U | | <0.015 | U | | <0.0074 | U | | <0.0064 | U | | <0.01 | U | | 0.011 | | | <0.0045 | U | | 0.0026 | J | | <0.045 | J | U | <0.0083 | U | | <0.0083 | U | |
| | | VMP-22-38-012413 | 1/24/2013 | <0.0048 | U | | 0.0061 | J | | <0.0066 | U | | <0.0057 | U | | <0.0092 | U | | <0.0091 | J | U | <0.004 | U | | <0.0051 | J | U | <0.04 | J | U | <0.0073 | U | | <0.0073 | U | |
| VMP-23 | 5 ft | VMP-23-5-021511 | 2/15/2011 | <0.0048 | U | | 0.0033 | J | | <0.0065 | U | | <0.0056 | U | | <0.0091 | U | | <0.009 | U | | <0.0039 | U | | 0.013 | | | <0.039 | U | | <0.0072 | U | | <0.0072 | U | |
| | | VMP-23-5-042111 | 4/21/2011 | <0.041 | U | | 0.015 | J | | <0.056 | U | | <0.49 | U | | <0.079 | U | | <0.078 | U | | <0.034 | U | | <0.043 | U | | <0.34 | U | | <0.062 | U | | <0.062 | U | |
| | | VMP-23-5-072711 | 7/27/2011 | <0.0048 | U | | 0.14 | | | 0.00076 | J | | 0.0013 | J | | <0.0091 | U | | <0.009 | U | | <0.0039 | U | | 0.037 | | | <0.039 | U | | <0.0072 | U | | <0.0072 | U | |
| | | VMP-23-5-110211 | 11/2/2011 | <0.0034 | U | | 0.014 | | | <0.0046 | U | | <0.004 | U | | <0.0064 | U | | <0.0063 | U | | <0.0028 | U | | 0.0098 | | | <0.028 | U | | <0.0051 | U | | <0.0051 | U | |
| | | VMP-23-5-012512 | 1/25/2012 | <0.0028 | U | | 0.0018 | J | | 0.0008 | J | | <0.0034 | U | | <0.0054 | U | | 0.0021 | J | | <0.0023 | U | | 0.0043 | | | <0.023 | U | | <0.0043 | U | | <0.0043 | U | |
| | | VMP-23-5-040912 | 4/9/2012 | <0.0034 | U | | 0.023 | | | <0.0047 | U | | <0.0041 | U | | <0.0066 | U | | <0.0065 | U | | 0.026 | | | 0.022 | | | <0.028 | U | | <0.0052 | U | | <0.0052 | U | |
| | | VMP-23-5-070912 | 7/9/2012 | <0.0031 | U | | <0.0084 | U | | <0.0042 | J | U | <0.0036 | J | U | <0.0059 | U | | <0.0058 | U | | 0.013 | | | 0.011 | | | <0.025 | U | | <0.0047 | U | | <0.0047 | U | |
| | | VMP-23-5-100312 | 10/3/2012 | <0.0052 | U | | <0.014 | U | | <0.0071 | U | | <0.0062 | U | | <0.0099 | U | | <0.0098 | U | | <0.0043 | U | | 0.0013 | J | | <0.043 | J | U | <0.0079 | U | | <0.0079 | U | |
| | | VMP-23-5-012413 | 1/24/2013 | <0.0044 | U | | 0.004 | J | | <0.0061 | U | | <0.0053 | U | | <0.0085 | U | | <0.0084 | U | | <0.0036 | U | | <0.0046 | J | U | <0.037 | J | U | <0.0067 | U | | <0.0067 | U | |
| | 10 ft | VMP-23-10-021511 | 2/15/2011 | <0.0049 | U | | 0.0045 | J | | <0.0067 | J | U | <0.0058 | U | | <0.0094 | U | | 0.0015 | J | | <0.004 | U | | 0.0062 | | | 0.0094 | J | | <0.0074 | U | | <0.0074 | U | |
| | | VMP-23-10-042111 | 4/21/2011 | <0.05 | U | | 0.012 | J | | <0.068 | U | | <0.59 | U | | <0.095 | U | | <0.094 | U | | <0.041 | U | | 0.25 | | | <0.41 | U | | <0.075 | U | | <0.075 | U | |
| | | VMP-23-10-072711 | 7/27/2011 | <0.0045 | U | | <0.012 | U | | <0.0062 | U | | <0.0054 | U | | <0.0086 | U | | <0.0085 | U | | <0.0037 | U | | <0.0047 | U | | <0.037 | U | | <0.0069 | U | | <0.0069 | U | |
| | | VMP-23-10-110211 | 11/2/2011 | <0.0033 | U | | 0.02 | | | <0.0045 | J | U | <0.0039 | U | | <0.0063 | U | | <0.0062 | U | | <0.0027 | U | | 0.014 | | | <0.027 | U | | <0.005 | U | | <0.005 | U | |
| | | VMP-23-10-012512 | 1/25/2012 | <0.0028 | U | | 0.0064 | J | | 0.00047 | J | | <0.0033 | U | | <0.0053 | U | | 0.0031 | J | | <0.0023 | U | | 0.017 | | | <0.023 | U | | <0.0042 | U | | <0.0042 | U | |
| | | VMP-23-10-040912 | 4/9/2012 | <0.0035 | U | | <0.0096 | U | | <0.0048 | U | | <0.0042 | U | | <0.0067 | U | | <0.0066 | U | | <0.0029 | U | | 0.011 | | | <0.029 | U | | <0.0053 | U | | <0.0053 | U | |
| | | VMP-23-10-040912-Dup | 4/9/2012 | <0.0035 | U | | 0.0075 | J | | <0.0048 | U | | <0.0042 | U | | <0.0067 | U | | 0.0056 | J | | 0.0029 | | | 0.013 | | | <0.029 | U | | <0.0053 | U | | <0.0053 | U | |
| | | VMP-23-10-070912 | 7/9/2012 | <0.0028 | U | | 0.0042 | J | | <0.0038 | J | U | <0.0033 | J | U | <0.0053 | U | | <0.0052 | U | | 0.0047 | | | <0.0029 | J | U | <0.023 | U | | <0.0042 | U | | <0.0042 | U | |
| | | VMP-23-10-100312 | 10/3/2012 | <0.0056 | U | | 0.004 | J | | <0.0076 | U | | <0.0066 | U | | <0.011 | U | | <0.01 | U | | <0.0046 | U | | 0.0018 | J | | <0.046 | U | | <0.0085 | U | | <0.0085 | U | |
| | | VMP-23-10-012413 | 1/24/2013 | <0.0044 | U | | 0.0047 | J | | <0.0061 | U | | <0.0053 | U | | <0.0085 | U | | <0.0084 | U | | <0.0036 | U | | <0.0046 | J | U | <0.037 | U | | <0.0067 | U | | <0.0067 | U | |
| | 25 ft | VMP-23-25-021511 | 2/15/2011 | <0.0045 | U | | 0.094 | | | <0.0062 | U | | <0.0054 | U | | <0.0086 | U | | <0.0085 | U | | <0.0037 | U | | 0.0011 | J | | <0.037 | U | | <0.0069 | U | | <0.0069 | U | |
| | | VMP-23-25-042111 | 4/21/2011 | <0.046 | U | | <0.13 | U | | <0.063 | U | | <0.55 | U | | <0.088 | U | | <0.088 | U | | <0.038 | U | | <0.049 | U | | <0.38 | U | | <0.07 | U | | <0.07 | U | |
| | | VMP-23-25-072711 | 7/27/2011 | <0.0052 | U | | 0.047 | | | <0.0071 | U | | 0.0021 | J | | <0.0099 | U | | <0.0098 | U | | <0.0043 | U | | 0.016 | | | 0.012 | J | | <0.0079 | U | | <0.0079 | U | |
| | | VMP-23-25-110511 | 11/5/2011 | <0.0033 | U | | 0.019 | | | <0.0045 | U | | <0.0039 | U | | <0.0063 | U | | <0.0062 | J | U | <0.0027 | U | | 0.015 | | | <0.027 | U | | <0.005 | U | | <0.005 | U | |
| | | VMP-23-25-012512 | 1/25/2012 | <0.003 | U | | 0.0082 | | | <0.004 | U | | <0.0035 | U | | <0.0056 | U | | 0.0026 | J | | <0.0024 | U | | 0.019 | | | <0.024 | U | | <0.0045 | U | | <0.0045 | U | |
| | | VMP-23-25-040912 | 4/9/2012 | <0.0034 | U | | 0.63 | | | 0.0011 | J | | 0.013 | | | <0.0066 | U | | <0.0065 | U | | 0.044 | | | 0.25 | | | <0.028 | U | | <0.0052 | U | | <0.0052 | U | |
| | | VMP-23-25-071012 | 7/10/2012 | <0.0044 | U | | 0.002 | J | | <0.006 | J | U | <0.0052 | J | U | <0.0084 | U | | <0.0083 | U | | 0.01 | | | 0.0058 | | | <0.036 | U | | <0.0066 | U | | <0.0066 | U | |
| | | VMP-23-25-100312 | 10/3/2012 | <0.0055 | U | | <0.015 | U | | <0.0074 | U | | <0.0064 | U | | <0.01 | U | | <0.01 | U | | <0.0045 | U | | 0.0018 | J | | <0.045 | U | | <0.0083 | U | | <0.0083 | U | |
| | | VMP-23-25-012413 | 1/24/2013 | <0.0045 | U | | 0.0019 | J | | <0.0062 | U | | <0.0054 | U | | <0.0086 | U | | <0.0085 | J | U | <0.0037 | U | | <0.0047 | J | U | <0.037 | U | | <0.0069 | U | | <0.0069 | U | |
| | 40 ft | VMP-23-40-071012 | 7/10/2012 | <0.0037 | U | | <0.01 | U | | <0.0051 | J | U | <0.0044 | J | U | <0.0071 | U | | <0.007 | U | | <0.003 | U | | 0.0058 | | | <0.03 | U | | <0.0056 | U | | <0.0056 | U | |
| | | VMP-23-40-100312 | 10/3/2012 | <0.0051 | U | | 0.0034 | J | | <0.0069 | U | | <0.006 | U | | <0.0096 | U | | <0.0095 | U | | <0.0041 | U | | 0.0022 | J | | <0.042 | U | | <0.0077 | U | | <0.0077 | U | |
| | | VMP-23-40-012413 | 1/24/2013 | <0.0046 | U | | 0.0021 | J | | <0.0063 | U | | <0.0055 | U | | <0.0088 | U | | <0.0088 | U | | <0.0038 | U | | <0.0049 | U | | <0.038 | U | | <0.007 | U | | <0.007 | U | |

SEE LAST PAGE OF TABLE FOR NOTES

**TABLE 5**
**CUMULATIVE SUMMARY OF SOIL VAPOR ANALYTICAL DETECTIONS AND SCREENING RESULTS: VILLAGE - VOCS**

| Location | Depth | Sample ID | Sample Date | Methyl tert-Butyl Ether (MTBE) 3400 | | | 2-Propanol 1400 | | | n-Propylbenzene | | | Styrene 1400 | | | 1,1,2,2-Tetrachloroethane | | | Tetrachloroethene 0.55 | | | Tetrahydrofuran | | | Toluene 6200 | | | 1,2,4-Trichlorobenzene 11 | | | 1,1,1-Trichloroethane (Methyl chloroform) 6600 | | | 1,1,2-Trichloroethane 170000 | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals |
| VMP-24 | 5 ft | VMP-24-5-021611 | 2/16/2011 | <0.0051 | U | | 0.0033 | J | | <0.0069 | J | U | <0.006 | U | | <0.0097 | U | | <0.0096 | U | | <0.0042 | U | | <0.0053 | J | U | <0.042 | J | U | <0.0077 | U | | <0.0077 | U | |
| | | VMP-24-5-040811 | 4/8/2011 | <0.054 | U | | <0.15 | U | | <0.074 | U | | <0.064 | U | | <0.1 | U | | <0.1 | U | | <0.044 | U | | <0.057 | U | | <0.45 | U | | <0.082 | U | | <0.082 | U | |
| | | VMP-24-5-072811 | 7/28/2011 | <0.0051 | U | | 0.019 | | | 0.0014 | J | | 0.0018 | J | | <0.0097 | U | | <0.0096 | U | | <0.0042 | U | | 0.045 | | | 0.0082 | J | | <0.0077 | U | | <0.0077 | U | |
| | | VMP-24-5-110211 | 11/2/2011 | <0.0034 | U | | 0.0072 | J | | <0.0046 | J | U | <0.004 | U | | <0.0064 | U | | <0.0063 | U | | <0.0028 | U | | 0.0068 | | | <0.028 | U | | <0.0051 | U | | <0.0051 | U | |
| | | VMP-24-5-110211-DUP | 11/2/2011 | <0.0047 | U | | 0.017 | | | <0.0064 | J | U | <0.0055 | U | | <0.0089 | U | | <0.0088 | U | | <0.0038 | U | | 0.0069 | | | <0.038 | U | | <0.0071 | U | | <0.0071 | U | |
| | | VMP-24-5-012512 | 1/25/2012 | <0.0029 | U | | 0.011 | | | <0.004 | U | | <0.0034 | U | | <0.0055 | U | | <0.0055 | U | | 0.00072 | J | | 0.011 | | | <0.024 | U | | <0.0044 | U | | <0.0044 | U | |
| | | VMP-24-5-040912 | 4/9/2012 | <0.0034 | U | | 0.16 | | | 0.0022 | J | | 0.0044 | | | <0.0066 | U | | <0.0065 | U | | 0.038 | | | 0.045 | | | <0.028 | U | | <0.0052 | U | | <0.0052 | U | |
| | | VMP-24-5-071212 | 7/12/2012 | <0.0033 | U | | <0.009 | U | | 0.002 | J | | <0.0039 | J | U | <0.0063 | U | | <0.0062 | U | | 0.0057 | | | 0.053 | | | <0.027 | U | | <0.005 | U | | <0.005 | U | |
| | | VMP-24-5-101912 | 10/19/2012 | <0.0051 | U | | 0.003 | J | | <0.007 | U | | <0.006 | U | | <0.0097 | U | | 0.004 | J | | <0.0042 | U | | 0.0023 | J | | <0.042 | U | | <0.0077 | U | | <0.0077 | U | |
| | | VMP-24-5-012313 | 1/23/2013 | <0.0045 | U | | 0.036 | | | <0.0062 | U | | <0.0054 | U | | <0.0086 | U | | <0.0085 | U | | <0.0037 | U | | <0.0047 | J | U | <0.037 | U | | <0.0069 | U | | <0.0069 | U | |
| | 10 ft | VM-24-10-021711 | 2/17/2011 | <0.0048 | U | | 0.0065 | J | | <0.0066 | J | U | <0.0057 | U | | <0.0092 | U | | <0.0091 | U | | <0.004 | U | | <0.0051 | J | U | <0.04 | U | | <0.0073 | U | | <0.0073 | U | |
| | | VMP-24-10-041111 | 4/11/2011 | 0.00079 | J | | <0.025 | U | | <0.012 | U | | <0.011 | U | | <0.017 | U | | 0.0033 | J | | <0.0074 | U | | 0.0025 | J | | <0.075 | U | | <0.014 | U | | <0.014 | U | |
| | | VMP-24-10-072811 | 7/28/2011 | <0.005 | U | | 0.038 | | | 0.0011 | J | | 0.0019 | J | | <0.0095 | U | | <0.0094 | U | | <0.0041 | U | | 0.024 | | | 0.0052 | J | | <0.0075 | U | | <0.0075 | U | |
| | | VMP-24-10-110211 | 11/2/2011 | <0.003 | U | | 0.011 | | | <0.004 | U | | <0.0035 | U | | <0.0056 | U | | <0.0056 | U | | <0.0024 | U | | 0.012 | | | <0.024 | U | | <0.0045 | U | | <0.0045 | U | |
| | | VMP-24-10-012512 | 1/25/2012 | <0.0028 | U | | 0.0054 | J | | 0.00041 | J | | <0.0033 | U | | <0.0053 | U | | <0.0052 | U | | <0.0023 | U | | 0.0045 | | | <0.023 | U | | <0.0042 | U | | <0.0042 | U | |
| | | VMP-24-10-041012 | 4/10/2012 | <0.0033 | U | | 0.1 | | | <0.0045 | U | | <0.0039 | U | | <0.0063 | U | | <0.0062 | U | | 0.022 | | | 0.076 | | | <0.027 | U | | <0.005 | U | | <0.005 | U | |
| | | VMP-24-10-071212 | 7/12/2012 | <0.0038 | U | | 0.045 | | | <0.0052 | J | U | <0.0045 | J | U | <0.0073 | U | | <0.0072 | U | | 0.0019 | J | | 0.049 | | | <0.031 | U | | <0.0058 | U | | <0.0058 | U | |
| | | VMP-24-10-100912 | 10/9/2012 | <0.0048 | U | | 0.074 | | | <0.0065 | U | | <0.0056 | U | | <0.0091 | U | | <0.009 | U | | <0.0039 | U | | 0.0042 | J | | <0.039 | U | | <0.0072 | U | | <0.0072 | U | |
| | | VMP-24-10-012313 | 1/23/2013 | <0.005 | U | | 0.016 | | | <0.0068 | U | | <0.0059 | U | | <0.0095 | U | | <0.0094 | J | U | <0.0041 | U | | 0.0013 | J | | <0.041 | U | | <0.0075 | U | | <0.0075 | U | |
| | 22 ft | VMP-24-22-021711 | 2/17/2011 | <0.0048 | U | | 0.0063 | J | | <0.0066 | J | U | <0.0057 | U | | <0.0092 | U | | 0.0014 | J | | <0.004 | U | | 0.0049 | J | | <0.04 | U | | <0.0073 | U | | <0.0073 | U | |
| | | VMP-24-22-041111 | 4/11/2011 | <0.0045 | U | | <0.012 | U | | <0.0062 | U | | <0.0054 | U | | <0.0086 | U | | 0.0025 | J | | <0.0037 | U | | <0.0047 | U | | <0.037 | U | | <0.0069 | U | | <0.0069 | U | |
| | | VMP-24-22-072811 | 7/28/2011 | <0.0045 | U | | 0.014 | | | 0.00067 | J | | 0.0014 | J | | <0.0086 | U | | <0.0085 | U | | <0.0037 | U | | 0.006 | | | 0.0039 | J | | <0.0069 | U | | <0.0069 | U | |
| | | VMP-24-22-072811-Dup | 7/28/2011 | <0.0052 | U | | 0.014 | | | 0.00064 | J | | 0.0013 | J | | <0.0099 | U | | <0.0098 | U | | 0.0042 | | | 0.009 | | | <0.043 | U | | <0.0079 | U | | <0.0079 | U | |
| | | VMP-24-22-110611 | 11/6/2011 | <0.0032 | U | | 0.02 | | | <0.0043 | U | | 0.00052 | J | | <0.006 | U | | <0.0059 | J | U | <0.0026 | U | | 0.011 | | | <0.026 | U | | <0.0048 | U | | <0.0048 | U | |
| | | VMP-24-22-012512 | 1/25/2012 | <0.003 | U | | 0.0078 | J | | <0.004 | U | | <0.0035 | U | | <0.0056 | U | | <0.0056 | U | | <0.0024 | U | | 0.0034 | | | <0.024 | U | | <0.0045 | U | | <0.0045 | U | |
| | | VMP-24-22-041012 | 4/10/2012 | <0.0032 | U | | 0.21 | | | <0.0044 | U | | <0.0038 | U | | <0.0061 | U | | <0.0061 | U | | 0.032 | | | 0.066 | | | 0.015 | J | | <0.0049 | U | | <0.0049 | U | |
| | | VMP-24-22-071212 | 7/12/2012 | <0.0039 | U | | 0.03 | | | <0.0053 | U | | <0.0046 | J | U | <0.0074 | U | | <0.0074 | U | | 0.0012 | J | | 0.034 | | | <0.032 | U | | <0.0059 | U | | <0.0059 | U | |
| | | VMP-24-22-100912 | 10/9/2012 | <0.0048 | U | | 0.051 | | | <0.0066 | U | | <0.0057 | U | | <0.0092 | U | | <0.0091 | U | | <0.004 | U | | <0.0051 | U | | <0.04 | U | | <0.0073 | U | | <0.0073 | U | |
| | | VMP-24-22-012313 | 1/23/2013 | <0.0051 | U | | 0.0098 | J | | <0.0069 | U | | <0.006 | U | | <0.0097 | U | | <0.0096 | J | U | <0.0042 | U | | <0.0053 | J | U | <0.042 | U | | <0.0077 | U | | <0.0077 | U | |
| | 34 ft | VMP-24-34-021711 | 2/17/2011 | <0.0048 | U | | 0.0026 | J | | <0.0066 | U | | <0.0057 | U | | <0.0092 | U | | <0.0091 | U | | 0.0014 | J | | <0.0051 | J | U | <0.04 | U | | <0.0073 | U | | <0.0073 | U | |
| | | VMP-24-34-041111 | 4/11/2011 | 0.00059 | J | | 0.0052 | J | | <0.0059 | U | | <0.0052 | U | | <0.0083 | U | | 0.0021 | J | | <0.0036 | U | | 0.00092 | J | | <0.036 | U | | <0.0066 | U | | <0.0066 | U | |
| | | VMP-24-34-072811 | 7/28/2011 | <0.0038 | U | | 0.02 | | | 0.00058 | J | | 0.0015 | J | | <0.0073 | U | | <0.0072 | U | | <0.0031 | U | | 0.0081 | | | <0.032 | U | | <0.0058 | U | | <0.0058 | U | |
| | | VMP-24-34-110611 | 11/6/2011 | <0.0024 | U | | 0.017 | | | 0.00035 | J | | <0.0029 | U | | <0.0047 | U | | <0.0046 | J | U | 0.002 | J | | 0.027 | | | <0.02 | U | | <0.0037 | U | | <0.0037 | U | |
| | | VMP-24-34-012512 | 1/25/2012 | <0.003 | U | | 0.0084 | | | <0.0041 | U | | <0.0036 | U | | <0.0058 | U | | <0.0057 | U | | <0.0025 | U | | 0.0051 | | | 0.0045 | J | | <0.0046 | U | | <0.0046 | U | |
| | | VMP-24-34-041012 | 4/10/2012 | <0.0034 | U | | 0.049 | | | 0.0025 | J | | 0.0012 | J | | <0.0064 | U | | <0.0063 | U | | 0.0033 | | | 0.02 | | | <0.028 | U | | <0.0051 | U | | <0.0051 | U | |
| | | VMP-24-34-071212 | 7/12/2012 | <0.0032 | U | | 0.053 | | | <0.0044 | J | U | <0.0038 | J | U | <0.0061 | U | | <0.0061 | U | | 0.0013 | J | | 0.038 | | | <0.026 | U | | <0.0049 | U | | <0.0049 | U | |
| | | VMP-24-34-100912 | 10/9/2012 | <0.005 | U | | 0.07 | | | <0.0068 | U | | <0.0059 | U | | <0.0095 | U | | <0.0094 | U | | <0.0041 | U | | 0.0019 | J | | <0.041 | U | | <0.0075 | U | | <0.0075 | U | |
| | | VMP-24-34-012313 | 1/23/2013 | <0.0052 | U | | 0.0032 | J | | <0.0071 | U | | <0.0062 | U | | <0.0099 | U | | <0.0098 | J | U | <0.0043 | U | | <0.0054 | J | U | <0.043 | U | | <0.0079 | U | | <0.0079 | U | |
| VMP-31 | 5 ft | VMP-31-5-042512 | 4/25/2012 | <0.0034 | U | | 0.039 | | | <0.0047 | U | | 0.0031 | J | | <0.0066 | U | | <0.0065 | J | U | 0.0046 | | | 0.02 | | | <0.028 | U | | <0.0052 | U | | <0.0052 | U | |
| | | VMP-31-5-072012 | 7/20/2012 | <0.0034 | U | | 0.021 | | | 0.00036 | J | | <0.0041 | U | | <0.0066 | U | | <0.0065 | U | | 0.0013 | J | | 0.0099 | | | <0.028 | U | | <0.0052 | U | | <0.0052 | U | |
| | | VMP-31-5-102612 | 10/26/2012 | <0.005 | U | | 0.062 | | J | 0.00077 | J | | 0.00068 | J | | <0.0095 | U | | <0.0094 | U | | 0.002 | J | | 0.0099 | | | <0.1 | U | UJ | <0.0075 | U | | <0.0075 | U | |
| | | VMP-31-5-021113 | 2/11/2013 | <0.0046 | U | | 0.064 | | | 0.0057 | J | | <0.0055 | U | | <0.0088 | U | | <0.0088 | J | U | <0.0038 | U | | 0.011 | | | <0.038 | J | U | <0.007 | U | | <0.007 | U | |
| | 10 ft | VMP-31-10-042512 | 4/25/2012 | <0.0046 | U | | 0.033 | | | <0.0063 | J | U | 0.0032 | J | | <0.0088 | U | | 0.0051 | J | | 0.03 | | | 0.018 | | | <0.038 | U | | <0.007 | U | | <0.007 | U | |
| | | VMP-31-10-072612 | 7/26/2012 | <0.0035 | U | | 0.012 | | | 0.0094 | J | | 0.0035 | J | | <0.0067 | U | | <0.0029 | U | | 0.0018 | J | | 0.061 | | | <0.029 | U | | <0.0053 | U | | <0.0053 | U | |
| | | VMP-31-10-102612 | 10/26/2012 | <0.0053 | U | | 0.12 | | J | 0.0012 | J | | <0.0063 | U | | <0.01 | U | | <0.01 | U | | 0.001 | J | | 0.0065 | | | <0.11 | U | UJ | <0.0081 | U | | <0.0081 | U | |
| | | VMP-31-10-021313 | 2/13/2013 | <0.0051 | U | | <0.014 | U | | 0.0042 | J | | <0.006 | U | | <0.0097 | U | | <0.0096 | U | | <0.0042 | U | | 0.016 | | | <0.042 | U | | <0.0077 | U | | <0.0077 | U | |
| | 20 ft | VMP-31-20-101912 | 10/19/2012 | <5 | U | | <14 | U | | <6.8 | U | | <5.9 | U | | <9.5 | U | | <9.4 | U | | <4.1 | U | | 0.66 | J | | <41 | U | | <7.5 | U | | <7.5 | U | |
| | | VMP-31-20-021113 | 2/11/2013 | <0.071 | U | | 0.049 | J | | <0.097 | U | | <0.084 | U | | <0.14 | U | | <0.13 | U | | <0.058 | U | | <0.074 | U | | <0.58 | U | | <0.11 | U | | <0.11 | U | |
| | 30 ft | VMP-31-30-042512 | 4/25/2012 | <1.8 | U | | <4.8 | U | | 1.2 | J | | <2.1 | U | | <3.4 | U | | <3.3 | U | | <1.4 | U | | 1.4 | J | | <14 | U | | <2.7 | U | | <2.7 | U | |
| | | VMP-31-30-042512-Dup | 4/25/2012 | <1.8 | U | | <4.8 | U | | 1.3 | J | | <2.1 | U | | <3.4 | U | | <3.3 | U | | <1.4 | U | | 1.5 | J | | <14 | U | | <2.7 | U | | <2.7 | U | |
| | | VMP-31-30-072012 | 7/20/2012 | <0.34 | U | | <0.94 | U | | <0.47 | U | | <0.41 | U | | <0.66 | U | | <0.65 | U | | <0.28 | U | | <0.36 | U | | <2.8 | U | | <0.52 | U | | <0.52 | U | |
| | | VMP-31-30-101912 | 10/19/2012 | <0.31 | U | | <0.84 | U | | <0.42 | U | | <0.37 | U | | <0.59 | U | | <0.58 | U | | <0.25 | U | | 0.087 | J | | <2.6 | U | | <0.47 | U | | <0.47 | U | |
| | | VMP-31-30-021113 | 2/11/2013 | <5.1 | U | | <14 | U | | <6.9 | U | | <6 | U | | <9.7 | U | | <9.6 | U | | <4.2 | U | | 1.6 | J | | <42 | U | | <7.7 | U | | <7.7 | U | |
| VMP-32 | 5 ft | VMP-32-5-042512 | 4/25/2012 | <0.0034 | U | | 0.1 | | | <0.0046 | J | U | 0.0017 | J | | <0.0064 | U | | <0.0063 | J | U | 0.0059 | | | 0.023 | | | <0.028 | U | | <0.0051 | U | | <0.0051 | U | |
| | | VMP-32-5-072012 | 7/20/2012 | <0.003 | U | | <0.0082 | U | | 0.00058 | J | | <0.0036 | U | | 0.002 | J | | <0.0057 | U | | <0.0025 | U | | 0.0042 | | | <0.025 | U | | <0.0046 | U | | <0.0046 | U | |
| | | VMP-32-5-101812 | 10/18/2012 | <0.0058 | U | | 0.0096 | J | | 0.0009 | J | | <0.0068 | U | | <0.011 | U | | <0.011 | U | | <0.0047 | U | | 0.0033 | J | | <0.12 | U | UJ | <0.0087 | U | | <0.0087 | U | |
| | | VMP-32-5-020513 | 2/5/2013 | <0.0045 | U | | 0.013 | | | <0.0062 | J | U | <0.0054 | U | | <0.0086 | U | | <0.0085 | J | U | 0.0014 | J | | <0.0047 | J | U | <0.037 | J | U | <0.0069 | U | | <0.0069 | U | |
| | 10 ft | VMP-32-10-041612 | 4/16/2012 | <0.0031 | U | | 0.052 | | | 0.00054 | J | | 0.00082 | J | | <0.0059 | U | | <0.0058 | U | | <0.0025 | U | | 0.027 | | | <0.025 | U | | <0.0047 | J | U | <0.0047 | U | |
| | | VMP-32-10-072012 | 7/20/2012 | <0.0035 | U | | 0.0046 | J | | 0.00036 | J | | <0.0042 | U | | <0.0067 | U | | <0.0066 | U | | <0.0029 | U | | 0.0042 | | | <0.029 | U | | <0.0053 | U | | <0.0053 | U | |
| | | VMP-32-10-101812 | 10/18/2012 | <0.0053 | U | | 0.0041 | J | | <0.0073 | U | | <0.0063 | U | | <0.01 | U | | <0.01 | U | | <0.0044 | U | | 0.0015 | J | | <0.11 | U | UJ | <0.0081 | U | | <0.0081 | U | |
| | | VMP-32-10-020513 | 2/5/2013 | <0.0045 | U | | 0.0089 | J | | <0.0062 | U | | <0.0054 | U | | <0.0086 | U | | <0.0085 | J | U | 0.0014 | J | | <0.0047 | J | U | <0.037 | J | U | <0.0069 | U | | <0.0069 | U | |
| | 20 ft | VMP-32-20-041612 | 4/16/2012 | <0.071 | UJ | UJ | 0.38 | | | 0.014 | J | | 0.11 | | | <0.13 | U | | <0.13 | U | | <0.058 | U | | 0.23 | | | 0.19 | J | | <0.11 | U | | <0.11 | U | |
| | | VMP-32-20-072012 | 7/20/2012 | <0.0034 | U | | <0.0094 | U | | 0.00037 | J | | <0.0041 | U | | <0.0066 | U | | <0.0065 | U | | 0.0014 | J | | 0.0057 | | | <0.028 | U | | <0.0052 | U | | <0.0052 | U | |
| | | VMP-32-20-101812 | 10/18/2012 | <0.005 | U | | 0.0048 | J | | 0.0007 | J | | <0.0059 | U | | <0.0095 | U | | <0.0094 | U | | <0.0041 | U | | 0.0023 | J | | <0.1 | U | UJ | <0.0075 | U | | <0.0075 | U | |
| | | VMP-32-20-020513 | 2/5/2013 | <0.0051 | U | | 0.0064 | J | | <0.0069 | U | | <0.006 | U | | <0.0097 | U | | <0.0096 | J | U | <0.0042 | U | | <0.0053 | J | U | <0.042 | J | U | <0.0077 | U | | <0.0077 | U | |
| | 30 ft | VMP-32-30-041612 | 4/16/2012 | <1.7 | U | | <4.6 | U | | 0.51 | J | | <2 | U | | <3.2 | U | | <3.2 | U | | <1.4 | U | | 38 | | | <14 | U | | <2.6 | U | | <2.6 | U | |
| | | VMP-32-30-072012 | 7/20/2012 | <3.5 | U | | <9.5 | U | | <4.7 | U | | <4.1 | U | | <6.6 | U | | <6.5 | U | | 3.2 | | | 12 | | | <29 | U | | <5.3 | U | | <5.3 | U | |
| | | VMP-32-30-101812 | 10/18/2012 | <0.2 | U | | <0.54 | U | | <0.27 | U | | <0.23 | U | | <0.38 | U | | <0.37 | U | | <0.16 | U | | <0.21 | U | | <1.6 | U | | <0.3 | U | | <0.3 | U | |
| | | VMP-32-30-020513 | 2/5/2013 | <0.2 | U | | <0.56 | U | | <0.28 | U | | <0.24 | U | | <0.39 | U | | <0.38 | U | | <0.17 | U | | <0.21 | U | | <1.7 | U | | <0.31 | U | | <0.31 | U | |

SEE LAST PAGE OF TABLE FOR NOTES

**TABLE 5**
**CUMULATIVE SUMMARY OF SOIL VAPOR ANALYTICAL DETECTIONS AND SCREENING RESULTS: VILLAGE - VOCS**

| Location | Depth | Sample ID | Sample Date | Methyl tert-Butyl Ether (MTBE) 3400 | | | 2-Propanol | | | n-Propylbenzene | | | Styrene 1400 | | | 1,1,2,2-Tetrachloroethane | | | Tetrachloroethene 0.55 | | | Tetrahydrofuran | | | Toluene 6200 | | | 1,2,4-Trichlorobenzene 11 | | | 1,1,1-Trichloroethane (Methyl chloroform) 6600 | | | 1,1,2-Trichloroethane 170000 | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals |
| VMP-42 | 10 ft | VMP-42-10-041812 | 4/18/2012 | <0.0031 | UJ | UJ | 0.04 | | | 0.0006 | J | | <0.0036 | U | | <0.0059 | U | | <0.0058 | U | | <0.0025 | U | | 0.024 | | | <0.025 | U | | <0.0047 | J | U | <0.0047 | U | |
| | | VMP-42-10-041812-Dup | 4/18/2012 | <0.0032 | UJ | UJ | 0.034 | | | 0.00055 | J | | <0.0037 | U | | <0.006 | U | | <0.0059 | U | | <0.0026 | U | | 0.022 | | | <0.026 | U | | <0.0048 | U | | <0.0048 | U | |
| | | VMP-42-20-041812 | 4/18/2012 | <1.6 | UJ | UJ | 6.2 | | | <2.2 | U | | 1.9 | J | | <3.1 | U | | <3 | U | | <1.3 | U | | 6.8 | | | 3.5 | J | | <2.4 | U | | <2.4 | U | |
| | | VMP-42-10-071912 | 7/19/2012 | <0.0034 | U | | 0.077 | | | <0.0047 | J | U | 0.002 | J | | <0.0066 | U | | 0.0032 | J | | 0.0063 | | | 0.057 | | | <0.028 | U | | <0.0052 | U | | <0.0052 | U | |
| | | VMP-42-10-101212 | 10/12/2012 | <0.0056 | U | | 0.026 | | | <0.0076 | U | | <0.0066 | U | | <0.011 | U | | 0.0075 | J | | <0.0046 | U | | 0.011 | | | <0.046 | U | | <0.0084 | U | | <0.0084 | U | |
| | | VMP-42-10-013113 | 1/31/2013 | <0.0051 | U | | 0.0023 | J | | <0.0069 | U | | <0.006 | U | | <0.0097 | U | | <0.0096 | U | | <0.0042 | U | | <0.0053 | U | | <0.042 | U | | <0.0077 | U | | <0.0077 | U | |
| | 20 ft | VMP-42-20-071912 | 7/19/2012 | <0.0034 | U | | 0.057 | | | <0.0046 | J | U | 0.0019 | J | | <0.0064 | U | | 0.0028 | J | | <0.0028 | U | | 0.06 | | | <0.028 | U | | <0.0051 | U | | <0.0051 | U | |
| | | VMP-42-20-101212 | 10/12/2012 | <0.0049 | U | | 0.009 | J | | <0.0067 | U | | <0.0058 | U | | <0.0094 | U | | <0.0092 | U | | <0.004 | U | | 0.002 | J | | <0.04 | U | | <0.0074 | U | | <0.0074 | U | |
| | | VMP-42-20-101212-Dup | 10/12/2012 | <0.005 | U | | 0.014 | | | <0.0068 | U | | <0.0059 | U | | <0.0095 | U | | <0.0094 | U | | 0.003 | J | | 0.0087 | | | <0.041 | U | | <0.0075 | U | | <0.0075 | U | |
| | | VMP-42-20-013113 | 1/31/2013 | <0.0046 | U | | 0.0026 | J | | <0.0063 | U | | <0.0055 | U | | <0.0088 | U | | <0.0088 | J | U | <0.0038 | U | | <0.0049 | J | U | <0.038 | U | | <0.007 | U | | <0.007 | U | |
| | 30 ft | VMP-42-30-041912 | 4/19/2012 | <3.4 | U | | <9.2 | U | | <4.6 | U | | <4 | U | | <5.4 | U | | <5.3 | U | | <2.8 | U | | <3.5 | U | | <28 | U | | <5.1 | U | | <5.1 | U | |
| | | VMP-42-30-071912 | 7/19/2012 | <0.0032 | U | | 0.072 | | J | <0.0043 | J | U | 0.0026 | J | J | <0.006 | U | | 0.0033 | J | J | <0.0026 | U | | 0.073 | J | J | <0.026 | U | | <0.0048 | U | | <0.0048 | U | |
| | | VMP-42-30-101212 | 10/12/2012 | <0.0052 | U | | 0.008 | J | | <0.0071 | U | | <0.0062 | U | | <0.0099 | U | | <0.0098 | U | | <0.0043 | U | | 0.0036 | J | | <0.043 | U | | <0.0079 | U | | <0.0079 | U | |
| | | VMP-42-30-101212-Dup | 10/12/2012 | <0.0052 | U | | 0.0045 | J | | <0.0071 | U | | <0.0062 | U | | 0.0057 | J | | <0.0098 | U | | <0.0043 | U | | 0.0034 | J | | <0.043 | U | | <0.0079 | U | | <0.0079 | U | |
| | | VMP-42-30-013113 | 1/31/2013 | <0.005 | U | | 0.0014 | J | | <0.0068 | U | | <0.0059 | U | | <0.0095 | U | | <0.0094 | U | | <0.0041 | U | | <0.0052 | J | U | <0.041 | U | | <0.0075 | U | | <0.0075 | U | |
| VMP-43 | 10 ft | VMP-43-10-041612 | 4/16/2012 | <0.0035 | UJ | UJ | 0.063 | | | 0.00071 | J | | 0.0014 | J | | <0.0067 | U | | <0.0066 | U | | 0.0071 | | | 0.03 | | | <0.029 | U | | <0.0053 | J | U | <0.0053 | U | |
| | | VMP-43-10-071912 | 7/19/2012 | <0.0067 | U | | 0.052 | | | 0.0017 | J | | 0.003 | J | | <0.013 | U | | 0.0027 | J | | <0.0055 | U | | 0.067 | | | <0.056 | U | | <0.01 | U | | <0.01 | U | |
| | | VMP-43-10-101612 | 10/16/2012 | <0.0058 | U | | 0.11 | | | <0.0078 | U | | <0.0068 | U | | <0.011 | U | | <0.011 | U | | <0.0047 | U | | 0.008 | | | <0.12 | U | UJ | <0.0087 | U | | <0.0087 | U | |
| | 20 ft | VMP-43-20-041612 | 4/16/2012 | <0.034 | U | | 0.051 | J | | 0.0061 | J | | <0.041 | U | | <0.066 | U | | <0.065 | U | | <0.028 | U | | 0.031 | J | | <0.28 | U | | <0.052 | U | | <0.052 | U | |
| | | VMP-43-20-071912 | 7/19/2012 | <0.012 | U | | 0.1 | | | <0.017 | U | | 0.0029 | J | | <0.024 | U | | <0.023 | U | | <0.01 | U | | 0.051 | | | <0.1 | U | | <0.019 | U | | <0.019 | U | |
| | | VMP-43-20-101812 | 10/18/2012 | <0.0048 | U | | 0.022 | | | <0.0065 | U | | <0.0056 | U | | <0.0091 | U | | <0.009 | U | | 0.0031 | J | | 0.0092 | | | <0.098 | U | UJ | <0.0072 | U | | <0.0072 | U | |
| | | VMP-43-20-012413 | 1/24/2013 | <0.0048 | U | | 0.0035 | J | | <0.0065 | U | | <0.0056 | U | | <0.0091 | U | | 0.0038 | J | | <0.0039 | U | | <0.005 | J | U | <0.039 | U | | <0.0072 | U | | <0.0072 | U | |
| | 30 ft | VMP-43-30-042312 | 4/23/2012 | <0.032 | U | | 0.042 | J | | <0.043 | U | | <0.037 | U | | <0.06 | U | | <0.059 | U | | <0.026 | U | | 0.018 | J | | <0.26 | U | | <0.048 | U | | <0.048 | U | |
| | | VMP-43-30-071912 | 7/19/2012 | <0.0034 | U | | 0.066 | | | 0.0016 | J | | 0.002 | J | | <0.0066 | U | | 0.0023 | J | | <0.0028 | U | | 0.04 | | | <0.028 | U | | <0.0052 | U | | <0.0052 | U | |
| | | VMP-43-30-101812 | 10/18/2012 | <0.005 | U | | 0.0051 | J | | <0.0068 | U | | <0.0059 | U | | <0.0095 | U | | <0.0094 | U | | <0.0041 | U | | 0.002 | J | | <0.1 | U | UJ | <0.0075 | U | | <0.0075 | U | |
| | | VMP-43-30-012413 | 1/24/2013 | <0.0048 | U | | 0.016 | | | <0.0066 | U | | <0.0057 | U | | <0.0092 | U | | <0.0091 | J | U | <0.004 | U | | <0.0051 | J | U | <0.04 | U | | <0.0073 | U | | <0.0073 | U | |
| VMP-44 | 10 ft | VMP-44-10-041912 | 4/19/2012 | <1.6 | U | | <4.5 | U | | <2.2 | U | | <1.9 | U | | <3.1 | U | | <3.1 | U | | <1.3 | U | | 0.59 | J | | <14 | U | | <2.5 | U | | <2.5 | U | |
| | | VMP-44-10-072012 | 7/20/2012 | <0.55 | U | | <1.5 | U | | <0.75 | U | | <0.65 | U | | <1 | U | | <1 | U | | <0.45 | U | | 0.78 | | J | <4.6 | U | | <0.84 | U | | <0.84 | U | |
| | | VMP-44-10-081012 | 8/10/2012 | <0.33 | U | | <0.9 | U | | <0.45 | U | | <0.39 | U | | <0.63 | U | | <0.62 | U | | <0.27 | U | | 0.55 | | J | <2.7 | U | | <0.5 | U | | <0.5 | U | |
| | | VMP-44-10-101212 | 10/12/2012 | 0.5 | J | | <2.8 | U | | <1.4 | U | | <1.2 | U | | <1.9 | U | | 0.35 | J | | <0.83 | U | | 0.15 | J | | <8.4 | U | | <1.5 | U | | <1.5 | U | |
| | | VMP-44-10-012513 | 1/25/2013 | <0.41 | U | | 0.093 | J | | <0.56 | U | | <0.49 | U | | <0.79 | U | | 0.24 | J | | <0.34 | U | | <0.43 | U | | <3.4 | U | | <0.63 | U | | <0.63 | U | |
| | 20 ft | VMP-44-20-041912 | 4/19/2012 | <0.36 | U | | <0.99 | U | | 0.1 | J | | <0.43 | U | | <0.69 | U | | 0.14 | J | | <0.3 | U | | 1.2 | | | <3 | U | | <0.55 | U | | <0.55 | U | |
| | | VMP-44-20-072512 | 7/25/2012 | <0.62 | U | | <1.7 | U | | <0.84 | U | | <0.73 | U | | <1.2 | U | | <1.2 | U | | <0.5 | U | | 0.32 | J | J | <5.1 | U | | <0.94 | U | | <0.94 | U | |
| | | VMP-44-20-101212 | 10/12/2012 | 0.85 | J | | <5.6 | U | | <2.8 | U | | <2.4 | U | | <3.9 | U | | 0.53 | J | | <1.7 | U | | 0.17 | J | | <17 | U | | <3.1 | U | | <3.1 | U | |
| | | VMP-44-20-012513 | 1/25/2013 | <0.15 | U | | 1.1 | | | <0.2 | U | | <0.18 | U | | <0.28 | U | | <0.28 | U | | <0.12 | U | | <0.16 | U | | <1.2 | U | | <0.23 | U | | <0.23 | U | |
| | 30 ft | VMP-44-30-041912 | 4/19/2012 | <0.21 | U | | <0.58 | U | | 0.16 | J | | <0.25 | U | | <0.4 | U | | <0.4 | U | | <0.17 | U | | 0.39 | | | <1.7 | U | | <0.32 | U | | <0.32 | U | |
| | | VMP-44-30-072512 | 7/25/2012 | <0.035 | U | | 0.039 | J | | 0.072 | | | <0.042 | U | | <0.067 | U | | <0.066 | U | | <0.029 | U | | 0.34 | | | <0.29 | U | | <0.053 | U | | <0.053 | U | |
| | | VMP-44-30-072512-Dup | 7/25/2012 | <0.035 | U | | 0.044 | J | | 0.068 | | | <0.042 | U | | <0.067 | U | | <0.066 | U | | <0.029 | U | | 0.34 | | | <0.29 | U | | <0.053 | U | | <0.053 | U | |
| | | VMP-44-30-101512 | 10/15/2012 | <0.22 | U | | <0.59 | U | | <0.3 | U | | <0.26 | U | | <0.42 | U | | <0.41 | U | | <0.18 | U | | <0.23 | U | | <4.5 | U | | <0.33 | U | | <0.33 | U | |
| | | VMP-44-30-101512-Dup | 10/15/2012 | <0.2 | U | | <0.56 | U | | <0.28 | U | | <0.24 | U | | <0.39 | U | | <0.38 | U | | <0.17 | U | | <0.21 | U | | <4.2 | U | | <0.31 | U | | <0.31 | U | |
| | | VMP-44-30-012513 | 1/25/2013 | <0.052 | U | UJ | 10 | | J | <0.072 | U | UJ | <0.062 | U | UJ | <0.1 | U | UJ | <0.099 | U | UJ | <0.043 | U | UJ | <0.055 | U | UJ | <0.43 | U | UJ | <0.079 | U | UJ | <0.079 | U | UJ |
| VMP-45 | 10 ft | VMP-45-10-041912 | 4/19/2012 | <0.0033 | UJ | UJ | 0.023 | | | <0.0045 | U | | <0.0039 | U | | <0.0063 | U | | <0.0062 | U | | 0.0044 | | | 0.02 | | | <0.027 | U | | <0.005 | J | U | <0.005 | U | |
| | | VMP-45-10-071912 | 7/19/2012 | <0.0034 | U | | 0.048 | | | 0.00071 | J | | 0.0028 | J | | <0.0064 | U | | 0.0031 | J | | 0.0053 | | | 0.13 | | | <0.028 | U | | <0.0051 | U | | <0.0051 | U | |
| | | VMP-45-10-101512 | 10/15/2012 | <0.0052 | U | | <0.014 | U | | <0.0072 | U | | <0.0062 | U | | <0.01 | U | | <0.0099 | U | | <0.0043 | U | | 0.0014 | J | | <0.043 | U | | <0.0079 | U | | <0.0079 | U | |
| | | VMP-45-10-013013 | 1/30/2013 | <0.0045 | U | | 0.057 | | | <0.0062 | U | | <0.0054 | U | | <0.0086 | U | | <0.0085 | U | | <0.0037 | U | | <0.0047 | J | U | <0.037 | U | | <0.0069 | U | | <0.0069 | U | |
| | 20 ft | VMP-45-20-041912 | 4/19/2012 | <0.2 | U | | 0.053 | J | | 0.24 | J | | <0.24 | U | | <0.39 | U | | <0.39 | U | | <0.17 | U | | 1.9 | | | <1.7 | U | | <0.31 | U | | <0.31 | U | |
| | | VMP-45-20-071912 | 7/19/2012 | <0.064 | U | | 0.096 | J | | <0.088 | U | | 0.026 | J | | <0.12 | U | | <0.12 | U | | <0.052 | U | | 0.25 | | | <0.53 | U | | <0.097 | U | | <0.097 | U | |
| | | VMP-45-20-101512 | 10/15/2012 | <0.005 | U | | 0.072 | | | <0.0068 | U | | <0.0059 | U | | <0.0095 | U | | <0.0094 | U | | <0.0041 | U | | 0.0031 | J | | <0.041 | U | | <0.0075 | U | | <0.0075 | U | |
| | | VMP-45-20-013013 | 1/30/2013 | <0.0048 | U | | 0.0081 | J | | <0.0065 | U | | <0.0056 | U | | <0.0091 | U | | <0.009 | U | | <0.0039 | U | | <0.005 | J | U | <0.039 | U | | <0.0072 | U | | <0.0072 | U | |
| | 30 ft | VMP-45-30-041912 | 4/19/2012 | <0.14 | U | | <0.38 | U | | 0.16 | J | J | <0.16 | U | | <0.26 | U | | <0.26 | U | | <0.11 | U | | 0.18 | | J | <1.1 | U | | <0.21 | U | | <0.21 | U | |
| | | VMP-45-30-071912 | 7/19/2012 | <0.034 | U | | <0.094 | U | | <0.047 | U | | <0.041 | U | | <0.066 | U | | <0.065 | U | | <0.028 | U | | 0.086 | | | <0.28 | U | | <0.052 | U | | <0.052 | U | |
| | | VMP-45-30-101512 | 10/15/2012 | <0.005 | U | | 0.003 | J | | <0.0068 | U | | <0.0059 | U | | <0.0095 | U | | <0.0094 | U | | <0.0041 | U | | <0.0052 | J | U | <0.041 | U | | <0.0075 | U | | <0.0075 | U | |
| | | VMP-45-30-101512-Dup | 10/15/2012 | <0.0049 | U | | <0.013 | U | | <0.0067 | U | | <0.0058 | U | | <0.0094 | U | | <0.0092 | U | | <0.004 | U | | <0.0051 | J | U | <0.04 | U | | <0.0074 | U | | <0.0074 | U | |
| | | VMP-45-30-013013 | 1/30/2013 | <0.0087 | U | | 2.3 | | | <0.012 | U | | <0.01 | U | | <0.017 | U | | <0.016 | U | | <0.0071 | U | | <0.0091 | J | U | <0.072 | U | | <0.013 | U | | <0.013 | U | |

SEE LAST PAGE OF TABLE FOR NOTES

**TABLE 5**
**CUMULATIVE SUMMARY OF SOIL VAPOR ANALYTICAL DETECTIONS AND SCREENING RESULTS: VILLAGE - VOCS**

| Location | Depth | Sample ID | Sample Date | Methyl tert-Butyl Ether (MTBE) | | | 2-Propanol | | | n-Propylbenzene | | | Styrene | | | 1,1,2,2-Tetrachloroethane | | | Tetrachloroethene | | | Tetrahydrofuran | | | Toluene | | | 1,2,4-Trichlorobenzene | | | 1,1,1-Trichloroethane (Methyl chloroform) | | | 1,1,2-Trichloroethane | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | 3400 | | | | | | | | | 1400 | | | | | | 0.55 | | | | | | 6200 | | | 11 | | | 6600 | | | 170000 | | |
| | | | | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals |
| VMP-47 | 5 ft | VMP-47-5-012113 | 1/21/2013 | <0.0052 | U | | 0.057 | | | <0.0071 | U | | <0.0062 | U | | <0.0099 | U | | <0.0098 | U | | <0.0043 | U | | 0.0007 | J | | <0.043 | U | | <0.0079 | U | | <0.0079 | U | |
| | | [4]VMP-47-5-012313-R | 1/23/2013 | <17 | U | | <48 | U | | <24 | U | | <21 | U | | <33 | U | | <33 | U | | <14 | U | | <18 | U | | <140 | U | | <26 | U | | <26 | U | |
| | 10 ft | VMP-47-10-012113 | 1/21/2013 | <0.005 | U | | 0.035 | | | <0.0068 | U | | <0.0059 | U | | <0.0095 | U | | <0.0094 | U | | <0.0041 | U | | <0.0052 | U | | <0.041 | U | | <0.0075 | U | | <0.0075 | U | |
| | | [4]VMP-47-10-012313-R | 1/23/2013 | <0.44 | U | | <1.2 | U | | <0.59 | U | | <0.52 | U | | <0.83 | U | | <0.82 | U | | <0.36 | U | | 0.19 | J | | <3.6 | U | | <0.66 | U | | <0.66 | U | |
| | 20 ft | VMP-47-20-012113 | 1/21/2013 | <4.5 | U | | <12 | U | | <6.2 | U | | <5.4 | U | | <8.6 | U | | <8.5 | U | | <3.7 | U | | <4.7 | U | | <37 | U | | <6.9 | U | | <6.9 | U | |
| | | [4]VMP-47-20-012313-R | 1/23/2013 | <11 | U | | <29 | U | | <15 | U | | <13 | U | | <20 | U | | <20 | U | | <8.8 | U | | <11 | U | | <88 | U | | <16 | U | | <16 | U | |
| | 30 ft | VMP-47-30-012113 | 1/21/2013 | <3.3 | U | | <9 | U | | <4.5 | U | | <3.9 | U | | <6.3 | U | | <6.2 | U | | <2.7 | U | | <3.5 | U | | <27 | U | | <5 | U | | <5 | U | |
| | | [4]VMP-47-30-012313-R | 1/23/2013 | <17 | U | | <47 | U | | <23 | U | | <20 | U | | <33 | U | | <32 | U | | <14 | U | | <18 | U | | <140 | U | | <26 | U | | <26 | U | |
| VMP-48 | 5 ft | VMP-48-5-020113 | 2/1/2013 | <0.0046 | U | | 0.0017 | J | | <0.0063 | U | | <0.0055 | U | | <0.0088 | U | | <0.0087 | J | U | <0.0038 | U | | <0.0048 | J | U | 0.0031 | J | | <0.007 | U | | <0.007 | U | |
| | 10 ft | VMP-48-10-020113 | 2/1/2013 | <0.0048 | U | | 0.011 | J | | <0.0065 | U | | <0.0057 | U | | <0.0091 | U | | <0.009 | J | U | <0.0039 | U | | <0.005 | J | U | <0.039 | U | | <0.0072 | U | | <0.0072 | U | |
| | 20 ft | VMP-48-20-020113 | 2/1/2013 | <0.0046 | U | | 0.002 | J | | <0.0063 | U | | <0.0054 | U | | <0.0088 | U | | <0.0086 | J | U | <0.0038 | U | | <0.0048 | J | U | <0.038 | U | | <0.007 | U | | <0.007 | U | |
| | 30 ft | VMP-48-30-020113 | 2/1/2013 | <0.0047 | U | | 0.0015 | J | J | 0.0011 | J | | <0.0056 | U | | <0.009 | U | | <0.0088 | U | | <0.0038 | U | | 0.005 | | | <0.039 | U | | <0.0071 | U | | <0.0071 | U | |
| | | VMP-48-30-020113-DUP | 2/1/2013 | <0.019 | U | | <0.051 | U | UJ | <0.026 | U | | <0.022 | U | | <0.036 | U | | 0.0084 | J | | <0.015 | U | | 0.0054 | J | | <0.15 | U | | <0.028 | U | | <0.028 | U | |
| VMP-49 | 5 ft | VMP-49-5-020113 | 2/1/2013 | <0.0048 | U | | 0.0077 | J | | <0.0066 | U | | <0.0057 | U | | <0.0092 | U | | <0.0091 | J | U | <0.004 | U | | <0.0051 | J | U | <0.04 | J | U | <0.0073 | U | | <0.0073 | U | |
| | 10 ft | VMP-49-10-020113 | 2/1/2013 | <0.0048 | U | | 0.0018 | J | | <0.0065 | J | U | <0.0056 | U | | <0.0091 | U | | <0.009 | J | U | <0.0039 | U | | <0.005 | J | U | <0.039 | J | U | <0.0072 | U | | <0.0072 | U | |
| | 20 ft | VMP-49-20-020113 | 2/1/2013 | <0.0046 | U | | 0.0017 | J | | <0.0063 | U | | <0.0055 | U | | <0.0088 | U | | <0.0086 | J | U | <0.0038 | U | | <0.0049 | J | U | <0.038 | U | | <0.007 | U | | <0.007 | U | |
| | 30 ft | VMP-49-30-020113 | 2/1/2013 | <0.22 | U | | 0.27 | J | | <0.3 | U | | 0.068 | J | | <0.42 | U | | <0.42 | U | | <0.18 | U | | 0.049 | J | | 0.15 | J | | <0.34 | U | | <0.34 | U | |
| VMP-50 | 5 ft | VMP-50-5-020113 | 2/1/2013 | <0.0045 | U | | 0.0057 | J | | <0.0062 | U | | <0.0054 | U | | <0.0086 | U | | <0.0085 | J | U | <0.0037 | U | | <0.0047 | J | U | <0.037 | J | U | 0.0078 | | | <0.0069 | U | |
| | 10 ft | VMP-50-10-020113 | 2/1/2013 | <0.005 | U | | 0.0042 | J | | <0.0068 | U | | <0.0059 | U | | <0.0095 | U | | 0.0056 | J | | <0.0041 | U | | <0.0052 | J | U | <0.041 | U | | <0.0075 | U | | <0.0075 | U | |
| | 20 ft | VMP-50-20-020113 | 2/1/2013 | <0.019 | U | | 0.0072 | J | | 0.0069 | J | | <0.023 | U | | <0.037 | U | | <0.036 | U | | <0.016 | U | | 0.0073 | J | | <0.16 | U | | <0.029 | U | | <0.029 | U | |
| | 30 ft | VMP-50-30-020113 | 2/1/2013 | <4.7 | U | | 3.3 | J | | 30 | | | <5.5 | U | | <8.9 | U | | <8.8 | U | | <3.8 | U | | 740 | | | 4.2 | J | | <7.1 | U | | <7.1 | U | |
| VMP-51 | 5 ft | VMP-51-5-020113 | 2/1/2013 | <0.0049 | U | | 0.0025 | J | | <0.0067 | U | | <0.0058 | U | | <0.0094 | U | | <0.0092 | J | U | <0.004 | U | | <0.0051 | J | U | <0.04 | U | | 0.0031 | J | | <0.0074 | U | |
| | 10 ft | VMP-51-10-020113 | 2/1/2013 | <0.005 | U | | 0.0024 | J | | <0.0068 | U | | <0.0059 | U | | <0.0095 | U | | 0.0036 | J | | <0.0041 | U | | <0.0052 | J | U | <0.041 | U | | <0.0075 | U | | <0.0075 | U | |
| | 20 ft | VMP-51-20-021513-R | 2/15/2013 | <0.0048 | U | | 0.011 | J | | 0.0074 | | | <0.0056 | U | | <0.0091 | U | | 0.0012 | J | | <0.0039 | U | | 0.00065 | J | | <0.039 | U | | <0.0072 | U | | <0.0072 | U | |
| | 30 ft | VMP-51-30-020413 | 2/4/2013 | <0.0052 | U | | 0.0016 | J | | <0.0071 | U | | <0.0062 | U | | <0.0099 | U | | <0.0098 | J | U | <0.0043 | U | | <0.0054 | J | U | <0.043 | J | U | <0.0079 | U | | <0.0079 | U | |
| | | VMP-51-30-020413-DUP | 2/4/2013 | <0.0051 | U | | 0.0031 | J | | <0.0069 | U | | <0.006 | U | | <0.0096 | U | | <0.0095 | J | U | <0.0041 | U | | <0.0053 | J | U | <0.042 | U | | <0.0077 | U | | <0.0077 | U | |
| VMP-52 | 5 ft | VMP-52-5-020413 | 2/4/2013 | <0.0045 | U | | 0.0079 | J | | <0.0062 | U | | <0.0054 | U | | <0.0086 | U | | <0.0085 | J | U | <0.0037 | U | | <0.0047 | J | U | <0.037 | J | U | 0.02 | | | <0.0069 | U | |
| | 10 ft | VMP-52-10-020413 | 2/4/2013 | <0.0043 | U | | 0.0026 | J | | <0.0059 | U | | <0.0051 | U | | <0.0082 | U | | <0.0081 | J | U | <0.0035 | U | | <0.0045 | J | U | <0.036 | J | U | 0.022 | | | <0.0065 | U | |
| | 20 ft | VMP-52-20-020413 | 2/4/2013 | <0.0048 | U | | 0.006 | J | | <0.0066 | J | U | <0.0057 | U | | <0.0092 | U | | <0.0091 | J | U | <0.004 | U | | 0.0026 | J | | <0.04 | J | U | <0.0073 | U | | <0.0073 | U | |
| | | VMP-52-20-020413-DUP | 2/4/2013 | <0.0046 | U | | 0.0014 | J | | <0.0063 | U | | <0.0055 | U | | <0.0088 | U | | 0.0024 | J | | <0.0038 | U | | 0.0017 | J | | <0.038 | J | U | <0.007 | U | | <0.007 | U | |
| | 30 ft | VMP-52-30-020413 | 2/4/2013 | <0.0051 | U | | <0.014 | U | | <0.0069 | U | | <0.006 | U | | <0.0096 | U | | <0.0095 | J | U | <0.0041 | U | | <0.0053 | J | U | <0.042 | J | U | <0.0077 | U | | <0.0077 | U | |
| VMP-53 | 5 ft | VMP-53-5-020513 | 2/5/2013 | <0.0046 | U | | 0.0028 | J | | <0.0063 | U | | <0.0055 | U | | <0.0088 | U | | <0.0088 | J | U | <0.0038 | U | | <0.0049 | J | U | <0.038 | U | | <0.007 | U | | <0.007 | U | |
| | 10 ft | VMP-53-10-020513 | 2/5/2013 | <0.0048 | U | | 0.0052 | J | | <0.0065 | U | | <0.0056 | U | | <0.0091 | U | | <0.009 | U | | <0.0039 | U | | <0.005 | J | U | <0.039 | U | | <0.0072 | U | | <0.0072 | U | |
| | | VMP-53-10-020513-DUP | 2/5/2013 | <0.0044 | U | | 0.0014 | J | | <0.0061 | U | | <0.0053 | U | | <0.0085 | U | | <0.0084 | U | | <0.0036 | U | | <0.0046 | J | U | <0.037 | U | | <0.0067 | U | | <0.0067 | U | |
| | 20 ft | VMP-53-20-020513 | 2/5/2013 | <0.0048 | U | | 0.0017 | J | | <0.0065 | J | U | <0.0056 | U | | <0.0091 | U | | <0.009 | J | U | <0.0039 | U | | <0.005 | J | U | <0.039 | J | U | <0.0072 | U | | <0.0072 | U | |
| | 30 ft | VMP-53-30-020513 | 2/5/2013 | <0.0048 | U | | 0.0012 | J | | <0.0066 | U | | <0.0057 | U | | <0.0092 | U | | <0.0091 | J | U | <0.004 | U | | <0.0051 | J | U | <0.04 | U | | <0.0073 | U | | <0.0073 | U | |
| VMP-54 | 5 ft | VMP-54-5-020613 | 2/6/2013 | <0.005 | U | | 0.0058 | J | | 0.011 | | | <0.0059 | U | | <0.0095 | U | | <0.0094 | J | U | <0.0041 | U | | 0.0092 | | | <0.041 | U | | <0.0075 | U | | <0.0075 | U | |
| | 10 ft | VMP-54-10-020613 | 2/6/2013 | <0.0051 | U | | 0.0042 | J | | <0.0069 | J | U | <0.006 | U | | <0.0097 | U | | <0.0096 | J | U | <0.0042 | U | | 0.0036 | J | | <0.042 | U | | <0.0077 | U | | <0.0077 | U | |
| | 20 ft | VMP-54-20-020613 | 2/6/2013 | <0.005 | U | | 0.0083 | J | | <0.0068 | J | U | <0.0059 | U | | <0.0095 | U | | 0.0052 | J | | <0.0041 | U | | <0.0052 | J | U | <0.041 | J | U | <0.0075 | U | | <0.0075 | U | |
| | | VMP-54-20-020613-DUP | 2/6/2013 | <0.005 | U | | 0.014 | | | <0.0068 | J | U | <0.0059 | U | | <0.0095 | U | | 0.0046 | J | | <0.0041 | U | | <0.0052 | J | U | <0.041 | J | U | <0.0075 | U | | <0.0075 | U | |
| | 30 ft | VMP-54-30-020613 | 2/6/2013 | <0.0053 | U | | 0.0042 | J | | <0.0073 | U | | <0.0063 | U | | <0.01 | U | | 0.0046 | J | | <0.0044 | U | | <0.0056 | J | U | <0.044 | J | U | <0.0081 | U | | <0.0081 | U | |
| | | VMP-54-30-020613-DUP | 2/6/2013 | <0.0053 | U | | 0.0034 | J | | <0.0073 | U | | <0.0063 | U | | <0.01 | U | | 0.0045 | J | | <0.0044 | U | | <0.0056 | J | U | <0.044 | U | | <0.0081 | U | | <0.0081 | U | |

SEE LAST PAGE OF TABLE FOR NOTES

**TABLE 5**
**CUMULATIVE SUMMARY OF SOIL VAPOR ANALYTICAL DETECTIONS AND SCREENING RESULTS: VILLAGE - VOCS**

| Location | Depth | Sample ID | Sample Date | Trichloroethene | | | Trichlorofluoromethane | | | 1,2,4-Trimethylbenzene | | | 1,3,5-Trimethylbenzene | | | 2,2,4-Trimethylpentane | | | Vinyl chloride | | | m,p-Xylene | | | o-Xylenes | | | [3]Butane, 2,2-dimethyl- | | | [3]Butane, 2,3-dimethyl- | | | [3]Cyclobutane, ethyl- | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | 1.5 | | | 860 | | | | | | | | | | | | 0.29 | | | 130 | | | 120 | | | | | | | | | | | |
| | | | | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result (ppbV) | Lab Quals | URS Quals | Result (ppbV) | Lab Quals | URS Quals | Result (ppbV) | Lab Quals | URS Quals |
| VMP-1 | 5 ft | VMP-1-5-082510 | 8/25/2010 | <0.023 | U | | <0.024 | U | | <0.021 | U | | <0.021 | U | | 0.74 | | | <0.011 | U | | 0.0024 | J | | <0.018 | U | | | | | | | | | | |
| | | VMP-1-5-111710 | 11/17/2010 | <0.028 | U | | <0.029 | U | | <0.025 | U | | <0.025 | U | | 5.3 | | | <0.013 | U | | 0.0043 | J | | <0.022 | U | | | | | | | | | | |
| | | VMP-1-5-020411 | 2/4/2011 | <0.54 | U | | <0.57 | U | | <0.5 | U | | <0.5 | U | | 270 | | | <0.26 | U | | <0.44 | U | | <0.44 | U | | | | | | | | | | |
| | | VMP-1-5-041211 | 4/12/2011 | <0.0071 | J | U | 0.0012 | J | | 0.0023 | J | | <0.0065 | U | | 1.5 | | | <0.0034 | U | | 0.0056 | | | <0.0057 | U | | | | | | | | | | |
| | | VMP-1-5-080111 | 8/1/2011 | 0.01 | | | <0.0074 | U | | 0.0066 | | | 0.0019 | J | | 0.14 | | | <0.0034 | U | | 0.0079 | | | 0.0029 | J | | | | | | | | | | |
| | | VMP-1-5-110311 | 11/3/2011 | <19 | U | | <20 | U | UJ | <17 | U | | <17 | U | | 250 | | | <8.9 | U | | <15 | U | | <15 | U | | | | | | | | | | |
| | | VMP-1-5-013012 | 1/30/2012 | <1.6 | U | | <1.6 | U | | <1.4 | U | | <1.4 | U | | 440 | | J | <0.74 | U | | <1.3 | U | | <1.3 | U | | | | | | | | | | |
| | | VMP-1-5-041312 | 4/13/2012 | <0.0048 | U | | 0.0014 | J | | 0.00086 | J | | <0.0044 | U | | 0.017 | | | <0.0023 | U | | 0.0036 | J | | 0.0013 | J | | | | | | | | | | |
| | | VMP-1-5-071612 | 7/16/2012 | <0.0049 | J | U | 0.0013 | J | | 0.0042 | J | | <0.0045 | J | U | 0.089 | | | <0.0023 | U | | 0.028 | | | <0.0086 | | | | | | | | | | | |
| | | VMP-1-5-101112 | 10/11/2012 | <0.012 | U | | <0.013 | U | | <0.011 | U | | <0.011 | U | | 1.2 | | | <0.0059 | U | | 0.0034 | J | | <0.01 | U | | | | | | | | | | |
| | | [4]VMP-1-5-012113 | 1/21/2013 | <0.14 | U | | <0.14 | U | | <0.13 | U | | <0.13 | U | | 4.5 | | | <0.066 | U | | <0.11 | U | | <0.11 | U | | | | | | | | 660 | | |
| | | [4]VMP-1-5-012313-R | 1/23/2013 | <6.3 | U | | <6.5 | U | | 2.3 | J | | <5.7 | U | | 140 | | | <3 | U | | 3.9 | J | | 1.8 | J | | | | | | | | 85,000 | | |
| | 8.5 ft | VMP-1-8.5-082510 | 8/25/2010 | <0.069 | U | | <0.072 | U | | <0.063 | U | | <0.063 | U | | 4.2 | | | <0.033 | U | | <0.056 | U | | <0.056 | U | | | | | | | | | | |
| | | VMP-1-8.5-111710 | 11/17/2010 | <0.013 | J | U | <0.014 | U | | <0.012 | U | | <0.012 | U | | 3.1 | | | <0.0063 | U | | 0.002 | J | | <0.011 | U | | | | | | | | | | |
| | | VMP-1-8.5-111710-Dup | 11/17/2010 | <0.013 | J | U | <0.014 | U | | <0.012 | U | | <0.012 | U | | 2.8 | | | <0.0063 | U | | 0.0014 | J | | <0.011 | U | | | | | | | | | | |
| | | VMP-1-8.5-020411 | 2/4/2011 | <1.1 | U | | <1.1 | U | | <0.98 | U | | <0.98 | U | | 350 | | | <0.51 | U | | <0.86 | U | | <0.86 | U | | | | | | | | | | |
| | | VMP-1-8.5-041211 | 4/12/2011 | 0.0048 | J | | 0.0012 | J | | 0.0025 | J | | <0.0086 | U | | 1.9 | | | <0.0044 | U | | 0.0047 | J | | <0.0076 | U | | | | | | | | | | |
| | | VMP-1-8.5-080111 | 8/1/2011 | <3.9 | U | | <4 | U | | <3.5 | U | | <3.5 | U | | 380 | | | <1.8 | U | | <3.1 | U | | <3.1 | U | | | | | | | | | | |
| | | VMP-1-8.5-080111-Dup | 8/1/2011 | <3.8 | U | | <4 | U | | <3.5 | U | | <3.5 | U | | 360 | | | <1.8 | U | | <3.1 | U | | <3.1 | U | | | | | | | | | | |
| | | VMP-1-8.5-110311 | 11/3/2011 | <43 | U | | <45 | U | UJ | <40 | U | | <40 | U | | 480 | | | <20 | U | | <35 | U | | <35 | U | | | | | | | | | | |
| | | VMP-1-8.5-013012 | 1/30/2012 | <9.4 | U | | <9.8 | U | | <8.6 | U | | <8.6 | U | | 320 | | | <4.5 | U | | <7.6 | U | | <7.6 | U | | | | | | | | | | |
| | | VMP-1-8.5-041612 | 4/16/2012 | <0.0057 | U | | 0.0018 | J | | <0.0052 | U | | <0.0051 | U | | 0.078 | | | <0.0027 | U | | 0.0073 | | | 0.0024 | J | | | | | | | | | | |
| | | VMP-1-8.5-041612-Dup | 4/16/2012 | <0.0055 | U | | 0.0019 | J | | 0.0015 | J | | <0.0051 | U | | 0.075 | | | <0.0026 | U | | 0.0068 | | | 0.0027 | J | | | | | | | | | | |
| | | VMP-1-8.5-071612 | 7/16/2012 | <0.0049 | J | U | 0.0012 | J | | <0.0045 | J | U | <0.0045 | J | U | 0.0041 | J | | <0.0024 | U | | 0.02 | | | 0.0052 | | | | | | | | | | | |
| | | VMP-1-8.5-101112 | 10/11/2012 | <0.0076 | U | | 0.0014 | J | | <0.0069 | U | | <0.0069 | U | | 0.82 | | | <0.0036 | U | | <0.0061 | U | | <0.0061 | U | | | | | | | | | | |
| | | [4]VMP-1-8.5-012113 | 1/21/2013 | <0.13 | U | | <0.14 | U | UJ | <0.12 | U | | <0.12 | U | | 5.7 | | | <0.064 | U | | <0.11 | U | | <0.11 | U | | 3,300 | | | | | | | | |
| | | [4]VMP-1-8.5-012313-R | 1/23/2013 | <0.12 | U | | <0.13 | U | | <0.11 | U | | <0.11 | U | | 4.6 | | | <0.06 | U | | 0.039 | J | | 0.021 | J | | | | | | | | 3,200 | | |
| | 23.5 ft | VMP - 1 - 23.5 - 083010 | 8/30/2010 | <2.4 | U | | <2.5 | U | | <2.2 | U | | <2.2 | U | | 1600 | | | <1.1 | U | | <1.9 | U | | <1.9 | U | | | | | | | | | | |
| | | VMP-1-23.5-111810 | 11/17/2010 | <0.0066 | J | U | 0.0014 | J | | <0.0061 | U | | <0.0061 | U | | 0.06 | | | <0.0032 | U | | <0.0054 | J | U | <0.0054 | U | | | | | | | | | | |
| | | VMP-1-23.5-020411 | 2/4/2011 | <6.3 | U | | <6.5 | U | | <5.7 | U | | <5.7 | U | | 1900 | | | <3 | U | | <5 | U | | <5 | U | | | | | | | | | | |
| | | VMP-1-23.5-041211 | 4/12/2011 | 11 | | | <11 | U | | <9.3 | U | | <9.3 | U | | 110 | | J | <4.8 | U | | <8.2 | U | | <8.2 | U | | | | | | | | | | |
| | | VMP-1-23.5-041211-DUP | 4/12/2011 | 2.2 | J | | <13 | U | | <12 | U | | <12 | U | | 150 | | J | <6.1 | U | | <10 | U | | <10 | U | | | | | | | | | | |
| | | VMP-1-23.5-080111 | 8/1/2011 | <69 | U | | <72 | U | | <63 | U | | <63 | U | | 1000 | | | <33 | U | | <56 | U | | <56 | U | | | | | | | | | | |
| | | VMP-1-23.5-110611 | 11/6/2011 | <16 | U | | <17 | U | | <15 | U | | <15 | U | | 710 | | | <7.8 | U | | <13 | U | | <13 | U | | | | | | | | | | |
| | | VMP-1-23.5-013112 | 1/31/2012 | <32 | U | | <34 | U | | <120 | U | | <29 | U | | 420 | | | <15 | U | | <26 | U | | <26 | U | | | | | | | | | | |
| | | VMP-1-23.5-041612 | 4/16/2012 | <2.6 | U | | <2.7 | U | | <2.3 | U | | <2.3 | U | | 76 | | | <1.2 | U | | <2.1 | U | | <2.1 | U | | | | | | | | | | |
| | | VMP-1-23.5-071612 | 7/16/2012 | <32 | U | | <34 | U | | <30 | U | | <30 | U | | 240 | | | <15 | U | | <26 | U | | <26 | U | | | | | | | | | | |
| | | VMP-1-23.5-102412 | 10/24/2012 | <65 | U | | <68 | U | | <59 | U | | <59 | U | | 180 | | | <31 | U | | 7 | J | | <52 | U | | | | | | | | | | |
| | | [4]VMP-1-23.5-012113 | 1/21/2013 | <0.072 | U | UJ | <0.076 | U | UJ | <0.066 | U | UJ | <0.066 | U | UJ | 4.2 | | J | <0.034 | U | UJ | <0.058 | U | UJ | <0.058 | U | UJ | | | | | | | | | |
| | | [4]VMP-1-23.5-012313-R | 1/23/2013 | <86 | U | | <90 | U | | <79 | U | | <79 | U | | 790 | | | <41 | U | | 23 | J | | <70 | U | | | | | | | | 450,000 | | |
| | 38.5 ft | VMP-1-38.5-073112 | 7/31/2012 | <0.005 | U | | 0.0012 | J | | 0.0044 | J | | <0.0046 | U | | 0.0042 | J | | <0.0024 | U | | 0.0084 | | | 0.0026 | J | | | | | | | | | | |
| | | VMP-1-38.5-102612 | 10/26/2012 | <3.5 | U | | <3.6 | U | | <3.2 | U | | <3.2 | U | | 58 | | | <1.7 | U | | <2.8 | U | | <2.8 | U | | | | | | | | | | |
| | | [4]VMP-1-38.5-012113 | 1/21/2013 | <0.047 | U | UJ | <0.049 | U | UJ | <0.043 | U | UJ | <0.043 | U | UJ | 1.4 | | J | <0.022 | U | UJ | <0.038 | U | UJ | <0.038 | U | UJ | | | | | | | | | |
| | | [4]VMP-1-38.5-012313-R | 1/23/2013 | <64 | U | | <67 | U | | <58 | U | | <58 | U | | 390 | | | <30 | U | | 16 | J | | 7.2 | J | | | | | | | | | | |
| VMP-2 | 5 ft | VMP - 2 - 5 - 083110 | 8/31/2010 | <2.4 | U | | <2.5 | U | | <2.2 | U | | <2.2 | U | | 1300 | | | <1.1 | U | | <1.9 | U | | <1.9 | U | | | | | | | | | | |
| | | VMP-2-5-111610 | 11/16/2010 | <3.5 | U | | <3.7 | U | | <3.2 | U | | <3.2 | U | | 2000 | | | <1.7 | U | | <2.9 | U | | <2.9 | U | | | | | | | | | | |
| | | VMP-2-5-020411 | 2/4/2011 | <0.93 | U | | <0.97 | U | | <0.85 | U | | <0.85 | U | | 570 | | | <0.44 | U | | <0.75 | U | | <0.75 | U | | | | | | | | | | |
| | | VMP-2-5-041311 | 4/13/2011 | 0.0042 | J | | 0.0015 | J | | 0.0022 | J | | <0.0068 | U | | 1.1 | | | <0.0036 | U | | 0.0038 | J | | <0.006 | U | | | | | | | | | | |
| | | VMP-2-5-080211 | 8/2/2011 | <7.8 | U | | <8.1 | U | | <7.1 | U | | <7.1 | U | | 1300 | | | <3.7 | U | | <6.3 | U | | <6.3 | U | | | | | | | | | | |
| | | VMP-2-5-110711 | 11/7/2011 | <0.0046 | J | U | 0.0011 | J | | <0.0042 | U | | <0.0042 | U | | 0.053 | | | <0.0022 | U | | 0.0022 | J | | 0.00071 | J | | | | | | | | | | |
| | | VMP-2-5-012512 | 1/25/2012 | <0.52 | U | | <0.54 | U | | <0.48 | U | | <0.48 | U | | 200 | | | <0.25 | U | | 0.14 | J | | <0.42 | U | | | | | | | | | | |
| | | VMP-2-5-042512 | 4/25/2012 | <0.02 | U | | <0.021 | U | | <0.019 | U | | <0.019 | U | | 12 | | | <0.0098 | U | | 0.0091 | J | | 0.0042 | J | | | | | | | | | | |
| | | VMP-2-5-071612 | 7/16/2012 | <0.005 | U | | 0.0012 | J | | 0.0049 | | | <0.0046 | J | U | 0.022 | | | <0.0024 | U | | 0.026 | | | 0.0071 | | | | | | | | | | | |
| | | VMP-2-5-102412 | 10/24/2012 | <0.0077 | U | | 0.0014 | J | | <0.007 | J | U | <0.007 | U | | 0.01 | | | <0.0036 | U | | 0.0044 | J | | 0.0012 | J | | | | | | | | | | |
| | | VMP-2-5-013113 | 1/31/2013 | <0.0074 | U | | 0.0014 | J | | <0.0068 | J | U | <0.0068 | J | U | 0.026 | | | <0.0035 | U | | <0.006 | U | | <0.006 | U | | | | | | | | | | |
| | 8.5 ft | VMP-2-8.5-083110 | 8/31/2010 | <2.5 | U | | <2.6 | U | | <2.3 | U | | <2.3 | U | | 2000 | | | <1.2 | U | | <2 | U | | <2 | U | | | | | | | | | | |
| | | VMP-2-8.5-111610 | 11/16/2010 | <6.8 | U | | <7.1 | U | | <6.2 | U | | <6.2 | U | | 2000 | | | <3.2 | U | | <5.5 | U | | <5.5 | U | | | | | | | | | | |
| | | VMP-2-8.5-020411 | 2/4/2011 | <2.3 | U | | <2.4 | U | | <2.1 | U | | <2.1 | U | | 830 | | | <1.1 | U | | <1.9 | U | | <1.9 | U | | | | | | | | | | |
| | | VMP-2-8.5-041311 | 4/13/2011 | 0.095 | J | | 0.12 | J | | <0.65 | U | | <0.65 | U | | 140 | B | | <0.34 | U | | 0.048 | J | | 0.074 | J | | | | | | | | | | |
| | | VMP-2-8.5-080211 | 8/2/2011 | <28 | U | | <30 | U | | <26 | U | | <26 | U | | 1600 | | | <14 | U | | <23 | U | | <23 | U | | | | | | | | | | |
| | | VMP-2-8.5-110711 | 11/7/2011 | <0.061 | U | | <0.064 | U | UJ | 0.01 | J | | <0.056 | U | | 14 | | | <0.029 | U | | <0.05 | U | | <0.05 | U | | | | | | | | | | |
| | | VMP-2-8.5-012612 | 1/26/2012 | <2.7 | U | | <2.8 | U | | <9.9 | U | | <2.5 | U | | 510 | | J | <1.3 | U | | <2.2 | U | | <2.2 | U | | | | | | | | | | |
| | | VMP-2-8.5-012612-DUP | 1/26/2012 | <2.7 | U | | <2.8 | U | | <9.9 | U | | <2.5 | U | | 770 | | J | <1.3 | U | | <2.2 | U | | <2.2 | U | | | | | | | | | | |
| | | VMP-2-8.5-041612 | 4/16/2012 | <0.0053 | U | | <0.0055 | U | | 0.0018 | J | | <0.0048 | U | | 0.19 | | | <0.0025 | U | | 0.0083 | | | 0.0035 | J | | | | | | | | | | |
| | | VMP-2-8.5-041612-Dup | 4/16/2012 | <0.0054 | U | | 0.0017 | J | | 0.0018 | J | | <0.0049 | U | | 0.19 | | | <0.0026 | U | | 0.0093 | | | 0.0037 | J | | | | | | | | | | |
| | | VMP-2-8.5-071612 | 7/16/2012 | <0.006 | U | | 0.0024 | J | | 0.0044 | J | | <0.0055 | J | U | 0.0073 | | | <0.0029 | U | | 0.018 | | J | 0.0062 | | | | | | | | | | |
| | | VMP-2-8.5-071612-Dup | 7/16/2012 | <0.0049 | J | U | 0.0022 | J | | 0.0088 | | | 0.0034 | J | | 0.0046 | | | <0.0024 | U | | 0.028 | | J | 0.0099 | | | | | | | | | | |
| | | VMP-2-8.5-102312 | 10/23/2012 | <0.0078 | U | | 0.0016 | J | | 0.0046 | J | | 0.002 | J | | 0.13 | | | <0.0037 | U | | 0.022 | | | 0.0074 | | | | | | | | | | |
| | | VMP-2-8.5-020513 | 2/5/2013 | <0.008 | U | | <0.0083 | J | U | <0.0073 | U | | <0.0073 | U | | 0.038 | | | <0.0038 | U | | 0.0036 | J | | 0.0022 | J | | | | | | | | | | |
| | 22 ft | VMP-2-22-083110 | 8/31/2010 | <3.8 | U | | <4 | U | | <3.5 | U | | <3.5 | U | | 2300 | | | <1.8 | U | | <3.1 | U | | <3.1 | U | | | | | | | | | | |
| | | VMP-2-22-111610 | 11/16/2010 | <7.1 | U | | <7.4 | U | | <6.5 | U | | <6.5 | U | | 2300 | | | <3.4 | U | | <5.7 | U | | <5.7 | U | | | | | | | | | | |
| | | VMP-2-22-020411 | 2/4/2011 | <3.2 | U | | <3.3 | U | | <2.9 | U | | <2.9 | U | | 1400 | | | <1.5 | U | | <2.6 | U | | <2.6 | U | | | | | | | | | | |
| | | VMP-2-22-041311 | 4/13/2011 | <9.4 | U | | <9.8 | U | | <8.6 | U | | <8.6 | U | | 760 | B | | <4.5 | U | | <7.6 | U | | <7.6 | U | | | | | | | | | | |
| | | VMP-2-22-080211 | 8/2/2011 | <38 | U | | <40 | U | | <35 | U | | <35 | U | | 1500 | | | <18 | U | | <31 | U | | <31 | U | | | | | | | | | | |
| | | VMP-2-22-110711 | 11/7/2011 | <2 | U | | <2.1 | U | UJ | <1.8 | U | | <1.8 | U | | 120 | | | <0.95 | U | | <1.6 | U | | <1.6 | U | | | | | | | | | | |
| | | VMP-2-22-012612 | 1/26/2012 | <4.2 | U | | <4.4 | U | | <15 | U | | <3.8 | U | | 650 | | J | <2 | U | | <3.4 | U | | <3.4 | U | | | | | | | | | | |
| | | VMP-2-22-042712 | 4/27/2012 | <0.0043 | U | | 0.0011 | J | | 0.0009 | J | | <0.004 | U | | 0.077 | | | <0.002 | U | | 0.0048 | | | 0.0017 | J | | | | | | | | | | |
| | | VMP-2-22-071612 | 7/16/2012 | <0.0051 | U | | 0.0021 | J | | 0.0056 | | | <0.0047 | J | U | 0.023 | | | <0.0024 | U | | 0.03 | | | 0.0094 | | | | | | | | | | | |
| | | VMP-2-22-102312 | 10/23/2012 | <0.0078 | U | | 0.0015 | J | | <0.0072 | U | | <0.0072 | U | | 0.031 | | | <0.0037 | U | | <0.0063 | J | U | <0.0063 | U | | | | | | | | | | |
| | | VMP-2-22-013113 | 1/31/2013 | <0.0072 | U | | 0.001 | J | | <0.0066 | U | | <0.0066 | U | | 0.0026 | J | | <0.0034 | U | | <0.0058 | U | | <0.0058 | U | | | | | | | | | | |
| | 42 ft | VMP-2-42-013113 | 1/31/2013 | <70 | U | | <73 | U | | 15 | J | | <64 | U | | 420 | | | <33 | U | | 12 | J | | <56 | U | | | | | | | | | | |

SEE LAST PAGE OF TABLE FOR NOTES

**TABLE 5**
**CUMULATIVE SUMMARY OF SOIL VAPOR ANALYTICAL DETECTIONS AND SCREENING RESULTS: VILLAGE - VOCS**

| Location | Depth | Sample ID | Sample Date | Trichloroethene | | | Trichlorofluoromethane | | | 1,2,4-Trimethylbenzene | | | 1,3,5-Trimethylbenzene | | | 2,2,4-Trimethylpentane | | | Vinyl chloride | | | m,p-Xylene | | | o-Xylenes | | | $^{3}$Butane, 2,2-dimethyl- | | | $^{3}$Butane, 2,3-dimethyl- | | | $^{3}$Cyclobutane, ethyl- | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | 1.5 | | | 860 | | | | | | | | | | | | 0.29 | | | 130 | | | 120 | | | | | | | | | | | |
| | | | | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result (ppbV) | Lab Quals | URS Quals | Result (ppbV) | Lab Quals | URS Quals | Result (ppbV) | Lab Quals | URS Quals |
| VMP-3 | 5 ft | VMP-3-5-090910 | 9/9/2010 | <7.1 | U | | <7.5 | U | | <6.5 | U | | <6.5 | U | | 1200 | | | <3.4 | U | | <5.8 | U | | <5.8 | U | | | | | | | | | | |
| | | VMP-3-5-112210 | 11/22/2010 | 8.9 | | | <7.6 | U | | <6.6 | U | | <6.6 | U | | 1100 | | | <3.4 | U | | 2.3 | J | | <5.8 | U | | | | | | | | | | |
| | | VMP-3-5-020911 | 2/9/2011 | <3.2 | U | | <3.4 | U | | <3 | U | | <3 | U | | 460 | | | <1.5 | U | | <2.6 | U | | <2.6 | U | | | | | | | | | | |
| | | VMP-3-5-041411 | 4/14/2011 | <35 | U | | <36 | U | | <32 | U | | <32 | U | | 1100 | | | <17 | U | | <28 | U | | <28 | U | | | | | | | | | | |
| | | VMP-3-5-080211 | 8/2/2011 | <0.0084 | U | | <0.0087 | U | | 0.0069 | J | | 0.0018 | J | | 0.37 | | | <0.004 | U | | 0.0074 | | | 0.0026 | J | | | | | | | | | | |
| | | VMP-3-5-110811 | 11/8/2011 | <0.0046 | U | | 0.00096 | J | | <0.0042 | J | U | <0.0042 | U | | <0.004 | U | | <0.0022 | U | | 0.0017 | J | | <0.0037 | U | | | | | | | | | | |
| | | VMP-3-5-110811-DUP | 11/8/2011 | <0.0047 | U | | 0.00086 | J | | <0.0043 | J | U | <0.0043 | U | | <0.0041 | U | | <0.0022 | U | | 0.0015 | J | | 0.00056 | J | | | | | | | | | | |
| | | VMP-3-5-012712 | 1/27/2012 | <2.4 | U | | <2.4 | U | | <8.6 | U | | <2.2 | U | | 260 | | | <1.1 | U | | <1.9 | U | | <1.9 | U | | | | | | | | | | |
| | | VMP-3-5-041912 | 4/19/2012 | <0.0051 | U | | 0.0017 | J | | 0.0041 | J | | 0.0013 | J | | 0.098 | | | <0.0024 | U | | 0.015 | | | 0.0045 | | | | | | | | | | | |
| | | VMP-3-5-072712 | 7/27/2012 | <0.0054 | U | | 0.0018 | J | | 0.0028 | J | | 0.0011 | J | | 0.0022 | J | | <0.0026 | U | | 0.0056 | | | 0.0029 | J | | | | | | | | | | |
| | 10 ft | VMP-3-10 | 6/21/2010 | <8.1 | U | | <8.5 | U | | 4.3 | J | | 1.4 | J | | 3500 | | | <3.9 | U | | 2.9 | J | | <6.6 | U | | | | | | | | | | |
| | | VMP-3-10-091010 | 9/10/2010 | <23 | U | | <24 | U | | <21 | U | | <21 | U | | 3000 | | | <11 | U | | <18 | U | | <18 | U | | | | | | | | | | |
| | | VMP-3-10-092010 | 9/20/2010 | <17 | U | | <17 | U | | <15 | U | | <15 | U | | 2400 | | | <7.9 | U | | 6.6 | J | | <13 | U | | | | | | | | | | |
| | | VMP-3-10-112210 | 11/22/2010 | <7.1 | U | | <7.4 | U | | <6.5 | U | | <6.5 | U | | 3200 | | | <3.4 | U | | 2.8 | J | | <5.7 | U | | | | | | | | | | |
| | | VMP-3-10-112210-Dup | 11/22/2010 | <9.9 | U | | <10 | U | | <9 | U | | <9 | U | | 3100 | | | <4.7 | U | | 2.2 | J | | <8 | U | | | | | | | | | | |
| | | VMP-3-10-020811 | 2/8/2011 | <10 | U | | <11 | U | | <9.5 | U | | <9.5 | U | | 3300 | | | <5 | U | | <8.4 | U | | <8.4 | U | | | | | | | | | | |
| | | VMP-3-10-041311 | 4/13/2011 | <60 | U | | <63 | U | | <55 | U | | <55 | U | | 1900 | | | <29 | U | | <49 | U | | <49 | U | | | | | | | | | | |
| | | VMP-3-10-080311 | 8/3/2011 | <0.076 | U | | <0.08 | U | | 0.013 | J | | <0.07 | U | | 26 | | | <0.036 | U | | 0.016 | J | | <0.062 | U | | | | | | | | | | |
| | | VMP-3-10-110811 | 11/8/2011 | <0.0063 | U | | <0.0065 | U | | 0.0012 | J | | <0.0057 | U | | 1.1 | | | <0.003 | U | | 0.0021 | J | | 0.00084 | J | | | | | | | | | | |
| | | VMP-3-10-012712 | 1/27/2012 | <0.045 | U | | <0.047 | U | | 0.021 | J | | 0.017 | J | | 8.9 | | | <0.021 | U | | 0.03 | J | | 0.019 | J | | | | | | | | | | |
| | | VMP-3-10-042012 | 4/20/2012 | <0.0046 | J | U | 0.0015 | J | | <0.0042 | J | U | <0.0042 | J | U | 0.049 | | | <0.0022 | U | | 0.0048 | | | 0.0016 | J | | | | | | | | | | |
| | | VMP-3-10-072312 | 7/23/2012 | <0.0054 | U | | 0.0012 | J | | 0.0018 | J | | <0.0049 | U | | 0.68 | | | <0.0026 | U | | 0.0024 | J | | 0.0012 | J | | | | | | | | | | |
| | | VMP-3-10-101812 | 10/18/2012 | <0.0081 | U | | 0.0035 | J | | 0.0042 | J | J | 0.018 | | | 0.25 | | | <0.0039 | U | | 0.028 | | | 0.017 | | | | | | | | | | | |
| | | VMP-3-10-020613 | 2/6/2013 | <0.0076 | U | | 0.0014 | J | | <0.0069 | U | | <0.0069 | U | | 0.0019 | J | | <0.0036 | U | | <0.0061 | U | | <0.0061 | U | | | | | | | | | | |
| | 22 ft | VMP-3-22-092010 | 9/20/2010 | <22 | U | | <23 | U | | 5.3 | J | | <20 | U | | 3200 | | | <10 | U | | 26 | | | 11 | J | | | | | | | | | | |
| | | VMP-3-22-112210 | 11/22/2010 | <25 | U | | <26 | U | | <23 | U | | <23 | U | | 4100 | | | <12 | U | | 8.8 | J | | <20 | U | | | | | | | | | | |
| | | VMP-3-22-020811 | 2/8/2011 | <12 | U | | <13 | U | | <11 | U | | <11 | U | | 2900 | | | <5.8 | U | | 7.6 | J | | <9.9 | U | | | | | | | | | | |
| | | VMP-3-22-041511 | 4/15/2011 | <67 | U | | <70 | U | | <61 | U | | <61 | U | | 2200 | | | <32 | U | | <54 | U | | <54 | U | | | | | | | | | | |
| | | VMP-3-22-080611 | 8/6/2011 | <0.11 | U | | <0.11 | U | | 0.014 | J | | <0.097 | U | | 23 | | | <0.05 | U | | 0.045 | J | | <0.086 | U | | | | | | | | | | |
| | | VMP-3-22-110811 | 11/8/2011 | <0.0047 | U | | 0.00099 | J | | <0.0043 | J | U | <0.0043 | U | | 0.78 | | | <0.0022 | U | | <0.0038 | J | U | 0.00063 | J | | | | | | | | | | |
| | | VMP-3-22-013012 | 1/30/2012 | <0.019 | U | | <0.02 | U | | <0.017 | U | | <0.017 | U | | 5.9 | | | <0.0089 | U | | 0.0083 | J | | <0.015 | U | | | | | | | | | | |
| | | VMP-3-22-042012 | 4/20/2012 | 0.002 | J | | 0.0012 | J | | <0.0043 | J | U | <0.0043 | U | | 0.28 | | | <0.0022 | U | | 0.0032 | J | | 0.0011 | J | | | | | | | | | | |
| | | VMP-3-22-072312 | 7/23/2012 | <0.0053 | U | | 0.00097 | J | | 0.00091 | J | | <0.0048 | U | | 0.01 | | | <0.0025 | U | | 0.0013 | J | | <0.0042 | U | | | | | | | | | | |
| | | VMP-3-22-101812 | 10/18/2012 | <0.008 | U | | <0.0083 | U | | <0.0073 | U | UJ | <0.0073 | U | | 0.012 | | | <0.0038 | U | | 0.003 | J | | <0.0064 | U | | | | | | | | | | |
| | | VMP-3-22-020613 | 2/6/2013 | <0.0078 | U | | 0.0014 | J | | <0.0071 | U | | <0.0071 | U | | 0.0032 | J | | <0.0037 | U | | <0.0063 | U | | <0.0063 | U | | | | | | | | | | |
| | 31.5 ft | VMP-3-31.5-090910 | 9/9/2010 | <41 | U | | <43 | U | | 38 | | | 17 | J | | 8300 | | | <19 | U | | 87 | | | 26 | J | | | | | | | | | | |
| | | VMP-3-31.5-112210 | 11/22/2010 | <28 | U | | <30 | U | | 9.8 | J | | <26 | U | | 8000 | | | <14 | U | | 68 | | | 19 | J | | | | | | | | | | |
| | | VMP-3-31.5-020911 | 2/9/2011 | <27 | U | | <28 | U | | <25 | U | | <25 | U | | 3200 | | | <13 | U | | 54 | | | 13 | J | | | | | | | | | | |
| | | VMP-3-31.5-041411 | 4/14/2011 | <220 | U | | <230 | U | | <200 | U | | <200 | U | | 4300 | | | <110 | U | | <180 | U | | <180 | U | | | | | | | | | | |
| | | VMP-3-31.5-041411-DUP | 4/14/2011 | <220 | U | | <230 | U | | <200 | U | | <200 | U | | 3900 | | | <110 | U | | <180 | U | | <180 | U | | | | | | | | | | |
| | | VMP-3-31.5-080211 | 8/2/2011 | <500 | U | | <530 | U | | <460 | U | | <460 | U | | 9100 | | | <240 | U | | <410 | U | | <410 | U | | | | | | | | | | |
| | | VMP-3-31.5-080211-Dup | 8/2/2011 | <300 | U | | <310 | U | | <270 | U | | <270 | U | | 13000 | | | <140 | U | | <240 | U | | <240 | U | | | | | | | | | | |
| | | VMP-3-31.5-110811 | 11/8/2011 | <12 | U | | <12 | U | | <11 | U | | <11 | U | | 650 | | | <5.6 | U | | 1.8 | J | | <9.5 | U | | | | | | | | | | |
| | | VMP-3-31.5-012712 | 1/27/2012 | <74 | U | | <78 | U | | <270 | U | | <68 | U | | 2900 | | J | <35 | U | | <60 | U | | <60 | U | | | | | | | | | | |
| | | VMP-3-31.5-041912 | 4/19/2012 | <130 | U | | <130 | U | | <120 | U | | <120 | U | | 9600 | | | <61 | U | | <100 | U | | <100 | U | | | | | | | | | | |
| | | VMP-3-31.5-041912-Dup | 4/19/2012 | <120 | U | | <130 | U | | <110 | U | | <110 | U | | 9800 | | | <58 | U | | <99 | U | | <99 | U | | | | | | | | | | |
| | | VMP-3-31.5-072312 | 7/23/2012 | <31 | U | | <32 | U | | <28 | U | | <28 | U | | 5300 | | | <15 | U | | <25 | U | | <25 | U | | | | | | | | | | |
| | | VMP-3-31.5-101912 | 10/19/2012 | <2.5 | U | | <2.6 | U | | <2.3 | U | | <2.3 | U | | 39 | | | <1.2 | U | | 0.22 | J | | <2 | U | | | | | | | | | | |
| | | VMP-3-31.5-020713 | 2/7/2013 | <14 | U | | <14 | U | | <13 | U | | <13 | U | | 1700 | | | <6.6 | U | | <11 | U | | <11 | U | | | | | | | | | | |
| | 39.5 ft | VMP-3-39-101912 | 10/19/2012 | <250 | U | | <260 | U | | <230 | U | | <230 | U | | 4200 | | | <120 | U | | 84 | J | | <200 | U | | | | | | | | | | |
| | | VMP-3-39-021213 | 2/12/2013 | <71 | U | | <74 | U | | <65 | U | | <65 | U | | 5700 | | | <34 | U | | 14 | J | | <57 | U | | | | | | | | | | |
| VMP-4 | 5 ft | VMP-4-5-082510 | 8/25/2010 | <0.39 | U | | <0.4 | U | | 0.054 | J | | <0.35 | U | | 220 | | | <0.18 | U | | <0.31 | U | | <0.31 | U | | | | | | | | | | |
| | | VMP-4-5-112210 | 11/22/2010 | <14 | U | | <15 | U | | <13 | U | | <13 | U | | 1800 | | | <6.9 | U | | 11 | J | | <12 | U | | | | | | | | | | |
| | | VMP-4-5-021411 | 2/14/2011 | <0.85 | U | | <0.88 | U | | <0.77 | U | | <0.77 | U | | 260 | | | <0.4 | U | | 0.45 | J | | <0.68 | U | | | | | | | | | | |
| | | VMP-4-5-041911 | 4/19/2011 | <39 | U | | <41 | U | | <36 | U | | <36 | U | | 1100 | | | <18 | U | | <31 | U | | <31 | U | | | | | | | | | | |
| | | VMP-4-5-080311 | 8/3/2011 | <0.084 | U | | <0.087 | U | | 0.016 | J | | <0.076 | U | | 28 | | | <0.04 | U | | 0.012 | J | | <0.068 | U | | | | | | | | | | |
| | | VMP-4-5-110911 | 11/9/2011 | <0.0046 | U | | 0.00092 | J | | <0.0042 | J | U | <0.0042 | J | U | 0.92 | | | <0.0022 | U | | 0.0025 | J | | 0.0013 | J | | | | | | | | | | |
| | | VMP-4-5-013012 | 1/30/2012 | <0.24 | U | | <0.24 | U | | <0.22 | U | | <0.22 | U | | 170 | | J | <0.11 | U | | <0.19 | U | | <0.19 | U | | | | | | | | | | |
| | | VMP-4-5-042512 | 4/25/2012 | <0.0058 | U | | 0.0014 | J | | 0.0041 | J | | <0.0053 | J | U | 0.47 | | | <0.0028 | U | | 0.018 | | | 0.0059 | | | | | | | | | | | |
| | | VMP-4-5-072512 | 7/25/2012 | <0.0058 | U | | 0.00096 | J | | 0.007 | | | 0.0028 | J | | 0.02 | | | <0.0027 | U | | 0.043 | | | 0.013 | | | | | | | | | | | |
| | | VMP-4-5-101812 | 10/18/2012 | <0.0084 | U | | <0.0087 | U | | 0.0019 | J | J | <0.0076 | U | | 0.007 | J | | <0.004 | U | | 0.0022 | J | | <0.0068 | U | | | | | | | | | | |
| | | VMP-4-5-020713 | 2/7/2013 | <0.0066 | U | | 0.0012 | J | | <0.0061 | J | U | <0.0061 | U | | 0.013 | | | <0.0032 | U | | 0.0012 | J | | <0.0054 | U | | | | | | | | | | |
| | 12 ft | VMP-4-12-082510 | 8/25/2010 | <6.8 | U | | <7.1 | U | | 1.8 | J | | 1.5 | J | | 1400 | | | <3.2 | U | | 5.6 | | | <5.5 | U | | | | | | | | | | |
| | | VMP-4-12-112310 | 11/23/2010 | <6.9 | U | | <7.2 | U | | 3.5 | J | | 2.6 | J | | 1300 | | | <3.3 | U | | 6.2 | | | <5.6 | U | | | | | | | | | | |
| | | VMP-4-12-021411 | 2/14/2011 | <1.7 | U | | <1.8 | U | | <1.6 | U | | 0.52 | J | | 600 | | | <0.83 | U | | 2.8 | | | 0.72 | J | | | | | | | | | | |
| | | VMP-4-12-041911 | 4/19/2011 | <34 | U | | <35 | U | | <31 | U | | <31 | U | | 1200 | | | <16 | U | | 51 | | | 7.6 | J | | | | | | | | | | |
| | | VMP-4-12-080311 | 8/3/2011 | <3.9 | U | | <4 | U | | <3.5 | U | | <3.5 | U | | 440 | | | <1.8 | U | | 0.77 | J | | <3.1 | U | | | | | | | | | | |
| | | VMP-4-12-080311-Dup | 8/3/2011 | <7.8 | U | | <8.1 | U | | <7.1 | U | | <7.1 | U | | 390 | | | <3.7 | U | | <6.3 | U | | <6.3 | U | | | | | | | | | | |
| | | VMP-4-12-110911 | 11/9/2011 | <1.2 | U | | <1.2 | U | UJ | <1.1 | U | | <1.1 | U | | 64 | | | <0.56 | U | | <0.95 | U | | <0.95 | U | | | | | | | | | | |
| | | VMP-4-12-013012 | 1/30/2012 | <2.4 | U | | <2.5 | U | | <2.2 | U | | <2.2 | U | | 380 | | | <1.1 | U | | 1.6 | J | | <1.9 | U | | | | | | | | | | |
| | | VMP-4-12-041812 | 4/18/2012 | <0.0054 | U | | <0.0056 | U | | 0.0017 | J | | 0.0007 | J | | 0.092 | | | <0.0026 | U | | 0.011 | | | 0.0025 | J | | | | | | | | | | |
| | | VMP-4-12-072312 | 7/23/2012 | <0.026 | U | | <0.027 | U | | 0.029 | | | 0.014 | J | | 0.46 | | | <0.012 | U | | 0.21 | | | 0.068 | | | | | | | | | | | |
| | | VMP-4-12-101812 | 10/18/2012 | <0.0081 | U | | <0.0085 | U | | 0.0012 | J | J | <0.0074 | U | | 0.0064 | J | | <0.0039 | U | | 0.042 | | | 0.008 | | | | | | | | | | | |
| | | VMP-4-12-101812-Dup | 10/18/2012 | <0.0084 | U | | <0.0087 | U | | 0.004 | J | J | 0.002 | J | | 0.01 | | | <0.004 | U | | 0.051 | | | 0.011 | | | | | | | | | | | |
| | | VMP-4-12-020713 | 2/7/2013 | <0.0072 | U | | 0.0012 | J | | 0.0073 | | | <0.0066 | J | U | 0.049 | | | <0.0034 | U | | <0.0058 | U | | <0.0058 | U | | | | | | | | | | |
| | | VMP-4-12-020713-DUP | 2/7/2013 | <0.0074 | U | | 0.0019 | J | | <0.0068 | U | | <0.0068 | U | | 0.051 | | | <0.0035 | U | | <0.006 | U | | <0.006 | U | | | | | | | | | | |
| | 23.5 ft | VMP - 4 - 23.5 - 083110 | 8/31/2010 | <7.8 | U | | <8.1 | U | | 190 | | J | 66 | | J | 5800 | | J | <3.7 | U | | 1800 | | J | 600 | | J | | | | | | | | | |
| | | VMP-4-23.5-112310 | 11/23/2010 | <78 | U | | <82 | U | | 31 | J | | <72 | U | | 4800 | | | <37 | U | | 1100 | | | 310 | | | | | | | | | | | |
| | | VMP-4-23.5-021411 | 2/14/2011 | <2.8 | U | | <3 | U | | <2.6 | U | | <2.6 | U | | 2400 | | J | <1.4 | U | | 130 | | J | 30 | | J | | | | | | | | | |
| | | VMP-4-23.5-042011 | 4/20/2011 | <180 | U | | <190 | U | | <160 | U | | <160 | U | | 5200 | | | <86 | U | | 900 | | | 230 | | | | | | | | | | | |
| | | VMP-4-23.5-042011-DUP | 4/20/2011 | <180 | U | | <190 | U | | <160 | U | | <160 | U | | 4800 | | | <86 | U | | 830 | | | 230 | | | | | | | | | | | |
| | | VMP-4-23.5-080611 | 8/6/2011 | <7.6 | U | | <7.9 | U | | 11 | | | 6.1 | J | | 2800 | | | <3.6 | U | | 320 | | | 91 | | | | | | | | | | | |
| | | VMP-4-23.5-110911 | 11/9/2011 | <22 | U | | <24 | U | | <21 | U | | <21 | U | | 1500 | | | <11 | U | | 4.2 | J | | <18 | U | | | | | | | | | | |
| | | VMP-4-23.5-013012 | 1/30/2012 | <48 | U | | <50 | U | | <44 | U | | <44 | U | | 4800 | | J | <23 | U | | 190 | | J | 34 | J | J | | | | | | | | | |
| | | VMP-4-23.5-013012-DUP | 1/30/2012 | <34 | U | | <35 | U | | <31 | U | | <31 | U | | 3300 | | J | <16 | U | | 57 | | J | 8.8 | J | | | | | | | | | | |
| | | VMP-4-23.5-041912 | 4/19/2012 | <10 | U | | <11 | U | | <9.6 | U | | <9.6 | U | | 2400 | | | <5 | U | | 13 | | | 4.4 | J | | | | | | | | | | |
| | | VMP-4-23.5-072312 | 7/23/2012 | <5 | U | | <5.3 | U | | <4.6 | U | | 4.9 | | | 1500 | | | <2.4 | U | | 210 | | | 60 | | | | | | | | | | | |
| | | VMP-4-23.5-101812 | 10/18/2012 | <5.5 | U | | <5.8 | U | | <5.1 | U | | <5.1 | U | | 110 | | | <2.6 | U | | 7.2 | | | 2.6 | J | | | | | | | | | | |
| | | VMP-4-23.5-020713 | 2/7/2013 | <1.8 | U | | <1.8 | U | | <1.6 | U | | <1.6 | U | | 150 | | | <0.84 | U | | <1.4 | U | | <1.4 | U | | | | | | | | | | |
| | 39 ft | VMP-4-39-042111 | 4/21/2011 | <220 | U | | <240 | U | | <210 | U | | <210 | U | | 4300 | | | <110 | U | | 670 | | | 170 | J | | | | | | | | | | |
| | | VMP-4-39-041912 | 4/19/2012 | <5.4 | U | | <5.6 | U | | 5.1 | | | 2.6 | J | | 3100 | | | <2.6 | U | | 200 | | | 53 | | | | | | | | | | | |
| | | VMP-4-39-072312 | 7/23/2012 | <8.1 | U | | <8.5 | U | | <7.4 | U | | <7.4 | U | | 3500 | | J | <3.8 | U | | 310 | | J | 83 | | J | | | | | | | | | |
| | | VMP-4-39-101812 | 10/18/2012 | <100 | U | | <110 | U | | <93 | U | | <93 | U | | 1500 | | | <48 | U | | 190 | | | 44 | J | | | | | | | | | | |
| | | VMP-4-39-101812-Dup | 10/18/2012 | <93 | U | | <97 | U | | <85 | U | | <85 | U | | 1500 | | | <44 | U | | 190 | | | 47 | J | | | | | | | | | | |
| | | VMP-4-39-020713 | 2/7/2013 | <14 | U | | <15 | U | | 12 | J | | 16 | | | 1800 | | | <6.9 | U | | 790 | | | 310 | | | | | | | | | | | |

SEE LAST PAGE OF TABLE FOR NOTES

**TABLE 5**
**CUMULATIVE SUMMARY OF SOIL VAPOR ANALYTICAL DETECTIONS AND SCREENING RESULTS: VILLAGE - VOCS**

| Location | Depth | Sample ID | Sample Date | Trichloroethene | | | Trichlorofluoromethane | | | 1,2,4-Trimethylbenzene | | | 1,3,5-Trimethylbenzene | | | 2,2,4-Trimethylpentane | | | Vinyl chloride | | | m,p-Xylene | | | o-Xylenes | | | $^{3}$Butane, 2,2-dimethyl- | | | $^{3}$Butane, 2,3-dimethyl- | | | $^{3}$Cyclobutane, ethyl- | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | 1.5 | | | 860 | | | | | | | | | | | | 0.29 | | | 130 | | | 120 | | | | | | | | | | | |
| | | | | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result (ppbV) | Lab Quals | URS Quals | Result (ppbV) | Lab Quals | URS Quals | Result (ppbV) | Lab Quals | URS Quals |
| VMP-5 | 5 ft | VMP-5-5-090910 | 9/9/2010 | <14 | U | | <15 | U | | 13 | | | 6.9 | J | | 1600 | | | <6.7 | U | | 9 | J | | 6.4 | J | | | | | | | | | | |
| | | VMP-5-5-112210 | 11/22/2010 | <3.5 | U | | <3.6 | U | | <3.2 | U | | <3.2 | U | | 1700 | | | <1.6 | U | | <2.8 | U | | <2.8 | U | | | | | | | | | | |
| | | VMP-5-5-021611 | 2/16/2011 | <0.022 | U | | <0.023 | U | | <0.02 | U | | <0.02 | U | | 24 | | | <0.01 | U | | 0.0062 | J | J | <0.018 | U | | | | | | | | | | |
| | | VMP-5-5-042111 | 4/21/2011 | <0.071 | U | | <0.074 | U | | <0.065 | U | | <0.065 | U | | 0.097 | | | <0.034 | U | | <0.057 | U | | <0.057 | U | | | | | | | | | | |
| | | VMP-5-5-080511 | 8/5/2011 | <0.0068 | J | U | 0.0014 | J | | 0.002 | J | | <0.0062 | U | | 0.23 | | | <0.0032 | U | | 0.0083 | | | 0.0024 | J | | | | | | | | | | |
| | | VMP-5-5-111111 | 11/11/2011 | <0.005 | U | | <0.0052 | U | | 0.0023 | J | | 0.0013 | J | | 0.97 | | | <0.0024 | U | | 0.0059 | | | 0.0016 | J | | | | | | | | | | |
| | | VMP-5-5-013012 | 1/30/2012 | 0.015 | J | | 0.011 | J | | 0.032 | J | | 0.011 | J | | 2.3 | | | <0.024 | U | | 0.08 | | | 0.026 | J | | | | | | | | | | |
| | | VMP-5-5-041112 | 4/11/2012 | 0.0081 | | | <0.0051 | U | | 0.0026 | J | | 0.00093 | J | | 0.0063 | | | <0.0023 | U | | 0.0074 | | | 0.0021 | J | | | | | | | | | | |
| | | VMP-5-5-071312 | 7/13/2012 | <0.0054 | U | | 0.0016 | J | | <0.005 | J | U | <0.005 | J | U | <0.0047 | J | U | <0.0026 | U | | <0.0044 | J | U | <0.0044 | J | U | | | | | | | | | | |
| | | VMP-5-5-101212 | 10/12/2012 | <0.0068 | U | | 0.0015 | J | | <0.0062 | U | | <0.0062 | U | | 0.004 | J | | <0.0032 | U | | <0.0055 | U | | <0.0055 | U | | | | | | | | | | |
| | | VMP-5-5-012513 | 1/25/2013 | <0.0071 | U | | <0.0074 | U | | <0.0065 | U | | <0.0065 | U | | 0.002 | J | | <0.0034 | U | | <0.0057 | U | | <0.0057 | U | | | | | | | | | | |
| | 12.5 ft | VMP-5-12.5-090910 | 9/9/2010 | <7.1 | U | | <7.4 | U | | 6.1 | J | | 3 | J | | 1500 | | | <3.4 | U | | 3.2 | J | | 2.2 | J | | | | | | | | | | |
| | | VMP-5-12.5-112310 | 11/23/2010 | <0.35 | U | | <0.37 | U | | <0.32 | U | | <0.32 | U | | 110 | | | <0.17 | U | | 0.2 | J | | <0.29 | U | | | | | | | | | | |
| | | VMP-5-12.5-021611 | 2/16/2011 | <1.1 | U | | <1.1 | U | | <0.98 | U | | <0.98 | U | | 170 | | | <0.51 | U | | <0.86 | U | | <0.86 | U | | | | | | | | | | |
| | | VMP-5-12.5-042111 | 4/21/2011 | <0.076 | U | | <0.079 | U | | <0.069 | U | | <0.069 | U | | 0.081 | | | <0.036 | U | | <0.061 | U | | <0.061 | U | | | | | | | | | | |
| | | VMP-5-12.5-080611 | 8/6/2011 | <6.7 | U | | <7 | U | | <6.1 | U | | <6.1 | U | | 810 | | | <3.2 | U | | <5.4 | U | | <5.4 | U | | | | | | | | | | |
| | | VMP-5-12.5-111111 | 11/11/2011 | 0.0017 | J | | <0.0049 | U | | 0.0014 | J | | 0.00061 | J | | 0.0093 | | | <0.0022 | U | | 0.0025 | J | | 0.00074 | J | | | | | | | | | | |
| | | VMP-5-12.5-013012 | 1/30/2012 | <0.015 | U | | <0.016 | U | | <0.014 | U | | <0.014 | U | | 0.72 | | | <0.0073 | U | | 0.0094 | J | | 0.0027 | J | | | | | | | | | | |
| | | VMP-5-12.5-041112 | 4/11/2012 | 0.0012 | J | | 0.0014 | J | | 0.0011 | J | | <0.0043 | U | | 0.0032 | J | | <0.0022 | U | | 0.0044 | | | 0.0013 | J | | | | | | | | | | |
| | | VMP-5-12.5-071212 | 7/12/2012 | <0.0055 | U | | 0.0014 | J | | 0.12 | | | 0.022 | | | <0.0048 | U | | <0.0026 | U | | 0.012 | | | 0.0036 | J | | | | | | | | | | |
| | | VMP-5-12.5-101112 | 10/11/2012 | <0.013 | U | | <0.014 | U | | <0.012 | U | | <0.012 | U | | 0.009 | J | | <0.0062 | U | | <0.011 | U | | <0.011 | U | | | | | | | | | | |
| | | VMP-5-12.5-012413 | 1/24/2013 | <0.0069 | U | | 0.0012 | J | | <0.0063 | U | | <0.0063 | U | | 0.0079 | | | <0.0033 | U | | <0.0056 | U | | <0.0056 | U | | | | | | | | | | |
| | 31 ft | VMP-5-31-090910 | 9/9/2010 | <30 | U | | <31 | U | | <27 | U | | <27 | U | | 4400 | | | <14 | U | | 7.7 | J | | <24 | U | | | | | | | | | | |
| | | VMP-5-31-112310 | 11/23/2010 | <18 | U | | <19 | U | | <17 | U | | <17 | U | | 4700 | | | <8.8 | U | | 12 | J | | <15 | U | | | | | | | | | | |
| | | VMP-5-31-021611 | 2/16/2011 | <7.4 | U | | <7.8 | U | | <6.8 | U | | <6.8 | U | | 3100 | | | <3.5 | U | | 5.5 | J | | <6 | U | | | | | | | | | | |
| | | VMP-5-31-042111 | 4/21/2011 | <110 | U | | <120 | U | | <100 | U | | <100 | U | | 3800 | | | <53 | U | | <89 | U | | <89 | U | | | | | | | | | | |
| | | VMP-5-31-080611 | 8/6/2011 | <62 | U | | <65 | U | | <57 | U | | <57 | U | | 3700 | | | <30 | U | | <50 | U | | <50 | U | | | | | | | | | | |
| | | VMP-5-31-111111 | 11/11/2011 | <31 | U | | <33 | U | | <29 | U | | <29 | U | | 3000 | | | <15 | U | | 6.9 | J | | <25 | U | | | | | | | | | | |
| | | VMP-5-31-013012 | 1/30/2012 | <16 | U | | <17 | U | | <15 | U | | <15 | U | | 2900 | | | <7.6 | U | | <13 | U | | <13 | U | | | | | | | | | | |
| | | VMP-5-31-041112 | 4/11/2012 | <0.051 | U | | <0.054 | U | | <0.047 | U | | <0.047 | U | | 4.8 | | | <0.024 | U | | 0.012 | J | | <0.041 | U | | | | | | | | | | |
| | | VMP-5-31-071212 | 7/12/2012 | <0.0054 | U | | 0.0015 | J | | <0.0049 | J | U | <0.0049 | U | | 0.3 | | | <0.0026 | U | | <0.0044 | J | U | <0.0044 | U | | | | | | | | | | |
| | | VMP-5-31-101112 | 10/11/2012 | <0.0076 | U | | 0.0013 | J | | <0.0069 | U | | <0.0069 | U | | 0.048 | | | <0.0036 | U | | <0.0061 | U | | <0.0061 | U | | | | | | | | | | |
| | | VMP-5-31-012413 | 1/24/2013 | <0.075 | U | | <0.079 | U | | <0.069 | U | | <0.069 | U | | 0.13 | | | <0.036 | U | | <0.061 | U | | <0.061 | U | | | | | | | | | | |
| | 40 ft | VMP-5-40-042111 | 4/21/2011 | <120 | U | | <120 | U | | <100 | U | | <100 | U | | 3500 | | | <55 | U | | <94 | U | | <94 | U | | | | | | | | | | |
| | | VMP-5-40-013012 | 1/30/2012 | <34 | U | | <35 | U | | <31 | U | | <31 | U | | 2500 | | | <16 | U | | <27 | U | | <27 | U | | | | | | | | | | |
| | | VMP-5-40-041212 | 4/12/2012 | <0.05 | U | | <0.052 | U | | <0.046 | U | | <0.046 | U | | 24 | | | <0.024 | U | | 0.02 | J | | <0.041 | U | | | | | | | | | | |
| | | VMP-5-40-071212 | 7/12/2012 | <0.054 | U | | <0.056 | U | | <0.049 | U | | <0.049 | U | | 2 | | | <0.026 | U | | <0.044 | U | | <0.044 | U | | | | | | | | | | |
| | | VMP-5-40-101112 | 10/11/2012 | <0.008 | U | | 0.0027 | J | | <0.0073 | U | | <0.0073 | U | | 1.1 | | | <0.0038 | U | | <0.0064 | U | | <0.0064 | U | | | | | | | | | | |
| | | VMP-5-40-012513 | 1/25/2013 | <0.023 | U | | <0.024 | U | | <0.021 | U | | <0.021 | U | | 1.7 | | | <0.011 | U | | <0.019 | U | | <0.019 | U | | | | | | | | | | |
| | | VMP-5-40-012513-Dup | 1/25/2013 | <0.022 | U | | <0.024 | U | | <0.021 | U | | <0.021 | U | | 1.7 | | | <0.011 | U | | <0.018 | U | | <0.018 | U | | | | | | | | | | |
| VMP-6 | 5 ft | VMP-6-5-090810 | 9/8/2010 | <1.2 | U | | <1.2 | U | | 0.74 | J | | 0.34 | J | | 340 | | | <0.56 | U | | 0.47 | J | | 0.33 | J | | | | | | | | | | |
| | | VMP-6-5-111610 | 11/16/2010 | <7.4 | U | | <7.8 | U | | <6.8 | U | | <6.8 | U | | 2300 | | | <3.5 | U | | 3.4 | J | | <6 | U | | | | | | | | | | |
| | | VMP-6-5-020711 | 2/7/2011 | 0.0022 | J | | 0.0013 | J | | 0.0071 | | | 0.0031 | J | | 0.96 | | | <0.003 | U | | 0.025 | | | 0.01 | J | | | | | | | | | | |
| | | VMP-6-5-040811 | 4/8/2011 | <0.014 | U | | <0.014 | U | | <0.013 | J | U | <0.013 | U | | 1.3 | | | <0.0066 | U | | 0.0039 | J | | <0.011 | U | | | | | | | | | | |
| | | VMP-6-5-080411 | 8/4/2011 | <0.36 | U | | <0.38 | U | | <0.33 | U | | <0.33 | U | | 6.5 | | | <0.17 | U | | 0.16 | J | | <0.29 | U | | | | | | | | | | |
| | | VMP-6-5-110911 | 11/9/2011 | <0.0043 | U | | 0.00095 | J | | 0.028 | | | 0.02 | | | 0.071 | | | <0.002 | U | | 0.13 | | | 0.056 | | | | | | | | | | | |
| | | VMP-6-5-013112 | 1/31/2012 | <0.051 | U | | <0.053 | U | | <0.047 | U | | <0.047 | U | | 2.9 | | | <0.024 | U | | 0.014 | J | | <0.041 | U | | | | | | | | | | |
| | | VMP-6-5-041212 | 4/12/2012 | <0.0054 | U | | <0.0056 | U | | 0.0017 | J | | <0.0049 | U | | 0.04 | | | <0.0026 | U | | 0.0046 | | | 0.0023 | J | | | | | | | | | | |
| | | VMP-6-5-071612 | 7/16/2012 | <0.0054 | U | | 0.0014 | J | | <0.0049 | J | U | <0.0049 | J | U | 0.0025 | J | | <0.0026 | U | | 0.0032 | J | | 0.0011 | J | | | | | | | | | | |
| | | VMP-6-5-101012 | 10/10/2012 | <0.0074 | U | | 0.00089 | J | | <0.0068 | U | | <0.0068 | U | | 0.016 | | | <0.0035 | U | | <0.006 | U | | <0.006 | U | | | | | | | | | | |
| | | VMP-6-5-021213 | 2/12/2013 | <0.0066 | U | | 0.0013 | J | | <0.0061 | U | | <0.0061 | U | | 0.058 | | | <0.0032 | U | | <0.0054 | U | | <0.0054 | U | | | | | | | | | | |
| | 10 ft | VMP-6-10-090810 | 9/8/2010 | <1.3 | U | | <1.3 | U | | 0.62 | J | J | 0.29 | J | J | 930 | | J | <0.61 | U | | 0.83 | J | J | 0.32 | J | J | | | | | | | | | | |
| | | VMP-6-10-111710 | 11/17/2010 | <0.0069 | J | U | 0.00081 | J | | <0.0063 | U | | <0.0063 | U | | 0.039 | | | <0.0033 | U | | <0.0056 | J | U | <0.0056 | U | | | | | | | | | | |
| | | VMP-6-10-020711 | 2/7/2011 | 0.0018 | J | | <0.0071 | U | | <0.0062 | U | | <0.0062 | U | | 0.061 | | | <0.0032 | U | | <0.0055 | U | | <0.0055 | U | | | | | | | | | | |
| | | VMP-6-10-040811 | 4/8/2011 | <0.16 | U | | <0.17 | U | | <0.15 | U | | <0.15 | U | | 52 | | | <0.077 | U | | 0.032 | J | | <0.13 | U | | | | | | | | | | |
| | | VMP-6-10-080411 | 8/4/2011 | <1.2 | U | | <1.2 | U | | <1 | U | | <1 | U | | 940 | | | <0.55 | U | | <0.93 | U | | <0.93 | U | | | | | | | | | | |
| | | VMP-6-10-111011 | 11/10/2011 | <0.0045 | U | | <0.0047 | U | | 0.00076 | J | | <0.0041 | U | | 0.0065 | | | <0.0021 | U | | 0.0012 | J | | <0.0036 | U | | | | | | | | | | |
| | | VMP-6-10-013112 | 1/31/2012 | <0.8 | U | | <0.84 | U | | <2.9 | U | | <0.73 | U | | 310 | | J | <0.38 | U | | <0.65 | U | | <0.65 | U | | | | | | | | | | |
| | | VMP-6-10-041212 | 4/12/2012 | <0.0052 | U | | 0.0015 | J | | 0.0018 | J | | <0.0048 | U | | 0.024 | | | <0.0025 | U | | 0.0043 | | | 0.002 | J | | | | | | | | | | |
| | | VMP-6-10-071612 | 7/16/2012 | <0.0071 | U | | 0.0013 | J | | <0.0065 | J | U | <0.0065 | J | U | 0.0054 | J | | <0.0034 | U | | 0.0038 | J | | <0.0057 | J | U | | | | | | | | | | |
| | | VMP-6-10-101112 | 10/11/2012 | <0.0078 | U | | 0.0015 | J | | <0.0071 | U | | <0.0071 | U | | 0.043 | | | <0.0037 | U | | <0.0063 | U | | <0.0063 | U | | | | | | | | | | |
| | | VMP-6-10-020513 | 2/5/2013 | <0.0074 | U | | <0.0078 | J | U | <0.0068 | U | | <0.0068 | U | | 0.0016 | J | | <0.0035 | U | | <0.006 | U | | <0.006 | U | | | | | | | | | | |
| | 31.5 ft | VMP-6-31.5-090810 | 9/8/2010 | <8.6 | U | | <9 | U | | 22 | | | 5.3 | J | | 3100 | | | <4.1 | U | | 51 | | | <7 | U | | | | | | | | | | |
| | | VMP-6-31.5-111710 | 11/17/2010 | <14 | U | | <14 | U | | 15 | | | 3.1 | J | | 3600 | | | <6.4 | U | | 45 | | | <11 | U | | | | | | | | | | |
| | | VMP-6-31.5-020711 | 2/7/2011 | <13 | U | | <14 | U | | 27 | | | 4.2 | J | | 3200 | | | <6.2 | U | | 64 | | | <10 | U | | | | | | | | | | |
| | | VMP-6-31.5-041111 | 4/11/2011 | <10 | U | | <10 | U | | 14 | | | <9.2 | U | | 2400 | | | <4.8 | U | | 28 | | | <8.1 | U | | | | | | | | | | |
| | | VMP-6-31.5-080411 | 8/4/2011 | <7.5 | U | | <7.8 | U | | <6.8 | U | | <6.8 | U | | 2000 | | | <3.6 | U | | 5.2 | J | | <6 | U | | | | | | | | | | |
| | | VMP-6-31.5-111011 | 11/10/2011 | <12 | U | | <12 | U | | <10 | U | | <10 | U | | 2200 | | | <5.5 | U | | <9.3 | U | | <9.3 | U | | | | | | | | | | |
| | | VMP-6-31.5-013112 | 1/31/2012 | <4.6 | U | | <4.8 | U | | <17 | U | | <4.2 | U | | 1800 | | J | <2.2 | U | | 1.8 | J | J | <3.7 | U | | | | | | | | | | |
| | | VMP-6-31.5-041212 | 4/12/2012 | <0.62 | U | | <0.64 | U | | <0.56 | U | | <0.56 | U | | 220 | | | <0.29 | U | | 0.13 | J | | <0.5 | U | | | | | | | | | | |
| | | VMP-6-31.5-071612 | 7/16/2012 | <0.0097 | U | | <0.01 | U | | 0.0049 | J | | <0.0089 | J | U | 3.1 | | | <0.0046 | U | | 0.0035 | J | | 0.0024 | J | | | | | | | | | | |
| | | VMP-6-31.5-101112 | 10/11/2012 | 0.0055 | J | | 0.0021 | J | | <0.0069 | U | | <0.0069 | U | | 0.71 | | | <0.0036 | U | | <0.0061 | U | | <0.0061 | U | | | | | | | | | | |
| | | VMP-6-31.5-020513 | 2/5/2013 | <0.0069 | U | | <0.0072 | J | U | <0.0063 | U | | <0.0063 | U | | 0.058 | | | <0.0033 | U | | <0.0056 | U | | <0.0056 | U | | | | | | | | | | |
| | 39 ft | VMP-6-39-041111 | 4/11/2011 | <12 | U | | <12 | U | | 21 | | | 3.4 | J | | 2300 | | | <5.7 | U | | 41 | | | <9.7 | U | | | | | | | | | | |
| | | VMP-6-39-013112 | 1/31/2012 | <4.6 | U | | <4.8 | U | | <17 | U | | <4.2 | U | | 2200 | | J | <2.2 | U | | 4.3 | | J | <3.7 | U | | | | | | | | | | |
| | | VMP-6-39-041212 | 4/12/2012 | <0.45 | U | | <0.47 | U | | 0.73 | | | 0.48 | | | 340 | | | <0.21 | U | | 2 | | | <0.36 | U | | | | | | | | | | |
| | | VMP-6-39-071612 | 7/16/2012 | <0.021 | U | | <0.022 | U | | <0.019 | U | | <0.019 | U | | 8.1 | | | <0.01 | U | | 0.0063 | J | | <0.017 | U | | | | | | | | | | |
| | | VMP-6-39-071612-Dup | 7/16/2012 | <0.021 | U | | <0.022 | U | | <0.02 | U | | <0.02 | U | | 8.2 | | | <0.01 | U | | <0.017 | U | | <0.017 | U | | | | | | | | | | |
| | | VMP-6-39-101112 | 10/11/2012 | <0.014 | U | | <0.015 | U | | <0.013 | U | | <0.013 | U | | 4.9 | | | <0.0069 | U | | <0.012 | U | | <0.012 | U | | | | | | | | | | |
| | | VMP-6-39-020513 | 2/5/2013 | <0.0071 | U | | <0.0074 | J | U | 0.024 | | | 0.0055 | J | | 0.63 | | | <0.0034 | U | | 0.023 | | | <0.0057 | U | | | | | | | | | | |

SEE LAST PAGE OF TABLE FOR NOTES

**TABLE 5**
**CUMULATIVE SUMMARY OF SOIL VAPOR ANALYTICAL DETECTIONS AND SCREENING RESULTS: VILLAGE - VOCS**

| Location | Depth | Sample ID | Sample Date | Trichloroethene | | | Trichlorofluoromethane | | | 1,2,4-Trimethylbenzene | | | 1,3,5-Trimethylbenzene | | | 2,2,4-Trimethylpentane | | | Vinyl chloride | | | m,p-Xylene | | | o-Xylenes | | | $^{3}$Butane, 2,2-dimethyl- | | | $^{3}$Butane, 2,3-dimethyl- | | | $^{3}$Cyclobutane, ethyl- | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | 1.5 | | | 860 | | | | | | | | | | | | 0.29 | | | 130 | | | 120 | | | | | | | | | | | |
| | | | | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result (ppbV) | Lab Quals | URS Quals | Result (ppbV) | Lab Quals | URS Quals | Result (ppbV) | Lab Quals | URS Quals |
| VMP-7 | 5 ft | VMP-7-5-082610 | 8/26/2010 | <0.0071 | U | | 0.0016 | J | | <0.0065 | U | | <0.0065 | U | | 0.034 | | | <0.0034 | U | | 0.00071 | J | | <0.0057 | U | | | | | | | | | | |
| | | VMP-7-5-111910 | 11/19/2010 | 0.0036 | J | | <0.0067 | U | | <0.0058 | U | | <0.0058 | U | | 0.14 | | | <0.003 | U | | <0.0052 | U | | <0.0052 | U | | | | | | | | | | |
| | | VMP-7-5-020711 | 2/7/2011 | 0.0039 | J | | 0.0018 | J | | <0.0063 | U | | <0.0063 | U | | 0.084 | | | <0.0033 | U | | 0.00082 | J | | <0.0056 | U | | | | | | | | | | |
| | | VMP-7-5-040711 | 4/7/2011 | 0.0032 | J | | <0.01 | U | | <0.0089 | U | | <0.0089 | U | | 0.01 | | | <0.0046 | U | | <0.0079 | U | | <0.0079 | U | | | | | | | | | | |
| | | VMP-7-5-080211 | 8/2/2011 | <0.97 | U | | <1 | U | | <0.89 | U | | <0.89 | U | | 710 | | | <0.46 | U | | <0.78 | U | | <0.78 | U | | | | | | | | | | |
| | | VMP-7-5-111011 | 11/10/2011 | <0.0046 | U | | <0.0048 | U | | <0.0042 | J | U | <0.0042 | U | | <0.004 | U | | <0.0022 | U | | <0.0037 | J | U | <0.0037 | U | | | | | | | | | | |
| | | VMP-7-5-111011-DUP | 11/10/2011 | <0.0043 | U | | <0.0045 | U | | 0.0008 | J | | <0.004 | U | | <0.0038 | U | | <0.002 | U | | 0.0011 | J | | <0.0035 | U | | | | | | | | | | |
| | | VMP-7-5-013112 | 1/31/2012 | <0.0047 | U | | <0.0049 | U | | <0.0043 | U | | <0.0043 | J | U | 0.00086 | J | | <0.0022 | U | | 0.0032 | J | | 0.001 | J | | | | | | | | | | |
| | | VMP-7-5-041212 | 4/12/2012 | <0.0051 | U | | 0.0014 | J | | 0.0022 | J | | <0.0047 | J | U | 0.0048 | | | <0.0024 | U | | 0.0097 | | | 0.0028 | J | | | | | | | | | | |
| | | VMP-7-5-073112 | 7/31/2012 | <0.013 | U | | <0.014 | U | | 0.0017 | J | | <0.012 | U | | 3 | | | <0.0063 | U | | 0.0098 | J | | 0.0031 | J | | | | | | | | | | |
| | | VMP-7-5-101012 | 10/10/2012 | <0.008 | U | | 0.0014 | J | | <0.0073 | U | | <0.0073 | U | | 0.0033 | J | | <0.0038 | U | | <0.0064 | U | | <0.0064 | U | | | | | | | | | | |
| | 13.5 ft | VMP-7-13.5-082610 | 8/26/2010 | <0.16 | U | | <0.16 | U | | <0.14 | U | | <0.14 | U | | 240 | E | J | <0.074 | U | | <0.12 | U | | <0.12 | U | | | | | | | | | | |
| | | VMP-7-13.5-111910 | 11/19/2010 | 1.9 | | J | <1.1 | U | | <0.99 | U | | <0.99 | U | | 450 | | | <0.52 | U | | <0.87 | U | | <0.87 | U | | | | | | | | | | |
| | | VMP-7-13.5-020711 | 2/7/2011 | 0.0023 | J | | <0.0069 | U | | <0.0061 | U | | <0.0061 | U | | 0.034 | | | <0.0032 | U | | <0.0054 | U | | <0.0054 | U | | | | | | | | | | |
| | | VMP-7-13.5-040711 | 4/7/2011 | 0.0038 | J | | <0.012 | U | | <0.011 | U | | <0.011 | U | | 0.017 | | | <0.0055 | U | | <0.0094 | U | | <0.0094 | U | | | | | | | | | | |
| | | VMP-7-13.5-080311 | 8/3/2011 | <1.3 | U | | <1.4 | U | | <1.2 | U | | <1.2 | U | | 610 | | | <0.62 | U | | <1 | U | | <1 | U | | | | | | | | | | |
| | | VMP-7-13.5-111011 | 11/10/2011 | <0.0042 | U | | <0.0044 | U | | 0.0052 | | | 0.0011 | J | | 2.9 | | | <0.002 | U | | 0.0058 | | | 0.00072 | J | | | | | | | | | | |
| | | VMP-7-13.5-013112 | 1/31/2012 | <0.06 | U | | <0.063 | U | | <0.22 | U | | <0.055 | U | | 33 | | J | <0.029 | U | | <0.049 | U | | <0.049 | U | | | | | | | | | | |
| | | VMP-7-13.5-013112-DUP | 1/31/2012 | <0.062 | U | | <0.064 | U | | <0.22 | U | | <0.056 | U | | 32 | | J | <0.029 | U | | <0.05 | U | | <0.05 | U | | | | | | | | | | |
| | | VMP-7-13.5-041212 | 4/12/2012 | <0.0049 | U | | 0.0013 | J | | 0.0018 | J | | <0.0045 | U | | 0.029 | | | <0.0023 | U | | 0.0058 | | | 0.0018 | J | | | | | | | | | | |
| | | VMP-7-13.5-041212-DUP | 4/12/2012 | <0.0052 | U | | 0.0011 | J | | 0.0016 | J | | <0.0047 | U | | 0.015 | | | <0.0025 | U | | 0.0058 | | | 0.002 | J | | | | | | | | | | |
| | | VMP-7-13.5-072012 | 7/20/2012 | <0.005 | U | | 0.0013 | J | | 0.0028 | J | | <0.0046 | U | | 0.0018 | J | | <0.0024 | U | | 0.0074 | | | 0.0019 | J | | | | | | | | | | |
| | | VMP-7-13.5-101012 | 10/10/2012 | <0.0074 | U | | 0.0014 | J | | <0.0068 | U | | <0.0068 | U | | 0.011 | | | <0.0035 | U | | <0.006 | U | | <0.006 | U | | | | | | | | | | |
| | | VMP-7-13.5-021313 | 2/13/2013 | <0.0074 | U | | 0.0013 | J | | <0.0068 | U | | <0.0068 | U | | 0.0007 | J | | <0.0035 | U | | <0.006 | U | | <0.006 | U | | | | | | | | | | |
| | 29.5 ft | VMP-7-29.5-083110 | 8/31/2010 | <2.2 | U | | <2.3 | U | | <2 | U | | <2 | U | | 1300 | | J | <1 | U | | 1.6 | J | J | <1.8 | U | | | | | | | | | | |
| | | VMP-7-29.5-111910 | 11/19/2010 | <3.3 | U | | <3.5 | U | | <3 | U | | <3 | U | | 1100 | | J | <1.6 | U | | 0.91 | J | J | <2.7 | U | | | | | | | | | | |
| | | VMP-7-29.5-020711 | 2/7/2011 | <3.5 | U | | <3.6 | U | | <3.2 | U | | <3.2 | U | | 1100 | | | <1.6 | U | | 1.8 | J | | <2.8 | U | | | | | | | | | | |
| | | VMP-7-29.5-040711 | 4/7/2011 | <0.84 | U | | <0.88 | U | | <0.77 | U | | <0.77 | U | | 550 | | J | <0.4 | U | | 0.77 | | J | <0.68 | U | | | | | | | | | | |
| | | VMP-7-29.5-080311 | 8/3/2011 | <2 | U | | <2.1 | U | | <1.8 | U | | <1.8 | U | | 950 | | | <0.94 | U | | 0.36 | J | | <1.6 | U | | | | | | | | | | |
| | | VMP-7-29.5-111111 | 11/11/2011 | <3.9 | U | | <4.1 | U | | 4.1 | | | 1.4 | J | | 720 | | | <1.8 | U | | 12 | | | 2.7 | J | | | | | | | | | | |
| | | VMP-7-29.5-020112 | 2/1/2012 | <0.78 | U | | <0.82 | U | | <2.9 | U | UJ | <0.72 | U | | 560 | | J | <0.37 | U | | <0.63 | U | | <0.63 | U | | | | | | | | | | |
| | | VMP-7-29.5-041312 | 4/13/2012 | <0.0049 | U | | 0.0011 | J | | 0.0072 | | | 0.0018 | J | | 0.71 | | | <0.0023 | U | | 0.0073 | | | 0.0038 | J | | | | | | | | | | |
| | | VMP-7-29.5-072012 | 7/20/2012 | <0.005 | U | | 0.0012 | J | | 0.0032 | J | | <0.0046 | U | | 0.031 | | | <0.0024 | U | | 0.0073 | | | 0.0026 | J | | | | | | | | | | |
| | | VMP-7-29.5-072012-Dup | 7/20/2012 | <0.005 | U | | 0.0013 | J | | 0.0035 | J | | 0.00098 | J | | 0.029 | | | <0.0024 | U | | 0.0081 | | | 0.0033 | J | | | | | | | | | | |
| | | VMP-7-29.5-101012 | 10/10/2012 | <0.0078 | U | | 0.0014 | J | | <0.0071 | U | | <0.0071 | U | | 0.013 | | | <0.0037 | U | | <0.0063 | U | | <0.0063 | U | | | | | | | | | | |
| | 38 ft | VMP-7-38-020711 | 2/7/2011 | <4.6 | U | | <4.9 | U | | <4.2 | U | | <4.2 | U | | 920 | | | <2.2 | U | | 1.1 | J | | <3.8 | U | | | | | | | | | | |
| | | VMP-7-38-040711 | 4/7/2011 | <1.2 | U | | <1.2 | U | | <1.1 | U | | <1.1 | U | | 720 | | J | <0.56 | U | | 0.42 | J | J | <0.96 | U | | | | | | | | | | |
| | | VMP-7-38-020112 | 2/1/2012 | <1.1 | U | | <1.2 | U | | <4.1 | U | UJ | <1 | U | | 630 | | J | <0.54 | U | | <0.91 | U | | <0.91 | U | | | | | | | | | | |
| | | VMP-7-38-042512 | 4/25/2012 | <0.0049 | U | | 0.0012 | J | | <0.0045 | J | U | <0.0045 | J | U | 0.32 | | J | <0.0023 | U | | 0.01 | | | 0.0032 | J | | | | | | | | | | |
| | | VMP-7-38-042512-Dup | 4/25/2012 | <0.0049 | J | U | 0.0015 | J | | <0.0045 | J | U | <0.0045 | J | U | 0.23 | | J | <0.0023 | U | | 0.009 | | | 0.0031 | J | | | | | | | | | | |
| | | VMP-7-38-101112 | 10/11/2012 | <0.0072 | U | | 0.0011 | J | | <0.0066 | U | | <0.0066 | U | | 0.011 | | | <0.0034 | U | | <0.0058 | U | | <0.0058 | U | | | | | | | | | | |
| VMP-8 | 5 ft | VMP-8-5-083010 | 8/30/2010 | 0.0027 | J | | 0.0013 | J | | 0.0015 | J | | <0.0066 | U | | 0.011 | | | <0.0034 | U | | 0.0014 | J | | <0.0058 | U | | | | | | | | | | |
| | | VMP-8-5-111810 | 11/17/2010 | <0.0063 | J | U | 0.0013 | J | | <0.0057 | J | U | <0.0057 | U | | 0.00032 | J | | <0.003 | U | | <0.005 | J | U | <0.005 | U | | | | | | | | | | |
| | | VMP-8-5-021011 | 2/10/2011 | <0.0066 | U | | <0.0069 | U | | <0.0061 | U | | <0.0061 | U | | 0.027 | | | <0.0032 | U | | <0.0054 | U | | <0.0054 | U | | | | | | | | | | |
| | | VMP-8-5-040711 | 4/7/2011 | 0.003 | J | | 0.0011 | J | | <0.0068 | U | | <0.0068 | U | | 0.003 | J | | <0.0035 | U | | 0.0018 | J | | <0.006 | U | | | | | | | | | | |
| | | VMP-8-5-072711 | 7/27/2011 | <0.008 | U | | <0.0083 | U | | 0.004 | J | | 0.0013 | J | | 0.011 | | | <0.0038 | U | | 0.0064 | | | 0.002 | J | | | | | | | | | | |
| | | VMP-8-5-110311 | 11/3/2011 | <0.0046 | U | | 0.0012 | J | | 0.00078 | J | | <0.0042 | U | | 0.0024 | J | | <0.0022 | U | | 0.0076 | | | 0.0015 | J | | | | | | | | | | |
| | | VMP-8-5-012312 | 1/23/2012 | <0.0057 | U | | 0.0014 | J | | <0.0052 | U | | <0.0052 | U | | 0.006 | | | <0.0027 | U | | 0.0013 | J | | <0.0046 | U | | | | | | | | | | |
| | | VMP-8-5-041012 | 4/10/2012 | 0.0012 | J | | <0.0054 | U | | 0.0015 | J | | <0.0047 | U | | 0.045 | | | <0.0024 | U | | 0.0026 | J | | 0.00069 | J | | | | | | | | | | |
| | | VMP-8-5-071312 | 7/13/2012 | <0.0043 | U | | <0.0045 | U | | <0.004 | J | U | <0.004 | U | | <0.0038 | U | | <0.002 | U | | <0.0035 | J | U | <0.0035 | U | | | | | | | | | | |
| | | VMP-8-5-073112 | 7/31/2012 | <0.0055 | U | | 0.0011 | J | | 0.0019 | J | | <0.0051 | U | | 0.11 | | | <0.0026 | U | | 0.012 | | | 0.0034 | J | | | | | | | | | | |
| | | VMP-8-5-100412 | 10/4/2012 | <0.0074 | U | | <0.0078 | U | | <0.0068 | J | U | <0.0068 | U | | <0.0064 | J | U | <0.0035 | U | | <0.006 | U | | <0.006 | U | | | | | | | | | | |
| | | VMP-8-5-100412-Dup | 10/4/2012 | <0.0071 | U | | <0.0074 | U | | <0.0065 | U | | <0.0065 | U | | <0.0062 | U | | <0.0034 | U | | <0.0057 | U | | <0.0057 | U | | | | | | | | | | |
| | | VMP-8-5-012413 | 1/24/2013 | <0.0072 | U | | 0.0014 | J | | <0.0066 | U | | <0.0066 | U | | 0.001 | J | | <0.0034 | U | | <0.0058 | U | | <0.0058 | U | | | | | | | | | | |
| | 9.5 ft | VMP-8-9.5 | 11/10/2009 | <0.006 | U | | <0.006 | U | | <0.005 | U | | <0.005 | U | | <0.005 | U | | <0.002 | U | | <0.004 | U | | <0.004 | U | | | | | | | | | | |
| | | VMP-8-9.5-083010 | 8/30/2010 | 0.0027 | J | | 0.0014 | J | | 0.00098 | J | | <0.0059 | U | | 0.0024 | J | | <0.0031 | U | | 0.0013 | J | | <0.0052 | U | | | | | | | | | | |
| | | VMP-8-9.5-083010-DUP | 8/30/2010 | 0.0019 | J | | 0.0017 | J | | 0.00079 | J | | <0.0061 | U | | 0.0016 | J | | <0.0032 | U | | <0.0054 | U | | <0.0054 | U | | | | | | | | | | |
| | | VMP-8-9.5-111810 | 11/17/2010 | <0.0065 | J | U | 0.0011 | J | | <0.0059 | U | | <0.0059 | U | | 0.0034 | J | | <0.0031 | U | | <0.0052 | U | | <0.0052 | U | | | | | | | | | | |
| | | VMP-8-9.5-021011 | 2/10/2011 | <0.0068 | U | | 0.0013 | J | | <0.0062 | U | | <0.0062 | U | | 0.0077 | | | <0.0032 | U | | <0.0055 | U | | <0.0055 | U | | | | | | | | | | |
| | | VMP-8-9.5-040711 | 4/7/2011 | 0.0036 | J | | <0.0078 | U | | <0.0068 | U | | <0.0068 | U | | 0.0028 | J | | <0.0035 | U | | 0.00063 | J | | <0.006 | U | | | | | | | | | | |
| | | VMP-8-9.5-072711 | 7/27/2011 | <0.0057 | U | | 0.0014 | J | | 0.0035 | J | | 0.0011 | J | | 0.0083 | | | <0.0027 | U | | 0.0079 | | | 0.0024 | J | | | | | | | | | | |
| | | VMP-8-9.5-110311 | 11/3/2011 | <0.0045 | U | | 0.0012 | J | | 0.0025 | J | | 0.00057 | J | | 0.0022 | J | | <0.0021 | U | | 0.012 | | | 0.0027 | J | | | | | | | | | | |
| | | VMP-8-9.5-012312 | 1/23/2012 | 0.027 | | | 0.0012 | J | | <0.005 | U | | <0.005 | U | | 0.0069 | | J | <0.0026 | U | | 0.0032 | J | | 0.001 | J | | | | | | | | | | |
| | | VMP-8-9.5-041012 | 4/10/2012 | 0.0014 | J | | <0.0054 | U | | <0.0047 | U | | <0.0047 | U | | 0.056 | | | <0.0024 | U | | 0.00097 | J | | <0.0041 | U | | | | | | | | | | |
| | | VMP-8-9.5-071312 | 7/13/2012 | <0.005 | U | | 0.0013 | J | | <0.0046 | U | | <0.0046 | U | | <0.0044 | U | | <0.0024 | U | | <0.0041 | U | | <0.0041 | U | | | | | | | | | | |
| | | VMP-8-9.5-071312-Dup | 7/13/2012 | <0.0048 | U | | 0.00099 | J | | <0.0044 | U | | <0.0044 | U | | <0.0042 | U | | <0.0023 | U | | <0.0039 | U | | <0.0039 | U | | | | | | | | | | |
| | | VMP-8-9.5-100412 | 10/4/2012 | <0.0081 | U | | 0.0015 | J | | <0.0074 | J | U | <0.0074 | U | | 0.075 | | | <0.0039 | U | | 0.0042 | J | | <0.0066 | U | | | | | | | | | | |
| | | VMP-8-9.5-012413 | 1/24/2013 | <0.0068 | U | | 0.0015 | J | | <0.0062 | U | | <0.0062 | U | | 0.0017 | J | | <0.0032 | U | | <0.0055 | U | | <0.0055 | U | | | | | | | | | | |
| | | VMP-8-9.5-012413-Dup | 1/24/2013 | <0.0072 | U | | 0.0012 | J | | <0.0066 | U | | <0.0066 | U | | 0.00094 | J | | <0.0034 | U | | <0.0058 | U | | <0.0058 | U | | | | | | | | | | |
| | 23.5 ft | VMP-8-23.5-083010 | 8/30/2010 | 0.002 | J | | 0.0017 | J | | <0.0065 | U | | <0.0065 | U | | 0.0073 | | | <0.0034 | U | | <0.0057 | U | | <0.0057 | U | | | | | | | | | | |
| | | VMP-8-23.5-111910 | 11/19/2010 | 0.0064 | J | | <0.0071 | U | | <0.0062 | U | | <0.0062 | U | | 0.0061 | | | <0.0032 | U | | 0.001 | J | | <0.0055 | U | | | | | | | | | | |
| | | VMP-8-23.5-021011 | 2/10/2011 | <0.0072 | U | | 0.0013 | J | | <0.0066 | U | | <0.0066 | U | | 0.018 | | | <0.0034 | U | | <0.0058 | U | | <0.0058 | U | | | | | | | | | | |
| | | VMP-8-23.5-040711 | 4/7/2011 | 0.003 | J | | 0.00098 | J | | <0.0062 | U | | <0.0062 | U | | 0.0023 | J | | <0.0032 | U | | 0.0012 | J | | <0.0055 | U | | | | | | | | | | |
| | | VMP-8-23.5-040711-DUP | 4/7/2011 | 0.006 | J | | <0.011 | U | | <0.0098 | U | | <0.0098 | U | | 0.0018 | J | | <0.0051 | U | | 0.001 | J | | <0.0087 | U | | | | | | | | | | |
| | | VMP-8-23.5-081011 | 8/10/2011 | <0.0071 | U | | 0.0014 | J | | 0.0024 | J | | <0.0065 | J | U | 0.031 | | | <0.0034 | U | | 0.0055 | J | | 0.0016 | J | | | | | | | | | | |
| | | VMP-8-23.5-110611 | 11/6/2011 | <0.0051 | U | | 0.0012 | J | | <0.0047 | U | | <0.0047 | U | | 0.001 | J | | <0.0024 | U | | 0.0026 | J | | 0.00092 | J | | | | | | | | | | |
| | | VMP-8-23.5-012312 | 1/23/2012 | <0.0057 | U | | 0.0014 | J | | <0.0052 | U | | <0.0052 | U | | 0.0037 | J | | <0.0027 | U | | 0.0033 | J | | 0.00092 | J | | | | | | | | | | |
| | | VMP-8-23.5-041012 | 4/10/2012 | <0.005 | U | | <0.0052 | U | | 0.00075 | J | | <0.0046 | U | | 0.066 | | | <0.0024 | U | | 0.0011 | J | | <0.0041 | U | | | | | | | | | | |
| | | VMP-8-23.5-071312 | 7/13/2012 | <0.0055 | U | | 0.0012 | J | | <0.0051 | U | | <0.0051 | U | | <0.0048 | U | | <0.0026 | U | | <0.0045 | U | | <0.0045 | U | | | | | | | | | | |
| | | VMP-8-23.5-100412 | 10/4/2012 | <0.0078 | U | | 0.0014 | J | | <0.0071 | U | | <0.0071 | U | | 0.069 | | | <0.0037 | U | | <0.0063 | U | | <0.0063 | U | | | | | | | | | | |
| | | VMP-8-23.5-012413 | 1/24/2013 | <0.0078 | U | | 0.0018 | J | | <0.0071 | U | | <0.0071 | U | | <0.0068 | U | | <0.0037 | U | | <0.0063 | U | | <0.0063 | U | | | | | | | | | | |

SEE LAST PAGE OF TABLE FOR NOTES

**TABLE 5**
**CUMULATIVE SUMMARY OF SOIL VAPOR ANALYTICAL DETECTIONS AND SCREENING RESULTS: VILLAGE - VOCS**

| Location | Depth | Sample ID | Sample Date | Trichloroethene | | | Trichlorofluoromethane | | | 1,2,4-Trimethylbenzene | | | 1,3,5-Trimethylbenzene | | | 2,2,4-Trimethylpentane | | | Vinyl chloride | | | m,p-Xylene | | | o-Xylenes | | | [3]Butane, 2,2-dimethyl- | | | [3]Butane, 2,3-dimethyl- | | | [3]Cyclobutane, ethyl- | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | 1.5 | | | 860 | | | | | | | | | | | | 0.29 | | | 130 | | | 120 | | | | | | | | | | | |
| | | | | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result (ppbV) | Lab Quals | URS Quals | Result (ppbV) | Lab Quals | URS Quals | Result (ppbV) | Lab Quals | URS Quals |
| VMP-9 | 5 ft | VMP-9-5-082610 | 8/26/2010 | <0.0061 | U | | <0.0064 | U | | <0.0056 | U | | <0.0056 | U | | 0.029 | | | <0.0029 | U | | 0.0013 | J | | <0.005 | U | | | | | | | | | | |
| | | VMP-9-5-111910 | 11/19/2010 | 0.0037 | J | | <0.0067 | U | | <0.0058 | U | | <0.0058 | U | | 0.0075 | | | <0.003 | U | | <0.0052 | U | | <0.0052 | U | | | | | | | | | | |
| | | VMP-9-5-020811 | 2/8/2011 | 0.0014 | J | | 0.0011 | J | | <0.0054 | U | | <0.0054 | U | | 0.002 | J | | <0.0028 | U | | <0.0048 | U | | <0.0048 | U | | | | | | | | | | |
| | | VMP-9-5-040611 | 4/6/2011 | 0.0077 | J | | <0.017 | U | | <0.015 | U | | <0.015 | U | | 0.022 | | | <0.0077 | U | | <0.013 | U | | <0.013 | U | | | | | | | | | | |
| | | VMP-9-5-080211 | 8/2/2011 | <0.32 | U | | <0.33 | U | | <0.29 | U | | <0.29 | U | | 150 | | | <0.15 | U | | <0.26 | U | | <0.26 | U | | | | | | | | | | |
| | | VMP-9-5-110411 | 11/4/2011 | <0.0047 | U | | <0.0049 | U | | 0.0016 | J | | <0.0043 | J | U | 0.38 | | | <0.0022 | U | | <0.0038 | J | U | <0.0038 | U | | | | | | | | | | |
| | | VMP-9-5-012612 | 1/26/2012 | 0.0017 | J | | 0.00055 | J | | <0.0037 | U | | <0.0037 | U | | 1.1 | | | <0.0019 | U | | 0.0018 | J | | 0.00064 | J | | | | | | | | | | |
| | | VMP-9-5-041112 | 4/11/2012 | <0.0048 | U | | <0.005 | U | | 0.0012 | J | | <0.0044 | U | | 0.087 | | | <0.0023 | U | | 0.0025 | J | | <0.0039 | U | | | | | | | | | | |
| | | VMP-9-5-071312 | 7/13/2012 | <0.0051 | U | | 0.0013 | J | | <0.0047 | U | | <0.0047 | U | | 0.0031 | J | | <0.0024 | U | | 0.0062 | | | <0.0041 | J | U | | | | | | | | | | |
| | | VMP-9-5-101012 | 10/10/2012 | <0.0078 | U | | 0.0014 | J | | <0.0071 | U | | <0.0071 | U | | 0.016 | | | <0.0037 | U | | <0.0063 | U | | <0.0063 | U | | | | | | | | | | |
| | | [4]VMP-9-5-012513 | 1/25/2013 | <0.0076 | U | UJ | 0.0016 | J | J | <0.0069 | U | UJ | <0.0069 | U | UJ | 0.0011 | J | J | <0.0036 | U | UJ | <0.0061 | U | UJ | <0.0061 | U | UJ | | | | | | | | | | |
| | | VMP-9-5-021513 | 2/15/2013 | <0.0074 | U | | 0.0014 | J | | 0.014 | J | J | <0.0068 | U | | 0.21 | | | <0.0035 | U | | 0.0015 | J | | <0.006 | U | | | | | | | | | | |
| | 11.5 ft | VMP-9-11.5-082610 | 8/26/2010 | <0.14 | U | | <0.14 | U | | <0.13 | U | | <0.13 | U | | 98 | | | <0.066 | U | | <0.11 | U | | <0.11 | U | | | | | | | | | | |
| | | VMP-9-11.5-111910 | 11/19/2010 | 0.37 | J | | <0.42 | U | | <0.37 | U | | <0.37 | U | | 150 | | | <0.19 | U | | <0.32 | U | | <0.32 | U | | | | | | | | | | |
| | | VMP-9-11.5-020911 | 2/9/2011 | <0.0072 | U | | <0.0076 | U | | <0.0066 | U | | <0.0066 | U | | 0.0073 | | | <0.0034 | U | | <0.0058 | U | | <0.0058 | U | | | | | | | | | | |
| | | VMP-9-11.5-020911-DUP | 2/9/2011 | <0.0056 | U | | <0.0059 | U | | <0.0051 | U | | <0.0051 | U | | 0.0074 | | | <0.0027 | U | | <0.0045 | U | | <0.0045 | U | | | | | | | | | | |
| | | VMP-9-11.5-040611 | 4/6/2011 | 0.011 | J | | <0.022 | U | | <0.019 | U | | <0.019 | U | | 0.0075 | J | | <0.01 | U | | <0.017 | U | | <0.017 | U | | | | | | | | | | |
| | | VMP-9-11.5-080211 | 8/2/2011 | <0.47 | U | | <0.49 | U | | <0.43 | U | | <0.43 | U | | 310 | | | <0.22 | U | | <0.38 | U | | <0.38 | U | | | | | | | | | | |
| | | VMP-9-11.5-110411 | 11/4/2011 | <0.0047 | U | | <0.0049 | U | | 0.0018 | J | | <0.0043 | J | U | 0.031 | | | <0.0022 | U | | <0.0038 | J | U | <0.0038 | U | | | | | | | | | | |
| | | VMP-9-11.5-012612 | 1/26/2012 | 0.0071 | | | <0.0044 | U | | <0.0038 | U | | <0.0038 | U | | 0.11 | | | <0.002 | U | | 0.0018 | J | | 0.00068 | J | | | | | | | | | | |
| | | VMP-9-11.5-041112 | 4/11/2012 | 0.0016 | J | | 0.0017 | J | | <0.0045 | U | | <0.0045 | U | | 0.075 | | | <0.0023 | U | | 0.0014 | J | | 0.00055 | J | | | | | | | | | | |
| | | VMP-9-11.5-071312 | 7/13/2012 | <0.0055 | U | | 0.0012 | J | | 0.0033 | J | | <0.0051 | J | U | <0.0048 | U | | <0.0026 | U | | 0.011 | | | 0.0037 | J | | | | | | | | | | |
| | | VMP-9-11.5-101012 | 10/10/2012 | <0.0074 | U | | 0.0016 | J | | <0.0068 | U | | <0.0068 | U | | 0.034 | | | <0.0035 | U | | 0.0016 | J | | <0.006 | U | | | | | | | | | | |
| | | VMP-9-11.5-012513 | 1/25/2013 | <0.0063 | U | | 0.0017 | J | | <0.0057 | U | | <0.0057 | U | | 0.0054 | | | <0.003 | U | | <0.005 | U | | <0.005 | U | | | | | | | | | | |
| | | VMP-9-11.5-012513-DUP | 1/25/2013 | <0.0068 | U | | 0.0015 | J | | <0.0062 | U | | <0.0062 | U | | 0.0083 | | | <0.0032 | U | | 0.0018 | J | | <0.0055 | J | U | | | | | | | | | | |
| | 25.5 ft | VMP-9-25.5-082610 | 8/26/2010 | <1.1 | U | | <1.1 | U | | 0.19 | J | | <0.99 | U | | 650 | | | <0.52 | U | | <0.87 | U | | <0.87 | U | | | | | | | | | | |
| | | VMP-9-25.5-082610-DUP | 8/26/2010 | <1.2 | U | | <1.2 | U | | 0.17 | J | | <1.1 | U | | 660 | | | <0.55 | U | | <0.94 | U | | <0.94 | U | | | | | | | | | | |
| | | VMP-9-25.5-111910 | 11/19/2010 | <1.2 | U | | <1.3 | U | | <1.1 | U | | <1.1 | U | | 550 | | | <0.59 | U | | <1 | U | | <1 | U | | | | | | | | | | |
| | | VMP-9-25.5-020911 | 2/9/2011 | <0.68 | U | | <0.71 | U | | 0.12 | J | | <0.62 | U | | 190 | | | <0.32 | U | | <0.55 | U | | <0.55 | U | | | | | | | | | | |
| | | VMP-9-25.5-040811 | 4/8/2011 | <0.34 | U | | <0.36 | U | | 0.056 | J | | <0.31 | U | | 98 | | | <0.16 | U | | 0.075 | J | | <0.28 | U | | | | | | | | | | |
| | | VMP-9-25.5-080211 | 8/2/2011 | <0.76 | U | | <0.79 | U | | <0.69 | U | | <0.69 | U | | 440 | | J | <0.36 | U | | <0.61 | U | | <0.61 | U | | | | | | | | | | |
| | | VMP-9-25.5-110711 | 11/7/2011 | 0.32 | J | | <0.7 | U | | <0.61 | U | | <0.61 | U | | 120 | | | <0.32 | U | | <0.54 | U | | <0.54 | U | | | | | | | | | | |
| | | VMP-9-25.5-110711-DUP | 11/7/2011 | 0.33 | J | | 0.12 | J | | <0.53 | U | | <0.53 | U | | 120 | | | <0.27 | U | | <0.47 | U | | <0.47 | U | | | | | | | | | | |
| | | VMP-9-25.5-012612 | 1/26/2012 | <0.17 | U | | <0.18 | U | | <0.63 | U | | <0.16 | U | | 76 | | J | <0.082 | U | | <0.14 | U | | <0.14 | U | | | | | | | | | | |
| | | VMP-9-25.5-041112 | 4/11/2012 | <0.0049 | U | | <0.0051 | U | | 0.0013 | J | | 0.0006 | J | | 0.046 | | | <0.0023 | U | | 0.0035 | J | | 0.0006 | J | | | | | | | | | | |
| | | VMP-9-25.5-071312 | 7/13/2012 | <0.0053 | U | | 0.0015 | J | | <0.0048 | J | U | <0.0048 | J | U | <0.0046 | J | U | <0.0025 | U | | 0.018 | | | 0.0064 | | | | | | | | | | | |
| | | VMP-9-25.5-071312-Dup | 7/13/2012 | <0.0051 | U | | 0.0016 | J | | <0.0047 | J | U | <0.0047 | J | U | <0.0045 | J | U | <0.0024 | U | | 0.017 | | | 0.006 | | | | | | | | | | | |
| | | VMP-9-25.5-101012 | 10/10/2012 | <0.0071 | U | | 0.0015 | J | | <0.0065 | U | | <0.0065 | U | | 0.0081 | | | <0.0034 | U | | <0.0057 | U | | <0.0057 | U | | | | | | | | | | |
| | | VMP-9-25.5-013013 | 1/30/2013 | <0.0076 | U | | 0.0016 | J | | <0.0069 | U | | <0.0069 | U | | 0.0038 | J | | <0.0036 | U | | <0.0061 | U | | <0.0061 | U | | | | | | | | | | |
| | 38.5 ft | VMP-9-38.5-020911 | 2/9/2011 | <1.1 | U | | <1.2 | U | | <1 | U | | <1 | U | | 380 | | | <0.53 | U | | <0.91 | U | | <0.91 | U | | | | | | | | | | |
| | | VMP-9-38.5-040811 | 4/8/2011 | <1.5 | U | | <1.6 | U | | <1.4 | U | | <1.4 | U | | 250 | | | <0.71 | U | | <1.2 | U | | <1.2 | U | | | | | | | | | | |
| | | VMP-9-38.5-012612 | 1/26/2012 | <0.22 | U | | <0.24 | U | | <0.82 | U | | <0.21 | U | | 120 | | J | <0.11 | U | | 0.019 | J | J | <0.18 | U | | | | | | | | | | |
| | | VMP-9-38.5-041112 | 4/11/2012 | 0.0017 | J | | <0.0045 | U | | <0.004 | U | | <0.004 | U | | 0.1 | | | <0.002 | U | | 0.0017 | J | | 0.00046 | J | | | | | | | | | | |
| | | VMP-9-38.5-071312 | 7/13/2012 | <0.0057 | J | U | 0.0014 | J | | 0.0035 | J | | <0.0052 | J | U | <0.005 | J | U | <0.0027 | U | | 0.014 | | | 0.005 | | | | | | | | | | | |
| | | VMP-9-38.5-101012 | 10/10/2012 | <0.021 | U | | <0.022 | U | | <0.019 | U | | <0.019 | U | | 4.8 | | | <0.01 | U | | <0.017 | U | | <0.017 | U | | | | | | | | | | |
| | | VMP-9-38.5-013013 | 1/30/2013 | <0.0076 | U | | 0.0016 | J | | <0.0069 | U | | <0.0069 | U | | 0.0051 | J | | <0.0036 | U | | <0.0061 | U | | <0.0061 | U | | | | | | | | | | |
| VMP-18 | 8.5 ft | VMP-18-8.5 | 6/18/2010 | <0.007 | U | | 0.0012 | J | | <0.007 | U | | <0.007 | U | | 0.0084 | | | <0.003 | U | | 0.0013 | J | | <0.006 | U | | | | | | | | | | |
| | | VMP-18-8.5-090710 | 9/7/2010 | <0.0069 | J | U | 0.0024 | J | | <0.0063 | J | U | <0.0063 | U | | 0.06 | | | <0.0033 | U | | 0.00095 | J | | <0.0056 | U | | | | | | | | | | |
| | | VMP-18-8.5-111910 | 11/19/2010 | 0.0022 | J | | <0.0061 | U | | <0.0053 | U | | <0.0053 | U | | 0.093 | | | <0.0028 | U | | <0.0047 | U | | <0.0047 | U | | | | | | | | | | |
| | | VMP-18-8.5-020711 | 2/7/2011 | 0.0026 | J | | 0.0011 | J | | 0.0042 | J | | 0.0019 | J | | 0.1 | | J | <0.003 | U | | 0.023 | | J | 0.0083 | | | | | | | | | | |
| | | VMP-18-8.5-020711-DUP | 2/7/2011 | 0.0019 | J | | 0.0011 | J | | 0.0023 | J | | <0.0056 | U | | 0.032 | | J | <0.0029 | U | | 0.0053 | | J | 0.0023 | J | | | | | | | | | | |
| | | VMP-18-8.5-040711 | 4/7/2011 | 0.0032 | J | | 0.001 | J | | <0.0063 | J | U | <0.0063 | U | | 0.022 | | | <0.0033 | U | | <0.0056 | J | U | <0.0056 | U | | | | | | | | | | |
| | | VMP-18-8.5-072811 | 7/28/2011 | <0.0074 | U | | <0.0078 | U | | 0.0063 | J | | <0.0068 | J | U | 0.0051 | J | | <0.0035 | U | | 0.007 | | | 0.0022 | J | | | | | | | | | | |
| | | VMP-18-8.5-110711 | 11/7/2011 | <0.0048 | U | | 0.00097 | J | | <0.0044 | J | U | <0.0044 | U | | <0.0042 | U | | <0.0023 | U | | <0.0039 | J | U | 0.00071 | J | | | | | | | | | | |
| | | VMP-18-8.5-012312 | 1/23/2012 | <0.0052 | U | | 0.00098 | J | | <0.0048 | U | | <0.0048 | U | | 0.0016 | J | | <0.0025 | U | | 0.0014 | J | | <0.0042 | U | | | | | | | | | | |
| | | VMP-18-8.5-041012 | 4/10/2012 | 0.0012 | J | | <0.0056 | U | | 0.0036 | J | | <0.0049 | J | U | 0.061 | | | <0.0026 | U | | 0.019 | | | 0.0053 | | | | | | | | | | | |
| | | VMP-18-8.5-071212 | 7/12/2012 | <0.0053 | U | | 0.001 | J | | 0.0041 | J | | <0.0048 | U | | 0.005 | | | <0.0025 | U | | 0.008 | | | 0.0025 | J | | | | | | | | | | |
| | | VMP-18-8.5-100912 | 10/9/2012 | <0.0071 | U | | 0.0013 | J | | <0.0065 | U | | <0.0065 | U | | 0.021 | | | <0.0034 | U | | <0.0057 | J | U | <0.0057 | U | | | | | | | | | | |
| | | VMP-18-8.5-012313 | 1/23/2013 | <0.0078 | U | | <0.0081 | U | | <0.0071 | U | | <0.0071 | U | | 0.013 | | | <0.0037 | U | | <0.0063 | U | | <0.0063 | U | | | | | | | | | | |
| VMP-19 | 5 ft | VMP-19-5 | 6/18/2010 | <0.007 | U | | 0.00091 | J | | <0.006 | U | | <0.006 | U | | 0.013 | | | <0.003 | U | | <0.005 | U | | <0.005 | U | | | | | | | | | | |
| | | VMP-19-5-090110 | 9/1/2010 | <0.0069 | U | | 0.0013 | J | | <0.0063 | J | U | <0.0063 | U | | 0.22 | J | J | <0.0033 | U | | 0.014 | | J | 0.0047 | J | J | | | | | | | | | | |
| | | VMP-19-5-111510 | 11/15/2010 | 0.0024 | J | | 0.0011 | J | | <0.0068 | U | | <0.0068 | U | | 0.0054 | J | | <0.0035 | U | | <0.006 | J | U | <0.006 | U | | | | | | | | | | |
| | | VMP-19-5-020411 | 2/4/2011 | 0.0032 | J | | 0.001 | J | | <0.0059 | U | | <0.0059 | U | | 0.046 | | | <0.0031 | U | | 0.00044 | J | | <0.0052 | U | | | | | | | | | | |
| | | VMP-19-5-040711 | 4/7/2011 | 0.0034 | J | | 0.00094 | J | | <0.0066 | U | | <0.0066 | U | | 0.054 | | | <0.0034 | U | | 0.0015 | J | | <0.0059 | U | | | | | | | | | | |
| | | VMP-19-5-080911 | 8/9/2011 | <0.008 | J | U | <0.0083 | J | U | <0.0073 | J | U | <0.0073 | J | U | 0.1 | | J | <0.0038 | U | | 0.011 | | | <0.0064 | J | U | | | | | | | | | | |
| | | VMP-19-5-080911-DUP | 8/9/2011 | <0.0076 | U | | <0.0079 | J | U | <0.0069 | J | U | <0.0069 | J | U | 0.078 | | J | <0.0036 | U | | 0.011 | | | <0.0061 | J | U | | | | | | | | | | |
| | | VMP-19-5-110811 | 11/8/2011 | <0.0053 | U | | <0.0055 | U | | <0.0048 | J | U | <0.0048 | U | | 0.0038 | J | | <0.0025 | U | | <0.0042 | J | U | <0.0042 | U | | | | | | | | | | |
| | | VMP-19-5-012612 | 1/26/2012 | <0.0046 | U | | <0.0048 | U | | <0.0042 | U | | <0.0042 | U | | 0.00079 | J | | <0.0022 | U | | 0.0079 | | | 0.0017 | J | | | | | | | | | | |
| | | VMP-19-5-041012 | 4/10/2012 | 0.0018 | J | | <0.0055 | U | | <0.0048 | J | U | <0.0048 | J | U | 0.026 | | | 0.00042 | J | | 0.0097 | | | 0.0025 | J | | | | | | | | | | |
| | | VMP-19-5-071112 | 7/11/2012 | <0.006 | U | | 0.0011 | J | | 0.0055 | | | <0.0055 | J | U | <0.0052 | U | | <0.0028 | U | | 0.0096 | | | 0.003 | J | | | | | | | | | | |
| | | VMP-19-5-100912 | 10/9/2012 | <0.008 | U | | <0.0083 | U | | <0.0073 | U | | <0.0073 | U | | 0.016 | | | <0.0038 | U | | <0.0064 | U | | <0.0064 | U | | | | | | | | | | |
| | | VMP-19-5-013113 | 1/31/2013 | <0.0069 | U | | 0.0012 | J | | 0.14 | | | 0.057 | | | 0.02 | | | <0.0033 | U | | 0.11 | | | 0.017 | | | | | | | | | | | |

SEE LAST PAGE OF TABLE FOR NOTES

**TABLE 5**
**CUMULATIVE SUMMARY OF SOIL VAPOR ANALYTICAL DETECTIONS AND SCREENING RESULTS: VILLAGE - VOCS**

| Location | Depth | Sample ID | Sample Date | Trichloroethene | | | Trichlorofluoromethane | | | 1,2,4-Trimethylbenzene | | | 1,3,5-Trimethylbenzene | | | 2,2,4-Trimethylpentane | | | Vinyl chloride | | | m,p-Xylene | | | o-Xylenes | | | $^{3}$Butane, 2,2-dimethyl- | | | $^{3}$Butane, 2,3-dimethyl- | | | $^{3}$Cyclobutane, ethyl- | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | 1.5 | | | 860 | | | | | | | | | | | | 0.29 | | | 130 | | | 120 | | | | | | | | | | | |
| | | | | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result (ppbV) | Lab Quals | URS Quals | Result (ppbV) | Lab Quals | URS Quals | Result (ppbV) | Lab Quals | URS Quals |
| VMP-20 | 5 ft | VMP-20-5-031411 | 3/14/2011 | <0.0065 | U | | 0.0015 | J | | 0.0039 | J | | 0.001 | J | | 1.4 | | | <0.0031 | U | | <0.0031 | U | | 0.023 | | | 0.0066 | | | | | | | | | | |
| | | VMP-20-5-041511 | 4/15/2011 | <0.071 | U | | <0.075 | U | | <0.065 | U | | <0.065 | U | | 4 | | | <0.034 | U | | <0.058 | U | | <0.058 | U | | <0.058 | U | | | | | | | | | |
| | | VMP-20-5-072511 | 7/25/2011 | <0.0076 | U | | 0.0017 | J | | <0.0069 | J | U | <0.0069 | U | | 0.0043 | J | | <0.0036 | U | | <0.0061 | J | U | <0.0061 | U | | | | | | | | | | | |
| | | VMP-20-5-110111 | 11/1/2011 | <0.0043 | U | | 0.0031 | J | | <0.004 | J | U | <0.004 | U | | 0.0017 | J | | <0.002 | U | | 0.0078 | | | 0.0016 | J | | | | | | | | | | | |
| | | VMP-20-5-012312 | 1/23/2012 | <0.021 | U | | 0.017 | J | | <0.019 | U | | <0.019 | U | | 2.2 | | | <0.0099 | U | | 0.0084 | J | | <0.017 | U | | | | | | | | | | | |
| | | VMP-20-5-041012 | 4/10/2012 | <0.0047 | U | | 0.0029 | J | | <0.0043 | U | | <0.0043 | U | | 0.051 | | | <0.0022 | U | | 0.003 | J | | 0.00064 | J | | | | | | | | | | | |
| | | VMP-20-5-071112 | 7/11/2012 | <0.0063 | U | | 0.004 | J | | <0.0057 | J | U | <0.0057 | U | | <0.0054 | U | | <0.003 | U | | <0.005 | U | | <0.005 | U | | | | | | | | | | | |
| | | VMP-20-5-073112 | 7/31/2012 | <0.0053 | U | | 0.017 | | | 0.0021 | J | | <0.0048 | U | | 0.0096 | | | <0.0025 | U | | 0.0077 | | | 0.0022 | J | | | | | | | | | | | |
| | | VMP-20-5-100412 | 10/4/2012 | <0.0078 | U | | 0.0021 | J | | <0.0071 | U | | <0.0071 | U | | 0.0031 | J | | <0.0037 | U | | <0.0063 | U | | <0.0063 | U | | | | | | | | | | | |
| | | VMP-20-5-020713 | 2/7/2013 | <0.0066 | U | | 0.012 | | | 0.06 | | | 0.0088 | | | 0.12 | | | <0.0032 | U | | 0.0042 | J | | <0.0054 | U | | | | | | | | | | | |
| | 10 ft | VMP-20-10-031411 | 3/14/2011 | <0.0065 | U | | 0.0011 | J | | 0.0046 | J | | 0.0024 | J | | 0.23 | | | <0.0031 | U | | 0.016 | | | 0.006 | | | | | | | | | | | |
| | | VMP-20-10-041511 | 4/15/2011 | <0.065 | U | | <0.068 | U | | <0.059 | U | | <0.059 | U | | 1.1 | | | <0.031 | U | | <0.052 | U | | <0.052 | U | | | | | | | | | | | |
| | | VMP-20-10-072511 | 7/25/2011 | <0.0069 | U | | <0.0072 | U | | 0.0025 | J | | <0.0063 | U | | <0.006 | U | | <0.0033 | U | | 0.0038 | J | | <0.0056 | U | | | | | | | | | | | |
| | | VMP-20-10-110111 | 11/1/2011 | <0.0046 | U | | 0.0069 | | | <0.0042 | U | | <0.0042 | U | | <0.004 | U | | <0.0022 | U | | <0.0037 | J | U | <0.0037 | U | | | | | | | | | | | |
| | | VMP-20-10-012312 | 1/23/2012 | <0.0048 | U | | 0.032 | | | <0.0044 | U | | <0.0044 | U | | 0.02 | | | <0.0023 | U | | 0.0032 | J | | 0.00075 | J | | | | | | | | | | | |
| | | VMP-20-10-041012 | 4/10/2012 | <0.0046 | U | | 0.025 | | | 0.0011 | J | | <0.0042 | U | | 0.094 | | | <0.0022 | U | | 0.004 | | | 0.0012 | J | | | | | | | | | | | |
| | | VMP-20-10-071112 | 7/11/2012 | <0.0053 | U | | 0.018 | | | <0.0048 | U | | <0.0048 | U | | <0.0046 | U | | <0.0025 | U | | <0.0042 | J | U | <0.0042 | U | | | | | | | | | | | |
| | | VMP-20-10-100412 | 10/4/2012 | <0.0072 | U | | 0.0048 | J | | <0.0066 | U | | <0.0066 | U | | <0.0063 | J | U | <0.0034 | U | | <0.0058 | U | | <0.0058 | U | | | | | | | | | | | |
| | | VMP-20-10-012213 | 1/22/2013 | <0.0066 | U | | 0.0033 | J | | <0.0061 | U | | <0.0061 | U | | 0.0049 | J | | <0.0032 | U | | <0.0054 | U | | <0.0054 | U | | | | | | | | | | | |
| | 25 ft | VMP-20-25-031411 | 3/14/2011 | <0.0064 | U | | <0.0067 | U | | <0.0059 | U | | <0.0059 | U | | 0.16 | | | <0.003 | U | | 0.0011 | J | | 0.00095 | J | | | | | | | | | | | |
| | | VMP-20-25-041511 | 4/15/2011 | <0.074 | U | | <0.078 | U | | <0.068 | U | | <0.068 | U | | 1 | | | <0.035 | U | | <0.06 | U | | <0.06 | U | | | | | | | | | | | |
| | | VMP-20-25-072611 | 7/26/2011 | <0.49 | U | | <0.52 | U | | <0.45 | U | | <0.45 | U | | 340 | | | <0.24 | U | | <0.4 | U | | <0.4 | U | | | | | | | | | | | |
| | | VMP-20-25-110511 | 11/5/2011 | <0.0045 | U | | 0.016 | | | 0.0013 | J | | <0.0041 | U | | 0.11 | | | <0.0021 | U | | 0.0023 | J | | 0.00094 | J | | | | | | | | | | | |
| | | VMP-20-25-012312 | 1/23/2012 | <0.005 | U | | 0.074 | | | <0.0046 | U | | <0.0046 | U | | 0.0029 | J | | <0.0024 | U | | 0.0014 | J | | <0.0041 | U | | | | | | | | | | | |
| | | VMP-20-25-041012 | 4/10/2012 | <0.0047 | U | | 0.086 | | | 0.00082 | J | | <0.0043 | U | | 0.011 | | | <0.0022 | U | | 0.0053 | | | 0.0015 | J | | | | | | | | | | | |
| | | VMP-20-25-041012-Dup | 4/10/2012 | <0.0048 | U | | 0.094 | | | 0.0012 | J | | <0.0043 | U | | 0.00099 | J | | <0.0023 | U | | 0.0044 | | | 0.0016 | J | | | | | | | | | | | |
| | | VMP-20-25-071112 | 7/11/2012 | <0.0054 | U | | 0.08 | | | <0.0049 | J | U | <0.0049 | U | | <0.0047 | U | | <0.0026 | U | | <0.0044 | J | U | <0.0044 | U | | | | | | | | | | | |
| | | VMP-20-25-100412 | 10/4/2012 | <0.008 | U | | 0.051 | | | <0.0073 | U | | <0.0073 | U | | <0.0069 | J | U | <0.0038 | U | | <0.0064 | U | | <0.0064 | U | | | | | | | | | | | |
| | | VMP-20-25-012213 | 1/22/2013 | <0.0066 | U | | 0.047 | | | <0.0061 | U | | <0.0061 | U | | <0.0058 | U | | <0.0032 | U | | <0.0054 | U | | <0.0054 | U | | | | | | | | | | | |
| | 39.5 ft | VMP-20-39.5-100412 | 10/4/2012 | <1.9 | U | | <2 | U | | <1.8 | U | | <1.8 | U | | 410 | | | <0.92 | U | | 0.46 | J | | <1.6 | U | | | | | | | | | | | |
| | | VMP-20-39.5-012313 | 1/23/2013 | <1.1 | U | | <1.2 | U | | <1 | U | | <1 | U | | 560 | | | <0.53 | U | | <0.9 | U | | <0.9 | U | | | | | | | | | | | |
| VMP-21 | 5 ft | VMP-21-5-020911 | 2/9/2011 | <2.5 | U | | <2.6 | U | | <2.3 | U | | <2.3 | U | | 830 | | | <1.2 | U | | <2 | U | | <2 | U | | | | | | | | | | | |
| | | VMP-21-5-020911-DUP | 2/9/2011 | <4.3 | U | | <4.5 | U | | <3.9 | U | | <3.9 | U | | 660 | | | <2 | U | | <3.4 | U | | <3.4 | U | | | | | | | | | | | |
| | | VMP-21-5-041311 | 4/13/2011 | <0.0071 | U | | 0.0012 | J | | 0.0014 | J | | <0.0065 | U | | 1.6 | | | <0.0034 | U | | 0.0035 | J | | <0.0057 | U | | | | | | | | | | | |
| | | VMP-21-5-072511 | 7/25/2011 | <0.0074 | U | | 0.0013 | J | | <0.0068 | J | U | <0.0068 | U | | 0.0035 | J | | <0.0035 | U | | 0.0045 | J | | 0.0014 | J | | | | | | | | | | | |
| | | VMP-21-5-110111 | 11/1/2011 | <0.0061 | U | | <0.0064 | U | | 0.13 | | | 0.033 | | | 0.016 | | | <0.0029 | U | | 0.044 | | | 0.018 | | | | | | | | | | | |
| | | VMP-21-5-012312 | 1/23/2012 | 0.0043 | J | | 0.0011 | J | | <0.0048 | U | | <0.0048 | U | | 0.0015 | J | | <0.0025 | U | | 0.0017 | J | | 0.00063 | J | | | | | | | | | | | |
| | | VMP-21-5-012312-DUP | 1/23/2012 | 0.0022 | J | | 0.0011 | J | | <0.0044 | U | | <0.0044 | U | | 0.0018 | J | | <0.0023 | U | | 0.0019 | J | | 0.0006 | J | | | | | | | | | | | |
| | | VMP-21-5-042412 | 4/24/2012 | <0.0098 | U | | <0.01 | U | | <0.009 | U | | <0.009 | U | | 1.3 | | | <0.0047 | U | | 0.0048 | J | | 0.0027 | J | | | | | | | | | | | |
| | | VMP-21-5-071012 | 7/10/2012 | <0.0057 | U | | 0.0016 | J | | 0.048 | | | 0.018 | | | <0.005 | U | | <0.0027 | U | | 0.12 | | | 0.022 | | | | | | | | | | | |
| | | VMP-21-5-100412 | 10/4/2012 | <0.0084 | U | | <0.0087 | U | | <0.0076 | U | | <0.0076 | U | | 0.0052 | J | | <0.004 | U | | 0.0029 | J | | <0.0068 | U | | | | | | | | | | | |
| | | VMP-21-5-020613 | 2/6/2013 | <0.0076 | U | | 0.0014 | J | | <0.0069 | U | | <0.0069 | U | | 0.0012 | J | | <0.0036 | U | | <0.0061 | U | | <0.0061 | U | | | | | | | | | | | |
| | 10 ft | VMP-21-10-021011 | 2/10/2011 | <2.2 | U | | <2.4 | U | | <2.1 | U | | <2.1 | U | | 480 | | | <1.1 | U | | <1.8 | U | | <1.8 | U | | | | | | | | | | | |
| | | VMP-21-10-041311 | 4/13/2011 | 0.17 | J | | <0.3 | U | | <0.26 | U | | <0.26 | U | | 42 | | | <0.14 | U | | <0.23 | U | | <0.23 | U | | | | | | | | | | | |
| | | VMP-21-10-072511 | 7/25/2011 | <0.016 | U | | 0.0029 | J | | <0.014 | J | U | <0.014 | U | | <0.014 | U | | <0.0075 | U | | 0.0033 | J | | <0.013 | U | | | | | | | | | | | |
| | | VMP-21-10-110111 | 11/1/2011 | <0.0046 | U | | 0.0014 | J | | <0.0042 | U | | <0.0042 | U | | <0.004 | U | | <0.0022 | U | | <0.0037 | J | U | <0.0037 | U | | | | | | | | | | | |
| | | VMP-21-10-012312 | 1/23/2012 | 0.0017 | J | | 0.0014 | J | | <0.0048 | U | | <0.0048 | U | | 0.0045 | | | <0.0025 | U | | 0.0014 | J | | <0.0042 | U | | | | | | | | | | | |
| | | VMP-21-10-040912 | 4/9/2012 | 0.0095 | | | <0.0049 | U | | 0.001 | J | | <0.0043 | U | | 0.79 | | | <0.0022 | U | | 0.007 | | | 0.003 | J | | | | | | | | | | | |
| | | VMP-21-10-071012 | 7/10/2012 | <0.0054 | U | | 0.0012 | J | | <0.0049 | J | U | <0.0049 | U | | <0.0047 | U | | <0.0026 | U | | <0.0044 | J | U | <0.0044 | U | | | | | | | | | | | |
| | | VMP-21-10-100412 | 10/4/2012 | <0.0076 | U | | <0.0079 | U | | <0.0069 | J | U | <0.0069 | U | | 0.017 | | | <0.0036 | U | | 0.0056 | J | | <0.0061 | J | U | | | | | | | | | | |
| | | VMP-21-10-020513 | 2/5/2013 | <0.0072 | U | | <0.0076 | J | U | <0.0066 | U | | <0.0066 | U | | 0.026 | | | <0.0034 | U | | <0.0058 | U | | <0.0058 | U | | | | | | | | | | | |
| | | VMP-21-10-020513-DUP | 2/5/2013 | <0.0068 | U | | <0.0071 | J | U | <0.0062 | U | | <0.0062 | U | | 0.03 | | | <0.0032 | U | | <0.0055 | U | | <0.0055 | U | | | | | | | | | | | |
| | 25 ft | VMP-21-25-021011 | 2/10/2011 | <6.3 | U | | <6.5 | U | | <5.7 | U | | <5.7 | U | | 1700 | | | <3 | U | | <5 | U | | <5 | U | | | | | | | | | | | |
| | | VMP-21-25-041411 | 4/14/2011 | <22 | U | | <23 | U | | <20 | U | | <20 | U | | 1200 | | | <10 | U | | <18 | U | | <18 | U | | | | | | | | | | | |
| | | VMP-21-25-041411-DUP | 4/14/2011 | <22 | U | | <23 | U | | <20 | U | | <20 | U | | 1200 | | | <10 | U | | <18 | U | | <18 | U | | | | | | | | | | | |
| | | VMP-21-25-072611 | 7/26/2011 | <7.1 | U | | <7.4 | U | | <6.5 | U | | <6.5 | U | | 1500 | | | <3.4 | U | | <5.7 | U | | <5.7 | U | | | | | | | | | | | |
| | | VMP-21-25-110511 | 11/5/2011 | <4.5 | U | | <4.7 | U | | <4.1 | U | | <4.1 | U | | 160 | | | <2.1 | U | | <3.6 | U | | <3.6 | U | | | | | | | | | | | |
| | | VMP-21-25-012412 | 1/24/2012 | <0.062 | U | | <0.065 | U | | <0.23 | U | | <0.057 | U | | 16 | | | <0.03 | U | | <0.05 | U | | <0.05 | U | | | | | | | | | | | |
| | | VMP-21-25-040912 | 4/9/2012 | 0.0021 | J | | <0.0051 | U | | <0.0045 | U | | <0.0045 | U | | 1.2 | | | <0.0023 | U | | 0.006 | | | 0.0024 | J | | | | | | | | | | | |
| | | VMP-21-25-071112 | 7/11/2012 | <0.0049 | U | | 0.0011 | J | | <0.0045 | J | U | <0.0045 | U | | 0.015 | | | <0.0023 | U | | <0.004 | J | U | <0.004 | U | | | | | | | | | | | |
| | | VMP-21-25-100412 | 10/4/2012 | <0.0078 | U | | 0.0016 | J | | <0.0071 | U | | <0.0071 | U | | 0.073 | | | <0.0037 | U | | 0.0028 | J | | <0.0063 | U | | | | | | | | | | | |
| | | VMP-21-25-020513 | 2/5/2013 | <0.0069 | U | | <0.0072 | J | U | <0.0063 | U | | <0.0063 | U | | 0.024 | | | <0.0033 | U | | <0.0056 | U | | <0.0056 | U | | | | | | | | | | | |
| | | VMP-21-25-020513-DUP | 2/5/2013 | <0.0072 | U | | <0.0076 | J | U | <0.0066 | U | | <0.0066 | U | | 0.014 | | | <0.0034 | U | | <0.0058 | U | | <0.0058 | U | | | | | | | | | | | |
| | 33 ft | VMP-21-33-021011 | 2/10/2011 | <6.3 | U | | <6.5 | U | | <5.7 | U | | <5.7 | U | | 1800 | | | <3 | U | | <5 | U | | <5 | U | | | | | | | | | | | |
| | | VMP-21-33-041411 | 4/14/2011 | <21 | U | | <22 | U | | <19 | U | | <19 | U | | 1300 | | | <10 | U | | 6.1 | J | | <17 | U | | | | | | | | | | | |
| | | VMP-21-33-110511 | 11/5/2011 | <1 | U | | <1.1 | U | | <0.94 | U | | <0.94 | U | | 69 | | | <0.49 | U | | <0.83 | U | | <0.83 | U | | | | | | | | | | | |
| | | VMP-21-33-012412 | 1/24/2012 | <0.15 | U | | <0.15 | U | | <0.54 | U | | <0.13 | U | | 54 | | J | <0.07 | U | | <0.12 | U | | <0.12 | U | | | | | | | | | | | |
| | | VMP-21-33-042412 | 4/24/2012 | <0.005 | J | U | <0.0052 | U | | <0.0046 | J | U | <0.0046 | U | | 0.58 | | | <0.0024 | U | | 0.0039 | J | | 0.0016 | J | | | | | | | | | | | |
| | | VMP-21-33-071112 | 7/11/2012 | <0.0053 | U | | <0.0055 | U | | <0.0048 | J | U | <0.0048 | U | | <0.0046 | U | | <0.0025 | U | | <0.0042 | J | U | <0.0042 | U | | | | | | | | | | | |
| | | VMP-21-33-100412 | 10/4/2012 | <0.0076 | U | | <0.0079 | U | | <0.0069 | J | U | <0.0069 | U | | 0.038 | | | <0.0036 | U | | 0.0052 | J | | <0.0061 | U | | | | | | | | | | | |
| | | VMP-21-33-020513 | 2/5/2013 | <0.0071 | U | | <0.0074 | U | | <0.0065 | U | | <0.0065 | U | | 0.01 | | | <0.0034 | U | | <0.0057 | U | | <0.0057 | U | | | | | | | | | | | |

SEE LAST PAGE OF TABLE FOR NOTES

**TABLE 5**
**CUMULATIVE SUMMARY OF SOIL VAPOR ANALYTICAL DETECTIONS AND SCREENING RESULTS: VILLAGE - VOCS**

| Location | Depth | Sample ID | Sample Date | Trichloroethene | | | Trichlorofluoromethane | | | 1,2,4-Trimethylbenzene | | | 1,3,5-Trimethylbenzene | | | 2,2,4-Trimethylpentane | | | Vinyl chloride | | | m,p-Xylene | | | o-Xylenes | | | $^{3}$Butane, 2,2-dimethyl- | | | $^{3}$Butane, 2,3-dimethyl- | | | $^{3}$Cyclobutane, ethyl- | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | 1.5 | | | 860 | | | | | | | | | | | | 0.29 | | | 130 | | | 120 | | | | | | | | | | | |
| | | | | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result (ppbV) | Lab Quals | URS Quals | Result (ppbV) | Lab Quals | URS Quals | Result (ppbV) | Lab Quals | URS Quals |
| VMP-22 | 5 ft | VMP-22-5-021111 | 2/11/2011 | <0.14 | U | | <0.14 | U | | <0.13 | U | | <0.13 | U | | 81 | | | <0.066 | U | | <0.11 | U | | <0.11 | U | | | | | | | | | | |
| | | VMP-22-5-041811 | 4/18/2011 | <0.068 | U | | <0.071 | U | | <0.062 | U | | <0.062 | U | | 0.22 | | | <0.032 | U | | <0.055 | U | | <0.055 | U | | | | | | | | | | |
| | | VMP-22-5-072611 | 7/26/2011 | <0.008 | U | | <0.0083 | U | | <0.0073 | J | U | <0.0073 | J | U | 0.13 | | | <0.0038 | U | | 0.0056 | J | | 0.002 | J | | | | | | | | | | |
| | | VMP-22-5-110111 | 11/1/2011 | <0.0045 | U | | <0.0047 | U | | <0.0041 | U | | <0.0041 | U | | 0.00041 | J | | <0.0021 | U | | <0.0036 | J | U | <0.0036 | U | | | | | | | | | | |
| | | VMP-22-5-012412 | 1/24/2012 | <0.0048 | U | | 0.0013 | J | J | <0.0044 | U | | <0.0044 | U | | 1.4 | | J | <0.0023 | U | | 0.0067 | | J | 0.0012 | J | J | | | | | | | | | |
| | | VMP-22-5-040912 | 4/9/2012 | <0.0053 | U | | <0.0055 | U | | <0.0048 | U | | <0.0048 | U | | 0.17 | | | <0.0025 | U | | 0.0016 | J | | <0.0042 | U | | | | | | | | | | |
| | | VMP-22-5-070912 | 7/9/2012 | <0.0058 | U | | 0.0013 | J | | <0.0053 | J | U | <0.0053 | U | | 0.0024 | J | | <0.0028 | U | | 0.0099 | | | 0.0028 | J | | | | | | | | | | |
| | | VMP-22-5-100312 | 10/3/2012 | <0.0068 | U | | <0.0071 | U | | <0.0062 | J | U | <0.0062 | U | | <0.0059 | J | U | <0.0032 | U | | <0.0055 | J | U | <0.0055 | U | | | | | | | | | | |
| | | VMP-22-5-100312-Dup | 10/3/2012 | <0.0062 | U | | 0.0012 | J | | <0.0056 | U | | <0.0056 | U | | 0.0084 | | | <0.0029 | U | | <0.005 | J | U | <0.005 | U | | | | | | | | | | |
| | | VMP-22-5-012413 | 1/24/2013 | <0.0069 | U | | 0.0015 | J | | <0.0063 | U | | <0.0063 | U | | 0.0081 | | | <0.0033 | U | | <0.0056 | U | | <0.0056 | U | | | | | | | | | | |
| | 10 ft | VMP-22-10-021111 | 2/11/2011 | <0.066 | U | | <0.068 | U | | <0.06 | U | | <0.06 | U | | 25 | | | <0.031 | U | | <0.053 | U | | <0.053 | U | | | | | | | | | | |
| | | VMP-22-10-041811 | 4/18/2011 | <0.07 | U | | <0.073 | U | | <0.064 | U | | <0.064 | U | | 0.016 | J | | <0.033 | U | | <0.057 | U | | <0.057 | U | | | | | | | | | | |
| | | VMP-22-10-072611 | 7/26/2011 | <0.0081 | U | | <0.0085 | U | | <0.0074 | J | U | <0.0074 | J | U | 0.022 | | J | <0.0039 | U | | 0.0039 | J | | <0.0066 | U | | | | | | | | | | |
| | | VMP-22-10-072611-DUP | 7/26/2011 | <0.0096 | U | | <0.01 | U | | <0.0088 | J | U | <0.0088 | U | | 0.051 | | J | <0.0046 | U | | 0.0034 | J | | <0.0077 | U | | | | | | | | | | |
| | | VMP-22-10-110211 | 11/2/2011 | <0.0046 | U | | <0.0048 | U | | <0.0042 | U | | <0.0042 | U | | <0.004 | U | | <0.0022 | U | | <0.0037 | J | U | <0.0037 | U | | | | | | | | | | |
| | | VMP-22-10-012412 | 1/24/2012 | 0.0015 | J | | 0.001 | J | | <0.0048 | U | | <0.0048 | U | | 0.0063 | | | <0.0025 | U | | 0.0018 | J | | 0.00084 | J | | | | | | | | | | |
| | | VMP-22-10-040912 | 4/9/2012 | <0.0052 | U | | 0.0018 | J | | <0.0047 | U | | <0.0047 | U | | 0.13 | | | <0.0025 | U | | 0.0023 | J | | <0.0042 | U | | | | | | | | | | |
| | | VMP-22-10-070912 | 7/9/2012 | <0.0058 | U | | 0.0014 | J | | <0.0053 | U | | <0.0053 | U | | <0.0051 | U | | <0.0028 | U | | <0.0047 | U | | <0.0047 | U | | | | | | | | | | |
| | | VMP-22-10-070912-Dup | 7/9/2012 | <0.0057 | U | | <0.006 | U | | <0.0052 | U | | <0.0052 | U | | <0.005 | U | | <0.0027 | U | | <0.0046 | J | U | <0.0046 | U | | | | | | | | | | |
| | | VMP-22-10-100312 | 10/3/2012 | <0.0065 | U | | 0.0014 | J | | <0.0059 | U | | <0.0059 | U | | 0.085 | | | <0.0031 | U | | <0.0052 | J | U | <0.0052 | U | | | | | | | | | | |
| | | VMP-22-10-012413 | 1/24/2013 | <0.0074 | U | | 0.0013 | J | | <0.0068 | U | | <0.0068 | U | | 0.003 | J | | <0.0035 | U | | <0.006 | U | | <0.006 | U | | | | | | | | | | |
| | 18 ft | VMP-22-18-021111 | 2/11/2011 | <1.1 | U | | <1.2 | U | | <1 | U | | <1 | U | | 480 | | | <0.54 | U | | <0.92 | U | | <0.92 | U | | | | | | | | | | |
| | | VMP-22-18-041811 | 4/18/2011 | <4.8 | U | | <5 | U | | <4.4 | U | | <4.4 | U | | 390 | | | <2.3 | U | | <3.9 | U | | <3.9 | U | | | | | | | | | | |
| | | VMP-22-18-072611 | 7/26/2011 | <2.5 | U | | <2.6 | U | | <2.3 | U | | <2.3 | U | | 340 | | | <1.2 | U | | <2 | U | | <2 | U | | | | | | | | | | |
| | | VMP-22-18-110511 | 11/5/2011 | <0.0049 | J | U | <0.0051 | U | | <0.0045 | U | | <0.0045 | U | | 0.028 | | | <0.0023 | U | | 0.0017 | J | | <0.004 | U | | | | | | | | | | |
| | | VMP-22-18-012412 | 1/24/2012 | <0.045 | U | | <0.047 | U | | <0.16 | U | | <0.041 | U | | 17 | | J | <0.021 | U | | <0.036 | U | | <0.036 | U | | | | | | | | | | |
| | | VMP-22-18-040912 | 4/9/2012 | <0.0054 | U | | <0.0056 | U | | <0.0049 | U | | <0.0049 | U | | 0.081 | | | <0.0026 | U | | 0.0015 | J | | <0.0044 | U | | | | | | | | | | |
| | | VMP-22-18-070912 | 7/9/2012 | <0.0057 | U | | <0.006 | U | | <0.0052 | U | | <0.0052 | U | | 0.0014 | J | | <0.0027 | U | | <0.0046 | J | U | <0.0046 | U | | | | | | | | | | |
| | | VMP-22-18-100412 | 10/4/2012 | <0.0078 | U | | 0.0013 | J | | <0.0071 | U | | <0.0071 | U | | 0.017 | | | <0.0037 | U | | <0.0063 | U | | <0.0063 | U | | | | | | | | | | |
| | | VMP-22-18-012413 | 1/24/2013 | <0.0074 | U | | 0.0014 | J | | <0.0068 | U | | <0.0068 | U | | 0.0021 | J | | <0.0035 | U | | <0.006 | U | | <0.006 | U | | | | | | | | | | |
| | 38 ft | VMP-22-38-041811 | 4/18/2011 | <15 | U | | <16 | U | | <14 | U | | <14 | U | | 710 | | | <7 | U | | <12 | U | | <12 | U | | | | | | | | | | |
| | | VMP-22-38-012512 | 1/25/2012 | <0.045 | U | | <0.047 | U | | <0.041 | U | | <0.041 | U | | 14 | | | <0.021 | U | | 0.0087 | J | | <0.036 | U | | | | | | | | | | |
| | | VMP-22-38-040912 | 4/9/2012 | 0.002 | J | | <0.0055 | U | | <0.0048 | U | | <0.0048 | U | | 0.14 | | | <0.0025 | U | | 0.0027 | J | | <0.0042 | U | | | | | | | | | | |
| | | VMP-22-38-070912 | 7/9/2012 | <0.0055 | U | | <0.0058 | U | | <0.0051 | U | | <0.0051 | U | | 0.0035 | J | | <0.0026 | U | | <0.0045 | J | U | <0.0045 | U | | | | | | | | | | |
| | | VMP-22-38-100412 | 10/4/2012 | <0.0081 | U | | <0.0085 | U | | <0.0074 | U | | <0.0074 | U | | 0.056 | | | <0.0039 | U | | <0.0066 | J | U | <0.0066 | U | | | | | | | | | | |
| | | VMP-22-38-012413 | 1/24/2013 | <0.0072 | U | | 0.0014 | J | | <0.0066 | U | | <0.0066 | U | | 0.0021 | J | | <0.0034 | U | | <0.0058 | U | | <0.0058 | U | | | | | | | | | | |
| VMP-23 | 5 ft | VMP-23-5-021511 | 2/15/2011 | 0.002 | J | | 0.0011 | J | | <0.0065 | U | | <0.0065 | U | | 0.0085 | | | <0.0034 | U | | 0.0046 | J | | 0.0013 | J | | | | | | | | | | |
| | | VMP-23-5-042111 | 4/21/2011 | <0.062 | U | | <0.064 | U | | <0.056 | U | | <0.056 | U | | 0.016 | J | | <0.029 | U | | 0.022 | J | | <0.05 | U | | | | | | | | | | |
| | | VMP-23-5-072711 | 7/27/2011 | <0.0071 | U | | 0.0017 | J | | 0.003 | J | | 0.00078 | J | | 0.047 | | | <0.0034 | U | | 0.0064 | | | 0.0014 | J | | | | | | | | | | |
| | | VMP-23-5-110211 | 11/2/2011 | <0.005 | U | | <0.0052 | U | | <0.0046 | U | | <0.0046 | U | | 0.00055 | J | | <0.0024 | U | | <0.0041 | J | U | <0.0041 | U | | | | | | | | | | |
| | | VMP-23-5-012512 | 1/25/2012 | 0.0014 | J | | <0.0044 | U | | 0.0012 | J | | 0.00097 | J | | 0.044 | | | <0.002 | U | | 0.0016 | J | | 0.00044 | J | | | | | | | | | | |
| | | VMP-23-5-040912 | 4/9/2012 | <0.0051 | U | | <0.0054 | U | | <0.0047 | U | | <0.0047 | U | | 0.022 | | | <0.0024 | U | | 0.015 | | | 0.0035 | J | | | | | | | | | | |
| | | VMP-23-5-070912 | 7/9/2012 | <0.0046 | U | | 0.0012 | J | | 0.003 | J | | 0.00091 | J | | 0.0028 | J | | <0.0022 | U | | <0.0037 | J | U | 0.00085 | J | | | | | | | | | | |
| | | VMP-23-5-100312 | 10/3/2012 | <0.0078 | U | | <0.0081 | U | | <0.0071 | U | | <0.0071 | U | | 0.0049 | J | | <0.0037 | U | | <0.0063 | U | | <0.0063 | U | | | | | | | | | | |
| | | VMP-23-5-012413 | 1/24/2013 | <0.0066 | U | | 0.0014 | J | | <0.0061 | U | | <0.0061 | U | | 0.011 | | | <0.0032 | U | | <0.0054 | U | | <0.0054 | U | | | | | | | | | | |
| | 10 ft | VMP-23-10-021511 | 2/15/2011 | <0.0073 | J | U | 0.0015 | J | | <0.0067 | J | U | <0.0067 | U | | 0.024 | | | <0.0035 | U | | 0.0086 | | | 0.0037 | J | | | | | | | | | | |
| | | VMP-23-10-042111 | 4/21/2011 | <0.074 | U | | <0.078 | U | | <0.068 | U | | <0.068 | U | | 1.4 | | | <0.035 | U | | 0.26 | | | 0.059 | | | | | | | | | | | |
| | | VMP-23-10-072711 | 7/27/2011 | <0.0068 | U | | <0.0071 | U | | <0.0062 | U | | <0.0062 | U | | <0.0059 | U | | <0.0032 | U | | <0.0055 | U | | <0.0055 | U | | | | | | | | | | |
| | | VMP-23-10-110211 | 11/2/2011 | <0.0049 | U | | <0.0051 | U | | <0.0045 | J | U | <0.0045 | J | U | 0.00047 | J | | <0.0023 | U | | 0.0042 | | | 0.0014 | J | | | | | | | | | | |
| | | VMP-23-10-012512 | 1/25/2012 | <0.0042 | U | | 0.0014 | J | | 0.0007 | J | | <0.0038 | U | | 0.88 | | | <0.002 | U | | 0.0045 | | | 0.0008 | J | | | | | | | | | | |
| | | VMP-23-10-040912 | 4/9/2012 | <0.0052 | U | | 0.0019 | J | | 0.002 | J | | <0.0048 | U | | <0.0046 | U | | <0.0025 | U | | 0.0057 | | | 0.002 | J | | | | | | | | | | |
| | | VMP-23-10-040912-Dup | 4/9/2012 | 0.0062 | | | 0.0032 | J | | <0.0048 | U | | <0.0048 | U | | 0.0059 | | | <0.0025 | U | | 0.0049 | | | 0.0016 | J | | | | | | | | | | |
| | | VMP-23-10-070912 | 7/9/2012 | <0.0042 | U | | 0.0013 | J | | 0.0019 | J | | 0.00078 | J | | <0.0036 | U | | <0.002 | U | | <0.0034 | J | U | 0.00074 | J | | | | | | | | | | |
| | | VMP-23-10-100312 | 10/3/2012 | <0.0084 | U | | <0.0087 | U | | <0.0076 | U | | <0.0076 | U | | 0.011 | | | <0.004 | U | | <0.0068 | U | | <0.0068 | U | | | | | | | | | | |
| | | VMP-23-10-012413 | 1/24/2013 | <0.0066 | U | | 0.0012 | J | | <0.0061 | U | | <0.0061 | U | | 0.0051 | J | | <0.0032 | U | | <0.0054 | U | | <0.0054 | U | | | | | | | | | | |
| | 25 ft | VMP-23-25-021511 | 2/15/2011 | 0.0024 | J | | <0.0071 | U | | <0.0062 | U | | <0.0062 | U | | 1.3 | | | <0.0032 | U | | 0.00067 | J | | <0.0055 | U | | | | | | | | | | |
| | | VMP-23-25-042111 | 4/21/2011 | <0.069 | U | | <0.072 | U | | <0.063 | U | | <0.063 | U | | 2.9 | | | <0.033 | U | | <0.056 | U | | <0.056 | U | | | | | | | | | | |
| | | VMP-23-25-072711 | 7/27/2011 | <0.0078 | U | | <0.0081 | U | | 0.004 | J | | 0.0024 | J | | 0.046 | | | <0.0037 | U | | 0.0065 | | | 0.002 | J | | | | | | | | | | |
| | | VMP-23-25-110511 | 11/5/2011 | <0.0049 | J | U | 0.001 | J | | <0.0045 | U | | <0.0045 | U | | 0.0022 | J | | <0.0023 | U | | 0.0018 | J | | 0.00062 | J | | | | | | | | | | |
| | | VMP-23-25-012512 | 1/25/2012 | <0.0044 | U | | 0.0022 | J | | <0.004 | U | | <0.004 | U | | 0.66 | | | <0.0021 | U | | 0.0032 | J | | <0.0036 | U | | | | | | | | | | |
| | | VMP-23-25-040912 | 4/9/2012 | 0.0061 | | | 0.0024 | J | | 0.0023 | J | | <0.0047 | U | | 0.0031 | J | | <0.0024 | U | | 0.013 | | | 0.0042 | | | | | | | | | | | |
| | | VMP-23-25-071012 | 7/10/2012 | <0.0066 | U | | 0.0022 | J | | <0.006 | U | | <0.006 | U | | 0.002 | J | | <0.0031 | U | | <0.0053 | J | U | 0.0014 | J | | | | | | | | | | |
| | | VMP-23-25-100312 | 10/3/2012 | <0.0081 | U | | 0.002 | J | | <0.0074 | U | | <0.0074 | U | | 0.016 | | | <0.0039 | U | | <0.0066 | U | | <0.0066 | U | | | | | | | | | | |
| | | VMP-23-25-012413 | 1/24/2013 | <0.0068 | U | | 0.0019 | J | | <0.0062 | U | | <0.0062 | U | | 0.0014 | J | | <0.0032 | U | | <0.0055 | U | | <0.0055 | U | | | | | | | | | | |
| | 40 ft | VMP-23-40-071012 | 7/10/2012 | <0.0055 | U | | <0.0058 | U | | 0.0021 | J | | <0.0051 | U | | <0.0048 | U | | <0.0026 | U | | <0.0045 | J | U | 0.00092 | J | | | | | | | | | | |
| | | VMP-23-40-100312 | 10/3/2012 | <0.0076 | U | | 0.003 | J | | <0.0069 | U | | <0.0069 | U | | 0.027 | | | <0.0036 | U | | <0.0061 | J | U | <0.0061 | U | | | | | | | | | | |
| | | VMP-23-40-012413 | 1/24/2013 | <0.0069 | U | | 0.0027 | J | | <0.0063 | U | | <0.0063 | U | | 0.0082 | | | <0.0033 | U | | <0.0056 | U | | <0.0056 | U | | | | | | | | | | |

SEE LAST PAGE OF TABLE FOR NOTES

**TABLE 5**
**CUMULATIVE SUMMARY OF SOIL VAPOR ANALYTICAL DETECTIONS AND SCREENING RESULTS: VILLAGE - VOCS**

| Location | Depth | Sample ID | Sample Date | Trichloroethene | | | Trichlorofluoromethane | | | 1,2,4-Trimethylbenzene | | | 1,3,5-Trimethylbenzene | | | 2,2,4-Trimethylpentane | | | Vinyl chloride | | | m,p-Xylene | | | o-Xylenes | | | $^3$Butane, 2,2-dimethyl- | | | $^3$Butane, 2,3-dimethyl- | | | $^3$Cyclobutane, ethyl- | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | 1.5 | | | 860 | | | | | | | | | | | | 0.29 | | | 130 | | | 120 | | | | | | | | | | | | |
| | | | | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result (ppbV) | Lab Quals | URS Quals | Result (ppbV) | Lab Quals | URS Quals | Result (ppbV) | Lab Quals | URS Quals |
| VMP-24 | 5 ft | VMP-24-5-021611 | 2/16/2011 | <0.0076 | U | | <0.0079 | U | | <0.0069 | J | U | <0.0069 | J | U | 0.011 | | | <0.0036 | U | | <0.0061 | J | U | <0.0061 | J | U | | | | | | | | | | |
| | | VMP-24-5-040811 | 4/8/2011 | <0.081 | U | | <0.084 | U | | <0.074 | U | | <0.074 | U | | 0.48 | | | <0.038 | U | | <0.065 | U | | <0.065 | U | | | | | | | | | | |
| | | VMP-24-5-072811 | 7/28/2011 | <0.0076 | U | | 0.0016 | J | | 0.0052 | J | | 0.0019 | J | | 0.012 | | | <0.0036 | U | | 0.0099 | | | 0.004 | J | | | | | | | | | | |
| | | VMP-24-5-110211 | 11/2/2011 | <0.005 | U | | 0.0016 | J | | <0.0046 | J | U | <0.0046 | J | U | 0.0017 | J | | <0.0024 | U | | 0.0031 | J | | <0.0041 | U | | | | | | | | | | |
| | | VMP-24-5-110211-DUP | 11/2/2011 | <0.007 | U | | <0.0073 | U | | 0.0073 | | | <0.0064 | J | U | 0.0083 | | | <0.0033 | U | | 0.0046 | J | | 0.0026 | J | | | | | | | | | | |
| | | VMP-24-5-012512 | 1/25/2012 | 0.00084 | J | | 0.0014 | J | | <0.004 | U | | <0.004 | U | | <0.0038 | U | | <0.002 | U | | 0.0062 | | | 0.001 | J | | | | | | | | | | |
| | | VMP-24-5-040912 | 4/9/2012 | 0.0027 | J | | 0.0018 | J | | 0.017 | | | 0.0048 | | | 0.013 | | | <0.0024 | U | | 0.023 | | | 0.0096 | | | | | | | | | | | |
| | | VMP-24-5-071212 | 7/12/2012 | <0.0049 | U | | 0.0013 | J | | 0.0087 | | | 0.0022 | J | | 0.012 | | | <0.0023 | U | | 0.0078 | | | 0.0029 | J | | | | | | | | | | |
| | | VMP-24-5-101912 | 10/19/2012 | <0.0076 | U | | <0.008 | U | | <0.007 | U | | <0.007 | U | | 0.0096 | | | <0.0036 | U | | <0.0061 | J | U | <0.0061 | U | | | | | | | | | | |
| | | VMP-24-5-012313 | 1/23/2013 | <0.0068 | U | | 0.0014 | J | | <0.0062 | U | | <0.0062 | U | | 0.019 | | | <0.0032 | U | | <0.0055 | U | | <0.0055 | U | | | | | | | | | | |
| | 10 ft | VMP-24-10-021711 | 2/17/2011 | <0.0072 | U | | 0.0019 | J | | <0.0066 | J | U | <0.0066 | U | | 1.2 | | | <0.0034 | U | | <0.0058 | J | U | <0.0058 | U | | | | | | | | | | |
| | | VMP-24-10-041111 | 4/11/2011 | 0.0037 | J | | <0.014 | U | | <0.012 | U | | <0.012 | U | | 0.12 | | | <0.0064 | U | | <0.011 | J | U | <0.011 | U | | | | | | | | | | |
| | | VMP-24-10-072811 | 7/28/2011 | <0.0074 | U | | 0.0027 | J | | 0.0033 | J | | 0.0014 | J | | 0.002 | J | | <0.0035 | U | | 0.0062 | | | 0.0015 | J | | | | | | | | | | |
| | | VMP-24-10-110211 | 11/2/2011 | <0.0044 | U | | 0.0017 | J | | <0.004 | J | U | <0.004 | U | | 0.00052 | J | | <0.0021 | U | | <0.0036 | J | U | <0.0036 | U | | | | | | | | | | |
| | | VMP-24-10-012512 | 1/25/2012 | 0.00087 | J | | 0.0016 | J | | <0.0038 | U | | <0.0038 | U | | 0.0015 | J | | <0.002 | U | | 0.0078 | | | 0.0021 | J | | | | | | | | | | |
| | | VMP-24-10-041012 | 4/10/2012 | <0.0049 | U | | 0.0019 | J | | <0.0045 | U | | <0.0045 | U | | 0.076 | | | <0.0023 | U | | 0.0026 | J | | <0.004 | U | | | | | | | | | | |
| | | VMP-24-10-071212 | 7/12/2012 | <0.0057 | U | | 0.0014 | J | | 0.0027 | J | | <0.0052 | U | | <0.005 | U | | <0.0027 | U | | 0.0073 | | | 0.0021 | J | | | | | | | | | | |
| | | VMP-24-10-100912 | 10/9/2012 | <0.0071 | U | | 0.0014 | J | | <0.0065 | U | | <0.0065 | U | | 0.0021 | J | | <0.0034 | U | | <0.0057 | J | U | <0.0057 | U | | | | | | | | | | |
| | | VMP-24-10-012313 | 1/23/2013 | <0.0074 | U | | 0.0018 | J | | <0.0068 | U | | <0.0068 | U | | 0.01 | | | <0.0035 | U | | <0.006 | U | | <0.006 | U | | | | | | | | | | |
| | 22 ft | VMP-24-22-021711 | 2/17/2011 | <0.0072 | U | | 0.0018 | J | | <0.0066 | J | U | <0.0066 | U | | 0.54 | | | <0.0034 | U | | 0.0084 | | | 0.003 | J | | | | | | | | | | |
| | | VMP-24-22-041111 | 4/11/2011 | <0.0068 | J | U | 0.0022 | J | | <0.0062 | U | | <0.0062 | U | | 0.00094 | J | | <0.0032 | U | | <0.0055 | U | | <0.0055 | U | | | | | | | | | | |
| | | VMP-24-22-072811 | 7/28/2011 | <0.0068 | U | | 0.0019 | J | | 0.0026 | J | | 0.0011 | J | | 0.00081 | J | | <0.0032 | U | | 0.0041 | J | | 0.0014 | J | | | | | | | | | | |
| | | VMP-24-22-072811-Dup | 7/28/2011 | <0.0078 | U | | 0.002 | J | | 0.0027 | J | | 0.00076 | J | | 0.0014 | J | | <0.0037 | U | | 0.0039 | J | | 0.0012 | J | | | | | | | | | | |
| | | VMP-24-22-110611 | 11/6/2011 | <0.0047 | J | U | 0.0015 | J | | <0.0043 | U | | <0.0043 | U | | 0.01 | | | <0.0022 | U | | 0.0022 | J | | 0.00069 | J | | | | | | | | | | |
| | | VMP-24-22-012512 | 1/25/2012 | <0.0044 | U | | 0.0022 | J | | <0.004 | U | | <0.004 | U | | <0.0038 | U | | <0.0021 | U | | 0.0011 | J | | <0.0036 | U | | | | | | | | | | |
| | | VMP-24-22-041012 | 4/10/2012 | <0.0048 | U | | 0.002 | J | | 0.0021 | J | | <0.0044 | U | | 0.051 | | | <0.0023 | U | | 0.0031 | J | | <0.0039 | U | | | | | | | | | | |
| | | VMP-24-22-071212 | 7/12/2012 | <0.0058 | U | | <0.0061 | U | | 0.0036 | J | | <0.0053 | U | | <0.0051 | U | | <0.0028 | U | | 0.0054 | | | 0.0017 | J | | | | | | | | | | |
| | | VMP-24-22-100912 | 10/9/2012 | <0.0072 | U | | 0.0015 | J | | <0.0066 | U | | <0.0066 | U | | 0.0034 | J | | <0.0034 | U | | <0.0058 | U | | <0.0058 | U | | | | | | | | | | |
| | | VMP-24-22-012313 | 1/23/2013 | <0.0076 | U | | 0.0017 | J | | <0.0069 | U | | <0.0069 | U | | 0.01 | | | <0.0036 | U | | <0.0061 | U | | <0.0061 | U | | | | | | | | | | |
| | 34 ft | VMP-24-34-021711 | 2/17/2011 | <0.0072 | U | | 0.0022 | J | | <0.0066 | U | | <0.0066 | U | | 0.024 | | | <0.0034 | U | | <0.0058 | U | | <0.0058 | U | | | | | | | | | | |
| | | VMP-24-34-041111 | 4/11/2011 | 0.003 | J | | 0.0021 | J | | <0.0059 | U | | <0.0059 | U | | 0.0012 | J | | <0.0031 | U | | <0.0052 | U | | <0.0052 | U | | | | | | | | | | |
| | | VMP-24-34-072811 | 7/28/2011 | <0.0057 | U | | 0.0016 | J | | 0.0025 | J | | 0.0008 | J | | 0.0035 | J | | <0.0027 | U | | 0.004 | J | | 0.0016 | J | | | | | | | | | | |
| | | VMP-24-34-110611 | 11/6/2011 | <0.0036 | J | U | 0.0016 | J | | <0.0033 | U | | 0.00036 | J | | 0.0088 | | | <0.0017 | U | | 0.0028 | J | | 0.0012 | J | | | | | | | | | | |
| | | VMP-24-34-012512 | 1/25/2012 | 0.0014 | J | | 0.0027 | J | | <0.0041 | U | | <0.0041 | U | | <0.0039 | U | | <0.0021 | U | | 0.0013 | J | | 0.00053 | J | | | | | | | | | | |
| | | VMP-24-34-041012 | 4/10/2012 | 0.0076 | | | <0.0052 | U | | <0.0046 | U | | <0.0046 | U | | 0.053 | | | <0.0024 | U | | 0.0053 | | | 0.0018 | J | | | | | | | | | | |
| | | VMP-24-34-071212 | 7/12/2012 | <0.0048 | U | | 0.0014 | J | | 0.0053 | | | 0.00088 | J | | <0.0042 | U | | <0.0023 | U | | 0.0067 | | | 0.0021 | J | | | | | | | | | | |
| | | VMP-24-34-100912 | 10/9/2012 | <0.0074 | U | | 0.0017 | J | | <0.0068 | U | | <0.0068 | U | | 0.042 | | | <0.0035 | U | | <0.006 | U | | <0.006 | U | | | | | | | | | | |
| | | VMP-24-34-012313 | 1/23/2013 | <0.0078 | U | | 0.0018 | J | | <0.0071 | U | | <0.0071 | U | | 0.0081 | | | <0.0037 | U | | <0.0063 | U | | <0.0063 | U | | | | | | | | | | |
| VMP-31 | 5 ft | VMP-31-5-042512 | 4/25/2012 | <0.0051 | U | | 0.0014 | J | | <0.0047 | J | U | <0.0047 | J | U | 0.00098 | J | | <0.0024 | U | | 0.011 | | | 0.0035 | J | | | | | | | | | | |
| | | VMP-31-5-072012 | 7/20/2012 | <0.0051 | U | | 0.0011 | J | | 0.00088 | J | | <0.0047 | U | | <0.0045 | U | | <0.0024 | U | | 0.0017 | J | | <0.0041 | U | | | | | | | | | | |
| | | VMP-31-5-102612 | 10/26/2012 | <0.0074 | U | | <0.0078 | U | | 0.002 | J | | <0.0068 | U | | 0.093 | | | <0.0035 | U | | 0.003 | J | | <0.006 | U | | | | | | | | | | |
| | | VMP-31-5-021113 | 2/11/2013 | <0.0069 | U | | 0.0013 | J | | 0.014 | | | 0.0053 | J | | 0.013 | | | <0.0033 | U | | 0.033 | | | 0.015 | | | | | | | | | | | |
| | 10 ft | VMP-31-10-042512 | 4/25/2012 | <0.0068 | U | | 0.0012 | J | | <0.0063 | J | U | <0.0063 | J | U | 0.029 | | | <0.0032 | U | | 0.007 | | | 0.0031 | J | | | | | | | | | | |
| | | VMP-31-10-072612 | 7/26/2012 | <0.0052 | U | | 0.0012 | J | | 0.0028 | J | | 0.0012 | J | | <0.0046 | U | | <0.0025 | U | | 0.011 | | | 0.0033 | J | | | | | | | | | | |
| | | VMP-31-10-102612 | 10/26/2012 | <0.008 | U | | <0.0083 | U | | 0.0021 | J | | <0.0073 | U | | 0.095 | | | <0.0038 | U | | 0.0026 | J | | <0.0064 | U | | | | | | | | | | |
| | | VMP-31-10-021313 | 2/13/2013 | <0.0076 | U | | <0.0079 | U | | 0.008 | J | J | 0.0036 | J | | 0.05 | | | <0.0036 | U | | 0.041 | | | 0.016 | | | | | | | | | | | |
| | 20 ft | VMP-31-20-101912 | 10/19/2012 | <7.4 | U | | <7.8 | U | | <6.8 | U | | <6.8 | U | | 960 | | | <3.5 | U | | 0.69 | J | | <6 | U | | | | | | | | | | |
| | | VMP-31-20-021113 | 2/11/2013 | <0.1 | U | | <0.11 | U | | <0.097 | U | | <0.097 | U | | 87 | | | <0.05 | U | | <0.086 | U | | <0.086 | U | | | | | | | | | | |
| | 30 ft | VMP-31-30-042512 | 4/25/2012 | <2.6 | U | | <2.8 | U | | 0.42 | J | | <2.4 | U | | 220 | | | <1.2 | U | | 2.6 | | | <2.1 | U | | | | | | | | | | |
| | | VMP-31-30-042512-Dup | 4/25/2012 | <2.6 | U | | <2.8 | U | | 0.44 | J | | <2.4 | U | | 240 | | | <1.2 | U | | 2.8 | | | <2.1 | U | | | | | | | | | | |
| | | VMP-31-30-072012 | 7/20/2012 | <0.51 | U | | <0.54 | U | | <0.47 | U | | <0.47 | U | | 17 | | | <0.24 | U | | <0.41 | U | | <0.41 | U | | | | | | | | | | |
| | | VMP-31-30-101912 | 10/19/2012 | <0.46 | U | | <0.48 | U | | <0.42 | U | | <0.42 | U | | 17 | | | <0.22 | U | | 0.087 | J | | <0.37 | U | | | | | | | | | | |
| | | VMP-31-30-021113 | 2/11/2013 | <7.6 | U | | <7.9 | U | | <6.9 | U | | <6.9 | U | | 400 | | | <3.6 | U | | 2.1 | J | | 7.2 | | | | | | | | | | | |
| VMP-32 | 5 ft | VMP-32-5-042512 | 4/25/2012 | <0.005 | U | | 0.0012 | J | | <0.0046 | J | U | <0.0046 | J | U | 0.0036 | J | | <0.0024 | U | | 0.0069 | | | 0.0031 | J | | | | | | | | | | |
| | | VMP-32-5-072012 | 7/20/2012 | <0.0045 | U | | 0.0011 | J | | 0.0022 | J | | 0.00095 | J | | 0.023 | | | <0.0021 | U | | 0.0035 | J | | 0.0016 | J | | | | | | | | | | |
| | | VMP-32-5-101812 | 10/18/2012 | <0.0086 | U | | <0.009 | U | | 0.0013 | J | J | <0.0078 | U | | 0.22 | | | <0.0041 | U | | 0.0027 | J | | <0.0069 | U | | | | | | | | | | |
| | | VMP-32-5-020513 | 2/5/2013 | <0.0068 | U | | <0.0071 | J | U | <0.0062 | J | U | <0.0062 | U | | 0.0086 | | | <0.0032 | U | | <0.0055 | U | | <0.0055 | U | | | | | | | | | | |
| | 10 ft | VMP-32-10-041612 | 4/16/2012 | <0.0046 | U | | 0.0015 | J | | <0.0042 | U | | <0.0042 | U | | 0.0082 | | | <0.0022 | U | | 0.0042 | | | <0.0037 | U | | | | | | | | | | |
| | | VMP-32-10-072012 | 7/20/2012 | <0.0053 | U | | 0.0015 | J | | 0.0015 | J | | <0.0048 | U | | 0.016 | | | <0.0025 | U | | 0.0024 | J | | 0.0011 | J | | | | | | | | | | |
| | | VMP-32-10-101812 | 10/18/2012 | <0.008 | U | | <0.0083 | U | | <0.0073 | U | UJ | <0.0073 | U | | 0.093 | | | <0.0038 | U | | 0.0018 | J | | <0.0064 | U | | | | | | | | | | |
| | | VMP-32-10-020513 | 2/5/2013 | <0.0068 | U | | <0.0071 | J | U | <0.0062 | U | | <0.0062 | U | | 0.0084 | | | <0.0032 | U | | <0.0055 | U | | <0.0055 | U | | | | | | | | | | |
| | 20 ft | VMP-32-20-041612 | 4/16/2012 | <0.1 | U | | <0.11 | U | | <0.096 | U | | <0.096 | U | | 24 | | | <0.05 | U | | 0.046 | J | | <0.085 | U | | | | | | | | | | |
| | | VMP-32-20-072012 | 7/20/2012 | <0.0051 | U | | 0.0012 | J | | 0.0011 | J | | <0.0047 | U | | 0.0026 | J | | <0.0024 | U | | 0.0014 | J | | <0.0041 | U | | | | | | | | | | |
| | | VMP-32-20-101812 | 10/18/2012 | <0.0074 | U | | 0.0015 | J | | <0.0068 | U | UJ | <0.0068 | U | | 0.14 | | | <0.0035 | U | | 0.0016 | J | | <0.006 | U | | | | | | | | | | |
| | | VMP-32-20-020513 | 2/5/2013 | <0.0076 | U | | <0.0079 | J | U | <0.0069 | U | | <0.0069 | U | | 0.028 | | | <0.0036 | U | | <0.0061 | U | | <0.0061 | U | | | | | | | | | | |
| | 30 ft | VMP-32-30-041612 | 4/16/2012 | <2.5 | U | | <2.6 | U | | 0.45 | J | | <2.3 | U | | 710 | | | <1.2 | U | | 18 | | | 3.7 | | | | | | | | | | | |
| | | VMP-32-30-072012 | 7/20/2012 | <5.2 | U | | <5.4 | U | | <4.7 | U | | <4.7 | U | | 470 | | | <2.5 | U | | <4.2 | U | | <4.2 | U | | | | | | | | | | |
| | | VMP-32-30-101812 | 10/18/2012 | <0.3 | U | | <0.31 | U | | <0.27 | U | | <0.27 | U | | 27 | | | <0.14 | U | | <0.24 | U | | <0.24 | U | | | | | | | | | | |
| | | VMP-32-30-020513 | 2/5/2013 | <0.3 | U | | <0.32 | U | | <0.28 | U | | <0.28 | U | | 140 | | | <0.14 | U | | <0.24 | U | | <0.24 | U | | | | | | | | | | |

SEE LAST PAGE OF TABLE FOR NOTES

**TABLE 5**
**CUMULATIVE SUMMARY OF SOIL VAPOR ANALYTICAL DETECTIONS AND SCREENING RESULTS: VILLAGE - VOCS**

| Location | Depth | Sample ID | Sample Date | Trichloroethene | | | Trichlorofluoromethane | | | 1,2,4-Trimethylbenzene | | | 1,3,5-Trimethylbenzene | | | 2,2,4-Trimethylpentane | | | Vinyl chloride | | | m,p-Xylene | | | o-Xylenes | | | $^{3}$Butane, 2,2-dimethyl- | | | $^{3}$Butane, 2,3-dimethyl- | | | $^{3}$Cyclobutane, ethyl- | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | 1.5 | | | 860 | | | | | | | | | | | | 0.29 | | | 130 | | | 120 | | | | | | | | | | | |
| | | | | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result (ppbV) | Lab Quals | URS Quals | Result (ppbV) | Lab Quals | URS Quals | Result (ppbV) | Lab Quals | URS Quals |
| VMP-42 | 10 ft | VMP-42-10-041812 | 4/18/2012 | 0.0019 | J | | 0.0014 | J | | <0.0042 | U | | <0.0042 | U | | 0.3 | | | <0.0022 | U | | 0.0098 | | | 0.0026 | J | | | | | | | | | |
| | | VMP-42-10-041812-Dup | 4/18/2012 | <0.0047 | U | | <0.0049 | U | | <0.0043 | U | | <0.0043 | U | | 0.26 | | | <0.0022 | U | | 0.0089 | | | 0.0026 | J | | | | | | | | | |
| | | VMP-42-20-041812 | 4/18/2012 | <2.4 | U | | <2.5 | U | | <2.2 | U | | <2.2 | U | | 66 | | | <1.1 | U | | 0.93 | J | | <1.9 | U | | | | | | | | | |
| | | VMP-42-10-071912 | 7/19/2012 | <0.0051 | U | | 0.0018 | J | J | 0.0024 | J | | <0.0047 | J | U | 0.0082 | | | <0.0024 | U | | 0.014 | | | 0.0045 | | | | | | | | | | |
| | | VMP-42-10-101212 | 10/12/2012 | <0.0083 | U | | <0.0087 | U | | <0.0076 | U | | <0.0076 | U | | 0.008 | | | <0.0039 | U | | <0.0067 | U | | <0.0067 | U | | | | | | | | | |
| | | VMP-42-10-013113 | 1/31/2013 | <0.0076 | U | | 0.0012 | J | | <0.0069 | J | U | <0.0069 | U | | 0.002 | J | | <0.0036 | U | | <0.0061 | U | | <0.0061 | U | | | | | | | | | |
| | 20 ft | VMP-42-20-071912 | 7/19/2012 | <0.005 | U | | 0.0057 | J | J | 0.0037 | J | | <0.0046 | J | U | 0.043 | | | <0.0024 | U | | 0.019 | | | 0.0062 | | | | | | | | | | |
| | | VMP-42-20-101212 | 10/12/2012 | <0.0073 | U | | 0.0015 | J | | <0.0067 | U | | <0.0067 | U | | 0.011 | | | <0.0035 | U | | <0.0059 | U | | <0.0059 | U | | | | | | | | | |
| | | VMP-42-20-101212-Dup | 10/12/2012 | <0.0074 | U | | 0.0018 | J | | <0.0068 | U | | <0.0068 | U | | 0.0039 | J | | <0.0035 | U | | <0.006 | J | U | <0.006 | U | | | | | | | | | |
| | | VMP-42-20-013113 | 1/31/2013 | <0.0069 | U | | 0.0014 | J | | <0.0063 | U | | <0.0063 | U | | 0.0011 | J | | <0.0033 | U | | <0.0056 | U | | <0.0056 | U | | | | | | | | | |
| | 30 ft | VMP-42-30-041912 | 4/19/2012 | <5 | U | | <5.2 | U | | <4.6 | U | | <4.6 | U | | 390 | | | <2.4 | U | | <4.1 | U | | <4.1 | U | | | | | | | | | |
| | | VMP-42-30-071912 | 7/19/2012 | <0.0047 | U | | 0.01 | J | J | 0.0051 | | J | 0.0063 | | J | 10 | S | | <0.0022 | U | | 0.032 | | J | 0.0076 | | J | | | | | | | | |
| | | VMP-42-30-101212 | 10/12/2012 | <0.0078 | U | | 0.0069 | J | | <0.0071 | U | | <0.0071 | U | | 0.49 | | | <0.0037 | U | | <0.0063 | U | | <0.0063 | U | | | | | | | | | |
| | | VMP-42-30-101212-Dup | 10/12/2012 | <0.0078 | J | U | 0.007 | J | | <0.0071 | U | | <0.0071 | U | | 0.47 | | | <0.0037 | U | | <0.0063 | U | | <0.0063 | U | | | | | | | | | |
| | | VMP-42-30-013113 | 1/31/2013 | <0.0074 | U | | 0.0034 | J | | <0.0068 | U | | <0.0068 | U | | 0.24 | | | <0.0035 | U | | <0.006 | U | | <0.006 | U | | | | | | | | | |
| VMP-43 | 10 ft | VMP-43-10-041612 | 4/16/2012 | <0.0053 | U | | <0.0055 | U | | 0.0024 | J | | 0.00087 | J | | 0.02 | | | <0.0025 | U | | 0.0086 | | | 0.0024 | J | | | | | | | | | |
| | | VMP-43-10-071912 | 7/19/2012 | <0.01 | U | | <0.01 | U | | 0.0042 | J | | 0.0015 | J | | 0.03 | | | <0.0048 | U | | 0.027 | | | 0.0085 | | | | | | | | | | |
| | | VMP-43-10-101612 | 10/16/2012 | <0.0086 | U | | <0.009 | U | | <0.0078 | U | UJ | <0.0078 | U | | 0.0069 | J | | <0.0041 | U | | 0.0013 | J | | <0.0069 | U | | | | | | | | | |
| | 20 ft | VMP-43-20-041612 | 4/16/2012 | <0.051 | U | | <0.054 | U | | 0.013 | J | | <0.047 | U | | 45 | | | <0.024 | U | | 0.038 | J | | 0.012 | J | | | | | | | | | |
| | | VMP-43-20-071912 | 7/19/2012 | <0.018 | U | | <0.019 | U | | 0.0034 | J | | <0.017 | U | | 3.3 | | | <0.0088 | U | | 0.019 | | | 0.006 | J | | | | | | | | | |
| | | VMP-43-20-101812 | 10/18/2012 | <0.0071 | U | | 0.0014 | J | | <0.0065 | U | UJ | <0.0065 | U | | 0.24 | | | <0.0034 | U | | 0.0018 | J | | <0.0057 | U | | | | | | | | | |
| | | VMP-43-20-012413 | 1/24/2013 | <0.0071 | U | | 0.0016 | J | | <0.0065 | U | | <0.0065 | U | | 0.025 | | | <0.0034 | U | | <0.0057 | U | | <0.0057 | U | | | | | | | | | |
| | 30 ft | VMP-43-30-042312 | 4/23/2012 | <0.047 | U | | <0.049 | U | | <0.043 | U | | <0.043 | U | | 6.8 | | | <0.022 | U | | <0.038 | U | | <0.038 | U | | | | | | | | | |
| | | VMP-43-30-071912 | 7/19/2012 | 0.0011 | J | | 0.0018 | J | J | 0.0046 | J | | 0.0014 | J | | 0.18 | | | <0.0024 | U | | 0.019 | | | 0.007 | | | | | | | | | | |
| | | VMP-43-30-101812 | 10/18/2012 | <0.0074 | U | | <0.0078 | U | | <0.0068 | U | UJ | <0.0068 | U | | 0.015 | | | <0.0035 | U | | <0.006 | U | | <0.006 | U | | | | | | | | | |
| | | VMP-43-30-012413 | 1/24/2013 | <0.0072 | U | | 0.0012 | J | | <0.0066 | U | | <0.0066 | U | | 0.0018 | J | | <0.0034 | U | | <0.0058 | U | | <0.0058 | U | | | | | | | | | |
| VMP-44 | 10 ft | VMP-44-10-041912 | 4/19/2012 | <2.4 | U | | <2.6 | U | | <2.2 | U | | <2.2 | U | | 1200 | | | <1.2 | U | | 0.89 | J | | <2 | U | | | | | | | | | |
| | | VMP-44-10-072012 | 7/20/2012 | <0.82 | U | | <0.86 | U | | 0.29 | J | J | 0.47 | J | J | 1200 | | | <0.39 | U | | 1.8 | | J | 0.66 | J | J | | | | | | | | |
| | | VMP-44-10-081012 | 8/10/2012 | <0.49 | U | | <0.51 | U | | 0.25 | J | J | 0.3 | J | J | 800 | | | <0.23 | U | | 1.3 | | J | 0.41 | | J | | | | | | | | |
| | | VMP-44-10-101212 | 10/12/2012 | 0.53 | J | | <1.6 | U | | <1.4 | U | UJ | <1.4 | U | | 190 | | | <0.72 | U | | 0.2 | J | | 0.17 | J | | | | | | | | | |
| | | VMP-44-10-012513 | 1/25/2013 | <0.62 | U | | <0.65 | U | | <0.56 | U | | <0.56 | U | | 300 | | | <0.29 | U | | 0.092 | J | | <0.5 | U | | | | | | | | | |
| | 20 ft | VMP-44-20-041912 | 4/19/2012 | <0.54 | U | | <0.56 | U | | 0.1 | J | | 0.23 | J | | 350 | | | <0.26 | U | | 0.86 | | | 0.5 | | | | | | | | | | |
| | | VMP-44-20-072512 | 7/25/2012 | <0.92 | U | | <0.96 | U | | <0.84 | U | | <0.84 | U | | 500 | | J | <0.44 | U | | <0.74 | U | | <0.74 | U | | | | | | | | | |
| | | VMP-44-20-101212 | 10/12/2012 | 0.76 | J | | <3.2 | U | | <2.8 | U | UJ | <2.8 | U | | 110 | | | <1.4 | U | | 0.3 | J | | 0.25 | J | | | | | | | | | |
| | | VMP-44-20-012513 | 1/25/2013 | <0.22 | U | | <0.23 | U | | <0.2 | U | | <0.2 | U | | 110 | | | <0.11 | U | | <0.18 | U | | <0.18 | U | | | | | | | | | |
| | 30 ft | VMP-44-30-041912 | 4/19/2012 | <0.31 | U | | <0.33 | U | | 0.16 | J | | 0.075 | J | | 23 | | | <0.15 | U | | 0.88 | | | 0.053 | J | | | | | | | | | |
| | | VMP-44-30-072512 | 7/25/2012 | <0.053 | U | | <0.055 | U | | 0.025 | J | | 0.042 | J | | 1.4 | | | <0.025 | U | | 0.34 | | | 0.024 | J | | | | | | | | | |
| | | VMP-44-30-072512-Dup | 7/25/2012 | <0.053 | U | | <0.055 | U | | 0.028 | J | | 0.038 | J | | 1.4 | | | <0.025 | U | | 0.35 | | | 0.026 | J | | | | | | | | | |
| | | VMP-44-30-101512 | 10/15/2012 | <0.32 | U | | <0.34 | U | | <0.3 | U | UJ | <0.3 | U | | 29 | | | <0.15 | U | | <0.26 | U | | <0.26 | U | | | | | | | | | |
| | | VMP-44-30-101512-Dup | 10/15/2012 | <0.3 | U | | <0.32 | U | | <0.28 | U | UJ | <0.28 | U | | 28 | | | <0.14 | U | | <0.24 | U | | <0.24 | U | | | | | | | | | |
| | | VMP-44-30-012513 | 1/25/2013 | <0.078 | U | UJ | <0.082 | U | UJ | <0.072 | U | UJ | <0.072 | U | UJ | 0.47 | | J | <0.037 | U | UJ | <0.063 | U | UJ | <0.063 | U | UJ | | | | | | | | |
| VMP-45 | 10 ft | VMP-45-10-041912 | 4/19/2012 | <0.0049 | U | | 0.0014 | J | | <0.0045 | U | | <0.0045 | U | | 0.043 | | | <0.0023 | U | | 0.0046 | | | <0.004 | U | | | | | | | | | |
| | | VMP-45-10-071912 | 7/19/2012 | <0.005 | U | | 0.0017 | J | J | 0.0017 | J | | 0.00057 | J | | <0.0044 | J | U | <0.0024 | U | | 0.014 | | | 0.0035 | J | | | | | | | | | |
| | | VMP-45-10-101512 | 10/15/2012 | <0.0078 | U | | 0.0014 | J | | <0.0072 | J | U | <0.0072 | U | | 0.038 | | | <0.0037 | U | | <0.0063 | J | U | <0.0063 | U | | | | | | | | | |
| | | VMP-45-10-013013 | 1/30/2013 | <0.0068 | U | | 0.0011 | J | | <0.0062 | U | | <0.0062 | U | | 0.0048 | J | | <0.0032 | U | | <0.0055 | U | | <0.0055 | U | | | | | | | | | |
| | 20 ft | VMP-45-20-041912 | 4/19/2012 | <0.31 | U | | <0.32 | U | | 0.4 | | | 0.19 | J | | 130 | | | <0.14 | U | | 8 | | | 2.5 | | | | | | | | | | |
| | | VMP-45-20-071912 | 7/19/2012 | <0.096 | U | | <0.1 | U | | <0.088 | U | | <0.088 | U | | 23 | | | <0.046 | U | | 0.065 | J | | 0.015 | J | | | | | | | | | |
| | | VMP-45-20-101512 | 10/15/2012 | <0.0074 | U | | <0.0078 | U | | <0.0068 | U | | <0.0068 | U | | 3.4 | | | <0.0035 | U | | <0.006 | U | | <0.006 | U | | | | | | | | | |
| | | VMP-45-20-013013 | 1/30/2013 | <0.0071 | U | | 0.001 | J | | <0.0065 | U | | <0.0065 | U | | 0.31 | | | <0.0034 | U | | <0.0057 | U | | <0.0057 | U | | | | | | | | | |
| | 30 ft | VMP-45-30-041912 | 4/19/2012 | <0.2 | U | | <0.21 | U | | <0.19 | U | | <0.19 | U | | 400 | | | <0.098 | U | | 0.27 | | J | <0.16 | U | | | | | | | | | |
| | | VMP-45-30-071912 | 7/19/2012 | <0.051 | U | | <0.054 | U | | <0.047 | U | | <0.047 | U | | 9.1 | | | <0.024 | U | | <0.041 | U | | <0.041 | U | | | | | | | | | |
| | | VMP-45-30-101512 | 10/15/2012 | <0.0074 | U | | 0.0035 | J | | <0.0068 | U | | <0.0068 | U | | 1.8 | | | <0.0035 | U | | <0.006 | U | | <0.006 | U | | | | | | | | | |
| | | VMP-45-30-101512-Dup | 10/15/2012 | <0.0073 | U | | 0.0039 | J | | <0.0067 | U | | <0.0067 | U | | 1.9 | | | <0.0035 | U | | <0.0059 | U | | <0.0059 | U | | | | | | | | | |
| | | VMP-45-30-013013 | 1/30/2013 | <0.013 | U | | 0.0038 | J | | <0.012 | U | | <0.012 | U | | 0.56 | | | <0.0062 | U | | <0.01 | U | | <0.01 | U | | | | | | | | | |

SEE LAST PAGE OF TABLE FOR NOTES

**TABLE 5**
**CUMULATIVE SUMMARY OF SOIL VAPOR ANALYTICAL DETECTIONS AND SCREENING RESULTS: VILLAGE - VOCS**

| Location | Depth | Sample ID | Sample Date | Trichloroethene | | | Trichlorofluoromethane | | | 1,2,4-Trimethylbenzene | | | 1,3,5-Trimethylbenzene | | | 2,2,4-Trimethylpentane | | | Vinyl chloride | | | m,p-Xylene | | | o-Xylenes | | | $^{3}$Butane, 2,2-dimethyl- | | | $^{3}$Butane, 2,3-dimethyl- | | | $^{3}$Cyclobutane, ethyl- | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | 1.5 | | | 860 | | | | | | | | | | | | 0.29 | | | 130 | | | 120 | | | | | | | | | | | | |
| | | | | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result (ppbV) | Lab Quals | URS Quals | Result (ppbV) | Lab Quals | URS Quals | Result (ppbV) | Lab Quals | URS Quals |
| VMP-47 | 5 ft | VMP-47-5-012113 | 1/21/2013 | <0.0078 | U | | <0.0081 | U | | <0.0071 | U | | <0.0071 | U | | 0.52 | | | <0.0037 | U | | <0.0063 | U | | <0.0063 | U | | 13 | | | | | | | | |
| | | [4]VMP-47-5-012313-R | 1/23/2013 | <26 | U | | <27 | U | | <24 | U | | <24 | U | | 430 | | | <12 | U | | <21 | U | | <21 | U | | | | | | | | | | |
| | 10 ft | VMP-47-10-012113 | 1/21/2013 | <0.0074 | U | | <0.0078 | U | | <0.0068 | U | | <0.0068 | U | | 0.0028 | J | | <0.0035 | U | | <0.006 | U | | <0.006 | U | | | | | | | | | | |
| | | [4]VMP-47-10-012313-R | 1/23/2013 | <0.65 | U | | <0.68 | U | | <0.59 | U | | <0.59 | U | | 100 | | | <0.31 | U | | 0.19 | J | | <0.52 | U | | | | | | | | | | |
| | 20 ft | VMP-47-20-012113 | 1/21/2013 | <6.8 | U | | <7.1 | U | | <6.2 | U | | <6.2 | U | | 160 | | | <3.2 | U | | <5.5 | U | | <5.5 | U | | | | | | | | | | |
| | | [4]VMP-47-20-012313-R | 1/23/2013 | <16 | U | | <17 | U | | <15 | U | | <15 | U | | 340 | | | <7.6 | U | | <13 | U | | <13 | U | | | | | | | | | | |
| | 30 ft | VMP-47-30-012113 | 1/21/2013 | <4.9 | U | | <5.2 | U | | <4.5 | U | | <4.5 | U | | 190 | | | <2.4 | U | | <4 | U | | <4 | U | | | | | | | | | | |
| | | [4]VMP-47-30-012313-R | 1/23/2013 | <26 | U | | <27 | U | | <23 | U | | <23 | U | | 430 | | | <12 | U | | <21 | U | | <21 | U | | | | | | | | | | |
| VMP-48 | 5 ft | VMP-48-5-020113 | 2/1/2013 | <0.0069 | U | | 0.00096 | J | | <0.0063 | U | | <0.0063 | U | | 0.0034 | J | | <0.0033 | U | | <0.0056 | U | | <0.0056 | U | | | | | | | | | | |
| | 10 ft | VMP-48-10-020113 | 2/1/2013 | <0.0071 | U | | 0.0018 | J | | <0.0065 | U | | <0.0065 | U | | <0.0062 | U | | <0.0034 | U | | <0.0058 | U | | <0.0058 | U | | | | | | | | | | |
| | 20 ft | VMP-48-20-020113 | 2/1/2013 | <0.0068 | U | | 0.002 | J | | <0.0063 | U | | <0.0063 | U | | 0.0013 | J | | <0.0032 | U | | <0.0055 | U | | <0.0055 | U | | | | | | | | | | |
| | 30 ft | VMP-48-30-020113 | 2/1/2013 | <0.007 | U | | 0.016 | | | 0.011 | | | 0.024 | | | 5.4 | | | <0.0033 | U | | 0.01 | | | 0.0024 | J | J | | | | | | | | | |
| | | VMP-48-30-020113-DUP | 2/1/2013 | <0.028 | U | | 0.017 | J | | 0.0093 | J | | 0.022 | J | | 5.5 | | | <0.013 | U | | 0.0094 | J | | <0.022 | U | UJ | | | | | | | | | |
| VMP-49 | 5 ft | VMP-49-5-020113 | 2/1/2013 | <0.0072 | U | | 0.0012 | J | | <0.0066 | U | | <0.0066 | U | | 0.0035 | J | | <0.0034 | U | | <0.0058 | U | | <0.0058 | U | | | | | | | | | | |
| | 10 ft | VMP-49-10-020113 | 2/1/2013 | <0.0071 | U | | 0.00098 | J | | 0.0085 | | | <0.0065 | J | U | <0.0062 | U | | <0.0034 | U | | <0.0057 | J | U | <0.0057 | U | | | | | | | | | | |
| | 20 ft | VMP-49-20-020113 | 2/1/2013 | <0.0069 | U | | 0.0011 | J | | <0.0063 | U | | <0.0063 | U | | 0.0034 | J | | <0.0033 | U | | <0.0056 | U | | <0.0056 | U | | | | | | | | | | |
| | 30 ft | VMP-49-30-020113 | 2/1/2013 | <0.33 | U | | <0.34 | U | | <0.3 | U | | <0.3 | U | | 45 | | | <0.16 | U | | <0.27 | U | | <0.27 | U | | | | | | | | | | |
| VMP-50 | 5 ft | VMP-50-5-020113 | 2/1/2013 | <0.0068 | U | | 0.0012 | J | | <0.0062 | U | | <0.0062 | U | | 0.012 | | | <0.0032 | U | | <0.0055 | U | | <0.0055 | U | | | | | | | | | | |
| | 10 ft | VMP-50-10-020113 | 2/1/2013 | <0.0074 | U | | 0.0011 | J | | <0.0068 | J | U | <0.0068 | J | U | 0.0093 | | | <0.0035 | U | | <0.006 | U | | <0.006 | U | | | | | | | | | | |
| | 20 ft | VMP-50-20-020113 | 2/1/2013 | <0.029 | U | | <0.03 | U | | 0.0075 | J | | <0.026 | U | | 9.2 | | | <0.014 | U | | 0.0078 | J | | 0.0071 | J | | | | | | | | | | |
| | 30 ft | VMP-50-30-020113 | 2/1/2013 | <7 | U | | <7.3 | U | | 39 | | | 19 | | | 450 | | | <3.3 | U | | 700 | | | 220 | | | | | | | | | | | |
| VMP-51 | 5 ft | VMP-51-5-020113 | 2/1/2013 | <0.0073 | U | | 0.0011 | J | | <0.0067 | U | | <0.0067 | U | | 0.0045 | J | | <0.0035 | U | | <0.0059 | U | | <0.0059 | U | | | | | | | | | | |
| | 10 ft | VMP-51-10-020113 | 2/1/2013 | <0.0074 | U | | 0.00093 | J | | <0.0068 | U | | <0.0068 | U | | 0.0027 | J | | <0.0035 | U | | <0.006 | U | | <0.006 | U | | | | | | | | | | |
| | 20 ft | VMP-51-20-021513-R | 2/15/2013 | <0.0071 | U | | 0.0013 | J | | 0.0049 | J | J | <0.0065 | U | | 0.078 | | | <0.0034 | U | | 0.0022 | J | | <0.0057 | U | | | | | | | | | | |
| | 30 ft | VMP-51-30-020413 | 2/4/2013 | <0.0078 | U | | <0.0081 | J | U | <0.0071 | U | | <0.0071 | U | | 0.0041 | J | | <0.0037 | U | | <0.0063 | U | | <0.0063 | U | | | | | | | | | | |
| | | VMP-51-30-020413-DUP | 2/4/2013 | <0.0076 | U | | <0.0079 | J | U | <0.0069 | U | | <0.0069 | U | | 0.0054 | J | | <0.0036 | U | | <0.0061 | U | | <0.0061 | U | | | | | | | | | | |
| VMP-52 | 5 ft | VMP-52-5-020413 | 2/4/2013 | <0.0068 | U | | 0.0014 | J | | <0.0062 | J | U | <0.0062 | U | | 0.0025 | J | | <0.0032 | U | | <0.0055 | U | | <0.0055 | U | | | | | | | | | | |
| | 10 ft | VMP-52-10-020413 | 2/4/2013 | <0.0064 | U | | 0.0011 | J | | <0.0059 | U | | <0.0059 | U | | 0.0032 | J | | <0.0031 | U | | <0.0052 | U | | <0.0052 | U | | | | | | | | | | |
| | 20 ft | VMP-52-20-020413 | 2/4/2013 | <0.0072 | U | | <0.0075 | J | U | <0.0066 | J | U | <0.0066 | J | U | 0.059 | | | <0.0034 | U | | 0.0025 | J | | <0.0058 | J | U | | | | | | | | | |
| | | VMP-52-20-020413-DUP | 2/4/2013 | <0.0069 | U | | <0.0072 | J | U | <0.0063 | U | | <0.0063 | U | | 0.052 | | | <0.0033 | U | | <0.0056 | U | | <0.0056 | U | | | | | | | | | | |
| | 30 ft | VMP-52-30-020413 | 2/4/2013 | <0.0076 | U | | 0.0021 | J | | <0.0069 | U | | <0.0069 | U | | 0.58 | | | <0.0036 | U | | <0.0061 | U | | <0.0061 | U | | | | | | | | | | |
| VMP-53 | 5 ft | VMP-53-5-020513 | 2/5/2013 | <0.0069 | U | | <0.0072 | J | U | <0.0063 | U | | <0.0063 | U | | 0.002 | J | | <0.0033 | U | | <0.0056 | U | | <0.0056 | U | | | | | | | | | | |
| | 10 ft | VMP-53-10-020513 | 2/5/2013 | <0.0071 | U | | <0.0074 | J | U | <0.0065 | U | | <0.0065 | U | | 0.0038 | J | | <0.0034 | U | | <0.0057 | U | | <0.0057 | U | | | | | | | | | | |
| | | VMP-53-10-020513-DUP | 2/5/2013 | <0.0066 | U | | <0.0069 | J | U | <0.0061 | U | | <0.0061 | U | | <0.0058 | J | U | <0.0032 | U | | <0.0054 | U | | <0.0054 | U | | | | | | | | | | |
| | 20 ft | VMP-53-20-020513 | 2/5/2013 | <0.0071 | U | | <0.0074 | J | U | <0.0065 | U | | <0.0065 | U | | 0.0024 | J | | <0.0034 | U | | <0.0057 | U | | <0.0057 | U | | | | | | | | | | |
| | 30 ft | VMP-53-30-020513 | 2/5/2013 | <0.0072 | U | | 0.0013 | J | | <0.0066 | U | | <0.0066 | U | | 0.0023 | J | | <0.0034 | U | | <0.0058 | U | | <0.0058 | U | | | | | | | | | | |
| VMP-54 | 5 ft | VMP-54-5-020613 | 2/6/2013 | <0.0074 | U | | <0.0078 | J | U | 0.047 | | | 0.014 | | | 0.022 | | | <0.0035 | U | | 0.036 | | | 0.02 | | | | | | | | | | | |
| | 10 ft | VMP-54-10-020613 | 2/6/2013 | <0.0076 | U | | <0.0079 | J | U | <0.0069 | J | U | <0.0069 | J | U | 0.0042 | J | | <0.0036 | U | | 0.0091 | | | 0.0041 | J | | | | | | | | | | |
| | 20 ft | VMP-54-20-020613 | 2/6/2013 | <0.0074 | U | | 0.0014 | J | | <0.0068 | J | U | <0.0068 | U | | 0.0011 | J | | <0.0035 | U | | <0.006 | U | | <0.006 | U | | | | | | | | | | |
| | | VMP-54-20-020613-DUP | 2/6/2013 | <0.0074 | U | | 0.0013 | J | | <0.0068 | J | U | <0.0068 | U | | 0.0043 | J | | <0.0035 | U | | <0.006 | U | | <0.006 | U | | | | | | | | | | |
| | 30 ft | VMP-54-30-020613 | 2/6/2013 | <0.008 | U | | 0.0012 | J | | <0.0073 | U | | <0.0073 | U | | 0.0023 | J | | <0.0038 | U | | <0.0064 | U | | <0.0064 | U | | | | | | | | | | |
| | | VMP-54-30-020613-DUP | 2/6/2013 | <0.008 | U | | 0.0013 | J | | <0.0073 | U | | <0.0073 | U | | 0.0013 | J | | <0.0038 | U | | <0.0064 | U | | <0.0064 | U | | | | | | | | | | |

SEE LAST PAGE OF TABLE FOR NOTES

**TABLE 5**
**CUMULATIVE SUMMARY OF SOIL VAPOR ANALYTICAL DETECTIONS AND SCREENING RESULTS: VILLAGE - VOCS**

| Location | Depth | Sample ID | Sample Date | [3]Heptadecane | | | [3]Hexane, 2,2,4-trimethyl- | | | [3]Pentane, 2,2,3-trimethyl- | | | [3]Pentane, 2,3,4-trimethyl- | | | [3]Pentane, 2,4-dimethyl- | | | [3]Cyclopentane, methyl- | | | [3]Butane, 2,2,3-trimethyl- | | | [3]Hexane, 3,4-dimethyl- | | | [3]Pentane, 2,3-dimethyl- | | | [3]Isobutane | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | Result (ppbV) | Lab Quals | URS Quals | Result (ppbV) | Lab Quals | URS Quals | Result (ppbV) | Lab Quals | URS Quals | Result (ppbV) | Lab Quals | URS Quals | Result (ppbV) | Lab Quals | URS Quals | Result (ppbV) | Lab Quals | URS Quals | Result (ppbV) | Lab Quals | URS Quals | Result (ppbV) | Lab Quals | URS Quals | Result (ppbV) | Lab Quals | URS Quals | Result (ppbV) | Lab Quals | URS Quals |
| VMP-1 | 5 ft | VMP-1-5-082510 | 8/25/2010 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-1-5-111710 | 11/17/2010 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-1-5-020411 | 2/4/2011 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-1-5-041211 | 4/12/2011 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-1-5-080111 | 8/1/2011 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-1-5-110311 | 11/3/2011 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-1-5-013012 | 1/30/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-1-5-041312 | 4/13/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-1-5-071612 | 7/16/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-1-5-101112 | 10/11/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | [4]VMP-1-5-012113 | 1/21/2013 | | | | | | | | | | | | | 1,400 | | | | | | | | | | | | 2,400 | | | | | |
| | | [4]VMP-1-5-012313-R | 1/23/2013 | | | | | | | | | | | | | | | | | | | 150,000 | | | | | | | | | 240,000 | | |
| | 8.5 ft | VMP-1-8.5-082510 | 8/25/2010 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-1-8.5-111710 | 11/17/2010 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-1-8.5-111710-Dup | 11/17/2010 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-1-8.5-020411 | 2/4/2011 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-1-8.5-041211 | 4/12/2011 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-1-8.5-080111 | 8/1/2011 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-1-8.5-080111-Dup | 8/1/2011 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-1-8.5-110311 | 11/3/2011 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-1-8.5-013012 | 1/30/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-1-8.5-041612 | 4/16/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-1-8.5-041612-Dup | 4/16/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-1-8.5-071612 | 7/16/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-1-8.5-101112 | 10/11/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | [4]VMP-1-8.5-012113 | 1/21/2013 | | | | | | | | | | | | | | | | | | | | | | | | | | | | 3800 | | | |
| | | [4]VMP-1-8.5-012313-R | 1/23/2013 | | | | | | | 5,900 | | | | | | | | | | | | | | | | | | | | | 11,000 | | | |
| | 23.5 ft | VMP - 1 - 23.5 - 083010 | 8/30/2010 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-1-23.5-111810 | 11/17/2010 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-1-23.5-020411 | 2/4/2011 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-1-23.5-041211 | 4/12/2011 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-1-23.5-041211-DUP | 4/12/2011 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-1-23.5-080111 | 8/1/2011 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-1-23.5-110611 | 11/6/2011 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-1-23.5-013112 | 1/31/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-1-23.5-041612 | 4/16/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-1-23.5-071612 | 7/16/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-1-23.5-102412 | 10/24/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | [4]VMP-1-23.5-012113 | 1/21/2013 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | [4]VMP-1-23.5-012313-R | 1/23/2013 | | | | | | | | | | | | | | | | | | | | | | | | | | | | 1,300,000 | | | |
| | 38.5 ft | VMP-1-38.5-073112 | 7/31/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-1-38.5-102612 | 10/26/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | [4]VMP-1-38.5-012113 | 1/21/2013 | | | | | | | | | | | | | 420 | | J | | | | | | | | | | 1,000 | | J | | | |
| | | [4]VMP-1-38.5-012313-R | 1/23/2013 | | | | | | | | | | | | | | | | 250,000 | | | 460,000 | | | | | | | | | 760,000 | | |
| VMP-2 | 5 ft | VMP - 2 - 5 - 083110 | 8/31/2010 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-2-5-111610 | 11/16/2010 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-2-5-020411 | 2/4/2011 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-2-5-041311 | 4/13/2011 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-2-5-080211 | 8/2/2011 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-2-5-110711 | 11/7/2011 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-2-5-012512 | 1/25/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-2-5-042512 | 4/25/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-2-5-071612 | 7/16/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-2-5-102412 | 10/24/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-2-5-013113 | 1/31/2013 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | 8.5 ft | VMP-2-8.5-083110 | 8/31/2010 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-2-8.5-111610 | 11/16/2010 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-2-8.5-020411 | 2/4/2011 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-2-8.5-041311 | 4/13/2011 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-2-8.5-080211 | 8/2/2011 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-2-8.5-110711 | 11/7/2011 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-2-8.5-012612 | 1/26/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-2-8.5-012612-DUP | 1/26/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-2-8.5-041612 | 4/16/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-2-8.5-041612-Dup | 4/16/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-2-8.5-071612 | 7/16/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-2-8.5-071612-Dup | 7/16/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-2-8.5-102312 | 10/23/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-2-8.5-020513 | 2/5/2013 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | 22 ft | VMP-2-22-083110 | 8/31/2010 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-2-22-111610 | 11/16/2010 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-2-22-020411 | 2/4/2011 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-2-22-041311 | 4/13/2011 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-2-22-080211 | 8/2/2011 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-2-22-110711 | 11/7/2011 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-2-22-012612 | 1/26/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-2-22-042712 | 4/27/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-2-22-071612 | 7/16/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-2-22-102312 | 10/23/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-2-22-013113 | 1/31/2013 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | 42 ft | VMP-2-42-013113 | 1/31/2013 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |

SEE LAST PAGE OF TABLE FOR NOTES

**TABLE 5**
**CUMULATIVE SUMMARY OF SOIL VAPOR ANALYTICAL DETECTIONS AND SCREENING RESULTS: VILLAGE - VOCS**

| Location | Depth | Sample ID | Sample Date | [3]Heptadecane | | | [3]Hexane, 2,2,4-trimethyl- | | | [3]Pentane, 2,2,3-trimethyl- | | | [3]Pentane, 2,3,4-trimethyl- | | | [3]Pentane, 2,4-dimethyl- | | | [3]Cyclopentane, methyl- | | | [3]Butane, 2,2,3-trimethyl- | | | [3]Hexane, 3,4-dimethyl- | | | [3]Pentane, 2,3-dimethyl- | | | [3]Isobutane | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | Result (ppbV) | Lab Quals | URS Quals | Result (ppbV) | Lab Quals | URS Quals | Result (ppbV) | Lab Quals | URS Quals | Result (ppbV) | Lab Quals | URS Quals | Result (ppbV) | Lab Quals | URS Quals | Result (ppbV) | Lab Quals | URS Quals | Result (ppbV) | Lab Quals | URS Quals | Result (ppbV) | Lab Quals | URS Quals | Result (ppbV) | Lab Quals | URS Quals | Result (ppbV) | Lab Quals | URS Quals |
| VMP-3 | 5 ft | VMP-3-5-090910 | 9/9/2010 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-3-5-112210 | 11/22/2010 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-3-5-020911 | 2/9/2011 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-3-5-041411 | 4/14/2011 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-3-5-080211 | 8/2/2011 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-3-5-110811 | 11/8/2011 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-3-5-110811-DUP | 11/8/2011 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-3-5-012712 | 1/27/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-3-5-041912 | 4/19/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-3-5-072712 | 7/27/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | 10 ft | VMP-3-10 | 6/21/2010 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-3-10-091010 | 9/10/2010 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-3-10-092010 | 9/20/2010 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-3-10-112210 | 11/22/2010 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-3-10-112210-Dup | 11/22/2010 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-3-10-020811 | 2/8/2011 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-3-10-041311 | 4/13/2011 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-3-10-080311 | 8/3/2011 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-3-10-110811 | 11/8/2011 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-3-10-012712 | 1/27/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-3-10-042012 | 4/20/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-3-10-072312 | 7/23/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-3-10-101812 | 10/18/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-3-10-020613 | 2/6/2013 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | 22 ft | VMP-3-22-092010 | 9/20/2010 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-3-22-112210 | 11/22/2010 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-3-22-020811 | 2/8/2011 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-3-22-041511 | 4/15/2011 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-3-22-080611 | 8/6/2011 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-3-22-110811 | 11/8/2011 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-3-22-013012 | 1/30/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-3-22-042012 | 4/20/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-3-22-072312 | 7/23/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-3-22-101812 | 10/18/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-3-22-020613 | 2/6/2013 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | 31.5 ft | VMP-3-31.5-090910 | 9/9/2010 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-3-31.5-112210 | 11/22/2010 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-3-31.5-020911 | 2/9/2011 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-3-31.5-041411 | 4/14/2011 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-3-31.5-041411-DUP | 4/14/2011 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-3-31.5-080211 | 8/2/2011 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-3-31.5-080211-Dup | 8/2/2011 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-3-31.5-110811 | 11/8/2011 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-3-31.5-012712 | 1/27/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-3-31.5-041912 | 4/19/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-3-31.5-041912-Dup | 4/19/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-3-31.5-072312 | 7/23/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-3-31.5-101912 | 10/19/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-3-31.5-020713 | 2/7/2013 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | 39.5 ft | VMP-3-39-101912 | 10/19/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-3-39-021213 | 2/12/2013 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| VMP-4 | 5 ft | VMP-4-5-082510 | 8/25/2010 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-4-5-112210 | 11/22/2010 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-4-5-021411 | 2/14/2011 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-4-5-041911 | 4/19/2011 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-4-5-080311 | 8/3/2011 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-4-5-110911 | 11/9/2011 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-4-5-013012 | 1/30/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-4-5-042512 | 4/25/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-4-5-072512 | 7/25/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-4-5-101812 | 10/18/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-4-5-020713 | 2/7/2013 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | 12 ft | VMP-4-12-082510 | 8/25/2010 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-4-12-112310 | 11/23/2010 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-4-12-021411 | 2/14/2011 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-4-12-041911 | 4/19/2011 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-4-12-080311 | 8/3/2011 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-4-12-080311-Dup | 8/3/2011 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-4-12-110911 | 11/9/2011 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-4-12-013012 | 1/30/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-4-12-041812 | 4/18/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-4-12-072312 | 7/23/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-4-12-101812 | 10/18/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-4-12-101812-Dup | 10/18/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-4-12-020713 | 2/7/2013 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-4-12-020713-DUP | 2/7/2013 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | 23.5 ft | VMP - 4 - 23.5 - 083110 | 8/31/2010 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-4-23.5-112310 | 11/23/2010 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-4-23.5-021411 | 2/14/2011 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-4-23.5-042011 | 4/20/2011 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-4-23.5-042011-DUP | 4/20/2011 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-4-23.5-080611 | 8/6/2011 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-4-23.5-110911 | 11/9/2011 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-4-23.5-013012 | 1/30/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-4-23.5-013012-DUP | 1/30/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-4-23.5-041912 | 4/19/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-4-23.5-072312 | 7/23/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-4-23.5-101812 | 10/18/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-4-23.5-020713 | 2/7/2013 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | 39 ft | VMP-4-39-042111 | 4/21/2011 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-4-39-041912 | 4/19/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-4-39-072312 | 7/23/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-4-39-101812 | 10/18/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-4-39-101812-Dup | 10/18/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-4-39-020713 | 2/7/2013 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |

SEE LAST PAGE OF TABLE FOR NOTES

**TABLE 5**
**CUMULATIVE SUMMARY OF SOIL VAPOR ANALYTICAL DETECTIONS AND SCREENING RESULTS: VILLAGE - VOCS**

| Location | Depth | Sample ID | Sample Date | $^{3}$Heptadecane | | | $^{3}$Hexane, 2,2,4-trimethyl- | | | $^{3}$Pentane, 2,2,3-trimethyl- | | | $^{3}$Pentane, 2,3,4-trimethyl- | | | $^{3}$Pentane, 2,4-dimethyl- | | | $^{3}$Cyclopentane, methyl- | | | $^{3}$Butane, 2,2,3-trimethyl- | | | $^{3}$Hexane, 3,4-dimethyl- | | | $^{3}$Pentane, 2,3-dimethyl- | | | $^{3}$Isobutane | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | Result (ppbV) | Lab Quals | URS Quals | Result (ppbV) | Lab Quals | URS Quals | Result (ppbV) | Lab Quals | URS Quals | Result (ppbV) | Lab Quals | URS Quals | Result (ppbV) | Lab Quals | URS Quals | Result (ppbV) | Lab Quals | URS Quals | Result (ppbV) | Lab Quals | URS Quals | Result (ppbV) | Lab Quals | URS Quals | Result (ppbV) | Lab Quals | URS Quals | Result (ppbV) | Lab Quals | URS Quals |
| VMP-5 | 5 ft | VMP-5-5-090910 | 9/9/2010 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-5-5-112210 | 11/22/2010 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-5-5-021611 | 2/16/2011 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-5-5-042111 | 4/21/2011 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-5-5-080511 | 8/5/2011 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-5-5-111111 | 11/11/2011 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-5-5-013012 | 1/30/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-5-5-041112 | 4/11/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-5-5-071312 | 7/13/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-5-5-101212 | 10/12/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-5-5-012513 | 1/25/2013 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | 12.5 ft | VMP-5-12.5-090910 | 9/9/2010 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-5-12.5-112310 | 11/23/2010 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-5-12.5-021611 | 2/16/2011 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-5-12.5-042111 | 4/21/2011 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-5-12.5-080611 | 8/6/2011 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-5-12.5-111111 | 11/11/2011 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-5-12.5-013012 | 1/30/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-5-12.5-041112 | 4/11/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-5-12.5-071212 | 7/12/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-5-12.5-101112 | 10/11/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-5-12.5-012413 | 1/24/2013 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | 31 ft | VMP-5-31-090910 | 9/9/2010 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-5-31-112310 | 11/23/2010 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-5-31-021611 | 2/16/2011 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-5-31-042111 | 4/21/2011 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-5-31-080611 | 8/6/2011 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-5-31-111111 | 11/11/2011 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-5-31-013012 | 1/30/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-5-31-041112 | 4/11/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-5-31-071212 | 7/12/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-5-31-101112 | 10/11/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-5-31-012413 | 1/24/2013 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | 40 ft | VMP-5-40-042111 | 4/21/2011 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-5-40-013012 | 1/30/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-5-40-041212 | 4/12/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-5-40-071212 | 7/12/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-5-40-101112 | 10/11/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-5-40-012513 | 1/25/2013 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-5-40-012513-Dup | 1/25/2013 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| VMP-6 | 5 ft | VMP-6-5-090810 | 9/8/2010 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-6-5-111610 | 11/16/2010 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-6-5-020711 | 2/7/2011 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-6-5-040811 | 4/8/2011 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-6-5-080411 | 8/4/2011 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-6-5-110911 | 11/9/2011 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-6-5-013112 | 1/31/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-6-5-041212 | 4/12/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-6-5-071612 | 7/16/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-6-5-101012 | 10/10/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-6-5-021213 | 2/12/2013 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | 10 ft | VMP-6-10-090810 | 9/8/2010 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-6-10-111710 | 11/17/2010 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-6-10-020711 | 2/7/2011 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-6-10-040811 | 4/8/2011 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-6-10-080411 | 8/4/2011 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-6-10-111011 | 11/10/2011 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-6-10-013112 | 1/31/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-6-10-041212 | 4/12/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-6-10-071612 | 7/16/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-6-10-101112 | 10/11/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-6-10-020513 | 2/5/2013 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | 31.5 ft | VMP-6-31.5-090810 | 9/8/2010 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-6-31.5-111710 | 11/17/2010 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-6-31.5-020711 | 2/7/2011 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-6-31.5-041111 | 4/11/2011 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-6-31.5-080411 | 8/4/2011 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-6-31.5-111011 | 11/10/2011 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-6-31.5-013112 | 1/31/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-6-31.5-041212 | 4/12/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-6-31.5-071612 | 7/16/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-6-31.5-101112 | 10/11/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-6-31.5-020513 | 2/5/2013 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | 39 ft | VMP-6-39-041111 | 4/11/2011 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-6-39-013112 | 1/31/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-6-39-041212 | 4/12/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-6-39-071612 | 7/16/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-6-39-071612-Dup | 7/16/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-6-39-101112 | 10/11/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-6-39-020513 | 2/5/2013 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |

SEE LAST PAGE OF TABLE FOR NOTES

**TABLE 5**
**CUMULATIVE SUMMARY OF SOIL VAPOR ANALYTICAL DETECTIONS AND SCREENING RESULTS: VILLAGE - VOCS**

| Location | Depth | Sample ID | Sample Date | [3]Heptadecane | | | [3]Hexane, 2,2,4-trimethyl- | | | [3]Pentane, 2,2,3-trimethyl- | | | [3]Pentane, 2,3,4-trimethyl- | | | [3]Pentane, 2,4-dimethyl- | | | [3]Cyclopentane, methyl- | | | [3]Butane, 2,2,3-trimethyl- | | | [3]Hexane, 3,4-dimethyl- | | | [3]Pentane, 2,3-dimethyl- | | | [3]Isobutane | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | Result (ppbV) | Lab Quals | URS Quals | Result (ppbV) | Lab Quals | URS Quals | Result (ppbV) | Lab Quals | URS Quals | Result (ppbV) | Lab Quals | URS Quals | Result (ppbV) | Lab Quals | URS Quals | Result (ppbV) | Lab Quals | URS Quals | Result (ppbV) | Lab Quals | URS Quals | Result (ppbV) | Lab Quals | URS Quals | Result (ppbV) | Lab Quals | URS Quals | Result (ppbV) | Lab Quals | URS Quals |
| VMP-7 | 5 ft | VMP-7-5-082610 | 8/26/2010 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-7-5-111910 | 11/19/2010 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-7-5-020711 | 2/7/2011 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-7-5-040711 | 4/7/2011 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-7-5-080211 | 8/2/2011 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-7-5-111011 | 11/10/2011 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-7-5-111011-DUP | 11/10/2011 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-7-5-013112 | 1/31/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-7-5-041212 | 4/12/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-7-5-073112 | 7/31/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-7-5-101012 | 10/10/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | 13.5 ft | VMP-7-13.5-082610 | 8/26/2010 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-7-13.5-111910 | 11/19/2010 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-7-13.5-020711 | 2/7/2011 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-7-13.5-040711 | 4/7/2011 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-7-13.5-080311 | 8/3/2011 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-7-13.5-111011 | 11/10/2011 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-7-13.5-013112 | 1/31/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-7-13.5-013112-DUP | 1/31/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-7-13.5-041212 | 4/12/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-7-13.5-041212-DUP | 4/12/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-7-13.5-072012 | 7/20/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-7-13.5-101012 | 10/10/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-7-13.5-021313 | 2/13/2013 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | 29.5 ft | VMP-7-29.5-083110 | 8/31/2010 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-7-29.5-111910 | 11/19/2010 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-7-29.5-020711 | 2/7/2011 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-7-29.5-040711 | 4/7/2011 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-7-29.5-080311 | 8/3/2011 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-7-29.5-111111 | 11/11/2011 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-7-29.5-020112 | 2/1/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-7-29.5-041312 | 4/13/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-7-29.5-072012 | 7/20/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-7-29.5-072012-Dup | 7/20/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-7-29.5-101012 | 10/10/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | 38 ft | VMP-7-38-020711 | 2/7/2011 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-7-38-040711 | 4/7/2011 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-7-38-020112 | 2/1/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-7-38-042512 | 4/25/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-7-38-042512-Dup | 4/25/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-7-38-101112 | 10/11/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| VMP-8 | 5 ft | VMP-8-5-083010 | 8/30/2010 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-8-5-111810 | 11/17/2010 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-8-5-021011 | 2/10/2011 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-8-5-040711 | 4/7/2011 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-8-5-072711 | 7/27/2011 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-8-5-110311 | 11/3/2011 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-8-5-012312 | 1/23/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-8-5-041012 | 4/10/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-8-5-071312 | 7/13/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-8-5-073112 | 7/31/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-8-5-100412 | 10/4/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-8-5-100412-Dup | 10/4/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-8-5-012413 | 1/24/2013 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | 9.5 ft | VMP-8-9.5 | 11/10/2009 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-8-9.5-083010 | 8/30/2010 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-8-9.5-083010-DUP | 8/30/2010 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-8-9.5-111810 | 11/17/2010 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-8-9.5-021011 | 2/10/2011 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-8-9.5-040711 | 4/7/2011 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-8-9.5-072711 | 7/27/2011 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-8-9.5-110311 | 11/3/2011 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-8-9.5-012312 | 1/23/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-8-9.5-041012 | 4/10/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-8-9.5-071312 | 7/13/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-8-9.5-071312-Dup | 7/13/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-8-9.5-100412 | 10/4/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-8-9.5-012413 | 1/24/2013 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-8-9.5-012413-Dup | 1/24/2013 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | 23.5 ft | VMP-8-23.5-083010 | 8/30/2010 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-8-23.5-111910 | 11/19/2010 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-8-23.5-021011 | 2/10/2011 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-8-23.5-040711 | 4/7/2011 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-8-23.5-040711-DUP | 4/7/2011 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-8-23.5-081011 | 8/10/2011 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-8-23.5-110611 | 11/6/2011 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-8-23.5-012312 | 1/23/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-8-23.5-041012 | 4/10/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-8-23.5-071312 | 7/13/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-8-23.5-100412 | 10/4/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-8-23.5-012413 | 1/24/2013 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |

SEE LAST PAGE OF TABLE FOR NOTES

**TABLE 5**
**CUMULATIVE SUMMARY OF SOIL VAPOR ANALYTICAL DETECTIONS AND SCREENING RESULTS: VILLAGE - VOCS**

| Location | Depth | Sample ID | Sample Date | [3]Heptadecane | | | [3]Hexane, 2,2,4-trimethyl- | | | [3]Pentane, 2,2,3-trimethyl- | | | [3]Pentane, 2,3,4-trimethyl- | | | [3]Pentane, 2,4-dimethyl- | | | [3]Cyclopentane, methyl- | | | [3]Butane, 2,2,3-trimethyl- | | | [3]Hexane, 3,4-dimethyl- | | | [3]Pentane, 2,3-dimethyl- | | | [3]Isobutane | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | Result (ppbV) | Lab Quals | URS Quals | Result (ppbV) | Lab Quals | URS Quals | Result (ppbV) | Lab Quals | URS Quals | Result (ppbV) | Lab Quals | URS Quals | Result (ppbV) | Lab Quals | URS Quals | Result (ppbV) | Lab Quals | URS Quals | Result (ppbV) | Lab Quals | URS Quals | Result (ppbV) | Lab Quals | URS Quals | Result (ppbV) | Lab Quals | URS Quals | Result (ppbV) | Lab Quals | URS Quals |
| VMP-9 | 5 ft | VMP-9-5-082610 | 8/26/2010 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-9-5-111910 | 11/19/2010 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-9-5-020811 | 2/8/2011 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-9-5-040611 | 4/6/2011 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-9-5-080211 | 8/2/2011 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-9-5-110411 | 11/4/2011 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-9-5-012612 | 1/26/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-9-5-041112 | 4/11/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-9-5-071312 | 7/13/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-9-5-101012 | 10/10/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | [4]VMP-9-5-012513 | 1/25/2013 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-9-5-021513 | 2/15/2013 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | 11.5 ft | VMP-9-11.5-082610 | 8/26/2010 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-9-11.5-111910 | 11/19/2010 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-9-11.5-020911 | 2/9/2011 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-9-11.5-020911-DUP | 2/9/2011 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-9-11.5-040611 | 4/6/2011 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-9-11.5-080211 | 8/2/2011 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-9-11.5-110411 | 11/4/2011 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-9-11.5-012612 | 1/26/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-9-11.5-041112 | 4/11/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-9-11.5-071312 | 7/13/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-9-11.5-101012 | 10/10/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-9-11.5-012513 | 1/25/2013 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-9-11.5-012513-DUP | 1/25/2013 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | 25.5 ft | VMP-9-25.5-082610 | 8/26/2010 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-9-25.5-082610-DUP | 8/26/2010 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-9-25.5-111910 | 11/19/2010 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-9-25.5-020911 | 2/9/2011 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-9-25.5-040811 | 4/8/2011 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-9-25.5-080211 | 8/2/2011 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-9-25.5-110711 | 11/7/2011 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-9-25.5-110711-DUP | 11/7/2011 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-9-25.5-012612 | 1/26/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-9-25.5-041112 | 4/11/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-9-25.5-071312 | 7/13/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-9-25.5-071312-Dup | 7/13/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-9-25.5-101012 | 10/10/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-9-25.5-013013 | 1/30/2013 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | 38.5 ft | VMP-9-38.5-020911 | 2/9/2011 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-9-38.5-040811 | 4/8/2011 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-9-38.5-012612 | 1/26/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-9-38.5-041112 | 4/11/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-9-38.5-071312 | 7/13/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-9-38.5-101012 | 10/10/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-9-38.5-013013 | 1/30/2013 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| VMP-18 | 8.5 ft | VMP-18-8.5 | 6/18/2010 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-18-8.5-090710 | 9/7/2010 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-18-8.5-111910 | 11/19/2010 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-18-8.5-020711 | 2/7/2011 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-18-8.5-020711-DUP | 2/7/2011 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-18-8.5-040711 | 4/7/2011 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-18-8.5-072811 | 7/28/2011 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-18-8.5-110711 | 11/7/2011 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-18-8.5-012312 | 1/23/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-18-8.5-041012 | 4/10/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-18-8.5-071212 | 7/12/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-18-8.5-100912 | 10/9/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-18-8.5-012313 | 1/23/2013 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| VMP-19 | 5 ft | VMP-19-5 | 6/18/2010 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-19-5-090110 | 9/1/2010 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-19-5-111510 | 11/15/2010 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-19-5-020411 | 2/4/2011 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-19-5-040711 | 4/7/2011 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-19-5-080911 | 8/9/2011 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-19-5-080911-DUP | 8/9/2011 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-19-5-110811 | 11/8/2011 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-19-5-012612 | 1/26/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-19-5-041012 | 4/10/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-19-5-071112 | 7/11/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-19-5-100912 | 10/9/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-19-5-013113 | 1/31/2013 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |

SEE LAST PAGE OF TABLE FOR NOTES

**TABLE 5**
**CUMULATIVE SUMMARY OF SOIL VAPOR ANALYTICAL DETECTIONS AND SCREENING RESULTS: VILLAGE - VOCS**

| Location | Depth | Sample ID | Sample Date | [3]Heptadecane | | | [3]Hexane, 2,2,4-trimethyl- | | | [3]Pentane, 2,2,3-trimethyl- | | | [3]Pentane, 2,3,4-trimethyl- | | | [3]Pentane, 2,4-dimethyl- | | | [3]Cyclopentane, methyl- | | | [3]Butane, 2,2,3-trimethyl- | | | [3]Hexane, 3,4-dimethyl- | | | [3]Pentane, 2,3-dimethyl- | | | [3]Isobutane | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | Result (ppbV) | Lab Quals | URS Quals | Result (ppbV) | Lab Quals | URS Quals | Result (ppbV) | Lab Quals | URS Quals | Result (ppbV) | Lab Quals | URS Quals | Result (ppbV) | Lab Quals | URS Quals | Result (ppbV) | Lab Quals | URS Quals | Result (ppbV) | Lab Quals | URS Quals | Result (ppbV) | Lab Quals | URS Quals | Result (ppbV) | Lab Quals | URS Quals | Result (ppbV) | Lab Quals | URS Quals |
| VMP-20 | 5 ft | VMP-20-5-031411 | 3/14/2011 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-20-5-041511 | 4/15/2011 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-20-5-072511 | 7/25/2011 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-20-5-110111 | 11/1/2011 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-20-5-012312 | 1/23/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-20-5-041012 | 4/10/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-20-5-071112 | 7/11/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-20-5-073112 | 7/31/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-20-5-100412 | 10/4/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-20-5-020713 | 2/7/2013 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | 10 ft | VMP-20-10-031411 | 3/14/2011 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-20-10-041511 | 4/15/2011 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-20-10-072511 | 7/25/2011 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-20-10-110111 | 11/1/2011 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-20-10-012312 | 1/23/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-20-10-041012 | 4/10/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-20-10-071112 | 7/11/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-20-10-100412 | 10/4/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-20-10-012213 | 1/22/2013 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | 25 ft | VMP-20-25-031411 | 3/14/2011 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-20-25-041511 | 4/15/2011 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-20-25-072611 | 7/26/2011 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-20-25-110511 | 11/5/2011 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-20-25-012312 | 1/23/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-20-25-041012 | 4/10/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-20-25-041012-Dup | 4/10/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-20-25-071112 | 7/11/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-20-25-100412 | 10/4/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-20-25-012213 | 1/22/2013 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | 39.5 ft | VMP-20-39.5-100412 | 10/4/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-20-39.5-012313 | 1/23/2013 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| VMP-21 | 5 ft | VMP-21-5-020911 | 2/9/2011 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-21-5-020911-DUP | 2/9/2011 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-21-5-041311 | 4/13/2011 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-21-5-072511 | 7/25/2011 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-21-5-110111 | 11/1/2011 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-21-5-012312 | 1/23/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-21-5-012312-DUP | 1/23/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-21-5-042412 | 4/24/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-21-5-071012 | 7/10/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-21-5-100412 | 10/4/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-21-5-020613 | 2/6/2013 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | 10 ft | VMP-21-10-021011 | 2/10/2011 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-21-10-041311 | 4/13/2011 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-21-10-072511 | 7/25/2011 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-21-10-110111 | 11/1/2011 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-21-10-012312 | 1/23/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-21-10-040912 | 4/9/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-21-10-071012 | 7/10/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-21-10-100412 | 10/4/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-21-10-020513 | 2/5/2013 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-21-10-020513-DUP | 2/5/2013 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | 25 ft | VMP-21-25-021011 | 2/10/2011 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-21-25-041411 | 4/14/2011 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-21-25-041411-DUP | 4/14/2011 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-21-25-072611 | 7/26/2011 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-21-25-110511 | 11/5/2011 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-21-25-012412 | 1/24/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-21-25-040912 | 4/9/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-21-25-071112 | 7/11/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-21-25-100412 | 10/4/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-21-25-020513 | 2/5/2013 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-21-25-020513-DUP | 2/5/2013 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | 33 ft | VMP-21-33-021011 | 2/10/2011 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-21-33-041411 | 4/14/2011 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-21-33-110511 | 11/5/2011 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-21-33-012412 | 1/24/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-21-33-042412 | 4/24/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-21-33-071112 | 7/11/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-21-33-100412 | 10/4/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-21-33-020513 | 2/5/2013 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |

**TABLE 5**
**CUMULATIVE SUMMARY OF SOIL VAPOR ANALYTICAL DETECTIONS AND SCREENING RESULTS: VILLAGE - VOCS**

| Location | Depth | Sample ID | Sample Date | [3]Heptadecane | | | [3]Hexane, 2,2,4-trimethyl- | | | [3]Pentane, 2,2,3-trimethyl- | | | [3]Pentane, 2,3,4-trimethyl- | | | [3]Pentane, 2,4-dimethyl- | | | [3]Cyclopentane, methyl- | | | [3]Butane, 2,2,3-trimethyl- | | | [3]Hexane, 3,4-dimethyl- | | | [3]Pentane, 2,3-dimethyl- | | | [3]Isobutane | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | Result (ppbV) | Lab Quals | URS Quals | Result (ppbV) | Lab Quals | URS Quals | Result (ppbV) | Lab Quals | URS Quals | Result (ppbV) | Lab Quals | URS Quals | Result (ppbV) | Lab Quals | URS Quals | Result (ppbV) | Lab Quals | URS Quals | Result (ppbV) | Lab Quals | URS Quals | Result (ppbV) | Lab Quals | URS Quals | Result (ppbV) | Lab Quals | URS Quals | Result (ppbV) | Lab Quals | URS Quals |
| VMP-22 | 5 ft | VMP-22-5-021111 | 2/11/2011 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-22-5-041811 | 4/18/2011 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-22-5-072611 | 7/26/2011 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-22-5-110111 | 11/1/2011 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-22-5-012412 | 1/24/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-22-5-040912 | 4/9/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-22-5-070912 | 7/9/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-22-5-100312 | 10/3/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-22-5-100312-Dup | 10/3/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-22-5-012413 | 1/24/2013 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | 10 ft | VMP-22-10-021111 | 2/11/2011 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-22-10-041811 | 4/18/2011 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-22-10-072611 | 7/26/2011 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-22-10-072611-DUP | 7/26/2011 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-22-10-110211 | 11/2/2011 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-22-10-012412 | 1/24/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-22-10-040912 | 4/9/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-22-10-070912 | 7/9/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-22-10-070912-Dup | 7/9/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-22-10-100312 | 10/3/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-22-10-012413 | 1/24/2013 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | 18 ft | VMP-22-18-021111 | 2/11/2011 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-22-18-041811 | 4/18/2011 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-22-18-072611 | 7/26/2011 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-22-18-110511 | 11/5/2011 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-22-18-012412 | 1/24/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-22-18-040912 | 4/9/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-22-18-070912 | 7/9/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-22-18-100412 | 10/4/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-22-18-012413 | 1/24/2013 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | 38 ft | VMP-22-38-041811 | 4/18/2011 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-22-38-012512 | 1/25/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-22-38-040912 | 4/9/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-22-38-070912 | 7/9/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-22-38-100412 | 10/4/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-22-38-012413 | 1/24/2013 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| VMP-23 | 5 ft | VMP-23-5-021511 | 2/15/2011 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-23-5-042111 | 4/21/2011 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-23-5-072711 | 7/27/2011 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-23-5-110211 | 11/2/2011 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-23-5-012512 | 1/25/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-23-5-040912 | 4/9/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-23-5-070912 | 7/9/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-23-5-100312 | 10/3/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-23-5-012413 | 1/24/2013 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | 10 ft | VMP-23-10-021511 | 2/15/2011 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-23-10-042111 | 4/21/2011 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-23-10-072711 | 7/27/2011 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-23-10-110211 | 11/2/2011 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-23-10-012512 | 1/25/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-23-10-040912 | 4/9/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-23-10-040912-Dup | 4/9/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-23-10-070912 | 7/9/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-23-10-100312 | 10/3/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-23-10-012413 | 1/24/2013 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | 25 ft | VMP-23-25-021511 | 2/15/2011 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-23-25-042111 | 4/21/2011 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-23-25-072711 | 7/27/2011 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-23-25-110511 | 11/5/2011 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-23-25-012512 | 1/25/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-23-25-040912 | 4/9/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-23-25-071012 | 7/10/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-23-25-100312 | 10/3/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-23-25-012413 | 1/24/2013 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | 40 ft | VMP-23-40-071012 | 7/10/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-23-40-100312 | 10/3/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-23-40-012413 | 1/24/2013 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |

SEE LAST PAGE OF TABLE FOR NOTES

**TABLE 5**
**CUMULATIVE SUMMARY OF SOIL VAPOR ANALYTICAL DETECTIONS AND SCREENING RESULTS: VILLAGE - VOCS**

| Location | Depth | Sample ID | Sample Date | [3]Heptadecane | | | [3]Hexane, 2,2,4-trimethyl- | | | [3]Pentane, 2,2,3-trimethyl- | | | [3]Pentane, 2,3,4-trimethyl- | | | [3]Pentane, 2,4-dimethyl- | | | [3]Cyclopentane, methyl- | | | [3]Butane, 2,2,3-trimethyl- | | | [3]Hexane, 3,4-dimethyl- | | | [3]Pentane, 2,3-dimethyl- | | | [3]Isobutane | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | Result (ppbV) | Lab Quals | URS Quals | Result (ppbV) | Lab Quals | URS Quals | Result (ppbV) | Lab Quals | URS Quals | Result (ppbV) | Lab Quals | URS Quals | Result (ppbV) | Lab Quals | URS Quals | Result (ppbV) | Lab Quals | URS Quals | Result (ppbV) | Lab Quals | URS Quals | Result (ppbV) | Lab Quals | URS Quals | Result (ppbV) | Lab Quals | URS Quals | Result (ppbV) | Lab Quals | URS Quals |
| VMP-24 | 5 ft | VMP-24-5-021611 | 2/16/2011 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-24-5-040811 | 4/8/2011 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-24-5-072811 | 7/28/2011 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-24-5-110211 | 11/2/2011 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-24-5-110211-DUP | 11/2/2011 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-24-5-012512 | 1/25/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-24-5-040912 | 4/9/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-24-5-071212 | 7/12/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-24-5-101912 | 10/19/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-24-5-012313 | 1/23/2013 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | 10 ft | VMP-24-10-021711 | 2/17/2011 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-24-10-041111 | 4/11/2011 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-24-10-072811 | 7/28/2011 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-24-10-110211 | 11/2/2011 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-24-10-012512 | 1/25/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-24-10-041012 | 4/10/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-24-10-071212 | 7/12/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-24-10-100912 | 10/9/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-24-10-012313 | 1/23/2013 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | 22 ft | VMP-24-22-021711 | 2/17/2011 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-24-22-041111 | 4/11/2011 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-24-22-072811 | 7/28/2011 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-24-22-072811-Dup | 7/28/2011 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-24-22-110611 | 11/6/2011 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-24-22-012512 | 1/25/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-24-22-041012 | 4/10/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-24-22-071212 | 7/12/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-24-22-100912 | 10/9/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-24-22-012313 | 1/23/2013 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | 34 ft | VMP-24-34-021711 | 2/17/2011 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-24-34-041111 | 4/11/2011 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-24-34-072811 | 7/28/2011 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-24-34-110611 | 11/6/2011 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-24-34-012512 | 1/25/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-24-34-041012 | 4/10/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-24-34-071212 | 7/12/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-24-34-100912 | 10/9/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-24-34-012313 | 1/23/2013 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| VMP-31 | 5 ft | VMP-31-5-042512 | 4/25/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-31-5-072012 | 7/20/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-31-5-102612 | 10/26/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-31-5-021113 | 2/11/2013 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | 10 ft | VMP-31-10-042512 | 4/25/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-31-10-072612 | 7/26/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-31-10-102612 | 10/26/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-31-10-021313 | 2/13/2013 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | 20 ft | VMP-31-20-101912 | 10/19/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-31-20-021113 | 2/11/2013 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | 30 ft | VMP-31-30-042512 | 4/25/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-31-30-042512-Dup | 4/25/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-31-30-072012 | 7/20/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-31-30-101912 | 10/19/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-31-30-021113 | 2/11/2013 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| VMP-32 | 5 ft | VMP-32-5-042512 | 4/25/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-32-5-072012 | 7/20/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-32-5-101812 | 10/18/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-32-5-020513 | 2/5/2013 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | 10 ft | VMP-32-10-041612 | 4/16/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-32-10-072012 | 7/20/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-32-10-101812 | 10/18/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-32-10-020513 | 2/5/2013 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | 20 ft | VMP-32-20-041612 | 4/16/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-32-20-072012 | 7/20/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-32-20-101812 | 10/18/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-32-20-020513 | 2/5/2013 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | 30 ft | VMP-32-30-041612 | 4/16/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-32-30-072012 | 7/20/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-32-30-101812 | 10/18/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-32-30-020513 | 2/5/2013 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |

SEE LAST PAGE OF TABLE FOR NOTES

**TABLE 5**
**CUMULATIVE SUMMARY OF SOIL VAPOR ANALYTICAL DETECTIONS AND SCREENING RESULTS: VILLAGE - VOCS**

| Location | Depth | Sample ID | Sample Date | [3]Heptadecane | | | [3]Hexane, 2,2,4-trimethyl- | | | [3]Pentane, 2,2,3-trimethyl- | | | [3]Pentane, 2,3,4-trimethyl- | | | [3]Pentane, 2,4-dimethyl- | | | [3]Cyclopentane, methyl- | | | [3]Butane, 2,2,3-trimethyl- | | | [3]Hexane, 3,4-dimethyl- | | | [3]Pentane, 2,3-dimethyl- | | | [3]Isobutane | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | Result (ppbV) | Lab Quals | URS Quals | Result (ppbV) | Lab Quals | URS Quals | Result (ppbV) | Lab Quals | URS Quals | Result (ppbV) | Lab Quals | URS Quals | Result (ppbV) | Lab Quals | URS Quals | Result (ppbV) | Lab Quals | URS Quals | Result (ppbV) | Lab Quals | URS Quals | Result (ppbV) | Lab Quals | URS Quals | Result (ppbV) | Lab Quals | URS Quals | Result (ppbV) | Lab Quals | URS Quals |
| VMP-42 | 10 ft | VMP-42-10-041812 | 4/18/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-42-10-041812-Dup | 4/18/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-42-20-041812 | 4/18/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-42-10-071912 | 7/19/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-42-10-101212 | 10/12/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-42-10-013113 | 1/31/2013 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | 20 ft | VMP-42-20-071912 | 7/19/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-42-20-101212 | 10/12/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-42-20-101212-Dup | 10/12/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-42-20-013113 | 1/31/2013 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | 30 ft | VMP-42-30-041912 | 4/19/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-42-30-071912 | 7/19/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-42-30-101212 | 10/12/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-42-30-101212-Dup | 10/12/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-42-30-013113 | 1/31/2013 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| VMP-43 | 10 ft | VMP-43-10-041612 | 4/16/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-43-10-071912 | 7/19/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-43-10-101612 | 10/16/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | 20 ft | VMP-43-20-041612 | 4/16/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-43-20-071912 | 7/19/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-43-20-101812 | 10/18/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-43-20-012413 | 1/24/2013 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | 30 ft | VMP-43-30-042312 | 4/23/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-43-30-071912 | 7/19/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-43-30-101812 | 10/18/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-43-30-012413 | 1/24/2013 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| VMP-44 | 10 ft | VMP-44-10-041912 | 4/19/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-44-10-072012 | 7/20/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-44-10-081012 | 8/10/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-44-10-101212 | 10/12/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-44-10-012513 | 1/25/2013 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | 20 ft | VMP-44-20-041912 | 4/19/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-44-20-072512 | 7/25/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-44-20-101212 | 10/12/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-44-20-012513 | 1/25/2013 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | 30 ft | VMP-44-30-041912 | 4/19/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-44-30-072512 | 7/25/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-44-30-072512-Dup | 7/25/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-44-30-101512 | 10/15/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-44-30-101512-Dup | 10/15/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-44-30-012513 | 1/25/2013 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| VMP-45 | 10 ft | VMP-45-10-041912 | 4/19/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-45-10-071912 | 7/19/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-45-10-101512 | 10/15/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-45-10-013013 | 1/30/2013 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | 20 ft | VMP-45-20-041912 | 4/19/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-45-20-071912 | 7/19/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-45-20-101512 | 10/15/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-45-20-013013 | 1/30/2013 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | 30 ft | VMP-45-30-041912 | 4/19/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-45-30-071912 | 7/19/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-45-30-101512 | 10/15/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-45-30-101512-Dup | 10/15/2012 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-45-30-013013 | 1/30/2013 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |

SEE LAST PAGE OF TABLE FOR NOTES

**TABLE 5**
**CUMULATIVE SUMMARY OF SOIL VAPOR ANALYTICAL DETECTIONS AND SCREENING RESULTS: VILLAGE - VOCS**

| Location | Depth | Sample ID | Sample Date | [3]Heptadecane | | | [3]Hexane, 2,2,4-trimethyl- | | | [3]Pentane, 2,2,3-trimethyl- | | | [3]Pentane, 2,3,4-trimethyl- | | | [3]Pentane, 2,4-dimethyl- | | | [3]Cyclopentane, methyl- | | | [3]Butane, 2,2,3-trimethyl- | | | [3]Hexane, 3,4-dimethyl- | | | [3]Pentane, 2,3-dimethyl- | | | [3]Isobutane | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | Result (ppbV) | Lab Quals | URS Quals | Result (ppbV) | Lab Quals | URS Quals | Result (ppbV) | Lab Quals | URS Quals | Result (ppbV) | Lab Quals | URS Quals | Result (ppbV) | Lab Quals | URS Quals | Result (ppbV) | Lab Quals | URS Quals | Result (ppbV) | Lab Quals | URS Quals | Result (ppbV) | Lab Quals | URS Quals | Result (ppbV) | Lab Quals | URS Quals | Result (ppbV) | Lab Quals | URS Quals |
| VMP-47 | 5 ft | VMP-47-5-012113 | 1/21/2013 | | | | 19 | | | | | | 39 | | | 13 | | | | | | | | | | | | | | | | |
| | | [4]VMP-47-5-012313-R | 1/23/2013 | | | | | | | | | | | | | | | | | | | | | 310,000 | | | 370,000 | | | 470,000 | | |
| | 10 ft | VMP-47-10-012113 | 1/21/2013 | 7.7 | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | [4]VMP-47-10-012313-R | 1/23/2013 | | | | | | | | | | | | | 27,000 | | | | | | | | | | | 42,000 | | | 56,000 | | |
| | 20 ft | VMP-47-20-012113 | 1/21/2013 | | | | | | | | | | | | | | | | | | | | | | | | 110,000 | | | 150,000 | | |
| | | [4]VMP-47-20-012313-R | 1/23/2013 | | | | | | | | | | | | | | | | | | | | | | | | 300,000 | | | 360,000 | | |
| | 30 ft | VMP-47-30-012113 | 1/21/2013 | | | | | | | | | | | | | | | | | | | 63,000 | | | | | 97,000 | | | 130,000 | | |
| | | [4]VMP-47-30-012313-R | 1/23/2013 | | | | | | | | | | | | | | | | | | | | | | | | 370,000 | | | 460,000 | | |
| VMP-48 | 5 ft | VMP-48-5-020113 | 2/1/2013 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | 10 ft | VMP-48-10-020113 | 2/1/2013 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | 20 ft | VMP-48-20-020113 | 2/1/2013 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | 30 ft | VMP-48-30-020113 | 2/1/2013 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-48-30-020113-DUP | 2/1/2013 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| VMP-49 | 5 ft | VMP-49-5-020113 | 2/1/2013 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | 10 ft | VMP-49-10-020113 | 2/1/2013 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | 20 ft | VMP-49-20-020113 | 2/1/2013 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | 30 ft | VMP-49-30-020113 | 2/1/2013 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| VMP-50 | 5 ft | VMP-50-5-020113 | 2/1/2013 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | 10 ft | VMP-50-10-020113 | 2/1/2013 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | 20 ft | VMP-50-20-020113 | 2/1/2013 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | 30 ft | VMP-50-30-020113 | 2/1/2013 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| VMP-51 | 5 ft | VMP-51-5-020113 | 2/1/2013 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | 10 ft | VMP-51-10-020113 | 2/1/2013 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | 20 ft | VMP-51-20-021513-R | 2/15/2013 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | 30 ft | VMP-51-30-020413 | 2/4/2013 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-51-30-020413-DUP | 2/4/2013 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| VMP-52 | 5 ft | VMP-52-5-020413 | 2/4/2013 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | 10 ft | VMP-52-10-020413 | 2/4/2013 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | 20 ft | VMP-52-20-020413 | 2/4/2013 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-52-20-020413-DUP | 2/4/2013 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | 30 ft | VMP-52-30-020413 | 2/4/2013 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| VMP-53 | 5 ft | VMP-53-5-020513 | 2/5/2013 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | 10 ft | VMP-53-10-020513 | 2/5/2013 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-53-10-020513-DUP | 2/5/2013 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | 20 ft | VMP-53-20-020513 | 2/5/2013 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | 30 ft | VMP-53-30-020513 | 2/5/2013 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| VMP-54 | 5 ft | VMP-54-5-020613 | 2/6/2013 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | 10 ft | VMP-54-10-020613 | 2/6/2013 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | 20 ft | VMP-54-20-020613 | 2/6/2013 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-54-20-020613-DUP | 2/6/2013 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | 30 ft | VMP-54-30-020613 | 2/6/2013 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | VMP-54-30-020613-DUP | 2/6/2013 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |

SEE LAST PAGE OF TABLE FOR NOTES

**TABLE 5**
**CUMULATIVE SUMMARY OF SOIL VAPOR ANALYTICAL DETECTIONS AND SCREENING RESULTS: VILLAGE - VOCS**

| Location | Depth | Sample ID | Sample Date | [3]Pentane | | | [3]Pentane, 2-methyl- | | | [3]Pentane, 3-methyl- | | | [3]Unknown | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | Result (ppbV) | Lab Quals | URS Quals | Result (ppbV) | Lab Quals | URS Quals | Result (ppbV) | Lab Quals | URS Quals | Result (ppbV) | Lab Quals | URS Quals |
| VMP-1 | 5 ft | VMP-1-5-082510 | 8/25/2010 | | | | | | | | | | | | |
| | | VMP-1-5-111710 | 11/17/2010 | | | | | | | | | | | | |
| | | VMP-1-5-020411 | 2/4/2011 | | | | | | | | | | | | |
| | | VMP-1-5-041211 | 4/12/2011 | | | | | | | | | | | | |
| | | VMP-1-5-080111 | 8/1/2011 | | | | | | | | | | | | |
| | | VMP-1-5-110311 | 11/3/2011 | | | | | | | | | | | | |
| | | VMP-1-5-013012 | 1/30/2012 | | | | | | | | | | | | |
| | | VMP-1-5-041312 | 4/13/2012 | | | | | | | | | | | | |
| | | VMP-1-5-071612 | 7/16/2012 | | | | | | | | | | | | |
| | | VMP-1-5-101112 | 10/11/2012 | | | | | | | | | | | | |
| | | [4]VMP-1-5-012113 | 1/21/2013 | 1,900 | | | | | | 1800 | | | | | |
| | | [4]VMP-1-5-012313-R | 1/23/2013 | 340,000 | | | 320000 | | | | | | | | |
| | 8.5 ft | VMP-1-8.5-082510 | 8/25/2010 | | | | | | | | | | | | |
| | | VMP-1-8.5-111710 | 11/17/2010 | | | | | | | | | | | | |
| | | VMP-1-8.5-111710-Dup | 11/17/2010 | | | | | | | | | | | | |
| | | VMP-1-8.5-020411 | 2/4/2011 | | | | | | | | | | | | |
| | | VMP-1-8.5-041211 | 4/12/2011 | | | | | | | | | | | | |
| | | VMP-1-8.5-080111 | 8/1/2011 | | | | | | | | | | | | |
| | | VMP-1-8.5-080111-Dup | 8/1/2011 | | | | | | | | | | | | |
| | | VMP-1-8.5-110311 | 11/3/2011 | | | | | | | | | | | | |
| | | VMP-1-8.5-013012 | 1/30/2012 | | | | | | | | | | | | |
| | | VMP-1-8.5-041612 | 4/16/2012 | | | | | | | | | | | | |
| | | VMP-1-8.5-041612-Dup | 4/16/2012 | | | | | | | | | | | | |
| | | VMP-1-8.5-071612 | 7/16/2012 | | | | | | | | | | | | |
| | | VMP-1-8.5-101112 | 10/11/2012 | | | | | | | | | | | | |
| | | [4]VMP-1-8.5-012113 | 1/21/2013 | 4,600 | | | 4400 | | | 3000 | | | | | |
| | | [4]VMP-1-8.5-012313-R | 1/23/2013 | 15,000 | | | 13000 | | | | | | | | |
| | 23.5 ft | VMP - 1 - 23.5 - 083010 | 8/30/2010 | | | | | | | | | | | | |
| | | VMP-1-23.5-111810 | 11/17/2010 | | | | | | | | | | | | |
| | | VMP-1-23.5-020411 | 2/4/2011 | | | | | | | | | | | | |
| | | VMP-1-23.5-041211 | 4/12/2011 | | | | | | | | | | | | |
| | | VMP-1-23.5-041211-DUP | 4/12/2011 | | | | | | | | | | | | |
| | | VMP-1-23.5-080111 | 8/1/2011 | | | | | | | | | | | | |
| | | VMP-1-23.5-110611 | 11/6/2011 | | | | | | | | | | | | |
| | | VMP-1-23.5-013112 | 1/31/2012 | | | | | | | | | | | | |
| | | VMP-1-23.5-041612 | 4/16/2012 | | | | | | | | | | | | |
| | | VMP-1-23.5-071612 | 7/16/2012 | | | | | | | | | | | | |
| | | VMP-1-23.5-102412 | 10/24/2012 | | | | | | | | | | | | |
| | | [4]VMP-1-23.5-012113 | 1/21/2013 | | | | | | | | | | | | |
| | | [4]VMP-1-23.5-012313-R | 1/23/2013 | 1,600,000 | | | 1800000 | | | 870000 | | | | | |
| | 38.5 ft | VMP-1-38.5-073112 | 7/31/2012 | | | | | | | | | | | | |
| | | VMP-1-38.5-102612 | 10/26/2012 | | | | | | | | | | | | |
| | | [4]VMP-1-38.5-012113 | 1/21/2013 | 680 | | J | 1200 | | J | 600 | | J | | | |
| | | [4]VMP-1-38.5-012313-R | 1/23/2013 | 1,000,000 | | | (ppbV) | | | | | | | | |
| VMP-2 | 5 ft | VMP - 2 - 5 - 083110 | 8/31/2010 | | | | | | | | | | | | |
| | | VMP-2-5-111610 | 11/16/2010 | | | | | | | | | | | | |
| | | VMP-2-5-020411 | 2/4/2011 | | | | | | | | | | | | |
| | | VMP-2-5-041311 | 4/13/2011 | | | | | | | | | | | | |
| | | VMP-2-5-080211 | 8/2/2011 | | | | | | | | | | | | |
| | | VMP-2-5-110711 | 11/7/2011 | | | | | | | | | | | | |
| | | VMP-2-5-012512 | 1/25/2012 | | | | | | | | | | | | |
| | | VMP-2-5-042512 | 4/25/2012 | | | | | | | | | | | | |
| | | VMP-2-5-071612 | 7/16/2012 | | | | | | | | | | | | |
| | | VMP-2-5-102412 | 10/24/2012 | | | | | | | | | | | | |
| | | VMP-2-5-013113 | 1/31/2013 | | | | | | | | | | | | |
| | 8.5 ft | VMP-2-8.5-083110 | 8/31/2010 | | | | | | | | | | | | |
| | | VMP-2-8.5-111610 | 11/16/2010 | | | | | | | | | | | | |
| | | VMP-2-8.5-020411 | 2/4/2011 | | | | | | | | | | | | |
| | | VMP-2-8.5-041311 | 4/13/2011 | | | | | | | | | | | | |
| | | VMP-2-8.5-080211 | 8/2/2011 | | | | | | | | | | | | |
| | | VMP-2-8.5-110711 | 11/7/2011 | | | | | | | | | | | | |
| | | VMP-2-8.5-012612 | 1/26/2012 | | | | | | | | | | | | |
| | | VMP-2-8.5-012612-DUP | 1/26/2012 | | | | | | | | | | | | |
| | | VMP-2-8.5-041612 | 4/16/2012 | | | | | | | | | | | | |
| | | VMP-2-8.5-041612-Dup | 4/16/2012 | | | | | | | | | | | | |
| | | VMP-2-8.5-071612 | 7/16/2012 | | | | | | | | | | | | |
| | | VMP-2-8.5-071612-Dup | 7/16/2012 | | | | | | | | | | | | |
| | | VMP-2-8.5-102312 | 10/23/2012 | | | | | | | | | | | | |
| | | VMP-2-8.5-020513 | 2/5/2013 | | | | | | | | | | | | |
| | 22 ft | VMP-2-22-083110 | 8/31/2010 | | | | | | | | | | | | |
| | | VMP-2-22-111610 | 11/16/2010 | | | | | | | | | | | | |
| | | VMP-2-22-020411 | 2/4/2011 | | | | | | | | | | | | |
| | | VMP-2-22-041311 | 4/13/2011 | | | | | | | | | | | | |
| | | VMP-2-22-080211 | 8/2/2011 | | | | | | | | | | | | |
| | | VMP-2-22-110711 | 11/7/2011 | | | | | | | | | | | | |
| | | VMP-2-22-012612 | 1/26/2012 | | | | | | | | | | | | |
| | | VMP-2-22-042712 | 4/27/2012 | | | | | | | | | | | | |
| | | VMP-2-22-071612 | 7/16/2012 | | | | | | | | | | | | |
| | | VMP-2-22-102312 | 10/23/2012 | | | | | | | | | | | | |
| | | VMP-2-22-013113 | 1/31/2013 | | | | | | | | | | | | |
| | 42 ft | VMP-2-42-013113 | 1/31/2013 | | | | | | | | | | | | |

**TABLE 5**
**CUMULATIVE SUMMARY OF SOIL VAPOR ANALYTICAL DETECTIONS AND SCREENING RESULTS: VILLAGE - VOCS**

| Location | Depth | Sample ID | Sample Date | [3]Pentane | | | [3]Pentane, 2-methyl- | | | [3]Pentane, 3-methyl- | | | [3]Unknown | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | Result (ppbV) | Lab Quals | URS Quals | Result (ppbV) | Lab Quals | URS Quals | Result (ppbV) | Lab Quals | URS Quals | Result (ppbV) | Lab Quals | URS Quals |
| VMP-3 | 5 ft | VMP-3-5-090910 | 9/9/2010 | | | | | | | | | | | | |
| | | VMP-3-5-112210 | 11/22/2010 | | | | | | | | | | | | |
| | | VMP-3-5-020911 | 2/9/2011 | | | | | | | | | | | | |
| | | VMP-3-5-041411 | 4/14/2011 | | | | | | | | | | | | |
| | | VMP-3-5-080211 | 8/2/2011 | | | | | | | | | | | | |
| | | VMP-3-5-110811 | 11/8/2011 | | | | | | | | | | | | |
| | | VMP-3-5-110811-DUP | 11/8/2011 | | | | | | | | | | | | |
| | | VMP-3-5-012712 | 1/27/2012 | | | | | | | | | | | | |
| | | VMP-3-5-041912 | 4/19/2012 | | | | | | | | | | | | |
| | | VMP-3-5-072712 | 7/27/2012 | | | | | | | | | | | | |
| | 10 ft | VMP-3-10 | 6/21/2010 | | | | | | | | | | | | |
| | | VMP 3-10-091010 | 9/10/2010 | | | | | | | | | | | | |
| | | VMP-3-10-092010 | 9/20/2010 | | | | | | | | | | | | |
| | | VMP-3-10-112210 | 11/22/2010 | | | | | | | | | | | | |
| | | VMP-3-10-112210-Dup | 11/22/2010 | | | | | | | | | | | | |
| | | VMP-3-10-020811 | 2/8/2011 | | | | | | | | | | | | |
| | | VMP-3-10-041311 | 4/13/2011 | | | | | | | | | | | | |
| | | VMP-3-10-080311 | 8/3/2011 | | | | | | | | | | | | |
| | | VMP-3-10-110811 | 11/8/2011 | | | | | | | | | | | | |
| | | VMP-3-10-012712 | 1/27/2012 | | | | | | | | | | | | |
| | | VMP-3-10-042012 | 4/20/2012 | | | | | | | | | | | | |
| | | VMP-3-10-072312 | 7/23/2012 | | | | | | | | | | | | |
| | | VMP-3-10-101812 | 10/18/2012 | | | | | | | | | | | | |
| | | VMP-3-10-020613 | 2/6/2013 | | | | | | | | | | | | |
| | 22 ft | VMP-3-22-092010 | 9/20/2010 | | | | | | | | | | | | |
| | | VMP-3-22-112210 | 11/22/2010 | | | | | | | | | | | | |
| | | VMP-3-22-020811 | 2/8/2011 | | | | | | | | | | | | |
| | | VMP-3-22-041511 | 4/15/2011 | | | | | | | | | | | | |
| | | VMP-3-22-080611 | 8/6/2011 | | | | | | | | | | | | |
| | | VMP-3-22-110811 | 11/8/2011 | | | | | | | | | | | | |
| | | VMP-3-22-013012 | 1/30/2012 | | | | | | | | | | | | |
| | | VMP-3-22-042012 | 4/20/2012 | | | | | | | | | | | | |
| | | VMP-3-22-072312 | 7/23/2012 | | | | | | | | | | | | |
| | | VMP-3-22-101812 | 10/18/2012 | | | | | | | | | | | | |
| | | VMP-3-22-020613 | 2/6/2013 | | | | | | | | | | | | |
| | 31.5 ft | VMP-3-31.5-090910 | 9/9/2010 | | | | | | | | | | | | |
| | | VMP-3-31.5-112210 | 11/22/2010 | | | | | | | | | | | | |
| | | VMP-3-31.5-020911 | 2/9/2011 | | | | | | | | | | | | |
| | | VMP-3-31.5-041411 | 4/14/2011 | | | | | | | | | | | | |
| | | VMP-3-31.5-041411-DUP | 4/14/2011 | | | | | | | | | | | | |
| | | VMP-3-31.5-080211 | 8/2/2011 | | | | | | | | | | | | |
| | | VMP-3-31.5-080211-Dup | 8/2/2011 | | | | | | | | | | | | |
| | | VMP-3-31.5-110811 | 11/8/2011 | | | | | | | | | | | | |
| | | VMP-3-31.5-012712 | 1/27/2012 | | | | | | | | | | | | |
| | | VMP-3-31.5-041912 | 4/19/2012 | | | | | | | | | | | | |
| | | VMP-3-31.5-041912-Dup | 4/19/2012 | | | | | | | | | | | | |
| | | VMP-3-31.5-072312 | 7/23/2012 | | | | | | | | | | | | |
| | | VMP-3-31.5-101912 | 10/19/2012 | | | | | | | | | | | | |
| | | VMP-3-31.5-020713 | 2/7/2013 | | | | | | | | | | | | |
| | 39.5 ft | VMP-3-39-101912 | 10/19/2012 | | | | | | | | | | | | |
| | | VMP-3-39-021213 | 2/12/2013 | | | | | | | | | | | | |
| VMP-4 | 5 ft | VMP-4-5-082510 | 8/25/2010 | | | | | | | | | | | | |
| | | VMP-4-5-112210 | 11/22/2010 | | | | | | | | | | | | |
| | | VMP-4-5-021411 | 2/14/2011 | | | | | | | | | | | | |
| | | VMP-4-5-041911 | 4/19/2011 | | | | | | | | | | | | |
| | | VMP-4-5-080311 | 8/3/2011 | | | | | | | | | | | | |
| | | VMP-4-5-110911 | 11/9/2011 | | | | | | | | | | | | |
| | | VMP-4-5-013012 | 1/30/2012 | | | | | | | | | | | | |
| | | VMP-4-5-042512 | 4/25/2012 | | | | | | | | | | | | |
| | | VMP-4-5-072512 | 7/25/2012 | | | | | | | | | | | | |
| | | VMP-4-5-101812 | 10/18/2012 | | | | | | | | | | | | |
| | | VMP-4-5-020713 | 2/7/2013 | | | | | | | | | | | | |
| | 12 ft | VMP-4-12-082510 | 8/25/2010 | | | | | | | | | | | | |
| | | VMP-4-12-112310 | 11/23/2010 | | | | | | | | | | | | |
| | | VMP-4-12-021411 | 2/14/2011 | | | | | | | | | | | | |
| | | VMP-4-12-041911 | 4/19/2011 | | | | | | | | | | | | |
| | | VMP-4-12-080311 | 8/3/2011 | | | | | | | | | | | | |
| | | VMP-4-12-080311-Dup | 8/3/2011 | | | | | | | | | | | | |
| | | VMP-4-12-110911 | 11/9/2011 | | | | | | | | | | | | |
| | | VMP-4-12-013012 | 1/30/2012 | | | | | | | | | | | | |
| | | VMP-4-12-041812 | 4/18/2012 | | | | | | | | | | | | |
| | | VMP-4-12-072312 | 7/23/2012 | | | | | | | | | | | | |
| | | VMP-4-12-101812 | 10/18/2012 | | | | | | | | | | | | |
| | | VMP-4-12-101812-Dup | 10/18/2012 | | | | | | | | | | | | |
| | | VMP-4-12-020713 | 2/7/2013 | | | | | | | | | | | | |
| | | VMP-4-12-020713-DUP | 2/7/2013 | | | | | | | | | | | | |
| | 23.5 ft | VMP - 4 - 23.5 - 083110 | 8/31/2010 | | | | | | | | | | | | |
| | | VMP-4-23.5-112310 | 11/23/2010 | | | | | | | | | | | | |
| | | VMP-4-23.5-021411 | 2/14/2011 | | | | | | | | | | | | |
| | | VMP-4-23.5-042011 | 4/20/2011 | | | | | | | | | | | | |
| | | VMP-4-23.5-042011-DUP | 4/20/2011 | | | | | | | | | | | | |
| | | VMP-4-23.5-080611 | 8/6/2011 | | | | | | | | | | | | |
| | | VMP-4-23.5-110911 | 11/9/2011 | | | | | | | | | | | | |
| | | VMP-4-23.5-013012 | 1/30/2012 | | | | | | | | | | | | |
| | | VMP-4-23.5-013012-DUP | 1/30/2012 | | | | | | | | | | | | |
| | | VMP-4-23.5-041912 | 4/19/2012 | | | | | | | | | | | | |
| | | VMP-4-23.5-072312 | 7/23/2012 | | | | | | | | | | | | |
| | | VMP-4-23.5-101812 | 10/18/2012 | | | | | | | | | | | | |
| | | VMP-4-23.5-020713 | 2/7/2013 | | | | | | | | | | | | |
| | 39 ft | VMP-4-39-042111 | 4/21/2011 | | | | | | | | | | | | |
| | | VMP-4-39-041912 | 4/19/2012 | | | | | | | | | | | | |
| | | VMP-4-39-072312 | 7/23/2012 | | | | | | | | | | | | |
| | | VMP-4-39-101812 | 10/18/2012 | | | | | | | | | | | | |
| | | VMP-4-39-101812-Dup | 10/18/2012 | | | | | | | | | | | | |
| | | VMP-4-39-020713 | 2/7/2013 | | | | | | | | | | | | |

SEE LAST PAGE OF TABLE FOR NOTES

**TABLE 5**
**CUMULATIVE SUMMARY OF SOIL VAPOR ANALYTICAL DETECTIONS AND SCREENING RESULTS: VILLAGE - VOCS**

| Location | Depth | Sample ID | Sample Date | [3]Pentane | | | [3]Pentane, 2-methyl- | | | [3]Pentane, 3-methyl- | | | [3]Unknown | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | Result (ppbV) | Lab Quals | URS Quals | Result (ppbV) | Lab Quals | URS Quals | Result (ppbV) | Lab Quals | URS Quals | Result (ppbV) | Lab Quals | URS Quals |
| VMP-5 | 5 ft | VMP-5-5-090910 | 9/9/2010 | | | | | | | | | | | | |
| | | VMP-5-5-112210 | 11/22/2010 | | | | | | | | | | | | |
| | | VMP-5-5-021611 | 2/16/2011 | | | | | | | | | | | | |
| | | VMP-5-5-042111 | 4/21/2011 | | | | | | | | | | | | |
| | | VMP-5-5-080511 | 8/5/2011 | | | | | | | | | | | | |
| | | VMP-5-5-111111 | 11/11/2011 | | | | | | | | | | | | |
| | | VMP-5-5-013012 | 1/30/2012 | | | | | | | | | | | | |
| | | VMP-5-5-041112 | 4/11/2012 | | | | | | | | | | | | |
| | | VMP-5-5-071312 | 7/13/2012 | | | | | | | | | | | | |
| | | VMP-5-5-101212 | 10/12/2012 | | | | | | | | | | | | |
| | | VMP-5-5-012513 | 1/25/2013 | | | | | | | | | | | | |
| | 12.5 ft | VMP-5-12.5-090910 | 9/9/2010 | | | | | | | | | | | | |
| | | VMP-5-12.5-112310 | 11/23/2010 | | | | | | | | | | | | |
| | | VMP-5-12.5-021611 | 2/16/2011 | | | | | | | | | | | | |
| | | VMP-5-12.5-042111 | 4/21/2011 | | | | | | | | | | | | |
| | | VMP-5-12.5-080611 | 8/6/2011 | | | | | | | | | | | | |
| | | VMP-5-12.5-111111 | 11/11/2011 | | | | | | | | | | | | |
| | | VMP-5-12.5-013012 | 1/30/2012 | | | | | | | | | | | | |
| | | VMP-5-12.5-041112 | 4/11/2012 | | | | | | | | | | | | |
| | | VMP-5-12.5-071212 | 7/12/2012 | | | | | | | | | | | | |
| | | VMP-5-12.5-101112 | 10/11/2012 | | | | | | | | | | | | |
| | | VMP-5-12.5-012413 | 1/24/2013 | | | | | | | | | | | | |
| | 31 ft | VMP-5-31-090910 | 9/9/2010 | | | | | | | | | | | | |
| | | VMP-5-31-112310 | 11/23/2010 | | | | | | | | | | | | |
| | | VMP-5-31-021611 | 2/16/2011 | | | | | | | | | | | | |
| | | VMP-5-31-042111 | 4/21/2011 | | | | | | | | | | | | |
| | | VMP-5-31-080611 | 8/6/2011 | | | | | | | | | | | | |
| | | VMP-5-31-111111 | 11/11/2011 | | | | | | | | | | | | |
| | | VMP-5-31-013012 | 1/30/2012 | | | | | | | | | | | | |
| | | VMP-5-31-041112 | 4/11/2012 | | | | | | | | | | | | |
| | | VMP-5-31-071212 | 7/12/2012 | | | | | | | | | | | | |
| | | VMP-5-31-101112 | 10/11/2012 | | | | | | | | | | | | |
| | | VMP-5-31-012413 | 1/24/2013 | | | | | | | | | | | | |
| | 40 ft | VMP-5-40-042111 | 4/21/2011 | | | | | | | | | | | | |
| | | VMP-5-40-013012 | 1/30/2012 | | | | | | | | | | | | |
| | | VMP-5-40-041212 | 4/12/2012 | | | | | | | | | | | | |
| | | VMP-5-40-071212 | 7/12/2012 | | | | | | | | | | | | |
| | | VMP-5-40-101112 | 10/11/2012 | | | | | | | | | | | | |
| | | VMP-5-40-012513 | 1/25/2013 | | | | | | | | | | | | |
| | | VMP-5-40-012513-Dup | 1/25/2013 | | | | | | | | | | | | |
| VMP-6 | 5 ft | VMP-6-5-090810 | 9/8/2010 | | | | | | | | | | | | |
| | | VMP-6-5-111610 | 11/16/2010 | | | | | | | | | | | | |
| | | VMP-6-5-020711 | 2/7/2011 | | | | | | | | | | | | |
| | | VMP-6-5-040811 | 4/8/2011 | | | | | | | | | | | | |
| | | VMP-6-5-080411 | 8/4/2011 | | | | | | | | | | | | |
| | | VMP-6-5-110911 | 11/9/2011 | | | | | | | | | | | | |
| | | VMP-6-5-013112 | 1/31/2012 | | | | | | | | | | | | |
| | | VMP-6-5-041212 | 4/12/2012 | | | | | | | | | | | | |
| | | VMP-6-5-071612 | 7/16/2012 | | | | | | | | | | | | |
| | | VMP-6-5-101012 | 10/10/2012 | | | | | | | | | | | | |
| | | VMP-6-5-021213 | 2/12/2013 | | | | | | | | | | | | |
| | 10 ft | VMP-6-10-090810 | 9/8/2010 | | | | | | | | | | | | |
| | | VMP-6-10-111710 | 11/17/2010 | | | | | | | | | | | | |
| | | VMP-6-10-020711 | 2/7/2011 | | | | | | | | | | | | |
| | | VMP-6-10-040811 | 4/8/2011 | | | | | | | | | | | | |
| | | VMP-6-10-080411 | 8/4/2011 | | | | | | | | | | | | |
| | | VMP-6-10-111011 | 11/10/2011 | | | | | | | | | | | | |
| | | VMP-6-10-013112 | 1/31/2012 | | | | | | | | | | | | |
| | | VMP-6-10-041212 | 4/12/2012 | | | | | | | | | | | | |
| | | VMP-6-10-071612 | 7/16/2012 | | | | | | | | | | | | |
| | | VMP-6-10-101112 | 10/11/2012 | | | | | | | | | | | | |
| | | VMP-6-10-020513 | 2/5/2013 | | | | | | | | | | | | |
| | 31.5 ft | VMP-6-31.5-090810 | 9/8/2010 | | | | | | | | | | | | |
| | | VMP-6-31.5-111710 | 11/17/2010 | | | | | | | | | | | | |
| | | VMP-6-31.5-020711 | 2/7/2011 | | | | | | | | | | | | |
| | | VMP-6-31.5-041111 | 4/11/2011 | | | | | | | | | | | | |
| | | VMP-6-31.5-080411 | 8/4/2011 | | | | | | | | | | | | |
| | | VMP-6-31.5-111011 | 11/10/2011 | | | | | | | | | | | | |
| | | VMP-6-31.5-013112 | 1/31/2012 | | | | | | | | | | | | |
| | | VMP-6-31.5-041212 | 4/12/2012 | | | | | | | | | | | | |
| | | VMP-6-31.5-071612 | 7/16/2012 | | | | | | | | | | | | |
| | | VMP-6-31.5-101112 | 10/11/2012 | | | | | | | | | | | | |
| | | VMP-6-31.5-020513 | 2/5/2013 | | | | | | | | | | | | |
| | 39 ft | VMP-6-39-041111 | 4/11/2011 | | | | | | | | | | | | |
| | | VMP-6-39-013112 | 1/31/2012 | | | | | | | | | | | | |
| | | VMP-6-39-041212 | 4/12/2012 | | | | | | | | | | | | |
| | | VMP-6-39-071612 | 7/16/2012 | | | | | | | | | | | | |
| | | VMP-6-39-071612-Dup | 7/16/2012 | | | | | | | | | | | | |
| | | VMP-6-39-101112 | 10/11/2012 | | | | | | | | | | | | |
| | | VMP-6-39-020513 | 2/5/2013 | | | | | | | | | | | | |

SEE LAST PAGE OF TABLE FOR NOTES

**TABLE 5**
**CUMULATIVE SUMMARY OF SOIL VAPOR ANALYTICAL DETECTIONS AND SCREENING RESULTS: VILLAGE - VOCS**

| Location | Depth | Sample ID | Sample Date | [3]Pentane | | | [3]Pentane, 2-methyl- | | | [3]Pentane, 3-methyl- | | | [3]Unknown | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | Result (ppbV) | Lab Quals | URS Quals | Result (ppbV) | Lab Quals | URS Quals | Result (ppbV) | Lab Quals | URS Quals | Result (ppbV) | Lab Quals | URS Quals |
| VMP-7 | 5 ft | VMP-7-5-082610 | 8/26/2010 | | | | | | | | | | | | |
| | | VMP-7-5-111910 | 11/19/2010 | | | | | | | | | | | | |
| | | VMP-7-5-020711 | 2/7/2011 | | | | | | | | | | | | |
| | | VMP-7-5-040711 | 4/7/2011 | | | | | | | | | | | | |
| | | VMP-7-5-080211 | 8/2/2011 | | | | | | | | | | | | |
| | | VMP-7-5-111011 | 11/10/2011 | | | | | | | | | | | | |
| | | VMP-7-5-111011-DUP | 11/10/2011 | | | | | | | | | | | | |
| | | VMP-7-5-013112 | 1/31/2012 | | | | | | | | | | | | |
| | | VMP-7-5-041212 | 4/12/2012 | | | | | | | | | | | | |
| | | VMP-7-5-073112 | 7/31/2012 | | | | | | | | | | | | |
| | | VMP-7-5-101012 | 10/10/2012 | | | | | | | | | | | | |
| | 13.5 ft | VMP-7-13.5-082610 | 8/26/2010 | | | | | | | | | | | | |
| | | VMP-7-13.5-111910 | 11/19/2010 | | | | | | | | | | | | |
| | | VMP-7-13.5-020711 | 2/7/2011 | | | | | | | | | | | | |
| | | VMP-7-13.5-040711 | 4/7/2011 | | | | | | | | | | | | |
| | | VMP-7-13.5-080311 | 8/3/2011 | | | | | | | | | | | | |
| | | VMP-7-13.5-111011 | 11/10/2011 | | | | | | | | | | | | |
| | | VMP-7-13.5-013112 | 1/31/2012 | | | | | | | | | | | | |
| | | VMP-7-13.5-013112-DUP | 1/31/2012 | | | | | | | | | | | | |
| | | VMP-7-13.5-041212 | 4/12/2012 | | | | | | | | | | | | |
| | | VMP-7-13.5-041212-DUP | 4/12/2012 | | | | | | | | | | | | |
| | | VMP-7-13.5-072012 | 7/20/2012 | | | | | | | | | | | | |
| | | VMP-7-13.5-101012 | 10/10/2012 | | | | | | | | | | | | |
| | | VMP-7-13.5-021313 | 2/13/2013 | | | | | | | | | | | | |
| | 29.5 ft | VMP-7-29.5-083110 | 8/31/2010 | | | | | | | | | | | | |
| | | VMP-7-29.5-111910 | 11/19/2010 | | | | | | | | | | | | |
| | | VMP-7-29.5-020711 | 2/7/2011 | | | | | | | | | | | | |
| | | VMP-7-29.5-040711 | 4/7/2011 | | | | | | | | | | | | |
| | | VMP-7-29.5-080311 | 8/3/2011 | | | | | | | | | | | | |
| | | VMP-7-29.5-111111 | 11/11/2011 | | | | | | | | | | | | |
| | | VMP-7-29.5-020112 | 2/1/2012 | | | | | | | | | | | | |
| | | VMP-7-29.5-041312 | 4/13/2012 | | | | | | | | | | | | |
| | | VMP-7-29.5-072012 | 7/20/2012 | | | | | | | | | | | | |
| | | VMP-7-29.5-072012-Dup | 7/20/2012 | | | | | | | | | | | | |
| | | VMP-7-29.5-101012 | 10/10/2012 | | | | | | | | | | | | |
| | 38 ft | VMP-7-38-020711 | 2/7/2011 | | | | | | | | | | | | |
| | | VMP-7-38-040711 | 4/7/2011 | | | | | | | | | | | | |
| | | VMP-7-38-020112 | 2/1/2012 | | | | | | | | | | | | |
| | | VMP-7-38-042512 | 4/25/2012 | | | | | | | | | | | | |
| | | VMP-7-38-042512-Dup | 4/25/2012 | | | | | | | | | | | | |
| | | VMP-7-38-101112 | 10/11/2012 | | | | | | | | | | | | |
| VMP-8 | 5 ft | VMP-8-5-083010 | 8/30/2010 | | | | | | | | | | | | |
| | | VMP-8-5-111810 | 11/17/2010 | | | | | | | | | | | | |
| | | VMP-8-5-021011 | 2/10/2011 | | | | | | | | | | | | |
| | | VMP-8-5-040711 | 4/7/2011 | | | | | | | | | | | | |
| | | VMP-8-5-072711 | 7/27/2011 | | | | | | | | | | | | |
| | | VMP-8-5-110311 | 11/3/2011 | | | | | | | | | | | | |
| | | VMP-8-5-012312 | 1/23/2012 | | | | | | | | | | | | |
| | | VMP-8-5-041012 | 4/10/2012 | | | | | | | | | | | | |
| | | VMP-8-5-071312 | 7/13/2012 | | | | | | | | | | | | |
| | | VMP-8-5-073112 | 7/31/2012 | | | | | | | | | | | | |
| | | VMP-8-5-100412 | 10/4/2012 | | | | | | | | | | | | |
| | | VMP-8-5-100412-Dup | 10/4/2012 | | | | | | | | | | | | |
| | | VMP-8-5-012413 | 1/24/2013 | | | | | | | | | | | | |
| | 9.5 ft | VMP-8-9.5 | 11/10/2009 | | | | | | | | | | | | |
| | | VMP-8-9.5-083010 | 8/30/2010 | | | | | | | | | | | | |
| | | VMP-8-9.5-083010-DUP | 8/30/2010 | | | | | | | | | | | | |
| | | VMP-8-9.5-111810 | 11/17/2010 | | | | | | | | | | | | |
| | | VMP-8-9.5-021011 | 2/10/2011 | | | | | | | | | | | | |
| | | VMP-8-9.5-040711 | 4/7/2011 | | | | | | | | | | | | |
| | | VMP-8-9.5-072711 | 7/27/2011 | | | | | | | | | | | | |
| | | VMP-8-9.5-110311 | 11/3/2011 | | | | | | | | | | | | |
| | | VMP-8-9.5-012312 | 1/23/2012 | | | | | | | | | | | | |
| | | VMP-8-9.5-041012 | 4/10/2012 | | | | | | | | | | | | |
| | | VMP-8-9.5-071312 | 7/13/2012 | | | | | | | | | | | | |
| | | VMP-8-9.5-071312-Dup | 7/13/2012 | | | | | | | | | | | | |
| | | VMP-8-9.5-100412 | 10/4/2012 | | | | | | | | | | | | |
| | | VMP-8-9.5-012413 | 1/24/2013 | | | | | | | | | | | | |
| | | VMP-8-9.5-012413-Dup | 1/24/2013 | | | | | | | | | | | | |
| | 23.5 ft | VMP-8-23.5-083010 | 8/30/2010 | | | | | | | | | | | | |
| | | VMP-8-23.5-111910 | 11/19/2010 | | | | | | | | | | | | |
| | | VMP-8-23.5-021011 | 2/10/2011 | | | | | | | | | | | | |
| | | VMP-8-23.5-040711 | 4/7/2011 | | | | | | | | | | | | |
| | | VMP-8-23.5-040711-DUP | 4/7/2011 | | | | | | | | | | | | |
| | | VMP-8-23.5-081011 | 8/10/2011 | | | | | | | | | | | | |
| | | VMP-8-23.5-110611 | 11/6/2011 | | | | | | | | | | | | |
| | | VMP-8-23.5-012312 | 1/23/2012 | | | | | | | | | | | | |
| | | VMP-8-23.5-041012 | 4/10/2012 | | | | | | | | | | | | |
| | | VMP-8-23.5-071312 | 7/13/2012 | | | | | | | | | | | | |
| | | VMP-8-23.5-100412 | 10/4/2012 | | | | | | | | | | | | |
| | | VMP-8-23.5-012413 | 1/24/2013 | | | | | | | | | | | | |

SEE LAST PAGE OF TABLE FOR NOTES

**TABLE 5**
**CUMULATIVE SUMMARY OF SOIL VAPOR ANALYTICAL DETECTIONS AND SCREENING RESULTS: VILLAGE - VOCS**

| Location | Depth | Sample ID | Sample Date | [3]Pentane | | | [3]Pentane, 2-methyl- | | | [3]Pentane, 3-methyl- | | | [3]Unknown | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | Result (ppbV) | Lab Quals | URS Quals | Result (ppbV) | Lab Quals | URS Quals | Result (ppbV) | Lab Quals | URS Quals | Result (ppbV) | Lab Quals | URS Quals |
| VMP-9 | 5 ft | VMP-9-5-082610 | 8/26/2010 | | | | | | | | | | | | |
| | | VMP-9-5-111910 | 11/19/2010 | | | | | | | | | | | | |
| | | VMP-9-5-020811 | 2/8/2011 | | | | | | | | | | | | |
| | | VMP-9-5-040611 | 4/6/2011 | | | | | | | | | | | | |
| | | VMP-9-5-080211 | 8/2/2011 | | | | | | | | | | | | |
| | | VMP-9-5-110411 | 11/4/2011 | | | | | | | | | | | | |
| | | VMP-9-5-012612 | 1/26/2012 | | | | | | | | | | | | |
| | | VMP-9-5-041112 | 4/11/2012 | | | | | | | | | | | | |
| | | VMP-9-5-071312 | 7/13/2012 | | | | | | | | | | | | |
| | | VMP-9-5-101012 | 10/10/2012 | | | | | | | | | | | | |
| | | [4]VMP-9-5-012513 | 1/25/2013 | | | | | | | | | | | | |
| | | VMP-9-5-021513 | 2/15/2013 | | | | | | | | | | | | |
| | 11.5 ft | VMP-9-11.5-082610 | 8/26/2010 | | | | | | | | | | | | |
| | | VMP-9-11.5-111910 | 11/19/2010 | | | | | | | | | | | | |
| | | VMP-9-11.5-020911 | 2/9/2011 | | | | | | | | | | | | |
| | | VMP-9-11.5-020911-DUP | 2/9/2011 | | | | | | | | | | | | |
| | | VMP-9-11.5-040611 | 4/6/2011 | | | | | | | | | | | | |
| | | VMP-9-11.5-080211 | 8/2/2011 | | | | | | | | | | | | |
| | | VMP-9-11.5-110411 | 11/4/2011 | | | | | | | | | | | | |
| | | VMP-9-11.5-012612 | 1/26/2012 | | | | | | | | | | | | |
| | | VMP-9-11.5-041112 | 4/11/2012 | | | | | | | | | | | | |
| | | VMP-9-11.5-071312 | 7/13/2012 | | | | | | | | | | | | |
| | | VMP-9-11.5-101012 | 10/10/2012 | | | | | | | | | | | | |
| | | VMP-9-11.5-012513 | 1/25/2013 | | | | | | | | | | | | |
| | | VMP-9-11.5-012513-DUP | 1/25/2013 | | | | | | | | | | | | |
| | 25.5 ft | VMP-9-25.5-082610 | 8/26/2010 | | | | | | | | | | | | |
| | | VMP-9-25.5-082610-DUP | 8/26/2010 | | | | | | | | | | | | |
| | | VMP-9-25.5-111910 | 11/19/2010 | | | | | | | | | | | | |
| | | VMP-9-25.5-020911 | 2/9/2011 | | | | | | | | | | | | |
| | | VMP-9-25.5-040811 | 4/8/2011 | | | | | | | | | | | | |
| | | VMP-9-25.5-080211 | 8/2/2011 | | | | | | | | | | | | |
| | | VMP-9-25.5-110711 | 11/7/2011 | | | | | | | | | | | | |
| | | VMP-9-25.5-110711-DUP | 11/7/2011 | | | | | | | | | | | | |
| | | VMP-9-25.5-012612 | 1/26/2012 | | | | | | | | | | | | |
| | | VMP-9-25.5-041112 | 4/11/2012 | | | | | | | | | | | | |
| | | VMP-9-25.5-071312 | 7/13/2012 | | | | | | | | | | | | |
| | | VMP-9-25.5-071312-Dup | 7/13/2012 | | | | | | | | | | | | |
| | | VMP-9-25.5-101012 | 10/10/2012 | | | | | | | | | | | | |
| | | VMP-9-25.5-013013 | 1/30/2013 | | | | | | | | | | | | |
| | 38.5 ft | VMP-9-38.5-020911 | 2/9/2011 | | | | | | | | | | | | |
| | | VMP-9-38.5-040811 | 4/8/2011 | | | | | | | | | | | | |
| | | VMP-9-38.5-012612 | 1/26/2012 | | | | | | | | | | | | |
| | | VMP-9-38.5-041112 | 4/11/2012 | | | | | | | | | | | | |
| | | VMP-9-38.5-071312 | 7/13/2012 | | | | | | | | | | | | |
| | | VMP-9-38.5-101012 | 10/10/2012 | | | | | | | | | | | | |
| | | VMP-9-38.5-013013 | 1/30/2013 | | | | | | | | | | | | |
| VMP-18 | 8.5 ft | VMP-18-8.5 | 6/18/2010 | | | | | | | | | | | | |
| | | VMP-18-8.5-090710 | 9/7/2010 | | | | | | | | | | | | |
| | | VMP-18-8.5-111910 | 11/19/2010 | | | | | | | | | | | | |
| | | VMP-18-8.5-020711 | 2/7/2011 | | | | | | | | | | | | |
| | | VMP-18-8.5-020711-DUP | 2/7/2011 | | | | | | | | | | | | |
| | | VMP-18-8.5-040711 | 4/7/2011 | | | | | | | | | | | | |
| | | VMP-18-8.5-072811 | 7/28/2011 | | | | | | | | | | | | |
| | | VMP-18-8.5-110711 | 11/7/2011 | | | | | | | | | | | | |
| | | VMP-18-8.5-012312 | 1/23/2012 | | | | | | | | | | | | |
| | | VMP-18-8.5-041012 | 4/10/2012 | | | | | | | | | | | | |
| | | VMP-18-8.5-071212 | 7/12/2012 | | | | | | | | | | | | |
| | | VMP-18-8.5-100912 | 10/9/2012 | | | | | | | | | | | | |
| | | VMP-18-8.5-012313 | 1/23/2013 | | | | | | | | | | | | |
| VMP-19 | 5 ft | VMP-19-5 | 6/18/2010 | | | | | | | | | | | | |
| | | VMP-19-5-090110 | 9/1/2010 | | | | | | | | | | | | |
| | | VMP-19-5-111510 | 11/15/2010 | | | | | | | | | | | | |
| | | VMP-19-5-020411 | 2/4/2011 | | | | | | | | | | | | |
| | | VMP-19-5-040711 | 4/7/2011 | | | | | | | | | | | | |
| | | VMP-19-5-080911 | 8/9/2011 | | | | | | | | | | | | |
| | | VMP-19-5-080911-DUP | 8/9/2011 | | | | | | | | | | | | |
| | | VMP-19-5-110811 | 11/8/2011 | | | | | | | | | | | | |
| | | VMP-19-5-012612 | 1/26/2012 | | | | | | | | | | | | |
| | | VMP-19-5-041012 | 4/10/2012 | | | | | | | | | | | | |
| | | VMP-19-5-071112 | 7/11/2012 | | | | | | | | | | | | |
| | | VMP-19-5-100912 | 10/9/2012 | | | | | | | | | | | | |
| | | VMP-19-5-013113 | 1/31/2013 | | | | | | | | | | | | |

SEE LAST PAGE OF TABLE FOR NOTES

**TABLE 5**
**CUMULATIVE SUMMARY OF SOIL VAPOR ANALYTICAL DETECTIONS AND SCREENING RESULTS: VILLAGE - VOCS**

| Location | Depth | Sample ID | Sample Date | [3]Pentane | | | [3]Pentane, 2-methyl- | | | [3]Pentane, 3-methyl- | | | [3]Unknown | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | Result (ppbV) | Lab Quals | URS Quals | Result (ppbV) | Lab Quals | URS Quals | Result (ppbV) | Lab Quals | URS Quals | Result (ppbV) | Lab Quals | URS Quals |
| VMP-20 | 5 ft | VMP-20-5-031411 | 3/14/2011 | | | | | | | | | | | | |
| | | VMP-20-5-041511 | 4/15/2011 | | | | | | | | | | | | |
| | | VMP-20-5-072511 | 7/25/2011 | | | | | | | | | | | | |
| | | VMP-20-5-110111 | 11/1/2011 | | | | | | | | | | | | |
| | | VMP-20-5-012312 | 1/23/2012 | | | | | | | | | | | | |
| | | VMP-20-5-041012 | 4/10/2012 | | | | | | | | | | | | |
| | | VMP-20-5-071112 | 7/11/2012 | | | | | | | | | | | | |
| | | VMP-20-5-073112 | 7/31/2012 | | | | | | | | | | | | |
| | | VMP-20-5-100412 | 10/4/2012 | | | | | | | | | | | | |
| | | VMP-20-5-020713 | 2/7/2013 | | | | | | | | | | | | |
| | 10 ft | VMP-20-10-031411 | 3/14/2011 | | | | | | | | | | | | |
| | | VMP-20-10-041511 | 4/15/2011 | | | | | | | | | | | | |
| | | VMP-20-10-072511 | 7/25/2011 | | | | | | | | | | | | |
| | | VMP-20-10-110111 | 11/1/2011 | | | | | | | | | | | | |
| | | VMP-20-10-012312 | 1/23/2012 | | | | | | | | | | | | |
| | | VMP-20-10-041012 | 4/10/2012 | | | | | | | | | | | | |
| | | VMP-20-10-071112 | 7/11/2012 | | | | | | | | | | | | |
| | | VMP-20-10-100412 | 10/4/2012 | | | | | | | | | | | | |
| | | VMP-20-10-012213 | 1/22/2013 | | | | | | | | | | | | |
| | 25 ft | VMP-20-25-031411 | 3/14/2011 | | | | | | | | | | | | |
| | | VMP-20-25-041511 | 4/15/2011 | | | | | | | | | | | | |
| | | VMP-20-25-072611 | 7/26/2011 | | | | | | | | | | | | |
| | | VMP-20-25-110511 | 11/5/2011 | | | | | | | | | | | | |
| | | VMP-20-25-012312 | 1/23/2012 | | | | | | | | | | | | |
| | | VMP-20-25-041012 | 4/10/2012 | | | | | | | | | | | | |
| | | VMP-20-25-041012-Dup | 4/10/2012 | | | | | | | | | | | | |
| | | VMP-20-25-071112 | 7/11/2012 | | | | | | | | | | | | |
| | | VMP-20-25-100412 | 10/4/2012 | | | | | | | | | | | | |
| | | VMP-20-25-012213 | 1/22/2013 | | | | | | | | | | | | |
| | 39.5 ft | VMP-20-39.5-100412 | 10/4/2012 | | | | | | | | | | | | |
| | | VMP-20-39.5-012313 | 1/23/2013 | | | | | | | | | | | | |
| VMP-21 | 5 ft | VMP-21-5-020911 | 2/9/2011 | | | | | | | | | | | | |
| | | VMP-21-5-020911-DUP | 2/9/2011 | | | | | | | | | | | | |
| | | VMP-21-5-041311 | 4/13/2011 | | | | | | | | | | | | |
| | | VMP-21-5-072511 | 7/25/2011 | | | | | | | | | | | | |
| | | VMP-21-5-110111 | 11/1/2011 | | | | | | | | | | | | |
| | | VMP-21-5-012312 | 1/23/2012 | | | | | | | | | | | | |
| | | VMP-21-5-012312-DUP | 1/23/2012 | | | | | | | | | | | | |
| | | VMP-21-5-042412 | 4/24/2012 | | | | | | | | | | | | |
| | | VMP-21-5-071012 | 7/10/2012 | | | | | | | | | | | | |
| | | VMP-21-5-100412 | 10/4/2012 | | | | | | | | | | | | |
| | | VMP-21-5-020613 | 2/6/2013 | | | | | | | | | | | | |
| | 10 ft | VMP-21-10-021011 | 2/10/2011 | | | | | | | | | | | | |
| | | VMP-21-10-041311 | 4/13/2011 | | | | | | | | | | | | |
| | | VMP-21-10-072511 | 7/25/2011 | | | | | | | | | | | | |
| | | VMP-21-10-110111 | 11/1/2011 | | | | | | | | | | | | |
| | | VMP-21-10-012312 | 1/23/2012 | | | | | | | | | | | | |
| | | VMP-21-10-040912 | 4/9/2012 | | | | | | | | | | | | |
| | | VMP-21-10-071012 | 7/10/2012 | | | | | | | | | | | | |
| | | VMP-21-10-100412 | 10/4/2012 | | | | | | | | | | | | |
| | | VMP-21-10-020513 | 2/5/2013 | | | | | | | | | | | | |
| | | VMP-21-10-020513-DUP | 2/5/2013 | | | | | | | | | | | | |
| | 25 ft | VMP-21-25-021011 | 2/10/2011 | | | | | | | | | | | | |
| | | VMP-21-25-041411 | 4/14/2011 | | | | | | | | | | | | |
| | | VMP-21-25-041411-DUP | 4/14/2011 | | | | | | | | | | | | |
| | | VMP-21-25-072611 | 7/26/2011 | | | | | | | | | | | | |
| | | VMP-21-25-110511 | 11/5/2011 | | | | | | | | | | | | |
| | | VMP-21-25-012412 | 1/24/2012 | | | | | | | | | | | | |
| | | VMP-21-25-040912 | 4/9/2012 | | | | | | | | | | | | |
| | | VMP-21-25-071112 | 7/11/2012 | | | | | | | | | | | | |
| | | VMP-21-25-100412 | 10/4/2012 | | | | | | | | | | | | |
| | | VMP-21-25-020513 | 2/5/2013 | | | | | | | | | | | | |
| | | VMP-21-25-020513-DUP | 2/5/2013 | | | | | | | | | | | | |
| | 33 ft | VMP-21-33-021011 | 2/10/2011 | | | | | | | | | | | | |
| | | VMP-21-33-041411 | 4/14/2011 | | | | | | | | | | | | |
| | | VMP-21-33-110511 | 11/5/2011 | | | | | | | | | | | | |
| | | VMP-21-33-012412 | 1/24/2012 | | | | | | | | | | | | |
| | | VMP-21-33-042412 | 4/24/2012 | | | | | | | | | | | | |
| | | VMP-21-33-071112 | 7/11/2012 | | | | | | | | | | | | |
| | | VMP-21-33-100412 | 10/4/2012 | | | | | | | | | | | | |
| | | VMP-21-33-020513 | 2/5/2013 | | | | | | | | | | | | |

SEE LAST PAGE OF TABLE FOR NOTES

**TABLE 5**
**CUMULATIVE SUMMARY OF SOIL VAPOR ANALYTICAL DETECTIONS AND SCREENING RESULTS: VILLAGE - VOCS**

| Location | Depth | Sample ID | Sample Date | [3]Pentane | | | [3]Pentane, 2-methyl- | | | [3]Pentane, 3-methyl- | | | [3]Unknown | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | Result (ppbV) | Lab Quals | URS Quals | Result (ppbV) | Lab Quals | URS Quals | Result (ppbV) | Lab Quals | URS Quals | Result (ppbV) | Lab Quals | URS Quals |
| VMP-22 | 5 ft | VMP-22-5-021111 | 2/11/2011 | | | | | | | | | | | | |
| | | VMP-22-5-041811 | 4/18/2011 | | | | | | | | | | | | |
| | | VMP-22-5-072611 | 7/26/2011 | | | | | | | | | | | | |
| | | VMP-22-5-110111 | 11/1/2011 | | | | | | | | | | | | |
| | | VMP-22-5-012412 | 1/24/2012 | | | | | | | | | | | | |
| | | VMP-22-5-040912 | 4/9/2012 | | | | | | | | | | | | |
| | | VMP-22-5-070912 | 7/9/2012 | | | | | | | | | | | | |
| | | VMP-22-5-100312 | 10/3/2012 | | | | | | | | | | | | |
| | | VMP-22-5-100312-Dup | 10/3/2012 | | | | | | | | | | | | |
| | | VMP-22-5-012413 | 1/24/2013 | | | | | | | | | | | | |
| | 10 ft | VMP-22-10-021111 | 2/11/2011 | | | | | | | | | | | | |
| | | VMP-22-10-041811 | 4/18/2011 | | | | | | | | | | | | |
| | | VMP-22-10-072611 | 7/26/2011 | | | | | | | | | | | | |
| | | VMP-22-10-072611-DUP | 7/26/2011 | | | | | | | | | | | | |
| | | VMP-22-10-110211 | 11/2/2011 | | | | | | | | | | | | |
| | | VMP-22-10-012412 | 1/24/2012 | | | | | | | | | | | | |
| | | VMP-22-10-040912 | 4/9/2012 | | | | | | | | | | | | |
| | | VMP-22-10-070912 | 7/9/2012 | | | | | | | | | | | | |
| | | VMP-22-10-070912-Dup | 7/9/2012 | | | | | | | | | | | | |
| | | VMP-22-10-100312 | 10/3/2012 | | | | | | | | | | | | |
| | | VMP-22-10-012413 | 1/24/2013 | | | | | | | | | | | | |
| | 18 ft | VMP-22-18-021111 | 2/11/2011 | | | | | | | | | | | | |
| | | VMP-22-18-041811 | 4/18/2011 | | | | | | | | | | | | |
| | | VMP-22-18-072611 | 7/26/2011 | | | | | | | | | | | | |
| | | VMP-22-18-110511 | 11/5/2011 | | | | | | | | | | | | |
| | | VMP-22-18-012412 | 1/24/2012 | | | | | | | | | | | | |
| | | VMP-22-18-040912 | 4/9/2012 | | | | | | | | | | | | |
| | | VMP-22-18-070912 | 7/9/2012 | | | | | | | | | | | | |
| | | VMP-22-18-100412 | 10/4/2012 | | | | | | | | | | | | |
| | | VMP-22-18-012413 | 1/24/2013 | | | | | | | | | | | | |
| | 38 ft | VMP-22-38-041811 | 4/18/2011 | | | | | | | | | | | | |
| | | VMP-22-38-012512 | 1/25/2012 | | | | | | | | | | | | |
| | | VMP-22-38-040912 | 4/9/2012 | | | | | | | | | | | | |
| | | VMP-22-38-070912 | 7/9/2012 | | | | | | | | | | | | |
| | | VMP-22-38-100412 | 10/4/2012 | | | | | | | | | | | | |
| | | VMP-22-38-012413 | 1/24/2013 | | | | | | | | | | | | |
| VMP-23 | 5 ft | VMP-23-5-021511 | 2/15/2011 | | | | | | | | | | | | |
| | | VMP-23-5-042111 | 4/21/2011 | | | | | | | | | | | | |
| | | VMP-23-5-072711 | 7/27/2011 | | | | | | | | | | | | |
| | | VMP-23-5-110211 | 11/2/2011 | | | | | | | | | | | | |
| | | VMP-23-5-012512 | 1/25/2012 | | | | | | | | | | | | |
| | | VMP-23-5-040912 | 4/9/2012 | | | | | | | | | | | | |
| | | VMP-23-5-070912 | 7/9/2012 | | | | | | | | | | | | |
| | | VMP-23-5-100312 | 10/3/2012 | | | | | | | | | | | | |
| | | VMP-23-5-012413 | 1/24/2013 | | | | | | | | | | | | |
| | 10 ft | VMP-23-10-021511 | 2/15/2011 | | | | | | | | | | | | |
| | | VMP-23-10-042111 | 4/21/2011 | | | | | | | | | | | | |
| | | VMP-23-10-072711 | 7/27/2011 | | | | | | | | | | | | |
| | | VMP-23-10-110211 | 11/2/2011 | | | | | | | | | | | | |
| | | VMP-23-10-012512 | 1/25/2012 | | | | | | | | | | | | |
| | | VMP-23-10-040912 | 4/9/2012 | | | | | | | | | | | | |
| | | VMP-23-10-040912-Dup | 4/9/2012 | | | | | | | | | | | | |
| | | VMP-23-10-070912 | 7/9/2012 | | | | | | | | | | | | |
| | | VMP-23-10-100312 | 10/3/2012 | | | | | | | | | | | | |
| | | VMP-23-10-012413 | 1/24/2013 | | | | | | | | | | | | |
| | 25 ft | VMP-23-25-021511 | 2/15/2011 | | | | | | | | | | | | |
| | | VMP-23-25-042111 | 4/21/2011 | | | | | | | | | | | | |
| | | VMP-23-25-072711 | 7/27/2011 | | | | | | | | | | | | |
| | | VMP-23-25-110511 | 11/5/2011 | | | | | | | | | | | | |
| | | VMP-23-25-012512 | 1/25/2012 | | | | | | | | | | | | |
| | | VMP-23-25-040912 | 4/9/2012 | | | | | | | | | | | | |
| | | VMP-23-25-071012 | 7/10/2012 | | | | | | | | | | | | |
| | | VMP-23-25-100312 | 10/3/2012 | | | | | | | | | | | | |
| | | VMP-23-25-012413 | 1/24/2013 | | | | | | | | | | | | |
| | 40 ft | VMP-23-40-071012 | 7/10/2012 | | | | | | | | | | | | |
| | | VMP-23-40-100312 | 10/3/2012 | | | | | | | | | | | | |
| | | VMP-23-40-012413 | 1/24/2013 | | | | | | | | | | | | |

SEE LAST PAGE OF TABLE FOR NOTES

**TABLE 5**
**CUMULATIVE SUMMARY OF SOIL VAPOR ANALYTICAL DETECTIONS AND SCREENING RESULTS: VILLAGE - VOCS**

| Location | Depth | Sample ID | Sample Date | [3]Pentane | | | [3]Pentane, 2-methyl- | | | [3]Pentane, 3-methyl- | | | [3]Unknown | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | Result (ppbV) | Lab Quals | URS Quals | Result (ppbV) | Lab Quals | URS Quals | Result (ppbV) | Lab Quals | URS Quals | Result (ppbV) | Lab Quals | URS Quals |
| VMP-24 | 5 ft | VMP-24-5-021611 | 2/16/2011 | | | | | | | | | | | | |
| | | VMP-24-5-040811 | 4/8/2011 | | | | | | | | | | | | |
| | | VMP-24-5-072811 | 7/28/2011 | | | | | | | | | | | | |
| | | VMP-24-5-110211 | 11/2/2011 | | | | | | | | | | | | |
| | | VMP-24-5-110211-DUP | 11/2/2011 | | | | | | | | | | | | |
| | | VMP-24-5-012512 | 1/25/2012 | | | | | | | | | | | | |
| | | VMP-24-5-040912 | 4/9/2012 | | | | | | | | | | | | |
| | | VMP-24-5-071212 | 7/12/2012 | | | | | | | | | | | | |
| | | VMP-24-5-101912 | 10/19/2012 | | | | | | | | | | | | |
| | | VMP-24-5-012313 | 1/23/2013 | | | | | | | | | | | | |
| | 10 ft | VMP-24-10-021711 | 2/17/2011 | | | | | | | | | | | | |
| | | VMP-24-10-041111 | 4/11/2011 | | | | | | | | | | | | |
| | | VMP-24-10-072811 | 7/28/2011 | | | | | | | | | | | | |
| | | VMP-24-10-110211 | 11/2/2011 | | | | | | | | | | | | |
| | | VMP-24-10-012512 | 1/25/2012 | | | | | | | | | | | | |
| | | VMP-24-10-041012 | 4/10/2012 | | | | | | | | | | | | |
| | | VMP-24-10-071212 | 7/12/2012 | | | | | | | | | | | | |
| | | VMP-24-10-100912 | 10/9/2012 | | | | | | | | | | | | |
| | | VMP-24-10-012313 | 1/23/2013 | | | | | | | | | | | | |
| | 22 ft | VMP-24-22-021711 | 2/17/2011 | | | | | | | | | | | | |
| | | VMP-24-22-041111 | 4/11/2011 | | | | | | | | | | | | |
| | | VMP-24-22-072811 | 7/28/2011 | | | | | | | | | | | | |
| | | VMP-24-22-072811-Dup | 7/28/2011 | | | | | | | | | | | | |
| | | VMP-24-22-110611 | 11/6/2011 | | | | | | | | | | | | |
| | | VMP-24-22-012512 | 1/25/2012 | | | | | | | | | | | | |
| | | VMP-24-22-041012 | 4/10/2012 | | | | | | | | | | | | |
| | | VMP-24-22-071212 | 7/12/2012 | | | | | | | | | | | | |
| | | VMP-24-22-100912 | 10/9/2012 | | | | | | | | | | | | |
| | | VMP-24-22-012313 | 1/23/2013 | | | | | | | | | | | | |
| | 34 ft | VMP-24-34-021711 | 2/17/2011 | | | | | | | | | | | | |
| | | VMP-24-34-041111 | 4/11/2011 | | | | | | | | | | | | |
| | | VMP-24-34-072811 | 7/28/2011 | | | | | | | | | | | | |
| | | VMP-24-34-110611 | 11/6/2011 | | | | | | | | | | | | |
| | | VMP-24-34-012512 | 1/25/2012 | | | | | | | | | | | | |
| | | VMP-24-34-041012 | 4/10/2012 | | | | | | | | | | | | |
| | | VMP-24-34-071212 | 7/12/2012 | | | | | | | | | | | | |
| | | VMP-24-34-100912 | 10/9/2012 | | | | | | | | | | | | |
| | | VMP-24-34-012313 | 1/23/2013 | | | | | | | | | | | | |
| VMP-31 | 5 ft | VMP-31-5-042512 | 4/25/2012 | | | | | | | | | | | | |
| | | VMP-31-5-072012 | 7/20/2012 | | | | | | | | | | | | |
| | | VMP-31-5-102612 | 10/26/2012 | | | | | | | | | | | | |
| | | VMP-31-5-021113 | 2/11/2013 | | | | | | | | | | | | |
| | 10 ft | VMP-31-10-042512 | 4/25/2012 | | | | | | | | | | | | |
| | | VMP-31-10-072612 | 7/26/2012 | | | | | | | | | | | | |
| | | VMP-31-10-102612 | 10/26/2012 | | | | | | | | | | | | |
| | | VMP-31-10-021313 | 2/13/2013 | | | | | | | | | | | | |
| | 20 ft | VMP-31-20-101912 | 10/19/2012 | | | | | | | | | | | | |
| | | VMP-31-20-021113 | 2/11/2013 | | | | | | | | | | | | |
| | 30 ft | VMP-31-30-042512 | 4/25/2012 | | | | | | | | | | | | |
| | | VMP-31-30-042512-Dup | 4/25/2012 | | | | | | | | | | | | |
| | | VMP-31-30-072012 | 7/20/2012 | | | | | | | | | | | | |
| | | VMP-31-30-101912 | 10/19/2012 | | | | | | | | | | | | |
| | | VMP-31-30-021113 | 2/11/2013 | | | | | | | | | | | | |
| VMP-32 | 5 ft | VMP-32-5-042512 | 4/25/2012 | | | | | | | | | | | | |
| | | VMP-32-5-072012 | 7/20/2012 | | | | | | | | | | | | |
| | | VMP-32-5-101812 | 10/18/2012 | | | | | | | | | | | | |
| | | VMP-32-5-020513 | 2/5/2013 | | | | | | | | | | | | |
| | 10 ft | VMP-32-10-041612 | 4/16/2012 | | | | | | | | | | | | |
| | | VMP-32-10-072012 | 7/20/2012 | | | | | | | | | | | | |
| | | VMP-32-10-101812 | 10/18/2012 | | | | | | | | | | | | |
| | | VMP-32-10-020513 | 2/5/2013 | | | | | | | | | | | | |
| | 20 ft | VMP-32-20-041612 | 4/16/2012 | | | | | | | | | | | | |
| | | VMP-32-20-072012 | 7/20/2012 | | | | | | | | | | | | |
| | | VMP-32-20-101812 | 10/18/2012 | | | | | | | | | | | | |
| | | VMP-32-20-020513 | 2/5/2013 | | | | | | | | | | | | |
| | 30 ft | VMP-32-30-041612 | 4/16/2012 | | | | | | | | | | | | |
| | | VMP-32-30-072012 | 7/20/2012 | | | | | | | | | | | | |
| | | VMP-32-30-101812 | 10/18/2012 | | | | | | | | | | | | |
| | | VMP-32-30-020513 | 2/5/2013 | | | | | | | | | | | | |

SEE LAST PAGE OF TABLE FOR NOTES

**TABLE 5**
**CUMULATIVE SUMMARY OF SOIL VAPOR ANALYTICAL DETECTIONS AND SCREENING RESULTS: VILLAGE - VOCS**

| Location | Depth | Sample ID | Sample Date | [3]Pentane | | | [3]Pentane, 2-methyl- | | | [3]Pentane, 3-methyl- | | | [3]Unknown | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | Result (ppbV) | Lab Quals | URS Quals | Result (ppbV) | Lab Quals | URS Quals | Result (ppbV) | Lab Quals | URS Quals | Result (ppbV) | Lab Quals | URS Quals |
| VMP-42 | 10 ft | VMP-42-10-041812 | 4/18/2012 | | | | | | | | | | | | |
| | | VMP-42-10-041812-Dup | 4/18/2012 | | | | | | | | | | | | |
| | | VMP-42-20-041812 | 4/18/2012 | | | | | | | | | | | | |
| | | VMP-42-10-071912 | 7/19/2012 | | | | | | | | | | | | |
| | | VMP-42-10-101212 | 10/12/2012 | | | | | | | | | | | | |
| | | VMP-42-10-013113 | 1/31/2013 | | | | | | | | | | | | |
| | 20 ft | VMP-42-20-071912 | 7/19/2012 | | | | | | | | | | | | |
| | | VMP-42-20-101212 | 10/12/2012 | | | | | | | | | | | | |
| | | VMP-42-20-101212-Dup | 10/12/2012 | | | | | | | | | | | | |
| | | VMP-42-20-013113 | 1/31/2013 | | | | | | | | | | | | |
| | 30 ft | VMP-42-30-041912 | 4/19/2012 | | | | | | | | | | | | |
| | | VMP-42-30-071912 | 7/19/2012 | | | | | | | | | | | | |
| | | VMP-42-30-101212 | 10/12/2012 | | | | | | | | | | | | |
| | | VMP-42-30-101212-Dup | 10/12/2012 | | | | | | | | | | | | |
| | | VMP-42-30-013113 | 1/31/2013 | | | | | | | | | | | | |
| VMP-43 | 10 ft | VMP-43-10-041612 | 4/16/2012 | | | | | | | | | | | | |
| | | VMP-43-10-071912 | 7/19/2012 | | | | | | | | | | | | |
| | | VMP-43-10-101612 | 10/16/2012 | | | | | | | | | | | | |
| | 20 ft | VMP-43-20-041612 | 4/16/2012 | | | | | | | | | | | | |
| | | VMP-43-20-071912 | 7/19/2012 | | | | | | | | | | | | |
| | | VMP-43-20-101812 | 10/18/2012 | | | | | | | | | | | | |
| | | VMP-43-20-012413 | 1/24/2013 | | | | | | | | | | | | |
| | 30 ft | VMP-43-30-042312 | 4/23/2012 | | | | | | | | | | | | |
| | | VMP-43-30-071912 | 7/19/2012 | | | | | | | | | | | | |
| | | VMP-43-30-101812 | 10/18/2012 | | | | | | | | | | | | |
| | | VMP-43-30-012413 | 1/24/2013 | | | | | | | | | | | | |
| VMP-44 | 10 ft | VMP-44-10-041912 | 4/19/2012 | | | | | | | | | | | | |
| | | VMP-44-10-072012 | 7/20/2012 | | | | | | | | | | | | |
| | | VMP-44-10-081012 | 8/10/2012 | | | | | | | | | | | | |
| | | VMP-44-10-101212 | 10/12/2012 | | | | | | | | | | | | |
| | | VMP-44-10-012513 | 1/25/2013 | | | | | | | | | | | | |
| | 20 ft | VMP-44-20-041912 | 4/19/2012 | | | | | | | | | | | | |
| | | VMP-44-20-072512 | 7/25/2012 | | | | | | | | | | | | |
| | | VMP-44-20-101212 | 10/12/2012 | | | | | | | | | | | | |
| | | VMP-44-20-012513 | 1/25/2013 | | | | | | | | | | | | |
| | 30 ft | VMP-44-30-041912 | 4/19/2012 | | | | | | | | | | | | |
| | | VMP-44-30-072512 | 7/25/2012 | | | | | | | | | | | | |
| | | VMP-44-30-072512-Dup | 7/25/2012 | | | | | | | | | | | | |
| | | VMP-44-30-101512 | 10/15/2012 | | | | | | | | | | | | |
| | | VMP-44-30-101512-Dup | 10/15/2012 | | | | | | | | | | | | |
| | | VMP-44-30-012513 | 1/25/2013 | | | | | | | | | | | | |
| VMP-45 | 10 ft | VMP-45-10-041912 | 4/19/2012 | | | | | | | | | | | | |
| | | VMP-45-10-071912 | 7/19/2012 | | | | | | | | | | | | |
| | | VMP-45-10-101512 | 10/15/2012 | | | | | | | | | | | | |
| | | VMP-45-10-013013 | 1/30/2013 | | | | | | | | | | | | |
| | 20 ft | VMP-45-20-041912 | 4/19/2012 | | | | | | | | | | | | |
| | | VMP-45-20-071912 | 7/19/2012 | | | | | | | | | | | | |
| | | VMP-45-20-101512 | 10/15/2012 | | | | | | | | | | | | |
| | | VMP-45-20-013013 | 1/30/2013 | | | | | | | | | | | | |
| | 30 ft | VMP-45-30-041912 | 4/19/2012 | | | | | | | | | | | | |
| | | VMP-45-30-071912 | 7/19/2012 | | | | | | | | | | | | |
| | | VMP-45-30-101512 | 10/15/2012 | | | | | | | | | | | | |
| | | VMP-45-30-101512-Dup | 10/15/2012 | | | | | | | | | | | | |
| | | VMP-45-30-013013 | 1/30/2013 | | | | | | | | | | | | |

SEE LAST PAGE OF TABLE FOR NOTES

**TABLE 5**
**CUMULATIVE SUMMARY OF SOIL VAPOR ANALYTICAL DETECTIONS AND SCREENING RESULTS: VILLAGE - VOCS**

| Location | Depth | Sample ID | Sample Date | [3]Pentane | | | [3]Pentane, 2-methyl- | | | [3]Pentane, 3-methyl- | | | [3]Unknown | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | Result (ppbV) | Lab Quals | URS Quals | Result (ppbV) | Lab Quals | URS Quals | Result (ppbV) | Lab Quals | URS Quals | Result (ppbV) | Lab Quals | URS Quals |
| VMP-47 | 5 ft | VMP-47-5-012113 | 1/21/2013 | | | | 13 (ppbV) | | | | | | | | |
| | | [1]VMP-47-5-012313-R | 1/23/2013 | 230,000 | | | (ppbV) | | | | | | | | |
| | 10 ft | VMP-47-10-012113 | 1/21/2013 | | | | | | | | | | 7.2 (ppbV) | | |
| | | [1]VMP-47-10-012313-R | 1/23/2013 | | | | (ppbV) | | | (ppbV) | | | | | |
| | 20 ft | VMP-47-20-012113 | 1/21/2013 | 55,000 | | | 160000 | | | | | | 73000 | | |
| | | [1]VMP-47-20-012313-R | 1/23/2013 | 210,000 | | | (ppbV) | | | (ppbV) | | | | | |
| | 30 ft | VMP-47-30-012113 | 1/21/2013 | 46,000 | | | 150000 | | | | | | | | |
| | | [1]VMP-47-30-012313-R | 1/23/2013 | 230,000 | | | (ppbV) | | | (ppbV) | | | | | |
| VMP-48 | 5 ft | VMP-48-5-020113 | 2/1/2013 | | | | | | | | | | | | |
| | 10 ft | VMP-48-10-020113 | 2/1/2013 | | | | | | | | | | | | |
| | 20 ft | VMP-48-20-020113 | 2/1/2013 | | | | | | | | | | | | |
| | 30 ft | VMP-48-30-020113 | 2/1/2013 | | | | | | | | | | | | |
| | | VMP-48-30-020113-DUP | 2/1/2013 | | | | | | | | | | | | |
| VMP-49 | 5 ft | VMP-49-5-020113 | 2/1/2013 | | | | | | | | | | | | |
| | 10 ft | VMP-49-10-020113 | 2/1/2013 | | | | | | | | | | | | |
| | 20 ft | VMP-49-20-020113 | 2/1/2013 | | | | | | | | | | | | |
| | 30 ft | VMP-49-30-020113 | 2/1/2013 | | | | | | | | | | | | |
| VMP-50 | 5 ft | VMP-50-5-020113 | 2/1/2013 | | | | | | | | | | | | |
| | 10 ft | VMP-50-10-020113 | 2/1/2013 | | | | | | | | | | | | |
| | 20 ft | VMP-50-20-020113 | 2/1/2013 | | | | | | | | | | | | |
| | 30 ft | VMP-50-30-020113 | 2/1/2013 | | | | | | | | | | | | |
| VMP-51 | 5 ft | VMP-51-5-020113 | 2/1/2013 | | | | | | | | | | | | |
| | 10 ft | VMP-51-10-020113 | 2/1/2013 | | | | | | | | | | | | |
| | 20 ft | VMP-51-20-021513-R | 2/15/2013 | | | | | | | | | | | | |
| | 30 ft | VMP-51-30-020413 | 2/4/2013 | | | | | | | | | | | | |
| | | VMP-51-30-020413-DUP | 2/4/2013 | | | | | | | | | | | | |
| VMP-52 | 5 ft | VMP-52-5-020413 | 2/4/2013 | | | | | | | | | | | | |
| | 10 ft | VMP-52-10-020413 | 2/4/2013 | | | | | | | | | | | | |
| | 20 ft | VMP-52-20-020413 | 2/4/2013 | | | | | | | | | | | | |
| | | VMP-52-20-020413-DUP | 2/4/2013 | | | | | | | | | | | | |
| | 30 ft | VMP-52-30-020413 | 2/4/2013 | | | | | | | | | | | | |
| VMP-53 | 5 ft | VMP-53-5-020513 | 2/5/2013 | | | | | | | | | | | | |
| | 10 ft | VMP-53-10-020513 | 2/5/2013 | | | | | | | | | | | | |
| | | VMP-53-10-020513-DUP | 2/5/2013 | | | | | | | | | | | | |
| | 20 ft | VMP-53-20-020513 | 2/5/2013 | | | | | | | | | | | | |
| | 30 ft | VMP-53-30-020513 | 2/5/2013 | | | | | | | | | | | | |
| VMP-54 | 5 ft | VMP-54-5-020613 | 2/6/2013 | | | | | | | | | | | | |
| | 10 ft | VMP-54-10-020613 | 2/6/2013 | | | | | | | | | | | | |
| | 20 ft | VMP-54-20-020613 | 2/6/2013 | | | | | | | | | | | | |
| | | VMP-54-20-020613-DUP | 2/6/2013 | | | | | | | | | | | | |
| | 30 ft | VMP-54-30-020613 | 2/6/2013 | | | | | | | | | | | | |
| | | VMP-54-30-020613-DUP | 2/6/2013 | | | | | | | | | | | | |

Notes
**Lab Qualifiers**
J = Estimated value; results between the MDL and RL
U = Compound analyzed for but not detected above the RL
**URS Qualifiers**
J = Estimated detection
UJ = Estimated non-detect
U = Non-detect due to blank contamination

[1] Grab sample taken
[2] After post sampling was conducted integrity issue were identified and sample results are not representative
[3] Tentatively Identified Compound
[4] Sample compromised at laboratory and data not representative

SEE LAST PAGE OF TABLE FOR NOTES

**TABLE 6**
**CUMULATIVE SUMMARY OF SOIL VAPOR ANALYTICAL DETECTIONS AND SCREENING RESULTS: PUBLIC WORKS YARD AND WRR - VOCS**

| Location | Depth | Sample ID | Sample Date | Acetone 750000 | | | alpha-Chlorotoluene | | | Benzene 2.8 | | | Bromodichloromethane 450000 | | | Bromoform 52 | | | Bromomethane 42 | | | 1,3-Butadiene | | | Butane | | | 2-Butanone 40000 | | | Carbon disulfide 5300 | | | Carbon tetrachloride 1.5 | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals |
| VMP-10 | 5 ft | VMP-10-5-090710 | 9/7/2010 | 0.024 | | | <0.0068 | U | | 0.1 | | | <0.0088 | U | | <0.014 | U | | 0.0024 | J | | <0.0029 | U | | | | | 0.004 | | | 0.01 | | | <0.0083 | U | |
| | | VMP-10-5-111810 | 11/17/2010 | 0.0074 | J | | <0.0063 | U | | 0.00098 | J | | 0.0015 | J | | <0.012 | U | | <0.0047 | U | | <0.0027 | U | | | | | 0.002 | J | | <0.0038 | U | | 0.001 | J | |
| | | VMP-10-5-021011 | 2/10/2011 | <0.011 | U | | <0.0062 | U | | <0.0038 | U | | <0.008 | U | | <0.012 | U | | <0.0046 | U | | <0.0026 | U | | | | | <0.0035 | U | | <0.0037 | U | | <0.0075 | U | |
| | | VMP-10-5-040511 | 4/5/2011 | 0.035 | | | <0.0057 | U | | 0.38 | | | <0.0074 | U | | <0.011 | U | | <0.0043 | U | | <0.0024 | U | | 0.013 | | | 0.0082 | J | | <0.014 | U | | <0.0069 | U | |
| | | VMP-10-5-072911 | 7/29/2011 | 0.13 | | | <0.0069 | U | | 0.07 | | | <0.009 | U | | <0.014 | U | | <0.0052 | U | | <0.003 | U | | <0.013 | U | | 0.016 | J | | 0.0079 | J | | <0.0084 | U | |
| | | VMP-10-5-110411 | 11/4/2011 | 0.018 | | | <0.0036 | U | | 0.0033 | | | <0.0046 | U | | <0.0072 | U | | <0.0027 | U | | <0.0015 | U | | <0.0066 | U | | 0.0071 | J | | <0.0086 | U | | <0.0044 | U | |
| | | VMP-10-5-012512 | 1/26/2012 | 0.007 | J | | <0.0045 | U | | 0.018 | | | 0.00086 | J | | <0.009 | U | | <0.0034 | U | | <0.0019 | U | | 0.0059 | J | | 0.0033 | J | | <0.011 | U | | <0.0055 | U | |
| | | VMP-10-5-041212 | 4/12/2012 | 0.04 | | | <0.0049 | U | | 0.0078 | | | <0.0063 | U | | <0.0097 | U | | <0.036 | U | | <0.0021 | U | | 0.011 | | | 0.013 | | | <0.012 | J | U | <0.0059 | U | |
| | | VMP-10-5-071312 | 7/13/2012 | 0.033 | | | <0.005 | U | | 0.0025 | J | | <0.0065 | U | | <0.01 | U | | <0.037 | U | UJ | <0.0021 | U | | <0.0092 | U | | 0.0057 | J | | <0.012 | J | U | <0.0061 | U | |
| | | VMP-10-5-101612 | 10/16/2012 | 0.032 | J | | <0.0078 | U | | 1.9 | | | <0.01 | U | | <0.016 | U | | <0.059 | U | | <0.0034 | U | | 0.085 | | | <0.018 | U | | <0.019 | U | | <0.0095 | U | |
| | | VMP-10-5-012913 | 1/29/2013 | 0.0075 | J | | <0.0073 | U | | 0.0017 | J | | <0.0094 | U | | <0.014 | U | | <0.055 | U | | <0.0031 | U | | 0.022 | | J | <0.017 | U | | <0.018 | J | U | <0.0089 | U | |
| | | VMP-10-5-012913-DUP | 1/29/2013 | 0.01 | J | | <0.008 | U | | <0.005 | U | | <0.01 | U | | <0.016 | U | | <0.06 | U | | <0.0034 | U | | 0.037 | | J | <0.018 | U | | <0.019 | J | U | <0.0098 | U | |
| | 10 ft | VMP-10-10-090710 | 9/7/2010 | 0.023 | | | <0.0068 | U | | 0.075 | | | <0.0088 | U | | <0.014 | U | | <0.0051 | U | | <0.0029 | U | | | | | 0.0033 | J | | 0.04 | | | <0.0083 | U | |
| | | VMP-10-10-111810 | 11/17/2010 | 0.01 | J | | <0.0067 | U | | 0.001 | J | | 0.0023 | J | | <0.013 | U | | <0.005 | U | | <0.0028 | U | | | | | 0.0018 | J | | <0.004 | U | | 0.0012 | J | |
| | | VMP-10-10-021111 | 2/11/2011 | 0.011 | | | <0.0052 | U | | 0.0011 | J | | <0.0068 | U | | <0.01 | U | | <0.0039 | U | | <0.0022 | U | | | | | 0.0081 | | | <0.0031 | U | | <0.0064 | U | |
| | | VMP-10-10-040611 | 4/6/2011 | 0.0084 | J | | <0.0068 | J | U | 0.067 | | | <0.0088 | U | | <0.014 | U | | <0.0051 | U | | <0.0029 | U | | 0.0086 | J | | 0.0015 | J | | 0.0014 | J | | <0.0083 | U | |
| | | VMP-10-10-072911 | 7/29/2011 | 0.061 | | | <0.0071 | U | | 0.072 | | | <0.0092 | U | | <0.014 | U | | <0.0054 | U | | <0.003 | U | | <0.013 | U | | 0.023 | | | 0.0088 | J | | <0.0087 | U | |
| | | VMP-10-10-110411 | 11/4/2011 | 0.012 | | J | <0.0046 | U | | 0.0063 | | | <0.006 | J | U | <0.0092 | J | U | <0.0035 | U | | <0.002 | U | | <0.0085 | U | | 0.0045 | J | | <0.011 | J | U | <0.0056 | U | |
| | | VMP-10-10-110411-DUP | 11/4/2011 | 0.051 | | J | <0.0046 | U | | 0.0067 | | | <0.006 | U | | <0.0092 | J | U | <0.0035 | U | | <0.002 | U | | <0.0085 | U | | 0.01 | J | | <0.011 | J | U | <0.0056 | U | |
| | | VMP-10-10-012512 | 1/26/2012 | 0.017 | | | <0.0045 | U | | 0.0042 | | J | <0.0059 | U | | <0.009 | U | | <0.0034 | U | | <0.0019 | U | | <0.0083 | U | UJ | 0.014 | | | <0.011 | U | | <0.0055 | U | |
| | | VMP-10-10-012512-DUP | 1/26/2012 | 0.02 | | | <0.0047 | U | | 0.048 | | J | 0.0007 | J | | <0.0094 | U | | <0.0036 | U | | <0.002 | U | | 0.026 | | J | 0.015 | | | <0.011 | U | | <0.0058 | U | |
| | | VMP-10-10-041112 | 4/11/2012 | 0.084 | | | <0.0049 | U | | 0.0096 | | | <0.0064 | U | | <0.0099 | U | | <0.037 | U | | <0.0021 | U | | 0.0039 | J | | 0.034 | | | <0.012 | U | | <0.006 | U | |
| | | VMP-10-10-071312 | 7/13/2012 | 0.029 | | | <0.0049 | U | | 0.01 | | | <0.0063 | U | | <0.0097 | U | | <0.036 | U | UJ | <0.0021 | U | | <0.0089 | U | | 0.0038 | J | | <0.012 | J | U | <0.0059 | U | |
| | | VMP-10-10-101612 | 10/16/2012 | 0.024 | J | | <0.0082 | U | | 0.95 | | | <0.01 | U | | <0.016 | U | | <0.061 | U | | <0.0035 | U | | 0.084 | | | <0.019 | U | | <0.02 | U | | <0.0099 | U | |
| | | VMP-10-10-012913 | 1/29/2013 | 0.02 | J | | <0.0065 | U | | 0.018 | | | <0.0084 | U | | <0.013 | U | | <0.049 | U | | <0.0028 | U | | 0.0032 | J | | <0.015 | U | | <0.016 | J | U | <0.0079 | U | |
| | 20 ft | VMP-10-20-090710 | 9/7/2010 | 0.036 | | | <0.0071 | U | | 0.039 | | J | <0.0092 | U | | <0.014 | U | | <0.0054 | U | | <0.003 | U | | | | | 0.0058 | | | 0.0021 | J | | <0.0087 | U | |
| | | VMP-10-20-090710-DUP | 9/7/2010 | 0.029 | | | <0.0067 | U | | 0.019 | | J | <0.0086 | U | | <0.013 | U | | <0.005 | U | | <0.0028 | U | | | | | 0.0046 | | | 0.0034 | J | | <0.0081 | U | |
| | | VMP-10-20-111810 | 11/17/2010 | 0.0093 | J | J | <0.013 | U | | <0.0078 | U | | 0.0042 | J | | <0.025 | U | | <0.0095 | U | | <0.0054 | U | | | | | <0.0072 | U | | <0.0076 | U | | <0.015 | U | |
| | | VMP-10-20-111810-Dup | 11/17/2010 | 0.14 | | J | <0.0064 | U | | 0.0017 | J | | 0.0017 | J | | <0.013 | U | | <0.0048 | U | | <0.0027 | U | | | | | 0.0014 | J | | <0.0038 | U | | <0.0078 | U | |
| | | VMP-10-20-021111 | 2/11/2011 | 0.0092 | J | | <0.0063 | U | | 0.02 | | | <0.0082 | U | | <0.013 | U | | <0.0047 | U | | <0.0027 | U | | | | | <0.0036 | U | | <0.0038 | U | | <0.0077 | U | |
| | | VMP-10-20-040611 | 4/6/2011 | 0.05 | | | <0.0076 | J | U | 0.18 | | | <0.0098 | U | | <0.015 | U | | <0.0057 | U | | <0.0032 | U | | 0.022 | | | 0.096 | | | <0.018 | J | U | <0.0092 | U | |
| | | VMP-10-20-072911 | 7/29/2011 | 0.055 | | | <0.0071 | U | | 0.12 | | | <0.0091 | U | | <0.014 | U | | <0.0053 | U | | <0.003 | U | | <0.013 | U | | 0.016 | | | <0.017 | U | | <0.0086 | U | |
| | | VMP-10-20-110411 | 11/4/2011 | 0.014 | | | <0.0046 | U | | 0.0042 | | | <0.006 | U | | <0.0092 | J | U | <0.0035 | U | | <0.002 | U | | 0.0064 | J | | 0.007 | J | | <0.011 | J | U | <0.0056 | U | |
| | | VMP-10-20-012612 | 1/26/2012 | 0.031 | | | <0.0043 | U | | 0.066 | | | 0.00095 | J | | <0.0087 | U | | <0.0033 | U | | <0.0018 | U | | 0.01 | | | 0.028 | | | <0.01 | U | | <0.0053 | U | |
| | | VMP-10-20-041212 | 4/12/2012 | 0.032 | | | <0.0049 | U | | 0.011 | | | <0.0063 | U | | <0.0097 | U | | <0.036 | U | | <0.0021 | U | | 0.0052 | J | | 0.0068 | J | | <0.012 | J | U | <0.0059 | U | |
| | | VMP-10-20-071612 | 7/16/2012 | 0.021 | J | | <0.0046 | U | | 0.0084 | | | <0.006 | U | | <0.0092 | U | | <0.035 | U | UJ | <0.002 | U | | <0.0085 | U | | 0.003 | J | | <0.011 | J | U | <0.0056 | U | |
| | | VMP-10-20-101612 | 10/16/2012 | 0.077 | | | <0.0082 | U | | 0.16 | | | <0.011 | U | | <0.016 | U | | <0.062 | U | | <0.0035 | U | | 0.013 | J | | <0.019 | U | | 0.0066 | J | | <0.01 | U | |
| | | VMP-10-20-012913 | 1/29/2013 | 0.011 | J | | <0.0071 | U | | 0.0078 | | | <0.0092 | U | | <0.014 | U | | <0.054 | U | | <0.003 | U | | 0.0051 | J | | <0.016 | U | | <0.017 | J | U | <0.0087 | U | |
| | 30 ft | VMP-10-30-041212 | 4/12/2012 | 0.087 | | | <0.0051 | U | | 0.0039 | | | <0.0068 | U | | <0.01 | U | | <0.038 | J | UJ | <0.0022 | U | | 0.0024 | J | | 0.029 | | | <0.012 | U | | <0.0062 | U | |
| | | VMP-10-30-071612 | 7/16/2012 | 0.021 | | | <0.0045 | U | | 0.013 | | | <0.0058 | U | | <0.0089 | U | | <0.034 | U | UJ | <0.0019 | U | | <0.0062 | U | | 0.0041 | J | | <0.011 | J | U | <0.0054 | U | |
| | | VMP-10-30-101612 | 10/16/2012 | 0.081 | | | <0.0078 | U | | 0.029 | | | <0.01 | U | | <0.016 | U | | <0.058 | U | | <0.0033 | U | | <0.014 | U | | 0.0059 | J | | <0.019 | U | | <0.0094 | U | |
| | | VMP-10-30-012913 | 1/29/2013 | 0.013 | J | | <0.0078 | U | | 0.0091 | | | <0.01 | U | | <0.016 | U | | <0.059 | U | | <0.0034 | U | | <0.014 | U | | <0.018 | U | | <0.019 | J | U | <0.0095 | U | |
| VMP-11 | 5 ft | VMP-11-5-090710 | 9/7/2010 | 0.036 | | | <0.0064 | U | | 0.014 | | | <0.0083 | U | | <0.013 | U | | <0.0048 | U | | <0.0027 | U | | | | | 0.0048 | | | 0.0021 | J | | <0.0078 | U | |
| | | VMP-11-5-112210 | 11/22/2010 | 0.015 | | | <0.0067 | U | | 0.00089 | J | | <0.0086 | U | | <0.013 | U | | <0.005 | U | | <0.0028 | U | | | | | 0.0034 | J | | <0.004 | J | U | <0.0081 | U | |
| | | VMP-11-5-021511 | 2/15/2011 | 0.018 | | | <0.0059 | U | | 0.0023 | J | | <0.0076 | U | | <0.012 | U | | <0.0044 | U | | <0.0025 | U | | | | | 0.0028 | J | | <0.0036 | U | | <0.0072 | U | |
| | | VMP-11-5-040611 | 4/6/2011 | 0.02 | J | | <0.056 | U | | 8.9 | | | <0.072 | U | | <0.11 | U | | <0.042 | U | | <0.024 | U | | 0.86 | | | <0.13 | U | | 0.0088 | J | | <0.068 | U | |
| | | VMP-11-5-080711 | 8/7/2011 | 0.065 | J | | <0.077 | U | | 0.1 | | | <0.1 | U | | <0.15 | U | | <0.058 | U | | <0.033 | U | | <0.14 | U | | <0.18 | U | | <0.046 | U | | <0.093 | U | |
| | | VMP-11-5-111111 | 11/11/2011 | 0.0078 | J | | <0.015 | U | | 0.016 | | | <0.02 | U | | <0.03 | U | | <0.011 | U | | <0.0065 | U | | 0.74 | | | <0.035 | U | | <0.036 | U | | <0.018 | U | |
| | | VMP-11-5-012612 | 1/26/2012 | 0.014 | | | <0.0045 | U | | 0.0017 | J | | <0.0059 | U | | <0.009 | U | | <0.0034 | U | | <0.0019 | U | | <0.0083 | U | | 0.0036 | J | | <0.011 | U | | <0.0055 | U | |
| | | VMP-11-5-041912 | 4/19/2012 | 0.042 | | | <0.0051 | U | | 0.061 | | | <0.0066 | U | | <0.01 | U | | <0.038 | U | | <0.0022 | U | | 0.0034 | J | | 0.047 | | | <0.012 | J | U | <0.0062 | U | |
| | | VMP-11-5-071912 | 7/16/2012 | 0.036 | | | <0.0066 | J | U | 0.006 | | | <0.0085 | U | | <0.013 | U | | <0.049 | U | UJ | <0.0028 | U | | <0.012 | U | | 0.004 | J | | <0.016 | J | U | <0.008 | U | |
| | | VMP-11-5-101612 | 10/16/2012 | 0.028 | J | | <0.0073 | U | | 0.003 | J | | <0.0095 | U | | <0.015 | U | | <0.055 | U | | <0.0031 | U | | <0.013 | U | | 0.0038 | J | | <0.018 | U | | <0.0089 | U | |
| | | VMP-11-5-012913 | 1/29/2013 | 13 | | | <0.37 | U | | <0.23 | U | | <0.48 | U | | <0.74 | U | | <2.8 | U | | <0.16 | U | | <0.68 | U | | <0.85 | U | | 0.16 | J | | <0.45 | U | |
| | 8 ft | VMP-11-8-090810 | 9/8/2010 | 0.017 | | | <0.0067 | U | | 0.024 | | | <0.0086 | U | | <0.013 | U | | <0.005 | U | | <0.0028 | U | | | | | 0.0023 | J | | <0.0049 | | U | <0.0081 | U | |
| | | VMP-11-8-112210 | 11/22/2010 | 0.014 | | | <0.0067 | U | | 0.0017 | J | | <0.0086 | U | | <0.013 | U | | <0.005 | U | | <0.0028 | U | | | | | <0.0038 | U | | <0.004 | J | U | <0.0081 | U | |
| | | VMP-11-8-021111 | 2/11/2011 | 0.0085 | J | | <0.0065 | U | | 0.03 | | | <0.0084 | U | | <0.013 | U | | <0.0048 | U | | <0.0028 | U | | | | | <0.0037 | U | | <0.0039 | U | | <0.0079 | U | |
| | | VMP-11-8-021111-DUP | 2/11/2011 | 0.0066 | J | | <0.0061 | U | | 0.014 | | | <0.0079 | U | | <0.012 | U | | <0.0046 | U | | <0.0026 | U | | | | | <0.0035 | U | | <0.0036 | U | | <0.0074 | U | |
| | | VMP-11-8-040611 | 4/6/2011 | <0.053 | U | | <0.029 | U | | 6.2 | | | <0.037 | U | | <0.057 | U | | <0.022 | U | | <0.012 | U | | 0.23 | | | <0.065 | U | | <0.069 | U | | <0.035 | U | |
| | | VMP-11-8-040611-DUP | 4/6/2011 | 0.018 | J | | <0.025 | U | | 5.5 | | | <0.032 | U | | <0.05 | U | | <0.019 | U | | <0.011 | U | | 0.17 | | | <0.057 | U | | 0.0041 | J | | <0.03 | U | |
| | | VMP-11-8-080711 | 8/7/2011 | 0.057 | J | | <0.077 | U | | 0.33 | | | <0.1 | U | | <0.15 | U | | <0.058 | U | | <0.033 | U | | <0.14 | U | | 0.028 | J | | <0.046 | U | | <0.093 | U | |
| | | VMP-11-8-111411 | 11/14/2011 | 0.019 | | | <0.0046 | U | | 0.7 | | | <0.0059 | U | | <0.0091 | U | | <0.0034 | U | | <0.0019 | U | | 0.042 | | | 0.0052 | J | | 0.0037 | J | | <0.0055 | U | |
| | | VMP-11-8-012612 | 1/26/2012 | 0.0075 | J | | <0.0044 | U | | 0.0016 | J | | <0.0057 | U | | <0.0088 | U | | <0.0033 | U | | <0.0019 | U | | <0.0081 | U | | 0.0035 | J | | <0.011 | U | | <0.0054 | U | |
| | | VMP-11-8-041912 | 4/19/2012 | 0.039 | | | <0.0051 | U | | 0.11 | | | <0.0066 | U | | <0.01 | U | | <0.038 | U | | <0.0022 | U | | 0.0042 | J | | 0.054 | | | <0.012 | J | U | <0.0062 | U | |
| | | VMP-11-8-072012 | 7/20/2012 | 0.025 | | | <0.0051 | U | | 0.0017 | J | | <0.0066 | U | | <0.01 | U | | <0.038 | U | | <0.0022 | U | | <0.0093 | U | | <0.012 | U | | <0.012 | U | | <0.0062 | U | |
| | | VMP-11-8-101612 | 10/16/2012 | 0.08 | | | <0.0074 | U | | 0.012 | | | <0.0096 | U | | <0.015 | U | | <0.056 | U | | <0.0032 | U | | <0.014 | U | | 0.02 | | | <0.018 | U | | <0.009 | U | |
| | | VMP-11-8-101612-Dup | 10/16/2012 | 0.065 | | | <0.0075 | U | | 0.012 | | | <0.0097 | U | | <0.015 | U | | <0.056 | U | | <0.0032 | U | | <0.014 | U | | 0.022 | | | <0.018 | U | | <0.0091 | U | |
| | | VMP-11-8-012913 | 1/29/2013 | 5.9 | | | <0.051 | U | | <0.031 | U | | <0.066 | U | | <0.1 | U | | <0.38 | U | | <0.022 | U | | <0.094 | U | | <0.12 | U | | 0.018 | J | | <0.062 | U | |
| | 29 ft | VMP-11-29-090810 | 9/8/2010 | <0.31 | U | | <0.17 | U | | 120 | | | <0.22 | U | | <0.33 | U | | <0.12 | U | | <0.071 | U | | | | | <0.095 | U | | <0.1 | U | | <0.2 | U | |
| | | VMP-11-29-112210 | 11/22/2010 | <4.4 | U | | <2.4 | U | | 460 | | | <3.1 | U | | <4.8 | U | | <1.8 | U | | <1 | U | | | | | <1.4 | U | | <1.4 | U | | <2.9 | U | |
| | | VMP-11-29-112210-Dup | 11/22/2010 | <3 | U | | <1.6 | U | | 440 | | | <2.1 | U | | <3.3 | U | | <1.2 | U | | <0.71 | U | | | | | <0.94 | U | | <1 | U | | <2 | U | |
| | | VMP-11-29-021411 | 2/14/2011 | 0.01 | J | | <0.0065 | U | | 0.0042 | | | <0.0084 | U | | <0.013 | U | | <0.0048 | U | | <0.0028 | U | | | | | <0.0037 | U | | <0.0039 | U | | <0.0079 | U | |
| | | VMP-11-29-040611 | 4/6/2011 | 0.023 | J | | <0.049 | U | | 9.4 | | | <0.063 | U | | <0.098 | U | | <0.037 | U | | <0.021 | U | | 0.26 | | | <0.11 | U | | 0.0075 | J | | <0.059 | U | |
| | | VMP-11-29-082511 | 8/25/2011 | 0.018 | | | <0.0071 | U | | 0.0039 | J | | <0.0092 | U | | <0.014 | U | | <0.0054 | U | | <0.003 | U | | <0.013 | U | | 0.0069 | J | | <0.017 | U | | <0.0087 | U | |
| | | VMP-11-29-082511-Dup | 8/25/2011 | 0.023 | | | <0.0071 | U | | 0.0039 | J | | <0.0092 | U | | <0.014 | U | | <0.0054 | U | | <0.003 | U | | <0.013 | U | | 0.0062 | J | | <0.017 | U | | <0.0087 | U | |
| | | VMP-11-29-111411 | 11/14/2011 | 0.015 | | | <0.0045 | U | | 0.009 | | | <0.0059 | U | | <0.009 | U | | <0.0034 | U | | <0.0019 | U | | <0.0083 | U | | 0.003 | J | | <0.011 | U | | <0.0055 | U | |
| | | VMP-11-29-012612 | 1/26/2012 | 0.0049 | J | | <0.0043 | U | | 0.0016 | J | | 0.0026 | J | | <0.0087 | U | | <0.0033 | U | | <0.0018 | U | | <0.008 | U | | 0.0012 | J | | <0.01 | U | | <0.0053 | U | |
| | | VMP-11-29-042712 | 4/27/2012 | 0.014 | J | | <0.0045 | U | | 0.14 | | | <0.0059 | U | | <0.009 | U | | <0.034 | U | | <0.0019 | U | | <0.0083 | U | | 0.016 | | | <0.011 | J | U | <0.0055 | U | |
| | | VMP-11-29-072012 | 7/23/2012 | 0.11 | | | <0.0045 | J | U | 0.018 | | | 0.0023 | J | | <0.009 | U | | <0.034 | U | | <0.0019 | U | | 0.005 | J | | 0.021 | | | 0.009 | J | | <0.0055 | U | |
| | | VMP-11-29-101612 | 10/16/2012 | 0.027 | J | | <0.0077 | U | | 0.0015 | J | | <0.0099 | U | | <0.015 | U | | <0.057 | U | | <0.0033 | U | | <0.014 | U | | <0.017 | U | | <0.018 | U | | <0.0093 | U | |
| | | VMP-11-29-012913 | 1/29/2013 | 0.04 | | | <0.0075 | U | | 0.049 | | | 0.028 | | | <0.015 | U | | <0.056 | U | | <0.0032 | U | | 0.0041 | J | | 0.0046 | J | | <0.018 | J | U | <0.0091 | U | |
| | 38 ft | VMP-11-38-042312 | 4/23/2012 | <0.62 | U | | <1.4 | U | | 370 | | | <0.44 | U | | <0.68 | U | | <0.25 | U | | <0.14 | U | | 0.13 | J | | <0.77 | U | | <0.2 | U | | <0.41 | U | |
| | | VMP-11-38-042312-Dup | 4/23/2012 | <2.2 | U | | <4.7 | U | | 380 | | | <1.5 | U | | <2.4 | U | | <0.89 | U | | <0.51 | U | | <2.2 | U | | <2.7 | U | | <0.71 | U | | <1.4 | U | |
| | | VMP-11-38-072312 | 7/23/2012 | <1 | U | | <0.56 | U | | 170 | | | <0.73 | U | | <1.1 | U | | <0.42 | U | | <0.24 | U | | <1 | U | | <1.3 | U | | <0.34 | U | | <0.68 | U | |
| | | VMP-11-38-101612 | 10/16/2012 | 0.026 | J | | <0.0078 | U | | 0.01 | | | <0.01 | U | | <0.016 | U | | <0.058 | U | | <0.0033 | U | | 0.012 | J | | <0.018 | U | | 0.074 | | | <0.0094 | U | |
| | | VMP-11-38-013013 | 1/30/2013 | 0.022 | J | | <0.0071 | U | | 0.0074 | | | 0.0061 | J | | <0.014 | U | | <0.054 | U | | <0.003 | U | | 0.012 | J | | <0.016 | U | | <0.017 | J | U | <0.0087 | U | |

SEE LAST PAGE OF TABLE FOR NOTES

**TABLE 6**
**CUMULATIVE SUMMARY OF SOIL VAPOR ANALYTICAL DETECTIONS AND SCREENING RESULTS: PUBLIC WORKS YARD AND WRR - VOCS**

| Location | Depth | Sample ID | Sample Date | Acetone 750000 | | | alpha-Chlorotoluene | | | Benzene 2.8 | | | Bromodichloromethane 450000 | | | Bromoform 52 | | | Bromomethane 42 | | | 1,3-Butadiene | | | Butane | | | 2-Butanone 40000 | | | Carbon disulfide 5300 | | | Carbon tetrachloride 1.5 | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals |
| VMP-12 | 5 ft | VMP-12-5-090310 | 9/3/2010 | <13 | U | | <7 | U | | 230 | | | <9 | U | | <14 | U | | <5.2 | U | | <3 | U | | | | | <4 | U | | <4.2 | U | | <8.5 | U | |
| | | VMP-12-5-120310 | 12/3/2010 | <130 | U | | <69 | U | | 16000 | | | <89 | U | | <140 | U | | <52 | U | | <29 | U | | | | | <39 | U | | <41 | U | | <84 | U | |
| | | VMP-12-5-021511 | 2/15/2011 | <5.8 | U | | <3.2 | U | | 80 | | | <4.1 | U | | <6.3 | U | | <2.4 | U | | <1.3 | U | | | | | <1.8 | U | | <1.9 | U | | <3.8 | U | |
| | | VMP-12-5-041911 | 4/19/2011 | 17 | J | | <23 | U | | 5.8 | J | | <30 | U | | <46 | U | | <17 | U | | <9.9 | U | | 3200 | | | <53 | U | | <14 | U | | <28 | U | |
| | | VMP-12-5-080411 | 8/4/2011 | <11 | U | | <6 | U | | 200 | | | <7.7 | U | | <12 | U | | <4.5 | U | | <2.6 | U | | 2800 | | | <14 | U | | <3.6 | U | | <7.3 | U | |
| | | VMP-12-5-111611 | 11/16/2011 | <0.0077 | U | | <0.0042 | U | | 0.9 | | | <0.0055 | U | | <0.0084 | U | | <0.0032 | U | | <0.0018 | U | | 0.098 | | | 0.0017 | J | | 0.0055 | J | | <0.0051 | U | |
| | | VMP-12-5-012412 | 1/24/2012 | <0.087 | J | U | <0.19 | U | | 6.8 | | | <0.061 | U | | <0.38 | U | | <0.036 | U | | <0.02 | U | | 3 | | | <0.11 | U | | <0.028 | U | | <0.058 | U | |
| | | VMP-12-5-041912 | 4/19/2012 | 0.021 | J | | <0.0047 | U | | 0.063 | | | <0.0061 | U | | <0.0094 | U | | <0.036 | U | | <0.002 | U | | 0.0057 | J | | 0.0051 | J | | <0.011 | J | U | <0.0058 | U | |
| | | VMP-12-5-072612 | 7/26/2012 | 0.057 | | | <0.005 | U | | 0.12 | | J | <0.0065 | U | | <0.01 | U | | <0.038 | U | | <0.0022 | U | | 0.014 | | | 0.0057 | J | | <0.012 | J | U | <0.0061 | U | |
| | | VMP-12-5-072612-Dup | 7/26/2012 | 0.032 | | | <0.0046 | U | | 0.0018 | J | J | <0.006 | U | | <0.0092 | U | | <0.034 | U | | <0.002 | U | | <0.0085 | U | | <0.01 | U | | <0.011 | J | U | <0.0056 | U | |
| | | VMP-12-5-102412 | 10/24/2012 | 0.023 | J | | <0.0078 | U | | 0.025 | | | <0.01 | U | | <0.016 | U | | <0.058 | U | | <0.0033 | U | | <0.014 | U | | 0.0054 | J | | <0.019 | J | U | <0.0094 | U | |
| | | VMP-12-5-021813 | 2/18/2013 | 0.0096 | J | | <0.007 | U | | 0.012 | | | <0.009 | U | | <0.014 | U | | <0.052 | U | | <0.003 | U | | 0.0074 | J | | 0.0038 | J | | <0.017 | U | | <0.0085 | U | |
| | 11.5 ft | VMP-12-11.5-090310 | 9/3/2010 | <16 | U | | <8.9 | U | | 4100 | | | <12 | U | | <18 | U | | <6.7 | U | | <3.8 | U | | | | | <5.1 | U | | <5.4 | U | | <11 | U | |
| | | VMP-12-11.5-120310 | 12/3/2010 | <14 | U | | <7.7 | U | | 2000 | | | <10 | U | | <15 | U | | <5.8 | U | | <3.3 | U | | | | | <4.4 | U | | <4.6 | U | | <9.4 | U | |
| | | VMP-12-11.5-021511 | 2/15/2011 | <13 | U | | <6.9 | U | | 1600 | | | <9 | U | | <14 | U | | <5.2 | U | | <3 | U | | | | | <4 | U | | <4.2 | U | | <8.4 | U | |
| | | VMP-12-11.5-021511-DUP | 2/15/2011 | <11 | U | | <6 | U | | 1300 | | | <7.7 | U | | <12 | U | | <4.5 | U | | <2.6 | U | | | | | <3.4 | U | | <3.6 | U | | <7.3 | U | |
| | | VMP-12-11.5-041911 | 4/19/2011 | 15 | J | | <21 | U | | 810 | | | <27 | U | | <42 | U | | <16 | U | | <8.9 | U | | 4300 | | | <48 | U | | <12 | U | | <25 | U | |
| | | VMP-12-11.5-080411 | 8/4/2011 | <13 | U | | <7.3 | U | | 1200 | | | <9.4 | U | | <14 | U | | <5.5 | U | | <3.1 | U | | 1500 | | | <17 | U | | <4.4 | U | | <8.9 | U | |
| | | VMP-12-11.5-111611 | 11/16/2011 | <0.11 | U | | <0.058 | U | | 4.6 | | | <0.075 | U | | <0.12 | U | | <0.044 | U | | <0.025 | U | | 2.8 | | | <0.13 | U | | <0.14 | U | | <0.071 | U | |
| | | VMP-12-11.5-012412 | 1/24/2012 | <1 | U | | <2.2 | U | | 4.1 | | | <0.7 | U | | <4.3 | U | | <0.41 | U | | <0.23 | U | | 100 | | | <1.2 | U | | <0.33 | U | | <0.66 | U | |
| | | VMP-12-11.5-041912 | 4/19/2012 | <0.091 | U | | <0.049 | U | | 0.065 | | | <0.064 | U | | <0.099 | U | | <0.037 | U | | <0.021 | U | | 0.3 | | | <0.11 | U | | <0.03 | U | | <0.06 | U | |
| | | VMP-12-11.5-082012 | 8/20/2012 | 0.031 | J | J | <0.0078 | U | | 0.044 | | | <0.01 | U | | <0.016 | U | | 0.0032 | J | | <0.0034 | U | | <0.014 | U | | 0.048 | | | <0.019 | J | U | <0.0095 | U | |
| | | VMP-12-11.5-102612 | 10/26/2012 | 0.026 | J | | <0.0075 | U | | 0.0098 | | | <0.0097 | U | | <0.015 | U | | <0.056 | U | | <0.0032 | U | | 0.041 | | | 0.0055 | J | | <0.018 | U | | <0.0091 | U | |
| | | VMP-12-11.5-021813 | 2/18/2013 | 0.0097 | J | | <0.0075 | U | | 0.0008 | J | | <0.0097 | U | | <0.015 | U | | <0.056 | U | | <0.0032 | U | | <0.014 | U | | <0.017 | U | | <0.018 | U | | <0.0091 | U | |
| | 25 ft | VMP-12-25-090310 | 9/3/2010 | <21 | U | | <11 | U | | 14000 | | | <15 | U | | <23 | U | | <8.5 | U | | <4.9 | U | | | | | <6.5 | U | | <6.8 | U | | <14 | U | |
| | | VMP-12-25-120310 | 12/3/2010 | <1 | U | | <0.56 | U | | 3.8 | | | <0.73 | U | | <1.1 | U | | <0.42 | U | | <0.24 | U | | | | | <0.32 | U | | <0.34 | U | | <0.68 | U | |
| | | VMP-12-25-021511 | 2/15/2011 | 6.9 | J | | <14 | U | | 7600 | | | <18 | U | | <27 | U | | <10 | U | | <5.9 | U | | | | | <7.8 | U | | <8.3 | U | | <17 | U | |
| | | VMP-12-25-041911 | 4/19/2011 | 27 | J | | <22 | U | | 8300 | | | <29 | U | | <45 | U | | <17 | U | | <9.6 | U | | 3500 | | | <51 | U | | <14 | U | | <27 | U | |
| | | VMP-12-25-080411 | 8/4/2011 | <26 | U | | <14 | U | | 3500 | | | <18 | U | | <28 | U | | <11 | U | | <6.1 | U | | 4000 | | | <32 | U | | <8.6 | U | | <17 | U | |
| | | VMP-12-25-111611 | 11/16/2011 | <30 | U | | <16 | U | | 2600 | | | <21 | U | | <32 | U | | <12 | U | | <6.9 | U | | 3400 | | | 7.8 | J | | 23 | J | | <20 | U | |
| | | VMP-12-25-012412 | 1/24/2012 | <11 | U | | <25 | U | | 5100 | | | <8 | U | | <50 | U | | <4.7 | U | | <2.6 | U | | 3200 | | | <14 | U | | <3.7 | U | | <7.6 | U | |
| | | VMP-12-25-012412-DUP | 1/24/2012 | 7.3 | J | | <180 | U | | 5400 | | | <59 | U | | <360 | U | | <34 | U | | <19 | U | | 3300 | | | <100 | U | | <27 | U | | <55 | U | |
| | | VMP-12-25-041912 | 4/19/2012 | <8.7 | U | | <4.7 | U | | 500 | | | <6.1 | U | | <9.4 | U | | <3.6 | U | | <2 | U | | 360 | | | <11 | U | | <2.8 | U | | <5.8 | U | |
| | | VMP-12-25-072712 | 7/27/2012 | <9.5 | U | | <5.2 | U | | 24 | | | <6.7 | U | | <10 | U | | <3.9 | U | | <2.2 | U | | 28 | | | <12 | U | | <3.1 | U | | <6.3 | U | |
| | | VMP-12-25-072712-Dup | 7/27/2012 | <9.5 | U | | <5.2 | U | | 30 | | | <6.7 | U | | <10 | U | | <3.9 | U | | <2.2 | U | | 34 | | | <12 | U | | <3.1 | U | | <6.3 | U | |
| | | VMP-12-25-102512 | 10/25/2012 | <4.1 | U | | <2.2 | U | | 0.47 | J | | <2.9 | U | | <4.5 | U | | <1.7 | U | | <0.96 | U | | 2.9 | J | | <5.1 | U | | <1.3 | U | | <2.7 | U | |
| | | VMP-12-25-021513 | 2/15/2013 | 0.93 | J | J | <4.2 | U | | 5.8 | | J | <5.4 | U | | <8.3 | U | | <3.1 | U | | <1.8 | U | | 53 | | J | <9.5 | U | | <2.5 | U | | <5.1 | U | |
| | 39 ft | VMP-12-39-041911 | 4/19/2011 | 24 | J | | <22 | U | | 10000 | | | <28 | U | | <44 | U | | <16 | U | | <9.3 | U | | 3200 | | | <50 | U | | <13 | U | | <26 | U | |
| | | VMP-12-39-012412 | 1/24/2012 | <83 | U | | <180 | U | | 5400 | | | <59 | U | | <360 | U | | <34 | U | | <19 | U | | 3300 | | | <100 | U | | <27 | U | | <55 | U | |
| | | VMP-12-39-041912 | 4/19/2012 | 5.6 | J | | <23 | U | | 1400 | | | <29 | U | | <45 | U | | <17 | U | | <9.7 | U | | 930 | | | <52 | U | | <14 | U | | <28 | U | |
| | | VMP-12-39-072612 | 7/26/2012 | <19 | U | | <10 | U | | 3100 | | | <13 | U | | <21 | U | | <7.8 | U | | <4.4 | U | | 580 | | | <24 | U | | 1.1 | J | | <13 | U | |
| | | VMP-12-39-102412 | 10/24/2012 | <50 | U | | <27 | U | | 1200 | | | <36 | U | | <55 | U | | <20 | U | | <12 | U | | 93 | | | <62 | U | | 5.3 | J | | <33 | U | |
| | | VMP-12-39-021513 | 2/15/2013 | <23 | U | | <12 | U | | 4100 | | | <16 | U | | <25 | U | | <9.4 | U | | <5.4 | U | | 320 | | | <28 | U | | <7.5 | U | | <15 | U | |
| VMP-13 | 5 ft | VMP 13-5-091310 | 9/13/2010 | 0.032 | J | | <0.046 | U | | 9 | | | <0.059 | U | | <0.091 | U | | <0.034 | U | | <0.019 | U | | | | | 0.0055 | J | | 0.018 | J | | <0.055 | U | |
| | | VMP-13-5-120110 | 12/1/2010 | 0.013 | | | <0.006 | U | | 0.0049 | | | <0.0078 | U | | <0.012 | U | | <0.0045 | U | | <0.0026 | U | | | | | <0.0034 | J | U | <0.0036 | U | | <0.0073 | U | |
| | | VMP-13-5-021811 | 2/18/2011 | 0.013 | J | | <0.0071 | U | | 0.0023 | J | | <0.0092 | U | | <0.014 | U | | <0.0054 | U | | <0.003 | U | | | | | 0.0019 | J | | <0.0043 | U | | <0.0087 | U | |
| | | VMP-13-5-040511 | 4/5/2011 | 0.017 | J | | <0.014 | U | | 0.048 | | | <0.018 | U | | <0.028 | U | | <0.011 | U | | <0.0061 | U | | 0.018 | J | | <0.032 | U | | <0.034 | U | | <0.017 | U | |
| | | VMP-13-5-080911 | 8/9/2011 | 0.061 | | J | <0.015 | J | U | 0.026 | | J | <0.02 | U | | <0.031 | U | | <0.011 | U | | <0.0065 | U | | 1.7 | | J | 0.013 | J | | <0.037 | U | | <0.019 | U | |
| | | VMP-13-5-080911-DUP | 8/9/2011 | 0.095 | | J | <0.014 | U | | 0.018 | | J | <0.018 | U | | <0.027 | U | | <0.01 | U | | <0.0058 | U | | 1.2 | | J | 0.015 | J | | <0.033 | J | U | <0.017 | U | |
| | | VMP-13-5-111411 | 11/14/2011 | 0.01 | | | <0.0048 | U | | 0.011 | | | <0.0062 | U | | <0.0095 | U | | <0.0036 | U | | <0.002 | U | | 0.0032 | J | | 0.003 | J | | 0.0018 | J | | <0.0058 | U | |
| | | VMP-13-5-012712 | 1/27/2012 | 0.034 | J | J | <0.16 | U | | 8.2 | | J | <0.052 | U | | <0.32 | U | | <0.03 | U | | <0.017 | U | | 0.21 | | J | <0.091 | U | | <0.024 | U | | <0.049 | U | |
| | | VMP-13-5-042012 | 4/20/2012 | 0.019 | J | | <0.0046 | J | U | 0.0027 | J | | <0.006 | U | | <0.0092 | U | | <0.035 | U | | <0.002 | U | | <0.0085 | U | | 0.019 | | | 0.002 | J | | <0.0056 | U | |
| | | VMP-13-5-071912 | 7/19/2012 | 0.1 | | | <0.0048 | U | UJ | 0.0039 | | | <0.0063 | U | | <0.0097 | U | | <0.036 | U | | <0.0021 | U | | 0.0029 | J | J | 0.017 | | | <0.012 | U | | <0.0059 | U | |
| | | VMP-13-5-071912-Dup | 7/19/2012 | 0.097 | | | <0.0048 | U | UJ | 0.004 | | | <0.0063 | U | | <0.0097 | U | | <0.036 | U | | <0.0021 | U | | | J | J | 0.016 | | | <0.012 | U | | <0.0059 | U | |
| | | VMP-13-5-100912 | 10/9/2012 | 0.023 | J | | <0.0075 | U | | 0.017 | | | <0.0097 | U | | <0.015 | U | | <0.056 | U | | <0.0032 | U | | <0.014 | U | | 0.0055 | J | | <0.018 | U | | <0.0091 | U | |
| | | VMP-13-5-012913 | 1/29/2013 | 0.0062 | J | | <0.008 | U | | 0.0038 | J | | <0.01 | U | | <0.016 | U | | <0.06 | U | | <0.0034 | U | | <0.015 | U | | <0.018 | U | | <0.019 | J | U | <0.0098 | U | |
| | 10.5 ft | VMP 13-10.5-091310 | 9/13/2010 | 0.017 | J | | <0.017 | U | | 3.3 | | | <0.022 | U | | <0.034 | U | | <0.013 | U | | <0.0072 | U | | | | | <0.0096 | U | | 0.0056 | J | | <0.02 | U | |
| | | VMP-13-10.5-091310-Dup | 9/13/2010 | 0.07 | | | <0.016 | U | | 3.4 | | | <0.021 | U | | <0.033 | U | | <0.012 | U | | <0.007 | U | | | | | 0.0036 | J | | 0.02 | | | <0.02 | U | |
| | | VMP-13-10.5-120110 | 12/1/2010 | 0.012 | | | <0.0067 | U | | 0.0045 | | | <0.0087 | U | | <0.013 | U | | <0.005 | U | | <0.0029 | U | | | | | <0.0038 | J | U | <0.004 | U | | <0.0081 | U | |
| | | VMP-13-10.5-120110-DUP | 12/1/2010 | <0.013 | J | U | <0.007 | U | | 0.0066 | | | <0.009 | U | | <0.014 | U | | <0.0052 | U | | <0.003 | U | | | | | <0.004 | J | U | <0.0042 | U | | <0.0085 | U | |
| | | VMP-13-10.5-021811 | 2/18/2011 | 2.8 | J | | <2.8 | U | | 420 | | | <3.6 | U | | <5.5 | U | | <2.1 | U | | <1.2 | U | | | | | <1.6 | U | | <1.7 | U | | <3.4 | U | |
| | | VMP-13-10.5-021811-DUP | 2/18/2011 | <4.9 | U | | <2.7 | U | | 420 | | | <3.4 | U | | <5.3 | U | | <2 | U | | <1.1 | U | | | | | <1.5 | U | | <1.6 | U | | <3.2 | U | |
| | | VMP-13-10.5-040511-DUP | 4/5/2011 | 0.012 | J | | <0.0071 | U | | 0.017 | | | <0.0092 | U | | <0.014 | U | | <0.0054 | U | | <0.003 | U | | 0.012 | J | | <0.016 | U | | <0.017 | U | | <0.0087 | U | |
| | | VMP-13-10.5-080911 | 8/9/2011 | <0.29 | U | | <0.16 | U | | 51 | | | <0.2 | U | | <0.31 | U | | <0.12 | U | | <0.067 | U | | 33 | | | <0.36 | U | | <0.094 | U | | <0.19 | U | |
| | | VMP-13-10.5-111411 | 11/14/2011 | 0.013 | | | <0.0046 | U | | 0.013 | | | <0.0059 | U | | <0.0091 | U | | <0.0034 | U | | <0.0019 | U | | 0.0054 | J | | 0.0037 | J | | <0.011 | U | | <0.0055 | U | |
| | | VMP-13-10.5-012712 | 1/26/2012 | 0.02 | J | | <0.013 | U | | 2.6 | | J | <0.016 | U | | <0.025 | U | | <0.0095 | U | | <0.0054 | U | | 0.05 | | | <0.029 | U | | <0.03 | U | | <0.015 | U | |
| | | VMP-13-10.5-012712-DUP | 1/26/2012 | <0.033 | U | | <0.018 | U | | 3.9 | | J | <0.023 | U | | <0.036 | U | | <0.014 | U | | <0.0077 | U | | 0.08 | | | <0.041 | U | | <0.044 | U | | <0.022 | U | |
| | | VMP-13-10.5-042012 | 4/20/2012 | 0.027 | | | 0.0014 | J | | 0.0088 | | | <0.0059 | U | | <0.009 | U | | <0.034 | U | | <0.0019 | U | | 0.0046 | J | | 0.015 | | | <0.011 | J | U | <0.0055 | U | |
| | | VMP-13-10.5-071912 | 7/19/2012 | 0.15 | | | <0.0048 | U | UJ | 0.0078 | | | <0.0063 | U | | <0.0097 | U | | <0.036 | U | | <0.0021 | U | | 0.0061 | J | J | 0.021 | | | 0.0055 | J | | <0.0059 | U | |
| | | VMP-13-10.5-100912 | 10/9/2012 | 0.024 | J | | <0.0064 | U | | 0.025 | | | <0.0083 | U | | <0.013 | U | | <0.048 | U | | <0.0027 | U | | <0.012 | U | | 0.0036 | J | | <0.015 | U | | <0.0078 | U | |
| | | VMP-13-10.5-100912-Dup | 10/9/2012 | 0.011 | J | | <0.0077 | U | | 0.023 | | | <0.0099 | U | | <0.015 | U | | <0.057 | U | | <0.0033 | U | | <0.014 | U | | <0.017 | U | | <0.018 | U | | <0.0093 | U | |
| | | VMP-13-10.5-013013 | 1/30/2013 | 0.01 | J | | <0.0065 | U | | 0.0021 | J | | <0.0084 | U | | <0.013 | U | | <0.049 | U | | <0.0028 | U | | <0.012 | U | | <0.015 | U | | <0.016 | J | U | <0.0079 | U | |
| | 21.5 ft | VMP 13-21.5-091310 | 9/13/2010 | <23 | U | | <12 | U | | 5800 | | | <16 | U | | <25 | U | | <9.4 | U | | <5.4 | U | | | | | <7.1 | U | | <7.5 | U | | <15 | U | |
| | | VMP-13-21.5-120110 | 12/1/2010 | <44 | U | | <24 | U | | 5400 | | | <31 | U | | <48 | U | | <18 | U | | <10 | U | | | | | <14 | U | | <15 | U | | <30 | U | |
| | | VMP-13-21.5-021811 | 2/18/2011 | <6.6 | U | | <3.6 | U | | 640 | | | <4.7 | U | | <7.2 | U | | <2.7 | U | | <1.5 | U | | | | | <2.1 | U | | 0.36 | J | | <4.4 | U | |
| | | VMP-13-21.5-040511 | 4/5/2011 | <9.6 | U | | <5.2 | U | | 1400 | | | <6.8 | U | | <10 | U | | <3.9 | U | | <2.2 | U | | 35 | | | <12 | U | | <3.1 | U | | <6.4 | U | |
| | | VMP-13-21.5-080911 | 8/9/2011 | <1.2 | U | | <0.65 | U | | 830 | | | <0.84 | U | | <1.3 | U | | <0.49 | U | | <0.28 | U | | 59 | | | <1.5 | U | | <0.39 | U | | <0.79 | U | |
| | | VMP-13-21.5-111411 | 11/14/2011 | 3.6 | J | | <3 | U | | 420 | | | <3.8 | U | | <5.9 | U | | <2.2 | U | | <1.3 | U | | 32 | | | 0.98 | J | | 3.5 | J | | <3.6 | U | |
| | | VMP-13-21.5-111411-DUP | 11/14/2011 | 3.7 | J | | <3 | U | | 410 | | | <3.8 | U | | <5.9 | U | | <2.2 | U | | <1.3 | U | | 31 | | | <6.8 | U | | 3.4 | J | | <3.6 | U | |
| | | VMP-13-21.5-012712 | 1/27/2012 | <1.3 | U | | <2.8 | U | | 370 | | J | <0.9 | U | | <5.5 | U | | <0.52 | U | | <0.3 | U | | 16 | | J | <1.6 | U | | <0.42 | U | | <0.84 | U | |
| | | VMP-13-21.5-042012 | 4/20/2012 | 0.17 | J | | <0.077 | U | | 0.098 | | | <0.1 | U | | <0.15 | U | | <0.58 | U | | <0.033 | U | | 5.6 | | | <0.18 | U | | 0.15 | J | | <0.094 | U | |
| | | VMP-13-21.5-071912 | 7/19/2012 | 0.18 | | | <0.0048 | U | UJ | 0.009 | | | <0.0063 | U | | <0.0097 | U | | <0.036 | U | | <0.0021 | U | | 0.13 | J | J | 0.038 | | | 0.0047 | J | | <0.0059 | U | |
| | | VMP-13-21.5-100912 | 10/9/2012 | 0.012 | J | | <0.0078 | U | | 0.088 | | | <0.01 | U | | <0.016 | U | | <0.059 | U | | <0.0034 | U | | 0.24 | | | <0.018 | U | | 0.0047 | J | | <0.0095 | U | |
| | | VMP-13-21.5-013013 | 1/30/2013 | 0.01 | J | | <0.0077 | U | | 0.0088 | | | <0.0099 | U | | <0.015 | U | | <0.057 | U | | <0.0033 | U | | <0.014 | U | | <0.017 | U | | 0.0078 | J | | <0.0093 | U | |
| | 29.5 ft | VMP-13-29.5-021811 | 2/18/2011 | <200 | U | | <110 | U | | 17000 | | | <140 | U | | <220 | U | | <84 | U | | <48 | U | | | | | <64 | U | | <67 | U | | <140 | U | |
| | | VMP-13-29.5-040511 | 4/5/2011 | <130 | U | | <72 | U | | 23000 | | | <94 | U | | <140 | U | | <54 | U | | <31 | U | | 94 | J | | <160 | U | | <44 | U | | <88 | U | |
| | | VMP-13-29.5-013012 | 1/30/2012 | <4.1 | U | | <2.2 | U | | 8600 | | | <2.9 | U | | <4.4 | U | | <1.7 | U | | <0.94 | U | | 32 | | J | <5 | U | | <1.3 | U | | <2.7 | U | |
| | | VMP-13-29.5-042012 | 4/20/2012 | 3.2 | J | | <2.9 | U | | 2300 | | | <3.8 | U | | <5.8 | U | | <22 | U | | <1.2 | U | | 57 | | | <6.6 | U | | 2.4 | J | | <3.5 | U | |
| | | VMP-13-29.5-071912 | 7/19/2012 | <15 | U | | <8.3 | U | | 2600 | | | <11 | U | | <17 | U | | <6.2 | U | | <3.6 | U | | 30 | | | <19 | U | | <5 | U | | <10 | U | |
| | | VMP-13-29.5-100912 | 10/9/2012 | <14 | U | | <7.8 | U | | 630 | | | <10 | U | | <16 | U | | <5.9 | U | | <3.4 | U | | 51 | | | <18 | U | | <4.7 | U | | 1.5 | J | |
| | | VMP-13-29.5-013013 | 1/30/2013 | 4.5 | J | | <3.3 | U | | 580 | | | <4.3 | U | | <6.6 | U | | <25 | U | | <1.4 | U | | <6.1 | U | | <7.5 | U | | 1.3 | J | | <4 | U | |

SEE LAST PAGE OF TABLE FOR NOTES

**TABLE 6**
**CUMULATIVE SUMMARY OF SOIL VAPOR ANALYTICAL DETECTIONS AND SCREENING RESULTS: PUBLIC WORKS YARD AND WRR - VOCS**

| Location | Depth | Sample ID | Sample Date | Acetone 750000 | | | alpha-Chlorotoluene | | | Benzene 2.8 | | | Bromodichloromethane 450000 | | | Bromoform 52 | | | Bromomethane 42 | | | 1,3-Butadiene | | | Butane | | | 2-Butanone 40000 | | | Carbon disulfide 5300 | | | Carbon tetrachloride 1.5 | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals |
| VMP-14 | 5 ft | VMP 14-5-091010 | 9/10/2010 | <0.59 | U | | <0.32 | U | | 0.71 | | | <0.42 | U | | <0.64 | U | | <0.24 | U | | <0.14 | U | | | | | <0.18 | U | | <0.19 | U | | <0.39 | U | |
| | | VMP-14-5-120110 | 12/1/2010 | 0.017 | | | <0.0062 | U | | 0.008 | | | 0.0012 | J | | <0.012 | U | | <0.0047 | U | | <0.0026 | U | | | | | 0.0028 | J | | <0.0037 | U | | <0.0076 | U | |
| | | VMP-14-5-021711 | 2/17/2011 | 0.0069 | J | | <0.0068 | U | | 1.2 | | | <0.0088 | U | | <0.014 | U | | <0.0051 | U | | <0.0029 | U | | | | | <0.0039 | U | | <0.0041 | J | U | <0.0083 | U | |
| | | VMP-14-5-040511 | 4/5/2011 | 0.012 | J | | <0.007 | U | | 0.011 | | | <0.009 | U | | <0.014 | U | | <0.0052 | J | U | <0.003 | U | | 1.5 | E | J | <0.016 | U | | <0.017 | J | U | <0.0085 | U | |
| | | VMP-14-5-080811 | 8/8/2011 | <13 | U | | <7.3 | U | | 13 | | | <9.4 | U | | <14 | U | | <5.4 | U | | <3.1 | U | | 2600 | | | <16 | U | | <4.4 | U | | <8.8 | U | |
| | | VMP-14-5-111411 | 11/14/2011 | 0.0078 | J | | <0.018 | U | | 3.1 | | | <0.024 | U | | <0.036 | U | | <0.014 | U | | <0.0078 | U | | 0.011 | J | | <0.042 | U | | 0.0088 | J | | <0.022 | U | |
| | | VMP-14-5-042012 | 4/20/2012 | 0.012 | J | | <0.0044 | U | | 0.026 | | | <0.0057 | U | | <0.0088 | U | | <0.033 | U | | <0.0019 | U | | 0.037 | | | 0.018 | | | <0.011 | J | U | <0.0054 | U | |
| | | VMP-14-5-072312 | 7/23/2012 | 0.2 | | | 0.0084 | | | 0.43 | | | <0.0069 | U | | <0.011 | U | | 0.0023 | J | | <0.0023 | U | | 0.0038 | J | | 0.09 | | | <0.013 | U | | <0.0065 | U | |
| | | VMP-14-5-101012 | 10/10/2012 | 0.012 | J | | <0.0075 | U | | 0.025 | | | <0.0097 | U | | <0.015 | U | | <0.056 | U | | <0.0032 | U | | <0.014 | U | | 0.0038 | J | | <0.018 | U | | <0.0091 | U | |
| | | VMP-14-5-013113 | 1/31/2013 | 0.01 | J | | <0.007 | U | | <0.0043 | U | | <0.009 | U | | <0.014 | U | | <0.052 | U | | <0.003 | U | | 0.0044 | J | | <0.016 | U | | <0.017 | J | U | <0.0085 | U | |
| | 11.5 ft | VMP-14-11.5-091010 | 9/10/2010 | <9.1 | U | | <4.9 | U | | 52 | | | <6.4 | U | | <9.9 | U | | <3.7 | U | | <2.1 | U | | | | | <2.8 | U | | <3 | U | | <6 | U | |
| | | VMP-14-11.5-120110 | 12/2/2010 | <0.8 | U | | <0.43 | U | | 0.28 | | | <0.56 | U | | <0.87 | U | | <0.33 | U | | <0.18 | U | | | | | <0.25 | U | | <0.26 | U | | <0.53 | U | |
| | | VMP-14-11.5-120110-DUP | 12/2/2010 | <0.72 | U | | <0.39 | U | | 0.28 | | | <0.51 | U | | <0.78 | U | | <0.3 | U | | <0.17 | U | | | | | <0.22 | U | | <0.24 | U | | <0.48 | U | |
| | | VMP-14-11.5-021711 | 2/17/2011 | <0.26 | U | | <0.14 | U | | 0.86 | | | <0.18 | U | | <0.28 | U | | <0.11 | U | | <0.061 | U | | | | | <0.081 | U | | 0.052 | J | | <0.17 | U | |
| | | VMP-14-11.5-021711-DUP | 2/17/2011 | <0.26 | U | | <0.14 | U | | 1 | | | <0.18 | U | | <0.28 | U | | <0.11 | U | | <0.061 | U | | | | | <0.081 | U | | 0.041 | J | | <0.17 | U | |
| | | VMP-14-11.5-040511 | 4/5/2011 | <0.043 | U | | <0.023 | U | | 0.079 | | | <0.03 | U | | <0.046 | U | | <0.017 | U | | <0.0099 | U | | 18 | E | J | 0.014 | J | | <0.056 | J | U | <0.028 | U | |
| | | VMP-14-11.5-080811 | 8/8/2011 | <1.3 | U | | <0.72 | U | | 0.18 | J | | <0.93 | U | | <1.4 | U | | <0.54 | U | | <0.31 | U | | 320 | | | <1.6 | U | | <0.43 | U | | <0.87 | U | |
| | | VMP-14-11.5-111511 | 11/15/2011 | 1.8 | J | | <1.1 | U | | 2.2 | | | <1.4 | U | | <2.2 | U | | <0.84 | U | | <0.48 | U | | 560 | | | 0.53 | J | | 1.7 | J | | <1.4 | U | |
| | | VMP-14-11.5-012612 | 1/26/2012 | <8.4 | U | | <18 | U | | 3.8 | | | <5.9 | U | | <36 | U | | <3.4 | U | | <1.9 | U | | 1500 | | | <10 | U | | <2.7 | U | | <5.5 | U | |
| | | VMP-14-11.5-042312 | 4/23/2012 | 0.015 | J | | <0.0047 | U | | 0.0068 | | | <0.0061 | U | | <0.0094 | U | | <0.036 | U | | <0.002 | U | | 0.044 | | | 0.011 | | | <0.011 | J | U | <0.0058 | U | |
| | | VMP-14-11.5-042312-Dup | 4/23/2012 | 0.0098 | J | | <0.0047 | U | | 0.0068 | | | <0.0061 | U | | <0.0094 | U | | <0.036 | U | | <0.002 | U | | 0.046 | | | 0.0081 | J | | <0.011 | J | U | <0.0058 | U | |
| | | VMP-14-11.5-072512 | 7/25/2012 | <3 | U | | <1.7 | U | | <1 | U | | <2.2 | U | | <3.3 | U | | <1.2 | U | | <0.71 | U | | 460 | | | <3.8 | U | | <1 | U | | <2 | U | |
| | | VMP-14-11.5-101012 | 10/10/2012 | 0.024 | J | | <0.0071 | U | | 0.0039 | J | | <0.0092 | U | | <0.014 | U | | <0.054 | U | | <0.003 | U | | 0.018 | | | <0.016 | U | | 0.008 | J | | <0.0087 | U | |
| | | VMP-14-11.5-013113 | 1/31/2013 | 0.0082 | J | | <0.0067 | J | U | <0.0041 | U | | <0.0086 | U | | <0.013 | U | | <0.05 | U | | <0.0028 | U | | <0.012 | U | | <0.015 | U | | <0.016 | J | U | <0.0081 | U | |
| | 20 ft | VMP-14-20-091010 | 9/10/2010 | <140 | U | | <75 | U | | 37000 | | | <97 | U | | <150 | U | | <56 | U | | <32 | U | | | | | <43 | U | | <45 | U | | <92 | U | |
| | | VMP-14-20-091010-Dup | 9/10/2010 | <140 | U | | <78 | U | | 35000 | | | <100 | U | | <160 | U | | <59 | U | | <33 | U | | | | | <44 | U | | <47 | U | | <95 | U | |
| | | VMP-14-20-120110 | 12/2/2010 | <370 | U | | <200 | U | | 47000 | | | <260 | U | | <400 | U | | <150 | U | | <87 | U | | | | | <120 | U | | <120 | U | | <250 | U | |
| | | VMP-14-20-021811 | 2/18/2011 | <210 | U | | <110 | U | | 20000 | | | <150 | U | | <230 | U | | <86 | U | | <49 | U | | | | | <65 | U | | <69 | U | | <140 | U | |
| | | VMP-14-20-040511 | 4/5/2011 | 18 | J | | <49 | U | | 22000 | | | <64 | U | | <98 | U | | <37 | U | | <21 | U | | 3400 | | | <110 | U | | <30 | U | | <60 | U | |
| | | VMP-14-20-080811 | 8/8/2011 | <33 | U | | <18 | U | | 17000 | | | <23 | U | | <36 | U | | <13 | U | | <7.6 | U | | 6000 | | | <41 | U | | <11 | U | | <22 | U | |
| | | VMP-14-20-111511 | 11/15/2011 | <170 | U | | <92 | U | | 16000 | | | <120 | U | | <180 | U | | <69 | U | | <39 | U | | 5900 | | | <210 | U | | <220 | U | | <110 | U | |
| | | VMP-14-20-012612 | 1/26/2012 | 2.8 | J | J | <36 | U | | 17000 | | | <12 | U | | <72 | U | | <6.8 | U | | <3.9 | U | | 4100 | | J | <21 | U | | 1.5 | J | J | <11 | U | |
| | | VMP-14-20-042312 | 4/23/2012 | <9.1 | U | | <20 | U | | 13000 | | | <6.4 | U | | <9.9 | U | | <3.7 | U | | <2.1 | U | | 2400 | | | <11 | U | | <3 | U | | <6 | U | |
| | | VMP-14-20-072512 | 7/25/2012 | <14 | U | | <7.9 | U | | 13000 | | | <10 | U | | <16 | U | | <5.9 | U | | <3.4 | U | | 2200 | | | <18 | U | | <4.7 | U | | <9.6 | U | |
| | | VMP-14-20-101612 | 10/16/2012 | 16 | J | | <36 | U | | 9400 | | | <47 | U | | <73 | U | | <27 | U | | <16 | U | | 1100 | | | <83 | U | | <22 | U | | <44 | U | |
| | | VMP-14-20-013113 | 1/31/2013 | 36 | J | | 2.8 | J | | 12000 | | | <17 | U | | <26 | U | | <98 | U | | <5.6 | U | | 350 | | | <30 | U | | 4.7 | J | | <16 | U | |
| | 29 ft | VMP-14-29-021811 | 2/18/2011 | 240 | J | | <170 | U | | 40000 | | | <220 | U | | <330 | U | | <120 | U | | <71 | U | | | | | <95 | U | | <100 | U | | <200 | U | |
| | | VMP-14-29-040511 | 4/5/2011 | <260 | U | | <140 | U | | 51000 | | | <180 | U | | <280 | U | | <110 | U | | <61 | U | | 4900 | | | <320 | U | | <86 | U | | <170 | U | |
| | | VMP-14-29-012612 | 1/26/2012 | <300 | U | | <650 | U | | 26000 | | | <210 | U | | <1300 | U | | <120 | U | | <69 | U | | 4000 | | | <370 | U | | <98 | U | | <200 | U | |
| | | VMP-14-29-042312 | 4/23/2012 | <110 | U | | <230 | U | | 22000 | | | <75 | U | | <120 | U | | <43 | U | | <25 | U | | 2800 | | | <130 | U | | <35 | U | | <70 | U | |
| | | VMP-14-29-072512 | 7/25/2012 | <110 | U | | <61 | U | | 21000 | | | <79 | U | | <120 | U | | <46 | U | | <26 | U | | 2900 | | | <140 | U | | <36 | U | | <74 | U | |
| | | VMP-14-29-101612 | 10/16/2012 | <170 | U | | <91 | U | | 9400 | | | <120 | U | | <180 | U | | <68 | U | | <39 | U | | 1600 | | | <210 | U | | <55 | U | | <110 | U | |
| | | VMP-14-29-013113-DUP | 1/31/2013 | <560 | U | UJ | <120 | U | | 13000 | | J | <160 | U | | <240 | U | | <920 | U | | <52 | U | | 380 | | J | <280 | U | | 36 | J | | <150 | U | |
| | | VMP-14-29-013113 | 1/31/2013 | 30 | J | J | <51 | U | | 54000 | | J | <66 | U | | <100 | U | | <380 | U | | <22 | U | | 2100 | | J | <120 | U | | 13 | J | | <62 | U | |
| VMP-15 | 5 ft | VMP 15-5-091410 | 9/14/2010 | 0.015 | | | <0.0065 | U | | 0.61 | | | <0.0084 | U | | <0.013 | U | | <0.0049 | J | U | <0.0028 | U | | | | | 0.001 | J | | <0.0039 | J | U | <0.0079 | U | |
| | | VMP-15-5-113010 | 11/30/2010 | <0.28 | U | | <0.15 | U | | <0.096 | U | | <0.2 | U | | <0.31 | U | | <0.12 | U | | <0.066 | U | | | | | <0.088 | U | | <0.093 | U | | <0.19 | U | |
| | | VMP-15-5-021611 | 2/16/2011 | 0.33 | | | <0.14 | U | | 2 | | | <0.19 | U | | <0.29 | U | | <0.11 | U | | <0.062 | U | | | | | 0.08 | J | | 0.11 | | | <0.18 | U | |
| | | VMP-15-5-042011 | 4/20/2011 | 0.083 | J | | <0.34 | U | | 1.4 | | | <0.44 | U | | <0.68 | U | | <0.26 | U | | <0.15 | U | | 6.3 | | | <0.78 | U | | <0.2 | U | | <0.42 | U | |
| | | VMP-15-5-080811 | 8/8/2011 | 0.088 | | | <0.0077 | J | U | 0.14 | | | <0.01 | U | | <0.015 | J | U | <0.0058 | U | | <0.0033 | U | | 0.0059 | J | | 0.016 | J | | 0.0042 | J | | <0.0093 | U | |
| | | VMP-15-5-111511 | 11/15/2011 | <0.016 | U | | <0.0086 | U | | 2.1 | | | <0.011 | U | | <0.017 | U | | <0.0064 | U | | <0.0037 | U | | 0.12 | | | 0.0034 | J | | <0.021 | U | | <0.01 | U | |
| | | VMP-15-5-020112 | 2/1/2012 | 0.012 | J | | <0.18 | U | | <0.027 | U | | <0.057 | U | | <0.35 | U | | <0.033 | U | | <0.019 | U | | <0.081 | U | | 0.0093 | J | | <0.027 | U | | <0.054 | U | |
| | | VMP-15-5-042412 | 4/24/2012 | 0.026 | J | | <0.18 | U | | 0.063 | | | <0.059 | U | | <0.09 | U | | <0.034 | U | | <0.019 | U | | <0.083 | U | | <0.1 | U | | <0.027 | U | | <0.055 | U | |
| | | VMP-15-5-072512 | 7/25/2012 | 0.064 | | | <0.0051 | U | | 0.005 | | | <0.0066 | U | | <0.01 | U | | 0.002 | J | J | <0.0022 | U | | <0.0094 | U | | 0.013 | | | 0.018 | | J | 0.0014 | J | |
| | | VMP-15-5-102512 | 10/25/2012 | 0.026 | J | | 0.0013 | J | | 0.013 | | | <0.01 | U | | <0.015 | U | | <0.058 | U | | <0.0033 | U | | 0.18 | | | 0.015 | J | | <0.018 | J | U | <0.0093 | U | |
| | | VMP-15-5-020513 | 2/5/2013 | 0.006 | J | | <0.0075 | U | | 0.004 | J | | <0.0097 | U | | <0.015 | U | | <0.056 | U | | <0.0032 | U | | <0.014 | U | | <0.017 | U | | <0.018 | J | U | <0.0091 | U | |
| | 21.5 ft | VMP-15-21.5-091410 | 9/14/2010 | <1.3 | U | | <0.71 | U | | 0.61 | | | <0.92 | U | | <1.4 | U | | <0.53 | U | | <0.3 | U | | | | | <0.4 | U | | <0.43 | U | | <0.86 | U | |
| | | VMP-15-21.5-113010 | 11/30/2010 | <1.5 | U | | <0.83 | U | | <0.51 | U | | <1.1 | U | | <1.6 | U | | <0.62 | U | | <0.36 | U | | | | | <0.47 | U | | <0.5 | U | | <1 | U | |
| | | VMP-15-21.5-021611 | 2/16/2011 | <1.1 | U | | <0.58 | U | | 2.2 | | | <0.75 | U | | <1.2 | U | | <0.43 | U | | <0.25 | U | | | | | <0.33 | U | | <0.35 | U | | <0.7 | U | |
| | | VMP-15-21.5-042011 | 4/20/2011 | <1.7 | U | | <0.91 | U | | 1.4 | | | <1.2 | U | | <1.8 | U | | <0.68 | U | | <0.39 | U | | 25 | | | <2.1 | U | | <0.55 | U | | <1.1 | U | |
| | | VMP-15-21.5-080811 | 8/8/2011 | 0.37 | J | | <0.73 | U | | 0.8 | | | <0.94 | U | | <1.4 | U | | <0.55 | U | | <0.31 | U | | 35 | | | <1.7 | U | | <0.44 | U | | <0.89 | U | |
| | | VMP-15-21.5-111511 | 11/15/2011 | <1.1 | U | | <0.58 | U | | 0.18 | J | | <0.74 | U | | <1.2 | U | | <0.44 | U | | <0.25 | U | | 4.4 | | | <1.3 | U | | <1.4 | U | | <0.71 | U | |
| | | VMP-15-21.5-020112 | 2/1/2012 | <0.8 | U | | <1.7 | U | | 0.16 | J | J | <0.56 | U | | <3.5 | U | | <0.33 | U | | <0.18 | U | | <0.8 | U | | <0.99 | U | | 0.091 | J | J | <0.53 | U | |
| | | VMP-15-21.5-042412 | 4/24/2012 | <0.35 | U | | <0.76 | U | | 0.91 | | | <0.24 | U | | <0.38 | U | | <0.14 | U | | <0.081 | U | | 1 | | | <0.43 | U | | 0.041 | J | | <0.23 | U | |
| | | VMP-15-21.5-072512 | 7/25/2012 | 0.19 | J | | <0.68 | U | | 0.25 | J | | <0.89 | U | | <1.4 | U | | <0.51 | U | | <0.29 | U | | 0.26 | J | | <1.6 | U | | <0.41 | U | | <0.83 | U | |
| | | VMP-15-21.5-102512 | 10/25/2012 | <2 | U | | <1.1 | U | | 0.24 | J | | <1.4 | U | | <2.2 | U | | <0.84 | U | | <0.48 | U | | 1 | J | | <2.6 | U | | <0.67 | U | | <1.4 | U | |
| | | VMP-15-21.5-102512-Dup | 10/25/2012 | <2.1 | U | | <1.2 | U | | 0.24 | J | | <1.5 | U | | <2.3 | U | | <0.87 | U | | <0.49 | U | | 1.1 | J | | <2.6 | U | | <0.69 | U | | <1.4 | U | |
| | | VMP-15-21.5-020713 | 2/7/2013 | 0.034 | J | | <0.028 | U | | 0.0077 | J | | <0.037 | U | | <0.057 | U | | <0.21 | U | | <0.012 | U | | 0.4 | | | <0.065 | U | | 0.029 | J | | <0.035 | U | |
| | 25.5 ft | VMP 15-25.5-091410 | 9/14/2010 | 0.013 | | | <0.0067 | U | | 0.3 | | | <0.0086 | U | | <0.013 | U | | <0.005 | U | | <0.0028 | U | | | | | 0.0015 | J | | <0.004 | J | U | <0.0081 | U | |
| | | VMP-15-25.5-021611 | 2/16/2011 | <0.16 | U | | <0.089 | U | | 0.36 | | | <0.12 | U | | <0.18 | U | | <0.067 | U | | <0.038 | U | | | | | <0.051 | U | | 0.028 | J | | <0.11 | U | |
| | | VMP-15-25.5-042011 | 4/20/2011 | <0.13 | U | | <0.073 | U | | 1.6 | | | <0.094 | U | | <0.14 | U | | <0.055 | U | | <0.031 | U | | 0.06 | J | | <0.17 | U | | <0.044 | U | | <0.089 | U | |
| | | VMP-15-25.5-042011-DUP | 4/20/2011 | <0.12 | U | | <0.068 | U | | 1.4 | | | <0.088 | U | | <0.14 | U | | <0.051 | U | | <0.029 | U | | 0.27 | | | <0.16 | U | | <0.041 | U | | <0.083 | U | |
| | | VMP-15-25.5-080811 | 8/8/2011 | 0.054 | J | | <0.073 | U | | 0.13 | | | <0.094 | U | | <0.14 | U | | <0.055 | U | | <0.031 | U | | 0.58 | | | <0.17 | U | | <0.044 | U | | <0.089 | U | |
| | | VMP-15-25.5-111511 | 11/15/2011 | <0.041 | U | | <0.022 | U | | 3.4 | | | 0.12 | | | <0.045 | U | | <0.017 | U | | <0.0096 | U | | 0.35 | | | <0.051 | U | | <0.054 | U | | <0.027 | U | |
| | | VMP-15-25.5-073112 | 7/31/2012 | 0.091 | | | <0.047 | U | | 0.024 | J | | <0.061 | U | | <0.094 | U | | <0.036 | U | | <0.02 | U | | 0.71 | | | 0.023 | J | | <0.028 | U | | <0.058 | U | |
| | | VMP-15-25.5-102512 | 10/25/2012 | <0.035 | U | | <0.0077 | U | | 0.034 | | | <0.01 | U | | <0.015 | U | | <0.058 | U | | <0.0033 | U | | 0.058 | | | 0.019 | | | <0.018 | U | | <0.0093 | U | |
| | | VMP-15-25.5-021213 | 2/12/2013 | <0.43 | U | | <0.23 | U | | <0.14 | U | | <0.3 | U | | <0.46 | U | | <0.17 | U | | <0.099 | U | | 2.4 | | | <0.53 | U | | <0.14 | U | | <0.28 | U | |
| | 29 ft | VMP-15-29-073112 | 7/31/2012 | 0.1 | J | J | <0.2 | U | | 0.17 | | J | <0.26 | U | | <0.4 | U | | <0.15 | U | | <0.087 | U | | 5.8 | | J | <0.46 | U | | <0.12 | U | | <0.25 | U | |
| | | VMP-15-29-102512 | 10/25/2012 | <0.073 | U | | <0.016 | U | | 0.026 | | | <0.021 | U | | <0.032 | U | | <0.12 | U | | <0.0068 | U | | 0.28 | | | 0.033 | J | | <0.038 | U | | <0.019 | U | |
| | | VMP-15-29-021213 | 2/12/2013 | 0.26 | | | <0.14 | U | | <0.086 | U | | <0.18 | U | | <0.28 | U | | <0.1 | U | | <0.06 | U | | 2 | | | <0.32 | U | | <0.084 | U | | <0.17 | U | |

SEE LAST PAGE OF TABLE FOR NOTES

**TABLE 6**
**CUMULATIVE SUMMARY OF SOIL VAPOR ANALYTICAL DETECTIONS AND SCREENING RESULTS: PUBLIC WORKS YARD AND WRR - VOCS**

| Location | Depth | Sample ID | Sample Date | Acetone 750000 | | | alpha-Chlorotoluene | | | Benzene 2.8 | | | Bromodichloromethane 450000 | | | Bromoform 52 | | | Bromomethane 42 | | | 1,3-Butadiene | | | Butane | | | 2-Butanone 40000 | | | Carbon disulfide 5300 | | | Carbon tetrachloride 1.5 | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals |
| VMP-16 | 5 ft | VMP-16-5-090210 | 9/2/2010 | <23 | U | | <12 | U | | 17 | | | <16 | U | | <25 | U | | <9.2 | U | | <5.3 | U | | | | | <7 | U | | <7.4 | U | | <15 | U | |
| | | VMP-16-5-112910 | 11/29/2010 | <10 | U | | <5.6 | U | | 16 | | J | <7.3 | U | | <11 | U | | <4.2 | U | | <2.4 | U | | | | | <3.2 | U | | <3.4 | U | | <6.8 | U | |
| | | VMP-16-5-021511 | 2/15/2011 | <6.3 | U | | <3.4 | U | | 10 | | J | <4.4 | U | | <6.8 | U | | <2.6 | U | | <1.5 | U | | | | | <1.9 | U | | <2 | U | | <4.2 | U | |
| | | VMP-16-5-042211 | 4/22/2011 | <8.4 | U | | <4.6 | U | | 7 | | | <5.9 | U | | <9.1 | U | | <3.4 | U | | <1.9 | U | | 260 | | | <10 | U | | <2.7 | U | | <5.5 | U | |
| | | VMP-16-5-080511 | 8/5/2011 | 0.5 | J | | <1.4 | U | | 2.9 | | | <1.9 | U | | <2.9 | U | | <1.1 | U | | <0.62 | U | | 39 | | | <3.3 | U | | <0.88 | U | | <1.8 | U | |
| | | VMP-16-5-042512 | 4/25/2012 | <9.1 | U | | <20 | U | | 6 | | | <6.4 | U | | <9.9 | U | | <3.7 | U | | <2.1 | U | | 140 | | | <11 | U | | <3 | U | | <6 | U | |
| | | VMP-16-5-073012 | 7/30/2012 | <8.5 | U | | <4.6 | U | | 8.8 | | J | <6 | U | | <9.2 | U | | <3.5 | U | | <2 | U | | 58 | | J | <10 | U | | <2.8 | U | | <5.6 | U | |
| | | VMP-16-5-102512 | 10/25/2012 | <6.7 | U | | <3.6 | U | | 0.63 | J | | <4.7 | U | | <7.3 | U | | <2.7 | U | | <1.6 | U | | 4 | J | | <8.3 | U | | <2.2 | U | | <4.4 | U | |
| | | VMP-16-5-021413 | 2/14/2013 | <1 | U | | <0.57 | U | | 0.17 | J | J | <0.74 | U | | <1.1 | U | | <0.43 | U | | <0.24 | U | | <1 | U | | <1.3 | U | | <0.34 | U | | <0.69 | U | |
| | 13.5 ft | VMP-16-13.5-090210 | 9/2/2010 | 3.6 | J | | <13 | U | | 17 | | | <16 | U | | <26 | U | | <9.6 | U | | <5.5 | U | | | | | <7.3 | U | | <7.7 | U | | <16 | U | |
| | | VMP-16-13.5-090210-DUP | 9/2/2010 | <23 | U | | <13 | U | | 16 | | | <16 | U | | <26 | U | | <9.6 | U | | <5.5 | U | | | | | <7.3 | U | | <7.7 | U | | <16 | U | |
| | | VMP-16-13.5-112910 | 11/29/2010 | <66 | U | | <36 | U | | 21 | J | | <47 | U | | <72 | U | | <27 | U | | <15 | U | | | | | <21 | U | | <22 | U | | <44 | U | |
| | | VMP-16-13.5-021611 | 2/16/2011 | <13 | U | | <7 | U | | 7.1 | | | <9 | U | | <14 | U | | <5.2 | U | | <3 | U | | | | | <4 | U | | <4.2 | U | | <8.5 | U | |
| | | VMP-16-13.5-021611-DUP | 2/16/2011 | <12 | U | | <6.8 | U | | 9.3 | | | <8.8 | U | | <14 | U | | <5.1 | U | | <2.9 | U | | | | | <3.9 | U | | <4.1 | U | | <8.3 | U | |
| | | VMP-16-13.5-042211 | 4/22/2011 | <13 | U | | <7.4 | U | | 8.3 | | | <9.5 | U | | <15 | U | | <5.5 | U | | <3.1 | U | | 320 | | | <17 | U | | <4.4 | U | | <8.9 | U | |
| | | VMP-16-13.5-080511 | 8/5/2011 | <1.3 | U | UJ | <0.71 | U | UJ | 0.54 | | J | <0.92 | U | UJ | <1.4 | U | UJ | <0.54 | U | UJ | <0.3 | U | UJ | 14 | | J | <1.6 | U | UJ | <0.43 | U | UJ | <0.87 | U | UJ |
| | | VMP-16-13.5-042512 | 4/25/2012 | <1.4 | U | | <3.2 | U | | 7.6 | | J | <1 | U | | <1.6 | U | | <0.59 | U | | <0.34 | U | | 360 | | | <1.8 | U | | <0.47 | U | | <0.96 | U | |
| | | VMP-16-13.5-073012 | 7/30/2012 | 9.8 | J | | <24 | U | | 27 | | | <31 | U | | <47 | U | | <18 | U | | <10 | U | | 180 | | | <54 | U | | 2.4 | J | | <29 | U | |
| | | VMP-16-13.5-102512 | 10/25/2012 | 20 | J | | <73 | U | | 22 | J | | <94 | U | | <140 | U | | <55 | U | | <31 | U | | 77 | J | | <170 | U | | 14 | J | | <89 | U | |
| | | VMP-16-13.5-021413 | 2/14/2013 | 5.3 | J | J | <12 | U | | 21 | | J | <15 | U | | <23 | U | | <8.7 | U | | <5 | U | | 92 | | J | <26 | U | | 2.3 | J | J | <14 | U | |
| | 19 ft | VMP-16-19-090210 | 9/2/2010 | <23 | U | | <13 | U | | 27 | | | <16 | U | | <26 | U | | <9.6 | U | | <5.5 | U | | | | | <7.3 | U | | <7.7 | U | | <16 | U | |
| | | VMP-16-19-112910 | 11/29/2010 | <51 | U | | <28 | U | | 20 | | | <36 | U | | <56 | U | | <21 | U | | <12 | U | | | | | <16 | U | | <17 | U | | <34 | U | |
| | | VMP-16-19-021611 | 2/16/2011 | <12 | U | | <6.7 | U | | 7.7 | | | <8.6 | U | | <13 | U | | <5 | U | | <2.8 | U | | | | | <3.8 | U | | <4 | U | | <8.1 | U | |
| | | VMP-16-19-042711 | 4/27/2011 | <12 | U | | <6.8 | U | | 3.7 | J | | <8.8 | U | | <14 | U | | <5.1 | U | | <2.9 | U | | 150 | | | <16 | U | | <4.1 | U | | <8.3 | U | |
| | | VMP-16-19-042711-DUP | 4/27/2011 | <12 | U | | <6.7 | U | | 3.1 | J | | <8.6 | U | | <13 | U | | <5 | U | | <2.8 | U | | 160 | | | <15 | U | | <4 | U | | <8.1 | U | |
| | | VMP-16-19-042512 | p | 5.2 | J | | <73 | U | | 12 | | | <24 | U | | <36 | U | | <14 | U | | <7.8 | U | | 390 | | | <42 | U | | <11 | U | | <22 | U | |
| | | VMP-16-19-073012 | 7/30/2012 | <30 | U | | <16 | U | | 14 | | | <21 | U | | <33 | U | | <12 | U | | <7 | U | | 230 | | | <37 | U | | 1.5 | J | | <20 | U | |
| | | VMP-16-19-102512 | 10/25/2012 | 15 | J | | <68 | U | | 14 | J | | <88 | U | | <140 | U | | <51 | U | | <29 | U | | 130 | | | <160 | U | | 14 | J | | <83 | U | |
| | | VMP-16-19-021413 | 2/14/2013 | <12 | U | | <6.8 | U | | 17 | | J | <8.8 | U | | <14 | U | | <5.1 | U | | <2.9 | U | | 240 | | J | <16 | U | | <4.1 | U | | <8.3 | U | |
| | 31 ft | VMP-16-31-090310 | 9/3/2010 | 0.033 | | | <0.0075 | U | | 0.0064 | | | <0.0097 | U | | <0.015 | U | | 0.0019 | J | | <0.0032 | U | | | | | 0.0056 | | | 0.0036 | J | | <0.0091 | U | |
| | | VMP-16-31-112910 | 11/29/2010 | <52 | U | | <28 | U | | 20 | | | <36 | U | | <56 | U | | <21 | U | | <12 | U | | | | | <16 | U | | <17 | U | | <34 | U | |
| | | VMP-16-31-042512 | 4/25/2012 | 6.7 | J | | <89 | U | | 15 | | | <29 | U | | <44 | U | | <17 | U | | <9.5 | U | | 470 | | | <51 | U | | <13 | U | | <27 | U | |
| | | VMP-16-31-073012 | 7/30/2012 | 8.1 | J | | <18 | U | | 16 | | | <23 | U | | <36 | U | | <14 | U | | <7.7 | U | | 320 | | | <41 | U | | 3.9 | J | | <22 | U | |
| | | VMP-16-31-102512 | 10/25/2012 | <160 | U | | <85 | U | | 12 | J | | <110 | U | | <170 | U | | <64 | U | | <36 | U | | 150 | J | | <190 | U | | 7.8 | J | | <100 | U | |
| | | VMP-16-31-021813 | 2/18/2013 | <47 | U | | <26 | U | | 29 | | | <33 | U | | <52 | U | | <19 | U | | <11 | U | | 290 | | | <59 | U | | <16 | U | | <31 | U | |
| VMP-17 | 5 ft | VMP-17-5 | 6/21/2010 | 0.06 | | J | <0.007 | U | | 0.0051 | | | <0.009 | U | | <0.015 | U | | <0.005 | U | | <0.003 | U | | | | | 0.018 | | J | <0.004 | U | | <0.009 | U | |
| | | VMP-17-5-DUP | 6/21/2010 | 0.027 | | J | <0.007 | U | | 0.0044 | J | | <0.01 | U | | <0.016 | U | | <0.005 | U | | <0.003 | U | | | | | 0.0028 | J | J | <0.004 | J | U | <0.009 | U | |
| | | VMP-17-5-090110 | 9/1/2010 | 0.25 | | | <0.007 | U | | 0.0086 | | | <0.009 | U | | <0.014 | U | | <0.0052 | U | | <0.003 | U | | | | | 0.096 | | | <0.0042 | J | U | <0.0085 | U | |
| | | VMP-17-5-112210 | 11/22/2010 | 0.03 | | | <0.007 | U | | 0.0044 | | | <0.009 | U | | <0.014 | U | | <0.0052 | U | | <0.003 | U | | | | | 0.0048 | | | <0.0042 | J | U | <0.0085 | U | |
| | | VMP-17-5-020711 | 2/7/2011 | 0.012 | J | | <0.0065 | U | | 0.0061 | | | <0.0084 | U | | <0.013 | U | | <0.0049 | U | | <0.0028 | U | | | | | <0.0037 | U | | <0.0039 | U | | <0.0079 | U | |
| | | VMP-17-5-040611 | 4/6/2011 | 0.039 | J | | <0.026 | U | | 5.8 | | | <0.034 | U | | <0.052 | U | | <0.02 | U | | <0.011 | U | | 0.13 | | | 0.005 | J | | 0.0058 | J | | <0.032 | U | |
| | | VMP-17-5-080111 | 8/1/2011 | <0.18 | U | | <0.1 | U | | 0.17 | | | <0.13 | U | | <0.2 | U | | <0.075 | U | | <0.042 | U | | 14 | | | <0.23 | U | | <0.12 | J | | <0.12 | U | |
| | | VMP-17-5-110711 | 11/7/2011 | 0.029 | | | <0.0044 | J | U | 0.0018 | J | | <0.0057 | U | | <0.0088 | U | | <0.0033 | U | | <0.0019 | U | | 0.0067 | J | | 0.0063 | J | | <0.011 | U | | <0.0054 | U | |
| | | VMP-17-5-012612 | 1/26/2012 | 0.013 | | | <0.0046 | U | | 0.0022 | J | | <0.006 | U | | <0.0092 | U | | <0.0035 | U | | <0.002 | U | | 0.0025 | J | | 0.0098 | J | | <0.011 | U | | <0.0056 | U | |
| | | VMP-17-5-041112 | 4/11/2012 | 0.028 | | | <0.0047 | U | | 0.021 | | | <0.0061 | U | | <0.0094 | U | | <0.036 | U | | <0.002 | U | | 0.0051 | J | | 0.039 | | | <0.011 | U | | <0.0058 | U | |
| | | VMP-17-5-071112 | 7/11/2012 | 0.099 | | | <0.0051 | U | UJ | 0.11 | | | <0.0066 | U | | <0.01 | U | | <0.038 | U | | <0.0022 | U | | 0.0061 | J | | 0.034 | | | <0.012 | U | | <0.0062 | U | |
| | | VMP-17-5-100912 | 10/9/2012 | 0.062 | | | <0.0078 | U | | 0.0043 | J | | <0.01 | U | | <0.016 | U | | <0.059 | U | | <0.0034 | U | | <0.014 | U | | 0.0055 | J | | <0.019 | U | | <0.0095 | U | |
| | | VMP-17-5-013113 | 1/31/2013 | 0.011 | J | | <0.027 | U | | 0.71 | | | <0.036 | U | | <0.055 | U | | <0.2 | U | | <0.012 | U | | <0.05 | U | | <0.062 | U | | 0.0076 | J | | <0.033 | U | |
| | | VMP-17-5-013113-DUP | 1/31/2013 | 0.0096 | J | | <0.027 | U | | 1 | | | <0.036 | U | | <0.055 | U | | <0.2 | U | | <0.012 | U | | 0.039 | J | | <0.062 | U | | 0.007 | J | | <0.033 | U | |
| VMP-25 | 5 ft | VMP-25-5-031511 | 3/15/2011 | 3.6 | | | <0.063 | U | | 0.82 | | | <0.081 | U | | <0.12 | U | | <0.047 | U | | <0.027 | U | | | | | <0.14 | U | | 0.0047 | J | | <0.076 | U | |
| | | VMP-25-5-040811 | 4/8/2011 | 0.043 | J | | <0.028 | U | | 5.2 | | | <0.037 | U | | <0.057 | U | | <0.021 | U | | <0.012 | U | | 0.12 | | | <0.065 | U | | 0.019 | J | | <0.035 | U | |
| | | VMP-25-5-080911 | 8/9/2011 | 0.16 | | | <0.006 | J | U | 0.31 | | | <0.0078 | U | | <0.012 | J | U | <0.0045 | U | | <0.0026 | U | | 0.094 | | | 0.058 | | | 0.0095 | J | | <0.0073 | U | |
| | | VMP-25-5-111711 | 11/17/2011 | 0.0076 | J | | <0.0043 | U | | 0.011 | | | <0.0056 | U | | <0.0087 | U | | <0.0033 | U | | <0.0018 | U | | <0.008 | U | | 0.0013 | J | | 0.0023 | J | | <0.0053 | U | |
| | | VMP-25-5-013112 | 1/31/2012 | 0.02 | J | | <0.032 | U | | 4.8 | | | <0.041 | U | | <0.063 | U | | <0.024 | U | | <0.013 | U | | 4 | | | 0.01 | J | | 0.006 | J | | <0.038 | U | |
| | | VMP-25-5-042512 | 4/25/2012 | 0.024 | | | <0.0049 | U | | 0.066 | | | <0.0064 | U | | <0.0099 | U | | <0.037 | U | | <0.0021 | U | | <0.0091 | U | | 0.031 | | | <0.012 | J | U | <0.006 | U | |
| | | VMP-25-5-072612 | 7/26/2012 | 0.021 | J | | <0.017 | U | | 0.21 | | | <0.022 | U | | <0.034 | U | | <0.13 | U | | <0.0073 | U | | 2 | | | 0.017 | J | | <0.041 | U | | <0.021 | U | |
| | | VMP-25-5-102612 | 10/26/2012 | 0.012 | J | | <0.007 | U | | 0.0017 | J | | <0.009 | U | | <0.014 | U | | <0.052 | U | | <0.003 | U | | <0.013 | U | | 0.0035 | J | | <0.017 | U | | <0.0085 | U | |
| | | VMP-25-5-030613 | 3/6/2013 | 0.018 | J | | <0.0066 | J | U | 0.0048 | | | <0.0086 | U | | <0.013 | U | | <0.05 | U | | <0.0028 | U | | 0.016 | | | 0.0054 | J | | <0.016 | J | U | <0.0081 | U | |
| | 21 ft | VMP-25-21-031511 | 3/15/2011 | 1200 | | J | <12 | U | | 97 | | J | <16 | U | | <24 | U | | <9.2 | U | | <5.2 | U | | | | | <28 | U | | 6.3 | J | | <15 | U | |
| | | VMP-25-21-031511-DUP | 3/15/2011 | 1800 | | J | <16 | U | | 140 | | J | <20 | U | | <31 | U | | <12 | U | | <6.7 | U | | | | | <36 | U | | 9 | J | | <19 | U | |
| | | VMP-25-21-040811 | 4/8/2011 | <240 | U | | <130 | U | | 130 | | | <170 | U | | <260 | U | | <98 | U | | <56 | U | | 14000 | | | <300 | U | | 61 | J | | <160 | U | |
| | | VMP-25-21-040811-DUP | 4/8/2011 | <240 | U | | <130 | U | | 120 | | | <170 | U | | <260 | U | | <99 | U | | <56 | U | | 13000 | | | <300 | U | | 57 | J | | <160 | U | |
| | | VMP-25-21-080911 | 8/9/2011 | <78 | U | | <43 | U | | 1100 | | | <55 | U | | <85 | U | | <32 | U | | <18 | U | | 15000 | | | <97 | U | | <26 | U | | <52 | U | |
| | | VMP-25-21-111711 | 11/17/2011 | <110 | U | | <58 | U | | 25 | J | | <75 | U | | <120 | U | | <44 | U | | <25 | U | | 6800 | | | <130 | U | | <140 | U | | <71 | U | |
| | | VMP-25-21-111711-DUP | 11/17/2011 | <160 | U | | <86 | U | | 18 | J | | <110 | U | | <170 | U | | <64 | U | | <37 | U | | 6900 | | | <200 | U | | <210 | U | | <100 | U | |
| | | VMP-25-21-013112 | 1/31/2012 | <56 | U | | <120 | U | | 59 | | | <39 | U | | <240 | U | | <23 | U | | <13 | U | | 8300 | | | <69 | U | | <18 | U | | <37 | U | |
| | | VMP-25-21-013112-DUP | 2/1/2012 | <52 | U | | <110 | U | | 62 | | | <36 | U | | <220 | U | | <21 | U | | <12 | U | | 9500 | | | <64 | U | | <17 | U | | <34 | U | |
| | | VMP-25-21-042512 | 4/25/2012 | 6.7 | J | | <77 | U | | 37 | | | <25 | U | | <38 | U | | <14 | U | | <8.2 | U | | 12000 | | | <44 | U | | <12 | U | | <23 | U | |
| | | VMP-25-21-072612 | 7/26/2012 | <60 | U | | <33 | U | | 48 | | | <42 | U | | <65 | U | | <24 | U | | <14 | U | | 15000 | | | <74 | U | | 3 | J | | <40 | U | |
| | | VMP-25-21-102612 | 10/26/2012 | <360 | U | | <200 | U | | 48 | J | | <250 | U | | <390 | U | | <150 | U | | <84 | U | | 14000 | | | <440 | U | | <120 | U | | <240 | U | |
| | | VMP-25-21-030613 | 3/6/2013 | <230 | U | | <50 | U | | 95 | | | <64 | U | | <99 | U | | <370 | U | | <21 | U | | 12000 | | | <110 | U | | 31 | J | | <60 | U | |
| | 31 ft | VMP-25-31-030613 | 3/6/2013 | <120 | U | | <66 | U | | 90 | | | <85 | U | | <130 | U | | <49 | U | | <28 | U | | 6200 | | | <150 | U | | <40 | U | | <80 | U | |

SEE LAST PAGE OF TABLE FOR NOTES

**TABLE 6**
**CUMULATIVE SUMMARY OF SOIL VAPOR ANALYTICAL DETECTIONS AND SCREENING RESULTS: PUBLIC WORKS YARD AND WRR - VOCS**

| Location | Depth | Sample ID | Sample Date | Acetone | | | alpha-Chlorotoluene | | | Benzene | | | Bromodichloromethane | | | Bromoform | | | Bromomethane | | | 1,3-Butadiene | | | Butane | | | 2-Butanone | | | Carbon disulfide | | | Carbon tetrachloride | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | 750000 | | | | | | 2.8 | | | 450000 | | | 52 | | | 42 | | | | | | | | | 40000 | | | 5300 | | | 1.5 | | |
| | | | | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals |
| VMP-29 | 10 ft | VMP-29-10-073012 | 7/30/2012 | 4.4 | | | <0.055 | U | | <0.034 | U | | <0.071 | U | | <0.11 | U | | <0.41 | U | | <0.023 | U | | <0.1 | U | | 12 | | | 0.39 | | | <0.067 | U | |
| | | VMP-29-10-100812 | 10/8/2012 | 8.4 | | | <0.097 | U | | 0.47 | | | <0.12 | U | | <0.19 | U | | <0.73 | U | | <0.042 | U | | <0.18 | U | | 22 | | | 0.15 | J | | <0.12 | U | |
| | | VMP-29-10-020613 | 2/6/2013 | 0.16 | | | <0.0073 | U | | 0.053 | | | <0.0094 | U | | <0.014 | U | | <0.055 | U | | <0.0031 | U | | 0.0038 | J | | 0.3 | | | 0.021 | | | <0.0089 | U | |
| | 20 ft | VMP-29-20-073012 | 7/30/2012 | 170 | | | <0.65 | U | | 0.066 | J | | <0.84 | U | | <1.3 | U | | <0.49 | U | | <0.28 | U | | <1.2 | U | | 270 | | | 0.83 | | | <0.79 | U | |
| | | VMP-29-20-073012-Dup | 7/30/2012 | 150 | | | <0.6 | U | | 0.047 | J | | <0.78 | U | | <1.2 | U | | <0.45 | U | | <0.26 | U | | <1.1 | U | | 240 | | | 0.74 | | | <0.74 | U | |
| | | VMP-29-20-100812 | 10/8/2012 | 15 | | | <0.097 | U | | 0.12 | | | <0.12 | U | | <0.19 | U | | <0.73 | U | | <0.042 | U | | <0.18 | U | | 31 | | | 0.23 | J | | <0.12 | U | |
| | | VMP-29-20-020613 | 2/6/2013 | 0.21 | | | <0.0071 | U | | 0.026 | | | <0.0092 | U | | <0.014 | U | | <0.054 | U | | <0.003 | U | | 0.0084 | J | | 0.75 | | | 0.035 | | | <0.0087 | U | |
| | 30 ft | VMP-29-30-073012 | 7/30/2012 | 26 | | | <0.11 | U | | 0.057 | J | | <0.14 | U | | <0.21 | U | | <0.08 | U | | <0.046 | U | | <0.2 | U | | 60 | | | 0.32 | | | <0.13 | U | |
| | | VMP-29-30-100812 | 10/8/2012 | 54 | | | <0.48 | U | | 0.11 | J | | <0.62 | U | | <0.96 | U | | <3.6 | U | | <0.2 | U | | <0.88 | U | | 72 | | | 1.5 | | | <0.58 | U | |
| | | VMP-29-30-020613 | 2/6/2013 | 0.76 | | | <0.0075 | U | | 0.084 | | | <0.0097 | U | | <0.015 | U | | <0.056 | U | | <0.0032 | U | | 0.0047 | J | | 2.1 | | | 0.1 | | | <0.0091 | U | |
| VMP-30 | 10 ft | VMP-30-10-073012 | 7/30/2012 | 35 | | | <0.19 | U | | 0.016 | J | | <0.25 | U | | <0.39 | U | | <0.14 | U | | <0.083 | U | | <0.36 | U | | 97 | | | 0.2 | | | <0.24 | U | |
| | | VMP-30-10-100812 | 10/8/2012 | 0.87 | | | <0.0073 | U | | 0.016 | | | <0.0094 | U | | <0.014 | U | | <0.055 | U | | <0.0031 | U | | <0.013 | U | | 2.3 | | | 0.02 | | | <0.0089 | U | |
| | | VMP-30-10-020613 | 2/6/2013 | 0.091 | | | <0.0068 | U | | 0.0018 | J | | <0.0088 | U | | <0.014 | U | | <0.051 | U | | <0.0029 | U | | <0.012 | U | | 0.15 | | | <0.016 | J | U | <0.0083 | U | |
| | 20 ft | VMP-30-20-073012 | 7/30/2012 | 200 | | | <0.82 | U | | 2.1 | | | <1.1 | U | | <1.6 | U | | <0.62 | U | | <0.35 | U | | <1.5 | U | | 390 | | | 0.83 | | | <1 | U | |
| | | VMP-30-20-100812 | 10/8/2012 | 44 | | | <0.3 | U | | 0.35 | | | <0.39 | U | | <0.6 | U | | <2.2 | U | | <0.13 | U | | <0.55 | U | | 45 | | | 1.1 | | | <0.36 | U | |
| | | VMP-30-20-020613 | 2/6/2013 | 0.17 | | | <0.0068 | J | U | 0.11 | | | <0.0088 | U | | <0.014 | U | | <0.051 | U | | <0.0029 | U | | 0.0088 | J | | 0.6 | | | 0.077 | | | <0.0083 | U | |
| | 30 ft | VMP-30-30-073012 | 7/30/2012 | 320 | | | <0.85 | U | | 7.2 | | | <1.1 | U | | <1.7 | U | | <0.63 | U | | <0.36 | U | | <1.6 | U | | 380 | | | 0.31 | J | | <1 | U | |
| | | VMP-30-30-100812 | 10/8/2012 | 75 | | | <0.62 | U | | 5.4 | | | <0.81 | U | | <1.2 | U | | <4.7 | U | | <0.27 | U | | 0.49 | J | | 100 | | | 1.2 | J | | <0.76 | U | |
| | | VMP-30-30-020613 | 2/6/2013 | 2.8 | | | <0.023 | U | | 1.4 | | | <0.029 | U | | <0.045 | U | | <0.17 | U | | <0.0097 | U | | <0.042 | U | | 6.4 | | | 0.1 | | | <0.028 | U | |
| VMP-41 | 10 ft | VMP-41-10-072712 | 7/27/2012 | 0.08 | | | <0.0063 | U | | 0.16 | | | <0.0081 | U | | <0.012 | U | | <0.047 | U | | <0.0027 | U | | 0.092 | | | 0.022 | | | <0.015 | U | | <0.0076 | U | |
| | | VMP-41-10-100912 | 10/9/2012 | 0.02 | J | | <0.0077 | U | | 0.034 | | | <0.0099 | U | | <0.015 | U | | <0.057 | U | | <0.0033 | U | | <0.014 | U | | 0.012 | J | | <0.018 | U | | <0.0093 | U | |
| | | VMP-41-10-012913 | 1/29/2013 | 0.006 | J | | <0.0077 | U | | 0.0018 | J | | <0.0099 | U | | <0.015 | U | | <0.057 | U | | <0.0033 | U | | <0.014 | U | | <0.017 | U | | <0.018 | J | U | <0.0093 | U | |
| | 20 ft | VMP-41-20-072712 | 7/27/2012 | 0.048 | | | <0.0048 | U | | 0.039 | | | <0.0063 | U | | <0.0097 | U | | <0.036 | U | | <0.0021 | U | | <0.0089 | U | | 0.012 | | | <0.012 | U | | <0.0059 | U | |
| | | VMP-41-20-072712-Dup | 7/27/2012 | 0.047 | | | <0.0049 | U | | 0.044 | | | <0.0064 | U | | <0.0099 | U | | <0.037 | U | | <0.0021 | U | | <0.0091 | U | | 0.013 | | | <0.012 | U | | <0.006 | U | |
| | | VMP-41-20-100912 | 10/9/2012 | 0.055 | | | <0.0075 | U | | 0.027 | | | <0.0097 | U | | <0.015 | U | | <0.056 | U | | <0.0032 | U | | <0.014 | U | | 0.012 | J | | <0.018 | U | | <0.0091 | U | |
| | | VMP-41-20-100912-Dup | 10/9/2012 | 0.024 | J | | <0.0077 | U | | 0.027 | | | <0.0099 | U | | <0.015 | U | | <0.057 | U | | <0.0033 | U | | <0.014 | U | | 0.009 | J | | <0.018 | U | | <0.0093 | U | |
| | | VMP-41-20-012913 | 1/29/2013 | 0.0096 | J | | <0.0078 | U | | 0.0044 | J | | <0.01 | U | | <0.016 | U | | <0.059 | U | | <0.0034 | U | | <0.014 | U | | <0.018 | U | | <0.019 | J | U | <0.0095 | U | |
| | 30 ft | VMP-41-30-072712 | 7/27/2012 | 0.094 | | | <0.0049 | U | | 0.34 | | | <0.0064 | U | | <0.0099 | U | | <0.037 | U | | <0.0021 | U | | 0.02 | | | 0.023 | | | <0.012 | U | | <0.006 | U | |
| | | VMP-41-30-100912 | 10/9/2012 | 0.019 | J | | <0.008 | U | | 0.041 | | | <0.01 | U | | <0.016 | U | | <0.06 | U | | <0.0034 | U | | <0.015 | U | | 0.008 | J | | <0.019 | U | | <0.0098 | U | |
| | | VMP-41-30-012913 | 1/29/2013 | 0.011 | J | | <0.0073 | U | | 0.0077 | | | <0.0094 | U | | <0.014 | U | | <0.055 | U | | <0.0031 | U | | 0.019 | | | <0.017 | U | | <0.018 | J | U | <0.0089 | U | |
| VMP-55 | 20 ft | VMP-55-20-021513 | 2/15/2013 | <33 | U | | <18 | U | | 1.3 | J | | <23 | U | | <36 | U | | <13 | U | | <7.6 | U | | 2900 | | | <41 | U | | <11 | U | | <22 | U | |

SEE LAST PAGE OF TABLE FOR NOTES

**TABLE 6**
**CUMULATIVE SUMMARY OF SOIL VAPOR ANALYTICAL DETECTIONS AND SCREENING RESULTS: PUBLIC WORKS YARD AND WRR - VOCS**

| Location | Depth | Sample ID | Sample Date | Chlorobenzene 420 | | | Chlorodibromomethane 57000 | | | Chloroethane | | | Chloroform 0.92 | | | Chloromethane | | | Cyclohexane | | | 1,2-Dibromoethane 0.06 | | | 1,2-Dichlorobenzene 1700 | | | 1,3-Dichlorobenzene | | | 1,4-Dichlorobenzene 6800 | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals |
| VMP-10 | 5 ft | VMP-10-5-090710 | 9/7/2010 | <0.0061 | U | | <0.011 | U | | <0.0035 | U | | <0.0064 | U | | <0.011 | U | | 0.0092 | | | <0.01 | U | | <0.0079 | U | | <0.0079 | U | | <0.0079 | U | |
| | | VMP-10-5-111810 | 11/17/2010 | <0.0056 | U | | <0.01 | U | | <0.0032 | U | | <0.0059 | U | | <0.01 | U | | 0.0048 | | | <0.0093 | U | | <0.0073 | U | | <0.0073 | U | | <0.0073 | U | |
| | | VMP-10-5-021011 | 2/10/2011 | <0.0055 | U | | <0.01 | U | | <0.0031 | U | | <0.0058 | U | | <0.0098 | U | | 0.023 | | | <0.0091 | U | | <0.0072 | U | | <0.0072 | U | | <0.0072 | U | |
| | | VMP-10-5-040511 | 4/5/2011 | <0.0051 | U | | <0.0094 | U | | <0.012 | U | | <0.0054 | U | | <0.0091 | U | | 0.0053 | | | <0.0084 | U | | <0.0066 | J | U | <0.0066 | U | | <0.0066 | J | U |
| | | VMP-10-5-07/2911 | 7/29/2011 | <0.0062 | U | | <0.011 | U | | <0.014 | U | | <0.0065 | U | | <0.011 | U | | <0.0046 | U | | <0.01 | U | | <0.008 | U | | <0.008 | U | | <0.008 | U | |
| | | VMP-10-5-110411 | 11/4/2011 | <0.0032 | U | | <0.0059 | U | | <0.0073 | U | | <0.0034 | U | | <0.0057 | U | | <0.0024 | U | | <0.0053 | U | | <0.0042 | U | | <0.0042 | U | | <0.0042 | U | |
| | | VMP-10-5-012512 | 1/26/2012 | <0.004 | U | | <0.0074 | U | | <0.0092 | U | | <0.0043 | U | | <0.0072 | U | | 0.00067 | J | | <0.0067 | U | | <0.0053 | U | | <0.0053 | U | | <0.0053 | U | |
| | | VMP-10-5-041212 | 4/12/2012 | <0.0043 | J | U | <0.008 | U | | <0.0099 | U | | <0.0046 | U | | <0.019 | U | | <0.0032 | U | | <0.0072 | U | | <0.0056 | U | | <0.0056 | U | | <0.0056 | U | |
| | | VMP-10-5-071312 | 7/13/2012 | <0.0044 | J | U | <0.0082 | U | | <0.01 | U | | <0.0047 | U | | <0.02 | U | | <0.0033 | J | U | <0.0074 | U | | <0.0058 | U | | <0.0058 | U | | <0.0058 | J | U |
| | | VMP-10-5-101612 | 10/16/2012 | <0.007 | U | | <0.013 | U | | <0.016 | U | | <0.0074 | U | | <0.031 | U | | 0.018 | | | <0.012 | U | | <0.0091 | U | | <0.0091 | U | | <0.0091 | U | |
| | | VMP-10-5-012913 | 1/29/2013 | <0.0065 | U | | <0.012 | U | | <0.015 | U | | <0.0069 | U | | <0.029 | U | | 0.0079 | | | <0.011 | U | | <0.0085 | U | | <0.0085 | J | U | <0.0085 | J | U |
| | | VMP-10-5-012913-DUP | 1/29/2013 | <0.0072 | U | | <0.013 | U | | <0.016 | U | | <0.0076 | U | | <0.032 | U | | 0.01 | | | <0.012 | U | | <0.0093 | U | | <0.0093 | J | U | <0.0093 | J | U |
| | 10 ft | VMP-10-10-090710 | 9/7/2010 | <0.0061 | U | | <0.011 | U | | <0.0035 | U | | <0.0064 | U | | <0.011 | U | | 0.0052 | | | <0.01 | U | | <0.0079 | U | | <0.0079 | U | | <0.0079 | U | |
| | | VMP-10-10-111810 | 11/17/2010 | <0.0059 | U | | <0.011 | U | | <0.0034 | U | | <0.0063 | U | | <0.011 | U | | 0.0053 | | | <0.0099 | U | | <0.0078 | U | | <0.0078 | U | | <0.0078 | U | |
| | | VMP-10-10-021111 | 2/11/2011 | <0.0046 | U | | <0.0086 | U | | <0.0027 | U | | <0.0049 | U | | <0.0083 | U | | 0.0034 | J | | <0.0078 | U | | <0.0061 | U | | <0.0061 | U | | <0.0061 | J | U |
| | | VMP-10-10-040611 | 4/6/2011 | <0.0061 | J | U | 0.0024 | J | | <0.014 | U | | <0.0064 | U | | <0.011 | U | | 0.0021 | J | | <0.01 | J | U | <0.0079 | J | U | <0.0079 | J | U | <0.0079 | J | U |
| | | VMP-10-10-072911 | 7/29/2011 | <0.0064 | U | | <0.012 | U | | <0.014 | U | | <0.0067 | U | | 0.0018 | J | | 0.0019 | J | | <0.011 | U | | <0.0083 | U | | <0.0083 | U | | <0.0083 | U | |
| | | VMP-10-10-110411 | 11/4/2011 | <0.0041 | J | U | <0.0076 | U | | <0.0094 | U | | <0.0044 | U | | <0.0074 | U | | <0.0031 | U | | <0.0069 | U | | <0.0054 | U | | <0.0054 | U | | <0.0054 | U | |
| | | VMP-10-10-110411-DUP | 11/4/2011 | <0.0041 | J | U | <0.0076 | J | U | <0.0094 | U | | <0.0044 | U | | <0.0074 | U | | <0.0031 | U | | <0.0069 | U | | <0.0054 | U | | <0.0054 | U | | <0.0054 | U | |
| | | VMP-10-10-012512 | 1/26/2012 | <0.004 | U | | <0.0074 | U | | <0.0092 | U | | <0.0043 | U | | <0.0072 | U | | <0.003 | U | | <0.0067 | U | | <0.0053 | U | | <0.0053 | U | | <0.0053 | U | |
| | | VMP-10-10-012512-DUP | 1/26/2012 | <0.0042 | U | | <0.0078 | U | | <0.0096 | U | | <0.0045 | U | | <0.0076 | U | | 0.0029 | J | | <0.007 | U | | 0.0015 | J | | <0.0055 | U | | <0.0055 | U | |
| | | VMP-10-10-041112 | 4/11/2012 | <0.0044 | U | | <0.0081 | U | | <0.01 | U | | <0.0047 | U | | 0.0079 | J | | 0.0069 | | | <0.0073 | U | | <0.0057 | U | | <0.0057 | J | U | <0.0057 | U | |
| | | VMP-10-10-071312 | 7/13/2012 | <0.0043 | J | U | <0.008 | U | | <0.0099 | U | | <0.0046 | U | | <0.019 | U | | <0.0032 | J | U | <0.0072 | U | | <0.0056 | U | | <0.0056 | U | | <0.0056 | J | U |
| | | VMP-10-10-101612 | 10/16/2012 | <0.0073 | U | | <0.013 | U | | <0.017 | U | | <0.0077 | U | | <0.033 | U | | 0.0058 | | | <0.012 | U | | <0.0095 | U | | <0.0095 | U | | <0.0095 | U | |
| | | VMP-10-10-012913 | 1/29/2013 | <0.0058 | U | | <0.011 | U | | <0.013 | U | | <0.0062 | U | | <0.026 | U | | <0.0043 | U | | <0.0097 | U | | <0.0076 | U | | <0.0076 | J | U | <0.0076 | U | |
| | 20 ft | VMP-10-20-090710 | 9/7/2010 | <0.0064 | U | | <0.012 | U | | <0.0036 | U | | <0.0067 | U | | <0.011 | U | | 0.0035 | J | | <0.011 | U | | <0.0083 | U | | <0.0083 | U | | <0.0083 | U | |
| | | VMP-10-20-090710-DUP | 9/7/2010 | <0.0059 | U | | <0.011 | U | | <0.0034 | U | | <0.0063 | U | | <0.011 | U | | 0.002 | J | | <0.0099 | U | | <0.0078 | U | | <0.0078 | U | | <0.0078 | U | |
| | | VMP-10-20-111810 | 11/17/2010 | <0.011 | U | | <0.021 | U | | <0.0064 | U | | 0.0017 | J | | <0.02 | U | | 0.0025 | J | | <0.019 | U | | <0.015 | U | | <0.015 | U | | <0.015 | U | |
| | | VMP-10-20-111810-Dup | 11/17/2010 | <0.0057 | U | | <0.01 | U | | <0.0032 | U | | 0.0014 | J | | <0.01 | U | | 0.0056 | | | <0.0095 | U | | <0.0074 | U | | <0.0074 | U | | <0.0074 | U | |
| | | VMP-10-20-021111 | 2/11/2011 | <0.0056 | U | | <0.01 | U | | <0.0032 | U | | <0.006 | U | | <0.01 | U | | 0.0027 | J | | <0.0094 | U | | <0.0073 | U | | <0.0073 | U | | <0.0073 | U | |
| | | VMP-10-20-040611 | 4/6/2011 | <0.0068 | J | U | <0.012 | U | | <0.016 | U | | <0.0072 | U | | <0.012 | U | | 0.0034 | J | | <0.011 | U | | <0.0088 | J | U | <0.0088 | J | U | <0.0088 | J | U |
| | | VMP-10-20-072911 | 7/29/2011 | <0.0063 | U | | <0.012 | U | | <0.014 | U | | <0.0067 | U | | <0.011 | U | | <0.0047 | U | | <0.01 | U | | <0.0082 | U | | <0.0082 | U | | <0.0082 | U | |
| | | VMP-10-20-110411 | 11/4/2011 | <0.0041 | J | U | <0.0076 | U | | <0.0094 | U | | <0.0044 | U | | <0.0074 | U | | <0.0031 | U | | <0.0069 | U | | <0.0054 | U | | <0.0054 | U | | <0.0054 | U | |
| | | VMP-10-20-012612 | 1/26/2012 | <0.0039 | U | | <0.0072 | U | | <0.0089 | U | | <0.0041 | U | | <0.0069 | U | | 0.0062 | | | <0.0064 | U | | <0.005 | U | | <0.005 | U | | <0.005 | U | |
| | | VMP-10-20-041212 | 4/12/2012 | <0.0043 | J | U | <0.008 | U | | <0.0099 | U | | <0.0046 | U | | <0.019 | U | | <0.0032 | U | | <0.0072 | U | | <0.0056 | U | | <0.0056 | U | | <0.0056 | J | U |
| | | VMP-10-20-071612 | 7/16/2012 | <0.0041 | J | U | <0.0076 | U | | <0.0094 | U | | <0.0044 | U | | <0.018 | U | | <0.0031 | J | U | <0.0069 | U | | <0.0054 | U | | <0.0054 | U | | <0.0054 | J | U |
| | | VMP-10-20-101612 | 10/16/2012 | <0.0073 | U | | <0.014 | U | | <0.017 | U | | <0.0078 | U | | <0.033 | U | | 0.0016 | J | | <0.012 | U | | <0.0096 | U | | <0.0096 | U | | <0.0096 | U | |
| | | VMP-10-20-012913 | 1/29/2013 | <0.0064 | U | | <0.012 | U | | <0.014 | U | | <0.0067 | U | | <0.028 | U | | <0.0048 | U | | <0.011 | U | | <0.0083 | U | | <0.0083 | J | U | <0.0083 | J | U |
| | 30 ft | VMP-10-30-041212 | 4/12/2012 | <0.0045 | U | | <0.0083 | U | | <0.01 | U | | <0.0048 | U | | <0.02 | U | | 0.005 | | | <0.0075 | U | | <0.0059 | U | | <0.0059 | U | | <0.0059 | U | |
| | | VMP-10-30-071612 | 7/16/2012 | <0.004 | J | U | <0.0074 | U | | <0.0091 | U | | <0.0042 | J | U | <0.018 | U | | <0.003 | J | U | <0.0066 | U | | <0.0052 | U | | <0.0052 | J | U | <0.0052 | J | U |
| | | VMP-10-30-101612 | 10/16/2012 | <0.0069 | U | | <0.013 | U | | <0.016 | U | | <0.0072 | U | | <0.031 | U | | 0.002 | J | | <0.012 | U | | <0.009 | U | | <0.009 | U | | <0.009 | U | |
| | | VMP-10-30-012913 | 1/29/2013 | <0.007 | U | | <0.013 | U | | <0.016 | U | | <0.0074 | U | | <0.031 | U | | <0.0052 | U | | <0.012 | U | | <0.0091 | U | | <0.0091 | U | | <0.0091 | J | U |
| VMP-11 | 5 ft | VMP-11-5-090710 | 9/7/2010 | <0.0057 | U | | <0.01 | U | | <0.0032 | U | | 0.0019 | J | | <0.01 | U | | 0.0012 | J | | <0.0095 | U | | <0.0074 | U | | <0.0074 | U | | <0.0074 | U | |
| | | VMP-11-5-112210 | 11/22/2010 | <0.0059 | U | | <0.011 | U | | <0.0034 | U | | 0.0039 | J | | <0.011 | U | | <0.0044 | U | | <0.0099 | U | | <0.0078 | U | | 0.0011 | J | | <0.0078 | U | |
| | | VMP-11-5-021511 | 2/15/2011 | <0.0052 | U | | <0.0097 | U | | <0.003 | U | | 0.0025 | J | | <0.0094 | U | | 0.0089 | | | <0.0088 | U | | <0.0068 | U | | <0.0068 | U | | <0.0068 | U | |
| | | VMP-11-5-040611 | 4/6/2011 | <0.05 | U | | <0.092 | U | | <0.11 | U | | <0.053 | U | | 0.055 | J | | 0.082 | | | <0.083 | U | | <0.065 | U | | <0.065 | U | | <0.065 | U | |
| | | VMP-11-5-080711 | 8/7/2011 | <0.068 | U | | <0.13 | U | | <0.16 | U | | <0.072 | U | | <0.12 | U | | <0.051 | U | | <0.11 | U | | <0.089 | U | | <0.089 | U | | <0.089 | U | |
| | | VMP-11-5-111111 | 11/11/2011 | <0.014 | U | | <0.025 | U | | <0.031 | U | | 0.006 | J | | <0.024 | U | | 0.14 | | | <0.022 | U | | <0.018 | U | | <0.018 | U | | <0.018 | U | |
| | | VMP-11-5-012612 | 1/26/2012 | <0.004 | U | | <0.0074 | U | | <0.0092 | U | | 0.01 | | | <0.0072 | U | | <0.003 | U | | <0.0067 | U | | <0.0053 | U | | <0.0053 | U | | <0.0053 | U | |
| | | VMP-11-5-041912 | 4/19/2012 | <0.0045 | U | | <0.0083 | U | | <0.01 | U | | <0.0048 | U | | <0.02 | U | | 0.0013 | J | | <0.0075 | U | | <0.0059 | U | | <0.0059 | U | | <0.0059 | J | U |
| | | VMP-11-5-071912 | 7/16/2012 | <0.0058 | J | U | <0.011 | U | | <0.013 | U | | <0.0062 | J | U | <0.026 | U | | 0.0032 | J | | <0.0098 | U | | <0.0076 | U | | <0.0076 | J | U | <0.0076 | J | U |
| | | VMP-11-5-101612 | 10/16/2012 | <0.0065 | U | | <0.012 | U | | <0.015 | U | | <0.0069 | U | | <0.029 | U | | <0.0049 | U | | <0.011 | U | | <0.0085 | U | | <0.0085 | U | | <0.0085 | U | |
| | | VMP-11-5-012913 | 1/29/2013 | <0.33 | U | | <0.61 | U | | <0.76 | U | | <0.35 | U | | <1.5 | U | | <0.25 | U | | <0.55 | U | | <0.43 | U | | <0.43 | U | | <0.43 | U | |
| | 8 ft | VMP-11-8-090810 | 9/8/2010 | <0.0059 | U | | <0.011 | U | | <0.0034 | U | | 0.0014 | J | | <0.011 | U | | 0.00085 | J | | <0.0099 | U | | <0.0078 | U | | <0.0078 | U | | <0.0078 | U | |
| | | VMP-11-8-112210 | 11/22/2010 | <0.0059 | U | | <0.011 | U | | <0.0034 | U | | <0.0063 | U | | <0.011 | U | | <0.0044 | U | | <0.0099 | U | | <0.0078 | U | | <0.0078 | U | | <0.0078 | U | |
| | | VMP-11-8-021111 | 2/11/2011 | <0.0058 | U | | <0.011 | U | | <0.0033 | U | | 0.0018 | J | | <0.01 | U | | 0.0013 | J | | <0.0096 | U | | <0.0075 | U | | <0.0075 | U | | <0.0075 | U | |
| | | VMP-11-8-021111-DUP | 2/11/2011 | <0.0054 | U | | <0.01 | U | | <0.0031 | U | | 0.0019 | J | | <0.0097 | U | | 0.001 | J | | <0.009 | U | | <0.0071 | U | | <0.0071 | U | | <0.0071 | U | |
| | | VMP-11-8-040611 | 4/6/2011 | <0.026 | U | | <0.047 | U | | <0.058 | U | | <0.027 | U | | <0.046 | U | | 0.042 | | | <0.043 | U | | <0.033 | U | | <0.033 | U | | <0.033 | U | |
| | | VMP-11-8-040611-DUP | 4/6/2011 | <0.022 | U | | <0.041 | U | | <0.051 | U | | 0.0029 | J | | <0.04 | U | | 0.047 | | | <0.037 | U | | <0.029 | U | | <0.029 | U | | <0.029 | U | |
| | | VMP-11-8-080711 | 8/7/2011 | <0.068 | U | | <0.13 | U | | <0.16 | U | | <0.072 | U | | <0.12 | U | | <0.051 | U | | <0.11 | U | | <0.089 | U | | <0.089 | U | | <0.089 | U | |
| | | VMP-11-8-111411 | 11/14/2011 | <0.004 | U | | <0.0075 | U | | <0.0093 | U | | 0.0026 | J | | <0.0073 | U | | 0.0077 | | | <0.0068 | U | | <0.0053 | U | | <0.0053 | U | | <0.0053 | U | |
| | | VMP-11-8-012612 | 1/26/2012 | <0.0039 | U | | <0.0073 | U | | <0.009 | U | | 0.0094 | | | <0.0071 | U | | <0.0029 | U | | <0.0066 | U | | <0.0051 | U | | <0.0051 | U | | <0.0051 | U | |
| | | VMP-11-8-041912 | 4/19/2012 | <0.0045 | U | | <0.0083 | U | | <0.01 | U | | <0.0048 | U | | <0.02 | U | | 0.001 | J | | <0.0075 | U | | <0.0059 | U | | <0.0059 | U | | <0.0059 | J | U |
| | | VMP-11-8-072012 | 7/20/2012 | <0.0045 | U | | <0.0083 | U | | <0.01 | U | | <0.0048 | U | | <0.02 | U | | <0.0034 | U | | <0.0075 | U | | <0.0059 | U | | <0.0059 | U | | <0.0059 | U | |
| | | VMP-11-8-101612 | 10/16/2012 | <0.0066 | U | | <0.012 | U | | <0.015 | U | | <0.007 | U | | <0.03 | U | | 0.0017 | J | | <0.011 | U | | <0.0086 | U | | <0.0086 | U | | <0.0086 | U | |
| | | VMP-11-8-101612-Dup | 10/16/2012 | <0.0066 | U | | <0.012 | U | | <0.015 | U | | 0.0042 | J | | <0.03 | U | | 0.0021 | J | | <0.011 | U | | <0.0087 | U | | <0.0087 | U | | <0.0087 | J | U |
| | | VMP-11-8-012913 | 1/29/2013 | <0.045 | U | | <0.084 | U | | <0.1 | U | | <0.048 | U | | <0.2 | U | | <0.034 | U | | <0.076 | U | | <0.059 | U | | <0.059 | U | | <0.059 | U | |
| | 29 ft | VMP-11-29-090810 | 9/8/2010 | <0.15 | U | | <0.27 | U | | <0.085 | U | | <0.16 | U | | <0.27 | U | | 0.068 | J | | <0.25 | U | | <0.19 | U | | <0.19 | U | | <0.19 | U | |
| | | VMP-11-29-112210 | 11/22/2010 | <2.1 | U | | <3.9 | U | | <1.2 | U | | <2.2 | U | | <3.8 | U | | <1.6 | U | | <3.5 | U | | <2.8 | U | | <2.8 | U | | <2.8 | U | |
| | | VMP-11-29-112210-Dup | 11/22/2010 | <1.5 | U | | <2.7 | U | | <0.84 | U | | <1.6 | U | | <2.6 | U | | <1.1 | U | | <2.5 | U | | <1.9 | U | | <1.9 | U | | <1.9 | U | |
| | | VMP-11-29-021411 | 2/14/2011 | <0.0058 | U | | <0.011 | U | | <0.0033 | U | | 0.0069 | | | <0.01 | U | | 0.032 | | | <0.0096 | U | | <0.0075 | U | | <0.0075 | U | | <0.0075 | U | |
| | | VMP-11-29-040611 | 4/6/2011 | <0.044 | U | | <0.08 | U | | <0.1 | U | | <0.046 | U | | <0.078 | U | | 0.065 | | | <0.073 | U | | <0.057 | U | | <0.057 | U | | <0.057 | U | |
| | | VMP-11-29-082511 | 8/25/2011 | <0.0064 | U | | <0.012 | U | | <0.014 | U | | 0.013 | | | <0.011 | U | | <0.0048 | U | | <0.011 | U | | <0.0083 | U | | <0.0083 | U | | <0.0083 | U | |
| | | VMP-11-29-082511-Dup | 8/25/2011 | <0.0064 | U | | <0.012 | U | | <0.014 | U | | 0.013 | | | <0.011 | U | | <0.0048 | U | | <0.011 | U | | <0.0083 | U | | <0.0083 | U | | <0.0083 | U | |
| | | VMP-11-29-111411 | 11/14/2011 | <0.004 | U | | <0.0074 | U | | <0.0092 | U | | 0.014 | | | <0.0072 | U | | 0.0014 | J | | <0.0067 | U | | <0.0053 | U | | <0.0053 | U | | <0.0053 | U | |
| | | VMP-11-29-012612 | 1/26/2012 | <0.0039 | U | | <0.0072 | U | | <0.0089 | U | | 0.024 | | | <0.0069 | U | | <0.0029 | U | | <0.0064 | U | | <0.005 | U | | <0.005 | U | | <0.005 | U | |
| | | VMP-11-29-042712 | 4/27/2012 | <0.004 | J | U | <0.0074 | U | | <0.0092 | U | | 0.019 | | | <0.018 | U | | 0.0029 | J | | <0.0067 | U | | <0.0053 | U | | <0.0053 | U | | <0.0053 | J | U |
| | | VMP-11-29-072012 | 7/23/2012 | <0.004 | U | | <0.0074 | U | | <0.0092 | U | | 0.019 | | | <0.018 | U | | 0.0067 | | | <0.0067 | U | | <0.0053 | U | | <0.0053 | U | | <0.0053 | U | |
| | | VMP-11-29-101612 | 10/16/2012 | <0.0068 | U | | <0.013 | U | | <0.016 | U | | 0.08 | | | <0.03 | U | | <0.0051 | U | | <0.011 | U | | <0.0089 | U | | <0.0089 | U | | <0.0089 | U | |
| | | VMP-11-29-012913 | 1/29/2013 | <0.0066 | U | | <0.012 | U | | <0.015 | U | | 0.28 | | | <0.03 | U | | <0.005 | U | | <0.011 | U | | <0.0087 | U | | <0.0087 | U | | <0.0087 | U | |
| | 38 ft | VMP-11-38-042312 | 4/23/2012 | <0.3 | U | | <0.56 | U | | <0.69 | U | | <0.32 | U | | <0.54 | U | | <0.22 | U | | <0.5 | U | | <0.39 | U | | <0.39 | U | | <0.39 | U | |
| | | VMP-11-38-042312-Dup | 4/23/2012 | <1 | U | | <2 | U | | <2.4 | U | | <1.1 | U | | <1.9 | U | | <0.79 | U | | <1.8 | U | | <1.4 | U | | <1.4 | U | | <1.4 | U | |
| | | VMP-11-38-072312 | 7/23/2012 | <0.5 | U | | <0.92 | U | | <1.1 | U | | <0.53 | U | | <0.9 | U | | <0.37 | U | | <0.83 | U | | <0.65 | U | | <0.65 | U | | <0.65 | U | |
| | | VMP-11-38-101612 | 10/16/2012 | <0.0069 | U | | <0.013 | U | | <0.016 | U | | 0.028 | | | 0.0075 | J | | 0.005 | | | <0.012 | U | | <0.009 | U | | <0.009 | U | | <0.009 | J | U |
| | | VMP-11-38-013013 | 1/30/2013 | <0.0064 | U | | <0.012 | U | | <0.014 | U | | 0.091 | | | <0.028 | U | | <0.0048 | U | | <0.011 | U | | <0.0083 | U | | <0.0083 | U | | <0.0083 | U | |

SEE LAST PAGE OF TABLE FOR NOTES

**TABLE 6**
**CUMULATIVE SUMMARY OF SOIL VAPOR ANALYTICAL DETECTIONS AND SCREENING RESULTS: PUBLIC WORKS YARD AND WRR - VOCS**

| Location | Depth | Sample ID | Sample Date | Chlorobenzene 420 | | | Chlorodibromomethane 57000 | | | Chloroethane | | | Chloroform 0.92 | | | Chloromethane | | | Cyclohexane | | | 1,2-Dibromoethane 0.06 | | | 1,2-Dichlorobenzene 1700 | | | 1,3-Dichlorobenzene | | | 1,4-Dichlorobenzene 6800 | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals |
| VMP-12 | 5 ft | VMP-12-5-090310 | 9/3/2010 | <6.2 | U | | <11 | U | | <3.5 | U | | <6.6 | U | | <11 | U | | 410 | | | <10 | U | | <8.1 | U | | <8.1 | U | | <8.1 | U | |
| | | VMP-12-5-120310 | 12/3/2010 | <61 | U | | <110 | U | | <35 | U | | <65 | U | | <110 | U | | 750 | | | <100 | U | | <80 | U | | <80 | U | | <80 | U | |
| | | VMP-12-5-021511 | 2/15/2011 | <2.8 | U | | <5.2 | U | | <1.6 | U | | <3 | U | | <5 | U | | 88 | | | <4.7 | U | | <3.7 | U | | <3.7 | U | | <3.7 | U | |
| | | VMP-12-5-041911 | 4/19/2011 | <20 | U | | <38 | U | | <47 | U | | <22 | U | | <37 | U | | 300 | | | <34 | U | | <27 | U | | <27 | U | | <27 | U | |
| | | VMP-12-5-080411 | 8/4/2011 | <5.3 | U | | <9.8 | U | | <12 | U | | <5.6 | U | | <9.5 | U | | 230 | | | <8.9 | U | | <6.9 | U | | <6.9 | U | | <6.9 | U | |
| | | VMP-12-5-111611 | 11/16/2011 | 0.0018 | J | | <0.0069 | U | | <0.0086 | U | | <0.004 | U | | <0.0067 | U | | 0.016 | | | <0.0063 | U | | <0.0049 | U | | <0.0049 | U | | <0.0049 | U | |
| | | VMP-12-5-012412 | 1/24/2012 | <0.042 | U | | <0.078 | U | | <0.096 | U | | <0.045 | U | | <0.076 | U | | 0.95 | | | <0.07 | U | | <0.055 | U | | <0.055 | U | | <0.055 | U | |
| | | VMP-12-5-041912 | 4/19/2012 | <0.0042 | U | | <0.0078 | U | | <0.0096 | U | | <0.0045 | U | | 0.0047 | J | | 0.046 | | | 0.0016 | J | | <0.0055 | U | | <0.0055 | U | | <0.0055 | U | |
| | | VMP-12-5-072612 | 7/26/2012 | <0.0045 | J | U | <0.0083 | U | | <0.01 | U | | 0.0049 | J | | <0.02 | U | | 0.006 | | | <0.0075 | U | | <0.0059 | U | | <0.0059 | U | | <0.0059 | J | U |
| | | VMP-12-5-072612-Dup | 7/26/2012 | <0.0041 | J | U | <0.0076 | U | | <0.0094 | U | | <0.0043 | U | | <0.018 | U | | <0.0031 | U | | <0.0068 | U | | <0.0054 | U | | <0.0054 | U | | <0.0054 | J | U |
| | | VMP-12-5-102412 | 10/24/2012 | <0.0069 | J | U | <0.013 | U | | <0.016 | U | | 0.0014 | J | | <0.031 | U | | <0.0052 | U | | <0.012 | U | | <0.009 | U | | <0.009 | U | | <0.009 | U | |
| | | VMP-12-5-021813 | 2/18/2013 | <0.0062 | U | | <0.011 | U | | <0.014 | U | | <0.0066 | U | | <0.028 | U | | 0.0022 | J | | <0.01 | U | | <0.0081 | U | | <0.0081 | U | | <0.0081 | J | U |
| | 11.5 ft | VMP-12-11.5-090310 | 9/3/2010 | <7.9 | U | | <15 | U | | <4.6 | U | | <8.4 | U | | <14 | U | | 580 | | | <13 | U | | <10 | U | | <10 | U | | <10 | U | |
| | | VMP-12-11.5-120310 | 12/3/2010 | <6.9 | U | | <13 | U | | <3.9 | U | | <7.3 | U | | <12 | U | | 340 | | | <11 | U | | <9 | U | | <9 | U | | <9 | U | |
| | | VMP-12-11.5-021511 | 2/15/2011 | <6.2 | U | | <11 | U | | <3.5 | U | | <6.5 | U | | <11 | U | | 450 | | | <10 | U | | <8 | U | | <8 | U | | <8 | U | |
| | | VMP-12-11.5-021511-DUP | 2/15/2011 | <5.3 | U | | <9.8 | U | | <3 | U | | <5.6 | U | | <9.5 | U | | 390 | | | <8.9 | U | | <6.9 | U | | <6.9 | U | | <6.9 | U | |
| | | VMP-12-11.5-041911 | 4/19/2011 | <19 | U | | <34 | U | | <43 | U | | <20 | U | | <33 | U | | 420 | | | <31 | U | | <24 | U | | <24 | U | | <24 | U | |
| | | VMP-12-11.5-080411 | 8/4/2011 | <6.5 | U | | <12 | U | | <15 | U | | <6.9 | U | | <12 | U | | 160 | | | <11 | U | | <8.5 | U | | <8.5 | U | | <8.5 | U | |
| | | VMP-12-11.5-111611 | 11/16/2011 | 0.028 | J | | <0.096 | U | | <0.12 | U | | <0.055 | U | | <0.093 | U | | 0.28 | | | <0.086 | U | | <0.068 | U | | <0.068 | U | | <0.068 | U | |
| | | VMP-12-11.5-012412 | 1/24/2012 | <0.48 | U | | <0.89 | U | | <1.1 | U | | <0.51 | U | | <0.87 | U | | 2.8 | | | <0.81 | U | | <0.63 | U | | <0.63 | U | | <0.63 | U | |
| | | VMP-12-11.5-041912 | 4/19/2012 | <0.044 | U | | <0.081 | U | | <0.1 | U | | <0.047 | U | | <0.079 | U | | 0.06 | | | <0.073 | U | | <0.057 | U | | <0.057 | U | | <0.057 | U | |
| | | VMP-12-11.5-082012 | 8/20/2012 | <0.007 | J | U | <0.013 | U | | <0.016 | U | | 0.0062 | J | | <0.031 | U | | <0.0052 | U | | <0.012 | U | | <0.0091 | U | | 0.003 | J | | <0.0091 | J | U |
| | | VMP-12-11.5-102612 | 10/26/2012 | <0.0066 | U | | <0.012 | U | | <0.015 | U | | <0.007 | U | | <0.03 | U | | 0.0037 | J | | <0.011 | U | | <0.0087 | U | | <0.0087 | U | | <0.0087 | U | |
| | | VMP-12-11.5-021813 | 2/18/2013 | <0.0066 | U | | <0.012 | U | | <0.015 | U | | <0.007 | U | | <0.03 | U | | <0.005 | U | | <0.011 | U | | <0.0087 | U | | <0.0087 | U | | <0.0087 | U | |
| | 25 ft | VMP-12-25-090310 | 9/3/2010 | <10 | U | | <19 | U | | <5.8 | U | | <11 | U | | <18 | U | | 650 | | | <17 | U | | <13 | U | | <13 | U | | <13 | U | |
| | | VMP-12-25-120310 | 12/3/2010 | <0.5 | U | | <0.93 | U | | <0.29 | U | | <0.53 | U | | <0.9 | U | | 18 | | | <0.84 | U | | <0.66 | U | | <0.66 | U | | <0.66 | U | |
| | | VMP-12-25-021511 | 2/15/2011 | <12 | U | | <23 | U | | <7 | U | | <13 | U | | <22 | U | | 410 | | | <20 | U | | <16 | U | | <16 | U | | <16 | U | |
| | | VMP-12-25-041911 | 4/19/2011 | <20 | U | | <37 | U | | <46 | U | | <21 | U | | <36 | U | | 430 | | | <33 | U | | <26 | U | | <26 | U | | <26 | U | |
| | | VMP-12-25-080411 | 8/4/2011 | <13 | U | | <23 | U | | <29 | U | | <13 | U | | <23 | U | | 320 | | | <21 | U | | <16 | U | | <16 | U | | <16 | U | |
| | | VMP-12-25-111611 | 11/16/2011 | 4.8 | J | | <27 | U | | <33 | U | | <15 | U | | <26 | U | | 320 | | | <24 | U | | <19 | U | | <19 | U | | <19 | U | |
| | | VMP-12-25-012412 | 1/24/2012 | <5.5 | U | | <10 | U | | <13 | U | | <5.8 | U | | <9.9 | U | | 460 | | J | <9.2 | U | | <7.2 | U | | <7.2 | U | | <7.2 | U | |
| | | VMP-12-25-012412-DUP | 1/24/2012 | <40 | U | | <74 | U | | <92 | U | | <43 | U | | <72 | U | | 410 | | | <67 | U | | <53 | U | | <53 | U | | <53 | U | |
| | | VMP-12-25-041912 | 4/19/2012 | <4.2 | U | | <7.8 | U | | <9.6 | U | | <4.5 | U | | <7.6 | U | | 54 | | | <7 | U | | <5.5 | U | | <5.5 | U | | <5.5 | U | |
| | | VMP-12-25-072712 | 7/27/2012 | <4.6 | U | | <8.6 | U | | <11 | U | | <4.9 | U | | <8.3 | U | | 59 | | | <7.7 | U | | <6 | U | | <6 | U | | <6 | U | |
| | | VMP-12-25-072712-Dup | 7/27/2012 | <4.6 | U | | <8.6 | U | | <11 | U | | <4.9 | U | | <8.3 | U | | 73 | | | <7.7 | U | | <6 | U | | <6 | U | | <6 | U | |
| | | VMP-12-25-102512 | 10/25/2012 | <2 | U | | <3.7 | U | | <4.6 | U | | <2.1 | U | | <3.6 | U | | 3.1 | | | <3.3 | U | | <2.6 | U | | <2.6 | U | | <2.6 | U | |
| | | VMP-12-25-021513 | 2/15/2013 | <3.7 | U | | <6.8 | U | | <8.5 | U | | <3.9 | U | | <6.6 | U | | 20 | | J | <6.2 | U | | <4.8 | U | | <4.8 | U | | <4.8 | U | |
| | 39 ft | VMP-12-39-041911 | 4/19/2011 | <19 | U | | <36 | U | | <44 | U | | <20 | U | | <35 | U | | 570 | | | <32 | U | | <25 | U | | <25 | U | | <25 | U | |
| | | VMP-12-39-012412 | 1/24/2012 | <40 | U | | <74 | U | | <92 | U | | <43 | U | | <72 | U | | 560 | | | <67 | U | | <53 | U | | <53 | U | | <53 | U | |
| | | VMP-12-39-041912 | 4/19/2012 | <20 | U | | <37 | U | | <46 | U | | <21 | U | | <36 | U | | 260 | | | <34 | U | | <26 | U | | <26 | U | | <26 | U | |
| | | VMP-12-39-072612 | 7/26/2012 | <9.2 | U | | <17 | U | | <21 | U | | <9.8 | U | | <17 | U | | 110 | | | <15 | U | | <12 | U | | <12 | U | | <12 | U | |
| | | VMP-12-39-102412 | 10/24/2012 | <24 | U | | <45 | U | | <56 | U | | <26 | U | | <44 | U | | 66 | | | <41 | U | | <32 | U | | <32 | U | | <32 | U | |
| | | VMP-12-39-021513 | 2/15/2013 | <11 | U | | <21 | U | | 2.2 | J | | <12 | U | | <20 | U | | 180 | | | <18 | U | | <14 | U | | <14 | U | | <14 | U | |
| VMP-13 | 5 ft | VMP 13-5-091310 | 9/13/2010 | <0.04 | U | | <0.075 | U | | <0.023 | U | | <0.043 | U | | <0.073 | U | | 0.014 | J | | <0.068 | U | | <0.053 | U | | <0.053 | U | | <0.053 | U | |
| | | VMP-13-5-120110 | 12/1/2010 | <0.0054 | U | | <0.0099 | U | | <0.0031 | U | | <0.0057 | U | | <0.0096 | U | | 0.031 | | | <0.009 | U | | <0.007 | U | | <0.007 | U | | <0.007 | U | |
| | | VMP-13-5-021811 | 2/18/2011 | <0.0064 | U | | <0.012 | U | | <0.0036 | U | | <0.0067 | U | | <0.011 | U | | 0.003 | J | | <0.011 | U | | <0.0083 | U | | <0.0083 | U | | <0.0083 | U | |
| | | VMP-13-5-040511 | 4/5/2011 | <0.013 | U | | <0.024 | U | | <0.029 | U | | <0.013 | U | | <0.023 | U | | 0.0021 | J | | <0.021 | U | | <0.016 | J | U | <0.016 | U | | <0.016 | J | U |
| | | VMP-13-5-080911 | 8/9/2011 | 0.0046 | J | | <0.025 | U | | <0.031 | U | | <0.014 | U | | <0.024 | U | | 0.0068 | J | | <0.023 | U | | <0.018 | U | | <0.018 | J | U | <0.018 | J | U |
| | | VMP-13-5-080911-DUP | 8/9/2011 | 0.0044 | J | | <0.022 | U | | <0.028 | U | | <0.013 | U | | <0.022 | U | | 0.0048 | J | | <0.02 | U | | <0.016 | U | | <0.016 | U | | <0.016 | U | |
| | | VMP-13-5-111411 | 11/14/2011 | <0.0042 | U | | <0.0078 | U | | <0.0097 | U | | <0.0045 | U | | <0.0076 | U | | <0.0032 | U | | <0.0071 | U | | <0.0055 | U | | <0.0055 | U | | <0.0055 | U | |
| | | VMP-13-5-012712 | 1/27/2012 | <0.036 | U | | <0.066 | U | | <0.082 | U | | <0.038 | U | | <0.064 | U | | 0.081 | | J | <0.06 | U | | <0.046 | U | | <0.046 | U | | <0.046 | U | |
| | | VMP-13-5-042012 | 4/20/2012 | <0.0041 | U | | <0.0076 | U | | <0.0094 | U | | 0.0022 | J | | <0.018 | U | | <0.0031 | U | | <0.0069 | U | | <0.0054 | U | | <0.0054 | U | | <0.0054 | J | U |
| | | VMP-13-5-071912 | 7/19/2012 | 0.0011 | J | | <0.008 | U | | <0.0099 | U | | 0.0056 | | | <0.019 | J | U | 0.0028 | J | | <0.0072 | J | U | <0.0056 | U | | <0.0056 | U | | <0.0056 | J | U |
| | | VMP-13-5-071912-Dup | 7/19/2012 | 0.0011 | J | | <0.008 | U | | <0.0099 | U | | 0.006 | | | <0.019 | U | | 0.0025 | J | | <0.0072 | U | | <0.0056 | U | | <0.0056 | U | | <0.0056 | U | |
| | | VMP-13-5-100912 | 10/9/2012 | <0.0066 | U | | <0.012 | U | | <0.015 | U | | <0.007 | U | | <0.03 | U | | 0.0014 | J | | <0.011 | U | | <0.0087 | U | | <0.0087 | U | | <0.0087 | J | U |
| | | VMP-13-5-012913 | 1/29/2013 | <0.0072 | U | | <0.013 | U | | <0.016 | U | | <0.0076 | U | | <0.032 | U | | <0.0054 | U | | <0.012 | U | | <0.0093 | U | | <0.0093 | U | | <0.0093 | U | |
| | 10.5 ft | VMP 13-10.5-091310 | 9/13/2010 | <0.015 | U | | <0.028 | U | | <0.0086 | U | | <0.016 | U | | <0.027 | U | | 0.014 | | | <0.025 | U | | <0.02 | U | | <0.02 | U | | <0.02 | U | |
| | | VMP 13-10.5-091310-Dup | 9/13/2010 | <0.015 | U | | <0.027 | U | | <0.0084 | U | | <0.016 | U | | <0.026 | U | | 0.015 | | | <0.024 | U | | <0.019 | U | | <0.019 | U | | <0.019 | U | |
| | | VMP-13-10.5-120110 | 12/1/2010 | <0.006 | U | | <0.011 | U | | <0.0034 | U | | 0.0012 | J | | <0.011 | U | | 0.0029 | J | | <0.01 | U | | <0.0078 | U | | <0.0078 | U | | <0.0078 | U | |
| | | VMP-13-10.5-120110-DUP | 12/1/2010 | <0.0062 | U | | <0.012 | U | | <0.0036 | U | | 0.00098 | J | | <0.011 | U | | 0.0048 | | | <0.01 | U | | <0.0081 | U | | <0.0081 | U | | <0.0081 | U | |
| | | VMP-13-10.5-021811 | 2/18/2011 | <2.5 | U | | <4.6 | U | | <1.4 | U | | <2.6 | U | | <4.4 | U | | 0.78 | J | | <4.1 | U | | <3.2 | U | | <3.2 | U | | <3.2 | U | |
| | | VMP-13-10.5-021811-DUP | 2/18/2011 | <2.4 | U | | <4.4 | U | | <1.4 | U | | <2.5 | U | | <4.2 | U | | 0.9 | J | | <4 | U | | <3.1 | U | | <3.1 | U | | <3.1 | U | |
| | | VMP-13-10.5-040511-DUP | 4/5/2011 | <0.0064 | U | | <0.012 | J | U | <0.014 | U | | <0.0067 | U | | <0.011 | U | | 0.0039 | J | | <0.011 | J | U | <0.0083 | U | | <0.0083 | U | | <0.0083 | J | U |
| | | VMP-13-10.5-080911 | 8/9/2011 | <0.14 | U | | <0.26 | U | | <0.32 | U | | <0.15 | U | | <0.25 | U | | <0.1 | U | | <0.23 | U | | <0.18 | U | | <0.18 | U | | <0.18 | U | |
| | | VMP-13-10.5-111411 | 11/14/2011 | <0.004 | U | | <0.0075 | U | | <0.0093 | U | | <0.0043 | U | | <0.0073 | U | | <0.003 | U | | <0.0068 | U | | <0.0053 | U | | <0.0053 | U | | <0.0053 | U | |
| | | VMP-13-10.5-012712 | 1/26/2012 | <0.011 | U | | <0.021 | U | | <0.026 | U | | <0.012 | U | | <0.02 | U | | 0.029 | | | <0.019 | U | | <0.015 | U | | <0.015 | U | | <0.015 | U | |
| | | VMP-13-10.5-012712-DUP | 1/26/2012 | <0.016 | U | | <0.03 | U | | <0.037 | U | | <0.017 | U | | <0.029 | U | | 0.043 | | | <0.027 | U | | <0.021 | U | | <0.021 | U | | <0.021 | U | |
| | | VMP-13-10.5-042012 | 4/20/2012 | <0.004 | U | | <0.0074 | U | | <0.0092 | U | | 0.0016 | J | | <0.018 | U | | 0.0013 | J | | 0.0015 | J | | <0.0053 | U | | <0.0053 | U | | <0.0053 | J | U |
| | | VMP-13-10.5-071912 | 7/19/2012 | 0.00092 | J | | <0.008 | U | | <0.0099 | U | | 0.0032 | J | | <0.019 | U | | 0.0048 | | | <0.0072 | J | U | <0.0056 | U | | 0.0082 | | | <0.0056 | U | |
| | | VMP-13-10.5-100912 | 10/9/2012 | <0.0057 | U | | <0.01 | U | | <0.013 | U | | <0.006 | U | | <0.026 | U | | 0.003 | J | | <0.0095 | U | | <0.0074 | U | | <0.0074 | U | | <0.0074 | U | |
| | | VMP-13-10.5-100912-Dup | 10/9/2012 | <0.0068 | U | | <0.013 | U | | <0.016 | U | | <0.0072 | U | | <0.03 | U | | <0.0051 | U | | <0.011 | U | | <0.0089 | U | | <0.0089 | U | | <0.0089 | U | |
| | | VMP-13-10.5-013013 | 1/30/2013 | <0.0058 | U | | <0.011 | U | | <0.013 | U | | <0.0062 | U | | <0.026 | U | | <0.0043 | U | | <0.0097 | U | | <0.0076 | U | | <0.0076 | U | | <0.0076 | U | |
| | 21.5 ft | VMP 13-21.5-091310 | 9/13/2010 | <11 | U | | <21 | U | | <6.4 | U | | <12 | U | | <20 | U | | 2.5 | J | | <18 | U | | <14 | U | | <14 | U | | <14 | U | |
| | | VMP-13-21.5-120110 | 12/1/2010 | <22 | U | | <40 | U | | <12 | U | | <23 | U | | <39 | U | | <16 | U | | <36 | U | | <28 | U | | <28 | U | | <28 | U | |
| | | VMP-13-21.5-021811 | 2/18/2011 | <3.2 | U | | <6 | U | | <1.8 | U | | <3.4 | U | | <5.8 | U | | 0.7 | J | | <5.4 | U | | <4.2 | U | | <4.2 | U | | <4.2 | U | |
| | | VMP-13-21.5-040511 | 4/5/2011 | <4.6 | U | | <8.6 | U | | <11 | U | | <4.9 | U | | <8.3 | U | | 1 | J | | <7.8 | U | | <6.1 | U | | <6.1 | U | | <6.1 | U | |
| | | VMP-13-21.5-080911 | 8/9/2011 | <0.58 | U | | <1.1 | U | | <1.3 | U | | <0.62 | U | | <1 | U | | <0.43 | U | | <0.97 | U | | <0.76 | U | | <0.76 | U | | <0.76 | U | |
| | | VMP-13-21.5-111411 | 11/14/2011 | <2.6 | U | | <4.9 | U | | <6.1 | U | | <2.8 | U | | <4.7 | U | | 0.67 | J | | <4.4 | U | | <3.4 | U | | 0.56 | J | | 0.77 | J | |
| | | VMP-13-21.5-111411-DUP | 11/14/2011 | <2.6 | U | | <4.9 | U | | <6.1 | U | | <2.8 | U | | <4.7 | U | | 0.95 | J | | <4.4 | U | | <3.4 | U | | <3.4 | U | | 0.71 | J | |
| | | VMP-13-21.5-012712 | 1/27/2012 | <0.62 | U | | <1.1 | U | | <1.4 | U | | <0.65 | U | | <1.1 | U | | 0.9 | | J | <1 | U | | <0.8 | U | | <0.8 | U | | <0.8 | U | |
| | | VMP-13-21.5-042012 | 4/20/2012 | 0.037 | J | | <0.13 | U | | <0.16 | U | | <0.073 | U | | <0.31 | U | | 0.18 | | | <0.11 | U | | <0.09 | U | | <0.09 | U | | 0.014 | J | |
| | | VMP-13-21.5-071912 | 7/19/2012 | 0.0013 | J | | <0.008 | U | | <0.0099 | U | | <0.0046 | U | | <0.019 | U | | 0.0053 | | | <0.0072 | J | U | <0.0056 | U | | 0.0067 | | | <0.0056 | U | |
| | | VMP-13-21.5-100912 | 10/9/2012 | <0.007 | U | | <0.013 | U | | <0.016 | U | | <0.0074 | U | | <0.031 | U | | 0.0028 | J | | <0.012 | U | | <0.0091 | U | | <0.0091 | U | | <0.0091 | U | |
| | | VMP-13-21.5-013013 | 1/30/2013 | <0.0068 | U | | <0.013 | U | | <0.016 | U | | 0.082 | | | <0.03 | U | | <0.0051 | U | | <0.011 | U | | <0.0089 | U | | <0.0089 | J | U | <0.0089 | J | U |
| | 29.5 ft | VMP-13-29.5-021811 | 2/18/2011 | <99 | U | | <180 | U | | <57 | U | | <100 | U | | <180 | U | | <74 | U | | <160 | U | | <130 | U | | <130 | U | | <130 | U | |
| | | VMP-13-29.5-040511 | 4/5/2011 | <64 | U | | <120 | U | | <150 | U | | <68 | U | | <120 | U | | <48 | U | | <110 | U | | <84 | U | | <84 | U | | <84 | U | |
| | | VMP-13-29.5-013012 | 1/30/2012 | <2 | U | | <3.6 | U | | <4.5 | U | | <2.1 | U | | <3.5 | U | | 4 | | J | <3.3 | U | | <2.6 | U | | <2.6 | U | | <2.6 | U | |
| | | VMP-13-29.5-042012 | 4/20/2012 | 1.1 | J | | <4.8 | U | | <5.9 | U | | <2.7 | U | | <12 | U | | 2.6 | | | <4.3 | U | | <3.4 | U | | <3.4 | U | | <3.4 | U | |
| | | VMP-13-29.5-071912 | 7/19/2012 | <7.4 | U | | <14 | U | | <17 | U | | <7.9 | U | | <13 | U | | <5.5 | U | | <12 | U | | <9.7 | U | | <9.7 | U | | <9.7 | U | |
| | | VMP-13-29.5-100912 | 10/9/2012 | <7 | U | | <13 | U | | <16 | U | | <7.4 | U | | <12 | U | | 2.2 | J | | <12 | U | | <9.1 | U | | <9.1 | U | | <9.1 | U | |
| | | VMP-13-29.5-013013 | 1/30/2013 | <2.9 | U | | <5.4 | U | | <6.8 | U | | <3.1 | U | | <13 | U | | <2.2 | U | | <4.9 | U | | <3.8 | U | | <3.8 | U | | <3.8 | U | |

SEE LAST PAGE OF TABLE FOR NOTES

**TABLE 6**
**CUMULATIVE SUMMARY OF SOIL VAPOR ANALYTICAL DETECTIONS AND SCREENING RESULTS: PUBLIC WORKS YARD AND WRR - VOCS**

| Location | Depth | Sample ID | Sample Date | Chlorobenzene 420 | | | Chlorodibromomethane 57000 | | | Chloroethane | | | Chloroform 0.92 | | | Chloromethane | | | Cyclohexane | | | 1,2-Dibromoethane 0.06 | | | 1,2-Dichlorobenzene 1700 | | | 1,3-Dichlorobenzene | | | 1,4-Dichlorobenzene 6800 | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals |
| VMP-14 | 5 ft | VMP 14-5-091010 | 9/10/2010 | <0.28 | U | | <0.53 | U | | <0.16 | U | | <0.3 | U | | <0.51 | U | | 0.85 | | | <0.48 | U | | <0.37 | U | | <0.37 | U | | <0.37 | U | |
| | | VMP-14-5-120110 | 12/1/2010 | <0.0055 | U | | <0.01 | U | | <0.0032 | U | | 0.00067 | J | | <0.0099 | U | | 0.001 | J | | <0.0092 | U | | <0.0072 | U | | <0.0072 | U | | <0.0072 | U | |
| | | VMP-14-5-021711 | 2/17/2011 | <0.0061 | U | | <0.011 | U | | <0.0035 | U | | <0.0064 | U | | <0.011 | U | | 0.069 | | | <0.01 | U | | <0.0079 | U | | <0.0079 | U | | <0.0079 | U | |
| | | VMP-14-5-040511 | 4/5/2011 | <0.0062 | U | | <0.011 | U | | <0.014 | U | | <0.0066 | U | | <0.011 | U | | 0.0013 | J | | <0.01 | U | | <0.0081 | J | U | <0.0081 | J | U | <0.0081 | J | U |
| | | VMP-14-5-080811 | 8/8/2011 | <6.5 | U | | <12 | U | | <15 | U | | <6.9 | U | | <12 | U | | 91 | | | <11 | U | | <8.4 | U | | <8.4 | U | | <8.4 | U | |
| | | VMP-14-5-111411 | 11/14/2011 | <0.016 | U | | <0.03 | U | | <0.037 | U | | <0.017 | U | | <0.029 | U | | <0.012 | U | | <0.027 | U | | <0.021 | U | | <0.021 | U | | <0.021 | U | |
| | | VMP-14-5-042012 | 4/20/2012 | <0.0039 | J | U | <0.0073 | U | | <0.009 | U | | <0.0042 | U | | <0.018 | U | | 0.008 | | | <0.0066 | U | | 0.0012 | J | | 0.0014 | J | | <0.0051 | J | U |
| | | VMP-14-5-072312 | 7/23/2012 | <0.0047 | U | | <0.0088 | U | | <0.011 | U | | 0.0013 | J | | 0.0039 | J | | <0.0035 | U | | <0.0079 | U | | <0.0062 | U | | <0.0062 | U | | <0.0062 | U | |
| | | VMP-14-5-101012 | 10/10/2012 | <0.0066 | U | | <0.012 | U | | <0.015 | U | | <0.007 | U | | <0.03 | U | | <0.005 | U | | <0.011 | U | | <0.0087 | U | | <0.0087 | U | | <0.0087 | U | |
| | | VMP-14-5-013113 | 1/31/2013 | <0.0062 | U | | <0.011 | U | | <0.014 | U | | <0.0066 | U | | <0.028 | U | | <0.0046 | U | | <0.01 | U | | <0.0081 | U | | <0.0081 | J | U | <0.0081 | J | U |
| | 11.5 ft | VMP 14-11.5-091010 | 9/10/2010 | <4.4 | U | | <8.1 | U | | <2.5 | U | | <4.7 | U | | <7.9 | U | | 140 | | | <7.3 | U | | <5.7 | U | | <5.7 | U | | <5.7 | U | |
| | | VMP-14-11.5-120110 | 12/2/2010 | <0.39 | U | | <0.72 | U | | <0.22 | U | | <0.41 | U | | <0.69 | U | | 3.6 | | | <0.64 | U | | <0.5 | U | | <0.5 | U | | <0.5 | U | |
| | | VMP-14-11.5-120110-DUP | 12/2/2010 | <0.35 | U | | <0.65 | U | | <0.2 | U | | <0.37 | U | | <0.63 | U | | 3.7 | | | <0.58 | U | | <0.46 | U | | <0.46 | U | | <0.46 | U | |
| | | VMP-14-11.5-021711 | 2/17/2011 | <0.13 | U | | <0.24 | U | | <0.073 | U | | <0.13 | U | | <0.23 | U | | 2.7 | | | <0.21 | U | | <0.16 | U | | <0.16 | U | | <0.16 | U | |
| | | VMP-14-11.5-021711-DUP | 2/17/2011 | <0.13 | U | | <0.24 | U | | <0.073 | U | | <0.13 | U | | <0.23 | U | | 3 | | | <0.21 | U | | <0.16 | U | | <0.16 | U | | <0.16 | U | |
| | | VMP-14-11.5-040511 | 4/5/2011 | <0.021 | U | | <0.038 | U | | 0.037 | J | | <0.022 | U | | <0.037 | U | | 1.2 | | | <0.034 | U | | <0.027 | U | | <0.027 | U | | <0.027 | U | |
| | | VMP-14-11.5-080811 | 8/8/2011 | <0.64 | U | | <1.2 | U | | 0.24 | J | | <0.68 | U | | <1.1 | U | | 1.6 | | | <1.1 | U | | <0.84 | U | | <0.84 | U | | <0.84 | U | |
| | | VMP-14-11.5-111511 | 11/15/2011 | <0.99 | U | | <1.8 | U | | <2.3 | U | | <1 | U | | <1.8 | U | | 12 | | | <1.6 | U | | <1.3 | U | | 0.21 | J | | 0.31 | J | |
| | | VMP-14-11.5-012612 | 1/26/2012 | <4 | U | | <7.5 | U | | <9.3 | U | | <4.3 | U | | <7.3 | U | | 22 | | | <6.8 | U | | <5.3 | U | | <5.3 | U | | <5.3 | U | |
| | | VMP-14-11.5-042312 | 4/23/2012 | <0.0042 | J | U | <0.0078 | U | | <0.0096 | U | | <0.0045 | U | | <0.019 | U | | 0.0056 | | | <0.007 | U | | <0.0055 | U | | <0.0055 | U | | <0.0055 | J | U |
| | | VMP-14-11.5-042312-Dup | 4/23/2012 | <0.0042 | J | U | <0.0078 | U | | <0.0096 | U | | <0.0045 | U | | <0.019 | U | | 0.0053 | | | <0.007 | U | | <0.0055 | U | | <0.0055 | U | | <0.0055 | J | U |
| | | VMP-14-11.5-072512 | 7/25/2012 | <1.5 | U | | <2.7 | U | | <3.4 | U | | <1.6 | U | | <2.6 | U | | 1.8 | | | <2.5 | U | | <1.9 | U | | <1.9 | U | | <1.9 | U | |
| | | VMP-14-11.5-101012 | 10/10/2012 | <0.0064 | U | | <0.012 | U | | <0.014 | U | | <0.0067 | U | | <0.028 | U | | 0.0029 | J | | <0.011 | U | | <0.0083 | U | | <0.0083 | U | | <0.0083 | U | |
| | | VMP-14-11.5-013113 | 1/31/2013 | <0.0059 | J | U | <0.011 | U | | <0.014 | U | | 0.0094 | | | <0.027 | U | | <0.0044 | U | | <0.0099 | U | | <0.0078 | J | U | <0.0078 | J | U | <0.0078 | J | U |
| | 20 ft | VMP 14-20-091010 | 9/10/2010 | <87 | U | | <120 | U | | <38 | U | | <71 | U | | <120 | U | | 250 | | | <110 | U | | <87 | U | | <87 | U | | <87 | U | |
| | | VMP-14-20-091010-Dup | 9/10/2010 | <70 | U | | <130 | U | | <40 | U | | <74 | U | | <120 | U | | 240 | | | <91 | U | | <91 | U | | <91 | U | | <91 | U | |
| | | VMP-14-20-120110 | 12/2/2010 | <180 | U | | <330 | U | | <100 | U | | <190 | U | | <320 | U | | 310 | | | <300 | U | | <240 | U | | <240 | U | | <240 | U | |
| | | VMP-14-20-021811 | 2/18/2011 | <100 | U | | <190 | U | | <58 | U | | <110 | U | | <180 | U | | 160 | | | <170 | U | | <130 | U | | <130 | U | | <130 | U | |
| | | VMP-14-20-040511 | 4/5/2011 | <44 | U | | <81 | U | | <100 | U | | <46 | U | | <78 | U | | 150 | | | <73 | U | | <57 | U | | <57 | U | | <57 | U | |
| | | VMP-14-20-080811 | 8/8/2011 | <16 | U | | <29 | U | | <36 | U | | <17 | U | | <28 | U | | <12 | U | | <26 | U | | <21 | U | | <21 | U | | <21 | U | |
| | | VMP-14-20-111511 | 11/15/2011 | <82 | U | | <150 | U | | <190 | U | | <87 | U | | <150 | U | | 240 | | | <140 | U | | <110 | U | | <110 | U | | <110 | U | |
| | | VMP-14-20-012612 | 1/26/2012 | <8 | U | | <15 | U | | <18 | U | | <8.5 | U | | <14 | U | | 230 | | J | <13 | U | | <10 | U | | <10 | U | | <10 | U | |
| | | VMP-14-20-042312 | 4/23/2012 | <4.4 | U | | <8.1 | U | | <10 | U | | <4.7 | U | | <7.9 | U | | 240 | | | <7.3 | U | | <5.7 | U | | <5.7 | U | | <5.7 | U | |
| | | VMP-14-20-072512 | 7/25/2012 | <7 | U | | <13 | U | | <16 | U | | <7.4 | U | | <12 | U | | 180 | | | <12 | U | | <9.2 | U | | <9.2 | U | | <9.2 | U | |
| | | VMP-14-20-101612 | 10/16/2012 | <32 | U | | <60 | U | | <74 | U | | <34 | U | | <58 | U | | 150 | | | <54 | U | | <42 | U | | <42 | U | | <42 | U | |
| | | VMP-14-20-013113 | 1/31/2013 | <12 | U | | <21 | U | | <26 | U | | <12 | U | | <52 | U | | 150 | | | <19 | U | | <15 | U | | 2.9 | J | | 3.2 | J | |
| | 29 ft | VMP-14-29-021811 | 2/18/2011 | <150 | U | | <270 | U | | <85 | U | | <160 | U | | <260 | U | | 180 | | | <250 | U | | <190 | U | | <190 | U | | <190 | U | |
| | | VMP-14-29-040511 | 4/5/2011 | <130 | U | | <240 | U | | <290 | U | | <130 | U | | <230 | U | | 250 | | | <210 | U | | <160 | U | | <160 | U | | <160 | U | |
| | | VMP-14-29-012612 | 1/26/2012 | <140 | U | | <270 | U | | <330 | U | | <150 | U | | <260 | U | | 250 | | | <240 | U | | <190 | U | | <190 | U | | <190 | U | |
| | | VMP-14-29-042312 | 4/23/2012 | <52 | U | | <95 | U | | <120 | U | | <55 | U | | <92 | U | | 220 | | | <86 | U | | <67 | U | | <67 | U | | <67 | U | |
| | | VMP-14-29-072512 | 7/25/2012 | <54 | U | | <100 | U | | <120 | U | | <57 | U | | <97 | U | | 210 | | | <90 | U | | <71 | U | | <71 | U | | <71 | U | |
| | | VMP-14-29-101612 | 10/16/2012 | <81 | U | | <150 | U | | <180 | U | | <86 | U | | <140 | U | | 140 | | | <140 | U | | <100 | U | | <100 | U | | <100 | U | |
| | | VMP-14-29-013113-DUP | 1/31/2013 | <110 | U | | <200 | U | | <250 | U | | <120 | U | | <490 | U | | 150 | | J | <180 | U | | <140 | U | | <140 | U | | <140 | U | |
| | | VMP-14-29-013113 | 1/31/2013 | <45 | U | | <84 | U | | <100 | U | | <48 | U | | <200 | U | | 480 | | J | <76 | U | | <59 | U | | <59 | U | | <59 | U | |
| VMP-15 | 5 ft | VMP 15-5-091410 | 9/14/2010 | <0.0058 | U | | <0.011 | U | | <0.0033 | U | | 0.0013 | J | | <0.01 | U | | 0.0048 | | | <0.0097 | U | | <0.0076 | U | | <0.0076 | U | | <0.0076 | U | |
| | | VMP-15-5-113010 | 11/30/2010 | <0.14 | U | | <0.25 | U | | 0.22 | | | <0.15 | U | | <0.25 | UJ | UJ | 8.6 | | | <0.23 | U | | <0.18 | U | | <0.18 | U | | <0.18 | U | |
| | | VMP-15-5-021611 | 2/16/2011 | <0.13 | U | | <0.24 | U | | <0.074 | U | | <0.14 | U | | <0.23 | U | | 0.29 | | | <0.22 | U | | <0.17 | U | | <0.17 | U | | <0.17 | U | |
| | | VMP-15-5-042011 | 4/20/2011 | <0.3 | U | | <0.56 | U | | <0.7 | U | | <0.32 | U | | <0.54 | U | | 3.2 | | | <0.51 | U | | <0.4 | U | | <0.4 | U | | <0.4 | U | |
| | | VMP-15-5-080811 | 8/8/2011 | <0.0068 | J | U | <0.013 | U | | <0.016 | U | | 0.0023 | J | | <0.012 | U | | <0.0051 | U | | <0.011 | J | U | <0.0089 | J | U | <0.0089 | J | U | <0.0089 | J | U |
| | | VMP-15-5-111511 | 11/15/2011 | 0.0083 | | | <0.014 | U | | <0.018 | U | | <0.0081 | U | | <0.014 | U | | 0.031 | | | <0.013 | U | | <0.01 | U | | <0.01 | U | | <0.01 | U | |
| | | VMP-15-5-020112 | 2/1/2012 | <0.039 | U | | <0.073 | U | | <0.09 | U | | <0.042 | U | | <0.071 | U | | <0.029 | U | | <0.066 | U | | <0.051 | U | | <0.051 | U | | <0.051 | U | |
| | | VMP-15-5-042412 | 4/24/2012 | <0.04 | U | | <0.074 | U | | <0.092 | U | | <0.043 | U | | <0.072 | U | | <0.03 | U | | <0.067 | U | | <0.053 | U | | <0.053 | U | | <0.053 | U | |
| | | VMP-15-5-072512 | 7/25/2012 | <0.0045 | | U | <0.0084 | U | | <0.01 | U | | 0.025 | | | 0.017 | J | | 0.00085 | J | | <0.0076 | U | | <0.0059 | U | | <0.0059 | J | U | <0.0059 | J | U |
| | | VMP-15-5-102512 | 10/25/2012 | <0.0068 | J | U | <0.013 | U | | <0.016 | U | | 0.002 | J | | <0.031 | U | | 0.0018 | J | | <0.011 | U | | <0.0089 | U | | <0.0089 | J | U | <0.0089 | J | U |
| | | VMP-15-5-020513 | 2/5/2013 | <0.0066 | U | | <0.012 | U | | <0.015 | U | | <0.007 | U | | <0.03 | U | | <0.005 | U | | <0.011 | U | | <0.0087 | U | | <0.0087 | U | | <0.0087 | U | |
| | 21.5 ft | VMP 15-21.5-091410 | 9/14/2010 | <0.63 | U | | <1.2 | U | | <0.36 | U | | <0.67 | U | | <1.1 | U | | 4 | | | <1 | U | | <0.82 | U | | <0.82 | U | | <0.82 | U | |
| | | VMP-15-21.5-113010 | 11/30/2010 | <0.74 | U | | <1.4 | U | | <0.42 | U | | <0.78 | U | | <1.3 | UJ | UJ | 6 | | | <1.2 | U | | <0.96 | U | | <0.96 | U | | <0.96 | U | |
| | | VMP-15-21.5-021611 | 2/16/2011 | <0.52 | U | | <0.95 | U | | <0.3 | U | | <0.55 | U | | <0.92 | U | | 2.4 | | | <0.86 | U | | <0.67 | U | | <0.67 | U | | <0.67 | U | |
| | | VMP-15-21.5-042011 | 4/20/2011 | <0.81 | U | | <1.5 | U | | <1.8 | U | | <0.86 | U | | <1.4 | U | | 6 | | | <1.4 | U | | <1 | U | | <1 | U | | <1 | U | |
| | | VMP-15-21.5-080811 | 8/8/2011 | <0.65 | U | | <1.2 | U | | <1.5 | U | | <0.69 | U | | <1.2 | U | | <0.48 | U | | <1.1 | U | | <0.85 | U | | <0.85 | U | | <0.85 | U | |
| | | VMP-15-21.5-111511 | 11/15/2011 | <0.52 | U | | <0.96 | U | | <1.2 | U | | <0.55 | U | | <0.93 | U | | 2.3 | | | <0.86 | U | | <0.68 | U | | <0.68 | U | | <0.68 | U | |
| | | VMP-15-21.5-020112 | 2/1/2012 | <0.39 | U | | <0.72 | U | | <0.89 | U | | <0.41 | U | | <0.69 | U | | <0.29 | U | | <0.64 | U | | <0.5 | U | | <0.5 | U | | <0.5 | U | |
| | | VMP-15-21.5-042412 | 4/24/2012 | <0.17 | U | | <0.31 | U | | <0.39 | U | | <0.18 | U | | <0.3 | U | | <0.12 | U | | <0.28 | U | | <0.22 | U | | <0.22 | U | | <0.22 | U | |
| | | VMP-15-21.5-072512 | 7/25/2012 | <0.61 | U | | <1.1 | U | | <1.4 | U | | <0.65 | U | | <1.1 | U | | 0.53 | | | <1 | U | | <0.8 | U | | <0.8 | U | | <0.8 | U | |
| | | VMP-15-21.5-102512 | 10/25/2012 | <1 | U | | <1.8 | U | | <2.3 | U | | <1 | U | | <1.8 | U | | 0.25 | J | | <1.7 | U | | <1.3 | U | | <1.3 | U | | <1.3 | U | |
| | | VMP-15-21.5-102512-Dup | 10/25/2012 | <1 | U | | <1.9 | U | | <2.4 | U | | <1.1 | U | | <1.8 | U | | 0.16 | J | | <1.7 | U | | <1.3 | U | | <1.3 | U | | <1.3 | U | |
| | | VMP-15-21.5-020713 | 2/7/2013 | <0.025 | U | | <0.047 | U | | <0.058 | U | | <0.027 | U | | <0.11 | U | | 0.093 | | | <0.042 | U | | <0.033 | U | | <0.033 | U | | <0.033 | U | |
| | 25.5 ft | VMP 15-25.5-091410 | 9/14/2010 | <0.0059 | U | | <0.011 | U | | <0.0034 | U | | 0.0023 | J | | <0.011 | U | | 0.084 | | | <0.0099 | U | | <0.0078 | U | | <0.0078 | U | | <0.0078 | U | |
| | | VMP-15-25.5-021611 | 2/16/2011 | <0.079 | U | | <0.15 | U | | <0.045 | U | | <0.084 | U | | <0.14 | U | | 0.45 | | | <0.13 | U | | <0.1 | U | | <0.1 | U | | <0.1 | U | |
| | | VMP-15-25.5-042011 | 4/20/2011 | <0.065 | U | | <0.12 | U | | <0.15 | U | | <0.069 | U | | <0.12 | U | | 0.062 | | | <0.11 | U | | <0.085 | U | | <0.085 | U | | <0.085 | U | |
| | | VMP-15-25.5-042011-DUP | 4/20/2011 | <0.061 | U | | <0.11 | U | | <0.14 | U | | <0.064 | U | | <0.11 | U | | 0.1 | | | <0.1 | U | | <0.079 | U | | <0.079 | U | | <0.079 | U | |
| | | VMP-15-25.5-080811 | 8/8/2011 | <0.065 | U | | <0.12 | U | | <0.15 | U | | 0.34 | | | <0.12 | U | | <0.048 | U | | <0.11 | U | | <0.085 | U | | <0.085 | U | | <0.085 | U | |
| | | VMP-15-25.5-111511 | 11/15/2011 | 0.012 | J | | <0.037 | U | | <0.046 | U | | <0.021 | U | | <0.036 | U | | 0.12 | | | <0.033 | U | | <0.026 | U | | <0.026 | U | | <0.026 | U | |
| | | VMP-15-25.5-073112 | 7/31/2012 | <0.042 | U | | <0.078 | U | | <0.096 | U | | <0.045 | U | | <0.076 | U | | 0.04 | | | <0.07 | U | | <0.055 | U | | <0.055 | U | | <0.055 | U | |
| | | VMP-15-25.5-102512 | 10/25/2012 | <0.0068 | U | | <0.013 | U | | <0.016 | U | | <0.0072 | U | | <0.031 | U | | 0.02 | | | <0.011 | U | | <0.0089 | U | | <0.0089 | U | | <0.0089 | U | |
| | | VMP-15-25.5-021213 | 2/12/2013 | <0.21 | U | | <0.38 | U | | <0.47 | U | | <0.22 | U | | <0.37 | U | | <0.15 | U | | <0.34 | U | | <0.27 | U | | <0.27 | U | | <0.27 | U | |
| | 29 ft | VMP-15-29-073112 | 7/31/2012 | <0.18 | U | | <0.33 | U | | <0.41 | U | | <0.19 | U | | <0.32 | U | | 1 | | J | <0.3 | U | | <0.24 | U | | <0.24 | U | | <0.24 | U | |
| | | VMP-15-29-102512 | 10/25/2012 | <0.014 | U | | <0.026 | U | | <0.033 | U | | <0.015 | U | | <0.064 | U | | 0.083 | | | <0.024 | U | | <0.018 | U | | <0.018 | U | | <0.018 | U | |
| | | VMP-15-29-021213 | 2/12/2013 | <0.12 | U | | <0.23 | U | | <0.28 | U | | <0.13 | U | | <0.22 | U | | <0.092 | U | | <0.21 | U | | <0.16 | U | | <0.16 | U | | <0.16 | U | |

**TABLE 6**
**CUMULATIVE SUMMARY OF SOIL VAPOR ANALYTICAL DETECTIONS AND SCREENING RESULTS: PUBLIC WORKS YARD AND WRR - VOCS**

| Location | Depth | Sample ID | Sample Date | Chlorobenzene 420 | | | Chlorodibromomethane 57000 | | | Chloroethane | | | Chloroform 0.92 | | | Chloromethane | | | Cyclohexane | | | 1,2-Dibromoethane 0.06 | | | 1,2-Dichlorobenzene 1700 | | | 1,3-Dichlorobenzene | | | 1,4-Dichlorobenzene 6800 | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals |
| VMP-16 | 5 ft | VMP-16-5-090210 | 9/2/2010 | <11 | U | | <20 | U | | <6.3 | U | | <12 | U | | <20 | U | | 160 | | | <18 | U | | <14 | U | | <14 | U | | <14 | U | |
| | | VMP-16-5-112910 | 11/29/2010 | <5 | U | | <9.3 | U | | 2.4 | J | J | <5.3 | U | | <9 | UJ | UJ | 150 | | J | <8.4 | U | | <6.6 | U | | <6.6 | U | | <6.6 | U | |
| | | VMP-16-5-021511 | 2/15/2011 | <3 | U | | <5.6 | U | | <1.7 | U | | <3.2 | U | | <5.4 | U | | 99 | | J | <5.1 | U | | <4 | U | | <4 | U | | <4 | U | |
| | | VMP-16-5-042211 | 4/22/2011 | <4 | U | | <7.5 | U | | <9.3 | U | | <4.3 | U | | <7.3 | U | | 100 | | | <6.8 | U | | <5.3 | U | | <5.3 | U | | <5.3 | U | |
| | | VMP-16-5-080511 | 8/5/2011 | <1.3 | U | | <2.4 | U | | <3 | U | | <1.4 | U | | <2.3 | U | | 22 | | | <2.2 | U | | <1.7 | U | | <1.7 | U | | <1.7 | U | |
| | | VMP-16-5-042512 | 4/25/2012 | <4.4 | U | | <8.1 | U | | <10 | U | | <4.7 | U | | <7.9 | U | | 67 | | | <7.3 | U | | <5.7 | U | | <5.7 | U | | <5.7 | U | |
| | | VMP-16-5-073012 | 7/30/2012 | <4.1 | U | | <7.6 | U | | <9.4 | U | | <4.4 | U | | <7.4 | U | | 77 | | J | <6.9 | U | | <5.4 | U | | <5.4 | U | | <5.4 | U | |
| | | VMP-16-5-102512 | 10/25/2012 | <3.2 | U | | <6 | U | | <7.4 | U | | <3.4 | U | | <5.8 | U | | 4.9 | | | <5.4 | U | | <4.2 | U | | <4.2 | U | | <4.2 | U | |
| | | VMP-16-5-021413 | 2/14/2013 | <0.51 | U | | <0.94 | U | | <1.2 | U | | <0.54 | U | | <0.91 | U | | 0.24 | J | J | <0.84 | U | | <0.66 | U | | <0.66 | U | | <0.66 | U | |
| | 13.5 ft | VMP-16-13.5-090210 | 9/2/2010 | <11 | U | | <21 | U | | <6.5 | U | | <12 | U | | <20 | U | | 150 | | | <19 | U | | <15 | U | | <15 | U | | <15 | U | |
| | | VMP-16-13.5-090210-DUP | 9/2/2010 | <11 | U | | <21 | U | | <6.5 | U | | <12 | U | | <20 | U | | 140 | | | <19 | U | | <15 | U | | <15 | U | | <15 | U | |
| | | VMP-16-13.5-112910 | 11/29/2010 | <32 | U | | <60 | U | | <18 | U | | <34 | U | | <58 | UJ | UJ | 180 | | | <54 | U | | <42 | U | | <42 | U | | <42 | U | |
| | | VMP-16-13.5-021611 | 2/16/2011 | <6.2 | U | | <11 | U | | <3.5 | U | | <6.6 | U | | <11 | U | | 78 | | | <10 | U | | <8.1 | U | | <8.1 | U | | <8.1 | U | |
| | | VMP-16-13.5-021611-DUP | 2/16/2011 | <6.1 | U | | <11 | U | | <3.5 | U | | <6.4 | U | | <11 | U | | 84 | | | <10 | U | | <7.9 | U | | <7.9 | U | | <7.9 | U | |
| | | VMP-16-13.5-042211 | 4/22/2011 | <6.5 | U | | <12 | U | | <15 | U | | <6.9 | U | | <12 | U | | 120 | | | <11 | U | | <8.5 | U | | <8.5 | U | | <8.5 | U | |
| | | VMP-16-13.5-080511 | 8/5/2011 | <0.64 | U | UJ | <1.2 | U | UJ | <1.4 | U | UJ | <0.67 | U | UJ | <1.1 | U | UJ | 6.4 | | J | <1.1 | U | UJ | <0.83 | U | UJ | <0.83 | U | UJ | <0.83 | U | UJ |
| | | VMP-16-13.5-042512 | 4/25/2012 | <0.7 | U | | <1.3 | U | | <1.6 | U | | <0.74 | U | | <1.2 | U | | 150 | | J | <1.2 | U | | <0.92 | U | | <0.92 | U | | <0.92 | U | |
| | | VMP-16-13.5-073012 | 7/30/2012 | <21 | U | | <39 | U | | <48 | U | | <22 | U | | <38 | U | | 170 | | | <35 | U | | <28 | U | | <28 | U | | <28 | U | |
| | | VMP-16-13.5-102512 | 10/25/2012 | <65 | U | | <120 | U | | <150 | U | | <69 | U | | <120 | U | | 140 | | | <110 | U | | <85 | U | | <85 | U | | <85 | U | |
| | | VMP-16-13.5-021413 | 2/14/2013 | <10 | U | | <19 | U | | <24 | U | | <11 | U | | <18 | U | | 130 | | J | <17 | U | | <13 | U | | <13 | U | | <13 | U | |
| | 19 ft | VMP-16-19-090210 | 9/2/2010 | <11 | U | | <21 | U | | <6.5 | U | | <12 | U | | <20 | U | | 190 | | | <19 | U | | <15 | U | | <15 | U | | <15 | U | |
| | | VMP-16-19-112910 | 11/29/2010 | <25 | U | | <46 | U | | <14 | U | | <26 | U | | <45 | UJ | UJ | 170 | | | <41 | U | | <32 | U | | <32 | U | | <32 | U | |
| | | VMP-16-19-021611 | 2/16/2011 | <5.9 | U | | <11 | U | | <3.4 | U | | <6.3 | U | | <11 | U | | 80 | | | <9.9 | U | | <7.8 | U | | <7.8 | U | | <7.8 | U | |
| | | VMP-16-19-042711 | 4/27/2011 | <6.1 | U | | <11 | U | | <14 | U | | <6.4 | U | | <11 | U | | 64 | | | <10 | U | | <7.9 | U | | <7.9 | U | | <7.9 | U | |
| | | VMP-16-19-042711-DUP | 4/27/2011 | <5.9 | U | | <11 | U | | <14 | U | | <6.3 | U | | <11 | U | | 64 | | | <9.9 | U | | <7.8 | U | | <7.8 | U | | <7.8 | U | |
| | | VMP-16-19-042512 | p | <16 | U | | <30 | U | | <37 | U | | <17 | U | | <29 | U | | 160 | | | <27 | U | | <21 | U | | <21 | U | | <21 | U | |
| | | VMP-16-19-073012 | 7/30/2012 | <14 | U | | <27 | U | | <33 | U | | <15 | U | | <26 | U | | 150 | | | <24 | U | | <19 | U | | <19 | U | | <19 | U | |
| | | VMP-16-19-102512 | 10/25/2012 | <61 | U | | <110 | U | | <140 | U | | <64 | U | | <110 | U | | 170 | | | <100 | U | | <79 | U | | <79 | U | | <79 | U | |
| | | VMP-16-19-021413 | 2/14/2013 | <6.1 | U | | <11 | U | | <14 | U | | <6.4 | U | | <11 | U | | 210 | | J | <10 | U | | <7.9 | U | | <7.9 | U | | <7.9 | U | |
| | 31 ft | VMP-16-31-090310 | 9/3/2010 | <0.0066 | U | | <0.012 | U | | <0.0038 | U | | <0.007 | U | | <0.012 | U | | 0.049 | | | <0.011 | U | | <0.0087 | U | | <0.0087 | U | | <0.0087 | U | |
| | | VMP-16-31-112910 | 11/29/2010 | <25 | U | | <46 | U | | <14 | U | | <27 | U | | <45 | UJ | UJ | 170 | | | <42 | U | | <33 | U | | <33 | U | | <33 | U | |
| | | VMP-16-31-042512 | 4/25/2012 | <20 | U | | <36 | U | | <45 | U | | <21 | U | | <35 | U | | 210 | | | <33 | U | | <26 | U | | <26 | U | | <26 | U | |
| | | VMP-16-31-073012 | 7/30/2012 | <16 | U | | <30 | U | | <37 | U | | <17 | U | | <29 | U | | 200 | | | <27 | U | | <21 | U | | <21 | U | | <21 | U | |
| | | VMP-16-31-102512 | 10/25/2012 | <76 | U | | <140 | U | | <170 | U | | <80 | U | | <140 | U | | 170 | | | <130 | U | | <99 | U | | <99 | U | | <99 | U | |
| | | VMP-16-31-021813 | 2/18/2013 | <23 | U | | <42 | U | | <53 | U | | <24 | U | | <41 | U | | 260 | | | <38 | U | | <30 | U | | <30 | U | | <30 | U | |
| VMP-17 | 5 ft | VMP-17-5 | 6/21/2010 | <0.006 | U | | <0.012 | U | | <0.003 | U | | <0.007 | U | | <0.012 | U | | 0.36 | | | <0.011 | U | | <0.008 | U | | <0.008 | U | | <0.008 | U | |
| | | VMP-17-5-DUP | 6/21/2010 | <0.006 | U | | <0.013 | U | | <0.004 | U | | <0.007 | U | | <0.012 | U | | 0.32 | | | <0.012 | U | | <0.009 | U | | <0.009 | U | | <0.009 | U | |
| | | VMP-17-5-090110 | 9/1/2010 | <0.0062 | J | U | <0.011 | U | | <0.0035 | U | | <0.0066 | U | | 0.0045 | J | | 0.02 | | | <0.01 | U | | 0.002 | J | | <0.0081 | U | | <0.0081 | U | |
| | | VMP-17-5-112210 | 11/22/2010 | <0.0062 | U | | <0.011 | U | | <0.0035 | U | | <0.0066 | U | | 0.0035 | J | | <0.0046 | U | | <0.01 | U | | <0.0081 | U | | <0.0081 | U | | <0.0081 | U | |
| | | VMP-17-5-020711 | 2/7/2011 | <0.0058 | U | | <0.011 | U | | <0.0033 | U | | <0.0062 | U | | <0.01 | U | | 0.029 | | | <0.0097 | U | | <0.0076 | J | U | <0.0076 | J | U | <0.0076 | J | U |
| | | VMP-17-5-040611 | 4/6/2011 | <0.023 | U | | <0.043 | U | | <0.053 | U | | <0.025 | U | | <0.042 | U | | 0.034 | | | <0.039 | U | | <0.03 | U | | <0.03 | U | | <0.03 | U | |
| | | VMP-17-5-080111 | 8/1/2011 | <0.089 | U | | <0.16 | U | | <0.2 | U | | <0.094 | U | | <0.16 | U | | 0.054 | J | | <0.15 | U | | <0.12 | U | | <0.12 | U | | <0.12 | U | |
| | | VMP-17-5-110711 | 11/7/2011 | <0.0039 | U | | <0.0073 | U | | <0.009 | U | | <0.0042 | U | | <0.0071 | U | | <0.0029 | U | | <0.0066 | U | | <0.0051 | U | | <0.0051 | J | U | <0.0051 | J | U |
| | | VMP-17-5-012612 | 1/26/2012 | <0.0041 | U | | <0.0076 | U | | <0.0094 | U | | <0.0044 | U | | <0.0074 | U | | <0.0031 | U | | <0.0069 | U | | <0.0054 | U | | <0.0054 | U | | <0.0054 | U | |
| | | VMP-17-5-041112 | 4/11/2012 | <0.0042 | U | | <0.0078 | U | | <0.0096 | U | | <0.0045 | U | | <0.019 | U | | 0.0019 | J | | <0.007 | U | | <0.0055 | U | | <0.0055 | U | | <0.0055 | J | U |
| | | VMP-17-5-071112 | 7/11/2012 | <0.0045 | U | | <0.0083 | U | | <0.01 | U | | <0.0048 | U | | <0.02 | U | | 0.004 | | | <0.0075 | U | | <0.0059 | U | | <0.0059 | U | | <0.0059 | U | |
| | | VMP-17-5-100912 | 10/9/2012 | <0.007 | U | | <0.013 | U | | <0.016 | U | | <0.0074 | U | | <0.031 | U | | <0.0052 | U | | <0.012 | U | | <0.0091 | U | | <0.0091 | U | | <0.0091 | J | U |
| | | VMP-17-5-013113 | 1/31/2013 | <0.024 | U | | <0.045 | U | | <0.056 | U | | <0.026 | U | | <0.11 | U | | 0.0097 | J | | <0.041 | U | | <0.032 | U | | <0.032 | U | | <0.032 | U | |
| | | VMP-17-5-013113-DUP | 1/31/2013 | <0.024 | U | | <0.045 | U | | <0.056 | U | | <0.026 | U | | <0.11 | U | | 0.015 | J | | <0.041 | U | | <0.032 | U | | <0.032 | U | | <0.032 | U | |
| VMP-25 | 5 ft | VMP-25-5-031511 | 3/15/2011 | 1 | | | <0.1 | U | | <0.13 | U | | 0.048 | J | | <0.1 | U | | 6 | | | <0.093 | U | | <0.073 | U | | <0.073 | U | | <0.073 | U | |
| | | VMP-25-5-040811 | 4/8/2011 | 0.0043 | J | | <0.047 | U | | <0.058 | U | | <0.027 | U | | <0.045 | U | | 0.12 | | | <0.042 | U | | <0.033 | J | U | <0.033 | U | | <0.033 | U | |
| | | VMP-25-5-080911 | 8/9/2011 | <0.0054 | J | U | <0.0099 | U | | <0.012 | U | | 0.0021 | J | | <0.0096 | U | | 0.039 | | | <0.009 | J | U | <0.007 | J | U | <0.007 | J | U | <0.007 | J | U |
| | | VMP-25-5-111711 | 11/17/2011 | <0.0039 | U | | <0.0072 | U | | <0.0089 | U | | 0.0017 | J | | <0.0069 | U | | <0.0029 | U | | <0.0064 | U | | <0.005 | U | | <0.005 | U | | <0.005 | U | |
| | | VMP-25-5-013112 | 1/31/2012 | 0.0072 | J | | <0.052 | U | | <0.064 | U | | <0.03 | U | | <0.05 | U | | 0.25 | | | <0.047 | U | | <0.037 | U | | <0.037 | U | | <0.037 | U | |
| | | VMP-25-5-042512 | 4/25/2012 | <0.0044 | J | U | <0.0081 | U | | <0.01 | U | | 0.0036 | J | | <0.02 | U | | 0.00068 | J | | <0.0073 | U | | <0.0057 | U | | <0.0057 | U | | <0.0057 | J | U |
| | | VMP-25-5-072612 | 7/26/2012 | 0.0087 | J | | <0.028 | U | | <0.035 | U | | 0.02 | | | <0.068 | U | | 0.48 | | | <0.025 | U | | <0.02 | U | | <0.02 | U | | <0.02 | J | U |
| | | VMP-25-5-102612 | 10/26/2012 | <0.0062 | U | | <0.011 | U | | <0.014 | U | | 0.004 | J | | <0.028 | U | | <0.0046 | U | | <0.01 | U | | <0.0081 | U | | <0.0081 | U | | <0.0081 | U | |
| | | VMP-25-5-030613 | 3/6/2013 | <0.0059 | J | U | <0.011 | U | | <0.014 | U | | <0.0063 | U | | <0.026 | U | | 0.0042 | J | J | <0.0099 | U | | <0.0077 | J | U | <0.0077 | J | U | <0.0077 | J | U |
| | 21 ft | VMP-25-21-031511 | 3/15/2011 | 29 | | J | <20 | U | | 3.7 | J | | <12 | U | | <20 | U | | 1400 | | J | <18 | U | | <14 | U | | <14 | U | | <14 | U | |
| | | VMP-25-21-031511-DUP | 3/15/2011 | 44 | | J | <26 | U | | <32 | U | | <15 | U | | <25 | U | | 2200 | | J | <23 | U | | <18 | U | | <18 | U | | <18 | U | |
| | | VMP-25-21-040811 | 4/8/2011 | <120 | U | | <210 | U | | <260 | U | | <120 | U | | <210 | U | | 1800 | | | <190 | U | | 22 | J | | <150 | U | | <150 | U | |
| | | VMP-25-21-040811-DUP | 4/8/2011 | <120 | U | | <220 | U | | <270 | U | | <120 | U | | <210 | U | | 1700 | | | <200 | U | | <150 | U | | <150 | U | | <150 | U | |
| | | VMP-25-21-080911 | 8/9/2011 | <38 | U | | <70 | U | | <87 | U | | <40 | U | | <68 | U | | <28 | U | | <63 | U | | <50 | U | | <50 | U | | <50 | U | |
| | | VMP-25-21-111711 | 11/17/2011 | <52 | U | | <96 | U | | <120 | U | | 9.8 | J | | <93 | U | | 860 | | | <86 | U | | <68 | U | | <68 | U | | <68 | U | |
| | | VMP-25-21-111711-DUP | 11/17/2011 | <76 | U | | <140 | U | | <180 | U | | <81 | U | | <140 | U | | 800 | | | <130 | U | | <100 | U | | <100 | U | | <100 | U | |
| | | VMP-25-21-013112 | 1/31/2012 | <27 | U | | <50 | U | | <62 | U | | <28 | U | | <48 | U | | 1400 | | | <45 | U | | <35 | U | | <35 | U | | <35 | U | |
| | | VMP-25-21-013112-DUP | 2/1/2012 | <25 | U | | <46 | U | | <58 | U | | <27 | U | | <45 | U | | 1600 | | | <42 | U | | <33 | U | | <33 | U | | <33 | U | |
| | | VMP-25-21-042512 | 4/25/2012 | <17 | U | | <32 | U | | <39 | U | | <18 | U | | 62 | | | 1400 | | | <29 | U | | <22 | U | | <22 | U | | <22 | U | |
| | | VMP-25-21-072612 | 7/26/2012 | <29 | U | | <54 | U | | <66 | U | | <31 | U | | <52 | U | | 1400 | | | <48 | U | | <38 | U | | <38 | U | | <38 | U | |
| | | VMP-25-21-102612 | 10/26/2012 | <170 | U | | <320 | U | | <400 | U | | <180 | U | | <310 | U | | 1400 | | | <290 | U | | <230 | U | | <230 | U | | <230 | U | |
| | | VMP-25-21-030613 | 3/6/2013 | <44 | U | | <82 | U | | <100 | U | | <47 | U | | <200 | U | | 2300 | J | J | <74 | U | | <58 | U | | <58 | U | | <58 | U | |
| | 31 ft | VMP-25-31-030613 | 3/6/2013 | <58 | U | | <110 | U | | 11 | J | | 7.3 | J | | <100 | U | | 580 | | | <98 | U | | <76 | U | | <76 | U | | <76 | U | |

SEE LAST PAGE OF TABLE FOR NOTES

**TABLE 6**
**CUMULATIVE SUMMARY OF SOIL VAPOR ANALYTICAL DETECTIONS AND SCREENING RESULTS: PUBLIC WORKS YARD AND WRR - VOCS**

| Location | Depth | Sample ID | Sample Date | Chlorobenzene | | | Chlorodibromomethane | | | Chloroethane | | | Chloroform | | | Chloromethane | | | Cyclohexane | | | 1,2-Dibromoethane | | | 1,2-Dichlorobenzene | | | 1,3-Dichlorobenzene | | | 1,4-Dichlorobenzene | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | 420 | | | 57000 | | | | | | 0.92 | | | | | | | | | 0.06 | | | 1700 | | | | | | 6800 | | |
| | | | | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals |
| VMP-29 | 10 ft | VMP-29-10-073012 | 7/30/2012 | <0.049 | U | | <0.09 | U | | <0.11 | U | | <0.052 | U | | <0.22 | U | | <0.036 | U | | <0.081 | U | | <0.064 | U | | <0.064 | U | | <0.064 | U | |
| | | VMP-29-10-100812 | 10/8/2012 | <0.086 | U | | <0.16 | U | | <0.2 | U | | <0.092 | U | | <0.39 | U | | <0.065 | U | | <0.14 | U | | <0.11 | U | | <0.11 | U | | <0.11 | U | |
| | | VMP-29-10-020613 | 2/6/2013 | <0.0065 | U | | <0.012 | U | | <0.015 | U | | <0.0069 | U | | <0.029 | U | | <0.0048 | U | | <0.011 | U | | <0.0085 | U | | <0.0085 | U | | <0.0085 | U | |
| | 20 ft | VMP-29-20-073012 | 7/30/2012 | <0.58 | U | | <1.1 | U | | <1.3 | U | | <0.61 | U | | <1 | U | | <0.43 | U | | <0.96 | U | | <0.75 | U | | <0.75 | U | | <0.75 | U | |
| | | VMP-29-20-073012-Dup | 7/30/2012 | <0.54 | U | | <1 | U | | <1.2 | U | | <0.57 | U | | <0.97 | U | | <0.4 | U | | <0.9 | U | | <0.7 | U | | <0.7 | U | | <0.7 | U | |
| | | VMP-29-20-100812 | 10/8/2012 | <0.086 | U | | <0.16 | U | | <0.2 | U | | <0.092 | U | | <0.39 | U | | <0.065 | U | | <0.14 | U | | <0.11 | U | | <0.11 | U | | <0.11 | U | |
| | | VMP-29-20-020613 | 2/6/2013 | <0.0064 | U | | <0.012 | U | | <0.014 | U | | <0.0067 | U | | <0.028 | U | | <0.0048 | U | | <0.011 | U | | <0.0083 | U | | <0.0083 | U | | <0.0083 | U | |
| | 30 ft | VMP-29-30-073012 | 7/30/2012 | <0.095 | U | | <0.18 | U | | <0.22 | U | | 0.02 | J | | <0.17 | U | | <0.071 | U | | <0.16 | U | | <0.12 | U | | <0.12 | U | | <0.12 | U | |
| | | VMP-29-30-100812 | 10/8/2012 | <0.42 | U | | <0.79 | U | | <0.98 | U | | <0.45 | U | | <1.9 | U | | <0.32 | U | | <0.71 | U | | <0.56 | U | | 0.059 | J | | <0.56 | U | |
| | | VMP-29-30-020613 | 2/6/2013 | <0.0066 | U | | <0.012 | U | | <0.015 | U | | 0.0056 | J | | <0.03 | U | | <0.005 | U | | <0.011 | U | | <0.0087 | U | | <0.0087 | U | | <0.0087 | U | |
| VMP-30 | 10 ft | VMP-30-10-073012 | 7/30/2012 | <0.17 | U | | <0.32 | U | | <0.39 | U | | <0.18 | U | | <0.31 | U | | <0.13 | U | | <0.29 | U | | <0.22 | U | | <0.22 | U | | <0.22 | U | |
| | | VMP-30-10-100812 | 10/8/2012 | <0.0065 | U | | <0.012 | U | | <0.015 | U | | <0.0069 | U | | <0.029 | U | | 0.0013 | J | | <0.011 | U | | <0.0085 | U | | <0.0085 | U | | <0.0085 | U | |
| | | VMP-30-10-020613 | 2/6/2013 | <0.0061 | U | | <0.011 | U | | <0.014 | U | | <0.0064 | U | | <0.027 | U | | <0.0045 | U | | <0.01 | U | | <0.0079 | U | | <0.0079 | U | | <0.0079 | U | |
| | 20 ft | VMP-30-20-073012 | 7/30/2012 | <0.73 | U | | <1.4 | U | | <1.7 | U | | <0.78 | U | | <1.3 | U | | <0.55 | U | | <1.2 | U | | <0.96 | U | | <0.96 | U | | <0.96 | U | |
| | | VMP-30-20-100812 | 10/8/2012 | <0.27 | U | | <0.49 | U | | <0.61 | U | | <0.28 | U | | <1.2 | U | | <0.2 | U | | <0.44 | U | | <0.35 | U | | <0.35 | U | | 0.034 | J | |
| | | VMP-30-20-020613 | 2/6/2013 | <0.0061 | U | | <0.011 | U | | <0.014 | U | | 0.012 | | | <0.027 | U | | <0.0045 | U | | <0.01 | U | | <0.0079 | J | U | <0.0079 | J | U | <0.0079 | J | U |
| | 30 ft | VMP-30-30-073012 | 7/30/2012 | <0.75 | U | | <1.4 | U | | <1.7 | U | | <0.8 | U | | <1.4 | U | | <0.56 | U | | <1.2 | U | | <0.98 | U | | <0.98 | U | | <0.98 | U | |
| | | VMP-30-30-100812 | 10/8/2012 | <0.55 | U | | <1 | U | | <1.3 | U | | <0.59 | U | | <2.5 | U | | <0.41 | U | | <0.92 | U | | <0.72 | U | | <0.72 | U | | <0.72 | U | |
| | | VMP-30-30-020613 | 2/6/2013 | <0.02 | U | | <0.037 | U | | <0.046 | U | | 0.01 | J | | <0.091 | U | | <0.015 | U | | <0.034 | U | | <0.026 | U | | <0.026 | U | | <0.026 | U | |
| VMP-41 | 10 ft | VMP-41-10-072712 | 7/27/2012 | <0.0056 | U | | <0.01 | U | | <0.013 | U | | <0.0059 | U | | <0.025 | U | | 0.0065 | | | <0.0093 | U | | <0.0073 | U | | <0.0073 | U | | <0.0073 | U | |
| | | VMP-41-10-100912 | 10/9/2012 | <0.0068 | U | | <0.013 | U | | <0.016 | U | | <0.0072 | U | | <0.03 | U | | <0.0051 | U | | <0.011 | U | | <0.0089 | U | | <0.0089 | U | | <0.0089 | U | |
| | | VMP-41-10-012913 | 1/29/2013 | <0.0068 | U | | <0.013 | U | | <0.016 | U | | <0.0072 | U | | <0.03 | U | | <0.0051 | U | | <0.011 | U | | <0.0089 | U | | <0.0089 | U | | <0.0089 | U | |
| | 20 ft | VMP-41-20-072712 | 7/27/2012 | <0.0043 | U | | <0.008 | U | | <0.0099 | U | | <0.0046 | U | | <0.019 | U | | 0.00088 | J | | <0.0072 | U | | <0.0056 | U | | <0.0056 | U | | <0.0056 | U | |
| | | VMP-41-20-072712-Dup | 7/27/2012 | <0.0044 | U | | <0.0081 | U | | <0.01 | U | | <0.0047 | U | | <0.02 | U | | 0.00069 | J | | <0.0073 | U | | <0.0057 | U | | <0.0057 | U | | <0.0057 | U | |
| | | VMP-41-20-100912 | 10/9/2012 | <0.0066 | U | | <0.012 | U | | <0.015 | U | | <0.007 | U | | 0.0079 | J | | <0.005 | U | | <0.011 | U | | <0.0087 | U | | <0.0087 | U | | <0.0087 | U | |
| | | VMP-41-20-100912-Dup | 10/9/2012 | <0.0068 | U | | <0.013 | U | | <0.016 | U | | <0.0072 | U | | <0.03 | U | | <0.0051 | U | | <0.011 | U | | <0.0089 | U | | <0.0089 | J | U | <0.0089 | J | U |
| | | VMP-41-20-012913 | 1/29/2013 | <0.007 | U | | <0.013 | U | | <0.016 | U | | <0.0074 | U | | <0.031 | U | | <0.0052 | U | | <0.012 | U | | <0.0091 | U | | <0.0091 | U | | <0.0091 | U | |
| | 30 ft | VMP-41-30-072712 | 7/27/2012 | <0.0044 | U | | <0.0081 | U | | <0.01 | U | | 0.0013 | J | | <0.02 | U | | 0.0051 | | | <0.0073 | U | | <0.0057 | U | | <0.0057 | U | | <0.0057 | U | |
| | | VMP-41-30-100912 | 10/9/2012 | <0.0072 | U | | <0.013 | U | | <0.016 | U | | <0.0076 | U | | <0.032 | U | | <0.0054 | U | | <0.012 | U | | <0.0093 | U | | <0.0093 | U | | <0.0093 | J | U |
| | | VMP-41-30-012913 | 1/29/2013 | <0.0065 | U | | <0.012 | U | | <0.015 | U | | 0.0023 | J | | <0.029 | U | | <0.0048 | U | | <0.011 | U | | <0.0085 | U | | <0.0085 | U | | <0.0085 | U | |
| VMP-55 | 20 ft | VMP-55-20-021513 | 2/15/2013 | <16 | U | | <29 | U | | <36 | U | | <17 | U | | <28 | U | | 230 | | | <26 | U | | <21 | U | | <21 | U | | <21 | U | |

SEE LAST PAGE OF TABLE FOR NOTES

**TABLE 6**
**CUMULATIVE SUMMARY OF SOIL VAPOR ANALYTICAL DETECTIONS AND SCREENING RESULTS: PUBLIC WORKS YARD AND WRR - VOCS**

| Location | Depth | Sample ID | Sample Date | Dichlorodifluoromethane | | | 1,1-Dichloroethane | | | 1,2-Dichloroethane | | | 1,1-Dichloroethene | | | cis-1,2-Dichloroethene | | | trans-1,2-Dichloroethene | | | Dichloromethane (Methylene | | | 1,2-Dichloropropane | | | cis-1,3-Dichloropropene | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | | | | 4200 | | | 0.81 | | | 1600 | | | 1100000 | | | 510 | | | 45 | | | 0.46 | | | 6.2 | | |
| | | | | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals |
| VMP-10 | 5 ft | VMP-10-5-090710 | 9/7/2010 | 0.0024 | J | | <0.0053 | U | | <0.0053 | U | | <0.0052 | U | | <0.0052 | U | | <0.0052 | U | | <0.0046 | U | | <0.0061 | U | | <0.006 | U | |
| | | VMP-10-5-111810 | 11/17/2010 | 0.0017 | J | | <0.0049 | U | | <0.0049 | U | | <0.0048 | U | | <0.0048 | U | | <0.0048 | U | | <0.0042 | U | | <0.0056 | U | | <0.0055 | U | |
| | | VMP-10-5-021011 | 2/10/2011 | 0.0024 | J | | <0.0048 | U | | <0.0048 | U | | <0.0047 | U | | <0.0047 | U | | <0.0047 | U | | <0.0041 | U | | <0.0055 | U | | <0.0054 | U | |
| | | VMP-10-5-040511 | 4/5/2011 | 0.0021 | J | | <0.0044 | U | | <0.0044 | U | | <0.0044 | U | | <0.0044 | U | | <0.0044 | U | | <0.0038 | J | U | <0.0051 | U | | <0.005 | U | |
| | | VMP-10-5-07/2911 | 7/29/2011 | 0.002 | J | | <0.0054 | U | | <0.0054 | U | | <0.0053 | U | | <0.0053 | U | | <0.0053 | U | | 0.00098 | J | | <0.0062 | U | | <0.0061 | U | |
| | | VMP-10-5-110411 | 11/4/2011 | 0.0018 | J | | <0.0028 | U | | <0.0028 | U | | <0.0028 | U | | <0.0028 | U | | <0.0028 | U | | 0.0014 | J | | <0.0032 | U | | <0.0032 | U | |
| | | VMP-10-5-012512 | 1/26/2012 | 0.0025 | J | | <0.0035 | U | | <0.0035 | U | | <0.0035 | U | | <0.0035 | U | | <0.0035 | U | | 0.0014 | J | | <0.004 | U | | <0.004 | U | |
| | | VMP-10-5-041212 | 4/12/2012 | 0.0023 | J | | <0.0038 | U | | <0.0038 | U | | <0.0037 | U | | <0.0037 | U | | <0.0037 | U | | <0.033 | J | U | <0.0043 | U | | <0.0043 | U | |
| | | VMP-10-5-071312 | 7/13/2012 | 0.0028 | J | | <0.0039 | U | | <0.0039 | U | | <0.0038 | U | | <0.0038 | U | | <0.0038 | U | | <0.034 | J | U | <0.0044 | U | | <0.0044 | U | |
| | | VMP-10-5-101612 | 10/16/2012 | 0.002 | J | | <0.0061 | U | | <0.0061 | U | | <0.006 | U | | <0.006 | U | | <0.006 | U | | <0.053 | U | | <0.007 | U | | <0.0069 | U | |
| | | VMP-10-5-012913 | 1/29/2013 | 0.0028 | J | | <0.0057 | U | | <0.0057 | U | | <0.0056 | U | | <0.0056 | U | | <0.0056 | U | | <0.049 | U | | <0.0065 | U | | <0.0064 | U | |
| | | VMP-10-5-012913-DUP | 1/29/2013 | 0.0029 | J | | <0.0063 | U | | <0.0063 | U | | <0.0062 | U | | <0.0062 | U | | <0.0062 | U | | <0.054 | J | U | <0.0072 | U | | <0.007 | U | |
| | 10 ft | VMP-10-10-090710 | 9/7/2010 | 0.0025 | J | | <0.0053 | U | | <0.0053 | U | | <0.0052 | U | | <0.0052 | U | | <0.0052 | U | | <0.0046 | U | | <0.0061 | U | | <0.006 | U | |
| | | VMP-10-10-111810 | 11/17/2010 | 0.0022 | J | | <0.0052 | U | | <0.0052 | U | | <0.0051 | U | | <0.0051 | U | | <0.0051 | U | | 0.001 | J | | <0.006 | U | | <0.0058 | U | |
| | | VMP-10-10-021111 | 2/11/2011 | 0.0015 | J | | <0.0041 | U | | <0.0041 | U | | <0.004 | U | | <0.004 | U | | <0.004 | U | | <0.0035 | U | | <0.0047 | U | | <0.0046 | U | |
| | | VMP-10-10-040611 | 4/6/2011 | 0.0023 | J | | <0.0053 | U | | <0.0053 | U | | <0.0052 | U | | <0.0052 | J | U | <0.0052 | U | | 0.016 | | | <0.0061 | U | | <0.006 | J | U |
| | | VMP-10-10-072911 | 7/29/2011 | 0.0021 | J | | <0.0056 | U | | <0.0056 | U | | <0.0055 | U | | <0.0055 | U | | <0.0055 | U | | <0.0048 | J | U | <0.0064 | U | | <0.0063 | U | |
| | | VMP-10-10-110411 | 11/4/2011 | 0.0026 | J | | <0.0036 | U | | <0.0036 | U | | <0.0035 | U | | 0.0031 | J | | <0.0035 | U | | 0.002 | J | | <0.0041 | U | | <0.0041 | U | |
| | | VMP-10-10-110411-DUP | 11/4/2011 | 0.0026 | J | | <0.0036 | U | | <0.0036 | U | | <0.0035 | U | | 0.0018 | J | | <0.0035 | U | | 0.002 | J | | 0.00064 | J | | <0.0041 | U | |
| | | VMP-10-10-012512 | 1/26/2012 | 0.0032 | J | | <0.0035 | U | | <0.0035 | U | | <0.0035 | U | | <0.0035 | U | | <0.0035 | U | | 0.0035 | | | <0.004 | U | | <0.004 | U | |
| | | VMP-10-10-012512-DUP | 1/26/2012 | 0.0026 | J | | <0.0037 | U | | <0.0037 | U | | <0.0036 | U | | <0.0036 | U | | <0.0036 | U | | 0.0025 | J | | <0.0042 | U | | <0.0042 | U | |
| | | VMP-10-10-041112 | 4/11/2012 | 0.002 | J | | <0.0039 | U | | <0.0039 | U | | <0.0038 | U | | <0.0038 | U | | <0.0038 | U | | 0.0028 | J | | 0.00091 | J | | <0.0043 | U | |
| | | VMP-10-10-071312 | 7/13/2012 | 0.0023 | J | | <0.0038 | U | | <0.0038 | U | | <0.0037 | U | | <0.0037 | U | | <0.0037 | U | | <0.033 | J | U | <0.0043 | U | | <0.0043 | U | |
| | | VMP-10-10-101612 | 10/16/2012 | 0.0019 | J | | <0.0064 | U | | <0.0064 | U | | <0.0063 | U | | <0.0063 | U | | <0.0063 | U | | <0.055 | U | | <0.0073 | U | | <0.0072 | U | |
| | | VMP-10-10-012913 | 1/29/2013 | 0.0024 | J | | <0.0051 | U | | <0.0051 | U | | <0.005 | U | | <0.005 | U | | <0.005 | U | | 0.002 | J | | <0.0058 | U | | <0.0057 | U | |
| | 20 ft | VMP-10-20-090710 | 9/7/2010 | 0.0027 | J | | <0.0056 | U | | <0.0056 | U | | <0.0055 | U | | <0.0055 | U | | <0.0055 | U | | <0.0048 | J | U | <0.0064 | U | | <0.0063 | U | |
| | | VMP-10-20-090710-DUP | 9/7/2010 | 0.0033 | J | | <0.0052 | U | | <0.0052 | U | | <0.0051 | U | | <0.0051 | U | | <0.0051 | U | | <0.026 | | U | <0.006 | U | | <0.0058 | U | |
| | | VMP-10-20-111810 | 11/17/2010 | 0.0028 | J | | <0.0099 | U | | <0.0099 | U | | <0.0097 | U | | <0.0097 | U | | <0.0097 | U | | <0.0085 | U | | <0.011 | U | | <0.011 | U | |
| | | VMP-10-20-111810-Dup | 11/17/2010 | 0.0019 | J | | <0.005 | U | | <0.005 | U | | <0.0049 | U | | <0.0049 | U | | <0.0049 | U | | 0.0026 | J | | <0.0057 | U | | <0.0056 | U | |
| | | VMP-10-20-021111 | 2/11/2011 | 0.002 | J | | <0.0049 | U | | <0.0049 | U | | <0.0048 | U | | <0.0048 | U | | <0.0048 | U | | <0.0042 | U | | <0.0056 | U | | <0.0055 | U | |
| | | VMP-10-20-040611 | 4/6/2011 | 0.0021 | J | | <0.006 | U | | <0.0059 | U | | <0.0058 | U | | <0.0058 | U | | <0.0058 | U | | 0.0068 | | | <0.0068 | U | | <0.0067 | U | |
| | | VMP-10-20-072911 | 7/29/2011 | 0.0023 | J | | <0.0055 | U | | <0.0055 | U | | <0.0054 | U | | <0.0054 | U | | <0.0054 | U | | <0.0047 | U | | <0.0063 | U | | <0.0062 | U | |
| | | VMP-10-20-110411 | 11/4/2011 | 0.0027 | J | | <0.0036 | U | | <0.0036 | U | | <0.0035 | U | | 0.0011 | J | | <0.0035 | U | | 0.0017 | J | | <0.0041 | U | | <0.0041 | U | |
| | | VMP-10-20-012612 | 1/26/2012 | 0.0024 | J | | <0.0034 | U | | <0.0034 | U | | <0.0033 | U | | <0.0033 | U | | <0.0033 | U | | 0.00031 | J | | <0.0039 | U | | <0.0038 | U | |
| | | VMP-10-20-041212 | 4/12/2012 | 0.0023 | J | | <0.0038 | U | | <0.0038 | U | | <0.0037 | U | | <0.0037 | U | | <0.0037 | U | | <0.033 | J | U | <0.0043 | U | | <0.0043 | U | |
| | | VMP-10-20-071612 | 7/16/2012 | 0.0028 | J | | <0.0036 | U | | <0.0036 | U | | <0.0035 | U | | <0.0035 | U | | <0.0035 | U | | <0.031 | J | U | <0.0041 | U | | <0.0041 | U | |
| | | VMP-10-20-101612 | 10/16/2012 | 0.0022 | J | | <0.0064 | U | | <0.0064 | U | | <0.0063 | U | | <0.0063 | U | | <0.0063 | U | | <0.055 | U | | <0.0074 | U | | <0.0072 | U | |
| | | VMP-10-20-012913 | 1/29/2013 | 0.0027 | J | | <0.0056 | U | | <0.0056 | U | | <0.0055 | U | | <0.0055 | U | | <0.0055 | U | | <0.048 | U | | <0.0064 | U | | <0.0063 | U | |
| | 30 ft | VMP-10-30-041212 | 4/12/2012 | 0.0035 | J | | <0.004 | U | | <0.004 | U | | <0.0039 | U | | <0.0039 | U | | <0.0039 | U | | <0.034 | U | | <0.0045 | U | | <0.0044 | U | |
| | | VMP-10-30-071612 | 7/16/2012 | 0.0026 | J | | <0.0035 | U | | <0.0035 | U | | <0.0034 | U | | <0.0034 | U | | <0.0034 | U | | <0.03 | J | U | <0.004 | U | | <0.0039 | U | |
| | | VMP-10-30-101612 | 10/16/2012 | 0.0026 | J | | <0.0061 | U | | <0.0061 | U | | <0.0059 | U | | <0.0059 | U | | <0.0059 | U | | 0.0053 | J | | <0.0069 | U | | <0.0068 | U | |
| | | VMP-10-30-012913 | 1/29/2013 | 0.0028 | J | | <0.0061 | U | | <0.0061 | U | | <0.006 | U | | <0.006 | U | | <0.006 | U | | <0.053 | U | | <0.007 | U | | <0.0069 | U | |
| VMP-11 | 5 ft | VMP-11-5-090710 | 9/7/2010 | 0.0025 | J | | <0.005 | U | | <0.005 | U | | <0.0049 | U | | <0.0049 | U | | <0.0049 | U | | <0.0043 | U | | <0.0057 | U | | <0.0056 | U | |
| | | VMP-11-5-112210 | 11/22/2010 | 0.0019 | J | | <0.0052 | U | | <0.0052 | U | | <0.0051 | U | | <0.0051 | U | | <0.0051 | U | | <0.0045 | U | | <0.006 | U | | <0.0058 | U | |
| | | VMP-11-5-021511 | 2/15/2011 | 0.0029 | J | | <0.0046 | U | | <0.0046 | U | | <0.0045 | U | | <0.0045 | U | | <0.0045 | U | | 0.0011 | J | | <0.0053 | U | | <0.0052 | U | |
| | | VMP-11-5-040611 | 4/6/2011 | <0.053 | U | | <0.044 | U | | <0.044 | U | | <0.043 | U | | <0.043 | U | | <0.043 | U | | 0.0086 | J | | <0.05 | U | | <0.049 | U | |
| | | VMP-11-5-080711 | 8/7/2011 | <0.073 | U | | <0.06 | U | | <0.06 | U | | <0.059 | U | | <0.059 | U | | <0.059 | U | | <0.052 | U | | <0.069 | U | | <0.067 | U | |
| | | VMP-11-5-111111 | 11/11/2011 | <0.014 | U | | <0.012 | U | | <0.012 | U | | <0.012 | U | | <0.012 | U | | <0.012 | U | | <0.01 | J | U | <0.014 | U | | <0.013 | U | |
| | | VMP-11-5-012612 | 1/26/2012 | 0.0024 | J | | <0.0035 | U | | <0.0035 | U | | <0.0035 | U | | <0.0035 | U | | <0.0035 | U | | 0.0072 | | | <0.004 | U | | <0.004 | U | |
| | | VMP-11-5-041912 | 4/19/2012 | 0.0028 | J | | <0.004 | U | | 0.00084 | J | | <0.0039 | U | | <0.0039 | U | | <0.0039 | U | | <0.034 | J | U | <0.0045 | U | | <0.0044 | U | |
| | | VMP-11-5-071912 | 7/16/2012 | 0.0022 | J | | <0.0051 | U | | <0.0051 | J | U | <0.005 | U | | <0.005 | U | | <0.005 | U | | <0.044 | J | U | <0.0059 | U | | <0.0058 | U | |
| | | VMP-11-5-101612 | 10/16/2012 | 0.0022 | J | | <0.0057 | U | | <0.0057 | U | | <0.0056 | U | | <0.0056 | U | | <0.0056 | U | | 0.0082 | J | | <0.0065 | U | | <0.0064 | U | |
| | | VMP-11-5-012913 | 1/29/2013 | <0.36 | U | | <0.29 | U | | <0.29 | U | | <0.28 | U | | <0.28 | U | | <0.28 | U | | 0.31 | J | | <0.33 | U | | <0.33 | U | |
| | 8 ft | VMP-11-8-090810 | 9/8/2010 | 0.0038 | J | | <0.0052 | U | | <0.0052 | U | | <0.0051 | U | | <0.0051 | U | | <0.0051 | U | | 0.047 | | | <0.006 | U | | <0.0058 | U | |
| | | VMP-11-8-112210 | 11/22/2010 | 0.0022 | J | | <0.0052 | U | | <0.0052 | U | | <0.0051 | U | | <0.0051 | U | | <0.0051 | U | | <0.0045 | U | | <0.006 | U | | <0.0058 | U | |
| | | VMP-11-8-021111 | 2/11/2011 | 0.0035 | J | | <0.005 | U | | <0.005 | U | | <0.005 | U | | <0.005 | U | | <0.005 | U | | <0.0043 | U | | <0.0058 | U | | <0.0057 | U | |
| | | VMP-11-8-021111-DUP | 2/11/2011 | 0.0033 | J | | <0.0048 | U | | <0.0048 | U | | <0.0046 | U | | <0.0046 | U | | <0.0046 | U | | <0.0041 | U | | <0.0054 | U | | <0.0053 | U | |
| | | VMP-11-8-040611 | 4/6/2011 | <0.027 | U | | <0.022 | U | | <0.022 | U | | <0.022 | U | | <0.022 | U | | <0.022 | U | | <0.019 | U | | <0.026 | U | | <0.025 | U | |
| | | VMP-11-8-040611-DUP | 4/6/2011 | <0.024 | U | | <0.019 | U | | <0.019 | U | | <0.019 | U | | <0.019 | U | | <0.019 | U | | 0.0027 | J | | <0.022 | U | | <0.022 | U | |
| | | VMP-11-8-080711 | 8/7/2011 | <0.073 | U | | <0.06 | U | | <0.06 | U | | <0.059 | U | | <0.059 | U | | <0.059 | U | | <0.052 | U | | <0.069 | U | | <0.067 | U | |
| | | VMP-11-8-111411 | 11/14/2011 | 0.0025 | J | | <0.0036 | U | | <0.0036 | U | | <0.0035 | U | | 0.0011 | J | | <0.0035 | U | | <0.003 | J | U | <0.0041 | U | | <0.004 | U | |
| | | VMP-11-8-012612 | 1/26/2012 | 0.0028 | J | | <0.0035 | U | | <0.0035 | U | | <0.0034 | U | | <0.0034 | U | | <0.0034 | U | | 0.0029 | J | | <0.004 | U | | <0.0039 | U | |
| | | VMP-11-8-041912 | 4/19/2012 | 0.0028 | J | | <0.004 | U | | <0.004 | U | | <0.0039 | U | | <0.0039 | U | | <0.0039 | U | | <0.034 | J | U | <0.0045 | U | | <0.0044 | U | |
| | | VMP-11-8-072012 | 7/20/2012 | 0.0027 | J | | <0.004 | U | | <0.004 | U | | <0.0039 | U | | <0.0039 | U | | <0.0039 | U | | 0.0047 | J | | <0.0045 | U | | <0.0044 | U | |
| | | VMP-11-8-101612 | 10/16/2012 | 0.0028 | J | | <0.0058 | U | | <0.0058 | U | | <0.0057 | U | | <0.0057 | U | | <0.0057 | U | | 0.0093 | J | | <0.0066 | U | | <0.0065 | U | |
| | | VMP-11-8-101612-Dup | 10/16/2012 | 0.0022 | J | | <0.0058 | U | | <0.0058 | U | | <0.0057 | U | | <0.0057 | U | | <0.0057 | U | | <0.05 | J | U | <0.0067 | U | | <0.0066 | U | |
| | | VMP-11-8-012913 | 1/29/2013 | <0.049 | U | | <0.04 | U | | <0.04 | U | | <0.039 | U | | <0.039 | U | | <0.039 | U | | <0.34 | U | | <0.046 | U | | <0.045 | U | |
| | 29 ft | VMP-11-29-090810 | 9/8/2010 | <0.16 | U | | <0.13 | U | | <0.13 | U | | <0.13 | U | | <0.13 | U | | <0.13 | U | | <0.11 | U | | <0.15 | U | | <0.15 | U | |
| | | VMP-11-29-112210 | 11/22/2010 | <2.3 | U | | <1.9 | U | | <1.9 | U | | <1.8 | U | | <1.8 | U | | <1.8 | U | | <1.6 | U | | <2.1 | U | | <2.1 | U | |
| | | VMP-11-29-112210-Dup | 11/22/2010 | <1.6 | U | | <1.3 | U | | <1.3 | U | | <1.3 | U | | <1.3 | U | | <1.3 | U | | <1.1 | U | | <1.5 | U | | <1.4 | U | |
| | | VMP-11-29-021411 | 2/14/2011 | 0.0041 | J | | <0.005 | U | | <0.005 | U | | <0.005 | U | | <0.005 | U | | <0.005 | U | | <0.0043 | U | | <0.0058 | U | | <0.0057 | U | |
| | | VMP-11-29-040611 | 4/6/2011 | <0.047 | U | | <0.038 | U | | <0.038 | U | | <0.037 | U | | <0.037 | U | | <0.037 | U | | <0.033 | U | | <0.044 | U | | <0.043 | U | |
| | | VMP-11-29-082511 | 8/25/2011 | 0.0023 | J | | <0.0056 | U | | <0.0056 | U | | <0.0055 | U | | <0.0055 | U | | <0.0055 | U | | 0.0021 | J | | <0.0064 | U | | <0.0063 | U | |
| | | VMP-11-29-082511-Dup | 8/25/2011 | 0.0023 | J | | <0.0056 | U | | <0.0056 | U | | <0.0055 | U | | <0.0055 | U | | <0.0055 | U | | <0.0048 | J | U | <0.0064 | U | | <0.0063 | U | |
| | | VMP-11-29-111411 | 11/14/2011 | 0.0019 | J | | <0.0035 | U | | <0.0035 | U | | <0.0035 | U | | <0.0035 | U | | <0.0035 | U | | <0.003 | J | U | <0.004 | U | | <0.004 | U | |
| | | VMP-11-29-012612 | 1/26/2012 | 0.0025 | J | | <0.0034 | U | | <0.0034 | U | | <0.0033 | U | | <0.0033 | U | | <0.0033 | U | | <0.0029 | U | | <0.0039 | U | | <0.0038 | U | |
| | | VMP-11-29-042712 | 4/27/2012 | 0.0022 | J | | <0.0035 | U | | <0.0035 | U | | <0.0035 | U | | <0.0035 | U | | <0.0035 | U | | 0.0021 | J | | <0.004 | U | | <0.004 | U | |
| | | VMP-11-29-072012 | 7/23/2012 | 0.0024 | J | | <0.0035 | U | | <0.0035 | U | | <0.0035 | U | | <0.0035 | U | | <0.0035 | U | | 0.002 | J | | <0.004 | U | | <0.004 | U | |
| | | VMP-11-29-101612 | 10/16/2012 | 0.0024 | J | | <0.006 | U | | <0.006 | U | | <0.0059 | U | | <0.0059 | U | | <0.0059 | U | | <0.051 | U | | <0.0068 | U | | <0.0067 | U | |
| | | VMP-11-29-012913 | 1/29/2013 | 0.003 | J | | <0.0058 | U | | <0.0058 | U | | <0.0057 | U | | <0.0057 | U | | <0.0057 | U | | <0.05 | J | U | <0.0067 | U | | <0.0066 | U | |
| | 38 ft | VMP-11-38-042312 | 4/23/2012 | <0.32 | U | | <0.26 | U | | <0.26 | U | | <0.26 | U | | <0.26 | U | | <0.26 | U | | <0.23 | U | | <0.3 | U | | <0.3 | U | |
| | | VMP-11-38-042312-Dup | 4/23/2012 | <1.1 | U | | <0.93 | U | | <0.93 | U | | <0.91 | U | | <0.91 | U | | <0.91 | U | | <0.8 | U | | <1 | U | | <1 | U | |
| | | VMP-11-38-072312 | 7/23/2012 | <0.54 | U | | <0.44 | U | | <0.44 | U | | <0.43 | U | | <0.43 | U | | <0.43 | U | | <0.38 | U | | <0.5 | U | | <0.49 | U | |
| | | VMP-11-38-101612 | 10/16/2012 | 0.0026 | J | | <0.0061 | U | | <0.0061 | U | | <0.0059 | U | | <0.0059 | U | | <0.0059 | U | | <0.052 | U | | <0.0069 | U | | <0.0068 | U | |
| | | VMP-11-38-013013 | 1/30/2013 | 0.0028 | J | | <0.0056 | U | | <0.0056 | U | | <0.0055 | U | | <0.0055 | U | | <0.0055 | U | | <0.048 | J | U | <0.0064 | U | | <0.0063 | U | |

SEE LAST PAGE OF TABLE FOR NOTES

**TABLE 6**
**CUMULATIVE SUMMARY OF SOIL VAPOR ANALYTICAL DETECTIONS AND SCREENING RESULTS: PUBLIC WORKS YARD AND WRR - VOCS**

| Location | Depth | Sample ID | Sample Date | Dichlorodifluoromethane | | | 1,1-Dichloroethane | | | 1,2-Dichloroethane | | | 1,1-Dichloroethene | | | cis-1,2-Dichloroethene | | | trans-1,2-Dichloroethene | | | Dichloromethane (Methylene | | | 1,2-Dichloropropane | | | cis-1,3-Dichloropropene | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | | | | 4200 | | | 0.81 | | | 1600 | | | 1100000 | | | 510 | | | 45 | | | 0.46 | | | 6.2 | | |
| | | | | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals |
| VMP-12 | 5 ft | VMP-12-5-090310 | 9/3/2010 | <6.6 | U | | <5.4 | U | | <5.4 | U | | <5.3 | U | | <5.3 | U | | <5.3 | U | | <4.7 | U | | <6.2 | U | | <6.1 | U | |
| | | VMP-12-5-120310 | 12/3/2010 | <66 | U | | <54 | U | | <54 | U | | <53 | U | | <53 | U | | <53 | U | | <46 | U | | <61 | U | | <60 | U | |
| | | VMP-12-5-021511 | 2/15/2011 | <3 | U | | <2.5 | U | | <2.5 | U | | <2.4 | U | | <2.4 | U | | <2.4 | U | | <2.1 | U | | <2.8 | U | | <2.8 | U | |
| | | VMP-12-5-041911 | 4/19/2011 | <22 | U | | <18 | U | | <18 | U | | <18 | U | | <18 | U | | <18 | U | | <16 | U | UJ | <21 | U | | <20 | U | |
| | | VMP-12-5-080411 | 8/4/2011 | <5.7 | U | | <4.7 | U | | <4.7 | U | | <4.6 | U | | <4.6 | U | | <4.6 | U | | <4 | U | | <5.3 | U | | <5.2 | U | |
| | | VMP-12-5-111611 | 11/16/2011 | <0.004 | U | UJ | <0.0033 | U | | <0.0033 | U | | <0.0032 | U | | <0.0032 | U | | <0.0032 | U | | 0.0026 | J | | <0.0038 | U | | <0.0037 | U | |
| | | VMP-12-5-012412 | 1/24/2012 | <0.045 | U | | <0.037 | U | | <0.037 | U | | <0.036 | U | | <0.036 | U | | <0.036 | U | | 0.011 | J | | <0.042 | U | | <0.042 | U | |
| | | VMP-12-5-041912 | 4/19/2012 | 0.0029 | J | | <0.0037 | U | | <0.0037 | U | | <0.0036 | U | | <0.0036 | U | | <0.0036 | U | | <0.032 | J | U | <0.0042 | U | | <0.0042 | U | |
| | | VMP-12-5-072612 | 7/26/2012 | 0.0032 | J | | <0.0039 | U | | <0.0039 | U | | <0.0039 | U | | <0.0039 | U | | <0.0039 | U | | 0.0074 | J | | <0.0045 | U | | <0.0044 | U | |
| | | VMP-12-5-072612-Dup | 7/26/2012 | 0.0059 | | | <0.0036 | U | | <0.0036 | U | | <0.0035 | U | | <0.0035 | U | | <0.0035 | U | | 0.045 | | | <0.0041 | U | | <0.004 | U | |
| | | VMP-12-5-102412 | 10/24/2012 | 0.0024 | J | | <0.0061 | U | | <0.0061 | U | | <0.0059 | U | | <0.0059 | U | | <0.0059 | U | | <0.052 | U | | <0.0069 | U | | <0.0068 | U | |
| | | VMP-12-5-021813 | 2/18/2013 | 0.0028 | J | | <0.0054 | U | | <0.0054 | U | | <0.0053 | U | | <0.0053 | U | | <0.0053 | U | | 0.0019 | J | | <0.0062 | U | | <0.0061 | U | |
| | 11.5 ft | VMP-12-11.5-090310 | 9/3/2010 | <8.5 | U | | <7 | U | | <7 | U | | <6.8 | U | | <6.8 | U | | <6.8 | U | | <6 | U | | <8 | U | | <7.8 | U | |
| | | VMP-12-11.5-120310 | 12/3/2010 | <7.4 | U | | <6 | U | | <6 | U | | <5.9 | U | | <5.9 | U | | <5.9 | U | | <5.2 | U | | <6.9 | U | | <6.8 | U | |
| | | VMP-12-11.5-021511 | 2/15/2011 | <6.6 | U | | <5.4 | U | | <5.4 | U | | <5.3 | U | | <5.3 | U | | <5.3 | U | | <4.6 | U | | <6.2 | U | | <6.1 | U | |
| | | VMP-12-11.5-021511-DUP | 2/15/2011 | <5.7 | U | | <4.7 | U | | <4.7 | U | | <4.6 | U | | <4.6 | U | | <4.6 | U | | <4 | U | | <5.3 | U | | <5.2 | U | |
| | | VMP-12-11.5-041911 | 4/19/2011 | <20 | U | | <16 | U | | <16 | U | | <16 | U | | <16 | U | | <16 | U | | <14 | U | UJ | <19 | U | | <18 | U | |
| | | VMP-12-11.5-080411 | 8/4/2011 | <7 | U | | <5.7 | U | | <5.7 | U | | <5.6 | U | | <5.6 | U | | <5.6 | U | | <4.9 | U | | <6.5 | U | | <6.4 | U | |
| | | VMP-12-11.5-111611 | 11/16/2011 | <0.056 | U | UJ | <0.046 | U | | <0.046 | U | | <0.045 | U | | <0.045 | U | | <0.045 | U | | <0.039 | U | | <0.052 | U | | <0.051 | U | |
| | | VMP-12-11.5-012412 | 1/24/2012 | <0.52 | U | | <0.42 | U | | <0.42 | U | | <0.42 | U | | <0.42 | U | | <0.42 | U | | 0.096 | J | | <0.48 | U | | <0.48 | U | |
| | | VMP-12-11.5-041912 | 4/19/2012 | <0.047 | U | | <0.039 | U | | <0.039 | U | | <0.038 | U | | <0.038 | U | | <0.038 | U | | 0.0081 | J | | <0.044 | U | | <0.043 | U | |
| | | VMP-12-11.5-082012 | 8/20/2012 | 0.004 | J | J | <0.0061 | U | | <0.0061 | U | | <0.006 | U | | <0.006 | U | | <0.006 | U | | 0.0016 | J | | <0.007 | U | | <0.0069 | U | |
| | | VMP-12-11.5-102612 | 10/26/2012 | 0.0022 | J | | <0.0058 | U | | <0.0058 | U | | <0.0057 | U | | <0.0057 | U | | <0.0057 | U | | <0.05 | U | | <0.0067 | U | | <0.0066 | U | |
| | | VMP-12-11.5-021813 | 2/18/2013 | 0.0023 | J | | <0.0058 | U | | <0.0058 | U | | <0.0057 | U | | <0.0057 | U | | <0.0057 | U | | <0.05 | U | | <0.0067 | U | | <0.0066 | U | |
| | 25 ft | VMP-12-25-090310 | 9/3/2010 | <11 | U | | <8.9 | U | | <8.9 | U | | <8.7 | U | | <8.7 | U | | <8.7 | U | | <7.6 | U | | <10 | U | | <10 | U | |
| | | VMP-12-25-120310 | 12/3/2010 | <0.54 | U | | <0.44 | U | | <0.44 | U | | <0.43 | U | | <0.43 | U | | <0.43 | U | | <0.38 | U | | <0.5 | U | | <0.49 | U | |
| | | VMP-12-25-021511 | 2/15/2011 | <13 | U | | <11 | U | | <11 | U | | <10 | U | | <10 | U | | <10 | U | | <9.2 | U | | <12 | U | | <12 | U | |
| | | VMP-12-25-041911 | 4/19/2011 | <21 | U | | <18 | U | | <18 | U | | <17 | U | | <17 | U | | <17 | U | | <15 | U | UJ | <20 | U | | <20 | U | |
| | | VMP-12-25-080411 | 8/4/2011 | <14 | U | | <11 | U | | <11 | U | | <11 | U | | <11 | U | | <11 | U | | <9.6 | U | | <13 | U | | <12 | U | |
| | | VMP-12-25-111611 | 11/16/2011 | <16 | U | UJ | <13 | U | | 11 | J | | <12 | U | | <12 | U | | <12 | U | | 9.6 | J | | <14 | U | | <14 | U | |
| | | VMP-12-25-012412 | 1/24/2012 | <5.9 | U | | <4.8 | U | | <4.8 | U | | <4.8 | U | | <4.8 | U | | <4.8 | U | | <4.2 | U | | <5.5 | U | | <5.4 | U | |
| | | VMP-12-25-012412-DUP | 1/24/2012 | <43 | U | | <35 | U | | <35 | U | | <35 | U | | <35 | U | | <35 | U | | 5.8 | J | | <40 | U | | <40 | U | |
| | | VMP-12-25-041912 | 4/19/2012 | <4.5 | U | | <3.7 | U | | <3.7 | U | | <3.6 | U | | <3.6 | U | | <3.6 | U | | 3.3 | | | <4.2 | U | | <4.2 | U | |
| | | VMP-12-25-072712 | 7/27/2012 | <5 | U | | <4.1 | U | | <4.1 | U | | <4 | U | | <4 | U | | <4 | U | | 1 | J | | <4.6 | U | | <4.6 | U | |
| | | VMP-12-25-072712-Dup | 7/27/2012 | <5 | U | | <4.1 | U | | <4.1 | U | | <4 | U | | <4 | U | | <4 | U | | 0.49 | J | | <4.6 | U | | <4.6 | U | |
| | | VMP-12-25-102512 | 10/25/2012 | <2.1 | U | | <1.8 | U | | <1.8 | U | | <1.7 | U | | <1.7 | U | | <1.7 | U | | 0.16 | J | | <2 | U | | <2 | U | |
| | | VMP-12-25-021513 | 2/15/2013 | <4 | U | | <3.2 | U | | <3.2 | U | | <3.2 | U | | <3.2 | U | | <3.2 | U | | 1.8 | J | J | 14 | | J | <3.6 | U | |
| | 39 ft | VMP-12-39-041911 | 4/19/2011 | <21 | U | | <17 | U | | <17 | U | | <17 | U | | <17 | U | | <17 | U | | <15 | U | UJ | <19 | U | | <19 | U | |
| | | VMP-12-39-012412 | 1/24/2012 | <43 | U | | <35 | U | | <35 | U | | <35 | U | | <35 | U | | <35 | U | | 6.4 | J | | <40 | U | | <40 | U | |
| | | VMP-12-39-041912 | 4/19/2012 | <22 | U | | <18 | U | | <18 | U | | <17 | U | | <17 | U | | <17 | U | | 3.8 | J | | <20 | U | | <20 | U | |
| | | VMP-12-39-072612 | 7/26/2012 | <9.9 | U | | <8.1 | U | | <8.1 | U | | <8 | U | | <8 | U | | <8 | U | | 2.7 | J | | <9.3 | U | | <9.1 | U | |
| | | VMP-12-39-102412 | 10/24/2012 | <26 | U | | <21 | U | | <21 | U | | <21 | U | | <21 | U | | <21 | U | | 7.1 | J | | <24 | U | | <24 | U | |
| | | VMP-12-39-021513 | 2/15/2013 | <12 | U | | <9.8 | U | | <9.8 | U | | 1 | J | | <9.6 | U | | <9.6 | U | | 9.5 | | | 21 | | | <11 | U | |
| VMP-13 | 5 ft | VMP-13-5-091310 | 9/13/2010 | <0.044 | U | | <0.036 | U | | <0.036 | U | | <0.035 | U | | <0.035 | U | | <0.035 | U | | <0.03 | U | | <0.041 | U | | <0.04 | U | |
| | | VMP-13-5-120110 | 12/1/2010 | 0.0032 | J | | <0.0047 | U | | <0.0047 | U | | <0.0046 | U | | <0.0046 | U | | <0.0046 | U | | <0.004 | U | | <0.0054 | U | | <0.0053 | U | |
| | | VMP-13-5-021811 | 2/18/2011 | 0.0024 | J | | <0.0056 | U | | <0.0056 | U | | <0.0055 | U | | <0.0055 | U | | <0.0055 | U | | <0.0048 | U | | <0.0064 | U | | <0.0063 | U | |
| | | VMP-13-5-040511 | 4/5/2011 | <0.014 | U | | <0.011 | U | | <0.011 | U | | <0.011 | U | | <0.011 | U | | <0.011 | U | | 0.0082 | J | | <0.013 | U | | <0.012 | U | |
| | | VMP-13-5-080911 | 8/9/2011 | 0.0027 | J | | <0.012 | U | | <0.012 | U | | <0.012 | U | | <0.012 | U | | <0.012 | U | | 0.0085 | J | | <0.014 | U | | <0.013 | U | |
| | | VMP-13-5-080911-DUP | 8/9/2011 | 0.003 | J | | <0.011 | U | | <0.011 | U | | <0.01 | U | | <0.01 | U | | <0.01 | U | | 0.004 | J | | <0.012 | U | | <0.012 | U | |
| | | VMP-13-5-111411 | 11/14/2011 | 0.002 | J | | <0.0037 | U | | <0.0037 | U | | <0.0036 | U | | <0.0036 | U | | <0.0036 | U | | <0.0032 | J | U | <0.0042 | U | | <0.0042 | U | |
| | | VMP-13-5-012712 | 1/27/2012 | <0.038 | U | | <0.031 | U | | <0.031 | U | | <0.031 | U | | <0.031 | U | | <0.031 | U | | 0.0072 | J | J | <0.036 | U | | <0.035 | U | |
| | | VMP-13-5-042012 | 4/20/2012 | 0.0028 | J | | <0.0036 | U | | <0.0036 | U | | <0.0035 | U | | <0.0035 | U | | <0.0035 | U | | <0.031 | U | | <0.0041 | U | | <0.0041 | U | |
| | | VMP-13-5-071912 | 7/19/2012 | 0.0028 | J | | <0.0038 | U | | 0.0011 | J | | <0.0037 | U | | <0.0037 | U | | <0.0037 | U | | <0.032 | J | U | <0.0043 | U | | <0.0042 | U | |
| | | VMP-13-5-071912-Dup | 7/19/2012 | 0.0032 | J | | <0.0038 | U | | 0.0008 | J | | <0.0037 | U | | <0.0037 | U | | <0.0037 | U | | <0.032 | J | U | <0.0043 | U | | <0.0042 | U | |
| | | VMP-13-5-100912 | 10/9/2012 | 0.0025 | J | | <0.0058 | U | | <0.0058 | U | | <0.0057 | U | | <0.0057 | U | | <0.0057 | U | | 0.0028 | J | | <0.0067 | U | | <0.0066 | U | |
| | | VMP-13-5-012913 | 1/29/2013 | 0.0034 | J | | <0.0063 | U | | <0.0063 | U | | <0.0062 | U | | <0.0062 | U | | <0.0062 | U | | <0.054 | U | | <0.0072 | U | | <0.007 | U | |
| | 10.5 ft | VMP-13-10.5-091310 | 9/13/2010 | 0.0032 | J | | <0.013 | U | | <0.013 | U | | <0.013 | U | | <0.013 | U | | <0.013 | U | | <0.011 | U | | <0.015 | U | | <0.015 | U | |
| | | VMP-13-10.5-091310-Dup | 9/13/2010 | 0.0034 | J | | <0.013 | U | | <0.013 | U | | <0.012 | U | | <0.012 | U | | <0.012 | U | | <0.011 | U | | <0.015 | U | | <0.014 | U | |
| | | VMP-13-10.5-120110 | 12/1/2010 | 0.003 | J | | <0.0052 | U | | <0.0052 | U | | <0.0051 | U | | <0.0051 | U | | <0.0051 | U | | <0.0045 | U | | <0.006 | U | | <0.0059 | U | |
| | | VMP-13-10.5-120110-DUP | 12/1/2010 | 0.0032 | J | | <0.0055 | U | | <0.0055 | U | | <0.0054 | U | | <0.0054 | U | | <0.0054 | U | | <0.0047 | U | | <0.0062 | U | | <0.0061 | U | |
| | | VMP-13-10.5-021811 | 2/18/2011 | <2.6 | U | | <2.2 | U | | <2.2 | U | | <2.1 | U | | <2.1 | U | | <2.1 | U | | <1.8 | U | | <2.5 | U | | <2.4 | U | |
| | | VMP-13-10.5-021811-DUP | 2/18/2011 | <2.5 | U | | <2.1 | U | | <2.1 | U | | <2 | U | | <2 | U | | <2 | U | | <1.8 | U | | <2.4 | U | | <2.3 | U | |
| | | VMP-13-10.5-040511-DUP | 4/5/2011 | 0.0021 | J | | <0.0056 | U | | <0.0056 | U | | <0.0055 | U | | <0.0055 | U | | <0.0055 | U | | <0.0048 | J | U | <0.0064 | U | | <0.0063 | U | |
| | | VMP-13-10.5-080911 | 8/9/2011 | <0.15 | U | | <0.12 | U | | <0.12 | U | | <0.12 | U | | <0.12 | U | | <0.12 | U | | <0.1 | U | | <0.14 | U | | <0.14 | U | |
| | | VMP-13-10.5-111411 | 11/14/2011 | 0.002 | J | | <0.0036 | U | | <0.0036 | U | | <0.0035 | U | | <0.0035 | U | | <0.0035 | U | | 0.0044 | | | <0.0041 | U | | <0.004 | U | |
| | | VMP-13-10.5-012712 | 1/26/2012 | 0.0024 | J | | <0.0099 | U | | <0.0099 | U | | <0.0097 | U | | <0.0097 | U | | <0.0097 | U | | <0.0085 | U | | <0.011 | U | | <0.011 | U | |
| | | VMP-13-10.5-012712-DUP | 1/26/2012 | <0.017 | U | | <0.014 | U | | <0.014 | U | | <0.014 | U | | <0.014 | U | | <0.014 | U | | <0.012 | U | | <0.016 | U | | <0.016 | U | |
| | | VMP-13-10.5-042012 | 4/20/2012 | 0.003 | J | | <0.0035 | U | | <0.0035 | J | U | <0.0035 | U | | <0.0035 | U | | <0.0035 | U | | 0.0016 | J | | 0.0011 | J | | <0.004 | U | |
| | | VMP-13-10.5-071912 | 7/19/2012 | 0.0031 | J | | <0.0038 | U | | <0.0038 | U | | <0.0037 | U | | <0.0037 | U | | <0.0037 | U | | <0.032 | J | U | <0.0043 | U | | <0.0042 | U | |
| | | VMP-13-10.5-100912 | 10/9/2012 | 0.0024 | J | | <0.005 | U | | <0.005 | U | | <0.0049 | U | | <0.0049 | U | | <0.0049 | U | | 0.0022 | J | | <0.0057 | U | | <0.0056 | U | |
| | | VMP-13-10.5-100912-Dup | 10/9/2012 | 0.002 | J | | <0.006 | U | | <0.006 | U | | <0.0059 | U | | <0.0059 | U | | <0.0059 | U | | 0.0043 | J | | <0.0068 | U | | <0.0067 | U | |
| | | VMP-13-10.5-013013 | 1/30/2013 | 0.0022 | J | | <0.0051 | U | | <0.0051 | U | | <0.005 | U | | <0.005 | U | | <0.005 | U | | <0.044 | U | | <0.0058 | U | | <0.0057 | U | |
| | 21.5 ft | VMP-13-21.5-091310 | 9/13/2010 | <12 | U | | <9.8 | U | | <9.8 | U | | <9.6 | U | | <9.6 | U | | <9.6 | U | | 9.2 | | | <11 | U | | <11 | U | |
| | | VMP-13-21.5-120110 | 12/1/2010 | <23 | U | | <19 | U | | <19 | U | | <18 | U | | <18 | U | | <18 | U | | 28 | | | <22 | U | | <21 | U | |
| | | VMP-13-21.5-021811 | 2/18/2011 | <3.5 | U | | <2.8 | U | | <2.8 | U | | <2.8 | U | | <2.8 | U | | <2.8 | U | | 0.51 | J | | <3.2 | U | | <3.2 | U | |
| | | VMP-13-21.5-040511 | 4/5/2011 | <5 | U | | <4.1 | U | | <4.1 | U | | <4 | U | | <4 | U | | <4 | U | | 2.3 | J | | <4.7 | U | | <4.6 | U | |
| | | VMP-13-21.5-080911 | 8/9/2011 | <0.62 | U | | <0.51 | U | | <0.51 | U | | <0.5 | U | | <0.5 | U | | <0.5 | U | | <0.44 | U | | <0.58 | U | | <0.57 | U | |
| | | VMP-13-21.5-111411 | 11/14/2011 | <2.8 | U | | <2.3 | U | | 1.4 | J | | <2.3 | U | | <2.3 | U | | <2.3 | U | | <2 | U | | <2.6 | U | | <2.6 | U | |
| | | VMP-13-21.5-111411-DUP | 11/14/2011 | <2.8 | U | | <2.3 | U | | 1.6 | J | | <2.3 | U | | <2.3 | U | | <2.3 | U | | <2 | U | | <2.6 | U | | <2.6 | U | |
| | | VMP-13-21.5-012712 | 1/27/2012 | <0.66 | U | | <0.54 | U | | <0.54 | U | | <0.53 | U | | <0.53 | U | | <0.53 | U | | 0.094 | J | J | <0.62 | U | | <0.61 | U | |
| | | VMP-13-21.5-042012 | 4/20/2012 | <0.074 | U | | <0.06 | U | | <0.06 | U | | <0.059 | U | | <0.059 | U | | <0.059 | U | | 0.028 | J | | 0.015 | J | | <0.068 | U | |
| | | VMP-13-21.5-071912 | 7/19/2012 | 0.0025 | J | | <0.0038 | U | | <0.0038 | U | | <0.0037 | U | | <0.0037 | U | | <0.0037 | U | | 0.0044 | J | | 0.00065 | J | | <0.0042 | U | |
| | | VMP-13-21.5-100912 | 10/9/2012 | 0.0025 | J | | <0.0061 | U | | <0.0061 | U | | <0.006 | U | | <0.006 | U | | <0.006 | U | | 0.0012 | J | | <0.007 | U | | <0.0069 | U | |
| | | VMP-13-21.5-013013 | 1/30/2013 | 0.0022 | J | | <0.006 | U | | <0.006 | U | | <0.0059 | U | | <0.0059 | U | | <0.0059 | U | | <0.051 | J | U | <0.0068 | U | | <0.0067 | U | |
| | 29.5 ft | VMP-13-29.5-021811 | 2/18/2011 | <110 | U | | <87 | U | | <87 | U | | <86 | U | | <86 | U | | <86 | U | | <75 | U | | <100 | U | | <98 | U | |
| | | VMP-13-29.5-040511 | 4/5/2011 | <69 | U | | <57 | U | | <57 | U | | <56 | U | | <56 | U | | <56 | U | | <49 | U | | <65 | U | | <64 | U | |
| | | VMP-13-29.5-013012 | 1/30/2012 | <2.1 | U | | <1.7 | U | | <1.7 | U | | <1.7 | U | | <1.7 | U | | <1.7 | U | | <1.5 | U | | <2 | U | | <1.9 | U | |
| | | VMP-13-29.5-042012 | 4/20/2012 | <2.8 | U | | <2.3 | U | | <2.3 | U | | <2.2 | U | | <2.2 | U | | <2.2 | U | | 0.59 | J | | <2.6 | U | | <2.5 | U | |
| | | VMP-13-29.5-071912 | 7/19/2012 | <8 | U | | <6.5 | U | | <6.5 | U | | <6.4 | U | | <6.4 | U | | <6.4 | U | | <5.6 | U | | <7.4 | U | | <7.3 | U | |
| | | VMP-13-29.5-100912 | 10/9/2012 | <7.5 | U | | <6.1 | U | | <6.1 | U | | <6 | U | | <6 | U | | <6 | U | | <5.3 | U | | <7 | U | | <6.9 | U | |
| | | VMP-13-29.5-013013 | 1/30/2013 | <3.2 | U | | <2.6 | U | | <2.6 | U | | <2.5 | U | | <2.5 | U | | <2.5 | U | | 1.7 | J | | <3 | U | | <2.9 | U | |

**TABLE 6**
**CUMULATIVE SUMMARY OF SOIL VAPOR ANALYTICAL DETECTIONS AND SCREENING RESULTS: PUBLIC WORKS YARD AND WRR - VOCS**

| Location | Depth | Sample ID | Sample Date | Dichlorodifluoromethane | | | 1,1-Dichloroethane | | | 1,2-Dichloroethane | | | 1,1-Dichloroethene | | | cis-1,2-Dichloroethene | | | trans-1,2-Dichloroethene | | | Dichloromethane (Methylene | | | 1,2-Dichloropropane | | | cis-1,3-Dichloropropene | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | | | | 4200 | | | 0.81 | | | 1600 | | | 1100000 | | | 510 | | | 45 | | | 0.46 | | | 6.2 | | |
| | | | | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals |
| VMP-14 | 5 ft | VMP 14-5-091010 | 9/10/2010 | <0.31 | U | | <0.25 | U | | <0.25 | U | | <0.24 | U | | <0.24 | U | | <0.24 | U | | <0.22 | U | | <0.29 | U | | <0.28 | U | |
| | | VMP-14-5-120110 | 12/1/2010 | 0.0025 | J | | <0.0048 | U | | <0.0048 | U | | <0.0048 | U | | <0.0048 | U | | <0.0048 | U | | <0.0042 | U | | <0.0055 | U | | <0.0054 | U | |
| | | VMP-14-5-021711 | 2/17/2011 | 0.0023 | J | | <0.0053 | U | | <0.0053 | U | | <0.0052 | U | | <0.0052 | U | | <0.0052 | U | | <0.0046 | U | | <0.0061 | U | | <0.006 | U | |
| | | VMP-14-5-040511 | 4/5/2011 | 0.0023 | J | | <0.0054 | U | | <0.0054 | U | | <0.0053 | U | | <0.0053 | U | | <0.0053 | U | | 0.0022 | J | | <0.0062 | U | | <0.0061 | U | |
| | | VMP-14-5-080811 | 8/8/2011 | <6.9 | U | | <5.7 | U | | <5.7 | U | | <5.6 | U | | <5.6 | U | | <5.6 | U | | <4.9 | U | | <6.5 | U | | <6.4 | U | |
| | | VMP-14-5-111411 | 11/14/2011 | <0.017 | U | | <0.014 | U | | <0.014 | U | | <0.014 | U | | <0.014 | U | | <0.014 | U | | <0.012 | U | | <0.016 | U | | <0.016 | U | |
| | | VMP-14-5-042012 | 4/20/2012 | 0.0025 | J | | <0.0035 | U | | 0.00037 | J | | <0.0034 | U | | <0.0034 | U | | <0.0034 | U | | <0.03 | J | U | <0.004 | U | | <0.0039 | U | |
| | | VMP-14-5-072312 | 7/23/2012 | 0.0028 | J | | <0.0042 | U | | <0.0042 | U | | <0.0041 | U | | <0.0041 | U | | <0.0041 | U | | 0.003 | J | | <0.0048 | U | | <0.0047 | U | |
| | | VMP-14-5-101012 | 10/10/2012 | 0.0024 | J | | <0.0058 | U | | <0.0058 | U | | <0.0057 | U | | <0.0057 | U | | <0.0057 | U | | 0.0033 | J | | <0.0067 | U | | <0.0066 | U | |
| | | VMP-14-5-013113 | 1/31/2013 | 0.0024 | J | | <0.0054 | U | | <0.0054 | U | | <0.0053 | U | | <0.0053 | U | | <0.0053 | U | | <0.047 | J | U | <0.0062 | U | | <0.0061 | U | |
| | 11.5 ft | VMP 14-11.5-091010 | 9/10/2010 | <4.7 | U | | <3.9 | U | | <3.9 | U | | <3.8 | U | | <3.8 | U | | <3.8 | U | | <3.3 | U | | <4.4 | U | | <4.3 | U | |
| | | VMP-14-11.5-120110 | 12/2/2010 | <0.42 | U | | <0.34 | U | | <0.34 | U | | <0.33 | U | | <0.33 | U | | <0.33 | U | | 1.2 | | | <0.39 | U | | <0.38 | U | |
| | | VMP-14-11.5-120110-DUP | 12/2/2010 | <0.38 | U | | <0.31 | U | | <0.31 | U | | <0.3 | U | | <0.3 | U | | <0.3 | U | | 1.9 | | | <0.35 | U | | <0.34 | U | |
| | | VMP-14-11.5-021711 | 2/17/2011 | <0.14 | U | | <0.11 | U | | <0.11 | U | | <0.11 | U | | <0.11 | U | | <0.11 | U | | <0.096 | U | | <0.13 | U | | <0.12 | U | |
| | | VMP-14-11.5-021711-DUP | 2/17/2011 | <0.14 | U | | <0.11 | U | | <0.11 | U | | <0.11 | U | | <0.11 | U | | <0.11 | U | | <0.096 | U | | <0.13 | U | | <0.12 | U | |
| | | VMP-14-11.5-040511 | 4/5/2011 | <0.022 | U | | <0.018 | U | | <0.018 | U | | <0.018 | U | | <0.018 | U | | <0.018 | U | | <0.016 | U | | <0.021 | U | | <0.02 | U | |
| | | VMP-14-11.5-080811 | 8/8/2011 | <0.69 | U | | <0.56 | U | | <0.56 | U | | <0.55 | U | | <0.55 | U | | <0.55 | U | | <0.48 | U | | <0.64 | U | | <0.63 | U | |
| | | VMP-14-11.5-111511 | 11/15/2011 | <1.1 | U | | <0.87 | U | | 0.89 | | | <0.86 | U | | <0.86 | U | | <0.86 | U | | <0.75 | U | | <1 | U | | <0.98 | U | |
| | | VMP-14-11.5-012612 | 1/26/2012 | <4.4 | U | | <3.6 | U | | <3.6 | U | | <3.5 | U | | <3.5 | U | | <3.5 | U | | <3 | U | | <4.1 | U | | <4 | U | |
| | | VMP-14-11.5-042312 | 4/23/2012 | 0.0023 | J | | <0.0037 | U | | 0.00076 | J | | <0.0036 | U | | <0.0036 | U | | <0.0036 | U | | 0.0018 | J | | <0.0042 | U | | <0.0042 | U | |
| | | VMP-14-11.5-042312-Dup | 4/23/2012 | 0.0014 | J | | <0.0037 | U | | <0.0037 | U | | <0.0036 | U | | <0.0036 | U | | <0.0036 | U | | <0.032 | J | U | <0.0042 | U | | <0.0042 | U | |
| | | VMP-14-11.5-072512 | 7/25/2012 | <1.6 | U | | <1.3 | U | | <1.3 | U | | <1.3 | U | | <1.3 | U | | <1.3 | U | | <1.1 | U | | <1.5 | U | | <1.4 | U | |
| | | VMP-14-11.5-101012 | 10/10/2012 | 0.0023 | J | | <0.0056 | U | | <0.0056 | U | | <0.0055 | U | | <0.0055 | U | | <0.0055 | U | | 0.0052 | J | | <0.0064 | U | | <0.0063 | U | |
| | | VMP-14-11.5-013113 | 1/31/2013 | 0.0028 | J | | <0.0052 | U | | <0.0052 | U | | <0.0051 | U | | <0.0051 | U | | <0.0051 | U | | <0.045 | U | | <0.006 | U | | <0.0058 | U | |
| | 20 ft | VMP 14-20-091010 | 9/10/2010 | <72 | U | | <59 | U | | <59 | U | | <58 | U | | <58 | U | | <58 | U | | 18 | J | | <67 | U | | <66 | U | |
| | | VMP-14-20-091010-Dup | 9/10/2010 | <75 | U | | <61 | U | | <61 | U | | <60 | U | | <60 | U | | <60 | U | | <52 | U | | <70 | U | | <68 | U | |
| | | VMP-14-20-120110 | 12/2/2010 | <190 | U | | <160 | U | | <160 | U | | <160 | U | | <160 | U | | <160 | U | | 160 | | | <180 | U | | <180 | U | |
| | | VMP-14-20-021811 | 2/18/2011 | <110 | U | | <90 | U | | <90 | U | | <88 | U | | <88 | U | | <88 | U | | <77 | U | | <100 | U | | <100 | U | |
| | | VMP-14-20-040511 | 4/5/2011 | <47 | U | | <38 | U | | <38 | U | | <38 | U | | <38 | U | | <38 | U | | <33 | U | | <44 | U | | <43 | U | |
| | | VMP-14-20-080811 | 8/8/2011 | <17 | U | | <14 | U | | <14 | U | | <14 | U | | <14 | U | | <14 | U | | <12 | U | | <16 | U | | <16 | U | |
| | | VMP-14-20-111511 | 11/15/2011 | <88 | U | | <72 | U | | <72 | U | | <70 | U | | <70 | U | | <70 | U | | <62 | U | | <82 | U | | <81 | U | |
| | | VMP-14-20-012612 | 1/26/2012 | <8.6 | U | | <7.1 | U | | <7.1 | U | | <6.9 | U | | <6.9 | U | | <6.9 | U | | 1.9 | J | J | <8.1 | U | | <7.9 | U | |
| | | VMP-14-20-042312 | 4/23/2012 | <4.7 | U | | <3.9 | U | | <3.9 | U | | <3.8 | U | | <3.8 | U | | <3.8 | U | | <3.3 | U | | <4.4 | U | | <4.3 | U | |
| | | VMP-14-20-072512 | 7/25/2012 | <7.5 | U | | <6.2 | U | | <6.2 | U | | <6 | U | | <6 | U | | <6 | U | | <5.3 | U | | <7 | U | | <6.9 | U | |
| | | VMP-14-20-101612 | 10/16/2012 | <35 | U | | <28 | U | | <28 | U | | <28 | U | | <28 | U | | <28 | U | | 2.6 | J | | <32 | U | | <32 | U | |
| | | VMP-14-20-013113 | 1/31/2013 | <12 | U | | <10 | U | | <10 | U | | <10 | U | | <10 | U | | <10 | U | | 7.7 | J | | <12 | U | | <11 | U | |
| | 29 ft | VMP-14-29-021811 | 2/18/2011 | <160 | U | | <130 | U | | <130 | U | | <130 | U | | <130 | U | | <130 | U | | <110 | U | | <150 | U | | <140 | U | |
| | | VMP-14-29-040511 | 4/5/2011 | <140 | U | | <110 | U | | <110 | U | | <110 | U | | <110 | U | | <110 | U | | <96 | U | | <130 | U | | <120 | U | |
| | | VMP-14-29-012612 | 1/26/2012 | <160 | U | | <130 | U | | <130 | U | | <120 | U | | <120 | U | | <120 | U | | <110 | U | | <140 | U | | <140 | U | |
| | | VMP-14-29-042312 | 4/23/2012 | <55 | U | | <45 | U | | <45 | U | | <44 | U | | <44 | U | | <44 | U | | <39 | U | | <52 | U | | <51 | U | |
| | | VMP-14-29-072512 | 7/25/2012 | <58 | U | | <48 | U | | <48 | U | | <46 | U | | <46 | U | | <46 | U | | <41 | U | | <54 | U | | <53 | U | |
| | | VMP-14-29-101612 | 10/16/2012 | <87 | U | | <71 | U | | <71 | U | | <70 | U | | <70 | U | | <70 | U | | <61 | U | | <81 | U | | <80 | U | |
| | | VMP-14-29-013113-DUP | 1/31/2013 | <120 | U | | <96 | U | | <96 | U | | <94 | U | | <94 | U | | <94 | U | | <820 | U | UJ | <110 | U | | <110 | U | |
| | | VMP-14-29-013113 | 1/31/2013 | <49 | U | | <40 | U | | <40 | U | | <39 | U | | <39 | U | | <39 | U | | 7.7 | J | J | <46 | U | | <45 | U | |
| VMP-15 | 5 ft | VMP 15-5-091410 | 9/14/2010 | 0.002 | J | | <0.0051 | U | | <0.0051 | U | | <0.005 | U | | <0.005 | U | | <0.005 | U | | 0.001 | J | | <0.0058 | U | | <0.0057 | U | |
| | | VMP-15-5-113010 | 11/30/2010 | <0.15 | U | | <0.12 | U | | <0.12 | U | | <0.12 | U | | <0.12 | U | | <0.12 | U | | <0.1 | U | | <0.14 | U | | <0.14 | U | |
| | | VMP-15-5-021611 | 2/16/2011 | <0.14 | U | | <0.11 | U | | <0.11 | U | | <0.11 | U | | <0.11 | U | | <0.11 | U | | 0.091 | J | | <0.13 | U | | <0.13 | U | |
| | | VMP-15-5-042011 | 4/20/2011 | <0.33 | U | | <0.27 | U | | <0.27 | U | | <0.26 | U | | <0.26 | U | | <0.26 | U | | <0.23 | U | | <0.3 | U | | <0.3 | U | |
| | | VMP-15-5-080811 | 8/8/2011 | 0.0026 | J | | <0.006 | U | | <0.006 | J | U | <0.0059 | U | | <0.0059 | U | | <0.0059 | U | | 0.012 | | | <0.0069 | U | | <0.0067 | J | U |
| | | VMP-15-5-111511 | 11/15/2011 | <0.0082 | U | | <0.0067 | U | | <0.0067 | U | | <0.0066 | U | | <0.0066 | U | | <0.0066 | U | | <0.0058 | J | U | <0.0077 | U | | <0.0075 | U | |
| | | VMP-15-5-020112 | 2/1/2012 | <0.042 | U | | <0.035 | U | | <0.035 | U | | <0.034 | U | | <0.034 | U | | <0.034 | U | | <0.03 | U | | <0.04 | U | | <0.039 | U | |
| | | VMP-15-5-042412 | 4/24/2012 | <0.043 | U | | <0.035 | U | | <0.035 | U | | <0.035 | U | | <0.035 | U | | <0.035 | U | | <0.03 | U | | <0.04 | U | | <0.04 | U | |
| | | VMP-15-5-072512 | 7/25/2012 | 0.0029 | J | | <0.004 | U | | <0.004 | U | | <0.0039 | U | | <0.0039 | U | | <0.0039 | U | | 0.0044 | J | | <0.0046 | U | | <0.0045 | U | |
| | | VMP-15-5-102512 | 10/25/2012 | 0.0024 | J | | <0.006 | U | | <0.006 | U | | <0.0059 | U | | <0.0059 | U | | <0.0059 | U | | 0.0042 | J | | <0.0069 | U | | <0.0067 | U | |
| | | VMP-15-5-020513 | 2/5/2013 | 0.002 | J | | <0.0058 | U | | <0.0058 | U | | <0.0057 | U | | <0.0057 | U | | <0.0057 | U | | <0.05 | J | U | <0.0067 | U | | <0.0066 | U | |
| | 21.5 ft | VMP 15-21.5-091410 | 9/14/2010 | <0.68 | U | | <0.55 | U | | <0.55 | U | | <0.54 | U | | <0.54 | U | | <0.54 | U | | <0.48 | U | | <0.63 | U | | <0.62 | U | |
| | | VMP-15-21.5-113010 | 11/30/2010 | <0.79 | U | | <0.65 | U | | <0.65 | U | | <0.64 | U | | <0.64 | U | | <0.64 | U | | <0.56 | U | | <0.74 | U | | <0.73 | U | |
| | | VMP-15-21.5-021611 | 2/16/2011 | <0.55 | U | | <0.45 | U | | <0.45 | U | | <0.44 | U | | <0.44 | U | | <0.44 | U | | <0.39 | U | | <0.52 | U | | <0.51 | U | |
| | | VMP-15-21.5-042011 | 4/20/2011 | <0.87 | U | | <0.71 | U | | <0.71 | U | | <0.7 | U | | <0.7 | U | | <0.7 | U | | <0.61 | U | | <0.81 | U | | <0.8 | U | |
| | | VMP-15-21.5-080811 | 8/8/2011 | <0.7 | U | | <0.57 | U | | <0.57 | U | | <0.56 | U | | <0.56 | U | | <0.56 | U | | 0.58 | | | <0.65 | U | | <0.64 | U | |
| | | VMP-15-21.5-111511 | 11/15/2011 | <0.56 | U | UJ | <0.46 | U | | <0.46 | U | | <0.45 | U | | <0.45 | U | | <0.45 | U | | <0.39 | U | | <0.52 | U | | <0.51 | U | |
| | | VMP-15-21.5-020112 | 2/1/2012 | <0.42 | U | | <0.34 | U | | <0.34 | U | | <0.33 | U | | <0.33 | U | | <0.33 | U | | <0.29 | U | | <0.39 | U | | <0.38 | U | |
| | | VMP-15-21.5-042412 | 4/24/2012 | <0.18 | U | | <0.15 | U | | <0.15 | U | | <0.14 | U | | <0.14 | U | | <0.14 | U | | <0.13 | U | | <0.17 | U | | <0.17 | U | |
| | | VMP-15-21.5-072512 | 7/25/2012 | <0.66 | U | | <0.54 | U | | <0.54 | U | | <0.52 | U | | <0.52 | U | | <0.52 | U | | 0.31 | J | | <0.61 | U | | <0.6 | U | |
| | | VMP-15-21.5-102512 | 10/25/2012 | <1.1 | U | | <0.88 | U | | <0.88 | U | | <0.86 | U | | <0.86 | U | | <0.86 | U | | <0.75 | U | | <1 | U | | <0.98 | U | |
| | | VMP-15-21.5-102512-Dup | 10/25/2012 | <1.1 | U | | <0.9 | U | | <0.9 | U | | <0.88 | U | | <0.88 | U | | <0.88 | U | | <0.77 | U | | <1 | U | | <1 | U | |
| | | VMP-15-21.5-020713 | 2/7/2013 | <0.027 | U | | <0.022 | U | | <0.022 | U | | <0.022 | U | | <0.022 | U | | <0.022 | U | | <0.19 | U | | <0.025 | U | | <0.025 | U | |
| | 25.5 ft | VMP 15-25.5-091410 | 9/14/2010 | 0.002 | J | | <0.0052 | U | | <0.0052 | U | | <0.0051 | U | | <0.0051 | U | | <0.0051 | U | | 0.0026 | J | | <0.006 | U | | <0.0058 | U | |
| | | VMP-15-25.5-021611 | 2/16/2011 | <0.085 | U | | <0.07 | U | | <0.07 | U | | <0.068 | U | | <0.068 | U | | <0.068 | U | | <0.06 | U | | <0.079 | U | | <0.078 | U | |
| | | VMP-15-25.5-042011 | 4/20/2011 | <0.07 | U | | <0.057 | U | | <0.057 | U | | <0.056 | U | | <0.056 | U | | <0.056 | U | | <0.049 | U | UJ | <0.065 | U | | <0.064 | U | |
| | | VMP-15-25.5-042011-DUP | 4/20/2011 | <0.065 | U | | <0.053 | U | | <0.053 | U | | <0.052 | U | | <0.052 | U | | <0.052 | U | | 0.15 | | J | <0.061 | U | | <0.06 | U | |
| | | VMP-15-25.5-080811 | 8/8/2011 | <0.07 | U | | <0.057 | U | | <0.057 | U | | <0.056 | U | | <0.056 | U | | <0.056 | U | | <0.049 | U | | <0.065 | U | | <0.064 | U | |
| | | VMP-15-25.5-111511 | 11/15/2011 | <0.021 | U | UJ | <0.018 | U | | <0.018 | U | | <0.017 | U | | <0.017 | U | | <0.017 | U | | 0.004 | J | | <0.02 | U | | <0.02 | U | |
| | | VMP-15-25.5-073112 | 7/31/2012 | <0.045 | U | | <0.037 | U | | <0.037 | U | | <0.036 | U | | <0.036 | U | | <0.036 | U | | 0.0062 | J | | <0.042 | U | | <0.042 | U | |
| | | VMP-15-25.5-102512 | 10/25/2012 | <0.0073 | U | | <0.006 | U | | <0.006 | U | | <0.0059 | U | | <0.0059 | U | | <0.0059 | U | | <0.052 | U | | <0.0069 | U | | <0.0067 | U | |
| | | VMP-15-25.5-021213 | 2/12/2013 | <0.22 | U | | <0.18 | U | | <0.18 | U | | <0.18 | U | | <0.18 | U | | <0.18 | U | | 0.23 | | | <0.21 | U | | <0.2 | U | |
| | 29 ft | VMP-15-29-073112 | 7/31/2012 | <0.19 | U | | <0.16 | U | | <0.16 | U | | <0.16 | U | | <0.16 | U | | <0.16 | U | | <0.14 | U | | <0.18 | U | | <0.18 | U | |
| | | VMP-15-29-102512 | 10/25/2012 | <0.015 | U | | <0.012 | U | | <0.012 | U | | <0.012 | U | | <0.012 | U | | <0.012 | U | | <0.11 | U | | <0.014 | U | | <0.014 | U | |
| | | VMP-15-29-021213 | 2/12/2013 | <0.13 | U | | <0.11 | U | | <0.11 | U | | <0.11 | U | | <0.11 | U | | <0.11 | U | | <0.093 | U | | <0.12 | U | | <0.12 | U | |

SEE LAST PAGE OF TABLE FOR NOTES

**TABLE 6**
**CUMULATIVE SUMMARY OF SOIL VAPOR ANALYTICAL DETECTIONS AND SCREENING RESULTS: PUBLIC WORKS YARD AND WRR - VOCS**

| Location | Depth | Sample ID | Sample Date | Dichlorodifluoromethane | | | 1,1-Dichloroethane | | | 1,2-Dichloroethane | | | 1,1-Dichloroethene | | | cis-1,2-Dichloroethene | | | trans-1,2-Dichloroethene | | | Dichloromethane (Methylene | | | 1,2-Dichloropropane | | | cis-1,3-Dichloropropene | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | | | | 4200 | | | 0.81 | | | 1600 | | | 1100000 | | | 510 | | | 45 | | | 0.46 | | | 6.2 | | |
| | | | | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals |
| VMP-16 | 5 ft | VMP-16-5-090210 | 9/2/2010 | <12 | U | | <9.6 | U | | <9.6 | U | | <9.4 | U | | <9.4 | U | | <9.4 | U | | <8.3 | U | | <11 | U | | <11 | U | |
| | | VMP-16-5-112910 | 11/29/2010 | <5.4 | U | | <4.4 | U | | <4.4 | U | | <4.3 | U | | <4.3 | U | | <4.3 | U | | <3.8 | U | | <5 | U | | <4.9 | U | |
| | | VMP-16-5-021511 | 2/15/2011 | <3.3 | U | | <2.7 | U | | <2.7 | U | | <2.6 | U | | <2.6 | U | | <2.6 | U | | <2.3 | U | | <3 | U | | <3 | U | |
| | | VMP-16-5-042211 | 4/22/2011 | <4.4 | U | | <3.6 | U | | <3.6 | U | | <3.5 | U | | <3.5 | U | | <3.5 | U | | <3 | U | | <4.1 | U | | <4 | U | |
| | | VMP-16-5-080511 | 8/5/2011 | <1.4 | U | | <1.1 | U | | <1.1 | U | | <1.1 | U | | <1.1 | U | | <1.1 | U | | <0.98 | U | | <1.3 | U | | <1.3 | U | |
| | | VMP-16-5-042512 | 4/25/2012 | <4.7 | U | | <3.9 | U | | <3.9 | U | | <3.8 | U | | <3.8 | U | | <3.8 | U | | 0.82 | J | | <4.4 | U | | <4.3 | U | |
| | | VMP-16-5-073012 | 7/30/2012 | <4.4 | U | | <3.6 | U | | <3.6 | U | | <3.5 | U | | <3.5 | U | | <3.5 | U | | 0.31 | J | J | <4.1 | U | | <4.1 | U | |
| | | VMP-16-5-102512 | 10/25/2012 | <3.5 | U | | <2.8 | U | | <2.8 | U | | <2.8 | U | | <2.8 | U | | <2.8 | U | | <2.4 | U | | <3.2 | U | | <3.2 | U | |
| | | VMP-16-5-021413 | 2/14/2013 | <0.54 | U | | <0.44 | U | | <0.44 | U | | <0.44 | U | | <0.44 | U | | <0.44 | U | | 0.24 | J | J | 3.1 | | J | <0.5 | U | |
| | 13.5 ft | VMP-16-13.5-090210 | 9/2/2010 | <12 | U | | <10 | U | | <10 | U | | <9.8 | U | | <9.8 | U | | <9.8 | U | | 2.1 | J | | <11 | U | | <11 | U | |
| | | VMP-16-13.5-090210-DUP | 9/2/2010 | <12 | U | | <10 | U | | <10 | U | | <9.8 | U | | <9.8 | U | | <9.8 | U | | <8.6 | U | | <11 | U | | <11 | U | |
| | | VMP-16-13.5-112910 | 11/29/2010 | <35 | U | | <28 | U | | <28 | U | | <28 | U | | <28 | U | | <28 | U | | <24 | U | | <32 | U | | <32 | U | |
| | | VMP-16-13.5-021611 | 2/16/2011 | <6.6 | U | | <5.4 | U | | <5.4 | U | | <5.3 | U | | <5.3 | U | | <5.3 | U | | <4.7 | U | | <6.2 | U | | <6.1 | U | |
| | | VMP-16-13.5-021611-DUP | 2/16/2011 | <6.5 | U | | <5.3 | U | | <5.3 | U | | <5.2 | U | | <5.2 | U | | <5.2 | U | | <4.6 | U | | <6.1 | U | | <6 | U | |
| | | VMP-16-13.5-042211 | 4/22/2011 | <7 | U | | <5.7 | U | | <5.7 | U | | <5.6 | U | | <5.6 | U | | <5.6 | U | | <4.9 | U | | <6.6 | U | | <6.4 | U | |
| | | VMP-16-13.5-080511 | 8/5/2011 | <0.68 | U | UJ | <0.56 | U | UJ | <0.56 | U | UJ | <0.55 | U | UJ | <0.55 | U | UJ | <0.55 | U | UJ | <0.48 | U | UJ | <0.64 | U | UJ | <0.63 | U | UJ |
| | | VMP-16-13.5-042512 | 4/25/2012 | <0.75 | U | | <0.62 | U | | <0.62 | U | | <0.6 | U | | <0.6 | U | | <0.6 | U | | <0.53 | U | | <0.7 | U | | <0.69 | U | |
| | | VMP-16-13.5-073012 | 7/30/2012 | <23 | U | | <18 | U | | <18 | U | | <18 | U | | <18 | U | | <18 | U | | 4.8 | J | | <21 | U | | <21 | U | |
| | | VMP-16-13.5-102512 | 10/25/2012 | <70 | U | | <57 | U | | <57 | U | | <56 | U | | <56 | U | | <56 | U | | <49 | U | | <65 | U | | <64 | U | |
| | | VMP-16-13.5-021413 | 2/14/2013 | <11 | U | | <9.1 | U | | <9.1 | U | | 1.7 | J | J | <8.9 | U | | <8.9 | U | | 12 | | J | 48 | | J | <10 | U | |
| | 19 ft | VMP-16-19-090210 | 9/2/2010 | <12 | U | | <10 | U | | <10 | U | | <9.8 | U | | <9.8 | U | | <9.8 | U | | <8.6 | U | | <11 | U | | <11 | U | |
| | | VMP-16-19-112910 | 11/29/2010 | <27 | U | | <22 | U | | <22 | U | | <21 | U | | <21 | U | | <21 | U | | <19 | U | | <25 | U | | <24 | U | |
| | | VMP-16-19-021611 | 2/16/2011 | <6.4 | U | | <5.2 | U | | <5.2 | U | | <5.1 | U | | <5.1 | U | | <5.1 | U | | <4.5 | U | | <6 | U | | <5.8 | U | |
| | | VMP-16-19-042711 | 4/27/2011 | <6.5 | U | | <5.3 | U | | <5.3 | U | | <5.2 | U | | <5.2 | U | | <5.2 | U | | 1 | J | | <6.1 | U | | <6 | U | |
| | | VMP-16-19-042711-DUP | 4/27/2011 | <6.4 | U | | <5.2 | U | | <5.2 | U | | <5.1 | U | | <5.1 | U | | <5.1 | U | | 0.54 | J | | <6 | U | | <5.8 | U | |
| | | VMP-16-19-042512 | p | <17 | U | | <14 | U | | <14 | U | | <14 | U | | <14 | U | | <14 | U | | 2.5 | J | | <16 | U | | <16 | U | |
| | | VMP-16-19-073012 | 7/30/2012 | <16 | U | | <13 | U | | <13 | U | | <12 | U | | <12 | U | | <12 | U | | 1.7 | J | | <15 | U | | <14 | U | |
| | | VMP-16-19-102512 | 10/25/2012 | <65 | U | | <53 | U | | <53 | U | | <52 | U | | <52 | U | | <52 | U | | <46 | U | | <61 | U | | <60 | U | |
| | | VMP-16-19-021413 | 2/14/2013 | <6.5 | U | | <5.3 | U | | <5.3 | U | | <5.2 | U | | <5.2 | U | | <5.2 | U | | 3.4 | J | J | 21 | | J | <6 | U | |
| | 31 ft | VMP-16-31-090310 | 9/3/2010 | 0.0018 | J | | <0.0058 | U | | <0.0058 | U | | <0.0057 | U | | <0.0057 | U | | <0.0057 | U | | <0.005 | U | | <0.0067 | U | | <0.0066 | U | |
| | | VMP-16-31-112910 | 11/29/2010 | <27 | U | | <22 | U | | <22 | U | | <22 | U | | <22 | U | | <22 | U | | <19 | U | | <25 | U | | <25 | U | |
| | | VMP-16-31-042512 | 4/25/2012 | <21 | U | | <17 | U | | <17 | U | | <17 | U | | <17 | U | | <17 | U | | 3.4 | J | | <20 | U | | <19 | U | |
| | | VMP-16-31-073012 | 7/30/2012 | <17 | U | | <14 | U | | <14 | U | | <14 | U | | <14 | U | | <14 | U | | 5.2 | J | | <16 | U | | <16 | U | |
| | | VMP-16-31-102512 | 10/25/2012 | <81 | U | | <66 | U | | <66 | U | | <65 | U | | <65 | U | | <65 | U | | <57 | U | | <76 | U | | <74 | U | |
| | | VMP-16-31-021813 | 2/18/2013 | <25 | U | | <20 | U | | <20 | U | | <20 | U | | <20 | U | | <20 | U | | 12 | J | | 25 | | | <23 | U | |
| VMP-17 | 5 ft | VMP-17-5 | 6/21/2010 | 0.0022 | J | | <0.005 | U | | <0.005 | U | | <0.005 | U | | <0.005 | U | | <0.005 | U | | <0.005 | U | | <0.006 | U | | <0.006 | U | |
| | | VMP-17-5-DUP | 6/21/2010 | 0.002 | J | | <0.006 | U | | <0.006 | U | | <0.005 | U | | <0.005 | U | | <0.005 | U | | <0.005 | U | | <0.006 | U | | <0.006 | U | |
| | | VMP-17-5-090110 | 9/1/2010 | 0.0026 | J | | <0.0054 | U | | <0.0054 | U | | <0.0053 | U | | <0.0053 | U | | <0.0053 | U | | <0.0047 | U | | <0.0062 | U | | <0.0061 | U | |
| | | VMP-17-5-112210 | 11/22/2010 | 0.0022 | J | | <0.0054 | U | | <0.0054 | U | | <0.0053 | U | | <0.0053 | U | | <0.0053 | U | | <0.0047 | U | | <0.0062 | U | | <0.0061 | U | |
| | | VMP-17-5-020711 | 2/7/2011 | 0.0013 | J | | <0.0051 | U | | <0.0051 | U | | <0.005 | U | | <0.005 | U | | <0.005 | U | | 0.001 | J | | <0.0058 | U | | <0.0057 | U | |
| | | VMP-17-5-040611 | 4/6/2011 | <0.025 | U | | <0.02 | U | | <0.02 | U | | <0.02 | U | | <0.02 | U | | <0.02 | U | | <0.018 | U | | <0.023 | U | | <0.023 | U | |
| | | VMP-17-5-080111 | 8/1/2011 | <0.095 | U | | <0.078 | U | | <0.078 | U | | <0.076 | U | | <0.076 | U | | <0.076 | U | | <0.067 | U | | <0.089 | U | | <0.087 | U | |
| | | VMP-17-5-110711 | 11/7/2011 | 0.0018 | J | | <0.0035 | U | | <0.0035 | U | | <0.0034 | U | | <0.0034 | U | | <0.0034 | U | | <0.003 | J | U | <0.004 | U | | <0.0039 | U | |
| | | VMP-17-5-012612 | 1/26/2012 | 0.0022 | J | | <0.0036 | U | | <0.0036 | U | | <0.0035 | U | | 0.0092 | | | <0.0035 | U | | 0.0011 | J | | <0.0041 | U | | <0.0041 | U | |
| | | VMP-17-5-041112 | 4/11/2012 | 0.0017 | J | | <0.0037 | U | | <0.0037 | U | | <0.0036 | U | | <0.0036 | U | | <0.0036 | U | | <0.032 | J | U | 0.00079 | J | | <0.0042 | U | |
| | | VMP-17-5-071112 | 7/11/2012 | 0.0026 | J | | <0.004 | U | | <0.004 | U | | <0.0039 | U | | <0.0039 | U | | <0.0039 | U | | <0.034 | U | | <0.0045 | U | | <0.0044 | U | |
| | | VMP-17-5-100912 | 10/9/2012 | 0.0021 | J | | <0.0061 | U | | <0.0061 | U | | <0.006 | U | | <0.006 | U | | <0.006 | U | | 0.0023 | J | | <0.007 | U | | <0.0069 | U | |
| | | VMP-17-5-013113 | 1/31/2013 | <0.026 | U | | <0.021 | U | | <0.021 | U | | <0.021 | U | | <0.021 | U | | <0.021 | U | | <0.18 | U | | <0.024 | U | | <0.024 | U | |
| | | VMP-17-5-013113-DUP | 1/31/2013 | <0.026 | U | | <0.021 | U | | <0.021 | U | | <0.021 | U | | <0.021 | U | | <0.021 | U | | <0.18 | U | | <0.024 | U | | <0.024 | U | |
| VMP-25 | 5 ft | VMP-25-5-031511 | 3/15/2011 | <0.06 | U | | <0.049 | U | | <0.049 | U | | <0.048 | U | | <0.048 | U | | <0.048 | U | | <0.042 | U | | <0.056 | U | | <0.055 | U | |
| | | VMP-25-5-040811 | 4/8/2011 | <0.027 | U | | <0.022 | U | | <0.022 | U | | <0.022 | U | | <0.022 | U | | <0.022 | U | | 0.0095 | J | | <0.025 | U | | <0.025 | U | |
| | | VMP-25-5-080911 | 8/9/2011 | 0.0025 | J | | <0.0047 | U | | 0.0022 | J | | <0.0046 | U | | <0.0046 | U | | <0.0046 | U | | 0.026 | | | 0.0029 | J | | <0.0053 | U | |
| | | VMP-25-5-111711 | 11/17/2011 | 0.0014 | J | J | <0.0034 | U | | <0.0034 | U | | <0.0033 | U | | <0.0033 | U | | <0.0033 | U | | 0.001 | J | | <0.0039 | U | | <0.0038 | U | |
| | | VMP-25-5-013112 | 1/31/2012 | <0.03 | U | | <0.025 | U | | <0.025 | U | | <0.024 | U | | <0.024 | U | | <0.024 | U | | <0.021 | U | | <0.028 | U | | <0.028 | U | |
| | | VMP-25-5-042512 | 4/25/2012 | 0.0023 | J | | <0.0039 | U | | <0.0039 | U | | <0.0038 | U | | <0.0038 | U | | <0.0038 | U | | <0.033 | J | U | <0.0044 | U | | <0.0043 | U | |
| | | VMP-25-5-072612 | 7/26/2012 | <0.016 | U | | <0.013 | U | | <0.013 | U | | <0.013 | U | | <0.013 | U | | <0.013 | U | | <0.11 | J | U | <0.015 | U | | <0.015 | U | |
| | | VMP-25-5-102612 | 10/26/2012 | <0.0066 | U | | <0.0054 | U | | <0.0054 | U | | <0.0053 | U | | <0.0053 | U | | <0.0053 | U | | <0.047 | U | | <0.0062 | U | | <0.0061 | U | |
| | | VMP-25-5-030613 | 3/6/2013 | 0.0017 | J | | <0.0052 | U | | <0.0052 | U | | <0.0051 | U | | <0.0051 | U | | <0.0051 | U | | <0.045 | J | U | <0.0059 | U | | <0.0058 | U | |
| | 21 ft | VMP-25-21-031511 | 3/15/2011 | <12 | U | | <9.6 | U | | <9.6 | U | | <9.4 | U | | <9.4 | U | | <9.4 | U | | 2.7 | J | | <11 | U | | <11 | U | |
| | | VMP-25-21-031511-DUP | 3/15/2011 | <15 | U | | <12 | U | | <12 | U | | <12 | U | | <12 | U | | <12 | U | | <10 | U | | <14 | U | | <14 | U | |
| | | VMP-25-21-040811 | 4/8/2011 | <120 | U | | <100 | U | | <100 | U | | <100 | U | | <100 | U | | <100 | U | | <88 | U | | <120 | U | | <110 | U | |
| | | VMP-25-21-040811-DUP | 4/8/2011 | <130 | U | | <100 | U | | <100 | U | | <100 | U | | <100 | U | | <100 | U | | <88 | U | | <120 | U | | <120 | U | |
| | | VMP-25-21-080911 | 8/9/2011 | <41 | U | | <33 | U | | <33 | U | | 22 | J | | 11 | J | | <33 | U | | <29 | U | | <38 | U | | <37 | U | |
| | | VMP-25-21-111711 | 11/17/2011 | <56 | U | UJ | <46 | U | | <46 | U | | <45 | U | | <45 | U | | <45 | U | | 15 | J | | <52 | U | | <51 | U | |
| | | VMP-25-21-111711-DUP | 11/17/2011 | <82 | U | UJ | <67 | U | | <67 | U | | <66 | U | | <66 | U | | <66 | U | | 18 | J | | <77 | U | | <75 | U | |
| | | VMP-25-21-013112 | 1/31/2012 | <29 | U | | <24 | U | | <24 | U | | <23 | U | | <23 | U | | <23 | U | | <20 | U | | <27 | U | | <26 | U | |
| | | VMP-25-21-013112-DUP | 2/1/2012 | <27 | U | | <22 | U | | <22 | U | | <22 | U | | <22 | U | | <22 | U | | <19 | U | | <25 | U | | <25 | U | |
| | | VMP-25-21-042512 | 4/25/2012 | <18 | U | | <15 | U | | <15 | U | | <15 | U | | <15 | U | | <15 | U | | <13 | U | | <17 | U | | <17 | U | |
| | | VMP-25-21-072612 | 7/26/2012 | <31 | U | | <26 | U | | <25 | U | | <25 | U | | <25 | U | | <25 | U | | 8.6 | J | | <29 | U | | <28 | U | |
| | | VMP-25-21-102612 | 10/26/2012 | <190 | U | | <150 | U | | <150 | U | | <150 | U | | <150 | U | | <150 | U | | 15 | J | | <170 | U | | <170 | U | |
| | | VMP-25-21-030613 | 3/6/2013 | <47 | U | | 7.7 | J | | <39 | U | | <38 | U | | <38 | U | | <38 | U | | 9.1 | J | | <44 | U | | <44 | U | |
| | 31 ft | VMP-25-31-030613 | 3/6/2013 | <63 | U | | <51 | U | | <51 | U | | <50 | U | | <50 | U | | <50 | U | | 30 | J | | <59 | U | | <58 | U | |

SEE LAST PAGE OF TABLE FOR NOTES

**TABLE 6**
**CUMULATIVE SUMMARY OF SOIL VAPOR ANALYTICAL DETECTIONS AND SCREENING RESULTS: PUBLIC WORKS YARD AND WRR - VOCS**

| Location | Depth | Sample ID | Sample Date | Dichlorodifluoromethane | | | 1,1-Dichloroethane | | | 1,2-Dichloroethane | | | 1,1-Dichloroethene | | | cis-1,2-Dichloroethene | | | trans-1,2-Dichloroethene | | | Dichloromethane (Methylene | | | 1,2-Dichloropropane | | | cis-1,3-Dichloropropene | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | | | | 4200 | | | 0.81 | | | 1600 | | | 1100000 | | | 510 | | | 45 | | | 0.46 | | | 6.2 | | |
| | | | | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals |
| VMP-29 | 10 ft | VMP-29-10-073012 | 7/30/2012 | <0.052 | U | | <0.043 | U | | <0.043 | U | | <0.042 | U | | <0.042 | U | | <0.042 | U | | <0.37 | U | | <0.049 | U | | <0.048 | U | |
| | | VMP-29-10-100812 | 10/8/2012 | <0.093 | U | | <0.076 | U | | <0.076 | U | | <0.074 | U | | <0.074 | U | | <0.074 | U | | <0.65 | U | | <0.087 | U | | <0.085 | U | |
| | | VMP-29-10-020613 | 2/6/2013 | 0.0025 | J | | <0.0057 | U | | <0.0057 | U | | <0.0056 | U | | <0.0056 | U | | <0.0056 | U | | <0.049 | U | | <0.0065 | U | | <0.0064 | U | |
| | 20 ft | VMP-29-20-073012 | 7/30/2012 | <0.62 | U | | <0.51 | U | | <0.51 | U | | <0.5 | U | | <0.5 | U | | <0.5 | U | | <0.44 | U | | <0.58 | U | | <0.57 | U | |
| | | VMP-29-20-073012-Dup | 7/30/2012 | <0.58 | U | | <0.47 | U | | <0.47 | U | | <0.46 | U | | <0.46 | U | | <0.46 | U | | <0.41 | U | | <0.54 | U | | <0.53 | U | |
| | | VMP-29-20-100812 | 10/8/2012 | <0.093 | U | | <0.076 | U | | <0.076 | U | | <0.074 | U | | <0.074 | U | | <0.074 | U | | <0.65 | U | | <0.087 | U | | <0.085 | U | |
| | | VMP-29-20-020613 | 2/6/2013 | 0.0022 | J | | <0.0056 | U | | <0.0056 | U | | <0.0055 | U | | <0.0055 | U | | <0.0055 | U | | <0.048 | J | U | <0.0064 | U | | <0.0063 | U | |
| | 30 ft | VMP-29-30-073012 | 7/30/2012 | <0.1 | U | | <0.083 | U | | <0.083 | U | | <0.082 | U | | <0.082 | U | | <0.082 | U | | <0.072 | U | | <0.095 | U | | <0.093 | U | |
| | | VMP-29-30-100812 | 10/8/2012 | <0.46 | U | | <0.37 | U | | <0.37 | U | | <0.37 | U | | <0.37 | U | | <0.37 | U | | 0.24 | J | | <0.43 | U | | <0.42 | U | |
| | | VMP-29-30-020613 | 2/6/2013 | 0.0024 | J | | <0.0058 | U | | <0.0058 | U | | <0.0057 | U | | <0.0057 | U | | <0.0057 | U | | <0.05 | J | U | <0.0067 | U | | <0.0066 | U | |
| VMP-30 | 10 ft | VMP-30-10-073012 | 7/30/2012 | <0.18 | U | | <0.15 | U | | <0.15 | U | | <0.15 | U | | <0.15 | U | | <0.15 | U | | <0.13 | U | | <0.17 | U | | <0.17 | U | |
| | | VMP-30-10-100812 | 10/8/2012 | 0.0022 | J | | <0.0057 | U | | <0.0057 | U | | <0.0056 | U | | <0.0056 | U | | <0.0056 | U | | 0.002 | J | | <0.0065 | U | | <0.0064 | U | |
| | | VMP-30-10-020613 | 2/6/2013 | 0.0022 | J | | <0.0053 | U | | <0.0053 | U | | <0.0052 | U | | <0.0052 | U | | <0.0052 | U | | <0.046 | J | U | <0.0061 | U | | <0.006 | U | |
| | 20 ft | VMP-30-20-073012 | 7/30/2012 | <0.79 | U | | <0.64 | U | | <0.64 | U | | <0.63 | U | | <0.63 | U | | <0.63 | U | | 0.11 | J | | <0.73 | U | | <0.72 | U | |
| | | VMP-30-20-100812 | 10/8/2012 | <0.29 | U | | <0.23 | U | | <0.23 | U | | <0.23 | U | | <0.23 | U | | <0.23 | U | | 0.25 | J | | <0.27 | U | | <0.26 | U | |
| | | VMP-30-20-020613 | 2/6/2013 | 0.0022 | J | | <0.0053 | U | | <0.0053 | U | | <0.0052 | U | | <0.0052 | U | | <0.0052 | U | | <0.046 | J | U | <0.0061 | U | | <0.006 | U | |
| | 30 ft | VMP-30-30-073012 | 7/30/2012 | <0.81 | U | | <0.66 | U | | <0.66 | U | | <0.65 | U | | <0.65 | U | | <0.65 | U | | 0.16 | J | | <0.76 | U | | <0.74 | U | |
| | | VMP-30-30-100812 | 10/8/2012 | <0.6 | U | | <0.49 | U | | <0.49 | U | | <0.48 | U | | <0.48 | U | | <0.48 | U | | 0.28 | J | | <0.56 | U | | <0.55 | U | |
| | | VMP-30-30-020613 | 2/6/2013 | <0.022 | U | | <0.018 | U | | <0.018 | U | | <0.017 | U | | <0.017 | U | | <0.017 | U | | <0.15 | U | | <0.02 | U | | <0.02 | U | |
| VMP-41 | 10 ft | VMP-41-10-072712 | 7/27/2012 | <0.006 | U | | <0.0049 | U | | <0.0049 | U | | <0.0048 | U | | <0.0048 | U | | <0.0048 | U | | <0.042 | J | U | <0.0056 | U | | <0.0055 | U | |
| | | VMP-41-10-100912 | 10/9/2012 | 0.0032 | J | | <0.006 | U | | <0.006 | U | | <0.0059 | U | | <0.0059 | U | | <0.0059 | U | | 0.0023 | J | | <0.0068 | U | | <0.0067 | U | |
| | | VMP-41-10-012913 | 1/29/2013 | 0.0033 | J | | <0.006 | U | | <0.006 | U | | <0.0059 | U | | <0.0059 | U | | <0.0059 | U | | <0.051 | J | U | <0.0068 | U | | <0.0067 | U | |
| | 20 ft | VMP-41-20-072712 | 7/27/2012 | 0.003 | J | | <0.0038 | U | | <0.0038 | U | | <0.0037 | U | | <0.0037 | U | | <0.0037 | U | | <0.032 | J | U | <0.0043 | U | | <0.0042 | U | |
| | | VMP-41-20-072712-Dup | 7/27/2012 | 0.0032 | J | | <0.0039 | U | | <0.0039 | U | | <0.0038 | U | | <0.0038 | U | | <0.0038 | U | | <0.033 | J | U | <0.0044 | U | | <0.0043 | U | |
| | | VMP-41-20-100912 | 10/9/2012 | 0.0026 | J | | <0.0058 | U | | <0.0058 | U | | <0.0057 | U | | <0.0057 | U | | <0.0057 | U | | 0.0042 | J | | <0.0067 | U | | <0.0066 | U | |
| | | VMP-41-20-100912-Dup | 10/9/2012 | 0.0028 | J | | <0.006 | U | | <0.006 | U | | <0.0059 | U | | <0.0059 | U | | <0.0059 | U | | <0.051 | J | U | <0.0068 | U | | <0.0067 | U | |
| | | VMP-41-20-012913 | 1/29/2013 | 0.0027 | J | | <0.0061 | U | | <0.0061 | U | | <0.006 | U | | <0.006 | U | | <0.006 | U | | <0.053 | J | U | <0.007 | U | | <0.0069 | U | |
| | 30 ft | VMP-41-30-072712 | 7/27/2012 | 0.003 | J | | <0.0039 | U | | <0.0039 | U | | <0.0038 | U | | <0.0038 | U | | <0.0038 | U | | <0.033 | J | U | <0.0044 | U | | <0.0043 | U | |
| | | VMP-41-30-100912 | 10/9/2012 | 0.0031 | J | | <0.0063 | U | | <0.0063 | U | | <0.0062 | U | | <0.0062 | U | | <0.0062 | U | | <0.054 | J | U | <0.0072 | U | | <0.007 | U | |
| | | VMP-41-30-012913 | 1/29/2013 | 0.0032 | J | | <0.0057 | U | | <0.0057 | U | | <0.0056 | U | | <0.0056 | U | | <0.0056 | U | | <0.049 | J | U | <0.0065 | U | | <0.0064 | U | |
| VMP-55 | 20 ft | VMP-55-20-021513 | 2/15/2013 | <17 | U | | <14 | U | | <14 | U | | <14 | U | | <14 | U | | <14 | U | | 14 | | | 19 | | | <16 | U | |

SEE LAST PAGE OF TABLE FOR NOTES

**TABLE 6**
**CUMULATIVE SUMMARY OF SOIL VAPOR ANALYTICAL DETECTIONS AND SCREENING RESULTS: PUBLIC WORKS YARD AND WRR - VOCS**

| Location | Depth | Sample ID | Sample Date | trans-1,3-Dichloropropene 6.2 | | | 1,4-Dioxane 2.3 | | | Ethanol | | | Ethylbenzene 8300 | | | 4-Ethyltoluene | | | Freon 113 | | | Freon 114 | | | Heptane | | | Hexachlorobutadiene | | | Hexane | | | 2-Hexanone (Methyl N-Butyl | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals |
| VMP-10 | 5 ft | VMP-10-5-090710 | 9/7/2010 | <0.006 | U | | <0.019 | U | | 0.015 | | | 0.009 | | | 0.0072 | | | <0.01 | U | | <0.0092 | U | | 0.0071 | | | <0.056 | U | | 0.015 | | | <0.022 | U | |
| | | VMP-10-5-111810 | 11/17/2010 | <0.0055 | U | | <0.017 | U | | 0.004 | J | | 0.0014 | J | | <0.0059 | U | | <0.0093 | U | | <0.0084 | U | | 0.012 | | | <0.052 | U | | 0.0072 | | | <0.02 | U | |
| | | VMP-10-5-021011 | 2/10/2011 | <0.0054 | U | | <0.017 | U | | <0.009 | U | | 0.0029 | J | | 0.0013 | J | | <0.0091 | U | | <0.0083 | U | | 0.044 | | | <0.051 | U | | 0.11 | | | <0.019 | U | |
| | | VMP-10-5-040511 | 4/5/2011 | <0.005 | U | | <0.016 | U | | 0.028 | | | 0.0018 | J | | 0.005 | J | | <0.0084 | U | | <0.0077 | U | | 0.0051 | | | <0.047 | U | | 0.0066 | | | <0.018 | U | |
| | | VMP-10-5-072911 | 7/29/2011 | <0.0061 | U | | 0.041 | | | 0.05 | | | 0.0012 | J | | <0.0066 | J | U | <0.01 | U | | <0.0094 | U | | <0.0055 | U | | <0.057 | U | | 0.0036 | J | | <0.022 | J | U |
| | | VMP-10-5-110411 | 11/4/2011 | <0.0032 | U | | <0.01 | U | | 0.011 | | | 0.00086 | J | | <0.0034 | J | U | <0.0053 | U | | <0.0048 | U | | <0.0028 | U | | <0.03 | U | | 0.00062 | J | | 0.00065 | J | |
| | | VMP-10-5-012512 | 1/26/2012 | <0.004 | U | | <0.013 | U | | 0.017 | | | <0.0038 | U | | <0.0043 | U | | <0.0067 | U | | <0.0061 | U | | 0.0022 | J | | <0.037 | U | | 0.0028 | J | | <0.014 | U | |
| | | VMP-10-5-041212 | 4/12/2012 | <0.0043 | U | | <0.014 | U | | 0.025 | | | 0.00077 | J | | <0.0046 | U | | <0.0072 | U | | <0.0066 | U | | 0.0047 | | | <0.04 | U | | 0.013 | | | <0.015 | U | |
| | | VMP-10-5-071312 | 7/13/2012 | <0.0044 | U | | <0.014 | U | | 0.0029 | J | | <0.0042 | J | U | <0.0047 | U | | <0.0074 | U | | <0.0067 | U | | <0.004 | J | U | <0.041 | U | | 0.0017 | J | | <0.016 | U | |
| | | VMP-10-5-101612 | 10/16/2012 | <0.0069 | U | | <0.022 | U | | <0.011 | U | | <0.0066 | U | | <0.0074 | U | | <0.012 | U | | <0.01 | U | | 0.012 | | | <0.065 | U | | 0.028 | | | <0.025 | U | |
| | | VMP-10-5-012913 | 1/29/2013 | <0.0064 | U | | <0.02 | U | | <0.011 | U | | 0.0012 | J | | <0.0069 | J | U | <0.011 | U | | <0.0098 | U | | 0.0048 | J | | <0.06 | U | | 0.0085 | | | <0.023 | U | |
| | | VMP-10-5-012913-DUP | 1/29/2013 | <0.007 | U | | <0.022 | U | | <0.012 | U | | <0.0068 | U | | <0.0076 | U | | <0.012 | U | | <0.011 | U | | 0.0049 | J | | <0.066 | U | | 0.011 | | | <0.025 | U | |
| | 10 ft | VMP-10-10-090710 | 9/7/2010 | <0.006 | U | | 0.0077 | J | | 0.0079 | J | | <0.0057 | U | | <0.0065 | U | | <0.01 | U | | <0.0092 | U | | 0.0017 | J | | <0.056 | U | | 0.0016 | J | | <0.022 | U | |
| | | VMP-10-10-111810 | 11/17/2010 | <0.0058 | U | | 0.0042 | J | | 0.0096 | J | | 0.0014 | J | | <0.0063 | U | | <0.0099 | U | | <0.009 | U | | 0.01 | | | <0.055 | U | | 0.0096 | | | <0.021 | U | |
| | | VMP-10-10-021111 | 2/11/2011 | <0.0046 | U | | <0.014 | U | | 0.1 | | | 0.0017 | J | | <0.005 | J | U | <0.0077 | U | | <0.0071 | U | | 0.006 | | | <0.043 | U | | 0.0049 | | | <0.016 | U | |
| | | VMP-10-10-040611 | 4/6/2011 | <0.006 | J | U | <0.019 | U | | 0.013 | | | 0.00094 | J | | <0.0065 | J | U | <0.01 | U | | <0.0092 | U | | 0.0022 | J | | <0.056 | J | U | 0.0068 | | | <0.022 | U | |
| | | VMP-10-10-072911 | 7/29/2011 | <0.0063 | U | | 0.017 | J | | 0.029 | | | 0.0024 | J | | <0.0068 | J | U | <0.01 | U | | <0.0096 | U | | 0.0027 | J | | <0.059 | U | | 0.0025 | J | | 0.0032 | J | |
| | | VMP-10-10-110411 | 11/4/2011 | <0.0041 | U | | 0.0025 | J | | 0.0095 | | | 0.00097 | J | | 0.0021 | J | | <0.0068 | U | | <0.0062 | U | | 0.0009 | J | | <0.038 | U | | <0.0032 | J | U | 0.00081 | J | |
| | | VMP-10-10-110411-DUP | 11/4/2011 | <0.0041 | U | | <0.013 | U | | 0.016 | | | 0.00091 | J | | 0.0019 | J | | <0.0068 | U | | <0.0062 | U | | 0.0018 | J | | <0.038 | U | | <0.0032 | J | U | 0.0018 | J | |
| | | VMP-10-10-012512 | 1/26/2012 | <0.004 | U | | <0.013 | U | | 0.028 | | J | <0.0038 | U | | <0.0043 | U | | <0.0067 | U | | <0.0061 | U | | <0.0036 | U | | <0.037 | U | | <0.0031 | U | | <0.014 | U | |
| | | VMP-10-10-012512-DUP | 1/26/2012 | <0.0042 | U | | <0.013 | U | | 0.013 | | J | <0.004 | U | | 0.0011 | J | | <0.007 | U | | <0.0064 | U | | <0.0037 | U | | <0.039 | U | | 0.00092 | J | | <0.015 | U | |
| | | VMP-10-10-041112 | 4/11/2012 | <0.0043 | U | | <0.014 | U | | 0.051 | | | 0.0029 | J | | <0.0047 | J | U | <0.0073 | U | | <0.0067 | U | | 0.0045 | | | <0.041 | U | | 0.011 | | | <0.016 | U | |
| | | VMP-10-10-071312 | 7/13/2012 | <0.0043 | U | | <0.014 | U | | 0.038 | | | <0.0041 | J | U | <0.0046 | U | | <0.0072 | J | U | <0.0066 | U | | <0.0038 | J | U | <0.04 | U | | <0.0033 | J | U | <0.015 | U | |
| | | VMP-10-10-101612 | 10/16/2012 | <0.0072 | U | | <0.023 | U | | <0.012 | U | | 0.0032 | J | | <0.0078 | U | | <0.012 | U | | <0.011 | U | | 0.0039 | J | | <0.067 | U | | 0.015 | | | <0.026 | U | |
| | | VMP-10-10-012913 | 1/29/2013 | <0.0057 | U | | <0.018 | U | | 0.0034 | J | | <0.0055 | U | | <0.0062 | U | | <0.0096 | U | | <0.0088 | U | | <0.0052 | U | | <0.054 | U | | 0.0014 | J | | <0.021 | U | |
| | 20 ft | VMP-10-20-090710 | 9/7/2010 | <0.0063 | U | | <0.02 | U | | 0.012 | | J | 0.002 | J | | <0.0068 | U | | <0.01 | U | | <0.0096 | U | | 0.0037 | J | | <0.059 | U | | 0.0061 | | | <0.023 | U | |
| | | VMP-10-20-090710-DUP | 9/7/2010 | <0.0058 | U | | <0.018 | U | | 0.048 | | J | 0.0017 | J | | <0.0063 | U | | <0.0099 | U | | <0.009 | U | | 0.0025 | J | | <0.055 | U | | 0.0043 | J | | <0.021 | U | |
| | | VMP-10-20-111810 | 11/17/2010 | <0.011 | U | | <0.035 | U | | 0.0097 | J | | <0.011 | U | | <0.012 | U | | <0.019 | U | | <0.017 | U | | 0.0048 | J | | <0.1 | U | | 0.0049 | J | | <0.04 | U | |
| | | VMP-10-20-111810-Dup | 11/17/2010 | <0.0056 | U | | <0.018 | U | | 0.017 | | | 0.0015 | J | | <0.0061 | U | | <0.0095 | U | | <0.0086 | U | | 0.013 | | | <0.053 | U | | 0.0097 | | | <0.02 | U | |
| | | VMP-10-20-021111 | 2/11/2011 | <0.0055 | U | | <0.018 | U | | 0.018 | | | <0.0053 | U | | <0.006 | U | | <0.0094 | U | | <0.0085 | U | | 0.0056 | | | <0.052 | U | | 0.0043 | | | <0.02 | U | |
| | | VMP-10-20-040611 | 4/6/2011 | <0.0067 | J | U | <0.021 | U | | 0.05 | | | 0.0026 | J | | <0.0072 | J | U | <0.011 | U | | <0.01 | U | | 0.0036 | J | | <0.063 | J | U | 0.0084 | | | <0.024 | U | |
| | | VMP-10-20-072911 | 7/29/2011 | <0.0062 | U | | <0.02 | U | | 0.062 | | | 0.0014 | J | | 0.0013 | J | | <0.01 | U | | <0.0095 | U | | <0.0056 | U | | <0.058 | U | | 0.003 | J | | <0.022 | J | U |
| | | VMP-10-20-110411 | 11/4/2011 | <0.0041 | U | | <0.013 | U | | 0.085 | | | 0.00094 | J | | 0.0015 | J | | <0.0068 | U | | <0.0062 | U | | 0.002 | J | | <0.038 | U | | 0.0033 | | | 0.00087 | J | |
| | | VMP-10-20-012612 | 1/26/2012 | <0.0038 | U | | <0.012 | U | | 0.0046 | J | | <0.0036 | U | | <0.0041 | U | | <0.0064 | U | | <0.0059 | U | | 0.0026 | J | | <0.036 | U | | 0.011 | | | <0.014 | U | |
| | | VMP-10-20-041212 | 4/12/2012 | <0.0043 | U | | <0.014 | U | | 0.011 | | | 0.00093 | J | | <0.0046 | U | | <0.0072 | U | | <0.0066 | U | | 0.0066 | | | <0.04 | U | | 0.013 | | | <0.015 | U | |
| | | VMP-10-20-071612 | 7/16/2012 | <0.0041 | U | | 0.02 | | | 0.0024 | J | | <0.0039 | J | U | <0.0044 | U | | <0.0068 | U | | <0.0062 | U | | 0.003 | J | | <0.038 | U | | 0.0043 | | | <0.015 | U | |
| | | VMP-10-20-101612 | 10/16/2012 | <0.0072 | U | | <0.023 | U | | 0.0056 | J | | <0.0069 | U | | 0.0067 | J | | <0.012 | U | | <0.011 | U | | <0.0065 | U | | <0.068 | U | | 0.0035 | J | | <0.026 | U | |
| | | VMP-10-20-012913 | 1/29/2013 | <0.0063 | U | | <0.02 | U | | <0.01 | U | | <0.006 | U | | <0.0068 | U | | <0.01 | U | | <0.0096 | U | | <0.0056 | U | | <0.059 | U | | 0.0029 | J | | <0.023 | U | |
| | 30 ft | VMP-10-30-041212 | 4/12/2012 | <0.0044 | U | | <0.014 | U | | 0.04 | | | 0.0016 | J | | <0.0048 | U | | <0.0075 | U | | <0.0068 | U | | 0.0028 | J | | <0.042 | U | | 0.008 | | | <0.016 | U | |
| | | VMP-10-30-071612 | 7/16/2012 | <0.0039 | U | | <0.012 | U | | <0.0065 | U | | <0.0038 | J | U | 0.0011 | J | | <0.0066 | U | | <0.006 | U | | 0.0045 | | | <0.037 | U | | 0.01 | | | <0.014 | U | |
| | | VMP-10-30-101612 | 10/16/2012 | <0.0068 | U | | <0.022 | U | | 0.022 | | | <0.0065 | U | | <0.0074 | U | | <0.011 | U | | <0.01 | U | | 0.0021 | J | | <0.064 | U | | 0.0046 | J | | <0.024 | U | |
| | | VMP-10-30-012913 | 1/29/2013 | <0.0069 | U | | <0.022 | U | | 0.0042 | J | | <0.0066 | U | | <0.0074 | U | | <0.012 | U | | <0.01 | U | | <0.0062 | U | | <0.065 | U | | 0.00092 | J | | <0.025 | U | |
| VMP-11 | 5 ft | VMP-11-5-090710 | 9/7/2010 | <0.0056 | U | | <0.018 | U | | 0.0099 | | | 0.0019 | J | | <0.0061 | U | | <0.0095 | U | | <0.0086 | U | | 0.001 | J | | <0.053 | U | | <0.0044 | U | | <0.02 | U | |
| | | VMP-11-5-112210 | 11/22/2010 | <0.0058 | U | | <0.018 | U | | 0.011 | | | 0.0021 | J | | <0.0063 | U | | <0.0099 | U | | <0.009 | U | | 0.0013 | J | | <0.055 | U | | 0.0018 | J | | <0.021 | U | |
| | | VMP-11-5-021511 | 2/15/2011 | <0.0052 | U | | <0.016 | U | | 0.017 | | | 0.0055 | | | <0.0056 | J | U | <0.0087 | U | | <0.008 | U | | 0.018 | | | <0.049 | U | | 0.028 | | | <0.019 | U | |
| | | VMP-11-5-040611 | 4/6/2011 | <0.049 | U | | <0.16 | U | | <0.081 | U | | <0.047 | U | | <0.053 | U | | <0.083 | U | | <0.076 | U | | 0.042 | J | | <0.46 | U | | 0.28 | | | <0.18 | U | |
| | | VMP-11-5-080711 | 8/7/2011 | <0.067 | U | | <0.21 | U | | 0.046 | J | | <0.064 | U | | <0.073 | U | | <0.11 | U | | <0.1 | U | | <0.061 | U | | <0.63 | U | | <0.052 | U | | <0.24 | U | |
| | | VMP-11-5-111111 | 11/11/2011 | <0.013 | U | | <0.042 | U | | <0.022 | U | | <0.013 | U | | <0.014 | U | | <0.022 | U | | <0.02 | U | | 0.084 | | | <0.12 | U | | 0.25 | | | <0.048 | U | |
| | | VMP-11-5-012612 | 1/26/2012 | <0.004 | U | | <0.013 | U | | 0.022 | | | 0.00096 | J | | <0.0043 | U | | <0.0067 | U | | <0.0061 | U | | <0.0036 | U | | <0.037 | U | | <0.0031 | U | | <0.014 | U | |
| | | VMP-11-5-041912 | 4/19/2012 | <0.0044 | U | | <0.014 | U | | 0.037 | | J | 0.0034 | J | | <0.0048 | U | | <0.0075 | U | | <0.0068 | U | | 0.0062 | | | <0.042 | U | | 0.0037 | | | <0.016 | U | |
| | | VMP-11-5-071912 | 7/16/2012 | <0.0058 | U | | <0.018 | U | | 0.006 | J | | <0.0055 | U | | <0.0062 | U | | <0.0097 | U | | <0.0089 | U | | <0.0052 | J | U | <0.054 | U | | <0.0045 | J | U | <0.021 | U | |
| | | VMP-11-5-101612 | 10/16/2012 | <0.0064 | U | | <0.02 | U | | 0.012 | | | <0.0061 | U | | <0.007 | U | | <0.011 | U | | <0.0099 | U | | <0.0058 | U | | <0.06 | U | | <0.005 | U | | <0.023 | U | |
| | | VMP-11-5-012913 | 1/29/2013 | <0.33 | U | | <1 | U | | <0.54 | U | | <0.31 | U | | <0.35 | U | | <0.55 | U | | <0.5 | U | | 0.23 | J | | <3.1 | U | | 0.12 | J | | <1.2 | U | |
| | 8 ft | VMP-11-8-090810 | 9/8/2010 | <0.0058 | U | | <0.018 | U | | 0.013 | | | <0.0056 | U | | <0.0063 | U | | <0.0099 | U | | <0.009 | U | | 0.0016 | J | | <0.055 | U | | 0.0034 | J | | <0.021 | U | |
| | | VMP-11-8-112210 | 11/22/2010 | <0.0058 | U | | <0.018 | U | | 0.0056 | J | | 0.0016 | J | | <0.0063 | U | | <0.0099 | U | | <0.009 | U | | 0.00074 | J | | <0.055 | U | | <0.0045 | U | | <0.021 | U | |
| | | VMP-11-8-021111 | 2/11/2011 | <0.0057 | U | | <0.018 | U | | 0.036 | | | <0.0054 | U | | <0.0061 | U | | <0.0096 | U | | <0.0087 | U | | 0.0033 | J | | <0.053 | U | | 0.003 | J | | <0.02 | U | |
| | | VMP-11-8-021111-DUP | 2/11/2011 | <0.0053 | U | | <0.017 | U | | 0.016 | | | <0.0051 | U | | <0.0058 | U | | <0.009 | U | | <0.0082 | U | | 0.0017 | J | | <0.05 | U | | 0.0016 | J | | <0.019 | U | |
| | | VMP-11-8-040611 | 4/6/2011 | <0.025 | U | | <0.08 | U | | <0.042 | U | | <0.024 | U | | <0.027 | U | | <0.042 | U | | <0.039 | U | | 0.035 | | | <0.24 | U | | <0.02 | U | UJ | <0.091 | U | |
| | | VMP-11-8-040611-DUP | 4/6/2011 | <0.022 | U | | <0.069 | U | | <0.036 | U | | <0.021 | U | | <0.024 | U | | <0.037 | U | | <0.034 | U | | 0.025 | | | <0.2 | U | | 0.12 | | J | <0.079 | U | |
| | | VMP-11-8-080711 | 8/7/2011 | <0.067 | U | | <0.21 | U | | 0.14 | | | <0.064 | U | | <0.073 | U | | <0.11 | U | | <0.1 | U | | <0.061 | U | | <0.63 | U | | <0.052 | U | | <0.24 | U | |
| | | VMP-11-8-111411 | 11/14/2011 | <0.004 | U | | <0.013 | U | | 0.043 | | | 0.0013 | J | | 0.00086 | J | | <0.0067 | U | | <0.0062 | U | | 0.005 | | | <0.038 | U | | 0.016 | | | <0.014 | U | |
| | | VMP-11-8-012612 | 1/26/2012 | <0.0039 | U | | <0.012 | U | | 0.019 | | | <0.0037 | U | | <0.0042 | U | | <0.0066 | U | | <0.006 | U | | <0.0035 | U | | <0.036 | U | | <0.003 | U | | <0.014 | U | |
| | | VMP-11-8-041912 | 4/19/2012 | <0.0044 | U | | <0.014 | U | | 0.052 | | J | 0.0024 | J | | <0.0048 | U | | <0.0075 | U | | <0.0068 | U | | 0.0019 | J | | <0.042 | U | | 0.0025 | J | | <0.016 | U | |
| | | VMP-11-8-072012 | 7/20/2012 | <0.0044 | U | | <0.014 | U | | 0.025 | | | <0.0042 | U | | <0.0048 | U | | <0.0075 | U | | <0.0068 | U | | <0.004 | U | | <0.042 | U | | <0.0034 | U | | 0.00028 | J | |
| | | VMP-11-8-101612 | 10/16/2012 | <0.0065 | U | | <0.021 | U | | 0.047 | | | <0.0062 | U | | <0.007 | U | | <0.011 | U | | <0.01 | U | | <0.0059 | U | | <0.061 | U | | 0.0032 | J | | <0.023 | U | |
| | | VMP-11-8-101612-Dup | 10/16/2012 | <0.0066 | U | | <0.021 | U | | 0.041 | | | <0.0063 | U | | <0.0071 | U | | <0.011 | U | | <0.01 | U | | <0.0059 | U | | <0.062 | U | | 0.0027 | J | | <0.024 | U | |
| | | VMP-11-8-012913 | 1/29/2013 | <0.045 | U | | <0.14 | U | | <0.074 | U | | <0.043 | U | | <0.048 | U | | <0.075 | U | | <0.069 | U | | <0.04 | U | | <0.42 | U | | <0.035 | U | | <0.16 | U | |
| | 29 ft | VMP-11-29-090810 | 9/8/2010 | <0.15 | U | | <0.46 | U | | <0.24 | U | | 0.033 | J | | 0.26 | | | <0.25 | U | | <0.22 | U | | <0.13 | U | | <1.4 | U | | 0.1 | J | | <0.53 | U | |
| | | VMP-11-29-112210 | 11/22/2010 | <2.1 | U | | <6.6 | U | | <3.5 | U | | <2 | U | | <2.3 | U | | <3.5 | U | | <3.2 | U | | <1.9 | U | | <20 | U | | <1.6 | U | | <7.5 | U | |
| | | VMP-11-29-112210-Dup | 11/22/2010 | <1.4 | U | | <4.6 | U | | <2.4 | U | | <1.4 | U | | <1.6 | U | | <2.4 | U | | <2.2 | U | | <1.3 | U | | <14 | U | | <1.1 | U | | <5.2 | U | |
| | | VMP-11-29-021411 | 2/14/2011 | <0.0057 | U | | <0.018 | U | | 0.018 | | | 0.0015 | J | | <0.0061 | J | U | <0.0096 | U | | <0.0087 | U | | 0.0062 | | | <0.053 | U | | 0.042 | | | <0.02 | U | |
| | | VMP-11-29-040611 | 4/6/2011 | <0.043 | U | | <0.14 | U | | <0.071 | U | | <0.041 | U | | <0.046 | U | | <0.072 | U | | <0.066 | U | | 0.052 | | | <0.4 | U | | 0.25 | | | <0.15 | U | |
| | | VMP-11-29-082511 | 8/25/2011 | <0.0063 | U | | <0.02 | U | | 0.013 | | | 0.0014 | J | | 0.0017 | J | J | <0.01 | U | | <0.0096 | U | | <0.0056 | U | | <0.059 | U | | 0.002 | J | | 0.00092 | J | |
| | | VMP-11-29-082511-Dup | 8/25/2011 | <0.0063 | U | | <0.02 | U | | 0.016 | | | 0.0012 | J | | 0.0018 | J | J | <0.01 | U | | <0.0096 | U | | <0.0056 | U | | <0.059 | U | | 0.0032 | J | | 0.00098 | J | |
| | | VMP-11-29-111411 | 11/14/2011 | <0.004 | U | | <0.013 | U | | 0.026 | | | 0.00086 | J | | <0.0043 | U | | <0.0067 | U | | <0.0061 | U | | 0.0029 | J | | <0.037 | U | | 0.0023 | J | | <0.014 | U | |
| | | VMP-11-29-012612 | 1/26/2012 | <0.0038 | U | | <0.012 | U | | 0.031 | | | <0.0036 | U | | <0.0041 | U | | <0.0064 | U | | <0.0059 | U | | <0.0034 | U | | <0.036 | U | | <0.003 | U | | <0.014 | U | |
| | | VMP-11-29-042712 | 4/27/2012 | <0.004 | U | | <0.013 | U | | 0.018 | | | 0.002 | J | | <0.0043 | U | | <0.0067 | U | | <0.0061 | U | | 0.0026 | J | | <0.037 | U | | 0.0037 | | | <0.014 | U | |
| | | VMP-11-29-072012 | 7/23/2012 | <0.004 | U | | <0.013 | U | | 0.1 | | | 0.01 | | | 0.0017 | J | | <0.0067 | U | | <0.0061 | U | | 0.038 | | | <0.037 | U | | 0.0095 | | | 0.0026 | J | |
| | | VMP-11-29-101612 | 10/16/2012 | <0.0067 | U | | <0.021 | U | | 0.0051 | J | | <0.0064 | U | | <0.0073 | U | | <0.011 | U | | <0.01 | U | | <0.0061 | U | | <0.063 | U | | <0.0052 | U | | <0.024 | U | |
| | | VMP-11-29-012913 | 1/29/2013 | <0.0066 | U | | <0.021 | U | | 0.028 | | | <0.0063 | U | | <0.0071 | U | | <0.011 | U | | <0.01 | U | | <0.0059 | U | | <0.062 | U | | 0.0012 | J | | <0.024 | U | |
| | 38 ft | VMP-11-38-042312 | 4/23/2012 | <0.3 | U | | <0.94 | U | | <0.49 | U | | 0.031 | J | | <0.32 | U | | <0.5 | U | | <0.46 | U | | <0.27 | U | | <2.8 | U | | <0.23 | U | | <1.1 | U | |
| | | VMP-11-38-042312-Dup | 4/23/2012 | <1 | U | | <3.3 | U | | <1.7 | U | | <0.99 | U | | <1.1 | U | | <1.8 | U | | <1.6 | U | | <0.94 | U | | <9.8 | U | | <0.81 | U | | <3.8 | U | |
| | | VMP-11-38-072312 | 7/23/2012 | <0.49 | U | | <1.6 | U | | <0.82 | U | | <0.47 | U | | <0.53 | U | | <0.83 | U | | <0.76 | U | | <0.44 | U | | <4.6 | U | | <0.38 | U | | <1.8 | U | |
| | | VMP-11-38-101612 | 10/16/2012 | <0.0068 | U | | <0.022 | U | | 0.005 | J | | <0.0065 | U | | <0.0074 | U | | <0.011 | U | | <0.01 | U | | <0.0061 | U | | <0.064 | U | | 0.0023 | J | | <0.024 | U | |
| | | VMP-11-38-013013 | 1/30/2013 | <0.0063 | U | | <0.02 | U | | 0.008 | J | | <0.006 | U | | <0.0068 | U | | <0.01 | U | | <0.0096 | U | | <0.0056 | U | | <0.059 | U | | 0.0013 | J | | <0.023 | U | |

SEE LAST PAGE OF TABLE FOR NOTES

**TABLE 6**
**CUMULATIVE SUMMARY OF SOIL VAPOR ANALYTICAL DETECTIONS AND SCREENING RESULTS: PUBLIC WORKS YARD AND WRR - VOCS**

| Location | Depth | Sample ID | Sample Date | trans-1,3-Dichloropropene 6.2 | | | 1,4-Dioxane 2.3 | | | Ethanol | | | Ethylbenzene 8300 | | | 4-Ethyltoluene | | | Freon 113 | | | Freon 114 | | | Heptane | | | Hexachlorobutadiene | | | Hexane | | | 2-Hexanone (Methyl N-Butyl | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals |
| VMP-12 | 5 ft | VMP-12-5-090310 | 9/3/2010 | <6.1 | U | | <19 | U | | <10 | U | | <5.8 | U | | <6.6 | U | | <10 | U | | <9.4 | U | | <5.5 | U | | <57 | U | | 11 | | | <22 | U | |
| | | VMP-12-5-120310 | 12/3/2010 | <60 | U | | <190 | U | | <100 | U | | <58 | U | | <65 | U | | <100 | U | | <93 | U | | <54 | U | | <570 | U | | 370 | | | <220 | U | |
| | | VMP-12-5-021511 | 2/15/2011 | <2.8 | U | | <8.8 | U | | <4.6 | U | | <2.6 | U | | <3 | U | | <4.7 | U | | <4.3 | U | | <2.5 | U | | <26 | U | | 9.6 | | | <10 | U | |
| | | VMP-12-5-041911 | 4/19/2011 | <20 | U | | <64 | U | | 5.2 | J | | <19 | U | | <22 | U | | <34 | U | | <31 | U | | <18 | U | | <190 | U | | 5.1 | J | | <73 | U | |
| | | VMP-12-5-080411 | 8/4/2011 | <5.2 | U | | <17 | U | | <8.7 | U | | <5 | U | | <5.7 | U | | <8.8 | U | | <8.1 | U | | <4.7 | U | | <49 | U | | 16 | | | <19 | U | |
| | | VMP-12-5-111611 | 11/16/2011 | <0.0037 | U | | <0.012 | U | | 0.015 | | | 0.00074 | J | | <0.004 | U | | <0.0062 | U | | <0.0057 | U | | 0.0046 | | | <0.035 | U | | 0.036 | | | 0.00029 | J | |
| | | VMP-12-5-012412 | 1/24/2012 | <0.042 | U | | <0.13 | U | | <0.069 | J | U | 0.0036 | J | | 0.0078 | J | | <0.07 | U | | <0.064 | U | | 0.4 | | | <0.39 | U | | 3.5 | | | <0.15 | U | |
| | | VMP-12-5-041912 | 4/19/2012 | <0.0042 | U | | <0.013 | U | | 0.0088 | | J | 0.0056 | | | 0.0012 | J | | <0.007 | U | | <0.0064 | U | | 0.012 | | | <0.039 | U | | 0.019 | | | <0.015 | U | |
| | | VMP-12-5-072612 | 7/26/2012 | <0.0044 | U | | <0.014 | U | | 0.017 | | | 0.0029 | J | | <0.0048 | U | | <0.0075 | U | | <0.0068 | U | | 0.0081 | | | <0.042 | U | | 0.0084 | | J | <0.016 | U | |
| | | VMP-12-5-072612-Dup | 7/26/2012 | <0.004 | U | | <0.013 | U | | 0.013 | | | <0.0039 | U | | <0.0044 | U | | <0.0068 | U | | <0.0062 | U | | 0.0006 | J | | <0.038 | U | | 0.00045 | J | J | <0.014 | U | |
| | | VMP-12-5-102412 | 10/24/2012 | <0.0068 | U | | <0.022 | U | | 0.01 | J | | 0.0016 | J | | <0.0074 | U | | <0.011 | U | | <0.01 | U | | <0.0061 | U | | <0.064 | U | | 0.0026 | J | | <0.024 | U | |
| | | VMP-12-5-021813 | 2/18/2013 | <0.0061 | J | U | <0.019 | U | | 0.0042 | J | | <0.0058 | U | | <0.0066 | U | | <0.01 | U | | <0.0094 | U | | <0.0055 | U | | <0.057 | U | | 0.0034 | J | | <0.022 | U | |
| | 11.5 ft | VMP-12-11.5-090310 | 9/3/2010 | <7.8 | U | | <25 | U | | <13 | U | | 5.4 | J | | <8.5 | U | | <13 | U | | <12 | U | | 4.5 | J | | <74 | U | | 41 | | | <28 | U | |
| | | VMP-12-11.5-120310 | 12/3/2010 | <6.8 | U | | <22 | U | | <11 | U | | <6.5 | U | | <7.3 | U | | <11 | U | | <10 | U | | <6.1 | U | | <64 | U | | 11 | | | <24 | U | |
| | | VMP-12-11.5-021511 | 2/15/2011 | <6.1 | U | | <19 | U | | <10 | U | | <5.8 | U | | <6.6 | U | | <10 | U | | <9.4 | U | | <5.5 | U | | <57 | U | | 18 | | | <22 | U | |
| | | VMP-12-11.5-021511-DUP | 2/15/2011 | <5.2 | U | | <17 | U | | <8.7 | U | | <5 | U | | <5.7 | U | | <8.8 | U | | <8.1 | U | | <4.7 | U | | <49 | U | | 15 | | | <19 | U | |
| | | VMP-12-11.5-041911 | 4/19/2011 | <18 | U | | <58 | U | | <30 | U | | <18 | U | | <20 | U | | <31 | U | | <28 | U | | <16 | U | | <170 | U | | 6.9 | J | | <66 | U | |
| | | VMP-12-11.5-080411 | 8/4/2011 | <6.4 | U | | <20 | U | | <11 | U | | <6.1 | U | | <6.9 | U | | <11 | U | | <9.8 | U | | <5.8 | U | | <60 | U | | 9.1 | | | <23 | U | |
| | | VMP-12-11.5-111611 | 11/16/2011 | <0.051 | U | | <0.16 | U | | 0.02 | J | | <0.049 | U | | <0.055 | U | | <0.086 | U | | <0.079 | U | | <0.046 | U | | <0.48 | U | | 0.054 | | | <0.18 | U | |
| | | VMP-12-11.5-012412 | 1/24/2012 | <0.48 | U | | <1.5 | U | | <0.79 | U | | <0.46 | U | | <0.52 | U | | <0.8 | U | | <0.73 | U | | <0.43 | U | | <4.5 | U | | 1.6 | | | <1.7 | U | |
| | | VMP-12-11.5-041912 | 4/19/2012 | <0.043 | U | | <0.14 | U | | <0.072 | U | | 0.005 | J | | <0.047 | U | | <0.073 | U | | <0.067 | U | | <0.039 | U | | <0.41 | U | | 0.023 | J | | <0.16 | U | |
| | | VMP-12-11.5-082012 | 8/20/2012 | <0.0069 | U | | <0.022 | U | | 0.045 | | J | 0.0029 | J | | <0.0074 | U | | <0.012 | U | | <0.01 | U | | <0.0062 | U | | <0.065 | U | | 0.002 | J | | <0.025 | U | |
| | | VMP-12-11.5-102612 | 10/26/2012 | <0.0066 | U | | <0.021 | U | | 0.025 | | | <0.0063 | U | | <0.0071 | U | | <0.011 | U | | <0.01 | U | | 0.0016 | J | | <0.062 | U | | 0.0057 | | | <0.024 | U | |
| | | VMP-12-11.5-021813 | 2/18/2013 | <0.0066 | U | | <0.021 | U | | <0.011 | U | | <0.0063 | U | | <0.0071 | U | | <0.011 | U | | <0.01 | U | | <0.0059 | U | | <0.062 | U | | 0.00098 | J | | <0.024 | U | |
| | 25 ft | VMP-12-25-090310 | 9/3/2010 | <10 | U | | <32 | U | | <16 | U | | 14 | | | <11 | U | | <15 | U | | <17 | U | | 100 | | | <94 | U | | 860 | | | <36 | U | |
| | | VMP-12-25-120310 | 12/3/2010 | <0.49 | U | | <1.6 | U | | <0.82 | U | | <0.47 | U | | <0.54 | U | | <0.84 | U | | <0.76 | U | | <0.45 | U | | <4.6 | U | | 0.55 | | | <1.8 | U | |
| | | VMP-12-25-021511 | 2/15/2011 | <12 | U | | <38 | U | | <20 | U | | 4.1 | J | | <13 | U | | <20 | U | | <18 | U | | 32 | | | <110 | U | | 180 | | | <44 | U | |
| | | VMP-12-25-041911 | 4/19/2011 | <20 | U | | <63 | U | | <33 | U | | <19 | U | | <21 | U | | <33 | U | | <30 | U | | 10 | J | | <180 | U | | 110 | | | <71 | U | |
| | | VMP-12-25-080411 | 8/4/2011 | <12 | U | | <40 | U | | <21 | U | | <12 | U | | <14 | U | | <21 | U | | <19 | U | | 9.2 | J | | <120 | U | | 190 | | | <45 | U | |
| | | VMP-12-25-111611 | 11/16/2011 | <14 | U | | <45 | U | | <24 | U | | <14 | U | | <15 | U | | <24 | U | | <22 | U | | <13 | U | | <130 | U | | 40 | | | <51 | U | |
| | | VMP-12-25-012412 | 1/24/2012 | <5.4 | U | | <17 | U | | <9 | U | | <5.2 | U | | <5.9 | U | | <9.2 | U | | <8.4 | U | | <4.9 | U | | <51 | U | | 40 | | J | <20 | U | |
| | | VMP-12-25-012412-DUP | 1/24/2012 | <40 | U | | <130 | U | | <66 | U | | <38 | U | | <43 | U | | <67 | U | | <61 | U | | <36 | U | | <370 | U | | 36 | | | <140 | U | |
| | | VMP-12-25-041912 | 4/19/2012 | <4.2 | U | | <13 | U | | <6.9 | U | | <4 | U | | <4.5 | U | | <7 | U | | <6.4 | U | | <3.7 | U | | <39 | U | | 9.9 | | | <15 | U | |
| | | VMP-12-25-072712 | 7/27/2012 | <4.6 | U | | <14 | U | | <7.6 | U | | <4.4 | U | | <4.9 | U | | <7.7 | U | | <7 | U | | <4.1 | U | | <43 | U | | <3.5 | U | | <16 | U | |
| | | VMP-12-25-072712-Dup | 7/27/2012 | <4.6 | U | | <14 | U | | <7.6 | U | | <4.4 | U | | <4.9 | U | | <7.7 | U | | <7 | U | | <4.1 | U | | <43 | U | | <3.5 | U | | <16 | U | |
| | | VMP-12-25-102512 | 10/25/2012 | <2 | U | | <6.2 | U | | <3.2 | U | | <1.9 | U | | <2.1 | U | | <3.3 | U | | <3 | U | | <1.8 | U | | <18 | U | | <1.5 | U | | <7.1 | U | |
| | | VMP-12-25-021513 | 2/15/2013 | <3.6 | U | | <12 | U | | <6.1 | U | | <3.5 | U | | <4 | U | | <6.2 | U | | <5.6 | U | | <3.3 | U | | <34 | U | | 6.6 | | J | <13 | U | |
| | 39 ft | VMP-12-39-041911 | 4/19/2011 | <19 | U | | <61 | U | | <32 | U | | 10 | J | | <21 | U | | <32 | U | | <29 | U | | 180 | | | <180 | U | | 1200 | | | <69 | U | |
| | | VMP-12-39-012412 | 1/24/2012 | <40 | U | | <130 | U | | <66 | U | | 3.5 | J | | <43 | U | | <67 | U | | <61 | U | | 280 | | | <370 | U | | 1900 | | | <140 | U | |
| | | VMP-12-39-041912 | 4/19/2012 | <20 | U | | <63 | U | | <33 | U | | 3 | J | | <22 | U | | <34 | U | | <30 | U | | 150 | | | <190 | U | | 840 | | | <72 | U | |
| | | VMP-12-39-072612 | 7/26/2012 | <9.1 | U | | <29 | U | | <15 | U | | <8.7 | U | | <9.9 | U | | <15 | U | | <14 | U | | 26 | | | <86 | U | | 240 | | | <33 | U | |
| | | VMP-12-39-102412 | 10/24/2012 | <24 | U | | <76 | U | | <40 | U | | 4.6 | J | | <26 | U | | <41 | U | | <37 | U | | <22 | U | | <230 | U | | 58 | | | <87 | U | |
| | | VMP-12-39-021513 | 2/15/2013 | <11 | U | | <35 | U | | <18 | U | | 41 | | | 9.2 | J | | <18 | U | | <17 | U | | 78 | | | <100 | U | | 220 | | | <40 | U | |
| VMP-13 | 5 ft | VMP-13-5-091310 | 9/13/2010 | <0.04 | U | | <0.13 | U | | 0.24 | | | <0.038 | U | | <0.043 | U | | <0.067 | U | | <0.062 | U | | 0.0094 | J | | <0.38 | U | | 0.015 | J | | <0.14 | U | |
| | | VMP-13-5-120110 | 12/1/2010 | <0.0053 | U | | <0.017 | U | | 0.007 | J | | 0.047 | | | 0.032 | | | <0.0089 | U | | <0.0081 | U | | 0.084 | | | <0.05 | U | | 0.14 | | | <0.019 | U | |
| | | VMP-13-5-021811 | 2/18/2011 | <0.0063 | U | | <0.02 | U | | 0.024 | | | <0.006 | U | | <0.0068 | U | | <0.01 | U | | <0.0096 | U | | 0.0016 | J | | <0.059 | U | | 0.0022 | J | | 0.00065 | J | |
| | | VMP-13-5-040511 | 4/5/2011 | <0.012 | U | | <0.04 | U | | 0.0054 | J | | <0.012 | U | | <0.014 | U | | <0.021 | U | | <0.019 | U | | 0.007 | J | | <0.12 | U | | 0.0088 | J | | <0.045 | U | |
| | | VMP-13-5-080911 | 8/9/2011 | <0.013 | U | | <0.043 | U | | 0.063 | | J | 0.0025 | J | | 0.0019 | J | | <0.023 | U | | <0.021 | U | | <0.012 | U | | <0.13 | U | | 0.0065 | J | | <0.048 | U | |
| | | VMP-13-5-080911-DUP | 8/9/2011 | <0.012 | U | | <0.038 | U | | 0.14 | | J | 0.0021 | J | | <0.013 | U | | <0.02 | U | | <0.018 | U | | <0.011 | U | | <0.11 | U | | 0.0098 | | | 0.0024 | J | |
| | | VMP-13-5-111411 | 11/14/2011 | <0.0042 | U | | <0.013 | U | | 0.027 | | | 0.00094 | J | | <0.0045 | U | | <0.007 | U | | <0.0064 | U | | 0.002 | J | | <0.039 | U | | 0.00093 | J | | <0.015 | U | |
| | | VMP-13-5-012712 | 1/27/2012 | <0.035 | U | | <0.11 | U | | 0.014 | J | J | 0.0044 | J | J | <0.038 | U | | <0.059 | U | | <0.054 | U | | 0.035 | | J | <0.33 | U | | 0.18 | | J | <0.13 | U | |
| | | VMP-13-5-042012 | 4/20/2012 | <0.0041 | U | | <0.013 | U | | 0.022 | | | 0.0013 | J | | <0.0044 | U | | <0.0068 | U | | <0.0062 | U | | <0.0037 | U | | <0.038 | U | | <0.0032 | U | | 0.0012 | J | |
| | | VMP-13-5-071912 | 7/19/2012 | <0.0042 | U | | <0.013 | U | | 0.056 | | | 0.0044 | | | 0.0045 | J | | <0.0072 | U | | <0.0065 | U | | 0.0053 | | | <0.04 | U | | 0.0061 | | | <0.015 | U | |
| | | VMP-13-5-071912-Dup | 7/19/2012 | <0.0042 | J | U | <0.013 | U | | 0.052 | | | 0.0036 | J | | 0.004 | J | | <0.0072 | U | | <0.0065 | U | | 0.0058 | | | <0.04 | U | | 0.0054 | | | <0.015 | U | |
| | | VMP-13-5-100912 | 10/9/2012 | <0.0066 | J | U | <0.021 | U | | <0.011 | U | | <0.0063 | U | | <0.0071 | U | | <0.011 | U | | <0.01 | U | | 0.0038 | J | | <0.062 | U | | 0.0069 | | | <0.024 | U | |
| | | VMP-13-5-012913 | 1/29/2013 | <0.007 | U | | <0.022 | U | | <0.012 | U | | <0.0068 | U | | <0.0076 | U | | <0.012 | U | | <0.011 | U | | <0.0064 | U | | <0.066 | U | | <0.0055 | U | | <0.025 | U | |
| | 10.5 ft | VMP-13-10.5-091310 | 9/13/2010 | <0.015 | U | | <0.047 | U | | <0.024 | U | | <0.014 | U | | <0.016 | U | | <0.025 | U | | <0.023 | U | | 0.0052 | J | | <0.14 | U | | 0.028 | | J | <0.053 | U | |
| | | VMP-13-10.5-091310-Dup | 9/13/2010 | <0.014 | U | | 0.041 | J | | 0.014 | J | | <0.014 | U | | <0.016 | U | | <0.024 | U | | <0.022 | U | | 0.0072 | J | | <0.14 | U | | 0.043 | | J | <0.052 | U | |
| | | VMP-13-10.5-120110 | 12/1/2010 | <0.0059 | U | | <0.019 | U | | <0.0098 | U | | <0.0056 | J | U | <0.0064 | U | | <0.0099 | U | | <0.009 | U | | 0.0029 | J | | <0.055 | U | | 0.0076 | | | <0.021 | U | |
| | | VMP-13-10.5-120110-DUP | 12/1/2010 | <0.0061 | U | | <0.019 | U | | 0.016 | | | <0.0059 | U | | <0.0066 | U | | <0.01 | U | | <0.0094 | U | | 0.0036 | J | | <0.058 | U | | 0.01 | | | <0.022 | U | |
| | | VMP-13-10.5-021811 | 2/18/2011 | <2.4 | U | | <7.7 | U | | <4 | U | | <2.3 | U | | <2.6 | U | | <4.1 | U | | <3.7 | U | | <2.2 | U | | <23 | U | | <1.9 | U | | <8.8 | U | |
| | | VMP-13-10.5-021811-DUP | 2/18/2011 | <2.3 | U | | <7.4 | U | | <3.9 | U | | <2.2 | U | | <2.5 | U | | <3.9 | U | | <3.6 | U | | <2.1 | U | | <22 | U | | <1.8 | U | | <8.4 | U | |
| | | VMP-13-10.5-040511-DUP | 4/5/2011 | <0.0063 | U | | <0.02 | U | | 0.0077 | J | | <0.006 | U | | <0.0068 | U | | <0.01 | U | | <0.0096 | U | | 0.003 | J | | <0.059 | U | | 0.0063 | | | <0.023 | U | |
| | | VMP-13-10.5-080911 | 8/9/2011 | <0.14 | U | | <0.44 | U | | <0.23 | U | | <0.13 | U | | <0.15 | U | | <0.23 | U | | <0.21 | U | | <0.12 | U | | <1.3 | U | | 0.3 | | | <0.5 | U | |
| | | VMP-13-10.5-111411 | 11/14/2011 | <0.004 | U | | <0.013 | U | | 0.053 | | | 0.0012 | J | | 0.00071 | J | | <0.0067 | U | | <0.0062 | U | | 0.0018 | J | | <0.038 | U | | 0.0013 | J | | <0.014 | U | |
| | | VMP-13-10.5-012712 | 1/26/2012 | <0.011 | U | | <0.035 | U | | 0.0084 | J | | <0.011 | U | | <0.012 | U | | <0.019 | U | | <0.017 | U | | 0.015 | | | <0.1 | U | | 0.057 | | J | <0.04 | U | |
| | | VMP-13-10.5-012712-DUP | 1/26/2012 | <0.016 | U | | <0.05 | U | | <0.026 | U | | <0.015 | U | | <0.017 | U | | <0.027 | U | | <0.024 | U | | 0.024 | | | <0.15 | U | | 0.088 | | J | <0.057 | U | |
| | | VMP-13-10.5-042012 | 4/20/2012 | 0.00098 | J | | <0.013 | U | | 0.022 | | J | 0.0016 | J | | 0.00096 | J | | <0.0067 | U | | <0.0061 | U | | 0.0012 | J | | <0.037 | U | | 0.021 | | | 0.00085 | J | |
| | | VMP-13-10.5-071912 | 7/19/2012 | <0.0042 | U | | <0.013 | U | | 0.038 | | | 0.002 | J | | 0.0021 | J | | <0.0072 | U | | <0.0065 | U | | 0.0062 | | | <0.04 | U | | 0.0066 | | | <0.015 | U | |
| | | VMP-13-10.5-100912 | 10/9/2012 | <0.0056 | U | | <0.018 | U | | 0.022 | | J | <0.0054 | U | | 0.0031 | J | | <0.0095 | U | | <0.0086 | U | | 0.0014 | J | | <0.053 | U | | 0.003 | J | | <0.02 | U | |
| | | VMP-13-10.5-100912-Dup | 10/9/2012 | <0.0067 | U | | <0.021 | U | | <0.011 | U | UJ | <0.0064 | U | | <0.0073 | U | | <0.011 | U | | <0.01 | U | | <0.0061 | U | | <0.063 | U | | <0.0052 | U | | <0.024 | U | |
| | | VMP-13-10.5-013013 | 1/30/2013 | <0.0057 | U | | <0.018 | U | | 0.0047 | J | | <0.0055 | U | | <0.0062 | J | U | <0.0096 | U | | <0.0088 | U | | <0.0052 | U | | <0.054 | U | | 0.0012 | J | | <0.021 | U | |
| | 21.5 ft | VMP-13-21.5-091310 | 9/13/2010 | <11 | U | | <35 | U | | <18 | U | | <10 | U | | <12 | U | | <18 | U | | <17 | U | | <9.9 | U | | <100 | U | | 2.1 | J | | <40 | U | |
| | | VMP-13-21.5-120110 | 12/1/2010 | <21 | U | | <68 | U | | <35 | U | | <20 | U | | <23 | U | | <36 | U | | <33 | U | | <19 | U | | <200 | U | | <16 | U | | <77 | U | |
| | | VMP-13-21.5-021811 | 2/18/2011 | <3.2 | U | | <10 | U | | <5.3 | U | | <3 | U | | <3.4 | U | | <5.4 | U | | <4.9 | U | | <2.9 | U | | <30 | U | | <2.5 | U | | <11 | U | |
| | | VMP-13-21.5-040511 | 4/5/2011 | <4.6 | U | | <14 | U | | <7.6 | U | | <4.4 | U | | <5 | U | | <7.7 | U | | <7.1 | U | | <4.1 | U | | <43 | U | | <3.6 | U | | <16 | U | |
| | | VMP-13-21.5-080911 | 8/9/2011 | <0.57 | U | | <1.8 | U | | <0.95 | U | | 0.38 | J | | <0.62 | U | | <0.96 | U | | <0.88 | U | | <0.52 | U | | <5.4 | U | | 1 | | | <2.1 | U | |
| | | VMP-13-21.5-111411 | 11/14/2011 | <2.6 | U | | <8.3 | U | | <4.3 | U | | <2.5 | U | | <2.8 | U | | <4.4 | U | | <4 | U | | <2.4 | U | | <24 | U | | <2 | U | | <9.4 | U | |
| | | VMP-13-21.5-111411-DUP | 11/14/2011 | <2.6 | U | | <8.3 | U | | <4.3 | U | | <2.5 | U | | <2.8 | U | | <4.4 | U | | <4 | U | | <2.4 | U | | <24 | U | | 0.98 | J | | <9.4 | U | |
| | | VMP-13-21.5-012712 | 1/27/2012 | <0.61 | U | | <1.9 | U | | <1 | U | | 0.13 | J | J | <0.66 | U | | <1 | U | | <0.94 | U | | <0.55 | U | | <5.7 | U | | 0.38 | J | J | <2.2 | U | |
| | | VMP-13-21.5-042012 | 4/20/2012 | <0.068 | U | | <0.21 | U | | 0.077 | J | | 0.016 | J | | <0.073 | U | | <0.11 | U | | <0.1 | U | | <0.061 | U | | <0.64 | U | | 0.083 | | | <0.24 | U | |
| | | VMP-13-21.5-071912 | 7/19/2012 | <0.0042 | U | | <0.013 | U | | 0.071 | | | 0.0024 | J | | 0.0015 | J | | <0.0072 | U | | <0.0065 | U | | 0.0089 | | | <0.04 | U | | 0.01 | | | <0.015 | U | |
| | | VMP-13-21.5-100912 | 10/9/2012 | <0.0069 | U | | 0.011 | J | | <0.011 | U | | <0.0066 | U | | <0.0074 | U | | <0.012 | U | | <0.01 | U | | <0.0062 | U | | <0.065 | U | | 0.0026 | J | | <0.025 | U | |
| | | VMP-13-21.5-013013 | 1/30/2013 | <0.0067 | U | | <0.021 | U | | 0.0051 | J | | <0.0064 | U | | <0.0073 | J | U | <0.011 | U | | <0.01 | U | | <0.0061 | U | | <0.063 | U | | 0.0011 | J | | <0.024 | U | |
| | 29.5 ft | VMP-13-29.5-021811 | 2/18/2011 | <98 | U | | <310 | U | | <160 | U | | <94 | U | | <110 | U | | <160 | U | | <150 | U | | <88 | U | | <920 | U | | <76 | U | | <350 | U | |
| | | VMP-13-29.5-040511 | 4/5/2011 | <64 | U | | <200 | U | | <100 | U | | 20 | J | | <69 | U | | <110 | U | | <98 | U | | <57 | U | | <600 | U | | <49 | U | | <230 | U | |
| | | VMP-13-29.5-013012 | 1/30/2012 | <1.9 | U | | <6.2 | U | | <3.2 | U | | 4.5 | | J | 0.48 | J | J | <3.3 | U | | <3 | U | | <1.8 | U | | <18 | U | | 0.4 | J | J | <7 | U | |
| | | VMP-13-29.5-042012 | 4/20/2012 | <2.5 | U | | <8.1 | U | | <4.2 | U | | 0.94 | J | | <2.8 | U | | <4.3 | U | | <3.9 | U | | <2.3 | U | | <24 | U | | 1.5 | J | | <9.2 | U | |
| | | VMP-13-29.5-071912 | 7/19/2012 | <7.3 | U | | <23 | U | | <12 | U | | <7 | U | | <7.9 | U | | <12 | U | | <11 | U | | <6.6 | U | | <69 | U | | <5.7 | U | | <26 | U | |
| | | VMP-13-29.5-100912 | 10/9/2012 | <6.9 | U | | <22 | U | | 15 | | | 1.3 | J | | <7.4 | U | | <12 | U | | <10 | U | | <6.2 | U | | <65 | U | | 2.8 | J | | <25 | U | |
| | | VMP-13-29.5-013013 | 1/30/2013 | <2.9 | U | | <9.2 | U | | 0.85 | J | | <2.8 | U | | 0.26 | J | | <4.9 | U | | <4.5 | U | | <2.6 | U | | <27 | U | | 0.46 | J | | <10 | U | |

SEE LAST PAGE OF TABLE FOR NOTES

**TABLE 6**
**CUMULATIVE SUMMARY OF SOIL VAPOR ANALYTICAL DETECTIONS AND SCREENING RESULTS: PUBLIC WORKS YARD AND WRR - VOCS**

| Location | Depth | Sample ID | Sample Date | trans-1,3-Dichloropropene 6.2 | | | 1,4-Dioxane 2.3 | | | Ethanol | | | Ethylbenzene 8300 | | | 4-Ethyltoluene | | | Freon 113 | | | Freon 114 | | | Heptane | | | Hexachlorobutadiene | | | Hexane | | | 2-Hexanone (Methyl N-Butyl | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals |
| VMP-14 | 5 ft | VMP 14-5-091010 | 9/10/2010 | <0.28 | U | | <0.89 | U | | <0.47 | U | | <0.27 | U | | <0.3 | U | | <0.48 | U | | <0.43 | U | | <0.25 | U | | <2.6 | U | | 0.55 | | | <1 | U | |
| | | VMP-14-5-120110 | 12/1/2010 | <0.0054 | U | | <0.017 | U | | 0.0085 | J | | <0.0052 | U | | <0.0059 | U | | <0.0092 | U | | <0.0084 | U | | 0.0011 | J | | <0.051 | U | | 0.0017 | J | | <0.02 | U | |
| | | VMP-14-5-021711 | 2/17/2011 | <0.006 | U | | <0.019 | U | | 0.026 | J | J | 0.0029 | J | | <0.0065 | U | | <0.01 | U | | <0.0092 | U | | 0.059 | | | <0.056 | U | | 0.1 | | | <0.022 | U | |
| | | VMP-14-5-040511 | 4/5/2011 | <0.0061 | U | | <0.019 | U | | 0.012 | | | <0.0058 | U | | <0.0066 | U | | <0.01 | U | | <0.0094 | U | | <0.0055 | U | | <0.057 | U | | 0.0076 | | | <0.022 | U | |
| | | VMP-14-5-080811 | 8/8/2011 | <6.4 | U | | <20 | U | | <10 | U | | <6.1 | U | | <6.9 | U | | <11 | U | | <9.8 | U | | 10 | | | <60 | U | | 120 | | | <23 | U | |
| | | VMP-14-5-111411 | 11/14/2011 | <0.016 | U | | <0.051 | U | | <0.026 | U | | <0.015 | U | | <0.017 | U | | <0.027 | U | | <0.025 | U | | <0.014 | U | | <0.15 | U | | <0.012 | U | | <0.058 | U | |
| | | VMP-14-5-042012 | 4/20/2012 | 0.00099 | J | | <0.012 | U | | 0.024 | | | 0.0019 | J | | <0.0042 | U | | <0.0066 | U | | <0.006 | U | | 0.0054 | | | <0.036 | U | | 0.023 | | | <0.014 | U | |
| | | VMP-14-5-072312 | 7/23/2012 | <0.0047 | U | | <0.015 | U | | 0.3 | | | 0.0078 | | | 0.0018 | J | | <0.0079 | U | | <0.0072 | U | | 0.0026 | J | | <0.044 | U | | <0.0036 | U | | 0.006 | J | |
| | | VMP-14-5-101012 | 10/10/2012 | <0.0066 | U | | <0.021 | U | | 0.024 | | | <0.0063 | U | | <0.0071 | U | | <0.011 | U | | <0.01 | U | | <0.0059 | U | | <0.062 | U | | <0.0051 | U | | <0.024 | U | |
| | | VMP-14-5-013113 | 1/31/2013 | <0.0061 | U | | <0.019 | U | | 0.0018 | J | | <0.0058 | U | | <0.0066 | U | | <0.01 | U | | <0.0094 | U | | <0.0055 | U | | <0.057 | U | | <0.0047 | U | | <0.022 | U | |
| | 11.5 ft | VMP-14-11.5-091010 | 9/10/2010 | <4.3 | U | | <14 | U | | <7.2 | U | | <4.1 | U | | <4.7 | U | | <7.3 | U | | <6.7 | U | | <3.9 | U | | <41 | U | | 4.6 | | | <16 | U | |
| | | VMP-14-11.5-120110 | 12/2/2010 | <0.38 | U | | <1.2 | U | | <0.63 | U | | <0.36 | U | | <0.41 | U | | <0.64 | U | | <0.59 | U | | <0.34 | U | | <3.6 | U | | 0.27 | J | | <1.4 | U | |
| | | VMP-14-11.5-120110-DUP | 12/2/2010 | <0.34 | U | | <1.1 | U | | <0.57 | U | | 0.08 | J | | <0.37 | U | | <0.58 | U | | <0.53 | U | | <0.31 | U | | <3.2 | U | | 0.32 | | | <1.2 | U | |
| | | VMP-14-11.5-021711 | 2/17/2011 | <0.12 | U | | <0.4 | U | | <0.21 | U | | <0.12 | U | | <0.14 | U | | <0.21 | U | | <0.19 | U | | <0.11 | U | | <1.2 | U | | <0.097 | U | | <0.45 | U | |
| | | VMP-14-11.5-021711-DUP | 2/17/2011 | <0.12 | U | | <0.4 | U | | <0.21 | U | | <0.12 | U | | <0.14 | U | | <0.21 | U | | <0.19 | U | | <0.11 | U | | <1.2 | U | | <0.097 | U | | <0.45 | U | |
| | | VMP-14-11.5-040511 | 4/5/2011 | <0.02 | U | | <0.065 | U | | <0.034 | U | | 0.0054 | J | | <0.022 | U | | <0.034 | U | | <0.031 | U | | <0.018 | U | | <0.19 | U | | 0.15 | | | <0.073 | U | |
| | | VMP-14-11.5-080811 | 8/8/2011 | <0.63 | U | | <2 | U | | <1 | U | | <0.6 | U | | <0.68 | U | | <1.1 | U | | <0.97 | U | | <0.57 | U | | <5.9 | U | | 1.2 | | | <2.3 | U | |
| | | VMP-14-11.5-111511 | 11/15/2011 | <0.98 | U | | <3.1 | U | | <1.6 | U | | <0.94 | U | | <1.1 | U | | <1.6 | U | | <1.5 | U | | 0.48 | J | | <9.2 | U | | 7.7 | | | <3.5 | U | |
| | | VMP-14-11.5-012612 | 1/26/2012 | <4 | U | | <13 | U | | <6.6 | U | | <3.8 | U | | <4.3 | U | | <6.7 | U | | <6.2 | U | | <3.6 | U | | <38 | U | | 63 | | | <14 | U | |
| | | VMP-14-11.5-042312 | 4/23/2012 | <0.0042 | U | | <0.013 | U | | 0.02 | | J | 0.0025 | J | | <0.0045 | U | | <0.007 | U | | <0.0064 | U | | 0.0054 | | | <0.039 | U | | 0.027 | | J | <0.015 | U | |
| | | VMP-14-11.5-042312-Dup | 4/23/2012 | <0.0042 | U | | <0.013 | U | | 0.0058 | J | J | 0.0022 | J | | <0.0045 | U | | <0.007 | U | | <0.0064 | U | | 0.0054 | | | <0.039 | U | | 0.016 | | J | <0.015 | U | |
| | | VMP-14-11.5-072512 | 7/25/2012 | <1.4 | U | | <4.6 | U | | <2.4 | U | | <1.4 | U | | <1.6 | U | | <2.5 | U | | <2.2 | U | | <1.3 | U | | <14 | U | | 9.8 | | | <5.3 | U | |
| | | VMP-14-11.5-101012 | 10/10/2012 | <0.0063 | U | | <0.02 | U | | 0.021 | | | <0.006 | U | | <0.0068 | U | | <0.01 | U | | <0.0096 | U | | <0.0056 | U | | <0.059 | U | | 0.0097 | | | <0.023 | U | |
| | | VMP-14-11.5-013113 | 1/31/2013 | <0.0058 | U | | <0.018 | U | | 0.0014 | J | | <0.0056 | U | | <0.0063 | J | U | <0.0099 | U | | <0.009 | U | | <0.0053 | U | | <0.055 | U | | 0.0014 | J | | <0.021 | U | |
| | 20 ft | VMP-14-20-091010 | 9/10/2010 | <66 | U | | <210 | U | | <110 | U | | <63 | U | | <72 | U | | <110 | U | | <100 | U | | 100 | | | <620 | U | | 700 | | | <240 | U | |
| | | VMP-14-20-091010-Dup | 9/10/2010 | <68 | U | | <220 | U | | <110 | U | | <66 | U | | <74 | U | | <120 | U | | <100 | U | | 98 | | | <640 | U | | 750 | | | <250 | U | |
| | | VMP-14-20-120110 | 12/2/2010 | <180 | U | | <560 | U | | <300 | U | | <170 | U | | <190 | U | | <300 | U | | <270 | U | | 130 | J | | <1700 | U | | 800 | | | <640 | U | |
| | | VMP-14-20-021811 | 2/18/2011 | <100 | U | | <320 | U | | <170 | U | | <96 | U | | <110 | U | | <170 | U | | <150 | U | | 47 | J | | <940 | U | | 320 | | | <360 | U | |
| | | VMP-14-20-040511 | 4/5/2011 | <43 | U | | <140 | U | | <72 | U | | <41 | U | | <47 | U | | <73 | U | | <66 | U | | 51 | | | <400 | U | | 350 | | | <160 | U | |
| | | VMP-14-20-080811 | 8/8/2011 | <16 | U | | <50 | U | | <26 | U | | <15 | U | | <17 | U | | <26 | U | | <24 | U | | 70 | | | <150 | U | | 590 | | | <56 | U | |
| | | VMP-14-20-111511 | 11/15/2011 | <81 | U | | <260 | U | | <130 | U | | <77 | U | | <88 | U | | <140 | U | | <120 | U | | 60 | J | | <760 | U | | 640 | | | <290 | U | |
| | | VMP-14-20-012612 | 1/26/2012 | <7.9 | U | | <25 | U | | <13 | U | | <7.6 | U | | <8.6 | U | | <13 | U | | <12 | U | | 79 | | J | <75 | U | | 700 | | J | <29 | U | |
| | | VMP-14-20-042312 | 4/23/2012 | <4.3 | U | | <14 | U | | <7.2 | U | | 0.38 | J | | <4.7 | U | | <7.3 | U | | <6.7 | U | | 77 | | | <41 | U | | 570 | | | <16 | U | |
| | | VMP-14-20-072512 | 7/25/2012 | <6.9 | U | | <22 | U | | <11 | U | | <6.6 | U | | <7.5 | U | | <12 | U | | <11 | U | | 61 | | | <65 | U | | 480 | | | <25 | U | |
| | | VMP-14-20-101612 | 10/16/2012 | <32 | U | | <100 | U | | <53 | U | | 12 | J | | <35 | U | | <54 | U | | <49 | U | | 49 | | | <300 | U | | 280 | | | <120 | U | |
| | | VMP-14-20-013113 | 1/31/2013 | <11 | U | | <36 | U | | 6.7 | J | | <11 | U | | <12 | U | | <19 | U | | <18 | U | | 48 | | | <110 | U | | 170 | | | <41 | U | |
| | 29 ft | VMP-14-29-021811 | 2/18/2011 | <140 | U | | <460 | U | | <240 | U | | <140 | U | | <160 | U | | <250 | U | | <220 | U | | 110 | J | | <1400 | U | | 530 | | | <520 | U | |
| | | VMP-14-29-040511 | 4/5/2011 | <120 | U | | <400 | U | | <210 | U | | <120 | U | | <140 | U | | <210 | U | | <190 | U | | 140 | | | <1200 | U | | 700 | | | <450 | U | |
| | | VMP-14-29-012612 | 1/26/2012 | <140 | U | | <450 | U | | <240 | U | | <140 | U | | <150 | U | | <240 | U | | <220 | U | | 120 | J | | <1300 | U | | 840 | | | <510 | U | |
| | | VMP-14-29-042312 | 4/23/2012 | <51 | U | | <160 | U | | <84 | U | | <49 | U | | <55 | U | | <86 | U | | <78 | U | | 110 | | | <480 | U | | 650 | | | <180 | U | |
| | | VMP-14-29-072512 | 7/25/2012 | <53 | U | | <170 | U | | <88 | U | | <51 | U | | <58 | U | | <90 | U | | <82 | U | | 100 | | | <500 | U | | 620 | | | <190 | U | |
| | | VMP-14-29-101612 | 10/16/2012 | <80 | U | | <250 | U | | <130 | U | | <76 | U | | <86 | U | | <130 | U | | <120 | U | | 48 | J | | <750 | U | | 300 | | | <290 | U | |
| | | VMP-14-29-013113-DUP | 1/31/2013 | <110 | U | | <340 | U | | <180 | U | | <100 | U | UJ | <120 | U | | <180 | U | | <160 | U | | 33 | J | J | <1000 | U | | 170 | | J | <390 | U | |
| | | VMP-14-29-013113 | 1/31/2013 | <45 | U | | <140 | U | | <74 | U | | 13 | J | J | <48 | U | | <75 | U | | <69 | U | | 250 | | J | <420 | U | | 980 | | J | <160 | U | |
| VMP-15 | 5 ft | VMP 15-5-091410 | 9/14/2010 | <0.0057 | U | | <0.018 | U | | 0.0076 | J | | <0.0055 | U | | <0.0062 | U | | <0.0096 | U | | <0.0088 | U | | 0.0059 | | | <0.054 | U | | 0.022 | | | <0.021 | U | |
| | | VMP-15-5-113010 | 11/30/2010 | <0.14 | U | | <0.43 | U | | <0.22 | U | | 0.031 | J | | <0.15 | U | | <0.23 | U | | <0.21 | U | | <0.12 | U | | <1.3 | U | | 0.12 | | | <0.49 | U | |
| | | VMP-15-5-021611 | 2/16/2011 | <0.13 | U | | <0.41 | U | | 0.13 | J | J | <0.12 | U | | <0.14 | U | | <0.22 | U | | <0.2 | U | | <0.12 | U | | <1.2 | U | | <0.099 | U | | <0.46 | U | |
| | | VMP-15-5-042011 | 4/20/2011 | <0.3 | U | | <0.95 | U | | <0.5 | U | | <0.29 | U | | <0.32 | U | | <0.5 | U | | <0.46 | U | | <0.27 | U | | <2.8 | U | | <0.23 | U | | <2.7 | U | |
| | | VMP-15-5-080811 | 8/8/2011 | <0.0067 | J | U | <0.021 | U | | 0.072 | | | 0.0016 | J | | <0.0073 | J | U | <0.011 | U | | <0.01 | U | | 0.0014 | J | | <0.063 | U | | 0.0056 | | | 0.0016 | J | |
| | | VMP-15-5-111511 | 11/15/2011 | <0.0075 | U | | <0.024 | U | | 0.026 | | | 0.0031 | J | | 0.0011 | J | | <0.013 | U | | <0.012 | U | | 0.019 | | | <0.071 | U | | 0.048 | | | <0.027 | U | |
| | | VMP-15-5-020112 | 2/1/2012 | <0.039 | U | | <0.12 | U | | 0.059 | J | | 0.025 | J | | 0.026 | J | | <0.066 | U | | <0.06 | U | | <0.035 | U | | <0.36 | U | | <0.03 | U | | <0.14 | U | |
| | | VMP-15-5-042412 | 4/24/2012 | <0.04 | U | | <0.13 | U | | <0.066 | U | | <0.038 | U | | <0.043 | U | | <0.067 | U | | <0.061 | U | | <0.036 | U | | <0.37 | U | | <0.031 | U | | <0.14 | U | |
| | | VMP-15-5-072512 | 7/25/2012 | <0.0045 | U | | <0.014 | U | | 0.049 | | | 0.0034 | J | | 0.0035 | J | | <0.0075 | U | | <0.0069 | U | | <0.004 | U | | <0.042 | U | | 0.012 | | | 0.0037 | J | |
| | | VMP-15-5-102512 | 10/25/2012 | <0.0067 | U | | <0.021 | U | | 0.038 | | | 0.0019 | J | | 0.0025 | J | | <0.011 | U | | <0.01 | U | | 0.0033 | J | | <0.063 | U | | 0.0066 | | | <0.024 | U | |
| | | VMP-15-5-020513 | 2/5/2013 | <0.0066 | U | | <0.021 | U | | 0.0033 | J | | <0.0063 | U | | <0.0071 | J | U | <0.011 | U | | <0.01 | U | | <0.0059 | U | | <0.062 | U | | <0.0051 | U | | <0.024 | U | |
| | 21.5 ft | VMP 15-21.5-091410 | 9/14/2010 | <0.62 | U | | <2 | U | | <1 | U | | <0.59 | U | | <0.67 | U | | <1 | U | | <0.96 | U | | <0.56 | U | | <5.8 | U | | <0.48 | U | | <2.2 | U | |
| | | VMP-15-21.5-113010 | 11/30/2010 | <0.73 | U | | <2.3 | U | | <1.2 | U | | <0.7 | U | | <0.79 | U | | <1.2 | U | | <1.1 | U | | <0.66 | U | | <6.8 | U | | <0.56 | U | | <2.6 | U | |
| | | VMP-15-21.5-021611 | 2/16/2011 | <0.51 | U | | <1.6 | U | | <0.84 | U | | <0.49 | U | | <0.55 | U | | <0.86 | U | | <0.78 | U | | <0.46 | U | | <4.8 | U | | 1.9 | | | <1.8 | U | |
| | | VMP-15-21.5-042011 | 4/20/2011 | <0.8 | U | | <2.5 | U | | <1.3 | U | | <0.76 | U | | <0.86 | U | | <1.3 | U | | <1.2 | U | | <0.72 | U | | <7.5 | U | | <0.62 | U | | <7.2 | U | |
| | | VMP-15-21.5-080811 | 8/8/2011 | <0.64 | U | | <2 | U | | <1.1 | U | | <0.61 | U | | <0.69 | U | | <1.1 | U | | <0.98 | U | | <0.58 | U | | <6 | U | | <0.5 | U | | <2.3 | U | |
| | | VMP-15-21.5-111511 | 11/15/2011 | <0.51 | U | | <1.6 | U | | <0.85 | U | | <0.49 | U | | <0.55 | U | | <0.86 | U | | <0.79 | U | | <0.46 | U | | <4.8 | U | | <0.4 | U | | <1.8 | U | |
| | | VMP-15-21.5-020112 | 2/1/2012 | <0.38 | U | | <1.2 | U | | <0.63 | U | | <0.36 | U | | <0.41 | U | | <0.64 | U | | <0.59 | U | | <0.34 | U | | <3.6 | U | | <0.3 | U | | <1.4 | U | |
| | | VMP-15-21.5-042412 | 4/24/2012 | <0.17 | U | | <0.53 | U | | <0.28 | U | | <0.16 | U | | <0.18 | U | | <0.28 | U | | <0.26 | U | | <0.15 | U | | <1.6 | U | | <0.13 | U | | <0.6 | U | |
| | | VMP-15-21.5-072512 | 7/25/2012 | <0.6 | U | | <1.9 | U | | <1 | U | | <0.58 | U | | <0.65 | U | | <1 | U | | <0.93 | U | | <0.54 | U | | <5.6 | U | | 0.097 | J | | <2.2 | U | |
| | | VMP-15-21.5-102512 | 10/25/2012 | <0.98 | U | | <3.1 | U | | <1.6 | U | | <0.94 | U | | <1.1 | U | | <1.6 | U | | <1.5 | U | | <0.89 | U | | <9.2 | U | | <0.76 | U | | <3.5 | U | |
| | | VMP-15-21.5-102512-Dup | 10/25/2012 | <1 | U | | <3.2 | U | | <1.7 | U | | <0.97 | U | | <1.1 | U | | <1.7 | U | | <1.6 | U | | <0.91 | U | | <9.5 | U | | <0.78 | U | | <3.6 | U | |
| | | VMP-15-21.5-020713 | 2/7/2013 | <0.025 | U | | <0.079 | U | | 0.04 | J | | <0.024 | U | | <0.027 | U | | <0.042 | U | | <0.038 | U | | 0.12 | | | <0.23 | U | | 0.41 | | | <0.09 | U | |
| | 25.5 ft | VMP 15-25.5-091410 | 9/14/2010 | <0.0058 | U | | <0.018 | U | | 0.0053 | J | | <0.0056 | U | | <0.0063 | U | | <0.0099 | U | | <0.009 | U | | 0.0039 | J | | <0.055 | U | | 0.011 | | | <0.021 | U | |
| | | VMP-15-25.5-021611 | 2/16/2011 | <0.078 | U | | <0.25 | U | | <0.13 | U | | <0.075 | U | | <0.084 | U | | <0.13 | U | | <0.12 | U | | <0.07 | U | | <0.73 | U | | <0.061 | U | | <0.28 | U | |
| | | VMP-15-25.5-042011 | 4/20/2011 | <0.064 | U | | <0.2 | U | | <0.11 | U | | <0.061 | U | | <0.069 | U | | <0.11 | U | | <0.098 | U | | <0.058 | U | | <0.6 | U | | 0.046 | J | | <0.58 | U | |
| | | VMP-15-25.5-042011-DUP | 4/20/2011 | <0.06 | U | | <0.19 | U | | <0.099 | U | | <0.057 | U | | <0.065 | U | | <0.1 | U | | <0.092 | U | | <0.054 | U | | <0.56 | U | | 0.035 | J | | <0.54 | U | |
| | | VMP-15-25.5-080811 | 8/8/2011 | <0.064 | U | | <0.2 | U | | 0.087 | J | | <0.061 | U | | <0.069 | U | | <0.11 | U | | <0.098 | U | | <0.058 | U | | <0.6 | U | | <0.05 | U | | <0.23 | U | |
| | | VMP-15-25.5-111511 | 11/15/2011 | <0.02 | U | | <0.062 | U | | 0.027 | J | | <0.019 | U | | <0.021 | U | | <0.033 | U | | <0.03 | U | | 0.013 | J | | <0.18 | U | | 0.097 | | | <0.071 | U | |
| | | VMP-15-25.5-073112 | 7/31/2012 | <0.042 | U | | <0.13 | U | | 0.052 | J | J | <0.04 | U | | <0.045 | U | | <0.07 | U | | <0.064 | U | | <0.037 | U | | <0.39 | U | | <0.032 | U | | <0.15 | U | |
| | | VMP-15-25.5-102512 | 10/25/2012 | <0.0067 | U | | <0.021 | U | | 0.065 | | | <0.0064 | U | | 0.0017 | J | | <0.011 | U | | <0.01 | U | | <0.0061 | U | | <0.063 | U | | <0.0052 | U | | <0.024 | U | |
| | | VMP-15-25.5-021213 | 2/12/2013 | <0.2 | U | | <0.65 | U | | <0.34 | U | | <0.19 | U | | <0.22 | U | | <0.34 | U | | <0.31 | U | | <0.18 | U | | <1.9 | U | | <0.16 | U | | <0.73 | U | |
| | 29 ft | VMP-15-29-073112 | 7/31/2012 | <0.18 | U | | <0.56 | U | | <0.3 | U | | <0.17 | U | | <0.19 | U | | <0.3 | U | | <0.27 | U | | <0.16 | U | | <1.7 | U | | <0.14 | U | | <0.64 | U | |
| | | VMP-15-29-102512 | 10/25/2012 | <0.014 | U | | <0.044 | U | | 0.086 | | | <0.013 | U | | 0.0023 | J | | <0.024 | U | | <0.022 | U | | <0.013 | U | | <0.13 | U | | 0.013 | | | <0.051 | U | |
| | | VMP-15-29-021213 | 2/12/2013 | <0.12 | U | | <0.39 | U | | <0.2 | U | | <0.12 | U | | <0.13 | U | | <0.21 | U | | <0.19 | U | | <0.11 | U | | <1.1 | U | | <0.095 | U | | <0.44 | U | |

**TABLE 6**
**CUMULATIVE SUMMARY OF SOIL VAPOR ANALYTICAL DETECTIONS AND SCREENING RESULTS: PUBLIC WORKS YARD AND WRR - VOCS**

| Location | Depth | Sample ID | Sample Date | trans-1,3-Dichloropropene 6.2 | | | 1,4-Dioxane 2.3 | | | Ethanol | | | Ethylbenzene 8300 | | | 4-Ethyltoluene | | | Freon 113 | | | Freon 114 | | | Heptane | | | Hexachlorobutadiene | | | Hexane | | | 2-Hexanone (Methyl N-Butyl | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals |
| VMP-16 | 5 ft | VMP-16-5-090210 | 9/2/2010 | <11 | U | | <34 | U | | <18 | U | | 12 | | | 2.5 | J | | <18 | U | | <17 | U | | 14 | | | <100 | U | | 6.3 | J | | <39 | U | |
| | | VMP-16-5-112910 | 11/29/2010 | <4.9 | U | | <16 | U | | <8.2 | U | | 7.5 | | J | <5.4 | U | | <8.4 | U | | <7.6 | U | | <4.5 | U | | <46 | U | | <3.8 | U | | <18 | U | |
| | | VMP-16-5-021511 | 2/15/2011 | <3 | U | | <9.5 | U | | <5 | U | | <2.9 | U | | <3.2 | U | | <5 | U | | <4.6 | U | | <2.7 | U | | <28 | U | | 45 | | J | <11 | U | |
| | | VMP-16-5-042211 | 4/22/2011 | <4 | U | | <13 | U | | <6.6 | U | | <3.8 | U | | <4.3 | U | | <6.7 | U | | <6.2 | U | | <3.6 | U | | <38 | U | | 4.8 | | | <36 | U | |
| | | VMP-16-5-080511 | 8/5/2011 | <1.3 | U | | <4 | U | | <2.1 | U | | <1.2 | U | | <1.4 | U | | <2.2 | U | | <2 | U | | <1.2 | U | | <12 | U | | 1.4 | | | <4.6 | U | |
| | | VMP-16-5-042512 | 4/25/2012 | <4.3 | U | | <14 | U | | <7.2 | U | | <4.1 | U | | <4.7 | U | | <7.3 | U | | <6.7 | U | | <3.9 | U | | <41 | U | | <3.4 | U | | <16 | U | |
| | | VMP-16-5-073012 | 7/30/2012 | <4.1 | U | | <13 | U | | <6.7 | U | | 0.64 | J | J | <4.4 | U | | <6.8 | U | | <6.2 | U | | <3.7 | U | | <38 | U | | <3.2 | U | | <15 | U | |
| | | VMP-16-5-102512 | 10/25/2012 | <3.2 | U | | <10 | U | | <5.3 | U | | <3.1 | U | | <3.5 | U | | <5.4 | U | | <4.9 | U | | <2.9 | U | | <30 | U | | <2.5 | U | | <12 | U | |
| | | VMP-16-5-021413 | 2/14/2013 | <0.5 | U | | <1.6 | U | | <0.83 | U | | <0.48 | U | | <0.54 | U | | <0.84 | U | | <0.77 | U | | <0.45 | U | | <4.7 | U | | <0.39 | U | | <1.8 | U | |
| | 13.5 ft | VMP-16-13.5-090210 | 9/2/2010 | <11 | U | | <36 | U | | <19 | U | | 15 | | | 3.4 | J | | <19 | U | | <17 | U | | 13 | | | <100 | U | | 6.6 | J | J | <40 | U | |
| | | VMP-16-13.5-090210-DUP | 9/2/2010 | <11 | U | | <36 | U | | <19 | U | | 15 | | | 2.9 | J | | <19 | U | | <17 | U | | 12 | | | <100 | U | | 9.7 | | J | <40 | U | |
| | | VMP-16-13.5-112910 | 11/29/2010 | <32 | U | | <100 | U | | <53 | U | | 9.9 | J | | <34 | U | | <54 | U | | <49 | U | | <29 | U | | <300 | U | | <25 | U | | <110 | U | |
| | | VMP-16-13.5-021611 | 2/16/2011 | <6.1 | U | | <19 | U | | <10 | U | | <5.8 | U | | <6.6 | U | | <10 | U | | <9.4 | U | | <5.5 | U | | <57 | U | | 12 | | | <22 | U | |
| | | VMP-16-13.5-021611-DUP | 2/16/2011 | <6 | U | | <19 | U | | <9.9 | U | | <5.7 | U | | <6.5 | U | | <10 | U | | <9.2 | U | | <5.4 | U | | <56 | U | | 10 | | | <22 | U | |
| | | VMP-16-13.5-042211 | 4/22/2011 | <6.4 | U | | <20 | U | | <11 | U | | <6.2 | U | | <7 | U | | <11 | U | | <9.9 | U | | <5.8 | U | | <60 | U | | 5 | | | <58 | U | |
| | | VMP-16-13.5-080511 | 8/5/2011 | <0.63 | U | UJ | <2 | U | UJ | <1 | U | UJ | <0.6 | U | UJ | <0.68 | U | UJ | <1 | U | UJ | <0.96 | U | UJ | <0.56 | U | UJ | <5.9 | U | UJ | 5.8 | | J | <2.3 | U | UJ |
| | | VMP-16-13.5-042512 | 4/25/2012 | <0.69 | U | | <2.2 | U | | <1.1 | U | | 3.2 | | J | 0.39 | J | J | <1.2 | U | | <1.1 | U | | <0.62 | U | | <6.5 | U | | <0.54 | U | | <2.5 | U | |
| | | VMP-16-13.5-073012 | 7/30/2012 | <21 | U | | <66 | U | | <34 | U | | <20 | U | | <22 | U | | <35 | U | | <32 | U | | <19 | U | | <200 | U | | 9 | J | | <75 | U | |
| | | VMP-16-13.5-102512 | 10/25/2012 | <64 | U | | <200 | U | | <110 | U | | <61 | U | | <69 | U | | <110 | U | | <98 | U | | <58 | U | | <600 | U | | <50 | U | | <230 | U | |
| | | VMP-16-13.5-021413 | 2/14/2013 | <10 | U | | <32 | U | | <17 | U | | 4 | J | J | <11 | U | | 3 | J | J | <16 | U | | <9.2 | U | | <96 | U | | 6.1 | J | J | <37 | U | |
| | 19 ft | VMP-16-19-090210 | 9/2/2010 | <11 | U | | <36 | U | | <19 | U | | 23 | | | 3.2 | J | | <19 | U | | <17 | U | | 14 | | | <100 | U | | 7.5 | J | | <40 | U | |
| | | VMP-16-19-112910 | 11/29/2010 | <24 | U | | <78 | U | | <41 | U | | 14 | J | | <26 | U | | <41 | U | | <38 | U | | <22 | U | | <230 | U | | <19 | U | | <88 | U | |
| | | VMP-16-19-021611 | 2/16/2011 | <5.8 | U | | <18 | U | | <9.7 | U | | <5.6 | U | | <6.3 | U | | <9.9 | U | | <9 | U | | <5.3 | U | | <55 | U | | 7.4 | | | <21 | U | |
| | | VMP-16-19-042711 | 4/27/2011 | <6 | U | | <19 | U | | <9.9 | U | | <5.7 | U | | <6.5 | U | | <10 | U | | <9.2 | U | | <5.4 | U | | <56 | U | | 1.8 | J | | <54 | U | |
| | | VMP-16-19-042711-DUP | 4/27/2011 | <5.8 | U | | <18 | U | | <9.7 | U | | <5.6 | U | | <6.3 | U | | <9.9 | U | | <9 | U | | <5.3 | U | | <55 | U | | 1.7 | J | | <53 | U | |
| | | VMP-16-19-042512 | p | <16 | U | | <51 | U | | <27 | U | | 7.3 | J | | <17 | U | | <27 | U | | <25 | U | | <14 | U | | <150 | U | | <12 | U | | <58 | U | |
| | | VMP-16-19-073012 | 7/30/2012 | <14 | U | | <46 | U | | <24 | U | | 12 | J | | <16 | U | | <24 | U | | <22 | U | | <13 | U | | <130 | U | | 4.9 | J | | <52 | U | |
| | | VMP-16-19-102512 | 10/25/2012 | <60 | U | | <190 | U | | <99 | U | | <57 | U | | <65 | U | | <100 | U | | <92 | U | | <54 | U | | <560 | U | | <46 | U | | <220 | U | |
| | | VMP-16-19-021413 | 2/14/2013 | <6 | U | | <19 | U | | <9.9 | U | | 88 | | J | 8.8 | | J | <10 | U | | <9.2 | U | | <5.4 | U | | <56 | U | | 4 | J | J | <22 | U | |
| | 31 ft | VMP-16-31-090310 | 9/3/2010 | <0.0066 | U | | <0.021 | U | | 0.014 | | | 0.002 | J | | <0.0071 | U | | <0.011 | U | | <0.01 | U | | <0.0059 | U | | <0.062 | U | | 0.0028 | J | | <0.024 | U | |
| | | VMP-16-31-112910 | 11/29/2010 | <25 | U | | <78 | U | | <41 | U | | 15 | J | | <27 | U | | <42 | U | | <38 | U | | <22 | U | | <230 | U | | <19 | U | | <89 | U | |
| | | VMP-16-31-042512 | 4/25/2012 | <19 | U | | <62 | U | | <32 | U | | 3.4 | J | | <21 | U | | <33 | U | | <30 | U | | <18 | U | | <180 | U | | <15 | U | | <70 | U | |
| | | VMP-16-31-073012 | 7/30/2012 | <16 | U | | <50 | U | | 6 | J | J | <15 | U | | <17 | U | | <27 | U | | <24 | U | | <14 | U | | <150 | U | | 5.6 | J | | <57 | U | |
| | | VMP-16-31-102512 | 10/25/2012 | <74 | U | | <240 | U | | <120 | U | | <71 | U | | <81 | U | | <120 | U | | <110 | U | | <67 | U | | <700 | U | | <58 | U | | <270 | U | |
| | | VMP-16-31-021813 | 2/18/2013 | <23 | U | | <72 | U | | <38 | U | | 43 | | | <24 | U | | <38 | U | | <35 | U | | <20 | U | | <210 | U | | 3 | J | | <82 | U | |
| VMP-17 | 5 ft | VMP-17-5 | 6/21/2010 | <0.006 | U | | <0.021 | U | | <0.011 | U | | <0.006 | U | | <0.007 | U | | <0.011 | U | | <0.01 | U | | 0.023 | | | <0.062 | U | | 0.41 | | | <0.024 | U | |
| | | VMP-17-5-DUP | 6/21/2010 | <0.006 | U | | <0.022 | U | | <0.011 | U | | <0.006 | U | | <0.007 | U | | <0.011 | U | | <0.01 | U | | 0.019 | | | <0.064 | U | | 0.35 | | | <0.024 | U | |
| | | VMP-17-5-090110 | 9/1/2010 | <0.0061 | U | | 0.0033 | J | | 0.022 | | | 0.0039 | J | J | <0.0066 | U | | <0.01 | U | U | <0.0094 | U | | 0.043 | | | <0.057 | U | UJ | 0.088 | | | <0.022 | U | |
| | | VMP-17-5-112210 | 11/22/2010 | <0.0061 | U | | 0.0036 | J | | 0.011 | | | <0.0058 | U | | <0.0066 | U | | <0.01 | U | | <0.0094 | U | | <0.0055 | U | | <0.057 | U | | 0.0013 | J | | <0.022 | U | |
| | | VMP-17-5-020711 | 2/7/2011 | <0.0057 | U | | 0.0034 | J | | <0.0095 | U | | <0.0055 | U | | <0.0062 | U | | <0.0096 | U | | <0.0088 | U | | 0.016 | | | <0.054 | U | | 0.02 | | | <0.021 | U | |
| | | VMP-17-5-040611 | 4/6/2011 | <0.023 | U | | <0.073 | U | | <0.038 | U | | <0.022 | U | | <0.025 | U | | <0.039 | U | | <0.035 | U | | 0.025 | | | <0.22 | U | | 0.11 | | | <0.083 | U | |
| | | VMP-17-5-080111 | 8/1/2011 | <0.087 | U | | <0.28 | U | | 0.17 | | | <0.084 | U | | <0.095 | U | | <0.15 | U | | <0.13 | U | | 0.028 | J | | <0.82 | U | | 0.24 | | | <0.32 | U | |
| | | VMP-17-5-110711 | 11/7/2011 | <0.0039 | U | | <0.012 | U | | 0.044 | | | <0.0037 | U | | <0.0042 | J | U | <0.0066 | U | | <0.006 | U | | 0.0009 | J | | <0.036 | U | | 0.00088 | J | | 0.00053 | J | |
| | | VMP-17-5-012612 | 1/26/2012 | <0.0041 | U | | <0.013 | U | | 0.0099 | | | 0.0012 | J | | <0.0044 | U | | <0.0068 | U | | <0.0062 | U | | <0.0037 | U | | <0.038 | U | | 0.00056 | J | | <0.015 | U | |
| | | VMP-17-5-041112 | 4/11/2012 | <0.0042 | U | | <0.013 | U | | 0.015 | | | 0.0023 | J | | <0.0045 | U | | <0.007 | U | | <0.0064 | U | | 0.0022 | J | | <0.039 | U | | 0.0025 | J | | <0.015 | U | |
| | | VMP-17-5-071112 | 7/11/2012 | <0.0044 | U | | <0.014 | U | | 0.064 | | | 0.0031 | J | | <0.0048 | J | U | <0.0075 | U | | <0.0068 | U | | 0.0035 | J | | <0.042 | U | | 0.0047 | | | <0.016 | J | U |
| | | VMP-17-5-100912 | 10/9/2012 | <0.0069 | U | | <0.022 | U | | 0.0052 | J | | <0.0066 | U | | 0.0045 | J | | <0.012 | U | | <0.01 | U | | <0.0062 | U | | <0.065 | U | | <0.0053 | U | | <0.025 | U | |
| | | VMP-17-5-013113 | 1/31/2013 | <0.024 | U | | <0.076 | U | | <0.04 | U | | 0.0047 | J | | 0.0096 | J | | <0.041 | U | | <0.037 | U | | <0.022 | U | | <0.23 | U | | 0.0065 | J | | <0.087 | U | |
| | | VMP-17-5-013113-DUP | 1/31/2013 | <0.024 | U | | <0.076 | U | | <0.04 | U | | <0.023 | U | | 0.0055 | J | | <0.041 | U | | <0.037 | U | | 0.0063 | J | | <0.23 | U | | 0.015 | J | | <0.087 | U | |
| VMP-25 | 5 ft | VMP-25-5-031511 | 3/15/2011 | <0.055 | U | | <0.17 | U | | <0.091 | U | | 0.07 | | | 0.12 | | | <0.093 | U | | <0.084 | U | | 0.6 | | | <0.52 | U | | 1.3 | | | <0.2 | U | |
| | | VMP-25-5-040811 | 4/8/2011 | <0.025 | U | | <0.079 | U | | 0.033 | J | | <0.024 | U | | <0.027 | U | | <0.042 | U | | <0.038 | U | | <0.022 | U | | <0.23 | U | | 0.093 | | | <0.09 | U | |
| | | VMP-25-5-080911 | 8/9/2011 | <0.0053 | J | U | <0.017 | U | | 0.1 | | | 0.01 | | | <0.0057 | J | U | <0.0089 | U | | <0.0081 | U | | 0.034 | | | <0.05 | U | | 0.1 | | | <0.019 | U | |
| | | VMP-25-5-111711 | 11/17/2011 | <0.0038 | U | | <0.012 | U | | 0.0071 | | | <0.0036 | U | | <0.0041 | U | | <0.0064 | U | | <0.0059 | U | | <0.0034 | U | | <0.036 | U | | <0.003 | U | | <0.014 | U | |
| | | VMP-25-5-013112 | 1/31/2012 | <0.028 | U | | <0.088 | U | | <0.046 | U | | 0.0044 | J | | <0.03 | U | | <0.047 | U | | <0.043 | U | | 0.072 | | | <0.26 | U | | 0.41 | | | <0.1 | U | |
| | | VMP-25-5-042512 | 4/25/2012 | <0.0043 | U | | <0.014 | U | | 0.058 | | | 0.003 | J | | 0.0019 | J | | <0.0073 | U | | <0.0067 | U | | 0.0016 | J | | <0.041 | U | | 0.0024 | J | | <0.016 | U | |
| | | VMP-25-5-072612 | 7/26/2012 | <0.015 | U | | <0.047 | U | | 0.019 | J | | 0.014 | | | 0.01 | J | | <0.025 | U | | <0.023 | U | | 0.18 | | | <0.14 | U | | 0.51 | | | <0.054 | U | |
| | | VMP-25-5-102612 | 10/26/2012 | <0.0061 | U | | <0.019 | U | | 0.048 | | | <0.0058 | U | | <0.0066 | U | | <0.01 | U | | <0.0094 | U | | <0.0055 | U | | <0.057 | U | | <0.0047 | U | | <0.022 | U | |
| | | VMP-25-5-030613 | 3/6/2013 | <0.0058 | J | U | <0.018 | U | | 0.0069 | J | | 0.0023 | J | | 0.0018 | J | | <0.0098 | U | | <0.009 | U | | <0.0053 | U | | <0.055 | U | | 0.0023 | J | | <0.021 | U | |
| | 21 ft | VMP-25-21-031511 | 3/15/2011 | <11 | U | | <34 | U | | 12 | J | | 11 | | | 1.7 | J | | <18 | U | | <16 | U | | 420 | | J | <100 | U | | 1700 | | J | <39 | U | |
| | | VMP-25-21-031511-DUP | 3/15/2011 | <14 | U | | <44 | U | | 14 | J | | 11 | J | | <15 | U | | <23 | U | | <21 | U | | 650 | | J | <130 | U | | 2700 | | J | <50 | U | |
| | | VMP-25-21-040811 | 4/8/2011 | <110 | U | | <360 | U | | <190 | U | | <110 | U | | <120 | U | | <190 | U | | <180 | U | | 480 | | | <1100 | U | | 2100 | | | <410 | U | |
| | | VMP-25-21-040811-DUP | 4/8/2011 | <120 | U | | <370 | U | | <190 | U | | <110 | U | | <120 | U | | <200 | U | | <180 | U | | 510 | | | <1100 | U | | 2100 | | | <420 | U | |
| | | VMP-25-21-080911 | 8/9/2011 | <37 | U | | <120 | U | | <62 | U | | 210 | | | 190 | | | <63 | U | | <58 | U | | 700 | | | <350 | U | | 2800 | | | <140 | U | |
| | | VMP-25-21-111711 | 11/17/2011 | <51 | U | | <160 | U | | <85 | U | | <49 | U | | <55 | U | | <86 | U | | <79 | U | | 120 | | | <480 | U | | 840 | | | <180 | U | |
| | | VMP-25-21-111711-DUP | 11/17/2011 | <75 | U | | <240 | U | | <120 | U | | <72 | U | | <82 | U | | <130 | U | | <120 | U | | 110 | | | <710 | U | | 800 | | | <270 | U | |
| | | VMP-25-21-013112 | 1/31/2012 | <26 | U | | <84 | U | | <44 | U | | <25 | U | | <29 | U | | <45 | U | | <41 | U | | 310 | | | <250 | U | | 1700 | | | <96 | U | |
| | | VMP-25-21-013112-DUP | 2/1/2012 | <25 | U | | <78 | U | | <41 | U | | <24 | U | | <27 | U | | <42 | U | | <38 | U | | 370 | | | <230 | U | | 1900 | | | <89 | U | |
| | | VMP-25-21-042512 | 4/25/2012 | <17 | U | | <54 | U | | <28 | U | | <16 | U | | <18 | U | | <28 | U | | <26 | U | | 300 | | | <160 | U | | 1900 | | | <61 | U | |
| | | VMP-25-21-072612 | 7/26/2012 | <28 | U | | <91 | U | | <47 | U | | <27 | U | | <31 | U | | <48 | U | | <44 | U | | 330 | | | <270 | U | | 2200 | | | <100 | U | |
| | | VMP-25-21-102612 | 10/26/2012 | <170 | U | | <540 | U | | <280 | U | | <160 | U | | <180 | U | | <290 | U | | <260 | U | | 350 | | | <1600 | U | | 2000 | | | <620 | U | |
| | | VMP-25-21-030613 | 3/6/2013 | <44 | U | | <140 | U | | <72 | U | | <42 | U | | <47 | U | | <74 | U | | <67 | U | | 530 | | | <410 | U | | 2200 | | | <160 | U | |
| | 31 ft | VMP-25-31-030613 | 3/6/2013 | <58 | U | | <180 | U | | 15 | J | | <55 | U | | <62 | U | | <97 | U | | <89 | U | | 60 | | | <540 | U | | 280 | | | <210 | U | |

SEE LAST PAGE OF TABLE FOR NOTES

**TABLE 6**
**CUMULATIVE SUMMARY OF SOIL VAPOR ANALYTICAL DETECTIONS AND SCREENING RESULTS: PUBLIC WORKS YARD AND WRR - VOCS**

| Location | Depth | Sample ID | Sample Date | trans-1,3-Dichloropropene | | | 1,4-Dioxane | | | Ethanol | | | Ethylbenzene | | | 4-Ethyltoluene | | | Freon 113 | | | Freon 114 | | | Heptane | | | Hexachlorobutadiene | | | Hexane | | | 2-Hexanone (Methyl N-Butyl | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | 6.2 | | | 2.3 | | | | | | 8300 | | | | | | | | | | | | | | | | | | | | | | | |
| | | | | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals |
| VMP-29 | 10 ft | VMP-29-10-073012 | 7/30/2012 | <0.048 | U | | <0.15 | U | | 0.034 | J | | <0.046 | U | | <0.052 | U | | <0.081 | U | | <0.074 | U | | <0.043 | U | | <0.45 | U | | <0.037 | U | | <0.17 | U | |
| | | VMP-29-10-100812 | 10/8/2012 | <0.085 | U | | <0.27 | U | | <0.14 | U | | <0.082 | U | | <0.092 | U | | <0.14 | U | | <0.13 | U | | <0.077 | U | | <0.8 | U | | <0.066 | U | | <0.31 | U | |
| | | VMP-29-10-020613 | 2/6/2013 | <0.0064 | U | | <0.02 | U | | 0.018 | | | <0.0061 | U | | <0.0069 | U | | <0.011 | U | | <0.0098 | U | | <0.0058 | U | | <0.06 | U | | <0.005 | U | | <0.023 | U | |
| | 20 ft | VMP-29-20-073012 | 7/30/2012 | <0.57 | U | | <1.8 | U | | 0.3 | J | | <0.54 | U | | <0.62 | U | | <0.96 | U | | <0.88 | U | | <0.51 | U | | <5.4 | U | | <0.44 | U | | <2 | U | |
| | | VMP-29-20-073012-Dup | 7/30/2012 | <0.53 | U | | <1.7 | U | | 0.19 | J | | <0.51 | U | | <0.58 | U | | <0.9 | U | | <0.82 | U | | <0.48 | U | | <5 | U | | <0.41 | U | | <1.9 | U | |
| | | VMP-29-20-100812 | 10/8/2012 | <0.085 | U | | <0.27 | U | | 0.077 | J | | <0.082 | U | | <0.092 | U | | <0.14 | U | | <0.13 | U | | <0.077 | U | | <0.8 | U | | <0.066 | U | | <0.31 | U | |
| | | VMP-29-20-020613 | 2/6/2013 | <0.0063 | U | | <0.02 | U | | 0.01 | J | | <0.006 | U | | <0.0068 | J | U | <0.01 | U | | <0.0096 | U | | <0.0056 | U | | <0.059 | U | | 0.0012 | J | | <0.023 | U | |
| | 30 ft | VMP-29-30-073012 | 7/30/2012 | <0.093 | U | | <0.3 | U | | 0.18 | | | <0.089 | U | | <0.1 | U | | <0.16 | U | | <0.14 | U | | <0.084 | U | | <0.88 | U | | <0.073 | U | | <0.34 | U | |
| | | VMP-29-30-100812 | 10/8/2012 | <0.42 | U | | <1.3 | U | | <0.7 | U | | <0.4 | U | | <0.45 | U | | <0.71 | U | | <0.65 | U | | <0.38 | U | | <3.9 | U | | 0.1 | J | | <1.5 | U | |
| | | VMP-29-30-020613 | 2/6/2013 | <0.0066 | U | | 0.019 | J | | 0.012 | | | <0.0063 | U | | <0.0071 | J | U | <0.011 | U | | <0.01 | U | | <0.0059 | U | | <0.062 | U | | 0.00089 | J | | <0.024 | U | |
| VMP-30 | 10 ft | VMP-30-10-073012 | 7/30/2012 | <0.17 | U | | <0.54 | U | | <0.28 | U | | <0.16 | U | | <0.18 | U | | <0.29 | U | | <0.26 | U | | <0.15 | U | | <1.6 | U | | <0.13 | U | | <0.61 | U | |
| | | VMP-30-10-100812 | 10/8/2012 | <0.0064 | U | | <0.02 | U | | 0.022 | | | <0.0061 | U | | <0.0069 | U | | <0.011 | U | | <0.0098 | U | | 0.0028 | J | | <0.06 | U | | 0.00099 | J | | <0.023 | U | |
| | | VMP-30-10-020613 | 2/6/2013 | <0.006 | U | | <0.019 | U | | 0.0046 | J | | <0.0057 | U | | <0.0065 | U | | <0.01 | U | | <0.0092 | U | | 0.0014 | J | | <0.056 | U | | 0.0022 | J | | <0.022 | U | |
| | 20 ft | VMP-30-20-073012 | 7/30/2012 | <0.72 | U | | <2.3 | U | | <1.2 | U | | <0.69 | U | | <0.78 | U | | <1.2 | U | | <1.1 | U | | <0.65 | U | | <6.8 | U | | <0.56 | U | | <2.6 | U | |
| | | VMP-30-20-100812 | 10/8/2012 | <0.26 | U | | <0.84 | U | | 0.25 | J | | <0.25 | U | | <0.28 | U | | <0.44 | U | | <0.4 | U | | <0.24 | U | | <2.5 | U | | <0.2 | U | | <0.95 | U | |
| | | VMP-30-20-020613 | 2/6/2013 | <0.006 | U | | <0.019 | U | | 0.008 | J | | <0.0057 | U | | <0.0065 | J | U | <0.01 | U | | <0.0092 | U | | <0.0054 | U | | <0.056 | J | U | 0.0025 | J | | <0.022 | U | |
| | 30 ft | VMP-30-30-073012 | 7/30/2012 | <0.74 | U | | <2.4 | U | | <1.2 | U | | <0.71 | U | | <0.8 | U | | <1.2 | U | | <1.1 | U | | <0.67 | U | | <7 | U | | <0.58 | U | | <2.7 | U | |
| | | VMP-30-30-100812 | 10/8/2012 | <0.55 | U | | <1.7 | U | | <0.91 | U | | <0.52 | U | | <0.59 | U | | <0.92 | U | | <0.84 | U | | <0.49 | U | | <5.1 | U | | 0.11 | J | | <2 | U | |
| | | VMP-30-30-020613 | 2/6/2013 | <0.02 | U | | <0.063 | U | | 0.0044 | J | | <0.019 | U | | <0.022 | U | | <0.034 | U | | <0.031 | U | | <0.018 | U | | <0.19 | U | | <0.016 | U | | <0.072 | U | |
| VMP-41 | 10 ft | VMP-41-10-072712 | 7/27/2012 | <0.0055 | U | | <0.018 | U | | 0.072 | | | 0.0059 | | | 0.0015 | J | | <0.0093 | U | | <0.0085 | U | | 0.0099 | | | <0.052 | U | | 0.011 | | | 0.0028 | J | |
| | | VMP-41-10-100912 | 10/9/2012 | <0.0067 | U | | <0.021 | U | | 0.035 | | | <0.0064 | U | | <0.0073 | U | | <0.011 | U | | <0.01 | U | | 0.0025 | J | | <0.063 | U | | <0.0052 | U | | <0.024 | U | |
| | | VMP-41-10-012913 | 1/29/2013 | <0.0067 | U | | <0.021 | U | | <0.011 | U | | <0.0064 | U | | <0.0073 | U | | <0.011 | U | | <0.01 | U | | <0.0061 | U | | <0.063 | U | | <0.0052 | U | | <0.024 | U | |
| | 20 ft | VMP-41-20-072712 | 7/27/2012 | <0.0042 | U | | <0.013 | U | | 0.042 | | | 0.003 | J | | 0.0009 | J | | <0.0072 | U | | <0.0065 | U | | 0.0028 | J | | <0.04 | U | | <0.0033 | U | | 0.0017 | J | |
| | | VMP-41-20-072712-Dup | 7/27/2012 | <0.0043 | U | | <0.014 | U | | 0.028 | | | 0.003 | J | | 0.00079 | J | | <0.0073 | U | | <0.0067 | U | | 0.0015 | J | | <0.041 | U | | 0.00086 | J | | 0.0014 | J | |
| | | VMP-41-20-100912 | 10/9/2012 | <0.0066 | U | | <0.021 | U | | 0.031 | | | <0.0063 | U | | <0.0071 | U | | <0.011 | U | | <0.01 | U | | 0.0024 | J | | <0.062 | U | | 0.001 | J | | 0.0014 | J | |
| | | VMP-41-20-100912-Dup | 10/9/2012 | <0.0067 | J | U | <0.021 | U | | 0.032 | | | <0.0064 | U | | <0.0073 | U | | <0.011 | U | | <0.01 | U | | 0.002 | J | | <0.063 | J | U | <0.0052 | U | | <0.024 | U | |
| | | VMP-41-20-012913 | 1/29/2013 | <0.0069 | U | | <0.022 | U | | <0.011 | U | | <0.0066 | U | | <0.0074 | U | | <0.012 | U | | <0.01 | U | | <0.0062 | U | | <0.065 | U | | 0.0017 | J | | <0.025 | U | |
| | 30 ft | VMP-41-30-072712 | 7/27/2012 | <0.0043 | U | | <0.014 | U | | 0.12 | | | 0.0032 | J | | 0.00082 | J | | <0.0073 | U | | <0.0067 | U | | 0.0081 | | | <0.041 | U | | 0.0062 | | | 0.0039 | J | |
| | | VMP-41-30-100912 | 10/9/2012 | <0.007 | U | | <0.022 | U | | 0.024 | | | <0.0068 | U | | <0.0076 | U | | <0.012 | U | | <0.011 | U | | 0.0024 | J | | <0.066 | U | | 0.0013 | J | | <0.025 | U | |
| | | VMP-41-30-012913 | 1/29/2013 | <0.0064 | U | | <0.02 | U | | 0.0054 | J | | <0.0061 | U | | <0.0069 | U | | <0.011 | U | | <0.0098 | U | | 0.0082 | | | <0.06 | U | | 0.0088 | | | <0.023 | U | |
| VMP-55 | 20 ft | VMP-55-20-021513 | 2/15/2013 | <16 | U | | <50 | U | | <26 | U | | <15 | U | | <17 | U | | <26 | U | | <24 | U | | <14 | U | | <150 | U | | 42 | | | <56 | U | |

SEE LAST PAGE OF TABLE FOR NOTES

**TABLE 6**
**CUMULATIVE SUMMARY OF SOIL VAPOR ANALYTICAL DETECTIONS AND SCREENING RESULTS: PUBLIC WORKS YARD AND WRR - VOCS**

| Location | Depth | Sample ID | Sample Date | Isopentane | | | Isopropylbenzene (Cumene) 3500 | | | 4-Methyl-2-pentanone (Methyl | | | Methyl tert-Butyl Ether (MTBE) 23000 | | | 2-Propanol | | | n-Propylbenzene | | | Styrene 8500 | | | 1,1,2,2-Tetrachloroethane | | | Tetrachloroethene 4 | | | Tetrahydrofuran | | | Toluene 40000 | | | 1,2,4-Trichlorobenzene 50 | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals |
| VMP-10 | 5 ft | VMP-10-5-090710 | 9/7/2010 | | | | 0.002 | J | | 0.0016 | J | | <0.0048 | U | | 0.02 | | | 0.0035 | J | | 0.0029 | J | | <0.0091 | U | | 0.0017 | J | | <0.0039 | U | | 0.014 | | | <0.039 | U | |
| | | VMP-10-5-111810 | 11/17/2010 | | | | <0.0059 | U | | <0.005 | U | | 0.00036 | J | | <0.012 | U | | <0.0059 | U | | 0.0024 | J | | <0.0083 | U | | <0.0082 | J | U | <0.0036 | U | | <0.0046 | U | | <0.036 | U | |
| | | VMP-10-5-021011 | 2/10/2011 | | | | <0.0058 | U | | <0.0049 | U | | <0.0043 | U | | 0.0058 | J | | <0.0058 | U | | <0.0051 | U | | <0.0082 | U | | <0.0081 | U | | <0.0035 | U | | 0.0028 | J | | <0.035 | U | |
| | | VMP-10-5-040511 | 4/5/2011 | 0.017 | | | 0.013 | | | 0.039 | | | 0.00036 | J | | 0.065 | | | <0.0054 | J | U | <0.0047 | U | | <0.0076 | U | | <0.0075 | J | U | 0.0062 | | | 0.0082 | | | <0.033 | J | U |
| | | VMP-10-5-072911 | 7/29/2011 | <0.016 | U | | 0.013 | | | 0.066 | | | <0.0048 | U | | 0.023 | | | <0.0066 | U | | 0.00097 | J | | <0.0092 | U | | <0.0091 | U | | 0.0014 | J | | 0.009 | | | <0.04 | U | |
| | | VMP-10-5-110411 | 11/4/2011 | <0.0082 | U | | 0.0046 | | | 0.026 | | | <0.0025 | U | | 0.016 | | | <0.0034 | U | | <0.003 | U | | <0.0048 | U | | <0.0047 | U | | 0.011 | | | <0.002 | U | | <0.021 | U | |
| | | VMP-10-5-012512 | 1/26/2012 | 0.0072 | J | | 0.0015 | J | | 0.027 | | | <0.0032 | U | | 0.0024 | J | | <0.0043 | U | | <0.0037 | U | | <0.006 | U | | 0.0018 | J | | <0.0026 | U | | 0.0037 | | | <0.026 | U | |
| | | VMP-10-5-041212 | 4/12/2012 | 0.024 | | | <0.0046 | U | | <0.0038 | U | | <0.0034 | U | | 0.073 | | | <0.0046 | U | | <0.004 | U | | <0.0064 | U | | <0.0064 | U | | 0.016 | | | 0.032 | | | <0.028 | U | |
| | | VMP-10-5-071312 | 7/13/2012 | <0.011 | U | | <0.0047 | J | U | <0.004 | J | U | <0.0035 | U | | 0.0023 | J | | <0.0047 | U | | <0.0041 | U | | <0.0066 | U | | <0.0065 | U | | 0.0073 | | | <0.0036 | J | U | <0.029 | U | |
| | | VMP-10-5-101612 | 10/16/2012 | 0.19 | | | 0.0031 | J | | <0.0062 | U | | <0.0055 | U | | <0.015 | U | | <0.0074 | J | U | <0.0064 | U | | <0.01 | U | | <0.01 | U | | <0.0045 | U | | 0.0014 | J | | <0.045 | U | |
| | | VMP-10-5-012913 | 1/29/2013 | 0.038 | | J | <0.0069 | U | | 0.0015 | J | | <0.0051 | U | | 0.0072 | J | | <0.0069 | U | | <0.006 | U | | <0.0097 | U | | <0.0096 | J | U | <0.0042 | U | | <0.0053 | J | U | <0.042 | J | U |
| | | VMP-10-5-012913-DUP | 1/29/2013 | 0.067 | | J | <0.0076 | U | | <0.0064 | U | | <0.0056 | U | | 0.0025 | J | | <0.0076 | U | | <0.0066 | U | | <0.011 | U | | <0.01 | J | U | <0.0046 | U | | <0.0058 | J | U | <0.046 | J | U |
| | 10 ft | VMP-10-10-090710 | 9/7/2010 | | | | <0.0065 | U | | 0.0012 | J | | <0.0048 | U | | 0.01 | J | | <0.0065 | U | | <0.0056 | U | | <0.0091 | U | | 0.0024 | J | | <0.0039 | U | | 0.0014 | J | | <0.039 | U | |
| | | VMP-10-10-111810 | 11/17/2010 | | | | <0.0063 | U | | <0.0053 | U | | 0.00046 | J | | 0.018 | | | <0.0063 | U | | 0.0022 | J | | <0.0088 | U | | 0.0026 | J | | 0.0023 | J | | 0.0019 | J | | <0.038 | U | |
| | | VMP-10-10-021111 | 2/11/2011 | | | | <0.005 | U | | <0.0041 | U | | <0.0036 | U | | 0.11 | | | <0.005 | J | U | <0.0043 | U | | <0.0069 | U | | 0.00083 | J | | 0.0023 | J | | 0.0035 | J | | <0.03 | U | |
| | | VMP-10-10-040611 | 4/6/2011 | 0.014 | J | | <0.0065 | U | | <0.0054 | U | | <0.0048 | U | | <0.013 | U | | <0.0065 | J | U | <0.0056 | U | | <0.0091 | U | | <0.009 | J | U | <0.0039 | U | | 0.0018 | J | | <0.039 | J | U |
| | | VMP-10-10-072911 | 7/29/2011 | <0.016 | U | | 0.023 | | | 0.13 | | | <0.005 | U | | 0.036 | | | <0.0068 | U | | 0.0015 | J | | <0.0095 | U | | <0.0094 | U | | 0.002 | J | | 0.024 | | | <0.041 | U | |
| | | VMP-10-10-110411 | 11/4/2011 | <0.01 | U | | 0.0061 | | | 0.018 | | | <0.0032 | U | | 0.0061 | J | | 0.00047 | J | | <0.0038 | U | | <0.0061 | U | | <0.0061 | J | U | <0.0026 | U | | 0.01 | | | <0.026 | U | |
| | | VMP-10-10-110411-DUP | 11/4/2011 | <0.01 | U | | 0.0056 | | | 0.016 | | | <0.0032 | U | | 0.0057 | J | | 0.00049 | J | | <0.0038 | U | | <0.0061 | U | | <0.0061 | J | U | <0.0026 | U | | 0.01 | | | <0.026 | U | |
| | | VMP-10-10-012512 | 1/26/2012 | 0.0017 | J | J | 0.004 | J | | 0.0013 | J | | <0.0032 | U | | 0.0072 | J | | 0.0025 | J | | <0.0037 | U | | <0.006 | U | | <0.0059 | U | | 0.011 | | | 0.0034 | | | <0.026 | U | |
| | | VMP-10-10-012512-DUP | 1/26/2012 | 0.081 | | J | 0.0017 | J | | 0.0017 | J | | <0.0033 | U | | 0.0066 | J | | 0.00099 | J | | <0.0039 | U | | <0.0063 | U | | <0.0062 | U | | 0.012 | | | 0.0032 | J | | <0.027 | U | |
| | | VMP-10-10-041112 | 4/11/2012 | 0.012 | | | 0.00084 | J | | 0.0007 | J | | <0.0034 | U | | 0.18 | | | <0.0047 | J | U | <0.0041 | U | | <0.0066 | U | | <0.0065 | J | U | 0.055 | | | 0.07 | | | <0.028 | U | |
| | | VMP-10-10-071312 | 7/13/2012 | 0.003 | J | | <0.0046 | J | U | <0.0038 | J | U | <0.0034 | U | | 0.014 | | | <0.0046 | U | | <0.004 | U | | <0.0064 | U | | <0.0064 | U | | 0.006 | | | <0.0035 | J | U | <0.028 | U | |
| | | VMP-10-10-101612 | 10/16/2012 | 0.13 | | | 0.0022 | J | | <0.0065 | U | | <0.0057 | U | | <0.016 | U | | <0.0078 | J | U | <0.0067 | U | | <0.011 | U | | <0.011 | U | | <0.0046 | U | | <0.006 | J | U | <0.047 | U | |
| | | VMP-10-10-012913 | 1/29/2013 | 0.0043 | J | | <0.0062 | U | | 0.0011 | J | | <0.0045 | U | | 0.015 | | | <0.0062 | U | | <0.0054 | U | | <0.0086 | U | | <0.0085 | J | U | <0.0037 | U | | <0.0047 | J | U | <0.037 | J | U |
| | 20 ft | VMP-10-20-090710 | 9/7/2010 | | | | <0.0068 | U | | 0.00098 | J | | <0.005 | U | | 0.023 | | | <0.0068 | U | | <0.0059 | U | | <0.0095 | U | | <0.0094 | U | | 0.0036 | J | | 0.005 | J | | <0.041 | U | |
| | | VMP-10-20-090710-DUP | 9/7/2010 | | | | <0.0063 | U | | 0.00096 | J | | <0.0046 | U | | 0.033 | | | <0.0063 | U | | <0.0055 | U | | <0.0088 | U | | 0.0007 | J | | 0.0042 | | | 0.0098 | | | <0.038 | U | |
| | | VMP-10-20-111810 | 11/17/2010 | | | | <0.012 | U | | <0.01 | U | | 0.0012 | J | | <0.024 | U | | <0.012 | U | | <0.01 | U | | <0.017 | U | | <0.016 | J | U | <0.0072 | U | | <0.0092 | U | | <0.072 | U | |
| | | VMP-10-20-111810-Dup | 11/17/2010 | | | | <0.0061 | U | | <0.005 | U | | 0.00047 | J | | 0.037 | | | <0.0061 | U | | 0.0025 | J | | <0.0085 | U | | <0.0084 | J | U | <0.0036 | U | | 0.0012 | J | | <0.037 | U | |
| | | VMP-10-20-021111 | 2/11/2011 | | | | <0.006 | U | | <0.005 | U | | <0.0044 | U | | 0.0048 | J | | <0.006 | U | | <0.0052 | U | | <0.0084 | U | | 0.002 | J | | <0.0036 | U | | 0.0064 | | | <0.036 | U | |
| | | VMP-10-20-040611 | 4/6/2011 | 0.027 | | | 0.029 | | | 0.1 | | | <0.0053 | U | | 0.054 | | | <0.0072 | U | | <0.0063 | U | | <0.01 | U | | <0.01 | J | U | <0.0043 | U | | 0.026 | | | <0.044 | J | U |
| | | VMP-10-20-072911 | 7/29/2011 | <0.016 | U | | 0.023 | | | 0.075 | | | <0.0049 | U | | 0.024 | | | <0.0067 | U | | 0.0016 | J | | <0.0094 | U | | <0.0092 | U | | 0.0014 | J | | 0.014 | | | <0.04 | U | |
| | | VMP-10-20-110411 | 11/4/2011 | 0.0043 | J | | 0.0057 | | | 0.031 | | | <0.0032 | U | | 0.025 | | | 0.00042 | J | | 0.0005 | J | | <0.0061 | U | | <0.0061 | J | U | 0.0023 | J | | 0.015 | | | <0.026 | U | |
| | | VMP-10-20-012612 | 1/26/2012 | 0.048 | | | 0.00095 | J | | 0.0023 | J | | <0.003 | U | | 0.0024 | J | | <0.0041 | U | | <0.0036 | U | | <0.0058 | U | | <0.0057 | U | | 0.02 | | | 0.0056 | | | <0.025 | U | |
| | | VMP-10-20-041212 | 4/12/2012 | 0.015 | | | <0.0046 | U | | <0.0038 | U | | <0.0034 | U | | 0.03 | | | <0.0046 | U | | <0.004 | U | | <0.0064 | U | | <0.0064 | U | | 0.0077 | | | 0.01 | | | <0.028 | U | |
| | | VMP-10-20-071612 | 7/16/2012 | 0.0056 | J | | <0.0037 | U | | <0.0032 | U | | <0.0032 | U | | 0.0014 | J | | <0.0044 | U | | <0.0038 | U | | <0.0061 | U | | <0.0061 | U | | 0.0041 | | | <0.0034 | J | U | <0.026 | U | |
| | | VMP-10-20-101612 | 10/16/2012 | 0.038 | | | <0.0078 | U | | <0.0065 | U | | <0.0058 | U | | <0.016 | U | | <0.0078 | J | U | <0.0068 | U | | <0.011 | U | | <0.011 | U | | <0.0047 | U | | <0.006 | J | U | <0.047 | U | |
| | | VMP-10-20-012913 | 1/29/2013 | 0.0019 | J | | <0.0068 | U | | <0.0056 | U | | <0.005 | U | | 0.0023 | J | | <0.0068 | U | | <0.0059 | U | | <0.0095 | U | | <0.0094 | J | U | <0.0041 | U | | <0.0052 | J | U | <0.041 | J | U |
| | 30 ft | VMP-10-30-041212 | 4/12/2012 | 0.024 | | | <0.0048 | U | | <0.004 | U | | <0.0035 | U | | 0.2 | | | <0.0048 | U | | <0.0042 | U | | <0.0067 | U | | <0.0066 | U | | 0.047 | | | 0.09 | | | <0.029 | U | |
| | | VMP-10-30-071612 | 7/16/2012 | 0.0068 | J | | <0.0042 | U | | <0.0035 | U | | <0.0031 | U | | 0.0012 | J | | <0.0042 | U | | <0.0037 | U | | <0.0059 | U | | <0.0059 | U | | 0.0046 | | | 0.0049 | | | <0.026 | U | |
| | | VMP-10-30-101612 | 10/16/2012 | 0.026 | | | <0.0074 | U | | <0.0061 | U | | <0.0054 | U | | 0.01 | J | | <0.0074 | U | | <0.0064 | U | | <0.01 | U | | <0.01 | U | | 0.0014 | J | | 0.0077 | | | <0.044 | U | |
| | | VMP-10-30-012913 | 1/29/2013 | <0.018 | U | | <0.0074 | U | | <0.0062 | U | | <0.0055 | U | | 0.0071 | J | | <0.0074 | U | | <0.0064 | U | | <0.01 | U | | 0.0022 | J | | <0.0045 | U | | <0.0057 | J | U | <0.045 | J | U |
| VMP-11 | 5 ft | VMP-11-5-090710 | 9/7/2010 | | | | <0.0061 | U | | 0.00085 | J | | <0.0044 | U | | <0.013 | | U | 0.00087 | J | | <0.0053 | U | | <0.0085 | U | | <0.0084 | U | | <0.0036 | U | | 0.003 | J | | <0.037 | U | |
| | | VMP-11-5-112210 | 11/22/2010 | | | | <0.0063 | U | | <0.0053 | U | | <0.0046 | U | | 0.078 | | | <0.0063 | U | | 0.006 | | | <0.0088 | U | | <0.0088 | U | | <0.0038 | U | | 0.0024 | J | | <0.038 | U | |
| | | VMP-11-5-021511 | 2/15/2011 | | | | <0.0056 | U | | 0.0015 | J | | <0.0041 | U | | 0.0096 | J | | <0.0056 | J | U | <0.0048 | U | | <0.0078 | U | | <0.0077 | U | | <0.0034 | U | | 0.0069 | | | <0.034 | U | |
| | | VMP-11-5-040611 | 4/6/2011 | 1.1 | | | <0.053 | U | | <0.044 | U | | <0.039 | U | | <0.11 | U | | <0.053 | U | | <0.046 | U | | <0.074 | U | | <0.073 | U | | <0.032 | U | | 0.0087 | J | | <0.32 | U | |
| | | VMP-11-5-080711 | 8/7/2011 | 0.019 | J | | 0.06 | J | | 0.16 | | | <0.054 | U | | 0.068 | J | | <0.073 | U | | <0.063 | U | | <0.1 | U | | <0.1 | U | | <0.044 | U | | 0.021 | J | | <0.44 | U | |
| | | VMP-11-5-111111 | 11/11/2011 | 1.4 | | | 0.0024 | J | | 0.024 | | | <0.01 | U | | <0.029 | U | | <0.014 | U | | <0.012 | U | | <0.02 | U | | <0.02 | U | | <0.0086 | U | | 0.01 | J | | <0.087 | U | |
| | | VMP-11-5-012612 | 1/26/2012 | <0.01 | U | | 0.0052 | | | 0.017 | | | <0.0032 | U | | 0.012 | | | <0.0043 | U | | <0.0037 | U | | <0.006 | U | | <0.0059 | U | | <0.0026 | U | | 0.0054 | | | <0.026 | U | |
| | | VMP-11-5-041912 | 4/19/2012 | <0.012 | J | U | 0.059 | | | 0.34 | | | <0.0035 | U | | 0.062 | | | 0.0022 | J | | 0.0016 | J | | <0.0067 | U | | 0.0047 | J | | 0.0088 | | | 0.036 | | | <0.029 | U | |
| | | VMP-11-5-071912 | 7/16/2012 | 0.0076 | J | | <0.0062 | U | | <0.0052 | U | | <0.0046 | U | | 0.012 | J | | <0.0062 | U | | <0.0054 | U | | <0.0087 | J | U | <0.0086 | U | | 0.0038 | | | 0.0037 | J | | <0.038 | U | |
| | | VMP-11-5-101612 | 10/16/2012 | 0.019 | | | <0.007 | U | | <0.0058 | U | | <0.0051 | U | | 0.047 | | | <0.007 | U | | <0.006 | U | | <0.0097 | U | | <0.0096 | U | | 0.0033 | J | | 0.0036 | J | | <0.042 | U | |
| | | VMP-11-5-012913 | 1/29/2013 | 0.29 | J | | <0.35 | U | | <0.29 | U | | <0.26 | U | | 36 | | | <0.35 | U | | 0.058 | J | | <0.49 | U | | 1 | | | <0.21 | U | | 0.1 | J | | <2.1 | U | |
| | 8 ft | VMP-11-8-090810 | 9/8/2010 | | | | <0.0063 | U | | <0.0053 | U | | <0.0046 | U | | <0.013 | J | U | <0.0063 | U | | <0.0055 | U | | <0.0088 | U | | <0.0088 | U | | <0.0038 | U | | 0.0025 | J | | <0.038 | U | |
| | | VMP-11-8-112210 | 11/22/2010 | | | | <0.0063 | U | | <0.0053 | U | | <0.0046 | U | | 0.033 | | | <0.0063 | U | | 0.0035 | J | | <0.0088 | U | | <0.0088 | U | | <0.0038 | U | | <0.0049 | J | U | <0.038 | U | |
| | | VMP-11-8-021111 | 2/11/2011 | | | | <0.0061 | U | | <0.0051 | U | | <0.0045 | U | | 0.0044 | J | | <0.0061 | U | | <0.0053 | U | | <0.0086 | U | | <0.0085 | U | | <0.0037 | U | | <0.0047 | U | | <0.037 | U | |
| | | VMP-11-8-021111-DUP | 2/11/2011 | | | | <0.0058 | U | | <0.0048 | U | | <0.0042 | U | | 0.0062 | J | | <0.0058 | U | | <0.005 | U | | <0.0081 | U | | <0.008 | U | | <0.0035 | U | | <0.0044 | U | | <0.035 | U | |
| | | VMP-11-8-040611 | 4/6/2011 | 0.38 | | | <0.027 | U | | <0.023 | U | | <0.02 | U | | <0.054 | U | | <0.027 | U | | <0.024 | U | | <0.038 | U | | <0.038 | U | | <0.016 | U | | <0.021 | U | | <0.16 | U | |
| | | VMP-11-8-040611-DUP | 4/6/2011 | 0.29 | | | <0.024 | U | | <0.02 | U | | <0.017 | U | | <0.047 | U | | <0.024 | U | | <0.02 | U | | <0.033 | U | | <0.033 | U | | <0.014 | U | | 0.0034 | J | | <0.14 | U | |
| | | VMP-11-8-080711 | 8/7/2011 | <0.18 | U | | 0.046 | J | | 0.14 | | | <0.054 | U | | 0.11 | J | | <0.073 | U | | <0.063 | U | | <0.1 | U | | <0.1 | U | | <0.044 | U | | 0.019 | J | | <0.44 | U | |
| | | VMP-11-8-111411 | 11/14/2011 | 0.078 | | | 0.0044 | | | 0.038 | | | <0.0032 | U | | 0.049 | | | <0.0043 | U | | <0.0037 | U | | <0.006 | U | | 0.0038 | J | | 0.0011 | J | | 0.013 | | | <0.026 | U | |
| | | VMP-11-8-012612 | 1/26/2012 | <0.01 | U | | 0.0048 | | | 0.021 | | | <0.0031 | U | | 0.0092 | | | <0.0042 | U | | <0.0036 | U | | <0.0059 | U | | <0.0058 | U | | <0.0025 | U | | 0.0045 | | | <0.025 | U | |
| | | VMP-11-8-041912 | 4/19/2012 | <0.012 | J | U | 0.048 | | | 0.34 | | | <0.0035 | U | | 0.068 | | | 0.00058 | J | | 0.0014 | J | | <0.0067 | U | | 0.006 | J | | 0.0086 | | | 0.034 | | | <0.029 | U | |
| | | VMP-11-8-072012 | 7/20/2012 | <0.012 | U | | <0.0048 | U | | <0.004 | U | | <0.0035 | U | | 0.0062 | J | | <0.0048 | U | | <0.0042 | U | | <0.0067 | U | | <0.0066 | U | | 0.0022 | J | | <0.0037 | U | | <0.029 | U | |
| | | VMP-11-8-101612 | 10/16/2012 | 0.015 | J | | <0.007 | U | | 0.0012 | J | | <0.0052 | U | | 0.97 | | | <0.007 | U | | <0.0061 | U | | <0.0098 | U | | <0.0097 | U | | 0.055 | | | 0.018 | | | <0.042 | U | |
| | | VMP-11-8-101612-Dup | 10/16/2012 | 0.0033 | J | | <0.0071 | U | | <0.0059 | U | | <0.0052 | U | | 1 | | | <0.0071 | U | | <0.0062 | U | | <0.0099 | U | | <0.0098 | U | | 0.06 | | | 0.016 | | | <0.043 | U | |
| | | VMP-11-8-012913 | 1/29/2013 | <0.12 | U | | <0.048 | U | | <0.04 | U | | <0.036 | U | | 0.71 | | | <0.048 | U | | <0.042 | U | | <0.068 | U | | <0.067 | U | | <0.029 | U | | 0.0062 | J | | <0.29 | U | |
| | 29 ft | VMP-11-29-090810 | 9/8/2010 | | | | <0.16 | U | | <0.13 | U | | 0.053 | J | | <0.32 | U | | 0.059 | J | | <0.14 | U | | <0.22 | U | | <0.22 | U | | <0.095 | U | | <0.12 | U | | <0.96 | U | |
| | | VMP-11-29-112210 | 11/22/2010 | | | | <2.3 | U | | <1.9 | U | | <1.6 | U | | <4.5 | U | | <2.3 | U | | <2 | U | | <3.2 | U | | <3.1 | U | | <1.4 | U | | <1.7 | U | | <14 | U | |
| | | VMP-11-29-112210-Dup | 11/22/2010 | | | | <1.6 | U | | <1.3 | U | | <1.2 | U | | <3.2 | U | | <1.6 | U | | <1.4 | U | | <2.2 | U | | 0.69 | J | | <0.94 | U | | <1.2 | U | | <9.5 | U | |
| | | VMP-11-29-021411 | 2/14/2011 | | | | <0.0061 | U | | 0.0013 | J | | 0.0011 | J | | 0.023 | | | <0.0061 | U | | <0.0053 | U | | <0.0086 | U | | 0.0014 | J | | <0.0037 | U | | 0.0027 | J | | <0.037 | U | |
| | | VMP-11-29-040611 | 4/6/2011 | 0.44 | | | <0.046 | U | | <0.039 | U | | 0.0031 | J | | <0.093 | U | | <0.046 | U | | <0.04 | U | | <0.065 | U | | <0.064 | U | | <0.028 | U | | <0.036 | U | | <0.28 | U | |
| | | VMP-11-29-082511 | 8/25/2011 | 0.004 | J | | 0.0088 | | | 0.056 | | | 0.0012 | J | | 0.033 | | | <0.0068 | U | | 0.00098 | J | | <0.0095 | U | | <0.0094 | U | | <0.0041 | U | | 0.0079 | | | <0.041 | U | |
| | | VMP-11-29-082511-Dup | 8/25/2011 | 0.004 | J | | 0.0086 | | | 0.052 | | | 0.00088 | J | | 0.034 | | | <0.0068 | U | | 0.00091 | J | | <0.0095 | U | | <0.0094 | U | | 0.001 | J | | 0.0071 | | | <0.041 | U | |
| | | VMP-11-29-111411 | 11/14/2011 | 0.0049 | J | | 0.0054 | | | 0.04 | | | 0.0037 | | | 0.018 | | | <0.0043 | U | | <0.0037 | U | | <0.006 | U | | <0.0059 | U | | <0.0026 | U | | 0.014 | | | <0.026 | U | |
| | | VMP-11-29-012612 | 1/26/2012 | 0.0062 | J | | 0.0043 | | | 0.012 | | | 0.0087 | | | 0.0035 | J | | <0.0041 | U | | <0.0036 | U | | <0.0058 | U | | <0.0057 | U | | <0.0025 | U | | 0.0028 | J | | <0.025 | U | |
| | | VMP-11-29-042712 | 4/27/2012 | 0.0072 | J | | 0.0092 | | | 0.098 | | | 0.00091 | J | | 0.029 | | | <0.0043 | U | | <0.0037 | U | | <0.006 | U | | 0.0018 | J | | 0.0031 | | | 0.012 | | | <0.026 | U | |
| | | VMP-11-29-072012 | 7/23/2012 | <0.01 | U | | 0.063 | | | 0.21 | | | <0.0032 | U | | 0.076 | | | 0.0011 | J | | 0.0033 | J | | <0.006 | U | | <0.0059 | U | | 0.0056 | | | 0.1 | | | <0.026 | U | |
| | | VMP-11-29-101612 | 10/16/2012 | <0.017 | U | | <0.0073 | U | | <0.0061 | U | | 0.00079 | J | | 0.018 | | | <0.0073 | U | | <0.0063 | U | | <0.01 | U | | <0.01 | U | | <0.0044 | U | | 0.002 | J | | <0.11 | U | UJ |
| | | VMP-11-29-012913 | 1/29/2013 | 0.0087 | J | | <0.0071 | U | | <0.0059 | U | | <0.0052 | U | | 0.17 | | | <0.0071 | U | | <0.0062 | U | | <0.0099 | U | | 0.0021 | J | | 0.00073 | J | | 0.0042 | J | | <0.043 | J | U |
| | 38 ft | VMP-11-38-042312 | 4/23/2012 | 0.45 | J | | <0.32 | U | | <0.27 | U | | 0.11 | J | | <0.64 | U | | <0.32 | U | | <0.28 | U | | <0.45 | U | | 0.3 | J | | <0.19 | U | | <0.25 | U | | <1.9 | U | |
| | | VMP-11-38-042312-Dup | 4/23/2012 | 0.49 | J | | <1.1 | U | | <0.94 | U | | 0.098 | J | | <2.2 | U | | <1.1 | U | | <0.98 | U | | <1.6 | U | | 0.42 | J | | <0.68 | U | | <0.86 | U | | <6.8 | U | |
| | | VMP-11-38-072312 | 7/23/2012 | 0.48 | J | | <0.53 | U | | <0.44 | U | | <0.39 | U | | <1.1 | U | | <0.53 | U | | <0.46 | U | | <0.74 | U | | <0.74 | U | | <0.32 | U | | <0.41 | U | | <3.2 | U | |
| | | VMP-11-38-101612 | 10/16/2012 | 0.032 | | | <0.0074 | U | | <0.0061 | U | | 0.011 | | | 0.015 | | | <0.0074 | U | | <0.0064 | U | | <0.01 | U | | <0.01 | U | | <0.0044 | U | | <0.0056 | J | U | <0.044 | U | |
| | | VMP-11-38-013013 | 1/30/2013 | 0.019 | | | <0.0068 | U | | <0.0056 | U | | 0.0079 | | | 0.025 | | | <0.0068 | U | | <0.0059 | U | | <0.0095 | U | | 0.0013 | J | | <0.0041 | U | | 0.00086 | J | | <0.041 | U | |

SEE LAST PAGE OF TABLE FOR NOTES

**TABLE 6**
**CUMULATIVE SUMMARY OF SOIL VAPOR ANALYTICAL DETECTIONS AND SCREENING RESULTS: PUBLIC WORKS YARD AND WRR - VOCS**

| Location | Depth | Sample ID | Sample Date | Isopentane | | | Isopropylbenzene (Cumene) | | | 4-Methyl-2-pentanone (Methyl | | | Methyl tert-Butyl Ether (MTBE) | | | 2-Propanol | | | n-Propylbenzene | | | Styrene | | | 1,1,2,2-Tetrachloroethane | | | Tetrachloroethene | | | Tetrahydrofuran | | | Toluene | | | 1,2,4-Trichlorobenzene | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | | | | 3500 | | | | | | 23000 | | | | | | | | | 8500 | | | | | | 4 | | | 40000 | | | 50 | | | | | |
| | | | | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals |
| VMP-12 | 5 ft | VMP-12-5-090310 | 9/3/2010 | | | | 2.9 | J | | <5.5 | U | | <4.8 | U | | 3.6 | J | | 3 | J | | <5.7 | U | | <9.2 | U | | <9.1 | U | | <4 | U | | 1 | J | | <40 | U | |
| | | VMP-12-5-120310 | 12/3/2010 | | | | 18 | J | | <54 | U | | <48 | U | | <130 | U | | 20 | J | | <57 | U | | <91 | U | | <90 | U | | <39 | U | | <50 | U | | <390 | U | |
| | | VMP-12-5-021511 | 2/15/2011 | | | | <3 | U | | <2.5 | U | | <2.2 | U | | <6 | U | | <3 | U | | <2.6 | U | | <4.2 | U | | <4.1 | U | | <1.8 | U | | 0.74 | J | | <18 | U | |
| | | VMP-12-5-041911 | 4/19/2011 | 9700 | | | <22 | U | | <18 | U | | <16 | U | | <44 | UJ | UJ | <22 | U | | <19 | U | | <31 | U | | <30 | U | | <13 | U | UJ | 11 | J | | <130 | U | |
| | | VMP-12-5-080411 | 8/4/2011 | 7700 | | | <5.7 | U | | <4.7 | U | | <4.2 | U | | <11 | U | | <5.7 | U | | <4.9 | U | | <7.9 | U | | <7.8 | U | | <3.4 | U | | <4.4 | U | | <34 | U | |
| | | VMP-12-5-111611 | 11/16/2011 | 0.26 | | | 0.0019 | J | | 0.013 | | | <0.0029 | U | | 0.013 | | | <0.004 | U | | <0.0035 | U | | <0.0056 | U | | <0.0055 | U | | <0.0024 | U | | 0.0083 | | | <0.024 | U | |
| | | VMP-12-5-012412 | 1/24/2012 | 12 | | | 0.0062 | J | | 0.08 | | | <0.033 | U | | 0.019 | J | | <0.045 | U | | <0.039 | U | | <0.063 | U | | <0.062 | U | | <0.027 | U | | 0.016 | J | | <0.27 | U | |
| | | VMP-12-5-041912 | 4/19/2012 | 0.029 | | | 0.014 | | | 0.0051 | | | <0.0033 | U | | 0.0062 | J | | 0.01 | | | <0.0039 | U | | <0.0063 | U | | <0.0062 | U | | <0.0027 | U | | 0.006 | | | <0.027 | U | |
| | | VMP-12-5-072612 | 7/26/2012 | 0.026 | | | 0.0011 | J | | 0.0044 | | | <0.0035 | U | | 0.14 | | J | 0.00081 | J | | 0.00093 | J | | <0.0067 | U | | <0.0066 | U | | <0.0029 | U | J | 0.011 | | J | <0.029 | U | |
| | | VMP-12-5-072612-Dup | 7/26/2012 | 0.0032 | J | | <0.0044 | U | | <0.0036 | U | | <0.0032 | U | | 0.0013 | J | J | <0.0044 | U | | <0.0038 | U | | <0.0061 | U | | <0.006 | U | | <0.0026 | U | J | 0.0016 | J | J | <0.026 | U | |
| | | VMP-12-5-102412 | 10/24/2012 | 0.008 | J | | 0.0031 | J | | 0.009 | | | <0.0054 | U | | 0.0063 | J | | <0.0074 | J | U | <0.0064 | U | | <0.01 | U | | 0.0036 | J | | <0.0044 | U | | 0.016 | | | <0.044 | U | |
| | | VMP-12-5-021813 | 2/18/2013 | 0.026 | | | 0.0017 | J | | 0.0081 | | | <0.0048 | U | | 0.012 | J | | 0.002 | J | | <0.0057 | U | | <0.0092 | U | | <0.0091 | U | | <0.004 | U | | 0.0021 | J | | <0.04 | U | |
| | 11.5 ft | VMP-12-11.5-090310 | 9/3/2010 | | | | 9.1 | | | <7.1 | U | | <6.2 | U | | 2.4 | J | | 11 | | | <7.3 | U | | <12 | U | | <12 | U | | <5.1 | U | | 1.1 | J | | <51 | U | |
| | | VMP-12-11.5-120310 | 12/3/2010 | | | | <7.3 | U | | <6.1 | U | | <5.4 | U | | <15 | U | | <7.3 | U | | <6.4 | U | | <10 | U | | <10 | U | | <4.4 | U | | <5.6 | U | | <44 | U | |
| | | VMP-12-11.5-021511 | 2/15/2011 | | | | <6.6 | U | | <5.5 | U | | <4.8 | U | | <13 | U | | 2.4 | J | | <5.7 | U | | <9.2 | U | | <9.1 | U | | <4 | U | | 1.5 | J | | <40 | U | |
| | | VMP-12-11.5-021511-DUP | 2/15/2011 | | | | <5.7 | U | | <4.7 | U | | <4.2 | U | | <11 | U | | 1.9 | J | | <4.9 | U | | <7.9 | U | | <7.8 | U | | <3.4 | U | | 1.7 | J | | <34 | U | |
| | | VMP-12-11.5-041911 | 4/19/2011 | 11000 | | | <20 | U | | <16 | U | | <14 | U | | <40 | UJ | UJ | <20 | U | | <17 | U | | <28 | U | | <27 | U | | <12 | U | UJ | <15 | U | | <120 | U | |
| | | VMP-12-11.5-080411 | 8/4/2011 | 4800 | | | <6.9 | U | | <5.8 | U | | <5.1 | U | | <14 | U | | <6.9 | U | | <6 | U | | <9.7 | U | | <9.6 | U | | <4.2 | U | | <5.3 | U | | <42 | U | |
| | | VMP-12-11.5-111611 | 11/16/2011 | 12 | | | 0.007 | J | | 0.017 | J | | <0.04 | U | | <0.11 | U | | <0.055 | U | | <0.048 | U | | <0.077 | U | | <0.076 | U | | <0.033 | U | | 0.014 | J | | <0.33 | U | |
| | | VMP-12-11.5-012412 | 1/24/2012 | 410 | | | <0.52 | U | | <0.43 | U | | <0.38 | U | | <1 | U | | <0.52 | U | | <0.45 | U | | <0.72 | U | | <0.71 | U | | <0.31 | U | | 0.21 | J | | <3.1 | U | |
| | | VMP-12-11.5-041912 | 4/19/2012 | 14 | | | 0.014 | J | | <0.039 | U | | <0.034 | U | | <0.094 | U | | 0.016 | J | | <0.041 | U | | <0.066 | U | | <0.065 | U | | <0.028 | U | | 0.014 | J | | <0.28 | U | |
| | | VMP-12-11.5-082012 | 8/20/2012 | 0.006 | J | | 0.096 | | | 0.18 | | | <0.0055 | U | | 0.026 | | | 0.0016 | J | | 0.0029 | J | | <0.01 | U | | <0.01 | U | | <0.0045 | U | | 0.015 | | | <0.045 | U | |
| | | VMP-12-11.5-102612 | 10/26/2012 | 0.066 | | | 0.016 | | | 0.032 | | | <0.0052 | U | | 0.016 | | J | <0.0071 | U | | <0.0062 | U | | <0.0099 | U | | <0.0098 | U | | <0.0043 | U | | 0.0048 | J | | <0.11 | U | UJ |
| | | VMP-12-11.5-021813 | 2/18/2013 | <0.017 | U | | <0.0071 | U | | <0.0059 | U | | <0.0052 | U | | 0.013 | J | | <0.0071 | U | | <0.0062 | U | | <0.0099 | U | | <0.0098 | U | | <0.0043 | U | | 0.00094 | J | | <0.043 | U | |
| | 25 ft | VMP-12-25-090310 | 9/3/2010 | | | | 20 | | | <9 | U | | <7.9 | U | | <22 | U | | 26 | | | <9.4 | U | | <15 | U | | <15 | U | | <6.5 | U | | 2.9 | J | | <65 | U | |
| | | VMP-12-25-120310 | 12/3/2010 | | | | <0.54 | U | | <0.45 | U | | <0.39 | U | | <1.1 | U | | <0.54 | U | | <0.46 | U | | <0.75 | U | | <0.74 | U | | <0.32 | U | | <0.41 | U | | <3.2 | U | |
| | | VMP-12-25-021511 | 2/15/2011 | | | | 9.2 | J | | <11 | U | | <9.6 | U | | <26 | U | | 9.7 | J | | <11 | U | | <18 | U | | <18 | U | | <7.8 | U | | 12 | | | <79 | U | |
| | | VMP-12-25-041911 | 4/19/2011 | 8300 | | | 8.6 | J | | <18 | U | | <16 | U | | <43 | UJ | UJ | 8.1 | J | | <18 | U | | <30 | U | | <29 | U | | <13 | U | UJ | <16 | U | | <130 | U | |
| | | VMP-12-25-080411 | 8/4/2011 | 9200 | | | <14 | U | | <11 | U | | <9.9 | U | | <27 | U | | <14 | U | | <12 | U | | <19 | U | | <19 | U | | <8.1 | U | | <10 | U | | <82 | U | |
| | | VMP-12-25-111611 | 11/16/2011 | 8900 | | | <15 | U | | <13 | U | | <11 | U | | <31 | U | | <15 | U | | <13 | U | | <22 | U | | <21 | U | | <9.2 | U | | 23 | | | <93 | U | |
| | | VMP-12-25-012412 | 1/24/2012 | 12000 | | | 0.77 | J | J | <4.9 | U | | <4.3 | U | | <12 | U | | <5.9 | U | | <5.1 | U | | <8.2 | U | | <8.1 | U | | <3.5 | U | | 0.96 | J | J | <36 | U | |
| | | VMP-12-25-012412-DUP | 1/24/2012 | 12000 | | | <43 | U | | <36 | U | | <32 | U | | <86 | U | | <43 | U | | <37 | U | | <60 | U | | <59 | U | | <26 | U | | <33 | U | | <260 | U | |
| | | VMP-12-25-041912 | 4/19/2012 | 8400 | | | <4.5 | U | | <3.7 | U | | <3.3 | U | | <9 | U | | <4.5 | U | | <3.9 | U | | <6.3 | U | | <6.2 | U | | <2.7 | U | | <3.4 | U | | <27 | U | |
| | | VMP-12-25-072712 | 7/27/2012 | 1400 | | J | <4.9 | U | | <4.1 | U | | <3.6 | U | | <9.9 | U | | <4.9 | U | | <4.3 | U | | <6.9 | U | | <6.8 | U | | <3 | U | | <3.8 | U | | <30 | U | |
| | | VMP-12-25-072712-Dup | 7/27/2012 | 1800 | | J | <4.9 | U | | <4.1 | U | | <3.6 | U | | <9.9 | U | | <4.9 | U | | <4.3 | U | | <6.9 | U | | <6.8 | U | | <3 | U | | <3.8 | U | | <30 | U | |
| | | VMP-12-25-102512 | 10/25/2012 | 180 | | | <2.1 | U | | <1.8 | U | | <1.6 | U | | <4.2 | U | | <2.1 | U | | <1.8 | U | | <3 | U | | <2.9 | U | | <1.3 | U | | <1.6 | U | | <13 | U | UJ |
| | | VMP-12-25-021513 | 2/15/2013 | 1400 | | J | <4 | U | | <13 | U | | <2.9 | U | | <7.9 | U | | <4 | U | | <3.4 | U | | <5.5 | U | | <5.5 | U | | <2.4 | U | | <3 | U | | <24 | U | |
| | 39 ft | VMP-12-39-041911 | 4/19/2011 | 7800 | | | 9.7 | J | | <17 | U | | <15 | U | | <41 | UJ | UJ | 10 | J | | <18 | U | | <29 | U | | <28 | U | | <12 | U | UJ | <16 | U | | <120 | U | |
| | | VMP-12-39-012412 | 1/24/2012 | 12000 | | | <43 | U | | <36 | U | | <32 | U | | <86 | U | | <43 | U | | <37 | U | | <60 | U | | <59 | U | | <26 | U | | 5.7 | J | | <260 | U | |
| | | VMP-12-39-041912 | 4/19/2012 | 8200 | | | <22 | U | | <18 | U | | <16 | U | | 19 | J | | <22 | U | | <19 | U | | <30 | U | | <30 | U | | <13 | U | | 8.4 | J | | <130 | U | |
| | | VMP-12-39-072612 | 7/26/2012 | 5400 | | | <9.9 | U | | <8.2 | U | | <7.2 | U | | 1.6 | J | | <9.9 | U | | <8.6 | U | | <14 | U | | <14 | U | | <5.9 | U | | 1.1 | J | | <60 | U | |
| | | VMP-12-39-102412 | 10/24/2012 | 2000 | | | <26 | U | | <22 | U | | 2.2 | J | | <52 | U | | <26 | U | | <22 | U | | <36 | U | | <36 | U | | <16 | U | | 14 | J | | <160 | U | |
| | | VMP-12-39-021513 | 2/15/2013 | 4100 | | | 17 | | | <40 | U | | <8.7 | U | | <24 | U | | 20 | | | <10 | U | | <17 | U | | <16 | U | | <7.1 | U | | 3.1 | J | | <72 | U | |
| VMP-13 | 5 ft | VMP-13-5-091310 | 9/13/2010 | | | | <0.043 | U | | <0.036 | U | | <0.032 | U | | <0.086 | U | | <0.043 | U | | <0.037 | U | | <0.06 | U | | <0.06 | U | | <0.026 | U | | 0.025 | J | | <0.26 | U | |
| | | VMP-13-5-120110 | 12/1/2010 | | | | 0.0037 | J | | <0.0048 | U | | <0.0042 | J | U | 0.049 | | | 0.008 | | | <0.005 | U | | <0.008 | U | | <0.0079 | J | U | <0.0034 | U | | 0.036 | | | <0.034 | U | |
| | | VMP-13-5-021811 | 2/18/2011 | | | | <0.0068 | U | | <0.0056 | U | | <0.005 | U | | 0.0066 | J | | <0.0068 | U | | <0.0059 | U | | <0.0095 | U | | <0.0094 | U | | <0.0041 | U | | 0.011 | | | <0.041 | U | |
| | | VMP-13-5-040511 | 4/5/2011 | 0.021 | J | | <0.014 | U | | <0.011 | U | | <0.01 | U | | <0.027 | U | | <0.014 | U | | <0.012 | U | | <0.019 | U | | <0.019 | J | U | <0.0081 | U | | 0.0026 | J | | <0.082 | J | U |
| | | VMP-13-5-080911 | 8/9/2011 | 3 | | J | 0.039 | | J | 0.12 | | J | <0.011 | U | | 0.021 | J | | <0.014 | J | U | 0.0025 | J | | <0.02 | U | | <0.02 | U | | <0.0087 | U | | 0.023 | | | <0.088 | J | U |
| | | VMP-13-5-080911-DUP | 8/9/2011 | 2 | | J | 0.026 | | J | 0.081 | | J | <0.0095 | U | | 0.048 | | | <0.013 | U | | 0.0013 | J | | <0.018 | U | | <0.018 | U | | <0.0078 | U | | 0.022 | | | <0.078 | U | |
| | | VMP-13-5-111411 | 11/14/2011 | 0.0017 | J | | 0.0046 | | | 0.031 | | | <0.0033 | U | | 0.012 | | | <0.0045 | U | | <0.0039 | U | | <0.0063 | U | | <0.0062 | U | | <0.0027 | U | | 0.011 | | | <0.027 | U | |
| | | VMP-13-5-012712 | 1/27/2012 | 0.64 | | J | 0.0062 | J | J | 0.0095 | J | J | <0.028 | U | | 0.017 | J | J | <0.038 | U | | <0.033 | U | | <0.053 | U | | <0.052 | U | | <0.023 | U | | 0.0098 | J | J | <0.23 | U | |
| | | VMP-13-5-042012 | 4/20/2012 | 0.0025 | J | | 0.015 | | | 0.048 | | | <0.0032 | U | | 0.032 | | | <0.0044 | U | | <0.0038 | U | | <0.0061 | U | | <0.0061 | U | | 0.004 | | | 0.012 | | | <0.026 | U | |
| | | VMP-13-5-071912 | 7/19/2012 | 0.0054 | J | | <0.0046 | J | U | 0.0037 | J | | <0.0034 | U | | 0.91 | | | <0.0046 | J | U | 0.0012 | J | | <0.0064 | U | | 0.0024 | J | | 0.026 | | | 0.023 | | | <0.028 | U | |
| | | VMP-13-5-071912-Dup | 7/19/2012 | 0.0053 | J | | <0.0046 | J | U | 0.0028 | J | | <0.0034 | U | | 0.88 | | | <0.0046 | J | U | 0.0014 | J | | <0.0064 | U | | 0.0016 | J | | 0.028 | | | 0.023 | | | <0.028 | U | |
| | | VMP-13-5-100912 | 10/9/2012 | 0.0092 | J | | <0.0071 | U | | <0.0059 | U | | <0.0052 | U | | <0.014 | U | | <0.0071 | U | | <0.0062 | U | | <0.0099 | U | | <0.0098 | U | | <0.0043 | U | | <0.0054 | U | | <0.043 | U | |
| | | VMP-13-5-012913 | 1/29/2013 | <0.018 | U | | <0.0076 | U | | <0.0064 | U | | <0.0056 | U | | 0.0044 | J | | <0.0076 | U | | <0.0066 | U | | <0.011 | U | | <0.01 | U | | <0.0046 | U | | <0.0058 | J | U | <0.046 | U | |
| | 10.5 ft | VMP-13-10.5-091310 | 9/13/2010 | | | | <0.016 | U | | <0.013 | U | | <0.012 | U | | 0.013 | J | | <0.016 | U | | <0.014 | U | | <0.022 | U | | 0.0073 | J | | <0.0096 | U | | 0.0075 | J | | <0.097 | U | |
| | | VMP-13-10.5-091310-Dup | 9/13/2010 | | | | <0.016 | U | | <0.013 | U | | <0.011 | U | | 0.012 | J | | <0.016 | U | | <0.014 | U | | <0.022 | U | | 0.0034 | J | | <0.0094 | U | | 0.0074 | J | | <0.094 | U | |
| | | VMP-13-10.5-120110 | 12/1/2010 | | | | <0.0064 | U | | <0.0053 | U | | <0.0047 | J | U | 0.1 | | | <0.0064 | U | | <0.0055 | U | | <0.0089 | U | | <0.0088 | J | U | <0.0038 | U | | 0.0011 | J | | <0.038 | U | |
| | | VMP-13-10.5-120110-DUP | 12/1/2010 | | | | <0.0066 | U | | <0.0055 | U | | <0.0049 | J | U | 0.13 | | | <0.0066 | U | | <0.0058 | U | | <0.0093 | U | | <0.0092 | J | U | <0.004 | U | | 0.00092 | J | | <0.04 | U | |
| | | VMP-13-10.5-021811 | 2/18/2011 | | | | <2.6 | U | | <2.2 | U | | <1.9 | U | | <5.2 | U | | <2.6 | U | | <2.3 | U | | <3.7 | U | | <3.6 | U | | <2 | U | | <16 | U | | <16 | U | |
| | | VMP-13-10.5-021811-DUP | 2/18/2011 | | | | <2.5 | U | | <2.1 | U | | <1.8 | U | | <5.1 | U | | <2.5 | U | | <2.2 | U | | <3.5 | U | | <3.5 | U | | <1.5 | U | | <1.9 | U | | <15 | U | |
| | | VMP-13-10.5-040511-DUP | 4/5/2011 | 0.017 | | | <0.0068 | U | | <0.0056 | U | | <0.005 | U | | 0.0022 | J | | <0.0068 | U | | <0.0059 | U | | <0.0095 | U | | <0.0094 | J | U | <0.0041 | U | | 0.0011 | J | | <0.041 | J | U |
| | | VMP-13-10.5-080911 | 8/9/2011 | 48 | | | 0.027 | J | | <0.12 | U | | <0.11 | U | | <0.3 | U | | <0.15 | U | | <0.13 | U | | <0.21 | U | | <0.2 | U | | <0.089 | U | | <0.11 | U | | <0.9 | U | |
| | | VMP-13-10.5-111411 | 11/14/2011 | 0.0086 | J | | 0.0049 | | | 0.039 | | | <0.0032 | U | | 0.022 | | | <0.0043 | U | | <0.0037 | U | | <0.006 | U | | <0.006 | U | | <0.0026 | U | | 0.017 | | | <0.026 | U | |
| | | VMP-13-10.5-012712 | 1/26/2012 | 0.13 | | J | 0.0058 | J | | 0.013 | | | <0.0088 | U | | <0.024 | U | | <0.012 | U | | <0.01 | U | | <0.017 | U | | <0.016 | U | | <0.0072 | U | | 0.0046 | J | | <0.072 | U | |
| | | VMP-13-10.5-012712-DUP | 1/26/2012 | 0.24 | | J | 0.0065 | J | | 0.015 | | | <0.013 | U | | <0.034 | U | | <0.017 | U | | <0.015 | U | | <0.024 | U | | <0.024 | U | | <0.01 | U | | 0.0047 | J | | <0.1 | U | |
| | | VMP-13-10.5-042012 | 4/20/2012 | 0.013 | | | 0.014 | | | 0.038 | | | <0.0032 | U | | 0.049 | | | 0.00062 | J | | <0.0037 | U | | <0.006 | U | | <0.0059 | U | | 0.0034 | | | 0.03 | | | <0.026 | J | U |
| | | VMP-13-10.5-071912 | 7/19/2012 | 0.012 | | | <0.0046 | U | | 0.00075 | J | | <0.0034 | U | | 0.23 | | | <0.0046 | J | U | 0.00079 | J | | <0.0064 | U | | 0.0023 | J | | 0.042 | | | 0.0082 | | | <0.028 | U | |
| | | VMP-13-10.5-100912 | 10/9/2012 | 0.0066 | J | | <0.0061 | U | | <0.005 | U | | <0.0044 | U | | 0.013 | | | <0.0061 | U | | <0.0053 | U | | <0.0085 | U | | <0.0084 | U | | <0.0036 | U | | 0.0087 | | | <0.037 | U | |
| | | VMP-13-10.5-100912-Dup | 10/9/2012 | <0.017 | U | | <0.0073 | U | | <0.0061 | U | | <0.0053 | U | | <0.014 | U | | <0.0073 | U | | <0.0063 | U | | <0.01 | U | | <0.01 | U | | <0.0044 | U | | 0.00089 | J | | <0.044 | U | |
| | | VMP-13-10.5-013013 | 1/30/2013 | 0.0024 | J | | <0.0062 | U | | <0.0052 | U | | <0.0045 | U | | 0.0096 | J | | <0.0062 | U | | <0.0054 | U | | <0.0086 | U | | <0.0085 | J | U | <0.0037 | U | | <0.0047 | J | U | <0.037 | J | U |
| | 21.5 ft | VMP-13-21.5-091310 | 9/13/2010 | | | | <12 | U | | <9.9 | U | | <8.7 | U | | <24 | U | | <12 | U | | <10 | U | | <17 | U | | <16 | U | | <7.1 | U | | 3.7 | J | | <72 | U | |
| | | VMP-13-21.5-120110 | 12/1/2010 | | | | <23 | U | | <19 | U | | <17 | U | | <46 | U | | <23 | U | | <20 | U | | <32 | U | | <32 | U | | <14 | U | | <18 | U | | <140 | U | |
| | | VMP-13-21.5-021811 | 2/18/2011 | | | | <3.4 | U | | <2.9 | U | | <2.5 | U | | 1.7 | J | | <3.4 | U | | 0.53 | J | | <4.8 | U | | <4.7 | U | | <2.1 | U | | 0.54 | J | | <21 | U | |
| | | VMP-13-21.5-040511 | 4/5/2011 | 40 | | | <5 | U | | <4.1 | U | | <3.6 | U | | <9.9 | U | | <5 | U | | <4.3 | U | | <6.9 | U | | <6.8 | U | | <3 | U | | <3.8 | U | | <30 | U | |
| | | VMP-13-21.5-080911 | 8/9/2011 | 100 | | | <0.62 | U | | <0.52 | U | | <0.45 | U | | <1.2 | U | | <0.62 | U | | <0.54 | U | | <0.86 | U | | <0.85 | U | | <0.37 | U | | 0.18 | J | | <3.7 | U | |
| | | VMP-13-21.5-111411 | 11/14/2011 | 63 | | | <2.8 | U | | <2.4 | U | | <2.1 | U | | <5.6 | U | | <2.8 | U | | <2.4 | U | | <3.9 | U | | <3.9 | U | | <1.7 | U | | 3.5 | | | <17 | U | |
| | | VMP-13-21.5-111411-DUP | 11/14/2011 | 63 | | | <2.8 | U | | <2.4 | U | | <2.1 | U | | 0.96 | J | | <2.8 | U | | <2.4 | U | | <3.9 | U | | <3.9 | U | | <1.7 | U | | 3.6 | | | <17 | U | |
| | | VMP-13-21.5-012712 | 1/27/2012 | 49 | | J | <0.66 | U | | <0.55 | U | | 0.075 | J | J | <1.3 | U | | <0.66 | U | | <0.57 | U | | <0.92 | U | | <0.91 | U | | <0.4 | U | | <0.5 | U | | <4 | U | |
| | | VMP-13-21.5-042012 | 4/20/2012 | 12 | | | 0.017 | J | | 0.049 | J | | 0.053 | | | 0.14 | J | | <0.073 | U | | 0.04 | J | | <0.1 | U | | <0.1 | U | | <0.044 | U | | 0.087 | | | <0.44 | U | |
| | | VMP-13-21.5-071912 | 7/19/2012 | 0.37 | | | <0.0046 | J | U | 0.011 | | | 0.0044 | | | 0.21 | | | <0.0046 | J | U | 0.0013 | J | | <0.0064 | U | | 0.0032 | J | | 0.039 | | | 0.018 | | | <0.028 | U | |
| | | VMP-13-21.5-100912 | 10/9/2012 | 0.22 | | | <0.0074 | U | | <0.0062 | U | | 0.0092 | | | <0.015 | U | | <0.0074 | U | | <0.0064 | U | | <0.01 | U | | <0.01 | U | | <0.0045 | U | | 0.0012 | J | | <0.045 | U | |
| | | VMP-13-21.5-013013 | 1/30/2013 | <0.017 | U | | <0.0073 | U | | 0.0016 | J | | <0.0053 | U | | 0.015 | | | <0.0073 | U | | <0.0063 | U | | <0.01 | U | | <0.01 | J | U | <0.0044 | U | | <0.0056 | J | U | <0.044 | J | U |
| | 29.5 ft | VMP-13-29.5-021811 | 2/18/2011 | | | | <110 | U | | <88 | U | | <78 | U | | <210 | U | | <110 | U | | <92 | U | | <150 | U | | <150 | U | | <64 | U | | 16 | J | | <640 | U | |
| | | VMP-13-29.5-040511 | 4/5/2011 | 100 | J | | <69 | U | | <57 | U | | <50 | U | | <140 | U | | <69 | U | | <60 | U | | <96 | U | | <95 | U | | <41 | U | | 19 | J | | <420 | U | |
| | | VMP-13-29.5-013012 | 1/30/2012 | 77 | | J | <2.1 | U | | <1.8 | U | | <1.5 | U | | <4.2 | U | | <2.1 | U | | <1.8 | U | | <2.9 | U | | <2.9 | U | | <1.3 | U | | 11 | | J | <13 | U | |
| | | VMP-13-29.5-042012 | 4/20/2012 | 96 | | | <2.8 | U | | <2.3 | U | | <2 | U | | 2.9 | J | | <2.8 | U | | 0.51 | J | | <3.8 | U | | <3.8 | U | | <1.6 | U | | 1.3 | J | | <17 | U | |
| | | VMP-13-29.5-071912 | 7/19/2012 | 50 | | | <7.9 | U | | <6.6 | U | | <5.8 | U | | <16 | U | | <7.9 | U | | <6.8 | U | | <11 | U | | <11 | U | | <4.7 | U | | <6.1 | U | | <48 | U | |
| | | VMP-13-29.5-100912 | 10/9/2012 | 74 | | | <7.4 | U | | <6.2 | U | | 4.8 | J | | <15 | U | | <7.4 | U | | <6.4 | U | | <10 | U | | 2 | J | | <4.5 | U | | 1.4 | J | | <45 | U | |
| | | VMP-13-29.5-013013 | 1/30/2013 | 1.9 | J | | <3.1 | U | | 0.63 | J | | <2.3 | U | | 1.7 | J | | <3.1 | U | | <2.7 | U | | <4.4 | U | | <4.3 | U | | <1.9 | U | | 0.65 | J | | 1.6 | J | |

SEE LAST PAGE OF TABLE FOR NOTES

**TABLE 6**
**CUMULATIVE SUMMARY OF SOIL VAPOR ANALYTICAL DETECTIONS AND SCREENING RESULTS: PUBLIC WORKS YARD AND WRR - VOCS**

| Location | Depth | Sample ID | Sample Date | Isopentane | | | Isopropylbenzene (Cumene) | | | 4-Methyl-2-pentanone (Methyl | | | Methyl tert-Butyl Ether (MBTE) | | | 2-Propanol | | | n-Propylbenzene | | | Styrene | | | 1,1,2,2-Tetrachloroethane | | | Tetrachloroethene | | | Tetrahydrofuran | | | Toluene | | | 1,2,4-Trichlorobenzene | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | | | | 3500 | | | | | | 23000 | | | | | | | | | 8500 | | | | | | 4 | | | 40000 | | | 50 | | | | | |
| | | | | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals |
| VMP-14 | 5 ft | VMP 14-5-091010 | 9/10/2010 | | | | <0.3 | U | | <0.25 | U | | <0.22 | U | | <0.61 | U | | <0.3 | U | | <0.26 | U | | <0.42 | U | | <0.42 | U | | <0.18 | U | | <0.23 | U | | <1.8 | U | |
| | | VMP-14-5-120110 | 12/1/2010 | | | | <0.0059 | U | | <0.0049 | U | | 0.00061 | J | | 0.15 | | | <0.0059 | U | | <0.0051 | U | | <0.0082 | U | | <0.0081 | U | | 0.0025 | J | | <0.0045 | U | | <0.036 | U | |
| | | VMP-14-5-021711 | 2/17/2011 | | | | <0.0065 | J | U | <0.0054 | U | | <0.0048 | U | | 0.0053 | J | | <0.0065 | J | U | <0.0056 | U | | <0.0091 | U | | <0.009 | U | | <0.0039 | U | | <0.005 | J | U | <0.039 | U | |
| | | VMP-14-5-040511 | 4/5/2011 | 1.7 | E | J | <0.0066 | U | | <0.0055 | U | | 0.00051 | J | | 0.004 | J | | <0.0066 | U | | <0.0057 | U | | <0.0092 | U | | <0.0091 | J | U | <0.004 | U | | 0.0032 | J | | <0.04 | J | U |
| | | VMP-14-5-080811 | 8/8/2011 | 4700 | | | <6.9 | U | | <5.8 | U | | <5.1 | U | | <14 | U | | <6.9 | U | | <6 | U | | <9.6 | U | | <9.5 | U | | <4.1 | U | | <5.3 | U | | <42 | U | |
| | | VMP-14-5-111411 | 11/14/2011 | 0.0097 | J | | 0.0022 | J | | 0.019 | | | <0.013 | U | | 0.0088 | J | | <0.017 | U | | <0.015 | U | | <0.024 | U | | <0.024 | U | | <0.01 | U | | 0.02 | | | <0.1 | U | |
| | | VMP-14-5-042012 | 4/20/2012 | 0.063 | | | 0.013 | | | 0.096 | | | <0.0031 | U | | 0.017 | | | <0.0042 | U | | <0.0036 | U | | <0.0059 | U | | 0.0025 | J | | 0.0037 | | | 0.012 | | | <0.025 | U | |
| | | VMP-14-5-072312 | 7/23/2012 | <0.012 | U | | 0.075 | | | 0.47 | | | <0.0037 | U | | 0.11 | | | 0.00095 | J | | 0.0034 | J | | <0.0071 | U | | 0.002 | J | | 0.0015 | J | | 0.12 | | | <0.03 | U | |
| | | VMP-14-5-101012 | 10/10/2012 | <0.017 | U | | 0.0061 | J | | 0.037 | | | <0.0052 | U | | 0.0089 | J | | <0.0071 | U | | <0.0062 | U | | <0.0099 | U | | 0.004 | J | | <0.0043 | U | | 0.0078 | | | <0.043 | U | |
| | | VMP-14-5-013113 | 1/31/2013 | 0.0017 | J | | <0.0066 | J | U | <0.0055 | U | | <0.0048 | U | | 0.0022 | J | | <0.0066 | J | U | <0.0057 | U | | <0.0092 | U | | <0.0091 | J | U | <0.004 | U | | <0.0051 | J | U | <0.04 | J | U |
| | 11.5 ft | VMP-14-11.5-091010 | 9/10/2010 | | | | 0.97 | J | | <3.9 | U | | <3.4 | U | | <9.4 | U | | <4.7 | U | | <4.1 | U | | <6.6 | U | | <6.5 | U | | <3.6 | U | | <28 | U | | <2.5 | U | |
| | | VMP-14-11.5-120110 | 12/2/2010 | | | | <0.41 | U | | <0.34 | U | | <0.3 | U | | 0.39 | J | | <0.41 | U | | <0.36 | U | | <0.58 | U | | <0.57 | U | | <0.25 | U | | <0.32 | U | | <2.5 | U | |
| | | VMP-14-11.5-120110-DUP | 12/2/2010 | | | | <0.37 | U | | <0.31 | U | | <0.27 | U | | 0.42 | J | | <0.37 | U | | <0.32 | U | | <0.52 | U | | <0.52 | U | | <0.22 | U | | 0.15 | J | | <2.2 | U | |
| | | VMP-14-11.5-021711 | 2/17/2011 | | | | <0.14 | U | | <0.11 | U | | <0.1 | U | | <0.27 | U | | <0.14 | U | | <0.12 | U | | <0.19 | U | | <0.19 | U | | <0.081 | U | | <0.1 | U | | <0.82 | U | |
| | | VMP-14-11.5-021711-DUP | 2/17/2011 | | | | <0.14 | U | | <0.11 | U | | <0.1 | U | | <0.27 | U | | <0.14 | U | | <0.12 | U | | <0.19 | U | | <0.19 | U | | <0.081 | U | | <0.1 | U | | <0.82 | U | |
| | | VMP-14-11.5-040511 | 4/5/2011 | 43 | E | J | <0.022 | U | | <0.018 | U | | <0.016 | U | | <0.044 | U | | 0.02 | J | | <0.019 | U | | <0.031 | U | | <0.03 | U | | <0.013 | U | | 0.035 | | | <0.13 | U | |
| | | VMP-14-11.5-080811 | 8/8/2011 | 490 | | | <0.68 | U | | <0.57 | U | | <0.5 | U | | <1.4 | U | | <0.68 | U | | <0.59 | U | | <0.95 | U | | <0.94 | U | | <0.41 | U | | <0.52 | U | | <4.1 | U | |
| | | VMP-14-11.5-111511 | 11/15/2011 | 1000 | | | <1.1 | U | | <0.88 | U | | <0.78 | U | | 0.42 | J | | <1.1 | U | | <0.92 | U | | <1.5 | U | | <1.5 | U | | <0.64 | U | | 1.9 | | | <6.4 | U | |
| | | VMP-14-11.5-012612 | 1/26/2012 | 2400 | | | <4.3 | U | | <3.6 | U | | <3.2 | U | | <8.6 | U | | <4.3 | U | | <3.7 | U | | <6 | U | | <6 | U | | <2.6 | U | | <3.3 | U | | <26 | U | |
| | | VMP-14-11.5-042312 | 4/23/2012 | 0.071 | | | 0.008 | | | 0.054 | | | <0.0033 | U | | 0.024 | | | <0.0045 | U | | <0.0039 | U | | <0.0063 | U | | 0.0014 | J | | <0.0027 | U | | 0.015 | | J | <0.027 | U | |
| | | VMP-14-11.5-042312-Dup | 4/23/2012 | 0.074 | | | 0.0059 | | | 0.045 | | | <0.0033 | U | | 0.0073 | J | | <0.0045 | U | | <0.0039 | U | | <0.0063 | U | | <0.0062 | U | | <0.0027 | U | | 0.0058 | | J | <0.027 | U | |
| | | VMP-14-11.5-072512 | 7/25/2012 | 830 | | | <1.6 | U | | <1.3 | U | | <1.2 | U | | <3.2 | U | | <1.6 | U | | <1.4 | U | | <2.2 | U | | <2.2 | U | | <0.95 | U | | <1.2 | U | | <9.5 | U | |
| | | VMP-14-11.5-101012 | 10/10/2012 | 0.094 | | | <0.0068 | U | | <0.0056 | U | | <0.005 | U | | 0.012 | J | | <0.0068 | U | | <0.0059 | U | | <0.0095 | U | | <0.0094 | U | | <0.0041 | U | | 0.0027 | J | | <0.041 | U | |
| | | VMP-14-11.5-013113 | 1/31/2013 | 0.0029 | J | | <0.0063 | U | | <0.0053 | U | | <0.0046 | U | | 0.0018 | J | | <0.0063 | J | U | <0.0055 | U | | <0.0088 | U | | <0.0088 | J | U | <0.0038 | U | | <0.0049 | J | U | 0.008 | J | |
| | 20 ft | VMP-14-20-091010 | 9/10/2010 | | | | 6.4 | J | | <60 | U | | <52 | U | | <140 | U | | <72 | U | | <62 | U | | <100 | U | | <99 | U | | <43 | U | | <55 | U | | <430 | U | |
| | | VMP-14-20-091010-Dup | 9/10/2010 | | | | <74 | U | | <62 | U | | <54 | U | | <150 | U | | <74 | U | | <64 | U | | <100 | U | | <100 | U | | <44 | U | | <57 | U | | <450 | U | |
| | | VMP-14-20-120110 | 12/2/2010 | | | | <190 | U | | <160 | U | | <140 | U | | <380 | U | | <190 | U | | <170 | U | | <270 | U | | <260 | U | | <120 | U | | <150 | U | | <1200 | U | |
| | | VMP-14-20-021811 | 2/18/2011 | | | | <110 | U | | <91 | U | | <80 | U | | <220 | U | | <110 | U | | <94 | U | | <150 | U | | <150 | U | | <65 | U | | <83 | U | | <660 | U | |
| | | VMP-14-20-040511 | 4/5/2011 | 3200 | | | <47 | U | | <39 | U | | <34 | U | | <93 | U | | <47 | U | | <40 | U | | <65 | U | | <64 | U | | <28 | U | | <36 | U | | <280 | U | |
| | | VMP-14-20-080811 | 8/8/2011 | 6100 | | | <17 | U | | <14 | U | | <12 | U | | <34 | U | | <17 | U | | <15 | U | | <24 | U | | <23 | U | | <10 | U | | <13 | U | | <100 | U | |
| | | VMP-14-20-111511 | 11/15/2011 | 6600 | | | <88 | U | | <73 | U | | <64 | U | | <170 | U | | <88 | U | | <76 | U | | <120 | U | | <120 | U | | <52 | U | | 34 | J | | <530 | U | |
| | | VMP-14-20-012612 | 1/26/2012 | 6600 | | | <8.6 | U | | <7.2 | U | | <6.3 | U | | 1.2 | J | J | <8.6 | U | | <7.4 | U | | <12 | U | | <12 | U | | <5.2 | U | | 2.2 | J | J | <52 | U | |
| | | VMP-14-20-042312 | 4/23/2012 | 4900 | | | 0.67 | J | | <3.9 | U | | <3.4 | U | | <9.4 | U | | <4.7 | U | | <4.1 | U | | <6.6 | U | | <6.5 | U | | <2.8 | U | | 1.8 | J | | <28 | U | |
| | | VMP-14-20-072512 | 7/25/2012 | 4700 | | | <7.5 | U | | <6.2 | U | | <5.5 | U | | <15 | U | | <7.5 | U | | <6.5 | U | | <10 | U | | <10 | U | | <4.5 | U | | <5.7 | U | | <45 | U | |
| | | VMP-14-20-101612 | 10/16/2012 | 3300 | | | <35 | U | | <29 | U | | <25 | U | | <69 | U | | <35 | U | | <30 | U | | <48 | U | | <48 | U | | <21 | U | | 8.7 | J | | <210 | U | |
| | | VMP-14-20-013113 | 1/31/2013 | 1500 | | | <12 | U | | 5.3 | J | | <9.1 | U | | 8.2 | J | | <12 | U | | 2.6 | J | | <17 | U | | <17 | U | | <7.4 | U | | 4.1 | J | | 9.3 | J | |
| | 29 ft | VMP-14-29-021811 | 2/18/2011 | | | | <160 | U | | <130 | U | | <120 | U | | <320 | U | | <160 | U | | <140 | U | | <220 | U | | <220 | U | | <95 | U | | 47 | J | | <950 | U | |
| | | VMP-14-29-040511 | 4/5/2011 | 4600 | | | <140 | U | | <110 | U | | <100 | U | | <270 | U | | <140 | U | | <120 | U | | <190 | U | | <190 | U | | <81 | U | | 50 | J | | <820 | U | |
| | | VMP-14-29-012612 | 1/26/2012 | 7300 | | | <150 | U | | <130 | U | | <110 | U | | <310 | U | | <150 | U | | <130 | U | | <220 | U | | <210 | U | | <92 | U | | <120 | U | | <930 | U | |
| | | VMP-14-29-042312 | 4/23/2012 | 4700 | | | <55 | U | | <46 | U | | <40 | U | | <110 | U | | <55 | U | | <48 | U | | <77 | U | | <76 | U | | <33 | U | | 7.3 | J | | <330 | U | |
| | | VMP-14-29-072512 | 7/25/2012 | 5400 | | | <58 | U | | <48 | U | | <42 | U | | <120 | U | | <58 | U | | <50 | U | | <81 | U | | <80 | U | | <35 | U | | <44 | U | | <350 | U | |
| | | VMP-14-29-101612 | 10/16/2012 | 3000 | | | <86 | U | | <72 | U | | <63 | U | | <170 | U | | <86 | U | | <75 | U | | <120 | U | | <120 | U | | <52 | U | | 9 | J | | <520 | U | |
| | | VMP-14-29-013113-DUP | 1/31/2013 | 1600 | | J | <120 | U | | <97 | U | | <85 | U | | <230 | U | | <120 | U | | <100 | U | | <160 | U | | <160 | U | | <70 | U | | <89 | U | UJ | <700 | U | |
| | | VMP-14-29-013113 | 1/31/2013 | 5600 | | J | <48 | U | | <40 | U | | <36 | U | | <97 | U | | <48 | U | | <42 | U | | <68 | U | | <67 | U | | <29 | U | | 8 | J | J | <290 | U | |
| VMP-15 | 5 ft | VMP 15-5-091410 | 9/14/2010 | | | | <0.0062 | U | | <0.0052 | U | | <0.0045 | U | | 0.018 | | | <0.0062 | U | | <0.0054 | U | | <0.0086 | U | | 0.0016 | J | | <0.0037 | U | | 0.0018 | J | | <0.037 | U | |
| | | VMP-15-5-113010 | 11/30/2010 | | | | <0.15 | U | | <0.12 | U | | <0.11 | U | | <0.29 | U | | 0.065 | J | | <0.13 | U | | <0.2 | U | | <0.2 | U | | <0.088 | U | | <0.11 | U | | <0.89 | U | |
| | | VMP-15-5-021611 | 2/16/2011 | | | | <0.14 | U | | <0.12 | U | | <0.1 | U | | 0.17 | J | | <0.14 | U | | 0.036 | J | | <0.19 | U | | <0.19 | U | | <0.083 | U | | 0.1 | J | | <0.84 | U | |
| | | VMP-15-5-042011 | 4/20/2011 | 140 | | | <0.32 | U | | <2.7 | U | | <0.24 | U | | <0.65 | U | | <0.32 | U | | <2.8 | U | | <0.45 | U | | <0.45 | U | | <0.19 | U | | <0.25 | U | | <2 | U | |
| | | VMP-15-5-080811 | 8/8/2011 | 0.014 | J | | 0.01 | | | 0.07 | | | <0.0054 | U | | 0.04 | | | <0.0073 | J | U | 0.0018 | J | | <0.01 | U | | 0.0013 | J | | <0.0044 | U | | 0.013 | | | <0.044 | J | U |
| | | VMP-15-5-111511 | 11/15/2011 | 0.26 | | | 0.0072 | J | | 0.03 | | | <0.006 | U | | 0.036 | | | 0.0019 | J | | <0.0071 | U | | <0.011 | U | | <0.011 | U | | <0.0049 | U | | 0.012 | | | <0.049 | U | |
| | | VMP-15-5-020112 | 2/1/2012 | 0.014 | J | | 0.03 | J | | 0.049 | | | <0.031 | U | | 0.029 | J | | 0.067 | | | <0.036 | U | | <0.059 | U | | <0.058 | U | | <0.025 | U | | 0.011 | J | | <0.25 | U | UJ |
| | | VMP-15-5-042412 | 4/24/2012 | 0.25 | | | 0.0094 | J | | <0.036 | U | | <0.032 | U | | 0.1 | | | <0.043 | U | | <0.037 | U | | <0.06 | U | | <0.059 | U | | <0.026 | U | | 0.01 | J | | <0.26 | U | |
| | | VMP-15-5-072512 | 7/25/2012 | 0.0034 | J | | 0.03 | | | 0.06 | | | <0.0036 | U | | 0.0099 | | | 0.0012 | J | | 0.004 | J | | <0.0068 | U | | <0.0067 | U | | <0.0029 | U | | 0.026 | | | <0.029 | U | |
| | | VMP-15-5-102512 | 10/25/2012 | 0.1 | | | 0.052 | | | 0.11 | | | <0.0054 | U | | 0.026 | | | <0.0073 | J | U | <0.0063 | U | | <0.01 | U | | 0.0051 | J | | <0.0044 | U | | 0.013 | | | <0.044 | U | |
| | | VMP-15-5-020513 | 2/5/2013 | 0.0019 | J | | <0.0071 | U | | <0.0059 | U | | <0.0052 | U | | 0.025 | | | <0.0071 | U | | <0.0062 | U | | <0.0099 | U | | <0.0098 | U | | <0.0043 | U | | <0.0054 | J | U | <0.043 | U | |
| | 21.5 ft | VMP-15-21.5-091410 | 9/14/2010 | | | | <0.67 | U | | <0.56 | U | | <0.49 | U | | <1.3 | U | | <0.67 | U | | <0.58 | U | | <0.94 | U | | <0.93 | U | | <0.4 | U | | <0.52 | U | | <4.1 | U | |
| | | VMP-15-21.5-113010 | 11/30/2010 | | | | <0.79 | U | | <0.66 | U | | <0.58 | U | | <1.6 | U | | <0.79 | U | | <0.68 | U | | <1.1 | U | | <1.1 | U | | <0.47 | U | | <0.6 | U | | <4.8 | U | |
| | | VMP-15-21.5-021611 | 2/16/2011 | | | | <0.55 | U | | <0.46 | U | | <0.4 | U | | <1.1 | U | | <0.55 | U | | <0.48 | U | | <0.77 | U | | <0.76 | U | | <0.33 | U | | <0.42 | U | | <3.3 | U | |
| | | VMP-15-21.5-042011 | 4/20/2011 | 190 | | | <0.86 | U | | <7.2 | U | | <0.63 | U | | <1.7 | U | | <0.86 | U | | <7.5 | U | | <1.2 | U | | <1.2 | U | | <0.52 | U | | <0.66 | U | | <5.2 | U | |
| | | VMP-15-21.5-080811 | 8/8/2011 | 130 | | | <0.69 | U | | <0.58 | U | | <0.51 | U | | <1.4 | U | | <0.69 | U | | <0.6 | U | | <0.97 | U | | <0.96 | U | | <0.42 | U | | 0.1 | J | | <4.2 | U | |
| | | VMP-15-21.5-111511 | 11/15/2011 | 100 | | | <0.55 | U | | <0.46 | U | | <0.4 | U | | <1.1 | U | | <0.55 | U | | <0.48 | U | | <0.77 | U | | <0.76 | U | | <0.33 | U | | <0.42 | U | | <3.3 | U | |
| | | VMP-15-21.5-020112 | 2/1/2012 | 7.9 | | J | <0.41 | U | | <0.34 | U | | <0.3 | U | | <0.82 | U | | <0.41 | U | | <0.36 | U | | <0.58 | U | | <0.57 | U | | <0.25 | U | | <0.32 | U | | <2.5 | U | UJ |
| | | VMP-15-21.5-042412 | 4/24/2012 | 9.8 | | | <0.18 | U | | <0.15 | U | | <0.13 | U | | <0.36 | U | | <0.18 | U | | <0.16 | U | | <0.25 | U | | <0.25 | U | | <0.11 | U | | <0.14 | U | | <1.1 | U | |
| | | VMP-15-21.5-072512 | 7/25/2012 | 4.2 | | | <0.65 | U | | <0.54 | U | | <0.48 | U | | 0.12 | J | | <0.65 | U | | <0.56 | U | | <0.91 | U | | <0.9 | U | | <0.39 | U | | 0.14 | J | | <3.9 | U | |
| | | VMP-15-21.5-102512 | 10/25/2012 | 6.2 | | | <1.1 | U | | <0.89 | U | | <0.78 | U | | <2.1 | U | | <1.1 | U | | <0.92 | U | | <1.5 | U | | <1.5 | U | | <0.64 | U | | <0.82 | U | | <6.4 | U | UJ |
| | | VMP-15-21.5-102512-Dup | 10/25/2012 | 6.4 | | | <1.1 | U | | <0.91 | U | | <0.8 | U | | <2.2 | U | | <1.1 | U | | <0.95 | U | | <1.5 | U | | <1.5 | U | | <0.66 | U | | <0.84 | U | | <6.6 | U | UJ |
| | | VMP-15-21.5-020713 | 2/7/2013 | 0.9 | | | <0.027 | U | | <0.022 | U | | <0.02 | U | | 0.026 | J | | <0.027 | U | | <0.023 | U | | <0.038 | U | | <0.037 | U | | <0.016 | U | | 0.0057 | J | | <0.16 | U | |
| | 25.5 ft | VMP 15-25.5-091410 | 9/14/2010 | | | | <0.0063 | U | | <0.0053 | U | | <0.0046 | U | | 0.0041 | J | | <0.0063 | U | | <0.0055 | U | | <0.0088 | U | | <0.0088 | U | | 0.0033 | J | | 0.0011 | J | | <0.038 | U | |
| | | VMP-15-25.5-021611 | 2/16/2011 | | | | <0.084 | U | | <0.07 | U | | <0.062 | U | | 0.057 | J | | <0.084 | U | | <0.073 | U | | <0.12 | U | | <0.12 | U | | <0.051 | U | | <0.065 | U | | <0.51 | U | |
| | | VMP-15-25.5-042011 | 4/20/2011 | 0.42 | | J | <0.069 | U | | <0.58 | U | | <0.051 | U | | <0.14 | U | | <0.069 | U | | <0.6 | U | | <0.097 | U | | <0.096 | U | | <0.042 | U | | <0.053 | U | | <0.42 | U | |
| | | VMP-15-25.5-042011-DUP | 4/20/2011 | 2.5 | | J | <0.065 | U | | <0.54 | U | | <0.048 | U | | <0.13 | U | | <0.065 | U | | <0.56 | U | | <0.091 | U | | <0.09 | U | | <0.039 | U | | <0.05 | U | | <0.39 | U | |
| | | VMP-15-25.5-080811 | 8/8/2011 | 4.8 | | | 0.022 | J | | <0.058 | U | | <0.051 | U | | <0.14 | U | | <0.069 | U | | <0.06 | U | | <0.097 | U | | <0.096 | U | | <0.042 | U | | 0.022 | J | | <0.42 | U | |
| | | VMP-15-25.5-111511 | 11/15/2011 | 4.3 | | | 0.0026 | J | | 0.044 | | | <0.016 | U | | 0.033 | J | | <0.021 | U | | <0.018 | U | | <0.03 | U | | <0.029 | U | | <0.013 | U | | 0.015 | J | | <0.13 | U | |
| | | VMP-15-25.5-073112 | 7/31/2012 | 12 | | | 0.032 | J | | 0.062 | | | <0.033 | U | | 0.013 | J | | <0.045 | U | | <0.039 | U | | <0.063 | U | | <0.062 | U | | <0.027 | U | | 0.051 | | | <0.27 | U | |
| | | VMP-15-25.5-102512 | 10/25/2012 | 0.72 | | | 0.049 | | | 0.14 | | | <0.0054 | U | | 0.026 | | J | <0.0073 | U | | 0.00064 | J | | <0.01 | U | | <0.01 | U | | 0.0014 | J | | 0.011 | | | <0.11 | U | UJ |
| | | VMP-15-25.5-021213 | 2/12/2013 | 37 | | | 0.07 | J | | <0.73 | U | | <0.16 | U | | <0.44 | U | | <0.22 | U | | <0.19 | U | | <0.31 | U | | <0.3 | U | | <0.13 | U | | <0.17 | U | | <1.3 | U | |
| | 29 ft | VMP-15-29-073112 | 7/31/2012 | 110 | | | 0.06 | J | J | <0.16 | U | | <0.14 | U | | 0.024 | J | J | <0.19 | U | | <0.17 | U | | <0.27 | U | | <0.26 | U | | <0.12 | U | | 0.098 | J | J | <1.2 | U | |
| | | VMP-15-29-102512 | 10/25/2012 | 2.1 | | | 0.075 | | | 0.23 | | | <0.011 | U | | 0.059 | | J | <0.015 | U | | 0.0012 | J | | <0.021 | U | | <0.021 | U | | 0.0024 | J | | 0.016 | | | <0.23 | U | UJ |
| | | VMP-15-29-021213 | 2/12/2013 | 48 | | | <0.13 | U | | <0.44 | U | | <0.097 | U | | <0.26 | U | | <0.13 | U | | <0.11 | U | | <0.18 | U | | <0.18 | U | | <0.079 | U | | <0.1 | U | | <0.8 | U | |

SEE LAST PAGE OF TABLE FOR NOTES

**TABLE 6**
**CUMULATIVE SUMMARY OF SOIL VAPOR ANALYTICAL DETECTIONS AND SCREENING RESULTS: PUBLIC WORKS YARD AND WRR - VOCS**

| Location | Depth | Sample ID | Sample Date | Isopentane | | | Isopropylbenzene (Cumene) | | | 4-Methyl-2-pentanone (Methyl | | | Methyl tert-Butyl Ether (MTBE) | | | 2-Propanol | | | n-Propylbenzene | | | Styrene | | | 1,1,2,2-Tetrachloroethane | | | Tetrachloroethene | | | Tetrahydrofuran | | | Toluene | | | 1,2,4-Trichlorobenzene | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | | | | 3500 | | | | | | 23000 | | | | | | | | | 8500 | | | | | | 4 | | | | | | 40000 | | | 50 | | |
| | | | | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals |
| VMP-16 | 5 ft | VMP-16-5-090210 | 9/2/2010 | | | | 14 | | | <9.7 | U | | 2.7 | J | | <23 | U | | 20 | | | <10 | U | | <16 | U | | <16 | U | | <7 | U | | <9 | U | | <71 | U | |
| | | VMP-16-5-112910 | 11/29/2010 | | | | 4.2 | J | J | <4.5 | U | | 1.2 | J | J | <11 | U | | 4.4 | J | J | <4.6 | U | | <7.5 | U | | <7.4 | U | | <3.2 | U | | <4.1 | U | | <32 | U | |
| | | VMP-16-5-021511 | 2/15/2011 | | | | <3.2 | U | | <2.7 | U | | <2.4 | U | | <6.5 | U | | 1.4 | J | J | <2.8 | U | | <4.5 | U | | <4.5 | U | | <1.9 | U | | 2.4 | J | J | <20 | U | |
| | | VMP-16-5-042211 | 4/22/2011 | 4800 | | | <4.3 | U | | <36 | U | | 1.9 | J | | <8.6 | U | | <4.3 | U | | <37 | U | | <6 | U | | <6 | U | | <2.6 | U | | <3.3 | U | | <26 | U | |
| | | VMP-16-5-080511 | 8/5/2011 | 760 | | | <1.4 | U | | <1.2 | U | | 0.29 | J | | <2.8 | U | | <1.4 | U | | <1.2 | U | | <1.9 | U | | <1.9 | U | | <0.83 | U | | <1 | U | | <8.3 | U | |
| | | VMP-16-5-042512 | 4/25/2012 | 2400 | | | <4.7 | U | | <3.9 | U | | 0.83 | J | | <9.4 | U | | <4.7 | U | | <4.1 | U | | <6.6 | U | | 1.4 | J | | <2.8 | U | | <3.6 | U | | <28 | U | |
| | | VMP-16-5-073012 | 7/30/2012 | 1400 | | J | 0.58 | J | J | <3.7 | U | | 0.84 | J | J | <8.8 | U | | 0.67 | J | J | <3.8 | U | | <6.1 | U | | <6.1 | U | | 0.31 | J | J | <26 | U | | <26 | U | |
| | | VMP-16-5-102512 | 10/25/2012 | 120 | | | <3.5 | U | | <2.9 | U | | <2.5 | U | | <6.9 | U | | <3.5 | U | | <3 | U | | <4.9 | U | | <4.8 | U | | <2.1 | U | | 0.18 | J | | <21 | U | |
| | | VMP-16-5-021413 | 2/14/2013 | 5.4 | | J | <0.54 | U | | <1.8 | U | | <0.4 | U | | <1.1 | U | | <0.54 | U | | <0.47 | U | | <0.76 | U | | <0.75 | U | | <0.32 | U | | <0.41 | U | | <3.3 | U | |
| | 13.5 ft | VMP-16-13.5-090210 | 9/2/2010 | | | | 15 | | | <10 | U | | 2.9 | J | | <24 | U | | 24 | | | <10 | U | | <17 | U | | <17 | U | | <7.3 | U | | 1.4 | J | | <73 | U | |
| | | VMP-16-13.5-090210-DUP | 9/2/2010 | | | | 16 | | | <10 | U | | 3.1 | J | | <24 | U | | 23 | | | <10 | U | | <17 | U | | <17 | U | | <7.3 | U | | 1.6 | J | | <73 | U | |
| | | VMP-16-13.5-112910 | 11/29/2010 | | | | <34 | U | | <29 | U | | <25 | U | | <69 | U | | <34 | U | | <30 | U | | <48 | U | | <47 | U | | <21 | U | | <26 | U | | <210 | U | |
| | | VMP-16-13.5-021611 | 2/16/2011 | | | | <6.6 | U | | <5.5 | U | | <4.8 | U | | <13 | U | | <6.6 | U | | <5.7 | U | | <9.2 | U | | <9.1 | U | | <4 | U | | <5.1 | U | | <40 | U | |
| | | VMP-16-13.5-021611-DUP | 2/16/2011 | | | | <6.5 | U | | <5.4 | U | | <4.8 | U | | <13 | U | | <6.5 | U | | <5.6 | U | | <9.1 | U | | <9 | U | | <3.9 | U | | <5 | U | | <39 | U | |
| | | VMP-16-13.5-042211 | 4/22/2011 | 4800 | | | <7 | U | | <58 | U | | 2.6 | J | | <14 | U | | <7 | U | | <60 | U | | <9.7 | U | | <9.6 | U | | <4.2 | U | | <5.4 | U | | <42 | U | |
| | | VMP-16-13.5-080511 | 8/5/2011 | 190 | | J | <0.68 | U | UJ | <0.56 | U | UJ | 0.29 | J | J | <1.4 | U | UJ | <0.68 | U | UJ | <0.59 | U | UJ | <0.95 | U | UJ | <0.94 | U | UJ | <0.41 | U | UJ | 0.12 | J | J | <4.1 | U | UJ |
| | | VMP-16-13.5-042512 | 4/25/2012 | 5200 | | | 0.8 | | J | <0.62 | U | | <0.55 | U | | 0.094 | J | J | 1.1 | | J | <0.65 | U | | <1 | U | | 0.14 | J | J | <0.45 | U | | <0.57 | U | | <4.5 | U | |
| | | VMP-16-13.5-073012 | 7/30/2012 | 4100 | | | <22 | U | | <19 | U | | 2.7 | J | | <45 | U | | <22 | U | | <19 | U | | <31 | U | | <31 | U | | <13 | U | | 2.5 | J | | <140 | U | |
| | | VMP-16-13.5-102512 | 10/25/2012 | 2500 | | | <69 | U | | <58 | U | | <51 | U | | <140 | U | | <69 | U | | <60 | U | | <97 | U | | <96 | U | | <42 | U | | 4.1 | J | | <420 | U | |
| | | VMP-16-13.5-021413 | 2/14/2013 | 1800 | | J | 4 | J | J | <37 | U | | 2.1 | J | J | <22 | U | | 7.8 | J | J | <9.5 | U | | <15 | U | | <15 | U | | <6.6 | U | | 2.8 | J | J | <66 | U | |
| | 19 ft | VMP-16-19-090210 | 9/2/2010 | | | | 24 | | | <10 | U | | 3.1 | J | | <24 | U | | 35 | | | <10 | U | | <17 | U | | <17 | U | | <7.3 | U | | <9.3 | U | | <73 | U | |
| | | VMP-16-19-112910 | 11/29/2010 | | | | 9.4 | J | | <22 | U | | <19 | U | | <53 | U | | 12 | J | | <23 | U | | <37 | U | | <37 | U | | <16 | U | | <20 | U | | <160 | U | |
| | | VMP-16-19-021611 | 2/16/2011 | | | | <6.3 | U | | <5.3 | U | | <4.6 | U | | <13 | U | | <6.3 | U | | <5.5 | U | | <8.8 | U | | <8.8 | U | | <3.8 | U | | <4.9 | U | | <38 | U | |
| | | VMP-16-19-042711 | 4/27/2011 | 2800 | | | <6.5 | U | | <54 | U | | 1.2 | J | | <13 | U | | <6.5 | U | | <56 | U | | <9.1 | U | | <9 | U | | <3.9 | U | | <5 | U | | <39 | U | |
| | | VMP-16-19-042711-DUP | 4/27/2011 | 2800 | | | <6.3 | U | | <53 | U | | 1.3 | J | | <13 | U | | <6.3 | U | | <55 | U | | <8.8 | U | | <8.8 | U | | <3.8 | U | | <4.9 | U | | <38 | U | |
| | | VMP-16-19-042512 | p | 5600 | | | 2.3 | J | | <14 | U | | 4 | J | | <35 | U | | 4 | J | | <15 | U | | <24 | U | | <24 | U | | <10 | U | | <13 | U | | <100 | U | |
| | | VMP-16-19-073012 | 7/30/2012 | 5200 | | | 3.3 | J | | <13 | U | | 3.3 | J | | <31 | U | | 5.2 | J | | <13 | U | | <22 | U | | <21 | U | | <9.3 | U | | 1.6 | J | | <94 | U | |
| | | VMP-16-19-102512 | 10/25/2012 | 4100 | | | <65 | U | | <54 | U | | <48 | U | | <130 | U | | <65 | U | | <56 | U | | <91 | U | | <90 | U | | <39 | U | | 5.7 | J | | <390 | U | |
| | | VMP-16-19-021413 | 2/14/2013 | 3800 | | J | 27 | | J | <22 | U | | 4.5 | J | J | <13 | U | | 45 | | J | <5.6 | U | | <9.1 | U | | <9 | U | | <3.9 | U | | 0.83 | J | J | <39 | U | |
| | 31 ft | VMP-16-31-090310 | 9/3/2010 | | | | 0.0037 | J | | <0.0059 | U | | 0.014 | | | 0.041 | | | 0.0047 | J | | <0.0062 | U | | <0.0099 | U | | <0.0098 | U | | <0.0043 | U | | 0.0016 | J | | <0.043 | U | |
| | | VMP-16-31-112910 | 11/29/2010 | | | | 12 | J | | <22 | U | | <20 | U | | <54 | U | | 14 | J | | <23 | U | | <37 | U | | <37 | U | | <16 | U | | <20 | U | | <160 | U | |
| | | VMP-16-31-042512 | 4/25/2012 | 6200 | | | 3.6 | J | | <18 | U | | 4.8 | J | | <42 | U | | 6.3 | J | | <18 | U | | <29 | U | | <29 | U | | <13 | U | | <16 | U | | <130 | U | |
| | | VMP-16-31-073012 | 7/30/2012 | 6200 | | | <17 | U | | <14 | U | | 3.3 | J | | <34 | U | | <17 | U | | <15 | U | | <24 | U | | <24 | U | | <10 | U | | 4 | J | | <100 | U | |
| | | VMP-16-31-102512 | 10/25/2012 | 4200 | | | <81 | U | | <67 | U | | <59 | U | | <160 | U | | <81 | U | | <70 | U | | <110 | U | | <110 | U | | <48 | U | | 3.9 | J | | <490 | U | |
| | | VMP-16-31-021813 | 2/18/2013 | 4600 | | | 21 | J | | <82 | U | | 4.1 | J | | <49 | U | | 36 | | | <21 | U | | <34 | U | | <34 | U | | <15 | U | | <19 | U | | <150 | U | |
| VMP-17 | 5 ft | VMP-17-5 | 6/21/2010 | | | | <0.007 | U | | <0.006 | U | | <0.005 | U | | 2.1 | E | J | <0.007 | U | | <0.006 | U | | <0.01 | U | | <0.009 | J | U | <0.004 | U | | 0.001 | J | | <0.043 | U | |
| | | VMP-17-5-DUP | 6/21/2010 | | | | <0.007 | U | | <0.006 | U | | <0.005 | U | | 1.6 | E | J | <0.007 | U | | <0.006 | U | | <0.01 | U | | <0.01 | J | U | <0.004 | U | | <0.005 | U | | <0.044 | U | |
| | | VMP-17-5-090110 | 9/1/2010 | | | | <0.0066 | U | | <0.0055 | U | | <0.0048 | U | | 0.027 | | | <0.0066 | U | | <0.0057 | U | | <0.0092 | U | | <0.0091 | J | U | 0.0034 | J | | 0.0078 | | | <0.04 | J | UJ |
| | | VMP-17-5-112210 | 11/22/2010 | | | | <0.0066 | U | | <0.0055 | U | | <0.0048 | U | | 0.022 | | | <0.0066 | U | | 0.0027 | J | | <0.0092 | U | | <0.0091 | J | U | <0.004 | U | | <0.0051 | J | U | <0.04 | U | |
| | | VMP-17-5-020711 | 2/7/2011 | | | | <0.0062 | U | | <0.0052 | U | | <0.0045 | U | | 0.004 | J | U | <0.0062 | J | U | <0.0054 | U | | <0.0086 | U | | <0.0085 | U | | <0.0037 | U | | 0.0021 | J | | <0.037 | J | U |
| | | VMP-17-5-040611 | 4/6/2011 | 0.18 | | | <0.025 | U | | <0.021 | U | | <0.018 | U | | <0.05 | U | | <0.025 | U | | <0.022 | U | | <0.035 | U | | <0.034 | U | | <0.015 | U | | <0.019 | U | | <0.15 | U | |
| | | VMP-17-5-080111 | 8/1/2011 | 12 | | | 0.035 | J | | 0.088 | | | <0.069 | U | | <0.19 | U | | <0.082 | U | | <0.082 | U | | <0.13 | U | | <0.13 | U | | <0.057 | U | | 0.052 | J | | <0.57 | U | |
| | | VMP-17-5-110711 | 11/7/2011 | 0.0054 | J | | 0.0017 | J | | 0.012 | | | <0.0031 | U | | 0.011 | | | <0.0042 | U | | <0.0036 | U | | <0.0059 | U | | <0.0058 | U | | <0.0025 | U | | 0.015 | | | <0.025 | U | |
| | | VMP-17-5-012612 | 1/26/2012 | 0.0026 | J | | 0.0056 | | | 0.039 | | | <0.0032 | U | | 0.039 | | | <0.0044 | U | | <0.0038 | U | | <0.0061 | U | | <0.0061 | U | | <0.0026 | U | | 0.0081 | | | <0.026 | U | |
| | | VMP-17-5-041112 | 4/11/2012 | 0.0034 | J | | 0.027 | | | 0.073 | | | <0.0033 | U | | 0.045 | | | <0.0045 | J | U | <0.0039 | J | U | <0.0063 | U | | <0.0062 | J | U | 0.0047 | | | 0.018 | | | <0.027 | U | |
| | | VMP-17-5-071112 | 7/11/2012 | 0.025 | | | 0.039 | | | 0.25 | | | <0.0035 | U | | 0.11 | | | <0.0048 | J | U | <0.0042 | J | U | <0.0067 | U | | <0.0066 | U | | 0.002 | J | | 0.063 | | | <0.029 | U | |
| | | VMP-17-5-100912 | 10/9/2012 | <0.018 | U | | <0.0074 | U | | <0.0062 | U | | <0.0055 | U | | 0.0049 | J | | <0.0074 | U | | <0.0064 | U | | <0.01 | U | | <0.01 | U | | <0.0045 | U | | 0.0011 | J | | <0.045 | U | |
| | | VMP-17-5-013113 | 1/31/2013 | 0.036 | J | | 0.012 | J | | <0.022 | U | | <0.019 | U | | 0.0065 | J | | 0.0062 | J | | <0.022 | U | | <0.036 | U | | <0.036 | U | | <0.016 | U | | 0.0028 | J | | <0.16 | J | U |
| | | VMP-17-5-013113-DUP | 1/31/2013 | 0.13 | | | 0.0068 | J | | <0.022 | U | | <0.019 | U | | <0.052 | U | | <0.026 | J | U | <0.022 | U | | <0.036 | U | | <0.036 | U | | <0.016 | U | | <0.02 | J | U | <0.16 | U | |
| VMP-25 | 5 ft | VMP-25-5-031511 | 3/15/2011 | | | | 0.28 | | | <0.05 | U | | <0.044 | U | | <0.12 | U | | 0.46 | | | <0.052 | U | | <0.083 | U | | <0.082 | U | | <0.036 | U | | 0.042 | J | | <0.36 | U | UJ |
| | | VMP-25-5-040811 | 4/8/2011 | 0.27 | | | <0.027 | U | | <0.022 | U | | 0.019 | J | | <0.054 | U | | <0.027 | U | | <0.023 | U | | <0.038 | U | | <0.037 | U | | <0.016 | U | | 0.0071 | J | | <0.16 | U | |
| | | VMP-25-5-080911 | 8/9/2011 | 0.53 | | | 0.0083 | | | 0.039 | | | 0.0023 | J | | 0.12 | | | <0.0057 | J | U | 0.0052 | | | <0.008 | U | | 0.0057 | J | | <0.0034 | U | | 1 | | | <0.034 | J | U |
| | | VMP-25-5-111711 | 11/17/2011 | 0.0036 | J | | 0.00079 | J | | 0.0037 | | | <0.003 | U | | 0.0024 | J | | <0.0041 | U | | <0.0036 | U | | <0.0058 | U | | <0.0057 | U | | <0.0025 | U | | 0.0026 | J | | <0.025 | U | |
| | | VMP-25-5-013112 | 1/31/2012 | 6.3 | | | 0.0054 | J | | 0.082 | | | <0.022 | U | | 0.026 | J | | <0.03 | U | | <0.026 | U | | <0.042 | U | | 0.0068 | J | | <0.018 | U | | 0.012 | J | | <0.18 | U | |
| | | VMP-25-5-042512 | 4/25/2012 | 0.0041 | J | | 0.024 | | | 0.086 | | | <0.0034 | U | | 0.037 | | | <0.0047 | U | | 0.001 | J | | <0.0066 | U | | <0.0065 | J | U | 0.0058 | | | 0.019 | | | <0.028 | U | |
| | | VMP-25-5-072612 | 7/26/2012 | 3 | | | 0.024 | | | 0.098 | | | <0.012 | U | | 0.039 | | | 0.013 | J | | 0.0037 | J | | <0.022 | U | | 0.0084 | J | | <0.0097 | U | | 0.042 | | | <0.098 | U | |
| | | VMP-25-5-102612 | 10/26/2012 | 0.014 | J | | 0.013 | | | 0.018 | | | <0.0048 | U | | 0.0096 | J | J | <0.0066 | U | | <0.0057 | U | | <0.0092 | U | | <0.0091 | U | | <0.004 | U | | 0.0036 | J | | <0.1 | U | UJ |
| | | VMP-25-5-030613 | 3/6/2013 | 0.029 | | | 0.0026 | J | | <0.0053 | U | | <0.0046 | U | | 0.022 | | | 0.0075 | | | <0.0055 | U | | <0.0088 | U | UJ | <0.0087 | J | U | 0.0008 | J | | 0.0053 | | | <0.038 | J | U |
| | 21 ft | VMP-25-21-031511 | 3/15/2011 | | | | 4.3 | J | | <9.7 | U | | <8.5 | U | | 15 | J | | 6.7 | J | | 1.4 | J | | <16 | U | | <16 | U | | <7 | U | | 27 | | | <70 | U | |
| | | VMP-25-21-031511-DUP | 3/15/2011 | | | | 6.7 | J | | <12 | U | | <11 | U | | 27 | J | | 9.3 | J | | <13 | U | | <21 | U | | <20 | U | | <8.9 | U | | 16 | | | <90 | U | |
| | | VMP-25-21-040811 | 4/8/2011 | 23000 | | | <120 | U | | <100 | U | | <91 | U | | 38 | J | | 17 | J | | <110 | U | | <170 | U | | <170 | U | | <74 | U | | 12 | J | | <750 | U | |
| | | VMP-25-21-040811-DUP | 4/8/2011 | 23000 | | | <120 | U | | <100 | U | | <92 | U | | <250 | U | | <120 | U | | <110 | U | | <180 | U | | <170 | U | | <75 | U | | <96 | U | | <760 | U | |
| | | VMP-25-21-080911 | 8/9/2011 | 19000 | | | 9.7 | J | | <34 | U | | <30 | U | | <81 | U | | 36 | J | | <35 | U | | <57 | U | | 270 | | | <24 | U | | 1200 | | | <240 | U | |
| | | VMP-25-21-111711 | 11/17/2011 | 14000 | | | <55 | U | | <46 | U | | <40 | U | | <110 | U | | <55 | U | | <48 | U | | <77 | U | | <76 | U | | <33 | U | | <42 | U | | <330 | U | |
| | | VMP-25-21-111711-DUP | 11/17/2011 | 14000 | | | <82 | U | | <68 | U | | <60 | U | | <160 | U | | <82 | U | | <71 | U | | <110 | U | | <110 | U | | <49 | U | | <62 | U | | <490 | U | |
| | | VMP-25-21-013112 | 1/31/2012 | 20000 | | | <29 | U | | <24 | U | | <21 | U | | <58 | U | | <29 | U | | <25 | U | | <40 | U | | <40 | U | | <17 | U | | <22 | U | | <170 | U | |
| | | VMP-25-21-013112-DUP | 2/1/2012 | 22000 | | | <27 | U | | <22 | U | | <20 | U | | <54 | U | | <27 | U | | <23 | U | | <37 | U | | <37 | U | | <16 | U | | <20 | U | | <160 | U | |
| | | VMP-25-21-042512 | 4/25/2012 | 21000 | | | <18 | U | | <15 | U | | <13 | U | | <37 | U | | <18 | U | | <16 | U | | <26 | U | | <25 | U | | <11 | U | | <14 | U | | <110 | U | |
| | | VMP-25-21-072612 | 7/26/2012 | 22000 | | | <31 | U | | <26 | U | | <23 | U | | <62 | U | | <31 | U | | <27 | U | | <43 | U | | <43 | U | | <18 | U | | 2.4 | J | | <190 | U | |
| | | VMP-25-21-102612 | 10/26/2012 | 20000 | | | <180 | U | | <150 | U | | <140 | U | | <370 | U | | <180 | U | | <160 | U | | <260 | U | | <260 | U | | <110 | U | | <140 | U | | <1100 | U | UJ |
| | | VMP-25-21-030613 | 3/6/2013 | 20000 | | | <47 | U | | <39 | U | | <35 | U | | <94 | U | | <47 | U | | <41 | U | | <66 | U | UJ | <65 | U | | <28 | U | | 4.2 | J | | <280 | U | |
| | 31 ft | VMP-25-31-030613 | 3/6/2013 | 23000 | | | <62 | U | | <52 | U | | 7.4 | J | | 5.6 | J | | <62 | U | | <54 | U | | <87 | U | | 10 | J | | <37 | U | | 12 | J | | <380 | U | |

SEE LAST PAGE OF TABLE FOR NOTES

**TABLE 6**
**CUMULATIVE SUMMARY OF SOIL VAPOR ANALYTICAL DETECTIONS AND SCREENING RESULTS: PUBLIC WORKS YARD AND WRR - VOCS**

| Location | Depth | Sample ID | Sample Date | Isopentane | | | Isopropylbenzene (Cumene) | | | 4-Methyl-2-pentanone (Methyl | | | Methyl tert-Butyl Ether (MBTE) | | | 2-Propanol | | | n-Propylbenzene | | | Styrene | | | 1,1,2,2-Tetrachloroethane | | | Tetrachloroethene | | | Tetrahydrofuran | | | Toluene | | | 1,2,4-Trichlorobenzene | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | | | | 3500 | | | | | | 23000 | | | | | | | | | 8500 | | | | | | 4 | | | | | | 40000 | | | 50 | | |
| | | | | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals |
| VMP-29 | 10 ft | VMP-29-10-073012 | 7/30/2012 | <0.12 | U | | 0.025 | J | | 0.082 | | | <0.038 | U | | 0.065 | J | | <0.052 | U | | <0.045 | U | | <0.073 | U | | <0.072 | U | | 8.6 | | | 0.055 | | | <0.31 | U | |
| | | VMP-29-10-100812 | 10/8/2012 | <0.22 | U | | <0.092 | U | | 0.059 | J | | <0.068 | U | | 0.047 | J | | <0.092 | U | | <0.08 | U | | <0.13 | U | | <0.13 | U | | 14 | | | 0.016 | J | | <0.56 | U | |
| | | VMP-29-10-020613 | 2/6/2013 | 0.0031 | J | | <0.0069 | U | | 0.0028 | J | | <0.0051 | U | | 0.044 | | | <0.0069 | U | | <0.006 | U | | <0.0097 | U | | <0.0096 | J | U | 0.29 | | | <0.0053 | J | U | <0.042 | U | |
| | 20 ft | VMP-29-20-073012 | 7/30/2012 | <1.5 | U | | <0.62 | U | | <0.51 | U | | <0.45 | U | | 0.95 | J | | <0.62 | U | | <0.53 | U | | <0.86 | U | | <0.85 | U | | 190 | | | 0.045 | J | | <3.7 | U | |
| | | VMP-29-20-073012-Dup | 7/30/2012 | <1.4 | U | | <0.58 | U | | <0.48 | U | | <0.42 | U | | 0.86 | J | | <0.58 | U | | <0.5 | U | | <0.8 | U | | <0.79 | U | | 170 | | | 0.041 | J | | <3.5 | U | |
| | | VMP-29-20-100812 | 10/8/2012 | <0.22 | U | | <0.092 | U | | 0.093 | | | <0.068 | U | | 0.097 | J | | <0.092 | U | | <0.08 | U | | <0.13 | U | | <0.13 | U | | 20 | | | 0.023 | J | | <0.56 | U | |
| | | VMP-29-20-020613 | 2/6/2013 | 0.0081 | J | | <0.0068 | J | U | 0.01 | | | <0.005 | U | | 0.04 | | | <0.0068 | U | | <0.0059 | U | | <0.0095 | U | | <0.0094 | J | U | 0.2 | | | 0.0019 | J | | <0.041 | U | |
| | 30 ft | VMP-29-30-073012 | 7/30/2012 | 0.09 | J | | 0.031 | J | | 0.091 | | | <0.074 | U | | 0.78 | | | <0.1 | U | | <0.088 | U | | <0.14 | U | | <0.14 | U | | 48 | | | 0.06 | J | | <0.61 | U | |
| | | VMP-29-30-100812 | 10/8/2012 | 0.46 | J | | <0.45 | U | | <0.38 | U | | <0.33 | U | | 0.55 | J | | <0.45 | U | | 0.12 | J | | <0.64 | U | | <0.63 | U | | 47 | | | 0.55 | | | <2.7 | U | |
| | | VMP-29-30-020613 | 2/6/2013 | 0.0046 | J | | <0.0071 | J | U | 0.012 | | | <0.0052 | U | | 0.029 | | | <0.0071 | U | | <0.0062 | U | | <0.0099 | U | | <0.0098 | J | U | 0.78 | | | <0.0054 | J | U | <0.043 | U | |
| VMP-30 | 10 ft | VMP-30-10-073012 | 7/30/2012 | <0.44 | U | | <0.18 | U | | <0.15 | U | | <0.13 | U | | 0.3 | J | | <0.18 | U | | <0.16 | U | | <0.26 | U | | <0.25 | U | | 69 | | | 0.027 | J | | <1.1 | U | |
| | | VMP-30-10-100812 | 10/8/2012 | 0.014 | J | | 0.0078 | | | 0.051 | | | <0.0051 | U | | 0.019 | | | <0.0069 | U | | <0.006 | U | | <0.0097 | U | | 0.0041 | J | | 1.6 | | | 0.0096 | | | <0.042 | U | |
| | | VMP-30-10-020613 | 2/6/2013 | 0.0077 | J | | <0.0065 | U | | 0.0023 | J | | <0.0048 | U | | 0.0028 | J | | <0.0065 | U | | <0.0056 | U | | <0.0091 | U | | <0.009 | J | U | 0.09 | | | 0.0016 | J | | <0.039 | U | |
| | 20 ft | VMP-30-20-073012 | 7/30/2012 | <1.9 | U | | <0.78 | U | | <0.65 | U | | <0.57 | U | | 1.3 | J | | <0.78 | U | | <0.68 | U | | <1.1 | U | | <1.1 | U | | 300 | | | 0.033 | J | | <4.7 | U | |
| | | VMP-30-20-100812 | 10/8/2012 | 0.18 | J | | <0.28 | U | | <0.24 | U | | <0.21 | U | | 0.26 | J | | <0.28 | U | | 0.12 | J | | <0.4 | U | | <0.39 | U | | 29 | | | 0.39 | | | <1.7 | U | |
| | | VMP-30-20-020613 | 2/6/2013 | 0.0073 | J | | <0.0065 | J | U | 0.0034 | J | | <0.0048 | U | | 0.011 | J | | <0.0065 | J | U | <0.0056 | U | | <0.0091 | U | | <0.009 | J | U | 0.21 | | | <0.005 | J | U | <0.039 | J | U |
| | 30 ft | VMP-30-30-073012 | 7/30/2012 | 0.31 | J | | <0.8 | U | | <0.67 | U | | <0.59 | U | | 1.2 | J | | <0.8 | U | | <0.7 | U | | <1.1 | U | | <1.1 | U | | 330 | | | 0.035 | J | | <4.8 | U | |
| | | VMP-30-30-100812 | 10/8/2012 | 1 | J | | <0.59 | U | | <0.49 | U | | <0.43 | U | | 0.46 | J | | <0.59 | U | | 0.093 | J | | <0.83 | U | | <0.82 | U | | 67 | | | 0.49 | | | <3.6 | U | |
| | | VMP-30-30-020613 | 2/6/2013 | <0.052 | U | | <0.022 | U | | <0.018 | U | | <0.016 | U | | 0.037 | J | | <0.022 | U | | <0.019 | U | | <0.03 | U | | <0.03 | U | | 2.6 | | | <0.016 | U | | <0.13 | J | U |
| VMP-41 | 10 ft | VMP-41-10-072712 | 7/27/2012 | 0.12 | | | 0.04 | | | 0.16 | | | <0.0044 | U | | 0.055 | | | 0.00096 | J | | 0.0024 | J | | <0.0083 | U | | <0.0082 | U | | 0.0016 | J | | 0.071 | | | <0.036 | U | |
| | | VMP-41-10-100912 | 10/9/2012 | <0.017 | U | | 0.021 | | | 0.1 | | | <0.0053 | U | | 0.035 | | | <0.0073 | U | | <0.0063 | U | | <0.01 | U | | 0.012 | | | <0.0044 | U | | 0.022 | | | <0.044 | U | |
| | | VMP-41-10-012913 | 1/29/2013 | <0.017 | U | | <0.0073 | U | | <0.0061 | U | | <0.0053 | U | | 0.01 | J | | <0.0073 | U | | <0.0063 | U | | <0.01 | U | | <0.01 | U | | <0.0044 | U | | <0.0056 | J | U | <0.044 | U | |
| | 20 ft | VMP-41-20-072712 | 7/27/2012 | <0.011 | U | | 0.025 | | | 0.089 | | | <0.0034 | U | | 0.03 | | | 0.00039 | J | | 0.0014 | J | | <0.0064 | U | | <0.0063 | U | | <0.0028 | U | | 0.038 | | | <0.028 | U | |
| | | VMP-41-20-072712-Dup | 7/27/2012 | <0.011 | U | | 0.025 | | | 0.09 | | | <0.0034 | U | | 0.029 | | | 0.00044 | J | | 0.0018 | J | | <0.0066 | U | | <0.0065 | U | | <0.0028 | U | | 0.039 | | | <0.028 | U | |
| | | VMP-41-20-100912 | 10/9/2012 | <0.017 | U | | 0.019 | | | 0.079 | | | <0.0052 | U | | 0.02 | | | <0.0071 | U | | 0.00092 | J | | <0.0099 | U | | 0.0091 | J | | <0.0043 | U | | 0.015 | | | <0.043 | U | |
| | | VMP-41-20-100912-Dup | 10/9/2012 | <0.017 | U | | 0.021 | | | 0.084 | | | <0.0053 | U | | 0.019 | | | <0.0073 | J | U | 0.0013 | J | | <0.01 | U | | 0.0073 | J | | <0.0044 | U | | 0.016 | | | <0.044 | U | |
| | | VMP-41-20-012913 | 1/29/2013 | 0.0076 | J | | <0.0074 | U | | <0.0062 | U | | <0.0055 | U | | 0.01 | J | | <0.0074 | U | | <0.0064 | U | | <0.01 | U | | 0.0016 | J | | <0.0045 | U | | <0.0057 | J | U | <0.045 | J | U |
| | 30 ft | VMP-41-30-072712 | 7/27/2012 | 0.039 | | | 0.011 | | | 0.1 | | | <0.0034 | U | | 0.036 | | | 0.00072 | J | | 0.0021 | J | | <0.0066 | U | | <0.0065 | U | | 0.00073 | J | | 0.03 | | | <0.028 | U | |
| | | VMP-41-30-100912 | 10/9/2012 | <0.018 | U | | 0.013 | | | 0.041 | | | <0.0056 | U | | 0.0093 | J | | <0.0076 | U | | <0.0066 | U | | <0.011 | U | | 0.0046 | J | | <0.0046 | U | | 0.0098 | | | <0.046 | U | |
| | | VMP-41-30-012913 | 1/29/2013 | 0.0056 | J | | <0.0069 | U | | <0.0058 | U | | <0.0051 | U | | 0.013 | J | | <0.0069 | U | | <0.006 | U | | <0.0097 | U | | 0.0027 | J | | <0.0042 | U | | 0.0013 | J | | <0.042 | U | |
| VMP-55 | 20 ft | VMP-55-20-021513 | 2/15/2013 | 4500 | | | <17 | U | | <56 | U | | <12 | U | | <34 | U | | <17 | U | | <15 | U | | <24 | U | | <23 | U | | <10 | U | | <13 | U | | <100 | U | |

SEE LAST PAGE OF TABLE FOR NOTES

**TABLE 6**
**CUMULATIVE SUMMARY OF SOIL VAPOR ANALYTICAL DETECTIONS AND SCREENING RESULTS: PUBLIC WORKS YARD AND WRR - VOCS**

| Location | Depth | Sample ID | Sample Date | 1,1,1-Trichloroethane (Methyl | | | 1,1,2-Trichloroethane | | | Trichloroethene | | | Trichlorofluoromethane | | | 1,2,4-Trimethylbenzene | | | 1,3,5-Trimethylbenzene | | | 2,2,4-Trimethylpentane | | | Vinyl chloride | | | m,p-Xylene | | | o-Xylenes | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | 41000 | | | 170000 | | | 12 | | | 5600 | | | | | | | | | | | | 4.8 | | | 820 | | | 790 | | |
| | | | | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals |
| VMP-10 | 5 ft | VMP-10-5-090710 | 9/7/2010 | <0.0072 | U | | <0.0072 | U | | <0.0071 | U | | 0.001 | J | | 0.007 | | | 0.0023 | J | | 0.093 | | | <0.0034 | U | | 0.014 | | | 0.0065 | | |
| | | VMP-10-5-111810 | 11/17/2010 | 0.00085 | J | | <0.0066 | U | | <0.0065 | J | U | 0.00082 | J | | <0.0059 | U | | <0.0059 | U | | 0.025 | | | <0.0031 | U | | <0.0052 | J | U | <0.0052 | U | |
| | | VMP-10-5-021011 | 2/10/2011 | <0.0065 | U | | <0.0065 | U | | <0.0064 | U | | <0.0067 | U | | 0.0013 | J | | <0.0058 | U | | 0.2 | | | <0.003 | U | | 0.0046 | J | | 0.0011 | J | |
| | | VMP-10-5-040511 | 4/5/2011 | <0.006 | U | | <0.006 | U | | <0.0059 | J | U | 0.00085 | J | | 0.0054 | | | <0.0054 | J | U | 0.011 | | | <0.0028 | U | | 0.0058 | | | <0.0048 | J | U |
| | | VMP-10-5-07/2911 | 7/29/2011 | <0.0073 | U | | <0.0073 | U | | <0.0072 | U | | <0.0075 | U | | <0.0066 | J | U | <0.0066 | U | | 0.003 | J | | <0.0034 | U | | 0.0033 | J | | 0.00096 | J | |
| | | VMP-10-5-110411 | 11/4/2011 | <0.0038 | U | | <0.0038 | U | | <0.0037 | U | | 0.00084 | J | J | <0.0034 | J | U | <0.0034 | J | U | <0.0032 | U | | <0.0018 | U | | 0.0027 | J | | 0.00085 | J | |
| | | VMP-10-5-012512 | 1/26/2012 | <0.0048 | U | | <0.0048 | U | | 0.0012 | J | | <0.0049 | U | | <0.0043 | U | | <0.0043 | U | | 0.0031 | J | | <0.0022 | U | | 0.00089 | J | | <0.0038 | U | |
| | | VMP-10-5-041212 | 4/12/2012 | <0.0051 | U | | <0.0051 | U | | <0.005 | U | | 0.0013 | J | | <0.0046 | U | | <0.0046 | U | | 0.034 | | | <0.0024 | U | | <0.0041 | J | U | <0.0041 | U | |
| | | VMP-10-5-071312 | 7/13/2012 | <0.0053 | U | | <0.0053 | U | | <0.0052 | U | | 0.0013 | J | | <0.0047 | J | U | <0.0047 | U | | <0.0045 | J | U | <0.0025 | U | | <0.0042 | J | U | <0.0042 | U | |
| | | VMP-10-5-101612 | 10/16/2012 | <0.0083 | U | | <0.0083 | U | | <0.0081 | U | | <0.0085 | U | | <0.0074 | U | | <0.0074 | U | | 0.038 | | | <0.0039 | U | | <0.0066 | U | | <0.0066 | U | |
| | | VMP-10-5-012913 | 1/29/2013 | <0.0077 | U | | <0.0077 | U | | <0.0076 | U | | 0.0021 | J | | <0.0069 | U | | <0.0069 | U | | 0.007 | | | <0.0036 | U | | <0.0061 | U | | <0.0061 | U | |
| | | VMP-10-5-012913-DUP | 1/29/2013 | <0.0085 | U | | <0.0085 | U | | <0.0084 | U | | 0.0015 | J | | <0.0076 | U | | <0.0076 | U | | 0.0082 | | | <0.004 | U | | <0.0068 | U | | <0.0068 | U | |
| | 10 ft | VMP-10-10-090710 | 9/7/2010 | <0.0072 | U | | <0.0072 | U | | <0.0071 | U | | 0.00097 | J | | <0.0065 | U | | <0.0065 | U | | 0.048 | | | <0.0034 | U | | 0.0011 | J | | <0.0057 | U | |
| | | VMP-10-10-111810 | 11/17/2010 | 0.0013 | J | | <0.007 | U | | <0.0069 | J | U | 0.00098 | J | | <0.0063 | U | | <0.0063 | U | | 0.026 | | | <0.0033 | U | | <0.0056 | J | U | <0.0056 | U | |
| | | VMP-10-10-021111 | 2/11/2011 | <0.0055 | U | | <0.0055 | U | | 0.002 | J | | 0.00063 | J | | <0.005 | J | U | <0.005 | U | | 0.018 | | | <0.0026 | U | | 0.0034 | J | | 0.0011 | J | |
| | | VMP-10-10-040611 | 4/6/2011 | <0.0072 | U | | <0.0072 | U | | <0.0071 | J | U | 0.0012 | J | | <0.0065 | J | U | <0.0065 | U | | 0.0088 | | | <0.0034 | U | | <0.0057 | J | U | <0.0057 | U | |
| | | VMP-10-10-072911 | 7/29/2011 | <0.0075 | U | | <0.0075 | U | | <0.0074 | U | | <0.0078 | U | | 0.0047 | J | | <0.0068 | J | U | 0.0094 | | | <0.0035 | U | | 0.0072 | | | 0.0018 | J | |
| | | VMP-10-10-110411 | 11/4/2011 | <0.0049 | U | | <0.0049 | U | | <0.0048 | J | U | 0.00083 | J | | 0.0019 | J | | 0.00059 | J | | 0.001 | J | | <0.0023 | U | | 0.0029 | J | | 0.00099 | J | |
| | | VMP-10-10-110411-DUP | 11/4/2011 | <0.0049 | U | | <0.0049 | U | | <0.0048 | J | U | 0.00093 | J | | 0.0015 | J | | 0.00047 | J | | 0.00076 | J | | <0.0023 | U | | 0.0025 | J | | 0.0011 | J | |
| | | VMP-10-10-012512 | 1/26/2012 | <0.0048 | U | | <0.0048 | U | | 0.0014 | J | | <0.0049 | U | | <0.0043 | U | | <0.0043 | U | | <0.0041 | U | | <0.0022 | U | | 0.0015 | J | | 0.00071 | J | |
| | | VMP-10-10-012512-DUP | 1/26/2012 | <0.005 | U | | <0.005 | U | | 0.0014 | J | | <0.0051 | U | | 0.0012 | J | | <0.0045 | U | | 0.008 | | | <0.0023 | U | | 0.0016 | J | | 0.00087 | J | |
| | | VMP-10-10-041112 | 4/11/2012 | <0.0052 | U | | <0.0052 | U | | <0.0051 | U | | <0.0054 | U | | <0.0047 | J | U | <0.0047 | U | | 0.057 | | | <0.0024 | U | | 0.0048 | | | 0.0022 | J | |
| | | VMP-10-10-071312 | 7/13/2012 | <0.0051 | U | | <0.0051 | U | | <0.005 | U | | <0.0053 | U | | <0.0046 | J | U | <0.0046 | U | | <0.0044 | J | U | <0.0024 | U | | <0.0041 | J | U | <0.0041 | J | U |
| | | VMP-10-10-101612 | 10/16/2012 | <0.0086 | U | | <0.0086 | U | | <0.0085 | U | | <0.0089 | U | | <0.0078 | U | | <0.0078 | U | | 0.021 | | | <0.004 | U | | 0.0068 | | | <0.0069 | U | |
| | | VMP-10-10-012913 | 1/29/2013 | <0.0069 | U | | <0.0069 | U | | <0.0068 | U | | 0.0012 | J | | <0.0062 | U | | <0.0062 | U | | 0.0064 | | | <0.0032 | U | | <0.0055 | U | | <0.0055 | U | |
| | 20 ft | VMP-10-20-090710 | 9/7/2010 | <0.0075 | U | | <0.0075 | U | | <0.0074 | U | | 0.0013 | J | | 0.0016 | J | | <0.0068 | U | | 0.027 | | J | <0.0035 | U | | 0.0043 | J | | 0.0015 | J | |
| | | VMP-10-20-090710-DUP | 9/7/2010 | <0.007 | U | | <0.007 | U | | <0.0069 | U | | 0.0018 | J | | 0.0013 | J | | <0.0063 | U | | 0.011 | | J | <0.0033 | U | | 0.0037 | J | | 0.0013 | J | |
| | | VMP-10-20-111810 | 11/17/2010 | 0.0024 | J | | <0.013 | U | | 0.0042 | J | | <0.014 | U | | <0.012 | U | | <0.012 | U | | 0.01 | J | J | <0.0062 | U | | <0.011 | U | | <0.011 | U | |
| | | VMP-10-20-111810-Dup | 11/17/2010 | 0.0011 | J | | <0.0067 | U | | 0.002 | J | | 0.00085 | J | | <0.0061 | U | | <0.0061 | U | | 0.03 | | J | <0.0032 | U | | <0.0054 | J | U | <0.0054 | U | |
| | | VMP-10-20-021111 | 2/11/2011 | <0.0066 | U | | <0.0066 | U | | 0.0033 | J | | <0.0068 | U | | <0.006 | U | | <0.006 | U | | 0.014 | | | <0.0031 | U | | 0.00059 | J | | <0.0053 | U | |
| | | VMP-10-20-040611 | 4/6/2011 | <0.008 | U | | <0.008 | U | | <0.0079 | J | U | 0.0014 | J | | <0.0072 | J | U | <0.0072 | U | | 0.031 | | | <0.0038 | U | | <0.0068 | | U | 0.0016 | J | |
| | | VMP-10-20-072911 | 7/29/2011 | <0.0074 | U | | <0.0074 | U | | <0.0073 | U | | <0.0077 | U | | 0.005 | J | | <0.0067 | J | U | 0.0054 | J | | <0.0035 | U | | 0.0053 | J | | 0.0018 | J | |
| | | VMP-10-20-110411 | 11/4/2011 | <0.0049 | U | | <0.0049 | U | | <0.0048 | U | | 0.001 | J | | <0.0044 | U | | 0.00043 | J | | 0.0012 | J | | <0.0023 | U | | 0.0034 | J | | 0.0011 | J | |
| | | VMP-10-20-012612 | 1/26/2012 | <0.0046 | U | | <0.0046 | U | | 0.001 | J | | <0.0047 | U | | <0.0041 | U | | <0.0041 | U | | 0.015 | | | <0.0021 | U | | 0.0014 | J | | 0.00042 | J | |
| | | VMP-10-20-041212 | 4/12/2012 | <0.0051 | U | | <0.0051 | U | | <0.005 | U | | 0.0009 | J | | <0.0046 | U | | <0.0046 | U | | 0.064 | | | <0.0024 | U | | <0.0041 | J | U | <0.0041 | U | |
| | | VMP-10-20-071612 | 7/16/2012 | <0.0049 | U | | <0.0049 | U | | <0.0048 | U | | 0.0012 | J | | <0.0044 | J | U | <0.0044 | U | | <0.0042 | J | U | <0.0023 | U | | <0.0039 | J | U | <0.0039 | U | |
| | | VMP-10-20-101612 | 10/16/2012 | <0.0087 | U | | <0.0087 | U | | <0.0086 | U | | <0.009 | U | | <0.0078 | J | U | 0.0026 | J | | 0.0059 | J | | <0.0041 | U | | <0.0069 | U | | <0.0069 | U | |
| | | VMP-10-20-012913 | 1/29/2013 | <0.0075 | U | | <0.0075 | U | | <0.0074 | U | | 0.0017 | J | | <0.0068 | U | | <0.0068 | U | | 0.0068 | | | <0.0035 | U | | <0.006 | U | | <0.006 | U | |
| | 30 ft | VMP-10-30-041212 | 4/12/2012 | <0.0053 | U | | <0.0053 | U | | <0.0053 | U | | 0.0018 | J | | <0.0048 | U | | <0.0048 | U | | 0.12 | | | <0.0025 | U | | 0.0038 | J | | 0.0013 | J | |
| | | VMP-10-30-071612 | 7/16/2012 | <0.0047 | U | | <0.0047 | U | | <0.0046 | U | | 0.0013 | J | | <0.0042 | J | U | <0.0042 | U | | <0.004 | J | U | <0.0022 | U | | <0.0038 | J | U | <0.0038 | U | |
| | | VMP-10-30-101612 | 10/16/2012 | <0.0082 | U | | <0.0082 | U | | <0.0081 | U | | <0.0084 | U | | <0.0074 | U | | <0.0074 | U | | 0.028 | | | <0.0038 | U | | <0.0065 | U | | <0.0065 | U | |
| | | VMP-10-30-012913 | 1/29/2013 | <0.0083 | U | | <0.0083 | U | | <0.0081 | U | | 0.0018 | J | | <0.0074 | U | | <0.0074 | U | | 0.0054 | J | | <0.0039 | U | | <0.0066 | U | | <0.0066 | U | |
| VMP-11 | 5 ft | VMP-11-5-090710 | 9/7/2010 | <0.0067 | U | | <0.0067 | U | | <0.0066 | U | | 0.0012 | J | | <0.0061 | U | | <0.0061 | U | | 0.041 | | | <0.0032 | U | | 0.0015 | J | | <0.0054 | U | |
| | | VMP-11-5-112210 | 11/22/2010 | <0.007 | U | | <0.007 | U | | <0.0069 | U | | <0.0072 | U | | <0.0063 | U | | <0.0063 | U | | 0.0019 | J | | <0.0033 | U | | <0.0056 | J | U | <0.0056 | U | |
| | | VMP-11-5-021511 | 2/15/2011 | <0.0062 | U | | <0.0062 | U | | 0.0024 | J | | 0.001 | J | | <0.0056 | J | U | <0.0056 | U | | 0.065 | | | <0.0029 | U | | 0.0089 | | | 0.0029 | J | |
| | | VMP-11-5-040611 | 4/6/2011 | <0.059 | U | | <0.059 | U | | <0.058 | U | | <0.061 | U | | <0.053 | U | | <0.053 | U | | 0.11 | | | <0.028 | U | | <0.047 | U | | <0.047 | U | |
| | | VMP-11-5-080711 | 8/7/2011 | <0.081 | U | | <0.081 | U | | <0.08 | U | | <0.083 | U | | <0.073 | U | | <0.073 | U | | <0.069 | U | | <0.038 | U | | 0.012 | J | | <0.064 | U | |
| | | VMP-11-5-111111 | 11/11/2011 | <0.016 | U | | <0.016 | U | | <0.016 | U | | <0.016 | U | | <0.014 | U | | <0.014 | U | | 0.94 | | | <0.0075 | U | | 0.0036 | J | | <0.013 | U | |
| | | VMP-11-5-012612 | 1/26/2012 | <0.0048 | U | | <0.0048 | U | | 0.001 | J | | <0.0049 | U | | <0.0043 | U | | <0.0043 | U | | <0.0041 | U | | <0.0022 | U | | 0.0031 | J | | 0.0007 | J | |
| | | VMP-11-5-041912 | 4/19/2012 | <0.0053 | J | U | <0.0053 | U | | <0.0053 | U | | 0.0017 | J | | 0.0023 | J | | 0.0012 | J | | 0.21 | | | <0.0025 | U | | 0.012 | | | 0.0033 | J | |
| | | VMP-11-5-071912 | 7/16/2012 | <0.0069 | U | | <0.0069 | U | | <0.0068 | J | U | 0.0015 | J | | <0.0062 | U | | <0.0062 | U | | 0.0061 | | | <0.0032 | U | | <0.0055 | J | U | <0.0055 | U | |
| | | VMP-11-5-101612 | 10/16/2012 | <0.0077 | U | | <0.0077 | U | | <0.0076 | U | | <0.008 | U | | <0.007 | U | | <0.007 | U | | 0.018 | | | <0.0036 | U | | <0.0061 | U | | <0.0061 | U | |
| | | VMP-11-5-012913 | 1/29/2013 | <0.39 | U | | <0.39 | U | | <0.39 | U | | <0.4 | U | | <0.35 | U | | <0.35 | U | | <0.34 | U | | <0.18 | U | | <0.31 | U | | <0.31 | U | |
| | 8 ft | VMP-11-8-090810 | 9/8/2010 | <0.007 | U | | <0.007 | U | | <0.0069 | U | | 0.002 | J | | <0.0063 | U | | <0.0063 | U | | 0.01 | | | <0.0033 | U | | <0.0056 | J | U | <0.0056 | U | |
| | | VMP-11-8-112210 | 11/22/2010 | <0.007 | U | | <0.007 | U | | <0.0069 | U | | <0.0072 | U | | <0.0063 | U | | <0.0063 | U | | 0.0024 | J | | <0.0033 | U | | <0.0056 | J | U | <0.0056 | U | |
| | | VMP-11-8-021111 | 2/11/2011 | <0.0068 | U | | <0.0068 | U | | 0.0034 | J | | <0.007 | U | | <0.0061 | U | | <0.0061 | U | | 0.012 | | | <0.0032 | U | | <0.0054 | U | | <0.0054 | U | |
| | | VMP-11-8-021111-DUP | 2/11/2011 | <0.0064 | U | | <0.0064 | U | | 0.0031 | J | | 0.001 | J | | <0.0058 | U | | <0.0058 | U | | 0.0085 | | | <0.003 | U | | <0.0051 | U | | <0.0051 | U | |
| | | VMP-11-8-040611 | 4/6/2011 | <0.03 | U | | <0.03 | U | | <0.03 | U | | <0.031 | U | | <0.027 | U | | <0.027 | U | | 0.062 | | | <0.014 | U | | <0.024 | U | | <0.024 | U | |
| | | VMP-11-8-040611-DUP | 4/6/2011 | <0.026 | U | | <0.026 | U | | 0.0028 | J | | <0.027 | U | | <0.024 | U | | <0.024 | U | | 0.048 | | | <0.012 | U | | <0.021 | U | | <0.021 | U | |
| | | VMP-11-8-080711 | 8/7/2011 | <0.081 | U | | <0.081 | U | | <0.08 | U | | <0.083 | U | | <0.073 | U | | <0.073 | U | | <0.069 | U | | <0.038 | U | | 0.01 | J | | <0.064 | U | |
| | | VMP-11-8-111411 | 11/14/2011 | <0.0048 | U | | <0.0048 | U | | 0.0015 | J | | <0.0049 | U | | 0.0012 | J | | <0.0043 | U | | 0.031 | | | <0.0022 | U | | 0.003 | J | | 0.0007 | J | |
| | | VMP-11-8-012612 | 1/26/2012 | <0.0047 | U | | <0.0047 | U | | 0.00099 | J | | <0.0048 | U | | <0.0042 | U | | <0.0042 | U | | <0.004 | U | | <0.0022 | U | | 0.001 | J | | <0.0037 | U | |
| | | VMP-11-8-041912 | 4/19/2012 | <0.0053 | J | U | <0.0053 | U | | <0.0053 | U | | 0.0016 | J | | <0.0048 | U | | <0.0048 | U | | 0.01 | | | <0.0025 | U | | 0.0075 | | | 0.0019 | J | |
| | | VMP-11-8-072012 | 7/20/2012 | <0.0053 | U | | <0.0053 | U | | <0.0053 | U | | 0.0013 | J | | <0.0048 | U | | <0.0048 | U | | <0.0046 | U | | <0.0025 | U | | <0.0042 | U | | <0.0042 | U | |
| | | VMP-11-8-101612 | 10/16/2012 | <0.0078 | U | | <0.0078 | U | | <0.0077 | U | | <0.008 | U | | <0.007 | U | | <0.007 | U | | 0.0019 | J | | <0.0036 | U | | <0.0062 | J | U | <0.0062 | U | |
| | | VMP-11-8-101612-Dup | 10/16/2012 | <0.0079 | U | | <0.0079 | U | | <0.0078 | U | | <0.0081 | U | | <0.0071 | U | | <0.0071 | U | | 0.0019 | J | | <0.0037 | U | | <0.0063 | J | U | <0.0063 | U | |
| | | VMP-11-8-012913 | 1/29/2013 | <0.054 | U | | <0.054 | U | | <0.053 | U | | <0.055 | U | | <0.048 | U | | <0.048 | U | | <0.046 | U | | <0.025 | U | | <0.043 | U | | <0.043 | U | |
| | 29 ft | VMP-11-29-090810 | 9/8/2010 | <0.18 | U | | <0.18 | U | | <0.17 | U | | <0.18 | U | | 0.17 | | | 0.088 | J | | 1.1 | | | <0.082 | U | | 0.1 | J | | 0.072 | J | |
| | | VMP-11-29-112210 | 11/22/2010 | <2.5 | U | | <2.5 | U | | <2.5 | U | | <2.6 | U | | <2.3 | U | | <2.3 | U | | 1.8 | J | | <1.2 | U | | <2 | U | | <2 | U | |
| | | VMP-11-29-112210-Dup | 11/22/2010 | <1.7 | U | | <1.7 | U | | <1.7 | U | | <1.8 | U | | <1.6 | U | | <1.6 | U | | 1.8 | | | <0.82 | U | | <1.4 | U | | <1.4 | U | |
| | | VMP-11-29-021411 | 2/14/2011 | <0.0068 | U | | <0.0068 | U | | 0.0028 | J | | <0.007 | U | | <0.0061 | J | U | <0.0061 | U | | 0.19 | | | <0.0032 | U | | 0.0043 | J | | 0.0016 | J | |
| | | VMP-11-29-040611 | 4/6/2011 | <0.052 | U | | <0.052 | U | | <0.051 | U | | <0.053 | U | | <0.046 | U | | <0.046 | U | | 0.096 | | | <0.024 | U | | <0.041 | U | | <0.041 | U | |
| | | VMP-11-29-082511 | 8/25/2011 | <0.0075 | U | | <0.0075 | U | | <0.0074 | U | | <0.0078 | U | | 0.0023 | J | | <0.0068 | U | | 0.002 | J | | <0.0035 | U | | 0.0037 | J | | 0.0011 | J | |
| | | VMP-11-29-082511-Dup | 8/25/2011 | <0.0075 | U | | <0.0075 | U | | <0.0074 | U | | <0.0078 | U | | 0.0023 | J | | <0.0068 | U | | 0.004 | J | | <0.0035 | U | | 0.0033 | J | | 0.0011 | J | |
| | | VMP-11-29-111411 | 11/14/2011 | <0.0048 | U | | <0.0048 | U | | 0.0014 | J | | <0.0049 | U | | 0.00088 | J | | <0.0043 | U | | 0.005 | | | <0.0022 | U | | 0.0018 | J | | 0.00048 | J | |
| | | VMP-11-29-012612 | 1/26/2012 | <0.0046 | U | | <0.0046 | U | | 0.001 | J | | <0.0047 | U | | <0.0041 | U | | <0.0041 | U | | <0.0039 | U | | <0.0021 | U | | <0.0036 | U | | <0.0036 | U | |
| | | VMP-11-29-042712 | 4/27/2012 | <0.0048 | U | | <0.0048 | U | | <0.0047 | U | | 0.00099 | J | | 0.0011 | J | | <0.0043 | U | | 0.013 | | | <0.0022 | U | | 0.0046 | | | 0.0014 | J | |
| | | VMP-11-29-072012 | 7/23/2012 | <0.0048 | U | | <0.0048 | U | | <0.0047 | U | | 0.0013 | J | | 0.0056 | | | 0.0015 | J | | 0.028 | | | <0.0022 | U | | 0.023 | | | 0.0062 | | |
| | | VMP-11-29-101612 | 10/16/2012 | <0.0081 | U | | <0.0081 | U | | <0.008 | U | | 0.0015 | J | | <0.0073 | U | UJ | <0.0073 | U | | 0.0071 | | | <0.0038 | U | | 0.0012 | J | | <0.0064 | U | |
| | | VMP-11-29-012913 | 1/29/2013 | <0.0079 | U | | <0.0079 | U | | <0.0078 | U | | 0.0017 | J | | <0.0071 | U | | <0.0071 | U | | 0.0062 | J | | <0.0037 | U | | <0.0063 | U | | <0.0063 | U | |
| | 38 ft | VMP-11-38-042312 | 4/23/2012 | <0.36 | U | | <0.36 | U | | <0.35 | U | | <0.37 | U | | <0.32 | U | | <0.32 | U | | <0.3 | U | | <0.17 | U | | <0.28 | U | | <0.28 | U | |
| | | VMP-11-38-042312-Dup | 4/23/2012 | <1.2 | U | | <1.2 | U | | <1.2 | U | | <1.3 | U | | <1.1 | U | | <1.1 | U | | <1.1 | U | | <0.58 | U | | <0.99 | U | | <0.99 | U | |
| | | VMP-11-38-072312 | 7/23/2012 | <0.59 | U | | <0.59 | U | | <0.58 | U | | <0.61 | U | | <0.53 | U | | <0.53 | U | | <0.51 | U | | <0.28 | U | | <0.47 | U | | <0.47 | U | |
| | | VMP-11-38-101612 | 10/16/2012 | <0.0082 | U | | <0.0082 | U | | <0.0081 | U | | <0.0084 | U | | <0.0074 | U | | <0.0074 | U | | 0.023 | | | <0.0038 | U | | <0.0065 | U | | <0.0065 | U | |
| | | VMP-11-38-013013 | 1/30/2013 | <0.0075 | U | | <0.0075 | U | | <0.0074 | U | | 0.0016 | J | | <0.0068 | U | | <0.0068 | U | | 0.0048 | J | | <0.0035 | U | | <0.006 | U | | <0.006 | U | |

SEE LAST PAGE OF TABLE FOR NOTES

**TABLE 6**
**CUMULATIVE SUMMARY OF SOIL VAPOR ANALYTICAL DETECTIONS AND SCREENING RESULTS: PUBLIC WORKS YARD AND WRR - VOCS**

| Location | Depth | Sample ID | Sample Date | 1,1,1-Trichloroethane (Methyl | | | 1,1,2-Trichloroethane | | | Trichloroethene | | | Trichlorofluoromethane | | | 1,2,4-Trimethylbenzene | | | 1,3,5-Trimethylbenzene | | | 2,2,4-Trimethylpentane | | | Vinyl chloride | | | m,p-Xylene | | | o-Xylenes | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | 41000 | | | 170000 | | | 12 | | | 5600 | | | | | | | | | | | | 4.8 | | | 820 | | | 790 | | |
| | | | | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals |
| VMP-12 | 5 ft | VMP-12-5-090310 | 9/3/2010 | <7.3 | U | | <7.3 | U | | <7.2 | U | | <7.6 | U | | <6.6 | U | | <6.6 | U | | 1700 | | | <3.4 | U | | <5.8 | U | | <5.8 | U | |
| | | VMP-12-5-120310 | 12/3/2010 | <72 | U | | <72 | U | | <71 | U | | <75 | U | | <65 | U | | <65 | U | | 1700 | | | <34 | U | | <58 | U | | <58 | U | |
| | | VMP-12-5-021511 | 2/15/2011 | <3.3 | U | | <3.3 | U | | <3.3 | U | | <3.4 | U | | <3 | U | | <3 | U | | 610 | | | <1.6 | U | | <2.6 | U | | <2.6 | U | |
| | | VMP-12-5-041911 | 4/19/2011 | <24 | U | | <24 | U | | <24 | U | | <25 | U | | <22 | U | | <22 | U | | 1100 | | | <11 | U | | 7.9 | J | | <19 | U | |
| | | VMP-12-5-080411 | 8/4/2011 | <6.3 | U | | <6.3 | U | | <6.2 | U | | <6.5 | U | | <5.7 | U | | <5.7 | U | | 700 | | | <3 | U | | <5 | U | | <5 | U | |
| | | VMP-12-5-111611 | 11/16/2011 | <0.0044 | U | | <0.0044 | U | | <0.0044 | U | | <0.0046 | U | | 0.0009 | J | | <0.004 | U | | 0.95 | | | <0.0021 | U | | 0.0018 | J | | 0.00046 | J | |
| | | VMP-12-5-012412 | 1/24/2012 | <0.05 | U | | <0.05 | U | | <0.049 | U | | <0.051 | U | | 0.011 | J | | <0.045 | U | | 2.9 | | | <0.023 | U | | 0.013 | J | | <0.04 | U | |
| | | VMP-12-5-041912 | 4/19/2012 | <0.005 | U | | <0.005 | U | | <0.0049 | U | | 0.0016 | J | | 0.0014 | J | | <0.0045 | U | | 0.4 | | | <0.0023 | U | | 0.0042 | | | <0.004 | U | |
| | | VMP-12-5-072612 | 7/26/2012 | <0.0053 | U | | <0.0053 | U | | <0.0052 | U | | 0.0012 | J | | 0.0017 | J | | 0.00084 | J | | 0.0065 | | | <0.0025 | U | | 0.0052 | | | 0.0018 | J | |
| | | VMP-12-5-072612-Dup | 7/26/2012 | <0.0048 | U | | <0.0048 | U | | <0.0048 | U | | 0.0018 | J | | <0.0044 | U | | <0.0044 | U | | 0.00079 | J | | <0.0023 | U | | 0.001 | J | | 0.00082 | J | |
| | | VMP-12-5-102412 | 10/24/2012 | <0.0082 | U | | <0.0082 | U | | <0.0081 | U | | 0.0015 | J | | 0.003 | J | | 0.0014 | J | | 0.0058 | J | | <0.0038 | U | | 0.012 | | | 0.0054 | J | |
| | | VMP-12-5-021813 | 2/18/2013 | <0.0073 | U | | <0.0073 | U | | <0.0072 | U | | 0.0014 | J | | 0.0021 | J | J | <0.0066 | U | | 0.11 | | | <0.0034 | U | | 0.0012 | J | | <0.0058 | U | |
| | 11.5 ft | VMP-12-11.5-090310 | 9/3/2010 | <9.4 | U | | <9.4 | U | | <9.3 | U | | <9.7 | U | | <8.5 | U | | <8.5 | U | | 1700 | | | <4.4 | U | | <7.5 | U | | <7.5 | U | |
| | | VMP-12-11.5-120310 | 12/3/2010 | <8.2 | U | | <8.2 | U | | <8 | U | | <8.4 | U | | <7.3 | U | | <7.3 | U | | 910 | | | <3.8 | U | | <6.5 | U | | <6.5 | U | |
| | | VMP-12-11.5-021511 | 2/15/2011 | <7.3 | U | | <7.3 | U | | <7.2 | U | | <7.5 | U | | <6.6 | U | | <6.6 | U | | 1300 | | | <3.4 | U | | <5.8 | U | | <5.8 | U | |
| | | VMP-12-11.5-021511-DUP | 2/15/2011 | <6.3 | U | | <6.3 | U | | <6.2 | U | | <6.5 | U | | <5.7 | U | | <5.7 | U | | 1100 | | | <3 | U | | <5 | U | | <5 | U | |
| | | VMP-12-11.5-041911 | 4/19/2011 | <22 | U | | <22 | U | | <22 | U | | <23 | U | | <20 | U | | <20 | U | | 1200 | | | <10 | U | | <18 | U | | <18 | U | |
| | | VMP-12-11.5-080411 | 8/4/2011 | <7.7 | U | | <7.7 | U | | <7.6 | U | | <7.9 | U | | <6.9 | U | | <6.9 | U | | 420 | | | <3.6 | U | | <6.1 | U | | <6.1 | U | |
| | | VMP-12-11.5-111611 | 11/16/2011 | <0.061 | U | | <0.061 | U | | <0.06 | U | | <0.063 | U | | <0.055 | U | | <0.055 | U | | 4.7 | | | <0.029 | U | | <0.049 | U | | <0.049 | U | |
| | | VMP-12-11.5-012412 | 1/24/2012 | <0.57 | U | | <0.57 | U | | <0.56 | U | | <0.59 | U | | <2.1 | U | | <0.52 | U | | 64 | | | <0.27 | U | | 0.13 | J | | <0.46 | U | |
| | | VMP-12-11.5-041912 | 4/19/2012 | <0.052 | U | | <0.052 | U | | <0.051 | U | | <0.054 | U | | <0.047 | U | | <0.047 | U | | 15 | | | <0.024 | U | | <0.041 | U | | <0.041 | U | |
| | | VMP-12-11.5-082012 | 8/20/2012 | <0.0083 | U | | <0.0083 | U | | <0.0081 | U | | 0.0022 | J | J | 0.0056 | J | | 0.0028 | J | | 0.012 | | | <0.0039 | U | | 0.0038 | J | | 0.0022 | J | |
| | | VMP-12-11.5-102612 | 10/26/2012 | <0.0079 | U | | <0.0079 | U | | <0.0078 | U | | <0.0081 | U | | 0.0017 | J | | <0.0071 | U | | 0.02 | | | <0.0037 | U | | 0.0022 | J | | <0.0063 | U | |
| | | VMP-12-11.5-021813 | 2/18/2013 | <0.0079 | U | | <0.0079 | U | | 0.0019 | J | | <0.0081 | U | | <0.0071 | U | | <0.0071 | U | | 0.0016 | J | | <0.0037 | U | | <0.0063 | U | | <0.0063 | U | |
| | 25 ft | VMP-12-25-090310 | 9/3/2010 | <12 | U | | <12 | U | | <12 | U | | <11 | U | | <11 | U | | <11 | U | | 1300 | | | <5.6 | U | | <9.6 | U | | <9.6 | U | |
| | | VMP-12-25-120310 | 12/3/2010 | <0.59 | U | | <0.59 | U | | <0.58 | U | | <0.61 | U | | <0.54 | U | | <0.54 | U | | 120 | | | <0.28 | U | | <0.47 | U | | <0.47 | U | |
| | | VMP-12-25-021511 | 2/15/2011 | <14 | U | | <14 | U | | <14 | U | | <15 | U | | <13 | U | | <13 | U | | 990 | | | <6.8 | U | | 5.8 | J | | <12 | U | |
| | | VMP-12-25-041911 | 4/19/2011 | <24 | U | | <24 | U | | <23 | U | | <24 | U | | <21 | U | | <21 | U | | 980 | | | <11 | U | | <19 | U | | <19 | U | |
| | | VMP-12-25-080411 | 8/4/2011 | <15 | U | | <15 | U | | <15 | U | | <15 | U | | <14 | U | | <14 | U | | 720 | | | <7 | U | | <12 | U | | <12 | U | |
| | | VMP-12-25-111611 | 11/16/2011 | <17 | U | | <17 | U | | <17 | U | | <18 | U | | <15 | U | | <15 | U | | 940 | | | <8 | U | | <14 | U | | <14 | U | |
| | | VMP-12-25-012412 | 1/24/2012 | <6.5 | U | | <6.5 | U | | <6.4 | U | | <6.7 | U | | <24 | U | | <5.9 | U | | 1200 | | J | <3.1 | U | | <5.2 | U | | <5.2 | U | |
| | | VMP-12-25-012412-DUP | 1/24/2012 | <48 | U | | <48 | U | | <47 | U | | <49 | U | | <170 | U | | <43 | U | | 1200 | | | <22 | U | | <38 | U | | <38 | U | |
| | | VMP-12-25-041912 | 4/19/2012 | <5 | U | | <5 | U | | <4.9 | U | | <5.1 | U | | <4.5 | U | | <4.5 | U | | 520 | | | <2.3 | U | | <4 | U | | <4 | U | |
| | | VMP-12-25-072712 | 7/27/2012 | <5.5 | U | | <5.5 | U | | <5.4 | U | | <5.6 | U | | <4.9 | U | | <4.9 | U | | 450 | | | <2.6 | U | | <4.4 | U | | <4.4 | U | |
| | | VMP-12-25-072712-Dup | 7/27/2012 | <5.5 | U | | <5.5 | U | | <5.4 | U | | <5.6 | U | | <4.9 | U | | <4.9 | U | | 540 | | | <2.6 | U | | <4.4 | U | | <4.4 | U | |
| | | VMP-12-25-102512 | 10/25/2012 | <2.4 | U | | <2.4 | U | | <2.3 | U | | <2.4 | U | | <2.1 | U | | <2.1 | U | | 140 | | | <1.1 | U | | <1.9 | U | | <1.9 | U | |
| | | VMP-12-25-021513 | 2/15/2013 | <4.4 | U | | <4.4 | U | | 2.1 | J | J | <4.5 | U | | <4 | U | | <4 | U | | 1200 | | J | <2 | U | | <3.5 | U | | <3.5 | U | |
| | 39 ft | VMP-12-39-041911 | 4/19/2011 | <23 | U | | <23 | U | | <23 | U | | <24 | U | | <21 | U | | <21 | U | | 1100 | | | <11 | U | | <18 | U | | <18 | U | |
| | | VMP-12-39-012412 | 1/24/2012 | <48 | U | | <48 | U | | <47 | U | | <49 | U | | <170 | U | | <43 | U | | 1200 | | | <22 | U | | <38 | U | | <38 | U | |
| | | VMP-12-39-041912 | 4/19/2012 | <24 | U | | <24 | U | | <24 | U | | <24 | U | | <22 | U | | <22 | U | | 680 | | | <11 | U | | 4 | J | | <19 | U | |
| | | VMP-12-39-072612 | 7/26/2012 | <11 | U | | <11 | U | | <11 | U | | <11 | U | | <9.9 | U | | <9.9 | U | | 1000 | | | <5.1 | U | | <8.7 | U | | <8.7 | U | |
| | | VMP-12-39-102412 | 10/24/2012 | <29 | U | | <29 | U | | <28 | U | | <30 | U | | <26 | U | | <26 | U | | 770 | | | <14 | U | | 10 | J | | 2.1 | J | |
| | | VMP-12-39-021513 | 2/15/2013 | <13 | U | | <13 | U | | 6.4 | J | | <14 | U | | 16 | | | <12 | U | | 3600 | | | <6.2 | U | | 21 | | | <10 | U | |
| VMP-13 | 5 ft | VMP-13-5-091310 | 9/13/2010 | <0.048 | U | | <0.048 | U | | <0.047 | U | | <0.049 | U | | <0.043 | U | | <0.043 | U | | 0.073 | | | <0.022 | U | | 0.0064 | J | | <0.038 | U | |
| | | VMP-13-5-120110 | 12/1/2010 | <0.0064 | U | | <0.0064 | U | | <0.0063 | J | U | 0.0015 | J | | 0.037 | | | 0.0091 | | | 0.13 | | | <0.003 | U | | 0.11 | | | 0.037 | | |
| | | VMP-13-5-021811 | 2/18/2011 | <0.0075 | U | | <0.0075 | U | | <0.0074 | U | | <0.0078 | U | | <0.0068 | U | | <0.0068 | U | | 0.0028 | J | | <0.0035 | U | | <0.006 | U | | <0.006 | U | |
| | | VMP-13-5-040511 | 4/5/2011 | <0.015 | U | | <0.015 | U | | 0.006 | J | | <0.016 | U | | <0.014 | U | | <0.014 | U | | 0.012 | J | | <0.007 | U | | <0.012 | U | | <0.012 | U | |
| | | VMP-13-5-080911 | 8/9/2011 | <0.016 | U | | <0.016 | U | | <0.016 | U | | <0.017 | U | | 0.0049 | J | | 0.0018 | J | | 2.9 | | J | <0.0076 | U | | 0.0073 | J | | 0.0018 | J | |
| | | VMP-13-5-080911-DUP | 8/9/2011 | <0.014 | U | | <0.014 | U | | <0.014 | U | | <0.015 | U | | 0.0028 | J | | <0.013 | U | | 1.8 | | J | <0.0067 | U | | 0.005 | J | | 0.0016 | J | |
| | | VMP-13-5-111411 | 11/14/2011 | <0.005 | U | | <0.005 | U | | 0.00096 | J | | <0.0052 | U | | 0.00072 | J | | <0.0045 | U | | 0.0044 | | | <0.0024 | U | | 0.0019 | J | | 0.00065 | J | |
| | | VMP-13-5-012712 | 1/27/2012 | <0.042 | U | | <0.042 | U | | <0.042 | U | | <0.044 | U | | <0.15 | U | | <0.038 | U | | 0.19 | | J | <0.02 | U | | <0.034 | U | | <0.034 | U | |
| | | VMP-13-5-042012 | 4/20/2012 | 0.00044 | J | | <0.0049 | U | | <0.0048 | U | | 0.0015 | J | | <0.0044 | U | | <0.0044 | U | | 0.0015 | J | | <0.0023 | U | | 0.0037 | J | | <0.0039 | U | |
| | | VMP-13-5-071912 | 7/19/2012 | <0.0051 | U | | <0.0051 | U | | <0.005 | U | | 0.0026 | J | J | 0.0071 | | | 0.002 | J | | 0.0041 | J | | <0.0024 | U | | 0.009 | | | 0.0046 | | |
| | | VMP-13-5-071912-Dup | 7/19/2012 | <0.0051 | U | | <0.0051 | U | | <0.005 | U | | 0.0024 | J | J | 0.0083 | | | 0.0022 | J | | 0.004 | J | | <0.0024 | U | | 0.0098 | | | 0.0047 | | |
| | | VMP-13-5-100912 | 10/9/2012 | <0.0079 | U | | <0.0079 | U | | <0.0078 | U | | 0.0015 | J | | <0.0071 | U | | <0.0071 | U | | 0.043 | | | <0.0037 | U | | <0.0063 | U | | <0.0063 | U | |
| | | VMP-13-5-012913 | 1/29/2013 | <0.0085 | U | | <0.0085 | U | | <0.0084 | U | | 0.0019 | J | | <0.0076 | U | | <0.0076 | U | | <0.0073 | U | | <0.004 | U | | <0.0068 | U | | <0.0068 | U | |
| | 10.5 ft | VMP-13-10.5-091310 | 9/13/2010 | <0.018 | U | | <0.018 | U | | <0.018 | U | | <0.018 | U | | <0.016 | U | | <0.016 | U | | 0.38 | | | <0.0083 | U | | <0.014 | U | | <0.014 | U | |
| | | VMP-13-10.5-091310-Dup | 9/13/2010 | <0.017 | U | | <0.017 | U | | <0.017 | U | | <0.018 | U | | <0.016 | U | | <0.016 | U | | 0.4 | | | <0.0081 | U | | 0.0025 | J | | <0.014 | U | |
| | | VMP-13-10.5-120110 | 12/1/2010 | 0.001 | J | | <0.0071 | U | | <0.007 | J | U | 0.0015 | J | | <0.0064 | U | | <0.0064 | U | | 0.081 | | | <0.0033 | U | | <0.0056 | J | U | <0.0056 | U | |
| | | VMP-13-10.5-120110-DUP | 12/1/2010 | 0.0011 | J | | <0.0074 | U | | <0.0072 | J | U | 0.0013 | J | | <0.0066 | U | | <0.0066 | U | | 0.097 | | | <0.0034 | U | | <0.0059 | J | U | <0.0059 | U | |
| | | VMP-13-10.5-021811 | 2/18/2011 | <2.9 | U | | <2.9 | U | | <2.9 | U | | <3 | U | | <2.6 | U | | <2.6 | U | | 17 | | | <1.4 | U | | <2.3 | U | | <2.3 | U | |
| | | VMP-13-10.5-021811-DUP | 2/18/2011 | <2.8 | U | | <2.8 | U | | <2.8 | U | | <2.9 | U | | <2.5 | U | | <2.5 | U | | 18 | | | <1.3 | U | | <2.2 | U | | <2.2 | U | |
| | | VMP-13-10.5-040511-DUP | 4/5/2011 | <0.0075 | U | | <0.0075 | U | | <0.0074 | J | U | 0.00087 | J | | <0.0068 | U | | <0.0068 | U | | 0.0012 | J | | <0.0035 | U | | 0.00081 | J | | <0.006 | U | |
| | | VMP-13-10.5-080911 | 8/9/2011 | <0.16 | U | | <0.16 | U | | <0.16 | U | | <0.17 | U | | <0.15 | U | | <0.15 | U | | 34 | | | <0.077 | U | | <0.13 | U | | <0.13 | U | |
| | | VMP-13-10.5-111411 | 11/14/2011 | <0.0048 | U | | <0.0048 | U | | 0.0012 | J | | <0.0049 | U | | 0.0014 | J | | <0.0043 | U | | 0.0017 | J | | <0.0022 | U | | 0.0023 | J | | 0.00073 | J | |
| | | VMP-13-10.5-012712 | 1/26/2012 | <0.013 | U | | <0.013 | U | | <0.013 | U | | <0.014 | U | | <0.012 | U | | <0.012 | U | | 0.052 | | | <0.0062 | U | | <0.011 | U | | <0.011 | U | |
| | | VMP-13-10.5-012712-DUP | 1/26/2012 | <0.019 | U | | <0.019 | U | | <0.019 | U | | <0.02 | U | | <0.017 | U | | <0.017 | U | | 0.08 | | | <0.0089 | U | | <0.015 | U | | <0.015 | U | |
| | | VMP-13-10.5-042012 | 4/20/2012 | <0.0048 | J | U | <0.0048 | U | | <0.0047 | U | | 0.0016 | J | | <0.0043 | U | | <0.0043 | U | | 0.0014 | J | | <0.0022 | U | | 0.0035 | J | | <0.0038 | U | |
| | | VMP-13-10.5-071912 | 7/19/2012 | <0.0051 | U | | <0.0051 | U | | <0.005 | U | | 0.0025 | J | J | 0.0018 | J | | <0.0046 | J | U | 0.01 | | | <0.0024 | U | | 0.0047 | | | 0.0019 | J | |
| | | VMP-13-10.5-100912 | 10/9/2012 | <0.0067 | U | | <0.0067 | U | | <0.0066 | U | | 0.0016 | J | | <0.0061 | J | U | <0.0061 | U | | 0.0022 | J | | <0.0032 | U | | 0.0084 | | | 0.0039 | J | |
| | | VMP-13-10.5-100912-Dup | 10/9/2012 | <0.0081 | U | | <0.0081 | U | | <0.008 | U | | 0.0014 | J | | <0.0073 | U | | <0.0073 | U | | 0.0012 | J | | <0.0038 | U | | <0.0064 | U | | <0.0064 | U | |
| | | VMP-13-10.5-013013 | 1/30/2013 | <0.0069 | U | | <0.0069 | U | | <0.0068 | U | | 0.0011 | J | | <0.0062 | U | | <0.0062 | U | | 0.001 | J | | <0.0032 | U | | <0.0055 | U | | <0.0055 | U | |
| | 21.5 ft | VMP-13-21.5-091310 | 9/13/2010 | <13 | U | | <13 | U | | <13 | U | | <14 | U | | <12 | U | | <12 | U | | 43 | | | <6.2 | U | | <10 | U | | <10 | U | |
| | | VMP-13-21.5-120110 | 12/1/2010 | <26 | U | | <26 | U | | <25 | U | | <26 | U | | <23 | U | | <23 | U | | 57 | | | <12 | U | | <20 | U | | <20 | U | |
| | | VMP-13-21.5-021811 | 2/18/2011 | <3.8 | U | | <3.8 | U | | <3.8 | U | | <3.9 | U | | <3.4 | U | | <3.4 | U | | 15 | | | <1.8 | U | | <3 | U | | <3 | U | |
| | | VMP-13-21.5-040511 | 4/5/2011 | <5.5 | U | | <5.5 | U | | <5.4 | U | | <5.7 | U | | <5 | U | | <5 | U | | 16 | | | <2.6 | U | | <4.4 | U | | <4.4 | U | |
| | | VMP-13-21.5-080911 | 8/9/2011 | <0.69 | U | | <0.69 | U | | <0.68 | U | | <0.71 | U | | <0.62 | U | | <0.62 | U | | 55 | | | <0.32 | U | | 0.18 | J | | <0.55 | U | |
| | | VMP-13-21.5-111411 | 11/14/2011 | <3.1 | U | | <3.1 | U | | <3.1 | U | | <3.2 | U | | <2.8 | U | | <2.8 | U | | 33 | | | <1.5 | U | | <2.5 | U | | <2.5 | U | |
| | | VMP-13-21.5-111411-DUP | 11/14/2011 | <3.1 | U | | <3.1 | U | | <3.1 | U | | <3.2 | U | | <2.8 | U | | <2.8 | U | | 31 | | | <1.5 | U | | <2.5 | U | | <2.5 | U | |
| | | VMP-13-21.5-012712 | 1/27/2012 | <0.73 | U | | <0.73 | U | | <0.72 | U | | <0.75 | U | | <2.6 | U | | <0.66 | U | | 29 | | J | <0.34 | U | | <0.58 | U | | <0.58 | U | |
| | | VMP-13-21.5-042012 | 4/20/2012 | <0.081 | U | | <0.081 | U | | <0.08 | U | | <0.084 | U | | 0.015 | J | | <0.073 | U | | 6.9 | | | <0.038 | U | | 0.024 | J | | <0.065 | U | |
| | | VMP-13-21.5-071912 | 7/19/2012 | <0.0051 | U | | <0.0051 | U | | <0.005 | U | | <0.0052 | U | | 0.0014 | J | | <0.0046 | J | U | 1.4 | | | <0.0024 | U | | 0.0054 | | | 0.0022 | J | |
| | | VMP-13-21.5-100912 | 10/9/2012 | <0.0083 | U | | <0.0083 | U | | <0.0081 | U | | <0.0085 | U | | <0.0074 | U | | <0.0074 | U | | 0.3 | | | <0.0039 | U | | <0.0066 | U | | <0.0066 | U | |
| | | VMP-13-21.5-013013 | 1/30/2013 | <0.0081 | U | | <0.0081 | U | | <0.008 | U | | 0.001 | J | | <0.0073 | U | | <0.0073 | U | | 0.0057 | J | | <0.0038 | U | | <0.0064 | U | | <0.0064 | U | |
| | 29.5 ft | VMP-13-29.5-021811 | 2/18/2011 | <120 | U | | <120 | U | | <120 | U | | <120 | U | | <110 | U | | <110 | U | | <100 | U | | <55 | U | | <94 | U | | <94 | U | |
| | | VMP-13-29.5-040511 | 4/5/2011 | <76 | U | | <76 | U | | <75 | U | | <79 | U | | <69 | U | | <69 | U | | 41 | J | | <36 | U | | 23 | J | | <61 | U | |
| | | VMP-13-29.5-013012 | 1/30/2012 | <2.3 | U | | <2.3 | U | | <2.3 | U | | <2.4 | U | | 0.3 | J | J | <2.1 | U | | 39 | | J | <1.1 | U | | 7.8 | | J | 2.1 | | J |
| | | VMP-13-29.5-042012 | 4/20/2012 | <3 | U | | <3 | U | | <3 | U | | <3.1 | U | | <2.8 | U | | <2.8 | U | | 17 | | | <1.4 | U | | 1 | J | | <2.4 | U | |
| | | VMP-13-29.5-071912 | 7/19/2012 | <8.8 | U | | <8.8 | U | | <8.6 | U | | <9 | U | | <7.9 | U | | <7.9 | U | | <7.5 | U | | <4.1 | U | | <7 | U | | <7 | U | |
| | | VMP-13-29.5-100912 | 10/9/2012 | <8.3 | U | | <8.3 | U | | 1.5 | J | | <8.5 | U | | <7.4 | U | UJ | <7.4 | U | | 4.5 | J | | <3.9 | U | | 0.67 | J | | <6.6 | U | |
| | | VMP-13-29.5-013013 | 1/30/2013 | <3.5 | U | | <3.5 | U | | <3.4 | U | | <3.6 | U | | <3.1 | U | | <3.1 | U | | <3 | U | | <1.6 | U | | <2.8 | U | | <2.8 | U | |

SEE LAST PAGE OF TABLE FOR NOTES

**TABLE 6**
**CUMULATIVE SUMMARY OF SOIL VAPOR ANALYTICAL DETECTIONS AND SCREENING RESULTS: PUBLIC WORKS YARD AND WRR - VOCS**

| Location | Depth | Sample ID | Sample Date | 1,1,1-Trichloroethane (Methyl | | | 1,1,2-Trichloroethane | | | Trichloroethene | | | Trichlorofluoromethane | | | 1,2,4-Trimethylbenzene | | | 1,3,5-Trimethylbenzene | | | 2,2,4-Trimethylpentane | | | Vinyl chloride | | | m,p-Xylene | | | o-Xylenes | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | 41000 | | | 170000 | | | 12 | | | 5600 | | | | | | | | | | | | 4.8 | | | 820 | | | 790 | | |
| | | | | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals |
| VMP-14 | 5 ft | VMP 14-5-091010 | 9/10/2010 | <0.34 | U | | <0.34 | U | | <0.33 | U | | <0.35 | U | | <0.3 | U | | <0.3 | U | | 19 | | | <0.16 | U | | <0.27 | U | | <0.27 | U | |
| | | VMP-14-5-120110 | 12/1/2010 | <0.0065 | U | | <0.0065 | U | | 0.0016 | J | | 0.0008 | J | | <0.0059 | U | | <0.0059 | U | | 0.014 | | | <0.0031 | U | | 0.0005 | J | | <0.0052 | U | |
| | | VMP-14-5-021711 | 2/17/2011 | <0.0072 | U | | <0.0072 | U | | <0.0071 | U | | <0.0074 | U | | <0.0065 | J | U | <0.0065 | U | | 0.62 | | | <0.0034 | U | | <0.0057 | J | U | <0.0057 | U | |
| | | VMP-14-5-040511 | 4/5/2011 | <0.0073 | U | | <0.0073 | U | | <0.0072 | J | U | 0.0018 | J | | <0.0066 | U | | <0.0066 | U | | 0.0042 | J | | <0.0034 | U | | <0.0058 | U | | <0.0058 | U | |
| | | VMP-14-5-080811 | 8/8/2011 | <7.7 | U | | <7.7 | U | | <7.6 | U | | <7.9 | U | | <6.9 | U | | <6.9 | U | | 120 | | | <3.6 | U | | <6.1 | U | | <6.1 | U | |
| | | VMP-14-5-111411 | 11/14/2011 | <0.019 | U | | <0.019 | U | | <0.019 | U | | <0.02 | U | | <0.017 | U | | <0.017 | U | | 0.012 | J | | <0.009 | U | | <0.015 | U | | <0.015 | U | |
| | | VMP-14-5-042012 | 4/20/2012 | <0.0047 | U | | <0.0047 | U | | <0.0046 | U | | 0.00086 | J | | 0.00076 | J | | <0.0042 | U | | 0.077 | | | <0.0022 | U | | 0.0043 | | | 0.0014 | J | |
| | | VMP-14-5-072312 | 7/23/2012 | <0.0056 | U | | <0.0056 | U | | <0.0055 | U | | 0.0011 | J | | 0.0076 | | | 0.0017 | J | | 0.0032 | J | | <0.0026 | U | | 0.025 | | | 0.0072 | | |
| | | VMP-14-5-101012 | 10/10/2012 | <0.0079 | U | | <0.0079 | U | | <0.0078 | U | | <0.0081 | U | | <0.0071 | U | | <0.0071 | U | | 0.018 | | | <0.0037 | U | | <0.0063 | J | U | <0.0063 | U | |
| | | VMP-14-5-013113 | 1/31/2013 | <0.0073 | U | | <0.0073 | U | | <0.0072 | U | | 0.0012 | J | | <0.0066 | U | | <0.0066 | U | | 0.0024 | J | | <0.0034 | U | | <0.0058 | U | | <0.0058 | U | |
| | 11.5 ft | VMP 14-11.5-091010 | 9/10/2010 | <5.2 | U | | <5.1 | U | | <5.1 | U | | <5.4 | U | | <4.7 | U | | <4.7 | U | | 230 | | | <2.4 | U | | <4.1 | U | | <4.1 | U | |
| | | VMP-14-11.5-120110 | 12/2/2010 | <0.46 | U | | <0.46 | U | | <0.45 | U | | <0.47 | U | | <0.41 | U | | <0.41 | U | | 36 | | | <0.21 | U | | 0.094 | J | | <0.36 | U | |
| | | VMP-14-11.5-120110-DUP | 12/2/2010 | <0.41 | U | | <0.41 | U | | <0.41 | U | | <0.43 | U | | <0.37 | U | | <0.37 | U | | 36 | | | <0.19 | U | | 0.14 | J | | <0.33 | U | |
| | | VMP-14-11.5-021711 | 2/17/2011 | <0.15 | U | | <0.15 | U | | <0.15 | U | | <0.16 | U | | <0.14 | U | | <0.14 | U | | 17 | | | <0.07 | U | | <0.12 | U | | <0.12 | U | |
| | | VMP-14-11.5-021711-DUP | 2/17/2011 | <0.15 | U | | <0.15 | U | | <0.15 | U | | <0.16 | U | | <0.14 | U | | <0.14 | U | | 19 | | | <0.07 | U | | <0.12 | U | | <0.12 | U | |
| | | VMP-14-11.5-040511 | 4/5/2011 | <0.024 | U | | <0.024 | U | | <0.024 | U | | <0.025 | U | | 0.0036 | J | | <0.022 | U | | 21 | | | <0.011 | U | | 0.0041 | J | | <0.019 | U | |
| | | VMP-14-11.5-080811 | 8/8/2011 | <0.76 | U | | <0.76 | U | | <0.75 | U | | <0.78 | U | | <0.68 | U | | <0.68 | U | | 20 | | | <0.36 | U | | <0.6 | U | | <0.6 | U | |
| | | VMP-14-11.5-111511 | 11/15/2011 | <1.2 | U | | <1.2 | U | | <1.2 | U | | <1.2 | U | | <1.1 | U | | <1.1 | U | | 25 | | | <0.55 | U | | <0.94 | U | | <0.94 | U | |
| | | VMP-14-11.5-012612 | 1/26/2012 | <4.8 | U | | <4.8 | U | | <4.7 | U | | <4.9 | U | | <17 | U | | <4.3 | U | | 86 | | | <2.2 | U | | <3.8 | U | | <3.8 | U | |
| | | VMP-14-11.5-042312 | 4/23/2012 | <0.005 | U | | <0.005 | U | | <0.0049 | U | | <0.0051 | U | | 0.00086 | J | | <0.0045 | U | | 0.028 | | | <0.0023 | U | | 0.0063 | | | 0.0017 | J | |
| | | VMP-14-11.5-042312-Dup | 4/23/2012 | <0.005 | U | | <0.005 | U | | <0.0049 | U | | <0.0051 | U | | <0.0045 | U | | <0.0045 | U | | 0.032 | | | <0.0023 | U | | 0.0046 | | | 0.0012 | J | |
| | | VMP-14-11.5-072512 | 7/25/2012 | <1.8 | U | | <1.8 | U | | <1.7 | U | | <1.8 | U | | <1.6 | U | | <1.6 | U | | 8.3 | | | <0.82 | U | | <1.4 | U | | <1.4 | U | |
| | | VMP-14-11.5-101012 | 10/10/2012 | <0.0075 | U | | <0.0075 | U | | <0.0074 | U | | <0.0078 | U | | <0.0068 | U | | <0.0068 | U | | 0.014 | | | <0.0035 | U | | <0.006 | U | | <0.006 | U | |
| | | VMP-14-11.5-013113 | 1/31/2013 | <0.007 | U | | <0.007 | U | | <0.0069 | U | | 0.0016 | J | | <0.0063 | U | | <0.0063 | U | | 0.0047 | J | | <0.0033 | U | | <0.0056 | U | | <0.0056 | U | |
| | 20 ft | VMP 14-20-091010 | 9/10/2010 | <79 | U | | <79 | U | | <78 | U | | <82 | U | | <72 | U | | <72 | U | | 250 | | | <37 | U | | <63 | U | | <63 | U | |
| | | VMP-14-20-091010-Dup | 9/10/2010 | <82 | U | | <82 | U | | <81 | U | | <85 | U | | <74 | U | | <74 | U | | 240 | | | <38 | U | | <66 | U | | <66 | U | |
| | | VMP-14-20-120110 | 12/2/2010 | <210 | U | | <210 | U | | <210 | U | | <220 | U | | <190 | U | | <190 | U | | 320 | | | <100 | U | | <170 | U | | <170 | U | |
| | | VMP-14-20-021811 | 2/18/2011 | <120 | U | | <120 | U | | <120 | U | | <120 | U | | <110 | U | | <110 | U | | 220 | | | <57 | U | | <96 | U | | <96 | U | |
| | | VMP-14-20-040511 | 4/5/2011 | <52 | U | | <52 | U | | <51 | U | | <53 | U | | <47 | U | | <47 | U | | 150 | | | <24 | U | | <41 | U | | <41 | U | |
| | | VMP-14-20-080811 | 8/8/2011 | <19 | U | | <19 | U | | <18 | U | | <19 | U | | <17 | U | | <17 | U | | 220 | | | <8.8 | U | | <15 | U | | <15 | U | |
| | | VMP-14-20-111511 | 11/15/2011 | <97 | U | | <97 | U | | <96 | U | | <100 | U | | <88 | U | | <88 | U | | 250 | | | <46 | U | | <77 | U | | <77 | U | |
| | | VMP-14-20-012612 | 1/26/2012 | <9.5 | U | | <9.5 | U | | <9.4 | U | | <9.8 | U | | <34 | U | | <8.6 | U | | 280 | | J | <4.5 | U | | <7.6 | U | | <7.6 | U | |
| | | VMP-14-20-042312 | 4/23/2012 | <5.2 | U | | <5.2 | U | | <5.1 | U | | <5.4 | U | | <4.7 | U | | <4.7 | U | | 240 | | | <2.4 | U | | <4.1 | U | | <4.1 | U | |
| | | VMP-14-20-072512 | 7/25/2012 | <8.3 | U | | <8.3 | U | | <8.2 | U | | <8.6 | U | | <7.5 | U | | <7.5 | U | | 190 | | | <3.9 | U | | <6.6 | U | | <6.6 | U | |
| | | VMP-14-20-101612 | 10/16/2012 | <38 | U | | <38 | U | | <38 | U | | <40 | U | | <35 | U | | <35 | U | | 150 | | | <18 | U | | 29 | J | | 4.6 | J | |
| | | VMP-14-20-013113 | 1/31/2013 | <14 | U | | <14 | U | | <14 | U | | <14 | U | | <12 | U | | <12 | U | | 140 | | | <6.4 | U | | <11 | U | | <11 | U | |
| | 29 ft | VMP-14-29-021811 | 2/18/2011 | <180 | U | | <180 | U | | <170 | U | | <180 | U | | <160 | U | | <160 | U | | 320 | | | <82 | U | | <140 | U | | <140 | U | |
| | | VMP-14-29-040511 | 4/5/2011 | <150 | U | | <150 | U | | <150 | U | | <160 | U | | <140 | U | | <140 | U | | 280 | | | <70 | U | | <120 | U | | <120 | U | |
| | | VMP-14-29-012612 | 1/26/2012 | <170 | U | | <170 | U | | <170 | U | | <180 | U | | <620 | U | | <150 | U | | 330 | | | <80 | U | | <140 | U | | <140 | U | |
| | | VMP-14-29-042312 | 4/23/2012 | <61 | U | | <61 | U | | <60 | U | | <63 | U | | <55 | U | | <55 | U | | 260 | | | <29 | U | | <49 | U | | <49 | U | |
| | | VMP-14-29-072512 | 7/25/2012 | <64 | U | | <64 | U | | <63 | U | | <66 | U | | <58 | U | | <58 | U | | 260 | | | <30 | U | | <51 | U | | <51 | U | |
| | | VMP-14-29-101612 | 10/16/2012 | <96 | U | | <96 | U | | <94 | U | | <99 | U | | <86 | U | | <86 | U | | 140 | | | <45 | U | | 31 | J | | <76 | U | |
| | | VMP-14-29-013113-DUP | 1/31/2013 | <130 | U | | <130 | U | | <130 | U | | <130 | U | | <120 | U | | <120 | U | | 160 | | J | <60 | U | | <100 | U | UJ | <100 | U | |
| | | VMP-14-29-013113 | 1/31/2013 | <54 | U | | <54 | U | | <53 | U | | <55 | U | | <48 | U | | <48 | U | | 470 | | J | <25 | U | | 19 | J | J | <43 | U | |
| VMP-15 | 5 ft | VMP 15-5-091410 | 9/14/2010 | <0.0069 | U | | <0.0069 | U | | <0.0068 | U | | <0.0071 | U | | <0.0062 | U | | <0.0062 | U | | 0.028 | | | <0.0032 | U | | 0.0011 | J | | <0.0055 | U | |
| | | VMP-15-5-113010 | 11/30/2010 | <0.16 | U | | <0.16 | U | | <0.16 | U | | <0.17 | U | | <0.15 | U | | <0.15 | U | | 56 | | | <0.076 | U | | <0.13 | U | | <0.13 | U | |
| | | VMP-15-5-021611 | 2/16/2011 | <0.15 | U | | <0.15 | U | | <0.15 | U | | <0.16 | U | | 0.017 | J | | <0.14 | U | | 39 | | | <0.072 | U | | 0.023 | J | | <0.12 | U | |
| | | VMP-15-5-042011 | 4/20/2011 | <0.36 | U | | <0.36 | U | | <0.35 | U | | <0.37 | U | | <0.32 | U | | <0.32 | U | | 65 | | | <0.17 | U | | <0.29 | U | | <0.29 | U | |
| | | VMP-15-5-080811 | 8/8/2011 | <0.0081 | U | | <0.0081 | U | | <0.008 | U | | 0.0015 | J | | 0.0034 | J | | <0.0073 | J | U | 0.0031 | J | | <0.0038 | U | | 0.004 | J | | 0.0016 | J | |
| | | VMP-15-5-111511 | 11/15/2011 | <0.009 | U | | <0.009 | U | | <0.0089 | U | | <0.0093 | U | | 0.0018 | J | | <0.0082 | U | | 0.096 | | | <0.0042 | U | | 0.005 | J | | 0.0011 | J | |
| | | VMP-15-5-020112 | 2/1/2012 | <0.047 | U | | <0.047 | U | | <0.046 | U | | <0.048 | U | | 0.013 | J | J | <0.042 | U | | 0.026 | J | | <0.022 | U | | 0.0099 | J | | <0.037 | U | |
| | | VMP-15-5-042412 | 4/24/2012 | <0.048 | U | | <0.048 | U | | <0.047 | U | | <0.049 | U | | <0.043 | U | | <0.043 | U | | 0.18 | | | <0.022 | U | | <0.038 | U | | <0.038 | U | |
| | | VMP-15-5-072512 | 7/25/2012 | <0.0054 | U | | <0.0054 | U | | <0.0053 | U | | 0.0016 | J | | 0.0039 | J | | 0.0018 | J | | 0.0012 | J | | <0.0025 | U | | 0.0085 | | | 0.0039 | J | |
| | | VMP-15-5-102512 | 10/25/2012 | <0.0081 | U | | <0.0081 | U | | <0.008 | U | | <0.0083 | U | | <0.0073 | J | U | <0.0073 | U | | 0.019 | | | <0.0038 | U | | 0.0041 | J | | 0.0015 | J | |
| | | VMP-15-5-020513 | 2/5/2013 | <0.0079 | U | | <0.0079 | U | | <0.0078 | U | | <0.0081 | U | | <0.0071 | U | | <0.0071 | U | | 0.0062 | J | | <0.0037 | U | | <0.0063 | U | | <0.0063 | U | |
| | 21.5 ft | VMP 15-21.5-091410 | 9/14/2010 | <0.75 | U | | <0.75 | U | | <0.74 | U | | <0.77 | U | | <0.67 | U | | <0.67 | U | | 300 | | | <0.35 | U | | <0.59 | U | | <0.59 | U | |
| | | VMP-15-21.5-113010 | 11/30/2010 | <0.88 | U | | <0.88 | U | | <0.86 | U | | <0.9 | U | | <0.79 | U | | <0.79 | U | | 440 | | | <0.41 | U | | <0.7 | U | | <0.7 | U | |
| | | VMP-15-21.5-021611 | 2/16/2011 | <0.61 | U | | <0.61 | U | | <0.6 | U | | <0.63 | U | | <0.55 | U | | <0.55 | U | | 430 | | | <0.29 | U | | <0.49 | U | | <0.49 | U | |
| | | VMP-15-21.5-042011 | 4/20/2011 | <0.96 | U | | <0.96 | U | | <0.94 | U | | <0.99 | U | | <0.86 | U | | <0.86 | U | | 580 | | | <0.45 | U | | <0.76 | U | | <0.76 | U | |
| | | VMP-15-21.5-080811 | 8/8/2011 | <0.77 | U | | <0.77 | U | | <0.76 | U | | <0.79 | U | | <0.69 | U | | <0.69 | U | | 310 | | | <0.36 | U | | <0.61 | U | | <0.61 | U | |
| | | VMP-15-21.5-111511 | 11/15/2011 | <0.61 | U | | <0.61 | U | | <0.6 | U | | <0.63 | U | | <0.55 | U | | <0.55 | U | | 170 | | | <0.29 | U | | <0.49 | U | | <0.49 | U | |
| | | VMP-15-21.5-020112 | 2/1/2012 | <0.46 | U | | <0.46 | U | | <0.45 | U | | <0.47 | U | | <1.6 | U | UJ | <0.41 | U | | 320 | | J | <0.21 | U | | <0.36 | U | | <0.36 | U | |
| | | VMP-15-21.5-042412 | 4/24/2012 | <0.2 | U | | <0.2 | U | | <0.2 | U | | <0.2 | U | | <0.18 | U | | <0.18 | U | | 210 | | | <0.094 | U | | <0.16 | U | | <0.16 | U | |
| | | VMP-15-21.5-072512 | 7/25/2012 | <0.72 | U | | <0.72 | U | | <0.71 | U | | <0.74 | U | | <0.65 | U | | <0.65 | U | | 260 | | | <0.34 | U | | <0.58 | U | | <0.58 | U | |
| | | VMP-15-21.5-102512 | 10/25/2012 | <1.2 | U | | <1.2 | U | | 0.28 | J | | <1.2 | U | | <1.1 | U | | <1.1 | U | | 110 | | | <0.55 | U | | <0.94 | U | | <0.94 | U | |
| | | VMP-15-21.5-102512-Dup | 10/25/2012 | <1.2 | U | | <1.2 | U | | 0.28 | J | | <1.2 | U | | <1.1 | U | | <1.1 | U | | 110 | | | <0.57 | U | | <0.97 | U | | <0.97 | U | |
| | | VMP-15-21.5-020713 | 2/7/2013 | <0.03 | U | | <0.03 | U | | <0.03 | U | | <0.031 | U | | <0.027 | U | | <0.027 | U | | 6.4 | | | <0.014 | U | | <0.024 | U | | <0.024 | U | |
| | 25.5 ft | VMP 15-25.5-091410 | 9/14/2010 | <0.007 | U | | <0.007 | U | | <0.0069 | U | | 0.001 | J | | <0.0063 | U | | <0.0063 | U | | 0.17 | | | <0.0033 | U | | <0.0056 | U | | <0.0056 | U | |
| | | VMP-15-25.5-021611 | 2/16/2011 | <0.094 | U | | <0.094 | U | | <0.092 | U | | <0.097 | U | | <0.084 | U | | <0.084 | U | | 29 | | | <0.044 | U | | <0.075 | U | | <0.075 | U | |
| | | VMP-15-25.5-042011 | 4/20/2011 | <0.077 | U | | <0.077 | U | | <0.076 | U | | <0.079 | U | | <0.069 | U | | <0.069 | U | | 1.2 | | J | <0.036 | U | | <0.061 | U | | <0.061 | U | |
| | | VMP-15-25.5-042011-DUP | 4/20/2011 | <0.072 | U | | <0.072 | U | | <0.071 | U | | <0.074 | U | | <0.065 | U | | <0.065 | U | | 1.6 | | J | <0.034 | U | | <0.057 | U | | <0.057 | U | |
| | | VMP-15-25.5-080811 | 8/8/2011 | <0.077 | U | | <0.077 | U | | <0.076 | U | | <0.079 | U | | 0.0099 | J | | <0.069 | U | | 17 | | | <0.036 | U | | 0.016 | J | | <0.061 | U | |
| | | VMP-15-25.5-111511 | 11/15/2011 | <0.024 | U | | <0.024 | U | | <0.023 | U | | <0.024 | U | | <0.021 | U | | <0.021 | U | | 3 | | | <0.011 | U | | 0.0054 | J | | <0.019 | U | |
| | | VMP-15-25.5-073112 | 7/31/2012 | <0.05 | U | | <0.05 | U | | <0.049 | U | | <0.051 | U | | <0.045 | U | | <0.045 | U | | 29 | | | <0.023 | U | | 0.011 | J | | 0.0058 | J | |
| | | VMP-15-25.5-102512 | 10/25/2012 | <0.0081 | U | | <0.0081 | U | | <0.008 | U | | <0.0083 | U | | 0.0029 | J | | 0.0015 | J | | 1.9 | | | <0.0038 | U | | 0.004 | J | | <0.0064 | U | |
| | | VMP-15-25.5-021213 | 2/12/2013 | <0.24 | U | | <0.24 | U | | <0.24 | U | | <0.25 | U | | 0.054 | J | | <0.22 | U | | 140 | | | <0.11 | U | | 0.074 | J | | 0.038 | J | |
| | 29 ft | VMP-15-29-073112 | 7/31/2012 | <0.21 | U | | <0.21 | U | | <0.21 | U | | <0.22 | U | | <0.19 | U | | <0.19 | U | | 150 | | J | <0.1 | U | | 0.017 | J | J | <0.17 | U | |
| | | VMP-15-29-102512 | 10/25/2012 | <0.017 | U | | <0.017 | U | | <0.017 | U | | <0.017 | U | | 0.0047 | J | | <0.015 | U | | 3.4 | | | <0.0079 | U | | 0.0042 | J | | <0.013 | U | |
| | | VMP-15-29-021213 | 2/12/2013 | <0.15 | U | | <0.15 | U | | <0.14 | U | | <0.15 | U | | <0.13 | U | | <0.13 | U | | 110 | | | <0.069 | U | | <0.12 | U | | <0.12 | U | |

SEE LAST PAGE OF TABLE FOR NOTES

**TABLE 6**
**CUMULATIVE SUMMARY OF SOIL VAPOR ANALYTICAL DETECTIONS AND SCREENING RESULTS: PUBLIC WORKS YARD AND WRR - VOCS**

| Location | Depth | Sample ID | Sample Date | 1,1,1-Trichloroethane (Methyl | | | 1,1,2-Trichloroethane | | | Trichloroethene | | | Trichlorofluoromethane | | | 1,2,4-Trimethylbenzene | | | 1,3,5-Trimethylbenzene | | | 2,2,4-Trimethylpentane | | | Vinyl chloride | | | m,p-Xylene | | | o-Xylenes | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | 41000 | | | 170000 | | | 12 | | | 5600 | | | | | | | | | | | | 4.8 | | | 820 | | | 790 | | |
| | | | | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals |
| VMP-16 | 5 ft | VMP-16-5-090210 | 9/2/2010 | <13 | U | | <13 | U | | <13 | U | | <13 | U | | 2.3 | J | | <12 | U | | 9300 | | | <6.1 | U | | 5.4 | J | | <10 | U | |
| | | VMP-16-5-112910 | 11/29/2010 | <5.9 | U | | <5.9 | U | | <5.8 | U | | <6.1 | U | | <5.4 | U | | <5.4 | U | | 7600 | | | <2.8 | U | | 2.6 | J | J | <4.7 | U | |
| | | VMP-16-5-021511 | 2/15/2011 | <3.6 | U | | <3.6 | U | | <3.5 | U | | <3.7 | U | | <3.2 | U | | <3.2 | U | | 5500 | | | <1.7 | U | | 0.98 | J | J | <2.9 | U | |
| | | VMP-16-5-042211 | 4/22/2011 | <4.8 | U | | <4.8 | U | | <4.7 | U | | <4.9 | U | | <4.3 | U | | <4.3 | U | | 7900 | | | <2.2 | U | | 1 | J | | <3.8 | U | |
| | | VMP-16-5-080511 | 8/5/2011 | <1.5 | U | | <1.5 | U | | <1.5 | U | | <1.6 | U | | <1.4 | U | | <1.4 | U | | 2100 | | | <0.72 | U | | <1.2 | U | | <1.2 | U | |
| | | VMP-16-5-042512 | 4/25/2012 | <5.2 | U | | <5.2 | U | | <5.1 | U | | <5.4 | U | | <4.7 | U | | <4.7 | U | | 6800 | | | <2.4 | U | | <4.1 | U | | <4.1 | U | |
| | | VMP-16-5-073012 | 7/30/2012 | <4.9 | U | | <4.9 | U | | <4.8 | U | | <5 | U | | <4.4 | U | | <4.4 | U | | 8200 | | | <2.3 | U | | 0.62 | J | J | <3.9 | U | |
| | | VMP-16-5-102512 | 10/25/2012 | <3.8 | U | | <3.8 | U | | <3.8 | U | | <4 | U | | <3.5 | U | | <3.5 | U | | 1000 | | J | <1.8 | U | | <3.1 | U | | <3.1 | U | |
| | | VMP-16-5-021413 | 2/14/2013 | <0.6 | U | | <0.6 | U | | 0.24 | J | J | <0.62 | U | | <0.54 | U | | <0.54 | U | | 290 | | J | <0.28 | U | | <0.48 | U | | <0.48 | U | |
| | 13.5 ft | VMP-16-13.5-090210 | 9/2/2010 | <13 | U | | <13 | U | | <13 | U | | <14 | U | | 3.6 | J | | 1.7 | J | | 8200 | | | <6.3 | U | | 5.6 | J | | <11 | U | |
| | | VMP-16-13.5-090210-DUP | 9/2/2010 | <13 | U | | <13 | U | | <13 | U | | <14 | U | | 3 | J | | <12 | U | | 8000 | | | <6.3 | U | | 6.1 | J | | <11 | U | |
| | | VMP-16-13.5-112910 | 11/29/2010 | <38 | U | | <38 | U | | <38 | U | | <39 | U | | <34 | U | | <34 | U | | 11000 | | | <18 | U | | <30 | U | | <30 | U | |
| | | VMP-16-13.5-021611 | 2/16/2011 | <7.3 | U | | <7.3 | U | | <7.2 | U | | <7.6 | U | | <6.6 | U | | <6.6 | U | | 5600 | | | <3.4 | U | | <5.8 | U | | <5.8 | U | |
| | | VMP-16-13.5-021611-DUP | 2/16/2011 | <7.2 | U | | <7.2 | U | | <7.1 | U | | <7.4 | U | | <6.5 | U | | <6.5 | U | | 6100 | | | <3.4 | U | | <5.7 | U | | <5.7 | U | |
| | | VMP-16-13.5-042211 | 4/22/2011 | <7.7 | U | | <7.7 | U | | <7.6 | U | | <8 | U | | <7 | U | | <7 | U | | 7600 | | | <3.6 | U | | <6.2 | U | | <6.2 | U | |
| | | VMP-16-13.5-080511 | 8/5/2011 | <0.75 | U | | <0.75 | U | UJ | <0.74 | U | UJ | <0.78 | U | UJ | <0.68 | U | UJ | <0.68 | U | UJ | 610 | | J | <0.35 | U | UJ | <0.6 | U | UJ | <0.6 | U | UJ |
| | | VMP-16-13.5-042512 | 4/25/2012 | <0.83 | U | | <0.83 | U | | <0.82 | U | | <0.86 | U | | 0.46 | J | J | 0.22 | J | J | 8600 | | | <0.39 | U | | 1.3 | | J | <0.66 | U | |
| | | VMP-16-13.5-073012 | 7/30/2012 | <25 | U | | <25 | U | | <24 | U | | <26 | U | | <22 | U | | <22 | U | | 12000 | | | <12 | U | | <20 | U | | <20 | U | |
| | | VMP-16-13.5-102512 | 10/25/2012 | <77 | U | | <77 | U | | <76 | U | | <79 | U | | <69 | U | | <69 | U | | 11000 | | | <36 | U | | <61 | U | | <61 | U | |
| | | VMP-16-13.5-021413 | 2/14/2013 | <12 | U | | <12 | U | | 18 | | J | <12 | U | | <11 | U | | <11 | U | | 11000 | | J | <5.7 | U | | 2.2 | J | J | <9.7 | U | |
| | 19 ft | VMP-16-19-090210 | 9/2/2010 | <13 | U | | <13 | U | | <13 | U | | <14 | U | | 3.8 | J | | <12 | U | | 10000 | | | <6.3 | U | | 8.2 | J | | <11 | U | |
| | | VMP-16-19-112910 | 11/29/2010 | <29 | U | | <29 | U | | <29 | U | | <30 | U | | <26 | U | | <26 | U | | 10000 | | | <14 | U | | <23 | U | | <23 | U | |
| | | VMP-16-19-021611 | 2/16/2011 | <7 | U | | <7 | U | | <6.9 | U | | <7.2 | U | | <6.3 | U | | <6.3 | U | | 5900 | | | <3.3 | U | | <5.6 | U | | <5.6 | U | |
| | | VMP-16-19-042711 | 4/27/2011 | <7.2 | U | | <7.2 | U | | 3.3 | J | | <7.4 | U | | <6.5 | U | | <6.5 | U | | 5100 | | | <3.4 | U | | <5.7 | U | | <5.7 | U | |
| | | VMP-16-19-042711-DUP | 4/27/2011 | <7 | U | | <7 | U | | <6.9 | U | | <7.2 | U | | <6.3 | U | | <6.3 | U | | 5000 | | | <3.3 | U | | <5.6 | U | | <5.6 | U | |
| | | VMP-16-19-042512 | p | <19 | U | | <19 | U | | <19 | U | | <20 | U | | <17 | U | | <17 | U | | 9100 | | | <9 | U | | <15 | U | | <15 | U | |
| | | VMP-16-19-073012 | 7/30/2012 | <17 | U | | <17 | U | | <17 | U | | <18 | U | | <16 | U | | <16 | U | | 8800 | | | <8.1 | U | | 3.3 | J | | <14 | U | |
| | | VMP-16-19-102512 | 10/25/2012 | <72 | U | | <72 | U | | <71 | U | | <74 | U | | <65 | U | | <65 | U | | 8600 | | | <34 | U | | <57 | U | | <57 | U | |
| | | VMP-16-19-021413 | 2/14/2013 | <7.2 | U | | <7.2 | U | | <7.1 | U | | <7.4 | U | | 13 | | J | 3.9 | J | J | 11000 | | J | <3.4 | U | | 26 | | J | 0.64 | J | J |
| | 31 ft | VMP-16-31-090310 | 9/3/2010 | <0.0079 | U | | <0.0079 | U | | <0.0078 | U | | 0.0013 | J | | 0.0028 | J | | 0.0027 | J | | 7.4 | | | <0.0037 | U | | 0.0024 | J | | <0.0063 | U | |
| | | VMP-16-31-112910 | 11/29/2010 | <30 | U | | <30 | U | | <29 | U | | <31 | U | | <27 | U | | <27 | U | | 11000 | | | <14 | U | | <24 | U | | <24 | U | |
| | | VMP-16-31-042512 | 4/25/2012 | <23 | U | | <23 | U | | <23 | U | | <24 | U | | <21 | U | | <21 | U | | 11000 | | | <11 | U | | <19 | U | | <19 | U | |
| | | VMP-16-31-073012 | 7/30/2012 | <19 | U | | <19 | U | | <19 | U | | <20 | U | | <17 | U | | <17 | U | | 11000 | | | <8.9 | U | | <15 | U | | <15 | U | |
| | | VMP-16-31-102512 | 10/25/2012 | <89 | U | | <89 | U | | <88 | U | | <92 | U | | <81 | U | | <81 | U | | 10000 | | | <42 | U | | <71 | U | | <71 | U | |
| | | VMP-16-31-021813 | 2/18/2013 | <27 | U | | <27 | U | | <27 | U | | <28 | U | | <24 | U | | <24 | U | | 13000 | | | <13 | U | | <22 | U | | <22 | U | |
| VMP-17 | 5 ft | VMP-17-5 | 6/21/2010 | <0.007 | U | | <0.007 | U | | <0.007 | U | | 0.0013 | J | | <0.007 | U | | <0.007 | U | | 1.2 | | | <0.003 | U | | <0.006 | U | | <0.006 | U | |
| | | VMP-17-5-DUP | 6/21/2010 | <0.008 | U | | <0.008 | U | | <0.008 | U | | 0.00099 | J | | <0.007 | U | | <0.007 | U | | 1 | | | <0.003 | U | | <0.006 | U | | <0.006 | U | |
| | | VMP-17-5-090110 | 9/1/2010 | <0.0073 | U | | <0.0073 | U | | <0.0072 | U | | 0.0015 | J | | <0.0066 | U | | <0.0066 | U | | 0.12 | J | J | <0.0034 | U | | 0.0053 | J | J | 0.0016 | J | J |
| | | VMP-17-5-112210 | 11/22/2010 | <0.0073 | U | | <0.0073 | U | | <0.0072 | U | | <0.0076 | U | | <0.0066 | U | | <0.0066 | U | | 0.0032 | J | | <0.0034 | U | | <0.0058 | J | U | <0.0058 | U | |
| | | VMP-17-5-020711 | 2/7/2011 | <0.0069 | U | | <0.0069 | U | | 0.0028 | J | | 0.001 | J | | <0.0062 | U | | <0.0062 | U | | 0.083 | | | <0.0032 | U | | <0.0055 | U | | <0.0055 | U | |
| | | VMP-17-5-040611 | 4/6/2011 | <0.028 | U | | <0.028 | U | | 0.0071 | J | | <0.028 | U | | <0.025 | U | | <0.025 | U | | 0.047 | | | <0.013 | U | | <0.022 | U | | <0.022 | U | |
| | | VMP-17-5-080111 | 8/1/2011 | <0.1 | U | | <0.1 | U | | <0.1 | U | | <0.11 | U | | <0.095 | U | | <0.095 | U | | 0.95 | | | <0.049 | U | | <0.084 | U | | <0.084 | U | |
| | | VMP-17-5-110711 | 11/7/2011 | <0.0047 | U | | <0.0047 | U | | <0.0046 | U | | 0.0008 | J | | <0.0042 | J | U | <0.0042 | U | | 0.0014 | J | | <0.0022 | U | | <0.0037 | J | U | 0.00057 | J | |
| | | VMP-17-5-012612 | 1/26/2012 | <0.0049 | U | | <0.0049 | U | | 0.019 | | | <0.005 | U | | <0.0044 | U | | <0.0044 | U | | 0.0013 | J | | <0.0023 | U | | 0.0038 | J | | 0.001 | J | |
| | | VMP-17-5-041112 | 4/11/2012 | <0.005 | U | | <0.005 | U | | <0.0049 | U | | <0.0051 | U | | <0.0045 | J | U | <0.0045 | J | U | 0.0079 | | | <0.0023 | U | | 0.0063 | | | 0.0016 | J | |
| | | VMP-17-5-071112 | 7/11/2012 | <0.0053 | U | | <0.0053 | U | | <0.0053 | U | | 0.0012 | J | | 0.0044 | J | | <0.0048 | U | | 0.0074 | | | <0.0025 | U | | 0.0089 | | | 0.0024 | J | |
| | | VMP-17-5-100912 | 10/9/2012 | <0.0083 | U | | <0.0083 | U | | <0.0081 | U | | <0.0085 | U | | <0.0074 | J | U | <0.0074 | U | | 0.025 | | | <0.0039 | U | | 0.0058 | J | | <0.0066 | J | U |
| | | VMP-17-5-013113 | 1/31/2013 | <0.029 | U | | <0.029 | U | | <0.028 | U | | <0.03 | U | | 0.0091 | J | | <0.026 | U | | 0.018 | J | | <0.014 | U | | 0.0068 | J | | <0.023 | U | |
| | | VMP-17-5-013113-DUP | 1/31/2013 | <0.029 | U | | <0.029 | U | | <0.028 | U | | <0.03 | U | | <0.026 | U | | <0.026 | U | | 0.016 | J | | <0.014 | U | | <0.023 | U | | <0.023 | U | |
| VMP-25 | 5 ft | VMP-25-5-031511 | 3/15/2011 | <0.066 | U | | <0.066 | U | | <0.065 | U | | <0.068 | U | | 0.14 | | | 0.13 | | | 30 | | | <0.031 | U | | 0.26 | | | 0.15 | | |
| | | VMP-25-5-040811 | 4/8/2011 | <0.03 | U | | <0.03 | U | | <0.03 | U | | <0.031 | U | | <0.027 | U | | <0.027 | U | | 0.73 | | | <0.014 | U | | <0.024 | U | | <0.024 | U | |
| | | VMP-25-5-080911 | 8/9/2011 | <0.0064 | U | | <0.0064 | U | | 0.0019 | J | | 0.0015 | J | | 0.0041 | J | | 0.0015 | J | | 0.076 | | | <0.003 | U | | 0.027 | | | 0.0078 | | |
| | | VMP-25-5-111711 | 11/17/2011 | <0.0046 | U | | <0.0046 | U | | <0.0045 | U | | <0.0047 | U | | <0.0041 | U | | <0.0041 | U | | 0.0029 | J | | <0.0021 | U | | <0.0036 | U | | <0.0036 | U | |
| | | VMP-25-5-013112 | 1/31/2012 | <0.033 | U | | <0.033 | U | | <0.033 | U | | <0.034 | U | | <0.03 | U | | <0.03 | U | | 1.1 | | | <0.016 | U | | 0.0074 | J | | <0.026 | U | |
| | | VMP-25-5-042512 | 4/25/2012 | <0.0052 | U | | <0.0052 | U | | <0.0051 | U | | <0.0054 | U | | <0.0047 | J | U | <0.0047 | U | | 0.0025 | J | | <0.0024 | U | | 0.0068 | | | 0.0025 | J | |
| | | VMP-25-5-072612 | 7/26/2012 | <0.018 | U | | <0.018 | U | | <0.018 | U | | <0.018 | U | | 0.0076 | J | | 0.0036 | J | | <0.015 | U | | <0.0084 | U | | 0.028 | | | 0.011 | J | |
| | | VMP-25-5-102612 | 10/26/2012 | <0.0073 | U | | <0.0073 | U | | <0.0072 | U | | <0.0076 | U | | <0.0066 | U | | <0.0066 | U | | 0.067 | | | <0.0034 | U | | 0.001 | J | | <0.0058 | U | |
| | | VMP-25-5-030613 | 3/6/2013 | <0.007 | U | | <0.007 | U | | <0.0069 | U | | 0.00096 | J | | 0.0034 | J | | <0.0063 | U | | 0.072 | J | J | <0.0033 | U | | <0.0056 | U | | <0.0056 | U | |
| | 21 ft | VMP-25-21-031511 | 3/15/2011 | <13 | U | | <13 | U | | <13 | U | | <13 | U | | 1.9 | J | | <12 | U | | <11 | U | | <6 | U | | 18 | | | 4.6 | J | |
| | | VMP-25-21-031511-DUP | 3/15/2011 | <16 | U | | <16 | U | | <16 | U | | <17 | U | | <15 | U | | <15 | U | | <14 | U | | <7.7 | U | | 18 | | | 5.3 | J | |
| | | VMP-25-21-040811 | 4/8/2011 | <140 | U | | <140 | U | | <140 | U | | <140 | U | | <120 | U | | <120 | U | | <120 | U | | <64 | U | | 16 | J | | <110 | U | |
| | | VMP-25-21-040811-DUP | 4/8/2011 | <140 | U | | <140 | U | | <140 | U | | <140 | U | | <120 | U | | <120 | U | | <120 | U | | <65 | U | | 14 | J | | <110 | U | |
| | | VMP-25-21-080911 | 8/9/2011 | 80 | | | <45 | U | | 54 | | | <46 | U | | 190 | | | 73 | | | 2400 | | | <21 | U | | 1000 | | | 280 | | |
| | | VMP-25-21-111711 | 11/17/2011 | <61 | U | | <61 | U | | <60 | U | | <63 | U | | <55 | U | | <55 | U | | 720 | | | <29 | U | | <49 | U | | <49 | U | |
| | | VMP-25-21-111711-DUP | 11/17/2011 | <90 | U | | <90 | U | | <89 | U | | <93 | U | | <82 | U | | <82 | U | | 680 | | | <42 | U | | <72 | U | | <72 | U | |
| | | VMP-25-21-013112 | 1/31/2012 | <32 | U | | <32 | U | | <31 | U | | <33 | U | | <120 | U | | <29 | U | | <27 | U | | <15 | U | | <25 | U | | <25 | U | |
| | | VMP-25-21-013112-DUP | 2/1/2012 | <30 | U | | <30 | U | | <29 | U | | <31 | U | | <110 | U | | <27 | U | | <25 | U | | <14 | U | | <24 | U | | <24 | U | |
| | | VMP-25-21-042512 | 4/25/2012 | <20 | U | | <20 | U | | <20 | U | | <21 | U | | <18 | U | | <18 | U | | <17 | U | | <9.5 | U | | <16 | U | | <16 | U | |
| | | VMP-25-21-072612 | 7/26/2012 | <34 | U | | <34 | U | | <34 | U | | <35 | U | | <31 | U | | <31 | U | | <29 | U | | <16 | U | | <27 | U | | <27 | U | |
| | | VMP-25-21-102612 | 10/26/2012 | <210 | U | | <210 | U | | 14 | J | | <210 | U | | <180 | U | | <180 | U | | 320 | | | <97 | U | | <160 | U | | <160 | U | |
| | | VMP-25-21-030613 | 3/6/2013 | <52 | U | | <52 | U | | <52 | U | | <54 | U | | <47 | U | | <47 | U | | 400 | J | J | <24 | U | | <42 | U | | <42 | U | |
| | 31 ft | VMP-25-31-030613 | 3/6/2013 | <69 | U | | <69 | U | | 11 | J | | <71 | U | | <62 | U | | <62 | U | | 990 | | | <32 | U | | 7 | J | | 7.3 | J | |

SEE LAST PAGE OF TABLE FOR NOTES

**TABLE 6**
**CUMULATIVE SUMMARY OF SOIL VAPOR ANALYTICAL DETECTIONS AND SCREENING RESULTS: PUBLIC WORKS YARD AND WRR - VOCS**

| Location | Depth | Sample ID | Sample Date | 1,1,1-Trichloroethane (Methyl | | | 1,1,2-Trichloroethane | | | Trichloroethene | | | Trichlorofluoromethane | | | 1,2,4-Trimethylbenzene | | | 1,3,5-Trimethylbenzene | | | 2,2,4-Trimethylpentane | | | Vinyl chloride | | | m,p-Xylene | | | o-Xylenes | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | 41000 | | | 170000 | | | 12 | | | 5600 | | | | | | | | | | | | 4.8 | | | 820 | | | 790 | | |
| | | | | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals | Result ($mg/m^3$) | Lab Quals | URS Quals |
| VMP-29 | 10 ft | VMP-29-10-073012 | 7/30/2012 | <0.058 | U | | <0.058 | U | | <0.057 | U | | <0.06 | U | | <0.052 | U | | <0.052 | U | | <0.05 | U | | <0.027 | U | | <0.046 | U | | <0.046 | U | |
| | | VMP-29-10-100812 | 10/8/2012 | <0.1 | U | | <0.1 | U | | <0.1 | U | | <0.1 | U | | <0.092 | U | | <0.092 | U | | <0.088 | U | | <0.048 | U | | <0.082 | U | | <0.082 | U | |
| | | VMP-29-10-020613 | 2/6/2013 | <0.0077 | U | | <0.0077 | U | | <0.0076 | U | | 0.0012 | J | | <0.0069 | U | | <0.0069 | U | | <0.0066 | J | U | <0.0036 | U | | <0.0061 | U | | <0.0061 | U | |
| | 20 ft | VMP-29-20-073012 | 7/30/2012 | <0.68 | U | | <0.68 | U | | <0.67 | U | | <0.7 | U | | <0.62 | U | | <0.62 | U | | <0.59 | U | | <0.32 | U | | <0.54 | U | | <0.54 | U | |
| | | VMP-29-20-073012-Dup | 7/30/2012 | <0.64 | U | | <0.64 | U | | <0.63 | U | | <0.66 | U | | <0.58 | U | | <0.58 | U | | <0.55 | U | | <0.3 | U | | <0.51 | U | | <0.51 | U | |
| | | VMP-29-20-100812 | 10/8/2012 | <0.1 | U | | <0.1 | U | | <0.1 | U | | <0.1 | U | | <0.092 | U | | <0.092 | U | | <0.088 | U | | <0.048 | U | | <0.082 | U | | <0.082 | U | |
| | | VMP-29-20-020613 | 2/6/2013 | <0.0075 | U | | <0.0075 | U | | <0.0074 | U | | <0.0078 | J | U | <0.0068 | U | | <0.0068 | U | | <0.0064 | U | | <0.0035 | U | | 0.002 | J | | <0.006 | U | |
| | 30 ft | VMP-29-30-073012 | 7/30/2012 | <0.11 | U | | <0.11 | U | | <0.11 | U | | <0.12 | U | | <0.1 | U | | <0.1 | U | | <0.096 | U | | <0.053 | U | | <0.089 | U | | <0.089 | U | |
| | | VMP-29-30-100812 | 10/8/2012 | <0.5 | U | | <0.5 | U | | <0.5 | U | | <0.52 | U | | <0.45 | U | | <0.45 | U | | <0.43 | U | | <0.24 | U | | <0.4 | U | | <0.4 | U | |
| | | VMP-29-30-020613 | 2/6/2013 | <0.0079 | U | | <0.0079 | U | | <0.0078 | U | | <0.0081 | J | U | <0.0071 | U | | <0.0071 | U | | <0.0068 | J | U | <0.0037 | U | | 0.0021 | J | | <0.0063 | U | |
| VMP-30 | 10 ft | VMP-30-10-073012 | 7/30/2012 | <0.2 | U | | <0.2 | U | | <0.2 | U | | <0.21 | U | | <0.18 | U | | <0.18 | U | | <0.17 | U | | <0.096 | U | | <0.16 | U | | <0.16 | U | |
| | | VMP-30-10-100812 | 10/8/2012 | <0.0077 | U | | <0.0077 | U | | <0.0076 | U | | <0.0079 | U | | <0.0069 | U | | <0.0069 | U | | 0.036 | | | <0.0036 | U | | <0.0061 | J | U | <0.0061 | U | |
| | | VMP-30-10-020613 | 2/6/2013 | <0.0072 | U | | <0.0072 | U | | <0.0071 | U | | <0.0074 | J | U | <0.0065 | U | | <0.0065 | U | | 0.0019 | J | | <0.0034 | U | | <0.0057 | U | | <0.0057 | U | |
| | 20 ft | VMP-30-20-073012 | 7/30/2012 | <0.87 | U | | <0.87 | U | | <0.85 | U | | <0.89 | U | | <0.78 | U | | <0.78 | U | | <0.74 | U | | <0.41 | U | | <0.69 | U | | <0.69 | U | |
| | | VMP-30-20-100812 | 10/8/2012 | <0.32 | U | | <0.32 | U | | <0.31 | U | | <0.32 | U | | <0.28 | U | | <0.28 | U | | <0.27 | U | | <0.15 | U | | <0.25 | U | | <0.25 | U | |
| | | VMP-30-20-020613 | 2/6/2013 | <0.0072 | U | | <0.0072 | U | | <0.0071 | U | | <0.0074 | J | U | <0.0065 | J | U | <0.0065 | J | U | <0.0062 | J | U | <0.0034 | U | | 0.0015 | J | | <0.0057 | U | |
| | 30 ft | VMP-30-30-073012 | 7/30/2012 | <0.89 | U | | <0.89 | U | | <0.88 | U | | <0.92 | U | | <0.8 | U | | <0.8 | U | | <0.76 | U | | <0.42 | U | | <0.71 | U | | <0.71 | U | |
| | | VMP-30-30-100812 | 10/8/2012 | <0.66 | U | | <0.66 | U | | <0.65 | U | | <0.68 | U | | <0.59 | U | | <0.59 | U | | 0.1 | J | | <0.31 | U | | <0.52 | U | | <0.52 | U | |
| | | VMP-30-30-020613 | 2/6/2013 | <0.024 | U | | <0.024 | U | | <0.024 | U | | <0.025 | U | | <0.022 | U | | <0.022 | U | | <0.02 | U | | <0.011 | U | | <0.019 | U | | <0.019 | U | |
| VMP-41 | 10 ft | VMP-41-10-072712 | 7/27/2012 | <0.0066 | U | | <0.0066 | U | | <0.0065 | U | | <0.0068 | U | | 0.005 | J | | 0.0014 | J | | 0.013 | | | <0.0031 | U | | 0.015 | | | 0.0045 | J | |
| | | VMP-41-10-100912 | 10/9/2012 | <0.0081 | U | | <0.0081 | U | | <0.008 | U | | <0.0083 | U | | <0.0073 | U | | <0.0073 | U | | 0.00089 | J | | <0.0038 | U | | 0.0038 | J | | <0.0064 | U | |
| | | VMP-41-10-012913 | 1/29/2013 | <0.0081 | U | | <0.0081 | U | | <0.008 | U | | 0.0018 | J | | <0.0073 | U | | <0.0073 | U | | 0.0016 | J | | <0.0038 | U | | <0.0064 | U | | <0.0064 | U | |
| | 20 ft | VMP-41-20-072712 | 7/27/2012 | <0.0051 | U | | <0.0051 | U | | <0.005 | U | | 0.001 | J | | 0.0027 | J | | <0.0046 | U | | 0.0039 | J | | <0.0024 | U | | 0.0079 | | | 0.0028 | J | |
| | | VMP-41-20-072712-Dup | 7/27/2012 | <0.0052 | U | | <0.0052 | U | | <0.0051 | U | | 0.001 | J | | 0.0034 | J | | 0.00096 | J | | 0.0032 | J | | <0.0024 | U | | 0.008 | | | 0.0025 | J | |
| | | VMP-41-20-100912 | 10/9/2012 | <0.0079 | U | | <0.0079 | U | | <0.0078 | U | | <0.0081 | U | | <0.0071 | U | | <0.0071 | U | | <0.0068 | U | | <0.0037 | U | | 0.0037 | J | | <0.0063 | U | |
| | | VMP-41-20-100912-Dup | 10/9/2012 | <0.0081 | U | | <0.0081 | U | | <0.008 | U | | <0.0083 | U | | <0.0073 | J | U | <0.0073 | U | | <0.0069 | U | | <0.0038 | U | | 0.0035 | J | | <0.0064 | U | |
| | | VMP-41-20-012913 | 1/29/2013 | <0.0083 | U | | <0.0083 | U | | <0.0081 | U | | 0.0018 | J | | <0.0074 | U | | <0.0074 | U | | 0.021 | | | <0.0039 | U | | <0.0066 | U | | <0.0066 | U | |
| | 30 ft | VMP-41-30-072712 | 7/27/2012 | <0.0052 | U | | <0.0052 | U | | <0.0051 | U | | <0.0054 | U | | 0.0049 | | | 0.00092 | J | | 0.013 | | | <0.0024 | U | | 0.007 | | | 0.0028 | J | |
| | | VMP-41-30-100912 | 10/9/2012 | <0.0085 | U | | <0.0085 | U | | <0.0084 | U | | <0.0087 | U | | <0.0076 | J | U | <0.0076 | U | | 0.0038 | J | | <0.004 | U | | 0.0018 | J | | <0.0068 | U | |
| | | VMP-41-30-012913 | 1/29/2013 | <0.0077 | U | | <0.0077 | U | | <0.0076 | U | | 0.0019 | J | | <0.0069 | U | | <0.0069 | U | | 0.02 | | | <0.0036 | U | | <0.0061 | U | | <0.0061 | U | |
| VMP-55 | 20 ft | VMP-55-20-021513 | 2/15/2013 | <19 | U | | <19 | U | | 5.5 | J | | <19 | U | | <17 | U | | <17 | U | | 370 | | | <8.8 | U | | <15 | U | | <15 | U | |

Notes
**Lab Qualifiers**
J = Estimated value; results between the MDL and RL
U = Compound analyzed for but not detected above the RL
**URS Qualifiers**
J = Estimated detection
UJ = Estimated non-detect
U = Non-detect due to blank contamination

SEE LAST PAGE OF TABLE FOR NOTES

**TABLE 7**
**CUMULATIVE SUMMARY OF SOIL VAPOR ANALYTICAL RESULTS - NATURAL GASES**

| Location | Depth | Sample ID | Sample Date | Carbon Dioxide | | | Carbon Monoxide | | | Ethane | | | Ethene | | | Helium | | | Methane | | | Nitrogen | | | Oxygen | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | Result % | Lab Quals | URS Quals | Result % | Lab Quals | URS Quals | Result % | Lab Quals | URS Quals | Result % | Lab Quals | URS Quals | Result % | Lab Quals | URS Quals | Result % | Lab Quals | URS Quals | Result % | Lab Quals | URS Quals | Result % | Lab Quals | URS Quals |
| VMP-1 | 5 ft | VMP-1-5-082510 | 8/25/2010 | 3 | | | <0.026 | U | | <0.0026 | U | | <0.0026 | U | | 0.95 | | | 0.0032 | | | 79 | | | 17 | | |
| | | VMP-1-5-111710 | 11/17/2010 | 1 | | | <0.026 | U | | <0.0026 | U | | <0.0026 | U | | 3.3 | | | 0.0013 | | | 76 | | | 20 | | |
| | | VMP-1-5-020411 | 2/4/2011 | 8 | | | <0.02 | U | | 0.00015 | J | | <0.002 | U | | 0.036 | J | | 0.26 | | | 84 | | | 7.5 | | |
| | | VMP-1-5-041211 | 4/12/2011 | 1.8 | | | <0.026 | U | | <0.0026 | U | | <0.0026 | U | | 0.54 | | | 0.000064 | J | | 78 | | | 20 | | |
| | | VMP-1-5-080111 | 8/1/2011 | 7.8 | | | <0.026 | U | | <0.0026 | U | | <0.0026 | U | | 0.59 | | | 0.00007 | J | | 80 | | | 12 | | |
| | | VMP-1-5-110311 | 11/3/2011 | 7.4 | | | <0.018 | U | | 0.00087 | J | | <0.0018 | U | | 0.017 | J | | 1.7 | | | 82 | | | 8.5 | | |
| | | VMP-1-5-013012 | 1/30/2012 | 12 | | | <0.018 | U | | 0.00086 | J | | <0.0018 | U | | 0.026 | J | | 1.4 | | | 84 | | | 1.7 | | |
| | | VMP-1-5-041312 | 4/13/2012 | 2 | | | <0.018 | U | | <0.0018 | U | | <0.0018 | U | | 0.05 | J | | 0.000022 | J | | 78 | | | 20 | | |
| | | VMP-1-5-071612 | 7/16/2012 | 1.8 | | | <0.024 | U | | <0.0024 | U | | <0.0024 | U | | 1.1 | | | 0.0012 | | | 78 | | | 19 | | |
| | | VMP-1-5-101112 | 10/11/2012 | 0.37 | | | <0.028 | U | | <0.0028 | U | | <0.0028 | U | | 0.094 | | | 0.000034 | J | | 80 | | | 19 | | |
| | | [2]VMP-1-5-012113 | 1/21/2013 | 0.34 | | | <0.13 | U | | <0.0026 | U | | <0.0026 | U | | 0.17 | | | 0.0016 | | | 78 | | | 21 | | |
| | | [1]VMP-1-5-012313-R | 1/23/2013 | 3.1 | | | <0.12 | U | | 0.00074 | J | | <0.0023 | U | | <0.12 | U | | 2 | | | 78 | | | 16 | | |
| | 8.5 ft | VMP-1-8.5-082510 | 8/25/2010 | 4.8 | | | <0.026 | U | | <0.0026 | U | | <0.0026 | U | | 4.1 | | | 0.0032 | | | 78 | | | 13 | | |
| | | VMP-1-8.5-111710 | 11/17/2010 | 4.8 | | | <0.025 | U | | <0.0025 | U | | <0.0025 | U | | 1.9 | | | 0.0012 | | | 81 | | | 12 | | |
| | | VMP-1-8.5-111710-Dup | 11/17/2010 | 4.6 | | | <0.025 | U | | <0.0025 | U | | <0.0025 | U | | 1.9 | | | 0.00088 | | | 80 | | | 13 | | |
| | | VMP-1-8.5-020411 | 2/4/2011 | 11 | | | <0.024 | U | | 0.00031 | J | | <0.0024 | U | | 0.025 | J | | 0.56 | | | 87 | | | 1.6 | | |
| | | VMP-1-8.5-041211 | 4/12/2011 | 4.2 | | | <0.026 | U | | <0.0026 | U | | <0.0026 | U | | 0.057 | J | | 0.00019 | J | | 83 | | | 13 | | |
| | | VMP-1-8.5-080111 | 8/1/2011 | 13 | | | <0.029 | U | | 0.00067 | J | | <0.0029 | U | | 0.017 | J | | 1.8 | | | 84 | | | 1.5 | | |
| | | VMP-1-8.5-080111-Dup | 8/1/2011 | 13 | | | <0.028 | U | | 0.00065 | J | | <0.0028 | U | | 0.015 | J | | 1.8 | | | 83 | | | 1.7 | | |
| | | VMP-1-8.5-110311 | 11/3/2011 | 12 | | | <0.016 | U | | 0.002 | | | <0.0016 | U | | 0.0025 | J | | 3.6 | | | 81 | | | 2.3 | | |
| | | VMP-1-8.5-013012 | 1/30/2012 | 11 | | | <0.018 | U | | 0.00088 | J | | <0.0018 | U | | 0.0064 | J | | 1.4 | | | 84 | | | 3.5 | | |
| | | VMP-1-8.5-041612 | 4/16/2012 | 4.4 | | | <0.021 | U | | <0.0021 | U | | <0.0021 | U | | 0.037 | J | | 0.000058 | J | | 78 | | | 18 | | |
| | | VMP-1-8.5-041612-Dup | 4/16/2012 | 4.5 | | | <0.021 | U | | <0.0021 | U | | <0.0021 | U | | 0.097 | J | | 0.000068 | J | | 77 | | | 18 | | |
| | | VMP-1-8.5-071612 | 7/16/2012 | 3.3 | | | <0.025 | U | | <0.0025 | U | | <0.0025 | U | | 0.063 | J | | 0.00024 | J | | 80 | | | 17 | | |
| | | VMP-1-8.5-101112 | 10/11/2012 | 1.8 | | | <0.028 | U | | <0.0028 | U | | <0.0028 | U | | 0.023 | J | | 0.000043 | J | | 81 | | | 17 | | |
| | | [2]VMP-1-8.5-012113 | 1/21/2013 | 0.48 | | | <0.25 | U | | <0.005 | U | | <0.005 | U | | 0.99 | | | 0.021 | | | 78 | | | 21 | | |
| | | [1]VMP-1-8.5-012313-R | 1/23/2013 | 3.3 | | | <0.12 | U | | <0.0023 | U | | <0.0023 | U | | 0.0094 | J | | 0.081 | | | 81 | | | 16 | | |
| | 23.5 ft | VMP - 1 - 23.5 - 083010 | 8/30/2010 | 8.1 | | | <0.027 | U | | 0.0052 | | | <0.0027 | U | | 0.032 | J | | 9.7 | | | 78 | | | 1.6 | | |
| | | VMP-1-23.5-111810 | 11/17/2010 | 1.6 | | | <0.025 | U | | <0.0025 | U | | <0.0025 | U | | 0.86 | | | 0.000052 | J | | 78 | | | 19 | | |
| | | VMP-1-23.5-020411 | 2/4/2011 | 8.9 | | | <0.023 | U | | 0.0052 | | | <0.0023 | U | | 0.016 | J | | 12 | | | 76 | | | 1.3 | | |
| | | VMP-1-23.5-041211 | 4/12/2011 | 7.4 | | J | <0.027 | U | | 0.00072 | J | | <0.0027 | U | | 0.15 | | | 2.2 | | J | 88 | | | 2.2 | | J |
| | | VMP-1-23.5-041211-DUP | 4/12/2011 | 10 | | J | <0.024 | U | | 0.0011 | J | | <0.0024 | U | | 0.023 | J | | 2.9 | | J | 85 | | | 1.6 | | J |
| | | VMP-1-23.5-080111 | 8/1/2011 | 9.3 | | | <0.026 | U | | 0.0057 | | | <0.0026 | U | | 0.16 | | | 10 | | | 76 | | | 2.2 | | |
| | | VMP-1-23.5-110611 | 11/6/2011 | 10 | | | <0.018 | U | | 0.0029 | | | <0.0018 | U | | 0.089 | J | | 7 | | | 80 | | | 1.5 | | |
| | | VMP-1-23.5-013112 | 1/31/2012 | 9.1 | | | <0.017 | U | | 0.0023 | | | <0.0017 | U | | <0.084 | U | | 6 | | | 80 | | | 4.2 | | |
| | | VMP-1-23.5-041612 | 4/16/2012 | 12 | | | <0.019 | U | | <0.0019 | U | | <0.0019 | U | | 0.086 | J | | 0.049 | | | 84 | | | 3.6 | | |
| | | VMP-1-23.5-071612 | 7/16/2012 | 7.7 | | | <0.019 | U | | 0.0012 | J | | <0.0019 | U | | 1 | | | 2.5 | | | 80 | | | 7.6 | | |
| | | VMP-1-23.5-102412 | 10/24/2012 | 1.3 | | | <0.029 | U | | 0.00057 | J | | <0.0029 | U | | 0.14 | | | 1.3 | | | 78 | | | 19 | | |
| | | [2]VMP-1-23.5-012113 | 1/21/2013 | 0.39 | | J | <0.13 | U | UJ | <0.0027 | U | UJ | <0.0027 | U | UJ | 6.2 | | J | 0.0044 | | J | 73 | | J | 20 | | J |
| | | [1]VMP-1-23.5-012313-R | 1/23/2013 | 8.5 | | | <0.13 | U | | 0.0035 | | | <0.0026 | U | | <0.13 | U | | 7.8 | | | 76 | | | 4.8 | | |
| | 38.5 ft | VMP-1-38.5-073112 | 7/31/2012 | 1.7 | | | <0.019 | U | | <0.0019 | U | | <0.0019 | U | | <0.094 | U | | 0.000097 | J | | 83 | | | 15 | | |
| | | VMP-1-38.5-102612 | 10/26/2012 | 0.29 | | | <0.026 | U | | 0.00068 | J | | <0.0026 | U | | 1.2 | | | 1.8 | | | 76 | | | 20 | | |
| | | [2]VMP-1-38.5-012113 | 1/21/2013 | 0.13 | | J | <0.13 | U | UJ | <0.0026 | U | UJ | <0.0026 | U | UJ | 6.6 | | J | 0.0012 | | J | 73 | | J | 20 | | J |
| | | [1]VMP-1-38.5-012313-R | 1/23/2013 | 3.2 | | | <0.12 | U | | 0.0021 | J | | <0.0024 | U | | <0.12 | U | | 6 | | | 75 | | | 14 | | |
| VMP-2 | 5 ft | VMP - 2 - 5 - 083110 | 8/31/2010 | 10 | | | <0.027 | U | | 0.00086 | J | | <0.0027 | U | | 0.039 | J | | 1.6 | | | 85 | | | 3.2 | | |
| | | VMP-2-5-111610 | 11/16/2010 | 11 | | | <0.026 | U | | 0.0021 | J | | <0.0026 | U | | 0.32 | | | 3.6 | | | 80 | | | 4.6 | | |
| | | VMP-2-5-020411 | 2/4/2011 | 10 | | | <0.028 | U | | 0.00055 | J | | <0.0028 | U | | 0.013 | J | | 1.7 | | | 85 | | | 3.2 | | |
| | | VMP-2-5-041311 | 4/13/2011 | 3.3 | | | <0.028 | U | | <0.0028 | U | | <0.0028 | U | | 0.04 | J | | 0.00014 | J | | 79 | | | 18 | | |
| | | VMP-2-5-080211 | 8/2/2011 | 12 | | | <0.029 | U | | 0.0018 | J | | <0.0029 | U | | 0.0082 | J | | 2.7 | | | 83 | | | 1.5 | | |
| | | VMP-2-5-110711 | 11/7/2011 | 5.3 | | | <0.017 | U | | <0.0017 | U | | <0.0017 | U | | 0.019 | J | | 0.000043 | J | | 85 | | | 10 | | |
| | | VMP-2-5-012512 | 1/25/2012 | 12 | | | <0.016 | U | | <0.0016 | U | | <0.0016 | U | | <0.078 | U | | 0.62 | | | 84 | | | 3 | | |
| | | VMP-2-5-042512 | 4/25/2012 | 6.8 | | | <0.029 | U | | <0.0029 | U | | <0.0029 | U | | 0.12 | J | | 0.00036 | | | 80 | | | 13 | | |
| | | VMP-2-5-071612 | 7/16/2012 | 1.5 | | | <0.025 | U | | <0.0025 | U | | <0.0025 | U | | 0.025 | J | | 0.0001 | J | | 80 | | | 19 | | |
| | | VMP-2-5-102412 | 10/24/2012 | 0.2 | | | <0.029 | U | | <0.0029 | U | | <0.0029 | U | | 0.054 | J | | 0.00011 | J | | 81 | | | 19 | | |
| | | VMP-2-5-013113 | 1/31/2013 | 0.32 | | | <0.14 | U | | <0.0028 | U | | <0.0028 | U | | 0.22 | | | 0.00025 | J | | 78 | | | 21 | | |
| | 8.5 ft | VMP - 2 - 8.5 - 083110 | 8/31/2010 | 11 | | | <0.028 | U | | 0.0025 | J | | <0.0028 | U | | 0.025 | J | | 4.5 | | | 82 | | | 1.4 | | |
| | | VMP-2-8.5-111610 | 11/16/2010 | 11 | | | <0.025 | U | | 0.0032 | | | <0.0025 | U | | 0.011 | J | | 6.3 | | | 80 | | | 1.6 | | |
| | | VMP-2-8.5-020411 | 2/4/2011 | 11 | | | <0.026 | U | | 0.0011 | J | | <0.0026 | U | | 0.86 | | | 3.8 | | | 82 | | | 1.7 | | |
| | | VMP-2-8.5-041311 | 4/13/2011 | 10 | | | <0.024 | U | | <0.0024 | U | | <0.0024 | U | | 0.028 | J | | 0.0027 | | | 84 | | | 5.4 | | |
| | | VMP-2-8.5-080211 | 8/2/2011 | 9.8 | | | <0.021 | U | | 0.0029 | | | <0.0021 | U | | 0.0091 | J | | 4.8 | | | 80 | | | 4 | | |
| | | VMP-2-8.5-110711 | 11/7/2011 | 9 | | | <0.017 | U | | <0.0017 | U | | <0.0017 | U | | 0.024 | J | | 0.00007 | J | | 85 | | | 5.7 | | |
| | | VMP-2-8.5-012612 | 1/26/2012 | 12 | | | <0.016 | U | | 0.00037 | J | | <0.0016 | U | | <0.08 | U | | 1.3 | | | 85 | | | 1.5 | | J |
| | | VMP-2-8.5-012612-DUP | 1/26/2012 | 12 | | | <0.016 | U | | 0.00034 | J | | <0.0016 | U | | <0.08 | U | | 1.2 | | | 84 | | | 2.5 | | J |
| | | VMP-2-8.5-041612 | 4/16/2012 | 1.8 | | | <0.02 | U | | <0.002 | U | | <0.002 | U | | 0.015 | J | | 0.0001 | J | | 78 | | | 20 | | |
| | | VMP-2-8.5-041612-Dup | 4/16/2012 | 1.8 | | | <0.02 | U | | <0.002 | U | | <0.002 | U | | 0.017 | J | | 0.000093 | J | | 78 | | | 20 | | |
| | | VMP-2-8.5-071612 | 7/16/2012 | 6 | | | <0.028 | U | | <0.0028 | U | | <0.0028 | U | | 0.013 | J | | <0.00028 | U | | 79 | | | 15 | | |
| | | VMP-2-8.5-071612-Dup | 7/16/2012 | 6.1 | | | <0.025 | U | | <0.0025 | U | | <0.0025 | U | | 0.016 | J | | <0.00025 | U | | 79 | | | 15 | | |
| | | VMP-2-8.5-102312 | 10/23/2012 | 0.62 | | | <0.029 | U | | <0.0029 | U | | <0.0029 | U | | 0.039 | J | | 0.000092 | J | | 80 | | | 19 | | |
| | | VMP-2-8.5-020513 | 2/5/2013 | 1.8 | | | <0.15 | U | | <0.003 | U | | <0.003 | U | | <0.15 | U | | <0.0003 | U | | 79 | | | 19 | | |
| | 22 ft | VMP - 2 - 22 - 083110 | 8/31/2010 | 10 | | | <0.028 | U | | 0.004 | | | <0.0028 | U | | 0.041 | J | | 8 | | | 79 | | | 1.4 | | |
| | | VMP-2-22-111610 | 11/16/2010 | 11 | | | <0.026 | U | | 0.0038 | | | <0.0026 | U | | <0.13 | U | | 8.2 | | | 78 | | | 1.5 | | |
| | | VMP-2-22-020411 | 2/4/2011 | 11 | | | <0.024 | U | | 0.0016 | J | | <0.0024 | U | | 0.01 | J | | 5.1 | | | 82 | | | 1.5 | | |
| | | VMP-2-22-041311 | 4/13/2011 | 11 | | | <0.026 | U | | 0.0013 | J | | <0.0026 | U | | 0.049 | J | | 4.3 | | | 83 | | | 1.7 | | |
| | | VMP-2-22-080211 | 8/2/2011 | 9.7 | | | <0.028 | U | | 0.0041 | | | <0.0028 | U | | 0.021 | J | | 8.2 | | | 79 | | | 1.9 | | |
| | | VMP-2-22-110711 | 11/7/2011 | 3.7 | | | <0.017 | U | | 0.00039 | J | | <0.0017 | U | | 0.0062 | J | | 1.2 | | | 80 | | | 15 | | |
| | | VMP-2-22-012612 | 1/26/2012 | 12 | | | <0.016 | U | | 0.00073 | J | | <0.0016 | U | | 0.033 | J | | 3.1 | | | 83 | | | 2 | | |
| | | VMP-2-22-042712 | 4/27/2012 | 3.8 | | | <0.022 | U | | <0.0022 | U | | <0.0022 | U | | 0.0089 | J | | 0.000085 | J | | 82 | | | 14 | | |
| | | VMP-2-22-071612 | 7/16/2012 | 5.6 | | | <0.026 | U | | <0.0026 | U | | <0.0026 | U | | 0.031 | J | | 0.00018 | J | | 81 | | | 13 | | |
| | | VMP-2-22-102312 | 10/23/2012 | 3.7 | | | <0.029 | U | | <0.0029 | U | | <0.0029 | U | | 0.052 | J | | 0.000042 | J | | 80 | | | 16 | | |
| | | VMP-2-22-013113 | 1/31/2013 | 2.5 | | | <0.13 | U | | <0.0027 | U | | <0.0027 | U | | <0.13 | U | | 0.000019 | J | | 80 | | | 18 | | |
| | 42 ft | VMP-2-42 | 11/3/2009 | 5 | | | <0.022 | U | | 0.02 | | | <0.0022 | U | | <0.11 | U | | 64 | | | 16 | | | 0.92 | | |
| | | VMP-2-42-013113 | 1/31/2013 | 6.2 | | | <0.12 | U | | 0.012 | | | <0.0025 | U | | <0.12 | U | | 25 | | | 60 | | | 4.1 | | |

SEE LAST PAGE OF TABLE FOR NOTES

**TABLE 7**
**CUMULATIVE SUMMARY OF SOIL VAPOR ANALYTICAL RESULTS - NATURAL GASES**

| Location | Depth | Sample ID | Sample Date | Carbon Dioxide | | | Carbon Monoxide | | | Ethane | | | Ethene | | | Helium | | | Methane | | | Nitrogen | | | Oxygen | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | Result % | Lab Quals | URS Quals | Result % | Lab Quals | URS Quals | Result % | Lab Quals | URS Quals | Result % | Lab Quals | URS Quals | Result % | Lab Quals | URS Quals | Result % | Lab Quals | URS Quals | Result % | Lab Quals | URS Quals | Result % | Lab Quals | URS Quals |
| VMP-3 | 5 ft | VMP-3-5-090910 | 9/9/2010 | 12 | | | <0.021 | U | | 0.0018 | J | | <0.0021 | U | | 0.5 | | | 7.5 | | | 76 | | | 2.7 | | |
| | | VMP-3-5-112210 | 11/22/2010 | 8 | | | <0.027 | U | | 0.0028 | | | <0.0027 | U | | 1.5 | | | 10 | | | 72 | | | 6.9 | | |
| | | VMP-3-5-020911 | 2/9/2011 | 4.2 | | | <0.024 | U | | 0.00094 | J | | <0.0024 | U | | 0.57 | | | 3.9 | | | 88 | | | 2.6 | | |
| | | VMP-3-5-041411 | 4/14/2011 | 9.8 | | | <0.026 | U | | 0.0053 | | | <0.0026 | U | | 0.48 | | | 15 | | | 71 | | | 1.6 | | |
| | | VMP-3-5-080211 | 8/2/2011 | 13 | | | <0.063 | U | | <0.0063 | U | | <0.0063 | U | | 0.025 | J | | 0.00046 | J | | 79 | | | 7.8 | | |
| | | VMP-3-5-110811 | 11/8/2011 | 3.1 | | | <0.017 | U | | <0.0017 | U | | <0.0017 | U | | 0.003 | J | | <0.00017 | U | | 80 | | | 17 | | |
| | | VMP-3-5-110811-DUP | 11/8/2011 | 3 | | | <0.018 | U | | <0.0018 | U | | <0.0018 | U | | 0.0035 | J | | 0.00003 | J | | 80 | | | 17 | | |
| | | VMP-3-5-012712 | 1/27/2012 | 1.9 | | | <0.018 | U | | <0.0018 | U | | <0.0018 | U | | <0.088 | U | | 0.000052 | J | | 84 | | | 14 | | |
| | | VMP-3-5-041912 | 4/19/2012 | 1.9 | | | <0.026 | U | | <0.0026 | U | | <0.0026 | U | | 0.038 | J | | 0.000043 | J | | 79 | | | 19 | | |
| | | VMP-3-5-072712 | 7/27/2012 | 0.37 | | | <0.02 | U | | <0.002 | U | | <0.002 | U | | 0.33 | | | 0.00028 | | | 79 | | | 20 | | |
| | 10 ft | VMP-3-10 | 6/21/2010 | 7.9 | | | <0.03 | U | | 0.01 | | | <0.003 | U | | <0.15 | U | | 26 | | | 60 | | | 1.3 | | |
| | | VMP 3-10-091010 | 9/10/2010 | 9.2 | | | <0.024 | U | | 0.012 | | | <0.0024 | U | | <0.12 | U | | 28 | | | 56 | | | 1.1 | | |
| | | VMP-3-10-092010 | 9/20/2010 | 8.3 | | | <0.025 | U | | 0.011 | | | <0.0025 | U | | <0.12 | J | U | 26 | | | 58 | | | 2.9 | | |
| | | VMP-3-10-112210 | 11/22/2010 | 8.7 | | | <0.026 | U | | 0.011 | | | <0.0026 | U | | 0.044 | J | | 25 | | | 60 | | | 1.6 | | |
| | | VMP-3-10-112210-Dup | 11/22/2010 | 8.3 | | | <0.026 | U | | 0.0098 | | | <0.0026 | U | | 0.018 | J | | 23 | | | 61 | | | 2.6 | | |
| | | VMP-3-10-020811 | 2/8/2011 | 8.2 | | | <0.023 | U | | 0.0072 | | | <0.0023 | U | | 0.1 | J | | 18 | | | 68 | | | 1.8 | | |
| | | VMP-3-10-041311 | 4/13/2011 | 8.2 | | | <0.027 | U | | 0.0092 | | | <0.0027 | U | | 0.098 | J | | 22 | | | 64 | | | 1.2 | | |
| | | VMP-3-10-080311 | 8/3/2011 | 14 | | | <0.021 | U | | <0.0021 | U | | <0.0021 | U | | 0.29 | | | 0.29 | | | 78 | | | 6.9 | | |
| | | VMP-3-10-110811 | 11/8/2011 | 5 | | | <0.018 | U | | <0.0018 | U | | <0.0018 | U | | 0.051 | J | | 0.0024 | | | 85 | | | 9.8 | | |
| | | VMP-3-10-012712 | 1/27/2012 | 2 | | | <0.017 | U | | <0.0017 | U | | <0.0017 | U | | <0.084 | U | | 0.0028 | | | 81 | | | 17 | | |
| | | VMP-3-10-042012 | 4/20/2012 | 1.4 | | | <0.022 | U | | <0.0022 | U | | <0.0022 | U | | 0.14 | | | 0.000024 | J | | 80 | | | 18 | | |
| | | VMP-3-10-072312 | 7/23/2012 | 1.9 | | | <0.02 | U | | <0.002 | U | | <0.002 | U | | 0.94 | | | 0.00009 | J | | 78 | | | 19 | | |
| | | VMP-3-10-101812 | 10/18/2012 | 0.76 | | | <0.03 | U | | <0.003 | U | | <0.003 | U | | 0.024 | J | | 0.000056 | J | | 79 | | | 20 | | |
| | | VMP-3-10-020613 | 2/6/2013 | 0.34 | | | <0.14 | U | | <0.0028 | U | | <0.0028 | U | | <0.14 | U | | 0.000039 | J | | 79 | | | 21 | | |
| | 22 ft | VMP-3-22-092010 | 9/20/2010 | 8 | | | <0.024 | U | | 0.013 | | | <0.0024 | U | | <0.12 | J | U | <0.00024 | U | | 52 | | | 1.1 | | |
| | | VMP-3-22-112210 | 11/22/2010 | 8.2 | | | <0.023 | U | | 0.011 | | | <0.0023 | U | | 0.02 | J | | 28 | | | 56 | | | 1.3 | | |
| | | VMP-3-22-020811 | 2/8/2011 | 7.9 | | | <0.045 | U | | 0.013 | | | <0.0045 | U | | 0.013 | J | | 25 | | | 60 | | | 1.6 | | |
| | | VMP-3-22-041511 | 4/15/2011 | 7.8 | | | <0.025 | U | | 0.012 | | | <0.0025 | U | | 0.028 | J | | 29 | | | 56 | | | 1.2 | | |
| | | VMP-3-22-080611 | 8/6/2011 | 2.4 | | | <0.032 | U | | <0.0032 | U | | <0.0032 | U | | 0.13 | J | | 0.83 | | | 84 | | | 13 | | |
| | | VMP-3-22-110811 | 11/8/2011 | 1 | | | <0.023 | U | | <0.0023 | U | | <0.0023 | U | | <0.12 | U | | 0.0043 | | | 78 | | | 21 | | |
| | | VMP-3-22-013012 | 1/30/2012 | 6.8 | | | <0.018 | U | | <0.0018 | U | | <0.0018 | U | | 0.0072 | J | | 0.0028 | | | 82 | | | 11 | | |
| | | VMP-3-22-042012 | 4/20/2012 | 0.97 | | | <0.023 | U | | <0.0023 | U | | <0.0023 | U | | 0.016 | J | | 0.0018 | | | 79 | | | 20 | | |
| | | VMP-3-22-072312 | 7/23/2012 | 0.89 | | | <0.02 | U | | <0.002 | U | | <0.002 | U | | 0.13 | | | 0.00015 | J | | 79 | | | 20 | | |
| | | VMP-3-22-101812 | 10/18/2012 | 2.9 | | | <0.03 | U | | <0.003 | U | | <0.003 | U | | 0.02 | J | | 0.000076 | J | | 79 | | | 18 | | |
| | | VMP-3-22-020613 | 2/6/2013 | 2.6 | | | <0.14 | U | | <0.0029 | U | | <0.0029 | U | | <0.14 | U | | 0.00028 | J | | 79 | | | 18 | | |
| | 31.5 ft | VMP-3-31.5-090910 | 9/9/2010 | 4.4 | | | <0.021 | U | | 0.017 | | | <0.0021 | U | | 0.018 | J | | 47 | | | 30 | | | 1.3 | | |
| | | VMP-3-31.5-112210 | 11/22/2010 | 4.9 | | | <0.026 | U | | 0.017 | | | <0.0026 | U | | 0.024 | J | | 47 | | | 32 | | | 1.1 | | |
| | | VMP-3-31.5-020911 | 2/9/2011 | 6.4 | | | <0.02 | U | | 0.014 | | | <0.002 | U | | 0.016 | J | | 37 | | | 46 | | | 2 | | |
| | | VMP-3-31.5-041411 | 4/14/2011 | 5.7 | | | <0.025 | U | | 0.016 | | | <0.0025 | U | | 0.019 | J | | 48 | | | 33 | | | 0.86 | | |
| | | VMP-3-31.5-041411-DUP | 4/14/2011 | 5.7 | | | <0.025 | U | | 0.016 | | | <0.0025 | U | | 0.066 | J | | 48 | | | 32 | | | 1 | | |
| | | VMP-3-31.5-080211 | 8/2/2011 | 4.7 | | | <0.028 | U | | 0.017 | | | <0.0028 | U | | 0.035 | J | | 50 | | | 27 | | | 0.92 | | |
| | | VMP-3-31.5-080211-Dup | 8/2/2011 | 4.6 | | | <0.028 | U | | 0.017 | | | <0.0028 | U | | 0.041 | J | | 49 | | | 28 | | | 1.4 | | |
| | | VMP-3-31.5-110811 | 11/8/2011 | 0.37 | | | <0.018 | U | | 0.00079 | J | | <0.0018 | U | | 0.02 | J | | 2.1 | | | 77 | | | 20 | | |
| | | VMP-3-31.5-012712 | 1/27/2012 | 5.9 | | | <0.017 | U | | 0.0026 | | | <0.0017 | U | | <0.083 | U | | 11 | | | 74 | | | 6.8 | | |
| | | VMP-3-31.5-041912 | 4/19/2012 | 7.6 | | | <0.019 | U | | 0.0062 | | | <0.0019 | U | | 1.3 | | | 18 | | | 64 | | | 1.6 | | |
| | | VMP-3-31.5-041912-Dup | 4/19/2012 | 7.6 | | | <0.018 | U | | 0.0051 | | | <0.0018 | U | | 1.4 | | | 18 | | | 64 | | | 1.6 | | |
| | | VMP-3-31.5-072312 | 7/23/2012 | 7.7 | | | <0.018 | U | | 0.0018 | | | <0.0018 | U | | 0.014 | J | | 5.3 | | | 89 | | | 3 | | |
| | | VMP-3-31.5-101912 | 10/19/2012 | 2.8 | | | <0.028 | U | | <0.0028 | U | | <0.0028 | U | | <0.14 | U | | 0.21 | | | 80 | | | 17 | | |
| | | VMP-3-31.5-020713 | 2/7/2013 | 9.9 | | | <0.13 | U | | 0.0006 | J | | <0.0026 | U | | <0.13 | U | | 2.9 | | | 85 | | | 1.5 | | |
| | 39 ft | VMP-3-39-101912 | 10/19/2012 | 8.1 | | | <0.028 | U | | 0.005 | | | <0.0028 | U | | 0.058 | J | | 12 | | | 72 | | | 3.5 | | |
| | | VMP-3-39-021213 | 2/12/2013 | 9.5 | | | <0.13 | U | | 0.0023 | J | | <0.0026 | U | | <0.13 | U | | 6.7 | | | 80 | | | 1.5 | | |
| VMP-4 | 5 ft | VMP-4-5-082510 | 8/25/2010 | 13 | | | <0.029 | U | | 0.0005 | J | | <0.0029 | U | | 0.026 | J | | 1.7 | | | 83 | | | 2.1 | | |
| | | VMP-4-5-112210 | 11/22/2010 | 13 | | | <0.027 | U | | 0.0052 | | | <0.0027 | U | | 0.024 | J | | 14 | | | 69 | | | 1.9 | | |
| | | VMP-4-5-021411 | 2/14/2011 | 4.8 | | | <0.025 | U | | 0.00027 | J | | <0.0025 | U | | 2.9 | | | 0.7 | | | 79 | | | 12 | | |
| | | VMP-4-5-041911 | 4/19/2011 | 12 | | | <0.026 | U | | 0.0044 | | | <0.0026 | U | | 0.031 | J | | 12 | | | 72 | | | 1.3 | | |
| | | VMP-4-5-080311 | 8/3/2011 | 11 | | | <0.031 | U | | <0.0031 | U | | <0.0031 | U | | 0.012 | J | | 0.01 | | | 80 | | | 8.4 | | |
| | | VMP-4-5-110911 | 11/9/2011 | 0.056 | | | <0.022 | U | | <0.0022 | U | | <0.0022 | U | | 0.077 | J | | 0.0002 | J | | 78 | | | 22 | | |
| | | VMP-4-5-013012 | 1/30/2012 | 9.5 | | | <0.018 | U | | <0.0018 | U | | <0.0018 | U | | 0.058 | J | | 0.00071 | | | 88 | | | 1.9 | | |
| | | VMP-4-5-042512 | 4/25/2012 | 1.5 | | | <0.029 | U | | <0.0029 | U | | <0.0029 | U | | 0.054 | J | | 0.000042 | J | | 80 | | | 18 | | |
| | | VMP-4-5-072512 | 7/25/2012 | 2.1 | | | <0.021 | U | | <0.0021 | U | | <0.0021 | U | | 0.04 | J | | 0.00022 | | | 80 | | | 18 | | |
| | | VMP-4-5-101812 | 10/18/2012 | 0.74 | | | <0.031 | U | | <0.0031 | U | | <0.0031 | U | | 0.5 | | | 0.00012 | J | | 79 | | | 20 | | |
| | | VMP-4-5-020713 | 2/7/2013 | 0.24 | | | <0.16 | U | | <0.0033 | U | | <0.0033 | U | | <0.16 | U | | 0.00016 | J | | 79 | | | 21 | | |
| | 12 ft | VMP-4-12-082510 | 8/25/2010 | 14 | | | <0.025 | U | | 0.0039 | | | <0.0025 | U | | 0.042 | J | | 17 | | | 66 | | | 1.2 | | |
| | | VMP-4-12-112310 | 11/23/2010 | 13 | | | <0.026 | U | | 0.0036 | | | <0.0026 | U | | <0.13 | U | | 12 | | | 72 | | | 1.3 | | |
| | | VMP-4-12-021411 | 2/14/2011 | 9 | | | <0.026 | U | | 0.0016 | J | | <0.0026 | U | | 0.35 | | | 4.7 | | | 80 | | | 5.3 | | |
| | | VMP-4-12-041911 | 4/19/2011 | 11 | | | <0.025 | U | | 0.0046 | | | <0.0025 | U | | 0.035 | J | | 13 | | | 72 | | | 1.5 | | |
| | | VMP-4-12-080311 | 8/3/2011 | 15 | | | <0.029 | U | | 0.0018 | J | | <0.0029 | U | | 1 | | | 6.9 | | | 75 | | | 1.6 | | |
| | | VMP-4-12-080311-Dup | 8/3/2011 | 15 | | | <0.029 | U | | 0.0018 | J | | <0.0029 | U | | 1 | | | 6.9 | | | 75 | | | 1.7 | | |
| | | VMP-4-12-110911 | 11/9/2011 | 8.5 | | | <0.018 | U | | 0.000082 | J | | <0.0018 | U | | 4.8 | | | 0.38 | | | 79 | | | 7.2 | | |
| | | VMP-4-12-013012 | 1/30/2012 | 11 | | | <0.018 | U | | 0.00016 | J | | <0.0018 | U | | 0.11 | | | 0.47 | | | 86 | | | 1.7 | | |
| | | VMP-4-12-041812 | 4/18/2012 | 1.7 | | | <0.027 | U | | <0.0027 | U | | <0.0027 | U | | 0.027 | J | | 0.00042 | | | 73 | | | 25 | | |
| | | VMP-4-12-072312 | 7/23/2012 | 2.7 | | | <0.018 | U | | <0.0018 | U | | <0.0018 | U | | 0.84 | | | 0.00029 | | | 78 | | | 18 | | |
| | | VMP-4-12-101812 | 10/18/2012 | 0.98 | | | <0.03 | U | | <0.003 | U | | <0.003 | U | | 0.52 | | | 0.00014 | J | | 78 | | | 20 | | |
| | | VMP-4-12-101812-Dup | 10/18/2012 | 1 | | | <0.031 | U | | <0.0031 | U | | <0.0031 | U | | 0.59 | | | 0.00014 | J | | 78 | | | 20 | | |
| | | VMP-4-12-020713 | 2/7/2013 | 0.61 | | | <0.13 | U | | <0.0027 | U | | <0.0027 | U | | 0.055 | J | | 0.00036 | | | 79 | | | 20 | | |
| | | VMP-4-12-020713-DUP | 2/7/2013 | 0.61 | | | <0.14 | U | | <0.0028 | U | | <0.0028 | U | | 0.038 | J | | 0.00034 | | | 79 | | | 20 | | |
| | 23.5 ft | VMP - 4 - 23.5 - 083110 | 8/31/2010 | 6.1 | | | <0.029 | U | | 0.018 | | | <0.0029 | U | | <0.14 | J | U | 43 | | | 38 | | | 0.81 | | |
| | | VMP-4-23.5-112310 | 11/23/2010 | 6.7 | | | <0.023 | U | | 0.021 | | | <0.0023 | U | | 0.01 | J | | 50 | | | 28 | | | 0.77 | | |
| | | VMP-4-23.5-021411 | 2/14/2011 | 6.5 | | | <0.021 | U | | 0.021 | | | <0.0021 | U | | 0.022 | J | | 51 | | | 28 | | | 0.91 | | |
| | | VMP-4-23.5-042011 | 4/20/2011 | 6 | | | <0.023 | U | | 0.019 | | | <0.0023 | U | | 0.85 | | J | 46 | | | 33 | | | 1.4 | | |
| | | VMP-4-23.5-042011-DUP | 4/20/2011 | 6 | | | <0.023 | U | | 0.02 | | | <0.0023 | U | | 0.06 | J | J | 49 | | | 31 | | | 1.2 | | |
| | | VMP-4-23.5-080611 | 8/6/2011 | 5.9 | | | <0.028 | U | | 0.02 | | | <0.0028 | U | | 0.01 | J | | 45 | | | 35 | | | 1 | | |
| | | VMP-4-23.5-110911 | 11/9/2011 | 5.6 | | | <0.017 | U | | 0.0097 | | | <0.0017 | U | | 0.043 | J | | 19 | | | 64 | | | 4.8 | | |
| | | VMP-4-23.5-013012 | 1/30/2012 | 8.4 | | | <0.018 | U | | 0.0047 | | | <0.0018 | U | | 0.01 | J | | 9.2 | | | 75 | | | 1.4 | | |
| | | VMP-4-23.5-013012-DUP | 1/30/2012 | 8.5 | | | <0.018 | U | | 0.0047 | | | <0.0018 | U | | <0.088 | U | | 9.2 | | | 75 | | | 1.5 | | |
| | | VMP-4-23.5-041912 | 4/19/2012 | 12 | | | <0.02 | U | | 0.00015 | J | | <0.002 | U | | 0.015 | J | | 1.2 | | | 83 | | | 2.2 | | |
| | | VMP-4-23.5-072312 | 7/23/2012 | 10 | | | <0.019 | U | | 0.000067 | J | | 0.00022 | J | | 0.01 | J | | 0.47 | | | 84 | | | 4.6 | | |
| | | VMP-4-23.5-101812 | 10/18/2012 | 7.5 | | | <0.029 | U | | <0.0029 | U | | 0.00006 | J | | 0.031 | J | | 0.32 | | | 78 | | | 14 | | |
| | | VMP-4-23.5-020713 | 2/7/2013 | 6.2 | | | <0.13 | U | | <0.0026 | U | | <0.0026 | U | | <0.13 | U | | 0.06 | | | 80 | | | 14 | | |
| | 39 ft | VMP-4-39-042111 | 4/21/2011 | 6.1 | | | <0.025 | U | | 0.021 | | | <0.0025 | U | | 0.018 | J | | 51 | | | 29 | | | 0.9 | | |
| | | VMP-4-39-041912 | 4/19/2012 | 12 | | | <0.02 | U | | 0.0004 | J | | <0.002 | U | | 0.018 | J | | 2.1 | | | 81 | | | 2 | | |
| | | VMP-4-39-072312 | 7/23/2012 | 12 | | | <0.019 | U | | 0.00023 | J | | 0.00029 | J | | <0.096 | U | | 1.1 | | | 83 | | | 2.5 | | |
| | | VMP-4-39-101812 | 10/18/2012 | 8.8 | | | <0.03 | U | | 0.0005 | J | | 0.000087 | J | | 0.048 | | | 3.1 | | | 75 | | | 13 | | |
| | | VMP-4-39-101812-Dup | 10/18/2012 | 8.7 | | | <0.028 | U | | 0.00049 | J | | 0.000089 | J | | 0.012 | J | | 3.1 | | | 75 | | | 13 | | |
| | | VMP-4-39-020713 | 2/7/2013 | 9.1 | | | <0.13 | U | | 0.00024 | J | | 0.00012 | J | | 0.072 | J | | 1.6 | | | 76 | | | 12 | | |

SEE LAST PAGE OF TABLE FOR NOTES

**TABLE 7**
**CUMULATIVE SUMMARY OF SOIL VAPOR ANALYTICAL RESULTS - NATURAL GASES**

| Location | Depth | Sample ID | Sample Date | Carbon Dioxide | | | Carbon Monoxide | | | Ethane | | | Ethene | | | Helium | | | Methane | | | Nitrogen | | | Oxygen | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | Result % | Lab Quals | URS Quals | Result % | Lab Quals | URS Quals | Result % | Lab Quals | URS Quals | Result % | Lab Quals | URS Quals | Result % | Lab Quals | URS Quals | Result % | Lab Quals | URS Quals | Result % | Lab Quals | URS Quals | Result % | Lab Quals | URS Quals |
| VMP-5 | 5 ft | VMP-5-5-090910 | 9/9/2010 | 12 | | | <0.026 | U | | 0.0036 | | | <0.0026 | U | | 1.6 | | | 3.9 | | | 78 | | | 2.4 | | |
| | | VMP-5-5-112210 | 11/22/2010 | 13 | | | <0.026 | U | | 0.0046 | | | <0.0026 | U | | 0.01 | J | | 7 | | | 76 | | | 1.6 | | |
| | | VMP-5-5-021611 | 2/16/2011 | 8 | | | <0.025 | U | | <0.0025 | U | | <0.0025 | U | | 0.47 | | | 0.064 | | | 76 | | | 15 | | |
| | | VMP-5-5-042111 | 4/21/2011 | 2 | | | <0.026 | U | | <0.0026 | U | | <0.0026 | U | | 0.1 | J | | <0.00026 | U | | 78 | | | 20 | | |
| | | VMP-5-5-080511 | 8/5/2011 | 7.9 | | | <0.025 | U | | <0.0025 | U | | <0.0025 | U | | 0.2 | | | 0.0013 | | | 81 | | | 11 | | |
| | | VMP-5-5-111111 | 11/11/2011 | 14 | | | <0.019 | U | | <0.0019 | U | | <0.0019 | U | | 0.019 | J | | 0.0003 | | | 81 | | | 5.3 | | |
| | | VMP-5-5-013012 | 1/30/2012 | 7.7 | | | <0.019 | U | | <0.0019 | U | | <0.0019 | U | | <0.094 | U | | 0.000052 | J | | 80 | | | 12 | | |
| | | VMP-5-5-041112 | 4/11/2012 | 0.36 | | | <0.024 | U | | <0.0024 | U | | <0.0024 | U | | 1.4 | | | 0.000086 | J | | 77 | | | 21 | | |
| | | VMP-5-5-071312 | 7/13/2012 | 0.53 | | | <0.027 | U | | <0.0027 | U | | <0.0027 | U | | 0.99 | | | 0.00012 | J | | 78 | | | 20 | | |
| | | VMP-5-5-101212 | 10/12/2012 | 0.1 | | | <0.025 | U | | <0.0025 | U | | <0.0025 | U | | 1.5 | | | 0.00011 | J | | 78 | | | 20 | | |
| | | VMP-5-5-012513 | 1/25/2013 | 0.13 | | | <0.13 | U | | <0.0026 | U | | <0.0026 | U | | 0.084 | J | | 0.000058 | J | | 79 | | | 21 | | |
| | 12.5 ft | VMP-5-12.5-090910 | 9/9/2010 | 14 | | | <0.026 | U | | 0.0032 | | | <0.0026 | U | | 0.039 | J | | 3.7 | | | 79 | | | 1.3 | | |
| | | VMP-5-12.5-112310 | 11/23/2010 | 12 | | | <0.026 | U | | <0.0026 | U | | <0.0026 | U | | 0.026 | J | | 0.025 | | | 83 | | | 5.2 | | |
| | | VMP-5-12.5-021611 | 2/16/2011 | 13 | | | <0.024 | U | | 0.00031 | J | | <0.0024 | U | | 0.04 | J | | 0.68 | | | 83 | | | 2.9 | | |
| | | VMP-5-12.5-042111 | 4/21/2011 | 6.9 | | | <0.028 | U | | <0.0028 | U | | <0.0028 | U | | 0.089 | J | | 0.00015 | J | | 80 | | | 13 | | |
| | | VMP-5-12.5-080611 | 8/6/2011 | 12 | | | <0.025 | U | | 0.0034 | | | <0.0025 | U | | 0.013 | J | | 6.6 | | | 76 | | | 3.7 | | |
| | | VMP-5-12.5-111111 | 11/11/2011 | 14 | | | <0.018 | U | | <0.0018 | U | | <0.0018 | U | | 0.014 | J | | <0.00018 | U | | 81 | | | 5.1 | | |
| | | VMP-5-12.5-013012 | 1/30/2012 | 8.2 | | | <0.02 | U | | <0.002 | U | | <0.002 | U | | 0.016 | J | | 0.000036 | J | | 80 | | | 12 | | |
| | | VMP-5-12.5-041112 | 4/11/2012 | 0.64 | | | <0.022 | U | | <0.0022 | U | | <0.0022 | U | | 0.16 | | | <0.00022 | U | | 79 | | | 20 | | |
| | | VMP-5-12.5-071212 | 7/12/2012 | 0.76 | | | <0.021 | U | | <0.0021 | U | | <0.0021 | U | | 4.6 | | | 0.000079 | J | | 76 | | | 19 | | |
| | | VMP-5-12.5-101112 | 10/11/2012 | 0.16 | | | <0.064 | U | | <0.0064 | U | | <0.0064 | U | | 0.5 | | | 0.000089 | J | | 77 | | | 22 | | |
| | | VMP-5-12.5-012413 | 1/24/2013 | 0.16 | | | <0.13 | U | | <0.0026 | U | | <0.0026 | U | | <0.13 | U | | 0.000037 | J | | 79 | | | 21 | | |
| | 31 ft | VMP-5-31-090910 | 9/9/2010 | 9 | | | <0.022 | U | | 0.015 | | | <0.0022 | U | | <0.11 | J | U | 26 | | | 55 | | | 1.5 | | |
| | | VMP-5-31-112310 | 11/23/2010 | 9.2 | | | <0.024 | U | | 0.012 | | | <0.0024 | U | | 0.012 | J | | 28 | | | 53 | | | 1.2 | | |
| | | VMP-5-31-021611 | 2/16/2011 | 9.2 | | | <0.028 | U | | 0.015 | | | <0.0028 | U | | 0.022 | J | | 24 | | | 58 | | | 1.3 | | |
| | | VMP-5-31-042111 | 4/21/2011 | 9 | | | <0.026 | U | | 0.012 | | | <0.0026 | U | | 0.015 | J | | 22 | | | 60 | | | 1.6 | | |
| | | VMP-5-31-080611 | 8/6/2011 | 9.2 | | | <0.028 | U | | 0.013 | | | <0.0028 | U | | 0.01 | J | | 24 | | | 58 | | | 1.2 | | |
| | | VMP-5-31-111111 | 11/11/2011 | 10 | | | <0.018 | U | | 0.0073 | | | <0.0018 | U | | 0.39 | | | 13 | | | 71 | | | 1.4 | | |
| | | VMP-5-31-013012 | 1/30/2012 | 10 | | | <0.018 | U | | 0.0034 | | | <0.0018 | U | | <0.09 | U | | 6 | | | 80 | | | 1.8 | | |
| | | VMP-5-31-041112 | 4/11/2012 | 12 | | | <0.019 | U | | <0.0019 | U | | <0.0019 | U | | 0.096 | | | 0.02 | | | 86 | | | 1.7 | | |
| | | VMP-5-31-071212 | 7/12/2012 | 7 | | | <0.02 | U | | <0.002 | U | | <0.002 | U | | 0.062 | J | | 0.00087 | | | 79 | | | 14 | | |
| | | VMP-5-31-101112 | 10/11/2012 | 4 | | | <0.028 | U | | <0.0028 | U | | <0.0028 | U | | 0.068 | | | 0.00027 | J | | 80 | | | 16 | | |
| | | VMP-5-31-012413 | 1/24/2013 | 3.6 | | | <0.13 | U | | <0.0025 | U | | <0.0025 | U | | <0.13 | U | | 0.00051 | | | 78 | | | 18 | | |
| | 40 ft | VMP-5-40-042111 | 4/21/2011 | 8.3 | | | <0.028 | U | | 0.011 | | | <0.0028 | U | | 1.4 | | | 19 | | | 62 | | | 2.6 | | |
| | | VMP-5-40-013012 | 1/30/2012 | 11 | | | <0.019 | U | | 0.0034 | | | <0.0019 | U | | 0.81 | | | 6.1 | | | 79 | | | 1.6 | | |
| | | VMP-5-40-041212 | 4/12/2012 | 11 | | | <0.019 | U | | <0.0019 | U | | <0.0019 | U | | 0.77 | | | 0.033 | | | 84 | | | 4.6 | | |
| | | VMP-5-40-071212 | 7/12/2012 | 6.3 | | | <0.02 | U | | <0.002 | U | | <0.002 | U | | 0.097 | J | | 0.0096 | | | 78 | | | 16 | | |
| | | VMP-5-40-101112 | 10/11/2012 | 3.5 | | | <0.03 | U | | <0.003 | U | | <0.003 | U | | 0.046 | | | 0.0034 | | | 79 | | | 17 | | |
| | | VMP-5-40-012513 | 1/25/2013 | 3.6 | | | <0.13 | U | | <0.0026 | U | | <0.0026 | U | | 0.19 | | | 0.0018 | | | 78 | | | 18 | | |
| | | VMP-5-40-012513-Dup | 1/25/2013 | 3.7 | | | <0.13 | U | | <0.0025 | U | | <0.0025 | U | | 0.079 | J | | 0.0018 | | | 78 | | | 18 | | |
| VMP-6 | 5 ft | VMP-6-5-090810 | 9/8/2010 | 15 | | | <0.026 | U | | 0.00049 | J | | <0.0026 | U | | <0.13 | J | U | 1.4 | | | 82 | | | 1.4 | | |
| | | VMP-6-5-111610 | 11/16/2010 | 14 | | | <0.028 | U | | 0.0012 | J | | <0.0028 | U | | 0.074 | J | | 2.7 | | | 81 | | | 1.5 | | |
| | | VMP-6-5-020711 | 2/7/2011 | 1.7 | | | <0.024 | U | | <0.0024 | U | | <0.0024 | U | | 0.42 | | | 0.000049 | J | | 79 | | | 19 | | |
| | | VMP-6-5-040811 | 4/8/2011 | 2 | | | <0.026 | U | | <0.0026 | U | | <0.0026 | U | | 0.44 | | | 0.0011 | | | 78 | | | 19 | | |
| | | VMP-6-5-080411 | 8/4/2011 | 3.4 | | | <0.027 | U | | <0.0027 | U | | <0.0027 | U | | 0.59 | | | <0.00027 | U | | 80 | | | 16 | | |
| | | VMP-6-5-110911 | 11/9/2011 | 1.8 | | | <0.016 | U | | <0.0016 | U | | <0.0016 | U | | 0.55 | | | <0.00016 | U | | 78 | | | 20 | | |
| | | VMP-6-5-013112 | 1/31/2012 | 9.4 | | | <0.017 | U | | <0.0017 | U | | <0.0017 | U | | 0.02 | J | | 0.00097 | | | 78 | | | 12 | | |
| | | VMP-6-5-041212 | 4/12/2012 | 0.18 | | | <0.02 | U | | <0.002 | U | | <0.002 | U | | 0.17 | | | 0.000025 | J | | 79 | | | 21 | | |
| | | VMP-6-5-071612 | 7/16/2012 | 0.31 | | | <0.027 | U | | <0.0027 | U | | <0.0027 | U | | 0.12 | J | | 0.0001 | J | | 80 | | | 20 | | |
| | | VMP-6-5-101012 | 10/10/2012 | 0.096 | | | <0.028 | U | | <0.0028 | U | | <0.0028 | U | | 1.6 | | | 0.00011 | J | | 78 | | | 20 | | |
| | | VMP-6-5-021213 | 2/12/2013 | 0.086 | | | <0.12 | U | | <0.0025 | U | | <0.0025 | U | | <0.12 | U | | 0.00012 | J | | 79 | | | 21 | | |
| | 10 ft | VMP-6-10-090810 | 9/8/2010 | 15 | | | <0.024 | U | | 0.0012 | J | | <0.0024 | U | | <0.12 | J | U | 3.6 | | | 80 | | | 1.3 | | |
| | | VMP-6-10-111710 | 11/17/2010 | 9.8 | | | <0.026 | U | | <0.0026 | U | | <0.0026 | U | | 0.092 | J | | <0.00026 | U | | 82 | | | 8.5 | | |
| | | VMP-6-10-020711 | 2/7/2011 | 8.5 | | | <0.025 | U | | <0.0025 | U | | <0.0025 | U | | 0.67 | | | <0.00025 | U | | 82 | | | 9.2 | | |
| | | VMP-6-10-040811 | 4/8/2011 | 11 | | | <0.03 | U | | <0.003 | U | | <0.003 | U | | 0.04 | J | | 0.00028 | J | | 84 | | | 5 | | |
| | | VMP-6-10-080411 | 8/4/2011 | 15 | | | <0.026 | U | | 0.0011 | J | | <0.0026 | U | | 0.05 | J | | 3.2 | | | 80 | | | 1.9 | | |
| | | VMP-6-10-111011 | 11/10/2011 | 9.5 | | | <0.017 | U | | <0.0017 | U | | <0.0017 | U | | 0.068 | J | | <0.00017 | U | | 81 | | | 9.2 | | |
| | | VMP-6-10-013112 | 1/31/2012 | 15 | | | <0.018 | U | | 0.00027 | J | | <0.0018 | U | | <0.09 | U | | 0.73 | | | 82 | | | 1.6 | | |
| | | VMP-6-10-041212 | 4/12/2012 | 2 | | | <0.02 | U | | <0.002 | U | | <0.002 | U | | 0.078 | J | | <0.0002 | U | | 79 | | | 19 | | |
| | | VMP-6-10-071612 | 7/16/2012 | 1.8 | | | <0.035 | U | | <0.0035 | U | | <0.0035 | U | | 0.079 | J | | <0.00035 | U | | 78 | | | 20 | | |
| | | VMP-6-10-101112 | 10/11/2012 | 0.54 | | | <0.029 | U | | <0.0029 | U | | <0.0029 | U | | 0.078 | | | 0.000052 | J | | 79 | | | 20 | | |
| | | VMP-6-10-020513 | 2/5/2013 | 0.34 | | | <0.14 | U | | <0.0028 | U | | <0.0028 | U | | 1.7 | | | 0.000023 | J | | 78 | | | 20 | | |
| | 31.5 ft | VMP-6-31.5-090810 | 9/8/2010 | 14 | | | <0.026 | U | | 0.0032 | | | <0.0026 | U | | <0.13 | U | | 8.6 | | | 74 | | | 1.2 | | |
| | | VMP-6-31.5-111710 | 11/17/2010 | 13 | | | <0.025 | U | | 0.003 | | | <0.0025 | U | | 0.012 | J | | 7.5 | | | 76 | | | 1.4 | | |
| | | VMP-6-31.5-020711 | 2/7/2011 | 13 | | | <0.024 | U | | 0.0023 | J | | <0.0024 | U | | 0.01 | J | | 5.9 | | | 78 | | | 1.5 | | |
| | | VMP-6-31.5-041111 | 4/11/2011 | 13 | | | <0.028 | U | | 0.0021 | J | | <0.0028 | U | | 0.08 | J | | 5.2 | | | 80 | | | 1.5 | | |
| | | VMP-6-31.5-080411 | 8/4/2011 | 12 | | | <0.028 | U | | 0.0024 | J | | <0.0028 | U | | 0.015 | J | | 6.2 | | | 78 | | | 2.6 | | |
| | | VMP-6-31.5-111011 | 11/10/2011 | 14 | | | <0.017 | U | | 0.0023 | | | <0.0017 | U | | 0.0076 | J | | 5.7 | | | 78 | | | 1.4 | | |
| | | VMP-6-31.5-013112 | 1/31/2012 | 14 | | | <0.017 | U | | 0.0018 | | | <0.0017 | U | | <0.086 | U | | 4.4 | | | 79 | | | 1.8 | | |
| | | VMP-6-31.5-041212 | 4/12/2012 | 10 | | | <0.018 | U | | <0.0018 | U | | <0.0018 | U | | 0.073 | J | | 0.089 | | | 85 | | | 4.7 | | |
| | | VMP-6-31.5-071612 | 7/16/2012 | 7.5 | | | <0.024 | U | | <0.0024 | U | | <0.0024 | U | | 0.069 | J | | 0.0035 | | | 84 | | | 8.8 | | |
| | | VMP-6-31.5-101112 | 10/11/2012 | 5.5 | | | <0.028 | U | | <0.0028 | U | | <0.0028 | U | | 0.034 | | | 0.0024 | | | 82 | | | 12 | | |
| | | VMP-6-31.5-020513 | 2/5/2013 | 7.5 | | | <0.13 | U | | <0.0026 | U | | <0.0026 | U | | <0.13 | U | | 0.0028 | | | 82 | | | 10 | | |
| | 39 ft | VMP-6-39-041111 | 4/11/2011 | 12 | | | <0.027 | U | | 0.0022 | J | | <0.0027 | U | | 0.083 | J | | 5.2 | | | 77 | | | 3.9 | | |
| | | VMP-6-39-013112 | 1/31/2012 | 14 | | | <0.017 | U | | 0.0023 | | | <0.0017 | U | | <0.086 | U | | 5.1 | | | 78 | | | 1.4 | | |
| | | VMP-6-39-041212 | 4/12/2012 | 12 | | | <0.02 | U | | 0.000059 | J | | <0.002 | U | | 0.13 | | | 0.15 | | | 86 | | | 1.6 | | |
| | | VMP-6-39-071612 | 7/16/2012 | 10 | | | <0.026 | U | | <0.0026 | U | | <0.0026 | U | | 0.053 | J | | 0.0073 | | | 84 | | | 5.6 | | |
| | | VMP-6-39-071612-Dup | 7/16/2012 | 10 | | | <0.027 | U | | <0.0027 | U | | <0.0027 | U | | 0.079 | J | | 0.0074 | | | 84 | | | 5.6 | | |
| | | VMP-6-39-101112 | 10/11/2012 | 9.4 | | | <0.035 | U | | <0.0035 | U | | <0.0035 | U | | 0.12 | | | 0.0034 | | | 84 | | | 6.3 | | |
| | | VMP-6-39-020513 | 2/5/2013 | 12 | | | <0.13 | U | | <0.0026 | U | | <0.0026 | U | | <0.13 | U | | 0.00036 | | | 82 | | | 5.4 | | |

SEE LAST PAGE OF TABLE FOR NOTES

**TABLE 7**
**CUMULATIVE SUMMARY OF SOIL VAPOR ANALYTICAL RESULTS - NATURAL GASES**

| Location | Depth | Sample ID | Sample Date | Carbon Dioxide | | | Carbon Monoxide | | | Ethane | | | Ethene | | | Helium | | | Methane | | | Nitrogen | | | Oxygen | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | Result % | Lab Quals | URS Quals | Result % | Lab Quals | URS Quals | Result % | Lab Quals | URS Quals | Result % | Lab Quals | URS Quals | Result % | Lab Quals | URS Quals | Result % | Lab Quals | URS Quals | Result % | Lab Quals | URS Quals | Result % | Lab Quals | URS Quals |
| VMP-7 | 5 ft | VMP-7-5-082610 | 8/26/2010 | 2.7 | | | <0.026 | U | | <0.0026 | U | | <0.0026 | U | | 1.9 | | | 0.0002 | J | | 79 | | | 16 | | |
| | | VMP-7-5-111910 | 11/19/2010 | 14 | | | <0.024 | U | | <0.0024 | U | | <0.0024 | U | | 0.76 | | | 0.0052 | | | 80 | | | 5.1 | | |
| | | VMP-7-5-020711 | 2/7/2011 | 2.6 | | | <0.026 | U | | <0.0026 | U | | <0.0026 | U | | 0.082 | J | | 0.000048 | J | | 80 | | | 17 | | |
| | | VMP-7-5-040711 | 4/7/2011 | 5.3 | | | <0.027 | U | | <0.0027 | U | | <0.0027 | U | | 0.025 | J | | <0.00027 | U | | 80 | | | 15 | | |
| | | VMP-7-5-080211 | 8/2/2011 | 16 | | | <0.029 | U | | 0.00035 | J | | <0.0029 | U | | 0.014 | J | | 2.3 | | | 80 | | | 1.5 | | |
| | | VMP-7-5-111011 | 11/10/2011 | 13 | | | <0.022 | U | | <0.0022 | U | | <0.0022 | U | | <0.11 | U | | <0.00022 | U | | 80 | | | 6.8 | | |
| | | VMP-7-5-111011-DUP | 11/10/2011 | 12 | | | <0.016 | U | | <0.0016 | U | | <0.0016 | U | | 0.012 | J | | 0.000022 | J | | 80 | | | 7.9 | | |
| | | VMP-7-5-013112 | 1/31/2012 | 11 | | | <0.018 | U | | <0.0018 | U | | <0.0018 | U | | <0.088 | U | | 0.000017 | J | | 82 | | | 7.2 | | |
| | | VMP-7-5-041212 | 4/12/2012 | 0.59 | | | <0.019 | U | | <0.0019 | U | | <0.0019 | U | | 0.15 | | | 0.00002 | J | | 78 | | | 21 | | |
| | | VMP-7-5-073112 | 7/31/2012 | 0.14 | | | <0.02 | U | | <0.002 | U | | <0.002 | U | | 0.59 | | | 0.00022 | | | 78 | | | 21 | | |
| | | VMP-7-5-101012 | 10/10/2012 | 0.23 | | | <0.03 | U | | <0.003 | U | | <0.003 | U | | 0.032 | | | 0.00011 | J | | 80 | | | 20 | | |
| | 13.5 ft | VMP-7-13.5-082610 | 8/26/2010 | 16 | | | <0.029 | U | | 0.000083 | J | | <0.0029 | U | | 0.041 | J | | 0.57 | | | 82 | | | 1.5 | | |
| | | VMP-7-13.5-111910 | 11/19/2010 | 16 | | | <0.024 | U | | 0.00025 | J | | <0.0024 | U | | 0.014 | J | | 1.8 | | | 80 | | | 1.6 | | |
| | | VMP-7-13.5-020711 | 2/7/2011 | 9.5 | | | <0.025 | U | | <0.0025 | U | | <0.0025 | U | | 0.0099 | J | | 0.00016 | J | | 82 | | | 8.6 | | |
| | | VMP-7-13.5-040711 | 4/7/2011 | 11 | | | <0.026 | U | | <0.0026 | U | | <0.0026 | U | | 0.033 | J | | <0.00026 | U | | 81 | | | 7.6 | | |
| | | VMP-7-13.5-080311 | 8/3/2011 | 17 | | | <0.029 | U | | 0.00029 | J | | <0.0029 | U | | 0.012 | J | | 1.9 | | | 79 | | | 1.6 | | |
| | | VMP-7-13.5-111011 | 11/10/2011 | 16 | | | <0.016 | U | | <0.0016 | U | | <0.0016 | U | | 0.0033 | J | | 0.045 | | | 82 | | | 2.1 | | |
| | | VMP-7-13.5-013112 | 1/31/2012 | 15 | | | <0.018 | U | | <0.0018 | U | | <0.0018 | U | | 0.41 | | J | 0.014 | | | 83 | | | 1.6 | | |
| | | VMP-7-13.5-013112-DUP | 1/31/2012 | 15 | | | <0.018 | U | | <0.0018 | U | | <0.0018 | U | | <0.092 | U | UJ | 0.014 | | | 83 | | | 1.5 | | |
| | | VMP-7-13.5-041212 | 4/12/2012 | 0.69 | | | <0.018 | U | | <0.0018 | U | | <0.0018 | U | | 0.046 | J | | 0.000046 | J | | 78 | | | 21 | | |
| | | VMP-7-13.5-041312-DUP | 4/12/2012 | 0.8 | | | <0.019 | U | | <0.0019 | U | | <0.0019 | U | | 0.052 | J | | <0.00019 | U | | 79 | | | 20 | | |
| | | VMP-7-13.5-072012 | 7/20/2012 | 1.4 | | | <0.019 | U | | <0.0019 | U | | <0.0019 | U | | 0.034 | J | | 0.000024 | J | | 79 | | | 20 | | |
| | | VMP-7-13.5-101012 | 10/10/2012 | 0.44 | | | <0.028 | U | | <0.0028 | U | | <0.0028 | U | | 0.028 | | | 0.000039 | J | | 80 | | | 20 | | |
| | | VMP-7-13.5-021313 | 2/13/2013 | 0.23 | | | <0.14 | U | | <0.0028 | U | | <0.0028 | U | | 0.022 | J | | 0.000024 | J | | 80 | | | 20 | | |
| | 29.5 ft | VMP - 7 - 29.5 - 083110 | 8/31/2010 | 15 | | | <0.025 | U | | 0.00058 | J | | <0.0025 | U | | <0.12 | J | U | 4.1 | | | 79 | | | 1.3 | | |
| | | VMP-7-29.5-111910 | 11/19/2010 | 16 | | | <0.025 | U | | 0.00068 | J | | <0.0025 | U | | 0.011 | J | | 3.4 | | | 79 | | | 1.5 | | |
| | | VMP-7-29.5-020711 | 2/7/2011 | 15 | | | <0.026 | U | | 0.00032 | J | | <0.0026 | U | | 0.2 | | | 2 | | | 81 | | | 1.5 | | |
| | | VMP-7-29.5-040711 | 4/7/2011 | 13 | | | <0.025 | U | | 0.00022 | J | | <0.0025 | U | | 0.016 | J | | 1.4 | | | 81 | | | 4.7 | | |
| | | VMP-7-29.5-080311 | 8/3/2011 | 15 | | | <0.03 | U | | 0.00071 | J | | <0.003 | U | | 0.0071 | J | | 3.6 | | | 80 | | | 1.4 | | |
| | | VMP-7-29.5-111111 | 11/11/2011 | 16 | | | <0.018 | U | | 0.00026 | J | | <0.0018 | U | | 0.0032 | J | | 1.8 | | | 80 | | | 1.4 | | |
| | | VMP-7-29.5-020112 | 2/1/2012 | 15 | | | <0.018 | U | | 0.00016 | J | | <0.0018 | U | | <0.088 | U | | 1 | | | 82 | | | 2 | | |
| | | VMP-7-29.5-041312 | 4/13/2012 | 8.8 | | | <0.018 | U | | <0.0018 | U | | <0.0018 | U | | 0.062 | J | | 0.0019 | | | 79 | | | 12 | | |
| | | VMP-7-29.5-072012 | 7/20/2012 | 5.6 | | | <0.019 | U | | <0.0019 | U | | <0.0019 | U | | 0.014 | J | | 0.000084 | J | | 78 | | | 16 | | |
| | | VMP-7-29.5-072012-Dup | 7/20/2012 | 5.8 | | | <0.019 | U | | <0.0019 | U | | <0.0019 | U | | 0.02 | J | | 0.000092 | J | | 77 | | | 17 | | |
| | | VMP-7-29.5-101012 | 10/10/2012 | 4.5 | | | <0.029 | U | | <0.0029 | U | | <0.0029 | U | | 0.078 | | | 0.00022 | J | | 78 | | | 17 | | |
| | 38 ft | VMP-7-38-020711 | 2/7/2011 | 16 | | | <0.022 | U | | 0.00063 | J | | <0.0022 | U | | 0.0087 | J | | 2.2 | | | 80 | | | 1.5 | | |
| | | VMP-7-38-040711 | 4/7/2011 | 15 | | | <0.026 | U | | 0.00028 | J | | <0.0026 | U | | 0.013 | J | | 1.8 | | | 81 | | | 1.9 | | |
| | | VMP-7-38-020112 | 2/1/2012 | 15 | | | <0.017 | U | | 0.00017 | J | | <0.0017 | U | | <0.084 | U | | 1.1 | | | 81 | | | 2.5 | | |
| | | VMP-7-38-042512 | 4/25/2012 | 0.64 | | | <0.024 | U | | <0.0024 | U | | <0.0024 | U | | 0.034 | J | | 0.000066 | J | | 79 | | | 20 | | |
| | | VMP-7-38-042512-Dup | 4/25/2012 | 0.54 | | | <0.024 | U | | <0.0024 | U | | <0.0024 | U | | 0.04 | J | | 0.000054 | J | | 79 | | | 20 | | |
| | | VMP-7-38-101112 | 10/11/2012 | 0.17 | | | <0.027 | U | | <0.0027 | U | | <0.0027 | U | | 0.11 | | | 0.00011 | J | | 80 | | | 20 | | |
| VMP-8 | 5 ft | VMP-8-5-083010 | 8/30/2010 | 7.3 | | | <0.027 | U | | <0.0027 | U | | <0.0027 | U | | 0.039 | J | | 0.00032 | | | 80 | | | 13 | | |
| | | VMP-8-5-111810 | 11/17/2010 | 2 | | | <0.023 | U | | <0.0023 | U | | <0.0023 | U | | 0.14 | | | 0.0002 | J | | 78 | | | 20 | | |
| | | VMP-8-5-021011 | 2/10/2011 | 4 | | | <0.025 | U | | <0.0025 | U | | <0.0025 | U | | 0.018 | J | | 0.00015 | J | | 81 | | | 15 | | |
| | | VMP-8-5-040711 | 4/7/2011 | 2.9 | | | <0.028 | U | | <0.0028 | U | | <0.0028 | U | | 0.032 | J | | 0.00017 | J | | 77 | | | 20 | | |
| | | VMP-8-5-072711 | 7/27/2011 | 8.8 | | | <0.03 | U | | <0.003 | U | | <0.003 | U | | 0.018 | J | | 0.000085 | J | | 79 | | | 12 | | |
| | | VMP-8-5-110311 | 11/3/2011 | 0.61 | | | <0.017 | U | | <0.0017 | U | | <0.0017 | U | | <0.086 | U | | 0.0001 | J | | 82 | | | 17 | | |
| | | VMP-8-5-012312 | 1/23/2012 | 1.1 | | | <0.019 | U | | <0.0019 | U | | <0.0019 | U | | 0.46 | | | 0.00024 | | | 77 | | | 21 | | |
| | | VMP-8-5-041012 | 4/10/2012 | 2.1 | | | <0.024 | U | | <0.0024 | U | | <0.0024 | U | | 0.076 | J | | 0.00013 | J | | 81 | | | 17 | | |
| | | VMP-8-5-071312 | 7/13/2012 | 2.1 | | | <0.016 | U | | <0.0016 | U | | <0.0016 | U | | 22 | | | 0.00016 | | | 61 | | | 15 | | |
| | | VMP-8-5-073112 | 7/31/2012 | 3.5 | | | <0.021 | U | | <0.0021 | U | | <0.0021 | U | | 0.0093 | J | | 0.00016 | J | | 78 | | | 18 | | |
| | | VMP-8-5-100412 | 10/4/2012 | 2 | | | <0.028 | U | | <0.0028 | U | | <0.0028 | U | | 0.11 | J | | 0.000097 | J | | 79 | | | 18 | | |
| | | VMP-8-5-100412-Dup | 10/4/2012 | 2 | | | <0.026 | U | | <0.0026 | U | | <0.0026 | U | | 0.051 | J | | 0.000099 | J | | 80 | | | 18 | | |
| | | VMP-8-5-012413 | 1/24/2013 | 0.33 | | | <0.13 | U | | <0.0027 | U | | <0.0027 | U | | <0.13 | U | | 0.00019 | J | | 79 | | | 21 | | |
| | 9.5 ft | VMP-8-9.5-083010 | 8/30/2010 | 8.4 | | | <0.051 | U | | <0.0051 | U | | <0.0051 | U | | <0.25 | J | U | 0.000048 | J | | 80 | | | 12 | | |
| | | VMP-8-9.5-083010-DUP | 8/30/2010 | 9.1 | | | <0.025 | U | | <0.0025 | U | | <0.0025 | U | | 0.024 | J | | 0.000026 | J | | 81 | | | 9.8 | | |
| | | VMP-8-9.5-111810 | 11/17/2010 | 8.5 | | | <0.024 | U | | <0.0024 | U | | <0.0024 | U | | 0.026 | J | | 0.000053 | J | | 78 | | | 13 | | |
| | | VMP-8-9.5-021011 | 2/10/2011 | 7.9 | | | <0.025 | U | | <0.0025 | U | | <0.0025 | U | | 0.015 | J | | <0.00025 | U | | 79 | | | 13 | | |
| | | VMP-8-9.5-040711 | 4/7/2011 | 7.4 | | | <0.028 | U | | <0.0028 | U | | <0.0028 | U | | 0.043 | J | | <0.00028 | U | | 79 | | | 14 | | |
| | | VMP-8-9.5-072711 | 7/27/2011 | 7.2 | | | <0.04 | U | | <0.004 | U | | <0.004 | U | | 0.0098 | J | | <0.0004 | U | | 78 | | | 15 | | |
| | | VMP-8-9.5-110311 | 11/3/2011 | 6.5 | | | <0.017 | U | | <0.0017 | U | | <0.0017 | U | | 0.0035 | J | | 0.000027 | J | | 79 | | | 14 | | |
| | | VMP-8-9.5-012312 | 1/23/2012 | 6.2 | | | <0.018 | U | | <0.0018 | U | | <0.0018 | U | | <0.092 | U | | 0.000047 | J | | 78 | | | 16 | | |
| | | VMP-8-9.5-041012 | 4/10/2012 | 5.3 | | | <0.024 | U | | <0.0024 | U | | <0.0024 | U | | 0.06 | J | | 0.000058 | J | | 80 | | | 15 | | |
| | | VMP-8-9.5-071312 | 7/13/2012 | 5.8 | | | <0.019 | U | | <0.0019 | U | | <0.0019 | U | | 0.092 | J | | 0.000028 | J | | 78 | | | 16 | | |
| | | VMP-8-9.5-071312-Dup | 7/13/2012 | 5.6 | | | <0.018 | U | | <0.0018 | U | | <0.0018 | U | | 0.026 | J | | 0.000039 | J | | 78 | | | 16 | | |
| | | VMP-8-9.5-100412 | 10/4/2012 | 4.4 | | | <0.03 | U | | <0.003 | U | | <0.003 | U | | 0.032 | J | | 0.00016 | J | | 80 | | | 16 | | |
| | | VMP-8-9.5-012413 | 1/24/2013 | 3.4 | | | <0.13 | U | | <0.0025 | U | | <0.0025 | U | | 0.051 | J | | 0.000041 | J | | 78 | | | 18 | | |
| | | VMP-8-9.5-012413-Dup | 1/24/2013 | 3.4 | | | <0.13 | U | | <0.0027 | U | | <0.0027 | U | | 0.054 | J | | 0.000043 | J | | 78 | | | 18 | | |
| | 23.5 ft | VMP-8-23.5-083010 | 8/30/2010 | 9.3 | | | <0.026 | U | | <0.0026 | U | | <0.0026 | U | | 0.036 | J | | 0.000032 | J | | 81 | | | 9.9 | | |
| | | VMP-8-23.5-111910 | 11/19/2010 | 9.9 | | | <0.025 | U | | <0.0025 | U | | <0.0025 | U | | 0.028 | J | | 0.000069 | J | | 79 | | | 11 | | |
| | | VMP-8-23.5-021011 | 2/10/2011 | 9.3 | | | <0.027 | U | | <0.0027 | U | | <0.0027 | U | | 0.02 | J | | <0.00027 | U | | 79 | | | 12 | | |
| | | VMP-8-23.5-040711 | 4/7/2011 | 8.3 | | | <0.025 | U | | <0.0025 | U | | <0.0025 | U | | 0.029 | J | | <0.00025 | U | | 79 | | | 13 | | |
| | | VMP-8-23.5-040711-DUP | 4/7/2011 | 11 | | | <0.06 | U | | <0.006 | U | | <0.006 | U | | 1.2 | | | <0.0006 | U | | 72 | | | 16 | | |
| | | VMP-8-23.5-081011 | 8/10/2011 | 8.8 | | | <0.026 | U | | <0.0026 | U | | <0.0026 | U | | 0.0086 | J | | <0.00026 | U | | 79 | | | 12 | | |
| | | VMP-8-23.5-110611 | 11/6/2011 | 9.4 | | | <0.019 | U | | <0.0019 | U | | <0.0019 | U | | 0.006 | J | | 0.000096 | J | | 68 | | | 22 | | |
| | | VMP-8-23.5-012312 | 1/23/2012 | 7.6 | | | <0.019 | U | | <0.0019 | U | | <0.0019 | U | | <0.096 | U | | 0.00029 | | | 77 | | | 15 | | |
| | | VMP-8-23.5-041012 | 4/10/2012 | 6.3 | | | <0.024 | U | | <0.0024 | U | | <0.0024 | U | | 0.13 | | | 0.000097 | J | | 80 | | | 14 | | |
| | | VMP-8-23.5-071312 | 7/13/2012 | 6.3 | | | <0.021 | U | | <0.0021 | U | | <0.0021 | U | | 0.048 | J | | 0.000046 | J | | 79 | | | 15 | | |
| | | VMP-8-23.5-100412 | 10/4/2012 | 5.9 | | | <0.029 | U | | <0.0029 | U | | <0.0029 | U | | 0.14 | J | | 0.00038 | | | 78 | | | 16 | | |
| | | VMP-8-23.5-012413 | 1/24/2013 | 4.8 | | | <0.14 | U | | <0.0029 | U | | <0.0029 | U | | <0.14 | U | | 0.000056 | J | | 78 | | | 17 | | |

**TABLE 7**
**CUMULATIVE SUMMARY OF SOIL VAPOR ANALYTICAL RESULTS - NATURAL GASES**

| Location | Depth | Sample ID | Sample Date | Carbon Dioxide | | | Carbon Monoxide | | | Ethane | | | Ethene | | | Helium | | | Methane | | | Nitrogen | | | Oxygen | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | Result % | Lab Quals | URS Quals | Result % | Lab Quals | URS Quals | Result % | Lab Quals | URS Quals | Result % | Lab Quals | URS Quals | Result % | Lab Quals | URS Quals | Result % | Lab Quals | URS Quals | Result % | Lab Quals | URS Quals | Result % | Lab Quals | URS Quals |
| VMP-9 | 5 ft | VMP-9-5-082610 | 8/26/2010 | 10 | | | <0.023 | U | | <0.0023 | U | | <0.0023 | U | | 0.012 | J | | 0.000061 | J | | 81 | | | 9.1 | | |
| | | VMP-9-5-111910 | 11/19/2010 | 14 | | | <0.024 | U | | <0.0024 | U | | <0.0024 | U | | 0.042 | J | | 0.00036 | | | 82 | | | 3.8 | | |
| | | VMP-9-5-020811 | 2/8/2011 | 1.5 | | | <0.022 | U | | <0.0022 | U | | <0.0022 | U | | 0.01 | J | | <0.00022 | U | | 78 | | | 20 | | |
| | | VMP-9-5-040611 | 4/6/2011 | 10 | | | <0.061 | U | | <0.0061 | U | | <0.0061 | U | | 0.034 | J | | <0.00061 | U | | 83 | | | 6.8 | | |
| | | VMP-9-5-080211 | 8/2/2011 | 15 | | | <0.03 | U | | <0.003 | U | | <0.003 | U | | 0.015 | J | | 0.24 | | | 83 | | | 1.8 | | |
| | | VMP-9-5-110411 | 11/4/2011 | 3 | | | <0.018 | U | | <0.0018 | U | | <0.0018 | U | | 0.0093 | J | | 0.000035 | J | | 80 | | | 17 | | |
| | | VMP-9-5-012612 | 1/26/2012 | 12 | | | <0.015 | U | | <0.0015 | U | | <0.0015 | U | | <0.074 | U | | 0.00017 | | | 82 | | | 6 | | |
| | | VMP-9-5-041112 | 4/11/2012 | 0.34 | | | <0.023 | U | | <0.0023 | U | | <0.0023 | U | | 0.22 | | | 0.00009 | J | | 80 | | | 19 | | |
| | | VMP-9-5-071312 | 7/13/2012 | 0.045 | | | <0.019 | U | | <0.0019 | U | | <0.0019 | U | | 0.014 | J | | 0.00022 | | | 79 | | | 21 | | |
| | | VMP-9-5-101012 | 10/10/2012 | 0.21 | | | <0.029 | U | | <0.0029 | U | | <0.0029 | U | | 0.089 | | | 0.000099 | J | | 80 | | | 20 | | |
| | | [3]VMP-9-5-012513 | 1/25/2013 | 0.16 | J | J | <0.21 | U | UJ | 0.00013 | J | J | <0.0042 | U | UJ | 0.28 | J | J | 0.00029 | J | J | 66 | J | J | 34 | J | J |
| | | VMP-9-5-021513 | 2/15/2013 | 0.16 | | | <0.14 | U | | <0.0028 | U | | <0.0028 | U | | <0.14 | U | | 0.00013 | J | | 79 | | | 21 | | |
| | 11.5 ft | VMP-9-11.5-082610 | 8/26/2010 | 15 | | | <0.026 | U | | 0.00015 | J | | <0.0026 | U | | 0.042 | J | | 1.8 | | | 82 | | | 1.4 | | |
| | | VMP-9-11.5-111910 | 11/19/2010 | 16 | | | <0.027 | U | | <0.0027 | U | | <0.0027 | U | | 0.021 | J | | 1.5 | | | 81 | | | 1.6 | | |
| | | VMP-9-11.5-020911 | 2/9/2011 | 10 | | | <0.027 | U | | <0.0027 | U | | <0.0027 | U | | 0.024 | J | | <0.00027 | U | | 83 | | | 7 | | |
| | | VMP-9-11.5-020911-DUP | 2/9/2011 | 9.9 | | | <0.021 | U | | <0.0021 | U | | <0.0021 | U | | 0.0097 | J | | <0.00021 | U | | 82 | | | 8.4 | | |
| | | VMP-9-11.5-040611 | 4/6/2011 | 13 | | | <0.059 | U | | <0.0059 | U | | <0.0059 | U | | 0.035 | J | | 0.0025 | | | 84 | | | 3.2 | | |
| | | VMP-9-11.5-080211 | 8/2/2011 | 15 | | | <0.028 | U | | 0.0002 | J | | <0.0028 | U | | 0.013 | J | | 3 | | | 80 | | | 1.4 | | |
| | | VMP-9-11.5-110411 | 11/4/2011 | 8.2 | | | <0.018 | U | | <0.0018 | U | | <0.0018 | U | | 0.0058 | J | | 0.000029 | J | | 80 | | | 12 | | |
| | | VMP-9-11.5-012612 | 1/26/2012 | 14 | | | <0.016 | U | | <0.0016 | U | | <0.0016 | U | | 0.048 | J | | 0.00003 | J | | 83 | | | 2.8 | | |
| | | VMP-9-11.5-041112 | 4/11/2012 | 1 | | | <0.023 | U | | <0.0023 | U | | <0.0023 | U | | 0.43 | | | <0.00023 | U | | 80 | | | 19 | | |
| | | VMP-9-11.5-071312 | 7/13/2012 | 1.4 | | | <0.021 | U | | <0.0021 | U | | <0.0021 | U | | 0.14 | | | <0.00021 | U | | 79 | | | 19 | | |
| | | VMP-9-11.5-101012 | 10/10/2012 | 0.43 | | | <0.036 | U | | <0.0036 | U | | <0.0036 | U | | 0.24 | | | 0.000051 | J | | 79 | | | 20 | | |
| | | VMP-9-11.5-012513 | 1/25/2013 | 0.3 | | | <0.12 | U | | <0.0023 | U | | <0.0023 | U | | <0.12 | U | | 0.000037 | J | | 80 | | | 20 | | |
| | | VMP-9-11.5-012513-DUP | 1/25/2013 | 0.31 | | | <0.13 | U | | <0.0025 | U | | <0.0025 | U | | 0.027 | J | | 0.00006 | J | | 80 | | | 20 | | |
| | 25.5 ft | VMP-9-25.5-082610 | 8/26/2010 | 14 | | | <0.024 | U | | 0.00042 | J | | <0.0024 | U | | 0.012 | J | J | 4.3 | | | 80 | | | 1.7 | | |
| | | VMP-9-25.5-082610-DUP | 8/26/2010 | 14 | | | <0.026 | U | | 0.0004 | J | | <0.0026 | U | | 0.04 | J | J | 4.3 | | | 80 | | | 1.5 | | |
| | | VMP-9-25.5-111910 | 11/19/2010 | 15 | | | <0.028 | U | | 0.0002 | J | | <0.0028 | U | | <0.14 | U | | 3 | | | 80 | | | 1.6 | | |
| | | VMP-9-25.5-020911 | 2/9/2011 | 15 | | | <0.025 | U | | <0.0025 | U | | <0.0025 | U | | 0.011 | J | | 0.98 | | | 83 | | | 1.3 | | |
| | | VMP-9-25.5-040811 | 4/8/2011 | 12 | | | <0.026 | U | | <0.0026 | U | | <0.0026 | U | | 9.2 | | | 0.64 | | | 75 | | | 3.3 | | |
| | | VMP-9-25.5-080211 | 8/2/2011 | 14 | | | <0.028 | U | | 0.00024 | J | | <0.0028 | U | | 0.012 | J | | 3.5 | | | 81 | | | 1.5 | | |
| | | VMP-9-25.5-110711 | 11/7/2011 | 16 | | | <0.019 | U | | 0.000059 | J | | <0.0019 | U | | 0.0034 | J | | 1.1 | | | 81 | | | 1.9 | | |
| | | VMP-9-25.5-110711-DUP | 11/7/2011 | 15 | | | <0.016 | U | | 0.000055 | J | | <0.0016 | U | | 0.0058 | J | | 1 | | | 82 | | | 1.6 | | |
| | | VMP-9-25.5-012612 | 1/26/2012 | 15 | | | <0.016 | U | | <0.0016 | U | | <0.0016 | U | | <0.08 | U | | 0.43 | | | 83 | | | 1.5 | | |
| | | VMP-9-25.5-041112 | 4/11/2012 | 3.2 | | | <0.023 | U | | <0.0023 | U | | <0.0023 | U | | 0.082 | J | | <0.00023 | U | | 80 | | | 17 | | |
| | | VMP-9-25.5-071312 | 7/13/2012 | 3 | | | <0.026 | U | | <0.0026 | U | | <0.0026 | U | | 0.088 | J | | <0.00026 | U | | 78 | | | 19 | | |
| | | VMP-9-25.5-071312-Dup | 7/13/2012 | 3 | | | <0.026 | U | | <0.0026 | U | | <0.0026 | U | | 0.076 | J | | <0.00026 | U | | 78 | | | 19 | | |
| | | VMP-9-25.5-101012 | 10/10/2012 | 1.6 | | | <0.026 | U | | <0.0026 | U | | <0.0026 | U | | 0.033 | | | <0.00026 | U | | 79 | | | 19 | | |
| | | VMP-9-25.5-013013 | 1/30/2013 | 1.3 | | | <0.14 | U | | 0.000062 | J | | <0.0028 | U | | <0.14 | U | | <0.00028 | U | | 79 | | | 20 | | |
| | 38.5 ft | VMP-9-38.5-020911 | 2/9/2011 | 16 | | | <0.021 | U | | 0.00011 | J | | <0.0021 | U | | <0.1 | U | | 1.4 | | | 81 | | | 1.5 | | |
| | | VMP-9-38.5-040811 | 4/8/2011 | 15 | | | <0.028 | U | | <0.0028 | U | | <0.0028 | U | | 0.11 | J | | 1.1 | | | 82 | | | 1.6 | | |
| | | VMP-9-38.5-012612 | 1/26/2012 | 15 | | | <0.017 | U | | <0.0017 | U | | <0.0017 | U | | <0.084 | U | | 0.47 | | | 83 | | | 1.7 | | |
| | | VMP-9-38.5-041112 | 4/11/2012 | 7.8 | | | <0.021 | U | | <0.0021 | U | | <0.0021 | U | | 0.036 | J | | 0.00094 | | | 78 | | | 14 | | |
| | | VMP-9-38.5-071312 | 7/13/2012 | 5.5 | | | <0.028 | U | | <0.0028 | U | | <0.0028 | U | | 0.1 | J | | 0.00012 | J | | 78 | | | 16 | | |
| | | VMP-9-38.5-101012 | 10/10/2012 | 5.9 | | | <0.028 | U | | <0.0028 | U | | <0.0028 | U | | 0.024 | J | | 0.0054 | | | 80 | | | 14 | | |
| | | VMP-9-38.5-013013 | 1/30/2013 | 5.9 | | | <0.14 | U | | 0.000066 | J | | <0.0028 | U | | <0.14 | U | | 0.00013 | J | | 79 | | | 15 | | |
| VMP-10 | 5 ft | VMP-10-5-090710 | 9/7/2010 | 5.2 | | | <0.026 | U | | <0.0026 | U | | <0.0026 | U | | <0.13 | J | U | 0.00017 | J | | 80 | | | 15 | | |
| | | VMP-10-5-111810 | 11/17/2010 | 3.2 | | | <0.024 | U | | <0.0024 | U | | <0.0024 | U | | 0.024 | J | | <0.00024 | U | | 79 | | | 18 | | |
| | | VMP-10-5-021011 | 2/10/2011 | 3.8 | | | <0.024 | U | | <0.0024 | U | | <0.0024 | U | | 0.0094 | J | | 0.00014 | J | | 79 | | | 17 | | |
| | | VMP-10-5-040511 | 4/5/2011 | 0.38 | | | <0.022 | U | | <0.0022 | U | | <0.0022 | U | | 0.29 | | | 0.00017 | J | | 78 | | | 21 | | |
| | | VMP-10-5-07/2911 | 7/29/2011 | 3.8 | | | <0.052 | U | | <0.0052 | U | | <0.0052 | U | | 0.16 | J | | <0.00052 | U | | 79 | | | 17 | | |
| | | VMP-10-5-110411 | 11/4/2011 | 2.5 | | | <0.014 | U | | <0.0014 | U | | <0.0014 | U | | 0.042 | J | | 0.000056 | J | | 78 | | | 19 | | |
| | | VMP-10-5-012512 | 1/26/2012 | 3.3 | | | <0.018 | U | | <0.0018 | U | | <0.0018 | U | | 0.046 | J | | <0.00018 | U | | 79 | | | 18 | | |
| | | VMP-10-5-041212 | 4/12/2012 | 2.8 | | | <0.019 | U | | <0.0019 | U | | <0.0019 | U | | 0.071 | J | | 0.000025 | J | | 79 | | | 18 | | |
| | | VMP-10-5-071312 | 7/13/2012 | 2.2 | | | <0.026 | U | | <0.0026 | U | | <0.0026 | U | | 0.059 | J | | 0.00003 | J | | 79 | | | 19 | | |
| | | VMP-10-5-101612 | 10/16/2012 | 2.1 | | | <0.03 | U | | <0.003 | U | | <0.003 | U | | 0.047 | J | | 0.00032 | | | 80 | | | 18 | | |
| | | VMP-10-5-012913 | 1/29/2013 | 0.11 | | | <0.14 | U | | <0.0028 | U | | <0.0028 | U | | 0.1 | J | | 0.0001 | J | | 79 | | | 21 | | |
| | | VMP-10-5-012913-DUP | 1/29/2013 | 0.1 | | | <0.16 | U | | <0.0031 | U | | <0.0031 | U | | <0.16 | U | | 0.0001 | J | | 80 | | | 20 | | |
| | 10 ft | VMP-10-10-090710 | 9/7/2010 | 7.6 | | | <0.026 | U | | <0.0026 | U | | <0.0026 | U | | <0.13 | J | U | 0.00013 | J | | 79 | | | 13 | | |
| | | VMP-10-10-111810 | 11/17/2010 | 5.3 | | | <0.026 | U | | <0.0026 | U | | <0.0026 | U | | 0.0082 | J | | <0.00026 | U | | 79 | | | 16 | | |
| | | VMP-10-10-021111 | 2/11/2011 | 4 | | | <0.02 | U | | <0.002 | U | | <0.002 | U | | 0.016 | J | | 0.00009 | J | | 79 | | | 17 | | |
| | | VMP-10-10-040611 | 4/6/2011 | 2.2 | | | <0.026 | U | | <0.0026 | U | | <0.0026 | U | | 0.026 | J | | 0.000048 | J | | 79 | | | 19 | | |
| | | VMP-10-10-072911 | 7/29/2011 | 5.5 | | | <0.028 | U | | <0.0028 | U | | <0.0028 | U | | 0.6 | | | <0.00028 | U | | 80 | | | 14 | | |
| | | VMP-10-10-110411 | 11/4/2011 | 4.2 | | | <0.018 | U | | <0.0018 | U | | <0.0018 | U | | 0.016 | J | | <0.00018 | U | | 80 | | | 16 | | |
| | | VMP-10-10-110411-DUP | 11/4/2011 | 4.3 | | | <0.018 | U | | <0.0018 | U | | <0.0018 | U | | 0.016 | J | | <0.00018 | U | | 80 | | | 16 | | |
| | | VMP-10-10-012512 | 1/26/2012 | 4 | | | <0.018 | U | | <0.0018 | U | | <0.0018 | U | | <0.088 | U | | <0.00018 | U | | 79 | | | 17 | | |
| | | VMP-10-10-012512-DUP | 1/26/2012 | 4.1 | | | <0.018 | U | | <0.0018 | U | | <0.0018 | U | | <0.092 | U | | 0.00011 | J | | 79 | | | 17 | | |
| | | VMP-10-10-041112 | 4/11/2012 | 3.9 | | | <0.024 | U | | <0.0024 | U | | <0.0024 | U | | 0.067 | J | | 0.000046 | J | | 80 | | | 16 | | |
| | | VMP-10-10-071312 | 7/13/2012 | 3.2 | | | <0.025 | U | | <0.0025 | U | | <0.0025 | U | | 0.11 | J | | <0.00025 | U | | 80 | | | 17 | | |
| | | VMP-10-10-101612 | 10/16/2012 | 2.7 | | | <0.032 | U | | <0.0032 | U | | <0.0032 | U | | 0.049 | J | | 0.00026 | J | | 80 | | | 17 | | |
| | | VMP-10-10-012913 | 1/29/2013 | 0.15 | | | <0.13 | U | | <0.0025 | U | | <0.0025 | U | | <0.13 | U | | 0.000034 | J | | 80 | | | 20 | | |
| | 20 ft | VMP-10-20-090710 | 9/7/2010 | 0.22 | | | <0.056 | U | | <0.0056 | U | | <0.0056 | U | | <0.28 | J | U | 0.00019 | J | | 80 | | | 20 | | |
| | | VMP-10-20-090710-DUP | 9/7/2010 | 0.16 | | | <0.052 | U | | <0.0052 | U | | <0.0052 | U | | 0.076 | J | | 0.00025 | J | | 74 | | | 26 | | |
| | | VMP-10-20-111810 | 11/17/2010 | 8.3 | | | <0.049 | U | | <0.0049 | U | | <0.0049 | U | | 0.0098 | J | | <0.00049 | U | | 79 | | | 13 | | |
| | | VMP-10-20-111810-Dup | 11/17/2010 | 7.4 | | | <0.025 | U | | <0.0025 | U | | <0.0025 | U | | 0.0043 | J | | 0.000045 | J | | 78 | | | 14 | | |
| | | VMP-10-20-021111 | 2/11/2011 | 6.4 | | | <0.051 | U | | <0.0051 | U | | <0.0051 | U | | 0.012 | J | | <0.00051 | U | | 78 | | | 16 | | |
| | | VMP-10-20-040611 | 4/6/2011 | 0.58 | | | <0.029 | U | | <0.0029 | U | | <0.0029 | U | | 0.028 | J | | 0.00019 | J | | 78 | | | 21 | | |
| | | VMP-10-20-072911 | 7/29/2011 | 7.1 | | | <0.027 | U | | <0.0027 | U | | <0.0027 | U | | <0.14 | U | | <0.00027 | U | | 80 | | | 13 | | |
| | | VMP-10-20-110411 | 11/4/2011 | 4.6 | | | <0.018 | U | | <0.0018 | U | | <0.0018 | U | | 0.062 | J | | 0.000073 | J | | 79 | | | 16 | | |
| | | VMP-10-20-012612 | 1/26/2012 | 5.6 | | | <0.017 | U | | <0.0017 | U | | <0.0017 | U | | <0.084 | U | | 0.000016 | J | | 79 | | | 15 | | |
| | | VMP-10-20-041212 | 4/12/2012 | 5.1 | | | <0.019 | U | | <0.0019 | U | | <0.0019 | U | | 0.065 | J | | 0.000037 | J | | 80 | | | 15 | | |
| | | VMP-10-20-071612 | 7/16/2012 | 5 | | | <0.024 | U | | <0.0024 | U | | <0.0024 | U | | 0.09 | J | | <0.00024 | U | | 79 | | | 16 | | |
| | | VMP-10-20-101612 | 10/16/2012 | 4.3 | | | <0.032 | U | | <0.0032 | U | | <0.0032 | U | | 0.057 | J | | 0.000026 | J | | 81 | | | 15 | | |
| | | VMP-10-20-012913 | 1/29/2013 | 0.45 | | | <0.29 | U | | <0.0058 | U | | <0.0058 | U | | <0.29 | U | | <0.00058 | U | | 78 | | | 21 | | |
| | 30 ft | VMP-10-30-041212 | 4/12/2012 | 6.1 | | | <0.032 | U | | <0.0032 | U | | <0.0032 | U | | 0.085 | J | | 0.00092 | | | 80 | | | 14 | | |
| | | VMP-10-30-071612 | 7/16/2012 | 5.9 | | | <0.023 | U | | <0.0023 | U | | <0.0023 | U | | 0.053 | J | | 0.00026 | | | 79 | | | 15 | | |
| | | VMP-10-30-101612 | 10/16/2012 | 5.1 | | | <0.03 | U | | <0.003 | U | | <0.003 | U | | 0.04 | J | | 0.000095 | J | | 80 | | | 15 | | |
| | | VMP-10-30-012913 | 1/29/2013 | 2.2 | | | <0.15 | U | | <0.003 | U | | <0.003 | U | | <0.15 | U | | 0.000055 | J | | 79 | | | 19 | | |

SEE LAST PAGE OF TABLE FOR NOTES

**TABLE 7**
**CUMULATIVE SUMMARY OF SOIL VAPOR ANALYTICAL RESULTS - NATURAL GASES**

| Location | Depth | Sample ID | Sample Date | Carbon Dioxide | | | Carbon Monoxide | | | Ethane | | | Ethene | | | Helium | | | Methane | | | Nitrogen | | | Oxygen | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | Result % | Lab Quals | URS Quals | Result % | Lab Quals | URS Quals | Result % | Lab Quals | URS Quals | Result % | Lab Quals | URS Quals | Result % | Lab Quals | URS Quals | Result % | Lab Quals | URS Quals | Result % | Lab Quals | URS Quals | Result % | Lab Quals | URS Quals |
| VMP-11 | 5 ft | VMP-11-5-090710 | 9/7/2010 | 8 | | | <0.025 | U | | <0.0025 | U | | <0.0025 | U | | <0.12 | J | U | 0.00072 | | | 80 | | | 12 | | |
| | | VMP-11-5-112210 | 11/22/2010 | 10 | | | <0.026 | U | | <0.0026 | U | | <0.0026 | U | | 0.016 | J | | 0.000096 | J | | 80 | | | 9.4 | | |
| | | VMP-11-5-021111 | 2/11/2011 | 8.5 | | | <0.023 | U | | <0.0023 | U | | <0.0023 | U | | 0.018 | J | | 0.00004 | J | | 80 | | | 11 | | |
| | | VMP-11-5-040611 | 4/6/2011 | 8 | | | <0.027 | U | | <0.0027 | U | | <0.0027 | U | | 0.022 | J | | 0.002 | | | 80 | | | 12 | | |
| | | VMP-11-5-080711 | 8/7/2011 | 7.1 | | | <0.03 | U | | <0.003 | U | | <0.003 | U | | 0.01 | J | | <0.0003 | U | | 79 | | | 14 | | |
| | | VMP-11-5-111111 | 11/11/2011 | 11 | | | <0.018 | U | | <0.0018 | U | | <0.0018 | U | | 0.65 | | | 0.000078 | J | | 80 | | | 8.3 | | |
| | | VMP-11-5-012612 | 1/26/2012 | 9.6 | | | <0.018 | U | | <0.0018 | U | | <0.0018 | U | | <0.088 | U | | 0.000049 | J | | 81 | | | 9.5 | | |
| | | VMP-11-5-041912 | 4/19/2012 | 3.4 | | | <0.026 | U | | <0.0026 | U | | <0.0026 | U | | 0.052 | J | | 0.00024 | J | | 73 | | | 24 | | |
| | | VMP-11-5-071912 | 7/16/2012 | 2.4 | | | <0.034 | U | | <0.0034 | U | | <0.0034 | U | | 0.075 | J | | 0.000057 | J | | 78 | | | 19 | | |
| | | VMP-11-5-101612 | 10/16/2012 | 4.2 | | | <0.028 | U | | <0.0028 | U | | <0.0028 | U | | 0.028 | J | | 0.000053 | J | | 81 | | | 15 | | |
| | | VMP-11-5-012913 | 1/29/2013 | 0.47 | | | <0.29 | U | | 0.00016 | J | | <0.0058 | U | | 0.74 | | | 0.000098 | J | | 77 | | | 22 | | |
| | 8 ft | VMP-11-8-080910 | 9/8/2010 | 7.8 | | | <0.053 | U | | <0.0053 | U | | <0.0053 | U | | 0.018 | J | | 0.0011 | | | 76 | | | 16 | | |
| | | VMP-11-8-112210 | 11/22/2010 | 11 | | | <0.026 | U | | <0.0026 | U | | <0.0026 | U | | 0.031 | J | | <0.00026 | U | | 80 | | | 8.8 | | |
| | | VMP-11-8-021111 | 2/11/2011 | 9.4 | | | <0.025 | U | | <0.0025 | U | | <0.0025 | U | | <0.12 | U | | <0.00025 | U | | 81 | | | 9.7 | | |
| | | VMP-11-8-021111-DUP | 2/11/2011 | 9.4 | | | <0.024 | U | | <0.0024 | U | | <0.0024 | U | | 0.014 | J | | <0.00024 | U | | 81 | | | 9.9 | | |
| | | VMP-11-8-040611 | 4/6/2011 | 8.2 | | | <0.028 | U | | <0.0028 | U | | <0.0028 | U | | 0.017 | J | | 0.00007 | J | | 81 | | | 11 | | |
| | | VMP-11-8-040611-DUP | 4/6/2011 | 8.1 | | | <0.029 | U | | <0.0029 | U | | <0.0029 | U | | 0.034 | J | | 0.000058 | J | | 80 | | | 12 | | |
| | | VMP-11-8-080711 | 8/7/2011 | 10 | | | <0.03 | U | | <0.003 | U | | <0.003 | U | | 0.015 | J | | <0.0003 | U | | 81 | | | 9 | | |
| | | VMP-11-8-111411 | 11/14/2011 | 9.7 | | | <0.018 | U | | <0.0018 | U | | <0.0018 | U | | 0.013 | J | | 0.000055 | J | | 80 | | | 9.7 | | |
| | | VMP-11-8-012612 | 1/26/2012 | 10 | | | <0.017 | U | | <0.0017 | U | | <0.0017 | U | | 0.025 | J | | 0.000023 | J | | 81 | | | 9.1 | | |
| | | VMP-11-8-041912 | 4/19/2012 | 4.6 | | | <0.025 | U | | <0.0025 | U | | <0.0025 | U | | 0.11 | J | | 0.000048 | J | | 78 | | | 17 | | |
| | | VMP-11-8-072012 | 7/20/2012 | 3.7 | | | <0.02 | U | | <0.002 | U | | <0.002 | U | | 0.056 | J | | 0.000055 | J | | 79 | | | 17 | | |
| | | VMP-11-8-101612 | 10/16/2012 | 4 | | | <0.029 | U | | <0.0029 | U | | <0.0029 | U | | 0.037 | J | | 0.000059 | J | | 80 | | | 16 | | |
| | | VMP-11-8-101612-Dup | 10/16/2012 | 4.2 | | | <0.029 | U | | <0.0029 | U | | <0.0029 | U | | 0.04 | J | | 0.000044 | J | | 80 | | | 16 | | |
| | | VMP-11-8-012913 | 1/29/2013 | 1.1 | | | <0.15 | U | | 0.000092 | J | | <0.003 | U | | <0.15 | U | | 0.000049 | J | | 80 | | | 19 | | |
| | 29 ft | VMP-11-29-090810 | 9/8/2010 | 14 | | | <0.026 | U | | <0.0026 | U | | <0.0026 | U | | 1 | | | 0.048 | | | 83 | | | 1.6 | | |
| | | VMP-11-29-112210 | 11/22/2010 | 14 | | | <0.028 | U | | <0.0028 | U | | <0.0028 | U | | 0.0073 | J | | 0.071 | | | 84 | | | 1.9 | | |
| | | VMP-11-29-112210-Dup | 11/22/2010 | 14 | | | <0.028 | U | | <0.0028 | U | | <0.0028 | U | | 0.013 | J | | 0.071 | | | 84 | | | 1.5 | | |
| | | VMP-11-29-021411 | 2/14/2011 | 14 | | | <0.025 | U | | <0.0025 | U | | <0.0025 | U | | 0.013 | J | | 0.00048 | | | 82 | | | 3.6 | | |
| | | VMP-11-29-040611 | 4/6/2011 | 15 | | | <0.028 | U | | <0.0028 | U | | <0.0028 | U | | 0.031 | J | | 0.00062 | | | 83 | | | 1.8 | | |
| | | VMP-11-29-082511 | 8/25/2011 | 14 | | | <0.028 | U | | <0.0028 | U | | <0.0028 | U | | 0.0056 | J | | 0.0025 | | | 84 | | | 2 | | |
| | | VMP-11-29-082511-Dup | 8/25/2011 | 14 | | | <0.028 | U | | <0.0028 | U | | <0.0028 | U | | 0.0044 | J | | 0.00013 | J | | 84 | | | 2 | | |
| | | VMP-11-29-111411 | 11/14/2011 | 14 | | | <0.018 | U | | <0.0018 | U | | <0.0018 | U | | 0.0064 | J | | 0.00017 | J | | 83 | | | 2.8 | | |
| | | VMP-11-29-012612 | 1/26/2012 | 16 | | | <0.017 | U | | <0.0017 | U | | <0.0017 | U | | <0.084 | U | | 0.00022 | | | 82 | | | 1.9 | | |
| | | VMP-11-29-042712 | 4/27/2012 | 10 | | | <0.024 | U | | <0.0024 | U | | <0.0024 | U | | 0.011 | J | | 0.00004 | J | | 81 | | | 8.7 | | |
| | | VMP-11-29-072012 | 7/23/2012 | 7.2 | | | <0.018 | U | | <0.0018 | U | | <0.0018 | U | | 0.059 | J | | 0.000098 | J | | 80 | | | 13 | | |
| | | VMP-11-29-101612 | 10/16/2012 | 9.2 | | | <0.03 | U | | <0.003 | U | | <0.003 | U | | 0.093 | J | | 0.000089 | J | | 78 | | | 13 | | |
| | | VMP-11-29-012913 | 1/29/2013 | 2.8 | | | <0.14 | U | | 0.0001 | J | | <0.0029 | U | | 0.071 | J | | 0.000079 | J | | 78 | | | 19 | | |
| | 38 ft | VMP-11-38-042312 | 4/23/2012 | 17 | | | <0.018 | U | | <0.0018 | U | | <0.0018 | U | | 0.017 | J | | 0.0066 | | | 82 | | | 1.5 | | |
| | | VMP-11-38-042312-Dup | 4/23/2012 | 17 | | | <0.018 | U | | <0.0018 | U | | <0.0018 | U | | 0.02 | J | | 0.0067 | | | 81 | | | 1.7 | | |
| | | VMP-11-38-072312 | 7/23/2012 | 16 | | | <0.02 | U | | <0.002 | U | | <0.002 | U | | 0.084 | J | | 0.0037 | | | 82 | | | 1.5 | | |
| | | VMP-11-38-101612 | 10/16/2012 | 13 | | | <0.03 | U | | <0.003 | U | | <0.003 | U | | 0.1 | J | | 0.0023 | | | 80 | | | 7.2 | | |
| | | VMP-11-38-013013 | 1/30/2013 | 8.2 | | | <0.14 | U | | 0.000083 | J | | <0.0028 | U | | 0.06 | J | | 0.0011 | | | 78 | | | 14 | | |
| VMP-12 | 5 ft | VMP-12-5-090310 | 9/3/2010 | 12 | | | <0.027 | U | | 0.0012 | J | | <0.0027 | U | | <0.13 | U | | 36 | | | 49 | | | 0.97 | | |
| | | VMP-12-5-120310 | 12/3/2010 | 13 | | | <0.021 | U | | 0.001 | J | | <0.0021 | U | | 0.0086 | J | | 36 | | | 47 | | | 1.3 | | |
| | | VMP-12-5-021511 | 2/15/2011 | 7.6 | | | <0.024 | U | | 0.00044 | J | | <0.0024 | U | | 0.021 | J | | 18 | | | 72 | | | 1.6 | | |
| | | VMP-12-5-041911 | 4/19/2011 | 7.4 | | | <0.029 | U | | 0.00088 | J | | <0.0029 | U | | 0.023 | J | | 31 | | | 59 | | | 1.4 | | |
| | | VMP-12-5-080411 | 8/4/2011 | 12 | | | <0.029 | U | | 0.00068 | J | | <0.0029 | U | | 0.062 | J | | 24 | | | 61 | | | 2.1 | | |
| | | VMP-12-5-111611 | 11/16/2011 | 7 | | | <0.016 | U | | <0.0016 | U | | <0.0016 | U | | 0.0056 | J | | 0.0003 | | | 77 | | | 16 | | |
| | | VMP-12-5-012412 | 1/24/2012 | 2.8 | | | <0.018 | U | | <0.0018 | U | | <0.0018 | U | | 1.4 | | | 0.0045 | | | 76 | | | 20 | | |
| | | VMP-12-5-041912 | 4/19/2012 | 4 | | | <0.024 | U | | <0.0024 | U | | <0.0024 | U | | 0.57 | | | 0.000054 | J | | 81 | | | 14 | | |
| | | VMP-12-5-072612 | 7/26/2012 | 0.17 | | | <0.02 | U | | <0.002 | U | | <0.002 | U | | 0.2 | | | 0.00017 | J | | 80 | | | 20 | | |
| | | VMP-12-5-072612-Dup | 7/26/2012 | 0.17 | | | <0.018 | U | | <0.0018 | U | | <0.0018 | U | | 0.13 | | | 0.00017 | J | | 80 | | | 20 | | |
| | | VMP-12-5-102412 | 10/24/2012 | 0.14 | | | <0.03 | U | | <0.003 | U | | <0.003 | U | | 0.028 | J | | 0.0001 | J | | 81 | | | 19 | | |
| | | VMP-12-5-021813 | 2/18/2013 | 0.089 | | | <0.13 | U | | <0.0027 | U | | <0.0027 | U | | 0.34 | | | 0.000044 | J | | 78 | | | 21 | | |
| | 11.5 ft | VMP-12-11.5-090310 | 9/3/2010 | 13 | | | <0.028 | U | | 0.0011 | J | | <0.0028 | U | | <0.14 | U | | 38 | | | 46 | | | 1.1 | | |
| | | VMP-12-11.5-120310 | 12/3/2010 | 11 | | | <0.021 | U | | 0.00072 | J | | <0.0021 | U | | 0.039 | J | | 27 | | | 58 | | | 2.5 | | |
| | | VMP-12-11.5-021511 | 2/15/2011 | 9.1 | | | <0.027 | U | | 0.00099 | J | | <0.0027 | U | | 0.022 | J | | 35 | | | 53 | | | 1.5 | | |
| | | VMP-12-11.5-021511-DUP | 2/15/2011 | 8.6 | | | <0.023 | U | | 0.00094 | J | | <0.0023 | U | | 0.04 | J | | 34 | | | 54 | | | 2.3 | | |
| | | VMP-12-11.5-041911 | 4/19/2011 | 9.2 | | | <0.026 | U | | 0.0011 | J | | <0.0026 | U | | 0.023 | J | | 37 | | | 50 | | | 1.6 | | |
| | | VMP-12-11.5-080411 | 8/4/2011 | 12 | | | <0.028 | U | | 0.00052 | J | | <0.0028 | U | | <0.14 | U | | 21 | | | 64 | | | 1.7 | | |
| | | VMP-12-11.5-111611 | 11/16/2011 | 7.7 | | | <0.017 | U | | <0.0017 | U | | <0.0017 | U | | <0.084 | U | | 0.16 | | | 80 | | | 12 | | |
| | | VMP-12-11.5-012412 | 1/24/2012 | 9.6 | | | <0.017 | U | | <0.0017 | U | | <0.0017 | U | | 0.031 | J | | 3.3 | | | 84 | | | 2.7 | | |
| | | VMP-12-11.5-041912 | 4/19/2012 | 5.8 | | | <0.026 | U | | <0.0026 | U | | <0.0026 | U | | 0.073 | J | | 1.3 | | | 80 | | | 13 | | |
| | | VMP-12-11.5-082012 | 8/20/2012 | 0.22 | | | <0.03 | U | | <0.003 | U | | <0.003 | U | | <0.15 | U | | 0.00012 | J | | 80 | | | 20 | | |
| | | VMP-12-11.5-102612 | 10/26/2012 | 0.11 | | | <0.029 | U | | <0.0029 | U | | <0.0029 | U | | 0.038 | J | | 0.00014 | J | | 80 | | | 20 | | |
| | | VMP-12-11.5-021813 | 2/18/2013 | 0.13 | | | <0.14 | U | | <0.0029 | U | | <0.0029 | U | | 0.1 | J | | 0.000079 | J | | 80 | | | 20 | | |
| | 25 ft | VMP-12-25-090310 | 9/3/2010 | 13 | | | <0.026 | U | | 0.0012 | J | | <0.0026 | U | | <0.13 | J | U | 36 | | | 47 | | | 0.99 | | |
| | | VMP-12-25-120310 | 12/3/2010 | 13 | | | <0.022 | U | | 0.000091 | J | | <0.0022 | U | | <0.11 | U | | 4.8 | | | 80 | | | 1.5 | | |
| | | VMP-12-25-021511 | 2/15/2011 | 13 | | | <0.027 | U | | 0.00089 | J | | <0.0027 | U | | 0.026 | J | | 32 | | | 52 | | | 1.4 | | |
| | | VMP-12-25-041911 | 4/19/2011 | 13 | | | <0.028 | U | | 0.00097 | J | | <0.0028 | U | | 0.032 | J | | 35 | | | 49 | | | 1.1 | | |
| | | VMP-12-25-080411 | 8/4/2011 | 12 | | | <0.026 | U | | 0.001 | J | | <0.0026 | U | | 0.013 | J | | 35 | | | 49 | | | 2.2 | | |
| | | VMP-12-25-111611 | 11/16/2011 | 12 | | | <0.016 | U | | 0.001 | J | | <0.0016 | U | | <0.078 | U | | 36 | | | 49 | | | 1.5 | | |
| | | VMP-12-25-012412 | 1/24/2012 | 12 | | | <0.017 | U | | 0.00086 | J | | <0.0017 | U | | 0.0067 | J | | 31 | | | 54 | | | 1.3 | | J |
| | | VMP-12-25-012412-DUP | 1/24/2012 | 12 | | | <0.018 | U | | 0.00085 | J | | <0.0018 | U | | 0.043 | J | | 30 | | | 55 | | | 1.8 | | J |
| | | VMP-12-25-041912 | 4/19/2012 | 9.5 | | | <0.018 | U | | 0.00067 | J | | <0.0018 | U | | 0.046 | J | | 29 | | | 58 | | | 2.3 | | |
| | | VMP-12-25-072712 | 7/27/2012 | 12 | | | <0.02 | U | | 0.00012 | J | | <0.002 | U | | 0.037 | J | | 4.8 | | | 81 | | | 1.9 | | |
| | | VMP-12-25-072712-Dup | 7/27/2012 | 12 | | | <0.02 | U | | 0.000088 | J | | <0.002 | U | | 0.035 | J | | 5 | | | 81 | | | 1.6 | | |
| | | VMP-12-25-102512 | 10/25/2012 | 12 | | | <0.029 | U | | <0.0029 | U | | <0.0029 | U | | 0.055 | J | | 0.92 | | | 85 | | | 1.8 | | |
| | | VMP-12-25-021513 | 2/15/2013 | 12 | | | <0.13 | U | | 0.00025 | J | | <0.0026 | U | | <0.13 | U | | 12 | | | 74 | | | 1.4 | | |
| | 39 ft | VMP-12-39-041911 | 4/19/2011 | 13 | | | <0.03 | U | | 0.0014 | J | | <0.003 | U | | 0.014 | J | | 42 | | | 42 | | | 1 | | |
| | | VMP-12-39-012412 | 1/24/2012 | 12 | | | <0.018 | U | | 0.0017 | J | | <0.0018 | U | | <0.088 | U | | 49 | | | 36 | | | 1.1 | | |
| | | VMP-12-39-041912 | 4/19/2012 | 12 | | | <0.018 | U | | 0.0009 | J | | <0.0018 | U | | 0.082 | J | | 40 | | | 46 | | | 1 | | |
| | | VMP-12-39-072612 | 7/26/2012 | 12 | | | <0.02 | U | | 0.0005 | J | | <0.002 | U | | 0.034 | J | | 21 | | | 65 | | | 1.4 | | |
| | | VMP-12-39-102412 | 10/24/2012 | 14 | | | <0.032 | U | | 0.00078 | J | | <0.0032 | U | | 0.035 | | | 12 | | | 72 | | | 1.6 | | |
| | | VMP-12-39-021513 | 2/15/2013 | 14 | | | <0.12 | U | | 0.00064 | J | | <0.0024 | U | | <0.12 | U | | 26 | | | 58 | | | 1.5 | | |

SEE LAST PAGE OF TABLE FOR NOTES

**TABLE 7**
**CUMULATIVE SUMMARY OF SOIL VAPOR ANALYTICAL RESULTS - NATURAL GASES**

| Location | Depth | Sample ID | Sample Date | Carbon Dioxide | | | Carbon Monoxide | | | Ethane | | | Ethene | | | Helium | | | Methane | | | Nitrogen | | | Oxygen | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | Result % | Lab Quals | URS Quals | Result % | Lab Quals | URS Quals | Result % | Lab Quals | URS Quals | Result % | Lab Quals | URS Quals | Result % | Lab Quals | URS Quals | Result % | Lab Quals | URS Quals | Result % | Lab Quals | URS Quals | Result % | Lab Quals | URS Quals |
| VMP-13 | 5 ft | VMP 13-5-091310 | 9/13/2010 | 8.4 | | | <0.026 | U | | <0.0026 | U | | <0.0026 | U | | <0.13 | U | | 0.00088 | | | 84 | | | 7 | | |
| | | VMP-13-5-120110 | 12/1/2010 | 6.1 | | | <0.023 | U | | <0.0023 | U | | <0.0023 | U | | 0.047 | J | | <0.00023 | U | | 81 | | | 13 | | |
| | | VMP-13-5-021811 | 2/18/2011 | 3.6 | | | <0.073 | U | | <0.0073 | U | | <0.0073 | U | | 0.017 | J | | 0.0048 | | | 80 | | | 16 | | |
| | | VMP-13-5-040511 | 4/5/2011 | 3.4 | | | <0.055 | U | | <0.0055 | U | | <0.0055 | U | | 0.079 | J | | <0.00055 | U | | 81 | | | 16 | | |
| | | VMP-13-5-080911 | 8/9/2011 | 9.1 | | | <0.03 | U | | <0.003 | U | | <0.003 | U | | 0.24 | | | 0.0095 | | | 84 | | | 6.5 | | |
| | | VMP-13-5-080911-DUP | 8/9/2011 | 6.2 | | | <0.026 | U | | <0.0026 | U | | <0.0026 | U | | 0.17 | | | 0.0061 | | | 83 | | | 11 | | |
| | | VMP-13-5-111411 | 11/14/2011 | 6.2 | | | <0.018 | U | | <0.0018 | U | | <0.0018 | U | | 0.0074 | J | | 0.000065 | J | | 82 | | | 12 | | |
| | | VMP-13-5-012712 | 1/27/2012 | 4.6 | | | <0.016 | U | | <0.0016 | U | | <0.0016 | U | | 0.0064 | J | | 0.000092 | J | | 81 | | | 14 | | |
| | | VMP-13-5-042012 | 4/20/2012 | 3.4 | | | <0.026 | U | | <0.0026 | U | | <0.0026 | U | | <0.13 | U | | 0.000032 | J | | 81 | | | 16 | | |
| | | VMP-13-5-071912 | 7/19/2012 | 4.3 | | | <0.024 | U | | <0.0024 | U | | <0.0024 | U | | 0.14 | | | 0.000083 | J | | 80 | | | 16 | | |
| | | VMP-13-5-071912-Dup | 7/19/2012 | 4.4 | | | <0.024 | U | | <0.0024 | U | | <0.0024 | U | | 0.032 | J | | 0.000079 | J | | 80 | | | 16 | | |
| | | VMP-13-5-100912 | 10/9/2012 | 2.8 | | | <0.037 | U | | <0.0037 | U | | <0.0037 | U | | 0.034 | J | | 0.000091 | J | | 79 | | | 18 | | |
| | | VMP-13-5-012913 | 1/29/2013 | 0.24 | | | <0.16 | U | | <0.0031 | U | | <0.0031 | U | | 0.091 | J | | 0.000061 | J | | 79 | | | 21 | | |
| | 10.5 ft | VMP 13-10.5-091310 | 9/13/2010 | 11 | | | <0.049 | U | | <0.0049 | U | | <0.0049 | U | | <0.24 | U | | 0.068 | | | 86 | | | 3.4 | | |
| | | VMP 13-10.5-091310-Dup | 9/13/2010 | 11 | | | <0.048 | U | | <0.0048 | U | | <0.0048 | U | | <0.24 | U | | 0.076 | | | 85 | | | 3.6 | | |
| | | VMP-13-10.5-120110 | 12/1/2010 | 8.6 | | | <0.026 | U | | <0.0026 | U | | <0.0026 | U | | 0.028 | J | | 0.00032 | | | 82 | | | 8.8 | | |
| | | VMP-13-10.5-120110-DUP | 12/1/2010 | 8.6 | | | <0.027 | U | | <0.0027 | U | | <0.0027 | U | | <0.14 | U | | 0.0003 | | | 83 | | | 8.7 | | |
| | | VMP-13-10.5-021811 | 2/18/2011 | 12 | | | <0.027 | U | | 0.00022 | J | | <0.0027 | U | | <0.13 | U | | 1.1 | | | 84 | | | 2.5 | | |
| | | VMP-13-10.5-021811-DUP | 2/18/2011 | 12 | | | <0.026 | U | | 0.00023 | J | | <0.0026 | U | | 0.021 | J | | 1.1 | | | 85 | | | 1.9 | | |
| | | VMP-13-10.5-040511-DUP | 4/5/2011 | 5.9 | | | <0.028 | U | | <0.0028 | U | | <0.0028 | U | | 0.023 | J | | <0.00028 | U | | 83 | | | 11 | | |
| | | VMP-13-10.5-080911 | 8/9/2011 | 11 | | | <0.03 | U | | 0.00012 | J | | <0.003 | U | | 0.0088 | J | | 0.59 | | | 87 | | | 1.7 | | |
| | | VMP-13-10.5-111411 | 11/14/2011 | 7 | | | <0.018 | U | | <0.0018 | U | | <0.0018 | U | | 0.0057 | J | | 0.000084 | J | | 83 | | | 10 | | |
| | | VMP-13-10.5-012712 | 1/26/2012 | 5.8 | | | <0.017 | U | | <0.0017 | U | | <0.0017 | U | | 0.23 | | | 0.000062 | J | | 82 | | | 12 | | |
| | | VMP-13-10.5-012712-DUP | 1/26/2012 | 5.9 | | | <0.018 | U | | <0.0018 | U | | <0.0018 | U | | 0.75 | | | 0.000064 | J | | 81 | | | 12 | | |
| | | VMP-13-10.5-042012 | 4/20/2012 | 4.2 | | | <0.023 | U | | <0.0023 | U | | <0.0023 | U | | <0.11 | U | | 0.00005 | J | | 81 | | | 15 | | |
| | | VMP-13-10.5-071912 | 7/19/2012 | 5.9 | | | <0.024 | U | | <0.0024 | U | | <0.0024 | U | | 0.045 | J | | 0.00005 | J | | 81 | | | 13 | | |
| | | VMP-13-10.5-100912 | 10/9/2012 | 3.4 | | | <0.025 | U | | <0.0025 | U | | <0.0025 | U | | <0.12 | J | U | 0.000085 | J | | 78 | | | 18 | | |
| | | VMP-13-10.5-100912-Dup | 10/9/2012 | 3.6 | | | <0.038 | U | | <0.0038 | U | | <0.0038 | U | | 0.023 | J | | 0.000066 | J | | 79 | | | 17 | | |
| | | VMP-13-10.5-013013 | 1/30/2013 | 0.32 | | | <0.13 | U | | <0.0025 | U | | <0.0025 | U | | 0.075 | J | | 0.000075 | J | | 79 | | | 21 | | |
| | 21.5 ft | VMP 13-21.5-091310 | 9/13/2010 | 12 | | | <0.024 | U | | 0.00034 | J | | <0.0024 | U | | <0.12 | U | | 2 | | | 83 | | | 2.5 | | |
| | | VMP-13-21.5-120110 | 12/1/2010 | 13 | | | <0.024 | U | | 0.00037 | J | | <0.0024 | U | | 0.02 | J | | 1.8 | | | 83 | | | 1.8 | | |
| | | VMP-13-21.5-021811 | 2/18/2011 | 12 | | | <0.025 | U | | 0.00026 | J | | <0.0025 | U | | 0.027 | J | | 1.2 | | | 85 | | | 1.9 | | |
| | | VMP-13-21.5-040511 | 4/5/2011 | 7.5 | | | <0.024 | U | | 0.0002 | J | | <0.0024 | U | | 0.029 | J | | 0.88 | | | 83 | | | 8.2 | | |
| | | VMP-13-21.5-080911 | 8/9/2011 | 11 | | | <0.03 | U | | 0.00038 | J | | <0.003 | U | | 0.0062 | J | | 1.9 | | | 85 | | | 1.6 | | |
| | | VMP-13-21.5-111411 | 11/14/2011 | 11 | | | <0.018 | U | | 0.00026 | J | | <0.0018 | U | | 0.005 | J | | 1.1 | | | 86 | | | 1.5 | | |
| | | VMP-13-21.5-111411-DUP | 11/14/2011 | 11 | | | <0.018 | U | | 0.00025 | J | | <0.0018 | U | | 0.0038 | J | | 1.1 | | | 86 | | | 1.5 | | |
| | | VMP-13-21.5-012712 | 1/27/2012 | 12 | | | <0.016 | U | | 0.00012 | J | | <0.0016 | U | | <0.08 | U | | 0.5 | | | 85 | | | 2.8 | | |
| | | VMP-13-21.5-042012 | 4/20/2012 | 10 | | | <0.024 | U | | <0.0024 | U | | <0.0024 | U | | <0.12 | U | | 0.074 | | | 82 | | | 8.3 | | |
| | | VMP-13-21.5-071912 | 7/19/2012 | 10 | | | <0.025 | U | | <0.0025 | U | | <0.0025 | U | | 0.042 | J | | 0.0027 | | | 82 | | | 7.7 | | |
| | | VMP-13-21.5-100912 | 10/9/2012 | 15 | | | <0.03 | U | | <0.003 | U | | <0.003 | U | | <0.051 | | U | 0.0015 | | | 83 | | | 2 | | |
| | | VMP-13-21.5-013013 | 1/30/2013 | 1.4 | | | <0.15 | U | | <0.003 | U | | <0.003 | U | | <0.15 | U | | 0.00002 | J | | 79 | | | 20 | | |
| | 29.5 ft | VMP-13-29.5-021811 | 2/18/2011 | 13 | | | <0.022 | U | | 0.00052 | J | | <0.0022 | U | | 0.01 | J | | 1.8 | | | 83 | | | 1.6 | | |
| | | VMP-13-29.5-040511 | 4/5/2011 | 12 | | | <0.022 | U | | 0.00047 | J | | <0.0022 | U | | 0.0083 | J | | 2 | | | 84 | | | 1.7 | | |
| | | VMP-13-29.5-013012 | 1/30/2012 | 12 | | | <0.017 | U | | 0.0002 | J | | <0.0017 | U | | 0.023 | J | | 0.84 | | | 85 | | | 2 | | |
| | | VMP-13-29.5-042012 | 4/20/2012 | 12 | | | <0.017 | U | | 0.00014 | J | | <0.0017 | U | | 0.0058 | J | | 0.4 | | | 86 | | | 1.5 | | |
| | | VMP-13-29.5-071912 | 7/19/2012 | 13 | | | <0.019 | U | | 0.000073 | J | | <0.0019 | U | | 0.084 | J | | 0.18 | | | 85 | | | 1.7 | | |
| | | VMP-13-29.5-100912 | 10/9/2012 | 14 | | | <0.03 | U | | 0.000076 | J | | <0.003 | U | | 0.042 | J | | 0.19 | | | 84 | | | 1.5 | | |
| | | VMP-13-29.5-013013 | 1/30/2013 | 5.2 | | | <0.13 | U | | <0.0026 | U | | <0.0026 | U | | <0.13 | U | | 0.0037 | | | 79 | | | 16 | | |
| VMP-14 | 5 ft | VMP 14-5-091010 | 9/10/2010 | 19 | | | <0.025 | U | | 0.0063 | | | <0.0025 | U | | 0.01 | J | | 10 | | | 69 | | | 1.8 | | |
| | | VMP-14-5-120110 | 12/1/2010 | 2.6 | | | <0.024 | U | | <0.0024 | U | | <0.0024 | U | | 0.025 | J | | 0.00007 | J | | 85 | | | 12 | | |
| | | VMP-14-5-021711 | 2/17/2011 | 1.9 | | | <0.026 | U | | <0.0026 | U | | <0.0026 | U | | 0.031 | J | | 0.016 | | | 93 | | | 5 | | |
| | | VMP-14-5-040511 | 4/5/2011 | 2.6 | | | <0.027 | U | | <0.0027 | U | | <0.0027 | U | | 0.025 | J | | 0.0022 | | | 78 | | | 19 | | |
| | | VMP-14-5-080811 | 8/8/2011 | 16 | | | <0.028 | U | | 0.0081 | | | <0.0028 | U | | 0.0098 | J | | 19 | | | 62 | | | 1.8 | | |
| | | VMP-14-5-111411 | 11/14/2011 | 8.2 | | | <0.018 | U | | <0.0018 | U | | <0.0018 | U | | 1.5 | | | 0.000018 | J | | 76 | | | 14 | | |
| | | VMP-14-5-042012 | 4/20/2012 | 2.9 | | | <0.025 | U | | <0.0025 | U | | <0.0025 | U | | 0.026 | J | | <0.00025 | U | | 79 | | | 18 | | |
| | | VMP-14-5-072312 | 7/23/2012 | 8.5 | | | <0.021 | U | | <0.0021 | U | | <0.0021 | U | | 0.039 | J | | <0.00021 | U | | 80 | | | 11 | | |
| | | VMP-14-5-101012 | 10/10/2012 | 1.2 | | | <0.029 | U | | <0.0029 | U | | <0.0029 | U | | 0.14 | | | 0.000042 | J | | 78 | | | 21 | | |
| | | VMP-14-5-013113 | 1/31/2013 | 0.09 | | | <0.13 | U | | <0.0027 | U | | <0.0027 | U | | 0.15 | | | 0.000058 | J | | 79 | | | 21 | | |
| | 11.5 ft | VMP 14-11.5-091010 | 9/10/2010 | 16 | | | <0.023 | U | | 0.01 | | | <0.0023 | U | | 0.0087 | J | | 20 | | | 62 | | | 1.1 | | |
| | | VMP-14-11.5-120110 | 12/2/2010 | 3.6 | | | <0.025 | U | | 0.001 | J | | <0.0025 | U | | 0.029 | J | | 2.8 | | | 92 | | | 1.6 | | |
| | | VMP-14-11.5-120110-DUP | 12/2/2010 | 3.6 | | | <0.024 | U | | 0.001 | J | | <0.0024 | U | | 0.0068 | J | | 2.8 | | | 92 | | | 1.6 | | |
| | | VMP-14-11.5-021711 | 2/17/2011 | 3.6 | | | <0.028 | U | | <0.0028 | U | | <0.0028 | U | | 0.0073 | J | | 0.15 | | | 93 | | | 3 | | |
| | | VMP-14-11.5-021711-DUP | 2/17/2011 | 3.7 | | | <0.028 | U | | <0.0028 | U | | <0.0028 | U | | 0.039 | J | | 0.16 | | | 93 | | | 2.8 | | |
| | | VMP-14-11.5-040511 | 4/5/2011 | 11 | | | <0.027 | U | | <0.0027 | U | | <0.0027 | U | | 0.028 | J | | 0.0024 | | | 79 | | | 10 | | |
| | | VMP-14-11.5-080811 | 8/8/2011 | 18 | | | <0.028 | U | | 0.0021 | J | | <0.0028 | U | | 0.01 | J | | 4.5 | | | 76 | | | 1.6 | | |
| | | VMP-14-11.5-111511 | 11/15/2011 | 14 | | | <0.017 | U | | 0.001 | J | | <0.0017 | U | | 0.25 | | | 3.4 | | | 81 | | | 1.6 | | |
| | | VMP-14-11.5-012612 | 1/26/2012 | 4.2 | | | <0.018 | U | | 0.00082 | J | | <0.0018 | U | | <0.088 | U | | 4.5 | | | 88 | | | 3.3 | | |
| | | VMP-14-11.5-042312 | 4/23/2012 | 4.5 | | | <0.024 | U | | <0.0024 | U | | <0.0024 | U | | 0.11 | J | | 0.0001 | J | | 85 | | | 10 | | |
| | | VMP-14-11.5-042312-Dup | 4/23/2012 | 4.1 | | | <0.03 | U | | <0.003 | U | | <0.003 | U | | 0.085 | J | | 0.00011 | J | | 84 | | | 12 | | |
| | | VMP-14-11.5-072512 | 7/25/2012 | 15 | | | <0.019 | U | | 0.00035 | J | | <0.0019 | U | | 0.032 | J | | 2 | | | 82 | | | 1.4 | | |
| | | VMP-14-11.5-101012 | 10/10/2012 | 6.7 | | | <0.028 | U | | <0.0028 | U | | <0.0028 | U | | <0.14 | J | U | 0.000072 | J | | 74 | | | 19 | | |
| | | VMP-14-11.5-013113 | 1/31/2013 | 0.42 | | | <0.13 | U | | <0.0026 | U | | <0.0026 | U | | 0.042 | J | | <0.00026 | U | | 80 | | | 20 | | |
| | 20 ft | VMP 14-20-091010 | 9/10/2010 | 17 | | | <0.023 | U | | 0.012 | | | <0.0023 | U | | <0.12 | U | | 22 | | | 57 | | | 0.97 | | |
| | | VMP 14-20-091010-Dup | 9/10/2010 | 17 | | | <0.024 | U | | 0.011 | | | <0.0024 | U | | <0.12 | U | | 22 | | | 57 | | | 1.1 | | |
| | | VMP-14-20-120110 | 12/2/2010 | 18 | | | <0.024 | U | | 0.0047 | | | <0.0024 | U | | 0.0053 | J | | 19 | | | 59 | | | 1.2 | | |
| | | VMP-14-20-021811 | 2/18/2011 | 16 | | | <0.027 | U | | 0.0058 | | | <0.0027 | U | | 0.025 | J | | 13 | | | 67 | | | 1.7 | | |
| | | VMP-14-20-040511 | 4/5/2011 | 14 | | | <0.053 | U | | 0.006 | | | <0.0053 | U | | 0.028 | J | | 12 | | | 68 | | | 4 | | |
| | | VMP-14-20-080811 | 8/8/2011 | 16 | | | <0.028 | U | | 0.0088 | | | <0.0028 | U | | 1.2 | | | 21 | | | 58 | | | 1.8 | | |
| | | VMP-14-20-111511 | 11/15/2011 | 18 | | | <0.018 | U | | 0.006 | | | <0.0018 | U | | 0.013 | J | | 17 | | | 62 | | | 1.2 | | |
| | | VMP-14-20-012612 | 1/26/2012 | 17 | | | <0.018 | U | | 0.0037 | | | <0.0018 | U | | <0.088 | U | | 12 | | | 68 | | | 1.4 | | |
| | | VMP-14-20-042312 | 4/23/2012 | 15 | | | <0.019 | U | | 0.0021 | | | <0.0019 | U | | 0.0094 | J | | 7.4 | | | 74 | | | 2.1 | | |
| | | VMP-14-20-072512 | 7/25/2012 | 14 | | | <0.018 | U | | 0.0014 | J | | <0.0018 | U | | 0.024 | J | | 5.7 | | | 76 | | | 3 | | |
| | | VMP-14-20-101612 | 10/16/2012 | 18 | | | <0.028 | U | | 0.00081 | J | | <0.0028 | U | | 0.061 | J | | 5.4 | | | 74 | | | 1.4 | | |
| | | VMP-14-20-013113 | 1/31/2013 | 10 | | | <0.13 | U | | 0.00036 | J | | <0.0025 | U | | 0.019 | J | | 2.6 | | | 80 | | | 7.1 | | |
| | | VMP-14-20-013113-DUP | 1/31/2013 | 10 | | | <0.12 | U | | 0.00036 | J | | <0.0024 | U | | <0.12 | U | | 2.6 | | | 80 | | | 7 | | |
| | 29 ft | VMP-14-29-021811 | 2/18/2011 | 16 | | | <0.026 | U | | 0.0062 | | | <0.0026 | U | | 0.61 | | | 13 | | | 66 | | | 1.6 | | |
| | | VMP-14-29-040511 | 4/5/2011 | 16 | | | <0.028 | U | | 0.0058 | | | <0.0028 | U | | 0.025 | J | | 13 | | | 67 | | | 1.3 | | |
| | | VMP-14-29-012612 | 1/26/2012 | 17 | | | <0.016 | U | | 0.0039 | | | <0.0016 | U | | <0.082 | U | | 12 | | | 68 | | | 1.3 | | |
| | | VMP-14-29-042312 | 4/23/2012 | 15 | | | <0.018 | U | | 0.0023 | | | <0.0018 | U | | 0.0071 | J | | 7.4 | | | 75 | | | 1.4 | | |
| | | VMP-14-29-072512 | 7/25/2012 | 15 | | | <0.019 | U | | 0.0017 | J | | <0.0019 | U | | 0.045 | J | | 6.2 | | | 76 | | | 1.2 | | |
| | | VMP-14-29-101612 | 10/16/2012 | 17 | | | <0.028 | U | | 0.0012 | J | | <0.0028 | U | | 0.041 | J | | 5.5 | | | 75 | | | 1.6 | | |
| | | VMP-14-29-013113 | 1/31/2013 | 15 | | | <0.12 | U | | 0.0013 | J | | <0.0025 | U | | <0.12 | U | | 5.5 | | | 76 | | | 1.5 | | |

SEE LAST PAGE OF TABLE FOR NOTES

**TABLE 7**
**CUMULATIVE SUMMARY OF SOIL VAPOR ANALYTICAL RESULTS - NATURAL GASES**

| Location | Depth | Sample ID | Sample Date | Carbon Dioxide | | | Carbon Monoxide | | | Ethane | | | Ethene | | | Helium | | | Methane | | | Nitrogen | | | Oxygen | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | Result % | Lab Quals | URS Quals | Result % | Lab Quals | URS Quals | Result % | Lab Quals | URS Quals | Result % | Lab Quals | URS Quals | Result % | Lab Quals | URS Quals | Result % | Lab Quals | URS Quals | Result % | Lab Quals | URS Quals | Result % | Lab Quals | URS Quals |
| VMP-15 | 5 ft | VMP 15-5-091410 | 9/14/2010 | 17 | | | <0.025 | U | | <0.0025 | U | | <0.0025 | U | | <0.13 | J | U | 0.00012 | J | | 80 | | | 3 | | |
| | | VMP-15-5-113010 | 11/30/2010 | 15 | | | <0.024 | U | | 0.00077 | J | | <0.0024 | U | | 0.04 | J | | 1.3 | | | 82 | | | 1.5 | | |
| | | VMP-15-5-021611 | 2/16/2011 | 10 | | | <0.028 | U | | <0.0028 | U | | <0.0028 | U | | 0.022 | J | | 0.069 | | | 85 | | | 4.9 | | |
| | | VMP-15-5-042011 | 4/20/2011 | 15 | | | <0.026 | U | | <0.0026 | U | | <0.0026 | U | | 0.04 | J | | 0.056 | | | 83 | | | 1.9 | | |
| | | VMP-15-5-080811 | 8/8/2011 | 14 | | | <0.023 | U | | <0.0023 | U | | <0.0023 | U | | 0.013 | J | | 0.00011 | J | | 78 | | | 7.6 | | |
| | | VMP-15-5-111511 | 11/15/2011 | 11 | | | <0.017 | U | | <0.0017 | U | | <0.0017 | U | | 0.0082 | J | | 0.000091 | J | | 82 | | | 6.6 | | |
| | | VMP-15-5-020112 | 2/1/2012 | 9.2 | | | <0.017 | U | | <0.0017 | U | | <0.0017 | U | | <0.086 | U | | <0.00017 | U | | 90 | | | 9.8 | | |
| | | VMP-15-5-042412 | 4/24/2012 | 11 | | | <0.023 | U | | <0.0023 | U | | <0.0023 | U | | 0.02 | J | | 0.0036 | | | 82 | | | 6.6 | | |
| | | VMP-15-5-072512 | 7/25/2012 | 12 | | | <0.02 | U | | <0.002 | U | | <0.002 | U | | <0.098 | U | | 0.000068 | J | | 78 | | | 10 | | |
| | | VMP-15-5-102512 | 10/25/2012 | 8.5 | | | <0.03 | U | | <0.003 | U | | <0.003 | U | | <0.15 | U | | 0.000053 | J | | 82 | | | 10 | | |
| | | VMP-15-5-020513 | 2/5/2013 | 6.7 | | | <0.14 | U | | <0.0029 | U | | <0.0029 | U | | <0.14 | U | | <0.00029 | U | | 83 | | | 10 | | |
| | 21.5 ft | VMP 15-21.5-091410 | 9/14/2010 | 17 | | | <0.025 | U | | 0.012 | | | <0.0025 | U | | 1 | | | 13 | | | 66 | | | 2.3 | | |
| | | VMP-15-21.5-113010 | 11/30/2010 | 19 | | | <0.024 | U | | 0.0085 | | | <0.0024 | U | | 0.22 | | | 11 | | | 68 | | | 1.3 | | |
| | | VMP-15-21.5-021611 | 2/16/2011 | 18 | | | <0.027 | U | | 0.0034 | | | <0.0027 | U | | 0.0097 | J | | 5.4 | | | 75 | | | 1.6 | | |
| | | VMP-15-21.5-042011 | 4/20/2011 | 18 | | | <0.028 | U | | 0.0055 | | | <0.0028 | U | | 0.022 | J | | 8.3 | | | 72 | | | 1.5 | | |
| | | VMP-15-21.5-080811 | 8/8/2011 | 19 | | | <0.028 | U | | 0.013 | | | <0.0028 | U | | 0.016 | J | | 16 | | | 64 | | | 1.3 | | |
| | | VMP-15-21.5-111511 | 11/15/2011 | 16 | | | <0.017 | U | | 0.0021 | | | <0.0017 | U | | 0.0053 | J | | 3.9 | | | 78 | | | 1.6 | | |
| | | VMP-15-21.5-020112 | 2/1/2012 | 15 | | | <0.017 | U | | 0.0013 | J | | <0.0017 | U | | <0.084 | U | | 2.2 | | | 79 | | | 3.8 | | |
| | | VMP-15-21.5-042412 | 4/24/2012 | 17 | | | <0.018 | U | | 0.00051 | J | | <0.0018 | U | | 0.0094 | J | | 1.1 | | | 80 | | | 1.7 | | |
| | | VMP-15-21.5-072512 | 7/25/2012 | 16 | | | <0.021 | U | | 0.00076 | J | | <0.0021 | U | | 0.011 | J | | 1.6 | | | 81 | | | 1.5 | | |
| | | VMP-15-21.5-102512 | 10/25/2012 | 16 | | | <0.03 | U | | 0.0006 | J | | <0.003 | U | | <0.15 | U | | 1.3 | | | 81 | | | 1.4 | | |
| | | VMP-15-21.5-102512-Dup | 10/25/2012 | 15 | | | <0.031 | U | | 0.00063 | J | | <0.0031 | U | | <0.16 | U | | 1.4 | | | 82 | | | 1.6 | | |
| | | VMP-15-21.5-020713 | 2/7/2013 | 15 | | | <0.14 | U | | <0.0028 | U | | <0.0028 | U | | 0.14 | | | 0.044 | | | 83 | | | 1.8 | | |
| | 25.5 ft | VMP 15-25.5-091410 | 9/14/2010 | 7.1 | | | <0.067 | U | | <0.0067 | U | | <0.0067 | U | | 5.3 | | | 0.013 | | | 74 | | | 14 | | |
| | | VMP-15-25.5-021611 | 2/16/2011 | 7.6 | | | <0.026 | U | | 0.0004 | J | | <0.0026 | U | | 4.3 | | | 0.6 | | | 79 | | | 8.5 | | |
| | | VMP-15-25.5-042011 | 4/20/2011 | 3.9 | | | <0.028 | U | | <0.0028 | U | | <0.0028 | U | | 9.9 | | | 0.0012 | | | 71 | | | 15 | | |
| | | VMP-15-25.5-042011-DUP | 4/20/2011 | 3.7 | | | <0.026 | U | | <0.0026 | U | | <0.0026 | U | | 9.5 | | | 0.0071 | | | 72 | | | 15 | | |
| | | VMP-15-25.5-080811 | 8/8/2011 | 15 | | | <0.028 | U | | <0.0028 | U | | <0.0028 | U | | 3.6 | | | 0.0036 | | | 75 | | | 5.9 | | |
| | | VMP-15-25.5-111511 | 11/15/2011 | 5 | | | <0.017 | U | | <0.0017 | U | | <0.0017 | U | | 4.1 | | | 0.012 | | | 78 | | | 13 | | |
| | | VMP-15-25.5-073112 | 7/31/2012 | 7.1 | | | <0.018 | U | | <0.0018 | U | | <0.0018 | U | | 0.036 | J | | 0.051 | | | 81 | | | 12 | | |
| | | VMP-15-25.5-102512 | 10/25/2012 | 3.2 | | | <0.037 | U | | <0.0037 | U | | <0.0037 | U | | 0.62 | | | 0.0077 | | | 71 | J | | 25 | J | |
| | | VMP-15-25.5-021213 | 2/12/2013 | 16 | | | <0.13 | U | | 0.00051 | J | | <0.0027 | U | | <0.13 | U | | 0.87 | | | 81 | | | 1.6 | | |
| | 29 ft | VMP-15-29-073112 | 7/31/2012 | 10 | | | <0.02 | U | | 0.00038 | J | | <0.002 | U | | 2.5 | | | 0.7 | | | 80 | | | 6.9 | | |
| | | VMP-15-29-102512 | 10/25/2012 | 3.4 | | | <0.031 | U | | <0.0031 | U | | <0.0031 | U | | 1.6 | | | 0.015 | | | 79 | | | 16 | | |
| | | VMP-15-29-021213 | 2/12/2013 | 13 | | | <0.13 | U | | 0.00039 | J | | <0.0027 | U | | 0.2 | | | 0.64 | | | 82 | | | 4.1 | | |
| VMP-16 | 5 ft | VMP-16-5-090210 | 9/2/2010 | 18 | | | <0.024 | U | | 0.0014 | J | | <0.0024 | U | | 0.032 | J | | 43 | | | 38 | | | 1 | | |
| | | VMP-16-5-112910 | 11/29/2010 | 12 | | | <0.022 | U | | 0.0008 | J | | <0.0022 | U | | 0.1 | J | | 32 | | | 48 | | | 7.3 | | |
| | | VMP-16-5-021511 | 2/15/2011 | 15 | | | <0.026 | U | | 0.00093 | J | | <0.0026 | U | | 0.03 | J | | 43 | | | 40 | | | 1 | | |
| | | VMP-16-5-042211 | 4/22/2011 | 17 | | | <0.026 | U | | 0.001 | J | | <0.0026 | U | | 0.04 | J | | 48 | | | 33 | | | 1.1 | | |
| | | VMP-16-5-080511 | 8/5/2011 | 13 | | | <0.028 | U | | 0.00012 | J | | <0.0028 | U | | 0.69 | | | 4.2 | | | 78 | | | 3.9 | | |
| | | VMP-16-5-042512 | 4/25/2012 | 17 | | | <0.019 | U | | 0.00065 | J | | <0.0019 | U | | 0.0089 | J | | 24 | | | 57 | | | 1.1 | | |
| | | VMP-16-5-073012 | 7/30/2012 | 20 | | | <0.018 | U | | 0.00023 | J | | <0.0018 | U | | <0.09 | U | | 6.8 | | | 71 | | | 1.3 | | |
| | | VMP-16-5-102512 | 10/25/2012 | 11 | | | <0.028 | U | | <0.0028 | U | | <0.0028 | U | | <0.14 | U | | 1.1 | | | 82 | | | 5.5 | | |
| | | VMP-16-5-021413 | 2/14/2013 | 4.1 | | | <0.13 | U | | <0.0026 | U | | <0.0026 | U | | 0.26 | | | 0.0001 | J | | 80 | | | 16 | | |
| | 13.5 ft | VMP-16-13.5-090210 | 9/2/2010 | 19 | | | <0.025 | U | | 0.0014 | J | | <0.0025 | U | | <0.12 | J | U | 46 | | | 34 | | | 0.78 | | J |
| | | VMP-16-13.5-090210-DUP | 9/2/2010 | 18 | | | <0.025 | U | | 0.0014 | J | | <0.0025 | U | | <0.12 | J | U | 45 | | | 35 | | | 2 | | J |
| | | VMP-16-13.5-112910 | 11/29/2010 | 17 | | | <0.022 | U | | 0.0012 | J | | <0.0022 | U | | 0.011 | J | | 50 | | | 31 | | | 0.84 | | |
| | | VMP-16-13.5-021611 | 2/16/2011 | 15 | | | <0.027 | U | | 0.00087 | J | | <0.0027 | U | | 0.013 | J | | 37 | | | 46 | | | 1.1 | | |
| | | VMP-16-13.5-021611-DUP | 2/16/2011 | 14 | | | <0.026 | U | | 0.00084 | J | | <0.0026 | U | | 0.039 | J | | 36 | | | 49 | | | 1.1 | | |
| | | VMP-16-13.5-042211 | 4/22/2011 | 16 | | | <0.028 | U | | 0.00099 | J | | <0.0028 | U | | 0.064 | J | | 48 | | | 33 | | | 0.93 | | |
| | | VMP-16-13.5-080511 | 8/5/2011 | 8.4 | | J | <0.028 | U | UJ | <0.0028 | U | UJ | <0.0028 | U | UJ | 6.4 | | J | 1.1 | | J | 74 | | J | 9.6 | | J |
| | | VMP-16-13.5-042512 | 4/25/2012 | 16 | | | <0.018 | U | | 0.001 | J | | <0.0018 | U | | 0.0078 | J | | 46 | | | 36 | | | 1.4 | | |
| | | VMP-16-13.5-073012 | 7/30/2012 | 18 | | | <0.018 | U | | 0.00063 | J | | <0.0018 | U | | <0.092 | U | | 21 | | | 59 | | | 1.1 | | |
| | | VMP-16-13.5-102512 | 10/25/2012 | 16 | | | <0.028 | U | | 0.00051 | J | | <0.0028 | U | | <0.14 | U | | 16 | | | 68 | | | 1.3 | | |
| | | VMP-16-13.5-021413 | 2/14/2013 | 13 | | | <0.13 | U | | 0.0003 | J | | <0.0027 | U | | <0.13 | U | | 9.2 | | | 76 | | | 1.3 | | |
| | 19 ft | VMP-16-19-090210 | 9/2/2010 | 19 | | | <0.025 | U | | 0.0014 | J | | <0.0025 | U | | <0.12 | U | | 51 | | | 28 | | | 0.73 | | |
| | | VMP-16-19-112910 | 11/29/2010 | 17 | | | <0.022 | U | | 0.0012 | J | | <0.0022 | U | | 0.014 | J | | 51 | | | 29 | | | 1.5 | | |
| | | VMP-16-19-021611 | 2/16/2011 | 14 | | | <0.026 | U | | 0.0009 | J | | <0.0026 | U | | 0.016 | J | | 40 | | | 44 | | | 1.3 | | |
| | | VMP-16-19-042711 | 4/27/2011 | 16 | | | <0.026 | U | | 0.00071 | J | | <0.0026 | U | | 3.4 | | | 33 | | | 46 | | | 1.2 | | |
| | | VMP-16-19-042711-DUP | 4/27/2011 | 15 | | | <0.026 | U | | 0.00071 | J | | <0.0026 | U | | 3.6 | | | 31 | | | 48 | | | 1.9 | | |
| | | VMP-16-19-042512 | 4/25/2012 | 16 | | | <0.021 | U | | 0.0011 | J | | <0.0021 | U | | 0.0079 | J | | 50 | | | 32 | | | 0.87 | | |
| | | VMP-16-19-073012 | 7/30/2012 | 14 | | | <0.016 | U | | 0.00086 | J | | <0.0016 | U | | <0.079 | U | | 32 | | | 49 | | | 4 | | |
| | | VMP-16-19-102512 | 10/25/2012 | 16 | | | <0.026 | U | | 0.00096 | J | | <0.0026 | U | | <0.13 | U | | 32 | | | 51 | | | 1 | | |
| | | VMP-16-19-021413 | 2/14/2013 | 14 | | | <0.13 | U | | 0.00076 | J | | <0.0026 | U | | <0.13 | U | | 26 | | | 59 | | | 1.2 | | |
| | 31 ft | VMP-16-31-090310 | 9/3/2010 | 0.09 | | | <0.061 | U | | <0.0061 | U | | <0.0061 | U | | 22 | | | 0.00046 | J | | 62 | | | 16 | | |
| | | VMP-16-31-112910 | 11/29/2010 | 17 | | | <0.022 | U | | 0.0012 | J | | <0.0022 | U | | 0.034 | J | | 51 | | | 29 | | | 1.2 | | |
| | | VMP-16-31-042512 | 4/25/2012 | 16 | | | <0.021 | U | | 0.0011 | J | | <0.0021 | U | | 0.0098 | J | | 51 | | | 31 | | | 0.94 | | |
| | | VMP-16-31-073012 | 7/30/2012 | 15 | | | <0.018 | U | | 0.0011 | J | | <0.0018 | U | | 0.011 | J | | 42 | | | 41 | | | 0.94 | | |
| | | VMP-16-31-102512 | 10/25/2012 | 16 | | | <0.033 | U | | 0.001 | J | | <0.0033 | U | | <0.16 | U | | 36 | | | 47 | | | 1.1 | | |
| | | VMP-16-31-021813 | 2/18/2013 | 15 | | | <0.16 | U | | 0.00089 | J | | <0.0032 | U | | <0.16 | U | | 30 | | | 54 | | | 0.97 | | |

SEE LAST PAGE OF TABLE FOR NOTES

**TABLE 7**
**CUMULATIVE SUMMARY OF SOIL VAPOR ANALYTICAL RESULTS - NATURAL GASES**

| Location | Depth | Sample ID | Sample Date | Carbon Dioxide | | | Carbon Monoxide | | | Ethane | | | Ethene | | | Helium | | | Methane | | | Nitrogen | | | Oxygen | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | Result % | Lab Quals | URS Quals | Result % | Lab Quals | URS Quals | Result % | Lab Quals | URS Quals | Result % | Lab Quals | URS Quals | Result % | Lab Quals | URS Quals | Result % | Lab Quals | URS Quals | Result % | Lab Quals | URS Quals | Result % | Lab Quals | URS Quals |
| VMP-17 | 5 ft | VMP-17-5 | 6/21/2010 | 6.7 | | | <0.029 | U | | <0.0029 | U | | <0.0029 | U | | <0.14 | U | | 0.00014 | J | | 81 | | | 12 | | |
| | | VMP-17-5-DUP | 6/21/2010 | 6.8 | | | <0.03 | U | | <0.003 | U | | <0.003 | U | | <0.15 | U | | 0.00018 | J | | 81 | | | 12 | | |
| | | VMP-17-5-090110 | 9/1/2010 | 7.8 | | | <0.054 | U | | <0.0054 | U | | <0.0054 | U | | 0.089 | J | | <0.00054 | J | U | 80 | | | 12 | | |
| | | VMP-17-5-112210 | 11/22/2010 | 5 | | | <0.027 | U | | <0.0027 | U | | <0.0027 | U | | 0.011 | J | | <0.00027 | U | | 79 | | | 16 | | |
| | | VMP-17-5-020711 | 2/7/2011 | 2 | | | <0.051 | U | | <0.0051 | U | | <0.0051 | U | | <0.25 | U | | 0.00017 | J | | 73 | | | 25 | | |
| | | VMP-17-5-040611 | 4/6/2011 | 3.2 | | | <0.03 | U | | <0.003 | U | | <0.003 | U | | 0.02 | J | | <0.0003 | U | | 79 | | | 18 | | |
| | | VMP-17-5-080111 | 8/1/2011 | 6.2 | | | <0.029 | U | | <0.0029 | U | | <0.0029 | U | | 0.012 | J | | 0.0018 | | | 81 | | | 13 | | |
| | | VMP-17-5-110711 | 11/7/2011 | 3.4 | | | <0.022 | U | | <0.0022 | U | | <0.0022 | U | | 0.0044 | J | | 0.000024 | J | | 78 | | | 18 | | |
| | | VMP-17-5-012612 | 1/26/2012 | 2.8 | | | <0.018 | U | | <0.0018 | U | | <0.0018 | U | | <0.09 | U | | <0.00018 | U | | 79 | | | 18 | | |
| | | VMP-17-5-041112 | 4/11/2012 | 1.1 | | | <0.023 | U | | <0.0023 | U | | <0.0023 | U | | 0.02 | J | | 0.000064 | J | | 79 | | | 20 | | |
| | | VMP-17-5-071112 | 7/11/2012 | 0.69 | | | <0.02 | U | | <0.002 | U | | <0.002 | U | | 0.044 | J | | 0.000051 | J | | 79 | | | 20 | | |
| | | VMP-17-5-100912 | 10/9/2012 | 0.37 | | | <0.03 | U | | <0.003 | U | | <0.003 | U | | 0.089 | | | 0.00003 | J | | 80 | | | 20 | | |
| | | VMP-17-5-013113 | 1/31/2013 | 0.12 | | | <0.13 | U | | <0.0026 | U | | <0.0026 | U | | 0.026 | J | | 0.00018 | J | | 79 | | | 21 | | |
| | | VMP-17-5-013113-DUP | 1/31/2013 | 0.11 | | | <0.13 | U | | <0.0026 | U | | <0.0026 | U | | 0.044 | J | | 0.00035 | | | 80 | | | 20 | | |
| VMP-18 | 8.5 ft | VMP-18-8.5 | 6/18/2010 | 7.7 | | | <0.029 | U | | <0.0029 | U | | <0.0029 | U | | <0.14 | U | | 0.000026 | J | | 81 | | | 11 | | |
| | | VMP-18-8.5-090710 | 9/7/2010 | 9.3 | | | <0.026 | U | | <0.0026 | U | | <0.0026 | U | | 0.021 | J | | 0.00011 | J | | 80 | | | 11 | | |
| | | VMP-18-8.5-111910 | 11/19/2010 | 8.2 | | | <0.022 | U | | <0.0022 | U | | <0.0022 | U | | 0.015 | J | | 0.000054 | J | | 80 | | | 12 | | |
| | | VMP-18-8.5-020711 | 2/7/2011 | 5.6 | | | <0.047 | U | | <0.0047 | U | | <0.0047 | U | | <0.23 | U | | <0.00047 | U | | 79 | | | 15 | | |
| | | VMP-18-8.5-020711-DUP | 2/7/2011 | 5.8 | | | <0.023 | U | | <0.0023 | U | | <0.0023 | U | | 0.029 | J | | <0.00023 | U | | 80 | | | 14 | | |
| | | VMP-18-8.5-040711 | 4/7/2011 | 6.4 | | | <0.026 | U | | <0.0026 | U | | <0.0026 | U | | 0.037 | J | | 0.000047 | J | | 80 | | | 14 | | |
| | | VMP-18-8.5-072811 | 7/28/2011 | 8.2 | | | <0.028 | U | | <0.0028 | U | | <0.0026 | U | | 0.21 | | | <0.00028 | U | | 80 | | | 12 | | |
| | | VMP-18-8.5-110711 | 11/7/2011 | 7 | | | <0.031 | U | | <0.0031 | U | | <0.0031 | U | | 0.088 | J | | 0.0012 | | | 76 | | | 17 | | |
| | | VMP-18-8.5-012312 | 1/23/2012 | 5.1 | | | <0.018 | U | | <0.0018 | U | | <0.0018 | U | | 0.01 | J | | 0.000022 | J | | 78 | | | 17 | | |
| | | VMP-18-8.5-041012 | 4/10/2012 | 4.9 | | | <0.026 | U | | <0.0026 | U | | <0.0026 | U | | 0.039 | J | | 0.000043 | J | | 78 | | | 17 | | |
| | | VMP-18-8.5-071212 | 7/12/2012 | 3.9 | | | <0.02 | U | | <0.002 | U | | <0.002 | U | | 0.025 | J | | 0.000083 | J | | 77 | | | 19 | | |
| | | VMP-18-8.5-100912 | 10/9/2012 | 4.1 | | | <0.026 | U | | <0.0026 | U | | <0.0026 | U | | <0.044 | | U | 0.000084 | J | | 77 | | | 19 | | |
| | | VMP-18-8.5-012313 | 1/23/2013 | 1.5 | | | <0.14 | U | | <0.0029 | U | | <0.0029 | U | | <0.14 | U | | 0.000023 | J | | 78 | | | 21 | | |
| VMP-19 | 5 ft | VMP-19-5 | 6/18/2010 | 8.7 | | | <0.027 | U | | <0.0027 | U | | <0.0027 | U | | 0.03 | | | <0.00027 | U | | 79 | | | 12 | | |
| | | VMP-19-5-090110 | 9/1/2010 | 10 | | | <0.053 | U | | <0.0053 | U | | <0.0053 | U | | 0.049 | J | | 0.00099 | | | 81 | | | 9.1 | | |
| | | VMP-19-5-111510 | 11/15/2010 | 8.5 | | | <0.028 | U | | <0.0028 | U | | <0.0028 | U | | <0.14 | U | | <0.00028 | U | | 80 | | | 12 | | |
| | | VMP-19-5-020411 | 2/4/2011 | 5.8 | | | <0.024 | U | | <0.0024 | U | | <0.0024 | U | | 0.018 | J | | 0.00014 | J | | 79 | | | 15 | | |
| | | VMP-19-5-040711 | 4/7/2011 | 5.8 | | | <0.027 | U | | <0.0027 | U | | <0.0027 | U | | 0.047 | J | | <0.00027 | U | | 78 | | | 16 | | |
| | | VMP-19-5-080911 | 8/9/2011 | 9.1 | | | <0.03 | U | | <0.003 | U | | <0.003 | U | | 0.012 | J | | <0.0003 | U | | 80 | | | 11 | | |
| | | VMP-19-5-080911-DUP | 8/9/2011 | 8.7 | | | <0.028 | U | | <0.0028 | U | | <0.0028 | U | | 0.01 | J | | <0.00028 | U | | 80 | | | 11 | | |
| | | VMP-19-5-110811 | 11/8/2011 | 5.5 | | | <0.025 | U | | <0.0025 | U | | <0.0025 | U | | <0.13 | U | | 0.000045 | J | | 78 | | | 16 | | |
| | | VMP-19-5-012612 | 1/26/2012 | 4.6 | | | <0.017 | U | | <0.0017 | U | | <0.0017 | U | | 0.008 | J | | 0.000058 | J | | 78 | | | 17 | | |
| | | VMP-19-5-041012 | 4/10/2012 | 1.6 | | | <0.025 | U | | <0.0025 | U | | <0.0025 | U | | 0.058 | J | | 0.000046 | J | | 78 | | | 20 | | |
| | | VMP-19-5-071112 | 7/11/2012 | 1.2 | | | <0.022 | U | | <0.0022 | U | | <0.0022 | U | | 0.17 | | | 0.000071 | J | | 79 | | | 20 | | |
| | | VMP-19-5-100912 | 10/9/2012 | 0.51 | | | <0.03 | U | | <0.003 | U | | <0.003 | U | | <0.04 | | U | 0.000068 | J | | 79 | | | 20 | | |
| | | VMP-19-5-013113 | 1/31/2013 | 0.15 | | | <0.13 | U | | <0.0026 | U | | <0.0026 | U | | <0.13 | U | | 0.00042 | | | 79 | | | 21 | | |
| VMP-20 | 5 ft | VMP-20-5-031411 | 3/14/2011 | 9.3 | | | <0.024 | U | | <0.0024 | U | | <0.0024 | U | | 0.012 | J | | 0.00017 | J | | 83 | | | 7.9 | | |
| | | VMP-20-5-041511 | 4/15/2011 | 6.9 | | | <0.027 | U | | <0.0027 | U | | <0.0027 | U | | 0.045 | J | | 0.0014 | | | 83 | | | 9.7 | | |
| | | VMP-20-5-072511 | 7/25/2011 | 14 | | | <0.028 | U | | <0.0028 | U | | <0.0028 | U | | 0.021 | J | | 0.000058 | J | | 78 | | | 7.7 | | |
| | | VMP-20-5-110111 | 11/1/2011 | 7.6 | | | <0.016 | U | | <0.0016 | U | | <0.0016 | U | | 0.033 | J | | 0.000032 | J | | 78 | | | 14 | | |
| | | VMP-20-5-012312 | 1/23/2012 | 4.4 | | | <0.017 | U | | <0.0017 | U | | <0.0017 | U | | 0.0064 | J | | 0.0001 | J | | 78 | | | 18 | | |
| | | VMP-20-5-041012 | 4/10/2012 | 5.1 | | | <0.022 | U | | <0.0022 | U | | <0.0022 | U | | 0.32 | | | 0.000079 | J | | 80 | | | 15 | | |
| | | VMP-20-5-071112 | 7/11/2012 | 8.8 | | | <0.018 | U | | <0.0018 | U | | <0.0018 | U | | 7.1 | | | 0.000067 | J | | 72 | | | 12 | | |
| | | VMP-20-5-073112 | 7/31/2012 | 12 | | | <0.02 | U | | <0.002 | U | | <0.002 | U | | 0.014 | J | | 0.000043 | J | | 76 | | | 12 | | |
| | | VMP-20-5-100412 | 10/4/2012 | 6 | | | <0.029 | U | | <0.0029 | U | | <0.0029 | U | | 0.063 | J | | 0.000051 | J | | 79 | | | 15 | | |
| | | VMP-20-5-020713 | 2/7/2013 | 3.8 | | | <0.12 | U | | <0.0025 | U | | <0.0025 | U | | <0.12 | U | | 0.000078 | J | | 78 | | | 18 | | |
| | 10 ft | VMP-20-10-031411 | 3/14/2011 | 6.8 | | | <0.024 | U | | <0.0024 | U | | <0.0024 | U | | <0.12 | U | | 0.000065 | J | | 83 | | | 10 | | |
| | | VMP-20-10-041511 | 4/15/2011 | 7.3 | | | <0.024 | U | | <0.0024 | U | | <0.0024 | U | | 0.039 | J | | 0.0001 | J | | 83 | | | 9.3 | | |
| | | VMP-20-10-072511 | 7/25/2011 | 8.1 | | | <0.026 | U | | <0.0026 | U | | <0.0026 | U | | 0.01 | J | | 0.00021 | J | | 84 | | | 7.8 | | |
| | | VMP-20-10-110111 | 11/1/2011 | 8.3 | | | <0.017 | U | | <0.0017 | U | | <0.0017 | U | | 0.025 | J | | 0.000063 | J | | 80 | | | 12 | | |
| | | VMP-20-10-012312 | 1/23/2012 | 5.7 | | | <0.016 | U | | <0.0016 | U | | <0.0016 | U | | 0.097 | | | 0.000051 | J | | 79 | | | 15 | | |
| | | VMP-20-10-041012 | 4/10/2012 | 5.9 | | | <0.023 | U | | <0.0023 | U | | <0.0023 | U | | 0.075 | J | | 0.000032 | J | | 81 | | | 13 | | |
| | | VMP-20-10-071112 | 7/11/2012 | 8.5 | | | <0.02 | U | | <0.002 | U | | <0.002 | U | | 0.034 | J | | 0.000028 | J | | 78 | | | 13 | | |
| | | VMP-20-10-100412 | 10/4/2012 | 8.3 | | | <0.027 | U | | <0.0027 | U | | <0.0027 | U | | 0.055 | J | | 0.000037 | J | | 79 | | | 13 | | |
| | | VMP-20-10-012213 | 1/22/2013 | 3.2 | | | <0.12 | U | | <0.0025 | U | | <0.0025 | U | | <0.12 | U | | 0.000027 | J | | 77 | | | 20 | | |
| | 25 ft | VMP-20-25-031411 | 3/14/2011 | 9.4 | | | <0.024 | U | | <0.0024 | U | | <0.0024 | U | | 0.0059 | J | | <0.00024 | U | | 87 | | | 3.2 | | |
| | | VMP-20-25-041511 | 4/15/2011 | 9.8 | | | <0.028 | U | | <0.0028 | U | | <0.0028 | U | | 0.042 | J | | <0.00028 | U | | 88 | | | 2.6 | | |
| | | VMP-20-25-072611 | 7/26/2011 | 8.5 | | | <0.026 | U | | 0.00011 | J | | <0.0026 | U | | 0.01 | J | | 0.23 | | | 89 | | | 1.8 | | |
| | | VMP-20-25-110511 | 11/5/2011 | 9.1 | | | <0.017 | U | | <0.0017 | U | | <0.0017 | U | | 0.0033 | J | | <0.00017 | U | | 88 | | | 2.9 | | |
| | | VMP-20-25-012312 | 1/23/2012 | 7.7 | | | <0.017 | U | | <0.0017 | U | | <0.0017 | U | | <0.084 | U | | 0.00002 | J | | 84 | | | 8.1 | | |
| | | VMP-20-25-041012 | 4/10/2012 | 7.5 | | | <0.023 | U | | <0.0023 | U | | <0.0023 | U | | 0.044 | J | | <0.00023 | U | | 84 | | | 8.7 | | |
| | | VMP-20-25-041012-Dup | 4/10/2012 | 7.6 | | | <0.024 | U | | <0.0024 | U | | <0.0024 | U | | 0.042 | J | | <0.00024 | U | | 84 | | | 8.6 | | |
| | | VMP-20-25-071112 | 7/11/2012 | 7.1 | | | <0.02 | U | | <0.002 | U | | <0.002 | U | | 0.052 | J | | <0.0002 | U | | 82 | | | 11 | | |
| | | VMP-20-25-100412 | 10/4/2012 | 7 | | | <0.03 | U | | <0.003 | U | | <0.003 | U | | 0.056 | J | | <0.0003 | U | | 80 | | | 13 | | |
| | | VMP-20-25-012213 | 1/22/2013 | 6.2 | | | <0.12 | U | | <0.0025 | U | | <0.0025 | U | | <0.12 | U | | 0.000016 | J | | 78 | | | 16 | | |
| | 39.5 ft | VMP-20-39.5-100412 | 10/4/2012 | 9.6 | | | <0.029 | U | | <0.0029 | U | | <0.0029 | U | | 0.084 | J | | 0.12 | | | 89 | | | 1.4 | | |
| | | VMP-20-39.5-012313 | 1/23/2013 | 9.9 | | | <0.12 | U | | <0.0025 | U | | <0.0025 | U | | <0.12 | U | | 0.023 | | | 88 | | | 1.5 | | |

SEE LAST PAGE OF TABLE FOR NOTES

**TABLE 7**
**CUMULATIVE SUMMARY OF SOIL VAPOR ANALYTICAL RESULTS - NATURAL GASES**

| Location | Depth | Sample ID | Sample Date | Carbon Dioxide | | | Carbon Monoxide | | | Ethane | | | Ethene | | | Helium | | | Methane | | | Nitrogen | | | Oxygen | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | Result % | Lab Quals | URS Quals | Result % | Lab Quals | URS Quals | Result % | Lab Quals | URS Quals | Result % | Lab Quals | URS Quals | Result % | Lab Quals | URS Quals | Result % | Lab Quals | URS Quals | Result % | Lab Quals | URS Quals | Result % | Lab Quals | URS Quals |
| VMP-21 | 5 ft | VMP-21-5-020911 | 2/9/2011 | 5.2 | | | <0.023 | U | | 0.00039 | J | | <0.0023 | U | | 0.01 | J | | 0.91 | | | 84 | | | 9.2 | | |
| | | VMP-21-5-020911-DUP | 2/9/2011 | 5.3 | | | <0.024 | U | | 0.00045 | J | | <0.0024 | U | | <0.12 | U | | 0.91 | | | 84 | | | 9.2 | | |
| | | VMP-21-5-041311 | 4/13/2011 | 2 | | | <0.026 | U | | <0.0026 | U | | <0.0026 | U | | 0.16 | | | 0.00056 | | | 81 | | | 17 | | |
| | | VMP-21-5-072511 | 7/25/2011 | 14 | | | <0.07 | U | | <0.007 | U | | <0.007 | U | | 0.018 | J | | 0.00029 | J | | 76 | | | 10 | | |
| | | VMP-21-5-110111 | 11/1/2011 | 4.1 | | | <0.017 | U | | <0.0017 | U | | <0.0017 | U | | 0.1 | | | 0.000034 | J | | 79 | | | 17 | | |
| | | VMP-21-5-012312 | 1/23/2012 | 1.4 | | | <0.018 | U | | <0.0018 | U | | <0.0018 | U | | <0.088 | U | | 0.000039 | J | | 78 | | | 21 | | |
| | | VMP-21-5-012312-DUP | 1/23/2012 | 1.4 | | | <0.016 | U | | <0.0016 | U | | <0.0016 | U | | <0.08 | U | | 0.000033 | J | | 78 | | | 21 | | |
| | | VMP-21-5-042412 | 4/24/2012 | 3.4 | | | <0.018 | U | | <0.0018 | U | | <0.0018 | U | | 0.033 | J | | 0.00045 | | | 80 | | | 17 | | |
| | | VMP-21-5-071012 | 7/10/2012 | 8.2 | | | <0.021 | U | | <0.0021 | U | | <0.0021 | U | | 0.051 | J | | 0.00011 | J | | 78 | | | 14 | | |
| | | VMP-21-5-100412 | 10/4/2012 | 4.1 | | | <0.031 | U | | <0.0031 | U | | <0.0031 | U | | 0.014 | J | | 0.000039 | J | | 79 | | | 17 | | |
| | | VMP-21-5-020613 | 2/6/2013 | 0.92 | | | <0.14 | U | | <0.0028 | U | | <0.0028 | U | | 0.035 | J | | 0.000023 | J | | 79 | | | 20 | | |
| | 10 ft | VMP-21-10-021011 | 2/10/2011 | 6.4 | | | <0.025 | U | | 0.00019 | J | | <0.0025 | U | | 0.3 | | | 0.41 | | | 83 | | | 9.7 | | |
| | | VMP-21-10-041311 | 4/13/2011 | 7.2 | | | <0.026 | U | | <0.0026 | U | | <0.0026 | U | | 0.021 | J | | 0.00032 | | | 83 | | | 9.6 | | |
| | | VMP-21-10-072511 | 7/25/2011 | 6 | | | <0.12 | U | | <0.012 | U | | <0.012 | U | | <0.59 | U | | 0.00021 | J | | 68 | | | 26 | | |
| | | VMP-21-10-110111 | 11/1/2011 | 7.2 | | | <0.017 | U | | <0.0017 | U | | <0.0017 | U | | 0.023 | J | | 0.000031 | J | | 79 | | | 14 | | |
| | | VMP-21-10-012312 | 1/23/2012 | 4.7 | | | <0.018 | U | | <0.0018 | U | | <0.0018 | U | | <0.088 | U | | 0.000031 | J | | 78 | | | 17 | | |
| | | VMP-21-10-040912 | 4/9/2012 | 2.7 | | | <0.023 | U | | <0.0023 | U | | <0.0023 | U | | 0.034 | J | | 0.000029 | J | | 85 | | | 12 | | |
| | | VMP-21-10-071012 | 7/10/2012 | 6.4 | | | <0.02 | U | | <0.002 | U | | <0.002 | U | | 0.13 | | | 0.000029 | J | | 79 | | | 14 | | |
| | | VMP-21-10-100412 | 10/4/2012 | 6.6 | | | <0.028 | U | | <0.0028 | U | | <0.0028 | U | | 0.017 | J | | 0.000019 | J | | 79 | | | 14 | | |
| | | VMP-21-10-020513 | 2/5/2013 | 3.4 | | | <0.13 | U | | <0.0027 | U | | <0.0027 | U | | <0.13 | U | | 0.000019 | J | | 79 | | | 18 | | |
| | | VMP-21-10-020513-DUP | 2/5/2013 | 3.5 | | | <0.13 | U | | <0.0025 | U | | <0.0025 | U | | <0.13 | U | | 0.000023 | J | | 78 | | | 18 | | |
| | 25 ft | VMP-21-25-021011 | 2/10/2011 | 6.4 | | | <0.023 | U | | 0.0017 | J | | <0.0023 | U | | 0.0092 | J | | 3.6 | | | 87 | | | 1.5 | | |
| | | VMP-21-25-041411 | 4/14/2011 | 6.1 | | | <0.026 | U | | 0.0018 | J | | <0.0026 | U | | 0.023 | J | | 3.9 | | | 86 | | | 1.7 | | |
| | | VMP-21-25-041411-DUP | 4/14/2011 | 6.1 | | | <0.026 | U | | 0.0018 | J | | <0.0026 | U | | 0.063 | J | | 3.9 | | | 86 | | | 1.9 | | |
| | | VMP-21-25-072611 | 7/26/2011 | 5.6 | | | <0.026 | U | | 0.00088 | J | | <0.0026 | U | | 0.22 | | | 2.3 | | | 89 | | | 1.7 | | |
| | | VMP-21-25-110511 | 11/5/2011 | 9.1 | | | <0.017 | U | | 0.000086 | J | | <0.0017 | U | | 0.0034 | J | | 0.24 | | | 89 | | | 2 | | |
| | | VMP-21-25-012412 | 1/24/2012 | 12 | | | <0.016 | U | | <0.0016 | U | | <0.0016 | U | | 0.081 | | | 0.0098 | | | 86 | | | 2.2 | | |
| | | VMP-21-25-040912 | 4/9/2012 | 12 | | | <0.03 | U | | <0.003 | U | | <0.003 | U | | 0.076 | J | | 0.00044 | | | 85 | | | 2.9 | | |
| | | VMP-21-25-071112 | 7/11/2012 | 10 | | | <0.018 | U | | <0.0018 | U | | <0.0018 | U | | 0.037 | J | | 0.000086 | J | | 84 | | | 6.4 | | |
| | | VMP-21-25-100412 | 10/4/2012 | 8.9 | | | <0.029 | U | | <0.0029 | U | | <0.0029 | U | | 0.037 | J | | 0.000058 | J | | 81 | | | 10 | | |
| | | VMP-21-25-020513 | 2/5/2013 | 8.7 | | | <0.13 | U | | <0.0026 | U | | <0.0026 | U | | 0.02 | J | | 0.000043 | J | | 80 | | | 11 | | |
| | | VMP-21-25-020513-DUP | 2/5/2013 | 8.8 | | | <0.13 | U | | <0.0027 | U | | <0.0027 | U | | 0.058 | | | 0.000036 | J | | 80 | | | 11 | | |
| | 33 ft | VMP-21-33-021011 | 2/10/2011 | 5.8 | | | <0.023 | U | | 0.0015 | J | | <0.0023 | U | | 0.15 | | | 3.7 | | | 86 | | | 1.9 | | |
| | | VMP-21-33-041411 | 4/14/2011 | 6 | | | <0.027 | U | | 0.0018 | J | | <0.0027 | U | | 0.026 | J | | 4 | | | 86 | | | 1.6 | | |
| | | VMP-21-33-110511 | 11/5/2011 | 7 | | | <0.019 | U | | <0.0019 | U | | <0.0019 | U | | 0.003 | J | | 0.2 | | | 91 | | | 1.9 | | |
| | | VMP-21-33-012412 | 1/24/2012 | 11 | | | <0.016 | U | | <0.0016 | U | | <0.0016 | U | | <0.082 | U | | 0.046 | | | 86 | | | 2.5 | | |
| | | VMP-21-33-042412 | 4/24/2012 | 12 | | | <0.029 | U | | <0.0029 | U | | <0.0029 | U | | <0.14 | U | | 0.0017 | | | 85 | | | 2.6 | | |
| | | VMP-21-33-071112 | 7/11/2012 | 12 | | | <0.02 | U | | <0.002 | U | | <0.002 | U | | 0.056 | J | | 0.00016 | J | | 85 | | | 2.6 | | |
| | | VMP-21-33-100412 | 10/4/2012 | 10 | | | <0.028 | U | | <0.0028 | U | | <0.0028 | U | | 0.019 | J | | 0.000088 | J | | 83 | | | 7 | | |
| | | VMP-21-33-020513 | 2/5/2013 | 10 | | | <0.13 | U | | <0.0026 | U | | <0.0026 | U | | <0.13 | U | | 0.000073 | J | | 81 | | | 9.1 | | |
| VMP-22 | 5 ft | VMP-22-5-021111 | 2/11/2011 | 8.4 | | | <0.026 | U | | <0.0026 | U | | <0.0026 | U | | 0.06 | J | | 0.0078 | | | 84 | | | 8 | | |
| | | VMP-22-5-041811 | 4/18/2011 | 7.1 | | | <0.025 | U | | <0.0025 | U | | <0.0025 | U | | 0.092 | J | | <0.00025 | U | | 83 | | | 9.9 | | |
| | | VMP-22-5-072611 | 7/26/2011 | 7.4 | | | <0.055 | U | | <0.0055 | U | | <0.0055 | U | | 0.015 | J | | <0.00055 | U | | 80 | | | 12 | | |
| | | VMP-22-5-110111 | 11/1/2011 | 2.6 | | | <0.017 | U | | <0.0017 | U | | <0.0017 | U | | 0.013 | J | | 0.00004 | J | | 79 | | | 18 | | |
| | | VMP-22-5-012412 | 1/24/2012 | 0.7 | | | <0.017 | U | | <0.0017 | U | | <0.0017 | U | | <0.084 | U | | 0.000062 | J | | 79 | | | 20 | | |
| | | VMP-22-5-040912 | 4/9/2012 | 0.81 | | | <0.032 | U | | <0.0032 | U | | <0.0032 | U | | 0.077 | J | | 0.000038 | J | | 80 | | | 19 | | |
| | | VMP-22-5-070912 | 7/9/2012 | 3 | | | <0.022 | U | | <0.0022 | U | | <0.0022 | U | | 0.14 | | | 0.00011 | J | | 78 | | | 19 | | |
| | | VMP-22-5-100312 | 10/3/2012 | 1 | | | <0.025 | U | | <0.0025 | U | | <0.0025 | U | | 1.5 | | | 0.000072 | J | | 78 | | | 19 | | |
| | | VMP-22-5-100312-Dup | 10/3/2012 | 0.9 | | | <0.023 | U | | <0.0023 | U | | <0.0023 | U | | 0.45 | | | 0.000098 | J | | 79 | | | 20 | | |
| | | VMP-22-5-012413 | 1/24/2013 | 0.38 | | | <0.13 | U | | <0.0026 | U | | <0.0026 | U | | <0.13 | U | | 0.000048 | J | | 79 | | | 21 | | |
| | 10 ft | VMP-22-10-021111 | 2/11/2011 | 10 | | | <0.024 | U | | <0.0024 | U | | <0.0024 | U | | 0.031 | J | | 0.0034 | | | 84 | | | 5.5 | | |
| | | VMP-22-10-041811 | 4/18/2011 | 8.9 | | | <0.026 | U | | <0.0026 | U | | <0.0026 | U | | 0.044 | J | | <0.00026 | U | | 82 | | | 9.3 | | |
| | | VMP-22-10-072611 | 7/26/2011 | 10 | | | <0.03 | U | | <0.003 | U | | <0.003 | U | | <0.15 | U | | 0.00016 | J | | 85 | | | 4.9 | | |
| | | VMP-22-10-072611-DUP | 7/26/2011 | 10 | | | <0.036 | U | | <0.0036 | U | | <0.0036 | U | | <0.18 | U | | 0.00015 | J | | 85 | | | 5 | | |
| | | VMP-22-10-110211 | 11/2/2011 | 5.3 | | | <0.017 | U | | <0.0017 | U | | <0.0017 | U | | 0.015 | J | | <0.00017 | U | | 79 | | | 16 | | |
| | | VMP-22-10-012412 | 1/24/2012 | 2.2 | | | <0.018 | U | | <0.0018 | U | | <0.0018 | U | | 0.0065 | J | | 0.000016 | J | | 77 | | | 21 | | |
| | | VMP-22-10-040912 | 4/9/2012 | 1.2 | | | <0.033 | U | | <0.0033 | U | | <0.0033 | U | | 0.1 | J | | 0.000046 | J | | 78 | | | 20 | | |
| | | VMP-22-10-070912 | 7/9/2012 | 3.4 | | | <0.022 | U | | <0.0022 | U | | <0.0022 | U | | 0.044 | J | | 0.000027 | J | | 78 | | | 18 | | |
| | | VMP-22-10-070912-Dup | 7/9/2012 | 3.5 | | | <0.021 | U | | <0.0021 | U | | <0.0021 | U | | 0.043 | J | | 0.000029 | J | | 78 | | | 18 | | |
| | | VMP-22-10-100312 | 10/3/2012 | 1.5 | | | <0.024 | U | | <0.0024 | U | | <0.0024 | U | | 0.047 | J | | 0.000044 | J | | 80 | | | 19 | | |
| | | VMP-22-10-012413 | 1/24/2013 | 0.68 | | | <0.14 | U | | <0.0028 | U | | <0.0028 | U | | <0.14 | U | | 0.000022 | J | | 79 | | | 20 | | |
| | 18 ft | VMP-22-18-021111 | 2/11/2011 | 11 | | | <0.026 | U | | 0.0008 | J | | <0.0026 | U | | 0.014 | J | | 1.5 | | | 85 | | | 1.7 | | |
| | | VMP-22-18-041811 | 4/18/2011 | 11 | | | <0.027 | U | | 0.0007 | J | | <0.0027 | U | | 0.027 | J | | 1.5 | | | 86 | | | 1.6 | | |
| | | VMP-22-18-072611 | 7/26/2011 | 10 | | | <0.056 | U | | 0.00046 | J | | <0.0056 | U | | 0.019 | J | | 0.9 | | | 84 | | | 5.3 | | |
| | | VMP-22-18-110511 | 11/5/2011 | 14 | | | <0.018 | U | | <0.0018 | U | | <0.0018 | U | | 0.019 | J | | 0.000043 | J | | 84 | | | 2.4 | | |
| | | VMP-22-18-012412 | 1/24/2012 | 10 | | | <0.017 | U | | <0.0017 | U | | <0.0017 | U | | <0.084 | U | | 0.000023 | J | | 80 | | | 9.7 | | |
| | | VMP-22-18-040912 | 4/9/2012 | 5.3 | | | <0.048 | U | | <0.0048 | U | | <0.0048 | U | | 0.14 | J | | <0.00048 | U | | 81 | | | 14 | | |
| | | VMP-22-18-070912 | 7/9/2012 | 5 | | | <0.021 | U | | <0.0021 | U | | <0.0021 | U | | 0.092 | J | | 0.000019 | J | | 78 | | | 17 | | |
| | | VMP-22-18-100412 | 10/4/2012 | 2.9 | | | <0.029 | U | | <0.0029 | U | | <0.0029 | U | | 0.029 | J | | 0.000018 | J | | 78 | | | 19 | | |
| | | VMP-22-18-012413 | 1/24/2013 | 2.2 | | | <0.14 | U | | <0.0028 | U | | <0.0028 | U | | <0.14 | U | | <0.00028 | U | | 78 | | | 20 | | |
| | 38 ft | VMP-22-38-041811 | 4/18/2011 | 11 | | | <0.028 | U | | 0.0011 | J | | <0.0028 | U | | 0.023 | J | | 2.1 | | | 84 | | | 1.9 | | |
| | | VMP-22-38-012512 | 1/25/2012 | 15 | | | <0.017 | U | | <0.0017 | U | | <0.0017 | U | | <0.084 | U | | 0.0076 | | | 83 | | | 1.8 | | |
| | | VMP-22-38-040912 | 4/9/2012 | 10 | | | <0.03 | U | | <0.003 | U | | <0.003 | U | | 0.086 | J | | 0.00012 | J | | 80 | | | 10 | | |
| | | VMP-22-38-070912 | 7/9/2012 | 6.7 | | | <0.021 | U | | <0.0021 | U | | <0.0021 | U | | 0.077 | J | | 0.000019 | J | | 78 | | | 15 | | |
| | | VMP-22-38-100412 | 10/4/2012 | 5.5 | | | <0.03 | U | | <0.003 | U | | <0.003 | U | | 0.063 | J | | 0.000021 | J | | 78 | | | 16 | | |
| | | VMP-22-38-012413 | 1/24/2013 | 5.1 | | | <0.13 | U | | <0.0027 | U | | <0.0027 | U | | <0.13 | U | | 0.00012 | J | | 77 | | | 18 | | |

SEE LAST PAGE OF TABLE FOR NOTES

**TABLE 7**
**CUMULATIVE SUMMARY OF SOIL VAPOR ANALYTICAL RESULTS - NATURAL GASES**

| Location | Depth | Sample ID | Sample Date | Carbon Dioxide | | | Carbon Monoxide | | | Ethane | | | Ethene | | | Helium | | | Methane | | | Nitrogen | | | Oxygen | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | Result % | Lab Quals | URS Quals | Result % | Lab Quals | URS Quals | Result % | Lab Quals | URS Quals | Result % | Lab Quals | URS Quals | Result % | Lab Quals | URS Quals | Result % | Lab Quals | URS Quals | Result % | Lab Quals | URS Quals | Result % | Lab Quals | URS Quals |
| VMP-23 | 5 ft | VMP-23-5-021511 | 2/15/2011 | 1.8 | | | <0.026 | U | | <0.0026 | U | | <0.0026 | U | | 0.1 | J | | 0.00015 | J | | 79 | | | 19 | | |
| | | VMP-23-5-042111 | 4/21/2011 | 4.2 | | | <0.023 | U | | <0.0023 | U | | <0.0023 | U | | 0.063 | J | | 0.000072 | J | | 79 | | | 17 | | |
| | | VMP-23-5-072711 | 7/27/2011 | 7.7 | | | <0.026 | U | | <0.0026 | U | | <0.0026 | U | | 0.018 | J | | 0.00018 | J | | 82 | | | 10 | | |
| | | VMP-23-5-110211 | 11/2/2011 | 2.6 | | | <0.019 | U | | <0.0019 | U | | <0.0019 | U | | 0.12 | | | 0.000057 | J | | 79 | | | 18 | | |
| | | VMP-23-5-012512 | 1/25/2012 | 1.9 | | | <0.016 | U | | <0.0016 | U | | <0.0016 | U | | 0.0075 | J | | 0.00011 | J | | 78 | | | 20 | | |
| | | VMP-23-5-040912 | 4/9/2012 | 0.76 | | | <0.031 | U | | <0.0031 | U | | <0.0031 | U | | <0.15 | U | | 0.00015 | J | | 79 | | | 20 | | |
| | | VMP-23-5-070912 | 7/9/2012 | 1.5 | | | <0.017 | U | | <0.0017 | U | | <0.0017 | U | | 0.14 | | | 0.00028 | | | 78 | | | 20 | | |
| | | VMP-23-5-100312 | 10/3/2012 | 0.6 | | | <0.029 | U | | <0.0029 | U | | <0.0029 | U | | 0.053 | J | | 0.000088 | J | | 80 | | | 19 | | |
| | | VMP-23-5-012413 | 1/24/2013 | 0.2 | | | <0.12 | U | | <0.0025 | U | | <0.0025 | U | | <0.12 | U | | 0.00017 | J | | 79 | | | 21 | | |
| | 10 ft | VMP-23-10-021511 | 2/15/2011 | 8.1 | | | <0.027 | U | | <0.0027 | U | | <0.0027 | U | | 0.022 | J | | <0.00027 | U | | 82 | | | 10 | | |
| | | VMP-23-10-042111 | 4/21/2011 | 6.2 | | | <0.028 | U | | <0.0028 | U | | <0.0028 | U | | 1.5 | | | <0.00028 | U | | 79 | | | 13 | | |
| | | VMP-23-10-072711 | 7/27/2011 | 9.4 | | | <0.025 | U | | <0.0025 | U | | <0.0025 | U | | 0.045 | J | | <0.00025 | U | | 84 | | | 6.6 | | |
| | | VMP-23-10-110211 | 11/2/2011 | 7.5 | | | <0.018 | U | | <0.0018 | U | | <0.0018 | U | | 0.0091 | J | | 0.000037 | J | | 82 | | | 10 | | |
| | | VMP-23-10-012512 | 1/25/2012 | 4.4 | | | <0.016 | U | | <0.0016 | U | | <0.0016 | U | | 0.026 | J | | 0.000064 | J | | 79 | | | 17 | | |
| | | VMP-23-10-040912 | 4/9/2012 | 0.83 | | | <0.026 | U | | <0.0026 | U | | <0.0026 | U | | <0.13 | U | | 0.00012 | J | | 77 | | | 22 | | |
| | | VMP-23-10-040912-Dup | 4/9/2012 | 0.96 | | | <0.032 | U | | <0.0032 | U | | <0.0032 | U | | <0.16 | U | | 0.00007 | J | | 80 | | | 19 | | |
| | | VMP-23-10-070912 | 7/9/2012 | 1.6 | | | <0.016 | U | | <0.0016 | U | | <0.0016 | U | | 0.036 | J | | 0.000093 | J | | 78 | | | 20 | | |
| | | VMP-23-10-100312 | 10/3/2012 | 0.8 | | | <0.031 | U | | <0.0031 | U | | <0.0031 | U | | 0.051 | J | | 0.000064 | J | | 79 | | | 20 | | |
| | | VMP-23-10-012413 | 1/24/2013 | 0.34 | | | <0.12 | U | | <0.0025 | U | | <0.0025 | U | | <0.12 | U | | 0.000098 | J | | 79 | | | 21 | | |
| | 25 ft | VMP-23-25-021511 | 2/15/2011 | 14 | | | <0.025 | U | | <0.0025 | U | | <0.0025 | U | | 0.02 | J | | 0.000065 | J | | 84 | | | 1.9 | | |
| | | VMP-23-25-042111 | 4/21/2011 | 13 | | | <0.026 | U | | <0.0026 | U | | <0.0026 | U | | 0.08 | J | | 0.00036 | | | 84 | | | 3.1 | | |
| | | VMP-23-25-072711 | 7/27/2011 | 12 | | | <0.029 | U | | <0.0029 | U | | <0.0029 | U | | 0.0063 | J | | 0.0011 | | | 86 | | | 1.9 | | |
| | | VMP-23-25-110511 | 11/5/2011 | 11 | | | <0.018 | U | | <0.0018 | U | | <0.0018 | U | | 0.005 | J | | 0.000029 | J | | 84 | | | 5.2 | | |
| | | VMP-23-25-012512 | 1/25/2012 | 12 | | | <0.016 | U | | <0.0016 | U | | <0.0016 | U | | 0.25 | | | <0.00016 | U | | 81 | | | 6.8 | | |
| | | VMP-23-25-040912 | 4/9/2012 | 5 | | | <0.031 | U | | <0.0031 | U | | <0.0031 | U | | 0.07 | J | | 0.000089 | J | | 78 | | | 17 | | |
| | | VMP-23-25-071012 | 7/10/2012 | 4.4 | | | <0.024 | U | | <0.0024 | U | | <0.0024 | U | | 0.17 | | | <0.00024 | U | | 79 | | | 16 | | |
| | | VMP-23-25-100312 | 10/3/2012 | 3.6 | | | <0.03 | U | | <0.003 | U | | <0.003 | U | | 0.059 | J | | <0.0003 | U | | 79 | | | 17 | | |
| | | VMP-23-25-012413 | 1/24/2013 | 3.2 | | | <0.13 | U | | <0.0025 | U | | <0.0025 | U | | <0.13 | U | | <0.00025 | U | | 78 | | | 19 | | |
| | 40 ft | VMP-23-40-071012 | 7/10/2012 | 0.041 | | | <0.021 | U | | <0.0021 | U | | <0.0021 | U | | 39 | | | 0.00014 | J | | 49 | | | 12 | | |
| | | VMP-23-40-100312 | 10/3/2012 | 5.6 | | | <0.029 | U | | <0.0029 | U | | <0.0029 | U | | 0.081 | J | | 0.000031 | J | | 79 | | | 15 | | |
| | | VMP-23-40-012413 | 1/24/2013 | 5.2 | | | <0.13 | U | | <0.0026 | U | | <0.0026 | U | | <0.13 | U | | <0.00026 | U | | 78 | | | 17 | | |
| VMP-24 | 5 ft | VMP-24-5-021611 | 2/16/2011 | 6.5 | | | <0.028 | U | | <0.0028 | U | | <0.0028 | U | | 0.016 | J | | 0.00015 | J | | 79 | | | 14 | | |
| | | VMP-24-5-040811 | 4/8/2011 | 4.7 | | | <0.023 | U | | <0.0023 | U | | <0.0023 | U | | 0.013 | J | | 0.0024 | | | 78 | | | 17 | | |
| | | VMP-24-5-072811 | 7/28/2011 | 6.6 | | | <0.028 | U | | <0.0028 | U | | <0.0028 | U | | 0.71 | | | 0.00016 | J | | 77 | | | 16 | | |
| | | VMP-24-5-110211 | 11/2/2011 | 8.2 | | | <0.019 | U | | <0.0019 | U | | <0.0019 | U | | <0.094 | U | | 0.000056 | J | | 79 | | | 13 | | |
| | | VMP-24-5-110211-DUP | 11/2/2011 | 8.2 | | | <0.019 | U | | <0.0019 | U | | <0.0019 | U | | 0.0044 | J | | 0.000037 | J | | 79 | | | 13 | | |
| | | VMP-24-5-012512 | 1/25/2012 | 3.5 | | | <0.016 | U | | <0.0016 | U | | <0.0016 | U | | 0.0065 | J | | 0.00019 | | | 78 | | | 18 | | |
| | | VMP-24-5-040912 | 4/9/2012 | 4.1 | | | <0.019 | U | | <0.0019 | U | | <0.0019 | U | | 0.14 | | | 0.000095 | J | | 78 | | | 18 | | |
| | | VMP-24-5-071212 | 7/12/2012 | 4.9 | | | <0.018 | U | | <0.0018 | U | | <0.0018 | U | | 0.037 | J | | 0.00011 | J | | 78 | | | 17 | | |
| | | VMP-24-5-101912 | 10/19/2012 | 3.5 | | | <0.028 | U | | <0.0028 | U | | <0.0028 | U | | 0.019 | J | | 0.00012 | J | | 80 | | | 17 | | |
| | | VMP-24-5-012313 | 1/23/2013 | 3.6 | | | <0.13 | U | | <0.0025 | U | | <0.0025 | U | | <0.13 | U | | 0.000085 | J | | 78 | | | 18 | | |
| | 10 ft | VMP-24-10-021711 | 2/17/2011 | 9 | | | <0.027 | U | | <0.0027 | U | | <0.0027 | U | | 0.02 | J | | 0.000078 | J | | 79 | | | 12 | | |
| | | VMP-24-10-041111 | 4/11/2011 | 6.8 | | | <0.025 | U | | <0.0025 | U | | <0.0025 | U | | 0.051 | J | | 0.00015 | J | | 77 | | | 16 | | |
| | | VMP-24-10-072811 | 7/28/2011 | 8.9 | | | <0.028 | U | | <0.0028 | U | | <0.0028 | U | | 0.0098 | J | | 0.00013 | J | | 79 | | | 12 | | |
| | | VMP-24-10-110211 | 11/2/2011 | 9.3 | | | <0.016 | U | | <0.0016 | U | | <0.0016 | U | | 0.014 | J | | 0.000067 | J | | 79 | | | 12 | | |
| | | VMP-24-10-012512 | 1/25/2012 | 7.2 | | | <0.016 | U | | <0.0016 | U | | <0.0016 | U | | <0.078 | U | | 0.00011 | J | | 78 | | | 15 | | |
| | | VMP-24-10-041012 | 4/10/2012 | 5.7 | | | <0.018 | U | | <0.0018 | U | | <0.0018 | U | | 0.052 | J | | 0.00005 | J | | 77 | | | 17 | | |
| | | VMP-24-10-071212 | 7/12/2012 | 7.2 | | | <0.021 | U | | <0.0021 | U | | <0.0021 | U | | 0.11 | | | 0.000027 | J | | 78 | | | 15 | | |
| | | VMP-24-10-100912 | 10/9/2012 | 6.3 | | | <0.026 | U | | <0.0026 | U | | <0.0026 | U | | 0.07 | | | 0.000072 | J | | 78 | | | 16 | | |
| | | VMP-24-10-012313 | 1/23/2013 | 5.3 | | | <0.14 | U | | <0.0028 | U | | <0.0028 | U | | <0.14 | U | | 0.000057 | J | | 78 | | | 17 | | |
| | 22 ft | VMP-24-22-021711 | 2/17/2011 | 9.7 | | | <0.027 | U | | <0.0027 | U | | <0.0027 | U | | 0.16 | | | 0.00031 | | | 78 | | | 12 | | |
| | | VMP-24-22-041111 | 4/11/2011 | 9.3 | | | <0.025 | U | | <0.0025 | U | | <0.0025 | U | | 0.021 | J | | <0.00025 | U | | 78 | | | 13 | | |
| | | VMP-24-22-072811 | 7/28/2011 | 9.6 | | | <0.025 | U | | <0.0025 | U | | <0.0025 | U | | 0.0046 | J | | 0.00016 | J | | 78 | | | 12 | | |
| | | VMP-24-22-072811-Dup | 7/28/2011 | 9.7 | | | <0.029 | U | | <0.0029 | U | | <0.0029 | U | | <0.14 | U | | 0.00017 | J | | 78 | | | 12 | | |
| | | VMP-24-22-110611 | 11/6/2011 | 7.9 | | | <0.018 | U | | <0.0018 | U | | <0.0018 | U | | 0.21 | | | 0.00011 | J | | 78 | | | 14 | | |
| | | VMP-24-22-012512 | 1/25/2012 | 9 | | | <0.016 | U | | <0.0016 | U | | <0.0016 | U | | 0.23 | | | 0.00011 | J | | 77 | | | 14 | | |
| | | VMP-24-22-041012 | 4/10/2012 | 7.7 | | | <0.018 | U | | <0.0018 | U | | <0.0018 | U | | 0.075 | J | | 0.000038 | J | | 77 | | | 15 | | |
| | | VMP-24-22-071212 | 7/12/2012 | 7.3 | | | <0.022 | U | | <0.0022 | U | | <0.0022 | U | | 0.083 | J | | 0.000028 | J | | 78 | | | 15 | | |
| | | VMP-24-22-100912 | 10/9/2012 | 7.7 | | | <0.027 | U | | <0.0027 | U | | <0.0027 | U | | 0.018 | J | | 0.000033 | J | | 77 | | | 15 | | |
| | | VMP-24-22-012313 | 1/23/2013 | 6.4 | | | <0.14 | U | | <0.0028 | U | | <0.0028 | U | | <0.14 | U | | 0.000033 | J | | 77 | | | 17 | | |
| | 34 ft | VMP-24-34-021711 | 2/17/2011 | 10 | | | <0.027 | U | | <0.0027 | U | | <0.0027 | U | | 0.15 | | | 0.000049 | J | | 79 | | | 11 | | |
| | | VMP-24-34-041111 | 4/11/2011 | 9.4 | | | <0.024 | U | | <0.0024 | U | | <0.0024 | U | | 0.085 | J | | <0.00024 | U | | 78 | | | 13 | | |
| | | VMP-24-34-072811 | 7/28/2011 | 7.5 | | | <0.021 | U | | <0.0021 | U | | <0.0021 | U | | 0.024 | J | | 0.00014 | J | | 78 | | | 14 | | |
| | | VMP-24-34-110611 | 11/6/2011 | 6.7 | | | <0.014 | U | | <0.0014 | U | | <0.0014 | U | | 0.0045 | J | | 0.000074 | J | | 78 | | | 15 | | |
| | | VMP-24-34-012512 | 1/25/2012 | 7.6 | | | <0.017 | U | | <0.0017 | U | | <0.0017 | U | | <0.084 | U | | 0.000091 | J | | 77 | | | 15 | | |
| | | VMP-24-34-041012 | 4/10/2012 | 4.9 | | | <0.019 | U | | <0.0019 | U | | <0.0019 | U | | 0.12 | | | 0.000071 | J | | 78 | | | 17 | | |
| | | VMP-24-34-071212 | 7/12/2012 | 6.7 | | | <0.018 | U | | <0.0018 | U | | <0.0018 | U | | 0.048 | J | | 0.000054 | J | | 78 | | | 15 | | |
| | | VMP-24-34-100912 | 10/9/2012 | 6.7 | | | <0.028 | U | | <0.0028 | U | | <0.0028 | U | | 0.025 | J | | 0.00017 | J | | 77 | | | 16 | | |
| | | VMP-24-34-012313 | 1/23/2013 | 4.7 | | | <0.14 | U | | <0.0029 | U | | <0.0029 | U | | <0.14 | U | | 0.00005 | J | | 78 | | | 17 | | |

SEE LAST PAGE OF TABLE FOR NOTES

**TABLE 7**
**CUMULATIVE SUMMARY OF SOIL VAPOR ANALYTICAL RESULTS - NATURAL GASES**

| Location | Depth | Sample ID | Sample Date | Carbon Dioxide | | | Carbon Monoxide | | | Ethane | | | Ethene | | | Helium | | | Methane | | | Nitrogen | | | Oxygen | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | Result % | Lab Quals | URS Quals | Result % | Lab Quals | URS Quals | Result % | Lab Quals | URS Quals | Result % | Lab Quals | URS Quals | Result % | Lab Quals | URS Quals | Result % | Lab Quals | URS Quals | Result % | Lab Quals | URS Quals | Result % | Lab Quals | URS Quals |
| VMP-25 | 5 ft | VMP-25-5-031511 | 3/15/2011 | 4.5 | | | <0.024 | U | | <0.0024 | U | | <0.0024 | U | | <0.12 | U | | 0.044 | | | 93 | | | 2.9 | | |
| | | VMP-25-5-040811 | 4/8/2011 | 6.9 | | | <0.028 | U | | <0.0028 | U | | <0.0028 | U | | 0.024 | J | | 0.0036 | | | 90 | | | 3.4 | | |
| | | VMP-25-5-080911 | 8/9/2011 | 5.3 | | | <0.023 | U | | <0.0023 | U | | <0.0023 | U | | 0.012 | J | | 0.00094 | | | 81 | | | 14 | | |
| | | VMP-25-5-080911-DUP | 8/9/2011 | 7.8 | | | <0.02 | U | | <0.002 | U | | <0.002 | U | | 0.25 | | | 0.0013 | | | 180 | | | 11 | | |
| | | VMP-25-5-111711 | 11/17/2011 | 3.2 | | | <0.017 | U | | <0.0017 | U | | <0.0017 | U | | <0.084 | U | | 0.000071 | J | | 86 | | | 11 | | |
| | | VMP-25-5-013112 | 1/31/2012 | 2.5 | | | <0.018 | U | | <0.0018 | U | | <0.0018 | U | | <0.092 | U | | 0.0001 | J | | 86 | | | 11 | | |
| | | VMP-25-5-042512 | 4/25/2012 | 5.9 | | | <0.025 | U | | <0.0025 | U | | <0.0025 | U | | <0.13 | U | | 0.00005 | J | | 84 | | | 10 | | |
| | | VMP-25-5-072612 | 7/26/2012 | 12 | | | <0.02 | U | | <0.002 | U | | <0.002 | U | | 0.075 | J | | 0.0021 | | | 81 | | | 6.5 | | |
| | | VMP-25-5-102612 | 10/26/2012 | 4.3 | | | <0.027 | U | | <0.0027 | U | | <0.0027 | U | | 0.026 | J | | 0.0002 | J | | 86 | | | 10 | | |
| | | VMP-25-5-030613 | 3/6/2013 | 1.9 | | | <0.026 | U | | <0.0026 | U | | <0.0026 | U | | <0.13 | U | | 0.00025 | J | | 81 | | | 17 | | |
| | 21 ft | VMP-25-21-031511 | 3/15/2011 | 15 | | | <0.024 | U | | 0.029 | | | <0.0024 | U | | <0.12 | U | | 30 | | | 50 | | | 1.1 | | |
| | | VMP-25-21-031511-DUP | 3/15/2011 | 14 | | | <0.024 | U | | 0.029 | | | <0.0024 | U | | <0.12 | U | | 29 | | | 52 | | | 1.2 | | |
| | | VMP-25-21-040811 | 4/8/2011 | 14 | | | <0.025 | U | | 0.02 | | | <0.0025 | U | | 0.009 | J | | 26 | | | 54 | | | 2.8 | | |
| | | VMP-25-21-040811-DUP | 4/8/2011 | 13 | | | <0.026 | U | | 0.02 | | | <0.0026 | U | | 0.026 | J | | 25 | | | 56 | | | 3.3 | | |
| | | VMP-25-21-080911 | 8/9/2011 | 9.2 | | | <0.026 | U | | 0.016 | | | <0.0026 | U | | 0.0086 | J | | 22 | | | 61 | | | 7.3 | | |
| | | VMP-25-21-111711 | 11/17/2011 | 13 | | | <0.017 | U | | 0.019 | | | <0.0017 | U | | 0.0055 | J | | 26 | | | 54 | | | 3.8 | | |
| | | VMP-25-21-111711-DUP | 11/17/2011 | 13 | | | <0.017 | U | | 0.019 | | | <0.0017 | U | | 0.0039 | J | | 26 | | | 54 | | | 4 | | |
| | | VMP-25-21-013112 | 1/31/2012 | 15 | | | <0.018 | U | | 0.022 | | | <0.0018 | U | | <0.088 | U | | 30 | | | 51 | | | 1.2 | | |
| | | VMP-25-21-013112-DUP | 2/1/2012 | 15 | | | <0.018 | U | | 0.022 | | | <0.0018 | U | | <0.088 | U | | 30 | | | 51 | | | 1.1 | | |
| | | VMP-25-21-042512 | 4/25/2012 | 14 | | | <0.018 | U | | 0.022 | | | <0.0018 | U | | 0.011 | J | | 30 | | | 52 | | | 1.2 | | |
| | | VMP-25-21-072612 | 7/26/2012 | 13 | | | <0.02 | U | | 0.024 | | | <0.002 | U | | 0.0099 | J | | 32 | | | 50 | | | 1.9 | | |
| | | VMP-25-21-102612 | 10/26/2012 | 15 | | | <0.026 | U | | 0.024 | | | <0.0026 | U | | <0.13 | U | | 39 | | | 41 | | | 1.4 | | |
| | | VMP-25-21-030613 | 3/6/2013 | 12 | | | <0.024 | U | | 0.021 | | | <0.0024 | U | | 1.7 | | | 31 | | | 48 | | | 3.9 | | |
| | 31 ft | VMP-25-31-030613 | 3/6/2013 | 12 | | | <0.024 | U | | 0.035 | | | <0.0024 | U | | <0.12 | U | | 26 | | | 57 | | | 2.2 | | |
| VMP-29 | 10 ft | VMP-29-10-073012 | 7/30/2012 | 9.1 | | | <0.02 | U | | <0.002 | U | | <0.002 | U | | <0.1 | U | | <0.0002 | U | | 81 | | | 9.5 | | |
| | | VMP-29-10-100812 | 10/8/2012 | 8.5 | | | <0.028 | U | | <0.0028 | U | | <0.0028 | U | | <0.14 | U | | 0.00011 | J | | 82 | | | 10 | | |
| | | VMP-29-10-020613 | 2/6/2013 | 1.2 | | | <0.14 | U | | <0.0028 | U | | <0.0028 | U | | 0.15 | | | 0.00009 | J | | 79 | | | 20 | | |
| | 20 ft | VMP-29-20-073012 | 7/30/2012 | 9.8 | | | <0.02 | U | | <0.002 | U | | <0.002 | U | | <0.1 | U | | 0.000078 | J | | 81 | | | 8.8 | | |
| | | VMP-29-20-073012-Dup | 7/30/2012 | 9.3 | | | <0.025 | U | | <0.0025 | U | | <0.0025 | U | | 0.06 | J | | 0.00003 | J | | 81 | | | 9.6 | | |
| | | VMP-29-20-100812 | 10/8/2012 | 9.5 | | | <0.028 | U | | <0.0028 | U | | <0.0028 | U | | 0.018 | J | | 0.00011 | J | | 81 | | | 9.1 | | |
| | | VMP-29-20-020613 | 2/6/2013 | 0.32 | | | <0.14 | U | | <0.0028 | U | | <0.0028 | U | | 0.16 | | | 0.00021 | J | | 78 | | | 21 | | |
| | 30 ft | VMP-29-30-073012 | 7/30/2012 | 11 | | | <0.021 | U | | <0.0021 | U | | <0.0021 | U | | 0.012 | J | | 0.000027 | J | | 82 | | | 6.6 | | |
| | | VMP-29-30-100812 | 10/8/2012 | 12 | | | <0.03 | U | | <0.003 | U | | <0.003 | U | | 0.026 | J | | 0.000021 | J | | 82 | | | 6.1 | | |
| | | VMP-29-30-020613 | 2/6/2013 | 1.8 | | | <0.14 | U | | <0.0029 | U | | <0.0029 | U | | 0.043 | | | 0.00014 | J | | 78 | | | 20 | | |
| VMP-30 | 10 ft | VMP-30-10-073012 | 7/30/2012 | 5.1 | | | <0.019 | U | | <0.0019 | U | | <0.0019 | U | | 0.007 | J | | 0.000019 | J | | 80 | | | 15 | | |
| | | VMP-30-10-100812 | 10/8/2012 | 2.5 | | | <0.028 | U | | <0.0028 | U | | <0.0028 | U | | 0.028 | J | | 0.000049 | J | | 79 | | | 18 | | |
| | | VMP-30-10-020613 | 2/6/2013 | 0.094 | | | <0.13 | U | | <0.0026 | U | | <0.0026 | U | | <0.13 | U | | 0.000058 | J | | 78 | | | 22 | | |
| | 20 ft | VMP-30-20-073012 | 7/30/2012 | 12 | | | <0.019 | U | | <0.0019 | U | | <0.0019 | U | | 0.029 | J | | 0.000091 | J | | 83 | | | 5 | | |
| | | VMP-30-20-100812 | 10/8/2012 | 11 | | | <0.029 | U | | <0.0029 | U | | <0.0029 | U | | 0.036 | | | 0.000089 | J | | 81 | | | 8.3 | | |
| | | VMP-30-20-020613 | 2/6/2013 | 0.52 | | | <0.13 | U | | <0.0026 | U | | <0.0026 | U | | <0.13 | U | | 0.00013 | J | | 78 | | | 21 | | |
| | 30 ft | VMP-30-30-073012 | 7/30/2012 | 14 | | | <0.02 | U | | <0.002 | U | | <0.002 | U | | 0.0098 | J | | 0.002 | | | 84 | | | 2.4 | | |
| | | VMP-30-30-100812 | 10/8/2012 | 14 | | | <0.029 | U | | <0.0029 | U | | <0.0029 | U | | <0.14 | U | | 0.0005 | | | 81 | | | 5.4 | | |
| | | VMP-30-30-020613 | 2/6/2013 | 1.8 | | | <0.13 | U | | <0.0026 | U | | <0.0026 | U | | <0.13 | U | | 0.00008 | J | | 78 | | | 20 | | |
| VMP-31 | 5 ft | VMP-31-5-042512 | 4/25/2012 | 0.92 | | | <0.027 | U | | <0.0027 | U | | <0.0027 | U | | 0.094 | J | | 0.00011 | J | | 80 | | | 19 | | |
| | | VMP-31-5-072012 | 7/20/2012 | 0.63 | | | <0.019 | U | | <0.0019 | U | | <0.0019 | U | | 1.3 | | | 0.00023 | | | 78 | | | 20 | | |
| | | VMP-31-5-102612 | 10/26/2012 | 0.47 | | | <0.028 | U | | <0.0028 | U | | <0.0028 | U | | 0.062 | J | | 0.00016 | J | | 80 | | | 20 | | |
| | | VMP-31-5-021113 | 2/11/2013 | 0.16 | | | <0.13 | U | | <0.0026 | U | | <0.0026 | U | | 0.29 | | | 0.00012 | J | | 80 | | | 20 | | |
| | 10 ft | VMP-31-10-042512 | 4/25/2012 | 1.1 | | | <0.025 | U | | <0.0025 | U | | <0.0025 | U | | 0.22 | | | 0.00012 | J | | 80 | | | 19 | | |
| | | VMP-31-10-072612 | 7/26/2012 | 0.99 | | | <0.02 | U | | <0.002 | U | | <0.002 | U | | <0.098 | U | | 0.00023 | | | 79 | | | 20 | | |
| | | VMP-31-10-102612 | 10/26/2012 | 0.57 | | | <0.03 | U | | <0.003 | U | | <0.003 | U | | 2.6 | | | 0.00014 | J | | 77 | | | 20 | | |
| | | VMP-31-10-021313 | 2/13/2013 | 0.18 | | | <0.14 | U | | <0.0028 | U | | <0.0028 | U | | 0.32 | | | 0.00015 | J | | 78 | | | 21 | | |
| | 20 ft | VMP-31-20-101912 | 10/19/2012 | 8 | | | <0.028 | U | | <0.0028 | U | | <0.0028 | U | | 0.21 | | | 0.014 | | | 82 | | | 9.9 | | |
| | | VMP-31-20-021113 | 2/11/2013 | 3.6 | | | <0.14 | U | | <0.0028 | U | | <0.0028 | U | | <0.14 | U | | 0.0044 | | | 78 | | | 18 | | |
| | 30 ft | VMP-31-30-042512 | 4/25/2012 | 11 | | | <0.02 | U | | 0.00049 | J | | 0.000081 | J | | 0.016 | J | | 1.2 | | | 86 | | | 1.8 | | |
| | | VMP-31-30-042512-Dup | 4/25/2012 | 12 | | | <0.02 | U | | 0.00022 | J | | <0.002 | U | | 0.0094 | J | | 0.92 | | | 85 | | | 1.7 | | |
| | | VMP-31-30-072012 | 7/20/2012 | 9.3 | | | <0.019 | U | | <0.0019 | U | | <0.0019 | U | | 0.023 | J | | 0.079 | | | 83 | | | 7.8 | | |
| | | VMP-31-30-101912 | 10/19/2012 | 2.5 | | | <0.028 | U | | <0.0028 | U | | <0.0028 | U | | 0.021 | J | | 0.0031 | | | 79 | | | 18 | | |
| | | VMP-31-30-021113 | 2/11/2013 | 11 | | | <0.14 | U | | <0.0028 | U | | <0.0028 | U | | <0.14 | U | | 0.0088 | | | 83 | | | 5.6 | | |
| VMP-32 | 5 ft | VMP-32-5-042512 | 4/25/2012 | 0.29 | | | <0.026 | U | | <0.0026 | U | | <0.0026 | U | | 0.066 | J | | 0.0002 | J | | 79 | | | 21 | | |
| | | VMP-32-5-072012 | 7/20/2012 | 1.1 | | | <0.017 | U | | <0.0017 | U | | <0.0017 | U | | 0.095 | | | 0.00016 | J | | 79 | | | 20 | | |
| | | VMP-32-5-101812 | 10/18/2012 | 0.88 | | | <0.032 | U | | <0.0032 | U | | <0.0032 | U | | 0.024 | J | | 0.000068 | J | | 81 | | | 18 | | |
| | | VMP-32-5-020513 | 2/5/2013 | 0.25 | | | <0.13 | U | | <0.0025 | U | | <0.0025 | U | | <0.13 | U | | 0.00013 | J | | 79 | | | 21 | | |
| | 10 ft | VMP-32-10-041612 | 4/16/2012 | 2.3 | | | <0.023 | U | | <0.0023 | U | | <0.0023 | U | | 0.15 | | | 0.00013 | J | | 76 | | | 22 | | |
| | | VMP-32-10-072012 | 7/20/2012 | 3.7 | | | <0.02 | U | | <0.002 | U | | <0.002 | U | | 0.056 | J | | 0.000063 | J | | 79 | | | 17 | | |
| | | VMP-32-10-101812 | 10/18/2012 | 3.4 | | | <0.03 | U | | <0.003 | U | | <0.003 | U | | 0.018 | J | | 0.000036 | J | | 80 | | | 17 | | |
| | | VMP-32-10-020513 | 2/5/2013 | 2.2 | | | <0.13 | U | | <0.0025 | U | | <0.0025 | U | | <0.13 | U | | 0.000027 | J | | 79 | | | 19 | | |
| | 20 ft | VMP-32-20-041612 | 4/16/2012 | 3.7 | | | <0.02 | U | | <0.002 | U | | <0.002 | U | | 0.057 | J | | 0.00013 | J | | 80 | | | 16 | | |
| | | VMP-32-20-072012 | 7/20/2012 | 4.9 | | | <0.019 | U | | <0.0019 | U | | <0.0019 | U | | 0.022 | J | | 0.000079 | J | | 81 | | | 14 | | |
| | | VMP-32-20-101812 | 10/18/2012 | 4.8 | | | <0.028 | U | | <0.0028 | U | | <0.0028 | U | | 0.013 | J | | 0.000027 | J | | 79 | | | 16 | | |
| | | VMP-32-20-020513 | 2/5/2013 | 3.4 | | | <0.14 | U | | <0.0028 | U | | <0.0028 | U | | <0.14 | U | | 0.000026 | J | | 79 | | | 18 | | |
| | 30 ft | VMP-32-30-041612 | 4/16/2012 | 11 | | | <0.019 | U | | 0.00022 | J | | <0.0019 | U | | 0.1 | | | 0.83 | | | 86 | | | 1.9 | | |
| | | VMP-32-30-072012 | 7/20/2012 | 11 | | | <0.019 | U | | 0.0001 | J | | <0.0019 | U | | 0.059 | J | | 0.44 | | | 87 | | | 1.6 | | |
| | | VMP-32-30-101812 | 10/18/2012 | 10 | | | <0.028 | U | | <0.0028 | U | | <0.0028 | U | | 0.013 | J | | 0.015 | | | 83 | | | 7 | | |
| | | VMP-32-30-020513 | 2/5/2013 | 14 | | | <0.14 | U | | <0.0028 | U | | <0.0028 | U | | <0.14 | U | | 0.00075 | | | 82 | | | 4.3 | | |

SEE LAST PAGE OF TABLE FOR NOTES

**TABLE 7**
**CUMULATIVE SUMMARY OF SOIL VAPOR ANALYTICAL RESULTS - NATURAL GASES**

| Location | Depth | Sample ID | Sample Date | Carbon Dioxide | | | Carbon Monoxide | | | Ethane | | | Ethene | | | Helium | | | Methane | | | Nitrogen | | | Oxygen | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | Result % | Lab Quals | URS Quals | Result % | Lab Quals | URS Quals | Result % | Lab Quals | URS Quals | Result % | Lab Quals | URS Quals | Result % | Lab Quals | URS Quals | Result % | Lab Quals | URS Quals | Result % | Lab Quals | URS Quals | Result % | Lab Quals | URS Quals |
| VMP-41 | 10 ft | VMP-41-10-072712 | 7/27/2012 | 5.2 | | | <0.02 | U | | <0.002 | U | | <0.002 | U | | 0.019 | J | | 0.00014 | J | | 80 | | | 15 | | |
| | | VMP-41-10-100912 | 10/9/2012 | 4.8 | | | <0.03 | U | | <0.003 | U | | <0.003 | U | | 0.011 | J | | 0.000022 | J | | 81 | | | 14 | | |
| | | VMP-41-10-012913 | 1/29/2013 | 0.41 | | | <0.15 | U | | <0.003 | U | | <0.003 | U | | <0.15 | U | | 0.000038 | J | | 78 | | | 21 | | |
| | 20 ft | VMP-41-20-072712 | 7/27/2012 | 7.2 | | | <0.019 | U | | <0.0019 | U | | <0.0019 | U | | <0.094 | U | | 0.000023 | J | | 80 | | | 13 | | |
| | | VMP-41-20-072712-Dup | 7/27/2012 | 7.1 | | | <0.019 | U | | <0.0019 | U | | <0.0019 | U | | <0.096 | U | | 0.000018 | J | | 80 | | | 13 | | |
| | | VMP-41-20-100912 | 10/9/2012 | 6.5 | | | <0.029 | U | | <0.0029 | U | | <0.0029 | U | | 0.53 | | | 0.000027 | J | | 81 | | | 12 | | |
| | | VMP-41-20-100912-Dup | 10/9/2012 | 6.7 | | | <0.03 | U | | <0.003 | U | | <0.003 | U | | 0.019 | J | | 0.000024 | J | | 81 | | | 12 | | |
| | | VMP-41-20-012913 | 1/29/2013 | 0.88 | | | <0.15 | U | | <0.003 | U | | <0.003 | U | | <0.15 | U | | 0.000032 | J | | 79 | | | 20 | | |
| | 30 ft | VMP-41-30-072712 | 7/27/2012 | 8.2 | | | <0.019 | U | | <0.0019 | U | | <0.0019 | U | | 0.0071 | J | | 0.000037 | J | | 80 | | | 12 | | |
| | | VMP-41-30-100912 | 10/9/2012 | 8.6 | | | <0.031 | U | | <0.0031 | U | | <0.0031 | U | | <0.16 | U | | 0.000058 | J | | 81 | | | 10 | | |
| | | VMP-41-30-012913 | 1/29/2013 | 1.9 | | | <0.28 | U | | <0.0057 | U | | <0.0057 | U | | <0.28 | U | | <0.00057 | U | | 76 | | | 22 | | |
| VMP-42 | 10 ft | VMP-42-10-041812 | 4/18/2012 | 3.1 | | | <0.022 | U | | <0.0022 | U | | <0.0022 | U | | 0.052 | J | | <0.00022 | U | | 79 | | | 18 | | |
| | | VMP-42-10-041812-Dup | 4/18/2012 | 3.1 | | | <0.023 | U | | <0.0023 | U | | <0.0023 | U | | 0.031 | J | | <0.00023 | U | | 79 | | | 18 | | |
| | | VMP-42-20-041812 | 4/18/2012 | 9.6 | | | <0.024 | U | | <0.0024 | U | | <0.0024 | U | | 0.038 | J | | 0.064 | | | 83 | | | 7.4 | | |
| | | VMP-42-10-071912 | 7/19/2012 | 2.5 | | | <0.026 | U | | <0.0026 | U | | <0.0026 | U | | 0.1 | J | | 0.000028 | J | | 79 | | | 19 | | |
| | | VMP-42-10-101212 | 10/12/2012 | 0.92 | | | <0.031 | U | | <0.0031 | U | | <0.0031 | U | | <0.15 | U | | 0.00002 | J | | 79 | | | 20 | | |
| | | VMP-42-10-013113 | 1/31/2013 | 0.45 | | | <0.14 | U | | <0.0028 | U | | <0.0028 | U | | <0.14 | U | | 0.000027 | J | | 78 | | | 21 | | |
| | 20 ft | VMP-42-20-071912 | 7/19/2012 | 6.7 | | | <0.024 | U | | <0.0024 | U | | <0.0024 | U | | 0.055 | J | | 0.000033 | J | | 220 | | | 14 | | |
| | | VMP-42-20-101212 | 10/12/2012 | 3.4 | | | <0.037 | U | | <0.0037 | U | | <0.0037 | U | | 0.093 | J | | 0.000036 | J | | 79 | | | 18 | | |
| | | VMP-42-20-101212-Dup | 10/12/2012 | 3.3 | | | <0.028 | U | | <0.0028 | U | | <0.0028 | U | | 0.051 | J | | 0.000047 | J | | 78 | | | 19 | | |
| | | VMP-42-20-013113 | 1/31/2013 | 2.5 | | | <0.13 | U | | <0.0026 | U | | <0.0026 | U | | <0.13 | U | | 0.00002 | J | | 78 | | | 19 | | |
| | 30 ft | VMP-42-30-041912 | 4/19/2012 | 12 | | | <0.019 | U | | 0.00022 | J | | <0.0019 | U | | 0.028 | J | | 0.45 | | | 86 | | | 1.8 | | |
| | | VMP-42-30-071912 | 7/19/2012 | 9.2 | | | <0.023 | U | | <0.0023 | U | | <0.0023 | U | | 0.048 | J | | 0.027 | | | 89 | | | 2.1 | | |
| | | VMP-42-30-101212 | 10/12/2012 | 8.2 | | | <0.029 | U | | <0.0029 | U | | <0.0029 | U | | 0.035 | J | | 0.0017 | | | 79 | | | 13 | | |
| | | VMP-42-30-101212-Dup | 10/12/2012 | 8.2 | | | <0.029 | U | | <0.0029 | U | | <0.0029 | U | | 0.04 | J | | 0.0017 | | | 79 | | | 13 | | |
| | | VMP-42-30-013113 | 1/31/2013 | 6.6 | | | <0.14 | U | | <0.0028 | U | | <0.0028 | U | | <0.14 | U | | 0.00029 | | | 79 | | | 14 | | |
| VMP-43 | 10 ft | VMP-43-10-041612 | 4/16/2012 | 0.88 | | | <0.025 | U | | <0.0025 | U | | <0.0025 | U | | 0.43 | | | 0.00011 | J | | 81 | | | 18 | | |
| | | VMP-43-10-071912 | 7/19/2012 | 0.87 | | | <0.023 | U | | <0.0023 | U | | <0.0023 | U | | 0.16 | | | 0.00019 | J | | 80 | | | 19 | | |
| | | VMP-43-10-101612 | 10/16/2012 | 0.55 | | | <0.032 | U | | <0.0032 | U | | <0.0032 | U | | 0.071 | J | | 0.00011 | J | | 80 | | | 19 | | |
| | 20 ft | VMP-43-20-041612 | 4/16/2012 | 4.8 | | | <0.019 | U | | <0.0019 | U | | <0.0019 | U | | 0.16 | | | 0.012 | | | 80 | | | 15 | | |
| | | VMP-43-20-071912 | 7/19/2012 | 2.9 | | | <0.024 | U | | <0.0024 | U | | <0.0024 | U | | 0.073 | J | | 0.0016 | | | 80 | | | 17 | | |
| | | VMP-43-20-101812 | 10/18/2012 | 1.9 | | | <0.026 | U | | <0.0026 | U | | <0.0026 | U | | 0.054 | J | | 0.0008 | | | 80 | | | 18 | | |
| | | VMP-43-20-012413 | 1/24/2013 | 3.2 | | | <0.13 | U | | <0.0026 | U | | <0.0026 | U | | <0.13 | U | | 0.00065 | | | 79 | | | 18 | | |
| | 30 ft | VMP-43-30-042312 | 4/23/2012 | 2.8 | | | <0.023 | U | | <0.0023 | U | | <0.0023 | U | | 0.016 | J | | 0.0008 | | | 75 | | | 22 | | |
| | | VMP-43-30-071912 | 7/19/2012 | 2.5 | | | <0.031 | U | | <0.0031 | U | | <0.0031 | U | | 0.044 | J | | 0.00071 | | | 80 | | | 18 | | |
| | | VMP-43-30-101812 | 10/18/2012 | 1.3 | | | <0.037 | U | | <0.0037 | U | | <0.0037 | U | | 0.016 | J | | 0.000047 | J | | 79 | | | 20 | | |
| | | VMP-43-30-012413 | 1/24/2013 | 1.7 | | | <0.13 | U | | <0.0027 | U | | <0.0027 | U | | <0.13 | U | | 0.00004 | J | | 79 | | | 19 | | |
| VMP-44 | 10 ft | VMP-44-10-041912 | 4/19/2012 | 9.1 | | | <0.018 | U | | <0.0018 | U | | <0.0018 | U | | 0.047 | J | | 0.025 | | | 84 | | | 6.6 | | |
| | | VMP-44-10-072012 | 7/20/2012 | 14 | | | <0.018 | U | | <0.0018 | U | | <0.0018 | U | | 0.037 | J | | 0.022 | | | 81 | | | 4.3 | | |
| | | VMP-44-10-081012 | 8/10/2012 | 12 | | | <0.018 | U | | <0.0018 | U | | <0.0018 | U | | 0.038 | J | | 0.045 | | | 91 | | | 6.4 | | |
| | | VMP-44-10-101212 | 10/12/2012 | 5.9 | | | <0.028 | U | | <0.0028 | U | | <0.0028 | U | | 1.4 | | | 0.0063 | | | 81 | | | 12 | | |
| | | VMP-44-10-012513 | 1/25/2013 | 7.2 | | | <0.12 | U | | 0.000081 | J | | <0.0023 | U | | <0.12 | U | | 0.0024 | | | 85 | | | 7.7 | | |
| | 20 ft | VMP-44-20-041912 | 4/19/2012 | 12 | | | <0.02 | U | | <0.002 | U | | <0.002 | U | | 0.17 | | | 0.069 | | | 85 | | | 2.5 | | |
| | | VMP-44-20-072512 | 7/25/2012 | 15 | | | <0.021 | U | | <0.0021 | U | | <0.0021 | U | | 0.056 | J | | 0.019 | | | 81 | | | 3.9 | | |
| | | VMP-44-20-101212 | 10/12/2012 | 11 | | | <0.03 | U | | <0.003 | U | | <0.003 | U | | 0.21 | | | 0.0086 | | | 81 | | | 7.8 | | |
| | | VMP-44-20-012513 | 1/25/2013 | 10 | | | <0.12 | U | | 0.000081 | J | | <0.0025 | U | | <0.12 | U | | 0.021 | | | 83 | | | 7.3 | | |
| | 30 ft | VMP-44-30-041912 | 4/19/2012 | 12 | | | <0.019 | U | | <0.0019 | U | | <0.0019 | U | | 0.046 | J | | 0.076 | | | 86 | | | 2.2 | | |
| | | VMP-44-30-072512 | 7/25/2012 | 9.2 | | | <0.02 | U | | <0.002 | U | | <0.002 | U | | 0.028 | J | | 0.0033 | | | 81 | | | 10 | | |
| | | VMP-44-30-072512-Dup | 7/25/2012 | 9.4 | | | <0.02 | U | | <0.002 | U | | <0.002 | U | | 0.016 | J | | 0.0034 | | | 81 | | | 9.9 | | |
| | | VMP-44-30-101512 | 10/15/2012 | 5.3 | | | <0.03 | U | | <0.003 | U | | <0.003 | U | | 0.019 | J | | 0.003 | | | 80 | | | 15 | | |
| | | VMP-44-30-101512-Dup | 10/15/2012 | 5.1 | | | <0.028 | U | | <0.0028 | U | | <0.0028 | U | | 0.018 | J | | 0.0029 | | | 80 | | | 15 | | |
| | | VMP-44-30-012513 | 1/25/2013 | 0.073 | | J | <0.19 | U | UJ | 0.0002 | J | J | <0.0038 | U | UJ | 9.9 | | J | 0.00034 | J | J | 71 | | J | 19 | | J |

**TABLE 7**
**CUMULATIVE SUMMARY OF SOIL VAPOR ANALYTICAL RESULTS - NATURAL GASES**

| Location | Depth | Sample ID | Sample Date | Carbon Dioxide | | | Carbon Monoxide | | | Ethane | | | Ethene | | | Helium | | | Methane | | | Nitrogen | | | Oxygen | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | Result % | Lab Quals | URS Quals | Result % | Lab Quals | URS Quals | Result % | Lab Quals | URS Quals | Result % | Lab Quals | URS Quals | Result % | Lab Quals | URS Quals | Result % | Lab Quals | URS Quals | Result % | Lab Quals | URS Quals | Result % | Lab Quals | URS Quals |
| VMP-45 | 10 ft | VMP-45-10-041912 | 4/19/2012 | 0.86 | | | <0.031 | U | | <0.0031 | U | | <0.0031 | U | | 0.11 | J | | <0.00031 | U | | 79 | | | 20 | | |
| | | VMP-45-10-071912 | 7/19/2012 | 0.83 | | | <0.024 | U | | <0.0024 | U | | <0.0024 | U | | 0.053 | J | | 0.000027 | J | | 79 | | | 20 | | |
| | | VMP-45-10-101512 | 10/15/2012 | 0.4 | | | <0.029 | U | | <0.0029 | U | | <0.0029 | U | | 0.06 | J | | 0.000018 | J | | 80 | | | 20 | | |
| | | VMP-45-10-013013 | 1/30/2013 | 0.13 | | | <0.13 | U | | <0.0025 | U | | <0.0025 | U | | <0.13 | U | | 0.000046 | J | | 80 | | | 20 | | |
| | 20 ft | VMP-45-20-041912 | 4/19/2012 | 6.3 | | | <0.018 | U | | <0.0018 | U | | <0.0018 | U | | 0.14 | | | 0.0003 | | | 80 | | | 14 | | |
| | | VMP-45-20-071912 | 7/19/2012 | 4.2 | | | <0.018 | U | | <0.0018 | U | | <0.0018 | U | | 0.6 | | | 0.00022 | | | 78 | | | 17 | | |
| | | VMP-45-20-101512 | 10/15/2012 | 2.4 | | | <0.028 | U | | <0.0028 | U | | <0.0028 | U | | 0.028 | J | | 0.00076 | | | 80 | | | 18 | | |
| | | VMP-45-20-013013 | 1/30/2013 | 2 | | | <0.13 | U | | <0.0026 | U | | <0.0026 | U | | <0.13 | U | | 0.0012 | | | 79 | | | 19 | | |
| | 30 ft | VMP-45-30-041912 | 4/19/2012 | 10 | | | <0.019 | U | | <0.0019 | U | | <0.0019 | U | | 0.033 | J | | 0.024 | | | 85 | | | 4.9 | | |
| | | VMP-45-30-071912 | 7/19/2012 | 7.8 | | | <0.019 | U | | <0.0019 | U | | <0.0019 | U | | 0.045 | J | | 0.00082 | | | 83 | | | 9.3 | | |
| | | VMP-45-30-101512 | 10/15/2012 | 4.1 | | | <0.028 | U | | <0.0028 | U | | <0.0028 | U | | 0.03 | J | | 0.0005 | | | 80 | | | 16 | | |
| | | VMP-45-30-101512-Dup | 10/15/2012 | 4.2 | | | <0.027 | U | | <0.0027 | U | | <0.0027 | U | | 0.026 | J | | 0.0005 | | | 80 | | | 16 | | |
| | | VMP-45-30-013013 | 1/30/2013 | 2.5 | | | <0.12 | U | | <0.0024 | U | | <0.0024 | U | | <0.12 | U | | 0.00046 | | | 80 | | | 18 | | |
| VMP-47 | 5 ft | VMP-47-5-012113 | 1/21/2013 | 6.8 | | | <0.14 | U | | <0.0029 | U | | <0.0029 | U | | <0.14 | U | | 0.00002 | J | | 81 | | | 12 | | |
| | | [1]VMP-47-5-012313-R | 1/23/2013 | 11 | | | <0.12 | U | | 0.0012 | J | | <0.0024 | U | | <0.12 | U | | 3.9 | | | 83 | | | 1.7 | | |
| | 10 ft | VMP-47-10-012113 | 1/21/2013 | 12 | | | <0.14 | U | | <0.0028 | U | | <0.0028 | U | | <0.14 | U | | <0.00028 | U | | 83 | | | 5.3 | | |
| | | [1]VMP-47-10-012313-R | 1/23/2013 | 11 | | | <0.12 | U | | <0.0024 | U | | <0.0024 | U | | <0.12 | U | | 0.14 | | | 86 | | | 2.5 | | |
| | 20 ft | VMP-47-20-012113 | 1/21/2013 | 13 | | | <0.13 | U | | 0.0001 | J | | <0.0025 | U | | 0.66 | | | 0.4 | | | 84 | | | 2 | | |
| | | [1]VMP-47-20-012313-R | 1/23/2013 | 12 | | | <0.12 | U | | 0.00061 | J | | <0.0024 | U | | <0.12 | U | | 2.1 | | | 84 | | | 1.5 | | |
| | 30 ft | VMP-47-30-012113 | 1/21/2013 | 12 | | | <0.13 | U | | 0.00041 | J | | <0.0026 | U | | <0.13 | U | | 2.2 | | | 84 | | | 1.5 | | |
| | | [1]VMP-47-30-012313-R | 1/23/2013 | 11 | | | <0.12 | U | | 0.0014 | J | | <0.0024 | U | | <0.12 | U | | 4.9 | | | 82 | | | 1.4 | | |
| VMP-48 | 5 ft | VMP-48-5-020113 | 2/1/2013 | 0.33 | | | <0.13 | U | | <0.0026 | U | | <0.0026 | U | | 0.022 | J | | 0.00023 | J | | 79 | | | 21 | | |
| | 10 ft | VMP-48-10-020113 | 2/1/2013 | 2.7 | | | <0.13 | U | | <0.0027 | U | | <0.0027 | U | | <0.13 | U | | 0.000057 | J | | 78 | | | 19 | | |
| | 20 ft | VMP-48-20-020113 | 2/1/2013 | 4.2 | | | <0.13 | U | | <0.0026 | U | | <0.0026 | U | | <0.13 | U | | 0.000044 | J | | 78 | | | 18 | | |
| | 30 ft | VMP-48-30-020113 | 2/1/2013 | 11 | | | <0.13 | U | | <0.0026 | U | | <0.0026 | U | | 0.029 | J | | 0.0017 | | | 87 | | | 1.6 | | |
| | | VMP-48-30-020113-DUP | 2/1/2013 | 11 | | | <0.13 | U | | <0.0026 | U | | <0.0026 | U | | 0.025 | J | | 0.0017 | | | 87 | | | 1.7 | | |
| VMP-49 | 5 ft | VMP-49-5-020113 | 2/1/2013 | 0.71 | | | <0.13 | U | | <0.0027 | U | | <0.0027 | U | | <0.13 | U | | <0.00027 | U | | 79 | | | 20 | | |
| | 10 ft | VMP-49-10-020113 | 2/1/2013 | 0.58 | | | <0.13 | U | | <0.0026 | U | | <0.0026 | U | | <0.13 | U | | 0.000051 | J | | 79 | | | 20 | | |
| | 20 ft | VMP-49-20-020113 | 2/1/2013 | 0.39 | | | <0.13 | U | | <0.0026 | U | | <0.0026 | U | | 0.75 | | | 0.00015 | J | | 79 | | | 20 | | |
| | 30 ft | VMP-49-30-020113 | 2/1/2013 | 11 | | | <0.12 | U | | <0.0025 | U | | <0.0025 | U | | 0.02 | J | | 0.069 | | | 84 | | | 4.4 | | |
| VMP-50 | 5 ft | VMP-50-5-020113 | 2/1/2013 | 0.85 | | | <0.13 | U | | <0.0025 | U | | <0.0025 | U | | <0.13 | U | | 0.00023 | J | | 79 | | | 20 | | |
| | 10 ft | VMP-50-10-020113 | 2/1/2013 | 4 | | | <0.14 | U | | <0.0028 | U | | <0.0028 | U | | <0.14 | U | | 0.000044 | J | | 80 | | | 16 | | |
| | 20 ft | VMP-50-20-020113 | 2/1/2013 | 0.39 | | | <0.13 | U | | <0.0027 | U | | <0.0027 | U | | 0.03 | J | | 0.00037 | | | 80 | | | 20 | | |
| | 30 ft | VMP-50-30-020113 | 2/1/2013 | 8 | | | <0.13 | U | | 0.000056 | J | | 0.000051 | J | | <0.13 | U | | 0.56 | | | 77 | | | 14 | | |
| VMP-51 | 5 ft | VMP-51-5-020113 | 2/1/2013 | 0.33 | | | <0.14 | U | | <0.0027 | U | | <0.0027 | U | | <0.14 | U | | 0.000057 | J | | 80 | | | 20 | | |
| | 10 ft | VMP-51-10-020113 | 2/1/2013 | 0.72 | | | <0.14 | U | | <0.0028 | U | | <0.0028 | U | | <0.14 | U | | <0.00028 | U | | 79 | | | 20 | | |
| | 20 ft | VMP-51-20-021513-R | 2/15/2013 | 2.9 | | | <0.13 | U | | <0.0026 | U | | <0.0026 | U | | <0.13 | U | | <0.00026 | U | | 78 | | | 19 | | |
| | 30 ft | VMP-51-30-020413 | 2/4/2013 | 4 | | | <0.14 | U | | <0.0029 | U | | <0.0029 | U | | 0.036 | J | | 0.000024 | J | | 78 | | | 18 | | |
| | | VMP-51-30-020413-DUP | 2/4/2013 | 3.9 | | | <0.14 | U | | <0.0028 | U | | <0.0028 | U | | 0.034 | J | | 0.000028 | J | | 78 | | | 18 | | |
| VMP-52 | 5 ft | VMP-52-5-020413 | 2/4/2013 | 0.98 | | | <0.13 | U | | <0.0025 | U | | <0.0025 | U | | <0.13 | U | | 0.00031 | | | 81 | | | 18 | | |
| | 10 ft | VMP-52-10-020413 | 2/4/2013 | 2.6 | | | <0.12 | U | | <0.0024 | U | | <0.0024 | U | | <0.12 | U | | 0.00068 | | | 82 | | | 15 | | |
| | 20 ft | VMP-52-20-020413 | 2/4/2013 | 6 | | | <0.13 | U | | <0.0027 | U | | <0.0027 | U | | 0.031 | J | | 0.00073 | | | 81 | | | 13 | | |
| | | VMP-52-20-020413-DUP | 2/4/2013 | 6.1 | | | <0.13 | U | | <0.0026 | U | | <0.0026 | U | | 0.036 | J | | 0.00074 | | | 81 | | | 13 | | |
| | 30 ft | VMP-52-30-020413 | 2/4/2013 | 7 | | | <0.14 | U | | <0.0028 | U | | <0.0028 | U | | <0.14 | U | | 0.0014 | | | 81 | | | 12 | | |
| VMP-53 | 5 ft | VMP-53-5-020513 | 2/5/2013 | 0.49 | | | <0.13 | U | | <0.0026 | U | | <0.0026 | U | | <0.13 | U | | 0.000073 | J | | 78 | | | 21 | | |
| | 10 ft | VMP-53-10-020513 | 2/5/2013 | 0.59 | | | <0.13 | U | | <0.0026 | U | | <0.0026 | U | | 0.027 | J | | 0.000018 | J | | 78 | | | 21 | | |
| | | VMP-53-10-020513-DUP | 2/5/2013 | 0.58 | | | <0.12 | U | | <0.0025 | U | | <0.0025 | U | | 0.019 | J | | 0.00002 | J | | 78 | | | 21 | | |
| | 20 ft | VMP-53-20-020513 | 2/5/2013 | 1.8 | | | <0.13 | U | | <0.0026 | U | | <0.0026 | U | | <0.13 | U | | 0.000029 | J | | 78 | | | 20 | | |
| | 30 ft | VMP-53-30-020513 | 2/5/2013 | 3.5 | | | <0.13 | U | | <0.0027 | U | | <0.0027 | U | | 0.026 | J | | 0.000043 | J | | 78 | | | 19 | | |
| VMP-54 | 5 ft | VMP-54-5-020613 | 2/6/2013 | 1.7 | | | <0.14 | U | | <0.0028 | U | | <0.0028 | U | | <0.14 | U | | 0.00011 | J | | 79 | | | 19 | | |
| | 10 ft | VMP-54-10-020613 | 2/6/2013 | 3.2 | | | <0.14 | U | | <0.0028 | U | | <0.0028 | U | | <0.14 | U | | <0.00028 | U | | 79 | | | 18 | | |
| | 20 ft | VMP-54-20-020613 | 2/6/2013 | 4.7 | | | <0.14 | U | | <0.0028 | U | | <0.0028 | U | | 0.039 | J | | <0.00028 | U | | 80 | | | 15 | | |
| | | VMP-54-20-020613-DUP | 2/6/2013 | 4.6 | | | <0.14 | U | | <0.0028 | U | | <0.0028 | U | | 0.035 | J | | 0.000022 | J | | 80 | | | 15 | | |
| | 30 ft | VMP-54-30-020613 | 2/6/2013 | 5.3 | | | <0.15 | U | | <0.003 | U | | <0.003 | U | | 0.032 | J | | 0.000042 | J | | 81 | | | 14 | | |
| | | VMP-54-30-020613-DUP | 2/6/2013 | 5.4 | | | <0.15 | U | | <0.003 | U | | <0.003 | U | | 0.028 | J | | 0.000051 | J | | 81 | | | 14 | | |
| VMP-55 | 20 ft | VMP-55-20-021513 | 2/15/2013 | 16 | | | <0.14 | U | | 0.0046 | | | <0.0028 | U | | 0.17 | | | 11 | | | 69 | | | 3.2 | | |

Notes
**Lab Qualifiers**
J = Estimated value; results between the MDL and RL
U = Compound analyzed for but not detected above the RL
**URS Qualifiers**
J = Estimated detection
UJ = Estimated non-detect
U = Non-detect due to blank contamination

[1] Grab sample taken
[2] After post sampling was conducted integrity issue were identified and sample results are not representative
[3] Sample compromised at laboratory and data not representative

SEE LAST PAGE OF TABLE FOR NOTES

TABLE 8
TEDLAR SAMPLE DATA FOR VMP-1 AND VMP-47

| Sample ID | Date | Initial Reading Time (24-Hour) | Vacuum/Pressure | Gauging Information | | | Fixed Gases | | | | Soil Vapor Concentrations | | | | Comment(s) |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | Initial Reading (Inches of H2O) | Depth to Product (FT BTOC) | Depth to Water (FT BTOC) | Depth to Top of Screen (FT BTOC) | CH4 (%) | LEL (%) | $CO_2$ (%) | $O_2$ (%) | PID (ppmv) | THC (ppmv) | CH4 (ppmv) | PHC (ppmv) | |
| VMP-1-5 | 1/16/2013 | 1345 | 0.02 | NM | NM | NM | OVR | OVR | 3.6 | 12.6 | 92.48 | 120,000 | 64,200 | 55,800 | |
| VMP-1-5 | 1/19/2013 | 956 | 0.01 | NM | NM | NM | OVR | OVR | 3.1 | 11.4 | 100 | 232,000 | 103,000 | 129,000 | |
| VMP-1-5 | 1/21/2013 | 1005 | -0.05 | NM | NM | NM | 0.0 | 0.0 | 0.3 | 20.6 | 10.50 | 73.10 | 16.80 | 56.30 | |
| VMP-1-5 | 1/22/2013 | 900 | -0.08 | NM | NM | NM | 0.0 | 0.0 | 0.3 | 20.7 | 2.20 | 30.7 | 19.1 | 11.6 | |
| VMP-1-5 | 1/22/2013 | 1601 | 0.05 | NM | NM | NM | OVR | OVR | 1.5 | 15.3 | 71.16 | 88,900 | 54,200 | 34,700 | |
| VMP-1-5 | 1/23/2013 | 812 | 0.03 | NM | NM | NM | OVR | OVR | 3.1 | 14.4 | 87.97 | 91,800 | 53,000 | 38,800 | |
| VMP-1-5 | 1/23/2013 | 1140 | 0.07 | NM | NM | NM | 21.4 | OVR | 3.6 | 15.7 | 77.25 | 35,300 | 21,800 | 13,500 | |
| VMP-1-5 | 1/24/2013 | 910 | -0.11 | NM | NM | NM | 0.0 | 1.0 | 0.4 | 20.6 | 18.8 | 166 | 26.3 | 140 | |
| VMP-1-5 | 1/24/2013 | 1600 | 0.00 | NM | NM | NM | OVR | OVR | 1.7 | 15.8 | 77.5 | 60,000 | 36,500 | 23,500 | |
| VMP-1-5 | 1/25/2013 | 843 | -0.07 | NM | NM | NM | OVR | OVR | 2.8 | 15.3 | 91.2 | 81,000 | 45,500 | 35,500 | |
| VMP-1-5 | 1/25/2013 | 1546 | -0.05 | NM | NM | NM | OVR | OVR | 2.7 | 14.9 | 88.3 | 100,000 | 51,600 | 48,400 | |
| VMP-1-5 | 1/28/2013 | 815 | -0.13 | NM | NM | NM | OVR | OVR | 1.7 | 14.2 | 110 | 76,200 | 29,200 | 47,000 | |
| VMP-1-5 | 1/28/2013 | 1610 | -0.09 | NM | NM | NM | 28.5 | OVR | 2.2 | 14.6 | 123 | 14,600 | 4,200 | 10,400 | |
| VMP-1-5 | 1/29/2013 | 855 | -0.01 | NM | NM | NM | OVR | OVR | 2.2 | 14.0 | 77.7 | 77,700 | 34,600 | 43,100 | |
| VMP-1-5 | 1/29/2013 | 1417 | 0.18 | NM | NM | NM | OVR | OVR | 3.9 | 13.9 | 82.1 | 97,200 | 50,100 | 47,100 | |
| VMP-1-5 | 1/30/2013 | 900 | -0.06 | NM | NM | NM | OVR | OVR | 3.3 | 12.0 | 119 | 86,900 | 36,300 | 50,600 | |
| VMP-1-5 | 1/30/2013 | 1550 | -0.33 | NM | NM | NM | 3.6 | 72.0 | 1.8 | 18.6 | 89.6 | 3,200 | 825 | 2,375 | |
| VMP-1-5 | 1/31/2013 | 950 | -0.19 | NM | NM | NM | 0.0 | 0.0 | 0.5 | 20.5 | 9.4 | 113 | 12.0 | 101 | |
| VMP-1-5 | 1/31/2013 | 1545 | -0.14 | NM | NM | NM | 0.0 | 0.0 | 0.5 | 20.6 | 6.2 | 83.3 | 8.8 | 74.5 | |
| VMP-1-5 | 2/1/2013 | 915 | -0.07 | NM | NM | NM | 0.0 | 0.0 | 0.4 | 20.5 | 4.5 | 54.9 | 14.0 | 40.9 | |
| VMP-1-5 | 2/1/2013 | 1550 | 0.00 | NM | NM | NM | OVR | OVR | 1.5 | 15.0 | 73.7 | 115,000 | 64,500 | 50,500 | |
| VMP-1-5 | 2/4/2013 | 850 | -0.47 | NM | NM | NM | 1.3 | 26.0 | 3.7 | 14.8 | 42.3 | 2,100 | 1,300 | 800 | |
| VMP-1-5 | 2/4/2013 | 1545 | -0.29 | NM | NM | NM | 1.2 | 24.0 | 3.9 | 15.0 | 43.9 | 1,910 | 1,070 | 840 | |
| VMP-1-5 | 2/5/2013 | 835 | -0.22 | NM | NM | NM | 0.0 | 0.0 | 1.4 | 20.3 | 7.9 | 76.9 | 1.5 | 75.4 | |
| VMP-1-5 | 2/5/2013 | 1525 | -0.25 | NM | NM | NM | 41.5 | OVR | 1.5 | 17.8 | 48.4 | 33,300 | 17,400 | 15,900 | |
| VMP-1-5 | 2/6/2013 | 848 | -0.31 | NM | NM | NM | 0.0 | 0.0 | 0.4 | 20.5 | 2.7 | 40.1 | 19.2 | 20.9 | |
| VMP-1-5 | 2/6/2013 | 1600 | -0.19 | NM | NM | NM | OVR | OVR | 1.3 | 14.3 | 58.1 | 52,300 | 28,400 | 23,900 | |
| VMP-1-5 | 2/7/2013 | 925 | -0.25 | NM | NM | NM | 8.1 | OVR | 2.0 | 15.4 | 87.8 | 8,500 | 3,070 | 5,430 | |
| VMP-1-5 | 2/7/2013 | 1418 | 0.03 | NM | NM | NM | OVR | OVR | 3.4 | 12.9 | 52.4 | 175,000 | 94,800 | 80,200 | |
| VMP-1-5 | 2/8/2013 | 913 | -0.26 | NM | NM | NM | 0.0 | 1.0 | 1.0 | 20.5 | 9.0 | 208 | 72 | 136 | |
| VMP-1-5 | 2/8/2013 | 1515 | -0.16 | NM | NM | NM | 0.0 | 0.0 | 0.6 | 20.5 | 5.3 | 63.7 | 0.0 | 63.7 | |
| VMP-1-5 | 2/11/2013 | 905 | -0.22 | NM | NM | NM | 1.5 | 30.0 | 1.6 | 18.7 | 42.2 | 1,820 | 85.9 | 1,734 | |
| VMP-1-5 | 2/11/2013 | 1508 | -0.14 | NM | NM | NM | 0.8 | 17.0 | 1.6 | 19.1 | 29.3 | 995 | 25.0 | 970 | |
| VMP-1-5 | 2/12/2013 | 906 | -0.15 | NM | NM | NM | 0.2 | 4.0 | 1.4 | 19.6 | 15.1 | 252 | 31.4 | 221 | |
| VMP-1-5 | 2/12/2013 | 1410 | 0.08 | NM | NM | NM | OVR | OVR | 1.7 | 14.3 | 55.0 | 125,000 | 46,000 | 79,000 | |
| VMP-1-5 | 2/13/2013 | 946 | 0.00 | NM | NM | NM | OVR | OVR | 2.6 | 13.6 | 69.3 | 95,400 | 44,500 | 50,900 | |
| VMP-1-5 | 2/13/2013 | 1500 | 0.00 | NM | NM | NM | 14.2 | OVR | 3.4 | 14.3 | 105 | 20,100 | 8,200 | 11,900 | |
| VMP-1-5 | 2/26/2013 | 900 | 0.06 | NM | NM | NM | 65.0 | OVR | 4.1 | 13.0 | 75.7 | 49,200 | 33,000 | 16,200 | |
| VMP-1-5 | 3/21/2013 | 1256 | -0.01 | NM | NM | NM | 0.0 | 0.00 | 0.2 | 18.6 | 0.9 | 1.9 | 0.0 | 1.9 | VMP reinstalled 3/6/13. |

TABLE 8
TEDLAR SAMPLE DATA FOR VMP-1 AND VMP-47

| Sample ID | Date | Initial Reading Time (24-Hour) | Vacuum/Pressure | Gauging Information | | | Fixed Gases | | | | Soil Vapor Concentrations | | | | Comment(s) |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | Initial Reading (Inches of H2O) | Depth to Product (FT BTOC) | Depth to Water (FT BTOC) | Depth to Top of Screen (FT BTOC) | CH4 (%) | LEL (%) | $CO_2$ (%) | $O_2$ (%) | PID (ppmv) | THC (ppmv) | CH4 (ppmv) | PHC (ppmv) | |
| VMP-1-8.5 | 1/16/2013 | 1350 | 0.06 | NM | NM | NM | 1.5 | 31.0 | 1.7 | 19.1 | 59.1 | 4,200 | 1,800 | 2,400 | |
| VMP-1-8.5 | 1/19/2013 | 957 | -0.41 | NM | NM | NM | OVR | OVR | 4.0 | 12.6 | 115 | 123,000 | 57,500 | 65,500 | |
| VMP-1-8.5 | 1/21/2013 | 1006 | -1.15 | NM | NM | NM | 0.0 | 0.0 | 0.2 | 20.8 | 1.3 | 9.4 | 0.0 | 9.4 | |
| VMP-1-8.5 | 1/22/2013 | 901 | -0.09 | NM | NM | NM | 0.0 | 0.0 | 0.8 | 20.4 | 1.4 | 14.4 | 3.9 | 10.5 | |
| VMP-1-8.5 | 1/22/2013 | 1602 | 0.05 | NM | NM | NM | 1.0 | 19.0 | 2.6 | 16.9 | 22.3 | 3,800 | 2,800 | 1,000 | |
| VMP-1-8.5 | 1/23/2013 | 817 | 0.04 | NM | NM | NM | 2.6 | 52.0 | 3.4 | 16.1 | 40.3 | 6,750 | 6,600 | 150 | |
| VMP-1-8.5 | 1/23/2013 | 1145 | 0.08 | NM | NM | NM | 0.4 | 8.0 | 3.8 | 16.2 | 18.3 | 1,225 | 970 | 255 | |
| VMP-1-8.5 | 1/24/2013 | 915 | -0.11 | NM | NM | NM | 0.0 | 1.0 | 0.5 | 20.5 | 17.5 | 140 | 17.7 | 122 | |
| VMP-1-8.5 | 1/24/2013 | 1601 | 0.00 | NM | NM | NM | 1.1 | 22.0 | 2.5 | 16.8 | 33.5 | 2,900 | 2,200 | 700 | |
| VMP-1-8.5 | 1/25/2013 | 844 | -0.08 | NM | NM | NM | OVR | OVR | 3.5 | 13.5 | 89.2 | 113,000 | 59,400 | 53,600 | |
| VMP-1-8.5 | 1/25/2013 | 1547 | -0.12 | NM | NM | NM | OVR | OVR | 3.8 | 12.9 | 97.6 | 136,000 | 62,200 | 73,800 | |
| VMP-1-8.5 | 1/28/2013 | 816 | -0.07 | NM | NM | NM | OVR | OVR | 3.0 | 13.0 | 114 | 110,000 | 48,000 | 62,000 | |
| VMP-1-8.5 | 1/28/2013 | 1611 | 0.00 | NM | NM | NM | 0.5 | 11.0 | 3.7 | 14.9 | 36 | 1,000 | 290 | 710 | |
| VMP-1-8.5 | 1/29/2013 | 856 | 0.00 | NM | NM | NM | 16.7 | OVR | 3.8 | 14.5 | 82.7 | 11,200 | 4,800 | 6,400 | |
| VMP-1-8.5 | 1/29/2013 | 1418 | 0.19 | NM | NM | NM | 1.3 | 26.0 | 4.1 | 14.0 | 37.4 | 3,700 | 2,200 | 1,500 | |
| VMP-1-8.5 | 1/30/2013 | 905 | -0.10 | NM | NM | NM | OVR | OVR | 4.2 | 11.5 | 120.0 | 88,500 | 34,900 | 53,600 | |
| VMP-1-8.5 | 1/30/2013 | 1551 | -0.35 | NM | NM | NM | 7.1 | OVR | 2.3 | 17.2 | 120.0 | 6,000 | 1,650 | 4,350 | |
| VMP-1-8.5 | 1/31/2013 | 951 | -0.17 | NM | NM | NM | 0.0 | 0.0 | 0.8 | 20.2 | 6.9 | 67.3 | 6.4 | 60.9 | |
| VMP-1-8.5 | 1/31/2013 | 1546 | -0.13 | NM | NM | NM | 0.0 | 0.0 | 0.7 | 20.4 | 5.9 | 77.6 | 16.5 | 61.1 | |
| VMP-1-8.5 | 2/1/2013 | 916 | -0.09 | NM | NM | NM | 0.0 | 0.0 | 0.5 | 20.4 | 3.4 | 34.3 | 5.7 | 28.6 | |
| VMP-1-8.5 | 2/1/2013 | 1551 | 0.00 | NM | NM | NM | 1.5 | 30.0 | 2.5 | 16.8 | 30.6 | 6,000 | 4,000 | 2,000 | |
| VMP-1-8.5 | 2/4/2013 | 851 | -0.24 | NM | NM | NM | 0.0 | 0.0 | 3.8 | 15.1 | 4.6 | 97.3 | 77.6 | 19.7 | |
| VMP-1-8.5 | 2/4/2013 | 1546 | -0.25 | NM | NM | NM | 0.0 | 1.0 | 3.9 | 15.6 | 7.7 | 300 | 190 | 110 | |
| VMP-1-8.5 | 2/5/2013 | 836 | -0.22 | NM | NM | NM | 1.0 | 20.0 | 2.4 | 19.3 | 35.0 | 2,520 | 1,740 | 780 | |
| VMP-1-8.5 | 2/5/2013 | 1526 | -0.34 | NM | NM | NM | OVR | OVR | 3.1 | 13.6 | 77.3 | 110,000 | 52,300 | 57,700 | |
| VMP-1-8.5 | 2/6/2013 | 849 | -0.60 | NM | NM | NM | 0.0 | 0.0 | 0.6 | 20.2 | 2.9 | 30.8 | 5.3 | 25.5 | |
| VMP-1-8.5 | 2/6/2013 | 1601 | -0.14 | NM | NM | NM | 10.5 | OVR | 2.6 | 16.2 | 28.5 | 11,100 | 5,560 | 5,540 | |
| VMP-1-8.5 | 2/7/2013 | 926 | -0.19 | NM | NM | NM | 0.0 | 1.0 | 3.3 | 16.3 | 9.4 | 229 | 132 | 97 | |
| VMP-1-8.5 | 2/7/2013 | 1419 | -0.25 | NM | NM | NM | 5.0 | OVR | 3.5 | 15.6 | 28.9 | 13,500 | 11,500 | 2,000 | |
| VMP-1-8.5 | 2/8/2013 | 914 | -0.50 | NM | NM | NM | 0.0 | 0.0 | 1.4 | 19.9 | 4.8 | 60.1 | 4.6 | 55.6 | |
| VMP-1-8.5 | 2/8/2013 | 1516 | -0.02 | NM | NM | NM | 0.0 | 0.0 | 1.5 | 19.3 | 3.0 | 32.5 | 0.0 | 32.5 | |
| VMP-1-8.5 | 2/11/2013 | 906 | -0.20 | NM | NM | NM | 1.9 | 38.0 | 2.2 | 17.9 | 48.0 | 1,915 | 36.5 | 1,879 | |
| VMP-1-8.5 | 2/11/2013 | 1509 | -0.12 | NM | NM | NM | 0.6 | 12.0 | 2.2 | 18.0 | 24.6 | 750 | 7.5 | 743 | |
| VMP-1-8.5 | 2/12/2013 | 907 | -0.14 | NM | NM | NM | 0.2 | 5.0 | 1.2 | 18.4 | 17.6 | 365 | 136 | 229 | |
| VMP-1-8.5 | 2/12/2013 | 1411 | 0.09 | NM | NM | NM | 18.8 | OVR | 3.3 | 15.2 | 43.0 | 16,000 | 13,000 | 3,000 | |
| VMP-1-8.5 | 2/13/2013 | 947 | 0.00 | NM | NM | NM | OVR | OVR | 3.6 | 14.2 | 92.8 | 33,600 | 11,600 | 22,000 | |
| VMP-1-8.5 | 2/13/2013 | 1501 | 0.00 | NM | NM | NM | 0.5 | 10 | 3.8 | 15.3 | 32.6 | 900 | 660 | 240 | |
| VMP-1-8.5 | 2/26/2013 | 900 | 0.06 | NM | NM | NM | 0.4 | 9.0 | 4.0 | 14.9 | 27.3 | 1,100 | 579 | 521 | |
| VMP-1-8.5 | 3/21/2013 | 1300 | -0.02 | NM | NM | NM | 0.0 | 0.0 | 2.1 | 18.6 | 0.5 | 1.2 | 0.0 | 1.2 | VMP reinstalled 3/6/13. |

SEE LAST PAGE OF TABLE FOR NOTES

TABLE 8
TEDLAR SAMPLE DATA FOR VMP-1 AND VMP-47

| Sample ID | Date | Initial Reading Time (24-Hour) | Vacuum/Pressure | Gauging Information | | | Fixed Gases | | | | Soil Vapor Concentrations | | | | Comment(s) |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | Initial Reading (Inches of H2O) | Depth to Product (FT BTOC) | Depth to Water (FT BTOC) | Depth to Top of Screen (FT BTOC) | CH4 (%) | LEL (%) | $CO_2$ (%) | $O_2$ (%) | PID (ppmv) | THC (ppmv) | CH4 (ppmv) | PHC (ppmv) | |
| VMP-1-23.5 | 1/16/2013 | 1355 | 0.06 | NM | NM | NM | OVR | OVR | 4.8 | 9.0 | 86.3 | 220,000 | 105,000 | 115,000 | |
| VMP-1-23.5 | 1/19/2013 | 958 | 0.10 | NM | NM | NM | OVR | OVR | 5.1 | 8.7 | 94.3 | 240,000 | 110,000 | 130,000 | |
| VMP-1-23.5 | 1/21/2013 | 1007 | -1.40 | NM | NM | NM | 0.2 | 4.0 | 4.9 | 13.7 | 21.6 | 315 | 284 | 31.0 | |
| VMP-1-23.5 | 1/22/2013 | 902 | -0.09 | NM | NM | NM | 0.0 | 0.0 | 4.9 | 14.2 | 4.30 | 17.8 | 2.6 | 15.2 | |
| VMP-1-23.5 | 1/22/2013 | 1603 | 0.06 | NM | NM | NM | OVR | OVR | 10.5 | 3.5 | 90.78 | 77,100 | 35,500 | 41,600 | |
| VMP-1-23.5 | 1/23/2013 | 822 | 0.04 | NM | NM | NM | OVR | OVR | 10.3 | 3.2 | 105 | 115,000 | 48,200 | 66,800 | |
| VMP-1-23.5 | 1/23/2013 | 1205 | 0.14 | NM | NM | NM | OVR | OVR | 8.4 | 5.7 | 79.8 | 180,000 | 83,100 | 96,900 | |
| VMP-1-23.5 | 1/24/2013 | 920 | -0.15 | NM | NM | NM | 0.0 | 0.0 | 4.5 | 15.1 | 9.3 | 72.8 | 20.0 | 52.8 | |
| VMP-1-23.5 | 1/24/2013 | 1602 | 0.00 | NM | NM | NM | OVR | OVR | 6.9 | 6.9 | 76.4 | 134,000 | 71,500 | 62,500 | |
| VMP-1-23.5 | 1/25/2013 | 845 | -0.09 | NM | NM | NM | OVR | OVR | 7.1 | 7.8 | 90.7 | 137,000 | 68,100 | 68,900 | |
| VMP-1-23.5 | 1/25/2013 | 1548 | -0.08 | NM | NM | NM | OVR | OVR | 7.3 | 7.3 | 95.2 | 156,000 | 78,300 | 77,700 | |
| VMP-1-23.5 | 1/28/2013 | 817 | -0.09 | NM | NM | NM | OVR | OVR | 7.9 | 6.5 | 93.2 | 80,000 | 47,500 | 32,500 | |
| VMP-1-23.5 | 1/28/2013 | 1612 | 0.00 | NM | NM | NM | OVR | OVR | 6.2 | 7.1 | 90.0 | 205,000 | 88,500 | 116,500 | |
| VMP-1-23.5 | 1/29/2013 | 857 | -0.02 | NM | NM | NM | OVR | OVR | 6.8 | 5.3 | 95.2 | 245,000 | 98,000 | 147,000 | |
| VMP-1-23.5 | 1/29/2013 | 1419 | 0.25 | NM | NM | NM | OVR | OVR | 7.0 | 3.6 | 72.8 | 630,000 | 225,000 | 405,000 | |
| VMP-1-23.5 | 1/30/2013 | 910 | -0.13 | NM | NM | NM | OVR | OVR | 8.3 | 4.9 | 91.9 | 118,000 | 57,800 | 60,200 | |
| VMP-1-23.5 | 1/30/2013 | 1552 | -0.46 | NM | NM | NM | 5.00 | OVR | 6.1 | 11.1 | 72.9 | 9,800 | 6,150 | 3,650 | |
| VMP-1-23.5 | 1/31/2013 | 952 | -0.26 | NM | NM | NM | 0.0 | 0.0 | 5.1 | 15.5 | 8.4 | 49.5 | 11.4 | 38.1 | |
| VMP-1-23.5 | 1/31/2013 | 1547 | -0.21 | NM | NM | NM | 0.0 | 0.0 | 5.8 | 12.5 | 5.1 | 40.5 | 19.2 | 21.3 | |
| VMP-1-23.5 | 2/1/2013 | 917 | -0.16 | NM | NM | NM | 0.0 | 0.0 | 6.1 | 12.7 | 4.4 | 18.5 | 0.0 | 18.5 | |
| VMP-1-23.5 | 2/1/2013 | 1552 | 0.01 | NM | NM | NM | OVR | OVR | 10.3 | 2.1 | 77.3 | 98,700 | 51,500 | 47,200 | |
| VMP-1-23.5 | 2/4/2013 | 852 | 0.07 | NM | NM | NM | OVR | OVR | 7.5 | 5.1 | 83.9 | 205,000 | 117,000 | 88,000 | |
| VMP-1-23.5 | 2/4/2013 | 1547 | -0.15 | NM | NM | NM | OVR | OVR | 8.3 | 5.5 | 86.1 | 148,000 | 77,400 | 70,600 | |
| VMP-1-23.5 | 2/5/2013 | 837 | -0.09 | NM | NM | NM | 13.0 | OVR | 10.6 | 5.3 | 57.4 | 18,500 | 12,600 | 5,900 | |
| VMP-1-23.5 | 2/5/2013 | 1527 | -0.10 | NM | NM | NM | OVR | OVR | 9.7 | 3.6 | 85.7 | 97,800 | 44,300 | 53,500 | |
| VMP-1-23.5 | 2/6/2013 | 850 | -0.17 | NM | NM | NM | 0.0 | 0.0 | 6.3 | 11.8 | 7.9 | 85.9 | 29.5 | 56.4 | |
| VMP-1-23.5 | 2/6/2013 | 1602 | 0.07 | NM | NM | NM | OVR | OVR | 9.3 | 4.3 | 65.2 | 63,700 | 38,100 | 25,600 | |
| VMP-1-23.5 | 2/7/2013 | 927 | 0.05 | NM | NM | NM | OVR | OVR | 8.1 | 4.5 | 60.6 | 258,000 | 122,000 | 136,000 | |
| VMP-1-23.5 | 2/7/2013 | 1420 | 0.05 | NM | NM | NM | OVR | OVR | 7.5 | 4.0 | 50.1 | 355,000 | 131,000 | 224,000 | |
| VMP-1-23.5 | 2/8/2013 | 915 | -0.29 | NM | NM | NM | 0.0 | 0.0 | 3.8 | 16.3 | 16.0 | 151 | 22.0 | 129 | |
| VMP-1-23.5 | 2/8/2013 | 1517 | -0.06 | NM | NM | NM | 0.0 | 0.0 | 4.7 | 14.6 | 16.0 | 120 | 0.0 | 120 | |
| VMP-1-23.5 | 2/11/2013 | 907 | -0.06 | NM | NM | NM | 0.9 | 19.0 | 5.4 | 12.6 | 31.9 | 1,500 | 730 | 770 | |
| VMP-1-23.5 | 2/11/2013 | 1510 | -0.50 | NM | NM | NM | 0.4 | 9.0 | 6.5 | 11.1 | 23.4 | 860 | 290 | 570 | |
| VMP-1-23.5 | 2/12/2013 | 908 | -0.16 | NM | NM | NM | 0.2 | 4.0 | 8.0 | 9.1 | 14.2 | 555 | 375 | 180 | |
| VMP-1-23.5 | 2/12/2013 | 1412 | 0.00 | NM | NM | NM | OVR | OVR | 8.6 | 4.3 | 55.0 | 111,000 | 66,000 | 45,000 | |
| VMP-1-23.5 | 2/13/2013 | 948 | 0.00 | NM | NM | NM | OVR | OVR | 8.3 | 5.0 | 69.7 | 127,000 | 61,500 | 65,500 | |
| VMP-1-23.5 | 2/13/2013 | 1502 | 0.00 | NM | NM | NM | OVR | OVR | 8.3 | 3.6 | 65.5 | 320,000 | 105,000 | 215,000 | |
| VMP-1-23.5 | 2/26/2013 | 905 | 0.07 | NM | NM | NM | OVR | OVR | 5.3 | 7.3 | 54.0 | 285,000 | 136,000 | 149,000 | |
| VMP-1-23.5 | 3/21/2013 | 1304 | -0.36 | NM | NM | NM | OVR | OVR | 10.1 | 1.8 | 81.4 | 85,700 | 36,700 | 49,000 | VMP reinstalled 3/6/13. |

SEE LAST PAGE OF TABLE FOR NOTES

TABLE 8
TEDLAR SAMPLE DATA FOR VMP-1 AND VMP-47

| Sample ID | Date | Initial Reading Time (24-Hour) | Vacuum/Pressure | Gauging Information | | | Fixed Gases | | | | Soil Vapor Concentrations | | | | Comment(s) |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | Initial Reading (Inches of H2O) | Depth to Product (FT BTOC) | Depth to Water (FT BTOC) | Depth to Top of Screen (FT BTOC) | CH4 (%) | LEL (%) | $CO_2$ (%) | $O_2$ (%) | PID (ppmv) | THC (ppmv) | CH4 (ppmv) | PHC (ppmv) | |
| VMP-1-38.5 | 1/16/2013 | 1355 | 0.05 | NM | NM | NM | OVR | OVR | 3.1 | 11.5 | 87.8 | 215,000 | 104,000 | 111,000 | |
| VMP-1-38.5 | 1/19/2013 | 959 | 0.01 | NM | NM | NM | OVR | OVR | 2.1 | 15.1 | 105 | 105,000 | 53,700 | 51,300 | |
| VMP-1-38.5 | 1/21/2013 | 1008 | -0.04 | NM | NM | NM | 0.2 | 3.0 | 0.3 | 20.7 | 22.44 | 155 | 23.50 | 132 | |
| VMP-1-38.5 | 1/22/2013 | 903 | -0.05 | NM | NM | NM | 0.0 | 0.0 | 0.3 | 20.6 | 1.50 | 12.8 | 3.2 | 9.5 | |
| VMP-1-38.5 | 1/22/2013 | 1604 | 0.04 | NM | NM | NM | OVR | OVR | 1.0 | 15.4 | 69.25 | 100,000 | 52,700 | 47,300 | |
| VMP-1-38.5 | 1/23/2013 | 827 | 0.03 | NM | NM | NM | OVR | OVR | 2.5 | 14.2 | 82.22 | 107,000 | 56,100 | 50,900 | |
| VMP-1-38.5 | 1/23/2013 | 1210 | 0.08 | NM | NM | NM | OVR | OVR | 35.0 | 14.2 | 71.45 | 110,000 | 62,600 | 47,400 | |
| VMP-1-38.5 | 1/24/2013 | 925 | -0.10 | NM | NM | NM | 0.0 | 0.0 | 0.3 | 20.6 | 14.3 | 138 | 27.7 | 110 | |
| VMP-1-38.5 | 1/24/2013 | 1603 | 0.00 | NM | NM | NM | OVR | OVR | 1.7 | 13.9 | 72.6 | 173,000 | 79,000 | 94,000 | |
| VMP-1-38.5 | 1/25/2013 | 846 | -0.06 | NM | NM | NM | 80.5 | OVR | 2.0 | 17.4 | 106 | 35,300 | 24,900 | 10,400 | |
| VMP-1-38.5 | 1/25/2013 | 1549 | -0.08 | NM | NM | NM | OVR | OVR | 2.1 | 16.9 | 102 | 72,800 | 34,900 | 37,900 | |
| VMP-1-38.5 | 1/28/2013 | 818 | -0.06 | NM | NM | NM | OVR | OVR | 1.2 | 16.2 | 106 | 40,500 | 21,300 | 19,200 | |
| VMP-1-38.5 | 1/28/2013 | 1613 | 0.00 | NM | NM | NM | 45.2 | OVR | 1.8 | 15.2 | 120 | 20,200 | 7,600 | 12,600 | |
| VMP-1-38.5 | 1/29/2013 | 858 | 0.00 | NM | NM | NM | OVR | OVR | 1.7 | 15.1 | 97.8 | 49,000 | 21,400 | 27,600 | |
| VMP-1-38.5 | 1/29/2013 | 1420 | 0.19 | NM | NM | NM | OVR | OVR | 3.7 | 11.0 | 77.0 | 270,000 | 120,000 | 150,000 | |
| VMP-1-38.5 | 1/30/2013 | 915 | -0.13 | NM | NM | NM | OVR | OVR | 2.8 | 12.5 | 123.0 | 60,300 | 26,100 | 34,200 | |
| VMP-1-38.5 | 1/30/2013 | 1553 | -0.33 | NM | NM | NM | 1.4 | 28.0 | 0.9 | 19.6 | 66.5 | 1,800 | 490 | 1,310 | |
| VMP-1-38.5 | 1/31/2013 | 953 | -0.15 | NM | NM | NM | 0.0 | 0.0 | 0.4 | 20.6 | 7.8 | 89.9 | 10.7 | 79.2 | |
| VMP-1-38.5 | 1/31/2013 | 1548 | -0.14 | NM | NM | NM | 0.0 | 0.0 | 0.3 | 20.7 | 6.4 | 79.9 | 10.0 | 69.9 | |
| VMP-1-38.5 | 2/1/2013 | 918 | -0.15 | NM | NM | NM | 0.0 | 0.0 | 0.3 | 20.6 | 4.9 | 69.5 | 26.2 | 43.3 | |
| VMP-1-38.5 | 2/1/2013 | 1553 | -0.13 | NM | NM | NM | OVR | OVR | 1.5 | 14.1 | 70.2 | 169,000 | 92,400 | 76,600 | |
| VMP-1-38.5 | 2/4/2013 | 853 | -0.18 | NM | NM | NM | 0.7 | 14.0 | 3.5 | 14.6 | 31.9 | 1,900 | 920 | 980 | |
| VMP-1-38.5 | 2/4/2013 | 1548 | -0.11 | NM | NM | NM | 0.7 | 14.0 | 3.1 | 15.9 | 36.9 | 1,650 | 570 | 1,080 | |
| VMP-1-38.5 | 2/5/2013 | 838 | -0.04 | NM | NM | NM | 0.0 | 0.0 | 0.9 | 20.5 | 12.8 | 145 | 35.6 | 109 | |
| VMP-1-38.5 | 2/5/2013 | 1528 | -0.05 | NM | NM | NM | 25.0 | OVR | 1.0 | 19.2 | 52.5 | 20,100 | 11,000 | 9,100 | |
| VMP-1-38.5 | 2/6/2013 | 851 | -0.09 | NM | NM | NM | 0.0 | 0.0 | 0.2 | 20.4 | 5.0 | 83.4 | 32.3 | 51.1 | |
| VMP-1-38.5 | 2/6/2013 | 1603 | 0.05 | NM | NM | NM | OVR | OVR | 1.0 | 14.8 | 54.6 | 49,000 | 29,300 | 19,700 | |
| VMP-1-38.5 | 2/7/2013 | 928 | 0.03 | NM | NM | NM | 73.1 | OVR | 1.4 | 15.5 | 71.8 | 28,400 | 17,800 | 10,600 | |
| VMP-1-38.5 | 2/7/2013 | 1421 | 0.03 | NM | NM | NM | OVR | OVR | 2.7 | 12.8 | 50.2 | 118,000 | 53,100 | 64,900 | |
| VMP-1-38.5 | 2/8/2013 | 916 | -0.24 | NM | NM | NM | 0.1 | 2.0 | 0.9 | 20.6 | 11.0 | 225 | 22.4 | 203 | |
| VMP-1-38.5 | 2/8/2013 | 1518 | -0.02 | NM | NM | NM | 0.0 | 1.0 | 0.9 | 20.2 | 13.5 | 146 | 0.0 | 146 | |
| VMP-1-38.5 | 2/11/2013 | 908 | -0.20 | NM | NM | NM | 1.9 | 38.0 | 1.3 | 18.9 | 47.9 | 2,160 | 175 | 1,985 | |
| VMP-1-38.5 | 2/11/2013 | 1511 | -0.11 | NM | NM | NM | 1.1 | 22.0 | 1.3 | 19.2 | 38.7 | 1,100 | 90.0 | 1,010 | |
| VMP-1-38.5 | 2/12/2013 | 909 | -0.12 | NM | NM | NM | 0.2 | 5.0 | 1.2 | 19.7 | 32.9 | 410 | 27.6 | 382 | |
| VMP-1-38.5 | 2/12/2013 | 1414 | 0.09 | NM | NM | NM | OVR | OVR | 2.1 | 13.7 | 45.0 | 167,000 | 89,000 | 78,000 | |
| VMP-1-38.5 | 2/13/2013 | 949 | 0.00 | NM | NM | NM | OVR | OVR | 2.1 | 14.2 | 66.2 | 70,900 | 34,000 | 36,900 | |
| VMP-1-38.5 | 2/13/2013 | 1503 | -0.23 | NM | NM | NM | OVR | OVR | 2.5 | 14.0 | 88.9 | 42,900 | 23,400 | 19,500 | |
| VMP-1-38.5 | 2/26/2013 | 907 | -0.10 | NM | NM | NM | OVR | OVR | 3.3 | 11.7 | 65.0 | 140,000 | 77,900 | 62,100 | |
| VMP-1-38.5 | 3/21/2013 | 1308 | -1.11 | NM | NM | NM | OVR | OVR | 4.0 | 0.9 | 25.7 | 1,000,000 | 1,000,000 | 0.0 | VMP reinstalled 3/6/13. |

SEE LAST PAGE OF TABLE FOR NOTES

TABLE 8
TEDLAR SAMPLE DATA FOR VMP-1 AND VMP-47

| Sample ID | Date | Initial Reading Time (24-Hour) | Vacuum/Pressure | Gauging Information | | | Fixed Gases | | | | Soil Vapor Concentrations | | | | Comment(s) |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | Initial Reading (Inches of H2O) | Depth to Product (FT BTOC) | Depth to Water (FT BTOC) | Depth to Top of Screen (FT BTOC) | CH4 (%) | LEL (%) | $CO_2$ (%) | $O_2$ (%) | PID (ppmv) | THC (ppmv) | CH4 (ppmv) | PHC (ppmv) | |
| VMP-47-5 | 1/19/2013 | 936 | 0.02 | NM | NM | NM | OVR | OVR | 11.5 | 0.7 | 110 | 74,600 | 47,800 | 26,800.0 | |
| VMP-47-5 | 1/21/2013 | 1010 | -0.03 | NM | NM | NM | 0.0 | 0.0 | 6.7 | 12.1 | 1.6 | 3.7 | 0.0 | 3.7 | |
| VMP-47-5 | 1/22/2013 | 915 | -0.16 | NM | NM | NM | 0.0 | 0.0 | 7.2 | 12.8 | 0.60 | 2.1 | 0.0 | 2.1 | |
| VMP-47-5 | 1/22/2013 | 1616 | -0.74 | NM | NM | NM | 0.0 | 0.0 | 10.6 | 2.5 | 14 | 100 | 25.0 | 75.0 | |
| VMP-47-5 | 1/23/2013 | 757 | -1.38 | NM | NM | NM | 43.5 | OVR | 12.0 | 0.7 | 94 | 37,600 | 24,400 | 13,200.0 | |
| VMP-47-5 | 1/23/2013 | 1235 | -0.07 | NM | NM | NM | 69.9 | OVR | 11.4 | 2.1 | 79 | 62,400 | 41,600 | 20,800.0 | |
| VMP-47-5 | 1/24/2013 | 850 | -1.20 | NM | NM | NM | 0.0 | 0.0 | 5.8 | 14.3 | 5.6 | 22.5 | 0.0 | 22.5 | |
| VMP-47-5 | 1/24/2013 | 1615 | -0.19 | NM | NM | NM | 0.1 | 2.0 | 9.7 | 4.0 | 39.9 | 400 | 45.2 | 355 | |
| VMP-47-5 | 1/25/2013 | 858 | -0.71 | NM | NM | NM | 87.4 | OVR | 11.7 | 0.7 | 102 | 55,500 | 35,000 | 20,500 | |
| VMP-47-5 | 1/25/2013 | 1530 | -0.62 | NM | NM | NM | OVR | OVR | 12.1 | 0.8 | 100 | 70,000 | 44,400 | 25,600 | |
| VMP-47-5 | 1/28/2013 | 836 | 0.02 | NM | NM | NM | OVR | OVR | 10.6 | 3.4 | 130 | 57,900 | 33,800 | 24,100 | |
| VMP-47-5 | 1/28/2013 | 1625 | 0.06 | NM | NM | NM | OVR | OVR | 11.5 | 0.7 | 92 | 82,500 | 62,700 | 19,800 | |
| VMP-47-5 | 1/29/2013 | 925 | 0.08 | NM | NM | NM | OVR | OVR | 10.6 | 1.9 | 105 | 100,000 | 50,500 | 49,500 | |
| VMP-47-5 | 1/29/2013 | 1444 | 0.22 | NM | NM | NM | OVR | OVR | 10.7 | 1.0 | 102 | 108,000 | 63,700 | 44,300 | |
| VMP-47-5 | 1/30/2013 | 940 | -0.14 | NM | NM | NM | OVR | OVR | 11.0 | 0.8 | 113 | 100,000 | 57,800 | 42,200 | |
| VMP-47-5 | 1/30/2013 | 1530 | -0.23 | NM | NM | NM | 46.2 | OVR | 6.0 | 12.0 | 123 | 35,200 | 18,600 | 16,600 | |
| VMP-47-5 | 1/31/2013 | 910 | -0.13 | NM | NM | NM | 0.0 | 0.0 | 6.4 | 12.2 | 25.9 | 71.2 | 0.0 | 71.2 | |
| VMP-47-5 | 1/31/2013 | 1559 | -0.36 | NM | NM | NM | 0.0 | 0.0 | 5.4 | 14.6 | 8.8 | 38.1 | 0.0 | 38.1 | |
| VMP-47-5 | 2/1/2013 | 940 | -0.49 | NM | NM | NM | 0.0 | 0.0 | 4.0 | 16.8 | 1.1 | 4.9 | 0.0 | 4.9 | |
| VMP-47-5 | 2/1/2013 | 1610 | -0.02 | NM | NM | NM | 0.0 | 0.0 | 7.9 | 7.1 | 8.3 | 71.5 | 0.0 | 71.5 | |
| VMP-47-5 | 2/4/2013 | 925 | -0.30 | NM | NM | NM | OVR | OVR | 10.0 | 0.7 | 100 | 76,100 | 48,200 | 27,900 | |
| VMP-47-5 | 2/4/2013 | 1605 | -0.43 | NM | NM | NM | OVR | OVR | 11.0 | 0.6 | 94 | 60,000 | 43,500 | 16,500 | |
| VMP-47-5 | 2/5/2013 | 900 | -0.62 | NM | NM | NM | 0.0 | 0.0 | 7.8 | 8.6 | 24.9 | 121 | 0.0 | 121.0 | |
| VMP-47-5 | 2/5/2013 | 1546 | -0.49 | NM | NM | NM | 32.9 | OVR | 11.2 | 0.9 | 83.1 | 22,000 | 14,800 | 7,200 | |
| VMP-47-5 | 2/6/2013 | 915 | -0.56 | NM | NM | NM | 0.0 | 0.0 | 2.8 | 17.0 | 2.0 | 11.9 | 0.0 | 11.9 | |
| VMP-47-5 | 2/6/2013 | 1627 | -0.46 | NM | NM | NM | 0.1 | 3.0 | 9.6 | 4.3 | 25.3 | 320 | 89 | 231.1 | |
| VMP-47-5 | 2/7/2013 | 950 | -0.43 | NM | NM | NM | 47.0 | OVR | 11.6 | 0.8 | 66.4 | 38,200 | 27,600 | 10,600 | |
| VMP-47-5 | 2/7/2013 | 1444 | -0.70 | NM | NM | NM | 78.2 | OVR | 11.5 | 0.9 | 71.4 | 46,400 | 33,100 | 13,300 | |
| VMP-47-5 | 2/8/2013 | 940 | 0.14 | NM | NM | NM | 0.0 | 0.0 | 3.0 | 17.5 | 13.0 | 75.4 | 0.0 | 75.4 | |
| VMP-47-5 | 2/8/2013 | 1545 | -0.29 | NM | NM | NM | 0.0 | 0.0 | 3.3 | 17.0 | 5.9 | 35.4 | 0.0 | 35.4 | |
| VMP-47-5 | 2/11/2013 | 940 | -1.05 | NM | NM | NM | 0.4 | 9.0 | 10.5 | 5.5 | 70.8 | 670 | 97.0 | 573.0 | |
| VMP-47-5 | 2/11/2013 | 1540 | -0.50 | NM | NM | NM | 0.1 | 2.0 | 4.7 | 14.7 | 29.9 | 155 | 0.0 | 155.0 | |
| VMP-47-5 | 2/12/2013 | 941 | -0.67 | NM | NM | NM | 0.0 | 0.0 | 4.9 | 14.6 | 2.8 | 10.2 | 0.0 | 10.2 | |
| VMP-47-5 | 2/12/2013 | 1545 | -0.10 | NM | NM | NM | 5.0 | OVR | 12.0 | 0.5 | 64.0 | 6,450 | 5,400 | 1,050 | |
| VMP-47-5 | 2/13/2013 | 1020 | -0.10 | NM | NM | NM | 51.1 | OVR | 12.0 | 0.6 | 80.6 | 32,600 | 19,000 | 13,600 | |
| VMP-47-5 | 2/13/2013 | 1535 | -0.10 | NM | NM | NM | 87.7 | OVR | 11.8 | 0.6 | 77.9 | 49,300 | 35,200 | 14,100 | |
| VMP-47-5 | 3/21/2013 | 1234 | 0.02 | NM | NM | NM | 0.0 | 0.0 | 10.9 | 3.6 | 10.9 | 152 | 0.0 | 152 | |

SEE LAST PAGE OF TABLE FOR NOTES

TABLE 8
TEDLAR SAMPLE DATA FOR VMP-1 AND VMP-47

| Sample ID | Date | Initial Reading Time (24-Hour) | Vacuum/Pressure | Gauging Information | | | Fixed Gases | | | | Soil Vapor Concentrations | | | | Comment(s) |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | Initial Reading (Inches of H2O) | Depth to Product (FT BTOC) | Depth to Water (FT BTOC) | Depth to Top of Screen (FT BTOC) | CH4 (%) | LEL (%) | $CO_2$ (%) | $O_2$ (%) | PID (ppmv) | THC (ppmv) | CH4 (ppmv) | PHC (ppmv) | |
| VMP-47-10 | 1/19/2013 | 937 | 0.01 | NM | NM | NM | 18.7 | OVR | 12.5 | 0.7 | 125 | 16,400 | 10,000 | 6,400 | |
| VMP-47-10 | 1/21/2013 | 1015 | -0.02 | NM | NM | NM | 0.0 | 0.0 | 11.8 | 4.2 | 1.2 | 1.4 | 0.0 | 1.4 | |
| VMP-47-10 | 1/22/2013 | 916 | -0.15 | NM | NM | NM | 0.0 | 0.0 | 11.7 | 5.7 | 0.4 | 1.7 | 0.0 | 1.7 | |
| VMP-47-10 | 1/22/2013 | 1617 | -0.74 | NM | NM | NM | 0.0 | 0.0 | 11.5 | 5.7 | 0.4 | 1.3 | 0.0 | 1.3 | |
| VMP-47-10 | 1/23/2013 | 802 | -0.84 | NM | NM | NM | 0.0 | 0.0 | 11.6 | 3.9 | 3.2 | 50.5 | 0.0 | 50.5 | |
| VMP-47-10 | 1/23/2013 | 1240 | 0.07 | NM | NM | NM | 0.4 | 8.0 | 12.7 | 2.0 | 36.4 | 1,100 | 550 | 550 | |
| VMP-47-10 | 1/24/2013 | 855 | -1.10 | NM | NM | NM | 0.0 | 0.0 | 12.1 | 4.4 | 5.3 | 29.6 | 0.0 | 29.6 | |
| VMP-47-10 | 1/24/2013 | 1616 | -0.03 | NM | NM | NM | 0.0 | 0.0 | 11.1 | 6.6 | 4.6 | 53.5 | 0.0 | 53.5 | |
| VMP-47-10 | 1/25/2013 | 859 | -0.52 | NM | NM | NM | 3.5 | 71.0 | 12.4 | 1.3 | 95.5 | 5,600 | 4,200 | 1,400 | |
| VMP-47-10 | 1/25/2013 | 1531 | -0.44 | NM | NM | NM | 7.8 | OVR | 13.3 | 0.5 | 120 | 8,300 | 4,600 | 3,700 | |
| VMP-47-10 | 1/28/2013 | 837 | -0.04 | NM | NM | NM | 16.6 | OVR | 13.3 | 0.4 | 130 | 14,500 | 8,400 | 6,100 | |
| VMP-47-10 | 1/28/2013 | 1626 | 0.04 | NM | NM | NM | 46.0 | OVR | 12.5 | 0.8 | 127 | 24,400 | 11,400 | 13,000 | |
| VMP-47-10 | 1/29/2013 | 926 | 0.06 | NM | NM | NM | 84.1 | OVR | 12.0 | 0.9 | 140 | 38,200 | 19,800 | 18,400 | |
| VMP-47-10 | 1/29/2013 | 1445 | 0.16 | NM | NM | NM | OVR | OVR | 11.1 | 0.9 | 113 | 95,900 | 52,700 | 43,200 | |
| VMP-47-10 | 1/30/2013 | 945 | -0.12 | NM | NM | NM | OVR | OVR | 12.3 | 0.7 | 133 | 50,000 | 26,200 | 23,800 | |
| VMP-47-10 | 1/30/2013 | 1531 | -0.48 | NM | NM | NM | 66.0 | OVR | 12.1 | 1.1 | 125 | 38,500 | 21,000 | 17,500 | |
| VMP-47-10 | 1/31/2013 | 911 | -0.33 | NM | NM | NM | 0.0 | 1.0 | 13.0 | 1.4 | 27.9 | 134 | 0.0 | 134 | |
| VMP-47-10 | 1/31/2013 | 1600 | -0.82 | NM | NM | NM | 0.0 | 0.0 | 13.2 | 1.6 | 3.6 | 34.9 | 0.0 | 34.9 | |
| VMP-47-10 | 2/1/2013 | 941 | -0.70 | NM | NM | NM | 0.0 | 0.0 | 12.0 | 4.8 | 0.8 | 1.5 | 0.0 | 1.5 | |
| VMP-47-10 | 2/1/2013 | 1611 | 0.01 | NM | NM | NM | 0.0 | 0.0 | 11.0 | 6.4 | 0.6 | 7.2 | 0.0 | 7.2 | |
| VMP-47-10 | 2/4/2013 | 926 | 0.03 | NM | NM | NM | 30.7 | OVR | 12.1 | 0.6 | 118 | 23,600 | 14,700 | 8,900 | |
| VMP-47-10 | 2/4/2013 | 1606 | -0.05 | NM | NM | NM | 28.0 | OVR | 12.1 | 1.1 | 115 | 20,300 | 11,600 | 8,700 | |
| VMP-47-10 | 2/5/2013 | 901 | -0.47 | NM | NM | NM | 0.0 | 0.0 | 13.2 | 1.5 | 10.3 | 57.6 | 0.0 | 57.6 | |
| VMP-47-10 | 2/5/2013 | 1547 | -0.31 | NM | NM | NM | 0.0 | 0.0 | 12.5 | 1.4 | 6.8 | 75.9 | 0.0 | 75.9 | |
| VMP-47-10 | 2/6/2013 | 916 | -0.80 | NM | NM | NM | 0.0 | 0.0 | 12.5 | 3.7 | 1.2 | 14.3 | 0.0 | 14.3 | |
| VMP-47-10 | 2/6/2013 | 1628 | -0.33 | NM | NM | NM | 0.0 | 0.0 | 12.0 | 5.0 | 0.7 | 11.0 | 0.0 | 11.0 | |
| VMP-47-10 | 2/7/2013 | 951 | -0.44 | NM | NM | NM | 0.1 | 2.0 | 11.7 | 2.4 | 17.5 | 375 | 124 | 252 | |
| VMP-47-10 | 2/7/2013 | 1445 | -0.95 | NM | NM | NM | 5.8 | OVR | 12.3 | 0.9 | 81.9 | 6,600 | 3,500 | 3,100 | |
| VMP-47-10 | 2/8/2013 | 941 | -0.21 | NM | NM | NM | 0.0 | 0.0 | 12.7 | 4.3 | 8.6 | 14.0 | 0.0 | 14.0 | |
| VMP-47-10 | 2/8/2013 | 1546 | -0.03 | NM | NM | NM | 0.0 | 0.0 | 11.4 | 5.1 | 4.0 | 21.0 | 0.0 | 21.0 | |
| VMP-47-10 | 2/11/2013 | 941 | -0.80 | NM | NM | NM | 0.2 | 4.0 | 12.5 | 1.2 | 35.5 | 540 | 190 | 350 | |
| VMP-47-10 | 2/11/2013 | 1541 | -0.15 | NM | NM | NM | 0.0 | 0.0 | 12.5 | 1.9 | 23.2 | 110 | 0.0 | 110 | |
| VMP-47-10 | 2/12/2013 | 942 | -0.51 | NM | NM | NM | 0.0 | 0.0 | 12.3 | 3.7 | 1.8 | 2.7 | 0.0 | 2.7 | |
| VMP-47-10 | 2/12/2013 | 1546 | -0.05 | NM | NM | NM | 0.0 | 0.0 | 11.5 | 4.3 | 1.8 | 70.0 | 44.0 | 26.0 | |
| VMP-47-10 | 2/13/2013 | 1021 | 0.12 | NM | NM | NM | 0.2 | 5.0 | 12.6 | 1.4 | 42.5 | 550 | 210 | 340 | |
| VMP-47-10 | 2/13/2013 | 1536 | -0.02 | NM | NM | NM | 8.5 | OVR | 12.7 | 0.8 | 89.4 | 7,300 | 4,000 | 3,300 | |
| VMP-47-10 | 3/21/2013 | 1238 | 0.03 | NM | NM | NM | 0.0 | 0.0 | 10.9 | 5.4 | 2.8 | 96.9 | 0.0 | 96.9 | |

SEE LAST PAGE OF TABLE FOR NOTES

TABLE 8
TEDLAR SAMPLE DATA FOR VMP-1 AND VMP-47

| Sample ID | Date | Initial Reading Time (24-Hour) | Vacuum/Pressure | Gauging Information | | | Fixed Gases | | | | Soil Vapor Concentrations | | | | Comment(s) |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | Initial Reading (Inches of H2O) | Depth to Product (FT BTOC) | Depth to Water (FT BTOC) | Depth to Top of Screen (FT BTOC) | CH4 (%) | LEL (%) | $CO_2$ (%) | $O_2$ (%) | PID (ppmv) | THC (ppmv) | CH4 (ppmv) | PHC (ppmv) | |
| VMP-47-20 | 1/19/2013 | 938 | 0.11 | NM | NM | NM | 55.0 | OVR | 12.2 | 0.8 | 110 | 41,100 | 24,500 | 16,600 | |
| VMP-47-20 | 1/21/2013 | 1025 | -1.19 | NM | NM | NM | 1.4 | 28.0 | 12.6 | 1.2 | 84.5 | 1,850 | 860 | 990 | |
| VMP-47-20 | 1/22/2013 | 917 | -0.61 | NM | NM | NM | 0.1 | 3.0 | 11.8 | 3.3 | 22.0 | 236 | 10.0 | 226 | |
| VMP-47-20 | 1/22/2013 | 1618 | 0.18 | NM | NM | NM | 2.5 | 50.0 | 12.5 | 0.9 | 93.9 | 3,000 | 745 | 2,255 | |
| VMP-47-20 | 1/23/2013 | 807 | -0.24 | NM | NM | NM | 33.5 | OVR | 12.4 | 0.7 | 100 | 27,200 | 16,800 | 10,400 | |
| VMP-47-20 | 1/23/2013 | 1250 | 0.54 | NM | NM | NM | 43.0 | OVR | 12.6 | 0.8 | 92.9 | 34,700 | 21,500 | 13,200 | |
| VMP-47-20 | 1/24/2013 | 900 | -0.84 | NM | NM | NM | 0.1 | 2.0 | 11.4 | 4.9 | 19.1 | 255 | 121.0 | 134 | |
| VMP-47-20 | 1/24/2013 | 1617 | 0.03 | NM | NM | NM | 1.4 | 28.0 | 11.7 | 2.0 | 82.2 | 1,200 | 65.5 | 1,135 | |
| VMP-47-20 | 1/25/2013 | 900 | -0.26 | NM | NM | NM | 47.6 | OVR | 12.6 | 0.5 | 116 | 31,800 | 19,300 | 12,500 | |
| VMP-47-20 | 1/25/2013 | 1532 | -0.28 | NM | NM | NM | 63.5 | OVR | 12.8 | 1.0 | 108 | 33,500 | 23,600 | 9,900 | |
| VMP-47-20 | 1/28/2013 | 838 | -0.11 | NM | NM | NM | 57.5 | OVR | 12.7 | 0.6 | 108 | 39,300 | 24,700 | 14,600 | |
| VMP-47-20 | 1/28/2013 | 1627 | 0.14 | NM | NM | NM | 81.2 | OVR | 12.1 | 0.8 | 95.3 | 41,000 | 24,200 | 16,800 | |
| VMP-47-20 | 1/29/2013 | 927 | 0.19 | NM | NM | NM | 87.0 | OVR | 12.0 | 0.8 | 110 | 48,300 | 26,400 | 21,900 | |
| VMP-47-20 | 1/29/2013 | 1446 | 0.68 | NM | NM | NM | OVR | OVR | 12.0 | 1.0 | 110 | 59,000 | 33,400 | 25,600 | |
| VMP-47-20 | 1/30/2013 | 950 | -0.27 | NM | NM | NM | 79.2 | OVR | 12.7 | 0.5 | 124 | 41,700 | 24,300 | 17,400 | |
| VMP-47-20 | 1/30/2013 | 1532 | -0.74 | NM | NM | NM | 36.6 | OVR | 13.1 | 0.8 | 113 | 28,100 | 14,900 | 13,200 | |
| VMP-47-20 | 1/31/2013 | 912 | -0.40 | NM | NM | NM | 0.2 | 5.0 | 12.2 | 2.3 | 47.7 | 415 | 122.9 | 292 | |
| VMP-47-20 | 1/31/2013 | 1601 | -0.52 | NM | NM | NM | 0.2 | 5.0 | 12.5 | 2.5 | 33.6 | 395 | 131 | 265 | |
| VMP-47-20 | 2/1/2013 | 942 | -0.45 | NM | NM | NM | 0.0 | 0.0 | 10.4 | 6.2 | 5.2 | 57.5 | 0.0 | 57.5 | |
| VMP-47-20 | 2/1/2013 | 1612 | 0.01 | NM | NM | NM | 0.4 | 8.0 | 10.0 | 3.2 | 37.2 | 525 | 0.0 | 525 | |
| VMP-47-20 | 2/4/2013 | 927 | -0.13 | NM | NM | NM | 64.8 | OVR | 11.8 | 0.6 | 116 | 37,200 | 22,800 | 14,400 | |
| VMP-47-20 | 2/4/2013 | 1607 | -0.35 | NM | NM | NM | 67.7 | OVR | 12.2 | 0.6 | 107 | 36,700 | 22,300 | 14,400 | |
| VMP-47-20 | 2/5/2013 | 902 | -0.31 | NM | NM | NM | 18.7 | OVR | 12.7 | 1.0 | 108 | 13,300 | 8,800 | 4,500 | |
| VMP-47-20 | 2/5/2013 | 1548 | -0.12 | NM | NM | NM | 36.8 | OVR | 12.1 | 0.4 | 90.3 | 24,300 | 15,400 | 8,900 | |
| VMP-47-20 | 2/6/2013 | 917 | -0.04 | NM | NM | NM | 0.0 | 0.0 | 11.0 | 4.6 | 11.0 | 122 | 19.5 | 102 | |
| VMP-47-20 | 2/6/2013 | 1629 | 0.02 | NM | NM | NM | 0.2 | 5.0 | 11.9 | 1.9 | 51.8 | 750 | 0.0 | 750 | |
| VMP-47-20 | 2/7/2013 | 952 | 0.26 | NM | NM | NM | 36.2 | OVR | 12.2 | 1.0 | 84.7 | 28,300 | 15,000 | 13,300 | |
| VMP-47-20 | 2/7/2013 | 1446 | -0.05 | NM | NM | NM | 48.1 | OVR | 12.3 | 0.6 | 88.7 | 21,600 | 16,100 | 5,500 | |
| VMP-47-20 | 2/8/2013 | 942 | -0.49 | NM | NM | NM | 0.0 | 1.0 | 12.0 | 5.3 | 20.0 | 228 | 155 | 72.7 | |
| VMP-47-20 | 2/8/2013 | 1547 | -0.26 | NM | NM | NM | 0.0 | 1.0 | 10.9 | 5.1 | 12.5 | 153 | 40.3 | 113 | |
| VMP-47-20 | 2/11/2013 | 942 | -0.52 | NM | NM | NM | 0.5 | 10.0 | 12.4 | 2.1 | 48.0 | 810 | 190 | 620 | |
| VMP-47-20 | 2/11/2013 | 1542 | -0.14 | NM | NM | NM | 0.2 | 5.0 | 12.0 | 2.7 | 29.5 | 363 | 0.0 | 363 | |
| VMP-47-20 | 2/12/2013 | 943 | 0.09 | NM | NM | NM | 0.0 | 0.0 | 9.7 | 5.8 | 9.0 | 67.3 | 0.0 | 67.3 | |
| VMP-47-20 | 2/12/2013 | 1547 | 0.41 | NM | NM | NM | 6.5 | OVR | 12.0 | 1.0 | 77.0 | 5,400 | 2,230 | 3,170 | |
| VMP-47-20 | 2/13/2013 | 1022 | 0.03 | NM | NM | NM | 40.2 | OVR | 12.4 | 0.7 | 81.2 | 45,000 | 13,500 | 31,500 | |
| VMP-47-20 | 2/13/2013 | 1537 | -0.03 | NM | NM | NM | 50.9 | OVR | 12.5 | 0.6 | 89.6 | 29,700 | 15,600 | 14,100 | |
| VMP-47-20 | 3/21/2013 | 1242 | 0.13 | NM | NM | NM | 4.1 | 80.0 | 12.2 | 1.0 | 57.8 | 4,800 | 3,250 | 1,550 | |

SEE LAST PAGE OF TABLE FOR NOTES

TABLE 8
TEDLAR SAMPLE DATA FOR VMP-1 AND VMP-47

| Sample ID | Date | Initial Reading Time (24-Hour) | Vacuum/Pressure | Gauging Information | | | Fixed Gases | | | | Soil Vapor Concentrations | | | | Comment(s) |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | Initial Reading (Inches of H2O) | Depth to Product (FT BTOC) | Depth to Water (FT BTOC) | Depth to Top of Screen (FT BTOC) | CH4 (%) | LEL (%) | $CO_2$ (%) | $O_2$ (%) | PID (ppmv) | THC (ppmv) | CH4 (ppmv) | PHC (ppmv) | |
| VMP-47-30 | 1/19/2013 | 939 | 0.03 | NM | NM | NM | OVR | OVR | 11.0 | 0.8 | 96.5 | 93,300 | 61,400 | 31,900 | |
| VMP-47-30 | 1/21/2013 | 1020 | -1.25 | NM | NM | NM | 2.2 | 44.0 | 12.1 | 0.7 | 62.3 | 8,400 | 5,800 | 2,600 | |
| VMP-47-30 | 1/22/2013 | 918 | -0.62 | NM | NM | NM | 0.0 | 0.0 | 4.3 | 15.9 | 0.4 | 1.2 | 0.00 | 1.2 | |
| VMP-47-30 | 1/22/2013 | 1619 | 0.15 | NM | NM | NM | 3.9 | 79.0 | 12.2 | 0.7 | 52.8 | 13,700 | 10,400 | 3,300 | |
| VMP-47-30 | 1/23/2013 | 800 | -0.08 | NM | NM | NM | 56.8 | OVR | 11.8 | 0.6 | 75.5 | 58,800 | 40,700 | 18,100 | |
| VMP-47-30 | 1/23/2013 | 1300 | 0.31 | NM | NM | NM | 82.0 | OVR | 12.1 | 0.9 | 73.9 | 77,000 | 52,500 | 24,500 | |
| VMP-47-30 | 1/24/2013 | 905 | -0.55 | NM | NM | NM | 0.0 | 0.0 | 7.7 | 10.6 | 10.5 | 110 | 48.7 | 61.3 | |
| VMP-47-30 | 1/24/2013 | 1618 | 0.10 | NM | NM | NM | 0.2 | 5.0 | 11.2 | 1.8 | 43.0 | 380 | 167 | 213 | |
| VMP-47-30 | 1/25/2013 | 901 | -0.24 | NM | NM | NM | OVR | OVR | 11.4 | 0.8 | 93.8 | 74,700 | 49,500 | 25,200 | |
| VMP-47-30 | 1/25/2013 | 1533 | -0.11 | NM | NM | NM | OVR | OVR | 11.9 | 0.5 | 90.1 | 94,800 | 59,700 | 35,100 | |
| VMP-47-30 | 1/28/2013 | 839 | -0.15 | NM | NM | NM | OVR | OVR | 0.3 | 11.4 | 112 | 100,000 | 60,300 | 39,700 | |
| VMP-47-30 | 1/28/2013 | 1628 | 0.20 | NM | NM | NM | OVR | OVR | 11.0 | 1.0 | 83.6 | 110,000 | 68,800 | 41,200 | |
| VMP-47-30 | 1/29/2013 | 928 | 0.27 | NM | NM | NM | OVR | OVR | 10.5 | 0.8 | 99.0 | 120,000 | 66,500 | 53,500 | |
| VMP-47-30 | 1/29/2013 | 1447 | 1.00 | NM | NM | NM | OVR | OVR | 10.4 | 0.8 | 93.2 | 123,000 | 76,100 | 46,900 | |
| VMP-47-30 | 1/30/2013 | 955 | -0.61 | NM | NM | NM | OVR | OVR | 10.5 | 1.0 | 110 | 130,000 | 68,700 | 61,300 | |
| VMP-47-30 | 1/30/2013 | 1533 | -0.92 | NM | NM | NM | OVR | OVR | 11.1 | 1.2 | 135 | 67,100 | 37,400 | 29,700 | |
| VMP-47-30 | 1/31/2013 | 913 | -0.52 | NM | NM | NM | 0.2 | 4.0 | 8.8 | 7.8 | 56.7 | 243 | 0.0 | 243 | |
| VMP-47-30 | 1/31/2013 | 1602 | -0.67 | NM | NM | NM | 0.0 | 1.0 | 8.9 | 7.9 | 22.6 | 136 | 0.0 | 136 | |
| VMP-47-30 | 2/1/2013 | 943 | -0.45 | NM | NM | NM | 0.0 | 0.0 | 6.2 | 13.1 | 2.3 | 14.5 | 0.0 | 14.5 | |
| VMP-47-30 | 2/1/2013 | 1613 | 0.09 | NM | NM | NM | 0.0 | 0.0 | 7.9 | 7.2 | 6.4 | 45.0 | 0.0 | 45.0 | |
| VMP-47-30 | 2/4/2013 | 928 | 0.22 | NM | NM | NM | OVR | OVR | 10.5 | 0.7 | 89.1 | 88,000 | 56,500 | 31,500 | |
| VMP-47-30 | 2/4/2013 | 1608 | -0.15 | NM | NM | NM | OVR | OVR | 10.6 | 1.3 | 87.4 | 75,400 | 44,400 | 31,000 | |
| VMP-47-30 | 2/5/2013 | 903 | -0.35 | NM | NM | NM | 16.0 | OVR | 12.0 | 1.0 | 75.7 | 26,000 | 20,000 | 6,000 | |
| VMP-47-30 | 2/5/2013 | 1549 | -0.10 | NM | NM | NM | 58.6 | OVR | 11.2 | 0.7 | 68.1 | 41,900 | 32,600 | 9,300 | |
| VMP-47-30 | 2/6/2013 | 918 | -0.31 | NM | NM | NM | 0.0 | 1.0 | 7.2 | 10.4 | 9.0 | 198 | 91.5 | 107 | |
| VMP-47-30 | 2/6/2013 | 1630 | 0.28 | NM | NM | NM | 0.1 | 3.0 | 11.0 | 2.2 | 27.7 | 215 | 0.0 | 215 | |
| VMP-47-30 | 2/7/2013 | 953 | 0.16 | NM | NM | NM | 47.5 | OVR | 11.5 | 0.7 | 54.1 | 57,900 | 24,500 | 33,400 | |
| VMP-47-30 | 2/7/2013 | 1447 | -0.13 | NM | NM | NM | 80.4 | OVR | 11.3 | 0.6 | 61.9 | 63,600 | 42,300 | 21,300 | |
| VMP-47-30 | 2/8/2013 | 943 | -0.69 | NM | NM | NM | 0.0 | 1.0 | 6.7 | 12.8 | 13.5 | 79.0 | 5.9 | 73.1 | |
| VMP-47-30 | 2/8/2013 | 1548 | -0.36 | NM | NM | NM | 0.0 | 0.0 | 6.9 | 11.5 | 5.2 | 12.6 | 0.0 | 12.6 | |
| VMP-47-30 | 2/11/2013 | 943 | -0.69 | NM | NM | NM | 0.4 | 9.0 | 10.1 | 5.6 | 68.2 | 565 | 131 | 434 | |
| VMP-47-30 | 2/11/2013 | 1543 | -0.22 | NM | NM | NM | 0.0 | 1.0 | 9.1 | 8.0 | 28.4 | 162 | 0.0 | 162 | |
| VMP-47-30 | 2/12/2013 | 944 | 0.10 | NM | NM | NM | 0.0 | 0.0 | 9.6 | 5.9 | 9.7 | 67.5 | 0.0 | 67.5 | |
| VMP-47-30 | 2/12/2013 | 1548 | 0.39 | NM | NM | NM | 3.4 | 67.0 | 12.4 | 0.3 | 38.0 | 10,550 | 7,150 | 3,400 | |
| VMP-47-30 | 2/13/2013 | 1023 | 0.17 | NM | NM | NM | 71.9 | OVR | 11.8 | 0.5 | 64.7 | 58,400 | 35,300 | 23,100 | |
| VMP-47-30 | 2/13/2013 | 1538 | 0.14 | NM | NM | NM | OVR | OVR | 11.6 | 0.6 | 69.5 | 63,300 | 44,000 | 19,300 | |
| VMP-47-30 | 3/21/2013 | 1246 | 0.18 | NM | NM | NM | 4.9 | 99.0 | 12.2 | 0.8 | 37.5 | 12,200 | 10,200 | 2,000 | |

Notes:
1) NM = Not Measured, PID - Photo Ionization Detector; THC = Total Hydrocarbon Concentration; PHC = Petroleum Hydrocarbon Concentration;
OVR = Over-range; ppmv = Parts Per Million By Volume.

SEE LAST PAGE OF TABLE FOR NOTES

**TABLE 9**
**SVE SYSTEM MONTHLY MONITORING - SVE SAMPLING DATA**

| Sample ID | Date | Initial Reading Time (24-Hour) | Vacuum/Pressure | Air Flow | Groundwater | Fixed Gases | | | | Soil Vapor Concentrations | | | | Comments |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | Initial Reading (Inches of $H_2O$) | Pitot Tube Pressure (Inches of $H_2O$) | Depth to Water (feet) | CH4 (%) | LEL (%) | $CO_2$ (%) | $O_2$ (%) | PID (ppmv) | THC (ppmv) | CH4 (ppmv) | PHC (ppmv) | |
| SVE-3 | 2/1/2012 | 1547 | NA | NA | NA | 0.3 | 6.0 | 1.8 | 18.7 | 52.3 | 251 | 55.4 | 195 | |
| SVE-3 | 2/2/2012 | 848 | NA | NA | NA | 0.0 | 1.0 | 1.5 | 18.9 | 22.2 | 115 | 4.3 | 111 | |
| SVE-3 | 2/7/2012 | 1404 | -0.88 | NA | NA | 0.0 | 0.0 | 1.6 | 19.2 | 12.0 | 67.7 | 8.9 | 58.8 | |
| SVE-3 | 2/15/2012 | 1357 | -2.50 | NA | NA | 0.2 | 4.0 | 1.4 | 19.0 | 61.9 | 340 | 4.0 | 336 | |
| SVE-3 | 2/17/2012 | 1026 | -2.66 | NA | NA | 0.0 | 0.0 | 1.4 | 19.8 | 23.1 | 65.3 | 8.0 | 57.3 | |
| SVE-3 | 2/22/2012 | 1615 | -2.43 | NA | NA | 0.0 | 0.0 | 1.8 | 19.0 | 8.0 | 28.3 | 11.6 | 16.7 | |
| SVE-3 | 2/29/2012 | 827 | -1.86 | NA | NA | 0.0 | 0.0 | 2.0 | 18.6 | 19.5 | 136 | 16.4 | 120 | |
| SVE-3 | 3/21/2012 | 1416 | -1.15 | NA | NA | 0.0 | 0.0 | 1.6 | 18.4 | 0.5 | 0.0 | 0.0 | 0.0 | |
| SVE-3 | 4/18/2012 | 1545 | -2.26 | NA | NA | 0.0 | 0.0 | 2.3 | 17.3 | 3.5 | 46.0 | 20.0 | 26.0 | |
| SVE-3 | 5/16/2012 | 1513 | -3.08 | NA | NA | 0.0 | 0.0 | 2.1 | 18.5 | 1.0 | 0.0 | 0.0 | 0.0 | |
| SVE-3 | 6/20/2012 | 1413 | -0.68 | 0.00 | NE | 0.0 | 0.0 | 0.1 | 20.8 | 7.5 | 5.6 | 0.0 | 5.6 | Vacuum would not stabilize during sampling. Highest value observed is listed. |
| SVE-3 | 7/18/2012 | 1104 | -2.72 | 0.24 | NE | 0.0 | 0.0 | 1.4 | 19.0 | 0.7 | 4.7 | 0.0 | 4.7 | |
| SVE-3 | 8/15/2012 | 1440 | -2.78 | NA | NA | 0.0 | 0.0 | 1.8 | 18.7 | 0.9 | 3.5 | 0.0 | 3.5 | Water present in SVE vault. |
| SVE-3 | 9/19/2012 | 813 | -4.57 | NA | NE | 0.0 | 0.0 | 1.4 | 19.3 | 0.8 | 1.2 | 0.0 | 1.2 | |
| SVE-3 | 10/17/2012 | 1434 | -0.49 | 0.00 | NE | 0.0 | 0.0 | 0.7 | 19.8 | 0.4 | 1.1 | 0.0 | 1.1 | Water present in SVE vault. |
| SVE-3 | 11/20/2012 | 1210 | -1.19 | NA | NE | 0.0 | 0.0 | 0.5 | 20.4 | 13.0 | 31.9 | 3.4 | 28.5 | Vacuum would not stabilize during sampling. Highest value observed is listed. |
| SVE-3 | 12/19/2012 | NM | NM | NM | NM | NM | NM | NM | NM | NM | NM | NM | NM | Vehicle parked on well. Could not access. |
| SVE-3 | 1/16/2013 | 1339 | -0.55 | NM | NE | 0.0 | 0.0 | 0.2 | 20.7 | 4.5 | 45.4 | 11.2 | 34.2 | |
| SVE-3 | 2/25/2013 | NM | NM | NM | NM | NM | NM | NM | NM | NM | NM | NM | NM | Well valve closed off from SVE System. |
| SVE-3 | 3/20/2013 | NM | NM | NM | NM | NM | NM | NM | NM | NM | NM | NM | NM | Well valve closed off from SVE System. |
| SVE-4 | 2/1/2012 | 1535 | NA | NA | NA | 0.0 | 0.0 | 1.4 | 19.7 | 1.3 | 7.1 | 0.0 | 7.1 | |
| SVE-4 | 2/2/2012 | 912 | NA | NA | NA | 0.0 | 0.0 | 0.9 | 20.0 | 6.0 | 4.1 | 0.0 | 4.1 | |
| SVE-4 | 2/7/2012 | 1414 | -2.46 | NA | NA | 0.0 | 0.0 | 1.3 | 20.0 | 0.2 | 0.8 | 0.0 | 0.8 | |
| SVE-4 | 2/15/2012 | 1349 | -5.25 | NA | NA | 0.0 | 0.0 | 1.1 | 19.9 | 4.9 | 10.7 | 0.0 | 10.7 | |
| SVE-4 | 2/17/2012 | 1022 | -2.67 | NA | NA | 0.0 | 0.0 | 1.2 | 20.2 | 0.8 | 5.8 | 5.8 | 0.0 | |
| SVE-4 | 2/22/2012 | 1645 | -2.48 | NA | NA | 0.0 | 0.0 | 1.2 | 20.9 | 0.7 | 3.0 | 0.0 | 3.0 | |
| SVE-4 | 2/29/2012 | 816 | -1.96 | NA | NA | 0.0 | 0.0 | 1.0 | 20.4 | 2.4 | 29.8 | 8.4 | 21.3 | |
| SVE-4 | 3/21/2012 | 1405 | -1.16 | NA | NA | 0.0 | 0.0 | 0.9 | 19.5 | 0.3 | 0.0 | 0.0 | 0.0 | |
| SVE-4 | 4/18/2012 | 1545 | -2.26 | NA | NA | 0.0 | 0.0 | 1.4 | 18.8 | 3.0 | 6.3 | 0.0 | 6.3 | |
| SVE-4 | 5/16/2012 | 1524 | -3.06 | NA | NA | 0.0 | 0.0 | 1.5 | 19.0 | 1.0 | 0.0 | 0.0 | 0.0 | |
| SVE-4 | 6/20/2012 | 1359 | -1.16 | 0.00 | NE | 0.0 | 0.0 | 1.7 | 18.6 | 0.4 | 3.0 | 0.0 | 3.0 | Vacuum would not stabilize during sampling. Highest value observed is listed. |
| SVE-4 | 7/18/2012 | 1124 | -2.64 | 0.02 | NE | 0.0 | 0.0 | 1.2 | 19.2 | 0.9 | 4.2 | 0.0 | 4.2 | |
| SVE-4 | 8/15/2012 | 1455 | -2.78 | 0.00 | NA | 0.0 | 0.0 | 1.3 | 19.7 | 0.8 | 3.0 | 0.0 | 3.0 | |
| SVE-4 | 9/19/2012 | 825 | -4.59 | 0.00 | NE | 0.0 | 0.0 | 1.3 | 19.6 | 0.5 | 0.7 | 0.0 | 0.7 | |
| SVE-4 | 10/17/2012 | NM | NM | NM | NM | NM | NM | NM | NM | NM | NM | NM | NM | Vehicle parked on well. Could not access. |
| SVE-4 | 11/20/2012 | 1206 | -0.52 | NA | NE | 0.0 | 0.0 | 0.9 | 20.0 | 0.7 | 2.4 | 0.0 | 2.4 | |
| SVE-4 | 12/19/2012 | NM | NM | NM | NM | NM | NM | NM | NM | NM | NM | NM | NM | Vehicle parked on well. Could not access. |
| SVE-4 | 1/16/2013 | 1328 | -2.29 | NM | 13.78 | 0.0 | 0.0 | 0.7 | 20.2 | 0.2 | 0.4 | 0.0 | 0.4 | |
| SVE-4 | 2/25/2013 | NM | NM | NM | NM | NM | NM | NM | NM | NM | NM | NM | NM | Well valve closed off from SVE System. |
| SVE-4 | 3/20/2013 | NM | NM | NM | NM | NM | NM | NM | NM | NM | NM | NM | NM | Well valve closed off from SVE System. |
| SVE-5 | 2/15/2012 | NM | NM | NM | NM | NM | NM | NM | NM | NM | NM | NM | NM | |
| SVE-5 | 2/16/2012 | 1429 | -2.77 | NA | NA | 84.2 | OVR | 7.7 | 2.2 | 122 | 92000 | 64410 | 27590 | |
| SVE-5 | 2/17/2012 | 917 | -2.71 | NA | NA | 82.8 | OVR | 7.2 | 3.2 | 128 | 100000 | 71200 | 28800 | |
| SVE-5 | 2/22/2012 | 922 | -2.40 | NA | NA | OVR | OVR | 7.5 | 2.7 | 125 | 103000 | 69930 | 33070 | |
| SVE-5 | 2/29/2012 | 828 | -2.56 | NA | NA | OVR | OVR | 7.8 | 2.9 | 122 | 74380 | 54070 | 20310 | |
| SVE-5 | 3/21/2012 | 815 | -1.49 | NA | NA | 65.4 | OVR | 7.4 | 4.5 | 122 | 87300 | 57500 | 29800 | |
| SVE-5 | 4/18/2012 | 852 | -2.60 | 0.04 | 18.79 | 87.3 | OVR | 7.3 | 5.2 | 112 | 62000 | 42600 | 19400 | |
| SVE-5 | 5/16/2012 | 1450 | -2.33 | NA | NA | 85.3 | OVR | 6.7 | 5.2 | 111 | 32500 | 24700 | 7800 | |
| SVE-5 | 6/20/2012 | 640 | -2.89 | 0.00 | 18.82 | OVR | OVR | 7.5 | 7.2 | 94.0 | 50900 | 36300 | 14600 | |
| SVE-5 | 7/18/2012 | 550 | -3.04 | 0.00 | 17.77 | 84.4 | OVR | 6.6 | 8.8 | 91.6 | 49300 | 28100 | 21200 | |
| SVE-5 | 8/15/2012 | 1346 | -3.03 | 0.00 | NA | OVR | OVR | 7.6 | 8.4 | 123 | 48000 | 26550 | 21450 | |
| SVE-5 | 9/19/2012 | 1135 | -5.22 | NA | 19.78 | 80.2 | OVR | 7.1 | 9.9 | 131 | 29600 | 18900 | 10700 | |
| SVE-5 | 10/17/2012 | 1004 | -5.61 | 0.00 | 18.77 | 80.0 | OVR | 6.5 | 10.5 | 113 | 41800 | 21200 | 20600 | |
| SVE-5 | 11/20/2012 | 849 | -4.87 | 0.00 | 18.79 | 54.7 | OVR | 6.1 | 11.6 | 162 | 31700 | 18200 | 13500 | |
| SVE-5 | 12/19/2012 | 930 | -3.00 | NA | 18.77 | 33.8 | OVR | 6.2 | 11.5 | 181 | 18900 | 10700 | 8200 | |
| SVE-5 | 1/16/2013 | 943 | -2.98 | NM | 18.79 | 33.6 | OVR | 6.0 | 11.8 | 162 | 21000 | 9900 | 11100 | |
| SVE-5 | 2/25/2013 | 950 | -3.23 | NM | 18.78 | 33.3 | OVR | 6.0 | 11.9 | 173 | 20200 | 10700 | 9500 | |
| SVE-5 | 3/20/2013 | 1047 | -6.74 | NM | 18.78 | 32.9 | OVR | 5.2 | 13.2 | 101 | 19000 | 11300 | 7700 | PID rechecked and verified. |

SEE LAST PAGE OF TABLE FOR NOTES

**TABLE 9**
**SVE SYSTEM MONTHLY MONITORING - SVE SAMPLING DATA**

| Sample ID | Date | Initial Reading Time (24-Hour) | Vacuum/Pressure | Air Flow | Groundwater | Fixed Gases | | | | Soil Vapor Concentrations | | | | Comments |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | Initial Reading (Inches of $H_2O$) | Pitot Tube Pressure (Inches of $H_2O$) | Depth to Water (feet) | CH4 (%) | LEL (%) | $CO_2$ (%) | $O_2$ (%) | PID (ppmv) | THC (ppmv) | CH4 (ppmv) | PHC (ppmv) | |
| SVE-6 | 2/15/2012 | 1617 | -2.54 | NA | NA | OVR | OVR | 8.1 | 5.9 | 146 | 106000 | 47000 | 59000 | |
| SVE-6 | 2/16/2012 | 1437 | -2.77 | NA | NA | OVR | OVR | 9.4 | 4.2 | 142 | 93300 | 75300 | 18000 | |
| SVE-6 | 2/17/2012 | 928 | -2.67 | NA | NA | OVR | OVR | 9.9 | 1.6 | 147 | 150000 | 90200 | 59800 | |
| SVE-6 | 2/22/2012 | 938 | -2.37 | NA | NA | OVR | OVR | 9.6 | 1.3 | 143 | 192000 | 95000 | 97000 | |
| SVE-6 | 2/29/2012 | 836 | -2.63 | NA | NA | OVR | OVR | 9.1 | 3.5 | 140 | 111000 | 72580 | 38420 | |
| SVE-6 | 3/21/2012 | 822 | -1.51 | NA | NA | OVR | OVR | 8.0 | 5.8 | 131 | 78000 | 51100 | 26900 | |
| SVE-6 | 4/18/2012 | 909 | -2.63 | 0.32 | 22.78 | 86.5 | OVR | 7.5 | 6.0 | 135 | 58600 | 40000 | 18600 | |
| SVE-6 | 5/16/2012 | 1050 | -2.78 | 1.71 | NE | 71.1 | OVR | 7.1 | 7.2 | 148 | 49100 | 36000 | 13100 | |
| SVE-6 | 6/20/2012 | 654 | -2.91 | 0.01 | 22.83 | 62.9 | OVR | 6.9 | 6.6 | 126 | 33570 | 26500 | 7070 | |
| SVE-6 | 7/18/2012 | 602 | -3.07 | 0.01 | 22.79 | 46.9 | OVR | 7.9 | 7.6 | 155 | 34500 | 20000 | 14500 | |
| SVE-6 | 8/15/2012 | 1338 | -3.03 | NA | NA | 41.5 | OVR | 8.9 | 7.9 | 191 | 20600 | 19000 | 1600 | |
| SVE-6 | 9/19/2012 | 907 | -5.23 | NA | 22.80 | 26.5 | OVR | 8.2 | 10.1 | 232 | 12700 | 8900 | 3800 | |
| SVE-6 | 10/17/2012 | 1015 | -5.58 | 0.00 | 22.79 | 33.5 | OVR | 8.2 | 9.8 | 234 | 17400 | 15500 | 1900 | |
| SVE-6 | 11/20/2012 | 858 | -4.85 | 0.01 | 22.59 | 22.0 | OVR | 7.7 | 10.6 | 327 | 12700 | 10200 | 2500 | |
| SVE-6 | 12/19/2012 | 935 | -3.04 | NA | 22.43 | 11.9 | OVR | 7.9 | 10.7 | 347 | 8900 | 6000 | 2900 | |
| SVE-6 | 1/16/2013 | 952 | -3.06 | NM | 22.75 | 11.0 | OVR | 7.8 | 10.6 | 344 | 10300 | 6000 | 4300 | |
| SVE-6 | 2/25/2013 | 1012 | -3.25 | NM | 22.74 | 8.2 | OVR | 6.7 | 12.3 | 334 | 7700 | 4200 | 3500 | |
| SVE-6 | 3/20/2013 | 1216 | -6.90 | NM | 22.77 | 5.2 | OVR | 5.8 | 13.7 | 222 | 4400 | 2900 | 1500 | |
| SVE-7 | 2/15/2012 | 1627 | -2.51 | NA | NA | 81.0 | OVR | 12.0 | 1.1 | 147 | 67680 | 47000 | 20680 | |
| SVE-7 | 2/16/2012 | 1450 | -2.75 | NA | NA | 86.6 | OVR | 12.2 | 2.2 | 151 | 47470 | 39200 | 8270 | |
| SVE-7 | 2/17/2012 | 942 | -2.67 | NA | NA | 86.3 | OVR | 11.0 | 2.5 | 154 | 59100 | 40700 | 18400 | |
| SVE-7 | 2/22/2012 | 1010 | -2.39 | NA | NA | OVR | OVR | 9.9 | 2.4 | 151 | 71300 | 50600 | 20700 | |
| SVE-7 | 2/29/2012 | 854 | -2.51 | NA | NA | OVR | OVR | 9.1 | 2.9 | 147 | 78800 | 50380 | 28420 | |
| SVE-7 | 3/21/2012 | 835 | -1.49 | NA | NA | 85.4 | OVR | 9.7 | 3.9 | 143 | 74300 | 41800 | 32500 | |
| SVE-7 | 4/18/2012 | 931 | -2.63 | 0.12 | 22.71 | 62.0 | OVR | 8.9 | 6.2 | 152 | 31300 | 21000 | 10300 | |
| SVE-7 | 5/16/2012 | 1112 | -2.76 | 2.24 | NE | 65.5 | OVR | 8.0 | 8.7 | 159 | 31200 | 18600 | 12600 | |
| SVE-7 | 6/20/2012 | 718 | -2.95 | 0.01 | 22.78 | 63.8 | OVR | 8.6 | 8.9 | 132 | 26200 | 17250 | 8950 | |
| SVE-7 | 7/18/2012 | 623 | -3.07 | 0.16 | 22.71 | 58.4 | OVR | 7.9 | 10.1 | 159 | 28900 | 12000 | 16900 | |
| SVE-7 | 8/15/2012 | 1327 | -3.04 | NA | NA | 45.8 | OVR | 7.9 | 10.9 | 201 | 20230 | 11300 | 8930 | |
| SVE-7 | 9/19/2012 | 917 | -5.25 | NA | 22.40 | 29.4 | OVR | 6.1 | 13.3 | 259 | 24700 | 6600 | 18100 | |
| SVE-7 | 10/17/2012 | 1025 | -5.67 | 0.00 | 22.79 | 54.3 | OVR | 5.7 | 13.0 | 213 | 21600 | 15600 | 6000 | |
| SVE-7 | 11/20/2012 | 911 | -4.90 | 0.01 | 22.79 | 23.8 | OVR | 4.9 | 14.1 | 310 | 14700 | 7300 | 7400 | |
| SVE-7 | 12/19/2012 | 950 | -3.02 | NA | 22.73 | 7.8 | OVR | 4.6 | 14.6 | 293 | 6400 | 2800 | 3600 | |
| SVE-7 | 1/16/2013 | 1003 | -3.12 | NM | 22.75 | 7.3 | OVR | 4.5 | 14.6 | 290 | 7500 | 3600 | 3900 | |
| SVE-7 | 2/25/2013 | 1022 | -3.18 | NM | 22.76 | 6.0 | OVR | 3.9 | 15.5 | 288 | 4500 | 2200 | 2300 | |
| SVE-7 | 3/20/2013 | 1233 | -6.82 | NM | 22.73 | 6.3 | OVR | 3.2 | 16.7 | 212 | 5000 | 3100 | 1900 | |
| SVE-8 | 2/15/2012 | 1638 | -2.57 | NA | NA | OVR | OVR | 9.0 | 4.1 | 346 | 62000 | 36200 | 25800 | |
| SVE-8 | 2/16/2012 | 1501 | -2.77 | NA | NA | OVR | OVR | 10.5 | 1.4 | 362 | 71800 | 39000 | 32800 | |
| SVE-8 | 2/17/2012 | 950 | -2.70 | NA | NA | OVR | OVR | 10.1 | 1.9 | 350 | 71700 | 49600 | 22100 | |
| SVE-8 | 2/22/2012 | 1036 | -2.43 | NA | NA | OVR | OVR | 8.1 | 3.0 | 271 | 84450 | 66270 | 18180 | |
| SVE-8 | 2/29/2012 | 907 | -2.50 | NA | NA | OVR | OVR | 7.4 | 4.9 | 248 | 100000 | 69330 | 30670 | |
| SVE-8 | 3/21/2012 | 845 | -1.50 | NA | NA | OVR | OVR | 6.8 | 7.3 | 249 | 102000 | 60800 | 41200 | |
| SVE-8 | 4/18/2012 | 952 | -2.66 | 0.31 | NE | OVR | OVR | 7.0 | 8.7 | 305 | 56000 | 31900 | 24100 | |
| SVE-8 | 5/16/2012 | 1133 | -2.79 | 0.21 | NE | 69.5 | OVR | 6.0 | 11.0 | 400 | 22900 | 15700 | 7200 | |
| SVE-8 | 6/20/2012 | 735 | -2.97 | 0.01 | 22.27 | 48.8 | OVR | 6.9 | 9.8 | 415 | 13000 | 1550 | 11450 | |
| SVE-8 | 7/18/2012 | 642 | -3.12 | 0.33 | 22.23 | 32.0 | OVR | 7.0 | 9.9 | 531 | 11800 | 3100 | 8700 | |
| SVE-8 | 8/15/2012 | 1240 | -3.11 | 0.01 | NA | 29.7 | OVR | 7.4 | 10.3 | 529 | 8200 | 1670 | 6530 | |
| SVE-8 | 9/19/2012 | 928 | -5.34 | NA | 22.23 | 16.7 | OVR | 6.3 | 12.2 | 726 | 4620 | 794 | 3826 | |
| SVE-8 | 10/17/2012 | 1037 | -5.74 | 0.00 | 22.23 | 10.9 | OVR | 6.1 | 12.4 | 515 | 3950 | 630 | 3320 | |
| SVE-8 | 11/20/2012 | 922 | -5.00 | 0.00 | 22.25 | 6.5 | OVR | 5.9 | 12.4 | 557 | 2900 | 650 | 2250 | |
| SVE-8 | 12/19/2012 | 1015 | -3.25 | NA | 22.23 | 3.5 | 70.0 | 5.8 | 12.5 | 545 | 1900 | 370 | 1530 | |
| SVE-8 | 1/16/2013 | 1014 | -3.15 | NM | 22.25 | 2.2 | 45.0 | 5.5 | 12.5 | 432 | 2100 | 390 | 1710 | |
| SVE-8 | 2/25/2013 | 1031 | -3.20 | NM | 22.22 | 1.5 | 31.0 | 4.4 | 14.2 | 328 | 1450 | 292 | 1158 | |
| SVE-8 | 3/20/2013 | 1246 | -6.89 | NM | 20.44 | 0.8 | 17.0 | 3.2 | 16.2 | 203 | 1200 | 250 | 950 | |

SEE LAST PAGE OF TABLE FOR NOTES

**TABLE 9**
**SVE SYSTEM MONTHLY MONITORING - SVE SAMPLING DATA**

| Sample ID | Date | Initial Reading Time (24-Hour) | Vacuum/Pressure | Air Flow | Groundwater | Fixed Gases | | | | Soil Vapor Concentrations | | | | Comments |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | Initial Reading (Inches of $H_2O$) | Pitot Tube Pressure (Inches of $H_20$) | Depth to Water (feet) | CH4 (%) | LEL (%) | $CO_2$ (%) | $O_2$ (%) | PID (ppmv) | THC (ppmv) | CH4 (ppmv) | PHC (ppmv) | |
| SVE-9 | 2/15/2012 | 1646 | -2.61 | NA | NA | 81.8 | OVR | 3.8 | 14.2 | 440 | 28720 | 11960 | 16760 | |
| SVE-9 | 2/16/2012 | 1510 | -2.82 | NA | NA | OVR | OVR | 7.9 | 5.8 | 362 | 69000 | 24830 | 44170 | |
| SVE-9 | 2/17/2012 | 957 | -2.76 | NA | NA | OVR | OVR | 9.2 | 3.4 | 392 | 126000 | 36290 | 89710 | |
| SVE-9 | 2/22/2012 | 1056 | -2.44 | NA | NA | OVR | OVR | 9.3 | 3.2 | 400 | 121000 | 39270 | 81730 | |
| SVE-9 | 2/29/2012 | 925 | -2.64 | NA | NA | OVR | OVR | 8.1 | 5.1 | 402 | 86360 | 23660 | 62700 | |
| SVE-9 | 3/21/2012 | 855 | -1.47 | NA | NA | 4.3 | 86.0 | 1.1 | 18.3 | 238 | 5730 | 1490 | 4240 | |
| SVE-9 | 4/18/2012 | 1009 | -2.66 | 0.22 | 22.48 | OVR | OVR | 7.6 | 4.5 | 575 | 35000 | 7150 | 27850 | |
| SVE-9 | 5/16/2012 | 1152 | -2.82 | 1.87 | NE | 37.3 | OVR | 4.4 | 12.5 | 565 | 10100 | 1900 | 8200 | |
| SVE-9 | 6/20/2012 | 749 | -2.98 | 0.01 | 22.56 | 35.9 | OVR | 4.3 | 12.0 | 522 | 11850 | 2550 | 9300 | |
| SVE-9 | 7/18/2012 | 657 | -3.14 | 0.00 | 22.58 | 84.0 | OVR | 7.7 | 8.3 | 512 | 19000 | 2400 | 16600 | |
| SVE-9 | 8/15/2012 | 1215 | -3.25 | 0.00 | NA | OVR | OVR | 8.5 | 8.0 | 491 | 16700 | 4000 | 12700 | |
| SVE-9 | 9/19/2012 | 939 | -5.48 | NA | 21.44 | 74.3 | OVR | 7.2 | 9.7 | 687 | 11500 | 1860 | 9640 | |
| SVE-9 | 10/17/2012 | 1048 | -5.88 | 0.00 | 22.19 | 31.3 | OVR | 6.9 | 6.8 | 510 | 9400 | 1220 | 8180 | |
| SVE-9 | 11/20/2012 | 933 | -5.05 | 0.01 | 22.27 | 32.9 | OVR | 6.2 | 10.6 | 647 | 8200 | 1400 | 6800 | |
| SVE-9 | 12/19/2012 | 1040 | -3.12 | NA | 22.53 | 41.0 | OVR | 7.3 | 9.1 | 830 | 9300 | 1300 | 8000 | |
| SVE-9 | 1/16/2013 | 1023 | -3.25 | NM | 22.52 | 59.7 | OVR | 7.6 | 8.4 | 822 | 13700 | 1750 | 11950 | |
| SVE-9 | 2/25/2013 | 1039 | -3.35 | NM | 22.25 | 43.5 | OVR | 6.4 | 10.0 | 775 | 10700 | 1280 | 9420 | |
| SVE-9 | 3/20/2013 | 1300 | -7.03 | NM | 21.72 | 34.5 | OVR | 6.2 | 11.0 | 765 | 7300 | 1200 | 6100 | |
| SVE-10 | 2/1/2012 | 1415 | NA | NA | NA | OVR | OVR | 8.5 | 2.5 | 123 | 615000 | 390000 | 225000 | |
| SVE-10 | 2/2/2012 | 955 | NA | NA | NA | OVR | OVR | 8.2 | 3.0 | 115 | 950000 | 305000 | 645000 | |
| SVE-10 | 2/7/2012 | 950 | -2.89 | NA | NA | OVR | OVR | 7.9 | 2.0 | 101 | 1000000 | 768000 | 232000 | |
| SVE-10 | 2/15/2012 | 931 | -2.69 | NA | NA | OVR | OVR | 7.8 | 3.0 | 129 | 862000 | 289000 | 573000 | |
| SVE-10 | 2/22/2012 | 1126 | -2.44 | NA | NA | OVR | OVR | 7.3 | 4.9 | 173 | 790000 | 204000 | 586000 | |
| SVE-10 | 2/29/2012 | 942 | -1.40 | NA | NA | OVR | OVR | 5.7 | 9.4 | 223 | 157000 | 73830 | 83170 | |
| SVE-10 | 3/21/2012 | 904 | -1.51 | NA | NA | OVR | OVR | 8.0 | 4.8 | 172 | 442000 | 158000 | 284000 | |
| SVE-10 | 4/18/2012 | 1028 | -2.56 | 1.66 | 22.59 | OVR | OVR | 8.4 | 5.2 | 270 | 139000 | 66500 | 72500 | |
| SVE-10 | 5/16/2012 | 1206 | -2.73 | 0.67 | NE | OVR | OVR | 8.2 | 6.7 | 325 | 69900 | 46100 | 23800 | |
| SVE-10 | 6/20/2012 | 805 | -3.24 | 0.00 | 22.65 | OVR | OVR | 9.1 | 6.2 | 317 | 38700 | 35100 | 3600 | |
| SVE-10 | 7/18/2012 | 713 | -2.93 | 0.04 | 22.62 | OVR | OVR | 8.6 | 7.2 | 233 | 46900 | 20300 | 26600 | |
| SVE-10 | 8/15/2012 | 1201 | -2.94 | 0.00 | NA | OVR | OVR | 9.3 | 6.8 | 398 | 30200 | 10500 | 19700 | |
| SVE-10 | 9/19/2012 | 948 | -4.68 | NA | 22.65 | OVR | OVR | 7.6 | 9.4 | 569 | 19400 | 4500 | 14900 | |
| SVE-10 | 10/17/2012 | 1149 | -6.87 | 0.00 | 22.58 | OVR | OVR | 7.9 | 9.5 | 563 | 25100 | 6500 | 18600 | |
| SVE-10 | 11/20/2012 | 943 | -4.22 | 0.01 | 22.59 | 71.8 | OVR | 8.3 | 9.2 | 589 | 13300 | 5300 | 8000 | |
| SVE-10 | 12/19/2012 | 1055 | -2.87 | NA | 22.57 | 41.0 | OVR | 7.7 | 10.0 | 650 | 12200 | 3800 | 8400 | |
| SVE-10 | 1/16/2013 | 1032 | -3.02 | NM | 22.57 | 44.3 | OVR | 7.8 | 9.4 | 635 | 13600 | 4300 | 9300 | |
| SVE-10 | 2/25/2013 | 1046 | -3.20 | NM | 22.54 | 51.9 | OVR | 7.3 | 10.0 | 585 | 16700 | 6600 | 10100 | |
| SVE-10 | 3/20/2013 | 1314 | -6.72 | NM | 22.55 | 65.8 | OVR | 6.3 | 11.9 | 440 | 18900 | 8900 | 10000 | |
| SVE-11 | 2/1/2012 | 1428 | NA | NA | NA | OVR | OVR | 9.6 | 1.2 | 287 | 205000 | 100000 | 105000 | |
| SVE-11 | 2/2/2012 | 1002 | NA | NA | NA | OVR | OVR | 9.5 | 1.5 | 270 | 300000 | 81400 | 218600 | |
| SVE-11 | 2/7/2012 | 1006 | -3.05 | NA | NA | OVR | OVR | 9.3 | 1.5 | 247 | 379000 | 125000 | 254000 | |
| SVE-11 | 2/15/2012 | 955 | -2.73 | NA | NA | OVR | OVR | 8.5 | 1.5 | 295 | 135000 | 90000 | 45000 | |
| SVE-11 | 2/22/2012 | 1148 | -2.54 | NA | NA | OVR | OVR | 8.0 | 2.1 | 321 | 229000 | 103000 | 126000 | |
| SVE-11 | 2/29/2012 | 1003 | -2.58 | NA | NA | OVR | OVR | 7.9 | 1.9 | 316 | 116000 | 62000 | 54000 | |
| SVE-11 | 3/21/2012 | 914 | -1.53 | NA | NA | OVR | OVR | 8.1 | 1.1 | 329 | 264000 | 87000 | 177000 | |
| SVE-11 | 4/18/2012 | 1052 | -2.60 | 0.06 | 22.78 | OVR | OVR | 9.0 | 1.4 | 410 | 105000 | 43700 | 61300 | |
| SVE-11 | 5/16/2012 | 1223 | -2.73 | 1.41 | NE | OVR | OVR | 10.1 | 2.4 | 485 | 70000 | 29400 | 40600 | |
| SVE-11 | 6/20/2012 | 821 | -3.31 | 0.00 | 22.82 | OVR | OVR | 11.1 | 1.4 | 364 | 61600 | 36600 | 25000 | |
| SVE-11 | 7/18/2012 | 735 | -2.95 | 0.02 | 22.77 | OVR | OVR | 11.2 | 2.4 | 240 | 73400 | 21500 | 51900 | |
| SVE-11 | 8/15/2012 | 1134 | -3.08 | 0.00 | NA | OVR | OVR | 11.7 | 2.3 | 409 | 60800 | 12800 | 48000 | |
| SVE-11 | 9/19/2012 | 958 | -5.15 | NA | 22.78 | OVR | OVR | 10.3 | 4.6 | 508 | 52400 | 9700 | 42700 | |
| SVE-11 | 10/17/2012 | 1202 | -6.96 | 0.00 | 22.77 | OVR | OVR | 9.9 | 4.5 | 584 | 52900 | 7900 | 45000 | |
| SVE-11 | 11/20/2012 | 956 | -5.14 | 0.02 | 22.80 | OVR | OVR | 9.7 | 4.8 | 566 | 39600 | 5800 | 33800 | |
| SVE-11 | 12/19/2012 | 1100 | -2.96 | NA | 22.77 | OVR | OVR | 10.1 | 4.4 | 820 | 29600 | 7400 | 22200 | |
| SVE-11 | 1/16/2013 | 1042 | -3.03 | NM | 22.78 | OVR | OVR | 9.6 | 5.0 | 750 | 28200 | 7100 | 21100 | |
| SVE-11 | 2/25/2013 | 1052 | -3.17 | NM | 22.77 | OVR | OVR | 9.1 | 6.0 | 710 | 20400 | 6000 | 14400 | |
| SVE-11 | 3/20/2013 | 1330 | -6.86 | NM | 21.78 | OVR | OVR | 8.0 | 8.0 | 752 | 22100 | 4700 | 17400 | |

SEE LAST PAGE OF TABLE FOR NOTES

**TABLE 9**
**SVE SYSTEM MONTHLY MONITORING - SVE SAMPLING DATA**

| Sample ID | Date | Initial Reading Time (24-Hour) | Vacuum/Pressure | Air Flow | Groundwater | Fixed Gases | | | | Soil Vapor Concentrations | | | | Comments |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | Initial Reading (Inches of $H_2O$) | Pitot Tube Pressure (Inches of $H_2O$) | Depth to Water (feet) | CH4 (%) | LEL (%) | $CO_2$ (%) | $O_2$ (%) | PID (ppmv) | THC (ppmv) | CH4 (ppmv) | PHC (ppmv) | |
| SVE-12 | 2/1/2012 | 1455 | NA | NA | NA | OVR | OVR | 5.0 | 9.0 | 190 | 315000 | 125000 | 190000 | |
| SVE-12 | 2/2/2012 | 1015 | NA | NA | NA | OVR | OVR | 4.5 | 10.0 | 200 | 400000 | 146000 | 254000 | |
| SVE-12 | 2/7/2012 | 1017 | -3.15 | NA | NA | 0.5 | 11.0 | 0.2 | 20.8 | 78.2 | 814 | 240 | 574 | |
| SVE-12 | 2/15/2012 | 1017 | NA | NA | NA | OVR | OVR | 2.2 | 15.4 | 224 | 78900 | 48300 | 30600 | |
| SVE-12 | 2/22/2012 | 1444 | -2.46 | NA | NA | OVR | OVR | 2.5 | 14.9 | 291 | 83400 | 53200 | 30200 | |
| SVE-12 | 2/29/2012 | 1029 | -2.61 | NA | NA | OVR | OVR | 4.0 | 11.6 | 288 | 239000 | 78410 | 160590 | |
| SVE-12 | 3/21/2012 | 925 | -1.55 | NA | NA | 1.5 | 31.0 | 0.2 | 20.7 | 115 | 2990 | 1360 | 1630 | |
| SVE-12 | 4/18/2012 | 1110 | -2.66 | 0.13 | 20.69 | 61.0 | OVR | 1.2 | 18.1 | 395 | 22000 | 7330 | 14670 | |
| SVE-12 | 5/16/2012 | 1238 | -2.84 | 1.32 | NE | 50.0 | OVR | 1.0 | 18.1 | 372 | 14200 | 9200 | 5000 | |
| SVE-12 | 6/20/2012 | 842 | -3.23 | 0.00 | 22.54 | OVR | OVR | 3.6 | 12.8 | 369 | 62500 | 17200 | 45300 | |
| SVE-12 | 7/18/2012 | 756 | -3.03 | 0.01 | 22.68 | OVR | OVR | 4.3 | 12.1 | 238 | 110000 | 15500 | 94500 | |
| SVE-12 | 8/15/2012 | 1116 | -3.23 | 0.00 | NA | OVR | OVR | 5.3 | 10.8 | 319 | 90200 | 14100 | 76100 | |
| SVE-12 | 9/19/2012 | 1013 | -5.31 | NA | 22.70 | OVR | OVR | 5.9 | 10.4 | 381 | 84800 | 15700 | 69100 | |
| SVE-12 | 10/17/2012 | 1251 | -7.01 | 0.00 | 22.71 | OVR | OVR | 7.6 | 7.6 | 399 | 135000 | 18100 | 116900 | |
| SVE-12 | 11/20/2012 | 1006 | -4.98 | 0.10 | 22.74 | OVR | OVR | 7.3 | 6.2 | 373 | 134000 | 14600 | 119400 | |
| SVE-12 | 12/19/2012 | 1120 | -3.02 | NA | 22.69 | OVR | OVR | 6.1 | 7.9 | 625 | 121000 | 10900 | 110100 | |
| SVE-12 | 1/16/2013 | 1053 | -3.01 | NM | 22.73 | OVR | OVR | 4.9 | 9.5 | 535 | 110000 | 10300 | 99700 | |
| SVE-12 | 2/25/2013 | 1059 | -3.22 | NM | 22.70 | OVR | OVR | 5.4 | 7.7 | 633 | 108000 | 8900 | 99100 | |
| SVE-12 | 3/20/2013 | 1346 | -7.04 | NM | 20.48 | OVR | OVR | 5.6 | 8.9 | 690 | 77200 | 4200 | 73000 | |
| SVE-13 | 2/2/2012 | 1350 | NA | NA | NA | OVR | OVR | 13.3 | 2.3 | 395 | 61400 | 29300 | 32100 | |
| SVE-13 | 2/3/2012 | 757 | -3.55 | NA | NA | OVR | OVR | 12.2 | 2.5 | 330 | 104000 | 43600 | 60400 | |
| SVE-13 | 2/7/2012 | 1028 | -2.32 | NA | NA | OVR | OVR | 10.1 | 3.1 | 284 | 222000 | 48500 | 173500 | |
| SVE-13 | 2/15/2012 | 1043 | -2.40 | NA | NA | OVR | OVR | 7.5 | 9.5 | 375 | 87700 | 20000 | 67700 | |
| SVE-13 | 2/22/2012 | 1502 | -1.95 | NA | NA | OVR | OVR | 7.1 | 8.4 | 396 | 87380 | 51590 | 35790 | |
| SVE-13 | 2/29/2012 | 1056 | -1.63 | NA | NA | OVR | OVR | 7.1 | 7.8 | 419 | 100000 | 37160 | 62840 | |
| SVE-13 | 3/21/2012 | 941 | -1.58 | NA | NA | 9.6 | OVR | 3.5 | 15.6 | 675 | 6100 | 154 | 5946 | |
| SVE-13 | 4/18/2012 | 1129 | -2.14 | 0.07 | 22.72 | OVR | OVR | 6.5 | 10.1 | 558 | 35500 | 10500 | 25000 | |
| SVE-13 | 5/16/2012 | 1310 | -2.27 | 0.00 | NE | OVR | OVR | 6.2 | 11.0 | 675 | 24300 | 6600 | 17700 | |
| SVE-13 | 6/20/2012 | 905 | -2.46 | 0.01 | 22.79 | 82.1 | OVR | 7.3 | 2.5 | 575 | 19200 | 4300 | 14900 | |
| SVE-13 | 7/18/2012 | 828 | -2.51 | 0.03 | 22.72 | 53.3 | OVR | 7.0 | 11.4 | 590 | 15300 | 3200 | 12100 | |
| SVE-13 | 8/15/2012 | 1100 | -2.56 | 0.01 | NA | 52.4 | OVR | 6.9 | 11.7 | 576 | 13280 | 2960 | 10320 | |
| SVE-13 | 9/19/2012 | 1029 | -4.06 | NA | 22.72 | 33.5 | OVR | 6.2 | 13.1 | 766 | 9260 | 1510 | 7750 | |
| SVE-13 | 10/17/2012 | 1301 | -4.34 | 0.00 | 22.73 | 22.1 | OVR | 6.7 | 12.4 | 759 | 8150 | 210 | 7940 | |
| SVE-13 | 11/20/2012 | 1018 | -3.94 | 0.01 | 22.75 | 11.9 | OVR | 6.3 | 12.6 | 658 | 4650 | 1050 | 3600 | |
| SVE-13 | 12/19/2012 | 1135 | -2.52 | NA | 22.72 | 6.4 | OVR | 6.3 | 12.8 | 620 | 5000 | 560 | 4440 | |
| SVE-13 | 1/16/2013 | 1104 | -2.50 | NM | 22.78 | 5.7 | OVR | 6.5 | 12.1 | 745 | 5400 | 490 | 4910 | |
| SVE-13 | 2/25/2013 | 1109 | -0.64 | NM | 22.71 | 0.2 | 4.0 | 0.3 | 20.7 | 41.6 | 143 | 25.0 | 118 | Valve closed visually 50% at well head. |
| SVE-13 | 3/20/2013 | 1401 | -4.39 | NM | 22.68 | 0.3 | 7.0 | 3.3 | 16.9 | 110 | 380 | 63.8 | 316 | Valve closed visually 50% at well head. |
| SVE-14 | 2/2/2012 | 1358 | NA | NA | NA | OVR | OVR | 12.1 | 1.5 | 259 | 221000 | 86200 | 134800 | |
| SVE-14 | 2/3/2012 | 807 | -3.53 | NA | NA | OVR | OVR | 11.9 | 1.6 | 230 | 230000 | 90000 | 140000 | |
| SVE-14 | 2/7/2012 | 1040 | -2.32 | NA | NA | OVR | OVR | 12.0 | 1.7 | 259 | 123000 | 64400 | 58600 | |
| SVE-14 | 2/15/2012 | 1105 | -2.40 | NA | NA | OVR | OVR | 10.7 | 3.4 | 291 | 129000 | 51000 | 78000 | |
| SVE-14 | 2/22/2012 | 1514 | -2.20 | NA | NA | OVR | OVR | 10.1 | 3.6 | 396 | 90500 | 54560 | 35940 | |
| SVE-14 | 2/29/2012 | 1111 | -1.66 | NA | NA | OVR | OVR | 10.1 | 3.1 | 423 | 89400 | 29690 | 59710 | |
| SVE-14 | 3/21/2012 | 954 | -1.56 | NA | NA | 12.2 | OVR | 6.6 | 8.9 | 658 | 5490 | 477 | 5013 | |
| SVE-14 | 4/18/2012 | 1146 | -2.11 | 0.48 | 22.41 | OVR | OVR | 9.7 | 3.4 | 515 | 51800 | 19200 | 32600 | |
| SVE-14 | 5/16/2012 | 1328 | -2.52 | 0.01 | NE | OVR | OVR | 9.5 | 6.6 | 575 | 16700 | 7800 | 8900 | |
| SVE-14 | 6/20/2012 | 1025 | -2.35 | 0.01 | 22.45 | OVR | OVR | 10.0 | 5.1 | 559 | 26600 | 11300 | 15300 | |
| SVE-14 | 7/18/2012 | 852 | -2.49 | 0.02 | 22.41 | 78.9 | OVR | 10.2 | 6.4 | 425 | 24200 | 8300 | 15900 | |
| SVE-14 | 8/15/2012 | 1043 | -2.57 | 0.01 | NA | 78.9 | OVR | 10.4 | 7.2 | 461 | 15600 | 8200 | 7400 | |
| SVE-14 | 9/19/2012 | 1040 | -4.07 | NA | 22.40 | 68.1 | OVR | 9.9 | 8.2 | 585 | 18400 | 8300 | 10100 | |
| SVE-14 | 10/17/2012 | 1313 | -4.34 | 0.00 | 22.42 | 61.5 | OVR | 9.9 | 8.2 | 617 | 18500 | 7500 | 11000 | |
| SVE-14 | 11/20/2012 | 1030 | -3.88 | 0.01 | 22.45 | 36.8 | OVR | 9.2 | 9.1 | 563 | 11700 | 6200 | 5500 | |
| SVE-14 | 12/19/2012 | 1150 | -2.53 | NA | 22.42 | 26.8 | OVR | 9.4 | 9.0 | 655 | 10800 | 4800 | 6000 | |
| SVE-14 | 1/16/2013 | 1115 | -2.50 | NM | 22.41 | 20.5 | OVR | 9.0 | 9.1 | 648 | 10300 | 3800 | 6500 | |
| SVE-14 | 2/25/2013 | 1116 | -0.66 | NM | 22.40 | 0.1 | 2.0 | 5.3 | 14.0 | 5.0 | 122 | 10.7 | 111 | Valve closed visually 50% at well head. |
| SVE-14 | 3/20/2013 | 1415 | -4.21 | NM | 22.43 | 5.7 | OVR | 7.1 | 12.0 | 420 | 3200 | 1300 | 1900 | Valve closed visually 50% at well head. |

SEE LAST PAGE OF TABLE FOR NOTES

**TABLE 9**
**SVE SYSTEM MONTHLY MONITORING - SVE SAMPLING DATA**

| Sample ID | Date | Initial Reading Time (24-Hour) | Vacuum/Pressure | Air Flow | Groundwater | Fixed Gases | | | | Soil Vapor Concentrations | | | | Comments |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | Initial Reading (Inches of $H_2O$) | Pitot Tube Pressure (Inches of $H_2O$) | Depth to Water (feet) | CH4 (%) | LEL (%) | $CO_2$ (%) | $O_2$ (%) | PID (ppmv) | THC (ppmv) | CH4 (ppmv) | PHC (ppmv) | |
| SVE-15 | 2/2/2012 | 1416 | NA | NA | NA | OVR | OVR | 12.2 | 2.6 | 327 | 61600 | 47200 | 14400 | |
| SVE-15 | 2/3/2012 | 817 | -3.55 | NA | NA | OVR | OVR | 10.9 | 4.5 | 305 | 92300 | 55000 | 37300 | |
| SVE-15 | 2/7/2012 | 1047 | -2.34 | NA | NA | OVR | OVR | 10.0 | 5.1 | 294 | 65300 | 35900 | 29400 | |
| SVE-15 | 2/15/2012 | 1112 | -2.33 | NA | NA | OVR | OVR | 9.2 | 6.7 | 364 | 68900 | 34250 | 34650 | |
| SVE-15 | 2/22/2012 | 1325 | -2.41 | NA | NA | OVR | OVR | 9.0 | 5.8 | 471 | 55700 | 30670 | 25030 | |
| SVE-15 | 2/29/2012 | 1329 | -1.30 | NA | NA | OVR | OVR | 9.9 | 5.9 | 420 | 50000 | 24200 | 25800 | |
| SVE-15 | 3/21/2012 | 959 | -1.54 | NA | NA | OVR | OVR | 8.8 | 5.8 | 433 | 60500 | 22800 | 37700 | |
| SVE-15 | 4/18/2012 | 1155 | -2.11 | 0.03 | NE | OVR | OVR | 8.7 | 5.5 | 555 | 36000 | 11400 | 24600 | |
| SVE-15 | 5/16/2012 | 1335 | -2.28 | 0.01 | NE | 83.7 | OVR | 8.7 | 7.4 | 660 | 13900 | 6100 | 7800 | |
| SVE-15 | 6/20/2012 | 1033 | -2.29 | 0.00 | NE | 80.3 | OVR | 9.0 | 7.3 | 640 | 17280 | 6260 | 11020 | |
| SVE-15 | 7/18/2012 | 859 | -2.49 | 0.13 | NE | 62.2 | OVR | 9.2 | 7.8 | 475 | 15700 | 6200 | 9500 | |
| SVE-15 | 8/15/2012 | 1038 | -2.61 | 0.00 | NA | 73.6 | OVR | 9.6 | 8.1 | 501 | 18300 | 7600 | 10700 | |
| SVE-15 | 9/19/2012 | 1045 | -4.05 | NA | 22.97 | 59.7 | OVR | 8.9 | 9.7 | 664 | 15400 | 5470 | 9930 | |
| SVE-15 | 10/17/2012 | 1319 | -4.38 | 0.00 | NE | 56.9 | OVR | 9.2 | 8.9 | 720 | 17100 | 3930 | 13170 | |
| SVE-15 | 11/20/2012 | 1037 | -3.92 | 0.55 | 22.97 | 37.4 | OVR | 8.1 | 10.1 | 651 | 7400 | 4050 | 3350 | |
| SVE-15 | 12/19/2012 | 1155 | -2.56 | NA | NE | 33.9 | OVR | 8.4 | 10.0 | 770 | 12100 | 5200 | 6900 | |
| SVE-15 | 1/16/2013 | 1120 | -2.49 | NM | 22.79 | 30.9 | OVR | 8.0 | 10.0 | 770 | 12000 | 2800 | 9200 | |
| SVE-15 | 2/25/2013 | 1119 | -3.15 | NM | 22.71 | 25.4 | OVR | 6.7 | 11.9 | 588 | 10900 | 4400 | 6500 | Valve closed visually 50% at well head. |
| SVE-15 | 3/20/2013 | 1422 | -5.91 | NM | 22.72 | 21.0 | OVR | 5.8 | 13.2 | 675 | 4400 | 1700 | 2700 | Valve closed visually 50% at well head. |
| SVE-16 | 2/2/2012 | 1407 | NA | NA | NA | OVR | OVR | 12.4 | 1.3 | 381 | 222000 | 72500 | 149500 | |
| SVE-16 | 2/3/2012 | 823 | -3.59 | NA | NA | OVR | OVR | 12.8 | 1.0 | 364 | 153000 | 67000 | 86000 | |
| SVE-16 | 2/7/2012 | 1057 | -2.41 | NA | NA | OVR | OVR | 12.8 | 1.4 | 376 | 86300 | 55900 | 30400 | |
| SVE-16 | 2/15/2012 | 1119 | -2.29 | NA | NA | OVR | OVR | 12.1 | 1.7 | 417 | 114000 | 51000 | 63000 | |
| SVE-16 | 2/22/2012 | 1543 | -2.09 | NA | NA | OVR | OVR | 11.3 | 2.2 | 480 | 114000 | 55800 | 58200 | |
| SVE-16 | 2/29/2012 | 1338 | -1.15 | NA | NA | OVR | OVR | 11.8 | 2.0 | 390 | 92200 | 49300 | 42900 | |
| SVE-16 | 3/21/2012 | 1003 | -1.43 | NA | NA | OVR | OVR | 11.2 | 1.6 | 539 | 82500 | 19000 | 63500 | |
| SVE-16 | 4/18/2012 | 1204 | -2.13 | 1.29 | 22.92 | OVR | OVR | 11.0 | 1.7 | 510 | 72100 | 32300 | 39800 | |
| SVE-16 | 5/16/2012 | 1342 | -2.29 | 0.01 | NE | OVR | OVR | 11.2 | 2.2 | 472 | 59500 | 35700 | 23800 | |
| SVE-16 | 6/20/2012 | 1040 | -2.32 | 0.00 | 22.98 | OVR | OVR | 11.6 | 2.2 | 463 | 48200 | 35000 | 13200 | |
| SVE-16 | 7/18/2012 | 909 | -2.51 | 0.08 | 22.91 | OVR | OVR | 11.4 | 4.0 | 270 | 38600 | 24800 | 13800 | |
| SVE-16 | 8/15/2012 | 1031 | -2.65 | 0.00 | NA | OVR | OVR | 11.4 | 5.1 | 367 | 44000 | 21500 | 22500 | |
| SVE-16 | 9/19/2012 | 1050 | -4.15 | NA | 22.93 | OVR | OVR | 11.1 | 5.8 | 492 | 39400 | 21600 | 17800 | |
| SVE-16 | 10/17/2012 | 1325 | -4.46 | 0.00 | 22.92 | 82.6 | OVR | 11.0 | 6.2 | 509 | 33400 | 27200 | 6200 | |
| SVE-16 | 11/20/2012 | 1044 | -3.86 | 0.48 | 22.95 | 50.3 | OVR | 10.6 | 6.4 | 465 | 23600 | 3500 | 20100 | |
| SVE-16 | 12/19/2012 | 1245 | -2.52 | NA | 22.92 | 39.8 | OVR | 11.1 | 5.8 | 555 | 21400 | 13700 | 7700 | |
| SVE-16 | 1/16/2013 | 1125 | -2.52 | NM | 22.94 | 30.8 | OVR | 10.4 | 6.4 | 540 | 19300 | 10000 | 9300 | |
| SVE-16 | 2/25/2013 | 1123 | -3.09 | NM | 22.95 | 30.9 | OVR | 10.1 | 6.6 | 455 | 15100 | 6400 | 8700 | Valve closed visually 50% at well head. |
| SVE-16 | 3/20/2013 | 1428 | -5.57 | NM | 22.93 | 21.5 | OVR | 8.5 | 9.1 | 480 | 11300 | 7700 | 3600 | Valve closed visually 50% at well head. |
| SVE-17 | 2/6/2012 | 1405 | -2.61 | NA | NA | OVR | OVR | 13.7 | 2.6 | 357 | 129000 | 54100 | 74900 | |
| SVE-17 | 2/7/2012 | 1100 | -2.50 | NA | NA | OVR | OVR | 12.5 | 3.5 | 364 | 50000 | 41800 | 8200 | |
| SVE-17 | 2/8/2012 | 930 | -2.85 | NA | NA | OVR | OVR | 11.0 | 4.4 | 376 | 65000 | 29900 | 35100 | |
| SVE-17 | 2/15/2012 | 1126 | -2.29 | NA | NA | OVR | OVR | 9.4 | 6.4 | 321 | 65000 | 51200 | 13800 | |
| SVE-17 | 2/22/2012 | 1552 | -2.17 | NA | NA | OVR | OVR | 8.7 | 7.0 | 306 | 102000 | 73270 | 28730 | |
| SVE-17 | 2/29/2012 | 1346 | -1.16 | NA | NA | OVR | OVR | 9.2 | 6.9 | 242 | 91500 | 66300 | 25200 | |
| SVE-17 | 3/21/2012 | 1008 | -1.32 | NA | NA | 5.5 | OVR | 9.2 | 2.1 | 345 | 13390 | 7600 | 5790 | |
| SVE-17 | 4/18/2012 | 1216 | -2.20 | 1.48 | 22.62 | OVR | OVR | 7.6 | 8.4 | 285 | 70500 | 50000 | 20500 | |
| SVE-17 | 5/16/2012 | 1352 | -2.37 | 0.03 | NE | OVR | OVR | 7.4 | 9.0 | 300 | 71300 | 47900 | 23400 | |
| SVE-17 | 6/20/2012 | 1047 | -2.41 | 0.01 | 22.62 | OVR | OVR | 7.6 | 8.7 | 324 | 64000 | 36500 | 27500 | |
| SVE-17 | 7/18/2012 | 922 | -2.61 | 0.01 | 22.59 | 84.1 | OVR | 7.7 | 9.1 | 250 | 38900 | 17400 | 21500 | |
| SVE-17 | 8/15/2012 | 1021 | -2.78 | 0.01 | NA | 82.4 | OVR | 8.1 | 9.4 | 373 | 25800 | 12800 | 13000 | |
| SVE-17 | 9/19/2012 | 1056 | -4.30 | NA | 22.56 | 72.5 | OVR | 7.6 | 10.4 | 533 | 22400 | 10600 | 11800 | |
| SVE-17 | 10/17/2012 | 1330 | -4.72 | 0.00 | 22.55 | 64.0 | OVR | 8.2 | 10.0 | 602 | 19100 | 8400 | 10700 | |
| SVE-17 | 11/20/2012 | 1057 | -3.95 | 0.04 | 22.56 | 40.5 | OVR | 7.4 | 11.0 | 555 | 12100 | 7100 | 5000 | |
| SVE-17 | 12/19/2012 | 1350 | -2.58 | NA | 22.51 | 35.0 | OVR | 7.8 | 10.7 | 690 | 14200 | 6300 | 7900 | |
| SVE-17 | 1/16/2013 | 1129 | -2.60 | NM | 22.53 | 27.5 | OVR | 7.4 | 10.8 | 660 | 13800 | 6700 | 7100 | |
| SVE-17 | 2/25/2013 | 1127 | -1.74 | NM | 22.52 | 20.0 | OVR | 7.1 | 11.4 | 550 | 6800 | 3050 | 3750 | Valve closed visually 50% at well head. |
| SVE-17 | 3/20/2013 | 1434 | -4.83 | NM | 22.56 | 17.1 | OVR | 5.7 | 13.6 | 545 | 6500 | 3700 | 2800 | Valve closed visually 50% at well head. |

SEE LAST PAGE OF TABLE FOR NOTES

**TABLE 9**
**SVE SYSTEM MONTHLY MONITORING - SVE SAMPLING DATA**

| Sample ID | Date | Initial Reading Time (24-Hour) | Vacuum/Pressure | Air Flow | Groundwater | Fixed Gases | | | | Soil Vapor Concentrations | | | | Comments |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | Initial Reading (Inches of $H_2O$) | Pitot Tube Pressure (Inches of $H_20$) | Depth to Water (feet) | CH4 (%) | LEL (%) | $CO_2$ (%) | $O_2$ (%) | PID (ppmv) | THC (ppmv) | CH4 (ppmv) | PHC (ppmv) | |
| SVE-18 | 2/6/2012 | 1420 | -2.77 | NA | 21.03 | OVR | OVR | 12.3 | 2.8 | 232 | 215000 | 105000 | 110000 | |
| SVE-18 | 2/7/2012 | 1108 | -2.69 | NA | NA | OVR | OVR | 11.8 | 4.5 | 209 | 79900 | 67200 | 12700 | |
| SVE-18 | 2/8/2012 | 1000 | -2.81 | NA | 20.99 | OVR | OVR | 11.3 | 4.8 | 226 | 100000 | 53610 | 46390 | |
| SVE-18 | 2/15/2012 | 1132 | -2.45 | NA | NA | OVR | OVR | 9.6 | 7.2 | 185 | 121000 | 83600 | 37400 | |
| SVE-18 | 2/22/2012 | 1559 | -2.32 | NA | NA | OVR | OVR | 9.3 | 6.9 | 154 | 180000 | 132000 | 48000 | |
| SVE-18 | 2/29/2012 | 1354 | -1.33 | NA | NA | OVR | OVR | 10.0 | 6.8 | 123 | 140000 | 109000 | 31000 | |
| SVE-18 | 3/21/2012 | 1013 | -1.31 | NA | NA | 2.1 | 43.0 | 9.4 | 5.2 | 237 | 4100 | 2560 | 1540 | |
| SVE-18 | 4/18/2012 | 1228 | -2.31 | 0.12 | 20.81 | OVR | OVR | 7.5 | 8.0 | 177 | 95400 | 69500 | 25900 | |
| SVE-18 | 5/16/2012 | 1358 | -2.51 | 0.03 | NE | OVR | OVR | 6.6 | 10.0 | 187 | 59200 | 52400 | 6800 | |
| SVE-18 | 6/20/2012 | 1054 | -2.54 | 0.01 | 20.86 | OVR | OVR | 6.5 | 10.4 | 203 | 68300 | 41200 | 27100 | |
| SVE-18 | 7/18/2012 | 930 | -2.79 | 0.00 | 20.81 | 69.2 | OVR | 6.2 | 11.2 | 222 | 36200 | 23200 | 13000 | |
| SVE-18 | 8/15/2012 | 1013 | -3.00 | -0.01 | NA | 58.3 | OVR | 6.5 | 12.5 | 388 | 18900 | 11600 | 7300 | |
| SVE-18 | 9/19/2012 | 1101 | -4.72 | NA | 20.82 | 33.4 | OVR | 5.5 | 13.1 | 561 | 12300 | 4100 | 8200 | |
| SVE-18 | 10/17/2012 | 1336 | -5.17 | 0.00 | 20.89 | 27.5 | OVR | 6.0 | 12.6 | 612 | 10400 | 3000 | 7400 | |
| SVE-18 | 11/20/2012 | 1101 | -4.33 | 0.01 | 20.62 | 12.5 | OVR | 5.3 | 13.9 | 576 | 3700 | 1100 | 2600 | |
| SVE-18 | 12/19/2012 | 1400 | -2.73 | NA | 20.74 | 10.8 | OVR | 6.4 | 12.4 | 636 | 4900 | 1000 | 3900 | |
| SVE-18 | 1/16/2013 | 1133 | -2.78 | NM | 20.74 | 7.9 | OVR | 6.5 | 12.1 | 600 | 5100 | 1800 | 3300 | |
| SVE-18 | 2/25/2013 | 1131 | -1.95 | NM | 20.72 | 2.9 | 59.0 | 6.1 | 12.8 | 305 | 2200 | 325 | 1875 | Valve closed visually 50% at well head. |
| SVE-18 | 3/20/2013 | 1441 | -5.41 | NM | 20.74 | 4.8 | 96.0 | 5.2 | 14.2 | 377 | 3100 | 1500 | 1600 | Valve closed visually 50% at well head. |
| SVE-19 | 2/6/2012 | 1428 | -0.76 | NA | 23.75 | 75.3 | OVR | 12.2 | 1.3 | 81.2 | 262000 | 169000 | 93000 | |
| SVE-19 | 2/7/2012 | 1113 | -2.93 | NA | NA | 84.6 | OVR | 12.7 | 0.6 | 86.8 | 116000 | 84200 | 31800 | |
| SVE-19 | 2/8/2012 | 1009 | -3.36 | NA | 23.85 | 64.7 | OVR | 11.7 | 2.9 | 100 | 120000 | 89300 | 30700 | |
| SVE-19 | 2/15/2012 | 1139 | -2.65 | NA | NA | 74.9 | OVR | 11.8 | 2.9 | 98.2 | 100000 | 84000 | 16000 | |
| SVE-19 | 2/22/2012 | 1609 | -2.51 | NA | NA | OVR | OVR | 11.2 | 3.4 | 100 | 190000 | 155000 | 35000 | |
| SVE-19 | 2/29/2012 | 1403 | -1.38 | NA | NA | 84.5 | OVR | 11.8 | 3.5 | 79.5 | 158000 | 110000 | 48000 | |
| SVE-19 | 3/21/2012 | 1018 | -1.36 | NA | NA | 0.1 | 3.0 | 8.4 | 6.3 | 25.5 | 1220 | 1000 | 220 | |
| SVE-19 | 4/18/2012 | 1237 | -2.50 | 1.91 | 23.76 | 47.2 | OVR | 8.2 | 6.2 | 95.0 | 91000 | 73200 | 17800 | |
| SVE-19 | 5/16/2012 | 1405 | -2.72 | 0.03 | NE | 47.1 | OVR | 7.5 | 8.8 | 82.0 | 28700 | 10100 | 18600 | |
| SVE-19 | 6/20/2012 | 1101 | -2.82 | NA | 23.58 | 35.8 | OVR | 6.5 | 10.8 | 71.4 | 56200 | 52000 | 4200 | |
| SVE-19 | 7/18/2012 | 939 | -3.05 | 0.01 | 23.73 | 41.1 | OVR | 7.4 | 10.1 | 67.3 | 55400 | 41100 | 14300 | |
| SVE-19 | 8/15/2012 | 1005 | -3.33 | 0.00 | NA | 34.2 | OVR | 7.2 | 11.2 | 150 | 35300 | 27400 | 7900 | |
| SVE-19 | 9/19/2012 | 1107 | -5.33 | NA | 23.73 | 16.1 | OVR | 5.9 | 12.5 | 262 | 13400 | 9500 | 3900 | |
| SVE-19 | 10/17/2012 | 1342 | -5.83 | 0.00 | 23.75 | 14.4 | OVR | 6.4 | 12.3 | 280 | 13900 | 6300 | 7600 | |
| SVE-19 | 11/20/2012 | 1106 | -4.79 | 0.00 | 23.76 | 2.1 | 42.0 | 4.0 | 14.7 | 233 | 2800 | 1300 | 1500 | |
| SVE-19 | 12/19/2012 | 1405 | -2.97 | NA | 23.74 | 4.0 | 80.0 | 5.4 | 12.9 | 278 | 6400 | 3800 | 2600 | |
| SVE-19 | 1/16/2013 | 1139 | -2.95 | NM | 23.77 | 4.3 | 86.0 | 5.2 | 12.8 | 265 | 10300 | 7000 | 3300 | |
| SVE-19 | 2/25/2013 | 1135 | -3.45 | NM | 23.71 | 4.6 | 93.0 | 5.0 | 13.1 | 193 | 8500 | 5100 | 3400 | |
| SVE-19 | 3/20/2013 | 1448 | -7.20 | NM | 23.70 | 3.6 | 73.0 | 4.4 | 14.4 | 150 | 7400 | 5800 | 1600 | |
| SVE-20 | 2/23/2012 | 953 | -3.17 | NA | NA | OVR | OVR | 12.7 | 1.0 | 77.5 | 1000000 | 1000000 | 0.0 | |
| SVE-20 | 2/29/2012 | 1419 | -3.74 | NA | NA | OVR | OVR | 12.7 | 1.1 | 70.3 | 1000000 | 920000 | 80000 | |
| SVE-20 | 3/1/2012 | 1500 | -1.08 | NA | NA | OVR | OVR | 12.6 | 1.1 | 102 | 921000 | 841000 | 80000 | |
| SVE-20 | 3/2/2012 | 1054 | -1.51 | NA | NA | OVR | OVR | 12.5 | 1.2 | 84.7 | 1000000 | 955000 | 45000 | Benzene Reading: 38.2 ppm |
| SVE-20 | 3/6/2012 | 1138 | -0.20 | NA | NA | OVR | OVR | 7.2 | 7.4 | 69.0 | 858000 | 486000 | 372000 | Benzene Reading: 30.0 ppm |
| SVE-20 | 3/7/2012 | 855 | -0.11 | NA | NA | OVR | OVR | 9.7 | 4.3 | 65.7 | 742000 | 261000 | 481000 | Benzene Reading: 24.9 ppm |
| SVE-20 | 3/21/2012 | 1027 | -2.21 | NA | NA | OVR | OVR | 11.6 | 0.4 | 98.5 | 770000 | 373000 | 397000 | |
| SVE-20 | 4/18/2012 | 1256 | -3.19 | 0.52 | 37.92 | OVR | OVR | 10.4 | 2.7 | 92.8 | 602000 | 376000 | 226000 | |
| SVE-20 | 5/16/2012 | 1413 | -3.42 | 0.03 | NE | OVR | OVR | 10.1 | 4.4 | 106 | 390000 | 270000 | 120000 | |
| SVE-20 | 6/20/2012 | 1107 | -3.57 | 0.01 | 37.95 | OVR | OVR | 10.2 | 4.6 | 105 | 210000 | 198000 | 12000 | |
| SVE-20 | 7/18/2012 | 1002 | -3.95 | 0.02 | 37.87 | OVR | OVR | 9.8 | 5.8 | 60.5 | 229000 | 146000 | 83000 | |
| SVE-20 | 8/15/2012 | 955 | -4.47 | -0.99 | NA | OVR | OVR | 11.0 | 4.6 | 115 | 125000 | 102000 | 23000 | |
| SVE-20 | 9/19/2012 | 1113 | -7.67 | NA | 37.90 | OVR | OVR | 10.5 | 6.6 | 136 | 200000 | 160000 | 40000 | |
| SVE-20 | 10/17/2012 | 1348 | -7.12 | 0.00 | 37.88 | OVR | OVR | 10.8 | 7.4 | 141 | 248000 | 212000 | 36000 | |
| SVE-20 | 11/20/2012 | 1112 | -13.54 | -0.21 | 37.85 | OVR | OVR | 9.1 | 8.6 | 175 | 104000 | 94000 | 10000 | Vacuum would not stabilize during sampling. Highest value observed is listed. |
| SVE-20 | 12/19/2012 | 1420 | -3.02 | NA | 37.89 | OVR | OVR | 11.3 | 4.5 | 195 | 230000 | 145000 | 85000 | |
| SVE-20 | 1/16/2013 | 1143 | -2.95 | NM | 37.92 | OVR | OVR | 11.3 | 5.2 | 190 | 218000 | 140000 | 78000 | |
| SVE-20 | 2/25/2013 | 1139 | -3.20 | NM | 37.90 | OVR | OVR | 11.6 | 5.0 | 159 | 202000 | 127000 | 75000 | |
| SVE-20 | 3/20/2013 | 1454 | -5.85 | NM | 37.82 | OVR | OVR | 11.4 | 5.5 | 143 | 340000 | 215000 | 125000 | |

SEE LAST PAGE OF TABLE FOR NOTES

**TABLE 9**
**SVE SYSTEM MONTHLY MONITORING - SVE SAMPLING DATA**

| Sample ID | Date | Initial Reading Time (24-Hour) | Vacuum/Pressure | Air Flow | Groundwater | Fixed Gases | | | | Soil Vapor Concentrations | | | | Comments |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | Initial Reading (Inches of $H_2O$) | Pitot Tube Pressure (Inches of $H_2O$) | Depth to Water (feet) | CH4 (%) | LEL (%) | $CO_2$ (%) | $O_2$ (%) | PID (ppmv) | THC (ppmv) | CH4 (ppmv) | PHC (ppmv) | |
| SVE-21 | 12/3/2012 | 1525 | -1.74 | NM | NM | 0.0 | 0.0 | 3.1 | 18.0 | 1.0 | 2.5 | 0.0 | 2.5 | |
| SVE-21 | 12/4/2012 | 1335 | -2.67 | NM | 34.51 | 0.0 | 0.0 | 4.0 | 17.0 | 0.5 | 1.9 | 0.0 | 1.9 | |
| SVE-21 | 12/13/2012 | 1521 | -1.47 | NM | 34.43 | 0.0 | 0.0 | 3.9 | 17.3 | 0.2 | 0.6 | 0.0 | 0.6 | |
| SVE-21 | 12/19/2012 | 1505 | -1.62 | NM | NM | 0.0 | 0.0 | 4.5 | 16.7 | 0.3 | 1.4 | 0.0 | 1.4 | |
| SVE-21 | 1/16/2013 | 1559 | -2.10 | NM | 34.43 | 0.0 | 0.0 | 2.9 | 18.5 | 0.1 | 1.1 | 0.0 | 1.1 | |
| SVE-21 | 2/26/2013 | 1210 | -1.91 | NM | 34.43 | 0.0 | 0.0 | 2.5 | 18.7 | 0.1 | 0.5 | 0.0 | 0.5 | |
| SVE-21 | 3/21/2013 | 1104 | -2.64 | NM | 34.48 | 0.0 | 0.0 | 2.2 | 19.5 | 0.1 | 0.8 | 0.0 | 0.8 | |
| SVE-22 | 12/5/2012 | 1625 | -1.57 | NM | 34.35 | 0.0 | 0.0 | 4.7 | 16.3 | 2.0 | 11.7 | 5.1 | 6.6 | |
| SVE-22 | 12/6/2012 | 1529 | -1.40 | NM | 34.31 | 0.0 | 0.0 | 4.4 | 16.3 | 1.3 | 12.3 | 8.2 | 4.1 | |
| SVE-22 | 12/13/2012 | 1350 | -1.13 | NM | 34.35 | 0.0 | 0.0 | 3.5 | 17.6 | 0.8 | 7.7 | 6.2 | 1.5 | |
| SVE-22 | 12/19/2012 | 1403 | -1.18 | NM | NM | 0.0 | 0.0 | 2.8 | 18.3 | 0.5 | 8.6 | 8.6 | 0.0 | |
| SVE-22 | 1/16/2013 | 1419 | -1.26 | NM | 34.37 | 0.0 | 0.0 | 1.7 | 19.5 | 0.4 | 4.3 | 0.0 | 4.3 | |
| SVE-22 | 2/26/2013 | 1148 | -1.40 | NM | 34.38 | 0.0 | 0.0 | 1.3 | 19.8 | 0.3 | 9.2 | 6.5 | 2.7 | |
| SVE-22 | 3/21/2013 | 1029 | -1.75 | NM | 34.39 | 0.0 | 0.0 | 1.2 | 20.0 | 0.3 | 5.4 | 4.8 | 0.6 | |
| SVE-23 | 12/6/2012 | 1541 | -1.29 | NM | 24.67 | 0.0 | 0.0 | 7.2 | 12.0 | 3.5 | 4.3 | 0.0 | 4.3 | |
| SVE-23 | 12/7/2012 | 1650 | -1.28 | NM | 24.68 | NM | NM | NM | NM | NM | NM | NM | NM | Sample depleted when screening conducted on 12/8/12. Could not sample. |
| SVE-23 | 12/10/2012 | 1336 | -1.29 | NM | 24.71 | 0.0 | 0.0 | 4.3 | 16.0 | 2.8 | 4.6 | 0.0 | 4.6 | |
| SVE-23 | 12/13/2012 | 1432 | -1.12 | NM | 24.71 | 0.0 | 0.0 | 4.5 | 16.0 | 0.7 | 0.2 | 0.0 | 0.2 | |
| SVE-23 | 12/19/2012 | 1350 | -1.17 | NM | NM | 0.0 | 0.0 | 3.5 | 17.0 | 0.4 | 0.7 | 0.0 | 0.7 | |
| SVE-23 | 1/16/2013 | 1432 | -1.25 | NM | 24.74 | 0.0 | 0.0 | 2.3 | 18.3 | 0.4 | 1.4 | 0.0 | 1.4 | |
| SVE-23 | 2/26/2013 | 1203 | -1.38 | NM | 24.69 | 0.1 | 3.0 | 2.7 | 16.9 | 6.5 | 745 | 720 | 25.0 | |
| SVE-23 | 3/21/2013 | 1057 | -1.74 | NM | 24.71 | 0.1 | 2.0 | 2.0 | 18.3 | 15.7 | 800 | 670 | 130 | |
| SVE-24 | 12/10/2012 | 1322 | -0.47 | NM | 25.25 | 18.0 | OVR | 12.4 | 3.4 | 1120 | 36400 | 23000 | 13400 | |
| SVE-24 | 12/11/2012 | 1330 | -0.25 | NM | 25.27 | 21.7 | OVR | 14.7 | 0.5 | 1490 | 31400 | 17700 | 13700 | |
| SVE-24 | 12/12/2012 | 1637 | -0.30 | NM | NM | 17.5 | OVR | 14.0 | 1.2 | 1420 | 28100 | 16500 | 11600 | Vacuum reading surging. Highest observed value listed. |
| SVE-24 | 12/13/2012 | 1031 | -0.33 | NM | 25.23 | 18.3 | OVR | 14.6 | 1.3 | 1180 | 31900 | 19100 | 12800 | Vacuum reading surging. Highest observed value listed. |
| SVE-24 | 12/19/2012 | 1427 | -0.30 | NM | NM | 14.7 | OVR | 11.5 | 3.9 | 1620 | 27300 | 17000 | 10300 | |
| SVE-24 | 1/16/2013 | 1359 | -0.42 | NM | 25.22 | 10.2 | OVR | 8.9 | 6.9 | 1590 | 23200 | 11800 | 11400 | |
| SVE-24 | 2/26/2013 | 1125 | -0.45 | NM | 25.20 | 20.8 | OVR | 9.0 | 7.0 | 1533 | 30500 | 18600 | 11900 | |
| SVE-24 | 3/21/2013 | 1007 | -1.06 | NM | 25.22 | 15.4 | OVR | 8.5 | 8.1 | 1840 | 32400 | 20700 | 11700 | |
| SVE-25 | 2/1/2012 | 1545 | NA | NA | NA | OVR | OVR | 8.0 | 6.4 | 182 | 165000 | 83100 | 81900 | |
| SVE-25 | 2/2/2012 | 845 | NA | NA | NA | OVR | OVR | 7.3 | 7.3 | 195 | 180000 | 61000 | 119000 | |
| SVE-25 | 2/7/2012 | 1408 | -2.88 | NA | NA | OVR | OVR | 8.4 | 6.6 | 217 | 125000 | 72000 | 53000 | |
| SVE-25 | 2/15/2012 | 1403 | -2.50 | NA | NA | 34.9 | OVR | 7.2 | 9.8 | 425 | 15950 | 6800 | 9150 | |
| SVE-25 | 2/17/2012 | 1025 | -2.66 | NA | NA | 14.3 | OVR | 6.2 | 12.5 | 445 | 6250 | 2600 | 3650 | |
| SVE-25 | 2/22/2012 | 1620 | -2.43 | NA | NA | 11.6 | OVR | 5.7 | 12.8 | 424 | 8180 | 2990 | 5190 | |
| SVE-25 | 2/29/2012 | 821 | -1.96 | NA | NA | 16.8 | OVR | 6.8 | 11.4 | 431 | 8470 | 2770 | 5700 | |
| SVE-25 | 3/21/2012 | 1412 | -1.15 | NA | NA | 9.7 | OVR | 6.0 | 12.0 | 342 | 3960 | 1810 | 2150 | |
| SVE-25 | 4/18/2012 | 1545 | -2.26 | NA | NA | 16.2 | OVR | 5.7 | 11.8 | 348 | 8200 | 2950 | 5250 | |
| SVE-25 | 5/16/2012 | 1518 | -3.09 | NA | NA | 5.7 | OVR | 4.8 | 14.6 | 305 | 4750 | 2250 | 2500 | |
| SVE-25 | 6/20/2012 | 1418 | -0.69 | 0.00 | NE | 0.0 | 0.0 | 0.8 | 20.0 | 2.0 | 7.0 | 0.0 | 7.0 | Vacuum would not stabilize during sampling. Highest value observed is listed. |
| SVE-25 | 7/18/2012 | 1109 | -2.64 | 0.01 | NE | 1.8 | 38.0 | 3.4 | 15.9 | 183 | 2490 | 690 | 1800 | |
| SVE-25 | 8/15/2012 | 1432 | -2.79 | NA | NA | 1.7 | 35.0 | 3.6 | 16.0 | 190 | 1930 | 510 | 1420 | |
| SVE-25 | 9/19/2012 | 810 | -4.58 | NA | NE | 3.7 | 75.0 | 4.0 | 15.5 | 331 | 4280 | 1110 | 3170 | |
| SVE-25 | 10/17/2012 | 1438 | -0.47 | NA | NE | 0.0 | 0.0 | 1.3 | 19.2 | 2.4 | 10.7 | 3.5 | 7.2 | Water present in SVE vault. |
| SVE-25 | 11/20/2012 | 1208 | -1.28 | NA | NE | 0.0 | 0.0 | 0.3 | 20.6 | 3.0 | 8.4 | 2.8 | 5.7 | Vacuum would not stabilize during sampling. Highest value observed is listed. |
| SVE-25 | 12/19/2012 | NM | NM | NM | NM | NM | NM | NM | NM | NM | NM | NM | NM | Vehicle parked on well. Could not access. |
| SVE-25 | 1/16/2013 | 1344 | -1.27 | NM | 22.98 | 0.0 | 0.0 | 0.1 | 20.7 | 6.5 | 60.4 | 10.9 | 49.5 | |
| SVE-25 | 2/25/2013 | 1215 | -2.73 | NM | NE | 1.3 | 26.0 | 3.8 | 16.5 | 140 | 2200 | 510 | 1690 | |
| SVE-25 | 3/21/2013 | 1114 | -6.56 | NM | 23.12 | 2.5 | 50.0 | 4.6 | 15.5 | 266 | 1600 | 560 | 1040 | Calibration checked and verified. |
| SVE-26 | 12/5/2012 | 1615 | -1.77 | NM | 30.57 | 0.2 | 5.0 | 12.3 | 4.8 | 266 | 1200 | 670 | 530 | Vacuum reading surging. Highest observed value listed. |
| SVE-26 | 12/6/2012 | 1516 | -0.40 | NM | 30.59 | 0.5 | 11.0 | 10.6 | 6.5 | 526 | 2350 | 1200 | 1150 | Vacuum reading surging. Highest observed value listed. |
| SVE-26 | 12/13/2012 | 1101 | -1.44 | NM | 30.58 | 1.4 | 28.0 | 10.1 | 8.0 | 400 | 4550 | 2700 | 1850 | |
| SVE-26 | 12/19/2012 | 1420 | -1.48 | NM | NM | 1.2 | 24.0 | 7.9 | 10.5 | 385 | 3800 | 3300 | 500 | |
| SVE-26 | 1/16/2013 | 1410 | -1.69 | NM | 30.57 | 0.6 | 12.0 | 6.0 | 12.5 | 395 | 2500 | 1300 | 1200 | |
| SVE-26 | 2/26/2013 | 1148 | -1.24 | NM | 30.48 | 0.4 | 9.0 | 6.1 | 11.7 | 322 | 1730 | 1000 | 730 | |
| SVE-26 | 3/21/2013 | 1026 | -2.22 | NM | 30.18 | 0.4 | 8.0 | 5.0 | 13.6 | 290 | 1100 | 580 | 520 | |

SEE LAST PAGE OF TABLE FOR NOTES

**TABLE 9**
**SVE SYSTEM MONTHLY MONITORING - SVE SAMPLING DATA**

| Sample ID | Date | Initial Reading Time (24-Hour) | Vacuum/Pressure | Air Flow | Groundwater | Fixed Gases | | | | Soil Vapor Concentrations | | | | Comments |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | Initial Reading (Inches of $H_2O$) | Pitot Tube Pressure (Inches of $H_2O$) | Depth to Water (feet) | CH4 (%) | LEL (%) | $CO_2$ (%) | $O_2$ (%) | PID (ppmv) | THC (ppmv) | CH4 (ppmv) | PHC (ppmv) | |
| SVE-27 | 12/3/2012 | 1410 | -1.80 | NM | NM | 3.0 | 60.0 | 11.0 | 4.0 | 1940 | 17400 | 7800 | 9600 | |
| SVE-27 | 12/4/2012 | 1315 | -3.11 | NM | 29.64 | 3.7 | 74.0 | 11.5 | 1.5 | 2295 | 23400 | 10100 | 13300 | |
| SVE-27 | 12/13/2012 | 1309 | -2.10 | NM | 30.05 | 4.7 | 95.0 | 11.4 | 3.3 | 1640 | 28300 | 17300 | 11000 | Vacuum reading surging. Highest observed value listed. |
| SVE-27 | 12/19/2012 | 1440 | -2.23 | NM | NM | 5.5 | OVR | 10.9 | 3.7 | 1860 | 33600 | 25200 | 8400 | |
| SVE-27 | 1/16/2013 | 1500 | -2.25 | NM | 29.65 | 6.9 | OVR | 9.5 | 6.8 | 1066 | 42800 | 29400 | 13400 | |
| SVE-27 | 2/26/2013 | 1139 | -2.40 | NM | 30.16 | 10.6 | OVR | 9.3 | 7.6 | 1050 | 44200 | 33300 | 10900 | |
| SVE-27 | 3/21/2013 | 1036 | -0.92 | NM | 29.32 | 6.9 | OVR | 8.9 | 7.7 | 1170 | 30000 | 23100 | 6900 | |
| SVE-28 | 2/20/2012 | 935 | -2.45 | NA | NA | 55.9 | OVR | 0.4 | 20.0 | 99.0 | 80000 | 28500 | 51500 | |
| SVE-28 | 2/21/2012 | 1036 | -2.73 | NA | NA | 0.9 | 18.0 | 0.1 | 20.9 | 150 | 1462 | 410 | 1052 | |
| SVE-28 | 2/22/2012 | 957 | -1.80 | NA | NA | 0.0 | 0.0 | 0.1 | 20.8 | 18.0 | 98.0 | 31.1 | 66.9 | |
| SVE-28 | 2/29/2012 | 843 | -1.73 | NA | NA | 0.2 | 5.0 | 0.1 | 20.9 | 19.7 | 533 | 133 | 400 | |
| SVE-28 | 3/21/2012 | 829 | -1.47 | NA | NA | 0.1 | 3.0 | 0.1 | 20.9 | 23.6 | 231 | 61.0 | 170 | |
| SVE-28 | 4/18/2012 | 919 | -2.27 | 0.60 | 42.62 | 4.1 | 83.0 | 0.0 | 20.9 | 47.5 | 7350 | 4920 | 2430 | |
| SVE-28 | 5/16/2012 | 1100 | -2.50 | 1.80 | 42.80 | 0.1 | 2.0 | 0.0 | 20.9 | 4.0 | 63.9 | 31.5 | 32.4 | |
| SVE-28 | 6/20/2012 | 705 | -2.55 | 0.01 | 42.81 | 10.4 | OVR | 0.1 | 20.6 | 51.7 | 11000 | 6550 | 4450 | |
| SVE-28 | 7/18/2012 | 610 | -2.68 | 0.00 | 42.83 | 1.7 | 34.0 | 0.0 | 20.9 | 40.4 | 4720 | 3100 | 1620 | |
| SVE-28 | 8/15/2012 | 1334 | -2.39 | 0.00 | NA | 1.8 | 38.0 | 0.4 | 20.2 | 153 | 2450 | 1470 | 980 | |
| SVE-28 | 9/19/2012 | 912 | -3.92 | NA | 44.51 | 0.8 | 17.0 | 7.3 | 8.7 | 69.6 | 2560 | 1130 | 1430 | |
| SVE-28 | 10/17/2012 | 1020 | -4.11 | 0.00 | 44.42 | 0.5 | 10.0 | 5.8 | 10.4 | 32.7 | 850 | 590 | 260 | |
| SVE-28 | 11/20/2012 | 905 | -3.73 | 0.19 | 44.66 | 0.3 | 7.0 | 5.5 | 11.3 | 39.0 | 905 | 450 | 455 | |
| SVE-28 | 12/19/2012 | 945 | -2.59 | NA | 45.32 | 1.7 | 34.0 | 7.2 | 10.2 | 81.1 | 2600 | 1300 | 1300 | |
| SVE-28 | 1/16/2013 | 958 | -2.48 | NM | 45.35 | 0.4 | 8.0 | 7.3 | 10.0 | 34.8 | 1450 | 970 | 480 | |
| SVE-28 | 2/25/2013 | 1017 | -2.60 | NM | 45.90 | 1.0 | 20.0 | 8.4 | 9.2 | 28.1 | 3000 | 1550 | 1450 | |
| SVE-28 | 3/20/2013 | 1224 | -5.25 | NM | 46.00 | 5.9 | OVR | 8.6 | 9.4 | 85.9 | 8300 | 5900 | 2400 | |
| SVE-29 | 2/20/2012 | 945 | -2.50 | NA | NA | OVR | OVR | 9.4 | 1.6 | 135 | 643000 | 225000 | 418000 | |
| SVE-29 | 2/21/2012 | 1047 | -2.76 | NA | NA | OVR | OVR | 9.1 | 1.3 | 148 | 564000 | 347000 | 217000 | |
| SVE-29 | 2/22/2012 | 1023 | -1.85 | NA | NA | OVR | OVR | 8.6 | 2.6 | 140 | 450000 | 149000 | 301000 | |
| SVE-29 | 2/29/2012 | 902 | -1.70 | NA | NA | OVR | OVR | 8.4 | 2.1 | 148 | 460000 | 100000 | 360000 | |
| SVE-29 | 3/21/2012 | 838 | -1.59 | NA | NA | OVR | OVR | 7.9 | 2.8 | 133 | 396000 | 247000 | 149000 | |
| SVE-29 | 4/18/2012 | 942 | -2.31 | 0.08 | 33.53 | OVR | OVR | 6.9 | 4.6 | 168 | 221000 | 103000 | 118000 | |
| SVE-29 | 5/16/2012 | 1122 | -2.47 | 0.28 | NA | OVR | OVR | 8.6 | 1.9 | 138 | 283000 | 129000 | 154000 | |
| SVE-29 | 6/20/2012 | 727 | -2.61 | 0.01 | 33.59 | OVR | OVR | 7.5 | 5.5 | 140 | 102000 | 100000 | 2000 | |
| SVE-29 | 7/18/2012 | 632 | -2.73 | 0.04 | 33.51 | OVR | OVR | 6.6 | 7.2 | 90.0 | 175000 | 88200 | 86800 | |
| SVE-29 | 8/15/2012 | 1252 | -2.45 | 0.00 | NA | OVR | OVR | 6.9 | 8.2 | 108 | 91800 | 57500 | 34300 | |
| SVE-29 | 9/19/2012 | 923 | -3.94 | NA | 33.54 | OVR | OVR | 7.3 | 8.3 | 245 | 74460 | 34300 | 40160 | |
| SVE-29 | 10/17/2012 | 1032 | -4.10 | 0.00 | 33.54 | OVR | OVR | 8.4 | 6.5 | 203 | 122000 | 61500 | 60500 | |
| SVE-29 | 11/20/2012 | 917 | -3.75 | 0.07 | 33.59 | OVR | OVR | 11.3 | 2.5 | 215 | 108000 | 64600 | 43400 | |
| SVE-29 | 12/19/2012 | 955 | -2.64 | NA | 33.56 | OVR | OVR | 12.5 | 1.3 | 255 | 132000 | 71100 | 60900 | |
| SVE-29 | 1/16/2013 | 1008 | -2.51 | NM | 33.59 | OVR | OVR | 12.8 | 1.6 | 230 | 170000 | 78500 | 91500 | |
| SVE-29 | 2/25/2013 | 1027 | -2.60 | NM | 33.55 | OVR | OVR | 13.2 | 1.8 | 191 | 135000 | 62100 | 72900 | |
| SVE-29 | 3/20/2013 | 1241 | -5.13 | NM | 33.57 | OVR | OVR | 12.1 | 3.4 | 208 | 160000 | 77000 | 83000 | |
| SVE-30 | 2/20/2012 | 955 | -2.38 | NA | NA | OVR | OVR | 6.4 | 1.4 | 116 | 1000000 | 384000 | 616000 | |
| SVE-30 | 2/21/2012 | 1057 | -2.72 | NA | NA | OVR | OVR | 6.0 | 2.9 | 129 | 1000000 | 455000 | 545000 | |
| SVE-30 | 2/22/2012 | 1046 | -1.81 | NA | NA | OVR | OVR | 6.6 | 1.4 | 116 | 1000000 | 425000 | 575000 | |
| SVE-30 | 2/29/2012 | 918 | -1.03 | NA | NA | 12.4 | OVR | 0.1 | 20.9 | 634 | 3630 | 434 | 3196 | |
| SVE-30 | 3/21/2012 | 849 | -1.43 | NA | NA | OVR | OVR | 4.7 | 6.3 | 89.3 | 1000000 | 590000 | 410000 | |
| SVE-30 | 4/18/2012 | 1001 | -2.23 | 1.52 | 37.78 | OVR | OVR | 6.2 | 1.7 | 102 | 1000000 | 425000 | 575000 | |
| SVE-30 | 5/16/2012 | 1141 | -2.48 | 2.09 | NA | OVR | OVR | 6.6 | 1.6 | 110 | 1000000 | 419000 | 581000 | |
| SVE-30 | 6/20/2012 | 743 | -2.58 | 0.00 | 0.00 | OVR | OVR | 7.1 | 0.5 | 120 | 353000 | 201000 | 152000 | |
| SVE-30 | 7/18/2012 | 649 | -2.71 | 0.05 | 37.81 | OVR | OVR | 6.9 | 1.2 | 59.2 | 1000000 | 300000 | 700000 | |
| SVE-30 | 8/15/2012 | 1221 | -2.52 | 0.00 | NA | OVR | OVR | 7.5 | 1.1 | 120 | 927000 | 180000 | 747000 | |
| SVE-30 | 9/19/2012 | 934 | -3.92 | NA | 0.00 | OVR | OVR | 7.8 | 1.8 | 148 | 628000 | 211000 | 417000 | |
| SVE-30 | 10/17/2012 | 1042 | -4.01 | 0.00 | 37.80 | OVR | OVR | 8.4 | 1.9 | 156 | 619000 | 174000 | 445000 | |
| SVE-30 | 11/20/2012 | 929 | -3.68 | 0.00 | 37.90 | OVR | OVR | 9.4 | 1.0 | 184 | 709000 | 282000 | 427000 | |
| SVE-30 | 12/19/2012 | 1025 | -2.73 | NA | 37.79 | OVR | OVR | 9.5 | 1.0 | 199 | 690000 | 224000 | 466000 | |
| SVE-30 | 1/16/2013 | 1019 | -2.53 | NM | 37.82 | OVR | OVR | 8.9 | 2.4 | 175 | 1000000 | 250000 | 750000 | |
| SVE-30 | 2/25/2013 | 1035 | -2.58 | NM | 37.77 | OVR | OVR | 8.5 | 3.3 | 146 | 810000 | 175000 | 635000 | |
| SVE-30 | 3/20/2013 | 1253 | -5.12 | NM | 37.80 | OVR | OVR | 9.9 | 1.0 | 135 | 1000000 | 275000 | 725000 | |

SEE LAST PAGE OF TABLE FOR NOTES

**TABLE 9**
**SVE SYSTEM MONTHLY MONITORING - SVE SAMPLING DATA**

| Sample ID | Date | Initial Reading Time (24-Hour) | Vacuum/Pressure | Air Flow | Groundwater | Fixed Gases | | | | Soil Vapor Concentrations | | | | Comments |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | Initial Reading (Inches of $H_2O$) | Pitot Tube Pressure (Inches of $H_20$) | Depth to Water (feet) | CH4 (%) | LEL (%) | $CO_2$ (%) | $O_2$ (%) | PID (ppmv) | THC (ppmv) | CH4 (ppmv) | PHC (ppmv) | |
| SVE-31 | 2/10/2012 | 1405 | -2.27 | NA | NA | OVR | OVR | 5.9 | 1.5 | 75.2 | 1000000 | 1000000 | 0.0 | |
| SVE-31 | 2/13/2012 | 857 | -2.58 | NA | NA | OVR | OVR | 5.8 | 1.0 | 92.4 | 1000000 | 810000 | 190000 | |
| SVE-31 | 2/15/2012 | 910 | -2.32 | NA | NA | OVR | OVR | 6.3 | 1.4 | 100 | 1000000 | 612000 | 388000 | |
| SVE-31 | 2/22/2012 | 1114 | -1.84 | NA | NA | OVR | OVR | 6.5 | 2.7 | 142 | 1000000 | 688000 | 312000 | |
| SVE-31 | 2/29/2012 | 934 | -1.33 | NA | NA | OVR | OVR | 4.5 | 9.3 | 187 | 519000 | 120000 | 399000 | |
| SVE-31 | 3/21/2012 | 900 | -1.43 | NA | NA | OVR | OVR | 7.8 | 0.8 | 160 | 1000000 | 1000000 | 0.0 | |
| SVE-31 | 4/18/2012 | 1018 | -2.18 | 0.12 | 37.72 | OVR | OVR | 8.3 | 0.8 | 215 | 790000 | 220000 | 570000 | |
| SVE-31 | 5/16/2012 | 1158 | -2.45 | 0.31 | 0.00 | OVR | OVR | 8.8 | 2.6 | 265 | 834000 | 185000 | 649000 | |
| SVE-31 | 6/20/2012 | 757 | -2.58 | 0.00 | 37.77 | OVR | OVR | 7.6 | 5.5 | 268 | 209000 | 61300 | 147700 | |
| SVE-31 | 7/18/2012 | 704 | -2.71 | 0.02 | 37.68 | OVR | OVR | 8.1 | 5.0 | 110 | 275000 | 125000 | 150000 | |
| SVE-31 | 8/15/2012 | 1207 | -2.57 | 0.00 | NA | OVR | OVR | 9.2 | 4.1 | 206 | 273000 | 86000 | 187000 | |
| SVE-31 | 9/19/2012 | 943 | -3.92 | NA | 37.65 | OVR | OVR | 8.2 | 4.7 | 236 | 322000 | 116000 | 206000 | |
| SVE-31 | 10/17/2012 | 1053 | -4.03 | 0.00 | 37.64 | OVR | OVR | 6.5 | 9.5 | 272 | 221000 | 82400 | 138600 | |
| SVE-31 | 11/20/2012 | 939 | -3.67 | 0.01 | 37.35 | OVR | OVR | 9.3 | 5.4 | 333 | 159000 | 46000 | 113000 | |
| SVE-31 | 12/19/2012 | 1045 | -2.70 | NA | 37.25 | OVR | OVR | 11.2 | 2.7 | 472 | 129000 | 44300 | 84700 | |
| SVE-31 | 1/16/2013 | 1027 | -2.58 | NM | 36.97 | OVR | OVR | 10.7 | 1.7 | 341 | 490000 | 50900 | 439100 | |
| SVE-31 | 2/25/2013 | 1043 | -2.64 | NM | 36.89 | OVR | OVR | 11.1 | 2.4 | 462 | 141000 | 31800 | 109200 | |
| SVE-31 | 3/20/2013 | 1307 | -5.16 | NM | 36.75 | OVR | OVR | 10.6 | 3.6 | 475 | 142000 | 38800 | 103200 | |
| SVE-32 | 2/10/2012 | 1356 | -2.29 | NA | 37.81 | OVR | OVR | 6.3 | 1.0 | 102 | 1000000 | 845000 | 155000 | |
| SVE-32 | 2/13/2012 | 905 | -2.59 | NA | NA | OVR | OVR | 6.1 | 1.5 | 105 | 1000000 | 882000 | 118000 | |
| SVE-32 | 2/15/2012 | 945 | -2.51 | NA | NA | OVR | OVR | 6.2 | 1.8 | 103 | 1000000 | 855000 | 145000 | |
| SVE-32 | 2/22/2012 | 1134 | -1.80 | NA | NA | OVR | OVR | 6.7 | 1.4 | 111 | 1000000 | 797000 | 203000 | |
| SVE-32 | 2/29/2012 | 952 | -1.37 | NA | NA | OVR | OVR | 6.9 | 1.7 | 99.0 | 1000000 | 549000 | 451000 | |
| SVE-32 | 3/21/2012 | 910 | -1.44 | NA | NA | OVR | OVR | 7.3 | 0.9 | 104 | 1000000 | 1000000 | 0.0 | |
| SVE-32 | 4/18/2012 | 1039 | -2.10 | 0.44 | NE | OVR | OVR | 7.2 | 1.2 | 115 | 1000000 | 668000 | 332000 | |
| SVE-32 | 5/16/2012 | 1214 | -2.34 | 0.00 | NE | OVR | OVR | 8.0 | 1.6 | 135 | 1000000 | 525000 | 475000 | |
| SVE-32 | 6/20/2012 | 812 | -2.63 | 0.00 | 37.82 | OVR | OVR | 9.0 | 0.8 | 151 | 973000 | 167000 | 806000 | |
| SVE-32 | 7/18/2012 | 723 | -2.69 | 0.01 | 37.77 | OVR | OVR | 8.6 | 1.7 | 65.6 | 980000 | 240000 | 740000 | |
| SVE-32 | 8/15/2012 | 1151 | -2.61 | 0.08 | NA | OVR | OVR | 9.5 | 1.5 | 141 | 447000 | 171000 | 276000 | |
| SVE-32 | 9/19/2012 | 953 | -3.95 | NA | 37.80 | OVR | OVR | 8.8 | 3.7 | 163 | 748000 | 224000 | 524000 | |
| SVE-32 | 10/17/2012 | 1157 | -4.17 | 0.00 | 37.74 | OVR | OVR | 9.1 | 3.8 | 159 | 911000 | 262000 | 649000 | |
| SVE-32 | 11/20/2012 | 949 | -3.69 | 0.01 | 37.76 | OVR | OVR | 8.9 | 4.6 | 198 | 440000 | 204000 | 236000 | |
| SVE-32 | 12/19/2012 | 1059 | -2.53 | NA | 37.74 | OVR | OVR | 9.6 | 4.1 | 250 | 495000 | 118000 | 377000 | |
| SVE-32 | 1/16/2013 | 1037 | -2.52 | NM | 37.84 | OVR | OVR | 9.4 | 3.9 | 217 | 715000 | 190000 | 525000 | |
| SVE-32 | 2/25/2013 | 1049 | -2.63 | NM | 37.81 | OVR | OVR | 10.1 | 3.3 | 177 | 365000 | 164000 | 201000 | |
| SVE-32 | 3/20/2013 | 1322 | -5.17 | NM | 37.78 | OVR | OVR | 9.5 | 4.9 | 184 | 790000 | 215000 | 575000 | |
| SVE-33 | 2/10/2012 | 1351 | -2.30 | NA | 37.73 | OVR | OVR | 8.6 | 1.5 | 204 | 1000000 | 118000 | 882000 | |
| SVE-33 | 2/13/2012 | 917 | -2.59 | NA | NA | OVR | OVR | 8.5 | 1.0 | 212 | 1000000 | 146000 | 854000 | |
| SVE-33 | 2/15/2012 | 1005 | -2.44 | NA | NA | OVR | OVR | 8.5 | 1.7 | 210 | 990000 | 193000 | 797000 | |
| SVE-33 | 2/22/2012 | 1428 | -1.91 | NA | NA | OVR | OVR | 7.6 | 1.6 | 169 | 1000000 | 690000 | 310000 | |
| SVE-33 | 2/29/2012 | 1011 | -1.33 | NA | NA | OVR | OVR | 7.4 | 1.3 | 142 | 1000000 | 283000 | 717000 | |
| SVE-33 | 3/21/2012 | 920 | -1.41 | NA | NA | OVR | OVR | 7.4 | 1.0 | 144 | 1000000 | 1000000 | 0.0 | |
| SVE-33 | 4/18/2012 | 1101 | -2.18 | 0.15 | 37.59 | OVR | OVR | 6.8 | 0.8 | 148 | 1000000 | 542000 | 458000 | |
| SVE-33 | 5/16/2012 | 1234 | -2.43 | 1.11 | 0.00 | OVR | OVR | 7.7 | 0.9 | 165 | 1000000 | 420000 | 580000 | |
| SVE-33 | 6/20/2012 | 835 | -2.62 | 0.00 | 37.67 | OVR | OVR | 8.6 | 0.2 | 165 | 1000000 | 404000 | 596000 | |
| SVE-33 | 7/18/2012 | 744 | -2.74 | 0.01 | 37.60 | OVR | OVR | 8.4 | 1.2 | 77.1 | 1000000 | 375000 | 625000 | |
| SVE-33 | 8/15/2012 | 1128 | -2.72 | 0.01 | NA | OVR | OVR | 9.2 | 1.9 | 154 | 374000 | 144000 | 230000 | |
| SVE-33 | 9/19/2012 | 1007 | -4.35 | NA | 37.61 | OVR | OVR | 8.6 | 5.6 | 191 | 509000 | 175000 | 334000 | |
| SVE-33 | 10/17/2012 | 1245 | -4.33 | 0.00 | 37.59 | OVR | OVR | 7.8 | 7.6 | 218 | 506000 | 159000 | 347000 | |
| SVE-33 | 11/20/2012 | 1002 | -3.87 | 0.01 | 37.65 | OVR | OVR | 7.3 | 7.7 | 229 | 218000 | 125000 | 93000 | |
| SVE-33 | 12/19/2012 | 1115 | -2.66 | NA | 37.58 | OVR | OVR | 7.7 | 8.1 | 322 | 340000 | 128000 | 212000 | |
| SVE-33 | 1/16/2013 | 1049 | -2.55 | NM | 37.63 | OVR | OVR | 7.5 | 7.0 | 245 | 395000 | 135000 | 260000 | |
| SVE-33 | 2/25/2013 | 1055 | -2.61 | NM | 37.57 | OVR | OVR | 7.9 | 7.2 | 232 | 293000 | 97000 | 196000 | |
| SVE-33 | 3/20/2013 | 1338 | -5.28 | NM | 37.59 | OVR | OVR | 7.3 | 9.0 | 265 | 315000 | 96000 | 219000 | |

SEE LAST PAGE OF TABLE FOR NOTES

**TABLE 9**
**SVE SYSTEM MONTHLY MONITORING - SVE SAMPLING DATA**

| Sample ID | Date | Initial Reading Time (24-Hour) | Vacuum/Pressure | Air Flow | Groundwater | Fixed Gases | | | | Soil Vapor Concentrations | | | | Comments |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | Initial Reading (Inches of $H_2O$) | Pitot Tube Pressure (Inches of $H_2O$) | Depth to Water (feet) | CH4 (%) | LEL (%) | $CO_2$ (%) | $O_2$ (%) | PID (ppmv) | THC (ppmv) | CH4 (ppmv) | PHC (ppmv) | |
| SVE-34 | 2/13/2012 | 1331 | -2.17 | NA | NA | OVR | OVR | 10.2 | 1.0 | 320 | 290000 | 80000 | 210000 | |
| SVE-34 | 2/14/2012 | 1552 | -2.85 | NA | NA | OVR | OVR | 10.1 | 1.4 | 286 | 290000 | 63000 | 227000 | |
| SVE-34 | 2/15/2012 | 1032 | -2.71 | NA | NA | OVR | OVR | 9.9 | 1.3 | 298 | 540000 | 80400 | 459600 | |
| SVE-34 | 2/22/2012 | 1455 | -2.17 | NA | NA | OVR | OVR | 9.5 | 2.3 | 269 | 840000 | 166000 | 674000 | |
| SVE-34 | 2/29/2012 | 1048 | -1.25 | NA | NA | OVR | OVR | 9.5 | 2.0 | 261 | 333000 | 120000 | 213000 | |
| SVE-34 | 3/21/2012 | 930 | -1.44 | NA | NA | OVR | OVR | 9.1 | 1.9 | 238 | 379000 | 100000 | 279000 | |
| SVE-34 | 4/18/2012 | 1119 | -2.38 | 0.99 | 44.77 | OVR | OVR | 8.8 | 1.5 | 280 | 275000 | 98000 | 177000 | |
| SVE-34 | 5/16/2012 | 1248 | -2.55 | 0.00 | 44.85 | OVR | OVR | 9.2 | 2.4 | 300 | 268000 | 110000 | 158000 | |
| SVE-34 | 6/20/2012 | 857 | -2.81 | 0.00 | 44.81 | OVR | OVR | 8.9 | 4.4 | 226 | 172000 | 70000 | 102000 | |
| SVE-34 | 7/18/2012 | 812 | -2.94 | 0.01 | 44.82 | OVR | OVR | 7.9 | 7.0 | 110 | 243000 | 115000 | 128000 | |
| SVE-34 | 8/15/2012 | 1107 | -2.98 | 0.02 | NA | OVR | OVR | 8.2 | 7.1 | 212 | 123000 | 73000 | 50000 | |
| SVE-34 | 9/19/2012 | 1024 | -4.65 | NA | 46.32 | OVR | OVR | 7.2 | 9.4 | 276 | 145000 | 56600 | 88400 | |
| SVE-34 | 10/17/2012 | 1256 | -4.77 | 0.00 | 46.29 | OVR | OVR | 7.5 | 9.4 | 282 | 161000 | 62800 | 98200 | |
| SVE-34 | 11/20/2012 | 1012 | -4.08 | 0.01 | 46.65 | OVR | OVR | 7.3 | 9.9 | 313 | 80400 | 60200 | 20200 | |
| SVE-34 | 12/19/2012 | 1130 | -2.65 | NA | 47.16 | OVR | OVR | 7.5 | 9.8 | 435 | 102000 | 48500 | 53500 | |
| SVE-34 | 1/16/2013 | 1058 | -2.61 | NM | 47.38 | OVR | OVR | 8.0 | 8.9 | 370 | 108000 | 42000 | 66000 | |
| SVE-34 | 2/25/2013 | 1104 | -2.69 | NM | 47.90 | OVR | OVR | 7.9 | 9.7 | 447 | 58900 | 25400 | 33500 | |
| SVE-34 | 3/20/2013 | 1353 | -5.77 | NM | 47.70 | OVR | OVR | 6.9 | 11.0 | 422 | 63900 | 32800 | 31100 | |
| SVE-35 | 2/13/2012 | 1337 | -2.27 | NA | NA | OVR | OVR | 12.3 | 1.0 | 355 | 96800 | 46000 | 50800 | |
| SVE-35 | 2/14/2012 | 1600 | -2.82 | NA | NA | OVR | OVR | 12.2 | 1.5 | 246 | 136000 | 69400 | 66600 | |
| SVE-35 | 2/15/2012 | 1054 | -2.77 | NA | NA | OVR | OVR | 12.0 | 1.4 | 228 | 102000 | 68400 | 33600 | |
| SVE-35 | 2/22/2012 | 1509 | -2.27 | NA | NA | OVR | OVR | 11.4 | 1.6 | 241 | 171000 | 110000 | 61000 | |
| SVE-35 | 2/29/2012 | 1104 | -1.52 | NA | NA | OVR | OVR | 11.1 | 1.9 | 258 | 175000 | 62700 | 112300 | |
| SVE-35 | 3/21/2012 | 947 | -1.42 | NA | NA | OVR | OVR | 11.3 | 0.7 | 321 | 69700 | 53800 | 15900 | |
| SVE-35 | 4/18/2012 | 1137 | -2.35 | 1.37 | 42.82 | OVR | OVR | 10.3 | 3.1 | 320 | 52800 | 28400 | 24400 | |
| SVE-35 | 5/16/2012 | 1319 | -2.55 | 0.01 | 42.90 | 85.3 | OVR | 9.7 | 4.9 | 395 | 29700 | 15100 | 14600 | |
| SVE-35 | 6/20/2012 | 1015 | -2.67 | 0.01 | 42.91 | 59.6 | OVR | 9.2 | 6.7 | 405 | 16700 | 9800 | 6900 | |
| SVE-35 | 7/18/2012 | 837 | -2.95 | 0.11 | 42.94 | 35.0 | OVR | 8.3 | 8.8 | 401 | 17000 | 6500 | 10500 | |
| SVE-35 | 8/15/2012 | 1051 | -3.05 | 0.00 | NA | 35.9 | OVR | 8.4 | 9.5 | 394 | 12800 | 5100 | 7700 | |
| SVE-35 | 9/19/2012 | 1034 | -4.76 | NA | 44.34 | 27.8 | OVR | 8.2 | 10.4 | 525 | 9600 | 4100 | 5500 | |
| SVE-35 | 10/17/2012 | 1308 | -4.88 | 0.00 | 44.26 | 17.5 | OVR | 7.6 | 11.8 | 521 | 9200 | 1900 | 7300 | |
| SVE-35 | 11/20/2012 | 1024 | -4.14 | 0.01 | 44.24 | 10.2 | OVR | 7.2 | 11.7 | 431 | 5600 | 2000 | 3600 | |
| SVE-35 | 12/19/2012 | 1140 | -2.67 | NA | 44.20 | 4.2 | 84.0 | 7.4 | 12.0 | 440 | 3300 | 1300 | 2000 | |
| SVE-35 | 1/16/2013 | 1109 | -2.55 | NM | 44.37 | 7.2 | OVR | 7.9 | 11.4 | 481 | 4100 | 1920 | 2180 | |
| SVE-35 | 2/25/2013 | 1113 | -2.55 | NM | 44.30 | 9.3 | OVR | 7.9 | 10.9 | 377 | 5700 | 1900 | 3800 | |
| SVE-35 | 3/20/2013 | 1408 | -5.09 | NM | 44.12 | 13.0 | OVR | 6.9 | 13.0 | 385 | 8200 | 4100 | 4100 | |
| SVE-36 | 2/6/2012 | 1438 | -3.05 | NA | 22.83 | 75.8 | OVR | 13.9 | 0.5 | 117 | 160000 | 105000 | 55000 | |
| SVE-36 | 2/7/2012 | 1121 | -3.12 | NA | NA | 76.9 | OVR | 13.7 | 1.0 | 111 | 96800 | 91470 | 5330 | |
| SVE-36 | 2/8/2012 | 1022 | -3.35 | NA | 23.60 | 68.7 | OVR | 12.5 | 2.2 | 117 | 93940 | 89730 | 4210 | |
| SVE-36 | 2/15/2012 | 1151 | -2.77 | NA | NA | 74.5 | OVR | 10.5 | 4.9 | 100 | 120000 | 93480 | 26520 | |
| SVE-36 | 2/22/2012 | 1618 | -2.67 | NA | NA | 84.2 | OVR | 10.2 | 5.4 | 84.4 | 200000 | 183000 | 17000 | |
| SVE-36 | 2/29/2012 | 1411 | -1.35 | NA | NA | 80.9 | OVR | 10.5 | 5.5 | 82.1 | 120000 | 97000 | 23000 | |
| SVE-36 | 3/21/2012 | 1022 | -1.41 | NA | NA | 16.4 | OVR | 6.5 | 10.1 | 302 | 22450 | 13800 | 8650 | |
| SVE-36 | 4/18/2012 | 1246 | -2.64 | 2.08 | 22.81 | 8.4 | OVR | 6.6 | 10.4 | 348 | 9280 | 5700 | 3580 | |
| SVE-36 | 5/16/2012 | 1420 | -2.88 | 0.03 | 0.00 | 3.8 | 76.0 | 6.4 | 11.8 | 320 | 1900 | 1500 | 400 | |
| SVE-36 | 6/20/2012 | 1115 | -2.89 | 0.05 | 22.89 | 1.2 | 25.0 | 5.7 | 12.6 | 225 | 2300 | 572 | 1728 | |
| SVE-36 | 7/18/2012 | 954 | -3.24 | 0.01 | 22.81 | 0.6 | 12.0 | 5.3 | 13.6 | 227 | 910 | 100 | 810 | |
| SVE-36 | 8/16/2012 | 1020 | -3.51 | NA | NA | 0.5 | 12.0 | 4.8 | 15.4 | 243 | 967 | 90.0 | 877 | |
| SVE-36 | 9/19/2012 | 1118 | -5.77 | NA | NE | 0.3 | 13.0 | 3.2 | 17.1 | 235 | 891 | 82.0 | 809 | |
| SVE-36 | 10/17/2012 | 1354 | -6.39 | 0.00 | 22.79 | 0.4 | 8.0 | 3.1 | 17.4 | 157 | 1380 | 131 | 1249 | |
| SVE-36 | 11/20/2012 | 1119 | -5.12 | 0.26 | 22.78 | 0.0 | 1.0 | 1.7 | 18.7 | 103 | 249 | 23.9 | 225 | |
| SVE-36 | 12/19/2012 | 1425 | -3.20 | NA | 22.73 | 0.0 | 0.0 | 3.4 | 17.1 | 67.9 | 190 | 23.4 | 167 | |
| SVE-36 | 1/16/2013 | 1147 | -3.12 | NM | 22.72 | 0.0 | 0.0 | 2.9 | 17.4 | 62.7 | 115 | 4.8 | 110 | |
| SVE-36 | 2/25/2013 | 1143 | -3.55 | NM | 22.70 | 0.0 | 1.0 | 2.3 | 18.2 | 25.2 | 85.9 | 29.9 | 56.0 | |
| SVE-36 | 3/20/2013 | 1459 | -7.65 | NM | 22.69 | 0.2 | 5.0 | 1.9 | 18.7 | 30.1 | 580 | 506 | 74.0 | |

Notes:
1) NM = Not Measured; NE = Not Encountered; PID = Photo Ionization Detector; THC = Total Hydrocarbon Concentration; PHC = Petroleum Hydrocarbon Concentration; OVR = Over-range; ppmv = Parts Per Million By Volume.

SEE LAST PAGE OF TABLE FOR NOTES

**TABLE 10**
**SVE SYSTEM MONTHLY MONITORING - VMP SAMPLING DATA**

| Sample ID | Date | Initial Reading Time (24-Hour) | Vacuum/Pressure | | Fixed Gases | | | | Soil Vapor Concentrations | | | | Comments |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | Initial Reading (Inches of $H_2O$) | Stabilized Reading (Inches of $H_2O$) | CH4 (%) | LEL (%) | $CO_2$ (%) | $O_2$ (%) | PID (ppmv) | THC (ppmv) | CH4 (ppmv) | PHC (ppmv) | |
| VMP-01-5 | 2/15/2012 | 1641 | 0.05 | 0.08 | 0.0 | 0.0 | 3.7 | 12.4 | 25.1 | 64.5 | 6.7 | 57.8 | |
| VMP-01-5 | 2/16/2012 | 1433 | 0.06 | 0.06 | 0.0 | 0.0 | 2.1 | 20.0 | 23.7 | 72.5 | 23.5 | 49.0 | |
| VMP-01-5 | 2/17/2012 | 1327 | 0.06 | 0.07 | 0.0 | 0.0 | 3.2 | 5.4 | 7.0 | 28.2 | 18.1 | 10.1 | |
| VMP-01-5 | 2/22/2012 | 804 | 0.04 | 0.00 | 42.1 | OVR | 11.4 | 1.0 | 154 | 22470 | 7870 | 14600 | |
| VMP-01-5 | 2/29/2012 | 846 | -1.11 | - 0.24 | 12.0 | OVR | 5.0 | 16.2 | 186 | 5430 | 214 | 5216 | |
| VMP-01-5 | 3/21/2012 | 1356 | 0.03 | 0.08 | 0.0 | 0.0 | 1.2 | 19.0 | 4.0 | 3.9 | 0.0 | 3.9 | |
| VMP-01-5 | 4/18/2012 | 829 | -0.14 | -0.03 | 0.0 | 0.0 | 1.9 | 19.5 | 2.4 | 1.5 | 0.0 | 1.5 | |
| VMP-01-5 | 5/16/2012 | 834 | -0.09 | -0.07 | 0.0 | 0.0 | 2.1 | 18.9 | 1.0 | 6.1 | 4.4 | 1.7 | |
| VMP-01-5 | 6/20/2012 | 1353 | 0.07 | 0.09 | 0.0 | 0.0 | 2.2 | 18.6 | 1.0 | 9.6 | 5.6 | 4.0 | |
| VMP-01-5 | 7/18/2012 | 1348 | 0.04 | 0.05 | 0.0 | 0.0 | 1.4 | 18.8 | 0.8 | 23.6 | 11.0 | 12.6 | |
| VMP-01-5 | 8/15/2012 | 1404 | 0.00 | 0.03 | 0.0 | 0.0 | 1.4 | 17.7 | 0.7 | 7.0 | 0.0 | 7.0 | |
| VMP-01-5 | 9/19/2012 | 837 | -0.04 | -0.08 | 0.0 | 0.0 | 0.6 | 20.4 | 0.6 | 4.6 | 0.0 | 4.6 | |
| VMP-01-5 | 10/17/2012 | 810 | -0.09 | -0.05 | 0.0 | 0.0 | 1.7 | 19.5 | 1.3 | 48.2 | 31.8 | 16.4 | |
| VMP-01-5 | 11/20/2012 | 1432 | -0.03 | -0.02 | 0.0 | 0.0 | 0.5 | 20.3 | 0.4 | 5.4 | 2.7 | 2.7 | |
| VMP-01-5 | 12/19/2012 | 830 | -0.54 | -0.06 | 0.0 | 0.0 | 0.5 | 20.5 | 0.5 | 3.8 | 0.0 | 3.8 | |
| VMP-01-5 | 1/16/2013 | 1345 | 0.02 | - 0.04 | OVR | OVR | 3.6 | 12.6 | 92.5 | 120000 | 64200 | 55800 | Resampled and confirmed. |
| VMP-01-5 | 2/26/2013 | 900 | 0.06 | - 0.09 | 65.0 | OVR | 4.1 | 13.0 | 75.7 | 49200 | 33000 | 16200 | |
| VMP-01-5 | 3/21/2013 | 1256 | -0.01 | 0.04 | 0.0 | 0.0 | 0.2 | 18.6 | 0.9 | 1.9 | 0.0 | 1.9 | VMP reinstalled on 3/6/13. |
| VMP-01-8.5 | 2/15/2012 | 1642 | -0.04 | 0.10 | 0.0 | 0.0 | 9.5 | 3.3 | 26.5 | 183 | 126 | 57.4 | |
| VMP-01-8.5 | 2/16/2012 | 1434 | 4.70 | 0.08 | 0.0 | 0.0 | 0.2 | 20.9 | 15.1 | 53.8 | 32.9 | 20.9 | |
| VMP-01-8.5 | 2/17/2012 | 1327 | 0.11 | 0.09 | 0.0 | 0.0 | 9.4 | 1.7 | 8.6 | 53.8 | 35.2 | 18.6 | |
| VMP-01-8.5 | 2/22/2012 | 807 | 0.04 | 0.00 | 35.6 | OVR | 11.4 | 1.6 | 152 | 19860 | 6520 | 13340 | |
| VMP-01-8.5 | 2/29/2012 | 847 | -1.03 | - 0.26 | 14.6 | OVR | 6.9 | 15.0 | 189 | 4460 | 139 | 4321 | |
| VMP-01-8.5 | 3/21/2012 | 1357 | 0.04 | 0.10 | 0.0 | 0.0 | 4.3 | 9.6 | 4.5 | 0.0 | 0.0 | 0.0 | |
| VMP-01-8.5 | 4/18/2012 | 830 | -0.08 | -0.03 | 0.0 | 0.0 | 2.5 | 19.2 | 3.4 | 2.1 | 0.0 | 2.1 | |
| VMP-01-8.5 | 5/16/2012 | 839 | -0.10 | -0.12 | 0.0 | 0.0 | 2.2 | 19.0 | 1.1 | 3.9 | 0.0 | 3.9 | |
| VMP-01-8.5 | 6/20/2012 | 1354 | 0.06 | 0.04 | 0.0 | 0.0 | 5.9 | 10.9 | 2.0 | 1.8 | 0.0 | 1.8 | |
| VMP-01-8.5 | 7/18/2012 | 1352 | 0.04 | 0.07 | 0.0 | 0.0 | 4.2 | 14.2 | 2.3 | 42.1 | 30.7 | 11.4 | |
| VMP-01-8.5 | 8/15/2012 | 1419 | 0.01 | -0.04 | 0.0 | 0.0 | 5.0 | 13.9 | 1.3 | 4.9 | 0.0 | 4.9 | |
| VMP-01-8.5 | 9/19/2012 | 838 | -0.68 | -0.76 | 0.0 | 0.0 | 0.8 | 20.0 | 0.9 | 3.0 | 0.0 | 3.0 | |
| VMP-01-8.5 | 10/17/2012 | 811 | -0.10 | 0.28 | 0.0 | 0.0 | 3.1 | 17.1 | 0.7 | 3.4 | 0.0 | 3.4 | |
| VMP-01-8.5 | 11/20/2012 | 1434 | -0.02 | -0.01 | 0.0 | 0.0 | 1.1 | 19.4 | 0.6 | 3.5 | 0.0 | 3.5 | |
| VMP-01-8.5 | 12/19/2012 | 835 | -0.04 | -0.60 | 0.0 | 0.0 | 0.7 | 20.1 | 0.8 | 3.3 | 0.0 | 3.3 | |
| VMP-01-8.5 | 1/16/2013 | 1350 | 0.06 | - 0.05 | 1.5 | 31.0 | 1.7 | 19.1 | 59.1 | 4200 | 1800 | 2400 | Resampled and confirmed. |
| VMP-01-8.5 | 2/25/2013 | 900 | 0.06 | - 0.14 | 0.4 | 9.0 | 4.0 | 14.9 | 27.3 | 1100 | 579 | 521 | |
| VMP-01-8.5 | 3/21/2013 | 1300 | -0.02 | 0.07 | 0.0 | 0.0 | 2.1 | 18.6 | 0.5 | 1.2 | 0.0 | 1.2 | VMP reinstalled on 3/6/13. |

SEE LAST PAGE OF TABLE FOR NOTES

**TABLE 10**
**SVE SYSTEM MONTHLY MONITORING - VMP SAMPLING DATA**

| Sample ID | Date | Initial Reading Time (24-Hour) | Vacuum/Pressure | | Fixed Gases | | | | Soil Vapor Concentrations | | | | Comments |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | Initial Reading (Inches of $H_2O$) | Stabilized Reading (Inches of $H_2O$) | CH4 (%) | LEL (%) | $CO_2$ (%) | $O_2$ (%) | PID (ppmv) | THC (ppmv) | CH4 (ppmv) | PHC (ppmv) | |
| VMP-01-23.5 | 2/15/2012 | 1643 | 0.06 | 0.01 | OVR | OVR | 9.9 | 1.7 | 68.9 | 132000 | 127000 | 5000 | |
| VMP-01-23.5 | 2/16/2012 | 1435 | 0.09 | 0.14 | 6.1 | OVR | 11.6 | 1.7 | 45.4 | 19990 | 13800 | 6190 | |
| VMP-01-23.5 | 2/17/2012 | 1327 | -0.02 | 0.09 | OVR | OVR | 10.1 | 1.2 | 76.2 | 161000 | 88990 | 72010 | |
| VMP-01-23.5 | 2/22/2012 | 808 | 0.04 | - 0.13 | OVR | OVR | 8.3 | 1.2 | 53.5 | 560000 | 250000 | 310000 | |
| VMP-01-23.5 | 2/29/2012 | 848 | -1.04 | - 0.24 | OVR | OVR | 10.1 | 1.4 | 63.7 | 133000 | 85100 | 47900 | |
| VMP-01-23.5 | 3/21/2012 | 1358 | 0.06 | 0.16 | OVR | OVR | 9.4 | 1.5 | 67.5 | 64900 | 46200 | 18700 | |
| VMP-01-23.5 | 4/18/2012 | 831 | -0.12 | -0.05 | OVR | OVR | 10.0 | 1.0 | 64.6 | 128000 | 69100 | 58900 | |
| VMP-01-23.5 | 5/16/2012 | 843 | -0.21 | -0.24 | 11.4 | OVR | 11.6 | 1.8 | 41.6 | 13800 | 7700 | 6100 | |
| VMP-01-23.5 | 6/20/2012 | 1355 | 0.05 | 0.11 | 16.5 | OVR | 10.9 | 1.4 | 58.3 | 57600 | 38600 | 19000 | |
| VMP-01-23.5 | 7/18/2012 | 1349 | 0.30 | 0.07 | OVR | OVR | 6.7 | 8.3 | 52.6 | 38500 | 23300 | 15200 | |
| VMP-01-23.5 | 8/15/2012 | 1414 | 0.00 | 0.00 | OVR | OVR | 7.0 | 8.4 | 128 | 44900 | 28900 | 16000 | |
| VMP-01-23.5 | 9/19/2012 | 839 | -0.09 | -0.09 | 0.0 | 1.0 | 3.1 | 16.9 | 4.2 | 14.3 | 4.9 | 9.4 | Sample integrity compromised during screening. |
| VMP-01-23.5 | 10/17/2012 | 812 | -0.05 | -0.26 | OVR | OVR | 5.3 | 9.5 | 70.2 | 208000 | 124000 | 84000 | |
| VMP-01-23.5 | 11/20/2012 | 1436 | -0.06 | -0.04 | OVR | OVR | 3.2 | 14.8 | 125 | 40300 | 28500 | 11800 | |
| VMP-01-23.5 | 12/19/2012 | 840 | -0.05 | -0.06 | 0.0 | 1.0 | 2.5 | 17.3 | 1.2 | 14.5 | 4.9 | 9.6 | |
| VMP-01-23.5 | 1/16/2013 | 1355 | 0.05 | -0.04 | OVR | OVR | 4.8 | 9.0 | 86.3 | 220000 | 105000 | 115000 | Resampled and confirmed. |
| VMP-01-23.5 | 2/26/2013 | 905 | 0.07 | -0.32 | OVR | OVR | 5.3 | 7.3 | 54.0 | 285000 | 136000 | 149000 | |
| VMP-01-23.5 | 3/21/2013 | 1304 | -0.36 | -0.04 | OVR | OVR | 10.1 | 1.8 | 81.4 | 85700 | 36700 | 49000 | VMP reinstalled on 3/6/13. |
| VMP-01-38.5 | 2/15/2012 | 1644 | 0.06 | NM | NM | NM | NM | NM | NM | NM | NM | NM | Screen submerged. |
| VMP-01-38.5 | 2/16/2012 | 1436 | 0.18 | 0.03 | 0.0 | 0.0 | 1.2 | 20.6 | 20.5 | 73.9 | 22.2 | 51.7 | |
| VMP-01-38.5 | 2/17/2012 | 1327 | -0.05 | 0.04 | 0.0 | 0.0 | 1.4 | 13.7 | 7.1 | 10.5 | 10.5 | 0 | |
| VMP-01-38.5 | 2/22/2012 | 808 | 0.02 | - 0.02 | 10.5 | OVR | 4.8 | 12.6 | 121 | 8980 | 2980 | 6000 | |
| VMP-01-38.5 | 2/29/2012 | 849 | -1.02 | - 0.33 | 5.5 | OVR | 3.4 | 17.8 | 150 | 4625 | 74.3 | 4551 | |
| VMP-01-38.5 | 3/21/2012 | 1359 | -0.03 | 0.06 | 0.2 | 4.0 | 0.6 | 20.3 | 37.2 | 165 | 30.8 | 134 | |
| VMP-01-38.5 | 4/18/2012 | 832 | -0.44 | 0.00 | 0.0 | 0.0 | 1.9 | 19.5 | 3.2 | 2.6 | 0.0 | 2.6 | |
| VMP-01-38.5 | 5/16/2012 | 849 | -1.94 | -0.23 | 0.0 | 0.0 | 1.4 | 19.6 | 1.9 | 25.8 | 20.5 | 5.3 | |
| VMP-01-38.5 | 6/20/2012 | 1356 | 0.03 | 0.04 | 0.0 | 0.0 | 0.3 | 20.7 | 0.5 | 10.1 | 4.0 | 6.1 | |
| VMP-01-38.5 | 7/18/2012 | 1353 | 0.00 | 0.06 | 0.1 | 3.0 | 1.2 | 18.4 | 7.5 | 436 | 185 | 251 | |
| VMP-01-38.5 | 8/15/2012 | 1409 | -1.19 | -0.07 | 0.0 | 0.0 | 1.3 | 18.6 | 2.8 | 89.2 | 44.2 | 45.0 | |
| VMP-01-38.5 | 9/19/2012 | 840 | -0.07 | -0.07 | 0.0 | 0.0 | 0.3 | 20.6 | 0.9 | 4.3 | 0.0 | 4.3 | |
| VMP-01-38.5 | 10/17/2012 | 815 | 0.00 | -0.05 | 68.1 | OVR | 0.9 | 19.9 | 72.3 | 35400 | 24400 | 11000 | |
| VMP-01-38.5 | 11/20/2012 | 1438 | -0.04 | -0.03 | 0.2 | 4.0 | 0.3 | 20.3 | 17.0 | 375 | 133 | 242 | |
| VMP-01-38.5 | 12/19/2012 | 845 | -0.07 | -0.05 | 0.0 | 0.0 | 0.3 | 20.7 | 2.2 | 16.3 | 0.0 | 16.3 | |
| VMP-01-38.5 | 1/16/2013 | 1400 | 0.05 | -0.04 | OVR | OVR | 3.1 | 11.5 | 87.8 | 215000 | 104000 | 111000 | Resampled and confirmed. |
| VMP-01-38.5 | 2/25/2013 | 907 | -0.10 | -0.02 | OVR | OVR | 3.3 | 11.7 | 65.0 | 140000 | 77900 | 62100 | |
| VMP-01-38.5 | 3/21/2013 | 1308 | -1.11 | -0.50 | OVR | OVR | 4.0 | 0.9 | 25.7 | 1000000 | 1000000 | 0.0 | VMP reinstalled on 3/6/13. |

SEE LAST PAGE OF TABLE FOR NOTES

**TABLE 10**
**SVE SYSTEM MONTHLY MONITORING - VMP SAMPLING DATA**

| Sample ID | Date | Initial Reading Time (24-Hour) | Vacuum/Pressure | | Fixed Gases | | | | Soil Vapor Concentrations | | | | Comments |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | Initial Reading (Inches of $H_2O$) | Stabilized Reading (Inches of $H_2O$) | CH4 (%) | LEL (%) | $CO_2$ (%) | $O_2$ (%) | PID (ppmv) | THC (ppmv) | CH4 (ppmv) | PHC (ppmv) | |
| VMP-02-5 | 2/15/2012 | 1705 | -0.11 | 0.18 | 0.0 | 0.0 | 1.6 | 19.2 | 12.0 | 39.3 | 2.0 | 37.3 | |
| VMP-02-5 | 2/16/2012 | 1524 | 0.18 | 0.17 | 0.0 | 0.0 | 0.5 | 20.9 | 4.0 | 13.3 | 6.3 | 6.9 | |
| VMP-02-5 | 2/17/2012 | 1356 | 0.07 | 0.08 | 0.0 | 0.0 | 4.6 | 11.4 | 3.0 | 15.4 | 15.3 | 0.1 | |
| VMP-02-5 | 2/22/2012 | 825 | -0.01 | - 0.01 | 0.0 | 0.0 | 7.6 | 11.2 | 10.5 | 94.0 | 58.0 | 36.0 | |
| VMP-02-5 | 2/29/2012 | 906 | -0.07 | - 0.05 | 0.0 | 0.0 | 1.0 | 20.7 | 1.0 | 37.1 | 3.5 | 33.6 | |
| VMP-02-5 | 3/21/2012 | 1416 | 0.05 | 0.06 | 0.0 | 0.0 | 1.1 | 19.2 | 0.6 | 0.0 | 0.0 | 0.0 | |
| VMP-02-5 | 4/18/2012 | 914 | -0.16 | -0.09 | 0.0 | 0.0 | 0.1 | 20.8 | 0.3 | 3.0 | 0.0 | 3.0 | |
| VMP-02-5 | 5/16/2012 | 901 | -0.30 | -0.30 | 0.0 | 0.0 | 0.1 | 20.8 | 0.2 | 1.7 | 0.0 | 1.7 | |
| VMP-02-5 | 6/20/2012 | 1419 | 0.03 | 0.02 | 0.0 | 0.0 | 0.7 | 20.0 | 1.6 | 5.8 | 3.1 | 2.8 | |
| VMP-02-5 | 7/18/2012 | 1425 | 0.04 | -0.02 | 0.0 | 0.0 | 1.1 | 19.1 | 0.6 | 2.5 | 0.0 | 2.5 | |
| VMP-02-5 | 8/15/2012 | 1323 | -0.13 | 0.00 | 0.0 | 0.0 | 3.0 | 18.1 | 0.6 | 3.1 | 0.0 | 3.1 | |
| VMP-02-5 | 9/19/2012 | 920 | -0.25 | -0.21 | 0.0 | 0.0 | 0.5 | 20.6 | 0.8 | 2.7 | 0.0 | 2.7 | |
| VMP-02-5 | 10/17/2012 | 1214 | -0.08 | -0.07 | 0.0 | 0.0 | 0.2 | 20.7 | 0.3 | 1.7 | 0.0 | 1.7 | |
| VMP-02-5 | 11/20/2012 | 1458 | -0.19 | -0.22 | 0.0 | 0.0 | 0.4 | 20.4 | 0.1 | 1.6 | 0.0 | 1.6 | |
| VMP-02-5 | 12/19/2012 | 900 | -0.26 | -0.32 | 0.0 | 0.0 | 0.6 | 20.3 | 0.2 | 0.9 | 0.0 | 0.9 | |
| VMP-02-5 | 1/16/2013 | 1410 | -0.04 | -0.15 | 0.0 | 0.0 | 0.9 | 19.7 | 0.2 | 1.5 | 0.0 | 1.5 | |
| VMP-02-5 | 2/26/2013 | 920 | -0.07 | -0.06 | 0.2 | 5.0 | 2.6 | 15.4 | 4.9 | 1210 | 1110 | 100 | |
| VMP-02-5 | 2/26/2013 | 1330 | -0.08 | NM | 2.4 | 47.0 | 2.2 | 13.5 | 25.5 | 5500 | 1900 | 3600 | Resampled tedlar and vacuum to confirm readings. |
| VMP-02-5 | 3/21/2013 | 1314 | -0.11 | -0.04 | 0.0 | 0.0 | 0.2 | 20.8 | 0.5 | 1.2 | 0.0 | 1.2 | |
| VMP-02-8.5 | 2/15/2012 | 1706 | -0.12 | 0.22 | 0.0 | 0.0 | 6.4 | 11.7 | 16.5 | 28.3 | 1.0 | 27.3 | |
| VMP-02-8.5 | 2/16/2012 | 1525 | 0.36 | 0.18 | 0.0 | 0.0 | 2.3 | 18.8 | 4.3 | 13.6 | 3.8 | 9.8 | |
| VMP-02-8.5 | 2/17/2012 | 1356 | 0.08 | 0.09 | 0.0 | 0.0 | 8.0 | 9.8 | 4.7 | 25.9 | 16.2 | 9.7 | |
| VMP-02-8.5 | 2/22/2012 | 825 | -0.05 | - 0.02 | 0.0 | 0.0 | 0.2 | 20.8 | 1.6 | 10.8 | 5.5 | 5.3 | |
| VMP-02-8.5 | 2/29/2012 | 906 | -0.16 | 0.06 | 0.0 | 0.0 | 2.7 | 17.9 | 11.0 | 38.2 | 4.2 | 34.0 | |
| VMP-02-8.5 | 3/21/2012 | 1417 | -0.04 | 0.05 | 0.0 | 0.0 | 6.0 | 14.0 | 0.7 | 0.0 | 0.0 | 0.0 | |
| VMP-02-8.5 | 4/18/2012 | 915 | -0.16 | -0.10 | 0.0 | 0.0 | 1.5 | 19.3 | 0.4 | 2.5 | 0.0 | 2.5 | |
| VMP-02-8.5 | 5/16/2012 | 905 | -0.32 | -0.31 | 0.0 | 0.0 | 0.9 | 20.1 | 0.3 | 0.8 | 0.0 | 0.8 | |
| VMP-02-8.5 | 6/20/2012 | 1321 | 0.02 | 0.03 | 0.0 | 0.0 | 4.2 | 16.4 | 0.9 | 2.2 | 0.0 | 2.2 | |
| VMP-02-8.5 | 7/18/2012 | 1430 | 0.03 | -0.02 | 0.0 | 0.0 | 4.7 | 15.5 | 0.8 | 2.3 | 0.0 | 2.3 | |
| VMP-02-8.5 | 8/15/2012 | 1329 | -0.02 | 0.00 | 0.0 | 0.0 | 5.3 | 16.0 | 0.4 | 1.5 | 0.0 | 1.5 | |
| VMP-02-8.5 | 9/19/2012 | 921 | -0.28 | -0.25 | 0.0 | 0.0 | 0.7 | 20.3 | 0.5 | 4.0 | 0.0 | 4.0 | |
| VMP-02-8.5 | 10/17/2012 | 1216 | -0.10 | -0.09 | 0.0 | 0.0 | 0.5 | 20.4 | 0.6 | 1.4 | 0.0 | 1.4 | |
| VMP-02-8.5 | 11/20/2012 | 1500 | -0.21 | -0.23 | 0.0 | 0.0 | 1.0 | 19.9 | 0.2 | 0.3 | 0.0 | 0.3 | |
| VMP-02-8.5 | 12/19/2012 | 905 | -0.27 | -0.34 | 0.0 | 0.0 | 1.6 | 19.5 | 0.2 | 0.3 | 0.0 | 0.3 | |
| VMP-02-8.5 | 1/16/2013 | 1415 | -0.02 | -0.16 | 0.0 | 0.0 | 2.5 | 19.0 | 0.1 | 1.7 | 0.0 | 1.7 | |
| VMP-02-8.5 | 2/26/2013 | 920 | -0.07 | -0.05 | 0.0 | 1.0 | 2.8 | 16.6 | 2.1 | 350 | 302 | 48.0 | |
| VMP-02-8.5 | 2/26/2013 | 1330 | -0.08 | NM | 0.1 | 2.0 | 2.6 | 16.6 | 5.9 | 670 | 555 | 115 | Resampled tedlar and vacuum to confirm readings. |
| VMP-02-8.5 | 3/21/2013 | 1318 | -0.12 | -0.04 | 0.0 | 0.0 | 1.0 | 20.3 | 0.2 | 0.3 | 0.0 | 0.3 | |

SEE LAST PAGE OF TABLE FOR NOTES

**TABLE 10**
**SVE SYSTEM MONTHLY MONITORING - VMP SAMPLING DATA**

| Sample ID | Date | Initial Reading Time (24-Hour) | Vacuum/Pressure | | Fixed Gases | | | | Soil Vapor Concentrations | | | | Comments |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | Initial Reading (Inches of $H_2O$) | Stabilized Reading (Inches of $H_2O$) | CH4 (%) | LEL (%) | $CO_2$ (%) | $O_2$ (%) | PID (ppmv) | THC (ppmv) | CH4 (ppmv) | PHC (ppmv) | |
| VMP-02-22 | 2/15/2012 | 1707 | -0.14 | 0.32 | 2.5 | 51.0 | 11.8 | 1.9 | 28.3 | 22000 | 20500 | 1500 | |
| VMP-02-22 | 2/16/2012 | 1526 | 0.28 | 0.26 | 0.0 | 0.0 | 8.9 | 8.1 | 7.3 | 1000 | 1000 | 0.0 | |
| VMP-02-22 | 2/17/2012 | 1357 | 0.12 | 0.13 | 0.7 | 15.0 | 10.3 | 4.9 | 20.6 | 6180 | 5600 | 580 | |
| VMP-02-22 | 2/22/2012 | 826 | 0.00 | - 0.03 | 1.0 | 20.0 | 11.2 | 3.3 | 29.3 | 11550 | 7490 | 4060 | |
| VMP-02-22 | 2/29/2012 | 907 | -0.09 | 0.12 | 0.2 | 4.0 | 9.7 | 6.8 | 18.5 | 1360 | 1360 | 0.0 | |
| VMP-02-22 | 3/21/2012 | 1418 | 0.09 | 0.08 | 0.0 | 0.0 | 8.5 | 8.5 | 8.0 | 170 | 162 | 8.0 | |
| VMP-02-22 | 4/18/2012 | 916 | -0.22 | -0.13 | 0.0 | 0.0 | 6.3 | 13.5 | 0.5 | 3.0 | 0.0 | 3.0 | |
| VMP-02-22 | 5/16/2012 | 909 | -0.42 | -0.41 | 0.0 | 0.0 | 5.8 | 15.1 | 0.3 | 0.4 | 0.0 | 0.4 | |
| VMP-02-22 | 6/20/2012 | 1421 | 0.05 | 0.03 | 0.0 | 0.0 | 5.4 | 14.6 | 1.6 | 4.7 | 0.0 | 4.7 | |
| VMP-02-22 | 7/18/2012 | 1425 | 0.03 | -0.03 | 0.0 | 0.0 | 5.1 | 14.5 | 0.7 | 2.5 | 0.0 | 2.5 | |
| VMP-02-22 | 8/15/2012 | 1330 | -0.04 | 0.00 | 0.0 | 0.0 | 4.1 | 17.1 | 0.4 | 2.5 | 0.0 | 2.5 | |
| VMP-02-22 | 9/19/2012 | 922 | -0.47 | -0.40 | 0.0 | 0.0 | 4.0 | 17.6 | 0.6 | 1.8 | 0.0 | 1.8 | |
| VMP-02-22 | 10/17/2012 | 1217 | -0.23 | -0.16 | 0.0 | 0.0 | 3.2 | 17.5 | 0.6 | 1.2 | 0.0 | 1.2 | |
| VMP-02-22 | 11/20/2012 | 1502 | -0.29 | -0.32 | 0.0 | 0.0 | 3.5 | 17.4 | 0.3 | 1.0 | 0.0 | 1.0 | |
| VMP-02-22 | 12/19/2012 | 910 | -0.34 | -0.44 | 0.0 | 0.0 | 3.2 | 17.9 | 0.3 | 0.5 | 0.0 | 0.5 | |
| VMP-02-22 | 1/16/2013 | 1420 | -0.03 | -0.22 | 0.0 | 0.0 | 3.7 | 16.3 | 0.3 | 19.3 | 14.8 | 4.5 | |
| VMP-02-22 | 2/26/2013 | 925 | 0.10 | -0.08 | 0.0 | 0.0 | 4.0 | 14.6 | 3.6 | 195 | 150 | 45.0 | |
| VMP-02-22 | 2/26/2013 | 1330 | 0.12 | NM | 0.1 | 3.0 | 4.2 | 14.2 | 4.2 | 960 | 787 | 173 | Resampled tedlar and vacuum to confirm readings. |
| VMP-02-22 | 3/21/2013 | 1322 | -0.15 | -0.05 | 0.0 | 0.0 | 1.7 | 19.7 | 0.4 | 0.8 | 0.0 | 0.8 | |
| VMP-02-42 | 2/15/2012 | 1708 | 0.37 | NM | NM | NM | NM | NM | NM | NM | NM | NM | Screen submerged. |
| VMP-02-42 | 2/16/2012 | 1527 | 5.84 | NM | NM | NM | NM | NM | NM | NM | NM | NM | Screen submerged. |
| VMP-02-42 | 2/17/2012 | 1357 | 0.09 | NM | NM | NM | NM | NM | NM | NM | NM | NM | Screen submerged. |
| VMP-02-42 | 2/22/2012 | 826 | -0.05 | NM | NM | NM | NM | NM | NM | NM | NM | NM | Screen submerged. |
| VMP-02-42 | 2/29/2012 | 909 | 0.95 | NM | NM | NM | NM | NM | NM | NM | NM | NM | Screen submerged. |
| VMP-02-42 | 3/21/2012 | NA | NM | NM | NM | NM | NM | NM | NM | NM | NM | NM | Screen submerged. |
| VMP-02-42 | 4/18/2012 | 917 | -3.02 | NM | NM | NM | NM | NM | NM | NM | NM | NM | Screen submerged. |
| VMP-02-42 | 5/16/2012 | 914 | -0.24 | NM | NM | NM | NM | NM | NM | NM | NM | NM | Screen submerged. |
| VMP-02-42 | 6/20/2012 | 1422 | 11.50 | NM | NM | NM | NM | NM | NM | NM | NM | NM | Screen submerged. |
| VMP-02-42 | 7/18/2012 | 1430 | -0.52 | -0.07 | NM | NM | NM | NM | NM | NM | NM | NM | Screen submerged. |
| VMP-02-42 | 8/15/2012 | 1331 | 0.00 | 0.00 | NM | NM | NM | NM | NM | NM | NM | NM | Screen submerged. |
| VMP-02-42 | 9/19/2012 | 923 | 12.19 | -0.40 | OVR | OVR | 4.3 | 1.6 | 30.9 | 1000000 | 944000 | 56000 | |
| VMP-02-42 | 10/17/2012 | 1214 | 2.57 | 0.16 | NM | NM | NM | NM | NM | NM | NM | NM | Screen submerged. |
| VMP-02-42 | 11/20/2012 | 1457 | -0.27 | NM | NM | NM | NM | NM | NM | NM | NM | NM | Screen submerged. |
| VMP-02-42 | 12/19/2012 | 915 | -1.71 | -0.54 | OVR | OVR | 4.2 | 3.6 | 52.7 | 1000000 | 575000 | 425000 | |
| VMP-02-42 | 1/16/2013 | 1425 | 0.30 | -0.02 | OVR | OVR | 5.2 | 0.9 | 40.3 | 1000000 | 1000000 | 0.0 | |
| VMP-02-42 | 2/26/2013 | 925 | 0.41 | 0.26 | OVR | OVR | 5.6 | 2.0 | 30.3 | 548000 | 320000 | 228000 | |
| VMP-02-42 | 3/21/2013 | 1326 | 0.11 | 0.30 | OVR | OVR | 6.4 | 0.9 | 28.8 | 1000000 | 680000 | 320000 | |

SEE LAST PAGE OF TABLE FOR NOTES

**TABLE 10**
**SVE SYSTEM MONTHLY MONITORING - VMP SAMPLING DATA**

| Sample ID | Date | Initial Reading Time (24-Hour) | Vacuum/Pressure | | Fixed Gases | | | | Soil Vapor Concentrations | | | | Comments |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | Initial Reading (Inches of $H_2O$) | Stabilized Reading (Inches of $H_2O$) | CH4 (%) | LEL (%) | $CO_2$ (%) | $O_2$ (%) | PID (ppmv) | THC (ppmv) | CH4 (ppmv) | PHC (ppmv) | |
| VMP-03-5 | 2/15/2012 | 1555 | -0.28 | -0.27 | 0.0 | 0.0 | 1.1 | 19.9 | 0.3 | 2.5 | 0.0 | 2.5 | |
| VMP-03-5 | 2/16/2012 | 1617 | -0.39 | -0.36 | 0.0 | 0.0 | 1.1 | 20.6 | 0.3 | 5.5 | 5.5 | 0 | |
| VMP-03-5 | 2/17/2012 | 936 | -0.35 | -0.30 | 0.0 | 0.0 | 1.2 | 20.3 | 0.3 | 1.2 | 0.0 | 1.2 | |
| VMP-03-5 | 2/20/2012 | 949 | -0.35 | -0.35 | 0.0 | 0.0 | 1.0 | 20.3 | 0.3 | 2.0 | 0.0 | 2.0 | |
| VMP-03-5 | 2/21/2012 | 853 | -0.50 | -0.45 | 0.0 | 0.0 | 0.9 | 20.5 | 0.3 | 2.1 | 0.0 | 2.1 | |
| VMP-03-5 | 2/22/2012 | 924 | -0.79 | - 0.20 | 0.0 | 0.0 | 1.0 | 20.7 | 0.1 | 0.0 | 0.0 | 0.0 | |
| VMP-03-5 | 2/29/2012 | 920 | -0.17 | - 0.23 | 0.0 | 0.0 | 0.9 | 20.1 | 0.2 | 0.0 | 0.0 | 0.0 | |
| VMP-03-5 | 3/21/2012 | 1513 | -0.03 | - 0.26 | 0.0 | 0.0 | 1.1 | 18.7 | 0.4 | 0.0 | 0.0 | 0.0 | |
| VMP-03-5 | 4/18/2012 | 1404 | -0.14 | -0.11 | 0.0 | 0.0 | 1.1 | 18.6 | 1.5 | 5.7 | 0.0 | 5.7 | |
| VMP-03-5 | 5/16/2012 | 954 | -0.19 | -0.19 | 0.0 | 0.0 | 1.1 | 20.0 | 0.2 | 0.9 | 0.0 | 0.9 | |
| VMP-03-5 | 6/20/2012 | 1511 | -0.13 | -0.12 | 0.0 | 0.0 | 3.3 | 18.0 | 1.1 | 6.1 | 0.1 | 6.0 | |
| VMP-03-5 | 7/18/2012 | 1448 | -0.03 | -0.02 | 0.0 | 0.0 | 0.2 | 20.5 | 0.6 | 7.3 | 5.2 | 2.1 | |
| VMP-03-5 | 8/15/2012 | 1416 | 0.00 | 0.00 | 0.0 | 0.0 | 0.2 | 20.7 | 0.6 | 4.7 | 0.0 | 4.7 | |
| VMP-03-5 | 9/19/2012 | 1023 | -0.28 | -0.25 | 0.0 | 0.0 | 0.9 | 20.2 | 0.7 | 5.5 | 0.0 | 5.5 | |
| VMP-03-5 | 10/17/2012 | 1235 | -0.31 | -0.10 | 0.0 | 0.0 | 0.3 | 20.4 | 0.7 | 1.9 | 0.0 | 1.9 | |
| VMP-03-5 | 11/20/2012 | 1405 | -0.14 | -0.15 | 0.0 | 0.0 | 0.2 | 20.7 | 0.2 | 2.4 | 0.0 | 2.4 | |
| VMP-03-5 | 12/19/2012 | 1100 | -0.14 | -0.10 | 0.0 | 0.0 | 0.1 | 20.7 | 0.1 | 1.1 | 0.0 | 1.1 | |
| VMP-03-5 | 1/16/2013 | 1455 | -0.09 | -0.11 | 0.0 | 0.0 | 0.1 | 20.8 | 0.1 | 2.8 | 0.0 | 2.8 | |
| VMP-03-5 | 2/26/2013 | 950 | -0.30 | -0.22 | 0.0 | 0.0 | 0.2 | 20.6 | 0.1 | 1.9 | 0.0 | 1.9 | |
| VMP-03-5 | 3/21/2013 | 1035 | 0.00 | -0.83 | 0.0 | 0.0 | 0.0 | 20.9 | 0.1 | 1.5 | 0.0 | 1.5 | |
| VMP-03-10 | 2/15/2012 | 1553 | -0.30 | -0.25 | 0.0 | 0.0 | 1.8 | 17.7 | 0.3 | 6.3 | 0.8 | 5.5 | |
| VMP-03-10 | 2/16/2012 | 1618 | -0.45 | -0.41 | 0.0 | 0.0 | 1.4 | 19.4 | 1.9 | 9.2 | 5.7 | 3.5 | |
| VMP-03-10 | 2/17/2012 | 937 | -0.52 | -0.34 | 0.0 | 0.0 | 1.3 | 19.6 | 1.0 | 4.3 | 0.0 | 4.3 | |
| VMP-03-10 | 2/20/2012 | 950 | -0.48 | -0.42 | 0.0 | 0.0 | 1.0 | 19.9 | 0.8 | 3.2 | 0.0 | 3.2 | |
| VMP-03-10 | 2/21/2012 | 855 | -0.62 | -0.59 | 0.0 | 0.0 | 0.8 | 20.2 | 0.7 | 2.5 | 0.0 | 2.5 | |
| VMP-03-10 | 2/22/2012 | 924 | -0.24 | - 0.26 | 0.0 | 0.0 | 0.8 | 20.4 | 0.4 | 2.5 | 0.0 | 2.5 | |
| VMP-03-10 | 2/29/2012 | 921 | 0.00 | -0.32 | 0.0 | 0.0 | 1.0 | 19.2 | 0.1 | 4.9 | 0.0 | 4.9 | |
| VMP-03-10 | 3/21/2012 | 1516 | -0.05 | - 0.19 | 0.0 | 0.0 | 0.9 | 18.3 | 0.8 | 0.0 | 0.0 | 0.0 | |
| VMP-03-10 | 4/18/2012 | 1405 | -0.15 | -0.12 | 0.0 | 0.0 | 1.6 | 18.4 | 0.9 | 4.9 | 0.0 | 4.9 | |
| VMP-03-10 | 5/16/2012 | 1006 | -0.24 | -0.28 | 0.0 | 0.0 | 2.0 | 18.7 | 0.3 | 0.5 | 0.0 | 0.5 | |
| VMP-03-10 | 6/20/2012 | 1512 | -0.30 | -0.30 | 0.0 | 0.0 | 0.3 | 20.8 | 1.5 | 10.6 | 4.3 | 6.4 | |
| VMP-03-10 | 7/18/2012 | 1452 | -0.10 | -0.08 | 0.0 | 0.0 | 1.8 | 19.0 | 1.0 | 4.3 | 0.0 | 4.3 | |
| VMP-03-10 | 8/15/2012 | 1417 | 0.00 | -0.10 | 0.0 | 0.0 | 1.4 | 19.6 | 0.5 | 2.8 | 0.0 | 2.8 | |
| VMP-03-10 | 9/19/2012 | 1024 | -0.33 | -0.22 | 0.0 | 0.0 | 0.7 | 20.3 | 1.0 | 4.2 | 0.0 | 4.2 | |
| VMP-03-10 | 10/17/2012 | 1236 | -0.18 | -0.19 | 0.0 | 0.0 | 0.5 | 20.0 | 0.7 | 1.3 | 0.0 | 1.3 | |
| VMP-03-10 | 11/20/2012 | 1417 | -0.20 | -0.21 | 0.0 | 0.0 | 0.5 | 20.4 | 0.2 | 2.0 | 0.0 | 2.0 | |
| VMP-03-10 | 12/19/2012 | 1115 | -0.17 | -0.11 | 0.0 | 0.0 | 0.5 | 20.4 | 0.2 | 0.5 | 0.0 | 0.5 | |
| VMP-03-10 | 1/16/2013 | 1510 | -0.15 | -0.17 | 0.0 | 0.0 | 0.5 | 20.4 | 0.1 | 1.8 | 0.0 | 1.8 | |
| VMP-03-10 | 2/26/2013 | 955 | -0.31 | -0.37 | 0.0 | 0.0 | 0.7 | 20.2 | 0.2 | 0.4 | 0.0 | 0.4 | |
| VMP-03-10 | 3/21/2013 | 1039 | -0.63 | -0.56 | 0.0 | 0.0 | 0.3 | 20.7 | 0.4 | 1.2 | 0.0 | 1.2 | |

SEE LAST PAGE OF TABLE FOR NOTES

**TABLE 10**
**SVE SYSTEM MONTHLY MONITORING - VMP SAMPLING DATA**

| Sample ID | Date | Initial Reading Time (24-Hour) | Vacuum/Pressure | | Fixed Gases | | | | Soil Vapor Concentrations | | | | Comments |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | Initial Reading (Inches of $H_2O$) | Stabilized Reading (Inches of $H_2O$) | CH4 (%) | LEL (%) | $CO_2$ (%) | $O_2$ (%) | PID (ppmv) | THC (ppmv) | CH4 (ppmv) | PHC (ppmv) | |
| VMP-03-22 | 2/15/2012 | 1558 | -0.33 | -0.30 | 0.0 | 0.0 | 6.3 | 14.3 | 0.8 | 5.5 | 0.6 | 5.0 | |
| VMP-03-22 | 2/16/2012 | 1619 | -1.14 | -0.77 | 0.0 | 0.0 | 7.1 | 13.4 | 2.1 | 6.3 | 3.0 | 3.4 | |
| VMP-03-22 | 2/17/2012 | 938 | -0.43 | -0.55 | 0.0 | 0.0 | 7.7 | 13.7 | 0.9 | 2.8 | 0.0 | 2.8 | |
| VMP-03-22 | 2/20/2012 | 951 | -1.22 | -0.95 | 0.0 | 0.0 | 5.6 | 17.1 | 0.8 | 3.9 | 0.0 | 3.9 | |
| VMP-03-22 | 2/21/2012 | 854 | -2.27 | -1.57 | 0.0 | 0.0 | 4.8 | 17.0 | 0.5 | 5.0 | 0.0 | 5.0 | |
| VMP-03-22 | 2/22/2012 | 923 | -0.22 | - 0.07 | 0.0 | 0.0 | 5.8 | 16.4 | 0.4 | 2.7 | 0.0 | 2.7 | |
| VMP-03-22 | 2/29/2012 | 922 | -0.27 | - 0.04 | 0.0 | 1.0 | 4.7 | 16.2 | 1.4 | 478 | 440 | 38.0 | |
| VMP-03-22 | 3/21/2012 | 1516 | -0.29 | -0.20 | 0.0 | 0.0 | 1.6 | 19.7 | 0.4 | 0.0 | 0.0 | 0.0 | |
| VMP-03-22 | 4/18/2012 | 1406 | -0.15 | 0.00 | 0.0 | 0.0 | 0.0 | 20.9 | 0.2 | 5.1 | 0.0 | 5.1 | |
| VMP-03-22 | 5/16/2012 | 1010 | -0.35 | -0.35 | 0.0 | 0.0 | 0.9 | 20.2 | 0.5 | 1.0 | 0.0 | 1.0 | |
| VMP-03-22 | 6/20/2012 | 1513 | -0.14 | -0.04 | 0.0 | 0.0 | 0.9 | 20.3 | 1.0 | 5.2 | 2.1 | 3.1 | |
| VMP-03-22 | 7/18/2012 | 1449 | -0.14 | -0.12 | 0.0 | 0.0 | 0.8 | 20.1 | 0.8 | 3.7 | 0.0 | 3.7 | |
| VMP-03-22 | 8/15/2012 | 1418 | -0.15 | -0.14 | 0.0 | 0.0 | 1.3 | 19.7 | 0.8 | 5.6 | 0.0 | 5.6 | |
| VMP-03-22 | 9/19/2012 | 1025 | -0.44 | -0.40 | 0.0 | 0.0 | 3.6 | 16.8 | 1.2 | 5.0 | 0.0 | 5.0 | |
| VMP-03-22 | 10/17/2012 | 1236 | -0.28 | -0.28 | 0.0 | 0.0 | 3.1 | 17.6 | 0.8 | 1.8 | 0.0 | 1.8 | |
| VMP-03-22 | 11/20/2012 | 1421 | -0.27 | -0.29 | 0.0 | 0.0 | 2.8 | 18.2 | 0.2 | 2.1 | 0.0 | 2.1 | |
| VMP-03-22 | 12/19/2012 | 1120 | -0.22 | -0.12 | 0.0 | 0.0 | 2.8 | 18.3 | 0.2 | 0.3 | 0.0 | 0.3 | |
| VMP-03-22 | 1/16/2013 | 1515 | -0.19 | -0.22 | 0.0 | 0.0 | 3.5 | 16.6 | 0.1 | 6.8 | 4.3 | 2.5 | |
| VMP-03-22 | 2/26/2013 | 1005 | -0.32 | -0.38 | 0.0 | 0.0 | 6.9 | 12.5 | 0.5 | 16.9 | 16.0 | 0.9 | |
| VMP-03-22 | 3/21/2013 | 1043 | -0.72 | -0.68 | 0.0 | 0.0 | 1.4 | 20.0 | 0.4 | 0.4 | 0.0 | 0.4 | |
| VMP-03-31.5 | 2/15/2012 | 1559 | -0.40 | -0.34 | OVR | OVR | 6.4 | 1.7 | 91.0 | 1000000 | 860000 | 140000 | |
| VMP-03-31.5 | 2/16/2012 | 1620 | -0.57 | -0.41 | OVR | OVR | 6.4 | 4.2 | 107 | 889000 | 231000 | 658000 | |
| VMP-03-31.5 | 2/17/2012 | 939 | -1.29 | -0.35 | OVR | OVR | 6.5 | 2.1 | 103 | 970000 | 517000 | 453000 | |
| VMP-03-31.5 | 2/20/2012 | 952 | -0.50 | -0.34 | OVR | OVR | 5.9 | 4.6 | 105 | 948000 | 279000 | 669000 | |
| VMP-03-31.5 | 2/21/2012 | 856 | -0.48 | -0.48 | OVR | OVR | 2.4 | 14.6 | 155 | 432000 | 88520 | 343480 | |
| VMP-03-31.5 | 2/22/2012 | 924 | -0.20 | - 0.25 | OVR | OVR | 4.4 | 7.3 | 109 | 930000 | 302000 | 628000 | |
| VMP-03-31.5 | 2/29/2012 | 923 | -0.62 | - 0.80 | OVR | OVR | 5.5 | 4.8 | 107 | 835000 | 213000 | 622000 | |
| VMP-03-31.5 | 3/21/2012 | 1515 | -0.05 | -0.15 | OVR | OVR | 7.2 | 1.7 | 99.0 | 1000000 | 256000 | 744000 | |
| VMP-03-31.5 | 4/18/2012 | 1407 | -0.20 | -0.08 | OVR | OVR | 6.2 | 1.4 | 115 | 1000000 | 238000 | 762000 | |
| VMP-03-31.5 | 5/16/2012 | 1001 | -1.19 | -1.16 | OVR | OVR | 4.2 | 9.7 | 175 | 133000 | 65900 | 67100 | |
| VMP-03-31.5 | 6/20/2012 | 1514 | -0.27 | -0.26 | OVR | OVR | 4.6 | 5.4 | 175 | 100000 | 40000 | 60000 | |
| VMP-03-31.5 | 7/18/2012 | 1450 | -0.41 | -0.37 | OVR | OVR | 5.9 | 5.5 | 110 | 129000 | 40000 | 89000 | |
| VMP-03-31.5 | 8/15/2012 | 1419 | -0.48 | -0.39 | OVR | OVR | 9.0 | 1.5 | 197 | 45600 | 26800 | 18800 | |
| VMP-03-31.5 | 9/19/2012 | 1026 | -1.45 | -1.27 | OVR | OVR | 8.7 | 3.4 | 243 | 38300 | 17100 | 21200 | |
| VMP-03-31.5 | 10/17/2012 | 1237 | -0.94 | -0.85 | 39.1 | OVR | 6.5 | 8.2 | 249 | 15200 | 10400 | 4800 | |
| VMP-03-31.5 | 11/20/2012 | 1409 | -0.82 | -0.86 | 2.2 | 45.0 | 4.7 | 11.8 | 165 | 2800 | 1400 | 1400 | |
| VMP-03-31.5 | 12/19/2012 | 1105 | -0.90 | -0.46 | 0.2 | 5.0 | 3.5 | 15.3 | 55.6 | 370 | 47.7 | 322 | |
| VMP-03-31.5 | 1/16/2013 | 1500 | -0.35 | -0.56 | 60.0 | OVR | 9.6 | 1.8 | 295 | 32000 | 17900 | 14100 | |
| VMP-03-31.5 | 2/26/2013 | 1000 | -0.46 | -0.59 | OVR | OVR | 10.1 | 0.9 | 190 | 58700 | 25300 | 33400 | |
| VMP-03-31.5 | 3/21/2013 | 1047 | -1.24 | -1.50 | 44.0 | OVR | 9.5 | 2.7 | 212 | 23700 | 16000 | 7700 | |

SEE LAST PAGE OF TABLE FOR NOTES

**TABLE 10**
**SVE SYSTEM MONTHLY MONITORING - VMP SAMPLING DATA**

| Sample ID | Date | Initial Reading Time (24-Hour) | Vacuum/Pressure | | Fixed Gases | | | | Soil Vapor Concentrations | | | | Comments |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | Initial Reading (Inches of $H_2O$) | Stabilized Reading (Inches of $H_2O$) | CH4 (%) | LEL (%) | $CO_2$ (%) | $O_2$ (%) | PID (ppmv) | THC (ppmv) | CH4 (ppmv) | PHC (ppmv) | |
| VMP-03-39 | 2/15/2012 | 1557 | -1.28 | NM | NM | NM | NM | NM | NM | NM | NM | NM | Screen submerged. |
| VMP-03-39 | 2/16/2012 | 1621 | -12.41 | NM | NM | NM | NM | NM | NM | NM | NM | NM | Screen submerged. |
| VMP-03-39 | 2/17/2012 | 940 | -96.22 | NM | NM | NM | NM | NM | NM | NM | NM | NM | Screen submerged. |
| VMP-03-39 | 2/20/2012 | 952 | NM | NM | NM | NM | NM | NM | NM | NM | NM | NM | Screen submerged. |
| VMP-03-39 | 2/21/2012 | 857 | -60.70 | NM | NM | NM | NM | NM | NM | NM | NM | NM | Screen submerged. |
| VMP-03-39 | 2/22/2012 | 925 | -0.14 | NM | NM | NM | NM | NM | NM | NM | NM | NM | Screen submerged. |
| VMP-03-39 | 2/29/2012 | 924 | 3.27 | NM | NM | NM | NM | NM | NM | NM | NM | NM | Screen submerged. |
| VMP-03-39 | 3/21/2012 | NA | NM | NM | NM | NM | NM | NM | NM | NM | NM | NM | Screen submerged. |
| VMP-03-39 | 4/18/2012 | 1408 | 0.00 | 0.00 | NM | NM | NM | NM | NM | NM | NM | NM | Screen submerged. |
| VMP-03-39 | 5/16/2012 | 1015 | 0.00 | NM | NM | NM | NM | NM | NM | NM | NM | NM | Screen submerged. |
| VMP-03-39 | 6/20/2012 | 1515 | 0.02 | 0.01 | NM | NM | NM | NM | NM | NM | NM | NM | Screen submerged. |
| VMP-03-39 | 7/18/2012 | 1452 | 0.04 | NM | NM | NM | NM | NM | NM | NM | NM | NM | Screen submerged. |
| VMP-03-39 | 8/15/2012 | 1420 | -0.27 | -0.19 | NM | NM | NM | NM | NM | NM | NM | NM | Screen submerged. |
| VMP-03-39 | 9/19/2012 | 1027 | -1.41 | -1.19 | OVR | OVR | 7.9 | 2.5 | 260 | 38100 | 34600 | 3500 | |
| VMP-03-39 | 10/17/2012 | 1424 | -3.03 | -0.84 | OVR | OVR | 8.8 | 1.3 | 226 | 50600 | 30300 | 20300 | |
| VMP-03-39 | 11/20/2012 | 1413 | -0.83 | -0.87 | OVR | OVR | 9.2 | 1.2 | 310 | 47900 | 22700 | 25200 | |
| VMP-03-39 | 12/19/2012 | 1110 | -0.93 | -0.43 | OVR | OVR | 7.9 | 2.1 | 240 | 450000 | 205000 | 245000 | |
| VMP-03-39 | 1/16/2013 | 1505 | -0.31 | -0.53 | OVR | OVR | 9.0 | 0.8 | 220 | 225000 | 74800 | 150200 | |
| VMP-03-39 | 2/26/2013 | 950 | -0.88 | -0.45 | 19.0 | OVR | 0.8 | 19.5 | 160 | 12000 | 4700 | 7300 | Tedlar results are suspect. |
| VMP-03-39 | 3/21/2013 | 1051 | -1.81 | -1.40 | OVR | OVR | 9.5 | 0.8 | 184 | 96300 | 46200 | 50100 | |
| VMP-04-5 | 2/1/2012 | 1708 | -0.15 | -0.15 | 0.0 | 0.0 | 1.2 | 20.1 | 0.6 | 2.3 | 0.0 | 2.3 | |
| VMP-04-5 | 2/2/2012 | 1054 | -0.17 | -0.14 | 0.0 | 0.0 | 0.8 | 20.9 | 0.6 | 1.2 | 0.0 | 1.2 | |
| VMP-04-5 | 2/7/2012 | 859 | -0.15 | -0.15 | 0.0 | 0.0 | 0.4 | 20.9 | 0.2 | 0.0 | 0.0 | 0.0 | |
| VMP-04-5 | 2/10/2012 | 830 | -0.11 | -0.15 | 0.0 | 0.0 | 0.2 | 20.9 | 2.0 | 10.6 | 5.8 | 4.8 | |
| VMP-04-5 | 2/13/2012 | 910 | -0.13 | -0.11 | 0.0 | 0.0 | 0.2 | 20.9 | 0.1 | 0.0 | 0.0 | 0.0 | |
| VMP-04-5 | 2/15/2012 | 1120 | -0.12 | -0.12 | 0.0 | 0.0 | 0.2 | 20.8 | 0.4 | 0.0 | 0.0 | 0.0 | |
| VMP-04-5 | 2/22/2012 | 1327 | -0.05 | - 0.05 | 0.0 | 0.0 | 0.4 | 20.8 | 1.6 | 4.0 | 0.0 | 4.0 | |
| VMP-04-5 | 2/29/2012 | 1031 | -0.12 | - 0.03 | 0.0 | 0.0 | 0.5 | 20.5 | 3.3 | 9.7 | 0.8 | 8.9 | |
| VMP-04-5 | 3/21/2012 | 1540 | -0.05 | -0.12 | 0.0 | 0.0 | 0.5 | 20.0 | 0.1 | 0.0 | 0.0 | 0.0 | |
| VMP-04-5 | 4/18/2012 | 1342 | -0.06 | -0.06 | 0.0 | 0.0 | 0.4 | 20.4 | 0.1 | 3.1 | 0.0 | 3.1 | |
| VMP-04-5 | 5/16/2012 | 1133 | -0.20 | -0.22 | 0.0 | 0.0 | 2.4 | 18.0 | 0.6 | 0.0 | 0.0 | 0.0 | |
| VMP-04-5 | 6/20/2012 | 1427 | -0.08 | NM | 0.0 | 0.0 | 2.3 | 18.3 | 1.0 | 5.4 | 0.0 | 5.4 | |
| VMP-04-5 | 7/18/2012 | 1512 | -0.04 | -0.02 | 0.0 | 0.0 | 1.5 | 18.6 | 0.5 | 3.6 | 0.0 | 3.6 | |
| VMP-04-5 | 8/15/2012 | 1509 | -0.27 | -0.23 | 0.0 | 0.0 | 1.6 | 18.6 | 0.9 | 4.8 | 0.0 | 4.8 | |
| VMP-04-5 | 9/19/2012 | 1113 | -0.08 | -0.08 | 0.0 | 0.0 | 0.8 | 20.1 | 0.8 | 7.5 | 7.1 | 0.4 | |
| VMP-04-5 | 10/17/2012 | 1310 | -0.07 | -0.06 | 0.0 | 0.0 | 0.6 | 20.1 | 0.6 | 2.0 | 0.0 | 2.0 | |
| VMP-04-5 | 11/20/2012 | 1438 | -0.06 | -0.08 | 0.0 | 0.0 | 0.4 | 20.4 | 0.2 | 0.8 | 0.0 | 0.8 | |
| VMP-04-5 | 12/19/2012 | 1030 | -0.07 | -0.05 | 0.0 | 0.0 | 0.4 | 20.4 | 0.4 | 0.5 | 0.0 | 0.5 | |
| VMP-04-5 | 1/16/2013 | 1525 | -0.18 | -0.08 | 0.0 | 0.0 | 0.2 | 20.7 | 0.1 | 1.7 | 0.0 | 1.7 | |
| VMP-04-5 | 2/26/2013 | 1031 | -0.08 | -0.16 | 0.0 | 0.0 | 0.3 | 20.5 | 0.1 | 0.8 | 0.0 | 0.8 | |
| VMP-04-5 | 3/21/2013 | 930 | -0.15 | -0.18 | 0.0 | 0.0 | 0.2 | 20.8 | 0.1 | 1.7 | 0.0 | 1.7 | |

SEE LAST PAGE OF TABLE FOR NOTES

**TABLE 10**
**SVE SYSTEM MONTHLY MONITORING - VMP SAMPLING DATA**

| Sample ID | Date | Initial Reading Time (24-Hour) | Vacuum/Pressure | | Fixed Gases | | | | Soil Vapor Concentrations | | | | Comments |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | Initial Reading (Inches of $H_2O$) | Stabilized Reading (Inches of $H_2O$) | CH4 (%) | LEL (%) | $CO_2$ (%) | $O_2$ (%) | PID (ppmv) | THC (ppmv) | CH4 (ppmv) | PHC (ppmv) | |
| VMP-04-12 | 2/1/2012 | 1713 | -0.23 | -0.25 | 0.0 | 0.0 | 3.6 | 14.6 | 1.1 | 3.8 | 0.0 | 3.8 | |
| VMP-04-12 | 2/2/2012 | 1102 | -0.27 | -0.23 | 0.0 | 0.0 | 2.5 | 16.5 | 0.9 | 2.3 | 0.0 | 2.3 | |
| VMP-04-12 | 2/7/2012 | 904 | -0.23 | -0.25 | 0.0 | 0.0 | 1.2 | 18.2 | 0.2 | 1.6 | 0.0 | 1.6 | |
| VMP-04-12 | 2/10/2012 | 831 | -0.18 | -0.24 | 0.0 | 0.0 | 1.4 | 17.6 | 2.0 | 10.6 | 6.7 | 3.8 | |
| VMP-04-12 | 2/13/2012 | 911 | -0.23 | -0.16 | 0.0 | 0.0 | 1.3 | 18.4 | 0.2 | 0.0 | 0.0 | 0.0 | |
| VMP-04-12 | 2/15/2012 | 1121 | -0.18 | -0.20 | 0.0 | 0.0 | 1.4 | 18.3 | 0.6 | 1.3 | 0.0 | 1.3 | |
| VMP-04-12 | 2/22/2012 | 1325 | -0.09 | - 0.09 | 0.0 | 0.0 | 2.1 | 17.6 | 2.4 | 7.3 | 2.1 | 5.2 | |
| VMP-04-12 | 2/29/2012 | 1032 | -0.08 | - 0.05 | 0.0 | 0.0 | 2.0 | 18.0 | 3.8 | 20.2 | 9.5 | 10.8 | |
| VMP-04-12 | 3/21/2012 | 1540 | -0.09 | -0.16 | 0.0 | 0.0 | 2.7 | 15.9 | 0.5 | 0.0 | 0.0 | 0.0 | |
| VMP-04-12 | 4/18/2012 | 1343 | -0.09 | -0.10 | 0.0 | 0.0 | 1.5 | 19.0 | 0.5 | 6.0 | 0.0 | 6.0 | |
| VMP-04-12 | 5/16/2012 | 1138 | -0.30 | -0.30 | 0.0 | 0.0 | 2.8 | 17.7 | 0.8 | 0.0 | 0.0 | 0.0 | |
| VMP-04-12 | 6/20/2012 | 1428 | -0.15 | NM | 0.0 | 0.0 | 3.0 | 17.6 | 1.0 | 1.9 | 0.0 | 1.9 | |
| VMP-04-12 | 7/18/2012 | 1517 | -0.09 | -0.08 | 0.0 | 0.0 | 2.5 | 17.5 | 0.7 | 3.1 | 0.0 | 3.1 | |
| VMP-04-12 | 8/15/2012 | 1509 | -0.07 | -0.10 | 0.0 | 0.0 | 2.9 | 17.9 | 1.3 | 3.4 | 0.0 | 3.4 | |
| VMP-04-12 | 9/19/2012 | 1114 | -0.21 | -0.19 | 0.0 | 0.0 | 1.7 | 19.2 | 0.8 | 4.0 | 0.0 | 4.0 | |
| VMP-04-12 | 10/17/2012 | 1311 | -0.22 | -0.17 | 0.0 | 0.0 | 1.0 | 19.7 | 1.0 | 1.6 | 0.0 | 1.6 | |
| VMP-04-12 | 11/20/2012 | 1426 | -0.25 | -0.24 | 0.0 | 0.0 | 0.7 | 20.1 | 0.6 | 1.4 | 0.0 | 1.4 | |
| VMP-04-12 | 12/19/2012 | 1035 | -0.14 | -0.10 | 0.0 | 0.0 | 0.8 | 20.0 | 0.3 | 0.5 | 0.0 | 0.5 | |
| VMP-04-12 | 1/16/2013 | 1530 | -0.10 | -0.19 | 0.0 | 0.0 | 0.6 | 20.3 | 0.2 | 2.2 | 0.0 | 2.2 | |
| VMP-04-12 | 2/26/2013 | 1036 | -0.14 | -0.01 | 0.0 | 0.0 | 0.8 | 19.9 | 0.3 | 2.9 | 0.0 | 2.9 | |
| VMP-04-12 | 3/21/2013 | 936 | -0.40 | 0.00 | 0.0 | 0.0 | 0.3 | 20.7 | 0.2 | 1.2 | 0.0 | 1.2 | |
| VMP-04-23.5 | 2/1/2012 | 1717 | -0.38 | -0.42 | OVR | OVR | 9.0 | 0.9 | 272 | 300000 | 79000 | 221000 | |
| VMP-04-23.5 | 2/2/2012 | 1107 | -0.85 | -0.67 | OVR | OVR | 8.7 | 3.0 | 259 | 1000000 | 141000 | 859000 | |
| VMP-04-23.5 | 2/7/2012 | 909 | -0.80 | -0.74 | OVR | OVR | 8.3 | 3.5 | 223 | 300000 | 79000 | 221000 | |
| VMP-04-23.5 | 2/10/2012 | 832 | -0.98 | -4.14 | OVR | OVR | 9.6 | 1.3 | 275 | 136000 | 82000 | 54000 | |
| VMP-04-23.5 | 2/13/2012 | 912 | -1.03 | -0.85 | OVR | OVR | 10.0 | 2.0 | 298 | 71500 | 34720 | 36780 | |
| VMP-04-23.5 | 2/15/2012 | 1122 | -1.24 | -1.01 | OVR | OVR | 10.1 | 2.1 | 359 | 93400 | 28000 | 65400 | |
| VMP-04-23.5 | 2/22/2012 | 1328 | -0.99 | - 0.58 | OVR | OVR | 10.6 | 2.3 | 431 | 80900 | 21510 | 59390 | |
| VMP-04-23.5 | 2/29/2012 | 1033 | -0.69 | - 0.57 | OVR | OVR | 11.1 | 1.8 | 527 | 71280 | 14130 | 57150 | |
| VMP-04-23.5 | 3/21/2012 | 1540 | -0.36 | -0.46 | OVR | OVR | 10.5 | 2.4 | 442 | 86300 | 16900 | 69400 | |
| VMP-04-23.5 | 4/18/2012 | 1344 | -0.68 | -0.60 | OVR | OVR | 10.0 | 1.0 | 557 | 61300 | 14300 | 47000 | |
| VMP-04-23.5 | 5/16/2012 | 1142 | -1.42 | -1.38 | OVR | OVR | 10.0 | 3.9 | 660 | 31000 | 9000 | 22000 | |
| VMP-04-23.5 | 6/20/2012 | 1429 | -0.80 | NM | OVR | OVR | 12.0 | 0.7 | 916 | 25900 | 9500 | 16400 | |
| VMP-04-23.5 | 7/18/2012 | 1515 | -0.93 | -0.92 | OVR | OVR | 11.2 | 2.4 | 554 | 29300 | 4250 | 25050 | |
| VMP-04-23.5 | 8/15/2012 | 1510 | -0.93 | -0.99 | OVR | OVR | 12.5 | 2.5 | 412 | 18100 | 6000 | 12100 | |
| VMP-04-23.5 | 9/19/2012 | 1115 | -1.92 | -1.82 | OVR | OVR | 10.7 | 9.7 | 680 | 18100 | 4100 | 14000 | |
| VMP-04-23.5 | 10/17/2012 | 1314 | -1.60 | -1.51 | 60.5 | OVR | 8.6 | 12.4 | 469 | 6660 | 2890 | 3770 | |
| VMP-04-23.5 | 11/20/2012 | 1430 | -1.32 | -1.42 | 3.7 | 74.0 | 5.8 | 14.1 | 330 | 3300 | 940 | 2360 | |
| VMP-04-23.5 | 12/19/2012 | 1040 | -1.37 | -0.90 | 0.8 | 16.0 | 5.8 | 14.1 | 120 | 2500 | 690 | 1810 | |
| VMP-04-23.5 | 1/16/2013 | 1535 | -0.68 | -1.40 | 1.3 | 26.0 | 5.9 | 13.9 | 155 | 2150 | 730 | 1420 | |
| VMP-04-23.5 | 2/26/2013 | 1041 | -0.88 | -0.98 | 3.3 | 66.0 | 8.1 | 11.6 | 180 | 3400 | 650 | 2750 | |
| VMP-04-23.5 | 3/21/2013 | 944 | -2.02 | -2.03 | 1.7 | 36.0 | 4.0 | 16.2 | 152 | 1050 | 210 | 840 | |

SEE LAST PAGE OF TABLE FOR NOTES

**TABLE 10**
**SVE SYSTEM MONTHLY MONITORING - VMP SAMPLING DATA**

| Sample ID | Date | Initial Reading Time (24-Hour) | Vacuum/Pressure | | Fixed Gases | | | | Soil Vapor Concentrations | | | | Comments |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | Initial Reading (Inches of $H_2O$) | Stabilized Reading (Inches of $H_2O$) | CH4 (%) | LEL (%) | $CO_2$ (%) | $O_2$ (%) | PID (ppmv) | THC (ppmv) | CH4 (ppmv) | PHC (ppmv) | |
| VMP-04-39 | 2/1/2012 | 1723 | NM | NM | NM | NM | NM | NM | NM | NM | NM | NM | Screen submerged. |
| VMP-04-39 | 2/2/2012 | 1112 | NM | NM | NM | NM | NM | NM | NM | NM | NM | NM | Screen submerged. |
| VMP-04-39 | 2/7/2012 | 857 | -1.00 | NM | NM | NM | NM | NM | NM | NM | NM | NM | Screen submerged. |
| VMP-04-39 | 2/10/2012 | 833 | -0.99 | NM | NM | NM | NM | NM | NM | NM | NM | NM | Screen submerged. |
| VMP-04-39 | 2/13/2012 | 913 | -2.37 | -0.83 | OVR | OVR | 9.3 | 3.2 | 281 | 116000 | 39100 | 76900 | |
| VMP-04-39 | 2/15/2012 | 1123 | -1.23 | -0.99 | OVR | OVR | 9.8 | 2.4 | 299 | 126000 | 37400 | 88600 | |
| VMP-04-39 | 2/22/2012 | 1328 | -0.59 | - 0.57 | OVR | OVR | 9.4 | 4.4 | 348 | 83900 | 32600 | 51300 | |
| VMP-04-39 | 2/29/2012 | 1034 | -0.74 | - 0.56 | OVR | OVR | 10.8 | 1.5 | 452 | 129000 | 24280 | 104720 | |
| VMP-04-39 | 3/21/2012 | 1540 | -0.36 | -0.37 | OVR | OVR | 11.0 | 1.0 | 396 | 162000 | 32600 | 129400 | |
| VMP-04-39 | 4/18/2012 | 1345 | -0.69 | -0.59 | OVR | OVR | 10.1 | 1.1 | 475 | 136000 | 28000 | 108000 | |
| VMP-04-39 | 5/16/2012 | 1154 | -1.42 | -1.35 | OVR | OVR | 9.2 | 3.2 | 610 | 58200 | 13500 | 44700 | |
| VMP-04-39 | 6/20/2012 | 1430 | -0.80 | NM | OVR | OVR | 8.8 | 5.3 | 724 | 21000 | 10300 | 10700 | |
| VMP-04-39 | 7/18/2012 | 1519 | -0.94 | -0.89 | OVR | OVR | 12.1 | 1.4 | 422 | 54000 | 12200 | 41800 | |
| VMP-04-39 | 8/15/2012 | 1510 | -0.89 | -0.97 | OVR | OVR | 12.0 | 2.2 | 260 | 71200 | 18500 | 52700 | |
| VMP-04-39 | 9/19/2012 | 1116 | -1.94 | -1.78 | OVR | OVR | 10.2 | 9.0 | 359 | 82300 | 16000 | 66300 | |
| VMP-04-39 | 10/17/2012 | 1315 | -1.56 | -1.50 | OVR | OVR | 7.1 | 13.6 | 300 | 66700 | 25100 | 41600 | |
| VMP-04-39 | 11/20/2012 | 1434 | -1.31 | -1.41 | OVR | OVR | 7.0 | 13.4 | 416 | 59800 | 14300 | 45500 | |
| VMP-04-39 | 12/19/2012 | 1045 | -1.37 | -0.90 | OVR | OVR | 8.9 | 11.1 | 660 | 50000 | 12600 | 37400 | |
| VMP-04-39 | 1/16/2013 | 1540 | -0.75 | -1.09 | OVR | OVR | 8.9 | 11.5 | 565 | 45700 | 14300 | 31400 | |
| VMP-04-39 | 2/26/2013 | 1043 | -0.91 | -0.97 | OVR | OVR | 8.9 | 11.8 | 590 | 46300 | 11200 | 35100 | |
| VMP-04-39 | 3/20/2013 | 952 | -2.09 | -2.19 | OVR | OVR | 7.0 | 15.1 | 660 | 26100 | 5500 | 20600 | |
| VMP-05-5 | 2/2/2012 | 1323 | -0.08 | 0.18 | 0.0 | 0.0 | 2.8 | 19.0 | 0.4 | 0.3 | 0.0 | 0.3 | |
| VMP-05-5 | 2/3/2012 | 825 | -0.16 | 0.26 | 0.0 | 0.0 | 2.1 | 19.5 | 0.6 | 1.7 | 0.0 | 1.7 | |
| VMP-05-5 | 2/7/2012 | 812 | -0.13 | -0.06 | 0.0 | 0.0 | 1.4 | 20.5 | 0.4 | 0.0 | 0.0 | 0.0 | |
| VMP-05-5 | 2/13/2012 | 1504 | -0.16 | 0.37 | 0.0 | 0.0 | 1.1 | 20.4 | 0.7 | 5.2 | 2.1 | 3.1 | |
| VMP-05-5 | 2/14/2012 | 1553 | 0.00 | 0.31 | 0.0 | 0.0 | 1.3 | 20.6 | 4.3 | 11.7 | 0.0 | 11.7 | |
| VMP-05-5 | 2/15/2012 | 1240 | -0.08 | -0.06 | 0.0 | 0.0 | 1.0 | 20.6 | 2.2 | 9.3 | 5.4 | 3.9 | |
| VMP-05-5 | 2/22/2012 | 838 | -0.01 | - 0.06 | 0.0 | 0.0 | 0.7 | 20.5 | 0.3 | 2.2 | 0.0 | 2.2 | |
| VMP-05-5 | 2/29/2012 | 817 | -0.07 | - 0.05 | 0.0 | 0.0 | 0.7 | 20.9 | 0.4 | 2.9 | 0.0 | 2.9 | |
| VMP-05-5 | 3/21/2012 | 849 | -0.08 | - 0.06 | 0.0 | 0.0 | 0.6 | 20.5 | 0.1 | 0.0 | 0.0 | 0.0 | |
| VMP-05-5 | 4/18/2012 | 859 | -0.11 | -0.09 | 0.0 | 0.0 | 0.3 | 20.8 | 2.6 | 3.5 | 0.0 | 3.5 | |
| VMP-05-5 | 5/16/2012 | 1151 | -0.11 | -0.09 | 0.0 | 0.0 | 0.3 | 20.6 | 0.8 | 0.0 | 0.0 | 0.0 | |
| VMP-05-5 | 6/20/2012 | 1258 | -0.06 | -0.05 | 0.0 | 0.0 | 0.4 | 20.7 | 1.1 | 3.8 | 0.0 | 3.8 | |
| VMP-05-5 | 7/18/2012 | 1039 | -0.07 | -0.05 | 0.0 | 0.0 | 0.4 | 20.6 | 0.3 | 1.7 | 0.0 | 1.7 | |
| VMP-05-5 | 8/15/2012 | 1000 | -0.06 | -0.05 | 0.0 | 0.0 | 0.4 | 20.5 | 0.8 | 4.3 | 0.0 | 4.3 | |
| VMP-05-5 | 9/19/2012 | 1324 | -0.05 | -0.05 | 0.0 | 0.0 | 0.1 | 20.8 | 0.7 | 1.5 | 0.0 | 1.5 | |
| VMP-05-5 | 10/17/2012 | 1335 | -0.05 | -0.03 | 0.0 | 0.0 | 0.2 | 20.7 | 0.6 | 1.6 | 0.0 | 1.6 | |
| VMP-05-5 | 11/20/2012 | 944 | -0.04 | -0.02 | 0.0 | 0.0 | 0.2 | 20.8 | 0.1 | 0.4 | 0.0 | 0.4 | |
| VMP-05-5 | 12/19/2012 | 919 | -0.05 | -0.08 | 0.0 | 0.0 | 0.2 | 20.7 | 0.1 | 0.3 | 0.0 | 0.3 | |
| VMP-05-5 | 1/16/2013 | 906 | -0.06 | -0.04 | 0.0 | 0.0 | 0.1 | 20.8 | 0.4 | 3.5 | 0.0 | 3.5 | |
| VMP-05-5 | 2/25/2013 | 1030 | -0.05 | -0.03 | 0.0 | 0.0 | 0.1 | 20.8 | 1.5 | 3.0 | 0.0 | 3.0 | |
| VMP-05-5 | 3/21/2013 | 1100 | -0.07 | -0.11 | 0.0 | 0.0 | 0.1 | 20.8 | 1.8 | 2.9 | 0.0 | 2.9 | |

SEE LAST PAGE OF TABLE FOR NOTES

**TABLE 10**
**SVE SYSTEM MONTHLY MONITORING - VMP SAMPLING DATA**

| Sample ID | Date | Initial Reading Time (24-Hour) | Vacuum/Pressure | | Fixed Gases | | | | Soil Vapor Concentrations | | | | Comments |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | Initial Reading (Inches of $H_2O$) | Stabilized Reading (Inches of $H_2O$) | CH4 (%) | LEL (%) | $CO_2$ (%) | $O_2$ (%) | PID (ppmv) | THC (ppmv) | CH4 (ppmv) | PHC (ppmv) | |
| VMP-05-12.5 | 2/2/2012 | 1329 | -0.07 | -0.07 | 0.0 | 0.0 | 4.2 | 17.5 | 0.5 | 0.0 | 0.0 | 0.0 | |
| VMP-05-12.5 | 2/3/2012 | 831 | -0.21 | -0.18 | 0.0 | 0.0 | 3.6 | 18.0 | 0.7 | 0.2 | 0.0 | 0.2 | |
| VMP-05-12.5 | 2/7/2012 | 818 | -0.13 | -0.21 | 0.0 | 0.0 | 2.5 | 19.6 | 0.5 | 0.0 | 0.0 | 0.0 | |
| VMP-05-12.5 | 2/13/2012 | 1505 | -0.09 | -0.07 | 0.0 | 0.0 | 2.2 | 19.8 | 0.4 | 0.0 | 0.0 | 0.0 | |
| VMP-05-12.5 | 2/14/2012 | 1554 | -0.18 | -0.25 | 0.0 | 0.0 | 2.1 | 20.2 | 3.5 | 8.1 | 0.0 | 8.1 | |
| VMP-05-12.5 | 2/15/2012 | 1241 | -0.15 | -0.18 | 0.0 | 0.0 | 1.4 | 20.5 | 1.8 | 8.3 | 4.9 | 3.4 | |
| VMP-05-12.5 | 2/22/2012 | 844 | -0.08 | - 0.10 | 0.0 | 0.0 | 1.1 | 20.3 | 0.4 | 11.4 | 1.6 | 9.8 | |
| VMP-05-12.5 | 2/29/2012 | 823 | -0.14 | - 0.11 | 0.0 | 0.0 | 1.1 | 20.7 | 0.5 | 2.9 | 0.0 | 2.9 | |
| VMP-05-12.5 | 3/21/2012 | 853 | -0.14 | - 0.12 | 0.0 | 0.0 | 0.8 | 20.3 | 0.1 | 0.0 | 0.0 | 0.0 | |
| VMP-05-12.5 | 4/18/2012 | 904 | -0.20 | -0.18 | 0.0 | 0.0 | 0.5 | 20.4 | 0.5 | 2.6 | 0.0 | 2.6 | |
| VMP-05-12.5 | 5/16/2012 | 1151 | -0.22 | -0.19 | 0.0 | 0.0 | 0.5 | 20.4 | 0.4 | 0.0 | 0.0 | 0.0 | |
| VMP-05-12.5 | 6/20/2012 | 1259 | -0.15 | -0.11 | 0.0 | 0.0 | 0.6 | 20.5 | 1.2 | 2.8 | 0.0 | 2.8 | |
| VMP-05-12.5 | 7/18/2012 | 1040 | -0.17 | -0.15 | 0.0 | 0.0 | 0.6 | 20.4 | 0.7 | 2.0 | 0.0 | 2.0 | |
| VMP-05-12.5 | 8/15/2012 | 1005 | -0.15 | -0.15 | 0.0 | 0.0 | 0.7 | 20.7 | 0.6 | 3.3 | 0.0 | 3.3 | |
| VMP-05-12.5 | 9/19/2012 | 1325 | -0.17 | -0.17 | 0.0 | 0.0 | 0.3 | 20.5 | 1.1 | 1.5 | 0.0 | 1.5 | |
| VMP-05-12.5 | 10/17/2012 | 1336 | -0.19 | -0.17 | 0.0 | 0.0 | 0.2 | 20.6 | 0.7 | 1.4 | 0.0 | 1.4 | |
| VMP-05-12.5 | 11/20/2012 | 947 | -0.17 | -0.15 | 0.0 | 0.0 | 0.3 | 20.7 | 0.3 | 0.7 | 0.0 | 0.7 | |
| VMP-05-12.5 | 12/19/2012 | 921 | -0.12 | -0.18 | 0.0 | 0.0 | 0.1 | 20.8 | 0.2 | 0.3 | 0.0 | 0.3 | |
| VMP-05-12.5 | 1/16/2013 | 910 | -0.14 | -0.09 | 0.0 | 0.0 | 0.2 | 20.7 | 0.4 | 2.7 | 0.0 | 2.7 | |
| VMP-05-12.5 | 2/25/2013 | 1030 | -0.12 | -0.08 | 0.0 | 0.0 | 0.1 | 20.8 | 1.1 | 2.8 | 0.0 | 2.8 | |
| VMP-05-12.5 | 3/21/2013 | 1105 | -0.24 | -0.24 | 0.0 | 0.0 | 0.1 | 20.8 | 0.8 | 1.4 | 0.0 | 1.4 | |
| VMP-05-31 | 2/2/2012 | 1334 | -0.14 | -0.27 | OVR | OVR | 11.3 | 1.0 | 229 | 146000 | 53300 | 92700 | |
| VMP-05-31 | 2/3/2012 | 837 | -0.65 | -0.33 | OVR | OVR | 10.8 | 1.5 | 192 | 100000 | 27500 | 72500 | |
| VMP-05-31 | 2/7/2012 | 823 | -0.75 | -0.51 | OVR | OVR | 11.1 | 2.5 | 192 | 59700 | 36140 | 23560 | |
| VMP-05-31 | 2/13/2012 | 1506 | -0.47 | -0.42 | 76.2 | OVR | 11.5 | 1.2 | 251 | 38260 | 20860 | 17400 | |
| VMP-05-31 | 2/14/2012 | 1555 | -1.05 | -1.10 | 68.2 | OVR | 11.6 | 1.3 | 246 | 38900 | 18600 | 20300 | |
| VMP-05-31 | 2/15/2012 | 1242 | -0.70 | -0.62 | 39.5 | OVR | 10.1 | 3.3 | 246 | 24000 | 12600 | 11400 | |
| VMP-05-31 | 2/22/2012 | 848 | -0.53 | - 0.49 | 3.5 | 70.0 | 11.5 | 1.6 | 188 | 6970 | 4020 | 2950 | |
| VMP-05-31 | 2/29/2012 | 828 | -0.66 | - 0.54 | 0.8 | 17.0 | 11.4 | 1.8 | 112 | 1280 | 1080 | 200 | |
| VMP-05-31 | 3/21/2012 | 859 | -0.59 | - 0.53 | 0.1 | 3.0 | 11.3 | 1.2 | 21.7 | 308 | 248 | 60.0 | |
| VMP-05-31 | 4/18/2012 | 908 | -0.88 | -0.87 | 0.0 | 0.0 | 11.4 | 1.7 | 8.4 | 140 | 110 | 30.0 | |
| VMP-05-31 | 5/16/2012 | 1151 | -1.00 | -0.88 | 0.0 | 0.0 | 11.8 | 2.9 | 5.7 | 15.3 | 0.0 | 15.3 | |
| VMP-05-31 | 6/20/2012 | 1300 | -0.78 | -0.58 | 0.0 | 0.0 | 8.2 | 12.3 | 5.0 | 13.7 | 1.4 | 12.3 | |
| VMP-05-31 | 7/18/2012 | 1041 | -0.88 | -0.81 | 0.0 | 0.0 | 6.1 | 15.0 | 2.5 | 11.8 | 8.3 | 3.5 | |
| VMP-05-31 | 8/15/2012 | 1009 | -0.91 | -0.90 | 0.0 | 0.0 | 5.9 | 15.3 | 1.4 | 12.6 | 9.7 | 2.9 | |
| VMP-05-31 | 9/19/2012 | 1326 | -1.04 | -1.02 | 0.0 | 0.0 | 4.6 | 16.2 | 1.2 | 3.9 | 0.0 | 3.9 | |
| VMP-05-31 | 10/17/2012 | 1334 | -1.17 | -1.12 | 0.0 | 0.0 | 4.0 | 17.4 | 0.7 | 6.0 | 5.2 | 0.8 | |
| VMP-05-31 | 11/20/2012 | 950 | -1.23 | -1.19 | 0.0 | 0.0 | 3.8 | 17.6 | 0.7 | 8.6 | 7.9 | 0.7 | |
| VMP-05-31 | 12/19/2012 | 922 | -0.77 | -1.05 | 0.0 | 0.0 | 4.0 | 17.3 | 0.6 | 5.7 | 3.9 | 1.8 | |
| VMP-05-31 | 1/16/2013 | 914 | -0.79 | -0.54 | 0.0 | 0.0 | 3.9 | 17.9 | 0.6 | 5.9 | 1.7 | 4.2 | |
| VMP-05-31 | 2/25/2013 | 1035 | -0.72 | -0.54 | 0.0 | 0.0 | 3.1 | 18.1 | 1.6 | 7.6 | 2.7 | 4.9 | |
| VMP-05-31 | 3/21/2013 | 1112 | -1.46 | -1.34 | 0.0 | 0.0 | 2.3 | 19.2 | 1.2 | 3.2 | 0.0 | 3.2 | |

SEE LAST PAGE OF TABLE FOR NOTES

**TABLE 10**
**SVE SYSTEM MONTHLY MONITORING - VMP SAMPLING DATA**

| Sample ID | Date | Initial Reading Time (24-Hour) | Vacuum/Pressure | | Fixed Gases | | | | Soil Vapor Concentrations | | | | Comments |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | Initial Reading (Inches of $H_2O$) | Stabilized Reading (Inches of $H_2O$) | CH4 (%) | LEL (%) | $CO_2$ (%) | $O_2$ (%) | PID (ppmv) | THC (ppmv) | CH4 (ppmv) | PHC (ppmv) | |
| VMP-05-40 | 2/2/2012 | 1339 | -0.22 | -0.24 | OVR | OVR | 8.8 | 6.6 | 219 | 92000 | 48300 | 43700 | |
| VMP-05-40 | 2/3/2012 | 842 | -0.47 | -0.32 | OVR | OVR | 10.8 | 2.0 | 184 | 64400 | 48000 | 16400 | |
| VMP-05-40 | 2/7/2012 | 829 | -0.61 | -0.50 | 66.8 | OVR | 11.0 | 2.5 | 185 | 32660 | 20650 | 12010 | |
| VMP-05-40 | 2/13/2012 | 1507 | -0.50 | -0.42 | 40.7 | OVR | 11.9 | 1.2 | 251 | 21740 | 13890 | 7850 | |
| VMP-05-40 | 2/14/2012 | 1556 | -1.01 | -1.09 | 31.2 | OVR | 11.8 | 1.5 | 232 | 26400 | 15600 | 10800 | |
| VMP-05-40 | 2/15/2012 | 1243 | -0.77 | -0.62 | 17.5 | OVR | 10.5 | 3.1 | 213 | 16460 | 9230 | 7230 | |
| VMP-05-40 | 2/22/2012 | 854 | -0.58 | - 0.48 | 2.0 | 41.0 | 11.6 | 2.0 | 168 | 5010 | 2410 | 2600 | |
| VMP-05-40 | 2/29/2012 | 833 | -0.64 | - 0.52 | 0.7 | 14.0 | 11.7 | 2.4 | 91.2 | 1150 | 776 | 374 | |
| VMP-05-40 | 3/21/2012 | 907 | -0.58 | - 0.54 | 0.3 | 6.0 | 12.0 | 1.0 | 44.1 | 471 | 329 | 142 | |
| VMP-05-40 | 4/18/2012 | 913 | -0.89 | -0.86 | 0.2 | 4.0 | 12.1 | 1.6 | 26.5 | 533 | 318 | 215 | |
| VMP-05-40 | 5/16/2012 | 1151 | -1.00 | -0.88 | 0.0 | 0.0 | 9.9 | 9.7 | 15.7 | 74.2 | 30.5 | 43.7 | |
| VMP-05-40 | 6/20/2012 | 1301 | -0.78 | -0.57 | 0.0 | 0.0 | 8.1 | 13.3 | 4.9 | 24.6 | 14.6 | 10.0 | |
| VMP-05-40 | 7/18/2012 | 1042 | -0.89 | -0.81 | 0.0 | 0.0 | 6.1 | 15.6 | 2.9 | 29.6 | 21.4 | 8.3 | |
| VMP-05-40 | 8/15/2012 | 1013 | -0.91 | -0.89 | 0.0 | 0.0 | 6.1 | 15.1 | 5.1 | 31.8 | 18.1 | 13.7 | |
| VMP-05-40 | 9/19/2012 | 1327 | -1.04 | -1.01 | 0.0 | 0.0 | 5.0 | 16.2 | 2.3 | 21.0 | 17.8 | 3.2 | |
| VMP-05-40 | 10/17/2012 | 1340 | -1.16 | -1.11 | 0.0 | 0.0 | 4.3 | 17.4 | 2.8 | 49.4 | 40.3 | 9.1 | |
| VMP-05-40 | 11/20/2012 | 953 | -1.23 | -1.20 | 0.0 | 0.0 | 4.1 | 17.5 | 2.5 | 65.2 | 52.9 | 12.4 | |
| VMP-05-40 | 12/19/2012 | 923 | -0.78 | -1.05 | 0.0 | 0.0 | 3.9 | 17.5 | 1.3 | 27.3 | 18.2 | 9.1 | |
| VMP-05-40 | 1/16/2013 | 918 | -0.77 | -0.52 | 0.0 | 0.0 | 4.0 | 17.6 | 0.9 | 22.2 | 16.2 | 6.0 | |
| VMP-05-40 | 2/25/2013 | 1035 | -0.73 | -0.53 | 0.0 | 0.0 | 3.3 | 17.9 | 1.7 | 9.8 | 5.1 | 4.7 | |
| VMP-05-40 | 3/21/2013 | 1119 | -1.43 | -1.37 | 0.0 | 0.0 | 2.9 | 18.7 | 1.2 | 10.3 | 7.7 | 2.6 | |
| VMP-06-5 | 2/2/2012 | 1356 | -0.03 | -0.05 | 0.0 | 0.0 | 0.7 | 20.6 | 0.3 | 4.7 | 0.0 | 4.7 | |
| VMP-06-5 | 2/3/2012 | 900 | -0.06 | -0.05 | 0.0 | 0.0 | 0.4 | 20.8 | 0.5 | 0.5 | 0.0 | 0.5 | |
| VMP-06-5 | 2/7/2012 | 936 | -0.05 | -0.05 | 0.0 | 0.0 | 0.3 | 20.9 | 0.2 | 0.0 | 0.0 | 0.0 | |
| VMP-06-5 | 2/15/2012 | 1330 | -0.03 | 0.00 | 0.0 | 0.0 | 0.3 | 20.9 | 0.4 | 3.5 | 0.0 | 3.5 | |
| VMP-06-5 | 2/22/2012 | 1059 | 0.00 | 0.00 | 0.0 | 0.0 | 0.6 | 20.7 | 0.4 | 0.0 | 0.0 | 0.0 | |
| VMP-06-5 | 2/29/2012 | 940 | -0.12 | - 0.05 | 0.0 | 0.0 | 0.8 | 20.6 | 0.4 | 3.4 | 0.0 | 3.4 | |
| VMP-06-5 | 3/21/2012 | 956 | -0.02 | 0.01 | 0.0 | 0.0 | 0.4 | 20.7 | 0.2 | 0.0 | 0.0 | 0.0 | |
| VMP-06-5 | 4/18/2012 | 951 | -0.06 | -0.05 | 0.0 | 0.0 | 0.1 | 20.9 | 0.8 | 5.7 | 0.0 | 5.7 | |
| VMP-06-5 | 5/16/2012 | 1214 | -0.10 | -0.07 | 0.0 | 0.0 | 0.1 | 20.7 | 0.9 | 0.0 | 0.0 | 0.0 | |
| VMP-06-5 | 6/20/2012 | 1018 | -0.06 | -0.04 | 0.0 | 0.0 | 0.2 | 20.6 | 0.5 | 4.3 | 0.0 | 4.3 | |
| VMP-06-5 | 7/18/2012 | 950 | -0.06 | -0.05 | 0.0 | 0.0 | 0.2 | 20.8 | 0.4 | 1.7 | 0.0 | 1.7 | |
| VMP-06-5 | 8/15/2012 | 930 | -0.03 | -0.04 | 0.0 | 0.0 | 0.2 | 20.8 | 0.7 | 3.4 | 0.0 | 3.4 | |
| VMP-06-5 | 9/19/2012 | 1356 | -0.01 | -0.04 | 0.0 | 0.0 | 0.1 | 20.8 | 0.8 | 2.3 | 0.0 | 2.3 | |
| VMP-06-5 | 10/17/2012 | 1332 | -0.02 | -0.08 | 0.0 | 0.0 | 0.1 | 20.8 | 0.3 | 1.9 | 0.0 | 1.9 | |
| VMP-06-5 | 11/20/2012 | 1100 | -0.01 | 0.00 | 0.0 | 0.0 | 0.0 | 20.9 | 0.1 | 0.7 | 0.0 | 0.7 | |
| VMP-06-5 | 12/19/2012 | 1138 | -0.02 | -0.01 | 0.0 | 0.0 | 0.0 | 20.9 | 0.1 | 0.3 | 0.0 | 0.3 | |
| VMP-06-5 | 1/16/2013 | 958 | -0.03 | -0.02 | 0.0 | 0.0 | 0.1 | 20.8 | 0.1 | 1.5 | 0.0 | 1.5 | |
| VMP-06-5 | 2/25/2013 | 1010 | -0.05 | -0.04 | 0.0 | 0.0 | 0.0 | 20.9 | 0.2 | 1.8 | 0.0 | 1.8 | |
| VMP-06-5 | 3/20/2013 | 1557 | -0.09 | -0.03 | 0.0 | 0.0 | 0.0 | 20.9 | 0.4 | 2.7 | 0.0 | 2.7 | |

SEE LAST PAGE OF TABLE FOR NOTES

**TABLE 10**
**SVE SYSTEM MONTHLY MONITORING - VMP SAMPLING DATA**

| Sample ID | Date | Initial Reading Time (24-Hour) | Vacuum/Pressure | | Fixed Gases | | | | Soil Vapor Concentrations | | | | Comments |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | Initial Reading (Inches of $H_2O$) | Stabilized Reading (Inches of $H_2O$) | CH4 (%) | LEL (%) | $CO_2$ (%) | $O_2$ (%) | PID (ppmv) | THC (ppmv) | CH4 (ppmv) | PHC (ppmv) | |
| VMP-06-10 | 2/2/2012 | 1402 | -0.26 | -0.14 | 0.0 | 0.0 | 6.8 | 13.0 | 0.3 | 0.0 | 0.0 | 0.0 | |
| VMP-06-10 | 2/3/2012 | 905 | -0.12 | -0.16 | 0.0 | 0.0 | 6.0 | 14.7 | 0.5 | 0.0 | 0.0 | 0.0 | |
| VMP-06-10 | 2/7/2012 | 943 | -0.29 | -0.24 | 0.0 | 0.0 | 4.1 | 18.8 | 0.2 | 0.0 | 0.0 | 0.0 | |
| VMP-06-10 | 2/15/2012 | 1331 | -0.19 | -0.09 | 0.0 | 0.0 | 2.4 | 20.0 | 0.3 | 2.8 | 0.0 | 2.8 | |
| VMP-06-10 | 2/22/2012 | 1104 | -0.12 | - 0.08 | 0.0 | 0.0 | 2.1 | 20.0 | 0.3 | 0.0 | 0.0 | 0.0 | |
| VMP-06-10 | 2/29/2012 | 945 | -0.12 | - 0.11 | 0.0 | 0.0 | 2.8 | 17.6 | 0.5 | 0.0 | 0.0 | 0.0 | |
| VMP-06-10 | 3/21/2012 | 1001 | -0.08 | - 0.04 | 0.0 | 0.0 | 2.2 | 18.4 | 0.2 | 0.0 | 0.0 | 0.0 | |
| VMP-06-10 | 4/18/2012 | 956 | -0.17 | -0.12 | 0.0 | 0.0 | 1.8 | 19.7 | 0.6 | 4.5 | 0.0 | 4.5 | |
| VMP-06-10 | 5/16/2012 | 1217 | -0.19 | -0.15 | 0.0 | 0.0 | 1.8 | 19.2 | 0.5 | 0.0 | 0.0 | 0.0 | |
| VMP-06-10 | 6/20/2012 | 1019 | -0.12 | -0.12 | 0.0 | 0.0 | 1.9 | 19.0 | 0.5 | 2.0 | 0.0 | 2.0 | |
| VMP-06-10 | 7/18/2012 | 951 | -0.12 | -0.12 | 0.0 | 0.0 | 1.4 | 19.8 | 0.5 | 0.0 | 0.0 | 0.0 | |
| VMP-06-10 | 8/15/2012 | 936 | -0.09 | -0.11 | 0.0 | 0.0 | 1.2 | 19.8 | 0.6 | 2.2 | 0.0 | 2.2 | |
| VMP-06-10 | 9/19/2012 | 1357 | -0.05 | -0.11 | 0.0 | 0.0 | 0.8 | 20.1 | 0.7 | 1.5 | 0.0 | 1.5 | |
| VMP-06-10 | 10/17/2012 | 1333 | -0.09 | -0.11 | 0.0 | 0.0 | 0.5 | 20.4 | 0.4 | 0.5 | 0.0 | 0.5 | |
| VMP-06-10 | 11/20/2012 | 1103 | -0.04 | -0.22 | 0.0 | 0.0 | 0.3 | 20.6 | 0.1 | 0.1 | 0.0 | 0.1 | |
| VMP-06-10 | 12/19/2012 | 1139 | -0.05 | -0.03 | 0.0 | 0.0 | 0.3 | 20.7 | 0.1 | 0.2 | 0.0 | 0.2 | |
| VMP-06-10 | 1/16/2013 | 1002 | -0.08 | -0.02 | 0.0 | 0.0 | 0.4 | 20.5 | 0.1 | 1.2 | 0.0 | 1.2 | |
| VMP-06-10 | 2/25/2013 | 1010 | -0.12 | -0.08 | 0.0 | 0.0 | 0.3 | 20.6 | 0.3 | 0.9 | 0.0 | 0.9 | |
| VMP-06-10 | 3/20/2013 | 1604 | -0.14 | -0.12 | 0.0 | 0.0 | 0.2 | 20.7 | 0.4 | 1.6 | 0.0 | 1.6 | |
| VMP-06-31.5 | 2/2/2012 | 1408 | -0.17 | -0.26 | OVR | OVR | 12.5 | 3.0 | 321 | 69600 | 41500 | 28100 | |
| VMP-06-31.5 | 2/3/2012 | 910 | -0.26 | -0.31 | 84.6 | OVR | 14.2 | 0.9 | 267 | 60730 | 42300 | 18430 | |
| VMP-06-31.5 | 2/7/2012 | 948 | -0.36 | -0.24 | 50.3 | OVR | 13.7 | 1.6 | 251 | 27800 | 20450 | 7350 | |
| VMP-06-31.5 | 2/15/2012 | 1332 | -0.19 | 0.00 | 48.5 | OVR | 12.9 | 1.6 | 113 | 36400 | 20140 | 16260 | |
| VMP-06-31.5 | 2/22/2012 | 1109 | 0.00 | - 0.01 | 33.3 | OVR | 13.3 | 0.6 | 354 | 18800 | 15040 | 3760 | |
| VMP-06-31.5 | 2/29/2012 | 949 | -0.28 | - 0.26 | 21.6 | OVR | 12.4 | 1.4 | 350 | 17880 | 10600 | 7280 | |
| VMP-06-31.5 | 3/21/2012 | 1006 | -0.19 | - 0.06 | 10.1 | OVR | 12.6 | 0.2 | 365 | 9200 | 4230 | 4970 | |
| VMP-06-31.5 | 4/18/2012 | 1000 | -1.14 | -0.20 | 1.2 | 24.0 | 9.8 | 4.1 | 205 | 1780 | 900 | 880 | |
| VMP-06-31.5 | 5/16/2012 | 1217 | -0.40 | -0.33 | 0.0 | 0.0 | 10.9 | 3.5 | 41.6 | 279 | 143 | 136 | |
| VMP-06-31.5 | 6/20/2012 | 1020 | -0.30 | -0.30 | 0.0 | 0.0 | 9.6 | 5.5 | 14.0 | 84.0 | 35.0 | 49.0 | |
| VMP-06-31.5 | 7/18/2012 | 952 | -0.29 | -0.30 | 0.0 | 0.0 | 7.3 | 9.1 | 4.0 | 44.1 | 41.2 | 2.9 | |
| VMP-06-31.5 | 8/15/2012 | 950 | -0.25 | -0.25 | 0.0 | 0.0 | 6.5 | 9.6 | 2.0 | 6.6 | 5.0 | 1.6 | |
| VMP-06-31.5 | 9/19/2012 | 1358 | -0.14 | -0.23 | 0.0 | 0.0 | 6.5 | 10.6 | 1.5 | 5.3 | 2.0 | 3.3 | |
| VMP-06-31.5 | 10/17/2012 | 1334 | -0.25 | -0.22 | 0.0 | 0.0 | 6.9 | 11.0 | 1.5 | 15.6 | 15.6 | 0.0 | |
| VMP-06-31.5 | 11/20/2012 | 1106 | -0.27 | -0.24 | 0.0 | 0.0 | 6.4 | 12.4 | 0.6 | 20.2 | 20.2 | 0.0 | |
| VMP-06-31.5 | 12/19/2012 | 1140 | -0.09 | -0.04 | 0.0 | 0.0 | 6.6 | 12.4 | 0.3 | 27.2 | 27.2 | 0.0 | |
| VMP-06-31.5 | 1/16/2013 | 1006 | -0.17 | -0.03 | 0.0 | 0.0 | 7.1 | 11.0 | 0.3 | 16.5 | 16.3 | 0.2 | |
| VMP-06-31.5 | 2/25/2013 | 1015 | -0.26 | -0.17 | 0.0 | 0.0 | 7.6 | 10.0 | 0.4 | 12.5 | 12.5 | 0.0 | |
| VMP-06-31.5 | 3/20/2013 | 1610 | -0.48 | -0.30 | 0.0 | 0.0 | 6.2 | 12.2 | 0.6 | 10.2 | 10.2 | 0.0 | |

SEE LAST PAGE OF TABLE FOR NOTES

**TABLE 10**
**SVE SYSTEM MONTHLY MONITORING - VMP SAMPLING DATA**

| Sample ID | Date | Initial Reading Time (24-Hour) | Vacuum/Pressure | | Fixed Gases | | | | Soil Vapor Concentrations | | | | Comments |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | Initial Reading (Inches of $H_2O$) | Stabilized Reading (Inches of $H_2O$) | CH4 (%) | LEL (%) | $CO_2$ (%) | $O_2$ (%) | PID (ppmv) | THC (ppmv) | CH4 (ppmv) | PHC (ppmv) | |
| VMP-06-39 | 2/2/2012 | 1420 | 0.00 | 0.08 | OVR | OVR | 14.3 | 1.0 | 343 | 94000 | 52500 | 41500 | |
| VMP-06-39 | 2/3/2012 | 916 | -0.38 | -0.48 | OVR | OVR | 14.5 | 0.9 | 287 | 62500 | 42000 | 20500 | |
| VMP-06-39 | 2/7/2012 | 952 | -0.34 | -0.42 | 67.2 | OVR | 14.4 | 0.7 | 265 | 43150 | 29480 | 13670 | |
| VMP-06-39 | 2/15/2012 | 1333 | -0.33 | 0.04 | 41.0 | OVR | 13.0 | 1.4 | 279 | 37000 | 23630 | 13370 | |
| VMP-06-39 | 2/22/2012 | 1114 | 0.01 | - 0.04 | 29.3 | OVR | 13.1 | 1.5 | 324 | 24800 | 16730 | 8070 | |
| VMP-06-39 | 2/29/2012 | 953 | -0.31 | - 0.26 | OVR | OVR | 12.2 | 2.0 | 103 | 348000 | 285000 | 63000 | |
| VMP-06-39 | 3/21/2012 | NA | -0.32 | 0.09 | 16.9 | OVR | 12.8 | 0.1 | 422 | 13600 | 5860 | 7740 | |
| VMP-06-39 | 4/18/2012 | 1004 | -0.36 | -0.24 | 4.5 | 91.0 | 12.0 | 0.6 | 375 | 3900 | 1400 | 2500 | |
| VMP-06-39 | 5/16/2012 | 1217 | -0.39 | -0.31 | 0.5 | 10.0 | 12.1 | 1.5 | 117 | 770 | 322 | 448 | |
| VMP-06-39 | 6/20/2012 | 1021 | -0.29 | -0.30 | 0.0 | 0.0 | 11.0 | 4.2 | 21.0 | 203 | 147 | 56.0 | |
| VMP-06-39 | 7/18/2012 | 953 | -0.29 | -0.30 | 0.0 | 0.0 | 9.6 | 5.7 | 6.7 | 94.6 | 69.2 | 25.4 | |
| VMP-06-39 | 8/15/2012 | 944 | -0.25 | -0.24 | 0.1 | 2.0 | 10.3 | 3.8 | 43.3 | 313 | 313 | 0.0 | |
| VMP-06-39 | 9/19/2012 | 1359 | -0.15 | -0.23 | 0.0 | 0.0 | 10.7 | 4.1 | 16.2 | 79.4 | 48.0 | 31.4 | |
| VMP-06-39 | 10/17/2012 | 1335 | -0.25 | -0.22 | 0.0 | 0.0 | 11.0 | 4.6 | 4.3 | 35.1 | 13.4 | 21.7 | |
| VMP-06-39 | 11/20/2012 | 1109 | -0.28 | -0.24 | 0.0 | 0.0 | 12.8 | 6.3 | 1.0 | 27.6 | 15.9 | 11.7 | |
| VMP-06-39 | 12/19/2012 | 1141 | -0.09 | -0.05 | 2.3 | 46.0 | 12.6 | 4.8 | 126 | 5000 | 3600 | 1400 | |
| VMP-06-39 | 1/16/2013 | 1010 | -0.18 | -0.01 | 0.0 | 0.0 | 11.2 | 5.5 | 0.7 | 77.5 | 60.5 | 17.0 | |
| VMP-06-39 | 2/25/2013 | 1455 | 0.13 | 0.20 | 0.0 | 0.0 | 11.4 | 4.6 | 0.4 | 10.1 | 0.0 | 10.1 | |
| VMP-06-39 | 3/20/2013 | 1615 | -0.26 | -0.30 | 0.0 | 0.0 | 10.1 | 6.8 | 0.6 | 19.2 | 0.0 | 19.2 | |
| VMP-07-5 | 2/6/2012 | 1039 | -0.14 | -0.08 | 0.0 | 0.0 | 5.6 | 16.3 | 1.6 | 0.5 | 0.0 | 0.5 | |
| VMP-07-5 | 2/7/2012 | 1028 | -0.11 | -0.12 | 0.0 | 0.0 | 3.7 | 19.8 | 4.0 | 6.6 | 0.0 | 6.6 | |
| VMP-07-5 | 2/8/2012 | 921 | -0.18 | -0.19 | 0.0 | 0.0 | 2.5 | 20.3 | 2.0 | 2.7 | 0.0 | 2.7 | |
| VMP-07-5 | 2/15/2012 | 1410 | -0.02 | -0.19 | 0.0 | 0.0 | 0.8 | 20.8 | 1.2 | 4.7 | 0.0 | 4.7 | |
| VMP-07-5 | 2/22/2012 | 1029 | -0.05 | 0.00 | 0.0 | 0.0 | 0.6 | 20.9 | 1.2 | 9.2 | 7.9 | 1.3 | |
| VMP-07-5 | 2/29/2012 | 1023 | -0.08 | - 0.07 | 0.0 | 0.0 | 1.5 | 18.9 | 1.5 | 1.4 | 0.0 | 1.4 | |
| VMP-07-5 | 3/21/2012 | 1029 | -0.04 | - 0.02 | 0.0 | 0.0 | 0.9 | 19.5 | 0.8 | 0.0 | 0.0 | 0.0 | |
| VMP-07-5 | 4/18/2012 | 1023 | -0.09 | -0.23 | 0.0 | 0.0 | 0.5 | 20.5 | 0.9 | 4.7 | 0.0 | 4.7 | |
| VMP-07-5 | 5/16/2012 | 1407 | -0.04 | -0.05 | 0.0 | 0.0 | 0.2 | 20.6 | 1.0 | 1.8 | 0.0 | 1.8 | |
| VMP-07-5 | 6/20/2012 | 945 | -0.03 | -0.04 | 0.0 | 0.0 | 0.4 | 20.3 | 0.4 | 2.2 | 0.0 | 2.2 | |
| VMP-07-5 | 7/18/2012 | 1324 | 0.00 | 0.00 | 0.0 | 0.0 | 0.3 | 20.3 | 0.5 | 3.5 | 0.0 | 3.5 | |
| VMP-07-5 | 8/15/2012 | 902 | -0.05 | -0.23 | 0.0 | 0.0 | 0.5 | 20.4 | 0.5 | 3.9 | 0.0 | 3.9 | |
| VMP-07-5 | 9/19/2012 | 1426 | 0.00 | -0.03 | 0.0 | 0.0 | 0.3 | 20.6 | 0.6 | 3.0 | 0.0 | 3.0 | |
| VMP-07-5 | 10/17/2012 | 1025 | -0.16 | -0.11 | 0.0 | 0.0 | 0.3 | 20.5 | 0.3 | 1.3 | 0.0 | 1.3 | |
| VMP-07-5 | 11/20/2012 | 1325 | -0.06 | -0.11 | 0.0 | 0.0 | 0.3 | 20.5 | 0.1 | 0.3 | 0.0 | 0.3 | |
| VMP-07-5 | 12/19/2012 | 1247 | -0.02 | -0.01 | 0.0 | 0.0 | 0.3 | 20.7 | 0.1 | 0.9 | 0.0 | 0.9 | |
| VMP-07-5 | 1/16/2013 | 1023 | -0.02 | -0.03 | 0.0 | 0.0 | 0.0 | 20.9 | 0.1 | 2.0 | 0.0 | 2.0 | |
| VMP-07-5 | 2/26/2013 | 1437 | -0.63 | -2.55 | 0.0 | 0.0 | 1.6 | 17.9 | 0.2 | 4.0 | 0.0 | 4.0 | |
| VMP-07-5 | 3/21/2013 | NM | NM | NM | NM | NM | NM | NM | NM | NM | NM | NM | Unable to sample. Stainless steel tubing broken. |

SEE LAST PAGE OF TABLE FOR NOTES

**TABLE 10**
**SVE SYSTEM MONTHLY MONITORING - VMP SAMPLING DATA**

| Sample ID | Date | Initial Reading Time (24-Hour) | Vacuum/Pressure | | Fixed Gases | | | | Soil Vapor Concentrations | | | | Comments |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | Initial Reading (Inches of $H_2O$) | Stabilized Reading (Inches of $H_2O$) | CH4 (%) | LEL (%) | $CO_2$ (%) | $O_2$ (%) | PID (ppmv) | THC (ppmv) | CH4 (ppmv) | PHC (ppmv) | |
| VMP-07-13.5 | 2/6/2012 | 1045 | -0.32 | -0.14 | 0.0 | 1.0 | 6.2 | 15.4 | 1.2 | 0.0 | 0.0 | 0.0 | |
| VMP-07-13.5 | 2/7/2012 | 1049 | -0.20 | -0.24 | 0.0 | 0.0 | 4.4 | 18.6 | 4.2 | 4.6 | 0.0 | 4.6 | |
| VMP-07-13.5 | 2/8/2012 | 926 | -0.35 | -0.36 | 0.0 | 0.0 | 2.8 | 19.8 | 1.9 | 1.5 | 0.0 | 1.5 | |
| VMP-07-13.5 | 2/15/2012 | 1411 | -0.04 | -0.30 | 0.0 | 0.0 | 1.2 | 20.1 | 1.2 | 4.9 | 0.0 | 4.9 | |
| VMP-07-13.5 | 2/22/2012 | 1035 | -0.08 | - 0.3 | 0.0 | 0.0 | 1.1 | 20.1 | 1.3 | 6.9 | 0.0 | 6.9 | |
| VMP-07-13.5 | 2/29/2012 | 1027 | -0.15 | - 0.16 | 0.0 | 0.0 | 1.8 | 18.9 | 1.4 | 0.9 | 0.0 | 0.9 | |
| VMP-07-13.5 | 3/21/2012 | 1033 | -0.09 | - 0.02 | 0.0 | 0.0 | 1.0 | 19.3 | 1.0 | 0.0 | 0.0 | 0.0 | |
| VMP-07-13.5 | 4/18/2012 | 1026 | -0.18 | -0.15 | 0.0 | 0.0 | 0.6 | 20.3 | 0.8 | 4.1 | 0.0 | 4.1 | |
| VMP-07-13.5 | 5/16/2012 | 1413 | -0.18 | -0.19 | 0.0 | 0.0 | 0.8 | 20.1 | 0.9 | 0.0 | 0.0 | 0.0 | |
| VMP-07-13.5 | 6/20/2012 | 946 | -0.18 | -0.18 | 0.0 | 0.0 | 0.9 | 19.9 | 0.5 | 1.4 | 0.0 | 1.4 | |
| VMP-07-13.5 | 7/18/2012 | 1325 | -0.02 | 0.00 | 0.0 | 0.0 | 1.2 | 19.5 | 0.7 | 2.5 | 0.0 | 2.5 | |
| VMP-07-13.5 | 8/15/2012 | 906 | -0.17 | -0.17 | 0.0 | 0.0 | 1.2 | 19.9 | 0.5 | 2.5 | 0.0 | 2.5 | |
| VMP-07-13.5 | 9/19/2012 | 1429 | -0.14 | -0.12 | 0.0 | 0.0 | 0.7 | 20.2 | 0.5 | 1.8 | 0.0 | 1.8 | |
| VMP-07-13.5 | 10/17/2012 | 1026 | -0.27 | -0.25 | 0.0 | 0.0 | 0.6 | 20.4 | 0.6 | 0.7 | 0.0 | 0.7 | |
| VMP-07-13.5 | 11/20/2012 | 1328 | -0.18 | -0.24 | 0.0 | 0.0 | 0.3 | 20.5 | 0.2 | 0.5 | 0.0 | 0.5 | |
| VMP-07-13.5 | 12/19/2012 | 1248 | 0.02 | -0.01 | 0.0 | 0.0 | 0.3 | 20.5 | 0.3 | 0.1 | 0.0 | 0.1 | |
| VMP-07-13.5 | 1/16/2013 | 1328 | 0.00 | -1.09 | 0.0 | 0.0 | 0.0 | 20.9 | 0.1 | 2.4 | 0.0 | 2.4 | |
| VMP-07-13.5 | 2/25/2013 | 1438 | NM | NM | NM | NM | NM | NM | NM | NM | NM | NM | Unable to sample. Stainless steel tubing broken. |
| VMP-07-13.5 | 3/21/2013 | NM | NM | NM | NM | NM | NM | NM | NM | NM | NM | NM | Unable to sample. Stainless steel tubing broken. |
| VMP-07-29.5 | 2/6/2012 | 1049 | -0.60 | -0.24 | 3.4 | 69.0 | 16.1 | 1.0 | 179 | 12300 | 8000 | 4300 | |
| VMP-07-29.5 | 2/7/2012 | 1039 | -0.38 | -0.54 | 2.5 | 50.0 | 16.0 | 1.2 | 161 | 5470 | 4230 | 1240 | |
| VMP-07-29.5 | 2/8/2012 | 930 | -0.46 | -0.10 | 1.3 | 26.0 | 16.2 | 0.8 | 136 | 3830 | 2980 | 850 | |
| VMP-07-29.5 | 2/15/2012 | 1412 | 0.12 | -0.21 | 0.3 | 7.0 | 15.1 | 1.2 | 76.2 | 1030 | 805 | 225 | |
| VMP-07-29.5 | 2/22/2012 | 1039 | 0.08 | - 0.07 | 0.0 | 0.0 | 13.5 | 2.9 | 15.0 | 161 | 95.1 | 66.1 | |
| VMP-07-29.5 | 2/29/2012 | 1031 | -0.20 | - 0.21 | 0.0 | 0.0 | 11.6 | 5.5 | 17.6 | 85.2 | 62.7 | 22.5 | |
| VMP-07-29.5 | 3/21/2012 | 1036 | -0.01 | - 0.03 | 0.0 | 0.0 | 10.9 | 5.4 | 19.4 | 385 | 262 | 123 | |
| VMP-07-29.5 | 4/18/2012 | 1030 | -0.23 | -0.18 | 0.0 | 0.0 | 8.1 | 12.2 | 1.2 | 10.2 | 5.4 | 4.8 | |
| VMP-07-29.5 | 5/16/2012 | 1417 | -0.22 | -0.22 | 0.0 | 0.0 | 6.3 | 15.2 | 2.0 | 1.5 | 0.0 | 1.5 | |
| VMP-07-29.5 | 6/20/2012 | 947 | -0.21 | -0.23 | 0.0 | 0.0 | 5.8 | 15.8 | 0.9 | 2.7 | 0.0 | 2.7 | |
| VMP-07-29.5 | 7/18/2012 | 1326 | -0.02 | 0.00 | 0.0 | 0.0 | 5.1 | 16.4 | 1.2 | 4.2 | 0.0 | 4.2 | |
| VMP-07-29.5 | 8/15/2012 | 911 | -0.22 | -0.23 | 0.0 | 0.0 | 5.5 | 16.2 | 0.8 | 10.2 | 9.3 | 0.8 | |
| VMP-07-29.5 | 9/19/2012 | 1429 | -0.18 | -0.15 | 0.0 | 0.0 | 4.8 | 16.5 | 0.7 | 4.8 | 0.0 | 4.8 | |
| VMP-07-29.5 | 10/17/2012 | 1026 | -0.34 | -0.31 | 0.0 | 0.0 | 4.5 | 17.0 | 0.4 | 2.3 | 0.0 | 2.3 | |
| VMP-07-29.5 | 11/20/2012 | 1331 | -0.25 | -0.31 | 0.0 | 0.0 | 3.8 | 17.1 | 0.5 | 1.5 | 0.0 | 1.5 | |
| VMP-07-29.5 | 12/19/2012 | 1249 | -0.18 | -0.02 | 0.0 | 0.0 | 4.2 | 17.2 | 0.2 | 3.5 | 0.0 | 3.5 | |
| VMP-07-29.5 | 1/16/2013 | 1332 | -0.16 | -0.06 | 0.0 | 0.0 | 1.3 | 19.5 | 0.2 | 18.0 | 13.1 | 4.9 | |
| VMP-07-29.5 | 2/26/2013 | 1440 | 0.00 | -0.30 | 0.0 | 0.0 | 3.8 | 16.2 | 0.2 | 3.0 | 0.0 | 3.0 | |
| VMP-07-29.5 | 3/20/2013 | NM | NM | NM | NM | NM | NM | NM | NM | NM | NM | NM | Water encountered during sampling. |

SEE LAST PAGE OF TABLE FOR NOTES

**TABLE 10**
**SVE SYSTEM MONTHLY MONITORING - VMP SAMPLING DATA**

| Sample ID | Date | Initial Reading Time (24-Hour) | Vacuum/Pressure | | Fixed Gases | | | | Soil Vapor Concentrations | | | | Comments |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | Initial Reading (Inches of $H_2O$) | Stabilized Reading (Inches of $H_2O$) | CH4 (%) | LEL (%) | $CO_2$ (%) | $O_2$ (%) | PID (ppmv) | THC (ppmv) | CH4 (ppmv) | PHC (ppmv) | |
| VMP-07-38 | 2/6/2012 | 1054 | -0.32 | -0.16 | 5.9 | OVR | 16.0 | 1.2 | 232 | 11490 | 11070 | 420 | |
| VMP-07-38 | 2/7/2012 | 1044 | -0.24 | -0.28 | 5.6 | OVR | 15.9 | 1.4 | 259 | 7940 | 5800 | 2140 | |
| VMP-07-38 | 2/8/2012 | 935 | -0.42 | -0.44 | 2.5 | 57.0 | 15.6 | 1.7 | 214 | 6980 | 4460 | 2520 | |
| VMP-07-38 | 2/15/2012 | 1413 | -0.02 | -0.36 | 0.0 | 1.0 | 13.6 | 1.8 | 16.2 | 715 | 696 | 19.4 | |
| VMP-07-38 | 2/22/2012 | 1044 | -0.08 | 0.00 | 0.2 | 5.0 | 14.9 | 1.0 | 78.7 | 395 | 145 | 250 | |
| VMP-07-38 | 2/29/2012 | 1035 | -0.18 | 0.00 | 0.3 | 7.0 | 14.3 | 1.0 | 87.1 | 403 | 110 | 293 | |
| VMP-07-38 | 3/21/2012 | 1040 | -0.12 | - 0.04 | 0.0 | 0.0 | 13.0 | 2.5 | 26.8 | 416 | 284 | 132 | |
| VMP-07-38 | 4/18/2012 | 1110 | -0.21 | -0.10 | 0.0 | 0.0 | 7.0 | 13.0 | 6.8 | 11.0 | 6.0 | 5.0 | |
| VMP-07-38 | 5/16/2012 | 1422 | -0.03 | -0.06 | 0.0 | 0.0 | 0.5 | 20.4 | 0.7 | 0.5 | 0.0 | 0.5 | |
| VMP-07-38 | 6/20/2012 | 948 | -0.06 | -0.06 | 0.0 | 0.0 | 0.8 | 20.0 | 0.4 | 3.5 | 0.0 | 3.5 | |
| VMP-07-38 | 7/18/2012 | 1327 | 0.00 | 0.00 | 0.0 | 0.0 | 0.1 | 20.7 | 1.0 | 4.7 | 0.0 | 4.7 | |
| VMP-07-38 | 8/15/2012 | 916 | -0.04 | -0.04 | 0.0 | 0.0 | 0.4 | 20.5 | 0.6 | 3.7 | 0.0 | 3.7 | |
| VMP-07-38 | 9/19/2012 | 1429 | -0.23 | -0.03 | 0.0 | 0.0 | 0.5 | 20.1 | 0.7 | 3.4 | 0.0 | 3.4 | |
| VMP-07-38 | 10/17/2012 | 1030 | 0.00 | -0.13 | 0.0 | 0.0 | 0.8 | 20.1 | 0.6 | 2.2 | 0.0 | 2.2 | |
| VMP-07-38 | 11/20/2012 | 1334 | -0.16 | -0.17 | 0.0 | 0.0 | 3.2 | 18.0 | 0.4 | 2.8 | 0.0 | 2.8 | |
| VMP-07-38 | 12/19/2012 | 1250 | -0.03 | 0.00 | 0.0 | 0.0 | 0.9 | 20.2 | 0.1 | 1.8 | 0.0 | 1.8 | |
| VMP-07-38 | 1/16/2013 | 1336 | -1.63 | -0.03 | 0.0 | 0.0 | 1.1 | 19.7 | 0.2 | 4.8 | 0.0 | 4.8 | |
| VMP-07-38 | 2/26/2013 | 1441 | -0.32 | -0.36 | 0.0 | 0.0 | 0.5 | 20.2 | 0.1 | 2.0 | 0.0 | 2.0 | |
| VMP-07-38 | 3/20/2013 | NM | NM | NM | NM | NM | NM | NM | NM | NM | NM | NM | Water encountered during sampling. |
| VMP-09-5 | 2/6/2012 | 1108 | -0.02 | 0.00 | 0.0 | 0.0 | 2.0 | 19.0 | 1.2 | 1.0 | 0.0 | 1.0 | |
| VMP-09-5 | 2/7/2012 | 1100 | -0.50 | 0.00 | 0.0 | 0.0 | 1.4 | 19.9 | 1.8 | 0.3 | 0.0 | 0.3 | |
| VMP-09-5 | 2/8/2012 | 949 | -0.07 | -0.01 | 0.0 | 0.0 | 0.9 | 20.6 | 0.5 | 0.0 | 0.0 | 0.0 | |
| VMP-09-5 | 2/15/2012 | 1458 | -0.03 | -0.02 | 0.0 | 0.0 | 0.8 | 20.8 | 0.9 | 4.1 | 0.0 | 4.1 | |
| VMP-09-5 | 2/22/2012 | 1127 | 0.00 | 0.00 | 0.0 | 0.0 | 1.0 | 20.5 | 1.2 | 4.3 | 0.0 | 4.3 | |
| VMP-09-5 | 2/29/2012 | 1319 | 0.00 | - 0.05 | 0.0 | 0.0 | 1.5 | 19.7 | 1.5 | 20.7 | 1.4 | 19.3 | |
| VMP-09-5 | 3/21/2012 | 1052 | -0.01 | - 0.01 | 0.0 | 0.0 | 0.8 | 19.6 | 0.7 | 0.0 | 0.0 | 0.0 | |
| VMP-09-5 | 4/18/2012 | 1051 | -0.01 | 0.00 | 0.0 | 0.0 | 0.3 | 20.6 | 0.4 | 3.0 | 0.0 | 3.0 | |
| VMP-09-5 | 5/16/2012 | 1303 | 0.00 | -0.04 | 0.0 | 0.0 | 0.4 | 20.4 | 0.7 | 0.0 | 0.0 | 0.0 | |
| VMP-09-5 | 6/20/2012 | 906 | 0.00 | -0.02 | 0.0 | 0.0 | 0.7 | 20.1 | 0.5 | 2.3 | 0.0 | 2.3 | |
| VMP-09-5 | 7/18/2012 | 906 | -0.02 | NM | 0.0 | 0.0 | 0.5 | 20.4 | 0.4 | 1.4 | 0.0 | 1.4 | |
| VMP-09-5 | 8/15/2012 | 835 | -0.04 | -0.02 | 0.0 | 0.0 | 0.5 | 20.3 | 0.6 | 3.2 | 0.0 | 3.2 | |
| VMP-09-5 | 9/19/2012 | 1131 | -0.02 | -0.02 | 0.0 | 0.0 | 0.7 | 20.1 | 0.5 | 1.6 | 0.0 | 1.6 | |
| VMP-09-5 | 10/17/2012 | 1320 | -0.01 | 0.00 | 0.0 | 0.0 | 0.3 | 20.5 | 0.6 | 0.8 | 0.0 | 0.8 | |
| VMP-09-5 | 11/20/2012 | 1355 | -0.04 | -0.01 | 0.0 | 0.0 | 0.2 | 20.7 | 0.4 | 0.7 | 0.0 | 0.7 | |
| VMP-09-5 | 12/19/2012 | 1208 | -0.01 | 0.00 | 0.0 | 0.0 | 0.2 | 20.8 | 0.1 | 0.5 | 0.0 | 0.5 | |
| VMP-09-5 | 1/16/2013 | 1046 | -0.01 | -0.02 | 0.0 | 0.0 | 0.1 | 20.8 | 0.1 | 0.8 | 0.0 | 0.8 | |
| VMP-09-5 | 2/25/2013 | 953 | -0.03 | 0.00 | 0.0 | 0.0 | 0.2 | 20.7 | 0.3 | 0.6 | 0.0 | 0.6 | |
| VMP-09-5 | 3/20/2013 | 1443 | -0.05 | 0.00 | 0.0 | 0.0 | 0.1 | 20.8 | 0.7 | 2.6 | 0.0 | 2.6 | |

SEE LAST PAGE OF TABLE FOR NOTES

**TABLE 10**
**SVE SYSTEM MONTHLY MONITORING - VMP SAMPLING DATA**

| Sample ID | Date | Initial Reading Time (24-Hour) | Vacuum/Pressure | | Fixed Gases | | | | Soil Vapor Concentrations | | | | Comments |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | Initial Reading (Inches of $H_2O$) | Stabilized Reading (Inches of $H_2O$) | CH4 (%) | LEL (%) | $CO_2$ (%) | $O_2$ (%) | PID (ppmv) | THC (ppmv) | CH4 (ppmv) | PHC (ppmv) | |
| VMP-09-11.5 | 2/6/2012 | 1114 | -0.05 | -0.02 | 0.0 | 0.0 | 6.1 | 14.3 | 1.5 | 0.1 | 0.0 | 0.1 | |
| VMP-09-11.5 | 2/7/2012 | 1105 | -0.13 | -0.07 | 0.0 | 0.0 | 4.5 | 16.8 | 2.2 | 0.0 | 0.0 | 0.0 | |
| VMP-09-11.5 | 2/8/2012 | 954 | -0.17 | -0.14 | 0.0 | 0.0 | 3.3 | 18.6 | 0.7 | 0.0 | 0.0 | 0.0 | |
| VMP-09-11.5 | 2/15/2012 | 1459 | -0.11 | -0.05 | 0.0 | 0.0 | 2.1 | 19.9 | 0.8 | 3.4 | 0.0 | 3.4 | |
| VMP-09-11.5 | 2/22/2012 | 1131 | 0.00 | 0.02 | 0.0 | 0.0 | 2.5 | 19.0 | 1.2 | 1.9 | 0.0 | 1.9 | |
| VMP-09-11.5 | 2/29/2012 | 1324 | 0.00 | - 0.05 | 0.0 | 0.0 | 0.2 | 20.9 | 1.2 | 14.3 | 2.2 | 12.1 | |
| VMP-09-11.5 | 3/21/2012 | 1056 | -0.04 | 0.00 | 0.0 | 0.0 | 1.1 | 19.4 | 0.6 | 0.0 | 0.0 | 0.0 | |
| VMP-09-11.5 | 4/18/2012 | 1056 | -0.07 | -0.06 | 0.0 | 0.0 | 0.8 | 20.1 | 0.4 | 2.7 | 0.0 | 2.7 | |
| VMP-09-11.5 | 5/16/2012 | 1303 | -0.05 | -0.04 | 0.0 | 0.0 | 1.2 | 19.7 | 0.9 | 0.0 | 0.0 | 0.0 | |
| VMP-09-11.5 | 6/20/2012 | 907 | -0.08 | -0.50 | 0.0 | 0.0 | 1.4 | 19.9 | 0.4 | 0.8 | 0.0 | 0.8 | |
| VMP-09-11.5 | 7/18/2012 | 907 | -0.12 | -0.02 | 0.0 | 0.0 | 1.2 | 19.8 | 0.5 | 0.7 | 0.0 | 0.7 | |
| VMP-09-11.5 | 8/15/2012 | 840 | -0.11 | -0.08 | 0.0 | 0.0 | 1.1 | 19.7 | 0.5 | 2.7 | 0.0 | 2.7 | |
| VMP-09-11.5 | 9/19/2012 | 1132 | -0.09 | -0.10 | 0.0 | 0.0 | 1.0 | 19.8 | 0.7 | 0.9 | 0.0 | 0.9 | |
| VMP-09-11.5 | 10/17/2012 | 1321 | -0.07 | -0.05 | 0.0 | 0.0 | 0.6 | 20.1 | 0.4 | 0.9 | 0.0 | 0.9 | |
| VMP-09-11.5 | 11/20/2012 | 1358 | -0.14 | -0.45 | 0.0 | 0.0 | 0.3 | 20.6 | 0.2 | 0.3 | 0.0 | 0.3 | |
| VMP-09-11.5 | 12/19/2012 | 1209 | -0.01 | 0.06 | 0.0 | 0.0 | 0.4 | 20.4 | 0.1 | 0.3 | 0.0 | 0.3 | |
| VMP-09-11.5 | 1/16/2013 | 1050 | -0.02 | -0.03 | 0.0 | 0.0 | 0.3 | 20.6 | 0.1 | 1.1 | 0.0 | 1.1 | |
| VMP-09-11.5 | 2/25/2013 | 955 | -0.08 | -0.03 | 0.0 | 0.0 | 0.3 | 20.6 | 0.2 | 0.3 | 0.0 | 0.3 | |
| VMP-09-11.5 | 3/20/2013 | 1448 | -0.09 | -0.07 | 0.0 | 0.0 | 0.1 | 20.8 | 0.7 | 2.3 | 0.0 | 2.3 | |
| VMP-09-25.5 | 2/6/2012 | 1119 | -0.12 | -0.07 | 0.0 | 0.0 | 14.9 | 2.0 | 1.6 | 55.0 | 46.6 | 8.4 | |
| VMP-09-25.5 | 2/7/2012 | 1110 | -0.28 | -0.19 | 0.0 | 0.0 | 13.6 | 4.3 | 2.6 | 0.1 | 0.0 | 0.1 | |
| VMP-09-25.5 | 2/8/2012 | 959 | -0.38 | -0.32 | 0.0 | 0.0 | 11.7 | 7.3 | 0.8 | 0.0 | 0.0 | 0.0 | |
| VMP-09-25.5 | 2/15/2012 | 1500 | -0.25 | -0.11 | 0.0 | 0.0 | 9.5 | 11.1 | 0.8 | 81.0 | 59.0 | 22.0 | |
| VMP-09-25.5 | 2/22/2012 | 1136 | 0.07 | 0.05 | 0.0 | 0.0 | 10.1 | 11.4 | 1.7 | 14.4 | 11.0 | 3.4 | |
| VMP-09-25.5 | 2/29/2012 | 1328 | 0.00 | - 0.02 | 0.0 | 0.0 | 8.4 | 13.0 | 2.0 | 4.2 | 0.0 | 4.2 | |
| VMP-09-25.5 | 3/21/2012 | 1059 | -0.10 | 0.00 | 0.0 | 0.0 | 5.9 | 14.6 | 0.8 | 0.0 | 0.0 | 0.0 | |
| VMP-09-25.5 | 4/18/2012 | 1059 | -0.16 | -0.15 | 0.0 | 0.0 | 3.1 | 18.5 | 0.3 | 2.6 | 0.0 | 2.6 | |
| VMP-09-25.5 | 5/16/2012 | 1303 | -0.16 | -0.15 | 0.0 | 0.0 | 2.7 | 18.2 | 0.5 | 0.0 | 0.0 | 0.0 | |
| VMP-09-25.5 | 6/20/2012 | 908 | -0.26 | -0.19 | 0.0 | 0.0 | 2.7 | 18.3 | 0.4 | 0.7 | 0.0 | 0.7 | |
| VMP-09-25.5 | 7/18/2012 | 908 | -0.28 | -0.31 | 0.0 | 0.0 | 2.9 | 18.5 | 0.6 | 0.0 | 0.0 | 0.0 | |
| VMP-09-25.5 | 8/15/2012 | 845 | -0.25 | -0.19 | 0.0 | 0.0 | 2.8 | 18.7 | 0.4 | 2.0 | 0.0 | 2.0 | |
| VMP-09-25.5 | 9/19/2012 | 1133 | -0.23 | -0.21 | 0.0 | 0.0 | 2.2 | 18.9 | 0.8 | 1.1 | 0.0 | 1.1 | |
| VMP-09-25.5 | 10/17/2012 | 1322 | -0.17 | -0.12 | 0.0 | 0.0 | 1.8 | 19.4 | 0.4 | 0.9 | 0.0 | 0.9 | |
| VMP-09-25.5 | 11/20/2012 | 1401 | -0.31 | -0.34 | 0.0 | 0.0 | 1.2 | 20.0 | 0.3 | 0.7 | 0.0 | 0.7 | |
| VMP-09-25.5 | 12/19/2012 | 1210 | -0.01 | 0.11 | 0.0 | 0.0 | 1.8 | 19.7 | 0.2 | 0.2 | 0.0 | 0.2 | |
| VMP-09-25.5 | 1/16/2013 | 1357 | -0.05 | -0.03 | 0.0 | 0.0 | 1.7 | 19.7 | 0.1 | 1.0 | 0.0 | 1.0 | |
| VMP-09-25.5 | 2/25/2013 | 1000 | -0.16 | -0.08 | 0.0 | 0.0 | 1.2 | 19.9 | 0.3 | 0.3 | 0.0 | 0.3 | |
| VMP-09-25.5 | 3/20/2013 | 1459 | -0.20 | -0.15 | 0.0 | 0.0 | 0.8 | 20.4 | 0.4 | 0.7 | 0.0 | 0.7 | |

SEE LAST PAGE OF TABLE FOR NOTES

**TABLE 10**
**SVE SYSTEM MONTHLY MONITORING - VMP SAMPLING DATA**

| Sample ID | Date | Initial Reading Time (24-Hour) | Vacuum/Pressure | | Fixed Gases | | | | Soil Vapor Concentrations | | | | Comments |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | Initial Reading (Inches of $H_2O$) | Stabilized Reading (Inches of $H_2O$) | CH4 (%) | LEL (%) | $CO_2$ (%) | $O_2$ (%) | PID (ppmv) | THC (ppmv) | CH4 (ppmv) | PHC (ppmv) | |
| VMP-09-38.5 | 2/6/2012 | 1123 | -0.12 | -0.04 | 0.5 | 10.0 | 16.3 | 0.7 | 39.3 | 3100 | 3080 | 20.0 | |
| VMP-09-38.5 | 2/7/2012 | 1115 | -0.26 | -0.18 | 0.3 | 6.0 | 15.8 | 1.0 | 41.0 | 1800 | 1280 | 520 | |
| VMP-09-38.5 | 2/8/2012 | 1003 | -0.37 | -0.31 | 0.1 | 3.0 | 15.2 | 2.0 | 29.7 | 1000 | 790 | 210 | |
| VMP-09-38.5 | 2/15/2012 | 1501 | -0.43 | -0.31 | 0.0 | 0.0 | 14.7 | 1.4 | 12.0 | 190 | 139 | 50.8 | |
| VMP-09-38.5 | 2/22/2012 | 1141 | 0.22 | - 0.21 | 0.0 | 0.0 | 14.5 | 1.1 | 17.8 | 59.6 | 32.2 | 27.4 | |
| VMP-09-38.5 | 2/29/2012 | 1332 | -0.09 | - 0.18 | 0.0 | 0.0 | 13.5 | 2.9 | 10.5 | 92.6 | 63.8 | 28.8 | |
| VMP-09-38.5 | 3/21/2012 | 1109 | -0.08 | 0.00 | 0.0 | 0.0 | 11.5 | 8.2 | 1.5 | 0.0 | 0.0 | 0.0 | |
| VMP-09-38.5 | 4/18/2012 | 1102 | -0.16 | -0.15 | 0.0 | 0.0 | 7.2 | 14.6 | 0.8 | 5.2 | 0.0 | 5.2 | |
| VMP-09-38.5 | 5/16/2012 | 1303 | -0.16 | -0.15 | 0.0 | 0.0 | 6.2 | 15.6 | 0.8 | 0.0 | 0.0 | 0.0 | |
| VMP-09-38.5 | 6/20/2012 | 909 | -0.29 | -0.18 | 0.0 | 0.0 | 5.3 | 15.9 | 0.7 | 1.8 | 0.0 | 1.8 | |
| VMP-09-38.5 | 7/18/2012 | 909 | -0.29 | -0.21 | 0.0 | 0.0 | 5.5 | 16.1 | 0.7 | 0.5 | 0.0 | 0.5 | |
| VMP-09-38.5 | 8/15/2012 | 850 | -0.25 | -0.19 | 0.0 | 0.0 | 5.7 | 16.6 | 0.5 | 4.9 | 0.0 | 4.9 | |
| VMP-09-38.5 | 9/19/2012 | 1134 | -0.20 | -0.23 | 0.0 | 0.0 | 5.7 | 14.7 | 0.9 | 2.3 | 0.0 | 2.3 | |
| VMP-09-38.5 | 10/17/2012 | 1323 | -0.18 | -0.09 | 0.0 | 0.0 | 6.3 | 13.8 | 12.1 | 65.9 | 23.5 | 42.4 | |
| VMP-09-38.5 | 11/20/2012 | 1404 | -0.32 | -0.35 | 0.0 | 0.0 | 5.5 | 15.9 | 0.4 | 1.0 | 0.0 | 1.0 | |
| VMP-09-38.5 | 12/19/2012 | 1211 | -0.02 | 0.14 | 0.0 | 0.0 | 5.9 | 15.5 | 0.2 | 0.9 | 0.0 | 0.9 | |
| VMP-09-38.5 | 1/16/2013 | 1058 | -0.04 | -0.05 | 0.0 | 0.0 | 5.9 | 15.9 | 0.1 | 1.3 | 0.0 | 1.3 | |
| VMP-09-38.5 | 2/25/2013 | 1000 | -0.17 | -0.07 | 0.0 | 0.0 | 5.6 | 15.7 | 0.3 | 0.4 | 0.0 | 0.4 | |
| VMP-09-38.5 | 3/20/2013 | 1509 | -0.20 | -0.16 | 0.0 | 0.0 | 4.8 | 17.4 | 0.6 | 1.9 | 0.0 | 1.9 | |
| VMP-10-5 | 12/5/2012 | 1455 | -0.01 | -0.08 | 0.0 | 0.0 | 1.6 | 19.1 | 0.2 | 1.0 | 0.0 | 1.0 | Initail sample after Public Works SVE startup. |
| VMP-10-5 | 12/6/2012 | 1317 | 0.00 | -0.01 | 0.0 | 0.0 | 1.2 | 19.7 | 0.2 | 0.3 | 0.0 | 0.3 | |
| VMP-10-5 | 12/13/2012 | 1353 | -0.03 | -0.03 | 0.0 | 0.0 | 0.4 | 20.5 | 0.1 | 0.6 | 0.0 | 0.6 | |
| VMP-10-5 | 12/19/2012 | 1324 | -0.04 | -0.16 | 0.0 | 0.0 | 0.3 | 20.6 | 0.3 | 0.9 | 0.0 | 0.9 | |
| VMP-10-5 | 1/16/2013 | 931 | -0.03 | -0.06 | 0.0 | 0.0 | 0.1 | 20.9 | 0.1 | 0.8 | 0.0 | 0.8 | |
| VMP-10-5 | 2/25/2013 | 1040 | -0.02 | -0.06 | 0.0 | 0.0 | 0.1 | 20.8 | 0.3 | 2.1 | 0.0 | 2.1 | |
| VMP-10-5 | 3/20/2013 | 1403 | -0.02 | 0.00 | 0.0 | 0.0 | 0.0 | 20.9 | 0.5 | 3.1 | 0.0 | 3.1 | |
| VMP-10-10 | 12/5/2012 | 1505 | -0.04 | -0.09 | 0.0 | 0.0 | 2.2 | 18.4 | 0.3 | 0.8 | 0.0 | 0.8 | Initail sample after Public Works SVE startup. |
| VMP-10-10 | 12/6/2012 | 1317 | -0.03 | -0.02 | 0.0 | 0.0 | 2.1 | 18.5 | 0.1 | 1.0 | 0.0 | 1.0 | |
| VMP-10-10 | 12/13/2012 | 1357 | -0.05 | -0.02 | 0.0 | 0.0 | 0.8 | 20.1 | 0.2 | 0.4 | 0.0 | 0.4 | |
| VMP-10-10 | 12/19/2012 | 1328 | -0.15 | -0.20 | 0.0 | 0.0 | 0.5 | 20.5 | 0.2 | 0.3 | 0.0 | 0.3 | |
| VMP-10-10 | 1/16/2013 | 932 | -0.04 | -0.20 | 0.0 | 0.0 | 0.2 | 20.8 | 0.1 | 1.4 | 0.0 | 1.4 | |
| VMP-10-10 | 2/25/2013 | 1045 | -0.03 | -0.07 | 0.0 | 0.0 | 0.1 | 20.7 | 0.2 | 1.6 | 0.0 | 1.6 | |
| VMP-10-10 | 3/20/2013 | 1407 | -0.03 | 0.00 | 0.0 | 0.0 | 0.0 | 20.9 | 0.3 | 1.6 | 0.0 | 1.6 | |
| VMP-10-20 | 12/5/2012 | 1507 | -0.08 | -0.11 | 0.0 | 0.0 | 4.1 | 16.0 | 0.4 | 0.2 | 0.0 | 0.2 | Initail sample after Public Works SVE startup. |
| VMP-10-20 | 12/6/2012 | 1318 | -0.04 | -0.03 | 0.0 | 0.0 | 3.8 | 16.4 | 0.3 | 0.6 | 0.0 | 0.6 | |
| VMP-10-20 | 12/13/2012 | 1401 | -0.03 | -0.03 | 0.0 | 0.0 | 2.5 | 18.8 | 0.4 | 0.3 | 0.0 | 0.3 | |
| VMP-10-20 | 12/19/2012 | 1332 | -0.05 | -0.09 | 0.0 | 0.0 | 1.7 | 19.5 | 0.2 | 0.4 | 0.0 | 0.4 | |
| VMP-10-20 | 1/16/2013 | 933 | -0.04 | -0.07 | 0.0 | 0.0 | 0.6 | 20.5 | 0.2 | 1.0 | 0.0 | 1.0 | |
| VMP-10-20 | 2/25/2013 | 1050 | -0.03 | -0.08 | 0.0 | 0.0 | 0.3 | 20.6 | 0.3 | 1.4 | 0.0 | 1.4 | |
| VMP-10-20 | 3/20/2013 | 1411 | -0.05 | -0.01 | 0.0 | 0.0 | 0.2 | 20.8 | 0.3 | 1.4 | 0.0 | 1.4 | |

SEE LAST PAGE OF TABLE FOR NOTES

**TABLE 10**
**SVE SYSTEM MONTHLY MONITORING - VMP SAMPLING DATA**

| Sample ID | Date | Initial Reading Time (24-Hour) | Vacuum/Pressure | | Fixed Gases | | | | Soil Vapor Concentrations | | | | Comments |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | Initial Reading (Inches of $H_2O$) | Stabilized Reading (Inches of $H_2O$) | CH4 (%) | LEL (%) | $CO_2$ (%) | $O_2$ (%) | PID (ppmv) | THC (ppmv) | CH4 (ppmv) | PHC (ppmv) | |
| VMP-10-30 | 12/5/2012 | 1512 | -0.08 | -0.11 | 0.0 | 0.0 | 6.1 | 13.8 | 0.5 | 6.2 | 2.7 | 3.5 | Initail sample after Public Works SVE startup. |
| VMP-10-30 | 12/6/2012 | 1318 | -0.04 | -0.04 | 0.0 | 0.0 | 5.9 | 14.0 | 0.2 | 1.9 | 0.0 | 1.9 | |
| VMP-10-30 | 12/13/2012 | 1403 | -0.03 | -0.04 | 0.0 | 0.0 | 5.2 | 15.7 | 0.4 | 2.0 | 1.0 | 1.0 | |
| VMP-10-30 | 12/19/2012 | 1336 | -0.05 | -0.12 | 0.0 | 0.0 | 4.4 | 16.6 | 0.3 | 3.1 | 0.0 | 3.1 | |
| VMP-10-30 | 1/16/2013 | 934 | -0.06 | -0.09 | 0.0 | 0.0 | 2.6 | 18.8 | 0.2 | 1.2 | 0.0 | 1.2 | |
| VMP-10-30 | 2/25/2013 | 1055 | -0.04 | -0.10 | 0.0 | 0.0 | 1.7 | 19.2 | 0.3 | 1.0 | 0.0 | 1.0 | |
| VMP-10-30 | 3/20/2013 | 1415 | -0.06 | -0.01 | 0.0 | 0.0 | 1.5 | 19.8 | 0.4 | 1.2 | 0.0 | 1.2 | |
| VMP-11-5 | 12/3/2012 | 1542 | -0.03 | -0.02 | 0.0 | 0.0 | 1.4 | 18.8 | 0.3 | 3.3 | 0.0 | 3.3 | Initail sample after Public Works SVE startup. |
| VMP-11-5 | 12/4/2012 | 1350 | -0.05 | -0.05 | 0.0 | 0.0 | 1.2 | 19.9 | 0.3 | 1.2 | 0.0 | 1.2 | |
| VMP-11-5 | 12/13/2012 | 1521 | -0.10 | -0.04 | 0.0 | 0.0 | 0.7 | 20.2 | 0.1 | 0.5 | 0.0 | 0.5 | |
| VMP-11-5 | 12/19/2012 | 1433 | -0.02 | -0.05 | 0.0 | 0.0 | 0.7 | 20.4 | 0.4 | 2.1 | 0.0 | 2.1 | |
| VMP-11-5 | 1/16/2013 | 1515 | -0.01 | -0.01 | 0.0 | 0.0 | 0.3 | 20.6 | 0.8 | 6.2 | 0.0 | 6.2 | |
| VMP-11-5 | 2/25/2013 | 907 | -0.03 | -0.03 | 0.0 | 0.0 | 0.2 | 20.7 | 3.4 | 8.6 | 0.0 | 8.6 | |
| VMP-11-5 | 3/20/2013 | 1550 | -0.05 | -0.05 | 0.0 | 0.0 | 0.1 | 20.8 | 1.5 | 4.3 | 0.0 | 4.3 | |
| VMP-11-8 | 12/3/2012 | 1543 | -0.05 | -0.04 | 0.0 | 0.0 | 2.6 | 17.4 | 0.3 | 2.2 | 0.0 | 2.2 | Initail sample after Public Works SVE startup. |
| VMP-11-8 | 12/4/2012 | 1351 | -0.08 | -0.08 | 0.0 | 0.0 | 2.6 | 18.6 | 0.4 | 1.0 | 0.0 | 1.0 | |
| VMP-11-8 | 12/13/2012 | 1532 | -0.11 | -0.03 | 0.0 | 0.0 | 1.8 | 19.0 | 0.3 | 0.2 | 0.0 | 0.2 | |
| VMP-11-8 | 12/19/2012 | 1437 | -0.02 | -0.07 | 0.0 | 0.0 | 1.8 | 19.0 | 0.5 | 1.4 | 0.0 | 1.4 | |
| VMP-11-8 | 1/16/2013 | 1519 | -0.02 | -0.02 | 0.0 | 0.0 | 1.2 | 19.5 | 0.6 | 3.5 | 0.0 | 3.5 | |
| VMP-11-8 | 2/25/2013 | 914 | -0.07 | -0.14 | 0.0 | 0.0 | 0.7 | 20.0 | 3.6 | 7.7 | 0.0 | 7.7 | |
| VMP-11-8 | 3/20/2013 | 1554 | -0.08 | -0.08 | 0.0 | 0.0 | 0.4 | 20.6 | 0.6 | 2.6 | 0.0 | 2.6 | |
| VMP-11-29 | 12/3/2012 | 1544 | -0.41 | -0.35 | 0.0 | 0.0 | 4.8 | 16.7 | 0.4 | 2.9 | 0.0 | 2.9 | Initail sample after Public Works SVE startup. |
| VMP-11-29 | 12/4/2012 | 1352 | -0.54 | -0.57 | 0.0 | 0.0 | 5.0 | 16.7 | 0.4 | 0.8 | 0.0 | 0.8 | |
| VMP-11-29 | 12/13/2012 | 1542 | -0.33 | -0.29 | 0.0 | 0.0 | 4.7 | 17.3 | 0.3 | 0.4 | 0.0 | 0.4 | |
| VMP-11-29 | 12/19/2012 | 1441 | -0.18 | -0.29 | 0.0 | 0.0 | 4.4 | 17.5 | 0.4 | 1.2 | 0.0 | 1.2 | |
| VMP-11-29 | 1/16/2013 | 1523 | -0.10 | -0.11 | 0.0 | 0.0 | 3.2 | 18.6 | 1.2 | 9.8 | 0.0 | 9.8 | |
| VMP-11-29 | 2/25/2013 | 919 | -0.38 | -0.38 | 0.0 | 0.0 | 2.3 | 19.2 | 2.2 | 5.2 | 0.0 | 5.2 | |
| VMP-11-29 | 3/20/2013 | 1558 | -0.43 | -0.40 | 0.0 | 0.0 | 2.0 | 19.6 | 0.9 | 2.2 | 0.0 | 2.2 | |
| VMP-11-38 | 12/3/2012 | 1545 | -0.40 | -0.36 | 0.0 | 0.0 | 10.6 | 10.6 | 0.6 | 13.8 | 12.7 | 1.1 | Initail sample after Public Works SVE startup. |
| VMP-11-38 | 12/4/2012 | 1353 | -0.52 | -0.56 | 0.0 | 0.0 | 9.5 | 11.9 | 0.5 | 7.4 | 7.3 | 0.1 | |
| VMP-11-38 | 12/13/2012 | 1546 | -0.34 | -0.28 | 0.0 | 0.0 | 10.2 | 11.2 | 0.5 | 13.6 | 13.6 | 0.0 | |
| VMP-11-38 | 12/19/2012 | 1445 | -0.16 | -0.27 | 0.0 | 0.0 | 10.1 | 11.3 | 0.5 | 8.1 | 8.1 | 0.0 | |
| VMP-11-38 | 1/16/2013 | 1527 | -0.10 | -0.11 | 0.0 | 0.0 | 8.7 | 12.9 | 1.2 | 12.8 | 8.5 | 4.3 | |
| VMP-11-38 | 2/25/2013 | 924 | -0.38 | -0.38 | 0.0 | 0.0 | 7.6 | 14.1 | 2.2 | 11.2 | 9.4 | 1.8 | |
| VMP-11-38 | 3/20/2013 | 1602 | -0.42 | -0.38 | 0.0 | 0.0 | 6.4 | 15.9 | 1.2 | 6.1 | 1.3 | 4.8 | |

SEE LAST PAGE OF TABLE FOR NOTES

**TABLE 10**
**SVE SYSTEM MONTHLY MONITORING - VMP SAMPLING DATA**

| Sample ID | Date | Initial Reading Time (24-Hour) | Vacuum/Pressure | | Fixed Gases | | | | Soil Vapor Concentrations | | | | Comments |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | Initial Reading (Inches of $H_2O$) | Stabilized Reading (Inches of $H_2O$) | CH4 (%) | LEL (%) | $CO_2$ (%) | $O_2$ (%) | PID (ppmv) | THC (ppmv) | CH4 (ppmv) | PHC (ppmv) | |
| VMP-12-5 | 2/6/2012 | 1020 | -0.14 | -0.07 | 23.1 | OVR | 11.9 | 1.0 | 35.9 | 125000 | 100000 | 25000 | |
| VMP-12-5 | 2/7/2012 | 822 | -0.29 | -0.21 | 0.1 | 3.0 | 10.8 | 4.5 | 21.3 | 912 | 880 | 31.9 | |
| VMP-12-5 | 2/8/2012 | 826 | -0.28 | -0.26 | 0.0 | 0.0 | 5.6 | 16.6 | 4.5 | 9.1 | 0.0 | 9.1 | |
| VMP-12-5 | 2/15/2012 | 850 | -0.12 | -0.19 | 0.0 | 0.0 | 3.1 | 18.0 | 15.0 | 101 | 8.1 | 92.9 | |
| VMP-12-5 | 2/22/2012 | 1025 | 0.08 | 0.05 | 1.8 | 36.0 | 4.2 | 9.4 | 21.8 | 15310 | 12780 | 2530 | |
| VMP-12-5 | 2/29/2012 | 1409 | 0.07 | 0.08 | OVR | OVR | 8.9 | 1.1 | 31.1 | 884000 | 790000 | 94000 | |
| VMP-12-5 | 3/6/2012 | 925 | -0.05 | - 0.02 | 0.2 | 5.0 | 8.5 | 5.0 | 2.6 | 1300 | 1300 | 0.0 | Benzene Reading: 2.8 ppm |
| VMP-12-5 | 3/7/2012 | 850 | -0.07 | - 0.03 | 8.9 | OVR | 9.2 | 2.8 | 15.7 | 49330 | 35700 | 13630 | Benzene Reading: 0.0 ppm |
| VMP-12-5 | 3/21/2012 | 840 | -0.23 | - 0.36 | 0.0 | 0.0 | 4.2 | 12.6 | 0.4 | 339 | 176 | 163 | |
| VMP-12-5 | 4/18/2012 | 1120 | -0.35 | -0.25 | 0.0 | 0.0 | 2.6 | 15.3 | 1.3 | 4.4 | 0.0 | 4.4 | |
| VMP-12-5 | 5/16/2012 | 821 | -1.28 | -1.20 | 0.0 | 0.0 | 2.5 | 18.5 | 2.9 | 3.9 | 0.0 | 3.9 | |
| VMP-12-5 | 6/20/2012 | 900 | -0.28 | -0.23 | 0.0 | 0.0 | 0.4 | 20.5 | 0.8 | 0.5 | 0.0 | 0.5 | |
| VMP-12-5 | 7/18/2012 | 935 | -0.20 | -0.17 | 0.0 | 0.0 | 0.1 | 20.8 | 0.7 | 3.1 | 0.0 | 3.1 | |
| VMP-12-5 | 8/15/2012 | 846 | -0.30 | -0.26 | 0.0 | 0.0 | 0.2 | 20.8 | 0.5 | 4.4 | 0.0 | 4.4 | |
| VMP-12-5 | 9/19/2012 | 925 | -0.65 | -0.48 | 0.0 | 0.0 | 0.3 | 20.2 | 0.4 | 1.6 | 0.0 | 1.6 | |
| VMP-12-5 | 10/17/2012 | 859 | -0.54 | -0.49 | 0.0 | 0.0 | 0.1 | 20.8 | 0.2 | 1.2 | 0.0 | 1.2 | |
| VMP-12-5 | 11/20/2012 | 923 | -0.79 | -0.70 | 0.0 | 0.0 | 0.0 | 20.9 | 0.5 | 2.9 | 0.0 | 2.9 | |
| VMP-12-5 | 12/19/2012 | 830 | -0.46 | -0.48 | 0.0 | 0.0 | 0.3 | 20.1 | 0.1 | 0.3 | 0.0 | 0.3 | |
| VMP-12-5 | 1/16/2013 | 915 | -0.37 | -0.21 | 0.0 | 0.0 | 0.1 | 20.6 | 0.1 | 0.5 | 0.0 | 0.5 | |
| VMP-12-5 | 2/25/2013 | 1255 | -0.11 | 0.08 | 0.0 | 0.0 | 0.0 | 20.9 | 0.1 | 0.2 | 0.0 | 0.2 | |
| VMP-12-5 | 3/20/2013 | 941 | -1.21 | -1.91 | 0.0 | 0.0 | 0.1 | 20.0 | 0.1 | 0.3 | 0.0 | 0.3 | |
| VMP-12-11.5 | 2/6/2012 | 1021 | -0.25 | -0.17 | 23.4 | OVR | 13.7 | 1.3 | 28.6 | 108000 | 100000 | 8000 | |
| VMP-12-11.5 | 2/7/2012 | 823 | -0.67 | -0.37 | 0.1 | 2.0 | 7.0 | 15.2 | 9.6 | 1085 | 744 | 341 | |
| VMP-12-11.5 | 2/8/2012 | 827 | -0.56 | -0.48 | 0.0 | 0.0 | 3.1 | 18.3 | 4.5 | 831 | 807 | 24.5 | |
| VMP-12-11.5 | 2/15/2012 | 851 | -0.20 | -0.17 | 2.1 | 43.0 | 6.3 | 12.0 | 9.4 | 20750 | 18300 | 2450 | |
| VMP-12-11.5 | 2/22/2012 | 1026 | 0.13 | 0.11 | OVR | OVR | 10.7 | 3.9 | 34.5 | 748000 | 748000 | 0.0 | |
| VMP-12-11.5 | 2/29/2012 | 1410 | 0.13 | 0.09 | OVR | OVR | 11.2 | 3.2 | 32.4 | 1000000 | 1000000 | 0.0 | |
| VMP-12-11.5 | 3/6/2012 | 928 | -0.13 | - 0.09 | OVR | OVR | 10.9 | 1.9 | 30.0 | 1000000 | 504000 | 496000 | Benzene Reading: 6.9 ppm |
| VMP-12-11.5 | 3/7/2012 | 851 | -0.10 | - 0.07 | 67.2 | OVR | 9.0 | 1.9 | 28.3 | 185000 | 73000 | 112000 | Benzene Reading: 5.7 ppm |
| VMP-12-11.5 | 3/21/2012 | 841 | -0.50 | - 0.05 | 0.8 | 16.0 | 4.4 | 14.7 | 0.5 | 8400 | 8400 | 0.0 | |
| VMP-12-11.5 | 4/18/2012 | 1121 | -0.43 | -0.36 | 1.6 | 33.0 | 7.8 | 8.4 | 4.4 | 18000 | 16100 | 1900 | |
| VMP-12-11.5 | 5/16/2012 | 821 | -0.72 | -0.69 | 0.0 | 0.0 | 1.7 | 19.0 | 3.9 | 36.4 | 12.2 | 24.2 | |
| VMP-12-11.5 | 6/20/2012 | 904 | -0.65 | -0.54 | 0.0 | 0.0 | 0.4 | 20.4 | 0.4 | 0.0 | 0.0 | 0.0 | |
| VMP-12-11.5 | 7/18/2012 | 939 | -0.52 | -0.46 | 0.0 | 0.0 | 0.1 | 20.8 | 0.8 | 3.2 | 0.0 | 3.2 | |
| VMP-12-11.5 | 8/15/2012 | 850 | -0.57 | -0.48 | 0.0 | 0.0 | 0.2 | 20.8 | 0.6 | 3.6 | 0.0 | 3.6 | |
| VMP-12-11.5 | 9/19/2012 | 925 | -0.98 | -0.80 | 0.0 | 0.0 | 0.1 | 20.7 | 0.9 | 3.3 | 0.0 | 3.3 | |
| VMP-12-11.5 | 10/17/2012 | 900 | -0.90 | -0.74 | 0.0 | 0.0 | 0.1 | 20.9 | 0.3 | 2.3 | 0.0 | 2.3 | |
| VMP-12-11.5 | 11/20/2012 | 924 | -1.30 | -1.16 | 0.0 | 0.0 | 0.0 | 20.9 | 0.6 | 2.4 | 0.0 | 2.4 | |
| VMP-12-11.5 | 12/19/2012 | 834 | -0.55 | -0.61 | 0.0 | 0.0 | 0.3 | 20.6 | 0.1 | 0.6 | 0.0 | 0.6 | |
| VMP-12-11.5 | 1/16/2013 | 920 | -0.48 | -0.28 | 0.0 | 0.0 | 0.2 | 20.7 | 0.1 | 1.6 | 0.0 | 1.6 | |
| VMP-12-11.5 | 2/25/2013 | 1259 | -0.93 | 0.05 | 0.0 | 0.0 | 2.9 | 13.8 | 0.2 | 0.8 | 0.0 | 0.8 | |
| VMP-12-11.5 | 3/20/2013 | 947 | -1.22 | -1.15 | 0.0 | 0.0 | 1.3 | 18.3 | 0.3 | 2.8 | 0.0 | 2.8 | |

SEE LAST PAGE OF TABLE FOR NOTES

**TABLE 10**
**SVE SYSTEM MONTHLY MONITORING - VMP SAMPLING DATA**

| Sample ID | Date | Initial Reading Time (24-Hour) | Vacuum/Pressure | | Fixed Gases | | | | Soil Vapor Concentrations | | | | Comments |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | Initial Reading (Inches of $H_2O$) | Stabilized Reading (Inches of $H_2O$) | CH4 (%) | LEL (%) | $CO_2$ (%) | $O_2$ (%) | PID (ppmv) | THC (ppmv) | CH4 (ppmv) | PHC (ppmv) | |
| VMP-12-25 | 2/6/2012 | 1022 | -0.43 | -0.21 | OVR | OVR | 12.8 | 0.9 | 76.3 | 1000000 | 453000 | 547000 | |
| VMP-12-25 | 2/7/2012 | 824 | -0.85 | -0.43 | OVR | OVR | 12.1 | 2.0 | 69.6 | 821000 | 525000 | 296000 | |
| VMP-12-25 | 2/8/2012 | 828 | -0.59 | -0.50 | OVR | OVR | 12.1 | 1.5 | 67.1 | 684000 | 598000 | 86000 | |
| VMP-12-25 | 2/15/2012 | 852 | -0.19 | -0.37 | OVR | OVR | 12.2 | 1.5 | 50.0 | 850000 | 850000 | 0.0 | |
| VMP-12-25 | 2/22/2012 | 1027 | 0.18 | 0.16 | OVR | OVR | 12.0 | 1.3 | 50.3 | 1000000 | 1000000 | 0.0 | |
| VMP-12-25 | 2/29/2012 | 1411 | -0.44 | -0.34 | OVR | OVR | 12.4 | 1.5 | 50.3 | 1000000 | 950000 | 50000 | |
| VMP-12-25 | 3/6/2012 | 931 | -0.55 | - 0.34 | OVR | OVR | 11.5 | 1.3 | 51.6 | 1000000 | 1000000 | 0.0 | Benzene Reading: 23.0 ppm |
| VMP-12-25 | 3/7/2012 | 852 | -0.30 | - 0.17 | OVR | OVR | 12.1 | 1.7 | 43.7 | 957000 | 666000 | 291000 | Benzene Reading: 19.4 ppm |
| VMP-12-25 | 3/21/2012 | 842 | -0.60 | - 0.62 | OVR | OVR | 11.5 | 0.5 | 37.8 | 1000000 | 1000000 | 0.0 | |
| VMP-12-25 | 4/18/2012 | 1122 | -0.54 | -0.46 | OVR | OVR | 9.5 | 1.0 | 45.0 | 624000 | 444000 | 180000 | |
| VMP-12-25 | 5/16/2012 | 822 | -0.86 | -0.83 | OVR | OVR | 9.1 | 2.1 | 46.1 | 271000 | 222000 | 49000 | |
| VMP-12-25 | 6/20/2012 | 908 | -0.88 | -0.73 | 48.3 | OVR | 9.4 | 1.4 | 62.0 | 108000 | 83000 | 25000 | |
| VMP-12-25 | 7/18/2012 | 949 | -0.80 | -0.68 | 30.4 | OVR | 10.1 | 1.8 | 74.5 | 58500 | 46700 | 11800 | |
| VMP-12-25 | 8/15/2012 | 855 | -0.93 | -0.77 | 12.7 | OVR | 13.7 | 0.7 | 84.0 | 20800 | 20200 | 600 | |
| VMP-12-25 | 9/19/2012 | 925 | -1.51 | -1.30 | 0.9 | 18.0 | 12.4 | 3.8 | 29.2 | 8000 | 6100 | 1900 | |
| VMP-12-25 | 10/17/2012 | 901 | -1.29 | -1.17 | 11.5 | OVR | 13.5 | 0.7 | 98.5 | 24100 | 18400 | 5700 | |
| VMP-12-25 | 11/20/2012 | 929 | -1.96 | -1.84 | 0.1 | 2.0 | 6.0 | 11.1 | 24.9 | 324 | 83.0 | 241 | |
| VMP-12-25 | 12/19/2012 | 838 | -0.67 | -0.77 | 23.2 | OVR | 13.1 | 1.1 | 46.9 | 106000 | 91000 | 15000 | |
| VMP-12-25 | 1/16/2013 | 925 | -0.61 | -0.36 | 27.0 | OVR | 12.7 | 1.3 | 46.5 | 116000 | 93000 | 23000 | |
| VMP-12-25 | 2/25/2013 | 1304 | -0.20 | -0.80 | 57.2 | OVR | 13.0 | 1.0 | 29.2 | 171000 | 134000 | 37000 | |
| VMP-12-25 | 3/20/2013 | 1000 | -0.67 | -1.30 | 34.2 | OVR | 11.8 | 1.2 | 17.4 | 257000 | 234000 | 23000 | |
| VMP-12-39 | 2/6/2012 | 1023 | -0.07 | 0.07 | OVR | OVR | 12.9 | 1.0 | 69.8 | 1000000 | 772000 | 228000 | |
| VMP-12-39 | 2/7/2012 | 825 | -0.48 | -0.40 | OVR | OVR | 12.3 | 2.0 | 57.1 | 881000 | 867000 | 14000 | |
| VMP-12-39 | 2/8/2012 | 829 | -0.60 | -0.51 | OVR | OVR | 12.2 | 2.0 | 60.1 | 802000 | 494000 | 308000 | |
| VMP-12-39 | 2/15/2012 | 853 | -0.19 | -0.39 | OVR | OVR | 12.5 | 1.0 | 45.7 | 1000000 | 1000000 | 0.0 | |
| VMP-12-39 | 2/22/2012 | 1028 | 0.17 | 0.20 | OVR | OVR | 12.3 | 1.2 | 40.9 | 1000000 | 1000000 | 0.0 | |
| VMP-12-39 | 2/29/2012 | 1412 | -0.06 | 0.09 | OVR | OVR | 11.8 | 2.5 | 47.3 | 1000000 | 1000000 | 0.0 | |
| VMP-12-39 | 3/6/2012 | 935 | -0.03 | - 0.03 | OVR | OVR | 11.8 | 1.3 | 57.5 | 1000000 | 520000 | 480000 | Benzene Reading: 27.5 ppm |
| VMP-12-39 | 3/7/2012 | 853 | -0.10 | - 0.03 | OVR | OVR | 11.8 | 1.6 | 49.9 | 1000000 | 944000 | 56000 | Benzene Reading: 21.3 ppm |
| VMP-12-39 | 3/21/2012 | 843 | -0.63 | - 0.66 | OVR | OVR | 12.3 | 0.7 | 42.4 | 1000000 | 1000000 | 0.0 | |
| VMP-12-39 | 4/18/2012 | 1123 | -0.58 | -0.51 | OVR | OVR | 11.4 | 1.0 | 53.3 | 1000000 | 800000 | 200000 | |
| VMP-12-39 | 5/16/2012 | 822 | -0.93 | -0.89 | OVR | OVR | 10.9 | 1.5 | 100 | 480000 | 430000 | 50000 | |
| VMP-12-39 | 6/20/2012 | 912 | -0.92 | -0.79 | OVR | OVR | 10.1 | 1.9 | 117 | 321000 | 285000 | 36000 | |
| VMP-12-39 | 7/18/2012 | 944 | -0.85 | -0.72 | OVR | OVR | 10.8 | 1.7 | 68.0 | 224000 | 180000 | 44000 | |
| VMP-12-39 | 8/15/2012 | 900 | -0.93 | -0.83 | OVR | OVR | 12.8 | 0.6 | 156 | 142000 | 122000 | 20000 | |
| VMP-12-39 | 9/19/2012 | 925 | -1.57 | -1.36 | OVR | OVR | 13.6 | 1.5 | 202 | 201000 | 176000 | 25000 | |
| VMP-12-39 | 10/17/2012 | 902 | -1.37 | -1.24 | OVR | OVR | 14.0 | 1.1 | 151 | 136000 | 118000 | 18000 | |
| VMP-12-39 | 11/20/2012 | 930 | -2.07 | -1.99 | 69.3 | OVR | 13.7 | 0.8 | 189 | 146000 | 117000 | 29000 | |
| VMP-12-39 | 12/19/2012 | 842 | -0.71 | -0.81 | 85.0 | OVR | 14.5 | 0.8 | 135 | 260000 | 200000 | 60000 | |
| VMP-12-39 | 1/16/2013 | 930 | -0.65 | -0.05 | OVR | OVR | 13.9 | 1.5 | 100 | 370000 | 280000 | 90000 | |
| VMP-12-39 | 2/25/2013 | 1309 | -0.23 | -0.40 | OVR | OVR | 14.6 | 1.5 | 70.3 | 560000 | 233000 | 327000 | |
| VMP-12-39 | 3/20/2013 | 1022 | -1.33 | -1.20 | 84.5 | OVR | 14.0 | 1.3 | 26.3 | 805000 | 614000 | 191000 | |

SEE LAST PAGE OF TABLE FOR NOTES

**TABLE 10**
**SVE SYSTEM MONTHLY MONITORING - VMP SAMPLING DATA**

| Sample ID | Date | Initial Reading Time (24-Hour) | Vacuum/Pressure | | Fixed Gases | | | | Soil Vapor Concentrations | | | | Comments |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | Initial Reading (Inches of $H_2O$) | Stabilized Reading (Inches of $H_2O$) | CH4 (%) | LEL (%) | $CO_2$ (%) | $O_2$ (%) | PID (ppmv) | THC (ppmv) | CH4 (ppmv) | PHC (ppmv) | |
| VMP-13-5 | 12/5/2012 | 1506 | -0.10 | -0.10 | 0.0 | 0.0 | 0.6 | 20.4 | 0.3 | 1.3 | 0.0 | 1.3 | Initail sample after Public Works SVE startup. |
| VMP-13-5 | 12/6/2012 | 1413 | -0.04 | -0.09 | 0.0 | 0.0 | 0.6 | 20.6 | 0.1 | 0.7 | 0.0 | 0.7 | |
| VMP-13-5 | 12/13/2012 | 1050 | -0.06 | -0.06 | 0.0 | 0.0 | 0.5 | 20.7 | 0.2 | 0.2 | 0.0 | 0.2 | |
| VMP-13-5 | 12/19/2012 | 1320 | -0.03 | -0.06 | 0.0 | 0.0 | 0.3 | 20.7 | 0.3 | 0.6 | 0.0 | 0.6 | |
| VMP-13-5 | 1/16/2013 | 1433 | -0.06 | -0.02 | 0.0 | 0.0 | 0.2 | 20.8 | 0.2 | 1.6 | 0.0 | 1.6 | |
| VMP-13-5 | 2/25/2013 | 940 | -0.09 | -0.09 | 0.0 | 0.0 | 0.1 | 20.8 | 0.3 | 1.0 | 0.0 | 1.0 | |
| VMP-13-5 | 3/20/2013 | 1450 | -0.10 | -0.10 | 0.0 | 0.0 | 0.2 | 20.8 | 0.6 | 2.2 | 0.0 | 2.2 | |
| VMP-13-10.5 | 12/5/2012 | 1507 | -0.21 | -0.21 | 0.0 | 0.0 | 1.4 | 19.7 | 0.4 | 0.8 | 0.0 | 0.8 | Initail sample after Public Works SVE startup. |
| VMP-13-10.5 | 12/6/2012 | 1413 | -0.14 | -0.23 | 0.0 | 0.0 | 1.4 | 19.7 | 0.3 | 2.1 | 0.0 | 2.1 | |
| VMP-13-10.5 | 12/13/2012 | 1052 | -0.15 | -0.13 | 0.0 | 0.0 | 1.0 | 20.4 | 0.1 | 0.9 | 0.0 | 0.9 | |
| VMP-13-10.5 | 12/19/2012 | 1325 | -0.11 | -0.17 | 0.0 | 0.0 | 0.8 | 20.5 | 0.5 | 0.4 | 0.0 | 0.4 | |
| VMP-13-10.5 | 1/16/2013 | 1437 | -0.16 | -0.06 | 0.0 | 0.0 | 0.4 | 20.6 | 0.2 | 1.0 | 0.0 | 1.0 | |
| VMP-13-10.5 | 2/25/2013 | 945 | -0.20 | -0.22 | 0.0 | 0.0 | 0.2 | 20.7 | 0.3 | 1.1 | 0.0 | 1.1 | |
| VMP-13-10.5 | 3/20/2013 | 1454 | -0.21 | -0.23 | 0.0 | 0.0 | 0.3 | 20.7 | 0.4 | 1.5 | 0.0 | 1.5 | |
| VMP-13-21.5 | 12/5/2012 | 1516 | -0.52 | -0.46 | 0.0 | 0.0 | 12.0 | 6.0 | 0.7 | 2.6 | 0.0 | 2.6 | Initail sample after Public Works SVE startup. |
| VMP-13-21.5 | 12/6/2012 | 1414 | -0.40 | -0.54 | 0.0 | 0.0 | 9.1 | 11.5 | 0.7 | 0.5 | 0.0 | 0.5 | |
| VMP-13-21.5 | 12/13/2012 | 1054 | -0.42 | -0.37 | 0.0 | 0.0 | 4.3 | 18.0 | 0.3 | 0.3 | 0.0 | 0.3 | |
| VMP-13-21.5 | 12/19/2012 | 1330 | -0.35 | -0.44 | 0.0 | 0.0 | 3.0 | 19.4 | 0.5 | 0.2 | 0.0 | 0.2 | |
| VMP-13-21.5 | 1/16/2013 | 1441 | -0.43 | -0.14 | 0.0 | 0.0 | 1.7 | 20.0 | 0.2 | 0.9 | 0.0 | 0.9 | |
| VMP-13-21.5 | 2/25/2013 | 950 | -0.50 | -0.49 | 0.0 | 0.0 | 0.9 | 20.4 | 0.3 | 1.3 | 0.0 | 1.3 | |
| VMP-13-21.5 | 3/20/2013 | 1458 | -0.51 | -0.55 | 0.0 | 0.0 | 0.6 | 20.6 | 0.6 | 1.6 | 0.0 | 1.6 | |
| VMP-13-29.5 | 12/5/2012 | 1520 | -0.41 | -0.40 | 0.0 | 0.0 | 15.6 | 0.9 | 355 | 965 | 525 | 440 | Initail sample after Public Works SVE startup. |
| VMP-13-29.5 | 12/6/2012 | 1415 | -0.32 | -0.44 | 0.0 | 0.0 | 16.5 | 1.3 | 286 | 417 | 210 | 207 | |
| VMP-13-29.5 | 12/13/2012 | 1056 | -0.30 | -0.27 | 0.0 | 1.0 | 13.8 | 0.7 | 135 | 258 | 110 | 148 | |
| VMP-13-29.5 | 12/19/2012 | 1335 | -0.24 | -0.34 | 0.0 | 0.0 | 10.9 | 9.1 | 1.4 | 89.9 | 61.0 | 28.9 | |
| VMP-13-29.5 | 1/16/2013 | 1445 | -0.35 | -0.12 | 0.0 | 0.0 | 5.9 | 15.1 | 69.3 | 145 | 60.3 | 84.7 | |
| VMP-13-29.5 | 2/25/2013 | 955 | -0.40 | -0.43 | 0.0 | 0.0 | 4.0 | 16.7 | 265 | 460 | 28.1 | 432 | |
| VMP-13-29.5 | 3/20/2013 | 1502 | -0.41 | -0.42 | 0.0 | 0.0 | 3.5 | 17.6 | 190 | 247 | 24.1 | 223 | |
| VMP-14-5 | 12/11/2012 | 1504 | -0.03 | -0.03 | 0.0 | 0.0 | 0.2 | 20.8 | 0.3 | 0.4 | 0.0 | 0.4 | Initail sample after Public Works SVE startup. |
| VMP-14-5 | 12/12/2012 | 1611 | -0.01 | 0.00 | 0.0 | 0.0 | 0.2 | 20.8 | 0.2 | 0.3 | 0.0 | 0.3 | |
| VMP-14-5 | 12/13/2012 | 1009 | 0.00 | 0.00 | 0.0 | 0.0 | 0.0 | 20.9 | 0.1 | 0.6 | 0.0 | 0.6 | |
| VMP-14-5 | 12/19/2012 | 1352 | -0.01 | -0.41 | 0.0 | 0.0 | 0.1 | 20.6 | 0.2 | 0.2 | 0.0 | 0.2 | |
| VMP-14-5 | 1/16/2013 | 1449 | 0.00 | -0.01 | 0.0 | 0.0 | 0.1 | 20.8 | 0.3 | 1.3 | 0.0 | 1.3 | |
| VMP-14-5 | 2/25/2013 | 1015 | -0.04 | 0.00 | 0.0 | 0.0 | 0.0 | 20.9 | 0.3 | 0.8 | 0.0 | 0.8 | |
| VMP-14-5 | 3/20/2013 | 1515 | -0.03 | -0.04 | 0.0 | 0.0 | 0.0 | 20.9 | 0.4 | 2.3 | 0.0 | 2.3 | |
| VMP-14-11.5 | 12/11/2012 | 1505 | -0.05 | -0.04 | 0.0 | 0.0 | 2.0 | 19.7 | 0.4 | 0.6 | 0.0 | 0.6 | Initail sample after Public Works SVE startup. |
| VMP-14-11.5 | 12/12/2012 | 1614 | -0.08 | -0.06 | 0.0 | 0.0 | 1.7 | 19.8 | 3.2 | 7.9 | 0.0 | 7.9 | |
| VMP-14-11.5 | 12/13/2012 | 1009 | -0.05 | -0.03 | 0.0 | 0.0 | 1.4 | 20.2 | 8.9 | 19.0 | 0.0 | 19.0 | |
| VMP-14-11.5 | 12/19/2012 | 1356 | -0.04 | -0.25 | 0.0 | 0.0 | 1.6 | 19.6 | 0.9 | 1.9 | 0.0 | 1.9 | |
| VMP-14-11.5 | 1/16/2013 | 1453 | -0.10 | -0.03 | 0.0 | 0.0 | 1.0 | 19.5 | 0.3 | 0.8 | 0.0 | 0.8 | |
| VMP-14-11.5 | 2/25/2013 | 1020 | -0.05 | 0.00 | 0.0 | 0.0 | 0.6 | 20.4 | 3.2 | 7.0 | 0.0 | 7.0 | |
| VMP-14-11.5 | 3/20/2013 | 1519 | -0.04 | -0.05 | 0.0 | 0.0 | 0.4 | 20.5 | 0.2 | 1.7 | 0.0 | 1.7 | |

SEE LAST PAGE OF TABLE FOR NOTES

**TABLE 10**
**SVE SYSTEM MONTHLY MONITORING - VMP SAMPLING DATA**

| Sample ID | Date | Initial Reading Time (24-Hour) | Vacuum/Pressure | | Fixed Gases | | | | Soil Vapor Concentrations | | | | Comments |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | Initial Reading (Inches of $H_2O$) | Stabilized Reading (Inches of $H_2O$) | CH4 (%) | LEL (%) | $CO_2$ (%) | $O_2$ (%) | PID (ppmv) | THC (ppmv) | CH4 (ppmv) | PHC (ppmv) | |
| VMP-14-20 | 12/11/2012 | 1506 | -0.11 | -0.09 | 56.3 | OVR | 16.4 | 1.7 | 1320 | 77900 | 42800 | 35100 | Initail sample after Public Works SVE startup. |
| VMP-14-20 | 12/12/2012 | 1614 | -0.10 | -0.11 | 46.5 | OVR | 14.6 | 4.1 | 1210 | 57000 | 34400 | 22600 | |
| VMP-14-20 | 12/13/2012 | 1010 | -0.02 | -0.04 | 53.1 | OVR | 16.4 | 2.4 | 1030 | 72900 | 39900 | 33000 | |
| VMP-14-20 | 12/19/2012 | 1400 | -0.16 | -0.03 | 42.5 | OVR | 14.4 | 2.4 | 1350 | 63500 | 39200 | 24300 | |
| VMP-14-20 | 1/16/2013 | 1457 | -0.68 | -0.07 | 43.5 | OVR | 13.7 | 2.9 | 1150 | 62900 | 33800 | 29100 | Manometer reading rechecked and verified. |
| VMP-14-20 | 2/25/2013 | 1025 | -0.12 | -0.01 | 19.0 | OVR | 10.9 | 5.8 | 1090 | 29100 | 22000 | 7100 | |
| VMP-14-20 | 3/20/2013 | 1523 | -0.04 | -0.09 | 14.5 | OVR | 9.5 | 6.9 | 960 | 26900 | 19500 | 7400 | |
| VMP-14-29 | 12/11/2012 | 1507 | -0.11 | -0.09 | 81.1 | OVR | 17.2 | 0.7 | 1720 | 106000 | 51900 | 54100 | Initail sample after Public Works SVE startup. |
| VMP-14-29 | 12/12/2012 | 1614 | -0.10 | -0.10 | 79.0 | OVR | 17.5 | 0.5 | 1710 | 102000 | 52700 | 49300 | |
| VMP-14-29 | 12/13/2012 | 1010 | -0.11 | -0.05 | 81.3 | OVR | 17.8 | 0.7 | 1370 | 110000 | 57800 | 52200 | |
| VMP-14-29 | 12/19/2012 | 1404 | 0.06 | -0.04 | 76.1 | OVR | 16.5 | 1.3 | 1570 | 100000 | 62900 | 37100 | |
| VMP-14-29 | 1/16/2013 | 1501 | -0.04 | -0.05 | 83.0 | OVR | 15.7 | 1.0 | 1390 | 107000 | 52000 | 55000 | |
| VMP-14-29 | 2/25/2013 | 1030 | -0.12 | -0.01 | 67.5 | OVR | 11.6 | 4.4 | 1705 | 69800 | 33300 | 36500 | |
| VMP-14-29 | 3/20/2013 | 1527 | -0.08 | -0.11 | 85.3 | OVR | 13.6 | 0.9 | 1475 | 101000 | 58700 | 42300 | |
| VMP-17-5 | 3/6/2012 | 1333 | -0.05 | - 0.02 | 0.0 | 0.0 | 1.1 | 20.4 | 0.2 | 1.1 | 0.0 | 1.1 | Benzene Reading: 0.0 ppm |
| VMP-17-5 | 3/7/2012 | 1003 | 0.00 | 0.03 | 0.0 | 0.0 | 1.2 | 20.6 | 0.4 | 0.0 | 0.0 | 0.0 | Benzene Reading: 0.0 ppm |
| VMP-17-5 | 3/21/2012 | 1310 | 0.00 | 0.00 | 0.0 | 0.0 | 1.2 | 19.7 | 1.1 | 0.0 | 0.0 | 0.0 | |
| VMP-17-5 | 4/18/2012 | 1131 | 0.00 | 0.00 | 0.0 | 0.0 | 1.0 | 20.5 | 0.7 | 4.9 | 0.0 | 4.9 | |
| VMP-17-5 | 5/16/2012 | 1326 | -0.02 | -0.01 | 0.0 | 0.0 | 1.2 | 19.8 | 0.6 | 0.0 | 0.0 | 0.0 | |
| VMP-17-5 | 6/20/2012 | 813 | 0.00 | 0.00 | 0.0 | 0.0 | 0.9 | 20.1 | 0.1 | 0.0 | 0.0 | 0.0 | |
| VMP-17-5 | 7/18/2012 | 837 | -0.01 | -0.01 | 0.0 | 0.0 | 0.6 | 20.5 | 0.4 | 0.6 | 0.0 | 0.6 | |
| VMP-17-5 | 8/15/2012 | 820 | -0.01 | 0.00 | 0.0 | 0.0 | 0.5 | 20.6 | 0.5 | 2.4 | 0.0 | 2.4 | |
| VMP-17-5 | 9/19/2012 | 1117 | 0.00 | 0.00 | 0.0 | 0.0 | 0.4 | 20.5 | 0.5 | 1.5 | 0.0 | 1.5 | |
| VMP-17-5 | 10/17/2012 | 1345 | 0.00 | 0.00 | 0.0 | 0.0 | 0.4 | 20.5 | 0.4 | 1.2 | 0.0 | 1.2 | |
| VMP-17-5 | 11/20/2012 | 1145 | -0.04 | -0.03 | 0.0 | 0.0 | 0.2 | 20.8 | 0.2 | 1.4 | 0.0 | 1.4 | |
| VMP-17-5 | 12/3/2012 | 1330 | 0.00 | 0.00 | 0.0 | 0.0 | 0.4 | 20.5 | 0.2 | 4.0 | 0.0 | 4.0 | |
| VMP-17-5 | 12/4/2012 | 1341 | -0.09 | -0.02 | 0.0 | 0.0 | 0.3 | 20.7 | 0.3 | 1.3 | 0.0 | 1.3 | |
| VMP-17-5 | 12/19/2012 | 1442 | -0.01 | -0.02 | 0.0 | 0.0 | 0.3 | 20.8 | 0.3 | 0.8 | 0.0 | 0.8 | |
| VMP-17-5 | 1/16/2013 | 1154 | -0.01 | -0.01 | 0.0 | 0.0 | 0.1 | 20.8 | 0.1 | 1.1 | 0.0 | 1.1 | |
| VMP-17-5 | 2/25/2013 | 1405 | 0.00 | 0.00 | 0.0 | 0.0 | 0.0 | 20.9 | 0.2 | 0.7 | 0.0 | 0.7 | |
| VMP-17-5 | 3/20/2013 | 1607 | -0.11 | -0.01 | 0.0 | 0.0 | 0.0 | 20.9 | 0.1 | 3.1 | 0.0 | 3.1 | |
| VMP-18-8.5 | 12/3/2012 | 1623 | -0.05 | -0.14 | 0.0 | 0.0 | 2.0 | 19.6 | 0.2 | 3.8 | 0.0 | 3.8 | Initail sample after Public Works SVE startup. |
| VMP-18-8.5 | 12/4/2012 | 1445 | -0.26 | -0.05 | 0.0 | 0.0 | 1.9 | 19.9 | 0.3 | 1.8 | 0.0 | 1.8 | |
| VMP-18-8.5 | 12/19/2012 | 1431 | -0.13 | -0.02 | 0.0 | 0.0 | 2.1 | 19.9 | 0.3 | 0.2 | 0.0 | 0.2 | |
| VMP-18-8.5 | 1/16/2013 | 1202 | -0.08 | -0.01 | 0.0 | 0.0 | 0.8 | 20.4 | 0.2 | 1.0 | 0.0 | 1.0 | |
| VMP-18-8.5 | 2/25/2013 | 857 | -0.13 | -0.15 | 0.0 | 0.0 | 0.5 | 20.5 | 0.3 | 1.5 | 0.0 | 1.5 | |
| VMP-18-8.5 | 3/20/2013 | 1354 | -0.15 | -0.09 | 0.0 | 0.0 | 0.4 | 20.7 | 0.4 | 2.8 | 0.0 | 2.8 | |

SEE LAST PAGE OF TABLE FOR NOTES

**TABLE 10**
**SVE SYSTEM MONTHLY MONITORING - VMP SAMPLING DATA**

| Sample ID | Date | Initial Reading Time (24-Hour) | Vacuum/Pressure | | Fixed Gases | | | | Soil Vapor Concentrations | | | | Comments |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | Initial Reading (Inches of $H_2O$) | Stabilized Reading (Inches of $H_2O$) | CH4 (%) | LEL (%) | $CO_2$ (%) | $O_2$ (%) | PID (ppmv) | THC (ppmv) | CH4 (ppmv) | PHC (ppmv) | |
| VMP-19-5 | 3/6/2012 | 1315 | -0.04 | - 0.02 | 0.0 | 0.0 | 2.4 | 19.7 | 0.3 | 2.2 | 0.0 | 2.2 | Benzene Reading: 0.0 ppm |
| VMP-19-5 | 3/7/2012 | NM | NM | NM | NM | NM | NM | NM | NM | NM | NM | NM | Car parked over well. Could not sample. |
| VMP-19-5 | 3/21/2012 | 1315 | 0.00 | 0.00 | 0.0 | 0.0 | 1.8 | 19.8 | 1.0 | 0.0 | 0.0 | 0.0 | |
| VMP-19-5 | 4/18/2012 | 1138 | -0.03 | -0.01 | 0.0 | 0.0 | 1.3 | 19.9 | 0.8 | 2.6 | 0.0 | 2.6 | |
| VMP-19-5 | 5/16/2012 | 1443 | 0.00 | -0.01 | 0.0 | 0.0 | 1.1 | 19.8 | 0.7 | 0.0 | 0.0 | 0.0 | |
| VMP-19-5 | 6/20/2012 | 840 | -0.03 | -0.01 | 0.0 | 0.0 | 1.4 | 19.7 | 0.2 | 0.0 | 0.0 | 0.0 | |
| VMP-19-5 | 7/18/2012 | 1259 | 0.00 | -0.01 | 0.0 | 0.0 | 0.9 | 20.1 | 0.9 | 3.8 | 0.0 | 3.8 | |
| VMP-19-5 | 8/15/2012 | 1030 | -0.05 | -0.02 | 0.0 | 0.0 | 0.5 | 20.6 | 0.3 | 3.4 | 0.0 | 3.4 | |
| VMP-19-5 | 9/19/2012 | 1405 | 0.00 | 0.00 | 0.0 | 0.0 | 0.6 | 20.2 | 0.5 | 2.3 | 0.0 | 2.3 | |
| VMP-19-5 | 10/17/2012 | 1039 | -0.05 | 0.00 | 0.0 | 0.0 | 0.5 | 20.5 | 0.2 | 1.8 | 0.0 | 1.8 | |
| VMP-19-5 | 11/20/2012 | 1133 | -0.07 | -0.07 | 0.0 | 0.0 | 0.2 | 20.8 | 0.4 | 1.3 | 0.0 | 1.3 | |
| VMP-19-5 | 12/3/2012 | 1614 | -0.02 | -0.03 | 0.0 | 0.0 | 0.2 | 20.6 | 0.3 | 4.4 | 0.0 | 4.4 | |
| VMP-19-5 | 12/4/2012 | 1458 | -0.04 | -0.06 | 0.0 | 0.0 | 0.2 | 20.7 | 0.2 | 3.2 | 0.0 | 3.2 | |
| VMP-19-5 | 12/19/2012 | 1422 | -0.04 | -0.04 | 0.0 | 0.0 | 0.2 | 20.8 | 0.3 | 0.5 | 0.0 | 0.5 | |
| VMP-19-5 | 1/16/2013 | 1145 | -0.02 | -0.04 | 0.0 | 0.0 | 0.2 | 20.8 | 0.1 | 3.4 | 0.0 | 3.4 | |
| VMP-19-5 | 2/25/2013 | 849 | -0.02 | -0.01 | 0.0 | 0.0 | 0.1 | 20.8 | 0.4 | 2.1 | 0.0 | 2.1 | |
| VMP-19-5 | 3/20/2013 | 1404 | -0.05 | 0.00 | 0.0 | 0.0 | 0.2 | 20.8 | 0.5 | 3.4 | 0.0 | 3.4 | |
| VMP-26-10 | 2/2/2012 | 1106 | -1.36 | -1.20 | OVR | OVR | 8.2 | 1.5 | 414 | 51800 | 26500 | 25300 | |
| VMP-26-10 | 2/7/2012 | 940 | -1.21 | -1.01 | 0.2 | 5.0 | 0.3 | 20.4 | 33.3 | 1636 | 1351 | 285 | |
| VMP-26-10 | 2/10/2012 | 1136 | -0.74 | -0.98 | 0.0 | 0.0 | 0.1 | 20.6 | 13.0 | 52.9 | 10.7 | 42.2 | |
| VMP-26-10 | 2/13/2012 | 959 | -1.03 | -0.80 | 35.1 | OVR | 7.1 | 4.2 | 687 | 9420 | 2060 | 7360 | |
| VMP-26-10 | 2/15/2012 | 1324 | -1.22 | -0.97 | 53.5 | OVR | 6.4 | 6.4 | 765 | 11490 | 1170 | 10320 | |
| VMP-26-10 | 2/22/2012 | 1103 | -0.77 | -0.71 | 0.0 | 0.0 | 0.2 | 20.7 | 23.6 | 33.3 | 12.1 | 21.2 | |
| VMP-26-10 | 2/29/2012 | 1003 | -0.72 | -0.72 | 0.9 | 18.0 | 0.9 | 19.0 | 229 | 1340 | 203 | 1137 | |
| VMP-26-10 | 3/21/2012 | 1005 | -0.82 | -0.70 | 0.3 | 6.0 | 0.4 | 20.2 | 92.6 | 376 | 43.5 | 333 | |
| VMP-26-10 | 4/18/2012 | 942 | -1.26 | -1.10 | 0.3 | 6.0 | 0.5 | 20.1 | 85.6 | 415 | 15.2 | 400 | |
| VMP-26-10 | 5/16/2012 | 1004 | -1.30 | -1.35 | 0.1 | 3.0 | 0.4 | 20.3 | 51.6 | 305 | 11.0 | 294 | |
| VMP-26-10 | 6/20/2012 | 1024 | -1.19 | -1.22 | 0.1 | 2.0 | 0.1 | 20.7 | 26.4 | 121 | 0.0 | 121 | |
| VMP-26-10 | 7/18/2012 | 1038 | -1.13 | -1.03 | 0.0 | 0.0 | 0.0 | 20.8 | 17.5 | 52.4 | 0.0 | 52.4 | |
| VMP-26-10 | 8/15/2012 | 1018 | -1.20 | -1.20 | 0.0 | 1.0 | 0.4 | 20.6 | 80.0 | 232 | 34.9 | 197 | |
| VMP-26-10 | 9/19/2012 | 1108 | -1.75 | -1.65 | 0.1 | 3.0 | 0.5 | 20.3 | 104 | 316 | 41.3 | 275 | |
| VMP-26-10 | 10/17/2012 | 1012 | -2.01 | -2.04 | 0.1 | 3.0 | 1.8 | 18.9 | 103 | 259 | 36.0 | 223 | |
| VMP-26-10 | 11/20/2012 | 1008 | -1.78 | -1.55 | 0.0 | 0.0 | 0.1 | 20.8 | 9.6 | 21.4 | 5.1 | 16.3 | |
| VMP-26-10 | 12/19/2012 | 1128 | -0.90 | -0.91 | 0.0 | 0.0 | 0.1 | 20.9 | 0.5 | 3.1 | 0.0 | 3.1 | |
| VMP-26-10 | 1/16/2013 | 1009 | -1.04 | -0.81 | 0.0 | 0.0 | 2.7 | 17.1 | 7.3 | 34.9 | 2.5 | 32.4 | |
| VMP-26-10 | 2/25/2013 | 1044 | -1.15 | -1.07 | 0.0 | 0.0 | 0.0 | 20.9 | 0.8 | 6.3 | 0.0 | 6.3 | Tedlar results are suspect. |
| VMP-26-10 | 2/26/2013 | 1026 | -1.23 | -1.30 | 0.0 | 0.0 | 1.2 | 19.2 | 18.4 | 59.6 | 3.6 | 56.0 | Resample. |
| VMP-26-10 | 3/20/2013 | 1025 | -2.48 | -0.58 | 0.0 | 0.0 | 1.1 | 19.8 | 12.0 | 25.6 | 7.5 | 18.1 | |

SEE LAST PAGE OF TABLE FOR NOTES

**TABLE 10**
**SVE SYSTEM MONTHLY MONITORING - VMP SAMPLING DATA**

| Sample ID | Date | Initial Reading Time (24-Hour) | Vacuum/Pressure | | Fixed Gases | | | | Soil Vapor Concentrations | | | | Comments |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | Initial Reading (Inches of $H_2O$) | Stabilized Reading (Inches of $H_2O$) | CH4 (%) | LEL (%) | $CO_2$ (%) | $O_2$ (%) | PID (ppmv) | THC (ppmv) | CH4 (ppmv) | PHC (ppmv) | |
| VMP-26-20 | 2/1/2012 | 1616 | -0.86 | -0.80 | 21.6 | OVR | 0.9 | 19.2 | 200 | 41200 | 27000 | 14200 | |
| VMP-26-20 | 2/2/2012 | 1110 | -1.21 | -1.02 | OVR | OVR | 7.9 | 3.9 | 69.8 | 858000 | 425000 | 433000 | |
| VMP-26-20 | 2/7/2012 | 940 | -1.11 | -0.90 | 0.0 | 0.0 | 0.2 | 20.9 | 36.7 | 221 | 97.9 | 123 | |
| VMP-26-20 | 2/10/2012 | 1137 | -0.69 | -0.94 | 0.0 | 0.0 | 0.1 | 20.6 | 5.5 | 13.1 | 0.0 | 13.1 | |
| VMP-26-20 | 2/13/2012 | 1000 | -1.12 | -0.85 | 0.4 | 9.0 | 0.1 | 20.9 | 23.6 | 3220 | 2812 | 408 | |
| VMP-26-20 | 2/15/2012 | 1325 | -1.37 | -1.09 | OVR | OVR | 6.5 | 2.9 | 74.9 | 1000000 | 989000 | 11000 | |
| VMP-26-20 | 2/22/2012 | 1104 | -0.87 | -0.79 | 0.0 | 0.0 | 0.3 | 20.8 | 14.3 | 51.3 | 3.3 | 48.0 | |
| VMP-26-20 | 2/29/2012 | 1004 | -0.88 | -0.90 | 0.2 | 5.0 | 0.1 | 20.9 | 90.8 | 609 | 4.0 | 605 | |
| VMP-26-20 | 3/21/2012 | 1006 | -1.00 | -0.82 | 0.0 | 0.0 | 0.1 | 20.9 | 34.3 | 177 | 3.4 | 174 | |
| VMP-26-20 | 4/18/2012 | 942 | -1.49 | -1.31 | 0.0 | 0.0 | 0.0 | 20.9 | 6.0 | 41.0 | 3.0 | 38.0 | |
| VMP-26-20 | 5/16/2012 | 1005 | -1.73 | -1.27 | 0.0 | 0.0 | 0.0 | 20.9 | 1.0 | 3.6 | 0.0 | 3.6 | |
| VMP-26-20 | 6/20/2012 | 1025 | -0.02 | -1.54 | 0.0 | 0.0 | 0.1 | 20.9 | 18.1 | 101 | 0.0 | 101 | |
| VMP-26-20 | 7/18/2012 | 1039 | -1.57 | -1.42 | 0.0 | 0.0 | 0.0 | 20.9 | 6.1 | 22.8 | 3.5 | 19.3 | |
| VMP-26-20 | 8/15/2012 | 1019 | -1.69 | -1.65 | 0.0 | 0.0 | 0.0 | 20.9 | 3.8 | 18.8 | 7.4 | 11.4 | |
| VMP-26-20 | 9/19/2012 | 1110 | -2.45 | -2.45 | 0.2 | 4.0 | 0.4 | 20.3 | 44.4 | 423 | 143 | 280 | |
| VMP-26-20 | 10/17/2012 | 1013 | -2.54 | -2.56 | 30.9 | OVR | 9.0 | 7.3 | 327 | 11730 | 7300 | 4430 | |
| VMP-26-20 | 11/20/2012 | 1012 | -2.30 | -2.02 | 0.1 | 2.0 | 0.4 | 20.6 | 39.2 | 193 | 68.1 | 125 | |
| VMP-26-20 | 12/19/2012 | 1129 | -1.22 | -1.18 | 0.0 | 0.0 | 0.0 | 20.9 | 1.4 | 22.2 | 14.3 | 7.9 | |
| VMP-26-20 | 1/16/2013 | 1014 | -1.28 | -0.97 | 14.0 | OVR | 12.7 | 1.6 | 445 | 7500 | 2100 | 5400 | |
| VMP-26-20 | 2/25/2013 | 1048 | -1.40 | -1.28 | 0.0 | 0.0 | 0.0 | 20.9 | 0.9 | 14.3 | 7.3 | 7.0 | Tedlar results are suspect. |
| VMP-26-20 | 2/26/2013 | 1030 | -1.34 | -1.44 | 3.9 | 79.0 | 12.1 | 3.1 | 205 | 4100 | 65.2 | 4035 | Resample. |
| VMP-26-20 | 3/20/2013 | 1029 | -3.00 | -0.70 | 0.1 | 2.0 | 5.4 | 12.7 | 15.5 | 131 | 100 | 31.0 | |
| VMP-26-30 | 2/1/2012 | 1617 | -0.74 | -0.66 | OVR | OVR | 2.2 | 14.8 | 100 | 235000 | 127000 | 108000 | |
| VMP-26-30 | 2/2/2012 | 1113 | -1.09 | -0.89 | OVR | OVR | 7.2 | 1.1 | 53.8 | 1000000 | 1000000 | 0.0 | |
| VMP-26-30 | 2/7/2012 | 941 | -0.97 | -0.76 | OVR | OVR | 1.1 | 18.0 | 87.3 | 91500 | 67700 | 23800 | |
| VMP-26-30 | 2/10/2012 | 1138 | -0.54 | -0.68 | 0.0 | 0.0 | 0.1 | 20.9 | 18.0 | 57.7 | 7.7 | 50.0 | |
| VMP-26-30 | 2/13/2012 | 1001 | -0.99 | -0.68 | 0.7 | 15.0 | 0.1 | 20.9 | 135 | 1180 | 127 | 1054 | |
| VMP-26-30 | 2/15/2012 | 1326 | -1.25 | -0.94 | OVR | OVR | 4.2 | 10.3 | 81.8 | 714000 | 389000 | 325000 | |
| VMP-26-30 | 2/22/2012 | 1105 | -0.72 | -0.67 | 0.0 | 0.0 | 0.3 | 20.8 | 17.7 | 67.7 | 0.0 | 67.7 | |
| VMP-26-30 | 2/29/2012 | 1005 | -0.85 | -0.82 | 0.4 | 9.0 | 0.1 | 20.9 | 120 | 1033 | 64.3 | 969 | |
| VMP-26-30 | 3/21/2012 | 1006 | -0.95 | -0.78 | 0.4 | 8.0 | 0.1 | 20.9 | 75.3 | 521 | 72.6 | 448 | |
| VMP-26-30 | 4/18/2012 | 943 | -1.40 | -1.21 | 0.0 | 1.0 | 0.1 | 20.9 | 8.8 | 126 | 54.0 | 72.0 | |
| VMP-26-30 | 5/16/2012 | 1006 | -1.63 | -1.65 | 0.0 | 0.0 | 0.0 | 20.9 | 18.1 | 100 | 46.0 | 54.0 | |
| VMP-26-30 | 6/20/2012 | 1026 | -1.35 | -1.36 | 0.0 | 0.0 | 0.0 | 20.9 | 2.0 | 2.2 | 0.0 | 2.2 | |
| VMP-26-30 | 7/18/2012 | 1040 | -1.44 | -1.29 | 0.0 | 0.0 | 0.0 | 20.9 | 13.8 | 54.1 | 12.3 | 41.8 | |
| VMP-26-30 | 8/15/2012 | 1010 | -1.54 | -1.49 | 0.0 | 0.0 | 0.0 | 20.9 | 7.2 | 38.5 | 12.6 | 25.9 | |
| VMP-26-30 | 9/19/2012 | 1112 | -2.20 | -2.13 | 0.0 | 0.0 | 0.0 | 20.9 | 13.3 | 45.6 | 12.8 | 32.8 | |
| VMP-26-30 | 10/17/2012 | 1014 | -2.20 | -2.18 | OVR | OVR | 3.2 | 15.7 | 306 | 36700 | 13100 | 23600 | |
| VMP-26-30 | 11/20/2012 | 1016 | -2.04 | -1.74 | 0.0 | 0.0 | 0.0 | 20.9 | 5.6 | 26.1 | 4.5 | 21.6 | |
| VMP-26-30 | 12/19/2012 | 1130 | -1.08 | -1.03 | 0.0 | 0.0 | 0.0 | 20.9 | 5.3 | 26.9 | 0.0 | 26.9 | |
| VMP-26-30 | 1/16/2013 | 1019 | -1.18 | -0.86 | OVR | OVR | 10.4 | 3.6 | 400 | 56700 | 19300 | 37400 | |
| VMP-26-30 | 2/25/2013 | 1052 | -1.26 | -1.14 | 0.0 | 1.0 | 0.0 | 20.9 | 14.9 | 65.4 | 5.2 | 60.2 | Tedlar results are suspect. |
| VMP-26-30 | 2/26/2013 | 1034 | -1.19 | -1.25 | OVR | OVR | 12.1 | 1.2 | 365 | 69200 | 28100 | 41100 | Resample. |
| VMP-26-30 | 3/20/2013 | 1033 | -2.52 | -0.66 | OVR | OVR | 10.9 | 0.9 | 270 | 191000 | 69100 | 121900 | |

SEE LAST PAGE OF TABLE FOR NOTES

**TABLE 10**
**SVE SYSTEM MONTHLY MONITORING - VMP SAMPLING DATA**

| Sample ID | Date | Initial Reading Time (24-Hour) | Vacuum/Pressure | | Fixed Gases | | | | Soil Vapor Concentrations | | | | Comments |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | Initial Reading (Inches of $H_2O$) | Stabilized Reading (Inches of $H_2O$) | CH4 (%) | LEL (%) | $CO_2$ (%) | $O_2$ (%) | PID (ppmv) | THC (ppmv) | CH4 (ppmv) | PHC (ppmv) | |
| VMP-26-38 | 2/1/2012 | 1618 | -0.46 | -0.39 | OVR | OVR | 1.0 | 17.3 | 105 | 133000 | 95000 | 38000 | |
| VMP-26-38 | 2/2/2012 | 1124 | -0.92 | -0.71 | OVR | OVR | 4.3 | 3.0 | 39.8 | 1000000 | 1000000 | 0.0 | |
| VMP-26-38 | 2/7/2012 | 941 | -0.75 | -0.54 | 17.1 | OVR | 0.3 | 20.4 | 107 | 32960 | 24800 | 8160 | |
| VMP-26-38 | 2/10/2012 | 1139 | -0.30 | -0.59 | 0.0 | 0.0 | 0.1 | 20.9 | 4.5 | 14.2 | 3.2 | 11.0 | |
| VMP-26-38 | 2/13/2012 | 1002 | -0.81 | -0.45 | OVR | OVR | 2.5 | 8.5 | 50.0 | 1000000 | 885000 | 115000 | |
| VMP-26-38 | 2/15/2012 | 1327 | -1.10 | -0.76 | OVR | OVR | 3.6 | 2.1 | 46.6 | 1000000 | 1000000 | 0.0 | |
| VMP-26-38 | 2/22/2012 | 1106 | -0.50 | -0.49 | 0.0 | 0.0 | 0.3 | 20.8 | 21.1 | 100 | 9.5 | 90.5 | |
| VMP-26-38 | 2/29/2012 | 1005 | -0.77 | -0.80 | 3.4 | 70.0 | 0.1 | 20.9 | 271 | 4230 | 174 | 4056 | |
| VMP-26-38 | 3/21/2012 | 1007 | -0.91 | -0.78 | 0.9 | 19.0 | 0.1 | 20.9 | 117 | 1500 | 262 | 1239 | |
| VMP-26-38 | 4/18/2012 | 943 | -1.27 | -1.12 | 0.0 | 1.0 | 0.0 | 20.9 | 8.7 | 180 | 131 | 49.0 | |
| VMP-26-38 | 5/16/2012 | 1007 | -1.57 | -1.63 | 0.0 | 0.0 | 0.0 | 20.9 | 7.0 | 84.7 | 58.1 | 26.6 | |
| VMP-26-38 | 6/20/2012 | 1027 | -1.23 | -1.24 | 0.1 | 2.0 | 0.0 | 20.9 | 31.4 | 217 | 82.5 | 135 | |
| VMP-26-38 | 7/18/2012 | 1041 | -1.35 | -1.22 | 0.0 | 0.0 | 0.0 | 20.9 | 10.6 | 51.3 | 26.9 | 24.4 | |
| VMP-26-38 | 8/15/2012 | 1019 | -1.40 | -1.39 | 0.0 | 0.0 | 0.0 | 20.9 | 3.5 | 45.1 | 23.8 | 21.2 | |
| VMP-26-38 | 9/19/2012 | 1114 | -1.97 | -1.89 | 1.6 | 33.0 | 0.0 | 20.9 | 113 | 5320 | 3790 | 1530 | |
| VMP-26-38 | 10/17/2012 | 1015 | -1.84 | -1.79 | OVR | OVR | 2.0 | 14.8 | 130 | 320000 | 120000 | 200000 | |
| VMP-26-38 | 11/20/2012 | 1020 | -1.83 | -1.51 | 0.0 | 0.0 | 0.0 | 20.9 | 9.0 | 72.8 | 27.2 | 45.7 | |
| VMP-26-38 | 12/19/2012 | 1131 | -0.98 | -0.85 | OVR | OVR | 5.2 | 8.1 | 181 | 770000 | 222000 | 548000 | |
| VMP-26-38 | 1/16/2013 | 1024 | -1.06 | -0.66 | OVR | OVR | 6.0 | 9.4 | 210 | 180000 | 67500 | 112500 | |
| VMP-26-38 | 2/25/2013 | 1056 | -1.05 | -0.92 | 0.1 | 2.0 | 0.0 | 20.9 | 46.7 | 310 | 45.5 | 265 | Tedlar results are suspect. |
| VMP-26-38 | 2/26/2013 | 1038 | -0.87 | -0.98 | OVR | OVR | 3.6 | 15.9 | 460 | 47900 | 8000 | 39900 | Resample. |
| VMP-26-38 | 3/20/2013 | 1037 | -2.56 | -0.60 | OVR | OVR | 1.5 | 19.7 | 697 | 15700 | 1700 | 14000 | |
| VMP-27-10 | 2/1/2012 | 1555 | -0.48 | -0.44 | OVR | OVR | 4.1 | 7.5 | 190 | 75500 | 50000 | 25500 | |
| VMP-27-10 | 2/2/2012 | 956 | -1.10 | -0.91 | OVR | OVR | 6.3 | 2.5 | 105 | 303000 | 178000 | 125000 | |
| VMP-27-10 | 2/7/2012 | 859 | -0.89 | -0.62 | 0.0 | 0.0 | 0.1 | 20.9 | 16.5 | 79.0 | 8.8 | 70.3 | |
| VMP-27-10 | 2/10/2012 | 1154 | -0.30 | -0.01 | 0.7 | 14.0 | 0.2 | 20.3 | 20.0 | 5115 | 5011 | 104 | |
| VMP-27-10 | 2/13/2012 | 933 | -0.75 | -0.29 | OVR | OVR | 6.6 | 2.4 | 65.4 | 251000 | 251000 | 0.0 | |
| VMP-27-10 | 2/15/2012 | 1241 | -0.99 | -0.83 | OVR | OVR | 6.4 | 2.2 | 61.3 | 328000 | 209000 | 119000 | |
| VMP-27-10 | 2/22/2012 | 1133 | -0.38 | -0.33 | 1.8 | 37.0 | 0.7 | 19.4 | 39.8 | 9513 | 9468 | 45.0 | |
| VMP-27-10 | 2/29/2012 | 1024 | -0.72 | -0.63 | 42.3 | OVR | 2.4 | 13.5 | 196 | 35300 | 21630 | 13670 | |
| VMP-27-10 | 3/21/2012 | 950 | -0.20 | -0.72 | 0.1 | 3.0 | 0.2 | 20.6 | 20.5 | 691 | 472 | 219 | |
| VMP-27-10 | 4/18/2012 | 917 | -1.35 | -1.00 | 0.6 | 13.0 | 0.4 | 19.7 | 67.0 | 1106 | 334 | 772 | |
| VMP-27-10 | 5/16/2012 | 940 | -1.29 | -1.28 | 0.0 | 0.0 | 0.2 | 20.7 | 12.7 | 82.0 | 17.7 | 64.3 | |
| VMP-27-10 | 6/20/2012 | 1000 | -1.01 | -0.91 | 0.0 | 1.0 | 0.2 | 20.8 | 9.1 | 39.4 | 4.2 | 35.3 | |
| VMP-27-10 | 7/18/2012 | 1012 | -0.98 | -0.95 | 0.0 | 0.0 | 0.1 | 20.5 | 18.9 | 83.3 | 15.6 | 67.7 | |
| VMP-27-10 | 8/15/2012 | 1042 | -0.99 | -0.98 | 0.0 | 0.0 | 0.2 | 20.8 | 16.7 | 59.0 | 13.7 | 45.3 | |
| VMP-27-10 | 9/19/2012 | 1036 | -1.25 | -1.40 | 0.2 | 4.0 | 2.5 | 16.9 | 82.2 | 359 | 85.0 | 274 | |
| VMP-27-10 | 10/17/2012 | 943 | -1.36 | -1.37 | 0.0 | 1.0 | 0.5 | 20.4 | 6.5 | 103 | 49.1 | 53.9 | |
| VMP-27-10 | 11/20/2012 | 1025 | -1.32 | -1.13 | 0.0 | 0.0 | 0.2 | 20.8 | 2.0 | 9.5 | 5.5 | 4.0 | |
| VMP-27-10 | 12/19/2012 | 1103 | -0.89 | -0.62 | 0.0 | 0.0 | 1.3 | 19.1 | 3.6 | 61.1 | 33.8 | 27.3 | |
| VMP-27-10 | 1/16/2013 | 1149 | -0.76 | -0.61 | 0.0 | 1.0 | 9.4 | 6.4 | 43.9 | 196 | 78.5 | 118 | |
| VMP-27-10 | 2/25/2013 | 1028 | -0.97 | -0.54 | 0.0 | 0.0 | 0.3 | 20.5 | 0.6 | 7.9 | 3.7 | 4.2 | Tedlar results are suspect. |
| VMP-27-10 | 2/26/2013 | 941 | -0.71 | -0.76 | 0.0 | 0.0 | 0.2 | 20.8 | 0.5 | 6.5 | 3.1 | 3.4 | Resample. |
| VMP-27-10 | 3/20/2013 | 1005 | -1.94 | -0.47 | 0.0 | 0.0 | 3.9 | 14.9 | 1.9 | 37.5 | 33.8 | 3.7 | |

SEE LAST PAGE OF TABLE FOR NOTES

**TABLE 10**
**SVE SYSTEM MONTHLY MONITORING - VMP SAMPLING DATA**

| Sample ID | Date | Initial Reading Time (24-Hour) | Vacuum/Pressure | | Fixed Gases | | | | Soil Vapor Concentrations | | | | Comments |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | Initial Reading (Inches of $H_2O$) | Stabilized Reading (Inches of $H_2O$) | CH4 (%) | LEL (%) | $CO_2$ (%) | $O_2$ (%) | PID (ppmv) | THC (ppmv) | CH4 (ppmv) | PHC (ppmv) | |
| VMP-27-20 | 2/1/2012 | 1556 | -0.46 | -0.40 | OVR | OVR | 1.7 | 17.0 | 101 | 83200 | 67000 | 16200 | |
| VMP-27-20 | 2/2/2012 | 957 | -1.16 | -0.95 | OVR | OVR | 7.8 | 1.6 | 54.0 | 1000000 | 873000 | 127000 | |
| VMP-27-20 | 2/7/2012 | 859 | -0.92 | -0.63 | 0.2 | 4.0 | 0.1 | 20.9 | 38.4 | 291 | 31.2 | 260 | |
| VMP-27-20 | 2/10/2012 | 1155 | -0.38 | -0.50 | 0.0 | 0.0 | 0.1 | 20.7 | 17.0 | 204 | 146 | 58.1 | |
| VMP-27-20 | 2/13/2012 | 934 | -0.86 | -0.37 | OVR | OVR | 7.3 | 2.0 | 50.3 | 1000000 | 1000000 | 0.0 | |
| VMP-27-20 | 2/15/2012 | 1242 | -1.13 | -0.97 | OVR | OVR | 6.9 | 2.4 | 54.9 | 1000000 | 1000000 | 0.0 | |
| VMP-27-20 | 2/22/2012 | 1134 | -0.44 | -0.38 | 0.0 | 0.0 | 0.3 | 20.9 | 30.9 | 231 | 42.8 | 188 | |
| VMP-27-20 | 2/29/2012 | 1025 | -0.80 | -0.71 | OVR | OVR | 1.3 | 17.8 | 95.8 | 124000 | 79400 | 44600 | |
| VMP-27-20 | 3/21/2012 | 950 | -0.23 | -0.84 | 0.0 | 0.0 | 0.1 | 20.9 | 18.1 | 122 | 38.6 | 83.4 | |
| VMP-27-20 | 4/18/2012 | 917 | -1.24 | -1.17 | 0.1 | 3.0 | 0.1 | 20.9 | 15.8 | 790 | 661 | 129 | |
| VMP-27-20 | 5/16/2012 | 941 | -1.53 | -1.54 | 0.0 | 0.0 | 0.0 | 20.9 | 6.3 | 11.4 | 34.8 | -23 | |
| VMP-27-20 | 6/20/2012 | 1001 | -1.20 | -1.13 | 0.0 | 0.0 | 0.0 | 20.9 | 9.5 | 45.8 | 9.6 | 36.2 | |
| VMP-27-20 | 7/18/2012 | 1013 | -1.26 | -1.24 | 0.0 | 0.0 | 0.3 | 20.6 | 10.1 | 112 | 44.2 | 67.8 | |
| VMP-27-20 | 8/15/2012 | 1043 | -1.28 | -1.26 | 0.0 | 0.0 | 0.0 | 20.9 | 3.9 | 22.1 | 8.2 | 13.9 | |
| VMP-27-20 | 9/19/2012 | 1038 | -1.94 | -1.83 | 0.0 | 0.0 | 0.0 | 20.9 | 4.5 | 24.6 | 6.2 | 18.4 | |
| VMP-27-20 | 10/17/2012 | 944 | -1.73 | -1.68 | 0.0 | 0.0 | 0.1 | 20.9 | 9.6 | 81.8 | 21.6 | 60.2 | |
| VMP-27-20 | 11/20/2012 | 1029 | -1.65 | -1.42 | 0.0 | 0.0 | 0.0 | 20.9 | 20.0 | 88.4 | 14.0 | 74.4 | |
| VMP-27-20 | 12/19/2012 | 1104 | -1.13 | -0.80 | 0.0 | 0.0 | 0.0 | 20.9 | 7.0 | 40.3 | 0.0 | 40.3 | |
| VMP-27-20 | 1/16/2013 | 1154 | -0.67 | -0.28 | OVR | OVR | 10.0 | 1.8 | 365 | 80200 | 29300 | 50900 | |
| VMP-27-20 | 2/25/2013 | 1032 | -1.16 | -0.89 | 0.0 | 0.0 | 0.0 | 20.9 | 2.3 | 21.3 | 4.3 | 17.0 | Tedlar results are suspect. |
| VMP-27-20 | 2/26/2013 | 945 | -0.79 | -0.83 | OVR | OVR | 9.0 | 1.3 | 290 | 84900 | 36200 | 48700 | Resample. |
| VMP-27-20 | 3/20/2013 | 1009 | -2.26 | -0.58 | OVR | OVR | 8.1 | 1.5 | 315 | 122000 | 53400 | 68600 | |
| VMP-27-30 | 2/1/2012 | 1557 | -0.46 | -0.40 | 0.0 | 0.0 | 0.1 | 20.9 | 17.2 | 137 | 0.0 | 137 | |
| VMP-27-30 | 2/2/2012 | 958 | -1.16 | -0.95 | OVR | OVR | 7.2 | 2.1 | 53.1 | 1000000 | 1000000 | 0.0 | |
| VMP-27-30 | 2/7/2012 | 900 | -0.94 | -0.63 | OVR | OVR | 1.6 | 16.8 | 60.0 | 132000 | 76060 | 55940 | |
| VMP-27-30 | 2/10/2012 | 1156 | -0.39 | -0.51 | OVR | OVR | 0.3 | 19.7 | 355 | 56000 | 16290 | 39710 | |
| VMP-27-30 | 2/13/2012 | 935 | -0.87 | -0.38 | OVR | OVR | 7.1 | 1.8 | 45.4 | 1000000 | 1000000 | 0.0 | |
| VMP-27-30 | 2/15/2012 | 1243 | -1.16 | -0.98 | OVR | OVR | 4.6 | 8.4 | 56.8 | 1000000 | 532000 | 468000 | |
| VMP-27-30 | 2/22/2012 | 1135 | -0.45 | -0.40 | 0.2 | 4.0 | 0.2 | 20.9 | 54.4 | 397 | 73.0 | 324 | |
| VMP-27-30 | 2/29/2012 | 1026 | -0.79 | -0.73 | OVR | OVR | 1.4 | 17.0 | 98.5 | 146000 | 117000 | 29000 | |
| VMP-27-30 | 3/21/2012 | 950 | -0.23 | -0.83 | 0.0 | 0.0 | 0.1 | 20.2 | 18.6 | 119 | 37.7 | 81.3 | |
| VMP-27-30 | 4/18/2012 | 917 | -1.22 | -1.16 | 0.0 | 0.0 | 0.0 | 20.9 | 2.2 | 39.5 | 18.5 | 21.0 | |
| VMP-27-30 | 5/16/2012 | 942 | -1.51 | -1.55 | 0.0 | 0.0 | 0.0 | 20.9 | 4.6 | 31.8 | 10.5 | 21.3 | |
| VMP-27-30 | 6/20/2012 | 1002 | -1.24 | -1.13 | 0.0 | 0.0 | 0.0 | 20.9 | 6.0 | 32.0 | 8.8 | 23.2 | |
| VMP-27-30 | 7/18/2012 | 1012 | -1.26 | -1.24 | 49.7 | OVR | 0.8 | 18.2 | 77.3 | 84100 | 28300 | 55800 | |
| VMP-27-30 | 8/15/2012 | 1044 | -1.28 | -1.26 | 0.0 | 0.0 | 0.0 | 20.9 | 5.1 | 31.8 | 9.9 | 21.9 | |
| VMP-27-30 | 9/19/2012 | 1040 | -1.96 | -1.82 | 0.0 | 0.0 | 0.0 | 20.9 | 5.3 | 22.2 | 6.1 | 16.0 | |
| VMP-27-30 | 10/17/2012 | 945 | -1.75 | -1.69 | 0.0 | 0.0 | 0.0 | 20.9 | 10.0 | 86.1 | 10.6 | 75.5 | |
| VMP-27-30 | 11/20/2012 | 1033 | -1.63 | -1.42 | 0.0 | 0.0 | 0.0 | 20.9 | 4.6 | 22.4 | 4.8 | 17.6 | |
| VMP-27-30 | 12/19/2012 | 1105 | -1.11 | -0.80 | 0.0 | 0.0 | 0.0 | 20.9 | 10.0 | 65.2 | 2.5 | 62.8 | |
| VMP-27-30 | 1/16/2013 | 1159 | -0.65 | -0.59 | OVR | OVR | 7.7 | 4.9 | 155 | 355000 | 154000 | 201000 | |
| VMP-27-30 | 2/25/2013 | 1036 | -1.16 | -0.90 | 0.0 | 0.0 | 0.0 | 20.9 | 6.0 | 53.3 | 7.7 | 45.6 | Tedlar results are suspect. |
| VMP-27-30 | 2/26/2013 | 949 | -0.79 | -0.83 | OVR | OVR | 8.8 | 0.9 | 174 | 282000 | 125000 | 157000 | Resample. |
| VMP-27-30 | 3/20/2013 | 1013 | -2.62 | -0.57 | OVR | OVR | 7.3 | 0.6 | 107 | 1000000 | 520000 | 480000 | |

SEE LAST PAGE OF TABLE FOR NOTES

**TABLE 10**
**SVE SYSTEM MONTHLY MONITORING - VMP SAMPLING DATA**

| Sample ID | Date | Initial Reading Time (24-Hour) | Vacuum/Pressure | | Fixed Gases | | | | Soil Vapor Concentrations | | | | Comments |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | Initial Reading (Inches of $H_2O$) | Stabilized Reading (Inches of $H_2O$) | CH4 (%) | LEL (%) | $CO_2$ (%) | $O_2$ (%) | PID (ppmv) | THC (ppmv) | CH4 (ppmv) | PHC (ppmv) | |
| VMP-27-38 | 2/1/2012 | 1558 | -0.30 | -0.28 | 80.0 | OVR | 0.6 | 19.3 | 95.3 | 105000 | 73200 | 31800 | |
| VMP-27-38 | 2/2/2012 | 959 | -1.11 | -0.89 | OVR | OVR | 4.9 | 1.4 | 37.3 | 1000000 | 1000000 | 0.0 | |
| VMP-27-38 | 2/7/2012 | 900 | -0.85 | -0.55 | OVR | OVR | 2.0 | 13.0 | 47.6 | 611000 | 567000 | 44000 | |
| VMP-27-38 | 2/10/2012 | 1157 | -0.27 | -0.38 | 0.0 | 0.0 | 0.1 | 20.9 | 6.5 | 27.6 | 7.7 | 19.9 | |
| VMP-27-38 | 2/13/2012 | 936 | -0.49 | -0.24 | 0.4 | 8.0 | 0.1 | 20.9 | 87.3 | 823 | 242 | 581 | |
| VMP-27-38 | 2/15/2012 | 1244 | -1.40 | -0.91 | OVR | OVR | 4.3 | 2.1 | 38.5 | 1000000 | 1000000 | 0.0 | |
| VMP-27-38 | 2/22/2012 | 1136 | -0.31 | -0.25 | OVR | OVR | 3.1 | 8.3 | 53.7 | 1000000 | 875000 | 125000 | |
| VMP-27-38 | 2/29/2012 | 1027 | -0.79 | -0.70 | 38.9 | OVR | 0.4 | 19.7 | 63.8 | 53550 | 39200 | 14350 | |
| VMP-27-38 | 3/21/2012 | 951 | -0.24 | -0.86 | 0.0 | 0.0 | 0.1 | 20.9 | 5.0 | 33.9 | 5.2 | 28.7 | |
| VMP-27-38 | 4/18/2012 | 917 | -1.23 | -1.14 | 0.0 | 0.0 | 0.0 | 20.9 | 0.5 | 4.8 | 0.0 | 4.8 | |
| VMP-27-38 | 5/16/2012 | 943 | -1.54 | -1.45 | 0.0 | 0.0 | 0.0 | 20.9 | 0.5 | 1.3 | 0.0 | 1.3 | |
| VMP-27-38 | 6/20/2012 | 1003 | -1.24 | -1.13 | 0.0 | 0.0 | 0.0 | 20.9 | 1.0 | 6.0 | 3.1 | 2.9 | |
| VMP-27-38 | 7/18/2012 | 1016 | -1.23 | -0.62 | 0.0 | 0.0 | 0.0 | 20.9 | 0.8 | 28.0 | 10.7 | 17.3 | |
| VMP-27-38 | 8/15/2012 | 1045 | -1.30 | -1.28 | 0.0 | 0.0 | 0.0 | 20.9 | 0.9 | 7.9 | 6.1 | 1.8 | |
| VMP-27-38 | 9/19/2012 | 1042 | -1.95 | -1.82 | 0.0 | 0.0 | 0.0 | 20.9 | 3.8 | 56.5 | 39.0 | 17.5 | |
| VMP-27-38 | 10/17/2012 | 946 | -1.71 | -1.61 | 0.0 | 0.0 | 0.0 | 20.9 | 11.5 | 158 | 60.5 | 97.5 | |
| VMP-27-38 | 11/20/2012 | 1037 | -1.64 | -1.40 | 0.0 | 0.0 | 0.0 | 20.9 | 1.8 | 20.4 | 10.6 | 9.8 | |
| VMP-27-38 | 12/19/2012 | 1106 | -1.11 | 0.77 | 0.0 | 0.0 | 0.0 | 20.9 | 50.5 | 320 | 13.1 | 307 | |
| VMP-27-38 | 1/16/2013 | 1204 | -0.57 | -0.49 | OVR | OVR | 10.0 | 1.9 | 252 | 218000 | 72200 | 145800 | |
| VMP-27-38 | 2/25/2013 | 1040 | -1.07 | -0.80 | 0.0 | 0.0 | 0.0 | 20.9 | 1.6 | 15.3 | 3.3 | 12.0 | Tedlar results are suspect. |
| VMP-27-38 | 2/26/2013 | 953 | -0.60 | -0.65 | OVR | OVR | 11.2 | 2.9 | 239 | 74700 | 42300 | 32400 | Resample. |
| VMP-27-38 | 3/20/2013 | 1017 | -2.56 | -0.55 | 9.4 | OVR | 4.7 | 14.2 | 430 | 3900 | 1200 | 2700 | Tedlar results are suspect. |
| VMP-28-10 | 2/1/2012 | 1632 | -1.20 | -1.17 | OVR | OVR | 8.4 | 4.7 | 216 | 150000 | 85700 | 64300 | |
| VMP-28-10 | 2/2/2012 | 1035 | -1.44 | -1.23 | OVR | OVR | 9.6 | 0.9 | 196 | 239000 | 132000 | 107000 | |
| VMP-28-10 | 2/7/2012 | 1010 | -1.01 | -1.15 | 0.1 | 3.0 | 0.2 | 20.8 | 41.5 | 287 | 72.6 | 214 | |
| VMP-28-10 | 2/10/2012 | 1108 | -0.04 | -0.79 | 0.5 | 11.0 | 0.2 | 20.6 | 105 | 1566 | 862 | 704 | |
| VMP-28-10 | 2/13/2012 | 1024 | 0.75 | -0.67 | OVR | OVR | 8.1 | 1.5 | 253 | 128000 | 60200 | 67800 | |
| VMP-28-10 | 2/15/2012 | 1349 | -0.91 | -0.75 | OVR | OVR | 6.1 | 5.7 | 266 | 87200 | 53820 | 33380 | |
| VMP-28-10 | 2/22/2012 | 1119 | -0.58 | - 0.62 | 1.3 | 27.0 | 0.6 | 20.0 | 128 | 3998 | 2430 | 1568 | |
| VMP-28-10 | 2/29/2012 | 1050 | -0.99 | -0.76 | 7.3 | OVR | 0.6 | 19.5 | 434 | 9343 | 3540 | 5803 | |
| VMP-28-10 | 3/21/2012 | 1029 | -0.60 | -0.52 | 45.5 | OVR | 1.9 | 15.1 | 395 | 35300 | 9510 | 25790 | |
| VMP-28-10 | 4/18/2012 | 1009 | -1.08 | -1.01 | 0.8 | 17.0 | 0.3 | 20.2 | 141 | 1781 | 750 | 1031 | |
| VMP-28-10 | 5/16/2012 | 1011 | -1.32 | -1.33 | 0.2 | 5.0 | 0.2 | 20.5 | 69.3 | 6200 | 231 | 5969 | |
| VMP-28-10 | 6/20/2012 | 1056 | -1.09 | -1.35 | 10.3 | OVR | 1.4 | 18.1 | 397 | 7000 | 825 | 6175 | |
| VMP-28-10 | 7/18/2012 | 1053 | -0.88 | -0.78 | 0.6 | 12.0 | 0.2 | 20.4 | 150 | 1000 | 32.5 | 968 | |
| VMP-28-10 | 8/15/2012 | 1106 | -0.93 | -0.92 | 2.2 | 46.0 | 0.6 | 20.0 | 354 | 7040 | 1130 | 5910 | |
| VMP-28-10 | 9/19/2012 | 1010 | -1.72 | -1.69 | OVR | OVR | 6.1 | 10.7 | 776 | 14200 | 1080 | 13120 | |
| VMP-28-10 | 10/17/2012 | 1030 | -2.11 | -2.07 | 27.3 | OVR | 3.8 | 15.0 | 882 | 18700 | 350 | 18350 | |
| VMP-28-10 | 11/20/2012 | 1055 | -1.60 | -1.59 | 0.3 | 6.0 | 0.3 | 20.7 | 211 | 600 | 63.8 | 536 | |
| VMP-28-10 | 12/19/2012 | 1150 | -0.82 | -0.64 | 17.5 | OVR | 5.0 | 14.9 | 868 | 4600 | 480 | 4120 | |
| VMP-28-10 | 1/16/2013 | 1211 | -0.70 | -0.77 | 19.0 | OVR | 13.2 | 1.5 | 828 | 7500 | 1350 | 6150 | |
| VMP-28-10 | 2/25/2013 | 1103 | -0.88 | -0.80 | 0.4 | 9.0 | 1.0 | 19.5 | 90.4 | 635 | 90.4 | 545 | Tedlar results are suspect. |
| VMP-28-10 | 2/26/2013 | 1104 | -0.99 | -0.92 | 32.8 | OVR | 12.0 | 2.8 | 800 | 10400 | 2600 | 7800 | Resample. |
| VMP-28-10 | 3/20/2013 | 1050 | -2.06 | -0.46 | 37.9 | OVR | 9.8 | 6.5 | 1105 | 4900 | 680 | 4220 | |

SEE LAST PAGE OF TABLE FOR NOTES

**TABLE 10**
**SVE SYSTEM MONTHLY MONITORING - VMP SAMPLING DATA**

| Sample ID | Date | Initial Reading Time (24-Hour) | Vacuum/Pressure | | Fixed Gases | | | | Soil Vapor Concentrations | | | | Comments |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | Initial Reading (Inches of $H_2O$) | Stabilized Reading (Inches of $H_2O$) | CH4 (%) | LEL (%) | $CO_2$ (%) | $O_2$ (%) | PID (ppmv) | THC (ppmv) | CH4 (ppmv) | PHC (ppmv) | |
| VMP-28-20 | 2/1/2012 | 1633 | -0.60 | -0.52 | OVR | OVR | 7.7 | 1.5 | 145 | 1000000 | 195000 | 805000 | |
| VMP-28-20 | 2/2/2012 | 1040 | -1.09 | -0.83 | OVR | OVR | 7.9 | 1.0 | 133 | 1000000 | 342000 | 658000 | |
| VMP-28-20 | 2/7/2012 | 1010 | -0.67 | -0.73 | 0.3 | 6.0 | 0.1 | 20.9 | 55.2 | 475 | 62.3 | 413 | |
| VMP-28-20 | 2/10/2012 | 1109 | -0.06 | -0.69 | 0.9 | 19.0 | 0.1 | 20.7 | 164 | 1425 | 102 | 1323 | |
| VMP-28-20 | 2/13/2012 | 1025 | -0.68 | -0.53 | OVR | OVR | 7.1 | 3.5 | 148 | 1000000 | 213000 | 787000 | |
| VMP-28-20 | 2/15/2012 | 1350 | -0.81 | -0.84 | OVR | OVR | 4.2 | 12.7 | 377 | 52900 | 25780 | 27120 | |
| VMP-28-20 | 2/22/2012 | 1120 | -0.62 | - 0.59 | 0.1 | 2.0 | 0.2 | 20.9 | 39.7 | 248 | 27.2 | 221 | |
| VMP-28-20 | 2/29/2012 | 1051 | -0.90 | -0.60 | 4.8 | 97.0 | 0.1 | 20.9 | 501 | 5056 | 130 | 4926 | |
| VMP-28-20 | 3/21/2012 | 1030 | -0.81 | -0.70 | 0.0 | 0.0 | 0.1 | 20.9 | 49.4 | 243 | 26.2 | 217 | |
| VMP-28-20 | 4/18/2012 | 1009 | -1.25 | -1.13 | 0.2 | 5.0 | 0.1 | 20.9 | 60.0 | 490 | 150 | 340 | |
| VMP-28-20 | 5/16/2012 | 1011 | -1.62 | -1.61 | 0.0 | 0.0 | 0.0 | 20.9 | 15.1 | 61.8 | 1.7 | 60.1 | |
| VMP-28-20 | 6/20/2012 | 1100 | -1.31 | -1.35 | 7.2 | OVR | 0.5 | 19.9 | 354 | 6020 | 864 | 5156 | |
| VMP-28-20 | 7/18/2012 | 1054 | -1.35 | -1.20 | 0.0 | 0.0 | 0.0 | 20.9 | 48.2 | 115 | 0.0 | 115 | |
| VMP-28-20 | 8/15/2012 | 1107 | -1.40 | -1.35 | 0.1 | 2.0 | 0.0 | 20.9 | 39.5 | 177 | 38.1 | 139 | |
| VMP-28-20 | 9/19/2012 | 1011 | -2.28 | -2.22 | 40.0 | OVR | 2.9 | 16.5 | 742 | 10700 | 1100 | 9600 | |
| VMP-28-20 | 10/17/2012 | 1031 | -2.15 | -2.08 | 5.5 | OVR | 0.6 | 20.2 | 295 | 6200 | 2200 | 4000 | |
| VMP-28-20 | 11/20/2012 | 1059 | -1.80 | -1.74 | 0.2 | 4.0 | 0.0 | 20.9 | 118 | 422 | 28.9 | 393 | |
| VMP-28-20 | 12/19/2012 | 1151 | -1.09 | -0.80 | 79.4 | OVR | 11.4 | 5.4 | 850 | 16200 | 4300 | 11900 | |
| VMP-28-20 | 1/16/2013 | 1216 | -0.86 | -0.63 | 64.5 | OVR | 13.0 | 2.6 | 490 | 24900 | 11100 | 13800 | |
| VMP-28-20 | 2/25/2013 | 1107 | -1.13 | -1.01 | 0.0 | 1.0 | 0.0 | 20.9 | 55.9 | 200 | 7.7 | 192 | Tedlar results are suspect. |
| VMP-28-20 | 2/26/2013 | 1108 | -1.13 | -1.07 | OVR | OVR | 12.7 | 0.8 | 173 | 178000 | 120000 | 58000 | Resample. |
| VMP-28-20 | 3/20/2013 | 1054 | -2.60 | -0.60 | 23.8 | OVR | 12.0 | 5.8 | 695 | 4400 | 865 | 3535 | |
| VMP-28-30 | 2/1/2012 | 1634 | -0.43 | -0.28 | OVR | OVR | 7.9 | 1.6 | 151 | 1000000 | 170000 | 830000 | |
| VMP-28-30 | 2/2/2012 | 1045 | -0.94 | -0.68 | OVR | OVR | 6.4 | 6.1 | 143 | 1000000 | 170000 | 830000 | |
| VMP-28-30 | 2/7/2012 | 1011 | -0.53 | -0.56 | 0.0 | 0.0 | 0.1 | 20.9 | 17.4 | 78.0 | 6.5 | 71.6 | |
| VMP-28-30 | 2/10/2012 | 1110 | -0.05 | -0.63 | 0.0 | 0.0 | 0.1 | 20.7 | 16.5 | 56.6 | 3.9 | 52.7 | |
| VMP-28-30 | 2/13/2012 | 1026 | -0.62 | -0.46 | OVR | OVR | 6.4 | 5.5 | 148 | 1000000 | 196000 | 804000 | |
| VMP-28-30 | 2/15/2012 | 1351 | -1.05 | -0.84 | 0.6 | 13.0 | 0.2 | 20.9 | 127 | 1035 | 26.6 | 1008 | |
| VMP-28-30 | 2/22/2012 | 1121 | -0.60 | - 0.55 | 0.0 | 0.0 | 0.2 | 20.9 | 26.7 | 132 | 24.1 | 108 | |
| VMP-28-30 | 2/29/2012 | 1052 | 0.83 | -0.52 | 38.5 | OVR | 0.6 | 19.6 | 281 | 60700 | 24280 | 36420 | |
| VMP-28-30 | 3/21/2012 | 1030 | -0.84 | -0.74 | 0.0 | 0.0 | 0.1 | 20.9 | 35.7 | 170 | 30.8 | 139 | |
| VMP-28-30 | 4/18/2012 | 1009 | -1.27 | -1.16 | 0.0 | 0.0 | 0.0 | 20.9 | 20.0 | 115 | 42.0 | 73.0 | |
| VMP-28-30 | 5/16/2012 | 1011 | -1.69 | -1.69 | 0.0 | 0.0 | 0.0 | 20.9 | 13.1 | 60.0 | NM | NM | Sample depelted before methane screened. |
| VMP-28-30 | 6/20/2012 | 1104 | -1.34 | -1.36 | 0.2 | 4.0 | 0.0 | 20.8 | 36.4 | 764 | 465 | 299 | |
| VMP-28-30 | 7/18/2012 | 1055 | -1.46 | -1.34 | 0.0 | 0.0 | 0.0 | 20.9 | 27.7 | 92.9 | 27.6 | 65.3 | |
| VMP-28-30 | 8/15/2012 | 1107 | -1.50 | -1.45 | 0.0 | 0.0 | 0.0 | 20.9 | 26.0 | 125 | 41.8 | 83.2 | |
| VMP-28-30 | 9/19/2012 | 1012 | -1.79 | -2.33 | 0.0 | 0.0 | 0.0 | 20.9 | 21.0 | 96.1 | 26.4 | 69.7 | |
| VMP-28-30 | 10/17/2012 | 1032 | -2.07 | -2.00 | 0.1 | 2.0 | 0.0 | 20.9 | 25.5 | 124 | 21.6 | 102 | |
| VMP-28-30 | 11/20/2012 | 1103 | -1.78 | -1.72 | 0.0 | 0.0 | 0.0 | 20.9 | 5.9 | 27.3 | 6.3 | 21.0 | |
| VMP-28-30 | 12/19/2012 | 1153 | -1.12 | -1.13 | OVR | OVR | 9.1 | 6.2 | 325 | 150000 | 70300 | 79700 | |
| VMP-28-30 | 1/16/2013 | 1221 | -0.83 | -0.74 | OVR | OVR | 8.9 | 6.6 | 225 | 138000 | 68800 | 69200 | |
| VMP-28-30 | 2/25/2013 | 1111 | -1.16 | -1.05 | 0.0 | 0.0 | 0.0 | 20.9 | 9.6 | 75.9 | 23.6 | 52.3 | Tedlar results are suspect. |
| VMP-28-30 | 2/26/2013 | 1112 | -1.13 | -1.09 | OVR | OVR | 9.5 | 1.5 | 120 | 585000 | 230000 | 355000 | Resample. |
| VMP-28-30 | 3/20/2013 | 1058 | -2.79 | -0.65 | OVR | OVR | 12.0 | 2.5 | 112 | 329000 | 168000 | 161000 | |

SEE LAST PAGE OF TABLE FOR NOTES

**TABLE 10**
**SVE SYSTEM MONTHLY MONITORING - VMP SAMPLING DATA**

| Sample ID | Date | Initial Reading Time (24-Hour) | Vacuum/Pressure | | Fixed Gases | | | | Soil Vapor Concentrations | | | | Comments |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | Initial Reading (Inches of $H_2O$) | Stabilized Reading (Inches of $H_2O$) | CH4 (%) | LEL (%) | $CO_2$ (%) | $O_2$ (%) | PID (ppmv) | THC (ppmv) | CH4 (ppmv) | PHC (ppmv) | |
| VMP-28-40 | 2/1/2012 | 1635 | -0.42 | -0.27 | OVR | OVR | 7.1 | 4.1 | 155 | 1000000 | 240000 | 760000 | |
| VMP-28-40 | 2/2/2012 | 1049 | -0.92 | -0.66 | OVR | OVR | 8.0 | 1.6 | 144 | 846000 | 223000 | 623000 | |
| VMP-28-40 | 2/7/2012 | 1011 | -0.49 | -0.57 | 0.0 | 0.0 | 0.1 | 20.9 | 29.2 | 90.8 | 7.0 | 83.8 | |
| VMP-28-40 | 2/10/2012 | 1111 | -0.12 | -0.62 | 0.0 | 0.0 | 0.1 | 20.7 | 25.0 | 62.9 | 3.1 | 59.8 | |
| VMP-28-40 | 2/13/2012 | 1027 | -0.78 | -0.44 | OVR | OVR | 1.8 | 14.5 | 135 | 76800 | 49900 | 26900 | |
| VMP-28-40 | 2/15/2012 | 1352 | -1.03 | -0.84 | 1.7 | 35.0 | 0.3 | 20.2 | 44.3 | 9789 | 9090 | 699 | |
| VMP-28-40 | 2/22/2012 | 1122 | -0.58 | - 0.53 | 0.0 | 0.0 | 0.2 | 20.9 | 0.8 | 15.4 | 3.0 | 12.5 | |
| VMP-28-40 | 2/29/2012 | 1053 | -0.09 | -0.52 | 3.2 | 64.0 | 0.1 | 20.9 | 389 | 5162 | 1170 | 3992 | |
| VMP-28-40 | 3/21/2012 | 1030 | -0.83 | -0.72 | 0.0 | 0.0 | 0.1 | 20.9 | 39.3 | 125 | 29.0 | 96.1 | |
| VMP-28-40 | 4/18/2012 | 1010 | -1.25 | -1.13 | 0.0 | 0.0 | 0.0 | 20.9 | 11.2 | 45.0 | 17.5 | 27.5 | |
| VMP-28-40 | 5/16/2012 | 1013 | -1.68 | -1.69 | 0.0 | 0.0 | 0.0 | 20.9 | 10.0 | 27.0 | 7.6 | 19.4 | |
| VMP-28-40 | 6/20/2012 | 1108 | -1.33 | -1.36 | 0.0 | 0.0 | 0.0 | 20.9 | 10.0 | 41.0 | 15.3 | 25.7 | |
| VMP-28-40 | 7/18/2012 | 1056 | -1.44 | -1.34 | 3.4 | 70.0 | 0.2 | 20.4 | 101 | 8950 | 6660 | 2290 | |
| VMP-28-40 | 8/15/2012 | 1108 | -1.48 | -1.44 | 0.0 | 0.0 | 0.0 | 20.9 | 6.6 | 39.1 | 26.1 | 13.0 | |
| VMP-28-40 | 9/19/2012 | 1013 | -2.40 | -2.31 | 0.1 | 2.0 | 0.0 | 20.7 | 32.3 | 769 | 583 | 186 | |
| VMP-28-40 | 10/17/2012 | 1033 | -1.88 | -2.00 | 1.4 | 29.0 | 0.2 | 20.8 | 122 | 3000 | 1620 | 1380 | |
| VMP-28-40 | 11/20/2012 | 1107 | -1.70 | -1.64 | 0.0 | 0.0 | 0.0 | 20.9 | 0.5 | 6.7 | 3.7 | 3.0 | |
| VMP-28-40 | 12/19/2012 | 1154 | -1.19 | -0.79 | 0.0 | 0.0 | 0.0 | 20.9 | 10.5 | 83.0 | 17.2 | 65.8 | |
| VMP-28-40 | 1/16/2013 | 1226 | -0.82 | -0.74 | OVR | OVR | 7.8 | 6.6 | 215 | 152000 | 76100 | 75900 | |
| VMP-28-40 | 2/25/2013 | 1115 | -1.16 | -1.05 | 0.0 | 0.0 | 0.0 | 20.9 | 7.4 | 59.2 | 16.0 | 43.2 | Tedlar results are suspect. |
| VMP-28-40 | 2/26/2013 | 1116 | -1.12 | -1.08 | OVR | OVR | 9.1 | 1.6 | 107 | 730000 | 266000 | 464000 | Resample. |
| VMP-28-40 | 3/20/2013 | 1102 | -2.79 | -0.65 | 10.2 | OVR | 1.5 | 18.9 | 74.8 | 18700 | 15500 | 3200 | Tedlar results are suspect. |
| VMP-29-10 | 12/5/2012 | 1632 | -0.06 | -0.09 | 0.0 | 0.0 | 1.3 | 19.3 | 1.2 | 2.9 | 0.0 | 2.9 | |
| VMP-29-10 | 12/6/2012 | 1353 | -0.03 | -0.06 | 0.0 | 0.0 | 1.6 | 18.8 | 0.5 | 1.8 | 0.0 | 1.8 | |
| VMP-29-10 | 12/13/2012 | 1321 | -0.01 | -0.01 | 0.0 | 0.0 | 3.2 | 17.3 | 0.6 | 0.7 | 0.0 | 0.7 | |
| VMP-29-10 | 12/19/2012 | 1400 | -0.01 | -0.06 | 0.0 | 0.0 | 2.6 | 17.9 | 0.6 | 1.4 | 0.0 | 1.4 | |
| VMP-29-10 | 1/16/2013 | 1003 | -0.02 | -0.06 | 0.0 | 0.0 | 0.7 | 20.2 | 0.2 | 2.9 | 0.0 | 2.9 | |
| VMP-29-10 | 2/25/2013 | 1250 | -0.08 | 0.05 | 0.0 | 0.0 | 0.6 | 20.4 | 1.6 | 3.3 | 0.0 | 3.3 | |
| VMP-29-10 | 3/20/2013 | 1420 | -0.03 | -0.09 | 0.0 | 0.0 | 0.8 | 20.2 | 1.4 | 3.0 | 0.0 | 3.0 | |
| VMP-29-20 | 12/5/2012 | 1635 | -0.08 | -0.10 | 0.0 | 0.0 | 0.6 | 20.3 | 1.9 | 4.9 | 0.0 | 4.9 | |
| VMP-29-20 | 12/6/2012 | 1353 | -0.03 | -0.06 | 0.0 | 0.0 | 0.5 | 20.5 | 1.1 | 3.0 | 0.0 | 3.0 | |
| VMP-29-20 | 12/13/2012 | 1324 | -0.01 | -0.02 | 0.0 | 0.0 | 5.8 | 14.0 | 5.2 | 5.4 | 0.0 | 5.4 | |
| VMP-29-20 | 12/19/2012 | 1405 | 0.00 | -0.06 | 0.0 | 0.0 | 6.9 | 13.0 | 1.4 | 0.3 | 0.0 | 0.3 | |
| VMP-29-20 | 1/16/2013 | 1004 | -0.02 | -0.07 | 0.0 | 0.0 | 1.0 | 20.0 | 0.7 | 4.7 | 0.0 | 4.7 | |
| VMP-29-20 | 2/25/2013 | 1255 | -0.08 | 0.05 | 0.0 | 0.0 | 1.2 | 19.7 | 1.5 | 2.5 | 0.0 | 2.5 | |
| VMP-29-20 | 3/20/2013 | 1424 | -0.04 | -0.09 | 0.0 | 0.0 | 1.6 | 19.6 | 4.4 | 7.1 | 0.0 | 7.1 | |
| VMP-29-30 | 12/5/2012 | 1640 | -0.10 | -0.13 | 0.0 | 0.0 | 2.1 | 18.6 | 8.0 | 12.9 | 0.0 | 12.9 | |
| VMP-29-30 | 12/6/2012 | 1357 | -0.04 | -0.06 | 0.0 | 0.0 | 4.7 | 15.4 | 15.5 | 18.4 | 0.0 | 18.4 | |
| VMP-29-30 | 12/13/2012 | 1337 | 0.02 | -0.02 | 0.0 | 0.0 | 9.3 | 10.0 | 8.5 | 13.8 | 0.0 | 13.8 | |
| VMP-29-30 | 12/19/2012 | 1415 | 0.00 | -0.06 | 0.0 | 0.0 | 8.5 | 10.6 | 2.4 | 2.6 | 0.0 | 2.6 | |
| VMP-29-30 | 1/16/2013 | 1005 | -0.02 | -0.08 | 0.0 | 0.0 | 5.2 | 15.3 | 5.4 | 8.5 | 0.0 | 8.5 | |
| VMP-29-30 | 2/25/2013 | 1300 | -0.10 | 0.06 | 0.0 | 0.0 | 3.7 | 16.7 | 1.5 | 1.3 | 0.0 | 1.3 | |
| VMP-29-30 | 3/20/2013 | 1428 | -0.05 | -0.08 | 0.0 | 0.0 | 2.1 | 19.0 | 4.9 | 7.4 | 0.0 | 7.4 | |

SEE LAST PAGE OF TABLE FOR NOTES

**TABLE 10**
**SVE SYSTEM MONTHLY MONITORING - VMP SAMPLING DATA**

| Sample ID | Date | Initial Reading Time (24-Hour) | Vacuum/Pressure | | Fixed Gases | | | | Soil Vapor Concentrations | | | | Comments |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | Initial Reading (Inches of $H_2O$) | Stabilized Reading (Inches of $H_2O$) | CH4 (%) | LEL (%) | $CO_2$ (%) | $O_2$ (%) | PID (ppmv) | THC (ppmv) | CH4 (ppmv) | PHC (ppmv) | |
| VMP-29-40 | 12/5/2012 | NM | -0.39 | NM | NM | NM | NM | NM | NM | NM | NM | NM | Screen submerged. |
| VMP-29-40 | 12/6/2012 | 1355 | -2.33 | NM | NM | NM | NM | NM | NM | NM | NM | NM | Screen submerged. |
| VMP-29-40 | 12/13/2012 | NM | -0.03 | NM | NM | NM | NM | NM | NM | NM | NM | NM | Screen submerged. |
| VMP-29-40 | 12/19/2012 | NM | 0.00 | NM | NM | NM | NM | NM | NM | NM | NM | NM | Screen submerged. |
| VMP-29-40 | 1/16/2013 | NM | 0.00 | NM | NM | NM | NM | NM | NM | NM | NM | NM | Screen submerged. |
| VMP-29-40 | 2/25/2013 | NM | NM | NM | NM | NM | NM | NM | NM | NM | NM | NM | Screen submerged. |
| VMP-29-40 | 3/20/2013 | NM | -0.21 | 0.00 | NM | NM | NM | NM | NM | NM | NM | NM | Screen submerged. |
| VMP-30-10 | 12/5/2012 | 1547 | -0.11 | -0.12 | 0.0 | 0.0 | 0.5 | 20.6 | 0.8 | 2.4 | 0.0 | 2.4 | |
| VMP-30-10 | 12/6/2012 | 1441 | -0.09 | -0.09 | 0.0 | 0.0 | 0.0 | 20.9 | 0.5 | 2.2 | 0.0 | 2.2 | |
| VMP-30-10 | 12/13/2012 | 1106 | -0.04 | -0.05 | 0.0 | 0.0 | 0.3 | 20.8 | 1.7 | 4.2 | 0.0 | 4.2 | |
| VMP-30-10 | 12/19/2012 | 1425 | -0.04 | -0.02 | 0.0 | 0.0 | 0.2 | 20.8 | 0.9 | 2.0 | 0.0 | 2.0 | |
| VMP-30-10 | 1/16/2013 | 1025 | -0.08 | -0.06 | 0.0 | 0.0 | 0.0 | 20.9 | 0.4 | 3.6 | 0.0 | 3.6 | |
| VMP-30-10 | 2/25/2013 | 1315 | -0.04 | -0.04 | 0.0 | 0.0 | 0.0 | 20.9 | 0.9 | 2.1 | 0.0 | 2.1 | |
| VMP-30-10 | 3/20/2013 | 1433 | -0.08 | -0.09 | 0.0 | 0.0 | 0.0 | 20.9 | 0.9 | 3.7 | 0.0 | 3.7 | |
| VMP-30-20 | 12/5/2012 | 1547 | -0.21 | -0.22 | 0.0 | 0.0 | 0.0 | 20.9 | 0.4 | 3.0 | 0.0 | 3.0 | |
| VMP-30-20 | 12/6/2012 | 1442 | -0.17 | -0.19 | 0.0 | 0.0 | 0.0 | 20.9 | 0.7 | 2.4 | 0.0 | 2.4 | |
| VMP-30-20 | 12/13/2012 | 1120 | -0.10 | -0.14 | 0.0 | 0.0 | 4.1 | 17.5 | 12.8 | 62.7 | 0.0 | 62.7 | |
| VMP-30-20 | 12/19/2012 | 1430 | -0.08 | -0.06 | 0.0 | 0.0 | 0.7 | 20.5 | 1.7 | 6.0 | 0.0 | 6.0 | |
| VMP-30-20 | 1/16/2013 | 1026 | -0.20 | -0.12 | 0.0 | 0.0 | 0.0 | 20.9 | 0.6 | 4.9 | 0.0 | 4.9 | |
| VMP-30-20 | 2/25/2013 | 1320 | -0.09 | -0.10 | 0.0 | 0.0 | 0.3 | 20.7 | 2.6 | 5.0 | 0.0 | 5.0 | |
| VMP-30-20 | 3/20/2013 | 1437 | -0.18 | -0.20 | 0.0 | 0.0 | 0.4 | 20.7 | 4.9 | 7.9 | 0.0 | 7.9 | |
| VMP-30-30 | 12/5/2012 | 1550 | -0.23 | -0.12 | 0.0 | 0.0 | 0.0 | 20.9 | 0.7 | 3.1 | 0.0 | 3.1 | |
| VMP-30-30 | 12/6/2012 | 1446 | -0.17 | -0.19 | 0.0 | 0.0 | 0.0 | 20.9 | 0.7 | 2.5 | 0.0 | 2.5 | |
| VMP-30-30 | 12/13/2012 | 1121 | -0.10 | -0.13 | 0.0 | 0.0 | 6.2 | 15.2 | 6.3 | 15.1 | 0.0 | 15.1 | |
| VMP-30-30 | 12/19/2012 | 1435 | -0.05 | -0.10 | 0.0 | 0.0 | 1.0 | 20.1 | 1.4 | 4.0 | 0.0 | 4.0 | |
| VMP-30-30 | 1/16/2013 | 1027 | -0.19 | -0.13 | 0.0 | 0.0 | 0.0 | 20.9 | 0.3 | 3.5 | 0.0 | 3.5 | |
| VMP-30-30 | 2/25/2013 | 1325 | -0.10 | -0.08 | 0.0 | 0.0 | 0.1 | 20.8 | 1.3 | 3.5 | 0.0 | 3.5 | |
| VMP-30-30 | 3/20/2013 | 1441 | -0.21 | -0.23 | 0.0 | 0.0 | 0.9 | 20.5 | 2.1 | 4.7 | 0.0 | 4.7 | |
| VMP-30-40 | 12/5/2012 | NM | NM | -0.33 | NM | NM | NM | NM | NM | NM | NM | NM | Screen submerged. |
| VMP-30-40 | 12/6/2012 | 1442 | 0.01 | NM | NM | NM | NM | NM | NM | NM | NM | NM | Screen submerged. |
| VMP-30-40 | 12/13/2012 | NM | NM | NM | NM | NM | NM | NM | NM | NM | NM | NM | Screen submerged. |
| VMP-30-40 | 12/19/2012 | NM | NM | NM | NM | NM | NM | NM | NM | NM | NM | NM | Screen submerged. |
| VMP-30-40 | 1/16/2013 | NM | NM | NM | NM | NM | NM | NM | NM | NM | NM | NM | Screen submerged. |
| VMP-30-40 | 2/25/2013 | NM | NM | NM | NM | NM | NM | NM | NM | NM | NM | NM | Screen submerged. |
| VMP-30-40 | 3/20/2013 | NM | NM | 0.00 | NM | NM | NM | NM | NM | NM | NM | NM | Screen submerged. |

SEE LAST PAGE OF TABLE FOR NOTES

**TABLE 10**
**SVE SYSTEM MONTHLY MONITORING - VMP SAMPLING DATA**

| Sample ID | Date | Initial Reading Time (24-Hour) | Vacuum/Pressure | | Fixed Gases | | | | Soil Vapor Concentrations | | | | Comments |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | Initial Reading (Inches of $H_2O$) | Stabilized Reading (Inches of $H_2O$) | CH4 (%) | LEL (%) | $CO_2$ (%) | $O_2$ (%) | PID (ppmv) | THC (ppmv) | CH4 (ppmv) | PHC (ppmv) | |
| VMP-31-5 | 2/1/2012 | 1552 | -0.25 | -0.30 | 0.0 | 0.0 | 0.5 | 20.5 | 0.1 | 0.6 | 0.0 | 0.6 | |
| VMP-31-5 | 2/2/2012 | 948 | -0.45 | -0.35 | 0.0 | 0.0 | 0.3 | 20.6 | 0.1 | 0.5 | 0.0 | 0.5 | |
| VMP-31-5 | 2/7/2012 | 1401 | -0.25 | -0.27 | 0.0 | 0.0 | 0.4 | 20.6 | 0.2 | 0.0 | 0.0 | 0.0 | |
| VMP-31-5 | 2/10/2012 | 906 | -0.10 | -0.38 | 0.0 | 0.0 | 0.2 | 20.8 | 1.0 | 7.5 | 6.3 | 1.2 | |
| VMP-31-5 | 2/13/2012 | 824 | -0.37 | -0.29 | 0.0 | 0.0 | 0.3 | 20.7 | 0.1 | 0.0 | 0.0 | 0.0 | |
| VMP-31-5 | 2/15/2012 | 1626 | 0.00 | -0.47 | 0.0 | 0.0 | 0.3 | 20.7 | 0.6 | 0.0 | 0.0 | 0.0 | |
| VMP-31-5 | 2/16/2012 | 1607 | -1.04 | -0.66 | 0.0 | 0.0 | 0.3 | 20.9 | 9.3 | 36.8 | 3.4 | 33.4 | |
| VMP-31-5 | 2/17/2012 | 912 | -0.64 | -0.41 | 0.0 | 0.0 | 0.4 | 20.8 | 1.1 | 6.3 | 5.0 | 1.3 | |
| VMP-31-5 | 2/20/2012 | 935 | -0.15 | -0.41 | 0.0 | 0.0 | 0.3 | 20.8 | 0.8 | 0.5 | 0.0 | 0.5 | |
| VMP-31-5 | 2/21/2012 | 830 | -0.39 | -0.53 | 0.0 | 0.0 | 0.2 | 20.9 | 0.5 | 4.0 | 0.0 | 4.0 | |
| VMP-31-5 | 2/22/2012 | 1001 | -0.25 | - 0.21 | 0.0 | 0.0 | 0.4 | 20.9 | 0.5 | 3.5 | 0.0 | 3.5 | |
| VMP-31-5 | 2/29/2012 | 1019 | -0.33 | - 0.19 | 0.0 | 0.0 | 0.5 | 20.4 | 0.8 | 6.0 | 3.1 | 2.9 | |
| VMP-31-5 | 3/21/2012 | 1447 | -0.11 | -0.11 | 0.0 | 0.0 | 0.5 | 20.0 | 0.2 | 0.0 | 0.0 | 0.0 | |
| VMP-31-5 | 4/18/2012 | 1446 | -0.16 | -0.15 | 0.0 | 0.0 | 0.1 | 20.4 | 2.0 | 5.3 | 0.0 | 5.3 | |
| VMP-31-5 | 5/16/2012 | 1046 | -0.40 | -0.44 | 0.0 | 0.0 | 1.5 | 19.0 | 0.3 | 0.2 | 0.0 | 0.2 | |
| VMP-31-5 | 6/20/2012 | 1734 | -0.15 | -0.16 | 0.0 | 0.0 | 1.6 | 19.0 | 0.1 | 1.5 | 0.0 | 1.5 | |
| VMP-31-5 | 7/18/2012 | 1508 | -0.22 | -0.20 | 0.0 | 0.0 | 0.6 | 19.9 | 0.9 | 5.7 | 4.3 | 1.4 | |
| VMP-31-5 | 8/15/2012 | 1503 | -0.21 | -0.74 | 0.0 | 0.0 | 0.8 | 20.0 | 1.2 | 4.4 | 0.0 | 4.4 | |
| VMP-31-5 | 9/19/2012 | 1323 | -0.43 | -0.59 | 0.0 | 0.0 | 0.7 | 20.1 | 0.9 | 2.4 | 0.0 | 2.4 | |
| VMP-31-5 | 10/17/2012 | 905 | -0.40 | 0.91 | 0.0 | 0.0 | 0.9 | 19.5 | 0.2 | 1.0 | 0.0 | 1.0 | |
| VMP-31-5 | 11/20/2012 | 1348 | -0.28 | -0.22 | 0.0 | 0.0 | 0.4 | 20.6 | 0.3 | 2.3 | 0.0 | 2.3 | |
| VMP-31-5 | 12/19/2012 | 1140 | -0.86 | -0.05 | 0.0 | 0.0 | 0.2 | 20.7 | 0.2 | 1.7 | 0.0 | 1.7 | |
| VMP-31-5 | 1/16/2013 | 1530 | -0.45 | -0.33 | 0.0 | 0.0 | 0.2 | 20.7 | 0.1 | 2.0 | 0.0 | 2.0 | |
| VMP-31-5 | 2/25/2013 | 1415 | -0.13 | -0.16 | 0.0 | 0.0 | 0.2 | 20.7 | 0.2 | 0.3 | 0.0 | 0.3 | |
| VMP-31-5 | 3/21/2013 | 958 | -0.86 | -0.83 | 0.0 | 0.0 | 0.1 | 20.8 | 0.4 | 2.1 | 0.0 | 2.1 | |
| VMP-31-10 | 2/1/2012 | 1559 | -0.40 | -0.50 | 0.0 | 0.0 | 0.5 | 20.3 | 0.2 | 0.5 | 0.0 | 0.5 | |
| VMP-31-10 | 2/2/2012 | 954 | -0.73 | -0.58 | 0.0 | 0.0 | 0.4 | 20.6 | 0.1 | 0.0 | 0.0 | 0.0 | |
| VMP-31-10 | 2/7/2012 | 1405 | -0.40 | -0.44 | 0.0 | 0.0 | 0.5 | 20.5 | 0.2 | 0.0 | 0.0 | 0.0 | |
| VMP-31-10 | 2/10/2012 | 907 | -0.15 | -0.62 | 0.0 | 0.0 | 0.3 | 20.8 | 1.0 | 6.8 | 6.1 | 0.7 | |
| VMP-31-10 | 2/13/2012 | 825 | -0.58 | -0.55 | 0.0 | 0.0 | 0.4 | 20.6 | 0.2 | 0.0 | 0.0 | 0.0 | |
| VMP-31-10 | 2/15/2012 | 1628 | -0.59 | -0.88 | 0.0 | 0.0 | 0.3 | 20.6 | 0.5 | 3.8 | 0.0 | 3.8 | |
| VMP-31-10 | 2/16/2012 | 1608 | -0.40 | -0.77 | 0.0 | 0.0 | 0.4 | 20.9 | 0.8 | 4.9 | 0.0 | 4.9 | |
| VMP-31-10 | 2/17/2012 | 913 | -0.83 | -0.63 | 0.0 | 0.0 | 0.4 | 20.8 | 0.7 | 3.1 | 0.0 | 3.1 | |
| VMP-31-10 | 2/20/2012 | 936 | -0.14 | -0.67 | 0.0 | 0.0 | 0.3 | 20.8 | 0.5 | 3.8 | 0.0 | 3.8 | |
| VMP-31-10 | 2/21/2012 | 831 | -0.90 | -0.88 | 0.0 | 0.0 | 0.3 | 20.9 | 0.5 | 3.8 | 0.0 | 3.8 | |
| VMP-31-10 | 2/22/2012 | 1001 | -0.42 | - 0.35 | 0.0 | 0.0 | 0.5 | 20.7 | 0.4 | 2.3 | 0.0 | 2.3 | |
| VMP-31-10 | 2/29/2012 | 1020 | -0.35 | - 0.37 | 0.0 | 0.0 | 0.5 | 20.3 | 0.5 | 2.5 | 0.0 | 2.5 | |
| VMP-31-10 | 3/21/2012 | 1448 | -0.22 | -0.17 | 0.0 | 0.0 | 0.6 | 20.0 | 0.3 | 0.0 | 0.0 | 0.0 | |
| VMP-31-10 | 4/18/2012 | 1447 | -0.29 | -0.26 | 0.0 | 0.0 | 0.1 | 20.9 | 0.8 | 5.0 | 0.0 | 5.0 | |
| VMP-31-10 | 5/16/2012 | 1052 | -0.69 | -0.66 | 0.0 | 0.0 | 1.9 | 18.7 | 0.4 | 0.0 | 0.0 | 0.0 | |
| VMP-31-10 | 6/20/2012 | 1739 | -0.27 | -0.27 | 0.0 | 0.0 | 1.5 | 19.2 | 0.6 | 1.6 | 0.0 | 1.6 | |
| VMP-31-10 | 7/18/2012 | 1509 | -0.37 | -0.32 | 0.0 | 0.0 | 0.7 | 19.9 | 1.0 | 6.6 | 3.3 | 3.3 | |
| VMP-31-10 | 8/15/2012 | 1508 | -0.38 | -0.46 | 0.0 | 0.0 | 1.0 | 19.5 | 1.0 | 4.5 | 0.0 | 4.5 | |
| VMP-31-10 | 9/19/2012 | 1324 | -0.59 | -0.68 | 0.0 | 0.0 | 0.9 | 19.9 | 0.9 | 3.4 | 0.0 | 3.4 | |
| VMP-31-10 | 10/17/2012 | 905 | -0.65 | -0.68 | 0.0 | 0.0 | 1.0 | 19.5 | 0.3 | 0.9 | 0.0 | 0.9 | |
| VMP-31-10 | 11/20/2012 | 1352 | -0.41 | -0.44 | 0.0 | 0.0 | 0.6 | 20.0 | 0.5 | 1.5 | 0.0 | 1.5 | |
| VMP-31-10 | 12/19/2012 | 1145 | -0.47 | -0.08 | 0.0 | 0.0 | 0.2 | 20.6 | 0.2 | 0.7 | 0.0 | 0.7 | |
| VMP-31-10 | 1/16/2013 | 1535 | -0.38 | -0.90 | 0.0 | 0.0 | 0.2 | 20.7 | 0.1 | 2.6 | 0.0 | 2.6 | |
| VMP-31-10 | 2/25/2013 | 1420 | -0.17 | -0.27 | 0.0 | 0.0 | 0.2 | 20.7 | 0.2 | 0.7 | 0.0 | 0.7 | |
| VMP-31-10 | 3/21/2013 | 1002 | -1.32 | -1.35 | 0.0 | 0.0 | 0.1 | 20.8 | 0.2 | 1.3 | 0.0 | 1.3 | |
| VMP-31-20 | 2/1/2012 | 1605 | -0.14 | NM | NM | NM | NM | NM | NM | NM | NM | NM | Screen submerged. |
| VMP-31-20 | 2/2/2012 | 1000 | NM | NM | NM | NM | NM | NM | NM | NM | NM | NM | Screen submerged. |
| VMP-31-20 | 2/7/2012 | 1358 | -0.67 | NM | NM | NM | NM | NM | NM | NM | NM | NM | Screen submerged. |
| VMP-31-20 | 2/10/2012 | 908 | NM | NM | NM | NM | NM | NM | NM | NM | NM | NM | Screen submerged. |
| VMP-31-20 | 2/13/2012 | 826 | -0.78 | NM | NM | NM | NM | NM | NM | NM | NM | NM | Screen submerged. |
| VMP-31-20 | 2/15/2012 | 1627 | 0.03 | NM | NM | NM | NM | NM | NM | NM | NM | NM | Screen submerged. |
| VMP-31-20 | 2/16/2012 | 1609 | -3.84 | NM | NM | NM | NM | NM | NM | NM | NM | NM | Screen submerged. |
| VMP-31-20 | 2/17/2012 | 914 | 0.00 | NM | NM | NM | NM | NM | NM | NM | NM | NM | Screen submerged. |

SEE LAST PAGE OF TABLE FOR NOTES

**TABLE 10**
**SVE SYSTEM MONTHLY MONITORING - VMP SAMPLING DATA**

| Sample ID | Date | Initial Reading Time (24-Hour) | Vacuum/Pressure | | Fixed Gases | | | | Soil Vapor Concentrations | | | | Comments |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | Initial Reading (Inches of $H_2O$) | Stabilized Reading (Inches of $H_2O$) | CH4 (%) | LEL (%) | $CO_2$ (%) | $O_2$ (%) | PID (ppmv) | THC (ppmv) | CH4 (ppmv) | PHC (ppmv) | |
| VMP-31-20 | 2/20/2012 | 937 | -1.07 | NM | NM | NM | NM | NM | NM | NM | NM | NM | Screen submerged. |
| VMP-31-20 | 2/21/2012 | 832 | 1.05 | NM | NM | NM | NM | NM | NM | NM | NM | NM | Screen submerged. |
| VMP-31-20 | 2/22/2012 | 1001 | -0.28 | NM | NM | NM | NM | NM | NM | NM | NM | NM | Screen submerged. |
| VMP-31-20 | 2/29/2012 | 1021 | 0.19 | NM | NM | NM | NM | NM | NM | NM | NM | NM | Screen submerged. |
| VMP-31-20 | 4/18/2012 | 1445 | 0.13 | NM | NM | NM | NM | NM | NM | NM | NM | NM | Screen submerged. |
| VMP-31-20 | 5/16/2012 | 1056 | -0.07 | NM | NM | NM | NM | NM | NM | NM | NM | NM | Screen submerged. |
| VMP-31-20 | 6/20/2012 | 1740 | NM | NM | NM | NM | NM | NM | NM | NM | NM | NM | Screen submerged. |
| VMP-31-20 | 7/18/2012 | 1510 | -0.27 | NM | NM | NM | NM | NM | NM | NM | NM | NM | Screen submerged. |
| VMP-31-20 | 8/15/2012 | 1511 | -0.74 | -0.88 | 0.8 | 17.0 | 6.1 | 14.3 | 252 | 1000 | 91.6 | 908 | |
| VMP-31-20 | 9/19/2012 | 1325 | -2.20 | -1.21 | 2.5 | 50.0 | 6.8 | 11.0 | 343 | 1780 | 250 | 1530 | |
| VMP-31-20 | 10/17/2012 | 906 | -1.03 | -0.75 | 5.8 | OVR | 10.1 | 6.2 | 441 | 2300 | 341 | 1959 | |
| VMP-31-20 | 11/20/2012 | 1356 | -0.75 | -0.79 | 2.3 | 46.0 | 8.6 | 8.1 | 383 | 1960 | 230 | 1730 | |
| VMP-31-20 | 12/19/2012 | 1150 | -0.77 | -0.23 | 0.6 | 12.0 | 7.2 | 12.1 | 210 | 1350 | 180 | 1170 | |
| VMP-31-20 | 1/16/2013 | 1545 | -1.16 | -0.66 | 0.2 | 4.0 | 6.7 | 12.4 | 90.6 | 765 | 115 | 650 | |
| VMP-31-20 | 2/25/2013 | 1425 | -0.18 | -0.15 | 0.0 | 0.0 | 0.1 | 20.7 | 2.0 | 13.9 | 1.3 | 12.6 | |
| VMP-31-20 | 3/21/2013 | 1006 | -0.70 | -0.81 | 0.0 | 0.0 | 1.4 | 19.3 | 8.0 | 22.7 | 13.2 | 9.5 | |
| VMP-31-30 | 2/1/2012 | 1605 | -1.39 | -0.72 | OVR | OVR | 6.0 | 0.9 | 81.1 | 1000000 | 742000 | 258000 | |
| VMP-31-30 | 2/2/2012 | 1004 | -1.30 | -0.97 | OVR | OVR | 5.8 | 1.8 | 75.0 | 1000000 | 860000 | 140000 | |
| VMP-31-30 | 2/7/2012 | 1410 | -0.67 | -0.72 | OVR | OVR | 6.3 | 2.7 | 79.2 | 1000000 | 1000000 | 0.0 | |
| VMP-31-30 | 2/10/2012 | 909 | -0.26 | -1.10 | OVR | OVR | 5.9 | 5.0 | 81.4 | 897000 | 285000 | 612000 | |
| VMP-31-30 | 2/13/2012 | 827 | -1.06 | -1.00 | OVR | OVR | 8.2 | 1.8 | 96.0 | 428000 | 169000 | 259000 | |
| VMP-31-30 | 2/15/2012 | 1629 | -0.97 | -1.02 | OVR | OVR | 8.8 | 2.3 | 101 | 1000000 | 226000 | 774000 | |
| VMP-31-30 | 2/16/2012 | 1610 | -1.37 | -1.29 | OVR | OVR | 8.5 | 2.6 | 121 | 371000 | 161000 | 210000 | |
| VMP-31-30 | 2/17/2012 | 915 | -1.19 | 1.02 | OVR | OVR | 9.8 | 2.1 | 125 | 245000 | 93200 | 151800 | |
| VMP-31-30 | 2/20/2012 | 938 | -0.26 | -1.18 | OVR | OVR | 9.6 | 1.6 | 148 | 167000 | 85300 | 81700 | |
| VMP-31-30 | 2/21/2012 | 833 | -1.57 | -1.60 | OVR | OVR | 9.4 | 1.4 | 158 | 310000 | 136000 | 174000 | |
| VMP-31-30 | 2/22/2012 | 1002 | -0.71 | - 0.61 | OVR | OVR | 9.6 | 1.9 | 130 | 151000 | 82750 | 68250 | |
| VMP-31-30 | 2/29/2012 | 1022 | -0.53 | - 0.67 | OVR | OVR | 10.4 | 1.3 | 189 | 67900 | 33590 | 34310 | |
| VMP-31-30 | 3/21/2012 | 1448 | -0.33 | -0.30 | OVR | OVR | 10.6 | 0.6 | 199 | 93400 | 46800 | 46600 | |
| VMP-31-30 | 4/18/2012 | 1449 | -0.59 | -0.52 | 7.1 | OVR | 10.3 | 1.8 | 114 | 11300 | 7800 | 3500 | |
| VMP-31-30 | 5/16/2012 | 1056 | -1.32 | -1.28 | 0.8 | 17.0 | 10.6 | 4.1 | 40.0 | 2990 | 2900 | 90.0 | |
| VMP-31-30 | 6/20/2012 | 1744 | -0.58 | -0.56 | 0.3 | 6.0 | 4.5 | 15.0 | 28.3 | 645 | 42.0 | 603 | |
| VMP-31-30 | 7/18/2012 | 1511 | -0.84 | -0.77 | 0.1 | 3.0 | 8.5 | 7.7 | 19.0 | 565 | 563 | 2.0 | |
| VMP-31-30 | 8/15/2012 | 1515 | -0.83 | -0.98 | 0.0 | 0.0 | 7.9 | 10.9 | 12.3 | 215 | 164 | 51.0 | |
| VMP-31-30 | 9/19/2012 | 1326 | -1.40 | -1.39 | 0.0 | 0.0 | 8.8 | 10.0 | 10.3 | 86.4 | 56.4 | 30.0 | |
| VMP-31-30 | 10/17/2012 | 906 | -1.24 | -3.58 | 0.2 | 5.0 | 3.4 | 17.6 | 25.7 | 286 | 28.8 | 257 | |
| VMP-31-30 | 11/20/2012 | 1400 | -0.90 | -0.96 | 0.1 | 3.0 | 8.2 | 12.2 | 54.0 | 137 | 12.9 | 124 | |
| VMP-31-30 | 12/19/2012 | 1155 | -0.85 | -0.51 | 2.3 | 26.0 | 11.0 | 8.0 | 86.0 | 5600 | 4250 | 1350 | |
| VMP-31-30 | 1/16/2013 | 1245 | -2.60 | -2.18 | OVR | OVR | 12.8 | 3.0 | 290 | 72000 | 25300 | 46700 | |
| VMP-31-30 | 2/25/2013 | 1430 | -0.41 | -0.44 | OVR | OVR | 15.3 | 0.6 | 266 | 34700 | 7600 | 27100 | |
| VMP-31-30 | 3/21/2013 | 1010 | -2.19 | -2.14 | OVR | OVR | 13.6 | 1.6 | 266 | 49800 | 16100 | 33700 | |

SEE LAST PAGE OF TABLE FOR NOTES

**TABLE 10**
**SVE SYSTEM MONTHLY MONITORING - VMP SAMPLING DATA**

| Sample ID | Date | Initial Reading Time (24-Hour) | Vacuum/Pressure | | Fixed Gases | | | | Soil Vapor Concentrations | | | | Comments |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | Initial Reading (Inches of $H_2O$) | Stabilized Reading (Inches of $H_2O$) | CH4 (%) | LEL (%) | $CO_2$ (%) | $O_2$ (%) | PID (ppmv) | THC (ppmv) | CH4 (ppmv) | PHC (ppmv) | |
| VMP-32-5 | 2/1/2012 | 1513 | -0.27 | -0.05 | 0.0 | 0.0 | 0.2 | 20.8 | 0.3 | 3.1 | 0.0 | 3.1 | |
| VMP-32-5 | 2/2/2012 | 918 | -0.06 | -0.04 | 0.0 | 0.0 | 0.1 | 20.9 | 0.3 | 2.3 | 0.0 | 2.3 | |
| VMP-32-5 | 2/7/2012 | 842 | -0.07 | -0.05 | 0.0 | 0.0 | 0.2 | 20.8 | 0.1 | 1.2 | 0.0 | 1.2 | |
| VMP-32-5 | 2/15/2012 | 1029 | -0.05 | -0.04 | 0.0 | 0.0 | 0.1 | 20.9 | 0.3 | 0.0 | 0.0 | 0.0 | |
| VMP-32-5 | 2/22/2012 | 1102 | -0.04 | - 0.01 | 0.0 | 0.0 | 0.3 | 20.9 | 1.0 | 8.2 | 3.7 | 4.5 | |
| VMP-32-5 | 2/29/2012 | 1058 | 0.00 | 0.00 | 0.0 | 0.0 | 0.2 | 20.8 | 0.6 | 3.3 | 0.0 | 3.3 | |
| VMP-32-5 | 3/21/2012 | 1322 | 0.00 | 0.00 | 0.0 | 0.0 | 0.2 | 20.6 | 0.4 | 0.0 | 0.0 | 0.0 | |
| VMP-32-5 | 4/18/2012 | 1139 | -0.04 | 0.00 | 0.0 | 0.0 | 0.1 | 20.7 | 0.8 | 2.1 | 0.0 | 2.1 | |
| VMP-32-5 | 5/16/2012 | 1102 | -0.04 | -0.04 | 0.0 | 0.0 | 0.3 | 20.6 | 0.3 | 0.2 | 0.0 | 0.2 | |
| VMP-32-5 | 6/20/2012 | 1508 | 0.00 | -0.01 | 0.0 | 0.0 | 2.2 | 18.7 | 0.4 | 21.3 | 9.6 | 11.7 | |
| VMP-32-5 | 7/18/2012 | 1428 | -0.04 | -0.03 | 0.0 | 0.0 | 0.9 | 19.7 | 1.2 | 9.0 | 4.7 | 4.3 | |
| VMP-32-5 | 8/15/2012 | 1555 | -0.03 | -0.03 | 0.0 | 0.0 | 1.8 | 18.9 | 0.7 | 4.7 | 0.0 | 4.7 | |
| VMP-32-5 | 9/19/2012 | 1407 | -0.04 | -0.04 | 0.0 | 0.0 | 1.1 | 19.8 | 0.6 | 3.6 | 0.0 | 3.6 | |
| VMP-32-5 | 10/17/2012 | 920 | -0.03 | -0.03 | 0.0 | 0.0 | 1.0 | 18.5 | 0.3 | 0.5 | 0.0 | 0.5 | |
| VMP-32-5 | 11/20/2012 | 1328 | -0.03 | -0.02 | 0.0 | 0.0 | 0.3 | 20.3 | 0.3 | 1.1 | 0.0 | 1.1 | |
| VMP-32-5 | 12/19/2012 | NM | NM | NM | NM | NM | NM | NM | NM | NM | NM | NM | Construction equipment parked on well. Could not access. |
| VMP-32-5 | 1/16/2013 | NM | NM | NM | NM | NM | NM | NM | NM | NM | NM | NM | Vehicle parked on well. Could not access. |
| VMP-32-5 | 2/25/2013 | 1450 | 0.00 | -0.02 | 0.0 | 0.0 | 0.2 | 20.6 | 0.2 | 0.9 | 0.0 | 0.9 | |
| VMP-32-5 | 3/21/2013 | 940 | -0.03 | -0.01 | 0.0 | 0.0 | 0.2 | 20.7 | 0.3 | 1.9 | 0.0 | 1.9 | |
| VMP-32-10 | 2/1/2012 | 1519 | -0.11 | -0.10 | 0.0 | 0.0 | 2.8 | 18.2 | 0.3 | 0.4 | 0.0 | 0.4 | |
| VMP-32-10 | 2/2/2012 | 923 | -0.10 | -0.25 | 0.0 | 0.0 | 2.4 | 18.9 | 0.2 | 0.0 | 0.0 | 0.0 | |
| VMP-32-10 | 2/7/2012 | 843 | -0.16 | -0.12 | 0.0 | 0.0 | 2.5 | 18.8 | 0.2 | 0.0 | 0.0 | 0.0 | |
| VMP-32-10 | 2/15/2012 | 1030 | -0.12 | -0.10 | 0.0 | 0.0 | 2.2 | 18.8 | 0.3 | 0.0 | 0.0 | 0.0 | |
| VMP-32-10 | 2/22/2012 | 1102 | -0.07 | - 0.62 | 0.0 | 0.0 | 2.3 | 19.1 | 1.3 | 7.7 | 0.0 | 7.7 | |
| VMP-32-10 | 2/29/2012 | 1059 | -0.08 | 0.00 | 0.0 | 0.0 | 2.1 | 18.8 | 0.6 | 2.6 | 0.0 | 2.6 | |
| VMP-32-10 | 3/21/2012 | 1323 | -0.04 | -0.03 | 0.0 | 0.0 | 2.0 | 18.5 | 0.2 | 0.0 | 0.0 | 0.0 | |
| VMP-32-10 | 4/18/2012 | 1140 | -0.09 | -0.06 | 0.0 | 0.0 | 2.2 | 18.0 | 0.5 | 2.2 | 0.0 | 2.2 | |
| VMP-32-10 | 5/16/2012 | 1109 | -0.10 | -0.07 | 0.0 | 0.0 | 2.9 | 17.2 | 0.5 | 0.0 | 0.0 | 0.0 | |
| VMP-32-10 | 6/20/2012 | 1509 | -0.01 | -0.02 | 0.0 | 0.0 | 3.6 | 16.2 | 1.0 | 4.6 | 0.0 | 4.6 | |
| VMP-32-10 | 7/18/2012 | 1429 | -0.07 | -0.05 | 0.0 | 0.0 | 3.2 | 17.1 | 0.6 | 2.7 | 0.0 | 2.7 | |
| VMP-32-10 | 8/15/2012 | 1550 | -0.08 | -0.06 | 0.0 | 0.0 | 3.5 | 17.5 | 0.9 | 4.2 | 0.0 | 4.2 | |
| VMP-32-10 | 9/19/2012 | 1408 | -0.07 | -0.10 | 0.0 | 0.0 | 3.4 | 17.2 | 1.1 | 4.2 | 0.0 | 4.2 | |
| VMP-32-10 | 10/17/2012 | 921 | -0.05 | 0.00 | 0.0 | 0.0 | 3.4 | 17.4 | 0.4 | 0.4 | 0.0 | 0.4 | |
| VMP-32-10 | 11/20/2012 | 1333 | -0.05 | -0.04 | 0.0 | 0.0 | 2.4 | 18.4 | 0.3 | 0.5 | 0.0 | 0.5 | |
| VMP-32-10 | 12/19/2012 | NM | NM | NM | NM | NM | NM | NM | NM | NM | NM | NM | Construction equipment parked on well. Could not access. |
| VMP-32-10 | 1/16/2013 | NM | NM | NM | NM | NM | NM | NM | NM | NM | NM | NM | Vehicle parked on well. Could not access. |
| VMP-32-10 | 2/25/2013 | 1455 | 0.00 | 0.00 | 0.0 | 0.0 | 2.2 | 18.2 | 0.2 | 0.7 | 0.0 | 0.7 | |
| VMP-32-10 | 3/21/2013 | 944 | -0.08 | -0.05 | 0.0 | 0.0 | 2.2 | 18.5 | 0.2 | 0.8 | 0.0 | 0.8 | |

SEE LAST PAGE OF TABLE FOR NOTES

**TABLE 10**
**SVE SYSTEM MONTHLY MONITORING - VMP SAMPLING DATA**

| Sample ID | Date | Initial Reading Time (24-Hour) | Vacuum/Pressure | | Fixed Gases | | | | Soil Vapor Concentrations | | | | Comments |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | Initial Reading (Inches of $H_2O$) | Stabilized Reading (Inches of $H_2O$) | CH4 (%) | LEL (%) | $CO_2$ (%) | $O_2$ (%) | PID (ppmv) | THC (ppmv) | CH4 (ppmv) | PHC (ppmv) | |
| VMP-32-20 | 2/1/2012 | 1523 | -0.03 | -0.57 | 0.8 | 16.0 | 4.4 | 16.0 | 55.5 | 1280 | 921 | 359 | |
| VMP-32-20 | 2/2/2012 | 929 | -0.75 | -0.61 | 0.0 | 0.0 | 3.5 | 17.3 | 0.8 | 5.4 | 2.0 | 3.4 | |
| VMP-32-20 | 2/7/2012 | 844 | -0.70 | -0.53 | 0.0 | 0.0 | 3.9 | 17.3 | 0.3 | 2.3 | 0.0 | 2.3 | |
| VMP-32-20 | 2/15/2012 | 1031 | -0.83 | -0.64 | 0.0 | 0.0 | 3.7 | 17.2 | 0.5 | 11.3 | 8.5 | 2.8 | |
| VMP-32-20 | 2/22/2012 | 1103 | -0.28 | - 0.20 | 0.1 | 2.0 | 3.9 | 16.8 | 16.8 | 522 | 413 | 109 | |
| VMP-32-20 | 2/29/2012 | 1100 | -0.48 | - 0.26 | 0.5 | 10.0 | 4.2 | 16.1 | 108 | 788 | 12.8 | 775 | |
| VMP-32-20 | 3/21/2012 | 840 | -0.32 | -0.11 | 0.0 | 0.0 | 3.4 | 16.5 | 15.6 | 603 | 476 | 128 | |
| VMP-32-20 | 4/18/2012 | 1141 | -0.44 | -0.24 | 0.0 | 0.0 | 3.4 | 16.4 | 0.5 | 2.8 | 0.0 | 2.8 | |
| VMP-32-20 | 5/16/2012 | 1113 | -0.74 | -0.68 | 0.0 | 0.0 | 4.2 | 15.4 | 0.4 | 0.0 | 0.0 | 0.0 | |
| VMP-32-20 | 6/20/2012 | 1510 | -0.15 | -0.18 | 0.0 | 0.0 | 4.2 | 15.2 | 1.5 | 23.9 | 21.2 | 2.7 | |
| VMP-32-20 | 7/18/2012 | 1430 | -0.35 | -0.38 | 0.0 | 0.0 | 4.6 | 15.1 | 0.8 | 18.0 | 3.9 | 14.1 | |
| VMP-32-20 | 8/15/2012 | 1559 | -0.40 | -0.42 | 0.0 | 0.0 | 5.0 | 15.9 | 1.0 | 3.5 | 0.0 | 3.5 | |
| VMP-32-20 | 9/19/2012 | 1409 | -0.56 | -0.64 | 0.0 | 0.0 | 5.1 | 15.2 | 1.1 | 3.0 | 0.0 | 3.0 | |
| VMP-32-20 | 10/17/2012 | 922 | -0.54 | -0.44 | 0.0 | 0.0 | 4.8 | 16.2 | 0.4 | 0.6 | 0.0 | 0.6 | |
| VMP-32-20 | 11/20/2012 | 1338 | -0.41 | -0.42 | 0.0 | 0.0 | 4.2 | 17.0 | 0.4 | 0.4 | 0.0 | 0.4 | |
| VMP-32-20 | 12/19/2012 | NM | NM | NM | NM | NM | NM | NM | NM | NM | NM | NM | Construction equipment parked on well. Could not access. |
| VMP-32-20 | 1/16/2013 | NM | NM | NM | NM | NM | NM | NM | NM | NM | NM | NM | Vehicle parked on well. Could not access. |
| VMP-32-20 | 2/25/2013 | 1500 | -0.15 | -0.11 | 0.0 | 0.0 | 3.7 | 16.5 | 0.3 | 0.7 | 0.0 | 0.7 | |
| VMP-32-20 | 3/21/2013 | 948 | -1.11 | -1.03 | 0.0 | 0.0 | 3.6 | 16.5 | 0.3 | 0.4 | 0.0 | 0.4 | |
| VMP-32-30 | 2/1/2012 | 1526 | -0.40 | -0.38 | OVR | OVR | 10.8 | 0.8 | 528 | 55500 | 17600 | 37900 | |
| VMP-32-30 | 2/2/2012 | 934 | -0.82 | -0.63 | OVR | OVR | 10.8 | 1.1 | 493 | 43800 | 13500 | 30300 | |
| VMP-32-30 | 2/7/2012 | 845 | -0.71 | -0.56 | OVR | OVR | 10.9 | 1.2 | 436 | 81000 | 19200 | 61800 | |
| VMP-32-30 | 2/15/2012 | 1032 | -0.74 | -0.58 | OVR | OVR | 10.0 | 1.9 | 450 | 32600 | 10700 | 21900 | |
| VMP-32-30 | 2/22/2012 | 1103 | -0.30 | - 0.22 | OVR | OVR | 10.3 | 1.6 | 489 | 36700 | 10440 | 26260 | |
| VMP-32-30 | 2/29/2012 | 1101 | -0.53 | - 0.36 | OVR | OVR | 10.2 | 1.4 | 526 | 29600 | 7770 | 21830 | |
| VMP-32-30 | 3/21/2012 | 1324 | -0.26 | -0.05 | OVR | OVR | 10.6 | 0.5 | 499 | 37400 | 11700 | 25700 | |
| VMP-32-30 | 4/18/2012 | 1142 | -0.47 | -0.26 | 84.5 | OVR | 9.3 | 1.8 | 444 | 26000 | 8150 | 17850 | |
| VMP-32-30 | 5/16/2012 | 1117 | -0.84 | -0.76 | 67.9 | OVR | 9.4 | 2.2 | 480 | 20500 | 7100 | 13400 | |
| VMP-32-30 | 6/20/2012 | 1511 | -0.16 | -0.22 | 13.0 | OVR | 10.7 | 0.5 | 265 | 5950 | 2640 | 3310 | |
| VMP-32-30 | 7/18/2012 | 1431 | -0.39 | -0.42 | 21.8 | OVR | 8.9 | 3.8 | 388 | 9320 | 3150 | 6170 | |
| VMP-32-30 | 8/15/2012 | 1604 | -0.45 | -0.48 | 9.5 | OVR | 11.3 | 1.5 | 325 | 4700 | 2400 | 2300 | |
| VMP-32-30 | 9/19/2012 | 1410 | -0.64 | -0.75 | 7.1 | OVR | 11.6 | 1.7 | 357 | 3500 | 2300 | 1200 | |
| VMP-32-30 | 10/17/2012 | 923 | -0.62 | -0.54 | 0.1 | 3.0 | 9.8 | 6.5 | 17.1 | 1400 | 540 | 860 | |
| VMP-32-30 | 11/20/2012 | 1343 | -0.92 | -0.51 | 0.1 | 2.0 | 12.9 | 2.6 | 83.0 | 480 | 51.5 | 429 | |
| VMP-32-30 | 12/19/2012 | NM | NM | NM | NM | NM | NM | NM | NM | NM | NM | NM | Construction equipment parked on well. Could not access. |
| VMP-32-30 | 1/16/2013 | NM | NM | NM | NM | NM | NM | NM | NM | NM | NM | NM | Vehicle parked on well. Could not access. |
| VMP-32-30 | 2/25/2013 | 1505 | -0.15 | -0.12 | 0.0 | 0.0 | 13.5 | 2.6 | 22.5 | 123 | 13.5 | 109 | |
| VMP-32-30 | 3/21/2013 | 952 | -1.35 | -1.22 | 2.4 | 46.0 | 14.2 | 1.3 | 242 | 1650 | 790 | 860 | |

SEE LAST PAGE OF TABLE FOR NOTES

**TABLE 10**
**SVE SYSTEM MONTHLY MONITORING - VMP SAMPLING DATA**

| Sample ID | Date | Initial Reading Time (24-Hour) | Vacuum/Pressure | | Fixed Gases | | | | Soil Vapor Concentrations | | | | Comments |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | Initial Reading (Inches of $H_2O$) | Stabilized Reading (Inches of $H_2O$) | CH4 (%) | LEL (%) | $CO_2$ (%) | $O_2$ (%) | PID (ppmv) | THC (ppmv) | CH4 (ppmv) | PHC (ppmv) | |
| VMP-33-10 | 2/15/2012 | 1555 | -0.12 | -0.50 | 0.0 | 0.0 | 9.0 | 3.4 | 6.5 | 136 | 124 | 12.2 | |
| VMP-33-10 | 2/16/2012 | 1323 | -0.10 | -0.14 | 0.0 | 0.0 | 3.6 | 15.8 | 2.7 | 5.4 | 0.0 | 5.4 | |
| VMP-33-10 | 2/17/2012 | 1019 | -0.26 | -0.08 | 0.0 | 0.0 | 3.8 | 15.7 | 1.4 | 2.7 | 0.0 | 2.7 | |
| VMP-33-10 | 2/22/2012 | 840 | 0.00 | -0.14 | 0.0 | 0.0 | 5.1 | 10.0 | 0.7 | 11.8 | 0.0 | 11.8 | |
| VMP-33-10 | 2/29/2012 | 842 | -0.08 | -0.10 | 0.0 | 0.0 | 3.9 | 15.3 | 0.5 | 2.5 | 0.0 | 2.5 | |
| VMP-33-10 | 3/21/2012 | 839 | -0.09 | -0.10 | 0.0 | 0.0 | 4.2 | 17.0 | 0.1 | 1.3 | 0.0 | 1.3 | |
| VMP-33-10 | 4/18/2012 | 1050 | -0.05 | 0.00 | 0.0 | 0.0 | 3.6 | 17.2 | 0.4 | 4.4 | 0.0 | 4.4 | |
| VMP-33-10 | 5/16/2012 | 1026 | -0.13 | -0.10 | 0.0 | 0.0 | 2.9 | 18.1 | 0.5 | 0.0 | 0.0 | 0.0 | |
| VMP-33-10 | 6/20/2012 | 1053 | -0.08 | -0.08 | 0.0 | 0.0 | 1.9 | 19.2 | 0.4 | 0.0 | 0.0 | 0.0 | |
| VMP-33-10 | 7/18/2012 | 1112 | -0.06 | -0.03 | 0.0 | 0.0 | 2.2 | 18.5 | 0.9 | 1.6 | 0.0 | 1.6 | |
| VMP-33-10 | 8/15/2012 | 927 | -0.05 | -0.05 | 0.0 | 0.0 | 1.8 | 19.3 | 1.0 | 4.5 | 0.0 | 4.5 | |
| VMP-33-10 | 9/19/2012 | 1252 | 0.00 | 0.00 | 0.0 | 0.0 | 0.7 | 20.2 | 0.9 | 3.5 | 0.0 | 3.5 | |
| VMP-33-10 | 10/17/2012 | 831 | -0.09 | -0.08 | 0.0 | 0.0 | 0.5 | 20.4 | 0.9 | 1.3 | 0.0 | 1.3 | |
| VMP-33-10 | 11/20/2012 | 914 | -0.10 | -0.07 | 0.0 | 0.0 | 0.3 | 20.6 | 0.5 | 1.6 | 0.0 | 1.6 | |
| VMP-33-10 | 12/19/2012 | 1001 | -0.05 | -0.08 | 0.0 | 0.0 | 0.2 | 20.6 | 0.1 | 0.2 | 0.0 | 0.2 | |
| VMP-33-10 | 1/16/2013 | 1237 | 0.02 | 0.00 | 0.0 | 0.0 | 0.3 | 20.5 | 0.2 | 1.2 | 0.0 | 1.2 | |
| VMP-33-10 | 2/25/2013 | 908 | -0.05 | -0.05 | 0.0 | 0.0 | 0.0 | 20.9 | 0.2 | 3.5 | 0.0 | 3.5 | |
| VMP-33-10 | 3/20/2013 | 852 | -0.22 | -0.16 | 0.0 | 0.0 | 0.1 | 20.7 | 0.2 | 0.5 | 0.0 | 0.5 | |
| VMP-33-20 | 2/15/2012 | 1601 | -0.23 | -0.83 | OVR | OVR | 7.1 | 3.3 | 96.5 | 85280 | 74660 | 10620 | |
| VMP-33-20 | 2/16/2012 | 1324 | -0.38 | -0.44 | OVR | OVR | 7.1 | 1.4 | 114 | 95460 | 76200 | 19260 | |
| VMP-33-20 | 2/17/2012 | 1019 | -0.24 | -0.28 | 90.9 | OVR | 6.9 | 2.0 | 119 | 76200 | 55800 | 20400 | |
| VMP-33-20 | 2/22/2012 | 841 | 0.00 | 0.09 | OVR | OVR | 7.4 | 1.5 | 100 | 108000 | 60600 | 47400 | |
| VMP-33-20 | 2/29/2012 | 843 | -0.01 | -0.38 | 31.9 | OVR | 7.4 | 1.3 | 120 | 39200 | 35050 | 4150 | |
| VMP-33-20 | 3/21/2012 | 840 | -0.32 | -0.32 | 1.1 | 23.0 | 7.4 | 2.7 | 40.1 | 5430 | 4940 | 490 | |
| VMP-33-20 | 4/18/2012 | 1050 | -0.17 | -0.10 | 0.4 | 9.0 | 9.8 | 1.1 | 15.1 | 3260 | 3200 | 60.0 | |
| VMP-33-20 | 5/16/2012 | 1027 | -0.44 | -0.43 | 0.0 | 0.0 | 12.0 | 1.5 | 3.1 | 724 | 661 | 63.0 | |
| VMP-33-20 | 6/20/2012 | 1054 | -0.25 | -0.28 | 0.0 | 0.0 | 14.0 | 1.2 | 1.5 | 326 | 45.5 | 281 | |
| VMP-33-20 | 7/18/2012 | 1113 | -0.25 | -0.16 | 0.0 | 0.0 | 16.8 | 3.5 | 1.1 | 80.1 | 3.8 | 76.3 | |
| VMP-33-20 | 8/15/2012 | 928 | -0.25 | -0.25 | 0.0 | 0.0 | 17.6 | 6.5 | 0.8 | 36.0 | 1.2 | 34.8 | |
| VMP-33-20 | 9/19/2012 | 1254 | -0.18 | -0.12 | 0.0 | 0.0 | 14.3 | 11.2 | 1.2 | 25.6 | 2.1 | 23.5 | |
| VMP-33-20 | 10/17/2012 | 832 | -0.38 | -0.33 | 0.0 | 0.0 | 11.0 | 13.4 | 0.4 | 2.2 | 0.0 | 2.2 | |
| VMP-33-20 | 11/20/2012 | 920 | -0.42 | -0.28 | 0.0 | 0.0 | 8.8 | 15.5 | 0.6 | 1.7 | 0.0 | 1.7 | |
| VMP-33-20 | 12/19/2012 | 1002 | -0.39 | -0.34 | 0.0 | 0.0 | 9.2 | 14.5 | 0.2 | 0.4 | 0.0 | 0.4 | |
| VMP-33-20 | 1/16/2013 | 1242 | 0.04 | 0.02 | 0.0 | 0.0 | 9.7 | 12.2 | 0.2 | 0.2 | 0.0 | 0.2 | |
| VMP-33-20 | 2/25/2013 | 912 | -0.21 | -0.20 | 0.0 | 0.0 | 5.5 | 17.7 | 0.2 | 1.0 | 0.0 | 1.0 | |
| VMP-33-20 | 3/20/2013 | 856 | -0.83 | -0.65 | 0.0 | 0.0 | 3.1 | 19.5 | 0.2 | 0.8 | 0.0 | 0.8 | |

SEE LAST PAGE OF TABLE FOR NOTES

**TABLE 10**
**SVE SYSTEM MONTHLY MONITORING - VMP SAMPLING DATA**

| Sample ID | Date | Initial Reading Time (24-Hour) | Vacuum/Pressure | | Fixed Gases | | | | Soil Vapor Concentrations | | | | Comments |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | Initial Reading (Inches of $H_2O$) | Stabilized Reading (Inches of $H_2O$) | CH4 (%) | LEL (%) | $CO_2$ (%) | $O_2$ (%) | PID (ppmv) | THC (ppmv) | CH4 (ppmv) | PHC (ppmv) | |
| VMP-33-30 | 2/15/2012 | 1605 | -0.24 | -0.60 | OVR | OVR | 7.3 | 1.6 | 89.7 | 200000 | 137000 | 63000 | |
| VMP-33-30 | 2/16/2012 | 1326 | -0.48 | -0.56 | OVR | OVR | 7.4 | 1.7 | 101 | 188000 | 155000 | 33000 | |
| VMP-33-30 | 2/17/2012 | 1019 | -0.30 | -0.34 | OVR | OVR | 7.3 | 1.3 | 106 | 249000 | 118000 | 131000 | |
| VMP-33-30 | 2/22/2012 | 842 | 0.00 | 0.15 | OVR | OVR | 7.5 | 1.4 | 86.3 | 219000 | 141000 | 78000 | |
| VMP-33-30 | 2/29/2012 | 844 | -0.04 | -0.06 | OVR | OVR | 7.4 | 1.4 | 111 | 136000 | 106000 | 30000 | |
| VMP-33-30 | 3/21/2012 | 840 | -1.00 | -0.80 | 74.6 | OVR | 7.3 | 1.7 | 110 | 114000 | 89500 | 24500 | |
| VMP-33-30 | 4/18/2012 | 1050 | -0.21 | -0.11 | 36.7 | OVR | 7.7 | 1.0 | 111 | 50900 | 40700 | 10200 | |
| VMP-33-30 | 5/16/2012 | 1028 | -0.56 | -0.56 | 7.3 | OVR | 9.2 | 0.8 | 73.6 | 24200 | 20000 | 4200 | |
| VMP-33-30 | 6/20/2012 | 1055 | -0.30 | -0.35 | 3.6 | 73.0 | 9.8 | 0.1 | 34.3 | 14100 | 11940 | 2160 | |
| VMP-33-30 | 7/18/2012 | 1114 | -0.31 | -0.20 | 2.5 | 50.0 | 10.5 | 1.4 | 30.7 | 11900 | 9910 | 1990 | |
| VMP-33-30 | 8/15/2012 | 929 | -0.32 | -0.31 | 2.0 | 21.0 | 10.8 | 2.1 | 36.0 | 9100 | 7400 | 1700 | |
| VMP-33-30 | 9/19/2012 | 1256 | -0.24 | -0.15 | 1.2 | 24.0 | 12.2 | 1.0 | 31.3 | 5900 | 4700 | 1200 | |
| VMP-33-30 | 10/17/2012 | 833 | -0.48 | -0.40 | 0.7 | 15.0 | 10.9 | 1.6 | 19.0 | 4400 | 3240 | 1160 | |
| VMP-33-30 | 11/20/2012 | 924 | -0.54 | -0.36 | 0.2 | 5.0 | 10.5 | 1.3 | 18.0 | 2460 | 2100 | 360 | |
| VMP-33-30 | 12/19/2012 | 1003 | -0.52 | -0.46 | 0.0 | 1.0 | 14.4 | 1.6 | 3.9 | 735 | 680 | 55.0 | |
| VMP-33-30 | 1/16/2013 | 1247 | 0.05 | 0.07 | 0.0 | 0.0 | 14.9 | 2.8 | 1.7 | 550 | 460 | 90.0 | |
| VMP-33-30 | 2/25/2013 | 916 | -0.26 | -0.26 | 0.0 | 0.0 | 13.6 | 5.7 | 1.0 | 41.7 | 17.3 | 24.4 | |
| VMP-33-30 | 3/20/2013 | 900 | 0.00 | -0.84 | NM | NM | NM | NM | NM | NM | NM | NM | Water encountered during sampling. |
| VMP-34-10 | 2/15/2012 | 1615 | -0.40 | -0.38 | OVR | OVR | 9.2 | 1.3 | 49.4 | 315000 | 271000 | 44000 | |
| VMP-34-10 | 2/16/2012 | 1347 | -0.86 | -0.97 | 23.4 | OVR | 7.8 | 5.8 | 36.6 | 69300 | 66100 | 3200 | |
| VMP-34-10 | 2/17/2012 | 1054 | -0.60 | -0.50 | 19.0 | OVR | 9.7 | 2.0 | 31.8 | 68900 | 68000 | 900 | |
| VMP-34-10 | 2/20/2012 | 1057 | -0.49 | -0.37 | 9.5 | OVR | 8.7 | 3.9 | 17.6 | 66900 | 59800 | 7100 | |
| VMP-34-10 | 2/21/2012 | 1018 | -1.03 | -1.06 | 48.7 | OVR | 8.9 | 3.9 | 38.2 | 211000 | 105000 | 106000 | |
| VMP-34-10 | 2/22/2012 | 908 | 0.00 | 0.06 | OVR | OVR | 9.1 | 1.7 | 50.4 | 199000 | 199000 | 0.0 | |
| VMP-34-10 | 2/29/2012 | 922 | -0.45 | -0.50 | OVR | OVR | 8.9 | 1.4 | 46.2 | 367000 | 268000 | 99000 | |
| VMP-34-10 | 3/21/2012 | 915 | -0.54 | -0.49 | OVR | OVR | 7.8 | 4.2 | 30.0 | 212000 | 210000 | 2000 | |
| VMP-34-10 | 4/18/2012 | 1032 | -0.36 | -0.33 | 12.8 | OVR | 5.9 | 6.0 | 11.5 | 74000 | 64000 | 10000 | |
| VMP-34-10 | 5/16/2012 | 1044 | -0.69 | -0.68 | 3.1 | 64.0 | 2.6 | 16.0 | 11.0 | 24300 | 20400 | 3900 | |
| VMP-34-10 | 6/20/2012 | 859 | -0.60 | -0.43 | 0.8 | 17.0 | 1.9 | 18.9 | 4.8 | 2300 | 1170 | 1130 | |
| VMP-34-10 | 7/18/2012 | 933 | -0.48 | -0.49 | 0.3 | 6.0 | 2.0 | 18.0 | 8.3 | 2730 | 2600 | 130 | |
| VMP-34-10 | 8/15/2012 | 902 | -0.46 | -0.47 | 0.0 | 0.0 | 0.3 | 20.7 | 2.0 | 75.0 | 6.3 | 68.7 | |
| VMP-34-10 | 9/19/2012 | 1207 | -0.55 | -0.49 | 0.0 | 0.0 | 1.8 | 17.0 | 1.8 | 5.0 | 0.0 | 5.0 | |
| VMP-34-10 | 10/17/2012 | 907 | -0.61 | -0.58 | 0.0 | 0.0 | 2.8 | 14.8 | 0.4 | 7.9 | 7.9 | 0.0 | |
| VMP-34-10 | 11/20/2012 | 929 | -0.66 | -0.50 | 0.0 | 0.0 | 2.9 | 14.5 | 0.4 | 6.6 | 6.4 | 0.2 | |
| VMP-34-10 | 12/19/2012 | 1042 | -0.63 | -0.44 | 0.0 | 0.0 | 2.2 | 15.8 | 0.6 | 3.4 | 0.0 | 3.4 | |
| VMP-34-10 | 1/16/2013 | 923 | -0.33 | -0.05 | 0.0 | 0.0 | 3.5 | 12.2 | 1.3 | 5.0 | 0.0 | 5.0 | |
| VMP-34-10 | 2/25/2013 | 943 | -0.45 | -0.35 | 0.0 | 0.0 | 3.2 | 13.3 | 0.2 | 4.1 | 0.0 | 4.1 | |
| VMP-34-10 | 3/20/2013 | 933 | -1.42 | -0.28 | 0.0 | 0.0 | 0.8 | 19.0 | 0.3 | 1.9 | 0.0 | 1.9 | |

SEE LAST PAGE OF TABLE FOR NOTES

**TABLE 10**
**SVE SYSTEM MONTHLY MONITORING - VMP SAMPLING DATA**

| Sample ID | Date | Initial Reading Time (24-Hour) | Vacuum/Pressure | | Fixed Gases | | | | Soil Vapor Concentrations | | | | Comments |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | Initial Reading (Inches of $H_2O$) | Stabilized Reading (Inches of $H_2O$) | CH4 (%) | LEL (%) | $CO_2$ (%) | $O_2$ (%) | PID (ppmv) | THC (ppmv) | CH4 (ppmv) | PHC (ppmv) | |
| VMP-34-20 | 2/15/2012 | 1620 | -0.36 | -0.30 | OVR | OVR | 7.9 | 1.4 | 53.9 | 1000000 | 704000 | 296000 | |
| VMP-34-20 | 2/16/2012 | 1348 | -0.91 | -1.02 | OVR | OVR | 7.2 | 2.8 | 56.2 | 1000000 | 946000 | 54000 | |
| VMP-34-20 | 2/17/2012 | 1054 | -0.57 | -0.47 | OVR | OVR | 7.8 | 1.3 | 60.5 | 1000000 | 1000000 | 0.0 | |
| VMP-34-20 | 2/20/2012 | 1102 | -0.51 | -0.39 | OVR | OVR | 7.6 | 1.9 | 59.1 | 1000000 | 925000 | 75000 | |
| VMP-34-20 | 2/21/2012 | 1019 | -1.21 | -1.28 | OVR | OVR | 7.6 | 1.3 | 60.3 | 1000000 | 1000000 | 0.0 | |
| VMP-34-20 | 2/22/2012 | 909 | 0.13 | 0.22 | OVR | OVR | 8.1 | 0.9 | 49.2 | 1000000 | 820000 | 180000 | |
| VMP-34-20 | 2/29/2012 | 923 | -0.49 | -0.50 | OVR | OVR | 7.5 | 1.2 | 51.2 | 1000000 | 833000 | 167000 | |
| VMP-34-20 | 3/21/2012 | 915 | -0.68 | -0.59 | OVR | OVR | 7.0 | 0.7 | 46.5 | 1000000 | 1000000 | 0.0 | |
| VMP-34-20 | 4/18/2012 | 1032 | -0.36 | -0.34 | OVR | OVR | 6.0 | 1.2 | 47.5 | 1000000 | 1000000 | 0.0 | |
| VMP-34-20 | 5/16/2012 | 1045 | -0.88 | -0.88 | OVR | OVR | 6.4 | 1.3 | 52.1 | 1000000 | 1000000 | 0.0 | |
| VMP-34-20 | 6/20/2012 | 900 | -0.78 | -0.58 | OVR | OVR | 7.2 | 0.9 | 72.0 | 1000000 | 1000000 | 0.0 | |
| VMP-34-20 | 7/18/2012 | 934 | -0.65 | -0.64 | OVR | OVR | 8.2 | 1.4 | 42.2 | 1000000 | 420000 | 580000 | |
| VMP-34-20 | 8/15/2012 | 903 | -0.60 | -0.60 | OVR | OVR | 9.6 | 2.5 | 91.2 | 180000 | 152000 | 28000 | |
| VMP-34-20 | 9/19/2012 | 1208 | -0.61 | -0.57 | OVR | OVR | 10.1 | 2.0 | 94.6 | 179000 | 152000 | 27000 | |
| VMP-34-20 | 10/17/2012 | 908 | -0.70 | -0.65 | OVR | OVR | 7.1 | 1.9 | 65.2 | 1000000 | 650000 | 350000 | |
| VMP-34-20 | 11/20/2012 | 933 | -0.83 | -0.62 | OVR | OVR | 10.8 | 1.1 | 158 | 159000 | 135000 | 24000 | |
| VMP-34-20 | 12/19/2012 | 1043 | -0.79 | -0.53 | OVR | OVR | 11.3 | 0.8 | 142 | 105000 | 81200 | 23800 | |
| VMP-34-20 | 1/16/2013 | 928 | -0.42 | 0.00 | OVR | OVR | 10.7 | 0.7 | 121 | 395000 | 191000 | 204000 | |
| VMP-34-20 | 2/25/2013 | 947 | -0.49 | -0.37 | OVR | OVR | 9.9 | 1.4 | 107 | 617000 | 164000 | 453000 | |
| VMP-34-20 | 3/20/2013 | 937 | -1.71 | -0.35 | OVR | OVR | 9.7 | 1.3 | 93.8 | 260000 | 154000 | 106000 | |
| VMP-34-30 | 2/15/2012 | 1625 | -0.27 | -0.30 | OVR | OVR | 7.2 | 1.5 | 51.4 | 1000000 | 561000 | 439000 | |
| VMP-34-30 | 2/16/2012 | 1349 | -0.95 | -1.03 | OVR | OVR | 7.0 | 2.2 | 59.6 | 1000000 | 878000 | 122000 | |
| VMP-34-30 | 2/17/2012 | 1054 | -0.59 | -0.45 | OVR | OVR | 7.2 | 1.4 | 62.6 | 1000000 | 800000 | 200000 | |
| VMP-34-30 | 2/20/2012 | 1103 | -0.53 | -0.42 | OVR | OVR | 7.2 | 1.8 | 60.8 | 1000000 | 936000 | 64000 | |
| VMP-34-30 | 2/21/2012 | 1020 | -1.26 | -1.33 | OVR | OVR | 7.1 | 1.4 | 62.0 | 1000000 | 1000000 | 0.0 | |
| VMP-34-30 | 2/22/2012 | 910 | 0.15 | 0.23 | OVR | OVR | 7.3 | 1.0 | 50.7 | 1000000 | 669000 | 331000 | |
| VMP-34-30 | 2/29/2012 | 924 | -0.49 | -0.53 | OVR | OVR | 6.9 | 1.2 | 53.1 | 1000000 | 881000 | 119000 | |
| VMP-34-30 | 3/21/2012 | 916 | -0.68 | -0.64 | OVR | OVR | 6.5 | 0.6 | 51.6 | 1000000 | 1000000 | 0.0 | |
| VMP-34-30 | 4/18/2012 | 1032 | -0.38 | -0.35 | OVR | OVR | 5.7 | 0.9 | 52.0 | 1000000 | 1000000 | 0.0 | |
| VMP-34-30 | 5/16/2012 | 1046 | -0.93 | -0.96 | OVR | OVR | 5.4 | 1.5 | 56.1 | 1000000 | 1000000 | 0.0 | |
| VMP-34-30 | 6/20/2012 | 901 | -0.84 | -0.62 | OVR | OVR | 5.3 | 1.3 | 78.0 | 1000000 | 1000000 | 0.0 | |
| VMP-34-30 | 7/18/2012 | 935 | -0.70 | -0.70 | OVR | OVR | 5.2 | 1.5 | 37.3 | 1000000 | 1000000 | 0.0 | |
| VMP-34-30 | 8/15/2012 | 903 | -0.66 | -0.67 | OVR | OVR | 6.0 | 1.5 | 70.0 | 838000 | 664000 | 174000 | |
| VMP-34-30 | 9/19/2012 | 1210 | -0.65 | -0.62 | OVR | OVR | 6.7 | 1.5 | 82.6 | 1000000 | 536000 | 464000 | |
| VMP-34-30 | 10/17/2012 | 909 | -0.70 | -0.64 | OVR | OVR | 9.6 | 1.7 | 84.6 | 775000 | 371000 | 404000 | |
| VMP-34-30 | 11/20/2012 | 937 | -0.90 | -0.68 | OVR | OVR | 7.9 | 1.3 | 108 | 1000000 | 804000 | 196000 | |
| VMP-34-30 | 12/19/2012 | 1044 | -0.80 | -0.59 | OVR | OVR | 8.7 | 1.2 | 118 | 1000000 | 765000 | 235000 | |
| VMP-34-30 | 1/16/2013 | 933 | -0.44 | 0.03 | OVR | OVR | 9.0 | 0.9 | 88.6 | 1000000 | 610000 | 390000 | |
| VMP-34-30 | 2/25/2013 | 951 | -0.50 | -0.37 | OVR | OVR | 8.9 | 1.3 | 87.3 | 1000000 | 485000 | 515000 | |
| VMP-34-30 | 3/20/2013 | 941 | -1.81 | -0.38 | OVR | OVR | 8.9 | 1.2 | 70.1 | 1000000 | 855000 | 145000 | |

SEE LAST PAGE OF TABLE FOR NOTES

**TABLE 10**
**SVE SYSTEM MONTHLY MONITORING - VMP SAMPLING DATA**

| Sample ID | Date | Initial Reading Time (24-Hour) | Vacuum/Pressure | | Fixed Gases | | | | Soil Vapor Concentrations | | | | Comments |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | Initial Reading (Inches of $H_2O$) | Stabilized Reading (Inches of $H_2O$) | CH4 (%) | LEL (%) | $CO_2$ (%) | $O_2$ (%) | PID (ppmv) | THC (ppmv) | CH4 (ppmv) | PHC (ppmv) | |
| VMP-35-10 | 2/1/2012 | 1521 | -0.59 | -0.02 | 0.0 | 0.0 | 0.2 | 20.7 | 4.9 | 46.6 | 26.7 | 19.9 | |
| VMP-35-10 | 2/2/2012 | 1031 | -0.28 | -0.25 | 0.0 | 0.0 | 0.2 | 21.0 | 2.4 | 10.9 | 3.1 | 7.9 | |
| VMP-35-10 | 2/7/2012 | 840 | -0.27 | -0.24 | 0.0 | 0.0 | 0.2 | 20.9 | 3.5 | 2.0 | 0.0 | 2.0 | |
| VMP-35-10 | 2/10/2012 | 1036 | -0.15 | -0.05 | 0.0 | 0.0 | 0.1 | 20.8 | 2.0 | 15.0 | 5.5 | 9.5 | |
| VMP-35-10 | 2/13/2012 | 909 | -0.13 | 0.02 | 0.0 | 0.0 | 0.1 | 20.9 | 0.3 | 2.1 | 0.0 | 2.1 | |
| VMP-35-10 | 2/15/2012 | 1305 | -0.27 | -0.26 | 0.0 | 0.0 | 0.1 | 20.9 | 16.3 | 88.5 | 6.7 | 81.8 | |
| VMP-35-10 | 2/22/2012 | 1005 | -0.16 | -0.10 | 0.0 | 0.0 | 0.3 | 20.9 | 0.7 | 8.8 | 0.0 | 8.8 | |
| VMP-35-10 | 2/29/2012 | 944 | -0.31 | -0.31 | 0.1 | 3.0 | 0.3 | 20.9 | 53.4 | 347 | 32.7 | 314 | |
| VMP-35-10 | 3/21/2012 | 932 | -0.32 | -0.30 | 0.0 | 0.0 | 0.1 | 20.9 | 0.1 | 10.2 | 3.9 | 6.3 | |
| VMP-35-10 | 4/18/2012 | 854 | -0.35 | -0.42 | 0.0 | 0.0 | 0.0 | 20.9 | 0.5 | 5.4 | 0.0 | 5.4 | |
| VMP-35-10 | 5/16/2012 | 900 | -0.48 | -0.44 | 0.0 | 0.0 | 0.0 | 20.8 | 0.4 | 3.3 | 0.0 | 3.3 | |
| VMP-35-10 | 6/20/2012 | 925 | -0.37 | -0.33 | 0.0 | 0.0 | 0.0 | 20.9 | 0.4 | 6.3 | 0.0 | 6.3 | |
| VMP-35-10 | 7/18/2012 | 952 | -0.38 | -0.35 | 0.0 | 0.0 | 0.0 | 20.9 | 0.9 | 8.6 | 3.4 | 5.3 | |
| VMP-35-10 | 8/15/2012 | 952 | -0.37 | -0.38 | 0.0 | 0.0 | 0.0 | 20.9 | 0.7 | 5.2 | 4.7 | 0.5 | |
| VMP-35-10 | 9/19/2012 | 1143 | -0.47 | -0.45 | 0.0 | 0.0 | 0.0 | 20.9 | 0.8 | 3.3 | 0.0 | 3.3 | |
| VMP-35-10 | 10/17/2012 | 926 | -0.56 | -0.55 | 0.0 | 0.0 | 0.0 | 20.9 | 0.3 | 3.2 | 0.0 | 3.2 | |
| VMP-35-10 | 11/20/2012 | 955 | -0.52 | -0.40 | 0.0 | 0.0 | 0.0 | 20.9 | 0.5 | 4.8 | 0.0 | 4.8 | |
| VMP-35-10 | 12/19/2012 | 1051 | -0.34 | -0.22 | 0.0 | 0.0 | 0.0 | 20.9 | 0.6 | 3.3 | 0.0 | 3.3 | |
| VMP-35-10 | 1/16/2013 | 947 | -0.30 | -0.13 | 0.0 | 0.0 | 0.0 | 20.9 | 0.3 | 3.5 | 0.0 | 3.5 | |
| VMP-35-10 | 2/25/2013 | 1007 | -0.37 | -0.32 | 0.0 | 0.0 | 0.0 | 20.9 | 0.3 | 3.5 | 0.0 | 3.5 | |
| VMP-35-10 | 3/20/2013 | 948 | -0.97 | -0.19 | 0.0 | 0.0 | 0.0 | 20.8 | 0.8 | 3.9 | 0.0 | 3.9 | |
| VMP-35-20 | 2/1/2012 | 1522 | -0.36 | -0.09 | OVR | OVR | 7.7 | 2.2 | 140 | 230000 | 155000 | 75000 | |
| VMP-35-20 | 2/2/2012 | 1032 | -0.88 | -0.76 | OVR | OVR | 6.7 | 6.2 | 106 | 166000 | 125000 | 41000 | |
| VMP-35-20 | 2/7/2012 | 840 | -0.83 | -0.70 | OVR | OVR | 7.4 | 5.1 | 102 | 174000 | 155000 | 19000 | |
| VMP-35-20 | 2/10/2012 | 1037 | -0.59 | -0.02 | OVR | OVR | 6.9 | 5.0 | 117 | 189000 | 136000 | 53000 | |
| VMP-35-20 | 2/13/2012 | 910 | -0.57 | -0.05 | OVR | OVR | 6.8 | 4.8 | 107 | 255000 | 161000 | 94000 | |
| VMP-35-20 | 2/15/2012 | 1306 | -0.71 | -0.65 | OVR | OVR | 6.5 | 2.6 | 110 | 736000 | 266000 | 470000 | |
| VMP-35-20 | 2/22/2012 | 1006 | -0.42 | -0.29 | OVR | OVR | 8.1 | 1.7 | 144 | 800000 | 205000 | 595000 | |
| VMP-35-20 | 2/29/2012 | 945 | -0.80 | -0.80 | OVR | OVR | 7.4 | 4.8 | 136 | 233000 | 123000 | 110000 | |
| VMP-35-20 | 3/21/2012 | 932 | -0.85 | -0.80 | 33.4 | OVR | 4.2 | 10.3 | 51.1 | 137000 | 113000 | 24000 | |
| VMP-35-20 | 4/18/2012 | 854 | -0.98 | -1.07 | 20.5 | OVR | 3.5 | 11.2 | 100 | 31600 | 24900 | 6700 | |
| VMP-35-20 | 5/16/2012 | 921 | -1.32 | -1.26 | 20.7 | OVR | 2.0 | 15.6 | 180 | 17600 | 11200 | 6400 | |
| VMP-35-20 | 6/20/2012 | 926 | -1.08 | -0.95 | 2.5 | 50.0 | 1.0 | 18.2 | 86.0 | 2840 | 2600 | 240 | |
| VMP-35-20 | 7/18/2012 | 953 | -1.08 | -1.03 | 0.9 | 19.0 | 1.0 | 18.4 | 53.6 | 3534 | 2039 | 1495 | |
| VMP-35-20 | 8/15/2012 | 953 | -1.01 | -1.10 | 9.0 | OVR | 1.8 | 17.0 | 252 | 7030 | 2790 | 4240 | |
| VMP-35-20 | 9/19/2012 | 1145 | -1.38 | -1.33 | 6.7 | OVR | 1.6 | 17.7 | 307 | 5800 | 1500 | 4300 | |
| VMP-35-20 | 10/17/2012 | 927 | -1.39 | -1.35 | 20.7 | OVR | 4.0 | 14.1 | 383 | 6100 | 1600 | 4500 | |
| VMP-35-20 | 11/20/2012 | 959 | -1.34 | -1.08 | 1.9 | 38.0 | 2.6 | 16.4 | 214 | 1500 | 635 | 865 | |
| VMP-35-20 | 12/19/2012 | 1055 | -0.93 | -0.69 | 1.4 | 28.0 | 2.2 | 17.1 | 175 | 1320 | 510 | 810 | |
| VMP-35-20 | 1/16/2013 | 950 | -0.82 | -0.37 | 0.7 | 14.0 | 2.8 | 16.3 | 106 | 1820 | 1100 | 720 | |
| VMP-35-20 | 2/25/2013 | 1011 | -0.95 | -0.78 | 1.0 | 20.0 | 1.9 | 17.9 | 60.1 | 2470 | 1440 | 1030 | |
| VMP-35-20 | 3/20/2013 | 952 | -2.33 | -0.48 | 0.0 | 1.0 | 0.4 | 20.5 | 14.9 | 260 | 162 | 98.0 | |

SEE LAST PAGE OF TABLE FOR NOTES

**TABLE 10**
**SVE SYSTEM MONTHLY MONITORING - VMP SAMPLING DATA**

| Sample ID | Date | Initial Reading Time (24-Hour) | Vacuum/Pressure | | Fixed Gases | | | | Soil Vapor Concentrations | | | | Comments |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | Initial Reading (Inches of $H_2O$) | Stabilized Reading (Inches of $H_2O$) | CH4 (%) | LEL (%) | $CO_2$ (%) | $O_2$ (%) | PID (ppmv) | THC (ppmv) | CH4 (ppmv) | PHC (ppmv) | |
| VMP-35-30 | 2/1/2012 | 1523 | -0.33 | -0.08 | 0.0 | 0.0 | 0.2 | 20.9 | 4.1 | 40.0 | 20.6 | 19.4 | |
| VMP-35-30 | 2/2/2012 | 1033 | -1.01 | -0.88 | OVR | OVR | 3.7 | 2.5 | 38.8 | 1000000 | 1000000 | 0.0 | |
| VMP-35-30 | 2/7/2012 | 840 | -0.85 | -0.75 | OVR | OVR | 3.8 | 1.5 | 35.9 | 1000000 | 1000000 | 0.0 | |
| VMP-35-30 | 2/10/2012 | 1037 | -0.51 | 20.10 | OVR | OVR | 3.5 | 2.0 | 39.4 | 1000000 | 1000000 | 0.0 | |
| VMP-35-30 | 2/13/2012 | 911 | -0.46 | 0.11 | OVR | OVR | 3.4 | 2.0 | 34.3 | 1000000 | 1000000 | 0.0 | |
| VMP-35-30 | 2/15/2012 | 1307 | -0.57 | -0.53 | OVR | OVR | 3.6 | 1.6 | 41.7 | 1000000 | 1000000 | 0.0 | |
| VMP-35-30 | 2/22/2012 | 1007 | -0.28 | -0.20 | OVR | OVR | 3.6 | 2.1 | 44.0 | 1000000 | 1000000 | 0.0 | |
| VMP-35-30 | 2/29/2012 | 946 | -0.78 | -0.77 | OVR | OVR | 3.5 | 1.7 | 48.2 | 1000000 | 1000000 | 0.0 | |
| VMP-35-30 | 3/21/2012 | 932 | -0.95 | -0.92 | OVR | OVR | 3.3 | 0.9 | 50.5 | 1000000 | 1000000 | 0.0 | |
| VMP-35-30 | 4/18/2012 | 854 | -1.04 | -1.12 | OVR | OVR | 3.1 | 0.8 | 45.0 | 1000000 | 1000000 | 0.0 | |
| VMP-35-30 | 5/16/2012 | 922 | -1.50 | -1.46 | OVR | OVR | 3.1 | 1.0 | 50.0 | 1000000 | 1000000 | 0.0 | |
| VMP-35-30 | 6/20/2012 | 927 | -1.25 | -1.04 | OVR | OVR | 3.0 | 0.6 | 65.0 | 1000000 | 1000000 | 0.0 | |
| VMP-35-30 | 7/18/2012 | 954 | -1.28 | -1.20 | OVR | OVR | 2.8 | 1.6 | 34.5 | 1000000 | 1000000 | 0.0 | |
| VMP-35-30 | 8/15/2012 | 953 | -1.25 | -1.26 | OVR | OVR | 3.3 | 2.0 | 62.0 | 1000000 | 1000000 | 0.0 | |
| VMP-35-30 | 9/19/2012 | 1147 | -1.60 | -1.57 | OVR | OVR | 3.6 | 3.1 | 65.6 | 1000000 | 762000 | 238000 | |
| VMP-35-30 | 10/17/2012 | 928 | -1.57 | -1.49 | OVR | OVR | 4.5 | 1.2 | 52.2 | 1000000 | 1000000 | 0.0 | |
| VMP-35-30 | 11/20/2012 | 1003 | -1.57 | -1.27 | OVR | OVR | 4.5 | 2.8 | 95.0 | 1000000 | 419000 | 581000 | |
| VMP-35-30 | 12/19/2012 | 1059 | -1.17 | -0.84 | OVR | OVR | 5.4 | 1.3 | 96.2 | 1000000 | 1000000 | 0.0 | |
| VMP-35-30 | 1/16/2013 | 953 | -0.95 | -0.46 | OVR | OVR | 5.8 | 0.8 | 66.3 | 1000000 | 1000000 | 0.0 | |
| VMP-35-30 | 2/25/2013 | 1015 | -1.09 | -0.83 | OVR | OVR | 5.8 | 1.8 | 52.1 | 1000000 | 770000 | 230000 | |
| VMP-35-30 | 3/20/2013 | 956 | -2.67 | -0.56 | OVR | OVR | 6.0 | 1.6 | 46.7 | 1000000 | 1000000 | 0.0 | |
| VMP-36-10 | 2/1/2012 | 1649 | -0.34 | -0.29 | 0.0 | 0.0 | 0.3 | 20.6 | 4.7 | 18.0 | 0.0 | 18.0 | |
| VMP-36-10 | 2/2/2012 | 917 | -0.74 | -0.60 | 0.0 | 0.0 | 0.2 | 20.8 | 1.7 | 6.4 | 0.0 | 6.4 | |
| VMP-36-10 | 2/7/2012 | 1003 | -0.41 | -0.36 | 0.0 | 0.0 | 0.2 | 20.9 | 2.4 | 7.6 | 0.0 | 7.6 | |
| VMP-36-10 | 2/10/2012 | 1023 | -0.36 | -0.01 | 0.0 | 0.0 | 0.1 | 20.8 | 1.7 | 8.3 | 4.3 | 4.0 | |
| VMP-36-10 | 2/13/2012 | 1049 | 0.00 | -0.10 | 0.0 | 0.0 | 0.2 | 20.8 | 0.5 | 2.5 | 0.0 | 2.5 | |
| VMP-36-10 | 2/15/2012 | 1222 | -0.44 | -0.21 | 0.0 | 0.0 | 0.2 | 20.9 | 2.6 | 14.7 | 4.7 | 10.0 | |
| VMP-36-10 | 2/22/2012 | 804 | 0.00 | - 0.25 | 0.0 | 0.0 | 0.4 | 20.5 | 1.4 | 6.9 | 3.9 | 3.0 | |
| VMP-36-10 | 2/29/2012 | 1346 | -0.06 | 0.06 | 0.0 | 0.0 | 0.9 | 20.2 | 12.5 | 57.7 | 0.0 | 57.7 | |
| VMP-36-10 | 3/21/2012 | 1100 | -0.24 | - 0.23 | 0.0 | 0.0 | 0.3 | 20.7 | 2.9 | 33.9 | 0.0 | 33.9 | |
| VMP-36-10 | 4/18/2012 | 845 | -0.36 | -0.11 | 0.0 | 0.0 | 0.1 | 20.9 | 0.2 | 2.2 | 0.0 | 2.2 | |
| VMP-36-10 | 5/16/2012 | 955 | -0.65 | -0.64 | 0.0 | 0.0 | 0.2 | 20.7 | 0.6 | 1.0 | 0.0 | 1.0 | |
| VMP-36-10 | 6/20/2012 | 1036 | -0.17 | -0.35 | 0.0 | 0.0 | 0.1 | 20.6 | 1.0 | 0.8 | 0.0 | 0.8 | |
| VMP-36-10 | 7/18/2012 | 1115 | -0.20 | -0.14 | 0.0 | 0.0 | 0.1 | 20.8 | 1.0 | 5.4 | 0.0 | 5.4 | |
| VMP-36-10 | 8/15/2012 | 1045 | -0.24 | -0.21 | 0.0 | 0.0 | 0.2 | 20.7 | 1.0 | 7.2 | 5.6 | 1.6 | |
| VMP-36-10 | 9/19/2012 | 1004 | -0.42 | -0.44 | 0.0 | 0.0 | 0.1 | 20.8 | 0.6 | 3.3 | 0.0 | 3.3 | |
| VMP-36-10 | 10/17/2012 | 1021 | -0.50 | -0.47 | 0.0 | 0.0 | 0.1 | 20.8 | 0.6 | 4.2 | 0.0 | 4.2 | |
| VMP-36-10 | 11/20/2012 | 1042 | -0.40 | -0.38 | 0.0 | 0.0 | 0.1 | 20.8 | 0.5 | 2.8 | 0.0 | 2.8 | |
| VMP-36-10 | 12/19/2012 | 1005 | -0.48 | -0.44 | 0.0 | 0.0 | 0.1 | 20.8 | 0.7 | 3.2 | 0.0 | 3.2 | |
| VMP-36-10 | 1/16/2013 | 1110 | -0.16 | -0.07 | 0.0 | 0.0 | 0.1 | 20.8 | 0.2 | 2.0 | 0.0 | 2.0 | |
| VMP-36-10 | 2/25/2013 | 1430 | 0.18 | 0.15 | 0.0 | 0.0 | 0.2 | 19.8 | 0.4 | 1.8 | 0.0 | 1.8 | |
| VMP-36-10 | 3/20/2013 | 1140 | -0.18 | -0.17 | 0.0 | 0.0 | 0.0 | 20.9 | 0.8 | 2.9 | 0.0 | 2.9 | |

SEE LAST PAGE OF TABLE FOR NOTES

**TABLE 10**
**SVE SYSTEM MONTHLY MONITORING - VMP SAMPLING DATA**

| Sample ID | Date | Initial Reading Time (24-Hour) | Vacuum/Pressure | | Fixed Gases | | | | Soil Vapor Concentrations | | | | Comments |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | Initial Reading (Inches of $H_2O$) | Stabilized Reading (Inches of $H_2O$) | CH4 (%) | LEL (%) | $CO_2$ (%) | $O_2$ (%) | PID (ppmv) | THC (ppmv) | CH4 (ppmv) | PHC (ppmv) | |
| VMP-36-20 | 2/1/2012 | 1650 | -0.53 | -0.05 | OVR | OVR | 8.2 | 3.6 | 98.6 | 1000000 | 770000 | 230000 | |
| VMP-36-20 | 2/2/2012 | 918 | -0.92 | -0.57 | OVR | OVR | 8.7 | 1.5 | 80.0 | 1000000 | 480000 | 520000 | |
| VMP-36-20 | 2/7/2012 | 1004 | -0.68 | -0.63 | OVR | OVR | 8.7 | 1.3 | 81.7 | 919000 | 558000 | 361000 | |
| VMP-36-20 | 2/10/2012 | 1024 | -0.59 | -0.54 | OVR | OVR | 8.2 | 1.5 | 74.3 | 1000000 | 930000 | 70000 | |
| VMP-36-20 | 2/13/2012 | 1050 | -0.20 | 0.15 | OVR | OVR | 8.2 | 1.5 | 67.6 | 1000000 | 931000 | 69000 | |
| VMP-36-20 | 2/15/2012 | 1223 | -1.21 | 0.14 | OVR | OVR | 8.3 | 1.2 | 76.5 | 1000000 | 1000000 | 0.0 | |
| VMP-36-20 | 2/22/2012 | 805 | -0.60 | - 0.26 | OVR | OVR | 8.6 | 0.9 | 81.5 | 1000000 | 470000 | 530000 | |
| VMP-36-20 | 2/29/2012 | 1347 | -0.35 | 0.14 | OVR | OVR | 8.2 | 1.6 | 100 | 1000000 | 710000 | 290000 | |
| VMP-36-20 | 3/21/2012 | 1101 | 0.05 | 0.50 | OVR | OVR | 8.0 | 0.6 | 118 | 1000000 | 1000000 | 0.0 | |
| VMP-36-20 | 4/18/2012 | 845 | -0.60 | -0.19 | OVR | OVR | 7.4 | 1.2 | 142 | 752000 | 324000 | 428000 | |
| VMP-36-20 | 5/16/2012 | 955 | -1.05 | -1.06 | OVR | OVR | 7.1 | 2.8 | 180 | 735000 | 217000 | 518000 | |
| VMP-36-20 | 6/20/2012 | 1041 | -0.63 | -0.56 | OVR | OVR | 6.7 | 3.0 | 189 | 266000 | 105000 | 161000 | |
| VMP-36-20 | 7/18/2012 | 1119 | -0.37 | -0.25 | OVR | OVR | 5.9 | 6.5 | 95.0 | 416000 | 123000 | 293000 | |
| VMP-36-20 | 8/15/2012 | 1050 | -0.42 | -0.36 | OVR | OVR | 9.5 | 1.1 | 149 | 183000 | 106000 | 77000 | |
| VMP-36-20 | 9/19/2012 | 1004 | -0.78 | -0.77 | OVR | OVR | 8.3 | 3.4 | 245 | 264000 | 54200 | 209800 | |
| VMP-36-20 | 10/17/2012 | 1022 | -0.90 | -0.82 | OVR | OVR | 8.4 | 1.1 | 235 | 253000 | 37100 | 215900 | |
| VMP-36-20 | 11/20/2012 | 1046 | -0.72 | -0.68 | OVR | OVR | 8.5 | 1.0 | 349 | 262000 | 41400 | 220600 | |
| VMP-36-20 | 12/19/2012 | 1010 | -0.84 | -0.74 | OVR | OVR | 9.1 | 0.9 | 410 | 180000 | 41100 | 138900 | |
| VMP-36-20 | 1/16/2013 | 1115 | -0.27 | -0.18 | OVR | OVR | 8.9 | 1.5 | 318 | 153000 | 37200 | 115800 | |
| VMP-36-20 | 2/25/2013 | 1434 | 0.13 | 0.24 | OVR | OVR | 8.8 | 1.1 | 233 | 106000 | 29100 | 76900 | |
| VMP-36-20 | 3/20/2013 | 1144 | -0.34 | -0.32 | OVR | OVR | 5.9 | 6.7 | 387 | 91600 | 19700 | 71900 | |
| VMP-36-30 | 2/1/2012 | 1651 | -0.25 | -0.23 | OVR | OVR | 8.1 | 1.0 | 140 | 1000000 | 425000 | 575000 | |
| VMP-36-30 | 2/2/2012 | 920 | -1.08 | -0.87 | OVR | OVR | 8.0 | 1.5 | 130 | 1000000 | 472000 | 528000 | |
| VMP-36-30 | 2/7/2012 | 1005 | -0.57 | -0.49 | OVR | OVR | 8.2 | 1.2 | 131 | 1000000 | 521000 | 479000 | |
| VMP-36-30 | 2/10/2012 | 1025 | -0.98 | -0.35 | OVR | OVR | 7.6 | 2.0 | 122 | 1000000 | 1000000 | 0.0 | |
| VMP-36-30 | 2/13/2012 | 1051 | -0.36 | -0.17 | OVR | OVR | 6.6 | 3.0 | 104 | 1000000 | 263000 | 737000 | |
| VMP-36-30 | 2/15/2012 | 1224 | -1.61 | -0.89 | OVR | OVR | 6.2 | 1.6 | 95.0 | 1000000 | 986000 | 14000 | |
| VMP-36-30 | 2/22/2012 | 806 | -0.71 | - 0.73 | OVR | OVR | 5.0 | 1.4 | 70.3 | 1000000 | 1000000 | 0.0 | |
| VMP-36-30 | 2/29/2012 | 1348 | -0.19 | 0.13 | OVR | OVR | 5.0 | 1.6 | 63.9 | 1000000 | 785000 | 215000 | |
| VMP-36-30 | 3/21/2012 | 1102 | -0.67 | - 0.59 | OVR | OVR | 4.4 | 0.4 | 38.9 | 1000000 | 1000000 | 0.0 | |
| VMP-36-30 | 4/18/2012 | 845 | -1.20 | -0.32 | OVR | OVR | 4.3 | 1.1 | 69.0 | 1000000 | 1000000 | 0.0 | |
| VMP-36-30 | 5/16/2012 | 955 | -1.65 | -1.65 | OVR | OVR | 5.2 | 1.6 | 78.2 | 1000000 | 1000000 | 0.0 | |
| VMP-36-30 | 6/20/2012 | 1046 | -1.34 | -1.24 | OVR | OVR | 4.9 | 3.0 | 96.4 | 1000000 | 402000 | 598000 | |
| VMP-36-30 | 7/18/2012 | 1123 | -1.32 | -1.19 | OVR | OVR | 5.7 | 1.7 | 48.4 | 1000000 | 675000 | 325000 | |
| VMP-36-30 | 8/15/2012 | 1055 | -1.45 | -1.38 | OVR | OVR | 7.1 | 1.0 | 103 | 1000000 | 373000 | 627000 | |
| VMP-36-30 | 9/19/2012 | 1005 | -2.22 | -2.17 | OVR | OVR | 7.8 | 1.9 | 144 | 1000000 | 402000 | 598000 | |
| VMP-36-30 | 10/17/2012 | 1023 | -2.00 | -1.90 | NM | NM | NM | NM | NM | NM | NM | NM | Pullback during purge. Could not sample. |
| VMP-36-30 | 11/20/2012 | 1050 | -1.69 | -1.63 | OVR | OVR | 8.2 | 0.8 | 201 | 648000 | 311000 | 337000 | |
| VMP-36-30 | 12/19/2012 | 1015 | -1.63 | -1.57 | OVR | OVR | 8.5 | 0.6 | 185 | 1000000 | 333000 | 667000 | |
| VMP-36-30 | 1/16/2013 | 1120 | -0.88 | -0.77 | OVR | OVR | 8.3 | 1.2 | 142 | 740000 | 275000 | 465000 | |
| VMP-36-30 | 2/25/2013 | 1338 | -0.24 | -0.28 | OVR | OVR | 8.9 | 1.3 | 136 | 719000 | 199000 | 520000 | |
| VMP-36-30 | 3/20/2013 | 1148 | -0.63 | -0.61 | OVR | OVR | 8.7 | 1.2 | 139 | 890000 | 240000 | 650000 | |

SEE LAST PAGE OF TABLE FOR NOTES

**TABLE 10**
**SVE SYSTEM MONTHLY MONITORING - VMP SAMPLING DATA**

| Sample ID | Date | Initial Reading Time (24-Hour) | Vacuum/Pressure | | Fixed Gases | | | | Soil Vapor Concentrations | | | | Comments |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | Initial Reading (Inches of $H_2O$) | Stabilized Reading (Inches of $H_2O$) | CH4 (%) | LEL (%) | $CO_2$ (%) | $O_2$ (%) | PID (ppmv) | THC (ppmv) | CH4 (ppmv) | PHC (ppmv) | |
| VMP-37-10 | 2/2/2012 | 1348 | 0.00 | -0.24 | OVR | OVR | 4.8 | 12.4 | 270 | 100000 | 38700 | 61300 | |
| VMP-37-10 | 2/3/2012 | 857 | -0.26 | -0.24 | OVR | OVR | 2.0 | 17.5 | 428 | 44400 | 20970 | 23430 | |
| VMP-37-10 | 2/7/2012 | 947 | -0.31 | 0.04 | 38.1 | OVR | 1.5 | 18.2 | 369 | 21390 | 14950 | 6440 | |
| VMP-37-10 | 2/13/2012 | 1352 | 0.12 | 0.10 | OVR | OVR | 3.6 | 10.0 | 285 | 84640 | 48610 | 36030 | |
| VMP-37-10 | 2/14/2012 | 1531 | -0.70 | -0.57 | 11.5 | OVR | 0.8 | 20.8 | 458 | 11300 | 4860 | 6440 | |
| VMP-37-10 | 2/15/2012 | 1042 | -0.65 | -0.40 | 7.1 | OVR | 0.5 | 20.3 | 466 | 7800 | 2290 | 5510 | |
| VMP-37-10 | 2/22/2012 | 824 | 0.00 | - 0.08 | 0.0 | 0.0 | 0.2 | 20.8 | 27.8 | 119 | 8.1 | 111 | |
| VMP-37-10 | 2/29/2012 | 1330 | NM | NM | NM | NM | NM | NM | NM | NM | NM | NM | Stainless Steel Broken and Venting. Could not sample. |
| VMP-37-10 | 3/21/2012 | 1035 | -0.25 | - 0.14 | 11.9 | OVR | 0.9 | 18.5 | 404 | 16200 | 9000 | 7200 | |
| VMP-37-10 | 4/18/2012 | 917 | -0.46 | -0.42 | 4.8 | 97.0 | 0.4 | 20.1 | 375 | 6225 | 2050 | 4175 | |
| VMP-37-10 | 5/16/2012 | 936 | -0.55 | -0.53 | 1.4 | 28.0 | 0.3 | 20.3 | 275 | 2600 | 790 | 1810 | |
| VMP-37-10 | 6/20/2012 | 1019 | -0.34 | -0.40 | 2.3 | 48.0 | 0.3 | 20.3 | 307 | 3261 | 752 | 2509 | |
| VMP-37-10 | 7/18/2012 | 1053 | -0.31 | -0.23 | 1.6 | 32.0 | 0.4 | 19.9 | 298 | 3500 | 1035 | 2465 | |
| VMP-37-10 | 8/15/2012 | 1022 | -0.32 | -0.30 | 1.1 | 23.0 | 0.3 | 20.6 | 238 | 1440 | 276 | 1164 | |
| VMP-37-10 | 9/19/2012 | 955 | -0.56 | -0.42 | 0.6 | 12.0 | 0.1 | 20.8 | 153 | 594 | 37.7 | 556 | |
| VMP-37-10 | 10/17/2012 | 1002 | -0.38 | -0.51 | 0.2 | 5.0 | 0.2 | 20.6 | 101 | 418 | 49.9 | 368 | |
| VMP-37-10 | 11/20/2012 | 1020 | -0.46 | -0.35 | 0.2 | 4.0 | 0.2 | 20.7 | 138 | 411 | 47.3 | 364 | |
| VMP-37-10 | 12/19/2012 | 950 | -0.42 | -0.45 | 0.2 | 4.0 | 0.2 | 20.5 | 105 | 458 | 67.8 | 390 | |
| VMP-37-10 | 1/16/2013 | 1050 | -0.24 | -0.11 | 0.2 | 5.0 | 0.2 | 20.6 | 160 | 710 | 129 | 581 | |
| VMP-37-10 | 2/25/2013 | 1410 | -0.08 | 0.29 | 1.9 | 39.0 | 0.5 | 19.0 | 345 | 2300 | 580 | 1720 | |
| VMP-37-10 | 3/20/2013 | 1207 | -0.80 | -0.52 | 0.0 | 0.0 | 0.0 | 20.9 | 3.9 | 11.5 | 0.0 | 11.5 | |
| VMP-37-20 | 2/2/2012 | 1349 | -0.26 | -0.27 | OVR | OVR | 10.7 | 2.0 | 152 | 790000 | 300000 | 490000 | |
| VMP-37-20 | 2/3/2012 | 857 | -0.43 | -0.39 | OVR | OVR | 10.6 | 1.5 | 147 | 834000 | 226000 | 608000 | |
| VMP-37-20 | 2/7/2012 | 948 | -0.49 | -0.37 | OVR | OVR | 9.9 | 3.0 | 152 | 539000 | 156000 | 383000 | |
| VMP-37-20 | 2/13/2012 | 1353 | -0.06 | 0.69 | OVR | OVR | 10.2 | 2.0 | 157 | 651000 | 232000 | 419000 | |
| VMP-37-20 | 2/14/2012 | 1532 | -1.24 | -1.10 | OVR | OVR | 7.4 | 6.5 | 193 | 367000 | 164000 | 203000 | |
| VMP-37-20 | 2/15/2012 | 1043 | -1.18 | -0.78 | OVR | OVR | 7.8 | 6.0 | 193 | 294000 | 111000 | 183000 | |
| VMP-37-20 | 2/22/2012 | 825 | -0.46 | - 0.34 | OVR | OVR | 8.2 | 3.7 | 219 | 238000 | 156000 | 82000 | |
| VMP-37-20 | 2/29/2012 | 1332 | -0.20 | -0.22 | OVR | OVR | 8.9 | 2.2 | 235 | 451000 | 126000 | 325000 | |
| VMP-37-20 | 3/21/2012 | 1034 | -0.51 | - 0.36 | OVR | OVR | 2.7 | 14.6 | 305 | 65700 | 28000 | 37700 | |
| VMP-37-20 | 4/18/2012 | 918 | -0.04 | -0.82 | OVR | OVR | 5.4 | 4.9 | 391 | 135000 | 46000 | 89000 | |
| VMP-37-20 | 5/16/2012 | 936 | -0.70 | -1.03 | OVR | OVR | 6.2 | 6.2 | 465 | 100000 | 29800 | 70200 | |
| VMP-37-20 | 6/20/2012 | 1028 | -0.79 | -0.81 | OVR | OVR | 6.8 | 5.7 | 513 | 68100 | 20000 | 48100 | |
| VMP-37-20 | 7/18/2012 | 1057 | -0.85 | -0.72 | OVR | OVR | 7.4 | 6.8 | 204 | 101000 | 18600 | 82400 | |
| VMP-37-20 | 8/15/2012 | 1027 | -0.89 | -0.84 | OVR | OVR | 8.6 | 7.0 | 252 | 57600 | 11500 | 46100 | |
| VMP-37-20 | 9/19/2012 | 955 | -1.46 | -1.27 | OVR | OVR | 7.1 | 9.0 | 438 | 64800 | 11400 | 53400 | |
| VMP-37-20 | 10/17/2012 | 1003 | -1.13 | -1.22 | OVR | OVR | 5.7 | 10.2 | 379 | 48900 | 10100 | 38800 | |
| VMP-37-20 | 11/20/2012 | 1022 | -1.17 | -0.95 | OVR | OVR | 5.8 | 8.3 | 442 | 71300 | 9700 | 61600 | |
| VMP-37-20 | 12/19/2012 | 954 | -0.96 | -0.97 | OVR | OVR | 6.8 | 5.7 | 775 | 50900 | 10800 | 40100 | |
| VMP-37-20 | 1/16/2013 | 1055 | -0.62 | -0.44 | OVR | OVR | 6.9 | 5.7 | 625 | 47400 | 7500 | 39900 | |
| VMP-37-20 | 2/25/2013 | 1414 | 0.14 | -0.04 | OVR | OVR | 8.3 | 2.5 | 666 | 40700 | 11400 | 29300 | |
| VMP-37-20 | 3/20/2013 | 1213 | -1.52 | -1.32 | OVR | OVR | 4.9 | 10.5 | 690 | 17500 | 2100 | 15400 | |

SEE LAST PAGE OF TABLE FOR NOTES

**TABLE 10**
**SVE SYSTEM MONTHLY MONITORING - VMP SAMPLING DATA**

| Sample ID | Date | Initial Reading Time (24-Hour) | Vacuum/Pressure | | Fixed Gases | | | | Soil Vapor Concentrations | | | | Comments |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | Initial Reading (Inches of $H_2O$) | Stabilized Reading (Inches of $H_2O$) | CH4 (%) | LEL (%) | $CO_2$ (%) | $O_2$ (%) | PID (ppmv) | THC (ppmv) | CH4 (ppmv) | PHC (ppmv) | |
| VMP-37-30 | 2/2/2012 | 1349 | -0.06 | -0.31 | OVR | OVR | 10.0 | 1.3 | 165 | 920000 | 212000 | 708000 | |
| VMP-37-30 | 2/3/2012 | 857 | -0.46 | -0.46 | OVR | OVR | 10.3 | 1.0 | 151 | 970000 | 200000 | 770000 | |
| VMP-37-30 | 2/7/2012 | 949 | -0.75 | -0.42 | OVR | OVR | 10.1 | 2.0 | 136 | 944000 | 266000 | 678000 | |
| VMP-37-30 | 2/13/2012 | 1354 | -0.45 | -0.36 | OVR | OVR | 10.3 | 1.0 | 129 | 1000000 | 233000 | 767000 | |
| VMP-37-30 | 2/14/2012 | 1533 | -2.15 | -1.38 | OVR | OVR | 9.7 | 2.0 | 129 | 1000000 | 239000 | 761000 | |
| VMP-37-30 | 2/15/2012 | 1044 | -1.45 | -1.06 | OVR | OVR | 9.9 | 2.0 | 126 | 1000000 | 347000 | 653000 | |
| VMP-37-30 | 2/22/2012 | 826 | -0.88 | - 0.53 | OVR | OVR | 9.8 | 1.2 | 114 | 1000000 | 338000 | 662000 | |
| VMP-37-30 | 2/29/2012 | 1334 | -0.04 | -0.08 | OVR | OVR | 9.4 | 1.1 | 123 | 1000000 | 462000 | 538000 | |
| VMP-37-30 | 3/21/2012 | 1037 | -0.16 | - 0.49 | OVR | OVR | 9.3 | 1.0 | 142 | 1000000 | 1000000 | 0.0 | |
| VMP-37-30 | 4/18/2012 | 919 | -0.38 | -0.27 | OVR | OVR | 8.8 | 1.5 | 217 | 205000 | 130000 | 75000 | |
| VMP-37-30 | 5/16/2012 | 937 | -1.39 | -1.34 | OVR | OVR | 9.0 | 1.3 | 240 | 141000 | 84000 | 57000 | |
| VMP-37-30 | 6/20/2012 | 1028 | -1.08 | -1.10 | OVR | OVR | 8.6 | 1.5 | 233 | 71000 | 36500 | 34500 | |
| VMP-37-30 | 7/18/2012 | 1101 | -1.16 | -1.03 | OVR | OVR | 10.1 | 1.2 | 212 | 55000 | 37500 | 17500 | |
| VMP-37-30 | 8/15/2012 | 1032 | -1.22 | -1.18 | 57.3 | OVR | 12.1 | 0.8 | 330 | 18600 | 11300 | 7300 | |
| VMP-37-30 | 9/19/2012 | 955 | -2.02 | -1.82 | 37.0 | OVR | 11.8 | 1.4 | 446 | 18400 | 10100 | 8300 | |
| VMP-37-30 | 10/17/2012 | 1004 | -1.62 | -1.75 | 30.6 | OVR | 11.9 | 1.2 | 392 | 12400 | 9400 | 3000 | |
| VMP-37-30 | 11/20/2012 | 1024 | -1.60 | -1.33 | 22.7 | OVR | 11.7 | 1.5 | 458 | 9100 | 5800 | 3300 | |
| VMP-37-30 | 12/19/2012 | 958 | -1.28 | -1.31 | 18.7 | OVR | 12.5 | 0.9 | 330 | 19800 | 13800 | 6000 | |
| VMP-37-30 | 1/16/2013 | 1100 | -0.88 | -0.66 | 8.7 | OVR | 11.3 | 3.1 | 252 | 12000 | 8500 | 3500 | |
| VMP-37-30 | 2/25/2013 | 1418 | -0.01 | -0.19 | 3.1 | 62.0 | 12.2 | 2.2 | 205 | 6200 | 3900 | 2300 | |
| VMP-37-30 | 3/20/2013 | 1220 | -2.04 | -1.88 | 2.0 | 41.0 | 10.5 | 4.9 | 145 | 3200 | 2200 | 1000 | |
| VMP-38-10 | 2/2/2012 | 1409 | -0.25 | -0.25 | 6.1 | OVR | 1.8 | 18.4 | 264 | 4020 | 794 | 3226 | |
| VMP-38-10 | 2/3/2012 | 923 | -0.05 | -0.10 | 45.1 | OVR | 8.2 | 1.2 | 436 | 21100 | 11200 | 9900 | |
| VMP-38-10 | 2/7/2012 | 931 | -0.32 | -0.25 | 15.2 | OVR | 5.5 | 1.8 | 632 | 7120 | 1500 | 5620 | |
| VMP-38-10 | 2/15/2012 | 1014 | -0.44 | -0.34 | 5.9 | OVR | 8.0 | 4.2 | 400 | 3440 | 1100 | 2340 | |
| VMP-38-10 | 2/22/2012 | 851 | 0.15 | -0.30 | 3.4 | 69.0 | 7.1 | 6.7 | 340 | 2260 | 125 | 2135 | |
| VMP-38-10 | 2/29/2012 | 918 | -0.18 | - 0.22 | 4.7 | 93.0 | 8.8 | 2.8 | 435 | 2790 | 188 | 2602 | |
| VMP-38-10 | 3/21/2012 | 1008 | -0.10 | - 0.11 | 0.2 | 4.0 | 12.1 | 1.2 | 82.5 | 625 | 307 | 318 | |
| VMP-38-10 | 4/18/2012 | 944 | -0.11 | -0.26 | 0.0 | 0.0 | 8.5 | 10.0 | 26.8 | 80.0 | 25.3 | 54.7 | |
| VMP-38-10 | 5/16/2012 | 919 | -0.39 | -0.37 | 0.0 | 0.0 | 8.9 | 8.9 | 7.3 | 50.0 | 24.7 | 25.3 | |
| VMP-38-10 | 6/20/2012 | 1004 | -0.20 | -0.28 | 0.0 | 0.0 | 11.7 | 4.9 | 30.7 | 121 | 45.5 | 75.5 | |
| VMP-38-10 | 7/18/2012 | 1034 | -0.24 | -0.19 | 0.0 | 0.0 | 14.2 | 2.9 | 9.1 | 32.6 | 14.6 | 18.0 | |
| VMP-38-10 | 8/15/2012 | 1000 | -0.26 | -0.24 | 0.0 | 0.0 | 13.5 | 4.0 | 0.9 | 25.3 | 10.0 | 15.3 | |
| VMP-38-10 | 9/19/2012 | 940 | -0.39 | -0.27 | 0.0 | 0.0 | 9.1 | 10.0 | 0.6 | 2.7 | 0.0 | 2.7 | |
| VMP-38-10 | 10/17/2012 | 1040 | -0.30 | -0.35 | 0.0 | 0.0 | 8.9 | 7.8 | 0.7 | 2.3 | 0.0 | 2.3 | |
| VMP-38-10 | 11/20/2012 | 1045 | -0.29 | -0.22 | 0.0 | 0.0 | 6.3 | 11.5 | 0.2 | 1.7 | 0.0 | 1.7 | |
| VMP-38-10 | 12/19/2012 | 934 | -0.31 | -0.26 | 0.0 | 0.0 | 5.7 | 13.2 | 0.6 | 2.3 | 0.0 | 2.3 | |
| VMP-38-10 | 1/16/2013 | 1025 | -0.26 | -0.31 | 0.0 | 0.0 | 3.4 | 15.4 | 0.3 | 1.3 | 0.0 | 1.3 | |
| VMP-38-10 | 2/25/2013 | 1350 | -0.16 | -0.05 | 0.0 | 0.0 | 2.9 | 16.3 | 0.5 | 0.4 | 0.0 | 0.4 | |
| VMP-38-10 | 3/20/2013 | 1139 | -0.82 | -0.40 | 0.0 | 0.0 | 1.3 | 19.9 | 0.7 | 1.6 | 0.0 | 1.6 | |

SEE LAST PAGE OF TABLE FOR NOTES

**TABLE 10**
**SVE SYSTEM MONTHLY MONITORING - VMP SAMPLING DATA**

| Sample ID | Date | Initial Reading Time (24-Hour) | Vacuum/Pressure | | Fixed Gases | | | | Soil Vapor Concentrations | | | | Comments |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | Initial Reading (Inches of $H_2O$) | Stabilized Reading (Inches of $H_2O$) | CH4 (%) | LEL (%) | $CO_2$ (%) | $O_2$ (%) | PID (ppmv) | THC (ppmv) | CH4 (ppmv) | PHC (ppmv) | |
| VMP-38-20 | 2/2/2012 | 1409 | -0.38 | -0.14 | OVR | OVR | 13.5 | 1.2 | 254 | 107000 | 85500 | 21500 | |
| VMP-38-20 | 2/3/2012 | 923 | -0.01 | -0.16 | OVR | OVR | 13.6 | 1.3 | 266 | 160000 | 76400 | 83600 | |
| VMP-38-20 | 2/7/2012 | 932 | -0.50 | -0.37 | OVR | OVR | 12.7 | 2.8 | 298 | 87000 | 51200 | 35800 | |
| VMP-38-20 | 2/15/2012 | 1015 | -0.70 | -0.55 | OVR | OVR | 12.2 | 1.5 | 409 | 65900 | 27200 | 38700 | |
| VMP-38-20 | 2/22/2012 | 852 | -0.15 | - 0.11 | OVR | OVR | 10.6 | 2.3 | 500 | 58400 | 13700 | 44700 | |
| VMP-38-20 | 2/29/2012 | 922 | -0.33 | - 0.34 | OVR | OVR | 8.6 | 5.4 | 555 | 52800 | 7870 | 44930 | |
| VMP-38-20 | 3/21/2012 | 1009 | -0.29 | - 0.24 | OVR | OVR | 10.5 | 0.6 | 493 | 132000 | 24200 | 107800 | |
| VMP-38-20 | 4/18/2012 | 945 | -0.55 | -0.41 | OVR | OVR | 11.9 | 1.2 | 616 | 53000 | 7300 | 45700 | |
| VMP-38-20 | 5/16/2012 | 915 | -0.66 | -0.65 | OVR | OVR | 13.8 | 0.8 | 645 | 46400 | 5000 | 41400 | |
| VMP-38-20 | 6/20/2012 | 1008 | -0.38 | -0.49 | OVR | OVR | 13.7 | 0.8 | 737 | 36000 | 6000 | 30000 | |
| VMP-38-20 | 7/18/2012 | 1038 | -0.45 | -0.35 | OVR | OVR | 12.8 | 1.0 | 401 | 52400 | 3400 | 49000 | |
| VMP-38-20 | 8/15/2012 | 1010 | -0.46 | -0.41 | OVR | OVR | 14.4 | 1.9 | 450 | 19200 | 4100 | 15100 | |
| VMP-38-20 | 9/19/2012 | 940 | -0.72 | -0.58 | OVR | OVR | 16.5 | 1.8 | 753 | 30100 | 4000 | 26100 | |
| VMP-38-20 | 10/17/2012 | 1041 | -0.62 | -0.60 | OVR | OVR | 15.9 | 0.8 | 646 | 24300 | 3450 | 20850 | |
| VMP-38-20 | 11/20/2012 | 1047 | -0.55 | -0.44 | OVR | OVR | 15.9 | 1.2 | 772 | 15500 | 5400 | 10100 | |
| VMP-38-20 | 12/19/2012 | 938 | -0.56 | -0.47 | 60.9 | OVR | 16.3 | 0.9 | 1030 | 11600 | 1850 | 9750 | |
| VMP-38-20 | 1/16/2013 | 1030 | -0.43 | -0.15 | 54.3 | OVR | 15.7 | 1.1 | 870 | 11200 | 2400 | 8800 | |
| VMP-38-20 | 2/25/2013 | 1354 | 0.02 | -0.08 | 46.7 | OVR | 15.7 | 1.1 | 920 | 8300 | 5400 | 2900 | |
| VMP-38-20 | 3/20/2013 | 1148 | -0.97 | -0.75 | 5.6 | OVR | 15.4 | 1.6 | 466 | 2000 | 650 | 1350 | |
| VMP-38-30 | 2/2/2012 | 1409 | -0.10 | -0.59 | OVR | OVR | 13.2 | 1.5 | 184 | 415000 | 180000 | 235000 | |
| VMP-38-30 | 2/3/2012 | 923 | -0.11 | -0.31 | OVR | OVR | 13.3 | 1.5 | 173 | 309000 | 150000 | 159000 | |
| VMP-38-30 | 2/7/2012 | 933 | -0.47 | -0.12 | OVR | OVR | 13.2 | 1.0 | 186 | 204000 | 113000 | 91000 | |
| VMP-38-30 | 2/15/2012 | 1016 | -0.70 | -0.56 | OVR | OVR | 13.8 | 1.5 | 218 | 200000 | 121000 | 79000 | |
| VMP-38-30 | 2/22/2012 | 853 | 0.19 | 0.42 | OVR | OVR | 13.5 | 1.2 | 277 | 120000 | 70700 | 49300 | |
| VMP-38-30 | 2/29/2012 | 923 | -0.31 | - 0.33 | OVR | OVR | 13.2 | 1.3 | 374 | 169000 | 68720 | 100280 | |
| VMP-38-30 | 3/21/2012 | 1010 | -0.29 | 0.28 | OVR | OVR | 12.5 | 0.8 | 331 | 210000 | 83300 | 126700 | |
| VMP-38-30 | 4/18/2012 | 945 | -0.05 | -0.33 | OVR | OVR | 10.5 | 1.0 | 461 | 83500 | 34400 | 49100 | |
| VMP-38-30 | 5/16/2012 | 915 | -0.68 | -0.66 | 0.1 | 2.0 | 8.7 | 9.7 | 7.0 | 54.3 | 30.2 | 24.1 | Well damaged during sampling event. |
| VMP-38-30 | 6/20/2012 | 1012 | 0.00 | -0.74 | OVR | OVR | 11.0 | 0.1 | 763 | 34300 | 11200 | 23100 | Well repaired before sampling. |
| VMP-38-30 | 7/18/2012 | 1042 | -0.08 | -0.21 | OVR | OVR | 11.4 | 1.1 | 515 | 26000 | 9600 | 16400 | |
| VMP-38-30 | 8/15/2012 | 1005 | -0.42 | -0.36 | 86.3 | OVR | 12.7 | 0.9 | 522 | 14500 | 7300 | 7200 | |
| VMP-38-30 | 9/19/2012 | 940 | -0.64 | -0.49 | 51.8 | OVR | 13.0 | 1.7 | 746 | 19000 | 8800 | 10200 | |
| VMP-38-30 | 10/17/2012 | 1043 | -0.60 | -0.45 | 48.7 | OVR | 13.7 | 1.0 | 683 | 11300 | 6200 | 5100 | |
| VMP-38-30 | 11/20/2012 | 1049 | -0.44 | -0.37 | 38.2 | OVR | 12.8 | 1.1 | 717 | 8400 | 4700 | 3700 | |
| VMP-38-30 | 12/19/2012 | 942 | -0.51 | -0.46 | 17.1 | OVR | 15.4 | 1.2 | 630 | 12800 | 7500 | 5300 | |
| VMP-38-30 | 1/16/2013 | 1035 | -0.37 | 0.07 | 11.8 | OVR | 11.9 | 6.4 | 534 | 8660 | 4900 | 3760 | |
| VMP-38-30 | 2/25/2013 | 1358 | 0.16 | -0.51 | 16.9 | OVR | 15.9 | 1.4 | 450 | 11600 | 6100 | 5500 | |
| VMP-38-30 | 3/20/2013 | 1158 | -1.23 | -0.91 | 23.1 | OVR | 13.0 | 4.4 | 810 | 4200 | 680 | 3520 | |

SEE LAST PAGE OF TABLE FOR NOTES

**TABLE 10**
**SVE SYSTEM MONTHLY MONITORING - VMP SAMPLING DATA**

| Sample ID | Date | Initial Reading Time (24-Hour) | Vacuum/Pressure | | Fixed Gases | | | | Soil Vapor Concentrations | | | | Comments |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | Initial Reading (Inches of $H_2O$) | Stabilized Reading (Inches of $H_2O$) | CH4 (%) | LEL (%) | $CO_2$ (%) | $O_2$ (%) | PID (ppmv) | THC (ppmv) | CH4 (ppmv) | PHC (ppmv) | |
| VMP-39-10 | 2/6/2012 | 1104 | -0.30 | -0.26 | 54.5 | OVR | 11.5 | 7.2 | 442 | 20200 | 8000 | 12200 | |
| VMP-39-10 | 2/7/2012 | 910 | -0.42 | -0.32 | 19.6 | OVR | 3.2 | 17.8 | 557 | 9460 | 184 | 9276 | |
| VMP-39-10 | 2/8/2012 | 909 | -0.44 | -0.43 | 9.5 | OVR | 2.1 | 18.8 | 557 | 6530 | 64.5 | 6466 | |
| VMP-39-10 | 2/15/2012 | 942 | -0.29 | -0.30 | 2.9 | 59.0 | 2.2 | 18.4 | 432 | 3000 | 21.0 | 2979 | |
| VMP-39-10 | 2/22/2012 | 913 | -0.09 | - 0.11 | 0.7 | 14.0 | 2.4 | 17.4 | 203 | 948 | 34.9 | 913 | |
| VMP-39-10 | 2/29/2012 | 957 | -0.24 | - 0.21 | 0.4 | 8.0 | 4.9 | 14.3 | 161 | 910 | 322 | 588 | |
| VMP-39-10 | 3/21/2012 | 948 | -0.06 | - 0.13 | 0.9 | 18.0 | 11.9 | 2.8 | 152 | 2250 | 1050 | 1200 | |
| VMP-39-10 | 4/18/2012 | 1012 | -0.32 | -0.27 | 0.0 | 0.0 | 5.0 | 15.6 | 37.4 | 185 | 23.5 | 162 | |
| VMP-39-10 | 5/16/2012 | 857 | -0.36 | -0.41 | 0.0 | 0.0 | 4.8 | 15.3 | 19.4 | 89.4 | 22.8 | 66.6 | |
| VMP-39-10 | 6/20/2012 | 942 | -0.25 | -0.30 | 0.0 | 0.0 | 2.7 | 17.0 | 11.0 | 58.0 | 24.8 | 33.2 | |
| VMP-39-10 | 7/18/2012 | 1017 | -0.20 | -0.19 | 0.0 | 0.0 | 0.9 | 19.5 | 5.0 | 25.5 | 10.8 | 14.7 | |
| VMP-39-10 | 8/15/2012 | 930 | -0.21 | -0.23 | 0.0 | 0.0 | 1.1 | 19.5 | 2.7 | 22.5 | 15.4 | 7.1 | |
| VMP-39-10 | 9/19/2012 | 907 | -0.44 | -0.40 | 0.0 | 0.0 | 0.5 | 20.3 | 0.8 | 5.9 | 5.7 | 0.2 | |
| VMP-39-10 | 10/17/2012 | 945 | -0.30 | -0.29 | 0.0 | 0.0 | 0.4 | 20.3 | 1.0 | 5.4 | 4.4 | 1.0 | |
| VMP-39-10 | 11/20/2012 | 1104 | -0.29 | -0.25 | 0.0 | 0.0 | 0.5 | 20.3 | 1.7 | 8.0 | 3.7 | 4.3 | |
| VMP-39-10 | 12/19/2012 | 916 | -0.68 | -0.23 | 0.0 | 0.0 | 0.5 | 20.0 | 0.2 | 3.7 | 0.0 | 3.7 | |
| VMP-39-10 | 1/16/2013 | 1005 | -0.17 | -0.05 | 0.0 | 0.0 | 0.4 | 20.3 | 0.4 | 4.6 | 0.0 | 4.6 | |
| VMP-39-10 | 2/25/2013 | 1335 | -0.21 | 0.01 | 0.0 | 0.0 | 0.5 | 19.4 | 0.4 | 7.0 | 4.4 | 2.6 | |
| VMP-39-10 | 3/20/2013 | 1117 | -0.71 | -0.38 | 0.0 | 0.0 | 0.0 | 20.9 | 0.5 | 4.3 | 0.0 | 4.3 | |
| VMP-39-20 | 2/6/2012 | 1105 | -0.28 | -0.36 | OVR | OVR | 14.3 | 1.2 | 186 | 189000 | 189000 | 0.0 | |
| VMP-39-20 | 2/7/2012 | 911 | -0.62 | -0.46 | OVR | OVR | 12.9 | 3.8 | 179 | 103000 | 101000 | 2000 | |
| VMP-39-20 | 2/8/2012 | 910 | -0.60 | -0.66 | OVR | OVR | 14.5 | 1.6 | 200 | 169000 | 100000 | 69000 | |
| VMP-39-20 | 2/15/2012 | 943 | -0.42 | -0.47 | 27.9 | OVR | 4.9 | 12.8 | 201 | 32580 | 22930 | 9650 | |
| VMP-39-20 | 2/22/2012 | 914 | -0.09 | - 0.14 | OVR | OVR | 13.8 | 1.8 | 365 | 100000 | 48800 | 51200 | |
| VMP-39-20 | 2/29/2012 | 958 | -0.41 | - 0.32 | OVR | OVR | 12.1 | 3.6 | 375 | 77900 | 41150 | 36750 | |
| VMP-39-20 | 3/21/2012 | 949 | -0.15 | - 0.24 | OVR | OVR | 11.1 | 4.8 | 439 | 78000 | 18600 | 59400 | |
| VMP-39-20 | 4/18/2012 | 1013 | -0.48 | -0.41 | OVR | OVR | 11.8 | 2.0 | 520 | 52000 | 22000 | 30000 | |
| VMP-39-20 | 5/16/2012 | 857 | -0.63 | -0.70 | OVR | OVR | 12.8 | 1.3 | 570 | 56500 | 21400 | 35100 | |
| VMP-39-20 | 6/20/2012 | 946 | -0.46 | -0.49 | OVR | OVR | 12.7 | 0.9 | 571 | 46200 | 19300 | 26900 | |
| VMP-39-20 | 7/18/2012 | 1021 | -0.43 | -0.38 | OVR | OVR | 13.6 | 1.6 | 311 | 66300 | 11200 | 55100 | |
| VMP-39-20 | 8/15/2012 | 940 | -0.45 | -0.44 | OVR | OVR | 15.8 | 0.5 | 426 | 22500 | 6000 | 16500 | |
| VMP-39-20 | 9/19/2012 | 907 | -0.89 | -0.80 | OVR | OVR | 14.5 | 2.3 | 688 | 32400 | 7200 | 25200 | |
| VMP-39-20 | 10/17/2012 | 946 | -0.67 | -0.60 | OVR | OVR | 14.9 | 1.4 | 535 | 31900 | 7300 | 24600 | |
| VMP-39-20 | 11/20/2012 | 1106 | -0.58 | -0.50 | OVR | OVR | 16.1 | 1.4 | 638 | 26300 | 5400 | 20900 | |
| VMP-39-20 | 12/19/2012 | 920 | -0.40 | -0.50 | OVR | OVR | 16.3 | 1.2 | 930 | 14600 | 5000 | 9600 | |
| VMP-39-20 | 1/16/2013 | 1010 | -0.12 | -0.07 | 9.0 | OVR | 3.5 | 17.0 | 545 | 4040 | 1000 | 3040 | |
| VMP-39-20 | 2/25/2013 | 1339 | -0.02 | 0.05 | 82.0 | OVR | 16.2 | 1.4 | 785 | 12600 | 6200 | 6400 | |
| VMP-39-20 | 3/20/2013 | 1123 | -0.17 | -0.05 | 10.4 | OVR | 3.3 | 16.7 | 510 | 7400 | 2700 | 4700 | |

SEE LAST PAGE OF TABLE FOR NOTES

**TABLE 10**
**SVE SYSTEM MONTHLY MONITORING - VMP SAMPLING DATA**

| Sample ID | Date | Initial Reading Time (24-Hour) | Vacuum/Pressure | | Fixed Gases | | | | Soil Vapor Concentrations | | | | Comments |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | Initial Reading (Inches of $H_2O$) | Stabilized Reading (Inches of $H_2O$) | CH4 (%) | LEL (%) | $CO_2$ (%) | $O_2$ (%) | PID (ppmv) | THC (ppmv) | CH4 (ppmv) | PHC (ppmv) | |
| VMP-39-30 | 2/6/2012 | 1106 | -0.44 | -0.23 | OVR | OVR | 15.2 | 1.0 | 253 | 110000 | 75000 | 35000 | |
| VMP-39-30 | 2/7/2012 | 912 | -0.50 | -0.33 | OVR | OVR | 14.6 | 1.5 | 245 | 78000 | 60050 | 17950 | |
| VMP-39-30 | 2/8/2012 | 911 | -0.51 | -0.51 | OVR | OVR | 14.9 | 1.3 | 248 | 111000 | 63000 | 48000 | |
| VMP-39-30 | 2/15/2012 | 944 | -0.29 | -0.32 | OVR | OVR | 14.4 | 1.5 | 265 | 95000 | 60700 | 34300 | |
| VMP-39-30 | 2/22/2012 | 915 | 0.00 | - 0.04 | OVR | OVR | 14.7 | 1.2 | 379 | 68900 | 54200 | 14700 | |
| VMP-39-30 | 2/29/2012 | 959 | -0.28 | - 0.20 | OVR | OVR | 13.0 | 3.4 | 414 | 68600 | 30940 | 37660 | |
| VMP-39-30 | 3/21/2012 | 950 | -0.18 | - 0.15 | OVR | OVR | 13.0 | 0.3 | 402 | 186000 | 66000 | 120000 | |
| VMP-39-30 | 4/18/2012 | 1014 | 0.00 | -0.28 | OVR | OVR | 12.2 | 1.5 | 655 | 36800 | 8700 | 28100 | |
| VMP-39-30 | 5/16/2012 | 857 | -0.54 | -0.60 | OVR | OVR | 12.9 | 1.0 | 818 | 24400 | 4200 | 20200 | |
| VMP-39-30 | 6/20/2012 | 951 | -0.36 | -0.64 | OVR | OVR | 12.5 | 1.2 | 829 | 24500 | 6400 | 18100 | |
| VMP-39-30 | 7/18/2012 | 1025 | -0.48 | -0.48 | OVR | OVR | 13.0 | 1.5 | 542 | 29900 | 3900 | 26000 | |
| VMP-39-30 | 8/15/2012 | 945 | -0.33 | -0.62 | OVR | OVR | 15.8 | 0.6 | 583 | 15450 | 6200 | 9250 | |
| VMP-39-30 | 9/19/2012 | 907 | -0.71 | -0.59 | OVR | OVR | 16.3 | 1.4 | 816 | 14200 | 5700 | 8500 | |
| VMP-39-30 | 10/17/2012 | 947 | -0.45 | -0.40 | OVR | OVR | 16.4 | 0.6 | 758 | 13000 | 4200 | 8800 | |
| VMP-39-30 | 11/20/2012 | 1108 | -0.42 | -0.34 | 81.4 | OVR | 17.4 | 1.2 | 874 | 13200 | 2900 | 10300 | |
| VMP-39-30 | 12/19/2012 | 924 | -0.28 | -0.38 | 28.6 | OVR | 18.5 | 0.7 | 880 | 10300 | 4100 | 6200 | |
| VMP-39-30 | 1/16/2013 | 1015 | -0.23 | 0.07 | 29.1 | OVR | 18.2 | 0.9 | 817 | 11300 | 4600 | 6700 | |
| VMP-39-30 | 2/25/2013 | 1343 | 0.06 | 0.14 | 32.7 | OVR | 18.7 | 0.8 | 856 | 6600 | 3700 | 2900 | |
| VMP-39-30 | 3/20/2013 | 1126 | -0.73 | -0.45 | 9.6 | OVR | 18.8 | 0.9 | 629 | 2900 | 1250 | 1650 | |
| VMP-40-10 | 2/6/2012 | 1047 | -0.31 | -0.12 | 0.6 | 12.0 | 0.7 | 20.1 | 12.2 | 5080 | 5080 | 0.0 | |
| VMP-40-10 | 2/7/2012 | 854 | -0.49 | -0.41 | 0.0 | 1.0 | 0.2 | 20.9 | 7.8 | 237 | 221 | 16.1 | |
| VMP-40-10 | 2/8/2012 | 848 | -0.65 | -0.52 | 0.0 | 0.0 | 0.2 | 20.9 | 2.0 | 34.3 | 14.3 | 20.0 | |
| VMP-40-10 | 2/15/2012 | 920 | -0.14 | -0.39 | 0.0 | 1.0 | 0.3 | 20.6 | 10.6 | 1306 | 1264 | 42.0 | |
| VMP-40-10 | 2/22/2012 | 949 | 0.20 | 0.13 | OVR | OVR | 11.8 | 2.1 | 15.4 | 711000 | 464000 | 247000 | |
| VMP-40-10 | 2/29/2012 | 1030 | -0.16 | - 0.19 | 1.4 | 29.0 | 0.9 | 19.7 | 53.0 | 13200 | 18050 | -4850 | |
| VMP-40-10 | 3/6/2012 | 1009 | -0.02 | - 0.49 | 5.6 | OVR | 2.1 | 15.7 | 6.5 | 38000 | 12000 | 26000 | Benzene Reading: 0.0 ppm |
| VMP-40-10 | 3/7/2012 | 911 | -0.06 | - 0.11 | 0.7 | 15.0 | 0.6 | 20.4 | 5.6 | 6320 | 443 | 5877 | Benzene Reading: 0.0 ppm |
| VMP-40-10 | 3/21/2012 | 904 | -0.33 | - 0.28 | 0.1 | 3.0 | 0.2 | 20.6 | 0.4 | 1250 | 1250 | 0.0 | |
| VMP-40-10 | 4/18/2012 | 1045 | -0.27 | -0.21 | 0.0 | 0.0 | 0.1 | 20.9 | 0.5 | 105 | 105 | 0.0 | |
| VMP-40-10 | 5/16/2012 | 839 | -0.53 | -0.52 | 0.0 | 0.0 | 0.1 | 20.8 | 0.3 | 33.0 | 33.0 | 0 | |
| VMP-40-10 | 6/20/2012 | 924 | -0.40 | -0.34 | 0.0 | 0.0 | 1.2 | 20.6 | 0.6 | 14.7 | 14.2 | 0.5 | |
| VMP-40-10 | 7/18/2012 | 1000 | -0.33 | -0.26 | 0.0 | 0.0 | 0.1 | 20.6 | 0.9 | 8.7 | 6.5 | 2.2 | |
| VMP-40-10 | 8/15/2012 | 915 | -0.37 | -0.34 | 0.0 | 0.0 | 0.1 | 20.8 | 0.7 | 7.7 | 7.4 | 0.3 | |
| VMP-40-10 | 9/19/2012 | 848 | -0.74 | -0.67 | 0.0 | 0.0 | 0.0 | 20.8 | 0.4 | 2.7 | 0.0 | 2.7 | |
| VMP-40-10 | 10/17/2012 | 923 | -0.56 | -0.49 | 0.0 | 0.0 | 0.1 | 20.9 | 0.5 | 3.1 | 0.0 | 3.1 | |
| VMP-40-10 | 11/20/2012 | 1001 | -0.79 | -0.61 | 0.0 | 0.0 | 0.0 | 20.9 | 0.7 | 2.5 | 0.0 | 2.5 | |
| VMP-40-10 | 12/19/2012 | 859 | -0.36 | -0.46 | 0.0 | 0.0 | 0.1 | 20.7 | 0.3 | 0.9 | 0.0 | 0.9 | |
| VMP-40-10 | 1/16/2013 | 945 | -0.21 | -0.03 | 0.0 | 0.0 | 2.5 | 12.9 | 0.7 | 37.2 | 31.1 | 6.1 | |
| VMP-40-10 | 2/25/2013 | 1320 | 0.19 | 0.30 | 0.1 | 2.0 | 6.8 | 4.5 | 3.8 | 935 | 715 | 220 | |
| VMP-40-10 | 3/20/2013 | 1039 | -0.79 | -0.85 | 0.0 | 0.0 | 0.0 | 20.9 | 0.4 | 3.6 | 0.0 | 3.6 | |

SEE LAST PAGE OF TABLE FOR NOTES

**TABLE 10**
**SVE SYSTEM MONTHLY MONITORING - VMP SAMPLING DATA**

| Sample ID | Date | Initial Reading Time (24-Hour) | Vacuum/Pressure | | Fixed Gases | | | | Soil Vapor Concentrations | | | | Comments |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | Initial Reading (Inches of $H_2O$) | Stabilized Reading (Inches of $H_2O$) | CH4 (%) | LEL (%) | $CO_2$ (%) | $O_2$ (%) | PID (ppmv) | THC (ppmv) | CH4 (ppmv) | PHC (ppmv) | |
| VMP-40-20 | 2/6/2012 | 1048 | 0.62 | 0.65 | OVR | OVR | 12.7 | 1.3 | 55.6 | 1000000 | 1000000 | 0.0 | |
| VMP-40-20 | 2/7/2012 | 855 | -0.44 | -0.47 | OVR | OVR | 12.8 | 1.2 | 53.1 | 749000 | 666000 | 83000 | |
| VMP-40-20 | 2/8/2012 | 849 | 0.07 | -0.61 | OVR | OVR | 12.4 | 1.5 | 49.5 | 880000 | 306000 | 574000 | |
| VMP-40-20 | 2/15/2012 | 921 | -0.18 | -0.43 | OVR | OVR | 12.7 | 1.0 | 39.5 | 990000 | 664000 | 326000 | |
| VMP-40-20 | 2/22/2012 | 950 | 0.22 | 0.13 | OVR | OVR | 12.7 | 1.4 | 37.8 | 843000 | 598000 | 245000 | |
| VMP-40-20 | 2/29/2012 | 1031 | -0.22 | - 0.24 | OVR | OVR | 11.6 | 2.0 | 50.1 | 1000000 | 727000 | 273000 | |
| VMP-40-20 | 3/6/2012 | 1015 | -0.06 | -0.27 | OVR | OVR | 11.2 | 1.2 | 46.0 | 856000 | 772000 | 84000 | Benzene Reading: 11.2 ppm |
| VMP-40-20 | 3/7/2012 | 912 | -0.52 | - 0.21 | OVR | OVR | 12.2 | 0.9 | 36.6 | 993000 | 610000 | 383000 | Benzene Reading: 8.3 ppm |
| VMP-40-20 | 3/21/2012 | 905 | -0.47 | - 0.64 | OVR | OVR | 11.9 | 0.7 | 34.7 | 1000000 | 1000000 | 0.0 | |
| VMP-40-20 | 4/18/2012 | 1046 | -0.32 | -0.25 | OVR | OVR | 10.6 | 1.5 | 36.5 | 1000000 | 833000 | 167000 | |
| VMP-40-20 | 5/16/2012 | 839 | -0.62 | -0.63 | OVR | OVR | 11.4 | 1.4 | 33.7 | 1000000 | 1000000 | 0.0 | |
| VMP-40-20 | 6/20/2012 | 928 | -0.45 | -0.39 | OVR | OVR | 11.4 | 0.6 | 41.7 | 1000000 | 1000000 | 0.0 | |
| VMP-40-20 | 7/18/2012 | 1008 | -0.40 | -0.31 | OVR | OVR | 10.8 | 1.7 | 32.4 | 363000 | 360000 | 3000 | |
| VMP-40-20 | 8/15/2012 | 920 | -0.43 | -0.40 | OVR | OVR | 12.5 | 0.5 | 75.4 | 91700 | 70000 | 21700 | |
| VMP-40-20 | 9/19/2012 | 849 | -0.85 | -0.78 | OVR | OVR | 11.0 | 1.8 | 130 | 160000 | 102000 | 58000 | |
| VMP-40-20 | 10/17/2012 | 924 | -0.64 | -0.52 | 88.0 | OVR | 11.3 | 0.5 | 119 | 101000 | 85400 | 15600 | |
| VMP-40-20 | 11/20/2012 | 1003 | -0.90 | -0.68 | 84.8 | OVR | 10.9 | 0.7 | 204 | 76700 | 68100 | 8600 | |
| VMP-40-20 | 12/19/2012 | 903 | -0.42 | -0.51 | 58.0 | OVR | 11.0 | 0.9 | 121 | 124000 | 99000 | 25000 | |
| VMP-40-20 | 1/16/2013 | 950 | -0.25 | 0.00 | 67.2 | OVR | 11.0 | 0.9 | 93.2 | 122000 | 93000 | 29000 | |
| VMP-40-20 | 2/25/2013 | 1324 | 0.21 | 0.35 | 78.0 | OVR | 10.9 | 1.0 | 58.0 | 83000 | 68300 | 14700 | |
| VMP-40-20 | 3/20/2013 | 1044 | -0.95 | -0.60 | 66.9 | OVR | 11.7 | 0.8 | 26.1 | 176000 | 147000 | 29000 | |
| VMP-40-30 | 2/6/2012 | 1049 | -0.05 | -0.71 | OVR | OVR | 13.7 | 1.0 | 52.6 | 1000000 | 587000 | 413000 | |
| VMP-40-30 | 2/7/2012 | 856 | -0.04 | -0.44 | OVR | OVR | 13.8 | 1.0 | 48.8 | 532000 | 438000 | 94000 | |
| VMP-40-30 | 2/8/2012 | 850 | -0.70 | -0.60 | OVR | OVR | 15.5 | 1.0 | 47.3 | 628000 | 392000 | 236000 | |
| VMP-40-30 | 2/15/2012 | 922 | -0.19 | -0.62 | OVR | OVR | 12.7 | 2.0 | 38.2 | 614000 | 614000 | 0.0 | |
| VMP-40-30 | 2/22/2012 | 951 | 0.62 | 0.18 | OVR | OVR | 13.2 | 1.0 | 38.6 | 934000 | 624000 | 310000 | |
| VMP-40-30 | 2/29/2012 | 1032 | -0.16 | - 0.21 | OVR | OVR | 12.8 | 1.2 | 44.8 | 1000000 | 838000 | 162000 | |
| VMP-40-30 | 3/6/2012 | 1020 | -0.58 | 0.02 | OVR | OVR | 12.7 | 0.9 | 41.8 | 1000000 | 945000 | 55000 | Benzene Reading: 10.5 ppm |
| VMP-40-30 | 3/7/2012 | 913 | -0.61 | - 0.18 | OVR | OVR | 13.1 | 1.2 | 35.5 | 1000000 | 902000 | 98000 | Benzene Reading: 9.8 ppm |
| VMP-40-30 | 3/21/2012 | 906 | -0.36 | - 0.42 | OVR | OVR | 12.6 | 0.4 | 34.7 | 1000000 | 1000000 | 0.0 | |
| VMP-40-30 | 4/18/2012 | 1047 | -0.44 | -0.85 | OVR | OVR | 11.6 | 4.3 | 35.0 | 1000000 | 1000000 | 0.0 | |
| VMP-40-30 | 5/16/2012 | 839 | -0.38 | -0.66 | OVR | OVR | 11.4 | 0.9 | 25.8 | 1000000 | 1000000 | 0.0 | |
| VMP-40-30 | 6/20/2012 | 932 | -0.10 | -1.04 | OVR | OVR | 10.7 | 0.3 | 32.0 | 1000000 | 1000000 | 0.0 | |
| VMP-40-30 | 7/18/2012 | 1004 | -0.44 | -0.49 | OVR | OVR | 9.9 | 1.6 | 19.4 | 1000000 | 1000000 | 0.0 | |
| VMP-40-30 | 8/15/2012 | 925 | -0.58 | -0.37 | OVR | OVR | 11.1 | 0.9 | 37.0 | 390000 | 292000 | 98000 | |
| VMP-40-30 | 9/19/2012 | 849 | -0.85 | -0.84 | OVR | OVR | 10.5 | 1.7 | 47.4 | 274000 | 163000 | 111000 | |
| VMP-40-30 | 10/17/2012 | 925 | 0.00 | -0.52 | OVR | OVR | 11.1 | 0.7 | 52.3 | 188000 | 120000 | 68000 | |
| VMP-40-30 | 11/20/2012 | 1005 | -0.93 | -0.71 | 61.2 | OVR | 11.8 | 0.6 | 80.8 | 102000 | 102000 | 0.0 | |
| VMP-40-30 | 12/19/2012 | 907 | -0.46 | -0.97 | 84.4 | OVR | 10.8 | 1.7 | 73.6 | 204000 | 160000 | 44000 | |
| VMP-40-30 | 1/16/2013 | 955 | -0.26 | 0.04 | OVR | OVR | 11.1 | 1.6 | 63.5 | 220000 | 162000 | 58000 | |
| VMP-40-30 | 2/25/2013 | 1328 | 0.25 | 0.55 | 87.7 | OVR | 11.5 | 0.7 | 36.7 | 153000 | 86600 | 66400 | |
| VMP-40-30 | 3/20/2013 | 1057 | -0.95 | -0.53 | OVR | OVR | 11.7 | 1.1 | 25.5 | 330000 | 267000 | 63000 | |

SEE LAST PAGE OF TABLE FOR NOTES

**TABLE 10**
**SVE SYSTEM MONTHLY MONITORING - VMP SAMPLING DATA**

| Sample ID | Date | Initial Reading Time (24-Hour) | Vacuum/Pressure | | Fixed Gases | | | | Soil Vapor Concentrations | | | | Comments |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | Initial Reading (Inches of $H_2O$) | Stabilized Reading (Inches of $H_2O$) | CH4 (%) | LEL (%) | $CO_2$ (%) | $O_2$ (%) | PID (ppmv) | THC (ppmv) | CH4 (ppmv) | PHC (ppmv) | |
| VMP-41-10 | 12/13/2012 | 1426 | -0.01 | -0.03 | 0.0 | 0.0 | 2.7 | 18.2 | 0.2 | 0.5 | 0.0 | 0.5 | Initail sample after Public Works SVE startup. |
| VMP-41-10 | 12/19/2012 | 1312 | 0.01 | -0.02 | 0.0 | 0.0 | 1.9 | 19.1 | 0.2 | 0.1 | 0.0 | 0.1 | |
| VMP-41-10 | 1/16/2013 | 905 | 0.00 | -0.04 | 0.0 | 0.0 | 0.5 | 20.7 | 0.1 | 1.6 | 0.0 | 1.6 | |
| VMP-41-10 | 2/25/2013 | 1115 | -0.06 | -0.07 | 0.0 | 0.0 | 0.2 | 20.7 | 0.2 | 1.5 | 0.0 | 1.5 | |
| VMP-41-10 | 3/20/2013 | 1350 | -0.02 | -0.05 | 0.0 | 0.0 | 0.2 | 20.8 | 1.3 | 4.4 | 0.0 | 4.4 | |
| VMP-41-20 | 12/13/2012 | 1438 | -0.04 | -0.03 | 0.0 | 0.0 | 4.7 | 15.9 | 0.1 | 0.7 | 0.0 | 0.7 | Initail sample after Public Works SVE startup. |
| VMP-41-20 | 12/19/2012 | 1316 | 0.00 | -0.01 | 0.0 | 0.0 | 3.6 | 17.6 | 0.3 | 0.3 | 0.0 | 0.3 | |
| VMP-41-20 | 1/16/2013 | 906 | 0.00 | -0.02 | 0.0 | 0.0 | 2.8 | 18.5 | 0.1 | 1.9 | 0.0 | 1.9 | |
| VMP-41-20 | 2/25/2013 | 1110 | -0.07 | -0.07 | 0.0 | 0.0 | 0.5 | 20.5 | 0.3 | 1.2 | 0.0 | 1.2 | |
| VMP-41-20 | 3/20/2013 | 1354 | -0.02 | -0.08 | 0.0 | 0.0 | 0.3 | 20.7 | 0.7 | 2.0 | 0.0 | 2.0 | |
| VMP-41-30 | 12/13/2012 | 1443 | -0.02 | -0.03 | 0.0 | 0.0 | 7.0 | 13.1 | 0.1 | 1.0 | 0.0 | 1.0 | Initail sample after Public Works SVE startup. |
| VMP-41-30 | 12/19/2012 | 1320 | -0.02 | -0.02 | 0.0 | 0.0 | 5.8 | 14.8 | 0.3 | 0.2 | 0.0 | 0.2 | |
| VMP-41-30 | 1/16/2013 | 907 | 0.00 | -0.08 | 0.0 | 0.0 | 2.4 | 19.1 | 0.2 | 1.1 | 0.0 | 1.1 | |
| VMP-41-30 | 2/25/2013 | 1120 | -0.07 | -0.08 | 0.0 | 0.0 | 1.1 | 20.0 | 0.3 | 1.5 | 0.0 | 1.5 | |
| VMP-41-30 | 3/20/2013 | 1358 | -0.01 | -0.08 | 0.0 | 0.0 | 0.9 | 20.4 | 0.6 | 1.4 | 0.0 | 1.4 | |
| VMP-42-10 | 2/16/2012 | 816 | -0.16 | -0.23 | 0.0 | 0.0 | 6.7 | 12.8 | 0.5 | 3.6 | 0.0 | 3.6 | |
| VMP-42-10 | 2/17/2012 | 1426 | -0.01 | -0.01 | 0.0 | 0.0 | 7.0 | 13.8 | 0.9 | 15.1 | 15.1 | 0.0 | |
| VMP-42-10 | 2/20/2012 | 1402 | 0.00 | 3.29 | 0.0 | 0.0 | 6.2 | 15.3 | 0.8 | 10.1 | 7.7 | 2.5 | |
| VMP-42-10 | 2/21/2012 | 815 | -0.08 | -0.12 | 0.0 | 0.0 | 5.0 | 16.9 | 1.2 | 7.9 | 7.9 | 0 | |
| VMP-42-10 | 2/22/2012 | 900 | -0.02 | - 0.02 | 0.0 | 0.0 | 5.5 | 16.2 | 0.7 | 17.2 | 14.2 | 3.0 | |
| VMP-42-10 | 2/29/2012 | 944 | 0.00 | 0.00 | 0.0 | 0.0 | 4.2 | 17.8 | 0.7 | 2.6 | 0.0 | 2.6 | |
| VMP-42-10 | 3/21/2012 | 1443 | 0.00 | 0.00 | 0.0 | 0.0 | 3.4 | 18.3 | 0.5 | 0.0 | 0.0 | 0.0 | |
| VMP-42-10 | 4/18/2012 | 1017 | -0.04 | 0.00 | 0.0 | 0.0 | 2.4 | 18.9 | 0.2 | 1.8 | 0.0 | 1.8 | |
| VMP-42-10 | 5/16/2012 | 932 | -0.10 | -0.13 | 0.0 | 0.0 | 2.2 | 19.1 | 0.3 | 0.0 | 0.0 | 0.0 | |
| VMP-42-10 | 6/20/2012 | 1405 | -0.05 | -0.04 | 0.0 | 0.0 | 2.4 | 18.7 | 1.0 | 2.7 | 0.0 | 2.7 | |
| VMP-42-10 | 7/18/2012 | 1514 | 0.00 | 0.00 | 0.0 | 0.0 | 2.3 | 18.6 | 0.6 | 2.7 | 0.0 | 2.7 | |
| VMP-42-10 | 8/15/2012 | 1439 | 0.01 | -0.04 | 0.0 | 0.0 | 2.3 | 19.0 | 1.1 | 4.1 | 0.0 | 4.1 | |
| VMP-42-10 | 9/19/2012 | 942 | -0.05 | -0.08 | 0.0 | 0.0 | 1.6 | 19.5 | 0.5 | 1.8 | 0.0 | 1.8 | |
| VMP-42-10 | 10/17/2012 | 827 | 0.00 | -0.09 | 0.0 | 0.0 | 1.0 | 19.9 | 0.4 | 0.7 | 0.0 | 0.7 | |
| VMP-42-10 | 11/20/2012 | 1527 | -0.07 | -0.08 | 0.0 | 0.0 | 0.7 | 20.1 | 0.2 | 1.8 | 0.0 | 1.8 | |
| VMP-42-10 | 12/19/2012 | 1005 | -0.11 | -0.03 | 0.0 | 0.0 | 0.5 | 20.4 | 0.1 | 0.6 | 0.0 | 0.6 | |
| VMP-42-10 | 1/16/2013 | 1510 | 0.00 | -0.10 | 0.0 | 0.0 | 0.5 | 20.5 | 0.2 | 0.8 | 0.0 | 0.8 | |
| VMP-42-10 | 2/25/2013 | 1520 | 0.08 | 0.08 | 0.0 | 0.0 | 0.6 | 20.6 | 0.2 | 0.6 | 0.0 | 0.6 | |
| VMP-42-10 | 3/21/2013 | 1100 | -0.10 | -0.05 | 0.0 | 0.0 | 0.2 | 20.8 | 0.6 | 1.3 | 0.0 | 1.3 | |

SEE LAST PAGE OF TABLE FOR NOTES

**TABLE 10**
**SVE SYSTEM MONTHLY MONITORING - VMP SAMPLING DATA**

| Sample ID | Date | Initial Reading Time (24-Hour) | Vacuum/Pressure | | Fixed Gases | | | | Soil Vapor Concentrations | | | | Comments |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | Initial Reading (Inches of $H_2O$) | Stabilized Reading (Inches of $H_2O$) | CH4 (%) | LEL (%) | $CO_2$ (%) | $O_2$ (%) | PID (ppmv) | THC (ppmv) | CH4 (ppmv) | PHC (ppmv) | |
| VMP-42-20 | 2/16/2012 | 817 | -0.18 | -0.73 | 4.6 | 93.0 | 13.5 | 1.4 | 96.3 | 9580 | 6940 | 2640 | |
| VMP-42-20 | 2/17/2012 | 1426 | -0.01 | -0.01 | 43.6 | OVR | 13.2 | 1.2 | 189 | 29100 | 15610 | 13490 | |
| VMP-42-20 | 2/20/2012 | 1403 | -0.07 | -0.20 | 36.3 | OVR | 13.6 | 0.9 | 190 | 27370 | 12140 | 15230 | |
| VMP-42-20 | 2/21/2012 | 816 | -0.37 | -0.42 | 1.3 | 27.0 | 13.9 | 1.4 | 76.6 | 3040 | 2030 | 1010 | |
| VMP-42-20 | 2/22/2012 | 900 | 0.00 | - 0.02 | 12.0 | OVR | 14.0 | 1.1 | 169 | 14000 | 5170 | 8830 | |
| VMP-42-20 | 2/29/2012 | 945 | -0.26 | 0.11 | 1.2 | 23.0 | 14.1 | 1.1 | 79.2 | 3100 | 1360 | 1740 | |
| VMP-42-20 | 3/21/2012 | 1444 | -0.12 | 0.00 | 0.2 | 5.0 | 14.2 | 0.8 | 11.5 | 1100 | 950 | 150 | |
| VMP-42-20 | 4/18/2012 | 1018 | -0.19 | -0.10 | 0.0 | 0.0 | 9.4 | 9.8 | 0.3 | 2.2 | 0.0 | 2.2 | |
| VMP-42-20 | 5/16/2012 | 937 | -0.35 | -0.37 | 0.0 | 0.0 | 7.5 | 13.5 | 0.4 | 1.0 | 0.0 | 1.0 | |
| VMP-42-20 | 6/20/2012 | 1410 | -0.09 | -0.06 | 0.0 | 0.0 | 7.1 | 13.4 | 1.0 | 1.9 | 0.0 | 1.9 | |
| VMP-42-20 | 7/18/2012 | 1515 | -0.01 | 0.00 | 0.0 | 0.0 | 6.5 | 14.0 | 0.5 | 1.4 | 0.0 | 1.4 | |
| VMP-42-20 | 8/15/2012 | 1444 | -0.03 | -0.06 | 0.0 | 0.0 | 6.7 | 15.3 | 1.0 | 2.8 | 0.0 | 2.8 | |
| VMP-42-20 | 9/19/2012 | 943 | -0.34 | -0.31 | 0.0 | 0.0 | 5.2 | 16.6 | 0.7 | 0.9 | 0.0 | 0.9 | |
| VMP-42-20 | 10/17/2012 | 828 | -0.26 | -0.28 | 0.0 | 0.0 | 4.4 | 17.4 | 0.5 | 0.2 | 0.0 | 0.2 | |
| VMP-42-20 | 11/20/2012 | 1532 | -0.23 | -0.28 | 0.0 | 0.0 | 3.5 | 18.1 | 0.3 | 0.2 | 0.0 | 0.2 | |
| VMP-42-20 | 12/19/2012 | 1010 | -0.27 | -0.10 | 0.0 | 0.0 | 3.3 | 18.4 | 0.2 | 0.9 | 0.0 | 0.9 | |
| VMP-42-20 | 1/16/2013 | 1315 | 0.03 | -0.24 | 0.0 | 0.0 | 2.9 | 18.6 | 0.2 | 1.1 | 0.0 | 1.1 | |
| VMP-42-20 | 2/25/2013 | 1525 | 0.18 | 0.03 | 0.0 | 0.0 | 3.6 | 18.2 | 0.2 | 0.8 | 0.0 | 0.8 | |
| VMP-42-20 | 3/21/2013 | 1104 | -0.35 | -0.17 | 0.0 | 0.0 | 1.4 | 20.1 | 0.2 | 0.3 | 0.0 | 0.3 | |
| VMP-42-30 | 2/16/2012 | 818 | -0.66 | -1.20 | OVR | OVR | 11.6 | 1.9 | 161 | 63100 | 43060 | 20040 | |
| VMP-42-30 | 2/17/2012 | 1426 | 0.15 | NM | NM | NM | NM | NM | NM | NM | NM | NM | Pullback during purge. |
| VMP-42-30 | 2/20/2012 | 1404 | -0.23 | -0.39 | OVR | OVR | 11.6 | 1.2 | 183 | 71800 | 36860 | 34940 | |
| VMP-42-30 | 2/21/2012 | 817 | -0.68 | -0.73 | OVR | OVR | 11.7 | 1.7 | 188 | 96700 | 42600 | 54100 | |
| VMP-42-30 | 2/22/2012 | 900 | -0.02 | 0.05 | OVR | OVR | 11.9 | 1.9 | 161 | 88630 | 32020 | 56610 | |
| VMP-42-30 | 2/29/2012 | 946 | -0.28 | - 0.23 | OVR | OVR | 12.3 | 1.4 | 203 | 54000 | 18440 | 35560 | |
| VMP-42-30 | 3/21/2012 | 1445 | 0.09 | 0.07 | 48.0 | OVR | 12.5 | 0.9 | 197 | 25900 | 10300 | 15600 | |
| VMP-42-30 | 4/18/2012 | 1019 | -0.25 | -0.12 | 9.7 | OVR | 10.9 | 1.0 | 129 | 8500 | 4260 | 4240 | |
| VMP-42-30 | 5/16/2012 | 943 | -0.58 | -0.30 | 2.6 | 46.0 | 10.1 | 1.4 | 88.5 | 2000 | 1300 | 700 | |
| VMP-42-30 | 6/20/2012 | 1415 | -0.09 | -0.02 | 0.7 | 13.0 | 10.0 | 0.1 | 49.5 | 1000 | 0.0 | 1000 | |
| VMP-42-30 | 7/18/2012 | 1516 | -0.02 | 0.00 | 0.1 | 3.0 | 9.1 | 1.2 | 33.0 | 413 | 255 | 158 | |
| VMP-42-30 | 8/15/2012 | 1448 | -0.03 | -0.07 | 0.0 | 0.0 | 10.4 | 1.5 | 11.9 | 165 | 145 | 20.0 | |
| VMP-42-30 | 9/19/2012 | 944 | -0.62 | -0.56 | 0.0 | 0.0 | 10.1 | 8.6 | 3.0 | 4.7 | 0.0 | 4.7 | |
| VMP-42-30 | 10/17/2012 | 829 | -0.41 | -0.42 | 0.0 | 0.0 | 9.5 | 11.0 | 2.1 | 14.5 | 14.3 | 0.2 | |
| VMP-42-30 | 11/20/2012 | 1534 | -0.46 | -0.52 | 0.0 | 0.0 | 7.3 | 14.0 | 0.7 | 6.0 | 4.3 | 1.8 | |
| VMP-42-30 | 12/19/2012 | 1015 | -0.54 | -0.14 | 0.0 | 0.0 | 7.7 | 13.9 | 0.4 | 3.7 | 0.0 | 3.7 | |
| VMP-42-30 | 1/16/2013 | 1515 | -0.01 | -0.39 | 0.0 | 0.0 | 6.8 | 14.7 | 0.4 | 3.7 | 0.0 | 3.7 | |
| VMP-42-30 | 2/25/2013 | 1530 | 0.43 | 0.30 | 0.0 | 0.0 | 6.1 | 15.7 | 0.4 | 1.2 | 0.0 | 1.2 | |
| VMP-42-30 | 3/21/2013 | 1108 | -0.70 | -0.26 | 0.0 | 0.0 | 4.3 | 18.0 | 0.3 | 0.5 | 0.0 | 0.5 | |

SEE LAST PAGE OF TABLE FOR NOTES

**TABLE 10**
**SVE SYSTEM MONTHLY MONITORING - VMP SAMPLING DATA**

| Sample ID | Date | Initial Reading Time (24-Hour) | Vacuum/Pressure | | Fixed Gases | | | | Soil Vapor Concentrations | | | | Comments |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | Initial Reading (Inches of $H_2O$) | Stabilized Reading (Inches of $H_2O$) | CH4 (%) | LEL (%) | $CO_2$ (%) | $O_2$ (%) | PID (ppmv) | THC (ppmv) | CH4 (ppmv) | PHC (ppmv) | |
| VMP-43-10 | 2/1/2012 | 1430 | -0.95 | -0.94 | 0.0 | 0.0 | 0.4 | 20.5 | 0.2 | 1.2 | 0.0 | 1.2 | |
| VMP-43-10 | 2/2/2012 | 851 | 1.24 | -1.05 | 0.0 | 0.0 | 0.4 | 20.4 | 1.0 | 3.1 | 0.0 | 3.1 | |
| VMP-43-10 | 2/7/2012 | 901 | -1.00 | -0.89 | 0.0 | 0.0 | 0.5 | 20.4 | 0.2 | 0.0 | 0.0 | 0.0 | |
| VMP-43-10 | 2/10/2012 | 856 | -0.24 | -0.98 | 0.0 | 0.0 | 0.2 | 20.7 | 1.4 | 8.1 | 6.5 | 1.6 | |
| VMP-43-10 | 2/13/2012 | 811 | -0.92 | -0.92 | 0.0 | 0.0 | 0.3 | 20.7 | 0.7 | 1.0 | 0.0 | 1.0 | |
| VMP-43-10 | 2/16/2012 | 754 | -1.62 | -1.75 | 0.0 | 0.0 | 0.4 | 20.6 | 0.9 | 4.5 | 0.0 | 4.5 | |
| VMP-43-10 | 2/17/2012 | 847 | -1.02 | -0.81 | 0.0 | 0.0 | 0.4 | 20.9 | 3.0 | 2.9 | 0.0 | 2.9 | |
| VMP-43-10 | 2/22/2012 | 1032 | -0.02 | - 0.66 | 0.0 | 0.0 | 0.4 | 20.9 | 0.6 | 2.5 | 0.0 | 2.5 | |
| VMP-43-10 | 2/29/2012 | 1046 | 0.00 | - 0.68 | 0.0 | 0.0 | 0.5 | 20.4 | 0.8 | 2.8 | 0.0 | 2.8 | |
| VMP-43-10 | 3/21/2012 | 1500 | -0.35 | - 0.33 | 0.0 | 0.0 | 0.9 | 19.0 | 0.8 | 0.0 | 0.0 | 0.0 | |
| VMP-43-10 | 4/18/2012 | 1101 | -0.99 | -0.89 | 0.0 | 0.0 | 0.7 | 19.5 | 0.6 | 2.9 | 0.0 | 2.9 | |
| VMP-43-10 | 5/16/2012 | 1029 | -1.09 | -1.03 | 0.0 | 0.0 | 1.2 | 19.6 | 0.2 | 3.8 | 0.0 | 3.8 | |
| VMP-43-10 | 6/20/2012 | 1435 | -0.30 | -0.30 | 0.0 | 0.0 | 1.6 | 19.2 | 0.6 | 4.0 | 0.0 | 4.0 | |
| VMP-43-10 | 7/18/2012 | 1502 | -0.22 | -0.18 | 0.0 | 0.0 | 0.7 | 19.8 | 0.8 | 5.5 | 3.8 | 1.6 | |
| VMP-43-10 | 8/15/2012 | 1530 | -0.85 | -0.92 | 0.0 | 0.0 | 0.7 | 20.1 | 1.0 | 4.3 | 0.0 | 4.3 | |
| VMP-43-10 | 9/19/2012 | 1137 | -1.56 | -1.56 | 0.0 | 0.0 | 0.0 | 20.9 | 1.3 | 3.5 | 0.0 | 3.5 | |
| VMP-43-10 | 10/17/2012 | 853 | -0.14 | -0.67 | 0.0 | 0.0 | 0.5 | 19.9 | 0.4 | 1.5 | 0.0 | 1.5 | |
| VMP-43-10 | 11/20/2012 | 1315 | -0.50 | -0.55 | 0.0 | 0.0 | 0.3 | 20.6 | 0.3 | 1.3 | 0.0 | 1.3 | |
| VMP-43-10 | 12/19/2012 | NM | NM | NM | NM | NM | NM | NM | NM | NM | NM | NM | Construction equipment parked on well. Could not access. |
| VMP-43-10 | 1/16/2013 | 1620 | -0.72 | -0.52 | 0.0 | 0.0 | 0.5 | 20.4 | 0.1 | 2.0 | 0.0 | 2.0 | |
| VMP-43-10 | 2/25/2013 | 1435 | -0.66 | -0.63 | 0.0 | 0.0 | 0.1 | 20.8 | 0.3 | 1.2 | 0.0 | 1.2 | |
| VMP-43-10 | 3/21/2013 | 925 | -2.12 | -2.60 | 0.0 | 0.0 | 0.1 | 20.9 | 0.3 | 1.4 | 0.0 | 1.4 | |
| VMP-43-20 | 2/1/2012 | 1438 | -1.28 | -1.06 | OVR | OVR | 10.3 | 1.6 | 161 | 442000 | 115000 | 327000 | |
| VMP-43-20 | 2/2/2012 | 859 | -1.64 | -1.35 | OVR | OVR | 10.0 | 1.1 | 115 | 1000000 | 385000 | 615000 | |
| VMP-43-20 | 2/7/2012 | 902 | -1.30 | -1.18 | OVR | OVR | 9.2 | 2.0 | 96.4 | 1000000 | 739000 | 261000 | |
| VMP-43-20 | 2/10/2012 | 857 | -0.33 | -3.32 | OVR | OVR | 6.3 | 6.0 | 87.6 | 659000 | 469000 | 190000 | |
| VMP-43-20 | 2/13/2012 | 812 | -1.33 | -1.28 | 0.3 | 6.0 | 5.1 | 15.2 | 29.6 | 1513 | 78.3 | 1435 | |
| VMP-43-20 | 2/16/2012 | 755 | -2.25 | -4.57 | 0.0 | 1.0 | 5.0 | 16.1 | 18.2 | 392 | 259 | 133 | |
| VMP-43-20 | 2/17/2012 | 848 | -6.27 | -1.27 | 0.1 | 3.0 | 4.8 | 16.3 | 22.5 | 305 | 176 | 129 | |
| VMP-43-20 | 2/22/2012 | 1033 | -0.66 | - 0.87 | 0.1 | 2.0 | 4.5 | 16.7 | 22.9 | 368 | 191 | 178 | |
| VMP-43-20 | 2/29/2012 | 1048 | -0.07 | - 0.93 | 0.5 | 11.0 | 4.9 | 15.5 | 77.3 | 1375 | 547 | 828 | |
| VMP-43-20 | 3/21/2012 | 1501 | -0.35 | - 0.30 | 0.1 | 2.0 | 5.1 | 14.4 | 19.8 | 315 | 29.2 | 286 | |
| VMP-43-20 | 4/18/2012 | 1102 | -1.05 | -0.90 | 0.0 | 0.0 | 3.8 | 16.0 | 10.9 | 127 | 54.0 | 73.0 | |
| VMP-43-20 | 5/16/2012 | 1033 | -1.33 | -1.28 | 0.0 | 0.0 | 3.2 | 17.0 | 14.6 | 115 | 53.5 | 61.5 | |
| VMP-43-20 | 6/20/2012 | 1440 | -0.43 | -0.43 | 0.0 | 0.0 | 3.5 | 16.6 | 8.8 | 36.4 | 13.5 | 22.9 | |
| VMP-43-20 | 7/18/2012 | 1503 | -0.20 | -0.19 | 0.0 | 0.0 | 2.8 | 17.5 | 5.1 | 35.4 | 17.8 | 17.7 | |
| VMP-43-20 | 8/15/2012 | 1535 | -0.82 | -1.01 | 0.0 | 0.0 | 3.0 | 18.3 | 3.0 | 24.5 | 13.7 | 10.8 | |
| VMP-43-20 | 9/19/2012 | 1138 | -1.78 | -1.70 | 0.0 | 0.0 | 2.5 | 18.3 | 3.5 | 26.5 | 20.2 | 6.3 | |
| VMP-43-20 | 10/17/2012 | 853 | -1.03 | -0.33 | 0.0 | 0.0 | 2.3 | 18.5 | 0.9 | 7.6 | 5.2 | 2.4 | |
| VMP-43-20 | 11/20/2012 | 1319 | -0.77 | -0.84 | 0.0 | 0.0 | 2.3 | 18.3 | 1.0 | 11.7 | 8.3 | 3.4 | |
| VMP-43-20 | 12/19/2012 | NM | NM | NM | NM | NM | NM | NM | NM | NM | NM | NM | Construction equipment parked on well. Could not access. |
| VMP-43-20 | 1/16/2013 | 1625 | -0.74 | -0.71 | 0.0 | 0.0 | 3.0 | 17.6 | 0.4 | 19.9 | 15.1 | 4.8 | |
| VMP-43-20 | 2/25/2013 | 1440 | -0.55 | -0.51 | 0.0 | 0.0 | 2.5 | 18.2 | 0.6 | 16.4 | 14.5 | 1.9 | |
| VMP-43-20 | 3/21/2013 | 929 | -2.29 | -2.07 | 0.0 | 0.0 | 1.7 | 19.4 | 0.4 | 12.0 | 10.9 | 1.1 | |

SEE LAST PAGE OF TABLE FOR NOTES

**TABLE 10**
**SVE SYSTEM MONTHLY MONITORING - VMP SAMPLING DATA**

| Sample ID | Date | Initial Reading Time (24-Hour) | Vacuum/Pressure | | Fixed Gases | | | | Soil Vapor Concentrations | | | | Comments |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | Initial Reading (Inches of $H_2O$) | Stabilized Reading (Inches of $H_2O$) | CH4 (%) | LEL (%) | $CO_2$ (%) | $O_2$ (%) | PID (ppmv) | THC (ppmv) | CH4 (ppmv) | PHC (ppmv) | |
| VMP-43-30 | 2/1/2012 | 1445 | -0.96 | -0.73 | OVR | OVR | 8.5 | 1.0 | 98.2 | 1000000 | 1000000 | 0.0 | |
| VMP-43-30 | 2/2/2012 | 904 | -1.26 | -1.08 | OVR | OVR | 8.3 | 2.0 | 88.0 | 1000000 | 320000 | 680000 | |
| VMP-43-30 | 2/7/2012 | 903 | -1.05 | -0.92 | OVR | OVR | 7.7 | 6.2 | 113 | 850000 | 272000 | 578000 | |
| VMP-43-30 | 2/10/2012 | 858 | -0.27 | -1.14 | 3.3 | 65.0 | 2.8 | 16.8 | 43.7 | 16100 | 16000 | 100 | |
| VMP-43-30 | 2/13/2012 | 813 | -1.09 | -1.03 | OVR | OVR | 9.6 | 1.3 | 155 | 269000 | 107000 | 162000 | |
| VMP-43-30 | 2/16/2012 | 756 | -2.12 | -4.20 | OVR | OVR | 10.7 | 1.4 | 234 | 80600 | 43130 | 37470 | |
| VMP-43-30 | 2/17/2012 | 849 | -13.12 | -0.98 | 38.7 | OVR | 10.3 | 1.7 | 236 | 25830 | 21550 | 4280 | |
| VMP-43-30 | 2/22/2012 | 1033 | -0.85 | - 0.64 | 0.5 | 11.0 | 10.0 | 5.4 | 62.8 | 2330 | 2100 | 230 | |
| VMP-43-30 | 2/29/2012 | 1047 | -0.32 | - 0.76 | 0.0 | 1.0 | 8.2 | 9.1 | 43.2 | 922 | 475 | 446 | |
| VMP-43-30 | 3/21/2012 | 1502 | -0.40 | - 0.45 | 0.2 | 4.0 | 9.3 | 7.5 | 52.4 | 108 | 0.0 | 108 | |
| VMP-43-30 | 4/18/2012 | 1103 | -1.26 | -0.42 | 0.0 | 0.0 | 4.1 | 15.3 | 2.6 | 24.3 | 5.1 | 19.2 | |
| VMP-43-30 | 5/16/2012 | 1038 | -1.50 | -1.46 | 0.0 | 0.0 | 2.6 | 17.7 | 4.0 | 14.6 | 5.8 | 8.8 | |
| VMP-43-30 | 6/20/2012 | 1445 | -0.44 | -0.44 | 0.0 | 0.0 | 2.7 | 17.6 | 3.3 | 3.0 | 0.0 | 3.0 | |
| VMP-43-30 | 7/18/2012 | 1504 | -0.29 | -0.25 | 0.0 | 0.0 | 2.1 | 18.3 | 1.0 | 10.0 | 7.6 | 2.4 | |
| VMP-43-30 | 8/15/2012 | 1540 | -1.20 | -1.28 | 0.0 | 0.0 | 2.3 | 18.7 | 0.7 | 9.1 | 7.3 | 1.8 | |
| VMP-43-30 | 9/19/2012 | 1139 | -2.26 | -2.12 | 0.0 | 0.0 | 1.5 | 19.5 | 0.8 | 4.8 | 0.0 | 4.8 | |
| VMP-43-30 | 10/17/2012 | 853 | -0.96 | -1.01 | 0.0 | 0.0 | 0.5 | 19.9 | 0.3 | 1.1 | 0.0 | 1.1 | |
| VMP-43-30 | 11/20/2012 | 1323 | -0.77 | -0.84 | 0.0 | 0.0 | 1.9 | 18.4 | 0.2 | 1.2 | 0.0 | 1.2 | |
| VMP-43-30 | 12/19/2012 | NM | NM | NM | NM | NM | NM | NM | NM | NM | NM | NM | Construction equipment parked on well. Could not access. |
| VMP-43-30 | 1/16/2013 | 1630 | -0.75 | -0.72 | 0.0 | 0.0 | 2.4 | 17.8 | 0.3 | 7.7 | 3.6 | 4.1 | |
| VMP-43-30 | 2/25/2013 | 1445 | -0.81 | -0.84 | 0.0 | 0.0 | 2.1 | 18.1 | 0.3 | 4.6 | 0.0 | 4.6 | |
| VMP-43-30 | 3/21/2013 | 933 | -2.83 | -2.53 | 0.0 | 0.0 | 2.6 | 17.9 | 0.3 | 9.1 | 8.2 | 0.9 | |
| VMP-44-10 | 2/2/2012 | 1456 | -0.02 | -0.09 | OVR | OVR | 10.2 | 1.0 | 562 | 49000 | 20000 | 29000 | |
| VMP-44-10 | 2/3/2012 | 909 | -0.29 | 0.11 | 79.7 | OVR | 9.9 | 1.0 | 494 | 29600 | 11200 | 18400 | |
| VMP-44-10 | 2/7/2012 | 1109 | 0.25 | -0.05 | 80.8 | OVR | 9.6 | 1.5 | 528 | 26600 | 11000 | 15600 | |
| VMP-44-10 | 2/13/2012 | 1446 | -0.24 | -0.22 | 63.5 | OVR | 9.6 | 1.3 | 522 | 24900 | 11290 | 13610 | |
| VMP-44-10 | 2/14/2012 | 1622 | -0.12 | -0.12 | 30.8 | OVR | 7.1 | 6.7 | 534 | 14400 | 3550 | 10850 | |
| VMP-44-10 | 2/15/2012 | 1431 | -0.11 | -0.36 | 79.0 | OVR | 7.5 | 3.0 | 715 | 18100 | 5450 | 12650 | |
| VMP-44-10 | 2/22/2012 | 911 | -0.15 | 0.00 | 44.7 | OVR | 7.9 | 2.5 | 674 | 13100 | 3740 | 9360 | |
| VMP-44-10 | 2/29/2012 | 1405 | 0.24 | - 0.32 | 76.0 | OVR | 9.1 | 1.4 | 753 | 17930 | 2300 | 15630 | |
| VMP-44-10 | 3/21/2012 | 827 | -0.42 | - 0.07 | 30.6 | OVR | 8.1 | 4.7 | 643 | 10400 | 545 | 9855 | |
| VMP-44-10 | 4/18/2012 | 837 | -0.11 | -0.10 | 19.1 | OVR | 8.5 | 7.3 | 561 | 7000 | 2850 | 4150 | |
| VMP-44-10 | 5/16/2012 | 1325 | -0.11 | -0.10 | 12.7 | OVR | 9.6 | 7.3 | 625 | 4500 | 159 | 4341 | |
| VMP-44-10 | 6/20/2012 | 1359 | -0.02 | -0.05 | 28.0 | OVR | 14.2 | 1.9 | 704 | 4900 | 477 | 4423 | |
| VMP-44-10 | 7/18/2012 | 1428 | 0.00 | -0.10 | 35.7 | OVR | 16.1 | 1.7 | 654 | 9240 | 350 | 8890 | |
| VMP-44-10 | 8/15/2012 | 1100 | -0.07 | -0.05 | 34.0 | OVR | 14.9 | 3.0 | 488 | 6600 | 1080 | 5520 | |
| VMP-44-10 | 9/19/2012 | 1511 | -0.07 | -0.06 | 7.1 | OVR | 8.0 | 9.8 | 510 | 2200 | 160 | 2040 | |
| VMP-44-10 | 10/17/2012 | 953 | -0.13 | -0.08 | 3.8 | 76.0 | 9.6 | 5.9 | 435 | 1540 | 231 | 1309 | |
| VMP-44-10 | 11/20/2012 | 910 | -0.02 | -0.04 | 0.7 | 16.0 | 8.2 | 7.8 | 233 | 653 | 71.6 | 581 | |
| VMP-44-10 | 12/19/2012 | 838 | -0.10 | -0.11 | 0.0 | 0.0 | 1.3 | 18.7 | 4.8 | 28.3 | 5.5 | 22.8 | |
| VMP-44-10 | 1/16/2013 | 1313 | -0.01 | 0.00 | 0.2 | 5.0 | 4.3 | 12.3 | 110 | 310 | 12.7 | 297 | Resampled and confirmed. |
| VMP-44-10 | 2/25/2013 | 1055 | -0.01 | -0.02 | 0.2 | 4.0 | 4.2 | 12.6 | 35.0 | 262 | 13.0 | 249 | |
| VMP-44-10 | 3/21/2013 | 1019 | -0.29 | -0.72 | 0.0 | 0.0 | 0.0 | 20.9 | 0.4 | 2.0 | 0.0 | 2.0 | Result is suspect. |

SEE LAST PAGE OF TABLE FOR NOTES

**TABLE 10**
**SVE SYSTEM MONTHLY MONITORING - VMP SAMPLING DATA**

| Sample ID | Date | Initial Reading Time (24-Hour) | Vacuum/Pressure | | Fixed Gases | | | | Soil Vapor Concentrations | | | | Comments |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | Initial Reading (Inches of $H_2O$) | Stabilized Reading (Inches of $H_2O$) | CH4 (%) | LEL (%) | $CO_2$ (%) | $O_2$ (%) | PID (ppmv) | THC (ppmv) | CH4 (ppmv) | PHC (ppmv) | |
| VMP-44-20 | 2/2/2012 | 1501 | -0.16 | -0.04 | OVR | OVR | 13.4 | 0.6 | 427 | 32000 | 18700 | 13300 | |
| VMP-44-20 | 2/3/2012 | 914 | -0.11 | -0.15 | 78.7 | OVR | 13.1 | 0.9 | 384 | 34000 | 16500 | 17500 | |
| VMP-44-20 | 2/7/2012 | 1110 | -0.14 | -0.11 | 61.4 | OVR | 13.1 | 1.2 | 440 | 20610 | 9700 | 10910 | |
| VMP-44-20 | 2/13/2012 | 1447 | -0.28 | -0.29 | 32.5 | OVR | 12.7 | 1.1 | 443 | 14140 | 7670 | 6470 | |
| VMP-44-20 | 2/14/2012 | 1623 | -0.16 | -0.62 | 25.2 | OVR | 11.9 | 2.0 | 390 | 13790 | 7800 | 5990 | |
| VMP-44-20 | 2/15/2012 | 1432 | -0.28 | -0.54 | 36.3 | OVR | 12.1 | 1.2 | 577 | 13100 | 5480 | 7620 | |
| VMP-44-20 | 2/22/2012 | 920 | -0.26 | - 0.25 | 16.2 | OVR | 11.7 | 1.2 | 445 | 12640 | 4770 | 7870 | |
| VMP-44-20 | 2/29/2012 | 1409 | -0.04 | - 0.05 | 19.6 | OVR | 11.5 | 0.9 | 489 | 11100 | 3230 | 7870 | |
| VMP-44-20 | 3/21/2012 | 831 | -0.07 | - 0.40 | 15.2 | OVR | 11.9 | 0.0 | 503 | 7820 | 2180 | 5640 | |
| VMP-44-20 | 4/18/2012 | 847 | -0.22 | -0.07 | 5.6 | OVR | 11.4 | 2.4 | 342 | 3040 | 716 | 2324 | |
| VMP-44-20 | 5/16/2012 | 1330 | -0.31 | -0.49 | 5.6 | OVR | 11.9 | 3.8 | 398 | 2700 | 110 | 2590 | |
| VMP-44-20 | 6/20/2012 | 1400 | -0.05 | -0.24 | 6.6 | OVR | 14.1 | 2.2 | 353 | 2480 | 266 | 2214 | |
| VMP-44-20 | 7/18/2012 | 1429 | 0.00 | 0.00 | 8.5 | OVR | 15.2 | 3.1 | 453 | 1720 | 218 | 1502 | |
| VMP-44-20 | 8/15/2012 | 1110 | -0.32 | -0.30 | 5.3 | OVR | 17.2 | 2.8 | 334 | 2460 | 380 | 2080 | |
| VMP-44-20 | 9/19/2012 | 1512 | -0.49 | -0.49 | 3.0 | 61.0 | 15.6 | 4.6 | 316 | 1770 | 184 | 1586 | |
| VMP-44-20 | 10/17/2012 | 955 | -0.83 | -0.74 | 1.2 | 26.0 | 13.6 | 5.1 | 173 | 1020 | 146 | 874 | |
| VMP-44-20 | 11/20/2012 | 912 | -0.72 | -0.71 | 0.4 | 9.0 | 12.5 | 5.6 | 131 | 456 | 71.8 | 384 | |
| VMP-44-20 | 12/19/2012 | 841 | -0.58 | -0.47 | 0.2 | 5.0 | 11.7 | 5.9 | 80.7 | 255 | 57.8 | 197 | |
| VMP-44-20 | 1/16/2013 | 841 | -0.48 | -0.40 | 0.0 | 1.0 | 10.5 | 6.6 | 47.2 | 346 | 126 | 220 | |
| VMP-44-20 | 2/25/2013 | 1055 | -0.37 | -0.32 | 0.1 | 1.0 | 8.5 | 8.5 | 21.6 | 325 | 296 | 29.5 | |
| VMP-44-20 | 3/21/2013 | 1026 | -0.85 | -0.81 | 0.0 | 0.0 | 6.2 | 11.9 | 24.9 | 179 | 122 | 57.0 | |
| VMP-44-30 | 2/2/2012 | 1505 | -0.24 | -0.07 | OVR | OVR | 8.8 | 3.5 | 207 | 195000 | 72000 | 123000 | |
| VMP-44-30 | 2/3/2012 | 919 | -0.26 | -0.26 | OVR | OVR | 9.9 | 1.0 | 207 | 155000 | 50600 | 104400 | |
| VMP-44-30 | 2/7/2012 | 1111 | 0.64 | -0.23 | OVR | OVR | 9.9 | 2.0 | 233 | 98700 | 57000 | 41700 | |
| VMP-44-30 | 2/13/2012 | 1448 | -0.51 | -0.58 | OVR | OVR | 10.9 | 1.5 | 247 | 55900 | 25880 | 30020 | |
| VMP-44-30 | 2/14/2012 | 1624 | -1.25 | -1.28 | 77.1 | OVR | 11.1 | 1.1 | 219 | 39900 | 31000 | 8900 | |
| VMP-44-30 | 2/15/2012 | 1433 | -0.57 | -1.09 | 78.4 | OVR | 11.3 | 0.8 | 315 | 33680 | 22690 | 10990 | |
| VMP-44-30 | 2/22/2012 | 925 | -0.57 | - 0.55 | 14.8 | OVR | 10.2 | 4.3 | 220 | 18420 | 9970 | 8450 | |
| VMP-44-30 | 2/29/2012 | 1414 | -0.20 | 0.00 | 13.2 | OVR | 11.8 | 0.9 | 268 | 12540 | 6260 | 6280 | |
| VMP-44-30 | 3/21/2012 | 836 | -0.77 | - 0.73 | 2.9 | 59.0 | 10.3 | 1.5 | 182 | 5080 | 2700 | 2380 | |
| VMP-44-30 | 4/18/2012 | 850 | -1.13 | -1.06 | 0.4 | 8.0 | 10.1 | 2.6 | 70.5 | 1380 | 920 | 460 | |
| VMP-44-30 | 5/16/2012 | 1334 | -1.00 | -0.98 | 0.1 | 2.0 | 10.5 | 3.4 | 42.5 | 401 | 220 | 181 | |
| VMP-44-30 | 6/20/2012 | 1359 | -0.72 | -0.76 | 0.0 | 0.0 | 10.6 | 5.1 | 24.0 | 207 | 83.4 | 124 | |
| VMP-44-30 | 7/18/2012 | 1430 | 0.00 | 0.00 | 0.0 | 0.0 | 8.4 | 9.8 | 30.4 | 380 | 67.7 | 312 | |
| VMP-44-30 | 8/15/2012 | 1105 | -0.11 | -1.07 | 0.0 | 0.0 | 7.9 | 11.8 | 19.1 | 586 | 253 | 333 | |
| VMP-44-30 | 9/19/2012 | 1513 | -0.19 | -1.23 | 0.0 | 0.0 | 6.1 | 14.7 | 13.4 | 46.7 | 15.5 | 31.2 | |
| VMP-44-30 | 10/17/2012 | 958 | -1.71 | -1.58 | 0.0 | 0.0 | 5.1 | 16.5 | 7.0 | 35.9 | 22.3 | 13.6 | |
| VMP-44-30 | 11/20/2012 | 914 | -1.42 | -1.47 | 0.0 | 0.0 | 4.5 | 17.6 | 9.2 | 52.6 | 6.7 | 45.9 | |
| VMP-44-30 | 12/19/2012 | 848 | -1.14 | -0.99 | 0.0 | 0.0 | 4.7 | 16.8 | 9.7 | 69.2 | 30.6 | 38.6 | |
| VMP-44-30 | 1/16/2013 | 846 | -0.98 | -0.03 | 0.0 | 0.0 | 1.4 | 19.9 | 2.0 | 20.9 | 9.0 | 11.9 | |
| VMP-44-30 | 2/25/2013 | 1100 | -0.90 | -0.37 | 0.0 | 0.0 | 3.5 | 17.9 | 5.9 | 46.3 | 17.0 | 29.3 | |
| VMP-44-30 | 3/21/2013 | 1033 | -1.91 | -1.81 | 0.0 | 0.0 | 2.7 | 18.9 | 2.2 | 17.2 | 5.1 | 12.1 | |

SEE LAST PAGE OF TABLE FOR NOTES

**TABLE 10**
**SVE SYSTEM MONTHLY MONITORING - VMP SAMPLING DATA**

| Sample ID | Date | Initial Reading Time (24-Hour) | Vacuum/Pressure | | Fixed Gases | | | | Soil Vapor Concentrations | | | | Comments |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | Initial Reading (Inches of $H_2O$) | Stabilized Reading (Inches of $H_2O$) | CH4 (%) | LEL (%) | $CO_2$ (%) | $O_2$ (%) | PID (ppmv) | THC (ppmv) | CH4 (ppmv) | PHC (ppmv) | |
| VMP-45-10 | 2/2/2012 | 1433 | -0.30 | -0.21 | 0.0 | 0.0 | 6.1 | 14.8 | 12.4 | 35.0 | 0.0 | 35.0 | |
| VMP-45-10 | 2/3/2012 | 931 | -0.19 | -0.25 | NM | NM | NM | NM | NM | NM | NM | NM | Tedlar overfilled and popped. Could not sample. |
| VMP-45-10 | 2/7/2012 | 1128 | -0.15 | -0.06 | 0.0 | 0.0 | 3.4 | 19.1 | 1.8 | 5.0 | 0.0 | 5.0 | |
| VMP-45-10 | 2/15/2012 | 1444 | -0.18 | 0.05 | 0.0 | 0.0 | 1.9 | 20.2 | 0.3 | 1.8 | 0.0 | 1.8 | |
| VMP-45-10 | 2/22/2012 | 1424 | 0.00 | - 0.04 | 0.0 | 0.0 | 1.5 | 20.5 | 0.4 | 0.0 | 0.0 | 0.0 | |
| VMP-45-10 | 2/29/2012 | 903 | -0.14 | - 0.15 | 0.0 | 0.0 | 2.2 | 18.1 | 3.5 | 12.3 | 2.8 | 9.5 | |
| VMP-45-10 | 3/21/2012 | 928 | -0.16 | - 0.11 | 0.0 | 0.0 | 0.9 | 20.2 | 0.2 | 0.0 | 0.0 | 0.0 | |
| VMP-45-10 | 4/18/2012 | 929 | -0.20 | -0.16 | 0.0 | 0.0 | 0.8 | 20.2 | 0.2 | 2.6 | 0.0 | 2.6 | |
| VMP-45-10 | 5/16/2012 | 1346 | -0.21 | -0.19 | 0.0 | 0.0 | 0.8 | 20.1 | 0.7 | 0.0 | 0.0 | 0.0 | |
| VMP-45-10 | 6/20/2012 | 1054 | -0.16 | -0.18 | 0.0 | 0.0 | 0.8 | 20.5 | 0.4 | 2.3 | 0.0 | 2.3 | |
| VMP-45-10 | 7/18/2012 | 1359 | 0.00 | 0.00 | 0.0 | 0.0 | 0.6 | 20.1 | 0.6 | 7.7 | 2.2 | 5.5 | |
| VMP-45-10 | 8/15/2012 | 1125 | -0.18 | -0.18 | 0.0 | 0.0 | 0.7 | 20.4 | 0.5 | 2.3 | 0.0 | 2.3 | |
| VMP-45-10 | 9/19/2012 | 1453 | -0.12 | -0.10 | 0.0 | 0.0 | 0.5 | 20.5 | 0.6 | 0.8 | 0.0 | 0.8 | |
| VMP-45-10 | 10/17/2012 | 1010 | -0.22 | -0.21 | 0.0 | 0.0 | 0.3 | 20.6 | 0.3 | 0.9 | 0.0 | 0.9 | |
| VMP-45-10 | 11/20/2012 | 1025 | -0.18 | -0.13 | 0.0 | 0.0 | 0.2 | 20.8 | 0.4 | 0.3 | 0.0 | 0.3 | |
| VMP-45-10 | 12/19/2012 | 1057 | -0.11 | -0.06 | 0.0 | 0.0 | 0.2 | 20.8 | 0.2 | 0.5 | 0.0 | 0.5 | |
| VMP-45-10 | 1/16/2013 | 935 | -0.12 | NM | 0.0 | 0.0 | 0.1 | 20.9 | 0.0 | 1.8 | 0.0 | 1.8 | |
| VMP-45-10 | 2/25/2013 | 1115 | -0.10 | -0.11 | 0.0 | 0.0 | 0.1 | 20.9 | 0.2 | 0.7 | 0.0 | 0.7 | |
| VMP-45-10 | 3/20/2013 | 1535 | -0.22 | -0.20 | 0.0 | 0.0 | 0.1 | 20.8 | 0.7 | 1.9 | 0.0 | 1.9 | |
| VMP-45-20 | 2/2/2012 | 1437 | -0.21 | -0.55 | 63.2 | OVR | 13.6 | 0.7 | 385 | 32400 | 18200 | 14200 | |
| VMP-45-20 | 2/3/2012 | 936 | -0.77 | -0.78 | 34.9 | OVR | 13.5 | 0.7 | 326 | 24900 | 14100 | 10800 | |
| VMP-45-20 | 2/7/2012 | 1129 | -0.34 | -0.20 | 26.9 | OVR | 12.5 | 1.7 | 427 | 11190 | 6420 | 4770 | |
| VMP-45-20 | 2/15/2012 | 1445 | -0.80 | -0.38 | 9.3 | OVR | 8.4 | 5.4 | 566 | 3750 | 530 | 3220 | |
| VMP-45-20 | 2/22/2012 | 1429 | -0.15 | - 0.15 | 4.7 | 95.0 | 7.6 | 6.0 | 475 | 2240 | 174 | 2066 | |
| VMP-45-20 | 2/29/2012 | 908 | -0.23 | - 0.25 | 3.4 | 63.0 | 6.3 | 9.7 | 367 | 1860 | 128 | 1732 | |
| VMP-45-20 | 3/21/2012 | 933 | -0.25 | 0.00 | 1.4 | 29.0 | 7.0 | 8.7 | 250 | 1260 | 100 | 1160 | |
| VMP-45-20 | 4/18/2012 | 933 | -0.38 | -0.01 | 0.4 | 9.0 | 4.8 | 14.9 | 111 | 515 | 0.0 | 515 | |
| VMP-45-20 | 5/16/2012 | 1351 | -0.36 | -0.36 | 0.3 | 6.0 | 4.4 | 16.0 | 94.3 | 380 | 0.0 | 380 | |
| VMP-45-20 | 6/20/2012 | 1055 | -0.10 | -0.25 | 0.0 | 0.0 | 4.0 | 16.9 | 41.1 | 215 | 0.0 | 215 | |
| VMP-45-20 | 7/18/2012 | 1401 | 0.00 | 0.00 | 0.0 | 0.0 | 3.9 | 16.6 | 38.1 | 153 | 8.1 | 145 | |
| VMP-45-20 | 8/15/2012 | 1130 | -0.36 | -0.33 | 0.0 | 0.0 | 3.4 | 17.4 | 27.2 | 67.4 | 9.2 | 58.2 | |
| VMP-45-20 | 9/19/2012 | 1454 | -0.25 | -0.17 | 0.0 | 0.0 | 2.6 | 18.5 | 9.5 | 20.4 | 3.9 | 16.5 | |
| VMP-45-20 | 10/17/2012 | 1011 | -0.47 | -0.42 | 0.0 | 0.0 | 2.5 | 18.6 | 4.7 | 19.6 | 3.9 | 15.7 | |
| VMP-45-20 | 11/20/2012 | 1028 | -0.41 | -0.31 | 0.0 | 0.0 | 2.1 | 18.9 | 2.3 | 17.3 | 11.5 | 5.9 | |
| VMP-45-20 | 12/19/2012 | 1059 | -0.22 | -0.19 | 0.0 | 0.0 | 2.4 | 18.6 | 1.9 | 11.8 | 7.2 | 4.6 | |
| VMP-45-20 | 1/16/2013 | 939 | -0.36 | NM | 0.0 | 0.0 | 2.2 | 18.7 | 1.2 | 15.7 | 10.6 | 5.1 | |
| VMP-45-20 | 2/25/2013 | 1115 | -0.20 | -0.21 | 0.0 | 0.0 | 1.9 | 18.8 | 0.9 | 12.7 | 8.7 | 4.0 | |
| VMP-45-20 | 3/20/2013 | 1539 | -0.41 | -0.43 | 0.0 | 0.0 | 1.0 | 20.0 | 0.8 | 5.4 | 1.2 | 4.2 | |

SEE LAST PAGE OF TABLE FOR NOTES

**TABLE 10**
**SVE SYSTEM MONTHLY MONITORING - VMP SAMPLING DATA**

| Sample ID | Date | Initial Reading Time (24-Hour) | Vacuum/Pressure | | Fixed Gases | | | | Soil Vapor Concentrations | | | | Comments |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | Initial Reading (Inches of $H_2O$) | Stabilized Reading (Inches of $H_2O$) | CH4 (%) | LEL (%) | $CO_2$ (%) | $O_2$ (%) | PID (ppmv) | THC (ppmv) | CH4 (ppmv) | PHC (ppmv) | |
| VMP-45-30 | 2/2/2012 | 1443 | -0.21 | -0.28 | OVR | OVR | 13.2 | 1.0 | 340 | 106000 | 53000 | 53000 | |
| VMP-45-30 | 2/3/2012 | 942 | -0.20 | -0.31 | OVR | OVR | 12.5 | 2.0 | 312 | 72800 | 40600 | 32200 | |
| VMP-45-30 | 2/7/2012 | 1130 | -0.53 | -0.13 | OVR | OVR | 13.1 | 1.3 | 395 | 56800 | 28760 | 28040 | |
| VMP-45-30 | 2/15/2012 | 1446 | -0.38 | -0.42 | OVR | OVR | 11.4 | 1.2 | 561 | 52500 | 20800 | 31700 | |
| VMP-45-30 | 2/22/2012 | 1434 | -0.15 | -0.10 | 86.6 | OVR | 10.2 | 1.2 | 616 | 31180 | 11790 | 19390 | |
| VMP-45-30 | 2/29/2012 | 913 | -0.29 | - 0.29 | 65.3 | OVR | 10.0 | 1.4 | 598 | 16640 | 9820 | 6820 | |
| VMP-45-30 | 3/21/2012 | 940 | -0.33 | - 0.25 | 33.4 | OVR | 12.3 | 0.0 | 789 | 12680 | 3560 | 9120 | |
| VMP-45-30 | 4/18/2012 | 937 | -0.45 | -0.38 | 7.3 | OVR | 9.8 | 4.7 | 639 | 3570 | 200 | 3370 | |
| VMP-45-30 | 5/16/2012 | 1355 | -0.42 | -0.42 | 1.5 | 30.0 | 8.9 | 7.3 | 450 | 1400 | 130 | 1270 | |
| VMP-45-30 | 6/20/2012 | 1056 | -0.37 | -0.41 | 0.3 | 7.0 | 8.7 | 7.8 | 209 | 277 | 53.5 | 224 | |
| VMP-45-30 | 7/18/2012 | 1400 | 0.00 | 0.00 | 0.1 | 2.0 | 7.3 | 9.4 | 143 | 86.0 | 54.0 | 32.0 | |
| VMP-45-30 | 8/15/2012 | 1135 | -0.43 | -0.38 | 0.0 | 1.0 | 7.0 | 12.6 | 60.0 | 71.0 | 35.2 | 35.8 | |
| VMP-45-30 | 9/19/2012 | 1455 | -0.33 | -0.29 | 0.0 | 0.0 | 4.9 | 15.2 | 42.8 | 87.7 | 37.7 | 50.0 | |
| VMP-45-30 | 10/17/2012 | 1012 | -0.57 | -0.51 | 0.0 | 0.0 | 4.2 | 16.4 | 22.5 | 54.9 | 6.6 | 48.3 | |
| VMP-45-30 | 11/20/2012 | 1031 | -0.50 | -0.40 | 0.0 | 0.0 | 3.7 | 17.2 | 9.0 | 19.1 | 5.8 | 13.3 | |
| VMP-45-30 | 12/19/2012 | 1100 | -0.29 | -0.19 | 0.0 | 0.0 | 3.7 | 17.3 | 10.1 | 20.9 | 4.0 | 16.9 | |
| VMP-45-30 | 1/16/2013 | 944 | -0.29 | NM | 0.0 | 0.0 | 3.2 | 17.5 | 5.9 | 17.8 | 5.1 | 12.7 | |
| VMP-45-30 | 2/25/2013 | 1115 | -0.25 | -0.25 | 0.0 | 0.0 | 2.9 | 17.7 | 5.1 | 19.6 | 5.1 | 14.5 | |
| VMP-45-30 | 3/20/2013 | 1544 | -0.50 | -0.50 | 0.0 | 0.0 | 1.8 | 19.1 | 1.2 | 4.8 | 0.0 | 4.8 | |
| VMP-46-10 | 2/15/2012 | NM | NM | NM | NM | NM | NM | NM | NM | NM | NM | NM | Chip and seal mounded over well. Cannot sample. |
| VMP-46-10 | 2/16/2012 | NM | NM | NM | NM | NM | NM | NM | NM | NM | NM | NM | Chip and seal mounded over well. Cannot sample. |
| VMP-46-10 | 2/17/2012 | NM | NM | NM | NM | NM | NM | NM | NM | NM | NM | NM | Chip and seal mounded over well. Cannot sample. |
| VMP-46-10 | 2/20/2012 | NM | NM | NM | NM | NM | NM | NM | NM | NM | NM | NM | Chip and seal mounded over well. Cannot sample. |
| VMP-46-10 | 2/21/2012 | 958 | -1.25 | -0.78 | 1.0 | 20.0 | 1.0 | 20.6 | 146 | 1379 | 37.3 | 1342 | |
| VMP-46-10 | 2/22/2012 | 936 | 0.12 | 0.11 | 0.6 | 12.0 | 0.2 | 20.8 | 45.4 | 1036 | 298 | 738 | |
| VMP-46-10 | 2/29/2012 | 901 | -0.33 | -0.38 | 0.3 | 6.0 | 2.6 | 18.0 | 93.9 | 744 | 58.6 | 685 | |
| VMP-46-10 | 3/21/2012 | 900 | -0.40 | -0.39 | 0.0 | 0.0 | 1.8 | 19.3 | 0.5 | 18.3 | 4.6 | 13.7 | |
| VMP-46-10 | 4/18/2012 | 829 | -0.36 | -0.27 | 0.0 | 1.0 | 1.5 | 19.2 | 0.8 | 115 | 78.0 | 37.0 | |
| VMP-46-10 | 5/16/2012 | 900 | -0.50 | -0.52 | 0.0 | 0.0 | 1.0 | 20.0 | 0.3 | 1.5 | 0.0 | 1.5 | |
| VMP-46-10 | 6/20/2012 | 840 | -0.48 | -0.45 | 0.0 | 0.0 | 0.6 | 20.3 | 0.4 | 0.0 | 0.0 | 0.0 | |
| VMP-46-10 | 7/18/2012 | 919 | -0.46 | -0.37 | 0.0 | 0.0 | 0.7 | 20.2 | 0.7 | 1.9 | 0.0 | 1.9 | |
| VMP-46-10 | 8/15/2012 | 836 | -0.39 | -0.31 | 0.0 | 0.0 | 0.5 | 20.7 | 0.9 | 4.8 | 0.0 | 4.8 | |
| VMP-46-10 | 9/19/2012 | 1228 | -0.33 | -0.25 | 0.0 | 0.0 | 0.2 | 20.6 | 0.7 | 5.1 | 0.0 | 5.1 | |
| VMP-46-10 | 10/17/2012 | 848 | -0.40 | -0.45 | 0.0 | 0.0 | 0.7 | 20.1 | 0.4 | 2.2 | 0.0 | 2.2 | |
| VMP-46-10 | 11/20/2012 | 942 | -0.53 | -0.36 | 0.0 | 0.0 | 0.4 | 20.6 | 0.6 | 2.6 | 0.0 | 2.6 | |
| VMP-46-10 | 12/19/2012 | 1021 | -0.43 | -0.36 | 0.0 | 0.0 | 0.2 | 20.7 | 0.3 | 0.3 | 0.0 | 0.3 | |
| VMP-46-10 | 1/16/2013 | 902 | -0.28 | -0.19 | 0.0 | 0.0 | 0.4 | 20.0 | 0.3 | 1.0 | 0.0 | 1.0 | |
| VMP-46-10 | 2/25/2013 | NM | NM | -11.20 | NM | NM | NM | NM | NM | NM | NM | NM | Water encountered during sampling. |
| VMP-46-10 | 3/20/2013 | 916 | -0.83 | -0.83 | 0.0 | 0.0 | 0.1 | 20.8 | 0.2 | 0.9 | 0.0 | 0.9 | |

SEE LAST PAGE OF TABLE FOR NOTES

**TABLE 10**
**SVE SYSTEM MONTHLY MONITORING - VMP SAMPLING DATA**

| Sample ID | Date | Initial Reading Time (24-Hour) | Vacuum/Pressure | | Fixed Gases | | | | Soil Vapor Concentrations | | | | Comments |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | Initial Reading (Inches of $H_2O$) | Stabilized Reading (Inches of $H_2O$) | CH4 (%) | LEL (%) | $CO_2$ (%) | $O_2$ (%) | PID (ppmv) | THC (ppmv) | CH4 (ppmv) | PHC (ppmv) | |
| VMP-46-20 | 2/15/2012 | NM | NM | NM | NM | NM | NM | NM | NM | NM | NM | NM | Chip and seal mounded over well. Cannot sample. |
| VMP-46-20 | 2/16/2012 | NM | NM | NM | NM | NM | NM | NM | NM | NM | NM | NM | Chip and seal mounded over well. Cannot sample. |
| VMP-46-20 | 2/17/2012 | NM | NM | NM | NM | NM | NM | NM | NM | NM | NM | NM | Chip and seal mounded over well. Cannot sample. |
| VMP-46-20 | 2/20/2012 | NM | NM | NM | NM | NM | NM | NM | NM | NM | NM | NM | Chip and seal mounded over well. Cannot sample. |
| VMP-46-20 | 2/21/2012 | 959 | -1.06 | -1.09 | OVR | OVR | 7.1 | 2.6 | 78.6 | 1000000 | 811000 | 189000 | |
| VMP-46-20 | 2/22/2012 | 937 | 0.19 | 0.17 | OVR | OVR | 7.7 | 1.2 | 64.3 | 923000 | 374000 | 549000 | |
| VMP-46-20 | 2/29/2012 | 902 | -0.45 | -0.51 | OVR | OVR | 7.4 | 1.2 | 67.7 | 1000000 | 405000 | 595000 | |
| VMP-46-20 | 3/21/2012 | 900 | -0.55 | -0.53 | OVR | OVR | 7.3 | 0.6 | 66.1 | 1000000 | 438000 | 562000 | |
| VMP-46-20 | 4/18/2012 | 829 | -0.49 | -0.38 | OVR | OVR | 6.4 | 1.9 | 70.0 | 775000 | 359000 | 416000 | |
| VMP-46-20 | 5/16/2012 | 901 | -0.36 | -0.74 | OVR | OVR | 8.0 | 1.0 | 82.1 | 510000 | 241000 | 269000 | |
| VMP-46-20 | 6/20/2012 | 841 | 0.02 | -0.64 | OVR | OVR | 9.7 | 0.5 | 82.0 | 136000 | 85300 | 50700 | |
| VMP-46-20 | 7/18/2012 | 920 | -0.64 | -0.52 | OVR | OVR | 10.1 | 1.5 | 56.0 | 203000 | 124000 | 79000 | |
| VMP-46-20 | 8/15/2012 | 837 | -0.55 | -0.51 | OVR | OVR | 12.7 | 1.5 | 107 | 149000 | 100000 | 49000 | |
| VMP-46-20 | 9/19/2012 | 1230 | -0.47 | -2.22 | OVR | OVR | 13.6 | 1.7 | 148 | 94500 | 89700 | 4800 | |
| VMP-46-20 | 10/17/2012 | 849 | -0.52 | -0.63 | OVR | OVR | 12.9 | 1.1 | 124 | 168000 | 111000 | 57000 | |
| VMP-46-20 | 11/20/2012 | 946 | -0.75 | -0.51 | OVR | OVR | 12.8 | 1.4 | 326 | 85700 | 56000 | 29700 | |
| VMP-46-20 | 12/19/2012 | 1022 | -0.66 | -0.52 | 57.2 | OVR | 12.7 | 1.4 | 190 | 70600 | 60000 | 10600 | |
| VMP-46-20 | 1/16/2013 | 907 | -0.38 | -0.25 | OVR | OVR | 12.6 | 0.9 | 235 | 76500 | 65000 | 11500 | |
| VMP-46-20 | 2/25/2013 | 927 | -0.47 | -0.44 | OVR | OVR | 12.0 | 0.8 | 223 | 86700 | 44800 | 41900 | |
| VMP-46-20 | 3/20/2013 | 920 | -1.41 | -1.25 | 18.5 | OVR | 9.2 | 6.7 | 145 | 24200 | 19900 | 4300 | |
| VMP-46-30 | 2/15/2012 | NM | NM | NM | NM | NM | NM | NM | NM | NM | NM | NM | Chip and seal mounded over well. Cannot sample. |
| VMP-46-30 | 2/16/2012 | NM | NM | NM | NM | NM | NM | NM | NM | NM | NM | NM | Chip and seal mounded over well. Cannot sample. |
| VMP-46-30 | 2/17/2012 | NM | NM | NM | NM | NM | NM | NM | NM | NM | NM | NM | Chip and seal mounded over well. Cannot sample. |
| VMP-46-30 | 2/20/2012 | NM | NM | NM | NM | NM | NM | NM | NM | NM | NM | NM | Chip and seal mounded over well. Cannot sample. |
| VMP-46-30 | 2/21/2012 | 1000 | -1.06 | -1.06 | OVR | OVR | 7.5 | 2.4 | 77.6 | 906000 | 747000 | 159000 | |
| VMP-46-30 | 2/22/2012 | 937 | 0.17 | 0.17 | OVR | OVR | 8.0 | 1.4 | 64.3 | 1000000 | 1000000 | 0.0 | |
| VMP-46-30 | 2/29/2012 | 903 | -0.47 | -0.50 | OVR | OVR | 7.5 | 1.4 | 69.3 | 1000000 | 533000 | 467000 | |
| VMP-46-30 | 3/21/2012 | 900 | -0.56 | -0.54 | OVR | OVR | 6.9 | 0.6 | 71.1 | 1000000 | 1000000 | 0.0 | |
| VMP-46-30 | 4/18/2012 | 830 | -0.49 | -0.39 | OVR | OVR | 6.2 | 1.2 | 71.5 | 1000000 | 448000 | 552000 | |
| VMP-46-30 | 5/16/2012 | 902 | -0.70 | -0.76 | OVR | OVR | 6.4 | 0.5 | 83.1 | 1000000 | 610000 | 390000 | |
| VMP-46-30 | 6/20/2012 | 842 | -0.69 | -0.65 | OVR | OVR | 6.3 | 1.6 | 106 | 565000 | 305000 | 260000 | |
| VMP-46-30 | 7/18/2012 | 921 | -0.64 | -0.13 | OVR | OVR | 6.2 | 1.8 | 55.4 | 1000000 | 283000 | 717000 | |
| VMP-46-30 | 8/15/2012 | 837 | -0.59 | -0.53 | OVR | OVR | 7.8 | 1.8 | 121 | 392000 | 225000 | 167000 | |
| VMP-46-30 | 9/19/2012 | 1231 | -0.51 | -2.53 | OVR | OVR | 9.3 | 1.9 | 152 | 669000 | 260000 | 409000 | |
| VMP-46-30 | 10/17/2012 | 850 | -0.56 | -0.61 | OVR | OVR | 10.7 | 1.0 | 119 | 414000 | 336000 | 78000 | |
| VMP-46-30 | 11/20/2012 | 950 | -0.76 | -0.51 | OVR | OVR | 11.7 | 1.4 | 223 | 256000 | 216000 | 40000 | |
| VMP-46-30 | 12/19/2012 | 1023 | -0.68 | -0.53 | OVR | OVR | 11.9 | 1.9 | 242 | 310000 | 155000 | 155000 | |
| VMP-46-30 | 1/16/2013 | 912 | -0.42 | -0.23 | OVR | OVR | 12.5 | 0.8 | 180 | 215000 | 114000 | 101000 | |
| VMP-46-30 | 2/25/2013 | 931 | -0.37 | -0.43 | OVR | OVR | 11.5 | 1.4 | 210 | 179000 | 79100 | 99900 | |
| VMP-46-30 | 3/20/2013 | 924 | -1.33 | -1.15 | 8.1 | OVR | 1.2 | 18.8 | 150 | 9600 | 6000 | 3600 | Results are suspect because oxygen concentrations in the Tedlar is higher than expected. |

SEE LAST PAGE OF TABLE FOR NOTES

**TABLE 10**
**SVE SYSTEM MONTHLY MONITORING - VMP SAMPLING DATA**

| Sample ID | Date | Initial Reading Time (24-Hour) | Vacuum/Pressure | | Fixed Gases | | | | Soil Vapor Concentrations | | | | Comments |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | Initial Reading (Inches of $H_2O$) | Stabilized Reading (Inches of $H_2O$) | CH4 (%) | LEL (%) | $CO_2$ (%) | $O_2$ (%) | PID (ppmv) | THC (ppmv) | CH4 (ppmv) | PHC (ppmv) | |
| VMP-47-5 | 3/21/2013 | 1234 | 0.02 | 0.12 | 0.0 | 0.0 | 10.9 | 3.6 | 10.9 | 152 | 0.0 | 152 | Initial monthly sample after installation. |
| VMP-47-10 | 3/21/2013 | 1238 | 0.03 | 0.10 | 0.0 | 0.0 | 10.9 | 5.4 | 2.8 | 96.9 | 0.0 | 96.9 | Initial monthly sample after installation. |
| VMP-47-20 | 3/21/2013 | 1242 | 0.13 | 0.41 | 4.1 | 80.0 | 12.2 | 1.0 | 57.8 | 4800 | 3250 | 1550 | Initial monthly sample after installation. |
| VMP-47-30 | 3/21/2013 | 1246 | 0.18 | 0.55 | 4.9 | 99.0 | 12.2 | 0.8 | 37.5 | 12200 | 10200 | 2000 | Initial monthly sample after installation. |
| VMP-48-5 | 2/26/2013 | 1339 | 0.00 | -0.01 | 0.0 | 0.0 | 0.1 | 20.2 | 0.2 | 4.5 | 0.0 | 4.5 | Initial monthly sample after installation. |
| VMP-48-5 | 3/21/2013 | 1447 | 0.00 | 0.00 | 0.0 | 0.0 | 0.4 | 20.3 | 0.3 | 2.9 | 0.0 | 2.9 | |
| VMP-48-10 | 2/26/2013 | 1343 | -0.03 | -0.05 | 0.0 | 0.0 | 2.4 | 18.4 | 0.1 | 0.5 | 0.0 | 0.5 | Initial monthly sample after installation. |
| VMP-48-10 | 3/21/2013 | 1449 | -0.04 | 0.00 | 0.0 | 0.0 | 1.8 | 19.2 | 0.2 | 0.7 | 0.0 | 0.7 | |
| VMP-48-20 | 2/26/2013 | 1345 | -0.03 | -0.72 | 0.0 | 0.0 | 4.1 | 17.9 | 0.2 | 1.2 | 0.0 | 1.2 | Initial monthly sample after installation. |
| VMP-48-20 | 3/21/2013 | 1454 | 0.00 | 0.00 | 0.0 | 0.0 | 3.4 | 18.6 | 0.2 | 0.2 | 0.0 | 0.2 | |
| VMP-48-30 | 2/26/2013 | 1347 | -0.17 | -0.30 | 0.0 | 0.0 | 11.2 | 1.3 | 2.3 | 26.0 | 0.0 | 26.0 | Initial monthly sample after installation. |
| VMP-48-30 | 3/21/2013 | 1456 | 0.09 | 0.05 | 0.0 | 0.0 | 11.1 | 1.9 | 1.9 | 13.8 | 0.0 | 13.8 | |
| VMP-49-5 | 2/26/2013 | 1358 | -0.21 | -0.23 | 0.0 | 0.0 | 0.9 | 20.0 | 8.3 | 74.8 | 18.2 | 56.6 | Initial monthly sample after installation. |
| VMP-49-5 | 3/21/2013 | 1508 | -0.02 | -0.20 | 0.0 | 0.0 | 0.4 | 20.6 | 0.3 | 0.2 | 0.0 | 0.2 | |
| VMP-49-10 | 2/26/2013 | 1402 | -0.18 | -0.20 | 0.0 | 0.0 | 0.1 | 20.4 | 0.2 | 0.3 | 0.0 | 0.3 | Initial monthly sample after installation. |
| VMP-49-10 | 3/21/2013 | 1510 | -0.17 | -0.19 | 0.0 | 0.0 | 0.5 | 20.5 | 0.2 | 0.9 | 0.0 | 0.9 | |
| VMP-49-20 | 2/26/2013 | 1404 | -0.03 | -0.03 | 0.0 | 0.0 | 0.2 | 20.4 | 0.1 | 1.1 | 0.0 | 1.1 | Initial monthly sample after installation. |
| VMP-49-20 | 3/21/2013 | 1512 | -0.02 | -0.02 | 0.0 | 0.0 | 0.4 | 20.5 | 0.2 | 1.1 | 0.0 | 1.1 | |
| VMP-49-30 | 2/26/2013 | 1406 | -0.54 | -0.66 | 19.5 | OVR | 10.7 | 2.3 | 220 | 13000 | 6400 | 6600 | Initial monthly sample after installation. |
| VMP-49-30 | 3/21/2013 | 1514 | -0.41 | -0.44 | 5.8 | OVR | 8.2 | 3.1 | 219 | 2100 | 325 | 1775 | |
| VMP-50-5 | 2/26/2013 | 1108 | 0.00 | 0.00 | 0.0 | 0.0 | 1.4 | 19.2 | 0.6 | 2.8 | 0.0 | 2.8 | Initial monthly sample after installation. |
| VMP-50-5 | 3/21/2013 | 1527 | 0.00 | 0.00 | 0.0 | 0.0 | 0.9 | 20.1 | 0.4 | 0.8 | 0.0 | 0.8 | |
| VMP-50-10 | 2/26/2013 | 1114 | -0.02 | 0.00 | 0.0 | 0.0 | 3.9 | 17.0 | 0.4 | 0.3 | 0.0 | 0.3 | Initial monthly sample after installation. |
| VMP-50-10 | 3/21/2013 | 1529 | 0.00 | 0.00 | 0.0 | 0.0 | 3.1 | 18.1 | 0.3 | 0.3 | 0.0 | 0.3 | |
| VMP-50-20 | 2/26/2013 | 1121 | -0.08 | 0.00 | 0.2 | 5.0 | 14.6 | 3.5 | 46.7 | 350 | 93.5 | 257 | Initial monthly sample after installation. |
| VMP-50-20 | 3/21/2013 | 1531 | 0.00 | -0.02 | 0.0 | 0.0 | 12.4 | 6.3 | 31.4 | 86.3 | 38.2 | 48.1 | |
| VMP-50-30 | 2/26/2013 | 1117 | -2.73 | -0.70 | 20.0 | OVR | 6.9 | 15.3 | 566 | 8300 | 1670 | 6630 | Initial monthly sample after installation. |
| VMP-50-30 | 3/21/2013 | 1533 | -1.21 | -1.01 | 16.7 | OVR | 5.4 | 17.1 | 685 | 8200 | 3800 | 4400 | |
| VMP-51-5 | 2/25/2013 | 1440 | 0.02 | 0.02 | 0.0 | 0.0 | 0.4 | 20.6 | 0.2 | 1.2 | 0.0 | 1.2 | Initial monthly sample after installation. |
| VMP-51-5 | 3/21/2013 | 1144 | -0.04 | 0.00 | 0.0 | 0.0 | 0.4 | 20.6 | 0.5 | 2.0 | 0.0 | 2.0 | |
| VMP-51-10 | 2/25/2013 | 1440 | 0.00 | 0.00 | 0.0 | 0.0 | 0.6 | 20.3 | 0.2 | 0.5 | 0.0 | 0.5 | Initial monthly sample after installation. |
| VMP-51-10 | 3/21/2013 | 1154 | 0.00 | 0.00 | 0.0 | 0.0 | 0.4 | 20.6 | 0.5 | 1.6 | 0.0 | 1.6 | |
| VMP-51-20 | 2/25/2013 | 1445 | 0.10 | 0.11 | 0.0 | 0.0 | 2.9 | 19.2 | 0.3 | 0.5 | 0.0 | 0.5 | Initial monthly sample after installation. |
| VMP-51-20 | 3/21/2013 | 1154 | -0.18 | -0.17 | 0.0 | 0.0 | 2.0 | 19.7 | 0.6 | 0.5 | 0.0 | 0.5 | |
| VMP-51-30 | 2/25/2013 | 1445 | 0.10 | 0.09 | 0.0 | 0.0 | 3.5 | 18.5 | 0.3 | 0.9 | 0.0 | 0.9 | Initial monthly sample after installation. |
| VMP-51-30 | 3/21/2013 | 1159 | -0.16 | -0.17 | 0.0 | 0.0 | 3.1 | 18.8 | 0.7 | 0.7 | 0.0 | 0.7 | |
| VMP-52-5 | 2/25/2013 | 1420 | 0.00 | -0.02 | 0.0 | 0.0 | 1.1 | 18.9 | 0.4 | 0.6 | 0.0 | 0.6 | Initial monthly sample after installation. |
| VMP-52-5 | 3/21/2013 | 1524 | 0.00 | 0.00 | 0.0 | 0.0 | 0.8 | 18.5 | 0.5 | 1.4 | 0.0 | 1.4 | |
| VMP-52-10 | 2/25/2013 | 1420 | 0.05 | 0.02 | 0.0 | 0.0 | 1.8 | 17.3 | 0.4 | 2.5 | 0.0 | 2.5 | Initial monthly sample after installation. |
| VMP-52-10 | 3/21/2013 | 1531 | 0.03 | 0.00 | 0.0 | 0.0 | 1.5 | 18.6 | 0.6 | 1.2 | 0.0 | 1.2 | |
| VMP-52-20 | 2/25/2013 | 1425 | 0.27 | 0.05 | 0.0 | 0.0 | 5.6 | 13.6 | 0.6 | 3.6 | 0.0 | 3.6 | Initial monthly sample after installation. |
| VMP-52-20 | 3/21/2013 | 1541 | -0.03 | -0.05 | 0.0 | 0.0 | 5.0 | 15.4 | 0.6 | 2.1 | 0.0 | 2.1 | |
| VMP-52-30 | 2/25/2013 | 1425 | 0.32 | 0.48 | 0.0 | 0.0 | 6.0 | 13.0 | 0.7 | 6.1 | 5.7 | 0.4 | Initial monthly sample after installation. |
| VMP-52-30 | 3/21/2013 | 1546 | -0.03 | -0.17 | 0.0 | 0.0 | 6.4 | 13.4 | 0.9 | 4.1 | 0.0 | 4.1 | |

SEE LAST PAGE OF TABLE FOR NOTES

**TABLE 10**
**SVE SYSTEM MONTHLY MONITORING - VMP SAMPLING DATA**

| Sample ID | Date | Initial Reading Time (24-Hour) | Vacuum/Pressure | | Fixed Gases | | | | Soil Vapor Concentrations | | | | Comments |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | Initial Reading (Inches of $H_2O$) | Stabilized Reading (Inches of $H_2O$) | CH4 (%) | LEL (%) | $CO_2$ (%) | $O_2$ (%) | PID (ppmv) | THC (ppmv) | CH4 (ppmv) | PHC (ppmv) | |
| VMP-53-5 | 2/25/2013 | 1355 | 0.00 | 0.00 | 0.0 | 0.0 | 0.4 | 20.6 | 0.4 | 0.5 | 0.0 | 0.5 | Initial monthly sample after installation. |
| VMP-53-5 | 3/21/2013 | 1449 | 0.00 | 0.00 | 0.0 | 0.0 | 0.4 | 20.6 | 0.5 | 0.8 | 0.0 | 0.8 | |
| VMP-53-10 | 2/25/2013 | 1355 | -0.44 | 0.11 | 0.0 | 0.0 | 0.5 | 20.5 | 0.4 | 0.7 | 0.0 | 0.7 | Initial monthly sample after installation. |
| VMP-53-10 | 3/21/2013 | 1453 | 0.00 | 0.00 | 0.0 | 0.0 | 0.4 | 20.6 | 0.6 | 1.1 | 0.0 | 1.1 | |
| VMP-53-20 | 2/25/2013 | 1400 | 0.05 | 0.08 | 0.0 | 0.0 | 1.6 | 19.8 | 0.4 | 1.1 | 0.0 | 1.1 | Initial monthly sample after installation. |
| VMP-53-20 | 3/21/2013 | 1459 | 0.00 | 0.00 | 0.0 | 0.0 | 1.1 | 20.2 | 0.6 | 0.4 | 0.0 | 0.4 | |
| VMP-53-30 | 2/25/2013 | 1400 | -0.66 | 0.25 | 0.0 | 0.0 | 3.2 | 18.6 | 0.4 | 0.7 | 0.0 | 0.7 | Initial monthly sample after installation. |
| VMP-53-30 | 3/21/2013 | 1503 | 0.00 | 0.00 | 0.0 | 0.0 | 2.8 | 19.1 | 0.5 | 0.4 | 0.0 | 0.4 | |
| VMP-54-5 | 2/25/2013 | 1335 | -0.12 | -0.19 | 0.0 | 0.0 | 1.7 | 18.7 | 0.4 | 0.9 | 0.0 | 0.9 | Initial monthly sample after installation. |
| VMP-54-5 | 3/21/2013 | 1414 | 0.00 | 0.03 | 0.0 | 0.0 | 2.0 | 18.8 | 0.5 | 0.3 | 0.0 | 0.3 | |
| VMP-54-10 | 2/25/2013 | 1340 | 0.02 | -0.01 | 0.0 | 0.0 | 2.8 | 17.5 | 0.5 | 1.5 | 0.0 | 1.5 | Initial monthly sample after installation. |
| VMP-54-10 | 3/21/2013 | 1418 | 0.00 | 0.04 | 0.0 | 0.0 | 2.9 | 17.7 | 0.6 | 0.6 | 0.0 | 0.6 | |
| VMP-54-20 | 2/25/2013 | 1335 | 0.02 | 0.02 | 0.0 | 0.0 | 3.5 | 16.6 | 0.5 | 0.6 | 0.0 | 0.6 | Initial monthly sample after installation. |
| VMP-54-20 | 3/21/2013 | 1423 | 0.05 | 0.07 | 0.0 | 0.0 | 3.3 | 16.9 | 0.6 | 0.7 | 0.0 | 0.7 | |
| VMP-54-30 | 2/25/2013 | 1340 | 0.04 | 0.03 | 0.0 | 0.0 | 4.9 | 14.6 | 0.5 | 1.3 | 0.0 | 1.3 | Initial monthly sample after installation. |
| VMP-54-30 | 3/21/2013 | 1427 | 0.07 | 0.06 | 0.0 | 0.0 | 4.8 | 15.2 | 0.6 | 0.6 | 0.0 | 0.6 | |
| VMP-55-5 | 3/21/2013 | NM | NM | NM | NM | NM | NM | NM | NM | NM | NM | NM | Screen submerged. |
| VMP-55-10 | 3/21/2013 | NM | NM | NM | NM | NM | NM | NM | NM | NM | NM | NM | Screen submerged. |
| VMP-55-20 | 3/21/2013 | 1343 | 0.33 | 0.40 | OVR | OVR | 20.9 | 1.1 | 25.5 | 252000 | 206000 | 46000 | Initial monthly sample after installation. |
| VMP-55-30 | 3/21/2013 | NM | NM | NM | NM | NM | NM | NM | NM | NM | NM | NM | Screen submerged. |

Notes:
1) NM = Not Measured, PID - Photo Ionization Detector; THC = Total Hydrocarbon Concentration; PHC = Petroleum Hydrocarbon Concentration;
OVR = Over-range; ppmv = Parts Per Million By Volume.

SEE LAST PAGE OF TABLE FOR NOTES

**TABLE 11**
**SVE SYSTEM HEADER AND EXHAUST ANALYTICAL DATA**

| Location | Sample ID | Sample Date | Acetone | | | Allyl chloride (3-Chloropropene) | | | alpha-Chlorotoluene | | | Benzene | | | Bromodichloromethane | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | Result (mg/m3) | Lab Qualifier | URS Qualifier | Result (mg/m3) | Lab Qualifier | URS Qualifier | Result (mg/m3) | Lab Qualifier | URS Qualifier | Result (mg/m3) | Lab Qualifier | URS Qualifier | Result (mg/m3) | Lab Qualifier | URS Qualifier |
| SVE Public Works Header | PWHeader-121912 | 12/19/2012 | 7 | U | | 9.3 | U | | 3.8 | U | | 700 | | | 5 | U | |
| SVE Public Works Header | PWHeader-SVE-01162013 | 1/16/2013 | 14 | U | | 18 | U | | 7.7 | U | | 1200 | | | 9.9 | U | |
| SVE Public Works Header | PWHeader-SVE-02202013 | 2/20/2013 | 13 | U | | 18 | U | | 7.3 | U | | 1300 | | | 9.4 | U | |
| SVE Public Works Header | PWHeader-SVE-03012013 | 3/1/2013 | 14 | J | | 36 | U | | 15 | U | | 1600 | | | 19 | U | |
| SVE Refinery Header | HEADER-SVE-020912 | 2/9/2012 | 150 | U | | 200 | U | | 83 | U | | 130 | | | 110 | U | |
| SVE Refinery Header | HEADER-SVE-021712 | 2/17/2012 | 80 | U | | 100 | U | | 170 | U | | 170 | | | 56 | U | |
| SVE Refinery Header | HEADER-SVE-030112 | 3/1/2012 | 6.5 | J | | 93 | U | | 150 | U | | 150 | | | 50 | U | |
| SVE Refinery Header | HEADER-SVE-030812 | 3/8/2012 | 36 | U | | 48 | U | | 79 | U | | 120 | | | 26 | U | |
| SVE Refinery Header | HEADER-SVE-032312 | 3/23/2012 | 20 | U | | 26 | U | | 43 | U | | 63 | | | 14 | U | |
| SVE Refinery Header | HEADER-SVE-032812 | 3/28/2012 | 9.5 | U | | 12 | U | | 21 | U | | 61 | | | 6.7 | U | |
| SVE Refinery Header | MainHeader-SVE-113012 | 11/30/2012 | 15 | U | | 19 | U | | 8 | U | | 44 | | | 10 | U | |
| SVE Refinery Header | MainHeader-121912 | 12/19/2012 | 14 | U | | 18 | U | | 7.7 | U | | 81 | | | 10 | U | |
| SVE Refinery Header | MainHeader-SVE-01162013 | 1/16/2013 | 9.4 | J | | 37 | U | | 15 | U | | 110 | | | 20 | U | |
| SVE Refinery Header | MainHeader-SVE-02202013 | 2/20/2013 | 43 | U | | 56 | U | | 23 | U | | 94 | | | 30 | U | |
| SVE Refinery Header | MainHeader-SVE-03012013 | 3/1/2013 | 19 | J | | 73 | U | | 30 | U | | 97 | | | 39 | U | |
| SVE RTO Exhaust | EXH-SVE-013112 | 1/31/2012 | 0.83 | | | 0.87 | U | | 0.12 | J | | 0.53 | | | 0.46 | U | |
| SVE RTO Exhaust | EXH-SVE-020112 | 2/1/2012 | 0.023 | | | 0.014 | U | | 0.006 | J | U | 0.019 | | | 0.0016 | J | |
| SVE RTO Exhaust | EXH-SVE-020212 | 2/2/2012 | 0.027 | | | 0.02 | U | | 0.0083 | U | | 0.081 | | | 0.011 | U | |
| SVE RTO Exhaust | EXH-SVE-020712 | 2/7/2012 | 0.023 | | | 0.011 | U | | 0.0047 | U | | 0.14 | | | 0.0061 | U | |
| SVE RTO Exhaust | EXH-SVE-020912 | 2/9/2012 | 0.064 | | J | 0.074 | U | UJ | 0.031 | U | UJ | 0.48 | | J | 0.0048 | J | J |
| SVE RTO Exhaust | EXH-SVE-021412 | 2/14/2012 | 0.058 | J | | 0.12 | U | | 0.19 | U | | 0.64 | | | 0.063 | U | |
| SVE RTO Exhaust | EXH-SVE-021712 | 2/17/2012 | 0.26 | | J | 0.22 | U | UJ | 0.36 | U | UJ | 3.2 | | J | 0.12 | U | UJ |
| SVE RTO Exhaust | EXH-SVE-022112 | 2/21/2012 | 0.62 | J | | 1.1 | U | | 0.46 | U | | 8.4 | | | 0.6 | U | |
| SVE RTO Exhaust | EXH-SVE-022412 | 2/24/2012 | 0.044 | J | | 0.024 | U | | 0.01 | U | | 0.67 | | | 0.013 | U | |
| SVE RTO Exhaust | EXH-SVE-022712 | 2/27/2012 | 0.12 | | | 0.024 | U | | 0.01 | U | | 1.5 | | | 0.013 | U | |
| SVE RTO Exhaust | EXH-SVE-030112 | 3/1/2012 | 1.2 | U | | 1.6 | U | | 2.6 | U | | 4.4 | | | 0.84 | U | |
| SVE RTO Exhaust | EXH-SVE-032312 | 3/23/2012 | 0.44 | | | 0.034 | U | | 0.014 | U | | 0.34 | | | 0.018 | U | |
| SVE RTO Exhaust | EXH-SVE-04192012 | 4/19/2012 | 0.063 | | | 0.012 | U | | 0.0051 | U | | 0.14 | | | 0.0066 | U | |
| SVE RTO Exhaust | EXH-SVE-05172012 | 5/17/2012 | 0.085 | J | | 0.48 | U | | 0.2 | U | | 1.9 | | | 0.26 | U | |
| SVE RTO Exhaust | EXH-SVE-06212012 | 6/21/2012 | 0.9 | J | | 1.5 | U | | 0.64 | U | | 1.5 | | | 0.82 | U | |
| SVE RTO Exhaust | EXH-SVE-08312012 | 8/31/2012 | 4.4 | | | 0.79 | U | | 0.33 | U | | 1.7 | | | 0.42 | U | |
| SVE RTO Exhaust | EXH-SVE-09282012 | 9/28/2012 | 1.1 | U | | 1.5 | U | | 0.61 | U | | 1.4 | | | 0.79 | U | |
| SVE RTO Exhaust | EXH-SVE-10252012 | 10/25/2012 | 0.3 | J | | 2 | U | | 0.82 | U | | 1.9 | | | 1.1 | U | |
| SVE RTO Exhaust | EXH-SVE-113012 | 11/30/2012 | 0.15 | | | 0.038 | U | | 0.016 | J | U | 0.058 | | | 0.02 | U | |
| SVE RTO Exhaust | EXH-SVE-120312 | 12/3/2012 | 0.19 | J | | 0.4 | U | | 0.16 | U | | 4.9 | | | 0.21 | U | |
| SVE RTO Exhaust | EXH-SVE-120412 | 12/4/2012 | 0.1 | | | 0.019 | U | | 0.008 | J | U | 0.78 | | | 0.01 | U | |
| SVE RTO Exhaust | EXH-SVE-120512 | 12/5/2012 | 0.17 | J | | 0.35 | U | | 0.14 | U | | 4.1 | | | 0.19 | U | |
| SVE RTO Exhaust | EXH-SVE-121012 | 12/10/2012 | 0.041 | J | | 0.16 | U | | 0.067 | U | | 0.52 | | | 0.087 | U | |
| SVE RTO Exhaust | EXH-SVE-121212 | 12/12/2012 | 0.062 | J | | 0.17 | U | | 0.07 | U | | 3.4 | | | 0.09 | U | |
| SVE RTO Exhaust | EXH-SVE-121712 | 12/17/2012 | 0.046 | | | 0.018 | U | | 0.0075 | U | | 0.17 | | | 0.0097 | U | |
| SVE RTO Exhaust | EXH-SVE-121912 | 12/19/2012 | 0.065 | J | | 0.34 | U | | 0.14 | U | | 4.7 | | | 0.18 | U | |
| SVE RTO Exhaust | EXH-SVE-01162013 | 1/16/2013 | 0.014 | J | | 0.018 | U | | 0.0073 | U | | 0.29 | | | 0.0094 | U | |
| SVE RTO Exhaust | EXH-SVE-02202013 | 2/20/2013 | 0.041 | J | | 0.22 | U | | 0.093 | U | | 5.4 | | | 0.12 | U | |
| SVE RTO Exhaust | EXH-SVE-03012013 | 3/1/2013 | 0.15 | J | | 0.44 | U | | 0.18 | U | | 6.6 | | | 0.24 | U | |

SEE LAST PAGE OF TABLE FOR NOTES

**TABLE 11**
**SVE SYSTEM HEADER AND EXHAUST ANALYTICAL DATA**

| Location | Sample ID | Sample Date | Bromoform | | | Bromomethane | | | 1,3-Butadiene | | | Butane | | | 2-Butanone | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | Result (mg/m3) | Lab Qualifier | URS Qualifier | Result (mg/m3) | Lab Qualifier | URS Qualifier | Result (mg/m3) | Lab Qualifier | URS Qualifier | Result (mg/m3) | Lab Qualifier | URS Qualifier | Result (mg/m3) | Lab Qualifier | URS Qualifier |
| SVE Public Works Header | PWHeader-121912 | 12/19/2012 | 7.6 | U | | 2.9 | U | | 1.6 | U | | 590 | | | 8.7 | U | |
| SVE Public Works Header | PWHeader-SVE-01162013 | 1/16/2013 | 15 | U | | 5.7 | U | | 3.3 | U | | 990 | | | 17 | U | |
| SVE Public Works Header | PWHeader-SVE-02202013 | 2/20/2013 | 14 | U | | 5.5 | UJ | UJ | 3.1 | U | | 880 | | | 17 | U | |
| SVE Public Works Header | PWHeader-SVE-03012013 | 3/1/2013 | 30 | U | | 110 | U | | 6.3 | U | | 890 | | | 34 | U | |
| SVE Refinery Header | HEADER-SVE-020912 | 2/9/2012 | 170 | U | | 62 | U | | 36 | U | | 11000 | | | 190 | U | |
| SVE Refinery Header | HEADER-SVE-021712 | 2/17/2012 | 350 | U | | 33 | U | | 18 | U | | 8600 | | | 99 | U | |
| SVE Refinery Header | HEADER-SVE-030112 | 3/1/2012 | 310 | U | | 29 | U | | 16 | U | | 4000 | | | 88 | U | |
| SVE Refinery Header | HEADER-SVE-030812 | 3/8/2012 | 39 | U | | 15 | U | | 8.4 | U | | 2900 | | | 45 | U | |
| SVE Refinery Header | HEADER-SVE-032312 | 3/23/2012 | 21 | U | | 8 | U | | 4.6 | U | | 1800 | | | 24 | U | |
| SVE Refinery Header | HEADER-SVE-032812 | 3/28/2012 | 10 | U | | 3.9 | U | | 2.2 | U | | 1700 | | | 12 | U | |
| SVE Refinery Header | MainHeader-SVE-113012 | 11/30/2012 | 16 | U | | 6 | U | | 3.4 | U | | 1500 | | | 18 | U | |
| SVE Refinery Header | MainHeader-121912 | 12/19/2012 | 15 | U | | 5.8 | U | | 3.3 | U | | 3000 | | | 18 | U | |
| SVE Refinery Header | MainHeader-SVE-01162013 | 1/16/2013 | 31 | U | | 11 | U | | 6.5 | U | | 4200 | | | 35 | U | |
| SVE Refinery Header | MainHeader-SVE-02202013 | 2/20/2013 | 47 | U | | 18 | UJ | UJ | 10 | U | | 3500 | | | 53 | U | |
| SVE Refinery Header | MainHeader-SVE-03012013 | 3/1/2013 | 60 | U | | 220 | U | | 13 | U | | 4400 | | | 68 | U | |
| SVE RTO Exhaust | EXH-SVE-013112 | 1/31/2012 | 0.72 | U | | 0.27 | U | | 0.15 | U | | 34 | | | 0.12 | J | |
| SVE RTO Exhaust | EXH-SVE-020112 | 2/1/2012 | 0.012 | U | | 0.0045 | U | | 0.0025 | U | | 0.15 | | | 0.0039 | J | |
| SVE RTO Exhaust | EXH-SVE-020212 | 2/2/2012 | 0.017 | U | | 0.0062 | U | | 0.0036 | U | | 0.59 | | | 0.0034 | J | |
| SVE RTO Exhaust | EXH-SVE-020712 | 2/7/2012 | 0.0094 | U | | 0.0036 | U | | 0.002 | U | | 0.2 | | | 0.0055 | J | |
| SVE RTO Exhaust | EXH-SVE-020912 | 2/9/2012 | 0.062 | U | UJ | 0.023 | U | UJ | 0.013 | U | UJ | 0.29 | | J | 0.0095 | J | J |
| SVE RTO Exhaust | EXH-SVE-021412 | 2/14/2012 | 0.39 | U | | 0.036 | U | | 0.021 | U | | 11 | | | 0.015 | J | |
| SVE RTO Exhaust | EXH-SVE-021712 | 2/17/2012 | 0.72 | U | UJ | 0.068 | U | UJ | 0.039 | U | UJ | 6.9 | | J | 0.14 | J | J |
| SVE RTO Exhaust | EXH-SVE-022112 | 2/21/2012 | 0.92 | U | | 3.5 | U | | 0.2 | U | | 27 | | | 1 | U | |
| SVE RTO Exhaust | EXH-SVE-022412 | 2/24/2012 | 0.02 | U | | 0.076 | U | | 0.0043 | U | | 0.36 | | | 0.018 | J | |
| SVE RTO Exhaust | EXH-SVE-022712 | 2/27/2012 | 0.02 | U | | 0.076 | U | | 0.0043 | U | | 0.3 | | | 0.089 | | |
| SVE RTO Exhaust | EXH-SVE-030112 | 3/1/2012 | 5.2 | U | | 0.49 | U | | 0.28 | U | | 100 | | | 1.5 | U | |
| SVE RTO Exhaust | EXH-SVE-032312 | 3/23/2012 | 0.028 | U | | 0.1 | U | | 0.0059 | U | | 1.2 | | | 0.29 | | |
| SVE RTO Exhaust | EXH-SVE-04192012 | 4/19/2012 | 0.01 | U | | 0.038 | U | | 0.0022 | U | | 0.32 | | | 0.017 | | |
| SVE RTO Exhaust | EXH-SVE-05172012 | 5/17/2012 | 0.39 | U | | 0.15 | U | | 0.084 | U | | 50 | | | 0.45 | U | |
| SVE RTO Exhaust | EXH-SVE-06212012 | 6/21/2012 | 1.3 | U | | 4.8 | U | | 0.27 | U | | 45 | | | 1.4 | U | |
| SVE RTO Exhaust | EXH-SVE-08312012 | 8/31/2012 | 0.65 | U | | 2.4 | U | | 0.14 | U | | 32 | | | 0.21 | J | |
| SVE RTO Exhaust | EXH-SVE-09282012 | 9/28/2012 | 1.2 | U | | 0.46 | U | | 0.26 | U | | 22 | | | 1.4 | U | |
| SVE RTO Exhaust | EXH-SVE-10252012 | 10/25/2012 | 1.6 | U | | 0.62 | U | | 0.35 | U | | 31 | | | 1.9 | U | |
| SVE RTO Exhaust | EXH-SVE-113012 | 11/30/2012 | 0.031 | U | | 0.014 | J | | 0.0067 | U | | 1.8 | | | 0.095 | | |
| SVE RTO Exhaust | EXH-SVE-120312 | 12/3/2012 | 0.33 | U | | 0.13 | J | | 0.07 | U | | 22 | | | 0.1 | J | |
| SVE RTO Exhaust | EXH-SVE-120412 | 12/4/2012 | 0.016 | U | | 0.06 | J | U | 0.0034 | U | | 0.4 | | | 0.077 | | |
| SVE RTO Exhaust | EXH-SVE-120512 | 12/5/2012 | 0.29 | U | | 0.1 | J | | 0.062 | U | | 12 | | | 0.12 | J | |
| SVE RTO Exhaust | EXH-SVE-121012 | 12/10/2012 | 0.13 | U | | 0.05 | U | | 0.029 | U | | 0.28 | | | 0.15 | U | |
| SVE RTO Exhaust | EXH-SVE-121212 | 12/12/2012 | 0.14 | U | | 0.052 | U | | 0.03 | U | | 16 | | | 0.015 | J | |
| SVE RTO Exhaust | EXH-SVE-121712 | 12/17/2012 | 0.015 | U | | 0.056 | U | | 0.0023 | J | | 0.26 | | | 0.01 | J | |
| SVE RTO Exhaust | EXH-SVE-121912 | 12/19/2012 | 0.28 | U | | 0.1 | U | | 0.06 | U | | 19 | | | 0.32 | U | |
| SVE RTO Exhaust | EXH-SVE-01162013 | 1/16/2013 | 0.014 | U | | 0.055 | U | | 0.0031 | U | | 0.51 | | | 0.0034 | J | |
| SVE RTO Exhaust | EXH-SVE-02202013 | 2/20/2013 | 0.19 | U | | 0.07 | UJ | UJ | 0.04 | U | | 19 | | | 0.21 | U | |
| SVE RTO Exhaust | EXH-SVE-03012013 | 3/1/2013 | 0.37 | U | | 1.4 | U | | 0.078 | U | | 24 | | | 0.42 | U | |

SEE LAST PAGE OF TABLE FOR NOTES

**TABLE 11**
**SVE SYSTEM HEADER AND EXHAUST ANALYTICAL DATA**

| Location | Sample ID | Sample Date | Carbon disulfide | | | Carbon tetrachloride | | | Chlorobenzene | | | Chlorodibromomethane | | | Chloroethane | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | Result (mg/m3) | Lab Qualifier | URS Qualifier | Result (mg/m3) | Lab Qualifier | URS Qualifier | Result (mg/m3) | Lab Qualifier | URS Qualifier | Result (mg/m3) | Lab Qualifier | URS Qualifier | Result (mg/m3) | Lab Qualifier | URS Qualifier |
| SVE Public Works Header | PWHeader-121912 | 12/19/2012 | 2.3 | U | | 4.6 | U | | 3.4 | U | | 6.3 | U | | 7.8 | U | |
| SVE Public Works Header | PWHeader-SVE-01162013 | 1/16/2013 | 4.6 | U | | 9.3 | U | | 6.8 | U | | 13 | U | | 16 | U | |
| SVE Public Works Header | PWHeader-SVE-02202013 | 2/20/2013 | 4.4 | U | | 8.9 | U | | 6.5 | U | | 12 | U | | 15 | U | |
| SVE Public Works Header | PWHeader-SVE-03012013 | 3/1/2013 | 22 | J | | 18 | U | | 13 | U | | 24 | U | | 30 | U | |
| SVE Refinery Header | HEADER-SVE-020912 | 2/9/2012 | 200 | U | | 100 | U | | 74 | U | | 140 | U | | 170 | U | |
| SVE Refinery Header | HEADER-SVE-021712 | 2/17/2012 | 26 | U | | 53 | U | | 39 | U | | 72 | U | | 89 | U | |
| SVE Refinery Header | HEADER-SVE-030112 | 3/1/2012 | 23 | U | | 12 | J | | 34 | U | | 63 | U | | 79 | U | |
| SVE Refinery Header | HEADER-SVE-030812 | 3/8/2012 | 12 | U | | 24 | U | | 18 | U | | 32 | U | | 40 | U | |
| SVE Refinery Header | HEADER-SVE-032312 | 3/23/2012 | 6.4 | U | | 13 | U | | 9.5 | U | | 18 | U | | 22 | U | |
| SVE Refinery Header | HEADER-SVE-032812 | 3/28/2012 | 3.1 | U | | 6.3 | U | | 4.6 | U | | 8.6 | U | | 11 | U | |
| SVE Refinery Header | MainHeader-SVE-113012 | 11/30/2012 | 4.8 | U | | 9.8 | U | | 7.2 | U | | 13 | U | | 16 | U | |
| SVE Refinery Header | MainHeader-121912 | 12/19/2012 | 4.6 | U | | 9.3 | U | | 6.8 | U | | 13 | U | | 16 | U | |
| SVE Refinery Header | MainHeader-SVE-01162013 | 1/16/2013 | 9.2 | U | | 19 | U | | 14 | U | | 25 | U | | 31 | U | |
| SVE Refinery Header | MainHeader-SVE-02202013 | 2/20/2013 | 14 | U | | 28 | U | | 21 | U | | 38 | U | | 48 | U | |
| SVE Refinery Header | MainHeader-SVE-03012013 | 3/1/2013 | 25 | J | | 36 | U | | 27 | U | | 49 | U | | 61 | U | |
| SVE RTO Exhaust | EXH-SVE-013112 | 1/31/2012 | 0.56 | J | | 0.44 | U | | 0.32 | U | | 0.59 | U | | 0.73 | U | |
| SVE RTO Exhaust | EXH-SVE-020112 | 2/1/2012 | 0.014 | U | | 0.0072 | U | | 0.0053 | U | | 0.0098 | U | | 0.012 | U | |
| SVE RTO Exhaust | EXH-SVE-020212 | 2/2/2012 | 0.02 | U | | 0.01 | U | | 0.0074 | U | | 0.014 | U | | 0.017 | U | |
| SVE RTO Exhaust | EXH-SVE-020712 | 2/7/2012 | 0.011 | U | | 0.0058 | U | | 0.0042 | U | | 0.0078 | U | | 0.0096 | U | |
| SVE RTO Exhaust | EXH-SVE-020912 | 2/9/2012 | 0.074 | U | UJ | 0.037 | U | UJ | 0.027 | U | UJ | 0.051 | U | UJ | 0.063 | U | UJ |
| SVE RTO Exhaust | EXH-SVE-021412 | 2/14/2012 | 0.029 | U | | 0.059 | U | | 0.043 | U | | 0.08 | U | | 0.099 | U | |
| SVE RTO Exhaust | EXH-SVE-021712 | 2/17/2012 | 0.054 | U | UJ | 0.11 | U | UJ | 0.08 | U | UJ | 0.15 | U | UJ | 0.18 | U | UJ |
| SVE RTO Exhaust | EXH-SVE-022112 | 2/21/2012 | 0.35 | J | | 0.56 | U | | 0.41 | U | | 0.76 | U | | 0.94 | U | |
| SVE RTO Exhaust | EXH-SVE-022412 | 2/24/2012 | 0.024 | J | U | 0.012 | U | | 0.009 | U | | 0.017 | U | | 0.021 | U | |
| SVE RTO Exhaust | EXH-SVE-022712 | 2/27/2012 | 0.024 | J | U | 0.012 | U | | 0.009 | U | | 0.017 | U | | 0.021 | U | |
| SVE RTO Exhaust | EXH-SVE-030112 | 3/1/2012 | 0.39 | U | | 0.48 | J | | 0.58 | U | | 1.1 | U | | 1.3 | U | |
| SVE RTO Exhaust | EXH-SVE-032312 | 3/23/2012 | 0.033 | U | | 0.017 | U | | 0.012 | U | | 0.023 | U | | 0.028 | U | |
| SVE RTO Exhaust | EXH-SVE-04192012 | 4/19/2012 | 0.012 | J | U | 0.0062 | U | | 0.0045 | U | | 0.0083 | U | | 0.01 | U | |
| SVE RTO Exhaust | EXH-SVE-05172012 | 5/17/2012 | 0.12 | U | | 0.24 | U | | 0.18 | U | | 0.32 | U | | 0.4 | U | |
| SVE RTO Exhaust | EXH-SVE-06212012 | 6/21/2012 | 0.76 | J | | 0.77 | U | | 0.57 | U | | 1 | U | | 1.3 | U | |
| SVE RTO Exhaust | EXH-SVE-08312012 | 8/31/2012 | 1 | | | 0.4 | U | | 0.29 | U | | 0.54 | U | | 0.66 | U | |
| SVE RTO Exhaust | EXH-SVE-09282012 | 9/28/2012 | 0.37 | U | | 0.74 | U | | 0.54 | U | | 1 | U | | 1.2 | U | |
| SVE RTO Exhaust | EXH-SVE-10252012 | 10/25/2012 | 0.5 | U | | 1 | U | | 0.73 | U | | 1.4 | U | | 1.7 | U | |
| SVE RTO Exhaust | EXH-SVE-113012 | 11/30/2012 | 0.015 | J | | 0.019 | U | | 0.014 | U | | 0.026 | U | | 0.032 | U | |
| SVE RTO Exhaust | EXH-SVE-120312 | 12/3/2012 | 0.4 | U | | 0.2 | U | | 0.15 | U | | 0.27 | U | | 0.34 | U | |
| SVE RTO Exhaust | EXH-SVE-120412 | 12/4/2012 | 0.019 | J | U | 0.0098 | U | | 0.0072 | U | | 0.013 | U | | 0.016 | U | |
| SVE RTO Exhaust | EXH-SVE-120512 | 12/5/2012 | 0.35 | U | | 0.18 | U | | 0.13 | U | | 0.24 | U | | 0.3 | U | |
| SVE RTO Exhaust | EXH-SVE-121012 | 12/10/2012 | 0.04 | U | | 0.081 | U | | 0.06 | U | | 0.11 | U | | 0.14 | U | |
| SVE RTO Exhaust | EXH-SVE-121212 | 12/12/2012 | 0.042 | U | | 0.085 | U | | 0.062 | U | | 0.12 | U | | 0.14 | U | |
| SVE RTO Exhaust | EXH-SVE-121712 | 12/17/2012 | 0.018 | U | | 0.0092 | U | | 0.0067 | U | | 0.012 | U | | 0.015 | U | |
| SVE RTO Exhaust | EXH-SVE-121912 | 12/19/2012 | 0.084 | U | | 0.17 | U | | 0.12 | U | | 0.23 | U | | 0.28 | U | |
| SVE RTO Exhaust | EXH-SVE-01162013 | 1/16/2013 | 0.018 | J | U | 0.0089 | U | | 0.0065 | U | | 0.012 | U | | 0.015 | U | |
| SVE RTO Exhaust | EXH-SVE-02202013 | 2/20/2013 | 0.056 | U | | 0.11 | U | | 0.083 | U | | 0.15 | U | | 0.19 | U | |
| SVE RTO Exhaust | EXH-SVE-03012013 | 3/1/2013 | 0.14 | J | | 0.22 | U | | 0.16 | U | | 0.3 | U | | 0.37 | U | |

SEE LAST PAGE OF TABLE FOR NOTES

**TABLE 11**
**SVE SYSTEM HEADER AND EXHAUST ANALYTICAL DATA**

| Location | Sample ID | Sample Date | Chloroform | | | Chloromethane | | | Cyclohexane | | | 1,2-Dibromoethane | | | 1,2-Dichlorobenzene | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | Result (mg/m3) | Lab Qualifier | URS Qualifier | Result (mg/m3) | Lab Qualifier | URS Qualifier | Result (mg/m3) | Lab Qualifier | URS Qualifier | Result (mg/m3) | Lab Qualifier | URS Qualifier | Result (mg/m3) | Lab Qualifier | URS Qualifier |
| SVE Public Works Header | PWHeader-121912 | 12/19/2012 | 3.6 | U | | 6.1 | U | | 30 | | | 5.7 | U | | 4.4 | U | |
| SVE Public Works Header | PWHeader-SVE-01162013 | 1/16/2013 | 7.2 | U | | 12 | U | | 48 | | | 11 | U | | 8.9 | U | |
| SVE Public Works Header | PWHeader-SVE-02202013 | 2/20/2013 | 6.9 | U | | 12 | U | | 64 | | | 11 | U | | 8.5 | U | |
| SVE Public Works Header | PWHeader-SVE-03012013 | 3/1/2013 | 14 | U | | 59 | U | | 60 | | | 22 | U | | 17 | U | |
| SVE Refinery Header | HEADER-SVE-020912 | 2/9/2012 | 79 | U | | 130 | U | | 520 | | | 120 | U | | 97 | U | |
| SVE Refinery Header | HEADER-SVE-021712 | 2/17/2012 | 41 | U | | 69 | U | | 570 | | | 64 | U | | 50 | U | |
| SVE Refinery Header | HEADER-SVE-030112 | 3/1/2012 | 36 | U | | 62 | U | | 660 | | | 57 | U | | 45 | U | |
| SVE Refinery Header | HEADER-SVE-030812 | 3/8/2012 | 19 | U | | 32 | U | | 410 | | | 29 | U | | 23 | U | |
| SVE Refinery Header | HEADER-SVE-032312 | 3/23/2012 | 10 | U | | 17 | U | | 220 | | | 16 | U | | 12 | U | |
| SVE Refinery Header | HEADER-SVE-032812 | 3/28/2012 | 4.9 | U | | 8.3 | U | | 190 | | | 7.7 | U | | 6 | U | |
| SVE Refinery Header | MainHeader-SVE-113012 | 11/30/2012 | 7.6 | U | | 13 | U | | 180 | | | 12 | U | | 9.3 | U | |
| SVE Refinery Header | MainHeader-121912 | 12/19/2012 | 7.2 | U | | 12 | U | | 290 | | | 11 | U | | 8.9 | U | |
| SVE Refinery Header | MainHeader-SVE-01162013 | 1/16/2013 | 14 | U | | 24 | U | | 410 | | | 23 | U | | 18 | U | |
| SVE Refinery Header | MainHeader-SVE-02202013 | 2/20/2013 | 22 | U | | 37 | U | | 380 | | | 35 | U | | 27 | U | |
| SVE Refinery Header | MainHeader-SVE-03012013 | 3/1/2013 | 28 | U | | 120 | U | | 440 | | | 44 | U | | 35 | U | |
| SVE RTO Exhaust | EXH-SVE-013112 | 1/31/2012 | 0.34 | U | | 0.57 | U | | 2.8 | | | 0.12 | J | | 0.1 | J | |
| SVE RTO Exhaust | EXH-SVE-020112 | 2/1/2012 | 0.0056 | U | | 0.0095 | U | | 0.0093 | | | 0.0088 | J | U | 0.0069 | J | U |
| SVE RTO Exhaust | EXH-SVE-020212 | 2/2/2012 | 0.0079 | U | | 0.013 | U | | 0.078 | | | 0.012 | U | | 0.0097 | U | |
| SVE RTO Exhaust | EXH-SVE-020712 | 2/7/2012 | 0.0045 | U | | 0.0076 | U | | 0.038 | | | 0.007 | U | | 0.0055 | U | |
| SVE RTO Exhaust | EXH-SVE-020912 | 2/9/2012 | 0.029 | U | UJ | 0.049 | U | UJ | 0.013 | J | J | 0.046 | U | UJ | 0.036 | U | UJ |
| SVE RTO Exhaust | EXH-SVE-021412 | 2/14/2012 | 0.046 | U | | 0.077 | U | | 1.1 | | | 0.072 | U | | 0.056 | U | |
| SVE RTO Exhaust | EXH-SVE-021712 | 2/17/2012 | 0.085 | U | UJ | 0.14 | U | | 3.5 | | J | 0.13 | U | UJ | 0.1 | U | UJ |
| SVE RTO Exhaust | EXH-SVE-022112 | 2/21/2012 | 0.44 | U | | 1.8 | U | | 22 | | | 0.69 | U | | 0.54 | U | |
| SVE RTO Exhaust | EXH-SVE-022412 | 2/24/2012 | 0.0096 | U | | 0.04 | U | | 0.25 | | | 0.015 | U | | 0.012 | U | |
| SVE RTO Exhaust | EXH-SVE-022712 | 2/27/2012 | 0.0096 | U | | 0.04 | U | | 0.1 | | | 0.015 | U | | 0.012 | U | |
| SVE RTO Exhaust | EXH-SVE-030112 | 3/1/2012 | 0.86 | | | 1 | U | | 13 | | | 0.96 | U | | 0.75 | U | |
| SVE RTO Exhaust | EXH-SVE-032312 | 3/23/2012 | 0.013 | U | | 0.055 | U | | 0.21 | | | 0.02 | U | | 0.016 | U | |
| SVE RTO Exhaust | EXH-SVE-04192012 | 4/19/2012 | 0.0048 | U | | 0.02 | U | | 0.1 | | | 0.0075 | U | | 0.0059 | U | |
| SVE RTO Exhaust | EXH-SVE-05172012 | 5/17/2012 | 0.19 | U | | 0.32 | U | | 3.6 | | | 0.29 | U | | 0.23 | U | |
| SVE RTO Exhaust | EXH-SVE-06212012 | 6/21/2012 | 0.6 | U | | 2.5 | U | | 3.1 | | | 0.94 | U | | 0.74 | U | |
| SVE RTO Exhaust | EXH-SVE-08312012 | 8/31/2012 | 0.31 | U | | 1.3 | U | | 3 | | | 0.48 | U | | 0.38 | U | |
| SVE RTO Exhaust | EXH-SVE-09282012 | 9/28/2012 | 0.58 | U | | 0.97 | U | | 2.2 | | | 0.91 | U | | 0.71 | U | |
| SVE RTO Exhaust | EXH-SVE-10252012 | 10/25/2012 | 0.78 | U | | 1.3 | U | | 2.9 | | | 1.2 | U | | 0.96 | U | |
| SVE RTO Exhaust | EXH-SVE-113012 | 11/30/2012 | 0.015 | U | | 0.062 | U | | 0.13 | | | 0.023 | U | | 0.018 | U | |
| SVE RTO Exhaust | EXH-SVE-120312 | 12/3/2012 | 0.16 | U | | 0.66 | U | | 1.9 | | | 0.24 | U | | 0.19 | U | |
| SVE RTO Exhaust | EXH-SVE-120412 | 12/4/2012 | 0.0076 | U | | 0.032 | U | | 0.11 | | | 0.012 | U | | 0.0093 | U | |
| SVE RTO Exhaust | EXH-SVE-120512 | 12/5/2012 | 0.14 | U | | 0.58 | U | | 1.4 | | | 0.22 | U | | 0.17 | U | |
| SVE RTO Exhaust | EXH-SVE-121012 | 12/10/2012 | 0.063 | U | | 0.11 | U | | 0.08 | | | 0.1 | U | | 0.078 | U | |
| SVE RTO Exhaust | EXH-SVE-121212 | 12/12/2012 | 0.066 | U | | 0.11 | U | | 1.7 | | | 0.1 | U | | 0.081 | U | |
| SVE RTO Exhaust | EXH-SVE-121712 | 12/17/2012 | 0.0071 | U | | 0.03 | U | | 0.034 | | | 0.011 | U | | 0.0087 | U | |
| SVE RTO Exhaust | EXH-SVE-121912 | 12/19/2012 | 0.13 | U | | 0.22 | U | | 2.2 | | | 0.21 | U | | 0.16 | U | |
| SVE RTO Exhaust | EXH-SVE-01162013 | 1/16/2013 | 0.0069 | U | | 0.029 | U | | 0.072 | | | 0.011 | U | | 0.0085 | U | |
| SVE RTO Exhaust | EXH-SVE-02202013 | 2/20/2013 | 0.088 | U | | 0.15 | U | | 2.2 | | | 0.14 | U | | 0.11 | U | |
| SVE RTO Exhaust | EXH-SVE-03012013 | 3/1/2013 | 0.17 | U | | 0.73 | U | | 2.6 | | | 0.27 | U | | 0.21 | U | |

SEE LAST PAGE OF TABLE FOR NOTES

**TABLE 11**
**SVE SYSTEM HEADER AND EXHAUST ANALYTICAL DATA**

| Location | Sample ID | Sample Date | 1,3-Dichlorobenzene | | | 1,4-Dichlorobenzene | | | Dichlorodifluoromethane | | | 1,1-Dichloroethane | | | 1,2-Dichloroethane | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | Result (mg/m3) | Lab Qualifier | URS Qualifier | Result (mg/m3) | Lab Qualifier | URS Qualifier | Result (mg/m3) | Lab Qualifier | URS Qualifier | Result (mg/m3) | Lab Qualifier | URS Qualifier | Result (mg/m3) | Lab Qualifier | URS Qualifier |
| SVE Public Works Header | PWHeader-121912 | 12/19/2012 | 4.4 | U | | 4.4 | U | | 3.6 | U | | 3 | U | | 3 | U | |
| SVE Public Works Header | PWHeader-SVE-01162013 | 1/16/2013 | 8.9 | U | | 8.9 | U | | 7.3 | U | | 6 | U | | 6 | U | |
| SVE Public Works Header | PWHeader-SVE-02202013 | 2/20/2013 | 8.5 | U | | 8.5 | U | | 7 | U | | 5.7 | U | | 5.7 | U | |
| SVE Public Works Header | PWHeader-SVE-03012013 | 3/1/2013 | 17 | U | | 17 | U | | 14 | U | | 12 | U | | 12 | U | |
| SVE Refinery Header | HEADER-SVE-020912 | 2/9/2012 | 97 | U | | 97 | U | | 80 | U | | 65 | U | | 65 | U | |
| SVE Refinery Header | HEADER-SVE-021712 | 2/17/2012 | 50 | U | | 50 | U | | 42 | U | | 34 | U | | 34 | U | |
| SVE Refinery Header | HEADER-SVE-030112 | 3/1/2012 | 45 | U | | 45 | U | | 37 | U | | 30 | U | | 30 | U | |
| SVE Refinery Header | HEADER-SVE-030812 | 3/8/2012 | 23 | U | | 23 | U | | 19 | U | | 15 | U | | 15 | U | |
| SVE Refinery Header | HEADER-SVE-032312 | 3/23/2012 | 12 | U | | 12 | U | | 10 | U | | 8.3 | U | | 8.3 | U | |
| SVE Refinery Header | HEADER-SVE-032812 | 3/28/2012 | 6 | U | | 6 | U | | 5 | U | | 4.1 | U | | 4.1 | U | |
| SVE Refinery Header | MainHeader-SVE-113012 | 11/30/2012 | 9.3 | U | | 9.3 | U | | 7.7 | U | | 6.3 | U | | 6.3 | U | |
| SVE Refinery Header | MainHeader-121912 | 12/19/2012 | 8.9 | U | | 8.9 | U | | 7.3 | U | | 6 | U | | 6 | U | |
| SVE Refinery Header | MainHeader-SVE-01162013 | 1/16/2013 | 18 | U | | 18 | U | | 15 | U | | 12 | U | | 12 | U | |
| SVE Refinery Header | MainHeader-SVE-02202013 | 2/20/2013 | 27 | U | | 27 | U | | 22 | U | | 18 | U | | 18 | U | |
| SVE Refinery Header | MainHeader-SVE-03012013 | 3/1/2013 | 35 | U | | 35 | U | | 29 | U | | 23 | U | | 23 | U | |
| SVE RTO Exhaust | EXH-SVE-013112 | 1/31/2012 | 0.11 | J | | 0.14 | J | | 0.34 | U | | 0.28 | U | | 0.28 | U | |
| SVE RTO Exhaust | EXH-SVE-020112 | 2/1/2012 | 0.0069 | J | U | 0.0069 | J | U | 0.0013 | J | | 0.0046 | U | | 0.0046 | J | U |
| SVE RTO Exhaust | EXH-SVE-020212 | 2/2/2012 | 0.0097 | U | | 0.0097 | J | U | 0.008 | U | | 0.0065 | U | | 0.0065 | U | |
| SVE RTO Exhaust | EXH-SVE-020712 | 2/7/2012 | 0.0055 | U | | 0.0055 | J | U | 0.0045 | U | | 0.0037 | U | | 0.0037 | U | |
| SVE RTO Exhaust | EXH-SVE-020912 | 2/9/2012 | 0.036 | U | UJ | 0.036 | U | UJ | 0.029 | U | UJ | 0.024 | U | UJ | 0.024 | U | UJ |
| SVE RTO Exhaust | EXH-SVE-021412 | 2/14/2012 | 0.056 | U | | 0.056 | U | | 0.046 | U | | 0.038 | U | | 0.038 | U | |
| SVE RTO Exhaust | EXH-SVE-021712 | 2/17/2012 | 0.1 | U | UJ | 0.1 | U | UJ | 0.086 | U | UJ | 0.071 | U | UJ | 0.071 | U | UJ |
| SVE RTO Exhaust | EXH-SVE-022112 | 2/21/2012 | 0.54 | U | | 0.54 | U | | 0.44 | U | | 0.36 | U | | 0.36 | U | |
| SVE RTO Exhaust | EXH-SVE-022412 | 2/24/2012 | 0.012 | U | | 0.012 | U | | 0.0097 | U | | 0.0079 | U | | 0.0079 | U | |
| SVE RTO Exhaust | EXH-SVE-022712 | 2/27/2012 | 0.012 | U | | 0.012 | U | | 0.0097 | U | | 0.0079 | U | | 0.0079 | U | |
| SVE RTO Exhaust | EXH-SVE-030112 | 3/1/2012 | 0.75 | U | | 0.75 | U | | 0.62 | U | | 0.51 | U | | 0.51 | U | |
| SVE RTO Exhaust | EXH-SVE-032312 | 3/23/2012 | 0.016 | U | | 0.016 | U | | 0.013 | U | | 0.011 | U | | 0.011 | U | |
| SVE RTO Exhaust | EXH-SVE-04192012 | 4/19/2012 | 0.0059 | U | | 0.0059 | J | U | 0.0048 | U | | 0.004 | U | | 0.004 | J | U |
| SVE RTO Exhaust | EXH-SVE-05172012 | 5/17/2012 | 0.23 | U | | 0.23 | U | | 0.19 | U | | 0.15 | U | | 0.15 | U | |
| SVE RTO Exhaust | EXH-SVE-06212012 | 6/21/2012 | 0.74 | U | | 0.74 | U | | 0.61 | U | | 0.5 | U | | 0.5 | U | |
| SVE RTO Exhaust | EXH-SVE-08312012 | 8/31/2012 | 0.38 | U | | 0.38 | U | | 0.31 | U | | 0.26 | U | | 0.25 | U | |
| SVE RTO Exhaust | EXH-SVE-09282012 | 9/28/2012 | 0.71 | U | | 0.71 | U | | 0.58 | U | | 0.48 | U | | 0.48 | U | |
| SVE RTO Exhaust | EXH-SVE-10252012 | 10/25/2012 | 0.96 | U | | 0.96 | U | | 0.79 | U | | 0.64 | U | | 0.64 | U | |
| SVE RTO Exhaust | EXH-SVE-113012 | 11/30/2012 | 0.018 | U | | 0.018 | J | U | 0.015 | U | | 0.012 | U | | 0.012 | U | |
| SVE RTO Exhaust | EXH-SVE-120312 | 12/3/2012 | 0.19 | U | | 0.19 | U | | 0.16 | U | | 0.13 | U | | 0.13 | U | |
| SVE RTO Exhaust | EXH-SVE-120412 | 12/4/2012 | 0.0093 | J | U | 0.0093 | J | U | 0.0077 | U | | 0.0063 | U | | 0.0063 | U | |
| SVE RTO Exhaust | EXH-SVE-120512 | 12/5/2012 | 0.17 | U | | 0.17 | U | | 0.14 | U | | 0.11 | U | | 0.11 | U | |
| SVE RTO Exhaust | EXH-SVE-121012 | 12/10/2012 | 0.078 | U | | 0.078 | U | | 0.064 | U | | 0.052 | U | | 0.052 | U | |
| SVE RTO Exhaust | EXH-SVE-121212 | 12/12/2012 | 0.081 | U | | 0.081 | U | | 0.067 | U | | 0.055 | U | | 0.055 | U | |
| SVE RTO Exhaust | EXH-SVE-121712 | 12/17/2012 | 0.0087 | U | | 0.0087 | J | U | 0.0072 | U | | 0.0059 | U | | 0.0059 | U | |
| SVE RTO Exhaust | EXH-SVE-121912 | 12/19/2012 | 0.16 | U | | 0.16 | U | | 0.13 | U | | 0.11 | U | | 0.11 | U | |
| SVE RTO Exhaust | EXH-SVE-01162013 | 1/16/2013 | 0.0085 | J | U | 0.0085 | J | U | 0.007 | U | | 0.0057 | U | | 0.0057 | U | |
| SVE RTO Exhaust | EXH-SVE-02202013 | 2/20/2013 | 0.11 | U | | 0.11 | U | | 0.089 | U | | 0.073 | U | | 0.073 | U | |
| SVE RTO Exhaust | EXH-SVE-03012013 | 3/1/2013 | 0.21 | U | | 0.21 | U | | 0.18 | U | | 0.14 | U | | 0.14 | U | |

SEE LAST PAGE OF TABLE FOR NOTES

**TABLE 11**
**SVE SYSTEM HEADER AND EXHAUST ANALYTICAL DATA**

| Location | Sample ID | Sample Date | 1,1-Dichloroethene | | | cis-1,2-Dichloroethene | | | trans-1,2-Dichloroethene | | | Dichloromethane (Methylene chloride) | | | 1,2-Dichloropropane | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | Result (mg/m3) | Lab Qualifier | URS Qualifier | Result (mg/m3) | Lab Qualifier | URS Qualifier | Result (mg/m3) | Lab Qualifier | URS Qualifier | Result (mg/m3) | Lab Qualifier | URS Qualifier | Result (mg/m3) | Lab Qualifier | URS Qualifier |
| SVE Public Works Header | PWHeader-121912 | 12/19/2012 | 2.9 | U | | 2.9 | U | | 2.9 | U | | 0.91 | J | | 3.4 | U | |
| SVE Public Works Header | PWHeader-SVE-01162013 | 1/16/2013 | 5.9 | U | | 1.6 | J | | 5.9 | U | | 1.6 | J | | 6.8 | U | |
| SVE Public Works Header | PWHeader-SVE-02202013 | 2/20/2013 | 5.6 | U | | 5.6 | U | | 5.6 | U | | 2.2 | J | | 6.5 | U | |
| SVE Public Works Header | PWHeader-SVE-03012013 | 3/1/2013 | 11 | U | | 11 | U | | 11 | U | | 3.3 | J | | 13 | U | |
| SVE Refinery Header | HEADER-SVE-020912 | 2/9/2012 | 64 | U | | 64 | U | | 64 | U | | 56 | U | | 74 | U | |
| SVE Refinery Header | HEADER-SVE-021712 | 2/17/2012 | 33 | U | | 33 | U | | 33 | U | | 8.2 | J | | 39 | U | |
| SVE Refinery Header | HEADER-SVE-030112 | 3/1/2012 | 30 | U | | 30 | U | | 30 | U | | 7.8 | J | | 34 | U | |
| SVE Refinery Header | HEADER-SVE-030812 | 3/8/2012 | 15 | U | | 15 | U | | 15 | U | | 3.2 | J | | 18 | U | |
| SVE Refinery Header | HEADER-SVE-032312 | 3/23/2012 | 8.2 | U | | 8.2 | U | | 8.2 | U | | 7.2 | U | | 9.5 | U | |
| SVE Refinery Header | HEADER-SVE-032812 | 3/28/2012 | 4 | U | | 4 | U | | 4 | U | | 3.5 | U | | 4.6 | U | |
| SVE Refinery Header | MainHeader-SVE-113012 | 11/30/2012 | 6.2 | U | | 6.2 | U | | 6.2 | U | | 5.4 | U | | 7.2 | U | |
| SVE Refinery Header | MainHeader-121912 | 12/19/2012 | 5.9 | U | | 5.9 | U | | 5.9 | U | | 1.3 | J | | 6.9 | U | |
| SVE Refinery Header | MainHeader-SVE-01162013 | 1/16/2013 | 12 | U | | 12 | U | | 12 | U | | 4.6 | J | | 14 | U | |
| SVE Refinery Header | MainHeader-SVE-02202013 | 2/20/2013 | 18 | U | | 18 | U | | 18 | U | | 8.9 | J | | 21 | U | |
| SVE Refinery Header | MainHeader-SVE-03012013 | 3/1/2013 | 23 | U | | 23 | U | | 23 | U | | 5.2 | J | | 27 | U | |
| SVE RTO Exhaust | EXH-SVE-013112 | 1/31/2012 | 0.28 | U | | 0.28 | U | | 0.28 | U | | 0.26 | | | 0.32 | U | |
| SVE RTO Exhaust | EXH-SVE-020112 | 2/1/2012 | 0.0046 | U | | 0.0046 | U | | 0.0046 | U | | 0.004 | J | U | 0.0053 | U | |
| SVE RTO Exhaust | EXH-SVE-020212 | 2/2/2012 | 0.0064 | U | | 0.0064 | U | | 0.0064 | U | | 0.0056 | J | U | 0.0074 | U | |
| SVE RTO Exhaust | EXH-SVE-020712 | 2/7/2012 | 0.0036 | U | | 0.0036 | U | | 0.0036 | U | | 0.0051 | | | 0.0042 | U | |
| SVE RTO Exhaust | EXH-SVE-020912 | 2/9/2012 | 0.024 | U | UJ | 0.024 | U | UJ | 0.024 | U | UJ | 0.0097 | J | J | 0.027 | U | UJ |
| SVE RTO Exhaust | EXH-SVE-021412 | 2/14/2012 | 0.037 | U | | 0.037 | U | | 0.037 | U | | 0.011 | J | | 0.043 | U | |
| SVE RTO Exhaust | EXH-SVE-021712 | 2/17/2012 | 0.069 | U | UJ | 0.069 | U | UJ | 0.069 | U | UJ | 0.061 | U | UJ | 0.081 | U | UJ |
| SVE RTO Exhaust | EXH-SVE-022112 | 2/21/2012 | 0.35 | U | | 0.35 | U | | 0.35 | U | | 3.1 | U | | 0.41 | U | |
| SVE RTO Exhaust | EXH-SVE-022412 | 2/24/2012 | 0.0078 | U | | 0.0078 | U | | 0.0078 | U | | 0.068 | J | U | 0.009 | U | |
| SVE RTO Exhaust | EXH-SVE-022712 | 2/27/2012 | 0.0078 | U | | 0.0078 | U | | 0.0078 | U | | 0.068 | J | U | 0.009 | U | |
| SVE RTO Exhaust | EXH-SVE-030112 | 3/1/2012 | 0.5 | U | | 0.5 | U | | 0.5 | U | | 0.42 | | | 0.58 | U | |
| SVE RTO Exhaust | EXH-SVE-032312 | 3/23/2012 | 0.011 | U | | 0.011 | U | | 0.011 | U | | 0.0038 | J | | 0.012 | U | |
| SVE RTO Exhaust | EXH-SVE-04192012 | 4/19/2012 | 0.0039 | U | | 0.0039 | U | | 0.0039 | U | | 0.0021 | J | | 0.0045 | U | |
| SVE RTO Exhaust | EXH-SVE-05172012 | 5/17/2012 | 0.15 | U | | 0.15 | U | | 0.15 | U | | 0.13 | U | | 0.18 | U | |
| SVE RTO Exhaust | EXH-SVE-06212012 | 6/21/2012 | 0.49 | U | | 0.49 | U | | 0.49 | U | | 0.34 | J | | 0.57 | U | |
| SVE RTO Exhaust | EXH-SVE-08312012 | 8/31/2012 | 0.25 | U | | 0.25 | U | | 0.25 | U | | 0.23 | J | | 0.29 | U | |
| SVE RTO Exhaust | EXH-SVE-09282012 | 9/28/2012 | 0.47 | U | | 0.47 | U | | 0.47 | U | | 0.41 | U | | 0.54 | U | |
| SVE RTO Exhaust | EXH-SVE-10252012 | 10/25/2012 | 0.63 | U | | 0.63 | U | | 0.63 | U | | 0.55 | U | | 0.74 | U | |
| SVE RTO Exhaust | EXH-SVE-113012 | 11/30/2012 | 0.012 | U | | 0.012 | U | | 0.012 | U | | 0.1 | U | | 0.014 | U | |
| SVE RTO Exhaust | EXH-SVE-120312 | 12/3/2012 | 0.13 | U | | 0.13 | U | | 0.13 | U | | 1.1 | U | | 0.15 | U | |
| SVE RTO Exhaust | EXH-SVE-120412 | 12/4/2012 | 0.0062 | U | | 0.0062 | U | | 0.0062 | U | | 0.054 | J | U | 0.0072 | U | |
| SVE RTO Exhaust | EXH-SVE-120512 | 12/5/2012 | 0.11 | U | | 0.11 | U | | 0.11 | U | | 0.98 | U | | 0.13 | U | |
| SVE RTO Exhaust | EXH-SVE-121012 | 12/10/2012 | 0.051 | U | | 0.051 | U | | 0.051 | U | | 0.045 | U | | 0.06 | U | |
| SVE RTO Exhaust | EXH-SVE-121212 | 12/12/2012 | 0.054 | U | | 0.054 | U | | 0.054 | U | | 0.047 | U | | 0.062 | U | |
| SVE RTO Exhaust | EXH-SVE-121712 | 12/17/2012 | 0.0058 | U | | 0.0058 | U | | 0.0058 | U | | 0.05 | J | U | 0.0067 | U | |
| SVE RTO Exhaust | EXH-SVE-121912 | 12/19/2012 | 0.11 | U | | 0.11 | U | | 0.11 | U | | 0.018 | J | | 0.12 | U | |
| SVE RTO Exhaust | EXH-SVE-01162013 | 1/16/2013 | 0.0056 | U | | 0.0056 | U | | 0.0056 | U | | 0.049 | J | U | 0.0065 | U | |
| SVE RTO Exhaust | EXH-SVE-02202013 | 2/20/2013 | 0.072 | U | | 0.072 | U | | 0.072 | U | | 0.03 | J | | 0.083 | U | |
| SVE RTO Exhaust | EXH-SVE-03012013 | 3/1/2013 | 0.14 | U | | 0.14 | U | | 0.14 | U | | 0.027 | J | | 0.16 | U | |

SEE LAST PAGE OF TABLE FOR NOTES

**TABLE 11**
**SVE SYSTEM HEADER AND EXHAUST ANALYTICAL DATA**

| Location | Sample ID | Sample Date | cis-1,3-Dichloropropene | | | trans-1,3-Dichloropropene | | | 1,4-Dioxane | | | Ethanol | | | Ethylbenzene | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | Result (mg/m3) | Lab Qualifier | URS Qualifier | Result (mg/m3) | Lab Qualifier | URS Qualifier | Result (mg/m3) | Lab Qualifier | URS Qualifier | Result (mg/m3) | Lab Qualifier | URS Qualifier | Result (mg/m3) | Lab Qualifier | URS Qualifier |
| SVE Public Works Header | PWHeader-121912 | 12/19/2012 | 3.4 | U | | 3.4 | U | | 11 | U | | 5.6 | U | | 0.79 | J | |
| SVE Public Works Header | PWHeader-SVE-01162013 | 1/16/2013 | 6.7 | U | | 6.7 | U | | 21 | U | | 11 | U | | 6.4 | U | |
| SVE Public Works Header | PWHeader-SVE-02202013 | 2/20/2013 | 6.4 | U | | 6.4 | U | | 20 | U | | 11 | U | | 2.1 | J | |
| SVE Public Works Header | PWHeader-SVE-03012013 | 3/1/2013 | 13 | U | | 13 | U | | 41 | U | | 22 | U | | 3 | J | |
| SVE Refinery Header | HEADER-SVE-020912 | 2/9/2012 | 73 | U | | 73 | U | | 230 | U | | 120 | U | | 70 | U | |
| SVE Refinery Header | HEADER-SVE-021712 | 2/17/2012 | 38 | U | | 38 | U | | 120 | U | | 63 | U | | 6.4 | J | |
| SVE Refinery Header | HEADER-SVE-030112 | 3/1/2012 | 34 | U | | 34 | U | | 110 | U | | 56 | U | | 16 | J | |
| SVE Refinery Header | HEADER-SVE-030812 | 3/8/2012 | 17 | U | | 17 | U | | 55 | U | | 29 | U | | 5.4 | J | |
| SVE Refinery Header | HEADER-SVE-032312 | 3/23/2012 | 9.3 | U | | 9.3 | U | | 30 | U | | 16 | U | | 14 | | |
| SVE Refinery Header | HEADER-SVE-032812 | 3/28/2012 | 4.6 | U | | 4.6 | U | | 14 | U | | 7.6 | U | | 18 | | |
| SVE Refinery Header | MainHeader-SVE-113012 | 11/30/2012 | 7 | U | | 7 | U | | 22 | U | | 12 | U | | 11 | | |
| SVE Refinery Header | MainHeader-121912 | 12/19/2012 | 6.7 | U | | 6.7 | U | | 21 | U | | 11 | U | | 17 | | |
| SVE Refinery Header | MainHeader-SVE-01162013 | 1/16/2013 | 13 | U | | 13 | U | | 43 | U | | 4.2 | J | J | 14 | | |
| SVE Refinery Header | MainHeader-SVE-02202013 | 2/20/2013 | 20 | U | | 20 | U | | 65 | U | | 34 | U | | 22 | | |
| SVE Refinery Header | MainHeader-SVE-03012013 | 3/1/2013 | 26 | U | | 26 | U | | 84 | U | | 44 | U | | 35 | | |
| SVE RTO Exhaust | EXH-SVE-013112 | 1/31/2012 | 0.32 | U | | 0.32 | U | | 1 | U | | 0.28 | J | | 0.15 | J | |
| SVE RTO Exhaust | EXH-SVE-020112 | 2/1/2012 | 0.0052 | U | | 0.0052 | J | U | 0.016 | U | | 0.016 | | | 0.0025 | J | |
| SVE RTO Exhaust | EXH-SVE-020212 | 2/2/2012 | 0.0073 | U | | 0.0073 | U | | 0.023 | U | | 0.019 | | | 0.011 | | |
| SVE RTO Exhaust | EXH-SVE-020712 | 2/7/2012 | 0.0042 | U | | 0.0042 | U | | 0.013 | U | | 0.023 | | | 0.004 | J | |
| SVE RTO Exhaust | EXH-SVE-020912 | 2/9/2012 | 0.027 | U | UJ | 0.027 | U | UJ | 0.086 | U | UJ | 0.084 | | J | 0.026 | U | UJ |
| SVE RTO Exhaust | EXH-SVE-021412 | 2/14/2012 | 0.042 | U | | 0.042 | U | | 0.13 | U | | 0.04 | J | | 0.044 | | |
| SVE RTO Exhaust | EXH-SVE-021712 | 2/17/2012 | 0.079 | U | UJ | 0.079 | U | UJ | 0.25 | U | UJ | 0.56 | | J | 0.21 | | J |
| SVE RTO Exhaust | EXH-SVE-022112 | 2/21/2012 | 0.41 | U | | 0.41 | U | | 1.3 | U | | 0.67 | U | | 3.3 | | |
| SVE RTO Exhaust | EXH-SVE-022412 | 2/24/2012 | 0.0089 | U | | 0.0089 | U | | 0.028 | U | | 0.045 | | | 0.015 | | |
| SVE RTO Exhaust | EXH-SVE-022712 | 2/27/2012 | 0.0089 | U | | 0.0089 | U | | 0.028 | U | | 0.1 | | | 0.0076 | J | |
| SVE RTO Exhaust | EXH-SVE-030112 | 3/1/2012 | 0.57 | U | | 0.57 | U | | 1.8 | U | | 0.94 | U | | 1.1 | | |
| SVE RTO Exhaust | EXH-SVE-032312 | 3/23/2012 | 0.012 | U | | 0.012 | U | | 0.039 | U | | 0.05 | | | 0.016 | | |
| SVE RTO Exhaust | EXH-SVE-04192012 | 4/19/2012 | 0.0044 | U | | 0.0044 | U | | 0.014 | U | | 0.017 | | J | 0.16 | | |
| SVE RTO Exhaust | EXH-SVE-05172012 | 5/17/2012 | 0.17 | U | | 0.17 | U | | 0.55 | U | | 0.29 | U | | 0.17 | | |
| SVE RTO Exhaust | EXH-SVE-06212012 | 6/21/2012 | 0.56 | U | | 0.56 | U | | 1.8 | U | | 0.93 | U | UJ | 0.27 | J | |
| SVE RTO Exhaust | EXH-SVE-08312012 | 8/31/2012 | 0.28 | U | | 0.28 | U | | 0.91 | U | | 0.18 | J | J | 0.42 | | |
| SVE RTO Exhaust | EXH-SVE-09282012 | 9/28/2012 | 0.54 | U | | 0.54 | U | | 1.7 | U | | 0.89 | U | | 0.51 | U | |
| SVE RTO Exhaust | EXH-SVE-10252012 | 10/25/2012 | 0.72 | U | | 0.72 | U | | 2.3 | U | | 1.2 | U | | 0.18 | J | |
| SVE RTO Exhaust | EXH-SVE-113012 | 11/30/2012 | 0.014 | U | | 0.014 | J | U | 0.044 | U | | 0.015 | J | | 0.014 | | |
| SVE RTO Exhaust | EXH-SVE-120312 | 12/3/2012 | 0.14 | U | | 0.14 | U | | 0.46 | U | | 0.24 | U | | 0.049 | J | |
| SVE RTO Exhaust | EXH-SVE-120412 | 12/4/2012 | 0.007 | U | | 0.007 | U | | 0.022 | U | | 0.013 | | | 0.12 | | |
| SVE RTO Exhaust | EXH-SVE-120512 | 12/5/2012 | 0.13 | U | | 0.13 | U | | 0.41 | U | | 0.21 | U | | 0.15 | | |
| SVE RTO Exhaust | EXH-SVE-121012 | 12/10/2012 | 0.059 | U | | 0.059 | U | | 0.19 | U | | 0.098 | U | | 0.052 | J | |
| SVE RTO Exhaust | EXH-SVE-121212 | 12/12/2012 | 0.061 | U | | 0.061 | U | | 0.19 | U | | 0.1 | J | U | 0.12 | | |
| SVE RTO Exhaust | EXH-SVE-121712 | 12/17/2012 | 0.0066 | U | | 0.0066 | U | | 0.021 | U | | 0.027 | | | 0.019 | | |
| SVE RTO Exhaust | EXH-SVE-121912 | 12/19/2012 | 0.12 | U | | 0.12 | U | | 0.39 | U | | 0.2 | U | | 0.21 | | |
| SVE RTO Exhaust | EXH-SVE-01162013 | 1/16/2013 | 0.0064 | U | | 0.0064 | U | | 0.02 | U | | 0.0057 | J | J | 0.0097 | | |
| SVE RTO Exhaust | EXH-SVE-02202013 | 2/20/2013 | 0.082 | U | | 0.082 | U | | 0.26 | U | | 0.14 | U | | 0.1 | | |
| SVE RTO Exhaust | EXH-SVE-03012013 | 3/1/2013 | 0.16 | U | | 0.16 | U | | 0.51 | U | | 0.27 | U | | 0.25 | | |

SEE LAST PAGE OF TABLE FOR NOTES

**TABLE 11**
**SVE SYSTEM HEADER AND EXHAUST ANALYTICAL DATA**

| Location | Sample ID | Sample Date | 4-Ethyltoluene | | | Freon 113 | | | Freon 114 | | | Heptane | | | Hexachlorobutadiene | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | Result (mg/m3) | Lab Qualifier | URS Qualifier | Result (mg/m3) | Lab Qualifier | URS Qualifier | Result (mg/m3) | Lab Qualifier | URS Qualifier | Result (mg/m3) | Lab Qualifier | URS Qualifier | Result (mg/m3) | Lab Qualifier | URS Qualifier |
| SVE Public Works Header | PWHeader-121912 | 12/19/2012 | 3.6 | U | | 5.7 | U | | 5.2 | U | | 19 | | | 32 | U | |
| SVE Public Works Header | PWHeader-SVE-01162013 | 1/16/2013 | 7.3 | U | | 11 | U | | 10 | U | | 30 | | | 63 | U | |
| SVE Public Works Header | PWHeader-SVE-02202013 | 2/20/2013 | 6.9 | U | | 11 | U | | 9.8 | U | | 40 | | | 60 | U | |
| SVE Public Works Header | PWHeader-SVE-03012013 | 3/1/2013 | 14 | U | | 22 | U | | 20 | U | | 40 | | | 120 | U | |
| SVE Refinery Header | HEADER-SVE-020912 | 2/9/2012 | 79 | U | | 120 | U | | 110 | U | | 350 | | | 690 | U | |
| SVE Refinery Header | HEADER-SVE-021712 | 2/17/2012 | 41 | U | | 64 | U | | 59 | U | | 370 | | | 360 | U | |
| SVE Refinery Header | HEADER-SVE-030112 | 3/1/2012 | 7.7 | J | | 57 | U | | 52 | U | | 500 | | | 320 | U | |
| SVE Refinery Header | HEADER-SVE-030812 | 3/8/2012 | 19 | U | | 29 | U | | 27 | U | | 240 | | | 160 | U | |
| SVE Refinery Header | HEADER-SVE-032312 | 3/23/2012 | 2.6 | J | | 16 | U | | 14 | U | | 200 | | | 88 | U | |
| SVE Refinery Header | HEADER-SVE-032812 | 3/28/2012 | 2.7 | J | | 7.7 | U | | 7 | U | | 190 | | | 43 | U | |
| SVE Refinery Header | MainHeader-SVE-113012 | 11/30/2012 | 7.6 | U | | 12 | U | | 11 | U | | 250 | | | 66 | U | |
| SVE Refinery Header | MainHeader-121912 | 12/19/2012 | 7.3 | U | | 11 | U | | 10 | U | | 330 | | | 63 | U | |
| SVE Refinery Header | MainHeader-SVE-01162013 | 1/16/2013 | 14 | U | | 23 | U | | 21 | U | | 420 | | | 130 | U | |
| SVE Refinery Header | MainHeader-SVE-02202013 | 2/20/2013 | 9.3 | J | | 35 | U | | 32 | U | | 490 | | | 190 | U | |
| SVE Refinery Header | MainHeader-SVE-03012013 | 3/1/2013 | 28 | U | | 44 | U | | 40 | U | | 400 | | | 250 | U | |
| SVE RTO Exhaust | EXH-SVE-013112 | 1/31/2012 | 0.34 | U | | 0.53 | U | | 0.48 | U | | 3 | | | 3 | U | |
| SVE RTO Exhaust | EXH-SVE-020112 | 2/1/2012 | 0.0056 | J | U | 0.0088 | U | | 0.008 | U | | 0.0094 | | | 0.049 | U | |
| SVE RTO Exhaust | EXH-SVE-020212 | 2/2/2012 | 0.0036 | J | | 0.012 | U | | 0.011 | U | | 0.067 | | | 0.069 | U | |
| SVE RTO Exhaust | EXH-SVE-020712 | 2/7/2012 | 0.0045 | J | U | 0.007 | U | | 0.0064 | U | | 0.029 | | | 0.039 | U | |
| SVE RTO Exhaust | EXH-SVE-020912 | 2/9/2012 | 0.029 | U | UJ | 0.046 | U | UJ | 0.042 | U | UJ | 0.008 | J | J | 0.25 | U | UJ |
| SVE RTO Exhaust | EXH-SVE-021412 | 2/14/2012 | 0.0064 | J | | 0.072 | U | | 0.065 | U | | 0.91 | | | 0.4 | U | |
| SVE RTO Exhaust | EXH-SVE-021712 | 2/17/2012 | 0.034 | J | J | 0.13 | U | UJ | 0.12 | U | UJ | 1.5 | | J | 0.75 | U | UJ |
| SVE RTO Exhaust | EXH-SVE-022112 | 2/21/2012 | 0.27 | J | | 0.68 | U | | 0.62 | U | | 27 | | | 3.8 | U | |
| SVE RTO Exhaust | EXH-SVE-022412 | 2/24/2012 | 0.0081 | J | | 0.015 | U | | 0.014 | U | | 0.18 | | | 0.084 | U | |
| SVE RTO Exhaust | EXH-SVE-022712 | 2/27/2012 | 0.0025 | J | | 0.015 | U | | 0.014 | U | | 0.12 | | | 0.084 | U | |
| SVE RTO Exhaust | EXH-SVE-030112 | 3/1/2012 | 0.1 | J | | 0.96 | U | | 0.88 | U | | 11 | | | 5.4 | U | |
| SVE RTO Exhaust | EXH-SVE-032312 | 3/23/2012 | 0.0055 | J | | 0.02 | U | | 0.019 | U | | 0.32 | | | 0.11 | U | |
| SVE RTO Exhaust | EXH-SVE-04192012 | 4/19/2012 | 0.094 | | J | 0.0075 | U | | 0.0068 | U | | 0.15 | | | 0.042 | U | |
| SVE RTO Exhaust | EXH-SVE-05172012 | 5/17/2012 | 0.19 | U | | 0.29 | U | | 0.27 | U | | 3.9 | | | 1.6 | U | |
| SVE RTO Exhaust | EXH-SVE-06212012 | 6/21/2012 | 0.6 | U | | 0.94 | U | | 0.86 | U | | 4 | | | 5.2 | U | |
| SVE RTO Exhaust | EXH-SVE-08312012 | 8/31/2012 | 0.087 | J | | 0.48 | U | | 0.44 | U | | 3.4 | | | 2.7 | U | |
| SVE RTO Exhaust | EXH-SVE-09282012 | 9/28/2012 | 0.58 | U | | 0.9 | U | | 0.82 | U | | 2.2 | | | 5 | U | |
| SVE RTO Exhaust | EXH-SVE-10252012 | 10/25/2012 | 0.78 | U | | 1.2 | U | | 1.1 | U | | 2.9 | | | 6.8 | U | |
| SVE RTO Exhaust | EXH-SVE-113012 | 11/30/2012 | 0.0061 | J | | 0.023 | U | | 0.021 | U | | 0.14 | | | 0.13 | U | |
| SVE RTO Exhaust | EXH-SVE-120312 | 12/3/2012 | 0.16 | U | | 0.24 | U | | 0.22 | U | | 2.3 | | | 1.4 | U | |
| SVE RTO Exhaust | EXH-SVE-120412 | 12/4/2012 | 0.022 | | | 0.012 | U | | 0.011 | U | | 0.22 | | | 0.066 | U | |
| SVE RTO Exhaust | EXH-SVE-120512 | 12/5/2012 | 0.14 | U | | 0.22 | U | | 0.2 | U | | 2 | | | 1.2 | U | |
| SVE RTO Exhaust | EXH-SVE-121012 | 12/10/2012 | 0.064 | U | | 0.099 | U | | 0.09 | U | | 0.14 | | | 0.55 | U | |
| SVE RTO Exhaust | EXH-SVE-121212 | 12/12/2012 | 0.066 | U | | 0.1 | U | | 0.094 | U | | 2.1 | | | 0.58 | U | |
| SVE RTO Exhaust | EXH-SVE-121712 | 12/17/2012 | 0.01 | | | 0.011 | U | | 0.01 | U | | 0.044 | | | 0.062 | U | |
| SVE RTO Exhaust | EXH-SVE-121912 | 12/19/2012 | 0.045 | J | | 0.21 | U | | 0.19 | U | | 2.4 | | | 1.2 | U | |
| SVE RTO Exhaust | EXH-SVE-01162013 | 1/16/2013 | 0.002 | J | | 0.011 | U | | 0.0098 | U | | 0.072 | | | 0.06 | U | |
| SVE RTO Exhaust | EXH-SVE-02202013 | 2/20/2013 | 0.089 | U | | 0.14 | U | | 0.13 | U | | 2.8 | | | 0.77 | U | |
| SVE RTO Exhaust | EXH-SVE-03012013 | 3/1/2013 | 0.17 | U | | 0.27 | U | | 0.25 | U | | 2.8 | | | 1.5 | U | |

SEE LAST PAGE OF TABLE FOR NOTES

**TABLE 11**
**SVE SYSTEM HEADER AND EXHAUST ANALYTICAL DATA**

| Location | Sample ID | Sample Date | Hexane | | | 2-Hexanone (Methyl N-Butyl Ketone) | | | Isopentane | | | Isopropylbenzene (Cumene) | | | 4-Methyl-2-pentanone (Methyl Isobutyl Ketone) | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | Result (mg/m3) | Lab Qualifier | URS Qualifier | Result (mg/m3) | Lab Qualifier | URS Qualifier | Result (mg/m3) | Lab Qualifier | URS Qualifier | Result (mg/m3) | Lab Qualifier | URS Qualifier | Result (mg/m3) | Lab Qualifier | URS Qualifier |
| SVE Public Works Header | PWHeader-121912 | 12/19/2012 | 140 | | | 12 | U | | 1400 | | | 3.6 | U | | 3 | U | |
| SVE Public Works Header | PWHeader-SVE-01162013 | 1/16/2013 | 230 | | | 24 | U | | 2300 | | | 7.3 | U | | 6.1 | U | |
| SVE Public Works Header | PWHeader-SVE-02202013 | 2/20/2013 | 260 | | | 23 | U | | 2200 | | | 6.9 | U | | 23 | U | |
| SVE Public Works Header | PWHeader-SVE-03012013 | 3/1/2013 | 260 | | | 47 | U | | 2500 | | | 14 | U | | 12 | U | |
| SVE Refinery Header | HEADER-SVE-020912 | 2/9/2012 | 2200 | | | 260 | U | | 15000 | | | 79 | U | | 66 | U | |
| SVE Refinery Header | HEADER-SVE-021712 | 2/17/2012 | 3600 | | | 140 | U | | 19000 | | | 41 | U | | 34 | U | |
| SVE Refinery Header | HEADER-SVE-030112 | 3/1/2012 | 2000 | | | 120 | U | | 10000 | | | 37 | U | | 30 | U | |
| SVE Refinery Header | HEADER-SVE-030812 | 3/8/2012 | 1100 | | | 62 | U | | 6100 | | | 19 | U | | 16 | U | |
| SVE Refinery Header | HEADER-SVE-032312 | 3/23/2012 | 880 | | | 34 | U | | 3500 | | | 10 | U | | 8.4 | U | |
| SVE Refinery Header | HEADER-SVE-032812 | 3/28/2012 | 760 | | | 16 | U | | 2900 | | | 1.1 | J | | 4.1 | U | |
| SVE Refinery Header | MainHeader-SVE-113012 | 11/30/2012 | 810 | | | 25 | U | | 2100 | | | 7.6 | U | | 6.4 | U | |
| SVE Refinery Header | MainHeader-121912 | 12/19/2012 | 1300 | | | 24 | U | | 4100 | | | 7.3 | U | | 6.1 | U | |
| SVE Refinery Header | MainHeader-SVE-01162013 | 1/16/2013 | 2200 | | | 48 | U | | 6800 | | | 14 | U | | 12 | U | |
| SVE Refinery Header | MainHeader-SVE-02202013 | 2/20/2013 | 2000 | | | 74 | U | | 5200 | | | 22 | U | | 74 | U | |
| SVE Refinery Header | MainHeader-SVE-03012013 | 3/1/2013 | 2300 | | | 95 | U | | 5800 | | | 28 | U | | 24 | U | |
| SVE RTO Exhaust | EXH-SVE-013112 | 1/31/2012 | 11 | | | 1.1 | U | | 61 | | | 0.34 | U | | 0.28 | U | |
| SVE RTO Exhaust | EXH-SVE-020112 | 2/1/2012 | 0.033 | | | 0.019 | U | | 0.21 | | | 0.0011 | J | | 0.0051 | | |
| SVE RTO Exhaust | EXH-SVE-020212 | 2/2/2012 | 0.19 | | | 0.026 | U | | 0.81 | | | 0.0026 | J | | 0.015 | | |
| SVE RTO Exhaust | EXH-SVE-020712 | 2/7/2012 | 0.06 | | | 0.015 | U | | 0.35 | | | 0.0016 | J | | 0.013 | | |
| SVE RTO Exhaust | EXH-SVE-020912 | 2/9/2012 | 0.043 | | J | 0.097 | U | UJ | 0.4 | | J | 0.029 | U | UJ | 0.024 | U | UJ |
| SVE RTO Exhaust | EXH-SVE-021412 | 2/14/2012 | 6 | | | 0.15 | U | | 27 | | | 0.046 | U | | 0.038 | U | |
| SVE RTO Exhaust | EXH-SVE-021712 | 2/17/2012 | 5.8 | | J | 0.29 | U | UJ | 15 | | J | 0.021 | J | J | 0.072 | U | UJ |
| SVE RTO Exhaust | EXH-SVE-022112 | 2/21/2012 | 66 | | | 1.5 | U | | 85 | | | 0.22 | J | | 0.37 | U | |
| SVE RTO Exhaust | EXH-SVE-022412 | 2/24/2012 | 0.43 | | | 0.032 | U | | 1.3 | | | 0.0024 | J | | 0.022 | | |
| SVE RTO Exhaust | EXH-SVE-022712 | 2/27/2012 | 0.31 | | | 0.012 | J | | 0.74 | | | 0.011 | | | 0.054 | | |
| SVE RTO Exhaust | EXH-SVE-030112 | 3/1/2012 | 36 | | | 2 | U | | 240 | | | 0.081 | J | | 0.51 | U | |
| SVE RTO Exhaust | EXH-SVE-032312 | 3/23/2012 | 0.65 | | | 0.046 | | | 2.4 | | | 0.0036 | J | | 0.032 | | |
| SVE RTO Exhaust | EXH-SVE-04192012 | 4/19/2012 | 0.23 | | | 0.016 | U | | 0.54 | | | 0.033 | | | 0.041 | | |
| SVE RTO Exhaust | EXH-SVE-05172012 | 5/17/2012 | 15 | | | 0.62 | U | | 74 | | | 0.19 | U | | 0.16 | U | |
| SVE RTO Exhaust | EXH-SVE-06212012 | 6/21/2012 | 14 | | | 2 | U | | 65 | | | 0.6 | U | | 0.5 | U | |
| SVE RTO Exhaust | EXH-SVE-08312012 | 8/31/2012 | 14 | | | 1 | U | | 56 | | | 0.31 | U | | 0.26 | U | |
| SVE RTO Exhaust | EXH-SVE-09282012 | 9/28/2012 | 10 | | | 1.9 | U | | 43 | | | 0.58 | U | | 0.48 | U | |
| SVE RTO Exhaust | EXH-SVE-10252012 | 10/25/2012 | 13 | | | 2.6 | U | | 55 | | | 0.78 | U | | 0.65 | U | |
| SVE RTO Exhaust | EXH-SVE-113012 | 11/30/2012 | 0.84 | | | 0.012 | J | | 3 | | | 0.015 | U | | 0.012 | U | |
| SVE RTO Exhaust | EXH-SVE-120312 | 12/3/2012 | 12 | | | 0.52 | U | | 35 | | | 0.16 | U | | 0.13 | U | |
| SVE RTO Exhaust | EXH-SVE-120412 | 12/4/2012 | 0.46 | | | 0.013 | J | | 0.74 | | | 0.0094 | | | 0.0018 | J | |
| SVE RTO Exhaust | EXH-SVE-120512 | 12/5/2012 | 7.6 | | | 0.46 | U | | 21 | | | 0.14 | U | | 0.12 | U | |
| SVE RTO Exhaust | EXH-SVE-121012 | 12/10/2012 | 0.29 | | | 0.21 | U | | 0.52 | | | 0.064 | U | | 0.053 | U | |
| SVE RTO Exhaust | EXH-SVE-121212 | 12/12/2012 | 7.9 | | | 0.22 | U | | 27 | | | 0.014 | J | | 0.055 | U | |
| SVE RTO Exhaust | EXH-SVE-121712 | 12/17/2012 | 0.14 | | | 0.024 | U | | 0.41 | | | 0.0081 | | | 0.0061 | | |
| SVE RTO Exhaust | EXH-SVE-121912 | 12/19/2012 | 10 | | | 0.44 | U | UJ | 34 | | | 0.13 | U | | 0.11 | U | |
| SVE RTO Exhaust | EXH-SVE-01162013 | 1/16/2013 | 0.31 | | | 0.023 | U | | 1 | | | 0.0021 | J | | 0.0058 | U | |
| SVE RTO Exhaust | EXH-SVE-02202013 | 2/20/2013 | 11 | | | 0.3 | U | | 31 | | | 0.089 | U | | 0.3 | U | |
| SVE RTO Exhaust | EXH-SVE-03012013 | 3/1/2013 | 12 | | | 0.58 | U | | 36 | | | 0.17 | U | | 0.14 | U | |

SEE LAST PAGE OF TABLE FOR NOTES

**TABLE 11**
**SVE SYSTEM HEADER AND EXHAUST ANALYTICAL DATA**

| Location | Sample ID | Sample Date | Methyl tert-Butyl Ether (MTBE) | | | 2-Propanol | | | n-Propylbenzene | | | Styrene | | | 1,1,2,2-Tetrachloroethane | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | Result (mg/m3) | Lab Qualifier | URS Qualifier | Result (mg/m3) | Lab Qualifier | URS Qualifier | Result (mg/m3) | Lab Qualifier | URS Qualifier | Result (mg/m3) | Lab Qualifier | URS Qualifier | Result (mg/m3) | Lab Qualifier | URS Qualifier |
| SVE Public Works Header | PWHeader-121912 | 12/19/2012 | 2.7 | U | | 7.3 | U | | 3.6 | U | | 3.2 | U | | 5.1 | U | |
| SVE Public Works Header | PWHeader-SVE-01162013 | 1/16/2013 | 5.3 | U | | 14 | U | | 7.3 | U | | 6.3 | U | | 10 | U | |
| SVE Public Works Header | PWHeader-SVE-02202013 | 2/20/2013 | 5.1 | U | | 14 | U | | 6.9 | U | | 6 | U | | 9.7 | U | |
| SVE Public Works Header | PWHeader-SVE-03012013 | 3/1/2013 | 10 | U | | 28 | U | | 14 | U | | 12 | U | | 20 | U | |
| SVE Refinery Header | HEADER-SVE-020912 | 2/9/2012 | 58 | U | | 160 | U | | 79 | U | | 68 | U | | 110 | U | |
| SVE Refinery Header | HEADER-SVE-021712 | 2/17/2012 | 30 | U | | 82 | U | | 41 | U | | 36 | U | | 58 | U | |
| SVE Refinery Header | HEADER-SVE-030112 | 3/1/2012 | 27 | U | | 73 | U | | 37 | U | | 32 | U | | 51 | U | |
| SVE Refinery Header | HEADER-SVE-030812 | 3/8/2012 | 14 | U | | 38 | U | | 19 | U | | 16 | U | | 26 | U | |
| SVE Refinery Header | HEADER-SVE-032312 | 3/23/2012 | 7.4 | U | | 1.3 | J | | 10 | U | | 8.8 | U | | 14 | U | |
| SVE Refinery Header | HEADER-SVE-032812 | 3/28/2012 | 3.6 | U | | 9.9 | U | | 1.5 | J | | 4.3 | U | | 6.9 | U | |
| SVE Refinery Header | MainHeader-SVE-113012 | 11/30/2012 | 5.6 | U | | 15 | U | | 7.6 | U | | 6.6 | U | | 11 | U | |
| SVE Refinery Header | MainHeader-121912 | 12/19/2012 | 0.67 | J | | 14 | U | | 7.3 | U | | 6.3 | U | | 10 | U | |
| SVE Refinery Header | MainHeader-SVE-01162013 | 1/16/2013 | 1.3 | J | | 1.8 | J | | 14 | U | | 13 | U | | 20 | U | |
| SVE Refinery Header | MainHeader-SVE-02202013 | 2/20/2013 | 16 | U | | 3.8 | J | | 22 | U | | 19 | U | | 31 | U | |
| SVE Refinery Header | MainHeader-SVE-03012013 | 3/1/2013 | 21 | U | | 57 | U | | 28 | U | | 25 | U | | 40 | U | |
| SVE RTO Exhaust | EXH-SVE-013112 | 1/31/2012 | 0.25 | U | | 0.24 | J | | 0.048 | J | | 0.3 | U | | 0.48 | U | |
| SVE RTO Exhaust | EXH-SVE-020112 | 2/1/2012 | 0.0041 | U | | 0.0031 | J | | 0.0056 | J | U | 0.0049 | U | | 0.0079 | U | |
| SVE RTO Exhaust | EXH-SVE-020212 | 2/2/2012 | 0.0058 | U | | 0.002 | J | | 0.0032 | J | | 0.0068 | U | | 0.011 | U | |
| SVE RTO Exhaust | EXH-SVE-020712 | 2/7/2012 | 0.0033 | U | | 0.0046 | J | | 0.0014 | J | | 0.0039 | U | | 0.0063 | U | |
| SVE RTO Exhaust | EXH-SVE-020912 | 2/9/2012 | 0.021 | U | UJ | 0.013 | J | J | 0.029 | U | UJ | 0.025 | U | UJ | 0.041 | U | UJ |
| SVE RTO Exhaust | EXH-SVE-021412 | 2/14/2012 | 0.034 | U | | 0.0076 | J | | 0.046 | U | | 0.04 | U | | 0.064 | U | |
| SVE RTO Exhaust | EXH-SVE-021712 | 2/17/2012 | 0.063 | U | UJ | 0.099 | J | J | 0.019 | J | J | 0.074 | U | UJ | 0.12 | U | UJ |
| SVE RTO Exhaust | EXH-SVE-022112 | 2/21/2012 | 0.32 | U | | 0.23 | J | | 0.37 | J | | 0.12 | J | | 0.61 | U | |
| SVE RTO Exhaust | EXH-SVE-022412 | 2/24/2012 | 0.0071 | U | | 0.01 | J | | 0.0016 | J | | 0.0083 | U | | 0.013 | U | |
| SVE RTO Exhaust | EXH-SVE-022712 | 2/27/2012 | 0.0071 | U | | 0.022 | | | 0.0096 | U | | 0.0083 | U | | 0.013 | U | |
| SVE RTO Exhaust | EXH-SVE-030112 | 3/1/2012 | 0.45 | U | | 1.2 | U | | 0.62 | U | | 0.53 | U | | 0.86 | U | |
| SVE RTO Exhaust | EXH-SVE-032312 | 3/23/2012 | 0.0097 | U | | 0.0098 | J | | 0.0026 | J | | 0.011 | U | | 0.018 | U | |
| SVE RTO Exhaust | EXH-SVE-04192012 | 4/19/2012 | 0.0035 | U | | 0.0044 | J | | 0.034 | | | 0.0042 | U | | 0.0067 | U | |
| SVE RTO Exhaust | EXH-SVE-05172012 | 5/17/2012 | 0.14 | U | | 0.38 | U | | 0.19 | U | | 0.16 | U | | 0.26 | U | |
| SVE RTO Exhaust | EXH-SVE-06212012 | 6/21/2012 | 0.44 | U | | 0.26 | J | | 0.6 | U | | 0.12 | J | | 0.84 | U | |
| SVE RTO Exhaust | EXH-SVE-08312012 | 8/31/2012 | 0.23 | U | | 0.18 | J | | 0.046 | J | | 0.094 | J | | 0.43 | U | |
| SVE RTO Exhaust | EXH-SVE-09282012 | 9/28/2012 | 0.42 | U | | 1.2 | U | | 0.58 | U | | 0.5 | U | | 0.81 | U | |
| SVE RTO Exhaust | EXH-SVE-10252012 | 10/25/2012 | 0.58 | U | | 1.6 | U | | 0.78 | U | | 0.68 | U | | 1.1 | U | |
| SVE RTO Exhaust | EXH-SVE-113012 | 11/30/2012 | 0.011 | U | | 0.03 | U | | 0.015 | J | U | 0.013 | U | | 0.021 | U | |
| SVE RTO Exhaust | EXH-SVE-120312 | 12/3/2012 | 0.12 | U | | 0.31 | U | | 0.16 | U | | 0.14 | U | | 0.22 | U | |
| SVE RTO Exhaust | EXH-SVE-120412 | 12/4/2012 | 0.0056 | U | | 0.015 | U | | 0.0066 | J | | 0.0066 | U | | 0.011 | U | |
| SVE RTO Exhaust | EXH-SVE-120512 | 12/5/2012 | 0.1 | U | | 0.28 | U | | 0.14 | U | | 0.12 | U | | 0.19 | U | |
| SVE RTO Exhaust | EXH-SVE-121012 | 12/10/2012 | 0.047 | U | | 0.13 | U | | 0.064 | U | | 0.055 | U | | 0.089 | U | |
| SVE RTO Exhaust | EXH-SVE-121212 | 12/12/2012 | 0.049 | U | | 0.0084 | J | | 0.066 | U | | 0.058 | U | | 0.093 | U | |
| SVE RTO Exhaust | EXH-SVE-121712 | 12/17/2012 | 0.0052 | U | | 0.0076 | J | | 0.0037 | J | | 0.0062 | U | | 0.01 | U | |
| SVE RTO Exhaust | EXH-SVE-121912 | 12/19/2012 | 0.097 | U | | 0.15 | J | | 0.13 | U | | 0.12 | U | | 0.18 | U | |
| SVE RTO Exhaust | EXH-SVE-01162013 | 1/16/2013 | 0.0051 | U | | 0.0017 | J | | 0.0015 | J | | 0.006 | U | | 0.0097 | U | |
| SVE RTO Exhaust | EXH-SVE-02202013 | 2/20/2013 | 0.065 | U | | 0.18 | U | | 0.089 | U | | 0.077 | U | | 0.12 | U | |
| SVE RTO Exhaust | EXH-SVE-03012013 | 3/1/2013 | 0.13 | U | | 0.35 | U | | 0.019 | J | | 0.15 | U | | 0.24 | U | |

SEE LAST PAGE OF TABLE FOR NOTES

**TABLE 11**
**SVE SYSTEM HEADER AND EXHAUST ANALYTICAL DATA**

| Location | Sample ID | Sample Date | Tetrachloroethene | | | Tetrahydrofuran | | | Toluene | | | 1,2,4-Trichlorobenzene | | | 1,1,1-Trichloroethane (Methyl chloroform) | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | Result (mg/m3) | Lab Qualifier | URS Qualifier | Result (mg/m3) | Lab Qualifier | URS Qualifier | Result (mg/m3) | Lab Qualifier | URS Qualifier | Result (mg/m3) | Lab Qualifier | URS Qualifier | Result (mg/m3) | Lab Qualifier | URS Qualifier |
| SVE Public Works Header | PWHeader-121912 | 12/19/2012 | 0.81 | J | | 2.2 | U | | 1.1 | J | | 22 | U | | 4 | U | |
| SVE Public Works Header | PWHeader-SVE-01162013 | 1/16/2013 | 24 | | | 4.4 | U | | 1.2 | J | | 44 | U | | 8.1 | U | |
| SVE Public Works Header | PWHeader-SVE-02202013 | 2/20/2013 | 9.6 | U | | 4.2 | U | | 7.4 | | | 42 | U | | 7.7 | U | |
| SVE Public Works Header | PWHeader-SVE-03012013 | 3/1/2013 | 19 | U | | 8.4 | U | | 3.3 | J | | 5.6 | J | | 16 | U | |
| SVE Refinery Header | HEADER-SVE-020912 | 2/9/2012 | 110 | U | | 47 | U | | 140 | | | 480 | U | | 88 | U | |
| SVE Refinery Header | HEADER-SVE-021712 | 2/17/2012 | 57 | U | | 25 | U | | 40 | | | 250 | U | | 46 | U | |
| SVE Refinery Header | HEADER-SVE-030112 | 3/1/2012 | 50 | U | | 22 | U | | 46 | | | 220 | U | | 41 | U | |
| SVE Refinery Header | HEADER-SVE-030812 | 3/8/2012 | 14 | J | | 11 | U | | 14 | J | | 110 | U | | 21 | U | |
| SVE Refinery Header | HEADER-SVE-032312 | 3/23/2012 | 14 | U | | 6.1 | U | | 46 | | | 61 | U | | 11 | U | |
| SVE Refinery Header | HEADER-SVE-032812 | 3/28/2012 | 0.96 | J | | 3 | U | | 60 | | | 30 | U | | 5.5 | U | |
| SVE Refinery Header | MainHeader-SVE-113012 | 11/30/2012 | 10 | U | | 4.6 | U | | 52 | | | 46 | U | | 8.5 | U | |
| SVE Refinery Header | MainHeader-121912 | 12/19/2012 | 1.1 | J | | 4.4 | U | | 76 | | | 44 | U | | 8.1 | U | |
| SVE Refinery Header | MainHeader-SVE-01162013 | 1/16/2013 | 20 | U | | 8.7 | U | | 100 | | | 88 | U | | 16 | U | |
| SVE Refinery Header | MainHeader-SVE-02202013 | 2/20/2013 | 31 | U | | 13 | U | | 120 | | | 130 | U | | 25 | U | |
| SVE Refinery Header | MainHeader-SVE-03012013 | 3/1/2013 | 39 | U | | 17 | U | | 97 | | | 170 | U | | 32 | U | |
| SVE RTO Exhaust | EXH-SVE-013112 | 1/31/2012 | 0.47 | U | | 0.2 | U | | 0.57 | | | 0.4 | J | | 0.38 | U | |
| SVE RTO Exhaust | EXH-SVE-020112 | 2/1/2012 | 0.0078 | U | | 0.0034 | U | | 0.0047 | | | 0.034 | J | U | 0.0063 | U | |
| SVE RTO Exhaust | EXH-SVE-020212 | 2/2/2012 | 0.011 | U | | 0.0047 | U | | 0.014 | | | 0.048 | U | | 0.0088 | U | |
| SVE RTO Exhaust | EXH-SVE-020712 | 2/7/2012 | 0.0062 | U | | 0.0027 | U | | 0.006 | | | 0.027 | U | | 0.005 | U | |
| SVE RTO Exhaust | EXH-SVE-020912 | 2/9/2012 | 0.04 | U | UJ | 0.018 | U | UJ | 0.0073 | J | J | 0.18 | U | UJ | 0.032 | U | UJ |
| SVE RTO Exhaust | EXH-SVE-021412 | 2/14/2012 | 0.063 | U | | 0.028 | U | | 0.13 | | | 0.28 | U | | 0.051 | U | |
| SVE RTO Exhaust | EXH-SVE-021712 | 2/17/2012 | 0.12 | U | UJ | 0.052 | U | UJ | 0.22 | | J | 0.52 | U | UJ | 0.095 | U | UJ |
| SVE RTO Exhaust | EXH-SVE-022112 | 2/21/2012 | 0.61 | U | | 0.26 | U | | 7 | | | 2.6 | U | | 0.49 | U | |
| SVE RTO Exhaust | EXH-SVE-022412 | 2/24/2012 | 0.013 | U | | 0.0058 | U | | 0.057 | | | 0.058 | U | | 0.011 | U | |
| SVE RTO Exhaust | EXH-SVE-022712 | 2/27/2012 | 0.013 | U | | 0.0058 | U | | 0.022 | | | 0.058 | U | | 0.011 | U | |
| SVE RTO Exhaust | EXH-SVE-030112 | 3/1/2012 | 0.85 | U | | 0.37 | U | | 1.9 | | | 3.7 | U | | 0.68 | U | |
| SVE RTO Exhaust | EXH-SVE-032312 | 3/23/2012 | 0.018 | U | | 0.0079 | U | | 0.036 | | | 0.08 | U | | 0.015 | U | |
| SVE RTO Exhaust | EXH-SVE-04192012 | 4/19/2012 | 0.0066 | U | | 0.0029 | U | | 0.19 | | | 0.029 | J | U | 0.0053 | U | |
| SVE RTO Exhaust | EXH-SVE-05172012 | 5/17/2012 | 0.26 | U | | 0.11 | U | | 0.84 | | | 1.1 | U | | 0.21 | U | |
| SVE RTO Exhaust | EXH-SVE-06212012 | 6/21/2012 | 0.83 | U | | 0.36 | U | | 0.92 | | | 3.6 | U | | 0.67 | U | |
| SVE RTO Exhaust | EXH-SVE-08312012 | 8/31/2012 | 0.43 | U | | 0.18 | U | | 2.7 | | | 1.9 | U | | 0.34 | U | |
| SVE RTO Exhaust | EXH-SVE-09282012 | 9/28/2012 | 0.8 | U | | 0.35 | U | | 0.4 | J | | 3.5 | U | | 0.64 | U | |
| SVE RTO Exhaust | EXH-SVE-10252012 | 10/25/2012 | 1.1 | U | | 0.47 | U | | 0.79 | | | 4.7 | U | | 0.87 | U | |
| SVE RTO Exhaust | EXH-SVE-113012 | 11/30/2012 | 0.02 | U | | 0.0089 | U | | 0.025 | | | 0.09 | U | | 0.016 | U | |
| SVE RTO Exhaust | EXH-SVE-120312 | 12/3/2012 | 0.22 | U | | 0.094 | U | | 0.3 | | | 0.95 | U | | 0.17 | U | |
| SVE RTO Exhaust | EXH-SVE-120412 | 12/4/2012 | 0.01 | U | | 0.0046 | U | | 0.18 | | | 0.046 | U | | 0.0085 | U | |
| SVE RTO Exhaust | EXH-SVE-120512 | 12/5/2012 | 0.19 | U | | 0.083 | U | | 0.51 | | | 0.84 | U | | 0.15 | U | |
| SVE RTO Exhaust | EXH-SVE-121012 | 12/10/2012 | 0.088 | U | | 0.038 | U | | 0.15 | | | 0.38 | U | | 0.071 | U | |
| SVE RTO Exhaust | EXH-SVE-121212 | 12/12/2012 | 0.092 | U | | 0.04 | U | | 0.41 | | | 0.4 | U | | 0.074 | U | |
| SVE RTO Exhaust | EXH-SVE-121712 | 12/17/2012 | 0.0099 | U | | 0.0043 | U | | 0.026 | | | 0.043 | U | | 0.0079 | U | |
| SVE RTO Exhaust | EXH-SVE-121912 | 12/19/2012 | 0.18 | U | | 0.08 | U | | 0.63 | | | 0.8 | U | | 0.15 | U | |
| SVE RTO Exhaust | EXH-SVE-01162013 | 1/16/2013 | 0.0052 | J | | 0.0042 | U | | 0.029 | | | 0.042 | J | U | 0.0077 | U | |
| SVE RTO Exhaust | EXH-SVE-02202013 | 2/20/2013 | 0.12 | U | | 0.053 | U | | 0.58 | | | 0.54 | U | | 0.098 | U | |
| SVE RTO Exhaust | EXH-SVE-03012013 | 3/1/2013 | 0.059 | J | | 0.1 | U | | 0.67 | | | 1 | U | | 0.19 | U | |

SEE LAST PAGE OF TABLE FOR NOTES

**TABLE 11**
**SVE SYSTEM HEADER AND EXHAUST ANALYTICAL DATA**

| Location | Sample ID | Sample Date | 1,1,2-Trichloroethane | | | Trichloroethene | | | Trichlorofluoromethane | | | 1,2,4-Trimethylbenzene | | | 1,3,5-Trimethylbenzene | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | Result (mg/m3) | Lab Qualifier | URS Qualifier | Result (mg/m3) | Lab Qualifier | URS Qualifier | Result (mg/m3) | Lab Qualifier | URS Qualifier | Result (mg/m3) | Lab Qualifier | URS Qualifier | Result (mg/m3) | Lab Qualifier | URS Qualifier |
| SVE Public Works Header | PWHeader-121912 | 12/19/2012 | 4 | U | | 0.37 | J | | 4.2 | U | | 3.6 | U | | 3.6 | U | |
| SVE Public Works Header | PWHeader-SVE-01162013 | 1/16/2013 | 8.1 | U | | 1.9 | J | | 8.3 | U | | 7.3 | U | | 7.3 | U | |
| SVE Public Works Header | PWHeader-SVE-02202013 | 2/20/2013 | 7.7 | U | | 7.6 | U | | 7.9 | U | | 1.6 | J | | 6.9 | U | |
| SVE Public Works Header | PWHeader-SVE-03012013 | 3/1/2013 | 16 | U | | 15 | U | | 16 | U | | 14 | U | | 14 | U | |
| SVE Refinery Header | HEADER-SVE-020912 | 2/9/2012 | 88 | U | | 86 | U | | 90 | U | | 79 | U | | 79 | U | |
| SVE Refinery Header | HEADER-SVE-021712 | 2/17/2012 | 46 | U | | 45 | U | | 47 | U | | 160 | U | | 41 | U | |
| SVE Refinery Header | HEADER-SVE-030112 | 3/1/2012 | 41 | U | | 40 | U | | 6.8 | J | | 13 | J | | 37 | U | |
| SVE Refinery Header | HEADER-SVE-030812 | 3/8/2012 | 21 | U | | 20 | U | | 21 | U | | 19 | U | | 19 | U | |
| SVE Refinery Header | HEADER-SVE-032312 | 3/23/2012 | 11 | U | | 11 | U | | 12 | U | | 1.8 | J | | 10 | U | |
| SVE Refinery Header | HEADER-SVE-032812 | 3/28/2012 | 5.5 | U | | 5.4 | U | | 5.6 | U | | 1.7 | J | | 0.92 | J | |
| SVE Refinery Header | MainHeader-SVE-113012 | 11/30/2012 | 8.5 | U | | 16 | | | 8.7 | U | | 7.6 | U | | 7.6 | U | |
| SVE Refinery Header | MainHeader-121912 | 12/19/2012 | 8.1 | U | | 8 | U | | 8.3 | U | | 7.3 | U | | 7.3 | U | |
| SVE Refinery Header | MainHeader-SVE-01162013 | 1/16/2013 | 16 | U | | 16 | U | | 17 | U | | 14 | U | | 14 | U | |
| SVE Refinery Header | MainHeader-SVE-02202013 | 2/20/2013 | 25 | U | | 24 | U | | 25 | U | | 6.5 | J | | 22 | U | |
| SVE Refinery Header | MainHeader-SVE-03012013 | 3/1/2013 | 32 | U | | 31 | U | | 32 | U | | 28 | U | | 28 | U | |
| SVE RTO Exhaust | EXH-SVE-013112 | 1/31/2012 | 0.38 | U | | 0.37 | U | | 0.39 | U | | 0.1 | J | | 0.057 | J | |
| SVE RTO Exhaust | EXH-SVE-020112 | 2/1/2012 | 0.0063 | U | | 0.0062 | J | U | 0.0065 | U | | 0.0056 | J | U | 0.0056 | J | U |
| SVE RTO Exhaust | EXH-SVE-020212 | 2/2/2012 | 0.0088 | U | | 0.0086 | U | | 0.009 | U | | 0.0051 | J | | 0.0079 | J | U |
| SVE RTO Exhaust | EXH-SVE-020712 | 2/7/2012 | 0.005 | U | | 0.0049 | J | U | 0.0051 | U | | 0.0025 | J | | 0.0045 | J | U |
| SVE RTO Exhaust | EXH-SVE-020912 | 2/9/2012 | 0.032 | U | UJ | 0.032 | U | UJ | 0.033 | U | UJ | 0.029 | U | UJ | 0.029 | U | UJ |
| SVE RTO Exhaust | EXH-SVE-021412 | 2/14/2012 | 0.051 | U | | 0.05 | U | | 0.052 | U | | 0.18 | U | | 0.046 | U | |
| SVE RTO Exhaust | EXH-SVE-021712 | 2/17/2012 | 0.095 | U | UJ | 0.094 | U | UJ | 0.098 | U | UJ | 0.019 | J | J | 0.015 | J | J |
| SVE RTO Exhaust | EXH-SVE-022112 | 2/21/2012 | 0.49 | U | | 0.48 | U | | 0.5 | U | | 0.36 | J | | 0.25 | J | |
| SVE RTO Exhaust | EXH-SVE-022412 | 2/24/2012 | 0.011 | U | | 0.01 | U | | 0.011 | U | | 0.016 | | | 0.0056 | J | |
| SVE RTO Exhaust | EXH-SVE-022712 | 2/27/2012 | 0.011 | U | | 0.01 | U | | 0.011 | U | | 0.0096 | U | | 0.0096 | U | |
| SVE RTO Exhaust | EXH-SVE-030112 | 3/1/2012 | 0.68 | U | | 1 | | | 0.47 | J | | 2.5 | U | | 0.62 | U | |
| SVE RTO Exhaust | EXH-SVE-032312 | 3/23/2012 | 0.015 | U | | 0.014 | U | | 0.015 | U | | 0.0056 | J | | 0.0019 | J | |
| SVE RTO Exhaust | EXH-SVE-04192012 | 4/19/2012 | 0.0053 | U | | 0.009 | | | 0.0055 | U | | 0.084 | | | 0.032 | | |
| SVE RTO Exhaust | EXH-SVE-05172012 | 5/17/2012 | 0.21 | U | | 0.2 | U | | 0.21 | U | | 0.19 | U | | 0.19 | U | |
| SVE RTO Exhaust | EXH-SVE-06212012 | 6/21/2012 | 0.67 | U | | 0.66 | U | | 0.69 | U | | 0.6 | U | | 0.6 | U | |
| SVE RTO Exhaust | EXH-SVE-08312012 | 8/31/2012 | 0.34 | U | | 0.34 | U | | 0.35 | U | | 0.31 | U | | 0.31 | U | |
| SVE RTO Exhaust | EXH-SVE-09282012 | 9/28/2012 | 0.64 | U | | 0.63 | U | | 0.66 | U | | 0.58 | U | | 0.58 | U | |
| SVE RTO Exhaust | EXH-SVE-10252012 | 10/25/2012 | 0.87 | U | | 0.86 | U | | 0.9 | U | | 0.78 | U | | 0.78 | U | |
| SVE RTO Exhaust | EXH-SVE-113012 | 11/30/2012 | 0.016 | U | | 0.016 | U | | 0.017 | U | | 0.005 | J | | 0.015 | U | |
| SVE RTO Exhaust | EXH-SVE-120312 | 12/3/2012 | 0.17 | U | | 0.17 | U | | 0.18 | U | | 0.16 | U | | 0.16 | U | |
| SVE RTO Exhaust | EXH-SVE-120412 | 12/4/2012 | 0.0085 | U | | 0.0084 | U | | 0.0087 | U | | 0.0086 | | | 0.009 | | |
| SVE RTO Exhaust | EXH-SVE-120512 | 12/5/2012 | 0.15 | U | | 0.15 | U | | 0.16 | U | | 0.14 | U | | 0.14 | U | |
| SVE RTO Exhaust | EXH-SVE-121012 | 12/10/2012 | 0.071 | U | | 0.07 | U | | 0.073 | U | | 0.064 | U | | 0.064 | U | |
| SVE RTO Exhaust | EXH-SVE-121212 | 12/12/2012 | 0.074 | U | | 0.072 | U | | 0.076 | U | | 0.066 | U | | 0.066 | U | |
| SVE RTO Exhaust | EXH-SVE-121712 | 12/17/2012 | 0.0079 | U | | 0.0078 | U | | 0.0082 | U | | 0.0089 | | | 0.004 | J | |
| SVE RTO Exhaust | EXH-SVE-121912 | 12/19/2012 | 0.15 | U | | 0.14 | U | | 0.15 | U | | 0.028 | J | | 0.13 | U | |
| SVE RTO Exhaust | EXH-SVE-01162013 | 1/16/2013 | 0.0077 | U | | 0.0076 | U | | 0.0079 | U | | 0.0029 | J | | 0.0013 | J | |
| SVE RTO Exhaust | EXH-SVE-02202013 | 2/20/2013 | 0.098 | U | | 0.097 | U | | 0.1 | U | | 0.089 | U | | 0.089 | U | |
| SVE RTO Exhaust | EXH-SVE-03012013 | 3/1/2013 | 0.19 | U | | 0.19 | U | | 0.2 | U | | 0.17 | U | | 0.17 | U | |

SEE LAST PAGE OF TABLE FOR NOTES

**TABLE 11**
**SVE SYSTEM HEADER AND EXHAUST ANALYTICAL DATA**

| Location | Sample ID | Sample Date | 2,2,4-Trimethylpentane | | | Vinyl chloride | | | m,p-Xylene | | | o-Xylenes | | | TPH (C2-C10) | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | Result (mg/m3) | Lab Qualifier | URS Qualifier | Result (mg/m3) | Lab Qualifier | URS Qualifier | Result (mg/m3) | Lab Qualifier | URS Qualifier | Result (mg/m3) | Lab Qualifier | URS Qualifier | Result (mg/m3) | Lab Qualifier | URS Qualifier |
| SVE Public Works Header | PWHeader-121912 | 12/19/2012 | 120 | | | 1.9 | U | | 0.97 | J | | 3.2 | U | | 12000 | | |
| SVE Public Works Header | PWHeader-SVE-01162013 | 1/16/2013 | 210 | | | 3.8 | U | | 6.4 | U | | 6.4 | U | | 17000 | | |
| SVE Public Works Header | PWHeader-SVE-02202013 | 2/20/2013 | 240 | | | 3.6 | U | | 3.1 | J | | 0.99 | J | | 15000 | | |
| SVE Public Works Header | PWHeader-SVE-03012013 | 3/1/2013 | 260 | | | 7.3 | U | | 3 | J | | 12 | U | | 16000 | | |
| SVE Refinery Header | HEADER-SVE-020912 | 2/9/2012 | 1600 | | | 41 | U | | 70 | U | | 70 | U | | | | |
| SVE Refinery Header | HEADER-SVE-021712 | 2/17/2012 | 1900 | | | 21 | U | | 9.5 | J | | 36 | U | | | | |
| SVE Refinery Header | HEADER-SVE-030112 | 3/1/2012 | 2300 | | | 19 | U | | 36 | | | 8.3 | J | | | | |
| SVE Refinery Header | HEADER-SVE-030812 | 3/8/2012 | 1300 | | | 9.8 | U | | 9.2 | J | | 16 | U | | 70000 | | |
| SVE Refinery Header | HEADER-SVE-032312 | 3/23/2012 | 740 | | | 5.3 | U | | 26 | | | 4.8 | J | | 34000 | | |
| SVE Refinery Header | HEADER-SVE-032812 | 3/28/2012 | 700 | | | 2.6 | U | | 34 | | | 6 | | | 32000 | | |
| SVE Refinery Header | MainHeader-SVE-113012 | 11/30/2012 | 1000 | | | 4 | U | | 24 | | | 4.6 | J | | 30000 | | J |
| SVE Refinery Header | MainHeader-121912 | 12/19/2012 | 1500 | | | 3.8 | U | | 32 | | | 6.9 | | | 54000 | | J |
| SVE Refinery Header | MainHeader-SVE-01162013 | 1/16/2013 | 1800 | | | 7.6 | U | | 24 | | | 4 | J | | 58000 | | J |
| SVE Refinery Header | MainHeader-SVE-02202013 | 2/20/2013 | 2000 | | | 12 | U | | 48 | | | 12 | J | | 54000 | | J |
| SVE Refinery Header | MainHeader-SVE-03012013 | 3/1/2013 | 2200 | | | 15 | U | | 71 | | | 15 | J | | 55000 | | J |
| SVE RTO Exhaust | EXH-SVE-013112 | 1/31/2012 | 8.2 | | | 0.18 | U | | 0.29 | J | | 0.072 | J | | | | |
| SVE RTO Exhaust | EXH-SVE-020112 | 2/1/2012 | 0.024 | | | 0.0029 | U | | 0.0062 | | | 0.0018 | J | | | | |
| SVE RTO Exhaust | EXH-SVE-020212 | 2/2/2012 | 0.43 | | | 0.0041 | U | | 0.026 | | | 0.0051 | J | | | | |
| SVE RTO Exhaust | EXH-SVE-020712 | 2/7/2012 | 0.12 | | | 0.0023 | U | | 0.0086 | | | 0.0018 | J | | | | |
| SVE RTO Exhaust | EXH-SVE-020912 | 2/9/2012 | 0.025 | J | J | 0.015 | U | UJ | 0.026 | U | UJ | 0.026 | U | UJ | | | |
| SVE RTO Exhaust | EXH-SVE-021412 | 2/14/2012 | 3.2 | | | 0.024 | U | | 0.072 | | | 0.013 | J | | | | |
| SVE RTO Exhaust | EXH-SVE-021712 | 2/17/2012 | 23 | | J | 0.045 | U | UJ | 0.42 | | J | 0.097 | | J | | | |
| SVE RTO Exhaust | EXH-SVE-022112 | 2/21/2012 | 83 | | | 0.23 | U | | 6 | | | 1 | | | 2700 | | |
| SVE RTO Exhaust | EXH-SVE-022412 | 2/24/2012 | 1.1 | | | 0.005 | U | | 0.065 | | | 0.017 | | | 38 | | |
| SVE RTO Exhaust | EXH-SVE-022712 | 2/27/2012 | 0.36 | | | 0.005 | U | | 0.013 | | | 0.0034 | J | | 22 | | |
| SVE RTO Exhaust | EXH-SVE-030112 | 3/1/2012 | 41 | | | 0.32 | U | | 1.7 | | | 0.19 | J | | | | |
| SVE RTO Exhaust | EXH-SVE-032312 | 3/23/2012 | 0.82 | | | 0.0068 | U | | 0.031 | | | 0.0068 | J | | 49 | | |
| SVE RTO Exhaust | EXH-SVE-04192012 | 4/19/2012 | 0.4 | | | 0.0025 | U | | 0.4 | | | 0.11 | | | 20 | | |
| SVE RTO Exhaust | EXH-SVE-05172012 | 5/17/2012 | 14 | | | 0.098 | U | | 0.31 | | | 0.052 | J | | 780 | | |
| SVE RTO Exhaust | EXH-SVE-06212012 | 6/21/2012 | 13 | | | 0.31 | U | | 0.47 | J | | 0.53 | U | | 740 | | |
| SVE RTO Exhaust | EXH-SVE-08312012 | 8/31/2012 | 13 | | | 0.16 | U | | 0.73 | | | 0.2 | J | | 690 | | |
| SVE RTO Exhaust | EXH-SVE-09282012 | 9/28/2012 | 11 | | | 0.3 | U | | 0.15 | J | | 0.51 | U | | 680 | | |
| SVE RTO Exhaust | EXH-SVE-10252012 | 10/25/2012 | 13 | | | 0.41 | U | | 0.32 | J | | 0.074 | J | | 610 | | |
| SVE RTO Exhaust | EXH-SVE-113012 | 11/30/2012 | 0.92 | | | 0.0077 | U | | 0.033 | | | 0.0098 | J | | 26 | | |
| SVE RTO Exhaust | EXH-SVE-120312 | 12/3/2012 | 11 | | | 0.082 | U | | 0.11 | J | | 0.14 | U | | 310 | | J |
| SVE RTO Exhaust | EXH-SVE-120412 | 12/4/2012 | 0.63 | | | 0.004 | U | | 0.35 | | | 0.096 | | | 19 | | |
| SVE RTO Exhaust | EXH-SVE-120512 | 12/5/2012 | 8.8 | | | 0.072 | U | | 0.33 | | | 0.064 | J | | 230 | | |
| SVE RTO Exhaust | EXH-SVE-121012 | 12/10/2012 | 0.38 | | | 0.033 | U | | 0.11 | | | 0.022 | J | | 13 | | |
| SVE RTO Exhaust | EXH-SVE-121212 | 12/12/2012 | 9.4 | | | 0.034 | U | | 0.26 | | | 0.052 | J | | 310 | | |
| SVE RTO Exhaust | EXH-SVE-121712 | 12/17/2012 | 0.18 | | | 0.0037 | U | | 0.052 | | | 0.014 | | | 6 | | |
| SVE RTO Exhaust | EXH-SVE-121912 | 12/19/2012 | 11 | | | 0.069 | U | | 0.47 | | | 0.11 | J | | 390 | | |
| SVE RTO Exhaust | EXH-SVE-01162013 | 1/16/2013 | 0.36 | | | 0.0036 | U | | 0.022 | | | 0.0049 | J | | 7.4 | | |
| SVE RTO Exhaust | EXH-SVE-02202013 | 2/20/2013 | 11 | | | 0.046 | U | | 0.14 | | | 0.013 | J | | 360 | | |
| SVE RTO Exhaust | EXH-SVE-03012013 | 3/1/2013 | 12 | | | 0.091 | U | | 0.53 | | | 0.11 | J | | 340 | | J |

SEE LAST PAGE OF TABLE FOR NOTES

**TABLE 11**
**SVE SYSTEM HEADER AND EXHAUST ANALYTICAL DATA**

| Location | Sample ID | Sample Date | TPH (Gasoline Range) | | | BTU | | | Butane | | | Isopentane | | | Acetylene | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | Result (mg/m3) | Lab Qualifier | URS Qualifier | Result (%) | Lab Qualifier | URS Qualifier | Result (%) | Lab Qualifier | URS Qualifier | Result (%) | Lab Qualifier | URS Qualifier | Result (%) | Lab Qualifier | URS Qualifier |
| SVE Public Works Header | PWHeader-121912 | 12/19/2012 | | | | | | | 0.033 | | | 0.069 | | | 0.003 | U | |
| SVE Public Works Header | PWHeader-SVE-01162013 | 1/16/2013 | | | | 0.042 | | | 0.089 | | | | | | 0.003 | U | |
| SVE Public Works Header | PWHeader-SVE-02202013 | 2/20/2013 | | | | 0.038 | | | 0.084 | | | | | | 0.0028 | U | |
| SVE Public Works Header | PWHeader-SVE-03012013 | 3/1/2013 | | | | 0.041 | | | 0.093 | | | | | | 0.0029 | U | |
| SVE Refinery Header | HEADER-SVE-020912 | 2/9/2012 | 99000 | | | | | | 0.61 | | | 0.6 | | | 0.0016 | U | |
| SVE Refinery Header | HEADER-SVE-021712 | 2/17/2012 | 97000 | | | | | | 0.45 | | | 0.57 | | | 0.002 | U | |
| SVE Refinery Header | HEADER-SVE-030112 | 3/1/2012 | 91000 | | | | | | 0.23 | | | 0.32 | | | 0.0018 | U | |
| SVE Refinery Header | HEADER-SVE-030812 | 3/8/2012 | | | | | | | 0.2 | | | 0.3 | | | 0.0019 | U | |
| SVE Refinery Header | HEADER-SVE-032312 | 3/23/2012 | | | | | | | 0.1 | | | 0.13 | | | 0.0021 | U | |
| SVE Refinery Header | HEADER-SVE-032812 | 3/28/2012 | | | | | | | 0.095 | | | 0.12 | | | 0.002 | U | |
| SVE Refinery Header | MainHeader-SVE-113012 | 11/30/2012 | | | | | | | 0.084 | | | 0.1 | | | 0.0031 | U | |
| SVE Refinery Header | MainHeader-121912 | 12/19/2012 | | | | | | | 0.18 | | | 0.22 | | | 0.003 | U | |
| SVE Refinery Header | MainHeader-SVE-01162013 | 1/16/2013 | | | | 0.2 | | | 0.24 | | | | | | 0.003 | U | |
| SVE Refinery Header | MainHeader-SVE-02202013 | 2/20/2013 | | | | 0.16 | | | 0.2 | | | | | | 0.0029 | U | |
| SVE Refinery Header | MainHeader-SVE-03012013 | 3/1/2013 | | | | 0.19 | | | 0.22 | | | | | | 0.0029 | U | |
| SVE RTO Exhaust | EXH-SVE-013112 | 1/31/2012 | 480 | | | | | | 0.0018 | | | 0.0023 | | | 0.0014 | U | |
| SVE RTO Exhaust | EXH-SVE-020112 | 2/1/2012 | 1.9 | | | | | | 0.0023 | U | | 0.0023 | U | | 0.0023 | U | |
| SVE RTO Exhaust | EXH-SVE-020212 | 2/2/2012 | 15 | | | | | | 0.0016 | U | | 0.000034 | J | | 0.0016 | U | |
| SVE RTO Exhaust | EXH-SVE-020712 | 2/7/2012 | 7.2 | | | | | | 0.0014 | U | | 0.0014 | U | | 0.0014 | U | |
| SVE RTO Exhaust | EXH-SVE-020912 | 2/9/2012 | 5.2 | | J | | | | 0.0091 | U | UJ | 0.0091 | U | UJ | 0.0091 | U | UJ |
| SVE RTO Exhaust | EXH-SVE-021412 | 2/14/2012 | 180 | | | | | | 0.00054 | J | | 0.00071 | J | | 0.0019 | U | |
| SVE RTO Exhaust | EXH-SVE-021712 | 2/17/2012 | 430 | | J | | | | 0.00035 | J | J | 0.00038 | J | | 0.0035 | U | UJ |
| SVE RTO Exhaust | EXH-SVE-022112 | 2/21/2012 | | | | | | | 0.0013 | J | | 0.0031 | | | 0.0018 | U | |
| SVE RTO Exhaust | EXH-SVE-022412 | 2/24/2012 | | | | | | | 0.002 | U | | 0.000046 | J | | 0.002 | U | |
| SVE RTO Exhaust | EXH-SVE-022712 | 2/27/2012 | | | | | | | 0.002 | U | | 0.002 | U | | 0.002 | U | |
| SVE RTO Exhaust | EXH-SVE-030112 | 3/1/2012 | 1700 | | | | | | 0.005 | | | 0.0064 | | | 0.0019 | U | |
| SVE RTO Exhaust | EXH-SVE-032312 | 3/23/2012 | | | | | | | 0.000068 | J | | 0.000094 | J | | 0.002 | U | |
| SVE RTO Exhaust | EXH-SVE-04192012 | 4/19/2012 | | | | | | | 0.0034 | U | | 0.0034 | U | | 0.0034 | U | |
| SVE RTO Exhaust | EXH-SVE-05172012 | 5/17/2012 | | | | 1.9 | U | | 0.002 | | | 0.0024 | | | 0.0019 | U | |
| SVE RTO Exhaust | EXH-SVE-06212012 | 6/21/2012 | | | | | | | 0.0019 | J | | 0.0022 | | | 0.002 | U | |
| SVE RTO Exhaust | EXH-SVE-08312012 | 8/31/2012 | | | | | | | 0.0013 | J | | 0.0018 | J | | 0.003 | U | |
| SVE RTO Exhaust | EXH-SVE-09282012 | 9/28/2012 | | | | | | | 0.0013 | J | | 0.0017 | J | | 0.0028 | U | |
| SVE RTO Exhaust | EXH-SVE-10252012 | 10/25/2012 | | | | | | | 0.0016 | J | | 0.0021 | J | | 0.0032 | U | |
| SVE RTO Exhaust | EXH-SVE-113012 | 11/30/2012 | | | | | | | 0.000088 | J | | 0.0001 | J | | 0.003 | U | |
| SVE RTO Exhaust | EXH-SVE-120312 | 12/3/2012 | | | | | | | 0.00097 | J | | 0.0012 | J | | 0.0032 | U | |
| SVE RTO Exhaust | EXH-SVE-120412 | 12/4/2012 | | | | | | | 0.0031 | U | | 0.0031 | U | | 0.0031 | U | |
| SVE RTO Exhaust | EXH-SVE-120512 | 12/5/2012 | | | | | | | 0.00051 | J | | 0.00068 | J | | 0.0028 | U | |
| SVE RTO Exhaust | EXH-SVE-121012 | 12/10/2012 | | | | | | | 0.0026 | U | | 0.0026 | U | | 0.0026 | U | |
| SVE RTO Exhaust | EXH-SVE-121212 | 12/12/2012 | | | | | | | 0.00078 | J | | 0.001 | J | | 0.0027 | U | |
| SVE RTO Exhaust | EXH-SVE-121712 | 12/17/2012 | | | | | | | 0.0029 | U | | 0.0029 | U | | 0.0029 | U | |
| SVE RTO Exhaust | EXH-SVE-121912 | 12/19/2012 | | | | | | | 0.00092 | J | | 0.0012 | J | | 0.0027 | U | |
| SVE RTO Exhaust | EXH-SVE-01162013 | 1/16/2013 | | | | 0.0028 | U | | 0.0028 | U | | | | | 0.0028 | U | |
| SVE RTO Exhaust | EXH-SVE-02202013 | 2/20/2013 | | | | 0.00082 | J | | 0.0011 | J | | | | | 0.0058 | U | |
| SVE RTO Exhaust | EXH-SVE-03012013 | 3/1/2013 | | | | 0.00085 | J | | 0.0011 | J | | | | | 0.0028 | U | |

SEE LAST PAGE OF TABLE FOR NOTES

**TABLE 11**
**SVE SYSTEM HEADER AND EXHAUST ANALYTICAL DATA**

| Location | Sample ID | Sample Date | C6+ | | | Carbon Dioxide | | | Carbon Monoxide | | | Ethane | | | Ethene | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | Result (%) | Lab Qualifier | URS Qualifier | Result (%) | Lab Qualifier | URS Qualifier | Result (%) | Lab Qualifier | URS Qualifier | Result (%) | Lab Qualifier | URS Qualifier | Result (%) | Lab Qualifier | URS Qualifier |
| SVE Public Works Header | PWHeader-121912 | 12/19/2012 | 0.11 | | | 5.9 | | | 0.03 | U | | 0.00019 | J | | 0.003 | U | |
| SVE Public Works Header | PWHeader-SVE-01162013 | 1/16/2013 | 0.15 | | | 7.2 | | | 0.15 | U | | 0.00024 | J | | 0.003 | U | |
| SVE Public Works Header | PWHeader-SVE-02202013 | 2/20/2013 | 0.15 | | | 6 | | | 0.14 | U | | 0.00023 | J | | 0.0028 | U | |
| SVE Public Works Header | PWHeader-SVE-03012013 | 3/1/2013 | 0.18 | | | 6.3 | | | 0.029 | U | | 0.00027 | J | | 0.0029 | U | |
| SVE Refinery Header | HEADER-SVE-020912 | 2/9/2012 | 0.79 | | | 8.1 | | | 0.016 | U | | 0.0032 | | | 0.000039 | J | |
| SVE Refinery Header | HEADER-SVE-021712 | 2/17/2012 | 0.9 | | | 7 | | | 0.02 | U | | 0.0024 | | | 0.002 | U | |
| SVE Refinery Header | HEADER-SVE-030112 | 3/1/2012 | 0.7 | | | 7.9 | | | 0.018 | U | | 0.0016 | J | | 0.000072 | J | |
| SVE Refinery Header | HEADER-SVE-030812 | 3/8/2012 | 0.56 | | | 8.1 | | | 0.019 | U | | 0.0018 | J | | 0.00011 | J | |
| SVE Refinery Header | HEADER-SVE-032312 | 3/23/2012 | 0.26 | | | 2.2 | | | 0.021 | U | | 0.0006 | J | | 0.0021 | U | |
| SVE Refinery Header | HEADER-SVE-032812 | 3/28/2012 | 0.26 | | | 2.2 | | | 0.02 | U | | 0.0006 | J | | 0.002 | U | |
| SVE Refinery Header | MainHeader-SVE-113012 | 11/30/2012 | 0.31 | | | 3.1 | | | 0.031 | U | | 0.00044 | J | | 0.0031 | U | |
| SVE Refinery Header | MainHeader-121912 | 12/19/2012 | 0.56 | | | 7 | | | 0.03 | U | | 0.00089 | J | | 0.003 | U | |
| SVE Refinery Header | MainHeader-SVE-01162013 | 1/16/2013 | 0.68 | | | 7.4 | | | 0.15 | U | | 0.00089 | J | | 0.003 | U | |
| SVE Refinery Header | MainHeader-SVE-02202013 | 2/20/2013 | 0.59 | | | 6.6 | | | 0.14 | U | | 0.00076 | J | | 0.0029 | U | |
| SVE Refinery Header | MainHeader-SVE-03012013 | 3/1/2013 | 0.63 | | | 7 | | | 0.029 | U | | 0.00084 | J | | 0.0029 | U | |
| SVE RTO Exhaust | EXH-SVE-013112 | 1/31/2012 | 0.0034 | J | | 1 | | | 0.014 | U | | 0.0014 | U | | 0.000058 | J | |
| SVE RTO Exhaust | EXH-SVE-020112 | 2/1/2012 | 0.023 | U | | 0.27 | | | 0.023 | U | | 0.0023 | U | | 0.0023 | U | |
| SVE RTO Exhaust | EXH-SVE-020212 | 2/2/2012 | 0.016 | U | | 0.56 | | | 0.016 | U | | 0.0016 | U | | 0.0016 | U | |
| SVE RTO Exhaust | EXH-SVE-020712 | 2/7/2012 | 0.014 | U | | 0.57 | | | 0.014 | U | | 0.0014 | U | | 0.0014 | U | |
| SVE RTO Exhaust | EXH-SVE-020912 | 2/9/2012 | 0.091 | U | UJ | 0.45 | | J | 0.091 | U | UJ | 0.0091 | U | UJ | 0.0091 | U | UJ |
| SVE RTO Exhaust | EXH-SVE-021412 | 2/14/2012 | 0.00096 | J | | 1.1 | | | 0.019 | U | | 0.0019 | U | | 0.0019 | U | |
| SVE RTO Exhaust | EXH-SVE-021712 | 2/17/2012 | 0.0025 | J | J | 1 | | J | 0.035 | U | UJ | 0.0035 | U | UJ | 0.0035 | U | UJ |
| SVE RTO Exhaust | EXH-SVE-022112 | 2/21/2012 | 0.021 | | | 0.94 | | | 0.018 | U | | 0.0018 | U | | 0.0018 | U | |
| SVE RTO Exhaust | EXH-SVE-022412 | 2/24/2012 | 0.02 | U | | 0.25 | | | 0.02 | U | | 0.002 | U | | 0.002 | U | |
| SVE RTO Exhaust | EXH-SVE-022712 | 2/27/2012 | 0.02 | U | | 0.64 | | | 0.02 | U | | 0.002 | U | | 0.002 | U | |
| SVE RTO Exhaust | EXH-SVE-030112 | 3/1/2012 | 0.015 | J | | 0.27 | | | 0.019 | U | | 0.000048 | J | | 0.0019 | U | |
| SVE RTO Exhaust | EXH-SVE-032312 | 3/23/2012 | 0.00081 | J | | 0.84 | | | 0.02 | U | | 0.002 | U | | 0.002 | U | |
| SVE RTO Exhaust | EXH-SVE-04192012 | 4/19/2012 | 0.034 | J | U | 0.77 | | | 0.034 | U | | 0.0034 | U | | 0.0034 | U | |
| SVE RTO Exhaust | EXH-SVE-05172012 | 5/17/2012 | 0.0046 | J | | 0.9 | | | 0.019 | U | | 0.0019 | U | | 0.0019 | U | |
| SVE RTO Exhaust | EXH-SVE-06212012 | 6/21/2012 | 0.0044 | J | | 0.85 | | | 0.02 | U | | 0.002 | U | | 0.0001 | J | |
| SVE RTO Exhaust | EXH-SVE-08312012 | 8/31/2012 | 0.0037 | J | | 0.94 | | | 0.03 | U | | 0.003 | U | | 0.000075 | J | |
| SVE RTO Exhaust | EXH-SVE-09282012 | 9/28/2012 | 0.0039 | J | | 1.2 | | | 0.028 | U | | 0.0028 | U | | 0.0001 | J | |
| SVE RTO Exhaust | EXH-SVE-10252012 | 10/25/2012 | 0.0047 | J | | 1.2 | | | 0.032 | U | | 0.0032 | U | | 0.00015 | J | |
| SVE RTO Exhaust | EXH-SVE-113012 | 11/30/2012 | | J | | 1.2 | | | 0.03 | U | | 0.003 | U | | 0.003 | U | |
| SVE RTO Exhaust | EXH-SVE-120312 | 12/3/2012 | 0.0024 | J | | 0.65 | | | 0.032 | U | | 0.0032 | U | | 0.0032 | U | |
| SVE RTO Exhaust | EXH-SVE-120412 | 12/4/2012 | 0.031 | U | | 0.86 | | | 0.031 | U | | 0.0031 | U | | 0.0031 | U | |
| SVE RTO Exhaust | EXH-SVE-120512 | 12/5/2012 | 0.0017 | J | | 0.74 | | | 0.028 | U | | 0.0028 | U | | 0.0028 | U | |
| SVE RTO Exhaust | EXH-SVE-121012 | 12/10/2012 | 0.026 | U | | 0.78 | | | 0.026 | U | | 0.0026 | U | | 0.0026 | U | |
| SVE RTO Exhaust | EXH-SVE-121212 | 12/12/2012 | 0.0027 | J | | 0.64 | | | 0.027 | U | | 0.0027 | U | | 0.0027 | U | |
| SVE RTO Exhaust | EXH-SVE-121712 | 12/17/2012 | 0.029 | U | | 0.78 | | | 0.029 | U | | 0.0029 | U | | 0.0029 | U | |
| SVE RTO Exhaust | EXH-SVE-121912 | 12/19/2012 | 0.0028 | J | | 0.69 | | | 0.027 | U | | 0.0027 | U | | 0.0027 | U | |
| SVE RTO Exhaust | EXH-SVE-01162013 | 1/16/2013 | 0.028 | U | | 0.73 | | | 0.14 | U | | 0.0028 | U | | 0.0028 | U | |
| SVE RTO Exhaust | EXH-SVE-02202013 | 2/20/2013 | 0.0026 | J | | 0.71 | | | 0.29 | U | | 0.0058 | U | | 0.0058 | U | |
| SVE RTO Exhaust | EXH-SVE-03012013 | 3/1/2013 | 0.0028 | J | | 0.73 | | | 0.028 | U | | 0.0028 | U | | 0.0028 | U | |

SEE LAST PAGE OF TABLE FOR NOTES

**TABLE 11**
**SVE SYSTEM HEADER AND EXHAUST ANALYTICAL DATA**

| Location | Sample ID | Sample Date | Hydrogen | | | Isobutane | | | Methane | | | Neopentane | | | Nitrogen | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | Result (%) | Lab Qualifier | URS Qualifier | Result (%) | Lab Qualifier | URS Qualifier | Result (%) | Lab Qualifier | URS Qualifier | Result (%) | Lab Qualifier | URS Qualifier | Result (%) | Lab Qualifier | URS Qualifier |
| SVE Public Works Header | PWHeader-121912 | 12/19/2012 | 0.03 | U | | 0.0037 | | | 3.1 | | | 0.0002 | J | | 77 | | |
| SVE Public Works Header | PWHeader-SVE-01162013 | 1/16/2013 | 0.03 | U | | 0.0045 | | | 4.1 | | | 0.00024 | J | | 76 | | |
| SVE Public Works Header | PWHeader-SVE-02202013 | 2/20/2013 | 0.028 | U | | 0.0042 | | | 3.9 | | | 0.00029 | J | | 78 | | |
| SVE Public Works Header | PWHeader-SVE-03012013 | 3/1/2013 | 0.029 | U | | 0.0045 | | | 4.3 | | | 0.00025 | J | | 75 | | |
| SVE Refinery Header | HEADER-SVE-020912 | 2/9/2012 | 0.016 | U | | 0.069 | | | 12 | | | 0.0021 | | | 71 | | |
| SVE Refinery Header | HEADER-SVE-021712 | 2/17/2012 | 0.02 | U | | 0.059 | | | 8.5 | | | 0.0019 | J | | 74 | | |
| SVE Refinery Header | HEADER-SVE-030112 | 3/1/2012 | 0.018 | U | | 0.035 | | | 6.9 | | | 0.0012 | J | | 78 | | |
| SVE Refinery Header | HEADER-SVE-030812 | 3/8/2012 | 0.019 | U | | 0.034 | | | 6 | | | 0.0012 | J | | 78 | | |
| SVE Refinery Header | HEADER-SVE-032312 | 3/23/2012 | 0.021 | U | | 0.013 | | | 2.1 | | | 0.00065 | J | | 78 | | |
| SVE Refinery Header | HEADER-SVE-032812 | 3/28/2012 | 0.02 | U | | 0.012 | | | 2 | | | 0.00042 | J | | 78 | | |
| SVE Refinery Header | MainHeader-SVE-113012 | 11/30/2012 | 0.031 | U | | 0.0096 | | | 1.5 | | | 0.00036 | J | | 78 | | |
| SVE Refinery Header | MainHeader-121912 | 12/19/2012 | 0.03 | U | | 0.02 | | | 3.2 | | | 0.00079 | J | | 78 | | |
| SVE Refinery Header | MainHeader-SVE-01162013 | 1/16/2013 | 0.03 | U | | 0.022 | | | 3.3 | | | 0.00089 | J | | 78 | | |
| SVE Refinery Header | MainHeader-SVE-02202013 | 2/20/2013 | 0.029 | U | | 0.018 | | | 2.8 | | | 0.00081 | J | | 78 | | |
| SVE Refinery Header | MainHeader-SVE-03012013 | 3/1/2013 | 0.029 | U | | 0.021 | | | 3.1 | | | 0.00081 | J | | 77 | | |
| SVE RTO Exhaust | EXH-SVE-013112 | 1/31/2012 | 0.014 | U | | 0.00022 | J | | 0.034 | | | 0.0014 | U | | 79 | | |
| SVE RTO Exhaust | EXH-SVE-020112 | 2/1/2012 | 0.023 | U | | 0.0023 | U | | 0.00018 | J | | 0.0023 | U | | 80 | | |
| SVE RTO Exhaust | EXH-SVE-020212 | 2/2/2012 | 0.016 | U | | 0.0016 | U | | 0.00075 | | | 0.0016 | U | | 78 | | |
| SVE RTO Exhaust | EXH-SVE-020712 | 2/7/2012 | 0.014 | U | | 0.0014 | U | | 0.00045 | | | 0.0014 | U | | 78 | | |
| SVE RTO Exhaust | EXH-SVE-020912 | 2/9/2012 | 0.091 | U | UJ | 0.0091 | U | UJ | 0.00048 | J | J | 0.0091 | U | UJ | 84 | | J |
| SVE RTO Exhaust | EXH-SVE-021412 | 2/14/2012 | 0.019 | U | | 0.000068 | J | | 0.01 | | | 0.0019 | U | | 79 | | |
| SVE RTO Exhaust | EXH-SVE-021712 | 2/17/2012 | 0.035 | U | UJ | 0.0035 | U | UJ | 0.0013 | | J | 0.0035 | U | UJ | 80 | | J |
| SVE RTO Exhaust | EXH-SVE-022112 | 2/21/2012 | 0.018 | U | | 0.00011 | J | | 0.0037 | | | 0.0018 | U | | 79 | | |
| SVE RTO Exhaust | EXH-SVE-022412 | 2/24/2012 | 0.02 | U | | 0.002 | U | | 0.00083 | | | 0.002 | U | | 84 | | |
| SVE RTO Exhaust | EXH-SVE-022712 | 2/27/2012 | 0.02 | U | | 0.002 | U | | 0.00031 | | | 0.002 | U | | 79 | | |
| SVE RTO Exhaust | EXH-SVE-030112 | 3/1/2012 | 0.019 | U | | 0.0009 | J | | 0.21 | | | 0.0019 | U | | 78 | | |
| SVE RTO Exhaust | EXH-SVE-032312 | 3/23/2012 | 0.02 | U | | 0.002 | U | | 0.0016 | | | 0.002 | U | | 79 | | |
| SVE RTO Exhaust | EXH-SVE-04192012 | 4/19/2012 | 0.034 | U | | 0.0034 | U | | 0.00042 | | | 0.0034 | U | | 79 | | |
| SVE RTO Exhaust | EXH-SVE-05172012 | 5/17/2012 | 0.019 | U | | 0.00025 | J | | 0.059 | | | 0.0019 | U | | 80 | | |
| SVE RTO Exhaust | EXH-SVE-06212012 | 6/21/2012 | 0.02 | U | | 0.00024 | J | | 0.057 | | | 0.002 | U | | 79 | | |
| SVE RTO Exhaust | EXH-SVE-08312012 | 8/31/2012 | 0.03 | U | | 0.00016 | J | | 0.035 | | | 0.003 | U | | 81 | | |
| SVE RTO Exhaust | EXH-SVE-09282012 | 9/28/2012 | 0.028 | U | | 0.00015 | J | | 0.037 | | | 0.0028 | U | | 80 | | |
| SVE RTO Exhaust | EXH-SVE-10252012 | 10/25/2012 | 0.032 | U | | 0.00019 | J | | 0.044 | | | 0.0032 | U | | 80 | | |
| SVE RTO Exhaust | EXH-SVE-113012 | 11/30/2012 | 0.03 | U | | 0.003 | U | | 0.0022 | | | 0.003 | U | | 79 | | |
| SVE RTO Exhaust | EXH-SVE-120312 | 12/3/2012 | 0.032 | U | | 0.00012 | J | | 0.023 | | | 0.0032 | U | | 79 | | |
| SVE RTO Exhaust | EXH-SVE-120412 | 12/4/2012 | 0.031 | U | | 0.0031 | U | | 0.00044 | | | 0.0031 | U | | 79 | | |
| SVE RTO Exhaust | EXH-SVE-120512 | 12/5/2012 | 0.028 | U | | 0.0028 | U | | 0.012 | | | 0.0028 | U | | 79 | | |
| SVE RTO Exhaust | EXH-SVE-121012 | 12/10/2012 | 0.026 | U | | 0.0026 | U | | 0.00031 | | | 0.0026 | U | | 79 | | |
| SVE RTO Exhaust | EXH-SVE-121212 | 12/12/2012 | 0.027 | U | | 0.0001 | J | | 0.019 | | | 0.0027 | U | | 80 | | |
| SVE RTO Exhaust | EXH-SVE-121712 | 12/17/2012 | 0.029 | U | | 0.0029 | U | | 0.00037 | | | 0.0029 | U | | 79 | | |
| SVE RTO Exhaust | EXH-SVE-121912 | 12/19/2012 | 0.027 | U | | 0.00011 | J | | 0.023 | | | 0.0027 | U | | 79 | | |
| SVE RTO Exhaust | EXH-SVE-01162013 | 1/16/2013 | 0.028 | U | | 0.0028 | U | | 0.0005 | | | 0.0028 | U | | 79 | | |
| SVE RTO Exhaust | EXH-SVE-02202013 | 2/20/2013 | 0.058 | U | | 0.000095 | J | | 0.021 | | | 0.0058 | U | | 78 | | |
| SVE RTO Exhaust | EXH-SVE-03012013 | 3/1/2013 | 0.028 | U | | 0.000094 | J | | 0.022 | | | 0.0028 | U | | 78 | | |

SEE LAST PAGE OF TABLE FOR NOTES

**TABLE 11**
**SVE SYSTEM HEADER AND EXHAUST ANALYTICAL DATA**

| Location | Sample ID | Sample Date | Oxygen | | | Pentane | | | Propane | | |
|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | Result (%) | Lab Qualifier | URS Qualifier | Result (%) | Lab Qualifier | URS Qualifier | Result (%) | Lab Qualifier | URS Qualifier |
| SVE Public Works Header | PWHeader-121912 | 12/19/2012 | 14 | | | 0.029 | | | 0.00013 | J | |
| SVE Public Works Header | PWHeader-SVE-01162013 | 1/16/2013 | 12 | | | 0.038 | | | 0.00013 | J | |
| SVE Public Works Header | PWHeader-SVE-02202013 | 2/20/2013 | 12 | | | 0.035 | | | 0.00011 | J | |
| SVE Public Works Header | PWHeader-SVE-03012013 | 3/1/2013 | 14 | | | 0.039 | | | 0.00013 | J | |
| SVE Refinery Header | HEADER-SVE-020912 | 2/9/2012 | 6.9 | | | 0.19 | | | 0.0038 | | |
| SVE Refinery Header | HEADER-SVE-021712 | 2/17/2012 | 8.1 | | | 0.22 | | | 0.0034 | | |
| SVE Refinery Header | HEADER-SVE-030112 | 3/1/2012 | 6 | | | 0.1 | | | 0.002 | | |
| SVE Refinery Header | HEADER-SVE-030812 | 3/8/2012 | 6.8 | | | 0.091 | | | 0.0021 | | |
| SVE Refinery Header | HEADER-SVE-032312 | 3/23/2012 | 17 | | | 0.056 | | | 0.00078 | J | |
| SVE Refinery Header | HEADER-SVE-032812 | 3/28/2012 | 17 | | | 0.04 | | | 0.00075 | J | |
| SVE Refinery Header | MainHeader-SVE-113012 | 11/30/2012 | 17 | | | 0.036 | | | 0.00063 | J | |
| SVE Refinery Header | MainHeader-121912 | 12/19/2012 | 11 | | | 0.078 | | | 0.0013 | J | |
| SVE Refinery Header | MainHeader-SVE-01162013 | 1/16/2013 | 10 | | | 0.091 | | | 0.0013 | J | |
| SVE Refinery Header | MainHeader-SVE-02202013 | 2/20/2013 | 11 | | | 0.077 | | | 0.0012 | J | |
| SVE Refinery Header | MainHeader-SVE-03012013 | 3/1/2013 | 12 | | | 0.084 | | | 0.0013 | J | |
| SVE RTO Exhaust | EXH-SVE-013112 | 1/31/2012 | 20 | | | 0.00076 | J | | 0.0014 | U | |
| SVE RTO Exhaust | EXH-SVE-020112 | 2/1/2012 | 20 | | | 0.0023 | U | | 0.0023 | U | |
| SVE RTO Exhaust | EXH-SVE-020212 | 2/2/2012 | 21 | | | 0.0016 | U | | 0.0016 | U | |
| SVE RTO Exhaust | EXH-SVE-020712 | 2/7/2012 | 21 | | | 0.0014 | U | | 0.0014 | U | |
| SVE RTO Exhaust | EXH-SVE-020912 | 2/9/2012 | 15 | | J | 0.0091 | U | UJ | 0.0091 | U | UJ |
| SVE RTO Exhaust | EXH-SVE-021412 | 2/14/2012 | 20 | | | 0.00031 | J | | 0.0019 | U | |
| SVE RTO Exhaust | EXH-SVE-021712 | 2/17/2012 | 19 | | J | 0.00015 | J | J | 0.0035 | U | UJ |
| SVE RTO Exhaust | EXH-SVE-022112 | 2/21/2012 | 20 | | | 0.0016 | J | | 0.0018 | U | |
| SVE RTO Exhaust | EXH-SVE-022412 | 2/24/2012 | 16 | | | 0.002 | U | | 0.002 | U | |
| SVE RTO Exhaust | EXH-SVE-022712 | 2/27/2012 | 20 | | | 0.002 | U | | 0.002 | U | |
| SVE RTO Exhaust | EXH-SVE-030112 | 3/1/2012 | 21 | | | 0.0017 | J | | 0.000056 | J | |
| SVE RTO Exhaust | EXH-SVE-032312 | 3/23/2012 | 20 | | | 0.002 | U | | 0.002 | U | |
| SVE RTO Exhaust | EXH-SVE-04192012 | 4/19/2012 | 20 | | | 0.0034 | U | | 0.0034 | U | |
| SVE RTO Exhaust | EXH-SVE-05172012 | 5/17/2012 | 19 | | | 0.00079 | J | | 0.0019 | U | |
| SVE RTO Exhaust | EXH-SVE-06212012 | 6/21/2012 | 20 | | | 0.00073 | J | | 0.002 | U | |
| SVE RTO Exhaust | EXH-SVE-08312012 | 8/31/2012 | 18 | | | 0.00065 | J | | 0.003 | U | |
| SVE RTO Exhaust | EXH-SVE-09282012 | 9/28/2012 | 19 | | | 0.00064 | J | | 0.0028 | U | |
| SVE RTO Exhaust | EXH-SVE-10252012 | 10/25/2012 | 19 | | | 0.00076 | J | | 0.0032 | U | |
| SVE RTO Exhaust | EXH-SVE-113012 | 11/30/2012 | 20 | | | 0.003 | U | | 0.003 | U | |
| SVE RTO Exhaust | EXH-SVE-120312 | 12/3/2012 | 20 | | | 0.00053 | J | | 0.0032 | U | |
| SVE RTO Exhaust | EXH-SVE-120412 | 12/4/2012 | 20 | | | 0.0031 | U | | 0.0031 | U | |
| SVE RTO Exhaust | EXH-SVE-120512 | 12/5/2012 | 20 | | | 0.00026 | J | | 0.0028 | U | |
| SVE RTO Exhaust | EXH-SVE-121012 | 12/10/2012 | 20 | | | 0.0026 | U | | 0.0026 | U | |
| SVE RTO Exhaust | EXH-SVE-121212 | 12/12/2012 | 19 | | | 0.00039 | J | | 0.0027 | U | |
| SVE RTO Exhaust | EXH-SVE-121712 | 12/17/2012 | 20 | | | 0.0029 | U | | 0.0029 | U | |
| SVE RTO Exhaust | EXH-SVE-121912 | 12/19/2012 | 20 | | | 0.00043 | J | | 0.0027 | U | |
| SVE RTO Exhaust | EXH-SVE-01162013 | 1/16/2013 | 20 | | | 0.0028 | U | | 0.0028 | U | |
| SVE RTO Exhaust | EXH-SVE-02202013 | 2/20/2013 | 21 | | | 0.00043 | J | | 0.0058 | U | |
| SVE RTO Exhaust | EXH-SVE-03012013 | 3/1/2013 | 21 | | | 0.00043 | J | | 0.0028 | U | |

Notes
**Lab Qualifiers**
J = Estimated value; results between the MDL and RL
U = Compound analyzed for but not detected above the RL
**URS Qualifiers**
J = Estimated detection
UJ = Estimated non-detect
U = Non-detect due to blank contamination

The following EVS descriptions and assumptions apply to **Figures 9** through **12**:

**Plan View Model Output** – The data input for the plan view model was not limited by depth and was modeled in three dimensions (3D). The bottom surface of the resulting model was limited to the potentiometric groundwater surface elevation. The two dimensional (2D) appearance of the figures created from the 3D model was achieved by displaying an aerial view of horizontal slices through the model. The horizontal slices were taken parallel to the ground surface that was created from GPS survey data, rather than at single elevation plane. The result of this is a surface that accurately represents soil vapor concentrations at discreet depths measured from ground surface.


**Inward Kriging / Boundary Cut-off** – This method of Kriging limits the horizontal extent of data modeling to the extent of the data on the x/y plane in a convex hull. The model is bounded by the VMPs.

**Vertical Cut-off** – The bottom surface of this model is based on the 3Q12 groundwater gauging data collected in Roxana. The groundwater gauging data was used to model a 2D surface that represents the interface between the top surface of groundwater and the bottom surface of soil vapor.

**Duplicate Samples –** Analytical concentrations from duplicate samples collected at the same location and depth were averaged.

**Detection Limits –** In cases where the lab reported a non-detect, half the value of the lab detection limit was used in the model. This conservative method is based on the assumption that the soil is likely not free of benzene but the quantity contained is lower than detectable at the analyzed dilution. Data are posted where non-detect.

File: P:\ENVIRONMENTAL\SHELL OIL PRODUCT US\SHELL OIL PRODUCTS US 2013\21562850 - ROXANA\21562850-5 SOIL VAPOR AND SVE AND ICE OPERATIONS\QUARTERLY MONITORING\1Q13\FIGURES\FIGURE 1 1Q13 INVESTIGATION AREA LOCATION MAP.DWG Last edited: 04/19/13 @ 08:37 a.m. @ WCC-ST.LOUIS




SOURCE:
MAP PROVIDED FROM ELECTRONIC USGS DIGITAL RASTER GRAPHIC 7.5 MINUTE TOPOGRAPHIC MAP OF WOOD RIVER, ILL-MO REVISED 1994.

CONTOUR INTERVAL = 5 FT

Ø 2ØØØ

SCALE FEET

N

SHELL OIL PRODUCTS US
SOIL VAPOR MONITORING PROGRAM
ROXANA, ILLINOIS

PROJECT NO.
21562850

URS

DRN. BY: djd April 2013
DSGN. BY: djd
CHKD. BY: kh

1Q13 Investigation Area Location Map

FIG. NO.
1

File: P:\ENVIRONMENTAL\SHELL OIL PRODUCT US\SHELL OIL PRODUCTS US 2013\21562850 – ROXANA\21562850-5_SOIL VAPOR AND SVE_AND_ICE OPERATIONS\QUARTERLY MONITORING\1Q13\FIGURES\FIGURE 2 1Q13 VAPOR MONITORING SAMPLING POINT LOCATIONS.DWG Last edited: APR. 19, 13 @ 08:38 a.m. by: david_deguire

LEGEND

- VAPOR MONITORING POINT LOCATIONS
- VAPOR MONITORING POINT LOCATION (NOT USED FOR QUARTERLY SAMPLING)

NOTES:
1. VMP–29, VMP–30, AND VMP–41 WERE ADDED TO QUARTERLY ROXANA SOIL VAPOR MONITORING PROGRAM IN 3Q12.
2. VMP 47 THROUGH VMP–55 WERE ADDED TO THE QUARTERLY ROXANA SOIL VAPOR MONITORING PROGRAM IN 1Q13.

VILLAGE OF ROXANA

TYDEMAN AVE
FIRST ST
SECOND ST
THIRD ST
FOURTH ST
FIFTH ST
SIXTH ST
SEVENTH ST
EIGHTH ST
S. CENTRAL AVE (HIGHWAY 111)
CHAFFER ST
RAND AVENUE
BP
1986 APPROXIMATE BENZENE RELEASE SITE

VMP-47 VMP-1 VMP-2 VMP-20 VMP-48 VMP-42 VMP-49 VMP-21 VMP-3 VMP-31 VMP-32 VMP-43 VMP-22 VMP-50 VMP-4 VMP-44 VMP-23 VMP-51 VMP-5 VMP-45 VMP-52 VMP-6 VMP-7 VMP-24 VMP-8 VMP-9 VMP-54 VMP-53 VMP-18 VMP-19 VMP-41 VMP-10 VMP-17 VMP-11 VMP-29 VMP-30 VMP-13 VMP-55 VMP-14 VMP-25 VMP-15 VMP-16


NORTH PROPERTY

VMP-33 VMP-46 VMP-34 VMP-35 VMP-27 VMP-26 VMP-28 VMP-36 VMP-37 VMP-38 VMP-39 VMP-40 VMP-12

A–28 A–33 A–27

WOOD RIVER REFINERY

PUBLIC WORKS YARD




KEYMAP
1" = 2,500'

SCALE Ø 200 FEET

N

| | | |
|---|---|---|
| SHELL OIL PRODUCTS US<br>SOIL VAPOR MONITORING PROGRAM<br>ROXANA, ILLINOIS | | PROJECT NO.<br>21562850 |
| URS | | |
| DRN. BY: djd April 2013<br>DSGN. BY: djd<br>CHKD. BY: kh | 1Q13 Vapor Monitoring Point Sampling Locations | FIG. NO.<br>2 |


NOTES:

1) CONTOUR LINES PRIMARILY GENERATED BY SURFER VERSION 8 MODELING OF GROUNDWATER ELEVATIONS. SOME INTERPRETATION WAS DONE UTILIZING PROFESSIONAL JUDGMENT AND CONTOUR LINES WERE MODIFIED BY HAND.

2) ELEVATIONS ARE RELATIVE TO 1988 USGS DATUM.

3) COMPREHENSIVE GROUNDWATER ELEVATIONS WERE MEASURED JANUARY 2–4 AND 7–8 2013. ADDITIONAL GAUGING ACTIVITIES WERE CONDUCTED ON JANUARY 23, 2013 AND FEBRUARY 11, 2013 FOR NEWLY INSTALLED GROUNDWATER MONITORING WELLS IN THE VILLAGE OF ROXANA.

4) GROUNDWATER MONITORING WELLS MW–16, MW–17, MW–18, MW–19, MW–20, MW–21, AND MW–22 WERE INSTALLED DURING 4Q12.




LEGEND

- GROUNDWATER MONITORING WELL LOCATION USED TO GENERATE GROUNDWATER CONTOURS
- GROUNDWATER MONITORING WELL LOCATION NOT USED TO GENERATE GROUNDWATER CONTOURS
- GROUNDWATER PIEZOMETER LOCATION USED TO GENERATE GROUNDWATER CONTOURS
- GROUNDWATER PIEZOMETER LOCATION NOT USED TO GENERATE GROUNDWATER CONTOURS
- WRR GROUNDWATER DEPRESSION WELLS
- GROUNDWATER GRADIENT
- 407 — GROUNDWATER SURFACE CONTOUR NGVD (CONTOUR INTERVAL 0.5 FT.)

| | | |
|---|---|---|
| SHELL OIL PRODUCTS US<br>SOIL VAPOR MONITORING PROGRAM<br>ROXANA, ILLINOIS | | PROJECT NO.<br>215628500 |
| URS | | |
| DRN. BY:djd April 2013<br>DSGN. BY:lr<br>CHKD. BY:kh | 1Q13 Groundwater Contours | Fig. No.<br>3 |

File: P:\ENVIRONMENTAL\SHELL OIL PRODUCT US\SHELL OIL PRODUCTS US 2013\21562850 – ROXANA\21562850-5_SOIL VAPOR AND SVE_AND_ICE OPERATIONS\QUARTERLY MONITORING\1Q13\FIGURES\FIGURE 3 1Q13 GROUNDWATER CONTOUR MAP.DWG Last edited: APR. 19, 13 @ 08:39 a.m. by: david_deguire

File: P:\ENVIRONMENTAL\SHELL OIL PRODUCT US\SHELL OIL PRODUCTS US 2013\21562850 – ROXANA\21562850-5_SOIL VAPOR AND SVE_AND_ICE OPERATIONS\QUARTERLY MONITORING\1Q13\FIGURES\FIGURE 4 VAPOR PORT SCREEN COMPARISON TO GW ELEVATIONS (1Q13).DWG Last edited: APR. 19, 13 @ 08:40 a.m. by: david_deguire

NOTES:

1. COMPREHENSIVE GROUNDWATER ELEVATIONS WERE MEASURED JANUARY 2–4 AND 7–8, 2013. ADDITIONAL GAUGING ACTIVITIES WERE CONDUCTED ON JANUARY 23, 2013 FOR NEWLY INSTALLED GROUNDWATER MONITORING WELLS IN THE VILLAGE OF ROXANA.
2. GROUNDWATER MONITORING WELLS MW–16, MW–17, MW–18, MW–19, MW–20, MW–21, AND MW–22 WERE INSTALLED DURING 4Q12.
3. CONTOUR LINES PRIMARILY GENERATED BY SURFER VERSION 8 MODELING OF GROUNDWATER ELEVATIONS. SOME INTERPRETATION WAS DONE UTILIZING PROFESSIONAL JUDGMENT AND CONTOUR LINES WERE MODIFIED BY HAND.
4. ELEVATIONS ARE RELATIVE TO 1988 USGS DATUM.
5. VMP–47 THROUGH VMP–55 WERE ADDED TO THE QUARTERLY ROXANA SOIL VAPOR MONITORING PROGRAM IN 1Q13.

---

* INDICATES THAT THE LNAPL AND/OR WATER LEVEL IS ABOVE THE TOP OF THE GROUNDWATER MONITORING WELL SCREEN OR THE DEEPEST VAPOR MONITORING POINT SCREEN.

LEGEND

- GROUNDWATER MONITORING WELL LOCATION USED TO GENERATE GROUNDWATER CONTOURS
- GROUNDWATER PIEZOMETER LOCATION USED TO GENERATE GROUNDWATER CONTOURS
- VAPOR MONITORING POINT LOCATION (ELEVATION OF TOP OF THE DEEPEST VAPOR MONITORING POINT SCREEN)
- WRR GROUNDWATER DEPRESSION WELLS
- GROUNDWATER MONITORING WELL LOCATION NOT USED TO GENERATE GROUNDWATER CONTOURS
- GROUNDWATER PIEZOMETER LOCATION NOT USED TO GENERATE GROUNDWATER CONTOURS
- VAPOR MONITORING POINT LOCATION (NOT USED FOR QUARTERLY SAMPLING)
- –401– GROUNDWATER SURFACE CONTOUR NGVD (CONTOUR INTERVAL 0.5 FT)


TYDEMAN AVE
FIRST ST
SECOND ST
THIRD ST
FOURTH ST
FIFTH ST
SIXTH ST
SEVENTH ST
EIGHTH ST
RAND AVENUE
CHAFFER ST
HIGHWAY 111 (S. CENTRAL AVE)
1986 APPROXIMATE BENZENE RELEASE SITE
VILLAGE OF ROXANA
NORTH PROPERTY
WOOD RIVER REFINERY
MAIN PROPERTY
WEST PROPERTY
BP

T–13* 401.50
T–1* 401.23
MW–10* 401.22
VMP-47 415.07
MW–9* 401.28
VMP-1 404.70
ROST–4–PZ(A) 401.51
VMP-2 401.56
ROST–4–PZ(B) 401.77
P–55 400.71
VMP-33
P–60–11 401.12
ROST–4–PZ(D)
VMP-48 413.72
ROST–4–PZ(C) 401.24
VMP-20 404.17
ROST–4–PZ 401.61
P–60–12 400.34
P–60–12S
VMP-42 412.32
ROST–3–MW 400.79
VMP-46
ROST–4–PZ–(E) 401.94
P–60 400.38
P–60–S 401.52
W–77
ROST–4–PZ(F) 401.82
VMP-34
P–68* 400.44
T–24 400.12
VMP-49 412.35
ROST–4–PZ(G) 400.64
MW–11* 400.84
VMP-21 409.43
VMP-3 403.22
P–54 400.56
ROST–5–PZ NA
VMP-35
T–12* 400.04
P–60–13 400.88
P–60–13S
MW–17 399.82
MW–22 400.36
VMP-31 411.82
VMP-32 412.03
VMP-43 411.54
P–69 399.33
VMP-27
ROST–7–PZ
MW–18 399.79
VMP-26
W–85
P–70* 400.11
P–62
VMP-50 413.83
VMP-22 407.15
VMP-4 404.09
VMP-28
VMP-36
MW–19 399.89
P–74* 400.08
P–61* 400.02
ROST–21–PZ
P–59* 400.24
W–78
MW–16 400.34
VMP-44 413.35
GP–9–PZ 400.20
ROST–10–PZ
VMP-23 404.14
VMP-5 404.59
VMP-37
MW–12* 400.74
VMP-51 414.27
MW–20 400.01
P–56 400.37
VMP-45 413.82
MW–2* 400.67
VMP-38
W–79
VMP-6 405.18
MW–1* 400.70
VMP-52 413.73
VMP-24 407.53
VMP-39
VMP-7 405.68
T–6* 400.71
VMP-9 405.73
MW–21
VMP-54 403.65
VMP-8* 406.15
P–57 400.71
MW–3* 400.86
MW–4* 400.87
VMP-53 413.55
VMP-40
P–73 400.72
P–93A* 400.85
P–93B
P–93C
P–93D
VMP-41 407.47
VMP-18 ~434
VMP-19 ~438
MW–7* 401.00
P–72* 401.16
VMP-10 404.72
VMP-11 405.46
VMP-12 405.46
MW–5* 400.94
VMP-29* 394.66
VMP-30* 395.54
VMP-17 ~438.5
VMP-55* 400.55
MW–8* 400.90
VMP-13 406.03
P–58 401.12
VMP-25 400.77
VMP-14 405.94
VMP-16 405.95
VMP-15 404.46
P–66 401.30
401.34 MW–6A*
MW–6B
MW–6C
MW–6D
P–75 401.45
MW–13 401.20
MW–14* 401.73
W–81
P–117* 400.22
P–114
P–116* 400.35
P–115 400.71
P–119* 401.46
T–64 399.91
T–63 400.79
T–62 401.34
T–2
P–71 401.00
S–1 400.44
400
401

0 300
SCALE FEET
N

| | |
|---|---|
| SHELL OIL PRODUCTS US<br>SOIL VAPOR MONITORING PROGRAM<br>ROXANA, ILLINOIS | PROJECT NO.<br>21562850 |
| URS | |
| DRN. BY: djd April 2013<br>DSGN. BY: djd<br>CHKD. BY: kh | 1Q13<br>Vapor Port Screen Comparison to Groundwater Elevations |
| | FIG. NO.<br>4 |

File: P:\ENVIRONMENTAL\SHELL OIL PRODUCT US\SHELL OIL PRODUCTS US 2013\21562850 – ROXANA\21562850-5_SOIL VAPOR AND SVE_AND_ICE OPERATIONS\QUARTERLY MONITORING\1Q13\FIGURES\FIGURE 5 SUMMARY OF BENZENE SOIL VAPOR ANALYTICAL RESULTS (VILLAGE).DWG Last edited: APR. 25, 13 @ 2:03 p.m. by: david_deguire




| Location | Depth | Benzene (mg/m³) 1Q13 |
|---|---|---|
| VMP-48 | 5 ft | 0.0048 |
| | 10 ft | 0.0087 |
| | 20 ft | 0.002 J |
| | 30 ft | 0.097 / 0.12 |

| Location | Depth | Benzene (mg/m³) 2Q12 | 3Q12 | 4Q12 | 1Q13 |
|---|---|---|---|---|---|
| VMP-20 | 5 ft | <0.0037 | 0.048 | 0.0082 | 0.035 |
| | 10 ft | 0.0043 | 0.0033 | 0.005 | 0.0018 J |
| | 25 ft | 0.004 / 0.0041 | 0.001 J | 0.0014 J | <0.0039 |
| | 39.5 ft | Not Sampled[1] | Not Sampled[1] | 0.28 J | 0.24 J |

| Location | Depth | Benzene (mg/m³) 2Q12 | 3Q12 | 4Q12 | 1Q13 |
|---|---|---|---|---|---|
| VMP-21 | 5 ft | 0.58 | 0.003 J | 0.0018 J | 0.002 J |
| | 10 ft | 0.041 | 0.0018 J | 0.0076 | 0.041 / 0.035 |
| | 25 ft | 0.048 | 0.00098 J | 0.0078 | 0.035 / 0.043 |
| | 33 ft | 0.41 | 0.0011 J | 0.012 | 0.0024 J |

| Location | Depth | Benzene (mg/m³) 1Q13 (Initial Sample) | 1Q13 (Resample[5]) |
|---|---|---|---|
| VMP-47 | 5 ft | 0.0018 J | <15 |
| | 10 ft | 0.0051 | 0.11 J |
| | 20 ft | <4 | <9.5 |
| | 30 ft | <2.9 | <15 |

| Location | Depth | Benzene (mg/m³) 2Q12 | 3Q12 | 4Q12 | 1Q13 (Initial Sample[4]) | 1Q13 (Resample[5]) |
|---|---|---|---|---|---|---|
| VMP-1 | 5 ft | 0.014 | 0.084 | <0.0073 | 0.015 J | 4.7 |
| | 8.5 ft | 0.0083 / 0.0072 | 0.058 | 0.0037 J | <0.08 | 0.05 J |
| | 23.5 ft | < 1.5 | < 19 | <38 | 0.0088 J | 14 J |
| | 38.5 ft | Not Sampled[3] | 0.042 | 0.71 J | 0.01 J | 11 J |

| Location | Depth | Benzene (mg/m³) 2Q12 | 3Q12 | 4Q12 | 1Q13 |
|---|---|---|---|---|---|
| VMP-2 | 5 ft | 0.18 | 0.067 | 0.17 | 0.0026 J |
| | 8.5 ft | 0.012 / 0.013 | 0.087 / 0.084 | 0.014 | 0.0022 J |
| | 22 ft | 0.079 | 0.19 | 0.0066 | 0.0018 J |
| | 42 ft | Not Sampled[1] | Not Sampled[1] | Not Sampled[1] | <42 |

| Location | Depth | Benzene (mg/m³) 2Q12 | 3Q12 | 4Q12 | 1Q13 |
|---|---|---|---|---|---|
| VMP-42 | 10 ft | 0.026 J / 0.02 J | 0.038 | 0.046 | 0.0023 J |
| | 20 ft | 0.4 J | 0.038 | 0.0067 / 0.008 | 0.0063 |
| | 30 ft | 3.1 | 0.077 J | 0.011 / 0.0072 | <0.0044 |

| Location | Depth | Benzene (mg/m³) 2Q12 | 3Q12 | 4Q12 | 1Q13 |
|---|---|---|---|---|---|
| VMP-3 | 5 ft | 0.086 | 0.13 | Not Sampled[3] | Not Sampled[3] |
| | 10 ft | 0.027 | 0.0049 | 0.066 | <0.0045 |
| | 22 ft | 0.028 | 0.0093 | 0.14 | 0.052 |
| | 31.5 ft | < 76 / < 73 | < 18 | 0.32 J | <8.2 |
| | 39 ft | Not Sampled[1] | Not Sampled[1] | 47 J | 20 J |

| Location | Depth | Benzene (mg/m³) 2Q12 | 3Q12 | 4Q12 | 1Q13 |
|---|---|---|---|---|---|
| VMP-31 | 5 ft | 0.29 | 0.0043 | 0.015 | 0.0017 J |
| | 10 ft | 0.54 | 0.0026 J | 0.02 | 0.024 |
| | 20 ft | Not Sampled[1] | Not Sampled[1] | 0.64 J | <0.063 |
| | 30 ft | 9.9 / 12 | < 0.3 | 0.044 J | <4.5 |

| Location | Depth | Benzene (mg/m³) 2Q12 | 3Q12 | 4Q12 | 1Q13 |
|---|---|---|---|---|---|
| VMP-43 | 10 ft | 0.56 | 0.044 | 0.022 | Not Sampled[3] |
| | 20 ft | 0.091 | 0.077 | 0.0026 J | 0.0021 J |
| | 30 ft | 0.84 | 0.063 | 0.29 | 0.12 |

| Location | Depth | Benzene (mg/m³) 1Q13 |
|---|---|---|
| VMP-50 | 5 ft | 0.0017 J |
| | 10 ft | 0.0026 J |
| | 20 ft | 0.011 J |
| | 30 ft | 92 |

| Location | Depth | Benzene (mg/m³) 2Q12 | 3Q12 | 4Q12 | 1Q13 |
|---|---|---|---|---|---|
| VMP-4 | 5 ft | 0.31 | 0.28 | 0.31 | 0.0057 |
| | 12 ft | 0.068 | 0.02 | 0.004 J / 0.0038 J | 0.0069 / 0.013 |
| | 23.5 ft | 44 | 56 | 1.6 J | 0.28 J |
| | 39 ft | 67 | 50 | 28 J /26 J | 25 |

| Location | Depth | Benzene (mg/m³) 2Q12 | 3Q12 | 4Q12 | 1Q13 |
|---|---|---|---|---|---|
| VMP-44 | 10 ft | < 1.5 | 4.2 J / 3.3 J[2] | 1.1 | 0.53 |
| | 20 ft | 4.1 | 3 J | 1.5 J | 0.065 J |
| | 30 ft | 32 | 14 / 14 | 4 / 3.9 | 0.037 J |

| Location | Depth | Benzene (mg/m³) 2Q12 | 3Q12 | 4Q12 | 1Q13 |
|---|---|---|---|---|---|
| VMP-5 | 5 ft | 0.017 | 0.0028 J | 0.0043 | 0.014 |
| | 12.5 ft | 0.033 | 0.0018 J | 0.015 | 0.0021 J |
| | 31 ft | 0.08 | 0.0044 | 0.0078 | <0.045 |
| | 40 ft | 0.15 | < 0.032 | 0.011 | 0.0037 J / 0.0037 J |

| Location | Depth | Benzene (mg/m³) 2Q12 | 3Q12 | 4Q12 | 1Q13 |
|---|---|---|---|---|---|
| VMP-45 | 10 ft | 0.052 | 0.005 | 0.0036 J | 0.016 |
| | 20 ft | 0.63 | 0.018 J | 0.0053 | <0.0042 |
| | 30 ft | < 0.12 | < 0.03 | 0.0052 / 0.0051 | 0.0058 J |

| Location | Depth | Benzene (mg/m³) 2Q12 | 3Q12 | 4Q12 | 1Q13 |
|---|---|---|---|---|---|
| VMP-6 | 5 ft | 0.01 | 0.0097 | 0.003 J | 0.037 |
| | 10 ft | 0.007 | 0.0081 | 0.0066 | 0.046 |
| | 31.5 ft | < 0.36 | 0.016 | 0.0049 | 0.004 J |
| | 39 ft | 1.7 | 0.02 / 0.016 | 0.0082 J | 0.066 |

| Location | Depth | Benzene (mg/m³) 2Q12 | 3Q12 | 4Q12 | 1Q13 |
|---|---|---|---|---|---|
| VMP-7 | 5 ft | 0.0089 | 0.12 | 0.0024 J | Not Sampled[3] |
| | 13.5 ft | 0.022 / 0.019 | 0.0087 | 0.0058 | 0.002 J |
| | 29.5 ft | 0.0078 | 0.031 / 0.032 | 0.0098 | Not Sampled[3] |
| | 38 ft | 0.48 / 0.54 | Not Sampled[3] | 0.012 | Not Sampled[3] |

| Location | Depth | Benzene (mg/m³) 2Q12 | 3Q12 | 4Q12 | 1Q13 (Initial Sample) | 1Q13 (Resample[2]) |
|---|---|---|---|---|---|---|
| VMP-9 | 5 ft | 0.0075 | 0.067 | 0.0037 J | 0.0046 | 0.012 J |
| | 11.5 ft | 0.0074 | 0.017 | 0.0066 | 0.002 J / 0.0015 J | |
| | 25.5 ft | 0.0038 | 0.062 / 0.061 | 0.005 | 0.0018 J | |
| | 38.5 ft | 0.01 | 0.21 | 1.2 | 0.0018 J | |

| Location | Depth | Benzene (mg/m³) 2Q12 | 3Q12 | 4Q12 | 1Q13 |
|---|---|---|---|---|---|
| VMP-8 | 5 ft | 0.0025 | 0.00084 J / 0.064[2] | 0.0031 J / 0.0038 J | 0.00077 J |
| | 9.5 ft | 0.0046 | < 0.003 / < 0.0028 | 0.021 | 0.0011 J / <0.0043 |
| | 23.5 ft | 0.0056 | 0.0028 J | 0.018 | 0.01 |
| | 35.5 ft | Not Sampled[1] | Not Sampled[1] | Not Sampled[1] | Not Sampled[1] |

| Location | Depth | Benzene (mg/m³) 1Q13 |
|---|---|---|
| VMP-53 | 5 ft | <0.0041 |
| | 10 ft | 0.059 / 0.017 |
| | 20 ft | 0.086 |
| | 30 ft | <0.0043 |

| Location | Depth | Benzene (mg/m³) 1Q13 |
|---|---|---|
| VMP-49 | 5 ft | <0.0043 |
| | 10 ft | 0.033 |
| | 20 ft | <0.0041 |
| | 30 ft | 0.4 |

| Location | Depth | Benzene (mg/m³) 2Q12 | 3Q12 | 4Q12 | 1Q13 |
|---|---|---|---|---|---|
| VMP-32 | 5 ft | 0.047 | 0.091 | 0.0037 J | 0.0042 |
| | 10 ft | 0.0032 | 0.044 | 0.026 | 0.0051 |
| | 20 ft | 0.034 J | 0.0085 | 0.0014 J | 0.0027 J |
| | 30 ft | 35 | 16 | 0.074 J | <0.18 |

| Location | Depth | Benzene (mg/m³) 2Q12 | 3Q12 | 4Q12 | 1Q13 |
|---|---|---|---|---|---|
| VMP-22 | 5 ft | 0.0085 | 0.0012 J | 0.0025 J / 0.0045 | 0.0093 |
| | 10 ft | 0.0068 | < 0.0035 / < 0.0034 | 0.015 | 0.0018 J |
| | 18 ft | 0.0062 | 0.029 | 0.0036 J | 0.002 J |
| | 38 ft | 0.012 | 0.074 | 0.0096 | 0.0026 J |

| Location | Depth | Benzene (mg/m³) 1Q13 |
|---|---|---|
| VMP-51 | 5 ft | <0.0044 |
| | 10 ft | <0.0044 |
| | 20 ft | 0.0053 |
| | 30 ft | 0.056 / 0.091 |

| Location | Depth | Benzene (mg/m³) 2Q12 | 3Q12 | 4Q12 | 1Q13 |
|---|---|---|---|---|---|
| VMP-23 | 5 ft | 0.0089 | 0.0024 J | 0.011 | 0.0019 J |
| | 10 ft | 0.002 J / 0.0041 | 0.0014 J | 0.011 | <0.0039 |
| | 25 ft | 0.022 | 0.0027 J | 0.0095 | <0.004 |
| | 40 ft | Not Sampled[1] | 0.0081 | 0.018 | <0.0041 |

| Location | Depth | Benzene (mg/m³) 1Q13 |
|---|---|---|
| VMP-52 | 5 ft | 0.073 |
| | 10 ft | <0.0038 |
| | 20 ft | 0.076 J / 0.012 J |
| | 30 ft | 0.0017 J |

| Location | Depth | Benzene (mg/m³) 2Q12 | 3Q12 | 4Q12 | 1Q13 |
|---|---|---|---|---|---|
| VMP-24 | 5 ft | 0.024 | 0.043 | 0.081 | 0.0088 |
| | 10 ft | < 0.0029 J U | 0.0078 | 0.00099 J | 0.0072 |
| | 22 ft | 0.0037 | 0.033 | 0.0013 J | <0.0045 |
| | 34 ft | 0.037 | 0.1 | 0.0067 | 0.0068 |

| Location | Depth | Benzene (mg/m³) 1Q13 |
|---|---|---|
| VMP-54 | 5 ft | 0.0024 J |
| | 10 ft | <0.0045 |
| | 20 ft | 0.0028 J / 0.036 |
| | 30 ft | 0.014 J / 0.0045 J |

| Location | Depth | Benzene (mg/m³) 2Q12 | 3Q12 | 4Q12 | 1Q13 |
|---|---|---|---|---|---|
| VMP-19 | 5 ft | 0.028 | 0.082 | 0.0033 J | 1.5 |

| Location | Depth | Benzene (mg/m³) 2Q12 | 3Q12 | 4Q12 | 1Q13 |
|---|---|---|---|---|---|
| VMP-18 | 8.5 ft | 0.039 | 0.12 | 0.0064 | 0.025 |

NOTES:

1. Not Sampled[1] = VMP SCREEN SUBMERGED BELOW WATER TABLE. NO SAMPLE COLLECTED.
2. Resample[2] = VMP RESAMPLED DUE TO ISSUES WITH CANISTER AT THE LABORATORY.
3. Not Sampled[3] = FAILED HELIUM LEAK TEST.
4. DATA NOT REPRESENTATIVE BASED ON INTEGRITY ASSESSMENT[4].
5. GRAB SAMPLE TAKEN[5].
6. J = RESULT IS ESTIMATED
   < = NOT DETECTED AT INDICATED REPORTING LIMIT.
7. MULTIPLE RESULTS (e.g., 44Ø/41Ø) INDICATE DUPLICATE SAMPLES.
8. VMP–47 THROUGH VMP–55 WERE ADDED TO THE QUARTERLY ROXANA SOIL VAPOR MONITORING PROGRAM IN 1Q13.

LEGEND

- VAPOR MONITORING POINT LOCATION
- VAPOR MONITORING POINT LOCATION (NOT USED FOR QUARTERLY SAMPLING)
- BENZENE CONCENTRATION > SCREENING CRITERION (Ø.37 mg/m³), FOR RESIDENTIAL.

Ø 2ØØ
SCALE FEET

N

| | | |
|---|---|---|
| SHELL OIL PRODUCTS US<br>SOIL VAPOR MONITORING PROGRAM<br>ROXANA, ILLINOIS | | PROJECT NO.<br>21562850 |
| URS | | |
| DRN. BY: djd April 2013<br>DSGN. BY: djd<br>CHKD. BY: kh | 1Q13 Summary of Benzene Soil Vapor Analytical Results – Village of Roxana | FIG. NO.<br>5 |

LEGEND

- VAPOR MONITORING POINT LOCATION
- VAPOR MONITORING POINT LOCATION (NOT USED FOR QUARTERLY SAMPLING)
- BENZENE CONCENTRATION > SCREENING CRITERION (2.8 mg/m³), FOR INDUSTRIAL/COMMERCIAL.

NOTES:

1. Not Sampled[1] = VMP SCREEN SUBMERGED BELOW WATER TABLE. NO SAMPLE COLLECTED.
2. Not Sampled[3] = FAILED HELIUM LEAK TEST.
3. J = RESULT IS ESTIMATED
   < = NOT DETECTED AT INDICATED REPORTING LIMIT.
4. MULTIPLE RESULTS (e.g., 440/410) INDICATE DUPLICATE SAMPLES.
5. VMP-47 THROUGH VMP-55 WERE ADDED TO THE QUARTERLY ROXANA SOIL VAPOR MONITORING PROGRAM IN 1Q13.

VMP-34 VMP-3 VMP-21 VMP-49 VMP-35 VMP-31 VMP-32 VMP-43 VMP-27 VMP-26 VMP-50 VMP-22 VMP-4 VMP-28 VMP-36 VMP-44 VMP-37 VMP-51 VMP-5 VMP-45 VMP-38 VMP-6 VMP-7 VMP-39 VMP-54 VMP-8 VMP-53 VMP-40 VMP-18 VMP-19 VMP-41 VMP-10 VMP-11 VMP-17 VMP-12 VMP-29 VMP-13 VMP-55 VMP-30 VMP-14 VMP-25 VMP-15 VMP-16

A–28 A–27

FOURTH ST
FIFTH ST
SIXTH ST
SEVENTH ST
EIGHTH ST
CHAFFER ST
HIGHWAY 111 (S. CENTRAL AVE)

VILLAGE
VILLAGE OF ROXANA
NORTH PROPERTY
WOOD RIVER REFINERY
PUBLIC WORKS YARD
MAIN PROPERTY
WEST PROPERTY
BP
RAND AVENUE

1986 APPROXIMATE BENZENE RELEASE SITE

| Location | Depth | Benzene (mg/m³) 2Q12 | 3Q12 | 4Q12 | 1Q13 |
|---|---|---|---|---|---|
| VMP-10 | 5 ft | 0.0078 | 0.0025 J | 1.9 | 0.0017 J / <0.005 |
| | 10 ft | 0.0096 | 0.01 | 0.95 | 0.018 |
| | 20 ft | 0.011 | 0.0084 | 0.16 | 0.0078 |
| | 30 ft | 0.0039 | 0.013 | 0.029 | 0.0091 |

| Location | Depth | Benzene (mg/m³) 2Q12 | 3Q12 | 4Q12 | 1Q13 |
|---|---|---|---|---|---|
| VMP-11 | 5 ft | 0.061 | 0.006 | 0.003 J | <0.23 |
| | 8 ft | 0.11 | 0.0017 J | 0.012 / 0.012 | <0.31 |
| | 29 ft | 0.14 | 0.018 | 0.0015 J | 0.049 |
| | 38 ft | 370 / 380 | 170 | 0.01 | 0.0074 |

| Location | Depth | Benzene (mg/m³) 2Q12 | 3Q12 | 4Q12 | 1Q13 |
|---|---|---|---|---|---|
| VMP-41 | 10 ft | | 0.16 | 0.034 | 0.0018 J |
| | 20 ft | | 0.039 / 0.044 | 0.027 / 0.027 | 0.0044 J |
| | 30 ft | | 0.34 | 0.041 | 0.0077 |

| Location | Depth | Benzene (mg/m³) 2Q12 | 3Q12 | 4Q12 | 1Q13 |
|---|---|---|---|---|---|
| VMP-17 | 5 ft | 0.021 | 0.11 | 0.0043 J | 0.71 / 1 |

| Location | Depth | Benzene (mg/m³) 2Q12 | 3Q12 | 4Q12 | 1Q13 |
|---|---|---|---|---|---|
| VMP-29 | 10 ft | | < 0.034 | 0.47 | 0.053 |
| | 20 ft | | 0.066 J / 0.047 J | 0.12 | 0.026 |
| | 30 ft | | 0.057 J | 0.11 J | 0.084 |
| | 40 ft | | Not Sampled[1] | Not Sampled[1] | Not Sampled[1] |

| Location | Depth | Benzene (mg/m³) 2Q12 | 3Q12 | 4Q12 | 1Q13 |
|---|---|---|---|---|---|
| VMP-30 | 10 ft | | 0.016 J | 0.016 | 0.0018 J |
| | 20 ft | | 2.1 | 0.35 | 0.11 |
| | 30 ft | | 7.2 | 5.4 | 1.4 |
| | 40 ft | | Not Sampled[1] | Not Sampled[1] | Not Sampled[1] |

| Location | Depth | Benzene (mg/m³) 2Q12 | 3Q12 | 4Q12 | 1Q13 |
|---|---|---|---|---|---|
| VMP-25 | 5 ft | 0.066 | 0.21 | 0.0017 J | 0.0048 |
| | 9.5 ft | Not Sampled[1] | Not Sampled[1] | Not Sampled[1] | Not Sampled[1] |
| | 21 ft | 37 | 48 | 48 J | 95 |
| | 31 ft | Not Sampled[1] | Not Sampled[1] | Not Sampled[1] | 90 |

| Location | Depth | Benzene (mg/m³) 1Q13 |
|---|---|---|
| VMP-55 | 5 ft | Not Sampled[1] |
| | 10 ft | Not Sampled[1] |
| | 20 ft | 1.3 J |
| | 30 ft | Not Sampled[1] |

| Location | Depth | Benzene (mg/m³) 2Q12 | 3Q12 | 4Q12 | 1Q13 |
|---|---|---|---|---|---|
| VMP-13 | 5 ft | 0.0027 J | 0.0039 / 0.004 | 0.017 | 0.0038 J |
| | 10.5 ft | 0.0088 | 0.0078 | 0.025 / 0.023 | 0.0021 J |
| | 21.5 ft | 0.098 | 0.009 | 0.088 | 0.0088 |
| | 29.5 ft | 2,300 | 2,600 | 630 | 580 |

| Location | Depth | Benzene (mg/m³) 2Q12 | 3Q12 | 4Q12 | 1Q13 |
|---|---|---|---|---|---|
| VMP-15 | 5 ft | 0.063 | 0.005 | 0.013 | 0.004 J |
| | 21.5 ft | 0.91 | 0.25 J | 0.24 J / 0.24 J | 0.0077 J |
| | 25.5 ft | Not Sampled[2] | 0.024 J | 0.034 | <0.14 |
| | 29 ft | Not Sampled[1] | 0.17 J | 0.026 | <0.086 |

| Location | Depth | Benzene (mg/m³) 2Q12 | 3Q12 | 4Q12 | 1Q13 |
|---|---|---|---|---|---|
| VMP-14 | 5 ft | 0.026 | 0.43 | 0.025 | <0.0043 |
| | 11.5 ft | 0.0068 / 0.0068 | < 1 | 0.0039 J | <0.0041 |
| | 20 ft | 13,000 | 13,000 | 9,400 | 12,000 |
| | 29 ft | 22,000 | 21,000 | 9,400 | 13,000 J / 54,000 J |

SCALE 0 200 FEET

N

SHELL OIL PRODUCTS US
SOIL VAPOR MONITORING PROGRAM
ROXANA, ILLINOIS

PROJECT NO. 21562850


URS

DRN. BY: djd April 2013
DSGN. BY: djd
CHKD. BY: kh

1Q13 Summary of Benzene Soil Vapor Analytical Results– Roxana Public Works Yard Area

FIG. NO. 6

File: P:\ENVIRONMENTAL\SHELL OIL PRODUCT US\SHELL OIL PRODUCTS US 2013\21562850 – ROXANA\21562850-5_SOIL VAPOR AND SVE_AND_ICE OPERATIONS\QUARTERLY MONITORING\1Q13\FIGURES\FIGURE 6 SUMMARY OF BENZENE SOIL VAPOR ANALYTICAL RESULTS (PUBLIC WORKS YARD).DWG Last edited: APR. 25, 13 @ 2:08 p.m. by: david_deguire




| Location | Depth | Benzene (mg/m³) 2Q12 | 3Q12 | 4Q12 | 1Q13 |
|---|---|---|---|---|---|
| VMP-12 | 5 ft | 0.063 | 0.12 J / 0.0018 J | 0.025 | 0.012 |
| | 11.5 ft | 0.065 | 0.044 | 0.0098 | 0.0008 J |
| | 25 ft | 500 | 24 / 30 | 0.47 J | 5.8 J |
| | 39 ft | 1,400 | 3,100 | 1,200 | 4,100 |

| Location | Depth | Benzene (mg/m³) 2Q12 | 3Q12 | 4Q12 | 1Q13 |
|---|---|---|---|---|---|
| VMP-16 | 5 ft | 6 | 8.8 J | 0.63 J | 0.17 J |
| | 13.5 ft | 7.6 J | 27 | 22 J | 21 J |
| | 19 ft | 12 | 14 | 14 J | 17 J |
| | 31 ft | 15 | 16 | 12 J | 29 |

LEGEND

- VAPOR MONITORING POINT LOCATION
- VAPOR MONITORING POINT LOCATION (NOT USED FOR QUARTERLY SAMPLING)
- BENZENE CONCENTRATION > SCREENING CRITERION (2.8 mg/m³), FOR INDUSTRIAL/COMMERCIAL.

NOTES:

1. J = RESULT IS ESTIMATED < = NOT DETECTED AT INDICATED REPORTING LIMIT.
2. MULTIPLE RESULTS (e.g., 440/410) INDICATE DUPLICATE SAMPLES.
3. VMP-47 THROUGH VMP-55 WERE ADDED TO THE QUARTERLY ROXANA SOIL VAPOR MONITORING PROGRAM IN 1Q13.

SHELL OIL PRODUCTS US
SOIL VAPOR MONITORING PROGRAM
ROXANA, ILLINOIS

PROJECT NO. 21562850

URS


DRN. BY: djd April 2013
DSGN. BY: djd
CHKD. BY: kh

1Q13 Summary of Benzene Soil Vapor Analytical Results – WRR

FIG. NO. 7

File: P:\ENVIRONMENTAL\SHELL OIL PRODUCT US\SHELL OIL PRODUCTS US 2013\21562850 - ROXANA\21562850-5_SOIL VAPOR AND SVE_AND_ICE OPERATIONS\QUARTERLY MONITORING\1Q13\FIGURES\FIGURE 7 SUMMARY OF BENZENE SOIL VAPOR ANALYTICAL RESULTS (WRR).DWG Last edited: APR. 19, 13 @ 08:44 a.m. by: david_deguire

PLAN VIEW (DEPICTING OFFSETS)




NOTES:
1. SOIL VAPOR BENZENE CONCENTRATIONS FROM THE 3Q12 SAMPLING EVENT ARE DEPICTED IN GREEN. VALUES DEPICTED IN ORANGE EXCEED BENZENE SCREENING CRITERION (0.37 mg/m³ FOR VMP 1–9, 31, 32 AND 42–45 [RESIDENTIAL] AND 2.8 mg/m³ FOR VMP–11 [COMMERCIAL/INDUSTRIAL]).
2. GROUNDWATER ELEVATIONS SHOWN ON THIS CROSS–SECTION ARE BASED ON GROUNDWATER GAUGING DATA COLLECTED ON JANUARY 2–4 AND 7–8, 2013. ADDITIONAL GAUGING ACTIVITIES WERE CONDUCTED ON JANUARY 23 2013 FOR NEWLY INSTALLED GROUNDWATER MONITORING WELLS IN THE VILLAGE OF ROXANA.
3. THIS CROSS–SECTION IS PRIMARILY BASED ON THE INTERPRETATION OF CPT DATA COLLECTED BY URS DURING THE 2006 AND 2009 INVESTIGATION ACTIVITIES. BORING LOGS DEVELOPED DURING OTHER DRILLING TECHNIQUES (E.G. AUGER AND GEOPROBE) WERE USED TO SUPPLEMENT CPT DATA.
4. THE DEPTH AND THE THICKNESS OF INDIVIDUAL STRATA WERE OBSERVED IN CPT LOGS GENERATED AT NEARBY LOCATIONS. THEREFORE, WELL SCREENS MAY APPEAR TO BE PARTIALLY WITHIN CLAY LAYERS OR SHALLOW/DEEPER WITHIN A PERMEABLE STRATUM THAN ACTUAL CONDITIONS DUE TO MAP PROJECTIONS.
5. CROSS–SECTION TRACE LINE SHOWS DISTANCE AND DIRECTION EACH POINT WAS PROJECTED TO CONSTRUCT THIS CROSS–SECTION.

LEGEND

- STRATUM BOUNDARY ASSUMED
- FILL (INCLUDES CINDERS, GRAVEL, CLAY, AND/OR SILTY CLAY.)
- CLAY PROJECTED BETWEEN POINTS (INCLUDES SILTY CLAY AND SANDY CLAY)
- SAND PROJECTED BETWEEN POINTS (INCLUDES SILTY SAND AND CLAYEY SAND)
- VAPOR PORT SCREENS
- GROUNDWATER WELL SCREEN
- GROUNDWATER WATER LEVEL
- POTENTIOMETRIC SURFACE – ESTIMATED

KEYMAP
NOT TO SCALE




Ø 10
VERTICAL SCALE FEET

Ø 100
APPROXIMATE HORIZONTAL SCALE FEET

SHELL OIL PRODUCTS US
SOIL VAPOR MONITORING PROGRAM
ROXANA, ILLINOIS

PROJECT NO. 21562850

URS

DRN. BY: djd April 2013
DSGN. BY: djd
CHKD. BY: kh

1Q13 Cross–Section with Benzene Soil Vapor Analytical Results – Chaffer Street

FIG. NO. 8

File: P:\ENVIRONMENTAL\SHELL OIL PRODUCT US\SHELL OIL PRODUCTS US 2013\21562850 – ROXANA\21562850–5_SOIL VAPOR AND SVE AND ICE OPERATIONS\QUARTERLY MONITORING\1Q13\FIGURES\FIGURE 8 TYPICAL CROSS–SECTION WITH BENZENE SOIL VAPOR ANALYTICAL RESULTS.DWG Last edited APR. 25, 13 @ 2:11 p.m. by: dsvis_dbguire


File: P:\ENVIRONMENTAL\SHELL OIL PRODUCT US\SHELL OIL PRODUCTS US 2013\21562850 – ROXANA\21562850-5_SOIL VAPOR AND SVE_AND_ICE OPERATIONS\QUARTERLY MONITORING\1Q13\FIGURES\FIGURE 9 SUMMARY OF SOIL VAPOR BENZENE-5FT BGS.DWG Last edited: APR. 19, 13 @ 08:47 a.m. by: david_deguire

LEGEND

- VAPOR MONITORING POINT
- VAPOR MONITORING POINT LOCATIONS (NOT USED FOR QUARTERLY SAMPLING)
- EXTENT OF EVS MODEL DATA SET
- MODELED SOIL VAPOR CONCENTRATION BENZENE ($mg/m^3$)

NOTE:

1. IMAGES GENERATED UTILIZING CTECH ENVIRONMENTAL VISUALIZATION SYSTEM MODELING SOFTWARE. CONCENTRATIONS BETWEEN KNOWN DATA POINTS (E.G. VMP WELLS) ARE INTERPOLATIONS AND EXTRAPOLATIONS OF THE MEASURED DATA.
2. THE LOWEST CONCENTRATION CONTOUR REPRESENTS THE SCREENING CRITERION FOR RESIDENTIAL PROPERTIES (Ø.37 $mg/m^3$).
3. DATA SHOWN REPRESENT A HORIZONTAL SLICE OF A 3D MODEL.
4. SOME INTERPRETATION WAS COMPLETED UTILIZING PROFESSIONAL JUDGMENT AND CONTOUR LINES WERE MODIFIED BY HAND (e.g., DASH LINES).
5. NON-DETECT VALUES ARE MODELED AT 1/2 THE REPORTING LIMIT.
6. VMP-47 THROUGH VMP-55 WERE ADDED TO THE QUARTERLY ROXANA SOIL VAPOR MONITORING PROGRAM IN 1Q13.




| | | |
|---|---|---|
| SHELL OIL PRODUCTS US<br>SOIL VAPOR MONITORING PROGRAM<br>ROXANA, ILLINOIS | | PROJECT NO.<br>21562850 |
| URS | | |
| DRN. BY: djd April 2013<br>DSGN. BY: djd/nm<br>CHKD. BY: kh | 1Q13 Benzene Soil Vapor Distribution– 5 ft bgs | FIG. NO.<br>9 |

File: P:\ENVIRONMENTAL\SHELL OIL PRODUCT US\SHELL OIL PRODUCTS US 2013\21562850 – ROXANA\21562850-5_SOIL VAPOR AND SVE_AND_ICE OPERATIONS\QUARTERLY MONITORING\1Q13\FIGURES\FIGURE 10 SUMMARY OF SOIL VAPOR BENZENE 10FT BGS.DWG Last edited: APR. 19, 13 @ 08:47 a.m. by: david_deguire

LEGEND

- VAPOR MONITORING POINT
- VAPOR MONITORING POINT LOCATIONS (NOT USED FOR QUARTERLY SAMPLING)
- EXTENT OF EVS MODEL DATA SET
- MODELED SOIL VAPOR CONCENTRATION BENZENE (mg/m$^3$)

NOTE:

1. IMAGES GENERATED UTILIZING CTECH ENVIRONMENTAL VISUALIZATION SYSTEM MODELING SOFTWARE. CONCENTRATIONS BETWEEN KNOWN DATA POINTS (E.G. VMP WELLS) ARE INTERPOLATIONS AND EXTRAPOLATIONS OF THE MEASURED DATA.
2. THE LOWEST CONCENTRATION CONTOUR REPRESENTS THE SCREENING CRITERION FOR RESIDENTIAL PROPERTIES (Ø.37 mg/m$^3$).
3. DATA SHOWN REPRESENT A HORIZONTAL SLICE OF A 3D MODEL.
4. SOME INTERPRETATION WAS COMPLETED UTILIZING PROFESSIONAL JUDGMENT AND CONTOUR LINES WERE MODIFIED BY HAND (e.g., DASH LINES).
5. NON-DETECT VALUES ARE MODELED AT 1/2 THE REPORTING LIMIT.
6. VMP-47 THROUGH VMP-55 WERE ADDED TO THE QUARTERLY ROXANA SOIL VAPOR MONITORING PROGRAM IN 1Q13.

VMP-47 VMP-1 VMP-33 VMP-2 VMP-20 VMP-48 VMP-46 VMP-42 VMP-34 VMP-21 VMP-49 VMP-3 VMP-35 VMP-31 VMP-32 VMP-43 VMP-27 VMP-26 VMP-22 VMP-50 VMP-4 VMP-28 VMP-36 0.37 VMP-44 VMP-37 VMP-23 VMP-51 VMP-5 VMP-45 VMP-38 VMP-6 VMP-52 VMP-7 VMP-39 VMP-24 VMP-9 VMP-8 VMP-54 VMP-53 VMP-40 VMP-18 VMP-19 VMP-41 VMP-11 VMP-10 VMP-17 VMP-12 VMP-29 VMP-30 VMP-13 VMP-55 VMP-14 VMP-25 0.37 1.0 VMP-15 VMP-16

SECOND ST
THIRD ST
FOURTH ST
FIFTH ST
SIXTH ST
SEVENTH ST
EIGHTH ST
HIGHWAY 111 (S. CENTRAL AVE)
CHAFFER ST
RAND AVENUE
1986 APPROXIMATE BENZENE RELEASE SITE
VILLAGE OF ROXANA
PUBLIC WORKS YARD
NORTH PROPERTY
WOOD RIVER REFINERY
MAIN PROPERTY
WEST PROPERTY
BP
A–28
A–27

Ø 200Ø
SCALE FEET
N

| | |
|---|---|
| SHELL OIL PRODUCTS US<br>SOIL VAPOR MONITORING PROGRAM<br>ROXANA, ILLINOIS | PROJECT NO.<br>21562850 |
| URS | |
| DRN. BY:djd April 2013<br>DSGN. BY:nm<br>CHKD. BY:kh | 1Q13 Benzene Soil Vapor Distribution– 10 ft bgs<br>FIG. NO.<br>10 |


File: P:\ENVIRONMENTAL\SHELL OIL PRODUCT US\SHELL OIL PRODUCTS US 2013\21562850 – ROXANA\21562850-5_SOIL VAPOR AND SVE_AND_ICE OPERATIONS\QUARTERLY MONITORING\1Q13\FIGURES\FIGURE 11 SUMMARY OF SOIL VAPOR BENZENE 25FT BGS.DWG Last edited: APR. 19, 13 @ 08:48 a.m. by: david_deguire

LEGEND

- VAPOR MONITORING POINT
- VAPOR MONITORING POINT LOCATIONS (NOT USED FOR QUARTERLY SAMPLING)
- EXTENT OF EVS MODEL DATA SET
- MODELED SOIL VAPOR CONCENTRATION BENZENE ($mg/m^3$)

NOTE:

1. IMAGES GENERATED UTILIZING CTECH ENVIRONMENTAL VISUALIZATION SYSTEM MODELING SOFTWARE. CONCENTRATIONS BETWEEN KNOWN DATA POINTS (E.G. VMP WELLS) ARE INTERPOLATIONS AND EXTRAPOLATIONS OF THE MEASURED DATA.
2. THE LOWEST CONCENTRATION CONTOUR REPRESENTS THE SCREENING CRITERION FOR RESIDENTIAL PROPERTIES (Ø.37 $mg/m^3$).
3. DATA SHOWN REPRESENT A HORIZONTAL SLICE OF A 3D MODEL.
4. SOME INTERPRETATION WAS COMPLETED UTILIZING PROFESSIONAL JUDGMENT AND CONTOUR LINES WERE MODIFIED BY HAND (e.g., DASH LINES).
5. NON-DETECT VALUES ARE MODELED AT 1/2 THE REPORTING LIMIT.
6. VMP-47 THROUGH VMP-55 WERE ADDED TO THE QUARTERLY ROXANA SOIL VAPOR MONITORING PROGRAM IN 1Q13.




| | | |
|---|---|---|
| SHELL OIL PRODUCTS US<br>SOIL VAPOR MONITORING PROGRAM<br>ROXANA, ILLINOIS | | PROJECT NO.<br>21562850 |
| URS | | |
| DRN. BY: djd April 2013<br>DSGN. BY: djd/nm<br>CHKD. BY: kh | 1Q13 Benzene Soil Vapor Distribution– 25 ft bgs | FIG. NO.<br>11 |

File: P:\ENVIRONMENTAL\SHELL OIL PRODUCT US\SHELL OIL PRODUCTS US 2013\21562850 – ROXANA\21562850-5_SOIL VAPOR AND SVE_AND_ICE OPERATIONS\QUARTERLY MONITORING\1Q13\FIGURES\FIGURE 12 DISSOLVED PHASE BENZENE CONCENTRATIONS IN GROUNDWATER.DWG Last edited: APR. 19, 13 @ 08:49 a.m. by: david_deguire

## LEGEND

- GROUNDWATER MONITORING WELL SAMPLING LOCATION
- GROUNDWATER MONITORING WELL LOCATION NOT SAMPLED
- GROUNDWATER MONITORING WELL LNAPL THICKNESS
- GROUNDWATER PIEZOMETER SAMPLING LOCATION
- GROUNDWATER PIEZOMETER LOCATION NOT SAMPLED
- GROUNDWATER PIEZOMETER LNAPL THICKNESS
- LNAPL THICKNESS CONTOUR (FEET)
- EXTENT OF EVS MODEL DATA SET
- 50.0 GROUNDWATER CONCENTRATION BENZENE (mg/L)

LNAPL THICKNESS WAS MEASURED DURING THE COMPREHENSIVE GROUNDWATER MONITORING GAUGING EVENT ON JANUARY 2–4 AND 7–8, 2013. LNAPL THICKNESS WAS ALSO MEASURED DURING ADDITIONAL GAUGING ACTIVITIES CONDUCTED ON JANUARY 23, 2013 AND FEBRUARY 11, 2013 FOR NEWLY INSTALLED GROUNDWATER MONITORING WELLS IN THE VILLAGE OF ROXANA. REFER TO TABLE 1 FOR GROUNDWATER GAUGING INFORMATION.

NOTES:

1. IMAGES GENERATED UTILIZING CTECH ENVIRONMENTAL VISUALIZATION SYSTEM MODELING SOFTWARE. CONCENTRATIONS BETWEEN KNOWN DATA POINTS (E.G. GROUNDWATER MONITORING WELLS) ARE INTERPOLATIONS AND EXTRAPOLATIONS OF THE MEASURED DATA. SOME INTERPRETATION WAS COMPLETED UTILIZING PROFESSIONAL JUDGEMENT AND CONTOUR LINES WERE MODIFIED BY HAND.
2. ALL RESULTS SHOWN IN mg/L.
3. ANALYTICAL REPORTING LIMITS ARE SHOWN FOR SAMPLES WITH NON-DETECT RESULTS (e.g., <Ø.ØØØ5 mg/L).
4. J = THE TARGET ANALYTE WAS DETECTED BELOW THE REPORTING LIMIT AND THE RESULT IS ESTIMATED.
   U = RESULTS IS NON-DETECT.
5. NON-DETECT VALUES ARE MODELED AT HALF THE REPORTING LIMIT.
6. MULTIPLE RESULTS (e.g. 123Ø/132Ø) INDICATE DUPLICATE SAMPLES.
7. GROUNDWATER MONITORING WELLS MW-16 AND MW-22 WERE ADDED TO THE GROUNDWATER MONITORING PROGRAM IN 1Q13.
8. PIEZOMETER ROST-3-PZ WAS REPLACED BY GROUNDWATER MONITORING WELL ROST-3-MW DURING 4Q12.
9. GROUNDWATER MONITORING WELL P-55 WAS REPLACED DURING 4Q12.

SECOND ST
THIRD ST
FOURTH ST
FIFTH ST
SIXTH ST
SEVENTH ST
EIGHTH ST
HIGHWAY 111 (S. CENTRAL AVE)
CHAFFER ST
VILLAGE OF ROXANA
BP
NORTH PROPERTY
WOOD RIVER REFINERY
MAIN PROPERTY
WEST PROPERTY
PUBLIC WORKS YARD
RAND AVENUE
1986 APPROXIMATE BENZENE RELEASE SITE

MW-9 <Ø.ØØØ5
MW-10 <Ø.ØØØ5/Ø.ØØ3
P-55 Ø.571/Ø.538
P-6Ø-11
ROST-4-PZ(C) <Ø.ØØØ5
ROST-3-MW Ø.ØØ51J
ROST-4-PZ
ROST-4-PZ(E)
P-6Ø-S Ø.61
0.10
P-6Ø
P-68 Ø.4
A-28
1.00
T-24 2.5
MW-11 <Ø.ØØØ5
P-54 <Ø.ØØØ5
MW-17
T-12 2.Ø3
P-69
MW-22 2.12/2.Ø9
P-7Ø
A-27
MW-18
MW-19
P-59 12.1
P-74 4.99
1.00
P-61 2.13
MW-16 Ø.ØØØ57J
MW-12 <Ø.ØØØ5
MW-2Ø
P-56 Ø.191
MW-1 <Ø.ØØØ5
MW-2 Ø.Ø192
T-6
MW-3 Ø.ØØ14
MW-4 9.Ø4J/8.96J 21.4
MW-21
P-57 114
P-93A 1Ø1/98.5
P-93B 415
P-93C <Ø.ØØØ5
P-93D Ø.1Ø6
MW-5 Ø.ØØ72
MW-7 123Ø/132Ø
MW-8 112ØJ
P-58 552
MW-13 Ø.ØØ67J
MW-6A Ø.Ø276
MW-6B <Ø.ØØØ5
MW-6C <Ø.ØØØ5UJ
MW-6D Ø.ØØØ53J
P-66 Ø.Ø896
P-75
P-114 <Ø.ØØØ5
MW-14 Ø.ØØ17
P-116
P-115

0.005
0.05
0.5
5.0
50.0
500.0

Ø 2ØØ
SCALE FEET
N


| | |
|---|---|
| SHELL OIL PRODUCTS US<br>SOIL VAPOR MONITORING PROGRAM<br>ROXANA, ILLINOIS | PROJECT NO.<br>21562850 |
| URS | |
| DRN. BY: djd April 2013<br>DSGN. BY: djd/nm<br>CHKD. BY: | 1Q13 Dissolved Phase Benzene Concentrations in Groundwater |
| | FIG. NO.<br>12 |

File: P:\ENVIRONMENTAL\SHELL OIL PRODUCT US\SHELL OIL PRODUCTS US 2013\21562850 – ROXANA\21562850-5_SOIL VAPOR AND SVE_AND_ICE OPERATIONS\QUARTERLY MONITORING\1Q13\FIGURES\FIGURE 13 THICKNESS OF LNAPL (1Q13).DWG Last edited: APR. 19, 13 @ 08:51 a.m. by: david_deguire

LEGEND

- GROUNDWATER MONITORING WELL LOCATION, LNAPL THICKNESS IN FEET
- GROUNDWATER MONITORING WELL LOCATION (NO LNAPL OBSERVED UNLESS OTHERWISE NOTED)
- GROUNDWATER PIEZOMETER LOCATION, LNAPL THICKNESS IN FEET
- GROUNDWATER PIEZOMETER SAMPLING LOCATION (NO LNAPL OBSERVED UNLESS OTHERWISE NOTED)
- OIL RECOVERY WELL
- LNAPL THICKNESS CONTOUR (FEET)
- * INDICATES THAT THE LNAPL AND/OR WATER LEVEL IS ABOVE THE TOP OF WELL SCREEN

NOTE:
1. THIS MAP DEPICTS THE EXTENT AND THICKNESS OF LNAPL BENEATH THE WEST FENCE LINE AREA. REFER TO TABLE 1 FOR GROUNDWATER GAUGING INFORMATION.
2. LNAPL THICKNESS WAS MEASURED DURING THE COMPREHENSIVE GROUNDWATER MONITORING GAUGING EVENT ON JANUARY 2–4 AND 7–8, 2013. LNAPL THICKNESS WAS ALSO MEASURED DURING ADDITIONAL GAUGING ACTIVITIES CONDUCTED ON JANUARY 23, 2013 AND FEBRUARY 11, 2013 FOR NEWLY INSTALLED GROUNDWATER MONITORING WELLS IN THE VILLAGE OF ROXANA.
3. GROUNDWATER MONITORING WELLS MW–16, MW–17, MW–18, MW–19, MW–20, MW–21, AND MW–22 WERE INSTALLED DURING 4Q12.




| | | |
|---|---|---|
| SHELL OIL PRODUCTS US<br>SOIL VAPOR MONITORING PROGRAM<br>ROXANA, ILLINOIS | | PROJECT NO.<br>21562850 |
| URS | | |
| DRN. BY: djd April 2013<br>DSGN. BY: lr<br>CHKD. BY: kh | 1Q13 Thickness of LNAPL | FIG. NO.<br>13 |

(S. CENTRAL AVE) HIGHWAY 111

VILLAGE OF ROXANA

1986 APPROXIMATE BENZENE RELEASE SITE

EIGHTH ST | SEVENTH ST | SIXTH ST | FIFTH ST | FOURTH ST | THIRD ST | SECOND ST

CHAFFER ST

PUBLIC WORKS PROPERTY

VMP-25 VMP-55 VMP-15 VMP-14 VMP-16 VMP-54 VMP-8 VMP-24 VMP-53 VMP-52 VMP-6 VMP-45 VMP-5 VMP-44 VMP-4 VMP-22 VMP-23 VMP-51 VMP-50 VMP-21 VMP-20 VMP-49 VMP-48 VMP-47 VMP-46 VMP-42 VMP-43 VMP-31 VMP-3 VMP-2 VMP-1 VMP-33 VMP-32 VMP-29 VMP-41 VMP-10 VMP-30 VMP-13 VMP-18 VMP-11 VMP-17 VMP-19 VMP-9 VMP-7 VMP-38 VMP-39 VMP-40 VMP-12 VMP-37 VMP-28 VMP-36 VMP-27 VMP-35 VMP-34

SVE-23 SVE-24 SVE-22 SVE-2 SVE-26 SVE-21 SVE-27 SVE-36 SVE-20 SVE-19 SVE-18 SVE-17 SVE-16 SVE-15 SVE-14 SVE-35 SVE-13 SVE-12 SVE-33 SVE-1 SVE-11 SVE-32 SVE-10 SVE-26 SVE-31 SVE-9 SVE-30 SVE-8 SVE-29 SVE-28 SVE-7 SVE-6 SVE-5 SVE-4 SVE-3 SVE-25

CONEX

RTO

ABOVE GROUND STORAGE TANKS

MAIN PROPERTY

F-76 F-78 F-77 F-73 F-74 A-22 A-27 A-28

WOOD RIVER REFINERY

NORTH PROPERTY

ASPHALT PARKING

OMC BUILDING

BUILDING

METER SHELTER

| LEG NO. | SVE WELLS | COLOR | WELL SYMBOL |
|---|---|---|---|
| 1 | SVE-5 THROUGH SVE-9 | RED | |
| 2 | SVE-3, SVE-4, SVE-25 & SVE-10 THROUGH SVE-12 | BLUE | |
| 3 | SVE-13 THROUGH SVE-19 & SVE-36 | GREEN | |
| 4 | SVE-20 THROUGH SVE-27 | TEAL | |
| 5 | SVE-28 THROUGH SVE-33 | PURPLE | |
| 6 | SVE-34 THROUGH SVE-35 | BROWN | |

LEGEND:

- SVE EXTRACTION WELL (SEE TABLE FOR COLOR LEGEND)
- VAPOR MONITORING POINT (VMP)
- PROPERTY BOUNDARY

N

80 0 80

SCALE IN FEET

| | |
|---|---|
| SHELL OIL PRODUCTS US<br>SOIL VAPOR MONITORING PROGRAM<br>ROXANA, ILLINOIS | PROJECT NO.<br>21562850 |
| URS | |
| DRN. BY: djd April 2013<br>DSGN. BY: lv<br>CHKD. BY: kh | 1Q13 SVE System Layout — FIG. NO. 14 |

File: P:\ENVIRONMENTAL\SHELL OIL PRODUCT US\SHELL OIL PRODUCTS US 2013\21562850 - ROXANA\21562850-5_SOIL VAPOR AND SVE_AND_ICE OPERATIONS\QUARTERLY MONITORING\1Q13\FIGURES\FIGURE 14 SVE SYSTEM LAYOUT.DWG Last edited: APR. 19, 13 @ 08:51 a.m. by: david_deguire

# Roxana Soil Vapor Quarterly – 1st Quarter 2013 Data Review

**Laboratory SDG: 1301353AR1, BR1**

**Data Reviewer: Elizabeth Kunkel**

**Peer Reviewer: Steve Gragert**

**Date Reviewed: 2/18/2013**

**Guidance: USEPA National Functional Guidelines for Superfund Organic Methods Data Review 2008**

| Sample Identification | Sample Identification |
|---|---|
| VMP-47-5-012113 | VMP-47-10-012113 |
| VMP-1-5-012113 | VMP-1-38.5-012113 |

## 1.0 Data Package Completeness

*Were all items delivered as specified in the QAPP and COC as appropriate?*

Yes, however, professional judgment was used to qualify sample VMP-1-38.5-012113 due to a helium result in the sample (6.6%) that was greater than 10% of helium in the shroud (57.8%).

## 2.0 Laboratory Case Narrative \ Cooler Receipt Form

*Were problems noted in the laboratory case narrative or cooler receipt form?*

Yes, the laboratory case narrative indicated sample VMP-1-38.5-012113 was diluted and re-analyzed to bring the highest level target analytes within the calibration range of the instrument. Results for the highest level target analytes were reported from the re-analysis diluted runs and the remaining compounds were reported from the original analyses. Samples VMP-1-5-012113 and VMP-1-38.5-012113 were diluted due to high levels of target analytes. Although not indicated in the laboratory case narrative, analytes were detected in the method blank. TO-15 LCS/LCSD recoveries were outside evaluation criteria. These issues are addressed further in the appropriate sections below. The laboratory report was re-issued to report additional natural gas analytes via ASTM D-1945 and also the top five tentatively identified compounds (TICs) via TO-15.

No issues or discrepancies were noted in the cooler receipt form.

## 3.0 Holding Times

*Were samples extracted/analyzed within applicable limits?*

Yes

## 4.0 Blank Contamination

*Were any analytes detected in the Blanks?*

Yes

| Blank ID | Parameter | Analyte | Concentration/ Amount |
|---|---|---|---|
| 1301353A-05A | TO-15 | Bromomethane | 0.46 ppbv / 1.8 µg/m$^3$ |
| 1301353A-05A | TO-15 | 1,4-Dichlorobenzene | 0.059 ppbv / 0.36 µg/m$^3$ |

| Blank ID | Parameter | Analyte | Concentration/ Amount |
|---|---|---|---|
| 1301353B-05A | Natural Gases | Nitrogen | 0.087% |

Qualifications due to blank contamination are included in the following table. Analytical data that were reported non-detect or at concentrations greater than five times (5X) the associated blank concentration did not require qualification.

| Sample ID | Parameter | Analyte | New Reporting Limit (RL) | Qualification |
|---|---|---|---|---|
| VMP-47-5-012113 | TO-15 | Bromomethane | - | **U** |
| VMP-47-10-012113 | TO-15 | Bromomethane | - | **U** |
| VMP-47-10-012113 | TO-15 | 1,4-Dichlorobenzene | - | **U** |

## 5.0 Laboratory Control Sample

*Were LCS recoveries within evaluation criteria?*

No

| LCS/LCSD ID | Parameter | Analyte | LCS/LCSD Recovery | LCS/ LCSD RPD | LCS/LCSD /RPD Criteria |
|---|---|---|---|---|---|
| 1301353A-07A/AA | TO-15 | Carbon disulfide | **137**/**131** | 5 | 70-130/25 |
| 1301353A-07A/AA | TO-15 | 3-Chloropropene | **139**/**131** | 6 | 70-130/25 |
| 1301353A-07A/AA | TO-15 | trans-1,2-Dichloroethene | **135**/130 | 4 | 70-130/25 |

Analytical data that required qualification based on LCS data are included in the table below. Analytical data reported as non-detect and associated with LCS recoveries above evaluation criteria, indicating a possible high bias, did not require qualification. No qualification of data was required.

## 6.0 Surrogate Recoveries

*Were surrogate recoveries within evaluation criteria?*

Yes

## 7.0 Matrix Spike and Matrix Spike Duplicate Recoveries

*Were MS/MSD samples analyzed as part of this SDG?*

MS/MSD samples are not applicable for vapor samples, due to the inability to spike the samples.

## 8.0 Laboratory Duplicate Results

*Were laboratory duplicate samples collected as part of this SDG?*

No

## 9.0 Field Duplicate Results

*Were field duplicate samples collected as part of this SDG?*

No

## 10.0 Sample Dilutions

*For samples that were diluted and nondetect, were undiluted results also reported?*

Not applicable; analytes were detected in samples that were diluted.

## 11.0 Additional Qualifications

*Were additional qualifications applied?*

Yes, professional judgment was used to qualify sample VMP-1-38.5-012113 due to a helium result in the sample (6.6%) that was greater than 10% of helium in the shroud (57.8%).

| Sample ID | Parameter | Analyte | Qualification |
|---|---|---|---|
| VMP-1-38.5-012113 | TO-15 | All detects | **J** |
| VMP-1-38.5-012113 | TO-15 | All non-detects | **UJ** |
| VMP-1-38.5-012113 | Natural gases | All detects | **J** |
| VMP-1-38.5-012113 | Natural gases | All non-detects | **UJ** |

eurofins | Air Toxics

2/15/2013
Ms. Elizabeth Kunkel
URS Corporation
1001 Highlands Plaza Dr. West
Suite 300
St. Louis MO 63110

Project Name: Roxana Soil Vapor
Project #:
Workorder #: 1301353AR1

Dear Ms. Elizabeth Kunkel

The following report includes the data for the above referenced project for sample(s) received on 1/22/2013 at Air Toxics Ltd.

The data and associated QC analyzed by Modified TO-15 are compliant with the project requirements or laboratory criteria with the exception of the deviations noted in the attached case narrative.

Thank you for choosing Air Toxics Ltd. for your air analysis needs. Air Toxics Ltd. is committed to providing accurate data of the highest quality. Please feel free to contact the Project Manager: Kelly Buettner at 916-985-1000 if you have any questions regarding the data in this report.

Regards,

Kelly Buettner

Project Manager

Reviewed
on
2/18/2013

eurofins | Air Toxics

# WORK ORDER #: 1301353AR1

Work Order Summary

| | | | |
|---|---|---|---|
| **CLIENT:** | Ms. Elizabeth Kunkel<br>URS Corporation<br>1001 Highlands Plaza Dr. West<br>Suite 300<br>St. Louis, MO 63110 | **BILL TO:** | Accounts Payable Austin<br>URS Corporation<br>P.O. BOX 203970<br>Austin, TX 78720-1088 |
| **PHONE:** | 314-743-4179 | **P.O. #** | 21562735.00013 |
| **FAX:** | | **PROJECT #** | Roxana Soil Vapor |
| **DATE RECEIVED:** | 01/22/2013 | **CONTACT:** | Kelly Buettner |
| **DATE COMPLETED:** | 01/23/2013 | | |
| **DATE REISSUED:** | 02/15/2013 | | |

| FRACTION # | NAME | TEST | RECEIPT VAC./PRES. | FINAL PRESSURE |
|---|---|---|---|---|
| 01A | VMP-47-5-012113 | Modified TO-15 | 9.0 "Hg | 15 psi |
| 02A | VMP-47-10-012113 | Modified TO-15 | 8.0 "Hg | 15 psi |
| 03A | VMP-1-5-012113 | Modified TO-15 | 6.5 "Hg | 15 psi |
| 04A | VMP-1-38.5-012113 | Modified TO-15 | 7.0 "Hg | 15 psi |
| 04B | VMP-1-38.5-012113 | Modified TO-15 | 7.0 "Hg | 15 psi |
| 05A | Lab Blank | Modified TO-15 | NA | NA |
| 06A | CCV | Modified TO-15 | NA | NA |
| 07A | LCS | Modified TO-15 | NA | NA |
| 07AA | LCSD | Modified TO-15 | NA | NA |

CERTIFIED BY: Heidi Hayes DATE: 02/15/13

Technical Director

Certification numbers: AZ Licensure AZ0775, CA NELAP - 12282CA, NY NELAP - 11291, TX NELAP - T104704434-12-4, UT NELAP CA009332012-3, WA NELAP - C935
Name of Accrediting Agency: NELAP/ORELAP (Oregon Environmental Laboratory Accreditation Program)
Accreditation number: CA300005, Effective date: 10/18/2012, Expiration date: 10/17/2013.
Eurofins Air Toxics Ltd. certifies that the test results contained in this report meet all requirements of the NELAC standards

This report shall not be reproduced, except in full, without the written approval of Eurofins Air Toxics, Inc.

180 BLUE RAVINE ROAD, SUITE B FOLSOM, CA - 9563
(916) 985-1000 . (800) 985-5955 . FAX (916) 985-1020

**LABORATORY NARRATIVE**
**EPA Method TO-15**
**URS Corporation**
**Workorder# 1301353AR1**

Four 1 Liter Summa Canister samples were received on January 22, 2013. The laboratory performed analysis via EPA Method TO-15 using GC/MS in the full scan mode.

This workorder was independently validated prior to submittal using 'USEPA National Functional Guidelines' as generally applied to the analysis of volatile organic compounds in air. A rules-based, logic driven, independent validation engine was employed to assess completeness, evaluate pass/fail of relevant project quality control requirements and verification of all quantified amounts.

**Receiving Notes**

There were no receiving discrepancies.

**Analytical Notes**

All Quality Control Limit exceedances and affected sample results are noted by flags. Each flag is defined at the bottom of this Case Narrative and on each Sample Result Summary page.

Dilution was performed on samples VMP-1-5-012113 and VMP-1-38.5-012113 due to the presence of high level target species.

Due to high-level target compounds, sample VMP-1-38.5-012113 was analyzed twice. In the "A" fraction, the sample was diluted to bring the highest-level compounds within the calibration range. The "B" fraction is also reported by client request and may be reported with "E" flags indicating the compound exceeds the calibration range. Both runs and associated QC are reported.

As per client project requirements, the laboratory has reported estimated values for target compound hits that are below the Reporting Limit but greater than the Method Detection Limit.

THE WORKORDER WAS REISSUED ON FEBRUARY 15, 2013 TO REPORT THE TOP 5 TENTATIVELY IDENTIFIED COMPOUNDS PER CLIENT'S REQUEST.

**Definition of Data Qualifying Flags**

Eight qualifiers may have been used on the data analysis sheets and indicates as follows:

B - Compound present in laboratory blank greater than reporting limit (background subtraction not performed).
J - Estimated value.
E - Exceeds instrument calibration range.
S - Saturated peak.
Q - Exceeds quality control limits.
U - Compound analyzed for but not detected above the reporting limit.
UJ- Non-detected compound associated with low bias in the CCV
N - The identification is based on presumptive evidence.

File extensions may have been used on the data analysis sheets and indicates as follows:

a-File was requantified
b-File was quantified by a second column and detector
r1-File was requantified for the purpose of reissue

eurofins | Air Toxics

# Summary of Detected Compounds
# EPA METHOD TO-15 GC/MS FULL SCAN

**Client Sample ID: VMP-47-5-012113**

**Lab ID#: 1301353AR1-01A**

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 1.4 | 0.61 J | 7.1 | 3.0 J |
| Bromomethane | 14 | ~~1.1 J~~ U | 56 | ~~4.2 J~~ U |
| Ethanol | 5.8 | 5.5 J | 11 | 10 J |
| Acetone | 14 | 11 J | 34 | 26 J |
| 2-Propanol | 5.8 | 23 | 14 | 57 |
| Hexane | 1.4 | 0.55 J | 5.1 | 1.9 J |
| 2-Butanone (Methyl Ethyl Ketone) | 5.8 | 2.0 J | 17 | 5.9 J |
| Cyclohexane | 1.4 | 0.72 J | 5.0 | 2.5 J |
| 2,2,4-Trimethylpentane | 1.4 | 110 | 6.8 | 520 |
| Benzene | 1.4 | 0.55 J | 4.6 | 1.8 J |
| Toluene | 1.4 | 0.19 J | 5.4 | 0.70 J |
| 1,3-Dichlorobenzene | 1.4 | 0.25 J | 8.7 | 1.5 J |
| 1,4-Dichlorobenzene | 1.4 | 0.36 J | 8.7 | 2.2 J |
| alpha-Chlorotoluene | 1.4 | 0.20 J | 7.5 | 1.0 J |
| Butane | 5.8 | 24 | 14 | 58 |
| Isopentane | 5.8 | 30 | 17 | 89 |

**TENTATIVELY IDENTIFIED COMPOUNDS**

| Compound | CAS Number | Match Quality | Amount (ppbv) |
|---|---|---|---|
| Butane, 2,2-dimethyl- | | | 13 NJ |
| Pentane, 2-methyl- | | | 13 NJ |
| Pentane, 2,4-dimethyl- | | | 13 NJ |
| Pentane, 2,3,4-trimethyl- | | | 39 NJ |
| Hexane, 2,2,4-trimethyl- | | | 19 NJ |

**Client Sample ID: VMP-47-10-012113**

**Lab ID#: 1301353AR1-02A**

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 1.4 | 0.71 J | 6.8 | 3.5 J |
| Bromomethane | 14 | ~~1.1 J~~ U | 54 | ~~4.2 J~~ U |
| Ethanol | 5.5 | 5.6 | 10 | 10 |
| Acetone | 14 | 3.5 J | 33 | 8.4 J |

eurofins | Air Toxics

# Summary of Detected Compounds
# EPA METHOD TO-15 GC/MS FULL SCAN

**Client Sample ID: VMP-47-10-012113**

**Lab ID#: 1301353AR1-02A**

| | | | | |
|---|---|---|---|---|
| 2-Propanol | 5.5 | 14 | 14 | 35 |
| Methylene Chloride | 14 | 1.1 J | 48 | 3.7 J |
| 2,2,4-Trimethylpentane | 1.4 | 0.61 J | 6.4 | 2.8 J |
| Benzene | 1.4 | 1.6 | 4.4 | 5.1 |
| 1,4-Dichlorobenzene | 1.4 | ~~0.15 J~~ UL | 8.3 | ~~0.90 J~~ UL |
| Butane | 5.5 | 2.9 J | 13 | 7.0 J |
| Isopentane | 5.5 | 1.8 J | 16 | 5.2 J |

**TENTATIVELY IDENTIFIED COMPOUNDS**

| Compound | CAS Number | Match Quality | Amount (ppbv) |
|---|---|---|---|
| Unknown | | | 7.2 J |
| Heptadecane | | | 7.7 NJ |

**Client Sample ID: VMP-1-5-012113**

**Lab ID#: 1301353AR1-03A**

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Bromomethane | 260 | 19 J | 1000 | 74 J |
| Ethanol | 100 | 75 J | 190 | 140 J |
| Acetone | 260 | 140 J | 610 | 320 J |
| 2-Propanol | 100 | 63 J | 250 | 150 J |
| Hexane | 26 | 770 | 91 | 2700 |
| Cyclohexane | 26 | 250 | 89 | 880 |
| 2,2,4-Trimethylpentane | 26 | 970 | 120 | 4500 |
| Benzene | 26 | 4.7 J | 82 | 15 J |
| Heptane | 26 | 33 | 100 | 140 |
| 4-Methyl-2-pentanone | 26 | 5.8 J | 100 | 24 J |
| Toluene | 26 | 6.8 J | 97 | 25 J |
| Styrene | 26 | 4.8 J | 110 | 21 J |
| 1,4-Dichlorobenzene | 26 | 3.3 J | 160 | 20 J |
| Butane | 100 | 7200 | 240 | 17000 |
| Isopentane | 100 | 7300 | 300 | 22000 |

**TENTATIVELY IDENTIFIED COMPOUNDS**

| Compound | CAS Number | Match Quality | Amount (ppbv) |
|---|---|---|---|

eurofins | Air Toxics

# Summary of Detected Compounds
# EPA METHOD TO-15 GC/MS FULL SCAN

**Client Sample ID: VMP-1-5-012113**

**Lab ID#: 1301353AR1-03A**

TENTATIVELY IDENTIFIED COMPOUNDS

| Compound | CAS Number | Match Quality | Amount (ppbv) |
|---|---|---|---|
| Pentane | | | 1900 NJ |
| Pentane, 3-methyl- | | | 1800 NJ |
| Pentane, 2,4-dimethyl- | | | 1400 NJ |
| Cyclobutane, ethyl- | | | 660 NJ |
| Pentane, 2,3-dimethyl- | | | 2400 NJ |

**Client Sample ID: VMP-1-38.5-012113** * Use these results only. All other data was reported from the 17.6X dilution analysis.

**Lab ID#: 1301353AR1-04A**

DF = 26.4

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Hexane | 13 | 260 | 46 | 940 |
| Cyclohexane | 13 | 170 | 45 | 570 |
| 2,2,4-Trimethylpentane | 13 | 300 | 62 | 1400 |
| Benzene | 13 | 3.8 J | 42 | 12 J |
| Heptane | 13 | 41 | 54 | 170 |
| * Butane | 53 | 3800 J | 120 | 9200 J |
| Isopentane | 53 | 2600 | 160 | 7500 |

TENTATIVELY IDENTIFIED COMPOUNDS

| Compound | CAS Number | Match Quality | Amount (ppbv) |
|---|---|---|---|
| Pentane | | | 670 NJ |
| Pentane, 2-methyl- | | | 1100 NJ |
| Pentane, 3-methyl- | | | 580 NJ |
| Pentane, 2,4-dimethyl- | | | 400 NJ |
| Pentane, 2,3-dimethyl- | | | 1000 NJ |

**Client Sample ID: VMP-1-38.5-012113** ** Do not use this data. Use all other data.

**Lab ID#: 1301353AR1-04B**

DF = 17.6

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Bromomethane | 88 | 6.1 J J | 340 | 24 J J |
| Acetone | 88 | 8.5 J J | 210 | 20 J J |

eurofins | Air Toxics

# Summary of Detected Compounds
# EPA METHOD TO-15 GC/MS FULL SCAN

**Client Sample ID: VMP-1-38.5-012113**

**Lab ID#: 1301353AR1-04B**

| | | | | |
|---|---|---|---|---|
| Hexane | 8.8 | 270 J | 31 | 940 J |
| Cyclohexane | 8.8 | 180 J | 30 | 620 J |
| 2,2,4-Trimethylpentane | 8.8 | 300 J | 41 | 1400 J |
| Benzene | 8.8 | 3.2 J J | 28 | 10 J J |
| Heptane | 8.8 | 42 J | 36 | 170 J |
| ~~Butane~~ | ~~35~~ | ~~3800 E~~ | ~~84~~ | ~~9100 E~~ |
| Isopentane | 35 | 2500 J | 100 | 7400 J |

**TENTATIVELY IDENTIFIED COMPOUNDS**

| Compound | CAS Number | Match Quality | Amount (ppbv) |
|---|---|---|---|
| Pentane | | | 680 NJ |
| Pentane, 2-methyl- | | | 1200 NJ |
| Pentane, 3-methyl- | | | 600 NJ |
| Pentane, 2,4-dimethyl- | | | 420 NJ |
| Pentane, 2,3-dimethyl- | | | 1000 NJ |

eurofins | Air Toxics

**Client Sample ID: VMP-47-5-012113**

**Lab ID#: 1301353AR1-01A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **3012212r1** | **Date of Collection:** | **1/21/13 12:40:00 PM** |
| **Dil. Factor:** | **2.89** | **Date of Analysis:** | **1/22/13 01:52 PM** |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 1.4 | 0.61 J | 7.1 | 3.0 J |
| Freon 114 | 1.4 | Not Detected | 10 | Not Detected |
| Chloromethane | 14 | Not Detected | 30 | Not Detected |
| Vinyl Chloride | 1.4 | Not Detected | 3.7 | Not Detected |
| 1,3-Butadiene | 1.4 | Not Detected | 3.2 | Not Detected |
| Bromomethane | 14 | ~~1.1 J~~ U | 56 | ~~4.2 J~~ U |
| Chloroethane | 5.8 | Not Detected | 15 | Not Detected |
| Freon 11 | 1.4 | Not Detected | 8.1 | Not Detected |
| Ethanol | 5.8 | 5.5 J | 11 | 10 J |
| Freon 113 | 1.4 | Not Detected | 11 | Not Detected |
| 1,1-Dichloroethene | 1.4 | Not Detected | 5.7 | Not Detected |
| Acetone | 14 | 11 J | 34 | 26 J |
| 2-Propanol | 5.8 | 23 | 14 | 57 |
| Carbon Disulfide | 5.8 | Not Detected | 18 | Not Detected |
| 3-Chloropropene | 5.8 | Not Detected | 18 | Not Detected |
| Methylene Chloride | 14 | Not Detected | 50 | Not Detected |
| Methyl tert-butyl ether | 1.4 | Not Detected | 5.2 | Not Detected |
| trans-1,2-Dichloroethene | 1.4 | Not Detected | 5.7 | Not Detected |
| Hexane | 1.4 | 0.55 J | 5.1 | 1.9 J |
| 1,1-Dichloroethane | 1.4 | Not Detected | 5.8 | Not Detected |
| 2-Butanone (Methyl Ethyl Ketone) | 5.8 | 2.0 J | 17 | 5.9 J |
| cis-1,2-Dichloroethene | 1.4 | Not Detected | 5.7 | Not Detected |
| Tetrahydrofuran | 1.4 | Not Detected | 4.3 | Not Detected |
| Chloroform | 1.4 | Not Detected | 7.0 | Not Detected |
| 1,1,1-Trichloroethane | 1.4 | Not Detected | 7.9 | Not Detected |
| Cyclohexane | 1.4 | 0.72 J | 5.0 | 2.5 J |
| Carbon Tetrachloride | 1.4 | Not Detected | 9.1 | Not Detected |
| 2,2,4-Trimethylpentane | 1.4 | 110 | 6.8 | 520 |
| Benzene | 1.4 | 0.55 J | 4.6 | 1.8 J |
| 1,2-Dichloroethane | 1.4 | Not Detected | 5.8 | Not Detected |
| Heptane | 1.4 | Not Detected | 5.9 | Not Detected |
| Trichloroethene | 1.4 | Not Detected | 7.8 | Not Detected |
| 1,2-Dichloropropane | 1.4 | Not Detected | 6.7 | Not Detected |
| 1,4-Dioxane | 5.8 | Not Detected | 21 | Not Detected |
| Bromodichloromethane | 1.4 | Not Detected | 9.7 | Not Detected |
| cis-1,3-Dichloropropene | 1.4 | Not Detected | 6.6 | Not Detected |
| 4-Methyl-2-pentanone | 1.4 | Not Detected | 5.9 | Not Detected |
| Toluene | 1.4 | 0.19 J | 5.4 | 0.70 J |
| trans-1,3-Dichloropropene | 1.4 | Not Detected | 6.6 | Not Detected |
| 1,1,2-Trichloroethane | 1.4 | Not Detected | 7.9 | Not Detected |
| Tetrachloroethene | 1.4 | Not Detected | 9.8 | Not Detected |
| 2-Hexanone | 5.8 | Not Detected | 24 | Not Detected |

eurofins | Air Toxics

**Client Sample ID: VMP-47-5-012113**

**Lab ID#: 1301353AR1-01A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **3012212r1** | **Date of Collection: 1/21/13 12:40:00 PM** | |
| **Dil. Factor:** | **2.89** | **Date of Analysis: 1/22/13 01:52 PM** | |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Dibromochloromethane | 1.4 | Not Detected | 12 | Not Detected |
| 1,2-Dibromoethane (EDB) | 1.4 | Not Detected | 11 | Not Detected |
| Chlorobenzene | 1.4 | Not Detected | 6.6 | Not Detected |
| Ethyl Benzene | 1.4 | Not Detected | 6.3 | Not Detected |
| m,p-Xylene | 1.4 | Not Detected | 6.3 | Not Detected |
| o-Xylene | 1.4 | Not Detected | 6.3 | Not Detected |
| Styrene | 1.4 | Not Detected | 6.2 | Not Detected |
| Bromoform | 1.4 | Not Detected | 15 | Not Detected |
| Cumene | 1.4 | Not Detected | 7.1 | Not Detected |
| 1,1,2,2-Tetrachloroethane | 1.4 | Not Detected | 9.9 | Not Detected |
| Propylbenzene | 1.4 | Not Detected | 7.1 | Not Detected |
| 4-Ethyltoluene | 1.4 | Not Detected | 7.1 | Not Detected |
| 1,3,5-Trimethylbenzene | 1.4 | Not Detected | 7.1 | Not Detected |
| 1,2,4-Trimethylbenzene | 1.4 | Not Detected | 7.1 | Not Detected |
| 1,3-Dichlorobenzene | 1.4 | 0.25 J | 8.7 | 1.5 J |
| 1,4-Dichlorobenzene | 1.4 | 0.36 J | 8.7 | 2.2 J |
| alpha-Chlorotoluene | 1.4 | 0.20 J | 7.5 | 1.0 J |
| 1,2-Dichlorobenzene | 1.4 | Not Detected | 8.7 | Not Detected |
| 1,2,4-Trichlorobenzene | 5.8 | Not Detected | 43 | Not Detected |
| Hexachlorobutadiene | 5.8 | Not Detected | 62 | Not Detected |
| Butane | 5.8 | 24 | 14 | 58 |
| Isopentane | 5.8 | 30 | 17 | 89 |

J = Estimated value.

**TENTATIVELY IDENTIFIED COMPOUNDS**

| Compound | CAS Number | Match Quality | Amount ((ppbv)) |
|---|---|---|---|
| Butane, 2,2-dimethyl- | | | 44 NJ |
| Pentane, 2-methyl- | | | 47 NJ |
| Pentane, 2,4-dimethyl- | | | 52 NJ |
| Pentane, 2,3,4-trimethyl- | | | 180 NJ |
| Hexane, 2,2,4-trimethyl- | | | 0 NJ |

NJ =The identification is based on presumptive evidence; estimated value.

**Container Type: 1 Liter Summa Canister**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| Toluene-d8 | 89 | 70-130 |
| 1,2-Dichloroethane-d4 | 88 | 70-130 |
| 4-Bromofluorobenzene | 97 | 70-130 |

**Client Sample ID: VMP-47-10-012113**

**Lab ID#: 1301353AR1-02A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **3012213r1** | **Date of Collection: 1/21/13 1:40:00 PM** | |
| **Dil. Factor:** | **2.76** | **Date of Analysis: 1/22/13 02:42 PM** | |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 1.4 | 0.71 J | 6.8 | 3.5 J |
| Freon 114 | 1.4 | Not Detected | 9.6 | Not Detected |
| Chloromethane | 14 | Not Detected | 28 | Not Detected |
| Vinyl Chloride | 1.4 | Not Detected | 3.5 | Not Detected |
| 1,3-Butadiene | 1.4 | Not Detected | 3.0 | Not Detected |
| Bromomethane | 14 | ~~4.1 J~~ U | 54 | ~~4.2 J~~ U |
| Chloroethane | 5.5 | Not Detected | 14 | Not Detected |
| Freon 11 | 1.4 | Not Detected | 7.8 | Not Detected |
| Ethanol | 5.5 | 5.6 | 10 | 10 |
| Freon 113 | 1.4 | Not Detected | 10 | Not Detected |
| 1,1-Dichloroethene | 1.4 | Not Detected | 5.5 | Not Detected |
| Acetone | 14 | 3.5 J | 33 | 8.4 J |
| 2-Propanol | 5.5 | 14 | 14 | 35 |
| Carbon Disulfide | 5.5 | Not Detected | 17 | Not Detected |
| 3-Chloropropene | 5.5 | Not Detected | 17 | Not Detected |
| Methylene Chloride | 14 | 1.1 J | 48 | 3.7 J |
| Methyl tert-butyl ether | 1.4 | Not Detected | 5.0 | Not Detected |
| trans-1,2-Dichloroethene | 1.4 | Not Detected | 5.5 | Not Detected |
| Hexane | 1.4 | Not Detected | 4.9 | Not Detected |
| 1,1-Dichloroethane | 1.4 | Not Detected | 5.6 | Not Detected |
| 2-Butanone (Methyl Ethyl Ketone) | 5.5 | Not Detected | 16 | Not Detected |
| cis-1,2-Dichloroethene | 1.4 | Not Detected | 5.5 | Not Detected |
| Tetrahydrofuran | 1.4 | Not Detected | 4.1 | Not Detected |
| Chloroform | 1.4 | Not Detected | 6.7 | Not Detected |
| 1,1,1-Trichloroethane | 1.4 | Not Detected | 7.5 | Not Detected |
| Cyclohexane | 1.4 | Not Detected | 4.8 | Not Detected |
| Carbon Tetrachloride | 1.4 | Not Detected | 8.7 | Not Detected |
| 2,2,4-Trimethylpentane | 1.4 | 0.61 J | 6.4 | 2.8 J |
| Benzene | 1.4 | 1.6 | 4.4 | 5.1 |
| 1,2-Dichloroethane | 1.4 | Not Detected | 5.6 | Not Detected |
| Heptane | 1.4 | Not Detected | 5.6 | Not Detected |
| Trichloroethene | 1.4 | Not Detected | 7.4 | Not Detected |
| 1,2-Dichloropropane | 1.4 | Not Detected | 6.4 | Not Detected |
| 1,4-Dioxane | 5.5 | Not Detected | 20 | Not Detected |
| Bromodichloromethane | 1.4 | Not Detected | 9.2 | Not Detected |
| cis-1,3-Dichloropropene | 1.4 | Not Detected | 6.3 | Not Detected |
| 4-Methyl-2-pentanone | 1.4 | Not Detected | 5.6 | Not Detected |
| Toluene | 1.4 | Not Detected | 5.2 | Not Detected |
| trans-1,3-Dichloropropene | 1.4 | Not Detected | 6.3 | Not Detected |
| 1,1,2-Trichloroethane | 1.4 | Not Detected | 7.5 | Not Detected |
| Tetrachloroethene | 1.4 | Not Detected | 9.4 | Not Detected |
| 2-Hexanone | 5.5 | Not Detected | 23 | Not Detected |

eurofins | Air Toxics

**Client Sample ID: VMP-47-10-012113**

**Lab ID#: 1301353AR1-02A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **3012213r1** | **Date of Collection: 1/21/13 1:40:00 PM** | |
| **Dil. Factor:** | **2.76** | **Date of Analysis: 1/22/13 02:42 PM** | |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Dibromochloromethane | 1.4 | Not Detected | 12 | Not Detected |
| 1,2-Dibromoethane (EDB) | 1.4 | Not Detected | 11 | Not Detected |
| Chlorobenzene | 1.4 | Not Detected | 6.4 | Not Detected |
| Ethyl Benzene | 1.4 | Not Detected | 6.0 | Not Detected |
| m,p-Xylene | 1.4 | Not Detected | 6.0 | Not Detected |
| o-Xylene | 1.4 | Not Detected | 6.0 | Not Detected |
| Styrene | 1.4 | Not Detected | 5.9 | Not Detected |
| Bromoform | 1.4 | Not Detected | 14 | Not Detected |
| Cumene | 1.4 | Not Detected | 6.8 | Not Detected |
| 1,1,2,2-Tetrachloroethane | 1.4 | Not Detected | 9.5 | Not Detected |
| Propylbenzene | 1.4 | Not Detected | 6.8 | Not Detected |
| 4-Ethyltoluene | 1.4 | Not Detected | 6.8 | Not Detected |
| 1,3,5-Trimethylbenzene | 1.4 | Not Detected | 6.8 | Not Detected |
| 1,2,4-Trimethylbenzene | 1.4 | Not Detected | 6.8 | Not Detected |
| 1,3-Dichlorobenzene | 1.4 | Not Detected | 8.3 | Not Detected |
| 1,4-Dichlorobenzene | 1.4 | ~~0.15 J~~ U | 8.3 | ~~0.90 J~~ U |
| alpha-Chlorotoluene | 1.4 | Not Detected | 7.1 | Not Detected |
| 1,2-Dichlorobenzene | 1.4 | Not Detected | 8.3 | Not Detected |
| 1,2,4-Trichlorobenzene | 5.5 | Not Detected | 41 | Not Detected |
| Hexachlorobutadiene | 5.5 | Not Detected | 59 | Not Detected |
| Butane | 5.5 | 2.9 J | 13 | 7.0 J |
| Isopentane | 5.5 | 1.8 J | 16 | 5.2 J |

J = Estimated value.

**TENTATIVELY IDENTIFIED COMPOUNDS**

| Compound | CAS Number | Match Quality | Amount ((ppbv)) |
|---|---|---|---|
| Unknown | | | 0 J |
| Heptadecane | | | 0 NJ |

NJ =The identification is based on presumptive evidence; estimated value.

**Container Type: 1 Liter Summa Canister**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| Toluene-d8 | 88 | 70-130 |
| 1,2-Dichloroethane-d4 | 86 | 70-130 |
| 4-Bromofluorobenzene | 94 | 70-130 |

eurofins | Air Toxics

**Client Sample ID: VMP-1-5-012113**

**Lab ID#: 1301353AR1-03A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **3012214r1** | **Date of Collection: 1/21/13 11:38:00 AM** | |
| **Dil. Factor:** | **51.6** | **Date of Analysis: 1/22/13 03:25 PM** | |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 26 | Not Detected | 130 | Not Detected |
| Freon 114 | 26 | Not Detected | 180 | Not Detected |
| Chloromethane | 260 | Not Detected | 530 | Not Detected |
| Vinyl Chloride | 26 | Not Detected | 66 | Not Detected |
| 1,3-Butadiene | 26 | Not Detected | 57 | Not Detected |
| Bromomethane | 260 | 19 J | 1000 | 74 J |
| Chloroethane | 100 | Not Detected | 270 | Not Detected |
| Freon 11 | 26 | Not Detected | 140 | Not Detected |
| Ethanol | 100 | 75 J | 190 | 140 J |
| Freon 113 | 26 | Not Detected | 200 | Not Detected |
| 1,1-Dichloroethene | 26 | Not Detected | 100 | Not Detected |
| Acetone | 260 | 140 J | 610 | 320 J |
| 2-Propanol | 100 | 63 J | 250 | 150 J |
| Carbon Disulfide | 100 | Not Detected | 320 | Not Detected |
| 3-Chloropropene | 100 | Not Detected | 320 | Not Detected |
| Methylene Chloride | 260 | Not Detected | 900 | Not Detected |
| Methyl tert-butyl ether | 26 | Not Detected | 93 | Not Detected |
| trans-1,2-Dichloroethene | 26 | Not Detected | 100 | Not Detected |
| Hexane | 26 | 770 | 91 | 2700 |
| 1,1-Dichloroethane | 26 | Not Detected | 100 | Not Detected |
| 2-Butanone (Methyl Ethyl Ketone) | 100 | Not Detected | 300 | Not Detected |
| cis-1,2-Dichloroethene | 26 | Not Detected | 100 | Not Detected |
| Tetrahydrofuran | 26 | Not Detected | 76 | Not Detected |
| Chloroform | 26 | Not Detected | 120 | Not Detected |
| 1,1,1-Trichloroethane | 26 | Not Detected | 140 | Not Detected |
| Cyclohexane | 26 | 250 | 89 | 880 |
| Carbon Tetrachloride | 26 | Not Detected | 160 | Not Detected |
| 2,2,4-Trimethylpentane | 26 | 970 | 120 | 4500 |
| Benzene | 26 | 4.7 J | 82 | 15 J |
| 1,2-Dichloroethane | 26 | Not Detected | 100 | Not Detected |
| Heptane | 26 | 33 | 100 | 140 |
| Trichloroethene | 26 | Not Detected | 140 | Not Detected |
| 1,2-Dichloropropane | 26 | Not Detected | 120 | Not Detected |
| 1,4-Dioxane | 100 | Not Detected | 370 | Not Detected |
| Bromodichloromethane | 26 | Not Detected | 170 | Not Detected |
| cis-1,3-Dichloropropene | 26 | Not Detected | 120 | Not Detected |
| 4-Methyl-2-pentanone | 26 | 5.8 J | 100 | 24 J |
| Toluene | 26 | 6.8 J | 97 | 25 J |
| trans-1,3-Dichloropropene | 26 | Not Detected | 120 | Not Detected |
| 1,1,2-Trichloroethane | 26 | Not Detected | 140 | Not Detected |
| Tetrachloroethene | 26 | Not Detected | 180 | Not Detected |
| 2-Hexanone | 100 | Not Detected | 420 | Not Detected |

**Client Sample ID: VMP-1-5-012113**

**Lab ID#: 1301353AR1-03A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **3012214r1** | **Date of Collection:** | **1/21/13 11:38:00 AM** |
| **Dil. Factor:** | **51.6** | **Date of Analysis:** | **1/22/13 03:25 PM** |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Dibromochloromethane | 26 | Not Detected | 220 | Not Detected |
| 1,2-Dibromoethane (EDB) | 26 | Not Detected | 200 | Not Detected |
| Chlorobenzene | 26 | Not Detected | 120 | Not Detected |
| Ethyl Benzene | 26 | Not Detected | 110 | Not Detected |
| m,p-Xylene | 26 | Not Detected | 110 | Not Detected |
| o-Xylene | 26 | Not Detected | 110 | Not Detected |
| Styrene | 26 | 4.8 J | 110 | 21 J |
| Bromoform | 26 | Not Detected | 270 | Not Detected |
| Cumene | 26 | Not Detected | 130 | Not Detected |
| 1,1,2,2-Tetrachloroethane | 26 | Not Detected | 180 | Not Detected |
| Propylbenzene | 26 | Not Detected | 130 | Not Detected |
| 4-Ethyltoluene | 26 | Not Detected | 130 | Not Detected |
| 1,3,5-Trimethylbenzene | 26 | Not Detected | 130 | Not Detected |
| 1,2,4-Trimethylbenzene | 26 | Not Detected | 130 | Not Detected |
| 1,3-Dichlorobenzene | 26 | Not Detected | 160 | Not Detected |
| 1,4-Dichlorobenzene | 26 | 3.3 J | 160 | 20 J |
| alpha-Chlorotoluene | 26 | Not Detected | 130 | Not Detected |
| 1,2-Dichlorobenzene | 26 | Not Detected | 160 | Not Detected |
| 1,2,4-Trichlorobenzene | 100 | Not Detected | 760 | Not Detected |
| Hexachlorobutadiene | 100 | Not Detected | 1100 | Not Detected |
| Butane | 100 | 7200 | 240 | 17000 |
| Isopentane | 100 | 7300 | 300 | 22000 |

J = Estimated value.

**TENTATIVELY IDENTIFIED COMPOUNDS**

| Compound | CAS Number | Match Quality | Amount ((ppbv)) |
|---|---|---|---|
| Pentane | | | 5600 NJ |
| Pentane, 3-methyl- | | | 6500 NJ |
| Pentane, 2,4-dimethyl- | | | 5600 NJ |
| Cyclobutane, ethyl- | | | 0 NJ |
| Pentane, 2,3-dimethyl- | | | 9800 NJ |

NJ =The identification is based on presumptive evidence; estimated value.

**Container Type: 1 Liter Summa Canister**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| Toluene-d8 | 89 | 70-130 |
| 1,2-Dichloroethane-d4 | 87 | 70-130 |
| 4-Bromofluorobenzene | 102 | 70-130 |

eurofins | Air Toxics

**Client Sample ID: VMP-1-38.5-012113** * Use these results only.
**Lab ID#: 1301353AR1-04A** All other data was reported
**EPA METHOD TO-15 GC/MS FULL SCAN** from the 17.6X dilution analysis.

| | | | |
|---|---|---|---|
| **File Name:** | **3012216r1** | **Date of Collection: 1/21/13 4:02:00 PM** | |
| **Dil. Factor:** | **26.4** | **Date of Analysis: 1/22/13 04:56 PM** | |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 13 | Not Detected | 65 | Not Detected |
| Freon 114 | 13 | Not Detected | 92 | Not Detected |
| Chloromethane | 130 | Not Detected | 270 | Not Detected |
| Vinyl Chloride | 13 | Not Detected | 34 | Not Detected |
| 1,3-Butadiene | 13 | Not Detected | 29 | Not Detected |
| Bromomethane | 130 | Not Detected | 510 | Not Detected |
| Chloroethane | 53 | Not Detected | 140 | Not Detected |
| Freon 11 | 13 | Not Detected | 74 | Not Detected |
| Ethanol | 53 | Not Detected | 99 | Not Detected |
| Freon 113 | 13 | Not Detected | 100 | Not Detected |
| 1,1-Dichloroethene | 13 | Not Detected | 52 | Not Detected |
| Acetone | 130 | Not Detected | 310 | Not Detected |
| 2-Propanol | 53 | Not Detected | 130 | Not Detected |
| Carbon Disulfide | 53 | Not Detected | 160 | Not Detected |
| 3-Chloropropene | 53 | Not Detected | 160 | Not Detected |
| Methylene Chloride | 130 | Not Detected | 460 | Not Detected |
| Methyl tert-butyl ether | 13 | Not Detected | 48 | Not Detected |
| trans-1,2-Dichloroethene | 13 | Not Detected | 52 | Not Detected |
| Hexane | 13 | 260 | 46 | 940 |
| 1,1-Dichloroethane | 13 | Not Detected | 53 | Not Detected |
| 2-Butanone (Methyl Ethyl Ketone) | 53 | Not Detected | 160 | Not Detected |
| cis-1,2-Dichloroethene | 13 | Not Detected | 52 | Not Detected |
| Tetrahydrofuran | 13 | Not Detected | 39 | Not Detected |
| Chloroform | 13 | Not Detected | 64 | Not Detected |
| 1,1,1-Trichloroethane | 13 | Not Detected | 72 | Not Detected |
| Cyclohexane | 13 | 170 | 45 | 570 |
| Carbon Tetrachloride | 13 | Not Detected | 83 | Not Detected |
| 2,2,4-Trimethylpentane | 13 | 300 | 62 | 1400 |
| Benzene | 13 | 3.8 J | 42 | 12 J |
| 1,2-Dichloroethane | 13 | Not Detected | 53 | Not Detected |
| Heptane | 13 | 41 | 54 | 170 |
| Trichloroethene | 13 | Not Detected | 71 | Not Detected |
| 1,2-Dichloropropane | 13 | Not Detected | 61 | Not Detected |
| 1,4-Dioxane | 53 | Not Detected | 190 | Not Detected |
| Bromodichloromethane | 13 | Not Detected | 88 | Not Detected |
| cis-1,3-Dichloropropene | 13 | Not Detected | 60 | Not Detected |
| 4-Methyl-2-pentanone | 13 | Not Detected | 54 | Not Detected |
| Toluene | 13 | Not Detected | 50 | Not Detected |
| trans-1,3-Dichloropropene | 13 | Not Detected | 60 | Not Detected |
| 1,1,2-Trichloroethane | 13 | Not Detected | 72 | Not Detected |
| Tetrachloroethene | 13 | Not Detected | 90 | Not Detected |
| 2-Hexanone | 53 | Not Detected | 220 | Not Detected |

**Client Sample ID: VMP-1-38.5-012113**

**Lab ID#: 1301353AR1-04A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **3012216r1** | **Date of Collection:** | **1/21/13 4:02:00 PM** |
| **Dil. Factor:** | **26.4** | **Date of Analysis:** | **1/22/13 04:56 PM** |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Dibromochloromethane | 13 | Not Detected | 110 | Not Detected |
| 1,2-Dibromoethane (EDB) | 13 | Not Detected | 100 | Not Detected |
| Chlorobenzene | 13 | Not Detected | 61 | Not Detected |
| Ethyl Benzene | 13 | Not Detected | 57 | Not Detected |
| m,p-Xylene | 13 | Not Detected | 57 | Not Detected |
| o-Xylene | 13 | Not Detected | 57 | Not Detected |
| Styrene | 13 | Not Detected | 56 | Not Detected |
| Bromoform | 13 | Not Detected | 140 | Not Detected |
| Cumene | 13 | Not Detected | 65 | Not Detected |
| 1,1,2,2-Tetrachloroethane | 13 | Not Detected | 91 | Not Detected |
| Propylbenzene | 13 | Not Detected | 65 | Not Detected |
| 4-Ethyltoluene | 13 | Not Detected | 65 | Not Detected |
| 1,3,5-Trimethylbenzene | 13 | Not Detected | 65 | Not Detected |
| 1,2,4-Trimethylbenzene | 13 | Not Detected | 65 | Not Detected |
| 1,3-Dichlorobenzene | 13 | Not Detected | 79 | Not Detected |
| 1,4-Dichlorobenzene | 13 | Not Detected | 79 | Not Detected |
| alpha-Chlorotoluene | 13 | Not Detected | 68 | Not Detected |
| 1,2-Dichlorobenzene | 13 | Not Detected | 79 | Not Detected |
| 1,2,4-Trichlorobenzene | 53 | Not Detected | 390 | Not Detected |
| Hexachlorobutadiene | 53 | Not Detected | 560 | Not Detected |
| Butane | 53 | 3800 J | 120 | 9200 J |
| Isopentane | 53 | 2600 | 160 | 7500 |

J = Estimated value.

**TENTATIVELY IDENTIFIED COMPOUNDS**

| Compound | CAS Number | Match Quality | Amount ((ppbv)) |
|---|---|---|---|
| Pentane | | | 2000 NJ |
| Pentane, 2-methyl- | | | 4000 NJ |
| Pentane, 3-methyl- | | | 2000 NJ |
| Pentane, 2,4-dimethyl- | | | 1600 NJ |
| Pentane, 2,3-dimethyl- | | | 4200 NJ |

NJ =The identification is based on presumptive evidence; estimated value.

**Container Type: 1 Liter Summa Canister**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| Toluene-d8 | 88 | 70-130 |
| 1,2-Dichloroethane-d4 | 87 | 70-130 |
| 4-Bromofluorobenzene | 91 | 70-130 |

eurofins | Air Toxics

**Client Sample ID: VMP-1-38.5-012113** ** Do not use this data. Use all other data.
**Lab ID#: 1301353AR1-04B**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **3012215r1** | **Date of Collection: 1/21/13 4:02:00 PM** | |
| **Dil. Factor:** | **17.6** | **Date of Analysis: 1/22/13 04:28 PM** | |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 8.8 | Not Detected UJ | 44 | Not Detected UJ |
| Freon 114 | 8.8 | Not Detected | 62 | Not Detected |
| Chloromethane | 88 | Not Detected | 180 | Not Detected |
| Vinyl Chloride | 8.8 | Not Detected | 22 | Not Detected |
| 1,3-Butadiene | 8.8 | Not Detected | 19 | Not Detected |
| Bromomethane | 88 | 6.1 J J | 340 | 24 J J |
| Chloroethane | 35 | Not Detected UJ | 93 | Not Detected UJ |
| Freon 11 | 8.8 | Not Detected | 49 | Not Detected |
| Ethanol | 35 | Not Detected | 66 | Not Detected |
| Freon 113 | 8.8 | Not Detected | 67 | Not Detected |
| 1,1-Dichloroethene | 8.8 | Not Detected | 35 | Not Detected |
| Acetone | 88 | 8.5 J J | 210 | 20 J J |
| 2-Propanol | 35 | Not Detected UJ | 86 | Not Detected UJ |
| Carbon Disulfide | 35 | Not Detected | 110 | Not Detected |
| 3-Chloropropene | 35 | Not Detected | 110 | Not Detected |
| Methylene Chloride | 88 | Not Detected | 300 | Not Detected |
| Methyl tert-butyl ether | 8.8 | Not Detected | 32 | Not Detected |
| trans-1,2-Dichloroethene | 8.8 | Not Detected | 35 | Not Detected |
| Hexane | 8.8 | 270 J | 31 | 940 J |
| 1,1-Dichloroethane | 8.8 | Not Detected UJ | 36 | Not Detected UJ |
| 2-Butanone (Methyl Ethyl Ketone) | 35 | Not Detected | 100 | Not Detected |
| cis-1,2-Dichloroethene | 8.8 | Not Detected | 35 | Not Detected |
| Tetrahydrofuran | 8.8 | Not Detected | 26 | Not Detected |
| Chloroform | 8.8 | Not Detected | 43 | Not Detected |
| 1,1,1-Trichloroethane | 8.8 | Not Detected | 48 | Not Detected |
| Cyclohexane | 8.8 | 180 J | 30 | 620 J |
| Carbon Tetrachloride | 8.8 | Not Detected UJ | 55 | Not Detected UJ |
| 2,2,4-Trimethylpentane | 8.8 | 300 J | 41 | 1400 J |
| Benzene | 8.8 | 3.2 J J | 28 | 10 J J |
| 1,2-Dichloroethane | 8.8 | Not Detected UJ | 36 | Not Detected UJ |
| Heptane | 8.8 | 42 J | 36 | 170 J |
| Trichloroethene | 8.8 | Not Detected UJ | 47 | Not Detected UJ |
| 1,2-Dichloropropane | 8.8 | Not Detected | 41 | Not Detected |
| 1,4-Dioxane | 35 | Not Detected | 130 | Not Detected |
| Bromodichloromethane | 8.8 | Not Detected | 59 | Not Detected |
| cis-1,3-Dichloropropene | 8.8 | Not Detected | 40 | Not Detected |
| 4-Methyl-2-pentanone | 8.8 | Not Detected | 36 | Not Detected |
| Toluene | 8.8 | Not Detected | 33 | Not Detected |
| trans-1,3-Dichloropropene | 8.8 | Not Detected | 40 | Not Detected |
| 1,1,2-Trichloroethane | 8.8 | Not Detected | 48 | Not Detected |
| Tetrachloroethene | 8.8 | Not Detected | 60 | Not Detected |
| 2-Hexanone | 35 | Not Detected | 140 | Not Detected |

eurofins | Air Toxics

**Client Sample ID: VMP-1-38.5-012113**

**Lab ID#: 1301353AR1-04B**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **3012215r1** | **Date of Collection: 1/21/13 4:02:00 PM** | |
| **Dil. Factor:** | **17.6** | **Date of Analysis: 1/22/13 04:28 PM** | |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Dibromochloromethane | 8.8 | Not Detected UJ | 75 | Not Detected UJ |
| 1,2-Dibromoethane (EDB) | 8.8 | Not Detected | 68 | Not Detected |
| Chlorobenzene | 8.8 | Not Detected | 40 | Not Detected |
| Ethyl Benzene | 8.8 | Not Detected | 38 | Not Detected |
| m,p-Xylene | 8.8 | Not Detected | 38 | Not Detected |
| o-Xylene | 8.8 | Not Detected | 38 | Not Detected |
| Styrene | 8.8 | Not Detected | 37 | Not Detected |
| Bromoform | 8.8 | Not Detected | 91 | Not Detected |
| Cumene | 8.8 | Not Detected | 43 | Not Detected |
| 1,1,2,2-Tetrachloroethane | 8.8 | Not Detected | 60 | Not Detected |
| Propylbenzene | 8.8 | Not Detected | 43 | Not Detected |
| 4-Ethyltoluene | 8.8 | Not Detected | 43 | Not Detected |
| 1,3,5-Trimethylbenzene | 8.8 | Not Detected | 43 | Not Detected |
| 1,2,4-Trimethylbenzene | 8.8 | Not Detected | 43 | Not Detected |
| 1,3-Dichlorobenzene | 8.8 | Not Detected | 53 | Not Detected |
| 1,4-Dichlorobenzene | 8.8 | Not Detected | 53 | Not Detected |
| alpha-Chlorotoluene | 8.8 | Not Detected | 46 | Not Detected |
| 1,2-Dichlorobenzene | 8.8 | Not Detected | 53 | Not Detected |
| 1,2,4-Trichlorobenzene | 35 | Not Detected | 260 | Not Detected |
| Hexachlorobutadiene | 35 | Not Detected | 380 | Not Detected |
| ~~Butane~~ | ~~35~~ | ~~3800 E~~ | ~~84~~ | ~~9100 E~~ |
| Isopentane | 35 | 2500 J | 100 | 7400 J |

J = Estimated value.
E = Exceeds instrument calibration range.

**TENTATIVELY IDENTIFIED COMPOUNDS**

| Compound | CAS Number | Match Quality | Amount ((ppbv)) |
|---|---|---|---|
| Pentane | | | 2000 NJ |
| Pentane, 2-methyl- | | | 4100 NJ |
| Pentane, 3-methyl- | | | 2100 NJ |
| Pentane, 2,4-dimethyl- | | | 1700 NJ |
| Pentane, 2,3-dimethyl- | | | 4300 NJ |

NJ =The identification is based on presumptive evidence; estimated value.

**Container Type: 1 Liter Summa Canister**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| Toluene-d8 | 88 | 70-130 |
| 1,2-Dichloroethane-d4 | 88 | 70-130 |
| 4-Bromofluorobenzene | 93 | 70-130 |

eurofins | Air Toxics

**Client Sample ID: Lab Blank**

**Lab ID#: 1301353AR1-05A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **3012210** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 1/22/13 12:39 PM** | |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 0.50 | Not Detected | 2.5 | Not Detected |
| Freon 114 | 0.50 | Not Detected | 3.5 | Not Detected |
| Chloromethane | 5.0 | Not Detected | 10 | Not Detected |
| Vinyl Chloride | 0.50 | Not Detected | 1.3 | Not Detected |
| 1,3-Butadiene | 0.50 | Not Detected | 1.1 | Not Detected |
| Bromomethane | 5.0 | 0.46 J | 19 | 1.8 J |
| Chloroethane | 2.0 | Not Detected | 5.3 | Not Detected |
| Freon 11 | 0.50 | Not Detected | 2.8 | Not Detected |
| Ethanol | 2.0 | Not Detected | 3.8 | Not Detected |
| Freon 113 | 0.50 | Not Detected | 3.8 | Not Detected |
| 1,1-Dichloroethene | 0.50 | Not Detected | 2.0 | Not Detected |
| Acetone | 5.0 | Not Detected | 12 | Not Detected |
| 2-Propanol | 2.0 | Not Detected | 4.9 | Not Detected |
| Carbon Disulfide | 2.0 | Not Detected | 6.2 | Not Detected |
| 3-Chloropropene | 2.0 | Not Detected | 6.3 | Not Detected |
| Methylene Chloride | 5.0 | Not Detected | 17 | Not Detected |
| Methyl tert-butyl ether | 0.50 | Not Detected | 1.8 | Not Detected |
| trans-1,2-Dichloroethene | 0.50 | Not Detected | 2.0 | Not Detected |
| Hexane | 0.50 | Not Detected | 1.8 | Not Detected |
| 1,1-Dichloroethane | 0.50 | Not Detected | 2.0 | Not Detected |
| 2-Butanone (Methyl Ethyl Ketone) | 2.0 | Not Detected | 5.9 | Not Detected |
| cis-1,2-Dichloroethene | 0.50 | Not Detected | 2.0 | Not Detected |
| Tetrahydrofuran | 0.50 | Not Detected | 1.5 | Not Detected |
| Chloroform | 0.50 | Not Detected | 2.4 | Not Detected |
| 1,1,1-Trichloroethane | 0.50 | Not Detected | 2.7 | Not Detected |
| Cyclohexane | 0.50 | Not Detected | 1.7 | Not Detected |
| Carbon Tetrachloride | 0.50 | Not Detected | 3.1 | Not Detected |
| 2,2,4-Trimethylpentane | 0.50 | Not Detected | 2.3 | Not Detected |
| Benzene | 0.50 | Not Detected | 1.6 | Not Detected |
| 1,2-Dichloroethane | 0.50 | Not Detected | 2.0 | Not Detected |
| Heptane | 0.50 | Not Detected | 2.0 | Not Detected |
| Trichloroethene | 0.50 | Not Detected | 2.7 | Not Detected |
| 1,2-Dichloropropane | 0.50 | Not Detected | 2.3 | Not Detected |
| 1,4-Dioxane | 2.0 | Not Detected | 7.2 | Not Detected |
| Bromodichloromethane | 0.50 | Not Detected | 3.4 | Not Detected |
| cis-1,3-Dichloropropene | 0.50 | Not Detected | 2.3 | Not Detected |
| 4-Methyl-2-pentanone | 0.50 | Not Detected | 2.0 | Not Detected |
| Toluene | 0.50 | Not Detected | 1.9 | Not Detected |
| trans-1,3-Dichloropropene | 0.50 | Not Detected | 2.3 | Not Detected |
| 1,1,2-Trichloroethane | 0.50 | Not Detected | 2.7 | Not Detected |
| Tetrachloroethene | 0.50 | Not Detected | 3.4 | Not Detected |
| 2-Hexanone | 2.0 | Not Detected | 8.2 | Not Detected |

**Client Sample ID: Lab Blank**

**Lab ID#: 1301353AR1-05A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **3012210** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 1/22/13 12:39 PM** | |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Dibromochloromethane | 0.50 | Not Detected | 4.2 | Not Detected |
| 1,2-Dibromoethane (EDB) | 0.50 | Not Detected | 3.8 | Not Detected |
| Chlorobenzene | 0.50 | Not Detected | 2.3 | Not Detected |
| Ethyl Benzene | 0.50 | Not Detected | 2.2 | Not Detected |
| m,p-Xylene | 0.50 | Not Detected | 2.2 | Not Detected |
| o-Xylene | 0.50 | Not Detected | 2.2 | Not Detected |
| Styrene | 0.50 | Not Detected | 2.1 | Not Detected |
| Bromoform | 0.50 | Not Detected | 5.2 | Not Detected |
| Cumene | 0.50 | Not Detected | 2.4 | Not Detected |
| 1,1,2,2-Tetrachloroethane | 0.50 | Not Detected | 3.4 | Not Detected |
| Propylbenzene | 0.50 | Not Detected | 2.4 | Not Detected |
| 4-Ethyltoluene | 0.50 | Not Detected | 2.4 | Not Detected |
| 1,3,5-Trimethylbenzene | 0.50 | Not Detected | 2.4 | Not Detected |
| 1,2,4-Trimethylbenzene | 0.50 | Not Detected | 2.4 | Not Detected |
| 1,3-Dichlorobenzene | 0.50 | Not Detected | 3.0 | Not Detected |
| 1,4-Dichlorobenzene | 0.50 | 0.059 J | 3.0 | 0.36 J |
| alpha-Chlorotoluene | 0.50 | Not Detected | 2.6 | Not Detected |
| 1,2-Dichlorobenzene | 0.50 | Not Detected | 3.0 | Not Detected |
| 1,2,4-Trichlorobenzene | 2.0 | Not Detected | 15 | Not Detected |
| Hexachlorobutadiene | 2.0 | Not Detected | 21 | Not Detected |
| Butane | 2.0 | Not Detected | 4.8 | Not Detected |
| Isopentane | 2.0 | Not Detected | 5.9 | Not Detected |

J = Estimated value.

**TENTATIVELY IDENTIFIED COMPOUNDS**

| Compound | CAS Number | Match Quality | Amount ((ppbv)) |
|---|---|---|---|
| None Identified | | | |

**Container Type: NA - Not Applicable**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| Toluene-d8 | 88 | 70-130 |
| 1,2-Dichloroethane-d4 | 84 | 70-130 |
| 4-Bromofluorobenzene | 94 | 70-130 |

eurofins | Air Toxics

**Client Sample ID: CCV**

**Lab ID#: 1301353AR1-06A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **3012202** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 1/22/13 09:02 AM** | |

| Compound | %Recovery |
|---|---|
| Freon 12 | 94 |
| Freon 114 | 105 |
| Chloromethane | 96 |
| Vinyl Chloride | 105 |
| 1,3-Butadiene | 105 |
| Bromomethane | 116 |
| Chloroethane | 105 |
| Freon 11 | 93 |
| Ethanol | 107 |
| Freon 113 | 109 |
| 1,1-Dichloroethene | 116 |
| Acetone | 110 |
| 2-Propanol | 108 |
| Carbon Disulfide | 110 |
| 3-Chloropropene | 117 |
| Methylene Chloride | 97 |
| Methyl tert-butyl ether | 119 |
| trans-1,2-Dichloroethene | 120 |
| Hexane | 124 |
| 1,1-Dichloroethane | 101 |
| 2-Butanone (Methyl Ethyl Ketone) | 105 |
| cis-1,2-Dichloroethene | 114 |
| Tetrahydrofuran | 107 |
| Chloroform | 96 |
| 1,1,1-Trichloroethane | 92 |
| Cyclohexane | 120 |
| Carbon Tetrachloride | 91 |
| 2,2,4-Trimethylpentane | 115 |
| Benzene | 91 |
| 1,2-Dichloroethane | 77 |
| Heptane | 106 |
| Trichloroethene | 89 |
| 1,2-Dichloropropane | 89 |
| 1,4-Dioxane | 92 |
| Bromodichloromethane | 81 |
| cis-1,3-Dichloropropene | 97 |
| 4-Methyl-2-pentanone | 103 |
| Toluene | 90 |
| trans-1,3-Dichloropropene | 108 |
| 1,1,2-Trichloroethane | 99 |
| Tetrachloroethene | 102 |
| 2-Hexanone | 116 |

**Client Sample ID: CCV**

**Lab ID#: 1301353AR1-06A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **3012202** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 1/22/13 09:02 AM** | |

| Compound | %Recovery |
|---|---|
| Dibromochloromethane | 99 |
| 1,2-Dibromoethane (EDB) | 102 |
| Chlorobenzene | 98 |
| Ethyl Benzene | 109 |
| m,p-Xylene | 112 |
| o-Xylene | 116 |
| Styrene | 118 |
| Bromoform | 100 |
| Cumene | 115 |
| 1,1,2,2-Tetrachloroethane | 91 |
| Propylbenzene | 106 |
| 4-Ethyltoluene | 111 |
| 1,3,5-Trimethylbenzene | 117 |
| 1,2,4-Trimethylbenzene | 122 |
| 1,3-Dichlorobenzene | 100 |
| 1,4-Dichlorobenzene | 102 |
| alpha-Chlorotoluene | 111 |
| 1,2-Dichlorobenzene | 100 |
| 1,2,4-Trichlorobenzene | 93 |
| Hexachlorobutadiene | 91 |
| Butane | 98 |
| Isopentane | 102 |

**Container Type: NA - Not Applicable**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| Toluene-d8 | 90 | 70-130 |
| 1,2-Dichloroethane-d4 | 83 | 70-130 |
| 4-Bromofluorobenzene | 98 | 70-130 |

eurofins | Air Toxics

**Client Sample ID: LCS**

**Lab ID#: 1301353AR1-07A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **3012203** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 1/22/13 09:31 AM** | |

| Compound | %Recovery |
|---|---|
| Freon 12 | 94 |
| Freon 114 | 106 |
| Chloromethane | 92 |
| Vinyl Chloride | 106 |
| 1,3-Butadiene | 106 |
| Bromomethane | 113 |
| Chloroethane | 106 |
| Freon 11 | 93 |
| Ethanol | 103 |
| Freon 113 | 112 |
| 1,1-Dichloroethene | 126 |
| Acetone | 111 |
| 2-Propanol | 110 |
| Carbon Disulfide | 137 Q |
| 3-Chloropropene | 139 Q |
| Methylene Chloride | 97 |
| Methyl tert-butyl ether | 119 |
| trans-1,2-Dichloroethene | 135 Q |
| Hexane | 122 |
| 1,1-Dichloroethane | 101 |
| 2-Butanone (Methyl Ethyl Ketone) | 110 |
| cis-1,2-Dichloroethene | 115 |
| Tetrahydrofuran | 102 |
| Chloroform | 97 |
| 1,1,1-Trichloroethane | 94 |
| Cyclohexane | 119 |
| Carbon Tetrachloride | 92 |
| 2,2,4-Trimethylpentane | 115 |
| Benzene | 89 |
| 1,2-Dichloroethane | 74 |
| Heptane | 103 |
| Trichloroethene | 88 |
| 1,2-Dichloropropane | 87 |
| 1,4-Dioxane | 93 |
| Bromodichloromethane | 81 |
| cis-1,3-Dichloropropene | 95 |
| 4-Methyl-2-pentanone | 96 |
| Toluene | 86 |
| trans-1,3-Dichloropropene | 106 |
| 1,1,2-Trichloroethane | 98 |
| Tetrachloroethene | 98 |
| 2-Hexanone | 110 |

**Client Sample ID: LCS**

**Lab ID#: 1301353AR1-07A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **3012203** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 1/22/13 09:31 AM** | |

| Compound | %Recovery |
|---|---|
| Dibromochloromethane | 97 |
| 1,2-Dibromoethane (EDB) | 100 |
| Chlorobenzene | 96 |
| Ethyl Benzene | 106 |
| m,p-Xylene | 112 |
| o-Xylene | 115 |
| Styrene | 115 |
| Bromoform | 99 |
| Cumene | 115 |
| 1,1,2,2-Tetrachloroethane | 92 |
| Propylbenzene | 106 |
| 4-Ethyltoluene | 105 |
| 1,3,5-Trimethylbenzene | 116 |
| 1,2,4-Trimethylbenzene | 119 |
| 1,3-Dichlorobenzene | 101 |
| 1,4-Dichlorobenzene | 102 |
| alpha-Chlorotoluene | 109 |
| 1,2-Dichlorobenzene | 102 |
| 1,2,4-Trichlorobenzene | 101 |
| Hexachlorobutadiene | 94 |
| Butane | 100 |
| Isopentane | 101 |

Q = Exceeds Quality Control limits.

**Container Type: NA - Not Applicable**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| Toluene-d8 | 89 | 70-130 |
| 1,2-Dichloroethane-d4 | 82 | 70-130 |
| 4-Bromofluorobenzene | 97 | 70-130 |

**Client Sample ID: LCSD**

**Lab ID#: 1301353AR1-07AA**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **3012204** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 1/22/13 09:49 AM** | |

| Compound | %Recovery |
|---|---|
| Freon 12 | 89 |
| Freon 114 | 99 |
| Chloromethane | 94 |
| Vinyl Chloride | 102 |
| 1,3-Butadiene | 100 |
| Bromomethane | 109 |
| Chloroethane | 100 |
| Freon 11 | 88 |
| Ethanol | 97 |
| Freon 113 | 105 |
| 1,1-Dichloroethene | 120 |
| Acetone | 104 |
| 2-Propanol | 103 |
| Carbon Disulfide | 131 Q |
| 3-Chloropropene | 131 Q |
| Methylene Chloride | 92 |
| Methyl tert-butyl ether | 112 |
| trans-1,2-Dichloroethene | 130 |
| Hexane | 115 |
| 1,1-Dichloroethane | 98 |
| 2-Butanone (Methyl Ethyl Ketone) | 101 |
| cis-1,2-Dichloroethene | 110 |
| Tetrahydrofuran | 99 |
| Chloroform | 93 |
| 1,1,1-Trichloroethane | 90 |
| Cyclohexane | 116 |
| Carbon Tetrachloride | 88 |
| 2,2,4-Trimethylpentane | 112 |
| Benzene | 88 |
| 1,2-Dichloroethane | 73 |
| Heptane | 100 |
| Trichloroethene | 86 |
| 1,2-Dichloropropane | 85 |
| 1,4-Dioxane | 85 |
| Bromodichloromethane | 79 |
| cis-1,3-Dichloropropene | 92 |
| 4-Methyl-2-pentanone | 94 |
| Toluene | 87 |
| trans-1,3-Dichloropropene | 103 |
| 1,1,2-Trichloroethane | 96 |
| Tetrachloroethene | 97 |
| 2-Hexanone | 106 |

**Client Sample ID: LCSD**

**Lab ID#: 1301353AR1-07AA**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **3012204** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 1/22/13 09:49 AM** | |

| Compound | %Recovery |
|---|---|
| Dibromochloromethane | 95 |
| 1,2-Dibromoethane (EDB) | 99 |
| Chlorobenzene | 96 |
| Ethyl Benzene | 105 |
| m,p-Xylene | 110 |
| o-Xylene | 113 |
| Styrene | 112 |
| Bromoform | 96 |
| Cumene | 113 |
| 1,1,2,2-Tetrachloroethane | 91 |
| Propylbenzene | 104 |
| 4-Ethyltoluene | 104 |
| 1,3,5-Trimethylbenzene | 114 |
| 1,2,4-Trimethylbenzene | 116 |
| 1,3-Dichlorobenzene | 100 |
| 1,4-Dichlorobenzene | 101 |
| alpha-Chlorotoluene | 104 |
| 1,2-Dichlorobenzene | 100 |
| 1,2,4-Trichlorobenzene | 104 |
| Hexachlorobutadiene | 95 |
| Butane | 90 |
| Isopentane | 96 |

Q = Exceeds Quality Control limits.

**Container Type: NA - Not Applicable**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| Toluene-d8 | 89 | 70-130 |
| 1,2-Dichloroethane-d4 | 82 | 70-130 |
| 4-Bromofluorobenzene | 97 | 70-130 |

1301353

# Shell Oil Products Chain Of Custody Record

URS

Air Toxics LTD.
Project Name: Roxana Soil Vapor
Project # 21562850.04001
Lab Vendor #

Please Check Appropriate Box:
☑ ENV. SERVICES ☐ MOTIVA RETAIL ☐ SHELL RETAIL
☐ MOTIVA SD&CN ☐ CONSULTANT ☐ LUBES
☐ SHELL PIPELINE ☐ OTHER

Print Bill To Contact Name: Robert Mooshegian
INCIDENT # (ENV SERVICES): 9 7 2 1 6 6 4 0
☐ CHECK IF NO INCIDENT # APPLIES
DATE: 01/21/13
PO #
SAP #: 3 4 0 0 6 1
PAGE: 1 of 1

SAMPLING COMPANY: URS CORPORATION
LOG CODE:
SITE ADDRESS: Street and City: 900 SOUTH CENTRAL AVE -- ROXANA
State: IL
GLOBAL ID NO.:
ADDRESS: 1001 HIGHLANDS PLAZA DRIVE WEST - SUITE 300; ST. LOUIS, MO 63110
EDF DELIVERABLE TO (Name, Company, Office Location): Elizabeth Kunkel, URS, St. Louis
PHONE NO.: 314-743-4179
E-MAIL: Elizabeth_Kunkel@URSCorp.com
CONSULTANT PROJECT NAME#: Roxana Soil Vapor
Laboratory Address: Air Toxics, LTD 180 Blue Ravine Road, Suite B, Folsom, CA 95630-4719
M. Currier, E. Arthur, A. Day, B. Lehon
TELEPHONE: 314-429-0100
FAX: 314-429-0462
Bill To Contact E-MAIL: Robert.Mooshegian@urs.com

TURNAROUND TIME (CALENDAR DAYS): SAME DAY
☐ STANDARD (14 DAY) ☐ 5 DAYS ☐ 3 DAYS ☐ 2 DAYS ☐ 24 HOURS ☐ RESULTS NEEDED ON WEEKEND

REQUESTED ANALYSIS

☐ LA - RWQCB REPORT FORMAT ☑ UST AGENCY:
DELIVERABLES: ☐ LEVEL 1 ☐ LEVEL 2 ☐ LEVEL 3 ☑ LEVEL 4 ☐ OTHER (SPECIFY)

☑ SHELL CONTRACT RATE APPLIES
☐ STATE REIMBURSEMENT RATE APPLIES
☐ EDD NOT NEEDED
☑ RECEIPT VERIFICATION REQUESTED

Turn Around Time:
☐ Normal
☑ Rush
SAME DAY Specify

Lab Use Only
Pressurized by:
Date:
Pressurization Gas: $N_2$ He

| LAB USE ONLY | Field Sample Identification | SAMPLING DATE | SAMPLING TIME | Canister Number | Canister Pressure/Vacuum Initial | Final | Receipt | Final (psi) | Modified TO-15 + Butane & Isopentane | ASTM D-1946 + Hollium | ASTM D-1946 |
|---|---|---|---|---|---|---|---|---|---|---|---|
| | VMP-47-5-012113 | 01/21/13 | 1210-1240 | 12372 | -30 | -11 | | | X | X | |
| | VMP-47-10-012113 | 01/21/13 | 1310-1340 | 8019 | -30 | -9 | | | X | X | |
| | VMP-1-5-012113 | 01/21/13 | 1108-1138 | 1033 | -30 | -8.5 | | | X | X | |
| | VMP-1-38.5-012113 | 01/21/13 | 1532-1602 | 31790 | -30 | -9 | | | X | X | |

ADDITIONAL NOTES:
- Same day turn around time
- Report results between MDL and RL
- Level IV ECVP

| | | | |
|---|---|---|---|
| Relinquished by: (Signature) | Received by: (Signature) FEDEX | Date: 1/21/13 | Time: 1830 |
| Relinquished by: (Signature) | Received by: (Signature) | Date: 1/22/13 | Time: 1045 |
| Relinquished by: (Signature) | Received by: (Signature) | Date: | Time |

05/2/05 Revision

Custody Seal Intact?
Y N None Temp N/A

eurofins | Air Toxics

2/12/2013
Ms. Elizabeth Kunkel
URS Corporation
1001 Highlands Plaza Dr. West
Suite 300
St. Louis MO 63110

Project Name: Roxana Soil Vapor
Project #:
Workorder #: 1301353BR1

Dear Ms. Elizabeth Kunkel

The following report includes the data for the above referenced project for sample(s) received on 1/22/2013 at Air Toxics Ltd.

The data and associated QC analyzed by Modified ASTM D-1945 are compliant with the project requirements or laboratory criteria with the exception of the deviations noted in the attached case narrative.

Thank you for choosing Air Toxics Ltd. for your air analysis needs. Air Toxics Ltd. is committed to providing accurate data of the highest quality. Please feel free to contact the Project Manager: Kelly Buettner at 916-985-1000 if you have any questions regarding the data in this report.

Regards,

Kelly Buettner

Project Manager

Reviewed
on
2/18/2013

eurofins | Air Toxics

# WORK ORDER #: 1301353BR1

Work Order Summary

| | | | |
|---|---|---|---|
| **CLIENT:** | Ms. Elizabeth Kunkel<br>URS Corporation<br>1001 Highlands Plaza Dr. West<br>Suite 300<br>St. Louis, MO 63110 | **BILL TO:** | Accounts Payable Austin<br>URS Corporation<br>P.O. BOX 203970<br>Austin, TX 78720-1088 |
| **PHONE:** | 314-743-4179 | **P.O. #** | 21562735.00013 |
| **FAX:** | | **PROJECT #** | Roxana Soil Vapor |
| **DATE RECEIVED:** | 01/22/2013 | **CONTACT:** | Kelly Buettner |
| **DATE COMPLETED:** | 01/23/2013 | | |
| **DATE REISSUED:** | 02/12/2013 | | |

| FRACTION # | NAME | TEST | RECEIPT VAC./PRES. | FINAL PRESSURE |
|---|---|---|---|---|
| 01A | VMP-47-5-012113 | Modified ASTM D-1945 | 9.0 "Hg | 15 psi |
| 02A | VMP-47-10-012113 | Modified ASTM D-1945 | 8.0 "Hg | 15 psi |
| 03A | VMP-1-5-012113 | Modified ASTM D-1945 | 6.5 "Hg | 15 psi |
| 04A | VMP-1-38.5-012113 | Modified ASTM D-1945 | 7.0 "Hg | 15 psi |
| 05A | Lab Blank | Modified ASTM D-1945 | NA | NA |
| 05B | Lab Blank | Modified ASTM D-1945 | NA | NA |
| 06A | LCS | Modified ASTM D-1945 | NA | NA |
| 06AA | LCSD | Modified ASTM D-1945 | NA | NA |

CERTIFIED BY: Heidi Hayes DATE: 02/12/13

Technical Director

Certification numbers: AZ Licensure AZ0775, CA NELAP - 12282CA, NY NELAP - 11291, TX NELAP - T104704434-12-4, UT NELAP CA009332012-3, WA NELAP - C935
Name of Accrediting Agency: NELAP/ORELAP (Oregon Environmental Laboratory Accreditation Program)
Accreditation number: CA300005, Effective date: 10/18/2012, Expiration date: 10/17/2013.
Eurofins Air Toxics Ltd. certifies that the test results contained in this report meet all requirements of the NELAC standards

This report shall not be reproduced, except in full, without the written approval of Eurofins Air Toxics, Inc.

180 BLUE RAVINE ROAD, SUITE B FOLSOM, CA - 9563
(916) 985-1000 . (800) 985-5955 . FAX (916) 985-1020

**LABORATORY NARRATIVE**
**Modified ASTM D-1946**
**URS Corporation**
**Workorder# 1301353BR1**

Four 1 Liter Summa Canister samples were received on January 22, 2013. The laboratory performed analysis via Modified ASTM Method D-1946 for Methane and fixed gases in air using GC/FID or GC/TCD. The method involves direct injection of 1.0 mL of sample.

On the analytical column employed for this analysis, Oxygen coelutes with Argon. The corresponding peak is quantitated as Oxygen.

Since Nitrogen is used to pressurize samples, the reported Nitrogen values are calculated by adding all the sample components and subtracting from 100%.

Method modifications taken to run these samples are summarized in the table below. Specific project requirements may over-ride the ATL modifications.

| *Requirement* | *ASTM D-1946* | *ATL Modifications* |
|---|---|---|
| Calibration | A single point calibration is performed using a reference standard closely matching the composition of the unknown. | A 3-point calibration curve is performed. Quantitation is based on a daily calibration standard which may or may not resemble the composition of the associated samples. |
| Reference Standard | The composition of any reference standard must be known to within 0.01 mol % for any component. | The standards used by ATL are blended to a >/= 95% accuracy. |
| Sample Injection Volume | Components whose concentrations are in excess of 5 % should not be analyzed by using sample volumes greater than 0.5 mL. | The sample container is connected directly to a fixed volume sample loop of 1.0 mL on the GC. Linear range is defined by the calibration curve. Bags are loaded by vacuum. |
| Normalization | Normalize the mole percent values by multiplying each value by 100 and dividing by the sum of the original values. The sum of the original values should not differ from 100% by more than 1.0%. | Results are not normalized. The sum of the reported values can differ from 100% by as much as 15%, either due to analytical variability or an unusual sample matrix. |
| Precision | Precision requirements established at each concentration level. | Duplicates should agree within 25% RPD for detections > 5 X's the RL. |

**Receiving Notes**

There were no receiving discrepancies.

**Analytical Notes**

As per project specific client request the laboratory has reported estimated values for target compound hits that are below the Reporting Limit but greater than the Method Detection Limit. Concentrations that are below the level at which the canister was certified may be false positives.

The reporting limit for Carbon Monoxide was raised from 0.010% to 0.050%.

THE WORKORDER WAS REISSUED ON 02/12/13 TO REPORT ADDITIONAL COMPOUNDS FOR VMP-47-5-012113, VMP-47-10-012113, VMP-1-5-012113 and VMP-1-38.5-012113 PER CLIENT REQUEST.

**Definition of Data Qualifying Flags**

Seven qualifiers may have been used on the data analysis sheets and indicate as follows:
B - Compound present in laboratory blank greater than reporting limit.
J - Estimated value.
E - Exceeds instrument calibration range.
S - Saturated peak.
Q - Exceeds quality control limits.
U - Compound analyzed for but not detected above the detection limit.
M - Reported value may be biased due to apparent matrix interferences.
File extensions may have been used on the data analysis sheets and indicates as follows:
a-File was requantified
b-File was quantified by a second column and detector
r1-File was requantified for the purpose of reissue

eurofins | Air Toxics

# Summary of Detected Compounds
# NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1945

**Client Sample ID: VMP-47-5-012113**

**Lab ID#: 1301353BR1-01A**

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.29 | 12 |
| Nitrogen | 0.29 | 81 |
| Methane | 0.00029 | 0.000020 J |
| Carbon Dioxide | 0.029 | 6.8 |

**Client Sample ID: VMP-47-10-012113**

**Lab ID#: 1301353BR1-02A**

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.28 | 5.3 |
| Nitrogen | 0.28 | 83 |
| Carbon Dioxide | 0.028 | 12 |

**Client Sample ID: VMP-1-5-012113**

**Lab ID#: 1301353BR1-03A**

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.26 | 21 |
| Nitrogen | 0.26 | 78 |
| Methane | 0.00026 | 0.0016 |
| Carbon Dioxide | 0.026 | 0.34 |
| Isobutane | 0.0026 | 0.000084 J |
| Butane | 0.0026 | 0.00090 J |
| Isopentane | 0.0026 | 0.00091 J |
| Pentane | 0.0026 | 0.00029 J |
| C6+ | 0.026 | 0.0011 J |
| Helium | 0.13 | 0.17 |

**Client Sample ID: VMP-1-38.5-012113**

**Lab ID#: 1301353BR1-04A**

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|

eurofins | Air Toxics

# Summary of Detected Compounds
# NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1945

**Client Sample ID: VMP-1-38.5-012113**

**Lab ID#: 1301353BR1-04A**

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.26 | 20 |
| Nitrogen | 0.26 | 73 |
| Methane | 0.00026 | 0.0012 |
| Carbon Dioxide | 0.026 | 0.13 |
| Butane | 0.0026 | 0.00036 J |
| Isopentane | 0.0026 | 0.00024 J |
| Pentane | 0.0026 | 0.000084 J |
| C6+ | 0.026 | 0.00016 J |
| Helium | 0.13 | 6.6 |

eurofins | Air Toxics

**Client Sample ID: VMP-47-5-012113**

**Lab ID#: 1301353BR1-01A**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1945**

| | | | |
|---|---|---|---|
| **File Name:** | **9012220r1** | **Date of Collection: 1/21/13 12:40:00 PM** | |
| **Dil. Factor:** | **2.89** | **Date of Analysis: 1/22/13 04:57 PM** | |

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.29 | 12 |
| Nitrogen | 0.29 | 81 |
| Carbon Monoxide | 0.14 | Not Detected |
| Methane | 0.00029 | 0.000020 J |
| Carbon Dioxide | 0.029 | 6.8 |
| Ethane | 0.0029 | Not Detected |
| Ethene | 0.0029 | Not Detected |
| Acetylene | 0.0029 | Not Detected |
| Propane | 0.0029 | Not Detected |
| Isobutane | 0.0029 | Not Detected |
| Butane | 0.0029 | Not Detected |
| Neopentane | 0.0029 | Not Detected |
| Isopentane | 0.0029 | Not Detected |
| Pentane | 0.0029 | Not Detected |
| C6+ | 0.029 | Not Detected |
| Helium | 0.14 | Not Detected |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

eurofins | Air Toxics

**Client Sample ID: VMP-47-10-012113**

**Lab ID#: 1301353BR1-02A**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1945**

| | | | |
|---|---|---|---|
| **File Name:** | **9012221r1** | **Date of Collection:** | **1/21/13 1:40:00 PM** |
| **Dil. Factor:** | **2.76** | **Date of Analysis:** | **1/22/13 05:28 PM** |

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.28 | 5.3 |
| Nitrogen | 0.28 | 83 |
| Carbon Monoxide | 0.14 | Not Detected |
| Methane | 0.00028 | Not Detected |
| Carbon Dioxide | 0.028 | 12 |
| Ethane | 0.0028 | Not Detected |
| Ethene | 0.0028 | Not Detected |
| Acetylene | 0.0028 | Not Detected |
| Propane | 0.0028 | Not Detected |
| Isobutane | 0.0028 | Not Detected |
| Butane | 0.0028 | Not Detected |
| Neopentane | 0.0028 | Not Detected |
| Isopentane | 0.0028 | Not Detected |
| Pentane | 0.0028 | Not Detected |
| C6+ | 0.028 | Not Detected |
| Helium | 0.14 | Not Detected |

**Container Type: 1 Liter Summa Canister**

eurofins | Air Toxics

**Client Sample ID: VMP-1-5-012113**

**Lab ID#: 1301353BR1-03A**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1945**

| | | | |
|---|---|---|---|
| **File Name:** | **9012222r1** | **Date of Collection:** | **1/21/13 11:38:00 AM** |
| **Dil. Factor:** | **2.58** | **Date of Analysis:** | **1/22/13 05:58 PM** |

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.26 | 21 |
| Nitrogen | 0.26 | 78 |
| Carbon Monoxide | 0.13 | Not Detected |
| Methane | 0.00026 | 0.0016 |
| Carbon Dioxide | 0.026 | 0.34 |
| Ethane | 0.0026 | Not Detected |
| Ethene | 0.0026 | Not Detected |
| Acetylene | 0.0026 | Not Detected |
| Propane | 0.0026 | Not Detected |
| Isobutane | 0.0026 | 0.000084 J |
| Butane | 0.0026 | 0.00090 J |
| Neopentane | 0.0026 | Not Detected |
| Isopentane | 0.0026 | 0.00091 J |
| Pentane | 0.0026 | 0.00029 J |
| C6+ | 0.026 | 0.0011 J |
| Helium | 0.13 | 0.17 |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

eurofins | Air Toxics

**Client Sample ID: VMP-1-38.5-012113**

**Lab ID#: 1301353BR1-04A**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1945**

| | | | |
|---|---|---|---|
| **File Name:** | **9012223r1** | **Date of Collection: 1/21/13 4:02:00 PM** | |
| **Dil. Factor:** | **2.64** | **Date of Analysis: 1/22/13 06:21 PM** | |

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.26 | 20 J |
| Nitrogen | 0.26 | 73 J |
| Carbon Monoxide | 0.13 | Not Detected UJ |
| Methane | 0.00026 | 0.0012 J |
| Carbon Dioxide | 0.026 | 0.13 J |
| Ethane | 0.0026 | Not Detected UJ |
| Ethene | 0.0026 | Not Detected |
| Acetylene | 0.0026 | Not Detected |
| Propane | 0.0026 | Not Detected |
| Isobutane | 0.0026 | Not Detected |
| Butane | 0.0026 | 0.00036 J J |
| Neopentane | 0.0026 | Not Detected UJ |
| Isopentane | 0.0026 | 0.00024 J J |
| Pentane | 0.0026 | 0.000084 J J |
| C6+ | 0.026 | 0.00016 J J |
| Helium | 0.13 | 6.6 J |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

eurofins | Air Toxics

**Client Sample ID: Lab Blank**

**Lab ID#: 1301353BR1-05A**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1945**

| | | | |
|---|---|---|---|
| **File Name:** | **9012214a** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 1/22/13 02:03 PM** | |

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.10 | Not Detected |
| Nitrogen | 0.10 | 0.087 J |
| Carbon Monoxide | 0.050 | Not Detected |
| Methane | 0.00010 | Not Detected |
| Carbon Dioxide | 0.010 | Not Detected |
| Ethane | 0.0010 | Not Detected |
| Ethene | 0.0010 | Not Detected |
| Acetylene | 0.0010 | Not Detected |
| Propane | 0.0010 | Not Detected |
| Isobutane | 0.0010 | Not Detected |
| Butane | 0.0010 | Not Detected |
| Neopentane | 0.0010 | Not Detected |
| Isopentane | 0.0010 | Not Detected |
| Pentane | 0.0010 | Not Detected |
| C6+ | 0.010 | Not Detected |

J = Estimated value.

**Container Type: NA - Not Applicable**

eurofins | Air Toxics

**Client Sample ID: Lab Blank**

**Lab ID#: 1301353BR1-05B**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1945**

| | | | |
|---|---|---|---|
| **File Name:** | **9012213b** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 1/22/13 01:41 PM** | |

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Helium | 0.050 | Not Detected |

**Container Type: NA - Not Applicable**

eurofins | Air Toxics

**Client Sample ID: LCS**

**Lab ID#: 1301353BR1-06A**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1945**

| | | | |
|---|---|---|---|
| **File Name:** | **9012202** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 1/22/13 08:08 AM** | |

| Compound | %Recovery |
|---|---|
| Oxygen | 100 |
| Nitrogen | 100 |
| Carbon Monoxide | 97 |
| Methane | 102 |
| Carbon Dioxide | 101 |
| Ethane | 103 |
| Ethene | 100 |
| Acetylene | 102 |
| Propane | 106 |
| Isobutane | 106 |
| Butane | 104 |
| Neopentane | 105 |
| Isopentane | 104 |
| Pentane | 104 |
| C6+ | 104 |
| Helium | 102 |

**Container Type: NA - Not Applicable**

eurofins | Air Toxics

**Client Sample ID: LCSD**

**Lab ID#: 1301353BR1-06AA**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1945**

| | | | |
|---|---|---|---|
| **File Name:** | **9012224** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 1/22/13 06:43 PM** | |

| Compound | %Recovery |
|---|---|
| Oxygen | 101 |
| Nitrogen | 101 |
| Carbon Monoxide | 96 |
| Methane | 107 |
| Carbon Dioxide | 101 |
| Ethane | 109 |
| Ethene | 105 |
| Acetylene | 107 |
| Propane | 111 |
| Isobutane | 112 |
| Butane | 110 |
| Neopentane | 111 |
| Isopentane | 109 |
| Pentane | 109 |
| C6+ | 109 |
| Helium | 101 |

**Container Type: NA - Not Applicable**

1301353

# Shell Oil Products Chain Of Custody Record

URS

Air Toxics LTD.
Project Name: Roxana Soil Vapor
Project # 21562850.04001
Lab Vendor #

Please Check Appropriate Box:
☑ ENV. SERVICES ☐ MOTIVA RETAIL ☐ SHELL RETAIL
☐ MOTIVA SD&CM ☐ CONSULTANT ☐ LUBES
☐ SHELL PIPELINE ☐ OTHER

Print Bill To Contact Name: Robert Moosheglan
PO #:
INCIDENT # (ENV SERVICES): 9 7 2 1 6 6 4 0
SAP #: 3 4 0 0 6 1
☐ CHECK IF NO INCIDENT # APPLIES
DATE: 01/21/13
PAGE 1 of 1

SAMPLING COMPANY: URS CORPORATION
LOG CODE:
SITE ADDRESS: Street and City: 900 SOUTH CENTRAL AVE -- ROXANA
State: IL
GLOBAL ID NO.:
ADDRESS: 1001 HIGHLANDS PLAZA DRIVE WEST - SUITE 300, ST. LOUIS, MO 63110
EDF DELIVERABLE TO (Name, Company, Office Location): Elizabeth Kunkel, URS, St. Louis
PHONE NO.: 314-743-4179
E-MAIL: Elizabeth.Kunkel@URSCorp.com
CONSULTANT PROJECT NAME#: Roxana Soil Vapor
Laboratory Address: Air Toxics, LTD 180 Blue Ravine Road, Suite B, Folsom, CA 95630-4719
M. Currier, E. Arthur, A. Day, B. Lehan
TELEPHONE: 314-429-0100
FAX: 314-429-0462
EDF To Contact E-MAIL: Robert.Moosheglan@urs.com

TURNAROUND TIME (CALENDAR DAYS): (ONLY ONE)
☐ STANDARD (14 DAY) ☐ 5 DAYS ☐ 3 DAYS ☐ 2 DAYS ☐ 24 HOURS ☐ RESULTS NEEDED ON WEEKEND

☐ LA - RWQCB REPORT FORMAT ☑ UST AGENCY:
DELIVERABLES: ☐ LEVEL 1 ☐ LEVEL 2 ☐ LEVEL 3 ☑ LEVEL 4 ☐ OTHER (SPECIFY)

☑ SHELL CONTRACT RATE APPLIES
☐ STATE REIMBURSEMENT RATE APPLIES
☐ EDD NOT NEEDED
☑ RECEIPT VERIFICATION REQUESTED

REQUESTED ANALYSIS

| LAB USE ONLY | Field Sample Identification | SAMPLING DATE | SAMPLING TIME | Canister Number | Canister Pressure/Vacuum: Initial | Final | Receipt | Final (psi) | Modified TO-15 + Butane & Isopentane | ASTM D-1946 + Helium | ASTM D-1946 | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | VMP-47-5-012113 | 01/21/13 | 1210-1240 | 12372 | -30 | -11 | | | X | X | | | | | |
| | VMP-47-10-012113 | 01/21/13 | 1310-1340 | 8019 | -30 | -9 | | | X | X | | | | | |
| | VMP-1-5-012113 | 01/21/13 | 1105-1138 | 1033 | -30 | -8.5 | | | X | X | | | | | |
| | VMP-1-38.5-012113 | 01/21/13 | 1532-1602 | 31790 | -30 | -9 | | | X | X | | | | | |

Turn Around Time:
☐ Normal
☑ Rush
SAME DAY Specify

Lab use Only
Pressurized by:
Date:
Pressurization Gas: N2 He

ADDITIONAL NOTES:
- Same day turn around time
- Report results between MDL and RL
- Level IV ECVP

| Relinquished by (Signature) | Received by (Signature) | Date | Time |
|---|---|---|---|
| | FEDEX | 1/21/13 | 1830 |
| | | 1/22/13 | 1045 |
| | | | |

05/2/05 Revision

Custody Seal Intact?
Y N None Temp N/A

# Roxana Soil Vapor Quarterly – 1st Quarter 2013 Data Review

**Laboratory SDG: 1301354AR1,BR1**

**Data Reviewer: Elizabeth Kunkel**

**Peer Reviewer: Steve Gragert**

**Date Reviewed: 2/19/2013**

**Guidance: USEPA National Functional Guidelines for Superfund Organic Methods Data Review 2008**

| Sample Identification | Sample Identification |
|---|---|
| VMP-47-20-012113 | VMP-47-30-012113 |
| VMP-1-8.5-012113 | VMP-1-23.5-012113 |

## 1.0 Data Package Completeness

*Were all items delivered as specified in the QAPP and COC as appropriate?*

Yes, however, professional judgment was used to qualify sample VMP-1-23.5-012113 due to the helium result in the sample (6.2%) that was greater than 10% of helium in the shroud (48.8%).

## 2.0 Laboratory Case Narrative \ Cooler Receipt Form

*Were problems noted in the laboratory case narrative or cooler receipt form?*

The laboratory case narrative indicated samples VMP-47-20-012113, VMP-47-30-012113, and VMP-1-8.5-012113 were diluted due to high levels of targets of analytes. Sample VMP-1-8.5-012113 was diluted and re-analyzed to bring butane and isopentane within the calibration range of the instrument. Butane and isopentane results were reported from the re-analysis run and the remaining compounds were reported from the original analysis. The TO-15 LCSD recovery for Freon 11 was outside evaluation criteria. Although not indicated in the laboratory case narrative, analytes were detected in the method blank. The CCV recovery for 1,2,4-trichlorobenzene was outside evaluation criteria. These issues are addressed further in the appropriate sections below. The laboratory report was re-issued to report additional natural gas analytes via ASTM D-1945, and also the top five tentatively identified compounds (TICs) via TO-15. Additionally, the ethanol result was corrected in sample VMP-1-23.5-012113 due to laboratory error in having reported ethanol below the method detection limit.

No issues or discrepancies were noted in the cooler receipt form.

## 3.0 Holding Times

*Were samples extracted/analyzed within applicable limits?*

Yes

## 4.0 Blank Contamination

*Were any analytes detected in the Blanks?*

Yes

| Blank ID | Parameter | Analyte | Concentration/ Amount |
|---|---|---|---|
| 1301354A-05A | TO-15 | Acetone | 0.67 ppbv / 1.6 µg/m$^3$ |
| 1301354A-05A | TO-15 | 4-Ethyltoluene | 0.093 ppbv / 0.46 µg/m$^3$ |
| 1301354A-05B | TO-15 | Ethanol | 8.0 ppbv / 15 µg/m$^3$ |
| 1301354A-05B | TO-15 | Methylene chloride | 1.1 ppbv / 3.8 µg/m$^3$ |
| 13013574B-05A | Natural gases | Nitrogen | 0.087% |

Analytical data that were reported non-detect or at concentrations greater than five times (5X) the associated blank concentration did not require qualification. No qualification of data was required.

## 5.0 Laboratory Control Sample

*Were LCS recoveries within evaluation criteria?*

No

| LCS/LCSD ID | Parameter | Analyte | LCS/LCSD Recovery | LCS/ LCSD RPD | LCS/LCSD /RPD Criteria |
|---|---|---|---|---|---|
| 1301354A-07A/AA | TO-15 | Freon 11 | 71/**69** | 3 | 70-130/25 |

Analytical data that required qualification based on LCS data are included in the table below.

| Sample ID | Parameter | Analyte | Qualification |
|---|---|---|---|
| VMP-1-8.5-012113 | TO-15 | Freon 11 | **UJ** |
| VMP-1-23.5-012113 | TO-15 | Freon 11 | **UJ** |

## 6.0 Surrogate Recoveries

*Were surrogate recoveries within evaluation criteria?*

Yes

## 7.0 Matrix Spike and Matrix Spike Duplicate Recoveries

*Were MS/MSD samples analyzed as part of this SDG?*

MS/MSD samples are not applicable for vapor samples, due to the inability to spike the samples.

## 8.0 Laboratory Duplicate Results

*Were laboratory duplicate samples collected as part of this SDG?*

No

## 9.0 Field Duplicate Results

*Were field duplicate samples collected as part of this SDG?*

No

## 10.0 Sample Dilutions

*For samples that were diluted and nondetect, were undiluted results also reported?*

Not applicable; analytes were detected in samples that were diluted.

## 11.0 Additional Qualifications

*Were additional qualifications applied?*

Yes, professional judgment was used to qualify sample VMP-1-23.5-012113 due to the helium result in the sample (6.2%) that was greater than 10% of helium in the shroud (48.8%).

| Sample ID | Parameter | Analyte | Qualification |
|---|---|---|---|
| VMP-1-23.5-012113 | TO-15 | All detects | **J** |
| VMP-1-23.5-012113 | TO-15 | All non-detects | **UJ** |
| VMP-1-23.5-012113 | Natural gases | All detects | **J** |
| VMP-1-23.5-012113 | Natural gases | All non-detects | **UJ** |

Additionally, the CCV percent recovery for 1,2,4-trichlorobenzene was outside evaluation criteria as summarized in the table below.

| CCV ID | Parameter | Analyte | CCV Recovery | CCV Criteria |
|---|---|---|---|---|
| 1301354A-06A | TO-15 | 1,,2,4-Trichlorobenzene | **68** | 70-130 |

Data requiring qualification based on CCV recoveries are summarized in the following table.

| Sample ID | Parameter | Analyte | Qualification |
|---|---|---|---|
| VMP-1-8.5-012113 | TO-15 | 1,,2,4-Trichlorobenzene | **UJ** |
| VMP-1-23.5-012113 | TO-15 | 1,,2,4-Trichlorobenzene | **UJ** |

eurofins | Air Toxics

2/15/2013
Ms. Elizabeth Kunkel
URS Corporation
1001 Highlands Plaza Dr. West
Suite 300
St. Louis MO 63110

Project Name: Roxana Soil Vapor
Project #: 21562850.04001
Workorder #: 1301354AR1

Dear Ms. Elizabeth Kunkel

The following report includes the data for the above referenced project for sample(s) received on 1/22/2013 at Air Toxics Ltd.

The data and associated QC analyzed by Modified TO-15 are compliant with the project requirements or laboratory criteria with the exception of the deviations noted in the attached case narrative.

Thank you for choosing Air Toxics Ltd. for your air analysis needs. Air Toxics Ltd. is committed to providing accurate data of the highest quality. Please feel free to contact the Project Manager: Kelly Buettner at 916-985-1000 if you have any questions regarding the data in this report.

Regards,

Kelly Buettner

Project Manager

Reviewed
on
2/18/2013

eurofins | Air Toxics

# WORK ORDER #: 1301354AR1

Work Order Summary

| | | | |
|---|---|---|---|
| **CLIENT:** | Ms. Elizabeth Kunkel<br>URS Corporation<br>1001 Highlands Plaza Dr. West<br>Suite 300<br>St. Louis, MO 63110 | **BILL TO:** | Accounts Payable Austin<br>URS Corporation<br>P.O. BOX 203970<br>Austin, TX 78720-1088 |
| **PHONE:** | 314-743-4179 | **P.O. #** | 21562735.00013 |
| **FAX:** | | **PROJECT #** | 21562850.04001 Roxana Soil Vapor |
| **DATE RECEIVED:** | 01/22/2013 | **CONTACT:** | Kelly Buettner |
| **DATE COMPLETED:** | 01/23/2013 | | |
| **DATE REISSUED:** | 02/15/2013 | | |

| FRACTION # | NAME | TEST | RECEIPT VAC./PRES. | FINAL PRESSURE |
|---|---|---|---|---|
| 01A | VMP-47-20-012113 | Modified TO-15 | 6.0 "Hg | 15 psi |
| 02A | VMP-47-30-012113 | Modified TO-15 | 6.5 "Hg | 15 psi |
| 03A | VMP-1-8.5-012113 | Modified TO-15 | 5.5 "Hg | 15 psi |
| 03B | VMP-1-8.5-012113 | Modified TO-15 | 5.5 "Hg | 15 psi |
| 04A | VMP-1-23.5-012113 | Modified TO-15 | 7.5 "Hg | 15 psi |
| 05A | Lab Blank | Modified TO-15 | NA | NA |
| 05B | Lab Blank | Modified TO-15 | NA | NA |
| 06A | CCV | Modified TO-15 | NA | NA |
| 06B | CCV | Modified TO-15 | NA | NA |
| 07A | LCS | Modified TO-15 | NA | NA |
| 07AA | LCSD | Modified TO-15 | NA | NA |
| 07B | LCS | Modified TO-15 | NA | NA |
| 07BB | LCSD | Modified TO-15 | NA | NA |

CERTIFIED BY: Heidi Hayes DATE: 02/15/13

Technical Director

Certification numbers: AZ Licensure AZ0775, CA NELAP - 12282CA, NY NELAP - 11291,
TX NELAP - T104704434-12-4, UT NELAP CA009332012-3, WA NELAP - C935
Name of Accrediting Agency: NELAP/ORELAP (Oregon Environmental Laboratory Accreditation Program)
Accreditation number: CA300005, Effective date: 10/18/2012, Expiration date: 10/17/2013.
Eurofins Air Toxics Ltd. certifies that the test results contained in this report meet all requirements of the NELAC standards

This report shall not be reproduced, except in full, without the written approval of Eurofins Air Toxics, Inc.

180 BLUE RAVINE ROAD, SUITE B FOLSOM, CA - 9563
(916) 985-1000 . (800) 985-5955 . FAX (916) 985-1020

**LABORATORY NARRATIVE**
**EPA Method TO-15**
**URS Corporation**
**Workorder# 1301354AR1**

Four 1 Liter Summa Canister samples were received on January 22, 2013. The laboratory performed analysis via EPA Method TO-15 using GC/MS in the full scan mode.

This workorder was independently validated prior to submittal using 'USEPA National Functional Guidelines' as generally applied to the analysis of volatile organic compounds in air. A rules-based, logic driven, independent validation engine was employed to assess completeness, evaluate pass/fail of relevant project quality control requirements and verification of all quantified amounts.

**Receiving Notes**

There were no receiving discrepancies.

**Analytical Notes**

As per client project requirements, the laboratory has reported estimated values for target compound hits that are below the Reporting Limit but greater than the Method Detection Limit.

Due to high-level target compounds, sample VMP-1-8.5-012113 was analyzed twice. In the "A" fraction, the sample was diluted to bring the highest-level compounds within the calibration range. The "B" fraction is also reported by client request and may be reported with "E" flags indicating the compound exceeds the calibration range. Both runs and associated QC are reported.

Dilution was performed on samples VMP-47-20-012113, VMP-47-30-012113, VMP-1-8.5-012113 and VMP-1-23.5-012113 due to the presence of high level target species.

All Quality Control Limit exceedances and affected sample results are noted by flags. Each flag is defined at the bottom of this Case Narrative and on each Sample Result Summary page.

THE WORK ORDER WAS RE-ISSUED ON FEBRUARY 15, 2013 FOR THE FOLLOWING REASONS:

1. TO REPORT THE TOP 5 TENTATIVELY IDENTIFIED COMPOUNDS PER CLIENT'S REQUEST.

2. TO REMOVE RESULTS FOR ETHANOL IN SAMPLE VMP-1-23.5-012113 WHICH WAS PREVIOUSLY REPORTED WITH A VALUE OF LESS THAN THE METHOD DETECTION LIMIT DUE TO LABORATORY ERROR.

**Definition of Data Qualifying Flags**

Eight qualifiers may have been used on the data analysis sheets and indicates as follows:

B - Compound present in laboratory blank greater than reporting limit (background subtraction not performed).

J - Estimated value.

E - Exceeds instrument calibration range.

S - Saturated peak.
Q - Exceeds quality control limits.
U - Compound analyzed for but not detected above the reporting limit.
UJ- Non-detected compound associated with low bias in the CCV
N - The identification is based on presumptive evidence.

File extensions may have been used on the data analysis sheets and indicates as follows:
a-File was requantified
b-File was quantified by a second column and detector
r1-File was requantified for the purpose of reissue

eurofins | Air Toxics

# Summary of Detected Compounds
# EPA METHOD TO-15 GC/MS

**Client Sample ID: VMP-47-20-012113**

**Lab ID#: 1301354AR1-01A**

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| 2,2,4-Trimethylpentane | 1300 | 35000 | 5900 | 160000 |
| Butane | 5000 | 500000 | 12000 | 1200000 |
| Isopentane | 5000 | 410000 | 15000 | 1200000 |

**TENTATIVELY IDENTIFIED COMPOUNDS**

| Compound | CAS Number | Match Quality | Amount (ppbv) |
|---|---|---|---|
| Propane, 2-methyl- | | | 150000 NJ |
| Pentane | | | 55000 NJ |
| Pentane, 2-methyl- | | | 160000 NJ |
| Unknown | | | 73000 J |
| Pentane, 2,3-dimethyl- | | | 110000 NJ |

**Client Sample ID: VMP-47-30-012113**

**Lab ID#: 1301354AR1-02A**

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| 2,2,4-Trimethylpentane | 920 | 41000 | 4300 | 190000 |
| Butane | 3700 | 530000 | 8700 | 1300000 |
| Isopentane | 3700 | 360000 | 11000 | 1100000 |

**TENTATIVELY IDENTIFIED COMPOUNDS**

| Compound | CAS Number | Match Quality | Amount (ppbv) |
|---|---|---|---|
| Propane, 2-methyl- | | | 130000 NJ |
| Pentane | | | 46000 NJ |
| Pentane, 2-methyl- | | | 150000 NJ |
| Butane, 2,2,3-trimethyl- | | | 63000 NJ |
| Pentane, 2,3-dimethyl- | | | 97000 NJ |

**Client Sample ID: VMP-1-8.5-012113** * Use these results only. All other data was reported from the 50.1 X dilution analysis.

**Lab ID#: 1301354AR1-03A**

DF = 251

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Hexane | 120 | 410 | 440 | 1400 |

eurofins | Air Toxics

# Summary of Detected Compounds
# EPA METHOD TO-15 GC/MS FULL SCAN

**Client Sample ID: VMP-1-8.5-012113**

**Lab ID#: 1301354AR1-03A**

| | | | | |
|---|---|---|---|---|
| Cyclohexane | 120 | 150 | 430 | 510 |
| 2,2,4-Trimethylpentane | 120 | 1000 | 590 | 4700 |
| Butane | 500 | 24000 | 1200 | 57000 |
| Isopentane | 500 | 12000 | 1500 | 36000 |

**TENTATIVELY IDENTIFIED COMPOUNDS**

| Compound | CAS Number | Match Quality | Amount (ppbv) |
|---|---|---|---|
| Propane, 2-methyl- | | | 3000 NJ |
| Pentane | | | 3900 NJ |
| Butane, 2,3-dimethyl- | | | 2800 NJ |
| Pentane, 2-methyl- | | | 3900 NJ |
| Pentane, 3-methyl- | | | 2500 NJ |

**Client Sample ID: VMP-1-8.5-012113** Do not use this data. Use all other data.

**Lab ID#: 1301354AR1-03B**

DF = 50.1

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Hexane | 25 | 510 | 88 | 1800 |
| Cyclohexane | 25 | 180 | 86 | 620 |
| 2,2,4-Trimethylpentane | 25 | 1200 | 120 | 5700 |
| Heptane | 25 | 29 | 100 | 120 |
| ~~Butane~~ | ~~100~~ | ~~28000 E~~ | ~~240~~ | ~~67000 E~~ |
| ~~Isopentane~~ | ~~100~~ | ~~14000 E~~ | ~~300~~ | ~~41000 E~~ |

**TENTATIVELY IDENTIFIED COMPOUNDS**

| Compound | CAS Number | Match Quality | Amount (ppbv) |
|---|---|---|---|
| Propane, 2-methyl- | | | 3800 NJ |
| Pentane | | | 4600 NJ |
| Butane, 2,3-dimethyl- | | | 3300 NJ |
| Pentane, 2-methyl- | | | 4400 NJ |
| Pentane, 3-methyl- | | | 3000 NJ |

**Client Sample ID: VMP-1-23.5-012113**

**Lab ID#: 1301354AR1-04A**

eurofins | Air Toxics

# Summary of Detected Compounds
# EPA METHOD TO-15 GC/MS FULL SCAN

**Client Sample ID: VMP-1-23.5-012113**

**Lab ID#: 130I354AR1-04A**

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Hexane | 13 | 280 J | 47 | 1000 J |
| Cyclohexane | 13 | 180 J | 46 | 640 J |
| 2,2,4-Trimethylpentane | 13 | 900 J | 63 | 4200 J |
| Benzene | 13 | 2.8 J J | 43 | 8.8 J J |
| Heptane | 13 | 34 J | 55 | 140 J |
| Butane | 54 | 5100 J | 130 | 12000 J |
| Isopentane | 54 | 4700 J | 160 | 14000 J |

**TENTATIVELY IDENTIFIED COMPOUNDS**

| Compound | CAS Number | Match Quality | Amount (ppbv) |
|---|---|---|---|
| Propane, 2-methyl- | | | 1500 NJ |
| Pentane | | | 1500 NJ |
| Butane, 2,3-dimethyl- | | | 1700 NJ |
| Pentane, 2-methyl- | | | 2100 NJ |
| Pentane, 3-methyl- | | | 1600 NJ |

eurofins | Air Toxics

**Client Sample ID: VMP-47-20-012113**
**Lab ID#: 1301354AR1-01A**
**EPA METHOD TO-15 GC/MS**

| | | | |
|---|---|---|---|
| File Name: | 14012238r1 | Date of Collection: | 1/21/13 2:47:00 PM |
| Dil. Factor: | 252 | Date of Analysis: | 1/23/13 08:10 AM |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 1300 | Not Detected | 6200 | Not Detected |
| Freon 114 | 1300 | Not Detected | 8800 | Not Detected |
| Chloromethane | 5000 | Not Detected | 10000 | Not Detected |
| Vinyl Chloride | 1300 | Not Detected | 3200 | Not Detected |
| 1,3-Butadiene | 1300 | Not Detected | 2800 | Not Detected |
| Bromomethane | 1300 | Not Detected | 4900 | Not Detected |
| Chloroethane | 5000 | Not Detected | 13000 | Not Detected |
| Freon 11 | 1300 | Not Detected | 7100 | Not Detected |
| Ethanol | 5000 | Not Detected | 9500 | Not Detected |
| Freon 113 | 1300 | Not Detected | 9600 | Not Detected |
| 1,1-Dichloroethene | 1300 | Not Detected | 5000 | Not Detected |
| Acetone | 5000 | Not Detected | 12000 | Not Detected |
| 2-Propanol | 5000 | Not Detected | 12000 | Not Detected |
| Carbon Disulfide | 1300 | Not Detected | 3900 | Not Detected |
| 3-Chloropropene | 5000 | Not Detected | 16000 | Not Detected |
| Methylene Chloride | 1300 | Not Detected | 4400 | Not Detected |
| Methyl tert-butyl ether | 1300 | Not Detected | 4500 | Not Detected |
| trans-1,2-Dichloroethene | 1300 | Not Detected | 5000 | Not Detected |
| Hexane | 1300 | Not Detected | 4400 | Not Detected |
| 1,1-Dichloroethane | 1300 | Not Detected | 5100 | Not Detected |
| 2-Butanone (Methyl Ethyl Ketone) | 5000 | Not Detected | 15000 | Not Detected |
| cis-1,2-Dichloroethene | 1300 | Not Detected | 5000 | Not Detected |
| Tetrahydrofuran | 1300 | Not Detected | 3700 | Not Detected |
| Chloroform | 1300 | Not Detected | 6200 | Not Detected |
| 1,1,1-Trichloroethane | 1300 | Not Detected | 6900 | Not Detected |
| Cyclohexane | 1300 | Not Detected | 4300 | Not Detected |
| Carbon Tetrachloride | 1300 | Not Detected | 7900 | Not Detected |
| 2,2,4-Trimethylpentane | 1300 | 35000 | 5900 | 160000 |
| Benzene | 1300 | Not Detected | 4000 | Not Detected |
| 1,2-Dichloroethane | 1300 | Not Detected | 5100 | Not Detected |
| Heptane | 1300 | Not Detected | 5200 | Not Detected |
| Trichloroethene | 1300 | Not Detected | 6800 | Not Detected |
| 1,2-Dichloropropane | 1300 | Not Detected | 5800 | Not Detected |
| 1,4-Dioxane | 5000 | Not Detected | 18000 | Not Detected |
| Bromodichloromethane | 1300 | Not Detected | 8400 | Not Detected |
| cis-1,3-Dichloropropene | 1300 | Not Detected | 5700 | Not Detected |
| 4-Methyl-2-pentanone | 1300 | Not Detected | 5200 | Not Detected |
| Toluene | 1300 | Not Detected | 4700 | Not Detected |
| trans-1,3-Dichloropropene | 1300 | Not Detected | 5700 | Not Detected |
| 1,1,2-Trichloroethane | 1300 | Not Detected | 6900 | Not Detected |
| Tetrachloroethene | 1300 | Not Detected | 8500 | Not Detected |
| 2-Hexanone | 5000 | Not Detected | 21000 | Not Detected |

**Client Sample ID: VMP-47-20-012113**

**Lab ID#: 1301354AR1-01A**

**EPA METHOD TO-15 GC/MS**

| | | | |
|---|---|---|---|
| **File Name:** | **14012238r1** | **Date of Collection:** | **1/21/13 2:47:00 PM** |
| **Dil. Factor:** | **252** | **Date of Analysis:** | **1/23/13 08:10 AM** |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Dibromochloromethane | 1300 | Not Detected | 11000 | Not Detected |
| 1,2-Dibromoethane (EDB) | 1300 | Not Detected | 9700 | Not Detected |
| Chlorobenzene | 1300 | Not Detected | 5800 | Not Detected |
| Ethyl Benzene | 1300 | Not Detected | 5500 | Not Detected |
| m,p-Xylene | 1300 | Not Detected | 5500 | Not Detected |
| o-Xylene | 1300 | Not Detected | 5500 | Not Detected |
| Styrene | 1300 | Not Detected | 5400 | Not Detected |
| Bromoform | 1300 | Not Detected | 13000 | Not Detected |
| Cumene | 1300 | Not Detected | 6200 | Not Detected |
| 1,1,2,2-Tetrachloroethane | 1300 | Not Detected | 8600 | Not Detected |
| Propylbenzene | 1300 | Not Detected | 6200 | Not Detected |
| 4-Ethyltoluene | 1300 | Not Detected | 6200 | Not Detected |
| 1,3,5-Trimethylbenzene | 1300 | Not Detected | 6200 | Not Detected |
| 1,2,4-Trimethylbenzene | 1300 | Not Detected | 6200 | Not Detected |
| 1,3-Dichlorobenzene | 1300 | Not Detected | 7600 | Not Detected |
| 1,4-Dichlorobenzene | 1300 | Not Detected | 7600 | Not Detected |
| alpha-Chlorotoluene | 1300 | Not Detected | 6500 | Not Detected |
| 1,2-Dichlorobenzene | 1300 | Not Detected | 7600 | Not Detected |
| 1,2,4-Trichlorobenzene | 5000 | Not Detected | 37000 | Not Detected |
| Hexachlorobutadiene | 5000 | Not Detected | 54000 | Not Detected |
| Butane | 5000 | 500000 | 12000 | 1200000 |
| Isopentane | 5000 | 410000 | 15000 | 1200000 |

**TENTATIVELY IDENTIFIED COMPOUNDS**

| Compound | CAS Number | Match Quality | Amount ((ppbv)) |
|---|---|---|---|
| Propane, 2-methyl- | | | 350000 NJ |
| Pentane | | | 160000 NJ |
| Pentane, 2-methyl- | | | 570000 NJ |
| Unknown | | | 0 J |
| Pentane, 2,3-dimethyl- | | | 440000 NJ |

NJ =The identification is based on presumptive evidence; estimated value.

**Container Type: 1 Liter Summa Canister**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| 1,2-Dichloroethane-d4 | 105 | 70-130 |
| Toluene-d8 | 97 | 70-130 |
| 4-Bromofluorobenzene | 98 | 70-130 |

**Client Sample ID: VMP-47-30-012113**
**Lab ID#: 1301354AR1-02A**
**EPA METHOD TO-15 GC/MS**

| | | | |
|---|---|---|---|
| **File Name:** | **14012239r1** | **Date of Collection:** | **1/21/13 3:45:00 PM** |
| **Dil. Factor:** | **184** | **Date of Analysis:** | **1/23/13 08:53 AM** |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 920 | Not Detected | 4500 | Not Detected |
| Freon 114 | 920 | Not Detected | 6400 | Not Detected |
| Chloromethane | 3700 | Not Detected | 7600 | Not Detected |
| Vinyl Chloride | 920 | Not Detected | 2400 | Not Detected |
| 1,3-Butadiene | 920 | Not Detected | 2000 | Not Detected |
| Bromomethane | 920 | Not Detected | 3600 | Not Detected |
| Chloroethane | 3700 | Not Detected | 9700 | Not Detected |
| Freon 11 | 920 | Not Detected | 5200 | Not Detected |
| Ethanol | 3700 | Not Detected | 6900 | Not Detected |
| Freon 113 | 920 | Not Detected | 7000 | Not Detected |
| 1,1-Dichloroethene | 920 | Not Detected | 3600 | Not Detected |
| Acetone | 3700 | Not Detected | 8700 | Not Detected |
| 2-Propanol | 3700 | Not Detected | 9000 | Not Detected |
| Carbon Disulfide | 920 | Not Detected | 2900 | Not Detected |
| 3-Chloropropene | 3700 | Not Detected | 12000 | Not Detected |
| Methylene Chloride | 920 | Not Detected | 3200 | Not Detected |
| Methyl tert-butyl ether | 920 | Not Detected | 3300 | Not Detected |
| trans-1,2-Dichloroethene | 920 | Not Detected | 3600 | Not Detected |
| Hexane | 920 | Not Detected | 3200 | Not Detected |
| 1,1-Dichloroethane | 920 | Not Detected | 3700 | Not Detected |
| 2-Butanone (Methyl Ethyl Ketone) | 3700 | Not Detected | 11000 | Not Detected |
| cis-1,2-Dichloroethene | 920 | Not Detected | 3600 | Not Detected |
| Tetrahydrofuran | 920 | Not Detected | 2700 | Not Detected |
| Chloroform | 920 | Not Detected | 4500 | Not Detected |
| 1,1,1-Trichloroethane | 920 | Not Detected | 5000 | Not Detected |
| Cyclohexane | 920 | Not Detected | 3200 | Not Detected |
| Carbon Tetrachloride | 920 | Not Detected | 5800 | Not Detected |
| 2,2,4-Trimethylpentane | 920 | 41000 | 4300 | 190000 |
| Benzene | 920 | Not Detected | 2900 | Not Detected |
| 1,2-Dichloroethane | 920 | Not Detected | 3700 | Not Detected |
| Heptane | 920 | Not Detected | 3800 | Not Detected |
| Trichloroethene | 920 | Not Detected | 4900 | Not Detected |
| 1,2-Dichloropropane | 920 | Not Detected | 4200 | Not Detected |
| 1,4-Dioxane | 3700 | Not Detected | 13000 | Not Detected |
| Bromodichloromethane | 920 | Not Detected | 6200 | Not Detected |
| cis-1,3-Dichloropropene | 920 | Not Detected | 4200 | Not Detected |
| 4-Methyl-2-pentanone | 920 | Not Detected | 3800 | Not Detected |
| Toluene | 920 | Not Detected | 3500 | Not Detected |
| trans-1,3-Dichloropropene | 920 | Not Detected | 4200 | Not Detected |
| 1,1,2-Trichloroethane | 920 | Not Detected | 5000 | Not Detected |
| Tetrachloroethene | 920 | Not Detected | 6200 | Not Detected |
| 2-Hexanone | 3700 | Not Detected | 15000 | Not Detected |

**Client Sample ID: VMP-47-30-012113**
**Lab ID#: 1301354AR1-02A**
**EPA METHOD TO-15 GC/MS**

| | | | |
|---|---|---|---|
| File Name: | 14012239r1 | Date of Collection: | 1/21/13 3:45:00 PM |
| Dil. Factor: | 184 | Date of Analysis: | 1/23/13 08:53 AM |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Dibromochloromethane | 920 | Not Detected | 7800 | Not Detected |
| 1,2-Dibromoethane (EDB) | 920 | Not Detected | 7100 | Not Detected |
| Chlorobenzene | 920 | Not Detected | 4200 | Not Detected |
| Ethyl Benzene | 920 | Not Detected | 4000 | Not Detected |
| m,p-Xylene | 920 | Not Detected | 4000 | Not Detected |
| o-Xylene | 920 | Not Detected | 4000 | Not Detected |
| Styrene | 920 | Not Detected | 3900 | Not Detected |
| Bromoform | 920 | Not Detected | 9500 | Not Detected |
| Cumene | 920 | Not Detected | 4500 | Not Detected |
| 1,1,2,2-Tetrachloroethane | 920 | Not Detected | 6300 | Not Detected |
| Propylbenzene | 920 | Not Detected | 4500 | Not Detected |
| 4-Ethyltoluene | 920 | Not Detected | 4500 | Not Detected |
| 1,3,5-Trimethylbenzene | 920 | Not Detected | 4500 | Not Detected |
| 1,2,4-Trimethylbenzene | 920 | Not Detected | 4500 | Not Detected |
| 1,3-Dichlorobenzene | 920 | Not Detected | 5500 | Not Detected |
| 1,4-Dichlorobenzene | 920 | Not Detected | 5500 | Not Detected |
| alpha-Chlorotoluene | 920 | Not Detected | 4800 | Not Detected |
| 1,2-Dichlorobenzene | 920 | Not Detected | 5500 | Not Detected |
| 1,2,4-Trichlorobenzene | 3700 | Not Detected | 27000 | Not Detected |
| Hexachlorobutadiene | 3700 | Not Detected | 39000 | Not Detected |
| Butane | 3700 | 530000 | 8700 | 1300000 |
| Isopentane | 3700 | 360000 | 11000 | 1100000 |

**TENTATIVELY IDENTIFIED COMPOUNDS**

| Compound | CAS Number | Match Quality | Amount ((ppbv)) |
|---|---|---|---|
| Propane, 2-methyl- | | | 300000 NJ |
| Pentane | | | 140000 NJ |
| Pentane, 2-methyl- | | | 520000 NJ |
| Butane, 2,2,3-trimethyl- | | | 0 NJ |
| Pentane, 2,3-dimethyl- | | | 400000 NJ |

NJ =The identification is based on presumptive evidence; estimated value.

**Container Type: 1 Liter Summa Canister**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| 1,2-Dichloroethane-d4 | 109 | 70-130 |
| Toluene-d8 | 98 | 70-130 |
| 4-Bromofluorobenzene | 99 | 70-130 |

eurofins | Air Toxics

**Client Sample ID: VMP-1-8.5-012113** * Use these results only - All other data was reported from the 50-1X dilution analysis.
**Lab ID#: 1301354AR1-03A**
**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **2012212r1** | **Date of Collection: 1/21/13 1:06:00 PM** | |
| **Dil. Factor:** | **251** | **Date of Analysis: 1/22/13 07:46 PM** | |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 120 | Not Detected | 620 | Not Detected |
| Freon 114 | 120 | Not Detected | 880 | Not Detected |
| Chloromethane | 1200 | Not Detected | 2600 | Not Detected |
| Vinyl Chloride | 120 | Not Detected | 320 | Not Detected |
| 1,3-Butadiene | 120 | Not Detected | 280 | Not Detected |
| Bromomethane | 1200 | Not Detected | 4900 | Not Detected |
| Chloroethane | 500 | Not Detected | 1300 | Not Detected |
| Freon 11 | 120 | Not Detected | 700 | Not Detected |
| Ethanol | 500 | Not Detected | 940 | Not Detected |
| Freon 113 | 120 | Not Detected | 960 | Not Detected |
| 1,1-Dichloroethene | 120 | Not Detected | 500 | Not Detected |
| Acetone | 1200 | Not Detected | 3000 | Not Detected |
| 2-Propanol | 500 | Not Detected | 1200 | Not Detected |
| Carbon Disulfide | 500 | Not Detected | 1600 | Not Detected |
| 3-Chloropropene | 500 | Not Detected | 1600 | Not Detected |
| Methylene Chloride | 1200 | Not Detected | 4400 | Not Detected |
| Methyl tert-butyl ether | 120 | Not Detected | 450 | Not Detected |
| trans-1,2-Dichloroethene | 120 | Not Detected | 500 | Not Detected |
| Hexane | 120 | 410 | 440 | 1400 |
| 1,1-Dichloroethane | 120 | Not Detected | 510 | Not Detected |
| 2-Butanone (Methyl Ethyl Ketone) | 500 | Not Detected | 1500 | Not Detected |
| cis-1,2-Dichloroethene | 120 | Not Detected | 500 | Not Detected |
| Tetrahydrofuran | 120 | Not Detected | 370 | Not Detected |
| Chloroform | 120 | Not Detected | 610 | Not Detected |
| 1,1,1-Trichloroethane | 120 | Not Detected | 680 | Not Detected |
| Cyclohexane | 120 | 150 | 430 | 510 |
| Carbon Tetrachloride | 120 | Not Detected | 790 | Not Detected |
| 2,2,4-Trimethylpentane | 120 | 1000 | 590 | 4700 |
| Benzene | 120 | Not Detected | 400 | Not Detected |
| 1,2-Dichloroethane | 120 | Not Detected | 510 | Not Detected |
| Heptane | 120 | Not Detected | 510 | Not Detected |
| Trichloroethene | 120 | Not Detected | 670 | Not Detected |
| 1,2-Dichloropropane | 120 | Not Detected | 580 | Not Detected |
| 1,4-Dioxane | 500 | Not Detected | 1800 | Not Detected |
| Bromodichloromethane | 120 | Not Detected | 840 | Not Detected |
| cis-1,3-Dichloropropene | 120 | Not Detected | 570 | Not Detected |
| 4-Methyl-2-pentanone | 120 | Not Detected | 510 | Not Detected |
| Toluene | 120 | Not Detected | 470 | Not Detected |
| trans-1,3-Dichloropropene | 120 | Not Detected | 570 | Not Detected |
| 1,1,2-Trichloroethane | 120 | Not Detected | 680 | Not Detected |
| Tetrachloroethene | 120 | Not Detected | 850 | Not Detected |
| 2-Hexanone | 500 | Not Detected | 2000 | Not Detected |

**Client Sample ID: VMP-1-8.5-012113**

**Lab ID#: 1301354AR1-03A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **2012212r1** | **Date of Collection:** | **1/21/13 1:06:00 PM** |
| **Dil. Factor:** | **251** | **Date of Analysis:** | **1/22/13 07:46 PM** |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Dibromochloromethane | 120 | Not Detected | 1100 | Not Detected |
| 1,2-Dibromoethane (EDB) | 120 | Not Detected | 960 | Not Detected |
| Chlorobenzene | 120 | Not Detected | 580 | Not Detected |
| Ethyl Benzene | 120 | Not Detected | 540 | Not Detected |
| m,p-Xylene | 120 | Not Detected | 540 | Not Detected |
| o-Xylene | 120 | Not Detected | 540 | Not Detected |
| Styrene | 120 | Not Detected | 530 | Not Detected |
| Bromoform | 120 | Not Detected | 1300 | Not Detected |
| Cumene | 120 | Not Detected | 620 | Not Detected |
| 1,1,2,2-Tetrachloroethane | 120 | Not Detected | 860 | Not Detected |
| Propylbenzene | 120 | Not Detected | 620 | Not Detected |
| 4-Ethyltoluene | 120 | Not Detected | 620 | Not Detected |
| 1,3,5-Trimethylbenzene | 120 | Not Detected | 620 | Not Detected |
| 1,2,4-Trimethylbenzene | 120 | Not Detected | 620 | Not Detected |
| 1,3-Dichlorobenzene | 120 | Not Detected | 750 | Not Detected |
| 1,4-Dichlorobenzene | 120 | Not Detected | 750 | Not Detected |
| alpha-Chlorotoluene | 120 | Not Detected | 650 | Not Detected |
| 1,2-Dichlorobenzene | 120 | Not Detected | 750 | Not Detected |
| 1,2,4-Trichlorobenzene | 500 | Not Detected UJ | 3700 | Not Detected UJ |
| Hexachlorobutadiene | 500 | Not Detected | 5400 | Not Detected |
| Butane | 500 | 24000 | 1200 | 57000 |
| Isopentane | 500 | 12000 | 1500 | 36000 |

UJ = Non-detected compound associated with low bias in the CCV and/or LCS.

**TENTATIVELY IDENTIFIED COMPOUNDS**

| Compound | CAS Number | Match Quality | Amount ((ppbv)) |
|---|---|---|---|
| Propane, 2-methyl- | | | 7000 NJ |
| Pentane | | | 12000 NJ |
| Butane, 2,3-dimethyl- | | | 9900 NJ |
| Pentane, 2-methyl- | | | 14000 NJ |
| Pentane, 3-methyl- | | | 9000 NJ |

NJ =The identification is based on presumptive evidence; estimated value.

**Container Type: 1 Liter Summa Canister**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| Toluene-d8 | 96 | 70-130 |
| 1,2-Dichloroethane-d4 | 100 | 70-130 |
| 4-Bromofluorobenzene | 94 | 70-130 |

eurofins | Air Toxics

**Client Sample ID: VMP-1-8.5-012113** ** Do not use this
**Lab ID#: 1301354AR1-03B** data. Use all other
**EPA METHOD TO-15 GC/MS FULL SCAN** data.

| | | | |
|---|---|---|---|
| **File Name:** | **2012210r1** | **Date of Collection:** | **1/21/13 1:06:00 PM** |
| **Dil. Factor:** | **50.1** | **Date of Analysis:** | **1/22/13 05:25 PM** |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 25 | Not Detected | 120 | Not Detected |
| Freon 114 | 25 | Not Detected | 180 | Not Detected |
| Chloromethane | 250 | Not Detected | 520 | Not Detected |
| Vinyl Chloride | 25 | Not Detected | 64 | Not Detected |
| 1,3-Butadiene | 25 | Not Detected | 55 | Not Detected |
| Bromomethane | 250 | Not Detected | 970 | Not Detected |
| Chloroethane | 100 | Not Detected | 260 | Not Detected |
| Freon 11 | 25 | Not Detected UJ | 140 | Not Detected UJ |
| Ethanol | 100 | Not Detected | 190 | Not Detected |
| Freon 113 | 25 | Not Detected | 190 | Not Detected |
| 1,1-Dichloroethene | 25 | Not Detected | 99 | Not Detected |
| Acetone | 250 | Not Detected | 600 | Not Detected |
| 2-Propanol | 100 | Not Detected | 250 | Not Detected |
| Carbon Disulfide | 100 | Not Detected | 310 | Not Detected |
| 3-Chloropropene | 100 | Not Detected | 310 | Not Detected |
| Methylene Chloride | 250 | Not Detected | 870 | Not Detected |
| Methyl tert-butyl ether | 25 | Not Detected | 90 | Not Detected |
| trans-1,2-Dichloroethene | 25 | Not Detected | 99 | Not Detected |
| Hexane | 25 | 510 | 88 | 1800 |
| 1,1-Dichloroethane | 25 | Not Detected | 100 | Not Detected |
| 2-Butanone (Methyl Ethyl Ketone) | 100 | Not Detected | 300 | Not Detected |
| cis-1,2-Dichloroethene | 25 | Not Detected | 99 | Not Detected |
| Tetrahydrofuran | 25 | Not Detected | 74 | Not Detected |
| Chloroform | 25 | Not Detected | 120 | Not Detected |
| 1,1,1-Trichloroethane | 25 | Not Detected | 140 | Not Detected |
| Cyclohexane | 25 | 180 | 86 | 620 |
| Carbon Tetrachloride | 25 | Not Detected | 160 | Not Detected |
| 2,2,4-Trimethylpentane | 25 | 1200 | 120 | 5700 |
| Benzene | 25 | Not Detected | 80 | Not Detected |
| 1,2-Dichloroethane | 25 | Not Detected | 100 | Not Detected |
| Heptane | 25 | 29 | 100 | 120 |
| Trichloroethene | 25 | Not Detected | 130 | Not Detected |
| 1,2-Dichloropropane | 25 | Not Detected | 120 | Not Detected |
| 1,4-Dioxane | 100 | Not Detected | 360 | Not Detected |
| Bromodichloromethane | 25 | Not Detected | 170 | Not Detected |
| cis-1,3-Dichloropropene | 25 | Not Detected | 110 | Not Detected |
| 4-Methyl-2-pentanone | 25 | Not Detected | 100 | Not Detected |
| Toluene | 25 | Not Detected | 94 | Not Detected |
| trans-1,3-Dichloropropene | 25 | Not Detected | 110 | Not Detected |
| 1,1,2-Trichloroethane | 25 | Not Detected | 140 | Not Detected |
| Tetrachloroethene | 25 | Not Detected | 170 | Not Detected |
| 2-Hexanone | 100 | Not Detected | 410 | Not Detected |

eurofins | Air Toxics

**Client Sample ID: VMP-1-8.5-012113**

**Lab ID#: 1301354AR1-03B**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **2012210r1** | **Date of Collection:** | **1/21/13 1:06:00 PM** |
| **Dil. Factor:** | **50.1** | **Date of Analysis:** | **1/22/13 05:25 PM** |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Dibromochloromethane | 25 | Not Detected | 210 | Not Detected |
| 1,2-Dibromoethane (EDB) | 25 | Not Detected | 190 | Not Detected |
| Chlorobenzene | 25 | Not Detected | 120 | Not Detected |
| Ethyl Benzene | 25 | Not Detected | 110 | Not Detected |
| m,p-Xylene | 25 | Not Detected | 110 | Not Detected |
| o-Xylene | 25 | Not Detected | 110 | Not Detected |
| Styrene | 25 | Not Detected | 110 | Not Detected |
| Bromoform | 25 | Not Detected | 260 | Not Detected |
| Cumene | 25 | Not Detected | 120 | Not Detected |
| 1,1,2,2-Tetrachloroethane | 25 | Not Detected | 170 | Not Detected |
| Propylbenzene | 25 | Not Detected | 120 | Not Detected |
| 4-Ethyltoluene | 25 | Not Detected | 120 | Not Detected |
| 1,3,5-Trimethylbenzene | 25 | Not Detected | 120 | Not Detected |
| 1,2,4-Trimethylbenzene | 25 | Not Detected | 120 | Not Detected |
| 1,3-Dichlorobenzene | 25 | Not Detected | 150 | Not Detected |
| 1,4-Dichlorobenzene | 25 | Not Detected | 150 | Not Detected |
| alpha-Chlorotoluene | 25 | Not Detected | 130 | Not Detected |
| 1,2-Dichlorobenzene | 25 | Not Detected | 150 | Not Detected |
| 1,2,4-Trichlorobenzene | 100 | Not Detected UJ UJ | 740 | Not Detected UJ UJ |
| Hexachlorobutadiene | 100 | Not Detected | 1100 | Not Detected |
| ~~Butane~~ | ~~100~~ | ~~28000 E~~ | ~~240~~ | ~~67000 E~~ |
| ~~Isopentane~~ | ~~100~~ | ~~14000 E~~ | ~~300~~ | ~~41000 E~~ |

UJ = Non-detected compound associated with low bias in the CCV and/or LCS.
E = Exceeds instrument calibration range.

**TENTATIVELY IDENTIFIED COMPOUNDS**

| Compound | CAS Number | Match Quality | Amount ((ppbv)) |
|---|---|---|---|
| Propane, 2-methyl- | | | 8900 NJ |
| Pentane | | | 14000 NJ |
| Butane, 2,3-dimethyl- | | | 12000 NJ |
| Pentane, 2-methyl- | | | 16000 NJ |
| Pentane, 3-methyl- | | | 10000 NJ |

NJ =The identification is based on presumptive evidence; estimated value.

**Container Type: 1 Liter Summa Canister**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| Toluene-d8 | 96 | 70-130 |
| 1,2-Dichloroethane-d4 | 96 | 70-130 |
| 4-Bromofluorobenzene | 96 | 70-130 |

eurofins | Air Toxics

**Client Sample ID: VMP-1-23.5-012113**
**Lab ID#: I30I354AR1-04A**
**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **2012213r1** | **Date of Collection:** | **1/21/13 2:28:00 PM** |
| **Dil. Factor:** | **26.9** | **Date of Analysis:** | **1/22/13 08:54 PM** |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 13 | Not Detected | 66 | Not Detected |
| Freon 114 | 13 | Not Detected | 94 | Not Detected |
| Chloromethane | 130 | Not Detected | 280 | Not Detected |
| Vinyl Chloride | 13 | Not Detected | 34 | Not Detected |
| 1,3-Butadiene | 13 | Not Detected | 30 | Not Detected |
| Bromomethane | 130 | Not Detected | 520 | Not Detected |
| Chloroethane | 54 | Not Detected | 140 | Not Detected |
| Freon 11 | 13 | Not Detected | 76 | Not Detected |
| Ethanol | 54 | Not Detected | 100 | Not Detected |
| Freon 113 | 13 | Not Detected | 100 | Not Detected |
| 1,1-Dichloroethene | 13 | Not Detected | 53 | Not Detected |
| Acetone | 130 | Not Detected | 320 | Not Detected |
| 2-Propanol | 54 | Not Detected | 130 | Not Detected |
| Carbon Disulfide | 54 | Not Detected | 170 | Not Detected |
| 3-Chloropropene | 54 | Not Detected | 170 | Not Detected |
| Methylene Chloride | 130 | Not Detected | 470 | Not Detected |
| Methyl tert-butyl ether | 13 | Not Detected | 48 | Not Detected |
| trans-1,2-Dichloroethene | 13 | Not Detected | 53 | Not Detected |
| Hexane | 13 | 280 | 47 | 1000 |
| 1,1-Dichloroethane | 13 | Not Detected | 54 | Not Detected |
| 2-Butanone (Methyl Ethyl Ketone) | 54 | Not Detected | 160 | Not Detected |
| cis-1,2-Dichloroethene | 13 | Not Detected | 53 | Not Detected |
| Tetrahydrofuran | 13 | Not Detected | 40 | Not Detected |
| Chloroform | 13 | Not Detected | 66 | Not Detected |
| 1,1,1-Trichloroethane | 13 | Not Detected | 73 | Not Detected |
| Cyclohexane | 13 | 180 | 46 | 640 |
| Carbon Tetrachloride | 13 | Not Detected | 85 | Not Detected |
| 2,2,4-Trimethylpentane | 13 | 900 | 63 | 4200 |
| Benzene | 13 | 2.8 J | 43 | 8.8 J |
| 1,2-Dichloroethane | 13 | Not Detected | 54 | Not Detected |
| Heptane | 13 | 34 | 55 | 140 |
| Trichloroethene | 13 | Not Detected | 72 | Not Detected |
| 1,2-Dichloropropane | 13 | Not Detected | 62 | Not Detected |
| 1,4-Dioxane | 54 | Not Detected | 190 | Not Detected |
| Bromodichloromethane | 13 | Not Detected | 90 | Not Detected |
| cis-1,3-Dichloropropene | 13 | Not Detected | 61 | Not Detected |
| 4-Methyl-2-pentanone | 13 | Not Detected | 55 | Not Detected |
| Toluene | 13 | Not Detected | 51 | Not Detected |
| trans-1,3-Dichloropropene | 13 | Not Detected | 61 | Not Detected |
| 1,1,2-Trichloroethane | 13 | Not Detected | 73 | Not Detected |
| Tetrachloroethene | 13 | Not Detected | 91 | Not Detected |
| 2-Hexanone | 54 | Not Detected | 220 | Not Detected |

eurofins | Air Toxics

**Client Sample ID: VMP-1-23.5-012113**
**Lab ID#: 1301354AR1-04A**
**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **2012213r1** | **Date of Collection:** | **1/21/13 2:28:00 PM** |
| **Dil. Factor:** | **26.9** | **Date of Analysis:** | **1/22/13 08:54 PM** |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Dibromochloromethane | 13 | Not Detected | 110 | Not Detected |
| 1,2-Dibromoethane (EDB) | 13 | Not Detected | 100 | Not Detected |
| Chlorobenzene | 13 | Not Detected | 62 | Not Detected |
| Ethyl Benzene | 13 | Not Detected | 58 | Not Detected |
| m,p-Xylene | 13 | Not Detected | 58 | Not Detected |
| o-Xylene | 13 | Not Detected | 58 | Not Detected |
| Styrene | 13 | Not Detected | 57 | Not Detected |
| Bromoform | 13 | Not Detected | 140 | Not Detected |
| Cumene | 13 | Not Detected | 66 | Not Detected |
| 1,1,2,2-Tetrachloroethane | 13 | Not Detected | 92 | Not Detected |
| Propylbenzene | 13 | Not Detected | 66 | Not Detected |
| 4-Ethyltoluene | 13 | Not Detected | 66 | Not Detected |
| 1,3,5-Trimethylbenzene | 13 | Not Detected | 66 | Not Detected |
| 1,2,4-Trimethylbenzene | 13 | Not Detected | 66 | Not Detected |
| 1,3-Dichlorobenzene | 13 | Not Detected | 81 | Not Detected |
| 1,4-Dichlorobenzene | 13 | Not Detected | 81 | Not Detected |
| alpha-Chlorotoluene | 13 | Not Detected | 70 | Not Detected |
| 1,2-Dichlorobenzene | 13 | Not Detected | 81 | Not Detected |
| 1,2,4-Trichlorobenzene | 54 | Not Detected UJ | 400 | Not Detected UJ |
| Hexachlorobutadiene | 54 | Not Detected | 570 | Not Detected |
| Butane | 54 | 5100 | 130 | 12000 |
| Isopentane | 54 | 4700 | 160 | 14000 |

J = Estimated value.
UJ = Non-detected compound associated with low bias in the CCV and/or LCS.

**TENTATIVELY IDENTIFIED COMPOUNDS**

| Compound | CAS Number | Match Quality | Amount ((ppbv)) |
|---|---|---|---|
| Propane, 2-methyl- | | | 3600 NJ |
| Pentane | | | 4500 NJ |
| Butane, 2,3-dimethyl- | | | 6100 NJ |
| Pentane, 2-methyl- | | | 7400 NJ |
| Pentane, 3-methyl- | | | 5800 NJ |

NJ =The identification is based on presumptive evidence; estimated value.

**Container Type: 1 Liter Summa Canister**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| Toluene-d8 | 96 | 70-130 |
| 1,2-Dichloroethane-d4 | 98 | 70-130 |
| 4-Bromofluorobenzene | 96 | 70-130 |

eurofins | Air Toxics

**Client Sample ID: Lab Blank**

**Lab ID#: I301354AR1-05A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **2012207d** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 1/22/13 01:56 PM** | |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 0.50 | Not Detected | 2.5 | Not Detected |
| Freon 114 | 0.50 | Not Detected | 3.5 | Not Detected |
| Chloromethane | 5.0 | Not Detected | 10 | Not Detected |
| Vinyl Chloride | 0.50 | Not Detected | 1.3 | Not Detected |
| 1,3-Butadiene | 0.50 | Not Detected | 1.1 | Not Detected |
| Bromomethane | 5.0 | Not Detected | 19 | Not Detected |
| Chloroethane | 2.0 | Not Detected | 5.3 | Not Detected |
| Freon 11 | 0.50 | Not Detected | 2.8 | Not Detected |
| Ethanol | 2.0 | Not Detected | 3.8 | Not Detected |
| Freon 113 | 0.50 | Not Detected | 3.8 | Not Detected |
| 1,1-Dichloroethene | 0.50 | Not Detected | 2.0 | Not Detected |
| Acetone | 5.0 | 0.67 J | 12 | 1.6 J |
| 2-Propanol | 2.0 | Not Detected | 4.9 | Not Detected |
| Carbon Disulfide | 2.0 | Not Detected | 6.2 | Not Detected |
| 3-Chloropropene | 2.0 | Not Detected | 6.3 | Not Detected |
| Methylene Chloride | 5.0 | Not Detected | 17 | Not Detected |
| Methyl tert-butyl ether | 0.50 | Not Detected | 1.8 | Not Detected |
| trans-1,2-Dichloroethene | 0.50 | Not Detected | 2.0 | Not Detected |
| Hexane | 0.50 | Not Detected | 1.8 | Not Detected |
| 1,1-Dichloroethane | 0.50 | Not Detected | 2.0 | Not Detected |
| 2-Butanone (Methyl Ethyl Ketone) | 2.0 | Not Detected | 5.9 | Not Detected |
| cis-1,2-Dichloroethene | 0.50 | Not Detected | 2.0 | Not Detected |
| Tetrahydrofuran | 0.50 | Not Detected | 1.5 | Not Detected |
| Chloroform | 0.50 | Not Detected | 2.4 | Not Detected |
| 1,1,1-Trichloroethane | 0.50 | Not Detected | 2.7 | Not Detected |
| Cyclohexane | 0.50 | Not Detected | 1.7 | Not Detected |
| Carbon Tetrachloride | 0.50 | Not Detected | 3.1 | Not Detected |
| 2,2,4-Trimethylpentane | 0.50 | Not Detected | 2.3 | Not Detected |
| Benzene | 0.50 | Not Detected | 1.6 | Not Detected |
| 1,2-Dichloroethane | 0.50 | Not Detected | 2.0 | Not Detected |
| Heptane | 0.50 | Not Detected | 2.0 | Not Detected |
| Trichloroethene | 0.50 | Not Detected | 2.7 | Not Detected |
| 1,2-Dichloropropane | 0.50 | Not Detected | 2.3 | Not Detected |
| 1,4-Dioxane | 2.0 | Not Detected | 7.2 | Not Detected |
| Bromodichloromethane | 0.50 | Not Detected | 3.4 | Not Detected |
| cis-1,3-Dichloropropene | 0.50 | Not Detected | 2.3 | Not Detected |
| 4-Methyl-2-pentanone | 0.50 | Not Detected | 2.0 | Not Detected |
| Toluene | 0.50 | Not Detected | 1.9 | Not Detected |
| trans-1,3-Dichloropropene | 0.50 | Not Detected | 2.3 | Not Detected |
| 1,1,2-Trichloroethane | 0.50 | Not Detected | 2.7 | Not Detected |
| Tetrachloroethene | 0.50 | Not Detected | 3.4 | Not Detected |
| 2-Hexanone | 2.0 | Not Detected | 8.2 | Not Detected |

**Client Sample ID: Lab Blank**

**Lab ID#: 1301354AR1-05A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **2012207d** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 1/22/13 01:56 PM** | |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Dibromochloromethane | 0.50 | Not Detected | 4.2 | Not Detected |
| 1,2-Dibromoethane (EDB) | 0.50 | Not Detected | 3.8 | Not Detected |
| Chlorobenzene | 0.50 | Not Detected | 2.3 | Not Detected |
| Ethyl Benzene | 0.50 | Not Detected | 2.2 | Not Detected |
| m,p-Xylene | 0.50 | Not Detected | 2.2 | Not Detected |
| o-Xylene | 0.50 | Not Detected | 2.2 | Not Detected |
| Styrene | 0.50 | Not Detected | 2.1 | Not Detected |
| Bromoform | 0.50 | Not Detected | 5.2 | Not Detected |
| Cumene | 0.50 | Not Detected | 2.4 | Not Detected |
| 1,1,2,2-Tetrachloroethane | 0.50 | Not Detected | 3.4 | Not Detected |
| Propylbenzene | 0.50 | Not Detected | 2.4 | Not Detected |
| 4-Ethyltoluene | 0.50 | 0.093 J | 2.4 | 0.46 J |
| 1,3,5-Trimethylbenzene | 0.50 | Not Detected | 2.4 | Not Detected |
| 1,2,4-Trimethylbenzene | 0.50 | Not Detected | 2.4 | Not Detected |
| 1,3-Dichlorobenzene | 0.50 | Not Detected | 3.0 | Not Detected |
| 1,4-Dichlorobenzene | 0.50 | Not Detected | 3.0 | Not Detected |
| alpha-Chlorotoluene | 0.50 | Not Detected | 2.6 | Not Detected |
| 1,2-Dichlorobenzene | 0.50 | Not Detected | 3.0 | Not Detected |
| 1,2,4-Trichlorobenzene | 2.0 | Not Detected UJ | 15 | Not Detected UJ |
| Hexachlorobutadiene | 2.0 | Not Detected | 21 | Not Detected |
| Butane | 2.0 | Not Detected | 4.8 | Not Detected |
| Isopentane | 2.0 | Not Detected | 5.9 | Not Detected |

J = Estimated value.
UJ = Non-detected compound associated with low bias in the CCV and/or LCS.

**TENTATIVELY IDENTIFIED COMPOUNDS**

| Compound | CAS Number | Match Quality | Amount ((ppbv)) |
|---|---|---|---|
| None Identified | | | |

**Container Type: NA - Not Applicable**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| Toluene-d8 | 91 | 70-130 |
| 1,2-Dichloroethane-d4 | 99 | 70-130 |
| 4-Bromofluorobenzene | 95 | 70-130 |

eurofins | Air Toxics

**Client Sample ID: Lab Blank**
**Lab ID#: 1301354AR1-05B**
**EPA METHOD TO-15 GC/MS**

| | | | |
|---|---|---|---|
| **File Name:** | **14012237a** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 1/23/13 07:05 AM** | |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 5.0 | Not Detected | 25 | Not Detected |
| Freon 114 | 5.0 | Not Detected | 35 | Not Detected |
| Chloromethane | 20 | Not Detected | 41 | Not Detected |
| Vinyl Chloride | 5.0 | Not Detected | 13 | Not Detected |
| 1,3-Butadiene | 5.0 | Not Detected | 11 | Not Detected |
| Bromomethane | 5.0 | Not Detected | 19 | Not Detected |
| Chloroethane | 20 | Not Detected | 53 | Not Detected |
| Freon 11 | 5.0 | Not Detected | 28 | Not Detected |
| Ethanol | 20 | 8.0 J | 38 | 15 J |
| Freon 113 | 5.0 | Not Detected | 38 | Not Detected |
| 1,1-Dichloroethene | 5.0 | Not Detected | 20 | Not Detected |
| Acetone | 20 | Not Detected | 48 | Not Detected |
| 2-Propanol | 20 | Not Detected | 49 | Not Detected |
| Carbon Disulfide | 5.0 | Not Detected | 16 | Not Detected |
| 3-Chloropropene | 20 | Not Detected | 63 | Not Detected |
| Methylene Chloride | 5.0 | 1.1 J | 17 | 3.8 J |
| Methyl tert-butyl ether | 5.0 | Not Detected | 18 | Not Detected |
| trans-1,2-Dichloroethene | 5.0 | Not Detected | 20 | Not Detected |
| Hexane | 5.0 | Not Detected | 18 | Not Detected |
| 1,1-Dichloroethane | 5.0 | Not Detected | 20 | Not Detected |
| 2-Butanone (Methyl Ethyl Ketone) | 20 | Not Detected | 59 | Not Detected |
| cis-1,2-Dichloroethene | 5.0 | Not Detected | 20 | Not Detected |
| Tetrahydrofuran | 5.0 | Not Detected | 15 | Not Detected |
| Chloroform | 5.0 | Not Detected | 24 | Not Detected |
| 1,1,1-Trichloroethane | 5.0 | Not Detected | 27 | Not Detected |
| Cyclohexane | 5.0 | Not Detected | 17 | Not Detected |
| Carbon Tetrachloride | 5.0 | Not Detected | 31 | Not Detected |
| 2,2,4-Trimethylpentane | 5.0 | Not Detected | 23 | Not Detected |
| Benzene | 5.0 | Not Detected | 16 | Not Detected |
| 1,2-Dichloroethane | 5.0 | Not Detected | 20 | Not Detected |
| Heptane | 5.0 | Not Detected | 20 | Not Detected |
| Trichloroethene | 5.0 | Not Detected | 27 | Not Detected |
| 1,2-Dichloropropane | 5.0 | Not Detected | 23 | Not Detected |
| 1,4-Dioxane | 20 | Not Detected | 72 | Not Detected |
| Bromodichloromethane | 5.0 | Not Detected | 34 | Not Detected |
| cis-1,3-Dichloropropene | 5.0 | Not Detected | 23 | Not Detected |
| 4-Methyl-2-pentanone | 5.0 | Not Detected | 20 | Not Detected |
| Toluene | 5.0 | Not Detected | 19 | Not Detected |
| trans-1,3-Dichloropropene | 5.0 | Not Detected | 23 | Not Detected |
| 1,1,2-Trichloroethane | 5.0 | Not Detected | 27 | Not Detected |
| Tetrachloroethene | 5.0 | Not Detected | 34 | Not Detected |
| 2-Hexanone | 20 | Not Detected | 82 | Not Detected |

**Client Sample ID: Lab Blank**
**Lab ID#: 1301354AR1-05B**
**EPA METHOD TO-15 GC/MS**

| | | | |
|---|---|---|---|
| File Name: | 14012237a | Date of Collection: NA | |
| Dil. Factor: | 1.00 | Date of Analysis: 1/23/13 07:05 AM | |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Dibromochloromethane | 5.0 | Not Detected | 42 | Not Detected |
| 1,2-Dibromoethane (EDB) | 5.0 | Not Detected | 38 | Not Detected |
| Chlorobenzene | 5.0 | Not Detected | 23 | Not Detected |
| Ethyl Benzene | 5.0 | Not Detected | 22 | Not Detected |
| m,p-Xylene | 5.0 | Not Detected | 22 | Not Detected |
| o-Xylene | 5.0 | Not Detected | 22 | Not Detected |
| Styrene | 5.0 | Not Detected | 21 | Not Detected |
| Bromoform | 5.0 | Not Detected | 52 | Not Detected |
| Cumene | 5.0 | Not Detected | 24 | Not Detected |
| 1,1,2,2-Tetrachloroethane | 5.0 | Not Detected | 34 | Not Detected |
| Propylbenzene | 5.0 | Not Detected | 24 | Not Detected |
| 4-Ethyltoluene | 5.0 | Not Detected | 24 | Not Detected |
| 1,3,5-Trimethylbenzene | 5.0 | Not Detected | 24 | Not Detected |
| 1,2,4-Trimethylbenzene | 5.0 | Not Detected | 24 | Not Detected |
| 1,3-Dichlorobenzene | 5.0 | Not Detected | 30 | Not Detected |
| 1,4-Dichlorobenzene | 5.0 | Not Detected | 30 | Not Detected |
| alpha-Chlorotoluene | 5.0 | Not Detected | 26 | Not Detected |
| 1,2-Dichlorobenzene | 5.0 | Not Detected | 30 | Not Detected |
| 1,2,4-Trichlorobenzene | 20 | Not Detected | 150 | Not Detected |
| Hexachlorobutadiene | 20 | Not Detected | 210 | Not Detected |
| Butane | 20 | Not Detected | 48 | Not Detected |
| Isopentane | 20 | Not Detected | 59 | Not Detected |

J = Estimated value.

**TENTATIVELY IDENTIFIED COMPOUNDS**

| Compound | CAS Number | Match Quality | Amount ((ppbv)) |
|---|---|---|---|
| None Identified | | | |

**Container Type: NA - Not Applicable**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| 1,2-Dichloroethane-d4 | 108 | 70-130 |
| Toluene-d8 | 99 | 70-130 |
| 4-Bromofluorobenzene | 100 | 70-130 |

**Client Sample ID: CCV**

**Lab ID#: 1301354AR1-06A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **2012202** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 1/22/13 09:16 AM** | |

| Compound | %Recovery |
|---|---|
| Freon 12 | 77 |
| Freon 114 | 80 |
| Chloromethane | 82 |
| Vinyl Chloride | 80 |
| 1,3-Butadiene | 85 |
| Bromomethane | 92 |
| Chloroethane | 88 |
| Freon 11 | 78 |
| Ethanol | 89 |
| Freon 113 | 79 |
| 1,1-Dichloroethene | 88 |
| Acetone | 88 |
| 2-Propanol | 92 |
| Carbon Disulfide | 87 |
| 3-Chloropropene | 94 |
| Methylene Chloride | 81 |
| Methyl tert-butyl ether | 94 |
| trans-1,2-Dichloroethene | 90 |
| Hexane | 89 |
| 1,1-Dichloroethane | 82 |
| 2-Butanone (Methyl Ethyl Ketone) | 94 |
| cis-1,2-Dichloroethene | 88 |
| Tetrahydrofuran | 93 |
| Chloroform | 79 |
| 1,1,1-Trichloroethane | 82 |
| Cyclohexane | 91 |
| Carbon Tetrachloride | 84 |
| 2,2,4-Trimethylpentane | 82 |
| Benzene | 76 |
| 1,2-Dichloroethane | 71 |
| Heptane | 78 |
| Trichloroethene | 76 |
| 1,2-Dichloropropane | 76 |
| 1,4-Dioxane | 78 |
| Bromodichloromethane | 75 |
| cis-1,3-Dichloropropene | 86 |
| 4-Methyl-2-pentanone | 82 |
| Toluene | 72 |
| trans-1,3-Dichloropropene | 97 |
| 1,1,2-Trichloroethane | 82 |
| Tetrachloroethene | 85 |
| 2-Hexanone | 90 |

eurofins | Air Toxics

**Client Sample ID: CCV**

**Lab ID#: I30I354ARI-06A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **2012202** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 1/22/13 09:16 AM** | |

| Compound | %Recovery |
|---|---|
| Dibromochloromethane | 89 |
| 1,2-Dibromoethane (EDB) | 86 |
| Chlorobenzene | 79 |
| Ethyl Benzene | 87 |
| m,p-Xylene | 86 |
| o-Xylene | 84 |
| Styrene | 92 |
| Bromoform | 92 |
| Cumene | 83 |
| 1,1,2,2-Tetrachloroethane | 79 |
| Propylbenzene | 88 |
| 4-Ethyltoluene | 82 |
| 1,3,5-Trimethylbenzene | 78 |
| 1,2,4-Trimethylbenzene | 85 |
| 1,3-Dichlorobenzene | 79 |
| 1,4-Dichlorobenzene | 76 |
| alpha-Chlorotoluene | 99 |
| 1,2-Dichlorobenzene | 79 |
| 1,2,4-Trichlorobenzene | 68 Q |
| Hexachlorobutadiene | 84 |
| Butane | 83 |
| Isopentane | 88 |

Q = Exceeds Quality Control limits.

**Container Type: NA - Not Applicable**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| Toluene-d8 | 92 | 70-130 |
| 1,2-Dichloroethane-d4 | 96 | 70-130 |
| 4-Bromofluorobenzene | 102 | 70-130 |

eurofins | Air Toxics

**Client Sample ID: CCV**
**Lab ID#: 1301354AR1-06B**
**EPA METHOD TO-15 GC/MS**

| | | | |
|---|---|---|---|
| **File Name:** | **14012233** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 1/22/13 09:36 PM** | |

| Compound | %Recovery |
|---|---|
| Freon 12 | 110 |
| Freon 114 | 112 |
| Chloromethane | 118 |
| Vinyl Chloride | 97 |
| 1,3-Butadiene | 102 |
| Bromomethane | 112 |
| Chloroethane | 104 |
| Freon 11 | 111 |
| Ethanol | 111 |
| Freon 113 | 98 |
| 1,1-Dichloroethene | 112 |
| Acetone | 102 |
| 2-Propanol | 102 |
| Carbon Disulfide | 87 |
| 3-Chloropropene | 89 |
| Methylene Chloride | 108 |
| Methyl tert-butyl ether | 93 |
| trans-1,2-Dichloroethene | 103 |
| Hexane | 100 |
| 1,1-Dichloroethane | 102 |
| 2-Butanone (Methyl Ethyl Ketone) | 98 |
| cis-1,2-Dichloroethene | 97 |
| Tetrahydrofuran | 102 |
| Chloroform | 102 |
| 1,1,1-Trichloroethane | 94 |
| Cyclohexane | 94 |
| Carbon Tetrachloride | 103 |
| 2,2,4-Trimethylpentane | 99 |
| Benzene | 99 |
| 1,2-Dichloroethane | 108 |
| Heptane | 99 |
| Trichloroethene | 102 |
| 1,2-Dichloropropane | 101 |
| 1,4-Dioxane | 103 |
| Bromodichloromethane | 98 |
| cis-1,3-Dichloropropene | 85 |
| 4-Methyl-2-pentanone | 95 |
| Toluene | 96 |
| trans-1,3-Dichloropropene | 84 |
| 1,1,2-Trichloroethane | 98 |
| Tetrachloroethene | 100 |
| 2-Hexanone | 94 |

eurofins | Air Toxics

**Client Sample ID: CCV**
**Lab ID#: 1301354AR1-06B**
**EPA METHOD TO-15 GC/MS**

| | | | |
|---|---|---|---|
| **File Name:** | **14012233** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 1/22/13 09:36 PM** | |

| Compound | %Recovery |
|---|---|
| Dibromochloromethane | 97 |
| 1,2-Dibromoethane (EDB) | 98 |
| Chlorobenzene | 102 |
| Ethyl Benzene | 96 |
| m,p-Xylene | 94 |
| o-Xylene | 98 |
| Styrene | 97 |
| Bromoform | 93 |
| Cumene | 99 |
| 1,1,2,2-Tetrachloroethane | 102 |
| Propylbenzene | 104 |
| 4-Ethyltoluene | 107 |
| 1,3,5-Trimethylbenzene | 110 |
| 1,2,4-Trimethylbenzene | 103 |
| 1,3-Dichlorobenzene | 101 |
| 1,4-Dichlorobenzene | 101 |
| alpha-Chlorotoluene | 81 |
| 1,2-Dichlorobenzene | 106 |
| 1,2,4-Trichlorobenzene | 98 |
| Hexachlorobutadiene | 108 |
| Butane | 110 |
| Isopentane | 112 |

**Container Type: NA - Not Applicable**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| 1,2-Dichloroethane-d4 | 105 | 70-130 |
| Toluene-d8 | 100 | 70-130 |
| 4-Bromofluorobenzene | 103 | 70-130 |

**Client Sample ID: LCS**
**Lab ID#: 1301354AR1-07A**
**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **2012203** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 1/22/13 10:00 AM** | |

| Compound | %Recovery |
|---|---|
| Freon 12 | 74 |
| Freon 114 | 78 |
| Chloromethane | 80 |
| Vinyl Chloride | 78 |
| 1,3-Butadiene | 83 |
| Bromomethane | 86 |
| Chloroethane | 86 |
| Freon 11 | 71 |
| Ethanol | 91 |
| Freon 113 | 80 |
| 1,1-Dichloroethene | 93 |
| Acetone | 88 |
| 2-Propanol | 94 |
| Carbon Disulfide | 107 |
| 3-Chloropropene | 103 |
| Methylene Chloride | 80 |
| Methyl tert-butyl ether | 96 |
| trans-1,2-Dichloroethene | 100 |
| Hexane | 85 |
| 1,1-Dichloroethane | 81 |
| 2-Butanone (Methyl Ethyl Ketone) | 96 |
| cis-1,2-Dichloroethene | 88 |
| Tetrahydrofuran | 89 |
| Chloroform | 79 |
| 1,1,1-Trichloroethane | 82 |
| Cyclohexane | 90 |
| Carbon Tetrachloride | 83 |
| 2,2,4-Trimethylpentane | 80 |
| Benzene | 76 |
| 1,2-Dichloroethane | 71 |
| Heptane | 76 |
| Trichloroethene | 77 |
| 1,2-Dichloropropane | 75 |
| 1,4-Dioxane | 77 |
| Bromodichloromethane | 74 |
| cis-1,3-Dichloropropene | 84 |
| 4-Methyl-2-pentanone | 81 |
| Toluene | 72 |
| trans-1,3-Dichloropropene | 94 |
| 1,1,2-Trichloroethane | 82 |
| Tetrachloroethene | 82 |
| 2-Hexanone | 89 |

eurofins | Air Toxics

**Client Sample ID: LCS**

**Lab ID#: 1301354AR1-07A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **2012203** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 1/22/13 10:00 AM** | |

| Compound | %Recovery |
|---|---|
| Dibromochloromethane | 83 |
| 1,2-Dibromoethane (EDB) | 83 |
| Chlorobenzene | 78 |
| Ethyl Benzene | 84 |
| m,p-Xylene | 86 |
| o-Xylene | 82 |
| Styrene | 92 |
| Bromoform | 86 |
| Cumene | 82 |
| 1,1,2,2-Tetrachloroethane | 79 |
| Propylbenzene | 87 |
| 4-Ethyltoluene | 76 |
| 1,3,5-Trimethylbenzene | 74 |
| 1,2,4-Trimethylbenzene | 81 |
| 1,3-Dichlorobenzene | 78 |
| 1,4-Dichlorobenzene | 75 |
| alpha-Chlorotoluene | 90 |
| 1,2-Dichlorobenzene | 77 |
| 1,2,4-Trichlorobenzene | 70 |
| Hexachlorobutadiene | 80 |
| Butane | 76 |
| Isopentane | 82 |

**Container Type: NA - Not Applicable**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| Toluene-d8 | 94 | 70-130 |
| 1,2-Dichloroethane-d4 | 94 | 70-130 |
| 4-Bromofluorobenzene | 98 | 70-130 |

eurofins | Air Toxics

**Client Sample ID: LCSD**
**Lab ID#: 1301354AR1-07AA**
**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **2012204** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 1/22/13 10:55 AM** | |

| Compound | %Recovery |
|---|---|
| Freon 12 | 73 |
| Freon 114 | 76 |
| Chloromethane | 80 |
| Vinyl Chloride | 76 |
| 1,3-Butadiene | 80 |
| Bromomethane | 83 |
| Chloroethane | 84 |
| Freon 11 | 69 Q |
| Ethanol | 88 |
| Freon 113 | 78 |
| 1,1-Dichloroethene | 91 |
| Acetone | 88 |
| 2-Propanol | 93 |
| Carbon Disulfide | 102 |
| 3-Chloropropene | 101 |
| Methylene Chloride | 78 |
| Methyl tert-butyl ether | 94 |
| trans-1,2-Dichloroethene | 97 |
| Hexane | 84 |
| 1,1-Dichloroethane | 79 |
| 2-Butanone (Methyl Ethyl Ketone) | 97 |
| cis-1,2-Dichloroethene | 86 |
| Tetrahydrofuran | 87 |
| Chloroform | 78 |
| 1,1,1-Trichloroethane | 79 |
| Cyclohexane | 88 |
| Carbon Tetrachloride | 80 |
| 2,2,4-Trimethylpentane | 77 |
| Benzene | 75 |
| 1,2-Dichloroethane | 71 |
| Heptane | 76 |
| Trichloroethene | 77 |
| 1,2-Dichloropropane | 75 |
| 1,4-Dioxane | 76 |
| Bromodichloromethane | 73 |
| cis-1,3-Dichloropropene | 84 |
| 4-Methyl-2-pentanone | 80 |
| Toluene | 71 |
| trans-1,3-Dichloropropene | 94 |
| 1,1,2-Trichloroethane | 82 |
| Tetrachloroethene | 81 |
| 2-Hexanone | 90 |

**Client Sample ID: LCSD**

**Lab ID#: 1301354AR1-07AA**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **2012204** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 1/22/13 10:55 AM** | |

| Compound | %Recovery |
|---|---|
| Dibromochloromethane | 84 |
| 1,2-Dibromoethane (EDB) | 85 |
| Chlorobenzene | 79 |
| Ethyl Benzene | 86 |
| m,p-Xylene | 88 |
| o-Xylene | 84 |
| Styrene | 93 |
| Bromoform | 86 |
| Cumene | 82 |
| 1,1,2,2-Tetrachloroethane | 79 |
| Propylbenzene | 88 |
| 4-Ethyltoluene | 78 |
| 1,3,5-Trimethylbenzene | 77 |
| 1,2,4-Trimethylbenzene | 84 |
| 1,3-Dichlorobenzene | 78 |
| 1,4-Dichlorobenzene | 76 |
| alpha-Chlorotoluene | 92 |
| 1,2-Dichlorobenzene | 78 |
| 1,2,4-Trichlorobenzene | 72 |
| Hexachlorobutadiene | 81 |
| Butane | 76 |
| Isopentane | 81 |

Q = Exceeds Quality Control limits.

**Container Type: NA - Not Applicable**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| Toluene-d8 | 91 | 70-130 |
| 1,2-Dichloroethane-d4 | 91 | 70-130 |
| 4-Bromofluorobenzene | 100 | 70-130 |

**Client Sample ID: LCS**
**Lab ID#: 1301354AR1-07B**
**EPA METHOD TO-15 GC/MS**

| | | | |
|---|---|---|---|
| **File Name:** | **14012234** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 1/22/13 10:10 PM** | |

| Compound | %Recovery |
|---|---|
| Freon 12 | 114 |
| Freon 114 | 111 |
| Chloromethane | 122 |
| Vinyl Chloride | 98 |
| 1,3-Butadiene | 103 |
| Bromomethane | 107 |
| Chloroethane | 102 |
| Freon 11 | 113 |
| Ethanol | 104 |
| Freon 113 | 98 |
| 1,1-Dichloroethene | 116 |
| Acetone | 101 |
| 2-Propanol | 106 |
| Carbon Disulfide | 110 |
| 3-Chloropropene | 104 |
| Methylene Chloride | 105 |
| Methyl tert-butyl ether | 96 |
| trans-1,2-Dichloroethene | 117 |
| Hexane | 98 |
| 1,1-Dichloroethane | 103 |
| 2-Butanone (Methyl Ethyl Ketone) | 94 |
| cis-1,2-Dichloroethene | 99 |
| Tetrahydrofuran | 99 |
| Chloroform | 107 |
| 1,1,1-Trichloroethane | 100 |
| Cyclohexane | 97 |
| Carbon Tetrachloride | 106 |
| 2,2,4-Trimethylpentane | 97 |
| Benzene | 103 |
| 1,2-Dichloroethane | 111 |
| Heptane | 98 |
| Trichloroethene | 103 |
| 1,2-Dichloropropane | 101 |
| 1,4-Dioxane | 104 |
| Bromodichloromethane | 103 |
| cis-1,3-Dichloropropene | 88 |
| 4-Methyl-2-pentanone | 94 |
| Toluene | 96 |
| trans-1,3-Dichloropropene | 85 |
| 1,1,2-Trichloroethane | 101 |
| Tetrachloroethene | 100 |
| 2-Hexanone | 92 |

**Client Sample ID: LCS**
**Lab ID#: 1301354AR1-07B**
**EPA METHOD TO-15 GC/MS**

| | | | |
|---|---|---|---|
| **File Name:** | 14012234 | **Date of Collection: NA** | |
| **Dil. Factor:** | 1.00 | **Date of Analysis: 1/22/13 10:10 PM** | |

| Compound | %Recovery |
|---|---|
| Dibromochloromethane | 99 |
| 1,2-Dibromoethane (EDB) | 100 |
| Chlorobenzene | 103 |
| Ethyl Benzene | 96 |
| m,p-Xylene | 100 |
| o-Xylene | 98 |
| Styrene | 100 |
| Bromoform | 96 |
| Cumene | 101 |
| 1,1,2,2-Tetrachloroethane | 109 |
| Propylbenzene | 106 |
| 4-Ethyltoluene | 103 |
| 1,3,5-Trimethylbenzene | 106 |
| 1,2,4-Trimethylbenzene | 98 |
| 1,3-Dichlorobenzene | 103 |
| 1,4-Dichlorobenzene | 103 |
| alpha-Chlorotoluene | 86 |
| 1,2-Dichlorobenzene | 106 |
| 1,2,4-Trichlorobenzene | 102 |
| Hexachlorobutadiene | 99 |
| Butane | 104 |
| Isopentane | 109 |

**Container Type: NA - Not Applicable**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| 1,2-Dichloroethane-d4 | 104 | 70-130 |
| Toluene-d8 | 101 | 70-130 |
| 4-Bromofluorobenzene | 105 | 70-130 |

eurofins | Air Toxics

**Client Sample ID: LCSD**
**Lab ID#: 1301354AR1-07BB**
**EPA METHOD TO-15 GC/MS**

| | | | |
|---|---|---|---|
| **File Name:** | 14012235 | **Date of Collection:** | NA |
| **Dil. Factor:** | 1.00 | **Date of Analysis:** | 1/22/13 10:46 PM |

| Compound | %Recovery |
|---|---|
| Freon 12 | 112 |
| Freon 114 | 110 |
| Chloromethane | 123 |
| Vinyl Chloride | 99 |
| 1,3-Butadiene | 102 |
| Bromomethane | 111 |
| Chloroethane | 103 |
| Freon 11 | 112 |
| Ethanol | 102 |
| Freon 113 | 98 |
| 1,1-Dichloroethene | 117 |
| Acetone | 104 |
| 2-Propanol | 102 |
| Carbon Disulfide | 108 |
| 3-Chloropropene | 103 |
| Methylene Chloride | 107 |
| Methyl tert-butyl ether | 94 |
| trans-1,2-Dichloroethene | 120 |
| Hexane | 97 |
| 1,1-Dichloroethane | 102 |
| 2-Butanone (Methyl Ethyl Ketone) | 94 |
| cis-1,2-Dichloroethene | 97 |
| Tetrahydrofuran | 98 |
| Chloroform | 106 |
| 1,1,1-Trichloroethane | 98 |
| Cyclohexane | 97 |
| Carbon Tetrachloride | 108 |
| 2,2,4-Trimethylpentane | 97 |
| Benzene | 101 |
| 1,2-Dichloroethane | 109 |
| Heptane | 99 |
| Trichloroethene | 104 |
| 1,2-Dichloropropane | 100 |
| 1,4-Dioxane | 101 |
| Bromodichloromethane | 102 |
| cis-1,3-Dichloropropene | 88 |
| 4-Methyl-2-pentanone | 94 |
| Toluene | 97 |
| trans-1,3-Dichloropropene | 88 |
| 1,1,2-Trichloroethane | 103 |
| Tetrachloroethene | 103 |
| 2-Hexanone | 93 |

eurofins | Air Toxics

**Client Sample ID: LCSD**
**Lab ID#: 1301354AR1-07BB**
**EPA METHOD TO-15 GC/MS**

| | | | |
|---|---|---|---|
| **File Name:** | **14012235** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 1/22/13 10:46 PM** | |

| Compound | %Recovery |
|---|---|
| Dibromochloromethane | 100 |
| 1,2-Dibromoethane (EDB) | 103 |
| Chlorobenzene | 106 |
| Ethyl Benzene | 97 |
| m,p-Xylene | 101 |
| o-Xylene | 101 |
| Styrene | 100 |
| Bromoform | 100 |
| Cumene | 104 |
| 1,1,2,2-Tetrachloroethane | 111 |
| Propylbenzene | 107 |
| 4-Ethyltoluene | 104 |
| 1,3,5-Trimethylbenzene | 110 |
| 1,2,4-Trimethylbenzene | 102 |
| 1,3-Dichlorobenzene | 106 |
| 1,4-Dichlorobenzene | 105 |
| alpha-Chlorotoluene | 86 |
| 1,2-Dichlorobenzene | 110 |
| 1,2,4-Trichlorobenzene | 103 |
| Hexachlorobutadiene | 111 |
| Butane | 101 |
| Isopentane | 112 |

**Container Type: NA - Not Applicable**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| 1,2-Dichloroethane-d4 | 104 | 70-130 |
| Toluene-d8 | 99 | 70-130 |
| 4-Bromofluorobenzene | 105 | 70-130 |

# Shell Oil Products Chain Of Custody Record

URS

Air Toxics LTD.
**Project Name: Roxana Soil Vapor**
**Project # 21562850.04001**
Lab Vendor #

Please Check Appropriate Box: ☑ ENV. SERVICES ☐ MOTIVA RETAIL ☐ SHELL RETAIL ☐ MOTIVA SD&ON ☐ CONSULTANT ☐ LUBES ☐ SHELL PIPELINE ☐ OTHER

Print Bill To Contact Name: Robert Mooshegian
PO #:
INCIDENT # (ENV SERVICES): 9 7 2 1 6 6 4 0
SAP #: 3 4 0 0 6 1
☐ CHECK IF NO INCIDENT # APPLIES
DATE: 01/21/13
PAGE: 1 of 1

SAMPLING COMPANY: JRS CORPORATION
LOG CODE:
SITE ADDRESS: Street and City: 900 SOUTH CENTRAL AVE -- ROXANA
State: IL
GLOBAL ID NO:
ADDRESS: 1001 HIGHLANDS PLAZA DRIVE WEST - SUITE 300, ST. LOUIS, MO 63110
CONTRACT VENDOR TO (Name, Company, City) Location: Elizabeth Kunkel, URS, St. Louis
PHONE NO: 314-743-4179
E-MAIL: Elizabeth_Kunkel@URSCorp.com
CONSULTANT PROJECT NAME: Roxana Soil Vapor
Laboratory Address: Air Toxics, LTD 180 Blue Ravine Road Suite B, Folsom, CA 95630-4719
M. Currier, E. Arthur, A. Day, B. Lehan
TELEPHONE: 314-429-0100
FAX: 314-429-0462
Report To Contact E-MAIL: Robert.Mooshegian@urs.com

TURNAROUND TIME (CALENDAR DAYS): SAME DAY
☐ STANDARD (14 DAY) ☐ 5 DAYS ☐ 3 DAYS ☐ 2 DAYS ☐ 24 HOURS ☐ RESULTS NEEDED ON WEEKEND

☐ LA - RWQCB REPORT FORMAT ☑ UST AGENCY:

DELIVERABLES: ☐ LEVEL 1 ☐ LEVEL 2 ☐ LEVEL 3 ☑ LEVEL 4 ☐ OTHER (SPECIFY)

☑ SHELL CONTRACT RATE APPLIES
☐ STATE REIMBURSEMENT RATE APPLIES
☐ EDD NOT NEEDED
☑ RECEIPT VERIFICATION REQUESTED

REQUESTED ANALYSIS

| LAB USE ONLY | Field Sample Identification | SAMPLING DATE | SAMPLING TIME | Canister Number | Canister Pressure/Vacuum Initial | Final | Receipt | Final (psi) | Modified TO-15 + Butane & Isopentane | ASTM D-1946 + Helium | ASTM D-1946 |
|---|---|---|---|---|---|---|---|---|---|---|---|
| [illegible] | VMP-47-20-012113 | 01/21/13 | 1417-1447 | 34141 | -30 | -7 | | | X | X | |
| [illegible] | VMP-47-30-012113 | 01/21/13 | 1515-1545 | 2035 | -30 | -7.5 | | | X | X | |
| [illegible] | VMP-1-8.5-012113 | 01/21/13 | 1234-1306 | 3002 | -30 | -8 | | | X | X | |
| [illegible] | VMP-1-23.5-012113 | 01/21/13 | 1356-1428 | 3997 | -30 | -10 | | | X | X | |

1/21/13

Turn Around Time: ☐ Normal ☑ Rush SAME DAY Specify

Lab Use Only
Pressurized by:
Date:
Pressurization Gas: $N_2$ He

ADDITIONAL NOTES:
- Same day turn around time
- Report results between MDL and RL
- Level IV ECVP

| | | | |
|---|---|---|---|
| Relinquished by (Signature) | Received by (Signature) FEDEX | Date 1/21/13 | Time 1830 |
| Relinquished by (Signature) | Received by (Signature) | Date 1/22/13 | Time 105 |
| Relinquished by (Signature) | Received by (Signature) | Date | Time |

Custody Seal Intact?
Y N None Temp N/A

05/2/06 Revision

1301354

eurofins | Air Toxics

2/12/2013
Ms. Elizabeth Kunkel
URS Corporation
1001 Highlands Plaza Dr. West
Suite 300
St. Louis MO 63110

Project Name: Roxana Soil Vapor
Project #: 21562850.04001
Workorder #: 1301354BR1

Dear Ms. Elizabeth Kunkel

The following report includes the data for the above referenced project for sample(s) received on 1/22/2013 at Air Toxics Ltd.

The data and associated QC analyzed by Modified ASTM D-1945 are compliant with the project requirements or laboratory criteria with the exception of the deviations noted in the attached case narrative.

Thank you for choosing Air Toxics Ltd. for your air analysis needs. Air Toxics Ltd. is committed to providing accurate data of the highest quality. Please feel free to contact the Project Manager: Kelly Buettner at 916-985-1000 if you have any questions regarding the data in this report.

Regards,

Kelly Buettner

Project Manager

Reviewed
on
2/18/2013

eurofins | Air Toxics

# WORK ORDER #: 1301354BR1

Work Order Summary

| | | | |
|---|---|---|---|
| **CLIENT:** | Ms. Elizabeth Kunkel<br>URS Corporation<br>1001 Highlands Plaza Dr. West<br>Suite 300<br>St. Louis, MO 63110 | **BILL TO:** | Accounts Payable Austin<br>URS Corporation<br>P.O. BOX 203970<br>Austin, TX 78720-1088 |
| **PHONE:** | 314-743-4179 | **P.O. #** | 21562735.00013 |
| **FAX:** | | **PROJECT #** | 21562850.04001 Roxana Soil Vapor |
| **DATE RECEIVED:** | 01/22/2013 | **CONTACT:** | Kelly Buettner |
| **DATE COMPLETED:** | 01/23/2013 | | |
| **DATE REISSUED:** | 02/12/2013 | | |

| FRACTION # | NAME | TEST | RECEIPT VAC./PRES. | FINAL PRESSURE |
|---|---|---|---|---|
| 01A | VMP-47-20-012113 | Modified ASTM D-1945 | 6.0 "Hg | 15 psi |
| 02A | VMP-47-30-012113 | Modified ASTM D-1945 | 6.5 "Hg | 15 psi |
| 03A | VMP-1-8.5-012113 | Modified ASTM D-1945 | 5.5 "Hg | 15 psi |
| 04A | VMP-1-23.5-012113 | Modified ASTM D-1945 | 7.5 "Hg | 15 psi |
| 05A | Lab Blank | Modified ASTM D-1945 | NA | NA |
| 05B | Lab Blank | Modified ASTM D-1945 | NA | NA |
| 06A | LCS | Modified ASTM D-1945 | NA | NA |
| 06AA | LCSD | Modified ASTM D-1945 | NA | NA |

CERTIFIED BY: Heidi Isaacs DATE: 02/12/13

Technical Director

Certification numbers: AZ Licensure AZ0775, CA NELAP - 12282CA, NY NELAP - 11291,
TX NELAP - T104704434-12-4, UT NELAP CA009332012-3, WA NELAP - C935
Name of Accrediting Agency: NELAP/ORELAP (Oregon Environmental Laboratory Accreditation Program)
Accreditation number: CA300005, Effective date: 10/18/2012, Expiration date: 10/17/2013.
Eurofins Air Toxics Ltd. certifies that the test results contained in this report meet all requirements of the NELAC standards

This report shall not be reproduced, except in full, without the written approval of Eurofins Air Toxics, Inc.

180 BLUE RAVINE ROAD, SUITE B FOLSOM, CA - 9563
(916) 985-1000 . (800) 985-5955 . FAX (916) 985-1020

**LABORATORY NARRATIVE**
**Modified ASTM D-1946**
**URS Corporation**
**Workorder# 1301354BR1**

Four 1 Liter Summa Canister samples were received on January 22, 2013. The laboratory performed analysis via Modified ASTM Method D-1946 for Methane and fixed gases in air using GC/FID or GC/TCD. The method involves direct injection of 1.0 mL of sample.

On the analytical column employed for this analysis, Oxygen coelutes with Argon. The corresponding peak is quantitated as Oxygen.

Since Nitrogen is used to pressurize samples, the reported Nitrogen values are calculated by adding all the sample components and subtracting from 100%.

Method modifications taken to run these samples are summarized in the table below. Specific project requirements may over-ride the ATL modifications.

| *Requirement* | *ASTM D-1946* | *ATL Modifications* |
|---|---|---|
| Calibration | A single point calibration is performed using a reference standard closely matching the composition of the unknown. | A 3-point calibration curve is performed. Quantitation is based on a daily calibration standard which may or may not resemble the composition of the associated samples. |
| Reference Standard | The composition of any reference standard must be known to within 0.01 mol % for any component. | The standards used by ATL are blended to a >/= 95% accuracy. |
| Sample Injection Volume | Components whose concentrations are in excess of 5 % should not be analyzed by using sample volumes greater than 0.5 mL. | The sample container is connected directly to a fixed volume sample loop of 1.0 mL on the GC. Linear range is defined by the calibration curve. Bags are loaded by vacuum. |
| Normalization | Normalize the mole percent values by multiplying each value by 100 and dividing by the sum of the original values. The sum of the original values should not differ from 100% by more than 1.0%. | Results are not normalized. The sum of the reported values can differ from 100% by as much as 15%, either due to analytical variability or an unusual sample matrix. |
| Precision | Precision requirements established at each concentration level. | Duplicates should agree within 25% RPD for detections > 5 X's the RL. |

**Receiving Notes**

There were no receiving discrepancies.

**Analytical Notes**

As per project specific client request the laboratory has reported estimated values for target compound hits that are below the Reporting Limit but greater than the Method Detection Limit.

The reporting limit for Carbon Monoxide was raised from 0.010% to 0.050%.

THE WORKORDER WAS REISSUED ON 02/12/13 TO REPORT ADDITIONAL COMPOUNDS FOR VMP-47-20-012113, VMP-47-30-012113, VMP-1-8.5-012113 and VMP-1-23.5-012113 PER CLIENT REQUEST.

**Definition of Data Qualifying Flags**

Seven qualifiers may have been used on the data analysis sheets and indicate as follows:
B - Compound present in laboratory blank greater than reporting limit.
J - Estimated value.
E - Exceeds instrument calibration range.
S - Saturated peak.
Q - Exceeds quality control limits.
U - Compound analyzed for but not detected above the detection limit.
M - Reported value may be biased due to apparent matrix interferences.
File extensions may have been used on the data analysis sheets and indicates as follows:
a-File was requantified
b-File was quantified by a second column and detector
r1-File was requantified for the purpose of reissue

eurofins | Air Toxics

# Summary of Detected Compounds
# NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1945

**Client Sample ID: VMP-47-20-012113**

**Lab ID#: 1301354BR1-01A**

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.25 | 2.0 |
| Nitrogen | 0.25 | 84 |
| Methane | 0.00025 | 0.40 |
| Carbon Dioxide | 0.025 | 13 |
| Ethane | 0.0025 | 0.00010 J |
| Propane | 0.0025 | 0.00027 J |
| Isobutane | 0.0025 | 0.016 |
| Butane | 0.0025 | 0.053 |
| Neopentane | 0.0025 | 0.0013 J |
| Isopentane | 0.0025 | 0.047 |
| Pentane | 0.0025 | 0.0044 |
| C6+ | 0.025 | 0.031 |
| Helium | 0.13 | 0.66 |

**Client Sample ID: VMP-47-30-012113**

**Lab ID#: 1301354BR1-02A**

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.26 | 1.5 |
| Nitrogen | 0.26 | 84 |
| Methane | 0.00026 | 2.2 |
| Carbon Dioxide | 0.026 | 12 |
| Ethane | 0.0026 | 0.00041 J |
| Propane | 0.0026 | 0.00049 J |
| Isobutane | 0.0026 | 0.016 |
| Butane | 0.0026 | 0.060 |
| Neopentane | 0.0026 | 0.0020 J |
| Isopentane | 0.0026 | 0.047 |
| Pentane | 0.0026 | 0.0044 |
| C6+ | 0.026 | 0.035 |

eurofins | Air Toxics

# Summary of Detected Compounds
# NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1945

**Client Sample ID: VMP-1-8.5-012113**

**Lab ID#: 1301354BR1-03A**

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.50 | 21 |
| Nitrogen | 0.50 | 78 |
| Methane | 0.00050 | 0.021 |
| Carbon Dioxide | 0.050 | 0.48 |
| Isobutane | 0.0050 | 0.00034 J |
| Butane | 0.0050 | 0.0032 J |
| Isopentane | 0.0050 | 0.0015 J |
| Pentane | 0.0050 | 0.00037 J |
| C6+ | 0.050 | 0.00099 J |
| Helium | 0.25 | 0.99 |

**Client Sample ID: VMP-1-23.5-012113**

**Lab ID#: 1301354BR1-04A**

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.27 | 20 |
| Nitrogen | 0.27 | 73 |
| Methane | 0.00027 | 0.0044 |
| Carbon Dioxide | 0.027 | 0.39 |
| Isobutane | 0.0027 | 0.000086 J |
| Butane | 0.0027 | 0.00055 J |
| Isopentane | 0.0027 | 0.00046 J |
| Pentane | 0.0027 | 0.00011 J |
| C6+ | 0.027 | 0.00045 J |
| Helium | 0.13 | 6.2 |

eurofins | Air Toxics

**Client Sample ID: VMP-47-20-012113**

**Lab ID#: 1301354BR1-01A**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1945**

| | | | |
|---|---|---|---|
| **File Name:** | **9012218r1** | **Date of Collection:** | **1/21/13 2:47:00 PM** |
| **Dil. Factor:** | **2.52** | **Date of Analysis:** | **1/22/13 04:09 PM** |

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.25 | 2.0 |
| Nitrogen | 0.25 | 84 |
| Carbon Monoxide | 0.13 | Not Detected |
| Methane | 0.00025 | 0.40 |
| Carbon Dioxide | 0.025 | 13 |
| Ethane | 0.0025 | 0.00010 J |
| Ethene | 0.0025 | Not Detected |
| Acetylene | 0.0025 | Not Detected |
| Propane | 0.0025 | 0.00027 J |
| Isobutane | 0.0025 | 0.016 |
| Butane | 0.0025 | 0.053 |
| Neopentane | 0.0025 | 0.0013 J |
| Isopentane | 0.0025 | 0.047 |
| Pentane | 0.0025 | 0.0044 |
| C6+ | 0.025 | 0.031 |
| Helium | 0.13 | 0.66 |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

eurofins | Air Toxics

**Client Sample ID: VMP-47-30-012113**

**Lab ID#: 1301354BR1-02A**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1945**

| | | | |
|---|---|---|---|
| **File Name:** | **9012219r1** | **Date of Collection:** | **1/21/13 3:45:00 PM** |
| **Dil. Factor:** | **2.58** | **Date of Analysis:** | **1/22/13 04:33 PM** |

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.26 | 1.5 |
| Nitrogen | 0.26 | 84 |
| Carbon Monoxide | 0.13 | Not Detected |
| Methane | 0.00026 | 2.2 |
| Carbon Dioxide | 0.026 | 12 |
| Ethane | 0.0026 | 0.00041 J |
| Ethene | 0.0026 | Not Detected |
| Acetylene | 0.0026 | Not Detected |
| Propane | 0.0026 | 0.00049 J |
| Isobutane | 0.0026 | 0.016 |
| Butane | 0.0026 | 0.060 |
| Neopentane | 0.0026 | 0.0020 J |
| Isopentane | 0.0026 | 0.047 |
| Pentane | 0.0026 | 0.0044 |
| C6+ | 0.026 | 0.035 |
| Helium | 0.13 | Not Detected |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

eurofins | Air Toxics

**Client Sample ID: VMP-1-8.5-012113**

**Lab ID#: 1301354BR1-03A**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1945**

| | | | |
|---|---|---|---|
| **File Name:** | **9012217r1** | **Date of Collection:** | **1/21/13 1:06:00 PM** |
| **Dil. Factor:** | **5.01** | **Date of Analysis:** | **1/22/13 03:28 PM** |

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.50 | 21 |
| Nitrogen | 0.50 | 78 |
| Carbon Monoxide | 0.25 | Not Detected |
| Methane | 0.00050 | 0.021 |
| Carbon Dioxide | 0.050 | 0.48 |
| Ethane | 0.0050 | Not Detected |
| Ethene | 0.0050 | Not Detected |
| Acetylene | 0.0050 | Not Detected |
| Propane | 0.0050 | Not Detected |
| Isobutane | 0.0050 | 0.00034 J |
| Butane | 0.0050 | 0.0032 J |
| Neopentane | 0.0050 | Not Detected |
| Isopentane | 0.0050 | 0.0015 J |
| Pentane | 0.0050 | 0.00037 J |
| C6+ | 0.050 | 0.00099 J |
| Helium | 0.25 | 0.99 |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

eurofins | Air Toxics

**Client Sample ID: VMP-1-23.5-012113**

**Lab ID#: 1301354BR1-04A**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1945**

| | | | |
|---|---|---|---|
| **File Name:** | **9012216r1** | **Date of Collection:** | **1/21/13 2:28:00 PM** |
| **Dil. Factor:** | **2.69** | **Date of Analysis:** | **1/22/13 03:05 PM** |

| Compound | Rpt. Limit (%) | Amount (%) | |
|---|---|---|---|
| Oxygen | 0.27 | 20 | J |
| Nitrogen | 0.27 | 73 | J |
| Carbon Monoxide | 0.13 | Not Detected | UJ |
| Methane | 0.00027 | 0.0044 | J |
| Carbon Dioxide | 0.027 | 0.39 | J |
| Ethane | 0.0027 | Not Detected | UJ |
| Ethene | 0.0027 | Not Detected | UJ |
| Acetylene | 0.0027 | Not Detected | UJ |
| Propane | 0.0027 | Not Detected | UJ |
| Isobutane | 0.0027 | 0.000086 J | J |
| Butane | 0.0027 | 0.00055 J | J |
| Neopentane | 0.0027 | Not Detected | UJ |
| Isopentane | 0.0027 | 0.00046 J | J |
| Pentane | 0.0027 | 0.00011 J | J |
| C6+ | 0.027 | 0.00045 J | J |
| Helium | 0.13 | 6.2 | J |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

eurofins | Air Toxics

**Client Sample ID: Lab Blank**

**Lab ID#: 1301354BR1-05A**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1945**

| | | | |
|---|---|---|---|
| **File Name:** | **9012214a** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 1/22/13 02:03 PM** | |

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.10 | Not Detected |
| Nitrogen | 0.10 | 0.087 J |
| Carbon Monoxide | 0.050 | Not Detected |
| Methane | 0.00010 | Not Detected |
| Carbon Dioxide | 0.010 | Not Detected |
| Ethane | 0.0010 | Not Detected |
| Ethene | 0.0010 | Not Detected |
| Acetylene | 0.0010 | Not Detected |
| Propane | 0.0010 | Not Detected |
| Isobutane | 0.0010 | Not Detected |
| Butane | 0.0010 | Not Detected |
| Neopentane | 0.0010 | Not Detected |
| Isopentane | 0.0010 | Not Detected |
| Pentane | 0.0010 | Not Detected |
| C6+ | 0.010 | Not Detected |

J = Estimated value.

**Container Type: NA - Not Applicable**

eurofins | Air Toxics

**Client Sample ID: Lab Blank**

**Lab ID#: 1301354BR1-05B**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1946**

| | | | |
|---|---|---|---|
| **File Name:** | **9012213b** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 1/22/13 01:41 PM** | |

| **Compound** | **Rpt. Limit (%)** | **Amount (%)** |
|---|---|---|
| Helium | 0.050 | Not Detected |

**Container Type: NA - Not Applicable**

eurofins | Air Toxics

**Client Sample ID: LCS**

**Lab ID#: 1301354BR1-06A**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1945**

| | | | |
|---|---|---|---|
| **File Name:** | **9012202** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 1/22/13 08:08 AM** | |

| Compound | %Recovery |
|---|---|
| Oxygen | 100 |
| Nitrogen | 100 |
| Carbon Monoxide | 97 |
| Methane | 102 |
| Carbon Dioxide | 101 |
| Ethane | 103 |
| Ethene | 100 |
| Acetylene | 102 |
| Propane | 106 |
| Isobutane | 106 |
| Butane | 104 |
| Neopentane | 105 |
| Isopentane | 104 |
| Pentane | 104 |
| C6+ | 104 |
| Helium | 102 |

**Container Type: NA - Not Applicable**

eurofins | Air Toxics

**Client Sample ID: LCSD**

**Lab ID#: 1301354BR1-06AA**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1945**

| | | | |
|---|---|---|---|
| **File Name:** | **9012224** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 1/22/13 06:43 PM** | |

| Compound | %Recovery |
|---|---|
| Oxygen | 101 |
| Nitrogen | 101 |
| Carbon Monoxide | 96 |
| Methane | 107 |
| Carbon Dioxide | 101 |
| Ethane | 109 |
| Ethene | 105 |
| Acetylene | 107 |
| Propane | 111 |
| Isobutane | 112 |
| Butane | 110 |
| Neopentane | 111 |
| Isopentane | 109 |
| Pentane | 109 |
| C6+ | 109 |
| Helium | 101 |

**Container Type: NA - Not Applicable**

# Shell Oil Products Chain Of Custody Record

URS

Air Toxics LTD.
**Project Name: Roxana Soil Vapor**
**Project # 21562850.04001**
Lab Vendor #

Please Check Appropriate Box: ☑ ENV. SERVICES ☐ MOTIVA RETAIL ☐ SHELL RETAIL ☐ MOTIVA SC&CN ☐ CONSULTANT ☐ LUBES ☐ SHELL PIPELINE ☐ OTHER

Print Bill To Contact Name: Robert Mooshegian

INCIDENT # (ENV SERVICES): 9 7 2 1 6 6 4 0

☐ CHECK IF NO INCIDENT # APPLIES

DATE: 01/21/13

PAGE: 1 of 1

PO #:

SAP #: 3 4 0 0 6 1

SAMPLING COMPANY: URS CORPORATION

LOG CODE:

SITE ADDRESS: Street and City: 900 SOUTH CENTRAL AVE -- ROXANA

State: IL

GLOBAL ID NO.:

ADDRESS: 1001 HIGHLANDS PLAZA DRIVE WEST - SUITE 300; ST. LOUIS, MO 63110

EDF DELIVERABLE TO (Name, Company, Office Location): Elizabeth Kunkel, URS, St. Louis

PHONE NO.: 314-743-4179

E-MAIL: Elizabeth_Kunkel@URSCorp.com

CONSULTANT PROJECT NAME: Roxana Soil Vapor

Laboratory Address: Air Toxics LTD 180 Blue Ravine Road, Suite B, Folsom, CA 95630-4719

M. Currier, E. Arthur, A. Day, B. Lehan

TELEPHONE: 314-429-0100

FAX: 314-429-0462

SEND TO (Contact E-MAIL): Robert.Mooshegian@urs.com

TURNAROUND TIME (CALENDAR DAYS): SAME DAY
☐ STANDARD (14 DAY) ☐ 5 DAYS ☐ 3 DAYS ☐ 2 DAYS ☐ 24 HOURS ☐ RESULTS NEEDED ON WEEKEND

REQUESTED ANALYSIS

☐ 1A - RWQCB REPORT FORMAT ☑ UST AGENCY:

DELIVERABLES: ☐ LEVEL 1 ☐ LEVEL 2 ☐ LEVEL 3 ☑ LEVEL 4 ☐ OTHER (SPECIFY)

☑ SHELL CONTRACT RATE APPLIES
☐ STATE REIMBURSEMENT RATE APPLIES
☐ EDD NOT NEEDED
☑ RECEIPT VERIFICATION REQUESTED

Turn Around Time: ☐ Normal ☑ Rush SAME DAY Specify

*Lab Use Only*
Pressurized by:
Date:
Pressurization Gas: $N_2$ He

| LAB USE ONLY | Field Sample Identification | SAMPLING DATE | SAMPLING TIME | Canister Number | Canister Pressure/Vacuum Initial | Final | Receipt | Final (psi) | Modified TO-15 + Butane & Isopentane | ASTM D-1946 + Helium | ASTM D-1946 | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| [illegible] | VMP-47-20-012113 | 01/21/13 | 1417-1447 | 34141 | -30 | -7 | | | X | X | | | | | |
| [illegible] | VMP-47-30-012113 | 01/21/13 | 1515-1545 | 2035 | -30 | -7.5 | | | X | X | | | | | |
| [illegible] | VMP-1-8.5-012113 | 01/21/13 | 1234-1306 | 3002 | -30 | -8 | | | X | X | | | | | |
| [illegible] | VMP-1-23.5-012113 | 01/21/13 | 1356-1428 | 3997 | -30 | -10 | | | X | X | | | | | |

ADDITIONAL NOTES:

- Same day turn around time
- Report results between MDL and RL
- Level IV ECVP

1/21/13

| | | | |
|---|---|---|---|
| Relinquished by (Signature) | Received by (Signature) FEDEX | Date 1/21/13 | Time 1830 |
| Relinquished by (Signature) | Received by (Signature) | Date 1/22/13 | Time 105 |
| Relinquished by (Signature) | Received by (Signature) | Date | Time |

Custody Seal Intact?
Y N None Temp N/A

05/2/05 Revision

1301354

# Roxana Soil Vapor Quarterly – 1st Quarter 2013 Data Review

**Laboratory SDG: 1301399AR1,BR1**

**Data Reviewer: Elizabeth Kunkel**

**Peer Reviewer: Steve Gragert**

**Date Reviewed: 2/26/2013**

**Guidance: USEPA National Functional Guidelines for Superfund Organic Methods Data Review 2008**

| Sample Identification | Sample Identification |
|---|---|
| VMP-1-5-012313-R | VMP-1-8.5-012313-R |
| VMP-1-23.5-012313-R | VMP-1-38.5-012313-R |
| VMP-47-5-012313-R | VMP-47-10-012313-R |
| VMP-47-20-012313-R | VMP-47-30-012313-R |

## 1.0 Data Package Completeness

*Were all items delivered as specified in the QAPP and COC as appropriate?*

Yes

## 2.0 Laboratory Case Narrative \ Cooler Receipt Form

*Were problems noted in the laboratory case narrative or cooler receipt form?*

Yes, the laboratory case narrative indicated samples VMP-1-5-012313-R, VMP-1-8.5-012313-R, and VMP-47-10-012313-R were diluted and re-analyzed to bring the highest level target analytes within the calibration range of the instrument. Results for the highest level target analytes were reported from the re-analysis diluted runs and the remaining compounds were reported from the original analyses. Samples were diluted due to high levels of target analytes. Although not indicated in the laboratory case narrative, nitrogen was detected in the method blank. The TO-15 LCS recovery for ethanol was outside evaluation criteria. These issues are addressed further in the appropriate sections below. The laboratory report was re-issued to report additional natural gas analytes via ASTM D-1945, and also the top five tentatively identified compounds (TICs) via TO-15.

No issues or discrepancies were noted in the cooler receipt form.

## 3.0 Holding Times

*Were samples extracted/analyzed within applicable limits?*

Yes

## 4.0 Blank Contamination

*Were any analytes detected in the Blanks?*

Yes

| Blank ID | Parameter | Analyte | Concentration/ Amount |
|---|---|---|---|
| 1301399B-09A | Natural gases | Nitrogen | 0.078% |

Analytical data that were reported non-detect or at concentrations greater than five times (5X) the associated blank concentration did not require qualification. No qualification of data was required.

**5.0 Laboratory Control Sample**

*Were LCS recoveries within evaluation criteria?*

No

| LCS/LCSD ID | Parameter | Analyte | LCS/LCSD Recovery | LCS/ LCSD RPD | LCS/LCSD /RPD Criteria |
|---|---|---|---|---|---|
| 1301399A-11A/AA | TO-15 | Ethanol | **133**/118 | 12 | 70-130/25 |

Analytical data reported as non-detect and associated with LCS recoveries above evaluation criteria, indicating a possible high bias, did not require qualification. No qualification of data was required.

**6.0 Surrogate Recoveries**

*Were surrogate recoveries within evaluation criteria?*

Yes

**7.0 Matrix Spike and Matrix Spike Duplicate Recoveries**

*Were MS/MSD samples analyzed as part of this SDG?*

MS/MSD samples are not applicable for vapor samples, due to the inability to spike the samples.

**8.0 Laboratory Duplicate Results**

*Were laboratory duplicate samples collected as part of this SDG?*

No

**9.0 Field Duplicate Results**

*Were field duplicate samples collected as part of this SDG?*

No

**10.0 Sample Dilutions**

*For samples that were diluted and nondetect, were undiluted results also reported?*

Not applicable; analytes were detected in samples that were diluted.

**11.0 Additional Qualifications**

*Were additional qualifications applied?*

No

eurofins | Air Toxics

2/15/2013
Ms. Elizabeth Kunkel
URS Corporation
1001 Highlands Plaza Dr. West
Suite 300
St. Louis MO 63110

Project Name: Roxana Soil Vapor
Project #: 21562850.04001
Workorder #: 1301399AR1

Dear Ms. Elizabeth Kunkel

The following report includes the data for the above referenced project for sample(s) received on 1/24/2013 at Air Toxics Ltd.

The data and associated QC analyzed by Modified TO-15 are compliant with the project requirements or laboratory criteria with the exception of the deviations noted in the attached case narrative.

Thank you for choosing Air Toxics Ltd. for your air analysis needs. Air Toxics Ltd. is committed to providing accurate data of the highest quality. Please feel free to contact the Project Manager: Kelly Buettner at 916-985-1000 if you have any questions regarding the data in this report.

Regards,

Kelly Buettner

Project Manager

Reviewed
on
2/18/2013

eurofins | Air Toxics

# WORK ORDER #: 1301399AR1

Work Order Summary

| | | | |
|---|---|---|---|
| **CLIENT:** | Ms. Elizabeth Kunkel<br>URS Corporation<br>1001 Highlands Plaza Dr. West<br>Suite 300<br>St. Louis, MO 63110 | **BILL TO:** | Accounts Payable Austin<br>URS Corporation<br>P.O. BOX 203970<br>Austin, TX 78720-1088 |
| **PHONE:** | 314-743-4179 | **P.O. #** | 21562735.00013 |
| **FAX:** | | **PROJECT #** | 21562850.04001 Roxana Soil Vapor |
| **DATE RECEIVED:** | 01/24/2013 | **CONTACT:** | Kelly Buettner |
| **DATE COMPLETED:** | 01/23/2013 | | |
| **DATE REISSUED:** | 02/15/2013 | | |

| FRACTION # | NAME | TEST | RECEIPT VAC./PRES. | FINAL PRESSURE |
|---|---|---|---|---|
| 01A | VMP-1-5-012313-R | Modified TO-15 | 4.0 "Hg | 15 psi |
| 01B | VMP-1-5-012313-R | Modified TO-15 | 4.0 "Hg | 15 psi |
| 02A | VMP-1-8.5-012313-R | Modified TO-15 | 4.0 "Hg | 15 psi |
| 02B | VMP-1-8.5-012313-R | Modified TO-15 | 4.0 "Hg | 15 psi |
| 03A | VMP-1-23.5-012313-R | Modified TO-15 | 6.5 "Hg | 15 psi |
| 04A | VMP-1-38.5-012313-R | Modified TO-15 | 4.5 "Hg | 15 psi |
| 05A | VMP-47-5-012313-R | Modified TO-15 | 5.0 "Hg | 15 psi |
| 06A | VMP-47-10-012313-R | Modified TO-15 | 5.0 "Hg | 15 psi |
| 06B | VMP-47-10-012313-R | Modified TO-15 | 5.0 "Hg | 15 psi |
| 07A | VMP-47-20-012313-R | Modified TO-15 | 4.5 "Hg | 15 psi |
| 08A | VMP-47-30-012313-R | Modified TO-15 | 4.5 "Hg | 15 psi |
| 09A | Lab Blank | Modified TO-15 | NA | NA |
| 10A | CCV | Modified TO-15 | NA | NA |
| 11A | LCS | Modified TO-15 | NA | NA |
| 11AA | LCSD | Modified TO-15 | NA | NA |

CERTIFIED BY: Heidi Hayes DATE: 02/15/13

Technical Director

Certification numbers: AZ Licensure AZ0775, CA NELAP - 12282CA, NY NELAP - 11291,
TX NELAP - T104704434-12-4, UT NELAP CA009332012-3, WA NELAP - C935
Name of Accrediting Agency: NELAP/ORELAP (Oregon Environmental Laboratory Accreditation Program)
Accreditation number: CA300005, Effective date: 10/18/2012, Expiration date: 10/17/2013.
Eurofins Air Toxics Ltd. certifies that the test results contained in this report meet all requirements of the NELAC standards

This report shall not be reproduced, except in full, without the written approval of Eurofins Air Toxics, Inc

**LABORATORY NARRATIVE**
**EPA Method TO-15**
**URS Corporation**
**Workorder# 1301399AR1**

Eight 1 Liter Summa Canister samples were received on January 24, 2013. The laboratory performed analysis via EPA Method TO-15 using GC/MS in the full scan mode.

This workorder was independently validated prior to submittal using 'USEPA National Functional Guidelines' as generally applied to the analysis of volatile organic compounds in air. A rules-based, logic driven, independent validation engine was employed to assess completeness, evaluate pass/fail of relevant project quality control requirements and verification of all quantified amounts.

**Receiving Notes**

There were no receiving discrepancies.

**Analytical Notes**

All Quality Control Limit exceedances and affected sample results are noted by flags. Each flag is defined at the bottom of this Case Narrative and on each Sample Result Summary page.

As per client project requirements, the laboratory has reported estimated values for target compound hits that are below the Reporting Limit but greater than the Method Detection Limit. Concentrations that are below the level at which the canister was certified (0.2 ppbv for compounds reported at 0.5 ppbv and 0.8 ppbv for compounds reported at 2.0 ppbv) may be false positives.

Dilution was performed on samples VMP-1-5-012313-R, VMP-1-5-012313-R, VMP-1-8.5-012313-R, VMP-1-8.5-012313-R, VMP-1-23.5-012313-R, VMP-1-38.5-012313-R, VMP-47-5-012313-R, VMP-47-10-012313-R, VMP-47-10-012313-R, VMP-47-20-012313-R and VMP-47-30-012313-R due to the presence of high level target species.

Due to high-level target compounds, samples VMP-1-5-012313-R, VMP-1-8.5-012313-R and VMP-47-10-012313-R were analyzed twice. In the "A" fraction, the sample was diluted to bring the highest-level compounds within the calibration range. The "B" fraction is also reported by client request and may be reported with "E" flags indicating the compound exceeds the calibration range. Both runs and associated QC are reported.

THE WORKORDER WAS REISSUED ON FEBRUARY 15, 2013 TO REPORT THE TOP 5 TENTATIVELY IDENTIFIED COMPOUNDS PER CLIENT'S REQUEST.

**Definition of Data Qualifying Flags**

Eight qualifiers may have been used on the data analysis sheets and indicates as follows:

B - Compound present in laboratory blank greater than reporting limit (background subtraction not performed).

J - Estimated value.

E - Exceeds instrument calibration range.

S - Saturated peak.
Q - Exceeds quality control limits.
U - Compound analyzed for but not detected above the reporting limit.
UJ- Non-detected compound associated with low bias in the CCV
N - The identification is based on presumptive evidence.

File extensions may have been used on the data analysis sheets and indicates as follows:
a-File was requantified
b-File was quantified by a second column and detector
r1-File was requantified for the purpose of reissue

eurofins | Air Toxics

# Summary of Detected Compounds
# EPA METHOD TO-15 GC/MS

**Client Sample ID: VMP-1-5-012313-R** * Use these results only. All other data was reported from the 2.33X dilution analysis.

**Lab ID#: 1301399AR1-01A**

DF = 932

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Hexane | 4700 | 32000 | 16000 | 110000 |
| Cyclohexane | 4700 | 7500 | 16000 | 26000 |
| 2,2,4-Trimethylpentane | 4700 | 21000 | 22000 | 98000 |
| Heptane | 4700 | 3800 J | 19000 | 15000 J |
| Toluene | 4700 | 730 J | 18000 | 2700 J |
| m,p-Xylene | 4700 | 1000 J | 20000 | 4500 J |
| * Butane | 19000 | 2500000 | 44000 | 5900000 |
| Isopentane | 19000 | 880000 | 55000 | 2600000 |

**TENTATIVELY IDENTIFIED COMPOUNDS**

| Compound | CAS Number | Match Quality | Amount (ppbv) |
|---|---|---|---|
| Propane, 2-methyl- | | | 240000 NJ |
| Pentane | | | 340000 NJ |
| Pentane, 2-methyl- | | | 300000 NJ |
| Pentane, 2,2,3-trimethyl- | | | 140000 NJ |
| Cyclobutane, ethyl- | | | 70000 NJ |

**Client Sample ID: VMP-1-5-012313-R** ** Do not use this data. Use all other data.

**Lab ID#: 1301399AR1-01B**

DF = 2.33

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Hexane | 1200 | 38000 | 4100 | 130000 |
| Cyclohexane | 1200 | 9500 | 4000 | 33000 |
| 2,2,4-Trimethylpentane | 1200 | 29000 | 5400 | 140000 |
| Benzene | 1200 | 1500 | 3700 | 4700 |
| Heptane | 1200 | 6200 | 4800 | 25000 |
| Toluene | 1200 | 1100 J | 4400 | 4000 J |
| Ethyl Benzene | 1200 | 350 J | 5000 | 1500 J |
| m,p-Xylene | 1200 | 910 J | 5000 | 3900 J |
| o-Xylene | 1200 | 420 J | 5000 | 1800 J |
| 4-Ethyltoluene | 1200 | 380 J | 5700 | 1900 J |
| 1,2,4-Trimethylbenzene | 1200 | 460 J | 5700 | 2300 J |
| ~~** Butane~~ | ~~4700~~ | ~~2800000 E~~ | ~~11000~~ | ~~6600000 E~~ |

eurofins | Air Toxics

# Summary of Detected Compounds
# EPA METHOD TO-15 GC/MS

**Client Sample ID: VMP-1-5-012313-R**

**Lab ID#: 1301399AR1-01B**

| | | | | |
|---|---|---|---|---|
| Isopentane | 4700 | 870000 | 14000 | 2600000 |

**TENTATIVELY IDENTIFIED COMPOUNDS**

| Compound | CAS Number | Match Quality | Amount (ppbv) |
|---|---|---|---|
| Propane, 2-methyl- | | | 240000 NJ |
| Pentane | | | 340000 NJ |
| Pentane, 2-methyl- | | | 320000 NJ |
| Butane, 2,2,3-trimethyl- | | | 150000 NJ |
| Cyclobutane, ethyl- | | | 85000 NJ |

**Client Sample ID: VMP-1-8.5-012313-R** * Use these results only. All other data was reported from the 4.66X dilution analysis.

**Lab ID#: 1301399AR1-02A** DF= 29.1

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Hexane | 140 | 1300 | 510 | 4800 |
| Cyclohexane | 140 | 390 | 500 | 1300 |
| 2,2,4-Trimethylpentane | 140 | 1000 | 680 | 4900 |
| Benzene | 140 | 63 J | 460 | 200 J |
| Heptane | 140 | 240 | 600 | 990 |
| Toluene | 140 | 100 J | 550 | 380 J |
| m,p-Xylene | 140 | 70 J | 630 | 300 J |
| o-Xylene | 140 | 29 J | 630 | 130 J |
| * Butane | 580 | 110000 | 1400 | 260000 |
| Isopentane | 580 | 33000 | 1700 | 99000 |

**TENTATIVELY IDENTIFIED COMPOUNDS**

| Compound | CAS Number | Match Quality | Amount (ppbv) |
|---|---|---|---|
| Propane, 2-methyl- | | | 9200 NJ |
| Pentane | | | 13000 NJ |
| Pentane, 2-methyl- | | | 12000 NJ |
| Pentane, 2,2,3-trimethyl- | | | 5800 NJ |
| Cyclobutane, ethyl- | | | 3400 NJ |

**Client Sample ID: VMP-1-8.5-012313-R**

**Lab ID#: 1301399AR1-02B**

eurofins | Air Toxics

# Summary of Detected Compounds
# EPA METHOD TO-15 GC/MS

**Client Sample ID: VMP-1-8.5-012313-R** ** Do not use this data. Use all other data.

**Lab ID#: 1301399AR1-02B**

DF = 4.66

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Hexane | 23 | 1500 | 82 | 5400 |
| Cyclohexane | 23 | 400 | 80 | 1400 |
| 2,2,4-Trimethylpentane | 23 | 990 | 110 | 4600 |
| Benzene | 23 | 16 J | 74 | 50 J |
| Heptane | 23 | 230 | 95 | 960 |
| Toluene | 23 | 4.7 J | 88 | 18 J |
| m,p-Xylene | 23 | 9.0 J | 100 | 39 J |
| o-Xylene | 23 | 4.9 J | 100 | 21 J |
| ~~Butane~~ ** | ~~93~~ | ~~98000 E~~ | ~~220~~ | ~~230000 E~~ |
| ~~Isopentane~~ ** | ~~93~~ | ~~37000 E~~ | ~~280~~ | ~~110000 E~~ |

**TENTATIVELY IDENTIFIED COMPOUNDS**

| Compound | CAS Number | Match Quality | Amount (ppbv) |
|---|---|---|---|
| Propane, 2-methyl- | | | 11000 NJ |
| Pentane | | | 15000 NJ |
| Pentane, 2-methyl- | | | 13000 NJ |
| Pentane, 2,2,3-trimethyl- | | | 5900 NJ |
| Cyclobutane, ethyl- | | | 3200 NJ |

**Client Sample ID: VMP-1-23.5-012313-R**

**Lab ID#: 1301399AR1-03A**

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Hexane | 16000 | 140000 | 57000 | 510000 |
| Cyclohexane | 16000 | 48000 | 55000 | 160000 |
| 2,2,4-Trimethylpentane | 16000 | 170000 | 75000 | 790000 |
| Benzene | 16000 | 4400 J | 51000 | 14000 J |
| Heptane | 16000 | 20000 | 66000 | 84000 |
| Toluene | 16000 | 7100 J | 61000 | 27000 J |
| m,p-Xylene | 16000 | 5300 J | 70000 | 23000 J |
| Butane | 64000 | 14000000 | 150000 | 33000000 |
| Isopentane | 64000 | 5000000 | 190000 | 15000000 |

eurofins | Air Toxics

# Summary of Detected Compounds
# EPA METHOD TO-15 GC/MS

**Client Sample ID: VMP-1-23.5-012313-R**

**Lab ID#: 1301399AR1-03A**

TENTATIVELY IDENTIFIED COMPOUNDS

| Compound | CAS Number | Match Quality | Amount (ppbv) |
|---|---|---|---|
| Propane, 2-methyl- | | | 1300000 NJ |
| Pentane | | | 1600000 NJ |
| Pentane, 2-methyl- | | | 1800000 NJ |
| Pentane, 3-methyl- | | | 870000 NJ |
| Cyclobutane, ethyl- | | | 450000 NJ |

**Client Sample ID: VMP-1-38.5-012313-R**

**Lab ID#: 1301399AR1-04A**

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Hexane | 12000 | 110000 | 42000 | 390000 |
| Cyclohexane | 12000 | 27000 | 41000 | 94000 |
| 2,2,4-Trimethylpentane | 12000 | 84000 | 56000 | 390000 |
| Benzene | 12000 | 3600 J | 38000 | 11000 J |
| Heptane | 12000 | 17000 | 49000 | 69000 |
| Toluene | 12000 | 6000 J | 45000 | 22000 J |
| m,p-Xylene | 12000 | 3800 J | 52000 | 16000 J |
| o-Xylene | 12000 | 1700 J | 52000 | 7200 J |
| Butane | 48000 | 8900000 | 110000 | 21000000 |
| Isopentane | 48000 | 2800000 | 140000 | 8200000 |

TENTATIVELY IDENTIFIED COMPOUNDS

| Compound | CAS Number | Match Quality | Amount (ppbv) |
|---|---|---|---|
| Propane, 2-methyl- | | | 760000 NJ |
| Pentane | | | 1000000 NJ |
| Pentane, 2-methyl- | | | 970000 NJ |
| Butane, 2,2,3-trimethyl- | | | 460000 NJ |
| Cyclopentane, methyl- | | | 250000 NJ |

**Client Sample ID: VMP-47-5-012313-R**

**Lab ID#: 1301399AR1-05A**

eurofins | Air Toxics

# Summary of Detected Compounds
# EPA METHOD TO-15 GC/MS

**Client Sample ID: VMP-47-5-012313-R**

**Lab ID#: 1301399AR1-05A**

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Cyclohexane | 4800 | 9700 | 17000 | 33000 |
| 2,2,4-Trimethylpentane | 4800 | 92000 | 23000 | 430000 |
| Butane | 19000 | 2000000 | 46000 | 4900000 |
| Isopentane | 19000 | 1600000 | 57000 | 4700000 |

**TENTATIVELY IDENTIFIED COMPOUNDS**

| Compound | CAS Number | Match Quality | Amount (ppbv) |
|---|---|---|---|
| Propane, 2-methyl- | | | 470000 NJ |
| Pentane | | | 230000 NJ |
| Pentane, 2-methyl- | | | 620000 NJ |
| Hexane, 3,4-dimethyl- | | | 310000 NJ |
| Pentane, 2,3-dimethyl- | | | 370000 NJ |

**Client Sample ID: VMP-47-10-012313-R** * Use these results only. All other data was reported from the 24.2x dilution analysis

**Lab ID#: 1301399AR1-06A** DF = 48.4

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Hexane | 240 | 540 | 850 | 1900 |
| Cyclohexane | 240 | 990 | 830 | 3400 |
| 2,2,4-Trimethylpentane | 240 | 23000 | 1100 | 100000 |
| Benzene | 240 | 49 J | 770 | 160 J |
| Toluene | 240 | 87 J | 910 | 330 J |
| m,p-Xylene | 240 | 69 J | 1000 | 300 J |
| Butane | 970 | 190000 | 2300 | 460000 |
| Isopentane | 970 | 190000 | 2800 | 560000 |

**TENTATIVELY IDENTIFIED COMPOUNDS**

| Compound | CAS Number | Match Quality | Amount (ppbv) |
|---|---|---|---|
| Propane, 2-methyl- | | | 65000 NJ |
| Pentane, 2-methyl- | | | 80000 NJ |
| Pentane, 3-methyl- | | | 34000 NJ |
| Pentane, 2,4-dimethyl- | | | 28000 NJ |
| Pentane, 2,3-dimethyl- | | | 44000 NJ |

eurofins | Air Toxics

# Summary of Detected Compounds
# EPA METHOD TO-15 GC/MS

**Client Sample ID: VMP-47-10-012313-R** Do not use this data. Use all other data.

**Lab ID#: 1301399AR1-06B**

DF = 24.2

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Hexane | 120 | 490 | 430 | 1700 |
| Cyclohexane | 120 | 1000 | 420 | 3500 |
| 2,2,4-Trimethylpentane | 120 | 22000 | 560 | 100000 |
| Benzene | 120 | 35 J | 390 | 110 J |
| Toluene | 120 | 52 J | 460 | 190 J |
| m,p-Xylene | 120 | 44 J | 520 | 190 J |
| ~~Butane~~ | ~~480~~ | ~~180000 E~~ | ~~1200~~ | ~~430000 E~~ |
| ~~Isopentane~~ | ~~480~~ | ~~180000 E~~ | ~~1400~~ | ~~530000 E~~ |

**TENTATIVELY IDENTIFIED COMPOUNDS**

| Compound | CAS Number | Match Quality | Amount (ppbv) |
|---|---|---|---|
| Propane, 2-methyl- | | | 56000 NJ |
| Pentane, 2-methyl- | | | 75000 NJ |
| Pentane, 3-methyl- | | | 31000 NJ |
| Pentane, 2,4-dimethyl- | | | 27000 NJ |
| Pentane, 2,3-dimethyl- | | | 42000 NJ |

**Client Sample ID: VMP-47-20-012313-R**

**Lab ID#: 1301399AR1-07A**

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Hexane | 3000 | 5600 | 10000 | 20000 |
| Cyclohexane | 3000 | 7900 | 10000 | 27000 |
| 2,2,4-Trimethylpentane | 3000 | 73000 | 14000 | 340000 |
| Butane | 12000 | 1700000 | 28000 | 4100000 |
| Isopentane | 12000 | 1200000 | 35000 | 3500000 |

**TENTATIVELY IDENTIFIED COMPOUNDS**

| Compound | CAS Number | Match Quality | Amount (ppbv) |
|---|---|---|---|
| Propane, 2-methyl- | | | 360000 NJ |
| Pentane | | | 210000 NJ |
| Pentane, 2-methyl- | | | 470000 NJ |
| Pentane, 3-methyl- | | | 240000 NJ |

eurofins | Air Toxics

# Summary of Detected Compounds
# EPA METHOD TO-15 GC/MS

**Client Sample ID: VMP-47-20-012313-R**

**Lab ID#: 1301399AR1-07A**

TENTATIVELY IDENTIFIED COMPOUNDS

| Compound | CAS Number | Match Quality | Amount (ppbv) |
|---|---|---|---|
| Pentane, 2,3-dimethyl- | | | 300000 NJ |

**Client Sample ID: VMP-47-30-012313-R**

**Lab ID#: 1301399AR1-08A**

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Cyclohexane | 4800 | 9600 | 16000 | 33000 |
| 2,2,4-Trimethylpentane | 4800 | 93000 | 22000 | 430000 |
| Butane | 19000 | 2000000 | 45000 | 4800000 |
| Isopentane | 19000 | 1600000 | 56000 | 4600000 |

TENTATIVELY IDENTIFIED COMPOUNDS

| Compound | CAS Number | Match Quality | Amount (ppbv) |
|---|---|---|---|
| Propane, 2-methyl- | | | 460000 NJ |
| Pentane | | | 230000 NJ |
| Pentane, 2-methyl- | | | 600000 NJ |
| Pentane, 3-methyl- | | | 290000 NJ |
| Pentane, 2,3-dimethyl- | | | 370000 NJ |

eurofins | Air Toxics

**Client Sample ID: VMP-1-5-012313-R** * Use these results only. All other data was reported from the 233X dilution analysis.
**Lab ID#: 1301399AR1-01A**
**EPA METHOD TO-15 GC/MS**

| | | | |
|---|---|---|---|
| **File Name:** | **14012330r1** | **Date of Collection:** | **1/23/13 11:40:00 AM** |
| **Dil. Factor:** | **932** | **Date of Analysis:** | **1/24/13 08:43 PM** |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 4700 | Not Detected | 23000 | Not Detected |
| Freon 114 | 4700 | Not Detected | 32000 | Not Detected |
| Chloromethane | 19000 | Not Detected | 38000 | Not Detected |
| Vinyl Chloride | 4700 | Not Detected | 12000 | Not Detected |
| 1,3-Butadiene | 4700 | Not Detected | 10000 | Not Detected |
| Bromomethane | 4700 | Not Detected | 18000 | Not Detected |
| Chloroethane | 19000 | Not Detected | 49000 | Not Detected |
| Freon 11 | 4700 | Not Detected | 26000 | Not Detected |
| Ethanol | 19000 | Not Detected | 35000 | Not Detected |
| Freon 113 | 4700 | Not Detected | 36000 | Not Detected |
| 1,1-Dichloroethene | 4700 | Not Detected | 18000 | Not Detected |
| Acetone | 19000 | Not Detected | 44000 | Not Detected |
| 2-Propanol | 19000 | Not Detected | 46000 | Not Detected |
| Carbon Disulfide | 4700 | Not Detected | 14000 | Not Detected |
| 3-Chloropropene | 19000 | Not Detected | 58000 | Not Detected |
| Methylene Chloride | 4700 | Not Detected | 16000 | Not Detected |
| Methyl tert-butyl ether | 4700 | Not Detected | 17000 | Not Detected |
| trans-1,2-Dichloroethene | 4700 | Not Detected | 18000 | Not Detected |
| Hexane | 4700 | 32000 | 16000 | 110000 |
| 1,1-Dichloroethane | 4700 | Not Detected | 19000 | Not Detected |
| 2-Butanone (Methyl Ethyl Ketone) | 19000 | Not Detected | 55000 | Not Detected |
| cis-1,2-Dichloroethene | 4700 | Not Detected | 18000 | Not Detected |
| Tetrahydrofuran | 4700 | Not Detected | 14000 | Not Detected |
| Chloroform | 4700 | Not Detected | 23000 | Not Detected |
| 1,1,1-Trichloroethane | 4700 | Not Detected | 25000 | Not Detected |
| Cyclohexane | 4700 | 7500 | 16000 | 26000 |
| Carbon Tetrachloride | 4700 | Not Detected | 29000 | Not Detected |
| 2,2,4-Trimethylpentane | 4700 | 21000 | 22000 | 98000 |
| Benzene | 4700 | Not Detected | 15000 | Not Detected |
| 1,2-Dichloroethane | 4700 | Not Detected | 19000 | Not Detected |
| Heptane | 4700 | 3800 J | 19000 | 15000 J |
| Trichloroethene | 4700 | Not Detected | 25000 | Not Detected |
| 1,2-Dichloropropane | 4700 | Not Detected | 22000 | Not Detected |
| 1,4-Dioxane | 19000 | Not Detected | 67000 | Not Detected |
| Bromodichloromethane | 4700 | Not Detected | 31000 | Not Detected |
| cis-1,3-Dichloropropene | 4700 | Not Detected | 21000 | Not Detected |
| 4-Methyl-2-pentanone | 4700 | Not Detected | 19000 | Not Detected |
| Toluene | 4700 | 730 J | 18000 | 2700 J |
| trans-1,3-Dichloropropene | 4700 | Not Detected | 21000 | Not Detected |
| 1,1,2-Trichloroethane | 4700 | Not Detected | 25000 | Not Detected |
| Tetrachloroethene | 4700 | Not Detected | 32000 | Not Detected |
| 2-Hexanone | 19000 | Not Detected | 76000 | Not Detected |

eurofins | Air Toxics

**Client Sample ID: VMP-1-5-012313-R**
**Lab ID#: 1301399AR1-01A**
**EPA METHOD TO-15 GC/MS**

| | | | |
|---|---|---|---|
| **File Name:** | **14012330r1** | **Date of Collection:** | **1/23/13 11:40:00 AM** |
| **Dil. Factor:** | **932** | **Date of Analysis:** | **1/24/13 08:43 PM** |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Dibromochloromethane | 4700 | Not Detected | 40000 | Not Detected |
| 1,2-Dibromoethane (EDB) | 4700 | Not Detected | 36000 | Not Detected |
| Chlorobenzene | 4700 | Not Detected | 21000 | Not Detected |
| Ethyl Benzene | 4700 | Not Detected | 20000 | Not Detected |
| m,p-Xylene | 4700 | 1000 J | 20000 | 4500 J |
| o-Xylene | 4700 | Not Detected | 20000 | Not Detected |
| Styrene | 4700 | Not Detected | 20000 | Not Detected |
| Bromoform | 4700 | Not Detected | 48000 | Not Detected |
| Cumene | 4700 | Not Detected | 23000 | Not Detected |
| 1,1,2,2-Tetrachloroethane | 4700 | Not Detected | 32000 | Not Detected |
| Propylbenzene | 4700 | Not Detected | 23000 | Not Detected |
| 4-Ethyltoluene | 4700 | Not Detected | 23000 | Not Detected |
| 1,3,5-Trimethylbenzene | 4700 | Not Detected | 23000 | Not Detected |
| 1,2,4-Trimethylbenzene | 4700 | Not Detected | 23000 | Not Detected |
| 1,3-Dichlorobenzene | 4700 | Not Detected | 28000 | Not Detected |
| 1,4-Dichlorobenzene | 4700 | Not Detected | 28000 | Not Detected |
| alpha-Chlorotoluene | 4700 | Not Detected | 24000 | Not Detected |
| 1,2-Dichlorobenzene | 4700 | Not Detected | 28000 | Not Detected |
| 1,2,4-Trichlorobenzene | 19000 | Not Detected | 140000 | Not Detected |
| Hexachlorobutadiene | 19000 | Not Detected | 200000 | Not Detected |
| Butane | 19000 | 2500000 | 44000 | 5900000 |
| Isopentane | 19000 | 880000 | 55000 | 2600000 |

J = Estimated value.

**TENTATIVELY IDENTIFIED COMPOUNDS**

| Compound | CAS Number | Match Quality | Amount ((ppbv)) |
|---|---|---|---|
| Propane, 2-methyl- | | | 570000 NJ |
| Pentane | | | 990000 NJ |
| Pentane, 2-methyl- | | | 1100000 NJ |
| Pentane, 2,2,3-trimethyl- | | | 670000 NJ |
| Cyclobutane, ethyl- | | | 0 NJ |

NJ =The identification is based on presumptive evidence; estimated value.

**Container Type: 1 Liter Summa Canister**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| 1,2-Dichloroethane-d4 | 107 | 70-130 |
| Toluene-d8 | 98 | 70-130 |
| 4-Bromofluorobenzene | 100 | 70-130 |

eurofins | Air Toxics

**Client Sample ID: VMP-1-5-012313-R** ** Do not use this data. Use all other data.
**Lab ID#: 1301399AR1-01B**
**EPA METHOD TO-15 GC/MS**

| | | | |
|---|---|---|---|
| **File Name:** | **14012310r1** | **Date of Collection:** | **1/23/13 11:40:00 AM** |
| **Dil. Factor:** | **233** | **Date of Analysis:** | **1/24/13 10:54 AM** |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 1200 | Not Detected | 5800 | Not Detected |
| Freon 114 | 1200 | Not Detected | 8100 | Not Detected |
| Chloromethane | 4700 | Not Detected | 9600 | Not Detected |
| Vinyl Chloride | 1200 | Not Detected | 3000 | Not Detected |
| 1,3-Butadiene | 1200 | Not Detected | 2600 | Not Detected |
| Bromomethane | 1200 | Not Detected | 4500 | Not Detected |
| Chloroethane | 4700 | Not Detected | 12000 | Not Detected |
| Freon 11 | 1200 | Not Detected | 6500 | Not Detected |
| Ethanol | 4700 | Not Detected | 8800 | Not Detected |
| Freon 113 | 1200 | Not Detected | 8900 | Not Detected |
| 1,1-Dichloroethene | 1200 | Not Detected | 4600 | Not Detected |
| Acetone | 4700 | Not Detected | 11000 | Not Detected |
| 2-Propanol | 4700 | Not Detected | 11000 | Not Detected |
| Carbon Disulfide | 1200 | Not Detected | 3600 | Not Detected |
| 3-Chloropropene | 4700 | Not Detected | 14000 | Not Detected |
| Methylene Chloride | 1200 | Not Detected | 4000 | Not Detected |
| Methyl tert-butyl ether | 1200 | Not Detected | 4200 | Not Detected |
| trans-1,2-Dichloroethene | 1200 | Not Detected | 4600 | Not Detected |
| Hexane | 1200 | 38000 | 4100 | 130000 |
| 1,1-Dichloroethane | 1200 | Not Detected | 4700 | Not Detected |
| 2-Butanone (Methyl Ethyl Ketone) | 4700 | Not Detected | 14000 | Not Detected |
| cis-1,2-Dichloroethene | 1200 | Not Detected | 4600 | Not Detected |
| Tetrahydrofuran | 1200 | Not Detected | 3400 | Not Detected |
| Chloroform | 1200 | Not Detected | 5700 | Not Detected |
| 1,1,1-Trichloroethane | 1200 | Not Detected | 6400 | Not Detected |
| Cyclohexane | 1200 | 9500 | 4000 | 33000 |
| Carbon Tetrachloride | 1200 | Not Detected | 7300 | Not Detected |
| 2,2,4-Trimethylpentane | 1200 | 29000 | 5400 | 140000 |
| Benzene | 1200 | 1500 | 3700 | 4700 |
| 1,2-Dichloroethane | 1200 | Not Detected | 4700 | Not Detected |
| Heptane | 1200 | 6200 | 4800 | 25000 |
| Trichloroethene | 1200 | Not Detected | 6300 | Not Detected |
| 1,2-Dichloropropane | 1200 | Not Detected | 5400 | Not Detected |
| 1,4-Dioxane | 4700 | Not Detected | 17000 | Not Detected |
| Bromodichloromethane | 1200 | Not Detected | 7800 | Not Detected |
| cis-1,3-Dichloropropene | 1200 | Not Detected | 5300 | Not Detected |
| 4-Methyl-2-pentanone | 1200 | Not Detected | 4800 | Not Detected |
| Toluene | 1200 | 1100 J | 4400 | 4000 J |
| trans-1,3-Dichloropropene | 1200 | Not Detected | 5300 | Not Detected |
| 1,1,2-Trichloroethane | 1200 | Not Detected | 6400 | Not Detected |
| Tetrachloroethene | 1200 | Not Detected | 7900 | Not Detected |
| 2-Hexanone | 4700 | Not Detected | 19000 | Not Detected |

**Client Sample ID: VMP-1-5-012313-R**

**Lab ID#: 1301399AR1-01B**

**EPA METHOD TO-15 GC/MS**

| | | | |
|---|---|---|---|
| **File Name:** | **14012310r1** | **Date of Collection:** | **1/23/13 11:40:00 AM** |
| **Dil. Factor:** | **233** | **Date of Analysis:** | **1/24/13 10:54 AM** |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Dibromochloromethane | 1200 | Not Detected | 9900 | Not Detected |
| 1,2-Dibromoethane (EDB) | 1200 | Not Detected | 9000 | Not Detected |
| Chlorobenzene | 1200 | Not Detected | 5400 | Not Detected |
| Ethyl Benzene | 1200 | 350 J | 5000 | 1500 J |
| m,p-Xylene | 1200 | 910 J | 5000 | 3900 J |
| o-Xylene | 1200 | 420 J | 5000 | 1800 J |
| Styrene | 1200 | Not Detected | 5000 | Not Detected |
| Bromoform | 1200 | Not Detected | 12000 | Not Detected |
| Cumene | 1200 | Not Detected | 5700 | Not Detected |
| 1,1,2,2-Tetrachloroethane | 1200 | Not Detected | 8000 | Not Detected |
| Propylbenzene | 1200 | Not Detected | 5700 | Not Detected |
| 4-Ethyltoluene | 1200 | 380 J | 5700 | 1900 J |
| 1,3,5-Trimethylbenzene | 1200 | Not Detected | 5700 | Not Detected |
| 1,2,4-Trimethylbenzene | 1200 | 460 J | 5700 | 2300 J |
| 1,3-Dichlorobenzene | 1200 | Not Detected | 7000 | Not Detected |
| 1,4-Dichlorobenzene | 1200 | Not Detected | 7000 | Not Detected |
| alpha-Chlorotoluene | 1200 | Not Detected | 6000 | Not Detected |
| 1,2-Dichlorobenzene | 1200 | Not Detected | 7000 | Not Detected |
| 1,2,4-Trichlorobenzene | 4700 | Not Detected | 34000 | Not Detected |
| Hexachlorobutadiene | 4700 | Not Detected | 50000 | Not Detected |
| ~~Butane~~ | ~~4700~~ | ~~2800000 E~~ | ~~11000~~ | ~~6600000 E~~ |
| Isopentane | 4700 | 870000 | 14000 | 2600000 |

J = Estimated value.
E = Exceeds instrument calibration range.

**TENTATIVELY IDENTIFIED COMPOUNDS**

| Compound | CAS Number | Match Quality | Amount ((ppbv)) |
|---|---|---|---|
| Propane, 2-methyl- | | | 560000 NJ |
| Pentane | | | 990000 NJ |
| Pentane, 2-methyl- | | | 1100000 NJ |
| Butane, 2,2,3-trimethyl- | | | 0 NJ |
| Cyclobutane, ethyl- | | | 0 NJ |

NJ =The identification is based on presumptive evidence; estimated value.

**Container Type: 1 Liter Summa Canister**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| 1,2-Dichloroethane-d4 | 106 | 70-130 |
| Toluene-d8 | 99 | 70-130 |
| 4-Bromofluorobenzene | 99 | 70-130 |

eurofins | Air Toxics

**Client Sample ID: VMP-1-8.5-012313-R** * Use these results
**Lab ID#: 1301399AR1-02A** only. All other data was
**EPA METHOD TO-15 GC/MS** reported from the 4.66X dilution analysis.

| | | | |
|---|---|---|---|
| **File Name:** | **14012315r1** | **Date of Collection:** | **1/23/13 11:45:00 AM** |
| **Dil. Factor:** | **29.1** | **Date of Analysis:** | **1/24/13 01:53 PM** |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 140 | Not Detected | 720 | Not Detected |
| Freon 114 | 140 | Not Detected | 1000 | Not Detected |
| Chloromethane | 580 | Not Detected | 1200 | Not Detected |
| Vinyl Chloride | 140 | Not Detected | 370 | Not Detected |
| 1,3-Butadiene | 140 | Not Detected | 320 | Not Detected |
| Bromomethane | 140 | Not Detected | 560 | Not Detected |
| Chloroethane | 580 | Not Detected | 1500 | Not Detected |
| Freon 11 | 140 | Not Detected | 820 | Not Detected |
| Ethanol | 580 | Not Detected | 1100 | Not Detected |
| Freon 113 | 140 | Not Detected | 1100 | Not Detected |
| 1,1-Dichloroethene | 140 | Not Detected | 580 | Not Detected |
| Acetone | 580 | Not Detected | 1400 | Not Detected |
| 2-Propanol | 580 | Not Detected | 1400 | Not Detected |
| Carbon Disulfide | 140 | Not Detected | 450 | Not Detected |
| 3-Chloropropene | 580 | Not Detected | 1800 | Not Detected |
| Methylene Chloride | 140 | Not Detected | 500 | Not Detected |
| Methyl tert-butyl ether | 140 | Not Detected | 520 | Not Detected |
| trans-1,2-Dichloroethene | 140 | Not Detected | 580 | Not Detected |
| Hexane | 140 | 1300 | 510 | 4800 |
| 1,1-Dichloroethane | 140 | Not Detected | 590 | Not Detected |
| 2-Butanone (Methyl Ethyl Ketone) | 580 | Not Detected | 1700 | Not Detected |
| cis-1,2-Dichloroethene | 140 | Not Detected | 580 | Not Detected |
| Tetrahydrofuran | 140 | Not Detected | 430 | Not Detected |
| Chloroform | 140 | Not Detected | 710 | Not Detected |
| 1,1,1-Trichloroethane | 140 | Not Detected | 790 | Not Detected |
| Cyclohexane | 140 | 390 | 500 | 1300 |
| Carbon Tetrachloride | 140 | Not Detected | 920 | Not Detected |
| 2,2,4-Trimethylpentane | 140 | 1000 | 680 | 4900 |
| Benzene | 140 | 63 J | 460 | 200 J |
| 1,2-Dichloroethane | 140 | Not Detected | 590 | Not Detected |
| Heptane | 140 | 240 | 600 | 990 |
| Trichloroethene | 140 | Not Detected | 780 | Not Detected |
| 1,2-Dichloropropane | 140 | Not Detected | 670 | Not Detected |
| 1,4-Dioxane | 580 | Not Detected | 2100 | Not Detected |
| Bromodichloromethane | 140 | Not Detected | 970 | Not Detected |
| cis-1,3-Dichloropropene | 140 | Not Detected | 660 | Not Detected |
| 4-Methyl-2-pentanone | 140 | Not Detected | 600 | Not Detected |
| Toluene | 140 | 100 J | 550 | 380 J |
| trans-1,3-Dichloropropene | 140 | Not Detected | 660 | Not Detected |
| 1,1,2-Trichloroethane | 140 | Not Detected | 790 | Not Detected |
| Tetrachloroethene | 140 | Not Detected | 990 | Not Detected |
| 2-Hexanone | 580 | Not Detected | 2400 | Not Detected |

**Client Sample ID: VMP-1-8.5-012313-R**

**Lab ID#: 1301399AR1-02A**

**EPA METHOD TO-15 GC/MS**

| | | | |
|---|---|---|---|
| **File Name:** | **14012315r1** | **Date of Collection:** | **1/23/13 11:45:00 AM** |
| **Dil. Factor:** | **29.1** | **Date of Analysis:** | **1/24/13 01:53 PM** |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Dibromochloromethane | 140 | Not Detected | 1200 | Not Detected |
| 1,2-Dibromoethane (EDB) | 140 | Not Detected | 1100 | Not Detected |
| Chlorobenzene | 140 | Not Detected | 670 | Not Detected |
| Ethyl Benzene | 140 | Not Detected | 630 | Not Detected |
| m,p-Xylene | 140 | 70 J | 630 | 300 J |
| o-Xylene | 140 | 29 J | 630 | 130 J |
| Styrene | 140 | Not Detected | 620 | Not Detected |
| Bromoform | 140 | Not Detected | 1500 | Not Detected |
| Cumene | 140 | Not Detected | 720 | Not Detected |
| 1,1,2,2-Tetrachloroethane | 140 | Not Detected | 1000 | Not Detected |
| Propylbenzene | 140 | Not Detected | 720 | Not Detected |
| 4-Ethyltoluene | 140 | Not Detected | 720 | Not Detected |
| 1,3,5-Trimethylbenzene | 140 | Not Detected | 720 | Not Detected |
| 1,2,4-Trimethylbenzene | 140 | Not Detected | 720 | Not Detected |
| 1,3-Dichlorobenzene | 140 | Not Detected | 870 | Not Detected |
| 1,4-Dichlorobenzene | 140 | Not Detected | 870 | Not Detected |
| alpha-Chlorotoluene | 140 | Not Detected | 750 | Not Detected |
| 1,2-Dichlorobenzene | 140 | Not Detected | 870 | Not Detected |
| 1,2,4-Trichlorobenzene | 580 | Not Detected | 4300 | Not Detected |
| Hexachlorobutadiene | 580 | Not Detected | 6200 | Not Detected |
| Butane | 580 | 110000 | 1400 | 260000 |
| Isopentane | 580 | 33000 | 1700 | 99000 |

J = Estimated value.

**TENTATIVELY IDENTIFIED COMPOUNDS**

| Compound | CAS Number | Match Quality | Amount ((ppbv)) |
|---|---|---|---|
| Propane, 2-methyl- | | | 22000 NJ |
| Pentane | | | 39000 NJ |
| Pentane, 2-methyl- | | | 43000 NJ |
| Pentane, 2,2,3-trimethyl- | | | 27000 NJ |
| Cyclobutane, ethyl- | | | 0 NJ |

NJ =The identification is based on presumptive evidence; estimated value.

**Container Type: 1 Liter Summa Canister**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| 1,2-Dichloroethane-d4 | 104 | 70-130 |
| Toluene-d8 | 99 | 70-130 |
| 4-Bromofluorobenzene | 98 | 70-130 |

eurofins | Air Toxics

**Client Sample ID: VMP-1-8.5-012313-R** ** Do not use this
**Lab ID#: 1301399AR1-02B** data. Use all other
**EPA METHOD TO-15 GC/MS** data.

| | | | |
|---|---|---|---|
| **File Name:** | **14012314r1** | **Date of Collection:** | **1/23/13 11:45:00 AM** |
| **Dil. Factor:** | **4.66** | **Date of Analysis:** | **1/24/13 01:25 PM** |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 23 | Not Detected | 120 | Not Detected |
| Freon 114 | 23 | Not Detected | 160 | Not Detected |
| Chloromethane | 93 | Not Detected | 190 | Not Detected |
| Vinyl Chloride | 23 | Not Detected | 60 | Not Detected |
| 1,3-Butadiene | 23 | Not Detected | 52 | Not Detected |
| Bromomethane | 23 | Not Detected | 90 | Not Detected |
| Chloroethane | 93 | Not Detected | 240 | Not Detected |
| Freon 11 | 23 | Not Detected | 130 | Not Detected |
| Ethanol | 93 | Not Detected | 180 | Not Detected |
| Freon 113 | 23 | Not Detected | 180 | Not Detected |
| 1,1-Dichloroethene | 23 | Not Detected | 92 | Not Detected |
| Acetone | 93 | Not Detected | 220 | Not Detected |
| 2-Propanol | 93 | Not Detected | 230 | Not Detected |
| Carbon Disulfide | 23 | Not Detected | 72 | Not Detected |
| 3-Chloropropene | 93 | Not Detected | 290 | Not Detected |
| Methylene Chloride | 23 | Not Detected | 81 | Not Detected |
| Methyl tert-butyl ether | 23 | Not Detected | 84 | Not Detected |
| trans-1,2-Dichloroethene | 23 | Not Detected | 92 | Not Detected |
| Hexane | 23 | 1500 | 82 | 5400 |
| 1,1-Dichloroethane | 23 | Not Detected | 94 | Not Detected |
| 2-Butanone (Methyl Ethyl Ketone) | 93 | Not Detected | 270 | Not Detected |
| cis-1,2-Dichloroethene | 23 | Not Detected | 92 | Not Detected |
| Tetrahydrofuran | 23 | Not Detected | 69 | Not Detected |
| Chloroform | 23 | Not Detected | 110 | Not Detected |
| 1,1,1-Trichloroethane | 23 | Not Detected | 130 | Not Detected |
| Cyclohexane | 23 | 400 | 80 | 1400 |
| Carbon Tetrachloride | 23 | Not Detected | 150 | Not Detected |
| 2,2,4-Trimethylpentane | 23 | 990 | 110 | 4600 |
| Benzene | 23 | 16 J | 74 | 50 J |
| 1,2-Dichloroethane | 23 | Not Detected | 94 | Not Detected |
| Heptane | 23 | 230 | 95 | 960 |
| Trichloroethene | 23 | Not Detected | 120 | Not Detected |
| 1,2-Dichloropropane | 23 | Not Detected | 110 | Not Detected |
| 1,4-Dioxane | 93 | Not Detected | 340 | Not Detected |
| Bromodichloromethane | 23 | Not Detected | 160 | Not Detected |
| cis-1,3-Dichloropropene | 23 | Not Detected | 100 | Not Detected |
| 4-Methyl-2-pentanone | 23 | Not Detected | 95 | Not Detected |
| Toluene | 23 | 4.7 J | 88 | 18 J |
| trans-1,3-Dichloropropene | 23 | Not Detected | 100 | Not Detected |
| 1,1,2-Trichloroethane | 23 | Not Detected | 130 | Not Detected |
| Tetrachloroethene | 23 | Not Detected | 160 | Not Detected |
| 2-Hexanone | 93 | Not Detected | 380 | Not Detected |

**Client Sample ID: VMP-1-8.5-012313-R**

**Lab ID#: 1301399AR1-02B**

**EPA METHOD TO-15 GC/MS**

| | | | |
|---|---|---|---|
| **File Name:** | **14012314r1** | **Date of Collection:** | **1/23/13 11:45:00 AM** |
| **Dil. Factor:** | **4.66** | **Date of Analysis:** | **1/24/13 01:25 PM** |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Dibromochloromethane | 23 | Not Detected | 200 | Not Detected |
| 1,2-Dibromoethane (EDB) | 23 | Not Detected | 180 | Not Detected |
| Chlorobenzene | 23 | Not Detected | 110 | Not Detected |
| Ethyl Benzene | 23 | Not Detected | 100 | Not Detected |
| m,p-Xylene | 23 | 9.0 J | 100 | 39 J |
| o-Xylene | 23 | 4.9 J | 100 | 21 J |
| Styrene | 23 | Not Detected | 99 | Not Detected |
| Bromoform | 23 | Not Detected | 240 | Not Detected |
| Cumene | 23 | Not Detected | 110 | Not Detected |
| 1,1,2,2-Tetrachloroethane | 23 | Not Detected | 160 | Not Detected |
| Propylbenzene | 23 | Not Detected | 110 | Not Detected |
| 4-Ethyltoluene | 23 | Not Detected | 110 | Not Detected |
| 1,3,5-Trimethylbenzene | 23 | Not Detected | 110 | Not Detected |
| 1,2,4-Trimethylbenzene | 23 | Not Detected | 110 | Not Detected |
| 1,3-Dichlorobenzene | 23 | Not Detected | 140 | Not Detected |
| 1,4-Dichlorobenzene | 23 | Not Detected | 140 | Not Detected |
| alpha-Chlorotoluene | 23 | Not Detected | 120 | Not Detected |
| 1,2-Dichlorobenzene | 23 | Not Detected | 140 | Not Detected |
| 1,2,4-Trichlorobenzene | 93 | Not Detected | 690 | Not Detected |
| Hexachlorobutadiene | 93 | Not Detected | 990 | Not Detected |
| ~~Butane~~ | ~~93~~ | ~~98000 E~~ | ~~220~~ | ~~230000 E~~ |
| ~~Isopentane~~ | ~~93~~ | ~~37000 E~~ | ~~280~~ | ~~110000 E~~ |

J = Estimated value.
E = Exceeds instrument calibration range.

**TENTATIVELY IDENTIFIED COMPOUNDS**

| Compound | CAS Number | Match Quality | Amount ((ppbv)) |
|---|---|---|---|
| Propane, 2-methyl- | | | 27000 NJ |
| Pentane | | | 44000 NJ |
| Pentane, 2-methyl- | | | 44000 NJ |
| Pentane, 2,2,3-trimethyl- | | | 27000 NJ |
| Cyclobutane, ethyl- | | | 0 NJ |

NJ =The identification is based on presumptive evidence; estimated value.

**Container Type: 1 Liter Summa Canister**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| 1,2-Dichloroethane-d4 | 108 | 70-130 |
| Toluene-d8 | 100 | 70-130 |
| 4-Bromofluorobenzene | 100 | 70-130 |

**Client Sample ID: VMP-I-23.5-012313-R**

**Lab ID#: I301399AR1-03A**

**EPA METHOD TO-15 GC/MS**

| | | | |
|---|---|---|---|
| **File Name:** | **14012317r1** | **Date of Collection:** | **1/23/13 12:05:00 PM** |
| **Dil. Factor:** | **3220** | **Date of Analysis:** | **1/24/13 02:53 PM** |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 16000 | Not Detected | 80000 | Not Detected |
| Freon 114 | 16000 | Not Detected | 110000 | Not Detected |
| Chloromethane | 64000 | Not Detected | 130000 | Not Detected |
| Vinyl Chloride | 16000 | Not Detected | 41000 | Not Detected |
| 1,3-Butadiene | 16000 | Not Detected | 36000 | Not Detected |
| Bromomethane | 16000 | Not Detected | 62000 | Not Detected |
| Chloroethane | 64000 | Not Detected | 170000 | Not Detected |
| Freon 11 | 16000 | Not Detected | 90000 | Not Detected |
| Ethanol | 64000 | Not Detected | 120000 | Not Detected |
| Freon 113 | 16000 | Not Detected | 120000 | Not Detected |
| 1,1-Dichloroethene | 16000 | Not Detected | 64000 | Not Detected |
| Acetone | 64000 | Not Detected | 150000 | Not Detected |
| 2-Propanol | 64000 | Not Detected | 160000 | Not Detected |
| Carbon Disulfide | 16000 | Not Detected | 50000 | Not Detected |
| 3-Chloropropene | 64000 | Not Detected | 200000 | Not Detected |
| Methylene Chloride | 16000 | Not Detected | 56000 | Not Detected |
| Methyl tert-butyl ether | 16000 | Not Detected | 58000 | Not Detected |
| trans-1,2-Dichloroethene | 16000 | Not Detected | 64000 | Not Detected |
| Hexane | 16000 | 140000 | 57000 | 510000 |
| 1,1-Dichloroethane | 16000 | Not Detected | 65000 | Not Detected |
| 2-Butanone (Methyl Ethyl Ketone) | 64000 | Not Detected | 190000 | Not Detected |
| cis-1,2-Dichloroethene | 16000 | Not Detected | 64000 | Not Detected |
| Tetrahydrofuran | 16000 | Not Detected | 47000 | Not Detected |
| Chloroform | 16000 | Not Detected | 79000 | Not Detected |
| 1,1,1-Trichloroethane | 16000 | Not Detected | 88000 | Not Detected |
| Cyclohexane | 16000 | 48000 | 55000 | 160000 |
| Carbon Tetrachloride | 16000 | Not Detected | 100000 | Not Detected |
| 2,2,4-Trimethylpentane | 16000 | 170000 | 75000 | 790000 |
| Benzene | 16000 | 4400 J | 51000 | 14000 J |
| 1,2-Dichloroethane | 16000 | Not Detected | 65000 | Not Detected |
| Heptane | 16000 | 20000 | 66000 | 84000 |
| Trichloroethene | 16000 | Not Detected | 86000 | Not Detected |
| 1,2-Dichloropropane | 16000 | Not Detected | 74000 | Not Detected |
| 1,4-Dioxane | 64000 | Not Detected | 230000 | Not Detected |
| Bromodichloromethane | 16000 | Not Detected | 110000 | Not Detected |
| cis-1,3-Dichloropropene | 16000 | Not Detected | 73000 | Not Detected |
| 4-Methyl-2-pentanone | 16000 | Not Detected | 66000 | Not Detected |
| Toluene | 16000 | 7100 J | 61000 | 27000 J |
| trans-1,3-Dichloropropene | 16000 | Not Detected | 73000 | Not Detected |
| 1,1,2-Trichloroethane | 16000 | Not Detected | 88000 | Not Detected |
| Tetrachloroethene | 16000 | Not Detected | 110000 | Not Detected |
| 2-Hexanone | 64000 | Not Detected | 260000 | Not Detected |

**Client Sample ID: VMP-1-23.5-012313-R**

**Lab ID#: 1301399AR1-03A**

**EPA METHOD TO-15 GC/MS**

| | | | |
|---|---|---|---|
| **File Name:** | **14012317r1** | **Date of Collection:** | **1/23/13 12:05:00 PM** |
| **Dil. Factor:** | **3220** | **Date of Analysis:** | **1/24/13 02:53 PM** |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Dibromochloromethane | 16000 | Not Detected | 140000 | Not Detected |
| 1,2-Dibromoethane (EDB) | 16000 | Not Detected | 120000 | Not Detected |
| Chlorobenzene | 16000 | Not Detected | 74000 | Not Detected |
| Ethyl Benzene | 16000 | Not Detected | 70000 | Not Detected |
| m,p-Xylene | 16000 | 5300 J | 70000 | 23000 J |
| o-Xylene | 16000 | Not Detected | 70000 | Not Detected |
| Styrene | 16000 | Not Detected | 68000 | Not Detected |
| Bromoform | 16000 | Not Detected | 170000 | Not Detected |
| Cumene | 16000 | Not Detected | 79000 | Not Detected |
| 1,1,2,2-Tetrachloroethane | 16000 | Not Detected | 110000 | Not Detected |
| Propylbenzene | 16000 | Not Detected | 79000 | Not Detected |
| 4-Ethyltoluene | 16000 | Not Detected | 79000 | Not Detected |
| 1,3,5-Trimethylbenzene | 16000 | Not Detected | 79000 | Not Detected |
| 1,2,4-Trimethylbenzene | 16000 | Not Detected | 79000 | Not Detected |
| 1,3-Dichlorobenzene | 16000 | Not Detected | 97000 | Not Detected |
| 1,4-Dichlorobenzene | 16000 | Not Detected | 97000 | Not Detected |
| alpha-Chlorotoluene | 16000 | Not Detected | 83000 | Not Detected |
| 1,2-Dichlorobenzene | 16000 | Not Detected | 97000 | Not Detected |
| 1,2,4-Trichlorobenzene | 64000 | Not Detected | 480000 | Not Detected |
| Hexachlorobutadiene | 64000 | Not Detected | 690000 | Not Detected |
| Butane | 64000 | 14000000 | 150000 | 33000000 |
| Isopentane | 64000 | 5000000 | 190000 | 15000000 |

J = Estimated value.

**TENTATIVELY IDENTIFIED COMPOUNDS**

| Compound | CAS Number | Match Quality | Amount ((ppbv)) |
|---|---|---|---|
| Propane, 2-methyl- | | | 3200000 NJ |
| Pentane | | | 4800000 NJ |
| Pentane, 2-methyl- | | | 6200000 NJ |
| Pentane, 3-methyl- | | | 3100000 NJ |
| Cyclobutane, ethyl- | | | 0 NJ |

NJ =The identification is based on presumptive evidence; estimated value.

**Container Type: 1 Liter Summa Canister**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| 1,2-Dichloroethane-d4 | 109 | 70-130 |
| Toluene-d8 | 98 | 70-130 |
| 4-Bromofluorobenzene | 99 | 70-130 |

eurofins | Air Toxics

**Client Sample ID: VMP-1-38.5-012313-R**

**Lab ID#: 1301399AR1-04A**

**EPA METHOD TO-15 GC/MS**

| | | | |
|---|---|---|---|
| **File Name:** | **14012319r1** | **Date of Collection:** | **1/23/13 12:10:00 PM** |
| **Dil. Factor:** | **2380** | **Date of Analysis:** | **1/24/13 03:47 PM** |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 12000 | Not Detected | 59000 | Not Detected |
| Freon 114 | 12000 | Not Detected | 83000 | Not Detected |
| Chloromethane | 48000 | Not Detected | 98000 | Not Detected |
| Vinyl Chloride | 12000 | Not Detected | 30000 | Not Detected |
| 1,3-Butadiene | 12000 | Not Detected | 26000 | Not Detected |
| Bromomethane | 12000 | Not Detected | 46000 | Not Detected |
| Chloroethane | 48000 | Not Detected | 120000 | Not Detected |
| Freon 11 | 12000 | Not Detected | 67000 | Not Detected |
| Ethanol | 48000 | Not Detected | 90000 | Not Detected |
| Freon 113 | 12000 | Not Detected | 91000 | Not Detected |
| 1,1-Dichloroethene | 12000 | Not Detected | 47000 | Not Detected |
| Acetone | 48000 | Not Detected | 110000 | Not Detected |
| 2-Propanol | 48000 | Not Detected | 120000 | Not Detected |
| Carbon Disulfide | 12000 | Not Detected | 37000 | Not Detected |
| 3-Chloropropene | 48000 | Not Detected | 150000 | Not Detected |
| Methylene Chloride | 12000 | Not Detected | 41000 | Not Detected |
| Methyl tert-butyl ether | 12000 | Not Detected | 43000 | Not Detected |
| trans-1,2-Dichloroethene | 12000 | Not Detected | 47000 | Not Detected |
| Hexane | 12000 | 110000 | 42000 | 390000 |
| 1,1-Dichloroethane | 12000 | Not Detected | 48000 | Not Detected |
| 2-Butanone (Methyl Ethyl Ketone) | 48000 | Not Detected | 140000 | Not Detected |
| cis-1,2-Dichloroethene | 12000 | Not Detected | 47000 | Not Detected |
| Tetrahydrofuran | 12000 | Not Detected | 35000 | Not Detected |
| Chloroform | 12000 | Not Detected | 58000 | Not Detected |
| 1,1,1-Trichloroethane | 12000 | Not Detected | 65000 | Not Detected |
| Cyclohexane | 12000 | 27000 | 41000 | 94000 |
| Carbon Tetrachloride | 12000 | Not Detected | 75000 | Not Detected |
| 2,2,4-Trimethylpentane | 12000 | 84000 | 56000 | 390000 |
| Benzene | 12000 | 3600 J | 38000 | 11000 J |
| 1,2-Dichloroethane | 12000 | Not Detected | 48000 | Not Detected |
| Heptane | 12000 | 17000 | 49000 | 69000 |
| Trichloroethene | 12000 | Not Detected | 64000 | Not Detected |
| 1,2-Dichloropropane | 12000 | Not Detected | 55000 | Not Detected |
| 1,4-Dioxane | 48000 | Not Detected | 170000 | Not Detected |
| Bromodichloromethane | 12000 | Not Detected | 80000 | Not Detected |
| cis-1,3-Dichloropropene | 12000 | Not Detected | 54000 | Not Detected |
| 4-Methyl-2-pentanone | 12000 | Not Detected | 49000 | Not Detected |
| Toluene | 12000 | 6000 J | 45000 | 22000 J |
| trans-1,3-Dichloropropene | 12000 | Not Detected | 54000 | Not Detected |
| 1,1,2-Trichloroethane | 12000 | Not Detected | 65000 | Not Detected |
| Tetrachloroethene | 12000 | Not Detected | 81000 | Not Detected |
| 2-Hexanone | 48000 | Not Detected | 190000 | Not Detected |

**Client Sample ID: VMP-1-38.5-012313-R**

**Lab ID#: 1301399AR1-04A**

**EPA METHOD TO-15 GC/MS**

| | | | |
|---|---|---|---|
| **File Name:** | **14012319r1** | **Date of Collection:** | **1/23/13 12:10:00 PM** |
| **Dil. Factor:** | **2380** | **Date of Analysis:** | **1/24/13 03:47 PM** |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Dibromochloromethane | 12000 | Not Detected | 100000 | Not Detected |
| 1,2-Dibromoethane (EDB) | 12000 | Not Detected | 91000 | Not Detected |
| Chlorobenzene | 12000 | Not Detected | 55000 | Not Detected |
| Ethyl Benzene | 12000 | Not Detected | 52000 | Not Detected |
| m,p-Xylene | 12000 | 3800 J | 52000 | 16000 J |
| o-Xylene | 12000 | 1700 J | 52000 | 7200 J |
| Styrene | 12000 | Not Detected | 51000 | Not Detected |
| Bromoform | 12000 | Not Detected | 120000 | Not Detected |
| Cumene | 12000 | Not Detected | 58000 | Not Detected |
| 1,1,2,2-Tetrachloroethane | 12000 | Not Detected | 82000 | Not Detected |
| Propylbenzene | 12000 | Not Detected | 58000 | Not Detected |
| 4-Ethyltoluene | 12000 | Not Detected | 58000 | Not Detected |
| 1,3,5-Trimethylbenzene | 12000 | Not Detected | 58000 | Not Detected |
| 1,2,4-Trimethylbenzene | 12000 | Not Detected | 58000 | Not Detected |
| 1,3-Dichlorobenzene | 12000 | Not Detected | 72000 | Not Detected |
| 1,4-Dichlorobenzene | 12000 | Not Detected | 72000 | Not Detected |
| alpha-Chlorotoluene | 12000 | Not Detected | 62000 | Not Detected |
| 1,2-Dichlorobenzene | 12000 | Not Detected | 72000 | Not Detected |
| 1,2,4-Trichlorobenzene | 48000 | Not Detected | 350000 | Not Detected |
| Hexachlorobutadiene | 48000 | Not Detected | 510000 | Not Detected |
| Butane | 48000 | 8900000 | 110000 | 21000000 |
| Isopentane | 48000 | 2800000 | 140000 | 8200000 |

J = Estimated value.

**TENTATIVELY IDENTIFIED COMPOUNDS**

| Compound | CAS Number | Match Quality | Amount ((ppbv)) |
|---|---|---|---|
| Propane, 2-methyl- | | | 1800000 NJ |
| Pentane | | | 3100000 NJ |
| Pentane, 2-methyl- | | | 3400000 NJ |
| Butane, 2,2,3-trimethyl- | | | 0 NJ |
| Cyclopentane, methyl- | | | 850000 NJ |

NJ =The identification is based on presumptive evidence; estimated value.

**Container Type: 1 Liter Summa Canister**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| 1,2-Dichloroethane-d4 | 108 | 70-130 |
| Toluene-d8 | 99 | 70-130 |
| 4-Bromofluorobenzene | 100 | 70-130 |

**Client Sample ID: VMP-47-5-012313-R**

**Lab ID#: 1301399AR1-05A**

**EPA METHOD TO-15 GC/MS**

| | | | |
|---|---|---|---|
| **File Name:** | **14012321r1** | **Date of Collection:** | **1/23/13 12:35:00 PM** |
| **Dil. Factor:** | **968** | **Date of Analysis:** | **1/24/13 04:49 PM** |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 4800 | Not Detected | 24000 | Not Detected |
| Freon 114 | 4800 | Not Detected | 34000 | Not Detected |
| Chloromethane | 19000 | Not Detected | 40000 | Not Detected |
| Vinyl Chloride | 4800 | Not Detected | 12000 | Not Detected |
| 1,3-Butadiene | 4800 | Not Detected | 11000 | Not Detected |
| Bromomethane | 4800 | Not Detected | 19000 | Not Detected |
| Chloroethane | 19000 | Not Detected | 51000 | Not Detected |
| Freon 11 | 4800 | Not Detected | 27000 | Not Detected |
| Ethanol | 19000 | Not Detected | 36000 | Not Detected |
| Freon 113 | 4800 | Not Detected | 37000 | Not Detected |
| 1,1-Dichloroethene | 4800 | Not Detected | 19000 | Not Detected |
| Acetone | 19000 | Not Detected | 46000 | Not Detected |
| 2-Propanol | 19000 | Not Detected | 48000 | Not Detected |
| Carbon Disulfide | 4800 | Not Detected | 15000 | Not Detected |
| 3-Chloropropene | 19000 | Not Detected | 60000 | Not Detected |
| Methylene Chloride | 4800 | Not Detected | 17000 | Not Detected |
| Methyl tert-butyl ether | 4800 | Not Detected | 17000 | Not Detected |
| trans-1,2-Dichloroethene | 4800 | Not Detected | 19000 | Not Detected |
| Hexane | 4800 | Not Detected | 17000 | Not Detected |
| 1,1-Dichloroethane | 4800 | Not Detected | 20000 | Not Detected |
| 2-Butanone (Methyl Ethyl Ketone) | 19000 | Not Detected | 57000 | Not Detected |
| cis-1,2-Dichloroethene | 4800 | Not Detected | 19000 | Not Detected |
| Tetrahydrofuran | 4800 | Not Detected | 14000 | Not Detected |
| Chloroform | 4800 | Not Detected | 24000 | Not Detected |
| 1,1,1-Trichloroethane | 4800 | Not Detected | 26000 | Not Detected |
| Cyclohexane | 4800 | 9700 | 17000 | 33000 |
| Carbon Tetrachloride | 4800 | Not Detected | 30000 | Not Detected |
| 2,2,4-Trimethylpentane | 4800 | 92000 | 23000 | 430000 |
| Benzene | 4800 | Not Detected | 15000 | Not Detected |
| 1,2-Dichloroethane | 4800 | Not Detected | 20000 | Not Detected |
| Heptane | 4800 | Not Detected | 20000 | Not Detected |
| Trichloroethene | 4800 | Not Detected | 26000 | Not Detected |
| 1,2-Dichloropropane | 4800 | Not Detected | 22000 | Not Detected |
| 1,4-Dioxane | 19000 | Not Detected | 70000 | Not Detected |
| Bromodichloromethane | 4800 | Not Detected | 32000 | Not Detected |
| cis-1,3-Dichloropropene | 4800 | Not Detected | 22000 | Not Detected |
| 4-Methyl-2-pentanone | 4800 | Not Detected | 20000 | Not Detected |
| Toluene | 4800 | Not Detected | 18000 | Not Detected |
| trans-1,3-Dichloropropene | 4800 | Not Detected | 22000 | Not Detected |
| 1,1,2-Trichloroethane | 4800 | Not Detected | 26000 | Not Detected |
| Tetrachloroethene | 4800 | Not Detected | 33000 | Not Detected |
| 2-Hexanone | 19000 | Not Detected | 79000 | Not Detected |

**Client Sample ID: VMP-47-5-012313-R**

**Lab ID#: 1301399AR1-05A**

**EPA METHOD TO-15 GC/MS**

| | | | |
|---|---|---|---|
| **File Name:** | **14012321r1** | **Date of Collection:** | **1/23/13 12:35:00 PM** |
| **Dil. Factor:** | **968** | **Date of Analysis:** | **1/24/13 04:49 PM** |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Dibromochloromethane | 4800 | Not Detected | 41000 | Not Detected |
| 1,2-Dibromoethane (EDB) | 4800 | Not Detected | 37000 | Not Detected |
| Chlorobenzene | 4800 | Not Detected | 22000 | Not Detected |
| Ethyl Benzene | 4800 | Not Detected | 21000 | Not Detected |
| m,p-Xylene | 4800 | Not Detected | 21000 | Not Detected |
| o-Xylene | 4800 | Not Detected | 21000 | Not Detected |
| Styrene | 4800 | Not Detected | 21000 | Not Detected |
| Bromoform | 4800 | Not Detected | 50000 | Not Detected |
| Cumene | 4800 | Not Detected | 24000 | Not Detected |
| 1,1,2,2-Tetrachloroethane | 4800 | Not Detected | 33000 | Not Detected |
| Propylbenzene | 4800 | Not Detected | 24000 | Not Detected |
| 4-Ethyltoluene | 4800 | Not Detected | 24000 | Not Detected |
| 1,3,5-Trimethylbenzene | 4800 | Not Detected | 24000 | Not Detected |
| 1,2,4-Trimethylbenzene | 4800 | Not Detected | 24000 | Not Detected |
| 1,3-Dichlorobenzene | 4800 | Not Detected | 29000 | Not Detected |
| 1,4-Dichlorobenzene | 4800 | Not Detected | 29000 | Not Detected |
| alpha-Chlorotoluene | 4800 | Not Detected | 25000 | Not Detected |
| 1,2-Dichlorobenzene | 4800 | Not Detected | 29000 | Not Detected |
| 1,2,4-Trichlorobenzene | 19000 | Not Detected | 140000 | Not Detected |
| Hexachlorobutadiene | 19000 | Not Detected | 210000 | Not Detected |
| Butane | 19000 | 2000000 | 46000 | 4900000 |
| Isopentane | 19000 | 1600000 | 57000 | 4700000 |

**TENTATIVELY IDENTIFIED COMPOUNDS**

| Compound | CAS Number | Match Quality | Amount ((ppbv)) |
|---|---|---|---|
| Propane, 2-methyl- | | | 1100000 NJ |
| Pentane | | | 680000 NJ |
| Pentane, 2-methyl- | | | 2200000 NJ |
| Hexane, 3,4-dimethyl- | | | 1400000 NJ |
| Pentane, 2,3-dimethyl- | | | 1500000 NJ |

NJ =The identification is based on presumptive evidence; estimated value.

**Container Type: 1 Liter Summa Canister**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| 1,2-Dichloroethane-d4 | 106 | 70-130 |
| Toluene-d8 | 100 | 70-130 |
| 4-Bromofluorobenzene | 98 | 70-130 |

eurofins | Air Toxics

**Client Sample ID: VMP-47-10-012313-R** * Use these results only. All other data was reported from the 24.2 X dilution analysis.
**Lab ID#: 1301399AR1-06A**
**EPA METHOD TO-15 GC/MS**

| | | | |
|---|---|---|---|
| **File Name:** | **14012323r1** | **Date of Collection:** | **1/23/13 12:40:00 PM** |
| **Dil. Factor:** | **48.4** | **Date of Analysis:** | **1/24/13 05:46 PM** |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 240 | Not Detected | 1200 | Not Detected |
| Freon 114 | 240 | Not Detected | 1700 | Not Detected |
| Chloromethane | 970 | Not Detected | 2000 | Not Detected |
| Vinyl Chloride | 240 | Not Detected | 620 | Not Detected |
| 1,3-Butadiene | 240 | Not Detected | 540 | Not Detected |
| Bromomethane | 240 | Not Detected | 940 | Not Detected |
| Chloroethane | 970 | Not Detected | 2600 | Not Detected |
| Freon 11 | 240 | Not Detected | 1400 | Not Detected |
| Ethanol | 970 | Not Detected | 1800 | Not Detected |
| Freon 113 | 240 | Not Detected | 1800 | Not Detected |
| 1,1-Dichloroethene | 240 | Not Detected | 960 | Not Detected |
| Acetone | 970 | Not Detected | 2300 | Not Detected |
| 2-Propanol | 970 | Not Detected | 2400 | Not Detected |
| Carbon Disulfide | 240 | Not Detected | 750 | Not Detected |
| 3-Chloropropene | 970 | Not Detected | 3000 | Not Detected |
| Methylene Chloride | 240 | Not Detected | 840 | Not Detected |
| Methyl tert-butyl ether | 240 | Not Detected | 870 | Not Detected |
| trans-1,2-Dichloroethene | 240 | Not Detected | 960 | Not Detected |
| Hexane | 240 | 540 | 850 | 1900 |
| 1,1-Dichloroethane | 240 | Not Detected | 980 | Not Detected |
| 2-Butanone (Methyl Ethyl Ketone) | 970 | Not Detected | 2800 | Not Detected |
| cis-1,2-Dichloroethene | 240 | Not Detected | 960 | Not Detected |
| Tetrahydrofuran | 240 | Not Detected | 710 | Not Detected |
| Chloroform | 240 | Not Detected | 1200 | Not Detected |
| 1,1,1-Trichloroethane | 240 | Not Detected | 1300 | Not Detected |
| Cyclohexane | 240 | 990 | 830 | 3400 |
| Carbon Tetrachloride | 240 | Not Detected | 1500 | Not Detected |
| 2,2,4-Trimethylpentane | 240 | 23000 | 1100 | 100000 |
| Benzene | 240 | 49 J | 770 | 160 J |
| 1,2-Dichloroethane | 240 | Not Detected | 980 | Not Detected |
| Heptane | 240 | Not Detected | 990 | Not Detected |
| Trichloroethene | 240 | Not Detected | 1300 | Not Detected |
| 1,2-Dichloropropane | 240 | Not Detected | 1100 | Not Detected |
| 1,4-Dioxane | 970 | Not Detected | 3500 | Not Detected |
| Bromodichloromethane | 240 | Not Detected | 1600 | Not Detected |
| cis-1,3-Dichloropropene | 240 | Not Detected | 1100 | Not Detected |
| 4-Methyl-2-pentanone | 240 | Not Detected | 990 | Not Detected |
| Toluene | 240 | 87 J | 910 | 330 J |
| trans-1,3-Dichloropropene | 240 | Not Detected | 1100 | Not Detected |
| 1,1,2-Trichloroethane | 240 | Not Detected | 1300 | Not Detected |
| Tetrachloroethene | 240 | Not Detected | 1600 | Not Detected |
| 2-Hexanone | 970 | Not Detected | 4000 | Not Detected |

**Client Sample ID: VMP-47-10-0I2313-R**

**Lab ID#: 1301399AR1-06A**

**EPA METHOD TO-15 GC/MS**

| | | | |
|---|---|---|---|
| **File Name:** | **14012323r1** | **Date of Collection:** | **1/23/13 12:40:00 PM** |
| **Dil. Factor:** | **48.4** | **Date of Analysis:** | **1/24/13 05:46 PM** |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Dibromochloromethane | 240 | Not Detected | 2100 | Not Detected |
| 1,2-Dibromoethane (EDB) | 240 | Not Detected | 1800 | Not Detected |
| Chlorobenzene | 240 | Not Detected | 1100 | Not Detected |
| Ethyl Benzene | 240 | Not Detected | 1000 | Not Detected |
| m,p-Xylene | 240 | 69 J | 1000 | 300 J |
| o-Xylene | 240 | Not Detected | 1000 | Not Detected |
| Styrene | 240 | Not Detected | 1000 | Not Detected |
| Bromoform | 240 | Not Detected | 2500 | Not Detected |
| Cumene | 240 | Not Detected | 1200 | Not Detected |
| 1,1,2,2-Tetrachloroethane | 240 | Not Detected | 1700 | Not Detected |
| Propylbenzene | 240 | Not Detected | 1200 | Not Detected |
| 4-Ethyltoluene | 240 | Not Detected | 1200 | Not Detected |
| 1,3,5-Trimethylbenzene | 240 | Not Detected | 1200 | Not Detected |
| 1,2,4-Trimethylbenzene | 240 | Not Detected | 1200 | Not Detected |
| 1,3-Dichlorobenzene | 240 | Not Detected | 1400 | Not Detected |
| 1,4-Dichlorobenzene | 240 | Not Detected | 1400 | Not Detected |
| alpha-Chlorotoluene | 240 | Not Detected | 1200 | Not Detected |
| 1,2-Dichlorobenzene | 240 | Not Detected | 1400 | Not Detected |
| 1,2,4-Trichlorobenzene | 970 | Not Detected | 7200 | Not Detected |
| Hexachlorobutadiene | 970 | Not Detected | 10000 | Not Detected |
| Butane | 970 | 190000 | 2300 | 460000 |
| Isopentane | 970 | 190000 | 2800 | 560000 |

J = Estimated value.

**TENTATIVELY IDENTIFIED COMPOUNDS**

| Compound | CAS Number | Match Quality | Amount ((ppbv)) |
|---|---|---|---|
| Propane, 2-methyl- | | | 150000 NJ |
| Pentane, 2-methyl- | | | 280000 NJ |
| Pentane, 3-methyl- | | | 120000 NJ |
| Pentane, 2,4-dimethyl- | | | 110000 NJ |
| Pentane, 2,3-dimethyl- | | | 180000 NJ |

NJ =The identification is based on presumptive evidence; estimated value.

**Container Type: 1 Liter Summa Canister**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| 1,2-Dichloroethane-d4 | 109 | 70-130 |
| Toluene-d8 | 99 | 70-130 |
| 4-Bromofluorobenzene | 100 | 70-130 |

eurofins | Air Toxics

**Client Sample ID: VMP-47-10-012313-R**
**Lab ID#: 1301399AR1-06B**
**EPA METHOD TO-15 GC/MS**

** Do not use this data. use all other data.

| | | | |
|---|---|---|---|
| **File Name:** | **14012322r1** | **Date of Collection:** | **1/23/13 12:40:00 PM** |
| **Dil. Factor:** | **24.2** | **Date of Analysis:** | **1/24/13 05:14 PM** |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 120 | Not Detected | 600 | Not Detected |
| Freon 114 | 120 | Not Detected | 840 | Not Detected |
| Chloromethane | 480 | Not Detected | 1000 | Not Detected |
| Vinyl Chloride | 120 | Not Detected | 310 | Not Detected |
| 1,3-Butadiene | 120 | Not Detected | 270 | Not Detected |
| Bromomethane | 120 | Not Detected | 470 | Not Detected |
| Chloroethane | 480 | Not Detected | 1300 | Not Detected |
| Freon 11 | 120 | Not Detected | 680 | Not Detected |
| Ethanol | 480 | Not Detected | 910 | Not Detected |
| Freon 113 | 120 | Not Detected | 930 | Not Detected |
| 1,1-Dichloroethene | 120 | Not Detected | 480 | Not Detected |
| Acetone | 480 | Not Detected | 1100 | Not Detected |
| 2-Propanol | 480 | Not Detected | 1200 | Not Detected |
| Carbon Disulfide | 120 | Not Detected | 380 | Not Detected |
| 3-Chloropropene | 480 | Not Detected | 1500 | Not Detected |
| Methylene Chloride | 120 | Not Detected | 420 | Not Detected |
| Methyl tert-butyl ether | 120 | Not Detected | 440 | Not Detected |
| trans-1,2-Dichloroethene | 120 | Not Detected | 480 | Not Detected |
| Hexane | 120 | 490 | 430 | 1700 |
| 1,1-Dichloroethane | 120 | Not Detected | 490 | Not Detected |
| 2-Butanone (Methyl Ethyl Ketone) | 480 | Not Detected | 1400 | Not Detected |
| cis-1,2-Dichloroethene | 120 | Not Detected | 480 | Not Detected |
| Tetrahydrofuran | 120 | Not Detected | 360 | Not Detected |
| Chloroform | 120 | Not Detected | 590 | Not Detected |
| 1,1,1-Trichloroethane | 120 | Not Detected | 660 | Not Detected |
| Cyclohexane | 120 | 1000 | 420 | 3500 |
| Carbon Tetrachloride | 120 | Not Detected | 760 | Not Detected |
| 2,2,4-Trimethylpentane | 120 | 22000 | 560 | 100000 |
| Benzene | 120 | 35 J | 390 | 110 J |
| 1,2-Dichloroethane | 120 | Not Detected | 490 | Not Detected |
| Heptane | 120 | Not Detected | 500 | Not Detected |
| Trichloroethene | 120 | Not Detected | 650 | Not Detected |
| 1,2-Dichloropropane | 120 | Not Detected | 560 | Not Detected |
| 1,4-Dioxane | 480 | Not Detected | 1700 | Not Detected |
| Bromodichloromethane | 120 | Not Detected | 810 | Not Detected |
| cis-1,3-Dichloropropene | 120 | Not Detected | 550 | Not Detected |
| 4-Methyl-2-pentanone | 120 | Not Detected | 500 | Not Detected |
| Toluene | 120 | 52 J | 460 | 190 J |
| trans-1,3-Dichloropropene | 120 | Not Detected | 550 | Not Detected |
| 1,1,2-Trichloroethane | 120 | Not Detected | 660 | Not Detected |
| Tetrachloroethene | 120 | Not Detected | 820 | Not Detected |
| 2-Hexanone | 480 | Not Detected | 2000 | Not Detected |

**Client Sample ID: VMP-47-10-012313-R**

**Lab ID#: 1301399ARI-06B**

**EPA METHOD TO-15 GC/MS**

| | | | |
|---|---|---|---|
| **File Name:** | **14012322r1** | **Date of Collection:** | **1/23/13 12:40:00 PM** |
| **Dil. Factor:** | **24.2** | **Date of Analysis:** | **1/24/13 05:14 PM** |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Dibromochloromethane | 120 | Not Detected | 1000 | Not Detected |
| 1,2-Dibromoethane (EDB) | 120 | Not Detected | 930 | Not Detected |
| Chlorobenzene | 120 | Not Detected | 560 | Not Detected |
| Ethyl Benzene | 120 | Not Detected | 520 | Not Detected |
| m,p-Xylene | 120 | 44 J | 520 | 190 J |
| o-Xylene | 120 | Not Detected | 520 | Not Detected |
| Styrene | 120 | Not Detected | 520 | Not Detected |
| Bromoform | 120 | Not Detected | 1200 | Not Detected |
| Cumene | 120 | Not Detected | 590 | Not Detected |
| 1,1,2,2-Tetrachloroethane | 120 | Not Detected | 830 | Not Detected |
| Propylbenzene | 120 | Not Detected | 590 | Not Detected |
| 4-Ethyltoluene | 120 | Not Detected | 590 | Not Detected |
| 1,3,5-Trimethylbenzene | 120 | Not Detected | 590 | Not Detected |
| 1,2,4-Trimethylbenzene | 120 | Not Detected | 590 | Not Detected |
| 1,3-Dichlorobenzene | 120 | Not Detected | 730 | Not Detected |
| 1,4-Dichlorobenzene | 120 | Not Detected | 730 | Not Detected |
| alpha-Chlorotoluene | 120 | Not Detected | 630 | Not Detected |
| 1,2-Dichlorobenzene | 120 | Not Detected | 730 | Not Detected |
| 1,2,4-Trichlorobenzene | 480 | Not Detected | 3600 | Not Detected |
| Hexachlorobutadiene | 480 | Not Detected | 5200 | Not Detected |
| ~~Butane~~ | ~~480~~ | ~~180000 E~~ | ~~1200~~ | ~~430000 E~~ |
| ~~Isopentane~~ | ~~480~~ | ~~180000 E~~ | ~~1400~~ | ~~530000 E~~ |

J = Estimated value.
E = Exceeds instrument calibration range.

**TENTATIVELY IDENTIFIED COMPOUNDS**

| Compound | CAS Number | Match Quality | Amount ((ppbv)) |
|---|---|---|---|
| Propane, 2-methyl- | | | 130000 NJ |
| Pentane, 2-methyl- | | | 260000 NJ |
| Pentane, 3-methyl- | | | 110000 NJ |
| Pentane, 2,4-dimethyl- | | | 110000 NJ |
| Pentane, 2,3-dimethyl- | | | 170000 NJ |

NJ =The identification is based on presumptive evidence; estimated value.

**Container Type: 1 Liter Summa Canister**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| 1,2-Dichloroethane-d4 | 109 | 70-130 |
| Toluene-d8 | 98 | 70-130 |
| 4-Bromofluorobenzene | 100 | 70-130 |

**Client Sample ID: VMP-47-20-012313-R**

**Lab ID#: 1301399AR1-07A**

**EPA METHOD TO-15 GC/MS**

| | | | |
|---|---|---|---|
| **File Name:** | **14012325r1** | **Date of Collection:** | **1/23/13 12:50:00 PM** |
| **Dil. Factor:** | **595** | **Date of Analysis:** | **1/24/13 06:39 PM** |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 3000 | Not Detected | 15000 | Not Detected |
| Freon 114 | 3000 | Not Detected | 21000 | Not Detected |
| Chloromethane | 12000 | Not Detected | 24000 | Not Detected |
| Vinyl Chloride | 3000 | Not Detected | 7600 | Not Detected |
| 1,3-Butadiene | 3000 | Not Detected | 6600 | Not Detected |
| Bromomethane | 3000 | Not Detected | 12000 | Not Detected |
| Chloroethane | 12000 | Not Detected | 31000 | Not Detected |
| Freon 11 | 3000 | Not Detected | 17000 | Not Detected |
| Ethanol | 12000 | Not Detected | 22000 | Not Detected |
| Freon 113 | 3000 | Not Detected | 23000 | Not Detected |
| 1,1-Dichloroethene | 3000 | Not Detected | 12000 | Not Detected |
| Acetone | 12000 | Not Detected | 28000 | Not Detected |
| 2-Propanol | 12000 | Not Detected | 29000 | Not Detected |
| Carbon Disulfide | 3000 | Not Detected | 9300 | Not Detected |
| 3-Chloropropene | 12000 | Not Detected | 37000 | Not Detected |
| Methylene Chloride | 3000 | Not Detected | 10000 | Not Detected |
| Methyl tert-butyl ether | 3000 | Not Detected | 11000 | Not Detected |
| trans-1,2-Dichloroethene | 3000 | Not Detected | 12000 | Not Detected |
| Hexane | 3000 | 5600 | 10000 | 20000 |
| 1,1-Dichloroethane | 3000 | Not Detected | 12000 | Not Detected |
| 2-Butanone (Methyl Ethyl Ketone) | 12000 | Not Detected | 35000 | Not Detected |
| cis-1,2-Dichloroethene | 3000 | Not Detected | 12000 | Not Detected |
| Tetrahydrofuran | 3000 | Not Detected | 8800 | Not Detected |
| Chloroform | 3000 | Not Detected | 14000 | Not Detected |
| 1,1,1-Trichloroethane | 3000 | Not Detected | 16000 | Not Detected |
| Cyclohexane | 3000 | 7900 | 10000 | 27000 |
| Carbon Tetrachloride | 3000 | Not Detected | 19000 | Not Detected |
| 2,2,4-Trimethylpentane | 3000 | 73000 | 14000 | 340000 |
| Benzene | 3000 | Not Detected | 9500 | Not Detected |
| 1,2-Dichloroethane | 3000 | Not Detected | 12000 | Not Detected |
| Heptane | 3000 | Not Detected | 12000 | Not Detected |
| Trichloroethene | 3000 | Not Detected | 16000 | Not Detected |
| 1,2-Dichloropropane | 3000 | Not Detected | 14000 | Not Detected |
| 1,4-Dioxane | 12000 | Not Detected | 43000 | Not Detected |
| Bromodichloromethane | 3000 | Not Detected | 20000 | Not Detected |
| cis-1,3-Dichloropropene | 3000 | Not Detected | 14000 | Not Detected |
| 4-Methyl-2-pentanone | 3000 | Not Detected | 12000 | Not Detected |
| Toluene | 3000 | Not Detected | 11000 | Not Detected |
| trans-1,3-Dichloropropene | 3000 | Not Detected | 14000 | Not Detected |
| 1,1,2-Trichloroethane | 3000 | Not Detected | 16000 | Not Detected |
| Tetrachloroethene | 3000 | Not Detected | 20000 | Not Detected |
| 2-Hexanone | 12000 | Not Detected | 49000 | Not Detected |

eurofins | Air Toxics

**Client Sample ID: VMP-47-20-012313-R**

**Lab ID#: 1301399AR1-07A**

**EPA METHOD TO-15 GC/MS**

| | | | |
|---|---|---|---|
| **File Name:** | **14012325r1** | **Date of Collection:** | **1/23/13 12:50:00 PM** |
| **Dil. Factor:** | **595** | **Date of Analysis:** | **1/24/13 06:39 PM** |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Dibromochloromethane | 3000 | Not Detected | 25000 | Not Detected |
| 1,2-Dibromoethane (EDB) | 3000 | Not Detected | 23000 | Not Detected |
| Chlorobenzene | 3000 | Not Detected | 14000 | Not Detected |
| Ethyl Benzene | 3000 | Not Detected | 13000 | Not Detected |
| m,p-Xylene | 3000 | Not Detected | 13000 | Not Detected |
| o-Xylene | 3000 | Not Detected | 13000 | Not Detected |
| Styrene | 3000 | Not Detected | 13000 | Not Detected |
| Bromoform | 3000 | Not Detected | 31000 | Not Detected |
| Cumene | 3000 | Not Detected | 15000 | Not Detected |
| 1,1,2,2-Tetrachloroethane | 3000 | Not Detected | 20000 | Not Detected |
| Propylbenzene | 3000 | Not Detected | 15000 | Not Detected |
| 4-Ethyltoluene | 3000 | Not Detected | 15000 | Not Detected |
| 1,3,5-Trimethylbenzene | 3000 | Not Detected | 15000 | Not Detected |
| 1,2,4-Trimethylbenzene | 3000 | Not Detected | 15000 | Not Detected |
| 1,3-Dichlorobenzene | 3000 | Not Detected | 18000 | Not Detected |
| 1,4-Dichlorobenzene | 3000 | Not Detected | 18000 | Not Detected |
| alpha-Chlorotoluene | 3000 | Not Detected | 15000 | Not Detected |
| 1,2-Dichlorobenzene | 3000 | Not Detected | 18000 | Not Detected |
| 1,2,4-Trichlorobenzene | 12000 | Not Detected | 88000 | Not Detected |
| Hexachlorobutadiene | 12000 | Not Detected | 130000 | Not Detected |
| Butane | 12000 | 1700000 | 28000 | 4100000 |
| Isopentane | 12000 | 1200000 | 35000 | 3500000 |

**TENTATIVELY IDENTIFIED COMPOUNDS**

| Compound | CAS Number | Match Quality | Amount ((ppbv)) |
|---|---|---|---|
| Propane, 2-methyl- | | | 860000 NJ |
| Pentane | | | 610000 NJ |
| Pentane, 2-methyl- | | | 1700000 NJ |
| Pentane, 3-methyl- | | | 840000 NJ |
| Pentane, 2,3-dimethyl- | | | 1200000 NJ |

NJ =The identification is based on presumptive evidence; estimated value.

**Container Type: 1 Liter Summa Canister**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| 1,2-Dichloroethane-d4 | 105 | 70-130 |
| Toluene-d8 | 100 | 70-130 |
| 4-Bromofluorobenzene | 98 | 70-130 |

**Client Sample ID: VMP-47-30-0123I3-R**

**Lab ID#: 1301399AR1-08A**

**EPA METHOD TO-15 GC/MS**

| | | | |
|---|---|---|---|
| **File Name:** | **14012327r1** | **Date of Collection:** | **1/23/13 1:00:00 PM** |
| **Dil. Factor:** | **952** | **Date of Analysis:** | **1/24/13 07:27 PM** |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 4800 | Not Detected | 24000 | Not Detected |
| Freon 114 | 4800 | Not Detected | 33000 | Not Detected |
| Chloromethane | 19000 | Not Detected | 39000 | Not Detected |
| Vinyl Chloride | 4800 | Not Detected | 12000 | Not Detected |
| 1,3-Butadiene | 4800 | Not Detected | 10000 | Not Detected |
| Bromomethane | 4800 | Not Detected | 18000 | Not Detected |
| Chloroethane | 19000 | Not Detected | 50000 | Not Detected |
| Freon 11 | 4800 | Not Detected | 27000 | Not Detected |
| Ethanol | 19000 | Not Detected | 36000 | Not Detected |
| Freon 113 | 4800 | Not Detected | 36000 | Not Detected |
| 1,1-Dichloroethene | 4800 | Not Detected | 19000 | Not Detected |
| Acetone | 19000 | Not Detected | 45000 | Not Detected |
| 2-Propanol | 19000 | Not Detected | 47000 | Not Detected |
| Carbon Disulfide | 4800 | Not Detected | 15000 | Not Detected |
| 3-Chloropropene | 19000 | Not Detected | 60000 | Not Detected |
| Methylene Chloride | 4800 | Not Detected | 16000 | Not Detected |
| Methyl tert-butyl ether | 4800 | Not Detected | 17000 | Not Detected |
| trans-1,2-Dichloroethene | 4800 | Not Detected | 19000 | Not Detected |
| Hexane | 4800 | Not Detected | 17000 | Not Detected |
| 1,1-Dichloroethane | 4800 | Not Detected | 19000 | Not Detected |
| 2-Butanone (Methyl Ethyl Ketone) | 19000 | Not Detected | 56000 | Not Detected |
| cis-1,2-Dichloroethene | 4800 | Not Detected | 19000 | Not Detected |
| Tetrahydrofuran | 4800 | Not Detected | 14000 | Not Detected |
| Chloroform | 4800 | Not Detected | 23000 | Not Detected |
| 1,1,1-Trichloroethane | 4800 | Not Detected | 26000 | Not Detected |
| Cyclohexane | 4800 | 9600 | 16000 | 33000 |
| Carbon Tetrachloride | 4800 | Not Detected | 30000 | Not Detected |
| 2,2,4-Trimethylpentane | 4800 | 93000 | 22000 | 430000 |
| Benzene | 4800 | Not Detected | 15000 | Not Detected |
| 1,2-Dichloroethane | 4800 | Not Detected | 19000 | Not Detected |
| Heptane | 4800 | Not Detected | 20000 | Not Detected |
| Trichloroethene | 4800 | Not Detected | 26000 | Not Detected |
| 1,2-Dichloropropane | 4800 | Not Detected | 22000 | Not Detected |
| 1,4-Dioxane | 19000 | Not Detected | 69000 | Not Detected |
| Bromodichloromethane | 4800 | Not Detected | 32000 | Not Detected |
| cis-1,3-Dichloropropene | 4800 | Not Detected | 22000 | Not Detected |
| 4-Methyl-2-pentanone | 4800 | Not Detected | 19000 | Not Detected |
| Toluene | 4800 | Not Detected | 18000 | Not Detected |
| trans-1,3-Dichloropropene | 4800 | Not Detected | 22000 | Not Detected |
| 1,1,2-Trichloroethane | 4800 | Not Detected | 26000 | Not Detected |
| Tetrachloroethene | 4800 | Not Detected | 32000 | Not Detected |
| 2-Hexanone | 19000 | Not Detected | 78000 | Not Detected |

**Client Sample ID: VMP-47-30-012313-R**

**Lab ID#: 1301399AR1-08A**

**EPA METHOD TO-15 GC/MS**

| | | | |
|---|---|---|---|
| **File Name:** | **14012327r1** | **Date of Collection:** | **1/23/13 1:00:00 PM** |
| **Dil. Factor:** | **952** | **Date of Analysis:** | **1/24/13 07:27 PM** |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Dibromochloromethane | 4800 | Not Detected | 40000 | Not Detected |
| 1,2-Dibromoethane (EDB) | 4800 | Not Detected | 36000 | Not Detected |
| Chlorobenzene | 4800 | Not Detected | 22000 | Not Detected |
| Ethyl Benzene | 4800 | Not Detected | 21000 | Not Detected |
| m,p-Xylene | 4800 | Not Detected | 21000 | Not Detected |
| o-Xylene | 4800 | Not Detected | 21000 | Not Detected |
| Styrene | 4800 | Not Detected | 20000 | Not Detected |
| Bromoform | 4800 | Not Detected | 49000 | Not Detected |
| Cumene | 4800 | Not Detected | 23000 | Not Detected |
| 1,1,2,2-Tetrachloroethane | 4800 | Not Detected | 33000 | Not Detected |
| Propylbenzene | 4800 | Not Detected | 23000 | Not Detected |
| 4-Ethyltoluene | 4800 | Not Detected | 23000 | Not Detected |
| 1,3,5-Trimethylbenzene | 4800 | Not Detected | 23000 | Not Detected |
| 1,2,4-Trimethylbenzene | 4800 | Not Detected | 23000 | Not Detected |
| 1,3-Dichlorobenzene | 4800 | Not Detected | 29000 | Not Detected |
| 1,4-Dichlorobenzene | 4800 | Not Detected | 29000 | Not Detected |
| alpha-Chlorotoluene | 4800 | Not Detected | 25000 | Not Detected |
| 1,2-Dichlorobenzene | 4800 | Not Detected | 29000 | Not Detected |
| 1,2,4-Trichlorobenzene | 19000 | Not Detected | 140000 | Not Detected |
| Hexachlorobutadiene | 19000 | Not Detected | 200000 | Not Detected |
| Butane | 19000 | 2000000 | 45000 | 4800000 |
| Isopentane | 19000 | 1600000 | 56000 | 4600000 |

**TENTATIVELY IDENTIFIED COMPOUNDS**

| Compound | CAS Number | Match Quality | Amount ((ppbv)) |
|---|---|---|---|
| Propane, 2-methyl- | | | 1100000 NJ |
| Pentane | | | 690000 NJ |
| Pentane, 2-methyl- | | | 2100000 NJ |
| Pentane, 3-methyl- | | | 1000000 NJ |
| Pentane, 2,3-dimethyl- | | | 1500000 NJ |

NJ =The identification is based on presumptive evidence; estimated value.

**Container Type: 1 Liter Summa Canister**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| 1,2-Dichloroethane-d4 | 105 | 70-130 |
| Toluene-d8 | 99 | 70-130 |
| 4-Bromofluorobenzene | 99 | 70-130 |

**Client Sample ID: Lab Blank**
**Lab ID#: 1301399AR1-09A**
**EPA METHOD TO-15 GC/MS**

| | | | |
|---|---|---|---|
| **File Name:** | **14012306** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 1/24/13 07:51 AM** | |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 5.0 | Not Detected | 25 | Not Detected |
| Freon 114 | 5.0 | Not Detected | 35 | Not Detected |
| Chloromethane | 20 | Not Detected | 41 | Not Detected |
| Vinyl Chloride | 5.0 | Not Detected | 13 | Not Detected |
| 1,3-Butadiene | 5.0 | Not Detected | 11 | Not Detected |
| Bromomethane | 5.0 | Not Detected | 19 | Not Detected |
| Chloroethane | 20 | Not Detected | 53 | Not Detected |
| Freon 11 | 5.0 | Not Detected | 28 | Not Detected |
| Ethanol | 20 | Not Detected | 38 | Not Detected |
| Freon 113 | 5.0 | Not Detected | 38 | Not Detected |
| 1,1-Dichloroethene | 5.0 | Not Detected | 20 | Not Detected |
| Acetone | 20 | Not Detected | 48 | Not Detected |
| 2-Propanol | 20 | Not Detected | 49 | Not Detected |
| Carbon Disulfide | 5.0 | Not Detected | 16 | Not Detected |
| 3-Chloropropene | 20 | Not Detected | 63 | Not Detected |
| Methylene Chloride | 5.0 | Not Detected | 17 | Not Detected |
| Methyl tert-butyl ether | 5.0 | Not Detected | 18 | Not Detected |
| trans-1,2-Dichloroethene | 5.0 | Not Detected | 20 | Not Detected |
| Hexane | 5.0 | Not Detected | 18 | Not Detected |
| 1,1-Dichloroethane | 5.0 | Not Detected | 20 | Not Detected |
| 2-Butanone (Methyl Ethyl Ketone) | 20 | Not Detected | 59 | Not Detected |
| cis-1,2-Dichloroethene | 5.0 | Not Detected | 20 | Not Detected |
| Tetrahydrofuran | 5.0 | Not Detected | 15 | Not Detected |
| Chloroform | 5.0 | Not Detected | 24 | Not Detected |
| 1,1,1-Trichloroethane | 5.0 | Not Detected | 27 | Not Detected |
| Cyclohexane | 5.0 | Not Detected | 17 | Not Detected |
| Carbon Tetrachloride | 5.0 | Not Detected | 31 | Not Detected |
| 2,2,4-Trimethylpentane | 5.0 | Not Detected | 23 | Not Detected |
| Benzene | 5.0 | Not Detected | 16 | Not Detected |
| 1,2-Dichloroethane | 5.0 | Not Detected | 20 | Not Detected |
| Heptane | 5.0 | Not Detected | 20 | Not Detected |
| Trichloroethene | 5.0 | Not Detected | 27 | Not Detected |
| 1,2-Dichloropropane | 5.0 | Not Detected | 23 | Not Detected |
| 1,4-Dioxane | 20 | Not Detected | 72 | Not Detected |
| Bromodichloromethane | 5.0 | Not Detected | 34 | Not Detected |
| cis-1,3-Dichloropropene | 5.0 | Not Detected | 23 | Not Detected |
| 4-Methyl-2-pentanone | 5.0 | Not Detected | 20 | Not Detected |
| Toluene | 5.0 | Not Detected | 19 | Not Detected |
| trans-1,3-Dichloropropene | 5.0 | Not Detected | 23 | Not Detected |
| 1,1,2-Trichloroethane | 5.0 | Not Detected | 27 | Not Detected |
| Tetrachloroethene | 5.0 | Not Detected | 34 | Not Detected |
| 2-Hexanone | 20 | Not Detected | 82 | Not Detected |

**Client Sample ID: Lab Blank**
**Lab ID#: 1301399AR1-09A**
**EPA METHOD TO-15 GC/MS**

| | | | |
|---|---|---|---|
| **File Name:** | **14012306** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 1/24/13 07:51 AM** | |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Dibromochloromethane | 5.0 | Not Detected | 42 | Not Detected |
| 1,2-Dibromoethane (EDB) | 5.0 | Not Detected | 38 | Not Detected |
| Chlorobenzene | 5.0 | Not Detected | 23 | Not Detected |
| Ethyl Benzene | 5.0 | Not Detected | 22 | Not Detected |
| m,p-Xylene | 5.0 | Not Detected | 22 | Not Detected |
| o-Xylene | 5.0 | Not Detected | 22 | Not Detected |
| Styrene | 5.0 | Not Detected | 21 | Not Detected |
| Bromoform | 5.0 | Not Detected | 52 | Not Detected |
| Cumene | 5.0 | Not Detected | 24 | Not Detected |
| 1,1,2,2-Tetrachloroethane | 5.0 | Not Detected | 34 | Not Detected |
| Propylbenzene | 5.0 | Not Detected | 24 | Not Detected |
| 4-Ethyltoluene | 5.0 | Not Detected | 24 | Not Detected |
| 1,3,5-Trimethylbenzene | 5.0 | Not Detected | 24 | Not Detected |
| 1,2,4-Trimethylbenzene | 5.0 | Not Detected | 24 | Not Detected |
| 1,3-Dichlorobenzene | 5.0 | Not Detected | 30 | Not Detected |
| 1,4-Dichlorobenzene | 5.0 | Not Detected | 30 | Not Detected |
| alpha-Chlorotoluene | 5.0 | Not Detected | 26 | Not Detected |
| 1,2-Dichlorobenzene | 5.0 | Not Detected | 30 | Not Detected |
| 1,2,4-Trichlorobenzene | 20 | Not Detected | 150 | Not Detected |
| Hexachlorobutadiene | 20 | Not Detected | 210 | Not Detected |
| Butane | 20 | Not Detected | 48 | Not Detected |
| Isopentane | 20 | Not Detected | 59 | Not Detected |

**TENTATIVELY IDENTIFIED COMPOUNDS**

| Compound | CAS Number | Match Quality | Amount ((ppbv)) |
|---|---|---|---|
| None Identified | | | |

**Container Type: NA - Not Applicable**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| 1,2-Dichloroethane-d4 | 106 | 70-130 |
| Toluene-d8 | 100 | 70-130 |
| 4-Bromofluorobenzene | 99 | 70-130 |

eurofins | Air Toxics

**Client Sample ID: CCV**
**Lab ID#: 1301399AR1-10A**
**EPA METHOD TO-15 GC/MS**

| | | | |
|---|---|---|---|
| **File Name:** | **14012302** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 1/23/13 09:37 PM** | |

| Compound | %Recovery |
|---|---|
| Freon 12 | 102 |
| Freon 114 | 102 |
| Chloromethane | 114 |
| Vinyl Chloride | 99 |
| 1,3-Butadiene | 104 |
| Bromomethane | 103 |
| Chloroethane | 96 |
| Freon 11 | 106 |
| Ethanol | 126 |
| Freon 113 | 96 |
| 1,1-Dichloroethene | 108 |
| Acetone | 102 |
| 2-Propanol | 120 |
| Carbon Disulfide | 89 |
| 3-Chloropropene | 92 |
| Methylene Chloride | 101 |
| Methyl tert-butyl ether | 103 |
| trans-1,2-Dichloroethene | 99 |
| Hexane | 102 |
| 1,1-Dichloroethane | 100 |
| 2-Butanone (Methyl Ethyl Ketone) | 103 |
| cis-1,2-Dichloroethene | 98 |
| Tetrahydrofuran | 107 |
| Chloroform | 102 |
| 1,1,1-Trichloroethane | 96 |
| Cyclohexane | 96 |
| Carbon Tetrachloride | 102 |
| 2,2,4-Trimethylpentane | 105 |
| Benzene | 98 |
| 1,2-Dichloroethane | 102 |
| Heptane | 100 |
| Trichloroethene | 101 |
| 1,2-Dichloropropane | 96 |
| 1,4-Dioxane | 105 |
| Bromodichloromethane | 100 |
| cis-1,3-Dichloropropene | 94 |
| 4-Methyl-2-pentanone | 106 |
| Toluene | 94 |
| trans-1,3-Dichloropropene | 95 |
| 1,1,2-Trichloroethane | 96 |
| Tetrachloroethene | 94 |
| 2-Hexanone | 110 |

eurofins | Air Toxics

**Client Sample ID: CCV**
**Lab ID#: 1301399AR1-10A**
**EPA METHOD TO-15 GC/MS**

| | | | |
|---|---|---|---|
| **File Name:** | **14012302** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 1/23/13 09:37 PM** | |

| Compound | %Recovery |
|---|---|
| Dibromochloromethane | 97 |
| 1,2-Dibromoethane (EDB) | 94 |
| Chlorobenzene | 96 |
| Ethyl Benzene | 95 |
| m,p-Xylene | 98 |
| o-Xylene | 98 |
| Styrene | 100 |
| Bromoform | 96 |
| Cumene | 98 |
| 1,1,2,2-Tetrachloroethane | 99 |
| Propylbenzene | 101 |
| 4-Ethyltoluene | 103 |
| 1,3,5-Trimethylbenzene | 104 |
| 1,2,4-Trimethylbenzene | 103 |
| 1,3-Dichlorobenzene | 95 |
| 1,4-Dichlorobenzene | 94 |
| alpha-Chlorotoluene | 96 |
| 1,2-Dichlorobenzene | 98 |
| 1,2,4-Trichlorobenzene | 93 |
| Hexachlorobutadiene | 88 |
| Butane | 118 |
| Isopentane | 115 |

**Container Type: NA - Not Applicable**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| 1,2-Dichloroethane-d4 | 105 | 70-130 |
| Toluene-d8 | 102 | 70-130 |
| 4-Bromofluorobenzene | 102 | 70-130 |

eurofins | Air Toxics

**Client Sample ID: LCS**
**Lab ID#: 1301399AR1-11A**
**EPA METHOD TO-15 GC/MS**

| | | | |
|---|---|---|---|
| **File Name:** | **14012303** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 1/23/13 10:08 PM** | |

| Compound | %Recovery |
|---|---|
| Freon 12 | 105 |
| Freon 114 | 104 |
| Chloromethane | 120 |
| Vinyl Chloride | 105 |
| 1,3-Butadiene | 110 |
| Bromomethane | 109 |
| Chloroethane | 102 |
| Freon 11 | 108 |
| Ethanol | 133 Q |
| Freon 113 | 101 |
| 1,1-Dichloroethene | 118 |
| Acetone | 104 |
| 2-Propanol | 125 |
| Carbon Disulfide | 116 |
| 3-Chloropropene | 108 |
| Methylene Chloride | 106 |
| Methyl tert-butyl ether | 108 |
| trans-1,2-Dichloroethene | 119 |
| Hexane | 103 |
| 1,1-Dichloroethane | 104 |
| 2-Butanone (Methyl Ethyl Ketone) | 99 |
| cis-1,2-Dichloroethene | 101 |
| Tetrahydrofuran | 106 |
| Chloroform | 108 |
| 1,1,1-Trichloroethane | 102 |
| Cyclohexane | 102 |
| Carbon Tetrachloride | 105 |
| 2,2,4-Trimethylpentane | 104 |
| Benzene | 101 |
| 1,2-Dichloroethane | 105 |
| Heptane | 100 |
| Trichloroethene | 101 |
| 1,2-Dichloropropane | 99 |
| 1,4-Dioxane | 104 |
| Bromodichloromethane | 102 |
| cis-1,3-Dichloropropene | 99 |
| 4-Methyl-2-pentanone | 103 |
| Toluene | 96 |
| trans-1,3-Dichloropropene | 98 |
| 1,1,2-Trichloroethane | 99 |
| Tetrachloroethene | 98 |
| 2-Hexanone | 104 |

**Client Sample ID: LCS**
**Lab ID#: 1301399AR1-11A**
**EPA METHOD TO-15 GC/MS**

| | | | |
|---|---|---|---|
| **File Name:** | **14012303** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 1/23/13 10:08 PM** | |

| Compound | %Recovery |
|---|---|
| Dibromochloromethane | 99 |
| 1,2-Dibromoethane (EDB) | 101 |
| Chlorobenzene | 97 |
| Ethyl Benzene | 95 |
| m,p-Xylene | 100 |
| o-Xylene | 99 |
| Styrene | 100 |
| Bromoform | 98 |
| Cumene | 102 |
| 1,1,2,2-Tetrachloroethane | 104 |
| Propylbenzene | 104 |
| 4-Ethyltoluene | 100 |
| 1,3,5-Trimethylbenzene | 103 |
| 1,2,4-Trimethylbenzene | 100 |
| 1,3-Dichlorobenzene | 97 |
| 1,4-Dichlorobenzene | 95 |
| alpha-Chlorotoluene | 97 |
| 1,2-Dichlorobenzene | 99 |
| 1,2,4-Trichlorobenzene | 87 |
| Hexachlorobutadiene | 88 |
| Butane | 115 |
| Isopentane | 120 |

Q = Exceeds Quality Control limits.

**Container Type: NA - Not Applicable**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| 1,2-Dichloroethane-d4 | 105 | 70-130 |
| Toluene-d8 | 102 | 70-130 |
| 4-Bromofluorobenzene | 102 | 70-130 |

eurofins | Air Toxics

**Client Sample ID: LCSD**
**Lab ID#: 1301399AR1-11AA**
**EPA METHOD TO-15 GC/MS**

| | | | |
|---|---|---|---|
| **File Name:** | **14012304** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 1/23/13 10:33 PM** | |

| Compound | %Recovery |
|---|---|
| Freon 12 | 103 |
| Freon 114 | 103 |
| Chloromethane | 117 |
| Vinyl Chloride | 100 |
| 1,3-Butadiene | 106 |
| Bromomethane | 104 |
| Chloroethane | 93 |
| Freon 11 | 105 |
| Ethanol | 118 |
| Freon 113 | 96 |
| 1,1-Dichloroethene | 115 |
| Acetone | 100 |
| 2-Propanol | 121 |
| Carbon Disulfide | 111 |
| 3-Chloropropene | 105 |
| Methylene Chloride | 103 |
| Methyl tert-butyl ether | 106 |
| trans-1,2-Dichloroethene | 111 |
| Hexane | 102 |
| 1,1-Dichloroethane | 102 |
| 2-Butanone (Methyl Ethyl Ketone) | 100 |
| cis-1,2-Dichloroethene | 97 |
| Tetrahydrofuran | 104 |
| Chloroform | 103 |
| 1,1,1-Trichloroethane | 99 |
| Cyclohexane | 100 |
| Carbon Tetrachloride | 104 |
| 2,2,4-Trimethylpentane | 101 |
| Benzene | 96 |
| 1,2-Dichloroethane | 99 |
| Heptane | 96 |
| Trichloroethene | 96 |
| 1,2-Dichloropropane | 96 |
| 1,4-Dioxane | 99 |
| Bromodichloromethane | 98 |
| cis-1,3-Dichloropropene | 96 |
| 4-Methyl-2-pentanone | 107 |
| Toluene | 93 |
| trans-1,3-Dichloropropene | 92 |
| 1,1,2-Trichloroethane | 96 |
| Tetrachloroethene | 94 |
| 2-Hexanone | 100 |

eurofins | Air Toxics

**Client Sample ID: LCSD**
**Lab ID#: 1301399AR1-11AA**
**EPA METHOD TO-15 GC/MS**

| | | | |
|---|---|---|---|
| **File Name:** | **14012304** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 1/23/13 10:33 PM** | |

| Compound | %Recovery |
|---|---|
| Dibromochloromethane | 94 |
| 1,2-Dibromoethane (EDB) | 96 |
| Chlorobenzene | 98 |
| Ethyl Benzene | 94 |
| m,p-Xylene | 96 |
| o-Xylene | 96 |
| Styrene | 95 |
| Bromoform | 95 |
| Cumene | 99 |
| 1,1,2,2-Tetrachloroethane | 101 |
| Propylbenzene | 100 |
| 4-Ethyltoluene | 96 |
| 1,3,5-Trimethylbenzene | 100 |
| 1,2,4-Trimethylbenzene | 96 |
| 1,3-Dichlorobenzene | 93 |
| 1,4-Dichlorobenzene | 90 |
| alpha-Chlorotoluene | 90 |
| 1,2-Dichlorobenzene | 96 |
| 1,2,4-Trichlorobenzene | 81 |
| Hexachlorobutadiene | 81 |
| Butane | 108 |
| Isopentane | 113 |

**Container Type: NA - Not Applicable**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| 1,2-Dichloroethane-d4 | 105 | 70-130 |
| Toluene-d8 | 100 | 70-130 |
| 4-Bromofluorobenzene | 101 | 70-130 |

1301399

# Shell Oil Products Chain Of Custody Record

URS

Air Toxics LTD.
Project Name: Roxana Soil Vapor
Project # 21562850.04001
Lab Vendor #

Please Check Appropriate Box:
☑ ENV. SERVICES ☐ MOTIVA RETAIL ☐ SHELL RETAIL
☐ MOTIVA SD&CN ☐ CONSULTANT ☐ LUBES
☐ SHELL PIPELINE ☐ OTHER

Print Bill To Contact Name: Robert Mooshegian
PO #:
INCIDENT # (ENV SERVICES): 9 7 2 1 6 6 4 0
SAP #: 3 4 0 0 6 1
☐ CHECK IF NO INCIDENT # APPLIES
DATE: 01/23/13 (ASS'D) 1/23/13
PAGE: 1 of 1

SAMPLING COMPANY: URS CORPORATION
LOG CODE:
SITE ADDRESS: Street and City: 900 SOUTH CENTRAL AVE – ROXANA
State: IL
GLOBAL ID NO:
ADDRESS: 1001 HIGHLANDS PLAZA DRIVE WEST - SUITE 300 ST. LOUIS, MO 63110
EDF DELIVERABLE TO (Name, Company, Office Location): Elizabeth Kunkel, URS, St. Louis
PHONE NO: 314-743-4179
E-MAIL: Elizabeth.Kunkel@URSCorp.com
CONSULTANT PROJECT NAME#: Roxana Soil Vapor
Laboratory Address: Air Toxics, LTD 180 Blue Ravine Road, Suite B Folsom, CA 95630-4719
M Currier, E. Arthur
TELEPHONE: 314-429-0100
FAX: 314-429-0402
EDF To Contact E-MAIL: Robert.Mooshegian@urs.com

TURNAROUND TIME (CALENDAR DAYS): SAME DAY
☐ STANDARD (14 DAY) ☐ 5 DAYS ☐ 3 DAYS ☐ 2 DAYS ☐ 24 HOURS ☐ RESULTS NEEDED ON WEEKEND

REQUESTED ANALYSIS

☐ LA - RWQCB REPORT FORMAT ☑ UST AGENCY:
DELIVERABLES ☐ LEVEL 1 ☐ LEVEL 2 ☐ LEVEL 3 ☑ LEVEL 4 ☐ OTHER (SPECIFY)

☑ SHELL CONTRACT RATE APPLIES
☐ STATE REIMBURSEMENT RATE APPLIES
☐ EDD NOT NEEDED
☑ RECEIPT VERIFICATION REQUESTED

Turn Around Time:
☐ Normal
☑ Rush
SAME DAY Specify

Lab Use Only
Pressurized by:
Date:
Pressurization Gas: N2 He

| LAB USE ONLY | Field Sample Identification | SAMPLING DATE | SAMPLING TIME | Canister Number | Canister Pressure/Vacuum Initial | Final | Receipt | Final (psi) | Modified TO-15 + Butane & Isopentane | ASTM D-1946 + Helium | ASTM D-1946 |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 01A | VMP-1-5-012313-R | 01/23/13 | 1140 | 37733 | -29 | -6 | | | X | X | |
| 02A | VMP-1-8.5-012313-R | 01/23/13 | 1145 | 34589 | -29.5 | -6 | | | X | X | |
| 03A | VMP-1-23.5-012313-R | 01/23/13 | 1205 | 37364 | -30 | -6.5 | | | X | X | |
| 04A | VMP-1-38.5-012313-R | 01/23/13 | 1210 | 1040 | -30 | -5 | | | X | X | |
| 05A | VMP-47-5-012313-R | 01/23/13 | 1235 | 3307 | -30 | -6 | | | X | X | |
| 06A | VMP-47-10-012313-R | 01/23/13 | 1240 | 8004 | -30 | -6 | | | X | X | |
| 07A | VMP-47-20-012313-R | 01/23/13 | 1250 | 9314 | -30 | -6 | | | X | X | |
| 08A | VMP-47-30-012313-R | 01/23/13 | 1300 | 94909 | -30 | -6.5 | | | X | X | |

ADDITIONAL NOTES:
- Same day turn around time
- Report results between MDL and RL
- Level IV ECVP

| Relinquished by: (Signature) | Received by: (Signature) | Date | Time |
|---|---|---|---|
| | FEDEX | 1/23/13 | 1730 |
| Relinquished by: (Signature) | Received by: (Signature) | Date | Time |
| | B Wuttke ATC Fedex | 1/24/13 | 0740 |
| Relinquished by: (Signature) | Received by: (Signature) | Date | Time |
| | Custody Seal Intact? (Y) N None Temp N/A | | |

05/2/05 Revision

eurofins | Air Toxics

2/12/2013
Ms. Elizabeth Kunkel
URS Corporation
1001 Highlands Plaza Dr. West
Suite 300
St. Louis MO 63110

Project Name: Roxana Soil Vapor
Project #: 21562850.04001
Workorder #: 1301399BR1

Dear Ms. Elizabeth Kunkel

The following report includes the data for the above referenced project for sample(s) received on 1/24/2013 at Air Toxics Ltd.

The data and associated QC analyzed by Modified ASTM D-1945 are compliant with the project requirements or laboratory criteria with the exception of the deviations noted in the attached case narrative.

Thank you for choosing Air Toxics Ltd. for your air analysis needs. Air Toxics Ltd. is committed to providing accurate data of the highest quality. Please feel free to contact the Project Manager: Kelly Buettner at 916-985-1000 if you have any questions regarding the data in this report.

Regards,

Kelly Buettner
Project Manager

Reviewed
on
2/18/2013

eurofins | Air Toxics

# WORK ORDER #: 1301399BR1

Work Order Summary

| | | | |
|---|---|---|---|
| **CLIENT:** | Ms. Elizabeth Kunkel<br>URS Corporation<br>1001 Highlands Plaza Dr. West<br>Suite 300<br>St. Louis, MO 63110 | **BILL TO:** | Accounts Payable Austin<br>URS Corporation<br>P.O. BOX 203970<br>Austin, TX 78720-1088 |
| **PHONE:** | 314-743-4179 | **P.O. #** | 21562735.00013 |
| **FAX:** | | **PROJECT #** | 21562850.04001 Roxana Soil Vapor |
| **DATE RECEIVED:** | 01/24/2013 | **CONTACT:** | Kelly Buettner |
| **DATE COMPLETED:** | 01/24/2013 | | |
| **DATE REISSUED:** | 02/12/2013 | | |

| FRACTION # | NAME | TEST | RECEIPT VAC./PRES. | FINAL PRESSURE |
|---|---|---|---|---|
| 01A | VMP-1-5-012313-R | Modified ASTM D-1945 | 4.0 "Hg | 15 psi |
| 02A | VMP-1-8.5-012313-R | Modified ASTM D-1945 | 4.0 "Hg | 15 psi |
| 03A | VMP-1-23.5-012313-R | Modified ASTM D-1945 | 6.5 "Hg | 15 psi |
| 04A | VMP-1-38.5-012313-R | Modified ASTM D-1945 | 4.5 "Hg | 15 psi |
| 05A | VMP-47-5-012313-R | Modified ASTM D-1945 | 5.0 "Hg | 15 psi |
| 06A | VMP-47-10-012313-R | Modified ASTM D-1945 | 5.0 "Hg | 15 psi |
| 07A | VMP-47-20-012313-R | Modified ASTM D-1945 | 4.5 "Hg | 15 psi |
| 08A | VMP-47-30-012313-R | Modified ASTM D-1945 | 4.5 "Hg | 15 psi |
| 09A | Lab Blank | Modified ASTM D-1945 | NA | NA |
| 09B | Lab Blank | Modified ASTM D-1945 | NA | NA |
| 10A | LCS | Modified ASTM D-1945 | NA | NA |
| 10AA | LCSD | Modified ASTM D-1945 | NA | NA |

CERTIFIED BY: Heidi Hayes DATE: 02/12/13

Technical Director

Certification numbers: AZ Licensure AZ0775, CA NELAP - 12282CA, NY NELAP - 11291, TX NELAP - T104704434-12-4, UT NELAP CA009332012-3, WA NELAP - C935
Name of Accrediting Agency: NELAP/ORELAP (Oregon Environmental Laboratory Accreditation Program)
Accreditation number: CA300005, Effective date: 10/18/2012, Expiration date: 10/17/2013.
Eurofins Air Toxics Ltd. certifies that the test results contained in this report meet all requirements of the NELAC standards

This report shall not be reproduced, except in full, without the written approval of Eurofins Air Toxics, Inc.

180 BLUE RAVINE ROAD, SUITE B FOLSOM, CA - 9563
(916) 985-1000 . (800) 985-5955 . FAX (916) 985-1020

**LABORATORY NARRATIVE**
**Modified ASTM D-1945**
**URS Corporation**
**Workorder# 1301399BR1**

Eight 1 Liter Summa Canister samples were received on January 24, 2013. The laboratory performed analysis via modified ASTM Method D-1945 for Methane and fixed gases in natural gas using GC/FID or GC/TCD. The method involves direct injection of 1.0 mL of sample.

On the analytical column employed for this analysis, Oxygen coelutes with Argon. The corresponding peak is quantitated as Oxygen.

Since Nitrogen is used to pressurize samples, the reported Nitrogen values are calculated by adding all the sample components and subtracting from 100%.

Method modifications taken to run these samples are summarized in the table below. Specific project requirements may over-ride the ATL modifications.

| *Requirement* | *ASTM D-1945* | *ATL Modifications* |
|---|---|---|
| Normalization | Sum of original values should not differ from 100.0% by more than 1.0%. | Sum of original values may range between 85-115%. Normalization of data not performed. |
| Sample analysis | Equilibrate samples to 20-50° F. above source temperature at field sampling | No heating of samples is performed. |
| Sample calculation | Response factor is calculated using peak height for C5 and lighter compounds. | Peak areas are used for all target analytes to quantitate concentrations. |
| Reference Standard | Concentration should not be < half of nor differ by more than 2 X the concentration of the sample. Run 2 consecutive checks; must agree within 1%. | A minimum 3-point linear calibration is performed. The acceptance criterion is %RSD </= 15%. All target analytes must be within the linear range of calibration (with the exception of O2, N2, and C6+ Hydrocarbons). |
| Sample Injection Volume | 0.50 mL to achieve Methane linearity. | 1.0 mL. |

**Receiving Notes**

There were no receiving discrepancies.

**Analytical Notes**

As per project specific client request the laboratory has reported estimated values for target compound hits that are below the Reporting Limit but greater than the Method Detection Limit. Concentrations that are below the level at which the canister was certified may be false positives.

Due to the linear calibration range of the instrument, the reporting limit for Carbon Monoxide was raised from 0.01 % to 0.05 %.

THE WORKORDER WAS REISSUED ON 02/12/13 TO REPORT ADDITIONAL COMPOUNDS FOR VMP-1-5-012313-R, VMP-1-8.5-012313-R, VMP-1-23.5-012313-R, VMP-1-38.5-012313-R, VMP-47-5-012313-R, VMP-47-10-012313-R, VMP-47-20-012313-R and VMP-47-30-012313-R PER CLIENT REQUEST.

**Definition of Data Qualifying Flags**

Six qualifiers may have been used on the data analysis sheets and indicate as follows:
J - Estimated value.
E - Exceeds instrument calibration range.
S - Saturated peak.
Q - Exceeds quality control limits.
U - Compound analyzed for but not detected above the detection limit.
M - Reported value may be biased due to apparent matrix interferences.

File extensions may have been used on the data analysis sheets and indicates as follows:
a-File was requantified
b-File was quantified by a second column and detector
r1-File was requantified for the purpose of reissue

eurofins | Air Toxics

# Summary of Detected Compounds
# NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1945

**Client Sample ID: VMP-1-5-012313-R**

**Lab ID#: 1301399BR1-01A**

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.23 | 16 |
| Nitrogen | 0.23 | 78 |
| Methane | 0.00023 | 2.0 |
| Carbon Dioxide | 0.023 | 3.1 |
| Ethane | 0.0023 | 0.00074 J |
| Propane | 0.0023 | 0.00055 J |
| Isobutane | 0.0023 | 0.026 |
| Butane | 0.0023 | 0.28 |
| Neopentane | 0.0023 | 0.0015 J |
| Isopentane | 0.0023 | 0.097 |
| Pentane | 0.0023 | 0.028 |
| C6+ | 0.023 | 0.054 |

**Client Sample ID: VMP-1-8.5-012313-R**

**Lab ID#: 1301399BR1-02A**

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.23 | 16 |
| Nitrogen | 0.23 | 81 |
| Methane | 0.00023 | 0.081 |
| Carbon Dioxide | 0.023 | 3.3 |
| Isobutane | 0.0023 | 0.00077 J |
| Butane | 0.0023 | 0.0085 |
| Isopentane | 0.0023 | 0.0029 |
| Pentane | 0.0023 | 0.00083 J |
| C6+ | 0.023 | 0.0014 J |

**Client Sample ID: VMP-1-23.5-012313-R**

**Lab ID#: 1301399BR1-03A**

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.26 | 4.8 |
| Nitrogen | 0.26 | 76 |

eurofins | Air Toxics

# Summary of Detected Compounds
# NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1945

**Client Sample ID: VMP-1-23.5-012313-R**

**Lab ID#: 1301399BR1-03A**

| | | |
|---|---|---|
| Methane | 0.00026 | 7.8 |
| Carbon Dioxide | 0.026 | 8.5 |
| Ethane | 0.0026 | 0.0035 |
| Propane | 0.0026 | 0.0029 |
| Isobutane | 0.0026 | 0.14 |
| Butane | 0.0026 | 1.3 |
| Neopentane | 0.0026 | 0.0085 |
| Isopentane | 0.0026 | 0.53 |
| Pentane | 0.0026 | 0.13 |
| C6+ | 0.026 | 0.29 |

**Client Sample ID: VMP-1-38.5-012313-R**

**Lab ID#: 1301399BR1-04A**

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.24 | 14 |
| Nitrogen | 0.24 | 75 |
| Methane | 0.00024 | 6.0 |
| Carbon Dioxide | 0.024 | 3.2 |
| Ethane | 0.0024 | 0.0021 J |
| Propane | 0.0024 | 0.0016 J |
| Isobutane | 0.0024 | 0.074 |
| Butane | 0.0024 | 0.81 |
| Neopentane | 0.0024 | 0.0042 |
| Isopentane | 0.0024 | 0.28 |
| Pentane | 0.0024 | 0.081 |
| C6+ | 0.024 | 0.16 |

**Client Sample ID: VMP-47-5-012313-R**

**Lab ID#: 1301399BR1-05A**

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.24 | 1.7 |
| Nitrogen | 0.24 | 83 |

eurofins | Air Toxics

# Summary of Detected Compounds
# NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1945

**Client Sample ID: VMP-47-5-012313-R**

**Lab ID#: 1301399BR1-05A**

| | | |
|---|---|---|
| Methane | 0.00024 | 3.9 |
| Carbon Dioxide | 0.024 | 11 |
| Ethane | 0.0024 | 0.0012 J |
| Propane | 0.0024 | 0.0016 J |
| Isobutane | 0.0024 | 0.052 |
| Butane | 0.0024 | 0.24 |
| Neopentane | 0.0024 | 0.0035 |
| Isopentane | 0.0024 | 0.18 |
| Pentane | 0.0024 | 0.021 |
| C6+ | 0.024 | 0.12 |

**Client Sample ID: VMP-47-10-012313-R**

**Lab ID#: 1301399BR1-06A**

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.24 | 2.5 |
| Nitrogen | 0.24 | 86 |
| Methane | 0.00024 | 0.14 |
| Carbon Dioxide | 0.024 | 11 |
| Propane | 0.0024 | 0.000089 J |
| Isobutane | 0.0024 | 0.0052 |
| Butane | 0.0024 | 0.014 |
| Neopentane | 0.0024 | 0.00067 J |
| Isopentane | 0.0024 | 0.017 |
| Pentane | 0.0024 | 0.0013 J |
| C6+ | 0.024 | 0.013 J |

**Client Sample ID: VMP-47-20-012313-R**

**Lab ID#: 1301399BR1-07A**

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.24 | 1.5 |
| Nitrogen | 0.24 | 84 |
| Methane | 0.00024 | 2.1 |

eurofins | Air Toxics

# Summary of Detected Compounds
# NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1945

**Client Sample ID: VMP-47-20-012313-R**

**Lab ID#: 1301399BR1-07A**

| | | |
|---|---|---|
| Carbon Dioxide | 0.024 | 12 |
| Ethane | 0.0024 | 0.00061 J |
| Propane | 0.0024 | 0.0010 J |
| Isobutane | 0.0024 | 0.037 |
| Butane | 0.0024 | 0.19 |
| Neopentane | 0.0024 | 0.0025 |
| Isopentane | 0.0024 | 0.13 |
| Pentane | 0.0024 | 0.017 |
| C6+ | 0.024 | 0.083 |

**Client Sample ID: VMP-47-30-012313-R**

**Lab ID#: 1301399BR1-08A**

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.24 | 1.4 |
| Nitrogen | 0.24 | 82 |
| Methane | 0.00024 | 4.9 |
| Carbon Dioxide | 0.024 | 11 |
| Ethane | 0.0024 | 0.0014 J |
| Propane | 0.0024 | 0.0018 J |
| Isobutane | 0.0024 | 0.056 |
| Butane | 0.0024 | 0.26 |
| Neopentane | 0.0024 | 0.0046 |
| Isopentane | 0.0024 | 0.19 |
| Pentane | 0.0024 | 0.023 |
| C6+ | 0.024 | 0.12 |

eurofins | Air Toxics

**Client Sample ID: VMP-1-5-012313-R**

**Lab ID#: 1301399BR1-01A**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1945**

| | | | |
|---|---|---|---|
| **File Name:** | **9012407r1** | **Date of Collection:** | **1/23/13 11:40:00 AM** |
| **Dil. Factor:** | **2.33** | **Date of Analysis:** | **1/24/13 09:55 AM** |

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.23 | 16 |
| Nitrogen | 0.23 | 78 |
| Carbon Monoxide | 0.12 | Not Detected |
| Methane | 0.00023 | 2.0 |
| Carbon Dioxide | 0.023 | 3.1 |
| Ethane | 0.0023 | 0.00074 J |
| Ethene | 0.0023 | Not Detected |
| Acetylene | 0.0023 | Not Detected |
| Propane | 0.0023 | 0.00055 J |
| Isobutane | 0.0023 | 0.026 |
| Butane | 0.0023 | 0.28 |
| Neopentane | 0.0023 | 0.0015 J |
| Isopentane | 0.0023 | 0.097 |
| Pentane | 0.0023 | 0.028 |
| C6+ | 0.023 | 0.054 |
| Helium | 0.12 | Not Detected |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

eurofins | Air Toxics

**Client Sample ID: VMP-1-8.5-012313-R**

**Lab ID#: 1301399BR1-02A**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1945**

| | | | |
|---|---|---|---|
| **File Name:** | **9012406r1** | **Date of Collection:** | **1/23/13 11:45:00 AM** |
| **Dil. Factor:** | **2.33** | **Date of Analysis:** | **1/24/13 09:33 AM** |

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.23 | 16 |
| Nitrogen | 0.23 | 81 |
| Carbon Monoxide | 0.12 | Not Detected |
| Methane | 0.00023 | 0.081 |
| Carbon Dioxide | 0.023 | 3.3 |
| Ethane | 0.0023 | Not Detected |
| Ethene | 0.0023 | Not Detected |
| Acetylene | 0.0023 | Not Detected |
| Propane | 0.0023 | Not Detected |
| Isobutane | 0.0023 | 0.00077 J |
| Butane | 0.0023 | 0.0085 |
| Neopentane | 0.0023 | Not Detected |
| Isopentane | 0.0023 | 0.0029 |
| Pentane | 0.0023 | 0.00083 J |
| C6+ | 0.023 | 0.0014 J |
| Helium | 0.12 | Not Detected |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

eurofins | Air Toxics

**Client Sample ID: VMP-1-23.5-012313-R**

**Lab ID#: 1301399BR1-03A**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1945**

| | | | |
|---|---|---|---|
| **File Name:** | **9012408r1** | **Date of Collection:** | **1/23/13 12:05:00 PM** |
| **Dil. Factor:** | **2.58** | **Date of Analysis:** | **1/24/13 10:17 AM** |

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.26 | 4.8 |
| Nitrogen | 0.26 | 76 |
| Carbon Monoxide | 0.13 | Not Detected |
| Methane | 0.00026 | 7.8 |
| Carbon Dioxide | 0.026 | 8.5 |
| Ethane | 0.0026 | 0.0035 |
| Ethene | 0.0026 | Not Detected |
| Acetylene | 0.0026 | Not Detected |
| Propane | 0.0026 | 0.0029 |
| Isobutane | 0.0026 | 0.14 |
| Butane | 0.0026 | 1.3 |
| Neopentane | 0.0026 | 0.0085 |
| Isopentane | 0.0026 | 0.53 |
| Pentane | 0.0026 | 0.13 |
| C6+ | 0.026 | 0.29 |
| Helium | 0.13 | Not Detected |

**Container Type: 1 Liter Summa Canister**

eurofins | Air Toxics

**Client Sample ID: VMP-1-38.5-012313-R**

**Lab ID#: 1301399BR1-04A**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1945**

| | | | |
|---|---|---|---|
| **File Name:** | **9012409r1** | **Date of Collection:** | **1/23/13 12:10:00 PM** |
| **Dil. Factor:** | **2.38** | **Date of Analysis:** | **1/24/13 10:42 AM** |

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.24 | 14 |
| Nitrogen | 0.24 | 75 |
| Carbon Monoxide | 0.12 | Not Detected |
| Methane | 0.00024 | 6.0 |
| Carbon Dioxide | 0.024 | 3.2 |
| Ethane | 0.0024 | 0.0021 J |
| Ethene | 0.0024 | Not Detected |
| Acetylene | 0.0024 | Not Detected |
| Propane | 0.0024 | 0.0016 J |
| Isobutane | 0.0024 | 0.074 |
| Butane | 0.0024 | 0.81 |
| Neopentane | 0.0024 | 0.0042 |
| Isopentane | 0.0024 | 0.28 |
| Pentane | 0.0024 | 0.081 |
| C6+ | 0.024 | 0.16 |
| Helium | 0.12 | Not Detected |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

eurofins | Air Toxics

**Client Sample ID: VMP-47-5-012313-R**

**Lab ID#: 1301399BR1-05A**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1945**

| | | | |
|---|---|---|---|
| **File Name:** | **9012410r1** | **Date of Collection:** | **1/23/13 12:35:00 PM** |
| **Dil. Factor:** | **2.42** | **Date of Analysis:** | **1/24/13 11:08 AM** |

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.24 | 1.7 |
| Nitrogen | 0.24 | 83 |
| Carbon Monoxide | 0.12 | Not Detected |
| Methane | 0.00024 | 3.9 |
| Carbon Dioxide | 0.024 | 11 |
| Ethane | 0.0024 | 0.0012 J |
| Ethene | 0.0024 | Not Detected |
| Acetylene | 0.0024 | Not Detected |
| Propane | 0.0024 | 0.0016 J |
| Isobutane | 0.0024 | 0.052 |
| Butane | 0.0024 | 0.24 |
| Neopentane | 0.0024 | 0.0035 |
| Isopentane | 0.0024 | 0.18 |
| Pentane | 0.0024 | 0.021 |
| C6+ | 0.024 | 0.12 |
| Helium | 0.12 | Not Detected |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

eurofins | Air Toxics

**Client Sample ID: VMP-47-10-012313-R**

**Lab ID#: 1301399BR1-06A**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1945**

| | | | |
|---|---|---|---|
| **File Name:** | **9012411r1** | **Date of Collection:** | **1/23/13 12:40:00 PM** |
| **Dil. Factor:** | **2.42** | **Date of Analysis:** | **1/24/13 11:30 AM** |

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.24 | 2.5 |
| Nitrogen | 0.24 | 86 |
| Carbon Monoxide | 0.12 | Not Detected |
| Methane | 0.00024 | 0.14 |
| Carbon Dioxide | 0.024 | 11 |
| Ethane | 0.0024 | Not Detected |
| Ethene | 0.0024 | Not Detected |
| Acetylene | 0.0024 | Not Detected |
| Propane | 0.0024 | 0.000089 J |
| Isobutane | 0.0024 | 0.0052 |
| Butane | 0.0024 | 0.014 |
| Neopentane | 0.0024 | 0.00067 J |
| Isopentane | 0.0024 | 0.017 |
| Pentane | 0.0024 | 0.0013 J |
| C6+ | 0.024 | 0.013 J |
| Helium | 0.12 | Not Detected |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

eurofins | Air Toxics

**Client Sample ID: VMP-47-20-012313-R**

**Lab ID#: 1301399BR1-07A**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1945**

| | | | |
|---|---|---|---|
| **File Name:** | **9012412r1** | **Date of Collection:** | **1/23/13 12:50:00 PM** |
| **Dil. Factor:** | **2.38** | **Date of Analysis:** | **1/24/13 12:03 PM** |

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.24 | 1.5 |
| Nitrogen | 0.24 | 84 |
| Carbon Monoxide | 0.12 | Not Detected |
| Methane | 0.00024 | 2.1 |
| Carbon Dioxide | 0.024 | 12 |
| Ethane | 0.0024 | 0.00061 J |
| Ethene | 0.0024 | Not Detected |
| Acetylene | 0.0024 | Not Detected |
| Propane | 0.0024 | 0.0010 J |
| Isobutane | 0.0024 | 0.037 |
| Butane | 0.0024 | 0.19 |
| Neopentane | 0.0024 | 0.0025 |
| Isopentane | 0.0024 | 0.13 |
| Pentane | 0.0024 | 0.017 |
| C6+ | 0.024 | 0.083 |
| Helium | 0.12 | Not Detected |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

eurofins | Air Toxics

**Client Sample ID: VMP-47-30-012313-R**

**Lab ID#: 1301399BR1-08A**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1945**

| | | | |
|---|---|---|---|
| **File Name:** | **9012413r1** | **Date of Collection:** | **1/23/13 1:00:00 PM** |
| **Dil. Factor:** | **2.38** | **Date of Analysis:** | **1/24/13 12:29 PM** |

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.24 | 1.4 |
| Nitrogen | 0.24 | 82 |
| Carbon Monoxide | 0.12 | Not Detected |
| Methane | 0.00024 | 4.9 |
| Carbon Dioxide | 0.024 | 11 |
| Ethane | 0.0024 | 0.0014 J |
| Ethene | 0.0024 | Not Detected |
| Acetylene | 0.0024 | Not Detected |
| Propane | 0.0024 | 0.0018 J |
| Isobutane | 0.0024 | 0.056 |
| Butane | 0.0024 | 0.26 |
| Neopentane | 0.0024 | 0.0046 |
| Isopentane | 0.0024 | 0.19 |
| Pentane | 0.0024 | 0.023 |
| C6+ | 0.024 | 0.12 |
| Helium | 0.12 | Not Detected |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

eurofins | Air Toxics

**Client Sample ID: Lab Blank**

**Lab ID#: 1301399BR1-09A**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1945**

| | | | |
|---|---|---|---|
| **File Name:** | **9012405a** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 1/24/13 09:05 AM** | |

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.10 | Not Detected |
| Nitrogen | 0.10 | 0.078 J |
| Carbon Monoxide | 0.050 | Not Detected |
| Methane | 0.00010 | Not Detected |
| Carbon Dioxide | 0.010 | Not Detected |
| Ethane | 0.0010 | Not Detected |
| Ethene | 0.0010 | Not Detected |
| Acetylene | 0.0010 | Not Detected |
| Propane | 0.0010 | Not Detected |
| Isobutane | 0.0010 | Not Detected |
| Butane | 0.0010 | Not Detected |
| Neopentane | 0.0010 | Not Detected |
| Isopentane | 0.0010 | Not Detected |
| Pentane | 0.0010 | Not Detected |
| C6+ | 0.010 | Not Detected |

J = Estimated value.

**Container Type: NA - Not Applicable**

eurofins | Air Toxics

**Client Sample ID: Lab Blank**

**Lab ID#: 1301399BR1-09B**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1945**

| | | | |
|---|---|---|---|
| File Name: | 9012403b | Date of Collection: NA | |
| Dil. Factor: | 1.00 | Date of Analysis: 1/24/13 08:15 AM | |

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Helium | 0.050 | Not Detected |

**Container Type: NA - Not Applicable**

eurofins | Air Toxics

**Client Sample ID: LCS**

**Lab ID#: 1301399BR1-10A**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1945**

| | | | |
|---|---|---|---|
| **File Name:** | **9012402** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 1/24/13 07:44 AM** | |

| Compound | %Recovery |
|---|---|
| Oxygen | 100 |
| Nitrogen | 100 |
| Carbon Monoxide | 101 |
| Methane | 90 |
| Carbon Dioxide | 101 |
| Ethane | 92 |
| Ethene | 89 |
| Acetylene | 91 |
| Propane | 94 |
| Isobutane | 95 |
| Butane | 93 |
| Neopentane | 94 |
| Isopentane | 93 |
| Pentane | 93 |
| C6+ | 92 |
| Helium | 99 |

**Container Type: NA - Not Applicable**

eurofins | Air Toxics

**Client Sample ID: LCSD**

**Lab ID#: 1301399BR1-10AA**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1945**

| | | | |
|---|---|---|---|
| **File Name:** | **9012414** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 1/24/13 01:08 PM** | |

| Compound | %Recovery |
|---|---|
| Oxygen | 101 |
| Nitrogen | 100 |
| Carbon Monoxide | 102 |
| Methane | 97 |
| Carbon Dioxide | 101 |
| Ethane | 99 |
| Ethene | 96 |
| Acetylene | 97 |
| Propane | 101 |
| Isobutane | 102 |
| Butane | 100 |
| Neopentane | 101 |
| Isopentane | 99 |
| Pentane | 99 |
| C6+ | 98 |
| Helium | 101 |

**Container Type: NA - Not Applicable**

1301399

# Shell Oil Products Chain Of Custody Record

URS

Air Toxics LTD.
Project Name: Roxana Soil Vapor
Project # 21562850.04001
Lab Vendor #

Please Check Appropriate Box:
☑ ENV. SERVICES ☐ MOTIVA RETAIL ☐ SHELL RETAIL
☐ MOTIVA SD&CM ☐ CONSULTANT ☐ LUBES
☐ SHELL PIPELINE ☐ OTHER

Print Bill To Contact Name: Robert Mooshegian
INCIDENT # (ENV SERVICES): 9 7 2 1 6 6 4 0 ☐ CHECK IF NO INCIDENT # APPLIES
RO #:
SAP #: 3 4 0 0 6 1
DATE: 01/23/13 1/23/13
PAGE: 1 of 1

SAMPLING COMPANY: URS CORPORATION
LOG CODE:
SITE ADDRESS, Street and City: 900 SOUTH CENTRAL AVE -- ROXANA
State: IL
GLOBAL ID NO:
ADDRESS: 1001 HIGHLANDS PLAZA DRIVE WEST - SUITE 300 ST LOUIS, MO 63110
PROJECT MANAGER (DELIVERABLE TO Name, Company, Office Location): Elizabeth Kunkel, URS, St. Louis
PHONE NO.: 314-743-4179
E-MAIL: Elizabeth_Kunkel@URSCorp.com
CONSULTANT PROJECT NAME: Roxana Soil Vapor
Attention: M. Curner, E. Arthur
Attorney Address: Air Toxics, LTD 180 Blue Ravine Road, Suite B Folsom, CA 95630-4719
TELEPHONE: 314-429-0100
FAX: 314-429-0462
RE To Contact E-MAIL: Robert.Mooshegian@urs.com

TURNAROUND TIME (CALENDAR DAYS): SAME DAY
☐ STANDARD (14 DAY) ☐ 5 DAYS ☐ 3 DAYS ☐ 2 DAYS ☐ 24 HOURS ☐ RESULTS NEEDED ON WEEKEND

REQUESTED ANALYSIS

☐ LA - RWQCB REPORT FORMAT ☑ UST AGENCY:
DELIVERABLES ☐ LEVEL 1 ☐ LEVEL 2 ☐ LEVEL 3 ☑ LEVEL 4 ☐ OTHER (SPECIFY)

☑ SHELL CONTRACT RATE APPLIES
☐ STATE REIMBURSEMENT RATE APPLIES
☐ EDD NOT NEEDED
☑ RECEIPT VERIFICATION REQUESTED

Turn Around Time: ☐ Normal ☑ Rush SAME DAY Specify

Lab Use Only
Pressurized by:
Date:
Pressurization Gas: $N_2$ He

| Lab Use Only | Field Sample Identification | SAMPLING DATE | SAMPLING TIME | Canister Number | Canister Pressure/Vacuum Initial | Final | Receipt | Final (psi) | Modified TO-15 + Butane & Isopentane | ASTM D-1946 + Hellium | ASTM D-1946 | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| 01A | VMP-1-5-012313-R | 01/23/13 | 1140 | 37733 | -29 | -6 | | | X | X | | | | | | |
| 02A | VMP-1-8.5-012313-R | 01/23/13 | 1145 | 34589 | -29.5 | -6 | | | X | X | | | | | | |
| 03A | VMP-1-23.5-012313-R | 01/23/13 | 1205 | 37364 | -30 | -8.5 | | | X | X | | | | | | |
| 04A | VMP-1-38.5-012313-R | 01/23/13 | 1210 | 1040 | -30 | -5 | | | X | X | | | | | | |
| 05A | VMP-47-5-012313-R | 01/23/13 | 1235 | 3007 | -30 | -6 | | | X | X | | | | | | |
| 06A | VMP-47-10-012313-R | 01/23/13 | 1240 | 8004 | -30 | -6 | | | X | X | | | | | | |
| 07A | VMP-47-20-012313-R | 01/23/13 | 1250 | 9314 | -30 | -6 | | | X | X | | | | | | |
| 08A | VMP-47-30-012313-R | 01/23/13 | 1300 | 94909 | -30 | -6.5 | | | X | X | | | | | | |
| | | | | | | | | | | | | | | | | |
| | | | | | | | | | | | | | | | | |

ADDITIONAL NOTES:
- Same day turn around time
- Report results between MDL and RL
- Level IV ECVP

| | | Date | Time |
|---|---|---|---|
| Relinquished by (Signature) | Received by: (Signature) FEDEX | 1/23/13 | 1730 |
| Relinquished by (Signature) | Received by: (Signature) Fedex | 1/24/13 | 0740 |
| Relinquished by (Signature) | Received by: (Signature) Custody Seal Intact? (Y) N None Temp N/A | Date | Time |

06/2005 Revision

# Roxana Soil Vapor Quarterly – 1st Quarter 2013 Data Review

**Laboratory SDG: 1301501A,B**

**Data Reviewer: Alan Fleisher**

**Peer Reviewer: Elizabeth Kunkel**

**Date Reviewed: 3/19/2013**

**Guidance: USEPA National Functional Guidelines for Superfund Organic Methods Data Review 2008**

| Sample Identification | Sample Identification |
|---|---|
| VMP-5-5-012513 | VMP-5-12.5-012413 |
| VMP-5-31-012413 | VMP-5-40-012513 |
| VMP-5-40-012513-Dup | VMP-8-5-012413 |
| VMP-8-9.5-012413 | VMP-8-9.5-012413-Dup |
| VMP-8-23.5-012413 | VMP-18-8.5-012313 |

## 1.0 Data Package Completeness

*Were all items delivered as specified in the QAPP and COC as appropriate?*

Yes

## 2.0 Laboratory Case Narrative \ Cooler Receipt Form

*Were problems noted in the laboratory case narrative or cooler receipt form?*

Yes, the laboratory case narrative indicated samples VMP-5-31-012413, VMP-5-40-012513, and VMP-5-40-012513-Dup were diluted due to high levels of target analytes. Although not indicated in the laboratory case narrative, analytes were detected in the method blank. The TO-15 LCSD recoveries for 1,2,4-trichlorobenzene were outside evaluation criteria. The difference in butane results for the field duplicate pair, VMP-5-40-012513/VMP-5-40-012513-Dup was greater than (2X) the reporting level; therefore, results were qualified as estimated. CCV recoveries for 1,2,4-trimethylbenzene were outside evaluation criteria. These issues are addressed further in the appropriate sections below.

No issues or discrepancies were noted in the cooler receipt form.

## 3.0 Holding Times

*Were samples extracted/analyzed within applicable limits?*

Yes

## 4.0 Blank Contamination

*Were any analytes detected in the Blanks?*

Yes

| Blank ID | Parameter | Analyte | Concentration/ Amount |
|---|---|---|---|
| 1301501A-11A | TO-15 | Trichloroethene | 0.14 ppbv / 0.78 µg/m$^3$ |
| 1301501A-11A | TO-15 | 2-Hexanone | 0.21 ppbv / 0.85 µg/m$^3$ |
| 1301501A-11A | TO-15 | Styrene | 0.067 ppbv / 0.29 µg/m$^3$ |
| 1301501A-11A | TO-15 | 1,1,2,2-Tetrachloroethane | 0.10 ppbv / 0.69 µg/m$^3$ |
| 1301501A-11A | TO-15 | Propylbenzene | 0.060 ppbv / 0.29 µg/m$^3$ |
| 1301501A-11A | TO-15 | 1,2,4-Trimethylbenzene | 0.090 ppbv / 0.44 µg/m$^3$ |
| 1301501A-11A | TO-15 | 1,3-Dichlorobenzene | 0.15 ppbv / 0.92 µg/m$^3$ |
| 1301501A-11A | TO-15 | 1,4-Dichlorobenzene | 0.24 ppbv / 1.5 µg/m$^3$ |
| 1301501A-11A | TO-15 | alpha-Chlorotoluene | 0.15 ppbv / 0.80 µg/m$^3$ |
| 1301501A-11A | TO-15 | 1,2-Dichlorobenzene | 0.19 ppbv / 1.2 µg/m$^3$ |
| 1301501A-11A | TO-15 | 1,2,4-Trichlorobenzene | 0.74 ppbv / 5.5 µg/m$^3$ |
| 1301501A-11B | TO-15 | Carbon disulfide | 0.39 ppbv / 1.2 µg/m$^3$ |
| 1301501A-11B | TO-15 | Methylene chloride | 0.20 ppbv / 0.70 µg/m$^3$ |
| 1301501A-11B | TO-15 | 1,2-Dichloroethane | 0.087 ppbv / 0.35 µg/m$^3$ |
| 1301501A-11B | TO-15 | cis-1,3-Dichloropropene | 0.10 ppbv / 0.48 µg/m$^3$ |
| 1301501A-11B | TO-15 | trans-1,3-Dichloropropene | 0.18 ppbv / 0.80 µg/m$^3$ |
| 1301501A-11B | TO-15 | Tetrachloroethene | 0.067 ppbv / 0.46 µg/m$^3$ |
| 1301501A-11B | TO-15 | 1,2-Dibromoethane (EDB) | 0.16 ppbv / 1.2 µg/m$^3$ |
| 1301501A-11B | TO-15 | Chlorobenzene | 0.12 ppbv / 0.54 µg/m$^3$ |
| 1301501A-11B | TO-15 | 1,1,2,2-Tetrachloroethane | 0.15 ppbv / 1.0 µg/m$^3$ |
| 1301501A-11B | TO-15 | Propylbenzene | 0.12 ppbv / 0.57 µg/m$^3$ |
| 1301501A-11B | TO-15 | 4-Ethyltoluene | 0.11 ppbv / 0.55 µg/m$^3$ |
| 1301501A-11B | TO-15 | 1,2,4-Trimethylbenzene | 0.095 ppbv / 0.47 µg/m$^3$ |
| 1301501A-11B | TO-15 | 1,3-Dichlorobenzene | 0.28 ppbv / 1.7 µg/m$^3$ |
| 1301501A-11B | TO-15 | 1,4-Dichlorobenzene | 0.27 ppbv / 1.6 µg/m$^3$ |
| 1301501A-11B | TO-15 | alpha-Chlorotoluene | 0.15 ppbv / 0.77 µg/m$^3$ |
| 1301501A-11B | TO-15 | 1,2-Dichlorobenzene | 0.25 ppbv / 1.5 µg/m$^3$ |
| 1301501A-11B | TO-15 | 1,2,4-Trichlorobenzene | 0.70 ppbv / 5.2 µg/m$^3$ |
| 1301501A-11B | TO-15 | Hexachlorobutadiene | 0.42 ppbv / 4.5 µg/m$^3$ |
| 1301501B-11A | Natural gases | Oxygen | 0.031% |
| 1301501B-11A | Natural gases | Nitrogen | 0.084% |

Qualifications due to blank contamination are included in the table below. Analytical data that were reported non-detect or at concentrations greater than five times (5X) the associated blank concentration did not require qualification.

| Sample ID | Parameter | Analyte | New Reporting Limit (RL) | Qualification |
|---|---|---|---|---|
| VMP-8-5-012413 | TO-15 | Methylene chloride | - | **U** |
| VMP-8-5-012413 | TO-15 | 1,4-Dichlorobenzene | - | **U** |
| VMP-8-9.5-012413 | TO-15 | Methylene chloride | - | **U** |
| VMP-8-9.5-012413 | TO-15 | Tetrachloroethene | - | **U** |
| VMP-8-9.5-012413 | TO-15 | 1,4-Dichlorobenzene | - | **U** |
| VMP-8-9.5-012413-Dup | TO-15 | Methylene chloride | - | **U** |

| Sample ID | Parameter | Analyte | New Reporting Limit (RL) | Qualification |
|---|---|---|---|---|
| VMP-8-9.5-012413-Dup | TO-15 | Tetrachloroethene | - | **U** |
| VMP-8-23.5-012413 | TO-15 | Carbon disulfide | - | **U** |
| VMP-8-23.5-012413 | TO-15 | Methylene chloride | - | **U** |
| VMP-18-18.5-012313 | TO-15 | Methylene chloride | - | **U** |

## 5.0 Laboratory Control Sample

*Were LCS recoveries within evaluation criteria?*

No

| LCS/LCSD ID | Parameter | Analyte | LCS/LCSD Recovery | LCS/ LCSD RPD | LCS/LCSD /RPD Criteria |
|---|---|---|---|---|---|
| 1301501A-13A/AA | TO-15 | 1,2,4-Trichlorobenzene | 70**/69** | 1 | 70-130/25 |
| 1301501A-13B/BB | TO-15 | 1,2,4-Trichlorobenzene | 129/**131** | 2 | 70-130/25 |

Analytical data that required qualification based on LCS data are included in the table below. Analytical data reported as non-detect and associated with LCS recoveries above evaluation criteria, indicating a possible high bias, did not require qualification.

| Sample ID | Parameter | Analyte | Qualification |
|---|---|---|---|
| VMP-5-5-012513 | TO-15 | 1,2,4-Trichlorobenzene | **UJ** |
| VMP-5-12.5-012413 | TO-15 | 1,2,4-Trichlorobenzene | **UJ** |
| VMP-5-31-012413 | TO-15 | 1,2,4-Trichlorobenzene | **UJ** |

## 6.0 Surrogate Recoveries

*Were surrogate recoveries within evaluation criteria?*

Yes

## 7.0 Matrix Spike and Matrix Spike Duplicate Recoveries

*Were MS/MSD samples analyzed as part of this SDG?*

MS/MSD samples are not applicable for vapor samples, due to the inability to spike the samples.

## 8.0 Laboratory Duplicate Results

*Were laboratory duplicate samples collected as part of this SDG?*

No

## 9.0 Field Duplicate Results

*Were field duplicate samples collected as part of this SDG?*

Yes

| Field ID | Field Duplicate ID |
|---|---|
| VMP-5-40-012513 | VMP-5-40-012513-Dup |
| VMP-8-9.5-012413 | VMP-8-9.5-012413-Dup |

*Were field duplicate sample RPDs within evaluation criteria?*

No

| Field ID | Field Duplicate ID | Parameter | Analyte | RPD | Qualification |
|---|---|---|---|---|---|
| VMP-5-40-012513 | VMP-5-40-012513-Dup | TO-15 | Butane | **>2X RL** | **J/J** |

## 10.0 Sample Dilutions

*For samples that were diluted and nondetect, were undiluted results also reported?*

Not applicable; analytes were detected in samples that were diluted.

## 11.0 Additional Qualifications

*Were additional qualifications applied?*

Yes, continuing calibration verification (CCV) recoveries listed in the table below were above evaluation criteria.

| CCV ID | Parameter | Analyte | CCV Recovery | CCV Criteria |
|---|---|---|---|---|
| 1301501A-12B | TO-15 | 1,2,4-Trimethylbenzene | **131** | 70-130 |

Analytical data reported as non-detect and associated with CCV recoveries above evaluation criteria, indicating a possible high bias, did not require qualification. No qualification of data was required.

eurofins | Air Toxics

2/11/2013
Ms. Elizabeth Kunkel
URS Corporation
1001 Highlands Plaza Dr. West
Suite 300
St. Louis MO 63110

Project Name: Roxana Soil Vapor
Project #: 21562850.04001
Workorder #: 1301501A

Dear Ms. Elizabeth Kunkel

The following report includes the data for the above referenced project for sample(s) received on 1/28/2013 at Air Toxics Ltd.

The data and associated QC analyzed by Modified TO-15 are compliant with the project requirements or laboratory criteria with the exception of the deviations noted in the attached case narrative.

Thank you for choosing Air Toxics Ltd. for your air analysis needs. Air Toxics Ltd. is committed to providing accurate data of the highest quality. Please feel free to contact the Project Manager: Kelly Buettner at 916-985-1000 if you have any questions regarding the data in this report.

Regards,

Kelly Buettner

Project Manager

REVIEWED
ON
3/18/13

eurofins | Air Toxics

# WORK ORDER #: 1301501A

Work Order Summary

| | | | |
|---|---|---|---|
| **CLIENT:** | Ms. Elizabeth Kunkel<br>URS Corporation<br>1001 Highlands Plaza Dr. West<br>Suite 300<br>St. Louis, MO 63110 | **BILL TO:** | Accounts Payable Austin<br>URS Corporation<br>P.O. BOX 203970<br>Austin, TX 78720-1088 |
| **PHONE:** | 314-743-4179 | **P.O. #** | 21562735.00013 |
| **FAX:** | | **PROJECT #** | 21562850.04001 Roxana Soil Vapor |
| **DATE RECEIVED:** | 01/28/2013 | **CONTACT:** | Kelly Buettner |
| **DATE COMPLETED:** | 02/11/2013 | | |

| FRACTION # | NAME | TEST | RECEIPT VAC./PRES. | FINAL PRESSURE |
|---|---|---|---|---|
| 01A | VMP-5-5-012513 | Modified TO-15 | 7.0 "Hg | 15 psi |
| 02A | VMP-5-12.5-012413 | Modified TO-15 | 6.5 "Hg | 15 psi |
| 03A | VMP-5-31-012413 | Modified TO-15 | 6.0 "Hg | 15 psi |
| 04A | VMP-5-40-012513 | Modified TO-15 | 6.5 "Hg | 15 psi |
| 05A | VMP-5-40-012513-Dup | Modified TO-15 | 6.0 "Hg | 15 psi |
| 06A | VMP-8-5-012413 | Modified TO-15 | 7.5 "Hg | 15 psi |
| 07A | VMP-8-9.5-012413 | Modified TO-15 | 6.0 "Hg | 15 psi |
| 08A | VMP-8-9.5-012413-Dup | Modified TO-15 | 7.5 "Hg | 15 psi |
| 09A | VMP-8-23.5-012413 | Modified TO-15 | 9.0 "Hg | 15 psi |
| 10A | VMP-18-8.5-012313 | Modified TO-15 | 9.0 "Hg | 15 psi |
| 11A | Lab Blank | Modified TO-15 | NA | NA |
| 11B | Lab Blank | Modified TO-15 | NA | NA |
| 12A | CCV | Modified TO-15 | NA | NA |
| 12B | CCV | Modified TO-15 | NA | NA |
| 13A | LCS | Modified TO-15 | NA | NA |
| 13AA | LCSD | Modified TO-15 | NA | NA |
| 13B | LCS | Modified TO-15 | NA | NA |
| 13BB | LCSD | Modified TO-15 | NA | NA |

CERTIFIED BY: Heidi Hayes DATE: 02/11/13

Technical Director

Certfication numbers: AZ Licensure AZ0775, CA NELAP - 12282CA, NY NELAP - 11291, TX NELAP - T104704434-12-5, UT NELAP CA009332012-3, WA NELAP - C935
Name of Accrediting Agency: NELAP/ORELAP (Oregon Environmental Laboratory Accreditation Program)
Accreditation number: CA300005, Effective date: 10/18/2011, Expiration date: 10/17/2012.
Eurofins Air Toxics Ltd. certifies that the test results contained in this report meet all requirements of the NELAC standards

This report shall not be reproduced, except in full, without the written approval of Eurofins Air Toxics, Inc.

180 BLUE RAVINE ROAD, SUITE B FOLSOM, CA - 9563
(916) 985-1000 . (800) 985-5955 . FAX (916) 985-1020

eurofins | Air Toxics

**LABORATORY NARRATIVE**
**EPA Method TO-15**
**URS Corporation**
**Workorder# 1301501A**

Ten 1 Liter Summa Canister samples were received on January 28, 2013. The laboratory performed analysis via EPA Method TO-15 using GC/MS in the full scan mode.

This workorder was independently validated prior to submittal using 'USEPA National Functional Guidelines' as generally applied to the analysis of volatile organic compounds in air. A rules-based, logic driven, independent validation engine was employed to assess completeness, evaluate pass/fail of relevant project quality control requirements and verification of all quantified amounts.

**Receiving Notes**

There were no receiving discrepancies.

**Analytical Notes**

As per client project requirements, the laboratory has reported estimated values for target compound hits that are below the Reporting Limit but greater than the Method Detection Limit. Concentrations that are below the level at which the canister was certified may be false positives.

Dilution was performed on samples VMP-5-31-012413, VMP-5-40-012513, and VMP-5-40-012513-Dup due to the presence of high level target species.

All Quality Control Limit exceedances and affected sample results are noted by flags. Each flag is defined at the bottom of this Case Narrative and on each Sample Result Summary page. Target compound non-detects in the samples that are associated with high bias in QC analyses have not been flagged.

**Definition of Data Qualifying Flags**

Eight qualifiers may have been used on the data analysis sheets and indicates as follows:

B - Compound present in laboratory blank greater than reporting limit (background subtraction not performed).
J - Estimated value.
E - Exceeds instrument calibration range.
S - Saturated peak.
Q - Exceeds quality control limits.
U - Compound analyzed for but not detected above the reporting limit.
UJ- Non-detected compound associated with low bias in the CCV and/or LCS.
N - The identification is based on presumptive evidence.

File extensions may have been used on the data analysis sheets and indicates as follows:
a-File was requantified
b-File was quantified by a second column and detector
r1-File was requantified for the purpose of reissue

eurofins | Air Toxics

# Summary of Detected Compounds
# EPA METHOD TO-15 GC/MS FULL SCAN

**Client Sample ID: VMP-5-5-012513**

**Lab ID#: 1301501A-01A**

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 1.3 | 0.37 J | 6.5 | 1.8 J |
| Ethanol | 5.3 | 2.5 J | 9.9 | 4.7 J |
| Acetone | 13 | 4.9 J | 31 | 12 J |
| 2-Propanol | 5.3 | 80 | 13 | 200 |
| 2,2,4-Trimethylpentane | 1.3 | 0.43 J | 6.2 | 2.0 J |
| Benzene | 1.3 | 4.3 | 4.2 | 14 |
| Isopentane | 5.3 | 0.98 J | 16 | 2.9 J |

**Client Sample ID: VMP-5-12.5-012413**

**Lab ID#: 1301501A-02A**

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 11 | 1.3 | 0.21 J | 7.2 | 1.2 J |
| Ethanol | 5.2 | 2.3 J | 9.7 | 4.3 J |
| Acetone | 13 | 10 J | 31 | 24 J |
| 2-Propanol | 5.2 | 110 | 13 | 270 |
| 2,2,4-Trimethylpentane | 1.3 | 1.7 | 6.0 | 7.9 |
| Benzene | 1.3 | 0.66 J | 4.1 | 2.1 J |
| Toluene | 1.3 | 0.20 J | 4.9 | 0.74 J |
| Isopentane | 5.2 | 0.72 J | 15 | 2.1 J |

**Client Sample ID: VMP-5-31-012413**

**Lab ID#: 1301501A-03A**

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Acetone | 140 | 20 J | 330 | 49 J |
| 2-Propanol | 56 | 3100 | 140 | 7500 |
| Hexane | 14 | 10 J | 49 | 36 J |
| Chloroform | 14 | 4.9 J | 68 | 24 J |
| Cyclohexane | 14 | 4.4 J | 48 | 15 J |
| 2,2,4-Trimethylpentane | 14 | 27 | 65 | 130 |
| Butane | 56 | 58 | 130 | 140 |
| Isopentane | 56 | 66 | 160 | 190 |

eurofins | Air Toxics

# Summary of Detected Compounds
# EPA METHOD TO-15 GC/MS FULL SCAN

**Client Sample ID: VMP-5-31-012413**

**Lab ID#: 1301501A-03A**

**Client Sample ID: VMP-5-40-012513**

**Lab ID#: 1301501A-04A**

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Acetone | 43 | 150 | 100 | 350 |
| 2-Propanol | 17 | 760 | 42 | 1900 |
| Methylene Chloride | 43 | 3.9 J | 150 | 14 J |
| Hexane | 4.3 | 7.5 | 15 | 26 |
| Chloroform | 4.3 | 8.3 | 21 | 40 |
| Cyclohexane | 4.3 | 5.1 | 15 | 18 |
| 2,2,4-Trimethylpentane | 4.3 | 360 | 20 | 1700 |
| Benzene | 4.3 | 1.2 J | 14 | 3.7 J |
| Heptane | 4.3 | 2.6 J | 18 | 10 J |
| Butane | 17 | 89 | 41 | 210 |
| Isopentane | 17 | 240 | 51 | 700 |

**Client Sample ID: VMP-5-40-012513-Dup**

**Lab ID#: 1301501A-05A**

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Acetone | 42 | 150 | 100 | 360 |
| 2-Propanol | 17 | 800 | 41 | 2000 |
| Methylene Chloride | 42 | 1.5 J | 140 | 5.4 J |
| Hexane | 4.2 | 3.6 J | 15 | 13 J |
| Chloroform | 4.2 | 8.8 | 20 | 43 |
| Cyclohexane | 4.2 | 1.7 J | 14 | 5.9 J |
| 2,2,4-Trimethylpentane | 4.2 | 370 | 20 | 1700 |
| Benzene | 4.2 | 1.2 J | 13 | 3.7 J |
| Butane | 17 | 44 | 40 | 100 |
| Isopentane | 17 | 180 | 50 | 530 |

**Client Sample ID: VMP-8-5-012413**

**Lab ID#: 1301501A-06A**

eurofins | Air Toxics

# Summary of Detected Compounds
# EPA METHOD TO-15 GC/MS FULL SCAN

**Client Sample ID: VMP-8-5-012413**

**Lab ID#: 1301501A-06A**

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 1.3 | 0.50 J | 6.6 | 2.5 J |
| Freon 11 | 1.3 | 0.25 J | 7.6 | 1.4 J |
| Ethanol | 5.4 | 2.0 J | 10 | 3.8 J |
| Acetone | 13 | 25 | 32 | 60 |
| 2-Propanol | 5.4 | 2.7 J | 13 | 6.6 J |
| Carbon Disulfide | 5.4 | ~~1.4 J~~ | 17 | ~~4.4 J~~ |
| Methylene Chloride | 13 | 1.4 J | 47 | 4.8 J |
| 2-Butanone (Methyl Ethyl Ketone) | 5.4 | 14 | 16 | 41 |
| Tetrahydrofuran | 1.3 | 1.4 | 4.0 | 4.1 |
| 2,2,4-Trimethylpentane | 1.3 | 0.21 J | 6.3 | 1.0 J |
| Benzene | 1.3 | 0.24 J | 4.3 | 0.77 J |
| 4-Methyl-2-pentanone | 1.3 | 0.68 J | 5.5 | 2.8 J |
| Toluene | 1.3 | 0.37 J | 5.1 | 1.4 J |
| 1,4-Dichlorobenzene | 1.3 | ~~0.20 J~~ | 8.1 | ~~1.2 J~~ |

**Client Sample ID: VMP-8-9.5-012413**

**Lab ID#: 1301501A-07A**

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 1.3 | 0.55 J | 6.2 | 2.7 J |
| Freon 11 | 1.3 | 0.26 J | 7.1 | 1.5 J |
| Acetone | 13 | 3.3 J | 30 | 7.8 J |
| 2-Propanol | 5.0 | 1.3 J | 12 | 3.2 J |
| Methylene Chloride | 13 | ~~0.47 J~~ | 44 | ~~1.6 J~~ |
| Hexane | 1.3 | 0.52 J | 4.4 | 1.8 J |
| Cyclohexane | 1.3 | 0.43 J | 4.3 | 1.5 J |
| 2,2,4-Trimethylpentane | 1.3 | 0.36 J | 5.9 | 1.7 J |
| Benzene | 1.3 | 0.34 J | 4.0 | 1.1 J |
| Tetrachloroethene | 1.3 | ~~0.28 J~~ | 8.5 | ~~1.9 J~~ |
| 1,4-Dichlorobenzene | 1.3 | ~~0.15 J~~ | 7.6 | ~~0.90 J~~ |
| Isopentane | 5.0 | 2.6 J | 15 | 7.7 J |

eurofins | Air Toxics

# Summary of Detected Compounds
# EPA METHOD TO-15 GC/MS FULL SCAN

**Client Sample ID: VMP-8-9.5-012413-Dup**

**Lab ID#: 1301501A-08A**

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 1.3 | 0.59 J | 6.6 | 2.9 J |
| Freon 11 | 1.3 | 0.22 J | 7.6 | 1.2 J |
| Acetone | 13 | 0.91 J | 32 | 2.2 J |
| Methylene Chloride | 13 | ~~0.41 J~~ | 47 | ~~1.4 J~~ |
| Cyclohexane | 1.3 | 0.35 J | 4.6 | 1.2 J |
| 2,2,4-Trimethylpentane | 1.3 | 0.20 J | 6.3 | 0.94 J |
| trans-1,3-Dichloropropene | 1.3 | 0.18 J | 6.1 | 0.81 J |
| Tetrachloroethene | 1.3 | ~~0.23 J~~ | 9.1 | ~~1.6 J~~ |
| Isopentane | 5.4 | 2.1 J | 16 | 6.2 J |

**Client Sample ID: VMP-8-23.5-012413**

**Lab ID#: 1301501A-09A**

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 1.4 | 0.66 J | 7.1 | 3.2 J |
| Freon 11 | 1.4 | 0.32 J | 8.1 | 1.8 J |
| Acetone | 14 | 2.7 J | 34 | 6.4 J |
| Carbon Disulfide | 5.8 | ~~1.2 J~~ | 18 | ~~3.6 J~~ |
| Methylene Chloride | 14 | ~~0.48 J~~ | 50 | ~~1.7 J~~ |
| Benzene | 1.4 | 3.2 | 4.6 | 10 |
| Tetrachloroethene | 1.4 | 0.50 J | 9.8 | 3.4 J |

**Client Sample ID: VMP-18-8.5-012313**

**Lab ID#: 1301501A-10A**

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 1.4 | 0.54 J | 7.1 | 2.7 J |
| Acetone | 14 | 2.1 J | 34 | 5.1 J |
| 2-Propanol | 5.8 | 2.8 J | 14 | 6.9 J |
| Methylene Chloride | 14 | ~~0.40 J~~ | 50 | ~~1.4 J~~ |
| 2,2,4-Trimethylpentane | 1.4 | 2.8 | 6.8 | 13 |
| Benzene | 1.4 | 7.8 | 4.6 | 25 |

eurofins | Air Toxics

**Client Sample ID: VMP-5-5-012513**

**Lab ID#: 1301501A-01A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **2013120** | **Date of Collection:** | **1/25/13 9:52:00 AM** |
| **Dil. Factor:** | **2.64** | **Date of Analysis:** | **2/1/13 08:06 AM** |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 1.3 | 0.37 J | 6.5 | 1.8 J |
| Freon 114 | 1.3 | Not Detected | 9.2 | Not Detected |
| Chloromethane | 13 | Not Detected | 27 | Not Detected |
| Vinyl Chloride | 1.3 | Not Detected | 3.4 | Not Detected |
| 1,3-Butadiene | 1.3 | Not Detected | 2.9 | Not Detected |
| Bromomethane | 13 | Not Detected | 51 | Not Detected |
| Chloroethane | 5.3 | Not Detected | 14 | Not Detected |
| Freon 11 | 1.3 | Not Detected | 7.4 | Not Detected |
| Ethanol | 5.3 | 2.5 J | 9.9 | 4.7 J |
| Freon 113 | 1.3 | Not Detected | 10 | Not Detected |
| 1,1-Dichloroethene | 1.3 | Not Detected | 5.2 | Not Detected |
| Acetone | 13 | 4.9 J | 31 | 12 J |
| 2-Propanol | 5.3 | 80 | 13 | 200 |
| Carbon Disulfide | 5.3 | Not Detected | 16 | Not Detected |
| 3-Chloropropene | 5.3 | Not Detected | 16 | Not Detected |
| Methylene Chloride | 13 | Not Detected | 46 | Not Detected |
| Methyl tert-butyl ether | 1.3 | Not Detected | 4.8 | Not Detected |
| trans-1,2-Dichloroethene | 1.3 | Not Detected | 5.2 | Not Detected |
| Hexane | 1.3 | Not Detected | 4.6 | Not Detected |
| 1,1-Dichloroethane | 1.3 | Not Detected | 5.3 | Not Detected |
| 2-Butanone (Methyl Ethyl Ketone) | 5.3 | Not Detected | 16 | Not Detected |
| cis-1,2-Dichloroethene | 1.3 | Not Detected | 5.2 | Not Detected |
| Tetrahydrofuran | 1.3 | Not Detected | 3.9 | Not Detected |
| Chloroform | 1.3 | Not Detected | 6.4 | Not Detected |
| 1,1,1-Trichloroethane | 1.3 | Not Detected | 7.2 | Not Detected |
| Cyclohexane | 1.3 | Not Detected | 4.5 | Not Detected |
| Carbon Tetrachloride | 1.3 | Not Detected | 8.3 | Not Detected |
| 2,2,4-Trimethylpentane | 1.3 | 0.43 J | 6.2 | 2.0 J |
| Benzene | 1.3 | 4.3 | 4.2 | 14 |
| 1,2-Dichloroethane | 1.3 | Not Detected | 5.3 | Not Detected |
| Heptane | 1.3 | Not Detected | 5.4 | Not Detected |
| Trichloroethene | 1.3 | Not Detected | 7.1 | Not Detected |
| 1,2-Dichloropropane | 1.3 | Not Detected | 6.1 | Not Detected |
| 1,4-Dioxane | 5.3 | Not Detected | 19 | Not Detected |
| Bromodichloromethane | 1.3 | Not Detected | 8.8 | Not Detected |
| cis-1,3-Dichloropropene | 1.3 | Not Detected | 6.0 | Not Detected |
| 4-Methyl-2-pentanone | 1.3 | Not Detected | 5.4 | Not Detected |
| Toluene | 1.3 | Not Detected | 5.0 | Not Detected |
| trans-1,3-Dichloropropene | 1.3 | Not Detected | 6.0 | Not Detected |
| 1,1,2-Trichloroethane | 1.3 | Not Detected | 7.2 | Not Detected |
| Tetrachloroethene | 1.3 | Not Detected | 9.0 | Not Detected |
| 2-Hexanone | 5.3 | Not Detected | 22 | Not Detected |

eurofins | Air Toxics

**Client Sample ID: VMP-5-5-012513**

**Lab ID#: 1301501A-01A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **2013120** | **Date of Collection:** | **1/25/13 9:52:00 AM** |
| **Dil. Factor:** | **2.64** | **Date of Analysis:** | **2/1/13 08:06 AM** |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Dibromochloromethane | 1.3 | Not Detected | 11 | Not Detected |
| 1,2-Dibromoethane (EDB) | 1.3 | Not Detected | 10 | Not Detected |
| Chlorobenzene | 1.3 | Not Detected | 6.1 | Not Detected |
| Ethyl Benzene | 1.3 | Not Detected | 5.7 | Not Detected |
| m,p-Xylene | 1.3 | Not Detected | 5.7 | Not Detected |
| o-Xylene | 1.3 | Not Detected | 5.7 | Not Detected |
| Styrene | 1.3 | Not Detected | 5.6 | Not Detected |
| Bromoform | 1.3 | Not Detected | 14 | Not Detected |
| Cumene | 1.3 | Not Detected | 6.5 | Not Detected |
| 1,1,2,2-Tetrachloroethane | 1.3 | Not Detected | 9.1 | Not Detected |
| Propylbenzene | 1.3 | Not Detected | 6.5 | Not Detected |
| 4-Ethyltoluene | 1.3 | Not Detected | 6.5 | Not Detected |
| 1,3,5-Trimethylbenzene | 1.3 | Not Detected | 6.5 | Not Detected |
| 1,2,4-Trimethylbenzene | 1.3 | Not Detected | 6.5 | Not Detected |
| 1,3-Dichlorobenzene | 1.3 | Not Detected | 7.9 | Not Detected |
| 1,4-Dichlorobenzene | 1.3 | Not Detected | 7.9 | Not Detected |
| alpha-Chlorotoluene | 1.3 | Not Detected | 6.8 | Not Detected |
| 1,2-Dichlorobenzene | 1.3 | Not Detected | 7.9 | Not Detected |
| 1,2,4-Trichlorobenzene | 5.3 UJ | Not Detected | 39 UJ | Not Detected |
| Hexachlorobutadiene | 5.3 | Not Detected | 56 | Not Detected |
| Butane | 5.3 | Not Detected | 12 | Not Detected |
| Isopentane | 5.3 | 0.98 J | 16 | 2.9 J |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| Toluene-d8 | 92 | 70-130 |
| 1,2-Dichloroethane-d4 | 93 | 70-130 |
| 4-Bromofluorobenzene | 99 | 70-130 |

eurofins | Air Toxics

**Client Sample ID: VMP-5-12.5-012413**

**Lab ID#: 1301501A-02A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **2013121** | **Date of Collection:** | **1/24/13 3:29:00 PM** |
| **Dil. Factor:** | **2.58** | **Date of Analysis:** | **2/1/13 08:58 AM** |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 1.3 | Not Detected | 6.4 | Not Detected |
| Freon 114 | 1.3 | Not Detected | 9.0 | Not Detected |
| Chloromethane | 13 | Not Detected | 27 | Not Detected |
| Vinyl Chloride | 1.3 | Not Detected | 3.3 | Not Detected |
| 1,3-Butadiene | 1.3 | Not Detected | 2.8 | Not Detected |
| Bromomethane | 13 | Not Detected | 50 | Not Detected |
| Chloroethane | 5.2 | Not Detected | 14 | Not Detected |
| Freon 11 | 1.3 | 0.21 J | 7.2 | 1.2 J |
| Ethanol | 5.2 | 2.3 J | 9.7 | 4.3 J |
| Freon 113 | 1.3 | Not Detected | 9.9 | Not Detected |
| 1,1-Dichloroethene | 1.3 | Not Detected | 5.1 | Not Detected |
| Acetone | 13 | 10 J | 31 | 24 J |
| 2-Propanol | 5.2 | 110 | 13 | 270 |
| Carbon Disulfide | 5.2 | Not Detected | 16 | Not Detected |
| 3-Chloropropene | 5.2 | Not Detected | 16 | Not Detected |
| Methylene Chloride | 13 | Not Detected | 45 | Not Detected |
| Methyl tert-butyl ether | 1.3 | Not Detected | 4.6 | Not Detected |
| trans-1,2-Dichloroethene | 1.3 | Not Detected | 5.1 | Not Detected |
| Hexane | 1.3 | Not Detected | 4.5 | Not Detected |
| 1,1-Dichloroethane | 1.3 | Not Detected | 5.2 | Not Detected |
| 2-Butanone (Methyl Ethyl Ketone) | 5.2 | Not Detected | 15 | Not Detected |
| cis-1,2-Dichloroethene | 1.3 | Not Detected | 5.1 | Not Detected |
| Tetrahydrofuran | 1.3 | Not Detected | 3.8 | Not Detected |
| Chloroform | 1.3 | Not Detected | 6.3 | Not Detected |
| 1,1,1-Trichloroethane | 1.3 | Not Detected | 7.0 | Not Detected |
| Cyclohexane | 1.3 | Not Detected | 4.4 | Not Detected |
| Carbon Tetrachloride | 1.3 | Not Detected | 8.1 | Not Detected |
| 2,2,4-Trimethylpentane | 1.3 | 1.7 | 6.0 | 7.9 |
| Benzene | 1.3 | 0.66 J | 4.1 | 2.1 J |
| 1,2-Dichloroethane | 1.3 | Not Detected | 5.2 | Not Detected |
| Heptane | 1.3 | Not Detected | 5.3 | Not Detected |
| Trichloroethene | 1.3 | Not Detected | 6.9 | Not Detected |
| 1,2-Dichloropropane | 1.3 | Not Detected | 6.0 | Not Detected |
| 1,4-Dioxane | 5.2 | Not Detected | 18 | Not Detected |
| Bromodichloromethane | 1.3 | Not Detected | 8.6 | Not Detected |
| cis-1,3-Dichloropropene | 1.3 | Not Detected | 5.8 | Not Detected |
| 4-Methyl-2-pentanone | 1.3 | Not Detected | 5.3 | Not Detected |
| Toluene | 1.3 | 0.20 J | 4.9 | 0.74 J |
| trans-1,3-Dichloropropene | 1.3 | Not Detected | 5.8 | Not Detected |
| 1,1,2-Trichloroethane | 1.3 | Not Detected | 7.0 | Not Detected |
| Tetrachloroethene | 1.3 | Not Detected | 8.8 | Not Detected |
| 2-Hexanone | 5.2 | Not Detected | 21 | Not Detected |

eurofins | Air Toxics

**Client Sample ID: VMP-5-12.5-012413**

**Lab ID#: 1301501A-02A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **2013121** | **Date of Collection: 1/24/13 3:29:00 PM** | |
| **Dil. Factor:** | **2.58** | **Date of Analysis: 2/1/13 08:58 AM** | |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Dibromochloromethane | 1.3 | Not Detected | 11 | Not Detected |
| 1,2-Dibromoethane (EDB) | 1.3 | Not Detected | 9.9 | Not Detected |
| Chlorobenzene | 1.3 | Not Detected | 5.9 | Not Detected |
| Ethyl Benzene | 1.3 | Not Detected | 5.6 | Not Detected |
| m,p-Xylene | 1.3 | Not Detected | 5.6 | Not Detected |
| o-Xylene | 1.3 | Not Detected | 5.6 | Not Detected |
| Styrene | 1.3 | Not Detected | 5.5 | Not Detected |
| Bromoform | 1.3 | Not Detected | 13 | Not Detected |
| Cumene | 1.3 | Not Detected | 6.3 | Not Detected |
| 1,1,2,2-Tetrachloroethane | 1.3 | Not Detected | 8.8 | Not Detected |
| Propylbenzene | 1.3 | Not Detected | 6.3 | Not Detected |
| 4-Ethyltoluene | 1.3 | Not Detected | 6.3 | Not Detected |
| 1,3,5-Trimethylbenzene | 1.3 | Not Detected | 6.3 | Not Detected |
| 1,2,4-Trimethylbenzene | 1.3 | Not Detected | 6.3 | Not Detected |
| 1,3-Dichlorobenzene | 1.3 | Not Detected | 7.8 | Not Detected |
| 1,4-Dichlorobenzene | 1.3 | Not Detected | 7.8 | Not Detected |
| alpha-Chlorotoluene | 1.3 | Not Detected | 6.7 | Not Detected |
| 1,2-Dichlorobenzene | 1.3 | Not Detected | 7.8 | Not Detected |
| 1,2,4-Trichlorobenzene | 5.2 UJ | Not Detected | 38 UJ | Not Detected |
| Hexachlorobutadiene | 5.2 | Not Detected | 55 | Not Detected |
| Butane | 5.2 | Not Detected | 12 | Not Detected |
| Isopentane | 5.2 | 0.72 J | 15 | 2.1 J |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| Toluene-d8 | 94 | 70-130 |
| 1,2-Dichloroethane-d4 | 96 | 70-130 |
| 4-Bromofluorobenzene | 98 | 70-130 |

eurofins | Air Toxics

**Client Sample ID: VMP-5-31-012413**

**Lab ID#: 1301501A-03A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **2013122** | **Date of Collection:** | **1/24/13 4:17:00 PM** |
| **Dil. Factor:** | **28.0** | **Date of Analysis:** | **2/1/13 09:35 AM** |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 14 | Not Detected | 69 | Not Detected |
| Freon 114 | 14 | Not Detected | 98 | Not Detected |
| Chloromethane | 140 | Not Detected | 290 | Not Detected |
| Vinyl Chloride | 14 | Not Detected | 36 | Not Detected |
| 1,3-Butadiene | 14 | Not Detected | 31 | Not Detected |
| Bromomethane | 140 | Not Detected | 540 | Not Detected |
| Chloroethane | 56 | Not Detected | 150 | Not Detected |
| Freon 11 | 14 | Not Detected | 79 | Not Detected |
| Ethanol | 56 | Not Detected | 100 | Not Detected |
| Freon 113 | 14 | Not Detected | 110 | Not Detected |
| 1,1-Dichloroethene | 14 | Not Detected | 56 | Not Detected |
| Acetone | 140 | 20 J | 330 | 49 J |
| 2-Propanol | 56 | 3100 | 140 | 7500 |
| Carbon Disulfide | 56 | Not Detected | 170 | Not Detected |
| 3-Chloropropene | 56 | Not Detected | 180 | Not Detected |
| Methylene Chloride | 140 | Not Detected | 490 | Not Detected |
| Methyl tert-butyl ether | 14 | Not Detected | 50 | Not Detected |
| trans-1,2-Dichloroethene | 14 | Not Detected | 56 | Not Detected |
| Hexane | 14 | 10 J | 49 | 36 J |
| 1,1-Dichloroethane | 14 | Not Detected | 57 | Not Detected |
| 2-Butanone (Methyl Ethyl Ketone) | 56 | Not Detected | 160 | Not Detected |
| cis-1,2-Dichloroethene | 14 | Not Detected | 56 | Not Detected |
| Tetrahydrofuran | 14 | Not Detected | 41 | Not Detected |
| Chloroform | 14 | 4.9 J | 68 | 24 J |
| 1,1,1-Trichloroethane | 14 | Not Detected | 76 | Not Detected |
| Cyclohexane | 14 | 4.4 J | 48 | 15 J |
| Carbon Tetrachloride | 14 | Not Detected | 88 | Not Detected |
| 2,2,4-Trimethylpentane | 14 | 27 | 65 | 130 |
| Benzene | 14 | Not Detected | 45 | Not Detected |
| 1,2-Dichloroethane | 14 | Not Detected | 57 | Not Detected |
| Heptane | 14 | Not Detected | 57 | Not Detected |
| Trichloroethene | 14 | Not Detected | 75 | Not Detected |
| 1,2-Dichloropropane | 14 | Not Detected | 65 | Not Detected |
| 1,4-Dioxane | 56 | Not Detected | 200 | Not Detected |
| Bromodichloromethane | 14 | Not Detected | 94 | Not Detected |
| cis-1,3-Dichloropropene | 14 | Not Detected | 64 | Not Detected |
| 4-Methyl-2-pentanone | 14 | Not Detected | 57 | Not Detected |
| Toluene | 14 | Not Detected | 53 | Not Detected |
| trans-1,3-Dichloropropene | 14 | Not Detected | 64 | Not Detected |
| 1,1,2-Trichloroethane | 14 | Not Detected | 76 | Not Detected |
| Tetrachloroethene | 14 | Not Detected | 95 | Not Detected |
| 2-Hexanone | 56 | Not Detected | 230 | Not Detected |

eurofins | Air Toxics

**Client Sample ID: VMP-5-31-012413**

**Lab ID#: 1301501A-03A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **2013122** | **Date of Collection:** | **1/24/13 4:17:00 PM** |
| **Dil. Factor:** | **28.0** | **Date of Analysis:** | **2/1/13 09:35 AM** |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Dibromochloromethane | 14 | Not Detected | 120 | Not Detected |
| 1,2-Dibromoethane (EDB) | 14 | Not Detected | 110 | Not Detected |
| Chlorobenzene | 14 | Not Detected | 64 | Not Detected |
| Ethyl Benzene | 14 | Not Detected | 61 | Not Detected |
| m,p-Xylene | 14 | Not Detected | 61 | Not Detected |
| o-Xylene | 14 | Not Detected | 61 | Not Detected |
| Styrene | 14 | Not Detected | 60 | Not Detected |
| Bromoform | 14 | Not Detected | 140 | Not Detected |
| Cumene | 14 | Not Detected | 69 | Not Detected |
| 1,1,2,2-Tetrachloroethane | 14 | Not Detected | 96 | Not Detected |
| Propylbenzene | 14 | Not Detected | 69 | Not Detected |
| 4-Ethyltoluene | 14 | Not Detected | 69 | Not Detected |
| 1,3,5-Trimethylbenzene | 14 | Not Detected | 69 | Not Detected |
| 1,2,4-Trimethylbenzene | 14 | Not Detected | 69 | Not Detected |
| 1,3-Dichlorobenzene | 14 | Not Detected | 84 | Not Detected |
| 1,4-Dichlorobenzene | 14 | Not Detected | 84 | Not Detected |
| alpha-Chlorotoluene | 14 | Not Detected | 72 | Not Detected |
| 1,2-Dichlorobenzene | 14 | Not Detected | 84 | Not Detected |
| 1,2,4-Trichlorobenzene | 56 UJ | Not Detected | 420 UJ | Not Detected |
| Hexachlorobutadiene | 56 | Not Detected | 600 | Not Detected |
| Butane | 56 | 58 | 130 | 140 |
| Isopentane | 56 | 66 | 160 | 190 |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| Toluene-d8 | 94 | 70-130 |
| 1,2-Dichloroethane-d4 | 99 | 70-130 |
| 4-Bromofluorobenzene | 92 | 70-130 |

eurofins | Air Toxics

**Client Sample ID: VMP-5-40-012513**

**Lab ID#: 1301501A-04A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **3020111** | **Date of Collection:** | **1/25/13 10:44:00 AM** |
| **Dil. Factor:** | **8.60** | **Date of Analysis:** | **2/1/13 05:57 PM** |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 4.3 | Not Detected | 21 | Not Detected |
| Freon 114 | 4.3 | Not Detected | 30 | Not Detected |
| Chloromethane | 43 | Not Detected | 89 | Not Detected |
| Vinyl Chloride | 4.3 | Not Detected | 11 | Not Detected |
| 1,3-Butadiene | 4.3 | Not Detected | 9.5 | Not Detected |
| Bromomethane | 43 | Not Detected | 170 | Not Detected |
| Chloroethane | 17 | Not Detected | 45 | Not Detected |
| Freon 11 | 4.3 | Not Detected | 24 | Not Detected |
| Ethanol | 17 | Not Detected | 32 | Not Detected |
| Freon 113 | 4.3 | Not Detected | 33 | Not Detected |
| 1,1-Dichloroethene | 4.3 | Not Detected | 17 | Not Detected |
| Acetone | 43 | 150 | 100 | 350 |
| 2-Propanol | 17 | 760 | 42 | 1900 |
| Carbon Disulfide | 17 | Not Detected | 54 | Not Detected |
| 3-Chloropropene | 17 | Not Detected | 54 | Not Detected |
| Methylene Chloride | 43 | 3.9 J | 150 | 14 J |
| Methyl tert-butyl ether | 4.3 | Not Detected | 16 | Not Detected |
| trans-1,2-Dichloroethene | 4.3 | Not Detected | 17 | Not Detected |
| Hexane | 4.3 | 7.5 | 15 | 26 |
| 1,1-Dichloroethane | 4.3 | Not Detected | 17 | Not Detected |
| 2-Butanone (Methyl Ethyl Ketone) | 17 | Not Detected | 51 | Not Detected |
| cis-1,2-Dichloroethene | 4.3 | Not Detected | 17 | Not Detected |
| Tetrahydrofuran | 4.3 | Not Detected | 13 | Not Detected |
| Chloroform | 4.3 | 8.3 | 21 | 40 |
| 1,1,1-Trichloroethane | 4.3 | Not Detected | 23 | Not Detected |
| Cyclohexane | 4.3 | 5.1 | 15 | 18 |
| Carbon Tetrachloride | 4.3 | Not Detected | 27 | Not Detected |
| 2,2,4-Trimethylpentane | 4.3 | 360 | 20 | 1700 |
| Benzene | 4.3 | 1.2 J | 14 | 3.7 J |
| 1,2-Dichloroethane | 4.3 | Not Detected | 17 | Not Detected |
| Heptane | 4.3 | 2.6 J | 18 | 10 J |
| Trichloroethene | 4.3 | Not Detected | 23 | Not Detected |
| 1,2-Dichloropropane | 4.3 | Not Detected | 20 | Not Detected |
| 1,4-Dioxane | 17 | Not Detected | 62 | Not Detected |
| Bromodichloromethane | 4.3 | Not Detected | 29 | Not Detected |
| cis-1,3-Dichloropropene | 4.3 | Not Detected | 20 | Not Detected |
| 4-Methyl-2-pentanone | 4.3 | Not Detected | 18 | Not Detected |
| Toluene | 4.3 | Not Detected | 16 | Not Detected |
| trans-1,3-Dichloropropene | 4.3 | Not Detected | 20 | Not Detected |
| 1,1,2-Trichloroethane | 4.3 | Not Detected | 23 | Not Detected |
| Tetrachloroethene | 4.3 | Not Detected | 29 | Not Detected |
| 2-Hexanone | 17 | Not Detected | 70 | Not Detected |

eurofins | Air Toxics

**Client Sample ID: VMP-5-40-012513**

**Lab ID#: 1301501A-04A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **3020111** | **Date of Collection:** | **1/25/13 10:44:00 AM** |
| **Dil. Factor:** | **8.60** | **Date of Analysis:** | **2/1/13 05:57 PM** |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Dibromochloromethane | 4.3 | Not Detected | 37 | Not Detected |
| 1,2-Dibromoethane (EDB) | 4.3 | Not Detected | 33 | Not Detected |
| Chlorobenzene | 4.3 | Not Detected | 20 | Not Detected |
| Ethyl Benzene | 4.3 | Not Detected | 19 | Not Detected |
| m,p-Xylene | 4.3 | Not Detected | 19 | Not Detected |
| o-Xylene | 4.3 | Not Detected | 19 | Not Detected |
| Styrene | 4.3 | Not Detected | 18 | Not Detected |
| Bromoform | 4.3 | Not Detected | 44 | Not Detected |
| Cumene | 4.3 | Not Detected | 21 | Not Detected |
| 1,1,2,2-Tetrachloroethane | 4.3 | Not Detected | 30 | Not Detected |
| Propylbenzene | 4.3 | Not Detected | 21 | Not Detected |
| 4-Ethyltoluene | 4.3 | Not Detected | 21 | Not Detected |
| 1,3,5-Trimethylbenzene | 4.3 | Not Detected | 21 | Not Detected |
| 1,2,4-Trimethylbenzene | 4.3 | Not Detected | 21 | Not Detected |
| 1,3-Dichlorobenzene | 4.3 | Not Detected | 26 | Not Detected |
| 1,4-Dichlorobenzene | 4.3 | Not Detected | 26 | Not Detected |
| alpha-Chlorotoluene | 4.3 | Not Detected | 22 | Not Detected |
| 1,2-Dichlorobenzene | 4.3 | Not Detected | 26 | Not Detected |
| 1,2,4-Trichlorobenzene | 17 | Not Detected | 130 | Not Detected |
| Hexachlorobutadiene | 17 | Not Detected | 180 | Not Detected |
| Butane | 17 | 89 J | 41 | 210 J |
| Isopentane | 17 | 240 | 51 | 700 |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| Toluene-d8 | 101 | 70-130 |
| 1,2-Dichloroethane-d4 | 108 | 70-130 |
| 4-Bromofluorobenzene | 93 | 70-130 |

eurofins | Air Toxics

**Client Sample ID: VMP-5-40-012513-Dup**

**Lab ID#: 1301501A-05A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **3020112** | **Date of Collection:** | **1/25/13 10:44:00 AM** |
| **Dil. Factor:** | **8.40** | **Date of Analysis:** | **2/1/13 06:29 PM** |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 4.2 | Not Detected | 21 | Not Detected |
| Freon 114 | 4.2 | Not Detected | 29 | Not Detected |
| Chloromethane | 42 | Not Detected | 87 | Not Detected |
| Vinyl Chloride | 4.2 | Not Detected | 11 | Not Detected |
| 1,3-Butadiene | 4.2 | Not Detected | 9.3 | Not Detected |
| Bromomethane | 42 | Not Detected | 160 | Not Detected |
| Chloroethane | 17 | Not Detected | 44 | Not Detected |
| Freon 11 | 4.2 | Not Detected | 24 | Not Detected |
| Ethanol | 17 | Not Detected | 32 | Not Detected |
| Freon 113 | 4.2 | Not Detected | 32 | Not Detected |
| 1,1-Dichloroethene | 4.2 | Not Detected | 17 | Not Detected |
| Acetone | 42 | 150 | 100 | 360 |
| 2-Propanol | 17 | 800 | 41 | 2000 |
| Carbon Disulfide | 17 | Not Detected | 52 | Not Detected |
| 3-Chloropropene | 17 | Not Detected | 52 | Not Detected |
| Methylene Chloride | 42 | 1.5 J | 140 | 5.4 J |
| Methyl tert-butyl ether | 4.2 | Not Detected | 15 | Not Detected |
| trans-1,2-Dichloroethene | 4.2 | Not Detected | 17 | Not Detected |
| Hexane | 4.2 | 3.6 J | 15 | 13 J |
| 1,1-Dichloroethane | 4.2 | Not Detected | 17 | Not Detected |
| 2-Butanone (Methyl Ethyl Ketone) | 17 | Not Detected | 50 | Not Detected |
| cis-1,2-Dichloroethene | 4.2 | Not Detected | 17 | Not Detected |
| Tetrahydrofuran | 4.2 | Not Detected | 12 | Not Detected |
| Chloroform | 4.2 | 8.8 | 20 | 43 |
| 1,1,1-Trichloroethane | 4.2 | Not Detected | 23 | Not Detected |
| Cyclohexane | 4.2 | 1.7 J | 14 | 5.9 J |
| Carbon Tetrachloride | 4.2 | Not Detected | 26 | Not Detected |
| 2,2,4-Trimethylpentane | 4.2 | 370 | 20 | 1700 |
| Benzene | 4.2 | 1.2 J | 13 | 3.7 J |
| 1,2-Dichloroethane | 4.2 | Not Detected | 17 | Not Detected |
| Heptane | 4.2 | Not Detected | 17 | Not Detected |
| Trichloroethene | 4.2 | Not Detected | 22 | Not Detected |
| 1,2-Dichloropropane | 4.2 | Not Detected | 19 | Not Detected |
| 1,4-Dioxane | 17 | Not Detected | 60 | Not Detected |
| Bromodichloromethane | 4.2 | Not Detected | 28 | Not Detected |
| cis-1,3-Dichloropropene | 4.2 | Not Detected | 19 | Not Detected |
| 4-Methyl-2-pentanone | 4.2 | Not Detected | 17 | Not Detected |
| Toluene | 4.2 | Not Detected | 16 | Not Detected |
| trans-1,3-Dichloropropene | 4.2 | Not Detected | 19 | Not Detected |
| 1,1,2-Trichloroethane | 4.2 | Not Detected | 23 | Not Detected |
| Tetrachloroethene | 4.2 | Not Detected | 28 | Not Detected |
| 2-Hexanone | 17 | Not Detected | 69 | Not Detected |

eurofins | Air Toxics

**Client Sample ID: VMP-5-40-012513-Dup**

**Lab ID#: 1301501A-05A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **3020112** | **Date of Collection: 1/25/13 10:44:00 AM** | |
| **Dil. Factor:** | **8.40** | **Date of Analysis: 2/1/13 06:29 PM** | |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Dibromochloromethane | 4.2 | Not Detected | 36 | Not Detected |
| 1,2-Dibromoethane (EDB) | 4.2 | Not Detected | 32 | Not Detected |
| Chlorobenzene | 4.2 | Not Detected | 19 | Not Detected |
| Ethyl Benzene | 4.2 | Not Detected | 18 | Not Detected |
| m,p-Xylene | 4.2 | Not Detected | 18 | Not Detected |
| o-Xylene | 4.2 | Not Detected | 18 | Not Detected |
| Styrene | 4.2 | Not Detected | 18 | Not Detected |
| Bromoform | 4.2 | Not Detected | 43 | Not Detected |
| Cumene | 4.2 | Not Detected | 21 | Not Detected |
| 1,1,2,2-Tetrachloroethane | 4.2 | Not Detected | 29 | Not Detected |
| Propylbenzene | 4.2 | Not Detected | 21 | Not Detected |
| 4-Ethyltoluene | 4.2 | Not Detected | 21 | Not Detected |
| 1,3,5-Trimethylbenzene | 4.2 | Not Detected | 21 | Not Detected |
| 1,2,4-Trimethylbenzene | 4.2 | Not Detected | 21 | Not Detected |
| 1,3-Dichlorobenzene | 4.2 | Not Detected | 25 | Not Detected |
| 1,4-Dichlorobenzene | 4.2 | Not Detected | 25 | Not Detected |
| alpha-Chlorotoluene | 4.2 | Not Detected | 22 | Not Detected |
| 1,2-Dichlorobenzene | 4.2 | Not Detected | 25 | Not Detected |
| 1,2,4-Trichlorobenzene | 17 | Not Detected | 120 | Not Detected |
| Hexachlorobutadiene | 17 | Not Detected | 180 | Not Detected |
| Butane | 17 | 44 J | 40 | 100 J |
| Isopentane | 17 | 180 | 50 | 530 |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| Toluene-d8 | 99 | 70-130 |
| 1,2-Dichloroethane-d4 | 108 | 70-130 |
| 4-Bromofluorobenzene | 94 | 70-130 |

eurofins | Air Toxics

**Client Sample ID: VMP-8-5-012413**

**Lab ID#: 1301501A-06A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **3020113** | **Date of Collection: 1/24/13 12:09:00 PM** | |
| **Dil. Factor:** | **2.69** | **Date of Analysis: 2/1/13 07:02 PM** | |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 1.3 | 0.50 J | 6.6 | 2.5 J |
| Freon 114 | 1.3 | Not Detected | 9.4 | Not Detected |
| Chloromethane | 13 | Not Detected | 28 | Not Detected |
| Vinyl Chloride | 1.3 | Not Detected | 3.4 | Not Detected |
| 1,3-Butadiene | 1.3 | Not Detected | 3.0 | Not Detected |
| Bromomethane | 13 | Not Detected | 52 | Not Detected |
| Chloroethane | 5.4 | Not Detected | 14 | Not Detected |
| Freon 11 | 1.3 | 0.25 J | 7.6 | 1.4 J |
| Ethanol | 5.4 | 2.0 J | 10 | 3.8 J |
| Freon 113 | 1.3 | Not Detected | 10 | Not Detected |
| 1,1-Dichloroethene | 1.3 | Not Detected | 5.3 | Not Detected |
| Acetone | 13 | 25 | 32 | 60 |
| 2-Propanol | 5.4 | 2.7 J | 13 | 6.6 J |
| Carbon Disulfide | 5.4 | ~~1.4 J~~ | 17 | ~~4.4 J~~ |
| 3-Chloropropene | 5.4 | Not Detected | 17 | Not Detected |
| Methylene Chloride | 13 | 1.4 J | 47 | 4.8 J |
| Methyl tert-butyl ether | 1.3 | Not Detected | 4.8 | Not Detected |
| trans-1,2-Dichloroethene | 1.3 | Not Detected | 5.3 | Not Detected |
| Hexane | 1.3 | Not Detected | 4.7 | Not Detected |
| 1,1-Dichloroethane | 1.3 | Not Detected | 5.4 | Not Detected |
| 2-Butanone (Methyl Ethyl Ketone) | 5.4 | 14 | 16 | 41 |
| cis-1,2-Dichloroethene | 1.3 | Not Detected | 5.3 | Not Detected |
| Tetrahydrofuran | 1.3 | 1.4 | 4.0 | 4.1 |
| Chloroform | 1.3 | Not Detected | 6.6 | Not Detected |
| 1,1,1-Trichloroethane | 1.3 | Not Detected | 7.3 | Not Detected |
| Cyclohexane | 1.3 | Not Detected | 4.6 | Not Detected |
| Carbon Tetrachloride | 1.3 | Not Detected | 8.5 | Not Detected |
| 2,2,4-Trimethylpentane | 1.3 | 0.21 J | 6.3 | 1.0 J |
| Benzene | 1.3 | 0.24 J | 4.3 | 0.77 J |
| 1,2-Dichloroethane | 1.3 | Not Detected | 5.4 | Not Detected |
| Heptane | 1.3 | Not Detected | 5.5 | Not Detected |
| Trichloroethene | 1.3 | Not Detected | 7.2 | Not Detected |
| 1,2-Dichloropropane | 1.3 | Not Detected | 6.2 | Not Detected |
| 1,4-Dioxane | 5.4 | Not Detected | 19 | Not Detected |
| Bromodichloromethane | 1.3 | Not Detected | 9.0 | Not Detected |
| cis-1,3-Dichloropropene | 1.3 | Not Detected | 6.1 | Not Detected |
| 4-Methyl-2-pentanone | 1.3 | 0.68 J | 5.5 | 2.8 J |
| Toluene | 1.3 | 0.37 J | 5.1 | 1.4 J |
| trans-1,3-Dichloropropene | 1.3 | Not Detected | 6.1 | Not Detected |
| 1,1,2-Trichloroethane | 1.3 | Not Detected | 7.3 | Not Detected |
| Tetrachloroethene | 1.3 | Not Detected | 9.1 | Not Detected |
| 2-Hexanone | 5.4 | Not Detected | 22 | Not Detected |

eurofins | Air Toxics

**Client Sample ID: VMP-8-5-012413**

**Lab ID#: 1301501A-06A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **3020113** | **Date of Collection:** | **1/24/13 12:09:00 PM** |
| **Dil. Factor:** | **2.69** | **Date of Analysis:** | **2/1/13 07:02 PM** |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Dibromochloromethane | 1.3 | Not Detected | 11 | Not Detected |
| 1,2-Dibromoethane (EDB) | 1.3 | Not Detected | 10 | Not Detected |
| Chlorobenzene | 1.3 | Not Detected | 6.2 | Not Detected |
| Ethyl Benzene | 1.3 | Not Detected | 5.8 | Not Detected |
| m,p-Xylene | 1.3 | Not Detected | 5.8 | Not Detected |
| o-Xylene | 1.3 | Not Detected | 5.8 | Not Detected |
| Styrene | 1.3 | Not Detected | 5.7 | Not Detected |
| Bromoform | 1.3 | Not Detected | 14 | Not Detected |
| Cumene | 1.3 | Not Detected | 6.6 | Not Detected |
| 1,1,2,2-Tetrachloroethane | 1.3 | Not Detected | 9.2 | Not Detected |
| Propylbenzene | 1.3 | Not Detected | 6.6 | Not Detected |
| 4-Ethyltoluene | 1.3 | Not Detected | 6.6 | Not Detected |
| 1,3,5-Trimethylbenzene | 1.3 | Not Detected | 6.6 | Not Detected |
| 1,2,4-Trimethylbenzene | 1.3 | Not Detected | 6.6 | Not Detected |
| 1,3-Dichlorobenzene | 1.3 | Not Detected | 8.1 | Not Detected |
| 1,4-Dichlorobenzene | 1.3 | ~~0.20 J~~ U | 8.1 | ~~1.2 J~~ U |
| alpha-Chlorotoluene | 1.3 | Not Detected | 7.0 | Not Detected |
| 1,2-Dichlorobenzene | 1.3 | Not Detected | 8.1 | Not Detected |
| 1,2,4-Trichlorobenzene | 5.4 | Not Detected | 40 | Not Detected |
| Hexachlorobutadiene | 5.4 | Not Detected | 57 | Not Detected |
| Butane | 5.4 | Not Detected | 13 | Not Detected |
| Isopentane | 5.4 | Not Detected | 16 | Not Detected |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| Toluene-d8 | 100 | 70-130 |
| 1,2-Dichloroethane-d4 | 104 | 70-130 |
| 4-Bromofluorobenzene | 95 | 70-130 |

eurofins | Air Toxics

**Client Sample ID: VMP-8-9.5-012413**

**Lab ID#: 1301501A-07A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **3020114** | **Date of Collection: 1/24/13 1:02:00 PM** | |
| **Dil. Factor:** | **2.52** | **Date of Analysis: 2/1/13 07:35 PM** | |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 1.3 | 0.55 J | 6.2 | 2.7 J |
| Freon 114 | 1.3 | Not Detected | 8.8 | Not Detected |
| Chloromethane | 13 | Not Detected | 26 | Not Detected |
| Vinyl Chloride | 1.3 | Not Detected | 3.2 | Not Detected |
| 1,3-Butadiene | 1.3 | Not Detected | 2.8 | Not Detected |
| Bromomethane | 13 | Not Detected | 49 | Not Detected |
| Chloroethane | 5.0 | Not Detected | 13 | Not Detected |
| Freon 11 | 1.3 | 0.26 J | 7.1 | 1.5 J |
| Ethanol | 5.0 | Not Detected | 9.5 | Not Detected |
| Freon 113 | 1.3 | Not Detected | 9.6 | Not Detected |
| 1,1-Dichloroethene | 1.3 | Not Detected | 5.0 | Not Detected |
| Acetone | 13 | 3.3 J | 30 | 7.8 J |
| 2-Propanol | 5.0 | 1.3 J | 12 | 3.2 J |
| Carbon Disulfide | 5.0 | Not Detected | 16 | Not Detected |
| 3-Chloropropene | 5.0 | Not Detected | 16 | Not Detected |
| Methylene Chloride | 13 | ~~0.47 J~~ U | 44 | ~~1.6 J~~ U |
| Methyl tert-butyl ether | 1.3 | Not Detected | 4.5 | Not Detected |
| trans-1,2-Dichloroethene | 1.3 | Not Detected | 5.0 | Not Detected |
| Hexane | 1.3 | 0.52 J | 4.4 | 1.8 J |
| 1,1-Dichloroethane | 1.3 | Not Detected | 5.1 | Not Detected |
| 2-Butanone (Methyl Ethyl Ketone) | 5.0 | Not Detected | 15 | Not Detected |
| cis-1,2-Dichloroethene | 1.3 | Not Detected | 5.0 | Not Detected |
| Tetrahydrofuran | 1.3 | Not Detected | 3.7 | Not Detected |
| Chloroform | 1.3 | Not Detected | 6.2 | Not Detected |
| 1,1,1-Trichloroethane | 1.3 | Not Detected | 6.9 | Not Detected |
| Cyclohexane | 1.3 | 0.43 J | 4.3 | 1.5 J |
| Carbon Tetrachloride | 1.3 | Not Detected | 7.9 | Not Detected |
| 2,2,4-Trimethylpentane | 1.3 | 0.36 J | 5.9 | 1.7 J |
| Benzene | 1.3 | 0.34 J | 4.0 | 1.1 J |
| 1,2-Dichloroethane | 1.3 | Not Detected | 5.1 | Not Detected |
| Heptane | 1.3 | Not Detected | 5.2 | Not Detected |
| Trichloroethene | 1.3 | Not Detected | 6.8 | Not Detected |
| 1,2-Dichloropropane | 1.3 | Not Detected | 5.8 | Not Detected |
| 1,4-Dioxane | 5.0 | Not Detected | 18 | Not Detected |
| Bromodichloromethane | 1.3 | Not Detected | 8.4 | Not Detected |
| cis-1,3-Dichloropropene | 1.3 | Not Detected | 5.7 | Not Detected |
| 4-Methyl-2-pentanone | 1.3 | Not Detected | 5.2 | Not Detected |
| Toluene | 1.3 | Not Detected | 4.7 | Not Detected |
| trans-1,3-Dichloropropene | 1.3 | Not Detected | 5.7 | Not Detected |
| 1,1,2-Trichloroethane | 1.3 | Not Detected | 6.9 | Not Detected |
| Tetrachloroethene | 1.3 | ~~0.28 J~~ U | 8.5 | ~~1.9 J~~ U |
| 2-Hexanone | 5.0 | Not Detected | 21 | Not Detected |

eurofins | Air Toxics

**Client Sample ID: VMP-8-9.5-012413**

**Lab ID#: 1301501A-07A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **3020114** | **Date of Collection:** | **1/24/13 1:02:00 PM** |
| **Dil. Factor:** | **2.52** | **Date of Analysis:** | **2/1/13 07:35 PM** |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Dibromochloromethane | 1.3 | Not Detected | 11 | Not Detected |
| 1,2-Dibromoethane (EDB) | 1.3 | Not Detected | 9.7 | Not Detected |
| Chlorobenzene | 1.3 | Not Detected | 5.8 | Not Detected |
| Ethyl Benzene | 1.3 | Not Detected | 5.5 | Not Detected |
| m,p-Xylene | 1.3 | Not Detected | 5.5 | Not Detected |
| o-Xylene | 1.3 | Not Detected | 5.5 | Not Detected |
| Styrene | 1.3 | Not Detected | 5.4 | Not Detected |
| Bromoform | 1.3 | Not Detected | 13 | Not Detected |
| Cumene | 1.3 | Not Detected | 6.2 | Not Detected |
| 1,1,2,2-Tetrachloroethane | 1.3 | Not Detected | 8.6 | Not Detected |
| Propylbenzene | 1.3 | Not Detected | 6.2 | Not Detected |
| 4-Ethyltoluene | 1.3 | Not Detected | 6.2 | Not Detected |
| 1,3,5-Trimethylbenzene | 1.3 | Not Detected | 6.2 | Not Detected |
| 1,2,4-Trimethylbenzene | 1.3 | Not Detected | 6.2 | Not Detected |
| 1,3-Dichlorobenzene | 1.3 | Not Detected | 7.6 | Not Detected |
| 1,4-Dichlorobenzene | 1.3 | ~~0.15 J~~ | 7.6 | ~~0.90 J~~ |
| alpha-Chlorotoluene | 1.3 | Not Detected | 6.5 | Not Detected |
| 1,2-Dichlorobenzene | 1.3 | Not Detected | 7.6 | Not Detected |
| 1,2,4-Trichlorobenzene | 5.0 | Not Detected | 37 | Not Detected |
| Hexachlorobutadiene | 5.0 | Not Detected | 54 | Not Detected |
| Butane | 5.0 | Not Detected | 12 | Not Detected |
| Isopentane | 5.0 | 2.6 J | 15 | 7.7 J |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| Toluene-d8 | 100 | 70-130 |
| 1,2-Dichloroethane-d4 | 105 | 70-130 |
| 4-Bromofluorobenzene | 96 | 70-130 |

eurofins | Air Toxics

**Client Sample ID: VMP-8-9.5-012413-Dup**

**Lab ID#: 1301501A-08A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **3020115** | **Date of Collection:** | **1/24/13 1:02:00 PM** |
| **Dil. Factor:** | **2.69** | **Date of Analysis:** | **2/1/13 08:06 PM** |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 1.3 | 0.59 J | 6.6 | 2.9 J |
| Freon 114 | 1.3 | Not Detected | 9.4 | Not Detected |
| Chloromethane | 13 | Not Detected | 28 | Not Detected |
| Vinyl Chloride | 1.3 | Not Detected | 3.4 | Not Detected |
| 1,3-Butadiene | 1.3 | Not Detected | 3.0 | Not Detected |
| Bromomethane | 13 | Not Detected | 52 | Not Detected |
| Chloroethane | 5.4 | Not Detected | 14 | Not Detected |
| Freon 11 | 1.3 | 0.22 J | 7.6 | 1.2 J |
| Ethanol | 5.4 | Not Detected | 10 | Not Detected |
| Freon 113 | 1.3 | Not Detected | 10 | Not Detected |
| 1,1-Dichloroethene | 1.3 | Not Detected | 5.3 | Not Detected |
| Acetone | 13 | 0.91 J | 32 | 2.2 J |
| 2-Propanol | 5.4 | Not Detected | 13 | Not Detected |
| Carbon Disulfide | 5.4 | Not Detected | 17 | Not Detected |
| 3-Chloropropene | 5.4 | Not Detected | 17 | Not Detected |
| Methylene Chloride | 13 | ~~0.41 J~~ U | 47 | ~~1.4 J~~ U |
| Methyl tert-butyl ether | 1.3 | Not Detected | 4.8 | Not Detected |
| trans-1,2-Dichloroethene | 1.3 | Not Detected | 5.3 | Not Detected |
| Hexane | 1.3 | Not Detected | 4.7 | Not Detected |
| 1,1-Dichloroethane | 1.3 | Not Detected | 5.4 | Not Detected |
| 2-Butanone (Methyl Ethyl Ketone) | 5.4 | Not Detected | 16 | Not Detected |
| cis-1,2-Dichloroethene | 1.3 | Not Detected | 5.3 | Not Detected |
| Tetrahydrofuran | 1.3 | Not Detected | 4.0 | Not Detected |
| Chloroform | 1.3 | Not Detected | 6.6 | Not Detected |
| 1,1,1-Trichloroethane | 1.3 | Not Detected | 7.3 | Not Detected |
| Cyclohexane | 1.3 | 0.35 J | 4.6 | 1.2 J |
| Carbon Tetrachloride | 1.3 | Not Detected | 8.5 | Not Detected |
| 2,2,4-Trimethylpentane | 1.3 | 0.20 J | 6.3 | 0.94 J |
| Benzene | 1.3 | Not Detected | 4.3 | Not Detected |
| 1,2-Dichloroethane | 1.3 | Not Detected | 5.4 | Not Detected |
| Heptane | 1.3 | Not Detected | 5.5 | Not Detected |
| Trichloroethene | 1.3 | Not Detected | 7.2 | Not Detected |
| 1,2-Dichloropropane | 1.3 | Not Detected | 6.2 | Not Detected |
| 1,4-Dioxane | 5.4 | Not Detected | 19 | Not Detected |
| Bromodichloromethane | 1.3 | Not Detected | 9.0 | Not Detected |
| cis-1,3-Dichloropropene | 1.3 | Not Detected | 6.1 | Not Detected |
| 4-Methyl-2-pentanone | 1.3 | Not Detected | 5.5 | Not Detected |
| Toluene | 1.3 | Not Detected | 5.1 | Not Detected |
| trans-1,3-Dichloropropene | 1.3 | 0.18 J | 6.1 | 0.81 J |
| 1,1,2-Trichloroethane | 1.3 | Not Detected | 7.3 | Not Detected |
| Tetrachloroethene | 1.3 | ~~0.23 J~~ U | 9.1 | ~~1.6 J~~ U |
| 2-Hexanone | 5.4 | Not Detected | 22 | Not Detected |

eurofins | Air Toxics

**Client Sample ID: VMP-8-9.5-012413-Dup**

**Lab ID#: 1301501A-08A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **3020115** | **Date of Collection:** | **1/24/13 1:02:00 PM** |
| **Dil. Factor:** | **2.69** | **Date of Analysis:** | **2/1/13 08:06 PM** |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Dibromochloromethane | 1.3 | Not Detected | 11 | Not Detected |
| 1,2-Dibromoethane (EDB) | 1.3 | Not Detected | 10 | Not Detected |
| Chlorobenzene | 1.3 | Not Detected | 6.2 | Not Detected |
| Ethyl Benzene | 1.3 | Not Detected | 5.8 | Not Detected |
| m,p-Xylene | 1.3 | Not Detected | 5.8 | Not Detected |
| o-Xylene | 1.3 | Not Detected | 5.8 | Not Detected |
| Styrene | 1.3 | Not Detected | 5.7 | Not Detected |
| Bromoform | 1.3 | Not Detected | 14 | Not Detected |
| Cumene | 1.3 | Not Detected | 6.6 | Not Detected |
| 1,1,2,2-Tetrachloroethane | 1.3 | Not Detected | 9.2 | Not Detected |
| Propylbenzene | 1.3 | Not Detected | 6.6 | Not Detected |
| 4-Ethyltoluene | 1.3 | Not Detected | 6.6 | Not Detected |
| 1,3,5-Trimethylbenzene | 1.3 | Not Detected | 6.6 | Not Detected |
| 1,2,4-Trimethylbenzene | 1.3 | Not Detected | 6.6 | Not Detected |
| 1,3-Dichlorobenzene | 1.3 | Not Detected | 8.1 | Not Detected |
| 1,4-Dichlorobenzene | 1.3 | Not Detected | 8.1 | Not Detected |
| alpha-Chlorotoluene | 1.3 | Not Detected | 7.0 | Not Detected |
| 1,2-Dichlorobenzene | 1.3 | Not Detected | 8.1 | Not Detected |
| 1,2,4-Trichlorobenzene | 5.4 | Not Detected | 40 | Not Detected |
| Hexachlorobutadiene | 5.4 | Not Detected | 57 | Not Detected |
| Butane | 5.4 | Not Detected | 13 | Not Detected |
| Isopentane | 5.4 | 2.1 J | 16 | 6.2 J |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| Toluene-d8 | 100 | 70-130 |
| 1,2-Dichloroethane-d4 | 105 | 70-130 |
| 4-Bromofluorobenzene | 94 | 70-130 |

eurofins | Air Toxics

**Client Sample ID: VMP-8-23.5-012413**

**Lab ID#: 1301501A-09A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **3020116** | **Date of Collection: 1/24/13 2:05:00 PM** | |
| **Dil. Factor:** | **2.89** | **Date of Analysis: 2/1/13 08:49 PM** | |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 1.4 | 0.66 J | 7.1 | 3.2 J |
| Freon 114 | 1.4 | Not Detected | 10 | Not Detected |
| Chloromethane | 14 | Not Detected | 30 | Not Detected |
| Vinyl Chloride | 1.4 | Not Detected | 3.7 | Not Detected |
| 1,3-Butadiene | 1.4 | Not Detected | 3.2 | Not Detected |
| Bromomethane | 14 | Not Detected | 56 | Not Detected |
| Chloroethane | 5.8 | Not Detected | 15 | Not Detected |
| Freon 11 | 1.4 | 0.32 J | 8.1 | 1.8 J |
| Ethanol | 5.8 | Not Detected | 11 | Not Detected |
| Freon 113 | 1.4 | Not Detected | 11 | Not Detected |
| 1,1-Dichloroethene | 1.4 | Not Detected | 5.7 | Not Detected |
| Acetone | 14 | 2.7 J | 34 | 6.4 J |
| 2-Propanol | 5.8 | Not Detected | 14 | Not Detected |
| Carbon Disulfide | 5.8 | ~~1.2 J~~ U | 18 | ~~3.6 J~~ U |
| 3-Chloropropene | 5.8 | Not Detected | 18 | Not Detected |
| Methylene Chloride | 14 | ~~0.48 J~~ U | 50 | ~~1.7 J~~ U |
| Methyl tert-butyl ether | 1.4 | Not Detected | 5.2 | Not Detected |
| trans-1,2-Dichloroethene | 1.4 | Not Detected | 5.7 | Not Detected |
| Hexane | 1.4 | Not Detected | 5.1 | Not Detected |
| 1,1-Dichloroethane | 1.4 | Not Detected | 5.8 | Not Detected |
| 2-Butanone (Methyl Ethyl Ketone) | 5.8 | Not Detected | 17 | Not Detected |
| cis-1,2-Dichloroethene | 1.4 | Not Detected | 5.7 | Not Detected |
| Tetrahydrofuran | 1.4 | Not Detected | 4.3 | Not Detected |
| Chloroform | 1.4 | Not Detected | 7.0 | Not Detected |
| 1,1,1-Trichloroethane | 1.4 | Not Detected | 7.9 | Not Detected |
| Cyclohexane | 1.4 | Not Detected | 5.0 | Not Detected |
| Carbon Tetrachloride | 1.4 | Not Detected | 9.1 | Not Detected |
| 2,2,4-Trimethylpentane | 1.4 | Not Detected | 6.8 | Not Detected |
| Benzene | 1.4 | 3.2 | 4.6 | 10 |
| 1,2-Dichloroethane | 1.4 | Not Detected | 5.8 | Not Detected |
| Heptane | 1.4 | Not Detected | 5.9 | Not Detected |
| Trichloroethene | 1.4 | Not Detected | 7.8 | Not Detected |
| 1,2-Dichloropropane | 1.4 | Not Detected | 6.7 | Not Detected |
| 1,4-Dioxane | 5.8 | Not Detected | 21 | Not Detected |
| Bromodichloromethane | 1.4 | Not Detected | 9.7 | Not Detected |
| cis-1,3-Dichloropropene | 1.4 | Not Detected | 6.6 | Not Detected |
| 4-Methyl-2-pentanone | 1.4 | Not Detected | 5.9 | Not Detected |
| Toluene | 1.4 | Not Detected | 5.4 | Not Detected |
| trans-1,3-Dichloropropene | 1.4 | Not Detected | 6.6 | Not Detected |
| 1,1,2-Trichloroethane | 1.4 | Not Detected | 7.9 | Not Detected |
| Tetrachloroethene | 1.4 | 0.50 J | 9.8 | 3.4 J |
| 2-Hexanone | 5.8 | Not Detected | 24 | Not Detected |

eurofins | Air Toxics

**Client Sample ID: VMP-8-23.5-012413**

**Lab ID#: 1301501A-09A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **3020116** | **Date of Collection: 1/24/13 2:05:00 PM** | |
| **Dil. Factor:** | **2.89** | **Date of Analysis: 2/1/13 08:49 PM** | |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Dibromochloromethane | 1.4 | Not Detected | 12 | Not Detected |
| 1,2-Dibromoethane (EDB) | 1.4 | Not Detected | 11 | Not Detected |
| Chlorobenzene | 1.4 | Not Detected | 6.6 | Not Detected |
| Ethyl Benzene | 1.4 | Not Detected | 6.3 | Not Detected |
| m,p-Xylene | 1.4 | Not Detected | 6.3 | Not Detected |
| o-Xylene | 1.4 | Not Detected | 6.3 | Not Detected |
| Styrene | 1.4 | Not Detected | 6.2 | Not Detected |
| Bromoform | 1.4 | Not Detected | 15 | Not Detected |
| Cumene | 1.4 | Not Detected | 7.1 | Not Detected |
| 1,1,2,2-Tetrachloroethane | 1.4 | Not Detected | 9.9 | Not Detected |
| Propylbenzene | 1.4 | Not Detected | 7.1 | Not Detected |
| 4-Ethyltoluene | 1.4 | Not Detected | 7.1 | Not Detected |
| 1,3,5-Trimethylbenzene | 1.4 | Not Detected | 7.1 | Not Detected |
| 1,2,4-Trimethylbenzene | 1.4 | Not Detected | 7.1 | Not Detected |
| 1,3-Dichlorobenzene | 1.4 | Not Detected | 8.7 | Not Detected |
| 1,4-Dichlorobenzene | 1.4 | Not Detected | 8.7 | Not Detected |
| alpha-Chlorotoluene | 1.4 | Not Detected | 7.5 | Not Detected |
| 1,2-Dichlorobenzene | 1.4 | Not Detected | 8.7 | Not Detected |
| 1,2,4-Trichlorobenzene | 5.8 | Not Detected | 43 | Not Detected |
| Hexachlorobutadiene | 5.8 | Not Detected | 62 | Not Detected |
| Butane | 5.8 | Not Detected | 14 | Not Detected |
| Isopentane | 5.8 | Not Detected | 17 | Not Detected |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| Toluene-d8 | 96 | 70-130 |
| 1,2-Dichloroethane-d4 | 107 | 70-130 |
| 4-Bromofluorobenzene | 92 | 70-130 |

eurofins | Air Toxics

**Client Sample ID: VMP-18-8.5-012313**

**Lab ID#: 1301501A-10A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **3020117** | **Date of Collection: 1/23/13 4:14:00 PM** | |
| **Dil. Factor:** | **2.89** | **Date of Analysis: 2/1/13 09:21 PM** | |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 1.4 | 0.54 J | 7.1 | 2.7 J |
| Freon 114 | 1.4 | Not Detected | 10 | Not Detected |
| Chloromethane | 14 | Not Detected | 30 | Not Detected |
| Vinyl Chloride | 1.4 | Not Detected | 3.7 | Not Detected |
| 1,3-Butadiene | 1.4 | Not Detected | 3.2 | Not Detected |
| Bromomethane | 14 | Not Detected | 56 | Not Detected |
| Chloroethane | 5.8 | Not Detected | 15 | Not Detected |
| Freon 11 | 1.4 | Not Detected | 8.1 | Not Detected |
| Ethanol | 5.8 | Not Detected | 11 | Not Detected |
| Freon 113 | 1.4 | Not Detected | 11 | Not Detected |
| 1,1-Dichloroethene | 1.4 | Not Detected | 5.7 | Not Detected |
| Acetone | 14 | 2.1 J | 34 | 5.1 J |
| 2-Propanol | 5.8 | 2.8 J | 14 | 6.9 J |
| Carbon Disulfide | 5.8 | Not Detected | 18 | Not Detected |
| 3-Chloropropene | 5.8 | Not Detected | 18 | Not Detected |
| Methylene Chloride | 14 | 0.40 J | 50 | 1.4 J |
| Methyl tert-butyl ether | 1.4 | Not Detected | 5.2 | Not Detected |
| trans-1,2-Dichloroethene | 1.4 | Not Detected | 5.7 | Not Detected |
| Hexane | 1.4 | Not Detected | 5.1 | Not Detected |
| 1,1-Dichloroethane | 1.4 | Not Detected | 5.8 | Not Detected |
| 2-Butanone (Methyl Ethyl Ketone) | 5.8 | Not Detected | 17 | Not Detected |
| cis-1,2-Dichloroethene | 1.4 | Not Detected | 5.7 | Not Detected |
| Tetrahydrofuran | 1.4 | Not Detected | 4.3 | Not Detected |
| Chloroform | 1.4 | Not Detected | 7.0 | Not Detected |
| 1,1,1-Trichloroethane | 1.4 | Not Detected | 7.9 | Not Detected |
| Cyclohexane | 1.4 | Not Detected | 5.0 | Not Detected |
| Carbon Tetrachloride | 1.4 | Not Detected | 9.1 | Not Detected |
| 2,2,4-Trimethylpentane | 1.4 | 2.8 | 6.8 | 13 |
| Benzene | 1.4 | 7.8 | 4.6 | 25 |
| 1,2-Dichloroethane | 1.4 | Not Detected | 5.8 | Not Detected |
| Heptane | 1.4 | Not Detected | 5.9 | Not Detected |
| Trichloroethene | 1.4 | Not Detected | 7.8 | Not Detected |
| 1,2-Dichloropropane | 1.4 | Not Detected | 6.7 | Not Detected |
| 1,4-Dioxane | 5.8 | Not Detected | 21 | Not Detected |
| Bromodichloromethane | 1.4 | Not Detected | 9.7 | Not Detected |
| cis-1,3-Dichloropropene | 1.4 | Not Detected | 6.6 | Not Detected |
| 4-Methyl-2-pentanone | 1.4 | Not Detected | 5.9 | Not Detected |
| Toluene | 1.4 | Not Detected | 5.4 | Not Detected |
| trans-1,3-Dichloropropene | 1.4 | Not Detected | 6.6 | Not Detected |
| 1,1,2-Trichloroethane | 1.4 | Not Detected | 7.9 | Not Detected |
| Tetrachloroethene | 1.4 | Not Detected | 9.8 | Not Detected |
| 2-Hexanone | 5.8 | Not Detected | 24 | Not Detected |

eurofins | Air Toxics

**Client Sample ID: VMP-18-8.5-012313**

**Lab ID#: 1301501A-10A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **3020117** | **Date of Collection: 1/23/13 4:14:00 PM** | |
| **Dil. Factor:** | **2.89** | **Date of Analysis: 2/1/13 09:21 PM** | |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Dibromochloromethane | 1.4 | Not Detected | 12 | Not Detected |
| 1,2-Dibromoethane (EDB) | 1.4 | Not Detected | 11 | Not Detected |
| Chlorobenzene | 1.4 | Not Detected | 6.6 | Not Detected |
| Ethyl Benzene | 1.4 | Not Detected | 6.3 | Not Detected |
| m,p-Xylene | 1.4 | Not Detected | 6.3 | Not Detected |
| o-Xylene | 1.4 | Not Detected | 6.3 | Not Detected |
| Styrene | 1.4 | Not Detected | 6.2 | Not Detected |
| Bromoform | 1.4 | Not Detected | 15 | Not Detected |
| Cumene | 1.4 | Not Detected | 7.1 | Not Detected |
| 1,1,2,2-Tetrachloroethane | 1.4 | Not Detected | 9.9 | Not Detected |
| Propylbenzene | 1.4 | Not Detected | 7.1 | Not Detected |
| 4-Ethyltoluene | 1.4 | Not Detected | 7.1 | Not Detected |
| 1,3,5-Trimethylbenzene | 1.4 | Not Detected | 7.1 | Not Detected |
| 1,2,4-Trimethylbenzene | 1.4 | Not Detected | 7.1 | Not Detected |
| 1,3-Dichlorobenzene | 1.4 | Not Detected | 8.7 | Not Detected |
| 1,4-Dichlorobenzene | 1.4 | Not Detected | 8.7 | Not Detected |
| alpha-Chlorotoluene | 1.4 | Not Detected | 7.5 | Not Detected |
| 1,2-Dichlorobenzene | 1.4 | Not Detected | 8.7 | Not Detected |
| 1,2,4-Trichlorobenzene | 5.8 | Not Detected | 43 | Not Detected |
| Hexachlorobutadiene | 5.8 | Not Detected | 62 | Not Detected |
| Butane | 5.8 | Not Detected | 14 | Not Detected |
| Isopentane | 5.8 | Not Detected | 17 | Not Detected |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| Toluene-d8 | 99 | 70-130 |
| 1,2-Dichloroethane-d4 | 108 | 70-130 |
| 4-Bromofluorobenzene | 94 | 70-130 |

eurofins | Air Toxics

**Client Sample ID: Lab Blank**

**Lab ID#: 1301501A-11A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **2013105a** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 1/31/13 01:27 PM** | |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 0.50 | Not Detected | 2.5 | Not Detected |
| Freon 114 | 0.50 | Not Detected | 3.5 | Not Detected |
| Chloromethane | 5.0 | Not Detected | 10 | Not Detected |
| Vinyl Chloride | 0.50 | Not Detected | 1.3 | Not Detected |
| 1,3-Butadiene | 0.50 | Not Detected | 1.1 | Not Detected |
| Bromomethane | 5.0 | Not Detected | 19 | Not Detected |
| Chloroethane | 2.0 | Not Detected | 5.3 | Not Detected |
| Freon 11 | 0.50 | Not Detected | 2.8 | Not Detected |
| Ethanol | 2.0 | Not Detected | 3.8 | Not Detected |
| Freon 113 | 0.50 | Not Detected | 3.8 | Not Detected |
| 1,1-Dichloroethene | 0.50 | Not Detected | 2.0 | Not Detected |
| Acetone | 5.0 | Not Detected | 12 | Not Detected |
| 2-Propanol | 2.0 | Not Detected | 4.9 | Not Detected |
| Carbon Disulfide | 2.0 | Not Detected | 6.2 | Not Detected |
| 3-Chloropropene | 2.0 | Not Detected | 6.3 | Not Detected |
| Methylene Chloride | 5.0 | Not Detected | 17 | Not Detected |
| Methyl tert-butyl ether | 0.50 | Not Detected | 1.8 | Not Detected |
| trans-1,2-Dichloroethene | 0.50 | Not Detected | 2.0 | Not Detected |
| Hexane | 0.50 | Not Detected | 1.8 | Not Detected |
| 1,1-Dichloroethane | 0.50 | Not Detected | 2.0 | Not Detected |
| 2-Butanone (Methyl Ethyl Ketone) | 2.0 | Not Detected | 5.9 | Not Detected |
| cis-1,2-Dichloroethene | 0.50 | Not Detected | 2.0 | Not Detected |
| Tetrahydrofuran | 0.50 | Not Detected | 1.5 | Not Detected |
| Chloroform | 0.50 | Not Detected | 2.4 | Not Detected |
| 1,1,1-Trichloroethane | 0.50 | Not Detected | 2.7 | Not Detected |
| Cyclohexane | 0.50 | Not Detected | 1.7 | Not Detected |
| Carbon Tetrachloride | 0.50 | Not Detected | 3.1 | Not Detected |
| 2,2,4-Trimethylpentane | 0.50 | Not Detected | 2.3 | Not Detected |
| Benzene | 0.50 | Not Detected | 1.6 | Not Detected |
| 1,2-Dichloroethane | 0.50 | Not Detected | 2.0 | Not Detected |
| Heptane | 0.50 | Not Detected | 2.0 | Not Detected |
| Trichloroethene | 0.50 | 0.14 J | 2.7 | 0.78 J |
| 1,2-Dichloropropane | 0.50 | Not Detected | 2.3 | Not Detected |
| 1,4-Dioxane | 2.0 | Not Detected | 7.2 | Not Detected |
| Bromodichloromethane | 0.50 | Not Detected | 3.4 | Not Detected |
| cis-1,3-Dichloropropene | 0.50 | Not Detected | 2.3 | Not Detected |
| 4-Methyl-2-pentanone | 0.50 | Not Detected | 2.0 | Not Detected |
| Toluene | 0.50 | Not Detected | 1.9 | Not Detected |
| trans-1,3-Dichloropropene | 0.50 | Not Detected | 2.3 | Not Detected |
| 1,1,2-Trichloroethane | 0.50 | Not Detected | 2.7 | Not Detected |
| Tetrachloroethene | 0.50 | Not Detected | 3.4 | Not Detected |
| 2-Hexanone | 2.0 | 0.21 J | 8.2 | 0.85 J |

eurofins | Air Toxics

**Client Sample ID: Lab Blank**

**Lab ID#: 1301501A-11A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **2013105a** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 1/31/13 01:27 PM** | |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Dibromochloromethane | 0.50 | Not Detected | 4.2 | Not Detected |
| 1,2-Dibromoethane (EDB) | 0.50 | Not Detected | 3.8 | Not Detected |
| Chlorobenzene | 0.50 | Not Detected | 2.3 | Not Detected |
| Ethyl Benzene | 0.50 | Not Detected | 2.2 | Not Detected |
| m,p-Xylene | 0.50 | Not Detected | 2.2 | Not Detected |
| o-Xylene | 0.50 | Not Detected | 2.2 | Not Detected |
| Styrene | 0.50 | 0.067 J | 2.1 | 0.29 J |
| Bromoform | 0.50 | Not Detected | 5.2 | Not Detected |
| Cumene | 0.50 | Not Detected | 2.4 | Not Detected |
| 1,1,2,2-Tetrachloroethane | 0.50 | 0.10 J | 3.4 | 0.69 J |
| Propylbenzene | 0.50 | 0.060 J | 2.4 | 0.29 J |
| 4-Ethyltoluene | 0.50 | Not Detected | 2.4 | Not Detected |
| 1,3,5-Trimethylbenzene | 0.50 | Not Detected | 2.4 | Not Detected |
| 1,2,4-Trimethylbenzene | 0.50 | 0.090 J | 2.4 | 0.44 J |
| 1,3-Dichlorobenzene | 0.50 | 0.15 J | 3.0 | 0.92 J |
| 1,4-Dichlorobenzene | 0.50 | 0.24 J | 3.0 | 1.5 J |
| alpha-Chlorotoluene | 0.50 | 0.15 J | 2.6 | 0.80 J |
| 1,2-Dichlorobenzene | 0.50 | 0.19 J | 3.0 | 1.2 J |
| 1,2,4-Trichlorobenzene | 2.0 | 0.74 J | 15 | 5.5 J |
| Hexachlorobutadiene | 2.0 | Not Detected | 21 | Not Detected |
| Butane | 2.0 | Not Detected | 4.8 | Not Detected |
| Isopentane | 2.0 | Not Detected | 5.9 | Not Detected |

J = Estimated value.

**Container Type: NA - Not Applicable**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| Toluene-d8 | 91 | 70-130 |
| 1,2-Dichloroethane-d4 | 99 | 70-130 |
| 4-Bromofluorobenzene | 96 | 70-130 |

eurofins | Air Toxics

**Client Sample ID: Lab Blank**

**Lab ID#: 1301501A-11B**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **3020106a** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 2/1/13 03:12 PM** | |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 0.50 | Not Detected | 2.5 | Not Detected |
| Freon 114 | 0.50 | Not Detected | 3.5 | Not Detected |
| Chloromethane | 5.0 | Not Detected | 10 | Not Detected |
| Vinyl Chloride | 0.50 | Not Detected | 1.3 | Not Detected |
| 1,3-Butadiene | 0.50 | Not Detected | 1.1 | Not Detected |
| Bromomethane | 5.0 | Not Detected | 19 | Not Detected |
| Chloroethane | 2.0 | Not Detected | 5.3 | Not Detected |
| Freon 11 | 0.50 | Not Detected | 2.8 | Not Detected |
| Ethanol | 2.0 | Not Detected | 3.8 | Not Detected |
| Freon 113 | 0.50 | Not Detected | 3.8 | Not Detected |
| 1,1-Dichloroethene | 0.50 | Not Detected | 2.0 | Not Detected |
| Acetone | 5.0 | Not Detected | 12 | Not Detected |
| 2-Propanol | 2.0 | Not Detected | 4.9 | Not Detected |
| Carbon Disulfide | 2.0 | 0.39 J | 6.2 | 1.2 J |
| 3-Chloropropene | 2.0 | Not Detected | 6.3 | Not Detected |
| Methylene Chloride | 5.0 | 0.20 J | 17 | 0.70 J |
| Methyl tert-butyl ether | 0.50 | Not Detected | 1.8 | Not Detected |
| trans-1,2-Dichloroethene | 0.50 | Not Detected | 2.0 | Not Detected |
| Hexane | 0.50 | Not Detected | 1.8 | Not Detected |
| 1,1-Dichloroethane | 0.50 | Not Detected | 2.0 | Not Detected |
| 2-Butanone (Methyl Ethyl Ketone) | 2.0 | Not Detected | 5.9 | Not Detected |
| cis-1,2-Dichloroethene | 0.50 | Not Detected | 2.0 | Not Detected |
| Tetrahydrofuran | 0.50 | Not Detected | 1.5 | Not Detected |
| Chloroform | 0.50 | Not Detected | 2.4 | Not Detected |
| 1,1,1-Trichloroethane | 0.50 | Not Detected | 2.7 | Not Detected |
| Cyclohexane | 0.50 | Not Detected | 1.7 | Not Detected |
| Carbon Tetrachloride | 0.50 | Not Detected | 3.1 | Not Detected |
| 2,2,4-Trimethylpentane | 0.50 | Not Detected | 2.3 | Not Detected |
| Benzene | 0.50 | Not Detected | 1.6 | Not Detected |
| 1,2-Dichloroethane | 0.50 | 0.087 J | 2.0 | 0.35 J |
| Heptane | 0.50 | Not Detected | 2.0 | Not Detected |
| Trichloroethene | 0.50 | Not Detected | 2.7 | Not Detected |
| 1,2-Dichloropropane | 0.50 | Not Detected | 2.3 | Not Detected |
| 1,4-Dioxane | 2.0 | Not Detected | 7.2 | Not Detected |
| Bromodichloromethane | 0.50 | Not Detected | 3.4 | Not Detected |
| cis-1,3-Dichloropropene | 0.50 | 0.10 J | 2.3 | 0.48 J |
| 4-Methyl-2-pentanone | 0.50 | Not Detected | 2.0 | Not Detected |
| Toluene | 0.50 | Not Detected | 1.9 | Not Detected |
| trans-1,3-Dichloropropene | 0.50 | 0.18 J | 2.3 | 0.80 J |
| 1,1,2-Trichloroethane | 0.50 | Not Detected | 2.7 | Not Detected |
| Tetrachloroethene | 0.50 | 0.067 J | 3.4 | 0.46 J |
| 2-Hexanone | 2.0 | Not Detected | 8.2 | Not Detected |

eurofins | Air Toxics

**Client Sample ID: Lab Blank**

**Lab ID#: 1301501A-11B**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **3020106a** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 2/1/13 03:12 PM** | |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Dibromochloromethane | 0.50 | Not Detected | 4.2 | Not Detected |
| 1,2-Dibromoethane (EDB) | 0.50 | 0.16 J | 3.8 | 1.2 J |
| Chlorobenzene | 0.50 | 0.12 J | 2.3 | 0.54 J |
| Ethyl Benzene | 0.50 | Not Detected | 2.2 | Not Detected |
| m,p-Xylene | 0.50 | Not Detected | 2.2 | Not Detected |
| o-Xylene | 0.50 | Not Detected | 2.2 | Not Detected |
| Styrene | 0.50 | Not Detected | 2.1 | Not Detected |
| Bromoform | 0.50 | Not Detected | 5.2 | Not Detected |
| Cumene | 0.50 | Not Detected | 2.4 | Not Detected |
| 1,1,2,2-Tetrachloroethane | 0.50 | 0.15 J | 3.4 | 1.0 J |
| Propylbenzene | 0.50 | 0.12 J | 2.4 | 0.57 J |
| 4-Ethyltoluene | 0.50 | 0.11 J | 2.4 | 0.55 J |
| 1,3,5-Trimethylbenzene | 0.50 | Not Detected | 2.4 | Not Detected |
| 1,2,4-Trimethylbenzene | 0.50 | 0.095 J | 2.4 | 0.47 J |
| 1,3-Dichlorobenzene | 0.50 | 0.28 J | 3.0 | 1.7 J |
| 1,4-Dichlorobenzene | 0.50 | 0.27 J | 3.0 | 1.6 J |
| alpha-Chlorotoluene | 0.50 | 0.15 J | 2.6 | 0.77 J |
| 1,2-Dichlorobenzene | 0.50 | 0.25 J | 3.0 | 1.5 J |
| 1,2,4-Trichlorobenzene | 2.0 | 0.70 J | 15 | 5.2 J |
| Hexachlorobutadiene | 2.0 | 0.42 J | 21 | 4.5 J |
| Butane | 2.0 | Not Detected | 4.8 | Not Detected |
| Isopentane | 2.0 | Not Detected | 5.9 | Not Detected |

J = Estimated value.

**Container Type: NA - Not Applicable**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| Toluene-d8 | 99 | 70-130 |
| 1,2-Dichloroethane-d4 | 103 | 70-130 |
| 4-Bromofluorobenzene | 96 | 70-130 |

eurofins | Air Toxics

**Client Sample ID: CCV**

**Lab ID#: 1301501A-12A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **2013102** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 1/31/13 10:30 AM** | |

| Compound | %Recovery |
|---|---|
| Freon 12 | 82 |
| Freon 114 | 86 |
| Chloromethane | 89 |
| Vinyl Chloride | 85 |
| 1,3-Butadiene | 92 |
| Bromomethane | 96 |
| Chloroethane | 95 |
| Freon 11 | 78 |
| Ethanol | 102 |
| Freon 113 | 86 |
| 1,1-Dichloroethene | 93 |
| Acetone | 94 |
| 2-Propanol | 100 |
| Carbon Disulfide | 92 |
| 3-Chloropropene | 100 |
| Methylene Chloride | 86 |
| Methyl tert-butyl ether | 98 |
| trans-1,2-Dichloroethene | 94 |
| Hexane | 93 |
| 1,1-Dichloroethane | 87 |
| 2-Butanone (Methyl Ethyl Ketone) | 102 |
| cis-1,2-Dichloroethene | 94 |
| Tetrahydrofuran | 98 |
| Chloroform | 84 |
| 1,1,1-Trichloroethane | 86 |
| Cyclohexane | 98 |
| Carbon Tetrachloride | 89 |
| 2,2,4-Trimethylpentane | 86 |
| Benzene | 80 |
| 1,2-Dichloroethane | 76 |
| Heptane | 83 |
| Trichloroethene | 82 |
| 1,2-Dichloropropane | 78 |
| 1,4-Dioxane | 83 |
| Bromodichloromethane | 79 |
| cis-1,3-Dichloropropene | 88 |
| 4-Methyl-2-pentanone | 87 |
| Toluene | 77 |
| trans-1,3-Dichloropropene | 98 |
| 1,1,2-Trichloroethane | 88 |
| Tetrachloroethene | 89 |
| 2-Hexanone | 96 |

eurofins | Air Toxics

**Client Sample ID: CCV**

**Lab ID#: 1301501A-12A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **2013102** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 1/31/13 10:30 AM** | |

| Compound | %Recovery |
|---|---|
| Dibromochloromethane | 91 |
| 1,2-Dibromoethane (EDB) | 89 |
| Chlorobenzene | 85 |
| Ethyl Benzene | 91 |
| m,p-Xylene | 91 |
| o-Xylene | 87 |
| Styrene | 98 |
| Bromoform | 94 |
| Cumene | 86 |
| 1,1,2,2-Tetrachloroethane | 83 |
| Propylbenzene | 90 |
| 4-Ethyltoluene | 85 |
| 1,3,5-Trimethylbenzene | 80 |
| 1,2,4-Trimethylbenzene | 88 |
| 1,3-Dichlorobenzene | 81 |
| 1,4-Dichlorobenzene | 80 |
| alpha-Chlorotoluene | 93 |
| 1,2-Dichlorobenzene | 80 |
| 1,2,4-Trichlorobenzene | 70 |
| Hexachlorobutadiene | 84 |
| Butane | 88 |
| Isopentane | 90 |

**Container Type: NA - Not Applicable**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| Toluene-d8 | 93 | 70-130 |
| 1,2-Dichloroethane-d4 | 96 | 70-130 |
| 4-Bromofluorobenzene | 100 | 70-130 |

eurofins | Air Toxics

**Client Sample ID: CCV**

**Lab ID#: 1301501A-12B**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **3020102** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 2/1/13 12:32 PM** | |

| Compound | %Recovery |
|---|---|
| Freon 12 | 101 |
| Freon 114 | 102 |
| Chloromethane | 100 |
| Vinyl Chloride | 100 |
| 1,3-Butadiene | 105 |
| Bromomethane | 100 |
| Chloroethane | 99 |
| Freon 11 | 102 |
| Ethanol | 104 |
| Freon 113 | 96 |
| 1,1-Dichloroethene | 99 |
| Acetone | 99 |
| 2-Propanol | 102 |
| Carbon Disulfide | 96 |
| 3-Chloropropene | 101 |
| Methylene Chloride | 100 |
| Methyl tert-butyl ether | 109 |
| trans-1,2-Dichloroethene | 102 |
| Hexane | 112 |
| 1,1-Dichloroethane | 100 |
| 2-Butanone (Methyl Ethyl Ketone) | 104 |
| cis-1,2-Dichloroethene | 100 |
| Tetrahydrofuran | 115 |
| Chloroform | 100 |
| 1,1,1-Trichloroethane | 101 |
| Cyclohexane | 110 |
| Carbon Tetrachloride | 103 |
| 2,2,4-Trimethylpentane | 112 |
| Benzene | 107 |
| 1,2-Dichloroethane | 108 |
| Heptane | 117 |
| Trichloroethene | 91 |
| 1,2-Dichloropropane | 103 |
| 1,4-Dioxane | 104 |
| Bromodichloromethane | 104 |
| cis-1,3-Dichloropropene | 106 |
| 4-Methyl-2-pentanone | 118 |
| Toluene | 104 |
| trans-1,3-Dichloropropene | 108 |
| 1,1,2-Trichloroethane | 102 |
| Tetrachloroethene | 99 |
| 2-Hexanone | 124 |

eurofins | Air Toxics

**Client Sample ID: CCV**

**Lab ID#: 1301501A-12B**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **3020102** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 2/1/13 12:32 PM** | |

| Compound | %Recovery |
|---|---|
| Dibromochloromethane | 106 |
| 1,2-Dibromoethane (EDB) | 104 |
| Chlorobenzene | 96 |
| Ethyl Benzene | 109 |
| m,p-Xylene | 114 |
| o-Xylene | 115 |
| Styrene | 120 |
| Bromoform | 106 |
| Cumene | 118 |
| 1,1,2,2-Tetrachloroethane | 115 |
| Propylbenzene | 113 |
| 4-Ethyltoluene | 115 |
| 1,3,5-Trimethylbenzene | 123 |
| 1,2,4-Trimethylbenzene | 131 Q |
| 1,3-Dichlorobenzene | 109 |
| 1,4-Dichlorobenzene | 111 |
| alpha-Chlorotoluene | 119 |
| 1,2-Dichlorobenzene | 107 |
| 1,2,4-Trichlorobenzene | 102 |
| Hexachlorobutadiene | 102 |
| Butane | 109 |
| Isopentane | 106 |

Q = Exceeds Quality Control limits.

**Container Type: NA - Not Applicable**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| Toluene-d8 | 106 | 70-130 |
| 1,2-Dichloroethane-d4 | 106 | 70-130 |
| 4-Bromofluorobenzene | 103 | 70-130 |

eurofins | Air Toxics

**Client Sample ID: LCS**

**Lab ID#: 1301501A-13A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **2013103** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 1/31/13 11:20 AM** | |

| Compound | %Recovery |
|---|---|
| Freon 12 | 75 |
| Freon 114 | 77 |
| Chloromethane | 82 |
| Vinyl Chloride | 78 |
| 1,3-Butadiene | 81 |
| Bromomethane | 87 |
| Chloroethane | 87 |
| Freon 11 | 76 |
| Ethanol | 88 |
| Freon 113 | 79 |
| 1,1-Dichloroethene | 90 |
| Acetone | 91 |
| 2-Propanol | 88 |
| Carbon Disulfide | 103 |
| 3-Chloropropene | 100 |
| Methylene Chloride | 78 |
| Methyl tert-butyl ether | 91 |
| trans-1,2-Dichloroethene | 96 |
| Hexane | 85 |
| 1,1-Dichloroethane | 80 |
| 2-Butanone (Methyl Ethyl Ketone) | 96 |
| cis-1,2-Dichloroethene | 85 |
| Tetrahydrofuran | 86 |
| Chloroform | 78 |
| 1,1,1-Trichloroethane | 80 |
| Cyclohexane | 89 |
| Carbon Tetrachloride | 83 |
| 2,2,4-Trimethylpentane | 80 |
| Benzene | 76 |
| 1,2-Dichloroethane | 72 |
| Heptane | 78 |
| Trichloroethene | 78 |
| 1,2-Dichloropropane | 73 |
| 1,4-Dioxane | 76 |
| Bromodichloromethane | 75 |
| cis-1,3-Dichloropropene | 83 |
| 4-Methyl-2-pentanone | 80 |
| Toluene | 74 |
| trans-1,3-Dichloropropene | 94 |
| 1,1,2-Trichloroethane | 84 |
| Tetrachloroethene | 84 |
| 2-Hexanone | 86 |

eurofins | Air Toxics

**Client Sample ID: LCS**

**Lab ID#: 1301501A-13A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **2013103** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 1/31/13 11:20 AM** | |

| Compound | %Recovery |
|---|---|
| Dibromochloromethane | 86 |
| 1,2-Dibromoethane (EDB) | 86 |
| Chlorobenzene | 81 |
| Ethyl Benzene | 88 |
| m,p-Xylene | 90 |
| o-Xylene | 86 |
| Styrene | 94 |
| Bromoform | 87 |
| Cumene | 85 |
| 1,1,2,2-Tetrachloroethane | 81 |
| Propylbenzene | 89 |
| 4-Ethyltoluene | 80 |
| 1,3,5-Trimethylbenzene | 78 |
| 1,2,4-Trimethylbenzene | 83 |
| 1,3-Dichlorobenzene | 81 |
| 1,4-Dichlorobenzene | 78 |
| alpha-Chlorotoluene | 91 |
| 1,2-Dichlorobenzene | 81 |
| 1,2,4-Trichlorobenzene | 70 |
| Hexachlorobutadiene | 85 |
| Butane | 75 |
| Isopentane | 84 |

**Container Type: NA - Not Applicable**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| Toluene-d8 | 95 | 70-130 |
| 1,2-Dichloroethane-d4 | 93 | 70-130 |
| 4-Bromofluorobenzene | 101 | 70-130 |

eurofins | Air Toxics

**Client Sample ID: LCSD**

**Lab ID#: 1301501A-13AA**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **2013104** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 1/31/13 12:39 PM** | |

| Compound | %Recovery |
|---|---|
| Freon 12 | 76 |
| Freon 114 | 78 |
| Chloromethane | 82 |
| Vinyl Chloride | 80 |
| 1,3-Butadiene | 82 |
| Bromomethane | 89 |
| Chloroethane | 88 |
| Freon 11 | 77 |
| Ethanol | 88 |
| Freon 113 | 80 |
| 1,1-Dichloroethene | 90 |
| Acetone | 93 |
| 2-Propanol | 88 |
| Carbon Disulfide | 104 |
| 3-Chloropropene | 104 |
| Methylene Chloride | 78 |
| Methyl tert-butyl ether | 94 |
| trans-1,2-Dichloroethene | 97 |
| Hexane | 86 |
| 1,1-Dichloroethane | 81 |
| 2-Butanone (Methyl Ethyl Ketone) | 95 |
| cis-1,2-Dichloroethene | 85 |
| Tetrahydrofuran | 88 |
| Chloroform | 79 |
| 1,1,1-Trichloroethane | 81 |
| Cyclohexane | 91 |
| Carbon Tetrachloride | 83 |
| 2,2,4-Trimethylpentane | 81 |
| Benzene | 75 |
| 1,2-Dichloroethane | 71 |
| Heptane | 77 |
| Trichloroethene | 78 |
| 1,2-Dichloropropane | 74 |
| 1,4-Dioxane | 74 |
| Bromodichloromethane | 74 |
| cis-1,3-Dichloropropene | 82 |
| 4-Methyl-2-pentanone | 78 |
| Toluene | 72 |
| trans-1,3-Dichloropropene | 93 |
| 1,1,2-Trichloroethane | 82 |
| Tetrachloroethene | 82 |
| 2-Hexanone | 85 |

eurofins | Air Toxics

**Client Sample ID: LCSD**

**Lab ID#: 1301501A-13AA**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **2013104** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 1/31/13 12:39 PM** | |

| Compound | %Recovery |
|---|---|
| Dibromochloromethane | 84 |
| 1,2-Dibromoethane (EDB) | 84 |
| Chlorobenzene | 79 |
| Ethyl Benzene | 85 |
| m,p-Xylene | 86 |
| o-Xylene | 84 |
| Styrene | 91 |
| Bromoform | 86 |
| Cumene | 81 |
| 1,1,2,2-Tetrachloroethane | 79 |
| Propylbenzene | 88 |
| 4-Ethyltoluene | 78 |
| 1,3,5-Trimethylbenzene | 76 |
| 1,2,4-Trimethylbenzene | 81 |
| 1,3-Dichlorobenzene | 78 |
| 1,4-Dichlorobenzene | 78 |
| alpha-Chlorotoluene | 91 |
| 1,2-Dichlorobenzene | 79 |
| 1,2,4-Trichlorobenzene | 69 Q |
| Hexachlorobutadiene | 84 |
| Butane | 78 |
| Isopentane | 87 |

Q = Exceeds Quality Control limits.

**Container Type: NA - Not Applicable**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| Toluene-d8 | 94 | 70-130 |
| 1,2-Dichloroethane-d4 | 94 | 70-130 |
| 4-Bromofluorobenzene | 100 | 70-130 |

eurofins | Air Toxics

**Client Sample ID: LCS**

**Lab ID#: 1301501A-13B**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **3020103** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 2/1/13 01:10 PM** | |

| Compound | %Recovery |
|---|---|
| Freon 12 | 103 |
| Freon 114 | 107 |
| Chloromethane | 108 |
| Vinyl Chloride | 115 |
| 1,3-Butadiene | 112 |
| Bromomethane | 101 |
| Chloroethane | 102 |
| Freon 11 | 102 |
| Ethanol | 106 |
| Freon 113 | 100 |
| 1,1-Dichloroethene | 111 |
| Acetone | 102 |
| 2-Propanol | 106 |
| Carbon Disulfide | 122 |
| 3-Chloropropene | 122 |
| Methylene Chloride | 98 |
| Methyl tert-butyl ether | 111 |
| trans-1,2-Dichloroethene | 116 |
| Hexane | 113 |
| 1,1-Dichloroethane | 100 |
| 2-Butanone (Methyl Ethyl Ketone) | 109 |
| cis-1,2-Dichloroethene | 101 |
| Tetrahydrofuran | 113 |
| Chloroform | 102 |
| 1,1,1-Trichloroethane | 102 |
| Cyclohexane | 114 |
| Carbon Tetrachloride | 104 |
| 2,2,4-Trimethylpentane | 115 |
| Benzene | 107 |
| 1,2-Dichloroethane | 104 |
| Heptane | 116 |
| Trichloroethene | 93 |
| 1,2-Dichloropropane | 103 |
| 1,4-Dioxane | 105 |
| Bromodichloromethane | 105 |
| cis-1,3-Dichloropropene | 108 |
| 4-Methyl-2-pentanone | 121 |
| Toluene | 104 |
| trans-1,3-Dichloropropene | 109 |
| 1,1,2-Trichloroethane | 102 |
| Tetrachloroethene | 99 |
| 2-Hexanone | 126 |

eurofins | Air Toxics

**Client Sample ID: LCS**

**Lab ID#: 1301501A-13B**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **3020103** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 2/1/13 01:10 PM** | |

| **Compound** | **%Recovery** |
|---|---|
| Dibromochloromethane | 104 |
| 1,2-Dibromoethane (EDB) | 106 |
| Chlorobenzene | 97 |
| Ethyl Benzene | 110 |
| m,p-Xylene | 115 |
| o-Xylene | 115 |
| Styrene | 120 |
| Bromoform | 103 |
| Cumene | 119 |
| 1,1,2,2-Tetrachloroethane | 115 |
| Propylbenzene | 114 |
| 4-Ethyltoluene | 111 |
| 1,3,5-Trimethylbenzene | 122 |
| 1,2,4-Trimethylbenzene | 129 |
| 1,3-Dichlorobenzene | 108 |
| 1,4-Dichlorobenzene | 110 |
| alpha-Chlorotoluene | 116 |
| 1,2-Dichlorobenzene | 108 |
| 1,2,4-Trichlorobenzene | 105 |
| Hexachlorobutadiene | 104 |
| Butane | 111 |
| Isopentane | 106 |

**Container Type: NA - Not Applicable**

| **Surrogates** | **%Recovery** | **Method Limits** |
|---|---|---|
| Toluene-d8 | 103 | 70-130 |
| 1,2-Dichloroethane-d4 | 101 | 70-130 |
| 4-Bromofluorobenzene | 100 | 70-130 |

eurofins | Air Toxics

**Client Sample ID: LCSD**

**Lab ID#: 1301501A-13BB**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **3020104** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 2/1/13 01:58 PM** | |

| Compound | %Recovery |
|---|---|
| Freon 12 | 104 |
| Freon 114 | 108 |
| Chloromethane | 104 |
| Vinyl Chloride | 109 |
| 1,3-Butadiene | 110 |
| Bromomethane | 103 |
| Chloroethane | 101 |
| Freon 11 | 101 |
| Ethanol | 104 |
| Freon 113 | 101 |
| 1,1-Dichloroethene | 114 |
| Acetone | 103 |
| 2-Propanol | 108 |
| Carbon Disulfide | 123 |
| 3-Chloropropene | 124 |
| Methylene Chloride | 99 |
| Methyl tert-butyl ether | 112 |
| trans-1,2-Dichloroethene | 118 |
| Hexane | 115 |
| 1,1-Dichloroethane | 101 |
| 2-Butanone (Methyl Ethyl Ketone) | 107 |
| cis-1,2-Dichloroethene | 104 |
| Tetrahydrofuran | 115 |
| Chloroform | 103 |
| 1,1,1-Trichloroethane | 103 |
| Cyclohexane | 116 |
| Carbon Tetrachloride | 104 |
| 2,2,4-Trimethylpentane | 116 |
| Benzene | 106 |
| 1,2-Dichloroethane | 102 |
| Heptane | 115 |
| Trichloroethene | 92 |
| 1,2-Dichloropropane | 104 |
| 1,4-Dioxane | 106 |
| Bromodichloromethane | 103 |
| cis-1,3-Dichloropropene | 107 |
| 4-Methyl-2-pentanone | 120 |
| Toluene | 103 |
| trans-1,3-Dichloropropene | 109 |
| 1,1,2-Trichloroethane | 103 |
| Tetrachloroethene | 101 |
| 2-Hexanone | 129 |

eurofins | Air Toxics

**Client Sample ID: LCSD**

**Lab ID#: 1301501A-13BB**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **3020104** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 2/1/13 01:58 PM** | |

| Compound | %Recovery |
|---|---|
| Dibromochloromethane | 104 |
| 1,2-Dibromoethane (EDB) | 107 |
| Chlorobenzene | 97 |
| Ethyl Benzene | 110 |
| m,p-Xylene | 117 |
| o-Xylene | 116 |
| Styrene | 120 |
| Bromoform | 104 |
| Cumene | 120 |
| 1,1,2,2-Tetrachloroethane | 115 |
| Propylbenzene | 115 |
| 4-Ethyltoluene | 112 |
| 1,3,5-Trimethylbenzene | 123 |
| 1,2,4-Trimethylbenzene | 131 Q |
| 1,3-Dichlorobenzene | 110 |
| 1,4-Dichlorobenzene | 111 |
| alpha-Chlorotoluene | 117 |
| 1,2-Dichlorobenzene | 108 |
| 1,2,4-Trichlorobenzene | 108 |
| Hexachlorobutadiene | 106 |
| Butane | 110 |
| Isopentane | 107 |

Q = Exceeds Quality Control limits.

**Container Type: NA - Not Applicable**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| Toluene-d8 | 102 | 70-130 |
| 1,2-Dichloroethane-d4 | 101 | 70-130 |
| 4-Bromofluorobenzene | 100 | 70-130 |

# Shell Oil Products Chain Of Custody Record

URS

Air Toxics LTD.
Project Name: Roxana Soil Vapor
Project # 21562850.04001
Lab Vendor #

Please Check Appropriate Box:
☑ ENV. SERVICES ☐ MOTIVA RETAIL ☐ SHELL RETAIL
☐ MOTIVA SD&CM ☐ CONSULTANT ☐ LUBES
☐ SHELL PIPELINE ☐ OTHER

Print Bill To Contact Name: Robert Moosheglan
PO #:
INCIDENT # (ENV SERVICES): 9 7 2 1 8 6 4 0
☐ CHECK IF NO INCIDENT # APPLIES
SAP #: 3 4 0 0 6 1
DATE: 01/25/13
PAGE: 1 of 3

SAMPLING COMPANY: URS CORPORATION
ADDRESS: 1001 HIGHLANDS PLAZA DRIVE WEST - SUITE 300; ST. LOUIS, MO 63110
LABORATORY ADDRESS: Air Toxics, LTD 180 Blue Ravine Road, Suite B, Folsom, CA 95630-4719
TELEPHONE: 314-429-0100 FAX: 314-429-0462 BILL TO CONTACT E-MAIL: Robert.Moosheglan@urs.com
SITE ADDRESS: Street and City: 900 SOUTH CENTRAL AVE – ROXANA State: IL GLOBAL ID NO.:
SAMPLER'S NAME(S) & TC (Name, Company, Office Location): Elizabeth Kunkel, URS, St. Louis PHONE NO.: 314-743-4179 E-MAIL: Elizabeth_Kunkel@URSCorp.com CONSULTANT PROJECT NAME#: Roxana Soil Vapor
M. Currier, C. Kretzer, M. Mittermeyer, L. Rathnow, S. Jansen, E. Arthur, A. Day, B. Lehan,

TURNAROUND TIME (CALENDAR DAYS):
☑ STANDARD (14 DAY) ☐ 5 DAYS ☐ 3 DAYS ☐ 2 DAYS ☐ 24 HOURS ☐ RESULTS NEEDED ON WEEKEND

☐ LA - RWQCB REPORT FORMAT ☑ UST AGENCY:

DELIVERABLES: ☐ LEVEL 1 ☐ LEVEL 2 ☐ LEVEL 3 ☑ LEVEL 4 ☐ OTHER (SPECIFY)

☑ SHELL CONTRACT RATE APPLIES
☐ STATE REIMBURSEMENT RATE APPLIES
☐ EDD NOT NEEDED
☑ RECEIPT VERIFICATION REQUESTED

REQUESTED ANALYSIS

Turn Around Time: ☑ Normal ☐ Rush ☐ Specify

Lab Use Only
Pressurized by:
Date:
Pressurization Gas: $N_2$ He

| LAB USE ONLY | Field Sample Identification | SAMPLING DATE | SAMPLING TIME | Canister Number | Canister Pressure/Vacuum Initial | Final | Receipt | Final (psi) | Modified TO-15 + Butane & Isopentane | ASTM D-1946 + Helium | ASTM D-1946 |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 01 | VMP-5-5-012513 | 01/25/13 | 0920-0952 | 34086 | -29 | -8.5 | | | X | X | |
| 02 | VMP-5-12.5-012413 | 01/24/13 | 1459-1529 | 36472 | -30 | -9 | | | X | X | |
| 03 | VMP-5-31-012413 | 01/24/13 | 1547-1617 | 34174 | -30 | -9 | | | X | X | |
| 04 | VMP-5-40-012513 | 01/25/13 | 1014-1044 | 36570 | -30 | -8 | | | X | X | |
| 05 | VMP-5-40-012513-Dup | 01/25/13 | 1014-1044 | 35644 | -30 | -7.5 | | | X | X | |
| 06 | VMP-8-5-012413 | 01/24/13 | 1128-1209 | 100187 | -28.5 | -8 | | | X | X | |
| 07 | VMP-8-9.5-012413 | 01/24/13 | 1232-1302 | 31771 | -29 | -7.5 | | | X | X | |
| 08 | VMP-8-9.5-012413-Dup | 01/24/13 | 1232-1302 | 36475 | -29.5 | -9 | | | X | X | |
| 09 | VMP-8-23.5-012413 | 01/24/13 | 1324-1405 | 12285 | -29.5 | -8 | | | X | X | |
| 10 | VMP-18-8.5-012313 | 01/23/13 | 1544-1614 | 36474 | -30 | -9.5 | | | X | X | |

ADDITIONAL NOTES:
- 14 day hold time
- Report results between MDL and RL
- Level IV ECVP

| | Received by: (Signature) | Date | Time |
|---|---|---|---|
| Relinquished by: (Signature) Lindsay Rathnow | FEDEX | 1/25/13 | 19:30 |
| Relinquished by: (Signature) | Received by: (Signature) B. Lehan ATL | 1/28/13 | 0945 |
| Relinquished by: (Signature) | Received by: (Signature) | Date: | Time: |

05/2/08 Revision

Fedex
Custody Seal Intact?
(Y) N None Temp____

1301501

eurofins | Air Toxics

2/11/2013
Ms. Elizabeth Kunkel
URS Corporation
1001 Highlands Plaza Dr. West
Suite 300
St. Louis MO 63110

Project Name: Roxana Soil Vapor
Project #: 21562850.04001
Workorder #: 1301501B

Dear Ms. Elizabeth Kunkel

The following report includes the data for the above referenced project for sample(s) received on 1/28/2013 at Air Toxics Ltd.

The data and associated QC analyzed by Modified ASTM D-1946 are compliant with the project requirements or laboratory criteria with the exception of the deviations noted in the attached case narrative.

Thank you for choosing Air Toxics Ltd. for your air analysis needs. Air Toxics Ltd. is committed to providing accurate data of the highest quality. Please feel free to contact the Project Manager: Kelly Buettner at 916-985-1000 if you have any questions regarding the data in this report.

Regards,

Kelly Buettner

Kelly Buettner
Project Manager

REVIEWED
ON
3/19/13

eurofins | Air Toxics

# WORK ORDER #: 1301501B

Work Order Summary

| | | | |
|---|---|---|---|
| **CLIENT:** | Ms. Elizabeth Kunkel<br>URS Corporation<br>1001 Highlands Plaza Dr. West<br>Suite 300<br>St. Louis, MO 63110 | **BILL TO:** | Accounts Payable Austin<br>URS Corporation<br>P.O. BOX 203970<br>Austin, TX 78720-1088 |
| **PHONE:** | 314-743-4179 | **P.O. #** | 21562735.00013 |
| **FAX:** | | **PROJECT #** | 21562850.04001 Roxana Soil Vapor |
| **DATE RECEIVED:** | 01/28/2013 | **CONTACT:** | Kelly Buettner |
| **DATE COMPLETED:** | 02/11/2013 | | |

| FRACTION # | NAME | TEST | RECEIPT VAC./PRES. | FINAL PRESSURE |
|---|---|---|---|---|
| 01A | VMP-5-5-012513 | Modified ASTM D-1946 | 7.0 "Hg | 15 psi |
| 02A | VMP-5-12.5-012413 | Modified ASTM D-1946 | 6.5 "Hg | 15 psi |
| 03A | VMP-5-31-012413 | Modified ASTM D-1946 | 6.0 "Hg | 15 psi |
| 04A | VMP-5-40-012513 | Modified ASTM D-1946 | 6.5 "Hg | 15 psi |
| 05A | VMP-5-40-012513-Dup | Modified ASTM D-1946 | 6.0 "Hg | 15 psi |
| 06A | VMP-8-5-012413 | Modified ASTM D-1946 | 7.5 "Hg | 15 psi |
| 07A | VMP-8-9.5-012413 | Modified ASTM D-1946 | 6.0 "Hg | 15 psi |
| 08A | VMP-8-9.5-012413-Dup | Modified ASTM D-1946 | 7.5 "Hg | 15 psi |
| 09A | VMP-8-23.5-012413 | Modified ASTM D-1946 | 9.0 "Hg | 15 psi |
| 10A | VMP-18-8.5-012313 | Modified ASTM D-1946 | 9.0 "Hg | 15 psi |
| 11A | Lab Blank | Modified ASTM D-1946 | NA | NA |
| 11B | Lab Blank | Modified ASTM D-1946 | NA | NA |
| 12A | LCS | Modified ASTM D-1946 | NA | NA |
| 12AA | LCSD | Modified ASTM D-1946 | NA | NA |

CERTIFIED BY: Heidi Mayo DATE: 02/11/13

Technical Director

Certification numbers: AZ Licensure AZ0775, CA NELAP - 12282CA, NY NELAP - 11291,
TX NELAP - T104704434-12-4, UT NELAP CA009332012-3, WA NELAP - C935
Name of Accrediting Agency: NELAP/ORELAP (Oregon Environmental Laboratory Accreditation Program)
Accreditation number: CA300005, Effective date: 10/18/2012, Expiration date: 10/17/2013.
Eurofins Air Toxics Ltd. certifies that the test results contained in this report meet all requirements of the NELAC standards

This report shall not be reproduced, except in full, without the written approval of Eurofins Air Toxics, Inc.

180 BLUE RAVINE ROAD, SUITE B FOLSOM, CA - 9563
(916) 985-1000 . (800) 985-5955 . FAX (916) 985-1020

**LABORATORY NARRATIVE**
**Modified ASTM D-1946**
**URS Corporation**
**Workorder# 1301501B**

Ten 1 Liter Summa Canister samples were received on January 28, 2013. The laboratory performed analysis via Modified ASTM Method D-1946 for Methane and fixed gases in air using GC/FID or GC/TCD. The method involves direct injection of 1.0 mL of sample.

On the analytical column employed for this analysis, Oxygen coelutes with Argon. The corresponding peak is quantitated as Oxygen.

Since Nitrogen is used to pressurize samples, the reported Nitrogen values are calculated by adding all the sample components and subtracting from 100%.

Method modifications taken to run these samples are summarized in the table below. Specific project requirements may over-ride the ATL modifications.

| *Requirement* | *ASTM D-1946* | *ATL Modifications* |
|---|---|---|
| Calibration | A single point calibration is performed using a reference standard closely matching the composition of the unknown. | A 3-point calibration curve is performed. Quantitation is based on a daily calibration standard which may or may not resemble the composition of the associated samples. |
| Reference Standard | The composition of any reference standard must be known to within 0.01 mol % for any component. | The standards used by ATL are blended to a >/= 95% accuracy. |
| Sample Injection Volume | Components whose concentrations are in excess of 5 % should not be analyzed by using sample volumes greater than 0.5 mL. | The sample container is connected directly to a fixed volume sample loop of 1.0 mL on the GC. Linear range is defined by the calibration curve. Bags are loaded by vacuum. |
| Normalization | Normalize the mole percent values by multiplying each value by 100 and dividing by the sum of the original values. The sum of the original values should not differ from 100% by more than 1.0%. | Results are not normalized. The sum of the reported values can differ from 100% by as much as 15%, either due to analytical variability or an unusual sample matrix. |
| Precision | Precision requirements established at each concentration level. | Duplicates should agree within 25% RPD for detections > 5 X's the RL. |

**Receiving Notes**

There were no receiving discrepancies.

**Analytical Notes**

As per project specific client request the laboratory has reported estimated values for target compound hits that are below the Reporting Limit but greater than the Method Detection Limit. Concentrations that are below the level at which the canister was certified may be false positives.

The reporting limit for Carbon Monoxide was raised from 0.010 % to 0.050 %.

**Definition of Data Qualifying Flags**

Seven qualifiers may have been used on the data analysis sheets and indicate as follows:
B - Compound present in laboratory blank greater than reporting limit.
J - Estimated value.
E - Exceeds instrument calibration range.
S - Saturated peak.
Q - Exceeds quality control limits.
U - Compound analyzed for but not detected above the detection limit.
M - Reported value may be biased due to apparent matrix interferences.
File extensions may have been used on the data analysis sheets and indicates as follows:
a-File was requantified
b-File was quantified by a second column and detector
r1-File was requantified for the purpose of reissue

eurofins | Air Toxics

# Summary of Detected Compounds
# NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1946

**Client Sample ID: VMP-5-5-012513**

**Lab ID#: 1301501B-01A**

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.26 | 21 |
| Nitrogen | 0.26 | 79 |
| Methane | 0.00026 | 0.000058 J |
| Carbon Dioxide | 0.026 | 0.13 |
| Helium | 0.13 | 0.084 J |

**Client Sample ID: VMP-5-12.5-012413**

**Lab ID#: 1301501B-02A**

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.26 | 21 |
| Nitrogen | 0.26 | 79 |
| Methane | 0.00026 | 0.000037 J |
| Carbon Dioxide | 0.026 | 0.16 |

**Client Sample ID: VMP-5-31-012413**

**Lab ID#: 1301501B-03A**

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.25 | 18 |
| Nitrogen | 0.25 | 78 |
| Methane | 0.00025 | 0.00051 |
| Carbon Dioxide | 0.025 | 3.6 |

**Client Sample ID: VMP-5-40-012513**

**Lab ID#: 1301501B-04A**

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.26 | 18 |
| Nitrogen | 0.26 | 78 |
| Methane | 0.00026 | 0.0018 |
| Carbon Dioxide | 0.026 | 3.6 |

eurofins | Air Toxics

# Summary of Detected Compounds
# NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1946

**Client Sample ID: VMP-5-40-012513**

**Lab ID#: 1301501B-04A**

| | | |
|---|---|---|
| Helium | 0.13 | 0.19 |

**Client Sample ID: VMP-5-40-012513-Dup**

**Lab ID#: 1301501B-05A**

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.25 | 18 |
| Nitrogen | 0.25 | 78 |
| Methane | 0.00025 | 0.0018 |
| Carbon Dioxide | 0.025 | 3.7 |
| Helium | 0.13 | 0.079 J |

**Client Sample ID: VMP-8-5-012413**

**Lab ID#: 1301501B-06A**

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.27 | 21 |
| Nitrogen | 0.27 | 79 |
| Methane | 0.00027 | 0.00019 J |
| Carbon Dioxide | 0.027 | 0.33 |

**Client Sample ID: VMP-8-9.5-012413**

**Lab ID#: 1301501B-07A**

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.25 | 18 |
| Nitrogen | 0.25 | 78 |
| Methane | 0.00025 | 0.000041 J |
| Carbon Dioxide | 0.025 | 3.4 |
| Helium | 0.13 | 0.051 J |

**Client Sample ID: VMP-8-9.5-012413-Dup**

**Lab ID#: 1301501B-08A**

eurofins | Air Toxics

# Summary of Detected Compounds
# NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1946

**Client Sample ID: VMP-8-9.5-012413-Dup**

**Lab ID#: 1301501B-08A**

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.27 | 18 |
| Nitrogen | 0.27 | 78 |
| Methane | 0.00027 | 0.000043 J |
| Carbon Dioxide | 0.027 | 3.4 |
| Helium | 0.13 | 0.054 J |

**Client Sample ID: VMP-8-23.5-012413**

**Lab ID#: 1301501B-09A**

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.29 | 17 |
| Nitrogen | 0.29 | 78 |
| Methane | 0.00029 | 0.000056 J |
| Carbon Dioxide | 0.029 | 4.8 |

**Client Sample ID: VMP-18-8.5-012313**

**Lab ID#: 1301501B-10A**

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.29 | 21 |
| Nitrogen | 0.29 | 78 |
| Methane | 0.00029 | 0.000023 J |
| Carbon Dioxide | 0.029 | 1.5 |

eurofins | Air Toxics

**Client Sample ID: VMP-5-5-012513**

**Lab ID#: 1301501B-01A**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1946**

| | | | |
|---|---|---|---|
| **File Name:** | **9013108** | **Date of Collection:** | **1/25/13 9:52:00 AM** |
| **Dil. Factor:** | **2.64** | **Date of Analysis:** | **1/31/13 01:08 PM** |

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.26 | 21 |
| Nitrogen | 0.26 | 79 |
| Carbon Monoxide | 0.13 | Not Detected |
| Methane | 0.00026 | 0.000058 J |
| Carbon Dioxide | 0.026 | 0.13 |
| Ethane | 0.0026 | Not Detected |
| Ethene | 0.0026 | Not Detected |
| Helium | 0.13 | 0.084 J |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

eurofins | Air Toxics

**Client Sample ID: VMP-5-12.5-012413**

**Lab ID#: 1301501B-02A**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1946**

| | | | |
|---|---|---|---|
| **File Name:** | **9013109** | **Date of Collection:** | **1/24/13 3:29:00 PM** |
| **Dil. Factor:** | **2.58** | **Date of Analysis:** | **1/31/13 01:34 PM** |

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.26 | 21 |
| Nitrogen | 0.26 | 79 |
| Carbon Monoxide | 0.13 | Not Detected |
| Methane | 0.00026 | 0.000037 J |
| Carbon Dioxide | 0.026 | 0.16 |
| Ethane | 0.0026 | Not Detected |
| Ethene | 0.0026 | Not Detected |
| Helium | 0.13 | Not Detected |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

eurofins | Air Toxics

**Client Sample ID: VMP-5-31-012413**

**Lab ID#: 1301501B-03A**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1946**

| | | | |
|---|---|---|---|
| **File Name:** | **9013110** | **Date of Collection:** | **1/24/13 4:17:00 PM** |
| **Dil. Factor:** | **2.52** | **Date of Analysis:** | **1/31/13 01:58 PM** |

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.25 | 18 |
| Nitrogen | 0.25 | 78 |
| Carbon Monoxide | 0.13 | Not Detected |
| Methane | 0.00025 | 0.00051 |
| Carbon Dioxide | 0.025 | 3.6 |
| Ethane | 0.0025 | Not Detected |
| Ethene | 0.0025 | Not Detected |
| Helium | 0.13 | Not Detected |

**Container Type: 1 Liter Summa Canister**

eurofins | Air Toxics

**Client Sample ID: VMP-5-40-012513**

**Lab ID#: 1301501B-04A**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1946**

| | | | |
|---|---|---|---|
| **File Name:** | **9013111** | **Date of Collection:** | **1/25/13 10:44:00 AM** |
| **Dil. Factor:** | **2.58** | **Date of Analysis:** | **1/31/13 02:22 PM** |

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.26 | 18 |
| Nitrogen | 0.26 | 78 |
| Carbon Monoxide | 0.13 | Not Detected |
| Methane | 0.00026 | 0.0018 |
| Carbon Dioxide | 0.026 | 3.6 |
| Ethane | 0.0026 | Not Detected |
| Ethene | 0.0026 | Not Detected |
| Helium | 0.13 | 0.19 |

**Container Type: 1 Liter Summa Canister**

eurofins | Air Toxics

**Client Sample ID: VMP-5-40-012513-Dup**

**Lab ID#: 1301501B-05A**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1946**

| | | | |
|---|---|---|---|
| **File Name:** | **9013112** | **Date of Collection:** | **1/25/13 10:44:00 AM** |
| **Dil. Factor:** | **2.52** | **Date of Analysis:** | **1/31/13 02:44 PM** |

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.25 | 18 |
| Nitrogen | 0.25 | 78 |
| Carbon Monoxide | 0.13 | Not Detected |
| Methane | 0.00025 | 0.0018 |
| Carbon Dioxide | 0.025 | 3.7 |
| Ethane | 0.0025 | Not Detected |
| Ethene | 0.0025 | Not Detected |
| Helium | 0.13 | 0.079 J |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

eurofins | Air Toxics

**Client Sample ID: VMP-8-5-012413**

**Lab ID#: 1301501B-06A**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1946**

| | | | |
|---|---|---|---|
| **File Name:** | **9013113** | **Date of Collection:** | **1/24/13 12:09:00 PM** |
| **Dil. Factor:** | **2.69** | **Date of Analysis:** | **1/31/13 03:06 PM** |

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.27 | 21 |
| Nitrogen | 0.27 | 79 |
| Carbon Monoxide | 0.13 | Not Detected |
| Methane | 0.00027 | 0.00019 J |
| Carbon Dioxide | 0.027 | 0.33 |
| Ethane | 0.0027 | Not Detected |
| Ethene | 0.0027 | Not Detected |
| Helium | 0.13 | Not Detected |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

eurofins | Air Toxics

**Client Sample ID: VMP-8-9.5-012413**

**Lab ID#: 1301501B-07A**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1946**

| | | | |
|---|---|---|---|
| **File Name:** | **9013114** | **Date of Collection:** | **1/24/13 1:02:00 PM** |
| **Dil. Factor:** | **2.52** | **Date of Analysis:** | **1/31/13 03:27 PM** |

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.25 | 18 |
| Nitrogen | 0.25 | 78 |
| Carbon Monoxide | 0.13 | Not Detected |
| Methane | 0.00025 | 0.000041 J |
| Carbon Dioxide | 0.025 | 3.4 |
| Ethane | 0.0025 | Not Detected |
| Ethene | 0.0025 | Not Detected |
| Helium | 0.13 | 0.051 J |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

eurofins | Air Toxics

**Client Sample ID: VMP-8-9.5-012413-Dup**

**Lab ID#: 1301501B-08A**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1946**

| | | | |
|---|---|---|---|
| **File Name:** | **9013115** | **Date of Collection:** | **1/24/13 1:02:00 PM** |
| **Dil. Factor:** | **2.69** | **Date of Analysis:** | **1/31/13 03:57 PM** |

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.27 | 18 |
| Nitrogen | 0.27 | 78 |
| Carbon Monoxide | 0.13 | Not Detected |
| Methane | 0.00027 | 0.000043 J |
| Carbon Dioxide | 0.027 | 3.4 |
| Ethane | 0.0027 | Not Detected |
| Ethene | 0.0027 | Not Detected |
| Helium | 0.13 | 0.054 J |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

eurofins | Air Toxics

**Client Sample ID: VMP-8-23.5-012413**

**Lab ID#: 1301501B-09A**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1946**

| | | | |
|---|---|---|---|
| **File Name:** | **9013116** | **Date of Collection:** | **1/24/13 2:05:00 PM** |
| **Dil. Factor:** | **2.89** | **Date of Analysis:** | **1/31/13 04:19 PM** |

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.29 | 17 |
| Nitrogen | 0.29 | 78 |
| Carbon Monoxide | 0.14 | Not Detected |
| Methane | 0.00029 | 0.000056 J |
| Carbon Dioxide | 0.029 | 4.8 |
| Ethane | 0.0029 | Not Detected |
| Ethene | 0.0029 | Not Detected |
| Helium | 0.14 | Not Detected |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

eurofins | Air Toxics

**Client Sample ID: VMP-18-8.5-012313**

**Lab ID#: 1301501B-10A**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1946**

| | | | |
|---|---|---|---|
| **File Name:** | **9013117** | **Date of Collection:** | **1/23/13 4:14:00 PM** |
| **Dil. Factor:** | **2.89** | **Date of Analysis:** | **1/31/13 04:40 PM** |

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.29 | 21 |
| Nitrogen | 0.29 | 78 |
| Carbon Monoxide | 0.14 | Not Detected |
| Methane | 0.00029 | 0.000023 J |
| Carbon Dioxide | 0.029 | 1.5 |
| Ethane | 0.0029 | Not Detected |
| Ethene | 0.0029 | Not Detected |
| Helium | 0.14 | Not Detected |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

eurofins | Air Toxics

**Client Sample ID: Lab Blank**

**Lab ID#: 1301501B-11A**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1946**

| | | | |
|---|---|---|---|
| **File Name:** | **9013105a** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 1/31/13 11:48 AM** | |

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.10 | 0.031 J |
| Nitrogen | 0.10 | 0.084 J |
| Carbon Monoxide | 0.050 | Not Detected |
| Methane | 0.00010 | Not Detected |
| Carbon Dioxide | 0.010 | Not Detected |
| Ethane | 0.0010 | Not Detected |
| Ethene | 0.0010 | Not Detected |

J = Estimated value.

**Container Type: NA - Not Applicable**

eurofins | Air Toxics

**Client Sample ID: Lab Blank**

**Lab ID#: 1301501B-11B**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1946**

| | | | |
|---|---|---|---|
| **File Name:** | **9013104ba** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 1/31/13 11:26 AM** | |

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Helium | 0.050 | Not Detected |

**Container Type: NA - Not Applicable**

eurofins | Air Toxics

**Client Sample ID: LCS**

**Lab ID#: 1301501B-12A**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1946**

| | | | |
|---|---|---|---|
| **File Name:** | **9013103** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 1/31/13 11:00 AM** | |

| Compound | %Recovery |
|---|---|
| Oxygen | 100 |
| Nitrogen | 101 |
| Carbon Monoxide | 98 |
| Methane | 98 |
| Carbon Dioxide | 101 |
| Ethane | 99 |
| Ethene | 96 |
| Helium | 101 |

**Container Type: NA - Not Applicable**

eurofins | Air Toxics

**Client Sample ID: LCSD**

**Lab ID#: 1301501B-12AA**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1946**

| | | | |
|---|---|---|---|
| **File Name:** | **9013126** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 1/31/13 08:36 PM** | |

| Compound | %Recovery |
|---|---|
| Oxygen | 100 |
| Nitrogen | 100 |
| Carbon Monoxide | 95 |
| Methane | 99 |
| Carbon Dioxide | 100 |
| Ethane | 101 |
| Ethene | 98 |
| Helium | 101 |

**Container Type: NA - Not Applicable**

# Shell Oil Products Chain Of Custody Record

URS

Air Toxics LTD.
**Project Name: Roxana Soil Vapor**
**Project # 21562850.04001**
**Lab Vendor #**

Please Check Appropriate Box: ☑ ENV. SERVICES ☐ MOTIVA RETAIL ☐ SHELL RETAIL ☐ MOTIVA SD&CM ☐ CONSULTANT ☐ LUBES ☐ SHELL PIPELINE ☐ OTHER

Print Bill To Contact Name: Robert Moosheglan

INCIDENT # (ENV SERVICES): 9 7 2 1 8 6 4 0 ☐ CHECK IF NO INCIDENT # APPLIES

PO #:

SAP #: 3 4 0 0 6 1

DATE: 01/25/13

PAGE: 1 of 3

SAMPLING COMPANY: URS CORPORATION

LOG CODE:

ADDRESS: 1001 HIGHLANDS PLAZA DRIVE WEST - SUITE 300; ST. LOUIS, MO 63110

SITE ADDRESS: River and City: 900 SOUTH CENTRAL AVE – ROXANA

State: IL

GLOBAL ID NO.:

Laboratory Address: Air Toxics, LTD 180 Blue Ravine Road, Suite B, Folsom, CA 95630-4719

EDF DELIVERABLE TO (Name, Company, Office Location): Elizabeth Kunkel, URS, St. Louis

PHONE NO.: 314-743-4179

E-MAIL: Elizabeth.Kunkel@URSCorp.com

CONSULTANT PROJECT NAME#: Roxana Soil Vapor

TELEPHONE: 314-429-0100

FAX: 314-429-0462

Bill To Contact E-MAIL: Robert.Moosheglan@urs.com

M. Currier, C. Kretzer, M. Mittermeyer, L. Rathnow, S. Jansen, E. Arthur, A. Day, B. Lehan,

TURNAROUND TIME (CALENDAR DAYS): ☑ STANDARD (14 DAY) ☐ 5 DAYS ☐ 3 DAYS ☐ 2 DAYS ☐ 24 HOURS ☐ RESULTS NEEDED ON WEEKEND

☐ LA - RWQCB REPORT FORMAT ☑ UST AGENCY:

DELIVERABLES: ☐ LEVEL 1 ☐ LEVEL 2 ☐ LEVEL 3 ☑ LEVEL 4 ☐ OTHER (SPECIFY)

☑ SHELL CONTRACT RATE APPLIES
☐ STATE REIMBURSEMENT RATE APPLIES
☐ EDD NOT NEEDED
☑ RECEIPT VERIFICATION REQUESTED

REQUESTED ANALYSIS

Turn Around Time: ☑ Normal ☐ Rush ☐ Specify

Lab Use Only
Pressurized by:
Date:
Pressurization Gas: $N_2$ He

| LAB USE ONLY | Field Sample Identification | SAMPLING DATE | SAMPLING TIME | Canister Number | Canister Pressure/Vacuum Initial | Final | Receipt | Final (psi) | Modified TO-15 + Butane & Isopentane | ASTM D-1946 + Helium | ASTM D-1946 | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| 01A | VMP-5-5-012513 | 01/25/13 | 0920-0952 | 34086 | -29 | -6.5 | | | X | X | | | | | | |
| 02A | VMP-5-12.5-012413 | 01/24/13 | 1459-1529 | 36472 | -30 | -9 | | | X | X | | | | | | |
| 03A | VMP-5-31-012413 | 01/24/13 | 1547-1617 | 34174 | -30 | -9 | | | X | X | | | | | | |
| 04A | VMP-5-40-012513 | 01/25/13 | 1014-1044 | 36570 | -30 | -8 | | | X | X | | | | | | |
| 05A | VMP-5-40-012513-Dup | 01/25/13 | 1014-1044 | 35644 | -30 | -7.5 | | | X | X | | | | | | |
| 06A | VMP-8-5-012413 | 01/24/13 | 1128-1209 | 100187 | -28.5 | -8 | | | X | X | | | | | | |
| 07A | VMP-8-9.5-012413 | 01/24/13 | 1232-1302 | 31771 | -29 | -7.5 | | | X | X | | | | | | |
| 08A | VMP-8-9.5-012413-Dup | 01/24/13 | 1232-1302 | 36475 | -29.5 | -9 | | | X | X | | | | | | |
| 09A | VMP-8-23.5-012413 | 01/24/13 | 1324-1405 | 12295 | -29.5 | -8 | | | X | X | | | | | | |
| 10A | VMP-18-8.5-012313 | 01/23/13 | 1544-1614 | 36474 | -30 | -6.5 | | | X | X | | | | | | |

ADDITIONAL NOTES:

- 14 day hold time
- Report results between MDL and RL
- Level IV ECVP

| Relinquished by: (Signature) | Received by: (Signature) | Date | Time |
|---|---|---|---|
| Lindsay Rathnow | FEDEX | 1/25/13 | 19:30 |
| Relinquished by: (Signature) | Received by: (Signature) | Date | Time |
| | R. Luttrell ATL 1/28/13 0945 | | |
| Relinquished by: (Signature) | Received by: (Signature) | Date | Time |
| | | | |

05/2/06 Revision

Fedex

Custody Seal Intact?
(Y) N None Temp____

1301501

# Roxana Soil Vapor Quarterly – 1st Quarter 2013 Data Review

**Laboratory SDG: 1301504A,B**

**Data Reviewer: Alan Fleisher**

**Peer Reviewer: Elizabeth Kunkel**

**Date Reviewed: 3/19/2013**

**Guidance: USEPA National Functional Guidelines for Superfund Organic Methods Data Review 2008**

| Sample Identification | Sample Identification |
|---|---|
| VMP-20-5-012213 | VMP-20-10-012213 |
| VMP-20-25-012213 | VMP-22-5-012413 |
| VMP-22-10-012413 | VMP-22-18-012413 |
| VMP-22-38-012413 | VMP-23-5-012413 |
| VMP-23-10-012413 | VMP-23-25-012413 |
| VMP-23-40-012413 | VMP-24-5-012313 |
| VMP-24-10-012313 | VMP-24-22-012313 |
| VMP-24-34-012313 | VMP-43-20-012313 |
| VMP-43-30-012313 | |

## 1.0 Data Package Completeness

*Were all items delivered as specified in the QAPP and COC as appropriate?*

Yes, however analysis of sample VMP-20-5-012213 was cancelled due to the discovery of an open canister valve upon laboratory receipt. The sample vented to ambient pressure during shipment. Well VMP-20-5 was re-sampled on February 7, 2013, and results were reported in SDG 1302248A,B.

## 2.0 Laboratory Case Narrative \ Cooler Receipt Form

*Were problems noted in the laboratory case narrative or cooler receipt form?*

Although not indicated in the laboratory case narrative, analytes were detected in the method blank. These issues are addressed further in the appropriate section below.

No issues or discrepancies were noted in the cooler receipt form.

## 3.0 Holding Times

*Were samples extracted/analyzed within applicable limits?*

Yes

## 4.0 Blank Contamination

*Were any analytes detected in the Blanks?*

Yes

| Blank ID | Parameter | Analyte | Concentration/ Amount |
|---|---|---|---|
| 1301504A-18A | TO-15 | Bromomethane | 0.26 ppbv / 0.99 µg/m$^3$ |

| Blank ID | Parameter | Analyte | Concentration/ Amount |
|---|---|---|---|
| 1301504A-18A | TO-15 | Acetone | 0.45 ppbv / 1.1 µg/m$^3$ |
| 1301504A-18A | TO-15 | Carbon disulfide | 0.5 ppbv / 1.6 µg/m$^3$ |
| 1301504A-18A | TO-15 | Methylene chloride | 0.18 ppbv / 0.64 µg/m$^3$ |
| 1301504A-18A | TO-15 | trans-1,2-Dichloroethene | 0.12 ppbv / 0.48 µg/m$^3$ |
| 1301504A-18A | TO-15 | cis-1,3-Dichloropropene | 0.099 ppbv / 0.45 µg/m$^3$ |
| 1301504A-18A | TO-15 | Toluene | 0.064 ppbv / 0.24 µg/m$^3$ |
| 1301504A-18A | TO-15 | trans-1,3-Dichloropropene | 0.17 ppbv / 0.78 µg/m$^3$ |
| 1301504A-18A | TO-15 | 1,2-Dibromoethane (EDB) | 0.13 ppbv / 0.99 µg/m$^3$ |
| 1301504A-18A | TO-15 | Chlorobenzene | 0.11 ppbv / 0.49 µg/m$^3$ |
| 1301504A-18A | TO-15 | Propylbenzene | 0.079 ppbv / 0.39 µg/m$^3$ |
| 1301504A-18A | TO-15 | 4-Ethyltoluene | 0.067 ppbv / 0.33 µg/m$^3$ |
| 1301504A-18A | TO-15 | 1,2,4-Trimethylbenzene | 0.12 ppbv / 0.57 µg/m$^3$ |
| 1301504A-18A | TO-15 | 1,3-Dichlorobenzene | 0.26 ppbv / 1.6 µg/m$^3$ |
| 1301504A-18A | TO-15 | 1,4-Dichlorobenzene | 0.28 ppbv / 1.6 µg/m$^3$ |
| 1301504A-18A | TO-15 | alpha-Chlorotoluene | 0.14 ppbv / 0.71 µg/m$^3$ |
| 1301504A-18A | TO-15 | 1,2-Dichlorobenzene | 0.22 ppbv / 1.3 µg/m$^3$ |
| 1301504A-18A | TO-15 | 1,2,4-Trichlorobenzene | 0.92 ppbv / 6.8 µg/m$^3$ |
| 1301504A-18A | TO-15 | Hexachlorobutadiene | 0.29 ppbv / 3.0 µg/m$^3$ |
| 1301504B-18A | Natural gases | Nitrogen | 0.099% |

Qualifications due to blank contamination are included in the table below. Analytical data that were reported non-detect or at concentrations greater than five times (5X) the associated blank concentration did not require qualification.

| Sample ID | Parameter | Analyte | New Reporting Limit (RL) | Qualification |
|---|---|---|---|---|
| VMP-20-10-012213 | TO-15 | Carbon disulfide | - | **U** |
| VMP-20-10-012213 | TO-15 | Methylene chloride | - | **U** |
| VMP-20-10-012213 | TO-15 | Toluene | - | **U** |
| VMP-20-10-012213 | TO-15 | Tetrachloroethene | - | **U** |
| VMP-20-10-012213 | TO-15 | 1,3-Dichlorobenzene | - | **U** |
| VMP-20-10-012213 | TO-15 | 1,4-Dichlorobenzene | - | **U** |
| VMP-20-10-012213 | TO-15 | 1,2,4-Trichlorobenzene | - | **U** |
| VMP-20-25-012213 | TO-15 | Bromomethane | - | **U** |
| VMP-20-25-012213 | TO-15 | Carbon disulfide | - | **U** |
| VMP-20-25-012213 | TO-15 | Methylene chloride | - | **U** |
| VMP-20-25-012213 | TO-15 | Toluene | - | **U** |
| VMP-20-25-012213 | TO-15 | Tetrachloroethene | - | **U** |
| VMP-20-25-012213 | TO-15 | 1,3-Dichlorobenzene | - | **U** |
| VMP-20-25-012213 | TO-15 | 1,4-Dichlorobenzene | - | **U** |
| VMP-20-25-012213 | TO-15 | 1,2,4-Trichlorobenzene | - | **U** |
| VMP-22-5-012413 | TO-15 | Carbon disulfide | - | **U** |
| VMP-22-5-012413 | TO-15 | Methylene chloride | - | **U** |
| VMP-22-5-012413 | TO-15 | Toluene | - | **U** |

| Sample ID | Parameter | Analyte | New Reporting Limit (RL) | Qualification |
|---|---|---|---|---|
| VMP-22-5-012413 | TO-15 | Tetrachloroethene | - | **U** |
| VMP-22-5-012413 | TO-15 | 4-Ethyltoluene | - | **U** |
| VMP-22-5-012413 | TO-15 | 1,3-Dichlorobenzene | - | **U** |
| VMP-22-5-012413 | TO-15 | 1,2,4-Trichlorobenzene | - | **U** |
| VMP-22-10-012413 | TO-15 | Carbon disulfide | - | **U** |
| VMP-22-10-012413 | TO-15 | Methylene chloride | - | **U** |
| VMP-22-10-012413 | TO-15 | Toluene | - | **U** |
| VMP-22-10-012413 | TO-15 | 4-Ethyltoluene | - | **U** |
| VMP-22-10-012413 | TO-15 | 1,3-Dichlorobenzene | - | **U** |
| VMP-22-10-012413 | TO-15 | 1,2,4-Trichlorobenzene | - | **U** |
| VMP-22-18-012413 | TO-15 | Acetone | - | **U** |
| VMP-22-18-012413 | TO-15 | Carbon disulfide | - | **U** |
| VMP-22-18-012413 | TO-15 | Methylene chloride | - | **U** |
| VMP-22-18-012413 | TO-15 | Toluene | - | **U** |
| VMP-22-18-012413 | TO-15 | Tetrachloroethene | - | **U** |
| VMP-22-18-012413 | TO-15 | 4-Ethyltoluene | - | **U** |
| VMP-22-38-012413 | TO-15 | Carbon disulfide | - | **U** |
| VMP-22-38-012413 | TO-15 | Toluene | - | **U** |
| VMP-22-38-012413 | TO-15 | Tetrachloroethene | - | **U** |
| VMP-22-38-012413 | TO-15 | 4-Ethyltoluene | - | **U** |
| VMP-22-38-012413 | TO-15 | 1,2,4-Trichlorobenzene | - | **U** |
| VMP-23-5-012413 | TO-15 | Carbon disulfide | - | **U** |
| VMP-23-5-012413 | TO-15 | Methylene chloride | - | **U** |
| VMP-23-5-012413 | TO-15 | Toluene | - | **U** |
| VMP-23-5-012413 | TO-15 | 1,2,4-Trichlorobenzene | - | **U** |
| VMP-23-10-012413 | TO-15 | Carbon disulfide | - | **U** |
| VMP-23-10-012413 | TO-15 | Methylene chloride | - | **U** |
| VMP-23-10-012413 | TO-15 | Toluene | - | **U** |
| VMP-23-25-012413 | TO-15 | Carbon disulfide | - | **U** |
| VMP-23-25-012413 | TO-15 | Methylene chloride | - | **U** |
| VMP-23-25-012413 | TO-15 | Toluene | - | **U** |
| VMP-23-25-012413 | TO-15 | Tetrachloroethene | - | **U** |
| VMP-23-40-012413 | TO-15 | Carbon disulfide | - | **U** |
| VMP-24-5-012313 | TO-15 | Carbon disulfide | - | **U** |
| VMP-24-5-012313 | TO-15 | Toluene | - | **U** |
| VMP-24-10-012313 | TO-15 | Acetone | - | **U** |
| VMP-24-10-012313 | TO-15 | Carbon disulfide | - | **U** |
| VMP-24-10-012313 | TO-15 | Methylene chloride | - | **U** |
| VMP-24-10-012313 | TO-15 | Tetrachloroethene | - | **U** |
| VMP-24-22-012313 | TO-15 | Carbon disulfide | - | **U** |
| VMP-24-22-012313 | TO-15 | Methylene chloride | - | **U** |
| VMP-24-22-012313 | TO-15 | Toluene | - | **U** |
| VMP-24-22-012313 | TO-15 | Tetrachloroethene | - | **U** |

| Sample ID | Parameter | Analyte | New Reporting Limit (RL) | Qualification |
|---|---|---|---|---|
| VMP-24-34-012313 | TO-15 | Carbon disulfide | - | **U** |
| VMP-24-34-012313 | TO-15 | Methylene chloride | - | **U** |
| VMP-24-34-012313 | TO-15 | Toluene | - | **U** |
| VMP-24-34-012313 | TO-15 | Tetrachloroethene | - | **U** |
| VMP-43-20-012413 | TO-15 | Carbon disulfide | - | **U** |
| VMP-43-20-012413 | TO-15 | Toluene | - | **U** |
| VMP-43-30-012413 | TO-15 | Carbon disulfide | - | **U** |
| VMP-43-30-012413 | TO-15 | Methylene chloride | - | **U** |
| VMP-43-30-012413 | TO-15 | Toluene | - | **U** |
| VMP-43-30-012413 | TO-15 | Tetrachloroethene | - | **U** |

## 5.0 Laboratory Control Sample

*Were LCS recoveries within evaluation criteria?*

Yes

## 6.0 Surrogate Recoveries

*Were surrogate recoveries within evaluation criteria?*

Yes

## 7.0 Matrix Spike and Matrix Spike Duplicate Recoveries

*Were MS/MSD samples analyzed as part of this SDG?*

MS/MSD samples are not applicable for vapor samples, due to the inability to spike the samples.

## 8.0 Laboratory Duplicate Results

*Were laboratory duplicate samples collected as part of this SDG?*

No

## 9.0 Field Duplicate Results

*Were field duplicate samples collected as part of this SDG?*

No

## 10.0 Sample Dilutions

*For samples that were diluted and nondetect, were undiluted results also reported?*

Not applicable; analytes were detected in samples that were diluted.

## 11.0 Additional Qualifications

*Were additional qualifications applied?*

No

eurofins | Air Toxics

2/11/2013
Ms. Elizabeth Kunkel
URS Corporation
1001 Highlands Plaza Dr. West
Suite 300
St. Louis MO 63110

Project Name: Roxana Soil Vapor
Project #: 21562850.04001
Workorder #: 1301504A

Dear Ms. Elizabeth Kunkel

The following report includes the data for the above referenced project for sample(s) received on 1/28/2013 at Air Toxics Ltd.

The data and associated QC analyzed by Modified TO-15 are compliant with the project requirements or laboratory criteria with the exception of the deviations noted in the attached case narrative.

Thank you for choosing Air Toxics Ltd. for your air analysis needs. Air Toxics Ltd. is committed to providing accurate data of the highest quality. Please feel free to contact the Project Manager: Kelly Buettner at 916-985-1000 if you have any questions regarding the data in this report.

Regards,

Kelly Buettner

Kelly Buettner
Project Manager

REVIEWED
ON
3/19/13

eurofins | Air Toxics

# WORK ORDER #: 1301504A

Work Order Summary

| | | | |
|---|---|---|---|
| **CLIENT:** | Ms. Elizabeth Kunkel<br>URS Corporation<br>1001 Highlands Plaza Dr. West<br>Suite 300<br>St. Louis, MO 63110 | **BILL TO:** | Accounts Payable Austin<br>URS Corporation<br>P.O. BOX 203970<br>Austin, TX 78720-1088 |
| **PHONE:** | 314-743-4179 | **P.O. #** | 21562735.00013 |
| **FAX:** | | **PROJECT #** | 21562850.04001 Roxana Soil Vapor |
| **DATE RECEIVED:** | 01/28/2013 | **CONTACT:** | Kelly Buettner |
| **DATE COMPLETED:** | 02/11/2013 | | |

| FRACTION # | NAME | TEST | RECEIPT VAC./PRES. | FINAL PRESSURE |
|---|---|---|---|---|
| 01A(cancelled) | VMP-20-5-012213 | Modified TO-15 | 0.0 "Hg | 15 psi |
| 02A | VMP-20-10-012213 | Modified TO-15 | 5.5 "Hg | 15 psi |
| 03A | VMP-20-25-012213 | Modified TO-15 | 5.5 "Hg | 15 psi |
| 04A | VMP-22-5-012413 | Modified TO-15 | 6.5 "Hg | 15 psi |
| 05A | VMP-22-10-012413 | Modified TO-15 | 8.0 "Hg | 15 psi |
| 06A | VMP-22-18-012413 | Modified TO-15 | 8.0 "Hg | 15 psi |
| 07A | VMP-22-38-012413 | Modified TO-15 | 7.5 "Hg | 15 psi |
| 08A | VMP-23-5-012413 | Modified TO-15 | 5.5 "Hg | 15 psi |
| 09A | VMP-23-10-012413 | Modified TO-15 | 5.5 "Hg | 15 psi |
| 10A | VMP-23-25-012413 | Modified TO-15 | 6.0 "Hg | 15 psi |
| 11A | VMP-23-40-012413 | Modified TO-15 | 6.5 "Hg | 15 psi |
| 12A | VMP-24-5-012313 | Modified TO-15 | 6.0 "Hg | 15 psi |
| 13A | VMP-24-10-012313 | Modified TO-15 | 8.0 "Hg | 15 psi |
| 14A | VMP-24-22-012313 | Modified TO-15 | 8.5 "Hg | 15 psi |
| 15A | VMP-24-34-012313 | Modified TO-15 | 9.0 "Hg | 15 psi |
| 16A | VMP-43-20-012413 | Modified TO-15 | 7.0 "Hg | 15 psi |
| 17A | VMP-43-30-012413 | Modified TO-15 | 7.5 "Hg | 15 psi |
| 18A | Lab Blank | Modified TO-15 | NA | NA |
| 19A | CCV | Modified TO-15 | NA | NA |
| 20A | LCS | Modified TO-15 | NA | NA |
| 20AA | LCSD | Modified TO-15 | NA | NA |

CERTIFIED BY: Heidi Hayes DATE: 02/11/13

Technical Director

Certfication numbers: AZ Licensure AZ0775, CA NELAP - 12282CA, NY NELAP - 11291,
TX NELAP - T104704434-12-5, UT NELAP CA009332012-3, WA NELAP - C935
Name of Accrediting Agency: NELAP/ORELAP (Oregon Environmental Laboratory Accreditation Program)
Accreditation number: CA300005, Effective date: 10/18/2011, Expiration date: 10/17/2012.
Eurofins Air Toxics Ltd. certifies that the test results contained in this report meet all requirements of the NELAC standards

This report shall not be reproduced, except in full, without the written approval of Eurofins Air Toxics, Inc.

180 BLUE RAVINE ROAD, SUITE B FOLSOM, CA - 9563
(916) 985-1000 . (800) 985-5955 . FAX (916) 985-1020

**LABORATORY NARRATIVE**
**EPA Method TO-15**
**URS Corporation**
**Workorder# 1301504A**

Seventeen 1 Liter Summa Canister samples were received on January 28, 2013. The laboratory performed analysis via EPA Method TO-15 using GC/MS in the full scan mode.

This workorder was independently validated prior to submittal using 'USEPA National Functional Guidelines' as generally applied to the analysis of volatile organic compounds in air. A rules-based, logic driven, independent validation engine was employed to assess completeness, evaluate pass/fail of relevant project quality control requirements and verification of all quantified amounts.

**Receiving Notes**

The canister valve on sample VMP-20-5-012213 was received open and a brass plug was not used to seal the canister. The sample vented to ambient pressure during shipment. The client was contacted, and the sample was cancelled.

**Analytical Notes**

As per client project requirements, the laboratory has reported estimated values for target compound hits that are below the Reporting Limit but greater than the Method Detection Limit. Concentrations that are below the level at which the canister was certified may be false positives.

**Definition of Data Qualifying Flags**

Eight qualifiers may have been used on the data analysis sheets and indicates as follows:

B - Compound present in laboratory blank greater than reporting limit (background subtraction not performed).
J - Estimated value.
E - Exceeds instrument calibration range.
S - Saturated peak.
Q - Exceeds quality control limits.
U - Compound analyzed for but not detected above the reporting limit.
UJ- Non-detected compound associated with low bias in the CCV and/or LCS.
N - The identification is based on presumptive evidence.

File extensions may have been used on the data analysis sheets and indicates as follows:
a-File was requantified
b-File was quantified by a second column and detector
r1-File was requantified for the purpose of reissue

eurofins | Air Toxics

# Summary of Detected Compounds
# EPA METHOD TO-15 GC/MS FULL SCAN

**Client Sample ID: VMP-20-10-012213**

**Lab ID#: 1301504A-02A**

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 1.2 | 0.53 J | 6.1 | 2.6 J |
| Freon 11 | 1.2 | 0.58 J | 6.9 | 3.3 J |
| Ethanol | 4.9 | 2.1 J | 9.3 | 4.0 J |
| Acetone | 12 | 5.0 J | 29 | 12 J |
| 2-Propanol | 4.9 | 3.3 J | 12 | 8.0 J |
| Carbon Disulfide | 4.9 | ~~0.88 J~~ | 15 | ~~2.8 J~~ |
| Methylene Chloride | 12 | ~~0.22 J~~ | 43 | ~~0.77 J~~ |
| Hexane | 1.2 | 0.26 J | 4.4 | 0.90 J |
| 2,2,4-Trimethylpentane | 1.2 | 1.0 J | 5.8 | 4.9 J |
| Benzene | 1.2 | 0.57 J | 3.9 | 1.8 J |
| Toluene | 1.2 | ~~0.17 J~~ | 4.6 | ~~0.63 J~~ |
| Tetrachloroethene | 1.2 | ~~0.16 J~~ | 8.4 | ~~1.1 J~~ |
| 1,3-Dichlorobenzene | 1.2 | ~~0.29 J~~ | 7.4 | ~~1.7 J~~ |
| 1,4-Dichlorobenzene | 1.2 | ~~0.37 J~~ | 7.4 | ~~2.2 J~~ |
| 1,2,4-Trichlorobenzene | 4.9 | ~~0.87 J~~ | 37 | ~~6.4 J~~ |
| Isopentane | 4.9 | 0.67 J | 14 | 2.0 J |

**Client Sample ID: VMP-20-25-012213**

**Lab ID#: 1301504A-03A**

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 1.2 | 0.53 J | 6.1 | 2.6 J |
| Bromomethane | 12 | ~~0.58 J~~ | 48 | ~~2.2 J~~ |
| Freon 11 | 1.2 | 8.4 | 6.9 | 47 |
| Acetone | 12 | 4.6 J | 29 | 11 J |
| 2-Propanol | 4.9 | 3.9 J | 12 | 9.5 J |
| Carbon Disulfide | 4.9 | ~~1.1 J~~ | 15 | ~~3.3 J~~ |
| Methylene Chloride | 12 | ~~0.21 J~~ | 43 | ~~0.72 J~~ |
| Toluene | 1.2 | ~~0.10 J~~ | 4.6 | ~~0.38 J~~ |
| Tetrachloroethene | 1.2 | ~~0.19 J~~ | 8.4 | ~~1.3 J~~ |
| 1,3-Dichlorobenzene | 1.2 | ~~0.22 J~~ | 7.4 | ~~1.4 J~~ |
| 1,4-Dichlorobenzene | 1.2 | ~~0.23 J~~ | 7.4 | ~~1.4 J~~ |
| 1,2,4-Trichlorobenzene | 4.9 | ~~0.64 J~~ | 37 | ~~4.8 J~~ |

eurofins | Air Toxics

# Summary of Detected Compounds
# EPA METHOD TO-15 GC/MS FULL SCAN

**Client Sample ID: VMP-20-25-012213**

**Lab ID#: 1301504A-03A**

| | | | | |
|---|---|---|---|---|
| Butane | 4.9 | 1.2 J | 12 | 3.0 J |
| Isopentane | 4.9 | 0.72 J | 14 | 2.1 J |

**Client Sample ID: VMP-22-5-012413**

**Lab ID#: 1301504A-04A**

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 1.3 | 0.50 J | 6.4 | 2.5 J |
| Freon 11 | 1.3 | 0.26 J | 7.2 | 1.5 J |
| Ethanol | 5.2 | 1.1 J | 9.7 | 2.1 J |
| Acetone | 13 | 5.7 J | 31 | 14 J |
| 2-Propanol | 5.2 | 0.46 J | 13 | 1.1 J |
| Carbon Disulfide | 5.2 | ~~0.87 J~~ | 16 | ~~2.7 J~~ |
| Methylene Chloride | 13 | ~~0.16 J~~ | 45 | ~~0.54 J~~ |
| 2,2,4-Trimethylpentane | 1.3 | 1.7 | 6.0 | 8.1 |
| Benzene | 1.3 | 2.9 | 4.1 | 9.3 |
| Toluene | 1.3 | ~~0.23 J~~ | 4.9 | ~~0.88 J~~ |
| Tetrachloroethene | 1.3 | ~~0.14 J~~ | 8.8 | ~~0.96 J~~ |
| 4-Ethyltoluene | 1.3 | ~~0.10 J~~ | 6.3 | ~~0.49 J~~ |
| 1,3-Dichlorobenzene | 1.3 | ~~0.18 J~~ | 7.8 | ~~1.1 J~~ |
| 1,2,4-Trichlorobenzene | 5.2 | ~~0.52 J~~ | 38 | ~~3.9 J~~ |

**Client Sample ID: VMP-22-10-012413**

**Lab ID#: 1301504A-05A**

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 1.4 | 0.58 J | 6.8 | 2.9 J |
| Freon 11 | 1.4 | 0.24 J | 7.8 | 1.3 J |
| Ethanol | 5.5 | 1.1 J | 10 | 2.2 J |
| 2-Propanol | 5.5 | 2.1 J | 14 | 5.2 J |
| Carbon Disulfide | 5.5 | ~~0.83 J~~ | 17 | ~~2.6 J~~ |
| Methylene Chloride | 14 | ~~0.18 J~~ | 48 | ~~0.64 J~~ |
| 2,2,4-Trimethylpentane | 1.4 | 0.65 J | 6.4 | 3.0 J |
| Benzene | 1.4 | 0.57 J | 4.4 | 1.8 J |

eurofins | Air Toxics

# Summary of Detected Compounds
# EPA METHOD TO-15 GC/MS FULL SCAN

**Client Sample ID: VMP-22-10-012413**

**Lab ID#: 1301504A-05A**

| | | | | |
|---|---|---|---|---|
| Toluene | 1.4 | ~~0.15 J~~ U | 5.2 | ~~0.56 J~~ U |
| 4-Ethyltoluene | 1.4 | ~~0.19 J~~ U | 6.8 | ~~0.95 J~~ U |
| 1,3-Dichlorobenzene | 1.4 | ~~0.18 J~~ U | 8.3 | ~~1.1 J~~ U |
| 1,2,4-Trichlorobenzene | 5.5 | ~~0.48 J~~ U | 41 | ~~3.6 J~~ U |

**Client Sample ID: VMP-22-18-012413**

**Lab ID#: 1301504A-06A**

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 1.4 | 0.58 J | 6.8 | 2.9 J |
| Freon 11 | 1.4 | 0.24 J | 7.8 | 1.4 J |
| Ethanol | 5.5 | 1.3 J | 10 | 2.4 J |
| Acetone | 14 | ~~1.6 J~~ U | 33 | ~~3.8 J~~ U |
| 2-Propanol | 5.5 | 3.0 J | 14 | 7.3 J |
| Carbon Disulfide | 5.5 | ~~0.94 J~~ U | 17 | ~~2.9 J~~ U |
| Methylene Chloride | 14 | ~~0.21 J~~ U | 48 | ~~0.73 J~~ U |
| Chloroform | 1.4 | 3.0 | 6.7 | 15 |
| 2,2,4-Trimethylpentane | 1.4 | 0.45 J | 6.4 | 2.1 J |
| Benzene | 1.4 | 0.61 J | 4.4 | 2.0 J |
| Toluene | 1.4 | ~~0.12 J~~ U | 5.2 | ~~0.46 J~~ U |
| Tetrachloroethene | 1.4 | ~~0.14 J~~ U | 9.4 | ~~0.98 J~~ U |
| 4-Ethyltoluene | 1.4 | ~~0.23 J~~ U | 6.8 | ~~1.1 J~~ U |

**Client Sample ID: VMP-22-38-012413**

**Lab ID#: 1301504A-07A**

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 1.3 | 0.50 J | 6.6 | 2.5 J |
| Freon 11 | 1.3 | 0.26 J | 7.6 | 1.4 J |
| Ethanol | 5.4 | 1.5 J | 10 | 2.9 J |
| Acetone | 13 | 4.9 J | 32 | 12 J |
| 2-Propanol | 5.4 | 2.5 J | 13 | 6.1 J |
| Carbon Disulfide | 5.4 | ~~1.0 J~~ U | 17 | ~~3.2 J~~ U |
| Chloroform | 1.3 | 13 | 6.6 | 62 |

eurofins | Air Toxics

# Summary of Detected Compounds
# EPA METHOD TO-15 GC/MS FULL SCAN

**Client Sample ID: VMP-22-38-012413**

**Lab ID#: 1301504A-07A**

| | | | | |
|---|---|---|---|---|
| 2,2,4-Trimethylpentane | 1.3 | 0.44 J | 6.3 | 2.1 J |
| Benzene | 1.3 | 0.80 J | 4.3 | 2.6 J |
| Toluene | 1.3 | ~~0.13 J~~ | 5.1 | ~~0.48 J~~ |
| Tetrachloroethene | 1.3 | ~~0.16 J~~ | 9.1 | ~~1.1 J~~ |
| 4-Ethyltoluene | 1.3 | ~~0.095 J~~ | 6.6 | ~~0.47 J~~ |
| 1,2,4-Trichlorobenzene | 5.4 | ~~0.38 J~~ | 40 | ~~2.8 J~~ |
| Isopentane | 5.4 | 0.74 J | 16 | 2.2 J |

**Client Sample ID: VMP-23-5-012413**

**Lab ID#: 1301504A-08A**

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 1.2 | 0.47 J | 6.1 | 2.3 J |
| Freon 11 | 1.2 | 0.24 J | 6.9 | 1.4 J |
| Ethanol | 4.9 | 0.83 J | 9.3 | 1.6 J |
| Acetone | 12 | 2.4 J | 29 | 5.6 J |
| 2-Propanol | 4.9 | 1.6 J | 12 | 4.0 J |
| Carbon Disulfide | 4.9 | ~~0.76 J~~ | 15 | ~~2.4 J~~ |
| Methylene Chloride | 12 | ~~0.17 J~~ | 43 | ~~0.60 J~~ |
| Hexane | 1.2 | 0.31 J | 4.4 | 1.1 J |
| 2,2,4-Trimethylpentane | 1.2 | 2.4 | 5.8 | 11 |
| Benzene | 1.2 | 0.60 J | 3.9 | 1.9 J |
| Toluene | 1.2 | ~~0.17 J~~ | 4.6 | ~~0.63 J~~ |
| 1,2,4-Trichlorobenzene | 4.9 | ~~0.36 J~~ | 37 | ~~2.7 J~~ |
| Butane | 4.9 | 4.8 J | 12 | 11 J |
| Isopentane | 4.9 | 5.0 | 14 | 15 |

**Client Sample ID: VMP-23-10-012413**

**Lab ID#: 1301504A-09A**

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 1.2 | 0.51 J | 6.1 | 2.5 J |
| Freon 11 | 1.2 | 0.22 J | 6.9 | 1.2 J |
| Ethanol | 4.9 | 1.5 J | 9.3 | 2.9 J |

eurofins | Air Toxics

# Summary of Detected Compounds
# EPA METHOD TO-15 GC/MS FULL SCAN

**Client Sample ID: VMP-23-10-012413**

**Lab ID#: 1301504A-09A**

| | | | | |
|---|---|---|---|---|
| Acetone | 12 | 3.0 J | 29 | 7.2 J |
| 2-Propanol | 4.9 | 1.9 J | 12 | 4.7 J |
| Carbon Disulfide | 4.9 | ~~0.82 J~~ | 15 | ~~2.6 J~~ |
| Methylene Chloride | 12 | ~~0.51 J~~ | 43 | ~~1.8 J~~ |
| Hexane | 1.2 | 0.29 J | 4.4 | 1.0 J |
| Chloroform | 1.2 | 0.33 J | 6.0 | 1.6 J |
| 2,2,4-Trimethylpentane | 1.2 | 1.1 J | 5.8 | 5.1 J |
| Toluene | 1.2 | ~~0.28 J~~ | 4.6 | ~~1.0 J~~ |
| Isopentane | 4.9 | 0.66 J | 14 | 2.0 J |

**Client Sample ID: VMP-23-25-012413**

**Lab ID#: 1301504A-10A**

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 1.3 | 0.49 J | 6.2 | 2.4 J |
| Freon 11 | 1.3 | 0.34 J | 7.1 | 1.9 J |
| Ethanol | 5.0 | 1.8 J | 9.5 | 3.3 J |
| Acetone | 13 | 3.1 J | 30 | 7.3 J |
| 2-Propanol | 5.0 | 0.76 J | 12 | 1.9 J |
| Carbon Disulfide | 5.0 | ~~0.68 J~~ | 16 | ~~2.1 J~~ |
| Methylene Chloride | 13 | ~~0.16 J~~ | 44 | ~~0.54 J~~ |
| Chloroform | 1.3 | 3.6 | 6.2 | 17 |
| 2,2,4-Trimethylpentane | 1.3 | 0.30 J | 5.9 | 1.4 J |
| Toluene | 1.3 | ~~0.11 J~~ | 4.7 | ~~0.42 J~~ |
| Tetrachloroethene | 1.3 | ~~0.28 J~~ | 8.5 | ~~1.9 J~~ |
| Butane | 5.0 | 2.5 J | 12 | 5.9 J |
| Isopentane | 5.0 | 2.6 J | 15 | 7.6 J |

**Client Sample ID: VMP-23-40-012413**

**Lab ID#: 1301504A-11A**

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 1.3 | 0.52 J | 6.4 | 2.6 J |
| Freon 11 | 1.3 | 0.47 J | 7.2 | 2.7 J |

eurofins | Air Toxics

# Summary of Detected Compounds
# EPA METHOD TO-15 GC/MS FULL SCAN

**Client Sample ID: VMP-23-40-012413**

**Lab ID#: 1301504A-11A**

| | | | | |
|---|---|---|---|---|
| Ethanol | 5.2 | 0.70 J | 9.7 | 1.3 J |
| Acetone | 13 | 5.3 J | 31 | 12 J |
| 2-Propanol | 5.2 | 0.87 J | 13 | 2.1 J |
| Carbon Disulfide | 5.2 | ~~0.76 J~~ | 16 | ~~2.4 J~~ |
| Hexane | 1.3 | 0.34 J | 4.5 | 1.2 J |
| 2-Butanone (Methyl Ethyl Ketone) | 5.2 | 0.82 J | 15 | 2.4 J |
| Chloroform | 1.3 | 1.4 | 6.3 | 6.9 |
| 2,2,4-Trimethylpentane | 1.3 | 1.8 | 6.0 | 8.2 |
| Butane | 5.2 | 1.9 J | 12 | 4.5 J |
| Isopentane | 5.2 | 3.4 J | 15 | 10 J |

**Client Sample ID: VMP-24-5-012313**

**Lab ID#: 1301504A-12A**

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 1.3 | 0.49 J | 6.2 | 2.4 J |
| Freon 11 | 1.3 | 0.25 J | 7.1 | 1.4 J |
| Ethanol | 5.0 | 2.6 J | 9.5 | 4.8 J |
| Acetone | 13 | 10 J | 30 | 25 J |
| 2-Propanol | 5.0 | 15 | 12 | 36 |
| Carbon Disulfide | 5.0 | ~~0.69 J~~ | 16 | ~~2.2 J~~ |
| 2,2,4-Trimethylpentane | 1.3 | 4.0 | 5.9 | 19 |
| Benzene | 1.3 | 2.7 | 4.0 | 8.8 |
| Toluene | 1.3 | ~~0.14 J~~ | 4.7 | ~~0.53 J~~ |

**Client Sample ID: VMP-24-10-012313**

**Lab ID#: 1301504A-13A**

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 1.4 | 0.51 J | 6.8 | 2.5 J |
| Freon 11 | 1.4 | 0.31 J | 7.8 | 1.8 J |
| Ethanol | 5.5 | 4.0 J | 10 | 7.6 J |
| Acetone | 14 | ~~1.8 J~~ | 33 | ~~4.4 J~~ |
| 2-Propanol | 5.5 | 6.7 | 14 | 16 |

eurofins | Air Toxics

# Summary of Detected Compounds
# EPA METHOD TO-15 GC/MS FULL SCAN

**Client Sample ID: VMP-24-10-012313**

**Lab ID#: 1301504A-13A**

| | | | | |
|---|---|---|---|---|
| Carbon Disulfide | 5.5 | ~~0.65 J~~ | 17 | ~~2.0 J~~ |
| Methylene Chloride | 14 | ~~0.48 J~~ | 48 | ~~1.6 J~~ |
| 2,2,4-Trimethylpentane | 1.4 | 2.2 | 6.4 | 10 |
| Benzene | 1.4 | 2.2 | 4.4 | 7.2 |
| Toluene | 1.4 | 0.34 J | 5.2 | 1.3 J |
| Tetrachloroethene | 1.4 | ~~0.18 J~~ | 9.4 | ~~1.2 J~~ |
| Isopentane | 5.5 | 1.2 J | 16 | 3.4 J |

**Client Sample ID: VMP-24-22-012313**

**Lab ID#: 1301504A-14A**

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 1.4 | 0.59 J | 7.0 | 2.9 J |
| Freon 11 | 1.4 | 0.30 J | 7.9 | 1.7 J |
| Ethanol | 5.6 | 2.0 J | 11 | 3.9 J |
| Acetone | 14 | 2.9 J | 33 | 6.9 J |
| 2-Propanol | 5.6 | 4.0 J | 14 | 9.8 J |
| Carbon Disulfide | 5.6 | ~~0.65 J~~ | 18 | ~~2.0 J~~ |
| Methylene Chloride | 14 | ~~0.27 J~~ | 49 | ~~0.94 J~~ |
| 2,2,4-Trimethylpentane | 1.4 | 2.3 | 6.6 | 10 |
| Toluene | 1.4 | ~~0.14 J~~ | 5.3 | ~~0.51 J~~ |
| Tetrachloroethene | 1.4 | ~~0.21 J~~ | 9.6 | ~~1.4 J~~ |
| Butane | 5.6 | 9.4 | 13 | 22 |
| Isopentane | 5.6 | 3.7 J | 17 | 11 J |

**Client Sample ID: VMP-24-34-012313**

**Lab ID#: 1301504A-15A**

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 1.4 | 0.55 J | 7.1 | 2.7 J |
| Freon 11 | 1.4 | 0.33 J | 8.1 | 1.8 J |
| Ethanol | 5.8 | 1.2 J | 11 | 2.2 J |
| Acetone | 14 | 3.8 J | 34 | 9.0 J |
| 2-Propanol | 5.8 | 1.3 J | 14 | 3.2 J |

eurofins | Air Toxics

# Summary of Detected Compounds
# EPA METHOD TO-15 GC/MS FULL SCAN

**Client Sample ID: VMP-24-34-012313**

**Lab ID#: 1301504A-15A**

| | | | | |
|---|---|---|---|---|
| Carbon Disulfide | 5.8 | ~~0.58 J~~ | 18 | ~~1.8 J~~ |
| Methylene Chloride | 14 | ~~0.30 J~~ | 50 | ~~1.0 J~~ |
| 2,2,4-Trimethylpentane | 1.4 | 1.7 | 6.8 | 8.1 |
| Benzene | 1.4 | 2.1 | 4.6 | 6.8 |
| Toluene | 1.4 | ~~0.12 J~~ | 5.4 | ~~0.45 J~~ |
| Tetrachloroethene | 1.4 | ~~0.17 J~~ | 9.8 | ~~1.2 J~~ |

**Client Sample ID: VMP-43-20-012413**

**Lab ID#: 1301504A-16A**

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 1.3 | 0.62 J | 6.5 | 3.1 J |
| Freon 11 | 1.3 | 0.29 J | 7.4 | 1.6 J |
| Ethanol | 5.3 | 2.0 J | 9.9 | 3.7 J |
| Acetone | 13 | 4.4 J | 31 | 10 J |
| 2-Propanol | 5.3 | 1.4 J | 13 | 3.5 J |
| Carbon Disulfide | 5.3 | ~~2.0 J~~ | 16 | ~~6.2 J~~ |
| Chloroform | 1.3 | 0.46 J | 6.4 | 2.2 J |
| 2,2,4-Trimethylpentane | 1.3 | 5.3 | 6.2 | 25 |
| Benzene | 1.3 | 0.67 J | 4.2 | 2.1 J |
| 4-Methyl-2-pentanone | 1.3 | 0.45 J | 5.4 | 1.8 J |
| Toluene | 1.3 | ~~0.20 J~~ | 5.0 | ~~0.75 J~~ |
| Tetrachloroethene | 1.3 | 0.56 J | 9.0 | 3.8 J |
| Butane | 5.3 | 6.9 | 12 | 16 |
| Isopentane | 5.3 | 1.4 J | 16 | 4.0 J |

**Client Sample ID: VMP-43-30-012413**

**Lab ID#: 1301504A-17A**

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 1.3 | 0.54 J | 6.6 | 2.6 J |
| Freon 11 | 1.3 | 0.22 J | 7.6 | 1.2 J |
| Ethanol | 5.4 | 3.5 J | 10 | 6.6 J |
| Acetone | 13 | 2.3 J | 32 | 5.5 J |

eurofins | Air Toxics

# Summary of Detected Compounds
# EPA METHOD TO-15 GC/MS FULL SCAN

**Client Sample ID: VMP-43-30-012413**

**Lab ID#: 1301504A-17A**

| | | | | |
|---|---|---|---|---|
| 2-Propanol | 5.4 | 6.5 | 13 | 16 |
| Carbon Disulfide | 5.4 | ~~0.72 J~~ | 17 | ~~2.2 J~~ |
| Methylene Chloride | 13 | ~~0.17 J~~ | 47 | ~~0.59 J~~ |
| 2,2,4-Trimethylpentane | 1.3 | 0.39 J | 6.3 | 1.8 J |
| Benzene | 1.3 | 3.8 | 4.3 | 12 |
| Toluene | 1.3 | ~~0.30 J~~ | 5.1 | ~~1.1 J~~ |
| Tetrachloroethene | 1.3 | ~~0.16 J~~ | 9.1 | ~~1.1 J~~ |
| Butane | 5.4 | 1.7 J | 13 | 4.0 J |
| Isopentane | 5.4 | 1.6 J | 16 | 4.8 J |

eurofins | Air Toxics

**Client Sample ID: VMP-20-10-012213**

**Lab ID#: 1301504A-02A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p020408** | **Date of Collection:** | **1/22/13 11:32:00 AM** |
| **Dil. Factor:** | **2.47** | **Date of Analysis:** | **2/4/13 01:03 PM** |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 1.2 | 0.53 J | 6.1 | 2.6 J |
| Freon 114 | 1.2 | Not Detected | 8.6 | Not Detected |
| Chloromethane | 12 | Not Detected | 26 | Not Detected |
| Vinyl Chloride | 1.2 | Not Detected | 3.2 | Not Detected |
| 1,3-Butadiene | 1.2 | Not Detected | 2.7 | Not Detected |
| Bromomethane | 12 | Not Detected | 48 | Not Detected |
| Chloroethane | 4.9 | Not Detected | 13 | Not Detected |
| Freon 11 | 1.2 | 0.58 J | 6.9 | 3.3 J |
| Ethanol | 4.9 | 2.1 J | 9.3 | 4.0 J |
| Freon 113 | 1.2 | Not Detected | 9.5 | Not Detected |
| 1,1-Dichloroethene | 1.2 | Not Detected | 4.9 | Not Detected |
| Acetone | 12 | 5.0 J | 29 | 12 J |
| 2-Propanol | 4.9 | 3.3 J | 12 | 8.0 J |
| Carbon Disulfide | 4.9 | ~~0.68 J~~ | 15 | ~~2.8 J~~ |
| 3-Chloropropene | 4.9 | Not Detected | 15 | Not Detected |
| Methylene Chloride | 12 | ~~0.22 J~~ | 43 | ~~0.77 J~~ |
| Methyl tert-butyl ether | 1.2 | Not Detected | 4.4 | Not Detected |
| trans-1,2-Dichloroethene | 1.2 | Not Detected | 4.9 | Not Detected |
| Hexane | 1.2 | 0.26 J | 4.4 | 0.90 J |
| 1,1-Dichloroethane | 1.2 | Not Detected | 5.0 | Not Detected |
| 2-Butanone (Methyl Ethyl Ketone) | 4.9 | Not Detected | 14 | Not Detected |
| cis-1,2-Dichloroethene | 1.2 | Not Detected | 4.9 | Not Detected |
| Tetrahydrofuran | 1.2 | Not Detected | 3.6 | Not Detected |
| Chloroform | 1.2 | Not Detected | 6.0 | Not Detected |
| 1,1,1-Trichloroethane | 1.2 | Not Detected | 6.7 | Not Detected |
| Cyclohexane | 1.2 | Not Detected | 4.2 | Not Detected |
| Carbon Tetrachloride | 1.2 | Not Detected | 7.8 | Not Detected |
| 2,2,4-Trimethylpentane | 1.2 | 1.0 J | 5.8 | 4.9 J |
| Benzene | 1.2 | 0.57 J | 3.9 | 1.8 J |
| 1,2-Dichloroethane | 1.2 | Not Detected | 5.0 | Not Detected |
| Heptane | 1.2 | Not Detected | 5.1 | Not Detected |
| Trichloroethene | 1.2 | Not Detected | 6.6 | Not Detected |
| 1,2-Dichloropropane | 1.2 | Not Detected | 5.7 | Not Detected |
| 1,4-Dioxane | 4.9 | Not Detected | 18 | Not Detected |
| Bromodichloromethane | 1.2 | Not Detected | 8.3 | Not Detected |
| cis-1,3-Dichloropropene | 1.2 | Not Detected | 5.6 | Not Detected |
| 4-Methyl-2-pentanone | 1.2 | Not Detected | 5.0 | Not Detected |
| Toluene | 1.2 | ~~0.17 J~~ | 4.6 | ~~0.63 J~~ |
| trans-1,3-Dichloropropene | 1.2 | Not Detected | 5.6 | Not Detected |
| 1,1,2-Trichloroethane | 1.2 | Not Detected | 6.7 | Not Detected |
| Tetrachloroethene | 1.2 | ~~0.16 J~~ | 8.4 | ~~1.1 J~~ |
| 2-Hexanone | 4.9 | Not Detected | 20 | Not Detected |

eurofins | Air Toxics

**Client Sample ID: VMP-20-10-012213**

**Lab ID#: 1301504A-02A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p020408** | **Date of Collection:** | **1/22/13 11:32:00 AM** |
| **Dil. Factor:** | **2.47** | **Date of Analysis:** | **2/4/13 01:03 PM** |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Dibromochloromethane | 1.2 | Not Detected | 10 | Not Detected |
| 1,2-Dibromoethane (EDB) | 1.2 | Not Detected | 9.5 | Not Detected |
| Chlorobenzene | 1.2 | Not Detected | 5.7 | Not Detected |
| Ethyl Benzene | 1.2 | Not Detected | 5.4 | Not Detected |
| m,p-Xylene | 1.2 | Not Detected | 5.4 | Not Detected |
| o-Xylene | 1.2 | Not Detected | 5.4 | Not Detected |
| Styrene | 1.2 | Not Detected | 5.3 | Not Detected |
| Bromoform | 1.2 | Not Detected | 13 | Not Detected |
| Cumene | 1.2 | Not Detected | 6.1 | Not Detected |
| 1,1,2,2-Tetrachloroethane | 1.2 | Not Detected | 8.5 | Not Detected |
| Propylbenzene | 1.2 | Not Detected | 6.1 | Not Detected |
| 4-Ethyltoluene | 1.2 | Not Detected | 6.1 | Not Detected |
| 1,3,5-Trimethylbenzene | 1.2 | Not Detected | 6.1 | Not Detected |
| 1,2,4-Trimethylbenzene | 1.2 | Not Detected | 6.1 | Not Detected |
| 1,3-Dichlorobenzene | 1.2 | ~~0.29 J~~ | 7.4 | ~~1.7 J~~ |
| 1,4-Dichlorobenzene | 1.2 | ~~0.37 J~~ | 7.4 | ~~2.2 J~~ |
| alpha-Chlorotoluene | 1.2 | Not Detected | 6.4 | Not Detected |
| 1,2-Dichlorobenzene | 1.2 | Not Detected | 7.4 | Not Detected |
| 1,2,4-Trichlorobenzene | 4.9 | ~~0.87 J~~ | 37 | ~~6.4 J~~ |
| Hexachlorobutadiene | 4.9 | Not Detected | 53 | Not Detected |
| Butane | 4.9 | Not Detected | 12 | Not Detected |
| Isopentane | 4.9 | 0.67 J | 14 | 2.0 J |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| Toluene-d8 | 98 | 70-130 |
| 1,2-Dichloroethane-d4 | 90 | 70-130 |
| 4-Bromofluorobenzene | 97 | 70-130 |

eurofins | Air Toxics

**Client Sample ID: VMP-20-25-012213**

**Lab ID#: 1301504A-03A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | p020409 | **Date of Collection:** | 1/22/13 2:36:00 PM |
| **Dil. Factor:** | 2.47 | **Date of Analysis:** | 2/4/13 01:39 PM |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 1.2 | 0.53 J | 6.1 | 2.6 J |
| Freon 114 | 1.2 | Not Detected | 8.6 | Not Detected |
| Chloromethane | 12 | Not Detected | 26 | Not Detected |
| Vinyl Chloride | 1.2 | Not Detected | 3.2 | Not Detected |
| 1,3-Butadiene | 1.2 | Not Detected | 2.7 | Not Detected |
| Bromomethane | 12 | ~~0.58 J~~ | 48 | ~~2.2 J~~ |
| Chloroethane | 4.9 | Not Detected | 13 | Not Detected |
| Freon 11 | 1.2 | 8.4 | 6.9 | 47 |
| Ethanol | 4.9 | Not Detected | 9.3 | Not Detected |
| Freon 113 | 1.2 | Not Detected | 9.5 | Not Detected |
| 1,1-Dichloroethene | 1.2 | Not Detected | 4.9 | Not Detected |
| Acetone | 12 | 4.6 J | 29 | 11 J |
| 2-Propanol | 4.9 | 3.9 J | 12 | 9.5 J |
| Carbon Disulfide | 4.9 | ~~1.1 J~~ | 15 | ~~3.3 J~~ |
| 3-Chloropropene | 4.9 | Not Detected | 15 | Not Detected |
| Methylene Chloride | 12 | ~~0.21 J~~ | 43 | ~~0.72 J~~ |
| Methyl tert-butyl ether | 1.2 | Not Detected | 4.4 | Not Detected |
| trans-1,2-Dichloroethene | 1.2 | Not Detected | 4.9 | Not Detected |
| Hexane | 1.2 | Not Detected | 4.4 | Not Detected |
| 1,1-Dichloroethane | 1.2 | Not Detected | 5.0 | Not Detected |
| 2-Butanone (Methyl Ethyl Ketone) | 4.9 | Not Detected | 14 | Not Detected |
| cis-1,2-Dichloroethene | 1.2 | Not Detected | 4.9 | Not Detected |
| Tetrahydrofuran | 1.2 | Not Detected | 3.6 | Not Detected |
| Chloroform | 1.2 | Not Detected | 6.0 | Not Detected |
| 1,1,1-Trichloroethane | 1.2 | Not Detected | 6.7 | Not Detected |
| Cyclohexane | 1.2 | Not Detected | 4.2 | Not Detected |
| Carbon Tetrachloride | 1.2 | Not Detected | 7.8 | Not Detected |
| 2,2,4-Trimethylpentane | 1.2 | Not Detected | 5.8 | Not Detected |
| Benzene | 1.2 | Not Detected | 3.9 | Not Detected |
| 1,2-Dichloroethane | 1.2 | Not Detected | 5.0 | Not Detected |
| Heptane | 1.2 | Not Detected | 5.1 | Not Detected |
| Trichloroethene | 1.2 | Not Detected | 6.6 | Not Detected |
| 1,2-Dichloropropane | 1.2 | Not Detected | 5.7 | Not Detected |
| 1,4-Dioxane | 4.9 | Not Detected | 18 | Not Detected |
| Bromodichloromethane | 1.2 | Not Detected | 8.3 | Not Detected |
| cis-1,3-Dichloropropene | 1.2 | Not Detected | 5.6 | Not Detected |
| 4-Methyl-2-pentanone | 1.2 | Not Detected | 5.0 | Not Detected |
| Toluene | 1.2 | ~~0.10 J~~ | 4.6 | ~~0.38 J~~ |
| trans-1,3-Dichloropropene | 1.2 | Not Detected | 5.6 | Not Detected |
| 1,1,2-Trichloroethane | 1.2 | Not Detected | 6.7 | Not Detected |
| Tetrachloroethene | 1.2 | ~~0.19 J~~ | 8.4 | ~~1.3 J~~ |
| 2-Hexanone | 4.9 | Not Detected | 20 | Not Detected |

eurofins | Air Toxics

**Client Sample ID: VMP-20-25-012213**

**Lab ID#: 1301504A-03A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p020409** | **Date of Collection:** | **1/22/13 2:36:00 PM** |
| **Dil. Factor:** | **2.47** | **Date of Analysis:** | **2/4/13 01:39 PM** |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Dibromochloromethane | 1.2 | Not Detected | 10 | Not Detected |
| 1,2-Dibromoethane (EDB) | 1.2 | Not Detected | 9.5 | Not Detected |
| Chlorobenzene | 1.2 | Not Detected | 5.7 | Not Detected |
| Ethyl Benzene | 1.2 | Not Detected | 5.4 | Not Detected |
| m,p-Xylene | 1.2 | Not Detected | 5.4 | Not Detected |
| o-Xylene | 1.2 | Not Detected | 5.4 | Not Detected |
| Styrene | 1.2 | Not Detected | 5.3 | Not Detected |
| Bromoform | 1.2 | Not Detected | 13 | Not Detected |
| Cumene | 1.2 | Not Detected | 6.1 | Not Detected |
| 1,1,2,2-Tetrachloroethane | 1.2 | Not Detected | 8.5 | Not Detected |
| Propylbenzene | 1.2 | Not Detected | 6.1 | Not Detected |
| 4-Ethyltoluene | 1.2 | Not Detected | 6.1 | Not Detected |
| 1,3,5-Trimethylbenzene | 1.2 | Not Detected | 6.1 | Not Detected |
| 1,2,4-Trimethylbenzene | 1.2 | Not Detected | 6.1 | Not Detected |
| 1,3-Dichlorobenzene | 1.2 | ~~0.22 J~~ | 7.4 | ~~1.4 J~~ |
| 1,4-Dichlorobenzene | 1.2 | ~~0.23 J~~ | 7.4 | ~~1.4 J~~ |
| alpha-Chlorotoluene | 1.2 | Not Detected | 6.4 | Not Detected |
| 1,2-Dichlorobenzene | 1.2 | Not Detected | 7.4 | Not Detected |
| 1,2,4-Trichlorobenzene | 4.9 | ~~0.84 J~~ | 37 | ~~4.8 J~~ |
| Hexachlorobutadiene | 4.9 | Not Detected | 53 | Not Detected |
| Butane | 4.9 | 1.2 J | 12 | 3.0 J |
| Isopentane | 4.9 | 0.72 J | 14 | 2.1 J |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| Toluene-d8 | 98 | 70-130 |
| 1,2-Dichloroethane-d4 | 89 | 70-130 |
| 4-Bromofluorobenzene | 98 | 70-130 |

eurofins | Air Toxics

**Client Sample ID: VMP-22-5-012413**

**Lab ID#: 1301504A-04A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p020410** | **Date of Collection:** | **1/24/13 10:37:00 AM** |
| **Dil. Factor:** | **2.58** | **Date of Analysis:** | **2/4/13 02:20 PM** |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 1.3 | 0.50 J | 6.4 | 2.5 J |
| Freon 114 | 1.3 | Not Detected | 9.0 | Not Detected |
| Chloromethane | 13 | Not Detected | 27 | Not Detected |
| Vinyl Chloride | 1.3 | Not Detected | 3.3 | Not Detected |
| 1,3-Butadiene | 1.3 | Not Detected | 2.8 | Not Detected |
| Bromomethane | 13 | Not Detected | 50 | Not Detected |
| Chloroethane | 5.2 | Not Detected | 14 | Not Detected |
| Freon 11 | 1.3 | 0.26 J | 7.2 | 1.5 J |
| Ethanol | 5.2 | 1.1 J | 9.7 | 2.1 J |
| Freon 113 | 1.3 | Not Detected | 9.9 | Not Detected |
| 1,1-Dichloroethene | 1.3 | Not Detected | 5.1 | Not Detected |
| Acetone | 13 | 5.7 J | 31 | 14 J |
| 2-Propanol | 5.2 | 0.46 J | 13 | 1.1 J |
| Carbon Disulfide | 5.2 | ~~0.87 J~~ | 16 | ~~2.7 J~~ |
| 3-Chloropropene | 5.2 | Not Detected | 16 | Not Detected |
| Methylene Chloride | 13 | ~~0.16 J~~ | 45 | ~~0.54 J~~ |
| Methyl tert-butyl ether | 1.3 | Not Detected | 4.6 | Not Detected |
| trans-1,2-Dichloroethene | 1.3 | Not Detected | 5.1 | Not Detected |
| Hexane | 1.3 | Not Detected | 4.5 | Not Detected |
| 1,1-Dichloroethane | 1.3 | Not Detected | 5.2 | Not Detected |
| 2-Butanone (Methyl Ethyl Ketone) | 5.2 | Not Detected | 15 | Not Detected |
| cis-1,2-Dichloroethene | 1.3 | Not Detected | 5.1 | Not Detected |
| Tetrahydrofuran | 1.3 | Not Detected | 3.8 | Not Detected |
| Chloroform | 1.3 | Not Detected | 6.3 | Not Detected |
| 1,1,1-Trichloroethane | 1.3 | Not Detected | 7.0 | Not Detected |
| Cyclohexane | 1.3 | Not Detected | 4.4 | Not Detected |
| Carbon Tetrachloride | 1.3 | Not Detected | 8.1 | Not Detected |
| 2,2,4-Trimethylpentane | 1.3 | 1.7 | 6.0 | 8.1 |
| Benzene | 1.3 | 2.9 | 4.1 | 9.3 |
| 1,2-Dichloroethane | 1.3 | Not Detected | 5.2 | Not Detected |
| Heptane | 1.3 | Not Detected | 5.3 | Not Detected |
| Trichloroethene | 1.3 | Not Detected | 6.9 | Not Detected |
| 1,2-Dichloropropane | 1.3 | Not Detected | 6.0 | Not Detected |
| 1,4-Dioxane | 5.2 | Not Detected | 18 | Not Detected |
| Bromodichloromethane | 1.3 | Not Detected | 8.6 | Not Detected |
| cis-1,3-Dichloropropene | 1.3 | Not Detected | 5.8 | Not Detected |
| 4-Methyl-2-pentanone | 1.3 | Not Detected | 5.3 | Not Detected |
| Toluene | 1.3 | ~~0.23 J~~ | 4.9 | ~~0.88 J~~ |
| trans-1,3-Dichloropropene | 1.3 | Not Detected | 5.8 | Not Detected |
| 1,1,2-Trichloroethane | 1.3 | Not Detected | 7.0 | Not Detected |
| Tetrachloroethene | 1.3 | ~~0.14 J~~ | 8.8 | ~~0.96 J~~ |
| 2-Hexanone | 5.2 | Not Detected | 21 | Not Detected |

eurofins | Air Toxics

**Client Sample ID: VMP-22-5-012413**

**Lab ID#: 1301504A-04A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p020410** | **Date of Collection:** | **1/24/13 10:37:00 AM** |
| **Dil. Factor:** | **2.58** | **Date of Analysis:** | **2/4/13 02:20 PM** |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Dibromochloromethane | 1.3 | Not Detected | 11 | Not Detected |
| 1,2-Dibromoethane (EDB) | 1.3 | Not Detected | 9.9 | Not Detected |
| Chlorobenzene | 1.3 | Not Detected | 5.9 | Not Detected |
| Ethyl Benzene | 1.3 | Not Detected | 5.6 | Not Detected |
| m,p-Xylene | 1.3 | Not Detected | 5.6 | Not Detected |
| o-Xylene | 1.3 | Not Detected | 5.6 | Not Detected |
| Styrene | 1.3 | Not Detected | 5.5 | Not Detected |
| Bromoform | 1.3 | Not Detected | 13 | Not Detected |
| Cumene | 1.3 | Not Detected | 6.3 | Not Detected |
| 1,1,2,2-Tetrachloroethane | 1.3 | Not Detected | 8.8 | Not Detected |
| Propylbenzene | 1.3 | Not Detected | 6.3 | Not Detected |
| 4-Ethyltoluene | 1.3 | ~~0.10 J~~ | 6.3 | ~~0.49 J~~ |
| 1,3,5-Trimethylbenzene | 1.3 | Not Detected | 6.3 | Not Detected |
| 1,2,4-Trimethylbenzene | 1.3 | Not Detected | 6.3 | Not Detected |
| 1,3-Dichlorobenzene | 1.3 | ~~0.18 J~~ | 7.8 | ~~1.1 J~~ |
| 1,4-Dichlorobenzene | 1.3 | Not Detected | 7.8 | Not Detected |
| alpha-Chlorotoluene | 1.3 | Not Detected | 6.7 | Not Detected |
| 1,2-Dichlorobenzene | 1.3 | Not Detected | 7.8 | Not Detected |
| 1,2,4-Trichlorobenzene | 5.2 | ~~0.52 J~~ | 38 | ~~3.9 J~~ |
| Hexachlorobutadiene | 5.2 | Not Detected | 55 | Not Detected |
| Butane | 5.2 | Not Detected | 12 | Not Detected |
| Isopentane | 5.2 | Not Detected | 15 | Not Detected |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| Toluene-d8 | 96 | 70-130 |
| 1,2-Dichloroethane-d4 | 90 | 70-130 |
| 4-Bromofluorobenzene | 98 | 70-130 |

eurofins | Air Toxics

**Client Sample ID: VMP-22-10-012413**

**Lab ID#: 1301504A-05A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p020411** | **Date of Collection:** | **1/24/13 11:22:00 AM** |
| **Dil. Factor:** | **2.76** | **Date of Analysis:** | **2/4/13 03:04 PM** |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 1.4 | 0.58 J | 6.8 | 2.9 J |
| Freon 114 | 1.4 | Not Detected | 9.6 | Not Detected |
| Chloromethane | 14 | Not Detected | 28 | Not Detected |
| Vinyl Chloride | 1.4 | Not Detected | 3.5 | Not Detected |
| 1,3-Butadiene | 1.4 | Not Detected | 3.0 | Not Detected |
| Bromomethane | 14 | Not Detected | 54 | Not Detected |
| Chloroethane | 5.5 | Not Detected | 14 | Not Detected |
| Freon 11 | 1.4 | 0.24 J | 7.8 | 1.3 J |
| Ethanol | 5.5 | 1.1 J | 10 | 2.2 J |
| Freon 113 | 1.4 | Not Detected | 10 | Not Detected |
| 1,1-Dichloroethene | 1.4 | Not Detected | 5.5 | Not Detected |
| Acetone | 14 | Not Detected | 33 | Not Detected |
| 2-Propanol | 5.5 | 2.1 J | 14 | 5.2 J |
| Carbon Disulfide | 5.5 | ~~0.83 J~~ | 17 | ~~2.6 J~~ |
| 3-Chloropropene | 5.5 | Not Detected | 17 | Not Detected |
| Methylene Chloride | 14 | ~~0.18 J~~ | 48 | ~~0.64 J~~ |
| Methyl tert-butyl ether | 1.4 | Not Detected | 5.0 | Not Detected |
| trans-1,2-Dichloroethene | 1.4 | Not Detected | 5.5 | Not Detected |
| Hexane | 1.4 | Not Detected | 4.9 | Not Detected |
| 1,1-Dichloroethane | 1.4 | Not Detected | 5.6 | Not Detected |
| 2-Butanone (Methyl Ethyl Ketone) | 5.5 | Not Detected | 16 | Not Detected |
| cis-1,2-Dichloroethene | 1.4 | Not Detected | 5.5 | Not Detected |
| Tetrahydrofuran | 1.4 | Not Detected | 4.1 | Not Detected |
| Chloroform | 1.4 | Not Detected | 6.7 | Not Detected |
| 1,1,1-Trichloroethane | 1.4 | Not Detected | 7.5 | Not Detected |
| Cyclohexane | 1.4 | Not Detected | 4.8 | Not Detected |
| Carbon Tetrachloride | 1.4 | Not Detected | 8.7 | Not Detected |
| 2,2,4-Trimethylpentane | 1.4 | 0.65 J | 6.4 | 3.0 J |
| Benzene | 1.4 | 0.57 J | 4.4 | 1.8 J |
| 1,2-Dichloroethane | 1.4 | Not Detected | 5.6 | Not Detected |
| Heptane | 1.4 | Not Detected | 5.6 | Not Detected |
| Trichloroethene | 1.4 | Not Detected | 7.4 | Not Detected |
| 1,2-Dichloropropane | 1.4 | Not Detected | 6.4 | Not Detected |
| 1,4-Dioxane | 5.5 | Not Detected | 20 | Not Detected |
| Bromodichloromethane | 1.4 | Not Detected | 9.2 | Not Detected |
| cis-1,3-Dichloropropene | 1.4 | Not Detected | 6.3 | Not Detected |
| 4-Methyl-2-pentanone | 1.4 | Not Detected | 5.6 | Not Detected |
| Toluene | 1.4 | ~~0.15 J~~ | 5.2 | ~~0.56 J~~ |
| trans-1,3-Dichloropropene | 1.4 | Not Detected | 6.3 | Not Detected |
| 1,1,2-Trichloroethane | 1.4 | Not Detected | 7.5 | Not Detected |
| Tetrachloroethene | 1.4 | Not Detected | 9.4 | Not Detected |
| 2-Hexanone | 5.5 | Not Detected | 23 | Not Detected |

eurofins | Air Toxics

**Client Sample ID: VMP-22-10-012413**

**Lab ID#: 1301504A-05A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | p020411 | **Date of Collection:** | 1/24/13 11:22:00 AM |
| **Dil. Factor:** | 2.76 | **Date of Analysis:** | 2/4/13 03:04 PM |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Dibromochloromethane | 1.4 | Not Detected | 12 | Not Detected |
| 1,2-Dibromoethane (EDB) | 1.4 | Not Detected | 11 | Not Detected |
| Chlorobenzene | 1.4 | Not Detected | 6.4 | Not Detected |
| Ethyl Benzene | 1.4 | Not Detected | 6.0 | Not Detected |
| m,p-Xylene | 1.4 | Not Detected | 6.0 | Not Detected |
| o-Xylene | 1.4 | Not Detected | 6.0 | Not Detected |
| Styrene | 1.4 | Not Detected | 5.9 | Not Detected |
| Bromoform | 1.4 | Not Detected | 14 | Not Detected |
| Cumene | 1.4 | Not Detected | 6.8 | Not Detected |
| 1,1,2,2-Tetrachloroethane | 1.4 | Not Detected | 9.5 | Not Detected |
| Propylbenzene | 1.4 | Not Detected | 6.8 | Not Detected |
| 4-Ethyltoluene | 1.4 | ~~0.19 J~~ | 6.8 | ~~0.95 J~~ |
| 1,3,5-Trimethylbenzene | 1.4 | Not Detected | 6.8 | Not Detected |
| 1,2,4-Trimethylbenzene | 1.4 | Not Detected | 6.8 | Not Detected |
| 1,3-Dichlorobenzene | 1.4 | ~~0.18 J~~ | 8.3 | ~~1.1 J~~ |
| 1,4-Dichlorobenzene | 1.4 | Not Detected | 8.3 | Not Detected |
| alpha-Chlorotoluene | 1.4 | Not Detected | 7.1 | Not Detected |
| 1,2-Dichlorobenzene | 1.4 | Not Detected | 8.3 | Not Detected |
| 1,2,4-Trichlorobenzene | 5.5 | ~~0.48 J~~ | 41 | ~~3.6 J~~ |
| Hexachlorobutadiene | 5.5 | Not Detected | 59 | Not Detected |
| Butane | 5.5 | Not Detected | 13 | Not Detected |
| Isopentane | 5.5 | Not Detected | 16 | Not Detected |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| Toluene-d8 | 98 | 70-130 |
| 1,2-Dichloroethane-d4 | 91 | 70-130 |
| 4-Bromofluorobenzene | 98 | 70-130 |

eurofins | Air Toxics

**Client Sample ID: VMP-22-18-012413**

**Lab ID#: 1301504A-06A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p020412** | **Date of Collection:** | **1/24/13 12:11:00 PM** |
| **Dil. Factor:** | **2.76** | **Date of Analysis:** | **2/4/13 03:35 PM** |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 1.4 | 0.58 J | 6.8 | 2.9 J |
| Freon 114 | 1.4 | Not Detected | 9.6 | Not Detected |
| Chloromethane | 14 | Not Detected | 28 | Not Detected |
| Vinyl Chloride | 1.4 | Not Detected | 3.5 | Not Detected |
| 1,3-Butadiene | 1.4 | Not Detected | 3.0 | Not Detected |
| Bromomethane | 14 | Not Detected | 54 | Not Detected |
| Chloroethane | 5.5 | Not Detected | 14 | Not Detected |
| Freon 11 | 1.4 | 0.24 J | 7.8 | 1.4 J |
| Ethanol | 5.5 | 1.3 J | 10 | 2.4 J |
| Freon 113 | 1.4 | Not Detected | 10 | Not Detected |
| 1,1-Dichloroethene | 1.4 | Not Detected | 5.5 | Not Detected |
| Acetone | 14 | ~~1.6 J~~ | 33 | ~~3.8 J~~ |
| 2-Propanol | 5.5 | 3.0 J | 14 | 7.3 J |
| Carbon Disulfide | 5.5 | ~~0.94 J~~ | 17 | ~~2.9 J~~ |
| 3-Chloropropene | 5.5 | Not Detected | 17 | Not Detected |
| Methylene Chloride | 14 | ~~0.21 J~~ | 48 | ~~0.73 J~~ |
| Methyl tert-butyl ether | 1.4 | Not Detected | 5.0 | Not Detected |
| trans-1,2-Dichloroethene | 1.4 | Not Detected | 5.5 | Not Detected |
| Hexane | 1.4 | Not Detected | 4.9 | Not Detected |
| 1,1-Dichloroethane | 1.4 | Not Detected | 5.6 | Not Detected |
| 2-Butanone (Methyl Ethyl Ketone) | 5.5 | Not Detected | 16 | Not Detected |
| cis-1,2-Dichloroethene | 1.4 | Not Detected | 5.5 | Not Detected |
| Tetrahydrofuran | 1.4 | Not Detected | 4.1 | Not Detected |
| Chloroform | 1.4 | 3.0 | 6.7 | 15 |
| 1,1,1-Trichloroethane | 1.4 | Not Detected | 7.5 | Not Detected |
| Cyclohexane | 1.4 | Not Detected | 4.8 | Not Detected |
| Carbon Tetrachloride | 1.4 | Not Detected | 8.7 | Not Detected |
| 2,2,4-Trimethylpentane | 1.4 | 0.45 J | 6.4 | 2.1 J |
| Benzene | 1.4 | 0.61 J | 4.4 | 2.0 J |
| 1,2-Dichloroethane | 1.4 | Not Detected | 5.6 | Not Detected |
| Heptane | 1.4 | Not Detected | 5.6 | Not Detected |
| Trichloroethene | 1.4 | Not Detected | 7.4 | Not Detected |
| 1,2-Dichloropropane | 1.4 | Not Detected | 6.4 | Not Detected |
| 1,4-Dioxane | 5.5 | Not Detected | 20 | Not Detected |
| Bromodichloromethane | 1.4 | Not Detected | 9.2 | Not Detected |
| cis-1,3-Dichloropropene | 1.4 | Not Detected | 6.3 | Not Detected |
| 4-Methyl-2-pentanone | 1.4 | Not Detected | 5.6 | Not Detected |
| Toluene | 1.4 | ~~0.12 J~~ | 5.2 | ~~0.46 J~~ |
| trans-1,3-Dichloropropene | 1.4 | Not Detected | 6.3 | Not Detected |
| 1,1,2-Trichloroethane | 1.4 | Not Detected | 7.5 | Not Detected |
| Tetrachloroethene | 1.4 | ~~0.14 J~~ | 9.4 | ~~0.98 J~~ |
| 2-Hexanone | 5.5 | Not Detected | 23 | Not Detected |

eurofins | Air Toxics

**Client Sample ID: VMP-22-18-012413**

**Lab ID#: 1301504A-06A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | p020412 | **Date of Collection:** | 1/24/13 12:11:00 PM |
| **Dil. Factor:** | 2.76 | **Date of Analysis:** | 2/4/13 03:35 PM |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Dibromochloromethane | 1.4 | Not Detected | 12 | Not Detected |
| 1,2-Dibromoethane (EDB) | 1.4 | Not Detected | 11 | Not Detected |
| Chlorobenzene | 1.4 | Not Detected | 6.4 | Not Detected |
| Ethyl Benzene | 1.4 | Not Detected | 6.0 | Not Detected |
| m,p-Xylene | 1.4 | Not Detected | 6.0 | Not Detected |
| o-Xylene | 1.4 | Not Detected | 6.0 | Not Detected |
| Styrene | 1.4 | Not Detected | 5.9 | Not Detected |
| Bromoform | 1.4 | Not Detected | 14 | Not Detected |
| Cumene | 1.4 | Not Detected | 6.8 | Not Detected |
| 1,1,2,2-Tetrachloroethane | 1.4 | Not Detected | 9.5 | Not Detected |
| Propylbenzene | 1.4 | Not Detected | 6.8 | Not Detected |
| 4-Ethyltoluene | 1.4 | ~~0.23 J~~ | 6.8 | ~~1.1 J~~ |
| 1,3,5-Trimethylbenzene | 1.4 | Not Detected | 6.8 | Not Detected |
| 1,2,4-Trimethylbenzene | 1.4 | Not Detected | 6.8 | Not Detected |
| 1,3-Dichlorobenzene | 1.4 | Not Detected | 8.3 | Not Detected |
| 1,4-Dichlorobenzene | 1.4 | Not Detected | 8.3 | Not Detected |
| alpha-Chlorotoluene | 1.4 | Not Detected | 7.1 | Not Detected |
| 1,2-Dichlorobenzene | 1.4 | Not Detected | 8.3 | Not Detected |
| 1,2,4-Trichlorobenzene | 5.5 | Not Detected | 41 | Not Detected |
| Hexachlorobutadiene | 5.5 | Not Detected | 59 | Not Detected |
| Butane | 5.5 | Not Detected | 13 | Not Detected |
| Isopentane | 5.5 | Not Detected | 16 | Not Detected |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| Toluene-d8 | 98 | 70-130 |
| 1,2-Dichloroethane-d4 | 95 | 70-130 |
| 4-Bromofluorobenzene | 95 | 70-130 |

eurofins | Air Toxics

**Client Sample ID: VMP-22-38-012413**

**Lab ID#: 1301504A-07A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | p020413 | **Date of Collection:** | 1/24/13 1:01:00 PM |
| **Dil. Factor:** | 2.69 | **Date of Analysis:** | 2/4/13 04:08 PM |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 1.3 | 0.50 J | 6.6 | 2.5 J |
| Freon 114 | 1.3 | Not Detected | 9.4 | Not Detected |
| Chloromethane | 13 | Not Detected | 28 | Not Detected |
| Vinyl Chloride | 1.3 | Not Detected | 3.4 | Not Detected |
| 1,3-Butadiene | 1.3 | Not Detected | 3.0 | Not Detected |
| Bromomethane | 13 | Not Detected | 52 | Not Detected |
| Chloroethane | 5.4 | Not Detected | 14 | Not Detected |
| Freon 11 | 1.3 | 0.26 J | 7.6 | 1.4 J |
| Ethanol | 5.4 | 1.5 J | 10 | 2.9 J |
| Freon 113 | 1.3 | Not Detected | 10 | Not Detected |
| 1,1-Dichloroethene | 1.3 | Not Detected | 5.3 | Not Detected |
| Acetone | 13 | 4.9 J | 32 | 12 J |
| 2-Propanol | 5.4 | 2.5 J | 13 | 6.1 J |
| Carbon Disulfide | 5.4 | ~~1.0 J~~ | 17 | ~~3.2 J~~ |
| 3-Chloropropene | 5.4 | Not Detected | 17 | Not Detected |
| Methylene Chloride | 13 | Not Detected | 47 | Not Detected |
| Methyl tert-butyl ether | 1.3 | Not Detected | 4.8 | Not Detected |
| trans-1,2-Dichloroethene | 1.3 | Not Detected | 5.3 | Not Detected |
| Hexane | 1.3 | Not Detected | 4.7 | Not Detected |
| 1,1-Dichloroethane | 1.3 | Not Detected | 5.4 | Not Detected |
| 2-Butanone (Methyl Ethyl Ketone) | 5.4 | Not Detected | 16 | Not Detected |
| cis-1,2-Dichloroethene | 1.3 | Not Detected | 5.3 | Not Detected |
| Tetrahydrofuran | 1.3 | Not Detected | 4.0 | Not Detected |
| Chloroform | 1.3 | 13 | 6.6 | 62 |
| 1,1,1-Trichloroethane | 1.3 | Not Detected | 7.3 | Not Detected |
| Cyclohexane | 1.3 | Not Detected | 4.6 | Not Detected |
| Carbon Tetrachloride | 1.3 | Not Detected | 8.5 | Not Detected |
| 2,2,4-Trimethylpentane | 1.3 | 0.44 J | 6.3 | 2.1 J |
| Benzene | 1.3 | 0.80 J | 4.3 | 2.6 J |
| 1,2-Dichloroethane | 1.3 | Not Detected | 5.4 | Not Detected |
| Heptane | 1.3 | Not Detected | 5.5 | Not Detected |
| Trichloroethene | 1.3 | Not Detected | 7.2 | Not Detected |
| 1,2-Dichloropropane | 1.3 | Not Detected | 6.2 | Not Detected |
| 1,4-Dioxane | 5.4 | Not Detected | 19 | Not Detected |
| Bromodichloromethane | 1.3 | Not Detected | 9.0 | Not Detected |
| cis-1,3-Dichloropropene | 1.3 | Not Detected | 6.1 | Not Detected |
| 4-Methyl-2-pentanone | 1.3 | Not Detected | 5.5 | Not Detected |
| Toluene | 1.3 | ~~0.13 J~~ | 5.1 | ~~0.48 J~~ |
| trans-1,3-Dichloropropene | 1.3 | Not Detected | 6.1 | Not Detected |
| 1,1,2-Trichloroethane | 1.3 | Not Detected | 7.3 | Not Detected |
| Tetrachloroethene | 1.3 | ~~0.16 J~~ | 9.1 | ~~1.1 J~~ |
| 2-Hexanone | 5.4 | Not Detected | 22 | Not Detected |

eurofins | Air Toxics

**Client Sample ID: VMP-22-38-012413**

**Lab ID#: 1301504A-07A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p020413** | **Date of Collection:** | **1/24/13 1:01:00 PM** |
| **Dil. Factor:** | **2.69** | **Date of Analysis:** | **2/4/13 04:08 PM** |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Dibromochloromethane | 1.3 | Not Detected | 11 | Not Detected |
| 1,2-Dibromoethane (EDB) | 1.3 | Not Detected | 10 | Not Detected |
| Chlorobenzene | 1.3 | Not Detected | 6.2 | Not Detected |
| Ethyl Benzene | 1.3 | Not Detected | 5.8 | Not Detected |
| m,p-Xylene | 1.3 | Not Detected | 5.8 | Not Detected |
| o-Xylene | 1.3 | Not Detected | 5.8 | Not Detected |
| Styrene | 1.3 | Not Detected | 5.7 | Not Detected |
| Bromoform | 1.3 | Not Detected | 14 | Not Detected |
| Cumene | 1.3 | Not Detected | 6.6 | Not Detected |
| 1,1,2,2-Tetrachloroethane | 1.3 | Not Detected | 9.2 | Not Detected |
| Propylbenzene | 1.3 | Not Detected | 6.6 | Not Detected |
| 4-Ethyltoluene | 1.3 | ~~0.095 J~~ | 6.6 | ~~0.47 J~~ |
| 1,3,5-Trimethylbenzene | 1.3 | Not Detected | 6.6 | Not Detected |
| 1,2,4-Trimethylbenzene | 1.3 | Not Detected | 6.6 | Not Detected |
| 1,3-Dichlorobenzene | 1.3 | Not Detected | 8.1 | Not Detected |
| 1,4-Dichlorobenzene | 1.3 | Not Detected | 8.1 | Not Detected |
| alpha-Chlorotoluene | 1.3 | Not Detected | 7.0 | Not Detected |
| 1,2-Dichlorobenzene | 1.3 | Not Detected | 8.1 | Not Detected |
| 1,2,4-Trichlorobenzene | 5.4 | ~~0.38 J~~ | 40 | ~~2.8 J~~ |
| Hexachlorobutadiene | 5.4 | Not Detected | 57 | Not Detected |
| Butane | 5.4 | Not Detected | 13 | Not Detected |
| Isopentane | 5.4 | 0.74 J | 16 | 2.2 J |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| Toluene-d8 | 98 | 70-130 |
| 1,2-Dichloroethane-d4 | 94 | 70-130 |
| 4-Bromofluorobenzene | 97 | 70-130 |

eurofins | Air Toxics

**Client Sample ID: VMP-23-5-012413**

**Lab ID#: 1301504A-08A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | p020414 | **Date of Collection:** | 1/24/13 10:38:00 AM |
| **Dil. Factor:** | 2.47 | **Date of Analysis:** | 2/4/13 04:38 PM |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 1.2 | 0.47 J | 6.1 | 2.3 J |
| Freon 114 | 1.2 | Not Detected | 8.6 | Not Detected |
| Chloromethane | 12 | Not Detected | 26 | Not Detected |
| Vinyl Chloride | 1.2 | Not Detected | 3.2 | Not Detected |
| 1,3-Butadiene | 1.2 | Not Detected | 2.7 | Not Detected |
| Bromomethane | 12 | Not Detected | 48 | Not Detected |
| Chloroethane | 4.9 | Not Detected | 13 | Not Detected |
| Freon 11 | 1.2 | 0.24 J | 6.9 | 1.4 J |
| Ethanol | 4.9 | 0.83 J | 9.3 | 1.6 J |
| Freon 113 | 1.2 | Not Detected | 9.5 | Not Detected |
| 1,1-Dichloroethene | 1.2 | Not Detected | 4.9 | Not Detected |
| Acetone | 12 | 2.4 J | 29 | 5.6 J |
| 2-Propanol | 4.9 | 1.6 J | 12 | 4.0 J |
| Carbon Disulfide | 4.9 | ~~0.76 J~~ | 15 | ~~2.4 J~~ |
| 3-Chloropropene | 4.9 | Not Detected | 15 | Not Detected |
| Methylene Chloride | 12 | ~~0.17 J~~ | 43 | ~~0.60 J~~ |
| Methyl tert-butyl ether | 1.2 | Not Detected | 4.4 | Not Detected |
| trans-1,2-Dichloroethene | 1.2 | Not Detected | 4.9 | Not Detected |
| Hexane | 1.2 | 0.31 J | 4.4 | 1.1 J |
| 1,1-Dichloroethane | 1.2 | Not Detected | 5.0 | Not Detected |
| 2-Butanone (Methyl Ethyl Ketone) | 4.9 | Not Detected | 14 | Not Detected |
| cis-1,2-Dichloroethene | 1.2 | Not Detected | 4.9 | Not Detected |
| Tetrahydrofuran | 1.2 | Not Detected | 3.6 | Not Detected |
| Chloroform | 1.2 | Not Detected | 6.0 | Not Detected |
| 1,1,1-Trichloroethane | 1.2 | Not Detected | 6.7 | Not Detected |
| Cyclohexane | 1.2 | Not Detected | 4.2 | Not Detected |
| Carbon Tetrachloride | 1.2 | Not Detected | 7.8 | Not Detected |
| 2,2,4-Trimethylpentane | 1.2 | 2.4 | 5.8 | 11 |
| Benzene | 1.2 | 0.60 J | 3.9 | 1.9 J |
| 1,2-Dichloroethane | 1.2 | Not Detected | 5.0 | Not Detected |
| Heptane | 1.2 | Not Detected | 5.1 | Not Detected |
| Trichloroethene | 1.2 | Not Detected | 6.6 | Not Detected |
| 1,2-Dichloropropane | 1.2 | Not Detected | 5.7 | Not Detected |
| 1,4-Dioxane | 4.9 | Not Detected | 18 | Not Detected |
| Bromodichloromethane | 1.2 | Not Detected | 8.3 | Not Detected |
| cis-1,3-Dichloropropene | 1.2 | Not Detected | 5.6 | Not Detected |
| 4-Methyl-2-pentanone | 1.2 | Not Detected | 5.0 | Not Detected |
| Toluene | 1.2 | ~~0.17 J~~ | 4.6 | ~~0.63 J~~ |
| trans-1,3-Dichloropropene | 1.2 | Not Detected | 5.6 | Not Detected |
| 1,1,2-Trichloroethane | 1.2 | Not Detected | 6.7 | Not Detected |
| Tetrachloroethene | 1.2 | Not Detected | 8.4 | Not Detected |
| 2-Hexanone | 4.9 | Not Detected | 20 | Not Detected |

eurofins | Air Toxics

**Client Sample ID: VMP-23-5-012413**

**Lab ID#: 1301504A-08A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p020414** | **Date of Collection: 1/24/13 10:38:00 AM** | |
| **Dil. Factor:** | **2.47** | **Date of Analysis: 2/4/13 04:38 PM** | |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Dibromochloromethane | 1.2 | Not Detected | 10 | Not Detected |
| 1,2-Dibromoethane (EDB) | 1.2 | Not Detected | 9.5 | Not Detected |
| Chlorobenzene | 1.2 | Not Detected | 5.7 | Not Detected |
| Ethyl Benzene | 1.2 | Not Detected | 5.4 | Not Detected |
| m,p-Xylene | 1.2 | Not Detected | 5.4 | Not Detected |
| o-Xylene | 1.2 | Not Detected | 5.4 | Not Detected |
| Styrene | 1.2 | Not Detected | 5.3 | Not Detected |
| Bromoform | 1.2 | Not Detected | 13 | Not Detected |
| Cumene | 1.2 | Not Detected | 6.1 | Not Detected |
| 1,1,2,2-Tetrachloroethane | 1.2 | Not Detected | 8.5 | Not Detected |
| Propylbenzene | 1.2 | Not Detected | 6.1 | Not Detected |
| 4-Ethyltoluene | 1.2 | Not Detected | 6.1 | Not Detected |
| 1,3,5-Trimethylbenzene | 1.2 | Not Detected | 6.1 | Not Detected |
| 1,2,4-Trimethylbenzene | 1.2 | Not Detected | 6.1 | Not Detected |
| 1,3-Dichlorobenzene | 1.2 | Not Detected | 7.4 | Not Detected |
| 1,4-Dichlorobenzene | 1.2 | Not Detected | 7.4 | Not Detected |
| alpha-Chlorotoluene | 1.2 | Not Detected | 6.4 | Not Detected |
| 1,2-Dichlorobenzene | 1.2 | Not Detected | 7.4 | Not Detected |
| 1,2,4-Trichlorobenzene | 4.9 | ~~0.36 J~~ | 37 | ~~2.7 J~~ |
| Hexachlorobutadiene | 4.9 | Not Detected | 53 | Not Detected |
| Butane | 4.9 | 4.8 J | 12 | 11 J |
| Isopentane | 4.9 | 5.0 | 14 | 15 |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| Toluene-d8 | 98 | 70-130 |
| 1,2-Dichloroethane-d4 | 95 | 70-130 |
| 4-Bromofluorobenzene | 96 | 70-130 |

eurofins | Air Toxics

**Client Sample ID: VMP-23-10-012413**

**Lab ID#: 1301504A-09A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p020415** | **Date of Collection:** | **1/24/13 11:23:00 AM** |
| **Dil. Factor:** | **2.47** | **Date of Analysis:** | **2/4/13 05:19 PM** |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 1.2 | 0.51 J | 6.1 | 2.5 J |
| Freon 114 | 1.2 | Not Detected | 8.6 | Not Detected |
| Chloromethane | 12 | Not Detected | 26 | Not Detected |
| Vinyl Chloride | 1.2 | Not Detected | 3.2 | Not Detected |
| 1,3-Butadiene | 1.2 | Not Detected | 2.7 | Not Detected |
| Bromomethane | 12 | Not Detected | 48 | Not Detected |
| Chloroethane | 4.9 | Not Detected | 13 | Not Detected |
| Freon 11 | 1.2 | 0.22 J | 6.9 | 1.2 J |
| Ethanol | 4.9 | 1.5 J | 9.3 | 2.9 J |
| Freon 113 | 1.2 | Not Detected | 9.5 | Not Detected |
| 1,1-Dichloroethene | 1.2 | Not Detected | 4.9 | Not Detected |
| Acetone | 12 | 3.0 J | 29 | 7.2 J |
| 2-Propanol | 4.9 | 1.9 J | 12 | 4.7 J |
| Carbon Disulfide | 4.9 | ~~0.82 J~~ | 15 | ~~2.6 J~~ |
| 3-Chloropropene | 4.9 | Not Detected | 15 | Not Detected |
| Methylene Chloride | 12 | ~~0.51 J~~ | 43 | ~~1.8 J~~ |
| Methyl tert-butyl ether | 1.2 | Not Detected | 4.4 | Not Detected |
| trans-1,2-Dichloroethene | 1.2 | Not Detected | 4.9 | Not Detected |
| Hexane | 1.2 | 0.29 J | 4.4 | 1.0 J |
| 1,1-Dichloroethane | 1.2 | Not Detected | 5.0 | Not Detected |
| 2-Butanone (Methyl Ethyl Ketone) | 4.9 | Not Detected | 14 | Not Detected |
| cis-1,2-Dichloroethene | 1.2 | Not Detected | 4.9 | Not Detected |
| Tetrahydrofuran | 1.2 | Not Detected | 3.6 | Not Detected |
| Chloroform | 1.2 | 0.33 J | 6.0 | 1.6 J |
| 1,1,1-Trichloroethane | 1.2 | Not Detected | 6.7 | Not Detected |
| Cyclohexane | 1.2 | Not Detected | 4.2 | Not Detected |
| Carbon Tetrachloride | 1.2 | Not Detected | 7.8 | Not Detected |
| 2,2,4-Trimethylpentane | 1.2 | 1.1 J | 5.8 | 5.1 J |
| Benzene | 1.2 | Not Detected | 3.9 | Not Detected |
| 1,2-Dichloroethane | 1.2 | Not Detected | 5.0 | Not Detected |
| Heptane | 1.2 | Not Detected | 5.1 | Not Detected |
| Trichloroethene | 1.2 | Not Detected | 6.6 | Not Detected |
| 1,2-Dichloropropane | 1.2 | Not Detected | 5.7 | Not Detected |
| 1,4-Dioxane | 4.9 | Not Detected | 18 | Not Detected |
| Bromodichloromethane | 1.2 | Not Detected | 8.3 | Not Detected |
| cis-1,3-Dichloropropene | 1.2 | Not Detected | 5.6 | Not Detected |
| 4-Methyl-2-pentanone | 1.2 | Not Detected | 5.0 | Not Detected |
| Toluene | 1.2 | ~~0.28 J~~ | 4.6 | ~~1.0 J~~ |
| trans-1,3-Dichloropropene | 1.2 | Not Detected | 5.6 | Not Detected |
| 1,1,2-Trichloroethane | 1.2 | Not Detected | 6.7 | Not Detected |
| Tetrachloroethene | 1.2 | Not Detected | 8.4 | Not Detected |
| 2-Hexanone | 4.9 | Not Detected | 20 | Not Detected |

eurofins | Air Toxics

**Client Sample ID: VMP-23-10-012413**

**Lab ID#: 1301504A-09A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | p020415 | **Date of Collection:** | 1/24/13 11:23:00 AM |
| **Dil. Factor:** | 2.47 | **Date of Analysis:** | 2/4/13 05:19 PM |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Dibromochloromethane | 1.2 | Not Detected | 10 | Not Detected |
| 1,2-Dibromoethane (EDB) | 1.2 | Not Detected | 9.5 | Not Detected |
| Chlorobenzene | 1.2 | Not Detected | 5.7 | Not Detected |
| Ethyl Benzene | 1.2 | Not Detected | 5.4 | Not Detected |
| m,p-Xylene | 1.2 | Not Detected | 5.4 | Not Detected |
| o-Xylene | 1.2 | Not Detected | 5.4 | Not Detected |
| Styrene | 1.2 | Not Detected | 5.3 | Not Detected |
| Bromoform | 1.2 | Not Detected | 13 | Not Detected |
| Cumene | 1.2 | Not Detected | 6.1 | Not Detected |
| 1,1,2,2-Tetrachloroethane | 1.2 | Not Detected | 8.5 | Not Detected |
| Propylbenzene | 1.2 | Not Detected | 6.1 | Not Detected |
| 4-Ethyltoluene | 1.2 | Not Detected | 6.1 | Not Detected |
| 1,3,5-Trimethylbenzene | 1.2 | Not Detected | 6.1 | Not Detected |
| 1,2,4-Trimethylbenzene | 1.2 | Not Detected | 6.1 | Not Detected |
| 1,3-Dichlorobenzene | 1.2 | Not Detected | 7.4 | Not Detected |
| 1,4-Dichlorobenzene | 1.2 | Not Detected | 7.4 | Not Detected |
| alpha-Chlorotoluene | 1.2 | Not Detected | 6.4 | Not Detected |
| 1,2-Dichlorobenzene | 1.2 | Not Detected | 7.4 | Not Detected |
| 1,2,4-Trichlorobenzene | 4.9 | Not Detected | 37 | Not Detected |
| Hexachlorobutadiene | 4.9 | Not Detected | 53 | Not Detected |
| Butane | 4.9 | Not Detected | 12 | Not Detected |
| Isopentane | 4.9 | 0.66 J | 14 | 2.0 J |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| Toluene-d8 | 97 | 70-130 |
| 1,2-Dichloroethane-d4 | 92 | 70-130 |
| 4-Bromofluorobenzene | 94 | 70-130 |

eurofins | Air Toxics

**Client Sample ID: VMP-23-25-012413**

**Lab ID#: 1301504A-10A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p020416** | **Date of Collection:** | **1/24/13 12:15:00 PM** |
| **Dil. Factor:** | **2.52** | **Date of Analysis:** | **2/4/13 06:05 PM** |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 1.3 | 0.49 J | 6.2 | 2.4 J |
| Freon 114 | 1.3 | Not Detected | 8.8 | Not Detected |
| Chloromethane | 13 | Not Detected | 26 | Not Detected |
| Vinyl Chloride | 1.3 | Not Detected | 3.2 | Not Detected |
| 1,3-Butadiene | 1.3 | Not Detected | 2.8 | Not Detected |
| Bromomethane | 13 | Not Detected | 49 | Not Detected |
| Chloroethane | 5.0 | Not Detected | 13 | Not Detected |
| Freon 11 | 1.3 | 0.34 J | 7.1 | 1.9 J |
| Ethanol | 5.0 | 1.8 J | 9.5 | 3.3 J |
| Freon 113 | 1.3 | Not Detected | 9.6 | Not Detected |
| 1,1-Dichloroethene | 1.3 | Not Detected | 5.0 | Not Detected |
| Acetone | 13 | 3.1 J | 30 | 7.3 J |
| 2-Propanol | 5.0 | 0.76 J | 12 | 1.9 J |
| Carbon Disulfide | 5.0 | ~~0.68 J~~ | 16 | ~~2.1 J~~ |
| 3-Chloropropene | 5.0 | Not Detected | 16 | Not Detected |
| Methylene Chloride | 13 | ~~0.16 J~~ | 44 | ~~0.54 J~~ |
| Methyl tert-butyl ether | 1.3 | Not Detected | 4.5 | Not Detected |
| trans-1,2-Dichloroethene | 1.3 | Not Detected | 5.0 | Not Detected |
| Hexane | 1.3 | Not Detected | 4.4 | Not Detected |
| 1,1-Dichloroethane | 1.3 | Not Detected | 5.1 | Not Detected |
| 2-Butanone (Methyl Ethyl Ketone) | 5.0 | Not Detected | 15 | Not Detected |
| cis-1,2-Dichloroethene | 1.3 | Not Detected | 5.0 | Not Detected |
| Tetrahydrofuran | 1.3 | Not Detected | 3.7 | Not Detected |
| Chloroform | 1.3 | 3.6 | 6.2 | 17 |
| 1,1,1-Trichloroethane | 1.3 | Not Detected | 6.9 | Not Detected |
| Cyclohexane | 1.3 | Not Detected | 4.3 | Not Detected |
| Carbon Tetrachloride | 1.3 | Not Detected | 7.9 | Not Detected |
| 2,2,4-Trimethylpentane | 1.3 | 0.30 J | 5.9 | 1.4 J |
| Benzene | 1.3 | Not Detected | 4.0 | Not Detected |
| 1,2-Dichloroethane | 1.3 | Not Detected | 5.1 | Not Detected |
| Heptane | 1.3 | Not Detected | 5.2 | Not Detected |
| Trichloroethene | 1.3 | Not Detected | 6.8 | Not Detected |
| 1,2-Dichloropropane | 1.3 | Not Detected | 5.8 | Not Detected |
| 1,4-Dioxane | 5.0 | Not Detected | 18 | Not Detected |
| Bromodichloromethane | 1.3 | Not Detected | 8.4 | Not Detected |
| cis-1,3-Dichloropropene | 1.3 | Not Detected | 5.7 | Not Detected |
| 4-Methyl-2-pentanone | 1.3 | Not Detected | 5.2 | Not Detected |
| Toluene | 1.3 | ~~0.11 J~~ | 4.7 | ~~0.42 J~~ |
| trans-1,3-Dichloropropene | 1.3 | Not Detected | 5.7 | Not Detected |
| 1,1,2-Trichloroethane | 1.3 | Not Detected | 6.9 | Not Detected |
| Tetrachloroethene | 1.3 | ~~0.28 J~~ | 8.5 | ~~1.9 J~~ |
| 2-Hexanone | 5.0 | Not Detected | 21 | Not Detected |

eurofins | Air Toxics

**Client Sample ID: VMP-23-25-012413**

**Lab ID#: 1301504A-10A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p020416** | **Date of Collection: 1/24/13 12:15:00 PM** | |
| **Dil. Factor:** | **2.52** | **Date of Analysis: 2/4/13 06:05 PM** | |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Dibromochloromethane | 1.3 | Not Detected | 11 | Not Detected |
| 1,2-Dibromoethane (EDB) | 1.3 | Not Detected | 9.7 | Not Detected |
| Chlorobenzene | 1.3 | Not Detected | 5.8 | Not Detected |
| Ethyl Benzene | 1.3 | Not Detected | 5.5 | Not Detected |
| m,p-Xylene | 1.3 | Not Detected | 5.5 | Not Detected |
| o-Xylene | 1.3 | Not Detected | 5.5 | Not Detected |
| Styrene | 1.3 | Not Detected | 5.4 | Not Detected |
| Bromoform | 1.3 | Not Detected | 13 | Not Detected |
| Cumene | 1.3 | Not Detected | 6.2 | Not Detected |
| 1,1,2,2-Tetrachloroethane | 1.3 | Not Detected | 8.6 | Not Detected |
| Propylbenzene | 1.3 | Not Detected | 6.2 | Not Detected |
| 4-Ethyltoluene | 1.3 | Not Detected | 6.2 | Not Detected |
| 1,3,5-Trimethylbenzene | 1.3 | Not Detected | 6.2 | Not Detected |
| 1,2,4-Trimethylbenzene | 1.3 | Not Detected | 6.2 | Not Detected |
| 1,3-Dichlorobenzene | 1.3 | Not Detected | 7.6 | Not Detected |
| 1,4-Dichlorobenzene | 1.3 | Not Detected | 7.6 | Not Detected |
| alpha-Chlorotoluene | 1.3 | Not Detected | 6.5 | Not Detected |
| 1,2-Dichlorobenzene | 1.3 | Not Detected | 7.6 | Not Detected |
| 1,2,4-Trichlorobenzene | 5.0 | Not Detected | 37 | Not Detected |
| Hexachlorobutadiene | 5.0 | Not Detected | 54 | Not Detected |
| Butane | 5.0 | 2.5 J | 12 | 5.9 J |
| Isopentane | 5.0 | 2.6 J | 15 | 7.6 J |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| Toluene-d8 | 97 | 70-130 |
| 1,2-Dichloroethane-d4 | 94 | 70-130 |
| 4-Bromofluorobenzene | 94 | 70-130 |

eurofins | Air Toxics

**Client Sample ID: VMP-23-40-012413**

**Lab ID#: 1301504A-11A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | p020417 | **Date of Collection:** | 1/24/13 1:15:00 PM |
| **Dil. Factor:** | 2.58 | **Date of Analysis:** | 2/4/13 06:36 PM |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 1.3 | 0.52 J | 6.4 | 2.6 J |
| Freon 114 | 1.3 | Not Detected | 9.0 | Not Detected |
| Chloromethane | 13 | Not Detected | 27 | Not Detected |
| Vinyl Chloride | 1.3 | Not Detected | 3.3 | Not Detected |
| 1,3-Butadiene | 1.3 | Not Detected | 2.8 | Not Detected |
| Bromomethane | 13 | Not Detected | 50 | Not Detected |
| Chloroethane | 5.2 | Not Detected | 14 | Not Detected |
| Freon 11 | 1.3 | 0.47 J | 7.2 | 2.7 J |
| Ethanol | 5.2 | 0.70 J | 9.7 | 1.3 J |
| Freon 113 | 1.3 | Not Detected | 9.9 | Not Detected |
| 1,1-Dichloroethene | 1.3 | Not Detected | 5.1 | Not Detected |
| Acetone | 13 | 5.3 J | 31 | 12 J |
| 2-Propanol | 5.2 | 0.87 J | 13 | 2.1 J |
| Carbon Disulfide | 5.2 | ~~0.76 J~~ | 16 | ~~2.4 J~~ |
| 3-Chloropropene | 5.2 | Not Detected | 16 | Not Detected |
| Methylene Chloride | 13 | Not Detected | 45 | Not Detected |
| Methyl tert-butyl ether | 1.3 | Not Detected | 4.6 | Not Detected |
| trans-1,2-Dichloroethene | 1.3 | Not Detected | 5.1 | Not Detected |
| Hexane | 1.3 | 0.34 J | 4.5 | 1.2 J |
| 1,1-Dichloroethane | 1.3 | Not Detected | 5.2 | Not Detected |
| 2-Butanone (Methyl Ethyl Ketone) | 5.2 | 0.82 J | 15 | 2.4 J |
| cis-1,2-Dichloroethene | 1.3 | Not Detected | 5.1 | Not Detected |
| Tetrahydrofuran | 1.3 | Not Detected | 3.8 | Not Detected |
| Chloroform | 1.3 | 1.4 | 6.3 | 6.9 |
| 1,1,1-Trichloroethane | 1.3 | Not Detected | 7.0 | Not Detected |
| Cyclohexane | 1.3 | Not Detected | 4.4 | Not Detected |
| Carbon Tetrachloride | 1.3 | Not Detected | 8.1 | Not Detected |
| 2,2,4-Trimethylpentane | 1.3 | 1.8 | 6.0 | 8.2 |
| Benzene | 1.3 | Not Detected | 4.1 | Not Detected |
| 1,2-Dichloroethane | 1.3 | Not Detected | 5.2 | Not Detected |
| Heptane | 1.3 | Not Detected | 5.3 | Not Detected |
| Trichloroethene | 1.3 | Not Detected | 6.9 | Not Detected |
| 1,2-Dichloropropane | 1.3 | Not Detected | 6.0 | Not Detected |
| 1,4-Dioxane | 5.2 | Not Detected | 18 | Not Detected |
| Bromodichloromethane | 1.3 | Not Detected | 8.6 | Not Detected |
| cis-1,3-Dichloropropene | 1.3 | Not Detected | 5.8 | Not Detected |
| 4-Methyl-2-pentanone | 1.3 | Not Detected | 5.3 | Not Detected |
| Toluene | 1.3 | Not Detected | 4.9 | Not Detected |
| trans-1,3-Dichloropropene | 1.3 | Not Detected | 5.8 | Not Detected |
| 1,1,2-Trichloroethane | 1.3 | Not Detected | 7.0 | Not Detected |
| Tetrachloroethene | 1.3 | Not Detected | 8.8 | Not Detected |
| 2-Hexanone | 5.2 | Not Detected | 21 | Not Detected |

eurofins | Air Toxics

**Client Sample ID: VMP-23-40-012413**

**Lab ID#: 1301504A-11A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p020417** | **Date of Collection:** | **1/24/13 1:15:00 PM** |
| **Dil. Factor:** | **2.58** | **Date of Analysis:** | **2/4/13 06:36 PM** |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Dibromochloromethane | 1.3 | Not Detected | 11 | Not Detected |
| 1,2-Dibromoethane (EDB) | 1.3 | Not Detected | 9.9 | Not Detected |
| Chlorobenzene | 1.3 | Not Detected | 5.9 | Not Detected |
| Ethyl Benzene | 1.3 | Not Detected | 5.6 | Not Detected |
| m,p-Xylene | 1.3 | Not Detected | 5.6 | Not Detected |
| o-Xylene | 1.3 | Not Detected | 5.6 | Not Detected |
| Styrene | 1.3 | Not Detected | 5.5 | Not Detected |
| Bromoform | 1.3 | Not Detected | 13 | Not Detected |
| Cumene | 1.3 | Not Detected | 6.3 | Not Detected |
| 1,1,2,2-Tetrachloroethane | 1.3 | Not Detected | 8.8 | Not Detected |
| Propylbenzene | 1.3 | Not Detected | 6.3 | Not Detected |
| 4-Ethyltoluene | 1.3 | Not Detected | 6.3 | Not Detected |
| 1,3,5-Trimethylbenzene | 1.3 | Not Detected | 6.3 | Not Detected |
| 1,2,4-Trimethylbenzene | 1.3 | Not Detected | 6.3 | Not Detected |
| 1,3-Dichlorobenzene | 1.3 | Not Detected | 7.8 | Not Detected |
| 1,4-Dichlorobenzene | 1.3 | Not Detected | 7.8 | Not Detected |
| alpha-Chlorotoluene | 1.3 | Not Detected | 6.7 | Not Detected |
| 1,2-Dichlorobenzene | 1.3 | Not Detected | 7.8 | Not Detected |
| 1,2,4-Trichlorobenzene | 5.2 | Not Detected | 38 | Not Detected |
| Hexachlorobutadiene | 5.2 | Not Detected | 55 | Not Detected |
| Butane | 5.2 | 1.9 J | 12 | 4.5 J |
| Isopentane | 5.2 | 3.4 J | 15 | 10 J |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| Toluene-d8 | 98 | 70-130 |
| 1,2-Dichloroethane-d4 | 96 | 70-130 |
| 4-Bromofluorobenzene | 94 | 70-130 |

eurofins | Air Toxics

**Client Sample ID: VMP-24-5-012313**

**Lab ID#: 1301504A-12A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | p020418 | **Date of Collection:** | 1/23/13 11:49:00 AM |
| **Dil. Factor:** | 2.52 | **Date of Analysis:** | 2/4/13 07:13 PM |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 1.3 | 0.49 J | 6.2 | 2.4 J |
| Freon 114 | 1.3 | Not Detected | 8.8 | Not Detected |
| Chloromethane | 13 | Not Detected | 26 | Not Detected |
| Vinyl Chloride | 1.3 | Not Detected | 3.2 | Not Detected |
| 1,3-Butadiene | 1.3 | Not Detected | 2.8 | Not Detected |
| Bromomethane | 13 | Not Detected | 49 | Not Detected |
| Chloroethane | 5.0 | Not Detected | 13 | Not Detected |
| Freon 11 | 1.3 | 0.25 J | 7.1 | 1.4 J |
| Ethanol | 5.0 | 2.6 J | 9.5 | 4.8 J |
| Freon 113 | 1.3 | Not Detected | 9.6 | Not Detected |
| 1,1-Dichloroethene | 1.3 | Not Detected | 5.0 | Not Detected |
| Acetone | 13 | 10 J | 30 | 25 J |
| 2-Propanol | 5.0 | 15 | 12 | 36 |
| Carbon Disulfide | 5.0 | ~~0.69 J~~ | 16 | ~~2.2 J~~ |
| 3-Chloropropene | 5.0 | Not Detected | 16 | Not Detected |
| Methylene Chloride | 13 | Not Detected | 44 | Not Detected |
| Methyl tert-butyl ether | 1.3 | Not Detected | 4.5 | Not Detected |
| trans-1,2-Dichloroethene | 1.3 | Not Detected | 5.0 | Not Detected |
| Hexane | 1.3 | Not Detected | 4.4 | Not Detected |
| 1,1-Dichloroethane | 1.3 | Not Detected | 5.1 | Not Detected |
| 2-Butanone (Methyl Ethyl Ketone) | 5.0 | Not Detected | 15 | Not Detected |
| cis-1,2-Dichloroethene | 1.3 | Not Detected | 5.0 | Not Detected |
| Tetrahydrofuran | 1.3 | Not Detected | 3.7 | Not Detected |
| Chloroform | 1.3 | Not Detected | 6.2 | Not Detected |
| 1,1,1-Trichloroethane | 1.3 | Not Detected | 6.9 | Not Detected |
| Cyclohexane | 1.3 | Not Detected | 4.3 | Not Detected |
| Carbon Tetrachloride | 1.3 | Not Detected | 7.9 | Not Detected |
| 2,2,4-Trimethylpentane | 1.3 | 4.0 | 5.9 | 19 |
| Benzene | 1.3 | 2.7 | 4.0 | 8.8 |
| 1,2-Dichloroethane | 1.3 | Not Detected | 5.1 | Not Detected |
| Heptane | 1.3 | Not Detected | 5.2 | Not Detected |
| Trichloroethene | 1.3 | Not Detected | 6.8 | Not Detected |
| 1,2-Dichloropropane | 1.3 | Not Detected | 5.8 | Not Detected |
| 1,4-Dioxane | 5.0 | Not Detected | 18 | Not Detected |
| Bromodichloromethane | 1.3 | Not Detected | 8.4 | Not Detected |
| cis-1,3-Dichloropropene | 1.3 | Not Detected | 5.7 | Not Detected |
| 4-Methyl-2-pentanone | 1.3 | Not Detected | 5.2 | Not Detected |
| Toluene | 1.3 | ~~0.14 J~~ | 4.7 | ~~0.53 J~~ |
| trans-1,3-Dichloropropene | 1.3 | Not Detected | 5.7 | Not Detected |
| 1,1,2-Trichloroethane | 1.3 | Not Detected | 6.9 | Not Detected |
| Tetrachloroethene | 1.3 | Not Detected | 8.5 | Not Detected |
| 2-Hexanone | 5.0 | Not Detected | 21 | Not Detected |

eurofins | Air Toxics

**Client Sample ID: VMP-24-5-012313**

**Lab ID#: 1301504A-12A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p020418** | **Date of Collection: 1/23/13 11:49:00 AM** | |
| **Dil. Factor:** | **2.52** | **Date of Analysis: 2/4/13 07:13 PM** | |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Dibromochloromethane | 1.3 | Not Detected | 11 | Not Detected |
| 1,2-Dibromoethane (EDB) | 1.3 | Not Detected | 9.7 | Not Detected |
| Chlorobenzene | 1.3 | Not Detected | 5.8 | Not Detected |
| Ethyl Benzene | 1.3 | Not Detected | 5.5 | Not Detected |
| m,p-Xylene | 1.3 | Not Detected | 5.5 | Not Detected |
| o-Xylene | 1.3 | Not Detected | 5.5 | Not Detected |
| Styrene | 1.3 | Not Detected | 5.4 | Not Detected |
| Bromoform | 1.3 | Not Detected | 13 | Not Detected |
| Cumene | 1.3 | Not Detected | 6.2 | Not Detected |
| 1,1,2,2-Tetrachloroethane | 1.3 | Not Detected | 8.6 | Not Detected |
| Propylbenzene | 1.3 | Not Detected | 6.2 | Not Detected |
| 4-Ethyltoluene | 1.3 | Not Detected | 6.2 | Not Detected |
| 1,3,5-Trimethylbenzene | 1.3 | Not Detected | 6.2 | Not Detected |
| 1,2,4-Trimethylbenzene | 1.3 | Not Detected | 6.2 | Not Detected |
| 1,3-Dichlorobenzene | 1.3 | Not Detected | 7.6 | Not Detected |
| 1,4-Dichlorobenzene | 1.3 | Not Detected | 7.6 | Not Detected |
| alpha-Chlorotoluene | 1.3 | Not Detected | 6.5 | Not Detected |
| 1,2-Dichlorobenzene | 1.3 | Not Detected | 7.6 | Not Detected |
| 1,2,4-Trichlorobenzene | 5.0 | Not Detected | 37 | Not Detected |
| Hexachlorobutadiene | 5.0 | Not Detected | 54 | Not Detected |
| Butane | 5.0 | Not Detected | 12 | Not Detected |
| Isopentane | 5.0 | Not Detected | 15 | Not Detected |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| Toluene-d8 | 102 | 70-130 |
| 1,2-Dichloroethane-d4 | 95 | 70-130 |
| 4-Bromofluorobenzene | 98 | 70-130 |

eurofins | Air Toxics

**Client Sample ID: VMP-24-10-012313**

**Lab ID#: 1301504A-13A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p020419** | **Date of Collection:** | **1/23/13 1:23:00 PM** |
| **Dil. Factor:** | **2.76** | **Date of Analysis:** | **2/4/13 08:11 PM** |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 1.4 | 0.51 J | 6.8 | 2.5 J |
| Freon 114 | 1.4 | Not Detected | 9.6 | Not Detected |
| Chloromethane | 14 | Not Detected | 28 | Not Detected |
| Vinyl Chloride | 1.4 | Not Detected | 3.5 | Not Detected |
| 1,3-Butadiene | 1.4 | Not Detected | 3.0 | Not Detected |
| Bromomethane | 14 | Not Detected | 54 | Not Detected |
| Chloroethane | 5.5 | Not Detected | 14 | Not Detected |
| Freon 11 | 1.4 | 0.31 J | 7.8 | 1.8 J |
| Ethanol | 5.5 | 4.0 J | 10 | 7.6 J |
| Freon 113 | 1.4 | Not Detected | 10 | Not Detected |
| 1,1-Dichloroethene | 1.4 | Not Detected | 5.5 | Not Detected |
| Acetone | 14 | ~~1.8 J~~ | 33 | ~~4.4 J~~ |
| 2-Propanol | 5.5 | 6.7 | 14 | 16 |
| Carbon Disulfide | 5.5 | ~~0.65 J~~ | 17 | ~~2.0 J~~ |
| 3-Chloropropene | 5.5 | Not Detected | 17 | Not Detected |
| Methylene Chloride | 14 | 0.48 J | 48 | 1.6 J |
| Methyl tert-butyl ether | 1.4 | Not Detected | 5.0 | Not Detected |
| trans-1,2-Dichloroethene | 1.4 | Not Detected | 5.5 | Not Detected |
| Hexane | 1.4 | Not Detected | 4.9 | Not Detected |
| 1,1-Dichloroethane | 1.4 | Not Detected | 5.6 | Not Detected |
| 2-Butanone (Methyl Ethyl Ketone) | 5.5 | Not Detected | 16 | Not Detected |
| cis-1,2-Dichloroethene | 1.4 | Not Detected | 5.5 | Not Detected |
| Tetrahydrofuran | 1.4 | Not Detected | 4.1 | Not Detected |
| Chloroform | 1.4 | Not Detected | 6.7 | Not Detected |
| 1,1,1-Trichloroethane | 1.4 | Not Detected | 7.5 | Not Detected |
| Cyclohexane | 1.4 | Not Detected | 4.8 | Not Detected |
| Carbon Tetrachloride | 1.4 | Not Detected | 8.7 | Not Detected |
| 2,2,4-Trimethylpentane | 1.4 | 2.2 | 6.4 | 10 |
| Benzene | 1.4 | 2.2 | 4.4 | 7.2 |
| 1,2-Dichloroethane | 1.4 | Not Detected | 5.6 | Not Detected |
| Heptane | 1.4 | Not Detected | 5.6 | Not Detected |
| Trichloroethene | 1.4 | Not Detected | 7.4 | Not Detected |
| 1,2-Dichloropropane | 1.4 | Not Detected | 6.4 | Not Detected |
| 1,4-Dioxane | 5.5 | Not Detected | 20 | Not Detected |
| Bromodichloromethane | 1.4 | Not Detected | 9.2 | Not Detected |
| cis-1,3-Dichloropropene | 1.4 | Not Detected | 6.3 | Not Detected |
| 4-Methyl-2-pentanone | 1.4 | Not Detected | 5.6 | Not Detected |
| Toluene | 1.4 | 0.34 J | 5.2 | 1.3 J |
| trans-1,3-Dichloropropene | 1.4 | Not Detected | 6.3 | Not Detected |
| 1,1,2-Trichloroethane | 1.4 | Not Detected | 7.5 | Not Detected |
| Tetrachloroethene | 1.4 | ~~0.18 J~~ | 9.4 | ~~1.2 J~~ |
| 2-Hexanone | 5.5 | Not Detected | 23 | Not Detected |

eurofins | Air Toxics

**Client Sample ID: VMP-24-10-012313**

**Lab ID#: 1301504A-13A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p020419** | **Date of Collection: 1/23/13 1:23:00 PM** | |
| **Dil. Factor:** | **2.76** | **Date of Analysis: 2/4/13 08:11 PM** | |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Dibromochloromethane | 1.4 | Not Detected | 12 | Not Detected |
| 1,2-Dibromoethane (EDB) | 1.4 | Not Detected | 11 | Not Detected |
| Chlorobenzene | 1.4 | Not Detected | 6.4 | Not Detected |
| Ethyl Benzene | 1.4 | Not Detected | 6.0 | Not Detected |
| m,p-Xylene | 1.4 | Not Detected | 6.0 | Not Detected |
| o-Xylene | 1.4 | Not Detected | 6.0 | Not Detected |
| Styrene | 1.4 | Not Detected | 5.9 | Not Detected |
| Bromoform | 1.4 | Not Detected | 14 | Not Detected |
| Cumene | 1.4 | Not Detected | 6.8 | Not Detected |
| 1,1,2,2-Tetrachloroethane | 1.4 | Not Detected | 9.5 | Not Detected |
| Propylbenzene | 1.4 | Not Detected | 6.8 | Not Detected |
| 4-Ethyltoluene | 1.4 | Not Detected | 6.8 | Not Detected |
| 1,3,5-Trimethylbenzene | 1.4 | Not Detected | 6.8 | Not Detected |
| 1,2,4-Trimethylbenzene | 1.4 | Not Detected | 6.8 | Not Detected |
| 1,3-Dichlorobenzene | 1.4 | Not Detected | 8.3 | Not Detected |
| 1,4-Dichlorobenzene | 1.4 | Not Detected | 8.3 | Not Detected |
| alpha-Chlorotoluene | 1.4 | Not Detected | 7.1 | Not Detected |
| 1,2-Dichlorobenzene | 1.4 | Not Detected | 8.3 | Not Detected |
| 1,2,4-Trichlorobenzene | 5.5 | Not Detected | 41 | Not Detected |
| Hexachlorobutadiene | 5.5 | Not Detected | 59 | Not Detected |
| Butane | 5.5 | Not Detected | 13 | Not Detected |
| Isopentane | 5.5 | 1.2 J | 16 | 3.4 J |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| Toluene-d8 | 99 | 70-130 |
| 1,2-Dichloroethane-d4 | 97 | 70-130 |
| 4-Bromofluorobenzene | 97 | 70-130 |

eurofins | Air Toxics

**Client Sample ID: VMP-24-22-012313**

**Lab ID#: 1301504A-14A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | p020420 | **Date of Collection:** | 1/23/13 2:04:00 PM |
| **Dil. Factor:** | 2.82 | **Date of Analysis:** | 2/4/13 08:46 PM |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 1.4 | 0.59 J | 7.0 | 2.9 J |
| Freon 114 | 1.4 | Not Detected | 9.8 | Not Detected |
| Chloromethane | 14 | Not Detected | 29 | Not Detected |
| Vinyl Chloride | 1.4 | Not Detected | 3.6 | Not Detected |
| 1,3-Butadiene | 1.4 | Not Detected | 3.1 | Not Detected |
| Bromomethane | 14 | Not Detected | 55 | Not Detected |
| Chloroethane | 5.6 | Not Detected | 15 | Not Detected |
| Freon 11 | 1.4 | 0.30 J | 7.9 | 1.7 J |
| Ethanol | 5.6 | 2.0 J | 11 | 3.9 J |
| Freon 113 | 1.4 | Not Detected | 11 | Not Detected |
| 1,1-Dichloroethene | 1.4 | Not Detected | 5.6 | Not Detected |
| Acetone | 14 | 2.9 J | 33 | 6.9 J |
| 2-Propanol | 5.6 | 4.0 J | 14 | 9.8 J |
| Carbon Disulfide | 5.6 | ~~0.65 J~~ | 18 | ~~2.0 J~~ |
| 3-Chloropropene | 5.6 | Not Detected | 18 | Not Detected |
| Methylene Chloride | 14 | ~~0.27 J~~ | 49 | ~~0.94 J~~ |
| Methyl tert-butyl ether | 1.4 | Not Detected | 5.1 | Not Detected |
| trans-1,2-Dichloroethene | 1.4 | Not Detected | 5.6 | Not Detected |
| Hexane | 1.4 | Not Detected | 5.0 | Not Detected |
| 1,1-Dichloroethane | 1.4 | Not Detected | 5.7 | Not Detected |
| 2-Butanone (Methyl Ethyl Ketone) | 5.6 | Not Detected | 17 | Not Detected |
| cis-1,2-Dichloroethene | 1.4 | Not Detected | 5.6 | Not Detected |
| Tetrahydrofuran | 1.4 | Not Detected | 4.2 | Not Detected |
| Chloroform | 1.4 | Not Detected | 6.9 | Not Detected |
| 1,1,1-Trichloroethane | 1.4 | Not Detected | 7.7 | Not Detected |
| Cyclohexane | 1.4 | Not Detected | 4.8 | Not Detected |
| Carbon Tetrachloride | 1.4 | Not Detected | 8.9 | Not Detected |
| 2,2,4-Trimethylpentane | 1.4 | 2.3 | 6.6 | 10 |
| Benzene | 1.4 | Not Detected | 4.5 | Not Detected |
| 1,2-Dichloroethane | 1.4 | Not Detected | 5.7 | Not Detected |
| Heptane | 1.4 | Not Detected | 5.8 | Not Detected |
| Trichloroethene | 1.4 | Not Detected | 7.6 | Not Detected |
| 1,2-Dichloropropane | 1.4 | Not Detected | 6.5 | Not Detected |
| 1,4-Dioxane | 5.6 | Not Detected | 20 | Not Detected |
| Bromodichloromethane | 1.4 | Not Detected | 9.4 | Not Detected |
| cis-1,3-Dichloropropene | 1.4 | Not Detected | 6.4 | Not Detected |
| 4-Methyl-2-pentanone | 1.4 | Not Detected | 5.8 | Not Detected |
| Toluene | 1.4 | ~~0.14 J~~ | 5.3 | ~~0.51 J~~ |
| trans-1,3-Dichloropropene | 1.4 | Not Detected | 6.4 | Not Detected |
| 1,1,2-Trichloroethane | 1.4 | Not Detected | 7.7 | Not Detected |
| Tetrachloroethene | 1.4 | ~~0.21 J~~ | 9.6 | ~~1.4 J~~ |
| 2-Hexanone | 5.6 | Not Detected | 23 | Not Detected |

eurofins | Air Toxics

**Client Sample ID: VMP-24-22-012313**

**Lab ID#: 1301504A-14A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p020420** | **Date of Collection: 1/23/13 2:04:00 PM** | |
| **Dil. Factor:** | **2.82** | **Date of Analysis: 2/4/13 08:46 PM** | |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Dibromochloromethane | 1.4 | Not Detected | 12 | Not Detected |
| 1,2-Dibromoethane (EDB) | 1.4 | Not Detected | 11 | Not Detected |
| Chlorobenzene | 1.4 | Not Detected | 6.5 | Not Detected |
| Ethyl Benzene | 1.4 | Not Detected | 6.1 | Not Detected |
| m,p-Xylene | 1.4 | Not Detected | 6.1 | Not Detected |
| o-Xylene | 1.4 | Not Detected | 6.1 | Not Detected |
| Styrene | 1.4 | Not Detected | 6.0 | Not Detected |
| Bromoform | 1.4 | Not Detected | 14 | Not Detected |
| Cumene | 1.4 | Not Detected | 6.9 | Not Detected |
| 1,1,2,2-Tetrachloroethane | 1.4 | Not Detected | 9.7 | Not Detected |
| Propylbenzene | 1.4 | Not Detected | 6.9 | Not Detected |
| 4-Ethyltoluene | 1.4 | Not Detected | 6.9 | Not Detected |
| 1,3,5-Trimethylbenzene | 1.4 | Not Detected | 6.9 | Not Detected |
| 1,2,4-Trimethylbenzene | 1.4 | Not Detected | 6.9 | Not Detected |
| 1,3-Dichlorobenzene | 1.4 | Not Detected | 8.5 | Not Detected |
| 1,4-Dichlorobenzene | 1.4 | Not Detected | 8.5 | Not Detected |
| alpha-Chlorotoluene | 1.4 | Not Detected | 7.3 | Not Detected |
| 1,2-Dichlorobenzene | 1.4 | Not Detected | 8.5 | Not Detected |
| 1,2,4-Trichlorobenzene | 5.6 | Not Detected | 42 | Not Detected |
| Hexachlorobutadiene | 5.6 | Not Detected | 60 | Not Detected |
| Butane | 5.6 | 9.4 | 13 | 22 |
| Isopentane | 5.6 | 3.7 J | 17 | 11 J |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| Toluene-d8 | 97 | 70-130 |
| 1,2-Dichloroethane-d4 | 95 | 70-130 |
| 4-Bromofluorobenzene | 96 | 70-130 |

eurofins | Air Toxics

**Client Sample ID: VMP-24-34-012313**

**Lab ID#: 1301504A-15A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | p020421 | **Date of Collection:** | 1/23/13 3:02:00 PM |
| **Dil. Factor:** | 2.89 | **Date of Analysis:** | 2/4/13 09:05 PM |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 1.4 | 0.55 J | 7.1 | 2.7 J |
| Freon 114 | 1.4 | Not Detected | 10 | Not Detected |
| Chloromethane | 14 | Not Detected | 30 | Not Detected |
| Vinyl Chloride | 1.4 | Not Detected | 3.7 | Not Detected |
| 1,3-Butadiene | 1.4 | Not Detected | 3.2 | Not Detected |
| Bromomethane | 14 | Not Detected | 56 | Not Detected |
| Chloroethane | 5.8 | Not Detected | 15 | Not Detected |
| Freon 11 | 1.4 | 0.33 J | 8.1 | 1.8 J |
| Ethanol | 5.8 | 1.2 J | 11 | 2.2 J |
| Freon 113 | 1.4 | Not Detected | 11 | Not Detected |
| 1,1-Dichloroethene | 1.4 | Not Detected | 5.7 | Not Detected |
| Acetone | 14 | 3.8 J | 34 | 9.0 J |
| 2-Propanol | 5.8 | 1.3 J | 14 | 3.2 J |
| Carbon Disulfide | 5.8 | ~~0.58 J~~ | 18 | ~~1.8 J~~ |
| 3-Chloropropene | 5.8 | Not Detected | 18 | Not Detected |
| Methylene Chloride | 14 | ~~0.30 J~~ | 50 | ~~1.0 J~~ |
| Methyl tert-butyl ether | 1.4 | Not Detected | 5.2 | Not Detected |
| trans-1,2-Dichloroethene | 1.4 | Not Detected | 5.7 | Not Detected |
| Hexane | 1.4 | Not Detected | 5.1 | Not Detected |
| 1,1-Dichloroethane | 1.4 | Not Detected | 5.8 | Not Detected |
| 2-Butanone (Methyl Ethyl Ketone) | 5.8 | Not Detected | 17 | Not Detected |
| cis-1,2-Dichloroethene | 1.4 | Not Detected | 5.7 | Not Detected |
| Tetrahydrofuran | 1.4 | Not Detected | 4.3 | Not Detected |
| Chloroform | 1.4 | Not Detected | 7.0 | Not Detected |
| 1,1,1-Trichloroethane | 1.4 | Not Detected | 7.9 | Not Detected |
| Cyclohexane | 1.4 | Not Detected | 5.0 | Not Detected |
| Carbon Tetrachloride | 1.4 | Not Detected | 9.1 | Not Detected |
| 2,2,4-Trimethylpentane | 1.4 | 1.7 | 6.8 | 8.1 |
| Benzene | 1.4 | 2.1 | 4.6 | 6.8 |
| 1,2-Dichloroethane | 1.4 | Not Detected | 5.8 | Not Detected |
| Heptane | 1.4 | Not Detected | 5.9 | Not Detected |
| Trichloroethene | 1.4 | Not Detected | 7.8 | Not Detected |
| 1,2-Dichloropropane | 1.4 | Not Detected | 6.7 | Not Detected |
| 1,4-Dioxane | 5.8 | Not Detected | 21 | Not Detected |
| Bromodichloromethane | 1.4 | Not Detected | 9.7 | Not Detected |
| cis-1,3-Dichloropropene | 1.4 | Not Detected | 6.6 | Not Detected |
| 4-Methyl-2-pentanone | 1.4 | Not Detected | 5.9 | Not Detected |
| Toluene | 1.4 | ~~0.12 J~~ | 5.4 | ~~0.45 J~~ |
| trans-1,3-Dichloropropene | 1.4 | Not Detected | 6.6 | Not Detected |
| 1,1,2-Trichloroethane | 1.4 | Not Detected | 7.9 | Not Detected |
| Tetrachloroethene | 1.4 | ~~0.17 J~~ | 9.8 | ~~1.2 J~~ |
| 2-Hexanone | 5.8 | Not Detected | 24 | Not Detected |

eurofins | Air Toxics

**Client Sample ID: VMP-24-34-012313**

**Lab ID#: 1301504A-15A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p020421** | **Date of Collection: 1/23/13 3:02:00 PM** | |
| **Dil. Factor:** | **2.89** | **Date of Analysis: 2/4/13 09:05 PM** | |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Dibromochloromethane | 1.4 | Not Detected | 12 | Not Detected |
| 1,2-Dibromoethane (EDB) | 1.4 | Not Detected | 11 | Not Detected |
| Chlorobenzene | 1.4 | Not Detected | 6.6 | Not Detected |
| Ethyl Benzene | 1.4 | Not Detected | 6.3 | Not Detected |
| m,p-Xylene | 1.4 | Not Detected | 6.3 | Not Detected |
| o-Xylene | 1.4 | Not Detected | 6.3 | Not Detected |
| Styrene | 1.4 | Not Detected | 6.2 | Not Detected |
| Bromoform | 1.4 | Not Detected | 15 | Not Detected |
| Cumene | 1.4 | Not Detected | 7.1 | Not Detected |
| 1,1,2,2-Tetrachloroethane | 1.4 | Not Detected | 9.9 | Not Detected |
| Propylbenzene | 1.4 | Not Detected | 7.1 | Not Detected |
| 4-Ethyltoluene | 1.4 | Not Detected | 7.1 | Not Detected |
| 1,3,5-Trimethylbenzene | 1.4 | Not Detected | 7.1 | Not Detected |
| 1,2,4-Trimethylbenzene | 1.4 | Not Detected | 7.1 | Not Detected |
| 1,3-Dichlorobenzene | 1.4 | Not Detected | 8.7 | Not Detected |
| 1,4-Dichlorobenzene | 1.4 | Not Detected | 8.7 | Not Detected |
| alpha-Chlorotoluene | 1.4 | Not Detected | 7.5 | Not Detected |
| 1,2-Dichlorobenzene | 1.4 | Not Detected | 8.7 | Not Detected |
| 1,2,4-Trichlorobenzene | 5.8 | Not Detected | 43 | Not Detected |
| Hexachlorobutadiene | 5.8 | Not Detected | 62 | Not Detected |
| Butane | 5.8 | Not Detected | 14 | Not Detected |
| Isopentane | 5.8 | Not Detected | 17 | Not Detected |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| Toluene-d8 | 97 | 70-130 |
| 1,2-Dichloroethane-d4 | 95 | 70-130 |
| 4-Bromofluorobenzene | 96 | 70-130 |

eurofins | Air Toxics

**Client Sample ID: VMP-43-20-012413**

**Lab ID#: 1301504A-16A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p020422** | **Date of Collection:** | **1/24/13 3:23:00 PM** |
| **Dil. Factor:** | **2.64** | **Date of Analysis:** | **2/4/13 09:31 PM** |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 1.3 | 0.62 J | 6.5 | 3.1 J |
| Freon 114 | 1.3 | Not Detected | 9.2 | Not Detected |
| Chloromethane | 13 | Not Detected | 27 | Not Detected |
| Vinyl Chloride | 1.3 | Not Detected | 3.4 | Not Detected |
| 1,3-Butadiene | 1.3 | Not Detected | 2.9 | Not Detected |
| Bromomethane | 13 | Not Detected | 51 | Not Detected |
| Chloroethane | 5.3 | Not Detected | 14 | Not Detected |
| Freon 11 | 1.3 | 0.29 J | 7.4 | 1.6 J |
| Ethanol | 5.3 | 2.0 J | 9.9 | 3.7 J |
| Freon 113 | 1.3 | Not Detected | 10 | Not Detected |
| 1,1-Dichloroethene | 1.3 | Not Detected | 5.2 | Not Detected |
| Acetone | 13 | 4.4 J | 31 | 10 J |
| 2-Propanol | 5.3 | 1.4 J | 13 | 3.5 J |
| Carbon Disulfide | 5.3 | ~~2.0 J~~ | 16 | ~~6.2 J~~ |
| 3-Chloropropene | 5.3 | Not Detected | 16 | Not Detected |
| Methylene Chloride | 13 | Not Detected | 46 | Not Detected |
| Methyl tert-butyl ether | 1.3 | Not Detected | 4.8 | Not Detected |
| trans-1,2-Dichloroethene | 1.3 | Not Detected | 5.2 | Not Detected |
| Hexane | 1.3 | Not Detected | 4.6 | Not Detected |
| 1,1-Dichloroethane | 1.3 | Not Detected | 5.3 | Not Detected |
| 2-Butanone (Methyl Ethyl Ketone) | 5.3 | Not Detected | 16 | Not Detected |
| cis-1,2-Dichloroethene | 1.3 | Not Detected | 5.2 | Not Detected |
| Tetrahydrofuran | 1.3 | Not Detected | 3.9 | Not Detected |
| Chloroform | 1.3 | 0.46 J | 6.4 | 2.2 J |
| 1,1,1-Trichloroethane | 1.3 | Not Detected | 7.2 | Not Detected |
| Cyclohexane | 1.3 | Not Detected | 4.5 | Not Detected |
| Carbon Tetrachloride | 1.3 | Not Detected | 8.3 | Not Detected |
| 2,2,4-Trimethylpentane | 1.3 | 5.3 | 6.2 | 25 |
| Benzene | 1.3 | 0.67 J | 4.2 | 2.1 J |
| 1,2-Dichloroethane | 1.3 | Not Detected | 5.3 | Not Detected |
| Heptane | 1.3 | Not Detected | 5.4 | Not Detected |
| Trichloroethene | 1.3 | Not Detected | 7.1 | Not Detected |
| 1,2-Dichloropropane | 1.3 | Not Detected | 6.1 | Not Detected |
| 1,4-Dioxane | 5.3 | Not Detected | 19 | Not Detected |
| Bromodichloromethane | 1.3 | Not Detected | 8.8 | Not Detected |
| cis-1,3-Dichloropropene | 1.3 | Not Detected | 6.0 | Not Detected |
| 4-Methyl-2-pentanone | 1.3 | 0.45 J | 5.4 | 1.8 J |
| Toluene | 1.3 | ~~0.20 J~~ | 5.0 | ~~0.75 J~~ |
| trans-1,3-Dichloropropene | 1.3 | Not Detected | 6.0 | Not Detected |
| 1,1,2-Trichloroethane | 1.3 | Not Detected | 7.2 | Not Detected |
| Tetrachloroethene | 1.3 | 0.56 J | 9.0 | 3.8 J |
| 2-Hexanone | 5.3 | Not Detected | 22 | Not Detected |

eurofins | Air Toxics

**Client Sample ID: VMP-43-20-012413**

**Lab ID#: 1301504A-16A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | p020422 | **Date of Collection:** | 1/24/13 3:23:00 PM |
| **Dil. Factor:** | 2.64 | **Date of Analysis:** | 2/4/13 09:31 PM |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Dibromochloromethane | 1.3 | Not Detected | 11 | Not Detected |
| 1,2-Dibromoethane (EDB) | 1.3 | Not Detected | 10 | Not Detected |
| Chlorobenzene | 1.3 | Not Detected | 6.1 | Not Detected |
| Ethyl Benzene | 1.3 | Not Detected | 5.7 | Not Detected |
| m,p-Xylene | 1.3 | Not Detected | 5.7 | Not Detected |
| o-Xylene | 1.3 | Not Detected | 5.7 | Not Detected |
| Styrene | 1.3 | Not Detected | 5.6 | Not Detected |
| Bromoform | 1.3 | Not Detected | 14 | Not Detected |
| Cumene | 1.3 | Not Detected | 6.5 | Not Detected |
| 1,1,2,2-Tetrachloroethane | 1.3 | Not Detected | 9.1 | Not Detected |
| Propylbenzene | 1.3 | Not Detected | 6.5 | Not Detected |
| 4-Ethyltoluene | 1.3 | Not Detected | 6.5 | Not Detected |
| 1,3,5-Trimethylbenzene | 1.3 | Not Detected | 6.5 | Not Detected |
| 1,2,4-Trimethylbenzene | 1.3 | Not Detected | 6.5 | Not Detected |
| 1,3-Dichlorobenzene | 1.3 | Not Detected | 7.9 | Not Detected |
| 1,4-Dichlorobenzene | 1.3 | Not Detected | 7.9 | Not Detected |
| alpha-Chlorotoluene | 1.3 | Not Detected | 6.8 | Not Detected |
| 1,2-Dichlorobenzene | 1.3 | Not Detected | 7.9 | Not Detected |
| 1,2,4-Trichlorobenzene | 5.3 | Not Detected | 39 | Not Detected |
| Hexachlorobutadiene | 5.3 | Not Detected | 56 | Not Detected |
| Butane | 5.3 | 6.9 | 12 | 16 |
| Isopentane | 5.3 | 1.4 J | 16 | 4.0 J |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| Toluene-d8 | 105 | 70-130 |
| 1,2-Dichloroethane-d4 | 99 | 70-130 |
| 4-Bromofluorobenzene | 102 | 70-130 |

eurofins | Air Toxics

**Client Sample ID: VMP-43-30-012413**

**Lab ID#: 1301504A-17A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | p020423 | **Date of Collection:** | 1/24/13 4:13:00 PM |
| **Dil. Factor:** | 2.69 | **Date of Analysis:** | 2/4/13 09:51 PM |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 1.3 | 0.54 J | 6.6 | 2.6 J |
| Freon 114 | 1.3 | Not Detected | 9.4 | Not Detected |
| Chloromethane | 13 | Not Detected | 28 | Not Detected |
| Vinyl Chloride | 1.3 | Not Detected | 3.4 | Not Detected |
| 1,3-Butadiene | 1.3 | Not Detected | 3.0 | Not Detected |
| Bromomethane | 13 | Not Detected | 52 | Not Detected |
| Chloroethane | 5.4 | Not Detected | 14 | Not Detected |
| Freon 11 | 1.3 | 0.22 J | 7.6 | 1.2 J |
| Ethanol | 5.4 | 3.5 J | 10 | 6.6 J |
| Freon 113 | 1.3 | Not Detected | 10 | Not Detected |
| 1,1-Dichloroethene | 1.3 | Not Detected | 5.3 | Not Detected |
| Acetone | 13 | 2.3 J | 32 | 5.5 J |
| 2-Propanol | 5.4 | 6.5 | 13 | 16 |
| Carbon Disulfide | 5.4 | ~~0.72 J~~ | 17 | ~~2.2 J~~ |
| 3-Chloropropene | 5.4 | Not Detected | 17 | Not Detected |
| Methylene Chloride | 13 | ~~0.17 J~~ | 47 | ~~0.59 J~~ |
| Methyl tert-butyl ether | 1.3 | Not Detected | 4.8 | Not Detected |
| trans-1,2-Dichloroethene | 1.3 | Not Detected | 5.3 | Not Detected |
| Hexane | 1.3 | Not Detected | 4.7 | Not Detected |
| 1,1-Dichloroethane | 1.3 | Not Detected | 5.4 | Not Detected |
| 2-Butanone (Methyl Ethyl Ketone) | 5.4 | Not Detected | 16 | Not Detected |
| cis-1,2-Dichloroethene | 1.3 | Not Detected | 5.3 | Not Detected |
| Tetrahydrofuran | 1.3 | Not Detected | 4.0 | Not Detected |
| Chloroform | 1.3 | Not Detected | 6.6 | Not Detected |
| 1,1,1-Trichloroethane | 1.3 | Not Detected | 7.3 | Not Detected |
| Cyclohexane | 1.3 | Not Detected | 4.6 | Not Detected |
| Carbon Tetrachloride | 1.3 | Not Detected | 8.5 | Not Detected |
| 2,2,4-Trimethylpentane | 1.3 | 0.39 J | 6.3 | 1.8 J |
| Benzene | 1.3 | 3.8 | 4.3 | 12 |
| 1,2-Dichloroethane | 1.3 | Not Detected | 5.4 | Not Detected |
| Heptane | 1.3 | Not Detected | 5.5 | Not Detected |
| Trichloroethene | 1.3 | Not Detected | 7.2 | Not Detected |
| 1,2-Dichloropropane | 1.3 | Not Detected | 6.2 | Not Detected |
| 1,4-Dioxane | 5.4 | Not Detected | 19 | Not Detected |
| Bromodichloromethane | 1.3 | Not Detected | 9.0 | Not Detected |
| cis-1,3-Dichloropropene | 1.3 | Not Detected | 6.1 | Not Detected |
| 4-Methyl-2-pentanone | 1.3 | Not Detected | 5.5 | Not Detected |
| Toluene | 1.3 | ~~0.30 J~~ | 5.1 | ~~1.1 J~~ |
| trans-1,3-Dichloropropene | 1.3 | Not Detected | 6.1 | Not Detected |
| 1,1,2-Trichloroethane | 1.3 | Not Detected | 7.3 | Not Detected |
| Tetrachloroethene | 1.3 | ~~0.16 J~~ | 9.1 | ~~1.1 J~~ |
| 2-Hexanone | 5.4 | Not Detected | 22 | Not Detected |

eurofins | Air Toxics

**Client Sample ID: VMP-43-30-012413**

**Lab ID#: 1301504A-17A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | p020423 | **Date of Collection:** | 1/24/13 4:13:00 PM |
| **Dil. Factor:** | 2.69 | **Date of Analysis:** | 2/4/13 09:51 PM |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Dibromochloromethane | 1.3 | Not Detected | 11 | Not Detected |
| 1,2-Dibromoethane (EDB) | 1.3 | Not Detected | 10 | Not Detected |
| Chlorobenzene | 1.3 | Not Detected | 6.2 | Not Detected |
| Ethyl Benzene | 1.3 | Not Detected | 5.8 | Not Detected |
| m,p-Xylene | 1.3 | Not Detected | 5.8 | Not Detected |
| o-Xylene | 1.3 | Not Detected | 5.8 | Not Detected |
| Styrene | 1.3 | Not Detected | 5.7 | Not Detected |
| Bromoform | 1.3 | Not Detected | 14 | Not Detected |
| Cumene | 1.3 | Not Detected | 6.6 | Not Detected |
| 1,1,2,2-Tetrachloroethane | 1.3 | Not Detected | 9.2 | Not Detected |
| Propylbenzene | 1.3 | Not Detected | 6.6 | Not Detected |
| 4-Ethyltoluene | 1.3 | Not Detected | 6.6 | Not Detected |
| 1,3,5-Trimethylbenzene | 1.3 | Not Detected | 6.6 | Not Detected |
| 1,2,4-Trimethylbenzene | 1.3 | Not Detected | 6.6 | Not Detected |
| 1,3-Dichlorobenzene | 1.3 | Not Detected | 8.1 | Not Detected |
| 1,4-Dichlorobenzene | 1.3 | Not Detected | 8.1 | Not Detected |
| alpha-Chlorotoluene | 1.3 | Not Detected | 7.0 | Not Detected |
| 1,2-Dichlorobenzene | 1.3 | Not Detected | 8.1 | Not Detected |
| 1,2,4-Trichlorobenzene | 5.4 | Not Detected | 40 | Not Detected |
| Hexachlorobutadiene | 5.4 | Not Detected | 57 | Not Detected |
| Butane | 5.4 | 1.7 J | 13 | 4.0 J |
| Isopentane | 5.4 | 1.6 J | 16 | 4.8 J |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| Toluene-d8 | 97 | 70-130 |
| 1,2-Dichloroethane-d4 | 96 | 70-130 |
| 4-Bromofluorobenzene | 100 | 70-130 |

eurofins | Air Toxics

**Client Sample ID: Lab Blank**

**Lab ID#: 1301504A-18A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p020406a** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 2/4/13 11:43 AM** | |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 0.50 | Not Detected | 2.5 | Not Detected |
| Freon 114 | 0.50 | Not Detected | 3.5 | Not Detected |
| Chloromethane | 5.0 | Not Detected | 10 | Not Detected |
| Vinyl Chloride | 0.50 | Not Detected | 1.3 | Not Detected |
| 1,3-Butadiene | 0.50 | Not Detected | 1.1 | Not Detected |
| Bromomethane | 5.0 | 0.26 J | 19 | 0.99 J |
| Chloroethane | 2.0 | Not Detected | 5.3 | Not Detected |
| Freon 11 | 0.50 | Not Detected | 2.8 | Not Detected |
| Ethanol | 2.0 | Not Detected | 3.8 | Not Detected |
| Freon 113 | 0.50 | Not Detected | 3.8 | Not Detected |
| 1,1-Dichloroethene | 0.50 | Not Detected | 2.0 | Not Detected |
| Acetone | 5.0 | 0.45 J | 12 | 1.1 J |
| 2-Propanol | 2.0 | Not Detected | 4.9 | Not Detected |
| Carbon Disulfide | 2.0 | 0.50 J | 6.2 | 1.6 J |
| 3-Chloropropene | 2.0 | Not Detected | 6.3 | Not Detected |
| Methylene Chloride | 5.0 | 0.18 J | 17 | 0.64 J |
| Methyl tert-butyl ether | 0.50 | Not Detected | 1.8 | Not Detected |
| trans-1,2-Dichloroethene | 0.50 | 0.12 J | 2.0 | 0.48 J |
| Hexane | 0.50 | Not Detected | 1.8 | Not Detected |
| 1,1-Dichloroethane | 0.50 | Not Detected | 2.0 | Not Detected |
| 2-Butanone (Methyl Ethyl Ketone) | 2.0 | Not Detected | 5.9 | Not Detected |
| cis-1,2-Dichloroethene | 0.50 | Not Detected | 2.0 | Not Detected |
| Tetrahydrofuran | 0.50 | Not Detected | 1.5 | Not Detected |
| Chloroform | 0.50 | Not Detected | 2.4 | Not Detected |
| 1,1,1-Trichloroethane | 0.50 | Not Detected | 2.7 | Not Detected |
| Cyclohexane | 0.50 | Not Detected | 1.7 | Not Detected |
| Carbon Tetrachloride | 0.50 | Not Detected | 3.1 | Not Detected |
| 2,2,4-Trimethylpentane | 0.50 | Not Detected | 2.3 | Not Detected |
| Benzene | 0.50 | Not Detected | 1.6 | Not Detected |
| 1,2-Dichloroethane | 0.50 | Not Detected | 2.0 | Not Detected |
| Heptane | 0.50 | Not Detected | 2.0 | Not Detected |
| Trichloroethene | 0.50 | Not Detected | 2.7 | Not Detected |
| 1,2-Dichloropropane | 0.50 | Not Detected | 2.3 | Not Detected |
| 1,4-Dioxane | 2.0 | Not Detected | 7.2 | Not Detected |
| Bromodichloromethane | 0.50 | Not Detected | 3.4 | Not Detected |
| cis-1,3-Dichloropropene | 0.50 | 0.099 J | 2.3 | 0.45 J |
| 4-Methyl-2-pentanone | 0.50 | Not Detected | 2.0 | Not Detected |
| Toluene | 0.50 | 0.064 J | 1.9 | 0.24 J |
| trans-1,3-Dichloropropene | 0.50 | 0.17 J | 2.3 | 0.78 J |
| 1,1,2-Trichloroethane | 0.50 | Not Detected | 2.7 | Not Detected |
| Tetrachloroethene | 0.50 | 0.090 J | 3.4 | 0.61 J |
| 2-Hexanone | 2.0 | Not Detected | 8.2 | Not Detected |

eurofins | Air Toxics

**Client Sample ID: Lab Blank**

**Lab ID#: 1301504A-18A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p020406a** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 2/4/13 11:43 AM** | |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Dibromochloromethane | 0.50 | Not Detected | 4.2 | Not Detected |
| 1,2-Dibromoethane (EDB) | 0.50 | 0.13 J | 3.8 | 0.99 J |
| Chlorobenzene | 0.50 | 0.11 J | 2.3 | 0.49 J |
| Ethyl Benzene | 0.50 | Not Detected | 2.2 | Not Detected |
| m,p-Xylene | 0.50 | Not Detected | 2.2 | Not Detected |
| o-Xylene | 0.50 | Not Detected | 2.2 | Not Detected |
| Styrene | 0.50 | Not Detected | 2.1 | Not Detected |
| Bromoform | 0.50 | Not Detected | 5.2 | Not Detected |
| Cumene | 0.50 | Not Detected | 2.4 | Not Detected |
| 1,1,2,2-Tetrachloroethane | 0.50 | Not Detected | 3.4 | Not Detected |
| Propylbenzene | 0.50 | 0.079 J | 2.4 | 0.39 J |
| 4-Ethyltoluene | 0.50 | 0.067 J | 2.4 | 0.33 J |
| 1,3,5-Trimethylbenzene | 0.50 | Not Detected | 2.4 | Not Detected |
| 1,2,4-Trimethylbenzene | 0.50 | 0.12 J | 2.4 | 0.57 J |
| 1,3-Dichlorobenzene | 0.50 | 0.26 J | 3.0 | 1.6 J |
| 1,4-Dichlorobenzene | 0.50 | 0.28 J | 3.0 | 1.6 J |
| alpha-Chlorotoluene | 0.50 | 0.14 J | 2.6 | 0.71 J |
| 1,2-Dichlorobenzene | 0.50 | 0.22 J | 3.0 | 1.3 J |
| 1,2,4-Trichlorobenzene | 2.0 | 0.92 J | 15 | 6.8 J |
| Hexachlorobutadiene | 2.0 | 0.29 J | 21 | 3.0 J |
| Butane | 2.0 | Not Detected | 4.8 | Not Detected |
| Isopentane | 2.0 | Not Detected | 5.9 | Not Detected |

J = Estimated value.

**Container Type: NA - Not Applicable**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| Toluene-d8 | 97 | 70-130 |
| 1,2-Dichloroethane-d4 | 91 | 70-130 |
| 4-Bromofluorobenzene | 97 | 70-130 |

eurofins | Air Toxics

**Client Sample ID: CCV**

**Lab ID#: 1301504A-19A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p020402** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 2/4/13 09:34 AM** | |

| Compound | %Recovery |
|---|---|
| Freon 12 | 98 |
| Freon 114 | 100 |
| Chloromethane | 99 |
| Vinyl Chloride | 104 |
| 1,3-Butadiene | 103 |
| Bromomethane | 103 |
| Chloroethane | 103 |
| Freon 11 | 96 |
| Ethanol | 114 |
| Freon 113 | 101 |
| 1,1-Dichloroethene | 103 |
| Acetone | 106 |
| 2-Propanol | 106 |
| Carbon Disulfide | 100 |
| 3-Chloropropene | 106 |
| Methylene Chloride | 100 |
| Methyl tert-butyl ether | 107 |
| trans-1,2-Dichloroethene | 104 |
| Hexane | 110 |
| 1,1-Dichloroethane | 100 |
| 2-Butanone (Methyl Ethyl Ketone) | 104 |
| cis-1,2-Dichloroethene | 111 |
| Tetrahydrofuran | 109 |
| Chloroform | 97 |
| 1,1,1-Trichloroethane | 101 |
| Cyclohexane | 116 |
| Carbon Tetrachloride | 98 |
| 2,2,4-Trimethylpentane | 111 |
| Benzene | 101 |
| 1,2-Dichloroethane | 94 |
| Heptane | 112 |
| Trichloroethene | 83 |
| 1,2-Dichloropropane | 100 |
| 1,4-Dioxane | 110 |
| Bromodichloromethane | 95 |
| cis-1,3-Dichloropropene | 105 |
| 4-Methyl-2-pentanone | 115 |
| Toluene | 100 |
| trans-1,3-Dichloropropene | 106 |
| 1,1,2-Trichloroethane | 101 |
| Tetrachloroethene | 98 |
| 2-Hexanone | 108 |

eurofins | Air Toxics

**Client Sample ID: CCV**

**Lab ID#: 1301504A-19A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p020402** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 2/4/13 09:34 AM** | |

| Compound | %Recovery |
|---|---|
| Dibromochloromethane | 103 |
| 1,2-Dibromoethane (EDB) | 100 |
| Chlorobenzene | 95 |
| Ethyl Benzene | 108 |
| m,p-Xylene | 111 |
| o-Xylene | 112 |
| Styrene | 117 |
| Bromoform | 103 |
| Cumene | 112 |
| 1,1,2,2-Tetrachloroethane | 110 |
| Propylbenzene | 106 |
| 4-Ethyltoluene | 112 |
| 1,3,5-Trimethylbenzene | 113 |
| 1,2,4-Trimethylbenzene | 113 |
| 1,3-Dichlorobenzene | 103 |
| 1,4-Dichlorobenzene | 102 |
| alpha-Chlorotoluene | 111 |
| 1,2-Dichlorobenzene | 105 |
| 1,2,4-Trichlorobenzene | 104 |
| Hexachlorobutadiene | 100 |
| Butane | 101 |
| Isopentane | 105 |

**Container Type: NA - Not Applicable**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| Toluene-d8 | 100 | 70-130 |
| 1,2-Dichloroethane-d4 | 100 | 70-130 |
| 4-Bromofluorobenzene | 100 | 70-130 |

eurofins | Air Toxics

**Client Sample ID: LCS**

**Lab ID#: 1301504A-20A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p020403** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 2/4/13 10:09 AM** | |

| Compound | %Recovery |
|---|---|
| Freon 12 | 95 |
| Freon 114 | 98 |
| Chloromethane | 95 |
| Vinyl Chloride | 104 |
| 1,3-Butadiene | 100 |
| Bromomethane | 98 |
| Chloroethane | 101 |
| Freon 11 | 92 |
| Ethanol | 79 |
| Freon 113 | 99 |
| 1,1-Dichloroethene | 105 |
| Acetone | 102 |
| 2-Propanol | 103 |
| Carbon Disulfide | 120 |
| 3-Chloropropene | 120 |
| Methylene Chloride | 96 |
| Methyl tert-butyl ether | 106 |
| trans-1,2-Dichloroethene | 116 |
| Hexane | 106 |
| 1,1-Dichloroethane | 96 |
| 2-Butanone (Methyl Ethyl Ketone) | 103 |
| cis-1,2-Dichloroethene | 106 |
| Tetrahydrofuran | 106 |
| Chloroform | 96 |
| 1,1,1-Trichloroethane | 98 |
| Cyclohexane | 113 |
| Carbon Tetrachloride | 95 |
| 2,2,4-Trimethylpentane | 108 |
| Benzene | 100 |
| 1,2-Dichloroethane | 91 |
| Heptane | 110 |
| Trichloroethene | 83 |
| 1,2-Dichloropropane | 99 |
| 1,4-Dioxane | 107 |
| Bromodichloromethane | 93 |
| cis-1,3-Dichloropropene | 104 |
| 4-Methyl-2-pentanone | 114 |
| Toluene | 98 |
| trans-1,3-Dichloropropene | 104 |
| 1,1,2-Trichloroethane | 100 |
| Tetrachloroethene | 97 |
| 2-Hexanone | 106 |

eurofins | Air Toxics

**Client Sample ID: LCS**

**Lab ID#: 1301504A-20A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p020403** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 2/4/13 10:09 AM** | |

| **Compound** | **%Recovery** |
|---|---|
| Dibromochloromethane | 99 |
| 1,2-Dibromoethane (EDB) | 98 |
| Chlorobenzene | 95 |
| Ethyl Benzene | 104 |
| m,p-Xylene | 110 |
| o-Xylene | 111 |
| Styrene | 116 |
| Bromoform | 98 |
| Cumene | 111 |
| 1,1,2,2-Tetrachloroethane | 110 |
| Propylbenzene | 105 |
| 4-Ethyltoluene | 105 |
| 1,3,5-Trimethylbenzene | 112 |
| 1,2,4-Trimethylbenzene | 109 |
| 1,3-Dichlorobenzene | 101 |
| 1,4-Dichlorobenzene | 98 |
| alpha-Chlorotoluene | 106 |
| 1,2-Dichlorobenzene | 102 |
| 1,2,4-Trichlorobenzene | 100 |
| Hexachlorobutadiene | 94 |
| Butane | 94 |
| Isopentane | 102 |

**Container Type: NA - Not Applicable**

| **Surrogates** | **%Recovery** | **Method Limits** |
|---|---|---|
| Toluene-d8 | 101 | 70-130 |
| 1,2-Dichloroethane-d4 | 94 | 70-130 |
| 4-Bromofluorobenzene | 100 | 70-130 |

eurofins | Air Toxics

**Client Sample ID: LCSD**

**Lab ID#: 1301504A-20AA**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p020404** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 2/4/13 10:38 AM** | |

| Compound | %Recovery |
|---|---|
| Freon 12 | 94 |
| Freon 114 | 98 |
| Chloromethane | 97 |
| Vinyl Chloride | 105 |
| 1,3-Butadiene | 99 |
| Bromomethane | 100 |
| Chloroethane | 101 |
| Freon 11 | 91 |
| Ethanol | 79 |
| Freon 113 | 98 |
| 1,1-Dichloroethene | 105 |
| Acetone | 101 |
| 2-Propanol | 104 |
| Carbon Disulfide | 119 |
| 3-Chloropropene | 119 |
| Methylene Chloride | 96 |
| Methyl tert-butyl ether | 105 |
| trans-1,2-Dichloroethene | 118 |
| Hexane | 106 |
| 1,1-Dichloroethane | 98 |
| 2-Butanone (Methyl Ethyl Ketone) | 96 |
| cis-1,2-Dichloroethene | 107 |
| Tetrahydrofuran | 105 |
| Chloroform | 95 |
| 1,1,1-Trichloroethane | 98 |
| Cyclohexane | 116 |
| Carbon Tetrachloride | 94 |
| 2,2,4-Trimethylpentane | 110 |
| Benzene | 99 |
| 1,2-Dichloroethane | 88 |
| Heptane | 107 |
| Trichloroethene | 81 |
| 1,2-Dichloropropane | 98 |
| 1,4-Dioxane | 105 |
| Bromodichloromethane | 90 |
| cis-1,3-Dichloropropene | 102 |
| 4-Methyl-2-pentanone | 107 |
| Toluene | 96 |
| trans-1,3-Dichloropropene | 102 |
| 1,1,2-Trichloroethane | 98 |
| Tetrachloroethene | 94 |
| 2-Hexanone | 103 |

eurofins | Air Toxics

**Client Sample ID: LCSD**

**Lab ID#: 1301504A-20AA**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p020404** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 2/4/13 10:38 AM** | |

| Compound | %Recovery |
|---|---|
| Dibromochloromethane | 97 |
| 1,2-Dibromoethane (EDB) | 98 |
| Chlorobenzene | 94 |
| Ethyl Benzene | 103 |
| m,p-Xylene | 107 |
| o-Xylene | 109 |
| Styrene | 114 |
| Bromoform | 96 |
| Cumene | 110 |
| 1,1,2,2-Tetrachloroethane | 107 |
| Propylbenzene | 103 |
| 4-Ethyltoluene | 103 |
| 1,3,5-Trimethylbenzene | 111 |
| 1,2,4-Trimethylbenzene | 107 |
| 1,3-Dichlorobenzene | 99 |
| 1,4-Dichlorobenzene | 98 |
| alpha-Chlorotoluene | 104 |
| 1,2-Dichlorobenzene | 101 |
| 1,2,4-Trichlorobenzene | 100 |
| Hexachlorobutadiene | 94 |
| Butane | 93 |
| Isopentane | 101 |

**Container Type: NA - Not Applicable**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| Toluene-d8 | 99 | 70-130 |
| 1,2-Dichloroethane-d4 | 92 | 70-130 |
| 4-Bromofluorobenzene | 100 | 70-130 |

# Shell Oil Products Chain Of Custody Record

URS

Air Toxics LTD.
**Project Name: Roxana Soil Vapor**
**Project # 21562850.04001**
Lab Vendor #

Please Check Appropriate Box: ☑ ENV. SERVICES ☐ MOTIVA RETAIL ☐ SHELL RETAIL ☐ MOTIVA SC&CH ☐ CONSULTANT ☐ LUBES ☐ SHELL PIPELINE ☐ OTHER

Print Bill To Contact Name: Robert Mooshegian
RO #:
INCIDENT # (ENV SERVICES): 97216840 ☐ CHECK IF NO INCIDENT # APPLIES
SAP #: 340081
DATE: 01/25/13
PAGE: 2 of 3

SAMPLING COMPANY: URS CORPORATION
LOG CODE:
ADDRESS: 1001 HIGHLANDS PLAZA DRIVE WEST - SUITE 300; ST. LOUIS, MO 63110
SITE ADDRESS: Street and City: 900 SOUTH CENTRAL AVE – ROXANA
State: IL
GLOBAL ID NO.:
Laboratory Address: Air Toxics, LTD 180 Blue Ravine Road, Suite B, Folsom, CA 95630-4719
EDF DELIVERABLE TO (Name, Company, Office Location): Elizabeth Kunkel, URS, St. Louis
PHONE NO.: 314-743-4179
E-MAIL: Elizabeth_Kunkel@URSCorp.com
CONSULTANT PROJECT NAME#: Roxana Soil Vapor
TELEPHONE: 314-429-0100
FAX: 314-429-0462
EDF To Contact E-MAIL: Robert.Mooshegian@urs.com
M. Curner, C. Kretzer, M. Mittermeyer, L. Rathnow, S. Jansen, E. Arthur, A. Day, B. Lohan,

TURNAROUND TIME (CALENDAR DAYS): ☑ STANDARD (14 DAY) ☐ 5 DAYS ☐ 3 DAYS ☐ 2 DAYS ☐ 24 HOURS ☐ RESULTS NEEDED ON WEEKEND
☐ LA - RWQCB REPORT FORMAT ☑ UST AGENCY:
DELIVERABLES: ☐ LEVEL 1 ☐ LEVEL 2 ☐ LEVEL 3 ☑ LEVEL 4 ☐ OTHER (SPECIFY)
☑ SHELL CONTRACT RATE APPLIES
☐ STATE REIMBURSEMENT RATE APPLIES
☐ EDD NOT NEEDED
☑ RECEIPT VERIFICATION REQUESTED

REQUESTED ANALYSIS

| LAB USE ONLY | Field Sample Identification | SAMPLING DATE | SAMPLING TIME | Canister Number | Canister Pressure/Vacuum Initial | Final | Receipt | Final (psi) | Modified TO-15 + Butane & Isopentane | ASTM D-1946 + Helium | ASTM D-1946 |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 01A | VMP-20-5-012213 | 01/22/13 | 0940-1015 | 37792 | -30 | -5.5 | | | X | X | |
| 02A | VMP-20-10-012213 | 01/22/13 | 1100-1132 | 37757 | -30 | -5.5 | | | X | X | |
| 03A | VMP-20-25-012213 | 01/22/13 | 1403-1436 | 35635 | -30 | -6.5 | | | X | X | |
| 04A | VMP-22-5-012413 | 01/24/13 | 1007-1037 | 34102 | -30 | -9 | | | X | X | |
| 05A | VMP-22-10-012413 | 01/24/13 | 1052-1122 | 37350 | -30 | -9.5 | | | X | X | |
| 06A | VMP-22-18-012413 | 01/24/13 | 1141-1211 | 36405 | -30 | -9.5 | | | X | X | |
| 07A | VMP-22-38-012413 | 01/24/13 | 1231-1301 | 15751 | -32 | -9 | | | X | X | |
| 08A | VMP-23-5-012413 | 01/24/13 | 1008-1038 | 37698 | -30 | -8.5 | | | X | X | |
| 09A | VMP-23-10-012413 | 01/24/13 | 1053-1123 | 36391 | -30 | -7.5 | | | X | X | |
| 10A | VMP-23-25-012413 | 01/24/13 | 1143-1215 | 35645 | -30 | -7.5 | | | X | X | |

Turn Around Time: ☑ Normal ☐ Rush ☐ Specify

Lab Use Only
Pressurized by:
Date:
Pressurization Gas: $N_2$ He

ADDITIONAL NOTES:
- 14 day hold time
- Report results between MDL and RL
- Level IV ECVP

Relinquished by: (Signature) [signature]
Received by: (Signature) FEDEX
Date: 1/25/13 Time: 17:30

Relinquished by: (Signature)
Received by: (Signature) B Whitaker ATC 1/25/13 0745
Date: Time:

Relinquished by: (Signature)
Received by: (Signature)
Date: Time:

05/2006 Revision

Fedex

Custody Seal Intact?
(Y) N None Temp_____

130150A

# Shell Oil Products Chain Of Custody Record

URS

Air Toxics LTD.
**Project Name: Roxana Soil Vapor**
**Project # 21562850.04001**
Lab Vendor #

Please Check Appropriate Box:
☑ ENV. SERVICES ☐ MOTIVA RETAIL ☐ SHELL RETAIL
☐ MOTIVA SOMCM ☐ CONSULTANT ☐ LUBES
☐ SHELL PIPELINE ☐ OTHER

Print Bill To Contact Name: Robert Mooshegian
INCIDENT # (ENV SERVICES): 9 7 2 1 8 6 4 0
☐ CHECK IF NO INCIDENT # APPLIES
DATE: 01/25/13
PAGE: 3 of 3
PO #:
SAP #: 3 4 0 0 8 1

URS CORPORATION
ADDRESS: 1001 HIGHLANDS PLAZA DRIVE WEST - SUITE 300; ST. LOUIS, MO 63110
Laboratory Address: Air Toxics, LTD 180 Blue Ravine Road, Suite B, Folsom, CA 95630-4719
TELEPHONE: 314-429-0100 FAX: 314-429-0462 Bill To Contact E-MAIL: Robert.Mooshegian@urs.com

SITE ADDRESS: Street and City: 900 SOUTH CENTRAL AVE – ROXANA State: IL GLOBAL ID NO.:
EDF DELIVERABLE TO (Name, Company, Office Location): Elizabeth Kunkel, URS, St. Louis PHONE NO.: 314-743-4179 E-MAIL: Elizabeth_Kunkel@URSCorp.com CONSULTANT PROJECT NAME#: Roxana Soil Vapor
M. Currier, C. Kretzer, M. Mittermeyer, L. Rathnow, S. Jansen, E. Arthur, A. Day, B. Lohan,

TURNAROUND TIME (CALENDAR DAYS):
☑ STANDARD (14 DAY) ☐ 5 DAYS ☐ 3 DAYS ☐ 2 DAYS ☐ 24 HOURS ☐ RESULTS NEEDED ON WEEKEND

☐ LA - RWQCB REPORT FORMAT ☑ UST AGENCY:

DELIVERABLES: ☐ LEVEL 1 ☐ LEVEL 2 ☐ LEVEL 3 ☑ LEVEL 4 ☐ OTHER (SPECIFY)

☑ SHELL CONTRACT RATE APPLIES
☐ STATE REIMBURSEMENT RATE APPLIES
☐ EDD NOT NEEDED
☑ RECEIPT VERIFICATION REQUESTED

REQUESTED ANALYSIS

| LAB USE ONLY | Field Sample Identification | SAMPLING DATE | SAMPLING TIME | Canister Number | Canister Pressure/Vacuum: Initial | Final | Receipt | Final (psi) | Modified TO-15 + Butane & Isopentane | ASTM D-1946 + Helium | ASTM D-1946 |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 11A | VMP-23-40-012413 | 01/24/13 | 1245-1315 | 37779 | -30 | -9.5 | | | X | X | |
| 12A | VMP-24-5-012313 | 01/23/13 | 1119-1149 | 34134 | -30 | -7 | | | X | X | |
| 13A | VMP-24-10-012313 | 01/23/13 | 1253-1323 | 36571 | -30 | -10 | | | X | X | |
| 14A | VMP-24-22-012313 | 01/23/13 | 1334-1404 | 34610 | -30 | -9.5 | | | X | X | |
| 15A | VMP-24-34-012313 | 01/23/13 | 1432-1502 | 33411 | -29.5 | -10 | | | X | X | |
| 16A | VMP-43-20-012413 | 01/24/13 | 1453-1523 | 37407 | -30 | -9.5 | | | X | X | |
| 17A | VMP-43-30-012413 | 01/24/13 | 1543-1613 | 31756 | -29 | -10 | | | X | X | |

Turn Around Time: ☑ Normal ☐ Rush ☐ Specify

Lab Use Only
Pressurized by:
Date:
Pressurization Gas: $N_2$ He

ADDITIONAL NOTES:
- 14 day hold time
- Report results between MDL and RL
- Level IV ECVP

| Relinquished by: (Signature) | Received by: (Signature) | Date | Time |
|---|---|---|---|
| Andrew Rathnow | FEDEX | 1/25/13 | 17:30 |
| Relinquished by: (Signature) | Received by: (Signature) B. Lohan ATL 1/26/13 0945 | Date: | Time: |
| Relinquished by: (Signature) | Received by: (Signature) | Date: | Time: |

02/2008 Revision

Custody Seal Intact?
(Y) N None Temp____

eurofins | Air Toxics

2/14/2013
Ms. Elizabeth Kunkel
URS Corporation
1001 Highlands Plaza Dr. West
Suite 300
St. Louis MO 63110

Project Name: Roxana Soil Vapor
Project #: 21562850.04001
Workorder #: 1301504B

Dear Ms. Elizabeth Kunkel

The following report includes the data for the above referenced project for sample(s) received on 1/28/2013 at Air Toxics Ltd.

The data and associated QC analyzed by Modified ASTM D-1946 are compliant with the project requirements or laboratory criteria with the exception of the deviations noted in the attached case narrative.

Thank you for choosing Air Toxics Ltd. for your air analysis needs. Air Toxics Ltd. is committed to providing accurate data of the highest quality. Please feel free to contact the Project Manager: Kelly Buettner at 916-985-1000 if you have any questions regarding the data in this report.

Regards,

Kelly Buettner

Kelly Buettner
Project Manager

REVIEWED
ON
3/19/13

eurofins | Air Toxics

# WORK ORDER #: 1301504B

Work Order Summary

| | | | |
|---|---|---|---|
| **CLIENT:** | Ms. Elizabeth Kunkel<br>URS Corporation<br>1001 Highlands Plaza Dr. West<br>Suite 300<br>St. Louis, MO 63110 | **BILL TO:** | Accounts Payable Austin<br>URS Corporation<br>P.O. BOX 203970<br>Austin, TX 78720-1088 |
| **PHONE:** | 314-743-4179 | **P.O. #** | 21562735.00013 |
| **FAX:** | | **PROJECT #** | 21562850.04001 Roxana Soil Vapor |
| **DATE RECEIVED:** | 01/28/2013 | **CONTACT:** | Kelly Buettner |
| **DATE COMPLETED:** | 02/14/2013 | | |

| FRACTION # | NAME | TEST | RECEIPT VAC./PRES. | FINAL PRESSURE |
|---|---|---|---|---|
| 01A(cancelled) | VMP-20-5-012213 | Modified ASTM D-1946 | 0.0 "Hg | 15 psi |
| 02A | VMP-20-10-012213 | Modified ASTM D-1946 | 5.5 "Hg | 15 psi |
| 03A | VMP-20-25-012213 | Modified ASTM D-1946 | 5.5 "Hg | 15 psi |
| 04A | VMP-22-5-012413 | Modified ASTM D-1946 | 6.5 "Hg | 15 psi |
| 05A | VMP-22-10-012413 | Modified ASTM D-1946 | 8.0 "Hg | 15 psi |
| 06A | VMP-22-18-012413 | Modified ASTM D-1946 | 8.0 "Hg | 15 psi |
| 07A | VMP-22-38-012413 | Modified ASTM D-1946 | 7.5 "Hg | 15 psi |
| 08A | VMP-23-5-012413 | Modified ASTM D-1946 | 5.5 "Hg | 15 psi |
| 09A | VMP-23-10-012413 | Modified ASTM D-1946 | 5.5 "Hg | 15 psi |
| 10A | VMP-23-25-012413 | Modified ASTM D-1946 | 6.0 "Hg | 15 psi |
| 11A | VMP-23-40-012413 | Modified ASTM D-1946 | 6.5 "Hg | 15 psi |
| 12A | VMP-24-5-012313 | Modified ASTM D-1946 | 6.0 "Hg | 15 psi |
| 13A | VMP-24-10-012313 | Modified ASTM D-1946 | 8.0 "Hg | 15 psi |
| 14A | VMP-24-22-012313 | Modified ASTM D-1946 | 8.5 "Hg | 15 psi |
| 15A | VMP-24-34-012313 | Modified ASTM D-1946 | 9.0 "Hg | 15 psi |
| 16A | VMP-43-20-012413 | Modified ASTM D-1946 | 7.0 "Hg | 15 psi |
| 17A | VMP-43-30-012413 | Modified ASTM D-1946 | 7.5 "Hg | 15 psi |
| 18A | Lab Blank | Modified ASTM D-1946 | NA | NA |
| 18B | Lab Blank | Modified ASTM D-1946 | NA | NA |
| 19A | LCS | Modified ASTM D-1946 | NA | NA |
| 19AA | LCSD | Modified ASTM D-1946 | NA | NA |

CERTIFIED BY: Heidi Hayes DATE: 02/14/13

Technical Director

Certification numbers: AZ Licensure AZ0775, CA NELAP - 12282CA, NY NELAP - 11291, TX NELAP - T104704434-12-4, UT NELAP CA009332012-3, WA NELAP - C935
Name of Accrediting Agency: NELAP/ORELAP (Oregon Environmental Laboratory Accreditation Program)
Accreditation number: CA300005, Effective date: 10/18/2012, Expiration date: 10/17/2013.
Eurofins Air Toxics Ltd. certifies that the test results contained in this report meet all requirements of the NELAC standards

This report shall not be reproduced, except in full, without the written approval of Eurofins Air Toxics, Inc.

180 BLUE RAVINE ROAD, SUITE B FOLSOM, CA - 9563
(916) 985-1000 . (800) 985-5955 . FAX (916) 985-1020

**LABORATORY NARRATIVE**
**Modified ASTM D-1946**
**URS Corporation**
**Workorder# 1301504B**

Seventeen 1 Liter Summa Canister samples were received on January 28, 2013. The laboratory performed analysis via Modified ASTM Method D-1946 for Methane and fixed gases in air using GC/FID or GC/TCD. The method involves direct injection of 1.0 mL of sample.

On the analytical column employed for this analysis, Oxygen coelutes with Argon. The corresponding peak is quantitated as Oxygen.

Since Nitrogen is used to pressurize samples, the reported Nitrogen values are calculated by adding all the sample components and subtracting from 100%.

Method modifications taken to run these samples are summarized in the table below. Specific project requirements may over-ride the ATL modifications.

| *Requirement* | *ASTM D-1946* | *ATL Modifications* |
|---|---|---|
| Calibration | A single point calibration is performed using a reference standard closely matching the composition of the unknown. | A 3-point calibration curve is performed. Quantitation is based on a daily calibration standard which may or may not resemble the composition of the associated samples. |
| Reference Standard | The composition of any reference standard must be known to within 0.01 mol % for any component. | The standards used by ATL are blended to a >/= 95% accuracy. |
| Sample Injection Volume | Components whose concentrations are in excess of 5 % should not be analyzed by using sample volumes greater than 0.5 mL. | The sample container is connected directly to a fixed volume sample loop of 1.0 mL on the GC. Linear range is defined by the calibration curve. Bags are loaded by vacuum. |
| Normalization | Normalize the mole percent values by multiplying each value by 100 and dividing by the sum of the original values. The sum of the original values should not differ from 100% by more than 1.0%. | Results are not normalized. The sum of the reported values can differ from 100% by as much as 15%, either due to analytical variability or an unusual sample matrix. |
| Precision | Precision requirements established at each concentration level. | Duplicates should agree within 25% RPD for detections > 5 X's the RL. |

**Receiving Notes**

The canister valve on sample VMP-20-5-012213 was received open and a brass plug was not used to seal the canister. The sample vented to ambient pressure during shipment. The client was contacted and the sample was cancelled.

**Analytical Notes**

As per project specific client request the laboratory has reported estimated values for target compound hits that are below the Reporting Limit but greater than the Method Detection Limit. Concentrations that are below the level at which the canister was certified may be false positives.

The reporting limit for Carbon Monoxide was raised from 0.010% to 0.050%.

**Definition of Data Qualifying Flags**

Seven qualifiers may have been used on the data analysis sheets and indicate as follows:
B - Compound present in laboratory blank greater than reporting limit.
J - Estimated value.
E - Exceeds instrument calibration range.
S - Saturated peak.
Q - Exceeds quality control limits.
U - Compound analyzed for but not detected above the detection limit.
M - Reported value may be biased due to apparent matrix interferences.
File extensions may have been used on the data analysis sheets and indicates as follows:
a-File was requantified
b-File was quantified by a second column and detector
r1-File was requantified for the purpose of reissue

eurofins | Air Toxics

# Summary of Detected Compounds
# NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1946

**Client Sample ID: VMP-20-10-012213**

**Lab ID#: 1301504B-02A**

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.25 | 20 |
| Nitrogen | 0.25 | 77 |
| Methane | 0.00025 | 0.000027 J |
| Carbon Dioxide | 0.025 | 3.2 |

**Client Sample ID: VMP-20-25-012213**

**Lab ID#: 1301504B-03A**

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.25 | 16 |
| Nitrogen | 0.25 | 78 |
| Methane | 0.00025 | 0.000016 J |
| Carbon Dioxide | 0.025 | 6.2 |

**Client Sample ID: VMP-22-5-012413**

**Lab ID#: 1301504B-04A**

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.26 | 21 |
| Nitrogen | 0.26 | 79 |
| Methane | 0.00026 | 0.000048 J |
| Carbon Dioxide | 0.026 | 0.38 |

**Client Sample ID: VMP-22-10-012413**

**Lab ID#: 1301504B-05A**

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.28 | 20 |
| Nitrogen | 0.28 | 79 |
| Methane | 0.00028 | 0.000022 J |
| Carbon Dioxide | 0.028 | 0.68 |

eurofins | Air Toxics

# Summary of Detected Compounds
# NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1946

**Client Sample ID: VMP-22-18-012413**

**Lab ID#: 1301504B-06A**

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.28 | 20 |
| Nitrogen | 0.28 | 78 |
| Carbon Dioxide | 0.028 | 2.2 |

**Client Sample ID: VMP-22-38-012413**

**Lab ID#: 1301504B-07A**

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.27 | 18 |
| Nitrogen | 0.27 | 77 |
| Methane | 0.00027 | 0.00012 J |
| Carbon Dioxide | 0.027 | 5.1 |

**Client Sample ID: VMP-23-5-012413**

**Lab ID#: 1301504B-08A**

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.25 | 21 |
| Nitrogen | 0.25 | 79 |
| Methane | 0.00025 | 0.00017 J |
| Carbon Dioxide | 0.025 | 0.20 |

**Client Sample ID: VMP-23-10-012413**

**Lab ID#: 1301504B-09A**

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.25 | 21 |
| Nitrogen | 0.25 | 79 |
| Methane | 0.00025 | 0.000098 J |
| Carbon Dioxide | 0.025 | 0.34 |

eurofins | Air Toxics

# Summary of Detected Compounds
# NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1946

**Client Sample ID: VMP-23-25-012413**

**Lab ID#: 1301504B-10A**

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.25 | 19 |
| Nitrogen | 0.25 | 78 |
| Carbon Dioxide | 0.025 | 3.2 |

**Client Sample ID: VMP-23-40-012413**

**Lab ID#: 1301504B-11A**

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.26 | 17 |
| Nitrogen | 0.26 | 78 |
| Carbon Dioxide | 0.026 | 5.2 |

**Client Sample ID: VMP-24-5-012313**

**Lab ID#: 1301504B-12A**

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.25 | 18 |
| Nitrogen | 0.25 | 78 |
| Methane | 0.00025 | 0.000085 J |
| Carbon Dioxide | 0.025 | 3.6 |

**Client Sample ID: VMP-24-10-012313**

**Lab ID#: 1301504B-13A**

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.28 | 17 |
| Nitrogen | 0.28 | 78 |
| Methane | 0.00028 | 0.000057 J |
| Carbon Dioxide | 0.028 | 5.3 |

**Client Sample ID: VMP-24-22-012313**

**Lab ID#: 1301504B-14A**

eurofins | Air Toxics

# Summary of Detected Compounds
# NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1946

**Client Sample ID: VMP-24-22-012313**

**Lab ID#: 1301504B-14A**

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.28 | 17 |
| Nitrogen | 0.28 | 77 |
| Methane | 0.00028 | 0.000033 J |
| Carbon Dioxide | 0.028 | 6.4 |

**Client Sample ID: VMP-24-34-012313**

**Lab ID#: 1301504B-15A**

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.29 | 17 |
| Nitrogen | 0.29 | 78 |
| Methane | 0.00029 | 0.000050 J |
| Carbon Dioxide | 0.029 | 4.7 |

**Client Sample ID: VMP-43-20-012413**

**Lab ID#: 1301504B-16A**

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.26 | 18 |
| Nitrogen | 0.26 | 79 |
| Methane | 0.00026 | 0.00065 |
| Carbon Dioxide | 0.026 | 3.2 |

**Client Sample ID: VMP-43-30-012413**

**Lab ID#: 1301504B-17A**

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.27 | 19 |
| Nitrogen | 0.27 | 79 |
| Methane | 0.00027 | 0.000040 J |
| Carbon Dioxide | 0.027 | 1.7 |

eurofins | Air Toxics

**Client Sample ID: VMP-20-10-012213**

**Lab ID#: 1301504B-02A**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1946**

| | | | |
|---|---|---|---|
| **File Name:** | **9020607** | **Date of Collection:** | **1/22/13 11:32:00 AM** |
| **Dil. Factor:** | **2.47** | **Date of Analysis:** | **2/5/13 09:39 PM** |

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.25 | 20 |
| Nitrogen | 0.25 | 77 |
| Carbon Monoxide | 0.12 | Not Detected |
| Methane | 0.00025 | 0.000027 J |
| Carbon Dioxide | 0.025 | 3.2 |
| Ethane | 0.0025 | Not Detected |
| Ethene | 0.0025 | Not Detected |
| Helium | 0.12 | Not Detected |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

eurofins | Air Toxics

**Client Sample ID: VMP-20-25-012213**

**Lab ID#: 1301504B-03A**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1946**

| | | | |
|---|---|---|---|
| **File Name:** | **9020608** | **Date of Collection:** | **1/22/13 2:36:00 PM** |
| **Dil. Factor:** | **2.47** | **Date of Analysis:** | **2/5/13 10:00 PM** |

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.25 | 16 |
| Nitrogen | 0.25 | 78 |
| Carbon Monoxide | 0.12 | Not Detected |
| Methane | 0.00025 | 0.000016 J |
| Carbon Dioxide | 0.025 | 6.2 |
| Ethane | 0.0025 | Not Detected |
| Ethene | 0.0025 | Not Detected |
| Helium | 0.12 | Not Detected |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

eurofins | Air Toxics

**Client Sample ID: VMP-22-5-012413**

**Lab ID#: 1301504B-04A**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1946**

| | | | |
|---|---|---|---|
| **File Name:** | **9020609** | **Date of Collection:** | **1/24/13 10:37:00 AM** |
| **Dil. Factor:** | **2.58** | **Date of Analysis:** | **2/5/13 10:30 PM** |

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.26 | 21 |
| Nitrogen | 0.26 | 79 |
| Carbon Monoxide | 0.13 | Not Detected |
| Methane | 0.00026 | 0.000048 J |
| Carbon Dioxide | 0.026 | 0.38 |
| Ethane | 0.0026 | Not Detected |
| Ethene | 0.0026 | Not Detected |
| Helium | 0.13 | Not Detected |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

eurofins | Air Toxics

**Client Sample ID: VMP-22-10-012413**

**Lab ID#: 1301504B-05A**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1946**

| | | | |
|---|---|---|---|
| **File Name:** | **9020610** | **Date of Collection:** | **1/24/13 11:22:00 AM** |
| **Dil. Factor:** | **2.76** | **Date of Analysis:** | **2/6/13 06:18 AM** |

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.28 | 20 |
| Nitrogen | 0.28 | 79 |
| Carbon Monoxide | 0.14 | Not Detected |
| Methane | 0.00028 | 0.000022 J |
| Carbon Dioxide | 0.028 | 0.68 |
| Ethane | 0.0028 | Not Detected |
| Ethene | 0.0028 | Not Detected |
| Helium | 0.14 | Not Detected |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

eurofins | Air Toxics

**Client Sample ID: VMP-22-18-012413**

**Lab ID#: 1301504B-06A**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1946**

| | | | |
|---|---|---|---|
| **File Name:** | **9020617** | **Date of Collection:** | **1/24/13 12:11:00 PM** |
| **Dil. Factor:** | **2.76** | **Date of Analysis:** | **2/6/13 09:26 AM** |

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.28 | 20 |
| Nitrogen | 0.28 | 78 |
| Carbon Monoxide | 0.14 | Not Detected |
| Methane | 0.00028 | Not Detected |
| Carbon Dioxide | 0.028 | 2.2 |
| Ethane | 0.0028 | Not Detected |
| Ethene | 0.0028 | Not Detected |
| Helium | 0.14 | Not Detected |

**Container Type: 1 Liter Summa Canister**

eurofins | Air Toxics

**Client Sample ID: VMP-22-38-012413**

**Lab ID#: 1301504B-07A**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1946**

| | | | |
|---|---|---|---|
| **File Name:** | **9020618** | **Date of Collection:** | **1/24/13 1:01:00 PM** |
| **Dil. Factor:** | **2.69** | **Date of Analysis:** | **2/6/13 09:50 AM** |

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.27 | 18 |
| Nitrogen | 0.27 | 77 |
| Carbon Monoxide | 0.13 | Not Detected |
| Methane | 0.00027 | 0.00012 J |
| Carbon Dioxide | 0.027 | 5.1 |
| Ethane | 0.0027 | Not Detected |
| Ethene | 0.0027 | Not Detected |
| Helium | 0.13 | Not Detected |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

eurofins | Air Toxics

**Client Sample ID: VMP-23-5-012413**

**Lab ID#: 1301504B-08A**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1946**

| | | | |
|---|---|---|---|
| **File Name:** | **9020619** | **Date of Collection:** | **1/24/13 10:38:00 AM** |
| **Dil. Factor:** | **2.47** | **Date of Analysis:** | **2/6/13 10:13 AM** |

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.25 | 21 |
| Nitrogen | 0.25 | 79 |
| Carbon Monoxide | 0.12 | Not Detected |
| Methane | 0.00025 | 0.00017 J |
| Carbon Dioxide | 0.025 | 0.20 |
| Ethane | 0.0025 | Not Detected |
| Ethene | 0.0025 | Not Detected |
| Helium | 0.12 | Not Detected |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

eurofins | Air Toxics

**Client Sample ID: VMP-23-10-012413**

**Lab ID#: 1301504B-09A**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1946**

| | | | |
|---|---|---|---|
| **File Name:** | **9020620** | **Date of Collection:** | **1/24/13 11:23:00 AM** |
| **Dil. Factor:** | **2.47** | **Date of Analysis:** | **2/6/13 10:44 AM** |

| **Compound** | **Rpt. Limit (%)** | **Amount (%)** |
|---|---|---|
| Oxygen | 0.25 | 21 |
| Nitrogen | 0.25 | 79 |
| Carbon Monoxide | 0.12 | Not Detected |
| Methane | 0.00025 | 0.000098 J |
| Carbon Dioxide | 0.025 | 0.34 |
| Ethane | 0.0025 | Not Detected |
| Ethene | 0.0025 | Not Detected |
| Helium | 0.12 | Not Detected |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

eurofins | Air Toxics

**Client Sample ID: VMP-23-25-012413**

**Lab ID#: 1301504B-10A**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1946**

| | | | |
|---|---|---|---|
| **File Name:** | **9020621** | **Date of Collection:** | **1/24/13 12:15:00 PM** |
| **Dil. Factor:** | **2.52** | **Date of Analysis:** | **2/6/13 11:19 AM** |

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.25 | 19 |
| Nitrogen | 0.25 | 78 |
| Carbon Monoxide | 0.13 | Not Detected |
| Methane | 0.00025 | Not Detected |
| Carbon Dioxide | 0.025 | 3.2 |
| Ethane | 0.0025 | Not Detected |
| Ethene | 0.0025 | Not Detected |
| Helium | 0.13 | Not Detected |

**Container Type: 1 Liter Summa Canister**

eurofins | Air Toxics

**Client Sample ID: VMP-23-40-012413**

**Lab ID#: 1301504B-11A**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1946**

| | | | |
|---|---|---|---|
| **File Name:** | **9020622** | **Date of Collection:** | **1/24/13 1:15:00 PM** |
| **Dil. Factor:** | **2.58** | **Date of Analysis:** | **2/6/13 11:52 AM** |

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.26 | 17 |
| Nitrogen | 0.26 | 78 |
| Carbon Monoxide | 0.13 | Not Detected |
| Methane | 0.00026 | Not Detected |
| Carbon Dioxide | 0.026 | 5.2 |
| Ethane | 0.0026 | Not Detected |
| Ethene | 0.0026 | Not Detected |
| Helium | 0.13 | Not Detected |

**Container Type: 1 Liter Summa Canister**

eurofins | Air Toxics

**Client Sample ID: VMP-24-5-012313**

**Lab ID#: 1301504B-12A**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1946**

| | | | |
|---|---|---|---|
| **File Name:** | **9020611** | **Date of Collection:** | **1/23/13 11:49:00 AM** |
| **Dil. Factor:** | **2.52** | **Date of Analysis:** | **2/6/13 06:49 AM** |

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.25 | 18 |
| Nitrogen | 0.25 | 78 |
| Carbon Monoxide | 0.13 | Not Detected |
| Methane | 0.00025 | 0.000085 J |
| Carbon Dioxide | 0.025 | 3.6 |
| Ethane | 0.0025 | Not Detected |
| Ethene | 0.0025 | Not Detected |
| Helium | 0.13 | Not Detected |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

eurofins | Air Toxics

**Client Sample ID: VMP-24-10-012313**

**Lab ID#: 1301504B-13A**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1946**

| | | | |
|---|---|---|---|
| **File Name:** | **9020612** | **Date of Collection:** | **1/23/13 1:23:00 PM** |
| **Dil. Factor:** | **2.76** | **Date of Analysis:** | **2/6/13 07:12 AM** |

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.28 | 17 |
| Nitrogen | 0.28 | 78 |
| Carbon Monoxide | 0.14 | Not Detected |
| Methane | 0.00028 | 0.000057 J |
| Carbon Dioxide | 0.028 | 5.3 |
| Ethane | 0.0028 | Not Detected |
| Ethene | 0.0028 | Not Detected |
| Helium | 0.14 | Not Detected |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

eurofins | Air Toxics

**Client Sample ID: VMP-24-22-012313**

**Lab ID#: 1301504B-14A**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1946**

| | | | |
|---|---|---|---|
| **File Name:** | **9020613** | **Date of Collection:** | **1/23/13 2:04:00 PM** |
| **Dil. Factor:** | **2.82** | **Date of Analysis:** | **2/6/13 07:35 AM** |

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.28 | 17 |
| Nitrogen | 0.28 | 77 |
| Carbon Monoxide | 0.14 | Not Detected |
| Methane | 0.00028 | 0.000033 J |
| Carbon Dioxide | 0.028 | 6.4 |
| Ethane | 0.0028 | Not Detected |
| Ethene | 0.0028 | Not Detected |
| Helium | 0.14 | Not Detected |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

eurofins | Air Toxics

**Client Sample ID: VMP-24-34-012313**

**Lab ID#: 1301504B-15A**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1946**

| | | | |
|---|---|---|---|
| **File Name:** | **9020614** | **Date of Collection:** | **1/23/13 3:02:00 PM** |
| **Dil. Factor:** | **2.89** | **Date of Analysis:** | **2/6/13 07:57 AM** |

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.29 | 17 |
| Nitrogen | 0.29 | 78 |
| Carbon Monoxide | 0.14 | Not Detected |
| Methane | 0.00029 | 0.000050 J |
| Carbon Dioxide | 0.029 | 4.7 |
| Ethane | 0.0029 | Not Detected |
| Ethene | 0.0029 | Not Detected |
| Helium | 0.14 | Not Detected |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

eurofins | Air Toxics

**Client Sample ID: VMP-43-20-012413**

**Lab ID#: 1301504B-16A**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1946**

| | | | |
|---|---|---|---|
| **File Name:** | **9020615** | **Date of Collection:** | **1/24/13 3:23:00 PM** |
| **Dil. Factor:** | **2.64** | **Date of Analysis:** | **2/6/13 08:27 AM** |

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.26 | 18 |
| Nitrogen | 0.26 | 79 |
| Carbon Monoxide | 0.13 | Not Detected |
| Methane | 0.00026 | 0.00065 |
| Carbon Dioxide | 0.026 | 3.2 |
| Ethane | 0.0026 | Not Detected |
| Ethene | 0.0026 | Not Detected |
| Helium | 0.13 | Not Detected |

**Container Type: 1 Liter Summa Canister**

eurofins | Air Toxics

**Client Sample ID: VMP-43-30-012413**

**Lab ID#: 1301504B-17A**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1946**

| | | | |
|---|---|---|---|
| **File Name:** | **9020616** | **Date of Collection:** | **1/24/13 4:13:00 PM** |
| **Dil. Factor:** | **2.69** | **Date of Analysis:** | **2/6/13 08:59 AM** |

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.27 | 19 |
| Nitrogen | 0.27 | 79 |
| Carbon Monoxide | 0.13 | Not Detected |
| Methane | 0.00027 | 0.000040 J |
| Carbon Dioxide | 0.027 | 1.7 |
| Ethane | 0.0027 | Not Detected |
| Ethene | 0.0027 | Not Detected |
| Helium | 0.13 | Not Detected |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

eurofins | Air Toxics

**Client Sample ID: Lab Blank**

**Lab ID#: 1301504B-18A**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1946**

| | | | |
|---|---|---|---|
| **File Name:** | **9020606a** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 2/5/13 09:15 PM** | |

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.10 | Not Detected |
| Nitrogen | 0.10 | 0.099 J |
| Carbon Monoxide | 0.010 | Not Detected |
| Methane | 0.00010 | Not Detected |
| Carbon Dioxide | 0.010 | Not Detected |
| Ethane | 0.0010 | Not Detected |
| Ethene | 0.0010 | Not Detected |

J = Estimated value.

**Container Type: NA - Not Applicable**

eurofins | Air Toxics

**Client Sample ID: Lab Blank**

**Lab ID#: 1301504B-18B**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1946**

| | | | |
|---|---|---|---|
| **File Name:** | **9020604b** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 2/5/13 08:28 PM** | |

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Helium | 0.050 | Not Detected |

**Container Type: NA - Not Applicable**

eurofins | Air Toxics

**Client Sample ID: LCS**

**Lab ID#: 1301504B-19A**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1946**

| | | | |
|---|---|---|---|
| **File Name:** | **9020603** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 2/5/13 07:39 PM** | |

| Compound | %Recovery |
|---|---|
| Oxygen | 102 |
| Nitrogen | 101 |
| Carbon Monoxide | 98 |
| Methane | 104 |
| Carbon Dioxide | 101 |
| Ethane | 106 |
| Ethene | 103 |
| Helium | 101 |

**Container Type: NA - Not Applicable**

eurofins | Air Toxics

**Client Sample ID: LCSD**

**Lab ID#: 1301504B-19AA**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1946**

| | | | |
|---|---|---|---|
| **File Name:** | **9020631a** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 2/6/13 04:57 PM** | |

| **Compound** | **%Recovery** |
|---|---|
| Oxygen | 101 |
| Nitrogen | 101 |
| Carbon Monoxide | 95 |
| Methane | 113 |
| Carbon Dioxide | 97 |
| Ethane | 115 |
| Ethene | 112 |
| Helium | 100 |

**Container Type: NA - Not Applicable**

# Shell Oil Products Chain Of Custody Record

URS

**Air Toxics LTD.**
**Project Name: Roxana Soil Vapor**
**Project # 21562850.04001**
**Lab Vendor #**

**Please Check Appropriate Box:**
☑ ENV. SERVICES ☐ MOTIVA RETAIL ☐ SHELL RETAIL
☐ MOTIVA SC&CM ☐ CONSULTANT ☐ LUBES
☐ SHELL PIPELINE ☐ OTHER

**Print Bill To Contact Name:** Robert Mooshegian
**INCIDENT # (ENV SERVICES):** 97216840 ☐ CHECK IF NO INCIDENT # APPLIES
DATE: 01/25/13
PAGE: 2 of 3
**PO #:**
**SAP #:** 340081

Sampling Company: URS CORPORATION
Address: 1001 HIGHLANDS PLAZA DRIVE WEST - SUITE 300; ST. LOUIS, MO 63110
Laboratory Address: Air Toxics, LTD 180 Blue Ravine Road, Suite B, Folsom, CA 95630-4719
Telephone: 314-429-0100 Fax: 314-429-0462 Collector E-Mail: Robert.Monshegian@urs.com

**SITE ADDRESS: Street and City:** 900 SOUTH CENTRAL AVE – ROXANA **State:** IL **GLOBAL ID NO.:**
**EDF DELIVERABLE TO (Name, Company, Office Location):** Elizabeth Kunkel, URS, St. Louis **Phone No.:** 314-743-4179 **E-MAIL:** Elizabeth_Kunkel@URSCorp.com **CONSULTANT PROJECT NAME/#:** Roxana Soil Vapor
M. Culmer, C. Kretzer, M. Mittermeyer, L. Rathnow, S. Jensen, E. Arthur, A. Day, B. Lohan,

TURNAROUND TIME (CALENDAR DAYS):
☑ STANDARD (14 DAY) ☐ 5 DAYS ☐ 3 DAYS ☐ 2 DAYS ☐ 24 HOURS ☐ RESULTS NEEDED ON WEEKEND

☐ LA - RWQCB REPORT FORMAT ☑ UST AGENCY:

DELIVERABLES: ☐ LEVEL 1 ☐ LEVEL 2 ☐ LEVEL 3 ☑ LEVEL 4 ☐ OTHER (SPECIFY) _____

☑ SHELL CONTRACT RATE APPLIES
☐ STATE REIMBURSEMENT RATE APPLIES
☐ EDD NOT NEEDED
☑ RECEIPT VERIFICATION REQUESTED

**REQUESTED ANALYSIS**

| LAB USE ONLY | Field Sample Identification | SAMPLING DATE | SAMPLING TIME | Canister Number | Canister Pressure/Vacuum Initial | Final | Receipt | Final (psi) | Modified TO-15 + Butane & Isopentane | ASTM D-1946 + Helium | ASTM D-1946 |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 01A | VMP-20-5-012213 | 01/22/13 | 0940-1015 | 37792 | -30 | -5.5 | | | X | X | |
| 02A | VMP-20-10-012213 | 01/22/13 | 1100-1132 | 37757 | -30 | -5.5 | | | X | X | |
| 03A | VMP-20-25-012213 | 01/22/13 | 1403-1436 | 35635 | -30 | -6.5 | | | X | X | |
| 04A | VMP-22-5-012413 | 01/24/13 | 1007-1037 | 34102 | -30 | -9 | | | X | X | |
| 05A | VMP-22-10-012413 | 01/24/13 | 1052-1122 | 37350 | -30 | -6.5 | | | X | X | |
| 06A | VMP-22-18-012413 | 01/24/13 | 1141-1211 | 36405 | -30 | -8.5 | | | X | X | |
| 07A | VMP-22-38-012413 | 01/24/13 | 1231-1301 | 15751 | -32 | -9 | | | X | X | |
| 08A | VMP-23-5-012413 | 01/24/13 | 1008-1038 | 37698 | -30 | -8.5 | | | X | X | |
| 09A | VMP-23-10-012413 | 01/24/13 | 1053-1123 | 36381 | -30 | -7.5 | | | X | X | |
| 10A | VMP-23-25-012413 | 01/24/13 | 1143-1215 | 35645 | -30 | -7.5 | | | X | X | |

**Turn Around Time:** ☑ Normal ☐ Rush ☐ Specify

**Lab Use Only**
Pressurized by:
Date:
Pressurization Gas: $N_2$ He

**ADDITIONAL NOTES:**
- 14 day hold time
- Report results between MDL and RL
- Level IV ECVP

| Relinquished by: (Signature) | Received by: (Signature) | Date | Time |
|---|---|---|---|
| [signature] | FEDEX | 1/25/13 | 17:30 |
| Relinquished by: (Signature) | Received by: (Signature) [signature] ATC 1/25/13 0945 | Date: | Time: |
| Relinquished by: (Signature) | Received by: (Signature) | Date | Time |

05/2008 Revision

Fedex

Custody Seal Intact?
(Y) N None Temp_____

130150A

# Shell Oil Products Chain Of Custody Record

URS

Air Toxics LTD.
**Project Name: Roxana Soil Vapor**
**Project # 21562850.04001**
Lab Vendor #

Please Check Appropriate Box:
☑ ENV. SERVICES ☐ MOTIVA RETAIL ☐ SHELL RETAIL
☐ MOTIVA STEAM ☐ CONSULTANT ☐ LUBES
☐ SHELL PIPELINE ☐ OTHER

Print Bill To Contact Name: Robert Moosheglan
PO #:
INCIDENT # (ENV SERVICES): 9 7 2 1 6 6 4 0
SAP #: 3 4 0 0 6 1
☐ CHECK IF NO INCIDENT # APPLIES
DATE: 01/25/13
PAGE: 3 of 3

SAMPLING COMPANY: URS CORPORATION
ADDRESS: 1001 HIGHLANDS PLAZA DRIVE WEST - SUITE 300; ST. LOUIS, MO 63110
LOGBOOK ADDRESS: Air Toxics, LTD 180 Blue Ravine Road, Suite B, Folsom, CA 95630-4719
TELEPHONE: 314-429-0100 FAX: 314-429-0462 BILL TO CONTACT E-MAIL: Robert.Moosheglan@urs.com
SITE ADDRESS: Street and City: 900 SOUTH CENTRAL AVE – ROXANA State: IL GLOBAL ENO.:
EDF DELIVERABLE TO (Name, Company, Office Location): Elizabeth Kunkel, URS, St. Louis PHONE NO.: 314-743-4179 E-MAIL: Elizabeth.Kunkel@URSCorp.com CONSULTANT PROJECT MANAGER: Roxana Soil Vapor
M. Currier, C. Kretzer, M. Mittermeyer, L. Rathnow, S. Jansen, E. Arthur, A. Day, B. Lohan,

TURNAROUND TIME (CALENDAR DAYS):
☑ STANDARD (14 DAY) ☐ 5 DAYS ☐ 3 DAYS ☐ 2 DAYS ☐ 24 HOURS ☐ RESULTS NEEDED ON WEEKEND

☐ LA - RWQCB REPORT FORMAT ☑ UST AGENCY:

DELIVERABLES: ☐ LEVEL 1 ☐ LEVEL 2 ☐ LEVEL 3 ☑ LEVEL 4 ☐ OTHER (SPECIFY)

☑ SHELL CONTRACT RATE APPLIES
☐ STATE REIMBURSEMENT RATE APPLIES
☐ EDD NOT NEEDED
☑ RECEIPT VERIFICATION REQUESTED

REQUESTED ANALYSIS

| LAB USE ONLY | Field Sample Identification | SAMPLING DATE | SAMPLING TIME | Canister Number | Canister Pressure/Vacuum Initial | Final | Receipt | Final (psi) | Modified TO-15 + Butane & Isopentane | ASTM D-1946 + Helium | ASTM D-1946 |
|---|---|---|---|---|---|---|---|---|---|---|---|
| | VMP-23-40-012413 | 01/24/13 | 1245-1315 | 37779 | -30 | -9.5 | | | X | X | |
| | VMP-24-5-012313 | 01/23/13 | 1119-1149 | 34134 | -30 | -7 | | | X | X | |
| | VMP-24-10-012313 | 01/23/13 | 1253-1323 | 36571 | -30 | -10 | | | X | X | |
| | VMP-24-22-012313 | 01/23/13 | 1334-1404 | 34610 | -30 | -9.5 | | | X | X | |
| | VMP-24-34-012313 | 01/23/13 | 1432-1502 | 33411 | -29.5 | -10 | | | X | X | |
| | VMP-43-20-012413 | 01/24/13 | 1453-1523 | 37407 | -30 | -9.5 | | | X | X | |
| | VMP-43-30-012413 | 01/24/13 | 1543-1613 | 31756 | -29 | -10 | | | X | X | |

Turn Around Time: ☑ Normal ☐ Rush Specify

Lab Use Only
Pressurized by:
Date:
Pressurization Gas: $N_2$ He

ADDITIONAL NOTES:
- 14 day hold time
- Report results between MDL and RL
- Level IV ECVP

Relinquished by: (Signature) Lindsay Rathnow
Relinquished by: (Signature)
Relinquished by: (Signature)

Received by: (Signature) FEDEX
Received by: (Signature) BJ Nuttelman ATL 1/26/13 0945
Received by: (Signature)

Date: 1/25/13 Time: 17:30
Date: Time:
Date: Time:

05/2008 Revision

4-cooler
Custody Seal Intact?
(Y) N None Temp_____

# SVE System O&M 2013 Data Review

**Laboratory SDG: 1301530A,B,C**

**Data Reviewer: Elizabeth Kunkel**

**Peer Reviewer: Steve Gragert**

**Date Reviewed: 2/25/2013**

**Guidance: USEPA National Functional Guidelines for Superfund Organic Methods Data Review 2008**

| Sample Identification | Sample Identification |
|---|---|
| EXH-SVE-01162013 | MainHeader-SVE-01162013 |
| PWHeader-SVE-01162013 | |

## 1.0 Data Package Completeness

*Were all items delivered as specified in the QAPP and COC as appropriate?*

Yes

## 2.0 Laboratory Case Narrative \ Cooler Receipt Form

*Were problems noted in the laboratory case narrative or cooler receipt form?*

Yes, the laboratory case narrative indicated samples MainHeader-SVE-01162013 and PWHeader-SVE-01162013 were diluted due to high levels of target analytes. Recovery of the surrogate fluorobenzene was outside evaluation criteria for TPH sample MainHeader-SVE-01162013 due to high levels of hydrocarbon matrix interference. Although not indicated in the laboratory case narrative, analytes were detected in the method blank. The CCV recovery for ethanol was outside evaluation criteria. These issues are addressed further in the appropriate sections below.

The cooler receipt form did not indicate any problems.

## 3.0 Holding Times

*Were samples extracted/analyzed within applicable limits?*

Yes

## 4.0 Blank Contamination

*Were any analytes detected in the Blanks?*

Yes

| Blank ID | Parameter | Analyte | Concentration/Amount |
|---|---|---|---|
| 1301530A-04A | TO-15 | Bromomethane | 0.26 ppbv / 1.0 µg/m$^3$ |
| 1301530A-04A | TO-15 | Ethanol | 0.61 ppbv / 1.1 µg/m$^3$ |
| 1301530A-04A | TO-15 | Carbon disulfide | 0.34 ppbv / 1.1 µg/m$^3$ |
| 1301530A-04A | TO-15 | Methylene chloride | 0.25 ppbv / 0.88 µg/m$^3$ |
| 1301530A-04A | TO-15 | 2,2,4-Trimethylpentane | 0.15 ppbv / 0.71 µg/m$^3$ |
| 1301530A-04A | TO-15 | Toluene | 0.060 ppbv / 0.23 µg/m$^3$ |
| 1301530A-04A | TO-15 | 1,3-Dichlorobenzene | 0.11 ppbv / 0.66 µg/m$^3$ |

| Blank ID | Parameter | Analyte | Concentration/Amount |
|---|---|---|---|
| 1301530A-04A | TO-15 | 1,4-Dichlorobenzene | 0.096 ppbv / 0.58 µg/m$^3$ |
| 1301530A-04A | TO-15 | 1,2,4-Trichlorobenzene | 0.33 ppbv / 2.4 µg/m$^3$ |
| 1301530A-04B | TO-15 | Methylene chloride | 1.0 ppbv / 3.6 µg/m$^3$ |
| 1301530A-04B | TO-15 | 1,4-Dichlorobenzene | 1.0 ppbv / 6.4 µg/m$^3$ |
| 1301530A-04B | TO-15 | alpha-Chlorotoluene | 1.0 ppbv / 5.4 µg/m$^3$ |
| 1301530A-04B | TO-15 | 1,2,4-Trichlorobenzene | 12 ppbv / 86 µg/m$^3$ |
| 1301530A-04B | TO-15 | Hexachlorobutadiene | 13 ppbv / 140 µg/m$^3$ |
| 1301530B-04A | TO-3 | TPH (C2-C10) | 0.014 ppmv/ 0.056 µg/L |
| 1301530C-04A | ASTM D-1945 | Nitrogen | 0.068% |

Qualifications due to blank contamination are included in the table below. Analytical data that were reported non-detect or at concentrations greater than five times (5X) the associated blank concentration did not require qualification.

| Sample ID | Parameter | Analyte | New Reporting Limit (RL) | Qualification |
|---|---|---|---|---|
| EXH-SVE-01162013 | TO-15 | Carbon disulfide | - | **U** |
| EXH-SVE-01162013 | TO-15 | Methylene chloride | - | **U** |
| EXH-SVE-01162013 | TO-15 | 1,3-Dichlorobenzene | - | **U** |
| EXH-SVE-01162013 | TO-15 | 1,4-Dichlorobenzene | - | **U** |
| EXH-SVE-01162013 | TO-15 | 1,2,4-Trichlorobenzene | - | **U** |

## 5.0 Laboratory Control Sample

*Were LCS recoveries within evaluation criteria?*

Yes

## 6.0 Surrogate Recoveries

*Were surrogate recoveries within evaluation criteria?*

No

| Sample ID | Parameter | Surrogate | Recovery (%) | Criteria (%) |
|---|---|---|---|---|
| MainHeader-SVE-01162013 | TO-3 | Fluorobenzene | **166** | 75-150 |

Analytical data that required qualification based on surrogate data are included in the table below.

| Sample ID | Parameter | Analyte | Qualification |
|---|---|---|---|
| MainHeader-SVE-01162013 | TO-3 | TPH (C2-C10) ref. to gasoline | **J** |

## 7.0 Matrix Spike and Matrix Spike Duplicate Recoveries

*Were MS/MSD samples analyzed as part of this SDG?*

MS/MSD samples are not applicable for vapor samples due to the inability to spike the samples in summa canisters.

## 8.0 Laboratory Duplicate Results

*Were laboratory duplicate samples collected as part of this SDG?*

No

## 9.0 Field Duplicate Results

*Were field duplicate samples collected as part of this SDG?*

No

## 10.0 Sample Dilutions

*For samples that were diluted and nondetect, were undiluted results also reported?*

Not applicable; analytes were detected in samples that were diluted.

## 11.0 Additional Qualifications

*Were additional qualifications applied?*

Yes, continuing calibration verification (CCV) recoveries listed in the table below were above evaluation criteria.

| CCV ID | Parameter | Analyte | CCV Recovery | CCV Criteria |
|---|---|---|---|---|
| 1301530A-05B | TO-15 | Ethanol | **138** | 70-130 |

Analytical data that required qualification based on CCV data are included in the table below. Analytical data reported as non-detect and associated with LCS recoveries above evaluation criteria, indicating a possible high bias, did not require qualification.

| Field ID | Parameter | Analyte | Qualification |
|---|---|---|---|
| EXH-SVE-01162013 | TO-15 | Ethanol | **J** |
| MainHeader-SVE-01162013 | TO-15 | Ethanol | **J** |

eurofins | Air Toxics

2/15/2013
Ms. Elizabeth Kunkel
URS Corporation
1001 Highlands Plaza Dr. West
Suite 300
St. Louis MO 63110

Project Name: Roxana SVE O&M
Project #: 21562850.05000
Workorder #: 1301530A

Dear Ms. Elizabeth Kunkel

The following report includes the data for the above referenced project for sample(s) received on 1/30/2013 at Air Toxics Ltd.

The data and associated QC analyzed by Modified TO-15 are compliant with the project requirements or laboratory criteria with the exception of the deviations noted in the attached case narrative.

Thank you for choosing Air Toxics Ltd. for your air analysis needs. Air Toxics Ltd. is committed to providing accurate data of the highest quality. Please feel free to contact the Project Manager: Kelly Buettner at 916-985-1000 if you have any questions regarding the data in this report.

Regards,

Kelly Buettner

Project Manager

Reviewed
on
2/25/2013

eurofins | Air Toxics

# WORK ORDER #: 1301530A

Work Order Summary

| | | | |
|---|---|---|---|
| **CLIENT:** | Ms. Elizabeth Kunkel<br>URS Corporation<br>1001 Highlands Plaza Dr. West<br>Suite 300<br>St. Louis, MO 63110 | **BILL TO:** | Accounts Payable Austin<br>URS Corporation<br>P.O. BOX 203970<br>Austin, TX 78720-1088 |
| **PHONE:** | 314-743-4179 | **P.O. #** | |
| **FAX:** | | **PROJECT #** | 21562850.05000 Roxana SVE O&M |
| **DATE RECEIVED:** | 01/30/2013 | **CONTACT:** | Kelly Buettner |
| **DATE COMPLETED:** | 02/15/2013 | | |

| FRACTION # | NAME | TEST | RECEIPT VAC./PRES. | FINAL PRESSURE |
|---|---|---|---|---|
| 01A | EXH-SVE-01162013 | Modified TO-15 | 8.5 "Hg | 15 psi |
| 02A | MainHeader-SVE-01162013 | Modified TO-15 | 9.5 "Hg | 15 psi |
| 03A | PWHeader-SVE-01162013 | Modified TO-15 | 9.5 "Hg | 15 psi |
| 04A | Lab Blank | Modified TO-15 | NA | NA |
| 04B | Lab Blank | Modified TO-15 | NA | NA |
| 05A | CCV | Modified TO-15 | NA | NA |
| 05B | CCV | Modified TO-15 | NA | NA |
| 06A | LCS | Modified TO-15 | NA | NA |
| 06AA | LCSD | Modified TO-15 | NA | NA |
| 06B | LCS | Modified TO-15 | NA | NA |
| 06BB | LCSD | Modified TO-15 | NA | NA |

CERTIFIED BY: Heidi Rogers DATE: 02/15/13

Technical Director

Certfication numbers: AZ Licensure AZ0775, CA NELAP - 12282CA, NY NELAP - 11291,
TX NELAP - T104704434-12-5, UT NELAP CA009332012-3, WA NELAP - C935
Name of Accrediting Agency: NELAP/ORELAP (Oregon Environmental Laboratory Accreditation Program)
Accreditation number: CA300005, Effective date: 10/18/2011, Expiration date: 10/17/2012.
Eurofins Air Toxics Ltd. certifies that the test results contained in this report meet all requirements of the NELAC standards

This report shall not be reproduced, except in full, without the written approval of Eurofins Air Toxics, Inc.

180 BLUE RAVINE ROAD, SUITE B FOLSOM, CA - 9563
(916) 985-1000 . (800) 985-5955 . FAX (916) 985-1020

**LABORATORY NARRATIVE**
**EPA Method TO-15**
**URS Corporation**
**Workorder# 1301530A**

Three 1 Liter Summa Canister samples were received on January 30, 2013. The laboratory performed analysis via EPA Method TO-15 using GC/MS in the full scan mode.

This workorder was independently validated prior to submittal using 'USEPA National Functional Guidelines' as generally applied to the analysis of volatile organic compounds in air. A rules-based, logic driven, independent validation engine was employed to assess completeness, evaluate pass/fail of relevant project quality control requirements and verification of all quantified amounts.

**Receiving Notes**

There were no receiving discrepancies.

**Analytical Notes**

As per client project requirements, the laboratory has reported estimated values for target compound hits that are below the Reporting Limit but greater than the Method Detection Limit. Concentrations that are below the level at which the canister was certified may be false positives.

Dilution was performed on samples MainHeader-SVE-01162013 and PWHeader-SVE-01162013 due to the presence of high level target species.

All Quality Control Limit exceedances and affected sample results are noted by flags. Each flag is defined at the bottom of this Case Narrative and on each Sample Result Summary page. Target compound non-detects in the samples that are associated with high bias in QC analyses have not been flagged.

**Definition of Data Qualifying Flags**

Eight qualifiers may have been used on the data analysis sheets and indicates as follows:

B - Compound present in laboratory blank greater than reporting limit (background subtraction not performed).

J - Estimated value.

E - Exceeds instrument calibration range.

S - Saturated peak.

Q - Exceeds quality control limits.

U - Compound analyzed for but not detected above the reporting limit.

UJ- Non-detected compound associated with low bias in the CCV and/or LCS.

N - The identification is based on presumptive evidence.

File extensions may have been used on the data analysis sheets and indicates as follows:

a-File was requantified

b-File was quantified by a second column and detector

r1-File was requantified for the purpose of reissue

eurofins | Air Toxics

# Summary of Detected Compounds
# EPA METHOD TO-15 GC/MS FULL SCAN

**Client Sample ID: EXH-SVE-01162013**

**Lab ID#: 1301530A-01A**

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Ethanol | 5.6 | 3.0 J J | 11 | 5.7 J J |
| Acetone | 14 | 5.9 J | 33 | 14 J |
| 2-Propanol | 5.6 | 0.70 J | 14 | 1.7 J |
| Carbon Disulfide | 5.6 | ~~1.3 J~~ U | 18 | ~~4.0 J~~ U |
| Methylene Chloride | 14 | ~~0.36 J~~ U | 49 | ~~1.3 J~~ U |
| Hexane | 1.4 | 87 | 5.0 | 310 |
| 2-Butanone (Methyl Ethyl Ketone) | 5.6 | 1.2 J | 17 | 3.4 J |
| Cyclohexane | 1.4 | 21 | 4.8 | 72 |
| 2,2,4-Trimethylpentane | 1.4 | 76 | 6.6 | 360 |
| Benzene | 1.4 | 91 | 4.5 | 290 |
| Heptane | 1.4 | 18 | 5.8 | 72 |
| Toluene | 1.4 | 7.6 | 5.3 | 29 |
| Tetrachloroethene | 1.4 | 0.77 J | 9.6 | 5.2 J |
| Ethyl Benzene | 1.4 | 2.2 | 6.1 | 9.7 |
| m,p-Xylene | 1.4 | 5.2 | 6.1 | 22 |
| o-Xylene | 1.4 | 1.1 J | 6.1 | 4.9 J |
| Cumene | 1.4 | 0.43 J | 6.9 | 2.1 J |
| Propylbenzene | 1.4 | 0.30 J | 6.9 | 1.5 J |
| 4-Ethyltoluene | 1.4 | 0.40 J | 6.9 | 2.0 J |
| 1,3,5-Trimethylbenzene | 1.4 | 0.26 J | 6.9 | 1.3 J |
| 1,2,4-Trimethylbenzene | 1.4 | 0.60 J | 6.9 | 2.9 J |
| 1,3-Dichlorobenzene | 1.4 | ~~0.23 J~~ U | 8.5 | ~~1.4 J~~ U |
| 1,4-Dichlorobenzene | 1.4 | ~~0.30 J~~ U | 8.5 | ~~1.8 J~~ U |
| 1,2,4-Trichlorobenzene | 5.6 | ~~0.55 J~~ U | 42 | ~~4.1 J~~ U |
| Butane | 5.6 | 210 | 13 | 510 |
| Isopentane | 5.6 | 340 | 17 | 1000 |

**Client Sample ID: MainHeader-SVE-01162013**

**Lab ID#: 1301530A-02A**

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Ethanol | 12000 | 2200 J J | 22000 | 4200 J J |
| Acetone | 12000 | 4000 J | 28000 | 9400 J |

# Summary of Detected Compounds
# EPA METHOD TO-15 GC/MS

**Client Sample ID: MainHeader-SVE-01162013**

**Lab ID#: 1301530A-02A**

| | | | | |
|---|---|---|---|---|
| 2-Propanol | 12000 | 730 J | 29000 | 1800 J |
| Methylene Chloride | 3000 | 1300 J | 10000 | 4600 J |
| Methyl tert-butyl ether | 3000 | 350 J | 11000 | 1300 J |
| Hexane | 3000 | 620000 | 10000 | 2200000 |
| Cyclohexane | 3000 | 120000 | 10000 | 410000 |
| 2,2,4-Trimethylpentane | 3000 | 390000 | 14000 | 1800000 |
| Benzene | 3000 | 34000 | 9400 | 110000 |
| Heptane | 3000 | 100000 | 12000 | 420000 |
| Toluene | 3000 | 28000 | 11000 | 100000 |
| Ethyl Benzene | 3000 | 3100 | 13000 | 14000 |
| m,p-Xylene | 3000 | 5500 | 13000 | 24000 |
| o-Xylene | 3000 | 910 J | 13000 | 4000 J |
| Butane | 12000 | 1800000 | 28000 | 4200000 |
| Isopentane | 12000 | 2300000 | 35000 | 6800000 |

**Client Sample ID: PWHeader-SVE-01162013**

**Lab ID#: 1301530A-03A**

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Methylene Chloride | 1500 | 480 J | 5100 | 1600 J |
| Hexane | 1500 | 65000 | 5200 | 230000 |
| cis-1,2-Dichloroethene | 1500 | 420 J | 5900 | 1600 J |
| Cyclohexane | 1500 | 14000 | 5100 | 48000 |
| 2,2,4-Trimethylpentane | 1500 | 44000 | 6900 | 210000 |
| Benzene | 1500 | 370000 | 4700 | 1200000 |
| Heptane | 1500 | 7400 | 6100 | 30000 |
| Trichloroethene | 1500 | 350 J | 8000 | 1900 J |
| Toluene | 1500 | 320 J | 5600 | 1200 J |
| Tetrachloroethene | 1500 | 3500 | 10000 | 24000 |
| Butane | 5900 | 420000 | 14000 | 990000 |
| Isopentane | 5900 | 780000 | 17000 | 2300000 |

eurofins | Air Toxics

**Client Sample ID: EXH-SVE-01162013**

**Lab ID#: 1301530A-01A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p013017** | **Date of Collection:** | **1/16/13 9:25:00 AM** |
| **Dil. Factor:** | **2.82** | **Date of Analysis:** | **1/30/13 08:00 PM** |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 1.4 | Not Detected | 7.0 | Not Detected |
| Freon 114 | 1.4 | Not Detected | 9.8 | Not Detected |
| Chloromethane | 14 | Not Detected | 29 | Not Detected |
| Vinyl Chloride | 1.4 | Not Detected | 3.6 | Not Detected |
| 1,3-Butadiene | 1.4 | Not Detected | 3.1 | Not Detected |
| Bromomethane | 14 | Not Detected | 55 | Not Detected |
| Chloroethane | 5.6 | Not Detected | 15 | Not Detected |
| Freon 11 | 1.4 | Not Detected | 7.9 | Not Detected |
| Ethanol | 5.6 | 3.0 J J | 11 | 5.7 J J |
| Freon 113 | 1.4 | Not Detected | 11 | Not Detected |
| 1,1-Dichloroethene | 1.4 | Not Detected | 5.6 | Not Detected |
| Acetone | 14 | 5.9 J | 33 | 14 J |
| 2-Propanol | 5.6 | 0.70 J | 14 | 1.7 J |
| Carbon Disulfide | 5.6 | ~~1.3 J~~ U | 18 | ~~4.0 J~~ U |
| 3-Chloropropene | 5.6 | Not Detected | 18 | Not Detected |
| Methylene Chloride | 14 | ~~0.36 J~~ U | 49 | ~~1.3 J~~ U |
| Methyl tert-butyl ether | 1.4 | Not Detected | 5.1 | Not Detected |
| trans-1,2-Dichloroethene | 1.4 | Not Detected | 5.6 | Not Detected |
| Hexane | 1.4 | 87 | 5.0 | 310 |
| 1,1-Dichloroethane | 1.4 | Not Detected | 5.7 | Not Detected |
| 2-Butanone (Methyl Ethyl Ketone) | 5.6 | 1.2 J | 17 | 3.4 J |
| cis-1,2-Dichloroethene | 1.4 | Not Detected | 5.6 | Not Detected |
| Tetrahydrofuran | 1.4 | Not Detected | 4.2 | Not Detected |
| Chloroform | 1.4 | Not Detected | 6.9 | Not Detected |
| 1,1,1-Trichloroethane | 1.4 | Not Detected | 7.7 | Not Detected |
| Cyclohexane | 1.4 | 21 | 4.8 | 72 |
| Carbon Tetrachloride | 1.4 | Not Detected | 8.9 | Not Detected |
| 2,2,4-Trimethylpentane | 1.4 | 76 | 6.6 | 360 |
| Benzene | 1.4 | 91 | 4.5 | 290 |
| 1,2-Dichloroethane | 1.4 | Not Detected | 5.7 | Not Detected |
| Heptane | 1.4 | 18 | 5.8 | 72 |
| Trichloroethene | 1.4 | Not Detected | 7.6 | Not Detected |
| 1,2-Dichloropropane | 1.4 | Not Detected | 6.5 | Not Detected |
| 1,4-Dioxane | 5.6 | Not Detected | 20 | Not Detected |
| Bromodichloromethane | 1.4 | Not Detected | 9.4 | Not Detected |
| cis-1,3-Dichloropropene | 1.4 | Not Detected | 6.4 | Not Detected |
| 4-Methyl-2-pentanone | 1.4 | Not Detected | 5.8 | Not Detected |
| Toluene | 1.4 | 7.6 | 5.3 | 29 |
| trans-1,3-Dichloropropene | 1.4 | Not Detected | 6.4 | Not Detected |
| 1,1,2-Trichloroethane | 1.4 | Not Detected | 7.7 | Not Detected |
| Tetrachloroethene | 1.4 | 0.77 J | 9.6 | 5.2 J |
| 2-Hexanone | 5.6 | Not Detected | 23 | Not Detected |

eurofins | Air Toxics

**Client Sample ID: EXH-SVE-01162013**

**Lab ID#: 1301530A-01A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p013017** | **Date of Collection:** | **1/16/13 9:25:00 AM** |
| **Dil. Factor:** | **2.82** | **Date of Analysis:** | **1/30/13 08:00 PM** |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Dibromochloromethane | 1.4 | Not Detected | 12 | Not Detected |
| 1,2-Dibromoethane (EDB) | 1.4 | Not Detected | 11 | Not Detected |
| Chlorobenzene | 1.4 | Not Detected | 6.5 | Not Detected |
| Ethyl Benzene | 1.4 | 2.2 | 6.1 | 9.7 |
| m,p-Xylene | 1.4 | 5.2 | 6.1 | 22 |
| o-Xylene | 1.4 | 1.1 J | 6.1 | 4.9 J |
| Styrene | 1.4 | Not Detected | 6.0 | Not Detected |
| Bromoform | 1.4 | Not Detected | 14 | Not Detected |
| Cumene | 1.4 | 0.43 J | 6.9 | 2.1 J |
| 1,1,2,2-Tetrachloroethane | 1.4 | Not Detected | 9.7 | Not Detected |
| Propylbenzene | 1.4 | 0.30 J | 6.9 | 1.5 J |
| 4-Ethyltoluene | 1.4 | 0.40 J | 6.9 | 2.0 J |
| 1,3,5-Trimethylbenzene | 1.4 | 0.26 J | 6.9 | 1.3 J |
| 1,2,4-Trimethylbenzene | 1.4 | 0.60 J | 6.9 | 2.9 J |
| 1,3-Dichlorobenzene | 1.4 | ~~0.23 J~~ U | 8.5 | ~~1.4 J~~ U |
| 1,4-Dichlorobenzene | 1.4 | ~~0.30 J~~ U | 8.5 | ~~1.8 J~~ U |
| alpha-Chlorotoluene | 1.4 | Not Detected | 7.3 | Not Detected |
| 1,2-Dichlorobenzene | 1.4 | Not Detected | 8.5 | Not Detected |
| 1,2,4-Trichlorobenzene | 5.6 | ~~0.55 J~~ U | 42 | ~~4.1 J~~ U |
| Hexachlorobutadiene | 5.6 | Not Detected | 60 | Not Detected |
| Butane | 5.6 | 210 | 13 | 510 |
| Isopentane | 5.6 | 340 | 17 | 1000 |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| Toluene-d8 | 120 | 70-130 |
| 1,2-Dichloroethane-d4 | 103 | 70-130 |
| 4-Bromofluorobenzene | 83 | 70-130 |

eurofins | Air Toxics

**Client Sample ID: MainHeader-SVE-01162013**

**Lab ID#: 1301530A-02A**

**EPA METHOD TO-15 GC/MS**

| | | | |
|---|---|---|---|
| **File Name:** | **14013028** | **Date of Collection:** | **1/16/13 9:35:00 AM** |
| **Dil. Factor:** | **592** | **Date of Analysis:** | **1/30/13 10:08 PM** |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 3000 | Not Detected | 15000 | Not Detected |
| Freon 114 | 3000 | Not Detected | 21000 | Not Detected |
| Chloromethane | 12000 | Not Detected | 24000 | Not Detected |
| Vinyl Chloride | 3000 | Not Detected | 7600 | Not Detected |
| 1,3-Butadiene | 3000 | Not Detected | 6500 | Not Detected |
| Bromomethane | 3000 | Not Detected | 11000 | Not Detected |
| Chloroethane | 12000 | Not Detected | 31000 | Not Detected |
| Freon 11 | 3000 | Not Detected | 17000 | Not Detected |
| Ethanol | 12000 | 2200 J J | 22000 | 4200 J J |
| Freon 113 | 3000 | Not Detected | 23000 | Not Detected |
| 1,1-Dichloroethene | 3000 | Not Detected | 12000 | Not Detected |
| Acetone | 12000 | 4000 J | 28000 | 9400 J |
| 2-Propanol | 12000 | 730 J | 29000 | 1800 J |
| Carbon Disulfide | 3000 | Not Detected | 9200 | Not Detected |
| 3-Chloropropene | 12000 | Not Detected | 37000 | Not Detected |
| Methylene Chloride | 3000 | 1300 J | 10000 | 4600 J |
| Methyl tert-butyl ether | 3000 | 350 J | 11000 | 1300 J |
| trans-1,2-Dichloroethene | 3000 | Not Detected | 12000 | Not Detected |
| Hexane | 3000 | 620000 | 10000 | 2200000 |
| 1,1-Dichloroethane | 3000 | Not Detected | 12000 | Not Detected |
| 2-Butanone (Methyl Ethyl Ketone) | 12000 | Not Detected | 35000 | Not Detected |
| cis-1,2-Dichloroethene | 3000 | Not Detected | 12000 | Not Detected |
| Tetrahydrofuran | 3000 | Not Detected | 8700 | Not Detected |
| Chloroform | 3000 | Not Detected | 14000 | Not Detected |
| 1,1,1-Trichloroethane | 3000 | Not Detected | 16000 | Not Detected |
| Cyclohexane | 3000 | 120000 | 10000 | 410000 |
| Carbon Tetrachloride | 3000 | Not Detected | 19000 | Not Detected |
| 2,2,4-Trimethylpentane | 3000 | 390000 | 14000 | 1800000 |
| Benzene | 3000 | 34000 | 9400 | 110000 |
| 1,2-Dichloroethane | 3000 | Not Detected | 12000 | Not Detected |
| Heptane | 3000 | 100000 | 12000 | 420000 |
| Trichloroethene | 3000 | Not Detected | 16000 | Not Detected |
| 1,2-Dichloropropane | 3000 | Not Detected | 14000 | Not Detected |
| 1,4-Dioxane | 12000 | Not Detected | 43000 | Not Detected |
| Bromodichloromethane | 3000 | Not Detected | 20000 | Not Detected |
| cis-1,3-Dichloropropene | 3000 | Not Detected | 13000 | Not Detected |
| 4-Methyl-2-pentanone | 3000 | Not Detected | 12000 | Not Detected |
| Toluene | 3000 | 28000 | 11000 | 100000 |
| trans-1,3-Dichloropropene | 3000 | Not Detected | 13000 | Not Detected |
| 1,1,2-Trichloroethane | 3000 | Not Detected | 16000 | Not Detected |
| Tetrachloroethene | 3000 | Not Detected | 20000 | Not Detected |
| 2-Hexanone | 12000 | Not Detected | 48000 | Not Detected |

**Client Sample ID: MainHeader-SVE-01162013**

**Lab ID#: 1301530A-02A**

**EPA METHOD TO-15 GC/MS**

| | | | |
|---|---|---|---|
| **File Name:** | **14013028** | **Date of Collection:** | **1/16/13 9:35:00 AM** |
| **Dil. Factor:** | **592** | **Date of Analysis:** | **1/30/13 10:08 PM** |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Dibromochloromethane | 3000 | Not Detected | 25000 | Not Detected |
| 1,2-Dibromoethane (EDB) | 3000 | Not Detected | 23000 | Not Detected |
| Chlorobenzene | 3000 | Not Detected | 14000 | Not Detected |
| Ethyl Benzene | 3000 | 3100 | 13000 | 14000 |
| m,p-Xylene | 3000 | 5500 | 13000 | 24000 |
| o-Xylene | 3000 | 910 J | 13000 | 4000 J |
| Styrene | 3000 | Not Detected | 13000 | Not Detected |
| Bromoform | 3000 | Not Detected | 31000 | Not Detected |
| Cumene | 3000 | Not Detected | 14000 | Not Detected |
| 1,1,2,2-Tetrachloroethane | 3000 | Not Detected | 20000 | Not Detected |
| Propylbenzene | 3000 | Not Detected | 14000 | Not Detected |
| 4-Ethyltoluene | 3000 | Not Detected | 14000 | Not Detected |
| 1,3,5-Trimethylbenzene | 3000 | Not Detected | 14000 | Not Detected |
| 1,2,4-Trimethylbenzene | 3000 | Not Detected | 14000 | Not Detected |
| 1,3-Dichlorobenzene | 3000 | Not Detected | 18000 | Not Detected |
| 1,4-Dichlorobenzene | 3000 | Not Detected | 18000 | Not Detected |
| alpha-Chlorotoluene | 3000 | Not Detected | 15000 | Not Detected |
| 1,2-Dichlorobenzene | 3000 | Not Detected | 18000 | Not Detected |
| 1,2,4-Trichlorobenzene | 12000 | Not Detected | 88000 | Not Detected |
| Hexachlorobutadiene | 12000 | Not Detected | 130000 | Not Detected |
| Butane | 12000 | 1800000 | 28000 | 4200000 |
| Isopentane | 12000 | 2300000 | 35000 | 6800000 |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| 1,2-Dichloroethane-d4 | 116 | 70-130 |
| Toluene-d8 | 100 | 70-130 |
| 4-Bromofluorobenzene | 102 | 70-130 |

eurofins | Air Toxics

**Client Sample ID: PWHeader-SVE-01162013**

**Lab ID#: 1301530A-03A**

**EPA METHOD TO-15 GC/MS**

| | | | |
|---|---|---|---|
| **File Name:** | **14013026** | **Date of Collection:** | **1/16/13 9:30:00 AM** |
| **Dil. Factor:** | **296** | **Date of Analysis:** | **1/30/13 09:19 PM** |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 1500 | Not Detected | 7300 | Not Detected |
| Freon 114 | 1500 | Not Detected | 10000 | Not Detected |
| Chloromethane | 5900 | Not Detected | 12000 | Not Detected |
| Vinyl Chloride | 1500 | Not Detected | 3800 | Not Detected |
| 1,3-Butadiene | 1500 | Not Detected | 3300 | Not Detected |
| Bromomethane | 1500 | Not Detected | 5700 | Not Detected |
| Chloroethane | 5900 | Not Detected | 16000 | Not Detected |
| Freon 11 | 1500 | Not Detected | 8300 | Not Detected |
| Ethanol | 5900 | Not Detected | 11000 | Not Detected |
| Freon 113 | 1500 | Not Detected | 11000 | Not Detected |
| 1,1-Dichloroethene | 1500 | Not Detected | 5900 | Not Detected |
| Acetone | 5900 | Not Detected | 14000 | Not Detected |
| 2-Propanol | 5900 | Not Detected | 14000 | Not Detected |
| Carbon Disulfide | 1500 | Not Detected | 4600 | Not Detected |
| 3-Chloropropene | 5900 | Not Detected | 18000 | Not Detected |
| Methylene Chloride | 1500 | 480 J | 5100 | 1600 J |
| Methyl tert-butyl ether | 1500 | Not Detected | 5300 | Not Detected |
| trans-1,2-Dichloroethene | 1500 | Not Detected | 5900 | Not Detected |
| Hexane | 1500 | 65000 | 5200 | 230000 |
| 1,1-Dichloroethane | 1500 | Not Detected | 6000 | Not Detected |
| 2-Butanone (Methyl Ethyl Ketone) | 5900 | Not Detected | 17000 | Not Detected |
| cis-1,2-Dichloroethene | 1500 | 420 J | 5900 | 1600 J |
| Tetrahydrofuran | 1500 | Not Detected | 4400 | Not Detected |
| Chloroform | 1500 | Not Detected | 7200 | Not Detected |
| 1,1,1-Trichloroethane | 1500 | Not Detected | 8100 | Not Detected |
| Cyclohexane | 1500 | 14000 | 5100 | 48000 |
| Carbon Tetrachloride | 1500 | Not Detected | 9300 | Not Detected |
| 2,2,4-Trimethylpentane | 1500 | 44000 | 6900 | 210000 |
| Benzene | 1500 | 370000 | 4700 | 1200000 |
| 1,2-Dichloroethane | 1500 | Not Detected | 6000 | Not Detected |
| Heptane | 1500 | 7400 | 6100 | 30000 |
| Trichloroethene | 1500 | 350 J | 8000 | 1900 J |
| 1,2-Dichloropropane | 1500 | Not Detected | 6800 | Not Detected |
| 1,4-Dioxane | 5900 | Not Detected | 21000 | Not Detected |
| Bromodichloromethane | 1500 | Not Detected | 9900 | Not Detected |
| cis-1,3-Dichloropropene | 1500 | Not Detected | 6700 | Not Detected |
| 4-Methyl-2-pentanone | 1500 | Not Detected | 6100 | Not Detected |
| Toluene | 1500 | 320 J | 5600 | 1200 J |
| trans-1,3-Dichloropropene | 1500 | Not Detected | 6700 | Not Detected |
| 1,1,2-Trichloroethane | 1500 | Not Detected | 8100 | Not Detected |
| Tetrachloroethene | 1500 | 3500 | 10000 | 24000 |
| 2-Hexanone | 5900 | Not Detected | 24000 | Not Detected |

eurofins | Air Toxics

**Client Sample ID: PWHeader-SVE-01162013**

**Lab ID#: 1301530A-03A**

**EPA METHOD TO-15 GC/MS**

| | | | |
|---|---|---|---|
| **File Name:** | **14013026** | **Date of Collection: 1/16/13 9:30:00 AM** | |
| **Dil. Factor:** | **296** | **Date of Analysis: 1/30/13 09:19 PM** | |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Dibromochloromethane | 1500 | Not Detected | 13000 | Not Detected |
| 1,2-Dibromoethane (EDB) | 1500 | Not Detected | 11000 | Not Detected |
| Chlorobenzene | 1500 | Not Detected | 6800 | Not Detected |
| Ethyl Benzene | 1500 | Not Detected | 6400 | Not Detected |
| m,p-Xylene | 1500 | Not Detected | 6400 | Not Detected |
| o-Xylene | 1500 | Not Detected | 6400 | Not Detected |
| Styrene | 1500 | Not Detected | 6300 | Not Detected |
| Bromoform | 1500 | Not Detected | 15000 | Not Detected |
| Cumene | 1500 | Not Detected | 7300 | Not Detected |
| 1,1,2,2-Tetrachloroethane | 1500 | Not Detected | 10000 | Not Detected |
| Propylbenzene | 1500 | Not Detected | 7300 | Not Detected |
| 4-Ethyltoluene | 1500 | Not Detected | 7300 | Not Detected |
| 1,3,5-Trimethylbenzene | 1500 | Not Detected | 7300 | Not Detected |
| 1,2,4-Trimethylbenzene | 1500 | Not Detected | 7300 | Not Detected |
| 1,3-Dichlorobenzene | 1500 | Not Detected | 8900 | Not Detected |
| 1,4-Dichlorobenzene | 1500 | Not Detected | 8900 | Not Detected |
| alpha-Chlorotoluene | 1500 | Not Detected | 7700 | Not Detected |
| 1,2-Dichlorobenzene | 1500 | Not Detected | 8900 | Not Detected |
| 1,2,4-Trichlorobenzene | 5900 | Not Detected | 44000 | Not Detected |
| Hexachlorobutadiene | 5900 | Not Detected | 63000 | Not Detected |
| Butane | 5900 | 420000 | 14000 | 990000 |
| Isopentane | 5900 | 780000 | 17000 | 2300000 |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| 1,2-Dichloroethane-d4 | 117 | 70-130 |
| Toluene-d8 | 98 | 70-130 |
| 4-Bromofluorobenzene | 103 | 70-130 |

**Client Sample ID: Lab Blank**

**Lab ID#: 1301530A-04A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p013009a** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 1/30/13 01:41 PM** | |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 0.50 | Not Detected | 2.5 | Not Detected |
| Freon 114 | 0.50 | Not Detected | 3.5 | Not Detected |
| Chloromethane | 5.0 | Not Detected | 10 | Not Detected |
| Vinyl Chloride | 0.50 | Not Detected | 1.3 | Not Detected |
| 1,3-Butadiene | 0.50 | Not Detected | 1.1 | Not Detected |
| Bromomethane | 5.0 | 0.26 J | 19 | 1.0 J |
| Chloroethane | 2.0 | Not Detected | 5.3 | Not Detected |
| Freon 11 | 0.50 | Not Detected | 2.8 | Not Detected |
| Ethanol | 2.0 | 0.61 J | 3.8 | 1.1 J |
| Freon 113 | 0.50 | Not Detected | 3.8 | Not Detected |
| 1,1-Dichloroethene | 0.50 | Not Detected | 2.0 | Not Detected |
| Acetone | 5.0 | Not Detected | 12 | Not Detected |
| 2-Propanol | 2.0 | Not Detected | 4.9 | Not Detected |
| Carbon Disulfide | 2.0 | 0.34 J | 6.2 | 1.1 J |
| 3-Chloropropene | 2.0 | Not Detected | 6.3 | Not Detected |
| Methylene Chloride | 5.0 | 0.25 J | 17 | 0.88 J |
| Methyl tert-butyl ether | 0.50 | Not Detected | 1.8 | Not Detected |
| trans-1,2-Dichloroethene | 0.50 | Not Detected | 2.0 | Not Detected |
| Hexane | 0.50 | Not Detected | 1.8 | Not Detected |
| 1,1-Dichloroethane | 0.50 | Not Detected | 2.0 | Not Detected |
| 2-Butanone (Methyl Ethyl Ketone) | 2.0 | Not Detected | 5.9 | Not Detected |
| cis-1,2-Dichloroethene | 0.50 | Not Detected | 2.0 | Not Detected |
| Tetrahydrofuran | 0.50 | Not Detected | 1.5 | Not Detected |
| Chloroform | 0.50 | Not Detected | 2.4 | Not Detected |
| 1,1,1-Trichloroethane | 0.50 | Not Detected | 2.7 | Not Detected |
| Cyclohexane | 0.50 | Not Detected | 1.7 | Not Detected |
| Carbon Tetrachloride | 0.50 | Not Detected | 3.1 | Not Detected |
| 2,2,4-Trimethylpentane | 0.50 | 0.15 J | 2.3 | 0.71 J |
| Benzene | 0.50 | Not Detected | 1.6 | Not Detected |
| 1,2-Dichloroethane | 0.50 | Not Detected | 2.0 | Not Detected |
| Heptane | 0.50 | Not Detected | 2.0 | Not Detected |
| Trichloroethene | 0.50 | Not Detected | 2.7 | Not Detected |
| 1,2-Dichloropropane | 0.50 | Not Detected | 2.3 | Not Detected |
| 1,4-Dioxane | 2.0 | Not Detected | 7.2 | Not Detected |
| Bromodichloromethane | 0.50 | Not Detected | 3.4 | Not Detected |
| cis-1,3-Dichloropropene | 0.50 | Not Detected | 2.3 | Not Detected |
| 4-Methyl-2-pentanone | 0.50 | Not Detected | 2.0 | Not Detected |
| Toluene | 0.50 | 0.060 J | 1.9 | 0.23 J |
| trans-1,3-Dichloropropene | 0.50 | Not Detected | 2.3 | Not Detected |
| 1,1,2-Trichloroethane | 0.50 | Not Detected | 2.7 | Not Detected |
| Tetrachloroethene | 0.50 | Not Detected | 3.4 | Not Detected |
| 2-Hexanone | 2.0 | Not Detected | 8.2 | Not Detected |

eurofins | Air Toxics

**Client Sample ID: Lab Blank**

**Lab ID#: 1301530A-04A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p013009a** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 1/30/13 01:41 PM** | |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Dibromochloromethane | 0.50 | Not Detected | 4.2 | Not Detected |
| 1,2-Dibromoethane (EDB) | 0.50 | Not Detected | 3.8 | Not Detected |
| Chlorobenzene | 0.50 | Not Detected | 2.3 | Not Detected |
| Ethyl Benzene | 0.50 | Not Detected | 2.2 | Not Detected |
| m,p-Xylene | 0.50 | Not Detected | 2.2 | Not Detected |
| o-Xylene | 0.50 | Not Detected | 2.2 | Not Detected |
| Styrene | 0.50 | Not Detected | 2.1 | Not Detected |
| Bromoform | 0.50 | Not Detected | 5.2 | Not Detected |
| Cumene | 0.50 | Not Detected | 2.4 | Not Detected |
| 1,1,2,2-Tetrachloroethane | 0.50 | Not Detected | 3.4 | Not Detected |
| Propylbenzene | 0.50 | Not Detected | 2.4 | Not Detected |
| 4-Ethyltoluene | 0.50 | Not Detected | 2.4 | Not Detected |
| 1,3,5-Trimethylbenzene | 0.50 | Not Detected | 2.4 | Not Detected |
| 1,2,4-Trimethylbenzene | 0.50 | Not Detected | 2.4 | Not Detected |
| 1,3-Dichlorobenzene | 0.50 | 0.11 J | 3.0 | 0.66 J |
| 1,4-Dichlorobenzene | 0.50 | 0.096 J | 3.0 | 0.58 J |
| alpha-Chlorotoluene | 0.50 | Not Detected | 2.6 | Not Detected |
| 1,2-Dichlorobenzene | 0.50 | Not Detected | 3.0 | Not Detected |
| 1,2,4-Trichlorobenzene | 2.0 | 0.33 J | 15 | 2.4 J |
| Hexachlorobutadiene | 2.0 | Not Detected | 21 | Not Detected |
| Butane | 2.0 | Not Detected | 4.8 | Not Detected |
| Isopentane | 2.0 | Not Detected | 5.9 | Not Detected |

J = Estimated value.

**Container Type: NA - Not Applicable**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| Toluene-d8 | 101 | 70-130 |
| 1,2-Dichloroethane-d4 | 99 | 70-130 |
| 4-Bromofluorobenzene | 84 | 70-130 |

eurofins | Air Toxics

**Client Sample ID: Lab Blank**

**Lab ID#: 1301530A-04B**

**EPA METHOD TO-15 GC/MS**

| | | | |
|---|---|---|---|
| **File Name:** | **14013005a** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 1/30/13 10:23 AM** | |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 5.0 | Not Detected | 25 | Not Detected |
| Freon 114 | 5.0 | Not Detected | 35 | Not Detected |
| Chloromethane | 20 | Not Detected | 41 | Not Detected |
| Vinyl Chloride | 5.0 | Not Detected | 13 | Not Detected |
| 1,3-Butadiene | 5.0 | Not Detected | 11 | Not Detected |
| Bromomethane | 5.0 | Not Detected | 19 | Not Detected |
| Chloroethane | 20 | Not Detected | 53 | Not Detected |
| Freon 11 | 5.0 | Not Detected | 28 | Not Detected |
| Ethanol | 20 | Not Detected | 38 | Not Detected |
| Freon 113 | 5.0 | Not Detected | 38 | Not Detected |
| 1,1-Dichloroethene | 5.0 | Not Detected | 20 | Not Detected |
| Acetone | 20 | Not Detected | 48 | Not Detected |
| 2-Propanol | 20 | Not Detected | 49 | Not Detected |
| Carbon Disulfide | 5.0 | Not Detected | 16 | Not Detected |
| 3-Chloropropene | 20 | Not Detected | 63 | Not Detected |
| Methylene Chloride | 5.0 | 1.0 J | 17 | 3.6 J |
| Methyl tert-butyl ether | 5.0 | Not Detected | 18 | Not Detected |
| trans-1,2-Dichloroethene | 5.0 | Not Detected | 20 | Not Detected |
| Hexane | 5.0 | Not Detected | 18 | Not Detected |
| 1,1-Dichloroethane | 5.0 | Not Detected | 20 | Not Detected |
| 2-Butanone (Methyl Ethyl Ketone) | 20 | Not Detected | 59 | Not Detected |
| cis-1,2-Dichloroethene | 5.0 | Not Detected | 20 | Not Detected |
| Tetrahydrofuran | 5.0 | Not Detected | 15 | Not Detected |
| Chloroform | 5.0 | Not Detected | 24 | Not Detected |
| 1,1,1-Trichloroethane | 5.0 | Not Detected | 27 | Not Detected |
| Cyclohexane | 5.0 | Not Detected | 17 | Not Detected |
| Carbon Tetrachloride | 5.0 | Not Detected | 31 | Not Detected |
| 2,2,4-Trimethylpentane | 5.0 | Not Detected | 23 | Not Detected |
| Benzene | 5.0 | Not Detected | 16 | Not Detected |
| 1,2-Dichloroethane | 5.0 | Not Detected | 20 | Not Detected |
| Heptane | 5.0 | Not Detected | 20 | Not Detected |
| Trichloroethene | 5.0 | Not Detected | 27 | Not Detected |
| 1,2-Dichloropropane | 5.0 | Not Detected | 23 | Not Detected |
| 1,4-Dioxane | 20 | Not Detected | 72 | Not Detected |
| Bromodichloromethane | 5.0 | Not Detected | 34 | Not Detected |
| cis-1,3-Dichloropropene | 5.0 | Not Detected | 23 | Not Detected |
| 4-Methyl-2-pentanone | 5.0 | Not Detected | 20 | Not Detected |
| Toluene | 5.0 | Not Detected | 19 | Not Detected |
| trans-1,3-Dichloropropene | 5.0 | Not Detected | 23 | Not Detected |
| 1,1,2-Trichloroethane | 5.0 | Not Detected | 27 | Not Detected |
| Tetrachloroethene | 5.0 | Not Detected | 34 | Not Detected |
| 2-Hexanone | 20 | Not Detected | 82 | Not Detected |

eurofins | Air Toxics

**Client Sample ID: Lab Blank**

**Lab ID#: 1301530A-04B**

**EPA METHOD TO-15 GC/MS**

| | | | |
|---|---|---|---|
| **File Name:** | **14013005a** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 1/30/13 10:23 AM** | |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Dibromochloromethane | 5.0 | Not Detected | 42 | Not Detected |
| 1,2-Dibromoethane (EDB) | 5.0 | Not Detected | 38 | Not Detected |
| Chlorobenzene | 5.0 | Not Detected | 23 | Not Detected |
| Ethyl Benzene | 5.0 | Not Detected | 22 | Not Detected |
| m,p-Xylene | 5.0 | Not Detected | 22 | Not Detected |
| o-Xylene | 5.0 | Not Detected | 22 | Not Detected |
| Styrene | 5.0 | Not Detected | 21 | Not Detected |
| Bromoform | 5.0 | Not Detected | 52 | Not Detected |
| Cumene | 5.0 | Not Detected | 24 | Not Detected |
| 1,1,2,2-Tetrachloroethane | 5.0 | Not Detected | 34 | Not Detected |
| Propylbenzene | 5.0 | Not Detected | 24 | Not Detected |
| 4-Ethyltoluene | 5.0 | Not Detected | 24 | Not Detected |
| 1,3,5-Trimethylbenzene | 5.0 | Not Detected | 24 | Not Detected |
| 1,2,4-Trimethylbenzene | 5.0 | Not Detected | 24 | Not Detected |
| 1,3-Dichlorobenzene | 5.0 | Not Detected | 30 | Not Detected |
| 1,4-Dichlorobenzene | 5.0 | 1.0 J | 30 | 6.4 J |
| alpha-Chlorotoluene | 5.0 | 1.0 J | 26 | 5.4 J |
| 1,2-Dichlorobenzene | 5.0 | Not Detected | 30 | Not Detected |
| 1,2,4-Trichlorobenzene | 20 | 12 J | 150 | 86 J |
| Hexachlorobutadiene | 20 | 13 J | 210 | 140 J |
| Butane | 20 | Not Detected | 48 | Not Detected |
| Isopentane | 20 | Not Detected | 59 | Not Detected |

J = Estimated value.

**Container Type: NA - Not Applicable**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| 1,2-Dichloroethane-d4 | 111 | 70-130 |
| Toluene-d8 | 98 | 70-130 |
| 4-Bromofluorobenzene | 101 | 70-130 |

eurofins | Air Toxics

**Client Sample ID: CCV**

**Lab ID#: 1301530A-05A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p013002** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 1/30/13 09:08 AM** | |

| Compound | %Recovery |
|---|---|
| Freon 12 | 98 |
| Freon 114 | 98 |
| Chloromethane | 97 |
| Vinyl Chloride | 100 |
| 1,3-Butadiene | 99 |
| Bromomethane | 99 |
| Chloroethane | 99 |
| Freon 11 | 100 |
| Ethanol | 107 |
| Freon 113 | 98 |
| 1,1-Dichloroethene | 99 |
| Acetone | 96 |
| 2-Propanol | 100 |
| Carbon Disulfide | 95 |
| 3-Chloropropene | 95 |
| Methylene Chloride | 99 |
| Methyl tert-butyl ether | 107 |
| trans-1,2-Dichloroethene | 106 |
| Hexane | 108 |
| 1,1-Dichloroethane | 100 |
| 2-Butanone (Methyl Ethyl Ketone) | 103 |
| cis-1,2-Dichloroethene | 102 |
| Tetrahydrofuran | 109 |
| Chloroform | 100 |
| 1,1,1-Trichloroethane | 101 |
| Cyclohexane | 110 |
| Carbon Tetrachloride | 102 |
| 2,2,4-Trimethylpentane | 113 |
| Benzene | 105 |
| 1,2-Dichloroethane | 109 |
| Heptane | 116 |
| Trichloroethene | 91 |
| 1,2-Dichloropropane | 104 |
| 1,4-Dioxane | 114 |
| Bromodichloromethane | 106 |
| cis-1,3-Dichloropropene | 110 |
| 4-Methyl-2-pentanone | 118 |
| Toluene | 107 |
| trans-1,3-Dichloropropene | 119 |
| 1,1,2-Trichloroethane | 106 |
| Tetrachloroethene | 105 |
| 2-Hexanone | 115 |

eurofins | Air Toxics

**Client Sample ID: CCV**

**Lab ID#: 1301530A-05A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p013002** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 1/30/13 09:08 AM** | |

| Compound | %Recovery |
|---|---|
| Dibromochloromethane | 112 |
| 1,2-Dibromoethane (EDB) | 112 |
| Chlorobenzene | 102 |
| Ethyl Benzene | 117 |
| m,p-Xylene | 120 |
| o-Xylene | 121 |
| Styrene | 126 |
| Bromoform | 113 |
| Cumene | 124 |
| 1,1,2,2-Tetrachloroethane | 122 |
| Propylbenzene | 120 |
| 4-Ethyltoluene | 122 |
| 1,3,5-Trimethylbenzene | 125 |
| 1,2,4-Trimethylbenzene | 124 |
| 1,3-Dichlorobenzene | 112 |
| 1,4-Dichlorobenzene | 115 |
| alpha-Chlorotoluene | 123 |
| 1,2-Dichlorobenzene | 115 |
| 1,2,4-Trichlorobenzene | 110 |
| Hexachlorobutadiene | 109 |
| Butane | 98 |
| Isopentane | 99 |

**Container Type: NA - Not Applicable**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| Toluene-d8 | 107 | 70-130 |
| 1,2-Dichloroethane-d4 | 100 | 70-130 |
| 4-Bromofluorobenzene | 97 | 70-130 |

eurofins | Air Toxics

**Client Sample ID: CCV**

**Lab ID#: 1301530A-05B**

**EPA METHOD TO-15 GC/MS**

| | | | |
|---|---|---|---|
| **File Name:** | **14013002** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 1/30/13 09:17 AM** | |

| Compound | %Recovery |
|---|---|
| Freon 12 | 116 |
| Freon 114 | 117 |
| Chloromethane | 127 |
| Vinyl Chloride | 109 |
| 1,3-Butadiene | 112 |
| Bromomethane | 116 |
| Chloroethane | 111 |
| Freon 11 | 120 |
| Ethanol | 138 Q |
| Freon 113 | 106 |
| 1,1-Dichloroethene | 114 |
| Acetone | 109 |
| 2-Propanol | 119 |
| Carbon Disulfide | 94 |
| 3-Chloropropene | 96 |
| Methylene Chloride | 113 |
| Methyl tert-butyl ether | 104 |
| trans-1,2-Dichloroethene | 110 |
| Hexane | 107 |
| 1,1-Dichloroethane | 109 |
| 2-Butanone (Methyl Ethyl Ketone) | 104 |
| cis-1,2-Dichloroethene | 106 |
| Tetrahydrofuran | 116 |
| Chloroform | 111 |
| 1,1,1-Trichloroethane | 106 |
| Cyclohexane | 104 |
| Carbon Tetrachloride | 116 |
| 2,2,4-Trimethylpentane | 109 |
| Benzene | 106 |
| 1,2-Dichloroethane | 119 |
| Heptane | 105 |
| Trichloroethene | 106 |
| 1,2-Dichloropropane | 105 |
| 1,4-Dioxane | 111 |
| Bromodichloromethane | 110 |
| cis-1,3-Dichloropropene | 99 |
| 4-Methyl-2-pentanone | 111 |
| Toluene | 101 |
| trans-1,3-Dichloropropene | 100 |
| 1,1,2-Trichloroethane | 108 |
| Tetrachloroethene | 108 |
| 2-Hexanone | 116 |

**Client Sample ID: CCV**

**Lab ID#: 1301530A-05B**

**EPA METHOD TO-15 GC/MS**

| | | | |
|---|---|---|---|
| **File Name:** | **14013002** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 1/30/13 09:17 AM** | |

| Compound | %Recovery |
|---|---|
| Dibromochloromethane | 112 |
| 1,2-Dibromoethane (EDB) | 110 |
| Chlorobenzene | 106 |
| Ethyl Benzene | 104 |
| m,p-Xylene | 108 |
| o-Xylene | 106 |
| Styrene | 113 |
| Bromoform | 114 |
| Cumene | 111 |
| 1,1,2,2-Tetrachloroethane | 112 |
| Propylbenzene | 112 |
| 4-Ethyltoluene | 116 |
| 1,3,5-Trimethylbenzene | 119 |
| 1,2,4-Trimethylbenzene | 112 |
| 1,3-Dichlorobenzene | 110 |
| 1,4-Dichlorobenzene | 108 |
| alpha-Chlorotoluene | 109 |
| 1,2-Dichlorobenzene | 115 |
| 1,2,4-Trichlorobenzene | 108 |
| Hexachlorobutadiene | 115 |
| Butane | 118 |
| Isopentane | 119 |

Q = Exceeds Quality Control limits.

**Container Type: NA - Not Applicable**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| 1,2-Dichloroethane-d4 | 107 | 70-130 |
| Toluene-d8 | 101 | 70-130 |
| 4-Bromofluorobenzene | 105 | 70-130 |

eurofins | Air Toxics

**Client Sample ID: LCS**

**Lab ID#: 1301530A-06A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p013003** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 1/30/13 09:39 AM** | |

| Compound | %Recovery |
|---|---|
| Freon 12 | 105 |
| Freon 114 | 106 |
| Chloromethane | 104 |
| Vinyl Chloride | 111 |
| 1,3-Butadiene | 111 |
| Bromomethane | 103 |
| Chloroethane | 107 |
| Freon 11 | 104 |
| Ethanol | 89 |
| Freon 113 | 106 |
| 1,1-Dichloroethene | 112 |
| Acetone | 105 |
| 2-Propanol | 108 |
| Carbon Disulfide | 125 |
| 3-Chloropropene | 126 |
| Methylene Chloride | 104 |
| Methyl tert-butyl ether | 112 |
| trans-1,2-Dichloroethene | 127 |
| Hexane | 115 |
| 1,1-Dichloroethane | 107 |
| 2-Butanone (Methyl Ethyl Ketone) | 114 |
| cis-1,2-Dichloroethene | 109 |
| Tetrahydrofuran | 113 |
| Chloroform | 106 |
| 1,1,1-Trichloroethane | 108 |
| Cyclohexane | 119 |
| Carbon Tetrachloride | 108 |
| 2,2,4-Trimethylpentane | 118 |
| Benzene | 108 |
| 1,2-Dichloroethane | 107 |
| Heptane | 116 |
| Trichloroethene | 92 |
| 1,2-Dichloropropane | 108 |
| 1,4-Dioxane | 118 |
| Bromodichloromethane | 106 |
| cis-1,3-Dichloropropene | 112 |
| 4-Methyl-2-pentanone | 128 |
| Toluene | 107 |
| trans-1,3-Dichloropropene | 122 |
| 1,1,2-Trichloroethane | 107 |
| Tetrachloroethene | 108 |
| 2-Hexanone | 123 |

eurofins | Air Toxics

**Client Sample ID: LCS**

**Lab ID#: 1301530A-06A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p013003** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 1/30/13 09:39 AM** | |

| Compound | %Recovery |
|---|---|
| Dibromochloromethane | 110 |
| 1,2-Dibromoethane (EDB) | 114 |
| Chlorobenzene | 108 |
| Ethyl Benzene | 119 |
| m,p-Xylene | 125 |
| o-Xylene | 124 |
| Styrene | 130 |
| Bromoform | 111 |
| Cumene | 129 |
| 1,1,2,2-Tetrachloroethane | 128 |
| Propylbenzene | 124 |
| 4-Ethyltoluene | 122 |
| 1,3,5-Trimethylbenzene | 128 |
| 1,2,4-Trimethylbenzene | 127 |
| 1,3-Dichlorobenzene | 117 |
| 1,4-Dichlorobenzene | 120 |
| alpha-Chlorotoluene | 124 |
| 1,2-Dichlorobenzene | 121 |
| 1,2,4-Trichlorobenzene | 125 |
| Hexachlorobutadiene | 120 |
| Butane | 107 |
| Isopentane | 105 |

**Container Type: NA - Not Applicable**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| Toluene-d8 | 106 | 70-130 |
| 1,2-Dichloroethane-d4 | 101 | 70-130 |
| 4-Bromofluorobenzene | 94 | 70-130 |

eurofins | Air Toxics

**Client Sample ID: LCSD**

**Lab ID#: 1301530A-06AA**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p013004** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 1/30/13 10:01 AM** | |

| Compound | %Recovery |
|---|---|
| Freon 12 | 101 |
| Freon 114 | 101 |
| Chloromethane | 100 |
| Vinyl Chloride | 106 |
| 1,3-Butadiene | 105 |
| Bromomethane | 101 |
| Chloroethane | 104 |
| Freon 11 | 99 |
| Ethanol | 83 |
| Freon 113 | 102 |
| 1,1-Dichloroethene | 111 |
| Acetone | 101 |
| 2-Propanol | 106 |
| Carbon Disulfide | 122 |
| 3-Chloropropene | 119 |
| Methylene Chloride | 100 |
| Methyl tert-butyl ether | 108 |
| trans-1,2-Dichloroethene | 120 |
| Hexane | 112 |
| 1,1-Dichloroethane | 104 |
| 2-Butanone (Methyl Ethyl Ketone) | 106 |
| cis-1,2-Dichloroethene | 108 |
| Tetrahydrofuran | 112 |
| Chloroform | 103 |
| 1,1,1-Trichloroethane | 103 |
| Cyclohexane | 115 |
| Carbon Tetrachloride | 102 |
| 2,2,4-Trimethylpentane | 114 |
| Benzene | 107 |
| 1,2-Dichloroethane | 103 |
| Heptane | 115 |
| Trichloroethene | 90 |
| 1,2-Dichloropropane | 104 |
| 1,4-Dioxane | 116 |
| Bromodichloromethane | 103 |
| cis-1,3-Dichloropropene | 113 |
| 4-Methyl-2-pentanone | 122 |
| Toluene | 105 |
| trans-1,3-Dichloropropene | 120 |
| 1,1,2-Trichloroethane | 106 |
| Tetrachloroethene | 105 |
| 2-Hexanone | 121 |

eurofins | Air Toxics

**Client Sample ID: LCSD**

**Lab ID#: 1301530A-06AA**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p013004** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 1/30/13 10:01 AM** | |

| Compound | %Recovery |
|---|---|
| Dibromochloromethane | 109 |
| 1,2-Dibromoethane (EDB) | 114 |
| Chlorobenzene | 107 |
| Ethyl Benzene | 118 |
| m,p-Xylene | 123 |
| o-Xylene | 122 |
| Styrene | 127 |
| Bromoform | 110 |
| Cumene | 127 |
| 1,1,2,2-Tetrachloroethane | 126 |
| Propylbenzene | 121 |
| 4-Ethyltoluene | 120 |
| 1,3,5-Trimethylbenzene | 127 |
| 1,2,4-Trimethylbenzene | 124 |
| 1,3-Dichlorobenzene | 117 |
| 1,4-Dichlorobenzene | 118 |
| alpha-Chlorotoluene | 123 |
| 1,2-Dichlorobenzene | 120 |
| 1,2,4-Trichlorobenzene | 125 |
| Hexachlorobutadiene | 118 |
| Butane | 99 |
| Isopentane | 102 |

**Container Type: NA - Not Applicable**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| Toluene-d8 | 105 | 70-130 |
| 1,2-Dichloroethane-d4 | 97 | 70-130 |
| 4-Bromofluorobenzene | 93 | 70-130 |

eurofins | Air Toxics

**Client Sample ID: LCS**
**Lab ID#: 1301530A-06B**
**EPA METHOD TO-15 GC/MS**

| | | | |
|---|---|---|---|
| **File Name:** | **14013003** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 1/30/13 09:40 AM** | |

| Compound | %Recovery |
|---|---|
| Freon 12 | 101 |
| Freon 114 | 99 |
| Chloromethane | 112 |
| Vinyl Chloride | 93 |
| 1,3-Butadiene | 98 |
| Bromomethane | 97 |
| Chloroethane | 92 |
| Freon 11 | 103 |
| Ethanol | 98 |
| Freon 113 | 94 |
| 1,1-Dichloroethene | 110 |
| Acetone | 93 |
| 2-Propanol | 96 |
| Carbon Disulfide | 99 |
| 3-Chloropropene | 89 |
| Methylene Chloride | 98 |
| Methyl tert-butyl ether | 85 |
| trans-1,2-Dichloroethene | 105 |
| Hexane | 87 |
| 1,1-Dichloroethane | 93 |
| 2-Butanone (Methyl Ethyl Ketone) | 85 |
| cis-1,2-Dichloroethene | 88 |
| Tetrahydrofuran | 93 |
| Chloroform | 98 |
| 1,1,1-Trichloroethane | 91 |
| Cyclohexane | 87 |
| Carbon Tetrachloride | 96 |
| 2,2,4-Trimethylpentane | 87 |
| Benzene | 92 |
| 1,2-Dichloroethane | 101 |
| Heptane | 85 |
| Trichloroethene | 93 |
| 1,2-Dichloropropane | 90 |
| 1,4-Dioxane | 90 |
| Bromodichloromethane | 92 |
| cis-1,3-Dichloropropene | 81 |
| 4-Methyl-2-pentanone | 84 |
| Toluene | 88 |
| trans-1,3-Dichloropropene | 78 |
| 1,1,2-Trichloroethane | 93 |
| Tetrachloroethene | 92 |
| 2-Hexanone | 80 |

eurofins | Air Toxics

**Client Sample ID: LCS**

**Lab ID#: 1301530A-06B**

**EPA METHOD TO-15 GC/MS**

| | | | |
|---|---|---|---|
| **File Name:** | **14013003** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 1/30/13 09:40 AM** | |

| Compound | %Recovery |
|---|---|
| Dibromochloromethane | 90 |
| 1,2-Dibromoethane (EDB) | 92 |
| Chlorobenzene | 95 |
| Ethyl Benzene | 87 |
| m,p-Xylene | 90 |
| o-Xylene | 88 |
| Styrene | 89 |
| Bromoform | 88 |
| Cumene | 92 |
| 1,1,2,2-Tetrachloroethane | 101 |
| Propylbenzene | 97 |
| 4-Ethyltoluene | 94 |
| 1,3,5-Trimethylbenzene | 101 |
| 1,2,4-Trimethylbenzene | 92 |
| 1,3-Dichlorobenzene | 99 |
| 1,4-Dichlorobenzene | 97 |
| alpha-Chlorotoluene | 81 |
| 1,2-Dichlorobenzene | 102 |
| 1,2,4-Trichlorobenzene | 111 |
| Hexachlorobutadiene | 118 |
| Butane | 98 |
| Isopentane | 97 |

**Container Type: NA - Not Applicable**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| 1,2-Dichloroethane-d4 | 108 | 70-130 |
| Toluene-d8 | 100 | 70-130 |
| 4-Bromofluorobenzene | 104 | 70-130 |

eurofins | Air Toxics

**Client Sample ID: LCSD**
**Lab ID#: 1301530A-06BB**
**EPA METHOD TO-15 GC/MS**

| | | | |
|---|---|---|---|
| **File Name:** | **14013004** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 1/30/13 10:02 AM** | |

| Compound | %Recovery |
|---|---|
| Freon 12 | 102 |
| Freon 114 | 99 |
| Chloromethane | 112 |
| Vinyl Chloride | 92 |
| 1,3-Butadiene | 93 |
| Bromomethane | 96 |
| Chloroethane | 91 |
| Freon 11 | 102 |
| Ethanol | 99 |
| Freon 113 | 91 |
| 1,1-Dichloroethene | 109 |
| Acetone | 91 |
| 2-Propanol | 94 |
| Carbon Disulfide | 99 |
| 3-Chloropropene | 94 |
| Methylene Chloride | 98 |
| Methyl tert-butyl ether | 84 |
| trans-1,2-Dichloroethene | 103 |
| Hexane | 86 |
| 1,1-Dichloroethane | 91 |
| 2-Butanone (Methyl Ethyl Ketone) | 83 |
| cis-1,2-Dichloroethene | 88 |
| Tetrahydrofuran | 90 |
| Chloroform | 94 |
| 1,1,1-Trichloroethane | 90 |
| Cyclohexane | 84 |
| Carbon Tetrachloride | 97 |
| 2,2,4-Trimethylpentane | 88 |
| Benzene | 91 |
| 1,2-Dichloroethane | 101 |
| Heptane | 84 |
| Trichloroethene | 91 |
| 1,2-Dichloropropane | 88 |
| 1,4-Dioxane | 85 |
| Bromodichloromethane | 92 |
| cis-1,3-Dichloropropene | 77 |
| 4-Methyl-2-pentanone | 82 |
| Toluene | 86 |
| trans-1,3-Dichloropropene | 78 |
| 1,1,2-Trichloroethane | 90 |
| Tetrachloroethene | 93 |
| 2-Hexanone | 81 |

eurofins | Air Toxics

**Client Sample ID: LCSD**

**Lab ID#: 1301530A-06BB**

**EPA METHOD TO-15 GC/MS**

| | | | |
|---|---|---|---|
| **File Name:** | **14013004** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 1/30/13 10:02 AM** | |

| Compound | %Recovery |
|---|---|
| Dibromochloromethane | 88 |
| 1,2-Dibromoethane (EDB) | 92 |
| Chlorobenzene | 92 |
| Ethyl Benzene | 86 |
| m,p-Xylene | 89 |
| o-Xylene | 88 |
| Styrene | 88 |
| Bromoform | 87 |
| Cumene | 94 |
| 1,1,2,2-Tetrachloroethane | 99 |
| Propylbenzene | 97 |
| 4-Ethyltoluene | 94 |
| 1,3,5-Trimethylbenzene | 100 |
| 1,2,4-Trimethylbenzene | 92 |
| 1,3-Dichlorobenzene | 99 |
| 1,4-Dichlorobenzene | 100 |
| alpha-Chlorotoluene | 80 |
| 1,2-Dichlorobenzene | 101 |
| 1,2,4-Trichlorobenzene | 107 |
| Hexachlorobutadiene | 114 |
| Butane | 98 |
| Isopentane | 101 |

**Container Type: NA - Not Applicable**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| 1,2-Dichloroethane-d4 | 106 | 70-130 |
| Toluene-d8 | 100 | 70-130 |
| 4-Bromofluorobenzene | 105 | 70-130 |

1301530

# Shell Oil Products Chain Of Custody Record

URS

Air Toxics LTD.
Project Name: Roxana SVE O&M
Project # 21562850.05000
Lab Vendor #

Please Check Appropriate Box:
☑ ENV. SERVICES ☐ MOTIVA RETAIL ☐ SHELL RETAIL
☐ MOTIVA SD&CM ☐ CONSULTANT ☐ LUBES
☐ SHELL PIPELINE ☐ OTHER

Print Bill To Contact Name: Robert Moshegian
INCIDENT # (ENV SERVICES): 9 7 2 1 6 8 4 0 ☐ Check if NO INCIDENT # APPLIES
PO #:
SAP #: 3 4 0 0 6 1
DATE: 29-Jan-13
PAGE: 1 of 1

SAMPLING COMPANY: URS CORPORATION
LOG CODE:
SITE ADDRESS: Street and City: 600 SOUTH CENTRAL AVE – ROXANA
State: IL
G-EDAL G no.:
ADDRESS: 1001 HIGHLANDS PLAZA DRIVE WEST - SUITE 300; ST. LOUIS, MO 63110
EDF DELIVERABLE TO (Name, Company, Office Location): Elizabeth Kunkel, URS, St. Louis
PHONE NO.: 314-743-4179
E-MAIL: elizabeth.kunkel@urs.com
CONSULTANT PROJECT NUMBER: Roxana SVE O&M
Laboratory Address: Air Toxics, LTD 180 Blue Ravine Road, Suite B, Folsom, CA 95630-4719
TELEPHONE: 314-429-0100
FAX: 314-429-0462
Bill To Contact E-MAIL: dave.palmer@urs.com
SAMPLER NAME(S) (PRINT): R. Wigler, T. Carrol

TURNAROUND TIME (CALENDAR DAYS):
☑ STANDARD (14 DAY) ☐ 5 DAYS ☐ 3 DAYS ☐ 2 DAYS ☐ 24 HOURS ☐ RESULTS NEEDED ON WEEKEND

REQUESTED ANALYSIS

☐ LA - RWQCB REPORT FORMAT ☑ UST AGENCY:
DELIVERABLES: ☐ LEVEL 1 ☐ LEVEL 2 ☐ LEVEL 3 ☑ LEVEL 4 ☐ OTHER (SPECIFY)

☑ SHELL CONTRACT RATE APPLIES
☐ STATE REIMBURSEMENT RATE APPLIES
☐ EDD NOT NEEDED
☑ RECEIPT VERIFICATION REQUESTED

Turn Around Time: ☑ Normal ☐ Rush Specify

Lab Use Only
Pressurized by:
Date:
Pressurization Gas: $N_2$ He

| Lab Use Only | Field Sample Identification | SAMPLING DATE | SAMPLING TIME | Canister Number | Canister Pressure/Vacuum Initial | Canister Pressure/Vacuum Final | Canister Pressure/Vacuum Receipt | Canister Pressure/Vacuum Final (psi) | Modified TO-15 + Butane & Isopentane | Modified ASTM D-1946 + BTU | Modified TO-3 (Sh)-TPHg | | Sample PID (ppm) |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| CLK | EXH-SVE-01162013 | 01/16/13 | 925 | 36461 | -29 | -9 | | | X | X | X | | |
| CLK | MainHeader-SVE-01162013 | 01/16/13 | 935 | 37358 | -29 | -9 | | | X | X | X | | |
| CLK | PWHeader-SVE-01162013 | 01/16/13 | 930 | 36535 | -29 | -9 | | | X | X | X | | |
| | | | | | | | | | | | | | |
| | | | | | | | | | | | | | |
| | | | | | | | | | | | | | |
| | | | | | | | | | | | | | |
| | | | | | | | | | | | | | |
| | | | | | | | | | | | | | |
| | | | | | | | | | | | | | |

ADDITIONAL NOTES:
- 14 day hold time
- Report results between MDL and RL
- Level IV ECVP

FedEx
Custody Seal Intact?
(Y) N None Temp NA

1/29/13

| Relinquished by: (Signature) | Received by: (Signature) | Date | Time |
|---|---|---|---|
| | FEDEX | 1/29/13 | 1730 |
| Relinquished by: (Signature) | Received by: (Signature) Kathy Deeks ATL | 01/30/13 | 1050 |
| Relinquished by: (Signature) | Received by: (Signature) | Date: | Time: |

05/2005 Revision

eurofins | Air Toxics

2/12/2013
Ms. Elizabeth Kunkel
URS Corporation
1001 Highlands Plaza Dr. West
Suite 300
St. Louis MO 63110

Project Name: Roxana SVE O&M
Project #: 21562850.05000
Workorder #: 1301530B

Dear Ms. Elizabeth Kunkel

The following report includes the data for the above referenced project for sample(s) received on 1/30/2013 at Air Toxics Ltd.

The data and associated QC analyzed by Modified TO-3 are compliant with the project requirements or laboratory criteria with the exception of the deviations noted in the attached case narrative.

Thank you for choosing Air Toxics Ltd. for your air analysis needs. Air Toxics Ltd. is committed to providing accurate data of the highest quality. Please feel free to contact the Project Manager: Kelly Buettner at 916-985-1000 if you have any questions regarding the data in this report.

Regards,

Kelly Buettner

Project Manager

Reviewed
on
2/25/2013

eurofins | Air Toxics

# WORK ORDER #: 1301530B

Work Order Summary

| | | | |
|---|---|---|---|
| **CLIENT:** | Ms. Elizabeth Kunkel<br>URS Corporation<br>1001 Highlands Plaza Dr. West<br>Suite 300<br>St. Louis, MO 63110 | **BILL TO:** | Accounts Payable Austin<br>URS Corporation<br>P.O. BOX 203970<br>Austin, TX 78720-1088 |
| **PHONE:** | 314-743-4179 | **P.O. #** | |
| **FAX:** | | **PROJECT #** | 21562850.05000 Roxana SVE O&M |
| **DATE RECEIVED:** | 01/30/2013 | **CONTACT:** | Kelly Buettner |
| **DATE COMPLETED:** | 02/12/2013 | | |

| FRACTION # | NAME | TEST | RECEIPT VAC./PRES. | FINAL PRESSURE |
|---|---|---|---|---|
| 01A | EXH-SVE-01162013 | Modified TO-3 | 8.5 "Hg | 15 psi |
| 02A | MainHeader-SVE-01162013 | Modified TO-3 | 9.5 "Hg | 15 psi |
| 03A | PWHeader-SVE-01162013 | Modified TO-3 | 9.5 "Hg | 15 psi |
| 04A | Lab Blank | Modified TO-3 | NA | NA |
| 05A | LCS | Modified TO-3 | NA | NA |
| 05AA | LCSD | Modified TO-3 | NA | NA |

CERTIFIED BY: Heidi Hayes DATE: 02/12/13

Technical Director

Certification numbers: AZ Licensure AZ0775, CA NELAP - 12282CA, NY NELAP - 11291,
TX NELAP - T104704434-12-4, UT NELAP CA009332012-3, WA NELAP - C935
Name of Accrediting Agency: NELAP/ORELAP (Oregon Environmental Laboratory Accreditation Program)
Accreditation number: CA300005, Effective date: 10/18/2012, Expiration date: 10/17/2013.
Eurofins Air Toxics Ltd. certifies that the test results contained in this report meet all requirements of the NELAC standards

This report shall not be reproduced, except in full, without the written approval of Eurofins Air Toxics, Inc.

180 BLUE RAVINE ROAD, SUITE B FOLSOM, CA - 9563
(916) 985-1000 . (800) 985-5955 . FAX (916) 985-1020

**LABORATORY NARRATIVE**
**Modified TO-3**
**URS Corporation**
**Workorder# 1301530B**

Three 1 Liter Summa Canister samples were received on January 30, 2013. The laboratory performed analysis for volatile organic compounds in air via modified EPA Method TO-3 using gas chromatography with flame ionization detection. The TPH results are calculated using the response of Gasoline. A molecular weight of 100 is used to convert the TPH ppmv result to ug/L. The method involves concentrating up to 200 mL of sample. The concentrated aliquot is then dry purged to remove water vapor prior to entering the chromatographic system.

Method modifications taken to run these samples are summarized in the table below. Specific project requirements may over-ride the ATL modifications.

| *Requirement* | *TO-3* | *ATL Modifications* |
|---|---|---|
| Daily Calibration Standard Frequency | Prior to sample analysis and every 4 - 6 hrs | Prior to sample analysis and after the analytical batch </= 20 samples. |
| Initial Calibration Calculation | 4-point calibration using a linear regression model | 5-point calibration using average Response Factor |
| Initial Calibration Frequency | Weekly | When daily calibration standard recovery is outside 75 - 125 %, or upon significant changes to procedure or instrumentation |
| Moisture Control | Nafion system | Sorbent system |
| Minimum Detection Limit (MDL) | Calculated using the equation DL = A+3.3S, where A is intercept of calibration line and S is the standard deviation of at least 3 reps of low level standard | 40 CFR Pt. 136 App. B |
| Preparation of Standards | Levels achieved through dilution of gas mixture | Levels achieved through loading various volumes of the gas mixture |

**Receiving Notes**

There were no receiving discrepancies.

**Analytical Notes**

The recovery of surrogate Fluorobenzene in sample MainHeader-SVE-01162013 was outside control limits due to high level hydrocarbon matrix interference. Data is reported as qualified.

As per project specific client request the laboratory has reported estimated values for target compound hits that are below the Reporting Limit but greater than the Method Detection Limit. Concentrations that are below the level at which the canister was certified may be false positives.

**Definition of Data Qualifying Flags**

Seven qualifiers may have been used on the data analysis sheets and indicate as follows:
B - Compound present in laboratory blank greater than reporting limit.
J - Estimated value.
E - Exceeds instrument calibration range.
S - Saturated peak.
Q - Exceeds quality control limits.
U - Compound analyzed for but not detected above the deteetion limit.
M - Reported value may be biased due to apparent matrix interferences.

File extensions may have been used on the data analysis sheets and indicates as follows:
a-File was requantified
b-File was quantified by a second eolumn and detector
r1-File was requantified for the purpose of reissue

eurofins | Air Toxics

# Summary of Detected Compounds
# MODIFIED EPA METHOD TO-3 GC/FID

**Client Sample ID: EXH-SVE-01162013**

**Lab ID#: 1301530B-01A**

| Compound | Rpt. Limit (ppmv) | Rpt. Limit (ug/L) | Amount (ppmv) | Amount (ug/L) |
|---|---|---|---|---|
| TPH (C2-C10) ref. to Gasoline MW=100 | 0.070 | 0.29 | 1.8 | 7.4 |

**Client Sample ID: MainHeader-SVE-01162013**

**Lab ID#: 1301530B-02A**

| Compound | Rpt. Limit (ppmv) | Rpt. Limit (ug/L) | Amount (ppmv) | Amount (ug/L) |
|---|---|---|---|---|
| TPH (C2-C10) ref. to Gasoline MW=100 | 30 | 120 | 14000 J | 58000 J |

**Client Sample ID: PWHeader-SVE-01162013**

**Lab ID#: 1301530B-03A**

| Compound | Rpt. Limit (ppmv) | Rpt. Limit (ug/L) | Amount (ppmv) | Amount (ug/L) |
|---|---|---|---|---|
| TPH (C2-C10) ref. to Gasoline MW=100 | 15 | 60 | 4100 | 17000 |

eurofins | Air Toxics

**Client Sample ID: EXH-SVE-01162013**

**Lab ID#: 1301530B-01A**

**MODIFIED EPA METHOD TO-3 GC/FID**

| | | | |
|---|---|---|---|
| File Name: | d013104 | Date of Collection: | 1/16/13 9:25:00 AM |
| Dil. Factor: | 2.82 | Date of Analysis: | 1/30/13 08:28 PM |

| Compound | Rpt. Limit (ppmv) | Rpt. Limit (ug/L) | Amount (ppmv) | Amount (ug/L) |
|---|---|---|---|---|
| TPH (C2-C10) ref. to Gasoline MW=100 | 0.070 | 0.29 | 1.8 | 7.4 |

**Container Type: 1 Liter Summa Canister**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| Fluorobenzene (FID) | 102 | 75-150 |

eurofins | Air Toxics

**Client Sample ID: MainHeader-SVE-01162013**

**Lab ID#: 1301530B-02A**

**MODIFIED EPA METHOD TO-3 GC/FID**

| | | | |
|---|---|---|---|
| **File Name:** | **d013106** | **Date of Collection: 1/16/13 9:35:00 AM** | |
| **Dil. Factor:** | **1180** | **Date of Analysis: 1/30/13 09:37 PM** | |

| Compound | Rpt. Limit (ppmv) | Rpt. Limit (ug/L) | Amount (ppmv) | Amount (ug/L) |
|---|---|---|---|---|
| TPH (C2-C10) ref. to Gasoline MW=100 | 30 | 120 | 14000 J | 58000 J |

Q = Exceeds Quality Control limits, possibly due to matrix effects.

**Container Type: 1 Liter Summa Canister**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| Fluorobenzene (FID) | 166 Q | 75-150 |

eurofins | Air Toxics

**Client Sample ID: PWHeader-SVE-01162013**

**Lab ID#: 1301530B-03A**

**MODIFIED EPA METHOD TO-3 GC/FID**

| | | | |
|---|---|---|---|
| **File Name:** | **d013105** | **Date of Collection: 1/16/13 9:30:00 AM** | |
| **Dil. Factor:** | **592** | **Date of Analysis: 1/30/13 09:04 PM** | |

| Compound | Rpt. Limit (ppmv) | Rpt. Limit (ug/L) | Amount (ppmv) | Amount (ug/L) |
|---|---|---|---|---|
| TPH (C2-C10) ref. to Gasoline MW=100 | 15 | 60 | 4100 | 17000 |

**Container Type: 1 Liter Summa Canister**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| Fluorobenzene (FID) | 116 | 75-150 |

eurofins | Air Toxics

**Client Sample ID: Lab Blank**

**Lab ID#: 1301530B-04A**

**MODIFIED EPA METHOD TO-3 GC/FID**

| | | | |
|---|---|---|---|
| **File Name:** | **d013103a** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 1/30/13 07:11 PM** | |

| Compound | Rpt. Limit (ppmv) | Rpt. Limit (ug/L) | Amount (ppmv) | Amount (ug/L) |
|---|---|---|---|---|
| TPH (C2-C10) ref. to Gasoline MW=100 | 0.025 | 0.10 | 0.014 J | 0.056 J |

J = Estimated value.

**Container Type: NA - Not Applicable**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| Fluorobenzene (FID) | 98 | 75-150 |

eurofins | Air Toxics

**Client Sample ID: LCS**

**Lab ID#: 1301530B-05A**

**MODIFIED EPA METHOD TO-3 GC/FID**

| | | | |
|---|---|---|---|
| **File Name:** | **d013121** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 1/31/13 03:22 PM** | |

| **Compound** | **%Recovery** |
|---|---|
| TPH (C2+ Hydrocarbons) ref. to Gasoline | 101 |

**Container Type: NA - Not Applicable**

| **Surrogates** | **%Recovery** | **Method Limits** |
|---|---|---|
| Fluorobenzene (FID) | 110 | 75-150 |

eurofins | Air Toxics

**Client Sample ID: LCSD**

**Lab ID#: 1301530B-05AA**

**MODIFIED EPA METHOD TO-3 GC/FID**

| | | | |
|---|---|---|---|
| **File Name:** | **d013122** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 1/31/13 04:05 PM** | |

| **Compound** | **%Recovery** |
|---|---|
| TPH (C2+ Hydrocarbons) ref. to Gasoline | 95 |

**Container Type: NA - Not Applicable**

| **Surrogates** | **%Recovery** | **Method Limits** |
|---|---|---|
| Fluorobenzene (FID) | 99 | 75-150 |

1301530

# Shell Oil Products Chain Of Custody Record

URS

Air Toxics LTD.
**Project Name: Roxana SVE O&M**
**Project # 21562850.05000**
Lab Vendor #

Please Check Appropriate Box:
☑ ENV. SERVICES ☐ MOTIVA RETAIL ☐ SHELL RETAIL
☐ MOTIVA SD&CH ☐ CONSULTANT ☐ LUBES
☐ SHELL PIPELINE ☐ OTHER

Print Bill To Contact Name: Robert Mooshegian
PO #:
INCIDENT # (ENV SERVICES): 9 7 2 1 6 6 4 0
SAP #: 3 4 0 0 6 1
☐ CHECK IF NO INCIDENT # APPLIES
DATE: 29-Jan-13
PAGE: 1 of 1

Sampler Company: URS CORPORATION
LOG CODE:
SITE ADDRESS, Street and City: 900 SOUTH CENTRAL AVE – ROXANA
State: IL
G-DOA, ID NO.:
Address: 1001 HIGHLANDS PLAZA DRIVE WEST - SUITE 300, ST LOUIS, MO 63110
EDF DELIVERABLE TO (Name, Company, Office Location): Elizabeth Kunkel, URS, St. Louis
PHONE NO.: 314-743-4179
E-MAIL: elizabeth.kunkel@urs.com
CONSULTANT PROJECT NAME#: Roxana SVE O&M
Laboratory Address: Air Toxics, LTD 180 Blue Ravine Road Suite B, Folsom, CA 95630-4719
TELEPHONE: 314-429-0100
FAX: 314-429-0462
Fax To Contact E-MAIL: dave.palmer@urs.com
SAMPLER NAME(S) (Print): S Wiefler, T. Carrol

TURNAROUND TIME (CALENDAR DAYS):
☑ STANDARD (14 DAY) ☐ 5 DAYS ☐ 3 DAYS ☐ 2 DAYS ☐ 24 HOURS ☐ RESULTS NEEDED ON WEEKEND

☐ LA - RWQCB REPORT FORMAT ☑ UST AGENCY:

DELIVERABLES: ☐ LEVEL 1 ☐ LEVEL 2 ☐ LEVEL 3 ☑ LEVEL 4 ☐ OTHER (SPECIFY)

☑ SHELL CONTRACT RATE APPLIES
☐ STATE REIMBURSEMENT RATE APPLIES
☐ EDD NOT NEEDED
☑ RECEIPT VERIFICATION REQUESTED

REQUESTED ANALYSIS

| LAB USE ONLY | Field Sample Identification | SAMPLING DATE | SAMPLING TIME | Canister Number | Canister Pressure/Vacuum Initial | Final | Receipt | Final (psi) | Modified TO-15 + Butane & Isopentane | Modified ASTM D-1945 + BTU | Modified TO-3 (Sh)-TPHg | | Sample PID (ppm) |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| 01A | EXH-SVE-01162013 | 01/16/13 | 925 | 36461 | -29 | -9 | | | X | X | X | | |
| 02A | MainHeader-SVE-01162013 | 01/16/13 | 935 | 37358 | -29 | -9 | | | X | X | X | | |
| 03A | PWHeader-SVE-01162013 | 01/16/13 | 930 | 36535 | -29 | -9 | | | X | X | X | | |

Turn Around Time: ☑ Normal ☐ Rush Specify

Lab Use Only
Pressurized by:
Date:
Pressurization Gas: $N_2$ He

ADDITIONAL NOTES:
- 14 day hold time
- Report results between MDL and RL
- Level IV ECVP

FedEx
Custody Seal Intact?
(Y) N None Temp NA

| Relinquished by (Signature) | Received by (Signature) | Date | Time |
|---|---|---|---|
| | FEDEX | 1/29/13 | 1730 |
| Relinquished by (Signature) | Received by (Signature) | Date | Time |
| | Kathy Deeb ARL | 01/30/13 | 1050 |
| Relinquished by (Signature) | Received by (Signature) | Date | Time |
| | | | |

05/2006 Revision

eurofins | Air Toxics

2/13/2013
Ms. Elizabeth Kunkel
URS Corporation
1001 Highlands Plaza Dr. West
Suite 300
St. Louis MO 63110

Project Name: Roxana SVE O&M
Project #: 21562850.05000
Workorder #: 1301530C

Dear Ms. Elizabeth Kunkel

The following report includes the data for the above referenced project for sample(s) received on 1/30/2013 at Air Toxics Ltd.

The data and associated QC analyzed by Modified ASTM D-1945 are compliant with the project requirements or laboratory criteria with the exception of the deviations noted in the attached case narrative.

Thank you for choosing Air Toxics Ltd. for your air analysis needs. Air Toxics Ltd. is committed to providing accurate data of the highest quality. Please feel free to contact the Project Manager: Kelly Buettner at 916-985-1000 if you have any questions regarding the data in this report.

Regards,

Kelly Buettner

Project Manager

Reviewed
on
2/25/2013

eurofins | Air Toxics

# WORK ORDER #: 1301530C

Work Order Summary

| | | | |
|---|---|---|---|
| **CLIENT:** | Ms. Elizabeth Kunkel<br>URS Corporation<br>1001 Highlands Plaza Dr. West<br>Suite 300<br>St. Louis, MO 63110 | **BILL TO:** | Accounts Payable Austin<br>URS Corporation<br>P.O. BOX 203970<br>Austin, TX 78720-1088 |
| **PHONE:** | 314-743-4179 | **P.O. #** | |
| **FAX:** | | **PROJECT #** | 21562850.05000 Roxana SVE O&M |
| **DATE RECEIVED:** | 01/30/2013 | **CONTACT:** | Kelly Buettner |
| **DATE COMPLETED:** | 02/13/2013 | | |

| FRACTION # | NAME | TEST | RECEIPT VAC./PRES. | FINAL PRESSURE |
|---|---|---|---|---|
| 01A | EXH-SVE-01162013 | Modified ASTM D-1945 | 8.5 "Hg | 15 psi |
| 02A | MainHeader-SVE-01162013 | Modified ASTM D-1945 | 9.5 "Hg | 15 psi |
| 03A | PWHeader-SVE-01162013 | Modified ASTM D-1945 | 9.5 "Hg | 15 psi |
| 04A | Lab Blank | Modified ASTM D-1945 | NA | NA |
| 04B | Lab Blank | Modified ASTM D-1945 | NA | NA |
| 05A | LCS | Modified ASTM D-1945 | NA | NA |
| 05AA | LCSD | Modified ASTM D-1945 | NA | NA |
| 05B | LCS | Modified ASTM D-1945 | NA | NA |
| 05BB | LCSD | Modified ASTM D-1945 | NA | NA |

CERTIFIED BY: Heidi Hayes DATE: 02/13/13

Technical Director

Certification numbers: AZ Licensure AZ0775, CA NELAP - 12282CA, NY NELAP - 11291,
TX NELAP - T104704434-12-4, UT NELAP CA009332012-3, WA NELAP - C935
Name of Accrediting Agency: NELAP/ORELAP (Oregon Environmental Laboratory Accreditation Program)
Accreditation number: CA300005, Effective date: 10/18/2012, Expiration date: 10/17/2013.
Eurofins Air Toxics Ltd. certifies that the test results contained in this report meet all requirements of the NELAC standards

This report shall not be reproduced, except in full, without the written approval of Eurofins Air Toxics, Inc.

180 BLUE RAVINE ROAD, SUITE B FOLSOM, CA - 9563
(916) 985-1000 . (800) 985-5955 . FAX (916) 985-1020

**LABORATORY NARRATIVE**
**Modified ASTM D-1945**
**URS Corporation**
**Workorder# 1301530C**

Three 1 Liter Summa Canister samples were received on January 30, 2013. The laboratory performed analysis via modified ASTM Method D-1945 for Methane and fixed gases in natural gas using GC/FID or GC/TCD. The method involves direct injection of 1.0 mL of sample.

On the analytical column employed for this analysis, Oxygen coelutes with Argon. The corresponding peak is quantitated as Oxygen.

Since Nitrogen is used to pressurize samples, the reported Nitrogen values are calculated by adding all the sample components and subtracting from 100%.

Method modifications taken to run these samples are summarized in the table below. Specific project requirements may over-ride the ATL modifications.

| *Requirement* | *ASTM D-1945* | *ATL Modifications* |
|---|---|---|
| Normalization | Sum of original values should not differ from 100.0% by more than 1.0%. | Sum of original values may range between 85-115%. Normalization of data not performed. |
| Sample analysis | Equilibrate samples to 20-50° F. above source temperature at field sampling | No heating of samples is performed. |
| Sample calculation | Response factor is calculated using peak height for C5 and lighter compounds. | Peak areas are used for all target analytes to quantitate concentrations. |
| Reference Standard | Concentration should not be < half of nor differ by more than 2 X the concentration of the sample. Run 2 consecutive checks; must agree within 1%. | A minimum 3-point linear calibration is performed. The acceptance criterion is %RSD </= 15%. All target analytes must be within the linear range of calibration (with the exception of O2, N2, and C6+ Hydrocarbons). |
| Sample Injection Volume | 0.50 mL to achieve Methane linearity. | 1.0 mL. |

**Receiving Notes**

There were no receiving discrepancies.

**Analytical Notes**

As per project specific client request the laboratory has reported estimated values for target compound hits that are below the Reporting Limit but greater than the Method Detection Limit. Concentrations that are below the level at which the canister was certified may be false positives.

The reporting limit for Carbon Monoxide was raised from 0.010% to 0.050%.

**Definition of Data Qualifying Flags**

Six qualifiers may have been used on the data analysis sheets and indicate as follows:
J - Estimated value.
E - Exceeds instrument calibration range.
S - Saturated peak.
Q - Exceeds quality control limits.
U - Compound analyzed for but not detected above the detection limit.
M - Reported value may be biased due to apparent matrix interferences.

File extensions may have been used on the data analysis sheets and indicates as follows:
a-File was requantified
b-File was quantified by a second column and detector
r1-File was requantified for the purpose of reissue

eurofins | Air Toxics

# Summary of Detected Compounds
# NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1945

**Client Sample ID: EXH-SVE-01162013**

**Lab ID#: 1301530C-01A**

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.28 | 20 |
| Nitrogen | 0.28 | 79 |
| Methane | 0.00028 | 0.00050 |
| Carbon Dioxide | 0.028 | 0.73 |

**Client Sample ID: MainHeader-SVE-01162013**

**Lab ID#: 1301530C-02A**

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.30 | 10 |
| Nitrogen | 0.30 | 78 |
| Methane | 0.00030 | 3.3 |
| Carbon Dioxide | 0.030 | 7.4 |
| Ethane | 0.0030 | 0.00089 J |
| Propane | 0.0030 | 0.0013 J |
| Isobutane | 0.0030 | 0.022 |
| Butane | 0.0030 | 0.20 |
| Neopentane | 0.0030 | 0.00089 J |
| Isopentane | 0.0030 | 0.24 |
| Pentane | 0.0030 | 0.091 |
| C6+ | 0.030 | 0.68 |

**Client Sample ID: PWHeader-SVE-01162013**

**Lab ID#: 1301530C-03A**

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.30 | 12 |
| Nitrogen | 0.30 | 76 |
| Methane | 0.00030 | 4.1 |
| Carbon Dioxide | 0.030 | 7.2 |
| Ethane | 0.0030 | 0.00024 J |
| Propane | 0.0030 | 0.00013 J |
| Isobutane | 0.0030 | 0.0045 |

eurofins | Air Toxics

## Summary of Detected Compounds
## NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1945

**Client Sample ID: PWHeader-SVE-01162013**

**Lab ID#: 1301530C-03A**

| | | |
|---|---|---|
| Butane | 0.0030 | 0.042 |
| Neopentane | 0.0030 | 0.00024 J |
| Isopentane | 0.0030 | 0.089 |
| Pentane | 0.0030 | 0.038 |
| C6+ | 0.030 | 0.15 |

eurofins | Air Toxics

**Client Sample ID: EXH-SVE-01162013**

**Lab ID#: 1301530C-01A**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1945**

| | | | |
|---|---|---|---|
| **File Name:** | **9013021** | **Date of Collection:** | **1/16/13 9:25:00 AM** |
| **Dil. Factor:** | **2.82** | **Date of Analysis:** | **1/30/13 07:14 PM** |

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.28 | 20 |
| Nitrogen | 0.28 | 79 |
| Carbon Monoxide | 0.14 | Not Detected |
| Methane | 0.00028 | 0.00050 |
| Carbon Dioxide | 0.028 | 0.73 |
| Ethane | 0.0028 | Not Detected |
| Ethene | 0.0028 | Not Detected |
| Acetylene | 0.0028 | Not Detected |
| Propane | 0.0028 | Not Detected |
| Isobutane | 0.0028 | Not Detected |
| Butane | 0.0028 | Not Detected |
| Neopentane | 0.0028 | Not Detected |
| Isopentane | 0.0028 | Not Detected |
| Pentane | 0.0028 | Not Detected |
| C6+ | 0.028 | Not Detected |
| Hydrogen | 0.028 | Not Detected |

Total BTU/Cu.F. = 0.0050
Total Sp. Gravity = 1.0
**Container Type: 1 Liter Summa Canister**

eurofins | Air Toxics

**Client Sample ID: MainHeader-SVE-01162013**

**Lab ID#: 1301530C-02A**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1945**

| | | | |
|---|---|---|---|
| **File Name:** | **9013023** | **Date of Collection:** | **1/16/13 9:35:00 AM** |
| **Dil. Factor:** | **2.96** | **Date of Analysis:** | **1/30/13 08:07 PM** |

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.30 | 10 |
| Nitrogen | 0.30 | 78 |
| Carbon Monoxide | 0.15 | Not Detected |
| Methane | 0.00030 | 3.3 |
| Carbon Dioxide | 0.030 | 7.4 |
| Ethane | 0.0030 | 0.00089 J |
| Ethene | 0.0030 | Not Detected |
| Acetylene | 0.0030 | Not Detected |
| Propane | 0.0030 | 0.0013 J |
| Isobutane | 0.0030 | 0.022 |
| Butane | 0.0030 | 0.20 |
| Neopentane | 0.0030 | 0.00089 J |
| Isopentane | 0.0030 | 0.24 |
| Pentane | 0.0030 | 0.091 |
| C6+ | 0.030 | 0.68 |
| Hydrogen | 0.030 | Not Detected |

J = Estimated value.

Total BTU/Cu.F. = 86

Total Sp. Gravity = 1.0

**Container Type: 1 Liter Summa Canister**

eurofins | Air Toxics

**Client Sample ID: PWHeader-SVE-01162013**

**Lab ID#: 1301530C-03A**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1945**

| | | | |
|---|---|---|---|
| **File Name:** | **9013022** | **Date of Collection:** | **1/16/13 9:30:00 AM** |
| **Dil. Factor:** | **2.96** | **Date of Analysis:** | **1/30/13 07:35 PM** |

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.30 | 12 |
| Nitrogen | 0.30 | 76 |
| Carbon Monoxide | 0.15 | Not Detected |
| Methane | 0.00030 | 4.1 |
| Carbon Dioxide | 0.030 | 7.2 |
| Ethane | 0.0030 | 0.00024 J |
| Ethene | 0.0030 | Not Detected |
| Acetylene | 0.0030 | Not Detected |
| Propane | 0.0030 | 0.00013 J |
| Isobutane | 0.0030 | 0.0045 |
| Butane | 0.0030 | 0.042 |
| Neopentane | 0.0030 | 0.00024 J |
| Isopentane | 0.0030 | 0.089 |
| Pentane | 0.0030 | 0.038 |
| C6+ | 0.030 | 0.15 |
| Hydrogen | 0.030 | Not Detected |

J = Estimated value.

Total BTU/Cu.F. = 55

Total Sp. Gravity = 1.0

**Container Type: 1 Liter Summa Canister**

eurofins | Air Toxics

**Client Sample ID: Lab Blank**

**Lab ID#: 1301530C-04A**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1945**

| | | | |
|---|---|---|---|
| **File Name:** | **9013005a** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 1/30/13 11:12 AM** | |

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.10 | Not Detected |
| Nitrogen | 0.10 | 0.068 J |
| Carbon Monoxide | 0.050 | Not Detected |
| Methane | 0.00010 | Not Detected |
| Carbon Dioxide | 0.010 | Not Detected |
| Ethane | 0.0010 | Not Detected |
| Ethene | 0.0010 | Not Detected |
| Acetylene | 0.0010 | Not Detected |
| Propane | 0.0010 | Not Detected |
| Isobutane | 0.0010 | Not Detected |
| Butane | 0.0010 | Not Detected |
| Neopentane | 0.0010 | Not Detected |
| Isopentane | 0.0010 | Not Detected |
| Pentane | 0.0010 | Not Detected |
| C6+ | 0.010 | Not Detected |

J = Estimated value.

**Container Type: NA - Not Applicable**

eurofins | Air Toxics

**Client Sample ID: Lab Blank**

**Lab ID#: 1301530C-04B**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1945**

| | | | |
|---|---|---|---|
| **File Name:** | **9013003b** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 1/30/13 10:12 AM** | |

| **Compound** | **Rpt. Limit (%)** | **Amount (%)** |
|---|---|---|
| Hydrogen | 0.010 | Not Detected |

**Container Type: NA - Not Applicable**

eurofins | Air Toxics

**Client Sample ID: LCS**

**Lab ID#: 1301530C-05A**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1945**

| | | | |
|---|---|---|---|
| **File Name:** | **9013008** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 1/30/13 12:22 PM** | |

| Compound | %Recovery |
|---|---|
| Oxygen | 99 |
| Nitrogen | 101 |
| Carbon Monoxide | 99 |
| Methane | 104 |
| Carbon Dioxide | 101 |
| Ethane | 105 |
| Ethene | 102 |
| Acetylene | 104 |
| Propane | 108 |
| Isobutane | 108 |
| Butane | 107 |
| Neopentane | 107 |
| Isopentane | 106 |
| Pentane | 106 |
| C6+ | 106 |

**Container Type: NA - Not Applicable**

eurofins | Air Toxics

**Client Sample ID: LCSD**

**Lab ID#: 1301530C-05AA**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1945**

| | | | |
|---|---|---|---|
| **File Name:** | **9013033** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 1/31/13 08:50 AM** | |

| Compound | %Recovery |
|---|---|
| Oxygen | 98 |
| Nitrogen | 100 |
| Carbon Monoxide | 101 |
| Methane | 92 |
| Carbon Dioxide | 101 |
| Ethane | 94 |
| Ethene | 91 |
| Acetylene | 92 |
| Propane | 96 |
| Isobutane | 96 |
| Butane | 95 |
| Neopentane | 96 |
| Isopentane | 94 |
| Pentane | 95 |
| C6+ | 95 |

**Container Type: NA - Not Applicable**

eurofins | Air Toxics

**Client Sample ID: LCS**

**Lab ID#: 1301530C-05B**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1945**

| | | | |
|---|---|---|---|
| **File Name:** | **9013009b** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 1/30/13 12:47 PM** | |

| **Compound** | **%Recovery** |
|---|---|
| Hydrogen | 98 |

**Container Type: NA - Not Applicable**

eurofins | Air Toxics

**Client Sample ID: LCSD**

**Lab ID#: 1301530C-05BB**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1945**

| | | | |
|---|---|---|---|
| **File Name:** | **9013032b** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 1/31/13 08:27 AM** | |

| **Compound** | **%Recovery** |
|---|---|
| Hydrogen | 97 |

**Container Type: NA - Not Applicable**

1301530

# Shell Oil Products Chain Of Custody Record

URS

Air Toxics LTD.
**Project Name: Roxana SVE O&M**
**Project # 21562850.05000**
Lab Vendor #

Please Check Appropriate Box: ☑ ENV. SERVICES ☐ MOTIVA RETAIL ☐ SHELL RETAIL ☐ MOTIVA SD&CH ☐ CONSULTANT ☐ LUBES ☐ SHELL PIPELINE ☐ OTHER

Print Bill To Contact Name: Robert Mooshegian

INCIDENT # (ENV SERVICES): 9 7 2 1 6 6 4 0 ☐ CHECK IF NO INCIDENT # APPLIES

PO #:

SAP #: 3 4 0 0 6 1

DATE: 29-Jan-13

PAGE: 1 of 1

SAMPLING COMPANY: URS CORPORATION

LOG CODE:

SITE ADDRESS: Street and City: 900 SOUTH CENTRAL AVE – ROXANA

State: IL

GLOBAL ID NO.:

ADDRESS: 1001 HIGHLANDS PLAZA DRIVE WEST - SUITE 300, ST LOUIS, MO 63110

EDF DELIVERABLE TO (Name, Company, Office Location): Elizabeth Kunkel, URS, St. Louis

PHONE NO.: 314-743-4179

E-MAIL: elizabeth.kunkel@urs.com

CONSULTANT PROJECT NAME: Roxana SVE O&M

Laboratory Address: Air Toxics, LTD 180 Blue Ravine Road Suite B, Folsom, CA 95630-4719

SAMPLER NAME(S) (Print): S Wistler, T Carrol

TELEPHONE: 314-429-0100

FAX: 314-429-0462

E-MAIL To Contact: dave.palmer@urs.com

TURNAROUND TIME (CALENDAR DAYS): ☑ STANDARD (14 DAY) ☐ 5 DAYS ☐ 3 DAYS ☐ 2 DAYS ☐ 24 HOURS ☐ RESULTS NEEDED ON WEEKEND

REQUESTED ANALYSIS

☐ LA - RWQCB REPORT FORMAT ☑ UST AGENCY:

DELIVERABLES: ☐ LEVEL 1 ☐ LEVEL 2 ☐ LEVEL 3 ☑ LEVEL 4 ☐ OTHER (SPECIFY)

☑ SHELL CONTRACT RATE APPLIES
☐ STATE REIMBURSEMENT RATE APPLIES
☐ EDD NOT NEEDED
☑ RECEIPT VERIFICATION REQUESTED

| LAB USE ONLY | Field Sample Identification | SAMPLING DATE | SAMPLING TIME | Canister Number | Canister Pressure/Vacuum Initial | Final | Receipt | Final (psi) | Modified TO-15 + Butane & Isopentane | Modified ASTM D-1945 + BTU | Modified TO-3 (Sh)-TPHg | | Sample PID (ppm) |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| 01A | EXH-SVE-01162013 | 01/16/13 | 925 | 36461 | -29 | -9 | | | X | X | X | | |
| 02A | MainHeader-SVE-01162013 | 01/16/13 | 935 | 37358 | -29 | -9 | | | X | X | X | | |
| 03A | PWHeader-SVE-01162013 | 01/16/13 | 930 | 36535 | -29 | -9 | | | X | X | X | | |

Turn Around Time: ☑ Normal ☐ Rush ☐ Specify

Lab Use Only
Pressurized by:
Date:
Pressurization Gas: $N_2$ He

ADDITIONAL NOTES:

- 14 day hold time
- Report results between MDL and RL
- Level IV ECVP

FedEx
Custody Seal Intact?
(Y) N None Temp NA

| Relinquished by (Signature) | Received by (Signature) | Date | Time |
|---|---|---|---|
| | FEDEX | 1/29/13 | 1730 |
| Relinquished by (Signature) | Received by (Signature) | Date | Time |
| | Kathy Deeter AR | 01/30/13 | 1050 |
| Relinquished by (Signature) | Received by (Signature) | Date | Time |
| | | | |

GC/MS Revision

# Roxana Soil Vapor Quarterly – 1st Quarter 2013 Data Review

**Laboratory SDG: 1301555A,B**

**Data Reviewer: Alan Fleisher**

**Peer Reviewer: Elizabeth Kunkel**

**Date Reviewed: 3/20/2013**

**Guidance: USEPA National Functional Guidelines for Superfund Organic Methods Data Review 2008**

| Sample Identification | Sample Identification |
|---|---|
| VMP-20-39.5-012313 | VMP-44-10-012513 |
| VMP-44-20-012513 | VMP-44-30-012513 |

## 1.0 Data Package Completeness

*Were all items delivered as specified in the QAPP and COC as appropriate?*

Yes, however, professional judgment was used to qualify sample VMP-44-30-012513 due to the helium result in the sample (9.9%) that was greater than 10% of helium in the shroud (61.0%).

## 2.0 Laboratory Case Narrative \ Cooler Receipt Form

*Were problems noted in the laboratory case narrative or cooler receipt form?*

Yes, the laboratory case narrative indicated samples VMP-20-39.5-012313, VMP-44-10-012513, and VMP-44-20-012513 were diluted due to high levels of target analytes. Although not indicated in the laboratory case narrative, analytes were detected in the method blank. These issues are addressed further in the appropriate sections below.

No issues or discrepancies were noted in the cooler receipt form.

## 3.0 Holding Times

*Were samples extracted/analyzed within applicable limits?*

Yes

## 4.0 Blank Contamination

*Were any analytes detected in the Blanks?*

Yes

| Blank ID | Parameter | Analyte | Concentration/ Amount |
|---|---|---|---|
| 1301555A-05A | TO-15 | Ethanol | 9.2 ppbv / 17 µg/m$^3$ |
| 1301555A-05A | TO-15 | Methylene chloride | 0.95 ppbv / 3.3 µg/m$^3$ |
| 1301555B-05A | Natural gases | Nitrogen | 0.085% |
| 1301555B-05C | Natural gases | Nitrogen | 0.089% |

Qualifications due to blank contamination are included in the table below. Analytical data that were reported non-detect or at concentrations greater than five times (5X) the associated blank concentration did not require qualification.

| Sample ID | Parameter | Analyte | New Reporting Limit (RL) | Qualification |
|---|---|---|---|---|
| VMP-44-30-012513 | TO-15 | Ethanol | - | **U** |
| VMP-44-30-012513 | TO-15 | Methylene chloride | - | **U** |

## 5.0 Laboratory Control Sample

*Were LCS recoveries within evaluation criteria?*

Yes

## 6.0 Surrogate Recoveries

*Were surrogate recoveries within evaluation criteria?*

Yes

## 7.0 Matrix Spike and Matrix Spike Duplicate Recoveries

*Were MS/MSD samples analyzed as part of this SDG?*

MS/MSD samples are not applicable for vapor samples, due to the inability to spike the samples.

## 8.0 Laboratory Duplicate Results

*Were laboratory duplicate samples collected as part of this SDG?*

No

## 9.0 Field Duplicate Results

*Were field duplicate samples collected as part of this SDG?*

No

## 10.0 Sample Dilutions

*For samples that were diluted and nondetect, were undiluted results also reported?*

Not applicable; analytes were detected in samples that were diluted.

## 11.0 Additional Qualifications

*Were additional qualifications applied?*

Yes, professional judgment was used to qualify sample VMP-44-30-012513 due to a helium result in the sample (6.6%) that was greater than 10% of helium in the shroud (57.8%).

| Sample ID | Parameter | Analyte | Qualification |
|---|---|---|---|
| VMP-44-30-012513 | TO-15 | All detects | **J** |
| VMP-44-30-012513 | TO-15 | All non-detects | **UJ** |
| VMP-44-30-012513 | Natural gases | All detects | **J** |
| VMP-44-30-012513 | Natural gases | All non-detects | **UJ** |

eurofins | Air Toxics

2/13/2013
Ms. Elizabeth Kunkel
URS Corporation
1001 Highlands Plaza Dr. West
Suite 300
St. Louis MO 63110

Project Name: Roxana Soil Vapor
Project #: 21562850.04001
Workorder #: 1301555A

Dear Ms. Elizabeth Kunkel

The following report includes the data for the above referenced project for sample(s) received on 1/31/2013 at Air Toxics Ltd.

The data and associated QC analyzed by Modified TO-15 are compliant with the project requirements or laboratory criteria with the exception of the deviations noted in the attached case narrative.

Thank you for choosing Air Toxics Ltd. for your air analysis needs. Air Toxics Ltd. is committed to providing accurate data of the highest quality. Please feel free to contact the Project Manager: Kelly Buettner at 916-985-1000 if you have any questions regarding the data in this report.

Regards,

Kelly Buettner

Project Manager

REVIEWED
ON
3/20/13

eurofins | Air Toxics

# WORK ORDER #: 1301555A

Work Order Summary

| | | | |
|---|---|---|---|
| **CLIENT:** | Ms. Elizabeth Kunkel<br>URS Corporation<br>1001 Highlands Plaza Dr. West<br>Suite 300<br>St. Louis, MO 63110 | **BILL TO:** | Accounts Payable Austin<br>URS Corporation<br>P.O. BOX 203970<br>Austin, TX 78720-1088 |
| **PHONE:** | 314-743-4179 | **P.O. #** | 21562735.00013 |
| **FAX:** | | **PROJECT #** | 21562850.04001 Roxana Soil Vapor |
| **DATE RECEIVED:** | 01/31/2013 | **CONTACT:** | Kelly Buettner |
| **DATE COMPLETED:** | 02/12/2013 | | |

| FRACTION # | NAME | TEST | RECEIPT VAC./PRES. | FINAL PRESSURE |
|---|---|---|---|---|
| 01A | VMP-20-39.5-012313 | Modified TO-15 | 5.6 "Hg | 15 psi |
| 02A | VMP-44-10-012513 | Modified TO-15 | 3.6 "Hg | 15 psi |
| 03A | VMP-44-20-012513 | Modified TO-15 | 5.8 "Hg | 15 psi |
| 04A | VMP-44-30-012513 | Modified TO-15 | 9.2 "Hg | 15 psi |
| 05A | Lab Blank | Modified TO-15 | NA | NA |
| 06A | CCV | Modified TO-15 | NA | NA |
| 07A | LCS | Modified TO-15 | NA | NA |
| 07AA | LCSD | Modified TO-15 | NA | NA |

CERTIFIED BY: _____ DATE: 02/13/13

Technical Director

Certification numbers: AZ Licensure AZ0775, CA NELAP - 12282CA, NY NELAP - 11291,
TX NELAP - T104704434-12-5, UT NELAP CA009332012-3, WA NELAP - C935
Name of Accrediting Agency: NELAP/ORELAP (Oregon Environmental Laboratory Accreditation Program)
Accreditation number: CA300005, Effective date: 10/18/2011, Expiration date: 10/17/2012.
Eurofins Air Toxics Ltd. certifies that the test results contained in this report meet all requirements of the NELAC standards

This report shall not be reproduced, except in full, without the written approval of Eurofins Air Toxics, Inc

180 BLUE RAVINE ROAD, SUITE B FOLSOM, CA - 9563
(916) 985-1000 . (800) 985-5955 . FAX (916) 985-1020

**LABORATORY NARRATIVE**
**EPA Method TO-15**
**URS Corporation**
**Workorder# 1301555A**

Four 1 Liter Summa Canister samples were received on January 31, 2013. The laboratory performed analysis via EPA Method TO-15 using GC/MS in the full scan mode.

This workorder was independently validated prior to submittal using 'USEPA National Functional Guidelines' as generally applied to the analysis of volatile organic compounds in air. A rules-based, logic driven, independent validation engine was employed to assess completeness, evaluate pass/fail of relevant project quality control requirements and verification of all quantified amounts.

**Receiving Notes**

There were no receiving discrepancies.

**Analytical Notes**

As per client project requirements, the laboratory has reported estimated values for target compound hits that are below the Reporting Limit but greater than the Method Detection Limit. Concentrations that are below the level at which the canister was certified may be false positives.

Dilution was performed on samples VMP-20-39.5-012313, VMP-44-10-012513, and VMP-44-20-012513 due to the presence of high level target species.

**Definition of Data Qualifying Flags**

Eight qualifiers may have been used on the data analysis sheets and indicates as follows:

B - Compound present in laboratory blank greater than reporting limit (background subtraction not performed).
J - Estimated value.
E - Exceeds instrument calibration range.
S - Saturated peak.
Q - Exceeds quality control limits.
U - Compound analyzed for but not detected above the reporting limit.
UJ- Non-detected compound associated with low bias in the CCV and/or LCS.
N - The identification is based on presumptive evidence.

File extensions may have been used on the data analysis sheets and indicates as follows:
a-File was requantified
b-File was quantified by a second column and detector
r1-File was requantified for the purpose of reissue

eurofins | Air Toxics

# Summary of Detected Compounds
# EPA METHOD TO-15 GC/MS

**Client Sample ID: VMP-20-39.5-012313**

**Lab ID#: 1301555A-01A**

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| 2-Propanol | 830 | 73 J | 2000 | 180 J |
| Methylene Chloride | 210 | 38 J | 720 | 130 J |
| Hexane | 210 | 19 J | 730 | 68 J |
| 2,2,4-Trimethylpentane | 210 | 120000 | 960 | 560000 |
| Benzene | 210 | 75 J | 660 | 240 J |
| Tetrachloroethene | 210 | 77 J | 1400 | 520 J |
| Butane | 830 | 5200 | 2000 | 12000 |
| Isopentane | 830 | 2400 | 2400 | 7100 |

**Client Sample ID: VMP-44-10-012513**

**Lab ID#: 1301555A-02A**

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| 2-Propanol | 460 | 38 J | 1100 | 93 J |
| Methylene Chloride | 120 | 22 J | 400 | 77 J |
| Hexane | 120 | 1400 | 400 | 5100 |
| Cyclohexane | 120 | 2700 | 400 | 9300 |
| 2,2,4-Trimethylpentane | 120 | 65000 | 540 | 300000 |
| Benzene | 120 | 160 | 370 | 530 |
| Tetrachloroethene | 120 | 35 J | 780 | 240 J |
| m,p-Xylene | 120 | 21 J | 500 | 92 J |
| Butane | 460 | 1300 | 1100 | 3100 |
| Isopentane | 460 | 2800 | 1400 | 8400 |

**Client Sample ID: VMP-44-20-012513**

**Lab ID#: 1301555A-03A**

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| 2-Propanol | 170 | 450 | 410 | 1100 |
| Methylene Chloride | 42 | 10 J | 140 | 36 J |
| Hexane | 42 | 110 | 150 | 380 |
| Cyclohexane | 42 | 940 | 140 | 3200 |
| 2,2,4-Trimethylpentane | 42 | 23000 | 190 | 110000 |

eurofins | Air Toxics

# Summary of Detected Compounds
# EPA METHOD TO-15 GC/MS

**Client Sample ID: VMP-44-20-012513**

**Lab ID#: 1301555A-03A**

| | | | | |
|---|---|---|---|---|
| Benzene | 42 | 20 J | 130 | 65 J |
| Butane | 170 | 190 | 400 | 460 |
| Isopentane | 170 | 5400 | 490 | 16000 |

**Client Sample ID: VMP-44-30-012513**

**Lab ID#: 1301555A-04A**

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Ethanol | 58 | ~~15 J~~ | 110 | ~~29 J~~ |
| Acetone | 58 | 6300 | 140 | 15000 |
| 2-Propanol | 58 | 4300 | 140 | 10000 |
| Methylene Chloride | 14 | ~~3.1 J~~ | 50 | ~~11 J~~ |
| Hexane | 14 | 4.7 J | 51 | 17 J |
| Cyclohexane | 14 | 6.3 J | 50 | 22 J |
| 2,2,4-Trimethylpentane | 14 | 100 | 68 | 470 |
| Benzene | 14 | 12 J | 46 | 37 J |
| Butane | 58 | 18 J | 140 | 42 J |
| Isopentane | 58 | 21 J | 170 | 61 J |

**Client Sample ID: VMP-20-39.5-012313**

**Lab ID#: 1301555A-01A**

**EPA METHOD TO-15 GC/MS**

| | | | |
|---|---|---|---|
| **File Name:** | **14020441** | **Date of Collection:** | **1/23/13 10:12:00 AM** |
| **Dil. Factor:** | **41.3** | **Date of Analysis:** | **2/5/13 11:02 AM** |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 210 | Not Detected | 1000 | Not Detected |
| Freon 114 | 210 | Not Detected | 1400 | Not Detected |
| Chloromethane | 830 | Not Detected | 1700 | Not Detected |
| Vinyl Chloride | 210 | Not Detected | 530 | Not Detected |
| 1,3-Butadiene | 210 | Not Detected | 460 | Not Detected |
| Bromomethane | 210 | Not Detected | 800 | Not Detected |
| Chloroethane | 830 | Not Detected | 2200 | Not Detected |
| Freon 11 | 210 | Not Detected | 1200 | Not Detected |
| Ethanol | 830 | Not Detected | 1600 | Not Detected |
| Freon 113 | 210 | Not Detected | 1600 | Not Detected |
| 1,1-Dichloroethene | 210 | Not Detected | 820 | Not Detected |
| Acetone | 830 | Not Detected | 2000 | Not Detected |
| 2-Propanol | 830 | 73 J | 2000 | 180 J |
| Carbon Disulfide | 210 | Not Detected | 640 | Not Detected |
| 3-Chloropropene | 830 | Not Detected | 2600 | Not Detected |
| Methylene Chloride | 210 | 38 J | 720 | 130 J |
| Methyl tert-butyl ether | 210 | Not Detected | 740 | Not Detected |
| trans-1,2-Dichloroethene | 210 | Not Detected | 820 | Not Detected |
| Hexane | 210 | 19 J | 730 | 68 J |
| 1,1-Dichloroethane | 210 | Not Detected | 840 | Not Detected |
| 2-Butanone (Methyl Ethyl Ketone) | 830 | Not Detected | 2400 | Not Detected |
| cis-1,2-Dichloroethene | 210 | Not Detected | 820 | Not Detected |
| Tetrahydrofuran | 210 | Not Detected | 610 | Not Detected |
| Chloroform | 210 | Not Detected | 1000 | Not Detected |
| 1,1,1-Trichloroethane | 210 | Not Detected | 1100 | Not Detected |
| Cyclohexane | 210 | Not Detected | 710 | Not Detected |
| Carbon Tetrachloride | 210 | Not Detected | 1300 | Not Detected |
| 2,2,4-Trimethylpentane | 210 | 120000 | 960 | 560000 |
| Benzene | 210 | 75 J | 660 | 240 J |
| 1,2-Dichloroethane | 210 | Not Detected | 840 | Not Detected |
| Heptane | 210 | Not Detected | 850 | Not Detected |
| Trichloroethene | 210 | Not Detected | 1100 | Not Detected |
| 1,2-Dichloropropane | 210 | Not Detected | 950 | Not Detected |
| 1,4-Dioxane | 830 | Not Detected | 3000 | Not Detected |
| Bromodichloromethane | 210 | Not Detected | 1400 | Not Detected |
| cis-1,3-Dichloropropene | 210 | Not Detected | 940 | Not Detected |
| 4-Methyl-2-pentanone | 210 | Not Detected | 840 | Not Detected |
| Toluene | 210 | Not Detected | 780 | Not Detected |
| trans-1,3-Dichloropropene | 210 | Not Detected | 940 | Not Detected |
| 1,1,2-Trichloroethane | 210 | Not Detected | 1100 | Not Detected |
| Tetrachloroethene | 210 | 77 J | 1400 | 520 J |
| 2-Hexanone | 830 | Not Detected | 3400 | Not Detected |

eurofins | Air Toxics

**Client Sample ID: VMP-20-39.5-012313**

**Lab ID#: 1301555A-01A**

**EPA METHOD TO-15 GC/MS**

| | | | |
|---|---|---|---|
| **File Name:** | **14020441** | **Date of Collection:** | **1/23/13 10:12:00 AM** |
| **Dil. Factor:** | **41.3** | **Date of Analysis:** | **2/5/13 11:02 AM** |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Dibromochloromethane | 210 | Not Detected | 1800 | Not Detected |
| 1,2-Dibromoethane (EDB) | 210 | Not Detected | 1600 | Not Detected |
| Chlorobenzene | 210 | Not Detected | 950 | Not Detected |
| Ethyl Benzene | 210 | Not Detected | 900 | Not Detected |
| m,p-Xylene | 210 | Not Detected | 900 | Not Detected |
| o-Xylene | 210 | Not Detected | 900 | Not Detected |
| Styrene | 210 | Not Detected | 880 | Not Detected |
| Bromoform | 210 | Not Detected | 2100 | Not Detected |
| Cumene | 210 | Not Detected | 1000 | Not Detected |
| 1,1,2,2-Tetrachloroethane | 210 | Not Detected | 1400 | Not Detected |
| Propylbenzene | 210 | Not Detected | 1000 | Not Detected |
| 4-Ethyltoluene | 210 | Not Detected | 1000 | Not Detected |
| 1,3,5-Trimethylbenzene | 210 | Not Detected | 1000 | Not Detected |
| 1,2,4-Trimethylbenzene | 210 | Not Detected | 1000 | Not Detected |
| 1,3-Dichlorobenzene | 210 | Not Detected | 1200 | Not Detected |
| 1,4-Dichlorobenzene | 210 | Not Detected | 1200 | Not Detected |
| alpha-Chlorotoluene | 210 | Not Detected | 1100 | Not Detected |
| 1,2-Dichlorobenzene | 210 | Not Detected | 1200 | Not Detected |
| 1,2,4-Trichlorobenzene | 830 | Not Detected | 6100 | Not Detected |
| Hexachlorobutadiene | 830 | Not Detected | 8800 | Not Detected |
| Butane | 830 | 5200 | 2000 | 12000 |
| Isopentane | 830 | 2400 | 2400 | 7100 |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| 1,2-Dichloroethane-d4 | 119 | 70-130 |
| Toluene-d8 | 101 | 70-130 |
| 4-Bromofluorobenzene | 98 | 70-130 |

eurofins | Air Toxics

**Client Sample ID: VMP-44-10-012513**

**Lab ID#: 1301555A-02A**

**EPA METHOD TO-15 GC/MS**

| | | | |
|---|---|---|---|
| **File Name:** | **14020442** | **Date of Collection:** | **1/25/13 9:50:00 AM** |
| **Dil. Factor:** | **23.0** | **Date of Analysis:** | **2/5/13 11:22 AM** |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 120 | Not Detected | 570 | Not Detected |
| Freon 114 | 120 | Not Detected | 800 | Not Detected |
| Chloromethane | 460 | Not Detected | 950 | Not Detected |
| Vinyl Chloride | 120 | Not Detected | 290 | Not Detected |
| 1,3-Butadiene | 120 | Not Detected | 250 | Not Detected |
| Bromomethane | 120 | Not Detected | 450 | Not Detected |
| Chloroethane | 460 | Not Detected | 1200 | Not Detected |
| Freon 11 | 120 | Not Detected | 650 | Not Detected |
| Ethanol | 460 | Not Detected | 870 | Not Detected |
| Freon 113 | 120 | Not Detected | 880 | Not Detected |
| 1,1-Dichloroethene | 120 | Not Detected | 460 | Not Detected |
| Acetone | 460 | Not Detected | 1100 | Not Detected |
| 2-Propanol | 460 | 38 J | 1100 | 93 J |
| Carbon Disulfide | 120 | Not Detected | 360 | Not Detected |
| 3-Chloropropene | 460 | Not Detected | 1400 | Not Detected |
| Methylene Chloride | 120 | 22 J | 400 | 77 J |
| Methyl tert-butyl ether | 120 | Not Detected | 410 | Not Detected |
| trans-1,2-Dichloroethene | 120 | Not Detected | 460 | Not Detected |
| Hexane | 120 | 1400 | 400 | 5100 |
| 1,1-Dichloroethane | 120 | Not Detected | 460 | Not Detected |
| 2-Butanone (Methyl Ethyl Ketone) | 460 | Not Detected | 1400 | Not Detected |
| cis-1,2-Dichloroethene | 120 | Not Detected | 460 | Not Detected |
| Tetrahydrofuran | 120 | Not Detected | 340 | Not Detected |
| Chloroform | 120 | Not Detected | 560 | Not Detected |
| 1,1,1-Trichloroethane | 120 | Not Detected | 630 | Not Detected |
| Cyclohexane | 120 | 2700 | 400 | 9300 |
| Carbon Tetrachloride | 120 | Not Detected | 720 | Not Detected |
| 2,2,4-Trimethylpentane | 120 | 65000 | 540 | 300000 |
| Benzene | 120 | 160 | 370 | 530 |
| 1,2-Dichloroethane | 120 | Not Detected | 460 | Not Detected |
| Heptane | 120 | Not Detected | 470 | Not Detected |
| Trichloroethene | 120 | Not Detected | 620 | Not Detected |
| 1,2-Dichloropropane | 120 | Not Detected | 530 | Not Detected |
| 1,4-Dioxane | 460 | Not Detected | 1600 | Not Detected |
| Bromodichloromethane | 120 | Not Detected | 770 | Not Detected |
| cis-1,3-Dichloropropene | 120 | Not Detected | 520 | Not Detected |
| 4-Methyl-2-pentanone | 120 | Not Detected | 470 | Not Detected |
| Toluene | 120 | Not Detected | 430 | Not Detected |
| trans-1,3-Dichloropropene | 120 | Not Detected | 520 | Not Detected |
| 1,1,2-Trichloroethane | 120 | Not Detected | 630 | Not Detected |
| Tetrachloroethene | 120 | 35 J | 780 | 240 J |
| 2-Hexanone | 460 | Not Detected | 1900 | Not Detected |

eurofins | Air Toxics

**Client Sample ID: VMP-44-10-012513**

**Lab ID#: 1301555A-02A**

**EPA METHOD TO-15 GC/MS**

| | | | |
|---|---|---|---|
| **File Name:** | **14020442** | **Date of Collection:** | **1/25/13 9:50:00 AM** |
| **Dil. Factor:** | **23.0** | **Date of Analysis:** | **2/5/13 11:22 AM** |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Dibromochloromethane | 120 | Not Detected | 980 | Not Detected |
| 1,2-Dibromoethane (EDB) | 120 | Not Detected | 880 | Not Detected |
| Chlorobenzene | 120 | Not Detected | 530 | Not Detected |
| Ethyl Benzene | 120 | Not Detected | 500 | Not Detected |
| m,p-Xylene | 120 | 21 J | 500 | 92 J |
| o-Xylene | 120 | Not Detected | 500 | Not Detected |
| Styrene | 120 | Not Detected | 490 | Not Detected |
| Bromoform | 120 | Not Detected | 1200 | Not Detected |
| Cumene | 120 | Not Detected | 560 | Not Detected |
| 1,1,2,2-Tetrachloroethane | 120 | Not Detected | 790 | Not Detected |
| Propylbenzene | 120 | Not Detected | 560 | Not Detected |
| 4-Ethyltoluene | 120 | Not Detected | 560 | Not Detected |
| 1,3,5-Trimethylbenzene | 120 | Not Detected | 560 | Not Detected |
| 1,2,4-Trimethylbenzene | 120 | Not Detected | 560 | Not Detected |
| 1,3-Dichlorobenzene | 120 | Not Detected | 690 | Not Detected |
| 1,4-Dichlorobenzene | 120 | Not Detected | 690 | Not Detected |
| alpha-Chlorotoluene | 120 | Not Detected | 600 | Not Detected |
| 1,2-Dichlorobenzene | 120 | Not Detected | 690 | Not Detected |
| 1,2,4-Trichlorobenzene | 460 | Not Detected | 3400 | Not Detected |
| Hexachlorobutadiene | 460 | Not Detected | 4900 | Not Detected |
| Butane | 460 | 1300 | 1100 | 3100 |
| Isopentane | 460 | 2800 | 1400 | 8400 |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| 1,2-Dichloroethane-d4 | 121 | 70-130 |
| Toluene-d8 | 102 | 70-130 |
| 4-Bromofluorobenzene | 100 | 70-130 |

eurofins | Air Toxics

**Client Sample ID: VMP-44-20-012513**

**Lab ID#: 1301555A-03A**

**EPA METHOD TO-15 GC/MS**

| | | | |
|---|---|---|---|
| **File Name:** | **14020443** | **Date of Collection:** | **1/25/13 11:00:00 AM** |
| **Dil. Factor:** | **8.33** | **Date of Analysis:** | **2/5/13 11:40 AM** |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 42 | Not Detected | 200 | Not Detected |
| Freon 114 | 42 | Not Detected | 290 | Not Detected |
| Chloromethane | 170 | Not Detected | 340 | Not Detected |
| Vinyl Chloride | 42 | Not Detected | 110 | Not Detected |
| 1,3-Butadiene | 42 | Not Detected | 92 | Not Detected |
| Bromomethane | 42 | Not Detected | 160 | Not Detected |
| Chloroethane | 170 | Not Detected | 440 | Not Detected |
| Freon 11 | 42 | Not Detected | 230 | Not Detected |
| Ethanol | 170 | Not Detected | 310 | Not Detected |
| Freon 113 | 42 | Not Detected | 320 | Not Detected |
| 1,1-Dichloroethene | 42 | Not Detected | 160 | Not Detected |
| Acetone | 170 | Not Detected | 400 | Not Detected |
| 2-Propanol | 170 | 450 | 410 | 1100 |
| Carbon Disulfide | 42 | Not Detected | 130 | Not Detected |
| 3-Chloropropene | 170 | Not Detected | 520 | Not Detected |
| Methylene Chloride | 42 | 10 J | 140 | 36 J |
| Methyl tert-butyl ether | 42 | Not Detected | 150 | Not Detected |
| trans-1,2-Dichloroethene | 42 | Not Detected | 160 | Not Detected |
| Hexane | 42 | 110 | 150 | 380 |
| 1,1-Dichloroethane | 42 | Not Detected | 170 | Not Detected |
| 2-Butanone (Methyl Ethyl Ketone) | 170 | Not Detected | 490 | Not Detected |
| cis-1,2-Dichloroethene | 42 | Not Detected | 160 | Not Detected |
| Tetrahydrofuran | 42 | Not Detected | 120 | Not Detected |
| Chloroform | 42 | Not Detected | 200 | Not Detected |
| 1,1,1-Trichloroethane | 42 | Not Detected | 230 | Not Detected |
| Cyclohexane | 42 | 940 | 140 | 3200 |
| Carbon Tetrachloride | 42 | Not Detected | 260 | Not Detected |
| 2,2,4-Trimethylpentane | 42 | 23000 | 190 | 110000 |
| Benzene | 42 | 20 J | 130 | 65 J |
| 1,2-Dichloroethane | 42 | Not Detected | 170 | Not Detected |
| Heptane | 42 | Not Detected | 170 | Not Detected |
| Trichloroethene | 42 | Not Detected | 220 | Not Detected |
| 1,2-Dichloropropane | 42 | Not Detected | 190 | Not Detected |
| 1,4-Dioxane | 170 | Not Detected | 600 | Not Detected |
| Bromodichloromethane | 42 | Not Detected | 280 | Not Detected |
| cis-1,3-Dichloropropene | 42 | Not Detected | 190 | Not Detected |
| 4-Methyl-2-pentanone | 42 | Not Detected | 170 | Not Detected |
| Toluene | 42 | Not Detected | 160 | Not Detected |
| trans-1,3-Dichloropropene | 42 | Not Detected | 190 | Not Detected |
| 1,1,2-Trichloroethane | 42 | Not Detected | 230 | Not Detected |
| Tetrachloroethene | 42 | Not Detected | 280 | Not Detected |
| 2-Hexanone | 170 | Not Detected | 680 | Not Detected |

eurofins | Air Toxics

**Client Sample ID: VMP-44-20-012513**

**Lab ID#: 1301555A-03A**

**EPA METHOD TO-15 GC/MS**

| | | | |
|---|---|---|---|
| **File Name:** | **14020443** | **Date of Collection: 1/25/13 11:00:00 AM** | |
| **Dil. Factor:** | **8.33** | **Date of Analysis: 2/5/13 11:40 AM** | |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Dibromochloromethane | 42 | Not Detected | 350 | Not Detected |
| 1,2-Dibromoethane (EDB) | 42 | Not Detected | 320 | Not Detected |
| Chlorobenzene | 42 | Not Detected | 190 | Not Detected |
| Ethyl Benzene | 42 | Not Detected | 180 | Not Detected |
| m,p-Xylene | 42 | Not Detected | 180 | Not Detected |
| o-Xylene | 42 | Not Detected | 180 | Not Detected |
| Styrene | 42 | Not Detected | 180 | Not Detected |
| Bromoform | 42 | Not Detected | 430 | Not Detected |
| Cumene | 42 | Not Detected | 200 | Not Detected |
| 1,1,2,2-Tetrachloroethane | 42 | Not Detected | 280 | Not Detected |
| Propylbenzene | 42 | Not Detected | 200 | Not Detected |
| 4-Ethyltoluene | 42 | Not Detected | 200 | Not Detected |
| 1,3,5-Trimethylbenzene | 42 | Not Detected | 200 | Not Detected |
| 1,2,4-Trimethylbenzene | 42 | Not Detected | 200 | Not Detected |
| 1,3-Dichlorobenzene | 42 | Not Detected | 250 | Not Detected |
| 1,4-Dichlorobenzene | 42 | Not Detected | 250 | Not Detected |
| alpha-Chlorotoluene | 42 | Not Detected | 220 | Not Detected |
| 1,2-Dichlorobenzene | 42 | Not Detected | 250 | Not Detected |
| 1,2,4-Trichlorobenzene | 170 | Not Detected | 1200 | Not Detected |
| Hexachlorobutadiene | 170 | Not Detected | 1800 | Not Detected |
| Butane | 170 | 190 | 400 | 460 |
| Isopentane | 170 | 5400 | 490 | 16000 |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| 1,2-Dichloroethane-d4 | 120 | 70-130 |
| Toluene-d8 | 102 | 70-130 |
| 4-Bromofluorobenzene | 101 | 70-130 |

eurofins | Air Toxics

**Client Sample ID: VMP-44-30-012513**

**Lab ID#: 1301555A-04A**

**EPA METHOD TO-15 GC/MS**

| | | | |
|---|---|---|---|
| **File Name:** | **14020444** | **Date of Collection:** | **1/25/13 11:54:00 AM** |
| **Dil. Factor:** | **2.91** | **Date of Analysis:** | **2/5/13 11:59 AM** |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 14 | Not Detected | 72 | Not Detected |
| Freon 114 | 14 | Not Detected | 100 | Not Detected |
| Chloromethane | 58 | Not Detected | 120 | Not Detected |
| Vinyl Chloride | 14 | Not Detected | 37 | Not Detected |
| 1,3-Butadiene | 14 | Not Detected | 32 | Not Detected |
| Bromomethane | 14 | Not Detected | 56 | Not Detected |
| Chloroethane | 58 | Not Detected | 150 | Not Detected |
| Freon 11 | 14 | Not Detected | 82 | Not Detected |
| Ethanol | 58 | ~~15 J~~ | 110 | ~~29 J~~ |
| Freon 113 | 14 | Not Detected | 110 | Not Detected |
| 1,1-Dichloroethene | 14 | Not Detected | 58 | Not Detected |
| Acetone | 58 | 6300 | 140 | 15000 |
| 2-Propanol | 58 | 4300 | 140 | 10000 |
| Carbon Disulfide | 14 | Not Detected | 45 | Not Detected |
| 3-Chloropropene | 58 | Not Detected | 180 | Not Detected |
| Methylene Chloride | 14 | ~~3.1 J~~ | 50 | ~~11 J~~ |
| Methyl tert-butyl ether | 14 | Not Detected | 52 | Not Detected |
| trans-1,2-Dichloroethene | 14 | Not Detected | 58 | Not Detected |
| Hexane | 14 | 4.7 J | 51 | 17 J |
| 1,1-Dichloroethane | 14 | Not Detected | 59 | Not Detected |
| 2-Butanone (Methyl Ethyl Ketone) | 58 | Not Detected | 170 | Not Detected |
| cis-1,2-Dichloroethene | 14 | Not Detected | 58 | Not Detected |
| Tetrahydrofuran | 14 | Not Detected | 43 | Not Detected |
| Chloroform | 14 | Not Detected | 71 | Not Detected |
| 1,1,1-Trichloroethane | 14 | Not Detected | 79 | Not Detected |
| Cyclohexane | 14 | 6.3 J | 50 | 22 J |
| Carbon Tetrachloride | 14 | Not Detected | 92 | Not Detected |
| 2,2,4-Trimethylpentane | 14 | 100 | 68 | 470 |
| Benzene | 14 | 12 J | 46 | 37 J |
| 1,2-Dichloroethane | 14 | Not Detected | 59 | Not Detected |
| Heptane | 14 | Not Detected | 60 | Not Detected |
| Trichloroethene | 14 | Not Detected | 78 | Not Detected |
| 1,2-Dichloropropane | 14 | Not Detected | 67 | Not Detected |
| 1,4-Dioxane | 58 | Not Detected | 210 | Not Detected |
| Bromodichloromethane | 14 | Not Detected | 97 | Not Detected |
| cis-1,3-Dichloropropene | 14 | Not Detected | 66 | Not Detected |
| 4-Methyl-2-pentanone | 14 | Not Detected | 60 | Not Detected |
| Toluene | 14 | Not Detected | 55 | Not Detected |
| trans-1,3-Dichloropropene | 14 | Not Detected | 66 | Not Detected |
| 1,1,2-Trichloroethane | 14 | Not Detected | 79 | Not Detected |
| Tetrachloroethene | 14 | Not Detected | 99 | Not Detected |
| 2-Hexanone | 58 | Not Detected | 240 | Not Detected |

eurofins | Air Toxics

**Client Sample ID: VMP-44-30-012513**

**Lab ID#: 1301555A-04A**

**EPA METHOD TO-15 GC/MS**

| | | | |
|---|---|---|---|
| **File Name:** | **14020444** | **Date of Collection:** | **1/25/13 11:54:00 AM** |
| **Dil. Factor:** | **2.91** | **Date of Analysis:** | **2/5/13 11:59 AM** |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Dibromochloromethane | 14 | Not Detected | 120 | Not Detected |
| 1,2-Dibromoethane (EDB) | 14 | Not Detected | 110 | Not Detected |
| Chlorobenzene | 14 | Not Detected | 67 | Not Detected |
| Ethyl Benzene | 14 | Not Detected | 63 | Not Detected |
| m,p-Xylene | 14 | Not Detected | 63 | Not Detected |
| o-Xylene | 14 | Not Detected | 63 | Not Detected |
| Styrene | 14 | Not Detected | 62 | Not Detected |
| Bromoform | 14 | Not Detected | 150 | Not Detected |
| Cumene | 14 | Not Detected | 72 | Not Detected |
| 1,1,2,2-Tetrachloroethane | 14 | Not Detected | 100 | Not Detected |
| Propylbenzene | 14 | Not Detected | 72 | Not Detected |
| 4-Ethyltoluene | 14 | Not Detected | 72 | Not Detected |
| 1,3,5-Trimethylbenzene | 14 | Not Detected | 72 | Not Detected |
| 1,2,4-Trimethylbenzene | 14 | Not Detected | 72 | Not Detected |
| 1,3-Dichlorobenzene | 14 | Not Detected | 87 | Not Detected |
| 1,4-Dichlorobenzene | 14 | Not Detected | 87 | Not Detected |
| alpha-Chlorotoluene | 14 | Not Detected | 75 | Not Detected |
| 1,2-Dichlorobenzene | 14 | Not Detected | 87 | Not Detected |
| 1,2,4-Trichlorobenzene | 58 | Not Detected | 430 | Not Detected |
| Hexachlorobutadiene | 58 | Not Detected | 620 | Not Detected |
| Butane | 58 | 18 J | 140 | 42 J |
| Isopentane | 58 | 21 J | 170 | 61 J |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| 1,2-Dichloroethane-d4 | 105 | 70-130 |
| Toluene-d8 | 101 | 70-130 |
| 4-Bromofluorobenzene | 104 | 70-130 |

eurofins | Air Toxics

**Client Sample ID: Lab Blank**

**Lab ID#: 1301555A-05A**

**EPA METHOD TO-15 GC/MS**

| | | | |
|---|---|---|---|
| **File Name:** | **14020434a** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 2/4/13 10:12 PM** | |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 5.0 | Not Detected | 25 | Not Detected |
| Freon 114 | 5.0 | Not Detected | 35 | Not Detected |
| Chloromethane | 20 | Not Detected | 41 | Not Detected |
| Vinyl Chloride | 5.0 | Not Detected | 13 | Not Detected |
| 1,3-Butadiene | 5.0 | Not Detected | 11 | Not Detected |
| Bromomethane | 5.0 | Not Detected | 19 | Not Detected |
| Chloroethane | 20 | Not Detected | 53 | Not Detected |
| Freon 11 | 5.0 | Not Detected | 28 | Not Detected |
| Ethanol | 20 | 9.2 J | 38 | 17 J |
| Freon 113 | 5.0 | Not Detected | 38 | Not Detected |
| 1,1-Dichloroethene | 5.0 | Not Detected | 20 | Not Detected |
| Acetone | 20 | Not Detected | 48 | Not Detected |
| 2-Propanol | 20 | Not Detected | 49 | Not Detected |
| Carbon Disulfide | 5.0 | Not Detected | 16 | Not Detected |
| 3-Chloropropene | 20 | Not Detected | 63 | Not Detected |
| Methylene Chloride | 5.0 | 0.95 J | 17 | 3.3 J |
| Methyl tert-butyl ether | 5.0 | Not Detected | 18 | Not Detected |
| trans-1,2-Dichloroethene | 5.0 | Not Detected | 20 | Not Detected |
| Hexane | 5.0 | Not Detected | 18 | Not Detected |
| 1,1-Dichloroethane | 5.0 | Not Detected | 20 | Not Detected |
| 2-Butanone (Methyl Ethyl Ketone) | 20 | Not Detected | 59 | Not Detected |
| cis-1,2-Dichloroethene | 5.0 | Not Detected | 20 | Not Detected |
| Tetrahydrofuran | 5.0 | Not Detected | 15 | Not Detected |
| Chloroform | 5.0 | Not Detected | 24 | Not Detected |
| 1,1,1-Trichloroethane | 5.0 | Not Detected | 27 | Not Detected |
| Cyclohexane | 5.0 | Not Detected | 17 | Not Detected |
| Carbon Tetrachloride | 5.0 | Not Detected | 31 | Not Detected |
| 2,2,4-Trimethylpentane | 5.0 | Not Detected | 23 | Not Detected |
| Benzene | 5.0 | Not Detected | 16 | Not Detected |
| 1,2-Dichloroethane | 5.0 | Not Detected | 20 | Not Detected |
| Heptane | 5.0 | Not Detected | 20 | Not Detected |
| Trichloroethene | 5.0 | Not Detected | 27 | Not Detected |
| 1,2-Dichloropropane | 5.0 | Not Detected | 23 | Not Detected |
| 1,4-Dioxane | 20 | Not Detected | 72 | Not Detected |
| Bromodichloromethane | 5.0 | Not Detected | 34 | Not Detected |
| cis-1,3-Dichloropropene | 5.0 | Not Detected | 23 | Not Detected |
| 4-Methyl-2-pentanone | 5.0 | Not Detected | 20 | Not Detected |
| Toluene | 5.0 | Not Detected | 19 | Not Detected |
| trans-1,3-Dichloropropene | 5.0 | Not Detected | 23 | Not Detected |
| 1,1,2-Trichloroethane | 5.0 | Not Detected | 27 | Not Detected |
| Tetrachloroethene | 5.0 | Not Detected | 34 | Not Detected |
| 2-Hexanone | 20 | Not Detected | 82 | Not Detected |

**Client Sample ID: Lab Blank**

**Lab ID#: 1301555A-05A**

**EPA METHOD TO-15 GC/MS**

| | | | |
|---|---|---|---|
| **File Name:** | **14020434a** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 2/4/13 10:12 PM** | |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Dibromochloromethane | 5.0 | Not Detected | 42 | Not Detected |
| 1,2-Dibromoethane (EDB) | 5.0 | Not Detected | 38 | Not Detected |
| Chlorobenzene | 5.0 | Not Detected | 23 | Not Detected |
| Ethyl Benzene | 5.0 | Not Detected | 22 | Not Detected |
| m,p-Xylene | 5.0 | Not Detected | 22 | Not Detected |
| o-Xylene | 5.0 | Not Detected | 22 | Not Detected |
| Styrene | 5.0 | Not Detected | 21 | Not Detected |
| Bromoform | 5.0 | Not Detected | 52 | Not Detected |
| Cumene | 5.0 | Not Detected | 24 | Not Detected |
| 1,1,2,2-Tetrachloroethane | 5.0 | Not Detected | 34 | Not Detected |
| Propylbenzene | 5.0 | Not Detected | 24 | Not Detected |
| 4-Ethyltoluene | 5.0 | Not Detected | 24 | Not Detected |
| 1,3,5-Trimethylbenzene | 5.0 | Not Detected | 24 | Not Detected |
| 1,2,4-Trimethylbenzene | 5.0 | Not Detected | 24 | Not Detected |
| 1,3-Dichlorobenzene | 5.0 | Not Detected | 30 | Not Detected |
| 1,4-Dichlorobenzene | 5.0 | Not Detected | 30 | Not Detected |
| alpha-Chlorotoluene | 5.0 | Not Detected | 26 | Not Detected |
| 1,2-Dichlorobenzene | 5.0 | Not Detected | 30 | Not Detected |
| 1,2,4-Trichlorobenzene | 20 | Not Detected | 150 | Not Detected |
| Hexachlorobutadiene | 20 | Not Detected | 210 | Not Detected |
| Butane | 20 | Not Detected | 48 | Not Detected |
| Isopentane | 20 | Not Detected | 59 | Not Detected |

J = Estimated value.

**Container Type: NA - Not Applicable**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| 1,2-Dichloroethane-d4 | 103 | 70-130 |
| Toluene-d8 | 99 | 70-130 |
| 4-Bromofluorobenzene | 101 | 70-130 |

eurofins | Air Toxics

**Client Sample ID: CCV**

**Lab ID#: 1301555A-06A**

**EPA METHOD TO-15 GC/MS**

| | | | |
|---|---|---|---|
| **File Name:** | **14020430** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 2/4/13 08:40 PM** | |

| Compound | %Recovery |
|---|---|
| Freon 12 | 111 |
| Freon 114 | 112 |
| Chloromethane | 118 |
| Vinyl Chloride | 106 |
| 1,3-Butadiene | 108 |
| Bromomethane | 114 |
| Chloroethane | 104 |
| Freon 11 | 114 |
| Ethanol | 108 |
| Freon 113 | 102 |
| 1,1-Dichloroethene | 107 |
| Acetone | 104 |
| 2-Propanol | 111 |
| Carbon Disulfide | 93 |
| 3-Chloropropene | 100 |
| Methylene Chloride | 106 |
| Methyl tert-butyl ether | 104 |
| trans-1,2-Dichloroethene | 108 |
| Hexane | 104 |
| 1,1-Dichloroethane | 106 |
| 2-Butanone (Methyl Ethyl Ketone) | 107 |
| cis-1,2-Dichloroethene | 101 |
| Tetrahydrofuran | 106 |
| Chloroform | 108 |
| 1,1,1-Trichloroethane | 104 |
| Cyclohexane | 105 |
| Carbon Tetrachloride | 110 |
| 2,2,4-Trimethylpentane | 107 |
| Benzene | 104 |
| 1,2-Dichloroethane | 109 |
| Heptane | 104 |
| Trichloroethene | 104 |
| 1,2-Dichloropropane | 102 |
| 1,4-Dioxane | 111 |
| Bromodichloromethane | 106 |
| cis-1,3-Dichloropropene | 98 |
| 4-Methyl-2-pentanone | 108 |
| Toluene | 100 |
| trans-1,3-Dichloropropene | 100 |
| 1,1,2-Trichloroethane | 103 |
| Tetrachloroethene | 103 |
| 2-Hexanone | 114 |

eurofins | Air Toxics

**Client Sample ID: CCV**
**Lab ID#: 1301555A-06A**
**EPA METHOD TO-15 GC/MS**

| | | | |
|---|---|---|---|
| **File Name:** | **14020430** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 2/4/13 08:40 PM** | |

| Compound | %Recovery |
|---|---|
| Dibromochloromethane | 109 |
| 1,2-Dibromoethane (EDB) | 108 |
| Chlorobenzene | 104 |
| Ethyl Benzene | 101 |
| m,p-Xylene | 104 |
| o-Xylene | 105 |
| Styrene | 110 |
| Bromoform | 112 |
| Cumene | 109 |
| 1,1,2,2-Tetrachloroethane | 111 |
| Propylbenzene | 110 |
| 4-Ethyltoluene | 114 |
| 1,3,5-Trimethylbenzene | 114 |
| 1,2,4-Trimethylbenzene | 110 |
| 1,3-Dichlorobenzene | 105 |
| 1,4-Dichlorobenzene | 105 |
| alpha-Chlorotoluene | 111 |
| 1,2-Dichlorobenzene | 109 |
| 1,2,4-Trichlorobenzene | 97 |
| Hexachlorobutadiene | 107 |
| Butane | 117 |
| Isopentane | 108 |

**Container Type: NA - Not Applicable**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| 1,2-Dichloroethane-d4 | 104 | 70-130 |
| Toluene-d8 | 100 | 70-130 |
| 4-Bromofluorobenzene | 103 | 70-130 |

eurofins | Air Toxics

**Client Sample ID: LCS**
**Lab ID#: 1301555A-07A**
**EPA METHOD TO-15 GC/MS**

| | | | |
|---|---|---|---|
| **File Name:** | **14020431** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 2/4/13 09:02 PM** | |

| Compound | %Recovery |
|---|---|
| Freon 12 | 94 |
| Freon 114 | 97 |
| Chloromethane | 106 |
| Vinyl Chloride | 95 |
| 1,3-Butadiene | 92 |
| Bromomethane | 97 |
| Chloroethane | 88 |
| Freon 11 | 99 |
| Ethanol | 94 |
| Freon 113 | 89 |
| 1,1-Dichloroethene | 102 |
| Acetone | 94 |
| 2-Propanol | 92 |
| Carbon Disulfide | 99 |
| 3-Chloropropene | 91 |
| Methylene Chloride | 92 |
| Methyl tert-butyl ether | 85 |
| trans-1,2-Dichloroethene | 103 |
| Hexane | 86 |
| 1,1-Dichloroethane | 91 |
| 2-Butanone (Methyl Ethyl Ketone) | 83 |
| cis-1,2-Dichloroethene | 88 |
| Tetrahydrofuran | 86 |
| Chloroform | 94 |
| 1,1,1-Trichloroethane | 91 |
| Cyclohexane | 88 |
| Carbon Tetrachloride | 96 |
| 2,2,4-Trimethylpentane | 87 |
| Benzene | 91 |
| 1,2-Dichloroethane | 97 |
| Heptane | 86 |
| Trichloroethene | 92 |
| 1,2-Dichloropropane | 86 |
| 1,4-Dioxane | 89 |
| Bromodichloromethane | 88 |
| cis-1,3-Dichloropropene | 81 |
| 4-Methyl-2-pentanone | 85 |
| Toluene | 85 |
| trans-1,3-Dichloropropene | 80 |
| 1,1,2-Trichloroethane | 92 |
| Tetrachloroethene | 88 |
| 2-Hexanone | 79 |

eurofins | Air Toxics

**Client Sample ID: LCS**

**Lab ID#: 1301555A-07A**

**EPA METHOD TO-15 GC/MS**

| | | | |
|---|---|---|---|
| **File Name:** | **14020431** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 2/4/13 09:02 PM** | |

| Compound | %Recovery |
|---|---|
| Dibromochloromethane | 88 |
| 1,2-Dibromoethane (EDB) | 91 |
| Chlorobenzene | 92 |
| Ethyl Benzene | 85 |
| m,p-Xylene | 90 |
| o-Xylene | 87 |
| Styrene | 86 |
| Bromoform | 90 |
| Cumene | 90 |
| 1,1,2,2-Tetrachloroethane | 96 |
| Propylbenzene | 94 |
| 4-Ethyltoluene | 92 |
| 1,3,5-Trimethylbenzene | 95 |
| 1,2,4-Trimethylbenzene | 90 |
| 1,3-Dichlorobenzene | 95 |
| 1,4-Dichlorobenzene | 91 |
| alpha-Chlorotoluene | 82 |
| 1,2-Dichlorobenzene | 96 |
| 1,2,4-Trichlorobenzene | 98 |
| Hexachlorobutadiene | 98 |
| Butane | 99 |
| Isopentane | 92 |

**Container Type: NA - Not Applicable**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| 1,2-Dichloroethane-d4 | 104 | 70-130 |
| Toluene-d8 | 99 | 70-130 |
| 4-Bromofluorobenzene | 105 | 70-130 |

eurofins | Air Toxics

**Client Sample ID: LCSD**

**Lab ID#: 1301555A-07AA**

**EPA METHOD TO-15 GC/MS**

| | | | |
|---|---|---|---|
| **File Name:** | **14020432** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 2/4/13 09:25 PM** | |

| Compound | %Recovery |
|---|---|
| Freon 12 | 95 |
| Freon 114 | 95 |
| Chloromethane | 104 |
| Vinyl Chloride | 94 |
| 1,3-Butadiene | 94 |
| Bromomethane | 97 |
| Chloroethane | 92 |
| Freon 11 | 97 |
| Ethanol | 90 |
| Freon 113 | 93 |
| 1,1-Dichloroethene | 101 |
| Acetone | 92 |
| 2-Propanol | 88 |
| Carbon Disulfide | 98 |
| 3-Chloropropene | 87 |
| Methylene Chloride | 91 |
| Methyl tert-butyl ether | 84 |
| trans-1,2-Dichloroethene | 105 |
| Hexane | 86 |
| 1,1-Dichloroethane | 90 |
| 2-Butanone (Methyl Ethyl Ketone) | 84 |
| cis-1,2-Dichloroethene | 85 |
| Tetrahydrofuran | 86 |
| Chloroform | 94 |
| 1,1,1-Trichloroethane | 89 |
| Cyclohexane | 86 |
| Carbon Tetrachloride | 96 |
| 2,2,4-Trimethylpentane | 86 |
| Benzene | 89 |
| 1,2-Dichloroethane | 98 |
| Heptane | 82 |
| Trichloroethene | 93 |
| 1,2-Dichloropropane | 89 |
| 1,4-Dioxane | 87 |
| Bromodichloromethane | 90 |
| cis-1,3-Dichloropropene | 79 |
| 4-Methyl-2-pentanone | 79 |
| Toluene | 85 |
| trans-1,3-Dichloropropene | 81 |
| 1,1,2-Trichloroethane | 91 |
| Tetrachloroethene | 88 |
| 2-Hexanone | 79 |

eurofins | Air Toxics

**Client Sample ID: LCSD**

**Lab ID#: 1301555A-07AA**

**EPA METHOD TO-15 GC/MS**

| | | | |
|---|---|---|---|
| **File Name:** | **14020432** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 2/4/13 09:25 PM** | |

| Compound | %Recovery |
|---|---|
| Dibromochloromethane | 86 |
| 1,2-Dibromoethane (EDB) | 90 |
| Chlorobenzene | 91 |
| Ethyl Benzene | 83 |
| m,p-Xylene | 90 |
| o-Xylene | 86 |
| Styrene | 84 |
| Bromoform | 86 |
| Cumene | 92 |
| 1,1,2,2-Tetrachloroethane | 96 |
| Propylbenzene | 93 |
| 4-Ethyltoluene | 89 |
| 1,3,5-Trimethylbenzene | 94 |
| 1,2,4-Trimethylbenzene | 89 |
| 1,3-Dichlorobenzene | 94 |
| 1,4-Dichlorobenzene | 92 |
| alpha-Chlorotoluene | 79 |
| 1,2-Dichlorobenzene | 96 |
| 1,2,4-Trichlorobenzene | 90 |
| Hexachlorobutadiene | 93 |
| Butane | 92 |
| Isopentane | 94 |

**Container Type: NA - Not Applicable**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| 1,2-Dichloroethane-d4 | 103 | 70-130 |
| Toluene-d8 | 100 | 70-130 |
| 4-Bromofluorobenzene | 104 | 70-130 |

# Shell Oil Products Chain Of Custody Record

URS

Air Toxics LTD.
Project Name: Roxana Soil Vapor
Project # 21562850.04001
Lab Vendor #

Please Check Appropriate Box:
☑ ENV. SERVICES ☐ MOTIVA RETAIL ☐ SHELL RETAIL
☐ MOTIVA SD&CH ☐ CONSULTANT ☐ LUBES
☐ SHELL PIPELINE ☐ OTHER

Print Bill To Contact Name: Robert Mcsheggan
PO #:
INCIDENT # (ENV SERVICES): 9 7 2 1 6 6 4 0
☐ CHECK IF NO INCIDENT # APPLIES
DATE: 01/30/13
SAP #: 3 4 0 0 6 1
PAGE: 1 of 1

SAMPLING COMPANY: URS CORPORATION
ADDRESS: 100 HIGHLANDS PLAZA DRIVE WEST - SUITE 300; ST. LOUIS, MO 63110
Send Report To: Air Toxics, LTD 180 Blue Ravine Road, Suite B, Folsom, CA 95630-4719
TELEPHONE: FAX: 314-429-0462
E-mail To: Robert.Mcsheggan@urs.com
SITE ADDRESS: 900 SOUTH CENTRAL AVE - ROXANA
State: IL
PROJECT MANAGER: Elizabeth Kunkel, URS, St. Louis
PHONE NO: 314-743-4179
SAMPLED BY: A. Day, M. Mittermeyer, B. Lehan
Roxana Soil Vapor

TURNAROUND TIME (CALENDAR DAYS):
☑ STANDARD (14 DAY) ☐ 5 DAYS ☐ 3 DAYS ☐ 2 DAYS ☐ 24 HOURS ☐ RESULTS NEEDED ON WEEKEND

☐ 1A - RWQCB REPORT FORMAT ☑ UST AGENCY:

DELIVERABLES: ☐ LEVEL 1 ☐ LEVEL 2 ☐ LEVEL 3 ☑ LEVEL 4 ☐ OTHER (SPECIFY)

☑ SHELL CONTRACT RATE APPLIES
☐ STATE REIMBURSEMENT RATE APPLIES
☐ EDD NOT REQUIRED
☑ RECEIPT VERIFICATION REQUESTED

REQUESTED ANALYSIS

| Lab Use Only | Field Sample Identification | SAMPLING DATE | SAMPLING TIME | Canister Number | Canister Pressure/Vacuum Initial | Final | Receipt | Final (psi) | Modified TO-15 + Butane & Isopentane | ASTM D-1946 + Helium | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | VMP-20-39.5-012313 | 01/23/13 | 942-1012 | 31192 | -30 | -7 | | | X | X | | | | | |
| | VMP-44-10-012513 | 01/25/13 | 829-858 | 30790 | -29.5 | -5 | | | X | X | | | | | |
| | VMP-44-20-012513 | 01/25/13 | 1030-1100 | 11629 | -20 | -6.5 | | | X | X | | | | | |
| | VMP-44-30-012513 | 01/25/13 | 1134-1154 | 12378 | -28.5 | -10 | | | X | X | | | | | |
| | | | | | | | | | X | X | | | | | |
| | | | | | | | | | X | X | | | | | |
| | | | | | | | | | X | X | | | | | |
| | | | | | | | | | X | X | | | | | |
| | | | | | | | | | X | X | | | | | |
| | | | | | | | | | X | X | | | | | |

Turn Around Time: ☑ Normal ☐ Rush ☐ Specify
Lab Use Only
Pressurized by:
Date:
Pressurization Gas: N2 He

ADDITIONAL NOTES:
- 14 day hold time
- Report results between MDL and RL
- Level IV ECVP

1/30/13

| Relinquished by: (Signature) | Received by: (Signature) | Date | Time |
|---|---|---|---|
| | FEDEX | 1/30/13 | 1800 |
| Relinquished by: (Signature) | Received by: (Signature) | 1/31/13 | 0945 |
| Relinquished by: (Signature) | Received by: (Signature) | | |

Custody Seal Intact?
Y N None Temp N/A

1371555

eurofins | Air Toxics

2/13/2013
Ms. Elizabeth Kunkel
URS Corporation
1001 Highlands Plaza Dr. West
Suite 300
St. Louis MO 63110

Project Name: Roxana Soil Vapor
Project #: 21562850.04001
Workorder #: 1301555B

Dear Ms. Elizabeth Kunkel

The following report includes the data for the above referenced project for sample(s) received on 1/31/2013 at Air Toxics Ltd.

The data and associated QC analyzed by Modified ASTM D-1946 are compliant with the project requirements or laboratory criteria with the exception of the deviations noted in the attached case narrative.

Thank you for choosing Air Toxics Ltd. for your air analysis needs. Air Toxics Ltd. is committed to providing accurate data of the highest quality. Please feel free to contact the Project Manager: Kelly Buettner at 916-985-1000 if you have any questions regarding the data in this report.

Regards,

Kelly Buettner

Project Manager

REVIEWED
ON
3/20/13

eurofins | Air Toxics

# WORK ORDER #: 1301555B

Work Order Summary

| | | | |
|---|---|---|---|
| **CLIENT:** | Ms. Elizabeth Kunkel<br>URS Corporation<br>1001 Highlands Plaza Dr. West<br>Suite 300<br>St. Louis, MO 63110 | **BILL TO:** | Accounts Payable Austin<br>URS Corporation<br>P.O. BOX 203970<br>Austin, TX 78720-1088 |
| **PHONE:** | 314-743-4179 | **P.O. #** | 21562735.00013 |
| **FAX:** | | **PROJECT #** | 21562850.04001 Roxana Soil Vapor |
| **DATE RECEIVED:** | 01/31/2013 | **CONTACT:** | Kelly Buettner |
| **DATE COMPLETED:** | 02/13/2013 | | |

| FRACTION # | NAME | TEST | RECEIPT VAC./PRES. | FINAL PRESSURE |
|---|---|---|---|---|
| 01A | VMP-20-39.5-012313 | Modified ASTM D-1946 | 5.6 "Hg | 15 psi |
| 02A | VMP-44-10-012513 | Modified ASTM D-1946 | 3.6 "Hg | 15 psi |
| 03A | VMP-44-20-012513 | Modified ASTM D-1946 | 5.8 "Hg | 15 psi |
| 04A | VMP-44-30-012513 | Modified ASTM D-1946 | 9.2 "Hg | 15 psi |
| 05A | Lab Blank | Modified ASTM D-1946 | NA | NA |
| 05B | Lab Blank | Modified ASTM D-1946 | NA | NA |
| 05C | Lab Blank | Modified ASTM D-1946 | NA | NA |
| 05D | Lab Blank | Modified ASTM D-1946 | NA | NA |
| 06A | LCS | Modified ASTM D-1946 | NA | NA |
| 06AA | LCSD | Modified ASTM D-1946 | NA | NA |
| 06B | LCS | Modified ASTM D-1946 | NA | NA |
| 06BB | LCSD | Modified ASTM D-1946 | NA | NA |

CERTIFIED BY: Heidi Hayes DATE: 02/13/13

Technical Director

Certification numbers: AZ Licensure AZ0775, CA NELAP - 12282CA, NY NELAP - 11291,
TX NELAP - T104704434-12-4, UT NELAP CA009332012-3, WA NELAP - C935
Name of Accrediting Agency: NELAP/ORELAP (Oregon Environmental Laboratory Accreditation Program)
Accreditation number: CA300005, Effective date: 10/18/2012, Expiration date: 10/17/2013.
Eurofins Air Toxics Ltd. certifies that the test results contained in this report meet all requirements of the NELAC standards

This report shall not be reproduced, except in full, without the written approval of Eurofins Air Toxics, Inc

180 BLUE RAVINE ROAD, SUITE B FOLSOM, CA - 9563
(916) 985-1000 . (800) 985-5955 . FAX (916) 985-1020

**LABORATORY NARRATIVE**
**Modified ASTM D-1946**
**URS Corporation**
**Workorder# 1301555B**

Four 1 Liter Summa Canister samples were received on January 31, 2013. The laboratory performed analysis via Modified ASTM Method D-1946 for Methane and fixed gases in air using GC/FID or GC/TCD. The method involves direct injection of 1.0 mL of sample.

On the analytical column employed for this analysis, Oxygen coelutes with Argon. The corresponding peak is quantitated as Oxygen.

Since Nitrogen is used to pressurize samples, the reported Nitrogen values are calculated by adding all the sample components and subtracting from 100%.

Method modifications taken to run these samples are summarized in the table below. Specific project requirements may over-ride the ATL modifications.

| *Requirement* | *ASTM D-1946* | *ATL Modifications* |
|---|---|---|
| Calibration | A single point calibration is performed using a reference standard closely matching the composition of the unknown. | A 3-point calibration curve is performed. Quantitation is based on a daily calibration standard which may or may not resemble the composition of the associated samples. |
| Reference Standard | The composition of any reference standard must be known to within 0.01 mol % for any component. | The standards used by ATL are blended to a >/= 95% accuracy. |
| Sample Injection Volume | Components whose concentrations are in excess of 5 % should not be analyzed by using sample volumes greater than 0.5 mL. | The sample container is connected directly to a fixed volume sample loop of 1.0 mL on the GC. Linear range is defined by the calibration curve. Bags are loaded by vacuum. |
| Normalization | Normalize the mole percent values by multiplying each value by 100 and dividing by the sum of the original values. The sum of the original values should not differ from 100% by more than 1.0%. | Results are not normalized. The sum of the reported values can differ from 100% by as much as 15%, either due to analytical variability or an unusual sample matrix. |
| Precision | Precision requirements established at each concentration level. | Duplicates should agree within 25% RPD for detections > 5 X's the RL. |

**Receiving Notes**

There were no receiving discrepancies.

**Analytical Notes**

As per project specific client request the laboratory has reported estimated values for target compound hits that are below the Reporting Limit but greater than the Method Detection Limit. Concentrations that are below the level at which the canister was certified may be false positives.

The reporting limit for Carbon Monoxide was raised from 0.010% to 0.050%.

**Definition of Data Qualifying Flags**

Seven qualifiers may have been used on the data analysis sheets and indicate as follows:
B - Compound present in laboratory blank greater than reporting limit.
J - Estimated value.
E - Exceeds instrument calibration range.
S - Saturated peak.
Q - Exceeds quality control limits.
U - Compound analyzed for but not detected above the detection limit.
M - Reported value may be biased due to apparent matrix interferences.
File extensions may have been used on the data analysis sheets and indicates as follows:
a-File was requantified
b-File was quantified by a second column and detector
r1-File was requantified for the purpose of reissue

eurofins | Air Toxics

# Summary of Detected Compounds
# NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1946

**Client Sample ID: VMP-20-39.5-012313**

**Lab ID#: 1301555B-01A**

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.25 | 1.5 |
| Nitrogen | 0.25 | 88 |
| Methane | 0.00025 | 0.023 |
| Carbon Dioxide | 0.025 | 9.9 |

**Client Sample ID: VMP-44-10-012513**

**Lab ID#: 1301555B-02A**

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.23 | 7.7 |
| Nitrogen | 0.23 | 85 |
| Methane | 0.00023 | 0.0024 |
| Carbon Dioxide | 0.023 | 7.2 |
| Ethane | 0.0023 | 0.000081 J |

**Client Sample ID: VMP-44-20-012513**

**Lab ID#: 1301555B-03A**

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.25 | 7.3 |
| Nitrogen | 0.25 | 83 |
| Methane | 0.00025 | 0.021 |
| Carbon Dioxide | 0.025 | 10 |
| Ethane | 0.0025 | 0.000081 J |

**Client Sample ID: VMP-44-30-012513**

**Lab ID#: 1301555B-04A**

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.38 | 19 |
| Nitrogen | 0.38 | 71 |
| Methane | 0.00038 | 0.00034 J |

eurofins | Air Toxics

## Summary of Detected Compounds
## NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1946

**Client Sample ID: VMP-44-30-012513**

**Lab ID#: 1301555B-04A**

| | | |
|---|---|---|
| Carbon Dioxide | 0.038 | 0.073 |
| Ethane | 0.0038 | 0.00020 J |
| Helium | 0.19 | 9.9 |

eurofins | Air Toxics

**Client Sample ID: VMP-20-39.5-012313**

**Lab ID#: 1301555B-01A**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1946**

| | | | |
|---|---|---|---|
| **File Name:** | **9020644** | **Date of Collection:** | **1/23/13 10:12:00 AM** |
| **Dil. Factor:** | **2.48** | **Date of Analysis:** | **2/6/13 10:24 PM** |

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.25 | 1.5 |
| Nitrogen | 0.25 | 88 |
| Carbon Monoxide | 0.12 | Not Detected |
| Methane | 0.00025 | 0.023 |
| Carbon Dioxide | 0.025 | 9.9 |
| Ethane | 0.0025 | Not Detected |
| Ethene | 0.0025 | Not Detected |
| Helium | 0.12 | Not Detected |

**Container Type: 1 Liter Summa Canister**

eurofins | Air Toxics

**Client Sample ID: VMP-44-10-012513**

**Lab ID#: 1301555B-02A**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1946**

| | | | |
|---|---|---|---|
| **File Name:** | **9020730** | **Date of Collection:** | **1/25/13 9:50:00 AM** |
| **Dil. Factor:** | **2.30** | **Date of Analysis:** | **2/8/13 07:19 AM** |

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.23 | 7.7 |
| Nitrogen | 0.23 | 85 |
| Carbon Monoxide | 0.12 | Not Detected |
| Methane | 0.00023 | 0.0024 |
| Carbon Dioxide | 0.023 | 7.2 |
| Ethane | 0.0023 | 0.000081 J |
| Ethene | 0.0023 | Not Detected |
| Helium | 0.12 | Not Detected |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

eurofins | Air Toxics

**Client Sample ID: VMP-44-20-012513**

**Lab ID#: 1301555B-03A**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1946**

| | | | |
|---|---|---|---|
| **File Name:** | **9020729** | **Date of Collection:** | **1/25/13 11:00:00 AM** |
| **Dil. Factor:** | **2.50** | **Date of Analysis:** | **2/8/13 06:37 AM** |

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.25 | 7.3 |
| Nitrogen | 0.25 | 83 |
| Carbon Monoxide | 0.12 | Not Detected |
| Methane | 0.00025 | 0.021 |
| Carbon Dioxide | 0.025 | 10 |
| Ethane | 0.0025 | 0.000081 J |
| Ethene | 0.0025 | Not Detected |
| Helium | 0.12 | Not Detected |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

eurofins | Air Toxics

**Client Sample ID: VMP-44-30-012513**

**Lab ID#: 1301555B-04A**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1946**

| | | | |
|---|---|---|---|
| **File Name:** | **9020728** | **Date of Collection:** | **1/25/13 11:54:00 AM** |
| **Dil. Factor:** | **3.78** | **Date of Analysis:** | **2/8/13 06:08 AM** |

| **Compound** | **Rpt. Limit (%)** | **Amount (%)** |
|---|---|---|
| Oxygen | 0.38 | 19 |
| Nitrogen | 0.38 | 71 |
| Carbon Monoxide | 0.19 | Not Detected |
| Methane | 0.00038 | 0.00034 J |
| Carbon Dioxide | 0.038 | 0.073 |
| Ethane | 0.0038 | 0.00020 J |
| Ethene | 0.0038 | Not Detected |
| Helium | 0.19 | 9.9 |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

**Client Sample ID: Lab Blank**

**Lab ID#: 1301555B-05A**

NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1946

| | | | |
|---|---|---|---|
| **File Name:** | **9020639** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 2/6/13 08:37 PM** | |

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.10 | Not Detected |
| Nitrogen | 0.10 | 0.085 J |
| Carbon Monoxide | 0.050 | Not Detected |
| Methane | 0.00010 | Not Detected |
| Carbon Dioxide | 0.010 | Not Detected |
| Ethane | 0.0010 | Not Detected |
| Ethene | 0.0010 | Not Detected |

J = Estimated value.

**Container Type: NA - Not Applicable**

eurofins | Air Toxics

**Client Sample ID: Lab Blank**

**Lab ID#: 1301555B-05B**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1946**

| | | | |
|---|---|---|---|
| **File Name:** | **9020636b** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 2/6/13 07:15 PM** | |

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Helium | 0.050 | Not Detected |

**Container Type: NA - Not Applicable**

eurofins | Air Toxics

**Client Sample ID: Lab Blank**

**Lab ID#: 1301555B-05C**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1946**

| | | | |
|---|---|---|---|
| **File Name:** | **9020708a** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 2/7/13 12:17 PM** | |

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.10 | Not Detected |
| Nitrogen | 0.10 | 0.089 J |
| Carbon Monoxide | 0.050 | Not Detected |
| Methane | 0.00010 | Not Detected |
| Carbon Dioxide | 0.010 | Not Detected |
| Ethane | 0.0010 | Not Detected |
| Ethene | 0.0010 | Not Detected |

J = Estimated value.

**Container Type: NA - Not Applicable**

eurofins | Air Toxics

**Client Sample ID: Lab Blank**

**Lab ID#: 1301555B-05D**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1946**

| | | | |
|---|---|---|---|
| **File Name:** | **9020707b** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 2/7/13 11:55 AM** | |
| **Compound** | | **Rpt. Limit (%)** | **Amount (%)** |
| Helium | | 0.050 | Not Detected |

**Container Type: NA - Not Applicable**

eurofins | Air Toxics

**Client Sample ID: LCS**

**Lab ID#: 1301555B-06A**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1946**

| | | | |
|---|---|---|---|
| **File Name:** | **9020634** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 2/6/13 06:18 PM** | |

| Compound | %Recovery |
|---|---|
| Oxygen | 99 |
| Nitrogen | 100 |
| Carbon Monoxide | 99 |
| Methane | 90 |
| Carbon Dioxide | 101 |
| Ethane | 92 |
| Ethene | 89 |
| Helium | 102 |

**Container Type: NA - Not Applicable**

eurofins | Air Toxics

**Client Sample ID: LCSD**

**Lab ID#: 1301555B-06AA**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1946**

| | | | |
|---|---|---|---|
| **File Name:** | **9020645** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 2/6/13 10:47 PM** | |

| Compound | %Recovery |
|---|---|
| Oxygen | 98 |
| Nitrogen | 100 |
| Carbon Monoxide | 100 |
| Methane | 96 |
| Carbon Dioxide | 101 |
| Ethane | 97 |
| Ethene | 94 |
| Helium | 100 |

**Container Type: NA - Not Applicable**

eurofins | Air Toxics

**Client Sample ID: LCS**

**Lab ID#: 1301555B-06B**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1946**

| | | | |
|---|---|---|---|
| **File Name:** | **9020706** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 2/7/13 11:23 AM** | |

| Compound | %Recovery |
|---|---|
| Oxygen | 99 |
| Nitrogen | 100 |
| Carbon Monoxide | 97 |
| Methane | 98 |
| Carbon Dioxide | 101 |
| Ethane | 100 |
| Ethene | 97 |
| Helium | 100 |

**Container Type: NA - Not Applicable**

eurofins | Air Toxics

**Client Sample ID: LCSD**

**Lab ID#: 1301555B-06BB**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1946**

| | | | |
|---|---|---|---|
| **File Name:** | **9020733** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 2/8/13 09:02 AM** | |

| Compound | %Recovery |
|---|---|
| Oxygen | 98 |
| Nitrogen | 100 |
| Carbon Monoxide | 103 |
| Methane | 99 |
| Carbon Dioxide | 100 |
| Ethane | 100 |
| Ethene | 98 |
| Helium | 100 |

**Container Type: NA - Not Applicable**

# Shell Oil Products Chain Of Custody Record

URS

**Air Toxics LTD.**
**Project Name: Roxana Soil Vapor**
**Project # 21562850.04001**
Lab Vendor #

Please Check Appropriate Box:
☑ DIV. SERVICES ☐ MOTIVA RETAIL ☐ SHELL RETAIL
☐ MOTIVA SOECH ☐ CONSULTANT ☐ LUBES
☐ SHELL PIPELINE ☐ OTHER

Print Bill To Contact Name: Robert Mossbegian
PO #:

INCIDENT # (ENV SERVICES): 9 7 2 1 8 8 4 0
☐ CHECK IF NO INCIDENT # APPLIES
DATE 01/30/13
SAP #: 3 4 0 0 6 1
PAGE 1 of 1

SAMPLING COMPANY: URS CORPORATION
ADDRESS: 100+ HIGHLANDS PLAZA DRIVE WEST - SUITE 300; ST. LOUIS, MO 63110
LABORATORY ADDRESS: Air Toxics, LTD 180 Blue Ravine Road, Suite B, Folsom, CA 95630-4719
TELEPHONE: FAX: 314-429-0462
E-MAIL TO CONTACT PERSON: Robert.Mossbegian@urs.com

SITE ADDRESS: Street and City: 900 SOUTH CENTRAL AVE - ROXANA
State: IL
Zip Code:
Consultant / Project Manager: Elizabeth Kunkel, URS, St. Louis
Telephone No.: 314-743-4179
Fax No.:
Sampler: A. Day, M. Mittermeyer, B. Lehan
Project No.: Roxana Soil Vapor

TURNAROUND TIME (CALENDAR DAYS):
☑ STANDARD (14 DAY) ☐ 5 DAYS ☐ 3 DAYS ☐ 2 DAYS ☐ 24 HOURS ☐ RESULTS NEEDED ON WEEKEND

☐ LA - RWQCB REPORT FORMAT ☑ UST AGENCY:
DELIVERABLES: ☐ LEVEL 1 ☐ LEVEL 2 ☐ LEVEL 3 ☑ LEVEL 4 ☐ OTHER (SPECIFY)

☑ SHELL CONTRACT RATE APPLIES
☐ STATE REIMBURSEMENT RATE APPLIES
☐ EDD NOT NEEDED
☑ RECEIPT VERIFICATION REQUESTED

REQUESTED ANALYSIS

| Lab Use Only | Field Sample Identification | SAMPLING DATE | SAMPLING TIME | Canister Number | Canister Pressure/Vacuum Initial | Canister Pressure/Vacuum Final | Canister Pressure/Vacuum Receipt | Canister Pressure/Vacuum Final (psi) | Modified TO-15 + Butane & Isopentane | ASTM D-1946 + Helium | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | VMP-20-39.5-012313 | 01/23/13 | 942-1012 | 21792 | -30 | -7 | | | X | X | | | | | |
| | VMP-44-10-012513 | 01/25/13 | 920-950 | 22786 | -29.5 | -6 | | | X | X | | | | | |
| | VMP-44-20-012513 | 01/25/13 | 1030-1100 | 11629 | -29 | -6.5 | | | X | X | | | | | |
| | VMP-44-30-012513 | 01/25/13 | 1124-1154 | 12378 | -28.5 | 10 | | | X | X | | | | | |
| | | | | | | | | | X | X | | | | | |
| | | | | | | | | | X | X | | | | | |
| | | | | | | | | | X | X | | | | | |
| | | | | | | | | | X | X | | | | | |
| | | | | | | | | | X | X | | | | | |
| | | | | | | | | | X | X | | | | | |

Turn Around Time: ☑ Normal ☐ Rush ☐ Specify

Lab Use Only
Pressurized by:
Date:
Pressurization Gas: $N_2$ He

ADDITIONAL NOTES:
- 14 day hold time
- Report results between MDL and RL
- Level IV ECVP

| Relinquished by: (Signature) | Received by: (Signature) | Date | Time |
|---|---|---|---|
| | FEDEX | 1/30/13 | 1800 |
| Relinquished by: (Signature) | Received by: (Signature) | 1/31/13 | 0945 |
| Relinquished by: (Signature) | Received by: (Signature) | | |

06/2001 Revision

Custody Seal Intact?
Y N None Temp N/A

1371555

# Roxana Soil Vapor Quarterly – 1st Quarter 2013 Data Review

**Laboratory SDG: 1301567A,B**

**Data Reviewer: Alan Fleisher**

**Peer Reviewer: Elizabeth Kunkel**

**Date Reviewed: 3/20/2013**

**Guidance: USEPA National Functional Guidelines for Superfund Organic Methods Data Review 2008**

| Sample Identification | Sample Identification |
|---|---|
| VMP-9-5-012513 | VMP-9-11.5-012513 |
| VMP-9-11.5-012513-Dup | VMP-9-25.5-013013 |
| VMP-9-38.5-013013 | VMP-10-5-012913 |
| VMP-10-5-012913-Dup | VMP-10-20-012913 |
| VMP-10-30-012913 | VMP-11-5-012913 |
| VMP-11-8-012913 | VMP-11-29-012913 |
| VMP-11-38-013013 | VMP-13-5-012913 |
| VMP-41-10-012913 | VMP-41-20-012913 |
| VMP-41-30-012913 | |

## 1.0 Data Package Completeness

*Were all items delivered as specified in the QAPP and COC as appropriate?*

Yes

## 2.0 Laboratory Case Narrative \ Cooler Receipt Form

*Were problems noted in the laboratory case narrative or cooler receipt form?*

Yes, the laboratory case narrative indicated samples VMP-11-5-012913 and VMP-11-8-012913 were diluted due to high levels of target analytes. Although not indicated in the laboratory case narrative, analytes were detected in the method blank. The Summa Canister for sample VMP-9-5-012513 was found to be leaking prior to ASTM D-1946 analysis; analyte concentrations were reported as qualified. The differences in 2-propanol, butane, and isopentane results for the field duplicate pair, VMP-9-11.5-012513/VMP-9-11.5-012513-Dup were greater than (2X) the reporting level; therefore, results were qualified as estimated. The differences in butane and isopentane results for the field duplicate pair, VMP-10-5-012913/VMP-10-5-012913-Dup were greater than (2X) the reporting level; therefore, results were qualified as estimated. These issues are addressed further in the appropriate sections below.

No issues or discrepancies were noted in the cooler receipt form.

## 3.0 Holding Times

*Were samples extracted/analyzed within applicable limits?*

Yes

## 4.0 Blank Contamination

*Were any analytes detected in the Blanks?*

Yes

| Blank ID | Parameter | Analyte | Concentration/ Amount |
|---|---|---|---|
| 1301567A-18A | TO-15 | Bromomethane | 0.38 ppbv / 1.5 µg/m$^3$ |
| 1301567A-18A | TO-15 | Carbon disulfide | 0.66 ppbv / 2.0 µg/m$^3$ |
| 1301567A-18A | TO-15 | Methylene chloride | 0.19 ppbv / 0.66 µg/m$^3$ |
| 1301567A-18A | TO-15 | trans-1,2-Dichloroethene | 0.16 ppbv / 0.63 µg/m$^3$ |
| 1301567A-18A | TO-15 | cis-1,3-Dichloropropene | 0.10 ppbv / 0.47 µg/m$^3$ |
| 1301567A-18A | TO-15 | 4-Methyl-2-pentanone | 0.12 ppbv / 0.48 µg/m$^3$ |
| 1301567A-18A | TO-15 | Toluene | 0.076 ppbv / 0.29 µg/m$^3$ |
| 1301567A-18A | TO-15 | trans-1,3-Dichloropropene | 0.19 ppbv / 0.86 µg/m$^3$ |
| 1301567A-18A | TO-15 | 1,2-Dibromoethane (EDB) | 0.14 ppbv / 1.1 µg/m$^3$ |
| 1301567A-18A | TO-15 | Chlorobenzene | 0.12 ppbv / 0.56 µg/m$^3$ |
| 1301567A-18A | TO-15 | o-Xylene | 0.080 ppbv / 0.35 µg/m$^3$ |
| 1301567A-18A | TO-15 | Styrene | 0.096 ppbv / 0.41 µg/m$^3$ |
| 1301567A-18A | TO-15 | Cumene | 0.11 ppbv / 0.55 µg/m$^3$ |
| 1301567A-18A | TO-15 | 1,1,2,2-Tetrachloroethane | 0.14 ppbv / 0.93 µg/m$^3$ |
| 1301567A-18A | TO-15 | Propylbenzene | 0.13 ppbv / 0.64 µg/m$^3$ |
| 1301567A-18A | TO-15 | 4-Ethyltoluene | 0.12 ppbv / 0.57 µg/m$^3$ |
| 1301567A-18A | TO-15 | 1,3,5-Trimethylbenzene | 0.19 ppbv / 0.92 µg/m$^3$ |
| 1301567A-18A | TO-15 | 1,2,4-Trimethylbenzene | 0.18 ppbv / 0.89 µg/m$^3$ |
| 1301567A-18A | TO-15 | 1,3-Dichlorobenzene | 0.33 ppbv / 2.0 µg/m$^3$ |
| 1301567A-18A | TO-15 | 1,4-Dichlorobenzene | 0.31 ppbv / 1.9 µg/m$^3$ |
| 1301567A-18A | TO-15 | alpha-Chlorotoluene | 0.20 ppbv / 1.0 µg/m$^3$ |
| 1301567A-18A | TO-15 | 1,2-Dichlorobenzene | 0.33 ppbv / 2.0 µg/m$^3$ |
| 1301567A-18A | TO-15 | 1,2,4-Trichlorobenzene | 1.2 ppbv / 8.6 µg/m$^3$ |
| 1301567A-18A | TO-15 | Hexachlorobutadiene | 0.62 ppbv / 6.6 µg/m$^3$ |
| 1301567A-18B | TO-15 | Carbon disulfide | 0.38 ppbv / 1.2 µg/m$^3$ |
| 1301567A-18B | TO-15 | Methylene chloride | 0.068 ppbv / 0.24 µg/m$^3$ |
| 1301567A-18B | TO-15 | Toluene | 0.035 ppbv / 0.13 µg/m$^3$ |
| 1301567A-18B | TO-15 | 4-Ethyltoluene | 0.080 ppbv / 0.39 µg/m$^3$ |
| 1301567A-18B | TO-15 | 1,3-Dichlorobenzene | 0.13 ppbv / 0.79 µg/m$^3$ |
| 1301567A-18B | TO-15 | 1,4-Dichlorobenzene | 0.13 ppbv / 0.80 µg/m$^3$ |
| 1301567A-18B | TO-15 | 1,2-Dichlorobenzene | 0.10 ppbv / 0.63 µg/m$^3$ |
| 1301567A-18B | TO-15 | 1,2,4-Trichlorbenzene | 0.44 ppbv / 3.3 µg/m$^3$ |
| 1301567A-18B | TO-15 | Hexachlorobutadiene | 0.20 ppbv / 2.1 µg/m$^3$ |
| 1301567B-18B | Natural gases | Nitrogen | 0.089% |

Qualifications due to blank contamination are included in the table below. Analytical data that were reported non-detect or at concentrations greater than five times (5X) the associated blank concentration did not require qualification.

| Sample ID | Parameter | Analyte | New Reporting Limit (RL) | Qualification |
|---|---|---|---|---|
| VMP-9-5-012513 | TO-15 | Carbon disulfide | - | **U** |
| VMP-9-5-012513 | TO-15 | Toluene | - | **U** |
| VMP-9-5-012513 | TO-15 | Tetrachloroethene | - | **U** |
| VMP-9-11.5-012513 | TO-15 | Carbon disulfide | - | **U** |
| VMP-9-11.5-012513 | TO-15 | Tetrachloroethene | - | **U** |
| VMP-9-11.5-012513 | TO-15 | 1,3-Dichlorobenzene | - | **U** |
| VMP-9-11.5-012513 | TO-15 | 1,4-Dichlorobenzene | - | **U** |
| VMP-9-11.5-012513 | TO-15 | 1,2,4-Trichlorobenzene | - | **U** |
| VMP-9-11.5-012513-Dup | TO-15 | Carbon disulfide | - | **U** |
| VMP-9-11.5-012513-Dup | TO-15 | Methylene chloride | - | **U** |
| VMP-9-11.5-012513-Dup | TO-15 | Tetrachloroethene | - | **U** |
| VMP-9-11.5-012513-Dup | TO-15 | o-Xylene | - | **U** |
| VMP-9-11.5-012513-Dup | TO-15 | 4-Ethyltoluene | - | **U** |
| VMP-9-11.5-012513-Dup | TO-15 | 1,3-Dichlorobenzene | - | **U** |
| VMP-9-11.5-012513-Dup | TO-15 | 1,4-Dichlorobenzene | - | **U** |
| VMP-9-11.5-012513-Dup | TO-15 | 1,2,4-Trichlorobenzene | - | **U** |
| VMP-9-25.5-013013 | TO-15 | Methylene chloride | - | **U** |
| VMP-9-25.5-013013 | TO-15 | Toluene | - | **U** |
| VMP-9-25.5-013013 | TO-15 | Tetrachloroethene | - | **U** |
| VMP-9-25.5-013013 | TO-15 | 1,2,4-Trichlorobenzene | - | **U** |
| VMP-9-38.5-013013 | TO-15 | Carbon disulfide | - | **U** |
| VMP-9-38.5-013013 | TO-15 | Toluene | - | **U** |
| VMP-9-38.5-013013 | TO-15 | Tetrachloroethene | - | **U** |
| VMP-9-38.5-013013 | TO-15 | 1,2,4-Trichlorobenzene | - | **U** |
| VMP-10-5-012913 | TO-15 | Carbon disulfide | - | **U** |
| VMP-10-5-012913 | TO-15 | Toluene | - | **U** |
| VMP-10-5-012913 | TO-15 | Tetrachloroethene | - | **U** |
| VMP-10-5-012913 | TO-15 | 4-Ethyltoluene | - | **U** |
| VMP-10-5-012913 | TO-15 | 1,3-Dichlorobenzene | - | **U** |
| VMP-10-5-012913 | TO-15 | 1,4-Dichlorobenzene | - | **U** |
| VMP-10-5-012913 | TO-15 | 1,2,4-Trichlorobenzene | - | **U** |
| VMP-10-5-012913-Dup | TO-15 | Carbon disulfide | - | **U** |
| VMP-10-5-012913-Dup | TO-15 | Methylene chloride | - | **U** |
| VMP-10-5-012913-Dup | TO-15 | Toluene | - | **U** |
| VMP-10-5-012913-Dup | TO-15 | Tetrachloroethene | - | **U** |
| VMP-10-5-012913-Dup | TO-15 | 1,3-Dichlorobenzene | - | **U** |
| VMP-10-5-012913-Dup | TO-15 | 1,4-Dichlorobenzene | - | **U** |
| VMP-10-5-012913-Dup | TO-15 | 1,2,4-Trichlorobenzene | - | **U** |
| VMP-10-20-012913 | TO-15 | Carbon disulfide | - | **U** |
| VMP-10-20-012913 | TO-15 | Toluene | - | **U** |
| VMP-10-20-012913 | TO-15 | Tetrachloroethene | - | **U** |
| VMP-10-20-012913 | TO-15 | 1,4-Dichlorobenzene | - | **U** |
| VMP-10-20-012913 | TO-15 | 1,2,4-Trichlorobenzene | - | **U** |

| Sample ID | Parameter | Analyte | New Reporting Limit (RL) | Qualification |
|---|---|---|---|---|
| VMP-10-30-012913 | TO-15 | Carbon disulfide | - | **U** |
| VMP-10-30-012913 | TO-15 | Toluene | - | **U** |
| VMP-10-30-012913 | TO-15 | 1,4-Dichlorobenzene | - | **U** |
| VMP-10-30-012913 | TO-15 | 1,2,4-Trichlorobenzene | - | **U** |
| VMP-11-29-012913 | TO-15 | Carbon disulfide | - | **U** |
| VMP-11-29-012913 | TO-15 | Methylene chloride | - | **U** |
| VMP-11-29-012913 | TO-15 | 1,2,4-Trichlorobenzene | - | **U** |
| VMP-11-38-013013 | TO-15 | Carbon disulfide | - | **U** |
| VMP-11-38-013013 | TO-15 | Methylene chloride | - | **U** |
| VMP-13-5-012913 | TO-15 | Carbon disulfide | - | **U** |
| VMP-13-5-012913 | TO-15 | Toluene | - | **U** |
| VMP-41-10-012913 | TO-15 | Carbon disulfide | - | **U** |
| VMP-41-10-012913 | TO-15 | Methylene chloride | - | **U** |
| VMP-41-10-012913 | TO-15 | Toluene | - | **U** |
| VMP-41-20-012913 | TO-15 | Carbon disulfide | - | **U** |
| VMP-41-20-012913 | TO-15 | Methylene chloride | - | **U** |
| VMP-41-20-012913 | TO-15 | Toluene | - | **U** |
| VMP-41-20-012913 | TO-15 | 1,2,4-Trichlorobenzene | - | **U** |
| VMP-41-30-012913 | TO-15 | Carbon disulfide | - | **U** |
| VMP-41-30-012913 | TO-15 | Methylene chloride | - | **U** |

## 5.0 Laboratory Control Sample

*Were LCS recoveries within evaluation criteria?*

Yes

## 6.0 Surrogate Recoveries

*Were surrogate recoveries within evaluation criteria?*

Yes

## 7.0 Matrix Spike and Matrix Spike Duplicate Recoveries

*Were MS/MSD samples analyzed as part of this SDG?*

MS/MSD samples are not applicable for vapor samples, due to the inability to spike the samples.

## 8.0 Laboratory Duplicate Results

*Were laboratory duplicate samples collected as part of this SDG?*

No

## 9.0 Field Duplicate Results

*Were field duplicate samples collected as part of this SDG?*

Yes

| Field ID | Field Duplicate ID |
|---|---|
| VMP-9-11.5-012513 | VMP-9-11.5-012513-Dup |
| VMP-10-5-012913 | VMP-10-5-012913-Dup |

*Were field duplicate sample RPDs within evaluation criteria?*

No

| Field ID | Field Duplicate ID | Parameter | Analyte | RPD | Qualification |
|---|---|---|---|---|---|
| VMP-9-11.5-012513 | VMP-9-11.5-012513-Dup | TO-15 | 2-Propanol | **>2X RL** | **J/J** |
| VMP-9-11.5-012513 | VMP-9-11.5-012513-Dup | TO-15 | Butane | **>2X RL** | **J/J** |
| VMP-9-11.5-012513 | VMP-9-11.5-012513-Dup | TO-15 | Isopentane | **>2X RL** | **J/J** |
| VMP-10-5-012913 | VMP-10-5-012913-Dup | TO-15 | Butane | **>2X RL** | **J/J** |
| VMP-10-5-012913 | VMP-10-5-012913-Dup | TO-15 | Isopentane | **>2X RL** | **J/J** |

## 10.0 Sample Dilutions

*For samples that were diluted and nondetect, were undiluted results also reported?*

Not applicable; analytes were detected in samples that were diluted.

## 11.0 Additional Qualifications

*Were additional qualifications applied?*

Yes, the Summa Canister for sample VMP-9-5-012513 was found to be leaking prior to ASTM D-1946 analysis; analyte concentrations were qualified for this sample as summarized in the following table.

| Sample ID | Parameter | Analyte | Qualification |
|---|---|---|---|
| VMP-9-5-012513 | TO-15 | All detects | **J** |
| VMP-9-5-012513 | TO-15 | All non-detects | **UJ** |
| VMP-9-5-012513 | Natural gases | All detects | **J** |
| VMP-9-5-012513 | Natural gases | All non-detects | **UJ** |

eurofins | Air Toxics

2/13/2013
Ms. Elizabeth Kunkel
URS Corporation
1001 Highlands Plaza Dr. West
Suite 300
St. Louis MO 63110

Project Name: Roxana Soil Vapor
Project #: 21562850.04001
Workorder #: 1301567A

Dear Ms. Elizabeth Kunkel

The following report includes the data for the above referenced project for sample(s) received on 1/31/2013 at Air Toxics Ltd.

The data and associated QC analyzed by Modified TO-15 are compliant with the project requirements or laboratory criteria with the exception of the deviations noted in the attached case narrative.

Thank you for choosing Air Toxics Ltd. for your air analysis needs. Air Toxics Ltd. is committed to providing accurate data of the highest quality. Please feel free to contact the Project Manager: Kelly Buettner at 916-985-1000 if you have any questions regarding the data in this report.

Regards,

Kelly Buettner

Kelly Buettner
Project Manager

REVIEWED
ON
3/20/13

eurofins | Air Toxics

# WORK ORDER #: 1301567A

Work Order Summary

| | | | |
|---|---|---|---|
| **CLIENT:** | Ms. Elizabeth Kunkel<br>URS Corporation<br>1001 Highlands Plaza Dr. West<br>Suite 300<br>St. Louis, MO 63110 | **BILL TO:** | Accounts Payable Austin<br>URS Corporation<br>P.O. BOX 203970<br>Austin, TX 78720-1088 |
| **PHONE:** | 314-743-4179 | **P.O. #** | 21562735.00013 |
| **FAX:** | | **PROJECT #** | 21562850.04001 Roxana Soil Vapor |
| **DATE RECEIVED:** | 01/31/2013 | **CONTACT:** | Kelly Buettner |
| **DATE COMPLETED:** | 02/12/2013 | | |

| FRACTION # | NAME | TEST | RECEIPT VAC./PRES. | FINAL PRESSURE |
|---|---|---|---|---|
| 01A | VMP-9-5-012513 | Modified TO-15 | 8.5 "Hg | 15 psi |
| 02A | VMP-9-11.5-012513 | Modified TO-15 | 4.0 "Hg | 15 psi |
| 03A | VMP-9-11.5-012513-DUP | Modified TO-15 | 6.0 "Hg | 15 psi |
| 04A | VMP-9-25.5-013013 | Modified TO-15 | 8.5 "Hg | 15 psi |
| 05A | VMP-9-38.5-013013 | Modified TO-15 | 8.5 "Hg | 15 psi |
| 06A | VMP-10-5-012913 | Modified TO-15 | 8.5 "Hg | 15 psi |
| 07A | VMP-10-5-012913-DUP | Modified TO-15 | 10.5 "Hg | 15 psi |
| 08A | VMP-10-20-012913 | Modified TO-15 | 8.0 "Hg | 15 psi |
| 09A | VMP-10-30-012913 | Modified TO-15 | 10.0 "Hg | 15 psi |
| 10A | VMP-11-5-012913 | Modified TO-15 | 9.0 "Hg | 15 psi |
| 11A | VMP-11-8-012913 | Modified TO-15 | 9.5 "Hg | 15 psi |
| 12A | VMP-11-29-012913 | Modified TO-15 | 9.0 "Hg | 15 psi |
| 13A | VMP-11-38-013013 | Modified TO-15 | 8.0 "Hg | 15 psi |
| 14A | VMP-13-5-012913 | Modified TO-15 | 10.5 "Hg | 15 psi |
| 15A | VMP-41-10-012913 | Modified TO-15 | 9.5 "Hg | 15 psi |
| 16A | VMP-41-20-012913 | Modified TO-15 | 10.0 "Hg | 15 psi |
| 17A | VMP-41-30-012913 | Modified TO-15 | 8.5 "Hg | 15 psi |
| 18A | Lab Blank | Modified TO-15 | NA | NA |
| 18B | Lab Blank | Modified TO-15 | NA | NA |
| 19A | CCV | Modified TO-15 | NA | NA |
| 19B | CCV | Modified TO-15 | NA | NA |
| 20A | LCS | Modified TO-15 | NA | NA |
| 20AA | LCSD | Modified TO-15 | NA | NA |

Continued on next page

eurofins | Air Toxics

# WORK ORDER #: 1301567A

Work Order Summary

| | | | |
|---|---|---|---|
| **CLIENT:** | Ms. Elizabeth Kunkel<br>URS Corporation<br>1001 Highlands Plaza Dr. West<br>Suite 300<br>St. Louis, MO 63110 | **BILL TO:** | Accounts Payable Austin<br>URS Corporation<br>P.O. BOX 203970<br>Austin, TX 78720-1088 |
| **PHONE:** | 314-743-4179 | **P.O. #** | 21562735.00013 |
| **FAX:** | | **PROJECT #** | 21562850.04001 Roxana Soil Vapor |
| **DATE RECEIVED:** | 01/31/2013 | **CONTACT:** | Kelly Buettner |
| **DATE COMPLETED:** | 02/12/2013 | | |

| FRACTION # | NAME | TEST | RECEIPT VAC./PRES. | FINAL PRESSURE |
|---|---|---|---|---|
| 20B | LCS | Modified TO-15 | NA | NA |
| 20BB | LCSD | Modified TO-15 | NA | NA |

CERTIFIED BY: Heidi Hayes DATE: 02/13/13

Technical Director

Certfication numbers: AZ Licensure AZ0775, CA NELAP - 12282CA, NY NELAP - 11291,
TX NELAP - T104704434-12-5, UT NELAP CA009332012-3, WA NELAP - C935
Name of Accrediting Agency: NELAP/ORELAP (Oregon Environmental Laboratory Accreditation Program)
Accreditation number: CA300005, Effective date: 10/18/2011, Expiration date: 10/17/2012.
Eurofins Air Toxics Ltd. certifies that the test results contained in this report meet all requirements of the NELAC standards

This report shall not be reproduced, except in full, without the written approval of Eurofins Air Toxics, Inc.

180 BLUE RAVINE ROAD, SUITE B FOLSOM, CA - 9563
(916) 985-1000 . (800) 985-5955 . FAX (916) 985-1020

**LABORATORY NARRATIVE**
**EPA Method TO-15**
**URS Corporation**
**Workorder# 1301567A**

Seventeen 1 Liter Summa Canister samples were received on January 31, 2013. The laboratory performed analysis via EPA Method TO-15 using GC/MS in the full scan mode.

This workorder was independently validated prior to submittal using 'USEPA National Functional Guidelines' as generally applied to the analysis of volatile organic compounds in air. A rules-based, logic driven, independent validation engine was employed to assess completeness, evaluate pass/fail of relevant project quality control requirements and verification of all quantified amounts.

**Receiving Notes**

There were no receiving discrepancies.

**Analytical Notes**

As per client project requirements, the laboratory has reported estimated values for target compound hits that are below the Reporting Limit but greater than the Method Detection Limit. Concentrations that are below the level at which the canister was certified may be false positives.

Dilution was performed on samples VMP-11-5-012913 and VMP-11-8-012913 due to the presence of high level target species.

**Definition of Data Qualifying Flags**

Eight qualifiers may have been used on the data analysis sheets and indicates as follows:

B - Compound present in laboratory blank greater than reporting limit (background subtraction not performed).
J - Estimated value.
E - Exceeds instrument calibration range.
S - Saturated peak.
Q - Exceeds quality control limits.
U - Compound analyzed for but not detected above the reporting limit.
UJ- Non-detected compound associated with low bias in the CCV and/or LCS.
N - The identification is based on presumptive evidence.

File extensions may have been used on the data analysis sheets and indicates as follows:
a-File was requantified
b-File was quantified by a second column and detector
r1-File was requantified for the purpose of reissue

eurofins | Air Toxics

# Summary of Detected Compounds
# EPA METHOD TO-15 GC/MS FULL SCAN

**Client Sample ID: VMP-9-5-012513**

**Lab ID#: 1301567A-01A**

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 1.4 | 0.57 J | 7.0 | 2.8 J |
| Freon 11 | 1.4 | 0.29 J | 7.9 | 1.6 J |
| Ethanol | 5.6 | 2.6 J | 11 | 5.0 J |
| Acetone | 14 | 2.6 J | 33 | 6.1 J |
| 2-Propanol | 5.6 | 8.5 | 14 | 21 |
| Carbon Disulfide | 5.6 | ~~1.1 J~~ | 18 | ~~3.4 J~~ |
| Methylene Chloride | 14 | 1.7 J | 49 | 5.8 J |
| Hexane | 1.4 | 0.67 J | 5.0 | 2.4 J |
| 2,2,4-Trimethylpentane | 1.4 | 0.23 J | 6.6 | 1.1 J |
| Benzene | 1.4 | 1.4 | 4.5 | 4.6 |
| Toluene | 1.4 | ~~0.31 J~~ | 5.3 | ~~1.2 J~~ |
| Tetrachloroethene | 1.4 | ~~0.42 J~~ | 9.6 | ~~2.8 J~~ |
| Isopentane | 5.6 | 0.73 J | 17 | 2.2 J |

**Client Sample ID: VMP-9-11.5-012513**

**Lab ID#: 1301567A-02A**

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 1.2 | 0.51 J | 5.8 | 2.5 J |
| Freon 11 | 1.2 | 0.31 J | 6.5 | 1.7 J |
| Ethanol | 4.7 | 1.9 J | 8.8 | 3.6 J |
| Acetone | 12 | 5.1 J | 28 | 12 J |
| 2-Propanol | 4.7 | 7.3 | 11 | 18 |
| Carbon Disulfide | 4.7 | ~~0.74 J~~ | 14 | ~~2.3 J~~ |
| Hexane | 1.2 | 2.2 | 4.1 | 7.9 |
| Tetrahydrofuran | 1.2 | 0.44 J | 3.4 | 1.3 J |
| Chloroform | 1.2 | 1.6 | 5.7 | 7.9 |
| Cyclohexane | 1.2 | 2.2 | 4.0 | 7.7 |
| 2,2,4-Trimethylpentane | 1.2 | 1.2 | 5.4 | 5.4 |
| Benzene | 1.2 | 0.63 J | 3.7 | 2.0 J |
| Heptane | 1.2 | 0.86 J | 4.8 | 3.5 J |
| Toluene | 1.2 | 0.33 J | 4.4 | 1.2 J |
| Tetrachloroethene | 1.2 | ~~0.19 J~~ | 7.9 | ~~1.3 J~~ |

eurofins | Air Toxics

# Summary of Detected Compounds
# EPA METHOD TO-15 GC/MS FULL SCAN

**Client Sample ID: VMP-9-11.5-012513**

**Lab ID#: 1301567A-02A**

| | | | | |
|---|---|---|---|---|
| Ethyl Benzene | 1.2 | 0.30 J | 5.0 | 1.3 J |
| 1,3-Dichlorobenzene | 1.2 | ~~0.17 J~~ | 7.0 | ~~1.0 J~~ |
| 1,4-Dichlorobenzene | 1.2 | ~~0.19 J~~ | 7.0 | ~~1.1 J~~ |
| 1,2,4-Trichlorobenzene | 4.7 | ~~0.55 J~~ | 34 | ~~4.1 J~~ |
| Butane | 4.7 | 10 | 11 | 25 |
| Isopentane | 4.7 | 16 | 14 | 49 |

**Client Sample ID: VMP-9-11.5-012513-DUP**

**Lab ID#: 1301567A-03A**

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 1.3 | 0.60 J | 6.2 | 3.0 J |
| Freon 11 | 1.3 | 0.26 J | 7.1 | 1.5 J |
| Acetone | 13 | 2.5 J | 30 | 6.0 J |
| 2-Propanol | 5.0 | 1.8 J J | 12 | 4.5 J |
| Carbon Disulfide | 5.0 | ~~0.91 J~~ | 16 | ~~2.8 J~~ |
| Methylene Chloride | 13 | ~~0.20 J~~ | 44 | ~~0.69 J~~ |
| Hexane | 1.3 | 3.3 | 4.4 | 12 |
| Chloroform | 1.3 | 1.5 | 6.2 | 7.5 |
| Cyclohexane | 1.3 | 3.0 | 4.3 | 10 |
| 2,2,4-Trimethylpentane | 1.3 | 1.8 | 5.9 | 8.3 |
| Benzene | 1.3 | 0.47 J | 4.0 | 1.5 J |
| Heptane | 1.3 | 1.1 J | 5.2 | 4.6 J |
| Toluene | 1.3 | 0.75 J | 4.7 | 2.8 J |
| Tetrachloroethene | 1.3 | ~~0.18 J~~ | 8.5 | ~~1.2 J~~ |
| Ethyl Benzene | 1.3 | 0.36 J | 5.5 | 1.6 J |
| m,p-Xylene | 1.3 | 0.41 J | 5.5 | 1.8 J |
| o-Xylene | 1.3 | ~~0.24 J~~ | 5.5 | ~~1.0 J~~ |
| 4-Ethyltoluene | 1.3 | ~~0.14 J~~ | 6.2 | ~~0.69 J~~ |
| 1,3-Dichlorobenzene | 1.3 | ~~0.16 J~~ | 7.6 | ~~0.98 J~~ |
| 1,4-Dichlorobenzene | 1.3 | ~~0.20 J~~ | 7.6 | ~~1.2 J~~ |
| 1,2,4-Trichlorobenzene | 5.0 | ~~0.43 J~~ | 37 | ~~3.2 J~~ |
| Butane | 5.0 | 22 | 12 | 52 |
| Isopentane | 5.0 | 32 | 15 | 93 |

eurofins | Air Toxics

# Summary of Detected Compounds
# EPA METHOD TO-15 GC/MS FULL SCAN

**Client Sample ID: VMP-9-25.5-013013**

**Lab ID#: 1301567A-04A**

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 1.4 | 0.50 J | 7.0 | 2.5 J |
| Freon 11 | 1.4 | 0.28 J | 7.9 | 1.6 J |
| Acetone | 14 | 8.3 J | 33 | 20 J |
| 2-Propanol | 5.6 | 4.7 J | 14 | 12 J |
| Carbon Disulfide | 5.6 | 0.90 J | 18 | 2.8 J |
| Methylene Chloride | 14 | ~~0.17 J~~ | 49 | ~~0.58 J~~ |
| Hexane | 1.4 | 0.25 J | 5.0 | 0.88 J |
| Chloroform | 1.4 | 2.0 | 6.9 | 9.5 |
| 2,2,4-Trimethylpentane | 1.4 | 0.81 J | 6.6 | 3.8 J |
| Benzene | 1.4 | 0.57 J | 4.5 | 1.8 J |
| 4-Methyl-2-pentanone | 1.4 | 0.42 J | 5.8 | 1.7 J |
| Toluene | 1.4 | ~~0.12 J~~ | 5.3 | ~~0.45 J~~ |
| Tetrachloroethene | 1.4 | ~~0.28 J~~ | 9.6 | ~~1.9 J~~ |
| 1,2,4-Trichlorobenzene | 5.6 | ~~0.48 J~~ | 42 | ~~3.5 J~~ |
| Isopentane | 5.6 | 1.2 J | 17 | 3.6 J |

**Client Sample ID: VMP-9-38.5-013013**

**Lab ID#: 1301567A-05A**

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 1.4 | 0.57 J | 7.0 | 2.8 J |
| Freon 11 | 1.4 | 0.28 J | 7.9 | 1.6 J |
| Ethanol | 5.6 | 2.0 J | 11 | 3.8 J |
| Acetone | 14 | 6.5 J | 33 | 15 J |
| 2-Propanol | 5.6 | 4.4 J | 14 | 11 J |
| Carbon Disulfide | 5.6 | ~~0.86 J~~ | 18 | ~~2.7 J~~ |
| Hexane | 1.4 | 0.39 J | 5.0 | 1.4 J |
| Chloroform | 1.4 | 1.2 J | 6.9 | 5.9 J |
| 2,2,4-Trimethylpentane | 1.4 | 1.1 J | 6.6 | 5.1 J |
| Benzene | 1.4 | 0.58 J | 4.5 | 1.8 J |
| Toluene | 1.4 | ~~0.16 J~~ | 5.3 | ~~0.60 J~~ |
| Tetrachloroethene | 1.4 | ~~0.18 J~~ | 9.6 | ~~1.2 J~~ |
| 1,2,4-Trichlorobenzene | 5.6 | ~~0.44 J~~ | 42 | ~~3.2~~ J |

eurofins | Air Toxics

# Summary of Detected Compounds
# EPA METHOD TO-15 GC/MS FULL SCAN

**Client Sample ID: VMP-9-38.5-013013**

**Lab ID#: 1301567A-05A**

| | | | | |
|---|---|---|---|---|
| Butane | 5.6 | 2.9 J | 13 | 6.8 J |
| Isopentane | 5.6 | 1.3 J | 17 | 4.0 J |

**Client Sample ID: VMP-10-5-012913**

**Lab ID#: 1301567A-06A**

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 1.4 | 0.56 J | 7.0 | 2.8 J |
| Freon 11 | 1.4 | 0.38 J | 7.9 | 2.1 J |
| Acetone | 14 | 3.1 J | 33 | 7.5 J |
| 2-Propanol | 5.6 | 3.0 J | 14 | 7.2 J |
| Carbon Disulfide | 5.6 | ~~1.1 J~~ | 18 | ~~3.3 J~~ |
| Hexane | 1.4 | 2.4 | 5.0 | 8.5 |
| Cyclohexane | 1.4 | 2.3 | 4.8 | 7.9 |
| 2,2,4-Trimethylpentane | 1.4 | 1.5 | 6.6 | 7.0 |
| Benzene | 1.4 | 0.52 J | 4.5 | 1.7 J |
| Heptane | 1.4 | 1.2 J | 5.8 | 4.8 J |
| 4-Methyl-2-pentanone | 1.4 | 0.37 J | 5.8 | 1.5 J |
| Toluene | 1.4 | ~~0.33 J~~ | 5.3 | ~~1.2 J~~ |
| Tetrachloroethene | 1.4 | ~~0.23 J~~ | 9.6 | ~~1.6 J~~ |
| Ethyl Benzene | 1.4 | 0.27 J | 6.1 | 1.2 J |
| 4-Ethyltoluene | 1.4 | ~~0.15 J~~ | 6.9 | ~~0.74 J~~ |
| 1,3-Dichlorobenzene | 1.4 | ~~0.24 J~~ | 8.5 | ~~1.5 J~~ |
| 1,4-Dichlorobenzene | 1.4 | ~~0.30 J~~ | 8.5 | ~~1.8 J~~ |
| 1,2,4-Trichlorobenzene | 5.6 | ~~0.72 J~~ | 42 | ~~5.3 J~~ |
| Butane | 5.6 | 9.1 | 13 | 22 |
| Isopentane | 5.6 | 13 | 17 | 38 |

**Client Sample ID: VMP-10-5-012913-DUP**

**Lab ID#: 1301567A-07A**

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 1.6 | 0.58 J | 7.7 | 2.9 J |
| Freon 11 | 1.6 | 0.27 J | 8.7 | 1.5 J |

eurofins | Air Toxics

# Summary of Detected Compounds
# EPA METHOD TO-15 GC/MS FULL SCAN

**Client Sample ID: VMP-10-5-012913-DUP**

**Lab ID#: 1301567A-07A**

| | | | | |
|---|---|---|---|---|
| Acetone | 16 | 4.3 J | 37 | 10 J |
| 2-Propanol | 6.2 | 1.0 J | 15 | 2.5 J |
| Carbon Disulfide | 6.2 | ~~1.2 J~~ | 19 | ~~3.6 J~~ |
| Methylene Chloride | 16 | ~~0.24 J~~ | 54 | ~~0.84 J~~ |
| Hexane | 1.6 | 3.2 | 5.5 | 11 |
| Cyclohexane | 1.6 | 3.0 | 5.4 | 10 |
| 2,2,4-Trimethylpentane | 1.6 | 1.8 | 7.3 | 8.2 |
| Heptane | 1.6 | 1.2 J | 6.4 | 4.9 J |
| Toluene | 1.6 | ~~0.32 J~~ | 5.8 | ~~1.2 J~~ |
| Tetrachloroethene | 1.6 | ~~0.19 J~~ | 10 | ~~1.3 J~~ |
| 1,3-Dichlorobenzene | 1.6 | ~~0.22 J~~ | 9.3 | ~~1.3 J~~ |
| 1,4-Dichlorobenzene | 1.6 | ~~0.26 J~~ | 9.3 | ~~1.6 J~~ |
| 1,2,4-Trichlorobenzene | 6.2 | ~~0.58 J~~ | 46 | ~~4.3 J~~ |
| Butane | 6.2 | 16 | 15 | 37 |
| Isopentane | 6.2 | 23 | 18 | 67 |

**Client Sample ID: VMP-10-20-012913**

**Lab ID#: 1301567A-08A**

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 1.4 | 0.55 J | 6.8 | 2.7 J |
| Freon 11 | 1.4 | 0.30 J | 7.8 | 1.7 J |
| Acetone | 14 | 4.5 J | 33 | 11 J |
| 2-Propanol | 5.5 | 0.92 J | 14 | 2.3 J |
| Carbon Disulfide | 5.5 | ~~0.87 J~~ | 17 | ~~2.7 J~~ |
| Hexane | 1.4 | 0.82 J | 4.9 | 2.9 J |
| 2,2,4-Trimethylpentane | 1.4 | 1.5 | 6.4 | 6.8 |
| Benzene | 1.4 | 2.4 | 4.4 | 7.8 |
| Toluene | 1.4 | ~~0.22 J~~ | 5.2 | ~~0.84 J~~ |
| Tetrachloroethene | 1.4 | ~~0.23 J~~ | 9.4 | ~~1.6 J~~ |
| 1,4-Dichlorobenzene | 1.4 | ~~0.23 J~~ | 8.3 | ~~1.4 J~~ |
| 1,2,4-Trichlorobenzene | 5.5 | ~~0.44 J~~ | 41 | ~~3.2 J~~ |
| Butane | 5.5 | 2.2 J | 13 | 5.1 J |
| Isopentane | 5.5 | 0.63 J | 16 | 1.9 J |

eurofins | Air Toxics

# Summary of Detected Compounds
# EPA METHOD TO-15 GC/MS FULL SCAN

**Client Sample ID: VMP-10-30-012913**

**Lab ID#: 1301567A-09A**

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 1.5 | 0.56 J | 7.5 | 2.8 J |
| Freon 11 | 1.5 | 0.32 J | 8.5 | 1.8 J |
| Ethanol | 6.1 | 2.2 J | 11 | 4.2 J |
| Acetone | 15 | 5.3 J | 36 | 13 J |
| 2-Propanol | 6.1 | 2.9 J | 15 | 7.1 J |
| Carbon Disulfide | 6.1 | ~~1.4 J~~ | 19 | ~~3.4 J~~ |
| Hexane | 1.5 | 0.26 J | 5.3 | 0.92 J |
| 2,2,4-Trimethylpentane | 1.5 | 1.2 J | 7.1 | 5.4 J |
| Benzene | 1.5 | 2.8 | 4.8 | 9.1 |
| Toluene | 1.5 | ~~0.15 J~~ | 5.7 | ~~0.57 J~~ |
| Tetrachloroethene | 1.5 | ~~0.32 J~~ | 10 | ~~2.2 J~~ |
| 1,4-Dichlorobenzene | 1.5 | ~~0.25 J~~ | 9.1 | ~~1.5 J~~ |
| 1,2,4-Trichlorobenzene | 6.1 | ~~0.58 J~~ | 45 | ~~4.2 J~~ |

**Client Sample ID: VMP-11-5-012913**

**Lab ID#: 1301567A-10A**

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Acetone | 720 | 5600 | 1700 | 13000 |
| 2-Propanol | 290 | 15000 | 710 | 36000 |
| Carbon Disulfide | 290 | 51 J | 900 | 160 J |
| Methylene Chloride | 720 | 89 J | 2500 | 310 J |
| Hexane | 72 | 35 J | 250 | 120 J |
| Heptane | 72 | 56 J | 300 | 230 J |
| Toluene | 72 | 27 J | 270 | 100 J |
| Tetrachloroethene | 72 | 150 | 490 | 1000 |
| Styrene | 72 | 14 J | 310 | 58 J |
| Isopentane | 290 | 98 J | 850 | 290 J |

**Client Sample ID: VMP-11-8-012913**

**Lab ID#: 1301567A-11A**

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|

eurofins | Air Toxics

# Summary of Detected Compounds
# EPA METHOD TO-15 GC/MS FULL SCAN

**Client Sample ID: VMP-11-8-012913**

**Lab ID#: 1301567A-11A**

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Acetone | 98 | 2500 | 230 | 5900 |
| 2-Propanol | 39 | 290 | 97 | 710 |
| Carbon Disulfide | 39 | 5.8 J | 120 | 18 J |
| Toluene | 9.8 | 1.6 J | 37 | 6.2 J |

**Client Sample ID: VMP-11-29-012913**

**Lab ID#: 1301567A-12A**

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 1.4 | 0.60 J | 7.1 | 3.0 J |
| Freon 11 | 1.4 | 0.30 J | 8.1 | 1.7 J |
| Ethanol | 5.8 | 15 | 11 | 28 |
| Acetone | 14 | 17 | 34 | 40 |
| 2-Propanol | 5.8 | 68 | 14 | 170 |
| Carbon Disulfide | 5.8 | ~~1.0 J~~ | 18 | ~~3.3 J~~ |
| Methylene Chloride | 14 | ~~0.29 J~~ | 50 | ~~1.0 J~~ |
| Hexane | 1.4 | 0.36 J | 5.1 | 1.2 J |
| 2-Butanone (Methyl Ethyl Ketone) | 5.8 | 1.5 J | 17 | 4.6 J |
| Tetrahydrofuran | 1.4 | 0.25 J | 4.3 | 0.73 J |
| Chloroform | 1.4 | 58 | 7.0 | 280 |
| 2,2,4-Trimethylpentane | 1.4 | 1.3 J | 6.8 | 6.2 J |
| Benzene | 1.4 | 15 | 4.6 | 49 |
| Bromodichloromethane | 1.4 | 4.2 | 9.7 | 28 |
| Toluene | 1.4 | 1.1 J | 5.4 | 4.2 J |
| Tetrachloroethene | 1.4 | 0.31 J | 9.8 | 2.1 J |
| 1,2,4-Trichlorobenzene | 5.8 | ~~0.42 J~~ | 43 | ~~3.1 J~~ |
| Butane | 5.8 | 1.7 J | 14 | 4.1 J |
| Isopentane | 5.8 | 3.0 J | 17 | 8.7 J |

**Client Sample ID: VMP-11-38-013013**

**Lab ID#: 1301567A-13A**

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|

eurofins | Air Toxics

# Summary of Detected Compounds
# EPA METHOD TO-15 GC/MS FULL SCAN

**Client Sample ID: VMP-11-38-013013**

**Lab ID#: 1301567A-13A**

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 1.4 | 0.56 J | 6.8 | 2.8 J |
| Freon 11 | 1.4 | 0.29 J | 7.8 | 1.6 J |
| Ethanol | 5.5 | 4.2 J | 10 | 8.0 J |
| Acetone | 14 | 9.1 J | 33 | 22 J |
| 2-Propanol | 5.5 | 10 | 14 | 25 |
| Carbon Disulfide | 5.5 | ~~1.8 J~~ | 17 | ~~5.6 J~~ |
| Methylene Chloride | 14 | ~~0.19 J~~ | 48 | ~~0.67 J~~ |
| Methyl tert-butyl ether | 1.4 | 2.2 | 5.0 | 7.9 |
| Hexane | 1.4 | 0.38 J | 4.9 | 1.3 J |
| Chloroform | 1.4 | 19 | 6.7 | 91 |
| 2,2,4-Trimethylpentane | 1.4 | 1.0 J | 6.4 | 4.8 J |
| Benzene | 1.4 | 2.3 | 4.4 | 7.4 |
| Bromodichloromethane | 1.4 | 0.92 J | 9.2 | 6.1 J |
| Toluene | 1.4 | 0.23 J | 5.2 | 0.86 J |
| Tetrachloroethene | 1.4 | 0.19 J | 9.4 | 1.3 J |
| Butane | 5.5 | 4.9 J | 13 | 12 J |
| Isopentane | 5.5 | 6.5 | 16 | 19 |

**Client Sample ID: VMP-13-5-012913**

**Lab ID#: 1301567A-14A**

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 1.6 | 0.69 J | 7.7 | 3.4 J |
| Freon 11 | 1.6 | 0.34 J | 8.7 | 1.9 J |
| Acetone | 16 | 2.6 J | 37 | 6.2 J |
| 2-Propanol | 6.2 | 1.8 J | 15 | 4.4 J |
| Carbon Disulfide | 6.2 | ~~0.98 J~~ | 19 | ~~3.1 J~~ |
| Benzene | 1.6 | 1.2 J | 5.0 | 3.8 J |
| Toluene | 1.6 | ~~0.11 J~~ | 5.8 | ~~0.42 J~~ |

**Client Sample ID: VMP-41-10-012913**

**Lab ID#: 1301567A-15A**

eurofins | Air Toxics

# Summary of Detected Compounds
# EPA METHOD TO-15 GC/MS FULL SCAN

**Client Sample ID: VMP-41-10-012913**

**Lab ID#: 1301567A-15A**

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 1.5 | 0.66 J | 7.3 | 3.3 J |
| Freon 11 | 1.5 | 0.32 J | 8.3 | 1.8 J |
| Acetone | 15 | 2.5 J | 35 | 6.0 J |
| 2-Propanol | 5.9 | 4.2 J | 14 | 10 J |
| Carbon Disulfide | 5.9 | ~~1.0 J~~ | 18 | ~~3.2 J~~ |
| Methylene Chloride | 15 | ~~0.23 J~~ | 51 | ~~0.81 J~~ |
| 2,2,4-Trimethylpentane | 1.5 | 0.35 J | 6.9 | 1.6 J |
| Benzene | 1.5 | 0.56 J | 4.7 | 1.8 J |
| Toluene | 1.5 | ~~0.11 J~~ | 5.6 | ~~0.41 J~~ |

**Client Sample ID: VMP-41-20-012913**

**Lab ID#: 1301567A-16A**

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 1.5 | 0.55 J | 7.5 | 2.7 J |
| Freon 11 | 1.5 | 0.32 J | 8.5 | 1.8 J |
| Acetone | 15 | 4.0 J | 36 | 9.6 J |
| 2-Propanol | 6.1 | 4.3 J | 15 | 10 J |
| Carbon Disulfide | 6.1 | ~~1.0 J~~ | 19 | ~~3.1 J~~ |
| Methylene Chloride | 15 | ~~0.20 J~~ | 53 | ~~0.70 J~~ |
| Hexane | 1.5 | 0.49 J | 5.3 | 1.7 J |
| 2,2,4-Trimethylpentane | 1.5 | 4.4 | 7.1 | 21 |
| Benzene | 1.5 | 1.4 J | 4.8 | 4.4 J |
| Toluene | 1.5 | ~~0.14 J~~ | 5.7 | ~~0.53 J~~ |
| Tetrachloroethene | 1.5 | 0.24 J | 10 | 1.6 J |
| 1,2,4-Trichlorobenzene | 6.1 | ~~0.52 J~~ | 45 | ~~3.9 J~~ |
| Isopentane | 6.1 | 2.6 J | 18 | 7.6 J |

**Client Sample ID: VMP-41-30-012913**

**Lab ID#: 1301567A-17A**

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 1.4 | 0.65 J | 7.0 | 3.2 J |

eurofins | Air Toxics

# Summary of Detected Compounds
# EPA METHOD TO-15 GC/MS FULL SCAN

**Client Sample ID: VMP-41-30-012913**

**Lab ID#: 1301567A-17A**

| | | | | |
|---|---|---|---|---|
| Freon 11 | 1.4 | 0.34 J | 7.9 | 1.9 J |
| Ethanol | 5.6 | 2.9 J | 11 | 5.4 J |
| Acetone | 14 | 4.7 J | 33 | 11 J |
| 2-Propanol | 5.6 | 5.4 J | 14 | 13 J |
| Carbon Disulfide | 5.6 | ~~1.1 J~~ | 18 | ~~3.4 J~~ |
| Methylene Chloride | 14 | ~~0.69 J~~ | 49 | ~~2.4 J~~ |
| Hexane | 1.4 | 2.5 | 5.0 | 8.8 |
| Chloroform | 1.4 | 0.47 J | 6.9 | 2.3 J |
| 2,2,4-Trimethylpentane | 1.4 | 4.2 | 6.6 | 20 |
| Benzene | 1.4 | 2.4 | 4.5 | 7.7 |
| Heptane | 1.4 | 2.0 | 5.8 | 8.2 |
| Toluene | 1.4 | 0.35 J | 5.3 | 1.3 J |
| Tetrachloroethene | 1.4 | 0.40 J | 9.6 | 2.7 J |
| Butane | 5.6 | 8.0 | 13 | 19 |
| Isopentane | 5.6 | 1.9 J | 17 | 5.6 J |

eurofins | Air Toxics

**Client Sample ID: VMP-9-5-012513**

**Lab ID#: 1301567A-01A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | p020523 | **Date of Collection:** | 1/25/13 2:34:00 PM |
| **Dil. Factor:** | 2.82 | **Date of Analysis:** | 2/5/13 10:16 PM |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 1.4 | 0.57 J | 7.0 | 2.8 J |
| Freon 114 | 1.4 | Not Detected | 9.8 | Not Detected |
| Chloromethane | 14 | Not Detected | 29 | Not Detected |
| Vinyl Chloride | 1.4 | Not Detected | 3.6 | Not Detected |
| 1,3-Butadiene | 1.4 | Not Detected | 3.1 | Not Detected |
| Bromomethane | 14 | Not Detected | 55 | Not Detected |
| Chloroethane | 5.6 | Not Detected | 15 | Not Detected |
| Freon 11 | 1.4 | 0.29 J | 7.9 | 1.6 J |
| Ethanol | 5.6 | 2.6 J | 11 | 5.0 J |
| Freon 113 | 1.4 | Not Detected | 11 | Not Detected |
| 1,1-Dichloroethene | 1.4 | Not Detected | 5.6 | Not Detected |
| Acetone | 14 | 2.6 J | 33 | 6.1 J |
| 2-Propanol | 5.6 | 8.5 | 14 | 21 |
| Carbon Disulfide | 5.6 | ~~1.1 J~~ | 18 | ~~3.4 J~~ |
| 3-Chloropropene | 5.6 | Not Detected | 18 | Not Detected |
| Methylene Chloride | 14 | 1.7 J | 49 | 5.8 J |
| Methyl tert-butyl ether | 1.4 | Not Detected | 5.1 | Not Detected |
| trans-1,2-Dichloroethene | 1.4 | Not Detected | 5.6 | Not Detected |
| Hexane | 1.4 | 0.67 J | 5.0 | 2.4 J |
| 1,1-Dichloroethane | 1.4 | Not Detected | 5.7 | Not Detected |
| 2-Butanone (Methyl Ethyl Ketone) | 5.6 | Not Detected | 17 | Not Detected |
| cis-1,2-Dichloroethene | 1.4 | Not Detected | 5.6 | Not Detected |
| Tetrahydrofuran | 1.4 | Not Detected | 4.2 | Not Detected |
| Chloroform | 1.4 | Not Detected | 6.9 | Not Detected |
| 1,1,1-Trichloroethane | 1.4 | Not Detected | 7.7 | Not Detected |
| Cyclohexane | 1.4 | Not Detected | 4.8 | Not Detected |
| Carbon Tetrachloride | 1.4 | Not Detected | 8.9 | Not Detected |
| 2,2,4-Trimethylpentane | 1.4 | 0.23 J | 6.6 | 1.1 J |
| Benzene | 1.4 | 1.4 | 4.5 | 4.6 |
| 1,2-Dichloroethane | 1.4 | Not Detected | 5.7 | Not Detected |
| Heptane | 1.4 | Not Detected | 5.8 | Not Detected |
| Trichloroethene | 1.4 | Not Detected | 7.6 | Not Detected |
| 1,2-Dichloropropane | 1.4 | Not Detected | 6.5 | Not Detected |
| 1,4-Dioxane | 5.6 | Not Detected | 20 | Not Detected |
| Bromodichloromethane | 1.4 | Not Detected | 9.4 | Not Detected |
| cis-1,3-Dichloropropene | 1.4 | Not Detected | 6.4 | Not Detected |
| 4-Methyl-2-pentanone | 1.4 | Not Detected | 5.8 | Not Detected |
| Toluene | 1.4 | ~~0.31 J~~ | 5.3 | ~~1.2 J~~ |
| trans-1,3-Dichloropropene | 1.4 | Not Detected | 6.4 | Not Detected |
| 1,1,2-Trichloroethane | 1.4 | Not Detected | 7.7 | Not Detected |
| Tetrachloroethene | 1.4 | ~~0.42 J~~ | 9.6 | ~~2.8 J~~ |
| 2-Hexanone | 5.6 | Not Detected | 23 | Not Detected |

eurofins | Air Toxics

**Client Sample ID: VMP-9-5-012513**

**Lab ID#: 1301567A-01A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | p020523 | **Date of Collection:** | 1/25/13 2:34:00 PM |
| **Dil. Factor:** | 2.82 | **Date of Analysis:** | 2/5/13 10:16 PM |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Dibromochloromethane | 1.4 | Not Detected | 12 | Not Detected |
| 1,2-Dibromoethane (EDB) | 1.4 | Not Detected | 11 | Not Detected |
| Chlorobenzene | 1.4 | Not Detected | 6.5 | Not Detected |
| Ethyl Benzene | 1.4 | Not Detected | 6.1 | Not Detected |
| m,p-Xylene | 1.4 | Not Detected | 6.1 | Not Detected |
| o-Xylene | 1.4 | Not Detected | 6.1 | Not Detected |
| Styrene | 1.4 | Not Detected | 6.0 | Not Detected |
| Bromoform | 1.4 | Not Detected | 14 | Not Detected |
| Cumene | 1.4 | Not Detected | 6.9 | Not Detected |
| 1,1,2,2-Tetrachloroethane | 1.4 | Not Detected | 9.7 | Not Detected |
| Propylbenzene | 1.4 | Not Detected | 6.9 | Not Detected |
| 4-Ethyltoluene | 1.4 | Not Detected | 6.9 | Not Detected |
| 1,3,5-Trimethylbenzene | 1.4 | Not Detected | 6.9 | Not Detected |
| 1,2,4-Trimethylbenzene | 1.4 | Not Detected | 6.9 | Not Detected |
| 1,3-Dichlorobenzene | 1.4 | Not Detected | 8.5 | Not Detected |
| 1,4-Dichlorobenzene | 1.4 | Not Detected | 8.5 | Not Detected |
| alpha-Chlorotoluene | 1.4 | Not Detected | 7.3 | Not Detected |
| 1,2-Dichlorobenzene | 1.4 | Not Detected | 8.5 | Not Detected |
| 1,2,4-Trichlorobenzene | 5.6 | Not Detected | 42 | Not Detected |
| Hexachlorobutadiene | 5.6 | Not Detected | 60 | Not Detected |
| Butane | 5.6 | Not Detected | 13 | Not Detected |
| Isopentane | 5.6 | 0.73 J | 17 | 2.2 J |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| Toluene-d8 | 97 | 70-130 |
| 1,2-Dichloroethane-d4 | 100 | 70-130 |
| 4-Bromofluorobenzene | 96 | 70-130 |

eurofins | Air Toxics

**Client Sample ID: VMP-9-11.5-012513**

**Lab ID#: 1301567A-02A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | p020508 | **Date of Collection:** | 1/25/13 3:22:00 PM |
| **Dil. Factor:** | 2.33 | **Date of Analysis:** | 2/5/13 01:26 PM |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 1.2 | 0.51 J | 5.8 | 2.5 J |
| Freon 114 | 1.2 | Not Detected | 8.1 | Not Detected |
| Chloromethane | 12 | Not Detected | 24 | Not Detected |
| Vinyl Chloride | 1.2 | Not Detected | 3.0 | Not Detected |
| 1,3-Butadiene | 1.2 | Not Detected | 2.6 | Not Detected |
| Bromomethane | 12 | Not Detected | 45 | Not Detected |
| Chloroethane | 4.7 | Not Detected | 12 | Not Detected |
| Freon 11 | 1.2 | 0.31 J | 6.5 | 1.7 J |
| Ethanol | 4.7 | 1.9 J | 8.8 | 3.6 J |
| Freon 113 | 1.2 | Not Detected | 8.9 | Not Detected |
| 1,1-Dichloroethene | 1.2 | Not Detected | 4.6 | Not Detected |
| Acetone | 12 | 5.1 J | 28 | 12 J |
| 2-Propanol | 4.7 | 7.3 J | 11 | 18 |
| Carbon Disulfide | 4.7 | ~~0.74 J~~ | 14 | ~~2.3 J~~ |
| 3-Chloropropene | 4.7 | Not Detected | 14 | Not Detected |
| Methylene Chloride | 12 | Not Detected | 40 | Not Detected |
| Methyl tert-butyl ether | 1.2 | Not Detected | 4.2 | Not Detected |
| trans-1,2-Dichloroethene | 1.2 | Not Detected | 4.6 | Not Detected |
| Hexane | 1.2 | 2.2 | 4.1 | 7.9 |
| 1,1-Dichloroethane | 1.2 | Not Detected | 4.7 | Not Detected |
| 2-Butanone (Methyl Ethyl Ketone) | 4.7 | Not Detected | 14 | Not Detected |
| cis-1,2-Dichloroethene | 1.2 | Not Detected | 4.6 | Not Detected |
| Tetrahydrofuran | 1.2 | 0.44 J | 3.4 | 1.3 J |
| Chloroform | 1.2 | 1.6 | 5.7 | 7.9 |
| 1,1,1-Trichloroethane | 1.2 | Not Detected | 6.4 | Not Detected |
| Cyclohexane | 1.2 | 2.2 | 4.0 | 7.7 |
| Carbon Tetrachloride | 1.2 | Not Detected | 7.3 | Not Detected |
| 2,2,4-Trimethylpentane | 1.2 | 1.2 | 5.4 | 5.4 |
| Benzene | 1.2 | 0.63 J | 3.7 | 2.0 J |
| 1,2-Dichloroethane | 1.2 | Not Detected | 4.7 | Not Detected |
| Heptane | 1.2 | 0.86 J | 4.8 | 3.5 J |
| Trichloroethene | 1.2 | Not Detected | 6.3 | Not Detected |
| 1,2-Dichloropropane | 1.2 | Not Detected | 5.4 | Not Detected |
| 1,4-Dioxane | 4.7 | Not Detected | 17 | Not Detected |
| Bromodichloromethane | 1.2 | Not Detected | 7.8 | Not Detected |
| cis-1,3-Dichloropropene | 1.2 | Not Detected | 5.3 | Not Detected |
| 4-Methyl-2-pentanone | 1.2 | Not Detected | 4.8 | Not Detected |
| Toluene | 1.2 | 0.33 J | 4.4 | 1.2 J |
| trans-1,3-Dichloropropene | 1.2 | Not Detected | 5.3 | Not Detected |
| 1,1,2-Trichloroethane | 1.2 | Not Detected | 6.4 | Not Detected |
| Tetrachloroethene | 1.2 | ~~0.19 J~~ | 7.9 | ~~1.3 J~~ |
| 2-Hexanone | 4.7 | Not Detected | 19 | Not Detected |

eurofins | Air Toxics

**Client Sample ID: VMP-9-11.5-012513**

**Lab ID#: 1301567A-02A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p020508** | **Date of Collection: 1/25/13 3:22:00 PM** | |
| **Dil. Factor:** | **2.33** | **Date of Analysis: 2/5/13 01:26 PM** | |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Dibromochloromethane | 1.2 | Not Detected | 9.9 | Not Detected |
| 1,2-Dibromoethane (EDB) | 1.2 | Not Detected | 9.0 | Not Detected |
| Chlorobenzene | 1.2 | Not Detected | 5.4 | Not Detected |
| Ethyl Benzene | 1.2 | 0.30 J | 5.0 | 1.3 J |
| m,p-Xylene | 1.2 | Not Detected | 5.0 | Not Detected |
| o-Xylene | 1.2 | Not Detected | 5.0 | Not Detected |
| Styrene | 1.2 | Not Detected | 5.0 | Not Detected |
| Bromoform | 1.2 | Not Detected | 12 | Not Detected |
| Cumene | 1.2 | Not Detected | 5.7 | Not Detected |
| 1,1,2,2-Tetrachloroethane | 1.2 | Not Detected | 8.0 | Not Detected |
| Propylbenzene | 1.2 | Not Detected | 5.7 | Not Detected |
| 4-Ethyltoluene | 1.2 | Not Detected | 5.7 | Not Detected |
| 1,3,5-Trimethylbenzene | 1.2 | Not Detected | 5.7 | Not Detected |
| 1,2,4-Trimethylbenzene | 1.2 | Not Detected | 5.7 | Not Detected |
| 1,3-Dichlorobenzene | 1.2 | ~~0.17 J~~ | 7.0 | ~~4.0 J~~ |
| 1,4-Dichlorobenzene | 1.2 | ~~0.19 J~~ | 7.0 | ~~4.1 J~~ |
| alpha-Chlorotoluene | 1.2 | Not Detected | 6.0 | Not Detected |
| 1,2-Dichlorobenzene | 1.2 | Not Detected | 7.0 | Not Detected |
| 1,2,4-Trichlorobenzene | 4.7 | ~~0.55 J~~ | 34 | ~~4.1 J~~ |
| Hexachlorobutadiene | 4.7 | Not Detected | 50 | Not Detected |
| Butane | 4.7 | 10 | 11 | 25 |
| Isopentane | 4.7 | 16 | 14 | 49 |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| Toluene-d8 | 97 | 70-130 |
| 1,2-Dichloroethane-d4 | 98 | 70-130 |
| 4-Bromofluorobenzene | 94 | 70-130 |

eurofins | Air Toxics

**Client Sample ID: VMP-9-11.5-012513-DUP**

**Lab ID#: 1301567A-03A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | p020509 | **Date of Collection:** | 1/25/13 3:22:00 PM |
| **Dil. Factor:** | 2.52 | **Date of Analysis:** | 2/5/13 02:01 PM |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 1.3 | 0.60 J | 6.2 | 3.0 J |
| Freon 114 | 1.3 | Not Detected | 8.8 | Not Detected |
| Chloromethane | 13 | Not Detected | 26 | Not Detected |
| Vinyl Chloride | 1.3 | Not Detected | 3.2 | Not Detected |
| 1,3-Butadiene | 1.3 | Not Detected | 2.8 | Not Detected |
| Bromomethane | 13 | Not Detected | 49 | Not Detected |
| Chloroethane | 5.0 | Not Detected | 13 | Not Detected |
| Freon 11 | 1.3 | 0.26 J | 7.1 | 1.5 J |
| Ethanol | 5.0 | Not Detected | 9.5 | Not Detected |
| Freon 113 | 1.3 | Not Detected | 9.6 | Not Detected |
| 1,1-Dichloroethene | 1.3 | Not Detected | 5.0 | Not Detected |
| Acetone | 13 | 2.5 J | 30 | 6.0 J |
| 2-Propanol | 5.0 | 1.8 J J | 12 | 4.5 J |
| Carbon Disulfide | 5.0 | ~~0.91 J~~ U | 16 | ~~2.8 J~~ U |
| 3-Chloropropene | 5.0 | Not Detected | 16 | Not Detected |
| Methylene Chloride | 13 | ~~0.20 J~~ U | 44 | ~~0.69 J~~ U |
| Methyl tert-butyl ether | 1.3 | Not Detected | 4.5 | Not Detected |
| trans-1,2-Dichloroethene | 1.3 | Not Detected | 5.0 | Not Detected |
| Hexane | 1.3 | 3.3 | 4.4 | 12 |
| 1,1-Dichloroethane | 1.3 | Not Detected | 5.1 | Not Detected |
| 2-Butanone (Methyl Ethyl Ketone) | 5.0 | Not Detected | 15 | Not Detected |
| cis-1,2-Dichloroethene | 1.3 | Not Detected | 5.0 | Not Detected |
| Tetrahydrofuran | 1.3 | Not Detected | 3.7 | Not Detected |
| Chloroform | 1.3 | 1.5 | 6.2 | 7.5 |
| 1,1,1-Trichloroethane | 1.3 | Not Detected | 6.9 | Not Detected |
| Cyclohexane | 1.3 | 3.0 | 4.3 | 10 |
| Carbon Tetrachloride | 1.3 | Not Detected | 7.9 | Not Detected |
| 2,2,4-Trimethylpentane | 1.3 | 1.8 | 5.9 | 8.3 |
| Benzene | 1.3 | 0.47 J | 4.0 | 1.5 J |
| 1,2-Dichloroethane | 1.3 | Not Detected | 5.1 | Not Detected |
| Heptane | 1.3 | 1.1 J | 5.2 | 4.6 J |
| Trichloroethene | 1.3 | Not Detected | 6.8 | Not Detected |
| 1,2-Dichloropropane | 1.3 | Not Detected | 5.8 | Not Detected |
| 1,4-Dioxane | 5.0 | Not Detected | 18 | Not Detected |
| Bromodichloromethane | 1.3 | Not Detected | 8.4 | Not Detected |
| cis-1,3-Dichloropropene | 1.3 | Not Detected | 5.7 | Not Detected |
| 4-Methyl-2-pentanone | 1.3 | Not Detected | 5.2 | Not Detected |
| Toluene | 1.3 | 0.75 J | 4.7 | 2.8 J |
| trans-1,3-Dichloropropene | 1.3 | Not Detected | 5.7 | Not Detected |
| 1,1,2-Trichloroethane | 1.3 | Not Detected | 6.9 | Not Detected |
| Tetrachloroethene | 1.3 | ~~0.18 J~~ U | 8.5 | ~~1.2 J~~ U |
| 2-Hexanone | 5.0 | Not Detected | 21 | Not Detected |

eurofins | Air Toxics

**Client Sample ID: VMP-9-11.5-012513-DUP**

**Lab ID#: 1301567A-03A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | p020509 | **Date of Collection:** | 1/25/13 3:22:00 PM |
| **Dil. Factor:** | 2.52 | **Date of Analysis:** | 2/5/13 02:01 PM |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Dibromochloromethane | 1.3 | Not Detected | 11 | Not Detected |
| 1,2-Dibromoethane (EDB) | 1.3 | Not Detected | 9.7 | Not Detected |
| Chlorobenzene | 1.3 | Not Detected | 5.8 | Not Detected |
| Ethyl Benzene | 1.3 | 0.36 J | 5.5 | 1.6 J |
| m,p-Xylene | 1.3 | 0.41 J | 5.5 | 1.8 J |
| o-Xylene | 1.3 | ~~0.24 J~~ U | 5.5 | ~~1.0 J~~ U |
| Styrene | 1.3 | Not Detected | 5.4 | Not Detected |
| Bromoform | 1.3 | Not Detected | 13 | Not Detected |
| Cumene | 1.3 | Not Detected | 6.2 | Not Detected |
| 1,1,2,2-Tetrachloroethane | 1.3 | Not Detected | 8.6 | Not Detected |
| Propylbenzene | 1.3 | Not Detected | 6.2 | Not Detected |
| 4-Ethyltoluene | 1.3 | ~~0.14 J~~ U | 6.2 | ~~0.69 J~~ U |
| 1,3,5-Trimethylbenzene | 1.3 | Not Detected | 6.2 | Not Detected |
| 1,2,4-Trimethylbenzene | 1.3 | Not Detected | 6.2 | Not Detected |
| 1,3-Dichlorobenzene | 1.3 | ~~0.16 J~~ U | 7.6 | ~~0.96 J~~ U |
| 1,4-Dichlorobenzene | 1.3 | ~~0.20 J~~ U | 7.6 | ~~1.2 J~~ U |
| alpha-Chlorotoluene | 1.3 | Not Detected | 6.5 | Not Detected |
| 1,2-Dichlorobenzene | 1.3 | Not Detected | 7.6 | Not Detected |
| 1,2,4-Trichlorobenzene | 5.0 | ~~0.43 J~~ U | 37 | ~~3.2 J~~ U |
| Hexachlorobutadiene | 5.0 | Not Detected | 54 | Not Detected |
| Butane | 5.0 | 22 J | 12 | 52 J |
| Isopentane | 5.0 | 32 J | 15 | 93 J |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| Toluene-d8 | 97 | 70-130 |
| 1,2-Dichloroethane-d4 | 96 | 70-130 |
| 4-Bromofluorobenzene | 94 | 70-130 |

eurofins | Air Toxics

**Client Sample ID: VMP-9-25.5-013013**

**Lab ID#: 1301567A-04A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p020510** | **Date of Collection:** | **1/30/13 10:30:00 AM** |
| **Dil. Factor:** | **2.82** | **Date of Analysis:** | **2/5/13 02:35 PM** |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 1.4 | 0.50 J | 7.0 | 2.5 J |
| Freon 114 | 1.4 | Not Detected | 9.8 | Not Detected |
| Chloromethane | 14 | Not Detected | 29 | Not Detected |
| Vinyl Chloride | 1.4 | Not Detected | 3.6 | Not Detected |
| 1,3-Butadiene | 1.4 | Not Detected | 3.1 | Not Detected |
| Bromomethane | 14 | Not Detected | 55 | Not Detected |
| Chloroethane | 5.6 | Not Detected | 15 | Not Detected |
| Freon 11 | 1.4 | 0.28 J | 7.9 | 1.6 J |
| Ethanol | 5.6 | Not Detected | 11 | Not Detected |
| Freon 113 | 1.4 | Not Detected | 11 | Not Detected |
| 1,1-Dichloroethene | 1.4 | Not Detected | 5.6 | Not Detected |
| Acetone | 14 | 8.3 J | 33 | 20 J |
| 2-Propanol | 5.6 | 4.7 J | 14 | 12 J |
| Carbon Disulfide | 5.6 | 0.90 J | 18 | 2.8 J |
| 3-Chloropropene | 5.6 | Not Detected | 18 | Not Detected |
| Methylene Chloride | 14 | ~~0.17 J~~ | 49 | ~~0.58 J~~ |
| Methyl tert-butyl ether | 1.4 | Not Detected | 5.1 | Not Detected |
| trans-1,2-Dichloroethene | 1.4 | Not Detected | 5.6 | Not Detected |
| Hexane | 1.4 | 0.25 J | 5.0 | 0.88 J |
| 1,1-Dichloroethane | 1.4 | Not Detected | 5.7 | Not Detected |
| 2-Butanone (Methyl Ethyl Ketone) | 5.6 | Not Detected | 17 | Not Detected |
| cis-1,2-Dichloroethene | 1.4 | Not Detected | 5.6 | Not Detected |
| Tetrahydrofuran | 1.4 | Not Detected | 4.2 | Not Detected |
| Chloroform | 1.4 | 2.0 | 6.9 | 9.5 |
| 1,1,1-Trichloroethane | 1.4 | Not Detected | 7.7 | Not Detected |
| Cyclohexane | 1.4 | Not Detected | 4.8 | Not Detected |
| Carbon Tetrachloride | 1.4 | Not Detected | 8.9 | Not Detected |
| 2,2,4-Trimethylpentane | 1.4 | 0.81 J | 6.6 | 3.8 J |
| Benzene | 1.4 | 0.57 J | 4.5 | 1.8 J |
| 1,2-Dichloroethane | 1.4 | Not Detected | 5.7 | Not Detected |
| Heptane | 1.4 | Not Detected | 5.8 | Not Detected |
| Trichloroethene | 1.4 | Not Detected | 7.6 | Not Detected |
| 1,2-Dichloropropane | 1.4 | Not Detected | 6.5 | Not Detected |
| 1,4-Dioxane | 5.6 | Not Detected | 20 | Not Detected |
| Bromodichloromethane | 1.4 | Not Detected | 9.4 | Not Detected |
| cis-1,3-Dichloropropene | 1.4 | Not Detected | 6.4 | Not Detected |
| 4-Methyl-2-pentanone | 1.4 | 0.42 J | 5.8 | 1.7 J |
| Toluene | 1.4 | ~~0.12 J~~ | 5.3 | ~~0.45 J~~ |
| trans-1,3-Dichloropropene | 1.4 | Not Detected | 6.4 | Not Detected |
| 1,1,2-Trichloroethane | 1.4 | Not Detected | 7.7 | Not Detected |
| Tetrachloroethene | 1.4 | ~~0.28 J~~ | 9.6 | ~~1.9 J~~ |
| 2-Hexanone | 5.6 | Not Detected | 23 | Not Detected |

eurofins | Air Toxics

**Client Sample ID: VMP-9-25.5-013013**

**Lab ID#: 1301567A-04A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p020510** | **Date of Collection:** | **1/30/13 10:30:00 AM** |
| **Dil. Factor:** | **2.82** | **Date of Analysis:** | **2/5/13 02:35 PM** |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Dibromochloromethane | 1.4 | Not Detected | 12 | Not Detected |
| 1,2-Dibromoethane (EDB) | 1.4 | Not Detected | 11 | Not Detected |
| Chlorobenzene | 1.4 | Not Detected | 6.5 | Not Detected |
| Ethyl Benzene | 1.4 | Not Detected | 6.1 | Not Detected |
| m,p-Xylene | 1.4 | Not Detected | 6.1 | Not Detected |
| o-Xylene | 1.4 | Not Detected | 6.1 | Not Detected |
| Styrene | 1.4 | Not Detected | 6.0 | Not Detected |
| Bromoform | 1.4 | Not Detected | 14 | Not Detected |
| Cumene | 1.4 | Not Detected | 6.9 | Not Detected |
| 1,1,2,2-Tetrachloroethane | 1.4 | Not Detected | 9.7 | Not Detected |
| Propylbenzene | 1.4 | Not Detected | 6.9 | Not Detected |
| 4-Ethyltoluene | 1.4 | Not Detected | 6.9 | Not Detected |
| 1,3,5-Trimethylbenzene | 1.4 | Not Detected | 6.9 | Not Detected |
| 1,2,4-Trimethylbenzene | 1.4 | Not Detected | 6.9 | Not Detected |
| 1,3-Dichlorobenzene | 1.4 | Not Detected | 8.5 | Not Detected |
| 1,4-Dichlorobenzene | 1.4 | Not Detected | 8.5 | Not Detected |
| alpha-Chlorotoluene | 1.4 | Not Detected | 7.3 | Not Detected |
| 1,2-Dichlorobenzene | 1.4 | Not Detected | 8.5 | Not Detected |
| 1,2,4-Trichlorobenzene | 5.6 | ~~0.48 J~~ | 42 | ~~3.5 J~~ |
| Hexachlorobutadiene | 5.6 | Not Detected | 60 | Not Detected |
| Butane | 5.6 | Not Detected | 13 | Not Detected |
| Isopentane | 5.6 | 1.2 J | 17 | 3.6 J |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| Toluene-d8 | 99 | 70-130 |
| 1,2-Dichloroethane-d4 | 99 | 70-130 |
| 4-Bromofluorobenzene | 95 | 70-130 |

eurofins | Air Toxics

**Client Sample ID: VMP-9-38.5-013013**

**Lab ID#: 1301567A-05A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | p020511 | **Date of Collection:** | 1/30/13 11:15:00 AM |
| **Dil. Factor:** | 2.82 | **Date of Analysis:** | 2/5/13 03:11 PM |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 1.4 | 0.57 J | 7.0 | 2.8 J |
| Freon 114 | 1.4 | Not Detected | 9.8 | Not Detected |
| Chloromethane | 14 | Not Detected | 29 | Not Detected |
| Vinyl Chloride | 1.4 | Not Detected | 3.6 | Not Detected |
| 1,3-Butadiene | 1.4 | Not Detected | 3.1 | Not Detected |
| Bromomethane | 14 | Not Detected | 55 | Not Detected |
| Chloroethane | 5.6 | Not Detected | 15 | Not Detected |
| Freon 11 | 1.4 | 0.28 J | 7.9 | 1.6 J |
| Ethanol | 5.6 | 2.0 J | 11 | 3.8 J |
| Freon 113 | 1.4 | Not Detected | 11 | Not Detected |
| 1,1-Dichloroethene | 1.4 | Not Detected | 5.6 | Not Detected |
| Acetone | 14 | 6.5 J | 33 | 15 J |
| 2-Propanol | 5.6 | 4.4 J | 14 | 11 J |
| Carbon Disulfide | 5.6 | ~~0.86 J~~ U | 18 | ~~2.7 J~~ U |
| 3-Chloropropene | 5.6 | Not Detected | 18 | Not Detected |
| Methylene Chloride | 14 | Not Detected | 49 | Not Detected |
| Methyl tert-butyl ether | 1.4 | Not Detected | 5.1 | Not Detected |
| trans-1,2-Dichloroethene | 1.4 | Not Detected | 5.6 | Not Detected |
| Hexane | 1.4 | 0.39 J | 5.0 | 1.4 J |
| 1,1-Dichloroethane | 1.4 | Not Detected | 5.7 | Not Detected |
| 2-Butanone (Methyl Ethyl Ketone) | 5.6 | Not Detected | 17 | Not Detected |
| cis-1,2-Dichloroethene | 1.4 | Not Detected | 5.6 | Not Detected |
| Tetrahydrofuran | 1.4 | Not Detected | 4.2 | Not Detected |
| Chloroform | 1.4 | 1.2 J | 6.9 | 5.9 J |
| 1,1,1-Trichloroethane | 1.4 | Not Detected | 7.7 | Not Detected |
| Cyclohexane | 1.4 | Not Detected | 4.8 | Not Detected |
| Carbon Tetrachloride | 1.4 | Not Detected | 8.9 | Not Detected |
| 2,2,4-Trimethylpentane | 1.4 | 1.1 J | 6.6 | 5.1 J |
| Benzene | 1.4 | 0.58 J | 4.5 | 1.8 J |
| 1,2-Dichloroethane | 1.4 | Not Detected | 5.7 | Not Detected |
| Heptane | 1.4 | Not Detected | 5.8 | Not Detected |
| Trichloroethene | 1.4 | Not Detected | 7.6 | Not Detected |
| 1,2-Dichloropropane | 1.4 | Not Detected | 6.5 | Not Detected |
| 1,4-Dioxane | 5.6 | Not Detected | 20 | Not Detected |
| Bromodichloromethane | 1.4 | Not Detected | 9.4 | Not Detected |
| cis-1,3-Dichloropropene | 1.4 | Not Detected | 6.4 | Not Detected |
| 4-Methyl-2-pentanone | 1.4 | Not Detected | 5.8 | Not Detected |
| Toluene | 1.4 | ~~0.16 J~~ U | 5.3 | ~~0.60 J~~ U |
| trans-1,3-Dichloropropene | 1.4 | Not Detected | 6.4 | Not Detected |
| 1,1,2-Trichloroethane | 1.4 | Not Detected | 7.7 | Not Detected |
| Tetrachloroethene | 1.4 | ~~0.18 J~~ U | 9.6 | ~~1.2 J~~ U |
| 2-Hexanone | 5.6 | Not Detected | 23 | Not Detected |

eurofins | Air Toxics

**Client Sample ID: VMP-9-38.5-013013**

**Lab ID#: 1301567A-05A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p020511** | **Date of Collection: 1/30/13 11:15:00 AM** | |
| **Dil. Factor:** | **2.82** | **Date of Analysis: 2/5/13 03:11 PM** | |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Dibromochloromethane | 1.4 | Not Detected | 12 | Not Detected |
| 1,2-Dibromoethane (EDB) | 1.4 | Not Detected | 11 | Not Detected |
| Chlorobenzene | 1.4 | Not Detected | 6.5 | Not Detected |
| Ethyl Benzene | 1.4 | Not Detected | 6.1 | Not Detected |
| m,p-Xylene | 1.4 | Not Detected | 6.1 | Not Detected |
| o-Xylene | 1.4 | Not Detected | 6.1 | Not Detected |
| Styrene | 1.4 | Not Detected | 6.0 | Not Detected |
| Bromoform | 1.4 | Not Detected | 14 | Not Detected |
| Cumene | 1.4 | Not Detected | 6.9 | Not Detected |
| 1,1,2,2-Tetrachloroethane | 1.4 | Not Detected | 9.7 | Not Detected |
| Propylbenzene | 1.4 | Not Detected | 6.9 | Not Detected |
| 4-Ethyltoluene | 1.4 | Not Detected | 6.9 | Not Detected |
| 1,3,5-Trimethylbenzene | 1.4 | Not Detected | 6.9 | Not Detected |
| 1,2,4-Trimethylbenzene | 1.4 | Not Detected | 6.9 | Not Detected |
| 1,3-Dichlorobenzene | 1.4 | Not Detected | 8.5 | Not Detected |
| 1,4-Dichlorobenzene | 1.4 | Not Detected | 8.5 | Not Detected |
| alpha-Chlorotoluene | 1.4 | Not Detected | 7.3 | Not Detected |
| 1,2-Dichlorobenzene | 1.4 | Not Detected | 8.5 | Not Detected |
| 1,2,4-Trichlorobenzene | 5.6 | ~~0.44 J~~ | 42 | ~~3.2 J~~ |
| Hexachlorobutadiene | 5.6 | Not Detected | 60 | Not Detected |
| Butane | 5.6 | 2.9 J | 13 | 6.8 J |
| Isopentane | 5.6 | 1.3 J | 17 | 4.0 J |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| Toluene-d8 | 98 | 70-130 |
| 1,2-Dichloroethane-d4 | 98 | 70-130 |
| 4-Bromofluorobenzene | 97 | 70-130 |

eurofins | Air Toxics

**Client Sample ID: VMP-10-5-012913**

**Lab ID#: 1301567A-06A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p020512** | **Date of Collection:** | **1/29/13 9:46:00 AM** |
| **Dil. Factor:** | **2.82** | **Date of Analysis:** | **2/5/13 04:00 PM** |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 1.4 | 0.56 J | 7.0 | 2.8 J |
| Freon 114 | 1.4 | Not Detected | 9.8 | Not Detected |
| Chloromethane | 14 | Not Detected | 29 | Not Detected |
| Vinyl Chloride | 1.4 | Not Detected | 3.6 | Not Detected |
| 1,3-Butadiene | 1.4 | Not Detected | 3.1 | Not Detected |
| Bromomethane | 14 | Not Detected | 55 | Not Detected |
| Chloroethane | 5.6 | Not Detected | 15 | Not Detected |
| Freon 11 | 1.4 | 0.38 J | 7.9 | 2.1 J |
| Ethanol | 5.6 | Not Detected | 11 | Not Detected |
| Freon 113 | 1.4 | Not Detected | 11 | Not Detected |
| 1,1-Dichloroethene | 1.4 | Not Detected | 5.6 | Not Detected |
| Acetone | 14 | 3.1 J | 33 | 7.5 J |
| 2-Propanol | 5.6 | 3.0 J | 14 | 7.2 J |
| Carbon Disulfide | 5.6 | ~~4.1 J~~ | 18 | ~~3.3 J~~ |
| 3-Chloropropene | 5.6 | Not Detected | 18 | Not Detected |
| Methylene Chloride | 14 | Not Detected | 49 | Not Detected |
| Methyl tert-butyl ether | 1.4 | Not Detected | 5.1 | Not Detected |
| trans-1,2-Dichloroethene | 1.4 | Not Detected | 5.6 | Not Detected |
| Hexane | 1.4 | 2.4 | 5.0 | 8.5 |
| 1,1-Dichloroethane | 1.4 | Not Detected | 5.7 | Not Detected |
| 2-Butanone (Methyl Ethyl Ketone) | 5.6 | Not Detected | 17 | Not Detected |
| cis-1,2-Dichloroethene | 1.4 | Not Detected | 5.6 | Not Detected |
| Tetrahydrofuran | 1.4 | Not Detected | 4.2 | Not Detected |
| Chloroform | 1.4 | Not Detected | 6.9 | Not Detected |
| 1,1,1-Trichloroethane | 1.4 | Not Detected | 7.7 | Not Detected |
| Cyclohexane | 1.4 | 2.3 | 4.8 | 7.9 |
| Carbon Tetrachloride | 1.4 | Not Detected | 8.9 | Not Detected |
| 2,2,4-Trimethylpentane | 1.4 | 1.5 | 6.6 | 7.0 |
| Benzene | 1.4 | 0.52 J | 4.5 | 1.7 J |
| 1,2-Dichloroethane | 1.4 | Not Detected | 5.7 | Not Detected |
| Heptane | 1.4 | 1.2 J | 5.8 | 4.8 J |
| Trichloroethene | 1.4 | Not Detected | 7.6 | Not Detected |
| 1,2-Dichloropropane | 1.4 | Not Detected | 6.5 | Not Detected |
| 1,4-Dioxane | 5.6 | Not Detected | 20 | Not Detected |
| Bromodichloromethane | 1.4 | Not Detected | 9.4 | Not Detected |
| cis-1,3-Dichloropropene | 1.4 | Not Detected | 6.4 | Not Detected |
| 4-Methyl-2-pentanone | 1.4 | 0.37 J | 5.8 | 1.5 J |
| Toluene | 1.4 | ~~0.33 J~~ | 5.3 | ~~1.2 J~~ |
| trans-1,3-Dichloropropene | 1.4 | Not Detected | 6.4 | Not Detected |
| 1,1,2-Trichloroethane | 1.4 | Not Detected | 7.7 | Not Detected |
| Tetrachloroethene | 1.4 | ~~0.23 J~~ | 9.6 | ~~1.6 J~~ |
| 2-Hexanone | 5.6 | Not Detected | 23 | Not Detected |

eurofins | Air Toxics

**Client Sample ID: VMP-10-5-012913**

**Lab ID#: 1301567A-06A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p020512** | **Date of Collection: 1/29/13 9:46:00 AM** | |
| **Dil. Factor:** | **2.82** | **Date of Analysis: 2/5/13 04:00 PM** | |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Dibromochloromethane | 1.4 | Not Detected | 12 | Not Detected |
| 1,2-Dibromoethane (EDB) | 1.4 | Not Detected | 11 | Not Detected |
| Chlorobenzene | 1.4 | Not Detected | 6.5 | Not Detected |
| Ethyl Benzene | 1.4 | 0.27 J | 6.1 | 1.2 J |
| m,p-Xylene | 1.4 | Not Detected | 6.1 | Not Detected |
| o-Xylene | 1.4 | Not Detected | 6.1 | Not Detected |
| Styrene | 1.4 | Not Detected | 6.0 | Not Detected |
| Bromoform | 1.4 | Not Detected | 14 | Not Detected |
| Cumene | 1.4 | Not Detected | 6.9 | Not Detected |
| 1,1,2,2-Tetrachloroethane | 1.4 | Not Detected | 9.7 | Not Detected |
| Propylbenzene | 1.4 | Not Detected | 6.9 | Not Detected |
| 4-Ethyltoluene | 1.4 | ~~0.15 J~~ | 6.9 | ~~0.74 J~~ |
| 1,3,5-Trimethylbenzene | 1.4 | Not Detected | 6.9 | Not Detected |
| 1,2,4-Trimethylbenzene | 1.4 | Not Detected | 6.9 | Not Detected |
| 1,3-Dichlorobenzene | 1.4 | ~~0.24 J~~ | 8.5 | ~~1.5 J~~ |
| 1,4-Dichlorobenzene | 1.4 | ~~0.30 J~~ | 8.5 | ~~1.8 J~~ |
| alpha-Chlorotoluene | 1.4 | Not Detected | 7.3 | Not Detected |
| 1,2-Dichlorobenzene | 1.4 | Not Detected | 8.5 | Not Detected |
| 1,2,4-Trichlorobenzene | 5.6 | ~~0.72 J~~ | 42 | ~~5.3 J~~ |
| Hexachlorobutadiene | 5.6 | Not Detected | 60 | Not Detected |
| Butane | 5.6 | 9.1 J | 13 | 22 J |
| Isopentane | 5.6 | 13 J | 17 | 38 J |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| Toluene-d8 | 96 | 70-130 |
| 1,2-Dichloroethane-d4 | 98 | 70-130 |
| 4-Bromofluorobenzene | 95 | 70-130 |

eurofins | Air Toxics

**Client Sample ID: VMP-10-5-012913-DUP**

**Lab ID#: 1301567A-07A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p020513** | **Date of Collection:** | **1/29/13 9:46:00 AM** |
| **Dil. Factor:** | **3.11** | **Date of Analysis:** | **2/5/13 04:36 PM** |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 1.6 | 0.58 J | 7.7 | 2.9 J |
| Freon 114 | 1.6 | Not Detected | 11 | Not Detected |
| Chloromethane | 16 | Not Detected | 32 | Not Detected |
| Vinyl Chloride | 1.6 | Not Detected | 4.0 | Not Detected |
| 1,3-Butadiene | 1.6 | Not Detected | 3.4 | Not Detected |
| Bromomethane | 16 | Not Detected | 60 | Not Detected |
| Chloroethane | 6.2 | Not Detected | 16 | Not Detected |
| Freon 11 | 1.6 | 0.27 J | 8.7 | 1.5 J |
| Ethanol | 6.2 | Not Detected | 12 | Not Detected |
| Freon 113 | 1.6 | Not Detected | 12 | Not Detected |
| 1,1-Dichloroethene | 1.6 | Not Detected | 6.2 | Not Detected |
| Acetone | 16 | 4.3 J | 37 | 10 J |
| 2-Propanol | 6.2 | 1.0 J | 15 | 2.5 J |
| Carbon Disulfide | 6.2 | ~~1.2 J~~ | 19 | ~~3.6 J~~ |
| 3-Chloropropene | 6.2 | Not Detected | 19 | Not Detected |
| Methylene Chloride | 16 | ~~0.24 J~~ | 54 | ~~0.84 J~~ |
| Methyl tert-butyl ether | 1.6 | Not Detected | 5.6 | Not Detected |
| trans-1,2-Dichloroethene | 1.6 | Not Detected | 6.2 | Not Detected |
| Hexane | 1.6 | 3.2 | 5.5 | 11 |
| 1,1-Dichloroethane | 1.6 | Not Detected | 6.3 | Not Detected |
| 2-Butanone (Methyl Ethyl Ketone) | 6.2 | Not Detected | 18 | Not Detected |
| cis-1,2-Dichloroethene | 1.6 | Not Detected | 6.2 | Not Detected |
| Tetrahydrofuran | 1.6 | Not Detected | 4.6 | Not Detected |
| Chloroform | 1.6 | Not Detected | 7.6 | Not Detected |
| 1,1,1-Trichloroethane | 1.6 | Not Detected | 8.5 | Not Detected |
| Cyclohexane | 1.6 | 3.0 | 5.4 | 10 |
| Carbon Tetrachloride | 1.6 | Not Detected | 9.8 | Not Detected |
| 2,2,4-Trimethylpentane | 1.6 | 1.8 | 7.3 | 8.2 |
| Benzene | 1.6 | Not Detected | 5.0 | Not Detected |
| 1,2-Dichloroethane | 1.6 | Not Detected | 6.3 | Not Detected |
| Heptane | 1.6 | 1.2 J | 6.4 | 4.9 J |
| Trichloroethene | 1.6 | Not Detected | 8.4 | Not Detected |
| 1,2-Dichloropropane | 1.6 | Not Detected | 7.2 | Not Detected |
| 1,4-Dioxane | 6.2 | Not Detected | 22 | Not Detected |
| Bromodichloromethane | 1.6 | Not Detected | 10 | Not Detected |
| cis-1,3-Dichloropropene | 1.6 | Not Detected | 7.0 | Not Detected |
| 4-Methyl-2-pentanone | 1.6 | Not Detected | 6.4 | Not Detected |
| Toluene | 1.6 | ~~0.32 J~~ | 5.8 | ~~1.2 J~~ |
| trans-1,3-Dichloropropene | 1.6 | Not Detected | 7.0 | Not Detected |
| 1,1,2-Trichloroethane | 1.6 | Not Detected | 8.5 | Not Detected |
| Tetrachloroethene | 1.6 | ~~0.19 J~~ | 10 | ~~1.3 J~~ |
| 2-Hexanone | 6.2 | Not Detected | 25 | Not Detected |

eurofins | Air Toxics

**Client Sample ID: VMP-10-5-012913-DUP**

**Lab ID#: 1301567A-07A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p020513** | **Date of Collection:** | **1/29/13 9:46:00 AM** |
| **Dil. Factor:** | **3.11** | **Date of Analysis:** | **2/5/13 04:36 PM** |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Dibromochloromethane | 1.6 | Not Detected | 13 | Not Detected |
| 1,2-Dibromoethane (EDB) | 1.6 | Not Detected | 12 | Not Detected |
| Chlorobenzene | 1.6 | Not Detected | 7.2 | Not Detected |
| Ethyl Benzene | 1.6 | Not Detected | 6.8 | Not Detected |
| m,p-Xylene | 1.6 | Not Detected | 6.8 | Not Detected |
| o-Xylene | 1.6 | Not Detected | 6.8 | Not Detected |
| Styrene | 1.6 | Not Detected | 6.6 | Not Detected |
| Bromoform | 1.6 | Not Detected | 16 | Not Detected |
| Cumene | 1.6 | Not Detected | 7.6 | Not Detected |
| 1,1,2,2-Tetrachloroethane | 1.6 | Not Detected | 11 | Not Detected |
| Propylbenzene | 1.6 | Not Detected | 7.6 | Not Detected |
| 4-Ethyltoluene | 1.6 | Not Detected | 7.6 | Not Detected |
| 1,3,5-Trimethylbenzene | 1.6 | Not Detected | 7.6 | Not Detected |
| 1,2,4-Trimethylbenzene | 1.6 | Not Detected | 7.6 | Not Detected |
| 1,3-Dichlorobenzene | 1.6 | ~~0.22 J~~ | 9.3 | ~~1.3 J~~ |
| 1,4-Dichlorobenzene | 1.6 | ~~0.26 J~~ | 9.3 | ~~1.6 J~~ |
| alpha-Chlorotoluene | 1.6 | Not Detected | 8.0 | Not Detected |
| 1,2-Dichlorobenzene | 1.6 | Not Detected | 9.3 | Not Detected |
| 1,2,4-Trichlorobenzene | 6.2 | ~~0.58 J~~ | 46 | ~~4.3 J~~ |
| Hexachlorobutadiene | 6.2 | Not Detected | 66 | Not Detected |
| Butane | 6.2 | 16 J | 15 | 37 J |
| Isopentane | 6.2 | 23 J | 18 | 67 J |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| Toluene-d8 | 98 | 70-130 |
| 1,2-Dichloroethane-d4 | 100 | 70-130 |
| 4-Bromofluorobenzene | 94 | 70-130 |

eurofins | Air Toxics

**Client Sample ID: VMP-10-20-012913**

**Lab ID#: 1301567A-08A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | p020514 | **Date of Collection:** | 1/29/13 11:42:00 AM |
| **Dil. Factor:** | 2.76 | **Date of Analysis:** | 2/5/13 05:05 PM |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 1.4 | 0.55 J | 6.8 | 2.7 J |
| Freon 114 | 1.4 | Not Detected | 9.6 | Not Detected |
| Chloromethane | 14 | Not Detected | 28 | Not Detected |
| Vinyl Chloride | 1.4 | Not Detected | 3.5 | Not Detected |
| 1,3-Butadiene | 1.4 | Not Detected | 3.0 | Not Detected |
| Bromomethane | 14 | Not Detected | 54 | Not Detected |
| Chloroethane | 5.5 | Not Detected | 14 | Not Detected |
| Freon 11 | 1.4 | 0.30 J | 7.8 | 1.7 J |
| Ethanol | 5.5 | Not Detected | 10 | Not Detected |
| Freon 113 | 1.4 | Not Detected | 10 | Not Detected |
| 1,1-Dichloroethene | 1.4 | Not Detected | 5.5 | Not Detected |
| Acetone | 14 | 4.5 J | 33 | 11 J |
| 2-Propanol | 5.5 | 0.92 J | 14 | 2.3 J |
| Carbon Disulfide | 5.5 | ~~0.67 J~~ | 17 | ~~2.7 J~~ |
| 3-Chloropropene | 5.5 | Not Detected | 17 | Not Detected |
| Methylene Chloride | 14 | Not Detected | 48 | Not Detected |
| Methyl tert-butyl ether | 1.4 | Not Detected | 5.0 | Not Detected |
| trans-1,2-Dichloroethene | 1.4 | Not Detected | 5.5 | Not Detected |
| Hexane | 1.4 | 0.82 J | 4.9 | 2.9 J |
| 1,1-Dichloroethane | 1.4 | Not Detected | 5.6 | Not Detected |
| 2-Butanone (Methyl Ethyl Ketone) | 5.5 | Not Detected | 16 | Not Detected |
| cis-1,2-Dichloroethene | 1.4 | Not Detected | 5.5 | Not Detected |
| Tetrahydrofuran | 1.4 | Not Detected | 4.1 | Not Detected |
| Chloroform | 1.4 | Not Detected | 6.7 | Not Detected |
| 1,1,1-Trichloroethane | 1.4 | Not Detected | 7.5 | Not Detected |
| Cyclohexane | 1.4 | Not Detected | 4.8 | Not Detected |
| Carbon Tetrachloride | 1.4 | Not Detected | 8.7 | Not Detected |
| 2,2,4-Trimethylpentane | 1.4 | 1.5 | 6.4 | 6.8 |
| Benzene | 1.4 | 2.4 | 4.4 | 7.8 |
| 1,2-Dichloroethane | 1.4 | Not Detected | 5.6 | Not Detected |
| Heptane | 1.4 | Not Detected | 5.6 | Not Detected |
| Trichloroethene | 1.4 | Not Detected | 7.4 | Not Detected |
| 1,2-Dichloropropane | 1.4 | Not Detected | 6.4 | Not Detected |
| 1,4-Dioxane | 5.5 | Not Detected | 20 | Not Detected |
| Bromodichloromethane | 1.4 | Not Detected | 9.2 | Not Detected |
| cis-1,3-Dichloropropene | 1.4 | Not Detected | 6.3 | Not Detected |
| 4-Methyl-2-pentanone | 1.4 | Not Detected | 5.6 | Not Detected |
| Toluene | 1.4 | ~~0.22 J~~ | 5.2 | ~~0.84 J~~ |
| trans-1,3-Dichloropropene | 1.4 | Not Detected | 6.3 | Not Detected |
| 1,1,2-Trichloroethane | 1.4 | Not Detected | 7.5 | Not Detected |
| Tetrachloroethene | 1.4 | ~~0.23 J~~ | 9.4 | ~~1.6 J~~ |
| 2-Hexanone | 5.5 | Not Detected | 23 | Not Detected |

eurofins | Air Toxics

**Client Sample ID: VMP-10-20-012913**

**Lab ID#: 1301567A-08A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p020514** | **Date of Collection: 1/29/13 11:42:00 AM** | |
| **Dil. Factor:** | **2.76** | **Date of Analysis: 2/5/13 05:05 PM** | |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Dibromochloromethane | 1.4 | Not Detected | 12 | Not Detected |
| 1,2-Dibromoethane (EDB) | 1.4 | Not Detected | 11 | Not Detected |
| Chlorobenzene | 1.4 | Not Detected | 6.4 | Not Detected |
| Ethyl Benzene | 1.4 | Not Detected | 6.0 | Not Detected |
| m,p-Xylene | 1.4 | Not Detected | 6.0 | Not Detected |
| o-Xylene | 1.4 | Not Detected | 6.0 | Not Detected |
| Styrene | 1.4 | Not Detected | 5.9 | Not Detected |
| Bromoform | 1.4 | Not Detected | 14 | Not Detected |
| Cumene | 1.4 | Not Detected | 6.8 | Not Detected |
| 1,1,2,2-Tetrachloroethane | 1.4 | Not Detected | 9.5 | Not Detected |
| Propylbenzene | 1.4 | Not Detected | 6.8 | Not Detected |
| 4-Ethyltoluene | 1.4 | Not Detected | 6.8 | Not Detected |
| 1,3,5-Trimethylbenzene | 1.4 | Not Detected | 6.8 | Not Detected |
| 1,2,4-Trimethylbenzene | 1.4 | Not Detected | 6.6 | Not Detected |
| 1,3-Dichlorobenzene | 1.4 | Not Detected | 8.3 | Not Detected |
| 1,4-Dichlorobenzene | 1.4 | ~~0.23 J~~ | 6.3 | ~~1.4 J~~ |
| alpha-Chlorotoluene | 1.4 | Not Detected | 7.1 | Not Detected |
| 1,2-Dichlorobenzene | 1.4 | Not Detected | 8.3 | Not Detected |
| 1,2,4-Trichlorobenzene | 5.5 | ~~0.44 J~~ | 41 | ~~3.2 J~~ |
| Hexachlorobutadiene | 5.5 | Not Detected | 59 | Not Detected |
| Butane | 5.5 | 2.2 J | 13 | 5.1 J |
| Isopentane | 5.5 | 0.63 J | 16 | 1.9 J |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| Toluene-d6 | 95 | 70-130 |
| 1,2-Dichloroethane-d4 | 97 | 70-130 |
| 4-Bromofluorobenzene | 94 | 70-130 |

eurofins | Air Toxics

**Client Sample ID: VMP-10-30-012913**

**Lab ID#: 1301567A-09A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p020515** | **Date of Collection:** | **1/29/13 2:12:00 PM** |
| **Dil. Factor:** | **3.03** | **Date of Analysis:** | **2/5/13 05:42 PM** |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 1.5 | 0.56 J | 7.5 | 2.8 J |
| Freon 114 | 1.5 | Not Detected | 10 | Not Detected |
| Chloromethane | 15 | Not Detected | 31 | Not Detected |
| Vinyl Chloride | 1.5 | Not Detected | 3.9 | Not Detected |
| 1,3-Butadiene | 1.5 | Not Detected | 3.4 | Not Detected |
| Bromomethane | 15 | Not Detected | 59 | Not Detected |
| Chloroethane | 6.1 | Not Detected | 16 | Not Detected |
| Freon 11 | 1.5 | 0.32 J | 8.5 | 1.8 J |
| Ethanol | 6.1 | 2.2 J | 11 | 4.2 J |
| Freon 113 | 1.5 | Not Detected | 12 | Not Detected |
| 1,1-Dichloroethene | 1.5 | Not Detected | 6.0 | Not Detected |
| Acetone | 15 | 5.3 J | 36 | 13 J |
| 2-Propanol | 6.1 | 2.9 J | 15 | 7.1 J |
| Carbon Disulfide | 6.1 | ~~1.1 J~~ | 19 | ~~3.4 J~~ |
| 3-Chloropropene | 6.1 | Not Detected | 19 | Not Detected |
| Methylene Chloride | 15 | Not Detected | 53 | Not Detected |
| Methyl tert-butyl ether | 1.5 | Not Detected | 5.5 | Not Detected |
| trans-1,2-Dichloroethene | 1.5 | Not Detected | 6.0 | Not Detected |
| Hexane | 1.5 | 0.26 J | 5.3 | 0.92 J |
| 1,1-Dichloroethane | 1.5 | Not Detected | 6.1 | Not Detected |
| 2-Butanone (Methyl Ethyl Ketone) | 6.1 | Not Detected | 18 | Not Detected |
| cis-1,2-Dichloroethene | 1.5 | Not Detected | 6.0 | Not Detected |
| Tetrahydrofuran | 1.5 | Not Detected | 4.5 | Not Detected |
| Chloroform | 1.5 | Not Detected | 7.4 | Not Detected |
| 1,1,1-Trichloroethane | 1.5 | Not Detected | 8.3 | Not Detected |
| Cyclohexane | 1.5 | Not Detected | 5.2 | Not Detected |
| Carbon Tetrachloride | 1.5 | Not Detected | 9.5 | Not Detected |
| 2,2,4-Trimethylpentane | 1.5 | 1.2 J | 7.1 | 5.4 J |
| Benzene | 1.5 | 2.8 | 4.8 | 9.1 |
| 1,2-Dichloroethane | 1.5 | Not Detected | 6.1 | Not Detected |
| Heptane | 1.5 | Not Detected | 6.2 | Not Detected |
| Trichloroethene | 1.5 | Not Detected | 8.1 | Not Detected |
| 1,2-Dichloropropane | 1.5 | Not Detected | 7.0 | Not Detected |
| 1,4-Dioxane | 6.1 | Not Detected | 22 | Not Detected |
| Bromodichloromethane | 1.5 | Not Detected | 10 | Not Detected |
| cis-1,3-Dichloropropene | 1.5 | Not Detected | 6.9 | Not Detected |
| 4-Methyl-2-pentanone | 1.5 | Not Detected | 6.2 | Not Detected |
| Toluene | 1.5 | ~~0.15 J~~ | 5.7 | ~~0.57 J~~ |
| trans-1,3-Dichloropropene | 1.5 | Not Detected | 6.9 | Not Detected |
| 1,1,2-Trichloroethane | 1.5 | Not Detected | 8.3 | Not Detected |
| Tetrachloroethene | 1.5 | ~~0.32 J~~ | 10 | ~~2.2 J~~ |
| 2-Hexanone | 6.1 | Not Detected | 25 | Not Detected |

eurofins | Air Toxics

**Client Sample ID: VMP-10-30-012913**

**Lab ID#: 1301567A-09A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Nama:** | **p020515** | **Date of Collection:** | **1/29/13 2:12:00 PM** |
| **Dil. Factor:** | **3.03** | **Date of Analysis:** | **2/5/13 05:42 PM** |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Dibromochloromethane | 1.5 | Not Detected | 13 | Not Detected |
| 1,2-Dibromoethane (EDB) | 1.5 | Not Detected | 12 | Not Detected |
| Chlorobenzene | 1.5 | Not Detected | 7.0 | Not Detected |
| Ethyl Benzene | 1.5 | Not Detected | 6.6 | Not Detected |
| m,p-Xylene | 1.5 | Not Detected | 6.6 | Not Detected |
| o-Xylene | 1.5 | Not Detected | 6.6 | Not Detected |
| Styrene | 1.5 | Not Detected | 6.4 | Not Detected |
| Bromoform | 1.5 | Not Detected | 16 | Not Detected |
| Cumene | 1.5 | Not Detected | 7.4 | Not Detected |
| 1,1,2,2-Tetrachloroethane | 1.5 | Not Detected | 10 | Not Detected |
| Propylbenzene | 1.5 | Not Detected | 7.4 | Not Detected |
| 4-Ethyltoluene | 1.5 | Not Detected | 7.4 | Not Detected |
| 1,3,5-Trimethylbenzene | 1.5 | Not Detected | 7.4 | Not Detected |
| 1,2,4-Trimethylbenzene | 1.5 | Not Detected | 7.4 | Not Detected |
| 1,3-Dichlorobenzene | 1.5 | Not Detected | 9.1 | Not Detected |
| 1,4-Dichlorobenzene | 1.5 | ~~0.25 J~~ | 9.1 | ~~1.5 J~~ |
| alpha-Chlorotoluene | 1.5 | Not Detected | 7.8 | Not Detected |
| 1,2-Dichlorobenzene | 1.5 | Not Detected | 9.1 | Not Detected |
| 1,2,4-Trichlorobenzene | 6.1 | ~~0.56 J~~ | 45 | ~~4.2 J~~ |
| Hexachlorobutadiene | 6.1 | Not Detected | 65 | Not Detected |
| Butane | 6.1 | Not Detected | 14 | Not Detected |
| Isopentane | 6.1 | Not Detected | 18 | Not Detected |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| Toluene-d8 | 98 | 70-130 |
| 1,2-Dichloroethane-d4 | 99 | 70-130 |
| 4-Bromofluorobenzene | 96 | 70-130 |

**Client Sample ID: VMP-11-5-012913**

**Lab ID#: 1301567A-10A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | p020524 | **Date of Collection:** | 1/29/13 1:45:00 PM |
| **Dil. Factor:** | 144 | **Date of Analysis:** | 2/5/13 10:43 PM |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 72 | Not Detected | 360 | Not Detected |
| Freon 114 | 72 | Not Detected | 500 | Not Detected |
| Chloromethane | 720 | Not Detected | 1500 | Not Detected |
| Vinyl Chloride | 72 | Not Detected | 180 | Not Detected |
| 1,3-Butadiene | 72 | Not Detected | 160 | Not Detected |
| Bromomethane | 720 | Not Detected | 2800 | Not Detected |
| Chloroethane | 290 | Not Detected | 760 | Not Detected |
| Freon 11 | 72 | Not Detected | 400 | Not Detected |
| Ethanol | 290 | Not Detected | 540 | Not Detected |
| Freon 113 | 72 | Not Detected | 550 | Not Detected |
| 1,1-Dichloroethene | 72 | Not Detected | 280 | Not Detected |
| Acetone | 720 | 5600 | 1700 | 13000 |
| 2-Propanol | 290 | 15000 | 710 | 36000 |
| Carbon Disulfide | 290 | 51 J | 900 | 160 J |
| 3-Chloropropene | 290 | Not Detected | 900 | Not Detected |
| Methylene Chloride | 720 | 89 J | 2500 | 310 J |
| Methyl tert-butyl ether | 72 | Not Detected | 260 | Not Detected |
| trans-1,2-Dichloroethene | 72 | Not Detected | 280 | Not Detected |
| Hexane | 72 | 35 J | 250 | 120 J |
| 1,1-Dichloroethane | 72 | Not Detected | 290 | Not Detected |
| 2-Butanone (Methyl Ethyl Ketone) | 290 | Not Detected | 850 | Not Detected |
| cis-1,2-Dichloroethene | 72 | Not Detected | 280 | Not Detected |
| Tetrahydrofuran | 72 | Not Detected | 210 | Not Detected |
| Chloroform | 72 | Not Detected | 350 | Not Detected |
| 1,1,1-Trichloroethane | 72 | Not Detected | 390 | Not Detected |
| Cyclohexane | 72 | Not Detected | 250 | Not Detected |
| Carbon Tetrachloride | 72 | Not Detected | 450 | Not Detected |
| 2,2,4-Trimethylpentane | 72 | Not Detected | 340 | Not Detected |
| Benzene | 72 | Not Detected | 230 | Not Detected |
| 1,2-Dichloroethane | 72 | Not Detected | 290 | Not Detected |
| Heptane | 72 | 56 J | 300 | 230 J |
| Trichloroethene | 72 | Not Detected | 390 | Not Detected |
| 1,2-Dichloropropane | 72 | Not Detected | 330 | Not Detected |
| 1,4-Dioxane | 290 | Not Detected | 1000 | Not Detected |
| Bromodichloromethane | 72 | Not Detected | 480 | Not Detected |
| cis-1,3-Dichloropropene | 72 | Not Detected | 330 | Not Detected |
| 4-Methyl-2-pentanone | 72 | Not Detected | 290 | Not Detected |
| Toluene | 72 | 27 J | 270 | 100 J |
| trans-1,3-Dichloropropene | 72 | Not Detected | 330 | Not Detected |
| 1,1,2-Trichloroethane | 72 | Not Detected | 390 | Not Detected |
| Tetrachloroethene | 72 | 150 | 490 | 1000 |
| 2-Hexanone | 290 | Not Detected | 1200 | Not Detected |

eurofins | Air Toxics

**Client Sample ID: VMP-11-5-012913**

**Lab ID#: 1301567A-10A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p020524** | **Date of Collection: 1/29/13 1:45:00 PM** | |
| **Dil. Factor:** | **144** | **Date of Analysis: 2/5/13 10:43 PM** | |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Dibromochloromethane | 72 | Not Detected | 610 | Not Detected |
| 1,2-Dibromoethane (EDB) | 72 | Not Detected | 550 | Not Detected |
| Chlorobenzene | 72 | Not Detected | 330 | Not Detected |
| Ethyl Benzene | 72 | Not Detected | 310 | Not Detected |
| m,p-Xylene | 72 | Not Detected | 310 | Not Detected |
| o-Xylene | 72 | Not Detected | 310 | Not Detected |
| Styrene | 72 | 14 J | 310 | 58 J |
| Bromoform | 72 | Not Detected | 740 | Not Detected |
| Cumene | 72 | Not Detected | 350 | Not Detected |
| 1,1,2,2-Tetrachloroethane | 72 | Not Detected | 490 | Not Detected |
| Propylbenzene | 72 | Not Detected | 350 | Not Detected |
| 4-Ethyltoluene | 72 | Not Detected | 350 | Not Detected |
| 1,3,5-Trimethylbenzene | 72 | Not Detected | 350 | Not Detected |
| 1,2,4-Trimethylbenzene | 72 | Not Detected | 350 | Not Detected |
| 1,3-Dichlorobenzene | 72 | Not Detected | 430 | Not Detected |
| 1,4-Dichlorobenzene | 72 | Not Detected | 430 | Not Detected |
| alpha-Chlorotoluene | 72 | Not Detected | 370 | Not Detected |
| 1,2-Dichlorobenzene | 72 | Not Detected | 430 | Not Detected |
| 1,2,4-Trichlorobenzene | 290 | Not Detected | 2100 | Not Detected |
| Hexachlorobutadiene | 290 | Not Detected | 3100 | Not Detected |
| Butane | 290 | Not Detected | 680 | Not Detected |
| Isopentane | 290 | 98 J | 850 | 290 J |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| Toluene-d8 | 99 | 70-130 |
| 1,2-Dichloroethane-d4 | 101 | 70-130 |
| 4-Bromofluorobenzene | 117 | 70-130 |

eurofins | Air Toxics

**Client Sample ID: VMP-11-8-012913**

**Lab ID#: 1301567A-11A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p020624** | **Date of Collection:** | **1/29/13 2:32:00 PM** |
| **Dil. Factor:** | **19.7** | **Date of Analysis:** | **2/7/13 09:41 AM** |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 9.8 | Not Detected | 49 | Not Detected |
| Freon 114 | 9.8 | Not Detected | 69 | Not Detected |
| Chloromethane | 98 | Not Detected | 200 | Not Detected |
| Vinyl Chloride | 9.8 | Not Detected | 25 | Not Detected |
| 1,3-Butadiene | 9.8 | Not Detected | 22 | Not Detected |
| Bromomethane | 98 | Not Detected | 380 | Not Detected |
| Chloroethane | 39 | Not Detected | 100 | Not Detected |
| Freon 11 | 9.8 | Not Detected | 55 | Not Detected |
| Ethanol | 39 | Not Detected | 74 | Not Detected |
| Freon 113 | 9.8 | Not Detected | 75 | Not Detected |
| 1,1-Dichloroethene | 9.8 | Not Detected | 39 | Not Detected |
| Acetone | 98 | 2500 | 230 | 5900 |
| 2-Propanol | 39 | 290 | 97 | 710 |
| Carbon Disulfide | 39 | 5.8 J | 120 | 18 J |
| 3-Chloropropene | 39 | Not Detected | 120 | Not Detected |
| Methylene Chloride | 98 | Not Detected | 340 | Not Detected |
| Methyl tert-butyl ether | 9.8 | Not Detected | 36 | Not Detected |
| trans-1,2-Dichloroethene | 9.8 | Not Detected | 39 | Not Detected |
| Hexane | 9.8 | Not Detected | 35 | Not Detected |
| 1,1-Dichloroethane | 9.8 | Not Detected | 40 | Not Detected |
| 2-Butanone (Methyl Ethyl Ketone) | 39 | Not Detected | 120 | Not Detected |
| cis-1,2-Dichloroethene | 9.8 | Not Detected | 39 | Not Detected |
| Tetrahydrofuran | 9.8 | Not Detected | 29 | Not Detected |
| Chloroform | 9.8 | Not Detected | 48 | Not Detected |
| 1,1,1-Trichloroethane | 9.8 | Not Detected | 54 | Not Detected |
| Cyclohexane | 9.8 | Not Detected | 34 | Not Detected |
| Carbon Tetrachloride | 9.8 | Not Detected | 62 | Not Detected |
| 2,2,4-Trimethylpentane | 9.8 | Not Detected | 46 | Not Detected |
| Benzene | 9.8 | Not Detected | 31 | Not Detected |
| 1,2-Dichloroethane | 9.8 | Not Detected | 40 | Not Detected |
| Heptane | 9.8 | Not Detected | 40 | Not Detected |
| Trichloroethene | 9.8 | Not Detected | 53 | Not Detected |
| 1,2-Dichloropropane | 9.8 | Not Detected | 46 | Not Detected |
| 1,4-Dioxane | 39 | Not Detected | 140 | Not Detected |
| Bromodichloromethane | 9.8 | Not Detected | 66 | Not Detected |
| cis-1,3-Dichloropropene | 9.8 | Not Detected | 45 | Not Detected |
| 4-Methyl-2-pentanone | 9.8 | Not Detected | 40 | Not Detected |
| Toluene | 9.8 | 1.6 J | 37 | 6.2 J |
| trans-1,3-Dichloropropene | 9.8 | Not Detected | 45 | Not Detected |
| 1,1,2-Trichloroethane | 9.8 | Not Detected | 54 | Not Detected |
| Tetrachloroethene | 9.8 | Not Detected | 67 | Not Detected |
| 2-Hexanone | 39 | Not Detected | 160 | Not Detected |

eurofins | Air Toxics

**Client Sample ID: VMP-11-8-012913**

**Lab ID#: 1301567A-11A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p020624** | **Date of Collection: 1/29/13 2:32:00 PM** | |
| **Dil. Factor:** | **19.7** | **Date of Analysis: 2/7/13 09:41 AM** | |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Dibromochloromethane | 9.8 | Not Detected | 84 | Not Detected |
| 1,2-Dibromoethane (EDB) | 9.8 | Not Detected | 76 | Not Detected |
| Chlorobenzene | 9.8 | Not Detected | 45 | Not Detected |
| Ethyl Benzene | 9.8 | Not Detected | 43 | Not Detected |
| m,p-Xylene | 9.8 | Not Detected | 43 | Not Detected |
| o-Xylene | 9.8 | Not Detected | 43 | Not Detected |
| Styrene | 9.8 | Not Detected | 42 | Not Detected |
| Bromoform | 9.8 | Not Detected | 100 | Not Detected |
| Cumene | 9.8 | Not Detected | 48 | Not Detected |
| 1,1,2,2-Tetrachloroethane | 9.8 | Not Detected | 68 | Not Detected |
| Propylbenzene | 9.8 | Not Detected | 48 | Not Detected |
| 4-Ethyltoluene | 9.8 | Not Detected | 48 | Not Detected |
| 1,3,5-Trimethylbenzene | 9.8 | Not Detected | 48 | Not Detected |
| 1,2,4-Trimethylbenzene | 9.8 | Not Detected | 48 | Not Detected |
| 1,3-Dichlorobenzene | 9.8 | Not Detected | 59 | Not Detected |
| 1,4-Dichlorobenzene | 9.8 | Not Detected | 59 | Not Detected |
| alpha-Chlorotoluene | 9.8 | Not Detected | 51 | Not Detected |
| 1,2-Dichlorobenzene | 9.8 | Not Detected | 59 | Not Detected |
| 1,2,4-Trichlorobenzene | 39 | Not Detected | 290 | Not Detected |
| Hexachlorobutadiene | 39 | Not Detected | 420 | Not Detected |
| Butane | 39 | Not Detected | 94 | Not Detected |
| Isopentane | 39 | Not Detected | 120 | Not Detected |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| Toluene-d8 | 96 | 70-130 |
| 1,2-Dichloroethane-d4 | 95 | 70-130 |
| 4-Bromofluorobenzene | 98 | 70-130 |

eurofins | Air Toxics

**Client Sample ID: VMP-11-29-012913**

**Lab ID#: 1301567A-12A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p020516** | **Date of Collection:** | **1/29/13 3:12:00 PM** |
| **Dil. Factor:** | **2.89** | **Date of Analysis:** | **2/5/13 06:05 PM** |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 1.4 | 0.60 J | 7.1 | 3.0 J |
| Freon 114 | 1.4 | Not Detected | 10 | Not Detected |
| Chloromethane | 14 | Not Detected | 30 | Not Detected |
| Vinyl Chloride | 1.4 | Not Detected | 3.7 | Not Detected |
| 1,3-Butadiene | 1.4 | Not Detected | 3.2 | Not Detected |
| Bromomethane | 14 | Not Detected | 56 | Not Detected |
| Chloroethane | 5.8 | Not Detected | 15 | Not Detected |
| Freon 11 | 1.4 | 0.30 J | 8.1 | 1.7 J |
| Ethanol | 5.8 | 15 | 11 | 28 |
| Freon 113 | 1.4 | Not Detected | 11 | Not Detected |
| 1,1-Dichloroethene | 1.4 | Not Detected | 5.7 | Not Detected |
| Acetone | 14 | 17 | 34 | 40 |
| 2-Propanol | 5.8 | 68 | 14 | 170 |
| Carbon Disulfide | 5.8 | ~~1.0 J~~ | 18 | ~~3.3 J~~ |
| 3-Chloropropene | 5.8 | Not Detected | 18 | Not Detected |
| Methylene Chloride | 14 | ~~0.29 J~~ | 50 | ~~1.0 J~~ |
| Methyl tert-butyl ether | 1.4 | Not Detected | 5.2 | Not Detected |
| trans-1,2-Dichloroethene | 1.4 | Not Detected | 5.7 | Not Detected |
| Hexane | 1.4 | 0.36 J | 5.1 | 1.2 J |
| 1,1-Dichloroethane | 1.4 | Not Detected | 5.8 | Not Detected |
| 2-Butanone (Methyl Ethyl Ketone) | 5.8 | 1.5 J | 17 | 4.6 J |
| cis-1,2-Dichloroethene | 1.4 | Not Detected | 5.7 | Not Detected |
| Tetrahydrofuran | 1.4 | 0.25 J | 4.3 | 0.73 J |
| Chloroform | 1.4 | 58 | 7.0 | 280 |
| 1,1,1-Trichloroethane | 1.4 | Not Detected | 7.9 | Not Detected |
| Cyclohexane | 1.4 | Not Detected | 5.0 | Not Detected |
| Carbon Tetrachloride | 1.4 | Not Detected | 9.1 | Not Detected |
| 2,2,4-Trimethylpentane | 1.4 | 1.3 J | 6.8 | 6.2 J |
| Benzene | 1.4 | 15 | 4.6 | 49 |
| 1,2-Dichloroethane | 1.4 | Not Detected | 5.8 | Not Detected |
| Heptane | 1.4 | Not Detected | 5.9 | Not Detected |
| Trichloroethene | 1.4 | Not Detected | 7.8 | Not Detected |
| 1,2-Dichloropropane | 1.4 | Not Detected | 6.7 | Not Detected |
| 1,4-Dioxane | 5.8 | Not Detected | 21 | Not Detected |
| Bromodichloromethane | 1.4 | 4.2 | 9.7 | 28 |
| cis-1,3-Dichloropropene | 1.4 | Not Detected | 6.6 | Not Detected |
| 4-Methyl-2-pentanone | 1.4 | Not Detected | 5.9 | Not Detected |
| Toluene | 1.4 | 1.1 J | 5.4 | 4.2 J |
| trans-1,3-Dichloropropene | 1.4 | Not Detected | 6.6 | Not Detected |
| 1,1,2-Trichloroethane | 1.4 | Not Detected | 7.9 | Not Detected |
| Tetrachloroethene | 1.4 | 0.31 J | 9.8 | 2.1 J |
| 2-Hexanone | 5.8 | Not Detected | 24 | Not Detected |

eurofins | Air Toxics

**Client Sample ID: VMP-11-29-012913**

**Lab ID#: 1301567A-12A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p020516** | **Date of Collection: 1/29/13 3:12:00 PM** | |
| **Dil. Factor:** | **2.89** | **Date of Analysis: 2/5/13 06:05 PM** | |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Dibromochloromethane | 1.4 | Not Detected | 12 | Not Detected |
| 1,2-Dibromoethane (EDB) | 1.4 | Not Detected | 11 | Not Detected |
| Chlorobenzene | 1.4 | Not Detected | 6.6 | Not Detected |
| Ethyl Benzene | 1.4 | Not Detected | 6.3 | Not Detected |
| m,p-Xylene | 1.4 | Not Detected | 6.3 | Not Detected |
| o-Xylene | 1.4 | Not Detected | 6.3 | Not Detected |
| Styrene | 1.4 | Not Detected | 6.2 | Not Detected |
| Bromoform | 1.4 | Not Detected | 15 | Not Detected |
| Cumene | 1.4 | Not Detected | 7.1 | Not Detected |
| 1,1,2,2-Tetrachloroethane | 1.4 | Not Detected | 9.9 | Not Detected |
| Propylbenzene | 1.4 | Not Detected | 7.1 | Not Detected |
| 4-Ethyltoluene | 1.4 | Not Detected | 7.1 | Not Detected |
| 1,3,5-Trimethylbenzene | 1.4 | Not Detected | 7.1 | Not Detected |
| 1,2,4-Trimethylbenzene | 1.4 | Not Detected | 7.1 | Not Detected |
| 1,3-Dichlorobenzene | 1.4 | Not Detected | 8.7 | Not Detected |
| 1,4-Dichlorobenzene | 1.4 | Not Detected | 8.7 | Not Detected |
| alpha-Chlorotoluene | 1.4 | Not Detected | 7.5 | Not Detected |
| 1,2-Dichlorobenzene | 1.4 | Not Detected | 8.7 | Not Detected |
| 1,2,4-Trichlorobenzene | 5.8 | ~~0.42 J~~ | 43 | ~~3.1 J~~ |
| Hexachlorobutadiene | 5.8 | Not Detected | 62 | Not Detected |
| Butane | 5.8 | 1.7 J | 14 | 4.1 J |
| Isopentane | 5.8 | 3.0 J | 17 | 8.7 J |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| Toluene-d8 | 97 | 70-130 |
| 1,2-Dichloroethane-d4 | 102 | 70-130 |
| 4-Bromofluorobenzene | 95 | 70-130 |

eurofins | Air Toxics

**Client Sample ID: VMP-11-38-013013**

**Lab ID#: 1301567A-13A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | p020517 | **Date of Collection:** | 1/30/13 12:30:00 PM |
| **Dil. Factor:** | 2.76 | **Date of Analysis:** | 2/5/13 06:33 PM |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 1.4 | 0.56 J | 6.8 | 2.8 J |
| Freon 114 | 1.4 | Not Detected | 9.6 | Not Detected |
| Chloromethane | 14 | Not Detected | 28 | Not Detected |
| Vinyl Chloride | 1.4 | Not Detected | 3.5 | Not Detected |
| 1,3-Butadiene | 1.4 | Not Detected | 3.0 | Not Detected |
| Bromomethane | 14 | Not Detected | 54 | Not Detected |
| Chloroethane | 5.5 | Not Detected | 14 | Not Detected |
| Freon 11 | 1.4 | 0.29 J | 7.8 | 1.6 J |
| Ethanol | 5.5 | 4.2 J | 10 | 8.0 J |
| Freon 113 | 1.4 | Not Detected | 10 | Not Detected |
| 1,1-Dichloroethene | 1.4 | Not Detected | 5.5 | Not Detected |
| Acetone | 14 | 9.1 J | 33 | 22 J |
| 2-Propanol | 5.5 | 10 | 14 | 25 |
| Carbon Disulfide | 5.5 | ~~1.8 J~~ | 17 | ~~5.8 J~~ |
| 3-Chloropropene | 5.5 | Not Detected | 17 | Not Detected |
| Methylene Chloride | 14 | ~~0.19 J~~ | 48 | ~~0.67 J~~ |
| Methyl tert-butyl ether | 1.4 | 2.2 | 5.0 | 7.9 |
| trans-1,2-Dichloroethene | 1.4 | Not Detected | 5.5 | Not Detected |
| Hexane | 1.4 | 0.38 J | 4.9 | 1.3 J |
| 1,1-Dichloroethane | 1.4 | Not Detected | 5.6 | Not Detected |
| 2-Butanone (Methyl Ethyl Ketone) | 5.5 | Not Detected | 16 | Not Detected |
| cis-1,2-Dichloroethene | 1.4 | Not Detected | 5.5 | Not Detected |
| Tetrahydrofuran | 1.4 | Not Detected | 4.1 | Not Detected |
| Chloroform | 1.4 | 19 | 6.7 | 91 |
| 1,1,1-Trichloroethane | 1.4 | Not Detected | 7.5 | Not Detected |
| Cyclohexane | 1.4 | Not Detected | 4.8 | Not Detected |
| Carbon Tetrachloride | 1.4 | Not Detected | 8.7 | Not Detected |
| 2,2,4-Trimethylpentane | 1.4 | 1.0 J | 6.4 | 4.8 J |
| Benzene | 1.4 | 2.3 | 4.4 | 7.4 |
| 1,2-Dichloroethane | 1.4 | Not Detected | 5.6 | Not Detected |
| Heptane | 1.4 | Not Detected | 5.6 | Not Detected |
| Trichloroethene | 1.4 | Not Detected | 7.4 | Not Detected |
| 1,2-Dichloropropane | 1.4 | Not Detected | 6.4 | Not Detected |
| 1,4-Dioxane | 5.5 | Not Detected | 20 | Not Detected |
| Bromodichloromethane | 1.4 | 0.92 J | 9.2 | 6.1 J |
| cis-1,3-Dichloropropene | 1.4 | Not Detected | 6.3 | Not Detected |
| 4-Methyl-2-pentanone | 1.4 | Not Detected | 5.6 | Not Detected |
| Toluene | 1.4 | 0.23 J | 5.2 | 0.86 J |
| trans-1,3-Dichloropropene | 1.4 | Not Detected | 6.3 | Not Detected |
| 1,1,2-Trichloroethane | 1.4 | Not Detected | 7.5 | Not Detected |
| Tetrachloroethene | 1.4 | 0.19 J | 9.4 | 1.3 J |
| 2-Hexanone | 5.5 | Not Detected | 23 | Not Detected |

eurofins | Air Toxics

**Client Sample ID: VMP-11-38-013013**

**Lab ID#: 1301567A-13A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p020517** | **Date of Collection: 1/30/13 12:30:00 PM** | |
| **Dil. Factor:** | **2.76** | **Date of Analysis: 2/5/13 06:33 PM** | |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Dibromochloromethane | 1.4 | Not Detected | 12 | Not Detected |
| 1,2-Dibromoethane (EDB) | 1.4 | Not Detected | 11 | Not Detected |
| Chlorobenzene | 1.4 | Not Detected | 6.4 | Not Detected |
| Ethyl Benzene | 1.4 | Not Detected | 6.0 | Not Detected |
| m,p-Xylene | 1.4 | Not Detected | 6.0 | Not Detected |
| o-Xylene | 1.4 | Not Detected | 6.0 | Not Detected |
| Styrene | 1.4 | Not Detected | 5.9 | Not Detected |
| Bromoform | 1.4 | Not Detected | 14 | Not Detected |
| Cumene | 1.4 | Not Detected | 6.8 | Not Detected |
| 1,1,2,2-Tetrachloroethane | 1.4 | Not Detected | 9.5 | Not Detected |
| Propylbenzene | 1.4 | Not Detected | 6.8 | Not Detected |
| 4-Ethyltoluene | 1.4 | Not Detected | 6.8 | Not Detected |
| 1,3,5-Trimethylbenzene | 1.4 | Not Detected | 6.8 | Not Detected |
| 1,2,4-Trimethylbenzene | 1.4 | Not Detected | 6.8 | Not Detected |
| 1,3-Dichlorobenzene | 1.4 | Not Detected | 8.3 | Not Detected |
| 1,4-Dichlorobenzene | 1.4 | Not Detected | 8.3 | Not Detected |
| alpha-Chlorotoluene | 1.4 | Not Detected | 7.1 | Not Detected |
| 1,2-Dichlorobenzene | 1.4 | Not Detected | 8.3 | Not Detected |
| 1,2,4-Trichlorobenzene | 5.5 | Not Detected | 41 | Not Detected |
| Hexachlorobutadiene | 5.5 | Not Detected | 59 | Not Detected |
| Butane | 5.5 | 4.9 J | 13 | 12 J |
| Isopentane | 5.5 | 6.5 | 16 | 19 |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| Toluene-d8 | 99 | 70-130 |
| 1,2-Dichloroethane-d4 | 103 | 70-130 |
| 4-Bromofluorobenzene | 95 | 70-130 |

eurofins | Air Toxics

**Client Sample ID: VMP-13-5-012913**

**Lab ID#: 1301567A-14A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p020518** | **Date of Collection:** | **1/29/13 3:27:00 PM** |
| **Dil. Factor:** | **3.11** | **Date of Analysis:** | **2/5/13 07:01 PM** |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 1.6 | 0.69 J | 7.7 | 3.4 J |
| Freon 114 | 1.6 | Not Detected | 11 | Not Detected |
| Chloromethane | 16 | Not Detected | 32 | Not Detected |
| Vinyl Chloride | 1.6 | Not Detected | 4.0 | Not Detected |
| 1,3-Butadiene | 1.6 | Not Detected | 3.4 | Not Detected |
| Bromomethane | 16 | Not Detected | 60 | Not Detected |
| Chloroethane | 6.2 | Not Detected | 16 | Not Detected |
| Freon 11 | 1.6 | 0.34 J | 8.7 | 1.9 J |
| Ethanol | 6.2 | Not Detected | 12 | Not Detected |
| Freon 113 | 1.6 | Not Detected | 12 | Not Detected |
| 1,1-Dichloroethene | 1.6 | Not Detected | 6.2 | Not Detected |
| Acetone | 16 | 2.6 J | 37 | 6.2 J |
| 2-Propanol | 6.2 | 1.8 J | 15 | 4.4 J |
| Carbon Disulfide | 6.2 | ~~0.98 J~~ | 19 | ~~3.1 J~~ |
| 3-Chloropropene | 6.2 | Not Detected | 19 | Not Detected |
| Methylene Chloride | 16 | Not Detected | 54 | Not Detected |
| Methyl tert-butyl ether | 1.6 | Not Detected | 5.6 | Not Detected |
| trans-1,2-Dichloroethene | 1.6 | Not Detected | 6.2 | Not Detected |
| Hexane | 1.6 | Not Detected | 5.5 | Not Detected |
| 1,1-Dichloroethane | 1.6 | Not Detected | 6.3 | Not Detected |
| 2-Butanone (Methyl Ethyl Ketone) | 6.2 | Not Detected | 18 | Not Detected |
| cis-1,2-Dichloroethene | 1.6 | Not Detected | 6.2 | Not Detected |
| Tetrahydrofuran | 1.6 | Not Detected | 4.6 | Not Detected |
| Chloroform | 1.6 | Not Detected | 7.6 | Not Detected |
| 1,1,1-Trichloroethane | 1.6 | Not Detected | 8.5 | Not Detected |
| Cyclohexane | 1.6 | Not Detected | 5.4 | Not Detected |
| Carbon Tetrachloride | 1.6 | Not Detected | 9.8 | Not Detected |
| 2,2,4-Trimethylpentane | 1.6 | Not Detected | 7.3 | Not Detected |
| Benzene | 1.6 | 1.2 J | 5.0 | 3.8 J |
| 1,2-Dichloroethane | 1.6 | Not Detected | 6.3 | Not Detected |
| Heptane | 1.6 | Not Detected | 6.4 | Not Detected |
| Trichloroethene | 1.6 | Not Detected | 8.4 | Not Detected |
| 1,2-Dichloropropane | 1.6 | Not Detected | 7.2 | Not Detected |
| 1,4-Dioxane | 6.2 | Not Detected | 22 | Not Detected |
| Bromodichloromethane | 1.6 | Not Detected | 10 | Not Detected |
| cis-1,3-Dichloropropene | 1.6 | Not Detected | 7.0 | Not Detected |
| 4-Methyl-2-pentanone | 1.6 | Not Detected | 6.4 | Not Detected |
| Toluene | 1.6 | ~~0.11 J~~ | 5.8 | ~~0.42 J~~ |
| trans-1,3-Dichloropropene | 1.6 | Not Detected | 7.0 | Not Detected |
| 1,1,2-Trichloroethane | 1.6 | Not Detected | 8.5 | Not Detected |
| Tetrachloroethene | 1.6 | Not Detected | 10 | Not Detected |
| 2-Hexanone | 6.2 | Not Detected | 25 | Not Detected |

eurofins | Air Toxics

**Client Sample ID: VMP-13-5-012913**

**Lab ID#: 1301567A-14A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p020518** | **Date of Collection:** | **1/29/13 3:27:00 PM** |
| **Dil. Factor:** | **3.11** | **Date of Analysis:** | **2/5/13 07:01 PM** |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Dibromochloromethane | 1.6 | Not Detected | 13 | Not Detected |
| 1,2-Dibromoethane (EDB) | 1.6 | Not Detected | 12 | Not Detected |
| Chlorobenzene | 1.6 | Not Detected | 7.2 | Not Detected |
| Ethyl Benzene | 1.6 | Not Detected | 6.8 | Not Detected |
| m,p-Xylene | 1.6 | Not Detected | 6.8 | Not Detected |
| o-Xylene | 1.6 | Not Detected | 6.8 | Not Detected |
| Styrene | 1.6 | Not Detected | 6.6 | Not Detected |
| Bromoform | 1.6 | Not Detected | 16 | Not Detected |
| Cumene | 1.6 | Not Detected | 7.6 | Not Detected |
| 1,1,2,2-Tetrachloroethane | 1.6 | Not Detected | 11 | Not Detected |
| Propylbenzene | 1.6 | Not Detected | 7.6 | Not Detected |
| 4-Ethyltoluene | 1.6 | Not Detected | 7.6 | Not Detected |
| 1,3,5-Trimethylbenzene | 1.6 | Not Detected | 7.6 | Not Detected |
| 1,2,4-Trimethylbenzene | 1.6 | Not Detected | 7.6 | Not Detected |
| 1,3-Dichlorobenzene | 1.6 | Not Detected | 9.3 | Not Detected |
| 1,4-Dichlorobenzene | 1.6 | Not Detected | 9.3 | Not Detected |
| alpha-Chlorotoluene | 1.6 | Not Detected | 8.0 | Not Detected |
| 1,2-Dichlorobenzene | 1.6 | Not Detected | 9.3 | Not Detected |
| 1,2,4-Trichlorobenzene | 6.2 | Not Detected | 46 | Not Detected |
| Hexachlorobutadiene | 6.2 | Not Detected | 66 | Not Detected |
| Butane | 6.2 | Not Detected | 15 | Not Detected |
| Isopentane | 6.2 | Not Detected | 18 | Not Detected |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| Toluene-d8 | 98 | 70-130 |
| 1,2-Dichloroethane-d4 | 102 | 70-130 |
| 4-Bromofluorobenzene | 94 | 70-130 |

eurofins | Air Toxics

**Client Sample ID: VMP-41-10-012913**

**Lab ID#: 1301567A-15A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | p020519 | **Date of Collection:** | 1/29/13 9:29:00 AM |
| **Dil. Factor:** | 2.96 | **Date of Analysis:** | 2/5/13 07:40 PM |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 1.5 | 0.66 J | 7.3 | 3.3 J |
| Freon 114 | 1.5 | Not Detected | 10 | Not Detected |
| Chloromethane | 15 | Not Detected | 30 | Not Detected |
| Vinyl Chloride | 1.5 | Not Detected | 3.8 | Not Detected |
| 1,3-Butadiene | 1.5 | Not Detected | 3.3 | Not Detected |
| Bromomethane | 15 | Not Detected | 57 | Not Detected |
| Chloroethane | 5.9 | Not Detected | 16 | Not Detected |
| Freon 11 | 1.5 | 0.32 J | 8.3 | 1.8 J |
| Ethanol | 5.9 | Not Detected | 11 | Not Detected |
| Freon 113 | 1.5 | Not Detected | 11 | Not Detected |
| 1,1-Dichloroethene | 1.5 | Not Detected | 5.9 | Not Detected |
| Acetone | 15 | 2.5 J | 35 | 6.0 J |
| 2-Propanol | 5.9 | 4.2 J | 14 | 10 J |
| Carbon Disulfide | 5.9 | ~~1.0 J~~ U | 18 | ~~3.2 J~~ U |
| 3-Chloropropene | 5.9 | Not Detected | 18 | Not Detected |
| Methylene Chloride | 15 | ~~0.23 J~~ U | 51 | ~~0.81 J~~ U |
| Methyl tert-butyl ether | 1.5 | Not Detected | 5.3 | Not Detected |
| trans-1,2-Dichloroethene | 1.5 | Not Detected | 5.9 | Not Detected |
| Hexane | 1.5 | Not Detected | 5.2 | Not Detected |
| 1,1-Dichloroethane | 1.5 | Not Detected | 6.0 | Not Detected |
| 2-Butanone (Methyl Ethyl Ketone) | 5.9 | Not Detected | 17 | Not Detected |
| cis-1,2-Dichloroethene | 1.5 | Not Detected | 5.9 | Not Detected |
| Tetrahydrofuran | 1.5 | Not Detected | 4.4 | Not Detected |
| Chloroform | 1.5 | Not Detected | 7.2 | Not Detected |
| 1,1,1-Trichloroethane | 1.5 | Not Detected | 8.1 | Not Detected |
| Cyclohexane | 1.5 | Not Detected | 5.1 | Not Detected |
| Carbon Tetrachloride | 1.5 | Not Detected | 9.3 | Not Detected |
| 2,2,4-Trimethylpentane | 1.5 | 0.35 J | 6.9 | 1.6 J |
| Benzene | 1.5 | 0.56 J | 4.7 | 1.8 J |
| 1,2-Dichloroethane | 1.5 | Not Detected | 6.0 | Not Detected |
| Heptane | 1.5 | Not Detected | 6.1 | Not Detected |
| Trichloroethene | 1.5 | Not Detected | 8.0 | Not Detected |
| 1,2-Dichloropropane | 1.5 | Not Detected | 6.8 | Not Detected |
| 1,4-Dioxane | 5.9 | Not Detected | 21 | Not Detected |
| Bromodichloromethane | 1.5 | Not Detected | 9.9 | Not Detected |
| cis-1,3-Dichloropropene | 1.5 | Not Detected | 6.7 | Not Detected |
| 4-Methyl-2-pentanone | 1.5 | Not Detected | 6.1 | Not Detected |
| Toluene | 1.5 | ~~0.11 J~~ U | 5.6 | ~~0.41 J~~ U |
| trans-1,3-Dichloropropene | 1.5 | Not Detected | 6.7 | Not Detected |
| 1,1,2-Trichloroethane | 1.5 | Not Detected | 8.1 | Not Detected |
| Tetrachloroethene | 1.5 | Not Detected | 10 | Not Detected |
| 2-Hexanone | 5.9 | Not Detected | 24 | Not Detected |

eurofins | Air Toxics

**Client Sample ID: VMP-41-10-012913**

**Lab ID#: 1301567A-15A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p020519** | **Date of Collection:** | **1/29/13 9:29:00 AM** |
| **Dil. Factor:** | **2.96** | **Date of Analysis:** | **2/5/13 07:40 PM** |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Dibromochloromethane | 1.5 | Not Detected | 13 | Not Detected |
| 1,2-Dibromoethane (EDB) | 1.5 | Not Detected | 11 | Not Detected |
| Chlorobenzene | 1.5 | Not Detected | 6.8 | Not Detected |
| Ethyl Benzene | 1.5 | Not Detected | 6.4 | Not Detected |
| m,p-Xylene | 1.5 | Not Detected | 6.4 | Not Detected |
| o-Xylene | 1.5 | Not Detected | 6.4 | Not Detected |
| Styrene | 1.5 | Not Detected | 6.3 | Not Detected |
| Bromoform | 1.5 | Not Detected | 15 | Not Detected |
| Cumene | 1.5 | Not Detected | 7.3 | Not Detected |
| 1,1,2,2-Tetrachloroethane | 1.5 | Not Detected | 10 | Not Detected |
| Propylbenzene | 1.5 | Not Detected | 7.3 | Not Detected |
| 4-Ethyltoluene | 1.5 | Not Detected | 7.3 | Not Detected |
| 1,3,5-Trimethylbenzene | 1.5 | Not Detected | 7.3 | Not Detected |
| 1,2,4-Trimethylbenzene | 1.5 | Not Detected | 7.3 | Not Detected |
| 1,3-Dichlorobenzene | 1.5 | Not Detected | 8.9 | Not Detected |
| 1,4-Dichlorobenzene | 1.5 | Not Detected | 8.9 | Not Detected |
| alpha-Chlorotoluene | 1.5 | Not Detected | 7.7 | Not Detected |
| 1,2-Dichlorobenzene | 1.5 | Not Detected | 8.9 | Not Detected |
| 1,2,4-Trichlorobenzene | 5.9 | Not Detected | 44 | Not Detected |
| Hexachlorobutadiene | 5.9 | Not Detected | 63 | Not Detected |
| Butane | 5.9 | Not Detected | 14 | Not Detected |
| Isopentane | 5.9 | Not Detected | 17 | Not Detected |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| Toluene-d8 | 98 | 70-130 |
| 1,2-Dichloroethane-d4 | 102 | 70-130 |
| 4-Bromofluorobenzene | 94 | 70-130 |

eurofins | Air Toxics

**Client Sample ID: VMP-41-20-012913**

**Lab ID#: 1301567A-16A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | p020520 | **Date of Collection:** | 1/29/13 10:21:00 AM |
| **Dil. Factor:** | 3.03 | **Date of Analysis:** | 2/5/13 08:30 PM |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 1.5 | 0.55 J | 7.5 | 2.7 J |
| Freon 114 | 1.5 | Not Detected | 10 | Not Detected |
| Chloromethane | 15 | Not Detected | 31 | Not Detected |
| Vinyl Chloride | 1.5 | Not Detected | 3.9 | Not Detected |
| 1,3-Butadiene | 1.5 | Not Detected | 3.4 | Not Detected |
| Bromomethane | 15 | Not Detected | 59 | Not Detected |
| Chloroethane | 6.1 | Not Detected | 16 | Not Detected |
| Freon 11 | 1.5 | 0.32 J | 8.5 | 1.8 J |
| Ethanol | 6.1 | Not Detected | 11 | Not Detected |
| Freon 113 | 1.5 | Not Detected | 12 | Not Detected |
| 1,1-Dichloroethene | 1.5 | Not Detected | 6.0 | Not Detected |
| Acetone | 15 | 4.0 J | 36 | 9.6 J |
| 2-Propanol | 6.1 | 4.3 J | 15 | 10 J |
| Carbon Disulfide | 6.1 | ~~1.0 J~~ | 19 | ~~3.1 J~~ |
| 3-Chloropropene | 6.1 | Not Detected | 19 | Not Detected |
| Methylene Chloride | 15 | ~~0.20 J~~ | 53 | ~~0.70 J~~ |
| Methyl tert-butyl ether | 1.5 | Not Detected | 5.5 | Not Detected |
| trans-1,2-Dichloroethene | 1.5 | Not Detected | 6.0 | Not Detected |
| Hexane | 1.5 | 0.49 J | 5.3 | 1.7 J |
| 1,1-Dichloroethane | 1.5 | Not Detected | 6.1 | Not Detected |
| 2-Butanone (Methyl Ethyl Ketone) | 6.1 | Not Detected | 18 | Not Detected |
| cis-1,2-Dichloroethene | 1.5 | Not Detected | 6.0 | Not Detected |
| Tetrahydrofuran | 1.5 | Not Detected | 4.5 | Not Detected |
| Chloroform | 1.5 | Not Detected | 7.4 | Not Detected |
| 1,1,1-Trichloroethane | 1.5 | Not Detected | 8.3 | Not Detected |
| Cyclohexane | 1.5 | Not Detected | 5.2 | Not Detected |
| Carbon Tetrachloride | 1.5 | Not Detected | 9.5 | Not Detected |
| 2,2,4-Trimethylpentane | 1.5 | 4.4 | 7.1 | 21 |
| Benzene | 1.5 | 1.4 J | 4.8 | 4.4 J |
| 1,2-Dichloroethane | 1.5 | Not Detected | 6.1 | Not Detected |
| Heptane | 1.5 | Not Detected | 6.2 | Not Detected |
| Trichloroethene | 1.5 | Not Detected | 8.1 | Not Detected |
| 1,2-Dichloropropane | 1.5 | Not Detected | 7.0 | Not Detected |
| 1,4-Dioxane | 6.1 | Not Detected | 22 | Not Detected |
| Bromodichloromethane | 1.5 | Not Detected | 10 | Not Detected |
| cis-1,3-Dichloropropene | 1.5 | Not Detected | 6.9 | Not Detected |
| 4-Methyl-2-pentanone | 1.5 | Not Detected | 6.2 | Not Detected |
| Toluene | 1.5 | ~~0.14 J~~ | 5.7 | ~~0.53 J~~ |
| trans-1,3-Dichloropropene | 1.5 | Not Detected | 6.9 | Not Detected |
| 1,1,2-Trichloroethane | 1.5 | Not Detected | 8.3 | Not Detected |
| Tetrachloroethene | 1.5 | 0.24 J | 10 | 1.6 J |
| 2-Hexanone | 6.1 | Not Detected | 25 | Not Detected |

eurofins | Air Toxics

**Client Sample ID: VMP-41-20-012913**

**Lab ID#: 1301567A-16A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p020520** | **Date of Collection: 1/29/13 10:21:00 AM** | |
| **Dil. Factor:** | **3.03** | **Date of Analysis: 2/5/13 08:30 PM** | |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Dibromochloromethane | 1.5 | Not Detected | 13 | Not Detected |
| 1,2-Dibromoethane (EDB) | 1.5 | Not Detected | 12 | Not Detected |
| Chlorobenzene | 1.5 | Not Detected | 7.0 | Not Detected |
| Ethyl Benzene | 1.5 | Not Detected | 6.6 | Not Detected |
| m,p-Xylene | 1.5 | Not Detected | 6.6 | Not Detected |
| o-Xylene | 1.5 | Not Detected | 6.6 | Not Detected |
| Styrene | 1.5 | Not Detected | 6.4 | Not Detected |
| Bromoform | 1.5 | Not Detected | 16 | Not Detected |
| Cumene | 1.5 | Not Detected | 7.4 | Not Detected |
| 1,1,2,2-Tetrachloroethane | 1.5 | Not Detected | 10 | Not Detected |
| Propylbenzene | 1.5 | Not Detected | 7.4 | Not Detected |
| 4-Ethyltoluene | 1.5 | Not Detected | 7.4 | Not Detected |
| 1,3,5-Trimethylbenzene | 1.5 | Not Detected | 7.4 | Not Detected |
| 1,2,4-Trimethylbenzene | 1.5 | Not Detected | 7.4 | Not Detected |
| 1,3-Dichlorobenzene | 1.5 | Not Detected | 9.1 | Not Detected |
| 1,4-Dichlorobenzene | 1.5 | Not Detected | 9.1 | Not Detected |
| alpha-Chlorotoluene | 1.5 | Not Detected | 7.8 | Not Detected |
| 1,2-Dichlorobenzene | 1.5 | Not Detected | 9.1 | Not Detected |
| 1,2,4-Trichlorobenzene | 6.1 | ~~0.52 J~~ | 45 | ~~3.9 J~~ |
| Hexachlorobutadiene | 6.1 | Not Detected | 65 | Not Detected |
| Butane | 6.1 | Not Detected | 14 | Not Detected |
| Isopentane | 6.1 | 2.6 J | 18 | 7.6 J |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| Toluene-d8 | 99 | 70-130 |
| 1,2-Dichloroethane-d4 | 103 | 70-130 |
| 4-Bromofluorobenzene | 96 | 70-130 |

eurofins | Air Toxics

**Client Sample ID: VMP-41-30-012913**

**Lab ID#: 1301567A-17A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p020521** | **Date of Collection:** | **1/29/13 11:14:00 AM** |
| **Dil. Factor:** | **2.82** | **Date of Analysis:** | **2/5/13 09:17 PM** |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 1.4 | 0.65 J | 7.0 | 3.2 J |
| Freon 114 | 1.4 | Not Detected | 9.8 | Not Detected |
| Chloromethane | 14 | Not Detected | 29 | Not Detected |
| Vinyl Chloride | 1.4 | Not Detected | 3.6 | Not Detected |
| 1,3-Butadiene | 1.4 | Not Detected | 3.1 | Not Detected |
| Bromomethane | 14 | Not Detected | 55 | Not Detected |
| Chloroethane | 5.6 | Not Detected | 15 | Not Detected |
| Freon 11 | 1.4 | 0.34 J | 7.9 | 1.9 J |
| Ethanol | 5.6 | 2.9 J | 11 | 5.4 J |
| Freon 113 | 1.4 | Not Detected | 11 | Not Detected |
| 1,1-Dichloroethene | 1.4 | Not Detected | 5.6 | Not Detected |
| Acetone | 14 | 4.7 J | 33 | 11 J |
| 2-Propanol | 5.6 | 5.4 J | 14 | 13 J |
| Carbon Disulfide | 5.6 | ~~4.1 J~~ U | 18 | ~~3.4 J~~ U |
| 3-Chloropropene | 5.6 | Not Detected | 18 | Not Detected |
| Methylene Chloride | 14 | ~~0.69 J~~ U | 49 | ~~2.4 J~~ U |
| Methyl tert-butyl ether | 1.4 | Not Detected | 5.1 | Not Detected |
| trans-1,2-Dichloroethene | 1.4 | Not Detected | 5.6 | Not Detected |
| Hexane | 1.4 | 2.5 | 5.0 | 8.8 |
| 1,1-Dichloroethane | 1.4 | Not Detected | 5.7 | Not Detected |
| 2-Butanone (Methyl Ethyl Ketone) | 5.6 | Not Detected | 17 | Not Detected |
| cis-1,2-Dichloroethene | 1.4 | Not Detected | 5.6 | Not Detected |
| Tetrahydrofuran | 1.4 | Not Detected | 4.2 | Not Detected |
| Chloroform | 1.4 | 0.47 J | 6.9 | 2.3 J |
| 1,1,1-Trichloroethane | 1.4 | Not Detected | 7.7 | Not Detected |
| Cyclohexane | 1.4 | Not Detected | 4.8 | Not Detected |
| Carbon Tetrachloride | 1.4 | Not Detected | 8.9 | Not Detected |
| 2,2,4-Trimethylpentane | 1.4 | 4.2 | 6.6 | 20 |
| Benzene | 1.4 | 2.4 | 4.5 | 7.7 |
| 1,2-Dichloroethane | 1.4 | Not Detected | 5.7 | Not Detected |
| Heptane | 1.4 | 2.0 | 5.8 | 8.2 |
| Trichloroethene | 1.4 | Not Detected | 7.6 | Not Detected |
| 1,2-Dichloropropane | 1.4 | Not Detected | 6.5 | Not Detected |
| 1,4-Dioxane | 5.6 | Not Detected | 20 | Not Detected |
| Bromodichloromethane | 1.4 | Not Detected | 9.4 | Not Detected |
| cis-1,3-Dichloropropene | 1.4 | Not Detected | 6.4 | Not Detected |
| 4-Methyl-2-pentanone | 1.4 | Not Detected | 5.8 | Not Detected |
| Toluene | 1.4 | 0.35 J | 5.3 | 1.3 J |
| trans-1,3-Dichloropropene | 1.4 | Not Detected | 6.4 | Not Detected |
| 1,1,2-Trichloroethane | 1.4 | Not Detected | 7.7 | Not Detected |
| Tetrachloroethene | 1.4 | 0.40 J | 9.6 | 2.7 J |
| 2-Hexanone | 5.6 | Not Detected | 23 | Not Detected |

eurofins | Air Toxics

**Client Sample ID: VMP-41-30-012913**

**Lab ID#: 1301567A-17A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p020521** | **Date of Collection:** | **1/29/13 11:14:00 AM** |
| **Dil. Factor:** | **2.82** | **Date of Analysis:** | **2/5/13 09:17 PM** |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Dibromochloromethane | 1.4 | Not Detected | 12 | Not Detected |
| 1,2-Dibromoethane (EDB) | 1.4 | Not Detected | 11 | Not Detected |
| Chlorobenzene | 1.4 | Not Detected | 6.5 | Not Detected |
| Ethyl Benzene | 1.4 | Not Detected | 6.1 | Not Detected |
| m,p-Xylene | 1.4 | Not Detected | 6.1 | Not Detected |
| o-Xylene | 1.4 | Not Detected | 6.1 | Not Detected |
| Styrene | 1.4 | Not Detected | 6.0 | Not Detected |
| Bromoform | 1.4 | Not Detected | 14 | Not Detected |
| Cumene | 1.4 | Not Detected | 6.9 | Not Detected |
| 1,1,2,2-Tetrachloroethane | 1.4 | Not Detected | 9.7 | Not Detected |
| Propylbenzene | 1.4 | Not Detected | 6.9 | Not Detected |
| 4-Ethyltoluene | 1.4 | Not Detected | 6.9 | Not Detected |
| 1,3,5-Trimethylbenzene | 1.4 | Not Detected | 6.9 | Not Detected |
| 1,2,4-Trimethylbenzene | 1.4 | Not Detected | 6.9 | Not Detected |
| 1,3-Dichlorobenzene | 1.4 | Not Detected | 8.5 | Not Detected |
| 1,4-Dichlorobenzene | 1.4 | Not Detected | 8.5 | Not Detected |
| alpha-Chlorotoluene | 1.4 | Not Detected | 7.3 | Not Detected |
| 1,2-Dichlorobenzene | 1.4 | Not Detected | 8.5 | Not Detected |
| 1,2,4-Trichlorobenzene | 5.6 | Not Detected | 42 | Not Detected |
| Hexachlorobutadiene | 5.6 | Not Detected | 60 | Not Detected |
| Butane | 5.6 | 8.0 | 13 | 19 |
| Isopentane | 5.6 | 1.9 J | 17 | 5.6 J |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| Toluene-d8 | 96 | 70-130 |
| 1,2-Dichloroethane-d4 | 103 | 70-130 |
| 4-Bromofluorobenzene | 96 | 70-130 |

eurofins | Air Toxics

**Client Sample ID: Lab Blank**

**Lab ID#: 1301567A-18A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| File Name: | p020505a | Date of Collection: NA | |
| Dil. Factor: | 1.00 | Date of Analysis: 2/5/13 11:31 AM | |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 0.50 | Not Detected | 2.5 | Not Detected |
| Freon 114 | 0.50 | Not Detected | 3.5 | Not Detected |
| Chloromethane | 5.0 | Not Detected | 10 | Not Detected |
| Vinyl Chloride | 0.50 | Not Detected | 1.3 | Not Detected |
| 1,3-Butadiene | 0.50 | Not Detected | 1.1 | Not Detected |
| Bromomethane | 5.0 | 0.38 J | 19 | 1.5 J |
| Chloroethane | 2.0 | Not Detected | 5.3 | Not Detected |
| Freon 11 | 0.50 | Not Detected | 2.8 | Not Detected |
| Ethanol | 2.0 | Not Detected | 3.8 | Not Detected |
| Freon 113 | 0.50 | Not Detected | 3.8 | Not Detected |
| 1,1-Dichloroethene | 0.50 | Not Detected | 2.0 | Not Detected |
| Acetone | 5.0 | Not Detected | 12 | Not Detected |
| 2-Propanol | 2.0 | Not Detected | 4.9 | Not Detected |
| Carbon Disulfide | 2.0 | 0.66 J | 6.2 | 2.0 J |
| 3-Chloropropene | 2.0 | Not Detected | 6.3 | Not Detected |
| Methylene Chloride | 5.0 | 0.19 J | 17 | 0.66 J |
| Methyl tert-butyl ether | 0.50 | Not Detected | 1.8 | Not Detected |
| trans-1,2-Dichloroethene | 0.50 | 0.16 J | 2.0 | 0.63 J |
| Hexane | 0.50 | Not Detected | 1.8 | Not Detected |
| 1,1-Dichloroethane | 0.50 | Not Detected | 2.0 | Not Detected |
| 2-Butanone (Methyl Ethyl Ketone) | 2.0 | Not Detected | 5.9 | Not Detected |
| cis-1,2-Dichloroethene | 0.50 | Not Detected | 2.0 | Not Detected |
| Tetrahydrofuran | 0.50 | Not Detected | 1.5 | Not Detected |
| Chloroform | 0.50 | Not Detected | 2.4 | Not Detected |
| 1,1,1-Trichloroethane | 0.50 | Not Detected | 2.7 | Not Detected |
| Cyclohexane | 0.50 | Not Detected | 1.7 | Not Detected |
| Carbon Tetrachloride | 0.50 | Not Detected | 3.1 | Not Detected |
| 2,2,4-Trimethylpentane | 0.50 | Not Detected | 2.3 | Not Detected |
| Benzene | 0.50 | Not Detected | 1.6 | Not Detected |
| 1,2-Dichloroethane | 0.50 | Not Detected | 2.0 | Not Detected |
| Heptane | 0.50 | Not Detected | 2.0 | Not Detected |
| Trichloroethene | 0.50 | Not Detected | 2.7 | Not Detected |
| 1,2-Dichloropropane | 0.50 | Not Detected | 2.3 | Not Detected |
| 1,4-Dioxane | 2.0 | Not Detected | 7.2 | Not Detected |
| Bromodichloromethane | 0.50 | Not Detected | 3.4 | Not Detected |
| cis-1,3-Dichloropropene | 0.50 | 0.10 J | 2.3 | 0.47 J |
| 4-Methyl-2-pentanone | 0.50 | 0.12 J | 2.0 | 0.48 J |
| Toluene | 0.50 | 0.076 J | 1.9 | 0.29 J |
| trans-1,3-Dichloropropene | 0.50 | 0.19 J | 2.3 | 0.86 J |
| 1,1,2-Trichloroethane | 0.50 | Not Detected | 2.7 | Not Detected |
| Tetrachloroethene | 0.50 | 0.12 J | 3.4 | 0.80 J |
| 2-Hexanone | 2.0 | Not Detected | 8.2 | Not Detected |

**Client Sample ID: Lab Blank**

**Lab ID#: 1301567A-18A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p020505a** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 2/5/13 11:31 AM** | |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Dibromochloromethane | 0.50 | Not Detected | 4.2 | Not Detected |
| 1,2-Dibromoethane (EDB) | 0.50 | 0.14 J | 3.8 | 1.1 J |
| Chlorobenzene | 0.50 | 0.12 J | 2.3 | 0.56 J |
| Ethyl Benzene | 0.50 | Not Detected | 2.2 | Not Detected |
| m,p-Xylene | 0.50 | Not Detected | 2.2 | Not Detected |
| o-Xylene | 0.50 | 0.080 J | 2.2 | 0.35 J |
| Styrene | 0.50 | 0.096 J | 2.1 | 0.41 J |
| Bromoform | 0.50 | Not Detected | 5.2 | Not Detected |
| Cumene | 0.50 | 0.11 J | 2.4 | 0.55 J |
| 1,1,2,2-Tetrachloroethane | 0.50 | 0.14 J | 3.4 | 0.93 J |
| Propylbenzene | 0.50 | 0.13 J | 2.4 | 0.64 J |
| 4-Ethyltoluene | 0.50 | 0.12 J | 2.4 | 0.57 J |
| 1,3,5-Trimethylbenzene | 0.50 | 0.19 J | 2.4 | 0.92 J |
| 1,2,4-Trimethylbenzene | 0.50 | 0.18 J | 2.4 | 0.89 J |
| 1,3-Dichlorobenzene | 0.50 | 0.33 J | 3.0 | 2.0 J |
| 1,4-Dichlorobenzene | 0.50 | 0.31 J | 3.0 | 1.9 J |
| alpha-Chlorotoluene | 0.50 | 0.20 J | 2.6 | 1.0 J |
| 1,2-Dichlorobenzene | 0.50 | 0.33 J | 3.0 | 2.0 J |
| 1,2,4-Trichlorobenzene | 2.0 | 1.2 J | 15 | 8.6 J |
| Hexachlorobutadiene | 2.0 | 0.62 J | 21 | 6.6 J |
| Butane | 2.0 | Not Detected | 4.8 | Not Detected |
| Isopentane | 2.0 | Not Detected | 5.9 | Not Detected |

J = Estimated value.

**Container Type: NA - Not Applicable**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| Toluene-d8 | 98 | 70-130 |
| 1,2-Dichloroethane-d4 | 97 | 70-130 |
| 4-Bromofluorobenzene | 96 | 70-130 |

eurofins | Air Toxics

**Client Sample ID: Lab Blank**

**Lab ID#: 1301567A-18B**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | p020606a | **Date of Collection:** | NA |
| **Dil. Factor:** | 1.00 | **Date of Analysis:** | 2/6/13 12:47 PM |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 0.50 | Not Detected | 2.5 | Not Detected |
| Freon 114 | 0.50 | Not Detected | 3.5 | Not Detected |
| Chloromethane | 5.0 | Not Detected | 10 | Not Detected |
| Vinyl Chloride | 0.50 | Not Detected | 1.3 | Not Detected |
| 1,3-Butadiene | 0.50 | Not Detected | 1.1 | Not Detected |
| Bromomethane | 5.0 | Not Detected | 19 | Not Detected |
| Chloroethane | 2.0 | Not Detected | 5.3 | Not Detected |
| Freon 11 | 0.50 | Not Detected | 2.8 | Not Detected |
| Ethanol | 2.0 | Not Detected | 3.8 | Not Detected |
| Freon 113 | 0.50 | Not Detected | 3.8 | Not Detected |
| 1,1-Dichloroethene | 0.50 | Not Detected | 2.0 | Not Detected |
| Acetone | 5.0 | Not Detected | 12 | Not Detected |
| 2-Propanol | 2.0 | Not Detected | 4.9 | Not Detected |
| Carbon Disulfide | 2.0 | 0.38 J | 6.2 | 1.2 J |
| 3-Chloropropene | 2.0 | Not Detected | 6.3 | Not Detected |
| Methylene Chloride | 5.0 | 0.068 J | 17 | 0.24 J |
| Methyl tert-butyl ether | 0.50 | Not Detected | 1.8 | Not Detected |
| trans-1,2-Dichloroethene | 0.50 | Not Detected | 2.0 | Not Detected |
| Hexane | 0.50 | Not Detected | 1.8 | Not Detected |
| 1,1-Dichloroethane | 0.50 | Not Detected | 2.0 | Not Detected |
| 2-Butanone (Methyl Ethyl Ketone) | 2.0 | Not Detected | 5.9 | Not Detected |
| cis-1,2-Dichloroethene | 0.50 | Not Detected | 2.0 | Not Detected |
| Tetrahydrofuran | 0.50 | Not Detected | 1.5 | Not Detected |
| Chloroform | 0.50 | Not Detected | 2.4 | Not Detected |
| 1,1,1-Trichloroethane | 0.50 | Not Detected | 2.7 | Not Detected |
| Cyclohexane | 0.50 | Not Detected | 1.7 | Not Detected |
| Carbon Tetrachloride | 0.50 | Not Detected | 3.1 | Not Detected |
| 2,2,4-Trimethylpentane | 0.50 | Not Detected | 2.3 | Not Detected |
| Benzene | 0.50 | Not Detected | 1.6 | Not Detected |
| 1,2-Dichloroethane | 0.50 | Not Detected | 2.0 | Not Detected |
| Heptane | 0.50 | Not Detected | 2.0 | Not Detected |
| Trichloroethene | 0.50 | Not Detected | 2.7 | Not Detected |
| 1,2-Dichloropropane | 0.50 | Not Detected | 2.3 | Not Detected |
| 1,4-Dioxane | 2.0 | Not Detected | 7.2 | Not Detected |
| Bromodichloromethane | 0.50 | Not Detected | 3.4 | Not Detected |
| cis-1,3-Dichloropropene | 0.50 | Not Detected | 2.3 | Not Detected |
| 4-Methyl-2-pentanone | 0.50 | Not Detected | 2.0 | Not Detected |
| Toluene | 0.50 | 0.035 J | 1.9 | 0.13 J |
| trans-1,3-Dichloropropene | 0.50 | Not Detected | 2.3 | Not Detected |
| 1,1,2-Trichloroethane | 0.50 | Not Detected | 2.7 | Not Detected |
| Tetrachloroethene | 0.50 | Not Detected | 3.4 | Not Detected |
| 2-Hexanone | 2.0 | Not Detected | 8.2 | Not Detected |

eurofins | Air Toxics

**Client Sample ID: Lab Blank**

**Lab ID#: 1301567A-18B**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p020606a** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 2/6/13 12:47 PM** | |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Dibromochloromethane | 0.50 | Not Detected | 4.2 | Not Detected |
| 1,2-Dibromoethane (EDB) | 0.50 | Not Detected | 3.8 | Not Detected |
| Chlorobenzene | 0.50 | Not Detected | 2.3 | Not Detected |
| Ethyl Benzene | 0.50 | Not Detected | 2.2 | Not Detected |
| m,p-Xylene | 0.50 | Not Detected | 2.2 | Not Detected |
| o-Xylene | 0.50 | Not Detected | 2.2 | Not Detected |
| Styrene | 0.50 | Not Detected | 2.1 | Not Detected |
| Bromoform | 0.50 | Not Detected | 5.2 | Not Detected |
| Cumene | 0.50 | Not Detected | 2.4 | Not Detected |
| 1,1,2,2-Tetrachloroethane | 0.50 | Not Detected | 3.4 | Not Detected |
| Propylbenzene | 0.50 | Not Detected | 2.4 | Not Detected |
| 4-Ethyltoluene | 0.50 | 0.080 J | 2.4 | 0.39 J |
| 1,3,5-Trimethylbenzene | 0.50 | Not Detected | 2.4 | Not Detected |
| 1,2,4-Trimethylbenzene | 0.50 | Not Detected | 2.4 | Not Detected |
| 1,3-Dichlorobenzene | 0.50 | 0.13 J | 3.0 | 0.79 J |
| 1,4-Dichlorobenzene | 0.50 | 0.13 J | 3.0 | 0.80 J |
| alpha-Chlorotoluene | 0.50 | Not Detected | 2.6 | Not Detected |
| 1,2-Dichlorobenzene | 0.50 | 0.10 J | 3.0 | 0.63 J |
| 1,2,4-Trichlorobenzene | 2.0 | 0.44 J | 15 | 3.3 J |
| Hexachlorobutadiene | 2.0 | 0.20 J | 21 | 2.1 J |
| Butane | 2.0 | Not Detected | 4.8 | Not Detected |
| Isopentane | 2.0 | Not Detected | 5.9 | Not Detected |

J = Estimated value.

**Container Type: NA - Not Applicable**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| Toluene-d8 | 98 | 70-130 |
| 1,2-Dichloroethane-d4 | 99 | 70-130 |
| 4-Bromofluorobenzene | 96 | 70-130 |

eurofins | Air Toxics

**Client Sample ID: CCV**

**Lab ID#: 1301567A-19A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p020502** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 2/5/13 09:06 AM** | |

| Compound | %Recovery |
|---|---|
| Freon 12 | 96 |
| Freon 114 | 99 |
| Chloromethane | 97 |
| Vinyl Chloride | 103 |
| 1,3-Butadiene | 101 |
| Bromomethane | 102 |
| Chloroethane | 99 |
| Freon 11 | 95 |
| Ethanol | 105 |
| Freon 113 | 100 |
| 1,1-Dichloroethene | 101 |
| Acetone | 103 |
| 2-Propanol | 102 |
| Carbon Disulfide | 98 |
| 3-Chloropropene | 104 |
| Methylene Chloride | 99 |
| Methyl tert-butyl ether | 106 |
| trans-1,2-Dichloroethene | 104 |
| Hexane | 106 |
| 1,1-Dichloroethane | 99 |
| 2-Butanone (Methyl Ethyl Ketone) | 101 |
| cis-1,2-Dichloroethene | 106 |
| Tetrahydrofuran | 109 |
| Chloroform | 98 |
| 1,1,1-Trichloroethane | 100 |
| Cyclohexane | 114 |
| Carbon Tetrachloride | 98 |
| 2,2,4-Trimethylpentane | 109 |
| Benzene | 104 |
| 1,2-Dichloroethane | 99 |
| Heptane | 114 |
| Trichloroethene | 85 |
| 1,2-Dichloropropane | 103 |
| 1,4-Dioxane | 114 |
| Bromodichloromethane | 100 |
| cis-1,3-Dichloropropene | 106 |
| 4-Methyl-2-pentanone | 117 |
| Toluene | 102 |
| trans-1,3-Dichloropropene | 108 |
| 1,1,2-Trichloroethane | 102 |
| Tetrachloroethene | 97 |
| 2-Hexanone | 108 |

eurofins | Air Toxics

**Client Sample ID: CCV**

**Lab ID#: 1301567A-19A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p020502** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 2/5/13 09:06 AM** | |

| Compound | %Recovery |
|---|---|
| Dibromochloromethane | 104 |
| 1,2-Dibromoethane (EDB) | 100 |
| Chlorobenzene | 96 |
| Ethyl Benzene | 106 |
| m,p-Xylene | 111 |
| o-Xylene | 112 |
| Styrene | 119 |
| Bromoform | 104 |
| Cumene | 113 |
| 1,1,2,2-Tetrachloroethane | 111 |
| Propylbenzene | 107 |
| 4-Ethyltoluene | 114 |
| 1,3,5-Trimethylbenzene | 115 |
| 1,2,4-Trimethylbenzene | 114 |
| 1,3-Dichlorobenzene | 104 |
| 1,4-Dichlorobenzene | 102 |
| alpha-Chlorotoluene | 110 |
| 1,2-Dichlorobenzene | 105 |
| 1,2,4-Trichlorobenzene | 105 |
| Hexachlorobutadiene | 102 |
| Butane | 98 |
| Isopentane | 102 |

**Container Type: NA - Not Applicable**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| Toluene-d8 | 103 | 70-130 |
| 1,2-Dichloroethane-d4 | 96 | 70-130 |
| 4-Bromofluorobenzene | 101 | 70-130 |

eurofins | Air Toxics

**Client Sample ID: CCV**

**Lab ID#: 1301567A-19B**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p020602** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 2/6/13 10:30 AM** | |

| Compound | %Recovery |
|---|---|
| Freon 12 | 97 |
| Freon 114 | 97 |
| Chloromethane | 96 |
| Vinyl Chloride | 100 |
| 1,3-Butadiene | 98 |
| Bromomethane | 99 |
| Chloroethane | 97 |
| Freon 11 | 97 |
| Ethanol | 103 |
| Freon 113 | 97 |
| 1,1-Dichloroethene | 97 |
| Acetone | 98 |
| 2-Propanol | 97 |
| Carbon Disulfide | 94 |
| 3-Chloropropene | 97 |
| Methylene Chloride | 99 |
| Methyl tert-butyl ether | 104 |
| trans-1,2-Dichloroethene | 102 |
| Hexane | 102 |
| 1,1-Dichloroethane | 97 |
| 2-Butanone (Methyl Ethyl Ketone) | 94 |
| cis-1,2-Dichloroethene | 103 |
| Tetrahydrofuran | 105 |
| Chloroform | 97 |
| 1,1,1-Trichloroethane | 101 |
| Cyclohexane | 108 |
| Carbon Tetrachloride | 100 |
| 2,2,4-Trimethylpentane | 106 |
| Benzene | 103 |
| 1,2-Dichloroethane | 102 |
| Heptane | 116 |
| Trichloroethene | 85 |
| 1,2-Dichloropropane | 102 |
| 1,4-Dioxane | 110 |
| Bromodichloromethane | 101 |
| cis-1,3-Dichloropropene | 105 |
| 4-Methyl-2-pentanone | 116 |
| Toluene | 102 |
| trans-1,3-Dichloropropene | 109 |
| 1,1,2-Trichloroethane | 104 |
| Tetrachloroethene | 100 |
| 2-Hexanone | 110 |

eurofins | Air Toxics

**Client Sample ID: CCV**

**Lab ID#: 1301567A-19B**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p020602** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 2/6/13 10:30 AM** | |

| Compound | %Recovery |
|---|---|
| Dibromochloromethane | 108 |
| 1,2-Dibromoethane (EDB) | 103 |
| Chlorobenzene | 97 |
| Ethyl Benzene | 108 |
| m,p-Xylene | 112 |
| o-Xylene | 111 |
| Styrene | 119 |
| Bromoform | 106 |
| Cumene | 115 |
| 1,1,2,2-Tetrachloroethane | 111 |
| Propylbenzene | 109 |
| 4-Ethyltoluene | 112 |
| 1,3,5-Trimethylbenzene | 117 |
| 1,2,4-Trimethylbenzene | 113 |
| 1,3-Dichlorobenzene | 104 |
| 1,4-Dichlorobenzene | 103 |
| alpha-Chlorotoluene | 111 |
| 1,2-Dichlorobenzene | 104 |
| 1,2,4-Trichlorobenzene | 100 |
| Hexachlorobutadiene | 101 |
| Butane | 95 |
| Isopentane | 100 |

**Container Type: NA - Not Applicable**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| Toluene-d8 | 104 | 70-130 |
| 1,2-Dichloroethane-d4 | 99 | 70-130 |
| 4-Bromofluorobenzene | 104 | 70-130 |

eurofins | Air Toxics

**Client Sample ID: LCS**

**Lab ID#: 1301567A-20A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p020503** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 2/5/13 10:03 AM** | |

| Compound | %Recovery |
|---|---|
| Freon 12 | 99 |
| Freon 114 | 102 |
| Chloromethane | 102 |
| Vinyl Chloride | 109 |
| 1,3-Butadiene | 104 |
| Bromomethane | 104 |
| Chloroethane | 105 |
| Freon 11 | 97 |
| Ethanol | 79 |
| Freon 113 | 102 |
| 1,1-Dichloroethene | 110 |
| Acetone | 107 |
| 2-Propanol | 104 |
| Carbon Disulfide | 123 |
| 3-Chloropropene | 120 |
| Methylene Chloride | 101 |
| Methyl tert-butyl ether | 106 |
| trans-1,2-Dichloroethene | 121 |
| Hexane | 108 |
| 1,1-Dichloroethane | 101 |
| 2-Butanone (Methyl Ethyl Ketone) | 103 |
| cis-1,2-Dichloroethene | 108 |
| Tetrahydrofuran | 109 |
| Chloroform | 100 |
| 1,1,1-Trichloroethane | 103 |
| Cyclohexane | 117 |
| Carbon Tetrachloride | 100 |
| 2,2,4-Trimethylpentane | 111 |
| Benzene | 104 |
| 1,2-Dichloroethane | 95 |
| Heptane | 111 |
| Trichloroethene | 83 |
| 1,2-Dichloropropane | 101 |
| 1,4-Dioxane | 110 |
| Bromodichloromethane | 96 |
| cis-1,3-Dichloropropene | 107 |
| 4-Methyl-2-pentanone | 116 |
| Toluene | 100 |
| trans-1,3-Dichloropropene | 107 |
| 1,1,2-Trichloroethane | 103 |
| Tetrachloroethene | 99 |
| 2-Hexanone | 108 |

eurofins | Air Toxics

**Client Sample ID: LCS**
**Lab ID#: 1301567A-20A**
**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p020503** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 2/5/13 10:03 AM** | |

| Compound | %Recovery |
|---|---|
| Dibromochloromethane | 103 |
| 1,2-Dibromoethane (EDB) | 103 |
| Chlorobenzene | 98 |
| Ethyl Benzene | 106 |
| m,p-Xylene | 111 |
| o-Xylene | 113 |
| Styrene | 121 |
| Bromoform | 103 |
| Cumene | 114 |
| 1,1,2,2-Tetrachloroethane | 113 |
| Propylbenzene | 108 |
| 4-Ethyltoluene | 108 |
| 1,3,5-Trimethylbenzene | 115 |
| 1,2,4-Trimethylbenzene | 112 |
| 1,3-Dichlorobenzene | 105 |
| 1,4-Dichlorobenzene | 102 |
| alpha-Chlorotoluene | 111 |
| 1,2-Dichlorobenzene | 106 |
| 1,2,4-Trichlorobenzene | 106 |
| Hexachlorobutadiene | 102 |
| Butane | 96 |
| Isopentane | 105 |

**Container Type: NA - Not Applicable**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| Toluene-d8 | 101 | 70-130 |
| 1,2-Dichloroethane-d4 | 97 | 70-130 |
| 4-Bromofluorobenzene | 102 | 70-130 |

eurofins | Air Toxics

**Client Sample ID: LCSD**

**Lab ID#: 1301567A-20AA**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p020504** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 2/5/13 10:21 AM** | |

| Compound | %Recovery |
|---|---|
| Freon 12 | 95 |
| Freon 114 | 98 |
| Chloromethane | 92 |
| Vinyl Chloride | 104 |
| 1,3-Butadiene | 99 |
| Bromomethane | 99 |
| Chloroethane | 100 |
| Freon 11 | 93 |
| Ethanol | 78 |
| Freon 113 | 98 |
| 1,1-Dichloroethene | 106 |
| Acetone | 100 |
| 2-Propanol | 101 |
| Carbon Disulfide | 118 |
| 3-Chloropropene | 118 |
| Methylene Chloride | 96 |
| Methyl tert-butyl ether | 101 |
| trans-1,2-Dichloroethene | 117 |
| Hexane | 104 |
| 1,1-Dichloroethane | 97 |
| 2-Butanone (Methyl Ethyl Ketone) | 98 |
| cis-1,2-Dichloroethene | 106 |
| Tetrahydrofuran | 105 |
| Chloroform | 97 |
| 1,1,1-Trichloroethane | 99 |
| Cyclohexane | 112 |
| Carbon Tetrachloride | 96 |
| 2,2,4-Trimethylpentane | 108 |
| Benzene | 103 |
| 1,2-Dichloroethane | 93 |
| Heptane | 111 |
| Trichloroethene | 84 |
| 1,2-Dichloropropane | 102 |
| 1,4-Dioxane | 111 |
| Bromodichloromethane | 96 |
| cis-1,3-Dichloropropene | 104 |
| 4-Methyl-2-pentanone | 116 |
| Toluene | 100 |
| trans-1,3-Dichloropropene | 106 |
| 1,1,2-Trichloroethane | 99 |
| Tetrachloroethene | 97 |
| 2-Hexanone | 105 |

eurofins | Air Toxics

**Client Sample ID: LCSD**

**Lab ID#: 1301567A-20AA**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p020504** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 2/5/13 10:21 AM** | |

| Compound | %Recovery |
|---|---|
| Dibromochloromethane | 99 |
| 1,2-Dibromoethane (EDB) | 100 |
| Chlorobenzene | 95 |
| Ethyl Benzene | 105 |
| m,p-Xylene | 110 |
| o-Xylene | 110 |
| Styrene | 116 |
| Bromoform | 99 |
| Cumene | 113 |
| 1,1,2,2-Tetrachloroethane | 111 |
| Propylbenzene | 107 |
| 4-Ethyltoluene | 107 |
| 1,3,5-Trimethylbenzene | 112 |
| 1,2,4-Trimethylbenzene | 110 |
| 1,3-Dichlorobenzene | 102 |
| 1,4-Dichlorobenzene | 100 |
| alpha-Chlorotoluene | 106 |
| 1,2-Dichlorobenzene | 104 |
| 1,2,4-Trichlorobenzene | 107 |
| Hexachlorobutadiene | 101 |
| Butane | 93 |
| Isopentane | 99 |

**Container Type: NA - Not Applicable**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| Toluene-d8 | 102 | 70-130 |
| 1,2-Dichloroethane-d4 | 95 | 70-130 |
| 4-Bromofluorobenzene | 100 | 70-130 |

eurofins | Air Toxics

**Client Sample ID: LCS**
**Lab ID#: 1301567A-20B**
**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p020603** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 2/6/13 11:03 AM** | |

| Compound | %Recovery |
|---|---|
| Freon 12 | 98 |
| Freon 114 | 98 |
| Chloromethane | 98 |
| Vinyl Chloride | 105 |
| 1,3-Butadiene | 100 |
| Bromomethane | 101 |
| Chloroethane | 102 |
| Freon 11 | 97 |
| Ethanol | 76 |
| Freon 113 | 98 |
| 1,1-Dichloroethene | 104 |
| Acetone | 99 |
| 2-Propanol | 101 |
| Carbon Disulfide | 119 |
| 3-Chloropropene | 112 |
| Methylene Chloride | 99 |
| Methyl tert-butyl ether | 102 |
| trans-1,2-Dichloroethene | 116 |
| Hexane | 104 |
| 1,1-Dichloroethane | 98 |
| 2-Butanone (Methyl Ethyl Ketone) | 99 |
| cis-1,2-Dichloroethene | 104 |
| Tetrahydrofuran | 103 |
| Chloroform | 99 |
| 1,1,1-Trichloroethane | 101 |
| Cyclohexane | 112 |
| Carbon Tetrachloride | 98 |
| 2,2,4-Trimethylpentane | 107 |
| Benzene | 103 |
| 1,2-Dichloroethane | 100 |
| Heptane | 110 |
| Trichloroethene | 85 |
| 1,2-Dichloropropane | 102 |
| 1,4-Dioxane | 109 |
| Bromodichloromethane | 98 |
| cis-1,3-Dichloropropene | 105 |
| 4-Methyl-2-pentanone | 117 |
| Toluene | 100 |
| trans-1,3-Dichloropropene | 106 |
| 1,1,2-Trichloroethane | 100 |
| Tetrachloroethene | 97 |
| 2-Hexanone | 107 |

eurofins | Air Toxics

**Client Sample ID: LCS**

**Lab ID#: 1301567A-20B**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p020603** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 2/6/13 11:03 AM** | |

| Compound | %Recovery |
|---|---|
| Dibromochloromethane | 103 |
| 1,2-Dibromoethane (EDB) | 103 |
| Chlorobenzene | 96 |
| Ethyl Benzene | 106 |
| m,p-Xylene | 111 |
| o-Xylene | 112 |
| Styrene | 118 |
| Bromoform | 101 |
| Cumene | 115 |
| 1,1,2,2-Tetrachloroethane | 113 |
| Propylbenzene | 108 |
| 4-Ethyltoluene | 107 |
| 1,3,5-Trimethylbenzene | 116 |
| 1,2,4-Trimethylbenzene | 111 |
| 1,3-Dichlorobenzene | 104 |
| 1,4-Dichlorobenzene | 103 |
| alpha-Chlorotoluene | 109 |
| 1,2-Dichlorobenzene | 106 |
| 1,2,4-Trichlorobenzene | 106 |
| Hexachlorobutadiene | 102 |
| Butane | 96 |
| Isopentane | 101 |

**Container Type: NA - Not Applicable**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| Toluene-d8 | 104 | 70-130 |
| 1,2-Dichloroethane-d4 | 98 | 70-130 |
| 4-Bromofluorobenzene | 102 | 70-130 |

eurofins | Air Toxics

**Client Sample ID: LCSD**

**Lab ID#: 1301567A-20BB**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p020604** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 2/6/13 11:25 AM** | |

| Compound | %Recovery |
|---|---|
| Freon 12 | 98 |
| Freon 114 | 100 |
| Chloromethane | 105 |
| Vinyl Chloride | 105 |
| 1,3-Butadiene | 100 |
| Bromomethane | 103 |
| Chloroethane | 99 |
| Freon 11 | 95 |
| Ethanol | 78 |
| Freon 113 | 99 |
| 1,1-Dichloroethene | 106 |
| Acetone | 100 |
| 2-Propanol | 101 |
| Carbon Disulfide | 119 |
| 3-Chloropropene | 119 |
| Methylene Chloride | 99 |
| Methyl tert-butyl ether | 101 |
| trans-1,2-Dichloroethene | 115 |
| Hexane | 104 |
| 1,1-Dichloroethane | 99 |
| 2-Butanone (Methyl Ethyl Ketone) | 102 |
| cis-1,2-Dichloroethene | 105 |
| Tetrahydrofuran | 105 |
| Chloroform | 99 |
| 1,1,1-Trichloroethane | 101 |
| Cyclohexane | 113 |
| Carbon Tetrachloride | 98 |
| 2,2,4-Trimethylpentane | 109 |
| Benzene | 104 |
| 1,2-Dichloroethane | 98 |
| Heptane | 110 |
| Trichloroethene | 85 |
| 1,2-Dichloropropane | 102 |
| 1,4-Dioxane | 110 |
| Bromodichloromethane | 97 |
| cis-1,3-Dichloropropene | 106 |
| 4-Methyl-2-pentanone | 118 |
| Toluene | 101 |
| trans-1,3-Dichloropropene | 107 |
| 1,1,2-Trichloroethane | 102 |
| Tetrachloroethene | 98 |
| 2-Hexanone | 109 |

eurofins | Air Toxics

**Client Sample ID: LCSD**

**Lab ID#: 1301567A-20BB**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p020604** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 2/6/13 11:25 AM** | |

| Compound | %Recovery |
|---|---|
| Dibromochloromethane | 103 |
| 1,2-Dibromoethane (EDB) | 103 |
| Chlorobenzene | 98 |
| Ethyl Benzene | 108 |
| m,p-Xylene | 113 |
| o-Xylene | 113 |
| Styrene | 118 |
| Bromoform | 102 |
| Cumene | 115 |
| 1,1,2,2-Tetrachloroethane | 114 |
| Propylbenzene | 110 |
| 4-Ethyltoluene | 107 |
| 1,3,5-Trimethylbenzene | 116 |
| 1,2,4-Trimethylbenzene | 112 |
| 1,3-Dichlorobenzene | 104 |
| 1,4-Dichlorobenzene | 102 |
| alpha-Chlorotoluene | 110 |
| 1,2-Dichlorobenzene | 108 |
| 1,2,4-Trichlorobenzene | 109 |
| Hexachlorobutadiene | 103 |
| Butane | 92 |
| Isopentane | 100 |

**Container Type: NA - Not Applicable**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| Toluene-d8 | 102 | 70-130 |
| 1,2-Dichloroethane-d4 | 96 | 70-130 |
| 4-Bromofluorobenzene | 100 | 70-130 |

# Shell Oil Products Chain Of Custody Record

URS

Air Toxics LTD.
**Project Name: Roxana Soil Vapor**
**Project # 21562850.04001**
Lab Vendor #

Please Check Appropriate Box: ☑ ENV. SERVICES ☐ MOTIVA RETAIL ☐ SHELL RETAIL ☐ MOTIVA SD&CH ☐ CONSULTANT ☐ LUBES ☐ SHELL PIPELINE ☐ OTHER

Print Bill To Contact Name: Robert Moosheglan
PO #:

INCIDENT # (ENV SERVICES): 9 7 2 1 8 8 4 0 ☐ CHECK IF NO INCIDENT # APPLIES
SAP #: 3 4 0 0 8 1
DATE: 01/30/13
PAGE: 1 of 2

DISPLAY COMPANY: URS CORPORATION
LAB CODE:
SITE ADDRESS: Street and City: 900 SOUTH CENTRAL AVE – ROXANA
State: IL
GLOBAL ID NO.:
ADDRESS: 1001 HIGHLANDS PLAZA DRIVE WEST - SUITE 300; ST LOUIS, MO 63110
SHIP SAMPLES TO (Name, Company, Shipping Location): Elizabeth Kunkel, URS, St. Louis
PHONE NO.: 314-743-4179
E-MAIL: Elizabeth.Kunkel@URSCorp.com
CONSULTANT PROJECT NUMBER: Roxana Soil Vapor
LABORATORY ADDRESS: Air Toxics, LTD 180 Blue Ravine Road, Suite B, Folsom, CA 95630-4719
SAMPLERS (Signature): A. Day, C. Williams, C. Kretzer, D. Mattingly, L. Rathnow, S. Jansen
TELEPHONE: 314-429-0482
FAX:
Air Contract E-Mail: Robert.Moosheglan@urs.com

TURNAROUND TIME (CALENDAR DAYS): ☑ STANDARD (14 DAY) ☐ 5 DAYS ☐ 3 DAYS ☐ 2 DAYS ☐ 24 HOURS ☐ RESULTS NEEDED ON WEEKEND
☐ LA - RWQCB REPORT FORMAT ☑ UST AGENCY:
DELIVERABLES: ☐ LEVEL 1 ☐ LEVEL 2 ☐ LEVEL 3 ☑ LEVEL 4 ☐ OTHER (SPECIFY)

☑ SHELL CONTRACT RATE APPLIES
☐ STATE REIMBURSEMENT RATE APPLIES
☐ EDD NOT NEEDED
☑ RECEIPT VERIFICATION REQUESTED

REQUESTED ANALYSIS

| LAB USE ONLY | Field Sample Identification | SAMPLING DATE | SAMPLING TIME | Canister Number | Canister Pressure/Vacuum: Initial | Final | Receipt | Final (psi) | Modified TO-15 + Butane & Isopentane | ASTM D-1946 + Helium |
|---|---|---|---|---|---|---|---|---|---|---|
| | VMP-9-5-012513 | 01/25/13 | 1403-1424 | 34611 | -30 | 10.5 | | | X | X |
| | VMP-9-11.5-012513 | 01/25/13 | 1452-1522 | 9401 | -30 | -4.5 | | | X | X |
| | VMP-9-11.5-012513-DUP | 01/25/13 | 1452 1522 | 1006 | -30 | 7.5 | | | X | X |
| | VMP-9-25.5-013013 | 01/30/13 | 1000-1030 | 2117 | -28.5 | -9.5 | | | X | X |
| | VMP-9-38.5-013013 | 01/30/13 | 1045-1115 | 34666 | -30 | -10.5 | | | X | X |
| | VMP-10-5-012913 | 01/29/13 | 915-945 | 37702 | -29.5 | -8.5 | | | X | X |
| | VMP-10-5-012913-DUP | 01/29/13 | 915-945 | 1740 | -29.5 | -10.5 | | | X | X |
| | VMP-10-20-012913 | 01/29/13 | 1112-1142 | 9445 | -29 | -7.5 | | | X | X |
| | VMP-10-30-012913 | 01/29/13 | 1342-1412 | 37769 | -28.5 | -10 | | | X | X |
| | | | 1/30/13 | | | | | | X | X |

Turn Around Time: ☑ Normal ☐ Rush ☐ Specify

Lab Use Only
Pressurized by:
Date:
Pressurization Gas: $N_2$ He

ADDITIONAL NOTES:
- 14 day hold time
- Report results between MDL and RL
- Level IV ECVP

| Relinquished by: (Signature) | Received by: (Signature) | Date | Time |
|---|---|---|---|
| | FEDEX | 1/30/13 | 1800 |
| | 1/31/13 0945 | | |
| | | | |

Custody Seal Intact?
Y N None Temp

1301507

# Shell Oil Products Chain Of Custody Record

URS

Air Toxics LTD.
Project Name: Roxana Soil Vapor
Project # 21562850.04001
Lab Vendor #

Please Check Appropriate Box:
☑ ENV. SERVICES ☐ MOTIVA RETAIL ☐ SHELL RETAIL
☐ MOTIVA SOMOA ☐ CONSULTANT ☐ LUBES
☐ SHELL PIPELINE ☐ OTHER

Print Bill To Contact Name: Robert Mooshegian
PO #:
INCIDENT # (ENV SERVICES): 9 7 2 1 6 6 4 0
SAP #: 3 4 0 0 6 1
☐ CHECK IF NO INCIDENT # APPLIES
DATE: 01/30/13
PAGE: 2 of 2

URS CORPORATION
1001 HIGHLANDS PLAZA DRIVE WEST - SUITE 300; ST. LOUIS, MO 63110
Air Toxics, LTD 180 Blue Ravine Road, Suite B, Folsom, CA 95630-4719
314-429-0462
Robert.Mooshegian@urs.com

SITE ADDRESS: Street and City: 900 SOUTH CENTRAL AVE – ROXANA
STATE: IL
GLOBAL ID NO.:
EDF DELIVERABLE TO (Name, Company, Office Location): Elizabeth Kunkel, URS, St. Louis
PHONE NO.: 314-743-4179
EMAIL: Elizabeth_Kunkel@URSCorp.com
CONSULTANT PROJECT NAME: Roxana Soil Vapor
A. Dey, C. Williams, C. Kretzer, D. Mattingly L. Rathnow, S. Jansen

TURNAROUND TIME (CALENDAR DAYS):
☑ STANDARD (14 DAY) ☐ 5 DAYS ☐ 3 DAYS ☐ 2 DAYS ☐ 24 HOURS ☐ RESULTS NEEDED ON WEEKEND

☐ LA - RWQCB REPORT FORMAT ☑ UST AGENCY:

DELIVERABLES: ☐ LEVEL 1 ☐ LEVEL 2 ☐ LEVEL 3 ☑ LEVEL 4 ☐ OTHER (SPECIFY)

☑ SHELL CONTRACT RATE APPLIES
☐ STATE REIMBURSEMENT RATE APPLIES
☐ EDD NOT NEEDED
☑ RECEIPT VERIFICATION REQUESTED

REQUESTED ANALYSIS

| Lab Use Only | Field Sample Identification | SAMPLING DATE | SAMPLING TIME | Canister Number | Canister Pressure/Vacuum Initial | Final | Receipt | Final (psi) | Modified TO-15 + Butane & Isopentane | ASTM D-1946 + Helium |
|---|---|---|---|---|---|---|---|---|---|---|
| | VMP-11-5-012913 | 01/29/13 | 1318-1348 | 37354 | -29 | -9 | | | X | X |
| | VMP-11-8-012913 | 01/29/13 | 1432-1432 | 2170 | -29 | -9.5 | | | X | X |
| | VMP-11-29-012913 | 01/29/13 | 1442-1512 | 3042 | -26.5 | -8.5 | | | X | X |
| | VMP-11-38-013013 | 01/30/13 | 1200-1220 | 36550 | -30 | -10 | | | X | X |
| | VMP-13-5-012913 | 01/29/13 | 1457-1527 | 34068 | -29.5 | -10 | | | X | X |
| | VMP-41-10-012913 | 01/29/13 | 850-920 | 13689 | -28.5 | -9.5 | | | X | X |
| | VMP-41-20-012913 | 01/29/13 | 951-1021 | 36415 | -29 | -10 | | | X | X |
| | VMP-41-30-012913 | 01/29/13 | 1044-1114 | 34088 | -28.5 | -8.5 | | | X | X |
| | | | | | | | | | X | X |
| | | | | | | | | | X | X |

Turn Around Time: ☑ Normal ☐ Rush ☐ Specify

Lab Use Only
Pressurized by:
Date:
Pressurization Gas: $N_2$ He

ADDITIONAL NOTES:
- 14 day hold time
- Report results between MDL and RL
- Level IV ECVP

Relinquished by: (Signature) — Received by: (Signature) FEDEX — Date: 1/30/13 — Time: 1800

Relinquished by: (Signature) — Received by: (Signature) AR 1/31/13 0945

Relinquished by: (Signature) — Received by: (Signature)

Custody Seal Intact? Y N None Temp N/A FedEx

130156

06/2008 Revision

eurofins | Air Toxics

2/21/2013
Ms. Elizabeth Kunkel
URS Corporation
1001 Highlands Plaza Dr. West
Suite 300
St. Louis MO 63110

Project Name: Roxana Soil Vapor
Project #: 21562850.04001
Workorder #: 1301567B

Dear Ms. Elizabeth Kunkel

The following report includes the data for the above referenced project for sample(s) received on 1/31/2013 at Air Toxics Ltd.

The data and associated QC analyzed by Modified ASTM D-1946 are compliant with the project requirements or laboratory criteria with the exception of the deviations noted in the attached case narrative.

Thank you for choosing Air Toxics Ltd. for your air analysis needs. Air Toxics Ltd. is committed to providing accurate data of the highest quality. Please feel free to contact the Project Manager: Kelly Buettner at 916-985-1000 if you have any questions regarding the data in this report.

Regards,

Kelly Buettner
Project Manager

REVIEWED
BY
3/20/13

eurofins | Air Toxics

# WORK ORDER #: 1301567B

Work Order Summary

| | | | |
|---|---|---|---|
| **CLIENT:** | Ms. Elizabeth Kunkel<br>URS Corporation<br>1001 Highlands Plaza Dr. West<br>Suite 300<br>St. Louis, MO 63110 | **BILL TO:** | Accounts Payable Austin<br>URS Corporation<br>P.O. BOX 203970<br>Austin, TX 78720-1088 |
| **PHONE:** | 314-743-4179 | **P.O. #** | 21562735.00013 |
| **FAX:** | | **PROJECT #** | 21562850.04001 Roxana Soil Vapor |
| **DATE RECEIVED:** | 01/31/2013 | **CONTACT:** | Kelly Buettner |
| **DATE COMPLETED:** | 02/13/2013 | | |

| FRACTION # | NAME | TEST | RECEIPT VAC./PRES. | FINAL PRESSURE |
|---|---|---|---|---|
| 01A | VMP-9-5-012513 | Modified ASTM D-1946 | 8.5 "Hg | 15 psi |
| 02A | VMP-9-11.5-012513 | Modified ASTM D-1946 | 4.0 "Hg | 15 psi |
| 03A | VMP-9-11.5-012513-DUP | Modified ASTM D-1946 | 6.0 "Hg | 15 psi |
| 04A | VMP-9-25.5-013013 | Modified ASTM D-1946 | 8.5 "Hg | 15 psi |
| 05A | VMP-9-38.5-013013 | Modified ASTM D-1946 | 8.5 "Hg | 15 psi |
| 06A | VMP-10-5-012913 | Modified ASTM D-1946 | 8.5 "Hg | 15 psi |
| 07A | VMP-10-5-012913-DUP | Modified ASTM D-1946 | 10.5 "Hg | 15 psi |
| 08A | VMP-10-20-012913 | Modified ASTM D-1946 | 8.0 "Hg | 15 psi |
| 09A | VMP-10-30-012913 | Modified ASTM D-1946 | 10.0 "Hg | 15 psi |
| 10A | VMP-11-5-012913 | Modified ASTM D-1946 | 9.0 "Hg | 15 psi |
| 11A | VMP-11-8-012913 | Modified ASTM D-1946 | 9.5 "Hg | 15 psi |
| 12A | VMP-11-29-012913 | Modified ASTM D-1946 | 9.0 "Hg | 15 psi |
| 13A | VMP-11-38-013013 | Modified ASTM D-1946 | 8.0 "Hg | 15 psi |
| 14A | VMP-13-5-012913 | Modified ASTM D-1946 | 10.5 "Hg | 15 psi |
| 15A | VMP-41-10-012913 | Modified ASTM D-1946 | 9.5 "Hg | 15 psi |
| 16A | VMP-41-20-012913 | Modified ASTM D-1946 | 10.0 "Hg | 15 psi |
| 17A | VMP-41-30-012913 | Modified ASTM D-1946 | 8.5 "Hg | 15 psi |
| 18A | Lab Blank | Modified ASTM D-1946 | NA | NA |
| 18B | Lab Blank | Modified ASTM D-1946 | NA | NA |
| 19A | LCS | Modified ASTM D-1946 | NA | NA |
| 19AA | LCSD | Modified ASTM D-1946 | NA | NA |

CERTIFIED BY: Heidi Rayos DATE: 02/21/13

Technical Director

Certification numbers: AZ Licensure AZ0775, CA NELAP - 12282CA, NY NELAP - 11291,
TX NELAP - T104704434-12-4, UT NELAP CA009332012-3, WA NELAP - C935
Name of Accrediting Agency: NELAP/ORELAP (Oregon Environmental Laboratory Accreditation Program)
Accreditation number: CA300005, Effective date: 10/18/2012, Expiration date: 10/17/2013.
Eurofins Air Toxics Ltd. certifies that the test results contained in this report meet all requirements of the NELAC standards

This report shall not be reproduced, except in full, without the written approval of Eurofins Air Toxics, Inc.

180 BLUE RAVINE ROAD, SUITE B FOLSOM, CA - 9563
(916) 985-1000 . (800) 985-5955 . FAX (916) 985-1020

**LABORATORY NARRATIVE**
**Modified ASTM D-1946**
**URS Corporation**
**Workorder# 1301567B**

Seventeen 1 Liter Summa Canister samples were received on January 31, 2013. The laboratory performed analysis via Modified ASTM Method D-1946 for Methane and fixed gases in air using GC/FID or GC/TCD. The method involves direct injection of 1.0 mL of sample.

On the analytical column employed for this analysis, Oxygen coelutes with Argon. The corresponding peak is quantitated as Oxygen.

Since Nitrogen is used to pressurize samples, the reported Nitrogen values are calculated by adding all the sample components and subtracting from 100%.

Method modifications taken to run these samples are summarized in the table below. Specific project requirements may over-ride the ATL modifications.

| *Requirement* | *ASTM D-1946* | *ATL Modifications* |
|---|---|---|
| Calibration | A single point calibration is performed using a reference standard closely matching the composition of the unknown. | A 3-point calibration curve is performed. Quantitation is based on a daily calibration standard which may or may not resemble the composition of the associated samples. |
| Reference Standard | The composition of any reference standard must be known to within 0.01 mol % for any component. | The standards used by ATL are blended to a >/= 95% accuracy. |
| Sample Injection Volume | Components whose concentrations are in excess of 5 % should not be analyzed by using sample volumes greater than 0.5 mL. | The sample container is connected directly to a fixed volume sample loop of 1.0 mL on the GC. Linear range is defined by the calibration curve. Bags are loaded by vacuum. |
| Normalization | Normalize the mole pereent values by multiplying each value by 100 and dividing by the sum of the original values. The sum of the original values should not differ from 100% by more than 1.0%. | Results are not normalized. The sum of the reported values can differ from 100% by as much as 15%, either due to analytical variability or an unusual sample matrix. |
| Precision | Precision requirements established at each concentration level. | Duplicates should agree within 25% RPD for detections > 5 X's the RL. |

**Receiving Notes**

There were no receiving discrepancies.

**Analytical Notes**

As per project specific client request the laboratory has reported estimated values for target compound hits that are below the Reporting Limit but greater than the Method Detection Limit. Concentrations that are below the level at which the canister was certified may be false positives.

The reporting limit for Carbon Monoxide was raised from 0.01% to 0.05%.

The Summa Canister for sample VMP-9-5-012513 was found to be leaking prior to ASTM D-1946 analysis. Analyte concentrations are reported as qualified.

**Definition of Data Qualifying Flags**

Seven qualifiers may have been used on the data analysis sheets and indicate as follows:
B - Compound present in laboratory blank greater than reporting limit.
J - Estimated value.
E - Exceeds instrument calibration range.
S - Saturated peak.
Q - Exceeds quality control limits.
U - Compound analyzed for but not detected above the detection limit.
M - Reported value may be biased due to apparent matrix interferences.
File extensions may have been used on the data analysis sheets and indicates as follows:
a-File was requantified
b-File was quantified by a second column and detector
r1-File was requantified for the purpose of reissue

eurofins | Air Toxics

# Summary of Detected Compounds
# NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1946

**Client Sample ID: VMP-9-5-012513**

**Lab ID#: 1301567B-01A**

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.42 | 34 J |
| Nitrogen | 0.42 | 66 J |
| Methane | 0.00042 | 0.00029 J |
| Carbon Dioxide | 0.042 | 0.16 J |
| Ethane | 0.0042 | 0.00013 J |
| Helium | 0.21 | 0.28 J |

**Client Sample ID: VMP-9-11.5-012513**

**Lab ID#: 1301567B-02A**

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.23 | 20 |
| Nitrogen | 0.23 | 80 |
| Methane | 0.00023 | 0.000037 J |
| Carbon Dioxide | 0.023 | 0.30 |

**Client Sample ID: VMP-9-11.5-012513-DUP**

**Lab ID#: 1301567B-03A**

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.25 | 20 |
| Nitrogen | 0.25 | 80 |
| Methane | 0.00025 | 0.000060 J |
| Carbon Dioxide | 0.025 | 0.31 |
| Helium | 0.13 | 0.027 J |

**Client Sample ID: VMP-9-25.5-013013**

**Lab ID#: 1301567B-04A**

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.28 | 20 |
| Nitrogen | 0.28 | 79 |

# Summary of Detected Compounds
# NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1946

**Client Sample ID: VMP-9-25.5-013013**

**Lab ID#: 1301567B-04A**

| | | |
|---|---|---|
| Carbon Dioxide | 0.028 | 1.3 |
| Ethane | 0.0028 | 0.000062 J |

**Client Sample ID: VMP-9-38.5-013013**

**Lab ID#: 1301567B-05A**

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.28 | 15 |
| Nitrogen | 0.28 | 79 |
| Methane | 0.00028 | 0.00013 J |
| Carbon Dioxide | 0.028 | 5.9 |
| Ethane | 0.0028 | 0.000066 J |

**Client Sample ID: VMP-10-5-012913**

**Lab ID#: 1301567B-06A**

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.28 | 21 |
| Nitrogen | 0.28 | 79 |
| Methane | 0.00028 | 0.00010 J |
| Carbon Dioxide | 0.028 | 0.11 |
| Helium | 0.14 | 0.10 J |

**Client Sample ID: VMP-10-5-012913-DUP**

**Lab ID#: 1301567B-07A**

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.31 | 20 |
| Nitrogen | 0.31 | 80 |
| Methane | 0.00031 | 0.00010 J |
| Carbon Dioxide | 0.031 | 0.10 |

**Client Sample ID: VMP-10-20-012913**

**Lab ID#: 1301567B-08A**

eurofins | Air Toxics

# Summary of Detected Compounds
# NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1946

**Client Sample ID: VMP-10-20-012913**

**Lab ID#: 1301567B-08A**

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.58 | 21 |
| Nitrogen | 0.58 | 78 |
| Carbon Dioxide | 0.058 | 0.45 |

**Client Sample ID: VMP-10-30-012913**

**Lab ID#: 1301567B-09A**

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.30 | 19 |
| Nitrogen | 0.30 | 79 |
| Methane | 0.00030 | 0.000055 J |
| Carbon Dioxide | 0.030 | 2.2 |

**Client Sample ID: VMP-11-5-012913**

**Lab ID#: 1301567B-10A**

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.58 | 22 |
| Nitrogen | 0.58 | 77 |
| Methane | 0.00058 | 0.000098 J |
| Carbon Dioxide | 0.058 | 0.47 |
| Ethane | 0.0058 | 0.00016 J |
| Helium | 0.29 | 0.74 |

**Client Sample ID: VMP-11-8-012913**

**Lab ID#: 1301567B-11A**

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.30 | 19 |
| Nitrogen | 0.30 | 80 |
| Methane | 0.00030 | 0.000049 J |
| Carbon Dioxide | 0.030 | 1.1 |

eurofins | Air Toxics

# Summary of Detected Compounds
# NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1946

**Client Sample ID: VMP-11-8-012913**

**Lab ID#: 1301567B-11A**

| | | |
|---|---|---|
| Ethane | 0.0030 | 0.000092 J |

**Client Sample ID: VMP-11-29-012913**

**Lab ID#: 1301567B-12A**

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.29 | 19 |
| Nitrogen | 0.29 | 78 |
| Methane | 0.00029 | 0.000079 J |
| Carbon Dioxide | 0.029 | 2.8 |
| Ethane | 0.0029 | 0.00010 J |
| Helium | 0.14 | 0.071 J |

**Client Sample ID: VMP-11-38-013013**

**Lab ID#: 1301567B-13A**

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.28 | 14 |
| Nitrogen | 0.28 | 78 |
| Methane | 0.00028 | 0.0011 |
| Carbon Dioxide | 0.028 | 8.2 |
| Ethane | 0.0028 | 0.000083 J |
| Helium | 0.14 | 0.060 J |

**Client Sample ID: VMP-13-5-012913**

**Lab ID#: 1301567B-14A**

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.31 | 21 |
| Nitrogen | 0.31 | 79 |
| Methane | 0.00031 | 0.000061 J |
| Carbon Dioxide | 0.031 | 0.24 |
| Helium | 0.16 | 0.091 J |

eurofins | Air Toxics

# Summary of Detected Compounds
# NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1946

**Client Sample ID: VMP-41-10-012913**

**Lab ID#: 1301567B-15A**

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.30 | 21 |
| Nitrogen | 0.30 | 78 |
| Methane | 0.00030 | 0.000038 J |
| Carbon Dioxide | 0.030 | 0.41 |

**Client Sample ID: VMP-41-20-012913**

**Lab ID#: 1301567B-16A**

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.30 | 20 |
| Nitrogen | 0.30 | 79 |
| Methane | 0.00030 | 0.000032 J |
| Carbon Dioxide | 0.030 | 0.88 |

**Client Sample ID: VMP-41-30-012913**

**Lab ID#: 1301567B-17A**

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.57 | 22 |
| Nitrogen | 0.57 | 76 |
| Carbon Dioxide | 0.057 | 1.9 |

eurofins | Air Toxics

**Client Sample ID: VMP-9-5-012513**

**Lab ID#: 1301567B-01A**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1946**

| | | | |
|---|---|---|---|
| **File Name:** | **9020731** | **Date of Collection:** | **1/25/13 2:34:00 PM** |
| **Dil. Factor:** | **4.24** | **Date of Analysis:** | **2/8/13 08:11 AM** |

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.42 | 34 J |
| Nitrogen | 0.42 | 66 J |
| Carbon Monoxide | 0.21 | Not Detected |
| Methane | 0.00042 | 0.00029 J |
| Carbon Dioxide | 0.042 | 0.16 J |
| Ethane | 0.0042 | 0.00013 J |
| Ethene | 0.0042 | Not Detected |
| Helium | 0.21 | 0.28 J |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

eurofins | Air Toxics

**Client Sample ID: VMP-9-11.5-012513**

**Lab ID#: 1301567B-02A**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1946**

| | | | |
|---|---|---|---|
| **File Name:** | **9020711** | **Date of Collection:** | **1/25/13 3:22:00 PM** |
| **Dil. Factor:** | **2.33** | **Date of Analysis:** | **2/7/13 02:08 PM** |

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.23 | 20 |
| Nitrogen | 0.23 | 80 |
| Carbon Monoxide | 0.12 | Not Detected |
| Methane | 0.00023 | 0.000037 J |
| Carbon Dioxide | 0.023 | 0.30 |
| Ethane | 0.0023 | Not Detected |
| Ethene | 0.0023 | Not Detected |
| Helium | 0.12 | Not Detected |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

eurofins | Air Toxics

**Client Sample ID: VMP-9-11.5-012513-DUP**

**Lab ID#: 1301567B-03A**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1946**

| | | | |
|---|---|---|---|
| **File Name:** | **9020712** | **Date of Collection:** | **1/25/13 3:22:00 PM** |
| **Dil. Factor:** | **2.52** | **Date of Analysis:** | **2/7/13 02:31 PM** |

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.25 | 20 |
| Nitrogen | 0.25 | 80 |
| Carbon Monoxide | 0.13 | Not Detected |
| Methane | 0.00025 | 0.000060 J |
| Carbon Dioxide | 0.025 | 0.31 |
| Ethane | 0.0025 | Not Detected |
| Ethene | 0.0025 | Not Detected |
| Helium | 0.13 | 0.027 J |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

eurofins | Air Toxics

**Client Sample ID: VMP-9-25.5-013013**

**Lab ID#: 1301567B-04A**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1946**

| | | | |
|---|---|---|---|
| **File Name:** | **9020713** | **Date of Collection:** | **1/30/13 10:30:00 AM** |
| **Dil. Factor:** | **2.82** | **Date of Analysis:** | **2/7/13 03:01 PM** |

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.28 | 20 |
| Nitrogen | 0.28 | 79 |
| Carbon Monoxide | 0.14 | Not Detected |
| Methane | 0.00028 | Not Detected |
| Carbon Dioxide | 0.028 | 1.3 |
| Ethane | 0.0028 | 0.000062 J |
| Ethene | 0.0028 | Not Detected |
| Helium | 0.14 | Not Detected |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

eurofins | Air Toxics

**Client Sample ID: VMP-9-38.5-013013**

**Lab ID#: 1301567B-05A**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1946**

| | | | |
|---|---|---|---|
| **File Name:** | **9020714** | **Date of Collection:** | **1/30/13 11:15:00 AM** |
| **Dil. Factor:** | **2.82** | **Date of Analysis:** | **2/7/13 03:40 PM** |

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.28 | 15 |
| Nitrogen | 0.28 | 79 |
| Carbon Monoxide | 0.14 | Not Detected |
| Methane | 0.00028 | 0.00013 J |
| Carbon Dioxide | 0.028 | 5.9 |
| Ethane | 0.0028 | 0.000066 J |
| Ethene | 0.0028 | Not Detected |
| Helium | 0.14 | Not Detected |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

eurofins | Air Toxics

**Client Sample ID: VMP-10-5-012913**

**Lab ID#: 1301567B-06A**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1946**

| | | | |
|---|---|---|---|
| **File Name:** | **9020715** | **Date of Collection:** | **1/29/13 9:46:00 AM** |
| **Dil. Factor:** | **2.82** | **Date of Analysis:** | **2/7/13 04:00 PM** |

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.28 | 21 |
| Nitrogen | 0.28 | 79 |
| Carbon Monoxide | 0.14 | Not Detected |
| Methane | 0.00028 | 0.00010 J |
| Carbon Dioxide | 0.028 | 0.11 |
| Ethane | 0.0028 | Not Detected |
| Ethene | 0.0028 | Not Detected |
| Helium | 0.14 | 0.10 J |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

eurofins | Air Toxics

**Client Sample ID: VMP-10-5-012913-DUP**

**Lab ID#: 1301567B-07A**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1946**

| | | | |
|---|---|---|---|
| **File Name:** | **9020716** | **Date of Collection:** | **1/29/13 9:46:00 AM** |
| **Dil. Factor:** | **3.11** | **Date of Analysis:** | **2/7/13 04:22 PM** |

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.31 | 20 |
| Nitrogen | 0.31 | 80 |
| Carbon Monoxide | 0.16 | Not Detected |
| Methane | 0.00031 | 0.00010 J |
| Carbon Dioxide | 0.031 | 0.10 |
| Ethane | 0.0031 | Not Detected |
| Ethene | 0.0031 | Not Detected |
| Helium | 0.16 | Not Detected |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

eurofins | Air Toxics

**Client Sample ID: VMP-10-20-012913**

**Lab ID#: 1301567B-08A**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1946**

| | | | |
|---|---|---|---|
| **File Name:** | **9020719** | **Date of Collection:** | **1/29/13 11:42:00 AM** |
| **Dil. Factor:** | **5.77** | **Date of Analysis:** | **2/7/13 06:38 PM** |

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.58 | 21 |
| Nitrogen | 0.58 | 78 |
| Carbon Monoxide | 0.29 | Not Detected |
| Methane | 0.00058 | Not Detected |
| Carbon Dioxide | 0.058 | 0.45 |
| Ethane | 0.0058 | Not Detected |
| Ethene | 0.0058 | Not Detected |
| Helium | 0.29 | Not Detected |

**Container Type: 1 Liter Summa Canister**

eurofins | Air Toxics

**Client Sample ID: VMP-10-30-012913**

**Lab ID#: 1301567B-09A**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1946**

| | | | |
|---|---|---|---|
| **File Name:** | **9020718** | **Date of Collection:** | **1/29/13 2:12:00 PM** |
| **Dil. Factor:** | **3.03** | **Date of Analysis:** | **2/7/13 06:16 PM** |

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.30 | 19 |
| Nitrogen | 0.30 | 79 |
| Carbon Monoxide | 0.15 | Not Detected |
| Methane | 0.00030 | 0.000055 J |
| Carbon Dioxide | 0.030 | 2.2 |
| Ethane | 0.0030 | Not Detected |
| Ethene | 0.0030 | Not Detected |
| Helium | 0.15 | Not Detected |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

eurofins | Air Toxics

**Client Sample ID: VMP-11-5-012913**

**Lab ID#: 1301567B-10A**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1946**

| | | | |
|---|---|---|---|
| **File Name:** | **9020726** | **Date of Collection:** | **1/29/13 1:45:00 PM** |
| **Dil. Factor:** | **5.84** | **Date of Analysis:** | **2/7/13 10:16 PM** |

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.58 | 22 |
| Nitrogen | 0.58 | 77 |
| Carbon Monoxide | 0.29 | Not Detected |
| Methane | 0.00058 | 0.000098 J |
| Carbon Dioxide | 0.058 | 0.47 |
| Ethane | 0.0058 | 0.00016 J |
| Ethene | 0.0058 | Not Detected |
| Helium | 0.29 | 0.74 |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

eurofins | Air Toxics

**Client Sample ID: VMP-11-8-012913**

**Lab ID#: 1301567B-11A**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1946**

| | | | |
|---|---|---|---|
| **File Name:** | **9020720** | **Date of Collection:** | **1/29/13 2:32:00 PM** |
| **Dil. Factor:** | **2.96** | **Date of Analysis:** | **2/7/13 07:12 PM** |

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.30 | 19 |
| Nitrogen | 0.30 | 80 |
| Carbon Monoxide | 0.15 | Not Detected |
| Methane | 0.00030 | 0.000049 J |
| Carbon Dioxide | 0.030 | 1.1 |
| Ethane | 0.0030 | 0.000092 J |
| Ethene | 0.0030 | Not Detected |
| Helium | 0.15 | Not Detected |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

eurofins | Air Toxics

**Client Sample ID: VMP-11-29-012913**

**Lab ID#: 1301567B-12A**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1946**

| | | | |
|---|---|---|---|
| **File Nama:** | **9020721** | **Date of Collection:** | **1/29/13 3:12:00 PM** |
| **Dil. Factor:** | **2.89** | **Date of Analysis:** | **2/7/13 08:12 PM** |

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.29 | 19 |
| Nitrogen | 0.29 | 78 |
| Carbon Monoxide | 0.14 | Not Detected |
| Methane | 0.00029 | 0.000079 J |
| Carbon Dioxide | 0.029 | 2.8 |
| Ethane | 0.0029 | 0.00010 J |
| Ethene | 0.0029 | Not Detected |
| Helium | 0.14 | 0.071 J |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

eurofins | Air Toxics

**Client Sample ID: VMP-11-38-013013**

**Lab ID#: 1301567B-13A**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1946**

| | | | |
|---|---|---|---|
| **File Name:** | **9020722** | **Date of Collection:** | **1/30/13 12:30:00 PM** |
| **Dil. Factor:** | **2.76** | **Date of Analysis:** | **2/7/13 08:43 PM** |

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.28 | 14 |
| Nitrogen | 0.28 | 78 |
| Carbon Monoxide | 0.14 | Not Detected |
| Methane | 0.00028 | 0.0011 |
| Carbon Dioxide | 0.028 | 8.2 |
| Ethane | 0.0028 | 0.000083 J |
| Ethene | 0.0028 | Not Detected |
| Helium | 0.14 | 0.060 J |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

eurofins | Air Toxics

**Client Sample ID: VMP-13-5-012913**

**Lab ID#: 1301567B-14A**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1946**

| | | | |
|---|---|---|---|
| **File Name:** | **9020723** | **Date of Collection:** | **1/29/13 3:27:00 PM** |
| **Dil. Factor:** | **3.11** | **Date of Analysis:** | **2/7/13 09:05 PM** |

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.31 | 21 |
| Nitrogen | 0.31 | 79 |
| Carbon Monoxide | 0.16 | Not Detected |
| Methane | 0.00031 | 0.000061 J |
| Carbon Dioxide | 0.031 | 0.24 |
| Ethane | 0.0031 | Not Detected |
| Ethene | 0.0031 | Not Detected |
| Helium | 0.16 | 0.091 J |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

eurofins | Air Toxics

**Client Sample ID: VMP-41-10-012913**

**Lab ID#: 1301567B-15A**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1946**

| | | | |
|---|---|---|---|
| **File Name:** | **9020724** | **Date of Collection:** | **1/29/13 9:29:00 AM** |
| **Dil. Factor:** | **2.96** | **Date of Analysis:** | **2/7/13 09:26 PM** |

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.30 | 21 |
| Nitrogen | 0.30 | 78 |
| Carbon Monoxide | 0.15 | Not Detected |
| Methane | 0.00030 | 0.000038 J |
| Carbon Dioxide | 0.030 | 0.41 |
| Ethane | 0.0030 | Not Detected |
| Ethene | 0.0030 | Not Detected |
| Helium | 0.15 | Not Detected |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

eurofins | Air Toxics

**Client Sample ID: VMP-41-20-012913**

**Lab ID#: 1301567B-16A**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1946**

| | | | |
|---|---|---|---|
| **File Name:** | **9020725** | **Date of Collection:** | **1/29/13 10:21:00 AM** |
| **Dil. Factor:** | **3.03** | **Date of Analysis:** | **2/7/13 09:48 PM** |

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.30 | 20 |
| Nitrogen | 0.30 | 79 |
| Carbon Monoxide | 0.15 | Not Detected |
| Methane | 0.00030 | 0.000032 J |
| Carbon Dioxide | 0.030 | 0.88 |
| Ethane | 0.0030 | Not Detected |
| Ethene | 0.0030 | Not Detected |
| Helium | 0.15 | Not Detected |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

eurofins | Air Toxics

**Client Sample ID: VMP-41-30-012913**

**Lab ID#: 1301567B-17A**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1946**

| | | | |
|---|---|---|---|
| **File Name:** | **9020727** | **Date of Collection:** | **1/29/13 11:14:00 AM** |
| **Dil. Factor:** | **5.70** | **Date of Analysis:** | **2/7/13 10:38 PM** |

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.57 | 22 |
| Nitrogen | 0.57 | 76 |
| Carbon Monoxide | 0.28 | Not Detected |
| Methane | 0.00057 | Not Detected |
| Carbon Dioxide | 0.057 | 1.9 |
| Ethane | 0.0057 | Not Detected |
| Ethene | 0.0057 | Not Detected |
| Helium | 0.28 | Not Detected |

**Container Type: 1 Liter Summa Canister**

eurofins | Air Toxics

**Client Sample ID: Lab Blank**

**Lab ID#: 1301567B-18A**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1946**

| | | | |
|---|---|---|---|
| **File Name:** | **9020708a** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 2/7/13 12:17 PM** | |

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.10 | Not Detected |
| Nitrogen | 0.10 | 0.089 J |
| Carbon Monoxide | 0.050 | Not Detected |
| Methane | 0.00010 | Not Detected |
| Carbon Dioxide | 0.010 | Not Detected |
| Ethane | 0.0010 | Not Detected |
| Ethene | 0.0010 | Not Detected |

J = Estimated value.

**Container Type: NA - Not Applicable**

eurofins | Air Toxics

**Client Sample ID: Lab Blank**

**Lab ID#: 1301567B-18B**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1946**

| | | | |
|---|---|---|---|
| **File Name:** | **9020707b** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 2/7/13 11:55 AM** | |

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Helium | 0.050 | Not Detected |

**Container Type: NA - Not Applicable**

eurofins | Air Toxics

**Client Sample ID: LCS**

**Lab ID#: 1301567B-19A**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1946**

| | | | |
|---|---|---|---|
| **File Name:** | **9020706** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 2/7/13 11:23 AM** | |

| Compound | %Recovery |
|---|---|
| Oxygen | 99 |
| Nitrogen | 100 |
| Carbon Monoxide | 97 |
| Methane | 98 |
| Carbon Dioxide | 101 |
| Ethane | 100 |
| Ethene | 97 |
| Helium | 100 |

**Container Type: NA - Not Applicable**

eurofins | Air Toxics

**Client Sample ID: LCSD**

**Lab ID#: 1301567B-19AA**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1946**

| | | | |
|---|---|---|---|
| **File Name:** | **9020733** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 2/8/13 09:02 AM** | |

| Compound | %Recovery |
|---|---|
| Oxygen | 98 |
| Nitrogen | 100 |
| Carbon Monoxide | 103 |
| Methane | 99 |
| Carbon Dioxide | 100 |
| Ethane | 100 |
| Ethene | 98 |
| Helium | 100 |

**Container Type: NA - Not Applicable**

# Shell Oil Products Chain Of Custody Record

URS

Air Toxics LTD.
**Project Name: Roxana Soil Vapor**
**Project # 21562850.04001**
Lab Vendor #

Please Check Appropriate Box: ☑ BMV. SERVICES ☐ MOTIVA RETAIL ☐ SHELL RETAIL ☐ MOTIVA SC&CH ☐ CONSULTANT ☐ LUBES ☐ SHELL PIPELINE ☐ OTHER

Print Bill To Contact Name: Robert Moosheglan

INCIDENT # (ENV SERVICES): 9 7 2 1 6 6 4 0 ☐ CHECK IF NO INCIDENT # APPLIES

DATE: 01/30/13

PAGE: 1 of 2

PO #:

SAP #: 3 4 0 0 8 1

URS CORPORATION

1001 HIGHLANDS PLAZA DRIVE WEST - SUITE 300; ST LOUIS, MO 63110

Air Toxics, LTD 180 Blue Ravine Road, Suite B, Folsom, CA 95630-4719

314-429-0462

Robert.Moosheglan@urs.com

000 SOUTH CENTRAL AVE -- ROXANA

IL

Elizabeth Kunkel, URS, St. Louis | 314-743-4179 | Elizabeth_Kunkel@URSCorp.com | Roxana Soil Vapor

A. Day, C. Williams, C. Kretzer, D. Mattingly, L. Rathnow, S. Jansen

TURNAROUND TIME (CALENDAR DAYS): ☑ STANDARD (14 DAY) ☐ 5 DAYS ☐ 3 DAYS ☐ 2 DAYS ☐ 24 HOURS ☐ RESULTS NEEDED ON WEEKEND

REQUESTED ANALYSIS

☐ LA - RWQCB REPORT FORMAT ☑ UST AGENCY:

DELIVERABLES: ☐ LEVEL 1 ☐ LEVEL 2 ☐ LEVEL 3 ☑ LEVEL 4 ☐ OTHER (SPECIFY)

☑ SHELL CONTRACT RATE APPLIES
☐ STATE REIMBURSEMENT RATE APPLIES
☐ DO NOT RESEND
☑ RECEIPT VERIFICATION REQUESTED

Turn Around Time: ☑ Normal ☐ Rush ☐ Specify

Lab Use Only
Pressurized by:
Date:
Pressurization Gas: $N_2$ He

| Lab Use Only | Field Sample Identification | SAMPLING DATE | SAMPLING TIME | Canister Number | Canister Pressure/Vacuum Initial | Final | Receipt | Final (psi) | Modified TO-15 + Butane & Isopentane | ASTM D-1946 + Helium | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | VMP-9-5-012513 | 01/25/13 | 1403-1434 | 34611 | -30 | -10.5 | | | X | X | | | | | |
| | VMP-9-11.5-012513 | 01/25/13 | 1452-1522 | 9461 | -30 | -4.5 | | | X | X | | | | | |
| | VMP-9-11.5-012513-DUP | 01/25/13 | 1452-1522 | 1006 | -30 | 7.5 | | | X | X | | | | | |
| | VMP-9-25.5-013013 | 01/30/13 | 1000-1030 | 2117 | -28.5 | -9.5 | | | X | X | | | | | |
| | VMP-9-38.5-013013 | 01/30/13 | 1045-1115 | 34095 | -30 | -10.5 | | | X | X | | | | | |
| | VMP-10-5-012913 | 01/29/13 | 915-946 | 37702 | -29.5 | -8.5 | | | X | X | | | | | |
| | VMP-10-5-012913-DUP | 01/29/13 | 915-946 | 1748 | -29.5 | -10.5 | | | X | X | | | | | |
| | VMP-10-20-012913 | 01/29/13 | 1113-1142 | 9446 | -29 | -7.5 | | | X | X | | | | | |
| | VMP-10-30-012913 | 01/29/13 | 1342-1412 | 37789 | -29.5 | -10 | | | X | X | | | | | |
| | | | | | | | | | X | X | | | | | |

ADDITIONAL NOTES:

- 14 day hold time
- Report results between MDL and RL
- Level IV ECVP

| Relinquished by: (Signature) | Received by: (Signature) | Date | Time |
|---|---|---|---|
| | FEDEX | 1/30/13 | 1800 |
| | 1/31/13 0945 | | |
| | | | |

Custody Seal Intact?
Y N None Temp

1301507

# Shell Oil Products Chain Of Custody Record

URS

Air Toxics LTD.
Project Name: Roxana Soil Vapor
Project # 21562850.04001
Lab Vendor #

Please Check Appropriate Box:
☑ ENV. SERVICES ☐ MOTIVA RETAIL ☐ SHELL RETAIL
☐ MOTIVA SD&CH ☐ CONSULTANT ☐ UBRS
☐ SHELL PIPELINE ☐ OTHER

Print Bill To Contact Name: Robert Moosheger

INCIDENT # (ENV SERVICES): 9 7 2 1 5 6 4 0
☐ CHECK IF NO INCIDENT # APPLIES
DATE: 01/30/13
PAGE 2 of 2

PO #:
SAP #: 3 4 0 0 6 1

SAMPLING COMPANY: URS CORPORATION
LOG CODE:
SITE ADDRESS: Street and City: 900 SOUTH CENTRAL AVE – ROXANA
State: IL
GLOBAL ID NO.:
ADDRESS: 1001 HIGHLANDS PLAZA DRIVE WEST - SUITE 300; ST. LOUIS, MO 63110
COP DELIVERABLE TO (Name, Company, Office Location): Elizabeth Kunkel, URS, St. Louis
PHONE NO.: 314-743-4179
E-MAIL: Elizabeth.Kunkel@URSCorp.com
CONSULTANT PROJECT MANAGER: Roxana Soil Vapor
Attorney Address: Air Toxics, LTD 180 Blue Ravine Road, Suite B, Folsom, CA 95630-4719
TELEPHONE:
FAX: 314-429-0462
Bill To (Invoice) E-MAIL: Robert.Moosheger@urs.com
A. Day, C. Williams, C Kretzer, D. Mattingly L. Rathnow, S. Jansen

TURNAROUND TIME (CALENDAR DAYS):
☑ STANDARD (14 DAY) ☐ 5 DAYS ☐ 3 DAYS ☐ 2 DAYS ☐ 24 HOURS ☐ RESULTS NEEDED ON WEEKEND

REQUESTED ANALYSIS

☐ LA - RWQCB REPORT FORMAT ☑ UST AGENCY:
DELIVERABLES: ☐ LEVEL 1 ☐ LEVEL 2 ☐ LEVEL 3 ☑ LEVEL 4 ☐ OTHER (SPECIFY)

☑ SHELL CONTRACT RATE APPLIES
☐ STATE REIMBURSEMENT RATE APPLIES
☐ EDD NOT NEEDED
☑ RECEIPT VERIFICATION REQUESTED

| CAS (LAB USE ONLY) | Field Sample Identification | SAMPLING DATE | SAMPLING TIME | Canister Number | Canister Pressure/Vacuum Initial | Final | Receipt | Final (psi) | Modified TO-15 + Butane & Isopentane | ASTM D-1946 + Helium | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | VMP-11-5-012913 | 01/29/13 | 1315-1345 | 37364 | -29 | -9 | | | X | X | | | | | |
| | VMP-11-8-012913 | 01/29/13 | 1402-1432 | 2170 | -29 | -9.5 | | | X | X | | | | | |
| | VMP-11-25-012913 | 01/29/13 | 1442-1512 | 3042 | -28.5 | -8.5 | | | X | X | | | | | |
| | VMP-11-38-013013 | 01/30/13 | 1200-1230 | 90660 | -30 | -10 | | | X | X | | | | | |
| | VMP-13-5-012913 | 01/29/13 | 1457-1527 | 34069 | -28.5 | -10 | | | X | X | | | | | |
| | VMP-41-10-012913 | 01/29/13 | 850-920 | 53409 | -28.5 | -9.5 | | | X | X | | | | | |
| | VMP-41-20-012913 | 01/29/13 | 951-1021 | 35415 | 29 | 10 | | | X | X | | | | | |
| | VMP-41-30-012913 | 01/29/13 | 1044-1114 | 34088 | -28.5 | -8.5 | | | X | X | | | | | |
| | | 1/30/13 | | | | | | | X | X | | | | | |
| | | | | | | | | | X | X | | | | | |

Turn Around Time: ☑ Normal ☐ Rush
Specify

Lab Use Only
Pressurized by:
Date:
Pressurization Gas: $N_2$ He

ADDITIONAL NOTES:
- 14 day hold time
- Report results between MDL and RL
- Level IV ECVP

Relinquished by: (Signature)
Received by: (Signature) FEDEX
Date: 1/30/13 Time: 1800

Relinquished by: (Signature)
Received by: (Signature) 1/31/13 0945
Date: Time:

Relinquished by: (Signature)
Received by: (Signature)
Date: Time:

05/2004 Revision

Custody Seal Intact?
Y N None Temp N/A
FEDEX

130/567

# Roxana Soil Vapor Quarterly – 1st Quarter 2013 Data Review

**Laboratory SDG: 1302070A,B**

**Data Reviewer: Alan Fleisher**

**Peer Reviewer: Elizabeth Kunkel**

**Date Reviewed: 3/20/2013**

**Guidance: USEPA National Functional Guidelines for Superfund Organic Methods Data Review 2008**

| Sample Identification | Sample Identification |
|---|---|
| VMP-2-5-013113 | VMP-2-22-013113 |
| VMP-10-10-012913 | VMP-13-10-013013 |
| VMP-13-21.5-013013 | VMP-14-5-013113 |
| VMP-14-11.5-013113 | VMP-17-5-013113 |
| VMP-17-5-013113-Dup | VMP-19-5-013113 |
| VMP-42-10-013113 | VMP-42-20-013113 |
| VMP-42-30-013113 | VMP-45-10-013013 |
| VMP-45-20-013013 | VMP-45-30-013013 |
| VMP-49-5-020113 | VMP-49-10-020113 |
| VMP-49-20-020113 | VMP-50-5-020113 |

## 1.0 Data Package Completeness

*Were all items delivered as specified in the QAPP and COC as appropriate?*

Yes

## 2.0 Laboratory Case Narrative \ Cooler Receipt Form

*Were problems noted in the laboratory case narrative or cooler receipt form?*

Yes, the laboratory case narrative indicated sample VMP-45-30-013013 was diluted due to high levels of target analytes. Samples VMP-17-5-013113 and VMP-17-5-013113-Dup were diluted due to high levels of non-target analytes. Although not indicated in the laboratory case narrative, analytes were detected in the method blank. These issues are addressed further in the appropriate sections below.

No issues or discrepancies were noted in the cooler receipt form.

## 3.0 Holding Times

*Were samples extracted/analyzed within applicable limits?*

Yes

## 4.0 Blank Contamination

*Were any analytes detected in the Blanks?*

Yes

| Blank ID | Parameter | Analyte | Concentration/ Amount |
|---|---|---|---|
| 1302070A-21A | TO-15 | Carbon disulfide | 0.35 ppbv / 1.1 µg/m$^3$ |
| 1302070A-21A | TO-15 | Methylene chloride | 0.096 ppbv / 0.33 µg/m$^3$ |
| 1302070A-21A | TO-15 | Toluene | 0.085 ppbv / 0.32 µg/m$^3$ |
| 1302070A-21A | TO-15 | trans-1,3-Dichloroethene | 0.13 ppbv / 0.61 µg/m$^3$ |
| 1302070A-21A | TO-15 | Tetrachloroethene | 0.13 ppbv / 0.87 µg/m$^3$ |
| 1302070A-21A | TO-15 | 1,2-Dibromoethane (EDB) | 0.15 ppbv / 1.2 µg/m$^3$ |
| 1302070A-21A | TO-15 | Chlorobenzene | 0.17 ppbv / 0.79 µg/m$^3$ |
| 1302070A-21A | TO-15 | Ethyl benzene | 0.13 ppbv / 0.55 µg/m$^3$ |
| 1302070A-21A | TO-15 | m,p-Xylene | 0.18 ppbv / 0.79 µg/m$^3$ |
| 1302070A-21A | TO-15 | o-Xylene | 0.18 ppbv / 0.64 µg/m$^3$ |
| 1302070A-21A | TO-15 | Styrene | 0.14 ppbv / 0.60 µg/m$^3$ |
| 1302070A-21A | TO-15 | Bromoform | 0.18 ppbv / 1.9 µg/m$^3$ |
| 1302070A-21A | TO-15 | Cumene | 0.14 ppbv / 0.71 µg/m$^3$ |
| 1302070A-21A | TO-15 | 1,1,2,2-Tetrachloroethane | 0.24 ppbv / 1.7 µg/m$^3$ |
| 1302070A-21A | TO-15 | Propylbenzene | 0.23 ppbv / 1.1 µg/m$^3$ |
| 1302070A-21A | TO-15 | 4-Ethyltoluene | 0.20 ppbv / 0.99 µg/m$^3$ |
| 1302070A-21A | TO-15 | 1,3,5-Trimethylbenzene | 0.23 ppbv / 1.1 µg/m$^3$ |
| 1302070A-21A | TO-15 | 1,2,4-Trimethylbenzene | 0.20 ppbv / 0.97 µg/m$^3$ |
| 1302070A-21A | TO-15 | 1,3-Dichlorobenzene | 0.38 ppbv / 2.3 µg/m$^3$ |
| 1302070A-21A | TO-15 | 1,4-Dichlorobenzene | 0.40 ppbv / 2.4 µg/m$^3$ |
| 1302070A-21A | TO-15 | alpha-Chlorotoluene | 0.27 ppbv / 1.4 µg/m$^3$ |
| 1302070A-21A | TO-15 | 1,2-Dichlorobenzene | 0.39 ppbv / 2.4 µg/m$^3$ |
| 1302070A-21A | TO-15 | 1,2,4-Trichlorobenzene | 1.2 ppbv / 9.0 µg/m$^3$ |
| 1302070A-21A | TO-15 | Hexachlorobutadiene | 0.70 ppbv / 7.5 µg/m$^3$ |
| 1302070B-21A | Natural gases | Nitrogen | 0.055% |

Qualifications due to blank contamination are included in the table below. Analytical data that were reported non-detect or at concentrations greater than five times (5X) the associated blank concentration did not require qualification.

| Sample ID | Parameter | Analyte | New Reporting Limit (RL) | Qualification |
|---|---|---|---|---|
| VMP-2-5-013113 | TO-15 | Carbon disulfide | - | **U** |
| VMP-2-5-013113 | TO-15 | Toluene | - | **U** |
| VMP-2-5-013113 | TO-15 | Tetrachloroethene | - | **U** |
| VMP-2-5-013113 | TO-15 | Propylbenzene | - | **U** |
| VMP-2-5-013113 | TO-15 | 4-Ethyltoluene | - | **U** |
| VMP-2-5-013113 | TO-15 | 1,3,5-Trimethylbenzene | - | **U** |
| VMP-2-5-013113 | TO-15 | 1,2,4-Trimethylbenzene | - | **U** |
| VMP-2-22-013113 | TO-15 | Tetrachloroethene | - | **U** |
| VMP-2-22-013113 | TO-15 | 4-Ethyltoluene | - | **U** |
| VMP-10-10-012913 | TO-15 | Carbon disulfide | - | **U** |
| VMP-10-10-012913 | TO-15 | Toluene | - | **U** |

| Sample ID | Parameter | Analyte | New Reporting Limit (RL) | Qualification |
|---|---|---|---|---|
| VMP-10-10-012913 | TO-15 | Tetrachloroethene | - | **U** |
| VMP-10-10-012913 | TO-15 | 1,3-Dichlorobenzene | - | **U** |
| VMP-10-10-012913 | TO-15 | 1,2,4-Trichlorobenzene | - | **U** |
| VMP-13-10.5-013013 | TO-15 | Carbon disulfide | - | **U** |
| VMP-13-10.5-013013 | TO-15 | Toluene | - | **U** |
| VMP-13-10.5-013013 | TO-15 | Tetrachloroethene | - | **U** |
| VMP-13-10.5-013013 | TO-15 | 4-Ethyltoluene | - | **U** |
| VMP-13-10.5-013013 | TO-15 | 1,2,4-Trichlorobenzene | - | **U** |
| VMP-13-21.5-013013 | TO-15 | Methylene chloride | - | **U** |
| VMP-13-21.5-013013 | TO-15 | Toluene | - | **U** |
| VMP-13-21.5-013013 | TO-15 | Tetrachloroethene | - | **U** |
| VMP-13-21.5-013013 | TO-15 | 4-Ethyltoluene | - | **U** |
| VMP-13-21.5-013013 | TO-15 | 1,3-Dichlorobenzene | - | **U** |
| VMP-13-21.5-013013 | TO-15 | 1,4-Dichlorobenzene | - | **U** |
| VMP-13-21.5-013013 | TO-15 | 1,2,4-Trichlorobenzene | - | **U** |
| VMP-14-5-013113 | TO-15 | Carbon disulfide | - | **U** |
| VMP-14-5-013113 | TO-15 | Methylene chloride | - | **U** |
| VMP-14-5-013113 | TO-15 | Toluene | - | **U** |
| VMP-14-5-013113 | TO-15 | Tetrachloroethene | - | **U** |
| VMP-14-5-013113 | TO-15 | Cumene | - | **U** |
| VMP-14-5-013113 | TO-15 | Propylbenzene | - | **U** |
| VMP-14-5-013113 | TO-15 | 1,3-Dichlorobenzene | - | **U** |
| VMP-14-5-013113 | TO-15 | 1,4-Dichlorobenzene | - | **U** |
| VMP-14-5-013113 | TO-15 | 1,2,4-Trichlorobenzene | - | **U** |
| VMP-14-11.5-013113 | TO-15 | Carbon disulfide | - | **U** |
| VMP-14-11.5-013113 | TO-15 | Toluene | - | **U** |
| VMP-14-11.5-013113 | TO-15 | Tetrachloroethene | - | **U** |
| VMP-14-11.5-013113 | TO-15 | Chlorobenzene | - | **U** |
| VMP-14-11.5-013113 | TO-15 | Propylbenzene | - | **U** |
| VMP-14-11.5-013113 | TO-15 | 4-Ethyltoluene | - | **U** |
| VMP-14-11.5-013113 | TO-15 | 1,3-Dichlorobenzene | - | **U** |
| VMP-14-11.5-013113 | TO-15 | 1,4-Dichlorobenzene | - | **U** |
| VMP-14-11.5-013113 | TO-15 | alpha-Chlorotoluene | - | **U** |
| VMP-14-11.5-013113 | TO-15 | 1,2-Dichlorobenzene | - | **U** |
| VMP-17-5-013113 | TO-15 | 1,2,4-Trichlorobenzene | - | **U** |
| VMP-17-5-013113-Dup | TO-15 | Toluene | - | **U** |
| VMP-17-5-013113-Dup | TO-15 | Propylbenzene | - | **U** |
| VMP-19-5-013113 | TO-15 | Carbon disulfide | - | **U** |
| VMP-19-5-013113 | TO-15 | Methylene chloride | - | **U** |
| VMP-19-5-013113 | TO-15 | 1,2,4-Trichlorobenzene | - | **U** |
| VMP-42-10-013113 | TO-15 | Carbon disulfide | - | **U** |
| VMP-42-10-013113 | TO-15 | 4-Ethyltoluene | - | **U** |
| VMP-42-10-013113 | TO-15 | 1,2,4-Trimethylbenzene | - | **U** |

| Sample ID | Parameter | Analyte | New Reporting Limit (RL) | Qualification |
|---|---|---|---|---|
| VMP-42-20-013113 | TO-15 | Carbon disulfide | - | **U** |
| VMP-42-20-013113 | TO-15 | Toluene | - | **U** |
| VMP-42-20-013113 | TO-15 | Tetrachloroethene | - | **U** |
| VMP-42-20-013113 | TO-15 | 4-Ethyltoluene | - | **U** |
| VMP-42-30-013113 | TO-15 | Toluene | - | **U** |
| VMP-45-10-013113 | TO-15 | Carbon disulfide | - | **U** |
| VMP-45-10-013113 | TO-15 | Toluene | - | **U** |
| VMP-45-20-013113 | TO-15 | Carbon disulfide | - | **U** |
| VMP-45-20-013113 | TO-15 | Toluene | - | **U** |
| VMP-45-30-013113 | TO-15 | Carbon disulfide | - | **U** |
| VMP-45-30-013113 | TO-15 | Toluene | - | **U** |
| VMP-49-5-020113 | TO-15 | Carbon disulfide | - | **U** |
| VMP-49-5-020113 | TO-15 | Toluene | - | **U** |
| VMP-49-5-020113 | TO-15 | Tetrachloroethene | - | **U** |
| VMP-49-5-020113 | TO-15 | 1,2,4-Trimethylbenzene | - | **U** |
| VMP-49-10-020113 | TO-15 | Carbon disulfide | - | **U** |
| VMP-49-10-020113 | TO-15 | Methylene chloride | - | **U** |
| VMP-49-10-020113 | TO-15 | Toluene | - | **U** |
| VMP-49-10-020113 | TO-15 | Tetrachloroethene | - | **U** |
| VMP-49-10-020113 | TO-15 | Ethyl benzene | - | **U** |
| VMP-49-10-020113 | TO-15 | m,p-Xylene | - | **U** |
| VMP-49-10-020113 | TO-15 | Cumene | - | **U** |
| VMP-49-10-020113 | TO-15 | Propylbenzene | - | **U** |
| VMP-49-10-020113 | TO-15 | 4-Ethylbenzene | - | **U** |
| VMP-49-10-020113 | TO-15 | 1,3,5-Trimethylbenzene | - | **U** |
| VMP-49-10-020113 | TO-15 | 1,2,4-Trichlorobenzene | - | **U** |
| VMP-49-20-020113 | TO-15 | Carbon disulfide | - | **U** |
| VMP-49-20-020113 | TO-15 | Methylene chloride | - | **U** |
| VMP-49-20-020113 | TO-15 | Toluene | - | **U** |
| VMP-49-20-020113 | TO-15 | Tetrachloroethene | - | **U** |
| VMP-50-5-020113 | TO-15 | Carbon disulfide | - | **U** |
| VMP-50-5-020113 | TO-15 | Methylene chloride | - | **U** |
| VMP-50-5-020113 | TO-15 | Toluene | - | **U** |
| VMP-50-5-020113 | TO-15 | Tetrachloroethene | - | **U** |
| VMP-50-5-020113 | TO-15 | 4-Ethyltoluene | - | **U** |
| VMP-50-5-020113 | TO-15 | 1,3-Dichlorobenzene | - | **U** |
| VMP-50-5-020113 | TO-15 | 1,4-Dichlorobenzene | - | **U** |
| VMP-50-5-020113 | TO-15 | 1,2,4-Trichlorobenzene | - | **U** |

## 5.0 Laboratory Control Sample

*Were LCS recoveries within evaluation criteria?*

Yes

## 6.0 Surrogate Recoveries

*Were surrogate recoveries within evaluation criteria?*

Yes

## 7.0 Matrix Spike and Matrix Spike Duplicate Recoveries

*Were MS/MSD samples analyzed as part of this SDG?*

MS/MSD samples are not applicable for vapor samples, due to the inability to spike the samples.

## 8.0 Laboratory Duplicate Results

*Were laboratory duplicate samples collected as part of this SDG?*

No

## 9.0 Field Duplicate Results

*Were field duplicate samples collected as part of this SDG?*

Yes

| Field ID | Field Duplicate ID |
|---|---|
| VMP-17-5-013113 | VMP-17-5-013113-Dup |

*Were field duplicate sample RPDs within evaluation criteria?*

Yes

## 10.0 Sample Dilutions

*For samples that were diluted and nondetect, were undiluted results also reported?*

Not applicable; analytes were detected in samples that were diluted.

## 11.0 Additional Qualifications

*Were additional qualifications applied?*

No

eurofins | Air Toxics

2/19/2013
Ms. Elizabeth Kunkel
URS Corporation
1001 Highlands Plaza Dr. West
Suite 300
St. Louis MO 63110

Project Name: Roxana Soil Vapor
Project #: 21562850.04001
Workorder #: 1302070A

Dear Ms. Elizabeth Kunkel

The following report includes the data for the above referenced project for sample(s) received on 2/4/2013 at Air Toxics Ltd.

The data and associated QC analyzed by Modified TO-15 are compliant with the project requirements or laboratory criteria with the exception of the deviations noted in the attached case narrative.

Thank you for choosing Air Toxics Ltd. for your air analysis needs. Air Toxics Ltd. is committed to providing accurate data of the highest quality. Please feel free to contact the Project Manager: Kelly Buettner at 916-985-1000 if you have any questions regarding the data in this report.

Regards,

Kelly Buettner

Project Manager

REVIEWED
ON
3/20/13

eurofins | Air Toxics

# WORK ORDER #: 1302070A

Work Order Summary

| | | | |
|---|---|---|---|
| **CLIENT:** | Ms. Elizabeth Kunkel<br>URS Corporation<br>1001 Highlands Plaza Dr. West<br>Suite 300<br>St. Louis, MO 63110 | **BILL TO:** | Accounts Payable Austin<br>URS Corporation<br>P.O. BOX 203970<br>Austin, TX 78720-1088 |
| **PHONE:** | 314-743-4179 | **P.O. #** | 21562735.00013 |
| **FAX:** | | **PROJECT #** | 21562850.04001 Roxana Soil Vapor |
| **DATE RECEIVED:** | 02/04/2013 | **CONTACT:** | Kelly Buettner |
| **DATE COMPLETED:** | 02/19/2013 | | |

| FRACTION # | NAME | TEST | RECEIPT VAC./PRES. | FINAL PRESSURE |
|---|---|---|---|---|
| 01A | VMP-2-5-013113 | Modified TO-15 | 8.0 "Hg | 15 psi |
| 02A | VMP-2-22-013113 | Modified TO-15 | 7.5 "Hg | 15 psi |
| 03A | VMP-10-10-012913 | Modified TO-15 | 6.0 "Hg | 15 psi |
| 04A | VMP-13-10.5-013013 | Modified TO-15 | 6.0 "Hg | 15 psi |
| 05A | VMP-13-21.5-013013 | Modified TO-15 | 9.5 "Hg | 15 psi |
| 06A | VMP-14-5-013113 | Modified TO-15 | 7.5 "Hg | 15 psi |
| 07A | VMP-14-11.5-013113 | Modified TO-15 | 6.5 "Hg | 15 psi |
| 08A | VMP-17-5-013113 | Modified TO-15 | 7.0 "Hg | 15 psi |
| 09A | VMP-17-5-013113-DUP | Modified TO-15 | 7.0 "Hg | 15 psi |
| 10A | VMP-19-5-013113 | Modified TO-15 | 6.5 "Hg | 15 psi |
| 11A | VMP-42-10-013113 | Modified TO-15 | 8.5 "Hg | 15 psi |
| 12A | VMP-42-20-013113 | Modified TO-15 | 6.5 "Hg | 15 psi |
| 13A | VMP-42-30-013113 | Modified TO-15 | 8.0 "Hg | 15 psi |
| 14A | VMP-45-10-013013 | Modified TO-15 | 6.0 "Hg | 15 psi |
| 15A | VMP-45-20-013013 | Modified TO-15 | 7.0 "Hg | 15 psi |
| 16A | VMP-45-30-013013 | Modified TO-15 | 5.0 "Hg | 15 psi |
| 17A | VMP-49-5-020113 | Modified TO-15 | 7.5 "Hg | 15 psi |
| 18A | VMP-49-10-020113 | Modified TO-15 | 7.0 "Hg | 15 psi |
| 19A | VMP-49-20-020113 | Modified TO-15 | 6.5 "Hg | 15 psi |
| 20A | VMP-50-5-020113 | Modified TO-15 | 6.0 "Hg | 15 psi |
| 21A | Lab Blank | Modified TO-15 | NA | NA |
| 22A | CCV | Modified TO-15 | NA | NA |
| 23A | LCS | Modified TO-15 | NA | NA |

Continued on next page

eurofins | Air Toxics

# WORK ORDER #: 1302070A

Work Order Summary

| | | | |
|---|---|---|---|
| **CLIENT:** | Ms. Elizabeth Kunkel<br>URS Corporation<br>1001 Highlands Plaza Dr. West<br>Suite 300<br>St. Louis, MO 63110 | **BILL TO:** | Accounts Payable Austin<br>URS Corporation<br>P.O. BOX 203970<br>Austin, TX 78720-1088 |
| **PHONE:** | 314-743-4179 | **P.O. #** | 21562735.00013 |
| **FAX:** | | **PROJECT #** | 21562850.04001 Roxana Soil Vapor |
| **DATE RECEIVED:** | 02/04/2013 | **CONTACT:** | Kelly Buettner |
| **DATE COMPLETED:** | 02/19/2013 | | |

| FRACTION # | NAME | TEST | RECEIPT VAC./PRES. | FINAL PRESSURE |
|---|---|---|---|---|
| 23AA | LCSD | Modified TO-15 | NA | NA |

CERTIFIED BY: Heidi Hayes

Technical Director

DATE: 02/19/13

Certfication numbers: AZ Licensure AZ0775, CA NELAP - 12282CA, NY NELAP - 11291,
TX NELAP - T104704434-12-5, UT NELAP CA009332012-3, WA NELAP - C935
Name of Accrediting Agency: NELAP/ORELAP (Oregon Environmental Laboratory Accreditation Program)
Accreditation number: CA300005, Effective date: 10/18/2011, Expiration date: 10/17/2012.
Eurofins Air Toxics Ltd. certifies that the test results contained in this report meet all requirements of the NELAC standards

This report shall not be reproduced, except in full, without the written approval of Eurofins Air Toxics, Inc.

180 BLUE RAVINE ROAD, SUITE B FOLSOM, CA - 9563
(916) 985-1000 . (800) 985-5955 . FAX (916) 985-1020

**LABORATORY NARRATIVE**
**EPA Method TO-15**
**URS Corporation**
**Workorder# 1302070A**

Twenty 1 Liter Summa Canister samples were received on February 05, 2013. The laboratory performed analysis via EPA Method TO-15 using GC/MS in the full scan mode.

This workorder was independently validated prior to submittal using 'USEPA National Functional Guidelines' as generally applied to the analysis of volatile organic compounds in air. A rules-based, logic driven, independent validation engine was employed to assess completeness, evaluate pass/fail of relevant project quality control requirements and verification of all quantified amounts.

**Receiving Notes**

There were no receiving discrepancies.

**Analytical Notes**

As per client project requirements, the laboratory has reported estimated values for target compound hits that are below the Reporting Limit but greater than the Method Detection Limit. Concentrations that are below the level at which the canister was certified may be false positives.

Dilution was performed on sample VMP-45-30-013013 due to the presence of high level target species.

Dilution was performed on samples VMP-17-5-013113 and VMP-17-5-013113-DUP due to the presence of high level non-target species.

**Definition of Data Qualifying Flags**

Eight qualifiers may have been used on the data analysis sheets and indicates as follows:

B - Compound present in laboratory blank greater than reporting limit (background subtraction not performed).
J - Estimated value.
E - Exceeds instrument calibration range.
S - Saturated peak.
Q - Exceeds quality control limits.
U - Compound analyzed for but not detected above the reporting limit.
UJ- Non-detected compound associated with low bias in the CCV and/or LCS.
N - The identification is based on presumptive evidence.

File extensions may have been used on the data analysis sheets and indicates as follows:
a-File was requantified
b-File was quantified by a second column and detector
r1-File was requantified for the purpose of reissue

eurofins | Air Toxics

# Summary of Detected Compounds
# EPA METHOD TO-15 GC/MS FULL SCAN

**Client Sample ID: VMP-2-5-013113**

**Lab ID#: 1302070A-01A**

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 1.4 | 0.43 J | 6.8 | 2.1 J |
| Freon 11 | 1.4 | 0.26 J | 7.8 | 1.4 J |
| Ethanol | 5.5 | 2.1 J | 10 | 4.0 J |
| Acetone | 14 | 5.6 J | 33 | 13 J |
| 2-Propanol | 5.5 | 16 | 14 | 39 |
| Carbon Disulfide | 5.5 | ~~0.69 J~~ | 17 | ~~2.2 J~~ |
| Hexane | 1.4 | 0.26 J | 4.9 | 0.93 J |
| 2,2,4-Trimethylpentane | 1.4 | 5.6 | 6.4 | 26 |
| Benzene | 1.4 | 0.82 J | 4.4 | 2.6 J |
| 4-Methyl-2-pentanone | 1.4 | 0.49 J | 5.6 | 2.0 J |
| Toluene | 1.4 | ~~0.17 J~~ | 5.2 | ~~0.64 J~~ |
| Tetrachloroethene | 1.4 | ~~0.26 J~~ | 9.4 | ~~1.8 J~~ |
| Propylbenzene | 1.4 | ~~0.20 J~~ | 6.8 | ~~0.99 J~~ |
| 4-Ethyltoluene | 1.4 | ~~0.24 J~~ | 6.8 | ~~1.2 J~~ |
| 1,3,5-Trimethylbenzene | 1.4 | ~~0.25 J~~ | 6.8 | ~~1.2 J~~ |
| 1,2,4-Trimethylbenzene | 1.4 | ~~0.80 J~~ | 6.8 | ~~3.9 J~~ |
| Butane | 5.5 | 9.9 | 13 | 23 |
| Isopentane | 5.5 | 1.5 J | 16 | 4.4 J |

**Client Sample ID: VMP-2-22-013113**

**Lab ID#: 1302070A-02A**

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 1.3 | 0.50 J | 6.6 | 2.5 J |
| Freon 11 | 1.3 | 0.18 J | 7.6 | 1.0 J |
| Ethanol | 5.4 | 2.2 J | 10 | 4.2 J |
| Acetone | 13 | 4.4 J | 32 | 10 J |
| 2-Propanol | 5.4 | 2.3 J | 13 | 5.7 J |
| Carbon Disulfide | 5.4 | ~~0.64 J~~ | 17 | ~~2.0 J~~ |
| Hexane | 1.3 | 0.25 J | 4.7 | 0.88 J |
| 2,2,4-Trimethylpentane | 1.3 | 0.55 J | 6.3 | 2.6 J |
| Benzene | 1.3 | 0.56 J | 4.3 | 1.8 J |
| Tetrachloroethene | 1.3 | 0.73 J | 9.1 | 4.9 J |

eurofins | Air Toxics

# Summary of Detected Compounds
# EPA METHOD TO-15 GC/MS FULL SCAN

**Client Sample ID: VMP-2-22-013113**

**Lab ID#: 1302070A-02A**

| | | | | |
|---|---|---|---|---|
| 4-Ethyltoluene | 1.3 | ~~0.19 J~~ | 6.6 | ~~0.94 J~~ |
| Butane | 5.4 | 1.8 J | 13 | 4.3 J |
| Isopentane | 5.4 | 1.5 J | 16 | 4.4 J |

**Client Sample ID: VMP-10-10-012913**

**Lab ID#: 1302070A-03A**

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 1.3 | 0.50 J | 6.2 | 2.4 J |
| Freon 11 | 1.3 | 0.22 J | 7.1 | 1.2 J |
| Ethanol | 5.0 | 1.8 J | 9.5 | 3.4 J |
| Acetone | 13 | 8.4 J | 30 | 20 J |
| 2-Propanol | 5.0 | 6.0 | 12 | 15 |
| Carbon Disulfide | 5.0 | ~~0.65 J~~ | 16 | ~~2.0 J~~ |
| Methylene Chloride | 13 | 0.58 J | 44 | 2.0 J |
| Hexane | 1.3 | 0.40 J | 4.4 | 1.4 J |
| 2,2,4-Trimethylpentane | 1.3 | 1.4 | 5.9 | 6.4 |
| Benzene | 1.3 | 5.6 | 4.0 | 18 |
| 4-Methyl-2-pentanone | 1.3 | 0.27 J | 5.2 | 1.1 J |
| Toluene | 1.3 | ~~0.28 J~~ | 4.7 | ~~1.1 J~~ |
| Tetrachloroethene | 1.3 | ~~0.16 J~~ | 8.5 | ~~1.1 J~~ |
| 1,3-Dichlorobenzene | 1.3 | ~~0.17 J~~ | 7.6 | ~~1.0 J~~ |
| 1,2,4-Trichlorobenzene | 5.0 | ~~0.49 J~~ | 37 | ~~3.7 J~~ |
| Butane | 5.0 | 1.4 J | 12 | 3.2 J |
| Isopentane | 5.0 | 1.4 J | 15 | 4.3 J |

**Client Sample ID: VMP-13-10.5-013013**

**Lab ID#: 1302070A-04A**

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 1.3 | 0.45 J | 6.2 | 2.2 J |
| Freon 11 | 1.3 | 0.20 J | 7.1 | 1.1 J |
| Ethanol | 5.0 | 2.5 J | 9.5 | 4.7 J |
| Acetone | 13 | 4.2 J | 30 | 10 J |

eurofins | Air Toxics

# Summary of Detected Compounds
# EPA METHOD TO-15 GC/MS FULL SCAN

**Client Sample ID: VMP-13-10.5-013013**

**Lab ID#: 1302070A-04A**

| | | | | |
|---|---|---|---|---|
| 2-Propanol | 5.0 | 3.9 J | 12 | 9.6 J |
| Carbon Disulfide | 5.0 | ~~0.64 J~~ | 16 | ~~2.0 J~~ |
| Hexane | 1.3 | 0.33 J | 4.4 | 1.2 J |
| 2,2,4-Trimethylpentane | 1.3 | 0.22 J | 5.9 | 1.0 J |
| Benzene | 1.3 | 0.66 J | 4.0 | 2.1 J |
| Toluene | 1.3 | ~~0.18 J~~ | 4.7 | ~~0.67 J~~ |
| Tetrachloroethene | 1.3 | ~~0.16 J~~ | 8.5 | ~~1.0 J~~ |
| 4-Ethyltoluene | 1.3 | ~~0.16 J~~ | 6.2 | ~~0.78 J~~ |
| 1,2,4-Trichlorobenzene | 5.0 | ~~0.42 J~~ | 37 | ~~3.1 J~~ |
| Isopentane | 5.0 | 0.82 J | 15 | 2.4 J |

**Client Sample ID: VMP-13-21.5-013013**

**Lab ID#: 1302070A-05A**

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 1.5 | 0.44 J | 7.3 | 2.2 J |
| Freon 11 | 1.5 | 0.18 J | 8.3 | 1.0 J |
| Ethanol | 5.9 | 2.7 J | 11 | 5.1 J |
| Acetone | 15 | 4.3 J | 35 | 10 J |
| 2-Propanol | 5.9 | 6.2 | 14 | 15 |
| Carbon Disulfide | 5.9 | 2.5 J | 18 | 7.8 J |
| Methylene Chloride | 15 | ~~0.28 J~~ | 51 | ~~0.98 J~~ |
| Hexane | 1.5 | 0.32 J | 5.2 | 1.1 J |
| Chloroform | 1.5 | 17 | 7.2 | 82 |
| 2,2,4-Trimethylpentane | 1.5 | 1.2 J | 6.9 | 5.7 J |
| Benzene | 1.5 | 2.7 | 4.7 | 8.8 |
| 4-Methyl-2-pentanone | 1.5 | 0.39 J | 6.1 | 1.6 J |
| Toluene | 1.5 | ~~0.17 J~~ | 5.6 | ~~0.63 J~~ |
| Tetrachloroethene | 1.5 | ~~0.30 J~~ | 10 | ~~2.0 J~~ |
| 4-Ethyltoluene | 1.5 | ~~0.14 J~~ | 7.3 | ~~0.68 J~~ |
| 1,3-Dichlorobenzene | 1.5 | ~~0.26 J~~ | 8.9 | ~~1.6 J~~ |
| 1,4-Dichlorobenzene | 1.5 | ~~0.27 J~~ | 8.9 | ~~1.6 J~~ |
| 1,2,4-Trichlorobenzene | 5.9 | ~~0.75 J~~ | 44 | ~~5.6 J~~ |

eurofins | Air Toxics

# Summary of Detected Compounds
# EPA METHOD TO-15 GC/MS FULL SCAN

**Client Sample ID: VMP-14-5-013113**

**Lab ID#: 1302070A-06A**

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 1.3 | 0.49 J | 6.6 | 2.4 J |
| Freon 11 | 1.3 | 0.21 J | 7.6 | 1.2 J |
| Ethanol | 5.4 | 0.96 J | 10 | 1.8 J |
| Acetone | 13 | 4.2 J | 32 | 10 J |
| 2-Propanol | 5.4 | 0.91 J | 13 | 2.2 J |
| Carbon Disulfide | 5.4 | 0.69 J | 17 | 2.2 J |
| Methylene Chloride | 13 | 0.18 J | 47 | 0.62 J |
| 2,2,4-Trimethylpentane | 1.3 | 0.51 J | 6.3 | 2.4 J |
| Toluene | 1.3 | 0.17 J | 5.1 | 0.64 J |
| Tetrachloroethene | 1.3 | 0.17 J | 9.1 | 1.1 J |
| Cumene | 1.3 | 0.15 J | 6.6 | 0.76 J |
| Propylbenzene | 1.3 | 0.29 J | 6.6 | 1.4 J |
| 1,3-Dichlorobenzene | 1.3 | 0.18 J | 8.1 | 1.1 J |
| 1,4-Dichlorobenzene | 1.3 | 0.27 J | 8.1 | 1.6 J |
| 1,2,4-Trichlorobenzene | 5.4 | 1.5 J | 40 | 11 J |
| Butane | 5.4 | 1.8 J | 13 | 4.4 J |
| Isopentane | 5.4 | 0.59 J | 16 | 1.7 J |

**Client Sample ID: VMP-14-11.5-013113**

**Lab ID#: 1302070A-07A**

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 1.3 | 0.56 J | 6.4 | 2.8 J |
| Freon 11 | 1.3 | 0.29 J | 7.2 | 1.6 J |
| Ethanol | 5.2 | 0.74 J | 9.7 | 1.4 J |
| Acetone | 13 | 3.4 J | 31 | 8.2 J |
| 2-Propanol | 5.2 | 0.73 J | 13 | 1.8 J |
| Carbon Disulfide | 5.2 | 0.87 J | 16 | 2.7 J |
| Hexane | 1.3 | 0.41 J | 4.5 | 1.4 J |
| Chloroform | 1.3 | 1.9 | 6.3 | 9.4 |
| 2,2,4-Trimethylpentane | 1.3 | 1.0 J | 6.0 | 4.7 J |
| Toluene | 1.3 | 0.24 J | 4.9 | 0.89 J |
| Tetrachloroethene | 1.3 | 0.16 J | 8.8 | 1.1 J |

eurofins | Air Toxics

# Summary of Detected Compounds
# EPA METHOD TO-15 GC/MS FULL SCAN

**Client Sample ID: VMP-14-11.5-013113**

**Lab ID#: 1302070A-07A**

| | | | | |
|---|---|---|---|---|
| Chlorobenzene | 1.3 | ~~0.17 J~~ | 5.9 | ~~0.80 J~~ |
| Propylbenzene | 1.3 | ~~0.20 J~~ | 6.3 | ~~0.97 J~~ |
| 4-Ethyltoluene | 1.3 | ~~0.14 J~~ | 6.3 | ~~0.67 J~~ |
| 1,3-Dichlorobenzene | 1.3 | ~~0.40 J~~ | 7.8 | ~~2.4 J~~ |
| 1,4-Dichlorobenzene | 1.3 | ~~0.43 J~~ | 7.8 | ~~2.6 J~~ |
| alpha-Chlorotoluene | 1.3 | ~~0.30 J~~ | 6.7 | ~~1.6 J~~ |
| 1,2-Dichlorobenzene | 1.3 | ~~0.35 J~~ | 7.8 | ~~2.1 J~~ |
| 1,2,4-Trichlorobenzene | 5.2 | ~~1.1 J~~ | 38 | ~~8.0 J~~ |
| Isopentane | 5.2 | 0.97 J | 15 | 2.9 J |

**Client Sample ID: VMP-17-5-013113**

**Lab ID#: 1302070A-08A**

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Acetone | 53 | 4.6 J | 120 | 11 J |
| 2-Propanol | 21 | 2.6 J | 52 | 6.5 J |
| Carbon Disulfide | 21 | 2.4 J | 66 | 7.6 J |
| Hexane | 5.3 | 1.8 J | 19 | 6.5 J |
| Cyclohexane | 5.3 | 2.8 J | 18 | 9.7 J |
| 2,2,4-Trimethylpentane | 5.3 | 3.8 J | 25 | 18 J |
| Benzene | 5.3 | 220 | 17 | 710 |
| Toluene | 5.3 | 0.75 J | 20 | 2.8 J |
| Ethyl Benzene | 5.3 | 1.1 J | 23 | 4.7 J |
| m,p-Xylene | 5.3 | 1.6 J | 23 | 6.8 J |
| Cumene | 5.3 | 2.4 J | 26 | 12 J |
| Propylbenzene | 5.3 | 1.3 J | 26 | 6.2 J |
| 4-Ethyltoluene | 5.3 | 1.9 J | 26 | 9.6 J |
| 1,2,4-Trimethylbenzene | 5.3 | 1.8 J | 26 | 9.1 J |
| 1,2,4-Trichlorobenzene | 21 | ~~3.3 J~~ | 160 | ~~24 J~~ |
| Isopentane | 21 | 12 J | 62 | 36 J |

**Client Sample ID: VMP-17-5-013113-DUP**

**Lab ID#: 1302070A-09A**

eurofins | Air Toxics

# Summary of Detected Compounds
# EPA METHOD TO-15 GC/MS FULL SCAN

**Client Sample ID: VMP-17-5-013113-DUP**

**Lab ID#: 1302070A-09A**

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Acetone | 53 | 4.0 J | 120 | 9.6 J |
| Carbon Disulfide | 21 | 2.2 J | 66 | 7.0 J |
| Hexane | 5.3 | 4.3 J | 19 | 15 J |
| Cyclohexane | 5.3 | 4.3 J | 18 | 15 J |
| 2,2,4-Trimethylpentane | 5.3 | 3.4 J | 25 | 16 J |
| Benzene | 5.3 | 330 | 17 | 1000 |
| Heptane | 5.3 | 1.5 J | 22 | 6.3 J |
| Toluene | 5.3 | ~~0.39 J~~ | 20 | ~~1.5 J~~ |
| Cumene | 5.3 | 1.4 J | 26 | 6.8 J |
| Propylbenzene | 5.3 | ~~0.70 J~~ | 26 | ~~3.5 J~~ |
| 4-Ethyltoluene | 5.3 | 1.1 J | 26 | 5.5 J |
| Butane | 21 | 16 J | 50 | 39 J |
| Isopentane | 21 | 45 | 62 | 130 |

**Client Sample ID: VMP-19-5-013113**

**Lab ID#: 1302070A-10A**

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 1.3 | 0.46 J | 6.4 | 2.3 J |
| Freon 11 | 1.3 | 0.21 J | 7.2 | 1.2 J |
| Ethanol | 5.2 | 12 | 9.7 | 22 |
| Acetone | 13 | 9.6 J | 31 | 23 J |
| 2-Propanol | 5.2 | 34 | 13 | 83 |
| Carbon Disulfide | 5.2 | ~~0.66 J~~ | 16 | ~~2.1 J~~ |
| Methylene Chloride | 13 | ~~0.16 J~~ | 45 | ~~0.54 J~~ |
| Hexane | 1.3 | 5.5 | 4.5 | 19 |
| Cyclohexane | 1.3 | 3.6 | 4.4 | 12 |
| 2,2,4-Trimethylpentane | 1.3 | 4.3 | 6.0 | 20 |
| Benzene | 1.3 | 470 | 4.1 | 1500 |
| Heptane | 1.3 | 2.4 | 5.3 | 9.6 |
| Toluene | 1.3 | 1.3 | 4.9 | 5.0 |
| Tetrachloroethene | 1.3 | 0.14 J | 8.8 | 0.99 J |
| Ethyl Benzene | 1.3 | 9.8 | 5.6 | 42 |

eurofins | Air Toxics

# Summary of Detected Compounds
# EPA METHOD TO-15 GC/MS FULL SCAN

**Client Sample ID: VMP-19-5-013113**

**Lab ID#: 1302070A-10A**

| | | | | |
|---|---|---|---|---|
| m,p-Xylene | 1.3 | 25 | 5.6 | 110 |
| o-Xylene | 1.3 | 4.0 | 5.6 | 17 |
| Cumene | 1.3 | 13 | 6.3 | 63 |
| Propylbenzene | 1.3 | 10 | 6.3 | 49 |
| 4-Ethyltoluene | 1.3 | 19 | 6.3 | 92 |
| 1,3,5-Trimethylbenzene | 1.3 | 12 | 6.3 | 57 |
| 1,2,4-Trimethylbenzene | 1.3 | 29 | 6.3 | 140 |
| 1,2,4-Trichlorobenzene | 5.2 | ~~0.38 J~~ | 38 | ~~2.8 J~~ |
| Butane | 5.2 | 24 | 12 | 57 |
| Isopentane | 5.2 | 40 | 15 | 120 |

**Client Sample ID: VMP-42-10-013113**

**Lab ID#: 1302070A-11A**

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 1.4 | 0.50 J | 7.0 | 2.5 J |
| Freon 11 | 1.4 | 0.21 J | 7.9 | 1.2 J |
| Ethanol | 5.6 | 1.2 J | 11 | 2.2 J |
| Acetone | 14 | 1.9 J | 33 | 4.5 J |
| 2-Propanol | 5.6 | 0.93 J | 14 | 2.3 J |
| Carbon Disulfide | 5.6 | ~~0.62 J~~ | 18 | ~~1.9 J~~ |
| Hexane | 1.4 | 0.26 J | 5.0 | 0.93 J |
| 2,2,4-Trimethylpentane | 1.4 | 0.43 J | 6.6 | 2.0 J |
| Benzene | 1.4 | 0.73 J | 4.5 | 2.3 J |
| 4-Ethyltoluene | 1.4 | ~~0.18 J~~ | 6.9 | ~~0.89 J~~ |
| 1,2,4-Trimethylbenzene | 1.4 | ~~0.44 J~~ | 6.9 | ~~2.1 J~~ |

**Client Sample ID: VMP-42-20-013113**

**Lab ID#: 1302070A-12A**

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 1.3 | 0.40 J | 6.4 | 2.0 J |
| Freon 11 | 1.3 | 0.24 J | 7.2 | 1.4 J |
| Ethanol | 5.2 | 2.4 J | 9.7 | 4.5 J |

eurofins | Air Toxics

# Summary of Detected Compounds
# EPA METHOD TO-15 GC/MS FULL SCAN

**Client Sample ID: VMP-42-20-013113**

**Lab ID#: 1302070A-12A**

| | | | | |
|---|---|---|---|---|
| Acetone | 13 | 3.1 J | 31 | 7.3 J |
| 2-Propanol | 5.2 | 1.1 J | 13 | 2.6 J |
| Carbon Disulfide | 5.2 | ~~0.66 J~~ | 16 | ~~2.0 J~~ |
| Methylene Chloride | 13 | 1.5 J | 45 | 5.3 J |
| Hexane | 1.3 | 1.3 | 4.5 | 4.5 |
| Chloroform | 1.3 | 5.1 | 6.3 | 25 |
| 2,2,4-Trimethylpentane | 1.3 | 0.23 J | 6.0 | 1.1 J |
| Benzene | 1.3 | 2.0 | 4.1 | 6.3 |
| Heptane | 1.3 | 0.95 J | 5.3 | 3.9 J |
| Toluene | 1.3 | ~~0.22 J~~ | 4.9 | ~~0.82 J~~ |
| Tetrachloroethene | 1.3 | ~~0.46 J~~ | 8.8 | ~~3.1 J~~ |
| 4-Ethyltoluene | 1.3 | ~~0.13 J~~ | 6.3 | ~~0.66 J~~ |
| Butane | 5.2 | 5.0 J | 12 | 12 J |
| Isopentane | 5.2 | 1.7 J | 15 | 5.1 J |

**Client Sample ID: VMP-42-30-013113**

**Lab ID#: 1302070A-13A**

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 1.4 | 0.41 J | 6.8 | 2.0 J |
| Freon 11 | 1.4 | 0.60 J | 7.8 | 3.4 J |
| Ethanol | 5.5 | 2.0 J | 10 | 3.8 J |
| Acetone | 14 | 2.6 J | 33 | 6.2 J |
| 2-Propanol | 5.5 | 0.59 J | 14 | 1.4 J |
| Carbon Disulfide | 5.5 | 1.9 J | 17 | 6.1 J |
| Hexane | 1.4 | 0.50 J | 4.9 | 1.8 J |
| Chloroform | 1.4 | 1.6 | 6.7 | 7.9 |
| Cyclohexane | 1.4 | 0.65 J | 4.8 | 2.2 J |
| 2,2,4-Trimethylpentane | 1.4 | 51 | 6.4 | 240 |
| Heptane | 1.4 | 0.32 J | 5.6 | 1.3 J |
| Toluene | 1.4 | ~~0.12 J~~ | 5.2 | ~~0.46 J~~ |
| Butane | 5.5 | 140 | 13 | 330 |
| Isopentane | 5.5 | 34 | 16 | 100 |

eurofins | Air Toxics

# Summary of Detected Compounds
# EPA METHOD TO-15 GC/MS FULL SCAN

**Client Sample ID: VMP-45-10-013013**

**Lab ID#: 1302070A-14A**

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 1.3 | 0.45 J | 6.2 | 2.2 J |
| Freon 11 | 1.3 | 0.19 J | 7.1 | 1.1 J |
| Ethanol | 5.0 | 12 | 9.5 | 22 |
| Acetone | 13 | 7.4 J | 30 | 18 J |
| 2-Propanol | 5.0 | 23 | 12 | 57 |
| Carbon Disulfide | 5.0 | ~~0.63 J~~ | 16 | ~~2.0 J~~ |
| Hexane | 1.3 | 0.57 J | 4.4 | 2.0 J |
| 2,2,4-Trimethylpentane | 1.3 | 1.0 J | 5.9 | 4.8 J |
| Benzene | 1.3 | 5.1 | 4.0 | 16 |
| Heptane | 1.3 | 0.29 J | 5.2 | 1.2 J |
| 4-Methyl-2-pentanone | 1.3 | 0.28 J | 5.2 | 1.1 J |
| Toluene | 1.3 | ~~0.34 J~~ | 4.7 | ~~1.3 J~~ |
| Butane | 5.0 | 2.1 J | 12 | 5.0 J |
| Isopentane | 5.0 | 0.86 J | 15 | 2.5 J |

**Client Sample ID: VMP-45-20-013013**

**Lab ID#: 1302070A-15A**

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 1.3 | 0.49 J | 6.5 | 2.4 J |
| Freon 11 | 1.3 | 0.18 J | 7.4 | 1.0 J |
| Ethanol | 5.3 | 1.9 J | 9.9 | 3.5 J |
| Acetone | 13 | 10 J | 31 | 24 J |
| 2-Propanol | 5.3 | 3.3 J | 13 | 8.1 J |
| Carbon Disulfide | 5.3 | ~~0.60 J~~ | 16 | ~~1.9 J~~ |
| 2-Butanone (Methyl Ethyl Ketone) | 5.3 | 1.2 J | 16 | 3.6 J |
| Chloroform | 1.3 | 2.3 | 6.4 | 11 |
| 2,2,4-Trimethylpentane | 1.3 | 66 | 6.2 | 310 |
| Toluene | 1.3 | ~~0.10 J~~ | 5.0 | ~~0.38 J~~ |
| Butane | 5.3 | 8.9 | 12 | 21 |
| Isopentane | 5.3 | 1.7 J | 16 | 5.1 J |

eurofins | Air Toxics

# Summary of Detected Compounds
# EPA METHOD TO-15 GC/MS FULL SCAN

**Client Sample ID: VMP-45-30-013013**

**Lab ID#: 1302070A-16A**

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 2.4 | 0.36 J | 12 | 1.8 J |
| Freon 11 | 2.4 | 0.67 J | 14 | 3.8 J |
| Ethanol | 9.7 | 8.3 J | 18 | 16 J |
| Acetone | 24 | 22 J | 57 | 52 J |
| 2-Propanol | 9.7 | 940 | 24 | 2300 |
| Carbon Disulfide | 9.7 | ~~1.3 J~~ U | 30 | ~~4.1 J~~ U |
| Hexane | 2.4 | 0.78 J | 8.5 | 2.8 J |
| Chloroform | 2.4 | 1.8 J | 12 | 8.6 J |
| 2,2,4-Trimethylpentane | 2.4 | 120 | 11 | 560 |
| Benzene | 2.4 | 1.8 J | 7.7 | 5.8 J |
| Toluene | 2.4 | ~~0.40 J~~ U | 9.1 | ~~1.5 J~~ U |
| Butane | 9.7 | 4.7 J | 23 | 11 J |
| Isopentane | 9.7 | 2.6 J | 28 | 7.8 J |

**Client Sample ID: VMP-49-5-020113**

**Lab ID#: 1302070A-17A**

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 1.3 | 0.43 J | 6.6 | 2.1 J |
| Freon 11 | 1.3 | 0.21 J | 7.6 | 1.2 J |
| Ethanol | 5.4 | 1.7 J | 10 | 3.3 J |
| Acetone | 13 | 11 J | 32 | 27 J |
| 2-Propanol | 5.4 | 3.2 J | 13 | 7.7 J |
| Carbon Disulfide | 5.4 | ~~0.72 J~~ U | 17 | ~~2.2 J~~ U |
| 2-Butanone (Methyl Ethyl Ketone) | 5.4 | 1.8 J | 16 | 5.5 J |
| 2,2,4-Trimethylpentane | 1.3 | 0.74 J | 6.3 | 3.5 J |
| 4-Methyl-2-pentanone | 1.3 | 0.33 J | 5.5 | 1.3 J |
| Toluene | 1.3 | ~~0.13 J~~ U | 5.1 | ~~0.50 J~~ U |
| Tetrachloroethene | 1.3 | ~~0.19 J~~ U | 9.1 | ~~1.3 J~~ U |
| 1,2,4-Trichlorobenzene | 5.4 | ~~0.35 J~~ U | 40 | ~~2.6 J~~ U |

eurofins | Air Toxics

# Summary of Detected Compounds
# EPA METHOD TO-15 GC/MS FULL SCAN

**Client Sample ID: VMP-49-10-020113**

**Lab ID#: 1302070A-18A**

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 1.3 | 0.42 J | 6.5 | 2.1 J |
| Freon 11 | 1.3 | 0.17 J | 7.4 | 0.98 J |
| Acetone | 13 | 3.6 J | 31 | 8.4 J |
| 2-Propanol | 5.3 | 0.73 J | 13 | 1.8 J |
| Carbon Disulfide | 5.3 | ~~0.92 J~~ | 16 | ~~2.9 J~~ |
| Methylene Chloride | 13 | ~~0.26 J~~ | 46 | ~~0.92 J~~ |
| Hexane | 1.3 | 0.45 J | 4.6 | 1.6 J |
| Benzene | 1.3 | 10 | 4.2 | 33 |
| Toluene | 1.3 | ~~0.15 J~~ | 5.0 | ~~0.58 J~~ |
| Tetrachloroethene | 1.3 | ~~0.15 J~~ | 9.0 | ~~1.0 J~~ |
| Ethyl Benzene | 1.3 | ~~0.23 J~~ | 5.7 | ~~0.98 J~~ |
| m,p-Xylene | 1.3 | ~~0.56 J~~ | 5.7 | ~~2.4 J~~ |
| Cumene | 1.3 | ~~0.34 J~~ | 6.5 | ~~1.7 J~~ |
| Propylbenzene | 1.3 | ~~0.43 J~~ | 6.5 | ~~2.1 J~~ |
| 4-Ethyltoluene | 1.3 | ~~0.66 J~~ | 6.5 | ~~3.3 J~~ |
| 1,3,5-Trimethylbenzene | 1.3 | ~~0.56 J~~ | 6.5 | ~~2.8 J~~ |
| 1,2,4-Trimethylbenzene | 1.3 | 1.7 | 6.5 | 8.5 |
| 1,2,4-Trichlorobenzene | 5.3 | ~~0.38 J~~ | 39 | ~~2.8 J~~ |
| Butane | 5.3 | 2.0 J | 12 | 4.8 J |
| Isopentane | 5.3 | 0.68 J | 16 | 2.0 J |

**Client Sample ID: VMP-49-20-020113**

**Lab ID#: 1302070A-19A**

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 1.3 | 0.48 J | 6.4 | 2.4 J |
| Freon 11 | 1.3 | 0.20 J | 7.2 | 1.1 J |
| Ethanol | 5.2 | 1.3 J | 9.7 | 2.4 J |
| Acetone | 13 | 5.8 J | 31 | 14 J |
| 2-Propanol | 5.2 | 0.70 J | 13 | 1.7 J |
| Carbon Disulfide | 5.2 | ~~1.0 J~~ | 16 | ~~3.2 J~~ |
| Methylene Chloride | 13 | ~~0.28 J~~ | 45 | ~~0.98 J~~ |
| Hexane | 1.3 | 0.61 J | 4.5 | 2.1 J |

eurofins | Air Toxics

# Summary of Detected Compounds
# EPA METHOD TO-15 GC/MS FULL SCAN

**Client Sample ID: VMP-49-20-020113**

**Lab ID#: 1302070A-19A**

| | | | | |
|---|---|---|---|---|
| 2,2,4-Trimethylpentane | 1.3 | 0.72 J | 6.0 | 3.4 J |
| Heptane | 1.3 | 0.35 J | 5.3 | 1.4 J |
| Toluene | 1.3 | ~~0.28 J~~ | 4.9 | ~~1.0 J~~ |
| Tetrachloroethene | 1.3 | ~~0.19 J~~ | 8.8 | ~~1.3 J~~ |
| Butane | 5.2 | 3.3 J | 12 | 7.8 J |
| Isopentane | 5.2 | 0.98 J | 15 | 2.9 J |

**Client Sample ID: VMP-50-5-020113**

**Lab ID#: 1302070A-20A**

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 1.3 | 0.56 J | 6.2 | 2.7 J |
| Freon 11 | 1.3 | 0.21 J | 7.1 | 1.2 J |
| Ethanol | 5.0 | 1.9 J | 9.5 | 3.7 J |
| Acetone | 13 | 3.0 J | 30 | 7.0 J |
| 2-Propanol | 5.0 | 2.3 J | 12 | 5.7 J |
| Carbon Disulfide | 5.0 | ~~1.3 J~~ | 16 | ~~3.9 J~~ |
| Methylene Chloride | 13 | ~~0.16 J~~ | 44 | ~~0.57 J~~ |
| Hexane | 1.3 | 1.1 J | 4.4 | 4.0 J |
| Chloroform | 1.3 | 0.29 J | 6.2 | 1.4 J |
| 1,1,1-Trichloroethane | 1.3 | 1.4 | 6.9 | 7.8 |
| 2,2,4-Trimethylpentane | 1.3 | 2.6 | 5.9 | 12 |
| Benzene | 1.3 | 0.52 J | 4.0 | 1.7 J |
| Heptane | 1.3 | 0.29 J | 5.2 | 1.2 J |
| Toluene | 1.3 | ~~0.16 J~~ | 4.7 | ~~0.60 J~~ |
| Tetrachloroethene | 1.3 | ~~0.26 J~~ | 8.5 | ~~1.7 J~~ |
| 4-Ethyltoluene | 1.3 | ~~0.24 J~~ | 6.2 | ~~1.2 J~~ |
| 1,3-Dichlorobenzene | 1.3 | ~~0.19 J~~ | 7.6 | ~~1.2 J~~ |
| 1,4-Dichlorobenzene | 1.3 | ~~0.26 J~~ | 7.6 | ~~1.6 J~~ |
| 1,2,4-Trichlorobenzene | 5.0 | ~~0.66 J~~ | 37 | ~~4.9 J~~ |
| Butane | 5.0 | 98 | 12 | 230 |
| Isopentane | 5.0 | 39 | 15 | 120 |

eurofins | Air Toxics

**Client Sample ID: VMP-2-5-013113**

**Lab ID#: 1302070A-01A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p021115** | **Date of Collection: 1/31/13 1:35:00 PM** | |
| **Dil. Factor:** | **2.76** | **Date of Analysis: 2/11/13 04:39 PM** | |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 1.4 | 0.43 J | 6.8 | 2.1 J |
| Freon 114 | 1.4 | Not Detected | 9.6 | Not Detected |
| Chloromethane | 14 | Not Detected | 28 | Not Detected |
| Vinyl Chloride | 1.4 | Not Detected | 3.5 | Not Detected |
| 1,3-Butadiene | 1.4 | Not Detected | 3.0 | Not Detected |
| Bromomethane | 14 | Not Detected | 54 | Not Detected |
| Chloroethane | 5.5 | Not Detected | 14 | Not Detected |
| Freon 11 | 1.4 | 0.26 J | 7.8 | 1.4 J |
| Ethanol | 5.5 | 2.1 J | 10 | 4.0 J |
| Freon 113 | 1.4 | Not Detected | 10 | Not Detected |
| 1,1-Dichloroethene | 1.4 | Not Detected | 5.5 | Not Detected |
| Acetone | 14 | 5.6 J | 33 | 13 J |
| 2-Propanol | 5.5 | 16 | 14 | 39 |
| Carbon Disulfide | 5.5 | ~~0.69 J~~ U | 17 | ~~2.2 J~~ U |
| 3-Chloropropene | 5.5 | Not Detected | 17 | Not Detected |
| Methylene Chloride | 14 | Not Detected | 48 | Not Detected |
| Methyl tert-butyl ether | 1.4 | Not Detected | 5.0 | Not Detected |
| trans-1,2-Dichloroethene | 1.4 | Not Detected | 5.5 | Not Detected |
| Hexane | 1.4 | 0.26 J | 4.9 | 0.93 J |
| 1,1-Dichloroethane | 1.4 | Not Detected | 5.6 | Not Detected |
| 2-Butanone (Methyl Ethyl Ketone) | 5.5 | Not Detected | 16 | Not Detected |
| cis-1,2-Dichloroethene | 1.4 | Not Detected | 5.5 | Not Detected |
| Tetrahydrofuran | 1.4 | Not Detected | 4.1 | Not Detected |
| Chloroform | 1.4 | Not Detected | 6.7 | Not Detected |
| 1,1,1-Trichloroethane | 1.4 | Not Detected | 7.5 | Not Detected |
| Cyclohexane | 1.4 | Not Detected | 4.8 | Not Detected |
| Carbon Tetrachloride | 1.4 | Not Detected | 8.7 | Not Detected |
| 2,2,4-Trimethylpentane | 1.4 | 5.6 | 6.4 | 26 |
| Benzene | 1.4 | 0.82 J | 4.4 | 2.6 J |
| 1,2-Dichloroethane | 1.4 | Not Detected | 5.6 | Not Detected |
| Heptane | 1.4 | Not Detected | 5.6 | Not Detected |
| Trichloroethene | 1.4 | Not Detected | 7.4 | Not Detected |
| 1,2-Dichloropropane | 1.4 | Not Detected | 6.4 | Not Detected |
| 1,4-Dioxane | 5.5 | Not Detected | 20 | Not Detected |
| Bromodichloromethane | 1.4 | Not Detected | 9.2 | Not Detected |
| cis-1,3-Dichloropropene | 1.4 | Not Detected | 6.3 | Not Detected |
| 4-Methyl-2-pentanone | 1.4 | 0.49 J | 5.6 | 2.0 J |
| Toluene | 1.4 | ~~0.17 J~~ U | 5.2 | ~~0.64 J~~ U |
| trans-1,3-Dichloropropene | 1.4 | Not Detected | 6.3 | Not Detected |
| 1,1,2-Trichloroethane | 1.4 | Not Detected | 7.5 | Not Detected |
| Tetrachloroethene | 1.4 | ~~0.26 J~~ U | 9.4 | ~~1.8 J~~ U |
| 2-Hexanone | 5.5 | Not Detected | 23 | Not Detected |

eurofins | Air Toxics

**Client Sample ID: VMP-2-5-013113**

**Lab ID#: 1302070A-01A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p021115** | **Date of Collection:** | **1/31/13 1:35:00 PM** |
| **Dil. Factor:** | **2.76** | **Date of Analysis:** | **2/11/13 04:39 PM** |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Dibromochloromethane | 1.4 | Not Detected | 12 | Not Detected |
| 1,2-Dibromoethane (EDB) | 1.4 | Not Detected | 11 | Not Detected |
| Chlorobenzene | 1.4 | Not Detected | 6.4 | Not Detected |
| Ethyl Benzene | 1.4 | Not Detected | 6.0 | Not Detected |
| m,p-Xylene | 1.4 | Not Detected | 6.0 | Not Detected |
| o-Xylene | 1.4 | Not Detected | 6.0 | Not Detected |
| Styrene | 1.4 | Not Detected | 5.9 | Not Detected |
| Bromoform | 1.4 | Not Detected | 14 | Not Detected |
| Cumene | 1.4 | Not Detected | 6.8 | Not Detected |
| 1,1,2,2-Tetrachloroethane | 1.4 | Not Detected | 9.5 | Not Detected |
| Propylbenzene | 1.4 | ~~0.20 J~~ | 6.8 | ~~0.99 J~~ |
| 4-Ethyltoluene | 1.4 | ~~0.24 J~~ | 6.8 | ~~1.2 J~~ |
| 1,3,5-Trimethylbenzene | 1.4 | ~~0.25 J~~ | 6.8 | ~~1.2 J~~ |
| 1,2,4-Trimethylbenzene | 1.4 | ~~0.80 J~~ | 6.8 | ~~3.9 J~~ |
| 1,3-Dichlorobenzene | 1.4 | Not Detected | 8.3 | Not Detected |
| 1,4-Dichlorobenzene | 1.4 | Not Detected | 8.3 | Not Detected |
| alpha-Chlorotoluene | 1.4 | Not Detected | 7.1 | Not Detected |
| 1,2-Dichlorobenzene | 1.4 | Not Detected | 8.3 | Not Detected |
| 1,2,4-Trichlorobenzene | 5.5 | Not Detected | 41 | Not Detected |
| Hexachlorobutadiene | 5.5 | Not Detected | 59 | Not Detected |
| Butane | 5.5 | 9.9 | 13 | 23 |
| Isopentane | 5.5 | 1.5 J | 16 | 4.4 J |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| Toluene-d8 | 97 | 70-130 |
| 1,2-Dichloroethane-d4 | 86 | 70-130 |
| 4-Bromofluorobenzene | 99 | 70-130 |

eurofins | Air Toxics

**Client Sample ID: VMP-2-22-013113**

**Lab ID#: 1302070A-02A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p021114** | **Date of Collection: 1/31/13 2:47:00 PM** | |
| **Dil. Factor:** | **2.69** | **Date of Analysis: 2/11/13 04:00 PM** | |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 1.3 | 0.50 J | 6.6 | 2.5 J |
| Freon 114 | 1.3 | Not Detected | 9.4 | Not Detected |
| Chloromethane | 13 | Not Detected | 28 | Not Detected |
| Vinyl Chloride | 1.3 | Not Detected | 3.4 | Not Detected |
| 1,3-Butadiene | 1.3 | Not Detected | 3.0 | Not Detected |
| Bromomethane | 13 | Not Detected | 52 | Not Detected |
| Chloroethane | 5.4 | Not Detected | 14 | Not Detected |
| Freon 11 | 1.3 | 0.18 J | 7.6 | 1.0 J |
| Ethanol | 5.4 | 2.2 J | 10 | 4.2 J |
| Freon 113 | 1.3 | Not Detected | 10 | Not Detected |
| 1,1-Dichloroethene | 1.3 | Not Detected | 5.3 | Not Detected |
| Acetone | 13 | 4.4 J | 32 | 10 J |
| 2-Propanol | 5.4 | 2.3 J | 13 | 5.7 J |
| Carbon Disulfide | 5.4 | ~~0.64 J~~ U | 17 | ~~2.0 J~~ U |
| 3-Chloropropene | 5.4 | Not Detected | 17 | Not Detected |
| Methylene Chloride | 13 | Not Detected | 47 | Not Detected |
| Methyl tert-butyl ether | 1.3 | Not Detected | 4.8 | Not Detected |
| trans-1,2-Dichloroethene | 1.3 | Not Detected | 5.3 | Not Detected |
| Hexane | 1.3 | 0.25 J | 4.7 | 0.88 J |
| 1,1-Dichloroethane | 1.3 | Not Detected | 5.4 | Not Detected |
| 2-Butanone (Methyl Ethyl Ketone) | 5.4 | Not Detected | 16 | Not Detected |
| cis-1,2-Dichloroethene | 1.3 | Not Detected | 5.3 | Not Detected |
| Tetrahydrofuran | 1.3 | Not Detected | 4.0 | Not Detected |
| Chloroform | 1.3 | Not Detected | 6.6 | Not Detected |
| 1,1,1-Trichloroethane | 1.3 | Not Detected | 7.3 | Not Detected |
| Cyclohexane | 1.3 | Not Detected | 4.6 | Not Detected |
| Carbon Tetrachloride | 1.3 | Not Detected | 8.5 | Not Detected |
| 2,2,4-Trimethylpentane | 1.3 | 0.55 J | 6.3 | 2.6 J |
| Benzene | 1.3 | 0.56 J | 4.3 | 1.8 J |
| 1,2-Dichloroethane | 1.3 | Not Detected | 5.4 | Not Detected |
| Heptane | 1.3 | Not Detected | 5.5 | Not Detected |
| Trichloroethene | 1.3 | Not Detected | 7.2 | Not Detected |
| 1,2-Dichloropropane | 1.3 | Not Detected | 6.2 | Not Detected |
| 1,4-Dioxane | 5.4 | Not Detected | 19 | Not Detected |
| Bromodichloromethane | 1.3 | Not Detected | 9.0 | Not Detected |
| cis-1,3-Dichloropropene | 1.3 | Not Detected | 6.1 | Not Detected |
| 4-Methyl-2-pentanone | 1.3 | Not Detected | 5.5 | Not Detected |
| Toluene | 1.3 | Not Detected | 5.1 | Not Detected |
| trans-1,3-Dichloropropene | 1.3 | Not Detected | 6.1 | Not Detected |
| 1,1,2-Trichloroethane | 1.3 | Not Detected | 7.3 | Not Detected |
| Tetrachloroethene | 1.3 | 0.73 J | 9.1 | 4.9 J |
| 2-Hexanone | 5.4 | Not Detected | 22 | Not Detected |

eurofins | Air Toxics

**Client Sample ID: VMP-2-22-013113**

**Lab ID#: 1302070A-02A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p021114** | **Date of Collection:** | **1/31/13 2:47:00 PM** |
| **Dil. Factor:** | **2.69** | **Date of Analysis:** | **2/11/13 04:00 PM** |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Dibromochloromethane | 1.3 | Not Detected | 11 | Not Detected |
| 1,2-Dibromoethane (EDB) | 1.3 | Not Detected | 10 | Not Detected |
| Chlorobenzene | 1.3 | Not Detected | 6.2 | Not Detected |
| Ethyl Benzene | 1.3 | Not Detected | 5.8 | Not Detected |
| m,p-Xylene | 1.3 | Not Detected | 5.8 | Not Detected |
| o-Xylene | 1.3 | Not Detected | 5.8 | Not Detected |
| Styrene | 1.3 | Not Detected | 5.7 | Not Detected |
| Bromoform | 1.3 | Not Detected | 14 | Not Detected |
| Cumene | 1.3 | Not Detected | 6.6 | Not Detected |
| 1,1,2,2-Tetrachloroethane | 1.3 | Not Detected | 9.2 | Not Detected |
| Propylbenzene | 1.3 | Not Detected | 6.6 | Not Detected |
| 4-Ethyltoluene | 1.3 | ~~0.19 J~~ | 6.6 | ~~0.94 J~~ |
| 1,3,5-Trimethylbenzene | 1.3 | Not Detected | 6.6 | Not Detected |
| 1,2,4-Trimethylbenzene | 1.3 | Not Detected | 6.6 | Not Detected |
| 1,3-Dichlorobenzene | 1.3 | Not Detected | 8.1 | Not Detected |
| 1,4-Dichlorobenzene | 1.3 | Not Detected | 8.1 | Not Detected |
| alpha-Chlorotoluene | 1.3 | Not Detected | 7.0 | Not Detected |
| 1,2-Dichlorobenzene | 1.3 | Not Detected | 8.1 | Not Detected |
| 1,2,4-Trichlorobenzene | 5.4 | Not Detected | 40 | Not Detected |
| Hexachlorobutadiene | 5.4 | Not Detected | 57 | Not Detected |
| Butane | 5.4 | 1.8 J | 13 | 4.3 J |
| Isopentane | 5.4 | 1.5 J | 16 | 4.4 J |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| Toluene-d8 | 98 | 70-130 |
| 1,2-Dichloroethane-d4 | 85 | 70-130 |
| 4-Bromofluorobenzene | 97 | 70-130 |

eurofins | Air Toxics

**Client Sample ID: VMP-10-10-012913**

**Lab ID#: 1302070A-03A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p021113** | **Date of Collection:** | **1/29/13 10:40:00 AM** |
| **Dil. Factor:** | **2.52** | **Date of Analysis:** | **2/11/13 03:24 PM** |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 1.3 | 0.50 J | 6.2 | 2.4 J |
| Freon 114 | 1.3 | Not Detected | 8.8 | Not Detected |
| Chloromethane | 13 | Not Detected | 26 | Not Detected |
| Vinyl Chloride | 1.3 | Not Detected | 3.2 | Not Detected |
| 1,3-Butadiene | 1.3 | Not Detected | 2.8 | Not Detected |
| Bromomethane | 13 | Not Detected | 49 | Not Detected |
| Chloroethane | 5.0 | Not Detected | 13 | Not Detected |
| Freon 11 | 1.3 | 0.22 J | 7.1 | 1.2 J |
| Ethanol | 5.0 | 1.8 J | 9.5 | 3.4 J |
| Freon 113 | 1.3 | Not Detected | 9.6 | Not Detected |
| 1,1-Dichloroethene | 1.3 | Not Detected | 5.0 | Not Detected |
| Acetone | 13 | 8.4 J | 30 | 20 J |
| 2-Propanol | 5.0 | 6.0 | 12 | 15 |
| Carbon Disulfide | 5.0 | ~~0.65 J~~ U | 16 | ~~2.0 J~~ U |
| 3-Chloropropene | 5.0 | Not Detected | 16 | Not Detected |
| Methylene Chloride | 13 | 0.58 J | 44 | 2.0 J |
| Methyl tert-butyl ether | 1.3 | Not Detected | 4.5 | Not Detected |
| trans-1,2-Dichloroethene | 1.3 | Not Detected | 5.0 | Not Detected |
| Hexane | 1.3 | 0.40 J | 4.4 | 1.4 J |
| 1,1-Dichloroethane | 1.3 | Not Detected | 5.1 | Not Detected |
| 2-Butanone (Methyl Ethyl Ketone) | 5.0 | Not Detected | 15 | Not Detected |
| cis-1,2-Dichloroethene | 1.3 | Not Detected | 5.0 | Not Detected |
| Tetrahydrofuran | 1.3 | Not Detected | 3.7 | Not Detected |
| Chloroform | 1.3 | Not Detected | 6.2 | Not Detected |
| 1,1,1-Trichloroethane | 1.3 | Not Detected | 6.9 | Not Detected |
| Cyclohexane | 1.3 | Not Detected | 4.3 | Not Detected |
| Carbon Tetrachloride | 1.3 | Not Detected | 7.9 | Not Detected |
| 2,2,4-Trimethylpentane | 1.3 | 1.4 | 5.9 | 6.4 |
| Benzene | 1.3 | 5.6 | 4.0 | 18 |
| 1,2-Dichloroethane | 1.3 | Not Detected | 5.1 | Not Detected |
| Heptane | 1.3 | Not Detected | 5.2 | Not Detected |
| Trichloroethene | 1.3 | Not Detected | 6.8 | Not Detected |
| 1,2-Dichloropropane | 1.3 | Not Detected | 5.8 | Not Detected |
| 1,4-Dioxane | 5.0 | Not Detected | 18 | Not Detected |
| Bromodichloromethane | 1.3 | Not Detected | 8.4 | Not Detected |
| cis-1,3-Dichloropropene | 1.3 | Not Detected | 5.7 | Not Detected |
| 4-Methyl-2-pentanone | 1.3 | 0.27 J | 5.2 | 1.1 J |
| Toluene | 1.3 | ~~0.28 J~~ U | 4.7 | ~~1.1 J~~ U |
| trans-1,3-Dichloropropene | 1.3 | Not Detected | 5.7 | Not Detected |
| 1,1,2-Trichloroethane | 1.3 | Not Detected | 6.9 | Not Detected |
| Tetrachloroethene | 1.3 | ~~0.16 J~~ U | 8.5 | ~~1.1 J~~ U |
| 2-Hexanone | 5.0 | Not Detected | 21 | Not Detected |

eurofins | Air Toxics

**Client Sample ID: VMP-10-10-012913**

**Lab ID#: 1302070A-03A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p021113** | **Date of Collection: 1/29/13 10:40:00 AM** | |
| **Dil. Factor:** | **2.52** | **Date of Analysis: 2/11/13 03:24 PM** | |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Dibromochloromethane | 1.3 | Not Detected | 11 | Not Detected |
| 1,2-Dibromoethane (EDB) | 1.3 | Not Detected | 9.7 | Not Detected |
| Chlorobenzene | 1.3 | Not Detected | 5.8 | Not Detected |
| Ethyl Benzene | 1.3 | Not Detected | 5.5 | Not Detected |
| m,p-Xylene | 1.3 | Not Detected | 5.5 | Not Detected |
| o-Xylene | 1.3 | Not Detected | 5.5 | Not Detected |
| Styrene | 1.3 | Not Detected | 5.4 | Not Detected |
| Bromoform | 1.3 | Not Detected | 13 | Not Detected |
| Cumene | 1.3 | Not Detected | 6.2 | Not Detected |
| 1,1,2,2-Tetrachloroethane | 1.3 | Not Detected | 8.6 | Not Detected |
| Propylbenzene | 1.3 | Not Detected | 6.2 | Not Detected |
| 4-Ethyltoluene | 1.3 | Not Detected | 6.2 | Not Detected |
| 1,3,5-Trimethylbenzene | 1.3 | Not Detected | 6.2 | Not Detected |
| 1,2,4-Trimethylbenzene | 1.3 | Not Detected | 6.2 | Not Detected |
| 1,3-Dichlorobenzene | 1.3 | ~~0.17 J~~ | 7.6 | ~~1.0 J~~ |
| 1,4-Dichlorobenzene | 1.3 | Not Detected | 7.6 | Not Detected |
| alpha-Chlorotoluene | 1.3 | Not Detected | 6.5 | Not Detected |
| 1,2-Dichlorobenzene | 1.3 | Not Detected | 7.6 | Not Detected |
| 1,2,4-Trichlorobenzene | 5.0 | ~~0.49 J~~ | 37 | ~~3.7 J~~ |
| Hexachlorobutadiene | 5.0 | Not Detected | 54 | Not Detected |
| Butane | 5.0 | 1.4 J | 12 | 3.2 J |
| Isopentane | 5.0 | 1.4 J | 15 | 4.3 J |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| Toluene-d8 | 98 | 70-130 |
| 1,2-Dichloroethane-d4 | 86 | 70-130 |
| 4-Bromofluorobenzene | 102 | 70-130 |

eurofins | Air Toxics

**Client Sample ID: VMP-13-10.5-013013**

**Lab ID#: 1302070A-04A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p021112** | **Date of Collection:** | **1/30/13 10:06:00 AM** |
| **Dil. Factor:** | **2.52** | **Date of Analysis:** | **2/11/13 02:51 PM** |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 1.3 | 0.45 J | 6.2 | 2.2 J |
| Freon 114 | 1.3 | Not Detected | 8.8 | Not Detected |
| Chloromethane | 13 | Not Detected | 26 | Not Detected |
| Vinyl Chloride | 1.3 | Not Detected | 3.2 | Not Detected |
| 1,3-Butadiene | 1.3 | Not Detected | 2.8 | Not Detected |
| Bromomethane | 13 | Not Detected | 49 | Not Detected |
| Chloroethane | 5.0 | Not Detected | 13 | Not Detected |
| Freon 11 | 1.3 | 0.20 J | 7.1 | 1.1 J |
| Ethanol | 5.0 | 2.5 J | 9.5 | 4.7 J |
| Freon 113 | 1.3 | Not Detected | 9.6 | Not Detected |
| 1,1-Dichloroethene | 1.3 | Not Detected | 5.0 | Not Detected |
| Acetone | 13 | 4.2 J | 30 | 10 J |
| 2-Propanol | 5.0 | 3.9 J | 12 | 9.6 J |
| Carbon Disulfide | 5.0 | ~~0.64 J~~ U | 16 | ~~2.0 J~~ U |
| 3-Chloropropene | 5.0 | Not Detected | 16 | Not Detected |
| Methylene Chloride | 13 | Not Detected | 44 | Not Detected |
| Methyl tert-butyl ether | 1.3 | Not Detected | 4.5 | Not Detected |
| trans-1,2-Dichloroethene | 1.3 | Not Detected | 5.0 | Not Detected |
| Hexane | 1.3 | 0.33 J | 4.4 | 1.2 J |
| 1,1-Dichloroethane | 1.3 | Not Detected | 5.1 | Not Detected |
| 2-Butanone (Methyl Ethyl Ketone) | 5.0 | Not Detected | 15 | Not Detected |
| cis-1,2-Dichloroethene | 1.3 | Not Detected | 5.0 | Not Detected |
| Tetrahydrofuran | 1.3 | Not Detected | 3.7 | Not Detected |
| Chloroform | 1.3 | Not Detected | 6.2 | Not Detected |
| 1,1,1-Trichloroethane | 1.3 | Not Detected | 6.9 | Not Detected |
| Cyclohexane | 1.3 | Not Detected | 4.3 | Not Detected |
| Carbon Tetrachloride | 1.3 | Not Detected | 7.9 | Not Detected |
| 2,2,4-Trimethylpentane | 1.3 | 0.22 J | 5.9 | 1.0 J |
| Benzene | 1.3 | 0.66 J | 4.0 | 2.1 J |
| 1,2-Dichloroethane | 1.3 | Not Detected | 5.1 | Not Detected |
| Heptane | 1.3 | Not Detected | 5.2 | Not Detected |
| Trichloroethene | 1.3 | Not Detected | 6.8 | Not Detected |
| 1,2-Dichloropropane | 1.3 | Not Detected | 5.8 | Not Detected |
| 1,4-Dioxane | 5.0 | Not Detected | 18 | Not Detected |
| Bromodichloromethane | 1.3 | Not Detected | 8.4 | Not Detected |
| cis-1,3-Dichloropropene | 1.3 | Not Detected | 5.7 | Not Detected |
| 4-Methyl-2-pentanone | 1.3 | Not Detected | 5.2 | Not Detected |
| Toluene | 1.3 | ~~0.16 J~~ U | 4.7 | ~~0.67 J~~ U |
| trans-1,3-Dichloropropene | 1.3 | Not Detected | 5.7 | Not Detected |
| 1,1,2-Trichloroethane | 1.3 | Not Detected | 6.9 | Not Detected |
| Tetrachloroethene | 1.3 | ~~0.16 J~~ U | 8.5 | ~~1.0 J~~ U |
| 2-Hexanone | 5.0 | Not Detected | 21 | Not Detected |

eurofins | Air Toxics

**Client Sample ID: VMP-13-10.5-013013**

**Lab ID#: 1302070A-04A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p021112** | **Date of Collection: 1/30/13 10:06:00 AM** | |
| **Dil. Factor:** | **2.52** | **Date of Analysis: 2/11/13 02:51 PM** | |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Dibromochloromethane | 1.3 | Not Detected | 11 | Not Detected |
| 1,2-Dibromoethane (EDB) | 1.3 | Not Detected | 9.7 | Not Detected |
| Chlorobenzene | 1.3 | Not Detected | 5.8 | Not Detected |
| Ethyl Benzene | 1.3 | Not Detected | 5.5 | Not Detected |
| m,p-Xylene | 1.3 | Not Detected | 5.5 | Not Detected |
| o-Xylene | 1.3 | Not Detected | 5.5 | Not Detected |
| Styrene | 1.3 | Not Detected | 5.4 | Not Detected |
| Bromoform | 1.3 | Not Detected | 13 | Not Detected |
| Cumene | 1.3 | Not Detected | 6.2 | Not Detected |
| 1,1,2,2-Tetrachloroethane | 1.3 | Not Detected | 8.6 | Not Detected |
| Propylbenzene | 1.3 | Not Detected | 6.2 | Not Detected |
| 4-Ethyltoluene | 1.3 | ~~0.16 J~~ | 6.2 | ~~0.78 J~~ |
| 1,3,5-Trimethylbenzene | 1.3 | Not Detected | 6.2 | Not Detected |
| 1,2,4-Trimethylbenzene | 1.3 | Not Detected | 6.2 | Not Detected |
| 1,3-Dichlorobenzene | 1.3 | Not Detected | 7.6 | Not Detected |
| 1,4-Dichlorobenzene | 1.3 | Not Detected | 7.6 | Not Detected |
| alpha-Chlorotoluene | 1.3 | Not Detected | 6.5 | Not Detected |
| 1,2-Dichlorobenzene | 1.3 | Not Detected | 7.6 | Not Detected |
| 1,2,4-Trichlorobenzene | 5.0 | ~~0.42 J~~ | 37 | ~~3.1 J~~ |
| Hexachlorobutadiene | 5.0 | Not Detected | 54 | Not Detected |
| Butane | 5.0 | Not Detected | 12 | Not Detected |
| Isopentane | 5.0 | 0.82 J | 15 | 2.4 J |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| Toluene-d8 | 97 | 70-130 |
| 1,2-Dichloroethane-d4 | 86 | 70-130 |
| 4-Bromofluorobenzene | 99 | 70-130 |

eurofins | Air Toxics

**Client Sample ID: VMP-13-21.5-013013**

**Lab ID#: 1302070A-05A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p021111** | **Date of Collection:** | **1/30/13 11:11:00 AM** |
| **Dil. Factor:** | **2.96** | **Date of Analysis:** | **2/11/13 02:19 PM** |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 1.5 | 0.44 J | 7.3 | 2.2 J |
| Freon 114 | 1.5 | Not Detected | 10 | Not Detected |
| Chloromethane | 15 | Not Detected | 30 | Not Detected |
| Vinyl Chloride | 1.5 | Not Detected | 3.8 | Not Detected |
| 1,3-Butadiene | 1.5 | Not Detected | 3.3 | Not Detected |
| Bromomethane | 15 | Not Detected | 57 | Not Detected |
| Chloroethane | 5.9 | Not Detected | 16 | Not Detected |
| Freon 11 | 1.5 | 0.18 J | 8.3 | 1.0 J |
| Ethanol | 5.9 | 2.7 J | 11 | 5.1 J |
| Freon 113 | 1.5 | Not Detected | 11 | Not Detected |
| 1,1-Dichloroethene | 1.5 | Not Detected | 5.9 | Not Detected |
| Acetone | 15 | 4.3 J | 35 | 10 J |
| 2-Propanol | 5.9 | 6.2 | 14 | 15 |
| Carbon Disulfide | 5.9 | 2.5 J | 18 | 7.8 J |
| 3-Chloropropene | 5.9 | Not Detected | 18 | Not Detected |
| Methylene Chloride | 15 | ~~0.28 J~~ U | 51 | ~~0.98 J~~ U |
| Methyl tert-butyl ether | 1.5 | Not Detected | 5.3 | Not Detected |
| trans-1,2-Dichloroethene | 1.5 | Not Detected | 5.9 | Not Detected |
| Hexane | 1.5 | 0.32 J | 5.2 | 1.1 J |
| 1,1-Dichloroethane | 1.5 | Not Detected | 6.0 | Not Detected |
| 2-Butanone (Methyl Ethyl Ketone) | 5.9 | Not Detected | 17 | Not Detected |
| cis-1,2-Dichloroethene | 1.5 | Not Detected | 5.9 | Not Detected |
| Tetrahydrofuran | 1.5 | Not Detected | 4.4 | Not Detected |
| Chloroform | 1.5 | 17 | 7.2 | 82 |
| 1,1,1-Trichloroethane | 1.5 | Not Detected | 8.1 | Not Detected |
| Cyclohexane | 1.5 | Not Detected | 5.1 | Not Detected |
| Carbon Tetrachloride | 1.5 | Not Detected | 9.3 | Not Detected |
| 2,2,4-Trimethylpentane | 1.5 | 1.2 J | 6.9 | 5.7 J |
| Benzene | 1.5 | 2.7 | 4.7 | 8.8 |
| 1,2-Dichloroethane | 1.5 | Not Detected | 6.0 | Not Detected |
| Heptane | 1.5 | Not Detected | 6.1 | Not Detected |
| Trichloroethene | 1.5 | Not Detected | 8.0 | Not Detected |
| 1,2-Dichloropropane | 1.5 | Not Detected | 6.8 | Not Detected |
| 1,4-Dioxane | 5.9 | Not Detected | 21 | Not Detected |
| Bromodichloromethane | 1.5 | Not Detected | 9.9 | Not Detected |
| cis-1,3-Dichloropropene | 1.5 | Not Detected | 6.7 | Not Detected |
| 4-Methyl-2-pentanone | 1.5 | 0.39 J | 6.1 | 1.6 J |
| Toluene | 1.5 | ~~0.17 J~~ U | 5.6 | ~~0.63 J~~ U |
| trans-1,3-Dichloropropene | 1.5 | Not Detected | 6.7 | Not Detected |
| 1,1,2-Trichloroethane | 1.5 | Not Detected | 8.1 | Not Detected |
| Tetrachloroethene | 1.5 | ~~0.30 J~~ U | 10 | ~~2.0 J~~ V |
| 2-Hexanone | 5.9 | Not Detected | 24 | Not Detected |

eurofins | Air Toxics

**Client Sample ID: VMP-13-21.5-013013**

**Lab ID#: 1302070A-05A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p021111** | **Date of Collection:** | **1/30/13 11:11:00 AM** |
| **Dil. Factor:** | **2.96** | **Date of Analysis:** | **2/11/13 02:19 PM** |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Dibromochloromethane | 1.5 | Not Detected | 13 | Not Detected |
| 1,2-Dibromoethane (EDB) | 1.5 | Not Detected | 11 | Not Detected |
| Chlorobenzene | 1.5 | Not Detected | 6.8 | Not Detected |
| Ethyl Benzene | 1.5 | Not Detected | 6.4 | Not Detected |
| m,p-Xylene | 1.5 | Not Detected | 6.4 | Not Detected |
| o-Xylene | 1.5 | Not Detected | 6.4 | Not Detected |
| Styrene | 1.5 | Not Detected | 6.3 | Not Detected |
| Bromoform | 1.5 | Not Detected | 15 | Not Detected |
| Cumene | 1.5 | Not Detected | 7.3 | Not Detected |
| 1,1,2,2-Tetrachloroethane | 1.5 | Not Detected | 10 | Not Detected |
| Propylbenzene | 1.5 | Not Detected | 7.3 | Not Detected |
| 4-Ethyltoluene | 1.5 | ~~0.14 J~~ | ~~7.3~~ JK (AA) | ~~0.68 J~~ |
| 1,3,5-Trimethylbenzene | 1.5 | Not Detected | 7.3 | Not Detected |
| 1,2,4-Trimethylbenzene | 1.5 | Not Detected | 7.3 | Not Detected |
| 1,3-Dichlorobenzene | 1.5 | ~~0.26 J~~ | 8.9 | ~~1.6 J~~ |
| 1,4-Dichlorobenzene | 1.5 | ~~0.27 J~~ | 8.9 | ~~1.6 J~~ |
| alpha-Chlorotoluene | 1.5 | Not Detected | 7.7 | Not Detected |
| 1,2-Dichlorobenzene | 1.5 | Not Detected | 8.9 | Not Detected |
| 1,2,4-Trichlorobenzene | 5.9 | ~~0.75 J~~ | 44 | ~~5.6 J~~ |
| Hexachlorobutadiene | 5.9 | Not Detected | 63 | Not Detected |
| Butane | 5.9 | Not Detected | 14 | Not Detected |
| Isopentane | 5.9 | Not Detected | 17 | Not Detected |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| Toluene-d8 | 97 | 70-130 |
| 1,2-Dichloroethane-d4 | 83 | 70-130 |
| 4-Bromofluorobenzene | 102 | 70-130 |

eurofins | Air Toxics

**Client Sample ID: VMP-14-5-013113**

**Lab ID#: 1302070A-06A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p021110** | **Date of Collection:** | **1/31/13 10:03:00 AM** |
| **Dil. Factor:** | **2.69** | **Date of Analysis:** | **2/11/13 01:33 PM** |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 1.3 | 0.49 J | 6.6 | 2.4 J |
| Freon 114 | 1.3 | Not Detected | 9.4 | Not Detected |
| Chloromethane | 13 | Not Detected | 28 | Not Detected |
| Vinyl Chloride | 1.3 | Not Detected | 3.4 | Not Detected |
| 1,3-Butadiene | 1.3 | Not Detected | 3.0 | Not Detected |
| Bromomethane | 13 | Not Detected | 52 | Not Detected |
| Chloroethane | 5.4 | Not Detected | 14 | Not Detected |
| Freon 11 | 1.3 | 0.21 J | 7.6 | 1.2 J |
| Ethanol | 5.4 | 0.96 J | 10 | 1.8 J |
| Freon 113 | 1.3 | Not Detected | 10 | Not Detected |
| 1,1-Dichloroethene | 1.3 | Not Detected | 5.3 | Not Detected |
| Acetone | 13 | 4.2 J | 32 | 10 J |
| 2-Propanol | 5.4 | 0.91 J | 13 | 2.2 J |
| Carbon Disulfide | 5.4 | ~~0.69 J~~ U | 17 | ~~2.2 J~~ U |
| 3-Chloropropene | 5.4 | Not Detected | 17 | Not Detected |
| Methylene Chloride | 13 | ~~0.18 J~~ U | 47 | ~~0.62 J~~ U |
| Methyl tert-butyl ether | 1.3 | Not Detected | 4.8 | Not Detected |
| trans-1,2-Dichloroethene | 1.3 | Not Detected | 5.3 | Not Detected |
| Hexane | 1.3 | Not Detected | 4.7 | Not Detected |
| 1,1-Dichloroethane | 1.3 | Not Detected | 5.4 | Not Detected |
| 2-Butanone (Methyl Ethyl Ketone) | 5.4 | Not Detected | 16 | Not Detected |
| cis-1,2-Dichloroethene | 1.3 | Not Detected | 5.3 | Not Detected |
| Tetrahydrofuran | 1.3 | Not Detected | 4.0 | Not Detected |
| Chloroform | 1.3 | Not Detected | 6.6 | Not Detected |
| 1,1,1-Trichloroethane | 1.3 | Not Detected | 7.3 | Not Detected |
| Cyclohexane | 1.3 | Not Detected | 4.6 | Not Detected |
| Carbon Tetrachloride | 1.3 | Not Detected | 8.5 | Not Detected |
| 2,2,4-Trimethylpentane | 1.3 | 0.51 J | 6.3 | 2.4 J |
| Benzene | 1.3 | Not Detected | 4.3 | Not Detected |
| 1,2-Dichloroethane | 1.3 | Not Detected | 5.4 | Not Detected |
| Heptane | 1.3 | Not Detected | 5.5 | Not Detected |
| Trichloroethene | 1.3 | Not Detected | 7.2 | Not Detected |
| 1,2-Dichloropropane | 1.3 | Not Detected | 6.2 | Not Detected |
| 1,4-Dioxane | 5.4 | Not Detected | 19 | Not Detected |
| Bromodichloromethane | 1.3 | Not Detected | 9.0 | Not Detected |
| cis-1,3-Dichloropropene | 1.3 | Not Detected | 6.1 | Not Detected |
| 4-Methyl-2-pentanone | 1.3 | Not Detected | 5.5 | Not Detected |
| Toluene | 1.3 | ~~0.17 J~~ U | 5.1 | ~~0.64 J~~ U |
| trans-1,3-Dichloropropene | 1.3 | Not Detected | 6.1 | Not Detected |
| 1,1,2-Trichloroethane | 1.3 | Not Detected | 7.3 | Not Detected |
| Tetrachloroethene | 1.3 | ~~0.17 J~~ U | 9.1 | ~~1.1 J~~ U |
| 2-Hexanone | 5.4 | Not Detected | 22 | Not Detected |

eurofins | Air Toxics

**Client Sample ID: VMP-14-5-013113**

**Lab ID#: 1302070A-06A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p021110** | **Date of Collection:** | **1/31/13 10:03:00 AM** |
| **Dil. Factor:** | **2.69** | **Date of Analysis:** | **2/11/13 01:33 PM** |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Dibromochloromethane | 1.3 | Not Detected | 11 | Not Detected |
| 1,2-Dibromoethane (EDB) | 1.3 | Not Detected | 10 | Not Detected |
| Chlorobenzene | 1.3 | Not Detected | 6.2 | Not Detected |
| Ethyl Benzene | 1.3 | Not Detected | 5.8 | Not Detected |
| m,p-Xylene | 1.3 | Not Detected | 5.8 | Not Detected |
| o-Xylene | 1.3 | Not Detected | 5.8 | Not Detected |
| Styrene | 1.3 | Not Detected | 5.7 | Not Detected |
| Bromoform | 1.3 | Not Detected | 14 | Not Detected |
| Cumene | 1.3 | ~~0.15 J~~ | 6.6 | ~~0.76 J~~ |
| 1,1,2,2-Tetrachloroethane | 1.3 | Not Detected | 9.2 | Not Detected |
| Propylbenzene | 1.3 | ~~0.29 J~~ | 6.6 | ~~1.4 J~~ |
| 4-Ethyltoluene | 1.3 | Not Detected | 6.6 | Not Detected |
| 1,3,5-Trimethylbenzene | 1.3 | Not Detected | 6.6 | Not Detected |
| 1,2,4-Trimethylbenzene | 1.3 | Not Detected | 6.6 | Not Detected |
| 1,3-Dichlorobenzene | 1.3 | ~~0.18 J~~ | 8.1 | ~~1.1 J~~ |
| 1,4-Dichlorobenzene | 1.3 | ~~0.27 J~~ | 8.1 | ~~1.6 J~~ |
| alpha-Chlorotoluene | 1.3 | Not Detected | 7.0 | Not Detected |
| 1,2-Dichlorobenzene | 1.3 | Not Detected | 8.1 | Not Detected |
| 1,2,4-Trichlorobenzene | 5.4 | ~~1.5 J~~ | 40 | ~~11 J~~ |
| Hexachlorobutadiene | 5.4 | Not Detected | 57 | Not Detected |
| Butane | 5.4 | 1.8 J | 13 | 4.4 J |
| Isopentane | 5.4 | 0.59 J | 16 | 1.7 J |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| Toluene-d8 | 99 | 70-130 |
| 1,2-Dichloroethane-d4 | 87 | 70-130 |
| 4-Bromofluorobenzene | 106 | 70-130 |

eurofins | Air Toxics

**Client Sample ID: VMP-14-11.5-013113**

**Lab ID#: 1302070A-07A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p021109** | **Date of Collection:** | **1/31/13 10:45:00 AM** |
| **Dil. Factor:** | **2.58** | **Date of Analysis:** | **2/11/13 12:52 PM** |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 1.3 | 0.56 J | 6.4 | 2.8 J |
| Freon 114 | 1.3 | Not Detected | 9.0 | Not Detected |
| Chloromethane | 13 | Not Detected | 27 | Not Detected |
| Vinyl Chloride | 1.3 | Not Detected | 3.3 | Not Detected |
| 1,3-Butadiene | 1.3 | Not Detected | 2.8 | Not Detected |
| Bromomethane | 13 | Not Detected | 50 | Not Detected |
| Chloroethane | 5.2 | Not Detected | 14 | Not Detected |
| Freon 11 | 1.3 | 0.29 J | 7.2 | 1.6 J |
| Ethanol | 5.2 | 0.74 J | 9.7 | 1.4 J |
| Freon 113 | 1.3 | Not Detected | 9.9 | Not Detected |
| 1,1-Dichloroethene | 1.3 | Not Detected | 5.1 | Not Detected |
| Acetone | 13 | 3.4 J | 31 | 8.2 J |
| 2-Propanol | 5.2 | 0.73 J | 13 | 1.8 J |
| Carbon Disulfide | 5.2 | ~~0.87 J~~ U | 16 | ~~2.7 J~~ U |
| 3-Chloropropene | 5.2 | Not Detected | 16 | Not Detected |
| Methylene Chloride | 13 | Not Detected | 45 | Not Detected |
| Methyl tert-butyl ether | 1.3 | Not Detected | 4.6 | Not Detected |
| trans-1,2-Dichloroethene | 1.3 | Not Detected | 5.1 | Not Detected |
| Hexane | 1.3 | 0.41 J | 4.5 | 1.4 J |
| 1,1-Dichloroethane | 1.3 | Not Detected | 5.2 | Not Detected |
| 2-Butanone (Methyl Ethyl Ketone) | 5.2 | Not Detected | 15 | Not Detected |
| cis-1,2-Dichloroethene | 1.3 | Not Detected | 5.1 | Not Detected |
| Tetrahydrofuran | 1.3 | Not Detected | 3.8 | Not Detected |
| Chloroform | 1.3 | 1.9 | 6.3 | 9.4 |
| 1,1,1-Trichloroethane | 1.3 | Not Detected | 7.0 | Not Detected |
| Cyclohexane | 1.3 | Not Detected | 4.4 | Not Detected |
| Carbon Tetrachloride | 1.3 | Not Detected | 8.1 | Not Detected |
| 2,2,4-Trimethylpentane | 1.3 | 1.0 J | 6.0 | 4.7 J |
| Benzene | 1.3 | Not Detected | 4.1 | Not Detected |
| 1,2-Dichloroethane | 1.3 | Not Detected | 5.2 | Not Detected |
| Heptane | 1.3 | Not Detected | 5.3 | Not Detected |
| Trichloroethene | 1.3 | Not Detected | 6.9 | Not Detected |
| 1,2-Dichloropropane | 1.3 | Not Detected | 6.0 | Not Detected |
| 1,4-Dioxane | 5.2 | Not Detected | 18 | Not Detected |
| Bromodichloromethane | 1.3 | Not Detected | 8.6 | Not Detected |
| cis-1,3-Dichloropropene | 1.3 | Not Detected | 5.8 | Not Detected |
| 4-Methyl-2-pentanone | 1.3 | Not Detected | 5.3 | Not Detected |
| Toluene | 1.3 | ~~0.24 J~~ U | 4.9 | ~~0.89 J~~ U |
| trans-1,3-Dichloropropene | 1.3 | Not Detected | 5.8 | Not Detected |
| 1,1,2-Trichloroethane | 1.3 | Not Detected | 7.0 | Not Detected |
| Tetrachloroethene | 1.3 | ~~0.16 J~~ U | 8.8 | ~~1.1 J~~ U |
| 2-Hexanone | 5.2 | Not Detected | 21 | Not Detected |

eurofins | Air Toxics

**Client Sample ID: VMP-14-11.5-013113**

**Lab ID#: 1302070A-07A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p021109** | **Date of Collection: 1/31/13 10:45:00 AM** | |
| **Dil. Factor:** | **2.58** | **Date of Analysis: 2/11/13 12:52 PM** | |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Dibromochloromethane | 1.3 | Not Detected | 11 | Not Detected |
| 1,2-Dibromoethane (EDB) | 1.3 | Not Detected | 9.9 | Not Detected |
| Chlorobenzene | 1.3 | ~~0.17 J~~ | 5.9 | ~~0.80 J~~ |
| Ethyl Benzene | 1.3 | Not Detected | 5.6 | Not Detected |
| m,p-Xylene | 1.3 | Not Detected | 5.6 | Not Detected |
| o-Xylene | 1.3 | Not Detected | 5.6 | Not Detected |
| Styrene | 1.3 | Not Detected | 5.5 | Not Detected |
| Bromoform | 1.3 | Not Detected | 13 | Not Detected |
| Cumene | 1.3 | Not Detected | 6.3 | Not Detected |
| 1,1,2,2-Tetrachloroethane | 1.3 | Not Detected | 8.8 | Not Detected |
| Propylbenzene | 1.3 | ~~0.20 J~~ | 6.3 | ~~0.97 J~~ |
| 4-Ethyltoluene | 1.3 | ~~0.14 J~~ | 6.3 | ~~0.67 J~~ |
| 1,3,5-Trimethylbenzene | 1.3 | Not Detected | 6.3 | Not Detected |
| 1,2,4-Trimethylbenzene | 1.3 | Not Detected | 6.3 | Not Detected |
| 1,3-Dichlorobenzene | 1.3 | ~~0.40 J~~ | 7.8 | ~~2.4 J~~ |
| 1,4-Dichlorobenzene | 1.3 | ~~0.43 J~~ | 7.8 | ~~2.6 J~~ |
| alpha-Chlorotoluene | 1.3 | ~~0.30 J~~ | 6.7 | ~~1.6 J~~ |
| 1,2-Dichlorobenzene | 1.3 | ~~0.35 J~~ | 7.8 | ~~2.1 J~~ |
| 1,2,4-Trichlorobenzene | 5.2 | ~~1.1 J~~ | 38 | ~~8.0 J~~ |
| Hexachlorobutadiene | 5.2 | Not Detected | 55 | Not Detected |
| Butane | 5.2 | Not Detected | 12 | Not Detected |
| Isopentane | 5.2 | 0.97 J | 15 | 2.9 J |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| Toluene-d8 | 96 | 70-130 |
| 1,2-Dichloroethane-d4 | 89 | 70-130 |
| 4-Bromofluorobenzene | 97 | 70-130 |

eurofins | Air Toxics

**Client Sample ID: VMP-17-5-013113**

**Lab ID#: 1302070A-08A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | p021107 | **Date of Collection:** | 1/31/13 3:34:00 PM |
| **Dil. Factor:** | 10.6 | **Date of Analysis:** | 2/11/13 11:35 AM |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 5.3 | Not Detected | 26 | Not Detected |
| Freon 114 | 5.3 | Not Detected | 37 | Not Detected |
| Chloromethane | 53 | Not Detected | 110 | Not Detected |
| Vinyl Chloride | 5.3 | Not Detected | 14 | Not Detected |
| 1,3-Butadiene | 5.3 | Not Detected | 12 | Not Detected |
| Bromomethane | 53 | Not Detected | 200 | Not Detected |
| Chloroethane | 21 | Not Detected | 56 | Not Detected |
| Freon 11 | 5.3 | Not Detected | 30 | Not Detected |
| Ethanol | 21 | Not Detected | 40 | Not Detected |
| Freon 113 | 5.3 | Not Detected | 41 | Not Detected |
| 1,1-Dichloroethene | 5.3 | Not Detected | 21 | Not Detected |
| Acetone | 53 | 4.6 J | 120 | 11 J |
| 2-Propanol | 21 | 2.6 J | 52 | 6.5 J |
| Carbon Disulfide | 21 | 2.4 J | 66 | 7.6 J |
| 3-Chloropropene | 21 | Not Detected | 66 | Not Detected |
| Methylene Chloride | 53 | Not Detected | 180 | Not Detected |
| Methyl tert-butyl ether | 5.3 | Not Detected | 19 | Not Detected |
| trans-1,2-Dichloroethene | 5.3 | Not Detected | 21 | Not Detected |
| Hexane | 5.3 | 1.8 J | 19 | 6.5 J |
| 1,1-Dichloroethane | 5.3 | Not Detected | 21 | Not Detected |
| 2-Butanone (Methyl Ethyl Ketone) | 21 | Not Detected | 62 | Not Detected |
| cis-1,2-Dichloroethene | 5.3 | Not Detected | 21 | Not Detected |
| Tetrahydrofuran | 5.3 | Not Detected | 16 | Not Detected |
| Chloroform | 5.3 | Not Detected | 26 | Not Detected |
| 1,1,1-Trichloroethane | 5.3 | Not Detected | 29 | Not Detected |
| Cyclohexane | 5.3 | 2.8 J | 18 | 9.7 J |
| Carbon Tetrachloride | 5.3 | Not Detected | 33 | Not Detected |
| 2,2,4-Trimethylpentane | 5.3 | 3.8 J | 25 | 18 J |
| Benzene | 5.3 | 220 | 17 | 710 |
| 1,2-Dichloroethane | 5.3 | Not Detected | 21 | Not Detected |
| Heptane | 5.3 | Not Detected | 22 | Not Detected |
| Trichloroethene | 5.3 | Not Detected | 28 | Not Detected |
| 1,2-Dichloropropane | 5.3 | Not Detected | 24 | Not Detected |
| 1,4-Dioxane | 21 | Not Detected | 76 | Not Detected |
| Bromodichloromethane | 5.3 | Not Detected | 36 | Not Detected |
| cis-1,3-Dichloropropene | 5.3 | Not Detected | 24 | Not Detected |
| 4-Methyl-2-pentanone | 5.3 | Not Detected | 22 | Not Detected |
| Toluene | 5.3 | 0.75 J | 20 | 2.8 J |
| trans-1,3-Dichloropropene | 5.3 | Not Detected | 24 | Not Detected |
| 1,1,2-Trichloroethane | 5.3 | Not Detected | 29 | Not Detected |
| Tetrachloroethene | 5.3 | Not Detected | 36 | Not Detected |
| 2-Hexanone | 21 | Not Detected | 87 | Not Detected |

eurofins | Air Toxics

**Client Sample ID: VMP-17-5-013113**

**Lab ID#: 1302070A-08A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p021107** | **Date of Collection:** | **1/31/13 3:34:00 PM** |
| **Dil. Factor:** | **10.6** | **Date of Analysis:** | **2/11/13 11:35 AM** |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Dibromochloromethane | 5.3 | Not Detected | 45 | Not Detected |
| 1,2-Dibromoethane (EDB) | 5.3 | Not Detected | 41 | Not Detected |
| Chlorobenzene | 5.3 | Not Detected | 24 | Not Detected |
| Ethyl Benzene | 5.3 | 1.1 J | 23 | 4.7 J |
| m,p-Xylene | 5.3 | 1.6 J | 23 | 6.8 J |
| o-Xylene | 5.3 | Not Detected | 23 | Not Detected |
| Styrene | 5.3 | Not Detected | 22 | Not Detected |
| Bromoform | 5.3 | Not Detected | 55 | Not Detected |
| Cumene | 5.3 | 2.4 J | 26 | 12 J |
| 1,1,2,2-Tetrachloroethane | 5.3 | Not Detected | 36 | Not Detected |
| Propylbenzene | 5.3 | 1.3 J | 26 | 6.2 J |
| 4-Ethyltoluene | 5.3 | 1.9 J | 26 | 9.6 J |
| 1,3,5-Trimethylbenzene | 5.3 | Not Detected | 26 | Not Detected |
| 1,2,4-Trimethylbenzene | 5.3 | 1.8 J | 26 | 9.1 J |
| 1,3-Dichlorobenzene | 5.3 | Not Detected | 32 | Not Detected |
| 1,4-Dichlorobenzene | 5.3 | Not Detected | 32 | Not Detected |
| alpha-Chlorotoluene | 5.3 | Not Detected | 27 | Not Detected |
| 1,2-Dichlorobenzene | 5.3 | Not Detected | 32 | Not Detected |
| 1,2,4-Trichlorobenzene | 21 | ~~3.3 J~~ U | 160 | ~~24 J~~ U |
| Hexachlorobutadiene | 21 | Not Detected | 230 | Not Detected |
| Butane | 21 | Not Detected | 50 | Not Detected |
| Isopentane | 21 | 12 J | 62 | 36 J |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| Toluene-d8 | 103 | 70-130 |
| 1,2-Dichloroethane-d4 | 94 | 70-130 |
| 4-Bromofluorobenzene | 99 | 70-130 |

eurofins | Air Toxics

**Client Sample ID: VMP-17-5-013113-DUP**

**Lab ID#: 1302070A-09A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p021116** | **Date of Collection:** | **1/31/13 3:34:00 PM** |
| **Dil. Factor:** | **10.6** | **Date of Analysis:** | **2/11/13 05:08 PM** |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 5.3 | Not Detected | 26 | Not Detected |
| Freon 114 | 5.3 | Not Detected | 37 | Not Detected |
| Chloromethane | 53 | Not Detected | 110 | Not Detected |
| Vinyl Chloride | 5.3 | Not Detected | 14 | Not Detected |
| 1,3-Butadiene | 5.3 | Not Detected | 12 | Not Detected |
| Bromomethane | 53 | Not Detected | 200 | Not Detected |
| Chloroethane | 21 | Not Detected | 56 | Not Detected |
| Freon 11 | 5.3 | Not Detected | 30 | Not Detected |
| Ethanol | 21 | Not Detected | 40 | Not Detected |
| Freon 113 | 5.3 | Not Detected | 41 | Not Detected |
| 1,1-Dichloroethene | 5.3 | Not Detected | 21 | Not Detected |
| Acetone | 53 | 4.0 J | 120 | 9.6 J |
| 2-Propanol | 21 | Not Detected | 52 | Not Detected |
| Carbon Disulfide | 21 | 2.2 J | 66 | 7.0 J |
| 3-Chloropropene | 21 | Not Detected | 66 | Not Detected |
| Methylene Chloride | 53 | Not Detected | 180 | Not Detected |
| Methyl tert-butyl ether | 5.3 | Not Detected | 19 | Not Detected |
| trans-1,2-Dichloroethene | 5.3 | Not Detected | 21 | Not Detected |
| Hexane | 5.3 | 4.3 J | 19 | 15 J |
| 1,1-Dichloroethane | 5.3 | Not Detected | 21 | Not Detected |
| 2-Butanone (Methyl Ethyl Ketone) | 21 | Not Detected | 62 | Not Detected |
| cis-1,2-Dichloroethene | 5.3 | Not Detected | 21 | Not Detected |
| Tetrahydrofuran | 5.3 | Not Detected | 16 | Not Detected |
| Chloroform | 5.3 | Not Detected | 26 | Not Detected |
| 1,1,1-Trichloroethane | 5.3 | Not Detected | 29 | Not Detected |
| Cyclohexane | 5.3 | 4.3 J | 18 | 15 J |
| Carbon Tetrachloride | 5.3 | Not Detected | 33 | Not Detected |
| 2,2,4-Trimethylpentane | 5.3 | 3.4 J | 25 | 16 J |
| Benzene | 5.3 | 330 | 17 | 1000 |
| 1,2-Dichloroethane | 5.3 | Not Detected | 21 | Not Detected |
| Heptane | 5.3 | 1.5 J | 22 | 6.3 J |
| Trichloroethene | 5.3 | Not Detected | 28 | Not Detected |
| 1,2-Dichloropropane | 5.3 | Not Detected | 24 | Not Detected |
| 1,4-Dioxane | 21 | Not Detected | 76 | Not Detected |
| Bromodichloromethane | 5.3 | Not Detected | 36 | Not Detected |
| cis-1,3-Dichloropropene | 5.3 | Not Detected | 24 | Not Detected |
| 4-Methyl-2-pentanone | 5.3 | Not Detected | 22 | Not Detected |
| Toluene | 5.3 | ~~6.39 J~~ | 20 | ~~1.5 J~~ |
| trans-1,3-Dichloropropene | 5.3 | Not Detected | 24 | Not Detected |
| 1,1,2-Trichloroethane | 5.3 | Not Detected | 29 | Not Detected |
| Tetrachloroethene | 5.3 | Not Detected | 36 | Not Detected |
| 2-Hexanone | 21 | Not Detected | 87 | Not Detected |

eurofins | Air Toxics

**Client Sample ID: VMP-17-5-013113-DUP**

**Lab ID#: 1302070A-09A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p021116** | **Date of Collection: 1/31/13 3:34:00 PM** | |
| **Dil. Factor:** | **10.6** | **Date of Analysis: 2/11/13 05:08 PM** | |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Dibromochloromethane | 5.3 | Not Detected | 45 | Not Detected |
| 1,2-Dibromoethane (EDB) | 5.3 | Not Detected | 41 | Not Detected |
| Chlorobenzene | 5.3 | Not Detected | 24 | Not Detected |
| Ethyl Benzene | 5.3 | Not Detected | 23 | Not Detected |
| m,p-Xylene | 5.3 | Not Detected | 23 | Not Detected |
| o-Xylene | 5.3 | Not Detected | 23 | Not Detected |
| Styrene | 5.3 | Not Detected | 22 | Not Detected |
| Bromoform | 5.3 | Not Detected | 55 | Not Detected |
| Cumene | 5.3 | 1.4 J | 26 | 6.8 J |
| 1,1,2,2-Tetrachloroethane | 5.3 | Not Detected | 36 | Not Detected |
| Propylbenzene | 5.3 | ~~0.70 J~~ | 26 | ~~3.5 J~~ |
| 4-Ethyltoluene | 5.3 | 1.1 J | 26 | 5.5 J |
| 1,3,5-Trimethylbenzene | 5.3 | Not Detected | 26 | Not Detected |
| 1,2,4-Trimethylbenzene | 5.3 | Not Detected | 26 | Not Detected |
| 1,3-Dichlorobenzene | 5.3 | Not Detected | 32 | Not Detected |
| 1,4-Dichlorobenzene | 5.3 | Not Detected | 32 | Not Detected |
| alpha-Chlorotoluene | 5.3 | Not Detected | 27 | Not Detected |
| 1,2-Dichlorobenzene | 5.3 | Not Detected | 32 | Not Detected |
| 1,2,4-Trichlorobenzene | 21 | Not Detected | 160 | Not Detected |
| Hexachlorobutadiene | 21 | Not Detected | 230 | Not Detected |
| Butane | 21 | 16 J | 50 | 39 J |
| Isopentane | 21 | 45 | 62 | 130 |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| Toluene-d8 | 97 | 70-130 |
| 1,2-Dichloroethane-d4 | 83 | 70-130 |
| 4-Bromofluorobenzene | 98 | 70-130 |

eurofins | Air Toxics

**Client Sample ID: VMP-19-5-013113**

**Lab ID#: 1302070A-10A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p021117** | **Date of Collection:** | **1/31/13 4:26:00 PM** |
| **Dil. Factor:** | **2.58** | **Date of Analysis:** | **2/11/13 05:44 PM** |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 1.3 | 0.46 J | 6.4 | 2.3 J |
| Freon 114 | 1.3 | Not Detected | 9.0 | Not Detected |
| Chloromethane | 13 | Not Detected | 27 | Not Detected |
| Vinyl Chloride | 1.3 | Not Detected | 3.3 | Not Detected |
| 1,3-Butadiene | 1.3 | Not Detected | 2.8 | Not Detected |
| Bromomethane | 13 | Not Detected | 50 | Not Detected |
| Chloroethane | 5.2 | Not Detected | 14 | Not Detected |
| Freon 11 | 1.3 | 0.21 J | 7.2 | 1.2 J |
| Ethanol | 5.2 | 12 | 9.7 | 22 |
| Freon 113 | 1.3 | Not Detected | 9.9 | Not Detected |
| 1,1-Dichloroethene | 1.3 | Not Detected | 5.1 | Not Detected |
| Acetone | 13 | 9.6 J | 31 | 23 J |
| 2-Propanol | 5.2 | 34 | 13 | 83 |
| Carbon Disulfide | 5.2 | ~~0.66 J~~ | 16 | ~~2.1 J~~ |
| 3-Chloropropene | 5.2 | Not Detected | 16 | Not Detected |
| Methylene Chloride | 13 | ~~0.16 J~~ | 45 | ~~0.54 J~~ |
| Methyl tert-butyl ether | 1.3 | Not Detected | 4.6 | Not Detected |
| trans-1,2-Dichloroethene | 1.3 | Not Detected | 5.1 | Not Detected |
| Hexane | 1.3 | 5.5 | 4.5 | 19 |
| 1,1-Dichloroethane | 1.3 | Not Detected | 5.2 | Not Detected |
| 2-Butanone (Methyl Ethyl Ketone) | 5.2 | Not Detected | 15 | Not Detected |
| cis-1,2-Dichloroethene | 1.3 | Not Detected | 5.1 | Not Detected |
| Tetrahydrofuran | 1.3 | Not Detected | 3.8 | Not Detected |
| Chloroform | 1.3 | Not Detected | 6.3 | Not Detected |
| 1,1,1-Trichloroethane | 1.3 | Not Detected | 7.0 | Not Detected |
| Cyclohexane | 1.3 | 3.6 | 4.4 | 12 |
| Carbon Tetrachloride | 1.3 | Not Detected | 8.1 | Not Detected |
| 2,2,4-Trimethylpentane | 1.3 | 4.3 | 6.0 | 20 |
| Benzene | 1.3 | 470 | 4.1 | 1500 |
| 1,2-Dichloroethane | 1.3 | Not Detected | 5.2 | Not Detected |
| Heptane | 1.3 | 2.4 | 5.3 | 9.6 |
| Trichloroethene | 1.3 | Not Detected | 6.9 | Not Detected |
| 1,2-Dichloropropane | 1.3 | Not Detected | 6.0 | Not Detected |
| 1,4-Dioxane | 5.2 | Not Detected | 18 | Not Detected |
| Bromodichloromethane | 1.3 | Not Detected | 8.6 | Not Detected |
| cis-1,3-Dichloropropene | 1.3 | Not Detected | 5.8 | Not Detected |
| 4-Methyl-2-pentanone | 1.3 | Not Detected | 5.3 | Not Detected |
| Toluene | 1.3 | 1.3 | 4.9 | 5.0 |
| trans-1,3-Dichloropropene | 1.3 | Not Detected | 5.8 | Not Detected |
| 1,1,2-Trichloroethane | 1.3 | Not Detected | 7.0 | Not Detected |
| Tetrachloroethene | 1.3 | 0.14 J | 8.8 | 0.99 J |
| 2-Hexanone | 5.2 | Not Detected | 21 | Not Detected |

eurofins | Air Toxics

**Client Sample ID: VMP-19-5-013113**

**Lab ID#: 1302070A-10A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p021117** | **Date of Collection: 1/31/13 4:26:00 PM** | |
| **Dil. Factor:** | **2.58** | **Date of Analysis: 2/11/13 05:44 PM** | |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Dibromochloromethane | 1.3 | Not Detected | 11 | Not Detected |
| 1,2-Dibromoethane (EDB) | 1.3 | Not Detected | 9.9 | Not Detected |
| Chlorobenzene | 1.3 | Not Detected | 5.9 | Not Detected |
| Ethyl Benzene | 1.3 | 9.8 | 5.6 | 42 |
| m,p-Xylene | 1.3 | 25 | 5.6 | 110 |
| o-Xylene | 1.3 | 4.0 | 5.6 | 17 |
| Styrene | 1.3 | Not Detected | 5.5 | Not Detected |
| Bromoform | 1.3 | Not Detected | 13 | Not Detected |
| Cumene | 1.3 | 13 | 6.3 | 63 |
| 1,1,2,2-Tetrachloroethane | 1.3 | Not Detected | 8.8 | Not Detected |
| Propylbenzene | 1.3 | 10 | 6.3 | 49 |
| 4-Ethyltoluene | 1.3 | 19 | 6.3 | 92 |
| 1,3,5-Trimethylbenzene | 1.3 | 12 | 6.3 | 57 |
| 1,2,4-Trimethylbenzene | 1.3 | 29 | 6.3 | 140 |
| 1,3-Dichlorobenzene | 1.3 | Not Detected | 7.8 | Not Detected |
| 1,4-Dichlorobenzene | 1.3 | Not Detected | 7.8 | Not Detected |
| alpha-Chlorotoluene | 1.3 | Not Detected | 6.7 | Not Detected |
| 1,2-Dichlorobenzene | 1.3 | Not Detected | 7.8 | Not Detected |
| 1,2,4-Trichlorobenzene | 5.2 | ~~0.38 J~~ | 38 | ~~2.8 J~~ |
| Hexachlorobutadiene | 5.2 | Not Detected | 55 | Not Detected |
| Butane | 5.2 | 24 | 12 | 57 |
| Isopentane | 5.2 | 40 | 15 | 120 |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| Toluene-d8 | 98 | 70-130 |
| 1,2-Dichloroethane-d4 | 87 | 70-130 |
| 4-Bromofluorobenzene | 98 | 70-130 |

eurofins | Air Toxics

**Client Sample ID: VMP-42-10-013113**

**Lab ID#: 1302070A-11A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | p021118 | **Date of Collection:** | 1/31/13 1:13:00 PM |
| **Dil. Factor:** | 2.82 | **Date of Analysis:** | 2/11/13 06:15 PM |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 1.4 | 0.50 J | 7.0 | 2.5 J |
| Freon 114 | 1.4 | Not Detected | 9.8 | Not Detected |
| Chloromethane | 14 | Not Detected | 29 | Not Detected |
| Vinyl Chloride | 1.4 | Not Detected | 3.6 | Not Detected |
| 1,3-Butadiene | 1.4 | Not Detected | 3.1 | Not Detected |
| Bromomethane | 14 | Not Detected | 55 | Not Detected |
| Chloroethane | 5.6 | Not Detected | 15 | Not Detected |
| Freon 11 | 1.4 | 0.21 J | 7.9 | 1.2 J |
| Ethanol | 5.6 | 1.2 J | 11 | 2.2 J |
| Freon 113 | 1.4 | Not Detected | 11 | Not Detected |
| 1,1-Dichloroethene | 1.4 | Not Detected | 5.6 | Not Detected |
| Acetone | 14 | 1.9 J | 33 | 4.5 J |
| 2-Propanol | 5.6 | 0.93 J | 14 | 2.3 J |
| Carbon Disulfide | 5.6 | ~~0.62 J~~ | 18 | ~~1.9 J~~ |
| 3-Chloropropene | 5.6 | Not Detected | 18 | Not Detected |
| Methylene Chloride | 14 | Not Detected | 49 | Not Detected |
| Methyl tert-butyl ether | 1.4 | Not Detected | 5.1 | Not Detected |
| trans-1,2-Dichloroethene | 1.4 | Not Detected | 5.6 | Not Detected |
| Hexane | 1.4 | 0.26 J | 5.0 | 0.93 J |
| 1,1-Dichloroethane | 1.4 | Not Detected | 5.7 | Not Detected |
| 2-Butanone (Methyl Ethyl Ketone) | 5.6 | Not Detected | 17 | Not Detected |
| cis-1,2-Dichloroethene | 1.4 | Not Detected | 5.6 | Not Detected |
| Tetrahydrofuran | 1.4 | Not Detected | 4.2 | Not Detected |
| Chloroform | 1.4 | Not Detected | 6.9 | Not Detected |
| 1,1,1-Trichloroethane | 1.4 | Not Detected | 7.7 | Not Detected |
| Cyclohexane | 1.4 | Not Detected | 4.8 | Not Detected |
| Carbon Tetrachloride | 1.4 | Not Detected | 8.9 | Not Detected |
| 2,2,4-Trimethylpentane | 1.4 | 0.43 J | 6.6 | 2.0 J |
| Benzene | 1.4 | 0.73 J | 4.5 | 2.3 J |
| 1,2-Dichloroethane | 1.4 | Not Detected | 5.7 | Not Detected |
| Heptane | 1.4 | Not Detected | 5.8 | Not Detected |
| Trichloroethene | 1.4 | Not Detected | 7.6 | Not Detected |
| 1,2-Dichloropropane | 1.4 | Not Detected | 6.5 | Not Detected |
| 1,4-Dioxane | 5.6 | Not Detected | 20 | Not Detected |
| Bromodichloromethane | 1.4 | Not Detected | 9.4 | Not Detected |
| cis-1,3-Dichloropropene | 1.4 | Not Detected | 6.4 | Not Detected |
| 4-Methyl-2-pentanone | 1.4 | Not Detected | 5.8 | Not Detected |
| Toluene | 1.4 | Not Detected | 5.3 | Not Detected |
| trans-1,3-Dichloropropene | 1.4 | Not Detected | 6.4 | Not Detected |
| 1,1,2-Trichloroethane | 1.4 | Not Detected | 7.7 | Not Detected |
| Tetrachloroethene | 1.4 | Not Detected | 9.6 | Not Detected |
| 2-Hexanone | 5.6 | Not Detected | 23 | Not Detected |

eurofins | Air Toxics

**Client Sample ID: VMP-42-10-013113**
**Lab ID#: 1302070A-11A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p021118** | **Date of Collection: 1/31/13 1:13:00 PM** | |
| **Dil. Factor:** | **2.82** | **Date of Analysis: 2/11/13 06:15 PM** | |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Dibromochloromethane | 1.4 | Not Detected | 12 | Not Detected |
| 1,2-Dibromoethane (EDB) | 1.4 | Not Detected | 11 | Not Detected |
| Chlorobenzene | 1.4 | Not Detected | 6.5 | Not Detected |
| Ethyl Benzene | 1.4 | Not Detected | 6.1 | Not Detected |
| m,p-Xylene | 1.4 | Not Detected | 6.1 | Not Detected |
| o-Xylene | 1.4 | Not Detected | 6.1 | Not Detected |
| Styrene | 1.4 | Not Detected | 6.0 | Not Detected |
| Bromoform | 1.4 | Not Detected | 14 | Not Detected |
| Cumene | 1.4 | Not Detected | 6.9 | Not Detected |
| 1,1,2,2-Tetrachloroethane | 1.4 | Not Detected | 9.7 | Not Detected |
| Propylbenzene | 1.4 | Not Detected | 6.9 | Not Detected |
| 4-Ethyltoluene | 1.4 | ~~0.18 J~~ | 6.9 | ~~0.89 J~~ |
| 1,3,5-Trimethylbenzene | 1.4 | Not Detected | 6.9 | Not Detected |
| 1,2,4-Trimethylbenzene | 1.4 | ~~0.44 J~~ | 6.9 | ~~2.1 J~~ |
| 1,3-Dichlorobenzene | 1.4 | Not Detected | 8.5 | Not Detected |
| 1,4-Dichlorobenzene | 1.4 | Not Detected | 8.5 | Not Detected |
| alpha-Chlorotoluene | 1.4 | Not Detected | 7.3 | Not Detected |
| 1,2-Dichlorobenzene | 1.4 | Not Detected | 8.5 | Not Detected |
| 1,2,4-Trichlorobenzene | 5.6 | Not Detected | 42 | Not Detected |
| Hexachlorobutadiene | 5.6 | Not Detected | 60 | Not Detected |
| Butane | 5.6 | Not Detected | 13 | Not Detected |
| Isopentane | 5.6 | Not Detected | 17 | Not Detected |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| Toluene-d8 | 96 | 70-130 |
| 1,2-Dichloroethane-d4 | 84 | 70-130 |
| 4-Bromofluorobenzene | 98 | 70-130 |

eurofins | Air Toxics

**Client Sample ID: VMP-42-20-013113**
**Lab ID#: 1302070A-12A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | p021119 | **Date of Collection:** | 1/31/13 2:09:00 PM |
| **Dil. Factor:** | 2.58 | **Date of Analysis:** | 2/11/13 06:49 PM |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 1.3 | 0.40 J | 6.4 | 2.0 J |
| Freon 114 | 1.3 | Not Detected | 9.0 | Not Detected |
| Chloromethane | 13 | Not Detected | 27 | Not Detected |
| Vinyl Chloride | 1.3 | Not Detected | 3.3 | Not Detected |
| 1,3-Butadiene | 1.3 | Not Detected | 2.8 | Not Detected |
| Bromomethane | 13 | Not Detected | 50 | Not Detected |
| Chloroethane | 5.2 | Not Detected | 14 | Not Detected |
| Freon 11 | 1.3 | 0.24 J | 7.2 | 1.4 J |
| Ethanol | 5.2 | 2.4 J | 9.7 | 4.5 J |
| Freon 113 | 1.3 | Not Detected | 9.9 | Not Detected |
| 1,1-Dichloroethene | 1.3 | Not Detected | 5.1 | Not Detected |
| Acetone | 13 | 3.1 J | 31 | 7.3 J |
| 2-Propanol | 5.2 | 1.1 J | 13 | 2.6 J |
| Carbon Disulfide | 5.2 | ~~0.66 J~~ U | 16 | ~~2.0 J~~ U |
| 3-Chloropropene | 5.2 | Not Detected | 16 | Not Detected |
| Methylene Chloride | 13 | 1.5 J | 45 | 5.3 J |
| Methyl tert-butyl ether | 1.3 | Not Detected | 4.6 | Not Detected |
| trans-1,2-Dichloroethene | 1.3 | Not Detected | 5.1 | Not Detected |
| Hexane | 1.3 | 1.3 | 4.5 | 4.5 |
| 1,1-Dichloroethane | 1.3 | Not Detected | 5.2 | Not Detected |
| 2-Butanone (Methyl Ethyl Ketone) | 5.2 | Not Detected | 15 | Not Detected |
| cis-1,2-Dichloroethene | 1.3 | Not Detected | 5.1 | Not Detected |
| Tetrahydrofuran | 1.3 | Not Detected | 3.8 | Not Detected |
| Chloroform | 1.3 | 5.1 | 6.3 | 25 |
| 1,1,1-Trichloroethane | 1.3 | Not Detected | 7.0 | Not Detected |
| Cyclohexane | 1.3 | Not Detected | 4.4 | Not Detected |
| Carbon Tetrachloride | 1.3 | Not Detected | 8.1 | Not Detected |
| 2,2,4-Trimethylpentane | 1.3 | 0.23 J | 6.0 | 1.1 J |
| Benzene | 1.3 | 2.0 | 4.1 | 6.3 |
| 1,2-Dichloroethane | 1.3 | Not Detected | 5.2 | Not Detected |
| Heptane | 1.3 | 0.95 J | 5.3 | 3.9 J |
| Trichloroethene | 1.3 | Not Detected | 6.9 | Not Detected |
| 1,2-Dichloropropane | 1.3 | Not Detected | 6.0 | Not Detected |
| 1,4-Dioxane | 5.2 | Not Detected | 18 | Not Detected |
| Bromodichloromethane | 1.3 | Not Detected | 8.6 | Not Detected |
| cis-1,3-Dichloropropene | 1.3 | Not Detected | 5.8 | Not Detected |
| 4-Methyl-2-pentanone | 1.3 | Not Detected | 5.3 | Not Detected |
| Toluene | 1.3 | ~~0.22 J~~ U | 4.9 | ~~0.82 J~~ U |
| trans-1,3-Dichloropropene | 1.3 | Not Detected | 5.8 | Not Detected |
| 1,1,2-Trichloroethane | 1.3 | Not Detected | 7.0 | Not Detected |
| Tetrachloroethene | 1.3 | ~~0.46 J~~ U | 8.8 | ~~3.1 J~~ U |
| 2-Hexanone | 5.2 | Not Detected | 21 | Not Detected |

eurofins | Air Toxics

**Client Sample ID: VMP-42-20-013113**

**Lab ID#: 1302070A-12A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p021119** | **Date of Collection: 1/31/13 2:09:00 PM** | |
| **Dil. Factor:** | **2.58** | **Date of Analysis: 2/11/13 06:49 PM** | |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Dibromochloromethane | 1.3 | Not Detected | 11 | Not Detected |
| 1,2-Dibromoethane (EDB) | 1.3 | Not Detected | 9.9 | Not Detected |
| Chlorobenzene | 1.3 | Not Detected | 5.9 | Not Detected |
| Ethyl Benzene | 1.3 | Not Detected | 5.6 | Not Detected |
| m,p-Xylene | 1.3 | Not Detected | 5.6 | Not Detected |
| o-Xylene | 1.3 | Not Detected | 5.6 | Not Detected |
| Styrene | 1.3 | Not Detected | 5.5 | Not Detected |
| Bromoform | 1.3 | Not Detected | 13 | Not Detected |
| Cumene | 1.3 | Not Detected | 6.3 | Not Detected |
| 1,1,2,2-Tetrachloroethane | 1.3 | Not Detected | 8.8 | Not Detected |
| Propylbenzene | 1.3 | Not Detected | 6.3 | Not Detected |
| 4-Ethyltoluene | 1.3 | ~~0.13 J~~ U | 6.3 | ~~0.66 J~~ U |
| 1,3,5-Trimethylbenzene | 1.3 | Not Detected | 6.3 | Not Detected |
| 1,2,4-Trimethylbenzene | 1.3 | Not Detected | 6.3 | Not Detected |
| 1,3-Dichlorobenzene | 1.3 | Not Detected | 7.8 | Not Detected |
| 1,4-Dichlorobenzene | 1.3 | Not Detected | 7.8 | Not Detected |
| alpha-Chlorotoluene | 1.3 | Not Detected | 6.7 | Not Detected |
| 1,2-Dichlorobenzene | 1.3 | Not Detected | 7.8 | Not Detected |
| 1,2,4-Trichlorobenzene | 5.2 | Not Detected | 38 | Not Detected |
| Hexachlorobutadiene | 5.2 | Not Detected | 55 | Not Detected |
| Butane | 5.2 | 5.0 J | 12 | 12 J |
| Isopentane | 5.2 | 1.7 J | 15 | 5.1 J |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| Toluene-d8 | 98 | 70-130 |
| 1,2-Dichloroethane-d4 | 81 | 70-130 |
| 4-Bromofluorobenzene | 99 | 70-130 |

eurofins | Air Toxics

**Client Sample ID: VMP-42-30-013113**

**Lab ID#: 1302070A-13A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p021120** | **Date of Collection:** | **1/31/13 3:00:00 PM** |
| **Dil. Factor:** | **2.76** | **Date of Analysis:** | **2/11/13 07:23 PM** |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 1.4 | 0.41 J | 6.8 | 2.0 J |
| Freon 114 | 1.4 | Not Detected | 9.6 | Not Detected |
| Chloromethane | 14 | Not Detected | 28 | Not Detected |
| Vinyl Chloride | 1.4 | Not Detected | 3.5 | Not Detected |
| 1,3-Butadiene | 1.4 | Not Detected | 3.0 | Not Detected |
| Bromomethane | 14 | Not Detected | 54 | Not Detected |
| Chloroethane | 5.5 | Not Detected | 14 | Not Detected |
| Freon 11 | 1.4 | 0.60 J | 7.8 | 3.4 J |
| Ethanol | 5.5 | 2.0 J | 10 | 3.8 J |
| Freon 113 | 1.4 | Not Detected | 10 | Not Detected |
| 1,1-Dichloroethene | 1.4 | Not Detected | 5.5 | Not Detected |
| Acetone | 14 | 2.6 J | 33 | 6.2 J |
| 2-Propanol | 5.5 | 0.59 J | 14 | 1.4 J |
| Carbon Disulfide | 5.5 | 1.9 J | 17 | 6.1 J |
| 3-Chloropropene | 5.5 | Not Detected | 17 | Not Detected |
| Methylene Chloride | 14 | Not Detected | 48 | Not Detected |
| Methyl tert-butyl ether | 1.4 | Not Detected | 5.0 | Not Detected |
| trans-1,2-Dichloroethene | 1.4 | Not Detected | 5.5 | Not Detected |
| Hexane | 1.4 | 0.50 J | 4.9 | 1.8 J |
| 1,1-Dichloroethane | 1.4 | Not Detected | 5.6 | Not Detected |
| 2-Butanone (Methyl Ethyl Ketone) | 5.5 | Not Detected | 16 | Not Detected |
| cis-1,2-Dichloroethene | 1.4 | Not Detected | 5.5 | Not Detected |
| Tetrahydrofuran | 1.4 | Not Detected | 4.1 | Not Detected |
| Chloroform | 1.4 | 1.6 | 6.7 | 7.9 |
| 1,1,1-Trichloroethane | 1.4 | Not Detected | 7.5 | Not Detected |
| Cyclohexane | 1.4 | 0.65 J | 4.8 | 2.2 J |
| Carbon Tetrachloride | 1.4 | Not Detected | 8.7 | Not Detected |
| 2,2,4-Trimethylpentane | 1.4 | 51 | 6.4 | 240 |
| Benzene | 1.4 | Not Detected | 4.4 | Not Detected |
| 1,2-Dichloroethane | 1.4 | Not Detected | 5.6 | Not Detected |
| Heptane | 1.4 | 0.32 J | 5.6 | 1.3 J |
| Trichloroethene | 1.4 | Not Detected | 7.4 | Not Detected |
| 1,2-Dichloropropane | 1.4 | Not Detected | 6.4 | Not Detected |
| 1,4-Dioxane | 5.5 | Not Detected | 20 | Not Detected |
| Bromodichloromethane | 1.4 | Not Detected | 9.2 | Not Detected |
| cis-1,3-Dichloropropene | 1.4 | Not Detected | 6.3 | Not Detected |
| 4-Methyl-2-pentanone | 1.4 | Not Detected | 5.6 | Not Detected |
| Toluene | 1.4 | ~~0.12 J~~ | 5.2 | ~~0.46 J~~ |
| trans-1,3-Dichloropropene | 1.4 | Not Detected | 6.3 | Not Detected |
| 1,1,2-Trichloroethane | 1.4 | Not Detected | 7.5 | Not Detected |
| Tetrachloroethene | 1.4 | Not Detected | 9.4 | Not Detected |
| 2-Hexanone | 5.5 | Not Detected | 23 | Not Detected |

eurofins | Air Toxics

**Client Sample ID: VMP-42-30-013113**

**Lab ID#: 1302070A-13A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | p021120 | **Date of Collection:** | 1/31/13 3:00:00 PM |
| **Dil. Factor:** | 2.76 | **Date of Analysis:** | 2/11/13 07:23 PM |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Dibromochloromethane | 1.4 | Not Detected | 12 | Not Detected |
| 1,2-Dibromoethane (EDB) | 1.4 | Not Detected | 11 | Not Detected |
| Chlorobenzene | 1.4 | Not Detected | 6.4 | Not Detected |
| Ethyl Benzene | 1.4 | Not Detected | 6.0 | Not Detected |
| m,p-Xylene | 1.4 | Not Detected | 6.0 | Not Detected |
| o-Xylene | 1.4 | Not Detected | 6.0 | Not Detected |
| Styrene | 1.4 | Not Detected | 5.9 | Not Detected |
| Bromoform | 1.4 | Not Detected | 14 | Not Detected |
| Cumene | 1.4 | Not Detected | 6.8 | Not Detected |
| 1,1,2,2-Tetrachloroethane | 1.4 | Not Detected | 9.5 | Not Detected |
| Propylbenzene | 1.4 | Not Detected | 6.8 | Not Detected |
| 4-Ethyltoluene | 1.4 | Not Detected | 6.8 | Not Detected |
| 1,3,5-Trimethylbenzene | 1.4 | Not Detected | 6.8 | Not Detected |
| 1,2,4-Trimethylbenzene | 1.4 | Not Detected | 6.8 | Not Detected |
| 1,3-Dichlorobenzene | 1.4 | Not Detected | 8.3 | Not Detected |
| 1,4-Dichlorobenzene | 1.4 | Not Detected | 8.3 | Not Detected |
| alpha-Chlorotoluene | 1.4 | Not Detected | 7.1 | Not Detected |
| 1,2-Dichlorobenzene | 1.4 | Not Detected | 8.3 | Not Detected |
| 1,2,4-Trichlorobenzene | 5.5 | Not Detected | 41 | Not Detected |
| Hexachlorobutadiene | 5.5 | Not Detected | 59 | Not Detected |
| Butane | 5.5 | 140 | 13 | 330 |
| Isopentane | 5.5 | 34 | 16 | 100 |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| Toluene-d8 | 97 | 70-130 |
| 1,2-Dichloroethane-d4 | 86 | 70-130 |
| 4-Bromofluorobenzene | 98 | 70-130 |

eurofins | Air Toxics

**Client Sample ID: VMP-45-10-013013**

**Lab ID#: 1302070A-14A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | p021121 | **Date of Collection:** | 1/30/13 3:00:00 PM |
| **Dil. Factor:** | 2.52 | **Date of Analysis:** | 2/11/13 07:52 PM |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 1.3 | 0.45 J | 6.2 | 2.2 J |
| Freon 114 | 1.3 | Not Detected | 8.8 | Not Detected |
| Chloromethane | 13 | Not Detected | 26 | Not Detected |
| Vinyl Chloride | 1.3 | Not Detected | 3.2 | Not Detected |
| 1,3-Butadiene | 1.3 | Not Detected | 2.8 | Not Detected |
| Bromomethane | 13 | Not Detected | 49 | Not Detected |
| Chloroethane | 5.0 | Not Detected | 13 | Not Detected |
| Freon 11 | 1.3 | 0.19 J | 7.1 | 1.1 J |
| Ethanol | 5.0 | 12 | 9.5 | 22 |
| Freon 113 | 1.3 | Not Detected | 9.6 | Not Detected |
| 1,1-Dichloroethene | 1.3 | Not Detected | 5.0 | Not Detected |
| Acetone | 13 | 7.4 J | 30 | 18 J |
| 2-Propanol | 5.0 | 23 | 12 | 57 |
| Carbon Disulfide | 5.0 | ~~0.63 J~~ | 16 | ~~2.0 J~~ |
| 3-Chloropropene | 5.0 | Not Detected | 16 | Not Detected |
| Methylene Chloride | 13 | Not Detected | 44 | Not Detected |
| Methyl tert-butyl ether | 1.3 | Not Detected | 4.5 | Not Detected |
| trans-1,2-Dichloroethene | 1.3 | Not Detected | 5.0 | Not Detected |
| Hexane | 1.3 | 0.57 J | 4.4 | 2.0 J |
| 1,1-Dichloroethane | 1.3 | Not Detected | 5.1 | Not Detected |
| 2-Butanone (Methyl Ethyl Ketone) | 5.0 | Not Detected | 15 | Not Detected |
| cis-1,2-Dichloroethene | 1.3 | Not Detected | 5.0 | Not Detected |
| Tetrahydrofuran | 1.3 | Not Detected | 3.7 | Not Detected |
| Chloroform | 1.3 | Not Detected | 6.2 | Not Detected |
| 1,1,1-Trichloroethane | 1.3 | Not Detected | 6.9 | Not Detected |
| Cyclohexane | 1.3 | Not Detected | 4.3 | Not Detected |
| Carbon Tetrachloride | 1.3 | Not Detected | 7.9 | Not Detected |
| 2,2,4-Trimethylpentane | 1.3 | 1.0 J | 5.9 | 4.8 J |
| Benzene | 1.3 | 5.1 | 4.0 | 16 |
| 1,2-Dichloroethane | 1.3 | Not Detected | 5.1 | Not Detected |
| Heptane | 1.3 | 0.29 J | 5.2 | 1.2 J |
| Trichloroethene | 1.3 | Not Detected | 6.8 | Not Detected |
| 1,2-Dichloropropane | 1.3 | Not Detected | 5.8 | Not Detected |
| 1,4-Dioxane | 5.0 | Not Detected | 18 | Not Detected |
| Bromodichloromethane | 1.3 | Not Detected | 8.4 | Not Detected |
| cis-1,3-Dichloropropene | 1.3 | Not Detected | 5.7 | Not Detected |
| 4-Methyl-2-pentanone | 1.3 | 0.28 J | 5.2 | 1.1 J |
| Toluene | 1.3 | ~~0.34 J~~ | 4.7 | ~~1.3 J~~ |
| trans-1,3-Dichloropropene | 1.3 | Not Detected | 5.7 | Not Detected |
| 1,1,2-Trichloroethane | 1.3 | Not Detected | 6.9 | Not Detected |
| Tetrachloroethene | 1.3 | Not Detected | 8.5 | Not Detected |
| 2-Hexanone | 5.0 | Not Detected | 21 | Not Detected |

eurofins | Air Toxics

**Client Sample ID: VMP-45-10-013013**

**Lab ID#: 1302070A-14A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p021121** | **Date of Collection:** | **1/30/13 3:00:00 PM** |
| **Dil. Factor:** | **2.52** | **Date of Analysis:** | **2/11/13 07:52 PM** |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Dibromochloromethane | 1.3 | Not Detected | 11 | Not Detected |
| 1,2-Dibromoethane (EDB) | 1.3 | Not Detected | 9.7 | Not Detected |
| Chlorobenzene | 1.3 | Not Detected | 5.8 | Not Detected |
| Ethyl Benzene | 1.3 | Not Detected | 5.5 | Not Detected |
| m,p-Xylene | 1.3 | Not Detected | 5.5 | Not Detected |
| o-Xylene | 1.3 | Not Detected | 5.5 | Not Detected |
| Styrene | 1.3 | Not Detected | 5.4 | Not Detected |
| Bromoform | 1.3 | Not Detected | 13 | Not Detected |
| Cumene | 1.3 | Not Detected | 6.2 | Not Detected |
| 1,1,2,2-Tetrachloroethane | 1.3 | Not Detected | 8.6 | Not Detected |
| Propylbenzene | 1.3 | Not Detected | 6.2 | Not Detected |
| 4-Ethyltoluene | 1.3 | Not Detected | 6.2 | Not Detected |
| 1,3,5-Trimethylbenzene | 1.3 | Not Detected | 6.2 | Not Detected |
| 1,2,4-Trimethylbenzene | 1.3 | Not Detected | 6.2 | Not Detected |
| 1,3-Dichlorobenzene | 1.3 | Not Detected | 7.6 | Not Detected |
| 1,4-Dichlorobenzene | 1.3 | Not Detected | 7.6 | Not Detected |
| alpha-Chlorotoluene | 1.3 | Not Detected | 6.5 | Not Detected |
| 1,2-Dichlorobenzene | 1.3 | Not Detected | 7.6 | Not Detected |
| 1,2,4-Trichlorobenzene | 5.0 | Not Detected | 37 | Not Detected |
| Hexachlorobutadiene | 5.0 | Not Detected | 54 | Not Detected |
| Butane | 5.0 | 2.1 J | 12 | 5.0 J |
| Isopentane | 5.0 | 0.86 J | 15 | 2.5 J |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| Toluene-d8 | 98 | 70-130 |
| 1,2-Dichloroethane-d4 | 84 | 70-130 |
| 4-Bromofluorobenzene | 100 | 70-130 |

eurofins | Air Toxics

**Client Sample ID: VMP-45-20-013013**

**Lab ID#: 1302070A-15A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p021122** | **Date of Collection:** | **1/30/13 3:46:00 PM** |
| **Dil. Factor:** | **2.64** | **Date of Analysis:** | **2/11/13 08:27 PM** |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 1.3 | 0.49 J | 6.5 | 2.4 J |
| Freon 114 | 1.3 | Not Detected | 9.2 | Not Detected |
| Chloromethane | 13 | Not Detected | 27 | Not Detected |
| Vinyl Chloride | 1.3 | Not Detected | 3.4 | Not Detected |
| 1,3-Butadiene | 1.3 | Not Detected | 2.9 | Not Detected |
| Bromomethane | 13 | Not Detected | 51 | Not Detected |
| Chloroethane | 5.3 | Not Detected | 14 | Not Detected |
| Freon 11 | 1.3 | 0.18 J | 7.4 | 1.0 J |
| Ethanol | 5.3 | 1.9 J | 9.9 | 3.5 J |
| Freon 113 | 1.3 | Not Detected | 10 | Not Detected |
| 1,1-Dichloroethene | 1.3 | Not Detected | 5.2 | Not Detected |
| Acetone | 13 | 10 J | 31 | 24 J |
| 2-Propanol | 5.3 | 3.3 J | 13 | 8.1 J |
| Carbon Disulfide | 5.3 | ~~0.60 J~~ U | 16 | ~~1.9 J~~ U |
| 3-Chloropropene | 5.3 | Not Detected | 16 | Not Detected |
| Methylene Chloride | 13 | Not Detected | 46 | Not Detected |
| Methyl tert-butyl ether | 1.3 | Not Detected | 4.8 | Not Detected |
| trans-1,2-Dichloroethene | 1.3 | Not Detected | 5.2 | Not Detected |
| Hexane | 1.3 | Not Detected | 4.6 | Not Detected |
| 1,1-Dichloroethane | 1.3 | Not Detected | 5.3 | Not Detected |
| 2-Butanone (Methyl Ethyl Ketone) | 5.3 | 1.2 J | 16 | 3.6 J |
| cis-1,2-Dichloroethene | 1.3 | Not Detected | 5.2 | Not Detected |
| Tetrahydrofuran | 1.3 | Not Detected | 3.9 | Not Detected |
| Chloroform | 1.3 | 2.3 | 6.4 | 11 |
| 1,1,1-Trichloroethane | 1.3 | Not Detected | 7.2 | Not Detected |
| Cyclohexane | 1.3 | Not Detected | 4.5 | Not Detected |
| Carbon Tetrachloride | 1.3 | Not Detected | 8.3 | Not Detected |
| 2,2,4-Trimethylpentane | 1.3 | 66 | 6.2 | 310 |
| Benzene | 1.3 | Not Detected | 4.2 | Not Detected |
| 1,2-Dichloroethane | 1.3 | Not Detected | 5.3 | Not Detected |
| Heptane | 1.3 | Not Detected | 5.4 | Not Detected |
| Trichloroethene | 1.3 | Not Detected | 7.1 | Not Detected |
| 1,2-Dichloropropane | 1.3 | Not Detected | 6.1 | Not Detected |
| 1,4-Dioxane | 5.3 | Not Detected | 19 | Not Detected |
| Bromodichloromethane | 1.3 | Not Detected | 8.8 | Not Detected |
| cis-1,3-Dichloropropene | 1.3 | Not Detected | 6.0 | Not Detected |
| 4-Methyl-2-pentanone | 1.3 | Not Detected | 5.4 | Not Detected |
| Toluene | 1.3 | ~~0.10 J~~ U | 5.0 | ~~0.38 J~~ U |
| trans-1,3-Dichloropropene | 1.3 | Not Detected | 6.0 | Not Detected |
| 1,1,2-Trichloroethane | 1.3 | Not Detected | 7.2 | Not Detected |
| Tetrachloroethene | 1.3 | Not Detected | 9.0 | Not Detected |
| 2-Hexanone | 5.3 | Not Detected | 22 | Not Detected |

eurofins | Air Toxics

**Client Sample ID: VMP-45-20-013013**

**Lab ID#: 1302070A-15A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p021122** | **Date of Collection: 1/30/13 3:46:00 PM** | |
| **Dil. Factor:** | **2.64** | **Date of Analysis: 2/11/13 08:27 PM** | |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Dibromochloromethane | 1.3 | Not Detected | 11 | Not Detected |
| 1,2-Dibromoethane (EDB) | 1.3 | Not Detected | 10 | Not Detected |
| Chlorobenzene | 1.3 | Not Detected | 6.1 | Not Detected |
| Ethyl Benzene | 1.3 | Not Detected | 5.7 | Not Detected |
| m,p-Xylene | 1.3 | Not Detected | 5.7 | Not Detected |
| o-Xylene | 1.3 | Not Detected | 5.7 | Not Detected |
| Styrene | 1.3 | Not Detected | 5.6 | Not Detected |
| Bromoform | 1.3 | Not Detected | 14 | Not Detected |
| Cumene | 1.3 | Not Detected | 6.5 | Not Detected |
| 1,1,2,2-Tetrachloroethane | 1.3 | Not Detected | 9.1 | Not Detected |
| Propylbenzene | 1.3 | Not Detected | 6.5 | Not Detected |
| 4-Ethyltoluene | 1.3 | Not Detected | 6.5 | Not Detected |
| 1,3,5-Trimethylbenzene | 1.3 | Not Detected | 6.5 | Not Detected |
| 1,2,4-Trimethylbenzene | 1.3 | Not Detected | 6.5 | Not Detected |
| 1,3-Dichlorobenzene | 1.3 | Not Detected | 7.9 | Not Detected |
| 1,4-Dichlorobenzene | 1.3 | Not Detected | 7.9 | Not Detected |
| alpha-Chlorotoluene | 1.3 | Not Detected | 6.8 | Not Detected |
| 1,2-Dichlorobenzene | 1.3 | Not Detected | 7.9 | Not Detected |
| 1,2,4-Trichlorobenzene | 5.3 | Not Detected | 39 | Not Detected |
| Hexachlorobutadiene | 5.3 | Not Detected | 56 | Not Detected |
| Butane | 5.3 | 8.9 | 12 | 21 |
| Isopentane | 5.3 | 1.7 J | 16 | 5.1 J |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| Toluene-d8 | 98 | 70-130 |
| 1,2-Dichloroethane-d4 | 83 | 70-130 |
| 4-Bromofluorobenzene | 97 | 70-130 |

eurofins | Air Toxics

**Client Sample ID: VMP-45-30-013013**

**Lab ID#: 1302070A-16A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p021123** | **Date of Collection:** | **1/30/13 4:35:00 PM** |
| **Dil. Factor:** | **4.84** | **Date of Analysis:** | **2/11/13 08:59 PM** |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 2.4 | 0.36 J | 12 | 1.8 J |
| Freon 114 | 2.4 | Not Detected | 17 | Not Detected |
| Chloromethane | 24 | Not Detected | 50 | Not Detected |
| Vinyl Chloride | 2.4 | Not Detected | 6.2 | Not Detected |
| 1,3-Butadiene | 2.4 | Not Detected | 5.4 | Not Detected |
| Bromomethane | 24 | Not Detected | 94 | Not Detected |
| Chloroethane | 9.7 | Not Detected | 26 | Not Detected |
| Freon 11 | 2.4 | 0.67 J | 14 | 3.8 J |
| Ethanol | 9.7 | 8.3 J | 18 | 16 J |
| Freon 113 | 2.4 | Not Detected | 18 | Not Detected |
| 1,1-Dichloroethene | 2.4 | Not Detected | 9.6 | Not Detected |
| Acetone | 24 | 22 J | 57 | 52 J |
| 2-Propanol | 9.7 | 940 | 24 | 2300 |
| Carbon Disulfide | 9.7 | ~~1.3 J~~ U | 30 | ~~4.1 J~~ U |
| 3-Chloropropene | 9.7 | Not Detected | 30 | Not Detected |
| Methylene Chloride | 24 | Not Detected | 84 | Not Detected |
| Methyl tert-butyl ether | 2.4 | Not Detected | 8.7 | Not Detected |
| trans-1,2-Dichloroethene | 2.4 | Not Detected | 9.6 | Not Detected |
| Hexane | 2.4 | 0.78 J | 8.5 | 2.8 J |
| 1,1-Dichloroethane | 2.4 | Not Detected | 9.8 | Not Detected |
| 2-Butanone (Methyl Ethyl Ketone) | 9.7 | Not Detected | 28 | Not Detected |
| cis-1,2-Dichloroethene | 2.4 | Not Detected | 9.6 | Not Detected |
| Tetrahydrofuran | 2.4 | Not Detected | 7.1 | Not Detected |
| Chloroform | 2.4 | 1.8 J | 12 | 8.6 J |
| 1,1,1-Trichloroethane | 2.4 | Not Detected | 13 | Not Detected |
| Cyclohexane | 2.4 | Not Detected | 8.3 | Not Detected |
| Carbon Tetrachloride | 2.4 | Not Detected | 15 | Not Detected |
| 2,2,4-Trimethylpentane | 2.4 | 120 | 11 | 560 |
| Benzene | 2.4 | 1.8 J | 7.7 | 5.8 J |
| 1,2-Dichloroethane | 2.4 | Not Detected | 9.8 | Not Detected |
| Heptane | 2.4 | Not Detected | 9.9 | Not Detected |
| Trichloroethene | 2.4 | Not Detected | 13 | Not Detected |
| 1,2-Dichloropropane | 2.4 | Not Detected | 11 | Not Detected |
| 1,4-Dioxane | 9.7 | Not Detected | 35 | Not Detected |
| Bromodichloromethane | 2.4 | Not Detected | 16 | Not Detected |
| cis-1,3-Dichloropropene | 2.4 | Not Detected | 11 | Not Detected |
| 4-Methyl-2-pentanone | 2.4 | Not Detected | 9.9 | Not Detected |
| Toluene | 2.4 | ~~0.40 J~~ U | 9.1 | ~~1.5 J~~ U |
| trans-1,3-Dichloropropene | 2.4 | Not Detected | 11 | Not Detected |
| 1,1,2-Trichloroethane | 2.4 | Not Detected | 13 | Not Detected |
| Tetrachloroethene | 2.4 | Not Detected | 16 | Not Detected |
| 2-Hexanone | 9.7 | Not Detected | 40 | Not Detected |

eurofins | Air Toxics

**Client Sample ID: VMP-45-30-013013**

**Lab ID#: 1302070A-16A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p021123** | **Date of Collection: 1/30/13 4:35:00 PM** | |
| **Dil. Factor:** | **4.84** | **Date of Analysis: 2/11/13 08:59 PM** | |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Dibromochloromethane | 2.4 | Not Detected | 21 | Not Detected |
| 1,2-Dibromoethane (EDB) | 2.4 | Not Detected | 18 | Not Detected |
| Chlorobenzene | 2.4 | Not Detected | 11 | Not Detected |
| Ethyl Benzene | 2.4 | Not Detected | 10 | Not Detected |
| m,p-Xylene | 2.4 | Not Detected | 10 | Not Detected |
| o-Xylene | 2.4 | Not Detected | 10 | Not Detected |
| Styrene | 2.4 | Not Detected | 10 | Not Detected |
| Bromoform | 2.4 | Not Detected | 25 | Not Detected |
| Cumene | 2.4 | Not Detected | 12 | Not Detected |
| 1,1,2,2-Tetrachloroethane | 2.4 | Not Detected | 17 | Not Detected |
| Propylbenzene | 2.4 | Not Detected | 12 | Not Detected |
| 4-Ethyltoluene | 2.4 | Not Detected | 12 | Not Detected |
| 1,3,5-Trimethylbenzene | 2.4 | Not Detected | 12 | Not Detected |
| 1,2,4-Trimethylbenzene | 2.4 | Not Detected | 12 | Not Detected |
| 1,3-Dichlorobenzene | 2.4 | Not Detected | 14 | Not Detected |
| 1,4-Dichlorobenzene | 2.4 | Not Detected | 14 | Not Detected |
| alpha-Chlorotoluene | 2.4 | Not Detected | 12 | Not Detected |
| 1,2-Dichlorobenzene | 2.4 | Not Detected | 14 | Not Detected |
| 1,2,4-Trichlorobenzene | 9.7 | Not Detected | 72 | Not Detected |
| Hexachlorobutadiene | 9.7 | Not Detected | 100 | Not Detected |
| Butane | 9.7 | 4.7 J | 23 | 11 J |
| Isopentane | 9.7 | 2.6 J | 28 | 7.8 J |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| Toluene-d8 | 99 | 70-130 |
| 1,2-Dichloroethane-d4 | 83 | 70-130 |
| 4-Bromofluorobenzene | 100 | 70-130 |

eurofins | Air Toxics

**Client Sample ID: VMP-49-5-020113**

**Lab ID#: 1302070A-17A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p021124** | **Date of Collection:** | **2/1/13 9:45:00 AM** |
| **Dil. Factor:** | **2.69** | **Date of Analysis:** | **2/11/13 09:33 PM** |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 1.3 | 0.43 J | 6.6 | 2.1 J |
| Freon 114 | 1.3 | Not Detected | 9.4 | Not Detected |
| Chloromethane | 13 | Not Detected | 28 | Not Detected |
| Vinyl Chloride | 1.3 | Not Detected | 3.4 | Not Detected |
| 1,3-Butadiene | 1.3 | Not Detected | 3.0 | Not Detected |
| Bromomethane | 13 | Not Detected | 52 | Not Detected |
| Chloroethane | 5.4 | Not Detected | 14 | Not Detected |
| Freon 11 | 1.3 | 0.21 J | 7.6 | 1.2 J |
| Ethanol | 5.4 | 1.7 J | 10 | 3.3 J |
| Freon 113 | 1.3 | Not Detected | 10 | Not Detected |
| 1,1-Dichloroethene | 1.3 | Not Detected | 5.3 | Not Detected |
| Acetone | 13 | 11 J | 32 | 27 J |
| 2-Propanol | 5.4 | 3.2 J | 13 | 7.7 J |
| Carbon Disulfide | 5.4 | ~~0.72 J~~ | 17 | ~~2.2 J~~ |
| 3-Chloropropene | 5.4 | Not Detected | 17 | Not Detected |
| Methylene Chloride | 13 | Not Detected | 47 | Not Detected |
| Methyl tert-butyl ether | 1.3 | Not Detected | 4.8 | Not Detected |
| trans-1,2-Dichloroethene | 1.3 | Not Detected | 5.3 | Not Detected |
| Hexane | 1.3 | Not Detected | 4.7 | Not Detected |
| 1,1-Dichloroethane | 1.3 | Not Detected | 5.4 | Not Detected |
| 2-Butanone (Methyl Ethyl Ketone) | 5.4 | 1.8 J | 16 | 5.5 J |
| cis-1,2-Dichloroethene | 1.3 | Not Detected | 5.3 | Not Detected |
| Tetrahydrofuran | 1.3 | Not Detected | 4.0 | Not Detected |
| Chloroform | 1.3 | Not Detected | 6.6 | Not Detected |
| 1,1,1-Trichloroethane | 1.3 | Not Detected | 7.3 | Not Detected |
| Cyclohexane | 1.3 | Not Detected | 4.6 | Not Detected |
| Carbon Tetrachloride | 1.3 | Not Detected | 8.5 | Not Detected |
| 2,2,4-Trimethylpentane | 1.3 | 0.74 J | 6.3 | 3.5 J |
| Benzene | 1.3 | Not Detected | 4.3 | Not Detected |
| 1,2-Dichloroethane | 1.3 | Not Detected | 5.4 | Not Detected |
| Heptane | 1.3 | Not Detected | 5.5 | Not Detected |
| Trichloroethene | 1.3 | Not Detected | 7.2 | Not Detected |
| 1,2-Dichloropropane | 1.3 | Not Detected | 6.2 | Not Detected |
| 1,4-Dioxane | 5.4 | Not Detected | 19 | Not Detected |
| Bromodichloromethane | 1.3 | Not Detected | 9.0 | Not Detected |
| cis-1,3-Dichloropropene | 1.3 | Not Detected | 6.1 | Not Detected |
| 4-Methyl-2-pentanone | 1.3 | 0.33 J | 5.5 | 1.3 J |
| Toluene | 1.3 | ~~0.13 J~~ | 5.1 | ~~0.50 J~~ |
| trans-1,3-Dichloropropene | 1.3 | Not Detected | 6.1 | Not Detected |
| 1,1,2-Trichloroethane | 1.3 | Not Detected | 7.3 | Not Detected |
| Tetrachloroethene | 1.3 | ~~0.19 J~~ | 9.1 | ~~1.3 J~~ |
| 2-Hexanone | 5.4 | Not Detected | 22 | Not Detected |

eurofins | Air Toxics

**Client Sample ID: VMP-49-5-020113**

**Lab ID#: 1302070A-17A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p021124** | **Date of Collection: 2/1/13 9:45:00 AM** | |
| **Dil. Factor:** | **2.69** | **Date of Analysis: 2/11/13 09:33 PM** | |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Dibromochloromethane | 1.3 | Not Detected | 11 | Not Detected |
| 1,2-Dibromoethane (EDB) | 1.3 | Not Detected | 10 | Not Detected |
| Chlorobenzene | 1.3 | Not Detected | 6.2 | Not Detected |
| Ethyl Benzene | 1.3 | Not Detected | 5.8 | Not Detected |
| m,p-Xylene | 1.3 | Not Detected | 5.8 | Not Detected |
| o-Xylene | 1.3 | Not Detected | 5.8 | Not Detected |
| Styrene | 1.3 | Not Detected | 5.7 | Not Detected |
| Bromoform | 1.3 | Not Detected | 14 | Not Detected |
| Cumene | 1.3 | Not Detected | 6.6 | Not Detected |
| 1,1,2,2-Tetrachloroethane | 1.3 | Not Detected | 9.2 | Not Detected |
| Propylbenzene | 1.3 | Not Detected | 6.6 | Not Detected |
| 4-Ethyltoluene | 1.3 | Not Detected | 6.6 | Not Detected |
| 1,3,5-Trimethylbenzene | 1.3 | Not Detected | 6.6 | Not Detected |
| 1,2,4-Trimethylbenzene | 1.3 | Not Detected | 6.6 | Not Detected |
| 1,3-Dichlorobenzene | 1.3 | Not Detected | 8.1 | Not Detected |
| 1,4-Dichlorobenzene | 1.3 | Not Detected | 8.1 | Not Detected |
| alpha-Chlorotoluene | 1.3 | Not Detected | 7.0 | Not Detected |
| 1,2-Dichlorobenzene | 1.3 | Not Detected | 8.1 | Not Detected |
| 1,2,4-Trichlorobenzene | 5.4 | ~~0.35 J~~ | 40 | ~~2.6 J~~ |
| Hexachlorobutadiene | 5.4 | Not Detected | 57 | Not Detected |
| Butane | 5.4 | Not Detected | 13 | Not Detected |
| Isopentane | 5.4 | Not Detected | 16 | Not Detected |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| Toluene-d8 | 99 | 70-130 |
| 1,2-Dichloroethane-d4 | 80 | 70-130 |
| 4-Bromofluorobenzene | 103 | 70-130 |

eurofins | Air Toxics

**Client Sample ID: VMP-49-10-020113**

**Lab ID#: 1302070A-18A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p021126** | **Date of Collection: 2/1/13 10:27:00 AM** | |
| **Dil. Factor:** | **2.64** | **Date of Analysis: 2/11/13 10:24 PM** | |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 1.3 | 0.42 J | 6.5 | 2.1 J |
| Freon 114 | 1.3 | Not Detected | 9.2 | Not Detected |
| Chloromethane | 13 | Not Detected | 27 | Not Detected |
| Vinyl Chloride | 1.3 | Not Detected | 3.4 | Not Detected |
| 1,3-Butadiene | 1.3 | Not Detected | 2.9 | Not Detected |
| Bromomethane | 13 | Not Detected | 51 | Not Detected |
| Chloroethane | 5.3 | Not Detected | 14 | Not Detected |
| Freon 11 | 1.3 | 0.17 J | 7.4 | 0.98 J |
| Ethanol | 5.3 | Not Detected | 9.9 | Not Detected |
| Freon 113 | 1.3 | Not Detected | 10 | Not Detected |
| 1,1-Dichloroethene | 1.3 | Not Detected | 5.2 | Not Detected |
| Acetone | 13 | 3.6 J | 31 | 8.4 J |
| 2-Propanol | 5.3 | 0.73 J | 13 | 1.8 J |
| Carbon Disulfide | 5.3 | ~~0.92 J~~ U | 16 | ~~2.9 J~~ U |
| 3-Chloropropene | 5.3 | Not Detected | 16 | Not Detected |
| Methylene Chloride | 13 | ~~0.26 J~~ U | 46 | ~~0.92 J~~ U |
| Methyl tert-butyl ether | 1.3 | Not Detected | 4.8 | Not Detected |
| trans-1,2-Dichloroethene | 1.3 | Not Detected | 5.2 | Not Detected |
| Hexane | 1.3 | 0.45 J | 4.6 | 1.6 J |
| 1,1-Dichloroethane | 1.3 | Not Detected | 5.3 | Not Detected |
| 2-Butanone (Methyl Ethyl Ketone) | 5.3 | Not Detected | 16 | Not Detected |
| cis-1,2-Dichloroethene | 1.3 | Not Detected | 5.2 | Not Detected |
| Tetrahydrofuran | 1.3 | Not Detected | 3.9 | Not Detected |
| Chloroform | 1.3 | Not Detected | 6.4 | Not Detected |
| 1,1,1-Trichloroethane | 1.3 | Not Detected | 7.2 | Not Detected |
| Cyclohexane | 1.3 | Not Detected | 4.5 | Not Detected |
| Carbon Tetrachloride | 1.3 | Not Detected | 8.3 | Not Detected |
| 2,2,4-Trimethylpentane | 1.3 | Not Detected | 6.2 | Not Detected |
| Benzene | 1.3 | 10 | 4.2 | 33 |
| 1,2-Dichloroethane | 1.3 | Not Detected | 5.3 | Not Detected |
| Heptane | 1.3 | Not Detected | 5.4 | Not Detected |
| Trichloroethene | 1.3 | Not Detected | 7.1 | Not Detected |
| 1,2-Dichloropropane | 1.3 | Not Detected | 6.1 | Not Detected |
| 1,4-Dioxane | 5.3 | Not Detected | 19 | Not Detected |
| Bromodichloromethane | 1.3 | Not Detected | 8.8 | Not Detected |
| cis-1,3-Dichloropropene | 1.3 | Not Detected | 6.0 | Not Detected |
| 4-Methyl-2-pentanone | 1.3 | Not Detected | 5.4 | Not Detected |
| Toluene | 1.3 | ~~0.15 J~~ U | 5.0 | ~~0.58 J~~ U |
| trans-1,3-Dichloropropene | 1.3 | Not Detected | 6.0 | Not Detected |
| 1,1,2-Trichloroethane | 1.3 | Not Detected | 7.2 | Not Detected |
| Tetrachloroethene | 1.3 | ~~0.15 J~~ U | 9.0 | ~~1.0 J~~ U |
| 2-Hexanone | 5.3 | Not Detected | 22 | Not Detected |

eurofins | Air Toxics

**Client Sample ID: VMP-49-10-020113**

**Lab ID#: 1302070A-18A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p021126** | **Date of Collection: 2/1/13 10:27:00 AM** | |
| **Dil. Factor:** | **2.64** | **Date of Analysis: 2/11/13 10:24 PM** | |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Dibromochloromethane | 1.3 | Not Detected | 11 | Not Detected |
| 1,2-Dibromoethane (EDB) | 1.3 | Not Detected | 10 | Not Detected |
| Chlorobenzene | 1.3 | Not Detected | 6.1 | Not Detected |
| Ethyl Benzene | 1.3 | ~~0.23 J~~ | 5.7 | ~~0.98 J~~ |
| m,p-Xylene | 1.3 | ~~0.56 J~~ | 5.7 | ~~2.4 J~~ |
| o-Xylene | 1.3 | Not Detected | 5.7 | Not Detected |
| Styrene | 1.3 | Not Detected | 5.6 | Not Detected |
| Bromoform | 1.3 | Not Detected | 14 | Not Detected |
| Cumene | 1.3 | ~~0.34 J~~ | 6.5 | ~~1.7 J~~ |
| 1,1,2,2-Tetrachloroethane | 1.3 | Not Detected | 9.1 | Not Detected |
| Propylbenzene | 1.3 | ~~0.43 J~~ | 6.5 | ~~2.1 J~~ |
| 4-Ethyltoluene | 1.3 | ~~0.66 J~~ | 6.5 | ~~3.3 J~~ |
| 1,3,5-Trimethylbenzene | 1.3 | ~~0.56 J~~ | 6.5 | ~~2.8 J~~ |
| 1,2,4-Trimethylbenzene | 1.3 | 1.7 | 6.5 | 8.5 |
| 1,3-Dichlorobenzene | 1.3 | Not Detected | 7.9 | Not Detected |
| 1,4-Dichlorobenzene | 1.3 | Not Detected | 7.9 | Not Detected |
| alpha-Chlorotoluene | 1.3 | Not Detected | 6.8 | Not Detected |
| 1,2-Dichlorobenzene | 1.3 | Not Detected | 7.9 | Not Detected |
| 1,2,4-Trichlorobenzene | 5.3 | ~~0.38 J~~ | 39 | ~~2.8 J~~ |
| Hexachlorobutadiene | 5.3 | Not Detected | 56 | Not Detected |
| Butane | 5.3 | 2.0 J | 12 | 4.8 J |
| Isopentane | 5.3 | 0.68 J | 16 | 2.0 J |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| Toluene-d8 | 97 | 70-130 |
| 1,2-Dichloroethane-d4 | 79 | 70-130 |
| 4-Bromofluorobenzene | 101 | 70-130 |

eurofins | Air Toxics

**Client Sample ID: VMP-49-20-020113**

**Lab ID#: 1302070A-19A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p021127** | **Date of Collection:** | **2/1/13 11:16:00 AM** |
| **Dil. Factor:** | **2.58** | **Date of Analysis:** | **2/11/13 10:49 PM** |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 1.3 | 0.48 J | 6.4 | 2.4 J |
| Freon 114 | 1.3 | Not Detected | 9.0 | Not Detected |
| Chloromethane | 13 | Not Detected | 27 | Not Detected |
| Vinyl Chloride | 1.3 | Not Detected | 3.3 | Not Detected |
| 1,3-Butadiene | 1.3 | Not Detected | 2.8 | Not Detected |
| Bromomethane | 13 | Not Detected | 50 | Not Detected |
| Chloroethane | 5.2 | Not Detected | 14 | Not Detected |
| Freon 11 | 1.3 | 0.20 J | 7.2 | 1.1 J |
| Ethanol | 5.2 | 1.3 J | 9.7 | 2.4 J |
| Freon 113 | 1.3 | Not Detected | 9.9 | Not Detected |
| 1,1-Dichloroethene | 1.3 | Not Detected | 5.1 | Not Detected |
| Acetone | 13 | 5.8 J | 31 | 14 J |
| 2-Propanol | 5.2 | 0.70 J | 13 | 1.7 J |
| Carbon Disulfide | 5.2 | ~~1.0 J~~ U | 16 | ~~3.2 J~~ U |
| 3-Chloropropene | 5.2 | Not Detected | 16 | Not Detected |
| Methylene Chloride | 13 | ~~0.28 J~~ U | 45 | ~~0.98 J~~ U |
| Methyl tert-butyl ether | 1.3 | Not Detected | 4.6 | Not Detected |
| trans-1,2-Dichloroethene | 1.3 | Not Detected | 5.1 | Not Detected |
| Hexane | 1.3 | 0.61 J | 4.5 | 2.1 J |
| 1,1-Dichloroethane | 1.3 | Not Detected | 5.2 | Not Detected |
| 2-Butanone (Methyl Ethyl Ketone) | 5.2 | Not Detected | 15 | Not Detected |
| cis-1,2-Dichloroethene | 1.3 | Not Detected | 5.1 | Not Detected |
| Tetrahydrofuran | 1.3 | Not Detected | 3.8 | Not Detected |
| Chloroform | 1.3 | Not Detected | 6.3 | Not Detected |
| 1,1,1-Trichloroethane | 1.3 | Not Detected | 7.0 | Not Detected |
| Cyclohexane | 1.3 | Not Detected | 4.4 | Not Detected |
| Carbon Tetrachloride | 1.3 | Not Detected | 8.1 | Not Detected |
| 2,2,4-Trimethylpentane | 1.3 | 0.72 J | 6.0 | 3.4 J |
| Benzene | 1.3 | Not Detected | 4.1 | Not Detected |
| 1,2-Dichloroethane | 1.3 | Not Detected | 5.2 | Not Detected |
| Heptane | 1.3 | 0.35 J | 5.3 | 1.4 J |
| Trichloroethene | 1.3 | Not Detected | 6.9 | Not Detected |
| 1,2-Dichloropropane | 1.3 | Not Detected | 6.0 | Not Detected |
| 1,4-Dioxane | 5.2 | Not Detected | 18 | Not Detected |
| Bromodichloromethane | 1.3 | Not Detected | 8.6 | Not Detected |
| cis-1,3-Dichloropropene | 1.3 | Not Detected | 5.8 | Not Detected |
| 4-Methyl-2-pentanone | 1.3 | Not Detected | 5.3 | Not Detected |
| Toluene | 1.3 | ~~0.28 J~~ ✓ | 4.9 | ~~1.0 J~~ ✓ |
| trans-1,3-Dichloropropene | 1.3 | Not Detected | 5.8 | Not Detected |
| 1,1,2-Trichloroethane | 1.3 | Not Detected | 7.0 | Not Detected |
| Tetrachloroethene | 1.3 | ~~0.19 J~~ U | 8.8 | ~~1.3 J~~ ✓ |
| 2-Hexanone | 5.2 | Not Detected | 21 | Not Detected |

eurofins | Air Toxics

**Client Sample ID: VMP-49-20-020113**

**Lab ID#: 1302070A-19A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p021127** | **Date of Collection: 2/1/13 11:16:00 AM** | |
| **Dil. Factor:** | **2.58** | **Date of Analysis: 2/11/13 10:49 PM** | |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Dibromochloromethane | 1.3 | Not Detected | 11 | Not Detected |
| 1,2-Dibromoethane (EDB) | 1.3 | Not Detected | 9.9 | Not Detected |
| Chlorobenzene | 1.3 | Not Detected | 5.9 | Not Detected |
| Ethyl Benzene | 1.3 | Not Detected | 5.6 | Not Detected |
| m,p-Xylene | 1.3 | Not Detected | 5.6 | Not Detected |
| o-Xylene | 1.3 | Not Detected | 5.6 | Not Detected |
| Styrene | 1.3 | Not Detected | 5.5 | Not Detected |
| Bromoform | 1.3 | Not Detected | 13 | Not Detected |
| Cumene | 1.3 | Not Detected | 6.3 | Not Detected |
| 1,1,2,2-Tetrachloroethane | 1.3 | Not Detected | 8.8 | Not Detected |
| Propylbenzene | 1.3 | Not Detected | 6.3 | Not Detected |
| 4-Ethyltoluene | 1.3 | Not Detected | 6.3 | Not Detected |
| 1,3,5-Trimethylbenzene | 1.3 | Not Detected | 6.3 | Not Detected |
| 1,2,4-Trimethylbenzene | 1.3 | Not Detected | 6.3 | Not Detected |
| 1,3-Dichlorobenzene | 1.3 | Not Detected | 7.8 | Not Detected |
| 1,4-Dichlorobenzene | 1.3 | Not Detected | 7.8 | Not Detected |
| alpha-Chlorotoluene | 1.3 | Not Detected | 6.7 | Not Detected |
| 1,2-Dichlorobenzene | 1.3 | Not Detected | 7.8 | Not Detected |
| 1,2,4-Trichlorobenzene | 5.2 | Not Detected | 38 | Not Detected |
| Hexachlorobutadiene | 5.2 | Not Detected | 55 | Not Detected |
| Butane | 5.2 | 3.3 J | 12 | 7.8 J |
| Isopentane | 5.2 | 0.98 J | 15 | 2.9 J |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| Toluene-d8 | 98 | 70-130 |
| 1,2-Dichloroethane-d4 | 82 | 70-130 |
| 4-Bromofluorobenzene | 103 | 70-130 |

eurofins | Air Toxics

**Client Sample ID: VMP-50-5-020113**

**Lab ID#: 1302070A-20A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | p021128 | **Date of Collection:** | 2/1/13 11:00:00 AM |
| **Dil. Factor:** | 2.52 | **Date of Analysis:** | 2/12/13 06:50 AM |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 1.3 | 0.56 J | 6.2 | 2.7 J |
| Freon 114 | 1.3 | Not Detected | 8.8 | Not Detected |
| Chloromethane | 13 | Not Detected | 26 | Not Detected |
| Vinyl Chloride | 1.3 | Not Detected | 3.2 | Not Detected |
| 1,3-Butadiene | 1.3 | Not Detected | 2.8 | Not Detected |
| Bromomethane | 13 | Not Detected | 49 | Not Detected |
| Chloroethane | 5.0 | Not Detected | 13 | Not Detected |
| Freon 11 | 1.3 | 0.21 J | 7.1 | 1.2 J |
| Ethanol | 5.0 | 1.9 J | 9.5 | 3.7 J |
| Freon 113 | 1.3 | Not Detected | 9.6 | Not Detected |
| 1,1-Dichloroethene | 1.3 | Not Detected | 5.0 | Not Detected |
| Acetone | 13 | 3.0 J | 30 | 7.0 J |
| 2-Propanol | 5.0 | 2.3 J | 12 | 5.7 J |
| Carbon Disulfide | 5.0 | ~~1.3 J~~ U | 16 | ~~3.9 J~~ U |
| 3-Chloropropene | 5.0 | Not Detected | 16 | Not Detected |
| Methylene Chloride | 13 | ~~0.16 J~~ U | 44 | ~~0.57 J~~ U |
| Methyl tert-butyl ether | 1.3 | Not Detected | 4.5 | Not Detected |
| trans-1,2-Dichloroethene | 1.3 | Not Detected | 5.0 | Not Detected |
| Hexane | 1.3 | 1.1 J | 4.4 | 4.0 J |
| 1,1-Dichloroethane | 1.3 | Not Detected | 5.1 | Not Detected |
| 2-Butanone (Methyl Ethyl Ketone) | 5.0 | Not Detected | 15 | Not Detected |
| cis-1,2-Dichloroethene | 1.3 | Not Detected | 5.0 | Not Detected |
| Tetrahydrofuran | 1.3 | Not Detected | 3.7 | Not Detected |
| Chloroform | 1.3 | 0.29 J | 6.2 | 1.4 J |
| 1,1,1-Trichloroethane | 1.3 | 1.4 | 6.9 | 7.8 |
| Cyclohexane | 1.3 | Not Detected | 4.3 | Not Detected |
| Carbon Tetrachloride | 1.3 | Not Detected | 7.9 | Not Detected |
| 2,2,4-Trimethylpentane | 1.3 | 2.6 | 5.9 | 12 |
| Benzene | 1.3 | 0.52 J | 4.0 | 1.7 J |
| 1,2-Dichloroethane | 1.3 | Not Detected | 5.1 | Not Detected |
| Heptane | 1.3 | 0.29 J | 5.2 | 1.2 J |
| Trichloroethene | 1.3 | Not Detected | 6.8 | Not Detected |
| 1,2-Dichloropropane | 1.3 | Not Detected | 5.8 | Not Detected |
| 1,4-Dioxane | 5.0 | Not Detected | 18 | Not Detected |
| Bromodichloromethane | 1.3 | Not Detected | 8.4 | Not Detected |
| cis-1,3-Dichloropropene | 1.3 | Not Detected | 5.7 | Not Detected |
| 4-Methyl-2-pentanone | 1.3 | Not Detected | 5.2 | Not Detected |
| Toluene | 1.3 | ~~0.16 J~~ U | 4.7 | ~~0.60 J~~ U |
| trans-1,3-Dichloropropene | 1.3 | Not Detected | 5.7 | Not Detected |
| 1,1,2-Trichloroethane | 1.3 | Not Detected | 6.9 | Not Detected |
| Tetrachloroethene | 1.3 | ~~0.26 J~~ U | 8.5 | ~~1.7 J~~ U |
| 2-Hexanone | 5.0 | Not Detected | 21 | Not Detected |

eurofins | Air Toxics

**Client Sample ID: VMP-50-5-020113**

**Lab ID#: 1302070A-20A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p021128** | **Date of Collection: 2/1/13 11:00:00 AM** | |
| **Dil. Factor:** | **2.52** | **Date of Analysis: 2/12/13 06:50 AM** | |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Dibromochloromethane | 1.3 | Not Detected | 11 | Not Detected |
| 1,2-Dibromoethane (EDB) | 1.3 | Not Detected | 9.7 | Not Detected |
| Chlorobenzene | 1.3 | Not Detected | 5.8 | Not Detected |
| Ethyl Benzene | 1.3 | Not Detected | 5.5 | Not Detected |
| m,p-Xylene | 1.3 | Not Detected | 5.5 | Not Detected |
| o-Xylene | 1.3 | Not Detected | 5.5 | Not Detected |
| Styrene | 1.3 | Not Detected | 5.4 | Not Detected |
| Bromoform | 1.3 | Not Detected | 13 | Not Detected |
| Cumene | 1.3 | Not Detected | 6.2 | Not Detected |
| 1,1,2,2-Tetrachloroethane | 1.3 | Not Detected | 8.6 | Not Detected |
| Propylbenzene | 1.3 | Not Detected | 6.2 | Not Detected |
| 4-Ethyltoluene | 1.3 | ~~0.24 J~~ | 6.2 | ~~1.2 J~~ |
| 1,3,5-Trimethylbenzene | 1.3 | Not Detected | 6.2 | Not Detected |
| 1,2,4-Trimethylbenzene | 1.3 | Not Detected | 6.2 | Not Detected |
| 1,3-Dichlorobenzene | 1.3 | ~~0.19 J~~ | 7.6 | ~~1.2 J~~ |
| 1,4-Dichlorobenzene | 1.3 | ~~0.26 J~~ | 7.6 | ~~1.6 J~~ |
| alpha-Chlorotoluene | 1.3 | Not Detected | 6.5 | Not Detected |
| 1,2-Dichlorobenzene | 1.3 | Not Detected | 7.6 | Not Detected |
| 1,2,4-Trichlorobenzene | 5.0 | ~~0.66 J~~ | 37 | ~~4.9 J~~ |
| Hexachlorobutadiene | 5.0 | Not Detected | 54 | Not Detected |
| Butane | 5.0 | 98 | 12 | 230 |
| Isopentane | 5.0 | 39 | 15 | 120 |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| Toluene-d8 | 96 | 70-130 |
| 1,2-Dichloroethane-d4 | 84 | 70-130 |
| 4-Bromofluorobenzene | 98 | 70-130 |

eurofins | Air Toxics

**Client Sample ID: Lab Blank**

**Lab ID#: 1302070A-21A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p021106a** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 2/11/13 10:56 AM** | |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 0.50 | Not Detected | 2.5 | Not Detected |
| Freon 114 | 0.50 | Not Detected | 3.5 | Not Detected |
| Chloromethane | 5.0 | Not Detected | 10 | Not Detected |
| Vinyl Chloride | 0.50 | Not Detected | 1.3 | Not Detected |
| 1,3-Butadiene | 0.50 | Not Detected | 1.1 | Not Detected |
| Bromomethane | 5.0 | Not Detected | 19 | Not Detected |
| Chloroethane | 2.0 | Not Detected | 5.3 | Not Detected |
| Freon 11 | 0.50 | Not Detected | 2.8 | Not Detected |
| Ethanol | 2.0 | Not Detected | 3.8 | Not Detected |
| Freon 113 | 0.50 | Not Detected | 3.8 | Not Detected |
| 1,1-Dichloroethene | 0.50 | Not Detected | 2.0 | Not Detected |
| Acetone | 5.0 | Not Detected | 12 | Not Detected |
| 2-Propanol | 2.0 | Not Detected | 4.9 | Not Detected |
| Carbon Disulfide | 2.0 | 0.35 J | 6.2 | 1.1 J |
| 3-Chloropropene | 2.0 | Not Detected | 6.3 | Not Detected |
| Methylene Chloride | 5.0 | 0.096 J | 17 | 0.33 J |
| Methyl tert-butyl ether | 0.50 | Not Detected | 1.8 | Not Detected |
| trans-1,2-Dichloroethene | 0.50 | Not Detected | 2.0 | Not Detected |
| Hexane | 0.50 | Not Detected | 1.8 | Not Detected |
| 1,1-Dichloroethane | 0.50 | Not Detected | 2.0 | Not Detected |
| 2-Butanone (Methyl Ethyl Ketone) | 2.0 | Not Detected | 5.9 | Not Detected |
| cis-1,2-Dichloroethene | 0.50 | Not Detected | 2.0 | Not Detected |
| Tetrahydrofuran | 0.50 | Not Detected | 1.5 | Not Detected |
| Chloroform | 0.50 | Not Detected | 2.4 | Not Detected |
| 1,1,1-Trichloroethane | 0.50 | Not Detected | 2.7 | Not Detected |
| Cyclohexane | 0.50 | Not Detected | 1.7 | Not Detected |
| Carbon Tetrachloride | 0.50 | Not Detected | 3.1 | Not Detected |
| 2,2,4-Trimethylpentane | 0.50 | Not Detected | 2.3 | Not Detected |
| Benzene | 0.50 | Not Detected | 1.6 | Not Detected |
| 1,2-Dichloroethane | 0.50 | Not Detected | 2.0 | Not Detected |
| Heptane | 0.50 | Not Detected | 2.0 | Not Detected |
| Trichloroethene | 0.50 | Not Detected | 2.7 | Not Detected |
| 1,2-Dichloropropane | 0.50 | Not Detected | 2.3 | Not Detected |
| 1,4-Dioxane | 2.0 | Not Detected | 7.2 | Not Detected |
| Bromodichloromethane | 0.50 | Not Detected | 3.4 | Not Detected |
| cis-1,3-Dichloropropene | 0.50 | Not Detected | 2.3 | Not Detected |
| 4-Methyl-2-pentanone | 0.50 | Not Detected | 2.0 | Not Detected |
| Toluene | 0.50 | 0.085 J | 1.9 | 0.32 J |
| trans-1,3-Dichloropropene | 0.50 | 0.13 J | 2.3 | 0.61 J |
| 1,1,2-Trichloroethane | 0.50 | Not Detected | 2.7 | Not Detected |
| Tetrachloroethene | 0.50 | 0.13 J | 3.4 | 0.87 J |
| 2-Hexanone | 2.0 | Not Detected | 8.2 | Not Detected |

eurofins | Air Toxics

**Client Sample ID: Lab Blank**

**Lab ID#: 1302070A-21A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p021106a** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 2/11/13 10:56 AM** | |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Dibromochloromethane | 0.50 | Not Detected | 4.2 | Not Detected |
| 1,2-Dibromoethane (EDB) | 0.50 | 0.15 J | 3.8 | 1.2 J |
| Chlorobenzene | 0.50 | 0.17 J | 2.3 | 0.79 J |
| Ethyl Benzene | 0.50 | 0.13 J | 2.2 | 0.55 J |
| m,p-Xylene | 0.50 | 0.18 J | 2.2 | 0.79 J |
| o-Xylene | 0.50 | 0.15 J | 2.2 | 0.64 J |
| Styrene | 0.50 | 0.14 J | 2.1 | 0.60 J |
| Bromoform | 0.50 | 0.18 J | 5.2 | 1.9 J |
| Cumene | 0.50 | 0.14 J | 2.4 | 0.71 J |
| 1,1,2,2-Tetrachloroethane | 0.50 | 0.24 J | 3.4 | 1.7 J |
| Propylbenzene | 0.50 | 0.23 J | 2.4 | 1.1 J |
| 4-Ethyltoluene | 0.50 | 0.20 J | 2.4 | 0.99 J |
| 1,3,5-Trimethylbenzene | 0.50 | 0.23 J | 2.4 | 1.1 J |
| 1,2,4-Trimethylbenzene | 0.50 | 0.20 J | 2.4 | 0.97 J |
| 1,3-Dichlorobenzene | 0.50 | 0.38 J | 3.0 | 2.3 J |
| 1,4-Dichlorobenzene | 0.50 | 0.40 J | 3.0 | 2.4 J |
| alpha-Chlorotoluene | 0.50 | 0.27 J | 2.6 | 1.4 J |
| 1,2-Dichlorobenzene | 0.50 | 0.39 J | 3.0 | 2.4 J |
| 1,2,4-Trichlorobenzene | 2.0 | 1.2 J | 15 | 9.0 J |
| Hexachlorobutadiene | 2.0 | 0.70 J | 21 | 7.5 J |
| Butane | 2.0 | Not Detected | 4.8 | Not Detected |
| Isopentane | 2.0 | Not Detected | 5.9 | Not Detected |

J = Estimated value.

**Container Type: NA - Not Applicable**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| Toluene-d8 | 96 | 70-130 |
| 1,2-Dichloroethane-d4 | 92 | 70-130 |
| 4-Bromofluorobenzene | 98 | 70-130 |

eurofins | Air Toxics

**Client Sample ID: CCV**
**Lab ID#: 1302070A-22A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p021102** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 2/11/13 08:54 AM** | |

| Compound | %Recovery |
|---|---|
| Freon 12 | 97 |
| Freon 114 | 101 |
| Chloromethane | 98 |
| Vinyl Chloride | 105 |
| 1,3-Butadiene | 101 |
| Bromomethane | 103 |
| Chloroethane | 102 |
| Freon 11 | 96 |
| Ethanol | 100 |
| Freon 113 | 100 |
| 1,1-Dichloroethene | 102 |
| Acetone | 103 |
| 2-Propanol | 105 |
| Carbon Disulfide | 100 |
| 3-Chloropropene | 104 |
| Methylene Chloride | 100 |
| Methyl tert-butyl ether | 118 |
| trans-1,2-Dichloroethene | 107 |
| Hexane | 109 |
| 1,1-Dichloroethane | 100 |
| 2-Butanone (Methyl Ethyl Ketone) | 105 |
| cis-1,2-Dichloroethene | 111 |
| Tetrahydrofuran | 114 |
| Chloroform | 97 |
| 1,1,1-Trichloroethane | 100 |
| Cyclohexane | 116 |
| Carbon Tetrachloride | 98 |
| 2,2,4-Trimethylpentane | 112 |
| Benzene | 101 |
| 1,2-Dichloroethane | 94 |
| Heptane | 113 |
| Trichloroethene | 84 |
| 1,2-Dichloropropane | 102 |
| 1,4-Dioxane | 110 |
| Bromodichloromethane | 96 |
| cis-1,3-Dichloropropene | 105 |
| 4-Methyl-2-pentanone | 117 |
| Toluene | 99 |
| trans-1,3-Dichloropropene | 105 |
| 1,1,2-Trichloroethane | 100 |
| Tetrachloroethene | 96 |
| 2-Hexanone | 109 |

eurofins | Air Toxics

**Client Sample ID: CCV**

**Lab ID#: 1302070A-22A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p021102** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 2/11/13 08:54 AM** | |

| Compound | %Recovery |
|---|---|
| Dibromochloromethane | 102 |
| 1,2-Dibromoethane (EDB) | 100 |
| Chlorobenzene | 94 |
| Ethyl Benzene | 105 |
| m,p-Xylene | 108 |
| o-Xylene | 110 |
| Styrene | 114 |
| Bromoform | 102 |
| Cumene | 111 |
| 1,1,2,2-Tetrachloroethane | 109 |
| Propylbenzene | 105 |
| 4-Ethyltoluene | 109 |
| 1,3,5-Trimethylbenzene | 114 |
| 1,2,4-Trimethylbenzene | 111 |
| 1,3-Dichlorobenzene | 101 |
| 1,4-Dichlorobenzene | 100 |
| alpha-Chlorotoluene | 109 |
| 1,2-Dichlorobenzene | 102 |
| 1,2,4-Trichlorobenzene | 100 |
| Hexachlorobutadiene | 97 |
| Butane | 99 |
| Isopentane | 104 |

**Container Type: NA - Not Applicable**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| Toluene-d8 | 101 | 70-130 |
| 1,2-Dichloroethane-d4 | 96 | 70-130 |
| 4-Bromofluorobenzene | 101 | 70-130 |

eurofins | Air Toxics

**Client Sample ID: LCS**
**Lab ID#: 1302070A-23A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p021103** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 2/11/13 09:24 AM** | |

| Compound | %Recovery |
|---|---|
| Freon 12 | 96 |
| Freon 114 | 100 |
| Chloromethane | 101 |
| Vinyl Chloride | 108 |
| 1,3-Butadiene | 101 |
| Bromomethane | 103 |
| Chloroethane | 101 |
| Freon 11 | 94 |
| Ethanol | 80 |
| Freon 113 | 100 |
| 1,1-Dichloroethene | 109 |
| Acetone | 104 |
| 2-Propanol | 104 |
| Carbon Disulfide | 122 |
| 3-Chloropropene | 123 |
| Methylene Chloride | 98 |
| Methyl tert-butyl ether | 114 |
| trans-1,2-Dichloroethene | 118 |
| Hexane | 114 |
| 1,1-Dichloroethane | 99 |
| 2-Butanone (Methyl Ethyl Ketone) | 101 |
| cis-1,2-Dichloroethene | 110 |
| Tetrahydrofuran | 107 |
| Chloroform | 99 |
| 1,1,1-Trichloroethane | 100 |
| Cyclohexane | 117 |
| Carbon Tetrachloride | 96 |
| 2,2,4-Trimethylpentane | 110 |
| Benzene | 104 |
| 1,2-Dichloroethane | 93 |
| Heptane | 112 |
| Trichloroethene | 85 |
| 1,2-Dichloropropane | 101 |
| 1,4-Dioxane | 111 |
| Bromodichloromethane | 95 |
| cis-1,3-Dichloropropene | 106 |
| 4-Methyl-2-pentanone | 116 |
| Toluene | 100 |
| trans-1,3-Dichloropropene | 106 |
| 1,1,2-Trichloroethane | 99 |
| Tetrachloroethene | 97 |
| 2-Hexanone | 107 |

eurofins | Air Toxics

**Client Sample ID: LCS**

**Lab ID#: 1302070A-23A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p021103** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 2/11/13 09:24 AM** | |

| Compound | %Recovery |
|---|---|
| Dibromochloromethane | 99 |
| 1,2-Dibromoethane (EDB) | 101 |
| Chlorobenzene | 94 |
| Ethyl Benzene | 105 |
| m,p-Xylene | 111 |
| o-Xylene | 112 |
| Styrene | 115 |
| Bromoform | 98 |
| Cumene | 112 |
| 1,1,2,2-Tetrachloroethane | 110 |
| Propylbenzene | 106 |
| 4-Ethyltoluene | 104 |
| 1,3,5-Trimethylbenzene | 113 |
| 1,2,4-Trimethylbenzene | 110 |
| 1,3-Dichlorobenzene | 102 |
| 1,4-Dichlorobenzene | 101 |
| alpha-Chlorotoluene | 106 |
| 1,2-Dichlorobenzene | 104 |
| 1,2,4-Trichlorobenzene | 107 |
| Hexachlorobutadiene | 98 |
| Butane | 96 |
| Isopentane | 102 |

**Container Type: NA - Not Applicable**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| Toluene-d8 | 101 | 70-130 |
| 1,2-Dichloroethane-d4 | 94 | 70-130 |
| 4-Bromofluorobenzene | 101 | 70-130 |

eurofins | Air Toxics

**Client Sample ID: LCSD**
**Lab ID#: 1302070A-23AA**
**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p021104** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 2/11/13 09:45 AM** | |

| Compound | %Recovery |
|---|---|
| Freon 12 | 93 |
| Freon 114 | 98 |
| Chloromethane | 101 |
| Vinyl Chloride | 104 |
| 1,3-Butadiene | 98 |
| Bromomethane | 100 |
| Chloroethane | 100 |
| Freon 11 | 91 |
| Ethanol | 78 |
| Freon 113 | 97 |
| 1,1-Dichloroethene | 108 |
| Acetone | 101 |
| 2-Propanol | 103 |
| Carbon Disulfide | 119 |
| 3-Chloropropene | 119 |
| Methylene Chloride | 95 |
| Methyl tert-butyl ether | 110 |
| trans-1,2-Dichloroethene | 118 |
| Hexane | 104 |
| 1,1-Dichloroethane | 96 |
| 2-Butanone (Methyl Ethyl Ketone) | 104 |
| cis-1,2-Dichloroethene | 108 |
| Tetrahydrofuran | 104 |
| Chloroform | 96 |
| 1,1,1-Trichloroethane | 98 |
| Cyclohexane | 116 |
| Carbon Tetrachloride | 93 |
| 2,2,4-Trimethylpentane | 108 |
| Benzene | 101 |
| 1,2-Dichloroethane | 89 |
| Heptane | 109 |
| Trichloroethene | 82 |
| 1,2-Dichloropropane | 99 |
| 1,4-Dioxane | 106 |
| Bromodichloromethane | 92 |
| cis-1,3-Dichloropropene | 104 |
| 4-Methyl-2-pentanone | 114 |
| Toluene | 98 |
| trans-1,3-Dichloropropene | 103 |
| 1,1,2-Trichloroethane | 99 |
| Tetrachloroethene | 96 |
| 2-Hexanone | 106 |

eurofins | Air Toxics

**Client Sample ID: LCSD**

**Lab ID#: 1302070A-23AA**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p021104** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 2/11/13 09:45 AM** | |

| Compound | %Recovery |
|---|---|
| Dibromochloromethane | 99 |
| 1,2-Dibromoethane (EDB) | 99 |
| Chlorobenzene | 95 |
| Ethyl Benzene | 105 |
| m,p-Xylene | 111 |
| o-Xylene | 112 |
| Styrene | 117 |
| Bromoform | 98 |
| Cumene | 112 |
| 1,1,2,2-Tetrachloroethane | 111 |
| Propylbenzene | 107 |
| 4-Ethyltoluene | 106 |
| 1,3,5-Trimethylbenzene | 114 |
| 1,2,4-Trimethylbenzene | 112 |
| 1,3-Dichlorobenzene | 102 |
| 1,4-Dichlorobenzene | 102 |
| alpha-Chlorotoluene | 108 |
| 1,2-Dichlorobenzene | 104 |
| 1,2,4-Trichlorobenzene | 108 |
| Hexachlorobutadiene | 100 |
| Butane | 94 |
| Isopentane | 100 |

**Container Type: NA - Not Applicable**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| Toluene-d8 | 101 | 70-130 |
| 1,2-Dichloroethane-d4 | 91 | 70-130 |
| 4-Bromofluorobenzene | 101 | 70-130 |

# Shell Oil Products Chain Of Custody Record

URS

Air Toxics LTD.
**Project Name: Roxana Soil Vapor**
**Project # 21562850.04001**
Lab Vendor #

Please Check Appropriate Box: ☑ ENV. SERVICES ☐ MOTIVA RETAIL ☐ SHELL RETAIL ☐ MOTIVA SD&CH ☐ CONSULTANT ☐ LUBES ☐ SHELL PIPELINE ☐ OTHER

Print Bill To Contact Name: Robert Mooshegian
PO #:
INCIDENT # (ENV SERVICES): 9 7 2 1 6 6 4 0 ☐ CHECK IF NO INCIDENT # APPLIES
SAP #: 3 4 0 0 6 1
DATE: 02/01/13
PAGE: 1 of 2

SAMPLING COMPANY: URS CORPORATION
LOG CODE:
ADDRESS: 1001 HIGHLANDS PLAZA DRIVE WEST - SUITE 300; ST. LOUIS, MO 63110
SITE ADDRESS: Street and City: 900 SOUTH CENTRAL AVE – ROXANA
State: IL
GLOBAL ID NO.:
REPORT TO/DELIVERABLE TO (Name, Company, Office Location): Elizabeth Kunkel, URS, St. Louis
PHONE NO.: 314-743-4179
E-MAIL: Elizabeth.Kunkel@URSCorp.com
CONSULTANT PROJECT NAME: Roxana Soil Vapor
Manifest Address: Air Toxics, LTD 180 Blue Ravine Road, Suite B, Folsom, CA 95630-4719
TELEPHONE:
FAX: 314-429-0462
Bill To Contact E-MAIL: Robert.Mooshegian@urs.com
C. Williams, C. Kretzer, D. Mattingly, L. Rathnow, S. Jansen, M. Mittermeyer, J. Staelter, M. Corbett

TURNAROUND TIME (CALENDAR DAYS): ☑ STANDARD (14 DAY) ☐ 5 DAYS ☐ 3 DAYS ☐ 2 DAYS ☐ 24 HOURS ☐ RESULTS NEEDED ON WEEKEND
☐ LA - RWQCB REPORT FORMAT ☑ UST AGENCY:
DELIVERABLES: ☐ LEVEL 1 ☐ LEVEL 2 ☐ LEVEL 3 ☑ LEVEL 4 ☐ OTHER (SPECIFY)

☑ SHELL CONTRACT RATE APPLIES
☐ STATE REIMBURSEMENT RATE APPLIES
☐ EDD NOT NEEDED
☑ RECEIPT VERIFICATION REQUESTED

REQUESTED ANALYSIS

| Lab Use Only | Field Sample Identification | SAMPLING DATE | SAMPLING TIME | Canister Number | Canister Pressure/Vacuum Initial | Final | Receipt | Final (psi) | Modified TO-15 + Butane & Isopentane | ASTM D-1946 + Helium |
|---|---|---|---|---|---|---|---|---|---|---|
| 01 | VMP-2-5-013113 | 01/31/13 | 1305-1535 | 34092 | -30 | -9.5 | | | X | X |
| 02 | VMP-2-22-013113 | 01/31/13 | 1417-1447 | 37355 | -30 | -10 | | | X | X |
| 03 | VMP-10-10-012913 | 01/29/13 | 1003-1040 | 94318 | -29 | -8 | | | X | X |
| 04 | VMP-13-10.5-013013 | 01/30/13 | 0936-1008 | 36538 | -29 | -5.5 | | | X | X |
| 05 | VMP-13-21.5-013013 | 01/30/13 | 1041-1111 | 15725 | -29 | -9.5 | | | X | X |
| 06 | VMP-14-5-013113 | 01/31/13 | 0925-1003 | 33735 | -30 | -9.5 | | | X | X |
| 07 | VMP-14-11.5-013113 | 01/31/13 | 1013-1045 | 37394 | -30 | -8 | | | X | X |
| 08 | VMP-17-5-013113 | 01/31/13 | 1504-1534 | 8034 | -30 | -6.5 | | | X | X |
| 09 | VMP-17-5-013113-DUP | 01/31/13 | 1504-1534 | 8023 | -30 | -6.5 | | | X | X |
| 10 | VMP-19-5-013113 | 01/31/13 | 1553-1628 | 37700 | -28.5 | -9.5 | | | X | X |

Turn Around Time: ☑ Normal ☐ Rush ☐ Specify

*Lab Use Only*
Pressurized by:
Date:
Pressurization Gas: $N_2$ He

ADDITIONAL NOTES:
- 14 day hold time
- Report results between MDL and RL
- Level IV ECVP

| Relinquished by: (Signature) | Received by: (Signature) | Date | Time |
|---|---|---|---|
| | FEDEX | 2/1/13 | 1700 |
| | BWSmith Adl | 2/4/13 | 0930 |
| | | | |

Custody Seal Intact?
(Y) N None Temp N/A
Fedex

10/2006 Revision

1302070

# Shell Oil Products Chain Of Custody Record

URS

Air Toxics LTD.
**Project Name: Roxana Soil Vapor**
**Project # 21562850.04001**
Lab Vendor #

Please Check Appropriate Box:
☑ ENV. SERVICES ☐ MOTIVA RETAIL ☐ SHELL RETAIL
☐ MOTIVA SD&OM ☐ CONSULTANT ☐ LUBES
☐ SHELL PIPELINE ☐ OTHER

Print Bill To Contact Name: Robert Mooshegian
INCIDENT # (ENV SERVICES): 9 7 2 1 6 6 4 0 ☐ CHECK IF NO INCIDENT # APPLIES
PO #:
SAP #: 3 4 0 0 6 1
DATE: 02/01/13
PAGE: 2 of 2

SAMPLING COMPANY: URS CORPORATION
LOG CODE:
SITE ADDRESS: Street and City: 900 SOUTH CENTRAL AVE – ROXANA
State: IL
GLOBAL ID NO.:
ADDRESS: 1001 HIGHLANDS PLAZA DRIVE WEST - SUITE 300; ST. LOUIS, MO 63110
PROJ. MGR. TO (Name, Company, Office Location): Elizabeth Kunkel, URS, St. Louis
PHONE NO.: 314-743-4179
E-MAIL: Elizabeth_Kunkel@URSCorp.com
CONSULTANT PROJECT NAME#: Roxana Soil Vapor
Laboratory Address: Air Toxics, LTD 180 Blue Ravine Road, Suite B, Folsom, CA 95630-4719
TELEPHONE:
FAX: 314-429-0462
Bill To Contact E-MAIL: Robert.Mooshegian@urs.com
C. Williams, C. Kretzer, D. Mattingly, L. Rathnow, S. Janser, M. Mittlemeyer, J. Stoetter, M. Corbett

TURNAROUND TIME (CALENDAR DAYS):
☑ STANDARD (14 DAY) ☐ 5 DAYS ☐ 3 DAYS ☐ 2 DAYS ☐ 24 HOURS ☐ RESULTS NEEDED ON WEEKEND

☐ LA - RWQCB REPORT FORMAT ☑ UST AGENCY:

DELIVERABLES: ☐ LEVEL 1 ☐ LEVEL 2 ☐ LEVEL 3 ☑ LEVEL 4 ☐ OTHER (SPECIFY)

☑ SHELL CONTRACT RATE APPLIES
☐ STATE REIMBURSEMENT RATE APPLIES
☐ EDD NOT NEEDED
☑ RECEIPT VERIFICATION REQUESTED

REQUESTED ANALYSIS

Turn Around Time: ☑ Normal ☐ Rush Specify

*Lab Use Only*
Pressurized by:
Date:
Pressurization Gas: $N_2$ He

| LAB USE ONLY | Field Sample Identification | SAMPLING DATE | SAMPLING TIME | Canister Number | Canister Pressure/Vacuum Initial | Final | Receipt | Final (psi) | Modified TO-15 + Butane & Isopentane | ASTM D-1946 + Helium |
|---|---|---|---|---|---|---|---|---|---|---|
| 11A | VMP-42-10-013113 | 01/31/13 | 1243-1313 | 35369 | 29.5 | 6.5 | | | X | X |
| 10A | VMP-42-20-013113 | 01/31/13 | 1330-1400 | 37311 | 29 | -7.5 | | | X | X |
| 12A | VMP-42-30-013113 | 01/31/13 | 1430-1500 | 15767 | -29 | -8.5 | | | X | X |
| 14A | VMP-45-10-013013 | 01/30/13 | 1430-1500 | 3391 | -30 | -9.5 | | | X | X |
| 6A | VMP-45-20-013013 | 01/30/13 | 1515-1548 | 37763 | -30 | -8 | | | X | X |
| 16A | VMP-45-30-013013 | 01/30/13 | 1604-1635 | 21021 | -30 | -7 | | | X | X |
| 17A | VMP-49-5-020113 | 02/01/13 | 0916-0945 | 30825 | -30 | -10 | | | X | X |
| 8A | VMP-49-10-020113 | 02/01/13 | 0956-1027 | 34096 | -30 | -9.5 | | | X | X |
| 9A | VMP-49-20-020113 | 02/01/13 | 1045-1118 | 36554 | -30 | -8 | | | X | X |
| 7A | VMP-50-5-020113 | 02/01/13 | 1030-1100 | 37393 | -30 | 7.5 | | | X | X |

ADDITIONAL NOTES:
- 14 day hold time
- Report results between MDL and RL
- Level IV ECVP

| Relinquished by: (Signature) | Received by: (Signature) | Date: | Time: |
|---|---|---|---|
| | FEDEX | 2/1/13 | 1700 |
| Relinquished by: (Signature) | Received by: (Signature) | Date: | Time: |
| | BW Mattoher ATL | 2/4/13 | 0930 |
| Relinquished by: (Signature) | Received by: (Signature) | Date: | Time: |
| | Fedex | | |

Custody Seal Intact?
(Y) N None Temp N/A

05/2008 Revision

1302570

eurofins | Air Toxics

2/16/2013
Ms. Elizabeth Kunkel
URS Corporation
1001 Highlands Plaza Dr. West
Suite 300
St. Louis MO 63110

Project Name: Roxana Soil Vapor
Project #: 21562850.04001
Workorder #: 1302070B

Dear Ms. Elizabeth Kunkel

The following report includes the data for the above referenced project for sample(s) received on 2/4/2013 at Air Toxics Ltd.

The data and associated QC analyzed by Modified ASTM D-1946 are compliant with the project requirements or laboratory criteria with the exception of the deviations noted in the attached case narrative.

Thank you for choosing Air Toxics Ltd. for your air analysis needs. Air Toxics Ltd. is committed to providing accurate data of the highest quality. Please feel free to contact the Project Manager: Kelly Buettner at 916-985-1000 if you have any questions regarding the data in this report.

Regards,

Kelly Buettner

Project Manager

REVIEWED ON
3/21/13

eurofins | Air Toxics

# WORK ORDER #: 1302070B

Work Order Summary

| | | | |
|---|---|---|---|
| **CLIENT:** | Ms. Elizabeth Kunkel<br>URS Corporation<br>1001 Highlands Plaza Dr. West<br>Suite 300<br>St. Louis, MO 63110 | **BILL TO:** | Accounts Payable Austin<br>URS Corporation<br>P.O. BOX 203970<br>Austin, TX 78720-1088 |
| **PHONE:** | 314-743-4179 | **P.O. #** | 21562735.00013 |
| **FAX:** | | **PROJECT #** | 21562850.04001 Roxana Soil Vapor |
| **DATE RECEIVED:** | 02/04/2013 | **CONTACT:** | Kelly Buettner |
| **DATE COMPLETED:** | 02/16/2013 | | |

| FRACTION # | NAME | TEST | RECEIPT VAC./PRES. | FINAL PRESSURE |
|---|---|---|---|---|
| 01A | VMP-2-5-013113 | Modified ASTM D-1946 | 8.0 "Hg | 15 psi |
| 02A | VMP-2-22-013113 | Modified ASTM D-1946 | 7.5 "Hg | 15 psi |
| 03A | VMP-10-10-012913 | Modified ASTM D-1946 | 6.0 "Hg | 15 psi |
| 04A | VMP-13-10.5-013013 | Modified ASTM D-1946 | 6.0 "Hg | 15 psi |
| 05A | VMP-13-21.5-013013 | Modified ASTM D-1946 | 9.5 "Hg | 15 psi |
| 06A | VMP-14-5-013113 | Modified ASTM D-1946 | 7.5 "Hg | 15 psi |
| 07A | VMP-14-11.5-013113 | Modified ASTM D-1946 | 6.5 "Hg | 15 psi |
| 08A | VMP-17-5-013113 | Modified ASTM D-1946 | 7.0 "Hg | 15 psi |
| 09A | VMP-17-5-013113-DUP | Modified ASTM D-1946 | 7.0 "Hg | 15 psi |
| 10A | VMP-19-5-013113 | Modified ASTM D-1946 | 6.5 "Hg | 15 psi |
| 11A | VMP-42-10-013113 | Modified ASTM D-1946 | 8.5 "Hg | 15 psi |
| 12A | VMP-42-20-013113 | Modified ASTM D-1946 | 6.5 "Hg | 15 psi |
| 13A | VMP-42-30-013113 | Modified ASTM D-1946 | 8.0 "Hg | 15 psi |
| 14A | VMP-45-10-013013 | Modified ASTM D-1946 | 6.0 "Hg | 15 psi |
| 15A | VMP-45-20-013013 | Modified ASTM D-1946 | 7.0 "Hg | 15 psi |
| 16A | VMP-45-30-013013 | Modified ASTM D-1946 | 5.0 "Hg | 15 psi |
| 17A | VMP-49-5-020113 | Modified ASTM D-1946 | 7.5 "Hg | 15 psi |
| 18A | VMP-49-10-020113 | Modified ASTM D-1946 | 7.0 "Hg | 15 psi |
| 19A | VMP-49-20-020113 | Modified ASTM D-1946 | 6.5 "Hg | 15 psi |
| 20A | VMP-50-5-020113 | Modified ASTM D-1946 | 6.0 "Hg | 15 psi |
| 21A | Lab Blank | Modified ASTM D-1946 | NA | NA |
| 21B | Lab Blank | Modified ASTM D-1946 | NA | NA |
| 22A | LCS | Modified ASTM D-1946 | NA | NA |

Continued on next page

eurofins | Air Toxics

# WORK ORDER #: 1302070B

Work Order Summary

| | | | |
|---|---|---|---|
| **CLIENT:** | Ms. Elizabeth Kunkel<br>URS Corporation<br>1001 Highlands Plaza Dr. West<br>Suite 300<br>St. Louis, MO 63110 | **BILL TO:** | Accounts Payable Austin<br>URS Corporation<br>P.O. BOX 203970<br>Austin, TX 78720-1088 |
| **PHONE:** | 314-743-4179 | **P.O. #** | 21562735.00013 |
| **FAX:** | | **PROJECT #** | 21562850.04001 Roxana Soil Vapor |
| **DATE RECEIVED:** | 02/04/2013 | **CONTACT:** | Kelly Buettner |
| **DATE COMPLETED:** | 02/16/2013 | | |

| FRACTION # | NAME | TEST | RECEIPT VAC./PRES. | FINAL PRESSURE |
|---|---|---|---|---|
| 22AA | LCSD | Modified ASTM D-1946 | NA | NA |

CERTIFIED BY: Heidi Hayes DATE: 02/16/13

Technical Director

Certification numbers: AZ Licensure AZ0775, CA NELAP - 12282CA, NY NELAP - 11291,
TX NELAP - T104704434-12-4, UT NELAP CA009332012-3, WA NELAP - C935
Name of Accrediting Agency: NELAP/ORELAP (Oregon Environmental Laboratory Accreditation Program)
Accreditation number: CA300005, Effective date: 10/18/2012, Expiration date: 10/17/2013.
Eurofins Air Toxics Ltd. certifies that the test results contained in this report meet all requirements of the NELAC standards

This report shall not be reproduced, except in full, without the written approval of Eurofins Air Toxics, Inc.

180 BLUE RAVINE ROAD, SUITE B FOLSOM, CA - 9563
(916) 985-1000 . (800) 985-5955 . FAX (916) 985-1020

**LABORATORY NARRATIVE**
**Modified ASTM D-1946**
**URS Corporation**
**Workorder# 1302070B**

Twenty 1 Liter Summa Canister samples were received on February 04, 2013. The laboratory performed analysis via Modified ASTM Method D-1946 for Methane and fixed gases in air using GC/FID or GC/TCD. The method involves direct injection of 1.0 mL of sample.

On the analytical column employed for this analysis, Oxygen coelutes with Argon. The corresponding peak is quantitated as Oxygen.

Since Nitrogen is used to pressurize samples, the reported Nitrogen values are calculated by adding all the sample components and subtracting from 100%.

Method modifications taken to run these samples are summarized in the table below. Specific project requirements may over-ride the ATL modifications.

| *Requirement* | *ASTM D-1946* | *ATL Modifications* |
|---|---|---|
| Calibration | A single point calibration is performed using a reference standard closely matching the composition of the unknown. | A 3-point calibration curve is performed. Quantitation is based on a daily calibration standard which may or may not resemble the composition of the associated samples. |
| Reference Standard | The composition of any reference standard must be known to within 0.01 mol % for any component. | The standards used by ATL are blended to a >/= 95% accuracy. |
| Sample Injection Volume | Components whose concentrations are in excess of 5 % should not be analyzed by using sample volumes greater than 0.5 mL. | The sample container is connected directly to a fixed volume sample loop of 1.0 mL on the GC. Linear range is defined by the calibration curve. Bags are loaded by vacuum. |
| Normalization | Normalize the mole percent values by multiplying each value by 100 and dividing by the sum of the original values. The sum of the original values should not differ from 100% by more than 1.0%. | Results are not normalized. The sum of the reported values can differ from 100% by as much as 15%, either due to analytical variability or an unusual sample matrix. |
| Precision | Precision requirements established at each concentration level. | Duplicates should agree within 25% RPD for detections > 5 X's the RL. |

**Receiving Notes**

There were no receiving discrepancies.

**Analytical Notes**

As per project specific client request the laboratory has reported estimated values for target compound hits that are below the Reporting Limit but greater than the Method Detection Limit. Concentrations that are below the level at which the canister was certified may be false positives.

The reporting limit for Carbon Monoxide was raised from 0.010% to 0.050%.

**Definition of Data Qualifying Flags**

Seven qualifiers may have been used on the data analysis sheets and indicate as follows:
B - Compound present in laboratory blank greater than reporting limit.
J - Estimated value.
E - Exceeds instrument calibration range.
S - Saturated peak.
Q - Exceeds quality control limits.
U - Compound analyzed for but not detected above the detection limit.
M - Reported value may be biased due to apparent matrix interferences.
File extensions may have been used on the data analysis sheets and indicates as follows:
a-File was requantified
b-File was quantified by a second column and detector
r1-File was requantified for the purpose of reissue

eurofins | Air Toxics

# Summary of Detected Compounds
# NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1946

**Client Sample ID: VMP-2-5-013113**

**Lab ID#: 1302070B-01A**

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.28 | 21 |
| Nitrogen | 0.28 | 78 |
| Methane | 0.00028 | 0.00025 J |
| Carbon Dioxide | 0.028 | 0.32 |
| Helium | 0.14 | 0.22 |

**Client Sample ID: VMP-2-22-013113**

**Lab ID#: 1302070B-02A**

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.27 | 18 |
| Nitrogen | 0.27 | 80 |
| Methane | 0.00027 | 0.000019 J |
| Carbon Dioxide | 0.027 | 2.5 |

**Client Sample ID: VMP-10-10-012913**

**Lab ID#: 1302070B-03A**

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.25 | 20 |
| Nitrogen | 0.25 | 80 |
| Methane | 0.00025 | 0.000034 J |
| Carbon Dioxide | 0.025 | 0.15 |

**Client Sample ID: VMP-13-10.5-013013**

**Lab ID#: 1302070B-04A**

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.25 | 21 |
| Nitrogen | 0.25 | 79 |
| Methane | 0.00025 | 0.000075 J |
| Carbon Dioxide | 0.025 | 0.32 |

eurofins | Air Toxics

# Summary of Detected Compounds
# NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1946

**Client Sample ID: VMP-13-10.5-013013**

**Lab ID#: 1302070B-04A**

| | | |
|---|---|---|
| Helium | 0.13 | 0.075 J |

**Client Sample ID: VMP-13-21.5-013013**

**Lab ID#: 1302070B-05A**

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.30 | 20 |
| Nitrogen | 0.30 | 79 |
| Methane | 0.00030 | 0.000020 J |
| Carbon Dioxide | 0.030 | 1.4 |

**Client Sample ID: VMP-14-5-013113**

**Lab ID#: 1302070B-06A**

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.27 | 21 |
| Nitrogen | 0.27 | 79 |
| Methane | 0.00027 | 0.000058 J |
| Carbon Dioxide | 0.027 | 0.090 |
| Helium | 0.13 | 0.15 |

**Client Sample ID: VMP-14-11.5-013113**

**Lab ID#: 1302070B-07A**

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.26 | 20 |
| Nitrogen | 0.26 | 80 |
| Carbon Dioxide | 0.026 | 0.42 |
| Helium | 0.13 | 0.042 J |

**Client Sample ID: VMP-17-5-013113**

**Lab ID#: 1302070B-08A**

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|

eurofins | Air Toxics

# Summary of Detected Compounds
# NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1946

**Client Sample ID: VMP-17-5-013113**

**Lab ID#: 1302070B-08A**

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.26 | 21 |
| Nitrogen | 0.26 | 79 |
| Methane | 0.00026 | 0.00018 J |
| Carbon Dioxide | 0.026 | 0.12 |
| Helium | 0.13 | 0.026 J |

**Client Sample ID: VMP-17-5-013113-DUP**

**Lab ID#: 1302070B-09A**

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.26 | 20 |
| Nitrogen | 0.26 | 80 |
| Methane | 0.00026 | 0.00035 |
| Carbon Dioxide | 0.026 | 0.11 |
| Helium | 0.13 | 0.044 J |

**Client Sample ID: VMP-19-5-013113**

**Lab ID#: 1302070B-10A**

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.26 | 21 |
| Nitrogen | 0.26 | 79 |
| Methane | 0.00026 | 0.00042 |
| Carbon Dioxide | 0.026 | 0.15 |

**Client Sample ID: VMP-42-10-013113**

**Lab ID#: 1302070B-11A**

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.28 | 21 |
| Nitrogen | 0.28 | 78 |
| Methane | 0.00028 | 0.000027 J |

eurofins | Air Toxics

# Summary of Detected Compounds
# NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1946

**Client Sample ID: VMP-42-10-013113**

**Lab ID#: 1302070B-11A**

| | | |
|---|---|---|
| Carbon Dioxide | 0.028 | 0.45 |

**Client Sample ID: VMP-42-20-013113**

**Lab ID#: 1302070B-12A**

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.26 | 19 |
| Nitrogen | 0.26 | 78 |
| Methane | 0.00026 | 0.000020 J |
| Carbon Dioxide | 0.026 | 2.5 |

**Client Sample ID: VMP-42-30-013113**

**Lab ID#: 1302070B-13A**

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.28 | 14 |
| Nitrogen | 0.28 | 79 |
| Methane | 0.00028 | 0.00029 |
| Carbon Dioxide | 0.028 | 6.6 |

**Client Sample ID: VMP-45-10-013013**

**Lab ID#: 1302070B-14A**

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.25 | 20 |
| Nitrogen | 0.25 | 80 |
| Methane | 0.00025 | 0.000046 J |
| Carbon Dioxide | 0.025 | 0.13 |

**Client Sample ID: VMP-45-20-013013**

**Lab ID#: 1302070B-15A**

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.26 | 19 |

eurofins | Air Toxics

# Summary of Detected Compounds
# NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1946

**Client Sample ID: VMP-45-20-013013**

**Lab ID#: 1302070B-15A**

| | | |
|---|---|---|
| Nitrogen | 0.26 | 79 |
| Methane | 0.00026 | 0.0012 |
| Carbon Dioxide | 0.026 | 2.0 |

**Client Sample ID: VMP-45-30-013013**

**Lab ID#: 1302070B-16A**

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.24 | 18 |
| Nitrogen | 0.24 | 80 |
| Methane | 0.00024 | 0.00046 |
| Carbon Dioxide | 0.024 | 2.5 |

**Client Sample ID: VMP-49-5-020113**

**Lab ID#: 1302070B-17A**

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.27 | 20 |
| Nitrogen | 0.27 | 79 |
| Carbon Dioxide | 0.027 | 0.71 |

**Client Sample ID: VMP-49-10-020113**

**Lab ID#: 1302070B-18A**

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.26 | 20 |
| Nitrogen | 0.26 | 79 |
| Methane | 0.00026 | 0.000051 J |
| Carbon Dioxide | 0.026 | 0.58 |

**Client Sample ID: VMP-49-20-020113**

**Lab ID#: 1302070B-19A**

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|

eurofins | Air Toxics

# Summary of Detected Compounds
# NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1946

**Client Sample ID: VMP-49-20-020113**

**Lab ID#: 1302070B-19A**

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.26 | 20 |
| Nitrogen | 0.26 | 79 |
| Methane | 0.00026 | 0.00015 J |
| Carbon Dioxide | 0.026 | 0.39 |
| Helium | 0.13 | 0.75 |

**Client Sample ID: VMP-50-5-020113**

**Lab ID#: 1302070B-20A**

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.25 | 20 |
| Nitrogen | 0.25 | 79 |
| Methane | 0.00025 | 0.00023 J |
| Carbon Dioxide | 0.025 | 0.85 |

eurofins | Air Toxics

**Client Sample ID: VMP-2-5-013113**

**Lab ID#: 1302070B-01A**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1946**

| | | | |
|---|---|---|---|
| **File Name:** | **9021205** | **Date of Collection:** | **1/31/13 1:35:00 PM** |
| **Dil. Factor:** | **2.76** | **Date of Analysis:** | **2/12/13 10:03 AM** |

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.28 | 21 |
| Nitrogen | 0.28 | 78 |
| Carbon Monoxide | 0.14 | Not Detected |
| Methane | 0.00028 | 0.00025 J |
| Carbon Dioxide | 0.028 | 0.32 |
| Ethane | 0.0028 | Not Detected |
| Ethene | 0.0028 | Not Detected |
| Helium | 0.14 | 0.22 |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

eurofins | Air Toxics

**Client Sample ID: VMP-2-22-013113**

**Lab ID#: 1302070B-02A**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1946**

| | | | |
|---|---|---|---|
| **File Name:** | **9021206** | **Date of Collection:** | **1/31/13 2:47:00 PM** |
| **Dil. Factor:** | **2.69** | **Date of Analysis:** | **2/12/13 10:27 AM** |

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.27 | 18 |
| Nitrogen | 0.27 | 80 |
| Carbon Monoxide | 0.13 | Not Detected |
| Methane | 0.00027 | 0.000019 J |
| Carbon Dioxide | 0.027 | 2.5 |
| Ethane | 0.0027 | Not Detected |
| Ethene | 0.0027 | Not Detected |
| Helium | 0.13 | Not Detected |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

eurofins | Air Toxics

**Client Sample ID: VMP-10-10-012913**

**Lab ID#: 1302070B-03A**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1946**

| | | | |
|---|---|---|---|
| **File Name:** | **9021207** | **Date of Collection:** | **1/29/13 10:40:00 AM** |
| **Dil. Factor:** | **2.52** | **Date of Analysis:** | **2/12/13 10:58 AM** |

| **Compound** | **Rpt. Limit (%)** | **Amount (%)** |
|---|---|---|
| Oxygen | 0.25 | 20 |
| Nitrogen | 0.25 | 80 |
| Carbon Monoxide | 0.13 | Not Detected |
| Methane | 0.00025 | 0.000034 J |
| Carbon Dioxide | 0.025 | 0.15 |
| Ethane | 0.0025 | Not Detected |
| Ethene | 0.0025 | Not Detected |
| Helium | 0.13 | Not Detected |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

eurofins | Air Toxics

**Client Sample ID: VMP-13-10.5-013013**

**Lab ID#: 1302070B-04A**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1946**

| | | | |
|---|---|---|---|
| **File Name:** | **9021208** | **Date of Collection:** | **1/30/13 10:06:00 AM** |
| **Dil. Factor:** | **2.52** | **Date of Analysis:** | **2/12/13 11:20 AM** |

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.25 | 21 |
| Nitrogen | 0.25 | 79 |
| Carbon Monoxide | 0.13 | Not Detected |
| Methane | 0.00025 | 0.000075 J |
| Carbon Dioxide | 0.025 | 0.32 |
| Ethane | 0.0025 | Not Detected |
| Ethene | 0.0025 | Not Detected |
| Helium | 0.13 | 0.075 J |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

eurofins | Air Toxics

**Client Sample ID: VMP-13-21.5-013013**

**Lab ID#: 1302070B-05A**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1946**

| | | | |
|---|---|---|---|
| **File Name:** | **9021209** | **Date of Collection:** | **1/30/13 11:11:00 AM** |
| **Dil. Factor:** | **2.96** | **Date of Analysis:** | **2/12/13 11:42 AM** |

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.30 | 20 |
| Nitrogen | 0.30 | 79 |
| Carbon Monoxide | 0.15 | Not Detected |
| Methane | 0.00030 | 0.000020 J |
| Carbon Dioxide | 0.030 | 1.4 |
| Ethane | 0.0030 | Not Detected |
| Ethene | 0.0030 | Not Detected |
| Helium | 0.15 | Not Detected |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

eurofins | Air Toxics

**Client Sample ID: VMP-14-5-013113**

**Lab ID#: 1302070B-06A**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1946**

| | | | |
|---|---|---|---|
| **File Name:** | **9021210** | **Date of Collection:** | **1/31/13 10:03:00 AM** |
| **Dil. Factor:** | **2.69** | **Date of Analysis:** | **2/12/13 12:06 PM** |

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.27 | 21 |
| Nitrogen | 0.27 | 79 |
| Carbon Monoxide | 0.13 | Not Detected |
| Methane | 0.00027 | 0.000058 J |
| Carbon Dioxide | 0.027 | 0.090 |
| Ethane | 0.0027 | Not Detected |
| Ethene | 0.0027 | Not Detected |
| Helium | 0.13 | 0.15 |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

eurofins | Air Toxics

**Client Sample ID: VMP-14-11.5-013113**

**Lab ID#: 1302070B-07A**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1946**

| | | | |
|---|---|---|---|
| **File Name:** | **9021211** | **Date of Collection:** | **1/31/13 10:45:00 AM** |
| **Dil. Factor:** | **2.58** | **Date of Analysis:** | **2/12/13 12:31 PM** |

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.26 | 20 |
| Nitrogen | 0.26 | 80 |
| Carbon Monoxide | 0.13 | Not Detected |
| Methane | 0.00026 | Not Detected |
| Carbon Dioxide | 0.026 | 0.42 |
| Ethane | 0.0026 | Not Detected |
| Ethene | 0.0026 | Not Detected |
| Helium | 0.13 | 0.042 J |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

eurofins | Air Toxics

**Client Sample ID: VMP-17-5-013113**

**Lab ID#: 1302070B-08A**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1946**

| | | | |
|---|---|---|---|
| **File Name:** | **9021212** | **Date of Collection:** | **1/31/13 3:34:00 PM** |
| **Dil. Factor:** | **2.64** | **Date of Analysis:** | **2/12/13 12:54 PM** |

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.26 | 21 |
| Nitrogen | 0.26 | 79 |
| Carbon Monoxide | 0.13 | Not Detected |
| Methane | 0.00026 | 0.00018 J |
| Carbon Dioxide | 0.026 | 0.12 |
| Ethane | 0.0026 | Not Detected |
| Ethene | 0.0026 | Not Detected |
| Helium | 0.13 | 0.026 J |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

eurofins | Air Toxics

**Client Sample ID: VMP-17-5-013113-DUP**

**Lab ID#: 1302070B-09A**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1946**

| | | | |
|---|---|---|---|
| **File Name:** | **9021213** | **Date of Collection:** | **1/31/13 3:34:00 PM** |
| **Dil. Factor:** | **2.64** | **Date of Analysis:** | **2/12/13 01:36 PM** |

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.26 | 20 |
| Nitrogen | 0.26 | 80 |
| Carbon Monoxide | 0.13 | Not Detected |
| Methane | 0.00026 | 0.00035 |
| Carbon Dioxide | 0.026 | 0.11 |
| Ethane | 0.0026 | Not Detected |
| Ethene | 0.0026 | Not Detected |
| Helium | 0.13 | 0.044 J |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

eurofins | Air Toxics

**Client Sample ID: VMP-19-5-013113**

**Lab ID#: 1302070B-10A**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1946**

| | | | |
|---|---|---|---|
| **File Name:** | **9021214** | **Date of Collection:** | **1/31/13 4:26:00 PM** |
| **Dil. Factor:** | **2.58** | **Date of Analysis:** | **2/12/13 02:00 PM** |

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.26 | 21 |
| Nitrogen | 0.26 | 79 |
| Carbon Monoxide | 0.13 | Not Detected |
| Methane | 0.00026 | 0.00042 |
| Carbon Dioxide | 0.026 | 0.15 |
| Ethane | 0.0026 | Not Detected |
| Ethene | 0.0026 | Not Detected |
| Helium | 0.13 | Not Detected |

**Container Type: 1 Liter Summa Canister**

eurofins | Air Toxics

**Client Sample ID: VMP-42-10-013113**

**Lab ID#: 1302070B-11A**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1946**

| | | | |
|---|---|---|---|
| **File Name:** | **9021215** | **Date of Collection:** | **1/31/13 1:13:00 PM** |
| **Dil. Factor:** | **2.82** | **Date of Analysis:** | **2/12/13 02:25 PM** |

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.28 | 21 |
| Nitrogen | 0.28 | 78 |
| Carbon Monoxide | 0.14 | Not Detected |
| Methane | 0.00028 | 0.000027 J |
| Carbon Dioxide | 0.028 | 0.45 |
| Ethane | 0.0028 | Not Detected |
| Ethene | 0.0028 | Not Detected |
| Helium | 0.14 | Not Detected |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

eurofins | Air Toxics

**Client Sample ID: VMP-42-20-013113**

**Lab ID#: 1302070B-12A**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1946**

| | | | |
|---|---|---|---|
| **File Name:** | **9021216** | **Date of Collection:** | **1/31/13 2:09:00 PM** |
| **Dil. Factor:** | **2.58** | **Date of Analysis:** | **2/12/13 03:04 PM** |

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.26 | 19 |
| Nitrogen | 0.26 | 78 |
| Carbon Monoxide | 0.13 | Not Detected |
| Methane | 0.00026 | 0.000020 J |
| Carbon Dioxide | 0.026 | 2.5 |
| Ethane | 0.0026 | Not Detected |
| Ethene | 0.0026 | Not Detected |
| Helium | 0.13 | Not Detected |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

eurofins | Air Toxics

**Client Sample ID: VMP-42-30-013113**

**Lab ID#: 1302070B-13A**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1946**

| | | | |
|---|---|---|---|
| **File Name:** | **9021217** | **Date of Collection: 1/31/13 3:00:00 PM** | |
| **Dil. Factor:** | **2.76** | **Date of Analysis: 2/12/13 03:29 PM** | |

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.28 | 14 |
| Nitrogen | 0.28 | 79 |
| Carbon Monoxide | 0.14 | Not Detected |
| Methane | 0.00028 | 0.00029 |
| Carbon Dioxide | 0.028 | 6.6 |
| Ethane | 0.0028 | Not Detected |
| Ethene | 0.0028 | Not Detected |
| Helium | 0.14 | Not Detected |

**Container Type: 1 Liter Summa Canister**

eurofins | Air Toxics

**Client Sample ID: VMP-45-10-013013**

**Lab ID#: 1302070B-14A**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1946**

| | | | |
|---|---|---|---|
| **File Name:** | **9021218** | **Date of Collection:** | **1/30/13 3:00:00 PM** |
| **Dil. Factor:** | **2.52** | **Date of Analysis:** | **2/12/13 04:07 PM** |

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.25 | 20 |
| Nitrogen | 0.25 | 80 |
| Carbon Monoxide | 0.13 | Not Detected |
| Methane | 0.00025 | 0.000046 J |
| Carbon Dioxide | 0.025 | 0.13 |
| Ethane | 0.0025 | Not Detected |
| Ethene | 0.0025 | Not Detected |
| Helium | 0.13 | Not Detected |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

eurofins | Air Toxics

**Client Sample ID: VMP-45-20-013013**

**Lab ID#: 1302070B-15A**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1946**

| | | | |
|---|---|---|---|
| **File Name:** | **9021219** | **Date of Collection:** | **1/30/13 3:46:00 PM** |
| **Dil. Factor:** | **2.64** | **Date of Analysis:** | **2/12/13 04:28 PM** |

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.26 | 19 |
| Nitrogen | 0.26 | 79 |
| Carbon Monoxide | 0.13 | Not Detected |
| Methane | 0.00026 | 0.0012 |
| Carbon Dioxide | 0.026 | 2.0 |
| Ethane | 0.0026 | Not Detected |
| Ethene | 0.0026 | Not Detected |
| Helium | 0.13 | Not Detected |

**Container Type: 1 Liter Summa Canister**

eurofins | Air Toxics

**Client Sample ID: VMP-45-30-013013**

**Lab ID#: 1302070B-16A**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1946**

| | | | |
|---|---|---|---|
| **File Name:** | **9021220** | **Date of Collection:** | **1/30/13 4:35:00 PM** |
| **Dil. Factor:** | **2.42** | **Date of Analysis:** | **2/12/13 04:52 PM** |

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.24 | 18 |
| Nitrogen | 0.24 | 80 |
| Carbon Monoxide | 0.12 | Not Detected |
| Methane | 0.00024 | 0.00046 |
| Carbon Dioxide | 0.024 | 2.5 |
| Ethane | 0.0024 | Not Detected |
| Ethene | 0.0024 | Not Detected |
| Helium | 0.12 | Not Detected |

**Container Type: 1 Liter Summa Canister**

eurofins | Air Toxics

**Client Sample ID: VMP-49-5-020113**

**Lab ID#: 1302070B-17A**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1946**

| | | | |
|---|---|---|---|
| **File Name:** | **9021221** | **Date of Collection: 2/1/13 9:45:00 AM** | |
| **Dil. Factor:** | **2.69** | **Date of Analysis: 2/12/13 05:43 PM** | |

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.27 | 20 |
| Nitrogen | 0.27 | 79 |
| Carbon Monoxide | 0.13 | Not Detected |
| Methane | 0.00027 | Not Detected |
| Carbon Dioxide | 0.027 | 0.71 |
| Ethane | 0.0027 | Not Detected |
| Ethene | 0.0027 | Not Detected |
| Helium | 0.13 | Not Detected |

**Container Type: 1 Liter Summa Canister**

eurofins | Air Toxics

**Client Sample ID: VMP-49-10-020113**

**Lab ID#: 1302070B-18A**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1946**

| | | | |
|---|---|---|---|
| **File Name:** | **9021222** | **Date of Collection: 2/1/13 10:27:00 AM** | |
| **Dil. Factor:** | **2.64** | **Date of Analysis: 2/12/13 06:04 PM** | |

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.26 | 20 |
| Nitrogen | 0.26 | 79 |
| Carbon Monoxide | 0.13 | Not Detected |
| Methane | 0.00026 | 0.000051 J |
| Carbon Dioxide | 0.026 | 0.58 |
| Ethane | 0.0026 | Not Detected |
| Ethene | 0.0026 | Not Detected |
| Helium | 0.13 | Not Detected |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

eurofins | Air Toxics

**Client Sample ID: VMP-49-20-020113**

**Lab ID#: 1302070B-19A**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1946**

| | | | |
|---|---|---|---|
| **File Name:** | **9021223** | **Date of Collection:** | **2/1/13 11:16:00 AM** |
| **Dil. Factor:** | **2.58** | **Date of Analysis:** | **2/12/13 06:30 PM** |

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.26 | 20 |
| Nitrogen | 0.26 | 79 |
| Carbon Monoxide | 0.13 | Not Detected |
| Methane | 0.00026 | 0.00015 J |
| Carbon Dioxide | 0.026 | 0.39 |
| Ethane | 0.0026 | Not Detected |
| Ethene | 0.0026 | Not Detected |
| Helium | 0.13 | 0.75 |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

eurofins | Air Toxics

**Client Sample ID: VMP-50-5-020113**

**Lab ID#: 1302070B-20A**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1946**

| | | | |
|---|---|---|---|
| **File Name:** | **9021224** | **Date of Collection:** | **2/1/13 11:00:00 AM** |
| **Dil. Factor:** | **2.52** | **Date of Analysis:** | **2/12/13 06:53 PM** |

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.25 | 20 |
| Nitrogen | 0.25 | 79 |
| Carbon Monoxide | 0.13 | Not Detected |
| Methane | 0.00025 | 0.00023 J |
| Carbon Dioxide | 0.025 | 0.85 |
| Ethane | 0.0025 | Not Detected |
| Ethene | 0.0025 | Not Detected |
| Helium | 0.13 | Not Detected |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

eurofins | Air Toxics

**Client Sample ID: Lab Blank**

**Lab ID#: 1302070B-21A**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1946**

| | | | |
|---|---|---|---|
| **File Name:** | **9021204** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 2/12/13 09:15 AM** | |

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.10 | Not Detected |
| Nitrogen | 0.10 | 0.055 J |
| Carbon Monoxide | 0.050 | Not Detected |
| Methane | 0.00010 | Not Detected |
| Carbon Dioxide | 0.010 | Not Detected |
| Ethane | 0.0010 | Not Detected |
| Ethene | 0.0010 | Not Detected |

J = Estimated value.

**Container Type: NA - Not Applicable**

eurofins | Air Toxics

**Client Sample ID: Lab Blank**

**Lab ID#: 1302070B-21B**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1946**

| | | | |
|---|---|---|---|
| **File Name:** | **9021203b** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 2/12/13 08:50 AM** | |

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Helium | 0.050 | Not Detected |

**Container Type: NA - Not Applicable**

eurofins | Air Toxics

**Client Sample ID: LCS**

**Lab ID#: 1302070B-22A**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1946**

| | | | |
|---|---|---|---|
| **File Name:** | **9021202** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 2/12/13 08:17 AM** | |

| Compound | %Recovery |
|---|---|
| Oxygen | 97 |
| Nitrogen | 100 |
| Carbon Monoxide | 98 |
| Methane | 99 |
| Carbon Dioxide | 101 |
| Ethane | 100 |
| Ethene | 96 |
| Helium | 102 |

**Container Type: NA - Not Applicable**

eurofins | Air Toxics

**Client Sample ID: LCSD**

**Lab ID#: 1302070B-22AA**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1946**

| | | | |
|---|---|---|---|
| **File Name:** | **9021226** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 2/12/13 07:42 PM** | |

| Compound | %Recovery |
|---|---|
| Oxygen | 99 |
| Nitrogen | 101 |
| Carbon Monoxide | 103 |
| Methane | 100 |
| Carbon Dioxide | 102 |
| Ethane | 102 |
| Ethene | 99 |
| Helium | 102 |

**Container Type: NA - Not Applicable**

# Shell Oil Products Chain Of Custody Record

URS

Air Toxics LTD.
**Project Name: Roxana Soil Vapor**
**Project # 21562850.04001**
Lab Vendor #

Please Check Appropriate Box:
☑ ENV. SERVICES ☐ MOTIVA RETAIL ☐ SHELL RETAIL
☐ MOTIVA SD&CM ☐ CONSULTANT ☐ LUBES
☐ SHELL PIPELINE ☐ OTHER

Print Bill To Contact Name: Robert Mooshegian
PO #:
INCIDENT # (ENV SERVICES): 9 7 2 1 6 6 4 0
SAP #: 3 4 0 0 6 1
☐ CHECK IF NO INCIDENT # APPLIES
DATE: 02/01/13
PAGE: 1 of 2

BILLING COMPANY: URS CORPORATION
LOG CODE:
ADDRESS: 1001 HIGHLANDS PLAZA DRIVE WEST - SUITE 300; ST. LOUIS, MO 63110
SITE ADDRESS: Street and City: 900 SOUTH CENTRAL AVE -- ROXANA
State: IL
GLOBAL ID NO.:
LABORATORY ADDRESS: Air Toxics, LTD 180 Blue Ravine Road, Suite B, Folsom, CA 95630-4719
EDF DELIVERABLE TO (Name, Company, Office Location): Elizabeth Kunkel, URS, St. Louis
PHONE NO.: 314-743-4179
E-MAIL: Elizabeth.Kunkel@URSCorp.com
CONSULTANT PROJECT NAME: Roxana Soil Vapor
TELEPHONE:
FAX: 314-429-0462
INVOICE E-MAIL: Robert.Mooshegian@urs.com
C. Williams, C. Kretzer, D. Mattingly, L. Rathnow, S. Jansen, M. Mittermeyer, J. Staetter, M. Corbett

TURNAROUND TIME (CALENDAR DAYS):
☑ STANDARD (14 DAY) ☐ 5 DAYS ☐ 3 DAYS ☐ 2 DAYS ☐ 24 HOURS ☐ RESULTS NEEDED ON WEEKEND

☐ LA - RWQCB REPORT FORMAT ☑ UST AGENCY:

DELIVERABLES: ☐ LEVEL 1 ☐ LEVEL 2 ☐ LEVEL 3 ☑ LEVEL 4 ☐ OTHER (SPECIFY)

☑ SHELL CONTRACT RATE APPLIES
☐ STATE REIMBURSEMENT RATE APPLIES
☐ EDD NOT NEEDED
☑ RECEIPT VERIFICATION REQUESTED

REQUESTED ANALYSIS

| LAB USE ONLY | Field Sample Identification | SAMPLING DATE | SAMPLING TIME | Canister Number | Canister Pressure/Vacuum Initial | Final | Receipt | Final (psi) | Modified TO-15 + Butane & Isopentane | ASTM D-1946 + Helium |
|---|---|---|---|---|---|---|---|---|---|---|
| 04A | VMP-2-5-013113 | 01/31/13 | 1305-1335 | 34092 | -30 | -9.5 | | | X | X |
| 04B | VMP-2-22-013113 | 01/31/13 | 1417-1447 | 37856 | -30 | -10 | | | X | X |
| 04C | VMP-10-10-012913 | 01/29/13 | 1003-1040 | 34318 | -29 | -8 | | | X | X |
| 04D | VMP-13-10.5-013013 | 01/30/13 | 0936-1008 | 36538 | -29 | -5.5 | | | X | X |
| 04E | VMP-13-21.5-013013 | 01/30/13 | 1041-1111 | 15725 | -29 | -9.5 | | | X | X |
| 04F | VMP-14-5-013113 | 01/31/13 | 0925-1003 | 33735 | -30 | -9.5 | | | X | X |
| 04G | VMP-14-11.5-013113 | 01/31/13 | 1013-1045 | 37394 | -30 | -8 | | | X | X |
| 04H | VMP-17-5-013113 | 01/31/13 | 1504-1534 | 8034 | -30 | -8.5 | | | X | X |
| 04I | VMP-17-5-013113-DUP | 01/31/13 | 1504-1534 | 8023 | -30 | -8.5 | | | X | X |
| 04J | VMP-19-5-013113 | 01/31/13 | 1553-1628 | 37700 | -28.5 | -9.5 | | | X | X |

Turn Around Time: ☑ Normal ☐ Rush Specify

*Lab Use Only*
Pressurized by:
Date:
Pressurization Gas: $N_2$ He

ADDITIONAL NOTES:
- 14 day hold time
- Report results between MDL and RL
- Level IV ECVP

| | Relinquished by: (Signature) | Received by: (Signature) | Date | Time |
|---|---|---|---|---|
| 1 | | FEDEX | 2/1/13 | 1700 |
| 2 | | | 2/4/13 | 0930 |
| 3 | | | | |

Custody Seal Intact?
(Y) N None Temp NA
Feder

05/2008 Revision

1302070

# Shell Oil Products Chain Of Custody Record

URS

Air Toxics LTD.
**Project Name: Roxana Soil Vapor**
**Project # 21562850.04001**
Lab Vendor #

Please Check Appropriate Box:
☑ ENV. SERVICES ☐ MOTIVA RETAIL ☐ SHELL RETAIL
☐ MOTIVA SD&DM ☐ CONSULTANT ☐ LUBES
☐ SHELL PIPELINE ☐ OTHER

Print Bill To Contact Name: Robert Mooshegian
INCIDENT # (ENV SERVICES): 9 7 2 1 6 6 4 0
☐ CHECK IF NO INCIDENT # APPLIES
DATE: 02/01/13
PAGE: 2 of 2
PO #:
SAP #: 3 4 0 0 6 1

SAMPLING COMPANY: URS CORPORATION
LOG CODE:
SITE ADDRESS: Street and City: 900 SOUTH CENTRAL AVE – ROXANA
State: IL
ADDRESS: 1001 HIGHLANDS PLAZA DRIVE WEST - SUITE 300; ST. LOUIS, MO 63110
REPORT DELIVERABLE TO (Name, Company, Office Location): Elizabeth Kunkel, URS, St. Louis
PHONE NO.: 314-743-4179
E-MAIL: Elizabeth_Kunkel@URSCorp.com
CONSULTANT PROJECT NAME/#: Roxana Soil Vapor
Laboratory Address: Air Toxics, LTD 180 Blue Ravine Road, Suite B, Folsom, CA 95630-4719
TELEPHONE:
FAX: 314-429-0462
Bill To Contact E-MAIL: Robert.Mooshegian@urs.com
COPY TO: C. Williams, C. Kretzer, D. Mattingly, L. Rathnow, S. Janser, M. Mittermeyer, J. Staetter, M. Corbett

TURNAROUND TIME (CALENDAR DAYS):
☑ STANDARD (14 DAY) ☐ 5 DAYS ☐ 3 DAYS ☐ 2 DAYS ☐ 24 HOURS ☐ RESULTS NEEDED ON WEEKEND

☐ LA - RWQCB REPORT FORMAT ☑ UST AGENCY:
DELIVERABLES: ☐ LEVEL 1 ☐ LEVEL 2 ☐ LEVEL 3 ☑ LEVEL 4 ☐ OTHER (SPECIFY)

☑ SHELL CONTRACT RATE APPLIES
☐ STATE REIMBURSEMENT RATE APPLIES
☐ EDD NOT NEEDED
☑ RECEIPT VERIFICATION REQUESTED

REQUESTED ANALYSIS

| LAB USE ONLY | Field Sample Identification | SAMPLING DATE | SAMPLING TIME | Canister Number | Canister Pressure/Vacuum: Initial | Final | Receipt | Final (psi) | Modified TO-15 + Butane & Isopentane | ASTM D-1946 + Helium |
|---|---|---|---|---|---|---|---|---|---|---|
| 1A | VMP-42-10-013113 | 01/31/13 | 1243-1313 | 35969 | -29.5 | -9.5 | | | X | X |
| 2A | VMP-42-20-013113 | 01/31/13 | 1330-1400 | 37311 | -29 | -7.5 | | | X | X |
| 3A | VMP-42-30-013113 | 01/31/13 | 1430-1500 | 16767 | -29 | -8.5 | | | X | X |
| 4A | VMP-45-10-013013 | 01/30/13 | 1430-1500 | 3391 | -30 | -9.5 | | | X | X |
| 5A | VMP-45-20-013013 | 01/30/13 | 1515-1548 | 37763 | -30 | -8 | | | X | X |
| 6A | VMP-45-30-013013 | 01/30/13 | 1604-1635 | 21321 | -30 | -7 | | | X | X |
| 7A | VMP-49-5-020113 | 02/01/13 | 0915-0945 | 30825 | -30 | -10 | | | X | X |
| 8A | VMP-49-10-020113 | 02/01/13 | 0956-1027 | 34066 | -30 | -9.5 | | | X | X |
| 9A | VMP-49-20-020113 | 02/01/13 | 1045-1118 | 36554 | -30 | -8 | | | X | X |
| 10A | VMP-50-5-020113 | 02/01/13 | 1030-1100 | 37393 | -30 | -7.5 | | | X | X |

Turn Around Time: ☑ Normal ☐ Rush Specify
Lab Use Only: Pressurized by: Date: Pressurization Gas: $N_2$ He

ADDITIONAL NOTES:
- 14 day hold time
- Report results between MDL and RL
- Level IV ECVP

| Relinquished by: (Signature) | Received by: (Signature) | Date: | Time: |
|---|---|---|---|
| | FEDEX | 2/1/13 | 1700 |
| | [signature] ATL | 2/4/13 | 0930 |
| | Fedex | | |

Custody Seal Intact?
(Y) N None Temp N/A

05/2008 Revision

130270

# Roxana Soil Vapor Quarterly – 1st Quarter 2013 Data Review

**Laboratory SDG: 1302081A,B**

**Data Reviewer: Alan Fleisher**

**Peer Reviewer: Elizabeth Kunkel**

**Date Reviewed: 3/21/2013**

**Guidance: USEPA National Functional Guidelines for Superfund Organic Methods Data Review 2008**

| Sample Identification | Sample Identification |
|---|---|
| VMP-2-42-013113 | VMP-13-29.5-013013 |
| VMP-14-20-013113 | VMP-14-29-013113 |
| VMP-14-29-013113-Dup | VMP-49-30-020113 |
| VMP-50-20-020113 | VMP-50-30-020113 |

## 1.0 Data Package Completeness

*Were all items delivered as specified in the QAPP and COC as appropriate?*

Yes

## 2.0 Laboratory Case Narrative \ Cooler Receipt Form

*Were problems noted in the laboratory case narrative or cooler receipt form?*

Yes, the laboratory case narrative indicated samples VMP-2-42-013113, VMP-14-20-013113, and VMP-14-29-013113 were diluted and re-analyzed to bring the highest level target analytes within the calibration range of the instrument. Results for the highest level target analytes were reported from the re-analysis diluted runs and the remaining compounds were reported from the original analyses. Although not indicated in the laboratory case narrative, analytes were detected in the method blank. These issues are addressed further in the appropriate sections below.

No issues or discrepancies were noted in the cooler receipt form.

## 3.0 Holding Times

*Were samples extracted/analyzed within applicable limits?*

Yes

## 4.0 Blank Contamination

*Were any analytes detected in the Blanks?*

Yes

| Blank ID | Parameter | Analyte | Concentration/ Amount |
|---|---|---|---|
| 1302081A-09A | TO-15 | Carbon disulfide | 0.30 ppbv / 0.92 µg/m$^3$ |
| 1302081A-09A | TO-15 | Methylene chloride | 0.099 ppbv / 0.34 µg/m$^3$ |
| 1302081A-09A | TO-15 | 4-Ethyltoluene | 0.063 ppbv / 0.31 µg/m$^3$ |
| 1302081A-09A | TO-15 | 1,3-Dichlorobenzene | 0.13 ppbv / 0.81 µg/m$^3$ |
| 1302081A-09A | TO-15 | 1,4-Dichlorobenzene | 0.17 ppbv / 1.0 µg/m$^3$ |

| Blank ID | Parameter | Analyte | Concentration/ Amount |
|---|---|---|---|
| 1302081A-09A | TO-15 | alpha-Chlorotoluene | 0.098 ppbv / 0.51 µg/$m^3$ |
| 1302081A-09A | TO-15 | 1,2-Dichlorobenzene | 0.12 ppbv / 0.69 µg/$m^3$ |
| 1302081A-09A | TO-15 | 1,2,4-Trichlorobenzene | 0.69 ppbv / 5.1µg/$m^3$ |
| 1302081A-09A | TO-15 | Hexachlorobutadiene | 0.27 ppbv / 2.9 µg/$m^3$ |
| 1302081B-09A | Natural gases | Nitrogen | 0.083% |

Analytical data reported non-detect or at concentrations greater than five times (5X) the associated blank concentration did not require qualification. No qualification of data was required.

## 5.0 Laboratory Control Sample

*Were LCS recoveries within evaluation criteria?*

Yes

## 6.0 Surrogate Recoveries

*Were surrogate recoveries within evaluation criteria?*

Yes

## 7.0 Matrix Spike and Matrix Spike Duplicate Recoveries

*Were MS/MSD samples analyzed as part of this SDG?*

MS/MSD samples are not applicable for vapor samples, due to the inability to spike the samples.

## 8.0 Laboratory Duplicate Results

*Were laboratory duplicate samples collected as part of this SDG?*

No

## 9.0 Field Duplicate Results

*Were field duplicate samples collected as part of this SDG?*

Yes

| Field ID | Field Duplicate ID |
|---|---|
| VMP-14-29-013113 | VMP-14-29-013113-Dup |

*Were field duplicate sample RPDs within evaluation criteria?*

No

| Field ID | Field Duplicate ID | Parameter | Analyte | RPD | Qualification |
|---|---|---|---|---|---|
| VMP-14-29-013113 | VMP-14-29-013113-Dup | TO-15 | Benzene | **>50%** | **J/J** |
| VMP-14-29-013113 | VMP-14-29-013113-Dup | TO-15 | Acetone | **>2X RL** | **J/UJ** |
| VMP-14-29-013113 | VMP-14-29-013113-Dup | TO-15 | Methylene chloride | **>2X RL** | **J/UJ** |

| | | | | | |
|---|---|---|---|---|---|
| VMP-14-29-013113 | VMP-14-29-013113-Dup | TO-15 | Hexane | **>2X RL** | **J/J** |
| VMP-14-29-013113 | VMP-14-29-013113-Dup | TO-15 | Cyclohexane | **>2X RL** | **J/J** |
| VMP-14-29-013113 | VMP-14-29-013113-Dup | TO-15 | 2,2,4-Trimethylpentane | **>2X RL** | **J/J** |
| VMP-14-29-013113 | VMP-14-29-013113-Dup | TO-15 | Heptane | **>2X RL** | **J/J** |
| VMP-14-29-013113 | VMP-14-29-013113-Dup | TO-15 | Toluene | **>2X RL** | **J/UJ** |
| VMP-14-29-013113 | VMP-14-29-013113-Dup | TO-15 | Ethyl benzene | **>2X RL** | **J/UJ** |
| VMP-14-29-013113 | VMP-14-29-013113-Dup | TO-15 | m,p-Xylene | **>2X RL** | **J/UJ** |
| VMP-14-29-013113 | VMP-14-29-013113-Dup | TO-15 | Butane | **>2X RL** | **J/J** |
| VMP-14-29-013113 | VMP-14-29-013113-Dup | TO-15 | Isopentane | **>2X RL** | **J/J** |

## 10.0 Sample Dilutions

*For samples that were diluted and nondetect, were undiluted results also reported?*

Not applicable; analytes were detected in samples that were diluted.

## 11.0 Additional Qualifications

*Were additional qualifications applied?*

No

eurofins | Air Toxics

2/21/2013
Ms. Elizabeth Kunkel
URS Corporation
1001 Highlands Plaza Dr. West
Suite 300
St. Louis MO 63110

Project Name: Roxana Soil Vapor
Project #: 21562850.04001
Workorder #: 1302081A

Dear Ms. Elizabeth Kunkel

The following report includes the data for the above referenced project for sample(s) received on 2/5/2013 at Air Toxics Ltd.

The data and associated QC analyzed by Modified TO-15 are compliant with the project requirements or laboratory criteria with the exception of the deviations noted in the attached case narrative.

Thank you for choosing Air Toxics Ltd. for your air analysis needs. Air Toxics Ltd. is committed to providing accurate data of the highest quality. Please feel free to contact the Project Manager: Kelly Buettner at 916-985-1000 if you have any questions regarding the data in this report.

Regards,

Kelly Buettner

Project Manager

REVIEWED
ON
3/21/13

eurofins | Air Toxics

# WORK ORDER #: 1302081A

Work Order Summary

| | | | |
|---|---|---|---|
| **CLIENT:** | Ms. Elizabeth Kunkel<br>URS Corporation<br>1001 Highlands Plaza Dr. West<br>Suite 300<br>St. Louis, MO 63110 | **BILL TO:** | Accounts Payable Austin<br>URS Corporation<br>P.O. BOX 203970<br>Austin, TX 78720-1088 |
| **PHONE:** | 314-743-4179 | **P.O. #** | 21562735.00013 |
| **FAX:** | | **PROJECT #** | 21562850.04001 Roxana Soil Vapor |
| **DATE RECEIVED:** | 02/05/2013 | **CONTACT:** | Kelly Buettner |
| **DATE COMPLETED:** | 02/21/2013 | | |

| FRACTION # | NAME | TEST | RECEIPT VAC./PRES. | FINAL PRESSURE |
|---|---|---|---|---|
| 01A | VMP-2-42-013113 | Modified TO-15 | 5.6 "Hg | 15 psi |
| 01B | VMP-2-42-013113 | Modified TO-15 | 5.6 "Hg | 15 psi |
| 02A | VMP-13-29.5-013013 | Modified TO-15 | 6.2 "Hg | 15 psi |
| 03A | VMP-14-20-013113 | Modified TO-15 | 6.0 "Hg | 15 psi |
| 03B | VMP-14-20-013113 | Modified TO-15 | 6.0 "Hg | 15 psi |
| 04A | VMP-14-29-013113 | Modified TO-15 | 5.4 "Hg | 15 psi |
| 04B | VMP-14-29-013113 | Modified TO-15 | 5.4 "Hg | 15 psi |
| 05A | VMP-14-29-013113-DUP | Modified TO-15 | 4.4 "Hg | 15 psi |
| 06A | VMP-49-30-020113 | Modified TO-15 | 5.4 "Hg | 15 psi |
| 07A | VMP-50-20-020113 | Modified TO-15 | 7.4 "Hg | 15 psi |
| 08A | VMP-50-30-020113 | Modified TO-15 | 6.6 "Hg | 15 psi |
| 09A | Lab Blank | Modified TO-15 | NA | NA |
| 10A | CCV | Modified TO-15 | NA | NA |
| 11A | LCS | Modified TO-15 | NA | NA |
| 11AA | LCSD | Modified TO-15 | NA | NA |

CERTIFIED BY: Heidi Hayes DATE: 02/21/13

Technical Director

Certfication numbers: AZ Licensure AZ0775, CA NELAP - 12282CA, NY NELAP - 11291,
TX NELAP - T104704434-12-5, UT NELAP CA009332012-3, WA NELAP - C935
Name of Accrediting Agency: NELAP/ORELAP (Oregon Environmental Laboratory Accreditation Program)
Accreditation number: CA300005, Effective date: 10/18/2011, Expiration date: 10/17/2012.
Eurofins Air Toxics Ltd. certifies that the test results contained in this report meet all requirements of the NELAC standards

This report shall not be reproduced, except in full, without the written approval of Eurofins Air Toxics, Inc.

180 BLUE RAVINE ROAD, SUITE B FOLSOM, CA - 9563
(916) 985-1000 . (800) 985-5955 . FAX (916) 985-1020

eurofins | Air Toxics

**LABORATORY NARRATIVE**
**EPA Method TO-15**
**URS Corporation**
**Workorder# 1302081A**

Eight 1 Liter Summa Canister samples were received on February 05, 2013. The laboratory performed analysis via EPA Method TO-15 using GC/MS in the full scan mode.

This workorder was independently validated prior to submittal using 'USEPA National Functional Guidelines' as generally applied to the analysis of volatile organic compounds in air. A rules-based, logic driven, independent validation engine was employed to assess completeness, evaluate pass/fail of relevant project quality control requirements and verification of all quantified amounts.

**Receiving Notes**

There were no receiving discrepancies.

**Analytical Notes**

As per client project requirements, the laboratory has reported estimated values for target compound hits that are below the Reporting Limit but greater than the Method Detection Limit. Concentrations that are below the level at which the canister was certified may be false positives.

Dilution was performed on all of the samples due to the presence of high level target species.

Due to high-level target compounds, samples VMP-2-42-013113, VMP-14-20-013113, and VMP-14-29-013113 were analyzed twice. In the "A" fraction, the sample was diluted to bring the highest-level compounds within the calibration range. The "B" fraction is also reported by client request and may be reported with "E" flags indicating the compound exceeds the calibration range. Both runs and associated QC are reported.

**Definition of Data Qualifying Flags**

Eight qualifiers may have been used on the data analysis sheets and indicates as follows:

B - Compound present in laboratory blank greater than reporting limit (background subtraction not performed).
J - Estimated value.
E - Exceeds instrument calibration range.
S - Saturated peak.
Q - Exceeds quality control limits.
U - Compound analyzed for but not detected above the reporting limit.
UJ- Non-detected compound associated with low bias in the CCV and/or LCS.
N - The identification is based on presumptive evidence.

File extensions may have been used on the data analysis sheets and indicates as follows:

a-File was requantified
b-File was quantified by a second column and detector
r1-File was requantified for the purpose of reissue

eurofins | Air Toxics

# Summary of Detected Compounds
# EPA METHOD TO-15 GC/MS FULL SCAN

**Client Sample ID: VMP-2-42-013113**

**Lab ID#: 1302081A-01A** DF = 104,000X

* USE THESE RESULTS ONLY. ALL OTHER DATA WAS REPORTED FROM THE 26,000X DILUTION ANALYSIS

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Acetone | 520000 | 120000 J | 1200000 | 280000 J |
| 2-Propanol | 210000 | 32000 J | 510000 | 79000 J |
| Carbon Disulfide | 210000 | 22000 J | 650000 | 70000 J |
| Methylene Chloride | 520000 | 17000 J | 1800000 | 60000 J |
| Hexane | 52000 | 140000 | 180000 | 490000 |
| Cyclohexane | 52000 | 34000 J | 180000 | 120000 J |
| 2,2,4-Trimethylpentane | 52000 | 70000 | 240000 | 330000 |
| Heptane | 52000 | 19000 J | 210000 | 80000 J |
| Toluene | 52000 | 4800 J | 200000 | 18000 J |
| * Butane | 210000 | 8600000 | 490000 | 20000000 |
| Isopentane | 210000 | 4200000 | 610000 | 12000000 |

**Client Sample ID: VMP-2-42-013113**

**Lab ID#: 1302081A-01B**

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Ethanol | 52000 | 38000 J | 98000 | 72000 J |
| Acetone | 130000 | 150000 | 310000 | 350000 |
| 2-Propanol | 52000 | 37000 J | 130000 | 90000 J |
| Carbon Disulfide | 52000 | 9700 J | 160000 | 30000 J |
| Methylene Chloride | 130000 | 23000 J | 450000 | 80000 J |
| Hexane | 13000 | 180000 | 46000 | 620000 |
| Cyclohexane | 13000 | 45000 | 45000 | 150000 |
| 2,2,4-Trimethylpentane | 13000 | 90000 | 61000 | 420000 |
| Heptane | 13000 | 26000 | 53000 | 100000 |
| 4-Methyl-2-pentanone | 13000 | 8600 J | 53000 | 35000 J |
| Toluene | 13000 | 5000 J | 49000 | 19000 J |
| m,p-Xylene | 13000 | 2900 J | 56000 | 12000 J |
| Styrene | 13000 | 5200 J | 55000 | 22000 J |
| 1,1,2,2-Tetrachloroethane | 13000 | 2300 J | 89000 | 16000 J |
| Propylbenzene | 13000 | 1900 J | 64000 | 9500 J |
| 4-Ethyltoluene | 13000 | 2700 J | 64000 | 13000 J |
| 1,2,4-Trimethylbenzene | 13000 | 3000 J | 64000 | 15000 J |

eurofins | Air Toxics

# Summary of Detected Compounds
# EPA METHOD TO-15 GC/MS FULL SCAN

**Client Sample ID: VMP-2-42-013113**

**Lab ID#: 1302081A-01B** DF = 26,000X

* DO NOT USE THIS DATA. USE ALL OTHER DATA.

| | | | | |
|---|---|---|---|---|
| 1,3-Dichlorobenzene | 13000 | 4400 J | 78000 | 27000 J |
| 1,4-Dichlorobenzene | 13000 | 5400 J | 78000 | 32000 J |
| alpha-Chlorotoluene | 13000 | 4200 J | 67000 | 22000 J |
| 1,2-Dichlorobenzene | 13000 | 4100 J | 78000 | 24000 J |
| 1,2,4-Trichlorobenzene | 52000 | 12000 J | 380000 | 92000 J |
| Hexachlorobutadiene | 52000 | 4900 J | 550000 | 53000 J |
| ~~Butane~~ | ~~52000~~ | ~~9700000 E~~ | ~~120000~~ | ~~23000000 E~~ |
| Isopentane | 52000 | 4700000 | 150000 | 14000000 |

**Client Sample ID: VMP-13-29.5-013013**

**Lab ID#: 1302081A-02A**

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Ethanol | 2600 | 450 J | 4800 | 850 J |
| Acetone | 6400 | 1900 J | 15000 | 4500 J |
| 2-Propanol | 2600 | 710 J | 6300 | 1700 J |
| Carbon Disulfide | 2600 | 410 J | 8000 | 1300 J |
| Methylene Chloride | 6400 | 490 J | 22000 | 1700 J |
| Hexane | 640 | 130 J | 2200 | 460 J |
| Benzene | 640 | 180000 | 2000 | 580000 |
| 4-Methyl-2-pentanone | 640 | 150 J | 2600 | 630 J |
| Toluene | 640 | 170 J | 2400 | 650 J |
| 4-Ethyltoluene | 640 | 54 J | 3100 | 260 J |
| 1,2,4-Trichlorobenzene | 2600 | 220 J | 19000 | 1600 J |
| Isopentane | 2600 | 630 J | 7600 | 1900 J |

**Client Sample ID: VMP-14-20-013113**

**Lab ID#: 1302081A-03A**

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Acetone | 100000 | 18000 J | 240000 | 42000 J |
| Carbon Disulfide | 40000 | 4500 J | 120000 | 14000 J |
| Methylene Chloride | 100000 | 2600 J | 350000 | 9200 J |
| Hexane | 10000 | 50000 | 36000 | 170000 |

eurofins | Air Toxics

# Summary of Detected Compounds
# EPA METHOD TO-15 GC/MS FULL SCAN

* ~~USE THIS DATA ONLY.~~ USE THESE RESULTS ONLY. ALL OTHER DATA WAS REPORTED FROM THE ~~1,280X~~ 5,040X

**Client Sample ID: VMP-14-20-013113**

**Lab ID#: 1302081A-03A** DF = 20,200X

| | | | | |
|---|---|---|---|---|
| Cyclohexane | 10000 | 43000 | 35000 | 150000 |
| 2,2,4-Trimethylpentane | 10000 | 34000 | 47000 | 160000 |
| Benzene | 10000 | 3700000 | 32000 | 12000000 |
| Heptane | 10000 | 12000 | 41000 | 48000 |
| Toluene | 10000 | 1700 J | 38000 | 6300 J |
| Butane | 40000 | 160000 | 96000 | 390000 |
| Isopentane | 40000 | 570000 | 120000 | 1700000 |

**Client Sample ID: VMP-14-20-013113**

* DO NOT USE THIS DATA, USE ALL OTHER DATA.

**Lab ID#: 1302081A-03B** DF = ~~1,280X~~ 5,040X

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Ethanol | 10000 | 3500 J | 19000 | 6700 J |
| Acetone | 25000 | 15000 J | 60000 | 36000 J |
| 2-Propanol | 10000 | 3300 J | 25000 | 8200 J |
| Carbon Disulfide | 10000 | 1500 J | 31000 | 4700 J |
| Methylene Chloride | 25000 | 2200 J | 88000 | 7700 J |
| Hexane | 2500 | 49000 | 8900 | 170000 |
| Cyclohexane | 2500 | 43000 | 8700 | 150000 |
| 2,2,4-Trimethylpentane | 2500 | 31000 | 12000 | 140000 |
| * ~~Benzene~~ | ~~2500~~ | ~~3200000 E~~ | ~~8000~~ | ~~10000000 E~~ |
| Heptane | 2500 | 12000 | 10000 | 48000 |
| 4-Methyl-2-pentanone | 2500 | 1300 J | 10000 | 5300 J |
| Toluene | 2500 | 1100 J | 9500 | 4100 J |
| Styrene | 2500 | 620 J | 11000 | 2600 J |
| 1,3-Dichlorobenzene | 2500 | 480 J | 15000 | 2900 J |
| 1,4-Dichlorobenzene | 2500 | 530 J | 15000 | 3200 J |
| alpha-Chlorotoluene | 2500 | 550 J | 13000 | 2800 J |
| 1,2,4-Trichlorobenzene | 10000 | 1200 J | 75000 | 9300 J |
| Butane | 10000 | 150000 | 24000 | 350000 |
| Isopentane | 10000 | 520000 | 30000 | 1500000 |

**Client Sample ID: VMP-14-29-013113**

**Lab ID#: 1302081A-04A**

eurofins | Air Toxics

# Summary of Detected Compounds
# EPA METHOD TO-15 GC/MS FULL SCAN

**Client Sample ID: VMP-14-29-013113**

* USE THESE RESULTS ONLY. ALL OTHER RESULTS REPORTED FROM THE 19,700X DILUTION

**Lab ID#: 1302081A-04A** DF = 98,400 X

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Carbon Disulfide | 200000 | 22000 J | 610000 | 68000 J |
| Hexane | 49000 | 250000 | 170000 | 900000 |
| Cyclohexane | 49000 | 130000 | 170000 | 440000 |
| 2,2,4-Trimethylpentane | 49000 | 97000 | 230000 | 450000 |
| Benzene | 49000 | 17000000 | 160000 | 54000000 |
| Heptane | 49000 | 59000 | 200000 | 240000 |
| Butane | 200000 | 840000 | 470000 | 2000000 |
| Isopentane | 200000 | 1800000 | 580000 | 5400000 |

**Client Sample ID: VMP-14-29-013113**

* DO NOT USE THIS DATA. USE ALL OTHER DATA.

**Lab ID#: 1302081A-04B** DF = 19,700 X

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Acetone | 98000 | 12000 J | 230000 | 30000 J |
| Carbon Disulfide | 39000 | 4200 J | 120000 | 13000 J |
| Methylene Chloride | 98000 | 2200 J | 340000 | 7700 J |
| Hexane | 9800 | 280000 | 35000 | 980000 |
| Cyclohexane | 9800 | 140000 | 34000 | 480000 |
| 2,2,4-Trimethylpentane | 9800 | 100000 | 46000 | 470000 |
| * ~~Benzene~~ | ~~9800~~ | ~~16000000 E~~ | ~~31000~~ | ~~52000000 E~~ |
| Heptane | 9800 | 61000 | 40000 | 250000 |
| Toluene | 9800 | 2100 J | 37000 | 8000 J |
| Ethyl Benzene | 9800 | 3000 J | 43000 | 13000 J |
| m,p-Xylene | 9800 | 4400 J | 43000 | 19000 J |
| Butane | 39000 | 890000 | 94000 | 2100000 |
| Isopentane | 39000 | 1900000 | 120000 | 5600000 |

**Client Sample ID: VMP-14-29-013113-DUP**

**Lab ID#: 1302081A-05A**

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Carbon Disulfide | 95000 | 12000 J | 300000 | 36000 J |
| Hexane | 24000 | 48000 | 84000 | 170000 |

eurofins | Air Toxics

# Summary of Detected Compounds
# EPA METHOD TO-15 GC/MS FULL SCAN

**Client Sample ID: VMP-14-29-013113-DUP**

**Lab ID#: 1302081A-05A**

| | | | | |
|---|---|---|---|---|
| Cyclohexane | 24000 | 45000 | 82000 | 150000 |
| 2,2,4-Trimethylpentane | 24000 | 35000 | 110000 | 160000 |
| Benzene | 24000 | 4100000 | 76000 | 13000000 |
| Heptane | 24000 | 8000 J | 97000 | 33000 J |
| Butane | 95000 | 160000 | 220000 | 380000 |
| Isopentane | 95000 | 560000 | 280000 | 1600000 |

**Client Sample ID: VMP-49-30-020113**

**Lab ID#: 1302081A-06A**

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Ethanol | 250 | 100 J | 460 | 190 J |
| Acetone | 620 | 430 J | 1500 | 1000 J |
| 2-Propanol | 250 | 110 J | 600 | 270 J |
| Carbon Disulfide | 250 | 39 J | 770 | 120 J |
| Methylene Chloride | 620 | 70 J | 2100 | 240 J |
| Hexane | 62 | 21 J | 220 | 73 J |
| Cyclohexane | 62 | 160 | 210 | 540 |
| 2,2,4-Trimethylpentane | 62 | 9700 | 290 | 45000 |
| Benzene | 62 | 130 | 200 | 400 |
| 4-Methyl-2-pentanone | 62 | 28 J | 250 | 110 J |
| Toluene | 62 | 13 J | 230 | 49 J |
| Styrene | 62 | 16 J | 260 | 68 J |
| 1,2,4-Trichlorobenzene | 250 | 21 J | 1800 | 150 J |
| Butane | 250 | 2700 | 580 | 6500 |
| Isopentane | 250 | 16000 | 720 | 47000 |

**Client Sample ID: VMP-50-20-020113**

**Lab ID#: 1302081A-07A**

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Ethanol | 21 | 3.5 J | 40 | 6.6 J |
| Acetone | 54 | 8.7 J | 130 | 21 J |
| 2-Propanol | 21 | 2.9 J | 52 | 7.2 J |

eurofins | Air Toxics

# Summary of Detected Compounds
# EPA METHOD TO-15 GC/MS FULL SCAN

**Client Sample ID: VMP-50-20-020113**

**Lab ID#: 1302081A-07A**

| | | | | |
|---|---|---|---|---|
| Carbon Disulfide | 21 | 4.6 J | 67 | 14 J |
| Hexane | 5.4 | 17 | 19 | 61 |
| Cyclohexane | 5.4 | 48 | 18 | 160 |
| 2,2,4-Trimethylpentane | 5.4 | 2000 | 25 | 9200 |
| Benzene | 5.4 | 3.4 J | 17 | 11 J |
| Heptane | 5.4 | 40 | 22 | 160 |
| Toluene | 5.4 | 1.9 J | 20 | 7.3 J |
| Ethyl Benzene | 5.4 | 3.9 J | 23 | 17 J |
| m,p-Xylene | 5.4 | 1.8 J | 23 | 7.8 J |
| o-Xylene | 5.4 | 1.6 J | 23 | 7.1 J |
| Cumene | 5.4 | 0.99 J | 26 | 4.8 J |
| Propylbenzene | 5.4 | 1.4 J | 26 | 6.9 J |
| 4-Ethyltoluene | 5.4 | 1.9 J | 26 | 9.5 J |
| 1,2,4-Trimethylbenzene | 5.4 | 1.5 J | 26 | 7.5 J |
| Butane | 21 | 29 | 51 | 69 |
| Isopentane | 21 | 45 | 63 | 130 |

**Client Sample ID: VMP-50-30-020113**

**Lab ID#: 1302081A-08A**

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Ethanol | 5200 | 1900 J | 9800 | 3600 J |
| Acetone | 13000 | 6700 J | 31000 | 16000 J |
| 2-Propanol | 5200 | 1300 J | 13000 | 3300 J |
| Carbon Disulfide | 5200 | 900 J | 16000 | 2800 J |
| Methylene Chloride | 13000 | 1300 J | 45000 | 4600 J |
| Hexane | 1300 | 320000 | 4600 | 1100000 |
| Cyclohexane | 1300 | 110000 | 4400 | 370000 |
| 2,2,4-Trimethylpentane | 1300 | 96000 | 6000 | 450000 |
| Benzene | 1300 | 29000 | 4100 | 92000 |
| Heptane | 1300 | 140000 | 5300 | 570000 |
| Toluene | 1300 | 200000 | 4900 | 740000 |
| Ethyl Benzene | 1300 | 84000 | 5600 | 370000 |
| m,p-Xylene | 1300 | 160000 | 5600 | 700000 |
| o-Xylene | 1300 | 50000 | 5600 | 220000 |

eurofins | Air Toxics

# Summary of Detected Compounds
# EPA METHOD TO-15 GC/MS FULL SCAN

**Client Sample ID: VMP-50-30-020113**

**Lab ID#: 1302081A-08A**

| | | | | |
|---|---|---|---|---|
| Cumene | 1300 | 3900 | 6400 | 19000 |
| Propylbenzene | 1300 | 6100 | 6400 | 30000 |
| 4-Ethyltoluene | 1300 | 18000 | 6400 | 88000 |
| 1,3,5-Trimethylbenzene | 1300 | 4000 | 6400 | 19000 |
| 1,2,4-Trimethylbenzene | 1300 | 8000 | 6400 | 39000 |
| 1,3-Dichlorobenzene | 1300 | 180 J | 7800 | 1000 J |
| 1,2,4-Trichlorobenzene | 5200 | 570 J | 38000 | 4200 J |
| Butane | 5200 | 180000 | 12000 | 440000 |
| Isopentane | 5200 | 370000 | 15000 | 1100000 |

eurofins | Air Toxics

**Client Sample ID: VMP-2-42-013113**

**Lab ID#: 1302081A-01A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | p021210 | **Date of Collection:** | 1/31/13 3:58:00 PM |
| **Dil. Factor:** | 104000 | **Date of Analysis:** | 2/12/13 02:49 PM |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 52000 | Not Detected | 260000 | Not Detected |
| Freon 114 | 52000 | Not Detected | 360000 | Not Detected |
| Chloromethane | 520000 | Not Detected | 1100000 | Not Detected |
| Vinyl Chloride | 52000 | Not Detected | 130000 | Not Detected |
| 1,3-Butadiene | 52000 | Not Detected | 120000 | Not Detected |
| Bromomethane | 520000 | Not Detected | 2000000 | Not Detected |
| Chloroethane | 210000 | Not Detected | 550000 | Not Detected |
| Freon 11 | 52000 | Not Detected | 290000 | Not Detected |
| Ethanol | 210000 | Not Detected | 390000 | Not Detected |
| Freon 113 | 52000 | Not Detected | 400000 | Not Detected |
| 1,1-Dichloroethene | 52000 | Not Detected | 210000 | Not Detected |
| Acetone | 520000 | 120000 J | 1200000 | 280000 J |
| 2-Propanol | 210000 | 32000 J | 510000 | 79000 J |
| Carbon Disulfide | 210000 | 22000 J | 650000 | 70000 J |
| 3-Chloropropene | 210000 | Not Detected | 650000 | Not Detected |
| Methylene Chloride | 520000 | 17000 J | 1800000 | 60000 J |
| Methyl tert-butyl ether | 52000 | Not Detected | 190000 | Not Detected |
| trans-1,2-Dichloroethene | 52000 | Not Detected | 210000 | Not Detected |
| Hexane | 52000 | 140000 | 180000 | 490000 |
| 1,1-Dichloroethane | 52000 | Not Detected | 210000 | Not Detected |
| 2-Butanone (Methyl Ethyl Ketone) | 210000 | Not Detected | 610000 | Not Detected |
| cis-1,2-Dichloroethene | 52000 | Not Detected | 210000 | Not Detected |
| Tetrahydrofuran | 52000 | Not Detected | 150000 | Not Detected |
| Chloroform | 52000 | Not Detected | 250000 | Not Detected |
| 1,1,1-Trichloroethane | 52000 | Not Detected | 280000 | Not Detected |
| Cyclohexane | 52000 | 34000 J | 180000 | 120000 J |
| Carbon Tetrachloride | 52000 | Not Detected | 330000 | Not Detected |
| 2,2,4-Trimethylpentane | 52000 | 70000 | 240000 | 330000 |
| Benzene | 52000 | Not Detected | 170000 | Not Detected |
| 1,2-Dichloroethane | 52000 | Not Detected | 210000 | Not Detected |
| Heptane | 52000 | 19000 J | 210000 | 80000 J |
| Trichloroethene | 52000 | Not Detected | 280000 | Not Detected |
| 1,2-Dichloropropane | 52000 | Not Detected | 240000 | Not Detected |
| 1,4-Dioxane | 210000 | Not Detected | 750000 | Not Detected |
| Bromodichloromethane | 52000 | Not Detected | 350000 | Not Detected |
| cis-1,3-Dichloropropene | 52000 | Not Detected | 240000 | Not Detected |
| 4-Methyl-2-pentanone | 52000 | Not Detected | 210000 | Not Detected |
| Toluene | 52000 | 4800 J | 200000 | 18000 J |
| trans-1,3-Dichloropropene | 52000 | Not Detected | 240000 | Not Detected |
| 1,1,2-Trichloroethane | 52000 | Not Detected | 280000 | Not Detected |
| Tetrachloroethene | 52000 | Not Detected | 350000 | Not Detected |
| 2-Hexanone | 210000 | Not Detected | 850000 | Not Detected |

eurofins | Air Toxics

**Client Sample ID: VMP-2-42-013113**
**Lab ID#: 1302081A-01A**

* USE THESE RESULTS ONLY. ALL OTHER DATA WERE REPORTED FROM THE 26,000X DILUTION ANALYSI

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | p021210 | **Date of Collection:** | 1/31/13 3:58:00 PM |
| **Dil. Factor:** | 104000 | **Date of Analysis:** | 2/12/13 02:49 PM |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Dibromochloromethane | 52000 | Not Detected | 440000 | Not Detected |
| 1,2-Dibromoethane (EDB) | 52000 | Not Detected | 400000 | Not Detected |
| Chlorobenzene | 52000 | Not Detected | 240000 | Not Detected |
| Ethyl Benzene | 52000 | Not Detected | 220000 | Not Detected |
| m,p-Xylene | 52000 | Not Detected | 220000 | Not Detected |
| o-Xylene | 52000 | Not Detected | 220000 | Not Detected |
| Styrene | 52000 | Not Detected | 220000 | Not Detected |
| Bromoform | 52000 | Not Detected | 540000 | Not Detected |
| Cumene | 52000 | Not Detected | 260000 | Not Detected |
| 1,1,2,2-Tetrachloroethane | 52000 | Not Detected | 360000 | Not Detected |
| Propylbenzene | 52000 | Not Detected | 260000 | Not Detected |
| 4-Ethyltoluene | 52000 | Not Detected | 260000 | Not Detected |
| 1,3,5-Trimethylbenzene | 52000 | Not Detected | 260000 | Not Detected |
| 1,2,4-Trimethylbenzene | 52000 | Not Detected | 260000 | Not Detected |
| 1,3-Dichlorobenzene | 52000 | Not Detected | 310000 | Not Detected |
| 1,4-Dichlorobenzene | 52000 | Not Detected | 310000 | Not Detected |
| alpha-Chlorotoluene | 52000 | Not Detected | 270000 | Not Detected |
| 1,2-Dichlorobenzene | 52000 | Not Detected | 310000 | Not Detected |
| 1,2,4-Trichlorobenzene | 210000 | Not Detected | 1500000 | Not Detected |
| Hexachlorobutadiene | 210000 | Not Detected | 2200000 | Not Detected |
| * Butane | 210000 | 8600000 | 490000 | 20000000 |
| Isopentane | 210000 | 4200000 | 610000 | 12000000 |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| Toluene-d8 | 94 | 70-130 |
| 1,2-Dichloroethane-d4 | 82 | 70-130 |
| 4-Bromofluorobenzene | 104 | 70-130 |

eurofins | Air Toxics

**Client Sample ID: VMP-2-42-013113**

**Lab ID#: 1302081A-01B**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | p021211 | **Date of Collection:** | 1/31/13 3:58:00 PM |
| **Dil. Factor:** | 26000 | **Date of Analysis:** | 2/12/13 03:27 PM |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 13000 | Not Detected | 64000 | Not Detected |
| Freon 114 | 13000 | Not Detected | 91000 | Not Detected |
| Chloromethane | 130000 | Not Detected | 270000 | Not Detected |
| Vinyl Chloride | 13000 | Not Detected | 33000 | Not Detected |
| 1,3-Butadiene | 13000 | Not Detected | 29000 | Not Detected |
| Bromomethane | 130000 | Not Detected | 500000 | Not Detected |
| Chloroethane | 52000 | Not Detected | 140000 | Not Detected |
| Freon 11 | 13000 | Not Detected | 73000 | Not Detected |
| Ethanol | 52000 | 38000 J | 98000 | 72000 J |
| Freon 113 | 13000 | Not Detected | 100000 | Not Detected |
| 1,1-Dichloroethene | 13000 | Not Detected | 52000 | Not Detected |
| Acetone | 130000 | 150000 | 310000 | 350000 |
| 2-Propanol | 52000 | 37000 J | 130000 | 90000 J |
| Carbon Disulfide | 52000 | 9700 J | 160000 | 30000 J |
| 3-Chloropropene | 52000 | Not Detected | 160000 | Not Detected |
| Methylene Chloride | 130000 | 23000 J | 450000 | 80000 J |
| Methyl tert-butyl ether | 13000 | Not Detected | 47000 | Not Detected |
| trans-1,2-Dichloroethene | 13000 | Not Detected | 52000 | Not Detected |
| Hexane | 13000 | 180000 | 46000 | 620000 |
| 1,1-Dichloroethane | 13000 | Not Detected | 53000 | Not Detected |
| 2-Butanone (Methyl Ethyl Ketone) | 52000 | Not Detected | 150000 | Not Detected |
| cis-1,2-Dichloroethene | 13000 | Not Detected | 52000 | Not Detected |
| Tetrahydrofuran | 13000 | Not Detected | 38000 | Not Detected |
| Chloroform | 13000 | Not Detected | 63000 | Not Detected |
| 1,1,1-Trichloroethane | 13000 | Not Detected | 71000 | Not Detected |
| Cyclohexane | 13000 | 45000 | 45000 | 150000 |
| Carbon Tetrachloride | 13000 | Not Detected | 82000 | Not Detected |
| 2,2,4-Trimethylpentane | 13000 | 90000 | 61000 | 420000 |
| Benzene | 13000 | Not Detected | 42000 | Not Detected |
| 1,2-Dichloroethane | 13000 | Not Detected | 53000 | Not Detected |
| Heptane | 13000 | 26000 | 53000 | 100000 |
| Trichloroethene | 13000 | Not Detected | 70000 | Not Detected |
| 1,2-Dichloropropane | 13000 | Not Detected | 60000 | Not Detected |
| 1,4-Dioxane | 52000 | Not Detected | 190000 | Not Detected |
| Bromodichloromethane | 13000 | Not Detected | 87000 | Not Detected |
| cis-1,3-Dichloropropene | 13000 | Not Detected | 59000 | Not Detected |
| 4-Methyl-2-pentanone | 13000 | 8600 J | 53000 | 35000 J |
| Toluene | 13000 | 5000 J | 49000 | 19000 J |
| trans-1,3-Dichloropropene | 13000 | Not Detected | 59000 | Not Detected |
| 1,1,2-Trichloroethane | 13000 | Not Detected | 71000 | Not Detected |
| Tetrachloroethene | 13000 | Not Detected | 88000 | Not Detected |
| 2-Hexanone | 52000 | Not Detected | 210000 | Not Detected |

eurofins | Air Toxics

**Client Sample ID: VMP-2-42-013113**
**Lab ID#: 1302081A-01B**

*DO NOT USE THIS DATA. USE ALL OTHER DATA.

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p021211** | **Date of Collection:** | **1/31/13 3:58:00 PM** |
| **Dil. Factor:** | **26000** | **Date of Analysis:** | **2/12/13 03:27 PM** |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Dibromochloromethane | 13000 | Not Detected | 110000 | Not Detected |
| 1,2-Dibromoethane (EDB) | 13000 | Not Detected | 100000 | Not Detected |
| Chlorobenzene | 13000 | Not Detected | 60000 | Not Detected |
| Ethyl Benzene | 13000 | Not Detected | 56000 | Not Detected |
| m,p-Xylene | 13000 | 2900 J | 56000 | 12000 J |
| o-Xylene | 13000 | Not Detected | 56000 | Not Detected |
| Styrene | 13000 | 5200 J | 55000 | 22000 J |
| Bromoform | 13000 | Not Detected | 130000 | Not Detected |
| Cumene | 13000 | Not Detected | 64000 | Not Detected |
| 1,1,2,2-Tetrachloroethane | 13000 | 2300 J | 89000 | 16000 J |
| Propylbenzene | 13000 | 1900 J | 64000 | 9500 J |
| 4-Ethyltoluene | 13000 | 2700 J | 64000 | 13000 J |
| 1,3,5-Trimethylbenzene | 13000 | Not Detected | 64000 | Not Detected |
| 1,2,4-Trimethylbenzene | 13000 | 3000 J | 64000 | 15000 J |
| 1,3-Dichlorobenzene | 13000 | 4400 J | 78000 | 27000 J |
| 1,4-Dichlorobenzene | 13000 | 5400 J | 78000 | 32000 J |
| alpha-Chlorotoluene | 13000 | 4200 J | 67000 | 22000 J |
| 1,2-Dichlorobenzene | 13000 | 4100 J | 78000 | 24000 J |
| 1,2,4-Trichlorobenzene | 52000 | 12000 J | 380000 | 92000 J |
| Hexachlorobutadiene | 52000 | 4900 J | 550000 | 53000 J |
| ~~Butane~~ | ~~52000~~ | ~~9700000 E~~ | ~~120000~~ | ~~23000000 E~~ |
| Isopentane | 52000 | 4700000 | 150000 | 14000000 |

J = Estimated value.
E = Exceeds instrument calibration range.
**Container Type: 1 Liter Summa Canister**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| Toluene-d8 | 96 | 70-130 |
| 1,2-Dichloroethane-d4 | 82 | 70-130 |
| 4-Bromofluorobenzene | 101 | 70-130 |

eurofins | Air Toxics

**Client Sample ID: VMP-13-29.5-013013**

**Lab ID#: 1302081A-02A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | p021220 | **Date of Collection:** | 1/30/13 1:57:00 PM |
| **Dil. Factor:** | 1280 | **Date of Analysis:** | 2/12/13 10:34 PM |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 640 | Not Detected | 3200 | Not Detected |
| Freon 114 | 640 | Not Detected | 4500 | Not Detected |
| Chloromethane | 6400 | Not Detected | 13000 | Not Detected |
| Vinyl Chloride | 640 | Not Detected | 1600 | Not Detected |
| 1,3-Butadiene | 640 | Not Detected | 1400 | Not Detected |
| Bromomethane | 6400 | Not Detected | 25000 | Not Detected |
| Chloroethane | 2600 | Not Detected | 6800 | Not Detected |
| Freon 11 | 640 | Not Detected | 3600 | Not Detected |
| Ethanol | 2600 | 450 J | 4800 | 850 J |
| Freon 113 | 640 | Not Detected | 4900 | Not Detected |
| 1,1-Dichloroethene | 640 | Not Detected | 2500 | Not Detected |
| Acetone | 6400 | 1900 J | 15000 | 4500 J |
| 2-Propanol | 2600 | 710 J | 6300 | 1700 J |
| Carbon Disulfide | 2600 | 410 J | 8000 | 1300 J |
| 3-Chloropropene | 2600 | Not Detected | 8000 | Not Detected |
| Methylene Chloride | 6400 | 490 J | 22000 | 1700 J |
| Methyl tert-butyl ether | 640 | Not Detected | 2300 | Not Detected |
| trans-1,2-Dichloroethene | 640 | Not Detected | 2500 | Not Detected |
| Hexane | 640 | 130 J | 2200 | 460 J |
| 1,1-Dichloroethane | 640 | Not Detected | 2600 | Not Detected |
| 2-Butanone (Methyl Ethyl Ketone) | 2600 | Not Detected | 7500 | Not Detected |
| cis-1,2-Dichloroethene | 640 | Not Detected | 2500 | Not Detected |
| Tetrahydrofuran | 640 | Not Detected | 1900 | Not Detected |
| Chloroform | 640 | Not Detected | 3100 | Not Detected |
| 1,1,1-Trichloroethane | 640 | Not Detected | 3500 | Not Detected |
| Cyclohexane | 640 | Not Detected | 2200 | Not Detected |
| Carbon Tetrachloride | 640 | Not Detected | 4000 | Not Detected |
| 2,2,4-Trimethylpentane | 640 | Not Detected | 3000 | Not Detected |
| Benzene | 640 | 180000 | 2000 | 580000 |
| 1,2-Dichloroethane | 640 | Not Detected | 2600 | Not Detected |
| Heptane | 640 | Not Detected | 2600 | Not Detected |
| Trichloroethene | 640 | Not Detected | 3400 | Not Detected |
| 1,2-Dichloropropane | 640 | Not Detected | 3000 | Not Detected |
| 1,4-Dioxane | 2600 | Not Detected | 9200 | Not Detected |
| Bromodichloromethane | 640 | Not Detected | 4300 | Not Detected |
| cis-1,3-Dichloropropene | 640 | Not Detected | 2900 | Not Detected |
| 4-Methyl-2-pentanone | 640 | 150 J | 2600 | 630 J |
| Toluene | 640 | 170 J | 2400 | 650 J |
| trans-1,3-Dichloropropene | 640 | Not Detected | 2900 | Not Detected |
| 1,1,2-Trichloroethane | 640 | Not Detected | 3500 | Not Detected |
| Tetrachloroethene | 640 | Not Detected | 4300 | Not Detected |
| 2-Hexanone | 2600 | Not Detected | 10000 | Not Detected |

eurofins | Air Toxics

**Client Sample ID: VMP-13-29.5-013013**

**Lab ID#: 1302081A-02A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p021220** | **Date of Collection:** | **1/30/13 1:57:00 PM** |
| **Dil. Factor:** | **1280** | **Date of Analysis:** | **2/12/13 10:34 PM** |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Dibromochloromethane | 640 | Not Detected | 5400 | Not Detected |
| 1,2-Dibromoethane (EDB) | 640 | Not Detected | 4900 | Not Detected |
| Chlorobenzene | 640 | Not Detected | 2900 | Not Detected |
| Ethyl Benzene | 640 | Not Detected | 2800 | Not Detected |
| m,p-Xylene | 640 | Not Detected | 2800 | Not Detected |
| o-Xylene | 640 | Not Detected | 2800 | Not Detected |
| Styrene | 640 | Not Detected | 2700 | Not Detected |
| Bromoform | 640 | Not Detected | 6600 | Not Detected |
| Cumene | 640 | Not Detected | 3100 | Not Detected |
| 1,1,2,2-Tetrachloroethane | 640 | Not Detected | 4400 | Not Detected |
| Propylbenzene | 640 | Not Detected | 3100 | Not Detected |
| 4-Ethyltoluene | 640 | 54 J | 3100 | 260 J |
| 1,3,5-Trimethylbenzene | 640 | Not Detected | 3100 | Not Detected |
| 1,2,4-Trimethylbenzene | 640 | Not Detected | 3100 | Not Detected |
| 1,3-Dichlorobenzene | 640 | Not Detected | 3800 | Not Detected |
| 1,4-Dichlorobenzene | 640 | Not Detected | 3800 | Not Detected |
| alpha-Chlorotoluene | 640 | Not Detected | 3300 | Not Detected |
| 1,2-Dichlorobenzene | 640 | Not Detected | 3800 | Not Detected |
| 1,2,4-Trichlorobenzene | 2600 | 220 J | 19000 | 1600 J |
| Hexachlorobutadiene | 2600 | Not Detected | 27000 | Not Detected |
| Butane | 2600 | Not Detected | 6100 | Not Detected |
| Isopentane | 2600 | 630 J | 7600 | 1900 J |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| Toluene-d8 | 92 | 70-130 |
| 1,2-Dichloroethane-d4 | 85 | 70-130 |
| 4-Bromofluorobenzene | 105 | 70-130 |

eurofins | Air Toxics

* USE THESE RESULTS ONLY. ALL OTHER DATA WAS REPORTED FROM THE ~~1280X~~ WERE 5,040X.

**Client Sample ID: VMP-14-20-013113**

**Lab ID#: 1302081A-03A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | p021214 | **Date of Collection:** | 1/31/13 11:35:00 AM |
| **Dil. Factor:** | 20200 | **Date of Analysis:** | 2/12/13 05:40 PM |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 10000 | Not Detected | 50000 | Not Detected |
| Freon 114 | 10000 | Not Detected | 71000 | Not Detected |
| Chloromethane | 100000 | Not Detected | 210000 | Not Detected |
| Vinyl Chloride | 10000 | Not Detected | 26000 | Not Detected |
| 1,3-Butadiene | 10000 | Not Detected | 22000 | Not Detected |
| Bromomethane | 100000 | Not Detected | 390000 | Not Detected |
| Chloroethane | 40000 | Not Detected | 110000 | Not Detected |
| Freon 11 | 10000 | Not Detected | 57000 | Not Detected |
| Ethanol | 40000 | Not Detected | 76000 | Not Detected |
| Freon 113 | 10000 | Not Detected | 77000 | Not Detected |
| 1,1-Dichloroethene | 10000 | Not Detected | 40000 | Not Detected |
| Acetone | 100000 | 18000 J | 240000 | 42000 J |
| 2-Propanol | 40000 | Not Detected | 99000 | Not Detected |
| Carbon Disulfide | 40000 | 4500 J | 120000 | 14000 J |
| 3-Chloropropene | 40000 | Not Detected | 130000 | Not Detected |
| Methylene Chloride | 100000 | 2600 J | 350000 | 9200 J |
| Methyl tert-butyl ether | 10000 | Not Detected | 36000 | Not Detected |
| trans-1,2-Dichloroethene | 10000 | Not Detected | 40000 | Not Detected |
| Hexane | 10000 | 50000 | 36000 | 170000 |
| 1,1-Dichloroethane | 10000 | Not Detected | 41000 | Not Detected |
| 2-Butanone (Methyl Ethyl Ketone) | 40000 | Not Detected | 120000 | Not Detected |
| cis-1,2-Dichloroethene | 10000 | Not Detected | 40000 | Not Detected |
| Tetrahydrofuran | 10000 | Not Detected | 30000 | Not Detected |
| Chloroform | 10000 | Not Detected | 49000 | Not Detected |
| 1,1,1-Trichloroethane | 10000 | Not Detected | 55000 | Not Detected |
| Cyclohexane | 10000 | 43000 | 35000 | 150000 |
| Carbon Tetrachloride | 10000 | Not Detected | 64000 | Not Detected |
| 2,2,4-Trimethylpentane | 10000 | 34000 | 47000 | 160000 |
| Benzene | 10000 | 3700000 | 32000 | 12000000 |
| 1,2-Dichloroethane | 10000 | Not Detected | 41000 | Not Detected |
| Heptane | 10000 | 12000 | 41000 | 48000 |
| Trichloroethene | 10000 | Not Detected | 54000 | Not Detected |
| 1,2-Dichloropropane | 10000 | Not Detected | 47000 | Not Detected |
| 1,4-Dioxane | 40000 | Not Detected | 140000 | Not Detected |
| Bromodichloromethane | 10000 | Not Detected | 68000 | Not Detected |
| cis-1,3-Dichloropropene | 10000 | Not Detected | 46000 | Not Detected |
| 4-Methyl-2-pentanone | 10000 | Not Detected | 41000 | Not Detected |
| Toluene | 10000 | 1700 J | 38000 | 6300 J |
| trans-1,3-Dichloropropene | 10000 | Not Detected | 46000 | Not Detected |
| 1,1,2-Trichloroethane | 10000 | Not Detected | 55000 | Not Detected |
| Tetrachloroethene | 10000 | Not Detected | 68000 | Not Detected |
| 2-Hexanone | 40000 | Not Detected | 160000 | Not Detected |

eurofins | Air Toxics

**Client Sample ID: VMP-14-20-013113**

**Lab ID#: 1302081A-03A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p021214** | **Date of Collection:** | **1/31/13 11:35:00 AM** |
| **Dil. Factor:** | **20200** | **Date of Analysis:** | **2/12/13 05:40 PM** |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Dibromochloromethane | 10000 | Not Detected | 86000 | Not Detected |
| 1,2-Dibromoethane (EDB) | 10000 | Not Detected | 78000 | Not Detected |
| Chlorobenzene | 10000 | Not Detected | 46000 | Not Detected |
| Ethyl Benzene | 10000 | Not Detected | 44000 | Not Detected |
| m,p-Xylene | 10000 | Not Detected | 44000 | Not Detected |
| o-Xylene | 10000 | Not Detected | 44000 | Not Detected |
| Styrene | 10000 | Not Detected | 43000 | Not Detected |
| Bromoform | 10000 | Not Detected | 100000 | Not Detected |
| Cumene | 10000 | Not Detected | 50000 | Not Detected |
| 1,1,2,2-Tetrachloroethane | 10000 | Not Detected | 69000 | Not Detected |
| Propylbenzene | 10000 | Not Detected | 50000 | Not Detected |
| 4-Ethyltoluene | 10000 | Not Detected | 50000 | Not Detected |
| 1,3,5-Trimethylbenzene | 10000 | Not Detected | 50000 | Not Detected |
| 1,2,4-Trimethylbenzene | 10000 | Not Detected | 50000 | Not Detected |
| 1,3-Dichlorobenzene | 10000 | Not Detected | 61000 | Not Detected |
| 1,4-Dichlorobenzene | 10000 | Not Detected | 61000 | Not Detected |
| alpha-Chlorotoluene | 10000 | Not Detected | 52000 | Not Detected |
| 1,2-Dichlorobenzene | 10000 | Not Detected | 61000 | Not Detected |
| 1,2,4-Trichlorobenzene | 40000 | Not Detected | 300000 | Not Detected |
| Hexachlorobutadiene | 40000 | Not Detected | 430000 | Not Detected |
| Butane | 40000 | 160000 | 96000 | 390000 |
| Isopentane | 40000 | 570000 | 120000 | 1700000 |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| Toluene-d8 | 96 | 70-130 |
| 1,2-Dichloroethane-d4 | 83 | 70-130 |
| 4-Bromofluorobenzene | 103 | 70-130 |

eurofins | Air Toxics

**Client Sample ID: VMP-14-20-013113** * DO NOT USE THIS DATA.
**Lab ID#: 1302081A-03B** USE ALL OTHER DATA.

## EPA METHOD TO-15 GC/MS FULL SCAN

| | | | |
|---|---|---|---|
| **File Name:** | p021212 | **Date of Collection:** | 1/31/13 11:35:00 AM |
| **Dil. Factor:** | 5040 | **Date of Analysis:** | 2/12/13 04:07 PM |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 2500 | Not Detected | 12000 | Not Detected |
| Freon 114 | 2500 | Not Detected | 18000 | Not Detected |
| Chloromethane | 25000 | Not Detected | 52000 | Not Detected |
| Vinyl Chloride | 2500 | Not Detected | 6400 | Not Detected |
| 1,3-Butadiene | 2500 | Not Detected | 5600 | Not Detected |
| Bromomethane | 25000 | Not Detected | 98000 | Not Detected |
| Chloroethane | 10000 | Not Detected | 26000 | Not Detected |
| Freon 11 | 2500 | Not Detected | 14000 | Not Detected |
| Ethanol | 10000 | 3500 J | 19000 | 6700 J |
| Freon 113 | 2500 | Not Detected | 19000 | Not Detected |
| 1,1-Dichloroethene | 2500 | Not Detected | 10000 | Not Detected |
| Acetone | 25000 | 15000 J | 60000 | 36000 J |
| 2-Propanol | 10000 | 3300 J | 25000 | 8200 J |
| Carbon Disulfide | 10000 | 1500 J | 31000 | 4700 J |
| 3-Chloropropene | 10000 | Not Detected | 32000 | Not Detected |
| Methylene Chloride | 25000 | 2200 J | 88000 | 7700 J |
| Methyl tert-butyl ether | 2500 | Not Detected | 9100 | Not Detected |
| trans-1,2-Dichloroethene | 2500 | Not Detected | 10000 | Not Detected |
| Hexane | 2500 | 49000 | 8900 | 170000 |
| 1,1-Dichloroethane | 2500 | Not Detected | 10000 | Not Detected |
| 2-Butanone (Methyl Ethyl Ketone) | 10000 | Not Detected | 30000 | Not Detected |
| cis-1,2-Dichloroethene | 2500 | Not Detected | 10000 | Not Detected |
| Tetrahydrofuran | 2500 | Not Detected | 7400 | Not Detected |
| Chloroform | 2500 | Not Detected | 12000 | Not Detected |
| 1,1,1-Trichloroethane | 2500 | Not Detected | 14000 | Not Detected |
| Cyclohexane | 2500 | 43000 | 8700 | 150000 |
| Carbon Tetrachloride | 2500 | Not Detected | 16000 | Not Detected |
| 2,2,4-Trimethylpentane | 2500 | 31000 | 12000 | 140000 |
| ~~Benzene~~ | ~~2500~~ | ~~3200000 E~~ | ~~8000~~ | ~~10000000 E~~ |
| 1,2-Dichloroethane | 2500 | Not Detected | 10000 | Not Detected |
| Heptane | 2500 | 12000 | 10000 | 48000 |
| Trichloroethene | 2500 | Not Detected | 14000 | Not Detected |
| 1,2-Dichloropropane | 2500 | Not Detected | 12000 | Not Detected |
| 1,4-Dioxane | 10000 | Not Detected | 36000 | Not Detected |
| Bromodichloromethane | 2500 | Not Detected | 17000 | Not Detected |
| cis-1,3-Dichloropropene | 2500 | Not Detected | 11000 | Not Detected |
| 4-Methyl-2-pentanone | 2500 | 1300 J | 10000 | 5300 J |
| Toluene | 2500 | 1100 J | 9500 | 4100 J |
| trans-1,3-Dichloropropene | 2500 | Not Detected | 11000 | Not Detected |
| 1,1,2-Trichloroethane | 2500 | Not Detected | 14000 | Not Detected |
| Tetrachloroethene | 2500 | Not Detected | 17000 | Not Detected |
| 2-Hexanone | 10000 | Not Detected | 41000 | Not Detected |

eurofins | Air Toxics

**Client Sample ID: VMP-14-20-013113**

**Lab ID#: 1302081A-03B**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | p021212 | **Date of Collection:** | 1/31/13 11:35:00 AM |
| **Dil. Factor:** | 5040 | **Date of Analysis:** | 2/12/13 04:07 PM |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Dibromochloromethane | 2500 | Not Detected | 21000 | Not Detected |
| 1,2-Dibromoethane (EDB) | 2500 | Not Detected | 19000 | Not Detected |
| Chlorobenzene | 2500 | Not Detected | 12000 | Not Detected |
| Ethyl Benzene | 2500 | Not Detected | 11000 | Not Detected |
| m,p-Xylene | 2500 | Not Detected | 11000 | Not Detected |
| o-Xylene | 2500 | Not Detected | 11000 | Not Detected |
| Styrene | 2500 | 620 J | 11000 | 2600 J |
| Bromoform | 2500 | Not Detected | 26000 | Not Detected |
| Cumene | 2500 | Not Detected | 12000 | Not Detected |
| 1,1,2,2-Tetrachloroethane | 2500 | Not Detected | 17000 | Not Detected |
| Propylbenzene | 2500 | Not Detected | 12000 | Not Detected |
| 4-Ethyltoluene | 2500 | Not Detected | 12000 | Not Detected |
| 1,3,5-Trimethylbenzene | 2500 | Not Detected | 12000 | Not Detected |
| 1,2,4-Trimethylbenzene | 2500 | Not Detected | 12000 | Not Detected |
| 1,3-Dichlorobenzene | 2500 | 480 J | 15000 | 2900 J |
| 1,4-Dichlorobenzene | 2500 | 530 J | 15000 | 3200 J |
| alpha-Chlorotoluene | 2500 | 550 J | 13000 | 2800 J |
| 1,2-Dichlorobenzene | 2500 | Not Detected | 15000 | Not Detected |
| 1,2,4-Trichlorobenzene | 10000 | 1200 J | 75000 | 9300 J |
| Hexachlorobutadiene | 10000 | Not Detected | 110000 | Not Detected |
| Butane | 10000 | 150000 | 24000 | 350000 |
| Isopentane | 10000 | 520000 | 30000 | 1500000 |

J = Estimated value.
E = Exceeds instrument calibration range.
**Container Type: 1 Liter Summa Canister**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| Toluene-d8 | 96 | 70-130 |
| 1,2-Dichloroethane-d4 | 84 | 70-130 |
| 4-Bromofluorobenzene | 99 | 70-130 |

eurofins | Air Toxics

**Client Sample ID: VMP-14-29-013113**
**Lab ID#: 1302081A-04A**

* USE THESE RESULTS ONLY. ALL OTHER DATA WERE REPORTED FROM THE 19,700X DILUTION ANALYSIS

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | p021217 | **Date of Collection:** | 1/31/13 12:24:00 PM |
| **Dil. Factor:** | 98400 | **Date of Analysis:** | 2/12/13 08:01 PM |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 49000 | Not Detected | 240000 | Not Detected |
| Freon 114 | 49000 | Not Detected | 340000 | Not Detected |
| Chloromethane | 490000 | Not Detected | 1000000 | Not Detected |
| Vinyl Chloride | 49000 | Not Detected | 120000 | Not Detected |
| 1,3-Butadiene | 49000 | Not Detected | 110000 | Not Detected |
| Bromomethane | 490000 | Not Detected | 1900000 | Not Detected |
| Chloroethane | 200000 | Not Detected | 520000 | Not Detected |
| Freon 11 | 49000 | Not Detected | 280000 | Not Detected |
| Ethanol | 200000 | Not Detected | 370000 | Not Detected |
| Freon 113 | 49000 | Not Detected | 380000 | Not Detected |
| 1,1-Dichloroethene | 49000 | Not Detected | 200000 | Not Detected |
| Acetone | 490000 | Not Detected | 1200000 | Not Detected |
| 2-Propanol | 200000 | Not Detected | 480000 | Not Detected |
| Carbon Disulfide | 200000 | 22000 J | 610000 | 68000 J |
| 3-Chloropropene | 200000 | Not Detected | 620000 | Not Detected |
| Methylene Chloride | 490000 | Not Detected | 1700000 | Not Detected |
| Methyl tert-butyl ether | 49000 | Not Detected | 180000 | Not Detected |
| trans-1,2-Dichloroethene | 49000 | Not Detected | 200000 | Not Detected |
| Hexane | 49000 | 250000 | 170000 | 900000 |
| 1,1-Dichloroethane | 49000 | Not Detected | 200000 | Not Detected |
| 2-Butanone (Methyl Ethyl Ketone) | 200000 | Not Detected | 580000 | Not Detected |
| cis-1,2-Dichloroethene | 49000 | Not Detected | 200000 | Not Detected |
| Tetrahydrofuran | 49000 | Not Detected | 140000 | Not Detected |
| Chloroform | 49000 | Not Detected | 240000 | Not Detected |
| 1,1,1-Trichloroethane | 49000 | Not Detected | 270000 | Not Detected |
| Cyclohexane | 49000 | 130000 | 170000 | 440000 |
| Carbon Tetrachloride | 49000 | Not Detected | 310000 | Not Detected |
| 2,2,4-Trimethylpentane | 49000 | 97000 | 230000 | 450000 |
| * Benzene | 49000 | 17000000 J | 160000 | 54000000 J |
| 1,2-Dichloroethane | 49000 | Not Detected | 200000 | Not Detected |
| Heptane | 49000 | 59000 | 200000 | 240000 |
| Trichloroethene | 49000 | Not Detected | 260000 | Not Detected |
| 1,2-Dichloropropane | 49000 | Not Detected | 230000 | Not Detected |
| 1,4-Dioxane | 200000 | Not Detected | 710000 | Not Detected |
| Bromodichloromethane | 49000 | Not Detected | 330000 | Not Detected |
| cis-1,3-Dichloropropene | 49000 | Not Detected | 220000 | Not Detected |
| 4-Methyl-2-pentanone | 49000 | Not Detected | 200000 | Not Detected |
| Toluene | 49000 | Not Detected | 180000 | Not Detected |
| trans-1,3-Dichloropropene | 49000 | Not Detected | 220000 | Not Detected |
| 1,1,2-Trichloroethane | 49000 | Not Detected | 270000 | Not Detected |
| Tetrachloroethene | 49000 | Not Detected | 330000 | Not Detected |
| 2-Hexanone | 200000 | Not Detected | 810000 | Not Detected |

eurofins | Air Toxics

**Client Sample ID: VMP-14-29-013113**

**Lab ID#: 1302081A-04A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | p021217 | **Date of Collection:** | 1/31/13 12:24:00 PM |
| **Dil. Factor:** | 98400 | **Date of Analysis:** | 2/12/13 08:01 PM |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Dibromochloromethane | 49000 | Not Detected | 420000 | Not Detected |
| 1,2-Dibromoethane (EDB) | 49000 | Not Detected | 380000 | Not Detected |
| Chlorobenzene | 49000 | Not Detected | 230000 | Not Detected |
| Ethyl Benzene | 49000 | Not Detected | 210000 | Not Detected |
| m,p-Xylene | 49000 | Not Detected | 210000 | Not Detected |
| o-Xylene | 49000 | Not Detected | 210000 | Not Detected |
| Styrene | 49000 | Not Detected | 210000 | Not Detected |
| Bromoform | 49000 | Not Detected | 510000 | Not Detected |
| Cumene | 49000 | Not Detected | 240000 | Not Detected |
| 1,1,2,2-Tetrachloroethane | 49000 | Not Detected | 340000 | Not Detected |
| Propylbenzene | 49000 | Not Detected | 240000 | Not Detected |
| 4-Ethyltoluene | 49000 | Not Detected | 240000 | Not Detected |
| 1,3,5-Trimethylbenzene | 49000 | Not Detected | 240000 | Not Detected |
| 1,2,4-Trimethylbenzene | 49000 | Not Detected | 240000 | Not Detected |
| 1,3-Dichlorobenzene | 49000 | Not Detected | 300000 | Not Detected |
| 1,4-Dichlorobenzene | 49000 | Not Detected | 300000 | Not Detected |
| alpha-Chlorotoluene | 49000 | Not Detected | 250000 | Not Detected |
| 1,2-Dichlorobenzene | 49000 | Not Detected | 300000 | Not Detected |
| 1,2,4-Trichlorobenzene | 200000 | Not Detected | 1500000 | Not Detected |
| Hexachlorobutadiene | 200000 | Not Detected | 2100000 | Not Detected |
| Butane | 200000 | 840000 | 470000 | 2000000 |
| Isopentane | 200000 | 1800000 | 580000 | 5400000 |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| Toluene-d8 | 94 | 70-130 |
| 1,2-Dichloroethane-d4 | 86 | 70-130 |
| 4-Bromofluorobenzene | 94 | 70-130 |

eurofins | Air Toxics

* DO NOT USE THIS DATA. USE ALL OTHER DATA.

**Client Sample ID: VMP-14-29-013113**

**Lab ID#: 1302081A-04B**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p021215** | **Date of Collection:** | **1/31/13 12:24:00 PM** |
| **Dil. Factor:** | **19700** | **Date of Analysis:** | **2/12/13 06:28 PM** |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 9800 | Not Detected | 49000 | Not Detected |
| Freon 114 | 9800 | Not Detected | 69000 | Not Detected |
| Chloromethane | 98000 | Not Detected | 200000 | Not Detected |
| Vinyl Chloride | 9800 | Not Detected | 25000 | Not Detected |
| 1,3-Butadiene | 9800 | Not Detected | 22000 | Not Detected |
| Bromomethane | 98000 | Not Detected | 380000 | Not Detected |
| Chloroethane | 39000 | Not Detected | 100000 | Not Detected |
| Freon 11 | 9800 | Not Detected | 55000 | Not Detected |
| Ethanol | 39000 | Not Detected | 74000 | Not Detected |
| Freon 113 | 9800 | Not Detected | 75000 | Not Detected |
| 1,1-Dichloroethene | 9800 | Not Detected | 39000 | Not Detected |
| Acetone | 98000 | 12000 J J | 230000 | 30000 J J |
| 2-Propanol | 39000 | Not Detected | 97000 | Not Detected |
| Carbon Disulfide | 39000 | 4200 J | 120000 | 13000 J |
| 3-Chloropropene | 39000 | Not Detected | 120000 | Not Detected |
| Methylene Chloride | 98000 | 2200 J J | 340000 | 7700 J J |
| Methyl tert-butyl ether | 9800 | Not Detected | 36000 | Not Detected |
| trans-1,2-Dichloroethene | 9800 | Not Detected | 39000 | Not Detected |
| Hexane | 9800 | 280000 J | 35000 | 980000 J |
| 1,1-Dichloroethane | 9800 | Not Detected | 40000 | Not Detected |
| 2-Butanone (Methyl Ethyl Ketone) | 39000 | Not Detected | 120000 | Not Detected |
| cis-1,2-Dichloroethene | 9800 | Not Detected | 39000 | Not Detected |
| Tetrahydrofuran | 9800 | Not Detected | 29000 | Not Detected |
| Chloroform | 9800 | Not Detected | 48000 | Not Detected |
| 1,1,1-Trichloroethane | 9800 | Not Detected | 54000 | Not Detected |
| Cyclohexane | 9800 | 140000 J | 34000 | 480000 J |
| Carbon Tetrachloride | 9800 | Not Detected | 62000 | Not Detected |
| 2,2,4-Trimethylpentane | 9800 | 100000 J | 46000 | 470000 J |
| * ~~Benzene~~ | ~~9800~~ | ~~16000000 E~~ | ~~31000~~ | ~~52000000 E~~ |
| 1,2-Dichloroethane | 9800 | Not Detected | 40000 | Not Detected |
| Heptane | 9800 | 61000 J | 40000 | 250000 J |
| Trichloroethene | 9800 | Not Detected | 53000 | Not Detected |
| 1,2-Dichloropropane | 9800 | Not Detected | 46000 | Not Detected |
| 1,4-Dioxane | 39000 | Not Detected | 140000 | Not Detected |
| Bromodichloromethane | 9800 | Not Detected | 66000 | Not Detected |
| cis-1,3-Dichloropropene | 9800 | Not Detected | 45000 | Not Detected |
| 4-Methyl-2-pentanone | 9800 | Not Detected | 40000 | Not Detected |
| Toluene | 9800 | 2100 J J | 37000 | 8000 J J |
| trans-1,3-Dichloropropene | 9800 | Not Detected | 45000 | Not Detected |
| 1,1,2-Trichloroethane | 9800 | Not Detected | 54000 | Not Detected |
| Tetrachloroethene | 9800 | Not Detected | 67000 | Not Detected |
| 2-Hexanone | 39000 | Not Detected | 160000 | Not Detected |

eurofins | Air Toxics

**Client Sample ID: VMP-14-29-013113**

**Lab ID#: 1302081A-04B**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p021215** | **Date of Collection: 1/31/13 12:24:00 PM** | |
| **Dil. Factor:** | **19700** | **Date of Analysis: 2/12/13 06:28 PM** | |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Dibromochloromethane | 9800 | Not Detected | 84000 | Not Detected |
| 1,2-Dibromoethane (EDB) | 9800 | Not Detected | 76000 | Not Detected |
| Chlorobenzene | 9800 | Not Detected | 45000 | Not Detected |
| Ethyl Benzene | 9800 | 3000 J | 43000 | 13000 J |
| m,p-Xylene | 9800 | 4400 J | 43000 | 19000 J |
| o-Xylene | 9800 | Not Detected | 43000 | Not Detected |
| Styrene | 9800 | Not Detected | 42000 | Not Detected |
| Bromoform | 9800 | Not Detected | 100000 | Not Detected |
| Cumene | 9800 | Not Detected | 48000 | Not Detected |
| 1,1,2,2-Tetrachloroethane | 9800 | Not Detected | 68000 | Not Detected |
| Propylbenzene | 9800 | Not Detected | 48000 | Not Detected |
| 4-Ethyltoluene | 9800 | Not Detected | 48000 | Not Detected |
| 1,3,5-Trimethylbenzene | 9800 | Not Detected | 48000 | Not Detected |
| 1,2,4-Trimethylbenzene | 9800 | Not Detected | 48000 | Not Detected |
| 1,3-Dichlorobenzene | 9800 | Not Detected | 59000 | Not Detected |
| 1,4-Dichlorobenzene | 9800 | Not Detected | 59000 | Not Detected |
| alpha-Chlorotoluene | 9800 | Not Detected | 51000 | Not Detected |
| 1,2-Dichlorobenzene | 9800 | Not Detected | 59000 | Not Detected |
| 1,2,4-Trichlorobenzene | 39000 | Not Detected | 290000 | Not Detected |
| Hexachlorobutadiene | 39000 | Not Detected | 420000 | Not Detected |
| Butane | 39000 | 890000 J | 94000 | 2100000 J |
| Isopentane | 39000 | 1900000 J | 120000 | 5600000 J |

J = Estimated value.
E = Exceeds instrument calibration range.
**Container Type: 1 Liter Summa Canister**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| Toluene-d8 | 96 | 70-130 |
| 1,2-Dichloroethane-d4 | 83 | 70-130 |
| 4-Bromofluorobenzene | 102 | 70-130 |

eurofins | Air Toxics

**Client Sample ID: VMP-14-29-013113-DUP**

**Lab ID#: 1302081A-05A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | p021218 | **Date of Collection:** | 1/31/13 11:35:00 AM |
| **Dil. Factor:** | 47400 | **Date of Analysis:** | 2/12/13 08:35 PM |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 24000 | Not Detected | 120000 | Not Detected |
| Freon 114 | 24000 | Not Detected | 160000 | Not Detected |
| Chloromethane | 240000 | Not Detected | 490000 | Not Detected |
| Vinyl Chloride | 24000 | Not Detected | 60000 | Not Detected |
| 1,3-Butadiene | 24000 | Not Detected | 52000 | Not Detected |
| Bromomethane | 240000 | Not Detected | 920000 | Not Detected |
| Chloroethane | 95000 | Not Detected | 250000 | Not Detected |
| Freon 11 | 24000 | Not Detected | 130000 | Not Detected |
| Ethanol | 95000 | Not Detected | 180000 | Not Detected |
| Freon 113 | 24000 | Not Detected | 180000 | Not Detected |
| 1,1-Dichloroethene | 24000 | Not Detected | 94000 | Not Detected |
| Acetone | 240000 | Not Detected UJ | 560000 | Not Detected UJ |
| 2-Propanol | 95000 | Not Detected | 230000 | Not Detected |
| Carbon Disulfide | 95000 | 12000 J | 300000 | 36000 J |
| 3-Chloropropene | 95000 | Not Detected | 300000 | Not Detected |
| Methylene Chloride | 240000 | Not Detected UJ | 820000 | Not Detected UJ |
| Methyl tert-butyl ether | 24000 | Not Detected | 85000 | Not Detected |
| trans-1,2-Dichloroethene | 24000 | Not Detected | 94000 | Not Detected |
| Hexane | 24000 | 48000 J | 84000 | 170000 J |
| 1,1-Dichloroethane | 24000 | Not Detected | 96000 | Not Detected |
| 2-Butanone (Methyl Ethyl Ketone) | 95000 | Not Detected | 280000 | Not Detected |
| cis-1,2-Dichloroethene | 24000 | Not Detected | 94000 | Not Detected |
| Tetrahydrofuran | 24000 | Not Detected | 70000 | Not Detected |
| Chloroform | 24000 | Not Detected | 120000 | Not Detected |
| 1,1,1-Trichloroethane | 24000 | Not Detected | 130000 | Not Detected |
| Cyclohexane | 24000 | 45000 J | 82000 | 150000 J |
| Carbon Tetrachloride | 24000 | Not Detected | 150000 | Not Detected |
| 2,2,4-Trimethylpentane | 24000 | 35000 J | 110000 | 160000 J |
| Benzene | 24000 | 4100000 J | 76000 | 13000000 J |
| 1,2-Dichloroethane | 24000 | Not Detected | 96000 | Not Detected |
| Heptane | 24000 | 8000 J J | 97000 | 33000 J J |
| Trichloroethene | 24000 | Not Detected | 130000 | Not Detected |
| 1,2-Dichloropropane | 24000 | Not Detected | 110000 | Not Detected |
| 1,4-Dioxane | 95000 | Not Detected | 340000 | Not Detected |
| Bromodichloromethane | 24000 | Not Detected | 160000 | Not Detected |
| cis-1,3-Dichloropropene | 24000 | Not Detected | 110000 | Not Detected |
| 4-Methyl-2-pentanone | 24000 | Not Detected | 97000 | Not Detected |
| Toluene | 24000 | Not Detected UJ | 89000 | Not Detected UJ |
| trans-1,3-Dichloropropene | 24000 | Not Detected | 110000 | Not Detected |
| 1,1,2-Trichloroethane | 24000 | Not Detected | 130000 | Not Detected |
| Tetrachloroethene | 24000 | Not Detected | 160000 | Not Detected |
| 2-Hexanone | 95000 | Not Detected | 390000 | Not Detected |

eurofins | Air Toxics

**Client Sample ID: VMP-14-29-013113-DUP**

**Lab ID#: 1302081A-05A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p021218** | **Date of Collection:** | **1/31/13 11:35:00 AM** |
| **Dil. Factor:** | **47400** | **Date of Analysis:** | **2/12/13 08:35 PM** |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Dibromochloromethane | 24000 | Not Detected | 200000 | Not Detected |
| 1,2-Dibromoethane (EDB) | 24000 | Not Detected | 180000 | Not Detected |
| Chlorobenzene | 24000 | Not Detected | 110000 | Not Detected |
| Ethyl Benzene | 24000 | Not Detected UJ | 100000 | Not Detected UJ |
| m,p-Xylene | 24000 | Not Detected UJ | 100000 | Not Detected UJ |
| o-Xylene | 24000 | Not Detected | 100000 | Not Detected |
| Styrene | 24000 | Not Detected | 100000 | Not Detected |
| Bromoform | 24000 | Not Detected | 240000 | Not Detected |
| Cumene | 24000 | Not Detected | 120000 | Not Detected |
| 1,1,2,2-Tetrachloroethane | 24000 | Not Detected | 160000 | Not Detected |
| Propylbenzene | 24000 | Not Detected | 120000 | Not Detected |
| 4-Ethyltoluene | 24000 | Not Detected | 120000 | Not Detected |
| 1,3,5-Trimethylbenzene | 24000 | Not Detected | 120000 | Not Detected |
| 1,2,4-Trimethylbenzene | 24000 | Not Detected | 120000 | Not Detected |
| 1,3-Dichlorobenzene | 24000 | Not Detected | 140000 | Not Detected |
| 1,4-Dichlorobenzene | 24000 | Not Detected | 140000 | Not Detected |
| alpha-Chlorotoluene | 24000 | Not Detected | 120000 | Not Detected |
| 1,2-Dichlorobenzene | 24000 | Not Detected | 140000 | Not Detected |
| 1,2,4-Trichlorobenzene | 95000 | Not Detected | 700000 | Not Detected |
| Hexachlorobutadiene | 95000 | Not Detected | 1000000 | Not Detected |
| Butane | 95000 | 160000 J | 220000 | 380000 J |
| Isopentane | 95000 | 560000 J | 280000 | 1600000 J |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| Toluene-d8 | 96 | 70-130 |
| 1,2-Dichloroethane-d4 | 84 | 70-130 |
| 4-Bromofluorobenzene | 98 | 70-130 |

eurofins | Air Toxics

**Client Sample ID: VMP-49-30-020113**

**Lab ID#: 1302081A-06A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | p021221 | **Date of Collection:** | 2/1/13 12:00:00 PM |
| **Dil. Factor:** | 123 | **Date of Analysis:** | 2/12/13 11:08 PM |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 62 | Not Detected | 300 | Not Detected |
| Freon 114 | 62 | Not Detected | 430 | Not Detected |
| Chloromethane | 620 | Not Detected | 1300 | Not Detected |
| Vinyl Chloride | 62 | Not Detected | 160 | Not Detected |
| 1,3-Butadiene | 62 | Not Detected | 140 | Not Detected |
| Bromomethane | 620 | Not Detected | 2400 | Not Detected |
| Chloroethane | 250 | Not Detected | 650 | Not Detected |
| Freon 11 | 62 | Not Detected | 340 | Not Detected |
| Ethanol | 250 | 100 J | 460 | 190 J |
| Freon 113 | 62 | Not Detected | 470 | Not Detected |
| 1,1-Dichloroethene | 62 | Not Detected | 240 | Not Detected |
| Acetone | 620 | 430 J | 1500 | 1000 J |
| 2-Propanol | 250 | 110 J | 600 | 270 J |
| Carbon Disulfide | 250 | 39 J | 770 | 120 J |
| 3-Chloropropene | 250 | Not Detected | 770 | Not Detected |
| Methylene Chloride | 620 | 70 J | 2100 | 240 J |
| Methyl tert-butyl ether | 62 | Not Detected | 220 | Not Detected |
| trans-1,2-Dichloroethene | 62 | Not Detected | 240 | Not Detected |
| Hexane | 62 | 21 J | 220 | 73 J |
| 1,1-Dichloroethane | 62 | Not Detected | 250 | Not Detected |
| 2-Butanone (Methyl Ethyl Ketone) | 250 | Not Detected | 720 | Not Detected |
| cis-1,2-Dichloroethene | 62 | Not Detected | 240 | Not Detected |
| Tetrahydrofuran | 62 | Not Detected | 180 | Not Detected |
| Chloroform | 62 | Not Detected | 300 | Not Detected |
| 1,1,1-Trichloroethane | 62 | Not Detected | 340 | Not Detected |
| Cyclohexane | 62 | 160 | 210 | 540 |
| Carbon Tetrachloride | 62 | Not Detected | 390 | Not Detected |
| 2,2,4-Trimethylpentane | 62 | 9700 | 290 | 45000 |
| Benzene | 62 | 130 | 200 | 400 |
| 1,2-Dichloroethane | 62 | Not Detected | 250 | Not Detected |
| Heptane | 62 | Not Detected | 250 | Not Detected |
| Trichloroethene | 62 | Not Detected | 330 | Not Detected |
| 1,2-Dichloropropane | 62 | Not Detected | 280 | Not Detected |
| 1,4-Dioxane | 250 | Not Detected | 890 | Not Detected |
| Bromodichloromethane | 62 | Not Detected | 410 | Not Detected |
| cis-1,3-Dichloropropene | 62 | Not Detected | 280 | Not Detected |
| 4-Methyl-2-pentanone | 62 | 28 J | 250 | 110 J |
| Toluene | 62 | 13 J | 230 | 49 J |
| trans-1,3-Dichloropropene | 62 | Not Detected | 280 | Not Detected |
| 1,1,2-Trichloroethane | 62 | Not Detected | 340 | Not Detected |
| Tetrachloroethene | 62 | Not Detected | 420 | Not Detected |
| 2-Hexanone | 250 | Not Detected | 1000 | Not Detected |

eurofins | Air Toxics

**Client Sample ID: VMP-49-30-020113**

**Lab ID#: 1302081A-06A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | p021221 | **Date of Collection:** | 2/1/13 12:00:00 PM |
| **Dil. Factor:** | 123 | **Date of Analysis:** | 2/12/13 11:08 PM |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Dibromochloromethane | 62 | Not Detected | 520 | Not Detected |
| 1,2-Dibromoethane (EDB) | 62 | Not Detected | 470 | Not Detected |
| Chlorobenzene | 62 | Not Detected | 280 | Not Detected |
| Ethyl Benzene | 62 | Not Detected | 270 | Not Detected |
| m,p-Xylene | 62 | Not Detected | 270 | Not Detected |
| o-Xylene | 62 | Not Detected | 270 | Not Detected |
| Styrene | 62 | 16 J | 260 | 68 J |
| Bromoform | 62 | Not Detected | 640 | Not Detected |
| Cumene | 62 | Not Detected | 300 | Not Detected |
| 1,1,2,2-Tetrachloroethane | 62 | Not Detected | 420 | Not Detected |
| Propylbenzene | 62 | Not Detected | 300 | Not Detected |
| 4-Ethyltoluene | 62 | Not Detected | 300 | Not Detected |
| 1,3,5-Trimethylbenzene | 62 | Not Detected | 300 | Not Detected |
| 1,2,4-Trimethylbenzene | 62 | Not Detected | 300 | Not Detected |
| 1,3-Dichlorobenzene | 62 | Not Detected | 370 | Not Detected |
| 1,4-Dichlorobenzene | 62 | Not Detected | 370 | Not Detected |
| alpha-Chlorotoluene | 62 | Not Detected | 320 | Not Detected |
| 1,2-Dichlorobenzene | 62 | Not Detected | 370 | Not Detected |
| 1,2,4-Trichlorobenzene | 250 | 21 J | 1800 | 150 J |
| Hexachlorobutadiene | 250 | Not Detected | 2600 | Not Detected |
| Butane | 250 | 2700 | 580 | 6500 |
| Isopentane | 250 | 16000 | 720 | 47000 |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| Toluene-d8 | 98 | 70-130 |
| 1,2-Dichloroethane-d4 | 87 | 70-130 |
| 4-Bromofluorobenzene | 103 | 70-130 |

eurofins | Air Toxics

**Client Sample ID: VMP-50-20-020113**

**Lab ID#: 1302081A-07A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p021222** | **Date of Collection:** | **2/1/13 2:25:00 PM** |
| **Dil. Factor:** | **10.7** | **Date of Analysis:** | **2/12/13 11:42 PM** |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 5.4 | Not Detected | 26 | Not Detected |
| Freon 114 | 5.4 | Not Detected | 37 | Not Detected |
| Chloromethane | 54 | Not Detected | 110 | Not Detected |
| Vinyl Chloride | 5.4 | Not Detected | 14 | Not Detected |
| 1,3-Butadiene | 5.4 | Not Detected | 12 | Not Detected |
| Bromomethane | 54 | Not Detected | 210 | Not Detected |
| Chloroethane | 21 | Not Detected | 56 | Not Detected |
| Freon 11 | 5.4 | Not Detected | 30 | Not Detected |
| Ethanol | 21 | 3.5 J | 40 | 6.6 J |
| Freon 113 | 5.4 | Not Detected | 41 | Not Detected |
| 1,1-Dichloroethene | 5.4 | Not Detected | 21 | Not Detected |
| Acetone | 54 | 8.7 J | 130 | 21 J |
| 2-Propanol | 21 | 2.9 J | 52 | 7.2 J |
| Carbon Disulfide | 21 | 4.6 J | 67 | 14 J |
| 3-Chloropropene | 21 | Not Detected | 67 | Not Detected |
| Methylene Chloride | 54 | Not Detected | 180 | Not Detected |
| Methyl tert-butyl ether | 5.4 | Not Detected | 19 | Not Detected |
| trans-1,2-Dichloroethene | 5.4 | Not Detected | 21 | Not Detected |
| Hexane | 5.4 | 17 | 19 | 61 |
| 1,1-Dichloroethane | 5.4 | Not Detected | 22 | Not Detected |
| 2-Butanone (Methyl Ethyl Ketone) | 21 | Not Detected | 63 | Not Detected |
| cis-1,2-Dichloroethene | 5.4 | Not Detected | 21 | Not Detected |
| Tetrahydrofuran | 5.4 | Not Detected | 16 | Not Detected |
| Chloroform | 5.4 | Not Detected | 26 | Not Detected |
| 1,1,1-Trichloroethane | 5.4 | Not Detected | 29 | Not Detected |
| Cyclohexane | 5.4 | 48 | 18 | 160 |
| Carbon Tetrachloride | 5.4 | Not Detected | 34 | Not Detected |
| 2,2,4-Trimethylpentane | 5.4 | 2000 | 25 | 9200 |
| Benzene | 5.4 | 3.4 J | 17 | 11 J |
| 1,2-Dichloroethane | 5.4 | Not Detected | 22 | Not Detected |
| Heptane | 5.4 | 40 | 22 | 160 |
| Trichloroethene | 5.4 | Not Detected | 29 | Not Detected |
| 1,2-Dichloropropane | 5.4 | Not Detected | 25 | Not Detected |
| 1,4-Dioxane | 21 | Not Detected | 77 | Not Detected |
| Bromodichloromethane | 5.4 | Not Detected | 36 | Not Detected |
| cis-1,3-Dichloropropene | 5.4 | Not Detected | 24 | Not Detected |
| 4-Methyl-2-pentanone | 5.4 | Not Detected | 22 | Not Detected |
| Toluene | 5.4 | 1.9 J | 20 | 7.3 J |
| trans-1,3-Dichloropropene | 5.4 | Not Detected | 24 | Not Detected |
| 1,1,2-Trichloroethane | 5.4 | Not Detected | 29 | Not Detected |
| Tetrachloroethene | 5.4 | Not Detected | 36 | Not Detected |
| 2-Hexanone | 21 | Not Detected | 88 | Not Detected |

eurofins | Air Toxics

**Client Sample ID: VMP-50-20-020113**

**Lab ID#: 1302081A-07A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | p021222 | **Date of Collection:** | 2/1/13 2:25:00 PM |
| **Dil. Factor:** | 10.7 | **Date of Analysis:** | 2/12/13 11:42 PM |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Dibromochloromethane | 5.4 | Not Detected | 46 | Not Detected |
| 1,2-Dibromoethane (EDB) | 5.4 | Not Detected | 41 | Not Detected |
| Chlorobenzene | 5.4 | Not Detected | 25 | Not Detected |
| Ethyl Benzene | 5.4 | 3.9 J | 23 | 17 J |
| m,p-Xylene | 5.4 | 1.8 J | 23 | 7.8 J |
| o-Xylene | 5.4 | 1.6 J | 23 | 7.1 J |
| Styrene | 5.4 | Not Detected | 23 | Not Detected |
| Bromoform | 5.4 | Not Detected | 55 | Not Detected |
| Cumene | 5.4 | 0.99 J | 26 | 4.8 J |
| 1,1,2,2-Tetrachloroethane | 5.4 | Not Detected | 37 | Not Detected |
| Propylbenzene | 5.4 | 1.4 J | 26 | 6.9 J |
| 4-Ethyltoluene | 5.4 | 1.9 J | 26 | 9.5 J |
| 1,3,5-Trimethylbenzene | 5.4 | Not Detected | 26 | Not Detected |
| 1,2,4-Trimethylbenzene | 5.4 | 1.5 J | 26 | 7.5 J |
| 1,3-Dichlorobenzene | 5.4 | Not Detected | 32 | Not Detected |
| 1,4-Dichlorobenzene | 5.4 | Not Detected | 32 | Not Detected |
| alpha-Chlorotoluene | 5.4 | Not Detected | 28 | Not Detected |
| 1,2-Dichlorobenzene | 5.4 | Not Detected | 32 | Not Detected |
| 1,2,4-Trichlorobenzene | 21 | Not Detected | 160 | Not Detected |
| Hexachlorobutadiene | 21 | Not Detected | 230 | Not Detected |
| Butane | 21 | 29 | 51 | 69 |
| Isopentane | 21 | 45 | 63 | 130 |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| Toluene-d8 | 98 | 70-130 |
| 1,2-Dichloroethane-d4 | 92 | 70-130 |
| 4-Bromofluorobenzene | 97 | 70-130 |

eurofins | Air Toxics

**Client Sample ID: VMP-50-30-020113**

**Lab ID#: 1302081A-08A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p021223** | **Date of Collection: 2/1/13 3:25:00 PM** | |
| **Dil. Factor:** | **2590** | **Date of Analysis: 2/13/13 06:59 AM** | |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 1300 | Not Detected | 6400 | Not Detected |
| Freon 114 | 1300 | Not Detected | 9000 | Not Detected |
| Chloromethane | 13000 | Not Detected | 27000 | Not Detected |
| Vinyl Chloride | 1300 | Not Detected | 3300 | Not Detected |
| 1,3-Butadiene | 1300 | Not Detected | 2900 | Not Detected |
| Bromomethane | 13000 | Not Detected | 50000 | Not Detected |
| Chloroethane | 5200 | Not Detected | 14000 | Not Detected |
| Freon 11 | 1300 | Not Detected | 7300 | Not Detected |
| Ethanol | 5200 | 1900 J | 9800 | 3600 J |
| Freon 113 | 1300 | Not Detected | 9900 | Not Detected |
| 1,1-Dichloroethene | 1300 | Not Detected | 5100 | Not Detected |
| Acetone | 13000 | 6700 J | 31000 | 16000 J |
| 2-Propanol | 5200 | 1300 J | 13000 | 3300 J |
| Carbon Disulfide | 5200 | 900 J | 16000 | 2800 J |
| 3-Chloropropene | 5200 | Not Detected | 16000 | Not Detected |
| Methylene Chloride | 13000 | 1300 J | 45000 | 4600 J |
| Methyl tert-butyl ether | 1300 | Not Detected | 4700 | Not Detected |
| trans-1,2-Dichloroethene | 1300 | Not Detected | 5100 | Not Detected |
| Hexane | 1300 | 320000 | 4600 | 1100000 |
| 1,1-Dichloroethane | 1300 | Not Detected | 5200 | Not Detected |
| 2-Butanone (Methyl Ethyl Ketone) | 5200 | Not Detected | 15000 | Not Detected |
| cis-1,2-Dichloroethene | 1300 | Not Detected | 5100 | Not Detected |
| Tetrahydrofuran | 1300 | Not Detected | 3800 | Not Detected |
| Chloroform | 1300 | Not Detected | 6300 | Not Detected |
| 1,1,1-Trichloroethane | 1300 | Not Detected | 7100 | Not Detected |
| Cyclohexane | 1300 | 110000 | 4400 | 370000 |
| Carbon Tetrachloride | 1300 | Not Detected | 8100 | Not Detected |
| 2,2,4-Trimethylpentane | 1300 | 96000 | 6000 | 450000 |
| Benzene | 1300 | 29000 | 4100 | 92000 |
| 1,2-Dichloroethane | 1300 | Not Detected | 5200 | Not Detected |
| Heptane | 1300 | 140000 | 5300 | 570000 |
| Trichloroethene | 1300 | Not Detected | 7000 | Not Detected |
| 1,2-Dichloropropane | 1300 | Not Detected | 6000 | Not Detected |
| 1,4-Dioxane | 5200 | Not Detected | 19000 | Not Detected |
| Bromodichloromethane | 1300 | Not Detected | 8700 | Not Detected |
| cis-1,3-Dichloropropene | 1300 | Not Detected | 5900 | Not Detected |
| 4-Methyl-2-pentanone | 1300 | Not Detected | 5300 | Not Detected |
| Toluene | 1300 | 200000 | 4900 | 740000 |
| trans-1,3-Dichloropropene | 1300 | Not Detected | 5900 | Not Detected |
| 1,1,2-Trichloroethane | 1300 | Not Detected | 7100 | Not Detected |
| Tetrachloroethene | 1300 | Not Detected | 8800 | Not Detected |
| 2-Hexanone | 5200 | Not Detected | 21000 | Not Detected |

eurofins | Air Toxics

**Client Sample ID: VMP-50-30-020113**

**Lab ID#: 1302081A-08A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p021223** | **Date of Collection: 2/1/13 3:25:00 PM** | |
| **Dil. Factor:** | **2590** | **Date of Analysis: 2/13/13 06:59 AM** | |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Dibromochloromethane | 1300 | Not Detected | 11000 | Not Detected |
| 1,2-Dibromoethane (EDB) | 1300 | Not Detected | 10000 | Not Detected |
| Chlorobenzene | 1300 | Not Detected | 6000 | Not Detected |
| Ethyl Benzene | 1300 | 84000 | 5600 | 370000 |
| m,p-Xylene | 1300 | 160000 | 5600 | 700000 |
| o-Xylene | 1300 | 50000 | 5600 | 220000 |
| Styrene | 1300 | Not Detected | 5500 | Not Detected |
| Bromoform | 1300 | Not Detected | 13000 | Not Detected |
| Cumene | 1300 | 3900 | 6400 | 19000 |
| 1,1,2,2-Tetrachloroethane | 1300 | Not Detected | 8900 | Not Detected |
| Propylbenzene | 1300 | 6100 | 6400 | 30000 |
| 4-Ethyltoluene | 1300 | 18000 | 6400 | 88000 |
| 1,3,5-Trimethylbenzene | 1300 | 4000 | 6400 | 19000 |
| 1,2,4-Trimethylbenzene | 1300 | 8000 | 6400 | 39000 |
| 1,3-Dichlorobenzene | 1300 | 180 J | 7800 | 1000 J |
| 1,4-Dichlorobenzene | 1300 | Not Detected | 7800 | Not Detected |
| alpha-Chlorotoluene | 1300 | Not Detected | 6700 | Not Detected |
| 1,2-Dichlorobenzene | 1300 | Not Detected | 7800 | Not Detected |
| 1,2,4-Trichlorobenzene | 5200 | 570 J | 38000 | 4200 J |
| Hexachlorobutadiene | 5200 | Not Detected | 55000 | Not Detected |
| Butane | 5200 | 180000 | 12000 | 440000 |
| Isopentane | 5200 | 370000 | 15000 | 1100000 |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| Toluene-d8 | 94 | 70-130 |
| 1,2-Dichloroethane-d4 | 87 | 70-130 |
| 4-Bromofluorobenzene | 98 | 70-130 |

eurofins | Air Toxics

**Client Sample ID: Lab Blank**

**Lab ID#: 1302081A-09A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | p021206a | **Date of Collection:** | NA |
| **Dil. Factor:** | 1.00 | **Date of Analysis:** | 2/12/13 11:21 AM |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 0.50 | Not Detected | 2.5 | Not Detected |
| Freon 114 | 0.50 | Not Detected | 3.5 | Not Detected |
| Chloromethane | 5.0 | Not Detected | 10 | Not Detected |
| Vinyl Chloride | 0.50 | Not Detected | 1.3 | Not Detected |
| 1,3-Butadiene | 0.50 | Not Detected | 1.1 | Not Detected |
| Bromomethane | 5.0 | Not Detected | 19 | Not Detected |
| Chloroethane | 2.0 | Not Detected | 5.3 | Not Detected |
| Freon 11 | 0.50 | Not Detected | 2.8 | Not Detected |
| Ethanol | 2.0 | Not Detected | 3.8 | Not Detected |
| Freon 113 | 0.50 | Not Detected | 3.8 | Not Detected |
| 1,1-Dichloroethene | 0.50 | Not Detected | 2.0 | Not Detected |
| Acetone | 5.0 | Not Detected | 12 | Not Detected |
| 2-Propanol | 2.0 | Not Detected | 4.9 | Not Detected |
| Carbon Disulfide | 2.0 | 0.30 J | 6.2 | 0.92 J |
| 3-Chloropropene | 2.0 | Not Detected | 6.3 | Not Detected |
| Methylene Chloride | 5.0 | 0.099 J | 17 | 0.34 J |
| Methyl tert-butyl ether | 0.50 | Not Detected | 1.8 | Not Detected |
| trans-1,2-Dichloroethene | 0.50 | Not Detected | 2.0 | Not Detected |
| Hexane | 0.50 | Not Detected | 1.8 | Not Detected |
| 1,1-Dichloroethane | 0.50 | Not Detected | 2.0 | Not Detected |
| 2-Butanone (Methyl Ethyl Ketone) | 2.0 | Not Detected | 5.9 | Not Detected |
| cis-1,2-Dichloroethene | 0.50 | Not Detected | 2.0 | Not Detected |
| Tetrahydrofuran | 0.50 | Not Detected | 1.5 | Not Detected |
| Chloroform | 0.50 | Not Detected | 2.4 | Not Detected |
| 1,1,1-Trichloroethane | 0.50 | Not Detected | 2.7 | Not Detected |
| Cyclohexane | 0.50 | Not Detected | 1.7 | Not Detected |
| Carbon Tetrachloride | 0.50 | Not Detected | 3.1 | Not Detected |
| 2,2,4-Trimethylpentane | 0.50 | Not Detected | 2.3 | Not Detected |
| Benzene | 0.50 | Not Detected | 1.6 | Not Detected |
| 1,2-Dichloroethane | 0.50 | Not Detected | 2.0 | Not Detected |
| Heptane | 0.50 | Not Detected | 2.0 | Not Detected |
| Trichloroethene | 0.50 | Not Detected | 2.7 | Not Detected |
| 1,2-Dichloropropane | 0.50 | Not Detected | 2.3 | Not Detected |
| 1,4-Dioxane | 2.0 | Not Detected | 7.2 | Not Detected |
| Bromodichloromethane | 0.50 | Not Detected | 3.4 | Not Detected |
| cis-1,3-Dichloropropene | 0.50 | Not Detected | 2.3 | Not Detected |
| 4-Methyl-2-pentanone | 0.50 | Not Detected | 2.0 | Not Detected |
| Toluene | 0.50 | Not Detected | 1.9 | Not Detected |
| trans-1,3-Dichloropropene | 0.50 | Not Detected | 2.3 | Not Detected |
| 1,1,2-Trichloroethane | 0.50 | Not Detected | 2.7 | Not Detected |
| Tetrachloroethene | 0.50 | Not Detected | 3.4 | Not Detected |
| 2-Hexanone | 2.0 | Not Detected | 8.2 | Not Detected |

eurofins | Air Toxics

**Client Sample ID: Lab Blank**

**Lab ID#: 1302081A-09A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p021206a** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 2/12/13 11:21 AM** | |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Dibromochloromethane | 0.50 | Not Detected | 4.2 | Not Detected |
| 1,2-Dibromoethane (EDB) | 0.50 | Not Detected | 3.8 | Not Detected |
| Chlorobenzene | 0.50 | Not Detected | 2.3 | Not Detected |
| Ethyl Benzene | 0.50 | Not Detected | 2.2 | Not Detected |
| m,p-Xylene | 0.50 | Not Detected | 2.2 | Not Detected |
| o-Xylene | 0.50 | Not Detected | 2.2 | Not Detected |
| Styrene | 0.50 | Not Detected | 2.1 | Not Detected |
| Bromoform | 0.50 | Not Detected | 5.2 | Not Detected |
| Cumene | 0.50 | Not Detected | 2.4 | Not Detected |
| 1,1,2,2-Tetrachloroethane | 0.50 | Not Detected | 3.4 | Not Detected |
| Propylbenzene | 0.50 | Not Detected | 2.4 | Not Detected |
| 4-Ethyltoluene | 0.50 | 0.063 J | 2.4 | 0.31 J |
| 1,3,5-Trimethylbenzene | 0.50 | Not Detected | 2.4 | Not Detected |
| 1,2,4-Trimethylbenzene | 0.50 | Not Detected | 2.4 | Not Detected |
| 1,3-Dichlorobenzene | 0.50 | 0.13 J | 3.0 | 0.81 J |
| 1,4-Dichlorobenzene | 0.50 | 0.17 J | 3.0 | 1.0 J |
| alpha-Chlorotoluene | 0.50 | 0.098 J | 2.6 | 0.51 J |
| 1,2-Dichlorobenzene | 0.50 | 0.12 J | 3.0 | 0.69 J |
| 1,2,4-Trichlorobenzene | 2.0 | 0.69 J | 15 | 5.1 J |
| Hexachlorobutadiene | 2.0 | 0.27 J | 21 | 2.9 J |
| Butane | 2.0 | Not Detected | 4.8 | Not Detected |
| Isopentane | 2.0 | Not Detected | 5.9 | Not Detected |

J = Estimated value.

**Container Type: NA - Not Applicable**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| Toluene-d8 | 97 | 70-130 |
| 1,2-Dichloroethane-d4 | 81 | 70-130 |
| 4-Bromofluorobenzene | 98 | 70-130 |

eurofins | Air Toxics

**Client Sample ID: CCV**
**Lab ID#: 1302081A-10A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p021202** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 2/12/13 09:08 AM** | |

| Compound | %Recovery |
|---|---|
| Freon 12 | 83 |
| Freon 114 | 92 |
| Chloromethane | 87 |
| Vinyl Chloride | 97 |
| 1,3-Butadiene | 93 |
| Bromomethane | 99 |
| Chloroethane | 98 |
| Freon 11 | 81 |
| Ethanol | 106 |
| Freon 113 | 93 |
| 1,1-Dichloroethene | 102 |
| Acetone | 96 |
| 2-Propanol | 94 |
| Carbon Disulfide | 95 |
| 3-Chloropropene | 103 |
| Methylene Chloride | 88 |
| Methyl tert-butyl ether | 98 |
| trans-1,2-Dichloroethene | 102 |
| Hexane | 104 |
| 1,1-Dichloroethane | 91 |
| 2-Butanone (Methyl Ethyl Ketone) | 98 |
| cis-1,2-Dichloroethene | 108 |
| Tetrahydrofuran | 102 |
| Chloroform | 87 |
| 1,1,1-Trichloroethane | 87 |
| Cyclohexane | 115 |
| Carbon Tetrachloride | 83 |
| 2,2,4-Trimethylpentane | 106 |
| Benzene | 99 |
| 1,2-Dichloroethane | 78 |
| Heptane | 110 |
| Trichloroethene | 78 |
| 1,2-Dichloropropane | 94 |
| 1,4-Dioxane | 108 |
| Bromodichloromethane | 84 |
| cis-1,3-Dichloropropene | 102 |
| 4-Methyl-2-pentanone | 111 |
| Toluene | 97 |
| trans-1,3-Dichloropropene | 97 |
| 1,1,2-Trichloroethane | 96 |
| Tetrachloroethene | 94 |
| 2-Hexanone | 102 |

eurofins | Air Toxics

**Client Sample ID: CCV**

**Lab ID#: 1302081A-10A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p021202** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 2/12/13 09:08 AM** | |

| Compound | %Recovery |
|---|---|
| Dibromochloromethane | 94 |
| 1,2-Dibromoethane (EDB) | 94 |
| Chlorobenzene | 92 |
| Ethyl Benzene | 103 |
| m,p-Xylene | 106 |
| o-Xylene | 108 |
| Styrene | 111 |
| Bromoform | 94 |
| Cumene | 106 |
| 1,1,2,2-Tetrachloroethane | 103 |
| Propylbenzene | 99 |
| 4-Ethyltoluene | 105 |
| 1,3,5-Trimethylbenzene | 108 |
| 1,2,4-Trimethylbenzene | 109 |
| 1,3-Dichlorobenzene | 96 |
| 1,4-Dichlorobenzene | 95 |
| alpha-Chlorotoluene | 99 |
| 1,2-Dichlorobenzene | 96 |
| 1,2,4-Trichlorobenzene | 95 |
| Hexachlorobutadiene | 88 |
| Butane | 91 |
| Isopentane | 95 |

**Container Type: NA - Not Applicable**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| Toluene-d8 | 98 | 70-130 |
| 1,2-Dichloroethane-d4 | 81 | 70-130 |
| 4-Bromofluorobenzene | 99 | 70-130 |

eurofins | Air Toxics

**Client Sample ID: LCS**

**Lab ID#: 1302081A-11A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p021203** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 2/12/13 09:43 AM** | |

| Compound | %Recovery |
|---|---|
| Freon 12 | 87 |
| Freon 114 | 96 |
| Chloromethane | 95 |
| Vinyl Chloride | 104 |
| 1,3-Butadiene | 97 |
| Bromomethane | 102 |
| Chloroethane | 99 |
| Freon 11 | 84 |
| Ethanol | 80 |
| Freon 113 | 97 |
| 1,1-Dichloroethene | 110 |
| Acetone | 101 |
| 2-Propanol | 100 |
| Carbon Disulfide | 121 |
| 3-Chloropropene | 123 |
| Methylene Chloride | 89 |
| Methyl tert-butyl ether | 96 |
| trans-1,2-Dichloroethene | 118 |
| Hexane | 107 |
| 1,1-Dichloroethane | 95 |
| 2-Butanone (Methyl Ethyl Ketone) | 104 |
| cis-1,2-Dichloroethene | 112 |
| Tetrahydrofuran | 102 |
| Chloroform | 92 |
| 1,1,1-Trichloroethane | 91 |
| Cyclohexane | 120 |
| Carbon Tetrachloride | 87 |
| 2,2,4-Trimethylpentane | 109 |
| Benzene | 100 |
| 1,2-Dichloroethane | 78 |
| Heptane | 108 |
| Trichloroethene | 80 |
| 1,2-Dichloropropane | 96 |
| 1,4-Dioxane | 109 |
| Bromodichloromethane | 85 |
| cis-1,3-Dichloropropene | 101 |
| 4-Methyl-2-pentanone | 109 |
| Toluene | 96 |
| trans-1,3-Dichloropropene | 99 |
| 1,1,2-Trichloroethane | 98 |
| Tetrachloroethene | 95 |
| 2-Hexanone | 105 |

eurofins | Air Toxics

**Client Sample ID: LCS**

**Lab ID#: 1302081A-11A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p021203** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 2/12/13 09:43 AM** | |

| Compound | %Recovery |
|---|---|
| Dibromochloromethane | 94 |
| 1,2-Dibromoethane (EDB) | 98 |
| Chlorobenzene | 95 |
| Ethyl Benzene | 105 |
| m,p-Xylene | 110 |
| o-Xylene | 112 |
| Styrene | 114 |
| Bromoform | 94 |
| Cumene | 110 |
| 1,1,2,2-Tetrachloroethane | 110 |
| Propylbenzene | 104 |
| 4-Ethyltoluene | 104 |
| 1,3,5-Trimethylbenzene | 112 |
| 1,2,4-Trimethylbenzene | 110 |
| 1,3-Dichlorobenzene | 102 |
| 1,4-Dichlorobenzene | 98 |
| alpha-Chlorotoluene | 101 |
| 1,2-Dichlorobenzene | 101 |
| 1,2,4-Trichlorobenzene | 105 |
| Hexachlorobutadiene | 94 |
| Butane | 88 |
| Isopentane | 99 |

**Container Type: NA - Not Applicable**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| Toluene-d8 | 97 | 70-130 |
| 1,2-Dichloroethane-d4 | 82 | 70-130 |
| 4-Bromofluorobenzene | 100 | 70-130 |

eurofins | Air Toxics

**Client Sample ID: LCSD**

**Lab ID#: 1302081A-11AA**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p021204** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 2/12/13 10:05 AM** | |

| Compound | %Recovery |
|---|---|
| Freon 12 | 82 |
| Freon 114 | 91 |
| Chloromethane | 88 |
| Vinyl Chloride | 98 |
| 1,3-Butadiene | 93 |
| Bromomethane | 97 |
| Chloroethane | 95 |
| Freon 11 | 79 |
| Ethanol | 73 |
| Freon 113 | 92 |
| 1,1-Dichloroethene | 106 |
| Acetone | 99 |
| 2-Propanol | 94 |
| Carbon Disulfide | 116 |
| 3-Chloropropene | 118 |
| Methylene Chloride | 87 |
| Methyl tert-butyl ether | 92 |
| trans-1,2-Dichloroethene | 113 |
| Hexane | 101 |
| 1,1-Dichloroethane | 90 |
| 2-Butanone (Methyl Ethyl Ketone) | 100 |
| cis-1,2-Dichloroethene | 108 |
| Tetrahydrofuran | 98 |
| Chloroform | 88 |
| 1,1,1-Trichloroethane | 88 |
| Cyclohexane | 114 |
| Carbon Tetrachloride | 82 |
| 2,2,4-Trimethylpentane | 105 |
| Benzene | 97 |
| 1,2-Dichloroethane | 75 |
| Heptane | 105 |
| Trichloroethene | 78 |
| 1,2-Dichloropropane | 94 |
| 1,4-Dioxane | 105 |
| Bromodichloromethane | 82 |
| cis-1,3-Dichloropropene | 98 |
| 4-Methyl-2-pentanone | 106 |
| Toluene | 94 |
| trans-1,3-Dichloropropene | 94 |
| 1,1,2-Trichloroethane | 93 |
| Tetrachloroethene | 91 |
| 2-Hexanone | 100 |

eurofins | Air Toxics

**Client Sample ID: LCSD**

**Lab ID#: 1302081A-11AA**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | p021204 | **Date of Collection:** | NA |
| **Dil. Factor:** | 1.00 | **Date of Analysis:** | 2/12/13 10:05 AM |

| Compound | %Recovery |
|---|---|
| Dibromochloromethane | 90 |
| 1,2-Dibromoethane (EDB) | 95 |
| Chlorobenzene | 92 |
| Ethyl Benzene | 102 |
| m,p-Xylene | 106 |
| o-Xylene | 107 |
| Styrene | 111 |
| Bromoform | 90 |
| Cumene | 105 |
| 1,1,2,2-Tetrachloroethane | 105 |
| Propylbenzene | 99 |
| 4-Ethyltoluene | 101 |
| 1,3,5-Trimethylbenzene | 108 |
| 1,2,4-Trimethylbenzene | 106 |
| 1,3-Dichlorobenzene | 97 |
| 1,4-Dichlorobenzene | 96 |
| alpha-Chlorotoluene | 98 |
| 1,2-Dichlorobenzene | 98 |
| 1,2,4-Trichlorobenzene | 103 |
| Hexachlorobutadiene | 91 |
| Butane | 86 |
| Isopentane | 94 |

**Container Type: NA - Not Applicable**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| Toluene-d8 | 98 | 70-130 |
| 1,2-Dichloroethane-d4 | 80 | 70-130 |
| 4-Bromofluorobenzene | 98 | 70-130 |

# Shell Oil Products Chain Of Custody Record

URS

Air Toxics LTD.
**Project Name: Roxana Soil Vapor**
**Project # 21562850.04001**
Lab Vendor #

Please Check Appropriate Box:
☑ ENV. SERVICES ☐ MOTIVA RETAIL ☐ SHELL RETAIL
☐ MOTIVA SD&CH ☐ CONSULTANT ☐ LUBES
☐ SHELL PIPELINE ☐ OTHER

Print Bill To Contact Name: Robert Mooshegian
INCIDENT # (ENV SERVICES): 9 7 2 1 6 5 4 0
☐ CHECK IF NO INCIDENT # APPLIES
DATE: 02/04/13
PAGE: 1 of 1
PO #:
SAP #: 3 4 0 0 6 1

SAMPLING COMPANY: URS CORPORATION
LOG CODE:
SITE ADDRESS: Street and City: 800 SOUTH CENTRAL AVE – ROXANA
State: IL
GLOBAL ID NO.:
ADDRESS: 1001 HIGHLANDS PLAZA DRIVE WEST - SUITE 300; ST. LOUIS, MO 63110
EDF DELIVERABLE TO (Name, Company, Office Location): Elizabeth Kunkel, URS, St. Louis
PHONE NO.: 314-743-4179
E-MAIL: Elizabeth_Kunkel@URSCorp.com
CONSULTANT PROJECT NAME: Roxana Soil Vapor
Laboratory Address: Air Toxics, LTD 180 Blue Ravine Road, Suite B, Folsom, CA 95630-4719
TELEPHONE: 314-429-0100
FAX: 314-429-0462
Bill To Contact E-MAIL: Robert.Mooshegian@urs.com
L. Rathnow, C. Kretzer, C. Williams, S. Jansen, D. Mattingly, M. Mittermeyer, J. Staetter, B. Lehan

TURNAROUND TIME (CALENDAR DAYS):
☑ STANDARD (14 DAY) ☐ 5 DAYS ☐ 3 DAYS ☐ 2 DAYS ☐ 24 HOURS ☐ RESULTS NEEDED ON WEEKEND

REQUESTED ANALYSIS

☐ LA - RWQCB REPORT FORMAT ☑ UST AGENCY:
DELIVERABLES: ☐ LEVEL 1 ☐ LEVEL 2 ☐ LEVEL 3 ☑ LEVEL 4 ☐ OTHER (SPECIFY)

☑ SHELL CONTRACT RATE APPLIES
☐ STATE REIMBURSEMENT RATE APPLIES
☐ EDD NOT NEEDED
☑ RECEIPT VERIFICATION REQUESTED

Turn Around Time: ☑ Normal ☐ Rush ____ Specify

*Lab Use Only*
Pressurized by:
Date:
Pressurization Gas: $N_2$ He

| LAB USE ONLY | Field Sample Identification | SAMPLING DATE | SAMPLING TIME | Canister Number | Conister Pressure/Vacuum Initial | Final | Receipt | Final (psi) | Modified TO-15 + Butane & Isopentane | ASTM D-1946 + Helium | ASTM D-1946 |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 01A | VMP-2-42-013113 | 01/31/13 | 1528-1558 | 8038 | -30 | -6 | | | X | X | |
| 02A | VMP-13-29.5-013013 | 01/30/13 | 1327-1357 | 14520 | -29 | -6 | | | X | X | |
| 03A | VMP-14-20-013113 | 01/31/13 | 1102-1135 | 37763 | -29.5 | -8 | | | X | X | |
| 04A | VMP-14-29-013113 | 01/31/13 | 1150-1224 | 34114 | -30 | -8 | | | X | X | |
| 05A | VMP-14-29-013113-Dup | 01/31/13 | 1102-1135 | 37665 | -30 | -6 | | | X | X | |
| 06A | VMP-49-30-020113 | 02/01/13 | 1127-1200 | 37406 | -29.5 | -7.5 | | | X | X | |
| 07A | VMP-50-20-020113 | 02/01/13 | 1355-1425 | 14507 | -30 | -9.5 | | | X | X | |
| 08A | VMP-50-30-020113 | 02/01/13 | 1455-1525 | 37734 | -30 | -7.5 | | | X | X | |

ADDITIONAL NOTES:
- 14 day hold time
- Report results between MDL and RL
- Level IV ECVP

FedEx
Custody Seal Intact? (Y) N None Temp NA

| | | | |
|---|---|---|---|
| Relinquished by: (Signature) | Received by: (Signature) FEDEX | Date: 2/4/13 | Time: 1830 |
| Relinquished by: (Signature) | Received by: (Signature) Katie Deck1 ATL 02/05/13 0925 | Date: 02/05/13 | Time: 0925 |
| Relinquished by: (Signature) | Received by: (Signature) | Date: | Time: |

05/2006 Revision

1302081

eurofins | Air Toxics

2/19/2013
Ms. Elizabeth Kunkel
URS Corporation
1001 Highlands Plaza Dr. West
Suite 300
St. Louis MO 63110

Project Name: Roxana Soil Vapor
Project #: 21562850.04001
Workorder #: 1302081B

Dear Ms. Elizabeth Kunkel

The following report includes the data for the above referenced project for sample(s) received on 2/5/2013 at Air Toxics Ltd.

The data and associated QC analyzed by Modified ASTM D-1946 are compliant with the project requirements or laboratory criteria with the exception of the deviations noted in the attached case narrative.

Thank you for choosing Air Toxics Ltd. for your air analysis needs. Air Toxics Ltd. is committed to providing accurate data of the highest quality. Please feel free to contact the Project Manager: Kelly Buettner at 916-985-1000 if you have any questions regarding the data in this report.

Regards,

Kelly Buettner

Project Manager

REVIEWED ON 3/21/13

eurofins | Air Toxics

# WORK ORDER #: 1302081B

Work Order Summary

| | | | |
|---|---|---|---|
| **CLIENT:** | Ms. Elizabeth Kunkel<br>URS Corporation<br>1001 Highlands Plaza Dr. West<br>Suite 300<br>St. Louis, MO 63110 | **BILL TO:** | Accounts Payable Austin<br>URS Corporation<br>P.O. BOX 203970<br>Austin, TX 78720-1088 |
| **PHONE:** | 314-743-4179 | **P.O. #** | 21562735.00013 |
| **FAX:** | | **PROJECT #** | 21562850.04001 Roxana Soil Vapor |
| **DATE RECEIVED:** | 02/05/2013 | **CONTACT:** | Kelly Buettner |
| **DATE COMPLETED:** | 02/19/2013 | | |

| FRACTION # | NAME | TEST | RECEIPT VAC./PRES. | FINAL PRESSURE |
|---|---|---|---|---|
| 01A | VMP-2-42-013113 | Modified ASTM D-1946 | 5.6 "Hg | 15 psi |
| 02A | VMP-13-29.5-013013 | Modified ASTM D-1946 | 6.2 "Hg | 15 psi |
| 03A | VMP-14-20-013113 | Modified ASTM D-1946 | 6.0 "Hg | 15 psi |
| 04A | VMP-14-29-013113 | Modified ASTM D-1946 | 5.4 "Hg | 15 psi |
| 05A | VMP-14-20-013113-DUP | Modified ASTM D-1946 | 4.4 "Hg | 15 psi |
| 06A | VMP-49-30-020113 | Modified ASTM D-1946 | 5.4 "Hg | 15 psi |
| 07A | VMP-50-20-020113 | Modified ASTM D-1946 | 7.4 "Hg | 15 psi |
| 08A | VMP-50-30-020113 | Modified ASTM D-1946 | 6.6 "Hg | 15 psi |
| 09A | Lab Blank | Modified ASTM D-1946 | NA | NA |
| 09B | Lab Blank | Modified ASTM D-1946 | NA | NA |
| 10A | LCS | Modified ASTM D-1946 | NA | NA |
| 10AA | LCSD | Modified ASTM D-1946 | NA | NA |

CERTIFIED BY: Heidi Hayes DATE: 02/19/13

Technical Director

Certification numbers: AZ Licensure AZ0775, CA NELAP - 12282CA, NY NELAP - 11291,
TX NELAP - T104704434-12-4, UT NELAP CA009332012-3, WA NELAP - C935
Name of Accrediting Agency: NELAP/ORELAP (Oregon Environmental Laboratory Accreditation Program)
Accreditation number: CA300005, Effective date: 10/18/2012, Expiration date: 10/17/2013.
Eurofins Air Toxics Ltd. certifies that the test results contained in this report meet all requirements of the NELAC standards

This report shall not be reproduced, except in full, without the written approval of Eurofins Air Toxics, Inc.

180 BLUE RAVINE ROAD, SUITE B FOLSOM, CA - 9563
(916) 985-1000 . (800) 985-5955 . FAX (916) 985-1020

**LABORATORY NARRATIVE**
**Modified ASTM D-1946**
**URS Corporation**
**Workorder# 1302081B**

Eight 1 Liter Summa Canister samples were received on February 05, 2013. The laboratory performed analysis via Modified ASTM Method D-1946 for Methane and fixed gases in air using GC/FID or GC/TCD. The method involves direct injection of 1.0 mL of sample.

On the analytical column employed for this analysis, Oxygen coelutes with Argon. The corresponding peak is quantitated as Oxygen.

Since Nitrogen is used to pressurize samples, the reported Nitrogen values are calculated by adding all the sample components and subtracting from 100%.

Method modifications taken to run these samples are summarized in the table below. Specific project requirements may over-ride the ATL modifications.

| *Requirement* | *ASTM D-1946* | *ATL Modifications* |
|---|---|---|
| Calibration | A single point calibration is performed using a reference standard closely matching the composition of the unknown. | A 3-point calibration curve is performed. Quantitation is based on a daily calibration standard which may or may not resemble the composition of the associated samples. |
| Reference Standard | The composition of any reference standard must be known to within 0.01 mol % for any component. | The standards used by ATL are blended to a >/= 95% accuracy. |
| Sample Injection Volume | Components whose concentrations are in excess of 5 % should not be analyzed by using sample volumes greater than 0.5 mL. | The sample container is connected directly to a fixed volume sample loop of 1.0 mL on the GC. Linear range is defined by the calibration curve. Bags are loaded by vacuum. |
| Normalization | Normalize the mole percent values by multiplying each value by 100 and dividing by the sum of the original values. The sum of the original values should not differ from 100% by more than 1.0%. | Results are not normalized. The sum of the reported values can differ from 100% by as much as 15%, either due to analytical variability or an unusual sample matrix. |
| Precision | Precision requirements established at each concentration level. | Duplicates should agree within 25% RPD for detections > 5 X's the RL. |

**Receiving Notes**

The Chain of Custody (COC) information for sample VMP-14-29-013113-DUP did not match the entry on the sample tag with regard to sample identification. The information on the sample tag was used to process and report the sample.

**Analytical Notes**

As per project specific client request the laboratory has reported estimated values for target compound hits that are below the Reporting Limit but greater than the Method Detection Limit. Concentrations that are below the level at which the canister was certified may be false positives.

The reporting limit for Carbon Monoxide was raised from 0.010% to 0.050%.

**Definition of Data Qualifying Flags**

Seven qualifiers may have been used on the data analysis sheets and indicate as follows:
B - Compound present in laboratory blank greater than reporting limit.
J - Estimated value.
E - Exceeds instrument calibration range.
S - Saturated peak.
Q - Exceeds quality control limits.
U - Compound analyzed for but not detected above the detection limit.
M - Reported value may be biased due to apparent matrix interferences.
File extensions may have been used on the data analysis sheets and indicates as follows:
a-File was requantified
b-File was quantified by a second column and detector
r1-File was requantified for the purpose of reissue

eurofins | Air Toxics

# Summary of Detected Compounds
# NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1946

**Client Sample ID: VMP-2-42-013113**

**Lab ID#: 1302081B-01A**

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.25 | 4.1 |
| Nitrogen | 0.25 | 60 |
| Methane | 0.00025 | 25 |
| Carbon Dioxide | 0.025 | 6.2 |
| Ethane | 0.0025 | 0.012 |

**Client Sample ID: VMP-13-29.5-013013**

**Lab ID#: 1302081B-02A**

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.26 | 16 |
| Nitrogen | 0.26 | 79 |
| Methane | 0.00026 | 0.0037 |
| Carbon Dioxide | 0.026 | 5.2 |

**Client Sample ID: VMP-14-20-013113**

**Lab ID#: 1302081B-03A**

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.25 | 7.1 |
| Nitrogen | 0.25 | 80 |
| Methane | 0.00025 | 2.6 |
| Carbon Dioxide | 0.025 | 10 |
| Ethane | 0.0025 | 0.00036 J |
| Helium | 0.13 | 0.019 J |

**Client Sample ID: VMP-14-29-013113**

**Lab ID#: 1302081B-04A**

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.25 | 1.5 |
| Nitrogen | 0.25 | 76 |

eurofins | Air Toxics

# Summary of Detected Compounds
# NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1946

**Client Sample ID: VMP-14-29-013113**

**Lab ID#: 1302081B-04A**

| | | |
|---|---|---|
| Methane | 0.00025 | 5.5 |
| Carbon Dioxide | 0.025 | 15 |
| Ethane | 0.0025 | 0.0013 J |

**Client Sample ID: VMP-14-20-013113-DUP**

**Lab ID#: 1302081B-05A**

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.24 | 7.0 |
| Nitrogen | 0.24 | 80 |
| Methane | 0.00024 | 2.6 |
| Carbon Dioxide | 0.024 | 10 |
| Ethane | 0.0024 | 0.00036 J |

**Client Sample ID: VMP-49-30-020113**

**Lab ID#: 1302081B-06A**

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.25 | 4.4 |
| Nitrogen | 0.25 | 84 |
| Methane | 0.00025 | 0.069 |
| Carbon Dioxide | 0.025 | 11 |
| Helium | 0.12 | 0.020 J |

**Client Sample ID: VMP-50-20-020113**

**Lab ID#: 1302081B-07A**

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.27 | 20 |
| Nitrogen | 0.27 | 80 |
| Methane | 0.00027 | 0.00037 |
| Carbon Dioxide | 0.027 | 0.39 |
| Helium | 0.13 | 0.030 J |

eurofins | Air Toxics

# Summary of Detected Compounds
# NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1946

**Client Sample ID: VMP-50-30-020113**

**Lab ID#: 1302081B-08A**

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.26 | 14 |
| Nitrogen | 0.26 | 77 |
| Methane | 0.00026 | 0.56 |
| Carbon Dioxide | 0.026 | 8.0 |
| Ethane | 0.0026 | 0.000056 J |
| Ethene | 0.0026 | 0.000051 J |

eurofins | Air Toxics

**Client Sample ID: VMP-2-42-013113**

**Lab ID#: 1302081B-01A**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1946**

| | | | |
|---|---|---|---|
| **File Name:** | **9021115** | **Date of Collection:** | **1/31/13 3:58:00 PM** |
| **Dil. Factor:** | **2.48** | **Date of Analysis:** | **2/11/13 03:45 PM** |

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.25 | 4.1 |
| Nitrogen | 0.25 | 60 |
| Carbon Monoxide | 0.12 | Not Detected |
| Methane | 0.00025 | 25 |
| Carbon Dioxide | 0.025 | 6.2 |
| Ethane | 0.0025 | 0.012 |
| Ethene | 0.0025 | Not Detected |
| Helium | 0.12 | Not Detected |

**Container Type: 1 Liter Summa Canister**

eurofins | Air Toxics

**Client Sample ID: VMP-13-29.5-013013**

**Lab ID#: 1302081B-02A**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1946**

| | | | |
|---|---|---|---|
| **File Name:** | **9021117** | **Date of Collection:** | **1/30/13 1:57:00 PM** |
| **Dil. Factor:** | **2.55** | **Date of Analysis:** | **2/11/13 04:42 PM** |

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.26 | 16 |
| Nitrogen | 0.26 | 79 |
| Carbon Monoxide | 0.13 | Not Detected |
| Methane | 0.00026 | 0.0037 |
| Carbon Dioxide | 0.026 | 5.2 |
| Ethane | 0.0026 | Not Detected |
| Ethene | 0.0026 | Not Detected |
| Helium | 0.13 | Not Detected |

**Container Type: 1 Liter Summa Canister**

eurofins | Air Toxics

**Client Sample ID: VMP-14-20-013113**

**Lab ID#: 1302081B-03A**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1946**

| | | | |
|---|---|---|---|
| **File Name:** | **9021118** | **Date of Collection:** | **1/31/13 11:35:00 AM** |
| **Dil. Factor:** | **2.52** | **Date of Analysis:** | **2/11/13 05:47 PM** |

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.25 | 7.1 |
| Nitrogen | 0.25 | 80 |
| Carbon Monoxide | 0.13 | Not Detected |
| Methane | 0.00025 | 2.6 |
| Carbon Dioxide | 0.025 | 10 |
| Ethane | 0.0025 | 0.00036 J |
| Ethene | 0.0025 | Not Detected |
| Helium | 0.13 | 0.019 J |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

eurofins | Air Toxics

**Client Sample ID: VMP-14-29-013113**

**Lab ID#: 1302081B-04A**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1946**

| | | | |
|---|---|---|---|
| **File Name:** | **9021119** | **Date of Collection:** | **1/31/13 12:24:00 PM** |
| **Dil. Factor:** | **2.46** | **Date of Analysis:** | **2/11/13 06:20 PM** |

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.25 | 1.5 |
| Nitrogen | 0.25 | 76 |
| Carbon Monoxide | 0.12 | Not Detected |
| Methane | 0.00025 | 5.5 |
| Carbon Dioxide | 0.025 | 15 |
| Ethane | 0.0025 | 0.0013 J |
| Ethene | 0.0025 | Not Detected |
| Helium | 0.12 | Not Detected |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

eurofins | Air Toxics

**Client Sample ID: VMP-14-20-013113-DUP**

**Lab ID#: 1302081B-05A**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1946**

| | | | |
|---|---|---|---|
| **File Name:** | **9021120** | **Date of Collection:** | **1/31/13 11:35:00 AM** |
| **Dil. Factor:** | **2.37** | **Date of Analysis:** | **2/11/13 06:41 PM** |

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.24 | 7.0 |
| Nitrogen | 0.24 | 80 |
| Carbon Monoxide | 0.12 | Not Detected |
| Methane | 0.00024 | 2.6 |
| Carbon Dioxide | 0.024 | 10 |
| Ethane | 0.0024 | 0.00036 J |
| Ethene | 0.0024 | Not Detected |
| Helium | 0.12 | Not Detected |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

eurofins | Air Toxics

**Client Sample ID: VMP-49-30-020113**

**Lab ID#: 1302081B-06A**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1946**

| | | | |
|---|---|---|---|
| **File Name:** | **9021121** | **Date of Collection:** | **2/1/13 12:00:00 PM** |
| **Dil. Factor:** | **2.46** | **Date of Analysis:** | **2/11/13 07:17 PM** |

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.25 | 4.4 |
| Nitrogen | 0.25 | 84 |
| Carbon Monoxide | 0.12 | Not Detected |
| Methane | 0.00025 | 0.069 |
| Carbon Dioxide | 0.025 | 11 |
| Ethane | 0.0025 | Not Detected |
| Ethene | 0.0025 | Not Detected |
| Helium | 0.12 | 0.020 J |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

eurofins | Air Toxics

**Client Sample ID: VMP-50-20-020113**

**Lab ID#: 1302081B-07A**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1946**

| | | | |
|---|---|---|---|
| **File Name:** | **9021122** | **Date of Collection:** | **2/1/13 2:25:00 PM** |
| **Dil. Factor:** | **2.68** | **Date of Analysis:** | **2/11/13 07:46 PM** |

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.27 | 20 |
| Nitrogen | 0.27 | 80 |
| Carbon Monoxide | 0.13 | Not Detected |
| Methane | 0.00027 | 0.00037 |
| Carbon Dioxide | 0.027 | 0.39 |
| Ethane | 0.0027 | Not Detected |
| Ethene | 0.0027 | Not Detected |
| Helium | 0.13 | 0.030 J |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

eurofins | Air Toxics

**Client Sample ID: VMP-50-30-020113**

**Lab ID#: 1302081B-08A**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1946**

| | | | |
|---|---|---|---|
| **File Name:** | **9021123** | **Date of Collection: 2/1/13 3:25:00 PM** | |
| **Dil. Factor:** | **2.59** | **Date of Analysis: 2/11/13 08:14 PM** | |

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.26 | 14 |
| Nitrogen | 0.26 | 77 |
| Carbon Monoxide | 0.13 | Not Detected |
| Methane | 0.00026 | 0.56 |
| Carbon Dioxide | 0.026 | 8.0 |
| Ethane | 0.0026 | 0.000056 J |
| Ethene | 0.0026 | 0.000051 J |
| Helium | 0.13 | Not Detected |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

eurofins | Air Toxics

**Client Sample ID: Lab Blank**

**Lab ID#: 1302081B-09A**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1946**

| | | | |
|---|---|---|---|
| **File Name:** | **9021104a** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 2/11/13 10:23 AM** | |

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.10 | Not Detected |
| Nitrogen | 0.10 | 0.083 J |
| Carbon Monoxide | 0.050 | Not Detected |
| Methane | 0.00010 | Not Detected |
| Carbon Dioxide | 0.010 | Not Detected |
| Ethane | 0.0010 | Not Detected |
| Ethene | 0.0010 | Not Detected |

J = Estimated value.

**Container Type: NA - Not Applicable**

eurofins | Air Toxics

**Client Sample ID: Lab Blank**

**Lab ID#: 1302081B-09B**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1946**

| | | | |
|---|---|---|---|
| **File Name:** | **9021103b** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 2/11/13 10:01 AM** | |

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Helium | 0.050 | Not Detected |

**Container Type: NA - Not Applicable**

eurofins | Air Toxics

**Client Sample ID: LCS**

**Lab ID#: 1302081B-10A**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1946**

| | | | |
|---|---|---|---|
| **File Name:** | **9021102** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 2/11/13 09:35 AM** | |

| Compound | %Recovery |
|---|---|
| Oxygen | 102 |
| Nitrogen | 101 |
| Carbon Monoxide | 102 |
| Methane | 98 |
| Carbon Dioxide | 101 |
| Ethane | 100 |
| Ethene | 97 |
| Helium | 101 |

**Container Type: NA - Not Applicable**

eurofins | Air Toxics

**Client Sample ID: LCSD**

**Lab ID#: 1302081B-10AA**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1946**

| | | | |
|---|---|---|---|
| **File Name:** | **9021112** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 2/11/13 02:32 PM** | |

| Compound | %Recovery |
|---|---|
| Oxygen | 102 |
| Nitrogen | 101 |
| Carbon Monoxide | 97 |
| Methane | 99 |
| Carbon Dioxide | 102 |
| Ethane | 100 |
| Ethene | 97 |
| Helium | 101 |

**Container Type: NA - Not Applicable**

# Shell Oil Products Chain Of Custody Record

URS

Air Toxics LTD.
**Project Name: Roxana Soil Vapor**
**Project # 21562850.04001**
Lab Vendor #

Please Check Appropriate Box: ☑ ENV. SERVICES ☐ MOTIVA RETAIL ☐ SHELL RETAIL ☐ MOTIVA SD&CH ☐ CONSULTANT ☐ LUBES ☐ SHELL PIPELINE ☐ OTHER

Print Bill To Contact Name: Robert Mooshegian

INCIDENT # (ENV SERVICES): 9 7 2 1 6 6 4 0 ☐ CHECK IF NO INCIDENT # APPLIES

DATE: 02/04/13

PAGE: 1 of 1

PO #:

SAP #: 3 4 0 0 6 1

SAMPLING COMPANY: URS CORPORATION

LOG CODE:

SITE ADDRESS: Street and City: 900 SOUTH CENTRAL AVE – ROXANA

State: IL

GLOBAL ID NO.:

ADDRESS: 1001 HIGHLANDS PLAZA DRIVE WEST - SUITE 300; ST. LOUIS, MO 63110

Laboratory Address: Air Toxics LTD 180 Blue Ravine Road, Suite B, Folsom, CA 95630-4719

LOP DELIVERABLE TO (Name, Company, Office Location): Elizabeth Kunkel, URS, St. Louis

PHONE NO.: 314-743-4179

E-MAIL: Elizabeth.Kunkel@URSCorp.com

CONSULTANT PROJECT NAME#: Roxana Soil Vapor

TELEPHONE: 314-429-0100

FAX: 314-429-0462

Sample Contact E-MAIL: Robert.Mooshegian@urs.com

L. Rathnow, C. Kretzer, C. Williams, S. Jansen, D. Mattingly, M. Mittermeyer, J. Staetter, B. Lehan

TURNAROUND TIME (CALENDAR DAYS): ☑ STANDARD (14 DAY) ☐ 5 DAYS ☐ 3 DAYS ☐ 2 DAYS ☐ 24 HOURS ☐ RESULTS NEEDED ON WEEKEND

REQUESTED ANALYSIS

☐ LA - RWQCB REPORT FORMAT ☑ UST AGENCY:

DELIVERABLES: ☐ LEVEL 1 ☐ LEVEL 2 ☐ LEVEL 3 ☑ LEVEL 4 ☐ OTHER (SPECIFY)

☑ SHELL CONTRACT RATE APPLIES
☐ STATE REIMBURSEMENT RATE APPLIES
☐ EDD NOT NEEDED
☑ RECEIPT VERIFICATION REQUESTED

Turn Around Time: ☑ Normal ☐ Rush — Specify

Lab Use Only
Pressurized by:
Date:
Pressurization Gas: $N_2$ He

| LAB USE ONLY | Field Sample Identification | SAMPLING DATE | SAMPLING TIME | Canister Number | Canister Pressure/Vacuum Initial | Final | Receipt | Final (psi) | Modified TO-15 + Butane & Isopentane | ASTM D-1946 + Hellium | ASTM D-1946 | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| 01A | VMP-2-42-013113 | 01/31/13 | 1528-1558 | 8038 | -30 | -6 | | | X | X | | | | | | |
| 02A | VMP-13-29.5-013013 | 01/30/13 | 1327-1357 | 14520 | -29 | -6 | | | X | X | | | | | | |
| 03A | VMP-14-20-013113 | 01/31/13 | 1102-1135 | 37763 | -29.5 | -6 | | | X | X | | | | | | |
| 04A | VMP-14-29-013113 | 01/31/13 | 1150-1224 | 34114 | -30 | -8 | | | X | X | | | | | | |
| 05A | VMP-14-29-013113-Dup | 01/31/13 | 1102-1135 | 37865 | -30 | -6 | | | X | X | | | | | | |
| 06A | VMP-49-30-020113 | 02/01/13 | 1127-1200 | 37406 | -29.5 | -7.5 | | | X | X | | | | | | |
| 07A | VMP-50-20-020113 | 02/01/13 | 1355-1425 | 14507 | -30 | -9.5 | | | X | X | | | | | | |
| 08A | VMP-50-30-020113 | 02/01/13 | 1455-1525 | 37734 | -30 | -7.5 | | | X | X | | | | | | |

ADDITIONAL NOTES:

- 14 day hold time
- Report results between MDL and RL
- Level IV ECVP

FedEx
Custody Seal Intact?
(Y) N None Temp NA

| | | | |
|---|---|---|---|
| Relinquished by: (Signature) | Received by: (Signature) FEDEX | Date: 2/4/13 | Time: 1830 |
| Relinquished by: (Signature) | Received by: (Signature) Katie Decker ATL 02/05/13 0925 | Date: 02/05/13 | Time: 0925 |
| Relinquished by: (Signature) | Received by: (Signature) | Date: | Time: |

05/2008 Revision

1302081

# Roxana Soil Vapor Quarterly – 1st Quarter 2013 Data Review

**Laboratory SDG: 1302083A,B**

**Data Reviewer: Alan Fleisher**

**Peer Reviewer: Elizabeth Kunkel**

**Date Reviewed: 3/22/2013**

**Guidance: USEPA National Functional Guidelines for Superfund Organic Methods Data Review 2008**

| Sample Identification | Sample Identification |
|---|---|
| VMP-48-5-020113 | VMP-48-10-020113 |
| VMP-48-20-020113 | VMP-48-30-020113 |
| VMP-48-30-020113-Dup | VMP-50-10-020113 |
| VMP-50-5-020113 | VMP-51-10-020113 |
| VMP-51-20-020113 | VMP-52-5-020413 |
| VMP-52-10-020413 | VMP-52-20-020413 |
| VMP-52-20-020413-Dup | VMP-52-30-020413 |
| VMP-51-30-020413 | VMP-51-30-020413-Dup |

## 1.0 Data Package Completeness

*Were all items delivered as specified in the QAPP and COC as appropriate?*

Yes, however analysis of sample VMP-51-20-020113 was cancelled by URS due to laboratory notification of canister valve leaking upon sample receipt.

## 2.0 Laboratory Case Narrative \ Cooler Receipt Form

*Were problems noted in the laboratory case narrative or cooler receipt form?*

Yes, the laboratory case narrative indicated sample VMP-48-30-020113 was diluted and re-analyzed to bring the highest level target analytes with the calibration range of the instrument. Results for the highest level target analytes were reported from the re-analysis diluted runs and the remaining compounds were reported from the original analysis. Samples VMP-48-30-020113 and VMP-48-30-020113-Dup were diluted due to high levels of target analytes. Although not indicated in the laboratory case narrative, analytes were detected in the method blank. These issues are addressed further in the appropriate sections below.

No issues or discrepancies were noted in the cooler receipt form.

## 3.0 Holding Times

*Were samples extracted/analyzed within applicable limits?*

Yes

## 4.0 Blank Contamination

*Were any analytes detected in the Blanks?*

Yes

| Blank ID | Parameter | Analyte | Concentration/ Amount |
|---|---|---|---|
| 1302083A-17A | TO-15 | Bromomethane | 0.26 ppbv / 1.0 µg/m$^3$ |
| 1302083A-17A | TO-15 | Acetone | 0.40 ppbv / 0.95 µg/m$^3$ |
| 1302083A-17A | TO-15 | Carbon disulfide | 0.35 ppbv / 1.1 µg/m$^3$ |
| 1302083A-17A | TO-15 | Methylene chloride | 0.091 ppbv / 0.32 µg/m$^3$ |
| 1302083A-17A | TO-15 | Toluene | 0.085 ppbv / 0.32 µg/m$^3$ |
| 1302083A-17A | TO-15 | Tetrachloroethene | 0.097 ppbv / 0.66 µg/m$^3$ |
| 1302083A-17A | TO-15 | Chlorobenzene | 0.12 ppbv / 0.55 µg/m$^3$ |
| 1302083A-17A | TO-15 | Ethyl benzene | 0.094 ppbv / 0.41 µg/m$^3$ |
| 1302083A-17A | TO-15 | m,p-Xylene | 0.11 ppbv / 0.48 µg/m$^3$ |
| 1302083A-17A | TO-15 | o-Xylene | 0.10 ppbv / 0.45 µg/m$^3$ |
| 1302083A-17A | TO-15 | Styrene | 0.094 ppbv / 0.40 µg/m$^3$ |
| 1302083A-17A | TO-15 | Cumene | 0.16 ppbv / 0.77 µg/m$^3$ |
| 1302083A-17A | TO-15 | 1,1,2,2-Tetrachloroethane | 0.15 ppbv / 1.0 µg/m$^3$ |
| 1302083A-17A | TO-15 | Propylbenzene | 0.18 ppbv / 0.90 µg/m$^3$ |
| 1302083A-17A | TO-15 | 4-Ethyltoluene | 0.16 ppbv / 0.80 µg/m$^3$ |
| 1302083A-17A | TO-15 | 1,3,5-Timethylbenzene | 0.27 ppbv / 1.3 µg/m$^3$ |
| 1302083A-17A | TO-15 | 1,2,4-Trimethylbenzene | 0.21 ppbv / 1.0 µg/m$^3$ |
| 1302083A-17A | TO-15 | 1,3-Dichlorobenzene | 0.28 ppbv / 1.7 µg/m$^3$ |
| 1302083A-17A | TO-15 | 1,4-Dichlorobenzene | 0.30 ppbv / 1.8 µg/m$^3$ |
| 1302083A-17A | TO-15 | alpha-Chlorotoluene | 0.17 ppbv / 0.90 µg/m$^3$ |
| 1302083A-17A | TO-15 | 1,2-Dichlorobenzene | 0.28 ppbv / 1.7 µg/m$^3$ |
| 1302083A-17A | TO-15 | 1,2,4-Trichlorobenzene | 1.2 ppbv / 9.1 µg/m$^3$ |
| 1302083A-17A | TO-15 | Hexachlorobutadiene | 0.67 ppbv / 7.2 µg/m$^3$ |
| 1302083A-17B | TO-15 | Bromomethane | 0.30 ppbv / 1.2 µg/m$^3$ |
| 1302083A-17B | TO-15 | Freon 11 | 0.074 ppbv / 0.42 µg/m$^3$ |
| 1302083A-17B | TO-15 | Carbon disulfide | 0.49 ppbv / 1.5 µg/m$^3$ |
| 1302083A-17B | TO-15 | Methylene chloride | 0.19 ppbv / 0.66 µg/m$^3$ |
| 1302083A-17B | TO-15 | 2,2,4-Trimethylpentane | 0.053 ppbv / 0.25 µg/m$^3$ |
| 1302083A-17B | TO-15 | Toluene | 0.072 ppbv / 0.27 µg/m$^3$ |
| 1302083A-17B | TO-15 | trans-1,3-Dichloropropene | 0.16 ppbv / 0.74 µg/m$^3$ |
| 1302083A-17B | TO-15 | Tetrachloroethene | 0.13 ppbv / 0.89 µg/m$^3$ |
| 1302083A-17B | TO-15 | Chlorobenzene | 0.11 ppbv / 0.50 µg/m$^3$ |
| 1302083A-17B | TO-15 | o-Xylene | 0.099 ppbv / 0.43 µg/m$^3$ |
| 1302083A-17B | TO-15 | Styrene | 0.098 ppbv / 0.42 µg/m$^3$ |
| 1302083A-17B | TO-15 | Cumene | 0.16 ppbv / 0.79 µg/m$^3$ |
| 1302083A-17B | TO-15 | 1,1,2,2-Tetrachloroethane | 0.15 ppbv / 1.0 µg/m$^3$ |
| 1302083A-17B | TO-15 | Propylbenzene | 0.18 ppbv / 0.87 µg/m$^3$ |
| 1302083A-17B | TO-15 | 4-Ethyltoluene | 0.15 ppbv / 0.74 µg/m$^3$ |
| 1302083A-17B | TO-15 | 1,3,5-Timethylbenzene | 0.27 ppbv / 1.3 µg/m$^3$ |
| 1302083A-17B | TO-15 | 1,2,4-Trimethylbenzene | 0.21 ppbv / 1.0 µg/m$^3$ |
| 1302083A-17B | TO-15 | 1,3-Dichlorobenzene | 0.36 ppbv / 2.2 µg/m$^3$ |
| 1302083A-17B | TO-15 | 1,4-Dichlorobenzene | 0.34 ppbv / 2.0 µg/m$^3$ |
| 1302083A-17B | TO-15 | alpha-Chlorotoluene | 0.20 ppbv / 1.0 µg/m$^3$ |
| 1302083A-17B | TO-15 | 1,2-Dichlorobenzene | 0.32 ppbv / 1.9 µg/m$^3$ |
| 1302083A-17B | TO-15 | 1,2,4-Trichlorobenzene | 1.4 ppbv / 10 µg/m$^3$ |

| Blank ID | Parameter | Analyte | Concentration/ Amount |
|---|---|---|---|
| 1302083A-17B | TO-15 | Hexachlorobutadiene | 0.79 ppbv / 8.4 µg/m$^3$ |
| 1302083B-17A | Natural gases | Oxygene | 0.036% |
| 1302083B-17A | Natural gases | Nitrogen | 0.089% |

Qualifications due to blank contamination are included in the table below. Analytical data that were reported non-detect or at concentrations greater than five times (5X) the associated blank concentration did not require qualification.

| Sample ID | Parameter | Analyte | New Reporting Limit (RL) | Qualification |
|---|---|---|---|---|
| VMP-48-5-020113 | TO-15 | Carbon disulfide | - | **U** |
| VMP-48-5-020113 | TO-15 | Methylene chloride | - | **U** |
| VMP-48-5-020113 | TO-15 | Toluene | - | **U** |
| VMP-48-5-020113 | TO-15 | Tetrachloroethene | - | **U** |
| VMP-48-5-020113 | TO-15 | 4-Ethyltoluene | - | **U** |
| VMP-48-10-020113 | TO-15 | Carbon disulfide | - | **U** |
| VMP-48-10-020113 | TO-15 | Methylene chloride | - | **U** |
| VMP-48-10-020113 | TO-15 | Toluene | - | **U** |
| VMP-48-10-020113 | TO-15 | Tetrachloroethene | - | **U** |
| VMP-48-20-020113 | TO-15 | Carbon disulfide | - | **U** |
| VMP-48-20-020113 | TO-15 | Toluene | - | **U** |
| VMP-48-20-020113 | TO-15 | Tetrachloroethene | - | **U** |
| VMP-50-10-020113 | TO-15 | Toluene | - | **U** |
| VMP-50-10-020113 | TO-15 | 4-Ethyltoluene | - | **U** |
| VMP-50-10-020113 | TO-15 | 1,3,5-Trimethylbenzene | - | **U** |
| VMP-50-10-020113 | TO-15 | 1,2,4-Trimethylbenzene | - | **U** |
| VMP-51-5-020113 | TO-15 | Carbon disulfide | - | **U** |
| VMP-51-5-020113 | TO-15 | Methyl chloride | - | **U** |
| VMP-51-5-020113 | TO-15 | Toluene | - | **U** |
| VMP-51-5-020113 | TO-15 | Tetrachloroethene | - | **U** |
| VMP-51-10-020113 | TO-15 | Carbon disulfide | - | **U** |
| VMP-51-10-020113 | TO-15 | Toluene | - | **U** |
| VMP-52-5-020413 | TO-15 | Carbon disulfide | - | **U** |
| VMP-52-5-020413 | TO-15 | Methylene chloride | - | **U** |
| VMP-52-5-020413 | TO-15 | Toluene | - | **U** |
| VMP-52-5-020413 | TO-15 | Tetrachloroethene | - | **U** |
| VMP-52-5-020413 | TO-15 | 4-Ethyltoluene | - | **U** |
| VMP-52-5-020413 | TO-15 | 1,2,4-Trimethylbenzene | - | **U** |
| VMP-52-5-020413 | TO-15 | 1,3-Dichlorobenzene | - | **U** |
| VMP-52-5-020413 | TO-15 | 1,4-Dichlorobenzene | - | **U** |
| VMP-52-5-020413 | TO-15 | 1,2,4-Trichlorobenzene | - | **U** |
| VMP-52-10-020413 | TO-15 | Toluene | - | **U** |
| VMP-52-10-020413 | TO-15 | Tetrachloroethene | - | **U** |
| VMP-52-10-020413 | TO-15 | 1,2,4-Trichlorobenzene | - | **U** |

| Sample ID | Parameter | Analyte | New Reporting Limit (RL) | Qualification |
|---|---|---|---|---|
| VMP-52-20-020413 | TO-15 | Freon 11 | - | **U** |
| VMP-52-20-020413 | TO-15 | Methylene chloride | - | **U** |
| VMP-52-20-020413 | TO-15 | Tetrachloroethene | - | **U** |
| VMP-52-20-020413 | TO-15 | o-Xylene | - | **U** |
| VMP-52-20-020413 | TO-15 | Propylbenzene | - | **U** |
| VMP-52-20-020413 | TO-15 | 4-Ethyltoluene | - | **U** |
| VMP-52-20-020413 | TO-15 | 1,3,5-Trimethylbenzene | - | **U** |
| VMP-52-20-020413 | TO-15 | 1,2,4-Trimethylbenzene | - | **U** |
| VMP-52-20-020413 | TO-15 | 1,3-Dichlorobenzene | - | **U** |
| VMP-52-20-020413 | TO-15 | 1,4-Dichlorobenzene | - | **U** |
| VMP-52-20-020413 | TO-15 | 1,2-Dichlorobenzene | - | **U** |
| VMP-52-20-020413 | TO-15 | 1,2,4-Trichlorobenzene | - | **U** |
| VMP-52-20-020413 | TO-15 | Hexachlorobutadiene | - | **U** |
| VMP-52-20-020413-Dup | TO-15 | Freon 11 | - | **U** |
| VMP-52-20-020413-Dup | TO-15 | Methylene chloride | - | **U** |
| VMP-52-20-020413-Dup | TO-15 | 4-Ethyltoluene | - | **U** |
| VMP-52-20-020413-Dup | TO-15 | 1,3-Dichlorobenzene | - | **U** |
| VMP-52-20-020413-Dup | TO-15 | 1,4-Dichlorobenzene | - | **U** |
| VMP-52-20-020413-Dup | TO-15 | 1,2,4-Trichlorobenzene | - | **U** |
| VMP-52-30-020413 | TO-15 | Carbon disulfide | - | **U** |
| VMP-52-30-020413 | TO-15 | Toluene | - | **U** |
| VMP-52-30-020413 | TO-15 | Tetrachloroethene | - | **U** |
| VMP-52-30-020413 | TO-15 | 1,2,4-Trichlorobenzene | - | **U** |
| VMP-51-30-020413 | TO-15 | Freon 11 | - | **U** |
| VMP-51-30-020413 | TO-15 | Carbon disulfide | - | **U** |
| VMP-51-30-020413 | TO-15 | Toluene | - | **U** |
| VMP-51-30-020413 | TO-15 | Tetrachloroethene | - | **U** |
| VMP-51-30-020413 | TO-15 | 1,2,4-Trichlorobenzene | - | **U** |
| VMP-51-30-020413-Dup | TO-15 | Freon 11 | - | **U** |
| VMP-51-30-020413-Dup | TO-15 | Carbon disulfide | - | **U** |
| VMP-51-30-020413-Dup | TO-15 | Toluene | - | **U** |
| VMP-51-30-020413-Dup | TO-15 | Tetrachloroethene | - | **U** |

## 5.0 Laboratory Control Sample

*Were LCS recoveries within evaluation criteria?*

Yes

## 6.0 Surrogate Recoveries

*Were surrogate recoveries within evaluation criteria?*

Yes

## 7.0 Matrix Spike and Matrix Spike Duplicate Recoveries

*Were MS/MSD samples analyzed as part of this SDG?*

MS/MSD samples are not applicable for vapor samples, due to the inability to spike the samples.

## 8.0 Laboratory Duplicate Results

*Were laboratory duplicate samples analyzed as part of this SDG?*

Yes, sample VMP-51-30-020413-Dup was duplicated and analyzed for all TO-15 analytes.

*Were laboratory duplicate sample RPDs within evaluation criteria?*

Yes

## 9.0 Field Duplicate Results

*Were field duplicate samples collected as part of this SDG?*

Yes

| Field ID | Field Duplicate ID |
|---|---|
| VMP-48-30-020113 | VMP-48-30-020113-Dup |
| VMP-52-20-020413 | VMP-52-20-020413-Dup |

*Were field duplicate sample RPDs within evaluation criteria?*

No

| Field ID | Field Duplicate ID | Parameter | Analyte | RPD | Qualification |
|---|---|---|---|---|---|
| VMP-48-30-020113 | VMP-48-30-020113-Dup | TO-15 | Freon 12 | **>2X RL** | **J/UJ** |
| VMP-48-30-020113 | VMP-48-30-020113-Dup | TO-15 | Acetone | **>2X RL** | **J/UJ** |
| VMP-48-30-020113 | VMP-48-30-020113-Dup | TO-15 | 2-Propanol | **>2X RL** | **J/UJ** |
| VMP-48-30-020113 | VMP-48-30-020113-Dup | TO-15 | Ethyl benzene | **>2X RL** | **J/UJ** |
| VMP-48-30-020113 | VMP-48-30-020113-Dup | TO-15 | o-Xylene | **>2X RL** | **J/UJ** |
| VMP-52-20-020413 | VMP-52-20-020413-Dup | TO-15 | Benzene | **>2X RL** | **J/J** |

## 10.0 Sample Dilutions

*For samples that were diluted and nondetect, were undiluted results also reported?*

Not applicable; analytes were detected in samples that were diluted.

## 11.0 Additional Qualifications

*Were additional qualifications applied?*

No

eurofins | Air Toxics

2/19/2013
Ms. Elizabeth Kunkel
URS Corporation
1001 Highlands Plaza Dr. West
Suite 300
St. Louis MO 63110

Project Name: Roxana Soil Vapor
Project #: 21562850.04001
Workorder #: 1302083A

Dear Ms. Elizabeth Kunkel

The following report includes the data for the above referenced project for sample(s) received on 2/5/2013 at Air Toxics Ltd.

The data and associated QC analyzed by Modified TO-15 are compliant with the project requirements or laboratory criteria with the exception of the deviations noted in the attached case narrative.

Thank you for choosing Air Toxics Ltd. for your air analysis needs. Air Toxics Ltd. is committed to providing accurate data of the highest quality. Please feel free to contact the Project Manager: Kelly Buettner at 916-985-1000 if you have any questions regarding the data in this report.

Regards,

Kelly Buettner

Kelly Buettner
Project Manager

REVIEWED
ON
3/22/13

eurofins | Air Toxics

# WORK ORDER #: 1302083A

Work Order Summary

| | | | |
|---|---|---|---|
| **CLIENT:** | Ms. Elizabeth Kunkel<br>URS Corporation<br>1001 Highlands Plaza Dr. West<br>Suite 300<br>St. Louis, MO 63110 | **BILL TO:** | Accounts Payable Austin<br>URS Corporation<br>P.O. BOX 203970<br>Austin, TX 78720-1088 |
| **PHONE:** | 314-743-4179 | **P.O. #** | 21562735.00013 |
| **FAX:** | | **PROJECT #** | 21562850.04001 Roxana Soil Vapor |
| **DATE RECEIVED:** | 02/05/2013 | **CONTACT:** | Kelly Buettner |
| **DATE COMPLETED:** | 02/19/2013 | | |

| FRACTION # | NAME | TEST | RECEIPT VAC./PRES. | FINAL PRESSURE |
|---|---|---|---|---|
| 01A | VMP-48-5-020113 | Modified TO-15 | 6.4 "Hg | 15 psi |
| 02A | VMP-48-10-020113 | Modified TO-15 | 7.2 "Hg | 15 psi |
| 03A | VMP-48-20-020113 | Modified TO-15 | 6.2 "Hg | 15 psi |
| 04A | VMP-48-30-020113 | Modified TO-15 | 6.8 "Hg | 15 psi |
| 04B | VMP-48-30-020113 | Modified TO-15 | 6.8 "Hg | 15 psi |
| 05A | VMP-48-30-020113-DUP | Modified TO-15 | 6.6 "Hg | 15 psi |
| 06A | VMP-50-10-020113 | Modified TO-15 | 8.0 "Hg | 15 psi |
| 07A | VMP-51-5-020113 | Modified TO-15 | 7.8 "Hg | 15 psi |
| 08A | VMP-51-10-020113 | Modified TO-15 | 8.0 "Hg | 15 psi |
| 09A(cancelled) | VMP-51-20-020113 | Modified TO-15 | 4.8 "Hg | 15 psi |
| 10A | VMP-52-5-020413 | Modified TO-15 | 6.0 "Hg | 15 psi |
| 11A | VMP-52-10-020413 | Modified TO-15 | 4.8 "Hg | 15 psi |
| 12A | VMP-52-20-020413 | Modified TO-15 | 7.4 "Hg | 15 psi |
| 13A | VMP-52-20-020413-DUP | Modified TO-15 | 6.4 "Hg | 15 psi |
| 14A | VMP-52-30-020413 | Modified TO-15 | 8.4 "Hg | 15 psi |
| 15A | VMP-51-30-020413 | Modified TO-15 | 9.0 "Hg | 15 psi |
| 16A | VMP-51-30-020413-DUP | Modified TO-15 | 8.4 "Hg | 15 psi |
| 16AA | VMP-51-30-020413-DUP Lab Duplicate | Modified TO-15 | 8.4 "Hg | 15 psi |
| 17A | Lab Blank | Modified TO-15 | NA | NA |
| 17B | Lab Blank | Modified TO-15 | NA | NA |
| 18A | CCV | Modified TO-15 | NA | NA |
| 18B | CCV | Modified TO-15 | NA | NA |
| 19A | LCS | Modified TO-15 | NA | NA |

Continued on next page

eurofins | Air Toxics

# WORK ORDER #: 1302083A

Work Order Summary

| | | | |
|---|---|---|---|
| **CLIENT:** | Ms. Elizabeth Kunkel<br>URS Corporation<br>1001 Highlands Plaza Dr. West<br>Suite 300<br>St. Louis, MO 63110 | **BILL TO:** | Accounts Payable Austin<br>URS Corporation<br>P.O. BOX 203970<br>Austin, TX 78720-1088 |
| **PHONE:** | 314-743-4179 | **P.O. #** | 21562735.00013 |
| **FAX:** | | **PROJECT #** | 21562850.04001 Roxana Soil Vapor |
| **DATE RECEIVED:** | 02/05/2013 | **CONTACT:** | Kelly Buettner |
| **DATE COMPLETED:** | 02/19/2013 | | |

| FRACTION # | NAME | TEST | RECEIPT VAC./PRES. | FINAL PRESSURE |
|---|---|---|---|---|
| 19AA | LCSD | Modified TO-15 | NA | NA |
| 19B | LCS | Modified TO-15 | NA | NA |
| 19BB | LCSD | Modified TO-15 | NA | NA |

CERTIFIED BY: Heidi Hayes DATE: 02/19/13

Technical Director

Certfication numbers: AZ Licensure AZ0775, CA NELAP - 12282CA, NY NELAP - 11291,
TX NELAP - T104704434-12-5, UT NELAP CA009332012-3, WA NELAP - C935
Name of Accrediting Agency: NELAP/ORELAP (Oregon Environmental Laboratory Accreditation Program)
Accreditation number: CA300005, Effective date: 10/18/2011, Expiration date: 10/17/2012.
Eurofins Air Toxics Ltd. certifies that the test results contained in this report meet all requirements of the NELAC standards

This report shall not be reproduced, except in full, without the written approval of Eurofins Air Toxics, Inc.

180 BLUE RAVINE ROAD, SUITE B FOLSOM, CA - 9563
(916) 985-1000 . (800) 985-5955 . FAX (916) 985-1020

**LABORATORY NARRATIVE**
**EPA Method TO-15**
**URS Corporation**
**Workorder# 1302083A**

Sixteen 1 Liter Summa Canister samples were received on February 05, 2013. The laboratory performed analysis via EPA Method TO-15 using GC/MS in the full scan mode.

This workorder was independently validated prior to submittal using 'USEPA National Functional Guidelines' as generally applied to the analysis of volatile organic compounds in air. A rules-based, logic driven, independent validation engine was employed to assess completeness, evaluate pass/fail of relevant project quality control requirements and verification of all quantified amounts.

**Receiving Notes**

Sample VMP-51-20-020113 was cancelled on February 15, 2013 per client's request.

**Analytical Notes**

As per client project requirements, the laboratory has reported estimated values for target compound hits that are below the Reporting Limit but greater than the Method Detection Limit. Concentrations that are below the level at which the canister was certified may be false positives.

Due to high-level target compounds, sample VMP-48-30-020113 was analyzed twice. In the "A" fraction, the sample was diluted to bring the highest-level compounds within the calibration range. The "B" fraction is also reported by client request and may be reported with "E" flags indicating the compound exceeds the calibration range. Both runs and associated QC are reported.

Dilution was performed on samples VMP-48-30-020113 and VMP-48-30-020113-DUP due to the presence of high level target species.

**Definition of Data Qualifying Flags**

Eight qualifiers may have been used on the data analysis sheets and indicates as follows:

B - Compound present in laboratory blank greater than reporting limit (background subtraction not performed).
J - Estimated value.
E - Exceeds instrument calibration range.
S - Saturated peak.
Q - Exceeds quality control limits.
U - Compound analyzed for but not detected above the reporting limit.
UJ- Non-detected compound associated with low bias in the CCV and/or LCS.
N - The identification is based on presumptive evidence.

File extensions may have been used on the data analysis sheets and indicates as follows:
a-File was requantified
b-File was quantified by a second column and detector
r1-File was requantified for the purpose of reissue

eurofins | Air Toxics

# Summary of Detected Compounds
# EPA METHOD TO-15 GC/MS FULL SCAN

**Client Sample ID: VMP-48-5-020113**

**Lab ID#: 1302083A-01A**

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 1.3 | 0.38 J | 6.4 | 1.9 J |
| Freon 11 | 1.3 | 0.17 J | 7.2 | 0.96 J |
| Ethanol | 5.1 | 2.4 J | 9.7 | 4.6 J |
| Acetone | 13 | 4.4 J | 30 | 10 J |
| 2-Propanol | 5.1 | 0.70 J | 13 | 1.7 J |
| Carbon Disulfide | 5.1 | ~~1.4 J~~ U | 16 | ~~4.3 J~~ U |
| Methylene Chloride | 13 | ~~0.17 J~~ U | 45 | ~~0.58 J~~ U |
| 2,2,4-Trimethylpentane | 1.3 | 0.74 J | 6.0 | 3.4 J |
| Benzene | 1.3 | 1.5 | 4.1 | 4.8 |
| Toluene | 1.3 | ~~0.10 J~~ U | 4.8 | ~~0.38 J~~ U |
| Tetrachloroethene | 1.3 | ~~0.21 J~~ U | 8.7 | ~~1.4 J~~ U |
| 4-Ethyltoluene | 1.3 | ~~0.11 J~~ U | 6.3 | ~~0.53 J~~ U |
| 1,2,4-Trichlorobenzene | 5.1 | 0.41 J | 38 | 3.1 J |
| Butane | 5.1 | ~~4.9 J~~ U OK | 12 (AF) | ~~12 J~~ U OK (AF) |
| Isopentane | 5.1 | 0.87 J | 15 | 2.6 J |

**Client Sample ID: VMP-48-10-020113**

**Lab ID#: 1302083A-02A**

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 1.3 | 0.49 J | 6.6 | 2.4 J |
| Freon 11 | 1.3 | 0.33 J | 7.5 | 1.8 J |
| Ethanol | 5.3 | 2.8 J | 10 | 5.3 J |
| Acetone | 13 | 4.4 J | 32 | 10 J |
| 2-Propanol | 5.3 | 4.4 J | 13 | 11 J |
| Carbon Disulfide | 5.3 | ~~0.89 J~~ U | 16 | ~~2.8 J~~ U |
| Methylene Chloride | 13 | ~~0.17 J~~ U | 46 | ~~0.60 J~~ U |
| Hexane | 1.3 | 0.25 J | 4.7 | 0.89 J |
| Chloroform | 1.3 | 0.29 J | 6.5 | 1.4 J |
| Benzene | 1.3 | 2.7 | 4.2 | 8.7 |
| Toluene | 1.3 | ~~0.19 J~~ U | 5.0 | ~~0.73 J~~ U |
| Tetrachloroethene | 1.3 | ~~0.27 J~~ U | 9.0 | ~~1.8 J~~ U |
| Isopentane | 5.3 | 0.94 J | 16 | 2.8 J |

eurofins | Air Toxics

# Summary of Detected Compounds
# EPA METHOD TO-15 GC/MS FULL SCAN

**Client Sample ID: VMP-48-20-020113**

**Lab ID#: 1302083A-03A**

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 1.3 | 0.43 J | 6.3 | 2.1 J |
| Freon 11 | 1.3 | 0.36 J | 7.2 | 2.0 J |
| Ethanol | 5.1 | 3.6 J | 9.6 | 6.8 J |
| Acetone | 13 | 5.5 J | 30 | 13 J |
| 2-Propanol | 5.1 | 0.84 J | 12 | 2.0 J |
| Carbon Disulfide | 5.1 | ~~1.1 J~~ U | 16 | ~~3.3 J~~ U |
| Hexane | 1.3 | 0.51 J | 4.5 | 1.8 J |
| 2-Butanone (Methyl Ethyl Ketone) | 5.1 | 0.89 J | 15 | 2.6 J |
| 2,2,4-Trimethylpentane | 1.3 | 0.28 J | 6.0 | 1.3 J |
| Benzene | 1.3 | 0.61 J | 4.1 | 2.0 J |
| Toluene | 1.3 | ~~0.14 J~~ U | 4.8 | ~~0.52 J~~ U |
| Tetrachloroethene | 1.3 | ~~0.19 J~~ U | 8.6 | ~~1.3 J~~ U |
| Butane | 5.1 | 39 | 12 | 92 |
| Isopentane | 5.1 | 7.4 | 15 | 22 |

**Client Sample ID: VMP-48-30-020113** * USE THESE RESULTS ONLY. ALL OTHER RESULTS

**Lab ID#: 1302083A-04A** DF = 10.4X REPORTED FROM 2.61X DILUTION ANALYSIS.

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 11 | 5.2 | 2.9 J | 29 | 16 J |
| Carbon Disulfide | 21 | 8.8 J | 65 | 28 J |
| Hexane | 5.2 | 4.2 J | 18 | 15 J |
| * 2,2,4-Trimethylpentane | 5.2 | 1200 | 24 | 5400 |
| Benzene | 5.2 | 30 | 17 | 97 |
| Heptane | 5.2 | 2.6 J | 21 | 11 J |
| Toluene | 5.2 | 1.4 J | 20 | 5.1 J |
| Tetrachloroethene | 5.2 | 3.4 J | 35 | 23 J |
| m,p-Xylene | 5.2 | 2.2 J | 22 | 9.4 J |
| 4-Ethyltoluene | 5.2 | 2.2 J | 26 | 11 J |
| 1,3,5-Trimethylbenzene | 5.2 | 4.2 J | 26 | 20 J |
| 1,2,4-Trimethylbenzene | 5.2 | 1.7 J | 26 | 8.5 J |
| Butane | 21 | 150 | 49 | 350 |
| Isopentane | 21 | 71 | 61 | 210 |

eurofins | Air Toxics

# Summary of Detected Compounds
# EPA METHOD TO-15 GC/MS FULL SCAN

**Client Sample ID: VMP-48-30-020113**

* DO NOT USE THIS DATA. USE ALL OTHER DATA.

**Lab ID#: 1302083A-04B**

DF = 2.61 x

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 1.3 | 0.62 J | 6.4 | 3.1 J |
| Freon 11 | 1.3 | 2.8 | 7.3 | 16 |
| Acetone | 13 | 2.5 J | 31 | 5.9 J |
| 2-Propanol | 5.2 | 0.63 J | 13 | 1.5 J |
| Carbon Disulfide | 5.2 | 7.7 | 16 | 24 |
| Hexane | 1.3 | 4.3 | 4.6 | 15 |
| * 2,2,4-Trimethylpentane | 1.3 | 1200 E | 6.1 | 5400 E |
| Benzene | 1.3 | 30 | 4.2 | 97 |
| Heptane | 1.3 | 2.5 | 5.3 | 10 |
| Toluene | 1.3 | 1.3 | 4.9 | 5.0 |
| Ethyl Benzene | 1.3 | 0.48 J | 5.7 | 2.1 J |
| m,p-Xylene | 1.3 | 2.3 | 5.7 | 10 |
| o-Xylene | 1.3 | 0.56 J | 5.7 | 2.4 J |
| Cumene | 1.3 | 0.18 J U | 6.4 | 0.88 J U |
| Propylbenzene | 1.3 | 0.22 J U | 6.4 | 1.1 J U |
| 4-Ethyltoluene | 1.3 | 2.4 | 6.4 | 12 |
| 1,3,5-Trimethylbenzene | 1.3 | 5.0 | 6.4 | 24 |
| 1,2,4-Trimethylbenzene | 1.3 | 2.2 | 6.4 | 11 |
| Butane | 5.2 | 130 | 12 | 300 |
| Isopentane | 5.2 | 73 | 15 | 220 |

**Client Sample ID: VMP-48-30-020113-DUP**

**Lab ID#: 1302083A-05A**

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 11 | 5.2 | 3.0 J | 29 | 17 J |
| Carbon Disulfide | 21 | 8.8 J | 65 | 27 J |
| Hexane | 5.2 | 4.8 J | 18 | 17 J |
| 2,2,4-Trimethylpentane | 5.2 | 1200 | 24 | 5500 |
| Benzene | 5.2 | 37 | 17 | 120 |
| Heptane | 5.2 | 2.1 J | 21 | 8.7 J |
| Toluene | 5.2 | 1.4 J | 20 | 5.4 J |
| Tetrachloroethene | 5.2 | 1.2 J | 35 | 8.4 J |

eurofins | Air Toxics

# Summary of Detected Compounds
# EPA METHOD TO-15 GC/MS FULL SCAN

**Client Sample ID: VMP-48-30-020113-DUP**

**Lab ID#: 1302083A-05A**

| | | | | |
|---|---|---|---|---|
| m,p-Xylene | 5.2 | 2.2 J | 22 | 9.4 J |
| 4-Ethyltoluene | 5.2 | 2.5 J | 26 | 12 J |
| 1,3,5-Trimethylbenzene | 5.2 | 4.6 J | 26 | 22 J |
| 1,2,4-Trimethylbenzene | 5.2 | 1.9 J | 26 | 9.3 J |
| Butane | 21 | 150 | 49 | 360 |
| Isopentane | 21 | 74 | 61 | 220 |

**Client Sample ID: VMP-50-10-020113**

**Lab ID#: 1302083A-06A**

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 1.4 | 0.44 J | 6.8 | 2.2 J |
| Freon 11 | 1.4 | 0.19 J | 7.8 | 1.1 J |
| Ethanol | 5.5 | 1.4 J | 10 | 2.7 J |
| Acetone | 14 | 2.6 J | 33 | 6.2 J |
| 2-Propanol | 5.5 | 1.7 J | 14 | 4.2 J |
| Carbon Disulfide | 5.5 | 0.76 J | 17 | 2.4 J |
| Methylene Chloride | 14 | 0.55 J | 48 | 1.9 J |
| Hexane | 1.4 | 0.60 J | 4.9 | 2.1 J |
| Chloroform | 1.4 | 8.8 | 6.7 | 43 |
| 2,2,4-Trimethylpentane | 1.4 | 2.0 | 6.4 | 9.3 |
| Benzene | 1.4 | 0.80 J | 4.4 | 2.6 J |
| Bromodichloromethane | 1.4 | 0.80 J | 9.2 | 5.3 J |
| Toluene | 1.4 | ~~0.18 J~~ | 5.2 | ~~0.69 J~~ |
| Tetrachloroethene | 1.4 | 0.82 J | 9.4 | 5.6 J |
| 4-Ethyltoluene | 1.4 | ~~0.53 J~~ | 6.8 | ~~2.6 J~~ |
| 1,3,5-Trimethylbenzene | 1.4 | ~~0.28 J~~ | 6.8 | ~~1.4 J~~ |
| 1,2,4-Trimethylbenzene | 1.4 | ~~0.81 J~~ | 6.8 | ~~4.0 J~~ |
| Butane | 5.5 | 24 | 13 | 58 |
| Isopentane | 5.5 | 14 | 16 | 42 |

**Client Sample ID: VMP-51-5-020113**

**Lab ID#: 1302083A-07A**

eurofins | Air Toxics

# Summary of Detected Compounds
# EPA METHOD TO-15 GC/MS FULL SCAN

**Client Sample ID: VMP-51-5-020113**

**Lab ID#: 1302083A-07A**

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 1.4 | 0.43 J | 6.8 | 2.1 J |
| Freon 11 | 1.4 | 0.19 J | 7.7 | 1.1 J |
| Ethanol | 5.5 | 0.78 J | 10 | 1.5 J |
| Acetone | 14 | 3.3 J | 32 | 7.7 J |
| 2-Propanol | 5.5 | 1.0 J | 13 | 2.5 J |
| Carbon Disulfide | 5.5 | ~~1.0 J~~ | 17 | ~~3.3 J~~ |
| Methylene Chloride | 14 | ~~0.18 J~~ | 47 | ~~0.61 J~~ |
| Hexane | 1.4 | 0.30 J | 4.8 | 1.1 J |
| Chloroform | 1.4 | 0.77 J | 6.7 | 3.8 J |
| 1,1,1-Trichloroethane | 1.4 | 0.57 J | 7.4 | 3.1 J |
| 2,2,4-Trimethylpentane | 1.4 | 0.97 J | 6.4 | 4.5 J |
| Toluene | 1.4 | ~~0.13 J~~ | 5.1 | ~~0.48 J~~ |
| Tetrachloroethene | 1.4 | ~~0.46 J~~ | 9.2 | ~~3.1 J~~ |
| Isopentane | 5.5 | 0.66 J | 16 | 1.9 J |

**Client Sample ID: VMP-51-10-020113**

**Lab ID#: 1302083A-08A**

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 1.4 | 0.44 J | 6.8 | 2.2 J |
| Freon 11 | 1.4 | 0.16 J | 7.8 | 0.93 J |
| Ethanol | 5.5 | 1.5 J | 10 | 2.9 J |
| Acetone | 14 | 2.6 J | 33 | 6.1 J |
| 2-Propanol | 5.5 | 0.97 J | 14 | 2.4 J |
| Carbon Disulfide | 5.5 | ~~0.76 J~~ | 17 | ~~2.4 J~~ |
| Hexane | 1.4 | 0.36 J | 4.9 | 1.3 J |
| Chloroform | 1.4 | 2.3 | 6.7 | 11 |
| 2,2,4-Trimethylpentane | 1.4 | 0.59 J | 6.4 | 2.7 J |
| Toluene | 1.4 | ~~0.18 J~~ | 5.2 | ~~0.68 J~~ |
| Tetrachloroethene | 1.4 | 0.53 J | 9.4 | 3.6 J |

eurofins | Air Toxics

# Summary of Detected Compounds
# EPA METHOD TO-15 GC/MS FULL SCAN

**Client Sample ID: VMP-52-5-020413**

**Lab ID#: 1302083A-10A**

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 1.3 | 0.49 J | 6.2 | 2.4 J |
| Freon 11 | 1.3 | 0.24 J | 7.1 | 1.4 J |
| Ethanol | 5.0 | 2.1 J | 9.5 | 3.9 J |
| Acetone | 13 | 4.6 J | 30 | 11 J |
| 2-Propanol | 5.0 | 3.2 J | 12 | 7.9 J |
| Carbon Disulfide | 5.0 | ~~1.2 J~~ | 16 | ~~3.7 J~~ |
| Methylene Chloride | 13 | ~~0.16 J~~ | 44 | ~~0.54 J~~ |
| Hexane | 1.3 | 0.41 J | 4.4 | 1.4 J |
| 2-Butanone (Methyl Ethyl Ketone) | 5.0 | 0.94 J | 15 | 2.8 J |
| 1,1,1-Trichloroethane | 1.3 | 3.6 | 6.9 | 20 |
| 2,2,4-Trimethylpentane | 1.3 | 0.53 J | 5.9 | 2.5 J |
| Benzene | 1.3 | 23 | 4.0 | 73 |
| 4-Methyl-2-pentanone | 1.3 | 2.4 | 5.2 | 9.9 |
| Toluene | 1.3 | ~~0.13 J~~ | 4.7 | ~~0.48 J~~ |
| Tetrachloroethene | 1.3 | ~~0.28 J~~ | 8.5 | ~~1.9 J~~ |
| 4-Ethyltoluene | 1.3 | ~~0.15 J~~ | 6.2 | ~~0.74 J~~ |
| 1,2,4-Trimethylbenzene | 1.3 | ~~0.27 J~~ | 6.2 | ~~1.3 J~~ |
| 1,3-Dichlorobenzene | 1.3 | ~~0.18 J~~ | 7.6 | ~~1.1 J~~ |
| 1,4-Dichlorobenzene | 1.3 | ~~0.24 J~~ | 7.6 | ~~1.4 J~~ |
| 1,2,4-Trichlorobenzene | 5.0 | ~~0.70 J~~ | 37 | ~~5.2 J~~ |
| Butane | 5.0 | 2.1 J | 12 | 5.0 J |
| Isopentane | 5.0 | 1.7 J | 15 | 5.0 J |

**Client Sample ID: VMP-52-10-020413**

**Lab ID#: 1302083A-11A**

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 1.2 | 0.54 J | 5.9 | 2.6 J |
| Freon 11 | 1.2 | 0.20 J | 6.7 | 1.1 J |
| Ethanol | 4.8 | 1.7 J | 9.0 | 3.2 J |
| Acetone | 12 | 2.5 J | 28 | 6.0 J |
| 2-Propanol | 4.8 | 1.0 J | 12 | 2.6 J |
| Carbon Disulfide | 4.8 | 7.5 | 15 | 23 |

eurofins | Air Toxics

# Summary of Detected Compounds
# EPA METHOD TO-15 GC/MS FULL SCAN

**Client Sample ID: VMP-52-10-020413**

**Lab ID#: 1302083A-11A**

| | | | | |
|---|---|---|---|---|
| Hexane | 1.2 | 0.30 J | 4.2 | 1.0 J |
| Chloroform | 1.2 | 0.40 J | 5.8 | 2.0 J |
| 1,1,1-Trichloroethane | 1.2 | 4.0 | 6.5 | 22 |
| 2,2,4-Trimethylpentane | 1.2 | 0.68 J | 5.6 | 3.2 J |
| Toluene | 1.2 | ~~0.14 J~~ U | 4.5 | ~~0.63 J~~ U |
| Tetrachloroethene | 1.2 | ~~0.43 J~~ U | 8.1 | ~~2.9 J~~ U |
| 1,2,4-Trichlorobenzene | 4.8 | ~~0.35 J~~ U | 36 | ~~2.6 J~~ U |
| Butane | 4.8 | 12 | 11 | 27 |
| Isopentane | 4.8 | 1.6 J | 14 | 4.7 J |

**Client Sample ID: VMP-52-20-020413**

**Lab ID#: 1302083A-12A**

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 1.3 | 0.58 J | 6.6 | 2.8 J |
| Bromomethane | 13 | 0.66 J | 52 | 2.5 J |
| Freon 11 | 1.3 | ~~0.34 J~~ U | 7.5 | ~~1.9 J~~ U |
| Ethanol | 5.4 | 1.4 J | 10 | 2.7 J |
| Acetone | 13 | 5.6 J | 32 | 13 J |
| 2-Propanol | 5.4 | 2.4 J | 13 | 6.0 J |
| Carbon Disulfide | 5.4 | 3.0 J | 17 | 9.2 J |
| Methylene Chloride | 13 | ~~0.34 J~~ U | 46 | ~~1.2 J~~ U |
| Hexane | 1.3 | 2.9 | 4.7 | 10 |
| 2-Butanone (Methyl Ethyl Ketone) | 5.4 | 1.6 J | 16 | 4.7 J |
| Chloroform | 1.3 | 0.51 J | 6.5 | 2.5 J |
| Cyclohexane | 1.3 | 6.7 | 4.6 | 23 |
| 2,2,4-Trimethylpentane | 1.3 | 13 | 6.2 | 59 |
| Benzene | 1.3 | 24 | 4.3 | 76 |
| Heptane | 1.3 | 1.0 J | 5.5 | 4.3 J |
| Toluene | 1.3 | 0.69 J | 5.0 | 2.6 J |
| Tetrachloroethene | 1.3 | ~~0.47 J~~ U | 9.1 | ~~3.2 J~~ U |
| m,p-Xylene | 1.3 | 0.58 J | 5.8 | 2.5 J |
| o-Xylene | 1.3 | ~~0.34 J~~ U | 5.8 | ~~1.5 J~~ U |
| Propylbenzene | 1.3 | ~~0.23 J~~ U | 6.6 | ~~1.1 J~~ U |
| 4-Ethyltoluene | 1.3 | ~~0.30 J~~ U | 6.6 | ~~1.5 J~~ U |

eurofins | Air Toxics

# Summary of Detected Compounds
# EPA METHOD TO-15 GC/MS FULL SCAN

**Client Sample ID: VMP-52-20-020413**

**Lab ID#: 1302083A-12A**

| | | | | |
|---|---|---|---|---|
| 1,3,5-Trimethylbenzene | 1.3 | ~~0.54 J~~ U | 6.6 | ~~2.6 J~~ U |
| 1,2,4-Trimethylbenzene | 1.3 | ~~0.71 J~~ U | 6.6 | ~~3.5 J~~ U |
| 1,3-Dichlorobenzene | 1.3 | ~~0.36 J~~ U | 8.0 | ~~2.2 J~~ U |
| 1,4-Dichlorobenzene | 1.3 | ~~0.35 J~~ U | 8.0 | ~~2.1 J~~ U |
| 1,2-Dichlorobenzene | 1.3 | ~~0.27 J~~ U | 8.0 | ~~1.6 J~~ U |
| 1,2,4-Trichlorobenzene | 5.4 | ~~1.3 J~~ U | 40 | ~~9.5 J~~ U |
| Hexachlorobutadiene | 5.4 | ~~0.50 J~~ U | 57 | ~~5.3 J~~ U |
| Butane | 5.4 | 35 | 13 | 82 |
| Isopentane | 5.4 | 18 | 16 | 53 |

**Client Sample ID: VMP-52-20-020413-DUP**

**Lab ID#: 1302083A-13A**

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 1.3 | 0.45 J | 6.4 | 2.2 J |
| Freon 11 | 1.3 | ~~0.33 J~~ U | 7.2 | ~~1.8 J~~ U |
| Ethanol | 5.1 | 1.8 J | 9.7 | 3.4 J |
| Acetone | 13 | 2.4 J | 30 | 5.8 J |
| 2-Propanol | 5.1 | 0.58 J | 13 | 1.4 J |
| Carbon Disulfide | 5.1 | 2.8 J | 16 | 8.8 J |
| Methylene Chloride | 13 | ~~0.25 J~~ U | 45 | ~~0.86 J~~ U |
| Hexane | 1.3 | 1.5 | 4.5 | 5.2 |
| Chloroform | 1.3 | 0.47 J | 6.3 | 2.3 J |
| Cyclohexane | 1.3 | 5.1 | 4.4 | 18 |
| 2,2,4-Trimethylpentane | 1.3 | 11 | 6.0 | 52 |
| Benzene | 1.3 | 3.6 | 4.1 | 12 |
| Toluene | 1.3 | 0.44 J | 4.8 | 1.7 J |
| Tetrachloroethene | 1.3 | ~~0.35 J~~ U | 8.7 | ~~2.4 J~~ U |
| 4-Ethyltoluene | 1.3 | ~~0.089 J~~ U | 6.3 | ~~0.44 J~~ U |
| 1,3-Dichlorobenzene | 1.3 | ~~0.17 J~~ U | 7.7 | ~~1.0 J~~ U |
| 1,4-Dichlorobenzene | 1.3 | ~~0.24 J~~ U | 7.7 | ~~1.4 J~~ U |
| 1,2,4-Trichlorobenzene | 5.1 | ~~0.77 J~~ U | 38 | ~~5.7 J~~ U |
| Butane | 5.1 | 29 | 12 | 69 |
| Isopentane | 5.1 | 10 | 15 | 30 |

eurofins | Air Toxics

# Summary of Detected Compounds
# EPA METHOD TO-15 GC/MS FULL SCAN

**Client Sample ID: VMP-52-30-020413**

**Lab ID#: 1302083A-14A**

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 1.4 | 0.49 J | 6.9 | 2.4 J |
| Freon 11 | 1.4 | 0.38 J | 7.9 | 2.1 J |
| Acetone | 14 | 37 | 33 | 88 |
| Carbon Disulfide | 5.6 | ~~2.3 J~~ U | 18 | ~~7.1 J~~ U |
| Hexane | 1.4 | 3.1 | 5.0 | 11 |
| Cyclohexane | 1.4 | 6.7 | 4.8 | 23 |
| 2,2,4-Trimethylpentane | 1.4 | 120 | 6.6 | 580 |
| Benzene | 1.4 | 0.52 J | 4.5 | 1.7 J |
| Heptane | 1.4 | 0.32 J | 5.8 | 1.3 J |
| Toluene | 1.4 | ~~0.25 J~~ U | 5.3 | ~~0.96 J~~ U |
| Tetrachloroethene | 1.4 | ~~0.19 J~~ U | 9.5 | ~~1.3 J~~ U |
| 1,2,4-Trichlorobenzene | 5.6 | ~~0.58 J~~ U | 42 | ~~4.3 J~~ U |
| Butane | 5.6 | 34 | 13 | 82 |
| Isopentane | 5.6 | 14 | 16 | 43 |

**Client Sample ID: VMP-51-30-020413**

**Lab ID#: 1302083A-15A**

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 1.4 | 0.40 J | 7.1 | 2.0 J |
| Freon 11 | 1.4 | ~~0.25 J~~ U | 8.1 | ~~1.4 J~~ U |
| Ethanol | 5.8 | 1.2 J | 11 | 2.3 J |
| Acetone | 14 | 2.6 J | 34 | 6.2 J |
| 2-Propanol | 5.8 | 0.64 J | 14 | 1.6 J |
| Carbon Disulfide | 5.8 | ~~1.3 J~~ U | 18 | ~~4.1 J~~ U |
| Hexane | 1.4 | 1.5 | 5.1 | 5.2 |
| Chloroform | 1.4 | 3.2 | 7.0 | 16 |
| Cyclohexane | 1.4 | 1.4 | 5.0 | 4.9 |
| 2,2,4-Trimethylpentane | 1.4 | 0.88 J | 6.8 | 4.1 J |
| Benzene | 1.4 | 18 | 4.6 | 56 |
| Heptane | 1.4 | 0.62 J | 5.9 | 2.6 J |
| Toluene | 1.4 | ~~0.22 J~~ U | 5.4 | ~~0.82 J~~ U |
| Tetrachloroethene | 1.4 | ~~0.28 J~~ U | 9.8 | ~~1.9 J~~ U |

eurofins | Air Toxics

# Summary of Detected Compounds
# EPA METHOD TO-15 GC/MS FULL SCAN

**Client Sample ID: VMP-51-30-020413**

**Lab ID#: 1302083A-15A**

| | | | | |
|---|---|---|---|---|
| 1,2,4-Trichlorobenzene | 5.8 | ~~0.48 J~~ U | 43 | ~~3.6 J~~ U |
| Butane | 5.8 | 3.0 J | 14 | 7.1 J |
| Isopentane | 5.8 | 5.5 J | 17 | 16 J |

**Client Sample ID: VMP-51-30-020413-DUP**

**Lab ID#: 1302083A-16A**

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 1.4 | 0.44 J | 6.9 | 2.2 J |
| Freon 11 | 1.4 | ~~0.30 J~~ U | 7.9 | ~~1.7 J~~ U |
| Ethanol | 5.6 | 1.1 J | 10 | 2.1 J |
| Acetone | 14 | 4.2 J | 33 | 10 J |
| 2-Propanol | 5.6 | 1.2 J | 14 | 3.1 J |
| Carbon Disulfide | 5.6 | ~~1.2 J~~ U | 18 | ~~3.9 J~~ U |
| Hexane | 1.4 | 2.0 | 5.0 | 7.0 |
| Chloroform | 1.4 | 3.0 | 6.9 | 15 |
| Cyclohexane | 1.4 | 2.5 | 4.8 | 8.7 |
| 2,2,4-Trimethylpentane | 1.4 | 1.2 J | 6.6 | 5.4 J |
| Benzene | 1.4 | 28 | 4.5 | 91 |
| Heptane | 1.4 | 0.92 J | 5.8 | 3.8 J |
| Toluene | 1.4 | ~~0.35 J~~ U | 5.3 | ~~1.3 J~~ U |
| Tetrachloroethene | 1.4 | ~~0.31 J~~ U | 9.5 | ~~2.1 J~~ U |
| Butane | 5.6 | 4.9 J | 13 | 12 J |
| Isopentane | 5.6 | 11 | 16 | 32 |

**Client Sample ID: VMP-51-30-020413-DUP Lab Duplicate**

**Lab ID#: 1302083A-16AA**

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 1.4 | 0.40 J | 6.9 | 2.0 J |
| Freon 11 | 1.4 | ~~0.28 J~~ U | 7.9 | ~~1.6 J~~ U |
| Ethanol | 5.6 | 2.2 J | 10 | 4.2 J |
| Acetone | 14 | 4.6 J | 33 | 11 J |
| 2-Propanol | 5.6 | 1.4 J | 14 | 3.5 J |

eurofins | Air Toxics

# Summary of Detected Compounds
# EPA METHOD TO-15 GC/MS FULL SCAN

**Client Sample ID: VMP-51-30-020413-DUP Lab Duplicate**

**Lab ID#: 1302083A-16AA**

| | | | | |
|---|---|---|---|---|
| Carbon Disulfide | 5.6 | ~~1.2 J~~ U | 18 | ~~3.8 J~~ U |
| Methylene Chloride | 14 | ~~0.19 J~~ U | 49 | ~~0.65 J~~ U |
| Hexane | 1.4 | 2.3 | 5.0 | 8.0 |
| Chloroform | 1.4 | 3.1 | 6.9 | 15 |
| Cyclohexane | 1.4 | 2.6 | 4.8 | 8.8 |
| 2,2,4-Trimethylpentane | 1.4 | 1.4 | 6.6 | 6.4 |
| Benzene | 1.4 | 29 | 4.5 | 94 |
| Heptane | 1.4 | 0.98 J | 5.8 | 4.0 J |
| Toluene | 1.4 | ~~0.35 J~~ U | 5.3 | ~~1.3 J~~ U |
| Tetrachloroethene | 1.4 | ~~0.29 J~~ U | 9.5 | ~~2.0 J~~ U |
| Butane | 5.6 | 5.7 | 13 | 14 |
| Isopentane | 5.6 | 11 | 16 | 33 |

eurofins | Air Toxics

**Client Sample ID: VMP-48-5-020113**

**Lab ID#: 1302083A-01A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p021309** | **Date of Collection:** | **2/1/13 11:20:00 AM** |
| **Dil. Factor:** | **2.57** | **Date of Analysis:** | **2/13/13 03:39 PM** |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 1.3 | 0.38 J | 6.4 | 1.9 J |
| Freon 114 | 1.3 | Not Detected | 9.0 | Not Detected |
| Chloromethane | 13 | Not Detected | 26 | Not Detected |
| Vinyl Chloride | 1.3 | Not Detected | 3.3 | Not Detected |
| 1,3-Butadiene | 1.3 | Not Detected | 2.8 | Not Detected |
| Bromomethane | 13 | Not Detected | 50 | Not Detected |
| Chloroethane | 5.1 | Not Detected | 14 | Not Detected |
| Freon 11 | 1.3 | 0.17 J | 7.2 | 0.96 J |
| Ethanol | 5.1 | 2.4 J | 9.7 | 4.6 J |
| Freon 113 | 1.3 | Not Detected | 9.8 | Not Detected |
| 1,1-Dichloroethene | 1.3 | Not Detected | 5.1 | Not Detected |
| Acetone | 13 | 4.4 J | 30 | 10 J |
| 2-Propanol | 5.1 | 0.70 J | 13 | 1.7 J |
| Carbon Disulfide | 5.1 | ~~1.4 J~~ U | 16 | ~~4.3 J~~ U |
| 3-Chloropropene | 5.1 | Not Detected | 16 | Not Detected |
| Methylene Chloride | 13 | ~~0.17 J~~ U | 45 | ~~0.58 J~~ U |
| Methyl tert-butyl ether | 1.3 | Not Detected | 4.6 | Not Detected |
| trans-1,2-Dichloroethene | 1.3 | Not Detected | 5.1 | Not Detected |
| Hexane | 1.3 | Not Detected | 4.5 | Not Detected |
| 1,1-Dichloroethane | 1.3 | Not Detected | 5.2 | Not Detected |
| 2-Butanone (Methyl Ethyl Ketone) | 5.1 | Not Detected | 15 | Not Detected |
| cis-1,2-Dichloroethene | 1.3 | Not Detected | 5.1 | Not Detected |
| Tetrahydrofuran | 1.3 | Not Detected | 3.8 | Not Detected |
| Chloroform | 1.3 | Not Detected | 6.3 | Not Detected |
| 1,1,1-Trichloroethane | 1.3 | Not Detected | 7.0 | Not Detected |
| Cyclohexane | 1.3 | Not Detected | 4.4 | Not Detected |
| Carbon Tetrachloride | 1.3 | Not Detected | 8.1 | Not Detected |
| 2,2,4-Trimethylpentane | 1.3 | 0.74 J | 6.0 | 3.4 J |
| Benzene | 1.3 | 1.5 | 4.1 | 4.8 |
| 1,2-Dichloroethane | 1.3 | Not Detected | 5.2 | Not Detected |
| Heptane | 1.3 | Not Detected | 5.3 | Not Detected |
| Trichloroethene | 1.3 | Not Detected | 6.9 | Not Detected |
| 1,2-Dichloropropane | 1.3 | Not Detected | 5.9 | Not Detected |
| 1,4-Dioxane | 5.1 | Not Detected | 18 | Not Detected |
| Bromodichloromethane | 1.3 | Not Detected | 8.6 | Not Detected |
| cis-1,3-Dichloropropene | 1.3 | Not Detected | 5.8 | Not Detected |
| 4-Methyl-2-pentanone | 1.3 | Not Detected | 5.3 | Not Detected |
| Toluene | 1.3 | ~~0.10 J~~ U | 4.8 | ~~0.38 J~~ U |
| trans-1,3-Dichloropropene | 1.3 | Not Detected | 5.8 | Not Detected |
| 1,1,2-Trichloroethane | 1.3 | Not Detected | 7.0 | Not Detected |
| Tetrachloroethene | 1.3 | ~~0.21 J~~ U | 8.7 | ~~1.4 J~~ U |
| 2-Hexanone | 5.1 | Not Detected | 21 | Not Detected |

eurofins | Air Toxics

**Client Sample ID: VMP-48-5-020113**

**Lab ID#: 1302083A-01A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p021309** | **Date of Collection:** | **2/1/13 11:20:00 AM** |
| **Dil. Factor:** | **2.57** | **Date of Analysis:** | **2/13/13 03:39 PM** |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Dibromochloromethane | 1.3 | Not Detected | 11 | Not Detected |
| 1,2-Dibromoethane (EDB) | 1.3 | Not Detected | 9.9 | Not Detected |
| Chlorobenzene | 1.3 | Not Detected | 5.9 | Not Detected |
| Ethyl Benzene | 1.3 | Not Detected | 5.6 | Not Detected |
| m,p-Xylene | 1.3 | Not Detected | 5.6 | Not Detected |
| o-Xylene | 1.3 | Not Detected | 5.6 | Not Detected |
| Styrene | 1.3 | Not Detected | 5.5 | Not Detected |
| Bromoform | 1.3 | Not Detected | 13 | Not Detected |
| Cumene | 1.3 | Not Detected | 6.3 | Not Detected |
| 1,1,2,2-Tetrachloroethane | 1.3 | Not Detected | 8.8 | Not Detected |
| Propylbenzene | 1.3 | Not Detected | 6.3 | Not Detected |
| 4-Ethyltoluene | 1.3 | ~~0.11 J~~ U | 6.3 | ~~0.53 J~~ U |
| 1,3,5-Trimethylbenzene | 1.3 | Not Detected | 6.3 | Not Detected |
| 1,2,4-Trimethylbenzene | 1.3 | Not Detected | 6.3 | Not Detected |
| 1,3-Dichlorobenzene | 1.3 | Not Detected | 7.7 | Not Detected |
| 1,4-Dichlorobenzene | 1.3 | Not Detected | 7.7 | Not Detected |
| alpha-Chlorotoluene | 1.3 | Not Detected | 6.6 | Not Detected |
| 1,2-Dichlorobenzene | 1.3 | Not Detected | 7.7 | Not Detected |
| 1,2,4-Trichlorobenzene | 5.1 | ~~0.41 J~~ U | 38 | ~~3.1 J~~ U |
| Hexachlorobutadiene | 5.1 | Not Detected | 55 | Not Detected |
| Butane | 5.1 | 4.9 J | 12 | 12 J |
| Isopentane | 5.1 | 0.87 J | 15 | 2.6 J |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| Toluene-d8 | 97 | 70-130 |
| 1,2-Dichloroethane-d4 | 82 | 70-130 |
| 4-Bromofluorobenzene | 99 | 70-130 |

eurofins | Air Toxics

**Client Sample ID: VMP-48-10-020113**

**Lab ID#: 1302083A-02A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p021311** | **Date of Collection: 2/1/13 1:43:00 PM** | |
| **Dil. Factor:** | **2.66** | **Date of Analysis: 2/13/13 04:48 PM** | |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 1.3 | 0.49 J | 6.6 | 2.4 J |
| Freon 114 | 1.3 | Not Detected | 9.3 | Not Detected |
| Chloromethane | 13 | Not Detected | 27 | Not Detected |
| Vinyl Chloride | 1.3 | Not Detected | 3.4 | Not Detected |
| 1,3-Butadiene | 1.3 | Not Detected | 2.9 | Not Detected |
| Bromomethane | 13 | Not Detected | 52 | Not Detected |
| Chloroethane | 5.3 | Not Detected | 14 | Not Detected |
| Freon 11 | 1.3 | 0.33 J | 7.5 | 1.8 J |
| Ethanol | 5.3 | 2.8 J | 10 | 5.3 J |
| Freon 113 | 1.3 | Not Detected | 10 | Not Detected |
| 1,1-Dichloroethene | 1.3 | Not Detected | 5.3 | Not Detected |
| Acetone | 13 | 4.4 J | 32 | 10 J |
| 2-Propanol | 5.3 | 4.4 J | 13 | 11 J |
| Carbon Disulfide | 5.3 | ~~0.89 J~~ U | 16 | ~~2.8 J~~ U |
| 3-Chloropropene | 5.3 | Not Detected | 17 | Not Detected |
| Methylene Chloride | 13 | ~~0.17 J~~ U | 46 | ~~0.60 J~~ U |
| Methyl tert-butyl ether | 1.3 | Not Detected | 4.8 | Not Detected |
| trans-1,2-Dichloroethene | 1.3 | Not Detected | 5.3 | Not Detected |
| Hexane | 1.3 | 0.25 J | 4.7 | 0.89 J |
| 1,1-Dichloroethane | 1.3 | Not Detected | 5.4 | Not Detected |
| 2-Butanone (Methyl Ethyl Ketone) | 5.3 | Not Detected | 16 | Not Detected |
| cis-1,2-Dichloroethene | 1.3 | Not Detected | 5.3 | Not Detected |
| Tetrahydrofuran | 1.3 | Not Detected | 3.9 | Not Detected |
| Chloroform | 1.3 | 0.29 J | 6.5 | 1.4 J |
| 1,1,1-Trichloroethane | 1.3 | Not Detected | 7.2 | Not Detected |
| Cyclohexane | 1.3 | Not Detected | 4.6 | Not Detected |
| Carbon Tetrachloride | 1.3 | Not Detected | 8.4 | Not Detected |
| 2,2,4-Trimethylpentane | 1.3 | Not Detected | 6.2 | Not Detected |
| Benzene | 1.3 | 2.7 | 4.2 | 8.7 |
| 1,2-Dichloroethane | 1.3 | Not Detected | 5.4 | Not Detected |
| Heptane | 1.3 | Not Detected | 5.4 | Not Detected |
| Trichloroethene | 1.3 | Not Detected | 7.1 | Not Detected |
| 1,2-Dichloropropane | 1.3 | Not Detected | 6.1 | Not Detected |
| 1,4-Dioxane | 5.3 | Not Detected | 19 | Not Detected |
| Bromodichloromethane | 1.3 | Not Detected | 8.9 | Not Detected |
| cis-1,3-Dichloropropene | 1.3 | Not Detected | 6.0 | Not Detected |
| 4-Methyl-2-pentanone | 1.3 | Not Detected | 5.4 | Not Detected |
| Toluene | 1.3 | ~~0.19 J~~ U | 5.0 | ~~0.73 J~~ U |
| trans-1,3-Dichloropropene | 1.3 | Not Detected | 6.0 | Not Detected |
| 1,1,2-Trichloroethane | 1.3 | Not Detected | 7.2 | Not Detected |
| Tetrachloroethene | 1.3 | ~~0.27 J~~ U | 9.0 | ~~1.8 J~~ U |
| 2-Hexanone | 5.3 | Not Detected | 22 | Not Detected |

eurofins | Air Toxics

**Client Sample ID: VMP-48-10-020113**

**Lab ID#: 1302083A-02A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p021311** | **Date of Collection:** | **2/1/13 1:43:00 PM** |
| **Dil. Factor:** | **2.66** | **Date of Analysis:** | **2/13/13 04:48 PM** |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Dibromochloromethane | 1.3 | Not Detected | 11 | Not Detected |
| 1,2-Dibromoethane (EDB) | 1.3 | Not Detected | 10 | Not Detected |
| Chlorobenzene | 1.3 | Not Detected | 6.1 | Not Detected |
| Ethyl Benzene | 1.3 | Not Detected | 5.8 | Not Detected |
| m,p-Xylene | 1.3 | Not Detected | 5.8 | Not Detected |
| o-Xylene | 1.3 | Not Detected | 5.8 | Not Detected |
| Styrene | 1.3 | Not Detected | 5.7 | Not Detected |
| Bromoform | 1.3 | Not Detected | 14 | Not Detected |
| Cumene | 1.3 | Not Detected | 6.5 | Not Detected |
| 1,1,2,2-Tetrachloroethane | 1.3 | Not Detected | 9.1 | Not Detected |
| Propylbenzene | 1.3 | Not Detected | 6.5 | Not Detected |
| 4-Ethyltoluene | 1.3 | Not Detected | 6.5 | Not Detected |
| 1,3,5-Trimethylbenzene | 1.3 | Not Detected | 6.5 | Not Detected |
| 1,2,4-Trimethylbenzene | 1.3 | Not Detected | 6.5 | Not Detected |
| 1,3-Dichlorobenzene | 1.3 | Not Detected | 8.0 | Not Detected |
| 1,4-Dichlorobenzene | 1.3 | Not Detected | 8.0 | Not Detected |
| alpha-Chlorotoluene | 1.3 | Not Detected | 6.9 | Not Detected |
| 1,2-Dichlorobenzene | 1.3 | Not Detected | 8.0 | Not Detected |
| 1,2,4-Trichlorobenzene | 5.3 | Not Detected | 39 | Not Detected |
| Hexachlorobutadiene | 5.3 | Not Detected | 57 | Not Detected |
| Butane | 5.3 | Not Detected | 13 | Not Detected |
| Isopentane | 5.3 | 0.94 J | 16 | 2.8 J |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| Toluene-d8 | 96 | 70-130 |
| 1,2-Dichloroethane-d4 | 83 | 70-130 |
| 4-Bromofluorobenzene | 99 | 70-130 |

eurofins | Air Toxics

**Client Sample ID: VMP-48-20-020113**

**Lab ID#: 1302083A-03A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p021312** | **Date of Collection:** | **2/1/13 2:35:00 PM** |
| **Dil. Factor:** | **2.55** | **Date of Analysis:** | **2/13/13 05:25 PM** |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 1.3 | 0.43 J | 6.3 | 2.1 J |
| Freon 114 | 1.3 | Not Detected | 8.9 | Not Detected |
| Chloromethane | 13 | Not Detected | 26 | Not Detected |
| Vinyl Chloride | 1.3 | Not Detected | 3.2 | Not Detected |
| 1,3-Butadiene | 1.3 | Not Detected | 2.8 | Not Detected |
| Bromomethane | 13 | Not Detected | 50 | Not Detected |
| Chloroethane | 5.1 | Not Detected | 13 | Not Detected |
| Freon 11 | 1.3 | 0.36 J | 7.2 | 2.0 J |
| Ethanol | 5.1 | 3.6 J | 9.6 | 6.8 J |
| Freon 113 | 1.3 | Not Detected | 9.8 | Not Detected |
| 1,1-Dichloroethene | 1.3 | Not Detected | 5.0 | Not Detected |
| Acetone | 13 | 5.5 J | 30 | 13 J |
| 2-Propanol | 5.1 | 0.84 J | 12 | 2.0 J |
| Carbon Disulfide | 5.1 | ~~1.1 J~~ U | 16 | ~~3.3 J~~ U |
| 3-Chloropropene | 5.1 | Not Detected | 16 | Not Detected |
| Methylene Chloride | 13 | Not Detected | 44 | Not Detected |
| Methyl tert-butyl ether | 1.3 | Not Detected | 4.6 | Not Detected |
| trans-1,2-Dichloroethene | 1.3 | Not Detected | 5.0 | Not Detected |
| Hexane | 1.3 | 0.51 J | 4.5 | 1.8 J |
| 1,1-Dichloroethane | 1.3 | Not Detected | 5.2 | Not Detected |
| 2-Butanone (Methyl Ethyl Ketone) | 5.1 | 0.89 J | 15 | 2.6 J |
| cis-1,2-Dichloroethene | 1.3 | Not Detected | 5.0 | Not Detected |
| Tetrahydrofuran | 1.3 | Not Detected | 3.8 | Not Detected |
| Chloroform | 1.3 | Not Detected | 6.2 | Not Detected |
| 1,1,1-Trichloroethane | 1.3 | Not Detected | 7.0 | Not Detected |
| Cyclohexane | 1.3 | Not Detected | 4.4 | Not Detected |
| Carbon Tetrachloride | 1.3 | Not Detected | 8.0 | Not Detected |
| 2,2,4-Trimethylpentane | 1.3 | 0.28 J | 6.0 | 1.3 J |
| Benzene | 1.3 | 0.61 J | 4.1 | 2.0 J |
| 1,2-Dichloroethane | 1.3 | Not Detected | 5.2 | Not Detected |
| Heptane | 1.3 | Not Detected | 5.2 | Not Detected |
| Trichloroethene | 1.3 | Not Detected | 6.8 | Not Detected |
| 1,2-Dichloropropane | 1.3 | Not Detected | 5.9 | Not Detected |
| 1,4-Dioxane | 5.1 | Not Detected | 18 | Not Detected |
| Bromodichloromethane | 1.3 | Not Detected | 8.5 | Not Detected |
| cis-1,3-Dichloropropene | 1.3 | Not Detected | 5.8 | Not Detected |
| 4-Methyl-2-pentanone | 1.3 | Not Detected U | 5.2 | Not Detected |
| Toluene | 1.3 | ~~0.14 J~~ | 4.8 | ~~0.52 J~~ U |
| trans-1,3-Dichloropropene | 1.3 | Not Detected | 5.8 | Not Detected |
| 1,1,2-Trichloroethane | 1.3 | Not Detected | 7.0 | Not Detected |
| Tetrachloroethene | 1.3 | ~~0.19 J~~ U | 8.6 | ~~1.3 J~~ U |
| 2-Hexanone | 5.1 | Not Detected | 21 | Not Detected |

eurofins | Air Toxics

**Client Sample ID: VMP-48-20-020113**

**Lab ID#: 1302083A-03A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p021312** | **Date of Collection: 2/1/13 2:35:00 PM** | |
| **Dil. Factor:** | **2.55** | **Date of Analysis: 2/13/13 05:25 PM** | |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Dibromochloromethane | 1.3 | Not Detected | 11 | Not Detected |
| 1,2-Dibromoethane (EDB) | 1.3 | Not Detected | 9.8 | Not Detected |
| Chlorobenzene | 1.3 | Not Detected | 5.9 | Not Detected |
| Ethyl Benzene | 1.3 | Not Detected | 5.5 | Not Detected |
| m,p-Xylene | 1.3 | Not Detected | 5.5 | Not Detected |
| o-Xylene | 1.3 | Not Detected | 5.5 | Not Detected |
| Styrene | 1.3 | Not Detected | 5.4 | Not Detected |
| Bromoform | 1.3 | Not Detected | 13 | Not Detected |
| Cumene | 1.3 | Not Detected | 6.3 | Not Detected |
| 1,1,2,2-Tetrachloroethane | 1.3 | Not Detected | 8.8 | Not Detected |
| Propylbenzene | 1.3 | Not Detected | 6.3 | Not Detected |
| 4-Ethyltoluene | 1.3 | Not Detected | 6.3 | Not Detected |
| 1,3,5-Trimethylbenzene | 1.3 | Not Detected | 6.3 | Not Detected |
| 1,2,4-Trimethylbenzene | 1.3 | Not Detected | 6.3 | Not Detected |
| 1,3-Dichlorobenzene | 1.3 | Not Detected | 7.7 | Not Detected |
| 1,4-Dichlorobenzene | 1.3 | Not Detected | 7.7 | Not Detected |
| alpha-Chlorotoluene | 1.3 | Not Detected | 6.6 | Not Detected |
| 1,2-Dichlorobenzene | 1.3 | Not Detected | 7.7 | Not Detected |
| 1,2,4-Trichlorobenzene | 5.1 | Not Detected | 38 | Not Detected |
| Hexachlorobutadiene | 5.1 | Not Detected | 54 | Not Detected |
| Butane | 5.1 | 39 | 12 | 92 |
| Isopentane | 5.1 | 7.4 | 15 | 22 |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| Toluene-d8 | 97 | 70-130 |
| 1,2-Dichloroethane-d4 | 82 | 70-130 |
| 4-Bromofluorobenzene | 97 | 70-130 |

eurofins | Air Toxics

* USE THIS RESULT ONLY. ALL OTHER RESULTS REPORTED FROM THE 2.61x DILUTION ANALYSIS

**Client Sample ID: VMP-48-30-020113**
**Lab ID#: 1302083A-04A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p021318** | **Date of Collection:** | **2/1/13 3:31:00 PM** |
| **Dil. Factor:** | **10.4** | **Date of Analysis:** | **2/13/13 09:17 PM** |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 5.2 | Not Detected | 26 | Not Detected |
| Freon 114 | 5.2 | Not Detected | 36 | Not Detected |
| Chloromethane | 52 | Not Detected | 110 | Not Detected |
| Vinyl Chloride | 5.2 | Not Detected | 13 | Not Detected |
| 1,3-Butadiene | 5.2 | Not Detected | 12 | Not Detected |
| Bromomethane | 52 | Not Detected | 200 | Not Detected |
| Chloroethane | 21 | Not Detected | 55 | Not Detected |
| Freon 11 | 5.2 | 2.9 J | 29 | 16 J |
| Ethanol | 21 | Not Detected | 39 | Not Detected |
| Freon 113 | 5.2 | Not Detected | 40 | Not Detected |
| 1,1-Dichloroethene | 5.2 | Not Detected | 21 | Not Detected |
| Acetone | 52 | Not Detected | 120 | Not Detected |
| 2-Propanol | 21 | Not Detected | 51 | Not Detected |
| Carbon Disulfide | 21 | 8.8 J | 65 | 28 J |
| 3-Chloropropene | 21 | Not Detected | 65 | Not Detected |
| Methylene Chloride | 52 | Not Detected | 180 | Not Detected |
| Methyl tert-butyl ether | 5.2 | Not Detected | 19 | Not Detected |
| trans-1,2-Dichloroethene | 5.2 | Not Detected | 21 | Not Detected |
| Hexane | 5.2 | 4.2 J | 18 | 15 J |
| 1,1-Dichloroethane | 5.2 | Not Detected | 21 | Not Detected |
| 2-Butanone (Methyl Ethyl Ketone) | 21 | Not Detected | 61 | Not Detected |
| cis-1,2-Dichloroethene | 5.2 | Not Detected | 21 | Not Detected |
| Tetrahydrofuran | 5.2 | Not Detected | 15 | Not Detected |
| Chloroform | 5.2 | Not Detected | 25 | Not Detected |
| 1,1,1-Trichloroethane | 5.2 | Not Detected | 28 | Not Detected |
| Cyclohexane | 5.2 | Not Detected | 18 | Not Detected |
| Carbon Tetrachloride | 5.2 | Not Detected | 33 | Not Detected |
| * 2,2,4-Trimethylpentane | 5.2 | 1200 | 24 | 5400 |
| Benzene | 5.2 | 30 | 17 | 97 |
| 1,2-Dichloroethane | 5.2 | Not Detected | 21 | Not Detected |
| Heptane | 5.2 | 2.6 J | 21 | 11 J |
| Trichloroethene | 5.2 | Not Detected | 28 | Not Detected |
| 1,2-Dichloropropane | 5.2 | Not Detected | 24 | Not Detected |
| 1,4-Dioxane | 21 | Not Detected | 75 | Not Detected |
| Bromodichloromethane | 5.2 | Not Detected | 35 | Not Detected |
| cis-1,3-Dichloropropene | 5.2 | Not Detected | 24 | Not Detected |
| 4-Methyl-2-pentanone | 5.2 | Not Detected | 21 | Not Detected |
| Toluene | 5.2 | 1.4 J | 20 | 5.1 J |
| trans-1,3-Dichloropropene | 5.2 | Not Detected | 24 | Not Detected |
| 1,1,2-Trichloroethane | 5.2 | Not Detected | 28 | Not Detected |
| Tetrachloroethene | 5.2 | 3.4 J | 35 | 23 J |
| 2-Hexanone | 21 | Not Detected | 85 | Not Detected |

eurofins | Air Toxics

**Client Sample ID: VMP-48-30-020113**

**Lab ID#: 1302083A-04A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p021318** | **Date of Collection: 2/1/13 3:31:00 PM** | |
| **Dil. Factor:** | **10.4** | **Date of Analysis: 2/13/13 09:17 PM** | |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Dibromochloromethane | 5.2 | Not Detected | 44 | Not Detected |
| 1,2-Dibromoethane (EDB) | 5.2 | Not Detected | 40 | Not Detected |
| Chlorobenzene | 5.2 | Not Detected | 24 | Not Detected |
| Ethyl Benzene | 5.2 | Not Detected | 22 | Not Detected |
| m,p-Xylene | 5.2 | 2.2 J | 22 | 9.4 J |
| o-Xylene | 5.2 | Not Detected | 22 | Not Detected |
| Styrene | 5.2 | Not Detected | 22 | Not Detected |
| Bromoform | 5.2 | Not Detected | 54 | Not Detected |
| Cumene | 5.2 | Not Detected | 26 | Not Detected |
| 1,1,2,2-Tetrachloroethane | 5.2 | Not Detected | 36 | Not Detected |
| Propylbenzene | 5.2 | Not Detected | 26 | Not Detected |
| 4-Ethyltoluene | 5.2 | 2.2 J | 26 | 11 J |
| 1,3,5-Trimethylbenzene | 5.2 | 4.2 J | 26 | 20 J |
| 1,2,4-Trimethylbenzene | 5.2 | 1.7 J | 26 | 8.5 J |
| 1,3-Dichlorobenzene | 5.2 | Not Detected | 31 | Not Detected |
| 1,4-Dichlorobenzene | 5.2 | Not Detected | 31 | Not Detected |
| alpha-Chlorotoluene | 5.2 | Not Detected | 27 | Not Detected |
| 1,2-Dichlorobenzene | 5.2 | Not Detected | 31 | Not Detected |
| 1,2,4-Trichlorobenzene | 21 | Not Detected | 150 | Not Detected |
| Hexachlorobutadiene | 21 | Not Detected | 220 | Not Detected |
| Butane | 21 | 150 | 49 | 350 |
| Isopentane | 21 | 71 | 61 | 210 |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| Toluene-d8 | 100 | 70-130 |
| 1,2-Dichloroethane-d4 | 90 | 70-130 |
| 4-Bromofluorobenzene | 95 | 70-130 |

eurofins | Air Toxics

**Client Sample ID: VMP-48-30-020113** * DO NOT USE THIS DATA. USE ALL OTHER DATA.

**Lab ID#: 1302083A-04B**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p021313** | **Date of Collection:** | **2/1/13 3:31:00 PM** |
| **Dil. Factor:** | **2.61** | **Date of Analysis:** | **2/13/13 06:01 PM** |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 1.3 | 0.62 J J | 6.4 | 3.1 J J |
| Freon 114 | 1.3 | Not Detected | 9.1 | Not Detected |
| Chloromethane | 13 | Not Detected | 27 | Not Detected |
| Vinyl Chloride | 1.3 | Not Detected | 3.3 | Not Detected |
| 1,3-Butadiene | 1.3 | Not Detected | 2.9 | Not Detected |
| Bromomethane | 13 | Not Detected | 51 | Not Detected |
| Chloroethane | 5.2 | Not Detected | 14 | Not Detected |
| Freon 11 | 1.3 | 2.8 | 7.3 | 16 |
| Ethanol | 5.2 | Not Detected | 9.8 | Not Detected |
| Freon 113 | 1.3 | Not Detected | 10 | Not Detected |
| 1,1-Dichloroethene | 1.3 | Not Detected | 5.2 | Not Detected |
| Acetone | 13 | 2.5 J J | 31 | 5.9 J J |
| 2-Propanol | 5.2 | 0.63 J J | 13 | 1.5 J J |
| Carbon Disulfide | 5.2 | 7.7 | 16 | 24 |
| 3-Chloropropene | 5.2 | Not Detected | 16 | Not Detected |
| Methylene Chloride | 13 | Not Detected | 45 | Not Detected |
| Methyl tert-butyl ether | 1.3 | Not Detected | 4.7 | Not Detected |
| trans-1,2-Dichloroethene | 1.3 | Not Detected | 5.2 | Not Detected |
| Hexane | 1.3 | 4.3 | 4.6 | 15 |
| 1,1-Dichloroethane | 1.3 | Not Detected | 5.3 | Not Detected |
| 2-Butanone (Methyl Ethyl Ketone) | 5.2 | Not Detected | 15 | Not Detected |
| cis-1,2-Dichloroethene | 1.3 | Not Detected | 5.2 | Not Detected |
| Tetrahydrofuran | 1.3 | Not Detected | 3.8 | Not Detected |
| Chloroform | 1.3 | Not Detected | 6.4 | Not Detected |
| 1,1,1-Trichloroethane | 1.3 | Not Detected | 7.1 | Not Detected |
| Cyclohexane | 1.3 | Not Detected | 4.5 | Not Detected |
| Carbon Tetrachloride | 1.3 | Not Detected | 8.2 | Not Detected |
| * ~~2,2,4-Trimethylpentane~~ | ~~1.3~~ | ~~1200 E~~ | ~~6.1~~ | ~~5400 E~~ |
| Benzene | 1.3 | 30 | 4.2 | 97 |
| 1,2-Dichloroethane | 1.3 | Not Detected | 5.3 | Not Detected |
| Heptane | 1.3 | 2.5 | 5.3 | 10 |
| Trichloroethene | 1.3 | Not Detected | 7.0 | Not Detected |
| 1,2-Dichloropropane | 1.3 | Not Detected | 6.0 | Not Detected |
| 1,4-Dioxane | 5.2 | Not Detected | 19 | Not Detected |
| Bromodichloromethane | 1.3 | Not Detected | 8.7 | Not Detected |
| cis-1,3-Dichloropropene | 1.3 | Not Detected | 5.9 | Not Detected |
| 4-Methyl-2-pentanone | 1.3 | Not Detected | 5.3 | Not Detected |
| Toluene | 1.3 | 1.3 | 4.9 | 5.0 |
| trans-1,3-Dichloropropene | 1.3 | Not Detected | 5.9 | Not Detected |
| 1,1,2-Trichloroethane | 1.3 | Not Detected | 7.1 | Not Detected |
| Tetrachloroethene | 1.3 | Not Detected | 8.8 | Not Detected |
| 2-Hexanone | 5.2 | Not Detected | 21 | Not Detected |

eurofins | Air Toxics

**Client Sample ID: VMP-48-30-020113-DUP**

**Lab ID#: 1302083A-05A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p021319** | **Date of Collection:** | **2/1/13 3:31:00 PM** |
| **Dil. Factor:** | **10.4** | **Date of Analysis:** | **2/13/13 09:37 PM** |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 5.2 | Not Detected UJ | 26 | Not Detected UJ |
| Freon 114 | 5.2 | Not Detected | 36 | Not Detected |
| Chloromethane | 52 | Not Detected | 110 | Not Detected |
| Vinyl Chloride | 5.2 | Not Detected | 13 | Not Detected |
| 1,3-Butadiene | 5.2 | Not Detected | 12 | Not Detected |
| Bromomethane | 52 | Not Detected | 200 | Not Detected |
| Chloroethane | 21 | Not Detected | 55 | Not Detected |
| Freon 11 | 5.2 | 3.0 J | 29 | 17 J |
| Ethanol | 21 | Not Detected | 39 | Not Detected |
| Freon 113 | 5.2 | Not Detected | 40 | Not Detected |
| 1,1-Dichloroethene | 5.2 | Not Detected | 21 | Not Detected |
| Acetone | 52 | Not Detected UJ | 120 | Not Detected UJ |
| 2-Propanol | 21 | Not Detected UJ | 51 | Not Detected UJ |
| Carbon Disulfide | 21 | 8.8 J | 65 | 27 J |
| 3-Chloropropene | 21 | Not Detected | 65 | Not Detected |
| Methylene Chloride | 52 | Not Detected | 180 | Not Detected |
| Methyl tert-butyl ether | 5.2 | Not Detected | 19 | Not Detected |
| trans-1,2-Dichloroethene | 5.2 | Not Detected | 21 | Not Detected |
| Hexane | 5.2 | 4.8 J | 18 | 17 J |
| 1,1-Dichloroethane | 5.2 | Not Detected | 21 | Not Detected |
| 2-Butanone (Methyl Ethyl Ketone) | 21 | Not Detected | 61 | Not Detected |
| cis-1,2-Dichloroethene | 5.2 | Not Detected | 21 | Not Detected |
| Tetrahydrofuran | 5.2 | Not Detected | 15 | Not Detected |
| Chloroform | 5.2 | Not Detected | 25 | Not Detected |
| 1,1,1-Trichloroethane | 5.2 | Not Detected | 28 | Not Detected |
| Cyclohexane | 5.2 | Not Detected | 18 | Not Detected |
| Carbon Tetrachloride | 5.2 | Not Detected | 33 | Not Detected |
| 2,2,4-Trimethylpentane | 5.2 | 1200 | 24 | 5500 |
| Benzene | 5.2 | 37 | 17 | 120 |
| 1,2-Dichloroethane | 5.2 | Not Detected | 21 | Not Detected |
| Heptane | 5.2 | 2.1 J | 21 | 8.7 J |
| Trichloroethene | 5.2 | Not Detected | 28 | Not Detected |
| 1,2-Dichloropropane | 5.2 | Not Detected | 24 | Not Detected |
| 1,4-Dioxane | 21 | Not Detected | 75 | Not Detected |
| Bromodichloromethane | 5.2 | Not Detected | 35 | Not Detected |
| cis-1,3-Dichloropropene | 5.2 | Not Detected | 24 | Not Detected |
| 4-Methyl-2-pentanone | 5.2 | Not Detected | 21 | Not Detected |
| Toluene | 5.2 | 1.4 J | 20 | 5.4 J |
| trans-1,3-Dichloropropene | 5.2 | Not Detected | 24 | Not Detected |
| 1,1,2-Trichloroethane | 5.2 | Not Detected | 28 | Not Detected |
| Tetrachloroethene | 5.2 | 1.2 J | 35 | 8.4 J |
| 2-Hexanone | 21 | Not Detected | 85 | Not Detected |

eurofins | Air Toxics

**Client Sample ID: VMP-48-30-020113**

**Lab ID#: 1302083A-04B**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p021313** | **Date of Collection: 2/1/13 3:31:00 PM** | |
| **Dil. Factor:** | **2.61** | **Date of Analysis: 2/13/13 06:01 PM** | |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Dibromochloromethane | 1.3 | Not Detected | 11 | Not Detected |
| 1,2-Dibromoethane (EDB) | 1.3 | Not Detected | 10 | Not Detected |
| Chlorobenzene | 1.3 | Not Detected | 6.0 | Not Detected |
| Ethyl Benzene | 1.3 | 0.48 J | 5.7 | 2.1 J |
| m,p-Xylene | 1.3 | 2.3 | 5.7 | 10 |
| o-Xylene | 1.3 | 0.56 J | 5.7 | 2.4 J |
| Styrene | 1.3 | Not Detected | 5.6 | Not Detected |
| Bromoform | 1.3 | Not Detected | 13 | Not Detected |
| Cumene | 1.3 | ~~0.18 J~~ | 6.4 | ~~0.88 J~~ |
| 1,1,2,2-Tetrachloroethane | 1.3 | Not Detected | 9.0 | Not Detected |
| Propylbenzene | 1.3 | ~~0.22 J~~ | 6.4 | ~~1.1 J~~ |
| 4-Ethyltoluene | 1.3 | 2.4 | 6.4 | 12 |
| 1,3,5-Trimethylbenzene | 1.3 | 5.0 | 6.4 | 24 |
| 1,2,4-Trimethylbenzene | 1.3 | 2.2 | 6.4 | 11 |
| 1,3-Dichlorobenzene | 1.3 | Not Detected | 7.8 | Not Detected |
| 1,4-Dichlorobenzene | 1.3 | Not Detected | 7.8 | Not Detected |
| alpha-Chlorotoluene | 1.3 | Not Detected | 6.8 | Not Detected |
| 1,2-Dichlorobenzene | 1.3 | Not Detected | 7.8 | Not Detected |
| 1,2,4-Trichlorobenzene | 5.2 | Not Detected | 39 | Not Detected |
| Hexachlorobutadiene | 5.2 | Not Detected | 56 | Not Detected |
| Butane | 5.2 | 130 | 12 | 300 |
| Isopentane | 5.2 | 73 | 15 | 220 |

J = Estimated value.
E = Exceeds instrument calibration range.
**Container Type: 1 Liter Summa Canister**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| Toluene-d8 | 101 | 70-130 |
| 1,2-Dichloroethane-d4 | 102 | 70-130 |
| 4-Bromofluorobenzene | 96 | 70-130 |

eurofins | Air Toxics

**Client Sample ID: VMP-48-30-020113-DUP**

**Lab ID#: 1302083A-05A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p021319** | **Date of Collection:** | **2/1/13 3:31:00 PM** |
| **Dil. Factor:** | **10.4** | **Date of Analysis:** | **2/13/13 09:37 PM** |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Dibromochloromethane | 5.2 | Not Detected | 44 | Not Detected |
| 1,2-Dibromoethane (EDB) | 5.2 | Not Detected | 40 | Not Detected |
| Chlorobenzene | 5.2 | Not Detected | 24 | Not Detected |
| Ethyl Benzene | 5.2 | Not Detected UJ | 22 | Not Detected UJ |
| m,p-Xylene | 5.2 | 2.2 J | 22 | 9.4 J |
| o-Xylene | 5.2 | Not Detected UJ | 22 | Not Detected UJ |
| Styrene | 5.2 | Not Detected | 22 | Not Detected |
| Bromoform | 5.2 | Not Detected | 54 | Not Detected |
| Cumene | 5.2 | Not Detected | 26 | Not Detected |
| 1,1,2,2-Tetrachloroethane | 5.2 | Not Detected | 36 | Not Detected |
| Propylbenzene | 5.2 | Not Detected | 26 | Not Detected |
| 4-Ethyltoluene | 5.2 | 2.5 J | 26 | 12 J |
| 1,3,5-Trimethylbenzene | 5.2 | 4.6 J | 26 | 22 J |
| 1,2,4-Trimethylbenzene | 5.2 | 1.9 J | 26 | 9.3 J |
| 1,3-Dichlorobenzene | 5.2 | Not Detected | 31 | Not Detected |
| 1,4-Dichlorobenzene | 5.2 | Not Detected | 31 | Not Detected |
| alpha-Chlorotoluene | 5.2 | Not Detected | 27 | Not Detected |
| 1,2-Dichlorobenzene | 5.2 | Not Detected | 31 | Not Detected |
| 1,2,4-Trichlorobenzene | 21 | Not Detected | 150 | Not Detected |
| Hexachlorobutadiene | 21 | Not Detected | 220 | Not Detected |
| Butane | 21 | 150 | 49 | 360 |
| Isopentane | 21 | 74 | 61 | 220 |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| Toluene-d8 | 98 | 70-130 |
| 1,2-Dichloroethane-d4 | 88 | 70-130 |
| 4-Bromofluorobenzene | 95 | 70-130 |

eurofins | Air Toxics

**Client Sample ID: VMP-50-10-020113**

**Lab ID#: 1302083A-06A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p021320** | **Date of Collection:** | **2/1/13 1:30:00 PM** |
| **Dil. Factor:** | **2.76** | **Date of Analysis:** | **2/13/13 10:02 PM** |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 1.4 | 0.44 J | 6.8 | 2.2 J |
| Freon 114 | 1.4 | Not Detected | 9.6 | Not Detected |
| Chloromethane | 14 | Not Detected | 28 | Not Detected |
| Vinyl Chloride | 1.4 | Not Detected | 3.5 | Not Detected |
| 1,3-Butadiene | 1.4 | Not Detected | 3.0 | Not Detected |
| Bromomethane | 14 | Not Detected | 54 | Not Detected |
| Chloroethane | 5.5 | Not Detected | 14 | Not Detected |
| Freon 11 | 1.4 | 0.19 J | 7.8 | 1.1 J |
| Ethanol | 5.5 | 1.4 J | 10 | 2.7 J |
| Freon 113 | 1.4 | Not Detected | 10 | Not Detected |
| 1,1-Dichloroethene | 1.4 | Not Detected | 5.5 | Not Detected |
| Acetone | 14 | 2.6 J | 33 | 6.2 J |
| 2-Propanol | 5.5 | 1.7 J | 14 | 4.2 J |
| Carbon Disulfide | 5.5 | 0.76 J | 17 | 2.4 J |
| 3-Chloropropene | 5.5 | Not Detected | 17 | Not Detected |
| Methylene Chloride | 14 | 0.55 J | 48 | 1.9 J |
| Methyl tert-butyl ether | 1.4 | Not Detected | 5.0 | Not Detected |
| trans-1,2-Dichloroethene | 1.4 | Not Detected | 5.5 | Not Detected |
| Hexane | 1.4 | 0.60 J | 4.9 | 2.1 J |
| 1,1-Dichloroethane | 1.4 | Not Detected | 5.6 | Not Detected |
| 2-Butanone (Methyl Ethyl Ketone) | 5.5 | Not Detected | 16 | Not Detected |
| cis-1,2-Dichloroethene | 1.4 | Not Detected | 5.5 | Not Detected |
| Tetrahydrofuran | 1.4 | Not Detected | 4.1 | Not Detected |
| Chloroform | 1.4 | 8.8 | 6.7 | 43 |
| 1,1,1-Trichloroethane | 1.4 | Not Detected | 7.5 | Not Detected |
| Cyclohexane | 1.4 | Not Detected | 4.8 | Not Detected |
| Carbon Tetrachloride | 1.4 | Not Detected | 8.7 | Not Detected |
| 2,2,4-Trimethylpentane | 1.4 | 2.0 | 6.4 | 9.3 |
| Benzene | 1.4 | 0.80 J | 4.4 | 2.6 J |
| 1,2-Dichloroethane | 1.4 | Not Detected | 5.6 | Not Detected |
| Heptane | 1.4 | Not Detected | 5.6 | Not Detected |
| Trichloroethene | 1.4 | Not Detected | 7.4 | Not Detected |
| 1,2-Dichloropropane | 1.4 | Not Detected | 6.4 | Not Detected |
| 1,4-Dioxane | 5.5 | Not Detected | 20 | Not Detected |
| Bromodichloromethane | 1.4 | 0.80 J | 9.2 | 5.3 J |
| cis-1,3-Dichloropropene | 1.4 | Not Detected | 6.3 | Not Detected |
| 4-Methyl-2-pentanone | 1.4 | Not Detected | 5.6 | Not Detected |
| Toluene | 1.4 | ~~0.18 J~~ | 5.2 | ~~0.69 J~~ |
| trans-1,3-Dichloropropene | 1.4 | Not Detected | 6.3 | Not Detected |
| 1,1,2-Trichloroethane | 1.4 | Not Detected | 7.5 | Not Detected |
| Tetrachloroethene | 1.4 | 0.82 J | 9.4 | 5.6 J |
| 2-Hexanone | 5.5 | Not Detected | 23 | Not Detected |

eurofins | Air Toxics

**Client Sample ID: VMP-50-10-020113**

**Lab ID#: 1302083A-06A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p021320** | **Date of Collection: 2/1/13 1:30:00 PM** | |
| **Dil. Factor:** | **2.76** | **Date of Analysis: 2/13/13 10:02 PM** | |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Dibromochloromethane | 1.4 | Not Detected | 12 | Not Detected |
| 1,2-Dibromoethane (EDB) | 1.4 | Not Detected | 11 | Not Detected |
| Chlorobenzene | 1.4 | Not Detected | 6.4 | Not Detected |
| Ethyl Benzene | 1.4 | Not Detected | 6.0 | Not Detected |
| m,p-Xylene | 1.4 | Not Detected | 6.0 | Not Detected |
| o-Xylene | 1.4 | Not Detected | 6.0 | Not Detected |
| Styrene | 1.4 | Not Detected | 5.9 | Not Detected |
| Bromoform | 1.4 | Not Detected | 14 | Not Detected |
| Cumene | 1.4 | Not Detected | 6.8 | Not Detected |
| 1,1,2,2-Tetrachloroethane | 1.4 | Not Detected | 9.5 | Not Detected |
| Propylbenzene | 1.4 | Not Detected | 6.8 | Not Detected |
| 4-Ethyltoluene | 1.4 | ~~0.53 J~~ U | 6.8 | ~~2.6 J~~ U |
| 1,3,5-Trimethylbenzene | 1.4 | ~~0.28 J~~ U | 6.8 | ~~1.4 J~~ U |
| 1,2,4-Trimethylbenzene | 1.4 | ~~0.81 J~~ U | 6.8 | ~~4.0 J~~ U |
| 1,3-Dichlorobenzene | 1.4 | Not Detected | 8.3 | Not Detected |
| 1,4-Dichlorobenzene | 1.4 | Not Detected | 8.3 | Not Detected |
| alpha-Chlorotoluene | 1.4 | Not Detected | 7.1 | Not Detected |
| 1,2-Dichlorobenzene | 1.4 | Not Detected | 8.3 | Not Detected |
| 1,2,4-Trichlorobenzene | 5.5 | Not Detected | 41 | Not Detected |
| Hexachlorobutadiene | 5.5 | Not Detected | 59 | Not Detected |
| Butane | 5.5 | 24 | 13 | 58 |
| Isopentane | 5.5 | 14 | 16 | 42 |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| Toluene-d8 | 98 | 70-130 |
| 1,2-Dichloroethane-d4 | 83 | 70-130 |
| 4-Bromofluorobenzene | 100 | 70-130 |

eurofins | Air Toxics

**Client Sample ID: VMP-51-5-020113**

**Lab ID#: 1302083A-07A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p021321** | **Date of Collection: 2/1/13 2:13:00 PM** | |
| **Dil. Factor:** | **2.73** | **Date of Analysis: 2/13/13 10:23 PM** | |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 1.4 | 0.43 J | 6.8 | 2.1 J |
| Freon 114 | 1.4 | Not Detected | 9.5 | Not Detected |
| Chloromethane | 14 | Not Detected | 28 | Not Detected |
| Vinyl Chloride | 1.4 | Not Detected | 3.5 | Not Detected |
| 1,3-Butadiene | 1.4 | Not Detected | 3.0 | Not Detected |
| Bromomethane | 14 | Not Detected | 53 | Not Detected |
| Chloroethane | 5.5 | Not Detected | 14 | Not Detected |
| Freon 11 | 1.4 | 0.19 J | 7.7 | 1.1 J |
| Ethanol | 5.5 | 0.78 J | 10 | 1.5 J |
| Freon 113 | 1.4 | Not Detected | 10 | Not Detected |
| 1,1-Dichloroethene | 1.4 | Not Detected | 5.4 | Not Detected |
| Acetone | 14 | 3.3 J | 32 | 7.7 J |
| 2-Propanol | 5.5 | 1.0 J | 13 | 2.5 J |
| Carbon Disulfide | 5.5 | ~~1.0 J~~ U | 17 | ~~3.3 J~~ U |
| 3-Chloropropene | 5.5 | Not Detected | 17 | Not Detected |
| Methylene Chloride | 14 | ~~0.18 J~~ U | 47 | ~~0.61 J~~ U |
| Methyl tert-butyl ether | 1.4 | Not Detected | 4.9 | Not Detected |
| trans-1,2-Dichloroethene | 1.4 | Not Detected | 5.4 | Not Detected |
| Hexane | 1.4 | 0.30 J | 4.8 | 1.1 J |
| 1,1-Dichloroethane | 1.4 | Not Detected | 5.5 | Not Detected |
| 2-Butanone (Methyl Ethyl Ketone) | 5.5 | Not Detected | 16 | Not Detected |
| cis-1,2-Dichloroethene | 1.4 | Not Detected | 5.4 | Not Detected |
| Tetrahydrofuran | 1.4 | Not Detected | 4.0 | Not Detected |
| Chloroform | 1.4 | 0.77 J | 6.7 | 3.8 J |
| 1,1,1-Trichloroethane | 1.4 | 0.57 J | 7.4 | 3.1 J |
| Cyclohexane | 1.4 | Not Detected | 4.7 | Not Detected |
| Carbon Tetrachloride | 1.4 | Not Detected | 8.6 | Not Detected |
| 2,2,4-Trimethylpentane | 1.4 | 0.97 J | 6.4 | 4.5 J |
| Benzene | 1.4 | Not Detected | 4.4 | Not Detected |
| 1,2-Dichloroethane | 1.4 | Not Detected | 5.5 | Not Detected |
| Heptane | 1.4 | Not Detected | 5.6 | Not Detected |
| Trichloroethene | 1.4 | Not Detected | 7.3 | Not Detected |
| 1,2-Dichloropropane | 1.4 | Not Detected | 6.3 | Not Detected |
| 1,4-Dioxane | 5.5 | Not Detected | 20 | Not Detected |
| Bromodichloromethane | 1.4 | Not Detected | 9.1 | Not Detected |
| cis-1,3-Dichloropropene | 1.4 | Not Detected | 6.2 | Not Detected |
| 4-Methyl-2-pentanone | 1.4 | Not Detected | 5.6 | Not Detected |
| Toluene | 1.4 | ~~0.13 J~~ U | 5.1 | ~~0.48 J~~ U |
| trans-1,3-Dichloropropene | 1.4 | Not Detected | 6.2 | Not Detected |
| 1,1,2-Trichloroethane | 1.4 | Not Detected | 7.4 | Not Detected |
| Tetrachloroethene | 1.4 | ~~0.46 J~~ U | 9.2 | ~~3.1 J~~ U |
| 2-Hexanone | 5.5 | Not Detected | 22 | Not Detected |

eurofins | Air Toxics

**Client Sample ID: VMP-51-5-020113**

**Lab ID#: 1302083A-07A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p021321** | **Date of Collection: 2/1/13 2:13:00 PM** | |
| **Dil. Factor:** | **2.73** | **Date of Analysis: 2/13/13 10:23 PM** | |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Dibromochloromethane | 1.4 | Not Detected | 12 | Not Detected |
| 1,2-Dibromoethane (EDB) | 1.4 | Not Detected | 10 | Not Detected |
| Chlorobenzene | 1.4 | Not Detected | 6.3 | Not Detected |
| Ethyl Benzene | 1.4 | Not Detected | 5.9 | Not Detected |
| m,p-Xylene | 1.4 | Not Detected | 5.9 | Not Detected |
| o-Xylene | 1.4 | Not Detected | 5.9 | Not Detected |
| Styrene | 1.4 | Not Detected | 5.8 | Not Detected |
| Bromoform | 1.4 | Not Detected | 14 | Not Detected |
| Cumene | 1.4 | Not Detected | 6.7 | Not Detected |
| 1,1,2,2-Tetrachloroethane | 1.4 | Not Detected | 9.4 | Not Detected |
| Propylbenzene | 1.4 | Not Detected | 6.7 | Not Detected |
| 4-Ethyltoluene | 1.4 | Not Detected | 6.7 | Not Detected |
| 1,3,5-Trimethylbenzene | 1.4 | Not Detected | 6.7 | Not Detected |
| 1,2,4-Trimethylbenzene | 1.4 | Not Detected | 6.7 | Not Detected |
| 1,3-Dichlorobenzene | 1.4 | Not Detected | 8.2 | Not Detected |
| 1,4-Dichlorobenzene | 1.4 | Not Detected | 8.2 | Not Detected |
| alpha-Chlorotoluene | 1.4 | Not Detected | 7.1 | Not Detected |
| 1,2-Dichlorobenzene | 1.4 | Not Detected | 8.2 | Not Detected |
| 1,2,4-Trichlorobenzene | 5.5 | Not Detected | 40 | Not Detected |
| Hexachlorobutadiene | 5.5 | Not Detected | 58 | Not Detected |
| Butane | 5.5 | Not Detected | 13 | Not Detected |
| Isopentane | 5.5 | 0.66 J | 16 | 1.9 J |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| Toluene-d8 | 96 | 70-130 |
| 1,2-Dichloroethane-d4 | 83 | 70-130 |
| 4-Bromofluorobenzene | 100 | 70-130 |

eurofins | Air Toxics

**Client Sample ID: VMP-51-10-020113**

**Lab ID#: 1302083A-08A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p021322** | **Date of Collection:** | **2/1/13 3:45:00 PM** |
| **Dil. Factor:** | **2.76** | **Date of Analysis:** | **2/13/13 10:44 PM** |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 1.4 | 0.44 J | 6.8 | 2.2 J |
| Freon 114 | 1.4 | Not Detected | 9.6 | Not Detected |
| Chloromethane | 14 | Not Detected | 28 | Not Detected |
| Vinyl Chloride | 1.4 | Not Detected | 3.5 | Not Detected |
| 1,3-Butadiene | 1.4 | Not Detected | 3.0 | Not Detected |
| Bromomethane | 14 | Not Detected | 54 | Not Detected |
| Chloroethane | 5.5 | Not Detected | 14 | Not Detected |
| Freon 11 | 1.4 | 0.16 J | 7.8 | 0.93 J |
| Ethanol | 5.5 | 1.5 J | 10 | 2.9 J |
| Freon 113 | 1.4 | Not Detected | 10 | Not Detected |
| 1,1-Dichloroethene | 1.4 | Not Detected | 5.5 | Not Detected |
| Acetone | 14 | 2.6 J | 33 | 6.1 J |
| 2-Propanol | 5.5 | 0.97 J | 14 | 2.4 J |
| Carbon Disulfide | 5.5 | ~~0.76 J~~ U | 17 | ~~2.4 J~~ U |
| 3-Chloropropene | 5.5 | Not Detected | 17 | Not Detected |
| Methylene Chloride | 14 | Not Detected | 48 | Not Detected |
| Methyl tert-butyl ether | 1.4 | Not Detected | 5.0 | Not Detected |
| trans-1,2-Dichloroethene | 1.4 | Not Detected | 5.5 | Not Detected |
| Hexane | 1.4 | 0.36 J | 4.9 | 1.3 J |
| 1,1-Dichloroethane | 1.4 | Not Detected | 5.6 | Not Detected |
| 2-Butanone (Methyl Ethyl Ketone) | 5.5 | Not Detected | 16 | Not Detected |
| cis-1,2-Dichloroethene | 1.4 | Not Detected | 5.5 | Not Detected |
| Tetrahydrofuran | 1.4 | Not Detected | 4.1 | Not Detected |
| Chloroform | 1.4 | 2.3 | 6.7 | 11 |
| 1,1,1-Trichloroethane | 1.4 | Not Detected | 7.5 | Not Detected |
| Cyclohexane | 1.4 | Not Detected | 4.8 | Not Detected |
| Carbon Tetrachloride | 1.4 | Not Detected | 8.7 | Not Detected |
| 2,2,4-Trimethylpentane | 1.4 | 0.59 J | 6.4 | 2.7 J |
| Benzene | 1.4 | Not Detected | 4.4 | Not Detected |
| 1,2-Dichloroethane | 1.4 | Not Detected | 5.6 | Not Detected |
| Heptane | 1.4 | Not Detected | 5.6 | Not Detected |
| Trichloroethene | 1.4 | Not Detected | 7.4 | Not Detected |
| 1,2-Dichloropropane | 1.4 | Not Detected | 6.4 | Not Detected |
| 1,4-Dioxane | 5.5 | Not Detected | 20 | Not Detected |
| Bromodichloromethane | 1.4 | Not Detected | 9.2 | Not Detected |
| cis-1,3-Dichloropropene | 1.4 | Not Detected | 6.3 | Not Detected |
| 4-Methyl-2-pentanone | 1.4 | Not Detected | 5.6 | Not Detected |
| Toluene | 1.4 | ~~0.18 J~~ U | 5.2 | ~~0.68 J~~ U |
| trans-1,3-Dichloropropene | 1.4 | Not Detected | 6.3 | Not Detected |
| 1,1,2-Trichloroethane | 1.4 | Not Detected | 7.5 | Not Detected |
| Tetrachloroethene | 1.4 | 0.53 J | 9.4 | 3.6 J |
| 2-Hexanone | 5.5 | Not Detected | 23 | Not Detected |

eurofins | Air Toxics

**Client Sample ID: VMP-51-10-020113**

**Lab ID#: 1302083A-08A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p021322** | **Date of Collection: 2/1/13 3:45:00 PM** | |
| **Dil. Factor:** | **2.76** | **Date of Analysis: 2/13/13 10:44 PM** | |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Dibromochloromethane | 1.4 | Not Detected | 12 | Not Detected |
| 1,2-Dibromoethane (EDB) | 1.4 | Not Detected | 11 | Not Detected |
| Chlorobenzene | 1.4 | Not Detected | 6.4 | Not Detected |
| Ethyl Benzene | 1.4 | Not Detected | 6.0 | Not Detected |
| m,p-Xylene | 1.4 | Not Detected | 6.0 | Not Detected |
| o-Xylene | 1.4 | Not Detected | 6.0 | Not Detected |
| Styrene | 1.4 | Not Detected | 5.9 | Not Detected |
| Bromoform | 1.4 | Not Detected | 14 | Not Detected |
| Cumene | 1.4 | Not Detected | 6.8 | Not Detected |
| 1,1,2,2-Tetrachloroethane | 1.4 | Not Detected | 9.5 | Not Detected |
| Propylbenzene | 1.4 | Not Detected | 6.8 | Not Detected |
| 4-Ethyltoluene | 1.4 | Not Detected | 6.8 | Not Detected |
| 1,3,5-Trimethylbenzene | 1.4 | Not Detected | 6.8 | Not Detected |
| 1,2,4-Trimethylbenzene | 1.4 | Not Detected | 6.8 | Not Detected |
| 1,3-Dichlorobenzene | 1.4 | Not Detected | 8.3 | Not Detected |
| 1,4-Dichlorobenzene | 1.4 | Not Detected | 8.3 | Not Detected |
| alpha-Chlorotoluene | 1.4 | Not Detected | 7.1 | Not Detected |
| 1,2-Dichlorobenzene | 1.4 | Not Detected | 8.3 | Not Detected |
| 1,2,4-Trichlorobenzene | 5.5 | Not Detected | 41 | Not Detected |
| Hexachlorobutadiene | 5.5 | Not Detected | 59 | Not Detected |
| Butane | 5.5 | Not Detected | 13 | Not Detected |
| Isopentane | 5.5 | Not Detected | 16 | Not Detected |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| Toluene-d8 | 97 | 70-130 |
| 1,2-Dichloroethane-d4 | 84 | 70-130 |
| 4-Bromofluorobenzene | 100 | 70-130 |

eurofins | Air Toxics

**Client Sample ID: VMP-52-5-020413**

**Lab ID#: 1302083A-10A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | p021324 | **Date of Collection:** | 2/4/13 9:47:00 AM |
| **Dil. Factor:** | 2.52 | **Date of Analysis:** | 2/14/13 06:55 AM |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 1.3 | 0.49 J | 6.2 | 2.4 J |
| Freon 114 | 1.3 | Not Detected | 8.8 | Not Detected |
| Chloromethane | 13 | Not Detected | 26 | Not Detected |
| Vinyl Chloride | 1.3 | Not Detected | 3.2 | Not Detected |
| 1,3-Butadiene | 1.3 | Not Detected | 2.8 | Not Detected |
| Bromomethane | 13 | Not Detected | 49 | Not Detected |
| Chloroethane | 5.0 | Not Detected | 13 | Not Detected |
| Freon 11 | 1.3 | 0.24 J | 7.1 | 1.4 J |
| Ethanol | 5.0 | 2.1 J | 9.5 | 3.9 J |
| Freon 113 | 1.3 | Not Detected | 9.6 | Not Detected |
| 1,1-Dichloroethene | 1.3 | Not Detected | 5.0 | Not Detected |
| Acetone | 13 | 4.6 J | 30 | 11 J |
| 2-Propanol | 5.0 | 3.2 J | 12 | 7.9 J |
| Carbon Disulfide | 5.0 | ~~1.2 J~~ U | 16 | ~~3.7 J~~ U |
| 3-Chloropropene | 5.0 | Not Detected | 16 | Not Detected |
| Methylene Chloride | 13 | ~~0.16 J~~ U | 44 | ~~0.54 J~~ U |
| Methyl tert-butyl ether | 1.3 | Not Detected | 4.5 | Not Detected |
| trans-1,2-Dichloroethene | 1.3 | Not Detected | 5.0 | Not Detected |
| Hexane | 1.3 | 0.41 J | 4.4 | 1.4 J |
| 1,1-Dichloroethane | 1.3 | Not Detected | 5.1 | Not Detected |
| 2-Butanone (Methyl Ethyl Ketone) | 5.0 | 0.94 J | 15 | 2.8 J |
| cis-1,2-Dichloroethene | 1.3 | Not Detected | 5.0 | Not Detected |
| Tetrahydrofuran | 1.3 | Not Detected | 3.7 | Not Detected |
| Chloroform | 1.3 | Not Detected | 6.2 | Not Detected |
| 1,1,1-Trichloroethane | 1.3 | 3.6 | 6.9 | 20 |
| Cyclohexane | 1.3 | Not Detected | 4.3 | Not Detected |
| Carbon Tetrachloride | 1.3 | Not Detected | 7.9 | Not Detected |
| 2,2,4-Trimethylpentane | 1.3 | 0.53 J | 5.9 | 2.5 J |
| Benzene | 1.3 | 23 | 4.0 | 73 |
| 1,2-Dichloroethane | 1.3 | Not Detected | 5.1 | Not Detected |
| Heptane | 1.3 | Not Detected | 5.2 | Not Detected |
| Trichloroethene | 1.3 | Not Detected | 6.8 | Not Detected |
| 1,2-Dichloropropane | 1.3 | Not Detected | 5.8 | Not Detected |
| 1,4-Dioxane | 5.0 | Not Detected | 18 | Not Detected |
| Bromodichloromethane | 1.3 | Not Detected | 8.4 | Not Detected |
| cis-1,3-Dichloropropene | 1.3 | Not Detected | 5.7 | Not Detected |
| 4-Methyl-2-pentanone | 1.3 | 2.4 | 5.2 | 9.9 |
| Toluene | 1.3 | ~~0.13 J~~ U | 4.7 | ~~0.48 J~~ U |
| trans-1,3-Dichloropropene | 1.3 | Not Detected | 5.7 | Not Detected |
| 1,1,2-Trichloroethane | 1.3 | Not Detected | 6.9 | Not Detected |
| Tetrachloroethene | 1.3 | ~~0.28 J~~ U | 8.5 | 1.9 J U |
| 2-Hexanone | 5.0 | Not Detected | 21 | Not Detected |

eurofins | Air Toxics

**Client Sample ID: VMP-52-5-020413**

**Lab ID#: 1302083A-10A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p021324** | **Date of Collection:** | **2/4/13 9:47:00 AM** |
| **Dil. Factor:** | **2.52** | **Date of Analysis:** | **2/14/13 06:55 AM** |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Dibromochloromethane | 1.3 | Not Detected | 11 | Not Detected |
| 1,2-Dibromoethane (EDB) | 1.3 | Not Detected | 9.7 | Not Detected |
| Chlorobenzene | 1.3 | Not Detected | 5.8 | Not Detected |
| Ethyl Benzene | 1.3 | Not Detected | 5.5 | Not Detected |
| m,p-Xylene | 1.3 | Not Detected | 5.5 | Not Detected |
| o-Xylene | 1.3 | Not Detected | 5.5 | Not Detected |
| Styrene | 1.3 | Not Detected | 5.4 | Not Detected |
| Bromoform | 1.3 | Not Detected | 13 | Not Detected |
| Cumene | 1.3 | Not Detected | 6.2 | Not Detected |
| 1,1,2,2-Tetrachloroethane | 1.3 | Not Detected | 8.6 | Not Detected |
| Propylbenzene | 1.3 | Not Detected | 6.2 | Not Detected |
| 4-Ethyltoluene | 1.3 | ~~0.15 J~~ | 6.2 | ~~0.74 J~~ |
| 1,3,5-Trimethylbenzene | 1.3 | Not Detected | 6.2 | Not Detected |
| 1,2,4-Trimethylbenzene | 1.3 | ~~0.27 J~~ | 6.2 | ~~1.3 J~~ |
| 1,3-Dichlorobenzene | 1.3 | ~~0.18 J~~ | 7.6 | ~~1.1 J~~ |
| 1,4-Dichlorobenzene | 1.3 | ~~0.24 J~~ | 7.6 | ~~1.4 J~~ |
| alpha-Chlorotoluene | 1.3 | Not Detected | 6.5 | Not Detected |
| 1,2-Dichlorobenzene | 1.3 | Not Detected | 7.6 | Not Detected |
| 1,2,4-Trichlorobenzene | 5.0 | ~~0.70 J~~ | 37 | ~~5.2 J~~ |
| Hexachlorobutadiene | 5.0 | Not Detected | 54 | Not Detected |
| Butane | 5.0 | 2.1 J | 12 | 5.0 J |
| Isopentane | 5.0 | 1.7 J | 15 | 5.0 J |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| Toluene-d8 | 98 | 70-130 |
| 1,2-Dichloroethane-d4 | 87 | 70-130 |
| 4-Bromofluorobenzene | 102 | 70-130 |

eurofins | Air Toxics

**Client Sample ID: VMP-52-10-020413**

**Lab ID#: 1302083A-11A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p021325** | **Date of Collection:** | **2/4/13 10:36:00 AM** |
| **Dil. Factor:** | **2.40** | **Date of Analysis:** | **2/14/13 07:38 AM** |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 1.2 | 0.54 J | 5.9 | 2.6 J |
| Freon 114 | 1.2 | Not Detected | 8.4 | Not Detected |
| Chloromethane | 12 | Not Detected | 25 | Not Detected |
| Vinyl Chloride | 1.2 | Not Detected | 3.1 | Not Detected |
| 1,3-Butadiene | 1.2 | Not Detected | 2.6 | Not Detected |
| Bromomethane | 12 | Not Detected | 47 | Not Detected |
| Chloroethane | 4.8 | Not Detected | 13 | Not Detected |
| Freon 11 | 1.2 | 0.20 J | 6.7 | 1.1 J |
| Ethanol | 4.8 | 1.7 J | 9.0 | 3.2 J |
| Freon 113 | 1.2 | Not Detected | 9.2 | Not Detected |
| 1,1-Dichloroethene | 1.2 | Not Detected | 4.8 | Not Detected |
| Acetone | 12 | 2.5 J | 28 | 6.0 J |
| 2-Propanol | 4.8 | 1.0 J | 12 | 2.6 J |
| Carbon Disulfide | 4.8 | 7.5 | 15 | 23 |
| 3-Chloropropene | 4.8 | Not Detected | 15 | Not Detected |
| Methylene Chloride | 12 | Not Detected | 42 | Not Detected |
| Methyl tert-butyl ether | 1.2 | Not Detected | 4.3 | Not Detected |
| trans-1,2-Dichloroethene | 1.2 | Not Detected | 4.8 | Not Detected |
| Hexane | 1.2 | 0.30 J | 4.2 | 1.0 J |
| 1,1-Dichloroethane | 1.2 | Not Detected | 4.8 | Not Detected |
| 2-Butanone (Methyl Ethyl Ketone) | 4.8 | Not Detected | 14 | Not Detected |
| cis-1,2-Dichloroethene | 1.2 | Not Detected | 4.8 | Not Detected |
| Tetrahydrofuran | 1.2 | Not Detected | 3.5 | Not Detected |
| Chloroform | 1.2 | 0.40 J | 5.8 | 2.0 J |
| 1,1,1-Trichloroethane | 1.2 | 4.0 | 6.5 | 22 |
| Cyclohexane | 1.2 | Not Detected | 4.1 | Not Detected |
| Carbon Tetrachloride | 1.2 | Not Detected | 7.6 | Not Detected |
| 2,2,4-Trimethylpentane | 1.2 | 0.68 J | 5.6 | 3.2 J |
| Benzene | 1.2 | Not Detected | 3.8 | Not Detected |
| 1,2-Dichloroethane | 1.2 | Not Detected | 4.8 | Not Detected |
| Heptane | 1.2 | Not Detected | 4.9 | Not Detected |
| Trichloroethene | 1.2 | Not Detected | 6.4 | Not Detected |
| 1,2-Dichloropropane | 1.2 | Not Detected | 5.5 | Not Detected |
| 1,4-Dioxane | 4.8 | Not Detected | 17 | Not Detected |
| Bromodichloromethane | 1.2 | Not Detected | 8.0 | Not Detected |
| cis-1,3-Dichloropropene | 1.2 | Not Detected | 5.4 | Not Detected |
| 4-Methyl-2-pentanone | 1.2 | Not Detected | 4.9 | Not Detected |
| Toluene | 1.2 | ~~0.14 J~~ | 4.5 | ~~0.53 J~~ |
| trans-1,3-Dichloropropene | 1.2 | Not Detected | 5.4 | Not Detected |
| 1,1,2-Trichloroethane | 1.2 | Not Detected | 6.5 | Not Detected |
| Tetrachloroethene | 1.2 | ~~0.43 J~~ | 8.1 | ~~2.9 J~~ |
| 2-Hexanone | 4.8 | Not Detected | 20 | Not Detected |

eurofins | Air Toxics

**Client Sample ID: VMP-52-10-020413**

**Lab ID#: 1302083A-11A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p021325** | **Date of Collection:** | **2/4/13 10:36:00 AM** |
| **Dil. Factor:** | **2.40** | **Date of Analysis:** | **2/14/13 07:38 AM** |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Dibromochloromethane | 1.2 | Not Detected | 10 | Not Detected |
| 1,2-Dibromoethane (EDB) | 1.2 | Not Detected | 9.2 | Not Detected |
| Chlorobenzene | 1.2 | Not Detected | 5.5 | Not Detected |
| Ethyl Benzene | 1.2 | Not Detected | 5.2 | Not Detected |
| m,p-Xylene | 1.2 | Not Detected | 5.2 | Not Detected |
| o-Xylene | 1.2 | Not Detected | 5.2 | Not Detected |
| Styrene | 1.2 | Not Detected | 5.1 | Not Detected |
| Bromoform | 1.2 | Not Detected | 12 | Not Detected |
| Cumene | 1.2 | Not Detected | 5.9 | Not Detected |
| 1,1,2,2-Tetrachloroethane | 1.2 | Not Detected | 8.2 | Not Detected |
| Propylbenzene | 1.2 | Not Detected | 5.9 | Not Detected |
| 4-Ethyltoluene | 1.2 | Not Detected | 5.9 | Not Detected |
| 1,3,5-Trimethylbenzene | 1.2 | Not Detected | 5.9 | Not Detected |
| 1,2,4-Trimethylbenzene | 1.2 | Not Detected | 5.9 | Not Detected |
| 1,3-Dichlorobenzene | 1.2 | Not Detected | 7.2 | Not Detected |
| 1,4-Dichlorobenzene | 1.2 | Not Detected | 7.2 | Not Detected |
| alpha-Chlorotoluene | 1.2 | Not Detected | 6.2 | Not Detected |
| 1,2-Dichlorobenzene | 1.2 | Not Detected | 7.2 | Not Detected |
| 1,2,4-Trichlorobenzene | 4.8 | ~~0.35 J~~ | 36 | ~~2.6 J~~ |
| Hexachlorobutadiene | 4.8 | Not Detected | 51 | Not Detected |
| Butane | 4.8 | 12 | 11 | 27 |
| Isopentane | 4.8 | 1.6 J | 14 | 4.7 J |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| Toluene-d8 | 97 | 70-130 |
| 1,2-Dichloroethane-d4 | 87 | 70-130 |
| 4-Bromofluorobenzene | 99 | 70-130 |

eurofins | Air Toxics

**Client Sample ID: VMP-52-20-020413**

**Lab ID#: 1302083A-12A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p021406** | **Date of Collection:** | **2/4/13 11:22:00 AM** |
| **Dil. Factor:** | **2.68** | **Date of Analysis:** | **2/14/13 12:16 PM** |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 1.3 | 0.58 J | 6.6 | 2.8 J |
| Freon 114 | 1.3 | Not Detected | 9.4 | Not Detected |
| Chloromethane | 13 | Not Detected | 28 | Not Detected |
| Vinyl Chloride | 1.3 | Not Detected | 3.4 | Not Detected |
| 1,3-Butadiene | 1.3 | Not Detected | 3.0 | Not Detected |
| Bromomethane | 13 | 0.66 J | 52 | 2.5 J |
| Chloroethane | 5.4 | Not Detected | 14 | Not Detected |
| Freon 11 | 1.3 | ~~0.34 J~~ U | 7.5 | ~~1.9 J~~ U |
| Ethanol | 5.4 | 1.4 J | 10 | 2.7 J |
| Freon 113 | 1.3 | Not Detected | 10 | Not Detected |
| 1,1-Dichloroethene | 1.3 | Not Detected | 5.3 | Not Detected |
| Acetone | 13 | 5.6 J | 32 | 13 J |
| 2-Propanol | 5.4 | 2.4 J | 13 | 6.0 J |
| Carbon Disulfide | 5.4 | 3.0 J | 17 | 9.2 J |
| 3-Chloropropene | 5.4 | Not Detected | 17 | Not Detected |
| Methylene Chloride | 13 | ~~0.34 J~~ U | 46 | ~~1.2 J~~ U |
| Methyl tert-butyl ether | 1.3 | Not Detected | 4.8 | Not Detected |
| trans-1,2-Dichloroethene | 1.3 | Not Detected | 5.3 | Not Detected |
| Hexane | 1.3 | 2.9 | 4.7 | 10 |
| 1,1-Dichloroethane | 1.3 | Not Detected | 5.4 | Not Detected |
| 2-Butanone (Methyl Ethyl Ketone) | 5.4 | 1.6 J | 16 | 4.7 J |
| cis-1,2-Dichloroethene | 1.3 | Not Detected | 5.3 | Not Detected |
| Tetrahydrofuran | 1.3 | Not Detected | 4.0 | Not Detected |
| Chloroform | 1.3 | 0.51 J | 6.5 | 2.5 J |
| 1,1,1-Trichloroethane | 1.3 | Not Detected | 7.3 | Not Detected |
| Cyclohexane | 1.3 | 6.7 | 4.6 | 23 |
| Carbon Tetrachloride | 1.3 | Not Detected | 8.4 | Not Detected |
| 2,2,4-Trimethylpentane | 1.3 | 13 | 6.2 | 59 |
| Benzene | 1.3 | 24 J | 4.3 | 76 J |
| 1,2-Dichloroethane | 1.3 | Not Detected | 5.4 | Not Detected |
| Heptane | 1.3 | 1.0 J | 5.5 | 4.3 J |
| Trichloroethene | 1.3 | Not Detected | 7.2 | Not Detected |
| 1,2-Dichloropropane | 1.3 | Not Detected | 6.2 | Not Detected |
| 1,4-Dioxane | 5.4 | Not Detected | 19 | Not Detected |
| Bromodichloromethane | 1.3 | Not Detected | 9.0 | Not Detected |
| cis-1,3-Dichloropropene | 1.3 | Not Detected | 6.1 | Not Detected |
| 4-Methyl-2-pentanone | 1.3 | Not Detected | 5.5 | Not Detected |
| Toluene | 1.3 | 0.69 J | 5.0 | 2.6 J |
| trans-1,3-Dichloropropene | 1.3 | Not Detected | 6.1 | Not Detected |
| 1,1,2-Trichloroethane | 1.3 | Not Detected | 7.3 | Not Detected |
| Tetrachloroethene | 1.3 | ~~0.47 J~~ U | 9.1 | ~~3.2 J~~ U |
| 2-Hexanone | 5.4 | Not Detected | 22 | Not Detected |

eurofins | Air Toxics

**Client Sample ID: VMP-52-20-020413**

**Lab ID#: 1302083A-12A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p021406** | **Date of Collection:** | **2/4/13 11:22:00 AM** |
| **Dil. Factor:** | **2.68** | **Date of Analysis:** | **2/14/13 12:16 PM** |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Dibromochloromethane | 1.3 | Not Detected | 11 | Not Detected |
| 1,2-Dibromoethane (EDB) | 1.3 | Not Detected | 10 | Not Detected |
| Chlorobenzene | 1.3 | Not Detected | 6.2 | Not Detected |
| Ethyl Benzene | 1.3 | Not Detected | 5.8 | Not Detected |
| m,p-Xylene | 1.3 | 0.58 J | 5.8 | 2.5 J |
| o-Xylene | 1.3 | 0.34 J | 5.8 | 1.5 J |
| Styrene | 1.3 | Not Detected | 5.7 | Not Detected |
| Bromoform | 1.3 | Not Detected | 14 | Not Detected |
| Cumene | 1.3 | Not Detected | 6.6 | Not Detected |
| 1,1,2,2-Tetrachloroethane | 1.3 | Not Detected | 9.2 | Not Detected |
| Propylbenzene | 1.3 | 0.23 J | 6.6 | 1.1 J |
| 4-Ethyltoluene | 1.3 | 0.30 J | 6.6 | 1.5 J |
| 1,3,5-Trimethylbenzene | 1.3 | 0.54 J | 6.6 | 2.6 J |
| 1,2,4-Trimethylbenzene | 1.3 | 0.71 J | 6.6 | 3.5 J |
| 1,3-Dichlorobenzene | 1.3 | 0.36 J | 8.0 | 2.2 J |
| 1,4-Dichlorobenzene | 1.3 | 0.35 J | 8.0 | 2.1 J |
| alpha-Chlorotoluene | 1.3 | Not Detected | 6.9 | Not Detected |
| 1,2-Dichlorobenzene | 1.3 | 0.27 J | 8.0 | 1.6 J |
| 1,2,4-Trichlorobenzene | 5.4 | 1.3 J | 40 | 9.5 J |
| Hexachlorobutadiene | 5.4 | 0.50 J | 57 | 5.3 J |
| Butane | 5.4 | 35 | 13 | 82 |
| Isopentane | 5.4 | 18 | 16 | 53 |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| Toluene-d8 | 98 | 70-130 |
| 1,2-Dichloroethane-d4 | 86 | 70-130 |
| 4-Bromofluorobenzene | 97 | 70-130 |

eurofins | Air Toxics

**Client Sample ID: VMP-52-20-020413-DUP**

**Lab ID#: 1302083A-13A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p021407** | **Date of Collection:** | **2/4/13 11:22:00 AM** |
| **Dil. Factor:** | **2.57** | **Date of Analysis:** | **2/14/13 12:56 PM** |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 1.3 | 0.45 J | 6.4 | 2.2 J |
| Freon 114 | 1.3 | Not Detected | 9.0 | Not Detected |
| Chloromethane | 13 | Not Detected | 26 | Not Detected |
| Vinyl Chloride | 1.3 | Not Detected | 3.3 | Not Detected |
| 1,3-Butadiene | 1.3 | Not Detected | 2.8 | Not Detected |
| Bromomethane | 13 | Not Detected | 50 | Not Detected |
| Chloroethane | 5.1 | Not Detected | 14 | Not Detected |
| Freon 11 | 1.3 | ~~0.33 J~~ U | 7.2 | ~~1.8 J~~ U |
| Ethanol | 5.1 | 1.8 J | 9.7 | 3.4 J |
| Freon 113 | 1.3 | Not Detected | 9.8 | Not Detected |
| 1,1-Dichloroethene | 1.3 | Not Detected | 5.1 | Not Detected |
| Acetone | 13 | 2.4 J | 30 | 5.8 J |
| 2-Propanol | 5.1 | 0.58 J | 13 | 1.4 J |
| Carbon Disulfide | 5.1 | 2.8 J | 16 | 8.8 J |
| 3-Chloropropene | 5.1 | Not Detected | 16 | Not Detected |
| Methylene Chloride | 13 | ~~0.25 J~~ U | 45 | ~~0.86 J~~ U |
| Methyl tert-butyl ether | 1.3 | Not Detected | 4.6 | Not Detected |
| trans-1,2-Dichloroethene | 1.3 | Not Detected | 5.1 | Not Detected |
| Hexane | 1.3 | 1.5 | 4.5 | 5.2 |
| 1,1-Dichloroethane | 1.3 | Not Detected | 5.2 | Not Detected |
| 2-Butanone (Methyl Ethyl Ketone) | 5.1 | Not Detected | 15 | Not Detected |
| cis-1,2-Dichloroethene | 1.3 | Not Detected | 5.1 | Not Detected |
| Tetrahydrofuran | 1.3 | Not Detected | 3.8 | Not Detected |
| Chloroform | 1.3 | 0.47 J | 6.3 | 2.3 J |
| 1,1,1-Trichloroethane | 1.3 | Not Detected | 7.0 | Not Detected |
| Cyclohexane | 1.3 | 5.1 | 4.4 | 18 |
| Carbon Tetrachloride | 1.3 | Not Detected | 8.1 | Not Detected |
| 2,2,4-Trimethylpentane | 1.3 | 11 | 6.0 | 52 |
| Benzene | 1.3 | 3.6 J | 4.1 | 12 J |
| 1,2-Dichloroethane | 1.3 | Not Detected | 5.2 | Not Detected |
| Heptane | 1.3 | Not Detected | 5.3 | Not Detected |
| Trichloroethene | 1.3 | Not Detected | 6.9 | Not Detected |
| 1,2-Dichloropropane | 1.3 | Not Detected | 5.9 | Not Detected |
| 1,4-Dioxane | 5.1 | Not Detected | 18 | Not Detected |
| Bromodichloromethane | 1.3 | Not Detected | 8.6 | Not Detected |
| cis-1,3-Dichloropropene | 1.3 | Not Detected | 5.8 | Not Detected |
| 4-Methyl-2-pentanone | 1.3 | Not Detected | 5.3 | Not Detected |
| Toluene | 1.3 | 0.44 J | 4.8 | 1.7 J |
| trans-1,3-Dichloropropene | 1.3 | Not Detected | 5.8 | Not Detected |
| 1,1,2-Trichloroethane | 1.3 | Not Detected | 7.0 | Not Detected |
| Tetrachloroethene | 1.3 | ~~0.35 J~~ U | 8.7 | ~~2.4 J~~ U |
| 2-Hexanone | 5.1 | Not Detected | 21 | Not Detected |

eurofins | Air Toxics

**Client Sample ID: VMP-52-20-020413-DUP**

**Lab ID#: 1302083A-13A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p021407** | **Date of Collection: 2/4/13 11:22:00 AM** | |
| **Dil. Factor:** | **2.57** | **Date of Analysis: 2/14/13 12:56 PM** | |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Dibromochloromethane | 1.3 | Not Detected | 11 | Not Detected |
| 1,2-Dibromoethane (EDB) | 1.3 | Not Detected | 9.9 | Not Detected |
| Chlorobenzene | 1.3 | Not Detected | 5.9 | Not Detected |
| Ethyl Benzene | 1.3 | Not Detected | 5.6 | Not Detected |
| m,p-Xylene | 1.3 | Not Detected | 5.6 | Not Detected |
| o-Xylene | 1.3 | Not Detected | 5.6 | Not Detected |
| Styrene | 1.3 | Not Detected | 5.5 | Not Detected |
| Bromoform | 1.3 | Not Detected | 13 | Not Detected |
| Cumene | 1.3 | Not Detected | 6.3 | Not Detected |
| 1,1,2,2-Tetrachloroethane | 1.3 | Not Detected | 8.8 | Not Detected |
| Propylbenzene | 1.3 | Not Detected | 6.3 | Not Detected |
| 4-Ethyltoluene | 1.3 | ~~0.089 J~~ | 6.3 | ~~0.44 J~~ |
| 1,3,5-Trimethylbenzene | 1.3 | Not Detected | 6.3 | Not Detected |
| 1,2,4-Trimethylbenzene | 1.3 | Not Detected | 6.3 | Not Detected |
| 1,3-Dichlorobenzene | 1.3 | ~~0.17 J~~ | 7.7 | ~~1.0 J~~ |
| 1,4-Dichlorobenzene | 1.3 | ~~0.24 J~~ | 7.7 | ~~1.4 J~~ |
| alpha-Chlorotoluene | 1.3 | Not Detected | 6.6 | Not Detected |
| 1,2-Dichlorobenzene | 1.3 | Not Detected | 7.7 | Not Detected |
| 1,2,4-Trichlorobenzene | 5.1 | ~~0.77 J~~ | 38 | ~~5.7 J~~ |
| Hexachlorobutadiene | 5.1 | Not Detected | 55 | Not Detected |
| Butane | 5.1 | 29 | 12 | 69 |
| Isopentane | 5.1 | 10 | 15 | 30 |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| Toluene-d8 | 98 | 70-130 |
| 1,2-Dichloroethane-d4 | 86 | 70-130 |
| 4-Bromofluorobenzene | 97 | 70-130 |

eurofins | Air Toxics

**Client Sample ID: VMP-52-30-020413**

**Lab ID#: 1302083A-14A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p021408** | **Date of Collection:** | **2/4/13 12:04:00 PM** |
| **Dil. Factor:** | **2.81** | **Date of Analysis:** | **2/14/13 01:42 PM** |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 1.4 | 0.49 J | 6.9 | 2.4 J |
| Freon 114 | 1.4 | Not Detected | 9.8 | Not Detected |
| Chloromethane | 14 | Not Detected | 29 | Not Detected |
| Vinyl Chloride | 1.4 | Not Detected | 3.6 | Not Detected |
| 1,3-Butadiene | 1.4 | Not Detected | 3.1 | Not Detected |
| Bromomethane | 14 | Not Detected | 54 | Not Detected |
| Chloroethane | 5.6 | Not Detected | 15 | Not Detected |
| Freon 11 | 1.4 | 0.38 J | 7.9 | 2.1 J |
| Ethanol | 5.6 | Not Detected | 10 | Not Detected |
| Freon 113 | 1.4 | Not Detected | 11 | Not Detected |
| 1,1-Dichloroethene | 1.4 | Not Detected | 5.6 | Not Detected |
| Acetone | 14 | 37 | 33 | 88 |
| 2-Propanol | 5.6 | Not Detected | 14 | Not Detected |
| Carbon Disulfide | 5.6 | ~~2.3 J~~ U | 18 | ~~7.1 J~~ U |
| 3-Chloropropene | 5.6 | Not Detected | 18 | Not Detected |
| Methylene Chloride | 14 | Not Detected | 49 | Not Detected |
| Methyl tert-butyl ether | 1.4 | Not Detected | 5.1 | Not Detected |
| trans-1,2-Dichloroethene | 1.4 | Not Detected | 5.6 | Not Detected |
| Hexane | 1.4 | 3.1 | 5.0 | 11 |
| 1,1-Dichloroethane | 1.4 | Not Detected | 5.7 | Not Detected |
| 2-Butanone (Methyl Ethyl Ketone) | 5.6 | Not Detected | 16 | Not Detected |
| cis-1,2-Dichloroethene | 1.4 | Not Detected | 5.6 | Not Detected |
| Tetrahydrofuran | 1.4 | Not Detected | 4.1 | Not Detected |
| Chloroform | 1.4 | Not Detected | 6.9 | Not Detected |
| 1,1,1-Trichloroethane | 1.4 | Not Detected | 7.7 | Not Detected |
| Cyclohexane | 1.4 | 6.7 | 4.8 | 23 |
| Carbon Tetrachloride | 1.4 | Not Detected | 8.8 | Not Detected |
| 2,2,4-Trimethylpentane | 1.4 | 120 | 6.6 | 580 |
| Benzene | 1.4 | 0.52 J | 4.5 | 1.7 J |
| 1,2-Dichloroethane | 1.4 | Not Detected | 5.7 | Not Detected |
| Heptane | 1.4 | 0.32 J | 5.8 | 1.3 J |
| Trichloroethene | 1.4 | Not Detected | 7.6 | Not Detected |
| 1,2-Dichloropropane | 1.4 | Not Detected | 6.5 | Not Detected |
| 1,4-Dioxane | 5.6 | Not Detected | 20 | Not Detected |
| Bromodichloromethane | 1.4 | Not Detected | 9.4 | Not Detected |
| cis-1,3-Dichloropropene | 1.4 | Not Detected | 6.4 | Not Detected |
| 4-Methyl-2-pentanone | 1.4 | Not Detected | 5.8 | Not Detected |
| Toluene | 1.4 | ~~0.25 J~~ U | 5.3 | ~~0.96 J~~ U |
| trans-1,3-Dichloropropene | 1.4 | Not Detected | 6.4 | Not Detected |
| 1,1,2-Trichloroethane | 1.4 | Not Detected | 7.7 | Not Detected |
| Tetrachloroethene | 1.4 | ~~0.19 J~~ U | 9.5 | ~~1.3 J~~ U |
| 2-Hexanone | 5.6 | Not Detected | 23 | Not Detected |

eurofins | Air Toxics

**Client Sample ID: VMP-52-30-020413**

**Lab ID#: 1302083A-14A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p021408** | **Date of Collection:** | **2/4/13 12:04:00 PM** |
| **Dil. Factor:** | **2.81** | **Date of Analysis:** | **2/14/13 01:42 PM** |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Dibromochloromethane | 1.4 | Not Detected | 12 | Not Detected |
| 1,2-Dibromoethane (EDB) | 1.4 | Not Detected | 11 | Not Detected |
| Chlorobenzene | 1.4 | Not Detected | 6.5 | Not Detected |
| Ethyl Benzene | 1.4 | Not Detected | 6.1 | Not Detected |
| m,p-Xylene | 1.4 | Not Detected | 6.1 | Not Detected |
| o-Xylene | 1.4 | Not Detected | 6.1 | Not Detected |
| Styrene | 1.4 | Not Detected | 6.0 | Not Detected |
| Bromoform | 1.4 | Not Detected | 14 | Not Detected |
| Cumene | 1.4 | Not Detected | 6.9 | Not Detected |
| 1,1,2,2-Tetrachloroethane | 1.4 | Not Detected | 9.6 | Not Detected |
| Propylbenzene | 1.4 | Not Detected | 6.9 | Not Detected |
| 4-Ethyltoluene | 1.4 | Not Detected | 6.9 | Not Detected |
| 1,3,5-Trimethylbenzene | 1.4 | Not Detected | 6.9 | Not Detected |
| 1,2,4-Trimethylbenzene | 1.4 | Not Detected | 6.9 | Not Detected |
| 1,3-Dichlorobenzene | 1.4 | Not Detected | 8.4 | Not Detected |
| 1,4-Dichlorobenzene | 1.4 | Not Detected | 8.4 | Not Detected |
| alpha-Chlorotoluene | 1.4 | Not Detected | 7.3 | Not Detected |
| 1,2-Dichlorobenzene | 1.4 | Not Detected | 8.4 | Not Detected |
| 1,2,4-Trichlorobenzene | 5.6 | ~~0.58 J~~ U | 42 | ~~4.3 J~~ U |
| Hexachlorobutadiene | 5.6 | Not Detected | 60 | Not Detected |
| Butane | 5.6 | 34 | 13 | 82 |
| Isopentane | 5.6 | 14 | 16 | 43 |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| Toluene-d8 | 98 | 70-130 |
| 1,2-Dichloroethane-d4 | 88 | 70-130 |
| 4-Bromofluorobenzene | 95 | 70-130 |

eurofins | Air Toxics

**Client Sample ID: VMP-51-30-020413**

**Lab ID#: 1302083A-15A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p021409** | **Date of Collection:** | **2/4/13 2:15:00 PM** |
| **Dil. Factor:** | **2.89** | **Date of Analysis:** | **2/14/13 02:15 PM** |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 1.4 | 0.40 J | 7.1 | 2.0 J |
| Freon 114 | 1.4 | Not Detected | 10 | Not Detected |
| Chloromethane | 14 | Not Detected | 30 | Not Detected |
| Vinyl Chloride | 1.4 | Not Detected | 3.7 | Not Detected |
| 1,3-Butadiene | 1.4 | Not Detected | 3.2 | Not Detected |
| Bromomethane | 14 | Not Detected | 56 | Not Detected |
| Chloroethane | 5.8 | Not Detected | 15 | Not Detected |
| Freon 11 | 1.4 | ~~0.25 J~~ U | 8.1 | ~~1.4 J~~ U |
| Ethanol | 5.8 | 1.2 J | 11 | 2.3 J |
| Freon 113 | 1.4 | Not Detected | 11 | Not Detected |
| 1,1-Dichloroethene | 1.4 | Not Detected | 5.7 | Not Detected |
| Acetone | 14 | 2.6 J | 34 | 6.2 J |
| 2-Propanol | 5.8 | 0.64 J | 14 | 1.6 J |
| Carbon Disulfide | 5.8 | ~~1.3 J~~ U | 18 | ~~4.1 J~~ U |
| 3-Chloropropene | 5.8 | Not Detected | 18 | Not Detected |
| Methylene Chloride | 14 | Not Detected | 50 | Not Detected |
| Methyl tert-butyl ether | 1.4 | Not Detected | 5.2 | Not Detected |
| trans-1,2-Dichloroethene | 1.4 | Not Detected | 5.7 | Not Detected |
| Hexane | 1.4 | 1.5 | 5.1 | 5.2 |
| 1,1-Dichloroethane | 1.4 | Not Detected | 5.8 | Not Detected |
| 2-Butanone (Methyl Ethyl Ketone) | 5.8 | Not Detected | 17 | Not Detected |
| cis-1,2-Dichloroethene | 1.4 | Not Detected | 5.7 | Not Detected |
| Tetrahydrofuran | 1.4 | Not Detected | 4.3 | Not Detected |
| Chloroform | 1.4 | 3.2 | 7.0 | 16 |
| 1,1,1-Trichloroethane | 1.4 | Not Detected | 7.9 | Not Detected |
| Cyclohexane | 1.4 | 1.4 | 5.0 | 4.9 |
| Carbon Tetrachloride | 1.4 | Not Detected | 9.1 | Not Detected |
| 2,2,4-Trimethylpentane | 1.4 | 0.88 J | 6.8 | 4.1 J |
| Benzene | 1.4 | 18 | 4.6 | 56 |
| 1,2-Dichloroethane | 1.4 | Not Detected | 5.8 | Not Detected |
| Heptane | 1.4 | 0.62 J | 5.9 | 2.6 J |
| Trichloroethene | 1.4 | Not Detected | 7.8 | Not Detected |
| 1,2-Dichloropropane | 1.4 | Not Detected | 6.7 | Not Detected |
| 1,4-Dioxane | 5.8 | Not Detected | 21 | Not Detected |
| Bromodichloromethane | 1.4 | Not Detected | 9.7 | Not Detected |
| cis-1,3-Dichloropropene | 1.4 | Not Detected | 6.6 | Not Detected |
| 4-Methyl-2-pentanone | 1.4 | Not Detected | 5.9 | Not Detected |
| Toluene | 1.4 | ~~0.22 J~~ U | 5.4 | ~~0.82 J~~ U |
| trans-1,3-Dichloropropene | 1.4 | Not Detected | 6.6 | Not Detected |
| 1,1,2-Trichloroethane | 1.4 | Not Detected | 7.9 | Not Detected |
| Tetrachloroethene | 1.4 | ~~0.28 J~~ U | 9.8 | ~~1.9 J~~ U |
| 2-Hexanone | 5.8 | Not Detected | 24 | Not Detected |

eurofins | Air Toxics

**Client Sample ID: VMP-51-30-020413**

**Lab ID#: 1302083A-15A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p021409** | **Date of Collection:** | **2/4/13 2:15:00 PM** |
| **Dil. Factor:** | **2.89** | **Date of Analysis:** | **2/14/13 02:15 PM** |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Dibromochloromethane | 1.4 | Not Detected | 12 | Not Detected |
| 1,2-Dibromoethane (EDB) | 1.4 | Not Detected | 11 | Not Detected |
| Chlorobenzene | 1.4 | Not Detected | 6.6 | Not Detected |
| Ethyl Benzene | 1.4 | Not Detected | 6.3 | Not Detected |
| m,p-Xylene | 1.4 | Not Detected | 6.3 | Not Detected |
| o-Xylene | 1.4 | Not Detected | 6.3 | Not Detected |
| Styrene | 1.4 | Not Detected | 6.2 | Not Detected |
| Bromoform | 1.4 | Not Detected | 15 | Not Detected |
| Cumene | 1.4 | Not Detected | 7.1 | Not Detected |
| 1,1,2,2-Tetrachloroethane | 1.4 | Not Detected | 9.9 | Not Detected |
| Propylbenzene | 1.4 | Not Detected | 7.1 | Not Detected |
| 4-Ethyltoluene | 1.4 | Not Detected | 7.1 | Not Detected |
| 1,3,5-Trimethylbenzene | 1.4 | Not Detected | 7.1 | Not Detected |
| 1,2,4-Trimethylbenzene | 1.4 | Not Detected | 7.1 | Not Detected |
| 1,3-Dichlorobenzene | 1.4 | Not Detected | 8.7 | Not Detected |
| 1,4-Dichlorobenzene | 1.4 | Not Detected | 8.7 | Not Detected |
| alpha-Chlorotoluene | 1.4 | Not Detected | 7.5 | Not Detected |
| 1,2-Dichlorobenzene | 1.4 | Not Detected | 8.7 | Not Detected |
| 1,2,4-Trichlorobenzene | 5.8 | ~~0.48 J~~ | 43 | ~~3.6 J~~ |
| Hexachlorobutadiene | 5.8 | Not Detected | 62 | Not Detected |
| Butane | 5.8 | 3.0 J | 14 | 7.1 J |
| Isopentane | 5.8 | 5.5 J | 17 | 16 J |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| Toluene-d8 | 97 | 70-130 |
| 1,2-Dichloroethane-d4 | 85 | 70-130 |
| 4-Bromofluorobenzene | 96 | 70-130 |

eurofins | Air Toxics

**Client Sample ID: VMP-51-30-020413-DUP**

**Lab ID#: 1302083A-16A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p021410** | **Date of Collection: 2/4/13 2:15:00 PM** | |
| **Dil. Factor:** | **2.81** | **Date of Analysis: 2/14/13 02:48 PM** | |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 1.4 | 0.44 J | 6.9 | 2.2 J |
| Freon 114 | 1.4 | Not Detected | 9.8 | Not Detected |
| Chloromethane | 14 | Not Detected | 29 | Not Detected |
| Vinyl Chloride | 1.4 | Not Detected | 3.6 | Not Detected |
| 1,3-Butadiene | 1.4 | Not Detected | 3.1 | Not Detected |
| Bromomethane | 14 | Not Detected | 54 | Not Detected |
| Chloroethane | 5.6 | Not Detected | 15 | Not Detected |
| Freon 11 | 1.4 | ~~0.30 J~~ U | 7.9 | ~~1.7 J~~ U |
| Ethanol | 5.6 | 1.1 J | 10 | 2.1 J |
| Freon 113 | 1.4 | Not Detected | 11 | Not Detected |
| 1,1-Dichloroethene | 1.4 | Not Detected | 5.6 | Not Detected |
| Acetone | 14 | 4.2 J | 33 | 10 J |
| 2-Propanol | 5.6 | 1.2 J | 14 | 3.1 J |
| Carbon Disulfide | 5.6 | ~~1.2 J~~ U | 18 | ~~3.9 J~~ U |
| 3-Chloropropene | 5.6 | Not Detected | 18 | Not Detected |
| Methylene Chloride | 14 | Not Detected | 49 | Not Detected |
| Methyl tert-butyl ether | 1.4 | Not Detected | 5.1 | Not Detected |
| trans-1,2-Dichloroethene | 1.4 | Not Detected | 5.6 | Not Detected |
| Hexane | 1.4 | 2.0 | 5.0 | 7.0 |
| 1,1-Dichloroethane | 1.4 | Not Detected | 5.7 | Not Detected |
| 2-Butanone (Methyl Ethyl Ketone) | 5.6 | Not Detected | 16 | Not Detected |
| cis-1,2-Dichloroethene | 1.4 | Not Detected | 5.6 | Not Detected |
| Tetrahydrofuran | 1.4 | Not Detected | 4.1 | Not Detected |
| Chloroform | 1.4 | 3.0 | 6.9 | 15 |
| 1,1,1-Trichloroethane | 1.4 | Not Detected | 7.7 | Not Detected |
| Cyclohexane | 1.4 | 2.5 | 4.8 | 8.7 |
| Carbon Tetrachloride | 1.4 | Not Detected | 8.8 | Not Detected |
| 2,2,4-Trimethylpentane | 1.4 | 1.2 J | 6.6 | 5.4 J |
| Benzene | 1.4 | 28 | 4.5 | 91 |
| 1,2-Dichloroethane | 1.4 | Not Detected | 5.7 | Not Detected |
| Heptane | 1.4 | 0.92 J | 5.8 | 3.8 J |
| Trichloroethene | 1.4 | Not Detected | 7.6 | Not Detected |
| 1,2-Dichloropropane | 1.4 | Not Detected | 6.5 | Not Detected |
| 1,4-Dioxane | 5.6 | Not Detected | 20 | Not Detected |
| Bromodichloromethane | 1.4 | Not Detected | 9.4 | Not Detected |
| cis-1,3-Dichloropropene | 1.4 | Not Detected | 6.4 | Not Detected |
| 4-Methyl-2-pentanone | 1.4 | Not Detected | 5.8 | Not Detected |
| Toluene | 1.4 | ~~0.35 J~~ U | 5.3 | ~~1.3 J~~ U |
| trans-1,3-Dichloropropene | 1.4 | Not Detected | 6.4 | Not Detected |
| 1,1,2-Trichloroethane | 1.4 | Not Detected | 7.7 | Not Detected |
| Tetrachloroethene | 1.4 | ~~0.31 J~~ U | 9.5 | ~~2.1 J~~ U |
| 2-Hexanone | 5.6 | Not Detected | 23 | Not Detected |

eurofins | Air Toxics

**Client Sample ID: VMP-51-30-020413-DUP**

**Lab ID#: 1302083A-16A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p021410** | **Date of Collection: 2/4/13 2:15:00 PM** | |
| **Dil. Factor:** | **2.81** | **Date of Analysis: 2/14/13 02:48 PM** | |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Dibromochloromethane | 1.4 | Not Detected | 12 | Not Detected |
| 1,2-Dibromoethane (EDB) | 1.4 | Not Detected | 11 | Not Detected |
| Chlorobenzene | 1.4 | Not Detected | 6.5 | Not Detected |
| Ethyl Benzene | 1.4 | Not Detected | 6.1 | Not Detected |
| m,p-Xylene | 1.4 | Not Detected | 6.1 | Not Detected |
| o-Xylene | 1.4 | Not Detected | 6.1 | Not Detected |
| Styrene | 1.4 | Not Detected | 6.0 | Not Detected |
| Bromoform | 1.4 | Not Detected | 14 | Not Detected |
| Cumene | 1.4 | Not Detected | 6.9 | Not Detected |
| 1,1,2,2-Tetrachloroethane | 1.4 | Not Detected | 9.6 | Not Detected |
| Propylbenzene | 1.4 | Not Detected | 6.9 | Not Detected |
| 4-Ethyltoluene | 1.4 | Not Detected | 6.9 | Not Detected |
| 1,3,5-Trimethylbenzene | 1.4 | Not Detected | 6.9 | Not Detected |
| 1,2,4-Trimethylbenzene | 1.4 | Not Detected | 6.9 | Not Detected |
| 1,3-Dichlorobenzene | 1.4 | Not Detected | 8.4 | Not Detected |
| 1,4-Dichlorobenzene | 1.4 | Not Detected | 8.4 | Not Detected |
| alpha-Chlorotoluene | 1.4 | Not Detected | 7.3 | Not Detected |
| 1,2-Dichlorobenzene | 1.4 | Not Detected | 8.4 | Not Detected |
| 1,2,4-Trichlorobenzene | 5.6 | Not Detected | 42 | Not Detected |
| Hexachlorobutadiene | 5.6 | Not Detected | 60 | Not Detected |
| Butane | 5.6 | 4.9 J | 13 | 12 J |
| Isopentane | 5.6 | 11 | 16 | 32 |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| Toluene-d8 | 97 | 70-130 |
| 1,2-Dichloroethane-d4 | 86 | 70-130 |
| 4-Bromofluorobenzene | 96 | 70-130 |

eurofins | Air Toxics

**Client Sample ID: VMP-51-30-020413-DUP Lab Duplicate**

**Lab ID#: 1302083A-16AA**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p021415** | **Date of Collection: 2/4/13 2:15:00 PM** | |
| **Dil. Factor:** | **2.81** | **Date of Analysis: 2/14/13 05:46 PM** | |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 1.4 | 0.40 J | 6.9 | 2.0 J |
| Freon 114 | 1.4 | Not Detected | 9.8 | Not Detected |
| Chloromethane | 14 | Not Detected | 29 | Not Detected |
| Vinyl Chloride | 1.4 | Not Detected | 3.6 | Not Detected |
| 1,3-Butadiene | 1.4 | Not Detected | 3.1 | Not Detected |
| Bromomethane | 14 | Not Detected | 54 | Not Detected |
| Chloroethane | 5.6 | Not Detected | 15 | Not Detected |
| Freon 11 | 1.4 | ~~0.28 J~~ | 7.9 | ~~1.6 J~~ |
| Ethanol | 5.6 | 2.2 J | 10 | 4.2 J |
| Freon 113 | 1.4 | Not Detected | 11 | Not Detected |
| 1,1-Dichloroethene | 1.4 | Not Detected | 5.6 | Not Detected |
| Acetone | 14 | 4.6 J | 33 | 11 J |
| 2-Propanol | 5.6 | 1.4 J | 14 | 3.5 J |
| Carbon Disulfide | 5.6 | ~~1.2 J~~ | 18 | ~~3.8 J~~ |
| 3-Chloropropene | 5.6 | Not Detected | 18 | Not Detected |
| Methylene Chloride | 14 | ~~0.19 J~~ | 49 | ~~0.65 J~~ |
| Methyl tert-butyl ether | 1.4 | Not Detected | 5.1 | Not Detected |
| trans-1,2-Dichloroethene | 1.4 | Not Detected | 5.6 | Not Detected |
| Hexane | 1.4 | 2.3 | 5.0 | 8.0 |
| 1,1-Dichloroethane | 1.4 | Not Detected | 5.7 | Not Detected |
| 2-Butanone (Methyl Ethyl Ketone) | 5.6 | Not Detected | 16 | Not Detected |
| cis-1,2-Dichloroethene | 1.4 | Not Detected | 5.6 | Not Detected |
| Tetrahydrofuran | 1.4 | Not Detected | 4.1 | Not Detected |
| Chloroform | 1.4 | 3.1 | 6.9 | 15 |
| 1,1,1-Trichloroethane | 1.4 | Not Detected | 7.7 | Not Detected |
| Cyclohexane | 1.4 | 2.6 | 4.8 | 8.8 |
| Carbon Tetrachloride | 1.4 | Not Detected | 8.8 | Not Detected |
| 2,2,4-Trimethylpentane | 1.4 | 1.4 | 6.6 | 6.4 |
| Benzene | 1.4 | 29 | 4.5 | 94 |
| 1,2-Dichloroethane | 1.4 | Not Detected | 5.7 | Not Detected |
| Heptane | 1.4 | 0.98 J | 5.8 | 4.0 J |
| Trichloroethene | 1.4 | Not Detected | 7.6 | Not Detected |
| 1,2-Dichloropropane | 1.4 | Not Detected | 6.5 | Not Detected |
| 1,4-Dioxane | 5.6 | Not Detected | 20 | Not Detected |
| Bromodichloromethane | 1.4 | Not Detected | 9.4 | Not Detected |
| cis-1,3-Dichloropropene | 1.4 | Not Detected | 6.4 | Not Detected |
| 4-Methyl-2-pentanone | 1.4 | Not Detected | 5.8 | Not Detected |
| Toluene | 1.4 | ~~0.35 J~~ | 5.3 | ~~1.3 J~~ |
| trans-1,3-Dichloropropene | 1.4 | Not Detected | 6.4 | Not Detected |
| 1,1,2-Trichloroethane | 1.4 | Not Detected | 7.7 | Not Detected |
| Tetrachloroethene | 1.4 | ~~0.29 J~~ | 9.5 | ~~2.0 J~~ |
| 2-Hexanone | 5.6 | Not Detected | 23 | Not Detected |

eurofins | Air Toxics

**Client Sample ID: VMP-51-30-020413-DUP Lab Duplicate**
**Lab ID#: 1302083A-16AA**
**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p021415** | **Date of Collection: 2/4/13 2:15:00 PM** | |
| **Dil. Factor:** | **2.81** | **Date of Analysis: 2/14/13 05:46 PM** | |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Dibromochloromethane | 1.4 | Not Detected | 12 | Not Detected |
| 1,2-Dibromoethane (EDB) | 1.4 | Not Detected | 11 | Not Detected |
| Chlorobenzene | 1.4 | Not Detected | 6.5 | Not Detected |
| Ethyl Benzene | 1.4 | Not Detected | 6.1 | Not Detected |
| m,p-Xylene | 1.4 | Not Detected | 6.1 | Not Detected |
| o-Xylene | 1.4 | Not Detected | 6.1 | Not Detected |
| Styrene | 1.4 | Not Detected | 6.0 | Not Detected |
| Bromoform | 1.4 | Not Detected | 14 | Not Detected |
| Cumene | 1.4 | Not Detected | 6.9 | Not Detected |
| 1,1,2,2-Tetrachloroethane | 1.4 | Not Detected | 9.6 | Not Detected |
| Propylbenzene | 1.4 | Not Detected | 6.9 | Not Detected |
| 4-Ethyltoluene | 1.4 | Not Detected | 6.9 | Not Detected |
| 1,3,5-Trimethylbenzene | 1.4 | Not Detected | 6.9 | Not Detected |
| 1,2,4-Trimethylbenzene | 1.4 | Not Detected | 6.9 | Not Detected |
| 1,3-Dichlorobenzene | 1.4 | Not Detected | 8.4 | Not Detected |
| 1,4-Dichlorobenzene | 1.4 | Not Detected | 8.4 | Not Detected |
| alpha-Chlorotoluene | 1.4 | Not Detected | 7.3 | Not Detected |
| 1,2-Dichlorobenzene | 1.4 | Not Detected | 8.4 | Not Detected |
| 1,2,4-Trichlorobenzene | 5.6 | Not Detected | 42 | Not Detected |
| Hexachlorobutadiene | 5.6 | Not Detected | 60 | Not Detected |
| Butane | 5.6 | 5.7 | 13 | 14 |
| Isopentane | 5.6 | 11 | 16 | 33 |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| Toluene-d8 | 97 | 70-130 |
| 1,2-Dichloroethane-d4 | 87 | 70-130 |
| 4-Bromofluorobenzene | 95 | 70-130 |

eurofins | Air Toxics

**Client Sample ID: Lab Blank**

**Lab ID#: 1302083A-17A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p021305a** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 2/13/13 11:21 AM** | |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 0.50 | Not Detected | 2.5 | Not Detected |
| Freon 114 | 0.50 | Not Detected | 3.5 | Not Detected |
| Chloromethane | 5.0 | Not Detected | 10 | Not Detected |
| Vinyl Chloride | 0.50 | Not Detected | 1.3 | Not Detected |
| 1,3-Butadiene | 0.50 | Not Detected | 1.1 | Not Detected |
| Bromomethane | 5.0 | 0.26 J | 19 | 1.0 J |
| Chloroethane | 2.0 | Not Detected | 5.3 | Not Detected |
| Freon 11 | 0.50 | Not Detected | 2.8 | Not Detected |
| Ethanol | 2.0 | Not Detected | 3.8 | Not Detected |
| Freon 113 | 0.50 | Not Detected | 3.8 | Not Detected |
| 1,1-Dichloroethene | 0.50 | Not Detected | 2.0 | Not Detected |
| Acetone | 5.0 | 0.40 J | 12 | 0.95 J |
| 2-Propanol | 2.0 | Not Detected | 4.9 | Not Detected |
| Carbon Disulfide | 2.0 | 0.35 J | 6.2 | 1.1 J |
| 3-Chloropropene | 2.0 | Not Detected | 6.3 | Not Detected |
| Methylene Chloride | 5.0 | 0.091 J | 17 | 0.32 J |
| Methyl tert-butyl ether | 0.50 | Not Detected | 1.8 | Not Detected |
| trans-1,2-Dichloroethene | 0.50 | Not Detected | 2.0 | Not Detected |
| Hexane | 0.50 | Not Detected | 1.8 | Not Detected |
| 1,1-Dichloroethane | 0.50 | Not Detected | 2.0 | Not Detected |
| 2-Butanone (Methyl Ethyl Ketone) | 2.0 | Not Detected | 5.9 | Not Detected |
| cis-1,2-Dichloroethene | 0.50 | Not Detected | 2.0 | Not Detected |
| Tetrahydrofuran | 0.50 | Not Detected | 1.5 | Not Detected |
| Chloroform | 0.50 | Not Detected | 2.4 | Not Detected |
| 1,1,1-Trichloroethane | 0.50 | Not Detected | 2.7 | Not Detected |
| Cyclohexane | 0.50 | Not Detected | 1.7 | Not Detected |
| Carbon Tetrachloride | 0.50 | Not Detected | 3.1 | Not Detected |
| 2,2,4-Trimethylpentane | 0.50 | Not Detected | 2.3 | Not Detected |
| Benzene | 0.50 | Not Detected | 1.6 | Not Detected |
| 1,2-Dichloroethane | 0.50 | Not Detected | 2.0 | Not Detected |
| Heptane | 0.50 | Not Detected | 2.0 | Not Detected |
| Trichloroethene | 0.50 | Not Detected | 2.7 | Not Detected |
| 1,2-Dichloropropane | 0.50 | Not Detected | 2.3 | Not Detected |
| 1,4-Dioxane | 2.0 | Not Detected | 7.2 | Not Detected |
| Bromodichloromethane | 0.50 | Not Detected | 3.4 | Not Detected |
| cis-1,3-Dichloropropene | 0.50 | Not Detected | 2.3 | Not Detected |
| 4-Methyl-2-pentanone | 0.50 | Not Detected | 2.0 | Not Detected |
| Toluene | 0.50 | 0.085 J | 1.9 | 0.32 J |
| trans-1,3-Dichloropropene | 0.50 | Not Detected | 2.3 | Not Detected |
| 1,1,2-Trichloroethane | 0.50 | Not Detected | 2.7 | Not Detected |
| Tetrachloroethene | 0.50 | 0.097 J | 3.4 | 0.66 J |
| 2-Hexanone | 2.0 | Not Detected | 8.2 | Not Detected |

eurofins | Air Toxics

**Client Sample ID: Lab Blank**

**Lab ID#: 1302083A-17A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p021305a** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 2/13/13 11:21 AM** | |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Dibromochloromethane | 0.50 | Not Detected | 4.2 | Not Detected |
| 1,2-Dibromoethane (EDB) | 0.50 | Not Detected | 3.8 | Not Detected |
| Chlorobenzene | 0.50 | 0.12 J | 2.3 | 0.55 J |
| Ethyl Benzene | 0.50 | 0.094 J | 2.2 | 0.41 J |
| m,p-Xylene | 0.50 | 0.11 J | 2.2 | 0.48 J |
| o-Xylene | 0.50 | 0.10 J | 2.2 | 0.45 J |
| Styrene | 0.50 | 0.094 J | 2.1 | 0.40 J |
| Bromoform | 0.50 | Not Detected | 5.2 | Not Detected |
| Cumene | 0.50 | 0.16 J | 2.4 | 0.77 J |
| 1,1,2,2-Tetrachloroethane | 0.50 | 0.15 J | 3.4 | 1.0 J |
| Propylbenzene | 0.50 | 0.18 J | 2.4 | 0.90 J |
| 4-Ethyltoluene | 0.50 | 0.16 J | 2.4 | 0.80 J |
| 1,3,5-Trimethylbenzene | 0.50 | 0.27 J | 2.4 | 1.3 J |
| 1,2,4-Trimethylbenzene | 0.50 | 0.21 J | 2.4 | 1.0 J |
| 1,3-Dichlorobenzene | 0.50 | 0.28 J | 3.0 | 1.7 J |
| 1,4-Dichlorobenzene | 0.50 | 0.30 J | 3.0 | 1.8 J |
| alpha-Chlorotoluene | 0.50 | 0.17 J | 2.6 | 0.90 J |
| 1,2-Dichlorobenzene | 0.50 | 0.28 J | 3.0 | 1.7 J |
| 1,2,4-Trichlorobenzene | 2.0 | 1.2 J | 15 | 9.1 J |
| Hexachlorobutadiene | 2.0 | 0.67 J | 21 | 7.2 J |
| Butane | 2.0 | Not Detected | 4.8 | Not Detected |
| Isopentane | 2.0 | Not Detected | 5.9 | Not Detected |

J = Estimated value.

**Container Type: NA - Not Applicable**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| Toluene-d8 | 96 | 70-130 |
| 1,2-Dichloroethane-d4 | 79 | 70-130 |
| 4-Bromofluorobenzene | 98 | 70-130 |

eurofins | Air Toxics

**Client Sample ID: Lab Blank**

**Lab ID#: 1302083A-17B**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p021405a** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 2/14/13 11:42 AM** | |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 0.50 | Not Detected | 2.5 | Not Detected |
| Freon 114 | 0.50 | Not Detected | 3.5 | Not Detected |
| Chloromethane | 5.0 | Not Detected | 10 | Not Detected |
| Vinyl Chloride | 0.50 | Not Detected | 1.3 | Not Detected |
| 1,3-Butadiene | 0.50 | Not Detected | 1.1 | Not Detected |
| Bromomethane | 5.0 | 0.30 J | 19 | 1.2 J |
| Chloroethane | 2.0 | Not Detected | 5.3 | Not Detected |
| Freon 11 | 0.50 | 0.074 J | 2.8 | 0.42 J |
| Ethanol | 2.0 | Not Detected | 3.8 | Not Detected |
| Freon 113 | 0.50 | Not Detected | 3.8 | Not Detected |
| 1,1-Dichloroethene | 0.50 | Not Detected | 2.0 | Not Detected |
| Acetone | 5.0 | Not Detected | 12 | Not Detected |
| 2-Propanol | 2.0 | Not Detected | 4.9 | Not Detected |
| Carbon Disulfide | 2.0 | 0.49 J | 6.2 | 1.5 J |
| 3-Chloropropene | 2.0 | Not Detected | 6.3 | Not Detected |
| Methylene Chloride | 5.0 | 0.19 J | 17 | 0.66 J |
| Methyl tert-butyl ether | 0.50 | Not Detected | 1.8 | Not Detected |
| trans-1,2-Dichloroethene | 0.50 | Not Detected | 2.0 | Not Detected |
| Hexane | 0.50 | Not Detected | 1.8 | Not Detected |
| 1,1-Dichloroethane | 0.50 | Not Detected | 2.0 | Not Detected |
| 2-Butanone (Methyl Ethyl Ketone) | 2.0 | Not Detected | 5.9 | Not Detected |
| cis-1,2-Dichloroethene | 0.50 | Not Detected | 2.0 | Not Detected |
| Tetrahydrofuran | 0.50 | Not Detected | 1.5 | Not Detected |
| Chloroform | 0.50 | Not Detected | 2.4 | Not Detected |
| 1,1,1-Trichloroethane | 0.50 | Not Detected | 2.7 | Not Detected |
| Cyclohexane | 0.50 | Not Detected | 1.7 | Not Detected |
| Carbon Tetrachloride | 0.50 | Not Detected | 3.1 | Not Detected |
| 2,2,4-Trimethylpentane | 0.50 | 0.053 J | 2.3 | 0.25 J |
| Benzene | 0.50 | Not Detected | 1.6 | Not Detected |
| 1,2-Dichloroethane | 0.50 | Not Detected | 2.0 | Not Detected |
| Heptane | 0.50 | Not Detected | 2.0 | Not Detected |
| Trichloroethene | 0.50 | Not Detected | 2.7 | Not Detected |
| 1,2-Dichloropropane | 0.50 | Not Detected | 2.3 | Not Detected |
| 1,4-Dioxane | 2.0 | Not Detected | 7.2 | Not Detected |
| Bromodichloromethane | 0.50 | Not Detected | 3.4 | Not Detected |
| cis-1,3-Dichloropropene | 0.50 | Not Detected | 2.3 | Not Detected |
| 4-Methyl-2-pentanone | 0.50 | Not Detected | 2.0 | Not Detected |
| Toluene | 0.50 | 0.072 J | 1.9 | 0.27 J |
| trans-1,3-Dichloropropene | 0.50 | 0.16 J | 2.3 | 0.74 J |
| 1,1,2-Trichloroethane | 0.50 | Not Detected | 2.7 | Not Detected |
| Tetrachloroethene | 0.50 | 0.13 J | 3.4 | 0.89 J |
| 2-Hexanone | 2.0 | Not Detected | 8.2 | Not Detected |

eurofins | Air Toxics

**Client Sample ID: Lab Blank**

**Lab ID#: 1302083A-17B**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p021405a** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 2/14/13 11:42 AM** | |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Dibromochloromethane | 0.50 | Not Detected | 4.2 | Not Detected |
| 1,2-Dibromoethane (EDB) | 0.50 | Not Detected | 3.8 | Not Detected |
| Chlorobenzene | 0.50 | 0.11 J | 2.3 | 0.50 J |
| Ethyl Benzene | 0.50 | Not Detected | 2.2 | Not Detected |
| m,p-Xylene | 0.50 | Not Detected | 2.2 | Not Detected |
| o-Xylene | 0.50 | 0.099 J | 2.2 | 0.43 J |
| Styrene | 0.50 | 0.098 J | 2.1 | 0.42 J |
| Bromoform | 0.50 | Not Detected | 5.2 | Not Detected |
| Cumene | 0.50 | 0.16 J | 2.4 | 0.79 J |
| 1,1,2,2-Tetrachloroethane | 0.50 | 0.15 J | 3.4 | 1.0 J |
| Propylbenzene | 0.50 | 0.18 J | 2.4 | 0.87 J |
| 4-Ethyltoluene | 0.50 | 0.15 J | 2.4 | 0.74 J |
| 1,3,5-Trimethylbenzene | 0.50 | 0.27 J | 2.4 | 1.3 J |
| 1,2,4-Trimethylbenzene | 0.50 | 0.21 J | 2.4 | 1.0 J |
| 1,3-Dichlorobenzene | 0.50 | 0.36 J | 3.0 | 2.2 J |
| 1,4-Dichlorobenzene | 0.50 | 0.34 J | 3.0 | 2.0 J |
| alpha-Chlorotoluene | 0.50 | 0.20 J | 2.6 | 1.0 J |
| 1,2-Dichlorobenzene | 0.50 | 0.32 J | 3.0 | 1.9 J |
| 1,2,4-Trichlorobenzene | 2.0 | 1.4 J | 15 | 10 J |
| Hexachlorobutadiene | 2.0 | 0.79 J | 21 | 8.4 J |
| Butane | 2.0 | Not Detected | 4.8 | Not Detected |
| Isopentane | 2.0 | Not Detected | 5.9 | Not Detected |

J = Estimated value.

**Container Type: NA - Not Applicable**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| Toluene-d8 | 96 | 70-130 |
| 1,2-Dichloroethane-d4 | 83 | 70-130 |
| 4-Bromofluorobenzene | 97 | 70-130 |

eurofins | Air Toxics

**Client Sample ID: CCV**
**Lab ID#: 1302083A-18A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p021302** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 2/13/13 09:35 AM** | |

| Compound | %Recovery |
|---|---|
| Freon 12 | 86 |
| Freon 114 | 96 |
| Chloromethane | 86 |
| Vinyl Chloride | 99 |
| 1,3-Butadiene | 96 |
| Bromomethane | 99 |
| Chloroethane | 99 |
| Freon 11 | 83 |
| Ethanol | 96 |
| Freon 113 | 95 |
| 1,1-Dichloroethene | 103 |
| Acetone | 102 |
| 2-Propanol | 97 |
| Carbon Disulfide | 97 |
| 3-Chloropropene | 106 |
| Methylene Chloride | 90 |
| Methyl tert-butyl ether | 111 |
| trans-1,2-Dichloroethene | 106 |
| Hexane | 106 |
| 1,1-Dichloroethane | 94 |
| 2-Butanone (Methyl Ethyl Ketone) | 103 |
| cis-1,2-Dichloroethene | 112 |
| Tetrahydrofuran | 106 |
| Chloroform | 90 |
| 1,1,1-Trichloroethane | 89 |
| Cyclohexane | 118 |
| Carbon Tetrachloride | 85 |
| 2,2,4-Trimethylpentane | 110 |
| Benzene | 100 |
| 1,2-Dichloroethane | 80 |
| Heptane | 113 |
| Trichloroethene | 79 |
| 1,2-Dichloropropane | 98 |
| 1,4-Dioxane | 111 |
| Bromodichloromethane | 85 |
| cis-1,3-Dichloropropene | 102 |
| 4-Methyl-2-pentanone | 111 |
| Toluene | 99 |
| trans-1,3-Dichloropropene | 100 |
| 1,1,2-Trichloroethane | 100 |
| Tetrachloroethene | 97 |
| 2-Hexanone | 107 |

eurofins | Air Toxics

**Client Sample ID: CCV**
**Lab ID#: 1302083A-18A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p021302** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 2/13/13 09:35 AM** | |

| Compound | %Recovery |
|---|---|
| Dibromochloromethane | 96 |
| 1,2-Dibromoethane (EDB) | 99 |
| Chlorobenzene | 95 |
| Ethyl Benzene | 106 |
| m,p-Xylene | 111 |
| o-Xylene | 112 |
| Styrene | 116 |
| Bromoform | 97 |
| Cumene | 110 |
| 1,1,2,2-Tetrachloroethane | 106 |
| Propylbenzene | 102 |
| 4-Ethyltoluene | 109 |
| 1,3,5-Trimethylbenzene | 114 |
| 1,2,4-Trimethylbenzene | 112 |
| 1,3-Dichlorobenzene | 100 |
| 1,4-Dichlorobenzene | 98 |
| alpha-Chlorotoluene | 102 |
| 1,2-Dichlorobenzene | 100 |
| 1,2,4-Trichlorobenzene | 101 |
| Hexachlorobutadiene | 92 |
| Butane | 93 |
| Isopentane | 98 |

**Container Type: NA - Not Applicable**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| Toluene-d8 | 99 | 70-130 |
| 1,2-Dichloroethane-d4 | 81 | 70-130 |
| 4-Bromofluorobenzene | 99 | 70-130 |

eurofins | Air Toxics

**Client Sample ID: CCV**

**Lab ID#: 1302083A-18B**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p021402** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 2/14/13 10:07 AM** | |

| Compound | %Recovery |
|---|---|
| Freon 12 | 90 |
| Freon 114 | 97 |
| Chloromethane | 88 |
| Vinyl Chloride | 99 |
| 1,3-Butadiene | 96 |
| Bromomethane | 100 |
| Chloroethane | 97 |
| Freon 11 | 87 |
| Ethanol | 93 |
| Freon 113 | 97 |
| 1,1-Dichloroethene | 102 |
| Acetone | 101 |
| 2-Propanol | 98 |
| Carbon Disulfide | 98 |
| 3-Chloropropene | 105 |
| Methylene Chloride | 93 |
| Methyl tert-butyl ether | 112 |
| trans-1,2-Dichloroethene | 105 |
| Hexane | 106 |
| 1,1-Dichloroethane | 94 |
| 2-Butanone (Methyl Ethyl Ketone) | 102 |
| cis-1,2-Dichloroethene | 108 |
| Tetrahydrofuran | 107 |
| Chloroform | 92 |
| 1,1,1-Trichloroethane | 93 |
| Cyclohexane | 116 |
| Carbon Tetrachloride | 90 |
| 2,2,4-Trimethylpentane | 110 |
| Benzene | 100 |
| 1,2-Dichloroethane | 83 |
| Heptane | 110 |
| Trichloroethene | 80 |
| 1,2-Dichloropropane | 97 |
| 1,4-Dioxane | 110 |
| Bromodichloromethane | 88 |
| cis-1,3-Dichloropropene | 102 |
| 4-Methyl-2-pentanone | 113 |
| Toluene | 98 |
| trans-1,3-Dichloropropene | 100 |
| 1,1,2-Trichloroethane | 100 |
| Tetrachloroethene | 97 |
| 2-Hexanone | 105 |

eurofins | Air Toxics

**Client Sample ID: CCV**
**Lab ID#: 1302083A-18B**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p021402** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 2/14/13 10:07 AM** | |

| Compound | %Recovery |
|---|---|
| Dibromochloromethane | 98 |
| 1,2-Dibromoethane (EDB) | 98 |
| Chlorobenzene | 94 |
| Ethyl Benzene | 105 |
| m,p-Xylene | 110 |
| o-Xylene | 110 |
| Styrene | 114 |
| Bromoform | 99 |
| Cumene | 109 |
| 1,1,2,2-Tetrachloroethane | 108 |
| Propylbenzene | 103 |
| 4-Ethyltoluene | 110 |
| 1,3,5-Trimethylbenzene | 111 |
| 1,2,4-Trimethylbenzene | 111 |
| 1,3-Dichlorobenzene | 100 |
| 1,4-Dichlorobenzene | 99 |
| alpha-Chlorotoluene | 103 |
| 1,2-Dichlorobenzene | 101 |
| 1,2,4-Trichlorobenzene | 101 |
| Hexachlorobutadiene | 95 |
| Butane | 94 |
| Isopentane | 98 |

**Container Type: NA - Not Applicable**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| Toluene-d8 | 99 | 70-130 |
| 1,2-Dichloroethane-d4 | 89 | 70-130 |
| 4-Bromofluorobenzene | 99 | 70-130 |

eurofins | Air Toxics

**Client Sample ID: LCS**

**Lab ID#: 1302083A-19A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p021303** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 2/13/13 10:08 AM** | |

| Compound | %Recovery |
|---|---|
| Freon 12 | 85 |
| Freon 114 | 93 |
| Chloromethane | 92 |
| Vinyl Chloride | 99 |
| 1,3-Butadiene | 95 |
| Bromomethane | 96 |
| Chloroethane | 96 |
| Freon 11 | 82 |
| Ethanol | 75 |
| Freon 113 | 94 |
| 1,1-Dichloroethene | 104 |
| Acetone | 99 |
| 2-Propanol | 95 |
| Carbon Disulfide | 118 |
| 3-Chloropropene | 115 |
| Methylene Chloride | 88 |
| Methyl tert-butyl ether | 104 |
| trans-1,2-Dichloroethene | 114 |
| Hexane | 101 |
| 1,1-Dichloroethane | 91 |
| 2-Butanone (Methyl Ethyl Ketone) | 104 |
| cis-1,2-Dichloroethene | 106 |
| Tetrahydrofuran | 101 |
| Chloroform | 88 |
| 1,1,1-Trichloroethane | 88 |
| Cyclohexane | 116 |
| Carbon Tetrachloride | 84 |
| 2,2,4-Trimethylpentane | 105 |
| Benzene | 98 |
| 1,2-Dichloroethane | 77 |
| Heptane | 106 |
| Trichloroethene | 78 |
| 1,2-Dichloropropane | 94 |
| 1,4-Dioxane | 106 |
| Bromodichloromethane | 83 |
| cis-1,3-Dichloropropene | 99 |
| 4-Methyl-2-pentanone | 108 |
| Toluene | 94 |
| trans-1,3-Dichloropropene | 98 |
| 1,1,2-Trichloroethane | 95 |
| Tetrachloroethene | 93 |
| 2-Hexanone | 100 |

eurofins | Air Toxics

**Client Sample ID: LCS**
**Lab ID#: 1302083A-19A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p021303** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 2/13/13 10:08 AM** | |

| Compound | %Recovery |
|---|---|
| Dibromochloromethane | 91 |
| 1,2-Dibromoethane (EDB) | 96 |
| Chlorobenzene | 93 |
| Ethyl Benzene | 102 |
| m,p-Xylene | 106 |
| o-Xylene | 109 |
| Styrene | 111 |
| Bromoform | 91 |
| Cumene | 107 |
| 1,1,2,2-Tetrachloroethane | 106 |
| Propylbenzene | 101 |
| 4-Ethyltoluene | 102 |
| 1,3,5-Trimethylbenzene | 108 |
| 1,2,4-Trimethylbenzene | 107 |
| 1,3-Dichlorobenzene | 98 |
| 1,4-Dichlorobenzene | 96 |
| alpha-Chlorotoluene | 99 |
| 1,2-Dichlorobenzene | 100 |
| 1,2,4-Trichlorobenzene | 102 |
| Hexachlorobutadiene | 92 |
| Butane | 86 |
| Isopentane | 94 |

**Container Type: NA - Not Applicable**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| Toluene-d8 | 98 | 70-130 |
| 1,2-Dichloroethane-d4 | 82 | 70-130 |
| 4-Bromofluorobenzene | 101 | 70-130 |

eurofins | Air Toxics

**Client Sample ID: LCSD**
**Lab ID#: 1302083A-19AA**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p021304** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 2/13/13 10:31 AM** | |

| Compound | %Recovery |
|---|---|
| Freon 12 | 81 |
| Freon 114 | 91 |
| Chloromethane | 88 |
| Vinyl Chloride | 96 |
| 1,3-Butadiene | 91 |
| Bromomethane | 94 |
| Chloroethane | 95 |
| Freon 11 | 79 |
| Ethanol | 74 |
| Freon 113 | 91 |
| 1,1-Dichloroethene | 103 |
| Acetone | 95 |
| 2-Propanol | 92 |
| Carbon Disulfide | 112 |
| 3-Chloropropene | 113 |
| Methylene Chloride | 85 |
| Methyl tert-butyl ether | 97 |
| trans-1,2-Dichloroethene | 112 |
| Hexane | 98 |
| 1,1-Dichloroethane | 89 |
| 2-Butanone (Methyl Ethyl Ketone) | 96 |
| cis-1,2-Dichloroethene | 106 |
| Tetrahydrofuran | 98 |
| Chloroform | 86 |
| 1,1,1-Trichloroethane | 85 |
| Cyclohexane | 113 |
| Carbon Tetrachloride | 82 |
| 2,2,4-Trimethylpentane | 103 |
| Benzene | 97 |
| 1,2-Dichloroethane | 76 |
| Heptane | 105 |
| Trichloroethene | 77 |
| 1,2-Dichloropropane | 94 |
| 1,4-Dioxane | 104 |
| Bromodichloromethane | 83 |
| cis-1,3-Dichloropropene | 99 |
| 4-Methyl-2-pentanone | 104 |
| Toluene | 94 |
| trans-1,3-Dichloropropene | 95 |
| 1,1,2-Trichloroethane | 95 |
| Tetrachloroethene | 92 |
| 2-Hexanone | 101 |

eurofins | Air Toxics

**Client Sample ID: LCSD**

**Lab ID#: 1302083A-19AA**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p021304** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 2/13/13 10:31 AM** | |

| Compound | %Recovery |
|---|---|
| Dibromochloromethane | 91 |
| 1,2-Dibromoethane (EDB) | 94 |
| Chlorobenzene | 93 |
| Ethyl Benzene | 102 |
| m,p-Xylene | 107 |
| o-Xylene | 109 |
| Styrene | 111 |
| Bromoform | 91 |
| Cumene | 107 |
| 1,1,2,2-Tetrachloroethane | 106 |
| Propylbenzene | 100 |
| 4-Ethyltoluene | 103 |
| 1,3,5-Trimethylbenzene | 108 |
| 1,2,4-Trimethylbenzene | 106 |
| 1,3-Dichlorobenzene | 98 |
| 1,4-Dichlorobenzene | 95 |
| alpha-Chlorotoluene | 98 |
| 1,2-Dichlorobenzene | 99 |
| 1,2,4-Trichlorobenzene | 104 |
| Hexachlorobutadiene | 92 |
| Butane | 84 |
| Isopentane | 91 |

**Container Type: NA - Not Applicable**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| Toluene-d8 | 98 | 70-130 |
| 1,2-Dichloroethane-d4 | 81 | 70-130 |
| 4-Bromofluorobenzene | 101 | 70-130 |

eurofins | Air Toxics

**Client Sample ID: LCS**

**Lab ID#: 1302083A-19B**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p021403** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 2/14/13 10:43 AM** | |

| Compound | %Recovery |
|---|---|
| Freon 12 | 84 |
| Freon 114 | 92 |
| Chloromethane | 91 |
| Vinyl Chloride | 96 |
| 1,3-Butadiene | 90 |
| Bromomethane | 94 |
| Chloroethane | 93 |
| Freon 11 | 82 |
| Ethanol | 71 |
| Freon 113 | 91 |
| 1,1-Dichloroethene | 102 |
| Acetone | 93 |
| 2-Propanol | 92 |
| Carbon Disulfide | 112 |
| 3-Chloropropene | 108 |
| Methylene Chloride | 87 |
| Methyl tert-butyl ether | 104 |
| trans-1,2-Dichloroethene | 110 |
| Hexane | 97 |
| 1,1-Dichloroethane | 89 |
| 2-Butanone (Methyl Ethyl Ketone) | 94 |
| cis-1,2-Dichloroethene | 100 |
| Tetrahydrofuran | 95 |
| Chloroform | 87 |
| 1,1,1-Trichloroethane | 88 |
| Cyclohexane | 108 |
| Carbon Tetrachloride | 84 |
| 2,2,4-Trimethylpentane | 101 |
| Benzene | 97 |
| 1,2-Dichloroethane | 79 |
| Heptane | 104 |
| Trichloroethene | 78 |
| 1,2-Dichloropropane | 94 |
| 1,4-Dioxane | 103 |
| Bromodichloromethane | 85 |
| cis-1,3-Dichloropropene | 99 |
| 4-Methyl-2-pentanone | 105 |
| Toluene | 94 |
| trans-1,3-Dichloropropene | 96 |
| 1,1,2-Trichloroethane | 93 |
| Tetrachloroethene | 91 |
| 2-Hexanone | 98 |

eurofins | Air Toxics

**Client Sample ID: LCS**

**Lab ID#: 1302083A-19B**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p021403** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 2/14/13 10:43 AM** | |

| Compound | %Recovery |
|---|---|
| Dibromochloromethane | 92 |
| 1,2-Dibromoethane (EDB) | 94 |
| Chlorobenzene | 91 |
| Ethyl Benzene | 100 |
| m,p-Xylene | 104 |
| o-Xylene | 105 |
| Styrene | 109 |
| Bromoform | 91 |
| Cumene | 105 |
| 1,1,2,2-Tetrachloroethane | 104 |
| Propylbenzene | 99 |
| 4-Ethyltoluene | 98 |
| 1,3,5-Trimethylbenzene | 106 |
| 1,2,4-Trimethylbenzene | 104 |
| 1,3-Dichlorobenzene | 96 |
| 1,4-Dichlorobenzene | 94 |
| alpha-Chlorotoluene | 96 |
| 1,2-Dichlorobenzene | 97 |
| 1,2,4-Trichlorobenzene | 100 |
| Hexachlorobutadiene | 91 |
| Butane | 83 |
| Isopentane | 92 |

**Container Type: NA - Not Applicable**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| Toluene-d8 | 100 | 70-130 |
| 1,2-Dichloroethane-d4 | 84 | 70-130 |
| 4-Bromofluorobenzene | 98 | 70-130 |

eurofins | Air Toxics

**Client Sample ID: LCSD**
**Lab ID#: 1302083A-19BB**
**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p021404** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 2/14/13 11:03 AM** | |

| Compound | %Recovery |
|---|---|
| Freon 12 | 89 |
| Freon 114 | 96 |
| Chloromethane | 96 |
| Vinyl Chloride | 101 |
| 1,3-Butadiene | 95 |
| Bromomethane | 101 |
| Chloroethane | 99 |
| Freon 11 | 86 |
| Ethanol | 78 |
| Freon 113 | 98 |
| 1,1-Dichloroethene | 108 |
| Acetone | 100 |
| 2-Propanol | 97 |
| Carbon Disulfide | 119 |
| 3-Chloropropene | 121 |
| Methylene Chloride | 91 |
| Methyl tert-butyl ether | 110 |
| trans-1,2-Dichloroethene | 116 |
| Hexane | 104 |
| 1,1-Dichloroethane | 95 |
| 2-Butanone (Methyl Ethyl Ketone) | 104 |
| cis-1,2-Dichloroethene | 110 |
| Tetrahydrofuran | 103 |
| Chloroform | 94 |
| 1,1,1-Trichloroethane | 93 |
| Cyclohexane | 116 |
| Carbon Tetrachloride | 89 |
| 2,2,4-Trimethylpentane | 108 |
| Benzene | 100 |
| 1,2-Dichloroethane | 82 |
| Heptane | 108 |
| Trichloroethene | 81 |
| 1,2-Dichloropropane | 96 |
| 1,4-Dioxane | 105 |
| Bromodichloromethane | 87 |
| cis-1,3-Dichloropropene | 102 |
| 4-Methyl-2-pentanone | 109 |
| Toluene | 98 |
| trans-1,3-Dichloropropene | 99 |
| 1,1,2-Trichloroethane | 96 |
| Tetrachloroethene | 96 |
| 2-Hexanone | 102 |

eurofins | Air Toxics

**Client Sample ID: LCSD**
**Lab ID#: 1302083A-19BB**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p021404** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 2/14/13 11:03 AM** | |

| Compound | %Recovery |
|---|---|
| Dibromochloromethane | 96 |
| 1,2-Dibromoethane (EDB) | 98 |
| Chlorobenzene | 95 |
| Ethyl Benzene | 104 |
| m,p-Xylene | 110 |
| o-Xylene | 111 |
| Styrene | 113 |
| Bromoform | 95 |
| Cumene | 110 |
| 1,1,2,2-Tetrachloroethane | 109 |
| Propylbenzene | 104 |
| 4-Ethyltoluene | 103 |
| 1,3,5-Trimethylbenzene | 112 |
| 1,2,4-Trimethylbenzene | 109 |
| 1,3-Dichlorobenzene | 101 |
| 1,4-Dichlorobenzene | 100 |
| alpha-Chlorotoluene | 102 |
| 1,2-Dichlorobenzene | 103 |
| 1,2,4-Trichlorobenzene | 107 |
| Hexachlorobutadiene | 97 |
| Butane | 88 |
| Isopentane | 96 |

**Container Type: NA - Not Applicable**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| Toluene-d8 | 100 | 70-130 |
| 1,2-Dichloroethane-d4 | 87 | 70-130 |
| 4-Bromofluorobenzene | 100 | 70-130 |

# Shell Oil Products Chain Of Custody Record

URS

**Air Toxics LTD.**
**Project Name: Roxana Soil Vapor**
**Project # 21562850.04001**
**Lab Vendor #**

Please Check Appropriate Box: ☑ ENV. SERVICES ☐ MOTIVA RETAIL ☐ SHELL RETAIL ☐ MOTIVA SD&CM ☐ CONSULTANT ☐ LUBES ☐ SHELL PIPELINE ☐ OTHER

Print Bill To Contact Name: Robert Moosheglan

INCIDENT # (ENV SERVICES): 9 7 2 1 6 8 4 0 ☐ CHECK IF NO INCIDENT # APPLIES

DATE: 02/04/13

PAGE: 1 of 2

PO #:

SAP #: 3 4 0 0 6 1

SAMPLING COMPANY: URS CORPORATION

LOG CODE:

SITE ADDRESS: Street and City: 900 SOUTH CENTRAL AVE – ROXANA

State: IL

GLOBAL ID NO.:

ADDRESS: 1001 HIGHLANDS PLAZA DRIVE WEST - SUITE 300; ST. LOUIS, MO 63110

PROJECT MGR. (Name, Company, Office Location): Elizabeth Kunkel, URS, St. Louis

PHONE NO.: 314-743-4179

EMAIL: Elizabeth.Kunkel@URSCorp.com

CONSULTANT PROJECT NAME/#: Roxana Soil Vapor

LABORATORY ADDRESS: Air Toxics, LTD 180 Blue Ravine Road, Suite B, Folsom, CA 95630-4719

TELEPHONE:

FAX: 314-429-0462

BILL TO (Company) EMAIL: Robert.Moosheglan@urs.com

C. Williams, L. Rathnow, S. Jansen, M. Mittermeyer, J. Staetter, B. Lehan, M. Currier

TURNAROUND TIME (CALENDAR DAYS): ☑ STANDARD (14 DAY) ☐ 5 DAYS ☐ 3 DAYS ☐ 2 DAYS ☐ 24 HOURS ☐ RESULTS NEEDED ON WEEKEND

☐ LA - RWQCB REPORT FORMAT ☑ UST AGENCY:

DELIVERABLES: ☐ LEVEL 1 ☐ LEVEL 2 ☐ LEVEL 3 ☑ LEVEL 4 ☐ OTHER (SPECIFY)

☑ SHELL CONTRACT RATE APPLIES
☐ STATE REIMBURSEMENT RATE APPLIES
☐ EDD NOT NEEDED
☑ RECEIPT VERIFICATION REQUESTED

REQUESTED ANALYSIS

| LAB USE ONLY | Field Sample Identification | SAMPLING DATE | SAMPLING TIME | Canister Number | Canister Pressure/Vacuum: Initial | Final | Receipt | Final (psi) | Modified TO-15 + Butane & Isopentane | ASTM D-1946 + Helium |
|---|---|---|---|---|---|---|---|---|---|---|
| | VMP-48-5-020113 | 02/01/13 | 1050-1120 | 37298 | -29.5 | -8.5 | | | X | X |
| | VMP-48-10-020113 | 02/01/13 | 1313-1343 | 2180 | -29.5 | -9 | | | X | X |
| | VMP-48-20-020113 | 02/01/13 | 1405-1435 | 37770 | -30 | -8 | | | X | X |
| | VMP-48-30-020113 | 02/01/13 | 1501-1531 | 34573 | -30 | -8 | | | X | X |
| | VMP-48-30-020113-DUP | 02/01/13 | 1501-1531 | 36473 | -30 | -7.5 | | | X | X |
| | VMP-50-10-020113 | 02/01/13 | 1259-1330 | 35634 | -30 | -10.5 | | | X | X |
| | VMP-51-5-020113 | 02/01/13 | 1340-1413 | 37385 | -30 | -10 | | | X | X |
| | VMP-51-10-020113 | 02/01/13 | 1514-1546 | 37427 | -30 | -10.5 | | | X | X |
| | VMP-51-20-020113 | 02/01/13 | 1428-1456 | 35624 | -30 | -8.5 | | | X | X |
| | | | | | | | | | X | X |

Turn Around Time: ☑ Normal ☐ Rush Specify

Lab Use Only: Pressurized by: Date: Pressurization Gas: $N_2$ He

ADDITIONAL NOTES:

- 14 day hold time
- Report results between MDL and RL
- Level IV ECVP

Relinquished by: (Signature)

Received by: (Signature) FEDEX

Date: 2/4/13 Time: 1830

Relinquished by: (Signature)

Received by: (Signature)

Date: 2/5/13 Time: 0925

Relinquished by: (Signature)

Received by: (Signature)

Custody Seal Intact? (Y) N None Temp N/A

Date: Time:

05/2/08 Revision

1302083

# Shell Oil Products Chain Of Custody Record

URS

**Air Toxics LTD.**
**Project Name: Roxana Soil Vapor**
**Project # 21562850.04001**
**Lab Vendor #**

**Please Check Appropriate Box:**
☑ ENV. SERVICES ☐ MOTIVA RETAIL ☐ SHELL RETAIL
☐ MOTIVA SD&DM ☐ CONSULTANT ☐ LUBES
☐ SHELL PIPELINE ☐ OTHER

**Print Bill To Contact Name:** Robert Mocshegian
**PO: #**
**INCIDENT # (ENV SERVICES):** 9 7 2 1 6 6 4 0
☐ CHECK IF NO INCIDENT # APPLIES
**SAP #:** 3 4 0 0 6 1
DATE: 02/04/13
PAGE: 2 of 2

SAMPLING COMPANY: URS CORPORATION
LOG CODE:
SITE ADDRESS: Street and City: 900 SOUTH CENTRAL AVE – ROXANA
State: IL
GLOBAL ID NO.:
ADDRESS: 1001 HIGHLANDS PLAZA DRIVE WEST - SUITE 300; ST LOUIS MO 63110
EDF DELIVERABLE TO (Name, Company, Office Location): Elizabeth Kunkel, URS, St. Louis
PHONE NO.: 314-743-4179
E-MAIL: Elizabeth_Kunkel@URSCorp.com
CONSULTANT PROJECT NAME#: Roxana Soil Vapor
Laboratory Address: Air Toxics, LTD 180 Blue Ravine Road Suite B, Folsom, CA 95630-4719
TELEPHONE:
FAX: 314-429-0482
Bill To Contact E-MAIL: Robert.Mocshegian@urs.com
C. Williams, L. Rethmow, S. Jansen, M. Mittlemeyer, J. Staetter, B. Lehan, M. Currier

TURNAROUND TIME (CALENDAR DAYS):
☑ STANDARD (14 DAY) ☐ 5 DAYS ☐ 3 DAYS ☐ 2 DAYS ☐ 24 HOURS ☐ RESULTS NEEDED ON WEEKEND

☐ LA - RWQCB REPORT FORMAT ☑ UST AGENCY:

DELIVERABLES: ☐ LEVEL 1 ☐ LEVEL 2 ☐ LEVEL 3 ☑ LEVEL 4 ☐ OTHER (SPECIFY)

☑ SHELL CONTRACT RATE APPLIES
☐ STATE REIMBURSEMENT RATE APPLIES
☐ EDD NOT NEEDED
☑ RECEIPT VERIFICATION REQUESTED

**REQUESTED ANALYSIS**

| Lab Use Only | Field Sample Identification | SAMPLING DATE | SAMPLING TIME | Canister Number | Canister Pressure/Vacuum: Initial | Final | Receipt | Final (psi) | Modified TO-15 + Butane & Isopentane | ASTM D-1946 + Helium |
|---|---|---|---|---|---|---|---|---|---|---|
| | VMP-52-5-020413 | 02/04/13 | 0917-0947 | 100188 | -30 | -8 | | | X | X |
| | VMP-52-10-020413 | 02/04/13 | 1006-1036 | 37353 | -30 | -7 | | | X | X |
| | VMP-52-20-020413 | 02/04/13 | 1052-1122 | 33645 | -30 | -8.5 | | | X | X |
| | VMP-52-20-020413-DUP | 02/04/13 | 1052-1122 | 37425 | -30 | -7.5 | | | X | X |
| | VMP-52-30-020413 | 02/04/13 | 1134-1204 | 34137 | -29 | -9.5 | | | X | X |
| | VMP-51-30-020413 | 02/04/13 | 1344-1415 | 31784 | -30 | -10 | | | X | X |
| | VMP-51-30-020413-DUP | 02/04/13 | 1344-1415 | 37379 | -30 | -10 | | | X | X |
| | | | | | | | | | X | X |
| | | | | | | | | | X | X |
| | | | | | | | | | X | X |

2/4/13

**Turn Around Time:** ☑ Normal ☐ Rush ☐ Specify

**Lab Use Only**
Pressurized by:
Date:
Pressurization Gas: $N_2$ He

**ADDITIONAL NOTES:**
- 14 day hold time
- Report results between MDL and RL
- Level IV ECVP

| Relinquished by: (Signature) | Received by: (Signature) | Date | Time |
|---|---|---|---|
| | FEDEX | 2/4/13 | 1830 |
| Relinquished by: (Signature) | Received by: (Signature) | Date | Time |
| | TBJ Whitaker ATL | 2/5/13 | 0925 |
| Relinquished by: (Signature) | Received by: (Signature) | Date | Time |
| | | | |

Custody Seal Intact? Y N None Temp N/A
Fedex

06/2008 Revision

eurofins | Air Toxics

2/19/2013
Ms. Elizabeth Kunkel
URS Corporation
1001 Highlands Plaza Dr. West
Suite 300
St. Louis MO 63110

Project Name: Roxana Soil Vapor
Project #: 21562850.04001
Workorder #: 1302083B

Dear Ms. Elizabeth Kunkel

The following report includes the data for the above referenced project for sample(s) received on 2/5/2013 at Air Toxics Ltd.

The data and associated QC analyzed by Modified ASTM D-1946 are compliant with the project requirements or laboratory criteria with the exception of the deviations noted in the attached case narrative.

Thank you for choosing Air Toxics Ltd. for your air analysis needs. Air Toxics Ltd. is committed to providing accurate data of the highest quality. Please feel free to contact the Project Manager: Kelly Buettner at 916-985-1000 if you have any questions regarding the data in this report.

Regards,

Kelly Buettner

Project Manager

REVIEWED
ON
3/22/13

eurofins | Air Toxics

# WORK ORDER #: 1302083B

Work Order Summary

| | | | |
|---|---|---|---|
| **CLIENT:** | Ms. Elizabeth Kunkel<br>URS Corporation<br>1001 Highlands Plaza Dr. West<br>Suite 300<br>St. Louis, MO 63110 | **BILL TO:** | Accounts Payable Austin<br>URS Corporation<br>P.O. BOX 203970<br>Austin, TX 78720-1088 |
| **PHONE:** | 314-743-4179 | **P.O. #** | 21562735.00013 |
| **FAX:** | | **PROJECT #** | 21562850.04001 Roxana Soil Vapor |
| **DATE RECEIVED:** | 02/05/2013 | **CONTACT:** | Kelly Buettner |
| **DATE COMPLETED:** | 02/19/2013 | | |

| FRACTION # | NAME | TEST | RECEIPT VAC./PRES. | FINAL PRESSURE |
|---|---|---|---|---|
| 01A | VMP-48-5-020113 | Modified ASTM D-1946 | 6.4 "Hg | 15 psi |
| 02A | VMP-48-10-020113 | Modified ASTM D-1946 | 7.2 "Hg | 15 psi |
| 03A | VMP-48-20-020113 | Modified ASTM D-1946 | 6.2 "Hg | 15 psi |
| 04A | VMP-48-30-020113 | Modified ASTM D-1946 | 6.8 "Hg | 15 psi |
| 05A | VMP-48-30-020113-DUP | Modified ASTM D-1946 | 6.6 "Hg | 15 psi |
| 06A | VMP-50-10-020113 | Modified ASTM D-1946 | 8.0 "Hg | 15 psi |
| 07A | VMP-51-5-020113 | Modified ASTM D-1946 | 7.8 "Hg | 15 psi |
| 08A | VMP-51-10-020113 | Modified ASTM D-1946 | 8.0 "Hg | 15 psi |
| 09A(cancelled) | VMP-51-20-020113 | Modified ASTM D-1946 | 4.8 "Hg | 15 psi |
| 10A | VMP-52-5-020413 | Modified ASTM D-1946 | 6.0 "Hg | 15 psi |
| 11A | VMP-52-10-020413 | Modified ASTM D-1946 | 4.8 "Hg | 15 psi |
| 12A | VMP-52-20-020413 | Modified ASTM D-1946 | 7.4 "Hg | 15 psi |
| 13A | VMP-52-20-020413-DUP | Modified ASTM D-1946 | 6.4 "Hg | 15 psi |
| 14A | VMP-52-30-020413 | Modified ASTM D-1946 | 8.4 "Hg | 15 psi |
| 15A | VMP-51-30-020413 | Modified ASTM D-1946 | 9.0 "Hg | 15 psi |
| 16A | VMP-51-30-020413-DUP | Modified ASTM D-1946 | 8.4 "Hg | 15 psi |
| 17A | Lab Blank | Modified ASTM D-1946 | NA | NA |
| 17B | Lab Blank | Modified ASTM D-1946 | NA | NA |
| 18A | LCS | Modified ASTM D-1946 | NA | NA |
| 18AA | LCSD | Modified ASTM D-1946 | NA | NA |

CERTIFIED BY: Heidi Hayes DATE: 02/19/13

Technical Director

Certification numbers: AZ Licensure AZ0775, CA NELAP - 12282CA, NY NELAP - 11291, TX NELAP - T104704434-12-4, UT NELAP CA009332012-3, WA NELAP - C935
Name of Accrediting Agency: NELAP/ORELAP (Oregon Environmental Laboratory Accreditation Program)
Accreditation number: CA300005, Effective date: 10/18/2012, Expiration date: 10/17/2013.
Eurofins Air Toxics Ltd. certifies that the test results contained in this report meet all requirements of the NELAC standards

This report shall not be reproduced, except in full, without the written approval of Eurofins Air Toxics, Inc.

180 BLUE RAVINE ROAD, SUITE B FOLSOM, CA - 9563
(916) 985-1000 . (800) 985-5955 . FAX (916) 985-1020

**LABORATORY NARRATIVE**
**Modified ASTM D-1946**
**URS Corporation**
**Workorder# 1302083B**

Sixteen 1 Liter Summa Canister samples were received on February 05, 2013. The laboratory performed analysis via Modified ASTM Method D-1946 for Methane and fixed gases in air using GC/FID or GC/TCD. The method involves direct injection of 1.0 mL of sample.

On the analytical column employed for this analysis, Oxygen coelutes with Argon. The corresponding peak is quantitated as Oxygen.

Since Nitrogen is used to pressurize samples, the reported Nitrogen values are calculated by adding all the sample components and subtracting from 100%.

Method modifications taken to run these samples are summarized in the table below. Specific project requirements may over-ride the ATL modifications.

| *Requirement* | *ASTM D-1946* | *ATL Modifications* |
|---|---|---|
| Calibration | A single point calibration is performed using a reference standard closely matching the composition of the unknown. | A 3-point calibration curve is performed. Quantitation is based on a daily calibration standard which may or may not resemble the composition of the associated samples. |
| Reference Standard | The composition of any reference standard must be known to within 0.01 mol % for any component. | The standards used by ATL are blended to a >/= 95% accuracy. |
| Sample Injection Volume | Components whose concentrations are in excess of 5 % should not be analyzed by using sample volumes greater than 0.5 mL. | The sample container is connected directly to a fixed volume sample loop of 1.0 mL on the GC. Linear range is defined by the calibration curve. Bags are loaded by vacuum. |
| Normalization | Normalize the mole percent values by multiplying each value by 100 and dividing by the sum of the original values. The sum of the original values should not differ from 100% by more than 1.0%. | Results are not normalized. The sum of the reported values can differ from 100% by as much as 15%, either due to analytical variability or an unusual sample matrix. |
| Precision | Precision requirements established at each concentration level. | Duplicates should agree within 25% RPD for detections > 5 X's the RL. |

**Receiving Notes**

There were no receiving discrepancies.

**Analytical Notes**

The Summa canister for sample VMP-51-20-020113 was leaking at the time of ASTM D-1946 analysis. The client was notified and the analysis was cancelled.

As per project specific client request the laboratory has reported estimated values for target compound hits that are below the Reporting Limit but greater than the Method Detection Limit. Concentrations that are below the level at which the canister was certified may be false positives.

The reporting limit for Carbon Monoxide was raised from 0.010% to 0.050%.

**Definition of Data Qualifying Flags**

Seven qualifiers may have been used on the data analysis sheets and indicate as follows:
B - Compound present in laboratory blank greater than reporting limit.
J - Estimated value.
E - Exceeds instrument calibration range.
S - Saturated peak.
Q - Exceeds quality control limits.
U - Compound analyzed for but not detected above the detection limit.
M - Reported value may be biased due to apparent matrix interferences.
File extensions may have been used on the data analysis sheets and indicates as follows:
a-File was requantified
b-File was quantified by a second column and detector
r1-File was requantified for the purpose of reissue

eurofins | Air Toxics

# Summary of Detected Compounds
# NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1946

**Client Sample ID: VMP-48-5-020113**

**Lab ID#: 1302083B-01A**

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.26 | 21 |
| Nitrogen | 0.26 | 79 |
| Methane | 0.00026 | 0.00023 J |
| Carbon Dioxide | 0.026 | 0.33 |
| Helium | 0.13 | 0.022 J |

**Client Sample ID: VMP-48-10-020113**

**Lab ID#: 1302083B-02A**

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.27 | 19 |
| Nitrogen | 0.27 | 78 |
| Methane | 0.00027 | 0.000057 J |
| Carbon Dioxide | 0.027 | 2.7 |

**Client Sample ID: VMP-48-20-020113**

**Lab ID#: 1302083B-03A**

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.26 | 18 |
| Nitrogen | 0.26 | 78 |
| Methane | 0.00026 | 0.000044 J |
| Carbon Dioxide | 0.026 | 4.2 |

**Client Sample ID: VMP-48-30-020113**

**Lab ID#: 1302083B-04A**

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.26 | 1.6 |
| Nitrogen | 0.26 | 87 |
| Methane | 0.00026 | 0.0017 |
| Carbon Dioxide | 0.026 | 11 |

eurofins | Air Toxics

# Summary of Detected Compounds
# NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1946

**Client Sample ID: VMP-48-30-020113**

**Lab ID#: 1302083B-04A**

| | | |
|---|---|---|
| Helium | 0.13 | 0.029 J |

**Client Sample ID: VMP-48-30-020113-DUP**

**Lab ID#: 1302083B-05A**

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.26 | 1.7 |
| Nitrogen | 0.26 | 87 |
| Methane | 0.00026 | 0.0017 |
| Carbon Dioxide | 0.026 | 11 |
| Helium | 0.13 | 0.025 J |

**Client Sample ID: VMP-50-10-020113**

**Lab ID#: 1302083B-06A**

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.28 | 16 |
| Nitrogen | 0.28 | 80 |
| Methane | 0.00028 | 0.000044 J |
| Carbon Dioxide | 0.028 | 4.0 |

**Client Sample ID: VMP-51-5-020113**

**Lab ID#: 1302083B-07A**

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.27 | 20 |
| Nitrogen | 0.27 | 80 |
| Methane | 0.00027 | 0.000057 J |
| Carbon Dioxide | 0.027 | 0.33 |

**Client Sample ID: VMP-51-10-020113**

**Lab ID#: 1302083B-08A**

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|

eurofins | Air Toxics

# Summary of Detected Compounds
# NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1946

**Client Sample ID: VMP-51-10-020113**

**Lab ID#: 1302083B-08A**

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.28 | 20 |
| Nitrogen | 0.28 | 79 |
| Carbon Dioxide | 0.028 | 0.72 |

**Client Sample ID: VMP-52-5-020413**

**Lab ID#: 1302083B-10A**

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.25 | 18 |
| Nitrogen | 0.25 | 81 |
| Methane | 0.00025 | 0.00031 |
| Carbon Dioxide | 0.025 | 0.98 |

**Client Sample ID: VMP-52-10-020413**

**Lab ID#: 1302083B-11A**

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.24 | 15 |
| Nitrogen | 0.24 | 82 |
| Methane | 0.00024 | 0.00068 |
| Carbon Dioxide | 0.024 | 2.6 |

**Client Sample ID: VMP-52-20-020413**

**Lab ID#: 1302083B-12A**

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.27 | 13 |
| Nitrogen | 0.27 | 81 |
| Methane | 0.00027 | 0.00073 |
| Carbon Dioxide | 0.027 | 6.0 |
| Helium | 0.13 | 0.031 J |

eurofins | Air Toxics

# Summary of Detected Compounds
# NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1946

**Client Sample ID: VMP-52-20-020413-DUP**

**Lab ID#: 1302083B-13A**

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.26 | 13 |
| Nitrogen | 0.26 | 81 |
| Methane | 0.00026 | 0.00074 |
| Carbon Dioxide | 0.026 | 6.1 |
| Helium | 0.13 | 0.036 J |

**Client Sample ID: VMP-52-30-020413**

**Lab ID#: 1302083B-14A**

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.28 | 12 |
| Nitrogen | 0.28 | 81 |
| Methane | 0.00028 | 0.0014 |
| Carbon Dioxide | 0.028 | 7.0 |

**Client Sample ID: VMP-51-30-020413**

**Lab ID#: 1302083B-15A**

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.29 | 18 |
| Nitrogen | 0.29 | 78 |
| Methane | 0.00029 | 0.000024 J |
| Carbon Dioxide | 0.029 | 4.0 |
| Helium | 0.14 | 0.036 J |

**Client Sample ID: VMP-51-30-020413-DUP**

**Lab ID#: 1302083B-16A**

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.28 | 18 |
| Nitrogen | 0.28 | 78 |
| Methane | 0.00028 | 0.000028 J |

eurofins | Air Toxics

## Summary of Detected Compounds
## NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1946

**Client Sample ID: VMP-51-30-020413-DUP**

**Lab ID#: 1302083B-16A**

| | | |
|---|---|---|
| Carbon Dioxide | 0.028 | 3.9 |
| Helium | 0.14 | 0.034 J |

eurofins | Air Toxics

**Client Sample ID: VMP-48-5-020113**

**Lab ID#: 1302083B-01A**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1946**

| | | | |
|---|---|---|---|
| **File Name:** | **9021407** | **Date of Collection:** | **2/1/13 11:20:00 AM** |
| **Dil. Factor:** | **2.57** | **Date of Analysis:** | **2/14/13 10:38 AM** |

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.26 | 21 |
| Nitrogen | 0.26 | 79 |
| Carbon Monoxide | 0.13 | Not Detected |
| Methane | 0.00026 | 0.00023 J |
| Carbon Dioxide | 0.026 | 0.33 |
| Ethane | 0.0026 | Not Detected |
| Ethene | 0.0026 | Not Detected |
| Helium | 0.13 | 0.022 J |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

eurofins | Air Toxics

**Client Sample ID: VMP-48-10-020113**

**Lab ID#: 1302083B-02A**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1946**

| | | | |
|---|---|---|---|
| **File Name:** | **9021408** | **Date of Collection:** | **2/1/13 1:43:00 PM** |
| **Dil. Factor:** | **2.66** | **Date of Analysis:** | **2/14/13 11:01 AM** |

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.27 | 19 |
| Nitrogen | 0.27 | 78 |
| Carbon Monoxide | 0.13 | Not Detected |
| Methane | 0.00027 | 0.000057 J |
| Carbon Dioxide | 0.027 | 2.7 |
| Ethane | 0.0027 | Not Detected |
| Ethene | 0.0027 | Not Detected |
| Helium | 0.13 | Not Detected |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

eurofins | Air Toxics

**Client Sample ID: VMP-48-20-020113**

**Lab ID#: 1302083B-03A**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1946**

| | | | |
|---|---|---|---|
| **File Name:** | **9021409** | **Date of Collection:** | **2/1/13 2:35:00 PM** |
| **Dil. Factor:** | **2.55** | **Date of Analysis:** | **2/14/13 11:26 AM** |

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.26 | 18 |
| Nitrogen | 0.26 | 78 |
| Carbon Monoxide | 0.13 | Not Detected |
| Methane | 0.00026 | 0.000044 J |
| Carbon Dioxide | 0.026 | 4.2 |
| Ethane | 0.0026 | Not Detected |
| Ethene | 0.0026 | Not Detected |
| Helium | 0.13 | Not Detected |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

eurofins | Air Toxics

**Client Sample ID: VMP-48-30-020113**

**Lab ID#: 1302083B-04A**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1946**

| | | | |
|---|---|---|---|
| **File Name:** | **9021410** | **Date of Collection:** | **2/1/13 3:31:00 PM** |
| **Dil. Factor:** | **2.61** | **Date of Analysis:** | **2/14/13 12:01 PM** |

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.26 | 1.6 |
| Nitrogen | 0.26 | 87 |
| Carbon Monoxide | 0.13 | Not Detected |
| Methane | 0.00026 | 0.0017 |
| Carbon Dioxide | 0.026 | 11 |
| Ethane | 0.0026 | Not Detected |
| Ethene | 0.0026 | Not Detected |
| Helium | 0.13 | 0.029 J |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

eurofins | Air Toxics

**Client Sample ID: VMP-48-30-020113-DUP**

**Lab ID#: 1302083B-05A**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1946**

| | | | |
|---|---|---|---|
| **File Name:** | **9021411** | **Date of Collection:** | **2/1/13 3:31:00 PM** |
| **Dil. Factor:** | **2.59** | **Date of Analysis:** | **2/14/13 12:24 PM** |

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.26 | 1.7 |
| Nitrogen | 0.26 | 87 |
| Carbon Monoxide | 0.13 | Not Detected |
| Methane | 0.00026 | 0.0017 |
| Carbon Dioxide | 0.026 | 11 |
| Ethane | 0.0026 | Not Detected |
| Ethene | 0.0026 | Not Detected |
| Helium | 0.13 | 0.025 J |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

eurofins | Air Toxics

**Client Sample ID: VMP-50-10-020113**

**Lab ID#: 1302083B-06A**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1946**

| | | | |
|---|---|---|---|
| **File Name:** | **9021412** | **Date of Collection:** | **2/1/13 1:30:00 PM** |
| **Dil. Factor:** | **2.76** | **Date of Analysis:** | **2/14/13 12:55 PM** |

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.28 | 16 |
| Nitrogen | 0.28 | 80 |
| Carbon Monoxide | 0.14 | Not Detected |
| Methane | 0.00028 | 0.000044 J |
| Carbon Dioxide | 0.028 | 4.0 |
| Ethane | 0.0028 | Not Detected |
| Ethene | 0.0028 | Not Detected |
| Helium | 0.14 | Not Detected |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

eurofins | Air Toxics

**Client Sample ID: VMP-51-5-020113**

**Lab ID#: 1302083B-07A**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1946**

| | | | |
|---|---|---|---|
| **File Name:** | **9021413** | **Date of Collection:** | **2/1/13 2:13:00 PM** |
| **Dil. Factor:** | **2.73** | **Date of Analysis:** | **2/14/13 01:20 PM** |

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.27 | 20 |
| Nitrogen | 0.27 | 80 |
| Carbon Monoxide | 0.14 | Not Detected |
| Methane | 0.00027 | 0.000057 J |
| Carbon Dioxide | 0.027 | 0.33 |
| Ethane | 0.0027 | Not Detected |
| Ethene | 0.0027 | Not Detected |
| Helium | 0.14 | Not Detected |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

eurofins | Air Toxics

**Client Sample ID: VMP-51-10-020113**

**Lab ID#: 1302083B-08A**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1946**

| | | | |
|---|---|---|---|
| **File Name:** | **9021414** | **Date of Collection:** | **2/1/13 3:45:00 PM** |
| **Dil. Factor:** | **2.76** | **Date of Analysis:** | **2/14/13 01:42 PM** |

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.28 | 20 |
| Nitrogen | 0.28 | 79 |
| Carbon Monoxide | 0.14 | Not Detected |
| Methane | 0.00028 | Not Detected |
| Carbon Dioxide | 0.028 | 0.72 |
| Ethane | 0.0028 | Not Detected |
| Ethene | 0.0028 | Not Detected |
| Helium | 0.14 | Not Detected |

**Container Type: 1 Liter Summa Canister**

eurofins | Air Toxics

**Client Sample ID: VMP-52-5-020413**

**Lab ID#: 1302083B-10A**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1946**

| | | | |
|---|---|---|---|
| **File Name:** | **9021415** | **Date of Collection:** | **2/4/13 9:47:00 AM** |
| **Dil. Factor:** | **2.52** | **Date of Analysis:** | **2/14/13 02:15 PM** |

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.25 | 18 |
| Nitrogen | 0.25 | 81 |
| Carbon Monoxide | 0.13 | Not Detected |
| Methane | 0.00025 | 0.00031 |
| Carbon Dioxide | 0.025 | 0.98 |
| Ethane | 0.0025 | Not Detected |
| Ethene | 0.0025 | Not Detected |
| Helium | 0.13 | Not Detected |

**Container Type: 1 Liter Summa Canister**

eurofins | Air Toxics

**Client Sample ID: VMP-52-10-020413**

**Lab ID#: 1302083B-11A**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1946**

| | | | |
|---|---|---|---|
| **File Name:** | **9021416** | **Date of Collection:** | **2/4/13 10:36:00 AM** |
| **Dil. Factor:** | **2.40** | **Date of Analysis:** | **2/14/13 02:44 PM** |

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.24 | 15 |
| Nitrogen | 0.24 | 82 |
| Carbon Monoxide | 0.12 | Not Detected |
| Methane | 0.00024 | 0.00068 |
| Carbon Dioxide | 0.024 | 2.6 |
| Ethane | 0.0024 | Not Detected |
| Ethene | 0.0024 | Not Detected |
| Helium | 0.12 | Not Detected |

**Container Type: 1 Liter Summa Canister**

eurofins | Air Toxics

**Client Sample ID: VMP-52-20-020413**

**Lab ID#: 1302083B-12A**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1946**

| | | | |
|---|---|---|---|
| **File Name:** | **9021417** | **Date of Collection:** | **2/4/13 11:22:00 AM** |
| **Dil. Factor:** | **2.68** | **Date of Analysis:** | **2/14/13 03:08 PM** |

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.27 | 13 |
| Nitrogen | 0.27 | 81 |
| Carbon Monoxide | 0.13 | Not Detected |
| Methane | 0.00027 | 0.00073 |
| Carbon Dioxide | 0.027 | 6.0 |
| Ethane | 0.0027 | Not Detected |
| Ethene | 0.0027 | Not Detected |
| Helium | 0.13 | 0.031 J |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

eurofins | Air Toxics

**Client Sample ID: VMP-52-20-020413-DUP**

**Lab ID#: 1302083B-13A**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1946**

| | | | |
|---|---|---|---|
| **File Name:** | **9021418** | **Date of Collection:** | **2/4/13 11:22:00 AM** |
| **Dil. Factor:** | **2.57** | **Date of Analysis:** | **2/14/13 03:32 PM** |

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.26 | 13 |
| Nitrogen | 0.26 | 81 |
| Carbon Monoxide | 0.13 | Not Detected |
| Methane | 0.00026 | 0.00074 |
| Carbon Dioxide | 0.026 | 6.1 |
| Ethane | 0.0026 | Not Detected |
| Ethene | 0.0026 | Not Detected |
| Helium | 0.13 | 0.036 J |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

eurofins | Air Toxics

**Client Sample ID: VMP-52-30-020413**

**Lab ID#: 1302083B-14A**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1946**

| | | | |
|---|---|---|---|
| **File Name:** | **9021419** | **Date of Collection:** | **2/4/13 12:04:00 PM** |
| **Dil. Factor:** | **2.81** | **Date of Analysis:** | **2/14/13 03:53 PM** |

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.28 | 12 |
| Nitrogen | 0.28 | 81 |
| Carbon Monoxide | 0.14 | Not Detected |
| Methane | 0.00028 | 0.0014 |
| Carbon Dioxide | 0.028 | 7.0 |
| Ethane | 0.0028 | Not Detected |
| Ethene | 0.0028 | Not Detected |
| Helium | 0.14 | Not Detected |

**Container Type: 1 Liter Summa Canister**

eurofins | Air Toxics

**Client Sample ID: VMP-51-30-020413**

**Lab ID#: 1302083B-15A**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1946**

| | | | |
|---|---|---|---|
| **File Name:** | **9021420** | **Date of Collection:** | **2/4/13 2:15:00 PM** |
| **Dil. Factor:** | **2.89** | **Date of Analysis:** | **2/14/13 04:15 PM** |

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.29 | 18 |
| Nitrogen | 0.29 | 78 |
| Carbon Monoxide | 0.14 | Not Detected |
| Methane | 0.00029 | 0.000024 J |
| Carbon Dioxide | 0.029 | 4.0 |
| Ethane | 0.0029 | Not Detected |
| Ethene | 0.0029 | Not Detected |
| Helium | 0.14 | 0.036 J |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

eurofins | Air Toxics

**Client Sample ID: VMP-51-30-020413-DUP**

**Lab ID#: 1302083B-16A**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1946**

| | | | |
|---|---|---|---|
| **File Name:** | **9021421** | **Date of Collection:** | **2/4/13 2:15:00 PM** |
| **Dil. Factor:** | **2.81** | **Date of Analysis:** | **2/14/13 05:08 PM** |

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.28 | 18 |
| Nitrogen | 0.28 | 78 |
| Carbon Monoxide | 0.14 | Not Detected |
| Methane | 0.00028 | 0.000028 J |
| Carbon Dioxide | 0.028 | 3.9 |
| Ethane | 0.0028 | Not Detected |
| Ethene | 0.0028 | Not Detected |
| Helium | 0.14 | 0.034 J |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

eurofins | Air Toxics

**Client Sample ID: Lab Blank**

**Lab ID#: 1302083B-17A**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1946**

| | | | |
|---|---|---|---|
| **File Name:** | **9021405a** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 2/14/13 09:46 AM** | |

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.10 | 0.036 J |
| Nitrogen | 0.10 | 0.089 J |
| Carbon Monoxide | 0.010 | Not Detected |
| Methane | 0.00010 | Not Detected |
| Carbon Dioxide | 0.010 | Not Detected |
| Ethane | 0.0010 | Not Detected |
| Ethene | 0.0010 | Not Detected |

J = Estimated value.

**Container Type: NA - Not Applicable**

eurofins | Air Toxics

**Client Sample ID: Lab Blank**

**Lab ID#: 1302083B-17B**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1946**

| | | | |
|---|---|---|---|
| **File Name:** | **9021403b** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 2/14/13 08:54 AM** | |

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Helium | 0.050 | Not Detected |

**Container Type: NA - Not Applicable**

eurofins | Air Toxics

**Client Sample ID: LCS**

**Lab ID#: 1302083B-18A**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1946**

| | | | |
|---|---|---|---|
| **File Name:** | **9021402** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 2/14/13 08:22 AM** | |

| Compound | %Recovery |
|---|---|
| Oxygen | 102 |
| Nitrogen | 101 |
| Carbon Monoxide | 95 |
| Methane | 98 |
| Carbon Dioxide | 100 |
| Ethane | 100 |
| Ethene | 96 |
| Helium | 101 |

**Container Type: NA - Not Applicable**

eurofins | Air Toxics

**Client Sample ID: LCSD**

**Lab ID#: 1302083B-18AA**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1946**

| | | | |
|---|---|---|---|
| **File Name:** | **9021425** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 2/14/13 07:20 PM** | |

| Compound | %Recovery |
|---|---|
| Oxygen | 98 |
| Nitrogen | 100 |
| Carbon Monoxide | 99 |
| Methane | 98 |
| Carbon Dioxide | 101 |
| Ethane | 99 |
| Ethene | 96 |
| Helium | 101 |

**Container Type: NA - Not Applicable**

# Shell Oil Products Chain Of Custody Record

URS

**Air Toxics LTD.**
**Project Name: Roxana Soil Vapor**
**Project # 21562850.04001**
**Lab Vendor #**

Please Check Appropriate Box: ☑ ENV. SERVICES ☐ MOTIVA RETAIL ☐ SHELL RETAIL ☐ MOTIVA SD&CM ☐ CONSULTANT ☐ LUBES ☐ SHELL PIPELINE ☐ OTHER

Print Bill To Contact Name: Robert Mooshegian

INCIDENT # (ENV SERVICES): 9 7 2 1 6 6 4 0 ☐ CHECK IF NO INCIDENT # APPLIES

PO #:

SAP #: 3 4 0 0 8 1

DATE: 02/04/13

PAGE: 1 of 2

SAMPLING COMPANY: URS CORPORATION

LOG CODE:

SITE ADDRESS: Street and City: 900 SOUTH CENTRAL AVE -- ROXANA

State: IL

GLOBAL ID NO.:

ADDRESS: 1001 HIGHLANDS PLAZA DRIVE WEST - SUITE 300; ST. LOUIS, MO 63110

CONSULTANT PROJECT NAME#: Roxana Soil Vapor

LABORATORY ADDRESS: Air Toxics, LTD 180 Blue Ravine Road, Suite B, Folsom, CA 95630-4719

TELEPHONE: FAX: 314-429-0462

BILL TO CONTACT E-MAIL: Robert.Mooshegian@urs.com

CONSULTANT PM: Elizabeth Kunkel, URS, St. Louis

PHONE NO.: 314-743-4179

E-MAIL: Elizabeth.Kunkel@URSCorp.com

C. Williams, L. Rathnow, S. Jansen, M. Mittermeyer, J. Staettar, B. Lehan, M. Currier

TURNAROUND TIME (CALENDAR DAYS): ☑ STANDARD (14 DAY) ☐ 5 DAYS ☐ 3 DAYS ☐ 2 DAYS ☐ 24 HOURS ☐ RESULTS NEEDED ON WEEKEND

REQUESTED ANALYSIS

☐ LA - RWQCB REPORT FORMAT ☑ UST AGENCY:

DELIVERABLES: ☐ LEVEL 1 ☐ LEVEL 2 ☐ LEVEL 3 ☑ LEVEL 4 ☐ OTHER (SPECIFY)

☑ SHELL CONTRACT RATE APPLIES
☐ STATE REIMBURSEMENT RATE APPLIES
☐ EDD NOT NEEDED
☑ RECEIPT VERIFICATION REQUESTED

Turn Around Time: ☑ Normal ☐ Rush ☐ Specify

Lab Use Only
Pressurized by:
Date:
Pressurization Gas: $N_2$ He

| LAB USE ONLY | Field Sample Identification | SAMPLING DATE | SAMPLING TIME | Canister Number | Canister Pressure/Vacuum Initial | Final | Receipt | Final (psi) | Modified TO-15 + Butane & Isopentane | ASTM D-1946 + Helium |
|---|---|---|---|---|---|---|---|---|---|---|
| 01A | VMP-48-5-020113 | 02/01/13 | 1050-1120 | 37298 | -29.5 | -8.5 | | | X | X |
| 02A | VMP-48-10-020113 | 02/01/13 | 1313-1343 | 2180 | -29.5 | -9 | | | X | X |
| 03A | VMP-48-20-020113 | 02/01/13 | 1405-1435 | 37770 | -30 | -8 | | | X | X |
| 04A | VMP-48-30-020113 | 02/01/13 | 1501-1531 | 34573 | -30 | -8 | | | X | X |
| 05A | VMP-48-30-020113-DUP | 02/01/13 | 1501-1531 | 36473 | -30 | -7.5 | | | X | X |
| 06A | VMP-50-10-020113 | 02/01/13 | 1259-1330 | 35634 | -30 | -10.5 | | | X | X |
| 07A | VMP-51-5-020113 | 02/01/13 | 1349-1413 | 37385 | -30 | -10 | | | X | X |
| 08A | VMP-51-10-020113 | 02/01/13 | 1514-1545 | 37427 | -30 | -10.5 | | | X | X |
| 09A | VMP-51-20-020113 | 02/01/13 | 1428-1458 | 35624 | -30 | -8.5 | | | X | X |
| | | | | | | | | | X | X |

ADDITIONAL NOTES:

- 14 day hold time
- Report results between MDL and RL
- Level IV ECVP

| Relinquished by: (Signature) | Received by: (Signature) | Date | Time |
|---|---|---|---|
| | FEDEX | 2/4/13 | 1830 |
| Relinquished by: (Signature) | Received by: (Signature) | Date | Time |
| | | 2/5/13 | 0925 |
| Relinquished by: (Signature) | Received by: (Signature) | Date | Time |
| | | | |

Custody Seal Intact? (Y) N None Temp in IA

Fedex

05/2008 Revision

1302083

# Shell Oil Products Chain Of Custody Record

URS

**Air Toxics LTD.**
**Project Name: Roxana Soil Vapor**
**Project # 21562850.04001**
Lab Vendor #

Please Check Appropriate Box: ☑ ENV. SERVICES ☐ MOTIVA RETAIL ☐ SHELL RETAIL ☐ MOTIVA SD&CH ☐ CONSULTANT ☐ LUBES ☐ SHELL PIPELINE ☐ OTHER

Print Bill To Contact Name: Robert Mooshegian

INCIDENT # (ENV SERVICES): 9 7 2 1 8 6 4 0 ☐ CHECK IF NO INCIDENT # APPLIES

DATE: 02/04/13

PAGE: 2 of 2

PO. #

SAP #: 3 4 0 0 8 1

SAMPLING COMPANY: URS CORPORATION

LOG CODE:

SITE ADDRESS: Street and City: 900 SOUTH CENTRAL AVE – ROXANA

State: IL

GLOBAL ID NO.:

ADDRESS: 1001 HIGHLANDS PLAZA DRIVE WEST - SUITE 300; ST LOUIS MO 63110

EDF DELIVERABLE TO (Name, Company, Office Location): Elizabeth Kunkel, URS, St. Louis

PHONE NO.: 314-743-4179

E-MAIL: Elizabeth.Kunkel@URSCorp.com

CONSULTANT PROJECT NAME/#: Roxana Soil Vapor

LABORATORY ADDRESS: Air Toxics, LTD 180 Blue Ravine Road Suite B, Folsom, CA 95630-4719

TELEPHONE:

FAX: 314-429-0452

Bill To Contact E-MAIL: Robert.Mooshegian@urs.com

C. Williams, L. Rathnow, S. Jansen, M. Mittermeyer, J. Stoetter, B. Lehan, M. Currier

TURNAROUND TIME (CALENDAR DAYS): ☑ STANDARD (14 DAY) ☐ 5 DAYS ☐ 3 DAYS ☐ 2 DAYS ☐ 24 HOURS ☐ RESULTS NEEDED ON WEEKEND

REQUESTED ANALYSIS

☐ LA - RWQCB REPORT FORMAT ☑ UST AGENCY:

DELIVERABLES: ☐ LEVEL 1 ☐ LEVEL 2 ☐ LEVEL 3 ☑ LEVEL 4 ☐ OTHER (SPECIFY)

☑ SHELL CONTRACT RATE APPLIES
☐ STATE REIMBURSEMENT RATE APPLIES
☐ EDD NOT NEEDED
☑ RECEIPT VERIFICATION REQUESTED

Turn Around Time: ☑ Normal ☐ Rush Specify

*Lab Use Only*
Pressurized by:
Date:
Pressurization Gas: $N_2$ He

ADDITIONAL NOTES:
- 14 day hold time
- Report results between MDL and RL
- Level IV ECVP

| Lab Use Only | Field Sample Identification | SAMPLING DATE | SAMPLING TIME | Canister Number | Canister Pressure/Vacuum Initial | Final | Receipt | Final (psi) | Modified TO-15 + Butane & Isopentane | ASTM D-1946 + Helium |
|---|---|---|---|---|---|---|---|---|---|---|
| 08 | VMP-52-5-020413 | 02/04/13 | 0917-0947 | 100188 | -30 | -8 | | | X | X |
| 09 | VMP-52-10-020413 | 02/04/13 | 1006-1036 | 37353 | -30 | -7 | | | X | X |
| 12 | VMP-52-20-020413 | 02/04/13 | 1052-1122 | 33645 | -30 | -8.5 | | | X | X |
| 11 | VMP-52-20-020413-DUP | 02/04/13 | 1052-1122 | 37429 | -30 | -7.5 | | | X | X |
| 10 | VMP-52-30-020413 | 02/04/13 | 1134-1204 | 34137 | -29 | -9.5 | | | X | X |
| 07 | VMP-51-30-020413 | 02/04/13 | 1344-1415 | 31784 | -30 | -10 | | | X | X |
| 06 | VMP-51-30-020413-DUP | 02/04/13 | 1344-1415 | 37379 | -30 | -10 | | | X | X |
| | | | | | | | | | X | X |
| | | | | | | | | | X | X |
| | | | | | | | | | X | X |

Relinquished by: (Signature)

Received by: (Signature) FEDEX — Date: 2/4/13 — Time: 1830

Relinquished by: (Signature)

Received by: (Signature) — Custody Seal Intact? (Y) N None Temp. N/A — Date: 2/5/13 — Time: 0925

Relinquished by: (Signature)

Received by: (Signature) Fedex — Date: — Time:

05/2008 Revision

# Roxana Soil Vapor Quarterly – 1st Quarter 2013 Data Review

**Laboratory SDG: 1302156A,B**

**Data Reviewer: Alan Fleisher**

**Peer Reviewer: Elizabeth Kunkel**

**Date Reviewed: 3/26/2013**

**Guidance: USEPA National Functional Guidelines for Superfund Organic Methods Data Review 2008**

| Sample Identification | Sample Identification |
|---|---|
| VMP-2-8.5-020513 | VMP-6-10-020513 |
| VMP-6-31.5-020513 | VMP-6-39-020513 |
| VMP-15-5-020513 | VMP-21-10-020513 |
| VMP-21-10-020513-Dup | VMP-21-25-020513 |
| VMP-21-25-020513-Dup | VMP-21-33-020513 |
| VMP-29-10-020613 | VMP-29-10-020613 |
| VMP-29-20-020613 | VMP-29-30-020613 |
| VMP-30-10-020613 | VMP-30-20-020613 |
| VMP-30-30-020613 | VMP-32-5-020513 |
| VMP-32-10-020513 | VMP-32-20-020513 |
| VMP-53-5-020513 | VMP-53-10-020513 |
| VMP-53-10-020513-Dup | VMP-53-20-020513 |
| VMP-53-30-020513 | VMP-54-5-020613 |
| VMP-54-10-020613 | |

## 1.0 Data Package Completeness

*Were all items delivered as specified in the QAPP and COC as appropriate?*

Yes

## 2.0 Laboratory Case Narrative \ Cooler Receipt Form

*Were problems noted in the laboratory case narrative or cooler receipt form?*

Yes, the laboratory case narrative indicated samples VMP-29-30-020613 and VMP-30-30-020613 were diluted and re-analyzed to bring the highest level target analytes within the calibration range of the instrument. Results for the highest level target anlaytes were reported from the re-analysis diluted runs and the remaining compounds were reported from the original analyses. Although not indicated in the laboratory case narrative, analytes were detected in the method blank. These issues are addressed further in the appropriate sections below.

No issues or discrepancies were noted in the cooler receipt form.

## 3.0 Holding Times

*Were samples extracted/analyzed within applicable limits?*

Yes

## 4.0 Blank Contamination

*Were any analytes detected in the Blanks?*

Yes

| Blank ID | Parameter | Analyte | Concentration/ Amount |
|---|---|---|---|
| 1302156A-27A | TO-15 | Bromomethane | 0.30 ppbv / 1.2 µg/m$^3$ |
| 1302156A-27A | TO-15 | Freon 11 | 0.074 ppbv / 0.42 µg/m$^3$ |
| 1302156A-27A | TO-15 | Carbon disulfide | 0.49 ppbv / 1.5 µg/m$^3$ |
| 1302156A-27A | TO-15 | Methylene chloride | 0.19 ppbv / 0.66 µg/m$^3$ |
| 1302156A-27A | TO-15 | 2,2,4-Trimethylpentane | 0.053 ppbv / 0.25 µg/m$^3$ |
| 1302156A-27A | TO-15 | Toluene | 0.072 ppbv / 0.27 µg/m$^3$ |
| 1302156A-27A | TO-15 | trans-1,3-Dichloropropene | 0.16 ppbv / 0.74 µg/m$^3$ |
| 1302156A-27A | TO-15 | Tetrachloroethene | 0.13 ppbv / 0.89 µg/m$^3$ |
| 1302156A-27A | TO-15 | Chlorobenzene | 0.11 ppbv / 0.50 µg/m$^3$ |
| 1302156A-27A | TO-15 | o-Xylene | 0.099 ppbv / 0.43 µg/m$^3$ |
| 1302156A-27A | TO-15 | Styrene | 0.098 ppbv / 0.42 µg/m$^3$ |
| 1302156A-27A | TO-15 | Cumene | 0.16 ppbv / 0.79 µg/m$^3$ |
| 1302156A-27A | TO-15 | 1,1,2,2-Tetrachloroethane | 0.15 ppbv / 1.0 µg/m$^3$ |
| 1302156A-27A | TO-15 | Propylbenzene | 0.18 ppbv / 0.87 µg/m$^3$ |
| 1302156A-27A | TO-15 | 4-Ethyltoluene | 0.15 ppbv / 0.74 µg/m$^3$ |
| 1302156A-27A | TO-15 | 1,3,5-Trimethylbenzene | 0.27 ppbv / 1.3 µg/m$^3$ |
| 1302156A-27A | TO-15 | 1,2,4-Trimethylbenzene | 0.21 ppbv / 1.0 µg/m$^3$ |
| 1302156A-27A | TO-15 | 1,3-Dichlorobenzene | 0.36 ppbv / 2.2 µg/m$^3$ |
| 1302156A-27A | TO-15 | 1,4-Dichlorobenzene | 0.34 ppbv / 2.0 µg/m$^3$ |
| 1302156A-27A | TO-15 | alpha-Chlorotoluene | 0.20 ppbv / 1.0 µg/m$^3$ |
| 1302156A-27A | TO-15 | 1,2-Dichlorobenzene | 0.32 ppbv / 1.9 µg/m$^3$ |
| 1302156A-27A | TO-15 | 1,2,4-Trichlorobenzene | 1.4 ppbv / 10 µg/m$^3$ |
| 1302156A-27A | TO-15 | Hexachlorobutadiene | 0.79 ppbv / 8.4 µg/m$^3$ |
| 1302156A-27B | TO-15 | Bromomethane | 0.39 ppbv / 1.5 µg/m$^3$ |
| 1302156A-27B | TO-15 | Freon 11 | 0.062 ppbv / 0.35 µg/m$^3$ |
| 1302156A-27B | TO-15 | Acetone | 0.33 ppbv / 0.78 µg/m$^3$ |
| 1302156A-27B | TO-15 | Carbon disulfide | 0.55 ppbv / 1.7 µg/m$^3$ |
| 1302156A-27B | TO-15 | Methylene chloride | 0.20 ppbv / 0.69 µg/m$^3$ |
| 1302156A-27B | TO-15 | trans-1,2-Dichloroethene | 0.12 ppbv / 0.48 µg/m$^3$ |
| 1302156A-27B | TO-15 | Tetrahydrofuran | 0.12 ppbv / 0.35 µg/m$^3$ |
| 1302156A-27B | TO-15 | 2,2,4-Trimethylpentane | 0.074 ppbv / 0.34 µg/m$^3$ |
| 1302156A-27B | TO-15 | cis-1,3-Dichloropropene | 0.12 ppbv / 0.56 µg/m$^3$ |
| 1302156A-27B | TO-15 | 4-Methyl-2-pentanone | 0.11 ppbv / 0.47 µg/m$^3$ |
| 1302156A-27B | TO-15 | Toluene | 0.11 ppbv / 0.41 µg/m$^3$ |
| 1302156A-27B | TO-15 | trans-1,3-Dichloropropene | 0.21 ppbv / 0.96 µg/m$^3$ |
| 1302156A-27B | TO-15 | Tetrachloroethene | 0.13 ppbv / 0.90 µg/m$^3$ |
| 1302156A-27B | TO-15 | 1,2-Dibromoethane (EDB) | 0.13 ppbv / 1.0 µg/m$^3$ |
| 1302156A-27B | TO-15 | Chlorobenzene | 0.16 ppbv / 0.74 µg/m$^3$ |
| 1302156A-27B | TO-15 | Ethyl benzene | 0.11 ppbv / 0.47 µg/m$^3$ |
| 1302156A-27B | TO-15 | o-Xylene | 0.13 ppbv / 0.58 µg/m$^3$ |
| 1302156A-27B | TO-15 | Styrene | 0.13 ppbv / 0.57 µg/m$^3$ |

| Blank ID | Parameter | Analyte | Concentration/ Amount |
|---|---|---|---|
| 1302156A-27B | TO-15 | Cumene | 0.17 ppbv / 0.82 µg/m$^3$ |
| 1302156A-27B | TO-15 | 1,1,2,2-Tetrachloroethane | 0.22 ppbv / 1.5 µg/m$^3$ |
| 1302156A-27B | TO-15 | Propylbenzene | 0.19 ppbv / 0.92 µg/m$^3$ |
| 1302156A-27B | TO-15 | 4-Ethyltoluene | 0.16 ppbv / 0.78 µg/m$^3$ |
| 1302156A-27B | TO-15 | 1,3,5-Trimethylbenzene | 0.27 ppbv / 1.3 µg/m$^3$ |
| 1302156A-27B | TO-15 | 1,2,4-Trimethylbenzene | 0.24 ppbv / 1.2 µg/m$^3$ |
| 1302156A-27B | TO-15 | 1,3-Dichlorobenzene | 0.47 ppbv / 2.8 µg/m$^3$ |
| 1302156A-27B | TO-15 | 1,4-Dichlorobenzene | 0.44 ppbv / 2.6 µg/m$^3$ |
| 1302156A-27B | TO-15 | alpha-Chlorotoluene | 0.29 ppbv / 1.5 µg/m$^3$ |
| 1302156A-27B | TO-15 | 1,2-Dichlorobenzene | 0.47 ppbv / 2.8 µg/m$^3$ |
| 1302156A-27B | TO-15 | 1,2,4-Trichlorobenzene | 1.7 ppbv / 12 µg/m$^3$ |
| 1302156A-27B | TO-15 | Hexachlorobutadiene | 1.1 ppbv / 12 µg/m$^3$ |
| 1302156B-27A | Natural Gases | Oxygen | 0.039% |
| 1302156B-27A | Natural Gases | Nitrogen | 0.051% |
| 1302156B-27C | Natural Gases | Nitrogen | 0.057% |

Qualifications due to blank contamination are included in the table below. Analytical data that were reported non-detect or at concentrations greater than five times (5X) the associated blank concentration did not require qualification.

| Sample ID | Parameter | Analyte | New Reporting Limit (RL) | Qualification |
|---|---|---|---|---|
| VMP-2-8.5-020513 | TO-15 | Freon 11 | - | **U** |
| VMP-2-8.5-020513 | TO-15 | Carbon disulfide | - | **U** |
| VMP-2-8.5-020513 | TO-15 | Methylene chloride | - | **U** |
| VMP-2-8.5-020513 | TO-15 | Tetrachloroethene | - | **U** |
| VMP-6-10-020513 | TO-15 | Freon 11 | - | **U** |
| VMP-6-10-020513 | TO-15 | Carbon disulfide | - | **U** |
| VMP-6-10-020513 | TO-15 | Methylene chloride | - | **U** |
| VMP-6-10-020513 | TO-15 | Toluene | - | **U** |
| VMP-6-10-020513 | TO-15 | Tetrachloroethene | - | **U** |
| VMP-6-10-020513 | TO-15 | 1,2,4-Trichlorobenzene | - | **U** |
| VMP-6-31.5-020513 | TO-15 | Freon 11 | - | **U** |
| VMP-6-31.5-020513 | TO-15 | Carbon disulfide | - | **U** |
| VMP-6-31.5-020513 | TO-15 | Toluene | - | **U** |
| VMP-6-31.5-020513 | TO-15 | Tetrachloroethene | - | **U** |
| VMP-6-39-020513 | TO-15 | Freon 11 | - | **U** |
| VMP-6-39-020513 | TO-15 | Carbon disulfide | - | **U** |
| VMP-6-39-020513 | TO-15 | Methylene chloride | - | **U** |
| VMP-6-39-020513 | TO-15 | Toluene | - | **U** |
| VMP-6-39-020513 | TO-15 | Tetrachloroethene | - | **U** |
| VMP-15-5-020513 | TO-15 | Carbon disulfide | - | **U** |
| VMP-15-5-020513 | TO-15 | Methylene chloride | - | **U** |
| VMP-15-5-020513 | TO-15 | Toluene | - | **U** |

| Sample ID | Parameter | Analyte | New Reporting Limit (RL) | Qualification |
|---|---|---|---|---|
| VMP-15-5-020513 | TO-15 | 4-Ethyltoluene | - | **U** |
| VMP-21-10-020513 | TO-15 | Freon 11 | - | **U** |
| VMP-21-10-020513 | TO-15 | Carbon disulfide | - | **U** |
| VMP-21-10-020513 | TO-15 | Methylene chloride | - | **U** |
| VMP-21-10-020513 | TO-15 | Toluene | - | **U** |
| VMP-21-10-020513-Dup | TO-15 | Freon 11 | - | **U** |
| VMP-21-10-020513-Dup | TO-15 | Carbon disulfide | - | **U** |
| VMP-21-10-020513-Dup | TO-15 | Methylene chloride | - | **U** |
| VMP-21-10-020513-Dup | TO-15 | Toluene | - | **U** |
| VMP-21-25-020513 | TO-15 | Freon 11 | - | **U** |
| VMP-21-25-020513 | TO-15 | Carbon disulfide | - | **U** |
| VMP-21-25-020513 | TO-15 | Methylene chloride | - | **U** |
| VMP-21-25-020513 | TO-15 | Toluene | - | **U** |
| VMP-21-25-020513-Dup | TO-15 | Freon 11 | - | **U** |
| VMP-21-25-020513-Dup | TO-15 | Carbon disulfide | - | **U** |
| VMP-21-25-020513-Dup | TO-15 | Methylene chloride | - | **U** |
| VMP-21-25-020513-Dup | TO-15 | Toluene | - | **U** |
| VMP-21-33-020513 | TO-15 | Carbon disulfide | - | **U** |
| VMP-21-33-020513 | TO-15 | Methylene chloride | - | **U** |
| VMP-29-10-020613 | TO-15 | 2,2,4-Trimethylpentane | - | **U** |
| VMP-29-10-020613 | TO-15 | Toluene | - | **U** |
| VMP-29-10-020613 | TO-15 | Tetrachloroethene | - | **U** |
| VMP-29-20-020613 | TO-15 | Freon 11 | - | **U** |
| VMP-29-20-020613 | TO-15 | Methylene chloride | - | **U** |
| VMP-29-20-020613 | TO-15 | Tetrachloroethene | - | **U** |
| VMP-29-20-020613 | TO-15 | Cumene | - | **U** |
| VMP-29-20-020613 | TO-15 | 4-Ethyltoluene | - | **U** |
| VMP-29-30-020613 | TO-15 | Freon 11 | - | **U** |
| VMP-29-30-020613 | TO-15 | Methylene chloride | - | **U** |
| VMP-29-30-020613 | TO-15 | 2,2,4-Trimethylpentane | - | **U** |
| VMP-29-30-020613 | TO-15 | Toluene | - | **U** |
| VMP-29-30-020613 | TO-15 | Tetrachloroethene | - | **U** |
| VMP-29-30-020613 | TO-15 | Cumene | - | **U** |
| VMP-29-30-020613 | TO-15 | 4-Ethyltoluene | - | **U** |
| VMP-30-10-020613 | TO-15 | Freon 11 | - | **U** |
| VMP-30-10-020613 | TO-15 | Carbon disulfide | - | **U** |
| VMP-30-10-020613 | TO-15 | Methylene chloride | - | **U** |
| VMP-30-10-020613 | TO-15 | Tetrachloroethene | - | **U** |
| VMP-30-20-020613 | TO-15 | Freon 11 | - | **U** |
| VMP-30-20-020613 | TO-15 | Methylene chloride | - | **U** |
| VMP-30-20-020613 | TO-15 | 2,2,4-Trimethylpentane | - | **U** |
| VMP-30-20-020613 | TO-15 | Toluene | - | **U** |
| VMP-30-20-020613 | TO-15 | Tetrachloroethene | - | **U** |

| Sample ID | Parameter | Analyte | New Reporting Limit (RL) | Qualification |
|---|---|---|---|---|
| VMP-30-20-020613 | TO-15 | Cumene | - | **U** |
| VMP-30-20-020613 | TO-15 | Propylbenzene | - | **U** |
| VMP-30-20-020613 | TO-15 | 4-Ethyltoluene | - | **U** |
| VMP-30-20-020613 | TO-15 | 1,3,5-Trimethylbenzene | - | **U** |
| VMP-30-20-020613 | TO-15 | 1,2,4-Trimethylbenzene | - | **U** |
| VMP-30-20-020613 | TO-15 | 1,3-Dichlorobenzene | - | **U** |
| VMP-30-20-020613 | TO-15 | 1,4-Dichlorobenzene | - | **U** |
| VMP-30-20-020613 | TO-15 | alpha-Chlorotoluene | - | **U** |
| VMP-30-20-020613 | TO-15 | 1,2-Dichlorobenzene | - | **U** |
| VMP-30-20-020613 | TO-15 | 1,2,4-Trichlorobenzene | - | **U** |
| VMP-30-20-020613 | TO-15 | Hexachlorobutadiene | - | **U** |
| VMP-30-30-020613 | TO-15 | 1,2,4-Trichlorobenzene | - | **U** |
| VMP-32-5-020513 | TO-15 | Freon 11 | - | **U** |
| VMP-32-5-020513 | TO-15 | Carbon disulfide | - | **U** |
| VMP-32-5-020513 | TO-15 | Methylene chloride | - | **U** |
| VMP-32-5-020513 | TO-15 | Toluene | - | **U** |
| VMP-32-5-020513 | TO-15 | Tetrachloroethene | - | **U** |
| VMP-32-5-020513 | TO-15 | Propylbenzene | - | **U** |
| VMP-32-5-020513 | TO-15 | 4-Ethyltoluene | - | **U** |
| VMP-32-5-020513 | TO-15 | 1,2,4-Trimethylbenzene | - | **U** |
| VMP-32-5-020513 | TO-15 | 1,3-Dichlorobenzene | - | **U** |
| VMP-32-5-020513 | TO-15 | 1,4-Dichlorobenzene | - | **U** |
| VMP-32-5-020513 | TO-15 | 1,2,4-Trichlorobenzene | - | **U** |
| VMP-32-10-020513 | TO-15 | Freon 11 | - | **U** |
| VMP-32-10-020513 | TO-15 | Carbon disulfide | - | **U** |
| VMP-32-10-020513 | TO-15 | Methylene chloride | - | **U** |
| VMP-32-10-020513 | TO-15 | Toluene | - | **U** |
| VMP-32-10-020513 | TO-15 | Tetrachloroethene | - | **U** |
| VMP-32-10-020513 | TO-15 | 4-Ethyltoluene | - | **U** |
| VMP-32-10-020513 | TO-15 | 1,2,4-Trichlorobenzene | - | **U** |
| VMP-32-20-020513 | TO-15 | Freon 11 | - | **U** |
| VMP-32-20-020513 | TO-15 | Carbon disulfide | - | **U** |
| VMP-32-20-020513 | TO-15 | Methylene chloride | - | **U** |
| VMP-32-20-020513 | TO-15 | Toluene | - | **U** |
| VMP-32-20-020513 | TO-15 | Tetrachloroethene | - | **U** |
| VMP-32-20-020513 | TO-15 | 1,2,4-Trichlorobenzene | - | **U** |
| VMP-53-5-020513 | TO-15 | Freon 11 | - | **U** |
| VMP-53-5-020513 | TO-15 | Carbon disulfide | - | **U** |
| VMP-53-5-020513 | TO-15 | Toluene | - | **U** |
| VMP-53-5-020513 | TO-15 | Tetrachloroethene | - | **U** |
| VMP-53-10-020513 | TO-15 | Freon 11 | - | **U** |
| VMP-53-10-020513 | TO-15 | Carbon disulfide | - | **U** |
| VMP-53-10-020513 | TO-15 | Toluene | - | **U** |

| Sample ID | Parameter | Analyte | New Reporting Limit (RL) | Qualification |
|---|---|---|---|---|
| VMP-53-10-020513-Dup | TO-15 | Freon 11 | - | **U** |
| VMP-53-10-020513-Dup | TO-15 | Carbon disulfide | - | **U** |
| VMP-53-10-020513-Dup | TO-15 | 2,2,4-Trimethylpentane | - | **U** |
| VMP-53-10-020513-Dup | TO-15 | Toluene | - | **U** |
| VMP-53-20-020513 | TO-15 | Freon 11 | - | **U** |
| VMP-53-20-020513 | TO-15 | Carbon disulfide | - | **U** |
| VMP-53-20-020513 | TO-15 | Toluene | - | **U** |
| VMP-53-20-020513 | TO-15 | Tetrachloroethene | - | **U** |
| VMP-53-20-020513 | TO-15 | Propylbenzene | - | **U** |
| VMP-53-20-020513 | TO-15 | 1,2,4-Trichlorobenzene | - | **U** |
| VMP-53-30-020513 | TO-15 | Carbon disulfide | - | **U** |
| VMP-53-30-020513 | TO-15 | Toluene | - | **U** |
| VMP-53-30-020513 | TO-15 | Tetrachloroethene | - | **U** |
| VMP-54-5-020613 | TO-15 | Freon 11 | - | **U** |
| VMP-54-5-020613 | TO-15 | Carbon disulfide | - | **U** |
| VMP-54-5-020613 | TO-15 | Tetrachloroethene | - | **U** |
| VMP-54-5-020613 | TO-15 | Cumene | - | **U** |
| VMP-54-10-020613 | TO-15 | Freon 11 | - | **U** |
| VMP-54-10-020613 | TO-15 | Carbon disulfide | - | **U** |
| VMP-54-10-020613 | TO-15 | Methylene chloride | - | **U** |
| VMP-54-10-020613 | TO-15 | Tetrachloroethene | - | **U** |
| VMP-54-10-020613 | TO-15 | Propylbenzene | - | **U** |
| VMP-54-10-020613 | TO-15 | 1,3,5-Trimethylbenzene | - | **U** |
| VMP-54-10-020613 | TO-15 | 1,2,4-Trimethylbenzene | - | **U** |

## 5.0 Laboratory Control Sample

*Were LCS recoveries within evaluation criteria?*

Yes

## 6.0 Surrogate Recoveries

*Were surrogate recoveries within evaluation criteria?*

Yes

## 7.0 Matrix Spike and Matrix Spike Duplicate Recoveries

*Were MS/MSD samples analyzed as part of this SDG?*

MS/MSD samples are not applicable for vapor samples, due to the inability to spike the samples.

## 8.0 Laboratory Duplicate Results

*Were laboratory duplicate samples collected as part of this SDG?*

No

## 9.0 Field Duplicate Results

*Were field duplicate samples collected as part of this SDG?*

Yes

| Field ID | Field Duplicate ID |
|---|---|
| VMP-21-10-020513 | VMP-21-10-020513-Dup |
| VMP-21-25-020513 | VMP-21-25-020513-Dup |
| VMP-53-10-020513 | VMP-53-10-020513-Dup |

*Were field duplicate sample RPDs within evaluation criteria?*

Yes

## 10.0 Sample Dilutions

*For samples that were diluted and nondetect, were undiluted results also reported?*

Not applicable; analytes were detected in samples that were diluted.

## 11.0 Additional Qualifications

*Were additional qualifications applied?*

No

eurofins | Air Toxics

2/25/2013
Ms. Elizabeth Kunkel
URS Corporation
1001 Highlands Plaza Dr. West
Suite 300
St. Louis MO 63110

Project Name: Roxana Soil Vapor
Project #: 21562850.04001
Workorder #: 1302156A

Dear Ms. Elizabeth Kunkel

The following report includes the data for the above referenced project for sample(s) received on 2/8/2013 at Air Toxics Ltd.

The data and associated QC analyzed by Modified TO-15 are compliant with the project requirements or laboratory criteria with the exception of the deviations noted in the attached case narrative.

Thank you for choosing Air Toxics Ltd. for your air analysis needs. Air Toxics Ltd. is committed to providing accurate data of the highest quality. Please feel free to contact the Project Manager: Kelly Buettner at 916-985-1000 if you have any questions regarding the data in this report.

Regards,

Kelly Buettner

Project Manager

REVIEWED
ON
3/26/13

eurofins | Air Toxics

# WORK ORDER #: 1302156A

Work Order Summary

| | | | |
|---|---|---|---|
| **CLIENT:** | Ms. Elizabeth Kunkel<br>URS Corporation<br>1001 Highlands Plaza Dr. West<br>Suite 300<br>St. Louis, MO 63110 | **BILL TO:** | Accounts Payable Austin<br>URS Corporation<br>P.O. BOX 203970<br>Austin, TX 78720-1088 |
| **PHONE:** | 314-743-4179 | **P.O. #** | 21562735.00013 |
| **FAX:** | | **PROJECT #** | 21562850.04001 Roxana Soil Vapor |
| **DATE RECEIVED:** | 02/08/2013 | **CONTACT:** | Kelly Buettner |
| **DATE COMPLETED:** | 02/25/2013 | | |

| FRACTION # | NAME | TEST | RECEIPT VAC./PRES. | FINAL PRESSURE |
|---|---|---|---|---|
| 01A | VMP-2-8.5-020513 | Modified TO-15 | 9.5 "Hg | 15 psi |
| 02A | VMP-6-10-020513 | Modified TO-15 | 8.0 "Hg | 15 psi |
| 03A | VMP-6-31.5-020513 | Modified TO-15 | 6.5 "Hg | 15 psi |
| 04A | VMP-6-39-020513 | Modified TO-15 | 7.0 "Hg | 15 psi |
| 05A | VMP-15-5-020513 | Modified TO-15 | 9.0 "Hg | 15 psi |
| 06A | VMP-21-10-020513 | Modified TO-15 | 7.5 "Hg | 15 psi |
| 07A | VMP-21-10-020513-DUP | Modified TO-15 | 6.0 "Hg | 15 psi |
| 08A | VMP-21-25-020513 | Modified TO-15 | 6.5 "Hg | 15 psi |
| 09A | VMP-21-25-020513-DUP | Modified TO-15 | 7.5 "Hg | 15 psi |
| 10A | VMP-21-33-020513 | Modified TO-15 | 7.0 "Hg | 15 psi |
| 11A | VMP-29-10-020613 | Modified TO-15 | 8.5 "Hg | 15 psi |
| 12A | VMP-29-20-020613 | Modified TO-15 | 8.0 "Hg | 15 psi |
| 13A | VMP-29-30-020613 | Modified TO-15 | 9.0 "Hg | 15 psi |
| 13B | VMP-29-30-020613 | Modified TO-15 | 9.0 "Hg | 15 psi |
| 14A | VMP-30-10-020613 | Modified TO-15 | 7.0 "Hg | 15 psi |
| 15A | VMP-30-20-020613 | Modified TO-15 | 7.0 "Hg | 15 psi |
| 16A | VMP-30-30-020613 | Modified TO-15 | 7.0 "Hg | 15 psi |
| 16B | VMP-30-30-020613 | Modified TO-15 | 7.0 "Hg | 15 psi |
| 17A | VMP-32-5-020513 | Modified TO-15 | 6.0 "Hg | 15 psi |
| 18A | VMP-32-10-020513 | Modified TO-15 | 6.0 "Hg | 15 psi |
| 19A | VMP-32-20-020513 | Modified TO-15 | 8.5 "Hg | 15 psi |
| 20A | VMP-53-5-020513 | Modified TO-15 | 6.5 "Hg | 15 psi |
| 21A | VMP-53-10-020513 | Modified TO-15 | 7.0 "Hg | 15 psi |

Continued on next page

eurofins | Air Toxics

# WORK ORDER #: 1302156A

Work Order Summary

| | | | |
|---|---|---|---|
| **CLIENT:** | Ms. Elizabeth Kunkel<br>URS Corporation<br>1001 Highlands Plaza Dr. West<br>Suite 300<br>St. Louis, MO 63110 | **BILL TO:** | Accounts Payable Austin<br>URS Corporation<br>P.O. BOX 203970<br>Austin, TX 78720-1088 |
| **PHONE:** | 314-743-4179 | **P.O. #** | 21562735.00013 |
| **FAX:** | | **PROJECT #** | 21562850.04001 Roxana Soil Vapor |
| **DATE RECEIVED:** | 02/08/2013 | **CONTACT:** | Kelly Buettner |
| **DATE COMPLETED:** | 02/25/2013 | | |

| FRACTION # | NAME | TEST | RECEIPT VAC./PRES. | FINAL PRESSURE |
|---|---|---|---|---|
| 22A | VMP-53-10-020513-DUP | Modified TO-15 | 5.5 "Hg | 15 psi |
| 23A | VMP-53-20-020513 | Modified TO-15 | 7.0 "Hg | 15 psi |
| 24A | VMP-53-30-020513 | Modified TO-15 | 7.5 "Hg | 15 psi |
| 25A | VMP-54-5-020613 | Modified TO-15 | 8.0 "Hg | 15 psi |
| 26A | VMP-54-10-020613 | Modified TO-15 | 8.5 "Hg | 15 psi |
| 27A | Lab Blank | Modified TO-15 | NA | NA |
| 27B | Lab Blank | Modified TO-15 | NA | NA |
| 28A | CCV | Modified TO-15 | NA | NA |
| 28B | CCV | Modified TO-15 | NA | NA |
| 29A | LCS | Modified TO-15 | NA | NA |
| 29AA | LCSD | Modified TO-15 | NA | NA |
| 29B | LCS | Modified TO-15 | NA | NA |
| 29BB | LCSD | Modified TO-15 | NA | NA |

CERTIFIED BY: Heidi Hayes DATE: 02/25/13

Technical Director

Certfication numbers: AZ Licensure AZ0775, CA NELAP - 12282CA, NY NELAP - 11291,
TX NELAP - T104704434-12-5, UT NELAP CA009332012-3, WA NELAP - C935
Name of Accrediting Agency: NELAP/ORELAP (Oregon Environmental Laboratory Accreditation Program)
Accreditation number: CA300005, Effective date: 10/18/2011, Expiration date: 10/17/2012.
Eurofins Air Toxics Ltd. certifies that the test results contained in this report meet all requirements of the NELAC standards

This report shall not be reproduced, except in full, without the written approval of Eurofins Air Toxics, Inc.

180 BLUE RAVINE ROAD, SUITE B FOLSOM, CA - 9563
(916) 985-1000 . (800) 985-5955 . FAX (916) 985-1020

**LABORATORY NARRATIVE**
**EPA Method TO-15**
**URS Corporation**
**Workorder# 1302156A**

Twenty-six 1 Liter Summa Canister samples were received on February 08, 2013. The laboratory performed analysis via EPA Method TO-15 using GC/MS in the full scan mode.

This workorder was independently validated prior to submittal using 'USEPA National Functional Guidelines' as generally applied to the analysis of volatile organic compounds in air. A rules-based, logic driven, independent validation engine was employed to assess completeness, evaluate pass/fail of relevant project quality control requirements and verification of all quantified amounts.

**Receiving Notes**

There were no receiving discrepancies.

**Analytical Notes**

As per client project requirements, the laboratory has reported estimated values for target compound hits that are below the Reporting Limit but greater than the Method Detection Limit. Concentrations that are below the level at which the canister was certified may be false positives.

Due to high-level target compounds, samples VMP-29-30-020613 and VMP-30-30-020613 were analyzed twice. In the "A" fraction, the sample was diluted to bring the highest-level compounds within the calibration range. The "B" fraction is also reported by client request and may be reported with "E" flags indicating the compound exceeds the calibration range. Both runs and associated QC are reported.

**Definition of Data Qualifying Flags**

Eight qualifiers may have been used on the data analysis sheets and indicates as follows:

B - Compound present in laboratory blank greater than reporting limit (background subtraction not performed).
J - Estimated value.
E - Exceeds instrument calibration range.
S - Saturated peak.
Q - Exceeds quality control limits.
U - Compound analyzed for but not detected above the reporting limit.
UJ- Non-detected compound associated with low bias in the CCV and/or LCS.
N - The identification is based on presumptive evidence.

File extensions may have been used on the data analysis sheets and indicates as follows:
a-File was requantified
b-File was quantified by a second column and detector
r1-File was requantified for the purpose of reissue

eurofins | Air Toxics

# Summary of Detected Compounds
# EPA METHOD TO-15 GC/MS FULL SCAN

**Client Sample ID: VMP-2-8.5-020513**

**Lab ID#: 1302156A-01A**

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 1.5 | 0.46 J | 7.3 | 2.3 J |
| Freon 11 | 1.5 | ~~0.19 J~~ | 8.3 | ~~1.1 J~~ |
| Ethanol | 5.9 | 1.4 J | 11 | 2.6 J |
| Acetone | 15 | 2.5 J | 35 | 6.0 J |
| 2-Propanol | 5.9 | 4.2 J | 14 | 10 J |
| Carbon Disulfide | 5.9 | ~~0.77 J~~ | 18 | ~~2.4 J~~ |
| Methylene Chloride | 15 | ~~0.22 J~~ | 51 | ~~0.78 J~~ |
| Hexane | 1.5 | 4.2 | 5.2 | 15 |
| Cyclohexane | 1.5 | 2.0 | 5.1 | 7.1 |
| 2,2,4-Trimethylpentane | 1.5 | 8.2 | 6.9 | 38 |
| Benzene | 1.5 | 0.68 J | 4.7 | 2.2 J |
| Heptane | 1.5 | 2.2 | 6.1 | 9.0 |
| 4-Methyl-2-pentanone | 1.5 | 0.38 J | 6.1 | 1.5 J |
| Toluene | 1.5 | 1.9 | 5.6 | 7.3 |
| Tetrachloroethene | 1.5 | ~~0.32 J~~ | 10 | ~~2.2 J~~ |
| Ethyl Benzene | 1.5 | 0.58 J | 6.4 | 2.5 J |
| m,p-Xylene | 1.5 | 0.82 J | 6.4 | 3.6 J |
| o-Xylene | 1.5 | 0.51 J | 6.4 | 2.2 J |
| Butane | 5.9 | 16 | 14 | 38 |
| Isopentane | 5.9 | 20 | 17 | 59 |

**Client Sample ID: VMP-6-10-020513**

**Lab ID#: 1302156A-02A**

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 1.4 | 0.47 J | 6.8 | 2.3 J |
| Freon 11 | 1.4 | ~~0.24~~ J | 7.8 | ~~1.3 J~~ |
| Ethanol | 5.5 | 0.91 J | 10 | 1.7 J |
| Acetone | 14 | 3.8 J | 33 | 9.0 J |
| 2-Propanol | 5.5 | 4.1 J | 14 | 10 J |
| Carbon Disulfide | 5.5 | ~~0.70 J~~ | 17 | ~~2.2 J~~ |
| Methylene Chloride | 14 | ~~0.68 J~~ | 48 | ~~2.4 J~~ |
| Hexane | 1.4 | 0.40 J | 4.9 | 1.4 J |

eurofins | Air Toxics

# Summary of Detected Compounds
# EPA METHOD TO-15 GC/MS FULL SCAN

**Client Sample ID: VMP-6-10-020513**

**Lab ID#: 1302156A-02A**

| | | | | |
|---|---|---|---|---|
| 2,2,4-Trimethylpentane | 1.4 | 0.33 J | 6.4 | 1.6 J |
| Benzene | 1.4 | 14 | 4.4 | 46 |
| Toluene | 1.4 | ~~0.11 J~~ U | 5.2 | ~~0.42 J~~ U |
| Tetrachloroethene | 1.4 | ~~0.17 J~~ U | 9.4 | ~~1.2 J~~ U |
| 1,2,4-Trichlorobenzene | 5.5 | ~~0.38 J~~ U | 41 | ~~2.8 J~~ U |
| Butane | 5.5 | 1.5 J | 13 | 3.6 J |
| Isopentane | 5.5 | 1.1 J | 16 | 3.2 J |

**Client Sample ID: VMP-6-31.5-020513**

**Lab ID#: 1302156A-03A**

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 1.3 | 0.52 J | 6.4 | 2.6 J |
| Freon 11 | 1.3 | ~~0.26 J~~ U | 7.2 | ~~1.4 J~~ U |
| Acetone | 13 | 4.0 J | 31 | 9.5 J |
| 2-Propanol | 5.2 | 46 | 13 | 110 |
| Carbon Disulfide | 5.2 | ~~0.85 J~~ U | 16 | ~~2.6 J~~ U |
| Methylene Chloride | 13 | 1.4 J | 45 | 5.0 J |
| Hexane | 1.3 | 0.26 J | 4.5 | 0.91 J |
| Chloroform | 1.3 | 0.89 J | 6.3 | 4.3 J |
| 2,2,4-Trimethylpentane | 1.3 | 12 | 6.0 | 58 |
| Benzene | 1.3 | 1.2 J | 4.1 | 4.0 J |
| Toluene | 1.3 | ~~0.11 J~~ U | 4.9 | ~~0.42 J~~ U |
| Tetrachloroethene | 1.3 | ~~0.14 J~~ U | 8.8 | ~~0.96 J~~ U |
| Butane | 5.2 | 12 | 12 | 30 |
| Isopentane | 5.2 | 2.7 J | 15 | 8.0 J |

**Client Sample ID: VMP-6-39-020513**

**Lab ID#: 1302156A-04A**

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 1.3 | 0.47 J | 6.5 | 2.3 J |
| Freon 11 | 1.3 | ~~0.23 J~~ U | 7.4 | ~~1.3 J~~ U |
| Ethanol | 5.3 | 2.2 J | 9.9 | 4.2 J |

eurofins | Air Toxics

# Summary of Detected Compounds
# EPA METHOD TO-15 GC/MS FULL SCAN

**Client Sample ID: VMP-6-39-020513**

**Lab ID#: 1302156A-04A**

| | | | | |
|---|---|---|---|---|
| Acetone | 13 | 5.8 J | 31 | 14 J |
| 2-Propanol | 5.3 | 4.5 J | 13 | 11 J |
| Carbon Disulfide | 5.3 | ~~0.64 J~~ | 16 | ~~2.0 J~~ |
| Methylene Chloride | 13 | ~~0.16 J~~ | 46 | ~~0.54 J~~ |
| Hexane | 1.3 | 1.4 | 4.6 | 5.1 |
| Cyclohexane | 1.3 | 3.0 | 4.5 | 10 |
| 2,2,4-Trimethylpentane | 1.3 | 140 | 6.2 | 630 |
| Benzene | 1.3 | 20 | 4.2 | 66 |
| Heptane | 1.3 | 6.6 | 5.4 | 27 |
| Toluene | 1.3 | ~~0.18 J~~ | 5.0 | ~~0.68 J~~ |
| Tetrachloroethene | 1.3 | ~~0.16 J~~ | 9.0 | ~~1.1 J~~ |
| Ethyl Benzene | 1.3 | 7.9 | 5.7 | 34 |
| m,p-Xylene | 1.3 | 5.3 | 5.7 | 23 |
| Cumene | 1.3 | 1.1 J | 6.5 | 5.6 J |
| Propylbenzene | 1.3 | 2.5 | 6.5 | 12 |
| 4-Ethyltoluene | 1.3 | 2.5 | 6.5 | 12 |
| 1,3,5-Trimethylbenzene | 1.3 | 1.1 J | 6.5 | 5.5 J |
| 1,2,4-Trimethylbenzene | 1.3 | 4.9 | 6.5 | 24 |
| Isopentane | 5.3 | 2.8 J | 16 | 8.2 J |

**Client Sample ID: VMP-15-5-020513**

**Lab ID#: 1302156A-05A**

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 1.4 | 0.39 J | 7.1 | 2.0 J |
| Ethanol | 5.8 | 1.8 J | 11 | 3.3 J |
| Acetone | 14 | 2.6 J | 34 | 6.0 J |
| 2-Propanol | 5.8 | 10 | 14 | 25 |
| Carbon Disulfide | 5.8 | ~~0.85 J~~ | 18 | ~~2.7 J~~ |
| Methylene Chloride | 14 | ~~0.34 J~~ | 50 | ~~1.2 J~~ |
| 2,2,4-Trimethylpentane | 1.4 | 1.3 J | 6.8 | 6.2 J |
| Benzene | 1.4 | 1.2 J | 4.6 | 4.0 J |
| Toluene | 1.4 | ~~0.14 J~~ | 5.4 | ~~0.53 J~~ |
| 4-Ethyltoluene | 1.4 | ~~0.11 J~~ | 7.1 | ~~0.54 J~~ |
| Isopentane | 5.8 | 0.66 J | 17 | 1.9 J |

eurofins | Air Toxics

# Summary of Detected Compounds
# EPA METHOD TO-15 GC/MS FULL SCAN

**Client Sample ID: VMP-21-10-020513**

**Lab ID#: 1302156A-06A**

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 1.3 | 0.44 J | 6.6 | 2.2 J |
| Freon 11 | 1.3 | ~~0.18 J~~ | 7.6 | ~~1.0 J~~ |
| Ethanol | 5.4 | 1.7 J | 10 | 3.3 J |
| Acetone | 13 | 2.7 J | 32 | 6.5 J |
| 2-Propanol | 5.4 | 2.5 J | 13 | 6.1 J |
| Carbon Disulfide | 5.4 | ~~0.53 J~~ | 17 | ~~1.6 J~~ |
| Methylene Chloride | 13 | ~~0.31 J~~ | 47 | ~~1.1 J~~ |
| Hexane | 1.3 | 0.79 J | 4.7 | 2.8 J |
| Cyclohexane | 1.3 | 1.0 J | 4.6 | 3.6 J |
| 2,2,4-Trimethylpentane | 1.3 | 5.5 | 6.3 | 26 |
| Benzene | 1.3 | 13 | 4.3 | 41 |
| Heptane | 1.3 | 0.47 J | 5.5 | 1.9 J |
| Toluene | 1.3 | ~~0.19 J~~ | 5.1 | ~~0.70 J~~ |
| Tetrachloroethene | 1.3 | 1.5 | 9.1 | 10 |
| Isopentane | 5.4 | 2.2 J | 16 | 6.6 J |

**Client Sample ID: VMP-21-10-020513-DUP**

**Lab ID#: 1302156A-07A**

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 1.3 | 0.49 J | 6.2 | 2.4 J |
| Freon 11 | 1.3 | ~~0.18 J~~ | 7.1 | ~~0.99 J~~ |
| Ethanol | 5.0 | 1.1 J | 9.5 | 2.0 J |
| Acetone | 13 | 2.6 J | 30 | 6.3 J |
| 2-Propanol | 5.0 | 2.4 J | 12 | 6.0 J |
| Carbon Disulfide | 5.0 | ~~0.58 J~~ | 16 | ~~1.8 J~~ |
| Methylene Chloride | 13 | ~~0.29 J~~ | 44 | ~~1.0 J~~ |
| Hexane | 1.3 | 0.60 J | 4.4 | 2.1 J |
| Cyclohexane | 1.3 | 1.2 J | 4.3 | 4.3 J |
| 2,2,4-Trimethylpentane | 1.3 | 6.5 | 5.9 | 30 |
| Benzene | 1.3 | 11 | 4.0 | 35 |
| Heptane | 1.3 | 0.51 J | 5.2 | 2.1 J |
| Toluene | 1.3 | ~~0.15 J~~ | 4.7 | ~~0.57 J~~ |

eurofins | Air Toxics

# Summary of Detected Compounds
# EPA METHOD TO-15 GC/MS FULL SCAN

**Client Sample ID: VMP-21-10-020513-DUP**

**Lab ID#: 1302156A-07A**

| | | | | |
|---|---|---|---|---|
| Tetrachloroethene | 1.3 | 1.4 | 8.5 | 9.6 |
| Isopentane | 5.0 | 0.92 J | 15 | 2.7 J |

**Client Sample ID: VMP-21-25-020513**

**Lab ID#: 1302156A-08A**

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 1.3 | 0.51 J | 6.4 | 2.5 J |
| Freon 11 | 1.3 | ~~0.25 J~~ ✓ | 7.2 | ~~1.4 J~~ ✓ |
| Ethanol | 5.2 | 2.3 J | 9.7 | 4.4 J |
| Acetone | 13 | 4.6 J | 31 | 11 J |
| 2-Propanol | 5.2 | 3.4 J | 13 | 8.3 J |
| Carbon Disulfide | 5.2 | ~~0.50 J~~ ✓ | 16 | ~~1.5 J~~ ✓ |
| Methylene Chloride | 13 | ~~0.20 J~~ ✓ | 45 | ~~0.71 J~~ ✓ |
| Hexane | 1.3 | 0.93 J | 4.5 | 3.3 J |
| Cyclohexane | 1.3 | 1.0 J | 4.4 | 3.5 J |
| 2,2,4-Trimethylpentane | 1.3 | 5.1 | 6.0 | 24 |
| Benzene | 1.3 | 11 | 4.1 | 35 |
| Heptane | 1.3 | 0.36 J | 5.3 | 1.5 J |
| Toluene | 1.3 | ~~0.11 J~~ ✓ | 4.9 | ~~0.43 J~~ ✓ |
| Tetrachloroethene | 1.3 | 15 | 8.8 | 100 |
| Butane | 5.2 | 1.3 J | 12 | 3.1 J |
| Isopentane | 5.2 | 2.8 J | 15 | 8.3 J |

**Client Sample ID: VMP-21-25-020513-DUP**

**Lab ID#: 1302156A-09A**

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 1.3 | 0.54 J | 6.6 | 2.7 J |
| Freon 11 | 1.3 | ~~0.30 J~~ ✓ | 7.6 | ~~1.7 J~~ ✓ |
| Ethanol | 5.4 | 2.0 J | 10 | 3.7 J |
| Acetone | 13 | 3.2 J | 32 | 7.7 J |
| 2-Propanol | 5.4 | 3.4 J | 13 | 8.4 J |
| Carbon Disulfide | 5.4 | ~~0.59 J~~ ✓ | 17 | ~~1.8 J~~ ✓ |

eurofins | Air Toxics

# Summary of Detected Compounds
# EPA METHOD TO-15 GC/MS FULL SCAN

**Client Sample ID: VMP-21-25-020513-DUP**

**Lab ID#: 1302156A-09A**

| | | | | |
|---|---|---|---|---|
| Methylene Chloride | 13 | ~~0.85 J~~ | 47 | ~~3.0 J~~ |
| Hexane | 1.3 | 0.80 J | 4.7 | 2.8 J |
| Cyclohexane | 1.3 | 1.2 J | 4.6 | 4.0 J |
| 2,2,4-Trimethylpentane | 1.3 | 3.1 | 6.3 | 14 |
| Benzene | 1.3 | 13 | 4.3 | 43 |
| Heptane | 1.3 | 0.41 J | 5.5 | 1.7 J |
| 4-Methyl-2-pentanone | 1.3 | 0.38 J | 5.5 | 1.6 J |
| Toluene | 1.3 | ~~0.26 J~~ | 5.1 | ~~0.97 J~~ |
| Tetrachloroethene | 1.3 | 16 | 9.1 | 110 |
| Isopentane | 5.4 | 3.6 J | 16 | 11 J |

**Client Sample ID: VMP-21-33-020513**

**Lab ID#: 1302156A-10A**

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 1.3 | 0.52 J | 6.5 | 2.6 J |
| Acetone | 13 | 2.5 J | 31 | 5.8 J |
| 2-Propanol | 5.3 | 12 | 13 | 29 |
| Carbon Disulfide | 5.3 | ~~0.72 J~~ | 16 | ~~2.2 J~~ |
| Methylene Chloride | 13 | ~~0.16 J~~ | 46 | ~~0.56 J~~ |
| Hexane | 1.3 | 0.33 J | 4.6 | 1.2 J |
| 2,2,4-Trimethylpentane | 1.3 | 2.3 | 6.2 | 10 |
| Benzene | 1.3 | 0.76 J | 4.2 | 2.4 J |
| Tetrachloroethene | 1.3 | 5.1 | 9.0 | 34 |
| Isopentane | 5.3 | 1.4 J | 16 | 4.2 J |

**Client Sample ID: VMP-29-10-020613**

**Lab ID#: 1302156A-11A**

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 1.4 | 0.51 J | 7.0 | 2.5 J |
| Freon 11 | 1.4 | ~~0.22 J~~ | 7.9 | ~~1.2 J~~ |
| Ethanol | 5.6 | 9.5 | 11 | 18 |
| Acetone | 14 | 69 | 33 | 160 |

eurofins | Air Toxics

# Summary of Detected Compounds
# EPA METHOD TO-15 GC/MS FULL SCAN

**Client Sample ID: VMP-29-10-020613**

**Lab ID#: 1302156A-11A**

| | | | | |
|---|---|---|---|---|
| 2-Propanol | 5.6 | 18 | 14 | 44 |
| Carbon Disulfide | 5.6 | 6.7 | 18 | 21 |
| 2-Butanone (Methyl Ethyl Ketone) | 5.6 | 100 | 17 | 300 |
| Tetrahydrofuran | 1.4 | 100 | 4.2 | 290 |
| 2,2,4-Trimethylpentane | 1.4 | ~~0.21 J~~ | 6.6 | ~~0.98 J~~ |
| Benzene | 1.4 | 17 | 4.5 | 53 |
| 4-Methyl-2-pentanone | 1.4 | 0.68 J | 5.8 | 2.8 J |
| Toluene | 1.4 | ~~0.13 J~~ | 5.3 | ~~0.48 J~~ |
| Tetrachloroethene | 1.4 | ~~0.19 J~~ | 9.6 | ~~1.3 J~~ |
| Butane | 5.6 | 1.6 J | 13 | 3.8 J |
| Isopentane | 5.6 | 1.0 J | 17 | 3.1 J |

**Client Sample ID: VMP-29-20-020613**

**Lab ID#: 1302156A-12A**

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 1.4 | 0.45 J | 6.8 | 2.2 J |
| Freon 11 | 1.4 | ~~0.22 J~~ | 7.8 | ~~1.3 J~~ |
| Ethanol | 5.5 | 5.4 J | 10 | 10 J |
| Acetone | 14 | 87 | 33 | 210 |
| 2-Propanol | 5.5 | 16 | 14 | 40 |
| Carbon Disulfide | 5.5 | 11 | 17 | 35 |
| Methylene Chloride | 14 | ~~0.28 J~~ | 48 | ~~0.98 J~~ |
| Hexane | 1.4 | 0.33 J | 4.9 | 1.2 J |
| 2-Butanone (Methyl Ethyl Ketone) | 5.5 | 260 | 16 | 750 |
| Tetrahydrofuran | 1.4 | 68 | 4.1 | 200 |
| Benzene | 1.4 | 8.1 | 4.4 | 26 |
| 4-Methyl-2-pentanone | 1.4 | 2.5 | 5.6 | 10 |
| Toluene | 1.4 | 0.52 J | 5.2 | 1.9 J |
| Tetrachloroethene | 1.4 | ~~0.15 J~~ | 9.4 | ~~1.0 J~~ |
| m,p-Xylene | 1.4 | 0.47 J | 6.0 | 2.0 J |
| Cumene | 1.4 | ~~0.73 J~~ | 6.8 | ~~3.6 J~~ |
| 4-Ethyltoluene | 1.4 | ~~0.14 J~~ | 6.8 | ~~0.69 J~~ |
| Butane | 5.5 | 3.6 J | 13 | 8.4 J |
| Isopentane | 5.5 | 2.7 J | 16 | 8.1 J |

eurofins | Air Toxics

# Summary of Detected Compounds
# EPA METHOD TO-15 GC/MS FULL SCAN

**Client Sample ID: VMP-29-30-020613**

* USE THIS RESULT ONLY. ALL OTHER DATA REPORTED IN 2.89X DILUTION ANALYSIS

**Lab ID#: 1302156A-13A**

DF = 4.82X

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 2.4 | 0.51 J | 12 | 2.5 J |
| Ethanol | 9.6 | 7.4 J | 18 | 14 J |
| Acetone | 24 | 350 | 57 | 820 |
| 2-Propanol | 9.6 | 13 | 24 | 32 |
| Carbon Disulfide | 9.6 | 38 | 30 | 120 |
| Methylene Chloride | 24 | ~~0.64 J~~ | 84 | ~~2.2 J~~ |
| Hexane | 2.4 | 0.44 J | 8.5 | 1.5 J |
| 2-Butanone (Methyl Ethyl Ketone) | 9.6 | 730 | 28 | 2100 |
| Tetrahydrofuran | 2.4 | 290 | 7.1 | 870 |
| Chloroform | 2.4 | 1.2 J | 12 | 6.1 J |
| 2,2,4-Trimethylpentane | 2.4 | 0.40 J | 11 | 1.9 J |
| Benzene | 2.4 | 29 | 7.7 | 93 |
| 1,4-Dioxane | 9.6 | 7.1 J | 35 | 26 J |
| 4-Methyl-2-pentanone | 2.4 | 3.9 | 9.9 | 16 |
| Toluene | 2.4 | 0.46 J | 9.1 | 1.7 J |
| Tetrachloroethene | 2.4 | ~~0.36 J~~ | 16 | ~~2.4 J~~ |
| Cumene | 2.4 | ~~0.42 J~~ | 12 | ~~2.1 J~~ |
| 4-Ethyltoluene | 2.4 | ~~0.16 J~~ | 12 | ~~0.80 J~~ |
| Butane | 9.6 | 2.4 J | 23 | 5.7 J |
| Isopentane | 9.6 | 1.7 J | 28 | 5.2 J |

**Client Sample ID: VMP-29-30-020613**

**Lab ID#: 1302156A-13B**

DF = 2.89X

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 1.4 | 0.48 J | 7.1 | 2.4 J |
| Freon 11 | 1.4 | ~~0.18 J~~ | 8.1 | ~~1.0 J~~ |
| Ethanol | 5.8 | 6.2 | 11 | 12 |
| Acetone | 14 | 320 | 34 | 760 |
| 2-Propanol | 5.8 | 12 | 14 | 29 |
| Carbon Disulfide | 5.8 | 34 | 18 | 100 |
| Methylene Chloride | 14 | ~~0.66 J~~ | 50 | ~~2.0 J~~ |
| Hexane | 1.4 | 0.25 J | 5.1 | 0.89 J |

eurofins | Air Toxics

# Summary of Detected Compounds
# EPA METHOD TO-15 GC/MS FULL SCAN

**Client Sample ID: VMP-29-30-020613**

**Lab ID#: 1302156A-13B** DF = 289x

* DO NOT USE THIS RESULT. USE ALL OTHER RESULTS

| | | | | |
|---|---|---|---|---|
| * ~~2-Butanone (Methyl Ethyl Ketone)~~ | ~~5.8~~ | ~~680 E~~ | ~~17~~ | ~~2000 E~~ |
| Tetrahydrofuran | 1.4 | 270 | 4.3 | 780 |
| Chloroform | 1.4 | 1.1 J | 7.0 | 5.6 J |
| 2,2,4-Trimethylpentane | 1.4 | ~~0.22 J~~ U | 6.8 | ~~1.0 J~~ U |
| Benzene | 1.4 | 26 | 4.6 | 84 |
| 1,4-Dioxane | 5.8 | 5.3 J | 21 | 19 J |
| 4-Methyl-2-pentanone | 1.4 | 2.9 | 5.9 | 12 |
| Toluene | 1.4 | ~~0.34 J~~ U | 5.4 | ~~1.3 J~~ U |
| Tetrachloroethene | 1.4 | ~~0.16 J~~ U | 9.8 | ~~1.1 J~~ U |
| m,p-Xylene | 1.4 | 0.48 J | 6.3 | 2.1 J |
| Cumene | 1.4 | ~~0.37 J~~ U | 7.1 | ~~1.8 J~~ U |
| 4-Ethyltoluene | 1.4 | ~~0.16 J~~ U | 7.1 | ~~0.78 J~~ U |
| Butane | 5.8 | 2.0 J | 14 | 4.7 J |
| Isopentane | 5.8 | 1.6 J | 17 | 4.6 J |

**Client Sample ID: VMP-30-10-020613**

**Lab ID#: 1302156A-14A**

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 1.3 | 0.46 J | 6.5 | 2.2 J |
| Freon 11 | 1.3 | ~~0.22 J~~ U | 7.4 | ~~1.2 J~~ U |
| Ethanol | 5.3 | 2.5 J | 9.9 | 4.6 J |
| Acetone | 13 | 38 | 31 | 91 |
| 2-Propanol | 5.3 | 1.2 J | 13 | 2.8 J |
| Carbon Disulfide | 5.3 | ~~2.2 J~~ U | 16 | ~~7.0 J~~ U |
| Methylene Chloride | 13 | ~~0.18 J~~ U | 46 | ~~0.61 J~~ U |
| Hexane | 1.3 | 0.64 J | 4.6 | 2.2 J |
| 2-Butanone (Methyl Ethyl Ketone) | 5.3 | 50 | 16 | 150 |
| Tetrahydrofuran | 1.3 | 30 | 3.9 | 90 |
| 2,2,4-Trimethylpentane | 1.3 | 0.41 J | 6.2 | 1.9 J |
| Benzene | 1.3 | 0.57 J | 4.2 | 1.8 J |
| Heptane | 1.3 | 0.34 J | 5.4 | 1.4 J |
| 4-Methyl-2-pentanone | 1.3 | 0.56 J | 5.4 | 2.3 J |
| Toluene | 1.3 | 0.41 J | 5.0 | 1.6 J |
| Tetrachloroethene | 1.3 | ~~0.18 J~~ U | 9.0 | ~~1.2 J~~ U |

eurofins | Air Toxics

# Summary of Detected Compounds
# EPA METHOD TO-15 GC/MS FULL SCAN

**Client Sample ID: VMP-30-10-020613**

**Lab ID#: 1302156A-14A**

| | | | | |
|---|---|---|---|---|
| Isopentane | 5.3 | 2.6 J | 16 | 7.7 J |

**Client Sample ID: VMP-30-20-020613**

**Lab ID#: 1302156A-15A**

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 1.3 | 0.44 J | 6.5 | 2.2 J |
| Freon 11 | 1.3 | ~~0.26 J~~ | 7.4 | ~~1.4 J~~ |
| Ethanol | 5.3 | 4.2 J | 9.9 | 8.0 J |
| Acetone | 13 | 70 | 31 | 170 |
| 2-Propanol | 5.3 | 4.5 J | 13 | 11 J |
| Carbon Disulfide | 5.3 | 25 | 16 | 77 |
| Methylene Chloride | 13 | ~~0.52 J~~ | 46 | ~~1.8 J~~ |
| Hexane | 1.3 | 0.70 J | 4.6 | 2.5 J |
| 2-Butanone (Methyl Ethyl Ketone) | 5.3 | 200 | 16 | 600 |
| Tetrahydrofuran | 1.3 | 70 | 3.9 | 210 |
| Chloroform | 1.3 | 2.5 | 6.4 | 12 |
| 2,2,4-Trimethylpentane | 1.3 | ~~0.25 J~~ | 6.2 | ~~1.2 J~~ |
| Benzene | 1.3 | 34 | 4.2 | 110 |
| 4-Methyl-2-pentanone | 1.3 | 0.82 J | 5.4 | 3.4 J |
| Toluene | 1.3 | ~~0.34 J~~ | 5.0 | ~~1.3 J~~ |
| Tetrachloroethene | 1.3 | ~~0.31 J~~ | 9.0 | ~~2.1 J~~ |
| m,p-Xylene | 1.3 | 0.34 J | 5.7 | 1.5 J |
| Cumene | 1.3 | ~~0.25 J~~ | 6.5 | ~~1.2 J~~ |
| Propylbenzene | 1.3 | ~~0.21 J~~ | 6.5 | ~~1.0 J~~ |
| 4-Ethyltoluene | 1.3 | ~~0.16 J~~ | 6.5 | ~~0.81 J~~ |
| 1,3,5-Trimethylbenzene | 1.3 | ~~0.25 J~~ | 6.5 | ~~1.2 J~~ |
| 1,2,4-Trimethylbenzene | 1.3 | ~~0.34 J~~ | 6.5 | ~~1.7 J~~ |
| 1,3-Dichlorobenzene | 1.3 | ~~0.48 J~~ | 7.9 | ~~2.9 J~~ |
| 1,4-Dichlorobenzene | 1.3 | ~~0.46 J~~ | 7.9 | ~~2.7 J~~ |
| alpha-Chlorotoluene | 1.3 | ~~0.33 J~~ | 6.8 | ~~1.7 J~~ |
| 1,2-Dichlorobenzene | 1.3 | ~~0.36 J~~ | 7.9 | ~~2.2 J~~ |
| 1,2,4-Trichlorobenzene | 5.3 | ~~1.5 J~~ | 39 | ~~11 J~~ |
| Hexachlorobutadiene | 5.3 | ~~0.61 J~~ | 56 | ~~6.5 J~~ |
| Butane | 5.3 | 3.7 J | 12 | 8.8 J |

eurofins | Air Toxics

# Summary of Detected Compounds
# EPA METHOD TO-15 GC/MS FULL SCAN

**Client Sample ID: VMP-30-20-020613**

**Lab ID#: 1302156A-15A**

| | | | | |
|---|---|---|---|---|
| Isopentane | 5.3 | 2.5 J | 16 | 7.3 J |

**Client Sample ID: VMP-30-30-020613** * USE THIS RESULT ONLY. ALL OTHER DATA REPORTED IN 8.80X DILUTION ANALYSIS.

**Lab ID#: 1302156A-16A** DF = 17.6X

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Acetone | 88 | 1200 | 210 | 2800 |
| 2-Propanol | 35 | 14 J | 86 | 35 J |
| Carbon Disulfide | 35 | 32 J | 110 | 100 J |
| * 2-Butanone (Methyl Ethyl Ketone) | 35 | 2200 | 100 | 6400 |
| Tetrahydrofuran | 8.8 | 900 | 26 | 2700 |
| Chloroform | 8.8 | 2.4 J | 43 | 12 J |
| Benzene | 8.8 | 450 | 28 | 1400 |

**Client Sample ID: VMP-30-30-020613** * DO NOT USE THIS RESULT. USE ALL OTHER DATA.

**Lab ID#: 1302156A-16B** DF = 8.80X

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Ethanol | 18 | 2.3 J | 33 | 4.4 J |
| Acetone | 44 | 1200 | 100 | 2800 |
| 2-Propanol | 18 | 15 J | 43 | 37 J |
| Carbon Disulfide | 18 | 32 | 55 | 100 |
| * ~~2-Butanone (Methyl Ethyl Ketone)~~ | ~~18~~ | ~~2200 E~~ | ~~52~~ | ~~6600 E~~ |
| Tetrahydrofuran | 4.4 | 880 | 13 | 2600 |
| Chloroform | 4.4 | 2.1 J | 21 | 10 J |
| Benzene | 4.4 | 430 | 14 | 1400 |
| 1,2,4-Trichlorobenzene | 18 | ~~1.2 J~~ U | 130 | ~~9.2 J~~ U |

**Client Sample ID: VMP-32-5-020513**

**Lab ID#: 1302156A-17A**

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 1.3 | 0.48 J | 6.2 | 2.4 J |
| Freon 11 | 1.3 | ~~0.22 J~~ U | 7.1 | ~~1.2 J~~ U |

eurofins | Air Toxics

# Summary of Detected Compounds
# EPA METHOD TO-15 GC/MS FULL SCAN

**Client Sample ID: VMP-32-5-020513**

**Lab ID#: 1302156A-17A**

| | | | | |
|---|---|---|---|---|
| Ethanol | 5.0 | 6.5 | 9.5 | 12 |
| Acetone | 13 | 4.6 J | 30 | 11 J |
| 2-Propanol | 5.0 | 5.5 | 12 | 13 |
| Carbon Disulfide | 5.0 | ~~0.94 J~~ U | 16 | ~~2.9 J~~ U |
| Methylene Chloride | 13 | ~~0.23 J~~ U | 44 | ~~0.81 J~~ U |
| Tetrahydrofuran | 1.3 | 0.47 J | 3.7 | 1.4 J |
| 2,2,4-Trimethylpentane | 1.3 | 1.8 | 5.9 | 8.6 |
| Benzene | 1.3 | 1.3 | 4.0 | 4.2 |
| Toluene | 1.3 | ~~0.12 J~~ U | 4.7 | ~~0.44 J~~ U |
| Tetrachloroethene | 1.3 | ~~0.13 J~~ U | 8.5 | ~~0.90 J~~ U |
| Propylbenzene | 1.3 | ~~0.14 J~~ U | 6.2 | ~~0.71 J~~ U |
| 4-Ethyltoluene | 1.3 | ~~0.22 J~~ U | 6.2 | ~~1.1 J~~ U |
| 1,2,4-Trimethylbenzene | 1.3 | ~~0.42 J~~ U | 6.2 | ~~2.1 J~~ U |
| 1,3-Dichlorobenzene | 1.3 | ~~0.19 J~~ U | 7.6 | ~~1.1 J~~ U |
| 1,4-Dichlorobenzene | 1.3 | ~~0.20 J~~ U | 7.6 | ~~1.2 J~~ U |
| 1,2,4-Trichlorobenzene | 5.0 | ~~0.63 J~~ U | 37 | ~~4.6 J~~ U |
| Isopentane | 5.0 | 0.77 J | 15 | 2.3 J |

**Client Sample ID: VMP-32-10-020513**

**Lab ID#: 1302156A-18A**

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 1.3 | 0.52 J | 6.2 | 2.6 J |
| Freon 11 | 1.3 | ~~0.25 J~~ U | 7.1 | ~~1.4 J~~ U |
| Ethanol | 5.0 | 7.2 | 9.5 | 14 |
| Acetone | 13 | 3.9 J | 30 | 9.2 J |
| 2-Propanol | 5.0 | 3.6 J | 12 | 8.9 J |
| Carbon Disulfide | 5.0 | ~~0.80 J~~ U | 16 | ~~2.5 J~~ U |
| Methylene Chloride | 13 | ~~0.23 J~~ U | 44 | ~~0.79 J~~ U |
| Tetrahydrofuran | 1.3 | 0.47 J | 3.7 | 1.4 J |
| 2,2,4-Trimethylpentane | 1.3 | 1.8 | 5.9 | 8.4 |
| Benzene | 1.3 | 1.6 | 4.0 | 5.1 |
| Toluene | 1.3 | ~~0.11 J~~ U | 4.7 | ~~0.42 J~~ U |
| Tetrachloroethene | 1.3 | ~~0.13 J~~ U | 8.5 | ~~0.90 J~~ U |
| 4-Ethyltoluene | 1.3 | ~~0.11 J~~ U | 6.2 | ~~0.55 J~~ U |

eurofins | Air Toxics

# Summary of Detected Compounds
# EPA METHOD TO-15 GC/MS FULL SCAN

**Client Sample ID: VMP-32-10-020513**

**Lab ID#: 1302156A-18A**

| | | | | |
|---|---|---|---|---|
| 1,2,4-Trichlorobenzene | 5.0 | ~~0.39 J~~ U | 37 | ~~2.9 J~~ U |

**Client Sample ID: VMP-32-20-020513**

**Lab ID#: 1302156A-19A**

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 1.4 | 0.49 J | 7.0 | 2.4 J |
| Freon 11 | 1.4 | ~~0.23 J~~ U | 7.9 | ~~1.3 J~~ U |
| Ethanol | 5.6 | 1.8 J | 11 | 3.5 J |
| Acetone | 14 | 4.2 J | 33 | 9.9 J |
| 2-Propanol | 5.6 | 2.6 J | 14 | 6.4 J |
| Carbon Disulfide | 5.6 | ~~0.80 J~~ U | 18 | ~~2.5 J~~ U |
| Methylene Chloride | 14 | ~~0.18 J~~ U | 49 | ~~0.63 J~~ U |
| Chloroform | 1.4 | 0.26 J | 6.9 | 1.3 J |
| 2,2,4-Trimethylpentane | 1.4 | 6.1 | 6.6 | 28 |
| Benzene | 1.4 | 0.83 J | 4.5 | 2.7 J |
| 4-Methyl-2-pentanone | 1.4 | 0.80 J | 5.8 | 3.3 J |
| Toluene | 1.4 | ~~0.13 J~~ U | 5.3 | ~~0.49 J~~ U |
| Tetrachloroethene | 1.4 | ~~0.24 J~~ U | 9.6 | ~~1.6 J~~ U |
| 1,2,4-Trichlorobenzene | 5.6 | ~~0.43 J~~ U | 42 | ~~3.2 J~~ U |

**Client Sample ID: VMP-53-5-020513**

**Lab ID#: 1302156A-20A**

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 1.3 | 0.44 J | 6.4 | 2.2 J |
| Freon 11 | 1.3 | ~~0.25 J~~ U | 7.2 | ~~1.4 J~~ U |
| Ethanol | 5.2 | 1.4 J | 9.7 | 2.7 J |
| Acetone | 13 | 6.5 J | 31 | 15 J |
| 2-Propanol | 5.2 | 1.2 J | 13 | 2.8 J |
| Carbon Disulfide | 5.2 | ~~1.0 J~~ U | 16 | ~~3.2 J~~ U |
| Hexane | 1.3 | 0.26 J | 4.5 | 0.92 J |
| 2,2,4-Trimethylpentane | 1.3 | 0.44 J | 6.0 | 2.0 J |
| Toluene | 1.3 | ~~0.11 J~~ U | 4.9 | ~~0.42 J~~ U |

eurofins | Air Toxics

# Summary of Detected Compounds
# EPA METHOD TO-15 GC/MS FULL SCAN

**Client Sample ID: VMP-53-5-020513**

**Lab ID#: 1302156A-20A**

| | | | | |
|---|---|---|---|---|
| Tetrachloroethene | 1.3 | ~~0.18 J~~ U | 8.8 | ~~1.2 J~~ U |
| Butane | 5.2 | 1.3 J | 12 | 3.2 J |
| Isopentane | 5.2 | 0.58 J | 15 | 1.7 J |

**Client Sample ID: VMP-53-10-020513**

**Lab ID#: 1302156A-21A**

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 1.3 | 0.56 J | 6.5 | 2.8 J |
| Freon 11 | 1.3 | ~~0.22 J~~ U | 7.4 | ~~1.3 J~~ U |
| Ethanol | 5.3 | 0.93 J | 9.9 | 1.8 J |
| Acetone | 13 | 4.0 J | 31 | 9.4 J |
| 2-Propanol | 5.3 | 2.1 J | 13 | 5.2 J |
| Carbon Disulfide | 5.3 | ~~0.76 J~~ U | 16 | ~~2.4 J~~ U |
| Hexane | 1.3 | 1.1 J | 4.6 | 4.0 J |
| Cyclohexane | 1.3 | 1.2 J | 4.5 | 4.3 J |
| 2,2,4-Trimethylpentane | 1.3 | 0.81 J | 6.2 | 3.8 J |
| Benzene | 1.3 | 18 | 4.2 | 59 |
| Heptane | 1.3 | 0.40 J | 5.4 | 1.6 J |
| Toluene | 1.3 | ~~0.15 J~~ U | 5.0 | ~~0.58 J~~ U |
| Butane | 5.3 | 2.2 J | 12 | 5.1 J |
| Isopentane | 5.3 | 4.3 J | 16 | 13 J |

**Client Sample ID: VMP-53-10-020513-DUP**

**Lab ID#: 1302156A-22A**

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 1.2 | 0.49 J | 6.1 | 2.4 J |
| Freon 11 | 1.2 | ~~0.21 J~~ U | 6.9 | ~~1.2 J~~ U |
| Acetone | 12 | 4.0 J | 29 | 9.6 J |
| 2-Propanol | 4.9 | 0.57 J | 12 | 1.4 J |
| Carbon Disulfide | 4.9 | ~~0.60 J~~ U | 15 | ~~1.9 J~~ U |
| Hexane | 1.2 | 0.60 J | 4.4 | 2.1 J |
| 2,2,4-Trimethylpentane | 1.2 | ~~0.22 J~~ U | 5.8 | ~~1.0 J~~ U |

eurofins | Air Toxics

# Summary of Detected Compounds
# EPA METHOD TO-15 GC/MS FULL SCAN

**Client Sample ID: VMP-53-10-020513-DUP**

**Lab ID#: 1302156A-22A**

| | | | | |
|---|---|---|---|---|
| Benzene | 1.2 | 5.4 | 3.9 | 17 |
| Heptane | 1.2 | 0.32 J | 5.1 | 1.3 J |
| Toluene | 1.2 | ~~0.12 J~~ U | 4.6 | ~~0.47 J~~ U |
| Butane | 4.9 | 1.4 J | 12 | 3.2 J |
| Isopentane | 4.9 | 2.2 J | 14 | 6.5 J |

**Client Sample ID: VMP-53-20-020513**

**Lab ID#: 1302156A-23A**

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 1.3 | 0.52 J | 6.5 | 2.6 J |
| Freon 11 | 1.3 | ~~0.23 J~~ U | 7.4 | ~~1.3 J~~ U |
| Ethanol | 5.3 | 1.7 J | 9.9 | 3.2 J |
| Acetone | 13 | 4.7 J | 31 | 11 J |
| 2-Propanol | 5.3 | 0.70 J | 13 | 1.7 J |
| Carbon Disulfide | 5.3 | ~~0.74 J~~ U | 16 | ~~2.3 J~~ U |
| Hexane | 1.3 | 0.45 J | 4.6 | 1.6 J |
| Chloroform | 1.3 | 1.0 J | 6.4 | 5.1 J |
| 2,2,4-Trimethylpentane | 1.3 | 0.51 J | 6.2 | 2.4 J |
| Benzene | 1.3 | 27 | 4.2 | 86 |
| Toluene | 1.3 | ~~0.28 J~~ U | 5.0 | ~~1.0 J~~ U |
| Tetrachloroethene | 1.3 | ~~0.15 J~~ U | 9.0 | ~~1.0 J~~ U |
| Propylbenzene | 1.3 | ~~0.14 J~~ U | 6.5 | ~~0.67 J~~ U |
| 1,2,4-Trichlorobenzene | 5.3 | ~~0.36 J~~ U | 39 | ~~2.7 J~~ U |
| Isopentane | 5.3 | 2.0 J | 16 | 6.0 J |

**Client Sample ID: VMP-53-30-020513**

**Lab ID#: 1302156A-24A**

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 1.3 | 0.52 J | 6.6 | 2.6 J |
| Freon 11 | 1.3 | ~~0.23 J~~ U | 7.6 | ~~1.3 J~~ U |
| Acetone | 13 | 3.2 J | 32 | 7.6 J |
| 2-Propanol | 5.4 | 0.51 J | 13 | 1.2 J |

eurofins | Air Toxics

# Summary of Detected Compounds
# EPA METHOD TO-15 GC/MS FULL SCAN

**Client Sample ID: VMP-53-30-020513**

**Lab ID#: 1302156A-24A**

| | | | | |
|---|---|---|---|---|
| Carbon Disulfide | 5.4 | ~~0.77 J~~ U | 17 | ~~2.4 J~~ U |
| Hexane | 1.3 | 0.23 J | 4.7 | 0.81 J |
| Chloroform | 1.3 | 2.4 | 6.6 | 12 |
| 2,2,4-Trimethylpentane | 1.3 | 0.50 J | 6.3 | 2.3 J |
| Toluene | 1.3 | ~~0.16 J~~ U | 5.1 | ~~0.58 J~~ U |
| Tetrachloroethene | 1.3 | ~~0.17 J~~ U | 9.1 | ~~1.2 J~~ U |

**Client Sample ID: VMP-54-5-020613**

**Lab ID#: 1302156A-25A**

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 1.4 | 0.42 J | 6.8 | 2.1 J |
| Freon 11 | 1.4 | ~~0.22 J~~ U | 7.8 | ~~1.2 J~~ U |
| Ethanol | 5.5 | 2.0 J | 10 | 3.7 J |
| Acetone | 14 | 3.8 J | 33 | 9.2 J |
| 2-Propanol | 5.5 | 2.4 J | 14 | 5.8 J |
| Carbon Disulfide | 5.5 | ~~1.2 J~~ U | 17 | ~~3.7 J~~ U |
| Hexane | 1.4 | 1.7 | 4.9 | 6.0 |
| Cyclohexane | 1.4 | 0.77 J | 4.8 | 2.6 J |
| 2,2,4-Trimethylpentane | 1.4 | 4.8 | 6.4 | 22 |
| Benzene | 1.4 | 0.74 J | 4.4 | 2.4 J |
| Heptane | 1.4 | 1.2 J | 5.6 | 5.0 J |
| Toluene | 1.4 | 2.4 | 5.2 | 9.2 |
| Tetrachloroethene | 1.4 | ~~0.19 J~~ U | 9.4 | ~~1.3 J~~ U |
| Ethyl Benzene | 1.4 | 2.6 | 6.0 | 11 |
| m,p-Xylene | 1.4 | 8.4 | 6.0 | 36 |
| o-Xylene | 1.4 | 4.7 | 6.0 | 20 |
| Cumene | 1.4 | ~~0.68 J~~ U | 6.8 | ~~3.4 J~~ U |
| Propylbenzene | 1.4 | 2.2 | 6.8 | 11 |
| 4-Ethyltoluene | 1.4 | 8.7 | 6.8 | 43 |
| 1,3,5-Trimethylbenzene | 1.4 | 2.9 | 6.8 | 14 |
| 1,2,4-Trimethylbenzene | 1.4 | 9.6 | 6.8 | 47 |
| Butane | 5.5 | 10 | 13 | 25 |
| Isopentane | 5.5 | 9.4 | 16 | 28 |

eurofins | Air Toxics

# Summary of Detected Compounds
# EPA METHOD TO-15 GC/MS FULL SCAN

**Client Sample ID: VMP-54-10-020613**

**Lab ID#: 1302156A-26A**

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 1.4 | 0.58 J | 7.0 | 2.8 J |
| Freon 11 | 1.4 | ~~0.20 J~~ | 7.9 | ~~1.1 J~~ |
| Ethanol | 5.6 | 1.2 J | 11 | 2.2 J |
| Acetone | 14 | 4.0 J | 33 | 9.4 J |
| 2-Propanol | 5.6 | 1.7 J | 14 | 4.2 J |
| Carbon Disulfide | 5.6 | ~~0.68 J~~ | 18 | ~~2.1 J~~ |
| Methylene Chloride | 14 | ~~0.24 J~~ | 49 | ~~0.82 J~~ |
| Hexane | 1.4 | 0.50 J | 5.0 | 1.7 J |
| 2,2,4-Trimethylpentane | 1.4 | 0.90 J | 6.6 | 4.2 J |
| Heptane | 1.4 | 0.32 J | 5.8 | 1.3 J |
| Toluene | 1.4 | 0.97 J | 5.3 | 3.6 J |
| Tetrachloroethene | 1.4 | ~~0.48 J~~ | 9.6 | ~~3.2 J~~ |
| Ethyl Benzene | 1.4 | 0.78 J | 6.1 | 3.4 J |
| m,p-Xylene | 1.4 | 2.1 | 6.1 | 9.1 |
| o-Xylene | 1.4 | 0.95 J | 6.1 | 4.1 J |
| Propylbenzene | 1.4 | ~~0.38 J~~ | 6.9 | ~~1.9 J~~ |
| 4-Ethyltoluene | 1.4 | 1.3 J | 6.9 | 6.4 J |
| 1,3,5-Trimethylbenzene | 1.4 | ~~0.40 J~~ | 6.9 | ~~2.0 J~~ |
| 1,2,4-Trimethylbenzene | 1.4 | ~~1.0 J~~ | 6.9 | ~~5.2 J~~ |
| Butane | 5.6 | 2.1 J | 13 | 5.1 J |
| Isopentane | 5.6 | 1.3 J | 17 | 3.9 J |

eurofins | Air Toxics

**Client Sample ID: VMP-2-8.5-020513**

**Lab ID#: 1302156A-01A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p021411** | **Date of Collection: 2/5/13 2:05:00 PM** | |
| **Dil. Factor:** | **2.96** | **Date of Analysis: 2/14/13 03:28 PM** | |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 1.5 | 0.46 J | 7.3 | 2.3 J |
| Freon 114 | 1.5 | Not Detected | 10 | Not Detected |
| Chloromethane | 15 | Not Detected | 30 | Not Detected |
| Vinyl Chloride | 1.5 | Not Detected | 3.8 | Not Detected |
| 1,3-Butadiene | 1.5 | Not Detected | 3.3 | Not Detected |
| Bromomethane | 15 | Not Detected | 57 | Not Detected |
| Chloroethane | 5.9 | Not Detected | 16 | Not Detected |
| Freon 11 | 1.5 | ~~0.19 J~~ U | 8.3 | ~~1.1 J~~ U |
| Ethanol | 5.9 | 1.4 J | 11 | 2.6 J |
| Freon 113 | 1.5 | Not Detected | 11 | Not Detected |
| 1,1-Dichloroethene | 1.5 | Not Detected | 5.9 | Not Detected |
| Acetone | 15 | 2.5 J | 35 | 6.0 J |
| 2-Propanol | 5.9 | 4.2 J | 14 | 10 J |
| Carbon Disulfide | 5.9 | ~~0.77 J~~ U | 18 | ~~2.4 J~~ U |
| 3-Chloropropene | 5.9 | Not Detected | 18 | Not Detected |
| Methylene Chloride | 15 | ~~0.22 J~~ U | 51 | ~~0.78 J~~ U |
| Methyl tert-butyl ether | 1.5 | Not Detected | 5.3 | Not Detected |
| trans-1,2-Dichloroethene | 1.5 | Not Detected | 5.9 | Not Detected |
| Hexane | 1.5 | 4.2 | 5.2 | 15 |
| 1,1-Dichloroethane | 1.5 | Not Detected | 6.0 | Not Detected |
| 2-Butanone (Methyl Ethyl Ketone) | 5.9 | Not Detected | 17 | Not Detected |
| cis-1,2-Dichloroethene | 1.5 | Not Detected | 5.9 | Not Detected |
| Tetrahydrofuran | 1.5 | Not Detected | 4.4 | Not Detected |
| Chloroform | 1.5 | Not Detected | 7.2 | Not Detected |
| 1,1,1-Trichloroethane | 1.5 | Not Detected | 8.1 | Not Detected |
| Cyclohexane | 1.5 | 2.0 | 5.1 | 7.1 |
| Carbon Tetrachloride | 1.5 | Not Detected | 9.3 | Not Detected |
| 2,2,4-Trimethylpentane | 1.5 | 8.2 | 6.9 | 38 |
| Benzene | 1.5 | 0.68 J | 4.7 | 2.2 J |
| 1,2-Dichloroethane | 1.5 | Not Detected | 6.0 | Not Detected |
| Heptane | 1.5 | 2.2 | 6.1 | 9.0 |
| Trichloroethene | 1.5 | Not Detected | 8.0 | Not Detected |
| 1,2-Dichloropropane | 1.5 | Not Detected | 6.8 | Not Detected |
| 1,4-Dioxane | 5.9 | Not Detected | 21 | Not Detected |
| Bromodichloromethane | 1.5 | Not Detected | 9.9 | Not Detected |
| cis-1,3-Dichloropropene | 1.5 | Not Detected | 6.7 | Not Detected |
| 4-Methyl-2-pentanone | 1.5 | 0.38 J | 6.1 | 1.5 J |
| Toluene | 1.5 | 1.9 | 5.6 | 7.3 |
| trans-1,3-Dichloropropene | 1.5 | Not Detected | 6.7 | Not Detected |
| 1,1,2-Trichloroethane | 1.5 | Not Detected | 8.1 | Not Detected |
| Tetrachloroethene | 1.5 | ~~0.32 J~~ U | 10 | ~~2.2 J~~ U |
| 2-Hexanone | 5.9 | Not Detected | 24 | Not Detected |

eurofins | Air Toxics

**Client Sample ID: VMP-2-8.5-020513**

**Lab ID#: 1302156A-01A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p021411** | **Date of Collection: 2/5/13 2:05:00 PM** | |
| **Dil. Factor:** | **2.96** | **Date of Analysis: 2/14/13 03:28 PM** | |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Dibromochloromethane | 1.5 | Not Detected | 13 | Not Detected |
| 1,2-Dibromoethane (EDB) | 1.5 | Not Detected | 11 | Not Detected |
| Chlorobenzene | 1.5 | Not Detected | 6.8 | Not Detected |
| Ethyl Benzene | 1.5 | 0.58 J | 6.4 | 2.5 J |
| m,p-Xylene | 1.5 | 0.82 J | 6.4 | 3.6 J |
| o-Xylene | 1.5 | 0.51 J | 6.4 | 2.2 J |
| Styrene | 1.5 | Not Detected | 6.3 | Not Detected |
| Bromoform | 1.5 | Not Detected | 15 | Not Detected |
| Cumene | 1.5 | Not Detected | 7.3 | Not Detected |
| 1,1,2,2-Tetrachloroethane | 1.5 | Not Detected | 10 | Not Detected |
| Propylbenzene | 1.5 | Not Detected | 7.3 | Not Detected |
| 4-Ethyltoluene | 1.5 | Not Detected | 7.3 | Not Detected |
| 1,3,5-Trimethylbenzene | 1.5 | Not Detected | 7.3 | Not Detected |
| 1,2,4-Trimethylbenzene | 1.5 | Not Detected | 7.3 | Not Detected |
| 1,3-Dichlorobenzene | 1.5 | Not Detected | 8.9 | Not Detected |
| 1,4-Dichlorobenzene | 1.5 | Not Detected | 8.9 | Not Detected |
| alpha-Chlorotoluene | 1.5 | Not Detected | 7.7 | Not Detected |
| 1,2-Dichlorobenzene | 1.5 | Not Detected | 8.9 | Not Detected |
| 1,2,4-Trichlorobenzene | 5.9 | Not Detected | 44 | Not Detected |
| Hexachlorobutadiene | 5.9 | Not Detected | 63 | Not Detected |
| Butane | 5.9 | 16 | 14 | 38 |
| Isopentane | 5.9 | 20 | 17 | 59 |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| Toluene-d8 | 97 | 70-130 |
| 1,2-Dichloroethane-d4 | 86 | 70-130 |
| 4-Bromofluorobenzene | 96 | 70-130 |

eurofins | Air Toxics

**Client Sample ID: VMP-6-10-020513**

**Lab ID#: 1302156A-02A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | p021412 | **Date of Collection:** | 2/5/13 3:09:00 PM |
| **Dil. Factor:** | 2.76 | **Date of Analysis:** | 2/14/13 04:00 PM |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 1.4 | 0.47 J | 6.8 | 2.3 J |
| Freon 114 | 1.4 | Not Detected | 9.6 | Not Detected |
| Chloromethane | 14 | Not Detected | 28 | Not Detected |
| Vinyl Chloride | 1.4 | Not Detected | 3.5 | Not Detected |
| 1,3-Butadiene | 1.4 | Not Detected | 3.0 | Not Detected |
| Bromomethane | 14 | Not Detected | 54 | Not Detected |
| Chloroethane | 5.5 | Not Detected | 14 | Not Detected |
| Freon 11 | 1.4 | ~~0.24 J~~ U | 7.8 | ~~1.3 J~~ U |
| Ethanol | 5.5 | 0.91 J | 10 | 1.7 J |
| Freon 113 | 1.4 | Not Detected | 10 | Not Detected |
| 1,1-Dichloroethene | 1.4 | Not Detected | 5.5 | Not Detected |
| Acetone | 14 | 3.8 J | 33 | 9.0 J |
| 2-Propanol | 5.5 | 4.1 J | 14 | 10 J |
| Carbon Disulfide | 5.5 | ~~0.70 J~~ U | 17 | ~~2.2 J~~ U |
| 3-Chloropropene | 5.5 | Not Detected | 17 | Not Detected |
| Methylene Chloride | 14 | ~~0.68 J~~ U | 48 | ~~2.4 J~~ U |
| Methyl tert-butyl ether | 1.4 | Not Detected | 5.0 | Not Detected |
| trans-1,2-Dichloroethene | 1.4 | Not Detected | 5.5 | Not Detected |
| Hexane | 1.4 | 0.40 J | 4.9 | 1.4 J |
| 1,1-Dichloroethane | 1.4 | Not Detected | 5.6 | Not Detected |
| 2-Butanone (Methyl Ethyl Ketone) | 5.5 | Not Detected | 16 | Not Detected |
| cis-1,2-Dichloroethene | 1.4 | Not Detected | 5.5 | Not Detected |
| Tetrahydrofuran | 1.4 | Not Detected | 4.1 | Not Detected |
| Chloroform | 1.4 | Not Detected | 6.7 | Not Detected |
| 1,1,1-Trichloroethane | 1.4 | Not Detected | 7.5 | Not Detected |
| Cyclohexane | 1.4 | Not Detected | 4.8 | Not Detected |
| Carbon Tetrachloride | 1.4 | Not Detected | 8.7 | Not Detected |
| 2,2,4-Trimethylpentane | 1.4 | 0.33 J | 6.4 | 1.6 J |
| Benzene | 1.4 | 14 | 4.4 | 46 |
| 1,2-Dichloroethane | 1.4 | Not Detected | 5.6 | Not Detected |
| Heptane | 1.4 | Not Detected | 5.6 | Not Detected |
| Trichloroethene | 1.4 | Not Detected | 7.4 | Not Detected |
| 1,2-Dichloropropane | 1.4 | Not Detected | 6.4 | Not Detected |
| 1,4-Dioxane | 5.5 | Not Detected | 20 | Not Detected |
| Bromodichloromethane | 1.4 | Not Detected | 9.2 | Not Detected |
| cis-1,3-Dichloropropene | 1.4 | Not Detected | 6.3 | Not Detected |
| 4-Methyl-2-pentanone | 1.4 | Not Detected | 5.6 | Not Detected |
| Toluene | 1.4 | ~~0.11 J~~ U | 5.2 | ~~0.42 J~~ U |
| trans-1,3-Dichloropropene | 1.4 | Not Detected | 6.3 | Not Detected |
| 1,1,2-Trichloroethane | 1.4 | Not Detected | 7.5 | Not Detected |
| Tetrachloroethene | 1.4 | ~~0.17 J~~ U | 9.4 | ~~1.2 J~~ U |
| 2-Hexanone | 5.5 | Not Detected | 23 | Not Detected |

eurofins | Air Toxics

**Client Sample ID: VMP-6-10-020513**

**Lab ID#: 1302156A-02A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p021412** | **Date of Collection: 2/5/13 3:09:00 PM** | |
| **Dil. Factor:** | **2.76** | **Date of Analysis: 2/14/13 04:00 PM** | |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Dibromochloromethane | 1.4 | Not Detected | 12 | Not Detected |
| 1,2-Dibromoethane (EDB) | 1.4 | Not Detected | 11 | Not Detected |
| Chlorobenzene | 1.4 | Not Detected | 6.4 | Not Detected |
| Ethyl Benzene | 1.4 | Not Detected | 6.0 | Not Detected |
| m,p-Xylene | 1.4 | Not Detected | 6.0 | Not Detected |
| o-Xylene | 1.4 | Not Detected | 6.0 | Not Detected |
| Styrene | 1.4 | Not Detected | 5.9 | Not Detected |
| Bromoform | 1.4 | Not Detected | 14 | Not Detected |
| Cumene | 1.4 | Not Detected | 6.8 | Not Detected |
| 1,1,2,2-Tetrachloroethane | 1.4 | Not Detected | 9.5 | Not Detected |
| Propylbenzene | 1.4 | Not Detected | 6.8 | Not Detected |
| 4-Ethyltoluene | 1.4 | Not Detected | 6.8 | Not Detected |
| 1,3,5-Trimethylbenzene | 1.4 | Not Detected | 6.8 | Not Detected |
| 1,2,4-Trimethylbenzene | 1.4 | Not Detected | 6.8 | Not Detected |
| 1,3-Dichlorobenzene | 1.4 | Not Detected | 8.3 | Not Detected |
| 1,4-Dichlorobenzene | 1.4 | Not Detected | 8.3 | Not Detected |
| alpha-Chlorotoluene | 1.4 | Not Detected | 7.1 | Not Detected |
| 1,2-Dichlorobenzene | 1.4 | Not Detected | 8.3 | Not Detected |
| 1,2,4-Trichlorobenzene | 5.5 | ~~0.38 J~~ U | 41 | ~~2.8 J~~ U |
| Hexachlorobutadiene | 5.5 | Not Detected | 59 | Not Detected |
| Butane | 5.5 | 1.5 J | 13 | 3.6 J |
| Isopentane | 5.5 | 1.1 J | 16 | 3.2 J |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| Toluene-d8 | 97 | 70-130 |
| 1,2-Dichloroethane-d4 | 85 | 70-130 |
| 4-Bromofluorobenzene | 98 | 70-130 |

eurofins | Air Toxics

**Client Sample ID: VMP-6-31.5-020513**

**Lab ID#: 1302156A-03A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p021413** | **Date of Collection:** | **2/5/13 2:26:00 PM** |
| **Dil. Factor:** | **2.58** | **Date of Analysis:** | **2/14/13 04:38 PM** |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 1.3 | 0.52 J | 6.4 | 2.6 J |
| Freon 114 | 1.3 | Not Detected | 9.0 | Not Detected |
| Chloromethane | 13 | Not Detected | 27 | Not Detected |
| Vinyl Chloride | 1.3 | Not Detected | 3.3 | Not Detected |
| 1,3-Butadiene | 1.3 | Not Detected | 2.8 | Not Detected |
| Bromomethane | 13 | Not Detected | 50 | Not Detected |
| Chloroethane | 5.2 | Not Detected | 14 | Not Detected |
| Freon 11 | 1.3 | ~~0.26 J~~ | 7.2 | ~~1.4 J~~ |
| Ethanol | 5.2 | Not Detected | 9.7 | Not Detected |
| Freon 113 | 1.3 | Not Detected | 9.9 | Not Detected |
| 1,1-Dichloroethene | 1.3 | Not Detected | 5.1 | Not Detected |
| Acetone | 13 | 4.0 J | 31 | 9.5 J |
| 2-Propanol | 5.2 | 46 | 13 | 110 |
| Carbon Disulfide | 5.2 | ~~0.85 J~~ | 16 | ~~2.6 J~~ |
| 3-Chloropropene | 5.2 | Not Detected | 16 | Not Detected |
| Methylene Chloride | 13 | 1.4 J | 45 | 5.0 J |
| Methyl tert-butyl ether | 1.3 | Not Detected | 4.6 | Not Detected |
| trans-1,2-Dichloroethene | 1.3 | Not Detected | 5.1 | Not Detected |
| Hexane | 1.3 | 0.26 J | 4.5 | 0.91 J |
| 1,1-Dichloroethane | 1.3 | Not Detected | 5.2 | Not Detected |
| 2-Butanone (Methyl Ethyl Ketone) | 5.2 | Not Detected | 15 | Not Detected |
| cis-1,2-Dichloroethene | 1.3 | Not Detected | 5.1 | Not Detected |
| Tetrahydrofuran | 1.3 | Not Detected | 3.8 | Not Detected |
| Chloroform | 1.3 | 0.89 J | 6.3 | 4.3 J |
| 1,1,1-Trichloroethane | 1.3 | Not Detected | 7.0 | Not Detected |
| Cyclohexane | 1.3 | Not Detected | 4.4 | Not Detected |
| Carbon Tetrachloride | 1.3 | Not Detected | 8.1 | Not Detected |
| 2,2,4-Trimethylpentane | 1.3 | 12 | 6.0 | 58 |
| Benzene | 1.3 | 1.2 J | 4.1 | 4.0 J |
| 1,2-Dichloroethane | 1.3 | Not Detected | 5.2 | Not Detected |
| Heptane | 1.3 | Not Detected | 5.3 | Not Detected |
| Trichloroethene | 1.3 | Not Detected | 6.9 | Not Detected |
| 1,2-Dichloropropane | 1.3 | Not Detected | 6.0 | Not Detected |
| 1,4-Dioxane | 5.2 | Not Detected | 18 | Not Detected |
| Bromodichloromethane | 1.3 | Not Detected | 8.6 | Not Detected |
| cis-1,3-Dichloropropene | 1.3 | Not Detected | 5.8 | Not Detected |
| 4-Methyl-2-pentanone | 1.3 | Not Detected | 5.3 | Not Detected |
| Toluene | 1.3 | ~~0.11 J~~ | 4.9 | ~~0.42 J~~ |
| trans-1,3-Dichloropropene | 1.3 | Not Detected | 5.8 | Not Detected |
| 1,1,2-Trichloroethane | 1.3 | Not Detected | 7.0 | Not Detected |
| Tetrachloroethene | 1.3 | ~~0.14 J~~ | 8.8 | ~~0.96 J~~ |
| 2-Hexanone | 5.2 | Not Detected | 21 | Not Detected |

eurofins | Air Toxics

**Client Sample ID: VMP-6-31.5-020513**

**Lab ID#: 1302156A-03A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p021413** | **Date of Collection: 2/5/13 2:26:00 PM** | |
| **Dil. Factor:** | **2.58** | **Date of Analysis: 2/14/13 04:38 PM** | |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Dibromochloromethane | 1.3 | Not Detected | 11 | Not Detected |
| 1,2-Dibromoethane (EDB) | 1.3 | Not Detected | 9.9 | Not Detected |
| Chlorobenzene | 1.3 | Not Detected | 5.9 | Not Detected |
| Ethyl Benzene | 1.3 | Not Detected | 5.6 | Not Detected |
| m,p-Xylene | 1.3 | Not Detected | 5.6 | Not Detected |
| o-Xylene | 1.3 | Not Detected | 5.6 | Not Detected |
| Styrene | 1.3 | Not Detected | 5.5 | Not Detected |
| Bromoform | 1.3 | Not Detected | 13 | Not Detected |
| Cumene | 1.3 | Not Detected | 6.3 | Not Detected |
| 1,1,2,2-Tetrachloroethane | 1.3 | Not Detected | 8.8 | Not Detected |
| Propylbenzene | 1.3 | Not Detected | 6.3 | Not Detected |
| 4-Ethyltoluene | 1.3 | Not Detected | 6.3 | Not Detected |
| 1,3,5-Trimethylbenzene | 1.3 | Not Detected | 6.3 | Not Detected |
| 1,2,4-Trimethylbenzene | 1.3 | Not Detected | 6.3 | Not Detected |
| 1,3-Dichlorobenzene | 1.3 | Not Detected | 7.8 | Not Detected |
| 1,4-Dichlorobenzene | 1.3 | Not Detected | 7.8 | Not Detected |
| alpha-Chlorotoluene | 1.3 | Not Detected | 6.7 | Not Detected |
| 1,2-Dichlorobenzene | 1.3 | Not Detected | 7.8 | Not Detected |
| 1,2,4-Trichlorobenzene | 5.2 | Not Detected | 38 | Not Detected |
| Hexachlorobutadiene | 5.2 | Not Detected | 55 | Not Detected |
| Butane | 5.2 | 12 | 12 | 30 |
| Isopentane | 5.2 | 2.7 J | 15 | 8.0 J |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| Toluene-d8 | 100 | 70-130 |
| 1,2-Dichloroethane-d4 | 85 | 70-130 |
| 4-Bromofluorobenzene | 96 | 70-130 |

eurofins | Air Toxics

**Client Sample ID: VMP-6-39-020513**

**Lab ID#: 1302156A-04A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | p021414 | **Date of Collection:** | 2/5/13 1:34:00 PM |
| **Dil. Factor:** | 2.64 | **Date of Analysis:** | 2/14/13 05:12 PM |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 1.3 | 0.47 J | 6.5 | 2.3 J |
| Freon 114 | 1.3 | Not Detected | 9.2 | Not Detected |
| Chloromethane | 13 | Not Detected | 27 | Not Detected |
| Vinyl Chloride | 1.3 | Not Detected | 3.4 | Not Detected |
| 1,3-Butadiene | 1.3 | Not Detected | 2.9 | Not Detected |
| Bromomethane | 13 | Not Detected | 51 | Not Detected |
| Chloroethane | 5.3 | Not Detected | 14 | Not Detected |
| Freon 11 | 1.3 | ~~0.23 J~~ U | 7.4 | ~~1.3 J~~ U |
| Ethanol | 5.3 | 2.2 J | 9.9 | 4.2 J |
| Freon 113 | 1.3 | Not Detected | 10 | Not Detected |
| 1,1-Dichloroethene | 1.3 | Not Detected | 5.2 | Not Detected |
| Acetone | 13 | 5.8 J | 31 | 14 J |
| 2-Propanol | 5.3 | 4.5 J | 13 | 11 J |
| Carbon Disulfide | 5.3 | ~~0.64 J~~ U | 16 | ~~2.0 J~~ U |
| 3-Chloropropene | 5.3 | Not Detected | 16 | Not Detected |
| Methylene Chloride | 13 | ~~0.16 J~~ U | 46 | ~~0.54 J~~ U |
| Methyl tert-butyl ether | 1.3 | Not Detected | 4.8 | Not Detected |
| trans-1,2-Dichloroethene | 1.3 | Not Detected | 5.2 | Not Detected |
| Hexane | 1.3 | 1.4 | 4.6 | 5.1 |
| 1,1-Dichloroethane | 1.3 | Not Detected | 5.3 | Not Detected |
| 2-Butanone (Methyl Ethyl Ketone) | 5.3 | Not Detected | 16 | Not Detected |
| cis-1,2-Dichloroethene | 1.3 | Not Detected | 5.2 | Not Detected |
| Tetrahydrofuran | 1.3 | Not Detected | 3.9 | Not Detected |
| Chloroform | 1.3 | Not Detected | 6.4 | Not Detected |
| 1,1,1-Trichloroethane | 1.3 | Not Detected | 7.2 | Not Detected |
| Cyclohexane | 1.3 | 3.0 | 4.5 | 10 |
| Carbon Tetrachloride | 1.3 | Not Detected | 8.3 | Not Detected |
| 2,2,4-Trimethylpentane | 1.3 | 140 | 6.2 | 630 |
| Benzene | 1.3 | 20 | 4.2 | 66 |
| 1,2-Dichloroethane | 1.3 | Not Detected | 5.3 | Not Detected |
| Heptane | 1.3 | 6.6 | 5.4 | 27 |
| Trichloroethene | 1.3 | Not Detected | 7.1 | Not Detected |
| 1,2-Dichloropropane | 1.3 | Not Detected | 6.1 | Not Detected |
| 1,4-Dioxane | 5.3 | Not Detected | 19 | Not Detected |
| Bromodichloromethane | 1.3 | Not Detected | 8.8 | Not Detected |
| cis-1,3-Dichloropropene | 1.3 | Not Detected | 6.0 | Not Detected |
| 4-Methyl-2-pentanone | 1.3 | Not Detected | 5.4 | Not Detected |
| Toluene | 1.3 | ~~0.18 J~~ U | 5.0 | ~~0.68 J~~ U |
| trans-1,3-Dichloropropene | 1.3 | Not Detected | 6.0 | Not Detected |
| 1,1,2-Trichloroethane | 1.3 | Not Detected | 7.2 | Not Detected |
| Tetrachloroethene | 1.3 | ~~0.16 J~~ U | 9.0 | ~~1.1 J~~ U |
| 2-Hexanone | 5.3 | Not Detected | 22 | Not Detected |

eurofins | Air Toxics

**Client Sample ID: VMP-6-39-020513**

**Lab ID#: 1302156A-04A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p021414** | **Date of Collection: 2/5/13 1:34:00 PM** | |
| **Dil. Factor:** | **2.64** | **Date of Analysis: 2/14/13 05:12 PM** | |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Dibromochloromethane | 1.3 | Not Detected | 11 | Not Detected |
| 1,2-Dibromoethane (EDB) | 1.3 | Not Detected | 10 | Not Detected |
| Chlorobenzene | 1.3 | Not Detected | 6.1 | Not Detected |
| Ethyl Benzene | 1.3 | 7.9 | 5.7 | 34 |
| m,p-Xylene | 1.3 | 5.3 | 5.7 | 23 |
| o-Xylene | 1.3 | Not Detected | 5.7 | Not Detected |
| Styrene | 1.3 | Not Detected | 5.6 | Not Detected |
| Bromoform | 1.3 | Not Detected | 14 | Not Detected |
| Cumene | 1.3 | 1.1 J | 6.5 | 5.6 J |
| 1,1,2,2-Tetrachloroethane | 1.3 | Not Detected | 9.1 | Not Detected |
| Propylbenzene | 1.3 | 2.5 | 6.5 | 12 |
| 4-Ethyltoluene | 1.3 | 2.5 | 6.5 | 12 |
| 1,3,5-Trimethylbenzene | 1.3 | 1.1 J | 6.5 | 5.5 J |
| 1,2,4-Trimethylbenzene | 1.3 | 4.9 | 6.5 | 24 |
| 1,3-Dichlorobenzene | 1.3 | Not Detected | 7.9 | Not Detected |
| 1,4-Dichlorobenzene | 1.3 | Not Detected | 7.9 | Not Detected |
| alpha-Chlorotoluene | 1.3 | Not Detected | 6.8 | Not Detected |
| 1,2-Dichlorobenzene | 1.3 | Not Detected | 7.9 | Not Detected |
| 1,2,4-Trichlorobenzene | 5.3 | Not Detected | 39 | Not Detected |
| Hexachlorobutadiene | 5.3 | Not Detected | 56 | Not Detected |
| Butane | 5.3 | Not Detected | 12 | Not Detected |
| Isopentane | 5.3 | 2.8 J | 16 | 8.2 J |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| Toluene-d8 | 102 | 70-130 |
| 1,2-Dichloroethane-d4 | 88 | 70-130 |
| 4-Bromofluorobenzene | 97 | 70-130 |

eurofins | Air Toxics

**Client Sample ID: VMP-15-5-020513**

**Lab ID#: 1302156A-05A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p021416** | **Date of Collection:** | **2/5/13 3:25:00 PM** |
| **Dil. Factor:** | **2.89** | **Date of Analysis:** | **2/14/13 06:26 PM** |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 1.4 | 0.39 J | 7.1 | 2.0 J |
| Freon 114 | 1.4 | Not Detected | 10 | Not Detected |
| Chloromethane | 14 | Not Detected | 30 | Not Detected |
| Vinyl Chloride | 1.4 | Not Detected | 3.7 | Not Detected |
| 1,3-Butadiene | 1.4 | Not Detected | 3.2 | Not Detected |
| Bromomethane | 14 | Not Detected | 56 | Not Detected |
| Chloroethane | 5.8 | Not Detected | 15 | Not Detected |
| Freon 11 | 1.4 | Not Detected | 8.1 | Not Detected |
| Ethanol | 5.8 | 1.8 J | 11 | 3.3 J |
| Freon 113 | 1.4 | Not Detected | 11 | Not Detected |
| 1,1-Dichloroethene | 1.4 | Not Detected | 5.7 | Not Detected |
| Acetone | 14 | 2.6 J | 34 | 6.0 J |
| 2-Propanol | 5.8 | 10 | 14 | 25 |
| Carbon Disulfide | 5.8 | ~~0.85 J~~ U | 18 | ~~2.7 J~~ U |
| 3-Chloropropene | 5.8 | Not Detected | 18 | Not Detected |
| Methylene Chloride | 14 | ~~0.34 J~~ U | 50 | ~~1.2 J~~ U |
| Methyl tert-butyl ether | 1.4 | Not Detected | 5.2 | Not Detected |
| trans-1,2-Dichloroethene | 1.4 | Not Detected | 5.7 | Not Detected |
| Hexane | 1.4 | Not Detected | 5.1 | Not Detected |
| 1,1-Dichloroethane | 1.4 | Not Detected | 5.8 | Not Detected |
| 2-Butanone (Methyl Ethyl Ketone) | 5.8 | Not Detected | 17 | Not Detected |
| cis-1,2-Dichloroethene | 1.4 | Not Detected | 5.7 | Not Detected |
| Tetrahydrofuran | 1.4 | Not Detected | 4.3 | Not Detected |
| Chloroform | 1.4 | Not Detected | 7.0 | Not Detected |
| 1,1,1-Trichloroethane | 1.4 | Not Detected | 7.9 | Not Detected |
| Cyclohexane | 1.4 | Not Detected | 5.0 | Not Detected |
| Carbon Tetrachloride | 1.4 | Not Detected | 9.1 | Not Detected |
| 2,2,4-Trimethylpentane | 1.4 | 1.3 J | 6.8 | 6.2 J |
| Benzene | 1.4 | 1.2 J | 4.6 | 4.0 J |
| 1,2-Dichloroethane | 1.4 | Not Detected | 5.8 | Not Detected |
| Heptane | 1.4 | Not Detected | 5.9 | Not Detected |
| Trichloroethene | 1.4 | Not Detected | 7.8 | Not Detected |
| 1,2-Dichloropropane | 1.4 | Not Detected | 6.7 | Not Detected |
| 1,4-Dioxane | 5.8 | Not Detected | 21 | Not Detected |
| Bromodichloromethane | 1.4 | Not Detected | 9.7 | Not Detected |
| cis-1,3-Dichloropropene | 1.4 | Not Detected | 6.6 | Not Detected |
| 4-Methyl-2-pentanone | 1.4 | Not Detected | 5.9 | Not Detected |
| Toluene | 1.4 | ~~0.14 J~~ U | 5.4 | ~~0.53 J~~ U |
| trans-1,3-Dichloropropene | 1.4 | Not Detected | 6.6 | Not Detected |
| 1,1,2-Trichloroethane | 1.4 | Not Detected | 7.9 | Not Detected |
| Tetrachloroethene | 1.4 | Not Detected | 9.8 | Not Detected |
| 2-Hexanone | 5.8 | Not Detected | 24 | Not Detected |

eurofins | Air Toxics

**Client Sample ID: VMP-15-5-020513**

**Lab ID#: 1302156A-05A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | p021416 | **Date of Collection:** | 2/5/13 3:25:00 PM |
| **Dil. Factor:** | 2.89 | **Date of Analysis:** | 2/14/13 06:26 PM |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Dibromochloromethane | 1.4 | Not Detected | 12 | Not Detected |
| 1,2-Dibromoethane (EDB) | 1.4 | Not Detected | 11 | Not Detected |
| Chlorobenzene | 1.4 | Not Detected | 6.6 | Not Detected |
| Ethyl Benzene | 1.4 | Not Detected | 6.3 | Not Detected |
| m,p-Xylene | 1.4 | Not Detected | 6.3 | Not Detected |
| o-Xylene | 1.4 | Not Detected | 6.3 | Not Detected |
| Styrene | 1.4 | Not Detected | 6.2 | Not Detected |
| Bromoform | 1.4 | Not Detected | 15 | Not Detected |
| Cumene | 1.4 | Not Detected | 7.1 | Not Detected |
| 1,1,2,2-Tetrachloroethane | 1.4 | Not Detected | 9.9 | Not Detected |
| Propylbenzene | 1.4 | Not Detected | 7.1 | Not Detected |
| 4-Ethyltoluene | 1.4 | ~~0.11 J~~ U | 7.1 | ~~0.54 J~~ U |
| 1,3,5-Trimethylbenzene | 1.4 | Not Detected | 7.1 | Not Detected |
| 1,2,4-Trimethylbenzene | 1.4 | Not Detected | 7.1 | Not Detected |
| 1,3-Dichlorobenzene | 1.4 | Not Detected | 8.7 | Not Detected |
| 1,4-Dichlorobenzene | 1.4 | Not Detected | 8.7 | Not Detected |
| alpha-Chlorotoluene | 1.4 | Not Detected | 7.5 | Not Detected |
| 1,2-Dichlorobenzene | 1.4 | Not Detected | 8.7 | Not Detected |
| 1,2,4-Trichlorobenzene | 5.8 | Not Detected | 43 | Not Detected |
| Hexachlorobutadiene | 5.8 | Not Detected | 62 | Not Detected |
| Butane | 5.8 | Not Detected | 14 | Not Detected |
| Isopentane | 5.8 | 0.66 J | 17 | 1.9 J |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| Toluene-d8 | 96 | 70-130 |
| 1,2-Dichloroethane-d4 | 86 | 70-130 |
| 4-Bromofluorobenzene | 94 | 70-130 |

eurofins | Air Toxics

**Client Sample ID: VMP-21-10-020513**

**Lab ID#: 1302156A-06A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p021417** | **Date of Collection:** | **2/5/13 3:30:00 PM** |
| **Dil. Factor:** | **2.69** | **Date of Analysis:** | **2/14/13 06:59 PM** |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 1.3 | 0.44 J | 6.6 | 2.2 J |
| Freon 114 | 1.3 | Not Detected | 9.4 | Not Detected |
| Chloromethane | 13 | Not Detected | 28 | Not Detected |
| Vinyl Chloride | 1.3 | Not Detected | 3.4 | Not Detected |
| 1,3-Butadiene | 1.3 | Not Detected | 3.0 | Not Detected |
| Bromomethane | 13 | Not Detected | 52 | Not Detected |
| Chloroethane | 5.4 | Not Detected | 14 | Not Detected |
| Freon 11 | 1.3 | ~~0.18 J~~ U | 7.6 | ~~1.0 J~~ U |
| Ethanol | 5.4 | 1.7 J | 10 | 3.3 J |
| Freon 113 | 1.3 | Not Detected | 10 | Not Detected |
| 1,1-Dichloroethene | 1.3 | Not Detected | 5.3 | Not Detected |
| Acetone | 13 | 2.7 J | 32 | 6.5 J |
| 2-Propanol | 5.4 | 2.5 J | 13 | 6.1 J |
| Carbon Disulfide | 5.4 | ~~0.53 J~~ U | 17 | ~~1.6 J~~ U |
| 3-Chloropropene | 5.4 | Not Detected | 17 | Not Detected |
| Methylene Chloride | 13 | ~~0.31 J~~ U | 47 | ~~1.1 J~~ U |
| Methyl tert-butyl ether | 1.3 | Not Detected | 4.8 | Not Detected |
| trans-1,2-Dichloroethene | 1.3 | Not Detected | 5.3 | Not Detected |
| Hexane | 1.3 | 0.79 J | 4.7 | 2.8 J |
| 1,1-Dichloroethane | 1.3 | Not Detected | 5.4 | Not Detected |
| 2-Butanone (Methyl Ethyl Ketone) | 5.4 | Not Detected | 16 | Not Detected |
| cis-1,2-Dichloroethene | 1.3 | Not Detected | 5.3 | Not Detected |
| Tetrahydrofuran | 1.3 | Not Detected | 4.0 | Not Detected |
| Chloroform | 1.3 | Not Detected | 6.6 | Not Detected |
| 1,1,1-Trichloroethane | 1.3 | Not Detected | 7.3 | Not Detected |
| Cyclohexane | 1.3 | 1.0 J | 4.6 | 3.6 J |
| Carbon Tetrachloride | 1.3 | Not Detected | 8.5 | Not Detected |
| 2,2,4-Trimethylpentane | 1.3 | 5.5 | 6.3 | 26 |
| Benzene | 1.3 | 13 | 4.3 | 41 |
| 1,2-Dichloroethane | 1.3 | Not Detected | 5.4 | Not Detected |
| Heptane | 1.3 | 0.47 J | 5.5 | 1.9 J |
| Trichloroethene | 1.3 | Not Detected | 7.2 | Not Detected |
| 1,2-Dichloropropane | 1.3 | Not Detected | 6.2 | Not Detected |
| 1,4-Dioxane | 5.4 | Not Detected | 19 | Not Detected |
| Bromodichloromethane | 1.3 | Not Detected | 9.0 | Not Detected |
| cis-1,3-Dichloropropene | 1.3 | Not Detected | 6.1 | Not Detected |
| 4-Methyl-2-pentanone | 1.3 | Not Detected | 5.5 | Not Detected |
| Toluene | 1.3 | ~~0.19 J~~ U | 5.1 | ~~0.70 J~~ U |
| trans-1,3-Dichloropropene | 1.3 | Not Detected | 6.1 | Not Detected |
| 1,1,2-Trichloroethane | 1.3 | Not Detected | 7.3 | Not Detected |
| Tetrachloroethene | 1.3 | 1.5 | 9.1 | 10 |
| 2-Hexanone | 5.4 | Not Detected | 22 | Not Detected |

eurofins | Air Toxics

**Client Sample ID: VMP-21-10-020513**

**Lab ID#: 1302156A-06A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p021417** | **Date of Collection: 2/5/13 3:30:00 PM** | |
| **Dil. Factor:** | **2.69** | **Date of Analysis: 2/14/13 06:59 PM** | |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Dibromochloromethane | 1.3 | Not Detected | 11 | Not Detected |
| 1,2-Dibromoethane (EDB) | 1.3 | Not Detected | 10 | Not Detected |
| Chlorobenzene | 1.3 | Not Detected | 6.2 | Not Detected |
| Ethyl Benzene | 1.3 | Not Detected | 5.8 | Not Detected |
| m,p-Xylene | 1.3 | Not Detected | 5.8 | Not Detected |
| o-Xylene | 1.3 | Not Detected | 5.8 | Not Detected |
| Styrene | 1.3 | Not Detected | 5.7 | Not Detected |
| Bromoform | 1.3 | Not Detected | 14 | Not Detected |
| Cumene | 1.3 | Not Detected | 6.6 | Not Detected |
| 1,1,2,2-Tetrachloroethane | 1.3 | Not Detected | 9.2 | Not Detected |
| Propylbenzene | 1.3 | Not Detected | 6.6 | Not Detected |
| 4-Ethyltoluene | 1.3 | Not Detected | 6.6 | Not Detected |
| 1,3,5-Trimethylbenzene | 1.3 | Not Detected | 6.6 | Not Detected |
| 1,2,4-Trimethylbenzene | 1.3 | Not Detected | 6.6 | Not Detected |
| 1,3-Dichlorobenzene | 1.3 | Not Detected | 8.1 | Not Detected |
| 1,4-Dichlorobenzene | 1.3 | Not Detected | 8.1 | Not Detected |
| alpha-Chlorotoluene | 1.3 | Not Detected | 7.0 | Not Detected |
| 1,2-Dichlorobenzene | 1.3 | Not Detected | 8.1 | Not Detected |
| 1,2,4-Trichlorobenzene | 5.4 | Not Detected | 40 | Not Detected |
| Hexachlorobutadiene | 5.4 | Not Detected | 57 | Not Detected |
| Butane | 5.4 | Not Detected | 13 | Not Detected |
| Isopentane | 5.4 | 2.2 J | 16 | 6.6 J |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| Toluene-d8 | 98 | 70-130 |
| 1,2-Dichloroethane-d4 | 87 | 70-130 |
| 4-Bromofluorobenzene | 95 | 70-130 |

eurofins | Air Toxics

**Client Sample ID: VMP-21-10-020513-DUP**

**Lab ID#: 1302156A-07A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p021418** | **Date of Collection: 2/5/13 3:30:00 PM** | |
| **Dil. Factor:** | **2.52** | **Date of Analysis: 2/14/13 07:35 PM** | |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 1.3 | 0.49 J | 6.2 | 2.4 J |
| Freon 114 | 1.3 | Not Detected | 8.8 | Not Detected |
| Chloromethane | 13 | Not Detected | 26 | Not Detected |
| Vinyl Chloride | 1.3 | Not Detected | 3.2 | Not Detected |
| 1,3-Butadiene | 1.3 | Not Detected | 2.8 | Not Detected |
| Bromomethane | 13 | Not Detected | 49 | Not Detected |
| Chloroethane | 5.0 | Not Detected | 13 | Not Detected |
| Freon 11 | 1.3 | ~~0.18 J~~ U | 7.1 | ~~0.99 J~~ U |
| Ethanol | 5.0 | 1.1 J | 9.5 | 2.0 J |
| Freon 113 | 1.3 | Not Detected | 9.6 | Not Detected |
| 1,1-Dichloroethene | 1.3 | Not Detected | 5.0 | Not Detected |
| Acetone | 13 | 2.6 J | 30 | 6.3 J |
| 2-Propanol | 5.0 | 2.4 J | 12 | 6.0 J |
| Carbon Disulfide | 5.0 | ~~0.58 J~~ U | 16 | ~~1.8 J~~ U |
| 3-Chloropropene | 5.0 | Not Detected | 16 | Not Detected |
| Methylene Chloride | 13 | ~~0.29 J~~ U | 44 | ~~1.0 J~~ U |
| Methyl tert-butyl ether | 1.3 | Not Detected | 4.5 | Not Detected |
| trans-1,2-Dichloroethene | 1.3 | Not Detected | 5.0 | Not Detected |
| Hexane | 1.3 | 0.60 J | 4.4 | 2.1 J |
| 1,1-Dichloroethane | 1.3 | Not Detected | 5.1 | Not Detected |
| 2-Butanone (Methyl Ethyl Ketone) | 5.0 | Not Detected | 15 | Not Detected |
| cis-1,2-Dichloroethene | 1.3 | Not Detected | 5.0 | Not Detected |
| Tetrahydrofuran | 1.3 | Not Detected | 3.7 | Not Detected |
| Chloroform | 1.3 | Not Detected | 6.2 | Not Detected |
| 1,1,1-Trichloroethane | 1.3 | Not Detected | 6.9 | Not Detected |
| Cyclohexane | 1.3 | 1.2 J | 4.3 | 4.3 J |
| Carbon Tetrachloride | 1.3 | Not Detected | 7.9 | Not Detected |
| 2,2,4-Trimethylpentane | 1.3 | 6.5 | 5.9 | 30 |
| Benzene | 1.3 | 11 | 4.0 | 35 |
| 1,2-Dichloroethane | 1.3 | Not Detected | 5.1 | Not Detected |
| Heptane | 1.3 | 0.51 J | 5.2 | 2.1 J |
| Trichloroethene | 1.3 | Not Detected | 6.8 | Not Detected |
| 1,2-Dichloropropane | 1.3 | Not Detected | 5.8 | Not Detected |
| 1,4-Dioxane | 5.0 | Not Detected | 18 | Not Detected |
| Bromodichloromethane | 1.3 | Not Detected | 8.4 | Not Detected |
| cis-1,3-Dichloropropene | 1.3 | Not Detected | 5.7 | Not Detected |
| 4-Methyl-2-pentanone | 1.3 | Not Detected | 5.2 | Not Detected |
| Toluene | 1.3 | ~~0.15 J~~ U | 4.7 | ~~0.57 J~~ U |
| trans-1,3-Dichloropropene | 1.3 | Not Detected | 5.7 | Not Detected |
| 1,1,2-Trichloroethane | 1.3 | Not Detected | 6.9 | Not Detected |
| Tetrachloroethene | 1.3 | 1.4 | 8.5 | 9.6 |
| 2-Hexanone | 5.0 | Not Detected | 21 | Not Detected |

eurofins | Air Toxics

**Client Sample ID: VMP-21-10-020513-DUP**

**Lab ID#: 1302156A-07A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | p021418 | **Date of Collection:** | 2/5/13 3:30:00 PM |
| **Dil. Factor:** | 2.52 | **Date of Analysis:** | 2/14/13 07:35 PM |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Dibromochloromethane | 1.3 | Not Detected | 11 | Not Detected |
| 1,2-Dibromoethane (EDB) | 1.3 | Not Detected | 9.7 | Not Detected |
| Chlorobenzene | 1.3 | Not Detected | 5.8 | Not Detected |
| Ethyl Benzene | 1.3 | Not Detected | 5.5 | Not Detected |
| m,p-Xylene | 1.3 | Not Detected | 5.5 | Not Detected |
| o-Xylene | 1.3 | Not Detected | 5.5 | Not Detected |
| Styrene | 1.3 | Not Detected | 5.4 | Not Detected |
| Bromoform | 1.3 | Not Detected | 13 | Not Detected |
| Cumene | 1.3 | Not Detected | 6.2 | Not Detected |
| 1,1,2,2-Tetrachloroethane | 1.3 | Not Detected | 8.6 | Not Detected |
| Propylbenzene | 1.3 | Not Detected | 6.2 | Not Detected |
| 4-Ethyltoluene | 1.3 | Not Detected | 6.2 | Not Detected |
| 1,3,5-Trimethylbenzene | 1.3 | Not Detected | 6.2 | Not Detected |
| 1,2,4-Trimethylbenzene | 1.3 | Not Detected | 6.2 | Not Detected |
| 1,3-Dichlorobenzene | 1.3 | Not Detected | 7.6 | Not Detected |
| 1,4-Dichlorobenzene | 1.3 | Not Detected | 7.6 | Not Detected |
| alpha-Chlorotoluene | 1.3 | Not Detected | 6.5 | Not Detected |
| 1,2-Dichlorobenzene | 1.3 | Not Detected | 7.6 | Not Detected |
| 1,2,4-Trichlorobenzene | 5.0 | Not Detected | 37 | Not Detected |
| Hexachlorobutadiene | 5.0 | Not Detected | 54 | Not Detected |
| Butane | 5.0 | Not Detected | 12 | Not Detected |
| Isopentane | 5.0 | 0.92 J | 15 | 2.7 J |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| Toluene-d8 | 97 | 70-130 |
| 1,2-Dichloroethane-d4 | 88 | 70-130 |
| 4-Bromofluorobenzene | 93 | 70-130 |

eurofins | Air Toxics

**Client Sample ID: VMP-21-25-020513**

**Lab ID#: 1302156A-08A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | p021419 | **Date of Collection:** | 2/5/13 2:40:00 PM |
| **Dil. Factor:** | 2.58 | **Date of Analysis:** | 2/14/13 08:07 PM |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 1.3 | 0.51 J | 6.4 | 2.5 J |
| Freon 114 | 1.3 | Not Detected | 9.0 | Not Detected |
| Chloromethane | 13 | Not Detected | 27 | Not Detected |
| Vinyl Chloride | 1.3 | Not Detected | 3.3 | Not Detected |
| 1,3-Butadiene | 1.3 | Not Detected | 2.8 | Not Detected |
| Bromomethane | 13 | Not Detected | 50 | Not Detected |
| Chloroethane | 5.2 | Not Detected | 14 | Not Detected |
| Freon 11 | 1.3 | ~~0.25 J~~ U | 7.2 | ~~1.4 J~~ U |
| Ethanol | 5.2 | 2.3 J | 9.7 | 4.4 J |
| Freon 113 | 1.3 | Not Detected | 9.9 | Not Detected |
| 1,1-Dichloroethene | 1.3 | Not Detected | 5.1 | Not Detected |
| Acetone | 13 | 4.6 J | 31 | 11 J |
| 2-Propanol | 5.2 | 3.4 J | 13 | 8.3 J |
| Carbon Disulfide | 5.2 | ~~0.50 J~~ U | 16 | ~~1.5 J~~ U |
| 3-Chloropropene | 5.2 | Not Detected | 16 | Not Detected |
| Methylene Chloride | 13 | ~~0.20 J~~ U | 45 | ~~0.71 J~~ U |
| Methyl tert-butyl ether | 1.3 | Not Detected | 4.6 | Not Detected |
| trans-1,2-Dichloroethene | 1.3 | Not Detected | 5.1 | Not Detected |
| Hexane | 1.3 | 0.93 J | 4.5 | 3.3 J |
| 1,1-Dichloroethane | 1.3 | Not Detected | 5.2 | Not Detected |
| 2-Butanone (Methyl Ethyl Ketone) | 5.2 | Not Detected | 15 | Not Detected |
| cis-1,2-Dichloroethene | 1.3 | Not Detected | 5.1 | Not Detected |
| Tetrahydrofuran | 1.3 | Not Detected | 3.8 | Not Detected |
| Chloroform | 1.3 | Not Detected | 6.3 | Not Detected |
| 1,1,1-Trichloroethane | 1.3 | Not Detected | 7.0 | Not Detected |
| Cyclohexane | 1.3 | 1.0 J | 4.4 | 3.5 J |
| Carbon Tetrachloride | 1.3 | Not Detected | 8.1 | Not Detected |
| 2,2,4-Trimethylpentane | 1.3 | 5.1 | 6.0 | 24 |
| Benzene | 1.3 | 11 | 4.1 | 35 |
| 1,2-Dichloroethane | 1.3 | Not Detected | 5.2 | Not Detected |
| Heptane | 1.3 | 0.36 J | 5.3 | 1.5 J |
| Trichloroethene | 1.3 | Not Detected | 6.9 | Not Detected |
| 1,2-Dichloropropane | 1.3 | Not Detected | 6.0 | Not Detected |
| 1,4-Dioxane | 5.2 | Not Detected | 18 | Not Detected |
| Bromodichloromethane | 1.3 | Not Detected | 8.6 | Not Detected |
| cis-1,3-Dichloropropene | 1.3 | Not Detected | 5.8 | Not Detected |
| 4-Methyl-2-pentanone | 1.3 | Not Detected | 5.3 | Not Detected |
| Toluene | 1.3 | ~~0.11 J~~ U | 4.9 | ~~0.43 J~~ U |
| trans-1,3-Dichloropropene | 1.3 | Not Detected | 5.8 | Not Detected |
| 1,1,2-Trichloroethane | 1.3 | Not Detected | 7.0 | Not Detected |
| Tetrachloroethene | 1.3 | 15 | 8.8 | 100 |
| 2-Hexanone | 5.2 | Not Detected | 21 | Not Detected |

eurofins | Air Toxics

**Client Sample ID: VMP-21-25-020513**

**Lab ID#: 1302156A-08A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p021419** | **Date of Collection: 2/5/13 2:40:00 PM** | |
| **Dil. Factor:** | **2.58** | **Date of Analysis: 2/14/13 08:07 PM** | |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Dibromochloromethane | 1.3 | Not Detected | 11 | Not Detected |
| 1,2-Dibromoethane (EDB) | 1.3 | Not Detected | 9.9 | Not Detected |
| Chlorobenzene | 1.3 | Not Detected | 5.9 | Not Detected |
| Ethyl Benzene | 1.3 | Not Detected | 5.6 | Not Detected |
| m,p-Xylene | 1.3 | Not Detected | 5.6 | Not Detected |
| o-Xylene | 1.3 | Not Detected | 5.6 | Not Detected |
| Styrene | 1.3 | Not Detected | 5.5 | Not Detected |
| Bromoform | 1.3 | Not Detected | 13 | Not Detected |
| Cumene | 1.3 | Not Detected | 6.3 | Not Detected |
| 1,1,2,2-Tetrachloroethane | 1.3 | Not Detected | 8.8 | Not Detected |
| Propylbenzene | 1.3 | Not Detected | 6.3 | Not Detected |
| 4-Ethyltoluene | 1.3 | Not Detected | 6.3 | Not Detected |
| 1,3,5-Trimethylbenzene | 1.3 | Not Detected | 6.3 | Not Detected |
| 1,2,4-Trimethylbenzene | 1.3 | Not Detected | 6.3 | Not Detected |
| 1,3-Dichlorobenzene | 1.3 | Not Detected | 7.8 | Not Detected |
| 1,4-Dichlorobenzene | 1.3 | Not Detected | 7.8 | Not Detected |
| alpha-Chlorotoluene | 1.3 | Not Detected | 6.7 | Not Detected |
| 1,2-Dichlorobenzene | 1.3 | Not Detected | 7.8 | Not Detected |
| 1,2,4-Trichlorobenzene | 5.2 | Not Detected | 38 | Not Detected |
| Hexachlorobutadiene | 5.2 | Not Detected | 55 | Not Detected |
| Butane | 5.2 | 1.3 J | 12 | 3.1 J |
| Isopentane | 5.2 | 2.8 J | 15 | 8.3 J |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| Toluene-d8 | 98 | 70-130 |
| 1,2-Dichloroethane-d4 | 87 | 70-130 |
| 4-Bromofluorobenzene | 94 | 70-130 |

eurofins | Air Toxics

**Client Sample ID: VMP-21-25-020513-DUP**

**Lab ID#: 1302156A-09A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p021420** | **Date of Collection:** | **2/5/13 2:40:00 PM** |
| **Dil. Factor:** | **2.69** | **Date of Analysis:** | **2/14/13 09:02 PM** |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 1.3 | 0.54 J | 6.6 | 2.7 J |
| Freon 114 | 1.3 | Not Detected | 9.4 | Not Detected |
| Chloromethane | 13 | Not Detected | 28 | Not Detected |
| Vinyl Chloride | 1.3 | Not Detected | 3.4 | Not Detected |
| 1,3-Butadiene | 1.3 | Not Detected | 3.0 | Not Detected |
| Bromomethane | 13 | Not Detected | 52 | Not Detected |
| Chloroethane | 5.4 | Not Detected | 14 | Not Detected |
| Freon 11 | 1.3 | ~~0.30 J~~ U | 7.6 | ~~1.7 J~~ U |
| Ethanol | 5.4 | 2.0 J | 10 | 3.7 J |
| Freon 113 | 1.3 | Not Detected | 10 | Not Detected |
| 1,1-Dichloroethene | 1.3 | Not Detected | 5.3 | Not Detected |
| Acetone | 13 | 3.2 J | 32 | 7.7 J |
| 2-Propanol | 5.4 | 3.4 J | 13 | 8.4 J |
| Carbon Disulfide | 5.4 | ~~0.59 J~~ U | 17 | ~~1.8 J~~ U |
| 3-Chloropropene | 5.4 | Not Detected | 17 | Not Detected |
| Methylene Chloride | 13 | ~~0.85 J~~ U | 47 | ~~3.0 J~~ U |
| Methyl tert-butyl ether | 1.3 | Not Detected | 4.8 | Not Detected |
| trans-1,2-Dichloroethene | 1.3 | Not Detected | 5.3 | Not Detected |
| Hexane | 1.3 | 0.80 J | 4.7 | 2.8 J |
| 1,1-Dichloroethane | 1.3 | Not Detected | 5.4 | Not Detected |
| 2-Butanone (Methyl Ethyl Ketone) | 5.4 | Not Detected | 16 | Not Detected |
| cis-1,2-Dichloroethene | 1.3 | Not Detected | 5.3 | Not Detected |
| Tetrahydrofuran | 1.3 | Not Detected | 4.0 | Not Detected |
| Chloroform | 1.3 | Not Detected | 6.6 | Not Detected |
| 1,1,1-Trichloroethane | 1.3 | Not Detected | 7.3 | Not Detected |
| Cyclohexane | 1.3 | 1.2 J | 4.6 | 4.0 J |
| Carbon Tetrachloride | 1.3 | Not Detected | 8.5 | Not Detected |
| 2,2,4-Trimethylpentane | 1.3 | 3.1 | 6.3 | 14 |
| Benzene | 1.3 | 13 | 4.3 | 43 |
| 1,2-Dichloroethane | 1.3 | Not Detected | 5.4 | Not Detected |
| Heptane | 1.3 | 0.41 J | 5.5 | 1.7 J |
| Trichloroethene | 1.3 | Not Detected | 7.2 | Not Detected |
| 1,2-Dichloropropane | 1.3 | Not Detected | 6.2 | Not Detected |
| 1,4-Dioxane | 5.4 | Not Detected | 19 | Not Detected |
| Bromodichloromethane | 1.3 | Not Detected | 9.0 | Not Detected |
| cis-1,3-Dichloropropene | 1.3 | Not Detected | 6.1 | Not Detected |
| 4-Methyl-2-pentanone | 1.3 | 0.38 J | 5.5 | 1.6 J |
| Toluene | 1.3 | ~~0.26 J~~ U | 5.1 | ~~0.97 J~~ U |
| trans-1,3-Dichloropropene | 1.3 | Not Detected | 6.1 | Not Detected |
| 1,1,2-Trichloroethane | 1.3 | Not Detected | 7.3 | Not Detected |
| Tetrachloroethene | 1.3 | 16 | 9.1 | 110 |
| 2-Hexanone | 5.4 | Not Detected | 22 | Not Detected |

eurofins | Air Toxics

**Client Sample ID: VMP-21-25-020513-DUP**

**Lab ID#: 1302156A-09A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p021420** | **Date of Collection: 2/5/13 2:40:00 PM** | |
| **Dil. Factor:** | **2.69** | **Date of Analysis: 2/14/13 09:02 PM** | |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Dibromochloromethane | 1.3 | Not Detected | 11 | Not Detected |
| 1,2-Dibromoethane (EDB) | 1.3 | Not Detected | 10 | Not Detected |
| Chlorobenzene | 1.3 | Not Detected | 6.2 | Not Detected |
| Ethyl Benzene | 1.3 | Not Detected | 5.8 | Not Detected |
| m,p-Xylene | 1.3 | Not Detected | 5.8 | Not Detected |
| o-Xylene | 1.3 | Not Detected | 5.8 | Not Detected |
| Styrene | 1.3 | Not Detected | 5.7 | Not Detected |
| Bromoform | 1.3 | Not Detected | 14 | Not Detected |
| Cumene | 1.3 | Not Detected | 6.6 | Not Detected |
| 1,1,2,2-Tetrachloroethane | 1.3 | Not Detected | 9.2 | Not Detected |
| Propylbenzene | 1.3 | Not Detected | 6.6 | Not Detected |
| 4-Ethyltoluene | 1.3 | Not Detected | 6.6 | Not Detected |
| 1,3,5-Trimethylbenzene | 1.3 | Not Detected | 6.6 | Not Detected |
| 1,2,4-Trimethylbenzene | 1.3 | Not Detected | 6.6 | Not Detected |
| 1,3-Dichlorobenzene | 1.3 | Not Detected | 8.1 | Not Detected |
| 1,4-Dichlorobenzene | 1.3 | Not Detected | 8.1 | Not Detected |
| alpha-Chlorotoluene | 1.3 | Not Detected | 7.0 | Not Detected |
| 1,2-Dichlorobenzene | 1.3 | Not Detected | 8.1 | Not Detected |
| 1,2,4-Trichlorobenzene | 5.4 | Not Detected | 40 | Not Detected |
| Hexachlorobutadiene | 5.4 | Not Detected | 57 | Not Detected |
| Butane | 5.4 | Not Detected | 13 | Not Detected |
| Isopentane | 5.4 | 3.6 J | 16 | 11 J |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| Toluene-d8 | 96 | 70-130 |
| 1,2-Dichloroethane-d4 | 88 | 70-130 |
| 4-Bromofluorobenzene | 94 | 70-130 |

eurofins | Air Toxics

**Client Sample ID: VMP-21-33-020513**

**Lab ID#: 1302156A-10A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p021421** | **Date of Collection: 2/5/13 1:54:00 PM** | |
| **Dil. Factor:** | **2.64** | **Date of Analysis: 2/14/13 09:42 PM** | |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 1.3 | 0.52 J | 6.5 | 2.6 J |
| Freon 114 | 1.3 | Not Detected | 9.2 | Not Detected |
| Chloromethane | 13 | Not Detected | 27 | Not Detected |
| Vinyl Chloride | 1.3 | Not Detected | 3.4 | Not Detected |
| 1,3-Butadiene | 1.3 | Not Detected | 2.9 | Not Detected |
| Bromomethane | 13 | Not Detected | 51 | Not Detected |
| Chloroethane | 5.3 | Not Detected | 14 | Not Detected |
| Freon 11 | 1.3 | Not Detected | 7.4 | Not Detected |
| Ethanol | 5.3 | Not Detected | 9.9 | Not Detected |
| Freon 113 | 1.3 | Not Detected | 10 | Not Detected |
| 1,1-Dichloroethene | 1.3 | Not Detected | 5.2 | Not Detected |
| Acetone | 13 | 2.5 J | 31 | 5.8 J |
| 2-Propanol | 5.3 | 12 | 13 | 29 |
| Carbon Disulfide | 5.3 | ~~0.72 J~~ | 16 | ~~2.2 J~~ |
| 3-Chloropropene | 5.3 | Not Detected | 16 | Not Detected |
| Methylene Chloride | 13 | ~~0.16 J~~ | 46 | ~~0.56 J~~ |
| Methyl tert-butyl ether | 1.3 | Not Detected | 4.8 | Not Detected |
| trans-1,2-Dichloroethene | 1.3 | Not Detected | 5.2 | Not Detected |
| Hexane | 1.3 | 0.33 J | 4.6 | 1.2 J |
| 1,1-Dichloroethane | 1.3 | Not Detected | 5.3 | Not Detected |
| 2-Butanone (Methyl Ethyl Ketone) | 5.3 | Not Detected | 16 | Not Detected |
| cis-1,2-Dichloroethene | 1.3 | Not Detected | 5.2 | Not Detected |
| Tetrahydrofuran | 1.3 | Not Detected | 3.9 | Not Detected |
| Chloroform | 1.3 | Not Detected | 6.4 | Not Detected |
| 1,1,1-Trichloroethane | 1.3 | Not Detected | 7.2 | Not Detected |
| Cyclohexane | 1.3 | Not Detected | 4.5 | Not Detected |
| Carbon Tetrachloride | 1.3 | Not Detected | 8.3 | Not Detected |
| 2,2,4-Trimethylpentane | 1.3 | 2.3 | 6.2 | 10 |
| Benzene | 1.3 | 0.76 J | 4.2 | 2.4 J |
| 1,2-Dichloroethane | 1.3 | Not Detected | 5.3 | Not Detected |
| Heptane | 1.3 | Not Detected | 5.4 | Not Detected |
| Trichloroethene | 1.3 | Not Detected | 7.1 | Not Detected |
| 1,2-Dichloropropane | 1.3 | Not Detected | 6.1 | Not Detected |
| 1,4-Dioxane | 5.3 | Not Detected | 19 | Not Detected |
| Bromodichloromethane | 1.3 | Not Detected | 8.8 | Not Detected |
| cis-1,3-Dichloropropene | 1.3 | Not Detected | 6.0 | Not Detected |
| 4-Methyl-2-pentanone | 1.3 | Not Detected | 5.4 | Not Detected |
| Toluene | 1.3 | Not Detected | 5.0 | Not Detected |
| trans-1,3-Dichloropropene | 1.3 | Not Detected | 6.0 | Not Detected |
| 1,1,2-Trichloroethane | 1.3 | Not Detected | 7.2 | Not Detected |
| Tetrachloroethene | 1.3 | 5.1 | 9.0 | 34 |
| 2-Hexanone | 5.3 | Not Detected | 22 | Not Detected |

eurofins | Air Toxics

**Client Sample ID: VMP-21-33-020513**

**Lab ID#: 1302156A-10A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | p021421 | **Date of Collection:** | 2/5/13 1:54:00 PM |
| **Dil. Factor:** | 2.64 | **Date of Analysis:** | 2/14/13 09:42 PM |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Dibromochloromethane | 1.3 | Not Detected | 11 | Not Detected |
| 1,2-Dibromoethane (EDB) | 1.3 | Not Detected | 10 | Not Detected |
| Chlorobenzene | 1.3 | Not Detected | 6.1 | Not Detected |
| Ethyl Benzene | 1.3 | Not Detected | 5.7 | Not Detected |
| m,p-Xylene | 1.3 | Not Detected | 5.7 | Not Detected |
| o-Xylene | 1.3 | Not Detected | 5.7 | Not Detected |
| Styrene | 1.3 | Not Detected | 5.6 | Not Detected |
| Bromoform | 1.3 | Not Detected | 14 | Not Detected |
| Cumene | 1.3 | Not Detected | 6.5 | Not Detected |
| 1,1,2,2-Tetrachloroethane | 1.3 | Not Detected | 9.1 | Not Detected |
| Propylbenzene | 1.3 | Not Detected | 6.5 | Not Detected |
| 4-Ethyltoluene | 1.3 | Not Detected | 6.5 | Not Detected |
| 1,3,5-Trimethylbenzene | 1.3 | Not Detected | 6.5 | Not Detected |
| 1,2,4-Trimethylbenzene | 1.3 | Not Detected | 6.5 | Not Detected |
| 1,3-Dichlorobenzene | 1.3 | Not Detected | 7.9 | Not Detected |
| 1,4-Dichlorobenzene | 1.3 | Not Detected | 7.9 | Not Detected |
| alpha-Chlorotoluene | 1.3 | Not Detected | 6.8 | Not Detected |
| 1,2-Dichlorobenzene | 1.3 | Not Detected | 7.9 | Not Detected |
| 1,2,4-Trichlorobenzene | 5.3 | Not Detected | 39 | Not Detected |
| Hexachlorobutadiene | 5.3 | Not Detected | 56 | Not Detected |
| Butane | 5.3 | Not Detected | 12 | Not Detected |
| Isopentane | 5.3 | 1.4 J | 16 | 4.2 J |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| Toluene-d8 | 97 | 70-130 |
| 1,2-Dichloroethane-d4 | 88 | 70-130 |
| 4-Bromofluorobenzene | 96 | 70-130 |

eurofins | Air Toxics

**Client Sample ID: VMP-29-10-020613**

**Lab ID#: 1302156A-11A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p021422** | **Date of Collection:** | **2/6/13 9:56:00 AM** |
| **Dil. Factor:** | **2.82** | **Date of Analysis:** | **2/14/13 10:15 PM** |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 1.4 | 0.51 J | 7.0 | 2.5 J |
| Freon 114 | 1.4 | Not Detected | 9.8 | Not Detected |
| Chloromethane | 14 | Not Detected | 29 | Not Detected |
| Vinyl Chloride | 1.4 | Not Detected | 3.6 | Not Detected |
| 1,3-Butadiene | 1.4 | Not Detected | 3.1 | Not Detected |
| Bromomethane | 14 | Not Detected | 55 | Not Detected |
| Chloroethane | 5.6 | Not Detected | 15 | Not Detected |
| Freon 11 | 1.4 | ~~0.22 J~~ U | 7.9 | ~~1.2 J~~ U |
| Ethanol | 5.6 | 9.5 | 11 | 18 |
| Freon 113 | 1.4 | Not Detected | 11 | Not Detected |
| 1,1-Dichloroethene | 1.4 | Not Detected | 5.6 | Not Detected |
| Acetone | 14 | 69 | 33 | 160 |
| 2-Propanol | 5.6 | 18 | 14 | 44 |
| Carbon Disulfide | 5.6 | 6.7 | 18 | 21 |
| 3-Chloropropene | 5.6 | Not Detected | 18 | Not Detected |
| Methylene Chloride | 14 | Not Detected | 49 | Not Detected |
| Methyl tert-butyl ether | 1.4 | Not Detected | 5.1 | Not Detected |
| trans-1,2-Dichloroethene | 1.4 | Not Detected | 5.6 | Not Detected |
| Hexane | 1.4 | Not Detected | 5.0 | Not Detected |
| 1,1-Dichloroethane | 1.4 | Not Detected | 5.7 | Not Detected |
| 2-Butanone (Methyl Ethyl Ketone) | 5.6 | 100 | 17 | 300 |
| cis-1,2-Dichloroethene | 1.4 | Not Detected | 5.6 | Not Detected |
| Tetrahydrofuran | 1.4 | 100 | 4.2 | 290 |
| Chloroform | 1.4 | Not Detected | 6.9 | Not Detected |
| 1,1,1-Trichloroethane | 1.4 | Not Detected | 7.7 | Not Detected |
| Cyclohexane | 1.4 | Not Detected | 4.8 | Not Detected |
| Carbon Tetrachloride | 1.4 | Not Detected | 8.9 | Not Detected |
| 2,2,4-Trimethylpentane | 1.4 | ~~0.21 J~~ U | 6.6 | ~~0.98 J~~ U |
| Benzene | 1.4 | 17 | 4.5 | 53 |
| 1,2-Dichloroethane | 1.4 | Not Detected | 5.7 | Not Detected |
| Heptane | 1.4 | Not Detected | 5.8 | Not Detected |
| Trichloroethene | 1.4 | Not Detected | 7.6 | Not Detected |
| 1,2-Dichloropropane | 1.4 | Not Detected | 6.5 | Not Detected |
| 1,4-Dioxane | 5.6 | Not Detected | 20 | Not Detected |
| Bromodichloromethane | 1.4 | Not Detected | 9.4 | Not Detected |
| cis-1,3-Dichloropropene | 1.4 | Not Detected | 6.4 | Not Detected |
| 4-Methyl-2-pentanone | 1.4 | 0.68 J | 5.8 | 2.8 J |
| Toluene | 1.4 | ~~0.13 J~~ U | 5.3 | ~~0.48 J~~ U |
| trans-1,3-Dichloropropene | 1.4 | Not Detected | 6.4 | Not Detected |
| 1,1,2-Trichloroethane | 1.4 | Not Detected | 7.7 | Not Detected |
| Tetrachloroethene | 1.4 | ~~0.19 J~~ U | 9.6 | ~~1.3 J~~ U |
| 2-Hexanone | 5.6 | Not Detected | 23 | Not Detected |

eurofins | Air Toxics

**Client Sample ID: VMP-29-10-020613**

**Lab ID#: 1302156A-11A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p021422** | **Date of Collection:** | **2/6/13 9:56:00 AM** |
| **Dil. Factor:** | **2.82** | **Date of Analysis:** | **2/14/13 10:15 PM** |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Dibromochloromethane | 1.4 | Not Detected | 12 | Not Detected |
| 1,2-Dibromoethane (EDB) | 1.4 | Not Detected | 11 | Not Detected |
| Chlorobenzene | 1.4 | Not Detected | 6.5 | Not Detected |
| Ethyl Benzene | 1.4 | Not Detected | 6.1 | Not Detected |
| m,p-Xylene | 1.4 | Not Detected | 6.1 | Not Detected |
| o-Xylene | 1.4 | Not Detected | 6.1 | Not Detected |
| Styrene | 1.4 | Not Detected | 6.0 | Not Detected |
| Bromoform | 1.4 | Not Detected | 14 | Not Detected |
| Cumene | 1.4 | Not Detected | 6.9 | Not Detected |
| 1,1,2,2-Tetrachloroethane | 1.4 | Not Detected | 9.7 | Not Detected |
| Propylbenzene | 1.4 | Not Detected | 6.9 | Not Detected |
| 4-Ethyltoluene | 1.4 | Not Detected | 6.9 | Not Detected |
| 1,3,5-Trimethylbenzene | 1.4 | Not Detected | 6.9 | Not Detected |
| 1,2,4-Trimethylbenzene | 1.4 | Not Detected | 6.9 | Not Detected |
| 1,3-Dichlorobenzene | 1.4 | Not Detected | 8.5 | Not Detected |
| 1,4-Dichlorobenzene | 1.4 | Not Detected | 8.5 | Not Detected |
| alpha-Chlorotoluene | 1.4 | Not Detected | 7.3 | Not Detected |
| 1,2-Dichlorobenzene | 1.4 | Not Detected | 8.5 | Not Detected |
| 1,2,4-Trichlorobenzene | 5.6 | Not Detected | 42 | Not Detected |
| Hexachlorobutadiene | 5.6 | Not Detected | 60 | Not Detected |
| Butane | 5.6 | 1.6 J | 13 | 3.8 J |
| Isopentane | 5.6 | 1.0 J | 17 | 3.1 J |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| Toluene-d8 | 95 | 70-130 |
| 1,2-Dichloroethane-d4 | 86 | 70-130 |
| 4-Bromofluorobenzene | 96 | 70-130 |

eurofins | Air Toxics

**Client Sample ID: VMP-29-20-020613**

**Lab ID#: 1302156A-12A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p021423** | **Date of Collection:** | **2/6/13 10:56:00 AM** |
| **Dil. Factor:** | **2.76** | **Date of Analysis:** | **2/14/13 10:44 PM** |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 1.4 | 0.45 J | 6.8 | 2.2 J |
| Freon 114 | 1.4 | Not Detected | 9.6 | Not Detected |
| Chloromethane | 14 | Not Detected | 28 | Not Detected |
| Vinyl Chloride | 1.4 | Not Detected | 3.5 | Not Detected |
| 1,3-Butadiene | 1.4 | Not Detected | 3.0 | Not Detected |
| Bromomethane | 14 | Not Detected | 54 | Not Detected |
| Chloroethane | 5.5 | Not Detected | 14 | Not Detected |
| Freon 11 | 1.4 | ~~0.22 J~~ U | 7.8 | ~~1.3 J~~ U |
| Ethanol | 5.5 | 5.4 J | 10 | 10 J |
| Freon 113 | 1.4 | Not Detected | 10 | Not Detected |
| 1,1-Dichloroethene | 1.4 | Not Detected | 5.5 | Not Detected |
| Acetone | 14 | 87 | 33 | 210 |
| 2-Propanol | 5.5 | 16 | 14 | 40 |
| Carbon Disulfide | 5.5 | 11 | 17 | 35 |
| 3-Chloropropene | 5.5 | Not Detected | 17 | Not Detected |
| Methylene Chloride | 14 | ~~0.28 J~~ U | 48 | ~~0.98 J~~ U |
| Methyl tert-butyl ether | 1.4 | Not Detected | 5.0 | Not Detected |
| trans-1,2-Dichloroethene | 1.4 | Not Detected | 5.5 | Not Detected |
| Hexane | 1.4 | 0.33 J | 4.9 | 1.2 J |
| 1,1-Dichloroethane | 1.4 | Not Detected | 5.6 | Not Detected |
| 2-Butanone (Methyl Ethyl Ketone) | 5.5 | 260 | 16 | 750 |
| cis-1,2-Dichloroethene | 1.4 | Not Detected | 5.5 | Not Detected |
| Tetrahydrofuran | 1.4 | 68 | 4.1 | 200 |
| Chloroform | 1.4 | Not Detected | 6.7 | Not Detected |
| 1,1,1-Trichloroethane | 1.4 | Not Detected | 7.5 | Not Detected |
| Cyclohexane | 1.4 | Not Detected | 4.8 | Not Detected |
| Carbon Tetrachloride | 1.4 | Not Detected | 8.7 | Not Detected |
| 2,2,4-Trimethylpentane | 1.4 | Not Detected | 6.4 | Not Detected |
| Benzene | 1.4 | 8.1 | 4.4 | 26 |
| 1,2-Dichloroethane | 1.4 | Not Detected | 5.6 | Not Detected |
| Heptane | 1.4 | Not Detected | 5.6 | Not Detected |
| Trichloroethene | 1.4 | Not Detected | 7.4 | Not Detected |
| 1,2-Dichloropropane | 1.4 | Not Detected | 6.4 | Not Detected |
| 1,4-Dioxane | 5.5 | Not Detected | 20 | Not Detected |
| Bromodichloromethane | 1.4 | Not Detected | 9.2 | Not Detected |
| cis-1,3-Dichloropropene | 1.4 | Not Detected | 6.3 | Not Detected |
| 4-Methyl-2-pentanone | 1.4 | 2.5 | 5.6 | 10 |
| Toluene | 1.4 | 0.52 J | 5.2 | 1.9 J |
| trans-1,3-Dichloropropene | 1.4 | Not Detected | 6.3 | Not Detected |
| 1,1,2-Trichloroethane | 1.4 | Not Detected | 7.5 | Not Detected |
| Tetrachloroethene | 1.4 | ~~0.15 J~~ U | 9.4 | ~~1.0 J~~ U |
| 2-Hexanone | 5.5 | Not Detected | 23 | Not Detected |

eurofins | Air Toxics

**Client Sample ID: VMP-29-20-020613**

**Lab ID#: 1302156A-12A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p021423** | **Date of Collection: 2/6/13 10:56:00 AM** | |
| **Dil. Factor:** | **2.76** | **Date of Analysis: 2/14/13 10:44 PM** | |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Dibromochloromethane | 1.4 | Not Detected | 12 | Not Detected |
| 1,2-Dibromoethane (EDB) | 1.4 | Not Detected | 11 | Not Detected |
| Chlorobenzene | 1.4 | Not Detected | 6.4 | Not Detected |
| Ethyl Benzene | 1.4 | Not Detected | 6.0 | Not Detected |
| m,p-Xylene | 1.4 | 0.47 J | 6.0 | 2.0 J |
| o-Xylene | 1.4 | Not Detected | 6.0 | Not Detected |
| Styrene | 1.4 | Not Detected | 5.9 | Not Detected |
| Bromoform | 1.4 | Not Detected | 14 | Not Detected |
| Cumene | 1.4 | ~~0.73 J~~ U | 6.8 | ~~3.6 J~~ U |
| 1,1,2,2-Tetrachloroethane | 1.4 | Not Detected | 9.5 | Not Detected |
| Propylbenzene | 1.4 | Not Detected | 6.8 | Not Detected |
| 4-Ethyltoluene | 1.4 | ~~0.14 J~~ U | 6.8 | ~~0.69 J~~ U |
| 1,3,5-Trimethylbenzene | 1.4 | Not Detected | 6.8 | Not Detected |
| 1,2,4-Trimethylbenzene | 1.4 | Not Detected | 6.8 | Not Detected |
| 1,3-Dichlorobenzene | 1.4 | Not Detected | 8.3 | Not Detected |
| 1,4-Dichlorobenzene | 1.4 | Not Detected | 8.3 | Not Detected |
| alpha-Chlorotoluene | 1.4 | Not Detected | 7.1 | Not Detected |
| 1,2-Dichlorobenzene | 1.4 | Not Detected | 8.3 | Not Detected |
| 1,2,4-Trichlorobenzene | 5.5 | Not Detected | 41 | Not Detected |
| Hexachlorobutadiene | 5.5 | Not Detected | 59 | Not Detected |
| Butane | 5.5 | 3.6 J | 13 | 8.4 J |
| Isopentane | 5.5 | 2.7 J | 16 | 8.1 J |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| Toluene-d8 | 96 | 70-130 |
| 1,2-Dichloroethane-d4 | 86 | 70-130 |
| 4-Bromofluorobenzene | 106 | 70-130 |

eurofins | Air Toxics

* USE THIS RESULT ONLY. ALL OTHER RESULTS REPORTED IN 2.89X DILUTION ANALYSIS

**Client Sample ID: VMP-29-30-020613**
**Lab ID#: 1302156A-13A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | p021425 | **Date of Collection:** | 2/6/13 11:50:00 AM |
| **Dil. Factor:** | 4.82 | **Date of Analysis:** | 2/15/13 08:31 AM |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 2.4 | 0.51 J | 12 | 2.5 J |
| Freon 114 | 2.4 | Not Detected | 17 | Not Detected |
| Chloromethane | 24 | Not Detected | 50 | Not Detected |
| Vinyl Chloride | 2.4 | Not Detected | 6.2 | Not Detected |
| 1,3-Butadiene | 2.4 | Not Detected | 5.3 | Not Detected |
| Bromomethane | 24 | Not Detected | 94 | Not Detected |
| Chloroethane | 9.6 | Not Detected | 25 | Not Detected |
| Freon 11 | 2.4 | Not Detected | 14 | Not Detected |
| Ethanol | 9.6 | 7.4 J | 18 | 14 J |
| Freon 113 | 2.4 | Not Detected | 18 | Not Detected |
| 1,1-Dichloroethene | 2.4 | Not Detected | 9.6 | Not Detected |
| Acetone | 24 | 350 | 57 | 820 |
| 2-Propanol | 9.6 | 13 | 24 | 32 |
| Carbon Disulfide | 9.6 | 38 | 30 | 120 |
| 3-Chloropropene | 9.6 | Not Detected | 30 | Not Detected |
| Methylene Chloride | 24 | ~~0.64 J~~ V OK (AE) | 84 | ~~2.2 J~~ V OK (AE) |
| Methyl tert-butyl ether | 2.4 | Not Detected | 8.7 | Not Detected |
| trans-1,2-Dichloroethene | 2.4 | Not Detected | 9.6 | Not Detected |
| Hexane | 2.4 | 0.44 J | 8.5 | 1.5 J |
| 1,1-Dichloroethane | 2.4 | Not Detected | 9.8 | Not Detected |
| * 2-Butanone (Methyl Ethyl Ketone) | 9.6 | 730 | 28 | 2100 |
| cis-1,2-Dichloroethene | 2.4 | Not Detected | 9.6 | Not Detected |
| Tetrahydrofuran | 2.4 | 290 | 7.1 | 870 |
| Chloroform | 2.4 | 1.2 J | 12 | 6.1 J |
| 1,1,1-Trichloroethane | 2.4 | Not Detected | 13 | Not Detected |
| Cyclohexane | 2.4 | Not Detected | 8.3 | Not Detected |
| Carbon Tetrachloride | 2.4 | Not Detected | 15 | Not Detected |
| 2,2,4-Trimethylpentane | 2.4 | 0.40 J | 11 | 1.9 J |
| Benzene | 2.4 | 29 | 7.7 | 93 |
| 1,2-Dichloroethane | 2.4 | Not Detected | 9.8 | Not Detected |
| Heptane | 2.4 | Not Detected | 9.9 | Not Detected |
| Trichloroethene | 2.4 | Not Detected | 13 | Not Detected |
| 1,2-Dichloropropane | 2.4 | Not Detected | 11 | Not Detected |
| 1,4-Dioxane | 9.6 | 7.1 J | 35 | 26 J |
| Bromodichloromethane | 2.4 | Not Detected | 16 | Not Detected |
| cis-1,3-Dichloropropene | 2.4 | Not Detected | 11 | Not Detected |
| 4-Methyl-2-pentanone | 2.4 | 3.9 | 9.9 | 16 |
| Toluene | 2.4 | 0.46 J | 9.1 | 1.7 J |
| trans-1,3-Dichloropropene | 2.4 | Not Detected | 11 | Not Detected |
| 1,1,2-Trichloroethane | 2.4 | Not Detected | 13 | Not Detected |
| Tetrachloroethene | 2.4 | ~~0.36 J~~ V OK (AE) | 16 | ~~2.4 J~~ V OK (AE) |
| 2-Hexanone | 9.6 | Not Detected | 39 | Not Detected |

eurofins | Air Toxics

**Client Sample ID: VMP-29-30-020613**

**Lab ID#: 1302156A-13A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p021425** | **Date of Collection:** | **2/6/13 11:50:00 AM** |
| **Dil. Factor:** | **4.82** | **Date of Analysis:** | **2/15/13 08:31 AM** |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Dibromochloromethane | 2.4 | Not Detected | 20 | Not Detected |
| 1,2-Dibromoethane (EDB) | 2.4 | Not Detected | 18 | Not Detected |
| Chlorobenzene | 2.4 | Not Detected | 11 | Not Detected |
| Ethyl Benzene | 2.4 | Not Detected | 10 | Not Detected |
| m,p-Xylene | 2.4 | Not Detected | 10 | Not Detected |
| o-Xylene | 2.4 | Not Detected | 10 | Not Detected |
| Styrene | 2.4 | Not Detected | 10 | Not Detected |
| Bromoform | 2.4 | Not Detected | 25 | Not Detected |
| Cumene | 2.4 | ~~0.42 J~~ U OK (CF) | 12 | ~~2.1 J~~ U OK (AF) |
| 1,1,2,2-Tetrachloroethane | 2.4 | Not Detected | 16 | Not Detected |
| Propylbenzene | 2.4 | Not Detected | 12 | Not Detected |
| 4-Ethyltoluene | 2.4 | ~~0.16 J~~ U OK (AF) | 12 | ~~0.80 J~~ U OK (AF) |
| 1,3,5-Trimethylbenzene | 2.4 | Not Detected | 12 | Not Detected |
| 1,2,4-Trimethylbenzene | 2.4 | Not Detected | 12 | Not Detected |
| 1,3-Dichlorobenzene | 2.4 | Not Detected | 14 | Not Detected |
| 1,4-Dichlorobenzene | 2.4 | Not Detected | 14 | Not Detected |
| alpha-Chlorotoluene | 2.4 | Not Detected | 12 | Not Detected |
| 1,2-Dichlorobenzene | 2.4 | Not Detected | 14 | Not Detected |
| 1,2,4-Trichlorobenzene | 9.6 | Not Detected | 72 | Not Detected |
| Hexachlorobutadiene | 9.6 | Not Detected | 100 | Not Detected |
| Butane | 9.6 | 2.4 J | 23 | 5.7 J |
| Isopentane | 9.6 | 1.7 J | 28 | 5.2 J |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| Toluene-d8 | 95 | 70-130 |
| 1,2-Dichloroethane-d4 | 89 | 70-130 |
| 4-Bromofluorobenzene | 108 | 70-130 |

eurofins | Air Toxics

* DO NOT USE THIS RESULT. USE ALL OTHER DATA.

**Client Sample ID: VMP-29-30-020613**
**Lab ID#: 1302156A-13B**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p021424** | **Date of Collection:** | **2/6/13 11:50:00 AM** |
| **Dil. Factor:** | **2.89** | **Date of Analysis:** | **2/14/13 11:08 PM** |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 1.4 | 0.48 J | 7.1 | 2.4 J |
| Freon 114 | 1.4 | Not Detected | 10 | Not Detected |
| Chloromethane | 14 | Not Detected | 30 | Not Detected |
| Vinyl Chloride | 1.4 | Not Detected | 3.7 | Not Detected |
| 1,3-Butadiene | 1.4 | Not Detected | 3.2 | Not Detected |
| Bromomethane | 14 | Not Detected | 56 | Not Detected |
| Chloroethane | 5.8 | Not Detected | 15 | Not Detected |
| Freon 11 | 1.4 | ~~0.18 J~~ U | 8.1 | ~~1.0 J~~ U |
| Ethanol | 5.8 | 6.2 | 11 | 12 |
| Freon 113 | 1.4 | Not Detected | 11 | Not Detected |
| 1,1-Dichloroethene | 1.4 | Not Detected | 5.7 | Not Detected |
| Acetone | 14 | 320 | 34 | 760 |
| 2-Propanol | 5.8 | 12 | 14 | 29 |
| Carbon Disulfide | 5.8 | 34 | 18 | 100 |
| 3-Chloropropene | 5.8 | Not Detected | 18 | Not Detected |
| Methylene Chloride | 14 | ~~0.56 J~~ U | 50 | ~~2.0 J~~ U |
| Methyl tert-butyl ether | 1.4 | Not Detected | 5.2 | Not Detected |
| trans-1,2-Dichloroethene | 1.4 | Not Detected | 5.7 | Not Detected |
| Hexane | 1.4 | 0.25 J | 5.1 | 0.89 J |
| 1,1-Dichloroethane | 1.4 | Not Detected | 5.8 | Not Detected |
| * ~~2-Butanone (Methyl Ethyl Ketone)~~ | ~~5.8~~ | ~~680 E~~ | ~~17~~ | ~~2000 E~~ |
| cis-1,2-Dichloroethene | 1.4 | Not Detected | 5.7 | Not Detected |
| Tetrahydrofuran | 1.4 | 270 | 4.3 | 780 |
| Chloroform | 1.4 | 1.1 J | 7.0 | 5.6 J |
| 1,1,1-Trichloroethane | 1.4 | Not Detected | 7.9 | Not Detected |
| Cyclohexane | 1.4 | Not Detected | 5.0 | Not Detected |
| Carbon Tetrachloride | 1.4 | Not Detected | 9.1 | Not Detected |
| 2,2,4-Trimethylpentane | 1.4 | ~~0.22 J~~ U | 6.8 | ~~1.0 J~~ U |
| Benzene | 1.4 | 26 | 4.6 | 84 |
| 1,2-Dichloroethane | 1.4 | Not Detected | 5.8 | Not Detected |
| Heptane | 1.4 | Not Detected | 5.9 | Not Detected |
| Trichloroethene | 1.4 | Not Detected | 7.8 | Not Detected |
| 1,2-Dichloropropane | 1.4 | Not Detected | 6.7 | Not Detected |
| 1,4-Dioxane | 5.8 | 5.3 J | 21 | 19 J |
| Bromodichloromethane | 1.4 | Not Detected | 9.7 | Not Detected |
| cis-1,3-Dichloropropene | 1.4 | Not Detected | 6.6 | Not Detected |
| 4-Methyl-2-pentanone | 1.4 | 2.9 | 5.9 | 12 |
| Toluene | 1.4 | ~~0.34 J~~ U | 5.4 | ~~1.3 J~~ U |
| trans-1,3-Dichloropropene | 1.4 | Not Detected | 6.6 | Not Detected |
| 1,1,2-Trichloroethane | 1.4 | Not Detected | 7.9 | Not Detected |
| Tetrachloroethene | 1.4 | ~~0.16 J~~ U | 9.8 | ~~1.1 J~~ U |
| 2-Hexanone | 5.8 | Not Detected | 24 | Not Detected |

eurofins | Air Toxics

**Client Sample ID: VMP-29-30-020613**

**Lab ID#: 1302156A-13B**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | p021424 | **Date of Collection:** | 2/6/13 11:50:00 AM |
| **Dil. Factor:** | 2.89 | **Date of Analysis:** | 2/14/13 11:08 PM |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Dibromochloromethane | 1.4 | Not Detected | 12 | Not Detected |
| 1,2-Dibromoethane (EDB) | 1.4 | Not Detected | 11 | Not Detected |
| Chlorobenzene | 1.4 | Not Detected | 6.6 | Not Detected |
| Ethyl Benzene | 1.4 | Not Detected | 6.3 | Not Detected |
| m,p-Xylene | 1.4 | 0.48 J | 6.3 | 2.1 J |
| o-Xylene | 1.4 | Not Detected | 6.3 | Not Detected |
| Styrene | 1.4 | Not Detected | 6.2 | Not Detected |
| Bromoform | 1.4 | Not Detected | 15 | Not Detected |
| Cumene | 1.4 | ~~0.37 J~~ | 7.1 | ~~1.8 J~~ |
| 1,1,2,2-Tetrachloroethane | 1.4 | Not Detected | 9.9 | Not Detected |
| Propylbenzene | 1.4 | Not Detected | 7.1 | Not Detected |
| 4-Ethyltoluene | 1.4 | ~~0.16 J~~ | 7.1 | ~~0.78 J~~ |
| 1,3,5-Trimethylbenzene | 1.4 | Not Detected | 7.1 | Not Detected |
| 1,2,4-Trimethylbenzene | 1.4 | Not Detected | 7.1 | Not Detected |
| 1,3-Dichlorobenzene | 1.4 | Not Detected | 8.7 | Not Detected |
| 1,4-Dichlorobenzene | 1.4 | Not Detected | 8.7 | Not Detected |
| alpha-Chlorotoluene | 1.4 | Not Detected | 7.5 | Not Detected |
| 1,2-Dichlorobenzene | 1.4 | Not Detected | 8.7 | Not Detected |
| 1,2,4-Trichlorobenzene | 5.8 | Not Detected | 43 | Not Detected |
| Hexachlorobutadiene | 5.8 | Not Detected | 62 | Not Detected |
| Butane | 5.8 | 2.0 J | 14 | 4.7 J |
| Isopentane | 5.8 | 1.6 J | 17 | 4.6 J |

J = Estimated value.
E = Exceeds instrument calibration range.
**Container Type: 1 Liter Summa Canister**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| Toluene-d8 | 94 | 70-130 |
| 1,2-Dichloroethane-d4 | 88 | 70-130 |
| 4-Bromofluorobenzene | 108 | 70-130 |

eurofins | Air Toxics

**Client Sample ID: VMP-30-10-020613**

**Lab ID#: 1302156A-14A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p021426** | **Date of Collection: 2/6/13 9:47:00 AM** | |
| **Dil. Factor:** | **2.64** | **Date of Analysis: 2/15/13 09:14 AM** | |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 1.3 | 0.46 J | 6.5 | 2.2 J |
| Freon 114 | 1.3 | Not Detected | 9.2 | Not Detected |
| Chloromethane | 13 | Not Detected | 27 | Not Detected |
| Vinyl Chloride | 1.3 | Not Detected | 3.4 | Not Detected |
| 1,3-Butadiene | 1.3 | Not Detected | 2.9 | Not Detected |
| Bromomethane | 13 | Not Detected | 51 | Not Detected |
| Chloroethane | 5.3 | Not Detected | 14 | Not Detected |
| Freon 11 | 1.3 | ~~0.22 J~~ U | 7.4 | ~~1.2 J~~ U |
| Ethanol | 5.3 | 2.5 J | 9.9 | 4.6 J |
| Freon 113 | 1.3 | Not Detected | 10 | Not Detected |
| 1,1-Dichloroethene | 1.3 | Not Detected | 5.2 | Not Detected |
| Acetone | 13 | 38 | 31 | 91 |
| 2-Propanol | 5.3 | 1.2 J | 13 | 2.8 J |
| Carbon Disulfide | 5.3 | ~~2.2 J~~ U | 16 | ~~7.0 J~~ U |
| 3-Chloropropene | 5.3 | Not Detected | 16 | Not Detected |
| Methylene Chloride | 13 | ~~0.18 J~~ U | 46 | ~~0.61 J~~ U |
| Methyl tert-butyl ether | 1.3 | Not Detected | 4.8 | Not Detected |
| trans-1,2-Dichloroethene | 1.3 | Not Detected | 5.2 | Not Detected |
| Hexane | 1.3 | 0.64 J | 4.6 | 2.2 J |
| 1,1-Dichloroethane | 1.3 | Not Detected | 5.3 | Not Detected |
| 2-Butanone (Methyl Ethyl Ketone) | 5.3 | 50 | 16 | 150 |
| cis-1,2-Dichloroethene | 1.3 | Not Detected | 5.2 | Not Detected |
| Tetrahydrofuran | 1.3 | 30 | 3.9 | 90 |
| Chloroform | 1.3 | Not Detected | 6.4 | Not Detected |
| 1,1,1-Trichloroethane | 1.3 | Not Detected | 7.2 | Not Detected |
| Cyclohexane | 1.3 | Not Detected | 4.5 | Not Detected |
| Carbon Tetrachloride | 1.3 | Not Detected | 8.3 | Not Detected |
| 2,2,4-Trimethylpentane | 1.3 | 0.41 J | 6.2 | 1.9 J |
| Benzene | 1.3 | 0.57 J | 4.2 | 1.8 J |
| 1,2-Dichloroethane | 1.3 | Not Detected | 5.3 | Not Detected |
| Heptane | 1.3 | 0.34 J | 5.4 | 1.4 J |
| Trichloroethene | 1.3 | Not Detected | 7.1 | Not Detected |
| 1,2-Dichloropropane | 1.3 | Not Detected | 6.1 | Not Detected |
| 1,4-Dioxane | 5.3 | Not Detected | 19 | Not Detected |
| Bromodichloromethane | 1.3 | Not Detected | 8.8 | Not Detected |
| cis-1,3-Dichloropropene | 1.3 | Not Detected | 6.0 | Not Detected |
| 4-Methyl-2-pentanone | 1.3 | 0.56 J | 5.4 | 2.3 J |
| Toluene | 1.3 | 0.41 J | 5.0 | 1.6 J |
| trans-1,3-Dichloropropene | 1.3 | Not Detected | 6.0 | Not Detected |
| 1,1,2-Trichloroethane | 1.3 | Not Detected | 7.2 | Not Detected |
| Tetrachloroethene | 1.3 | ~~0.18 J~~ U | 9.0 | ~~1.2 J~~ U |
| 2-Hexanone | 5.3 | Not Detected | 22 | Not Detected |

eurofins | Air Toxics

**Client Sample ID: VMP-30-10-020613**

**Lab ID#: 1302156A-14A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p021426** | **Date of Collection:** | **2/6/13 9:47:00 AM** |
| **Dil. Factor:** | **2.64** | **Date of Analysis:** | **2/15/13 09:14 AM** |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Dibromochloromethane | 1.3 | Not Detected | 11 | Not Detected |
| 1,2-Dibromoethane (EDB) | 1.3 | Not Detected | 10 | Not Detected |
| Chlorobenzene | 1.3 | Not Detected | 6.1 | Not Detected |
| Ethyl Benzene | 1.3 | Not Detected | 5.7 | Not Detected |
| m,p-Xylene | 1.3 | Not Detected | 5.7 | Not Detected |
| o-Xylene | 1.3 | Not Detected | 5.7 | Not Detected |
| Styrene | 1.3 | Not Detected | 5.6 | Not Detected |
| Bromoform | 1.3 | Not Detected | 14 | Not Detected |
| Cumene | 1.3 | Not Detected | 6.5 | Not Detected |
| 1,1,2,2-Tetrachloroethane | 1.3 | Not Detected | 9.1 | Not Detected |
| Propylbenzene | 1.3 | Not Detected | 6.5 | Not Detected |
| 4-Ethyltoluene | 1.3 | Not Detected | 6.5 | Not Detected |
| 1,3,5-Trimethylbenzene | 1.3 | Not Detected | 6.5 | Not Detected |
| 1,2,4-Trimethylbenzene | 1.3 | Not Detected | 6.5 | Not Detected |
| 1,3-Dichlorobenzene | 1.3 | Not Detected | 7.9 | Not Detected |
| 1,4-Dichlorobenzene | 1.3 | Not Detected | 7.9 | Not Detected |
| alpha-Chlorotoluene | 1.3 | Not Detected | 6.8 | Not Detected |
| 1,2-Dichlorobenzene | 1.3 | Not Detected | 7.9 | Not Detected |
| 1,2,4-Trichlorobenzene | 5.3 | Not Detected | 39 | Not Detected |
| Hexachlorobutadiene | 5.3 | Not Detected | 56 | Not Detected |
| Butane | 5.3 | Not Detected | 12 | Not Detected |
| Isopentane | 5.3 | 2.6 J | 16 | 7.7 J |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| Toluene-d8 | 96 | 70-130 |
| 1,2-Dichloroethane-d4 | 88 | 70-130 |
| 4-Bromofluorobenzene | 95 | 70-130 |

eurofins | Air Toxics

**Client Sample ID: VMP-30-20-020613**

**Lab ID#: 1302156A-15A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p021506** | **Date of Collection:** | **2/6/13 10:47:00 AM** |
| **Dil. Factor:** | **2.64** | **Date of Analysis:** | **2/15/13 12:26 PM** |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 1.3 | 0.44 J | 6.5 | 2.2 J |
| Freon 114 | 1.3 | Not Detected | 9.2 | Not Detected |
| Chloromethane | 13 | Not Detected | 27 | Not Detected |
| Vinyl Chloride | 1.3 | Not Detected | 3.4 | Not Detected |
| 1,3-Butadiene | 1.3 | Not Detected | 2.9 | Not Detected |
| Bromomethane | 13 | Not Detected | 51 | Not Detected |
| Chloroethane | 5.3 | Not Detected | 14 | Not Detected |
| Freon 11 | 1.3 | ~~0.26 J~~ U | 7.4 | ~~1.4 J~~ U |
| Ethanol | 5.3 | 4.2 J | 9.9 | 8.0 J |
| Freon 113 | 1.3 | Not Detected | 10 | Not Detected |
| 1,1-Dichloroethene | 1.3 | Not Detected | 5.2 | Not Detected |
| Acetone | 13 | 70 | 31 | 170 |
| 2-Propanol | 5.3 | 4.5 J | 13 | 11 J |
| Carbon Disulfide | 5.3 | 25 | 16 | 77 |
| 3-Chloropropene | 5.3 | Not Detected | 16 | Not Detected |
| Methylene Chloride | 13 | ~~0.52 J~~ U | 46 | ~~1.8 J~~ U |
| Methyl tert-butyl ether | 1.3 | Not Detected | 4.8 | Not Detected |
| trans-1,2-Dichloroethene | 1.3 | Not Detected | 5.2 | Not Detected |
| Hexane | 1.3 | 0.70 J | 4.6 | 2.5 J |
| 1,1-Dichloroethane | 1.3 | Not Detected | 5.3 | Not Detected |
| 2-Butanone (Methyl Ethyl Ketone) | 5.3 | 200 | 16 | 600 |
| cis-1,2-Dichloroethene | 1.3 | Not Detected | 5.2 | Not Detected |
| Tetrahydrofuran | 1.3 | 70 | 3.9 | 210 |
| Chloroform | 1.3 | 2.5 | 6.4 | 12 |
| 1,1,1-Trichloroethane | 1.3 | Not Detected | 7.2 | Not Detected |
| Cyclohexane | 1.3 | Not Detected | 4.5 | Not Detected |
| Carbon Tetrachloride | 1.3 | Not Detected | 8.3 | Not Detected |
| 2,2,4-Trimethylpentane | 1.3 | ~~0.25 J~~ U | 6.2 | ~~1.2 J~~ U |
| Benzene | 1.3 | 34 | 4.2 | 110 |
| 1,2-Dichloroethane | 1.3 | Not Detected | 5.3 | Not Detected |
| Heptane | 1.3 | Not Detected | 5.4 | Not Detected |
| Trichloroethene | 1.3 | Not Detected | 7.1 | Not Detected |
| 1,2-Dichloropropane | 1.3 | Not Detected | 6.1 | Not Detected |
| 1,4-Dioxane | 5.3 | Not Detected | 19 | Not Detected |
| Bromodichloromethane | 1.3 | Not Detected | 8.8 | Not Detected |
| cis-1,3-Dichloropropene | 1.3 | Not Detected | 6.0 | Not Detected |
| 4-Methyl-2-pentanone | 1.3 | 0.82 J | 5.4 | 3.4 J |
| Toluene | 1.3 | ~~0.34 J~~ U | 5.0 | ~~1.3 J~~ U |
| trans-1,3-Dichloropropene | 1.3 | Not Detected | 6.0 | Not Detected |
| 1,1,2-Trichloroethane | 1.3 | Not Detected | 7.2 | Not Detected |
| Tetrachloroethene | 1.3 | ~~0.31 J~~ U | 9.0 | ~~2.1 J~~ U |
| 2-Hexanone | 5.3 | Not Detected | 22 | Not Detected |

eurofins | Air Toxics

**Client Sample ID: VMP-30-20-020613**

**Lab ID#: 1302156A-15A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p021506** | **Date of Collection: 2/6/13 10:47:00 AM** | |
| **Dil. Factor:** | **2.64** | **Date of Analysis: 2/15/13 12:26 PM** | |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Dibromochloromethane | 1.3 | Not Detected | 11 | Not Detected |
| 1,2-Dibromoethane (EDB) | 1.3 | Not Detected | 10 | Not Detected |
| Chlorobenzene | 1.3 | Not Detected | 6.1 | Not Detected |
| Ethyl Benzene | 1.3 | Not Detected | 5.7 | Not Detected |
| m,p-Xylene | 1.3 | 0.34 J | 5.7 | 1.5 J |
| o-Xylene | 1.3 | Not Detected | 5.7 | Not Detected |
| Styrene | 1.3 | Not Detected | 5.6 | Not Detected |
| Bromoform | 1.3 | Not Detected | 14 | Not Detected |
| Cumene | 1.3 | ~~0.25 J~~ | 6.5 | ~~1.2 J~~ |
| 1,1,2,2-Tetrachloroethane | 1.3 | Not Detected | 9.1 | Not Detected |
| Propylbenzene | 1.3 | ~~0.21 J~~ | 6.5 | ~~1.0 J~~ |
| 4-Ethyltoluene | 1.3 | ~~0.16 J~~ | 6.5 | ~~0.81 J~~ |
| 1,3,5-Trimethylbenzene | 1.3 | ~~0.25 J~~ | 6.5 | ~~1.2 J~~ |
| 1,2,4-Trimethylbenzene | 1.3 | ~~0.34 J~~ | 6.5 | ~~1.7 J~~ |
| 1,3-Dichlorobenzene | 1.3 | ~~0.48 J~~ | 7.9 | ~~2.9 J~~ |
| 1,4-Dichlorobenzene | 1.3 | ~~0.46 J~~ | 7.9 | ~~2.7 J~~ |
| alpha-Chlorotoluene | 1.3 | ~~0.33 J~~ | 6.8 | ~~1.7 J~~ |
| 1,2-Dichlorobenzene | 1.3 | ~~0.36 J~~ | 7.9 | ~~2.2 J~~ |
| 1,2,4-Trichlorobenzene | 5.3 | ~~1.5 J~~ | 39 | ~~11 J~~ |
| Hexachlorobutadiene | 5.3 | ~~0.61 J~~ | 56 | ~~6.5 J~~ |
| Butane | 5.3 | 3.7 J | 12 | 8.8 J |
| Isopentane | 5.3 | 2.5 J | 16 | 7.3 J |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| Toluene-d8 | 94 | 70-130 |
| 1,2-Dichloroethane-d4 | 89 | 70-130 |
| 4-Bromofluorobenzene | 105 | 70-130 |

eurofins | Air Toxics

**Client Sample ID: VMP-30-30-020613**
**Lab ID#: 1302156A-16A**

* USE THIS RESULT ONLY. ALL OTHER DATA REPORTED IN 8.90X DILUTION ANALYSIS

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p021524** | **Date of Collection:** | **2/6/13 11:45:00 AM** |
| **Dil. Factor:** | **17.6** | **Date of Analysis:** | **2/15/13 10:29 PM** |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 8.8 | Not Detected | 44 | Not Detected |
| Freon 114 | 8.8 | Not Detected | 62 | Not Detected |
| Chloromethane | 88 | Not Detected | 180 | Not Detected |
| Vinyl Chloride | 8.8 | Not Detected | 22 | Not Detected |
| 1,3-Butadiene | 8.8 | Not Detected | 19 | Not Detected |
| Bromomethane | 88 | Not Detected | 340 | Not Detected |
| Chloroethane | 35 | Not Detected | 93 | Not Detected |
| Freon 11 | 8.8 | Not Detected | 49 | Not Detected |
| Ethanol | 35 | Not Detected | 66 | Not Detected |
| Freon 113 | 8.8 | Not Detected | 67 | Not Detected |
| 1,1-Dichloroethene | 8.8 | Not Detected | 35 | Not Detected |
| Acetone | 88 | 1200 | 210 | 2800 |
| 2-Propanol | 35 | 14 J | 86 | 35 J |
| Carbon Disulfide | 35 | 32 J | 110 | 100 J |
| 3-Chloropropene | 35 | Not Detected | 110 | Not Detected |
| Methylene Chloride | 88 | Not Detected | 300 | Not Detected |
| Methyl tert-butyl ether | 8.8 | Not Detected | 32 | Not Detected |
| trans-1,2-Dichloroethene | 8.8 | Not Detected | 35 | Not Detected |
| Hexane | 8.8 | Not Detected | 31 | Not Detected |
| 1,1-Dichloroethane | 8.8 | Not Detected | 36 | Not Detected |
| * 2-Butanone (Methyl Ethyl Ketone) | 35 | 2200 | 100 | 6400 |
| cis-1,2-Dichloroethene | 8.8 | Not Detected | 35 | Not Detected |
| Tetrahydrofuran | 8.8 | 900 | 26 | 2700 |
| Chloroform | 8.8 | 2.4 J | 43 | 12 J |
| 1,1,1-Trichloroethane | 8.8 | Not Detected | 48 | Not Detected |
| Cyclohexane | 8.8 | Not Detected | 30 | Not Detected |
| Carbon Tetrachloride | 8.8 | Not Detected | 55 | Not Detected |
| 2,2,4-Trimethylpentane | 8.8 | Not Detected | 41 | Not Detected |
| Benzene | 8.8 | 450 | 28 | 1400 |
| 1,2-Dichloroethane | 8.8 | Not Detected | 36 | Not Detected |
| Heptane | 8.8 | Not Detected | 36 | Not Detected |
| Trichloroethene | 8.8 | Not Detected | 47 | Not Detected |
| 1,2-Dichloropropane | 8.8 | Not Detected | 41 | Not Detected |
| 1,4-Dioxane | 35 | Not Detected | 130 | Not Detected |
| Bromodichloromethane | 8.8 | Not Detected | 59 | Not Detected |
| cis-1,3-Dichloropropene | 8.8 | Not Detected | 40 | Not Detected |
| 4-Methyl-2-pentanone | 8.8 | Not Detected | 36 | Not Detected |
| Toluene | 8.8 | Not Detected | 33 | Not Detected |
| trans-1,3-Dichloropropene | 8.8 | Not Detected | 40 | Not Detected |
| 1,1,2-Trichloroethane | 8.8 | Not Detected | 48 | Not Detected |
| Tetrachloroethene | 8.8 | Not Detected | 60 | Not Detected |
| 2-Hexanone | 35 | Not Detected | 140 | Not Detected |

eurofins | Air Toxics

**Client Sample ID: VMP-30-30-020613**

**Lab ID#: 1302156A-16A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p021524** | **Date of Collection: 2/6/13 11:45:00 AM** | |
| **Dil. Factor:** | **17.6** | **Date of Analysis: 2/15/13 10:29 PM** | |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Dibromochloromethane | 8.8 | Not Detected | 75 | Not Detected |
| 1,2-Dibromoethane (EDB) | 8.8 | Not Detected | 68 | Not Detected |
| Chlorobenzene | 8.8 | Not Detected | 40 | Not Detected |
| Ethyl Benzene | 8.8 | Not Detected | 38 | Not Detected |
| m,p-Xylene | 8.8 | Not Detected | 38 | Not Detected |
| o-Xylene | 8.8 | Not Detected | 38 | Not Detected |
| Styrene | 8.8 | Not Detected | 37 | Not Detected |
| Bromoform | 8.8 | Not Detected | 91 | Not Detected |
| Cumene | 8.8 | Not Detected | 43 | Not Detected |
| 1,1,2,2-Tetrachloroethane | 8.8 | Not Detected | 60 | Not Detected |
| Propylbenzene | 8.8 | Not Detected | 43 | Not Detected |
| 4-Ethyltoluene | 8.8 | Not Detected | 43 | Not Detected |
| 1,3,5-Trimethylbenzene | 8.8 | Not Detected | 43 | Not Detected |
| 1,2,4-Trimethylbenzene | 8.8 | Not Detected | 43 | Not Detected |
| 1,3-Dichlorobenzene | 8.8 | Not Detected | 53 | Not Detected |
| 1,4-Dichlorobenzene | 8.8 | Not Detected | 53 | Not Detected |
| alpha-Chlorotoluene | 8.8 | Not Detected | 46 | Not Detected |
| 1,2-Dichlorobenzene | 8.8 | Not Detected | 53 | Not Detected |
| 1,2,4-Trichlorobenzene | 35 | Not Detected | 260 | Not Detected |
| Hexachlorobutadiene | 35 | Not Detected | 380 | Not Detected |
| Butane | 35 | Not Detected | 84 | Not Detected |
| Isopentane | 35 | Not Detected | 100 | Not Detected |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| Toluene-d8 | 92 | 70-130 |
| 1,2-Dichloroethane-d4 | 100 | 70-130 |
| 4-Bromofluorobenzene | 104 | 70-130 |

eurofins | Air Toxics

Client Sample ID: VMP-30-30-020613
Lab ID#: 1302156A-16B

* DO NOT USE THIS RESULT. USE ALL OTHER DATA.

EPA METHOD TO-15 GC/MS FULL SCAN

File Name: p021507
Dil. Factor: 8.80
Date of Collection: 2/6/13 11:45:00 AM
Date of Analysis: 2/15/13 12:54 PM

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 4.4 | Not Detected | 22 | Not Detected |
| Freon 114 | 4.4 | Not Detected | 31 | Not Detected |
| Chloromethane | 44 | Not Detected | 91 | Not Detected |
| Vinyl Chloride | 4.4 | Not Detected | 11 | Not Detected |
| 1,3-Butadiene | 4.4 | Not Detected | 9.7 | Not Detected |
| Bromomethane | 44 | Not Detected | 170 | Not Detected |
| Chloroethane | 18 | Not Detected | 46 | Not Detected |
| Freon 11 | 4.4 | Not Detected | 25 | Not Detected |
| Ethanol | 18 | 2.3 J | 33 | 4.4 J |
| Freon 113 | 4.4 | Not Detected | 34 | Not Detected |
| 1,1-Dichloroethene | 4.4 | Not Detected | 17 | Not Detected |
| Acetone | 44 | 1200 | 100 | 2800 |
| 2-Propanol | 18 | 15 J | 43 | 37 J |
| Carbon Disulfide | 18 | 32 | 55 | 100 |
| 3-Chloropropene | 18 | Not Detected | 55 | Not Detected |
| Methylene Chloride | 44 | Not Detected | 150 | Not Detected |
| Methyl tert-butyl ether | 4.4 | Not Detected | 16 | Not Detected |
| trans-1,2-Dichloroethene | 4.4 | Not Detected | 17 | Not Detected |
| Hexane | 4.4 | Not Detected | 16 | Not Detected |
| 1,1-Dichloroethane | 4.4 | Not Detected | 18 | Not Detected |
| * ~~2-Butanone (Methyl Ethyl Ketone)~~ | ~~18~~ | ~~2200 E~~ | ~~52~~ | ~~6600 E~~ |
| cis-1,2-Dichloroethene | 4.4 | Not Detected | 17 | Not Detected |
| Tetrahydrofuran | 4.4 | 880 | 13 | 2600 |
| Chloroform | 4.4 | 2.1 J | 21 | 10 J |
| 1,1,1-Trichloroethane | 4.4 | Not Detected | 24 | Not Detected |
| Cyclohexane | 4.4 | Not Detected | 15 | Not Detected |
| Carbon Tetrachloride | 4.4 | Not Detected | 28 | Not Detected |
| 2,2,4-Trimethylpentane | 4.4 | Not Detected | 20 | Not Detected |
| Benzene | 4.4 | 430 | 14 | 1400 |
| 1,2-Dichloroethane | 4.4 | Not Detected | 18 | Not Detected |
| Heptane | 4.4 | Not Detected | 18 | Not Detected |
| Trichloroethene | 4.4 | Not Detected | 24 | Not Detected |
| 1,2-Dichloropropane | 4.4 | Not Detected | 20 | Not Detected |
| 1,4-Dioxane | 18 | Not Detected | 63 | Not Detected |
| Bromodichloromethane | 4.4 | Not Detected | 29 | Not Detected |
| cis-1,3-Dichloropropene | 4.4 | Not Detected | 20 | Not Detected |
| 4-Methyl-2-pentanone | 4.4 | Not Detected | 18 | Not Detected |
| Toluene | 4.4 | Not Detected | 16 | Not Detected |
| trans-1,3-Dichloropropene | 4.4 | Not Detected | 20 | Not Detected |
| 1,1,2-Trichloroethane | 4.4 | Not Detected | 24 | Not Detected |
| Tetrachloroethene | 4.4 | Not Detected | 30 | Not Detected |
| 2-Hexanone | 18 | Not Detected | 72 | Not Detected |

eurofins | Air Toxics

**Client Sample ID: VMP-30-30-020613**

**Lab ID#: 1302156A-16B**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p021507** | **Date of Collection:** | **2/6/13 11:45:00 AM** |
| **Dil. Factor:** | **8.80** | **Date of Analysis:** | **2/15/13 12:54 PM** |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Dibromochloromethane | 4.4 | Not Detected | 37 | Not Detected |
| 1,2-Dibromoethane (EDB) | 4.4 | Not Detected | 34 | Not Detected |
| Chlorobenzene | 4.4 | Not Detected | 20 | Not Detected |
| Ethyl Benzene | 4.4 | Not Detected | 19 | Not Detected |
| m,p-Xylene | 4.4 | Not Detected | 19 | Not Detected |
| o-Xylene | 4.4 | Not Detected | 19 | Not Detected |
| Styrene | 4.4 | Not Detected | 19 | Not Detected |
| Bromoform | 4.4 | Not Detected | 45 | Not Detected |
| Cumene | 4.4 | Not Detected | 22 | Not Detected |
| 1,1,2,2-Tetrachloroethane | 4.4 | Not Detected | 30 | Not Detected |
| Propylbenzene | 4.4 | Not Detected | 22 | Not Detected |
| 4-Ethyltoluene | 4.4 | Not Detected | 22 | Not Detected |
| 1,3,5-Trimethylbenzene | 4.4 | Not Detected | 22 | Not Detected |
| 1,2,4-Trimethylbenzene | 4.4 | Not Detected | 22 | Not Detected |
| 1,3-Dichlorobenzene | 4.4 | Not Detected | 26 | Not Detected |
| 1,4-Dichlorobenzene | 4.4 | Not Detected | 26 | Not Detected |
| alpha-Chlorotoluene | 4.4 | Not Detected | 23 | Not Detected |
| 1,2-Dichlorobenzene | 4.4 | Not Detected | 26 | Not Detected |
| 1,2,4-Trichlorobenzene | 18 | ~~1.2 J~~ | 130 | ~~9.2 J~~ |
| Hexachlorobutadiene | 18 | Not Detected | 190 | Not Detected |
| Butane | 18 | Not Detected | 42 | Not Detected |
| Isopentane | 18 | Not Detected | 52 | Not Detected |

J = Estimated value.
E = Exceeds instrument calibration range.
**Container Type: 1 Liter Summa Canister**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| Toluene-d8 | 93 | 70-130 |
| 1,2-Dichloroethane-d4 | 89 | 70-130 |
| 4-Bromofluorobenzene | 105 | 70-130 |

eurofins | Air Toxics

**Client Sample ID: VMP-32-5-020513**
**Lab ID#: 1302156A-17A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | p021508 | **Date of Collection:** | 2/5/13 9:23:00 AM |
| **Dil. Factor:** | 2.52 | **Date of Analysis:** | 2/15/13 01:51 PM |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 1.3 | 0.48 J | 6.2 | 2.4 J |
| Freon 114 | 1.3 | Not Detected | 8.8 | Not Detected |
| Chloromethane | 13 | Not Detected | 26 | Not Detected |
| Vinyl Chloride | 1.3 | Not Detected | 3.2 | Not Detected |
| 1,3-Butadiene | 1.3 | Not Detected | 2.8 | Not Detected |
| Bromomethane | 13 | Not Detected | 49 | Not Detected |
| Chloroethane | 5.0 | Not Detected | 13 | Not Detected |
| Freon 11 | 1.3 | ~~0.22 J~~ U | 7.1 | ~~1.2 J~~ U |
| Ethanol | 5.0 | 6.5 | 9.5 | 12 |
| Freon 113 | 1.3 | Not Detected | 9.6 | Not Detected |
| 1,1-Dichloroethene | 1.3 | Not Detected | 5.0 | Not Detected |
| Acetone | 13 | 4.6 J | 30 | 11 J |
| 2-Propanol | 5.0 | 5.5 | 12 | 13 |
| Carbon Disulfide | 5.0 | ~~0.94 J~~ U | 16 | ~~2.9 J~~ U |
| 3-Chloropropene | 5.0 | Not Detected | 16 | Not Detected |
| Methylene Chloride | 13 | ~~0.23 J~~ U | 44 | ~~0.81 J~~ U |
| Methyl tert-butyl ether | 1.3 | Not Detected | 4.5 | Not Detected |
| trans-1,2-Dichloroethene | 1.3 | Not Detected | 5.0 | Not Detected |
| Hexane | 1.3 | Not Detected | 4.4 | Not Detected |
| 1,1-Dichloroethane | 1.3 | Not Detected | 5.1 | Not Detected |
| 2-Butanone (Methyl Ethyl Ketone) | 5.0 | Not Detected | 15 | Not Detected |
| cis-1,2-Dichloroethene | 1.3 | Not Detected | 5.0 | Not Detected |
| Tetrahydrofuran | 1.3 | 0.47 J | 3.7 | 1.4 J |
| Chloroform | 1.3 | Not Detected | 6.2 | Not Detected |
| 1,1,1-Trichloroethane | 1.3 | Not Detected | 6.9 | Not Detected |
| Cyclohexane | 1.3 | Not Detected | 4.3 | Not Detected |
| Carbon Tetrachloride | 1.3 | Not Detected | 7.9 | Not Detected |
| 2,2,4-Trimethylpentane | 1.3 | 1.8 | 5.9 | 8.6 |
| Benzene | 1.3 | 1.3 | 4.0 | 4.2 |
| 1,2-Dichloroethane | 1.3 | Not Detected | 5.1 | Not Detected |
| Heptane | 1.3 | Not Detected | 5.2 | Not Detected |
| Trichloroethene | 1.3 | Not Detected | 6.8 | Not Detected |
| 1,2-Dichloropropane | 1.3 | Not Detected | 5.8 | Not Detected |
| 1,4-Dioxane | 5.0 | Not Detected | 18 | Not Detected |
| Bromodichloromethane | 1.3 | Not Detected | 8.4 | Not Detected |
| cis-1,3-Dichloropropene | 1.3 | Not Detected | 5.7 | Not Detected |
| 4-Methyl-2-pentanone | 1.3 | Not Detected | 5.2 | Not Detected |
| Toluene | 1.3 | ~~0.12 J~~ U | 4.7 | ~~0.44 J~~ U |
| trans-1,3-Dichloropropene | 1.3 | Not Detected | 5.7 | Not Detected |
| 1,1,2-Trichloroethane | 1.3 | Not Detected | 6.9 | Not Detected |
| Tetrachloroethene | 1.3 | ~~0.13 J~~ U | 8.5 | ~~0.90 J~~ U |
| 2-Hexanone | 5.0 | Not Detected | 21 | Not Detected |

eurofins | Air Toxics

**Client Sample ID: VMP-32-5-020513**

**Lab ID#: 1302156A-17A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p021508** | **Date of Collection:** | **2/5/13 9:23:00 AM** |
| **Dil. Factor:** | **2.52** | **Date of Analysis:** | **2/15/13 01:51 PM** |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Dibromochloromethane | 1.3 | Not Detected | 11 | Not Detected |
| 1,2-Dibromoethane (EDB) | 1.3 | Not Detected | 9.7 | Not Detected |
| Chlorobenzene | 1.3 | Not Detected | 5.8 | Not Detected |
| Ethyl Benzene | 1.3 | Not Detected | 5.5 | Not Detected |
| m,p-Xylene | 1.3 | Not Detected | 5.5 | Not Detected |
| o-Xylene | 1.3 | Not Detected | 5.5 | Not Detected |
| Styrene | 1.3 | Not Detected | 5.4 | Not Detected |
| Bromoform | 1.3 | Not Detected | 13 | Not Detected |
| Cumene | 1.3 | Not Detected | 6.2 | Not Detected |
| 1,1,2,2-Tetrachloroethane | 1.3 | Not Detected | 8.6 | Not Detected |
| Propylbenzene | 1.3 | ~~0.14 J~~ U | 6.2 | ~~0.71 J~~ U |
| 4-Ethyltoluene | 1.3 | ~~0.22 J~~ U | 6.2 | ~~1.1 J~~ U |
| 1,3,5-Trimethylbenzene | 1.3 | Not Detected | 6.2 | Not Detected |
| 1,2,4-Trimethylbenzene | 1.3 | ~~0.42 J~~ U | 6.2 | ~~2.1 J~~ U |
| 1,3-Dichlorobenzene | 1.3 | ~~0.19 J~~ U | 7.6 | ~~1.1 J~~ U |
| 1,4-Dichlorobenzene | 1.3 | ~~0.20 J~~ U | 7.6 | ~~1.2 J~~ U |
| alpha-Chlorotoluene | 1.3 | Not Detected | 6.5 | Not Detected |
| 1,2-Dichlorobenzene | 1.3 | Not Detected | 7.6 | Not Detected |
| 1,2,4-Trichlorobenzene | 5.0 | ~~0.63 J~~ U | 37 | ~~4.6 J~~ U |
| Hexachlorobutadiene | 5.0 | Not Detected | 54 | Not Detected |
| Butane | 5.0 | Not Detected | 12 | Not Detected |
| Isopentane | 5.0 | 0.77 J | 15 | 2.3 J |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| Toluene-d8 | 98 | 70-130 |
| 1,2-Dichloroethane-d4 | 89 | 70-130 |
| 4-Bromofluorobenzene | 94 | 70-130 |

eurofins | Air Toxics

**Client Sample ID: VMP-32-10-020513**

**Lab ID#: 1302156A-18A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | p021509 | **Date of Collection:** | 2/5/13 10:09:00 AM |
| **Dil. Factor:** | 2.52 | **Date of Analysis:** | 2/15/13 02:23 PM |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 1.3 | 0.52 J | 6.2 | 2.6 J |
| Freon 114 | 1.3 | Not Detected | 8.8 | Not Detected |
| Chloromethane | 13 | Not Detected | 26 | Not Detected |
| Vinyl Chloride | 1.3 | Not Detected | 3.2 | Not Detected |
| 1,3-Butadiene | 1.3 | Not Detected | 2.8 | Not Detected |
| Bromomethane | 13 | Not Detected | 49 | Not Detected |
| Chloroethane | 5.0 | Not Detected | 13 | Not Detected |
| Freon 11 | 1.3 | ~~0.25 J~~ U | 7.1 | ~~1.4 J~~ U |
| Ethanol | 5.0 | 7.2 | 9.5 | 14 |
| Freon 113 | 1.3 | Not Detected | 9.6 | Not Detected |
| 1,1-Dichloroethene | 1.3 | Not Detected | 5.0 | Not Detected |
| Acetone | 13 | 3.9 J | 30 | 9.2 J |
| 2-Propanol | 5.0 | 3.6 J | 12 | 8.9 J |
| Carbon Disulfide | 5.0 | ~~0.80 J~~ U | 16 | ~~2.5 J~~ U |
| 3-Chloropropene | 5.0 | Not Detected | 16 | Not Detected |
| Methylene Chloride | 13 | ~~0.23 J~~ U | 44 | ~~0.79 J~~ U |
| Methyl tert-butyl ether | 1.3 | Not Detected | 4.5 | Not Detected |
| trans-1,2-Dichloroethene | 1.3 | Not Detected | 5.0 | Not Detected |
| Hexane | 1.3 | Not Detected | 4.4 | Not Detected |
| 1,1-Dichloroethane | 1.3 | Not Detected | 5.1 | Not Detected |
| 2-Butanone (Methyl Ethyl Ketone) | 5.0 | Not Detected | 15 | Not Detected |
| cis-1,2-Dichloroethene | 1.3 | Not Detected | 5.0 | Not Detected |
| Tetrahydrofuran | 1.3 | 0.47 J | 3.7 | 1.4 J |
| Chloroform | 1.3 | Not Detected | 6.2 | Not Detected |
| 1,1,1-Trichloroethane | 1.3 | Not Detected | 6.9 | Not Detected |
| Cyclohexane | 1.3 | Not Detected | 4.3 | Not Detected |
| Carbon Tetrachloride | 1.3 | Not Detected | 7.9 | Not Detected |
| 2,2,4-Trimethylpentane | 1.3 | 1.8 | 5.9 | 8.4 |
| Benzene | 1.3 | 1.6 | 4.0 | 5.1 |
| 1,2-Dichloroethane | 1.3 | Not Detected | 5.1 | Not Detected |
| Heptane | 1.3 | Not Detected | 5.2 | Not Detected |
| Trichloroethene | 1.3 | Not Detected | 6.8 | Not Detected |
| 1,2-Dichloropropane | 1.3 | Not Detected | 5.8 | Not Detected |
| 1,4-Dioxane | 5.0 | Not Detected | 18 | Not Detected |
| Bromodichloromethane | 1.3 | Not Detected | 8.4 | Not Detected |
| cis-1,3-Dichloropropene | 1.3 | Not Detected | 5.7 | Not Detected |
| 4-Methyl-2-pentanone | 1.3 | Not Detected | 5.2 | Not Detected |
| Toluene | 1.3 | ~~0.11 J~~ U | 4.7 | ~~0.42 J~~ U |
| trans-1,3-Dichloropropene | 1.3 | Not Detected | 5.7 | Not Detected |
| 1,1,2-Trichloroethane | 1.3 | Not Detected | 6.9 | Not Detected |
| Tetrachloroethene | 1.3 | ~~0.13 J~~ U | 8.5 | ~~0.90 J~~ U |
| 2-Hexanone | 5.0 | Not Detected | 21 | Not Detected |

eurofins | Air Toxics

**Client Sample ID: VMP-32-10-020513**

**Lab ID#: 1302156A-18A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p021509** | **Date of Collection:** | **2/5/13 10:09:00 AM** |
| **Dil. Factor:** | **2.52** | **Date of Analysis:** | **2/15/13 02:23 PM** |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Dibromochloromethane | 1.3 | Not Detected | 11 | Not Detected |
| 1,2-Dibromoethane (EDB) | 1.3 | Not Detected | 9.7 | Not Detected |
| Chlorobenzene | 1.3 | Not Detected | 5.8 | Not Detected |
| Ethyl Benzene | 1.3 | Not Detected | 5.5 | Not Detected |
| m,p-Xylene | 1.3 | Not Detected | 5.5 | Not Detected |
| o-Xylene | 1.3 | Not Detected | 5.5 | Not Detected |
| Styrene | 1.3 | Not Detected | 5.4 | Not Detected |
| Bromoform | 1.3 | Not Detected | 13 | Not Detected |
| Cumene | 1.3 | Not Detected | 6.2 | Not Detected |
| 1,1,2,2-Tetrachloroethane | 1.3 | Not Detected | 8.6 | Not Detected |
| Propylbenzene | 1.3 | Not Detected | 6.2 | Not Detected |
| 4-Ethyltoluene | 1.3 | ~~0.11 J~~ U | 6.2 | ~~0.55 J~~ U |
| 1,3,5-Trimethylbenzene | 1.3 | Not Detected | 6.2 | Not Detected |
| 1,2,4-Trimethylbenzene | 1.3 | Not Detected | 6.2 | Not Detected |
| 1,3-Dichlorobenzene | 1.3 | Not Detected | 7.6 | Not Detected |
| 1,4-Dichlorobenzene | 1.3 | Not Detected | 7.6 | Not Detected |
| alpha-Chlorotoluene | 1.3 | Not Detected | 6.5 | Not Detected |
| 1,2-Dichlorobenzene | 1.3 | Not Detected | 7.6 | Not Detected |
| 1,2,4-Trichlorobenzene | 5.0 | ~~0.39 J~~ U | 37 | ~~2.9 J~~ U |
| Hexachlorobutadiene | 5.0 | Not Detected | 54 | Not Detected |
| Butane | 5.0 | Not Detected | 12 | Not Detected |
| Isopentane | 5.0 | Not Detected | 15 | Not Detected |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| Toluene-d8 | 97 | 70-130 |
| 1,2-Dichloroethane-d4 | 89 | 70-130 |
| 4-Bromofluorobenzene | 95 | 70-130 |

eurofins | Air Toxics

**Client Sample ID: VMP-32-20-020513**

**Lab ID#: 1302156A-19A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | p021510 | **Date of Collection:** | 2/5/13 10:58:00 AM |
| **Dil. Factor:** | 2.82 | **Date of Analysis:** | 2/15/13 03:04 PM |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 1.4 | 0.49 J | 7.0 | 2.4 J |
| Freon 114 | 1.4 | Not Detected | 9.8 | Not Detected |
| Chloromethane | 14 | Not Detected | 29 | Not Detected |
| Vinyl Chloride | 1.4 | Not Detected | 3.6 | Not Detected |
| 1,3-Butadiene | 1.4 | Not Detected | 3.1 | Not Detected |
| Bromomethane | 14 | Not Detected | 55 | Not Detected |
| Chloroethane | 5.6 | Not Detected | 15 | Not Detected |
| Freon 11 | 1.4 | ~~0.23 J~~ U | 7.9 | ~~1.3 J~~ U |
| Ethanol | 5.6 | 1.8 J | 11 | 3.5 J |
| Freon 113 | 1.4 | Not Detected | 11 | Not Detected |
| 1,1-Dichloroethene | 1.4 | Not Detected | 5.6 | Not Detected |
| Acetone | 14 | 4.2 J | 33 | 9.9 J |
| 2-Propanol | 5.6 | 2.6 J | 14 | 6.4 J |
| Carbon Disulfide | 5.6 | ~~0.80 J~~ U | 18 | ~~2.5 J~~ U |
| 3-Chloropropene | 5.6 | Not Detected | 18 | Not Detected |
| Methylene Chloride | 14 | ~~0.18 J~~ U | 49 | ~~0.63 J~~ U |
| Methyl tert-butyl ether | 1.4 | Not Detected | 5.1 | Not Detected |
| trans-1,2-Dichloroethene | 1.4 | Not Detected | 5.6 | Not Detected |
| Hexane | 1.4 | Not Detected | 5.0 | Not Detected |
| 1,1-Dichloroethane | 1.4 | Not Detected | 5.7 | Not Detected |
| 2-Butanone (Methyl Ethyl Ketone) | 5.6 | Not Detected | 17 | Not Detected |
| cis-1,2-Dichloroethene | 1.4 | Not Detected | 5.6 | Not Detected |
| Tetrahydrofuran | 1.4 | Not Detected | 4.2 | Not Detected |
| Chloroform | 1.4 | 0.26 J | 6.9 | 1.3 J |
| 1,1,1-Trichloroethane | 1.4 | Not Detected | 7.7 | Not Detected |
| Cyclohexane | 1.4 | Not Detected | 4.8 | Not Detected |
| Carbon Tetrachloride | 1.4 | Not Detected | 8.9 | Not Detected |
| 2,2,4-Trimethylpentane | 1.4 | 6.1 | 6.6 | 28 |
| Benzene | 1.4 | 0.83 J | 4.5 | 2.7 J |
| 1,2-Dichloroethane | 1.4 | Not Detected | 5.7 | Not Detected |
| Heptane | 1.4 | Not Detected | 5.8 | Not Detected |
| Trichloroethene | 1.4 | Not Detected | 7.6 | Not Detected |
| 1,2-Dichloropropane | 1.4 | Not Detected | 6.5 | Not Detected |
| 1,4-Dioxane | 5.6 | Not Detected | 20 | Not Detected |
| Bromodichloromethane | 1.4 | Not Detected | 9.4 | Not Detected |
| cis-1,3-Dichloropropene | 1.4 | Not Detected | 6.4 | Not Detected |
| 4-Methyl-2-pentanone | 1.4 | 0.80 J | 5.8 | 3.3 J |
| Toluene | 1.4 | ~~0.13 J~~ U | 5.3 | ~~0.49 J~~ U |
| trans-1,3-Dichloropropene | 1.4 | Not Detected | 6.4 | Not Detected |
| 1,1,2-Trichloroethane | 1.4 | Not Detected | 7.7 | Not Detected |
| Tetrachloroethene | 1.4 | ~~0.24 J~~ U | 9.6 | ~~1.6 J~~ U |
| 2-Hexanone | 5.6 | Not Detected | 23 | Not Detected |

eurofins | Air Toxics

**Client Sample ID: VMP-32-20-020513**

**Lab ID#: 1302156A-19A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p021510** | **Date of Collection:** | **2/5/13 10:58:00 AM** |
| **Dil. Factor:** | **2.82** | **Date of Analysis:** | **2/15/13 03:04 PM** |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Dibromochloromethane | 1.4 | Not Detected | 12 | Not Detected |
| 1,2-Dibromoethane (EDB) | 1.4 | Not Detected | 11 | Not Detected |
| Chlorobenzene | 1.4 | Not Detected | 6.5 | Not Detected |
| Ethyl Benzene | 1.4 | Not Detected | 6.1 | Not Detected |
| m,p-Xylene | 1.4 | Not Detected | 6.1 | Not Detected |
| o-Xylene | 1.4 | Not Detected | 6.1 | Not Detected |
| Styrene | 1.4 | Not Detected | 6.0 | Not Detected |
| Bromoform | 1.4 | Not Detected | 14 | Not Detected |
| Cumene | 1.4 | Not Detected | 6.9 | Not Detected |
| 1,1,2,2-Tetrachloroethane | 1.4 | Not Detected | 9.7 | Not Detected |
| Propylbenzene | 1.4 | Not Detected | 6.9 | Not Detected |
| 4-Ethyltoluene | 1.4 | Not Detected | 6.9 | Not Detected |
| 1,3,5-Trimethylbenzene | 1.4 | Not Detected | 6.9 | Not Detected |
| 1,2,4-Trimethylbenzene | 1.4 | Not Detected | 6.9 | Not Detected |
| 1,3-Dichlorobenzene | 1.4 | Not Detected | 8.5 | Not Detected |
| 1,4-Dichlorobenzene | 1.4 | Not Detected | 8.5 | Not Detected |
| alpha-Chlorotoluene | 1.4 | Not Detected | 7.3 | Not Detected |
| 1,2-Dichlorobenzene | 1.4 | Not Detected | 8.5 | Not Detected |
| 1,2,4-Trichlorobenzene | 5.6 | ~~0.43 J~~ | 42 | ~~3.2 J~~ |
| Hexachlorobutadiene | 5.6 | Not Detected | 60 | Not Detected |
| Butane | 5.6 | Not Detected | 13 | Not Detected |
| Isopentane | 5.6 | Not Detected | 17 | Not Detected |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| Toluene-d8 | 100 | 70-130 |
| 1,2-Dichloroethane-d4 | 91 | 70-130 |
| 4-Bromofluorobenzene | 97 | 70-130 |

eurofins | Air Toxics

**Client Sample ID: VMP-53-5-020513**

**Lab ID#: 1302156A-20A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p021511** | **Date of Collection:** | **2/5/13 9:17:00 AM** |
| **Dil. Factor:** | **2.58** | **Date of Analysis:** | **2/15/13 03:45 PM** |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 1.3 | 0.44 J | 6.4 | 2.2 J |
| Freon 114 | 1.3 | Not Detected | 9.0 | Not Detected |
| Chloromethane | 13 | Not Detected | 27 | Not Detected |
| Vinyl Chloride | 1.3 | Not Detected | 3.3 | Not Detected |
| 1,3-Butadiene | 1.3 | Not Detected | 2.8 | Not Detected |
| Bromomethane | 13 | Not Detected | 50 | Not Detected |
| Chloroethane | 5.2 | Not Detected | 14 | Not Detected |
| Freon 11 | 1.3 | ~~0.25 J~~ U | 7.2 | ~~1.4 J~~ U |
| Ethanol | 5.2 | 1.4 J | 9.7 | 2.7 J |
| Freon 113 | 1.3 | Not Detected | 9.9 | Not Detected |
| 1,1-Dichloroethene | 1.3 | Not Detected | 5.1 | Not Detected |
| Acetone | 13 | 6.5 J | 31 | 15 J |
| 2-Propanol | 5.2 | 1.2 J | 13 | 2.8 J |
| Carbon Disulfide | 5.2 | ~~1.0 J~~ U | 16 | ~~3.2 J~~ U |
| 3-Chloropropene | 5.2 | Not Detected | 16 | Not Detected |
| Methylene Chloride | 13 | Not Detected | 45 | Not Detected |
| Methyl tert-butyl ether | 1.3 | Not Detected | 4.6 | Not Detected |
| trans-1,2-Dichloroethene | 1.3 | Not Detected | 5.1 | Not Detected |
| Hexane | 1.3 | 0.26 J | 4.5 | 0.92 J |
| 1,1-Dichloroethane | 1.3 | Not Detected | 5.2 | Not Detected |
| 2-Butanone (Methyl Ethyl Ketone) | 5.2 | Not Detected | 15 | Not Detected |
| cis-1,2-Dichloroethene | 1.3 | Not Detected | 5.1 | Not Detected |
| Tetrahydrofuran | 1.3 | Not Detected | 3.8 | Not Detected |
| Chloroform | 1.3 | Not Detected | 6.3 | Not Detected |
| 1,1,1-Trichloroethane | 1.3 | Not Detected | 7.0 | Not Detected |
| Cyclohexane | 1.3 | Not Detected | 4.4 | Not Detected |
| Carbon Tetrachloride | 1.3 | Not Detected | 8.1 | Not Detected |
| 2,2,4-Trimethylpentane | 1.3 | 0.44 J | 6.0 | 2.0 J |
| Benzene | 1.3 | Not Detected | 4.1 | Not Detected |
| 1,2-Dichloroethane | 1.3 | Not Detected | 5.2 | Not Detected |
| Heptane | 1.3 | Not Detected | 5.3 | Not Detected |
| Trichloroethene | 1.3 | Not Detected | 6.9 | Not Detected |
| 1,2-Dichloropropane | 1.3 | Not Detected | 6.0 | Not Detected |
| 1,4-Dioxane | 5.2 | Not Detected | 18 | Not Detected |
| Bromodichloromethane | 1.3 | Not Detected | 8.6 | Not Detected |
| cis-1,3-Dichloropropene | 1.3 | Not Detected | 5.8 | Not Detected |
| 4-Methyl-2-pentanone | 1.3 | Not Detected | 5.3 | Not Detected |
| Toluene | 1.3 | ~~0.11 J~~ U | 4.9 | ~~0.42 J~~ U |
| trans-1,3-Dichloropropene | 1.3 | Not Detected | 5.8 | Not Detected |
| 1,1,2-Trichloroethane | 1.3 | Not Detected | 7.0 | Not Detected |
| Tetrachloroethene | 1.3 | ~~0.18 J~~ U | 8.8 | ~~1.2 J~~ U |
| 2-Hexanone | 5.2 | Not Detected | 21 | Not Detected |

eurofins | Air Toxics

**Client Sample ID: VMP-53-5-020513**

**Lab ID#: 1302156A-20A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | p021511 | **Date of Collection:** | 2/5/13 9:17:00 AM |
| **Dil. Factor:** | 2.58 | **Date of Analysis:** | 2/15/13 03:45 PM |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Dibromochloromethane | 1.3 | Not Detected | 11 | Not Detected |
| 1,2-Dibromoethane (EDB) | 1.3 | Not Detected | 9.9 | Not Detected |
| Chlorobenzene | 1.3 | Not Detected | 5.9 | Not Detected |
| Ethyl Benzene | 1.3 | Not Detected | 5.6 | Not Detected |
| m,p-Xylene | 1.3 | Not Detected | 5.6 | Not Detected |
| o-Xylene | 1.3 | Not Detected | 5.6 | Not Detected |
| Styrene | 1.3 | Not Detected | 5.5 | Not Detected |
| Bromoform | 1.3 | Not Detected | 13 | Not Detected |
| Cumene | 1.3 | Not Detected | 6.3 | Not Detected |
| 1,1,2,2-Tetrachloroethane | 1.3 | Not Detected | 8.8 | Not Detected |
| Propylbenzene | 1.3 | Not Detected | 6.3 | Not Detected |
| 4-Ethyltoluene | 1.3 | Not Detected | 6.3 | Not Detected |
| 1,3,5-Trimethylbenzene | 1.3 | Not Detected | 6.3 | Not Detected |
| 1,2,4-Trimethylbenzene | 1.3 | Not Detected | 6.3 | Not Detected |
| 1,3-Dichlorobenzene | 1.3 | Not Detected | 7.8 | Not Detected |
| 1,4-Dichlorobenzene | 1.3 | Not Detected | 7.8 | Not Detected |
| alpha-Chlorotoluene | 1.3 | Not Detected | 6.7 | Not Detected |
| 1,2-Dichlorobenzene | 1.3 | Not Detected | 7.8 | Not Detected |
| 1,2,4-Trichlorobenzene | 5.2 | Not Detected | 38 | Not Detected |
| Hexachlorobutadiene | 5.2 | Not Detected | 55 | Not Detected |
| Butane | 5.2 | 1.3 J | 12 | 3.2 J |
| Isopentane | 5.2 | 0.58 J | 15 | 1.7 J |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| Toluene-d8 | 97 | 70-130 |
| 1,2-Dichloroethane-d4 | 94 | 70-130 |
| 4-Bromofluorobenzene | 95 | 70-130 |

eurofins | Air Toxics

**Client Sample ID: VMP-53-10-020513**

**Lab ID#: 1302156A-21A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p021512** | **Date of Collection:** | **2/5/13 10:04:00 AM** |
| **Dil. Factor:** | **2.64** | **Date of Analysis:** | **2/15/13 04:28 PM** |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 1.3 | 0.56 J | 6.5 | 2.8 J |
| Freon 114 | 1.3 | Not Detected | 9.2 | Not Detected |
| Chloromethane | 13 | Not Detected | 27 | Not Detected |
| Vinyl Chloride | 1.3 | Not Detected | 3.4 | Not Detected |
| 1,3-Butadiene | 1.3 | Not Detected | 2.9 | Not Detected |
| Bromomethane | 13 | Not Detected | 51 | Not Detected |
| Chloroethane | 5.3 | Not Detected | 14 | Not Detected |
| Freon 11 | 1.3 | ~~0.22 J~~ U | 7.4 | ~~1.3 J~~ U |
| Ethanol | 5.3 | 0.93 J | 9.9 | 1.8 J |
| Freon 113 | 1.3 | Not Detected | 10 | Not Detected |
| 1,1-Dichloroethene | 1.3 | Not Detected | 5.2 | Not Detected |
| Acetone | 13 | 4.0 J | 31 | 9.4 J |
| 2-Propanol | 5.3 | 2.1 J | 13 | 5.2 J |
| Carbon Disulfide | 5.3 | ~~0.76 J~~ U | 16 | ~~2.4 J~~ U |
| 3-Chloropropene | 5.3 | Not Detected | 16 | Not Detected |
| Methylene Chloride | 13 | Not Detected | 46 | Not Detected |
| Methyl tert-butyl ether | 1.3 | Not Detected | 4.8 | Not Detected |
| trans-1,2-Dichloroethene | 1.3 | Not Detected | 5.2 | Not Detected |
| Hexane | 1.3 | 1.1 J | 4.6 | 4.0 J |
| 1,1-Dichloroethane | 1.3 | Not Detected | 5.3 | Not Detected |
| 2-Butanone (Methyl Ethyl Ketone) | 5.3 | Not Detected | 16 | Not Detected |
| cis-1,2-Dichloroethene | 1.3 | Not Detected | 5.2 | Not Detected |
| Tetrahydrofuran | 1.3 | Not Detected | 3.9 | Not Detected |
| Chloroform | 1.3 | Not Detected | 6.4 | Not Detected |
| 1,1,1-Trichloroethane | 1.3 | Not Detected | 7.2 | Not Detected |
| Cyclohexane | 1.3 | 1.2 J | 4.5 | 4.3 J |
| Carbon Tetrachloride | 1.3 | Not Detected | 8.3 | Not Detected |
| 2,2,4-Trimethylpentane | 1.3 | 0.81 J | 6.2 | 3.8 J |
| Benzene | 1.3 | 18 | 4.2 | 59 |
| 1,2-Dichloroethane | 1.3 | Not Detected | 5.3 | Not Detected |
| Heptane | 1.3 | 0.40 J | 5.4 | 1.6 J |
| Trichloroethene | 1.3 | Not Detected | 7.1 | Not Detected |
| 1,2-Dichloropropane | 1.3 | Not Detected | 6.1 | Not Detected |
| 1,4-Dioxane | 5.3 | Not Detected | 19 | Not Detected |
| Bromodichloromethane | 1.3 | Not Detected | 8.8 | Not Detected |
| cis-1,3-Dichloropropene | 1.3 | Not Detected | 6.0 | Not Detected |
| 4-Methyl-2-pentanone | 1.3 | Not Detected | 5.4 | Not Detected |
| Toluene | 1.3 | ~~0.15 J~~ U | 5.0 | ~~0.58 J~~ U |
| trans-1,3-Dichloropropene | 1.3 | Not Detected | 6.0 | Not Detected |
| 1,1,2-Trichloroethane | 1.3 | Not Detected | 7.2 | Not Detected |
| Tetrachloroethene | 1.3 | Not Detected | 9.0 | Not Detected |
| 2-Hexanone | 5.3 | Not Detected | 22 | Not Detected |

eurofins | Air Toxics

**Client Sample ID: VMP-53-10-020513**

**Lab ID#: 1302156A-21A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p021512** | **Date of Collection: 2/5/13 10:04:00 AM** | |
| **Dil. Factor:** | **2.64** | **Date of Analysis: 2/15/13 04:28 PM** | |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Dibromochloromethane | 1.3 | Not Detected | 11 | Not Detected |
| 1,2-Dibromoethane (EDB) | 1.3 | Not Detected | 10 | Not Detected |
| Chlorobenzene | 1.3 | Not Detected | 6.1 | Not Detected |
| Ethyl Benzene | 1.3 | Not Detected | 5.7 | Not Detected |
| m,p-Xylene | 1.3 | Not Detected | 5.7 | Not Detected |
| o-Xylene | 1.3 | Not Detected | 5.7 | Not Detected |
| Styrene | 1.3 | Not Detected | 5.6 | Not Detected |
| Bromoform | 1.3 | Not Detected | 14 | Not Detected |
| Cumene | 1.3 | Not Detected | 6.5 | Not Detected |
| 1,1,2,2-Tetrachloroethane | 1.3 | Not Detected | 9.1 | Not Detected |
| Propylbenzene | 1.3 | Not Detected | 6.5 | Not Detected |
| 4-Ethyltoluene | 1.3 | Not Detected | 6.5 | Not Detected |
| 1,3,5-Trimethylbenzene | 1.3 | Not Detected | 6.5 | Not Detected |
| 1,2,4-Trimethylbenzene | 1.3 | Not Detected | 6.5 | Not Detected |
| 1,3-Dichlorobenzene | 1.3 | Not Detected | 7.9 | Not Detected |
| 1,4-Dichlorobenzene | 1.3 | Not Detected | 7.9 | Not Detected |
| alpha-Chlorotoluene | 1.3 | Not Detected | 6.8 | Not Detected |
| 1,2-Dichlorobenzene | 1.3 | Not Detected | 7.9 | Not Detected |
| 1,2,4-Trichlorobenzene | 5.3 | Not Detected | 39 | Not Detected |
| Hexachlorobutadiene | 5.3 | Not Detected | 56 | Not Detected |
| Butane | 5.3 | 2.2 J | 12 | 5.1 J |
| Isopentane | 5.3 | 4.3 J | 16 | 13 J |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| Toluene-d8 | 97 | 70-130 |
| 1,2-Dichloroethane-d4 | 92 | 70-130 |
| 4-Bromofluorobenzene | 97 | 70-130 |

eurofins | Air Toxics

**Client Sample ID: VMP-53-10-020513-DUP**

**Lab ID#: 1302156A-22A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | p021513 | **Date of Collection:** | 2/5/13 10:04:00 AM |
| **Dil. Factor:** | 2.47 | **Date of Analysis:** | 2/15/13 04:59 PM |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 1.2 | 0.49 J | 6.1 | 2.4 J |
| Freon 114 | 1.2 | Not Detected | 8.6 | Not Detected |
| Chloromethane | 12 | Not Detected | 26 | Not Detected |
| Vinyl Chloride | 1.2 | Not Detected | 3.2 | Not Detected |
| 1,3-Butadiene | 1.2 | Not Detected | 2.7 | Not Detected |
| Bromomethane | 12 | Not Detected | 48 | Not Detected |
| Chloroethane | 4.9 | Not Detected | 13 | Not Detected |
| Freon 11 | 1.2 | ~~0.21 J~~ | 6.9 | ~~1.2 J~~ |
| Ethanol | 4.9 | Not Detected | 9.3 | Not Detected |
| Freon 113 | 1.2 | Not Detected | 9.5 | Not Detected |
| 1,1-Dichloroethene | 1.2 | Not Detected | 4.9 | Not Detected |
| Acetone | 12 | 4.0 J | 29 | 9.6 J |
| 2-Propanol | 4.9 | 0.57 J | 12 | 1.4 J |
| Carbon Disulfide | 4.9 | ~~0.60 J~~ | 15 | ~~1.9 J~~ |
| 3-Chloropropene | 4.9 | Not Detected | 15 | Not Detected |
| Methylene Chloride | 12 | Not Detected | 43 | Not Detected |
| Methyl tert-butyl ether | 1.2 | Not Detected | 4.4 | Not Detected |
| trans-1,2-Dichloroethene | 1.2 | Not Detected | 4.9 | Not Detected |
| Hexane | 1.2 | 0.60 J | 4.4 | 2.1 J |
| 1,1-Dichloroethane | 1.2 | Not Detected | 5.0 | Not Detected |
| 2-Butanone (Methyl Ethyl Ketone) | 4.9 | Not Detected | 14 | Not Detected |
| cis-1,2-Dichloroethene | 1.2 | Not Detected | 4.9 | Not Detected |
| Tetrahydrofuran | 1.2 | Not Detected | 3.6 | Not Detected |
| Chloroform | 1.2 | Not Detected | 6.0 | Not Detected |
| 1,1,1-Trichloroethane | 1.2 | Not Detected | 6.7 | Not Detected |
| Cyclohexane | 1.2 | Not Detected | 4.2 | Not Detected |
| Carbon Tetrachloride | 1.2 | Not Detected | 7.8 | Not Detected |
| 2,2,4-Trimethylpentane | 1.2 | ~~0.22 J~~ | 5.8 | ~~1.0 J~~ |
| Benzene | 1.2 | 5.4 | 3.9 | 17 |
| 1,2-Dichloroethane | 1.2 | Not Detected | 5.0 | Not Detected |
| Heptane | 1.2 | 0.32 J | 5.1 | 1.3 J |
| Trichloroethene | 1.2 | Not Detected | 6.6 | Not Detected |
| 1,2-Dichloropropane | 1.2 | Not Detected | 5.7 | Not Detected |
| 1,4-Dioxane | 4.9 | Not Detected | 18 | Not Detected |
| Bromodichloromethane | 1.2 | Not Detected | 8.3 | Not Detected |
| cis-1,3-Dichloropropene | 1.2 | Not Detected | 5.6 | Not Detected |
| 4-Methyl-2-pentanone | 1.2 | Not Detected | 5.0 | Not Detected |
| Toluene | 1.2 | ~~0.12 J~~ | 4.6 | ~~0.47 J~~ |
| trans-1,3-Dichloropropene | 1.2 | Not Detected | 5.6 | Not Detected |
| 1,1,2-Trichloroethane | 1.2 | Not Detected | 6.7 | Not Detected |
| Tetrachloroethene | 1.2 | Not Detected | 8.4 | Not Detected |
| 2-Hexanone | 4.9 | Not Detected | 20 | Not Detected |

eurofins | Air Toxics

**Client Sample ID: VMP-53-10-020513-DUP**

**Lab ID#: 1302156A-22A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p021513** | **Date of Collection: 2/5/13 10:04:00 AM** | |
| **Dil. Factor:** | **2.47** | **Date of Analysis: 2/15/13 04:59 PM** | |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Dibromochloromethane | 1.2 | Not Detected | 10 | Not Detected |
| 1,2-Dibromoethane (EDB) | 1.2 | Not Detected | 9.5 | Not Detected |
| Chlorobenzene | 1.2 | Not Detected | 5.7 | Not Detected |
| Ethyl Benzene | 1.2 | Not Detected | 5.4 | Not Detected |
| m,p-Xylene | 1.2 | Not Detected | 5.4 | Not Detected |
| o-Xylene | 1.2 | Not Detected | 5.4 | Not Detected |
| Styrene | 1.2 | Not Detected | 5.3 | Not Detected |
| Bromoform | 1.2 | Not Detected | 13 | Not Detected |
| Cumene | 1.2 | Not Detected | 6.1 | Not Detected |
| 1,1,2,2-Tetrachloroethane | 1.2 | Not Detected | 8.5 | Not Detected |
| Propylbenzene | 1.2 | Not Detected | 6.1 | Not Detected |
| 4-Ethyltoluene | 1.2 | Not Detected | 6.1 | Not Detected |
| 1,3,5-Trimethylbenzene | 1.2 | Not Detected | 6.1 | Not Detected |
| 1,2,4-Trimethylbenzene | 1.2 | Not Detected | 6.1 | Not Detected |
| 1,3-Dichlorobenzene | 1.2 | Not Detected | 7.4 | Not Detected |
| 1,4-Dichlorobenzene | 1.2 | Not Detected | 7.4 | Not Detected |
| alpha-Chlorotoluene | 1.2 | Not Detected | 6.4 | Not Detected |
| 1,2-Dichlorobenzene | 1.2 | Not Detected | 7.4 | Not Detected |
| 1,2,4-Trichlorobenzene | 4.9 | Not Detected | 37 | Not Detected |
| Hexachlorobutadiene | 4.9 | Not Detected | 53 | Not Detected |
| Butane | 4.9 | 1.4 J | 12 | 3.2 J |
| Isopentane | 4.9 | 2.2 J | 14 | 6.5 J |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| Toluene-d8 | 96 | 70-130 |
| 1,2-Dichloroethane-d4 | 95 | 70-130 |
| 4-Bromofluorobenzene | 97 | 70-130 |

eurofins | Air Toxics

**Client Sample ID: VMP-53-20-020513**

**Lab ID#: 1302156A-23A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | p021514 | **Date of Collection:** | 2/5/13 10:47:00 AM |
| **Dil. Factor:** | 2.64 | **Date of Analysis:** | 2/15/13 05:21 PM |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 1.3 | 0.52 J | 6.5 | 2.6 J |
| Freon 114 | 1.3 | Not Detected | 9.2 | Not Detected |
| Chloromethane | 13 | Not Detected | 27 | Not Detected |
| Vinyl Chloride | 1.3 | Not Detected | 3.4 | Not Detected |
| 1,3-Butadiene | 1.3 | Not Detected | 2.9 | Not Detected |
| Bromomethane | 13 | Not Detected | 51 | Not Detected |
| Chloroethane | 5.3 | Not Detected | 14 | Not Detected |
| Freon 11 | 1.3 | ~~0.23 J~~ U | 7.4 | ~~1.3 J~~ U |
| Ethanol | 5.3 | 1.7 J | 9.9 | 3.2 J |
| Freon 113 | 1.3 | Not Detected | 10 | Not Detected |
| 1,1-Dichloroethene | 1.3 | Not Detected | 5.2 | Not Detected |
| Acetone | 13 | 4.7 J | 31 | 11 J |
| 2-Propanol | 5.3 | 0.70 J | 13 | 1.7 J |
| Carbon Disulfide | 5.3 | ~~0.74 J~~ U | 16 | ~~2.3 J~~ U |
| 3-Chloropropene | 5.3 | Not Detected | 16 | Not Detected |
| Methylene Chloride | 13 | Not Detected | 46 | Not Detected |
| Methyl tert-butyl ether | 1.3 | Not Detected | 4.8 | Not Detected |
| trans-1,2-Dichloroethene | 1.3 | Not Detected | 5.2 | Not Detected |
| Hexane | 1.3 | 0.45 J | 4.6 | 1.6 J |
| 1,1-Dichloroethane | 1.3 | Not Detected | 5.3 | Not Detected |
| 2-Butanone (Methyl Ethyl Ketone) | 5.3 | Not Detected | 16 | Not Detected |
| cis-1,2-Dichloroethene | 1.3 | Not Detected | 5.2 | Not Detected |
| Tetrahydrofuran | 1.3 | Not Detected | 3.9 | Not Detected |
| Chloroform | 1.3 | 1.0 J | 6.4 | 5.1 J |
| 1,1,1-Trichloroethane | 1.3 | Not Detected | 7.2 | Not Detected |
| Cyclohexane | 1.3 | Not Detected | 4.5 | Not Detected |
| Carbon Tetrachloride | 1.3 | Not Detected | 8.3 | Not Detected |
| 2,2,4-Trimethylpentane | 1.3 | 0.51 J | 6.2 | 2.4 J |
| Benzene | 1.3 | 27 | 4.2 | 86 |
| 1,2-Dichloroethane | 1.3 | Not Detected | 5.3 | Not Detected |
| Heptane | 1.3 | Not Detected | 5.4 | Not Detected |
| Trichloroethene | 1.3 | Not Detected | 7.1 | Not Detected |
| 1,2-Dichloropropane | 1.3 | Not Detected | 6.1 | Not Detected |
| 1,4-Dioxane | 5.3 | Not Detected | 19 | Not Detected |
| Bromodichloromethane | 1.3 | Not Detected | 8.8 | Not Detected |
| cis-1,3-Dichloropropene | 1.3 | Not Detected | 6.0 | Not Detected |
| 4-Methyl-2-pentanone | 1.3 | Not Detected | 5.4 | Not Detected |
| Toluene | 1.3 | ~~0.28 J~~ U | 5.0 | ~~1.0 J~~ U |
| trans-1,3-Dichloropropene | 1.3 | Not Detected | 6.0 | Not Detected |
| 1,1,2-Trichloroethane | 1.3 | Not Detected | 7.2 | Not Detected |
| Tetrachloroethene | 1.3 | ~~0.15 J~~ U | 9.0 | ~~1.0 J~~ U |
| 2-Hexanone | 5.3 | Not Detected | 22 | Not Detected |

eurofins | Air Toxics

**Client Sample ID: VMP-53-20-020513**

**Lab ID#: 1302156A-23A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p021514** | **Date of Collection: 2/5/13 10:47:00 AM** | |
| **Dil. Factor:** | **2.64** | **Date of Analysis: 2/15/13 05:21 PM** | |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Dibromochloromethane | 1.3 | Not Detected | 11 | Not Detected |
| 1,2-Dibromoethane (EDB) | 1.3 | Not Detected | 10 | Not Detected |
| Chlorobenzene | 1.3 | Not Detected | 6.1 | Not Detected |
| Ethyl Benzene | 1.3 | Not Detected | 5.7 | Not Detected |
| m,p-Xylene | 1.3 | Not Detected | 5.7 | Not Detected |
| o-Xylene | 1.3 | Not Detected | 5.7 | Not Detected |
| Styrene | 1.3 | Not Detected | 5.6 | Not Detected |
| Bromoform | 1.3 | Not Detected | 14 | Not Detected |
| Cumene | 1.3 | Not Detected | 6.5 | Not Detected |
| 1,1,2,2-Tetrachloroethane | 1.3 | Not Detected | 9.1 | Not Detected |
| Propylbenzene | 1.3 | ~~0.14 J~~ U | 6.5 | ~~0.67 J~~ U |
| 4-Ethyltoluene | 1.3 | Not Detected | 6.5 | Not Detected |
| 1,3,5-Trimethylbenzene | 1.3 | Not Detected | 6.5 | Not Detected |
| 1,2,4-Trimethylbenzene | 1.3 | Not Detected | 6.5 | Not Detected |
| 1,3-Dichlorobenzene | 1.3 | Not Detected | 7.9 | Not Detected |
| 1,4-Dichlorobenzene | 1.3 | Not Detected | 7.9 | Not Detected |
| alpha-Chlorotoluene | 1.3 | Not Detected | 6.8 | Not Detected |
| 1,2-Dichlorobenzene | 1.3 | Not Detected | 7.9 | Not Detected |
| 1,2,4-Trichlorobenzene | 5.3 | ~~0.36 J~~ U | 39 | ~~2.7 J~~ U |
| Hexachlorobutadiene | 5.3 | Not Detected | 56 | Not Detected |
| Butane | 5.3 | Not Detected | 12 | Not Detected |
| Isopentane | 5.3 | 2.0 J | 16 | 6.0 J |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| Toluene-d8 | 97 | 70-130 |
| 1,2-Dichloroethane-d4 | 92 | 70-130 |
| 4-Bromofluorobenzene | 101 | 70-130 |

eurofins | Air Toxics

**Client Sample ID: VMP-53-30-020513**

**Lab ID#: 1302156A-24A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | p021515 | **Date of Collection:** | 2/5/13 11:29:00 AM |
| **Dil. Factor:** | 2.69 | **Date of Analysis:** | 2/15/13 05:48 PM |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 1.3 | 0.52 J | 6.6 | 2.6 J |
| Freon 114 | 1.3 | Not Detected | 9.4 | Not Detected |
| Chloromethane | 13 | Not Detected | 28 | Not Detected |
| Vinyl Chloride | 1.3 | Not Detected | 3.4 | Not Detected |
| 1,3-Butadiene | 1.3 | Not Detected | 3.0 | Not Detected |
| Bromomethane | 13 | Not Detected | 52 | Not Detected |
| Chloroethane | 5.4 | Not Detected | 14 | Not Detected |
| Freon 11 | 1.3 | ~~0.23 J~~ U | 7.6 | ~~1.3 J~~ U |
| Ethanol | 5.4 | Not Detected | 10 | Not Detected |
| Freon 113 | 1.3 | Not Detected | 10 | Not Detected |
| 1,1-Dichloroethene | 1.3 | Not Detected | 5.3 | Not Detected |
| Acetone | 13 | 3.2 J | 32 | 7.6 J |
| 2-Propanol | 5.4 | 0.51 J | 13 | 1.2 J |
| Carbon Disulfide | 5.4 | ~~0.77 J~~ U | 17 | ~~2.4 J~~ U |
| 3-Chloropropene | 5.4 | Not Detected | 17 | Not Detected |
| Methylene Chloride | 13 | Not Detected | 47 | Not Detected |
| Methyl tert-butyl ether | 1.3 | Not Detected | 4.8 | Not Detected |
| trans-1,2-Dichloroethene | 1.3 | Not Detected | 5.3 | Not Detected |
| Hexane | 1.3 | 0.23 J | 4.7 | 0.81 J |
| 1,1-Dichloroethane | 1.3 | Not Detected | 5.4 | Not Detected |
| 2-Butanone (Methyl Ethyl Ketone) | 5.4 | Not Detected | 16 | Not Detected |
| cis-1,2-Dichloroethene | 1.3 | Not Detected | 5.3 | Not Detected |
| Tetrahydrofuran | 1.3 | Not Detected | 4.0 | Not Detected |
| Chloroform | 1.3 | 2.4 | 6.6 | 12 |
| 1,1,1-Trichloroethane | 1.3 | Not Detected | 7.3 | Not Detected |
| Cyclohexane | 1.3 | Not Detected | 4.6 | Not Detected |
| Carbon Tetrachloride | 1.3 | Not Detected | 8.5 | Not Detected |
| 2,2,4-Trimethylpentane | 1.3 | 0.50 J | 6.3 | 2.3 J |
| Benzene | 1.3 | Not Detected | 4.3 | Not Detected |
| 1,2-Dichloroethane | 1.3 | Not Detected | 5.4 | Not Detected |
| Heptane | 1.3 | Not Detected | 5.5 | Not Detected |
| Trichloroethene | 1.3 | Not Detected | 7.2 | Not Detected |
| 1,2-Dichloropropane | 1.3 | Not Detected | 6.2 | Not Detected |
| 1,4-Dioxane | 5.4 | Not Detected | 19 | Not Detected |
| Bromodichloromethane | 1.3 | Not Detected | 9.0 | Not Detected |
| cis-1,3-Dichloropropene | 1.3 | Not Detected | 6.1 | Not Detected |
| 4-Methyl-2-pentanone | 1.3 | Not Detected | 5.5 | Not Detected |
| Toluene | 1.3 | ~~0.16 J~~ U | 5.1 | ~~0.58 J~~ U |
| trans-1,3-Dichloropropene | 1.3 | Not Detected | 6.1 | Not Detected |
| 1,1,2-Trichloroethane | 1.3 | Not Detected | 7.3 | Not Detected |
| Tetrachloroethene | 1.3 | ~~0.17 J~~ U | 9.1 | ~~1.2 J~~ U |
| 2-Hexanone | 5.4 | Not Detected | 22 | Not Detected |

eurofins | Air Toxics

**Client Sample ID: VMP-53-30-020513**

**Lab ID#: 1302156A-24A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p021515** | **Date of Collection:** | **2/5/13 11:29:00 AM** |
| **Dil. Factor:** | **2.69** | **Date of Analysis:** | **2/15/13 05:48 PM** |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Dibromochloromethane | 1.3 | Not Detected | 11 | Not Detected |
| 1,2-Dibromoethane (EDB) | 1.3 | Not Detected | 10 | Not Detected |
| Chlorobenzene | 1.3 | Not Detected | 6.2 | Not Detected |
| Ethyl Benzene | 1.3 | Not Detected | 5.8 | Not Detected |
| m,p-Xylene | 1.3 | Not Detected | 5.8 | Not Detected |
| o-Xylene | 1.3 | Not Detected | 5.8 | Not Detected |
| Styrene | 1.3 | Not Detected | 5.7 | Not Detected |
| Bromoform | 1.3 | Not Detected | 14 | Not Detected |
| Cumene | 1.3 | Not Detected | 6.6 | Not Detected |
| 1,1,2,2-Tetrachloroethane | 1.3 | Not Detected | 9.2 | Not Detected |
| Propylbenzene | 1.3 | Not Detected | 6.6 | Not Detected |
| 4-Ethyltoluene | 1.3 | Not Detected | 6.6 | Not Detected |
| 1,3,5-Trimethylbenzene | 1.3 | Not Detected | 6.6 | Not Detected |
| 1,2,4-Trimethylbenzene | 1.3 | Not Detected | 6.6 | Not Detected |
| 1,3-Dichlorobenzene | 1.3 | Not Detected | 8.1 | Not Detected |
| 1,4-Dichlorobenzene | 1.3 | Not Detected | 8.1 | Not Detected |
| alpha-Chlorotoluene | 1.3 | Not Detected | 7.0 | Not Detected |
| 1,2-Dichlorobenzene | 1.3 | Not Detected | 8.1 | Not Detected |
| 1,2,4-Trichlorobenzene | 5.4 | Not Detected | 40 | Not Detected |
| Hexachlorobutadiene | 5.4 | Not Detected | 57 | Not Detected |
| Butane | 5.4 | Not Detected | 13 | Not Detected |
| Isopentane | 5.4 | Not Detected | 16 | Not Detected |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| Toluene-d8 | 97 | 70-130 |
| 1,2-Dichloroethane-d4 | 92 | 70-130 |
| 4-Bromofluorobenzene | 94 | 70-130 |

eurofins | Air Toxics

**Client Sample ID: VMP-54-5-020613**

**Lab ID#: 1302156A-25A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p021516** | **Date of Collection: 2/6/13 10:18:00 AM** | |
| **Dil. Factor:** | **2.76** | **Date of Analysis: 2/15/13 06:19 PM** | |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 1.4 | 0.42 J | 6.8 | 2.1 J |
| Freon 114 | 1.4 | Not Detected | 9.6 | Not Detected |
| Chloromethane | 14 | Not Detected | 28 | Not Detected |
| Vinyl Chloride | 1.4 | Not Detected | 3.5 | Not Detected |
| 1,3-Butadiene | 1.4 | Not Detected | 3.0 | Not Detected |
| Bromomethane | 14 | Not Detected | 54 | Not Detected |
| Chloroethane | 5.5 | Not Detected | 14 | Not Detected |
| Freon 11 | 1.4 | ~~0.22 J~~ U | 7.8 | ~~1.2 J~~ U |
| Ethanol | 5.5 | 2.0 J | 10 | 3.7 J |
| Freon 113 | 1.4 | Not Detected | 10 | Not Detected |
| 1,1-Dichloroethene | 1.4 | Not Detected | 5.5 | Not Detected |
| Acetone | 14 | 3.8 J | 33 | 9.2 J |
| 2-Propanol | 5.5 | 2.4 J | 14 | 5.8 J |
| Carbon Disulfide | 5.5 | ~~1.2 J~~ U | 17 | ~~3.7 J~~ U |
| 3-Chloropropene | 5.5 | Not Detected | 17 | Not Detected |
| Methylene Chloride | 14 | Not Detected | 48 | Not Detected |
| Methyl tert-butyl ether | 1.4 | Not Detected | 5.0 | Not Detected |
| trans-1,2-Dichloroethene | 1.4 | Not Detected | 5.5 | Not Detected |
| Hexane | 1.4 | 1.7 | 4.9 | 6.0 |
| 1,1-Dichloroethane | 1.4 | Not Detected | 5.6 | Not Detected |
| 2-Butanone (Methyl Ethyl Ketone) | 5.5 | Not Detected | 16 | Not Detected |
| cis-1,2-Dichloroethene | 1.4 | Not Detected | 5.5 | Not Detected |
| Tetrahydrofuran | 1.4 | Not Detected | 4.1 | Not Detected |
| Chloroform | 1.4 | Not Detected | 6.7 | Not Detected |
| 1,1,1-Trichloroethane | 1.4 | Not Detected | 7.5 | Not Detected |
| Cyclohexane | 1.4 | 0.77 J | 4.8 | 2.6 J |
| Carbon Tetrachloride | 1.4 | Not Detected | 8.7 | Not Detected |
| 2,2,4-Trimethylpentane | 1.4 | 4.8 | 6.4 | 22 |
| Benzene | 1.4 | 0.74 J | 4.4 | 2.4 J |
| 1,2-Dichloroethane | 1.4 | Not Detected | 5.6 | Not Detected |
| Heptane | 1.4 | 1.2 J | 5.6 | 5.0 J |
| Trichloroethene | 1.4 | Not Detected | 7.4 | Not Detected |
| 1,2-Dichloropropane | 1.4 | Not Detected | 6.4 | Not Detected |
| 1,4-Dioxane | 5.5 | Not Detected | 20 | Not Detected |
| Bromodichloromethane | 1.4 | Not Detected | 9.2 | Not Detected |
| cis-1,3-Dichloropropene | 1.4 | Not Detected | 6.3 | Not Detected |
| 4-Methyl-2-pentanone | 1.4 | Not Detected | 5.6 | Not Detected |
| Toluene | 1.4 | 2.4 | 5.2 | 9.2 |
| trans-1,3-Dichloropropene | 1.4 | Not Detected | 6.3 | Not Detected |
| 1,1,2-Trichloroethane | 1.4 | Not Detected | 7.5 | Not Detected |
| Tetrachloroethene | 1.4 | ~~0.19 J~~ U | 9.4 | ~~1.3 J~~ U |
| 2-Hexanone | 5.5 | Not Detected | 23 | Not Detected |

eurofins | Air Toxics

**Client Sample ID: VMP-54-5-020613**

**Lab ID#: 1302156A-25A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p021516** | **Date of Collection: 2/6/13 10:18:00 AM** | |
| **Dil. Factor:** | **2.76** | **Date of Analysis: 2/15/13 06:19 PM** | |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Dibromochloromethane | 1.4 | Not Detected | 12 | Not Detected |
| 1,2-Dibromoethane (EDB) | 1.4 | Not Detected | 11 | Not Detected |
| Chlorobenzene | 1.4 | Not Detected | 6.4 | Not Detected |
| Ethyl Benzene | 1.4 | 2.6 | 6.0 | 11 |
| m,p-Xylene | 1.4 | 8.4 | 6.0 | 36 |
| o-Xylene | 1.4 | 4.7 | 6.0 | 20 |
| Styrene | 1.4 | Not Detected | 5.9 | Not Detected |
| Bromoform | 1.4 | Not Detected | 14 | Not Detected |
| Cumene | 1.4 | ~~0.68 J~~ U | 6.8 | ~~3.4 J~~ U |
| 1,1,2,2-Tetrachloroethane | 1.4 | Not Detected | 9.5 | Not Detected |
| Propylbenzene | 1.4 | 2.2 | 6.8 | 11 |
| 4-Ethyltoluene | 1.4 | 8.7 | 6.8 | 43 |
| 1,3,5-Trimethylbenzene | 1.4 | 2.9 | 6.8 | 14 |
| 1,2,4-Trimethylbenzene | 1.4 | 9.6 | 6.8 | 47 |
| 1,3-Dichlorobenzene | 1.4 | Not Detected | 8.3 | Not Detected |
| 1,4-Dichlorobenzene | 1.4 | Not Detected | 8.3 | Not Detected |
| alpha-Chlorotoluene | 1.4 | Not Detected | 7.1 | Not Detected |
| 1,2-Dichlorobenzene | 1.4 | Not Detected | 8.3 | Not Detected |
| 1,2,4-Trichlorobenzene | 5.5 | Not Detected | 41 | Not Detected |
| Hexachlorobutadiene | 5.5 | Not Detected | 59 | Not Detected |
| Butane | 5.5 | 10 | 13 | 25 |
| Isopentane | 5.5 | 9.4 | 16 | 28 |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| Toluene-d8 | 99 | 70-130 |
| 1,2-Dichloroethane-d4 | 98 | 70-130 |
| 4-Bromofluorobenzene | 97 | 70-130 |

eurofins | Air Toxics

**Client Sample ID: VMP-54-10-020613**

**Lab ID#: 1302156A-26A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p021517** | **Date of Collection:** | **2/6/13 11:52:00 AM** |
| **Dil. Factor:** | **2.82** | **Date of Analysis:** | **2/15/13 06:42 PM** |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 1.4 | 0.58 J | 7.0 | 2.8 J |
| Freon 114 | 1.4 | Not Detected | 9.8 | Not Detected |
| Chloromethane | 14 | Not Detected | 29 | Not Detected |
| Vinyl Chloride | 1.4 | Not Detected | 3.6 | Not Detected |
| 1,3-Butadiene | 1.4 | Not Detected | 3.1 | Not Detected |
| Bromomethane | 14 | Not Detected | 55 | Not Detected |
| Chloroethane | 5.6 | Not Detected | 15 | Not Detected |
| Freon 11 | 1.4 | ~~0.20 J~~ U | 7.9 | ~~1.1 J~~ U |
| Ethanol | 5.6 | 1.2 J | 11 | 2.2 J |
| Freon 113 | 1.4 | Not Detected | 11 | Not Detected |
| 1,1-Dichloroethene | 1.4 | Not Detected | 5.6 | Not Detected |
| Acetone | 14 | 4.0 J | 33 | 9.4 J |
| 2-Propanol | 5.6 | 1.7 J | 14 | 4.2 J |
| Carbon Disulfide | 5.6 | ~~0.68 J~~ U | 18 | ~~2.1 J~~ U |
| 3-Chloropropene | 5.6 | Not Detected | 18 | Not Detected |
| Methylene Chloride | 14 | ~~0.24 J~~ U | 49 | ~~0.82 J~~ U |
| Methyl tert-butyl ether | 1.4 | Not Detected | 5.1 | Not Detected |
| trans-1,2-Dichloroethene | 1.4 | Not Detected | 5.6 | Not Detected |
| Hexane | 1.4 | 0.50 J | 5.0 | 1.7 J |
| 1,1-Dichloroethane | 1.4 | Not Detected | 5.7 | Not Detected |
| 2-Butanone (Methyl Ethyl Ketone) | 5.6 | Not Detected | 17 | Not Detected |
| cis-1,2-Dichloroethene | 1.4 | Not Detected | 5.6 | Not Detected |
| Tetrahydrofuran | 1.4 | Not Detected | 4.2 | Not Detected |
| Chloroform | 1.4 | Not Detected | 6.9 | Not Detected |
| 1,1,1-Trichloroethane | 1.4 | Not Detected | 7.7 | Not Detected |
| Cyclohexane | 1.4 | Not Detected | 4.8 | Not Detected |
| Carbon Tetrachloride | 1.4 | Not Detected | 8.9 | Not Detected |
| 2,2,4-Trimethylpentane | 1.4 | 0.90 J | 6.6 | 4.2 J |
| Benzene | 1.4 | Not Detected | 4.5 | Not Detected |
| 1,2-Dichloroethane | 1.4 | Not Detected | 5.7 | Not Detected |
| Heptane | 1.4 | 0.32 J | 5.8 | 1.3 J |
| Trichloroethene | 1.4 | Not Detected | 7.6 | Not Detected |
| 1,2-Dichloropropane | 1.4 | Not Detected | 6.5 | Not Detected |
| 1,4-Dioxane | 5.6 | Not Detected | 20 | Not Detected |
| Bromodichloromethane | 1.4 | Not Detected | 9.4 | Not Detected |
| cis-1,3-Dichloropropene | 1.4 | Not Detected | 6.4 | Not Detected |
| 4-Methyl-2-pentanone | 1.4 | Not Detected | 5.8 | Not Detected |
| Toluene | 1.4 | 0.97 J | 5.3 | 3.6 J |
| trans-1,3-Dichloropropene | 1.4 | Not Detected | 6.4 | Not Detected |
| 1,1,2-Trichloroethane | 1.4 | Not Detected | 7.7 | Not Detected |
| Tetrachloroethene | 1.4 | ~~0.48 J~~ U | 9.6 | ~~3.2 J~~ U |
| 2-Hexanone | 5.6 | Not Detected | 23 | Not Detected |

eurofins | Air Toxics

**Client Sample ID: VMP-54-10-020613**

**Lab ID#: 1302156A-26A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | p021517 | **Date of Collection:** | 2/6/13 11:52:00 AM |
| **Dil. Factor:** | 2.82 | **Date of Analysis:** | 2/15/13 06:42 PM |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Dibromochloromethane | 1.4 | Not Detected | 12 | Not Detected |
| 1,2-Dibromoethane (EDB) | 1.4 | Not Detected | 11 | Not Detected |
| Chlorobenzene | 1.4 | Not Detected | 6.5 | Not Detected |
| Ethyl Benzene | 1.4 | 0.78 J | 6.1 | 3.4 J |
| m,p-Xylene | 1.4 | 2.1 | 6.1 | 9.1 |
| o-Xylene | 1.4 | 0.95 J | 6.1 | 4.1 J |
| Styrene | 1.4 | Not Detected | 6.0 | Not Detected |
| Bromoform | 1.4 | Not Detected | 14 | Not Detected |
| Cumene | 1.4 | Not Detected | 6.9 | Not Detected |
| 1,1,2,2-Tetrachloroethane | 1.4 | Not Detected | 9.7 | Not Detected |
| Propylbenzene | 1.4 | ~~0.38 J~~ U | 6.9 | ~~1.9 J~~ U |
| 4-Ethyltoluene | 1.4 | 1.3 J | 6.9 | 6.4 J |
| 1,3,5-Trimethylbenzene | 1.4 | ~~0.40 J~~ U | 6.9 | ~~2.0 J~~ U |
| 1,2,4-Trimethylbenzene | 1.4 | ~~1.0 J~~ U | 6.9 | ~~5.2 J~~ U |
| 1,3-Dichlorobenzene | 1.4 | Not Detected | 8.5 | Not Detected |
| 1,4-Dichlorobenzene | 1.4 | Not Detected | 8.5 | Not Detected |
| alpha-Chlorotoluene | 1.4 | Not Detected | 7.3 | Not Detected |
| 1,2-Dichlorobenzene | 1.4 | Not Detected | 8.5 | Not Detected |
| 1,2,4-Trichlorobenzene | 5.6 | Not Detected | 42 | Not Detected |
| Hexachlorobutadiene | 5.6 | Not Detected | 60 | Not Detected |
| Butane | 5.6 | 2.1 J | 13 | 5.1 J |
| Isopentane | 5.6 | 1.3 J | 17 | 3.9 J |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| Toluene-d8 | 97 | 70-130 |
| 1,2-Dichloroethane-d4 | 94 | 70-130 |
| 4-Bromofluorobenzene | 94 | 70-130 |

eurofins | Air Toxics

**Client Sample ID: Lab Blank**

**Lab ID#: 1302156A-27A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p021405a** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 2/14/13 11:42 AM** | |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 0.50 | Not Detected | 2.5 | Not Detected |
| Freon 114 | 0.50 | Not Detected | 3.5 | Not Detected |
| Chloromethane | 5.0 | Not Detected | 10 | Not Detected |
| Vinyl Chloride | 0.50 | Not Detected | 1.3 | Not Detected |
| 1,3-Butadiene | 0.50 | Not Detected | 1.1 | Not Detected |
| Bromomethane | 5.0 | 0.30 J | 19 | 1.2 J |
| Chloroethane | 2.0 | Not Detected | 5.3 | Not Detected |
| Freon 11 | 0.50 | 0.074 J | 2.8 | 0.42 J |
| Ethanol | 2.0 | Not Detected | 3.8 | Not Detected |
| Freon 113 | 0.50 | Not Detected | 3.8 | Not Detected |
| 1,1-Dichloroethene | 0.50 | Not Detected | 2.0 | Not Detected |
| Acetone | 5.0 | Not Detected | 12 | Not Detected |
| 2-Propanol | 2.0 | Not Detected | 4.9 | Not Detected |
| Carbon Disulfide | 2.0 | 0.49 J | 6.2 | 1.5 J |
| 3-Chloropropene | 2.0 | Not Detected | 6.3 | Not Detected |
| Methylene Chloride | 5.0 | 0.19 J | 17 | 0.66 J |
| Methyl tert-butyl ether | 0.50 | Not Detected | 1.8 | Not Detected |
| trans-1,2-Dichloroethene | 0.50 | Not Detected | 2.0 | Not Detected |
| Hexane | 0.50 | Not Detected | 1.8 | Not Detected |
| 1,1-Dichloroethane | 0.50 | Not Detected | 2.0 | Not Detected |
| 2-Butanone (Methyl Ethyl Ketone) | 2.0 | Not Detected | 5.9 | Not Detected |
| cis-1,2-Dichloroethene | 0.50 | Not Detected | 2.0 | Not Detected |
| Tetrahydrofuran | 0.50 | Not Detected | 1.5 | Not Detected |
| Chloroform | 0.50 | Not Detected | 2.4 | Not Detected |
| 1,1,1-Trichloroethane | 0.50 | Not Detected | 2.7 | Not Detected |
| Cyclohexane | 0.50 | Not Detected | 1.7 | Not Detected |
| Carbon Tetrachloride | 0.50 | Not Detected | 3.1 | Not Detected |
| 2,2,4-Trimethylpentane | 0.50 | 0.053 J | 2.3 | 0.25 J |
| Benzene | 0.50 | Not Detected | 1.6 | Not Detected |
| 1,2-Dichloroethane | 0.50 | Not Detected | 2.0 | Not Detected |
| Heptane | 0.50 | Not Detected | 2.0 | Not Detected |
| Trichloroethene | 0.50 | Not Detected | 2.7 | Not Detected |
| 1,2-Dichloropropane | 0.50 | Not Detected | 2.3 | Not Detected |
| 1,4-Dioxane | 2.0 | Not Detected | 7.2 | Not Detected |
| Bromodichloromethane | 0.50 | Not Detected | 3.4 | Not Detected |
| cis-1,3-Dichloropropene | 0.50 | Not Detected | 2.3 | Not Detected |
| 4-Methyl-2-pentanone | 0.50 | Not Detected | 2.0 | Not Detected |
| Toluene | 0.50 | 0.072 J | 1.9 | 0.27 J |
| trans-1,3-Dichloropropene | 0.50 | 0.16 J | 2.3 | 0.74 J |
| 1,1,2-Trichloroethane | 0.50 | Not Detected | 2.7 | Not Detected |
| Tetrachloroethene | 0.50 | 0.13 J | 3.4 | 0.89 J |
| 2-Hexanone | 2.0 | Not Detected | 8.2 | Not Detected |

eurofins | Air Toxics

**Client Sample ID: Lab Blank**

**Lab ID#: 1302156A-27A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p021405a** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 2/14/13 11:42 AM** | |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Dibromochloromethane | 0.50 | Not Detected | 4.2 | Not Detected |
| 1,2-Dibromoethane (EDB) | 0.50 | Not Detected | 3.8 | Not Detected |
| Chlorobenzene | 0.50 | 0.11 J | 2.3 | 0.50 J |
| Ethyl Benzene | 0.50 | Not Detected | 2.2 | Not Detected |
| m,p-Xylene | 0.50 | Not Detected | 2.2 | Not Detected |
| o-Xylene | 0.50 | 0.099 J | 2.2 | 0.43 J |
| Styrene | 0.50 | 0.098 J | 2.1 | 0.42 J |
| Bromoform | 0.50 | Not Detected | 5.2 | Not Detected |
| Cumene | 0.50 | 0.16 J | 2.4 | 0.79 J |
| 1,1,2,2-Tetrachloroethane | 0.50 | 0.15 J | 3.4 | 1.0 J |
| Propylbenzene | 0.50 | 0.18 J | 2.4 | 0.87 J |
| 4-Ethyltoluene | 0.50 | 0.15 J | 2.4 | 0.74 J |
| 1,3,5-Trimethylbenzene | 0.50 | 0.27 J | 2.4 | 1.3 J |
| 1,2,4-Trimethylbenzene | 0.50 | 0.21 J | 2.4 | 1.0 J |
| 1,3-Dichlorobenzene | 0.50 | 0.36 J | 3.0 | 2.2 J |
| 1,4-Dichlorobenzene | 0.50 | 0.34 J | 3.0 | 2.0 J |
| alpha-Chlorotoluene | 0.50 | 0.20 J | 2.6 | 1.0 J |
| 1,2-Dichlorobenzene | 0.50 | 0.32 J | 3.0 | 1.9 J |
| 1,2,4-Trichlorobenzene | 2.0 | 1.4 J | 15 | 10 J |
| Hexachlorobutadiene | 2.0 | 0.79 J | 21 | 8.4 J |
| Butane | 2.0 | Not Detected | 4.8 | Not Detected |
| Isopentane | 2.0 | Not Detected | 5.9 | Not Detected |

J = Estimated value.

**Container Type: NA - Not Applicable**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| Toluene-d8 | 96 | 70-130 |
| 1,2-Dichloroethane-d4 | 83 | 70-130 |
| 4-Bromofluorobenzene | 97 | 70-130 |

eurofins | Air Toxics

**Client Sample ID: Lab Blank**

**Lab ID#: 1302156A-27B**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p021505a** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 2/15/13 11:52 AM** | |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 0.50 | Not Detected | 2.5 | Not Detected |
| Freon 114 | 0.50 | Not Detected | 3.5 | Not Detected |
| Chloromethane | 5.0 | Not Detected | 10 | Not Detected |
| Vinyl Chloride | 0.50 | Not Detected | 1.3 | Not Detected |
| 1,3-Butadiene | 0.50 | Not Detected | 1.1 | Not Detected |
| Bromomethane | 5.0 | 0.39 J | 19 | 1.5 J |
| Chloroethane | 2.0 | Not Detected | 5.3 | Not Detected |
| Freon 11 | 0.50 | 0.062 J | 2.8 | 0.35 J |
| Ethanol | 2.0 | Not Detected | 3.8 | Not Detected |
| Freon 113 | 0.50 | Not Detected | 3.8 | Not Detected |
| 1,1-Dichloroethene | 0.50 | Not Detected | 2.0 | Not Detected |
| Acetone | 5.0 | 0.33 J | 12 | 0.78 J |
| 2-Propanol | 2.0 | Not Detected | 4.9 | Not Detected |
| Carbon Disulfide | 2.0 | 0.55 J | 6.2 | 1.7 J |
| 3-Chloropropene | 2.0 | Not Detected | 6.3 | Not Detected |
| Methylene Chloride | 5.0 | 0.20 J | 17 | 0.69 J |
| Methyl tert-butyl ether | 0.50 | Not Detected | 1.8 | Not Detected |
| trans-1,2-Dichloroethene | 0.50 | 0.12 J | 2.0 | 0.48 J |
| Hexane | 0.50 | Not Detected | 1.8 | Not Detected |
| 1,1-Dichloroethane | 0.50 | Not Detected | 2.0 | Not Detected |
| 2-Butanone (Methyl Ethyl Ketone) | 2.0 | Not Detected | 5.9 | Not Detected |
| cis-1,2-Dichloroethene | 0.50 | Not Detected | 2.0 | Not Detected |
| Tetrahydrofuran | 0.50 | 0.12 J | 1.5 | 0.35 J |
| Chloroform | 0.50 | Not Detected | 2.4 | Not Detected |
| 1,1,1-Trichloroethane | 0.50 | Not Detected | 2.7 | Not Detected |
| Cyclohexane | 0.50 | Not Detected | 1.7 | Not Detected |
| Carbon Tetrachloride | 0.50 | Not Detected | 3.1 | Not Detected |
| 2,2,4-Trimethylpentane | 0.50 | 0.074 J | 2.3 | 0.34 J |
| Benzene | 0.50 | Not Detected | 1.6 | Not Detected |
| 1,2-Dichloroethane | 0.50 | Not Detected | 2.0 | Not Detected |
| Heptane | 0.50 | Not Detected | 2.0 | Not Detected |
| Trichloroethene | 0.50 | Not Detected | 2.7 | Not Detected |
| 1,2-Dichloropropane | 0.50 | Not Detected | 2.3 | Not Detected |
| 1,4-Dioxane | 2.0 | Not Detected | 7.2 | Not Detected |
| Bromodichloromethane | 0.50 | Not Detected | 3.4 | Not Detected |
| cis-1,3-Dichloropropene | 0.50 | 0.12 J | 2.3 | 0.56 J |
| 4-Methyl-2-pentanone | 0.50 | 0.11 J | 2.0 | 0.47 J |
| Toluene | 0.50 | 0.11 J | 1.9 | 0.41 J |
| trans-1,3-Dichloropropene | 0.50 | 0.21 J | 2.3 | 0.96 J |
| 1,1,2-Trichloroethane | 0.50 | Not Detected | 2.7 | Not Detected |
| Tetrachloroethene | 0.50 | 0.13 J | 3.4 | 0.90 J |
| 2-Hexanone | 2.0 | Not Detected | 8.2 | Not Detected |

eurofins | Air Toxics

**Client Sample ID: Lab Blank**

**Lab ID#: 1302156A-27B**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p021505a** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 2/15/13 11:52 AM** | |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Dibromochloromethane | 0.50 | Not Detected | 4.2 | Not Detected |
| 1,2-Dibromoethane (EDB) | 0.50 | 0.13 J | 3.8 | 1.0 J |
| Chlorobenzene | 0.50 | 0.16 J | 2.3 | 0.74 J |
| Ethyl Benzene | 0.50 | 0.11 J | 2.2 | 0.47 J |
| m,p-Xylene | 0.50 | Not Detected | 2.2 | Not Detected |
| o-Xylene | 0.50 | 0.13 J | 2.2 | 0.58 J |
| Styrene | 0.50 | 0.13 J | 2.1 | 0.57 J |
| Bromoform | 0.50 | Not Detected | 5.2 | Not Detected |
| Cumene | 0.50 | 0.17 J | 2.4 | 0.82 J |
| 1,1,2,2-Tetrachloroethane | 0.50 | 0.22 J | 3.4 | 1.5 J |
| Propylbenzene | 0.50 | 0.19 J | 2.4 | 0.92 J |
| 4-Ethyltoluene | 0.50 | 0.16 J | 2.4 | 0.78 J |
| 1,3,5-Trimethylbenzene | 0.50 | 0.27 J | 2.4 | 1.3 J |
| 1,2,4-Trimethylbenzene | 0.50 | 0.24 J | 2.4 | 1.2 J |
| 1,3-Dichlorobenzene | 0.50 | 0.47 J | 3.0 | 2.8 J |
| 1,4-Dichlorobenzene | 0.50 | 0.44 J | 3.0 | 2.6 J |
| alpha-Chlorotoluene | 0.50 | 0.29 J | 2.6 | 1.5 J |
| 1,2-Dichlorobenzene | 0.50 | 0.47 J | 3.0 | 2.8 J |
| 1,2,4-Trichlorobenzene | 2.0 | 1.7 J | 15 | 12 J |
| Hexachlorobutadiene | 2.0 | 1.1 J | 21 | 12 J |
| Butane | 2.0 | Not Detected | 4.8 | Not Detected |
| Isopentane | 2.0 | Not Detected | 5.9 | Not Detected |

J = Estimated value.

**Container Type: NA - Not Applicable**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| Toluene-d8 | 97 | 70-130 |
| 1,2-Dichloroethane-d4 | 89 | 70-130 |
| 4-Bromofluorobenzene | 97 | 70-130 |

eurofins | Air Toxics

**Client Sample ID: CCV**

**Lab ID#: 1302156A-28A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p021402** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 2/14/13 10:07 AM** | |

| Compound | %Recovery |
|---|---|
| Freon 12 | 90 |
| Freon 114 | 97 |
| Chloromethane | 88 |
| Vinyl Chloride | 99 |
| 1,3-Butadiene | 96 |
| Bromomethane | 100 |
| Chloroethane | 97 |
| Freon 11 | 87 |
| Ethanol | 93 |
| Freon 113 | 97 |
| 1,1-Dichloroethene | 102 |
| Acetone | 101 |
| 2-Propanol | 98 |
| Carbon Disulfide | 98 |
| 3-Chloropropene | 105 |
| Methylene Chloride | 93 |
| Methyl tert-butyl ether | 112 |
| trans-1,2-Dichloroethene | 105 |
| Hexane | 106 |
| 1,1-Dichloroethane | 94 |
| 2-Butanone (Methyl Ethyl Ketone) | 102 |
| cis-1,2-Dichloroethene | 108 |
| Tetrahydrofuran | 107 |
| Chloroform | 92 |
| 1,1,1-Trichloroethane | 93 |
| Cyclohexane | 116 |
| Carbon Tetrachloride | 90 |
| 2,2,4-Trimethylpentane | 110 |
| Benzene | 100 |
| 1,2-Dichloroethane | 83 |
| Heptane | 110 |
| Trichloroethene | 80 |
| 1,2-Dichloropropane | 97 |
| 1,4-Dioxane | 110 |
| Bromodichloromethane | 88 |
| cis-1,3-Dichloropropene | 102 |
| 4-Methyl-2-pentanone | 113 |
| Toluene | 98 |
| trans-1,3-Dichloropropene | 100 |
| 1,1,2-Trichloroethane | 100 |
| Tetrachloroethene | 97 |
| 2-Hexanone | 105 |

eurofins | Air Toxics

**Client Sample ID: CCV**

**Lab ID#: 1302156A-28A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p021402** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 2/14/13 10:07 AM** | |

| Compound | %Recovery |
|---|---|
| Dibromochloromethane | 98 |
| 1,2-Dibromoethane (EDB) | 98 |
| Chlorobenzene | 94 |
| Ethyl Benzene | 105 |
| m,p-Xylene | 110 |
| o-Xylene | 110 |
| Styrene | 114 |
| Bromoform | 99 |
| Cumene | 109 |
| 1,1,2,2-Tetrachloroethane | 108 |
| Propylbenzene | 103 |
| 4-Ethyltoluene | 110 |
| 1,3,5-Trimethylbenzene | 111 |
| 1,2,4-Trimethylbenzene | 111 |
| 1,3-Dichlorobenzene | 100 |
| 1,4-Dichlorobenzene | 99 |
| alpha-Chlorotoluene | 103 |
| 1,2-Dichlorobenzene | 101 |
| 1,2,4-Trichlorobenzene | 101 |
| Hexachlorobutadiene | 95 |
| Butane | 94 |
| Isopentane | 98 |

**Container Type: NA - Not Applicable**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| Toluene-d8 | 99 | 70-130 |
| 1,2-Dichloroethane-d4 | 89 | 70-130 |
| 4-Bromofluorobenzene | 99 | 70-130 |

eurofins | Air Toxics

**Client Sample ID: CCV**

**Lab ID#: 1302156A-28B**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p021502** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 2/15/13 10:16 AM** | |

| Compound | %Recovery |
|---|---|
| Freon 12 | 93 |
| Freon 114 | 98 |
| Chloromethane | 86 |
| Vinyl Chloride | 100 |
| 1,3-Butadiene | 97 |
| Bromomethane | 103 |
| Chloroethane | 99 |
| Freon 11 | 92 |
| Ethanol | 91 |
| Freon 113 | 98 |
| 1,1-Dichloroethene | 102 |
| Acetone | 100 |
| 2-Propanol | 98 |
| Carbon Disulfide | 98 |
| 3-Chloropropene | 98 |
| Methylene Chloride | 95 |
| Methyl tert-butyl ether | 113 |
| trans-1,2-Dichloroethene | 104 |
| Hexane | 104 |
| 1,1-Dichloroethane | 96 |
| 2-Butanone (Methyl Ethyl Ketone) | 103 |
| cis-1,2-Dichloroethene | 107 |
| Tetrahydrofuran | 106 |
| Chloroform | 95 |
| 1,1,1-Trichloroethane | 96 |
| Cyclohexane | 113 |
| Carbon Tetrachloride | 94 |
| 2,2,4-Trimethylpentane | 109 |
| Benzene | 102 |
| 1,2-Dichloroethane | 91 |
| Heptane | 112 |
| Trichloroethene | 82 |
| 1,2-Dichloropropane | 100 |
| 1,4-Dioxane | 110 |
| Bromodichloromethane | 94 |
| cis-1,3-Dichloropropene | 104 |
| 4-Methyl-2-pentanone | 114 |
| Toluene | 101 |
| trans-1,3-Dichloropropene | 105 |
| 1,1,2-Trichloroethane | 102 |
| Tetrachloroethene | 100 |
| 2-Hexanone | 109 |

eurofins | Air Toxics

**Client Sample ID: CCV**

**Lab ID#: 1302156A-28B**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p021502** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 2/15/13 10:16 AM** | |

| Compound | %Recovery |
|---|---|
| Dibromochloromethane | 104 |
| 1,2-Dibromoethane (EDB) | 101 |
| Chlorobenzene | 97 |
| Ethyl Benzene | 109 |
| m,p-Xylene | 111 |
| o-Xylene | 114 |
| Styrene | 118 |
| Bromoform | 104 |
| Cumene | 114 |
| 1,1,2,2-Tetrachloroethane | 111 |
| Propylbenzene | 107 |
| 4-Ethyltoluene | 111 |
| 1,3,5-Trimethylbenzene | 117 |
| 1,2,4-Trimethylbenzene | 115 |
| 1,3-Dichlorobenzene | 104 |
| 1,4-Dichlorobenzene | 103 |
| alpha-Chlorotoluene | 109 |
| 1,2-Dichlorobenzene | 106 |
| 1,2,4-Trichlorobenzene | 105 |
| Hexachlorobutadiene | 102 |
| Butane | 93 |
| Isopentane | 99 |

**Container Type: NA - Not Applicable**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| Toluene-d8 | 102 | 70-130 |
| 1,2-Dichloroethane-d4 | 92 | 70-130 |
| 4-Bromofluorobenzene | 103 | 70-130 |

eurofins | Air Toxics

**Client Sample ID: LCS**

**Lab ID#: 1302156A-29A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p021403** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 2/14/13 10:43 AM** | |

| Compound | %Recovery |
|---|---|
| Freon 12 | 84 |
| Freon 114 | 92 |
| Chloromethane | 91 |
| Vinyl Chloride | 96 |
| 1,3-Butadiene | 90 |
| Bromomethane | 94 |
| Chloroethane | 93 |
| Freon 11 | 82 |
| Ethanol | 71 |
| Freon 113 | 91 |
| 1,1-Dichloroethene | 102 |
| Acetone | 93 |
| 2-Propanol | 92 |
| Carbon Disulfide | 112 |
| 3-Chloropropene | 108 |
| Methylene Chloride | 87 |
| Methyl tert-butyl ether | 104 |
| trans-1,2-Dichloroethene | 110 |
| Hexane | 97 |
| 1,1-Dichloroethane | 89 |
| 2-Butanone (Methyl Ethyl Ketone) | 94 |
| cis-1,2-Dichloroethene | 100 |
| Tetrahydrofuran | 95 |
| Chloroform | 87 |
| 1,1,1-Trichloroethane | 88 |
| Cyclohexane | 108 |
| Carbon Tetrachloride | 84 |
| 2,2,4-Trimethylpentane | 101 |
| Benzene | 97 |
| 1,2-Dichloroethane | 79 |
| Heptane | 104 |
| Trichloroethene | 78 |
| 1,2-Dichloropropane | 94 |
| 1,4-Dioxane | 103 |
| Bromodichloromethane | 85 |
| cis-1,3-Dichloropropene | 99 |
| 4-Methyl-2-pentanone | 105 |
| Toluene | 94 |
| trans-1,3-Dichloropropene | 96 |
| 1,1,2-Trichloroethane | 93 |
| Tetrachloroethene | 91 |
| 2-Hexanone | 98 |

eurofins | Air Toxics

**Client Sample ID: LCS**

**Lab ID#: 1302156A-29A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p021403** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 2/14/13 10:43 AM** | |

| Compound | %Recovery |
|---|---|
| Dibromochloromethane | 92 |
| 1,2-Dibromoethane (EDB) | 94 |
| Chlorobenzene | 91 |
| Ethyl Benzene | 100 |
| m,p-Xylene | 104 |
| o-Xylene | 105 |
| Styrene | 109 |
| Bromoform | 91 |
| Cumene | 105 |
| 1,1,2,2-Tetrachloroethane | 104 |
| Propylbenzene | 99 |
| 4-Ethyltoluene | 98 |
| 1,3,5-Trimethylbenzene | 106 |
| 1,2,4-Trimethylbenzene | 104 |
| 1,3-Dichlorobenzene | 96 |
| 1,4-Dichlorobenzene | 94 |
| alpha-Chlorotoluene | 96 |
| 1,2-Dichlorobenzene | 97 |
| 1,2,4-Trichlorobenzene | 100 |
| Hexachlorobutadiene | 91 |
| Butane | 83 |
| Isopentane | 92 |

**Container Type: NA - Not Applicable**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| Toluene-d8 | 100 | 70-130 |
| 1,2-Dichloroethane-d4 | 84 | 70-130 |
| 4-Bromofluorobenzene | 98 | 70-130 |

eurofins | Air Toxics

**Client Sample ID: LCSD**

**Lab ID#: 1302156A-29AA**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p021404** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 2/14/13 11:03 AM** | |

| Compound | %Recovery |
|---|---|
| Freon 12 | 89 |
| Freon 114 | 96 |
| Chloromethane | 96 |
| Vinyl Chloride | 101 |
| 1,3-Butadiene | 95 |
| Bromomethane | 101 |
| Chloroethane | 99 |
| Freon 11 | 86 |
| Ethanol | 78 |
| Freon 113 | 98 |
| 1,1-Dichloroethene | 108 |
| Acetone | 100 |
| 2-Propanol | 97 |
| Carbon Disulfide | 119 |
| 3-Chloropropene | 121 |
| Methylene Chloride | 91 |
| Methyl tert-butyl ether | 110 |
| trans-1,2-Dichloroethene | 116 |
| Hexane | 104 |
| 1,1-Dichloroethane | 95 |
| 2-Butanone (Methyl Ethyl Ketone) | 104 |
| cis-1,2-Dichloroethene | 110 |
| Tetrahydrofuran | 103 |
| Chloroform | 94 |
| 1,1,1-Trichloroethane | 93 |
| Cyclohexane | 116 |
| Carbon Tetrachloride | 89 |
| 2,2,4-Trimethylpentane | 108 |
| Benzene | 100 |
| 1,2-Dichloroethane | 82 |
| Heptane | 108 |
| Trichloroethene | 81 |
| 1,2-Dichloropropane | 96 |
| 1,4-Dioxane | 105 |
| Bromodichloromethane | 87 |
| cis-1,3-Dichloropropene | 102 |
| 4-Methyl-2-pentanone | 109 |
| Toluene | 98 |
| trans-1,3-Dichloropropene | 99 |
| 1,1,2-Trichloroethane | 96 |
| Tetrachloroethene | 96 |
| 2-Hexanone | 102 |

eurofins | Air Toxics

**Client Sample ID: LCSD**

**Lab ID#: 1302156A-29AA**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p021404** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 2/14/13 11:03 AM** | |

| Compound | %Recovery |
|---|---|
| Dibromochloromethane | 96 |
| 1,2-Dibromoethane (EDB) | 98 |
| Chlorobenzene | 95 |
| Ethyl Benzene | 104 |
| m,p-Xylene | 110 |
| o-Xylene | 111 |
| Styrene | 113 |
| Bromoform | 95 |
| Cumene | 110 |
| 1,1,2,2-Tetrachloroethane | 109 |
| Propylbenzene | 104 |
| 4-Ethyltoluene | 103 |
| 1,3,5-Trimethylbenzene | 112 |
| 1,2,4-Trimethylbenzene | 109 |
| 1,3-Dichlorobenzene | 101 |
| 1,4-Dichlorobenzene | 100 |
| alpha-Chlorotoluene | 102 |
| 1,2-Dichlorobenzene | 103 |
| 1,2,4-Trichlorobenzene | 107 |
| Hexachlorobutadiene | 97 |
| Butane | 88 |
| Isopentane | 96 |

**Container Type: NA - Not Applicable**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| Toluene-d8 | 100 | 70-130 |
| 1,2-Dichloroethane-d4 | 87 | 70-130 |
| 4-Bromofluorobenzene | 100 | 70-130 |

eurofins | Air Toxics

**Client Sample ID: LCS**

**Lab ID#: 1302156A-29B**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p021503** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 2/15/13 10:48 AM** | |

| Compound | %Recovery |
|---|---|
| Freon 12 | 96 |
| Freon 114 | 101 |
| Chloromethane | 100 |
| Vinyl Chloride | 106 |
| 1,3-Butadiene | 103 |
| Bromomethane | 106 |
| Chloroethane | 103 |
| Freon 11 | 94 |
| Ethanol | 76 |
| Freon 113 | 103 |
| 1,1-Dichloroethene | 111 |
| Acetone | 106 |
| 2-Propanol | 103 |
| Carbon Disulfide | 124 |
| 3-Chloropropene | 125 |
| Methylene Chloride | 98 |
| Methyl tert-butyl ether | 113 |
| trans-1,2-Dichloroethene | 123 |
| Hexane | 108 |
| 1,1-Dichloroethane | 100 |
| 2-Butanone (Methyl Ethyl Ketone) | 105 |
| cis-1,2-Dichloroethene | 111 |
| Tetrahydrofuran | 105 |
| Chloroform | 99 |
| 1,1,1-Trichloroethane | 101 |
| Cyclohexane | 118 |
| Carbon Tetrachloride | 97 |
| 2,2,4-Trimethylpentane | 112 |
| Benzene | 102 |
| 1,2-Dichloroethane | 88 |
| Heptane | 110 |
| Trichloroethene | 83 |
| 1,2-Dichloropropane | 99 |
| 1,4-Dioxane | 109 |
| Bromodichloromethane | 92 |
| cis-1,3-Dichloropropene | 103 |
| 4-Methyl-2-pentanone | 113 |
| Toluene | 98 |
| trans-1,3-Dichloropropene | 102 |
| 1,1,2-Trichloroethane | 99 |
| Tetrachloroethene | 97 |
| 2-Hexanone | 105 |

eurofins | Air Toxics

**Client Sample ID: LCS**

**Lab ID#: 1302156A-29B**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p021503** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 2/15/13 10:48 AM** | |

| Compound | %Recovery |
|---|---|
| Dibromochloromethane | 98 |
| 1,2-Dibromoethane (EDB) | 98 |
| Chlorobenzene | 94 |
| Ethyl Benzene | 105 |
| m,p-Xylene | 109 |
| o-Xylene | 111 |
| Styrene | 114 |
| Bromoform | 98 |
| Cumene | 112 |
| 1,1,2,2-Tetrachloroethane | 110 |
| Propylbenzene | 106 |
| 4-Ethyltoluene | 104 |
| 1,3,5-Trimethylbenzene | 112 |
| 1,2,4-Trimethylbenzene | 110 |
| 1,3-Dichlorobenzene | 102 |
| 1,4-Dichlorobenzene | 100 |
| alpha-Chlorotoluene | 103 |
| 1,2-Dichlorobenzene | 104 |
| 1,2,4-Trichlorobenzene | 106 |
| Hexachlorobutadiene | 99 |
| Butane | 97 |
| Isopentane | 102 |

**Container Type: NA - Not Applicable**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| Toluene-d8 | 100 | 70-130 |
| 1,2-Dichloroethane-d4 | 94 | 70-130 |
| 4-Bromofluorobenzene | 101 | 70-130 |

eurofins | Air Toxics

**Client Sample ID: LCSD**

**Lab ID#: 1302156A-29BB**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p021504** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 2/15/13 11:18 AM** | |

| Compound | %Recovery |
|---|---|
| Freon 12 | 93 |
| Freon 114 | 97 |
| Chloromethane | 98 |
| Vinyl Chloride | 102 |
| 1,3-Butadiene | 99 |
| Bromomethane | 103 |
| Chloroethane | 101 |
| Freon 11 | 91 |
| Ethanol | 78 |
| Freon 113 | 99 |
| 1,1-Dichloroethene | 108 |
| Acetone | 101 |
| 2-Propanol | 100 |
| Carbon Disulfide | 120 |
| 3-Chloropropene | 122 |
| Methylene Chloride | 94 |
| Methyl tert-butyl ether | 109 |
| trans-1,2-Dichloroethene | 119 |
| Hexane | 107 |
| 1,1-Dichloroethane | 97 |
| 2-Butanone (Methyl Ethyl Ketone) | 104 |
| cis-1,2-Dichloroethene | 107 |
| Tetrahydrofuran | 103 |
| Chloroform | 95 |
| 1,1,1-Trichloroethane | 97 |
| Cyclohexane | 116 |
| Carbon Tetrachloride | 93 |
| 2,2,4-Trimethylpentane | 109 |
| Benzene | 102 |
| 1,2-Dichloroethane | 87 |
| Heptane | 110 |
| Trichloroethene | 83 |
| 1,2-Dichloropropane | 99 |
| 1,4-Dioxane | 108 |
| Bromodichloromethane | 92 |
| cis-1,3-Dichloropropene | 102 |
| 4-Methyl-2-pentanone | 112 |
| Toluene | 97 |
| trans-1,3-Dichloropropene | 103 |
| 1,1,2-Trichloroethane | 100 |
| Tetrachloroethene | 97 |
| 2-Hexanone | 106 |

eurofins | Air Toxics

**Client Sample ID: LCSD**

**Lab ID#: 1302156A-29BB**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p021504** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 2/15/13 11:18 AM** | |

| Compound | %Recovery |
|---|---|
| Dibromochloromethane | 100 |
| 1,2-Dibromoethane (EDB) | 100 |
| Chlorobenzene | 97 |
| Ethyl Benzene | 107 |
| m,p-Xylene | 112 |
| o-Xylene | 114 |
| Styrene | 116 |
| Bromoform | 100 |
| Cumene | 113 |
| 1,1,2,2-Tetrachloroethane | 112 |
| Propylbenzene | 107 |
| 4-Ethyltoluene | 106 |
| 1,3,5-Trimethylbenzene | 115 |
| 1,2,4-Trimethylbenzene | 112 |
| 1,3-Dichlorobenzene | 104 |
| 1,4-Dichlorobenzene | 102 |
| alpha-Chlorotoluene | 106 |
| 1,2-Dichlorobenzene | 106 |
| 1,2,4-Trichlorobenzene | 111 |
| Hexachlorobutadiene | 102 |
| Butane | 93 |
| Isopentane | 101 |

**Container Type: NA - Not Applicable**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| Toluene-d8 | 99 | 70-130 |
| 1,2-Dichloroethane-d4 | 91 | 70-130 |
| 4-Bromofluorobenzene | 101 | 70-130 |

1302156

# Shell Oil Products Chain Of Custody Record

URS

Air Toxics LTD.
Project Name: Roxana Soil Vapor
Project # 21562850.04001
Lab Vendor #

Please Check Appropriate Box:
☑ ENV. SERVICES ☐ MOTIVA RETAIL ☐ SHELL RETAIL
☐ MOTIVA SC/GA ☐ CONSULTANT ☐ LUBES
☐ SHELL PIPELINE ☐ OTHER

Print Bill To Contact Name: Robert Mooshegian
INCIDENT # (ENV SERVICES): 9 7 2 1 6 6 4 0 ☐ CHECK IF NO INCIDENT # APPLIES
DATE 02/07/13
PO #:
SAP #: 3 4 0 0 6 1
PAGE: 1 of 3

SAMPLING COMPANY: URS CORPORATION
LOG CODE:
SITE ADDRESS: Street and City: 900 SOUTH CENTRAL AVE – ROXANA
State: IL
GLOBAL ID NO.:
ADDRESS: 1001 HIGHLANDS PLAZA DRIVE WEST - SUITE 300; ST. LOUIS, MO 63110
REPORT DELIVERABLE TO (Name, Company, Office Location): Elizabeth Kunkel, URS, St. Louis
PHONE NO: 314-743-4179
E-MAIL: Elizabeth_Kunkel@URSCorp.com
CONSULTANT PROJECT NAME/#: Roxana Soil Vapor
Invoice Address: Air Toxics, LTD 180 Blue Ravine Road, Suite B, Folsom, CA 95630-4719
TELEPHONE:
FAX: 314-429-0462
Bill To Contact E-MAIL: Robert.Mooshegian@urs.com
COPY TO: C. Williams, L. Rahnow, S. Jansen, D. Mattingly, B. Lehan, C. Kretzer

TURNAROUND TIME (CALENDAR DAYS):
☑ STANDARD (14 DAY) ☐ 5 DAYS ☐ 3 DAYS ☐ 2 DAYS ☐ 24 HOURS ☐ RESULTS NEEDED ON WEEKEND

☐ LA - RWQCB REPORT FORMAT ☑ UST AGENCY:

DELIVERABLES: ☐ LEVEL 1 ☐ LEVEL 2 ☐ LEVEL 3 ☑ LEVEL 4 ☐ OTHER (SPECIFY)

☑ SHELL CONTRACT RATE APPLIES
☐ STATE REIMBURSEMENT RATE APPLIES
☐ EDD NOT NEEDED
☑ RECEIPT VERIFICATION REQUESTED

REQUESTED ANALYSIS

Turn Around Time: ☑ Normal ☐ Rush ☐ Specify

Lab Use Only
Pressurized by:
Date:
Pressurization Gas: $N_2$ He

ADDITIONAL NOTES:
- 14 day hold time
- Report results between MDL and RL
- Level IV ECVP

| LAB USE ONLY | Field Sample Identification | SAMPLING DATE | SAMPLING TIME | Canister Number | Canister Pressure/Vacuum Initial | Final | Receipt | Final (psi) | Modified TO-15 + Butane & Isopentane | ASTM D-1946 + Helium |
|---|---|---|---|---|---|---|---|---|---|---|
| 01A | VMP-2-8.5-020513 | 02/05/13 | 1335-1405 | 1353 | -30 | -10.5 | | | X | X |
| 02A | VMP-6-10-020513 | 02/05/13 | 1429-1509 | 36487 | -30 | -9 | | | X | X |
| 03A | VMP-6-31.5-020513 | 02/05/13 | 1351-1428 | 36485 | -30 | -8 | | | X | X |
| 04A | VMP-6-39-020513 | 02/05/13 | 1304-1334 | 35671 | -30 | -8 | | | X | X |
| 05A | VMP-15-5-020513 | 02/05/13 | 1455-1525 | 3010 | -29 | -10.5 | | | X | X |
| 06A | VMP-21-10-020513 | 02/05/13 | 1500-1530 | 37791 | -29.5 | -8.5 | | | X | X |
| 07A | VMP-21-10-020513-DUP | 02/05/13 | 1500-1530 | 35639 | -30 | -7 | | | X | X |
| 08A | VMP-21-25-020513 | 02/05/13 | 1410-1440 | 34130 | -29.5 | -7.5 | | | X | X |
| 09A | VMP-21-25-020513-DUP | 02/05/13 | 1410-1440 | 2107 | -29.5 | -8.5 | | | X | X |
| 10A | VMP-21-33-020513 | 02/05/13 | 1324-1354 | 34680 | -29.5 | -7.5 | | | X | X |

| | | Date | Time |
|---|---|---|---|
| Relinquished by: (Signature) | Received by: (Signature) FEDEX | 2/7/13 | 1330 |
| Relinquished by: (Signature) | Received by: (Signature) | 2/8/13 | 0830 |
| Relinquished by: (Signature) | Received by: (Signature) | Date | Time |

05.2006 Revision

Custody Seal Intact?
Y N None Temp ___

1302156

# Shell Oil Products Chain Of Custody Record

URS

Air Toxics LTD.
Project Name: Roxana Soil Vapor
Project # 21562850.04001
Lab Vendor #

Please Check Appropriate Box:
☑ ENV. SERVICES ☐ MOTIVA RETAIL ☐ SHELL RETAIL
☐ MOTIVA SD&CN ☐ CONSULTANT ☐ LUBES
☐ SHELL PIPELINE ☐ OTHER

Print Bill To Contact Name: Robert Mooshegian
INCIDENT # (ENV SERVICES): 9 7 2 1 6 6 4 0 ☐ CHECK IF NO INCIDENT # APPLIES
PO #:
SAP #: 3 4 0 0 6 1
DATE: 02/07/13
PAGE: 2 of 3

SAMPLING COMPANY: URS CORPORATION
LOG CODE:
ADDRESS: 1001 HIGHLANDS PLAZA DRIVE WEST - SUITE 300; ST. LOUIS, MO 63110
SITE ADDRESS: Street and City: 900 SOUTH CENTRAL AVE – ROXANA
State: IL
GLOBAL ID NO.:
Laboratory Address: Air Toxics, LTD 180 Blue Ravine Road, Suite B, Folsom, CA 95630-4719
REPORT DELIVERABLE TO (Name, Company, Office Location): Elizabeth Kunkel, URS, St. Louis
PHONE NO.: 314-743-4179
E-MAIL: Elizabeth.Kunkel@URSCorp.com
CONSULTANT PROJECT NAME#: Roxana Soil Vapor
TELEPHONE:
FAX: 314-429-0462
Bill To Contact E-MAIL: Robert.Mooshegian@urs.com
C. Williams, L. Rathnow, S. Jansen, D. Mattingly, B. Lehan, C. Kretzer

TURNAROUND TIME (CALENDAR DAYS):
☑ STANDARD (14 DAY) ☐ 5 DAYS ☐ 3 DAYS ☐ 2 DAYS ☐ 24 HOURS ☐ RESULTS NEEDED ON WEEKEND

REQUESTED ANALYSIS

☐ LA - RWQCB REPORT FORMAT ☑ UST AGENCY:

DELIVERABLES: ☐ LEVEL 1 ☐ LEVEL 2 ☐ LEVEL 3 ☑ LEVEL 4 ☐ OTHER (SPECIFY)

☑ SHELL CONTRACT RATE APPLIES
☐ STATE REIMBURSEMENT RATE APPLIES
☐ EDD NOT NEEDED
☑ RECEIPT VERIFICATION REQUESTED

Turn Around Time: ☑ Normal ☐ Rush ☐ Specify

Lab Use Only
Pressurized by:
Date:
Pressurization Gas: $N_2$ He

| Lab Use Only | Field Sample Identification | SAMPLING DATE | SAMPLING TIME | Canister Number | Canister Pressure/Vacuum Initial | Final | Receipt | Final (psi) | Modified TO-15 + Butane & Isopentane | ASTM D-1946 + Helium |
|---|---|---|---|---|---|---|---|---|---|---|
| LA | VMP-29-10-020613 | 02/06/13 | 0928-0958 | 12392 | -30 | -9.5 | | | X | X |
| 2A | VMP-29-20-020613 | 02/06/13 | 1022-1056 | 36529 | -30 | -9.5 | | | X | X |
| 3A | VMP-29-30-020613 | 02/06/13 | 1120-1150 | 37391 | -30 | -10.5 | | | X | X |
| 4A | VMP-30-10-020613 | 02/06/13 | 0917-0947 | 34064 | -30 | -8 | | | X | X |
| 5A | VMP-30-20-020613 | 02/06/13 | 1017-1047 | 36515 | -30 | -9 | | | X | X |
| 6A | VMP-30-30-020613 | 02/06/13 | 1118-1146 | 3390 | -30 | -8.5 | | | X | X |
| 7A | VMP-32-5-020513 | 02/05/13 | 0853-0923 | 34850 | -29.5 | -7.5 | | | X | X |
| 8A | VMP-32-10-020513 | 02/05/13 | 0939-1009 | 37695 | -29.5 | -7 | | | X | X |
| 9A | VMP-32-20-020513 | 02/05/13 | 1028-1058 | 35601 | -29.5 | -9 | | | X | X |
| | | | | | | | | | X | X |

ADDITIONAL NOTES:
- 14 day hold time
- Report results between MDL and RL
- Level IV ECVP

Relinquished by: (Signature)

Received by: (Signature)
FEDEX

Date: 2/7/13 Time: 1730

Relinquished by: (Signature)

Received by: (Signature)

Date: 2/8/13 Time: 0930

Relinquished by: (Signature)

Received by: (Signature)

Date: Time:

Custody Seal Intact? Y N None Temp 4.2

05/2008 Revision

1302156

# Shell Oil Products Chain Of Custody Record

**Air Toxics LTD.**
**Project Name: Roxana Soil Vapor**
**Project # 21562850.04001**
Lab Vendor #

Please Check Appropriate Box:
☑ ENV. SERVICES ☐ MOTIVA RETAIL ☐ SHELL RETAIL
☐ MOTIVA SD&LM ☐ CONSULTANT ☐ LUBES
☐ SHELL PIPELINE ☐ OTHER

Print Bill To Contact Name: Robert Mooshegian
PO #:
INCIDENT # (ENV SERVICES): 9 7 2 1 6 6 4 0 ☐ CHECK IF NO INCIDENT # APPLIES
SAP #: 3 4 0 0 6 1
DATE: 02/07/13
PAGE: 3 of 3

SAMPLING COMPANY: URS CORPORATION
LOG CODE:
ADDRESS: 1001 HIGHLANDS PLAZA DRIVE WEST - SUITE 300; ST. LOUIS, MO 63110
SITE ADDRESS: Street and City: 900 SOUTH CENTRAL AVE – ROXANA
State: IL
GLOBAL ID NO.:
Laboratory Address: Air Toxics, LTD 180 Blue Ravine Road, Suite B, Folsom, CA 95630-4719
EDF DELIVERABLE TO (Name, Company, Office Location): Elizabeth Kunkel, URS, St. Louis
PHONE NO.: 314-743-4178
E-MAIL: Elizabeth_Kunkel@URSCorp.com
CONSULTANT PROJECT NAME#: Roxana Soil Vapor
TELEPHONE:
FAX: 314-429-0462
Bill To Contact E-MAIL: Robert.Mooshegian@urs.com
C. Williams, L. Rathnow, S. Jansen, D. Mattingly, B. Lehan, C. Kretzer

TURNAROUND TIME (CALENDAR DAYS):
☑ STANDARD (14 DAY) ☐ 5 DAYS ☐ 3 DAYS ☐ 2 DAYS ☐ 24 HOURS ☐ RESULTS NEEDED ON WEEKEND

☐ IA - RWQCB REPORT FORMAT ☑ UST AGENCY:

DELIVERABLES: ☐ LEVEL 1 ☐ LEVEL 2 ☐ LEVEL 3 ☑ LEVEL 4 ☐ OTHER (SPECIFY)

☑ SHELL CONTRACT RATE APPLIES
☐ STATE REIMBURSEMENT RATE APPLIES
☐ EDD NOT NEEDED
☑ RECEIPT VERIFICATION REQUESTED

REQUESTED ANALYSIS

| Lab Use Only | Field Sample Identification | SAMPLING DATE | SAMPLING TIME | Canister Number | Canister Pressure/Vacuum Initial | Final | Receipt | Final (psi) | Modified TO-15 + Butane & Isopentane | ASTM D-1946 + Helium |
|---|---|---|---|---|---|---|---|---|---|---|
| 20A | VMP-53-5-020513 | 02/05/13 | 0847-0917 | 22982 | -30 | -8.5 | | | X | X |
| 21A | VMP-53-10-020513 | 02/05/13 | 0934-1004 | 35688 | -30 | -8 | | | X | X |
| 22A | VMP-53-10-020513-DUP | 02/05/13 | 0934-1004 | 36441 | -30 | -7 | | | X | X |
| 23A | VMP-53-20-020513 | 02/05/13 | 1017-1047 | 37314 | -30 | -8.5 | | | X | X |
| 24A | VMP-53-30-020513 | 02/05/13 | 1050-1120 | 34133 | -30 | -8.5 | | | X | X |
| 25A | VMP-54-5-020613 | 02/06/13 | 0947-1018 | 31772 | -30 | -10 | | | X | X |
| 26A | VMP-54-10-020613 | 02/06/13 | 1122-1152 | 36431 | -30 | -9 | | | X | X |
| | | | | | | | | | X | X |
| | | | | | | | | | X | X |
| | | | | | | | | | X | X |

Turn Around Time: ☑ Normal ☐ Rush ☐ Specify

Lab Use Only
Pressurized by:
Date:
Pressurization Gas: $N_2$ He

ADDITIONAL NOTES:
- 14 day hold time
- Report results between MDL and RL
- Level IV ECVP

Relinquished by: (Signature)
Relinquished by: (Signature)
Relinquished by: (Signature)

Received by: (Signature) FEDEX
Received by: (Signature)
Received by: (Signature)

Date: 2/7/13 Time: 1730
Date: 2/8/13 Time: 0930
Date: Time:

05/2008 Revision

Custody Seal Intact?
Y N None Temp: N/A

eurofins | Air Toxics

2/22/2013
Ms. Elizabeth Kunkel
URS Corporation
1001 Highlands Plaza Dr. West
Suite 300
St. Louis MO 63110

Project Name: Roxana Soil Vapor
Project #: 21562850.04001
Workorder #: 1302156B

Dear Ms. Elizabeth Kunkel

The following report includes the data for the above referenced project for sample(s) received on 2/8/2013 at Air Toxics Ltd.

The data and associated QC analyzed by Modified ASTM D-1946 are compliant with the project requirements or laboratory criteria with the exception of the deviations noted in the attached case narrative.

Thank you for choosing Air Toxics Ltd. for your air analysis needs. Air Toxics Ltd. is committed to providing accurate data of the highest quality. Please feel free to contact the Project Manager: Kelly Buettner at 916-985-1000 if you have any questions regarding the data in this report.

Regards,

Kelly Buettner

Project Manager

REVIEWED
ON
3/26/13

eurofins | Air Toxics

# WORK ORDER #: 1302156B

Work Order Summary

| | | | |
|---|---|---|---|
| **CLIENT:** | Ms. Elizabeth Kunkel<br>URS Corporation<br>1001 Highlands Plaza Dr. West<br>Suite 300<br>St. Louis, MO 63110 | **BILL TO:** | Accounts Payable Austin<br>URS Corporation<br>P.O. BOX 203970<br>Austin, TX 78720-1088 |
| **PHONE:** | 314-743-4179 | **P.O. #** | 21562735.00013 |
| **FAX:** | | **PROJECT #** | 21562850.04001 Roxana Soil Vapor |
| **DATE RECEIVED:** | 02/08/2013 | **CONTACT:** | Kelly Buettner |
| **DATE COMPLETED:** | 02/22/2013 | | |

| FRACTION # | NAME | TEST | RECEIPT VAC./PRES. | FINAL PRESSURE |
|---|---|---|---|---|
| 01A | VMP-2-8.5-020513 | Modified ASTM D-1946 | 9.5 "Hg | 15 psi |
| 02A | VMP-6-10-020513 | Modified ASTM D-1946 | 8.0 "Hg | 15 psi |
| 03A | VMP-6-31.5-020513 | Modified ASTM D-1946 | 6.5 "Hg | 15 psi |
| 04A | VMP-6-39-020513 | Modified ASTM D-1946 | 7.0 "Hg | 15 psi |
| 05A | VMP-15-5-020513 | Modified ASTM D-1946 | 9.0 "Hg | 15 psi |
| 06A | VMP-21-10-020513 | Modified ASTM D-1946 | 7.5 "Hg | 15 psi |
| 07A | VMP-21-10-020513-DUP | Modified ASTM D-1946 | 6.0 "Hg | 15 psi |
| 08A | VMP-21-25-020513 | Modified ASTM D-1946 | 6.5 "Hg | 15 psi |
| 09A | VMP-21-25-020513-DUP | Modified ASTM D-1946 | 7.5 "Hg | 15 psi |
| 10A | VMP-21-33-020513 | Modified ASTM D-1946 | 7.0 "Hg | 15 psi |
| 11A | VMP-29-10-020613 | Modified ASTM D-1946 | 8.5 "Hg | 15 psi |
| 12A | VMP-29-20-020613 | Modified ASTM D-1946 | 8.0 "Hg | 15 psi |
| 13A | VMP-29-30-020613 | Modified ASTM D-1946 | 9.0 "Hg | 15 psi |
| 14A | VMP-30-10-020613 | Modified ASTM D-1946 | 7.0 "Hg | 15 psi |
| 15A | VMP-30-20-020613 | Modified ASTM D-1946 | 7.0 "Hg | 15 psi |
| 16A | VMP-30-30-020613 | Modified ASTM D-1946 | 7.0 "Hg | 15 psi |
| 17A | VMP-32-5-020513 | Modified ASTM D-1946 | 6.0 "Hg | 15 psi |
| 18A | VMP-32-10-020513 | Modified ASTM D-1946 | 6.0 "Hg | 15 psi |
| 19A | VMP-32-20-020513 | Modified ASTM D-1946 | 8.5 "Hg | 15 psi |
| 20A | VMP-53-5-020513 | Modified ASTM D-1946 | 6.5 "Hg | 15 psi |
| 21A | VMP-53-10-020513 | Modified ASTM D-1946 | 7.0 "Hg | 15 psi |
| 22A | VMP-53-10-020513-DUP | Modified ASTM D-1946 | 5.5 "Hg | 15 psi |
| 23A | VMP-53-20-020513 | Modified ASTM D-1946 | 7.0 "Hg | 15 psi |

Continued on next page

eurofins | Air Toxics

# WORK ORDER #: 1302156B

Work Order Summary

| | | | |
|---|---|---|---|
| **CLIENT:** | Ms. Elizabeth Kunkel<br>URS Corporation<br>1001 Highlands Plaza Dr. West<br>Suite 300<br>St. Louis, MO 63110 | **BILL TO:** | Accounts Payable Austin<br>URS Corporation<br>P.O. BOX 203970<br>Austin, TX 78720-1088 |
| **PHONE:** | 314-743-4179 | **P.O. #** | 21562735.00013 |
| **FAX:** | | **PROJECT #** | 21562850.04001 Roxana Soil Vapor |
| **DATE RECEIVED:** | 02/08/2013 | **CONTACT:** | Kelly Buettner |
| **DATE COMPLETED:** | 02/22/2013 | | |

| FRACTION # | NAME | TEST | RECEIPT VAC./PRES. | FINAL PRESSURE |
|---|---|---|---|---|
| 24A | VMP-53-30-020513 | Modified ASTM D-1946 | 7.5 "Hg | 15 psi |
| 25A | VMP-54-5-020613 | Modified ASTM D-1946 | 8.0 "Hg | 15 psi |
| 26A | VMP-54-10-020613 | Modified ASTM D-1946 | 8.5 "Hg | 15 psi |
| 27A | Lab Blank | Modified ASTM D-1946 | NA | NA |
| 27B | Lab Blank | Modified ASTM D-1946 | NA | NA |
| 27C | Lab Blank | Modified ASTM D-1946 | NA | NA |
| 27D | Lab Blank | Modified ASTM D-1946 | NA | NA |
| 28A | LCS | Modified ASTM D-1946 | NA | NA |
| 28AA | LCSD | Modified ASTM D-1946 | NA | NA |
| 28B | LCS | Modified ASTM D-1946 | NA | NA |
| 28BB | LCSD | Modified ASTM D-1946 | NA | NA |

CERTIFIED BY: Heidi Hayes DATE: 02/22/13

Technical Director

Certification numbers: AZ Licensure AZ0775, CA NELAP - 12282CA, NY NELAP - 11291,
TX NELAP - T104704434-12-4, UT NELAP CA009332012-3, WA NELAP - C935
Name of Accrediting Agency: NELAP/ORELAP (Oregon Environmental Laboratory Accreditation Program)
Accreditation number: CA300005, Effective date: 10/18/2012, Expiration date: 10/17/2013.
Eurofins Air Toxics Ltd. certifies that the test results contained in this report meet all requirements of the NELAC standards

This report shall not be reproduced, except in full, without the written approval of Eurofins Air Toxics, Inc.

180 BLUE RAVINE ROAD, SUITE B FOLSOM, CA - 9563
(916) 985-1000 . (800) 985-5955 . FAX (916) 985-1020

**LABORATORY NARRATIVE**
**Modified ASTM D-1946**
**URS Corporation**
**Workorder# 1302156B**

Twenty-six 1 Liter Summa Canister samples were received on February 08, 2013. The laboratory performed analysis via Modified ASTM Method D-1946 for Methane and fixed gases in air using GC/FID or GC/TCD. The method involves direct injection of 1.0 mL of sample.

On the analytical column employed for this analysis, Oxygen coelutes with Argon. The corresponding peak is quantitated as Oxygen.

Since Nitrogen is used to pressurize samples, the reported Nitrogen values are calculated by adding all the sample components and subtracting from 100%.

Method modifications taken to run these samples are summarized in the table below. Specific project requirements may over-ride the ATL modifications.

| *Requirement* | *ASTM D-1946* | *ATL Modifications* |
|---|---|---|
| Calibration | A single point calibration is performed using a reference standard closely matching the composition of the unknown. | A 3-point calibration curve is performed. Quantitation is based on a daily calibration standard which may or may not resemble the composition of the associated samples. |
| Reference Standard | The composition of any reference standard must be known to within 0.01 mol % for any component. | The standards used by ATL are blended to a >/= 95% accuracy. |
| Sample Injection Volume | Components whose concentrations are in excess of 5 % should not be analyzed by using sample volumes greater than 0.5 mL. | The sample container is connected directly to a fixed volume sample loop of 1.0 mL on the GC. Linear range is defined by the calibration curve. Bags are loaded by vacuum. |
| Normalization | Normalize the mole percent values by multiplying each value by 100 and dividing by the sum of the original values. The sum of the original values should not differ from 100% by more than 1.0%. | Results are not normalized. The sum of the reported values can differ from 100% by as much as 15%, either due to analytical variability or an unusual sample matrix. |
| Precision | Precision requirements established at each concentration level. | Duplicates should agree within 25% RPD for detections > 5 X's the RL. |

**Receiving Notes**

There were no receiving discrepancies.

**Analytical Notes**

As per project specific client request the laboratory has reported estimated values for target compound hits that are below the Reporting Limit but greater than the Method Detection Limit. Concentrations that are below the level at which the canister was certified may be false positives.

The reporting limit for Carbon Monoxide was raised from 0.010% to 0.050%.

**Definition of Data Qualifying Flags**

Seven qualifiers may have been used on the data analysis sheets and indicate as follows:
B - Compound present in laboratory blank greater than reporting limit.
J - Estimated value.
E - Exceeds instrument calibration range.
S - Saturated peak.
Q - Exceeds quality control limits.
U - Compound analyzed for but not detected above the detection limit.
M - Reported value may be biased due to apparent matrix interferences.
File extensions may have been used on the data analysis sheets and indicates as follows:
a-File was requantified
b-File was quantified by a second column and detector
r1-File was requantified for the purpose of reissue

eurofins | Air Toxics

# Summary of Detected Compounds
# NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1946

**Client Sample ID: VMP-2-8.5-020513**

**Lab ID#: 1302156B-01A**

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.30 | 19 |
| Nitrogen | 0.30 | 79 |
| Carbon Dioxide | 0.030 | 1.8 |

**Client Sample ID: VMP-6-10-020513**

**Lab ID#: 1302156B-02A**

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.28 | 20 |
| Nitrogen | 0.28 | 78 |
| Methane | 0.00028 | 0.000023 J |
| Carbon Dioxide | 0.028 | 0.34 |
| Helium | 0.14 | 1.7 |

**Client Sample ID: VMP-6-31.5-020513**

**Lab ID#: 1302156B-03A**

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.26 | 10 |
| Nitrogen | 0.26 | 82 |
| Methane | 0.00026 | 0.0028 |
| Carbon Dioxide | 0.026 | 7.5 |

**Client Sample ID: VMP-6-39-020513**

**Lab ID#: 1302156B-04A**

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.26 | 5.4 |
| Nitrogen | 0.26 | 82 |
| Methane | 0.00026 | 0.00036 |
| Carbon Dioxide | 0.026 | 12 |

eurofins | Air Toxics

# Summary of Detected Compounds
# NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1946

**Client Sample ID: VMP-15-5-020513**

**Lab ID#: 1302156B-05A**

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.29 | 10 |
| Nitrogen | 0.29 | 83 |
| Carbon Dioxide | 0.029 | 6.7 |

**Client Sample ID: VMP-21-10-020513**

**Lab ID#: 1302156B-06A**

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.27 | 18 |
| Nitrogen | 0.27 | 79 |
| Methane | 0.00027 | 0.000019 J |
| Carbon Dioxide | 0.027 | 3.4 |

**Client Sample ID: VMP-21-10-020513-DUP**

**Lab ID#: 1302156B-07A**

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.25 | 18 |
| Nitrogen | 0.25 | 78 |
| Methane | 0.00025 | 0.000023 J |
| Carbon Dioxide | 0.025 | 3.5 |

**Client Sample ID: VMP-21-25-020513**

**Lab ID#: 1302156B-08A**

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.26 | 11 |
| Nitrogen | 0.26 | 80 |
| Methane | 0.00026 | 0.000043 J |
| Carbon Dioxide | 0.026 | 8.7 |
| Helium | 0.13 | 0.020 J |

eurofins | Air Toxics

# Summary of Detected Compounds
# NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1946

**Client Sample ID: VMP-21-25-020513-DUP**

**Lab ID#: 1302156B-09A**

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.27 | 11 |
| Nitrogen | 0.27 | 80 |
| Methane | 0.00027 | 0.000036 J |
| Carbon Dioxide | 0.027 | 8.8 |
| Helium | 0.13 | 0.058 |

**Client Sample ID: VMP-21-33-020513**

**Lab ID#: 1302156B-10A**

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.26 | 9.1 |
| Nitrogen | 0.26 | 81 |
| Methane | 0.00026 | 0.000073 J |
| Carbon Dioxide | 0.026 | 10 |

**Client Sample ID: VMP-29-10-020613**

**Lab ID#: 1302156B-11A**

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.28 | 20 |
| Nitrogen | 0.28 | 79 |
| Methane | 0.00028 | 0.000090 J |
| Carbon Dioxide | 0.028 | 1.2 |
| Helium | 0.14 | 0.15 |

**Client Sample ID: VMP-29-20-020613**

**Lab ID#: 1302156B-12A**

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.28 | 21 |
| Nitrogen | 0.28 | 78 |
| Methane | 0.00028 | 0.00021 J |

eurofins | Air Toxics

# Summary of Detected Compounds
# NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1946

**Client Sample ID: VMP-29-20-020613**

**Lab ID#: 1302156B-12A**

| | | |
|---|---|---|
| Carbon Dioxide | 0.028 | 0.32 |
| Helium | 0.14 | 0.16 |

**Client Sample ID: VMP-29-30-020613**

**Lab ID#: 1302156B-13A**

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.29 | 20 |
| Nitrogen | 0.29 | 78 |
| Methane | 0.00029 | 0.00014 J |
| Carbon Dioxide | 0.029 | 1.8 |
| Helium | 0.14 | 0.043 |

**Client Sample ID: VMP-30-10-020613**

**Lab ID#: 1302156B-14A**

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.26 | 22 |
| Nitrogen | 0.26 | 78 |
| Methane | 0.00026 | 0.000058 J |
| Carbon Dioxide | 0.026 | 0.094 |

**Client Sample ID: VMP-30-20-020613**

**Lab ID#: 1302156B-15A**

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.26 | 21 |
| Nitrogen | 0.26 | 78 |
| Methane | 0.00026 | 0.00013 J |
| Carbon Dioxide | 0.026 | 0.52 |

**Client Sample ID: VMP-30-30-020613**

**Lab ID#: 1302156B-16A**

eurofins | Air Toxics

# Summary of Detected Compounds
# NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1946

**Client Sample ID: VMP-30-30-020613**

**Lab ID#: 1302156B-16A**

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.26 | 20 |
| Nitrogen | 0.26 | 78 |
| Methane | 0.00026 | 0.000080 J |
| Carbon Dioxide | 0.026 | 1.8 |

**Client Sample ID: VMP-32-5-020513**

**Lab ID#: 1302156B-17A**

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.25 | 21 |
| Nitrogen | 0.25 | 79 |
| Methane | 0.00025 | 0.00013 J |
| Carbon Dioxide | 0.025 | 0.25 |

**Client Sample ID: VMP-32-10-020513**

**Lab ID#: 1302156B-18A**

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.25 | 19 |
| Nitrogen | 0.25 | 79 |
| Methane | 0.00025 | 0.000027 J |
| Carbon Dioxide | 0.025 | 2.2 |

**Client Sample ID: VMP-32-20-020513**

**Lab ID#: 1302156B-19A**

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.28 | 18 |
| Nitrogen | 0.28 | 79 |
| Methane | 0.00028 | 0.000026 J |
| Carbon Dioxide | 0.028 | 3.4 |

eurofins | Air Toxics

# Summary of Detected Compounds
# NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1946

**Client Sample ID: VMP-53-5-020513**

**Lab ID#: 1302156B-20A**

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.26 | 21 |
| Nitrogen | 0.26 | 78 |
| Methane | 0.00026 | 0.000073 J |
| Carbon Dioxide | 0.026 | 0.49 |

**Client Sample ID: VMP-53-10-020513**

**Lab ID#: 1302156B-21A**

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.26 | 21 |
| Nitrogen | 0.26 | 78 |
| Methane | 0.00026 | 0.000018 J |
| Carbon Dioxide | 0.026 | 0.59 |
| Helium | 0.13 | 0.027 J |

**Client Sample ID: VMP-53-10-020513-DUP**

**Lab ID#: 1302156B-22A**

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.25 | 21 |
| Nitrogen | 0.25 | 78 |
| Methane | 0.00025 | 0.000020 J |
| Carbon Dioxide | 0.025 | 0.58 |
| Helium | 0.12 | 0.019 J |

**Client Sample ID: VMP-53-20-020513**

**Lab ID#: 1302156B-23A**

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.26 | 20 |
| Nitrogen | 0.26 | 78 |
| Methane | 0.00026 | 0.000029 J |

eurofins | Air Toxics

# Summary of Detected Compounds
# NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1946

**Client Sample ID: VMP-53-20-020513**

**Lab ID#: 1302156B-23A**

| | | |
|---|---|---|
| Carbon Dioxide | 0.026 | 1.8 |

**Client Sample ID: VMP-53-30-020513**

**Lab ID#: 1302156B-24A**

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.27 | 19 |
| Nitrogen | 0.27 | 78 |
| Methane | 0.00027 | 0.000043 J |
| Carbon Dioxide | 0.027 | 3.5 |
| Helium | 0.13 | 0.026 J |

**Client Sample ID: VMP-54-5-020613**

**Lab ID#: 1302156B-25A**

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.28 | 19 |
| Nitrogen | 0.28 | 79 |
| Methane | 0.00028 | 0.00011 J |
| Carbon Dioxide | 0.028 | 1.7 |

**Client Sample ID: VMP-54-10-020613**

**Lab ID#: 1302156B-26A**

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.28 | 18 |
| Nitrogen | 0.28 | 79 |
| Carbon Dioxide | 0.028 | 3.2 |

eurofins | Air Toxics

**Client Sample ID: VMP-2-8.5-020513**

**Lab ID#: 1302156B-01A**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1946**

| | | | |
|---|---|---|---|
| **File Name:** | **9021609** | **Date of Collection:** | **2/5/13 2:05:00 PM** |
| **Dil. Factor:** | **2.96** | **Date of Analysis:** | **2/16/13 08:25 AM** |

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.30 | 19 |
| Nitrogen | 0.30 | 79 |
| Carbon Monoxide | 0.15 | Not Detected |
| Methane | 0.00030 | Not Detected |
| Carbon Dioxide | 0.030 | 1.8 |
| Ethane | 0.0030 | Not Detected |
| Ethene | 0.0030 | Not Detected |
| Helium | 0.15 | Not Detected |

**Container Type: 1 Liter Summa Canister**

eurofins | Air Toxics

**Client Sample ID: VMP-6-10-020513**

**Lab ID#: 1302156B-02A**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1946**

| | | | |
|---|---|---|---|
| **File Name:** | **9021610** | **Date of Collection: 2/5/13 3:09:00 PM** | |
| **Dil. Factor:** | **2.76** | **Date of Analysis: 2/16/13 08:47 AM** | |

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.28 | 20 |
| Nitrogen | 0.28 | 78 |
| Carbon Monoxide | 0.14 | Not Detected |
| Methane | 0.00028 | 0.000023 J |
| Carbon Dioxide | 0.028 | 0.34 |
| Ethane | 0.0028 | Not Detected |
| Ethene | 0.0028 | Not Detected |
| Helium | 0.14 | 1.7 |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

eurofins | Air Toxics

**Client Sample ID: VMP-6-31.5-020513**

**Lab ID#: 1302156B-03A**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1946**

| | | | |
|---|---|---|---|
| **File Name:** | **9021611** | **Date of Collection:** | **2/5/13 2:26:00 PM** |
| **Dil. Factor:** | **2.58** | **Date of Analysis:** | **2/16/13 09:11 AM** |

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.26 | 10 |
| Nitrogen | 0.26 | 82 |
| Carbon Monoxide | 0.13 | Not Detected |
| Methane | 0.00026 | 0.0028 |
| Carbon Dioxide | 0.026 | 7.5 |
| Ethane | 0.0026 | Not Detected |
| Ethene | 0.0026 | Not Detected |
| Helium | 0.13 | Not Detected |

**Container Type: 1 Liter Summa Canister**

eurofins | Air Toxics

**Client Sample ID: VMP-6-39-020513**

**Lab ID#: 1302156B-04A**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1946**

| | | | |
|---|---|---|---|
| **File Name:** | **9021612** | **Date of Collection:** | **2/5/13 1:34:00 PM** |
| **Dil. Factor:** | **2.64** | **Date of Analysis:** | **2/16/13 09:33 AM** |

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.26 | 5.4 |
| Nitrogen | 0.26 | 82 |
| Carbon Monoxide | 0.13 | Not Detected |
| Methane | 0.00026 | 0.00036 |
| Carbon Dioxide | 0.026 | 12 |
| Ethane | 0.0026 | Not Detected |
| Ethene | 0.0026 | Not Detected |
| Helium | 0.13 | Not Detected |

**Container Type: 1 Liter Summa Canister**

eurofins | Air Toxics

**Client Sample ID: VMP-15-5-020513**

**Lab ID#: 1302156B-05A**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1946**

| | | | |
|---|---|---|---|
| **File Name:** | **9021613** | **Date of Collection:** | **2/5/13 3:25:00 PM** |
| **Dil. Factor:** | **2.89** | **Date of Analysis:** | **2/16/13 09:59 AM** |

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.29 | 10 |
| Nitrogen | 0.29 | 83 |
| Carbon Monoxide | 0.14 | Not Detected |
| Methane | 0.00029 | Not Detected |
| Carbon Dioxide | 0.029 | 6.7 |
| Ethane | 0.0029 | Not Detected |
| Ethene | 0.0029 | Not Detected |
| Helium | 0.14 | Not Detected |

**Container Type: 1 Liter Summa Canister**

eurofins | Air Toxics

**Client Sample ID: VMP-21-10-020513**

**Lab ID#: 1302156B-06A**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1946**

| | | | |
|---|---|---|---|
| **File Name:** | **9021614** | **Date of Collection:** | **2/5/13 3:30:00 PM** |
| **Dil. Factor:** | **2.69** | **Date of Analysis:** | **2/16/13 10:28 AM** |

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.27 | 18 |
| Nitrogen | 0.27 | 79 |
| Carbon Monoxide | 0.13 | Not Detected |
| Methane | 0.00027 | 0.000019 J |
| Carbon Dioxide | 0.027 | 3.4 |
| Ethane | 0.0027 | Not Detected |
| Ethene | 0.0027 | Not Detected |
| Helium | 0.13 | Not Detected |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

eurofins | Air Toxics

**Client Sample ID: VMP-21-10-020513-DUP**

**Lab ID#: 1302156B-07A**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1946**

| | | | |
|---|---|---|---|
| **File Name:** | **9021615** | **Date of Collection:** | **2/5/13 3:30:00 PM** |
| **Dil. Factor:** | **2.52** | **Date of Analysis:** | **2/16/13 10:50 AM** |

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.25 | 18 |
| Nitrogen | 0.25 | 78 |
| Carbon Monoxide | 0.13 | Not Detected |
| Methane | 0.00025 | 0.000023 J |
| Carbon Dioxide | 0.025 | 3.5 |
| Ethane | 0.0025 | Not Detected |
| Ethene | 0.0025 | Not Detected |
| Helium | 0.13 | Not Detected |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

eurofins | Air Toxics

**Client Sample ID: VMP-21-25-020513**

**Lab ID#: 1302156B-08A**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1946**

| | | | |
|---|---|---|---|
| **File Name:** | **9021616** | **Date of Collection:** | **2/5/13 2:40:00 PM** |
| **Dil. Factor:** | **2.58** | **Date of Analysis:** | **2/16/13 11:12 AM** |

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.26 | 11 |
| Nitrogen | 0.26 | 80 |
| Carbon Monoxide | 0.13 | Not Detected |
| Methane | 0.00026 | 0.000043 J |
| Carbon Dioxide | 0.026 | 8.7 |
| Ethane | 0.0026 | Not Detected |
| Ethene | 0.0026 | Not Detected |
| Helium | 0.13 | 0.020 J |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

eurofins | Air Toxics

**Client Sample ID: VMP-21-25-020513-DUP**

**Lab ID#: 1302156B-09A**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1946**

| | | | |
|---|---|---|---|
| **File Name:** | **9021617** | **Date of Collection: 2/5/13 2:40:00 PM** | |
| **Dil. Factor:** | **2.69** | **Date of Analysis: 2/16/13 11:34 AM** | |

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.27 | 11 |
| Nitrogen | 0.27 | 80 |
| Carbon Monoxide | 0.13 | Not Detected |
| Methane | 0.00027 | 0.000036 J |
| Carbon Dioxide | 0.027 | 8.8 |
| Ethane | 0.0027 | Not Detected |
| Ethene | 0.0027 | Not Detected |
| Helium | 0.13 | 0.058 |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

eurofins | Air Toxics

**Client Sample ID: VMP-21-33-020513**

**Lab ID#: 1302156B-10A**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1946**

| | | | |
|---|---|---|---|
| **File Name:** | **9021618** | **Date of Collection:** | **2/5/13 1:54:00 PM** |
| **Dil. Factor:** | **2.64** | **Date of Analysis:** | **2/16/13 11:56 AM** |

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.26 | 9.1 |
| Nitrogen | 0.26 | 81 |
| Carbon Monoxide | 0.13 | Not Detected |
| Methane | 0.00026 | 0.000073 J |
| Carbon Dioxide | 0.026 | 10 |
| Ethane | 0.0026 | Not Detected |
| Ethene | 0.0026 | Not Detected |
| Helium | 0.13 | Not Detected |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

eurofins | Air Toxics

**Client Sample ID: VMP-29-10-020613**

**Lab ID#: 1302156B-11A**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1946**

| | | | |
|---|---|---|---|
| **File Name:** | **9021619** | **Date of Collection:** | **2/6/13 9:56:00 AM** |
| **Dil. Factor:** | **2.82** | **Date of Analysis:** | **2/16/13 12:18 PM** |

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.28 | 20 |
| Nitrogen | 0.28 | 79 |
| Carbon Monoxide | 0.14 | Not Detected |
| Methane | 0.00028 | 0.000090 J |
| Carbon Dioxide | 0.028 | 1.2 |
| Ethane | 0.0028 | Not Detected |
| Ethene | 0.0028 | Not Detected |
| Helium | 0.14 | 0.15 |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

eurofins | Air Toxics

**Client Sample ID: VMP-29-20-020613**

**Lab ID#: 1302156B-12A**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1946**

| | | | |
|---|---|---|---|
| **File Name:** | **9021620** | **Date of Collection:** | **2/6/13 10:56:00 AM** |
| **Dil. Factor:** | **2.76** | **Date of Analysis:** | **2/16/13 12:56 PM** |

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.28 | 21 |
| Nitrogen | 0.28 | 78 |
| Carbon Monoxide | 0.14 | Not Detected |
| Methane | 0.00028 | 0.00021 J |
| Carbon Dioxide | 0.028 | 0.32 |
| Ethane | 0.0028 | Not Detected |
| Ethene | 0.0028 | Not Detected |
| Helium | 0.14 | 0.16 |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

eurofins | Air Toxics

**Client Sample ID: VMP-29-30-020613**

**Lab ID#: 1302156B-13A**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1946**

| | | | |
|---|---|---|---|
| **File Name:** | **9021621** | **Date of Collection:** | **2/6/13 11:50:00 AM** |
| **Dil. Factor:** | **2.89** | **Date of Analysis:** | **2/16/13 01:18 PM** |

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.29 | 20 |
| Nitrogen | 0.29 | 78 |
| Carbon Monoxide | 0.14 | Not Detected |
| Methane | 0.00029 | 0.00014 J |
| Carbon Dioxide | 0.029 | 1.8 |
| Ethane | 0.0029 | Not Detected |
| Ethene | 0.0029 | Not Detected |
| Helium | 0.14 | 0.043 |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

eurofins | Air Toxics

**Client Sample ID: VMP-30-10-020613**

**Lab ID#: 1302156B-14A**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1946**

| | | | |
|---|---|---|---|
| **File Name:** | **9021622** | **Date of Collection:** | **2/6/13 9:47:00 AM** |
| **Dil. Factor:** | **2.64** | **Date of Analysis:** | **2/16/13 01:40 PM** |

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.26 | 22 |
| Nitrogen | 0.26 | 78 |
| Carbon Monoxide | 0.13 | Not Detected |
| Methane | 0.00026 | 0.000058 J |
| Carbon Dioxide | 0.026 | 0.094 |
| Ethane | 0.0026 | Not Detected |
| Ethene | 0.0026 | Not Detected |
| Helium | 0.13 | Not Detected |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

eurofins | Air Toxics

**Client Sample ID: VMP-30-20-020613**

**Lab ID#: 1302156B-15A**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1946**

| | | | |
|---|---|---|---|
| **File Name:** | **9021623** | **Date of Collection:** | **2/6/13 10:47:00 AM** |
| **Dil. Factor:** | **2.64** | **Date of Analysis:** | **2/16/13 02:02 PM** |

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.26 | 21 |
| Nitrogen | 0.26 | 78 |
| Carbon Monoxide | 0.13 | Not Detected |
| Methane | 0.00026 | 0.00013 J |
| Carbon Dioxide | 0.026 | 0.52 |
| Ethane | 0.0026 | Not Detected |
| Ethene | 0.0026 | Not Detected |
| Helium | 0.13 | Not Detected |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

eurofins | Air Toxics

**Client Sample ID: VMP-30-30-020613**

**Lab ID#: 1302156B-16A**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1946**

| | | | |
|---|---|---|---|
| **File Name:** | **9021624** | **Date of Collection:** | **2/6/13 11:45:00 AM** |
| **Dil. Factor:** | **2.64** | **Date of Analysis:** | **2/16/13 02:24 PM** |

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.26 | 20 |
| Nitrogen | 0.26 | 78 |
| Carbon Monoxide | 0.13 | Not Detected |
| Methane | 0.00026 | 0.000080 J |
| Carbon Dioxide | 0.026 | 1.8 |
| Ethane | 0.0026 | Not Detected |
| Ethene | 0.0026 | Not Detected |
| Helium | 0.13 | Not Detected |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

eurofins | Air Toxics

**Client Sample ID: VMP-32-5-020513**

**Lab ID#: 1302156B-17A**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1946**

| | | | |
|---|---|---|---|
| **File Name:** | **9021625** | **Date of Collection: 2/5/13 9:23:00 AM** | |
| **Dil. Factor:** | **2.52** | **Date of Analysis: 2/16/13 02:46 PM** | |

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.25 | 21 |
| Nitrogen | 0.25 | 79 |
| Carbon Monoxide | 0.13 | Not Detected |
| Methane | 0.00025 | 0.00013 J |
| Carbon Dioxide | 0.025 | 0.25 |
| Ethane | 0.0025 | Not Detected |
| Ethene | 0.0025 | Not Detected |
| Helium | 0.13 | Not Detected |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

eurofins | Air Toxics

**Client Sample ID: VMP-32-10-020513**

**Lab ID#: 1302156B-18A**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1946**

| | | | |
|---|---|---|---|
| **File Name:** | **9021905** | **Date of Collection:** | **2/5/13 10:09:00 AM** |
| **Dil. Factor:** | **2.52** | **Date of Analysis:** | **2/19/13 10:50 AM** |

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.25 | 19 |
| Nitrogen | 0.25 | 79 |
| Carbon Monoxide | 0.13 | Not Detected |
| Methane | 0.00025 | 0.000027 J |
| Carbon Dioxide | 0.025 | 2.2 |
| Ethane | 0.0025 | Not Detected |
| Ethene | 0.0025 | Not Detected |
| Helium | 0.13 | Not Detected |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

eurofins | Air Toxics

**Client Sample ID: VMP-32-20-020513**

**Lab ID#: 1302156B-19A**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1946**

| | | | |
|---|---|---|---|
| **File Name:** | **9021906** | **Date of Collection:** | **2/5/13 10:58:00 AM** |
| **Dil. Factor:** | **2.82** | **Date of Analysis:** | **2/19/13 11:13 AM** |

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.28 | 18 |
| Nitrogen | 0.28 | 79 |
| Carbon Monoxide | 0.14 | Not Detected |
| Methane | 0.00028 | 0.000026 J |
| Carbon Dioxide | 0.028 | 3.4 |
| Ethane | 0.0028 | Not Detected |
| Ethene | 0.0028 | Not Detected |
| Helium | 0.14 | Not Detected |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

eurofins | Air Toxics

**Client Sample ID: VMP-53-5-020513**

**Lab ID#: 1302156B-20A**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1946**

| | | | |
|---|---|---|---|
| **File Name:** | **9021907** | **Date of Collection: 2/5/13 9:17:00 AM** | |
| **Dil. Factor:** | **2.58** | **Date of Analysis: 2/19/13 11:38 AM** | |

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.26 | 21 |
| Nitrogen | 0.26 | 78 |
| Carbon Monoxide | 0.13 | Not Detected |
| Methane | 0.00026 | 0.000073 J |
| Carbon Dioxide | 0.026 | 0.49 |
| Ethane | 0.0026 | Not Detected |
| Ethene | 0.0026 | Not Detected |
| Helium | 0.13 | Not Detected |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

eurofins | Air Toxics

**Client Sample ID: VMP-53-10-020513**

**Lab ID#: 1302156B-21A**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1946**

| | | | |
|---|---|---|---|
| **File Name:** | **9021908** | **Date of Collection:** | **2/5/13 10:04:00 AM** |
| **Dil. Factor:** | **2.64** | **Date of Analysis:** | **2/19/13 12:03 PM** |

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.26 | 21 |
| Nitrogen | 0.26 | 78 |
| Carbon Monoxide | 0.13 | Not Detected |
| Methane | 0.00026 | 0.000018 J |
| Carbon Dioxide | 0.026 | 0.59 |
| Ethane | 0.0026 | Not Detected |
| Ethene | 0.0026 | Not Detected |
| Helium | 0.13 | 0.027 J |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

eurofins | Air Toxics

**Client Sample ID: VMP-53-10-020513-DUP**

**Lab ID#: 1302156B-22A**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1946**

| | | | |
|---|---|---|---|
| **File Name:** | **9021909** | **Date of Collection:** | **2/5/13 10:04:00 AM** |
| **Dil. Factor:** | **2.47** | **Date of Analysis:** | **2/19/13 12:28 PM** |

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.25 | 21 |
| Nitrogen | 0.25 | 78 |
| Carbon Monoxide | 0.12 | Not Detected |
| Methane | 0.00025 | 0.000020 J |
| Carbon Dioxide | 0.025 | 0.58 |
| Ethane | 0.0025 | Not Detected |
| Ethene | 0.0025 | Not Detected |
| Helium | 0.12 | 0.019 J |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

eurofins | Air Toxics

**Client Sample ID: VMP-53-20-020513**

**Lab ID#: 1302156B-23A**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1946**

| | | | |
|---|---|---|---|
| **File Name:** | **9021910** | **Date of Collection:** | **2/5/13 10:47:00 AM** |
| **Dil. Factor:** | **2.64** | **Date of Analysis:** | **2/19/13 01:16 PM** |

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.26 | 20 |
| Nitrogen | 0.26 | 78 |
| Carbon Monoxide | 0.13 | Not Detected |
| Methane | 0.00026 | 0.000029 J |
| Carbon Dioxide | 0.026 | 1.8 |
| Ethane | 0.0026 | Not Detected |
| Ethene | 0.0026 | Not Detected |
| Helium | 0.13 | Not Detected |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

eurofins | Air Toxics

**Client Sample ID: VMP-53-30-020513**

**Lab ID#: 1302156B-24A**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1946**

| | | | |
|---|---|---|---|
| **File Name:** | **9021911** | **Date of Collection:** | **2/5/13 11:29:00 AM** |
| **Dil. Factor:** | **2.69** | **Date of Analysis:** | **2/19/13 01:41 PM** |

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.27 | 19 |
| Nitrogen | 0.27 | 78 |
| Carbon Monoxide | 0.13 | Not Detected |
| Methane | 0.00027 | 0.000043 J |
| Carbon Dioxide | 0.027 | 3.5 |
| Ethane | 0.0027 | Not Detected |
| Ethene | 0.0027 | Not Detected |
| Helium | 0.13 | 0.026 J |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

eurofins | Air Toxics

**Client Sample ID: VMP-54-5-020613**

**Lab ID#: 1302156B-25A**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1946**

| | | | |
|---|---|---|---|
| **File Name:** | **9021912** | **Date of Collection: 2/6/13 10:18:00 AM** | |
| **Dil. Factor:** | **2.76** | **Date of Analysis: 2/19/13 02:14 PM** | |

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.28 | 19 |
| Nitrogen | 0.28 | 79 |
| Carbon Monoxide | 0.14 | Not Detected |
| Methane | 0.00028 | 0.00011 J |
| Carbon Dioxide | 0.028 | 1.7 |
| Ethane | 0.0028 | Not Detected |
| Ethene | 0.0028 | Not Detected |
| Helium | 0.14 | Not Detected |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

eurofins | Air Toxics

**Client Sample ID: VMP-54-10-020613**

**Lab ID#: 1302156B-26A**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1946**

| | | | |
|---|---|---|---|
| **File Name:** | **9021913** | **Date of Collection:** | **2/6/13 11:52:00 AM** |
| **Dil. Factor:** | **2.82** | **Date of Analysis:** | **2/19/13 02:38 PM** |

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.28 | 18 |
| Nitrogen | 0.28 | 79 |
| Carbon Monoxide | 0.14 | Not Detected |
| Methane | 0.00028 | Not Detected |
| Carbon Dioxide | 0.028 | 3.2 |
| Ethane | 0.0028 | Not Detected |
| Ethene | 0.0028 | Not Detected |
| Helium | 0.14 | Not Detected |

**Container Type: 1 Liter Summa Canister**

eurofins | Air Toxics

**Client Sample ID: Lab Blank**

**Lab ID#: 1302156B-27A**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1946**

| | | | |
|---|---|---|---|
| **File Name:** | **9021607a** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 2/16/13 07:38 AM** | |

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.10 | 0.039 J |
| Nitrogen | 0.10 | 0.051 J |
| Carbon Monoxide | 0.050 | Not Detected |
| Methane | 0.00010 | Not Detected |
| Carbon Dioxide | 0.010 | Not Detected |
| Ethane | 0.0010 | Not Detected |
| Ethene | 0.0010 | Not Detected |

J = Estimated value.

**Container Type: NA - Not Applicable**

eurofins | Air Toxics

**Client Sample ID: Lab Blank**

**Lab ID#: 1302156B-27B**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1946**

| | | | |
|---|---|---|---|
| **File Name:** | **9021604b** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 2/15/13 09:15 PM** | |

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Helium | 0.050 | Not Detected |

**Container Type: NA - Not Applicable**

eurofins | Air Toxics

**Client Sample ID: Lab Blank**

**Lab ID#: 1302156B-27C**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1946**

| | | | |
|---|---|---|---|
| **File Name:** | **9021904a** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 2/19/13 10:22 AM** | |

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.10 | Not Detected |
| Nitrogen | 0.10 | 0.057 J |
| Carbon Monoxide | 0.050 | Not Detected |
| Methane | 0.00010 | Not Detected |
| Carbon Dioxide | 0.010 | Not Detected |
| Ethane | 0.0010 | Not Detected |
| Ethene | 0.0010 | Not Detected |

J = Estimated value.

**Container Type: NA - Not Applicable**

eurofins | Air Toxics

**Client Sample ID: Lab Blank**

**Lab ID#: 1302156B-27D**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1946**

| | | | |
|---|---|---|---|
| **File Name:** | **9021903b** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 2/19/13 09:55 AM** | |

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Helium | 0.050 | Not Detected |

**Container Type: NA - Not Applicable**

eurofins | Air Toxics

**Client Sample ID: LCS**

**Lab ID#: 1302156B-28A**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1946**

| | | | |
|---|---|---|---|
| **File Name:** | **9021602** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 2/15/13 08:28 PM** | |

| Compound | %Recovery |
|---|---|
| Oxygen | 101 |
| Nitrogen | 101 |
| Carbon Monoxide | 94 |
| Methane | 99 |
| Carbon Dioxide | 96 |
| Ethane | 100 |
| Ethene | 97 |
| Helium | 102 |

**Container Type: NA - Not Applicable**

eurofins | Air Toxics

**Client Sample ID: LCSD**

**Lab ID#: 1302156B-28AA**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1946**

| | | | |
|---|---|---|---|
| **File Name:** | **9021630** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 2/16/13 04:43 PM** | |

| Compound | %Recovery |
|---|---|
| Oxygen | 100 |
| Nitrogen | 101 |
| Carbon Monoxide | 96 |
| Methane | 99 |
| Carbon Dioxide | 100 |
| Ethane | 101 |
| Ethene | 98 |
| Helium | 101 |

**Container Type: NA - Not Applicable**

eurofins | Air Toxics

**Client Sample ID: LCS**

**Lab ID#: 1302156B-28B**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1946**

| | | | |
|---|---|---|---|
| **File Name:** | **9021902** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 2/19/13 09:23 AM** | |

| Compound | %Recovery |
|---|---|
| Oxygen | 100 |
| Nitrogen | 101 |
| Carbon Monoxide | 97 |
| Methane | 97 |
| Carbon Dioxide | 100 |
| Ethane | 98 |
| Ethene | 96 |
| Helium | 99 |

**Container Type: NA - Not Applicable**

eurofins | Air Toxics

**Client Sample ID: LCSD**

**Lab ID#: 1302156B-28BB**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1946**

| | | | |
|---|---|---|---|
| **File Name:** | **9021928** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 2/19/13 10:15 PM** | |

| Compound | %Recovery |
|---|---|
| Oxygen | 100 |
| Nitrogen | 100 |
| Carbon Monoxide | 98 |
| Methane | 95 |
| Carbon Dioxide | 99 |
| Ethane | 97 |
| Ethene | 94 |
| Helium | 98 |

**Container Type: NA - Not Applicable**

1302156

# Shell Oil Products Chain Of Custody Record

URS

Air Toxics LTD.
Project Name: Roxana Soil Vapor
Project # 21562850.04001
Lab Vendor #

Please Check Appropriate Box:
☑ ENV. SERVICES ☐ MOTIVA RETAIL ☐ SHELL RETAIL
☐ MOTIVA SC/ON ☐ CONSULTANT ☐ LUBES
☐ SHELL PIPELINE ☐ OTHER

Print Bill To Contact Name: Robert Mooshegian
INCIDENT # (ENV SERVICES): 5 7 2 1 6 6 4 0 ☐ CHECK IF NO INCIDENT # APPLIES
DATE 02/07/13
PO #:
SAP #: 3 4 0 0 6 1
PAGE 1 of 3

SAMPLING COMPANY: URS CORPORATION
LOG CODE:
ADDRESS: 1001 HIGHLANDS PLAZA DRIVE WEST - SUITE 300; ST. LOUIS, MO 63110
LABORATORY ADDRESS: Air Toxics, LTD 180 Blue Ravine Road, Suite B, Folsom, CA 95630-4719
TELEPHONE:
FAX: 314-429-0462
BILL TO CONTACT E-MAIL: Robert.Mooshegian@urs.com

SITE ADDRESS: Street and City: 900 SOUTH CENTRAL AVE – ROXANA
State: IL
GLOBAL ID NO.:
DELIVERABLE TO (Name, Company, Office Location): Elizabeth Kunkel, URS, St. Louis
PHONE NO: 314-743-4179
E-MAIL: Elizabeth_Kunkel@URSCorp.com
CONSULTANT PROJECT NAME #: Roxana Soil Vapor
C. Williams, L. Rathnow, S. Jansen, D. Mattingly, B. Lehan, C. Kretzer

TURNAROUND TIME (CALENDAR DAYS):
☑ STANDARD (14 DAY) ☐ 5 DAYS ☐ 3 DAYS ☐ 2 DAYS ☐ 24 HOURS ☐ RESULTS NEEDED ON WEEKEND

☐ LA - RWQCB REPORT FORMAT ☑ UST AGENCY:

DELIVERABLES: ☐ LEVEL 1 ☐ LEVEL 2 ☐ LEVEL 3 ☑ LEVEL 4 ☐ OTHER (SPECIFY)

☑ SHELL CONTRACT RATE APPLIES
☐ STATE REIMBURSEMENT RATE APPLIES
☐ EDD NOT NEEDED
☑ RECEIPT VERIFICATION REQUESTED

REQUESTED ANALYSIS

| LAB USE ONLY | Field Sample Identification | SAMPLING DATE | SAMPLING TIME | Canister Number | Conister Pressure/Vacuum Initial | Final | Receipt | Final (psi) | Modified TO-15 + Butane & Isopentane | ASTM D-1946 + Helium |
|---|---|---|---|---|---|---|---|---|---|---|
| 01A | VMP-2-8.5-020513 | 02/05/13 | 1335-1405 | 1353 | -30 | -10.5 | | | X | X |
| 02A | VMP-6-10-020513 | 02/05/13 | 1439-1509 | 36487 | -30 | -9 | | | X | X |
| 03A | VMP-6-31.5-020513 | 02/05/13 | 1351-1428 | 36486 | -30 | -8 | | | X | X |
| 04A | VMP-6-39-020513 | 02/05/13 | 1304-1334 | 35671 | -30 | -8 | | | X | X |
| 05A | VMP-15-5-020513 | 02/05/13 | 1455-1525 | 3010 | -29 | -10.5 | | | X | X |
| 06A | VMP-21-10-020513 | 02/05/13 | 1500-1530 | 37791 | -29.5 | -8.5 | | | X | X |
| 07A | VMP-21-10-020513-DUP | 02/05/13 | 1500-1530 | 35639 | -30 | -7 | | | X | X |
| 08A | VMP-21-25-020513 | 02/05/13 | 1410-1440 | 34130 | -29.5 | -7.5 | | | X | X |
| 09A | VMP-21-25-020513-DUP | 02/05/13 | 1410-1440 | 2107 | -29.5 | -8.5 | | | X | X |
| 10A | VMP-21-33-020513 | 02/05/13 | 1324-1354 | 34590 | -29.5 | -7.5 | | | X | X |

Turn Around Time: ☑ Normal ☐ Rush Specify

Lab Use Only
Pressurized by:
Date:
Pressurization Gas: $N_2$ He

ADDITIONAL NOTES:
- 14 day hold time
- Report results between MDL and RL
- Level IV ECVP

| | Relinquished by: (Signature) | Received by: (Signature) | Date | Time |
|---|---|---|---|---|
| 1 | | FEDEX | 2/7/13 | 1330 |
| 2 | | | 2/8/13 | 0930 |
| 3 | | | | |

05/2006 Revision

Custody Seal Intact?
Y N None Temp

1302156

# Shell Oil Products Chain Of Custody Record

URS

**Air Toxics LTD.**
**Project Name: Roxana Soil Vapor**
**Project # 21562850.04001**
Lab Vendor #

Please Check Appropriate Box:
☑ ENV. SERVICES ☐ MOTIVA RETAIL ☐ SHELL RETAIL
☐ MOTIVA SD&CN ☐ CONSULTANT ☐ LUBES
☐ SHELL PIPELINE ☐ OTHER

Print Bill To Contact Name: Robert Mooshegian
PO: #
INCIDENT # (ENV SERVICES): 9 7 2 1 6 6 4 0 ☐ CHECK IF NO INCIDENT # APPLIES
SAF #: 3 4 0 0 6 1
DATE: 02/07/13
PAGE 2 of 3

SAMPLING COMPANY: URS CORPORATION
ADDRESS: 1001 HIGHLANDS PLAZA DRIVE WEST - SUITE 300; ST. LOUIS, MO 63110
LABORATORY ADDRESS: Air Toxics, LTD 180 Blue Ravine Road, Suite B, Folsom, CA 95630-4719
TELEPHONE: FAX: 314-429-0462
Bill To Contact E-MAIL: Robert.Mooshegian@urs.com
LOG CODE:
SITE ADDRESS: Street and City: 900 SOUTH CENTRAL AVE – ROXANA
State: IL
GLOBAL ID NO.:
EDF DELIVERABLE TO (Name, Company, Office Location): Elizabeth Kunkel, URS, St. Louis
PHONE NO: 314-743-4179
E-MAIL: Elizabeth.Kunkel@URSCorp.com
CONSULTANT PROJECT NAME: Roxana Soil Vapor
C. Williams, L. Rathnow, S. Jansen, D. Mattingly, B. Lehan, C. Kretzer

TURNAROUND TIME (CALENDAR DAYS):
☑ STANDARD (14 DAY) ☐ 5 DAYS ☐ 3 DAYS ☐ 2 DAYS ☐ 24 HOURS ☐ RESULTS NEEDED ON WEEKEND

☐ LA - RWQCB REPORT FORMAT ☑ UST AGENCY:

DELIVERABLES: ☐ LEVEL 1 ☐ LEVEL 2 ☐ LEVEL 3 ☑ LEVEL 4 ☐ OTHER (SPECIFY)

☑ SHELL CONTRACT RATE APPLIES
☐ STATE REIMBURSEMENT RATE APPLIES
☐ EDD NOT NEEDED
☑ RECEIPT VERIFICATION REQUESTED

REQUESTED ANALYSIS

| Lab Use Only | Field Sample Identification | SAMPLING DATE | SAMPLING TIME | Canister Number | Canister Pressure/Vacuum: Initial | Final | Receipt | Final (psi) | Modified TO-15 + Butane & Isopentane | ASTM D-1946 + Helium |
|---|---|---|---|---|---|---|---|---|---|---|
| LIA | VMP-29-10-020613 | 02/06/13 | 0929-0956 | 12392 | -30 | -9.5 | | | X | X |
| DA | VMP-29-20-020613 | 02/06/13 | 1022-1056 | 36529 | -30 | -9.5 | | | X | X |
| BA | VMP-29-30-020613 | 02/06/13 | 1120-1150 | 37391 | -30 | -10.5 | | | X | X |
| UA | VMP-30-10-020613 | 02/06/13 | 0917-0947 | 34064 | -30 | -8 | | | X | X |
| SA | VMP-30-20-020613 | 02/06/13 | 1017-1047 | 36515 | -30 | -9 | | | X | X |
| WA | VMP-30-30-020613 | 02/06/13 | 1115-1145 | 3390 | -30 | -8.5 | | | X | X |
| FA | VMP-32-5-020513 | 02/05/13 | 0853-0923 | 34650 | -29.5 | -7.5 | | | X | X |
| GA | VMP-32-10-020513 | 02/05/13 | 0939-1006 | 37695 | -29.5 | -7 | | | X | X |
| KA | VMP-32-20-020513 | 02/05/13 | 1028-1058 | 35601 | -29.5 | -9 | | | X | X |
| | | | | | | | | | X | X |

Turn Around Time: ☑ Normal ☐ Rush ☐ Specify

Lab Use Only
Pressurized by:
Date:
Pressurization Gas: $N_2$ He

ADDITIONAL NOTES:
- 14 day hold time
- Report results between MDL and RL
- Level IV ECVP

Relinquished by: (Signature)

Received by: (Signature) FEDEX

Relinquished by: (Signature)

Received by: (Signature)

Date: 2/7/13 Time: 1730
Date: 2/8/13 Time: 0930
Date: Time:

Custody Seal Intact?
Y N None Temp 4.2

05/2/08 Revision

1302156

# Shell Oil Products Chain Of Custody Record

URS

Air Toxics LTD.
**Project Name: Roxana Soil Vapor**
**Project # 21562850.04001**
Lab Vendor #

Please Check Appropriate Box:
☑ ENV. SERVICES ☐ MOTIVA RETAIL ☐ SHELL RETAIL
☐ MOTIVA SD&CM ☐ CONSULTANT ☐ LUBES
☐ SHELL PIPELINE ☐ OTHER

Print Bill To Contact Name: Robert Mooshegian
PO. #
INCIDENT # (ENV SERVICES): 9 7 2 1 6 6 4 0
☐ CHECK IF NO INCIDENT # APPLIES
SAP #: 3 4 0 0 6 1
DATE: 02/07/13
PAGE: 3 of 3

SAMPLING COMPANY: URS CORPORATION
LOG CODE:
SITE ADDRESS: Street and City: 900 SOUTH CENTRAL AVE – ROXANA
State: IL
GLOBAL ID NO.:
ADDRESS: 1001 HIGHLANDS PLAZA DRIVE WEST - SUITE 300; ST. LOUIS, MO 63110
LABORATORY ADDRESS: Air Toxics, LTD 180 Blue Ravine Road, Suite B, Folsom, CA 95630-4719
TELEPHONE:
FAX: 314-429-0462
BILL TO CONTACT E-MAIL: Robert.Mooshegian@urs.com
EDF DELIVERABLE TO (Name, Company, Office Location): Elizabeth Kunkel, URS, St. Louis
PHONE NO.: 314-743-4179
E-MAIL: Elizabeth_Kunkel@URSCorp.com
CONSULTANT PROJECT NAME: Roxana Soil Vapor
C. Williams, L. Rathnow, S. Jansen, D. Mattingly, B. Lehan, C. Kretzer

TURNAROUND TIME (CALENDAR DAYS):
☑ STANDARD (14 DAY) ☐ 5 DAYS ☐ 3 DAYS ☐ 2 DAYS ☐ 24 HOURS ☐ RESULTS NEEDED ON WEEKEND
☐ LA - RWQCB REPORT FORMAT ☑ UST AGENCY:
DELIVERABLES: ☐ LEVEL 1 ☐ LEVEL 2 ☐ LEVEL 3 ☑ LEVEL 4 ☐ OTHER (SPECIFY)

☑ SHELL CONTRACT RATE APPLIES
☐ STATE REIMBURSEMENT RATE APPLIES
☐ EDD NOT NEEDED
☑ RECEIPT VERIFICATION REQUESTED

REQUESTED ANALYSIS

| Lab Use Only | Field Sample Identification | SAMPLING DATE | SAMPLING TIME | Canister Number | Canister Pressure/Vacuum Initial | Final | Receipt | Final (psi) | Modified TO-15 + Butane & Isopentane | ASTM D-1946 + Helium |
|---|---|---|---|---|---|---|---|---|---|---|
| 20A | VMP-53-5-020513 | 02/05/13 | 0847-0917 | 22982 | -30 | -8.5 | | | X | X |
| 21A | VMP-53-10-020513 | 02/05/13 | 0934-1004 | 35688 | -30 | -8 | | | X | X |
| 22A | VMP-53-10-020513-DUP | 02/05/13 | 0934-1004 | 36441 | -30 | -7 | | | X | X |
| 23A | VMP-53-20-020513 | 02/05/13 | 1017-1047 | 37314 | -30 | -8.5 | | | X | X |
| 24A | VMP-53-30-020513 | 02/05/13 | 1059-1129 | 34133 | -30 | -8.5 | | | X | X |
| 25A | VMP-54-5-020613 | 02/06/13 | 0947-1018 | 31772 | -30 | -10 | | | X | X |
| 26A | VMP-54-10-020613 | 02/06/13 | 1122-1152 | 36431 | -30 | -9 | | | X | X |
| | | | | | | | | | X | X |
| | | | | | | | | | X | X |
| | | | | | | | | | X | X |

Turn Around Time:
☑ Normal
☐ Rush
Specify

Lab Use Only
Pressurized by:
Date:
Pressurization Gas: $N_2$ He

ADDITIONAL NOTES:
- 14 day hold time
- Report results between MDL and RL
- Level IV ECVP

| | | | |
|---|---|---|---|
| Relinquished by: (Signature) | Received by: (Signature) | Date: 2/7/13 | Time: 1730 |
| Relinquished by: (Signature) | Received by: (Signature) FEDEX | Date: 2/8/13 | Time: 0930 |
| Relinquished by: (Signature) | Received by: (Signature) | Date: | Time: |

05/2008 Revision

Custody Seal Intact?
Y N None Temp N/A

# Roxana Soil Vapor Quarterly – 1st Quarter 2013 Data Review

**Laboratory SDG: 1302248A,B**

**Data Reviewer: Alan Fleisher**

**Peer Reviewer: Elizabeth Kunkel**

**Date Reviewed: 3/26/2013**

**Guidance: USEPA National Functional Guidelines for Superfund Organic Methods Data Review 2008**

| Sample Identification | Sample Identification |
|---|---|
| VMP-3-10-020613 | VMP-3-22-020613 |
| VMP-4-5-020713 | VMP-4-12-020713 |
| VMP-4-12-020713-Dup | VMP-6-5-021213 |
| VMP-20-5-020713 | VMP-21-5-020613 |
| VMP-31-5-021113 | VMP-54-20-020613 |
| VMP-54-20-020613-Dup | VMP-54-30-020613 |
| VMP-54-30-020613-Dup | VMP-7-13.5-021313 |

## 1.0 Data Package Completeness

*Were all items delivered as specified in the QAPP and COC as appropriate?*

Yes

## 2.0 Laboratory Case Narrative \ Cooler Receipt Form

*Were problems noted in the laboratory case narrative or cooler receipt form?*

Yes, the laboratory case narrative indicated sample VMP-6-5-021213 was diluted and re-analyzed to bring the highest level target analytes within the calibration range of the instrument. Results for the highest level target anlaytes were reported from the re-analysis diluted runs and the remaining compounds were reported from the original analysis. The difference in benzene results for the field duplicate pair VMP-54-30-020613/VMP-54-30-020613-Dup was greater than two times (2X) the reporting level; therefore, results were qualified as estimated. Although not indicated in the laboratory case narrative, analytes were detected in the method blank. These issues are addressed further in the appropriate sections below.

No issues or discrepancies were noted in the cooler receipt form.

## 3.0 Holding Times

*Were samples extracted/analyzed within applicable limits?*

Yes

## 4.0 Blank Contamination

*Were any analytes detected in the Blanks?*

Yes

| Blank ID | Parameter | Analyte | Concentration/ Amount |
|---|---|---|---|
| 1302248A-15A | TO-15 | Bromomethane | 0.27 ppbv / 1.0 µg/m$^3$ |
| 1302248A-15A | TO-15 | Carbon disulfide | 0.48 ppbv / 1.5 µg/m$^3$ |
| 1302248A-15A | TO-15 | Methylene chloride | 0.18 ppbv / 0.64 µg/m$^3$ |
| 1302248A-15A | TO-15 | cis-1,3-Dichloropropene | 0.088 ppbv / 0.40 µg/m$^3$ |
| 1302248A-15A | TO-15 | Toluene | 0.080 ppbv / 0.30 µg/m$^3$ |
| 1302248A-15A | TO-15 | trans-1,3-Dichloropropene | 0.18 ppbv / 0.80 µg/m$^3$ |
| 1302248A-15A | TO-15 | Tetrachloroethene | 0.082 ppbv / 0.55 µg/m$^3$ |
| 1302248A-15A | TO-15 | 1,2-Dibromoethane (EDB) | 0.12 ppbv / 0.91 µg/m$^3$ |
| 1302248A-15A | TO-15 | Chlorobenzene | 0.11 ppbv / 0.49 µg/m$^3$ |
| 1302248A-15A | TO-15 | Cumene | 0.087 ppbv / 0.42 µg/m$^3$ |
| 1302248A-15A | TO-15 | 1,1,2,2-Tetrachloroethane | 0.094 ppbv / 0.64 µg/m$^3$ |
| 1302248A-15A | TO-15 | Propylbenzene | 0.12 ppbv / 0.56 µg/m$^3$ |
| 1302248A-15A | TO-15 | 4-Ethyltoluene | 0.088 ppbv / 0.44 µg/m$^3$ |
| 1302248A-15A | TO-15 | 1,3,5-Trimethylbenzene | 0.18 ppbv / 0.91 µg/m$^3$ |
| 1302248A-15A | TO-15 | 1,2,4-Tirmethylbenzene | 0.16 ppbv / 0.77 µg/m$^3$ |
| 1302248A-15A | TO-15 | 1,3-Dichlorobenzene | 0.29 ppbv / 1.8 µg/m$^3$ |
| 1302248A-15A | TO-15 | 1,4-Dichlorobenzene | 0.31 ppbv / 1.9 µg/m$^3$ |
| 1302248A-15A | TO-15 | alpha-Chlorotoluene | 0.16 ppbv / 0.80µg/m$^3$ |
| 1302248A-15A | TO-15 | 1,2-Dichlorobenzene | 0.27 ppbv / 1.6 µg/m$^3$ |
| 1302248A-15A | TO-15 | 1,2,4-Trichlorobenzene | 1.3 ppbv / 9.4 µg/m$^3$ |
| 1302248A-15A | TO-15 | Hexachlorobutadiene | 0.64 ppbv / 6.8 µg/m$^3$ |
| 1302248A-15B | TO-15 | Carbon disulfide | 0.34 ppbv / 1.1 µg/m$^3$ |
| 1302248A-15B | TO-15 | Toluene | 0.066 ppbv / 0.25 µg/m$^3$ |
| 1302248A-15B | TO-15 | Tetrachloroethene | 0.071 ppbv / 0.48 µg/m$^3$ |
| 1302248A-15B | TO-15 | 1,2-Dibromoethane (EDB) | 0.13 ppbv / 1.0 µg/m$^3$ |
| 1302248A-15B | TO-15 | Chlorobenzene | 0.13 ppbv / 0.59 µg/m$^3$ |
| 1302248A-15B | TO-15 | o-Xylene | 0.099 ppbv / 0.43 µg/m$^3$ |
| 1302248A-15B | TO-15 | Styrene | 0.11 ppbv / 0.46 µg/m$^3$ |
| 1302248A-15B | TO-15 | Cumene | 0.091 ppbv / 0.44 µg/m$^3$ |
| 1302248A-15B | TO-15 | 1,1,2,2-Tetrachloroethane | 0.18 ppbv / 1.3 µg/m$^3$ |
| 1302248A-15B | TO-15 | Propylbenzene | 0.15 ppbv / 0.76 µg/m$^3$ |
| 1302248A-15B | TO-15 | 4-Ethyltoluene | 0.097 ppbv / 0.48 µg/m$^3$ |
| 1302248A-15B | TO-15 | 1,3,5-Trimethylbenzene | 0.16 ppbv / 0.76 µg/m$^3$ |
| 1302248A-15B | TO-15 | 1,2,4-Tirmethylbenzene | 0.18 ppbv / 0.89 µg/m$^3$ |
| 1302248A-15B | TO-15 | 1,3-Dichlorobenzene | 0.28 ppbv / 1.7 µg/m$^3$ |
| 1302248A-15B | TO-15 | 1,4-Dichlorobenzene | 0.33 ppbv / 2.0 µg/m$^3$ |
| 1302248A-15B | TO-15 | alpha-Chlorotoluene | 0.18 ppbv / 0.95 µg/m$^3$ |
| 1302248A-15B | TO-15 | 1,2-Dichlorobenzene | 0.26 ppbv / 1.5 µg/m$^3$ |
| 1302248A-15B | TO-15 | 1,2,4-Trichlorobenzene | 0.72 ppbv / 5.3 µg/m$^3$ |
| 1302248A-15B | TO-15 | Hexachlorobutadiene | 0.46 ppbv / 4.9 µg/m$^3$ |
| 1302248B-15A | Natural Gases | Oxygen | 0.042% |
| 1302248B-15A | Natural Gases | Nitrogen | 0.099% |

Qualifications due to blank contamination are included in the table below. Analytical data that were reported non-detect or at concentrations greater than five times (5X) the

associated blank concentration did not require qualification.

| Sample ID | Parameter | Analyte | New Reporting Limit (RL) | Qualification |
|---|---|---|---|---|
| VMP-3-10-020613 | TO-15 | Carbon disulfide | - | **U** |
| VMP-3-10-020613 | TO-15 | Methylene chloride | - | **U** |
| VMP-3-10-020613 | TO-15 | Toluene | - | **U** |
| VMP-3-22-020613 | TO-15 | Carbon disulfide | - | **U** |
| VMP-3-22-020613 | TO-15 | Methylene chloride | - | **U** |
| VMP-3-22-020613 | TO-15 | Toluene | - | **U** |
| VMP-3-22-020613 | TO-15 | Tetrachloroethene | - | **U** |
| VMP-3-22-020613 | TO-15 | 1,2,4-Trichlorobenzene | - | **U** |
| VMP-4-5-020713 | TO-15 | Carbon disulfide | - | **U** |
| VMP-4-5-020713 | TO-15 | Propylbenzene | - | **U** |
| VMP-4-5-020713 | TO-15 | 1,2,4-Trimethylbenzene | - | **U** |
| VMP-4-12-020713 | TO-15 | Carbon disulfide | - | **U** |
| VMP-4-12-020713 | TO-15 | Methylene chloride | - | **U** |
| VMP-4-12-020713 | TO-15 | Toluene | - | **U** |
| VMP-4-12-020713 | TO-15 | Propylbenzene | - | **U** |
| VMP-4-12-020713 | TO-15 | 1,3,5-Trimethylbenzene | - | **U** |
| VMP-4-12-020713-Dup | TO-15 | Carbon disulfide | - | **U** |
| VMP-4-12-020713-Dup | TO-15 | Toluene | - | **U** |
| VMP-4-12-020713-Dup | TO-15 | 4-Ethyltoluene | - | **U** |
| VMP-6-5-021213 | TO-15 | Carbon disulfide | - | **U** |
| VMP-6-5-021213 | TO-15 | Toluene | - | **U** |
| VMP-6-5-021213 | TO-15 | 4-Ethyltoluene | - | **U** |
| VMP-20-5-020713 | TO-15 | Carbon disulfide | - | **U** |
| VMP-20-5-020713 | TO-15 | Methylene chloride | - | **U** |
| VMP-20-5-020713 | TO-15 | Toluene | - | **U** |
| VMP-20-5-020713 | TO-15 | Tetrachloroethene | - | **U** |
| VMP-21-5-020613 | TO-15 | Carbon disulfide | - | **U** |
| VMP-21-5-020613 | TO-15 | Toluene | - | **U** |
| VMP-21-5-020613 | TO-15 | Tetrachloroethene | - | **U** |
| VMP-21-5-020613 | TO-15 | 1,2,4-Trichlorobenzene | - | **U** |
| VMP-31-5-021113 | TO-15 | Bromomethane | - | **U** |
| VMP-31-5-021113 | TO-15 | Carbon disulfide | - | **U** |
| VMP-31-5-021113 | TO-15 | Tetrachloroethene | - | **U** |
| VMP-31-5-021113 | TO-15 | 1,3-Dichlorobenzene | - | **U** |
| VMP-31-5-021113 | TO-15 | 1,4-Dichlorobenzene | - | **U** |
| VMP-31-5-021113 | TO-15 | 1,2,4-Trichlorobenzene | - | **U** |
| VMP-54-20-020613 | TO-15 | Carbon disulfide | - | **U** |
| VMP-54-20-020613 | TO-15 | Toluene | - | **U** |
| VMP-54-20-020613 | TO-15 | Propylbenzene | - | **U** |
| VMP-54-20-020613 | TO-15 | 4-Ethyltoluene | - | **U** |
| VMP-54-20-020613 | TO-15 | 1,2,4-Trimethylbenzene | - | **U** |

| Sample ID | Parameter | Analyte | New Reporting Limit (RL) | Qualification |
|---|---|---|---|---|
| VMP-54-20-020613 | TO-15 | 1,3-Dichlorobenzene | - | **U** |
| VMP-54-20-020613 | TO-15 | 1,4-Dichlorobenzene | - | **U** |
| VMP-54-20-020613 | TO-15 | 1,2,4-Trichlorobenzene | - | **U** |
| VMP-54-20-020613-Dup | TO-15 | Carbon disulfide | - | **U** |
| VMP-54-20-020613-Dup | TO-15 | Toluene | - | **U** |
| VMP-54-20-020613-Dup | TO-15 | Propylbenzene | - | **U** |
| VMP-54-20-020613-Dup | TO-15 | 4-Ethyltoluene | - | **U** |
| VMP-54-20-020613-Dup | TO-15 | 1,2,4-Trimethylbenzene | - | **U** |
| VMP-54-20-020613-Dup | TO-15 | 1,3-Dichlorobenzene | - | **U** |
| VMP-54-20-020613-Dup | TO-15 | 1,4-Dichlorobenzene | - | **U** |
| VMP-54-20-020613-Dup | TO-15 | 1,2,4-Trichlorobenzene | - | **U** |
| VMP-54-30-020613 | TO-15 | Carbon disulfide | - | **U** |
| VMP-54-30-020613 | TO-15 | Toluene | - | **U** |
| VMP-54-30-020613 | TO-15 | 1,2,4-Trichlorobenzene | - | **U** |
| VMP-54-30-020613-Dup | TO-15 | Carbon disulfide | - | **U** |
| VMP-54-30-020613-Dup | TO-15 | Toluene | - | **U** |
| VMP-7-13.5-021313 | TO-15 | Carbon disulfide | - | **U** |
| VMP-7-13.5-021313 | TO-15 | Toluene | - | **U** |
| VMP-7-13.5-021313 | TO-15 | 1,2,4-Trichlorobenzene | - | **U** |

## 5.0 Laboratory Control Sample

*Were LCS recoveries within evaluation criteria?*

Yes

## 6.0 Surrogate Recoveries

*Were surrogate recoveries within evaluation criteria?*

Yes

## 7.0 Matrix Spike and Matrix Spike Duplicate Recoveries

*Were MS/MSD samples analyzed as part of this SDG?*

MS/MSD samples are not applicable for vapor samples, due to the inability to spike the samples.

## 8.0 Laboratory Duplicate Results

*Were laboratory duplicate samples collected as part of this SDG?*

No

## 9.0 Field Duplicate Results

*Were field duplicate samples collected as part of this SDG?*

Yes

| Field ID | Field Duplicate ID |
|---|---|
| VMP-4-12-020713 | VMP-4-12-020713-Dup |
| VMP-54-20-020613 | VMP-54-20-020613-Dup |
| VMP-54-30-020613 | VMP-54-30-020613-Dup |

*Were field duplicate sample RPDs within evaluation criteria?*

No

| Field ID | Field Duplicate ID | Parameter | Analyte | RPD | Qualification |
|---|---|---|---|---|---|
| VMP-54-30-020613 | VMP-54-30-020613-Dup | TO-15 | Benzene | **>2X RL** | **J/J** |

## 10.0 Sample Dilutions

*For samples that were diluted and nondetect, were undiluted results also reported?*

Not applicable; analytes were detected in samples that were diluted.

## 11.0 Additional Qualifications

*Were additional qualifications applied?*

No

eurofins | Air Toxics

2/28/2013
Ms. Elizabeth Kunkel
URS Corporation
1001 Highlands Plaza Dr. West
Suite 300
St. Louis MO 63110

Project Name: Roxana Soil Vapor
Project #: 21562850.04001
Workorder #: 1302248A

Dear Ms. Elizabeth Kunkel

The following report includes the data for the above referenced project for sample(s) received on 2/14/2013 at Air Toxics Ltd.

The data and associated QC analyzed by Modified TO-15 are compliant with the project requirements or laboratory criteria with the exception of the deviations noted in the attached case narrative.

Thank you for choosing Air Toxics Ltd. for your air analysis needs. Air Toxics Ltd. is committed to providing accurate data of the highest quality. Please feel free to contact the Project Manager: Kelly Buettner at 916-985-1000 if you have any questions regarding the data in this report.

Regards,

Kelly Buettner

Project Manager

REVIEWED
ON
3/26/13

eurofins | Air Toxics

# WORK ORDER #: 1302248A

Work Order Summary

| | | | |
|---|---|---|---|
| **CLIENT:** | Ms. Elizabeth Kunkel<br>URS Corporation<br>1001 Highlands Plaza Dr. West<br>Suite 300<br>St. Louis, MO 63110 | **BILL TO:** | Accounts Payable Austin<br>URS Corporation<br>P.O. BOX 203970<br>Austin, TX 78720-1088 |
| **PHONE:** | 314-743-4179 | **P.O. #** | 21562735.00013 |
| **FAX:** | | **PROJECT #** | 21562850.04001 Roxana Soil Vapor |
| **DATE RECEIVED:** | 02/14/2013 | **CONTACT:** | Kelly Buettner |
| **DATE COMPLETED:** | 02/28/2013 | | |

| FRACTION # | NAME | TEST | RECEIPT VAC./PRES. | FINAL PRESSURE |
|---|---|---|---|---|
| 01A | VMP-3-10-020613 | Modified TO-15 | 8.5 "Hg | 15 psi |
| 02A | VMP-3-22-020613 | Modified TO-15 | 9.0 "Hg | 15 psi |
| 03A | VMP-4-5-020713 | Modified TO-15 | 5.5 "Hg | 15 psi |
| 04A | VMP-4-12-020713 | Modified TO-15 | 7.5 "Hg | 15 psi |
| 05A | VMP-4-12-020713-DUP | Modified TO-15 | 8.0 "Hg | 15 psi |
| 06A | VMP-6-5-021213 | Modified TO-15 | 5.5 "Hg | 15 psi |
| 06B | VMP-6-5-021213 | Modified TO-15 | 5.5 "Hg | 15 psi |
| 07A | VMP-20-5-020713 | Modified TO-15 | 5.5 "Hg | 15 psi |
| 08A | VMP-21-5-020613 | Modified TO-15 | 8.5 "Hg | 15 psi |
| 09A | VMP-31-5-021113 | Modified TO-15 | 6.5 "Hg | 15 psi |
| 10A | VMP-54-20-020613 | Modified TO-15 | 8.0 "Hg | 15 psi |
| 11A | VMP-54-20-020613-DUP | Modified TO-15 | 8.0 "Hg | 15 psi |
| 12A | VMP-54-30-020613 | Modified TO-15 | 9.5 "Hg | 15 psi |
| 13A | VMP-54-30-020613-DUP | Modified TO-15 | 9.5 "Hg | 15 psi |
| 14A | VMP-7-13.5-021313 | Modified TO-15 | 8.0 "Hg | 15 psi |
| 15A | Lab Blank | Modified TO-15 | NA | NA |
| 15B | Lab Blank | Modified TO-15 | NA | NA |
| 16A | CCV | Modified TO-15 | NA | NA |
| 16B | CCV | Modified TO-15 | NA | NA |
| 17A | LCS | Modified TO-15 | NA | NA |
| 17AA | LCSD | Modified TO-15 | NA | NA |
| 17B | LCS | Modified TO-15 | NA | NA |
| 17BB | LCSD | Modified TO-15 | NA | NA |

CERTIFIED BY: Heidi Hayes DATE: 02/28/13

Technical Director

Certfication numbers: AZ Licensure AZ0775, CA NELAP - 12282CA, NY NELAP - 11291, TX NELAP - T104704434-12-5, UT NELAP CA009332012-3, WA NELAP - C935
Name of Accrediting Agency: NELAP/ORELAP (Oregon Environmental Laboratory Accreditation Program)
Accreditation number: CA300005, Effective date: 10/18/2011, Expiration date: 10/17/2012.
Eurofins Air Toxics Ltd. certifies that the test results contained in this report meet all requirements of the NELAC standards

This report shall not be reproduced, except in full, without the written approval of Eurofins Air Toxics, Inc.

180 BLUE RAVINE ROAD, SUITE B FOLSOM, CA - 9563
(916) 985-1000 . (800) 985-5955 . FAX (916) 985-1020

**LABORATORY NARRATIVE**
**EPA Method TO-15**
**URS Corporation**
**Workorder# 1302248A**

Fourteen 1 Liter Summa Canister samples were received on February 14, 2013. The laboratory performed analysis via EPA Method TO-15 using GC/MS in the full scan mode.

This workorder was independently validated prior to submittal using 'USEPA National Functional Guidelines' as generally applied to the analysis of volatile organic compounds in air. A rules-based, logic driven, independent validation engine was employed to assess completeness, evaluate pass/fail of relevant project quality control requirements and verification of all quantified amounts.

**Receiving Notes**

There were no receiving discrepancies.

**Analytical Notes**

As per client project requirements, the laboratory has reported estimated values for target compound hits that are below the Reporting Limit but greater than the Method Detection Limit. Concentrations that are below the level at which the canister was certified (0.2 ppbv for compounds reported at 0.5 ppbv and 0.8 ppbv for compounds reported at 2.0 ppbv) may be false positives.

Due to high-level target compounds, sample VMP-6-5-021213 was analyzed twice. In the "A" fraction, the sample was diluted to bring the highest-level compounds within the calibration range. The "B" fraction is also reported by client request and may be reported with "E" flags indicating the compound exceeds the calibration range. Both runs and associated QC are reported.

**Definition of Data Qualifying Flags**

Eight qualifiers may have been used on the data analysis sheets and indicates as follows:

B - Compound present in laboratory blank greater than reporting limit (background subtraction not performed).
J - Estimated value.
E - Exceeds instrument calibration range.
S - Saturated peak.
Q - Exceeds quality control limits.
U - Compound analyzed for but not detected above the reporting limit.
UJ- Non-detected compound associated with low bias in the CCV and/or LCS.
N - The identification is based on presumptive evidence.

File extensions may have been used on the data analysis sheets and indicates as follows:
a-File was requantified
b-File was quantified by a second column and detector
r1-File was requantified for the purpose of reissue

eurofins | Air Toxics

# Summary of Detected Compounds
# EPA METHOD TO-15 GC/MS FULL SCAN

**Client Sample ID: VMP-3-10-020613**

**Lab ID#: 1302248A-01A**

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 1.4 | 0.51 J | 7.0 | 2.5 J |
| Freon 11 | 1.4 | 0.25 J | 7.9 | 1.4 J |
| Ethanol | 5.6 | 1.2 J | 11 | 2.3 J |
| Acetone | 14 | 4.8 J | 33 | 12 J |
| 2-Propanol | 5.6 | 1.4 J | 14 | 3.5 J |
| Carbon Disulfide | 5.6 | ~~0.81 J~~ U | 18 | ~~2.5 J~~ U |
| Methylene Chloride | 14 | ~~0.27 J~~ U | 49 | ~~0.94 J~~ U |
| 2,2,4-Trimethylpentane | 1.4 | 0.41 J | 6.6 | 1.9 J |
| Toluene | 1.4 | ~~0.17 J~~ U | 5.3 | ~~0.65 J~~ U |
| Tetrachloroethene | 1.4 | 1.3 J | 9.6 | 8.8 J |

**Client Sample ID: VMP-3-22-020613**

**Lab ID#: 1302248A-02A**

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 1.4 | 0.52 J | 7.1 | 2.6 J |
| Freon 11 | 1.4 | 0.25 J | 8.1 | 1.4 J |
| Ethanol | 5.8 | 2.2 J | 11 | 4.2 J |
| Acetone | 14 | 7.9 J | 34 | 19 J |
| 2-Propanol | 5.8 | 0.89 J | 14 | 2.2 J |
| Carbon Disulfide | 5.8 | ~~0.86 J~~ U | 18 | ~~2.7 J~~ U |
| Methylene Chloride | 14 | ~~0.23 J~~ U | 50 | ~~0.79 J~~ U |
| Hexane | 1.4 | 0.33 J | 5.1 | 1.2 J |
| Tetrahydrofuran | 1.4 | 0.37 J | 4.3 | 1.1 J |
| Chloroform | 1.4 | 16 | 7.0 | 78 |
| 2,2,4-Trimethylpentane | 1.4 | 0.68 J | 6.8 | 3.2 J |
| Benzene | 1.4 | 16 | 4.6 | 52 |
| Toluene | 1.4 | ~~0.15 J~~ U | 5.4 | ~~0.56 J~~ U |
| Tetrachloroethene | 1.4 | ~~0.18 J~~ U | 9.8 | ~~1.2 J~~ U |
| 1,2,4-Trichlorobenzene | 5.8 | ~~0.49 J~~ U | 43 | ~~3.6 J~~ U |
| Butane | 5.8 | 2.5 J | 14 | 6.0 J |
| Isopentane | 5.8 | 3.0 J | 17 | 8.7 J |

eurofins | Air Toxics

# Summary of Detected Compounds
# EPA METHOD TO-15 GC/MS FULL SCAN

**Client Sample ID: VMP-4-5-020713**

**Lab ID#: 1302248A-03A**

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 1.2 | 0.45 J | 6.1 | 2.2 J |
| Freon 11 | 1.2 | 0.22 J | 6.9 | 1.2 J |
| Ethanol | 4.9 | 1.8 J | 9.3 | 3.4 J |
| Acetone | 12 | 3.2 J | 29 | 7.6 J |
| 2-Propanol | 4.9 | 1.7 J | 12 | 4.3 J |
| Carbon Disulfide | 4.9 | ~~0.83 J~~ | 15 | ~~2.6 J~~ |
| Methylene Chloride | 12 | 0.93 J | 43 | 3.2 J |
| Hexane | 1.2 | 0.50 J | 4.4 | 1.7 J |
| 2,2,4-Trimethylpentane | 1.2 | 2.7 | 5.8 | 13 |
| Benzene | 1.2 | 1.8 | 3.9 | 5.7 |
| Toluene | 1.2 | 0.42 J | 4.6 | 1.6 J |
| m,p-Xylene | 1.2 | 0.28 J | 5.4 | 1.2 J |
| Propylbenzene | 1.2 | ~~0.16 J~~ | 6.1 | ~~0.78 J~~ |
| 4-Ethyltoluene | 1.2 | 0.50 J | 6.1 | 2.4 J |
| 1,2,4-Trimethylbenzene | 1.2 | ~~0.29 J~~ | 6.1 | ~~1.4 J~~ |
| Butane | 4.9 | 2.9 J | 12 | 6.8 J |
| Isopentane | 4.9 | 3.0 J | 14 | 8.8 J |

**Client Sample ID: VMP-4-12-020713**

**Lab ID#: 1302248A-04A**

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 1.3 | 0.52 J | 6.6 | 2.6 J |
| Freon 11 | 1.3 | 0.21 J | 7.6 | 1.2 J |
| Ethanol | 5.4 | 1.6 J | 10 | 3.1 J |
| Acetone | 13 | 3.2 J | 32 | 7.7 J |
| 2-Propanol | 5.4 | 3.0 J | 13 | 7.3 J |
| Carbon Disulfide | 5.4 | ~~0.86 J~~ | 17 | ~~2.7 J~~ |
| Methylene Chloride | 13 | ~~0.22 J~~ | 47 | ~~0.75 J~~ |
| Cyclohexane | 1.3 | 0.97 J | 4.6 | 3.3 J |
| 2,2,4-Trimethylpentane | 1.3 | 10 | 6.3 | 49 |
| Benzene | 1.3 | 2.2 | 4.3 | 6.9 |
| Toluene | 1.3 | ~~0.18 J~~ | 5.1 | ~~0.68 J~~ |

eurofins | Air Toxics

# Summary of Detected Compounds
# EPA METHOD TO-15 GC/MS FULL SCAN

**Client Sample ID: VMP-4-12-020713**

**Lab ID#: 1302248A-04A**

| | | | | |
|---|---|---|---|---|
| Propylbenzene | 1.3 | ~~0.30 J~~ U | 6.6 | ~~1.5 J~~ U |
| 4-Ethyltoluene | 1.3 | 1.4 | 6.6 | 7.0 |
| 1,3,5-Trimethylbenzene | 1.3 | ~~0.46 J~~ U | 6.6 | ~~2.2 J~~ U |
| 1,2,4-Trimethylbenzene | 1.3 | ~~1.5~~ J OK (AF) | 6.6 | ~~7.3~~ J OK (AF) |
| Butane | 5.4 | 11 | 13 | 25 |
| Isopentane | 5.4 | 15 | 16 | 44 |

**Client Sample ID: VMP-4-12-020713-DUP**

**Lab ID#: 1302248A-05A**

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 1.4 | 0.50 J | 6.8 | 2.5 J |
| Freon 11 | 1.4 | 0.34 J | 7.8 | 1.9 J |
| Ethanol | 5.5 | 2.0 J | 10 | 3.7 J |
| Acetone | 14 | 5.2 J | 33 | 12 J |
| 2-Propanol | 5.5 | 2.2 J | 14 | 5.4 J |
| Carbon Disulfide | 5.5 | ~~0.86 J~~ U | 17 | ~~2.7 J~~ U |
| Hexane | 1.4 | 0.76 J | 4.9 | 2.7 J |
| 2,2,4-Trimethylpentane | 1.4 | 11 | 6.4 | 51 |
| Benzene | 1.4 | 4.2 | 4.4 | 13 |
| Toluene | 1.4 | ~~0.13 J~~ U | 5.2 | ~~0.48 J~~ U |
| 4-Ethyltoluene | 1.4 | ~~0.094 J~~ U | 6.8 | ~~0.46 J~~ U |
| Butane | 5.5 | 12 | 13 | 30 |
| Isopentane | 5.5 | 15 | 16 | 45 |

**Client Sample ID: VMP-6-5-021213**

* USE THIS RESULT ONLY. ALL OTHER RESULTS REPORTED IN 2.47X DILUTION ANALYSIS

**Lab ID#: 1302248A-06A**

DF = 4.94X

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 2.5 | 0.54 J | 12 | 2.7 J |
| Ethanol | 9.9 | 2.0 J | 19 | 3.8 J |
| * Acetone | 25 | 770 | 59 | 1800 |
| 2-Propanol | 9.9 | 3.5 J | 24 | 8.6 J |
| Carbon Disulfide | 9.9 | ~~1.4 J~~ U | 31 | ~~4.4 J~~ U |

eurofins | Air Toxics

# Summary of Detected Compounds
# EPA METHOD TO-15 GC/MS FULL SCAN

**Client Sample ID: VMP-6-5-021213**

**Lab ID#: 1302248A-06A**

| | | | | |
|---|---|---|---|---|
| Hexane | 2.5 | 4.3 | 8.7 | 15 |
| 2,2,4-Trimethylpentane | 2.5 | 13 | 12 | 60 |
| Benzene | 2.5 | 12 | 7.9 | 39 |
| 4-Methyl-2-pentanone | 2.5 | 0.60 J | 10 | 2.4 J |
| Toluene | 2.5 | ~~0.21 J~~ U | 9.3 | ~~0.80 J~~ U |
| Butane | 9.9 | 49 | 23 | 120 |
| Isopentane | 9.9 | 46 | 29 | 140 |

**Client Sample ID: VMP-6-5-021213** * DO NOT USE THIS DATA. USE ALL OTHER DATA.

**Lab ID#: 1302248A-06B** DF = 2.47 x

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 1.2 | 0.52 J | 6.1 | 2.6 J |
| Freon 11 | 1.2 | 0.23 J | 6.9 | 1.3 J |
| Ethanol | 4.9 | 2.1 J | 9.3 | 4.0 J |
| * ~~Acetone~~ | ~~12~~ | ~~680 E~~ | ~~29~~ | ~~1600 E~~ |
| 2-Propanol | 4.9 | 3.0 J | 12 | 7.3 J |
| Carbon Disulfide | 4.9 | ~~0.74 J~~ U | 15 | ~~2.3 J~~ U |
| Hexane | 1.2 | 4.2 | 4.4 | 15 |
| Cyclohexane | 1.2 | 0.55 J | 4.2 | 1.9 J |
| 2,2,4-Trimethylpentane | 1.2 | 12 | 5.8 | 58 |
| Benzene | 1.2 | 12 | 3.9 | 37 |
| Heptane | 1.2 | 0.46 J | 5.1 | 1.9 J |
| 4-Methyl-2-pentanone | 1.2 | 0.44 J | 5.0 | 1.8 J |
| Toluene | 1.2 | ~~0.13 J~~ U | 4.6 | ~~0.49 J~~ U |
| 4-Ethyltoluene | 1.2 | ~~0.15 J~~ U | 6.1 | ~~0.74 J~~ U |
| Butane | 4.9 | 46 | 12 | 110 |
| Isopentane | 4.9 | 42 | 14 | 120 |

**Client Sample ID: VMP-20-5-020713**

**Lab ID#: 1302248A-07A**

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 1.2 | 0.56 J | 6.1 | 2.8 J |

eurofins | Air Toxics

# Summary of Detected Compounds
# EPA METHOD TO-15 GC/MS FULL SCAN

**Client Sample ID: VMP-20-5-020713**

**Lab ID#: 1302248A-07A**

| | | | | |
|---|---|---|---|---|
| Freon 11 | 1.2 | 2.2 | 6.9 | 12 |
| Ethanol | 4.9 | 3.4 J | 9.3 | 6.4 J |
| Acetone | 12 | 10 J | 29 | 24 J |
| 2-Propanol | 4.9 | 2.3 J | 12 | 5.7 J |
| Carbon Disulfide | 4.9 | ~~0.88 J~~ U | 15 | ~~2.8 J~~ U |
| Methylene Chloride | 12 | ~~0.18 J~~ U | 43 | ~~0.61 J~~ U |
| Hexane | 1.2 | 7.6 | 4.4 | 27 |
| 2-Butanone (Methyl Ethyl Ketone) | 4.9 | 0.94 J | 14 | 2.8 J |
| 2,2,4-Trimethylpentane | 1.2 | 25 | 5.8 | 120 |
| Benzene | 1.2 | 11 | 3.9 | 35 |
| Heptane | 1.2 | 0.49 J | 5.1 | 2.0 J |
| Toluene | 1.2 | ~~0.22 J~~ U | 4.6 | ~~0.81 J~~ U |
| Tetrachloroethene | 1.2 | ~~0.13 J~~ U | 8.4 | ~~0.89 J~~ U |
| Ethyl Benzene | 1.2 | 0.47 J | 5.4 | 2.0 J |
| m,p-Xylene | 1.2 | 0.98 J | 5.4 | 4.2 J |
| Cumene | 1.2 | 0.44 J | 6.1 | 2.1 J |
| Propylbenzene | 1.2 | 1.2 | 6.1 | 6.0 |
| 4-Ethyltoluene | 1.2 | 3.5 | 6.1 | 17 |
| 1,3,5-Trimethylbenzene | 1.2 | 1.8 | 6.1 | 8.8 |
| 1,2,4-Trimethylbenzene | 1.2 | 12 | 6.1 | 60 |
| Butane | 4.9 | 220 | 12 | 510 |
| Isopentane | 4.9 | 180 | 14 | 530 |

**Client Sample ID: VMP-21-5-020613**

**Lab ID#: 1302248A-08A**

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 1.4 | 0.58 J | 7.0 | 2.9 J |
| Freon 11 | 1.4 | 0.25 J | 7.9 | 1.4 J |
| Ethanol | 5.6 | 3.3 J | 11 | 6.2 J |
| Acetone | 14 | 5.0 J | 33 | 12 J |
| 2-Propanol | 5.6 | 1.4 J | 14 | 3.3 J |
| Carbon Disulfide | 5.6 | ~~0.92 J~~ U | 18 | ~~2.8 J~~ U |
| 2-Butanone (Methyl Ethyl Ketone) | 5.6 | 0.91 J | 17 | 2.7 J |
| 2,2,4-Trimethylpentane | 1.4 | 0.25 J | 6.6 | 1.2 J |

eurofins | Air Toxics

# Summary of Detected Compounds
# EPA METHOD TO-15 GC/MS FULL SCAN

**Client Sample ID: VMP-21-5-020613**

**Lab ID#: 1302248A-08A**

| | | | | |
|---|---|---|---|---|
| Benzene | 1.4 | 0.62 J | 4.5 | 2.0 J |
| Toluene | 1.4 | ~~0.12 J~~ | 5.3 | ~~0.44 J~~ |
| Tetrachloroethene | 1.4 | ~~0.25 J~~ | 9.6 | ~~1.7 J~~ |
| 1,2,4-Trichlorobenzene | 5.6 | ~~0.37 J~~ | 42 | ~~2.8 J~~ |

**Client Sample ID: VMP-31-5-021113**

**Lab ID#: 1302248A-09A**

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 1.3 | 0.44 J | 6.4 | 2.2 J |
| Bromomethane | 13 | ~~0.65 J~~ | 50 | ~~2.5 J~~ |
| Freon 11 | 1.3 | 0.24 J | 7.2 | 1.3 J |
| Ethanol | 5.2 | 9.8 | 9.7 | 18 |
| Acetone | 13 | 27 | 31 | 64 |
| 2-Propanol | 5.2 | 26 | 13 | 64 |
| Carbon Disulfide | 5.2 | ~~0.90 J~~ | 16 | ~~2.8 J~~ |
| Hexane | 1.3 | 3.1 | 4.5 | 11 |
| 2-Butanone (Methyl Ethyl Ketone) | 5.2 | 1.3 J | 15 | 3.9 J |
| Cyclohexane | 1.3 | 0.93 J | 4.4 | 3.2 J |
| 2,2,4-Trimethylpentane | 1.3 | 2.8 | 6.0 | 13 |
| Benzene | 1.3 | 0.55 J | 4.1 | 1.7 J |
| Heptane | 1.3 | 1.7 | 5.3 | 7.1 |
| 4-Methyl-2-pentanone | 1.3 | 0.72 J | 5.3 | 2.9 J |
| Toluene | 1.3 | 3.0 | 4.9 | 11 |
| Tetrachloroethene | 1.3 | ~~0.17 J~~ | 8.8 | ~~1.2 J~~ |
| Ethyl Benzene | 1.3 | 2.7 | 5.6 | 12 |
| m,p-Xylene | 1.3 | 7.6 | 5.6 | 33 |
| o-Xylene | 1.3 | 3.4 | 5.6 | 15 |
| Cumene | 1.3 | 0.44 J | 6.3 | 2.2 J |
| Propylbenzene | 1.3 | 1.2 J | 6.3 | 5.7 J |
| 4-Ethyltoluene | 1.3 | 3.6 | 6.3 | 18 |
| 1,3,5-Trimethylbenzene | 1.3 | 1.1 J | 6.3 | 5.3 J |
| 1,2,4-Trimethylbenzene | 1.3 | 2.9 | 6.3 | 14 |
| 1,3-Dichlorobenzene | 1.3 | ~~0.20 J~~ | 7.8 | ~~1.2 J~~ |
| 1,4-Dichlorobenzene | 1.3 | ~~0.23 J~~ | 7.8 | ~~1.4 J~~ |

eurofins | Air Toxics

# Summary of Detected Compounds
# EPA METHOD TO-15 GC/MS FULL SCAN

**Client Sample ID: VMP-31-5-021113**

**Lab ID#: 1302248A-09A**

| | | | | |
|---|---|---|---|---|
| 1,2,4-Trichlorobenzene | 5.2 | ~~0.38 J~~ U | 38 | ~~2.8 J~~ U |
| Butane | 5.2 | 4.0 J | 12 | 9.6 J |
| Isopentane | 5.2 | 5.8 | 15 | 17 |

**Client Sample ID: VMP-54-20-020613**

**Lab ID#: 1302248A-10A**

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 1.4 | 0.58 J | 6.8 | 2.8 J |
| Freon 11 | 1.4 | 0.24 J | 7.8 | 1.4 J |
| Ethanol | 5.5 | 1.7 J | 10 | 3.2 J |
| Acetone | 14 | 12 J | 33 | 29 J |
| 2-Propanol | 5.5 | 3.4 J | 14 | 8.3 J |
| Carbon Disulfide | 5.5 | ~~0.89 J~~ U | 17 | ~~2.8 J~~ U |
| Hexane | 1.4 | 1.1 J | 4.9 | 4.0 J |
| 2-Butanone (Methyl Ethyl Ketone) | 5.5 | 1.7 J | 16 | 5.0 J |
| 2,2,4-Trimethylpentane | 1.4 | 0.24 J | 6.4 | 1.1 J |
| Benzene | 1.4 | 0.89 J | 4.4 | 2.8 J |
| Heptane | 1.4 | 0.98 J | 5.6 | 4.0 J |
| Toluene | 1.4 | ~~0.19 J~~ U | 5.2 | ~~0.72 J~~ U |
| Tetrachloroethene | 1.4 | 0.77 J | 9.4 | 5.2 J |
| Propylbenzene | 1.4 | ~~0.15 J~~ U | 6.8 | ~~0.74 J~~ U |
| 4-Ethyltoluene | 1.4 | ~~0.13 J~~ U | 6.8 | ~~0.63 J~~ U |
| 1,2,4-Trimethylbenzene | 1.4 | ~~0.33 J~~ U | 6.8 | ~~1.6 J~~ U |
| 1,3-Dichlorobenzene | 1.4 | ~~0.23 J~~ U | 8.3 | ~~1.4 J~~ U |
| 1,4-Dichlorobenzene | 1.4 | ~~0.25 J~~ U | 8.3 | ~~1.5 J~~ U |
| 1,2,4-Trichlorobenzene | 5.5 | ~~0.78 J~~ U | 41 | ~~5.8 J~~ U |
| Butane | 5.5 | 2.0 J | 13 | 4.9 J |
| Isopentane | 5.5 | 1.0 J | 16 | 3.0 J |

**Client Sample ID: VMP-54-20-020613-DUP**

**Lab ID#: 1302248A-11A**

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|

eurofins | Air Toxics

# Summary of Detected Compounds
# EPA METHOD TO-15 GC/MS FULL SCAN

**Client Sample ID: VMP-54-20-020613-DUP**

**Lab ID#: 1302248A-11A**

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 1.4 | 0.47 J | 6.8 | 2.3 J |
| Freon 11 | 1.4 | 0.23 J | 7.8 | 1.3 J |
| Ethanol | 5.5 | 2.7 J | 10 | 5.0 J |
| Acetone | 14 | 9.8 J | 33 | 23 J |
| 2-Propanol | 5.5 | 5.9 | 14 | 14 |
| Carbon Disulfide | 5.5 | ~~0.78 J~~ U | 17 | ~~2.4 J~~ U |
| Methylene Chloride | 14 | 0.26 J | 48 | 0.92 J |
| Hexane | 1.4 | 1.8 | 4.9 | 6.4 |
| 2-Butanone (Methyl Ethyl Ketone) | 5.5 | 1.1 J | 16 | 3.3 J |
| Cyclohexane | 1.4 | 0.75 J | 4.8 | 2.6 J |
| 2,2,4-Trimethylpentane | 1.4 | 0.93 J | 6.4 | 4.3 J |
| Benzene | 1.4 | 11 | 4.4 | 36 |
| Heptane | 1.4 | 1.2 J | 5.6 | 4.8 J |
| Toluene | 1.4 | ~~0.18 J~~ U | 5.2 | ~~0.68 J~~ U |
| Tetrachloroethene | 1.4 | 0.67 J | 9.4 | 4.6 J |
| Propylbenzene | 1.4 | ~~0.15 J~~ U | 6.8 | ~~0.73 J~~ U |
| 4-Ethyltoluene | 1.4 | ~~0.42 J~~ U | 6.8 | ~~2.1 J~~ U |
| 1,2,4-Trimethylbenzene | 1.4 | ~~0.32 J~~ U | 6.8 | ~~1.6 J~~ U |
| 1,3-Dichlorobenzene | 1.4 | ~~0.20 J~~ U | 8.3 | ~~1.2 J~~ U |
| 1,4-Dichlorobenzene | 1.4 | ~~0.21 J~~ U | 8.3 | ~~1.3 J~~ U |
| 1,2,4-Trichlorobenzene | 5.5 | ~~0.55 J~~ U | 41 | ~~4.1 J~~ U |
| Butane | 5.5 | 2.6 J | 13 | 6.1 J |
| Isopentane | 5.5 | 3.9 J | 16 | 12 J |

**Client Sample ID: VMP-54-30-020613**

**Lab ID#: 1302248A-12A**

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 1.5 | 0.53 J | 7.3 | 2.6 J |
| Freon 11 | 1.5 | 0.21 J | 8.3 | 1.2 J |
| Ethanol | 5.9 | 1.4 J | 11 | 2.7 J |
| Acetone | 15 | 5.1 J | 35 | 12 J |
| 2-Propanol | 5.9 | 1.7 J | 14 | 4.2 J |

eurofins | Air Toxics

# Summary of Detected Compounds
# EPA METHOD TO-15 GC/MS FULL SCAN

**Client Sample ID: VMP-54-30-020613**

**Lab ID#: 1302248A-12A**

| | | | | |
|---|---|---|---|---|
| Carbon Disulfide | 5.9 | ~~1.0 J~~ U | 18 | ~~3.2 J~~ U |
| Methylene Chloride | 15 | 0.28 J | 51 | 0.97 J |
| Hexane | 1.5 | 0.46 J | 5.2 | 1.6 J |
| 2,2,4-Trimethylpentane | 1.5 | 0.50 J | 6.9 | 2.3 J |
| Benzene | 1.5 | 4.5 | 4.7 | 14 |
| Toluene | 1.5 | ~~0.12 J~~ U | 5.6 | ~~0.48 J~~ U |
| Tetrachloroethene | 1.5 | 0.67 J | 10 | 4.6 J |
| 1,2,4-Trichlorobenzene | 5.9 | ~~0.41 J~~ U | 44 | ~~3.1 J~~ U |
| Isopentane | 5.9 | 1.5 J | 17 | 4.5 J |

**Client Sample ID: VMP-54-30-020613-DUP**

**Lab ID#: 1302248A-13A**

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 1.5 | 0.51 J | 7.3 | 2.5 J |
| Freon 11 | 1.5 | 0.23 J | 8.3 | 1.3 J |
| Ethanol | 5.9 | 1.8 J | 11 | 3.5 J |
| Acetone | 15 | 5.6 J | 35 | 13 J |
| 2-Propanol | 5.9 | 1.4 J | 14 | 3.4 J |
| Carbon Disulfide | 5.9 | ~~0.95 J~~ U | 18 | ~~3.0 J~~ U |
| Hexane | 1.5 | 0.46 J | 5.2 | 1.6 J |
| 2,2,4-Trimethylpentane | 1.5 | 0.27 J | 6.9 | 1.3 J |
| Benzene | 1.5 | 1.4 J | 4.7 | 4.5 J |
| Toluene | 1.5 | ~~0.14 J~~ U | 5.6 | ~~0.55 J~~ U |
| Tetrachloroethene | 1.5 | 0.67 J | 10 | 4.5 J |
| Isopentane | 5.9 | 0.78 J | 17 | 2.3 J |

**Client Sample ID: VMP-7-13.5-021313**

**Lab ID#: 1302248A-14A**

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 1.4 | 0.54 J | 6.8 | 2.6 J |
| Freon 11 | 1.4 | 0.22 J | 7.8 | 1.3 J |
| Ethanol | 5.5 | 3.6 J | 10 | 6.8 J |

eurofins | Air Toxics

# Summary of Detected Compounds
# EPA METHOD TO-15 GC/MS FULL SCAN

**Client Sample ID: VMP-7-13.5-021313**

**Lab ID#: 1302248A-14A**

| | | | | |
|---|---|---|---|---|
| Acetone | 14 | 10 J | 33 | 24 J |
| 2-Propanol | 5.5 | 1.6 J | 14 | 3.9 J |
| Carbon Disulfide | 5.5 | ~~0.76 J~~ U | 17 | ~~2.4 J~~ U |
| Methylene Chloride | 14 | 0.18 J | 48 | 0.61 J |
| Hexane | 1.4 | 0.33 J | 4.9 | 1.2 J |
| Chloroform | 1.4 | 0.42 J | 6.7 | 2.0 J |
| 2,2,4-Trimethylpentane | 1.4 | 0.15 J | 6.4 | 0.70 J |
| Benzene | 1.4 | 0.63 J | 4.4 | 2.0 J |
| Toluene | 1.4 | ~~0.18 J~~ U | 5.2 | ~~0.66 J~~ U |
| 1,2,4-Trichlorobenzene | 5.5 | ~~0.56 J~~ U | 41 | ~~4.1 J~~ U |
| Isopentane | 5.5 | 0.63 J | 16 | 1.8 J |

eurofins | Air Toxics

**Client Sample ID: VMP-3-10-020613**

**Lab ID#: 1302248A-01A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p021915** | **Date of Collection:** | **2/6/13 3:57:00 PM** |
| **Dil. Factor:** | **2.82** | **Date of Analysis:** | **2/19/13 04:18 PM** |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 1.4 | 0.51 J | 7.0 | 2.5 J |
| Freon 114 | 1.4 | Not Detected | 9.8 | Not Detected |
| Chloromethane | 14 | Not Detected | 29 | Not Detected |
| Vinyl Chloride | 1.4 | Not Detected | 3.6 | Not Detected |
| 1,3-Butadiene | 1.4 | Not Detected | 3.1 | Not Detected |
| Bromomethane | 14 | Not Detected | 55 | Not Detected |
| Chloroethane | 5.6 | Not Detected | 15 | Not Detected |
| Freon 11 | 1.4 | 0.25 J | 7.9 | 1.4 J |
| Ethanol | 5.6 | 1.2 J | 11 | 2.3 J |
| Freon 113 | 1.4 | Not Detected | 11 | Not Detected |
| 1,1-Dichloroethene | 1.4 | Not Detected | 5.6 | Not Detected |
| Acetone | 14 | 4.8 J | 33 | 12 J |
| 2-Propanol | 5.6 | 1.4 J | 14 | 3.5 J |
| Carbon Disulfide | 5.6 | ~~0.81 J~~ U | 18 | ~~2.5 J~~ U |
| 3-Chloropropene | 5.6 | Not Detected | 18 | Not Detected |
| Methylene Chloride | 14 | ~~0.27 J~~ U | 49 | ~~0.94 J~~ U |
| Methyl tert-butyl ether | 1.4 | Not Detected | 5.1 | Not Detected |
| trans-1,2-Dichloroethene | 1.4 | Not Detected | 5.6 | Not Detected |
| Hexane | 1.4 | Not Detected | 5.0 | Not Detected |
| 1,1-Dichloroethane | 1.4 | Not Detected | 5.7 | Not Detected |
| 2-Butanone (Methyl Ethyl Ketone) | 5.6 | Not Detected | 17 | Not Detected |
| cis-1,2-Dichloroethene | 1.4 | Not Detected | 5.6 | Not Detected |
| Tetrahydrofuran | 1.4 | Not Detected | 4.2 | Not Detected |
| Chloroform | 1.4 | Not Detected | 6.9 | Not Detected |
| 1,1,1-Trichloroethane | 1.4 | Not Detected | 7.7 | Not Detected |
| Cyclohexane | 1.4 | Not Detected | 4.8 | Not Detected |
| Carbon Tetrachloride | 1.4 | Not Detected | 8.9 | Not Detected |
| 2,2,4-Trimethylpentane | 1.4 | 0.41 J | 6.6 | 1.9 J |
| Benzene | 1.4 | Not Detected | 4.5 | Not Detected |
| 1,2-Dichloroethane | 1.4 | Not Detected | 5.7 | Not Detected |
| Heptane | 1.4 | Not Detected | 5.8 | Not Detected |
| Trichloroethene | 1.4 | Not Detected | 7.6 | Not Detected |
| 1,2-Dichloropropane | 1.4 | Not Detected | 6.5 | Not Detected |
| 1,4-Dioxane | 5.6 | Not Detected | 20 | Not Detected |
| Bromodichloromethane | 1.4 | Not Detected | 9.4 | Not Detected |
| cis-1,3-Dichloropropene | 1.4 | Not Detected | 6.4 | Not Detected |
| 4-Methyl-2-pentanone | 1.4 | Not Detected | 5.8 | Not Detected |
| Toluene | 1.4 | ~~0.17 J~~ U | 5.3 | ~~0.65 J~~ U |
| trans-1,3-Dichloropropene | 1.4 | Not Detected | 6.4 | Not Detected |
| 1,1,2-Trichloroethane | 1.4 | Not Detected | 7.7 | Not Detected |
| Tetrachloroethene | 1.4 | 1.3 J | 9.6 | 8.8 J |
| 2-Hexanone | 5.6 | Not Detected | 23 | Not Detected |

eurofins | Air Toxics

**Client Sample ID: VMP-3-10-020613**

**Lab ID#: 1302248A-01A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p021915** | **Date of Collection: 2/6/13 3:57:00 PM** | |
| **Dil. Factor:** | **2.82** | **Date of Analysis: 2/19/13 04:18 PM** | |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Dibromochloromethane | 1.4 | Not Detected | 12 | Not Detected |
| 1,2-Dibromoethane (EDB) | 1.4 | Not Detected | 11 | Not Detected |
| Chlorobenzene | 1.4 | Not Detected | 6.5 | Not Detected |
| Ethyl Benzene | 1.4 | Not Detected | 6.1 | Not Detected |
| m,p-Xylene | 1.4 | Not Detected | 6.1 | Not Detected |
| o-Xylene | 1.4 | Not Detected | 6.1 | Not Detected |
| Styrene | 1.4 | Not Detected | 6.0 | Not Detected |
| Bromoform | 1.4 | Not Detected | 14 | Not Detected |
| Cumene | 1.4 | Not Detected | 6.9 | Not Detected |
| 1,1,2,2-Tetrachloroethane | 1.4 | Not Detected | 9.7 | Not Detected |
| Propylbenzene | 1.4 | Not Detected | 6.9 | Not Detected |
| 4-Ethyltoluene | 1.4 | Not Detected | 6.9 | Not Detected |
| 1,3,5-Trimethylbenzene | 1.4 | Not Detected | 6.9 | Not Detected |
| 1,2,4-Trimethylbenzene | 1.4 | Not Detected | 6.9 | Not Detected |
| 1,3-Dichlorobenzene | 1.4 | Not Detected | 8.5 | Not Detected |
| 1,4-Dichlorobenzene | 1.4 | Not Detected | 8.5 | Not Detected |
| alpha-Chlorotoluene | 1.4 | Not Detected | 7.3 | Not Detected |
| 1,2-Dichlorobenzene | 1.4 | Not Detected | 8.5 | Not Detected |
| 1,2,4-Trichlorobenzene | 5.6 | Not Detected | 42 | Not Detected |
| Hexachlorobutadiene | 5.6 | Not Detected | 60 | Not Detected |
| Butane | 5.6 | Not Detected | 13 | Not Detected |
| Isopentane | 5.6 | Not Detected | 17 | Not Detected |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| Toluene-d8 | 97 | 70-130 |
| 1,2-Dichloroethane-d4 | 94 | 70-130 |
| 4-Bromofluorobenzene | 97 | 70-130 |

eurofins | Air Toxics

**Client Sample ID: VMP-3-22-020613**

**Lab ID#: 1302248A-02A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p021916** | **Date of Collection: 2/6/13 3:07:00 PM** | |
| **Dil. Factor:** | **2.89** | **Date of Analysis: 2/19/13 05:32 PM** | |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 1.4 | 0.52 J | 7.1 | 2.6 J |
| Freon 114 | 1.4 | Not Detected | 10 | Not Detected |
| Chloromethane | 14 | Not Detected | 30 | Not Detected |
| Vinyl Chloride | 1.4 | Not Detected | 3.7 | Not Detected |
| 1,3-Butadiene | 1.4 | Not Detected | 3.2 | Not Detected |
| Bromomethane | 14 | Not Detected | 56 | Not Detected |
| Chloroethane | 5.8 | Not Detected | 15 | Not Detected |
| Freon 11 | 1.4 | 0.25 J | 8.1 | 1.4 J |
| Ethanol | 5.8 | 2.2 J | 11 | 4.2 J |
| Freon 113 | 1.4 | Not Detected | 11 | Not Detected |
| 1,1-Dichloroethene | 1.4 | Not Detected | 5.7 | Not Detected |
| Acetone | 14 | 7.9 J | 34 | 19 J |
| 2-Propanol | 5.8 | 0.89 J | 14 | 2.2 J |
| Carbon Disulfide | 5.8 | ~~0.86 J~~ | 18 | ~~2.7 J~~ |
| 3-Chloropropene | 5.8 | Not Detected | 18 | Not Detected |
| Methylene Chloride | 14 | ~~0.23 J~~ | 50 | ~~0.79 J~~ |
| Methyl tert-butyl ether | 1.4 | Not Detected | 5.2 | Not Detected |
| trans-1,2-Dichloroethene | 1.4 | Not Detected | 5.7 | Not Detected |
| Hexane | 1.4 | 0.33 J | 5.1 | 1.2 J |
| 1,1-Dichloroethane | 1.4 | Not Detected | 5.8 | Not Detected |
| 2-Butanone (Methyl Ethyl Ketone) | 5.8 | Not Detected | 17 | Not Detected |
| cis-1,2-Dichloroethene | 1.4 | Not Detected | 5.7 | Not Detected |
| Tetrahydrofuran | 1.4 | 0.37 J | 4.3 | 1.1 J |
| Chloroform | 1.4 | 16 | 7.0 | 78 |
| 1,1,1-Trichloroethane | 1.4 | Not Detected | 7.9 | Not Detected |
| Cyclohexane | 1.4 | Not Detected | 5.0 | Not Detected |
| Carbon Tetrachloride | 1.4 | Not Detected | 9.1 | Not Detected |
| 2,2,4-Trimethylpentane | 1.4 | 0.68 J | 6.8 | 3.2 J |
| Benzene | 1.4 | 16 | 4.6 | 52 |
| 1,2-Dichloroethane | 1.4 | Not Detected | 5.8 | Not Detected |
| Heptane | 1.4 | Not Detected | 5.9 | Not Detected |
| Trichloroethene | 1.4 | Not Detected | 7.8 | Not Detected |
| 1,2-Dichloropropane | 1.4 | Not Detected | 6.7 | Not Detected |
| 1,4-Dioxane | 5.8 | Not Detected | 21 | Not Detected |
| Bromodichloromethane | 1.4 | Not Detected | 9.7 | Not Detected |
| cis-1,3-Dichloropropene | 1.4 | Not Detected | 6.6 | Not Detected |
| 4-Methyl-2-pentanone | 1.4 | Not Detected | 5.9 | Not Detected |
| Toluene | 1.4 | ~~0.15 J~~ | 5.4 | ~~0.56 J~~ |
| trans-1,3-Dichloropropene | 1.4 | Not Detected | 6.6 | Not Detected |
| 1,1,2-Trichloroethane | 1.4 | Not Detected | 7.9 | Not Detected |
| Tetrachloroethene | 1.4 | ~~0.18 J~~ | 9.8 | ~~1.2 J~~ |
| 2-Hexanone | 5.8 | Not Detected | 24 | Not Detected |

eurofins | Air Toxics

**Client Sample ID: VMP-3-22-020613**

**Lab ID#: 1302248A-02A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p021916** | **Date of Collection: 2/6/13 3:07:00 PM** | |
| **Dil. Factor:** | **2.89** | **Date of Analysis: 2/19/13 05:32 PM** | |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Dibromochloromethane | 1.4 | Not Detected | 12 | Not Detected |
| 1,2-Dibromoethane (EDB) | 1.4 | Not Detected | 11 | Not Detected |
| Chlorobenzene | 1.4 | Not Detected | 6.6 | Not Detected |
| Ethyl Benzene | 1.4 | Not Detected | 6.3 | Not Detected |
| m,p-Xylene | 1.4 | Not Detected | 6.3 | Not Detected |
| o-Xylene | 1.4 | Not Detected | 6.3 | Not Detected |
| Styrene | 1.4 | Not Detected | 6.2 | Not Detected |
| Bromoform | 1.4 | Not Detected | 15 | Not Detected |
| Cumene | 1.4 | Not Detected | 7.1 | Not Detected |
| 1,1,2,2-Tetrachloroethane | 1.4 | Not Detected | 9.9 | Not Detected |
| Propylbenzene | 1.4 | Not Detected | 7.1 | Not Detected |
| 4-Ethyltoluene | 1.4 | Not Detected | 7.1 | Not Detected |
| 1,3,5-Trimethylbenzene | 1.4 | Not Detected | 7.1 | Not Detected |
| 1,2,4-Trimethylbenzene | 1.4 | Not Detected | 7.1 | Not Detected |
| 1,3-Dichlorobenzene | 1.4 | Not Detected | 8.7 | Not Detected |
| 1,4-Dichlorobenzene | 1.4 | Not Detected | 8.7 | Not Detected |
| alpha-Chlorotoluene | 1.4 | Not Detected | 7.5 | Not Detected |
| 1,2-Dichlorobenzene | 1.4 | Not Detected | 8.7 | Not Detected |
| 1,2,4-Trichlorobenzene | 5.8 | ~~0.49 J~~ | 43 | ~~3.6 J~~ |
| Hexachlorobutadiene | 5.8 | Not Detected | 62 | Not Detected |
| Butane | 5.8 | 2.5 J | 14 | 6.0 J |
| Isopentane | 5.8 | 3.0 J | 17 | 8.7 J |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| Toluene-d8 | 98 | 70-130 |
| 1,2-Dichloroethane-d4 | 96 | 70-130 |
| 4-Bromofluorobenzene | 98 | 70-130 |

eurofins | Air Toxics

**Client Sample ID: VMP-4-5-020713**

**Lab ID#: 1302248A-03A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p021917** | **Date of Collection:** | **2/7/13 9:38:00 AM** |
| **Dil. Factor:** | **2.47** | **Date of Analysis:** | **2/19/13 06:03 PM** |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 1.2 | 0.45 J | 6.1 | 2.2 J |
| Freon 114 | 1.2 | Not Detected | 8.6 | Not Detected |
| Chloromethane | 12 | Not Detected | 26 | Not Detected |
| Vinyl Chloride | 1.2 | Not Detected | 3.2 | Not Detected |
| 1,3-Butadiene | 1.2 | Not Detected | 2.7 | Not Detected |
| Bromomethane | 12 | Not Detected | 48 | Not Detected |
| Chloroethane | 4.9 | Not Detected | 13 | Not Detected |
| Freon 11 | 1.2 | 0.22 J | 6.9 | 1.2 J |
| Ethanol | 4.9 | 1.8 J | 9.3 | 3.4 J |
| Freon 113 | 1.2 | Not Detected | 9.5 | Not Detected |
| 1,1-Dichloroethene | 1.2 | Not Detected | 4.9 | Not Detected |
| Acetone | 12 | 3.2 J | 29 | 7.6 J |
| 2-Propanol | 4.9 | 1.7 J | 12 | 4.3 J |
| Carbon Disulfide | 4.9 | ~~0.83 J~~ | 15 | ~~2.6 J~~ |
| 3-Chloropropene | 4.9 | Not Detected | 15 | Not Detected |
| Methylene Chloride | 12 | 0.93 J | 43 | 3.2 J |
| Methyl tert-butyl ether | 1.2 | Not Detected | 4.4 | Not Detected |
| trans-1,2-Dichloroethene | 1.2 | Not Detected | 4.9 | Not Detected |
| Hexane | 1.2 | 0.50 J | 4.4 | 1.7 J |
| 1,1-Dichloroethane | 1.2 | Not Detected | 5.0 | Not Detected |
| 2-Butanone (Methyl Ethyl Ketone) | 4.9 | Not Detected | 14 | Not Detected |
| cis-1,2-Dichloroethene | 1.2 | Not Detected | 4.9 | Not Detected |
| Tetrahydrofuran | 1.2 | Not Detected | 3.6 | Not Detected |
| Chloroform | 1.2 | Not Detected | 6.0 | Not Detected |
| 1,1,1-Trichloroethane | 1.2 | Not Detected | 6.7 | Not Detected |
| Cyclohexane | 1.2 | Not Detected | 4.2 | Not Detected |
| Carbon Tetrachloride | 1.2 | Not Detected | 7.8 | Not Detected |
| 2,2,4-Trimethylpentane | 1.2 | 2.7 | 5.8 | 13 |
| Benzene | 1.2 | 1.8 | 3.9 | 5.7 |
| 1,2-Dichloroethane | 1.2 | Not Detected | 5.0 | Not Detected |
| Heptane | 1.2 | Not Detected | 5.1 | Not Detected |
| Trichloroethene | 1.2 | Not Detected | 6.6 | Not Detected |
| 1,2-Dichloropropane | 1.2 | Not Detected | 5.7 | Not Detected |
| 1,4-Dioxane | 4.9 | Not Detected | 18 | Not Detected |
| Bromodichloromethane | 1.2 | Not Detected | 8.3 | Not Detected |
| cis-1,3-Dichloropropene | 1.2 | Not Detected | 5.6 | Not Detected |
| 4-Methyl-2-pentanone | 1.2 | Not Detected | 5.0 | Not Detected |
| Toluene | 1.2 | 0.42 J | 4.6 | 1.6 J |
| trans-1,3-Dichloropropene | 1.2 | Not Detected | 5.6 | Not Detected |
| 1,1,2-Trichloroethane | 1.2 | Not Detected | 6.7 | Not Detected |
| Tetrachloroethene | 1.2 | Not Detected | 8.4 | Not Detected |
| 2-Hexanone | 4.9 | Not Detected | 20 | Not Detected |

eurofins | Air Toxics

**Client Sample ID: VMP-4-5-020713**

**Lab ID#: 1302248A-03A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p021917** | **Date of Collection:** | **2/7/13 9:38:00 AM** |
| **Dil. Factor:** | **2.47** | **Date of Analysis:** | **2/19/13 06:03 PM** |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Dibromochloromethane | 1.2 | Not Detected | 10 | Not Detected |
| 1,2-Dibromoethane (EDB) | 1.2 | Not Detected | 9.5 | Not Detected |
| Chlorobenzene | 1.2 | Not Detected | 5.7 | Not Detected |
| Ethyl Benzene | 1.2 | Not Detected | 5.4 | Not Detected |
| m,p-Xylene | 1.2 | 0.28 J | 5.4 | 1.2 J |
| o-Xylene | 1.2 | Not Detected | 5.4 | Not Detected |
| Styrene | 1.2 | Not Detected | 5.3 | Not Detected |
| Bromoform | 1.2 | Not Detected | 13 | Not Detected |
| Cumene | 1.2 | Not Detected | 6.1 | Not Detected |
| 1,1,2,2-Tetrachloroethane | 1.2 | Not Detected | 8.5 | Not Detected |
| Propylbenzene | 1.2 | ~~0.16 J~~ | 6.1 | ~~0.78 J~~ |
| 4-Ethyltoluene | 1.2 | 0.50 J | 6.1 | 2.4 J |
| 1,3,5-Trimethylbenzene | 1.2 | Not Detected | 6.1 | Not Detected |
| 1,2,4-Trimethylbenzene | 1.2 | ~~0.29 J~~ | 6.1 | ~~1.4 J~~ |
| 1,3-Dichlorobenzene | 1.2 | Not Detected | 7.4 | Not Detected |
| 1,4-Dichlorobenzene | 1.2 | Not Detected | 7.4 | Not Detected |
| alpha-Chlorotoluene | 1.2 | Not Detected | 6.4 | Not Detected |
| 1,2-Dichlorobenzene | 1.2 | Not Detected | 7.4 | Not Detected |
| 1,2,4-Trichlorobenzene | 4.9 | Not Detected | 37 | Not Detected |
| Hexachlorobutadiene | 4.9 | Not Detected | 53 | Not Detected |
| Butane | 4.9 | 2.9 J | 12 | 6.8 J |
| Isopentane | 4.9 | 3.0 J | 14 | 8.8 J |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| Toluene-d8 | 100 | 70-130 |
| 1,2-Dichloroethane-d4 | 96 | 70-130 |
| 4-Bromofluorobenzene | 96 | 70-130 |

eurofins | Air Toxics

**Client Sample ID: VMP-4-12-020713**

**Lab ID#: 1302248A-04A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p021918** | **Date of Collection:** | **2/7/13 10:30:00 AM** |
| **Dil. Factor:** | **2.69** | **Date of Analysis:** | **2/19/13 06:35 PM** |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 1.3 | 0.52 J | 6.6 | 2.6 J |
| Freon 114 | 1.3 | Not Detected | 9.4 | Not Detected |
| Chloromethane | 13 | Not Detected | 28 | Not Detected |
| Vinyl Chloride | 1.3 | Not Detected | 3.4 | Not Detected |
| 1,3-Butadiene | 1.3 | Not Detected | 3.0 | Not Detected |
| Bromomethane | 13 | Not Detected | 52 | Not Detected |
| Chloroethane | 5.4 | Not Detected | 14 | Not Detected |
| Freon 11 | 1.3 | 0.21 J | 7.6 | 1.2 J |
| Ethanol | 5.4 | 1.6 J | 10 | 3.1 J |
| Freon 113 | 1.3 | Not Detected | 10 | Not Detected |
| 1,1-Dichloroethene | 1.3 | Not Detected | 5.3 | Not Detected |
| Acetone | 13 | 3.2 J | 32 | 7.7 J |
| 2-Propanol | 5.4 | 3.0 J | 13 | 7.3 J |
| Carbon Disulfide | 5.4 | ~~0.86 J~~ | 17 | ~~2.7 J~~ |
| 3-Chloropropene | 5.4 | Not Detected | 17 | Not Detected |
| Methylene Chloride | 13 | ~~0.22 J~~ | 47 | ~~0.75 J~~ |
| Methyl tert-butyl ether | 1.3 | Not Detected | 4.8 | Not Detected |
| trans-1,2-Dichloroethene | 1.3 | Not Detected | 5.3 | Not Detected |
| Hexane | 1.3 | Not Detected | 4.7 | Not Detected |
| 1,1-Dichloroethane | 1.3 | Not Detected | 5.4 | Not Detected |
| 2-Butanone (Methyl Ethyl Ketone) | 5.4 | Not Detected | 16 | Not Detected |
| cis-1,2-Dichloroethene | 1.3 | Not Detected | 5.3 | Not Detected |
| Tetrahydrofuran | 1.3 | Not Detected | 4.0 | Not Detected |
| Chloroform | 1.3 | Not Detected | 6.6 | Not Detected |
| 1,1,1-Trichloroethane | 1.3 | Not Detected | 7.3 | Not Detected |
| Cyclohexane | 1.3 | 0.97 J | 4.6 | 3.3 J |
| Carbon Tetrachloride | 1.3 | Not Detected | 8.5 | Not Detected |
| 2,2,4-Trimethylpentane | 1.3 | 10 | 6.3 | 49 |
| Benzene | 1.3 | 2.2 | 4.3 | 6.9 |
| 1,2-Dichloroethane | 1.3 | Not Detected | 5.4 | Not Detected |
| Heptane | 1.3 | Not Detected | 5.5 | Not Detected |
| Trichloroethene | 1.3 | Not Detected | 7.2 | Not Detected |
| 1,2-Dichloropropane | 1.3 | Not Detected | 6.2 | Not Detected |
| 1,4-Dioxane | 5.4 | Not Detected | 19 | Not Detected |
| Bromodichloromethane | 1.3 | Not Detected | 9.0 | Not Detected |
| cis-1,3-Dichloropropene | 1.3 | Not Detected | 6.1 | Not Detected |
| 4-Methyl-2-pentanone | 1.3 | Not Detected | 5.5 | Not Detected |
| Toluene | 1.3 | ~~0.18 J~~ | 5.1 | ~~0.68 J~~ |
| trans-1,3-Dichloropropene | 1.3 | Not Detected | 6.1 | Not Detected |
| 1,1,2-Trichloroethane | 1.3 | Not Detected | 7.3 | Not Detected |
| Tetrachloroethene | 1.3 | Not Detected | 9.1 | Not Detected |
| 2-Hexanone | 5.4 | Not Detected | 22 | Not Detected |

eurofins | Air Toxics

**Client Sample ID: VMP-4-12-020713**

**Lab ID#: 1302248A-04A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p021918** | **Date of Collection:** | **2/7/13 10:30:00 AM** |
| **Dil. Factor:** | **2.69** | **Date of Analysis:** | **2/19/13 06:35 PM** |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Dibromochloromethane | 1.3 | Not Detected | 11 | Not Detected |
| 1,2-Dibromoethane (EDB) | 1.3 | Not Detected | 10 | Not Detected |
| Chlorobenzene | 1.3 | Not Detected | 6.2 | Not Detected |
| Ethyl Benzene | 1.3 | Not Detected | 5.8 | Not Detected |
| m,p-Xylene | 1.3 | Not Detected | 5.8 | Not Detected |
| o-Xylene | 1.3 | Not Detected | 5.8 | Not Detected |
| Styrene | 1.3 | Not Detected | 5.7 | Not Detected |
| Bromoform | 1.3 | Not Detected | 14 | Not Detected |
| Cumene | 1.3 | Not Detected | 6.6 | Not Detected |
| 1,1,2,2-Tetrachloroethane | 1.3 | Not Detected | 9.2 | Not Detected |
| Propylbenzene | 1.3 | ~~0.30 J~~ U | 6.6 | ~~1.5 J~~ U |
| 4-Ethyltoluene | 1.3 | 1.4 | 6.6 | 7.0 |
| 1,3,5-Trimethylbenzene | 1.3 | ~~0.46 J~~ U | 6.6 | ~~2.2 J~~ U |
| 1,2,4-Trimethylbenzene | 1.3 | 1.5 | 6.6 | 7.3 |
| 1,3-Dichlorobenzene | 1.3 | Not Detected | 8.1 | Not Detected |
| 1,4-Dichlorobenzene | 1.3 | Not Detected | 8.1 | Not Detected |
| alpha-Chlorotoluene | 1.3 | Not Detected | 7.0 | Not Detected |
| 1,2-Dichlorobenzene | 1.3 | Not Detected | 8.1 | Not Detected |
| 1,2,4-Trichlorobenzene | 5.4 | Not Detected | 40 | Not Detected |
| Hexachlorobutadiene | 5.4 | Not Detected | 57 | Not Detected |
| Butane | 5.4 | 11 | 13 | 25 |
| Isopentane | 5.4 | 15 | 16 | 44 |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| Toluene-d8 | 99 | 70-130 |
| 1,2-Dichloroethane-d4 | 98 | 70-130 |
| 4-Bromofluorobenzene | 94 | 70-130 |

eurofins | Air Toxics

**Client Sample ID: VMP-4-12-020713-DUP**

**Lab ID#: 1302248A-05A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p021919** | **Date of Collection:** | **2/7/13 10:30:00 AM** |
| **Dil. Factor:** | **2.76** | **Date of Analysis:** | **2/19/13 07:22 PM** |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 1.4 | 0.50 J | 6.8 | 2.5 J |
| Freon 114 | 1.4 | Not Detected | 9.6 | Not Detected |
| Chloromethane | 14 | Not Detected | 28 | Not Detected |
| Vinyl Chloride | 1.4 | Not Detected | 3.5 | Not Detected |
| 1,3-Butadiene | 1.4 | Not Detected | 3.0 | Not Detected |
| Bromomethane | 14 | Not Detected | 54 | Not Detected |
| Chloroethane | 5.5 | Not Detected | 14 | Not Detected |
| Freon 11 | 1.4 | 0.34 J | 7.8 | 1.9 J |
| Ethanol | 5.5 | 2.0 J | 10 | 3.7 J |
| Freon 113 | 1.4 | Not Detected | 10 | Not Detected |
| 1,1-Dichloroethene | 1.4 | Not Detected | 5.5 | Not Detected |
| Acetone | 14 | 5.2 J | 33 | 12 J |
| 2-Propanol | 5.5 | 2.2 J | 14 | 5.4 J |
| Carbon Disulfide | 5.5 | ~~0.86 J~~ U | 17 | ~~2.7 J~~ U |
| 3-Chloropropene | 5.5 | Not Detected | 17 | Not Detected |
| Methylene Chloride | 14 | Not Detected | 48 | Not Detected |
| Methyl tert-butyl ether | 1.4 | Not Detected | 5.0 | Not Detected |
| trans-1,2-Dichloroethene | 1.4 | Not Detected | 5.5 | Not Detected |
| Hexane | 1.4 | 0.76 J | 4.9 | 2.7 J |
| 1,1-Dichloroethane | 1.4 | Not Detected | 5.6 | Not Detected |
| 2-Butanone (Methyl Ethyl Ketone) | 5.5 | Not Detected | 16 | Not Detected |
| cis-1,2-Dichloroethene | 1.4 | Not Detected | 5.5 | Not Detected |
| Tetrahydrofuran | 1.4 | Not Detected | 4.1 | Not Detected |
| Chloroform | 1.4 | Not Detected | 6.7 | Not Detected |
| 1,1,1-Trichloroethane | 1.4 | Not Detected | 7.5 | Not Detected |
| Cyclohexane | 1.4 | Not Detected | 4.8 | Not Detected |
| Carbon Tetrachloride | 1.4 | Not Detected | 8.7 | Not Detected |
| 2,2,4-Trimethylpentane | 1.4 | 11 | 6.4 | 51 |
| Benzene | 1.4 | 4.2 | 4.4 | 13 |
| 1,2-Dichloroethane | 1.4 | Not Detected | 5.6 | Not Detected |
| Heptane | 1.4 | Not Detected | 5.6 | Not Detected |
| Trichloroethene | 1.4 | Not Detected | 7.4 | Not Detected |
| 1,2-Dichloropropane | 1.4 | Not Detected | 6.4 | Not Detected |
| 1,4-Dioxane | 5.5 | Not Detected | 20 | Not Detected |
| Bromodichloromethane | 1.4 | Not Detected | 9.2 | Not Detected |
| cis-1,3-Dichloropropene | 1.4 | Not Detected | 6.3 | Not Detected |
| 4-Methyl-2-pentanone | 1.4 | Not Detected | 5.6 | Not Detected |
| Toluene | 1.4 | ~~0.13 J~~ U | 5.2 | ~~0.48 J~~ U |
| trans-1,3-Dichloropropene | 1.4 | Not Detected | 6.3 | Not Detected |
| 1,1,2-Trichloroethane | 1.4 | Not Detected | 7.5 | Not Detected |
| Tetrachloroethene | 1.4 | Not Detected | 9.4 | Not Detected |
| 2-Hexanone | 5.5 | Not Detected | 23 | Not Detected |

eurofins | Air Toxics

**Client Sample ID: VMP-4-12-020713-DUP**

**Lab ID#: 1302248A-05A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p021919** | **Date of Collection:** | **2/7/13 10:30:00 AM** |
| **Dil. Factor:** | **2.76** | **Date of Analysis:** | **2/19/13 07:22 PM** |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Dibromochloromethane | 1.4 | Not Detected | 12 | Not Detected |
| 1,2-Dibromoethane (EDB) | 1.4 | Not Detected | 11 | Not Detected |
| Chlorobenzene | 1.4 | Not Detected | 6.4 | Not Detected |
| Ethyl Benzene | 1.4 | Not Detected | 6.0 | Not Detected |
| m,p-Xylene | 1.4 | Not Detected | 6.0 | Not Detected |
| o-Xylene | 1.4 | Not Detected | 6.0 | Not Detected |
| Styrene | 1.4 | Not Detected | 5.9 | Not Detected |
| Bromoform | 1.4 | Not Detected | 14 | Not Detected |
| Cumene | 1.4 | Not Detected | 6.8 | Not Detected |
| 1,1,2,2-Tetrachloroethane | 1.4 | Not Detected | 9.5 | Not Detected |
| Propylbenzene | 1.4 | Not Detected | 6.8 | Not Detected |
| 4-Ethyltoluene | 1.4 | ~~0.094 J~~ U | 6.8 | ~~0.46 J~~ U |
| 1,3,5-Trimethylbenzene | 1.4 | Not Detected | 6.8 | Not Detected |
| 1,2,4-Trimethylbenzene | 1.4 | Not Detected | 6.8 | Not Detected |
| 1,3-Dichlorobenzene | 1.4 | Not Detected | 8.3 | Not Detected |
| 1,4-Dichlorobenzene | 1.4 | Not Detected | 8.3 | Not Detected |
| alpha-Chlorotoluene | 1.4 | Not Detected | 7.1 | Not Detected |
| 1,2-Dichlorobenzene | 1.4 | Not Detected | 8.3 | Not Detected |
| 1,2,4-Trichlorobenzene | 5.5 | Not Detected | 41 | Not Detected |
| Hexachlorobutadiene | 5.5 | Not Detected | 59 | Not Detected |
| Butane | 5.5 | 12 | 13 | 30 |
| Isopentane | 5.5 | 15 | 16 | 45 |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| Toluene-d8 | 100 | 70-130 |
| 1,2-Dichloroethane-d4 | 97 | 70-130 |
| 4-Bromofluorobenzene | 93 | 70-130 |

eurofins | Air Toxics

* USE THIS RESULT ONLY. ALL OTHER RESULTS REPORTED IN 2.47x DILUTION ANALYSIS.

**Client Sample ID: VMP-6-5-021213**
**Lab ID#: 1302248A-06A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p021921** | **Date of Collection: 2/12/13 1:38:00 PM** | |
| **Dil. Factor:** | **4.94** | **Date of Analysis: 2/19/13 08:34 PM** | |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 2.5 | 0.54 J | 12 | 2.7 J |
| Freon 114 | 2.5 | Not Detected | 17 | Not Detected |
| Chloromethane | 25 | Not Detected | 51 | Not Detected |
| Vinyl Chloride | 2.5 | Not Detected | 6.3 | Not Detected |
| 1,3-Butadiene | 2.5 | Not Detected | 5.5 | Not Detected |
| Bromomethane | 25 | Not Detected | 96 | Not Detected |
| Chloroethane | 9.9 | Not Detected | 26 | Not Detected |
| Freon 11 | 2.5 | Not Detected | 14 | Not Detected |
| Ethanol | 9.9 | 2.0 J | 19 | 3.8 J |
| Freon 113 | 2.5 | Not Detected | 19 | Not Detected |
| 1,1-Dichloroethene | 2.5 | Not Detected | 9.8 | Not Detected |
| * Acetone | 25 | 770 | 59 | 1800 |
| 2-Propanol | 9.9 | 3.5 J | 24 | 8.6 J |
| Carbon Disulfide | 9.9 | ~~1.4 J~~ V | 31 | ~~4.4 J~~ U |
| 3-Chloropropene | 9.9 | Not Detected | 31 | Not Detected |
| Methylene Chloride | 25 | Not Detected | 86 | Not Detected |
| Methyl tert-butyl ether | 2.5 | Not Detected | 8.9 | Not Detected |
| trans-1,2-Dichloroethene | 2.5 | Not Detected | 9.8 | Not Detected |
| Hexane | 2.5 | 4.3 | 8.7 | 15 |
| 1,1-Dichloroethane | 2.5 | Not Detected | 10 | Not Detected |
| 2-Butanone (Methyl Ethyl Ketone) | 9.9 | Not Detected | 29 | Not Detected |
| cis-1,2-Dichloroethene | 2.5 | Not Detected | 9.8 | Not Detected |
| Tetrahydrofuran | 2.5 | Not Detected | 7.3 | Not Detected |
| Chloroform | 2.5 | Not Detected | 12 | Not Detected |
| 1,1,1-Trichloroethane | 2.5 | Not Detected | 13 | Not Detected |
| Cyclohexane | 2.5 | Not Detected | 8.5 | Not Detected |
| Carbon Tetrachloride | 2.5 | Not Detected | 16 | Not Detected |
| 2,2,4-Trimethylpentane | 2.5 | 13 | 12 | 60 |
| Benzene | 2.5 | 12 | 7.9 | 39 |
| 1,2-Dichloroethane | 2.5 | Not Detected | 10 | Not Detected |
| Heptane | 2.5 | Not Detected | 10 | Not Detected |
| Trichloroethene | 2.5 | Not Detected | 13 | Not Detected |
| 1,2-Dichloropropane | 2.5 | Not Detected | 11 | Not Detected |
| 1,4-Dioxane | 9.9 | Not Detected | 36 | Not Detected |
| Bromodichloromethane | 2.5 | Not Detected | 16 | Not Detected |
| cis-1,3-Dichloropropene | 2.5 | Not Detected | 11 | Not Detected |
| 4-Methyl-2-pentanone | 2.5 | 0.60 J | 10 | 2.4 J |
| Toluene | 2.5 | ~~0.21 J~~ U | 9.3 | ~~0.80 J~~ U |
| trans-1,3-Dichloropropene | 2.5 | Not Detected | 11 | Not Detected |
| 1,1,2-Trichloroethane | 2.5 | Not Detected | 13 | Not Detected |
| Tetrachloroethene | 2.5 | Not Detected | 17 | Not Detected |
| 2-Hexanone | 9.9 | Not Detected | 40 | Not Detected |

eurofins | Air Toxics

**Client Sample ID: VMP-6-5-021213**

**Lab ID#: 1302248A-06A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p021921** | **Date of Collection: 2/12/13 1:38:00 PM** | |
| **Dil. Factor:** | **4.94** | **Date of Analysis: 2/19/13 08:34 PM** | |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Dibromochloromethane | 2.5 | Not Detected | 21 | Not Detected |
| 1,2-Dibromoethane (EDB) | 2.5 | Not Detected | 19 | Not Detected |
| Chlorobenzene | 2.5 | Not Detected | 11 | Not Detected |
| Ethyl Benzene | 2.5 | Not Detected | 11 | Not Detected |
| m,p-Xylene | 2.5 | Not Detected | 11 | Not Detected |
| o-Xylene | 2.5 | Not Detected | 11 | Not Detected |
| Styrene | 2.5 | Not Detected | 10 | Not Detected |
| Bromoform | 2.5 | Not Detected | 26 | Not Detected |
| Cumene | 2.5 | Not Detected | 12 | Not Detected |
| 1,1,2,2-Tetrachloroethane | 2.5 | Not Detected | 17 | Not Detected |
| Propylbenzene | 2.5 | Not Detected | 12 | Not Detected |
| 4-Ethyltoluene | 2.5 | Not Detected | 12 | Not Detected |
| 1,3,5-Trimethylbenzene | 2.5 | Not Detected | 12 | Not Detected |
| 1,2,4-Trimethylbenzene | 2.5 | Not Detected | 12 | Not Detected |
| 1,3-Dichlorobenzene | 2.5 | Not Detected | 15 | Not Detected |
| 1,4-Dichlorobenzene | 2.5 | Not Detected | 15 | Not Detected |
| alpha-Chlorotoluene | 2.5 | Not Detected | 13 | Not Detected |
| 1,2-Dichlorobenzene | 2.5 | Not Detected | 15 | Not Detected |
| 1,2,4-Trichlorobenzene | 9.9 | Not Detected | 73 | Not Detected |
| Hexachlorobutadiene | 9.9 | Not Detected | 100 | Not Detected |
| Butane | 9.9 | 49 | 23 | 120 |
| Isopentane | 9.9 | 46 | 29 | 140 |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| Toluene-d8 | 98 | 70-130 |
| 1,2-Dichloroethane-d4 | 100 | 70-130 |
| 4-Bromofluorobenzene | 98 | 70-130 |

eurofins | Air Toxics

* DO NOT USE THIS RESULT. USE ALL OTHER DATA.

**Client Sample ID: VMP-6-5-021213**
**Lab ID#: 1302248A-06B**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p021920** | **Date of Collection:** | **2/12/13 1:38:00 PM** |
| **Dil. Factor:** | **2.47** | **Date of Analysis:** | **2/19/13 07:44 PM** |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 1.2 | 0.52 J | 6.1 | 2.6 J |
| Freon 114 | 1.2 | Not Detected | 8.6 | Not Detected |
| Chloromethane | 12 | Not Detected | 26 | Not Detected |
| Vinyl Chloride | 1.2 | Not Detected | 3.2 | Not Detected |
| 1,3-Butadiene | 1.2 | Not Detected | 2.7 | Not Detected |
| Bromomethane | 12 | Not Detected | 48 | Not Detected |
| Chloroethane | 4.9 | Not Detected | 13 | Not Detected |
| Freon 11 | 1.2 | 0.23 J | 6.9 | 1.3 J |
| Ethanol | 4.9 | 2.1 J | 9.3 | 4.0 J |
| Freon 113 | 1.2 | Not Detected | 9.5 | Not Detected |
| 1,1-Dichloroethene | 1.2 | Not Detected | 4.9 | Not Detected |
| ~~Acetone~~ * | ~~12~~ | ~~680 E~~ | ~~29~~ | ~~1600 E~~ |
| 2-Propanol | 4.9 | 3.0 J | 12 | 7.3 J |
| Carbon Disulfide | 4.9 | ~~0.74 J~~ U | 15 | ~~2.3 J~~ U |
| 3-Chloropropene | 4.9 | Not Detected | 15 | Not Detected |
| Methylene Chloride | 12 | Not Detected | 43 | Not Detected |
| Methyl tert-butyl ether | 1.2 | Not Detected | 4.4 | Not Detected |
| trans-1,2-Dichloroethene | 1.2 | Not Detected | 4.9 | Not Detected |
| Hexane | 1.2 | 4.2 | 4.4 | 15 |
| 1,1-Dichloroethane | 1.2 | Not Detected | 5.0 | Not Detected |
| 2-Butanone (Methyl Ethyl Ketone) | 4.9 | Not Detected | 14 | Not Detected |
| cis-1,2-Dichloroethene | 1.2 | Not Detected | 4.9 | Not Detected |
| Tetrahydrofuran | 1.2 | Not Detected | 3.6 | Not Detected |
| Chloroform | 1.2 | Not Detected | 6.0 | Not Detected |
| 1,1,1-Trichloroethane | 1.2 | Not Detected | 6.7 | Not Detected |
| Cyclohexane | 1.2 | 0.55 J | 4.2 | 1.9 J |
| Carbon Tetrachloride | 1.2 | Not Detected | 7.8 | Not Detected |
| 2,2,4-Trimethylpentane | 1.2 | 12 | 5.8 | 58 |
| Benzene | 1.2 | 12 | 3.9 | 37 |
| 1,2-Dichloroethane | 1.2 | Not Detected | 5.0 | Not Detected |
| Heptane | 1.2 | 0.46 J | 5.1 | 1.9 J |
| Trichloroethene | 1.2 | Not Detected | 6.6 | Not Detected |
| 1,2-Dichloropropane | 1.2 | Not Detected | 5.7 | Not Detected |
| 1,4-Dioxane | 4.9 | Not Detected | 18 | Not Detected |
| Bromodichloromethane | 1.2 | Not Detected | 8.3 | Not Detected |
| cis-1,3-Dichloropropene | 1.2 | Not Detected | 5.6 | Not Detected |
| 4-Methyl-2-pentanone | 1.2 | ~~0.44 J~~ OK (HF) | 5.0 | 1.8 J |
| Toluene | 1.2 | ~~0.13 J~~ U | 4.6 | ~~0.49~~ J U |
| trans-1,3-Dichloropropene | 1.2 | Not Detected | 5.6 | Not Detected |
| 1,1,2-Trichloroethane | 1.2 | Not Detected | 6.7 | Not Detected |
| Tetrachloroethene | 1.2 | Not Detected | 8.4 | Not Detected |
| 2-Hexanone | 4.9 | Not Detected | 20 | Not Detected |

eurofins | Air Toxics

**Client Sample ID: VMP-6-5-021213**

**Lab ID#: 1302248A-06B**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p021920** | **Date of Collection: 2/12/13 1:38:00 PM** | |
| **Dil. Factor:** | **2.47** | **Date of Analysis: 2/19/13 07:44 PM** | |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Dibromochloromethane | 1.2 | Not Detected | 10 | Not Detected |
| 1,2-Dibromoethane (EDB) | 1.2 | Not Detected | 9.5 | Not Detected |
| Chlorobenzene | 1.2 | Not Detected | 5.7 | Not Detected |
| Ethyl Benzene | 1.2 | Not Detected | 5.4 | Not Detected |
| m,p-Xylene | 1.2 | Not Detected | 5.4 | Not Detected |
| o-Xylene | 1.2 | Not Detected | 5.4 | Not Detected |
| Styrene | 1.2 | Not Detected | 5.3 | Not Detected |
| Bromoform | 1.2 | Not Detected | 13 | Not Detected |
| Cumene | 1.2 | Not Detected | 6.1 | Not Detected |
| 1,1,2,2-Tetrachloroethane | 1.2 | Not Detected | 8.5 | Not Detected |
| Propylbenzene | 1.2 | Not Detected | 6.1 | Not Detected |
| 4-Ethyltoluene | 1.2 | ~~0.15 J~~ | 6.1 | ~~0.74 J~~ |
| 1,3,5-Trimethylbenzene | 1.2 | Not Detected | 6.1 | Not Detected |
| 1,2,4-Trimethylbenzene | 1.2 | Not Detected | 6.1 | Not Detected |
| 1,3-Dichlorobenzene | 1.2 | Not Detected | 7.4 | Not Detected |
| 1,4-Dichlorobenzene | 1.2 | Not Detected | 7.4 | Not Detected |
| alpha-Chlorotoluene | 1.2 | Not Detected | 6.4 | Not Detected |
| 1,2-Dichlorobenzene | 1.2 | Not Detected | 7.4 | Not Detected |
| 1,2,4-Trichlorobenzene | 4.9 | Not Detected | 37 | Not Detected |
| Hexachlorobutadiene | 4.9 | Not Detected | 53 | Not Detected |
| Butane | 4.9 | 46 | 12 | 110 |
| Isopentane | 4.9 | 42 | 14 | 120 |

J = Estimated value.
E = Exceeds instrument calibration range.
**Container Type: 1 Liter Summa Canister**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| Toluene-d8 | 99 | 70-130 |
| 1,2-Dichloroethane-d4 | 97 | 70-130 |
| 4-Bromofluorobenzene | 100 | 70-130 |

eurofins | Air Toxics

**Client Sample ID: VMP-20-5-020713**

**Lab ID#: 1302248A-07A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p021922** | **Date of Collection:** | **2/7/13 3:35:00 PM** |
| **Dil. Factor:** | **2.47** | **Date of Analysis:** | **2/19/13 09:18 PM** |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 1.2 | 0.56 J | 6.1 | 2.8 J |
| Freon 114 | 1.2 | Not Detected | 8.6 | Not Detected |
| Chloromethane | 12 | Not Detected | 26 | Not Detected |
| Vinyl Chloride | 1.2 | Not Detected | 3.2 | Not Detected |
| 1,3-Butadiene | 1.2 | Not Detected | 2.7 | Not Detected |
| Bromomethane | 12 | Not Detected | 48 | Not Detected |
| Chloroethane | 4.9 | Not Detected | 13 | Not Detected |
| Freon 11 | 1.2 | 2.2 | 6.9 | 12 |
| Ethanol | 4.9 | 3.4 J | 9.3 | 6.4 J |
| Freon 113 | 1.2 | Not Detected | 9.5 | Not Detected |
| 1,1-Dichloroethene | 1.2 | Not Detected | 4.9 | Not Detected |
| Acetone | 12 | 10 J | 29 | 24 J |
| 2-Propanol | 4.9 | 2.3 J | 12 | 5.7 J |
| Carbon Disulfide | 4.9 | ~~0.88 J~~ | 15 | ~~2.8 J~~ |
| 3-Chloropropene | 4.9 | Not Detected | 15 | Not Detected |
| Methylene Chloride | 12 | ~~0.18 J~~ | 43 | ~~0.61 J~~ |
| Methyl tert-butyl ether | 1.2 | Not Detected | 4.4 | Not Detected |
| trans-1,2-Dichloroethene | 1.2 | Not Detected | 4.9 | Not Detected |
| Hexane | 1.2 | 7.6 | 4.4 | 27 |
| 1,1-Dichloroethane | 1.2 | Not Detected | 5.0 | Not Detected |
| 2-Butanone (Methyl Ethyl Ketone) | 4.9 | 0.94 J | 14 | 2.8 J |
| cis-1,2-Dichloroethene | 1.2 | Not Detected | 4.9 | Not Detected |
| Tetrahydrofuran | 1.2 | Not Detected | 3.6 | Not Detected |
| Chloroform | 1.2 | Not Detected | 6.0 | Not Detected |
| 1,1,1-Trichloroethane | 1.2 | Not Detected | 6.7 | Not Detected |
| Cyclohexane | 1.2 | Not Detected | 4.2 | Not Detected |
| Carbon Tetrachloride | 1.2 | Not Detected | 7.8 | Not Detected |
| 2,2,4-Trimethylpentane | 1.2 | 25 | 5.8 | 120 |
| Benzene | 1.2 | 11 | 3.9 | 35 |
| 1,2-Dichloroethane | 1.2 | Not Detected | 5.0 | Not Detected |
| Heptane | 1.2 | 0.49 J | 5.1 | 2.0 J |
| Trichloroethene | 1.2 | Not Detected | 6.6 | Not Detected |
| 1,2-Dichloropropane | 1.2 | Not Detected | 5.7 | Not Detected |
| 1,4-Dioxane | 4.9 | Not Detected | 18 | Not Detected |
| Bromodichloromethane | 1.2 | Not Detected | 8.3 | Not Detected |
| cis-1,3-Dichloropropene | 1.2 | Not Detected | 5.6 | Not Detected |
| 4-Methyl-2-pentanone | 1.2 | Not Detected | 5.0 | Not Detected |
| Toluene | 1.2 | ~~0.22 J~~ | 4.6 | ~~0.81 J~~ |
| trans-1,3-Dichloropropene | 1.2 | Not Detected | 5.6 | Not Detected |
| 1,1,2-Trichloroethane | 1.2 | Not Detected | 6.7 | Not Detected |
| Tetrachloroethene | 1.2 | ~~0.13 J~~ | 8.4 | ~~0.89 J~~ |
| 2-Hexanone | 4.9 | Not Detected | 20 | Not Detected |

eurofins | Air Toxics

**Client Sample ID: VMP-20-5-020713**

**Lab ID#: 1302248A-07A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p021922** | **Date of Collection: 2/7/13 3:35:00 PM** | |
| **Dil. Factor:** | **2.47** | **Date of Analysis: 2/19/13 09:18 PM** | |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Dibromochloromethane | 1.2 | Not Detected | 10 | Not Detected |
| 1,2-Dibromoethane (EDB) | 1.2 | Not Detected | 9.5 | Not Detected |
| Chlorobenzene | 1.2 | Not Detected | 5.7 | Not Detected |
| Ethyl Benzene | 1.2 | 0.47 J | 5.4 | 2.0 J |
| m,p-Xylene | 1.2 | 0.98 J | 5.4 | 4.2 J |
| o-Xylene | 1.2 | Not Detected | 5.4 | Not Detected |
| Styrene | 1.2 | Not Detected | 5.3 | Not Detected |
| Bromoform | 1.2 | Not Detected | 13 | Not Detected |
| Cumene | 1.2 | 0.44 J | 6.1 | 2.1 J |
| 1,1,2,2-Tetrachloroethane | 1.2 | Not Detected | 8.5 | Not Detected |
| Propylbenzene | 1.2 | 1.2 | 6.1 | 6.0 |
| 4-Ethyltoluene | 1.2 | 3.5 | 6.1 | 17 |
| 1,3,5-Trimethylbenzene | 1.2 | 1.8 | 6.1 | 8.8 |
| 1,2,4-Trimethylbenzene | 1.2 | 12 | 6.1 | 60 |
| 1,3-Dichlorobenzene | 1.2 | Not Detected | 7.4 | Not Detected |
| 1,4-Dichlorobenzene | 1.2 | Not Detected | 7.4 | Not Detected |
| alpha-Chlorotoluene | 1.2 | Not Detected | 6.4 | Not Detected |
| 1,2-Dichlorobenzene | 1.2 | Not Detected | 7.4 | Not Detected |
| 1,2,4-Trichlorobenzene | 4.9 | Not Detected | 37 | Not Detected |
| Hexachlorobutadiene | 4.9 | Not Detected | 53 | Not Detected |
| Butane | 4.9 | 220 | 12 | 510 |
| Isopentane | 4.9 | 180 | 14 | 530 |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| Toluene-d8 | 97 | 70-130 |
| 1,2-Dichloroethane-d4 | 98 | 70-130 |
| 4-Bromofluorobenzene | 104 | 70-130 |

eurofins | Air Toxics

**Client Sample ID: VMP-21-5-020613**

**Lab ID#: 1302248A-08A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p021923** | **Date of Collection:** | **2/6/13 2:50:00 PM** |
| **Dil. Factor:** | **2.82** | **Date of Analysis:** | **2/19/13 10:13 PM** |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 1.4 | 0.58 J | 7.0 | 2.9 J |
| Freon 114 | 1.4 | Not Detected | 9.8 | Not Detected |
| Chloromethane | 14 | Not Detected | 29 | Not Detected |
| Vinyl Chloride | 1.4 | Not Detected | 3.6 | Not Detected |
| 1,3-Butadiene | 1.4 | Not Detected | 3.1 | Not Detected |
| Bromomethane | 14 | Not Detected | 55 | Not Detected |
| Chloroethane | 5.6 | Not Detected | 15 | Not Detected |
| Freon 11 | 1.4 | 0.25 J | 7.9 | 1.4 J |
| Ethanol | 5.6 | 3.3 J | 11 | 6.2 J |
| Freon 113 | 1.4 | Not Detected | 11 | Not Detected |
| 1,1-Dichloroethene | 1.4 | Not Detected | 5.6 | Not Detected |
| Acetone | 14 | 5.0 J | 33 | 12 J |
| 2-Propanol | 5.6 | 1.4 J | 14 | 3.3 J |
| Carbon Disulfide | 5.6 | ~~0.92 J~~ U | 18 | ~~2.8 J~~ U |
| 3-Chloropropene | 5.6 | Not Detected | 18 | Not Detected |
| Methylene Chloride | 14 | Not Detected | 49 | Not Detected |
| Methyl tert-butyl ether | 1.4 | Not Detected | 5.1 | Not Detected |
| trans-1,2-Dichloroethene | 1.4 | Not Detected | 5.6 | Not Detected |
| Hexane | 1.4 | Not Detected | 5.0 | Not Detected |
| 1,1-Dichloroethane | 1.4 | Not Detected | 5.7 | Not Detected |
| 2-Butanone (Methyl Ethyl Ketone) | 5.6 | 0.91 J | 17 | 2.7 J |
| cis-1,2-Dichloroethene | 1.4 | Not Detected | 5.6 | Not Detected |
| Tetrahydrofuran | 1.4 | Not Detected | 4.2 | Not Detected |
| Chloroform | 1.4 | Not Detected | 6.9 | Not Detected |
| 1,1,1-Trichloroethane | 1.4 | Not Detected | 7.7 | Not Detected |
| Cyclohexane | 1.4 | Not Detected | 4.8 | Not Detected |
| Carbon Tetrachloride | 1.4 | Not Detected | 8.9 | Not Detected |
| 2,2,4-Trimethylpentane | 1.4 | 0.25 J | 6.6 | 1.2 J |
| Benzene | 1.4 | 0.62 J | 4.5 | 2.0 J |
| 1,2-Dichloroethane | 1.4 | Not Detected | 5.7 | Not Detected |
| Heptane | 1.4 | Not Detected | 5.8 | Not Detected |
| Trichloroethene | 1.4 | Not Detected | 7.6 | Not Detected |
| 1,2-Dichloropropane | 1.4 | Not Detected | 6.5 | Not Detected |
| 1,4-Dioxane | 5.6 | Not Detected | 20 | Not Detected |
| Bromodichloromethane | 1.4 | Not Detected | 9.4 | Not Detected |
| cis-1,3-Dichloropropene | 1.4 | Not Detected | 6.4 | Not Detected |
| 4-Methyl-2-pentanone | 1.4 | Not Detected | 5.8 | Not Detected |
| Toluene | 1.4 | ~~0.12 J~~ U | 5.3 | ~~0.44 J~~ U |
| trans-1,3-Dichloropropene | 1.4 | Not Detected | 6.4 | Not Detected |
| 1,1,2-Trichloroethane | 1.4 | Not Detected | 7.7 | Not Detected |
| Tetrachloroethene | 1.4 | ~~0.25 J~~ U | 9.6 | ~~1.7 J~~ U |
| 2-Hexanone | 5.6 | Not Detected | 23 | Not Detected |

eurofins | Air Toxics

**Client Sample ID: VMP-21-5-020613**

**Lab ID#: 1302248A-08A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | p021923 | **Date of Collection:** | 2/6/13 2:50:00 PM |
| **Dil. Factor:** | 2.82 | **Date of Analysis:** | 2/19/13 10:13 PM |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Dibromochloromethane | 1.4 | Not Detected | 12 | Not Detected |
| 1,2-Dibromoethane (EDB) | 1.4 | Not Detected | 11 | Not Detected |
| Chlorobenzene | 1.4 | Not Detected | 6.5 | Not Detected |
| Ethyl Benzene | 1.4 | Not Detected | 6.1 | Not Detected |
| m,p-Xylene | 1.4 | Not Detected | 6.1 | Not Detected |
| o-Xylene | 1.4 | Not Detected | 6.1 | Not Detected |
| Styrene | 1.4 | Not Detected | 6.0 | Not Detected |
| Bromoform | 1.4 | Not Detected | 14 | Not Detected |
| Cumene | 1.4 | Not Detected | 6.9 | Not Detected |
| 1,1,2,2-Tetrachloroethane | 1.4 | Not Detected | 9.7 | Not Detected |
| Propylbenzene | 1.4 | Not Detected | 6.9 | Not Detected |
| 4-Ethyltoluene | 1.4 | Not Detected | 6.9 | Not Detected |
| 1,3,5-Trimethylbenzene | 1.4 | Not Detected | 6.9 | Not Detected |
| 1,2,4-Trimethylbenzene | 1.4 | Not Detected | 6.9 | Not Detected |
| 1,3-Dichlorobenzene | 1.4 | Not Detected | 8.5 | Not Detected |
| 1,4-Dichlorobenzene | 1.4 | Not Detected | 8.5 | Not Detected |
| alpha-Chlorotoluene | 1.4 | Not Detected | 7.3 | Not Detected |
| 1,2-Dichlorobenzene | 1.4 | Not Detected | 8.5 | Not Detected |
| 1,2,4-Trichlorobenzene | 5.6 | ~~0.37 J~~ | 42 | ~~2.8 J~~ |
| Hexachlorobutadiene | 5.6 | Not Detected | 60 | Not Detected |
| Butane | 5.6 | Not Detected | 13 | Not Detected |
| Isopentane | 5.6 | Not Detected | 17 | Not Detected |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| Toluene-d8 | 97 | 70-130 |
| 1,2-Dichloroethane-d4 | 92 | 70-130 |
| 4-Bromofluorobenzene | 107 | 70-130 |

eurofins | Air Toxics

**Client Sample ID: VMP-31-5-021113**

**Lab ID#: 1302248A-09A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p021924** | **Date of Collection:** | **2/11/13 10:31:00 AM** |
| **Dil. Factor:** | **2.58** | **Date of Analysis:** | **2/19/13 10:55 PM** |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 1.3 | 0.44 J | 6.4 | 2.2 J |
| Freon 114 | 1.3 | Not Detected | 9.0 | Not Detected |
| Chloromethane | 13 | Not Detected | 27 | Not Detected |
| Vinyl Chloride | 1.3 | Not Detected | 3.3 | Not Detected |
| 1,3-Butadiene | 1.3 | Not Detected | 2.8 | Not Detected |
| Bromomethane | 13 | ~~0.65 J~~ U | 50 | ~~2.5 J~~ U |
| Chloroethane | 5.2 | Not Detected | 14 | Not Detected |
| Freon 11 | 1.3 | 0.24 J | 7.2 | 1.3 J |
| Ethanol | 5.2 | 9.8 | 9.7 | 18 |
| Freon 113 | 1.3 | Not Detected | 9.9 | Not Detected |
| 1,1-Dichloroethene | 1.3 | Not Detected | 5.1 | Not Detected |
| Acetone | 13 | 27 | 31 | 64 |
| 2-Propanol | 5.2 | 26 | 13 | 64 |
| Carbon Disulfide | 5.2 | ~~0.90 J~~ U | 16 | ~~2.8 J~~ U |
| 3-Chloropropene | 5.2 | Not Detected | 16 | Not Detected |
| Methylene Chloride | 13 | Not Detected | 45 | Not Detected |
| Methyl tert-butyl ether | 1.3 | Not Detected | 4.6 | Not Detected |
| trans-1,2-Dichloroethene | 1.3 | Not Detected | 5.1 | Not Detected |
| Hexane | 1.3 | 3.1 | 4.5 | 11 |
| 1,1-Dichloroethane | 1.3 | Not Detected | 5.2 | Not Detected |
| 2-Butanone (Methyl Ethyl Ketone) | 5.2 | 1.3 J | 15 | 3.9 J |
| cis-1,2-Dichloroethene | 1.3 | Not Detected | 5.1 | Not Detected |
| Tetrahydrofuran | 1.3 | Not Detected | 3.8 | Not Detected |
| Chloroform | 1.3 | Not Detected | 6.3 | Not Detected |
| 1,1,1-Trichloroethane | 1.3 | Not Detected | 7.0 | Not Detected |
| Cyclohexane | 1.3 | 0.93 J | 4.4 | 3.2 J |
| Carbon Tetrachloride | 1.3 | Not Detected | 8.1 | Not Detected |
| 2,2,4-Trimethylpentane | 1.3 | 2.8 | 6.0 | 13 |
| Benzene | 1.3 | 0.55 J | 4.1 | 1.7 J |
| 1,2-Dichloroethane | 1.3 | Not Detected | 5.2 | Not Detected |
| Heptane | 1.3 | 1.7 | 5.3 | 7.1 |
| Trichloroethene | 1.3 | Not Detected | 6.9 | Not Detected |
| 1,2-Dichloropropane | 1.3 | Not Detected | 6.0 | Not Detected |
| 1,4-Dioxane | 5.2 | Not Detected | 18 | Not Detected |
| Bromodichloromethane | 1.3 | Not Detected | 8.6 | Not Detected |
| cis-1,3-Dichloropropene | 1.3 | Not Detected | 5.8 | Not Detected |
| 4-Methyl-2-pentanone | 1.3 | 0.72 J | 5.3 | 2.9 J |
| Toluene | 1.3 | 3.0 | 4.9 | 11 |
| trans-1,3-Dichloropropene | 1.3 | Not Detected | 5.8 | Not Detected |
| 1,1,2-Trichloroethane | 1.3 | Not Detected | 7.0 | Not Detected |
| Tetrachloroethene | 1.3 | ~~0.17 J~~ U | 8.8 | ~~1.2 J~~ U |
| 2-Hexanone | 5.2 | Not Detected | 21 | Not Detected |

eurofins | Air Toxics

**Client Sample ID: VMP-31-5-021113**

**Lab ID#: 1302248A-09A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p021924** | **Date of Collection:** | **2/11/13 10:31:00 AM** |
| **Dil. Factor:** | **2.58** | **Date of Analysis:** | **2/19/13 10:55 PM** |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Dibromochloromethane | 1.3 | Not Detected | 11 | Not Detected |
| 1,2-Dibromoethane (EDB) | 1.3 | Not Detected | 9.9 | Not Detected |
| Chlorobenzene | 1.3 | Not Detected | 5.9 | Not Detected |
| Ethyl Benzene | 1.3 | 2.7 | 5.6 | 12 |
| m,p-Xylene | 1.3 | 7.6 | 5.6 | 33 |
| o-Xylene | 1.3 | 3.4 | 5.6 | 15 |
| Styrene | 1.3 | Not Detected | 5.5 | Not Detected |
| Bromoform | 1.3 | Not Detected | 13 | Not Detected |
| Cumene | 1.3 | 0.44 J | 6.3 | 2.2 J |
| 1,1,2,2-Tetrachloroethane | 1.3 | Not Detected | 8.8 | Not Detected |
| Propylbenzene | 1.3 | 1.2 J | 6.3 | 5.7 J |
| 4-Ethyltoluene | 1.3 | 3.6 | 6.3 | 18 |
| 1,3,5-Trimethylbenzene | 1.3 | 1.1 J | 6.3 | 5.3 J |
| 1,2,4-Trimethylbenzene | 1.3 | 2.9 | 6.3 | 14 |
| 1,3-Dichlorobenzene | 1.3 | ~~0.20 J~~ U | 7.8 | ~~1.2 J~~ U |
| 1,4-Dichlorobenzene | 1.3 | ~~0.23 J~~ U | 7.8 | ~~1.4 J~~ U |
| alpha-Chlorotoluene | 1.3 | Not Detected | 6.7 | Not Detected |
| 1,2-Dichlorobenzene | 1.3 | Not Detected | 7.8 | Not Detected |
| 1,2,4-Trichlorobenzene | 5.2 | ~~0.38 J~~ U | 38 | ~~2.8 J~~ U |
| Hexachlorobutadiene | 5.2 | Not Detected | 55 | Not Detected |
| Butane | 5.2 | 4.0 J | 12 | 9.6 J |
| Isopentane | 5.2 | 5.8 | 15 | 17 |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| Toluene-d8 | 96 | 70-130 |
| 1,2-Dichloroethane-d4 | 96 | 70-130 |
| 4-Bromofluorobenzene | 97 | 70-130 |

eurofins | Air Toxics

**Client Sample ID: VMP-54-20-020613**

**Lab ID#: 1302248A-10A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | p022007 | **Date of Collection:** | 2/6/13 3:01:00 PM |
| **Dil. Factor:** | 2.76 | **Date of Analysis:** | 2/20/13 11:59 AM |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 1.4 | 0.58 J | 6.8 | 2.8 J |
| Freon 114 | 1.4 | Not Detected | 9.6 | Not Detected |
| Chloromethane | 14 | Not Detected | 28 | Not Detected |
| Vinyl Chloride | 1.4 | Not Detected | 3.5 | Not Detected |
| 1,3-Butadiene | 1.4 | Not Detected | 3.0 | Not Detected |
| Bromomethane | 14 | Not Detected | 54 | Not Detected |
| Chloroethane | 5.5 | Not Detected | 14 | Not Detected |
| Freon 11 | 1.4 | 0.24 J | 7.8 | 1.4 J |
| Ethanol | 5.5 | 1.7 J | 10 | 3.2 J |
| Freon 113 | 1.4 | Not Detected | 10 | Not Detected |
| 1,1-Dichloroethene | 1.4 | Not Detected | 5.5 | Not Detected |
| Acetone | 14 | 12 J | 33 | 29 J |
| 2-Propanol | 5.5 | 3.4 J | 14 | 8.3 J |
| Carbon Disulfide | 5.5 | ~~0.89 J~~ U | 17 | ~~2.8 J~~ U |
| 3-Chloropropene | 5.5 | Not Detected | 17 | Not Detected |
| Methylene Chloride | 14 | Not Detected | 48 | Not Detected |
| Methyl tert-butyl ether | 1.4 | Not Detected | 5.0 | Not Detected |
| trans-1,2-Dichloroethene | 1.4 | Not Detected | 5.5 | Not Detected |
| Hexane | 1.4 | 1.1 J | 4.9 | 4.0 J |
| 1,1-Dichloroethane | 1.4 | Not Detected | 5.6 | Not Detected |
| 2-Butanone (Methyl Ethyl Ketone) | 5.5 | 1.7 J | 16 | 5.0 J |
| cis-1,2-Dichloroethene | 1.4 | Not Detected | 5.5 | Not Detected |
| Tetrahydrofuran | 1.4 | Not Detected | 4.1 | Not Detected |
| Chloroform | 1.4 | Not Detected | 6.7 | Not Detected |
| 1,1,1-Trichloroethane | 1.4 | Not Detected | 7.5 | Not Detected |
| Cyclohexane | 1.4 | Not Detected | 4.8 | Not Detected |
| Carbon Tetrachloride | 1.4 | Not Detected | 8.7 | Not Detected |
| 2,2,4-Trimethylpentane | 1.4 | 0.24 J | 6.4 | 1.1 J |
| Benzene | 1.4 | 0.89 J | 4.4 | 2.8 J |
| 1,2-Dichloroethane | 1.4 | Not Detected | 5.6 | Not Detected |
| Heptane | 1.4 | 0.98 J | 5.6 | 4.0 J |
| Trichloroethene | 1.4 | Not Detected | 7.4 | Not Detected |
| 1,2-Dichloropropane | 1.4 | Not Detected | 6.4 | Not Detected |
| 1,4-Dioxane | 5.5 | Not Detected | 20 | Not Detected |
| Bromodichloromethane | 1.4 | Not Detected | 9.2 | Not Detected |
| cis-1,3-Dichloropropene | 1.4 | Not Detected | 6.3 | Not Detected |
| 4-Methyl-2-pentanone | 1.4 | Not Detected | 5.6 | Not Detected |
| Toluene | 1.4 | ~~0.19 J~~ U | 5.2 | ~~0.72 J~~ U |
| trans-1,3-Dichloropropene | 1.4 | Not Detected | 6.3 | Not Detected |
| 1,1,2-Trichloroethane | 1.4 | Not Detected | 7.5 | Not Detected |
| Tetrachloroethene | 1.4 | 0.77 J | 9.4 | 5.2 J |
| 2-Hexanone | 5.5 | Not Detected | 23 | Not Detected |

eurofins | Air Toxics

**Client Sample ID: VMP-54-20-020613**

**Lab ID#: 1302248A-10A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p022007** | **Date of Collection: 2/6/13 3:01:00 PM** | |
| **Dil. Factor:** | **2.76** | **Date of Analysis: 2/20/13 11:59 AM** | |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Dibromochloromethane | 1.4 | Not Detected | 12 | Not Detected |
| 1,2-Dibromoethane (EDB) | 1.4 | Not Detected | 11 | Not Detected |
| Chlorobenzene | 1.4 | Not Detected | 6.4 | Not Detected |
| Ethyl Benzene | 1.4 | Not Detected | 6.0 | Not Detected |
| m,p-Xylene | 1.4 | Not Detected | 6.0 | Not Detected |
| o-Xylene | 1.4 | Not Detected | 6.0 | Not Detected |
| Styrene | 1.4 | Not Detected | 5.9 | Not Detected |
| Bromoform | 1.4 | Not Detected | 14 | Not Detected |
| Cumene | 1.4 | Not Detected | 6.8 | Not Detected |
| 1,1,2,2-Tetrachloroethane | 1.4 | Not Detected | 9.5 | Not Detected |
| Propylbenzene | 1.4 | ~~0.15 J~~ U | 6.8 | ~~0.74 J~~ U |
| 4-Ethyltoluene | 1.4 | ~~0.13 J~~ U | 6.8 | ~~0.63 J~~ U |
| 1,3,5-Trimethylbenzene | 1.4 | Not Detected | 6.8 | Not Detected |
| 1,2,4-Trimethylbenzene | 1.4 | ~~0.33 J~~ U | 6.8 | ~~1.6 J~~ U |
| 1,3-Dichlorobenzene | 1.4 | ~~0.23 J~~ U | 8.3 | ~~1.4 J~~ U |
| 1,4-Dichlorobenzene | 1.4 | ~~0.25 J~~ U | 8.3 | ~~1.5 J~~ U |
| alpha-Chlorotoluene | 1.4 | Not Detected | 7.1 | Not Detected |
| 1,2-Dichlorobenzene | 1.4 | Not Detected | 8.3 | Not Detected |
| 1,2,4-Trichlorobenzene | 5.5 | ~~0.78 J~~ U | 41 | ~~5.8 J~~ U |
| Hexachlorobutadiene | 5.5 | Not Detected | 59 | Not Detected |
| Butane | 5.5 | 2.0 J | 13 | 4.9 J |
| Isopentane | 5.5 | 1.0 J | 16 | 3.0 J |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| Toluene-d8 | 97 | 70-130 |
| 1,2-Dichloroethane-d4 | 89 | 70-130 |
| 4-Bromofluorobenzene | 95 | 70-130 |

eurofins | Air Toxics

**Client Sample ID: VMP-54-20-020613-DUP**

**Lab ID#: 1302248A-11A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | p022008 | **Date of Collection:** | 2/6/13 3:01:00 PM |
| **Dil. Factor:** | 2.76 | **Date of Analysis:** | 2/20/13 12:42 PM |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 1.4 | 0.47 J | 6.8 | 2.3 J |
| Freon 114 | 1.4 | Not Detected | 9.6 | Not Detected |
| Chloromethane | 14 | Not Detected | 28 | Not Detected |
| Vinyl Chloride | 1.4 | Not Detected | 3.5 | Not Detected |
| 1,3-Butadiene | 1.4 | Not Detected | 3.0 | Not Detected |
| Bromomethane | 14 | Not Detected | 54 | Not Detected |
| Chloroethane | 5.5 | Not Detected | 14 | Not Detected |
| Freon 11 | 1.4 | 0.23 J | 7.8 | 1.3 J |
| Ethanol | 5.5 | 2.7 J | 10 | 5.0 J |
| Freon 113 | 1.4 | Not Detected | 10 | Not Detected |
| 1,1-Dichloroethene | 1.4 | Not Detected | 5.5 | Not Detected |
| Acetone | 14 | 9.8 J | 33 | 23 J |
| 2-Propanol | 5.5 | 5.9 | 14 | 14 |
| Carbon Disulfide | 5.5 | ~~0.78 J~~ U | 17 | ~~2.4 J~~ U |
| 3-Chloropropene | 5.5 | Not Detected | 17 | Not Detected |
| Methylene Chloride | 14 | 0.26 J | 48 | 0.92 J |
| Methyl tert-butyl ether | 1.4 | Not Detected | 5.0 | Not Detected |
| trans-1,2-Dichloroethene | 1.4 | Not Detected | 5.5 | Not Detected |
| Hexane | 1.4 | 1.8 | 4.9 | 6.4 |
| 1,1-Dichloroethane | 1.4 | Not Detected | 5.6 | Not Detected |
| 2-Butanone (Methyl Ethyl Ketone) | 5.5 | 1.1 J | 16 | 3.3 J |
| cis-1,2-Dichloroethene | 1.4 | Not Detected | 5.5 | Not Detected |
| Tetrahydrofuran | 1.4 | Not Detected | 4.1 | Not Detected |
| Chloroform | 1.4 | Not Detected | 6.7 | Not Detected |
| 1,1,1-Trichloroethane | 1.4 | Not Detected | 7.5 | Not Detected |
| Cyclohexane | 1.4 | 0.75 J | 4.8 | 2.6 J |
| Carbon Tetrachloride | 1.4 | Not Detected | 8.7 | Not Detected |
| 2,2,4-Trimethylpentane | 1.4 | 0.93 J | 6.4 | 4.3 J |
| Benzene | 1.4 | 11 | 4.4 | 36 |
| 1,2-Dichloroethane | 1.4 | Not Detected | 5.6 | Not Detected |
| Heptane | 1.4 | 1.2 J | 5.6 | 4.8 J |
| Trichloroethene | 1.4 | Not Detected | 7.4 | Not Detected |
| 1,2-Dichloropropane | 1.4 | Not Detected | 6.4 | Not Detected |
| 1,4-Dioxane | 5.5 | Not Detected | 20 | Not Detected |
| Bromodichloromethane | 1.4 | Not Detected | 9.2 | Not Detected |
| cis-1,3-Dichloropropene | 1.4 | Not Detected | 6.3 | Not Detected |
| 4-Methyl-2-pentanone | 1.4 | Not Detected | 5.6 | Not Detected |
| Toluene | 1.4 | ~~0.18 J~~ U | 5.2 | ~~0.68 J~~ U |
| trans-1,3-Dichloropropene | 1.4 | Not Detected | 6.3 | Not Detected |
| 1,1,2-Trichloroethane | 1.4 | Not Detected | 7.5 | Not Detected |
| Tetrachloroethene | 1.4 | 0.67 J | 9.4 | 4.6 J |
| 2-Hexanone | 5.5 | Not Detected | 23 | Not Detected |

eurofins | Air Toxics

**Client Sample ID: VMP-54-20-020613-DUP**

**Lab ID#: 1302248A-11A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p022008** | **Date of Collection: 2/6/13 3:01:00 PM** | |
| **Dil. Factor:** | **2.76** | **Date of Analysis: 2/20/13 12:42 PM** | |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Dibromochloromethane | 1.4 | Not Detected | 12 | Not Detected |
| 1,2-Dibromoethane (EDB) | 1.4 | Not Detected | 11 | Not Detected |
| Chlorobenzene | 1.4 | Not Detected | 6.4 | Not Detected |
| Ethyl Benzene | 1.4 | Not Detected | 6.0 | Not Detected |
| m,p-Xylene | 1.4 | Not Detected | 6.0 | Not Detected |
| o-Xylene | 1.4 | Not Detected | 6.0 | Not Detected |
| Styrene | 1.4 | Not Detected | 5.9 | Not Detected |
| Bromoform | 1.4 | Not Detected | 14 | Not Detected |
| Cumene | 1.4 | Not Detected | 6.8 | Not Detected |
| 1,1,2,2-Tetrachloroethane | 1.4 | Not Detected | 9.5 | Not Detected |
| Propylbenzene | 1.4 | 0.15 J | 6.8 | 0.73 J |
| 4-Ethyltoluene | 1.4 | 0.42 J | 6.8 | 2.1 J |
| 1,3,5-Trimethylbenzene | 1.4 | Not Detected | 6.8 | Not Detected |
| 1,2,4-Trimethylbenzene | 1.4 | 0.32 J | 6.8 | 1.6 J |
| 1,3-Dichlorobenzene | 1.4 | 0.20 J | 8.3 | 1.2 J |
| 1,4-Dichlorobenzene | 1.4 | 0.21 J | 8.3 | 1.3 J |
| alpha-Chlorotoluene | 1.4 | Not Detected | 7.1 | Not Detected |
| 1,2-Dichlorobenzene | 1.4 | Not Detected | 8.3 | Not Detected |
| 1,2,4-Trichlorobenzene | 5.5 | 0.55 J | 41 | 4.1 J |
| Hexachlorobutadiene | 5.5 | Not Detected | 59 | Not Detected |
| Butane | 5.5 | 2.6 J | 13 | 6.1 J |
| Isopentane | 5.5 | 3.9 J | 16 | 12 J |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| Toluene-d8 | 97 | 70-130 |
| 1,2-Dichloroethane-d4 | 93 | 70-130 |
| 4-Bromofluorobenzene | 96 | 70-130 |

eurofins | Air Toxics

**Client Sample ID: VMP-54-30-020613**

**Lab ID#: 1302248A-12A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p022009** | **Date of Collection:** | **2/6/13 3:55:00 PM** |
| **Dil. Factor:** | **2.96** | **Date of Analysis:** | **2/20/13 01:13 PM** |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 1.5 | 0.53 J | 7.3 | 2.6 J |
| Freon 114 | 1.5 | Not Detected | 10 | Not Detected |
| Chloromethane | 15 | Not Detected | 30 | Not Detected |
| Vinyl Chloride | 1.5 | Not Detected | 3.8 | Not Detected |
| 1,3-Butadiene | 1.5 | Not Detected | 3.3 | Not Detected |
| Bromomethane | 15 | Not Detected | 57 | Not Detected |
| Chloroethane | 5.9 | Not Detected | 16 | Not Detected |
| Freon 11 | 1.5 | 0.21 J | 8.3 | 1.2 J |
| Ethanol | 5.9 | 1.4 J | 11 | 2.7 J |
| Freon 113 | 1.5 | Not Detected | 11 | Not Detected |
| 1,1-Dichloroethene | 1.5 | Not Detected | 5.9 | Not Detected |
| Acetone | 15 | 5.1 J | 35 | 12 J |
| 2-Propanol | 5.9 | 1.7 J | 14 | 4.2 J |
| Carbon Disulfide | 5.9 | ~~1.0 J~~ U | 18 | ~~3.2 J~~ U |
| 3-Chloropropene | 5.9 | Not Detected | 18 | Not Detected |
| Methylene Chloride | 15 | 0.28 J | 51 | 0.97 J |
| Methyl tert-butyl ether | 1.5 | Not Detected | 5.3 | Not Detected |
| trans-1,2-Dichloroethene | 1.5 | Not Detected | 5.9 | Not Detected |
| Hexane | 1.5 | 0.46 J | 5.2 | 1.6 J |
| 1,1-Dichloroethane | 1.5 | Not Detected | 6.0 | Not Detected |
| 2-Butanone (Methyl Ethyl Ketone) | 5.9 | Not Detected | 17 | Not Detected |
| cis-1,2-Dichloroethene | 1.5 | Not Detected | 5.9 | Not Detected |
| Tetrahydrofuran | 1.5 | Not Detected | 4.4 | Not Detected |
| Chloroform | 1.5 | Not Detected | 7.2 | Not Detected |
| 1,1,1-Trichloroethane | 1.5 | Not Detected | 8.1 | Not Detected |
| Cyclohexane | 1.5 | Not Detected | 5.1 | Not Detected |
| Carbon Tetrachloride | 1.5 | Not Detected | 9.3 | Not Detected |
| 2,2,4-Trimethylpentane | 1.5 | 0.50 J | 6.9 | 2.3 J |
| Benzene | 1.5 | 4.5 J | 4.7 | 14 J |
| 1,2-Dichloroethane | 1.5 | Not Detected | 6.0 | Not Detected |
| Heptane | 1.5 | Not Detected | 6.1 | Not Detected |
| Trichloroethene | 1.5 | Not Detected | 8.0 | Not Detected |
| 1,2-Dichloropropane | 1.5 | Not Detected | 6.8 | Not Detected |
| 1,4-Dioxane | 5.9 | Not Detected | 21 | Not Detected |
| Bromodichloromethane | 1.5 | Not Detected | 9.9 | Not Detected |
| cis-1,3-Dichloropropene | 1.5 | Not Detected | 6.7 | Not Detected |
| 4-Methyl-2-pentanone | 1.5 | Not Detected | 6.1 | Not Detected |
| Toluene | 1.5 | ~~0.12 J~~ U | 5.6 | ~~0.46 J~~ U |
| trans-1,3-Dichloropropene | 1.5 | Not Detected | 6.7 | Not Detected |
| 1,1,2-Trichloroethane | 1.5 | Not Detected | 8.1 | Not Detected |
| Tetrachloroethene | 1.5 | 0.67 J | 10 | 4.6 J |
| 2-Hexanone | 5.9 | Not Detected | 24 | Not Detected |

eurofins | Air Toxics

**Client Sample ID: VMP-54-30-020613**

**Lab ID#: 1302248A-12A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p022009** | **Date of Collection:** | **2/6/13 3:55:00 PM** |
| **Dil. Factor:** | **2.96** | **Date of Analysis:** | **2/20/13 01:13 PM** |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Dibromochloromethane | 1.5 | Not Detected | 13 | Not Detected |
| 1,2-Dibromoethane (EDB) | 1.5 | Not Detected | 11 | Not Detected |
| Chlorobenzene | 1.5 | Not Detected | 6.8 | Not Detected |
| Ethyl Benzene | 1.5 | Not Detected | 6.4 | Not Detected |
| m,p-Xylene | 1.5 | Not Detected | 6.4 | Not Detected |
| o-Xylene | 1.5 | Not Detected | 6.4 | Not Detected |
| Styrene | 1.5 | Not Detected | 6.3 | Not Detected |
| Bromoform | 1.5 | Not Detected | 15 | Not Detected |
| Cumene | 1.5 | Not Detected | 7.3 | Not Detected |
| 1,1,2,2-Tetrachloroethane | 1.5 | Not Detected | 10 | Not Detected |
| Propylbenzene | 1.5 | Not Detected | 7.3 | Not Detected |
| 4-Ethyltoluene | 1.5 | Not Detected | 7.3 | Not Detected |
| 1,3,5-Trimethylbenzene | 1.5 | Not Detected | 7.3 | Not Detected |
| 1,2,4-Trimethylbenzene | 1.5 | Not Detected | 7.3 | Not Detected |
| 1,3-Dichlorobenzene | 1.5 | Not Detected | 8.9 | Not Detected |
| 1,4-Dichlorobenzene | 1.5 | Not Detected | 8.9 | Not Detected |
| alpha-Chlorotoluene | 1.5 | Not Detected | 7.7 | Not Detected |
| 1,2-Dichlorobenzene | 1.5 | Not Detected | 8.9 | Not Detected |
| 1,2,4-Trichlorobenzene | 5.9 | ~~0.41 J~~ U | 44 | ~~3.1 J~~ U |
| Hexachlorobutadiene | 5.9 | Not Detected | 63 | Not Detected |
| Butane | 5.9 | Not Detected | 14 | Not Detected |
| Isopentane | 5.9 | 1.5 J | 17 | 4.5 J |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| Toluene-d8 | 95 | 70-130 |
| 1,2-Dichloroethane-d4 | 94 | 70-130 |
| 4-Bromofluorobenzene | 92 | 70-130 |

eurofins | Air Toxics

**Client Sample ID: VMP-54-30-020613-DUP**

**Lab ID#: 1302248A-13A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p022010** | **Date of Collection:** | **2/6/13 3:55:00 PM** |
| **Dil. Factor:** | **2.96** | **Date of Analysis:** | **2/20/13 01:34 PM** |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 1.5 | 0.51 J | 7.3 | 2.5 J |
| Freon 114 | 1.5 | Not Detected | 10 | Not Detected |
| Chloromethane | 15 | Not Detected | 30 | Not Detected |
| Vinyl Chloride | 1.5 | Not Detected | 3.8 | Not Detected |
| 1,3-Butadiene | 1.5 | Not Detected | 3.3 | Not Detected |
| Bromomethane | 15 | Not Detected | 57 | Not Detected |
| Chloroethane | 5.9 | Not Detected | 16 | Not Detected |
| Freon 11 | 1.5 | 0.23 J | 8.3 | 1.3 J |
| Ethanol | 5.9 | 1.8 J | 11 | 3.5 J |
| Freon 113 | 1.5 | Not Detected | 11 | Not Detected |
| 1,1-Dichloroethene | 1.5 | Not Detected | 5.9 | Not Detected |
| Acetone | 15 | 5.6 J | 35 | 13 J |
| 2-Propanol | 5.9 | 1.4 J | 14 | 3.4 J |
| Carbon Disulfide | 5.9 | ~~0.95 J~~ U | 18 | ~~3.0 J~~ U |
| 3-Chloropropene | 5.9 | Not Detected | 18 | Not Detected |
| Methylene Chloride | 15 | Not Detected | 51 | Not Detected |
| Methyl tert-butyl ether | 1.5 | Not Detected | 5.3 | Not Detected |
| trans-1,2-Dichloroethene | 1.5 | Not Detected | 5.9 | Not Detected |
| Hexane | 1.5 | 0.46 J | 5.2 | 1.6 J |
| 1,1-Dichloroethane | 1.5 | Not Detected | 6.0 | Not Detected |
| 2-Butanone (Methyl Ethyl Ketone) | 5.9 | Not Detected | 17 | Not Detected |
| cis-1,2-Dichloroethene | 1.5 | Not Detected | 5.9 | Not Detected |
| Tetrahydrofuran | 1.5 | Not Detected | 4.4 | Not Detected |
| Chloroform | 1.5 | Not Detected | 7.2 | Not Detected |
| 1,1,1-Trichloroethane | 1.5 | Not Detected | 8.1 | Not Detected |
| Cyclohexane | 1.5 | Not Detected | 5.1 | Not Detected |
| Carbon Tetrachloride | 1.5 | Not Detected | 9.3 | Not Detected |
| 2,2,4-Trimethylpentane | 1.5 | 0.27 J | 6.9 | 1.3 J |
| Benzene | 1.5 | 1.4 J J | 4.7 | 4.5 J J |
| 1,2-Dichloroethane | 1.5 | Not Detected | 6.0 | Not Detected |
| Heptane | 1.5 | Not Detected | 6.1 | Not Detected |
| Trichloroethene | 1.5 | Not Detected | 8.0 | Not Detected |
| 1,2-Dichloropropane | 1.5 | Not Detected | 6.8 | Not Detected |
| 1,4-Dioxane | 5.9 | Not Detected | 21 | Not Detected |
| Bromodichloromethane | 1.5 | Not Detected | 9.9 | Not Detected |
| cis-1,3-Dichloropropene | 1.5 | Not Detected | 6.7 | Not Detected |
| 4-Methyl-2-pentanone | 1.5 | Not Detected | 6.1 | Not Detected |
| Toluene | 1.5 | ~~0.14 J~~ U | 5.6 | ~~0.55 J~~ U |
| trans-1,3-Dichloropropene | 1.5 | Not Detected | 6.7 | Not Detected |
| 1,1,2-Trichloroethane | 1.5 | Not Detected | 8.1 | Not Detected |
| Tetrachloroethene | 1.5 | 0.67 J | 10 | 4.5 J |
| 2-Hexanone | 5.9 | Not Detected | 24 | Not Detected |

eurofins | Air Toxics

**Client Sample ID: VMP-54-30-020613-DUP**

**Lab ID#: 1302248A-13A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p022010** | **Date of Collection: 2/6/13 3:55:00 PM** | |
| **Dil. Factor:** | **2.96** | **Date of Analysis: 2/20/13 01:34 PM** | |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Dibromochloromethane | 1.5 | Not Detected | 13 | Not Detected |
| 1,2-Dibromoethane (EDB) | 1.5 | Not Detected | 11 | Not Detected |
| Chlorobenzene | 1.5 | Not Detected | 6.8 | Not Detected |
| Ethyl Benzene | 1.5 | Not Detected | 6.4 | Not Detected |
| m,p-Xylene | 1.5 | Not Detected | 6.4 | Not Detected |
| o-Xylene | 1.5 | Not Detected | 6.4 | Not Detected |
| Styrene | 1.5 | Not Detected | 6.3 | Not Detected |
| Bromoform | 1.5 | Not Detected | 15 | Not Detected |
| Cumene | 1.5 | Not Detected | 7.3 | Not Detected |
| 1,1,2,2-Tetrachloroethane | 1.5 | Not Detected | 10 | Not Detected |
| Propylbenzene | 1.5 | Not Detected | 7.3 | Not Detected |
| 4-Ethyltoluene | 1.5 | Not Detected | 7.3 | Not Detected |
| 1,3,5-Trimethylbenzene | 1.5 | Not Detected | 7.3 | Not Detected |
| 1,2,4-Trimethylbenzene | 1.5 | Not Detected | 7.3 | Not Detected |
| 1,3-Dichlorobenzene | 1.5 | Not Detected | 8.9 | Not Detected |
| 1,4-Dichlorobenzene | 1.5 | Not Detected | 8.9 | Not Detected |
| alpha-Chlorotoluene | 1.5 | Not Detected | 7.7 | Not Detected |
| 1,2-Dichlorobenzene | 1.5 | Not Detected | 8.9 | Not Detected |
| 1,2,4-Trichlorobenzene | 5.9 | Not Detected | 44 | Not Detected |
| Hexachlorobutadiene | 5.9 | Not Detected | 63 | Not Detected |
| Butane | 5.9 | Not Detected | 14 | Not Detected |
| Isopentane | 5.9 | 0.78 J | 17 | 2.3 J |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| Toluene-d8 | 98 | 70-130 |
| 1,2-Dichloroethane-d4 | 91 | 70-130 |
| 4-Bromofluorobenzene | 91 | 70-130 |

eurofins | Air Toxics

**Client Sample ID: VMP-7-13.5-021313**

**Lab ID#: 1302248A-14A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p022011** | **Date of Collection: 2/13/13 10:52:00 AM** | |
| **Dil. Factor:** | **2.76** | **Date of Analysis: 2/20/13 02:18 PM** | |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 1.4 | 0.54 J | 6.8 | 2.6 J |
| Freon 114 | 1.4 | Not Detected | 9.6 | Not Detected |
| Chloromethane | 14 | Not Detected | 28 | Not Detected |
| Vinyl Chloride | 1.4 | Not Detected | 3.5 | Not Detected |
| 1,3-Butadiene | 1.4 | Not Detected | 3.0 | Not Detected |
| Bromomethane | 14 | Not Detected | 54 | Not Detected |
| Chloroethane | 5.5 | Not Detected | 14 | Not Detected |
| Freon 11 | 1.4 | 0.22 J | 7.8 | 1.3 J |
| Ethanol | 5.5 | 3.6 J | 10 | 6.8 J |
| Freon 113 | 1.4 | Not Detected | 10 | Not Detected |
| 1,1-Dichloroethene | 1.4 | Not Detected | 5.5 | Not Detected |
| Acetone | 14 | 10 J | 33 | 24 J |
| 2-Propanol | 5.5 | 1.6 J | 14 | 3.9 J |
| Carbon Disulfide | 5.5 | ~~0.76 J~~ | 17 | ~~2.4 J~~ |
| 3-Chloropropene | 5.5 | Not Detected | 17 | Not Detected |
| Methylene Chloride | 14 | 0.18 J | 48 | 0.61 J |
| Methyl tert-butyl ether | 1.4 | Not Detected | 5.0 | Not Detected |
| trans-1,2-Dichloroethene | 1.4 | Not Detected | 5.5 | Not Detected |
| Hexane | 1.4 | 0.33 J | 4.9 | 1.2 J |
| 1,1-Dichloroethane | 1.4 | Not Detected | 5.6 | Not Detected |
| 2-Butanone (Methyl Ethyl Ketone) | 5.5 | Not Detected | 16 | Not Detected |
| cis-1,2-Dichloroethene | 1.4 | Not Detected | 5.5 | Not Detected |
| Tetrahydrofuran | 1.4 | Not Detected | 4.1 | Not Detected |
| Chloroform | 1.4 | 0.42 J | 6.7 | 2.0 J |
| 1,1,1-Trichloroethane | 1.4 | Not Detected | 7.5 | Not Detected |
| Cyclohexane | 1.4 | Not Detected | 4.8 | Not Detected |
| Carbon Tetrachloride | 1.4 | Not Detected | 8.7 | Not Detected |
| 2,2,4-Trimethylpentane | 1.4 | 0.15 J | 6.4 | 0.70 J |
| Benzene | 1.4 | 0.63 J | 4.4 | 2.0 J |
| 1,2-Dichloroethane | 1.4 | Not Detected | 5.6 | Not Detected |
| Heptane | 1.4 | Not Detected | 5.6 | Not Detected |
| Trichloroethene | 1.4 | Not Detected | 7.4 | Not Detected |
| 1,2-Dichloropropane | 1.4 | Not Detected | 6.4 | Not Detected |
| 1,4-Dioxane | 5.5 | Not Detected | 20 | Not Detected |
| Bromodichloromethane | 1.4 | Not Detected | 9.2 | Not Detected |
| cis-1,3-Dichloropropene | 1.4 | Not Detected | 6.3 | Not Detected |
| 4-Methyl-2-pentanone | 1.4 | Not Detected | 5.6 | Not Detected |
| Toluene | 1.4 | ~~0.18 J~~ | 5.2 | ~~0.66 J~~ |
| trans-1,3-Dichloropropene | 1.4 | Not Detected | 6.3 | Not Detected |
| 1,1,2-Trichloroethane | 1.4 | Not Detected | 7.5 | Not Detected |
| Tetrachloroethene | 1.4 | Not Detected | 9.4 | Not Detected |
| 2-Hexanone | 5.5 | Not Detected | 23 | Not Detected |

eurofins | Air Toxics

**Client Sample ID: VMP-7-13.5-021313**

**Lab ID#: 1302248A-14A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p022011** | **Date of Collection: 2/13/13 10:52:00 AM** | |
| **Dil. Factor:** | **2.76** | **Date of Analysis: 2/20/13 02:18 PM** | |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Dibromochloromethane | 1.4 | Not Detected | 12 | Not Detected |
| 1,2-Dibromoethane (EDB) | 1.4 | Not Detected | 11 | Not Detected |
| Chlorobenzene | 1.4 | Not Detected | 6.4 | Not Detected |
| Ethyl Benzene | 1.4 | Not Detected | 6.0 | Not Detected |
| m,p-Xylene | 1.4 | Not Detected | 6.0 | Not Detected |
| o-Xylene | 1.4 | Not Detected | 6.0 | Not Detected |
| Styrene | 1.4 | Not Detected | 5.9 | Not Detected |
| Bromoform | 1.4 | Not Detected | 14 | Not Detected |
| Cumene | 1.4 | Not Detected | 6.8 | Not Detected |
| 1,1,2,2-Tetrachloroethane | 1.4 | Not Detected | 9.5 | Not Detected |
| Propylbenzene | 1.4 | Not Detected | 6.8 | Not Detected |
| 4-Ethyltoluene | 1.4 | Not Detected | 6.8 | Not Detected |
| 1,3,5-Trimethylbenzene | 1.4 | Not Detected | 6.8 | Not Detected |
| 1,2,4-Trimethylbenzene | 1.4 | Not Detected | 6.8 | Not Detected |
| 1,3-Dichlorobenzene | 1.4 | Not Detected | 8.3 | Not Detected |
| 1,4-Dichlorobenzene | 1.4 | Not Detected | 8.3 | Not Detected |
| alpha-Chlorotoluene | 1.4 | Not Detected | 7.1 | Not Detected |
| 1,2-Dichlorobenzene | 1.4 | Not Detected | 8.3 | Not Detected |
| 1,2,4-Trichlorobenzene | 5.5 | ~~0.56 J~~ | 41 | ~~4.1 J~~ |
| Hexachlorobutadiene | 5.5 | Not Detected | 59 | Not Detected |
| Butane | 5.5 | Not Detected | 13 | Not Detected |
| Isopentane | 5.5 | 0.63 J | 16 | 1.8 J |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| Toluene-d8 | 97 | 70-130 |
| 1,2-Dichloroethane-d4 | 94 | 70-130 |
| 4-Bromofluorobenzene | 99 | 70-130 |

eurofins | Air Toxics

**Client Sample ID: Lab Blank**

**Lab ID#: 1302248A-15A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p021905a** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 2/19/13 10:13 AM** | |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 0.50 | Not Detected | 2.5 | Not Detected |
| Freon 114 | 0.50 | Not Detected | 3.5 | Not Detected |
| Chloromethane | 5.0 | Not Detected | 10 | Not Detected |
| Vinyl Chloride | 0.50 | Not Detected | 1.3 | Not Detected |
| 1,3-Butadiene | 0.50 | Not Detected | 1.1 | Not Detected |
| Bromomethane | 5.0 | 0.27 J | 19 | 1.0 J |
| Chloroethane | 2.0 | Not Detected | 5.3 | Not Detected |
| Freon 11 | 0.50 | Not Detected | 2.8 | Not Detected |
| Ethanol | 2.0 | Not Detected | 3.8 | Not Detected |
| Freon 113 | 0.50 | Not Detected | 3.8 | Not Detected |
| 1,1-Dichloroethene | 0.50 | Not Detected | 2.0 | Not Detected |
| Acetone | 5.0 | Not Detected | 12 | Not Detected |
| 2-Propanol | 2.0 | Not Detected | 4.9 | Not Detected |
| Carbon Disulfide | 2.0 | 0.48 J | 6.2 | 1.5 J |
| 3-Chloropropene | 2.0 | Not Detected | 6.3 | Not Detected |
| Methylene Chloride | 5.0 | 0.18 J | 17 | 0.64 J |
| Methyl tert-butyl ether | 0.50 | Not Detected | 1.8 | Not Detected |
| trans-1,2-Dichloroethene | 0.50 | Not Detected | 2.0 | Not Detected |
| Hexane | 0.50 | Not Detected | 1.8 | Not Detected |
| 1,1-Dichloroethane | 0.50 | Not Detected | 2.0 | Not Detected |
| 2-Butanone (Methyl Ethyl Ketone) | 2.0 | Not Detected | 5.9 | Not Detected |
| cis-1,2-Dichloroethene | 0.50 | Not Detected | 2.0 | Not Detected |
| Tetrahydrofuran | 0.50 | Not Detected | 1.5 | Not Detected |
| Chloroform | 0.50 | Not Detected | 2.4 | Not Detected |
| 1,1,1-Trichloroethane | 0.50 | Not Detected | 2.7 | Not Detected |
| Cyclohexane | 0.50 | Not Detected | 1.7 | Not Detected |
| Carbon Tetrachloride | 0.50 | Not Detected | 3.1 | Not Detected |
| 2,2,4-Trimethylpentane | 0.50 | Not Detected | 2.3 | Not Detected |
| Benzene | 0.50 | Not Detected | 1.6 | Not Detected |
| 1,2-Dichloroethane | 0.50 | Not Detected | 2.0 | Not Detected |
| Heptane | 0.50 | Not Detected | 2.0 | Not Detected |
| Trichloroethene | 0.50 | Not Detected | 2.7 | Not Detected |
| 1,2-Dichloropropane | 0.50 | Not Detected | 2.3 | Not Detected |
| 1,4-Dioxane | 2.0 | Not Detected | 7.2 | Not Detected |
| Bromodichloromethane | 0.50 | Not Detected | 3.4 | Not Detected |
| cis-1,3-Dichloropropene | 0.50 | 0.088 J | 2.3 | 0.40 J |
| 4-Methyl-2-pentanone | 0.50 | Not Detected | 2.0 | Not Detected |
| Toluene | 0.50 | 0.080 J | 1.9 | 0.30 J |
| trans-1,3-Dichloropropene | 0.50 | 0.18 J | 2.3 | 0.80 J |
| 1,1,2-Trichloroethane | 0.50 | Not Detected | 2.7 | Not Detected |
| Tetrachloroethene | 0.50 | 0.082 J | 3.4 | 0.55 J |
| 2-Hexanone | 2.0 | Not Detected | 8.2 | Not Detected |

eurofins | Air Toxics

**Client Sample ID: Lab Blank**

**Lab ID#: 1302248A-15A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p021905a** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 2/19/13 10:13 AM** | |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Dibromochloromethane | 0.50 | Not Detected | 4.2 | Not Detected |
| 1,2-Dibromoethane (EDB) | 0.50 | 0.12 J | 3.8 | 0.91 J |
| Chlorobenzene | 0.50 | 0.11 J | 2.3 | 0.49 J |
| Ethyl Benzene | 0.50 | Not Detected | 2.2 | Not Detected |
| m,p-Xylene | 0.50 | Not Detected | 2.2 | Not Detected |
| o-Xylene | 0.50 | Not Detected | 2.2 | Not Detected |
| Styrene | 0.50 | Not Detected | 2.1 | Not Detected |
| Bromoform | 0.50 | Not Detected | 5.2 | Not Detected |
| Cumene | 0.50 | 0.087 J | 2.4 | 0.42 J |
| 1,1,2,2-Tetrachloroethane | 0.50 | 0.094 J | 3.4 | 0.64 J |
| Propylbenzene | 0.50 | 0.12 J | 2.4 | 0.56 J |
| 4-Ethyltoluene | 0.50 | 0.088 J | 2.4 | 0.44 J |
| 1,3,5-Trimethylbenzene | 0.50 | 0.18 J | 2.4 | 0.91 J |
| 1,2,4-Trimethylbenzene | 0.50 | 0.16 J | 2.4 | 0.77 J |
| 1,3-Dichlorobenzene | 0.50 | 0.29 J | 3.0 | 1.8 J |
| 1,4-Dichlorobenzene | 0.50 | 0.31 J | 3.0 | 1.9 J |
| alpha-Chlorotoluene | 0.50 | 0.16 J | 2.6 | 0.80 J |
| 1,2-Dichlorobenzene | 0.50 | 0.27 J | 3.0 | 1.6 J |
| 1,2,4-Trichlorobenzene | 2.0 | 1.3 J | 15 | 9.4 J |
| Hexachlorobutadiene | 2.0 | 0.64 J | 21 | 6.8 J |
| Butane | 2.0 | Not Detected | 4.8 | Not Detected |
| Isopentane | 2.0 | Not Detected | 5.9 | Not Detected |

J = Estimated value.

**Container Type: NA - Not Applicable**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| Toluene-d8 | 99 | 70-130 |
| 1,2-Dichloroethane-d4 | 98 | 70-130 |
| 4-Bromofluorobenzene | 94 | 70-130 |

eurofins | Air Toxics

**Client Sample ID: Lab Blank**

**Lab ID#: 1302248A-15B**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p022006a** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 2/20/13 11:19 AM** | |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 0.50 | Not Detected | 2.5 | Not Detected |
| Freon 114 | 0.50 | Not Detected | 3.5 | Not Detected |
| Chloromethane | 5.0 | Not Detected | 10 | Not Detected |
| Vinyl Chloride | 0.50 | Not Detected | 1.3 | Not Detected |
| 1,3-Butadiene | 0.50 | Not Detected | 1.1 | Not Detected |
| Bromomethane | 5.0 | Not Detected | 19 | Not Detected |
| Chloroethane | 2.0 | Not Detected | 5.3 | Not Detected |
| Freon 11 | 0.50 | Not Detected | 2.8 | Not Detected |
| Ethanol | 2.0 | Not Detected | 3.8 | Not Detected |
| Freon 113 | 0.50 | Not Detected | 3.8 | Not Detected |
| 1,1-Dichloroethene | 0.50 | Not Detected | 2.0 | Not Detected |
| Acetone | 5.0 | Not Detected | 12 | Not Detected |
| 2-Propanol | 2.0 | Not Detected | 4.9 | Not Detected |
| Carbon Disulfide | 2.0 | 0.34 J | 6.2 | 1.1 J |
| 3-Chloropropene | 2.0 | Not Detected | 6.3 | Not Detected |
| Methylene Chloride | 5.0 | Not Detected | 17 | Not Detected |
| Methyl tert-butyl ether | 0.50 | Not Detected | 1.8 | Not Detected |
| trans-1,2-Dichloroethene | 0.50 | Not Detected | 2.0 | Not Detected |
| Hexane | 0.50 | Not Detected | 1.8 | Not Detected |
| 1,1-Dichloroethane | 0.50 | Not Detected | 2.0 | Not Detected |
| 2-Butanone (Methyl Ethyl Ketone) | 2.0 | Not Detected | 5.9 | Not Detected |
| cis-1,2-Dichloroethene | 0.50 | Not Detected | 2.0 | Not Detected |
| Tetrahydrofuran | 0.50 | Not Detected | 1.5 | Not Detected |
| Chloroform | 0.50 | Not Detected | 2.4 | Not Detected |
| 1,1,1-Trichloroethane | 0.50 | Not Detected | 2.7 | Not Detected |
| Cyclohexane | 0.50 | Not Detected | 1.7 | Not Detected |
| Carbon Tetrachloride | 0.50 | Not Detected | 3.1 | Not Detected |
| 2,2,4-Trimethylpentane | 0.50 | Not Detected | 2.3 | Not Detected |
| Benzene | 0.50 | Not Detected | 1.6 | Not Detected |
| 1,2-Dichloroethane | 0.50 | Not Detected | 2.0 | Not Detected |
| Heptane | 0.50 | Not Detected | 2.0 | Not Detected |
| Trichloroethene | 0.50 | Not Detected | 2.7 | Not Detected |
| 1,2-Dichloropropane | 0.50 | Not Detected | 2.3 | Not Detected |
| 1,4-Dioxane | 2.0 | Not Detected | 7.2 | Not Detected |
| Bromodichloromethane | 0.50 | Not Detected | 3.4 | Not Detected |
| cis-1,3-Dichloropropene | 0.50 | Not Detected | 2.3 | Not Detected |
| 4-Methyl-2-pentanone | 0.50 | Not Detected | 2.0 | Not Detected |
| Toluene | 0.50 | 0.066 J | 1.9 | 0.25 J |
| trans-1,3-Dichloropropene | 0.50 | Not Detected | 2.3 | Not Detected |
| 1,1,2-Trichloroethane | 0.50 | Not Detected | 2.7 | Not Detected |
| Tetrachloroethene | 0.50 | 0.071 J | 3.4 | 0.48 J |
| 2-Hexanone | 2.0 | Not Detected | 8.2 | Not Detected |

eurofins | Air Toxics

**Client Sample ID: Lab Blank**

**Lab ID#: 1302248A-15B**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p022006a** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 2/20/13 11:19 AM** | |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Dibromochloromethane | 0.50 | Not Detected | 4.2 | Not Detected |
| 1,2-Dibromoethane (EDB) | 0.50 | 0.13 J | 3.8 | 1.0 J |
| Chlorobenzene | 0.50 | 0.13 J | 2.3 | 0.59 J |
| Ethyl Benzene | 0.50 | Not Detected | 2.2 | Not Detected |
| m,p-Xylene | 0.50 | Not Detected | 2.2 | Not Detected |
| o-Xylene | 0.50 | 0.099 J | 2.2 | 0.43 J |
| Styrene | 0.50 | 0.11 J | 2.1 | 0.46 J |
| Bromoform | 0.50 | Not Detected | 5.2 | Not Detected |
| Cumene | 0.50 | 0.091 J | 2.4 | 0.44 J |
| 1,1,2,2-Tetrachloroethane | 0.50 | 0.18 J | 3.4 | 1.3 J |
| Propylbenzene | 0.50 | 0.15 J | 2.4 | 0.76 J |
| 4-Ethyltoluene | 0.50 | 0.097 J | 2.4 | 0.48 J |
| 1,3,5-Trimethylbenzene | 0.50 | 0.16 J | 2.4 | 0.76 J |
| 1,2,4-Trimethylbenzene | 0.50 | 0.18 J | 2.4 | 0.89 J |
| 1,3-Dichlorobenzene | 0.50 | 0.28 J | 3.0 | 1.7 J |
| 1,4-Dichlorobenzene | 0.50 | 0.33 J | 3.0 | 2.0 J |
| alpha-Chlorotoluene | 0.50 | 0.18 J | 2.6 | 0.95 J |
| 1,2-Dichlorobenzene | 0.50 | 0.26 J | 3.0 | 1.5 J |
| 1,2,4-Trichlorobenzene | 2.0 | 0.72 J | 15 | 5.3 J |
| Hexachlorobutadiene | 2.0 | 0.46 J | 21 | 4.9 J |
| Butane | 2.0 | Not Detected | 4.8 | Not Detected |
| Isopentane | 2.0 | Not Detected | 5.9 | Not Detected |

J = Estimated value.

**Container Type: NA - Not Applicable**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| Toluene-d8 | 98 | 70-130 |
| 1,2-Dichloroethane-d4 | 93 | 70-130 |
| 4-Bromofluorobenzene | 93 | 70-130 |

eurofins | Air Toxics

**Client Sample ID: CCV**
**Lab ID#: 1302248A-16A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | |
|---|---|---|
| **File Name:** | **p021902** | **Date of Collection: NA** |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 2/19/13 08:41 AM** |

| Compound | %Recovery |
|---|---|
| Freon 12 | 104 |
| Freon 114 | 102 |
| Chloromethane | 105 |
| Vinyl Chloride | 106 |
| 1,3-Butadiene | 104 |
| Bromomethane | 100 |
| Chloroethane | 104 |
| Freon 11 | 107 |
| Ethanol | 108 |
| Freon 113 | 103 |
| 1,1-Dichloroethene | 101 |
| Acetone | 100 |
| 2-Propanol | 96 |
| Carbon Disulfide | 100 |
| 3-Chloropropene | 96 |
| Methylene Chloride | 105 |
| Methyl tert-butyl ether | 100 |
| trans-1,2-Dichloroethene | 105 |
| Hexane | 106 |
| 1,1-Dichloroethane | 102 |
| 2-Butanone (Methyl Ethyl Ketone) | 97 |
| cis-1,2-Dichloroethene | 103 |
| Tetrahydrofuran | 106 |
| Chloroform | 103 |
| 1,1,1-Trichloroethane | 109 |
| Cyclohexane | 114 |
| Carbon Tetrachloride | 107 |
| 2,2,4-Trimethylpentane | 109 |
| Benzene | 108 |
| 1,2-Dichloroethane | 115 |
| Heptane | 119 |
| Trichloroethene | 90 |
| 1,2-Dichloropropane | 108 |
| 1,4-Dioxane | 109 |
| Bromodichloromethane | 109 |
| cis-1,3-Dichloropropene | 108 |
| 4-Methyl-2-pentanone | 121 |
| Toluene | 108 |
| trans-1,3-Dichloropropene | 114 |
| 1,1,2-Trichloroethane | 108 |
| Tetrachloroethene | 105 |
| 2-Hexanone | 108 |

eurofins | Air Toxics

**Client Sample ID: CCV**

**Lab ID#: 1302248A-16A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p021902** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 2/19/13 08:41 AM** | |

| Compound | %Recovery |
|---|---|
| Dibromochloromethane | 114 |
| 1,2-Dibromoethane (EDB) | 107 |
| Chlorobenzene | 100 |
| Ethyl Benzene | 112 |
| m,p-Xylene | 116 |
| o-Xylene | 116 |
| Styrene | 125 |
| Bromoform | 113 |
| Cumene | 121 |
| 1,1,2,2-Tetrachloroethane | 116 |
| Propylbenzene | 115 |
| 4-Ethyltoluene | 119 |
| 1,3,5-Trimethylbenzene | 121 |
| 1,2,4-Trimethylbenzene | 117 |
| 1,3-Dichlorobenzene | 109 |
| 1,4-Dichlorobenzene | 108 |
| alpha-Chlorotoluene | 117 |
| 1,2-Dichlorobenzene | 111 |
| 1,2,4-Trichlorobenzene | 104 |
| Hexachlorobutadiene | 108 |
| Butane | 102 |
| Isopentane | 104 |

**Container Type: NA - Not Applicable**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| Toluene-d8 | 105 | 70-130 |
| 1,2-Dichloroethane-d4 | 107 | 70-130 |
| 4-Bromofluorobenzene | 102 | 70-130 |

eurofins | Air Toxics

**Client Sample ID: CCV**
**Lab ID#: 1302248A-16B**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p022002** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 2/20/13 09:01 AM** | |

| Compound | %Recovery |
|---|---|
| Freon 12 | 96 |
| Freon 114 | 100 |
| Chloromethane | 95 |
| Vinyl Chloride | 104 |
| 1,3-Butadiene | 102 |
| Bromomethane | 97 |
| Chloroethane | 103 |
| Freon 11 | 96 |
| Ethanol | 106 |
| Freon 113 | 101 |
| 1,1-Dichloroethene | 104 |
| Acetone | 105 |
| 2-Propanol | 102 |
| Carbon Disulfide | 101 |
| 3-Chloropropene | 103 |
| Methylene Chloride | 101 |
| Methyl tert-butyl ether | 109 |
| trans-1,2-Dichloroethene | 106 |
| Hexane | 109 |
| 1,1-Dichloroethane | 100 |
| 2-Butanone (Methyl Ethyl Ketone) | 104 |
| cis-1,2-Dichloroethene | 111 |
| Tetrahydrofuran | 110 |
| Chloroform | 98 |
| 1,1,1-Trichloroethane | 100 |
| Cyclohexane | 117 |
| Carbon Tetrachloride | 98 |
| 2,2,4-Trimethylpentane | 114 |
| Benzene | 108 |
| 1,2-Dichloroethane | 98 |
| Heptane | 118 |
| Trichloroethene | 88 |
| 1,2-Dichloropropane | 107 |
| 1,4-Dioxane | 116 |
| Bromodichloromethane | 100 |
| cis-1,3-Dichloropropene | 108 |
| 4-Methyl-2-pentanone | 118 |
| Toluene | 105 |
| trans-1,3-Dichloropropene | 109 |
| 1,1,2-Trichloroethane | 107 |
| Tetrachloroethene | 104 |
| 2-Hexanone | 112 |

eurofins | Air Toxics

**Client Sample ID: CCV**

**Lab ID#: 1302248A-16B**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p022002** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 2/20/13 09:01 AM** | |

| Compound | %Recovery |
|---|---|
| Dibromochloromethane | 108 |
| 1,2-Dibromoethane (EDB) | 106 |
| Chlorobenzene | 100 |
| Ethyl Benzene | 112 |
| m,p-Xylene | 116 |
| o-Xylene | 117 |
| Styrene | 123 |
| Bromoform | 107 |
| Cumene | 118 |
| 1,1,2,2-Tetrachloroethane | 117 |
| Propylbenzene | 112 |
| 4-Ethyltoluene | 118 |
| 1,3,5-Trimethylbenzene | 120 |
| 1,2,4-Trimethylbenzene | 118 |
| 1,3-Dichlorobenzene | 107 |
| 1,4-Dichlorobenzene | 107 |
| alpha-Chlorotoluene | 113 |
| 1,2-Dichlorobenzene | 108 |
| 1,2,4-Trichlorobenzene | 104 |
| Hexachlorobutadiene | 102 |
| Butane | 101 |
| Isopentane | 105 |

**Container Type: NA - Not Applicable**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| Toluene-d8 | 104 | 70-130 |
| 1,2-Dichloroethane-d4 | 94 | 70-130 |
| 4-Bromofluorobenzene | 102 | 70-130 |

eurofins | Air Toxics

**Client Sample ID: LCS**
**Lab ID#: 1302248A-17A**
**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p021903** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 2/19/13 09:16 AM** | |

| Compound | %Recovery |
|---|---|
| Freon 12 | 105 |
| Freon 114 | 102 |
| Chloromethane | 112 |
| Vinyl Chloride | 109 |
| 1,3-Butadiene | 106 |
| Bromomethane | 99 |
| Chloroethane | 103 |
| Freon 11 | 104 |
| Ethanol | 81 |
| Freon 113 | 102 |
| 1,1-Dichloroethene | 107 |
| Acetone | 106 |
| 2-Propanol | 103 |
| Carbon Disulfide | 123 |
| 3-Chloropropene | 110 |
| Methylene Chloride | 104 |
| Methyl tert-butyl ether | 99 |
| trans-1,2-Dichloroethene | 119 |
| Hexane | 106 |
| 1,1-Dichloroethane | 102 |
| 2-Butanone (Methyl Ethyl Ketone) | 100 |
| cis-1,2-Dichloroethene | 105 |
| Tetrahydrofuran | 105 |
| Chloroform | 104 |
| 1,1,1-Trichloroethane | 107 |
| Cyclohexane | 115 |
| Carbon Tetrachloride | 104 |
| 2,2,4-Trimethylpentane | 109 |
| Benzene | 107 |
| 1,2-Dichloroethane | 109 |
| Heptane | 116 |
| Trichloroethene | 89 |
| 1,2-Dichloropropane | 106 |
| 1,4-Dioxane | 112 |
| Bromodichloromethane | 105 |
| cis-1,3-Dichloropropene | 106 |
| 4-Methyl-2-pentanone | 120 |
| Toluene | 103 |
| trans-1,3-Dichloropropene | 110 |
| 1,1,2-Trichloroethane | 106 |
| Tetrachloroethene | 102 |
| 2-Hexanone | 108 |

eurofins | Air Toxics

**Client Sample ID: LCS**

**Lab ID#: 1302248A-17A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p021903** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 2/19/13 09:16 AM** | |

| Compound | %Recovery |
|---|---|
| Dibromochloromethane | 109 |
| 1,2-Dibromoethane (EDB) | 107 |
| Chlorobenzene | 100 |
| Ethyl Benzene | 110 |
| m,p-Xylene | 115 |
| o-Xylene | 115 |
| Styrene | 120 |
| Bromoform | 104 |
| Cumene | 119 |
| 1,1,2,2-Tetrachloroethane | 117 |
| Propylbenzene | 113 |
| 4-Ethyltoluene | 109 |
| 1,3,5-Trimethylbenzene | 118 |
| 1,2,4-Trimethylbenzene | 115 |
| 1,3-Dichlorobenzene | 108 |
| 1,4-Dichlorobenzene | 107 |
| alpha-Chlorotoluene | 111 |
| 1,2-Dichlorobenzene | 111 |
| 1,2,4-Trichlorobenzene | 115 |
| Hexachlorobutadiene | 111 |
| Butane | 98 |
| Isopentane | 107 |

**Container Type: NA - Not Applicable**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| Toluene-d8 | 104 | 70-130 |
| 1,2-Dichloroethane-d4 | 103 | 70-130 |
| 4-Bromofluorobenzene | 99 | 70-130 |

eurofins | Air Toxics

**Client Sample ID: LCSD**

**Lab ID#: 1302248A-17AA**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p021904** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 2/19/13 09:37 AM** | |

| Compound | %Recovery |
|---|---|
| Freon 12 | 105 |
| Freon 114 | 104 |
| Chloromethane | 105 |
| Vinyl Chloride | 108 |
| 1,3-Butadiene | 106 |
| Bromomethane | 102 |
| Chloroethane | 105 |
| Freon 11 | 103 |
| Ethanol | 79 |
| Freon 113 | 106 |
| 1,1-Dichloroethene | 109 |
| Acetone | 110 |
| 2-Propanol | 105 |
| Carbon Disulfide | 126 |
| 3-Chloropropene | 123 |
| Methylene Chloride | 104 |
| Methyl tert-butyl ether | 104 |
| trans-1,2-Dichloroethene | 123 |
| Hexane | 109 |
| 1,1-Dichloroethane | 104 |
| 2-Butanone (Methyl Ethyl Ketone) | 104 |
| cis-1,2-Dichloroethene | 108 |
| Tetrahydrofuran | 110 |
| Chloroform | 104 |
| 1,1,1-Trichloroethane | 109 |
| Cyclohexane | 119 |
| Carbon Tetrachloride | 105 |
| 2,2,4-Trimethylpentane | 112 |
| Benzene | 108 |
| 1,2-Dichloroethane | 105 |
| Heptane | 114 |
| Trichloroethene | 89 |
| 1,2-Dichloropropane | 105 |
| 1,4-Dioxane | 112 |
| Bromodichloromethane | 103 |
| cis-1,3-Dichloropropene | 107 |
| 4-Methyl-2-pentanone | 120 |
| Toluene | 104 |
| trans-1,3-Dichloropropene | 110 |
| 1,1,2-Trichloroethane | 105 |
| Tetrachloroethene | 102 |
| 2-Hexanone | 108 |

eurofins | Air Toxics

**Client Sample ID: LCSD**

**Lab ID#: 1302248A-17AA**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p021904** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 2/19/13 09:37 AM** | |

| Compound | %Recovery |
|---|---|
| Dibromochloromethane | 108 |
| 1,2-Dibromoethane (EDB) | 107 |
| Chlorobenzene | 99 |
| Ethyl Benzene | 111 |
| m,p-Xylene | 116 |
| o-Xylene | 116 |
| Styrene | 119 |
| Bromoform | 106 |
| Cumene | 119 |
| 1,1,2,2-Tetrachloroethane | 117 |
| Propylbenzene | 114 |
| 4-Ethyltoluene | 112 |
| 1,3,5-Trimethylbenzene | 119 |
| 1,2,4-Trimethylbenzene | 114 |
| 1,3-Dichlorobenzene | 109 |
| 1,4-Dichlorobenzene | 106 |
| alpha-Chlorotoluene | 112 |
| 1,2-Dichlorobenzene | 111 |
| 1,2,4-Trichlorobenzene | 116 |
| Hexachlorobutadiene | 111 |
| Butane | 100 |
| Isopentane | 107 |

**Container Type: NA - Not Applicable**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| Toluene-d8 | 104 | 70-130 |
| 1,2-Dichloroethane-d4 | 102 | 70-130 |
| 4-Bromofluorobenzene | 100 | 70-130 |

eurofins | Air Toxics

**Client Sample ID: LCS**

**Lab ID#: 1302248A-17B**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p022003** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 2/20/13 09:33 AM** | |

| Compound | %Recovery |
|---|---|
| Freon 12 | 95 |
| Freon 114 | 101 |
| Chloromethane | 98 |
| Vinyl Chloride | 104 |
| 1,3-Butadiene | 100 |
| Bromomethane | 97 |
| Chloroethane | 102 |
| Freon 11 | 93 |
| Ethanol | 77 |
| Freon 113 | 99 |
| 1,1-Dichloroethene | 106 |
| Acetone | 108 |
| 2-Propanol | 100 |
| Carbon Disulfide | 120 |
| 3-Chloropropene | 118 |
| Methylene Chloride | 97 |
| Methyl tert-butyl ether | 105 |
| trans-1,2-Dichloroethene | 117 |
| Hexane | 116 |
| 1,1-Dichloroethane | 98 |
| 2-Butanone (Methyl Ethyl Ketone) | 102 |
| cis-1,2-Dichloroethene | 106 |
| Tetrahydrofuran | 104 |
| Chloroform | 96 |
| 1,1,1-Trichloroethane | 98 |
| Cyclohexane | 116 |
| Carbon Tetrachloride | 94 |
| 2,2,4-Trimethylpentane | 109 |
| Benzene | 103 |
| 1,2-Dichloroethane | 92 |
| Heptane | 112 |
| Trichloroethene | 84 |
| 1,2-Dichloropropane | 102 |
| 1,4-Dioxane | 111 |
| Bromodichloromethane | 95 |
| cis-1,3-Dichloropropene | 104 |
| 4-Methyl-2-pentanone | 117 |
| Toluene | 101 |
| trans-1,3-Dichloropropene | 106 |
| 1,1,2-Trichloroethane | 102 |
| Tetrachloroethene | 98 |
| 2-Hexanone | 103 |

eurofins | Air Toxics

**Client Sample ID: LCS**

**Lab ID#: 1302248A-17B**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p022003** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 2/20/13 09:33 AM** | |

| Compound | %Recovery |
|---|---|
| Dibromochloromethane | 100 |
| 1,2-Dibromoethane (EDB) | 101 |
| Chlorobenzene | 97 |
| Ethyl Benzene | 105 |
| m,p-Xylene | 111 |
| o-Xylene | 113 |
| Styrene | 116 |
| Bromoform | 99 |
| Cumene | 112 |
| 1,1,2,2-Tetrachloroethane | 112 |
| Propylbenzene | 107 |
| 4-Ethyltoluene | 106 |
| 1,3,5-Trimethylbenzene | 113 |
| 1,2,4-Trimethylbenzene | 111 |
| 1,3-Dichlorobenzene | 103 |
| 1,4-Dichlorobenzene | 101 |
| alpha-Chlorotoluene | 107 |
| 1,2-Dichlorobenzene | 104 |
| 1,2,4-Trichlorobenzene | 107 |
| Hexachlorobutadiene | 101 |
| Butane | 92 |
| Isopentane | 102 |

**Container Type: NA - Not Applicable**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| Toluene-d8 | 103 | 70-130 |
| 1,2-Dichloroethane-d4 | 93 | 70-130 |
| 4-Bromofluorobenzene | 99 | 70-130 |

eurofins | Air Toxics

**Client Sample ID: LCSD**

**Lab ID#: 1302248A-17BB**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p022004** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 2/20/13 09:53 AM** | |

| Compound | %Recovery |
|---|---|
| Freon 12 | 92 |
| Freon 114 | 97 |
| Chloromethane | 100 |
| Vinyl Chloride | 103 |
| 1,3-Butadiene | 97 |
| Bromomethane | 95 |
| Chloroethane | 100 |
| Freon 11 | 91 |
| Ethanol | 77 |
| Freon 113 | 98 |
| 1,1-Dichloroethene | 106 |
| Acetone | 103 |
| 2-Propanol | 96 |
| Carbon Disulfide | 119 |
| 3-Chloropropene | 118 |
| Methylene Chloride | 95 |
| Methyl tert-butyl ether | 105 |
| trans-1,2-Dichloroethene | 116 |
| Hexane | 105 |
| 1,1-Dichloroethane | 96 |
| 2-Butanone (Methyl Ethyl Ketone) | 102 |
| cis-1,2-Dichloroethene | 108 |
| Tetrahydrofuran | 104 |
| Chloroform | 96 |
| 1,1,1-Trichloroethane | 97 |
| Cyclohexane | 114 |
| Carbon Tetrachloride | 93 |
| 2,2,4-Trimethylpentane | 108 |
| Benzene | 104 |
| 1,2-Dichloroethane | 91 |
| Heptane | 110 |
| Trichloroethene | 84 |
| 1,2-Dichloropropane | 101 |
| 1,4-Dioxane | 109 |
| Bromodichloromethane | 94 |
| cis-1,3-Dichloropropene | 103 |
| 4-Methyl-2-pentanone | 114 |
| Toluene | 100 |
| trans-1,3-Dichloropropene | 104 |
| 1,1,2-Trichloroethane | 102 |
| Tetrachloroethene | 98 |
| 2-Hexanone | 104 |

eurofins | Air Toxics

**Client Sample ID: LCSD**

**Lab ID#: 1302248A-17BB**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p022004** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 2/20/13 09:53 AM** | |

| Compound | %Recovery |
|---|---|
| Dibromochloromethane | 100 |
| 1,2-Dibromoethane (EDB) | 102 |
| Chlorobenzene | 98 |
| Ethyl Benzene | 108 |
| m,p-Xylene | 112 |
| o-Xylene | 114 |
| Styrene | 116 |
| Bromoform | 99 |
| Cumene | 114 |
| 1,1,2,2-Tetrachloroethane | 114 |
| Propylbenzene | 108 |
| 4-Ethyltoluene | 107 |
| 1,3,5-Trimethylbenzene | 113 |
| 1,2,4-Trimethylbenzene | 111 |
| 1,3-Dichlorobenzene | 105 |
| 1,4-Dichlorobenzene | 104 |
| alpha-Chlorotoluene | 106 |
| 1,2-Dichlorobenzene | 106 |
| 1,2,4-Trichlorobenzene | 112 |
| Hexachlorobutadiene | 103 |
| Butane | 92 |
| Isopentane | 99 |

**Container Type: NA - Not Applicable**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| Toluene-d8 | 101 | 70-130 |
| 1,2-Dichloroethane-d4 | 90 | 70-130 |
| 4-Bromofluorobenzene | 102 | 70-130 |

# Shell Oil Products Chain Of Custody Record

URS

Air Toxics LTD.
**Project Name: Roxana Soil Vapor**
**Project # 21562850.04001**
Lab Vendor #

Please Check Appropriate Box:
☑ ENV. SERVICES ☐ MOTIVA RETAIL ☐ SHELL RETAIL
☐ MOTIVA SC&CH ☐ CONSULTANT ☐ LUBES
☐ SHELL PIPELINE ☐ OTHER

Print Bill To Contact Name: Robert Mooshegian
PO #:
INCIDENT # (ENV SERVICES): 9 7 2 1 6 6 4 0
SAP #: 3 4 0 0 6 1
☐ CHECK IF NO INCIDENT # APPLIES
DATE: 02/13/13
PAGE: 1 of 2

SAMPLING COMPANY: URS CORPORATION
LOG CODE:
ADDRESS: 1001 HIGHLANDS PLAZA DRIVE WEST - SUITE 300; ST. LOUIS, MO 63110
Laboratory Address: Air Toxics, LTD 180 Blue Ravine Road Suite B, Folsom, CA 95630-4719
TELEPHONE: 314-429-0100
FAX: 314-429-0462
Bill To Contact E-MAIL: Robert.Mooshegian@urs.com

SITE ADDRESS: Street and City: 900 SOUTH CENTRAL AVE -- ROXANA
State: IL
GLOBAL ID NO.:
EDF DELIVERABLE TO (Name, Company, Office Location): Elizabeth Kunkel, URS, St. Louis
PHONE NO: 314-743-4179
E-MAIL: Elizabeth.Kunkel@URSCorp.com
CONSULTANT PROJECT NAME/#: Roxana Soil Vapor

TURNAROUND TIME (CALENDAR DAYS):
☑ STANDARD (14 DAY) ☐ 5 DAYS ☐ 3 DAYS ☐ 2 DAYS ☐ 24 HOURS ☐ RESULTS NEEDED ON WEEKEND

REQUESTED ANALYSIS

☐ LA - RWQCB REPORT FORMAT ☑ UST AGENCY:
DELIVERABLES: ☐ LEVEL 1 ☐ LEVEL 2 ☐ LEVEL 3 ☑ LEVEL 4 ☐ OTHER (SPECIFY)

☑ SHELL CONTRACT RATE APPLIES
☐ STATE REIMBURSEMENT RATE APPLIES
☐ EDD NOT NEEDED
☑ RECEIPT VERIFICATION REQUESTED

Turn Around Time: ☑ Normal ☐ Rush ☐ Specify

*Lab Use Only*
Pressurized by:
Date:
Pressurization Gas: $N_2$ He

| LAB USE ONLY | Field Sample Identification | SAMPLING DATE | SAMPLING TIME | Canister Number | Canister Pressure/Vacuum Initial | Final | Receipt | Final (psi) | Modified TO-15 + Butane & Isopentane | ASTM D-1946 + Helium | ASTM D-1946 | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | VMP-3-10-020613 | 02/06/13 | 1527-1557 | 37338 | -29.5 | -10 | | | X | X | | | | | | |
| | VMP-3-22-020613 | 02/06/13 | 1437-1507 | 34633 | -30 | -9.5 | | | X | X | | | | | | |
| | VMP-4-5-020713 | 02/07/13 | 0909-0938 | 34576 | -27.5 | -6.5 | | | X | X | | | | | | |
| | VMP-4-12-020713 | 02/07/13 | 1000-1030 | 37372 | -28 | -8 | | | X | X | | | | | | |
| | VMP-4-12-020713-DUP | 02/07/13 | 1000-1030 | 36533 | -30 | -9 | | | X | X | | | | | | |
| | VMP-6-5-021213 | 02/12/13 | 1308-1338 | 9388 | -30 | -7 | | | X | X | | | | | | |
| | VMP-20-5-020713 | 02/07/13 | 1505-1535 | 33644 | -30 | -8 | | | X | X | | | | | | |
| | VMP-21-5-020613 | 02/06/13 | 1421-1450 | 31763 | -30 | -8.5 | | | X | X | | | | | | |
| | VMP-31-5-021113 | 02/11/13 | 1001-1031 | 38443 | -30 | -8 | | | X | X | | | | | | |
| | VMP-54-20-020513 | 02/06/13 | 1430-1501 | 11430 | -30 | -10 | | | X | X | | | | | | |

**ADDITIONAL NOTES:**
- 14 day hold time
- Report results between MDL and RL
- Level IV ECVP

| Relinquished by (Signature) | Received by: (Signature) | Date | Time |
|---|---|---|---|
| Cynthia Krejs | FEDEX | 02/13/13 | 1730 |
| Relinquished by (Signature) | Received by: (Signature) | Date | Time |
| | | 2/14/13 | 0945 |
| Relinquished by (Signature) | Received by: (Signature) | Date | Time |
| | | | |

05/2008 Revision

Custody Seal Intact? Y N None Temp N/A

1372248

# Shell Oil Products Chain Of Custody Record

URS

Air Toxics LTD.
**Project Name: Roxana Soil Vapor**
**Project # 21562850.04001**
Lab Vendor #

**Please Check Appropriate Box:**
☑ ENV. SERVICES ☐ MOTIVA RETAIL ☐ SHELL RETAIL
☐ MOTIVA SD&CH ☐ CONSULTANT ☐ LUBES
☐ SHELL PIPELINE ☐ OTHER

Print Bill To Contact Name: Robert Mooshegian
INCIDENT # (ENV SERVICES): 9 7 2 1 6 6 4 0
☐ CHECK IF NO INCIDENT # APPLIES
DATE: 02/13/13
PAGE: 2 of 2
PO #:
SAP #: 3 4 0 0 6 1

SAMPLING COMPANY: URS CORPORATION
LOC CODE:
SITE ADDRESS: Street and City: 900 SOUTH CENTRAL AVE – ROXANA
State: IL
GLOBAL ID NO.:
ADDRESS: 1001 HIGHLANDS PLAZA DRIVE WEST - SUITE 300; ST. LOUIS, MO 63110
PROJ. DELIVERABLE'S TO (Name, Company, Office Location): Elizabeth Kunkel, URS, St. Louis
PHONE NO.: 314-743-4179
E-MAIL: Elizabeth_Kunkel@URSCorp.com
CONSULTANT PROJECT NAME/#: Roxana Soil Vapor
Laboratory Address: Air Toxics, LTD 180 Blue Ravine Road, Suite B, Folsom, CA 95630-4719
TELEPHONE: 314-429-0100
FAX: 314-429-0462
Bill To Contact E-MAIL: Robert.Mooshegian@urs.com

TURNAROUND TIME (CALENDAR DAYS)
☑ STANDARD (14 DAY) ☐ 5 DAYS ☐ 3 DAYS ☐ 2 DAYS ☐ 24 HOURS ☐ RESULTS NEEDED ON WEEKEND

REQUESTED ANALYSIS

☐ LA - RWQCB REPORT FORMAT ☑ UST AGENCY:
DELIVERABLES: ☐ LEVEL 1 ☐ LEVEL 2 ☐ LEVEL 3 ☑ LEVEL 4 ☐ OTHER (SPECIFY)

☑ SHELL CONTRACT RATE APPLIES
☐ STATE REIMBURSEMENT RATE APPLIES
☐ EDD NOT NEEDED
☑ RECEIPT VERIFICATION REQUESTED

| LAB USE ONLY | Field Sample Identification | SAMPLING DATE | SAMPLING TIME | Canister Number | Canister Pressure/Vacuum Initial | Final | Receipt | Final (psi) | Modified TO-15 + Butane & Isopentane | ASTM D-1946 + Helium | ASTM D-1946 | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| 1 | VMP-54-20-020613-DUP | 02/06/13 | 1430-1501 | 2070 | -30 | -10 | | | X | X | | | | | |
| 2 | VMP-54-30-020613 | 02/06/13 | 1525-1555 | 34097 | -30 | -11.5 | | | X | X | | | | | |
| 3 | VMP-54-30-020613-DUP | 02/06/13 | 1525-1555 | 37771 | -30 | -12 | | | X | X | | | | | |
| 4 | VMP-7-13.5-021313 | 02/13/13 | 1022-1052 | 36393 | -30 | -9.5 | | | X | X | | | | | |
| | | | | | | | | | X | X | | | | | |
| | | | | | | | | | X | X | | | | | |
| | | | | | | | | | X | X | | | | | |
| | | | | | | | | | X | X | | | | | |
| | | | | | | | | | X | X | | | | | |
| | | | | | | | | | X | X | | | | | |

Turn Around Time: ☑ Normal ☐ Rush
Specify

*Lab Use Only*
Pressurized by:
Date:
Pressurization Gas: $N_2$ He

**ADDITIONAL NOTES:**
- 14 day hold time
- Report results between MDL and RL
- Level IV ECVP

| | | | |
|---|---|---|---|
| Relinquished by: (Signature) | Received by: (Signature) FEDEX | Date: 02/13/13 | Time: 1730 |
| Relinquished by: (Signature) | Received by: (Signature) AR 2/14/13 | Date: 0945 | Time: |
| Relinquished by: (Signature) | Received by: (Signature) | Date: | Time: |

08/2008 Revision

Custody Seal Intact? Y N None Temp 1.2 fedex

1302248

eurofins | Air Toxics

2/28/2013
Ms. Elizabeth Kunkel
URS Corporation
1001 Highlands Plaza Dr. West
Suite 300
St. Louis MO 63110

Project Name: Roxana Soil Vapor
Project #: 21562850.04001
Workorder #: 1302248B

Dear Ms. Elizabeth Kunkel

The following report includes the data for the above referenced project for sample(s) received on 2/14/2013 at Air Toxics Ltd.

The data and associated QC analyzed by Modified ASTM D-1946 are compliant with the project requirements or laboratory criteria with the exception of the deviations noted in the attached case narrative.

Thank you for choosing Air Toxics Ltd. for your air analysis needs. Air Toxics Ltd. is committed to providing accurate data of the highest quality. Please feel free to contact the Project Manager: Kelly Buettner at 916-985-1000 if you have any questions regarding the data in this report.

Regards,

Kelly Buettner

Project Manager

REVIEWED
ON
3/26/13

eurofins | Air Toxics

# WORK ORDER #: 1302248B

Work Order Summary

| | | | |
|---|---|---|---|
| **CLIENT:** | Ms. Elizabeth Kunkel<br>URS Corporation<br>1001 Highlands Plaza Dr. West<br>Suite 300<br>St. Louis, MO 63110 | **BILL TO:** | Accounts Payable Austin<br>URS Corporation<br>P.O. BOX 203970<br>Austin, TX 78720-1088 |
| **PHONE:** | 314-743-4179 | **P.O. #** | 21562735.00013 |
| **FAX:** | | **PROJECT #** | 21562850.04001 Roxana Soil Vapor |
| **DATE RECEIVED:** | 02/14/2013 | **CONTACT:** | Kelly Buettner |
| **DATE COMPLETED:** | 02/28/2013 | | |

| FRACTION # | NAME | TEST | RECEIPT VAC./PRES. | FINAL PRESSURE |
|---|---|---|---|---|
| 01A | VMP-3-10-020613 | Modified ASTM D-1946 | 8.5 "Hg | 15 psi |
| 02A | VMP-3-22-020613 | Modified ASTM D-1946 | 9.0 "Hg | 15 psi |
| 03A | VMP-4-5-020713 | Modified ASTM D-1946 | 5.5 "Hg | 15 psi |
| 04A | VMP-4-12-020713 | Modified ASTM D-1946 | 7.5 "Hg | 15 psi |
| 05A | VMP-4-12-020713-DUP | Modified ASTM D-1946 | 8.0 "Hg | 15 psi |
| 06A | VMP-6-5-021213 | Modified ASTM D-1946 | 5.5 "Hg | 15 psi |
| 07A | VMP-20-5-020713 | Modified ASTM D-1946 | 5.5 "Hg | 15 psi |
| 08A | VMP-21-5-020613 | Modified ASTM D-1946 | 8.5 "Hg | 15 psi |
| 09A | VMP-31-5-021113 | Modified ASTM D-1946 | 6.5 "Hg | 15 psi |
| 10A | VMP-54-20-020613 | Modified ASTM D-1946 | 8.0 "Hg | 15 psi |
| 11A | VMP-54-20-020613-DUP | Modified ASTM D-1946 | 8.0 "Hg | 15 psi |
| 12A | VMP-54-30-020613 | Modified ASTM D-1946 | 9.5 "Hg | 15 psi |
| 13A | VMP-54-30-020613-DUP | Modified ASTM D-1946 | 9.5 "Hg | 15 psi |
| 14A | VMP-7-13.5-021313 | Modified ASTM D-1946 | 8.0 "Hg | 15 psi |
| 15A | Lab Blank | Modified ASTM D-1946 | NA | NA |
| 15B | Lab Blank | Modified ASTM D-1946 | NA | NA |
| 16A | LCS | Modified ASTM D-1946 | NA | NA |
| 16AA | LCSD | Modified ASTM D-1946 | NA | NA |

CERTIFIED BY: Heidi Hayes DATE: 02/28/13

Technical Director

Certification numbers: AZ Licensure AZ0775, CA NELAP - 12282CA, NY NELAP - 11291, TX NELAP - T104704434-12-4, UT NELAP CA009332012-3, WA NELAP - C935
Name of Accrediting Agency: NELAP/ORELAP (Oregon Environmental Laboratory Accreditation Program)
Accreditation number: CA300005, Effective date: 10/18/2012, Expiration date: 10/17/2013.
Eurofins Air Toxics Ltd. certifies that the test results contained in this report meet all requirements of the NELAC standards

This report shall not be reproduced, except in full, without the written approval of Eurofins Air Toxics, Inc.

180 BLUE RAVINE ROAD, SUITE B FOLSOM, CA - 9563
(916) 985-1000 . (800) 985-5955 . FAX (916) 985-1020

**LABORATORY NARRATIVE**
**Modified ASTM D-1946**
**URS Corporation**
**Workorder# 1302248B**

Fourteen 1 Liter Summa Canister samples were received on February 14, 2013. The laboratory performed analysis via Modified ASTM Method D-1946 for Methane and fixed gases in air using GC/FID or GC/TCD. The method involves direct injection of 1.0 mL of sample.

On the analytical column employed for this analysis, Oxygen coelutes with Argon. The corresponding peak is quantitated as Oxygen.

Since Nitrogen is used to pressurize samples, the reported Nitrogen values are calculated by adding all the sample components and subtracting from 100%.

Method modifications taken to run these samples are summarized in the table below. Specific project requirements may over-ride the ATL modifications.

| *Requirement* | *ASTM D-1946* | *ATL Modifications* |
|---|---|---|
| Calibration | A single point calibration is performed using a reference standard closely matching the composition of the unknown. | A 3-point calibration curve is performed. Quantitation is based on a daily calibration standard which may or may not resemble the composition of the associated samples. |
| Reference Standard | The composition of any reference standard must be known to within 0.01 mol % for any component. | The standards used by ATL are blended to a >/= 95% accuracy. |
| Sample Injection Volume | Components whose concentrations are in excess of 5 % should not be analyzed by using sample volumes greater than 0.5 mL. | The sample container is connected directly to a fixed volume sample loop of 1.0 mL on the GC. Linear range is defined by the calibration curve. Bags are loaded by vacuum. |
| Normalization | Normalize the mole percent values by multiplying each value by 100 and dividing by the sum of the original values. The sum of the original values should not differ from 100% by more than 1.0%. | Results are not normalized. The sum of the reported values can differ from 100% by as much as 15%, either due to analytical variability or an unusual sample matrix. |
| Precision | Precision requirements established at each concentration level. | Duplicates should agree within 25% RPD for detections > 5 X's the RL. |

**Receiving Notes**

There were no receiving discrepancies.

**Analytical Notes**

As per project specific client request the laboratory has reported estimated values for target compound hits that are below the Reporting Limit but greater than the Method Detection Limit. Concentrations that are below the level at which the canister was certified may be false positives.

The reporting limit for Carbon Monoxide was raised from 0.010% to 0.050%.

**Definition of Data Qualifying Flags**

Seven qualifiers may have been used on the data analysis sheets and indicate as follows:
B - Compound present in laboratory blank greater than reporting limit.
J - Estimated value.
E - Exceeds instrument calibration range.
S - Saturated peak.
Q - Exceeds quality control limits.
U - Compound analyzed for but not detected above the detection limit.
M - Reported value may be biased due to apparent matrix interferences.
File extensions may have been used on the data analysis sheets and indicates as follows:
a-File was requantified
b-File was quantified by a second column and detector
r1-File was requantified for the purpose of reissue

eurofins | Air Toxics

# Summary of Detected Compounds
# NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1946

**Client Sample ID: VMP-3-10-020613**

**Lab ID#: 1302248B-01A**

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.28 | 21 |
| Nitrogen | 0.28 | 79 |
| Methane | 0.00028 | 0.000039 J |
| Carbon Dioxide | 0.028 | 0.34 |

**Client Sample ID: VMP-3-22-020613**

**Lab ID#: 1302248B-02A**

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.29 | 18 |
| Nitrogen | 0.29 | 79 |
| Methane | 0.00029 | 0.00028 J |
| Carbon Dioxide | 0.029 | 2.6 |

**Client Sample ID: VMP-4-5-020713**

**Lab ID#: 1302248B-03A**

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.33 | 21 |
| Nitrogen | 0.33 | 79 |
| Methane | 0.00033 | 0.00016 J |
| Carbon Dioxide | 0.033 | 0.24 |

**Client Sample ID: VMP-4-12-020713**

**Lab ID#: 1302248B-04A**

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.27 | 20 |
| Nitrogen | 0.27 | 79 |
| Methane | 0.00027 | 0.00036 |
| Carbon Dioxide | 0.027 | 0.61 |
| Helium | 0.13 | 0.055 J |

eurofins | Air Toxics

# Summary of Detected Compounds
# NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1946

**Client Sample ID: VMP-4-12-020713-DUP**

**Lab ID#: 1302248B-05A**

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.28 | 20 |
| Nitrogen | 0.28 | 79 |
| Methane | 0.00028 | 0.00034 |
| Carbon Dioxide | 0.028 | 0.61 |
| Helium | 0.14 | 0.038 J |

**Client Sample ID: VMP-6-5-021213**

**Lab ID#: 1302248B-06A**

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.25 | 21 |
| Nitrogen | 0.25 | 79 |
| Methane | 0.00025 | 0.00012 J |
| Carbon Dioxide | 0.025 | 0.086 |

**Client Sample ID: VMP-20-5-020713**

**Lab ID#: 1302248B-07A**

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.25 | 18 |
| Nitrogen | 0.25 | 78 |
| Methane | 0.00025 | 0.000078 J |
| Carbon Dioxide | 0.025 | 3.8 |

**Client Sample ID: VMP-21-5-020613**

**Lab ID#: 1302248B-08A**

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.28 | 20 |
| Nitrogen | 0.28 | 79 |
| Methane | 0.00028 | 0.000023 J |
| Carbon Dioxide | 0.028 | 0.92 |

eurofins | Air Toxics

# Summary of Detected Compounds
# NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1946

**Client Sample ID: VMP-21-5-020613**

**Lab ID#: 1302248B-08A**

| | | |
|---|---|---|
| Helium | 0.14 | 0.035 J |

**Client Sample ID: VMP-31-5-021113**

**Lab ID#: 1302248B-09A**

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.26 | 20 |
| Nitrogen | 0.26 | 80 |
| Methane | 0.00026 | 0.00012 J |
| Carbon Dioxide | 0.026 | 0.16 |
| Helium | 0.13 | 0.29 |

**Client Sample ID: VMP-54-20-020613**

**Lab ID#: 1302248B-10A**

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.28 | 15 |
| Nitrogen | 0.28 | 80 |
| Carbon Dioxide | 0.028 | 4.7 |
| Helium | 0.14 | 0.039 J |

**Client Sample ID: VMP-54-20-020613-DUP**

**Lab ID#: 1302248B-11A**

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.28 | 15 |
| Nitrogen | 0.28 | 80 |
| Methane | 0.00028 | 0.000022 J |
| Carbon Dioxide | 0.028 | 4.6 |
| Helium | 0.14 | 0.035 J |

**Client Sample ID: VMP-54-30-020613**

**Lab ID#: 1302248B-12A**

eurofins | Air Toxics

# Summary of Detected Compounds
# NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1946

**Client Sample ID: VMP-54-30-020613**

**Lab ID#: 1302248B-12A**

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.30 | 14 |
| Nitrogen | 0.30 | 81 |
| Methane | 0.00030 | 0.000042 J |
| Carbon Dioxide | 0.030 | 5.3 |
| Helium | 0.15 | 0.032 J |

**Client Sample ID: VMP-54-30-020613-DUP**

**Lab ID#: 1302248B-13A**

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.30 | 14 |
| Nitrogen | 0.30 | 81 |
| Methane | 0.00030 | 0.000051 J |
| Carbon Dioxide | 0.030 | 5.4 |
| Helium | 0.15 | 0.028 J |

**Client Sample ID: VMP-7-13.5-021313**

**Lab ID#: 1302248B-14A**

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.28 | 20 |
| Nitrogen | 0.28 | 80 |
| Methane | 0.00028 | 0.000024 J |
| Carbon Dioxide | 0.028 | 0.23 |
| Helium | 0.14 | 0.022 J |

eurofins | Air Toxics

**Client Sample ID: VMP-3-10-020613**

**Lab ID#: 1302248B-01A**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1946**

| | | | |
|---|---|---|---|
| **File Name:** | **9022005** | **Date of Collection:** | **2/6/13 3:57:00 PM** |
| **Dil. Factor:** | **2.82** | **Date of Analysis:** | **2/20/13 10:24 AM** |

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.28 | 21 |
| Nitrogen | 0.28 | 79 |
| Carbon Monoxide | 0.14 | Not Detected |
| Methane | 0.00028 | 0.000039 J |
| Carbon Dioxide | 0.028 | 0.34 |
| Ethane | 0.0028 | Not Detected |
| Ethene | 0.0028 | Not Detected |
| Helium | 0.14 | Not Detected |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

eurofins | Air Toxics

**Client Sample ID: VMP-3-22-020613**

**Lab ID#: 1302248B-02A**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1946**

| | | | |
|---|---|---|---|
| **File Name:** | **9022006** | **Date of Collection:** | **2/6/13 3:07:00 PM** |
| **Dil. Factor:** | **2.89** | **Date of Analysis:** | **2/20/13 10:52 AM** |

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.29 | 18 |
| Nitrogen | 0.29 | 79 |
| Carbon Monoxide | 0.14 | Not Detected |
| Methane | 0.00029 | 0.00028 J |
| Carbon Dioxide | 0.029 | 2.6 |
| Ethane | 0.0029 | Not Detected |
| Ethene | 0.0029 | Not Detected |
| Helium | 0.14 | Not Detected |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

eurofins | Air Toxics

**Client Sample ID: VMP-4-5-020713**

**Lab ID#: 1302248B-03A**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1946**

| | | | |
|---|---|---|---|
| **File Name:** | **9022009** | **Date of Collection:** | **2/7/13 9:38:00 AM** |
| **Dil. Factor:** | **3.26** | **Date of Analysis:** | **2/20/13 12:04 PM** |

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.33 | 21 |
| Nitrogen | 0.33 | 79 |
| Carbon Monoxide | 0.16 | Not Detected |
| Methane | 0.00033 | 0.00016 J |
| Carbon Dioxide | 0.033 | 0.24 |
| Ethane | 0.0033 | Not Detected |
| Ethene | 0.0033 | Not Detected |
| Helium | 0.16 | Not Detected |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

eurofins | Air Toxics

**Client Sample ID: VMP-4-12-020713**

**Lab ID#: 1302248B-04A**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1946**

| | | | |
|---|---|---|---|
| **File Name:** | **9022007** | **Date of Collection:** | **2/7/13 10:30:00 AM** |
| **Dil. Factor:** | **2.69** | **Date of Analysis:** | **2/20/13 11:16 AM** |

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.27 | 20 |
| Nitrogen | 0.27 | 79 |
| Carbon Monoxide | 0.13 | Not Detected |
| Methane | 0.00027 | 0.00036 |
| Carbon Dioxide | 0.027 | 0.61 |
| Ethane | 0.0027 | Not Detected |
| Ethene | 0.0027 | Not Detected |
| Helium | 0.13 | 0.055 J |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

eurofins | Air Toxics

**Client Sample ID: VMP-4-12-020713-DUP**

**Lab ID#: 1302248B-05A**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1946**

| | | | |
|---|---|---|---|
| **File Name:** | **9022008** | **Date of Collection:** | **2/7/13 10:30:00 AM** |
| **Dil. Factor:** | **2.76** | **Date of Analysis:** | **2/20/13 11:43 AM** |

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.28 | 20 |
| Nitrogen | 0.28 | 79 |
| Carbon Monoxide | 0.14 | Not Detected |
| Methane | 0.00028 | 0.00034 |
| Carbon Dioxide | 0.028 | 0.61 |
| Ethane | 0.0028 | Not Detected |
| Ethene | 0.0028 | Not Detected |
| Helium | 0.14 | 0.038 J |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

eurofins | Air Toxics

**Client Sample ID: VMP-6-5-021213**

**Lab ID#: 1302248B-06A**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1946**

| | | | |
|---|---|---|---|
| **File Name:** | **9022010** | **Date of Collection:** | **2/12/13 1:38:00 PM** |
| **Dil. Factor:** | **2.47** | **Date of Analysis:** | **2/20/13 12:32 PM** |

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.25 | 21 |
| Nitrogen | 0.25 | 79 |
| Carbon Monoxide | 0.12 | Not Detected |
| Methane | 0.00025 | 0.00012 J |
| Carbon Dioxide | 0.025 | 0.086 |
| Ethane | 0.0025 | Not Detected |
| Ethene | 0.0025 | Not Detected |
| Helium | 0.12 | Not Detected |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

eurofins | Air Toxics

**Client Sample ID: VMP-20-5-020713**

**Lab ID#: 1302248B-07A**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1946**

| | | | |
|---|---|---|---|
| **File Name:** | **9022011** | **Date of Collection:** | **2/7/13 3:35:00 PM** |
| **Dil. Factor:** | **2.47** | **Date of Analysis:** | **2/20/13 01:23 PM** |

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.25 | 18 |
| Nitrogen | 0.25 | 78 |
| Carbon Monoxide | 0.12 | Not Detected |
| Methane | 0.00025 | 0.000078 J |
| Carbon Dioxide | 0.025 | 3.8 |
| Ethane | 0.0025 | Not Detected |
| Ethene | 0.0025 | Not Detected |
| Helium | 0.12 | Not Detected |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

eurofins | Air Toxics

**Client Sample ID: VMP-21-5-020613**

**Lab ID#: 1302248B-08A**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1946**

| | | | |
|---|---|---|---|
| **File Name:** | **9022012** | **Date of Collection:** | **2/6/13 2:50:00 PM** |
| **Dil. Factor:** | **2.82** | **Date of Analysis:** | **2/20/13 01:48 PM** |

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.28 | 20 |
| Nitrogen | 0.28 | 79 |
| Carbon Monoxide | 0.14 | Not Detected |
| Methane | 0.00028 | 0.000023 J |
| Carbon Dioxide | 0.028 | 0.92 |
| Ethane | 0.0028 | Not Detected |
| Ethene | 0.0028 | Not Detected |
| Helium | 0.14 | 0.035 J |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

eurofins | Air Toxics

**Client Sample ID: VMP-31-5-021113**

**Lab ID#: 1302248B-09A**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1946**

| | | | |
|---|---|---|---|
| **File Name:** | **9022013** | **Date of Collection:** | **2/11/13 10:31:00 AM** |
| **Dil. Factor:** | **2.58** | **Date of Analysis:** | **2/20/13 02:11 PM** |

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.26 | 20 |
| Nitrogen | 0.26 | 80 |
| Carbon Monoxide | 0.13 | Not Detected |
| Methane | 0.00026 | 0.00012 J |
| Carbon Dioxide | 0.026 | 0.16 |
| Ethane | 0.0026 | Not Detected |
| Ethene | 0.0026 | Not Detected |
| Helium | 0.13 | 0.29 |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

eurofins | Air Toxics

**Client Sample ID: VMP-54-20-020613**

**Lab ID#: 1302248B-10A**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1946**

| | | | |
|---|---|---|---|
| **File Name:** | **9022014** | **Date of Collection:** | **2/6/13 3:01:00 PM** |
| **Dil. Factor:** | **2.76** | **Date of Analysis:** | **2/20/13 02:35 PM** |

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.28 | 15 |
| Nitrogen | 0.28 | 80 |
| Carbon Monoxide | 0.14 | Not Detected |
| Methane | 0.00028 | Not Detected |
| Carbon Dioxide | 0.028 | 4.7 |
| Ethane | 0.0028 | Not Detected |
| Ethene | 0.0028 | Not Detected |
| Helium | 0.14 | 0.039 J |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

eurofins | Air Toxics

**Client Sample ID: VMP-54-20-020613-DUP**

**Lab ID#: 1302248B-11A**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1946**

| | | | |
|---|---|---|---|
| **File Name:** | **9022015** | **Date of Collection:** | **2/6/13 3:01:00 PM** |
| **Dil. Factor:** | **2.76** | **Date of Analysis:** | **2/20/13 03:10 PM** |

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.28 | 15 |
| Nitrogen | 0.28 | 80 |
| Carbon Monoxide | 0.14 | Not Detected |
| Methane | 0.00028 | 0.000022 J |
| Carbon Dioxide | 0.028 | 4.6 |
| Ethane | 0.0028 | Not Detected |
| Ethene | 0.0028 | Not Detected |
| Helium | 0.14 | 0.035 J |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

eurofins | Air Toxics

**Client Sample ID: VMP-54-30-020613**

**Lab ID#: 1302248B-12A**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1946**

| | | | |
|---|---|---|---|
| **File Name:** | **9022016** | **Date of Collection:** | **2/6/13 3:55:00 PM** |
| **Dil. Factor:** | **2.96** | **Date of Analysis:** | **2/20/13 04:05 PM** |

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.30 | 14 |
| Nitrogen | 0.30 | 81 |
| Carbon Monoxide | 0.15 | Not Detected |
| Methane | 0.00030 | 0.000042 J |
| Carbon Dioxide | 0.030 | 5.3 |
| Ethane | 0.0030 | Not Detected |
| Ethene | 0.0030 | Not Detected |
| Helium | 0.15 | 0.032 J |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

eurofins | Air Toxics

**Client Sample ID: VMP-54-30-020613-DUP**

**Lab ID#: 1302248B-13A**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1946**

| | | | |
|---|---|---|---|
| **File Name:** | **9022017** | **Date of Collection:** | **2/6/13 3:55:00 PM** |
| **Dil. Factor:** | **2.96** | **Date of Analysis:** | **2/20/13 05:18 PM** |

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.30 | 14 |
| Nitrogen | 0.30 | 81 |
| Carbon Monoxide | 0.15 | Not Detected |
| Methane | 0.00030 | 0.000051 J |
| Carbon Dioxide | 0.030 | 5.4 |
| Ethane | 0.0030 | Not Detected |
| Ethene | 0.0030 | Not Detected |
| Helium | 0.15 | 0.028 J |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

eurofins | Air Toxics

**Client Sample ID: VMP-7-13.5-021313**

**Lab ID#: 1302248B-14A**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1946**

| | | | |
|---|---|---|---|
| **File Name:** | **9022018** | **Date of Collection:** | **2/13/13 10:52:00 AM** |
| **Dil. Factor:** | **2.76** | **Date of Analysis:** | **2/20/13 06:00 PM** |

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.28 | 20 |
| Nitrogen | 0.28 | 80 |
| Carbon Monoxide | 0.14 | Not Detected |
| Methane | 0.00028 | 0.000024 J |
| Carbon Dioxide | 0.028 | 0.23 |
| Ethane | 0.0028 | Not Detected |
| Ethene | 0.0028 | Not Detected |
| Helium | 0.14 | 0.022 J |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

eurofins | Air Toxics

**Client Sample ID: Lab Blank**

**Lab ID#: 1302248B-15A**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1946**

| | | | |
|---|---|---|---|
| **File Name:** | **9022004a** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 2/20/13 09:46 AM** | |

| **Compound** | **Rpt. Limit (%)** | **Amount (%)** |
|---|---|---|
| Oxygen | 0.10 | 0.042 J |
| Nitrogen | 0.10 | 0.099 J |
| Carbon Monoxide | 0.050 | Not Detected |
| Methane | 0.00010 | Not Detected |
| Carbon Dioxide | 0.010 | Not Detected |
| Ethane | 0.0010 | Not Detected |
| Ethene | 0.0010 | Not Detected |

J = Estimated value.

**Container Type: NA - Not Applicable**

eurofins | Air Toxics

**Client Sample ID: Lab Blank**

**Lab ID#: 1302248B-15B**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1946**

| | | | |
|---|---|---|---|
| **File Name:** | **9022003b** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 2/20/13 09:24 AM** | |

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Helium | 0.050 | Not Detected |

**Container Type: NA - Not Applicable**

eurofins | Air Toxics

**Client Sample ID: LCS**

**Lab ID#: 1302248B-16A**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1946**

| | | | |
|---|---|---|---|
| **File Name:** | **9022002** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 2/20/13 08:58 AM** | |

| Compound | %Recovery |
|---|---|
| Oxygen | 99 |
| Nitrogen | 101 |
| Carbon Monoxide | 99 |
| Methane | 99 |
| Carbon Dioxide | 100 |
| Ethane | 100 |
| Ethene | 98 |
| Helium | 101 |

**Container Type: NA - Not Applicable**

eurofins | Air Toxics

**Client Sample ID: LCSD**

**Lab ID#: 1302248B-16AA**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1946**

| | | |
|---|---|---|
| **File Name:** | **9022025** | **Date of Collection: NA** |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 2/20/13 09:41 PM** |

| Compound | %Recovery |
|---|---|
| Oxygen | 98 |
| Nitrogen | 100 |
| Carbon Monoxide | 97 |
| Methane | 100 |
| Carbon Dioxide | 99 |
| Ethane | 101 |
| Ethene | 98 |
| Helium | 101 |

**Container Type: NA - Not Applicable**

# Shell Oil Products Chain Of Custody Record

URS

Air Toxics LTD.
**Project Name: Roxana Soil Vapor**
**Project # 21562850.04001**
Lab Vendor #

Please Check Appropriate Box:
☑ ENV. SERVICES ☐ MOTIVA RETAIL ☐ SHELL RETAIL
☐ MOTIVA SC&CM ☐ CONSULTANT ☐ LUBES
☐ SHELL PIPELINE ☐ OTHER

Print Bill To Contact Name: Robert Mooshegian
INCIDENT # (ENV SERVICES): 9 7 2 1 6 6 4 0
☐ CHECK IF NO INCIDENT # APPLIES
DATE: 02/13/13
PO #:
SAP #: 3 4 0 0 6 1
PAGE: 1 of 2

SAMPLING COMPANY: URS CORPORATION
LOG CODE:
SITE ADDRESS: Street and City: 900 SOUTH CENTRAL AVE – ROXANA
State: IL
GLOBAL ID NO:
ADDRESS: 1001 HIGHLANDS PLAZA DRIVE WEST - SUITE 300; ST. LOUIS, MO 63110
Laboratory Address: Air Toxics, LTD 180 Blue Ravine Road, Suite B, Folsom, CA 95630-4719
TELEPHONE: 314-429-0100
FAX: 314-429-0462
Bill To Contact E-MAIL: Robert.Mooshegian@urs.com
COP DELIVERABLE TO (Name, Company, Office Location): Elizabeth Kunkel, URS, St. Louis
PHONE NO.: 314-743-4179
E-MAIL: Elizabeth.Kunkel@URSCorp.com
CONSULTANT PROJECT NAME/NO.: Roxana Soil Vapor

TURNAROUND TIME (CALENDAR DAYS):
☑ STANDARD (14 DAY) ☐ 5 DAYS ☐ 3 DAYS ☐ 2 DAYS ☐ 24 HOURS ☐ RESULTS NEEDED ON WEEKEND

☐ LA - RWQCB REPORT FORMAT ☑ UST AGENCY:
DELIVERABLES: ☐ LEVEL 1 ☐ LEVEL 2 ☐ LEVEL 3 ☑ LEVEL 4 ☐ OTHER (SPECIFY)

☑ SHELL CONTRACT RATE APPLIES
☐ STATE REIMBURSEMENT RATE APPLIES
☐ EDD NOT NEEDED
☑ RECEIPT VERIFICATION REQUESTED

REQUESTED ANALYSIS

| LAB USE ONLY | Field Sample Identification | SAMPLING DATE | SAMPLING TIME | Canister Number | Canister Pressure/Vacuum Initial | Final | Receipt | Final (psi) | Modified TO-15 + Butane & Isopentane | ASTM D-1946 + Helium | ASTM D-1946 | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | VMP-3-10-020613 | 02/06/13 | 1527-1557 | 37338 | -29.5 | -10 | | | X | X | | | | | | |
| | VMP-3-22-020613 | 02/06/13 | 1437-1507 | 34633 | -30 | -9.5 | | | X | X | | | | | | |
| | VMP-4-5-020713 | 02/07/13 | 0909-0938 | 34576 | -27.5 | -6.5 | | | X | X | | | | | | |
| | VMP-4-12-020713 | 02/07/13 | 1000-1030 | 37372 | -28 | -8 | | | X | X | | | | | | |
| | VMP-4-12-020713-DUP | 02/07/13 | 1000-1030 | 36533 | -30 | -9 | | | X | X | | | | | | |
| | VMP-6-5-021213 | 02/12/13 | 1308-1338 | 9368 | -30 | -7 | | | X | X | | | | | | |
| | VMP-20-5-020713 | 02/07/13 | 1505-1535 | 33844 | -30 | -6 | | | X | X | | | | | | |
| | VMP-21-5-020613 | 02/06/13 | 1421-1450 | 31763 | -30 | -8.5 | | | X | X | | | | | | |
| | VMP-31-5-021113 | 02/11/13 | 1001-1031 | 36443 | -30 | -8 | | | X | X | | | | | | |
| | VMP-54-20-020513 | 02/06/13 | 1430-1501 | 11430 | -30 | -10 | | | X | X | | | | | | |

Turn Around Time:
☑ Normal
☐ Rush
Specify

*Lab Use Only*
Pressurized by:
Date:
Pressurization Gas: $N_2$ He

ADDITIONAL NOTES:
- 14 day hold time
- Report results between MDL and RL
- Level IV ECVP

| Relinquished by (Signature) | Received by: (Signature) | Date | Time |
|---|---|---|---|
| Cynthia Krejs | FEDEX | 02/13/13 | 1730 |
| Relinquished by (Signature) | Received by: (Signature) | Date | Time |
| | | 2/14/13 | 0945 |
| Relinquished by (Signature) | Received by: (Signature) | Date | Time |
| | | | |

05/2008 Revision

Custody Seal Intact?
Y N None Temp

1322248

# Shell Oil Products Chain Of Custody Record

URS

Air Toxics LTD.
**Project Name: Roxana Soil Vapor**
**Project # 21562850.04001**
**Lab Vendor #**

**Please Check Appropriate Box:**
☑ ENV. SERVICES ☐ MOTIVA RETAIL ☐ SHELL RETAIL
☐ MOTIVA SD&CM ☐ CONSULTANT ☐ LUBES
☐ SHELL PIPELINE ☐ OTHER

**Print Bill To Contact Name:** Robert Moosheg:an
**INCIDENT # (ENV SERVICES):** 9 7 2 1 6 6 4 0 ☐ CHECK IF NO INCIDENT # APPLIES
**PO. #:**
**SAP #:** 3 4 0 0 6 1
DATE: 02/13/13
PAGE: 2 of 2

SAMPLING COMPANY: URS CORPORATION
LOC CODE:
ADDRESS: 1001 HIGHLANDS PLAZA DRIVE WEST - SUITE 300; ST. LOUIS, MO 63110
Laboratory Address: Air Toxics, LTD 180 Blue Ravine Road, Suite B, Folsom, CA 95630-4719
TELEPHONE: 314-429-0100
FAX: 314-429-0462
Bill To Contact E-MAIL: Robert.Moosheg:an@urs.com

SITE ADDRESS: Street and City: 900 SOUTH CENTRAL AVE – ROXANA
State: IL
GLOBAL ID NO.:
EDF DELIVERABLE TO (Name, Company, Office Location): Elizabeth Kunkel, URS, St. Louis
PHONE NO.: 314-743-4179
E-MAIL: Elizabeth.Kunkel@URSCorp.com
CONSULTANT PROJECT NAME/#: Roxana Soil Vapor

TURNAROUND TIME (CALENDAR DAYS)
☑ STANDARD (14 DAY) ☐ 5 DAYS ☐ 3 DAYS ☐ 2 DAYS ☐ 24 HOURS ☐ RESULTS NEEDED ON WEEKEND

☐ LA - RWQCB REPORT FORMAT ☑ UST AGENCY:

DELIVERABLES: ☐ LEVEL 1 ☐ LEVEL 2 ☐ LEVEL 3 ☑ LEVEL 4 ☐ OTHER (SPECIFY)

☑ SHELL CONTRACT RATE APPLIES
☐ STATE REIMBURSEMENT RATE APPLIES
☐ EDD NOT NEEDED
☑ RECEIPT VERIFICATION REQUESTED

**REQUESTED ANALYSIS**

| LAB USE ONLY | Field Sample Identification | SAMPLING DATE | SAMPLING TIME | Canister Number | Canister Pressure/Vacuum: Initial | Final | Receipt | Final (psi) | Modified TO-15 + Butane & Isopentane | ASTM D-1946 + Helium | ASTM D-1946 |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 11 | VMP-54-20-020613-DUP | 02/06/13 | 1430-1501 | 2070 | -30 | -10 | | | X | X | |
| 12 | VMP-54-30-020613 | 02/06/13 | 1525-1555 | 34097 | -30 | -11.5 | | | X | X | |
| 13 | VMP-54-30-020013-DUP | 02/06/13 | 1525-1555 | 37771 | -30 | -12 | | | X | X | |
| 14 | VMP-7-13.5-021313 | 02/13/13 | 1022-1052 | 36393 | -30 | -9.5 | | | X | X | |
| | | | | | | | | | X | X | |
| | | | | | | | | | X | X | |
| | | | | | | | | | X | X | |
| | | | | | | | | | X | X | |
| | | | | | | | | | X | X | |
| | | | | | | | | | X | X | |

**Turn Around Time:** ☑ Normal ☐ Rush
Specify

**Lab Use Only**
Pressurized by:
Date:
Pressurization Gas: N2 He

**ADDITIONAL NOTES:**
- 14 day hold time
- Report results between MDL and RL
- Level IV ECVP

| Relinquished by: (Signature) | Received by: (Signature) | Date | Time |
|---|---|---|---|
| | FEDEX | 02/13/13 | 1730 |
| | | Date: | Time: |
| | 2/14/13 | 0945 | |
| | | Date: | Time: |

08/2008 Revision

Custody Seal Intact? Y N None Temp: 1.2
Fedex
1302248

# Roxana Soil Vapor Quarterly – 1st Quarter 2013 Data Review

**Laboratory SDG: 1302278A,B**

**Data Reviewer: Alan Fleisher**

**Peer Reviewer: Elizabeth Kunkel**

**Date Reviewed: 3/25/2013**

**Guidance: USEPA National Functional Guidelines for Superfund Organic Methods Data Review 2008**

| Sample Identification | Sample Identification |
|---|---|
| VMP-3-31.5-020713 | VMP-3-39-021213 |
| VMP-4-23.5-020713 | VMP-4-39-020713 |
| VMP-15-21.5-020713 | VMP-15-25.5-021213 |
| VMP-15-29-021213 | VMP-31-20-021113 |
| VMP-31-30-021113 | VMP-32-30-020513 |

## 1.0 Data Package Completeness

*Were all items delivered as specified in the QAPP and COC as appropriate?*

Yes

## 2.0 Laboratory Case Narrative \ Cooler Receipt Form

*Were problems noted in the laboratory case narrative or cooler receipt form?*

Yes, the laboratory case narrative indicated sample VMP-15-29-021213 was diluted and re-analyzed to bring the highest level target analytes with the calibration range of the instrument. Results for the highest level target analytes were reported from the re-analysis diluted runs and the remaining compounds were reported from the original analysis. The TO-15 LCS/LCSD recoveries for 2-hexanone and 4-methyl-2-pentanone were outside evaluation criteria. Although not indicated in the laboratory case narrative, analytes were detected in the method blank. These issues are addressed further in the appropriate sections below.

No issues or discrepancies were noted in the cooler receipt form.

## 3.0 Holding Times

*Were samples extracted/analyzed within applicable limits?*

Yes

## 4.0 Blank Contamination

*Were any analytes detected in the Blanks?*

Yes

| Blank ID | Parameter | Analyte | Concentration/ Amount |
|---|---|---|---|
| 1302278A-11A | TO-15 | 1,3-Butadiene | 0.74 ppbv / 1.6 µg/m$^3$ |

| Blank ID | Parameter | Analyte | Concentration/ Amount |
|---|---|---|---|
| 1302278A-11A | TO-15 | Methylene chloride | 1.7 ppbv / 6.0 µg/m$^3$ |
| 1302278A-11B | TO-15 | Methylene chloride | 2.0 ppbv / 7.1 µg/m$^3$ |
| 1302278A-11C | TO-15 | Carbon disulfide | 0.36 ppbv / 1.1 µg/m$^3$ |
| 1302278A-11C | TO-15 | Methylene chloride | 0.066 ppbv / 0.23 µg/m$^3$ |
| 1302278A-11C | TO-15 | 2,2,4-Trimethylpentane | 0.064 ppbv / 0.30 µg/m$^3$ |
| 1302278A-11C | TO-15 | Toluene | 0.039 ppbv / 0.14 µg/m$^3$ |
| 1302278A-11C | TO-15 | Propylbenzene | 0.053 ppbv / 0.26 µg/m$^3$ |
| 1302278A-11C | TO-15 | 4-Ethyltoluene | 0.043 ppbv / 0.21 µg/m$^3$ |
| 1302278A-11C | TO-15 | 1,3-Dichlorobenzene | 0.13 ppbv / 0.79 µg/m$^3$ |
| 1302278A-11C | TO-15 | 1,4-Dichlorobenzene | 0.15 ppbv / 0.92 µg/m$^3$ |
| 1302278A-11C | TO-15 | 1,2-Dichlorobenzene | 0.10 ppbv / 0.62 µg/m$^3$ |
| 1302278A-11C | TO-15 | 1,2,4-Trichlorobenzene | 0.48 ppbv / 3.6 µg/m$^3$ |
| 1302278A-11C | TO-15 | Hexachlorobutadiene | 0.20 ppbv / 2.2 µg/m$^3$ |
| 1302278B-11A | Natural gases | Nitrogen | 0.057% |

Analytical data were reported non-detect or at concentrations greater than five times (5X) the associated blank concentration and did not require qualification.

## 5.0 Laboratory Control Sample

*Were LCS recoveries within evaluation criteria?*

No

| LCS/LCSD ID | Parameter | Analyte | LCS/LCSD Recovery | LCS/ LCSD RPD | LCS/LCSD /RPD Criteria |
|---|---|---|---|---|---|
| 1302278A-13A/AA | TO-15 | 2-Hexanone | **69/67** | 3 | 70-130/25 |
| 1302278A-13B/BB | TO-15 | 4-Methyl-2-pentanone | **68/68** | 0 | 70-130/25 |
| 1302278A-13B/BB | TO-15 | 2-Hexanone | **66/61** | 8 | 70-130/25 |

Analytical data that required qualification based on LCS/LCSD data are included in the table below.

| Sample ID | Parameter | Analyte | Qualification |
|---|---|---|---|
| VMP-3-31.5-020713 | TO-15 | 2-Hexanone | **UJ** |
| VMP-3-39-021213 | TO-15 | 2-Hexanone | **UJ** |
| VMP-4-23.5-020713 | TO-15 | 4-Methyl-2-pentanone | **UJ** |
| VMP-4-23.5-020713 | TO-15 | 2-Hexanone | **UJ** |
| VMP-4-39-020713 | TO-15 | 4-Methyl-2-pentanone | **UJ** |
| VMP-4-39-020713 | TO-15 | 2-Hexanone | **UJ** |

## 6.0 Surrogate Recoveries

*Were surrogate recoveries within evaluation criteria?*

Yes

## 7.0 Matrix Spike and Matrix Spike Duplicate Recoveries

*Were MS/MSD samples analyzed as part of this SDG?*

MS/MSD samples are not applicable for vapor samples, due to the inability to spike the samples.

## 8.0 Laboratory Duplicate Results

*Were laboratory duplicate samples collected as part of this SDG?*

No

## 9.0 Field Duplicate Results

*Were field duplicate samples collected as part of this SDG?*

No

## 10.0 Sample Dilutions

*For samples that were diluted and nondetect, were undiluted results also reported?*

Not applicable; analytes were detected in samples that were diluted.

## 11.0 Additional Qualifications

*Were additional qualifications applied?*

No

eurofins | Air Toxics

3/4/2013
Ms. Elizabeth Kunkel
URS Corporation
1001 Highlands Plaza Dr. West
Suite 300
St. Louis MO 63110

Project Name: Roxana Soil Vapor
Project #: 21562850.04001
Workorder #: 1302278A

Dear Ms. Elizabeth Kunkel

The following report includes the data for the above referenced project for sample(s) received on 2/15/2013 at Air Toxics Ltd.

The data and associated QC analyzed by Modified TO-15 are compliant with the project requirements or laboratory criteria with the exception of the deviations noted in the attached case narrative.

Thank you for choosing Air Toxics Ltd. for your air analysis needs. Air Toxics Ltd. is committed to providing accurate data of the highest quality. Please feel free to contact the Project Manager: Kelly Buettner at 916-985-1000 if you have any questions regarding the data in this report.

Regards,

Kelly Buettner

Kelly Buettner
Project Manager

REVIEWED
ON
3/25/13

eurofins | Air Toxics

# WORK ORDER #: 1302278A

Work Order Summary

| | | | |
|---|---|---|---|
| **CLIENT:** | Ms. Elizabeth Kunkel<br>URS Corporation<br>1001 Highlands Plaza Dr. West<br>Suite 300<br>St. Louis, MO 63110 | **BILL TO:** | Accounts Payable Austin<br>URS Corporation<br>P.O. BOX 203970<br>Austin, TX 78720-1088 |
| **PHONE:** | 314-743-4179 | **P.O. #** | 21562735.00013 |
| **FAX:** | | **PROJECT #** | 21562850.04001 Roxana Soil Vapor |
| **DATE RECEIVED:** | 02/15/2013 | **CONTACT:** | Kelly Buettner |
| **DATE COMPLETED:** | 03/04/2013 | | |

| FRACTION # | NAME | TEST | RECEIPT VAC./PRES. | FINAL PRESSURE |
|---|---|---|---|---|
| 01A | VMP-3-31.5-020713 | Modified TO-15 | 6.5 "Hg | 15 psi |
| 02A | VMP-3-39-021213 | Modified TO-15 | 7.0 "Hg | 15 psi |
| 03A | VMP-4-23.5-020713 | Modified TO-15 | 7.0 "Hg | 15 psi |
| 04A | VMP-4-39-020713 | Modified TO-15 | 7.5 "Hg | 15 psi |
| 05A | VMP-15-21.5-020713 | Modified TO-15 | 8.0 "Hg | 15 psi |
| 06A | VMP-15-25.5-021213 | Modified TO-15 | 7.5 "Hg | 15 psi |
| 07A | VMP-15-29-021213 | Modified TO-15 | 7.5 "Hg | 15 psi |
| 07B | VMP-15-29-021213 | Modified TO-15 | 7.5 "Hg | 15 psi |
| 08A | VMP-31-20-021113 | Modified TO-15 | 8.0 "Hg | 15 psi |
| 09A | VMP-31-30-021113 | Modified TO-15 | 8.5 "Hg | 15 psi |
| 10A | VMP-32-30-020513 | Modified TO-15 | 8.5 "Hg | 15 psi |
| 11A | Lab Blank | Modified TO-15 | NA | NA |
| 11B | Lab Blank | Modified TO-15 | NA | NA |
| 11C | Lab Blank | Modified TO-15 | NA | NA |
| 12A | CCV | Modified TO-15 | NA | NA |
| 12B | CCV | Modified TO-15 | NA | NA |
| 12C | CCV | Modified TO-15 | NA | NA |
| 13A | LCS | Modified TO-15 | NA | NA |
| 13AA | LCSD | Modified TO-15 | NA | NA |
| 13B | LCS | Modified TO-15 | NA | NA |
| 13BB | LCSD | Modified TO-15 | NA | NA |
| 13C | LCS | Modified TO-15 | NA | NA |
| 13CC | LCSD | Modified TO-15 | NA | NA |

CERTIFIED BY: Heidi Hayes

Technical Director

DATE: 03/04/13

Certification numbers: AZ Licensure AZ0775, CA NELAP - 12282CA, NY NELAP - 11291,
TX NELAP - T104704434-12-4, UT NELAP CA009332012-3, WA NELAP - C935
Name of Accrediting Agency: NELAP/ORELAP (Oregon Environmental Laboratory Accreditation Program)
Accreditation number: CA300005, Effective date: 10/18/2012, Expiration date: 10/17/2013.
Eurofins Air Toxics Ltd. certifies that the test results contained in this report meet all requirements of the NELAC standards

This report shall not be reproduced, except in full, without the written approval of Eurofins Air Toxics, Inc.

180 BLUE RAVINE ROAD, SUITE B FOLSOM, CA - 9563
(916) 985-1000 . (800) 985-5955 . FAX (916) 985-1020

**LABORATORY NARRATIVE**
**EPA Method TO-15**
**URS Corporation**
**Workorder# 1302278A**

Ten 1 Liter Summa Canister samples were received on February 15, 2013. The laboratory performed analysis via EPA Method TO-15 using GC/MS in the full scan mode.

This workorder was independently validated prior to submittal using 'USEPA National Functional Guidelines' as generally applied to the analysis of volatile organic compounds in air. A rules-based, logic driven, independent validation engine was employed to assess completeness, evaluate pass/fail of relevant project quality control requirements and verification of all quantified amounts.

**Receiving Notes**

The Chain of Custody (COC) information for sample VMP-31-20-021113 did not match the information on the canister with regard to canister identification. The client was notified of the discrepancy and the information on the canister was used to process and report the sample.

**Analytical Notes**

As per client project requirements, the laboratory has reported estimated values for target compound hits that are below the Reporting Limit but greater than the Method Detection Limit. Concentrations that are below the level at which the canister was certified may be false positives.

All Quality Control Limit exceedances and affected sample results are noted by flags. Each flag is defined at the bottom of this Case Narrative and on each Sample Result Summary page.

Dilution was performed on all samples due to the presence of high level target species.

Due to the linear calibration range of instrument MSD-14, the reporting limit for 4-Methyl-2-pentanone was raised from 5.0ppbv to 20ppbv.

Due to high-level target compounds, sample VMP-15-29-021213 was analyzed twice. In the "A" fraction, the sample was diluted to bring the highest-level compounds within the calibration range. The "B" fraction is also reported by client request and may be reported with "E" flags indicating the compound exceeds the calibration range. Both runs and associated QC are reported.

**Definition of Data Qualifying Flags**

Eight qualifiers may have been used on the data analysis sheets and indicates as follows:

B - Compound present in laboratory blank greater than reporting limit (background subtraction not performed).
J - Estimated value.
E - Exceeds instrument calibration range.
S - Saturated peak.
Q - Exceeds quality control limits.
U - Compound analyzed for but not detected above the reporting limit.

UJ- Non-detected compound associated with low bias in the CCV
N - The identification is based on presumptive evidence.

File extensions may have been used on the data analysis sheets and indicates as follows:
a-File was requantified
b-File was quantified by a second column and detector
r1-File was requantified for the purpose of reissue

eurofins | Air Toxics

# Summary of Detected Compounds
# EPA METHOD TO-15 GC/MS

**Client Sample ID: VMP-3-31.5-020713**

**Lab ID#: 1302278A-01A**

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Carbon Disulfide | 2600 | 420 J | 8000 | 1300 J |
| Hexane | 2600 | 79000 | 9100 | 280000 |
| 2,2,4-Trimethylpentane | 2600 | 370000 | 12000 | 1700000 |
| Butane | 10000 | 1300000 | 24000 | 3000000 |
| Isopentane | 10000 | 1400000 | 30000 | 4200000 |

**Client Sample ID: VMP-3-39-021213**

**Lab ID#: 1302278A-02A**

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Hexane | 13000 | 600000 | 46000 | 2100000 |
| 2,2,4-Trimethylpentane | 13000 | 1200000 | 62000 | 5700000 |
| Benzene | 13000 | 6200 J | 42000 | 20000 J |
| Ethyl Benzene | 13000 | 3000 J | 57000 | 13000 J |
| m,p-Xylene | 13000 | 3200 J | 57000 | 14000 J |
| Butane | 53000 | 7700000 | 120000 | 18000000 |
| Isopentane | 53000 | 6000000 | 160000 | 18000000 |

**Client Sample ID: VMP-4-23.5-020713**

**Lab ID#: 1302278A-03A**

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Hexane | 330 | 23000 | 1200 | 82000 |
| 2,2,4-Trimethylpentane | 330 | 32000 | 1500 | 150000 |
| Benzene | 330 | 87 J | 1000 | 280 J |
| Toluene | 330 | 71 J | 1200 | 270 J |
| Butane | 1300 | 63000 | 3100 | 150000 |
| Isopentane | 1300 | 220000 | 3900 | 630000 |

**Client Sample ID: VMP-4-39-020713**

**Lab ID#: 1302278A-04A**

eurofins | Air Toxics

# Summary of Detected Compounds
# EPA METHOD TO-15 GC/MS

**Client Sample ID: VMP-4-39-020713**

**Lab ID#: 1302278A-04A**

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Carbon Disulfide | 2700 | 1000 J | 8400 | 3200 J |
| Hexane | 2700 | 1300000 | 9500 | 4500000 |
| 2,2,4-Trimethylpentane | 2700 | 390000 | 12000 | 1800000 |
| Benzene | 2700 | 7900 | 8600 | 25000 |
| Heptane | 2700 | 570000 | 11000 | 2300000 |
| Toluene | 2700 | 160000 | 10000 | 610000 |
| Ethyl Benzene | 2700 | 100000 | 12000 | 450000 |
| m,p-Xylene | 2700 | 180000 | 12000 | 790000 |
| o-Xylene | 2700 | 70000 | 12000 | 310000 |
| Cumene | 2700 | 1100 J | 13000 | 5500 J |
| Propylbenzene | 2700 | 610 J | 13000 | 3000 J |
| 4-Ethyltoluene | 2700 | 12000 | 13000 | 58000 |
| 1,3,5-Trimethylbenzene | 2700 | 3300 | 13000 | 16000 |
| 1,2,4-Trimethylbenzene | 2700 | 2400 J | 13000 | 12000 J |
| Butane | 11000 | 1100000 | 26000 | 2500000 |
| Isopentane | 11000 | 1800000 | 32000 | 5300000 |

**Client Sample ID: VMP-15-21.5-020713**

**Lab ID#: 1302278A-05A**

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Ethanol | 22 | 21 J | 41 | 40 J |
| Acetone | 55 | 14 J | 130 | 34 J |
| 2-Propanol | 22 | 10 J | 54 | 26 J |
| Carbon Disulfide | 22 | 9.3 J | 68 | 29 J |
| Hexane | 5.5 | 120 | 19 | 410 |
| Cyclohexane | 5.5 | 27 | 19 | 93 |
| 2,2,4-Trimethylpentane | 5.5 | 1400 | 26 | 6400 |
| Benzene | 5.5 | 2.4 J | 18 | 7.7 J |
| Heptane | 5.5 | 31 | 22 | 120 |
| Toluene | 5.5 | 1.5 J | 21 | 5.7 J |
| Butane | 22 | 170 | 52 | 400 |
| Isopentane | 22 | 300 | 65 | 900 |

eurofins | Air Toxics

# Summary of Detected Compounds
# EPA METHOD TO-15 GC/MS

**Client Sample ID: VMP-15-25.5-021213**

**Lab ID#: 1302278A-06A**

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Methylene Chloride | 45 | 66 | 160 | 230 |
| 2,2,4-Trimethylpentane | 45 | 31000 | 210 | 140000 |
| m,p-Xylene | 45 | 17 J | 190 | 74 J |
| o-Xylene | 45 | 8.7 J | 190 | 38 J |
| Cumene | 45 | 14 J | 220 | 70 J |
| 1,2,4-Trimethylbenzene | 45 | 11 J | 220 | 54 J |
| Butane | 180 | 1000 | 430 | 2400 |
| Isopentane | 180 | 12000 | 530 | 37000 |

**Client Sample ID: VMP-15-29-021213**

* USE THIS RESULT ONLY. ALL OTHER DATA REPORTED FROM 5.38X DILUTION ANALYSIS

**Lab ID#: 1302278A-07A**

DF = 8.97X

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Acetone | 180 | 90 J | 430 | 210 J |
| Methylene Chloride | 45 | 28 J | 160 | 96 J |
| * 2,2,4-Trimethylpentane | 45 | 23000 | 210 | 110000 |
| Butane | 180 | 640 | 430 | 1500 |
| Isopentane | 180 | 12000 | 530 | 37000 |

**Client Sample ID: VMP-15-29-021213**

* DO NOT USE THIS DATA. USE ALL OTHER DATA.

**Lab ID#: 1302278A-07B**

DF = 5.38X

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Acetone | 110 | 110 | 260 | 260 |
| * ~~2,2,4-Trimethylpentane~~ | ~~27~~ | ~~30000 E~~ | ~~120~~ | ~~140000 E~~ |
| Butane | 110 | 830 | 260 | 2000 |
| Isopentane | 110 | 16000 | 320 | 48000 |

**Client Sample ID: VMP-31-20-021113**

**Lab ID#: 1302278A-08A**

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|

eurofins | Air Toxics

# Summary of Detected Compounds
# EPA METHOD TO-15 GC/MS

**Client Sample ID: VMP-31-20-021113**

**Lab ID#: 1302278A-08A**

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Ethanol | 79 | 220 | 150 | 420 |
| Acetone | 79 | 19 J | 190 | 45 J |
| 2-Propanol | 79 | 20 J | 190 | 49 J |
| 2,2,4-Trimethylpentane | 20 | 18000 | 92 | 87000 |
| 1,4-Dioxane | 79 | 14 J | 280 | 50 J |
| Butane | 79 | 650 | 190 | 1500 |
| Isopentane | 79 | 4300 | 230 | 13000 |

**Client Sample ID: VMP-31-30-021113**

**Lab ID#: 1302278A-09A**

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| 2-Butanone (Methyl Ethyl Ketone) | 5600 | 880 J | 17000 | 2600 J |
| 2,2,4-Trimethylpentane | 1400 | 84000 | 6600 | 400000 |
| Toluene | 1400 | 410 J | 5300 | 1600 J |
| m,p-Xylene | 1400 | 490 J | 6100 | 2100 J |
| o-Xylene | 1400 | 1700 | 6100 | 7200 |
| Butane | 5600 | 440000 | 13000 | 1000000 |
| Isopentane | 5600 | 470000 | 17000 | 1400000 |

**Client Sample ID: VMP-32-30-020513**

**Lab ID#: 1302278A-10A**

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Methylene Chloride | 56 | 29 J | 200 | 100 J |
| 2,2,4-Trimethylpentane | 56 | 30000 | 260 | 140000 |
| Isopentane | 230 | 63 J | 670 | 180 J |

eurofins | Air Toxics

**Client Sample ID: VMP-3-31.5-020713**

**Lab ID#: 1302278A-01A**

**EPA METHOD TO-15 GC/MS**

| | | | |
|---|---|---|---|
| **File Name:** | **14021943** | **Date of Collection:** | **2/7/13 10:35:00 AM** |
| **Dil. Factor:** | **516** | **Date of Analysis:** | **2/20/13 03:51 PM** |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 2600 | Not Detected | 13000 | Not Detected |
| Freon 114 | 2600 | Not Detected | 18000 | Not Detected |
| Chloromethane | 10000 | Not Detected | 21000 | Not Detected |
| Vinyl Chloride | 2600 | Not Detected | 6600 | Not Detected |
| 1,3-Butadiene | 2600 | Not Detected | 5700 | Not Detected |
| Bromomethane | 2600 | Not Detected | 10000 | Not Detected |
| Chloroethane | 10000 | Not Detected | 27000 | Not Detected |
| Freon 11 | 2600 | Not Detected | 14000 | Not Detected |
| Ethanol | 10000 | Not Detected | 19000 | Not Detected |
| Freon 113 | 2600 | Not Detected | 20000 | Not Detected |
| 1,1-Dichloroethene | 2600 | Not Detected | 10000 | Not Detected |
| Acetone | 10000 | Not Detected | 24000 | Not Detected |
| 2-Propanol | 10000 | Not Detected | 25000 | Not Detected |
| Carbon Disulfide | 2600 | 420 J | 8000 | 1300 J |
| 3-Chloropropene | 10000 | Not Detected | 32000 | Not Detected |
| Methylene Chloride | 2600 | Not Detected | 9000 | Not Detected |
| Methyl tert-butyl ether | 2600 | Not Detected | 9300 | Not Detected |
| trans-1,2-Dichloroethene | 2600 | Not Detected | 10000 | Not Detected |
| Hexane | 2600 | 79000 | 9100 | 280000 |
| 1,1-Dichloroethane | 2600 | Not Detected | 10000 | Not Detected |
| 2-Butanone (Methyl Ethyl Ketone) | 10000 | Not Detected | 30000 | Not Detected |
| cis-1,2-Dichloroethene | 2600 | Not Detected | 10000 | Not Detected |
| Tetrahydrofuran | 2600 | Not Detected | 7600 | Not Detected |
| Chloroform | 2600 | Not Detected | 12000 | Not Detected |
| 1,1,1-Trichloroethane | 2600 | Not Detected | 14000 | Not Detected |
| Cyclohexane | 2600 | Not Detected | 8900 | Not Detected |
| Carbon Tetrachloride | 2600 | Not Detected | 16000 | Not Detected |
| 2,2,4-Trimethylpentane | 2600 | 370000 | 12000 | 1700000 |
| Benzene | 2600 | Not Detected | 8200 | Not Detected |
| 1,2-Dichloroethane | 2600 | Not Detected | 10000 | Not Detected |
| Heptane | 2600 | Not Detected | 10000 | Not Detected |
| Trichloroethene | 2600 | Not Detected | 14000 | Not Detected |
| 1,2-Dichloropropane | 2600 | Not Detected | 12000 | Not Detected |
| 1,4-Dioxane | 10000 | Not Detected | 37000 | Not Detected |
| Bromodichloromethane | 2600 | Not Detected | 17000 | Not Detected |
| cis-1,3-Dichloropropene | 2600 | Not Detected | 12000 | Not Detected |
| 4-Methyl-2-pentanone | 10000 | Not Detected | 42000 | Not Detected |
| Toluene | 2600 | Not Detected | 9700 | Not Detected |
| trans-1,3-Dichloropropene | 2600 | Not Detected | 12000 | Not Detected |
| 1,1,2-Trichloroethane | 2600 | Not Detected | 14000 | Not Detected |
| Tetrachloroethene | 2600 | Not Detected | 18000 | Not Detected |
| 2-Hexanone | 10000 | Not Detected UJ | 42000 | Not Detected UJ |

eurofins | Air Toxics

**Client Sample ID: VMP-3-31.5-020713**

**Lab ID#: 1302278A-01A**

**EPA METHOD TO-15 GC/MS**

| | | | |
|---|---|---|---|
| **File Name:** | **14021943** | **Date of Collection: 2/7/13 10:35:00 AM** | |
| **Dil. Factor:** | **516** | **Date of Analysis: 2/20/13 03:51 PM** | |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Dibromochloromethane | 2600 | Not Detected | 22000 | Not Detected |
| 1,2-Dibromoethane (EDB) | 2600 | Not Detected | 20000 | Not Detected |
| Chlorobenzene | 2600 | Not Detected | 12000 | Not Detected |
| Ethyl Benzene | 2600 | Not Detected | 11000 | Not Detected |
| m,p-Xylene | 2600 | Not Detected | 11000 | Not Detected |
| o-Xylene | 2600 | Not Detected | 11000 | Not Detected |
| Styrene | 2600 | Not Detected | 11000 | Not Detected |
| Bromoform | 2600 | Not Detected | 27000 | Not Detected |
| Cumene | 2600 | Not Detected | 13000 | Not Detected |
| 1,1,2,2-Tetrachloroethane | 2600 | Not Detected | 18000 | Not Detected |
| Propylbenzene | 2600 | Not Detected | 13000 | Not Detected |
| 4-Ethyltoluene | 2600 | Not Detected | 13000 | Not Detected |
| 1,3,5-Trimethylbenzene | 2600 | Not Detected | 13000 | Not Detected |
| 1,2,4-Trimethylbenzene | 2600 | Not Detected | 13000 | Not Detected |
| 1,3-Dichlorobenzene | 2600 | Not Detected | 16000 | Not Detected |
| 1,4-Dichlorobenzene | 2600 | Not Detected | 16000 | Not Detected |
| alpha-Chlorotoluene | 2600 | Not Detected | 13000 | Not Detected |
| 1,2-Dichlorobenzene | 2600 | Not Detected | 16000 | Not Detected |
| 1,2,4-Trichlorobenzene | 10000 | Not Detected | 76000 | Not Detected |
| Hexachlorobutadiene | 10000 | Not Detected | 110000 | Not Detected |
| Butane | 10000 | 1300000 | 24000 | 3000000 |
| Isopentane | 10000 | 1400000 | 30000 | 4200000 |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| 1,2-Dichloroethane-d4 | 104 | 70-130 |
| Toluene-d8 | 100 | 70-130 |
| 4-Bromofluorobenzene | 97 | 70-130 |

eurofins | Air Toxics

**Client Sample ID: VMP-3-39-021213**
**Lab ID#: 1302278A-02A**
**EPA METHOD TO-15 GC/MS**

| | | | |
|---|---|---|---|
| **File Name:** | **14021945** | **Date of Collection:** | **2/12/13 10:59:00 AM** |
| **Dil. Factor:** | **2640** | **Date of Analysis:** | **2/20/13 04:44 PM** |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 13000 | Not Detected | 65000 | Not Detected |
| Freon 114 | 13000 | Not Detected | 92000 | Not Detected |
| Chloromethane | 53000 | Not Detected | 110000 | Not Detected |
| Vinyl Chloride | 13000 | Not Detected | 34000 | Not Detected |
| 1,3-Butadiene | 13000 | Not Detected | 29000 | Not Detected |
| Bromomethane | 13000 | Not Detected | 51000 | Not Detected |
| Chloroethane | 53000 | Not Detected | 140000 | Not Detected |
| Freon 11 | 13000 | Not Detected | 74000 | Not Detected |
| Ethanol | 53000 | Not Detected | 99000 | Not Detected |
| Freon 113 | 13000 | Not Detected | 100000 | Not Detected |
| 1,1-Dichloroethene | 13000 | Not Detected | 52000 | Not Detected |
| Acetone | 53000 | Not Detected | 120000 | Not Detected |
| 2-Propanol | 53000 | Not Detected | 130000 | Not Detected |
| Carbon Disulfide | 13000 | Not Detected | 41000 | Not Detected |
| 3-Chloropropene | 53000 | Not Detected | 160000 | Not Detected |
| Methylene Chloride | 13000 | Not Detected | 46000 | Not Detected |
| Methyl tert-butyl ether | 13000 | Not Detected | 48000 | Not Detected |
| trans-1,2-Dichloroethene | 13000 | Not Detected | 52000 | Not Detected |
| Hexane | 13000 | 600000 | 46000 | 2100000 |
| 1,1-Dichloroethane | 13000 | Not Detected | 53000 | Not Detected |
| 2-Butanone (Methyl Ethyl Ketone) | 53000 | Not Detected | 160000 | Not Detected |
| cis-1,2-Dichloroethene | 13000 | Not Detected | 52000 | Not Detected |
| Tetrahydrofuran | 13000 | Not Detected | 39000 | Not Detected |
| Chloroform | 13000 | Not Detected | 64000 | Not Detected |
| 1,1,1-Trichloroethane | 13000 | Not Detected | 72000 | Not Detected |
| Cyclohexane | 13000 | Not Detected | 45000 | Not Detected |
| Carbon Tetrachloride | 13000 | Not Detected | 83000 | Not Detected |
| 2,2,4-Trimethylpentane | 13000 | 1200000 | 62000 | 5700000 |
| Benzene | 13000 | 6200 J | 42000 | 20000 J |
| 1,2-Dichloroethane | 13000 | Not Detected | 53000 | Not Detected |
| Heptane | 13000 | Not Detected | 54000 | Not Detected |
| Trichloroethene | 13000 | Not Detected | 71000 | Not Detected |
| 1,2-Dichloropropane | 13000 | Not Detected | 61000 | Not Detected |
| 1,4-Dioxane | 53000 | Not Detected | 190000 | Not Detected |
| Bromodichloromethane | 13000 | Not Detected | 88000 | Not Detected |
| cis-1,3-Dichloropropene | 13000 | Not Detected | 60000 | Not Detected |
| 4-Methyl-2-pentanone | 53000 | Not Detected | 220000 | Not Detected |
| Toluene | 13000 | Not Detected | 50000 | Not Detected |
| trans-1,3-Dichloropropene | 13000 | Not Detected | 60000 | Not Detected |
| 1,1,2-Trichloroethane | 13000 | Not Detected | 72000 | Not Detected |
| Tetrachloroethene | 13000 | Not Detected | 90000 | Not Detected |
| 2-Hexanone | 53000 | Not Detected UJ | 220000 | Not Detected UJ |

eurofins | Air Toxics

**Client Sample ID: VMP-3-39-021213**

**Lab ID#: 1302278A-02A**

**EPA METHOD TO-15 GC/MS**

| | | | |
|---|---|---|---|
| **File Name:** | **14021945** | **Date of Collection: 2/12/13 10:59:00 AM** | |
| **Dil. Factor:** | **2640** | **Date of Analysis: 2/20/13 04:44 PM** | |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Dibromochloromethane | 13000 | Not Detected | 110000 | Not Detected |
| 1,2-Dibromoethane (EDB) | 13000 | Not Detected | 100000 | Not Detected |
| Chlorobenzene | 13000 | Not Detected | 61000 | Not Detected |
| Ethyl Benzene | 13000 | 3000 J | 57000 | 13000 J |
| m,p-Xylene | 13000 | 3200 J | 57000 | 14000 J |
| o-Xylene | 13000 | Not Detected | 57000 | Not Detected |
| Styrene | 13000 | Not Detected | 56000 | Not Detected |
| Bromoform | 13000 | Not Detected | 140000 | Not Detected |
| Cumene | 13000 | Not Detected | 65000 | Not Detected |
| 1,1,2,2-Tetrachloroethane | 13000 | Not Detected | 91000 | Not Detected |
| Propylbenzene | 13000 | Not Detected | 65000 | Not Detected |
| 4-Ethyltoluene | 13000 | Not Detected | 65000 | Not Detected |
| 1,3,5-Trimethylbenzene | 13000 | Not Detected | 65000 | Not Detected |
| 1,2,4-Trimethylbenzene | 13000 | Not Detected | 65000 | Not Detected |
| 1,3-Dichlorobenzene | 13000 | Not Detected | 79000 | Not Detected |
| 1,4-Dichlorobenzene | 13000 | Not Detected | 79000 | Not Detected |
| alpha-Chlorotoluene | 13000 | Not Detected | 68000 | Not Detected |
| 1,2-Dichlorobenzene | 13000 | Not Detected | 79000 | Not Detected |
| 1,2,4-Trichlorobenzene | 53000 | Not Detected | 390000 | Not Detected |
| Hexachlorobutadiene | 53000 | Not Detected | 560000 | Not Detected |
| Butane | 53000 | 7700000 | 120000 | 18000000 |
| Isopentane | 53000 | 6000000 | 160000 | 18000000 |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| 1,2-Dichloroethane-d4 | 103 | 70-130 |
| Toluene-d8 | 98 | 70-130 |
| 4-Bromofluorobenzene | 100 | 70-130 |

eurofins | Air Toxics

**Client Sample ID: VMP-4-23.5-020713**

**Lab ID#: 1302278A-03A**

**EPA METHOD TO-15 GC/MS**

| | | | |
|---|---|---|---|
| **File Name:** | **14021936** | **Date of Collection:** | **2/7/13 11:22:00 AM** |
| **Dil. Factor:** | **66.0** | **Date of Analysis:** | **2/20/13 11:17 AM** |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 330 | Not Detected | 1600 | Not Detected |
| Freon 114 | 330 | Not Detected | 2300 | Not Detected |
| Chloromethane | 1300 | Not Detected | 2700 | Not Detected |
| Vinyl Chloride | 330 | Not Detected | 840 | Not Detected |
| 1,3-Butadiene | 330 | Not Detected | 730 | Not Detected |
| Bromomethane | 330 | Not Detected | 1300 | Not Detected |
| Chloroethane | 1300 | Not Detected | 3500 | Not Detected |
| Freon 11 | 330 | Not Detected | 1800 | Not Detected |
| Ethanol | 1300 | Not Detected | 2500 | Not Detected |
| Freon 113 | 330 | Not Detected | 2500 | Not Detected |
| 1,1-Dichloroethene | 330 | Not Detected | 1300 | Not Detected |
| Acetone | 1300 | Not Detected | 3100 | Not Detected |
| 2-Propanol | 1300 | Not Detected | 3200 | Not Detected |
| Carbon Disulfide | 330 | Not Detected | 1000 | Not Detected |
| 3-Chloropropene | 1300 | Not Detected | 4100 | Not Detected |
| Methylene Chloride | 330 | Not Detected | 1100 | Not Detected |
| Methyl tert-butyl ether | 330 | Not Detected | 1200 | Not Detected |
| trans-1,2-Dichloroethene | 330 | Not Detected | 1300 | Not Detected |
| Hexane | 330 | 23000 | 1200 | 82000 |
| 1,1-Dichloroethane | 330 | Not Detected | 1300 | Not Detected |
| 2-Butanone (Methyl Ethyl Ketone) | 1300 | Not Detected | 3900 | Not Detected |
| cis-1,2-Dichloroethene | 330 | Not Detected | 1300 | Not Detected |
| Tetrahydrofuran | 330 | Not Detected | 970 | Not Detected |
| Chloroform | 330 | Not Detected | 1600 | Not Detected |
| 1,1,1-Trichloroethane | 330 | Not Detected | 1800 | Not Detected |
| Cyclohexane | 330 | Not Detected | 1100 | Not Detected |
| Carbon Tetrachloride | 330 | Not Detected | 2100 | Not Detected |
| 2,2,4-Trimethylpentane | 330 | 32000 | 1500 | 150000 |
| Benzene | 330 | 87 J | 1000 | 280 J |
| 1,2-Dichloroethane | 330 | Not Detected | 1300 | Not Detected |
| Heptane | 330 | Not Detected | 1400 | Not Detected |
| Trichloroethene | 330 | Not Detected | 1800 | Not Detected |
| 1,2-Dichloropropane | 330 | Not Detected | 1500 | Not Detected |
| 1,4-Dioxane | 1300 | Not Detected | 4800 | Not Detected |
| Bromodichloromethane | 330 | Not Detected | 2200 | Not Detected |
| cis-1,3-Dichloropropene | 330 | Not Detected | 1500 | Not Detected |
| 4-Methyl-2-pentanone | 1300 | Not Detected UJ | 5400 | Not Detected UJ |
| Toluene | 330 | 71 J | 1200 | 270 J |
| trans-1,3-Dichloropropene | 330 | Not Detected | 1500 | Not Detected |
| 1,1,2-Trichloroethane | 330 | Not Detected | 1800 | Not Detected |
| Tetrachloroethene | 330 | Not Detected | 2200 | Not Detected |
| 2-Hexanone | 1300 | Not Detected UJ | 5400 | Not Detected UJ |

eurofins | Air Toxics

**Client Sample ID: VMP-4-23.5-020713**

**Lab ID#: 1302278A-03A**

**EPA METHOD TO-15 GC/MS**

| | | | |
|---|---|---|---|
| **File Name:** | **14021936** | **Date of Collection:** | **2/7/13 11:22:00 AM** |
| **Dil. Factor:** | **66.0** | **Date of Analysis:** | **2/20/13 11:17 AM** |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Dibromochloromethane | 330 | Not Detected | 2800 | Not Detected |
| 1,2-Dibromoethane (EDB) | 330 | Not Detected | 2500 | Not Detected |
| Chlorobenzene | 330 | Not Detected | 1500 | Not Detected |
| Ethyl Benzene | 330 | Not Detected | 1400 | Not Detected |
| m,p-Xylene | 330 | Not Detected | 1400 | Not Detected |
| o-Xylene | 330 | Not Detected | 1400 | Not Detected |
| Styrene | 330 | Not Detected | 1400 | Not Detected |
| Bromoform | 330 | Not Detected | 3400 | Not Detected |
| Cumene | 330 | Not Detected | 1600 | Not Detected |
| 1,1,2,2-Tetrachloroethane | 330 | Not Detected | 2300 | Not Detected |
| Propylbenzene | 330 | Not Detected | 1600 | Not Detected |
| 4-Ethyltoluene | 330 | Not Detected | 1600 | Not Detected |
| 1,3,5-Trimethylbenzene | 330 | Not Detected | 1600 | Not Detected |
| 1,2,4-Trimethylbenzene | 330 | Not Detected | 1600 | Not Detected |
| 1,3-Dichlorobenzene | 330 | Not Detected | 2000 | Not Detected |
| 1,4-Dichlorobenzene | 330 | Not Detected | 2000 | Not Detected |
| alpha-Chlorotoluene | 330 | Not Detected | 1700 | Not Detected |
| 1,2-Dichlorobenzene | 330 | Not Detected | 2000 | Not Detected |
| 1,2,4-Trichlorobenzene | 1300 | Not Detected | 9800 | Not Detected |
| Hexachlorobutadiene | 1300 | Not Detected | 14000 | Not Detected |
| Butane | 1300 | 63000 | 3100 | 150000 |
| Isopentane | 1300 | 220000 | 3900 | 630000 |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| 1,2-Dichloroethane-d4 | 114 | 70-130 |
| Toluene-d8 | 99 | 70-130 |
| 4-Bromofluorobenzene | 96 | 70-130 |

eurofins | Air Toxics

**Client Sample ID: VMP-4-39-020713**

**Lab ID#: 1302278A-04A**

**EPA METHOD TO-15 GC/MS**

| | | | |
|---|---|---|---|
| **File Name:** | **14021944** | **Date of Collection: 2/7/13 1:43:00 PM** | |
| **Dil. Factor:** | **538** | **Date of Analysis: 2/20/13 04:15 PM** | |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 2700 | Not Detected | 13000 | Not Detected |
| Freon 114 | 2700 | Not Detected | 19000 | Not Detected |
| Chloromethane | 11000 | Not Detected | 22000 | Not Detected |
| Vinyl Chloride | 2700 | Not Detected | 6900 | Not Detected |
| 1,3-Butadiene | 2700 | Not Detected | 6000 | Not Detected |
| Bromomethane | 2700 | Not Detected | 10000 | Not Detected |
| Chloroethane | 11000 | Not Detected | 28000 | Not Detected |
| Freon 11 | 2700 | Not Detected | 15000 | Not Detected |
| Ethanol | 11000 | Not Detected | 20000 | Not Detected |
| Freon 113 | 2700 | Not Detected | 21000 | Not Detected |
| 1,1-Dichloroethene | 2700 | Not Detected | 11000 | Not Detected |
| Acetone | 11000 | Not Detected | 26000 | Not Detected |
| 2-Propanol | 11000 | Not Detected | 26000 | Not Detected |
| Carbon Disulfide | 2700 | 1000 J | 8400 | 3200 J |
| 3-Chloropropene | 11000 | Not Detected | 34000 | Not Detected |
| Methylene Chloride | 2700 | Not Detected | 9300 | Not Detected |
| Methyl tert-butyl ether | 2700 | Not Detected | 9700 | Not Detected |
| trans-1,2-Dichloroethene | 2700 | Not Detected | 11000 | Not Detected |
| Hexane | 2700 | 1300000 | 9500 | 4500000 |
| 1,1-Dichloroethane | 2700 | Not Detected | 11000 | Not Detected |
| 2-Butanone (Methyl Ethyl Ketone) | 11000 | Not Detected | 32000 | Not Detected |
| cis-1,2-Dichloroethene | 2700 | Not Detected | 11000 | Not Detected |
| Tetrahydrofuran | 2700 | Not Detected | 7900 | Not Detected |
| Chloroform | 2700 | Not Detected | 13000 | Not Detected |
| 1,1,1-Trichloroethane | 2700 | Not Detected | 15000 | Not Detected |
| Cyclohexane | 2700 | Not Detected | 9200 | Not Detected |
| Carbon Tetrachloride | 2700 | Not Detected | 17000 | Not Detected |
| 2,2,4-Trimethylpentane | 2700 | 390000 | 12000 | 1800000 |
| Benzene | 2700 | 7900 | 8600 | 25000 |
| 1,2-Dichloroethane | 2700 | Not Detected | 11000 | Not Detected |
| Heptane | 2700 | 570000 | 11000 | 2300000 |
| Trichloroethene | 2700 | Not Detected | 14000 | Not Detected |
| 1,2-Dichloropropane | 2700 | Not Detected | 12000 | Not Detected |
| 1,4-Dioxane | 11000 | Not Detected | 39000 | Not Detected |
| Bromodichloromethane | 2700 | Not Detected | 18000 | Not Detected |
| cis-1,3-Dichloropropene | 2700 | Not Detected | 12000 | Not Detected |
| 4-Methyl-2-pentanone | 11000 | Not Detected UJ | 44000 | Not Detected UJ |
| Toluene | 2700 | 160000 | 10000 | 610000 |
| trans-1,3-Dichloropropene | 2700 | Not Detected | 12000 | Not Detected |
| 1,1,2-Trichloroethane | 2700 | Not Detected | 15000 | Not Detected |
| Tetrachloroethene | 2700 | Not Detected | 18000 | Not Detected |
| 2-Hexanone | 11000 | Not Detected UJ | 44000 | Not Detected UJ |

eurofins | Air Toxics

**Client Sample ID: VMP-4-39-020713**

**Lab ID#: 1302278A-04A**

**EPA METHOD TO-15 GC/MS**

| | | | |
|---|---|---|---|
| **File Name:** | **14021944** | **Date of Collection: 2/7/13 1:43:00 PM** | |
| **Dil. Factor:** | **538** | **Date of Analysis: 2/20/13 04:15 PM** | |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Dibromochloromethane | 2700 | Not Detected | 23000 | Not Detected |
| 1,2-Dibromoethane (EDB) | 2700 | Not Detected | 21000 | Not Detected |
| Chlorobenzene | 2700 | Not Detected | 12000 | Not Detected |
| Ethyl Benzene | 2700 | 100000 | 12000 | 450000 |
| m,p-Xylene | 2700 | 180000 | 12000 | 790000 |
| o-Xylene | 2700 | 70000 | 12000 | 310000 |
| Styrene | 2700 | Not Detected | 11000 | Not Detected |
| Bromoform | 2700 | Not Detected | 28000 | Not Detected |
| Cumene | 2700 | 1100 J | 13000 | 5500 J |
| 1,1,2,2-Tetrachloroethane | 2700 | Not Detected | 18000 | Not Detected |
| Propylbenzene | 2700 | 610 J | 13000 | 3000 J |
| 4-Ethyltoluene | 2700 | 12000 | 13000 | 58000 |
| 1,3,5-Trimethylbenzene | 2700 | 3300 | 13000 | 16000 |
| 1,2,4-Trimethylbenzene | 2700 | 2400 J | 13000 | 12000 J |
| 1,3-Dichlorobenzene | 2700 | Not Detected | 16000 | Not Detected |
| 1,4-Dichlorobenzene | 2700 | Not Detected | 16000 | Not Detected |
| alpha-Chlorotoluene | 2700 | Not Detected | 14000 | Not Detected |
| 1,2-Dichlorobenzene | 2700 | Not Detected | 16000 | Not Detected |
| 1,2,4-Trichlorobenzene | 11000 | Not Detected | 80000 | Not Detected |
| Hexachlorobutadiene | 11000 | Not Detected | 110000 | Not Detected |
| Butane | 11000 | 1100000 | 26000 | 2500000 |
| Isopentane | 11000 | 1800000 | 32000 | 5300000 |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| 1,2-Dichloroethane-d4 | 108 | 70-130 |
| Toluene-d8 | 100 | 70-130 |
| 4-Bromofluorobenzene | 99 | 70-130 |

eurofins | Air Toxics

**Client Sample ID: VMP-15-21.5-020713**

**Lab ID#: 1302278A-05A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p022117** | **Date of Collection:** | **2/7/13 3:27:00 PM** |
| **Dil. Factor:** | **11.0** | **Date of Analysis:** | **2/21/13 07:03 PM** |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 5.5 | Not Detected | 27 | Not Detected |
| Freon 114 | 5.5 | Not Detected | 38 | Not Detected |
| Chloromethane | 55 | Not Detected | 110 | Not Detected |
| Vinyl Chloride | 5.5 | Not Detected | 14 | Not Detected |
| 1,3-Butadiene | 5.5 | Not Detected | 12 | Not Detected |
| Bromomethane | 55 | Not Detected | 210 | Not Detected |
| Chloroethane | 22 | Not Detected | 58 | Not Detected |
| Freon 11 | 5.5 | Not Detected | 31 | Not Detected |
| Ethanol | 22 | 21 J | 41 | 40 J |
| Freon 113 | 5.5 | Not Detected | 42 | Not Detected |
| 1,1-Dichloroethene | 5.5 | Not Detected | 22 | Not Detected |
| Acetone | 55 | 14 J | 130 | 34 J |
| 2-Propanol | 22 | 10 J | 54 | 26 J |
| Carbon Disulfide | 22 | 9.3 J | 68 | 29 J |
| 3-Chloropropene | 22 | Not Detected | 69 | Not Detected |
| Methylene Chloride | 55 | Not Detected | 190 | Not Detected |
| Methyl tert-butyl ether | 5.5 | Not Detected | 20 | Not Detected |
| trans-1,2-Dichloroethene | 5.5 | Not Detected | 22 | Not Detected |
| Hexane | 5.5 | 120 | 19 | 410 |
| 1,1-Dichloroethane | 5.5 | Not Detected | 22 | Not Detected |
| 2-Butanone (Methyl Ethyl Ketone) | 22 | Not Detected | 65 | Not Detected |
| cis-1,2-Dichloroethene | 5.5 | Not Detected | 22 | Not Detected |
| Tetrahydrofuran | 5.5 | Not Detected | 16 | Not Detected |
| Chloroform | 5.5 | Not Detected | 27 | Not Detected |
| 1,1,1-Trichloroethane | 5.5 | Not Detected | 30 | Not Detected |
| Cyclohexane | 5.5 | 27 | 19 | 93 |
| Carbon Tetrachloride | 5.5 | Not Detected | 35 | Not Detected |
| 2,2,4-Trimethylpentane | 5.5 | 1400 | 26 | 6400 |
| Benzene | 5.5 | 2.4 J | 18 | 7.7 J |
| 1,2-Dichloroethane | 5.5 | Not Detected | 22 | Not Detected |
| Heptane | 5.5 | 31 | 22 | 120 |
| Trichloroethene | 5.5 | Not Detected | 30 | Not Detected |
| 1,2-Dichloropropane | 5.5 | Not Detected | 25 | Not Detected |
| 1,4-Dioxane | 22 | Not Detected | 79 | Not Detected |
| Bromodichloromethane | 5.5 | Not Detected | 37 | Not Detected |
| cis-1,3-Dichloropropene | 5.5 | Not Detected | 25 | Not Detected |
| 4-Methyl-2-pentanone | 5.5 | Not Detected | 22 | Not Detected |
| Toluene | 5.5 | 1.5 J | 21 | 5.7 J |
| trans-1,3-Dichloropropene | 5.5 | Not Detected | 25 | Not Detected |
| 1,1,2-Trichloroethane | 5.5 | Not Detected | 30 | Not Detected |
| Tetrachloroethene | 5.5 | Not Detected | 37 | Not Detected |
| 2-Hexanone | 22 | Not Detected | 90 | Not Detected |

eurofins | Air Toxics

**Client Sample ID: VMP-15-21.5-020713**

**Lab ID#: 1302278A-05A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p022117** | **Date of Collection: 2/7/13 3:27:00 PM** | |
| **Dil. Factor:** | **11.0** | **Date of Analysis: 2/21/13 07:03 PM** | |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Dibromochloromethane | 5.5 | Not Detected | 47 | Not Detected |
| 1,2-Dibromoethane (EDB) | 5.5 | Not Detected | 42 | Not Detected |
| Chlorobenzene | 5.5 | Not Detected | 25 | Not Detected |
| Ethyl Benzene | 5.5 | Not Detected | 24 | Not Detected |
| m,p-Xylene | 5.5 | Not Detected | 24 | Not Detected |
| o-Xylene | 5.5 | Not Detected | 24 | Not Detected |
| Styrene | 5.5 | Not Detected | 23 | Not Detected |
| Bromoform | 5.5 | Not Detected | 57 | Not Detected |
| Cumene | 5.5 | Not Detected | 27 | Not Detected |
| 1,1,2,2-Tetrachloroethane | 5.5 | Not Detected | 38 | Not Detected |
| Propylbenzene | 5.5 | Not Detected | 27 | Not Detected |
| 4-Ethyltoluene | 5.5 | Not Detected | 27 | Not Detected |
| 1,3,5-Trimethylbenzene | 5.5 | Not Detected | 27 | Not Detected |
| 1,2,4-Trimethylbenzene | 5.5 | Not Detected | 27 | Not Detected |
| 1,3-Dichlorobenzene | 5.5 | Not Detected | 33 | Not Detected |
| 1,4-Dichlorobenzene | 5.5 | Not Detected | 33 | Not Detected |
| alpha-Chlorotoluene | 5.5 | Not Detected | 28 | Not Detected |
| 1,2-Dichlorobenzene | 5.5 | Not Detected | 33 | Not Detected |
| 1,2,4-Trichlorobenzene | 22 | Not Detected | 160 | Not Detected |
| Hexachlorobutadiene | 22 | Not Detected | 230 | Not Detected |
| Butane | 22 | 170 | 52 | 400 |
| Isopentane | 22 | 300 | 65 | 900 |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| Toluene-d8 | 97 | 70-130 |
| 1,2-Dichloroethane-d4 | 89 | 70-130 |
| 4-Bromofluorobenzene | 93 | 70-130 |

eurofins | Air Toxics

**Client Sample ID: VMP-15-25.5-021213**

**Lab ID#: 1302278A-06A**

**EPA METHOD TO-15 GC/MS**

| | | | |
|---|---|---|---|
| **File Name:** | **14021938** | **Date of Collection:** | **2/12/13 2:49:00 PM** |
| **Dil. Factor:** | **8.97** | **Date of Analysis:** | **2/20/13 12:14 PM** |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 45 | Not Detected | 220 | Not Detected |
| Freon 114 | 45 | Not Detected | 310 | Not Detected |
| Chloromethane | 180 | Not Detected | 370 | Not Detected |
| Vinyl Chloride | 45 | Not Detected | 110 | Not Detected |
| 1,3-Butadiene | 45 | Not Detected | 99 | Not Detected |
| Bromomethane | 45 | Not Detected | 170 | Not Detected |
| Chloroethane | 180 | Not Detected | 470 | Not Detected |
| Freon 11 | 45 | Not Detected | 250 | Not Detected |
| Ethanol | 180 | Not Detected | 340 | Not Detected |
| Freon 113 | 45 | Not Detected | 340 | Not Detected |
| 1,1-Dichloroethene | 45 | Not Detected | 180 | Not Detected |
| Acetone | 180 | Not Detected | 430 | Not Detected |
| 2-Propanol | 180 | Not Detected | 440 | Not Detected |
| Carbon Disulfide | 45 | Not Detected | 140 | Not Detected |
| 3-Chloropropene | 180 | Not Detected | 560 | Not Detected |
| Methylene Chloride | 45 | 66 | 160 | 230 |
| Methyl tert-butyl ether | 45 | Not Detected | 160 | Not Detected |
| trans-1,2-Dichloroethene | 45 | Not Detected | 180 | Not Detected |
| Hexane | 45 | Not Detected | 160 | Not Detected |
| 1,1-Dichloroethane | 45 | Not Detected | 180 | Not Detected |
| 2-Butanone (Methyl Ethyl Ketone) | 180 | Not Detected | 530 | Not Detected |
| cis-1,2-Dichloroethene | 45 | Not Detected | 180 | Not Detected |
| Tetrahydrofuran | 45 | Not Detected | 130 | Not Detected |
| Chloroform | 45 | Not Detected | 220 | Not Detected |
| 1,1,1-Trichloroethane | 45 | Not Detected | 240 | Not Detected |
| Cyclohexane | 45 | Not Detected | 150 | Not Detected |
| Carbon Tetrachloride | 45 | Not Detected | 280 | Not Detected |
| 2,2,4-Trimethylpentane | 45 | 31000 | 210 | 140000 |
| Benzene | 45 | Not Detected | 140 | Not Detected |
| 1,2-Dichloroethane | 45 | Not Detected | 180 | Not Detected |
| Heptane | 45 | Not Detected | 180 | Not Detected |
| Trichloroethene | 45 | Not Detected | 240 | Not Detected |
| 1,2-Dichloropropane | 45 | Not Detected | 210 | Not Detected |
| 1,4-Dioxane | 180 | Not Detected | 650 | Not Detected |
| Bromodichloromethane | 45 | Not Detected | 300 | Not Detected |
| cis-1,3-Dichloropropene | 45 | Not Detected | 200 | Not Detected |
| 4-Methyl-2-pentanone | 180 | Not Detected | 730 | Not Detected |
| Toluene | 45 | Not Detected | 170 | Not Detected |
| trans-1,3-Dichloropropene | 45 | Not Detected | 200 | Not Detected |
| 1,1,2-Trichloroethane | 45 | Not Detected | 240 | Not Detected |
| Tetrachloroethene | 45 | Not Detected | 300 | Not Detected |
| 2-Hexanone | 180 | Not Detected | 730 | Not Detected |

eurofins | Air Toxics

**Client Sample ID: VMP-15-25.5-021213**

**Lab ID#: 1302278A-06A**

**EPA METHOD TO-15 GC/MS**

| | | | |
|---|---|---|---|
| **File Name:** | **14021938** | **Date of Collection: 2/12/13 2:49:00 PM** | |
| **Dil. Factor:** | **8.97** | **Date of Analysis: 2/20/13 12:14 PM** | |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Dibromochloromethane | 45 | Not Detected | 380 | Not Detected |
| 1,2-Dibromoethane (EDB) | 45 | Not Detected | 340 | Not Detected |
| Chlorobenzene | 45 | Not Detected | 210 | Not Detected |
| Ethyl Benzene | 45 | Not Detected | 190 | Not Detected |
| m,p-Xylene | 45 | 17 J | 190 | 74 J |
| o-Xylene | 45 | 8.7 J | 190 | 38 J |
| Styrene | 45 | Not Detected | 190 | Not Detected |
| Bromoform | 45 | Not Detected | 460 | Not Detected |
| Cumene | 45 | 14 J | 220 | 70 J |
| 1,1,2,2-Tetrachloroethane | 45 | Not Detected | 310 | Not Detected |
| Propylbenzene | 45 | Not Detected | 220 | Not Detected |
| 4-Ethyltoluene | 45 | Not Detected | 220 | Not Detected |
| 1,3,5-Trimethylbenzene | 45 | Not Detected | 220 | Not Detected |
| 1,2,4-Trimethylbenzene | 45 | 11 J | 220 | 54 J |
| 1,3-Dichlorobenzene | 45 | Not Detected | 270 | Not Detected |
| 1,4-Dichlorobenzene | 45 | Not Detected | 270 | Not Detected |
| alpha-Chlorotoluene | 45 | Not Detected | 230 | Not Detected |
| 1,2-Dichlorobenzene | 45 | Not Detected | 270 | Not Detected |
| 1,2,4-Trichlorobenzene | 180 | Not Detected | 1300 | Not Detected |
| Hexachlorobutadiene | 180 | Not Detected | 1900 | Not Detected |
| Butane | 180 | 1000 | 430 | 2400 |
| Isopentane | 180 | 12000 | 530 | 37000 |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| 1,2-Dichloroethane-d4 | 125 | 70-130 |
| Toluene-d8 | 103 | 70-130 |
| 4-Bromofluorobenzene | 99 | 70-130 |

eurofins | Air Toxics

**Client Sample ID: VMP-15-29-021213**
**Lab ID#: 1302278A-07A**
**EPA METHOD TO-15 GC/MS**

* USE THIS RESULT ONLY. ALL OTHER RESULTS REPORTED IN 5.38X DILUTION ANALYSIS.

| | | | |
|---|---|---|---|
| **File Name:** | **14021941** | **Date of Collection:** | **2/12/13 3:37:00 PM** |
| **Dil. Factor:** | **8.97** | **Date of Analysis:** | **2/20/13 02:26 PM** |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 45 | Not Detected | 220 | Not Detected |
| Freon 114 | 45 | Not Detected | 310 | Not Detected |
| Chloromethane | 180 | Not Detected | 370 | Not Detected |
| Vinyl Chloride | 45 | Not Detected | 110 | Not Detected |
| 1,3-Butadiene | 45 | Not Detected | 99 | Not Detected |
| Bromomethane | 45 | Not Detected | 170 | Not Detected |
| Chloroethane | 180 | Not Detected | 470 | Not Detected |
| Freon 11 | 45 | Not Detected | 250 | Not Detected |
| Ethanol | 180 | Not Detected | 340 | Not Detected |
| Freon 113 | 45 | Not Detected | 340 | Not Detected |
| 1,1-Dichloroethene | 45 | Not Detected | 180 | Not Detected |
| Acetone | 180 | 90 J | 430 | 210 J |
| 2-Propanol | 180 | Not Detected | 440 | Not Detected |
| Carbon Disulfide | 45 | Not Detected | 140 | Not Detected |
| 3-Chloropropene | 180 | Not Detected | 560 | Not Detected |
| Methylene Chloride | 45 | 28 J | 160 | 96 J |
| Methyl tert-butyl ether | 45 | Not Detected | 160 | Not Detected |
| trans-1,2-Dichloroethene | 45 | Not Detected | 180 | Not Detected |
| Hexane | 45 | Not Detected | 160 | Not Detected |
| 1,1-Dichloroethane | 45 | Not Detected | 180 | Not Detected |
| 2-Butanone (Methyl Ethyl Ketone) | 180 | Not Detected | 530 | Not Detected |
| cis-1,2-Dichloroethene | 45 | Not Detected | 180 | Not Detected |
| Tetrahydrofuran | 45 | Not Detected | 130 | Not Detected |
| Chloroform | 45 | Not Detected | 220 | Not Detected |
| 1,1,1-Trichloroethane | 45 | Not Detected | 240 | Not Detected |
| Cyclohexane | 45 | Not Detected | 150 | Not Detected |
| Carbon Tetrachloride | 45 | Not Detected | 280 | Not Detected |
| * 2,2,4-Trimethylpentane | 45 | 23000 | 210 | 110000 |
| Benzene | 45 | Not Detected | 140 | Not Detected |
| 1,2-Dichloroethane | 45 | Not Detected | 180 | Not Detected |
| Heptane | 45 | Not Detected | 180 | Not Detected |
| Trichloroethene | 45 | Not Detected | 240 | Not Detected |
| 1,2-Dichloropropane | 45 | Not Detected | 210 | Not Detected |
| 1,4-Dioxane | 180 | Not Detected | 650 | Not Detected |
| Bromodichloromethane | 45 | Not Detected | 300 | Not Detected |
| cis-1,3-Dichloropropene | 45 | Not Detected | 200 | Not Detected |
| 4-Methyl-2-pentanone | 180 | Not Detected | 730 | Not Detected |
| Toluene | 45 | Not Detected | 170 | Not Detected |
| trans-1,3-Dichloropropene | 45 | Not Detected | 200 | Not Detected |
| 1,1,2-Trichloroethane | 45 | Not Detected | 240 | Not Detected |
| Tetrachloroethene | 45 | Not Detected | 300 | Not Detected |
| 2-Hexanone | 180 | Not Detected | 730 | Not Detected |

eurofins | Air Toxics

**Client Sample ID: VMP-15-29-021213**
**Lab ID#: 1302278A-07A**
**EPA METHOD TO-15 GC/MS**

| | | | |
|---|---|---|---|
| **File Name:** | **14021941** | **Date of Collection: 2/12/13 3:37:00 PM** | |
| **Dil. Factor:** | **8.97** | **Date of Analysis: 2/20/13 02:26 PM** | |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Dibromochloromethane | 45 | Not Detected | 380 | Not Detected |
| 1,2-Dibromoethane (EDB) | 45 | Not Detected | 340 | Not Detected |
| Chlorobenzene | 45 | Not Detected | 210 | Not Detected |
| Ethyl Benzene | 45 | Not Detected | 190 | Not Detected |
| m,p-Xylene | 45 | Not Detected | 190 | Not Detected |
| o-Xylene | 45 | Not Detected | 190 | Not Detected |
| Styrene | 45 | Not Detected | 190 | Not Detected |
| Bromoform | 45 | Not Detected | 460 | Not Detected |
| Cumene | 45 | Not Detected | 220 | Not Detected |
| 1,1,2,2-Tetrachloroethane | 45 | Not Detected | 310 | Not Detected |
| Propylbenzene | 45 | Not Detected | 220 | Not Detected |
| 4-Ethyltoluene | 45 | Not Detected | 220 | Not Detected |
| 1,3,5-Trimethylbenzene | 45 | Not Detected | 220 | Not Detected |
| 1,2,4-Trimethylbenzene | 45 | Not Detected | 220 | Not Detected |
| 1,3-Dichlorobenzene | 45 | Not Detected | 270 | Not Detected |
| 1,4-Dichlorobenzene | 45 | Not Detected | 270 | Not Detected |
| alpha-Chlorotoluene | 45 | Not Detected | 230 | Not Detected |
| 1,2-Dichlorobenzene | 45 | Not Detected | 270 | Not Detected |
| 1,2,4-Trichlorobenzene | 180 | Not Detected | 1300 | Not Detected |
| Hexachlorobutadiene | 180 | Not Detected | 1900 | Not Detected |
| Butane | 180 | 640 | 430 | 1500 |
| Isopentane | 180 | 12000 | 530 | 37000 |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| 1,2-Dichloroethane-d4 | 114 | 70-130 |
| Toluene-d8 | 102 | 70-130 |
| 4-Bromofluorobenzene | 98 | 70-130 |

eurofins | Air Toxics

**Client Sample ID: VMP-15-29-021213**
**Lab ID#: 1302278A-07B**
**EPA METHOD TO-15 GC/MS**

* DO NOT USE THIS RESULT. USE ALL OTHER DATA.

| | | | |
|---|---|---|---|
| **File Name:** | **14021939** | **Date of Collection:** | **2/12/13 3:37:00 PM** |
| **Dil. Factor:** | **5.38** | **Date of Analysis:** | **2/20/13 01:11 PM** |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 27 | Not Detected | 130 | Not Detected |
| Freon 114 | 27 | Not Detected | 190 | Not Detected |
| Chloromethane | 110 | Not Detected | 220 | Not Detected |
| Vinyl Chloride | 27 | Not Detected | 69 | Not Detected |
| 1,3-Butadiene | 27 | Not Detected | 60 | Not Detected |
| Bromomethane | 27 | Not Detected | 100 | Not Detected |
| Chloroethane | 110 | Not Detected | 280 | Not Detected |
| Freon 11 | 27 | Not Detected | 150 | Not Detected |
| Ethanol | 110 | Not Detected | 200 | Not Detected |
| Freon 113 | 27 | Not Detected | 210 | Not Detected |
| 1,1-Dichloroethene | 27 | Not Detected | 110 | Not Detected |
| Acetone | 110 | 110 | 260 | 260 |
| 2-Propanol | 110 | Not Detected | 260 | Not Detected |
| Carbon Disulfide | 27 | Not Detected | 84 | Not Detected |
| 3-Chloropropene | 110 | Not Detected | 340 | Not Detected |
| Methylene Chloride | 27 | Not Detected | 93 | Not Detected |
| Methyl tert-butyl ether | 27 | Not Detected | 97 | Not Detected |
| trans-1,2-Dichloroethene | 27 | Not Detected | 110 | Not Detected |
| Hexane | 27 | Not Detected | 95 | Not Detected |
| 1,1-Dichloroethane | 27 | Not Detected | 110 | Not Detected |
| 2-Butanone (Methyl Ethyl Ketone) | 110 | Not Detected | 320 | Not Detected |
| cis-1,2-Dichloroethene | 27 | Not Detected | 110 | Not Detected |
| Tetrahydrofuran | 27 | Not Detected | 79 | Not Detected |
| Chloroform | 27 | Not Detected | 130 | Not Detected |
| 1,1,1-Trichloroethane | 27 | Not Detected | 150 | Not Detected |
| Cyclohexane | 27 | Not Detected | 92 | Not Detected |
| Carbon Tetrachloride | 27 | Not Detected | 170 | Not Detected |
| * ~~2,2,4-Trimethylpentane~~ | ~~27~~ | ~~30000 E~~ | ~~120~~ | ~~140000 E~~ |
| Benzene | 27 | Not Detected | 86 | Not Detected |
| 1,2-Dichloroethane | 27 | Not Detected | 110 | Not Detected |
| Heptane | 27 | Not Detected | 110 | Not Detected |
| Trichloroethene | 27 | Not Detected | 140 | Not Detected |
| 1,2-Dichloropropane | 27 | Not Detected | 120 | Not Detected |
| 1,4-Dioxane | 110 | Not Detected | 390 | Not Detected |
| Bromodichloromethane | 27 | Not Detected | 180 | Not Detected |
| cis-1,3-Dichloropropene | 27 | Not Detected | 120 | Not Detected |
| 4-Methyl-2-pentanone | 110 | Not Detected | 440 | Not Detected |
| Toluene | 27 | Not Detected | 100 | Not Detected |
| trans-1,3-Dichloropropene | 27 | Not Detected | 120 | Not Detected |
| 1,1,2-Trichloroethane | 27 | Not Detected | 150 | Not Detected |
| Tetrachloroethene | 27 | Not Detected | 180 | Not Detected |
| 2-Hexanone | 110 | Not Detected | 440 | Not Detected |

eurofins | Air Toxics

**Client Sample ID: VMP-15-29-021213**

**Lab ID#: 1302278A-07B**

**EPA METHOD TO-15 GC/MS**

| | | | |
|---|---|---|---|
| **File Name:** | **14021939** | **Date of Collection: 2/12/13 3:37:00 PM** | |
| **Dil. Factor:** | **5.38** | **Date of Analysis: 2/20/13 01:11 PM** | |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Dibromochloromethane | 27 | Not Detected | 230 | Not Detected |
| 1,2-Dibromoethane (EDB) | 27 | Not Detected | 210 | Not Detected |
| Chlorobenzene | 27 | Not Detected | 120 | Not Detected |
| Ethyl Benzene | 27 | Not Detected | 120 | Not Detected |
| m,p-Xylene | 27 | Not Detected | 120 | Not Detected |
| o-Xylene | 27 | Not Detected | 120 | Not Detected |
| Styrene | 27 | Not Detected | 110 | Not Detected |
| Bromoform | 27 | Not Detected | 280 | Not Detected |
| Cumene | 27 | Not Detected | 130 | Not Detected |
| 1,1,2,2-Tetrachloroethane | 27 | Not Detected | 180 | Not Detected |
| Propylbenzene | 27 | Not Detected | 130 | Not Detected |
| 4-Ethyltoluene | 27 | Not Detected | 130 | Not Detected |
| 1,3,5-Trimethylbenzene | 27 | Not Detected | 130 | Not Detected |
| 1,2,4-Trimethylbenzene | 27 | Not Detected | 130 | Not Detected |
| 1,3-Dichlorobenzene | 27 | Not Detected | 160 | Not Detected |
| 1,4-Dichlorobenzene | 27 | Not Detected | 160 | Not Detected |
| alpha-Chlorotoluene | 27 | Not Detected | 140 | Not Detected |
| 1,2-Dichlorobenzene | 27 | Not Detected | 160 | Not Detected |
| 1,2,4-Trichlorobenzene | 110 | Not Detected | 800 | Not Detected |
| Hexachlorobutadiene | 110 | Not Detected | 1100 | Not Detected |
| Butane | 110 | 830 | 260 | 2000 |
| Isopentane | 110 | 16000 | 320 | 48000 |

E = Exceeds instrument calibration range.

**Container Type: 1 Liter Summa Canister**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| 1,2-Dichloroethane-d4 | 128 | 70-130 |
| Toluene-d8 | 105 | 70-130 |
| 4-Bromofluorobenzene | 99 | 70-130 |

eurofins | Air Toxics

**Client Sample ID: VMP-31-20-021113**

**Lab ID#: 1302278A-08A**

**EPA METHOD TO-15 GC/MS**

| | | | |
|---|---|---|---|
| **File Name:** | **14021940** | **Date of Collection:** | **2/11/13 12:05:00 PM** |
| **Dil. Factor:** | **3.94** | **Date of Analysis:** | **2/20/13 01:30 PM** |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 20 | Not Detected | 97 | Not Detected |
| Freon 114 | 20 | Not Detected | 140 | Not Detected |
| Chloromethane | 79 | Not Detected | 160 | Not Detected |
| Vinyl Chloride | 20 | Not Detected | 50 | Not Detected |
| 1,3-Butadiene | 20 | Not Detected | 44 | Not Detected |
| Bromomethane | 20 | Not Detected | 76 | Not Detected |
| Chloroethane | 79 | Not Detected | 210 | Not Detected |
| Freon 11 | 20 | Not Detected | 110 | Not Detected |
| Ethanol | 79 | 220 | 150 | 420 |
| Freon 113 | 20 | Not Detected | 150 | Not Detected |
| 1,1-Dichloroethene | 20 | Not Detected | 78 | Not Detected |
| Acetone | 79 | 19 J | 190 | 45 J |
| 2-Propanol | 79 | 20 J | 190 | 49 J |
| Carbon Disulfide | 20 | Not Detected | 61 | Not Detected |
| 3-Chloropropene | 79 | Not Detected | 250 | Not Detected |
| Methylene Chloride | 20 | Not Detected | 68 | Not Detected |
| Methyl tert-butyl ether | 20 | Not Detected | 71 | Not Detected |
| trans-1,2-Dichloroethene | 20 | Not Detected | 78 | Not Detected |
| Hexane | 20 | Not Detected | 69 | Not Detected |
| 1,1-Dichloroethane | 20 | Not Detected | 80 | Not Detected |
| 2-Butanone (Methyl Ethyl Ketone) | 79 | Not Detected | 230 | Not Detected |
| cis-1,2-Dichloroethene | 20 | Not Detected | 78 | Not Detected |
| Tetrahydrofuran | 20 | Not Detected | 58 | Not Detected |
| Chloroform | 20 | Not Detected | 96 | Not Detected |
| 1,1,1-Trichloroethane | 20 | Not Detected | 110 | Not Detected |
| Cyclohexane | 20 | Not Detected | 68 | Not Detected |
| Carbon Tetrachloride | 20 | Not Detected | 120 | Not Detected |
| 2,2,4-Trimethylpentane | 20 | 18000 | 92 | 87000 |
| Benzene | 20 | Not Detected | 63 | Not Detected |
| 1,2-Dichloroethane | 20 | Not Detected | 80 | Not Detected |
| Heptane | 20 | Not Detected | 81 | Not Detected |
| Trichloroethene | 20 | Not Detected | 100 | Not Detected |
| 1,2-Dichloropropane | 20 | Not Detected | 91 | Not Detected |
| 1,4-Dioxane | 79 | 14 J | 280 | 50 J |
| Bromodichloromethane | 20 | Not Detected | 130 | Not Detected |
| cis-1,3-Dichloropropene | 20 | Not Detected | 89 | Not Detected |
| 4-Methyl-2-pentanone | 79 | Not Detected | 320 | Not Detected |
| Toluene | 20 | Not Detected | 74 | Not Detected |
| trans-1,3-Dichloropropene | 20 | Not Detected | 89 | Not Detected |
| 1,1,2-Trichloroethane | 20 | Not Detected | 110 | Not Detected |
| Tetrachloroethene | 20 | Not Detected | 130 | Not Detected |
| 2-Hexanone | 79 | Not Detected | 320 | Not Detected |

eurofins | Air Toxics

**Client Sample ID: VMP-31-20-021113**

**Lab ID#: 1302278A-08A**

**EPA METHOD TO-15 GC/MS**

| | | | |
|---|---|---|---|
| **File Name:** | **14021940** | **Date of Collection:** | **2/11/13 12:05:00 PM** |
| **Dil. Factor:** | **3.94** | **Date of Analysis:** | **2/20/13 01:30 PM** |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Dibromochloromethane | 20 | Not Detected | 170 | Not Detected |
| 1,2-Dibromoethane (EDB) | 20 | Not Detected | 150 | Not Detected |
| Chlorobenzene | 20 | Not Detected | 91 | Not Detected |
| Ethyl Benzene | 20 | Not Detected | 86 | Not Detected |
| m,p-Xylene | 20 | Not Detected | 86 | Not Detected |
| o-Xylene | 20 | Not Detected | 86 | Not Detected |
| Styrene | 20 | Not Detected | 84 | Not Detected |
| Bromoform | 20 | Not Detected | 200 | Not Detected |
| Cumene | 20 | Not Detected | 97 | Not Detected |
| 1,1,2,2-Tetrachloroethane | 20 | Not Detected | 140 | Not Detected |
| Propylbenzene | 20 | Not Detected | 97 | Not Detected |
| 4-Ethyltoluene | 20 | Not Detected | 97 | Not Detected |
| 1,3,5-Trimethylbenzene | 20 | Not Detected | 97 | Not Detected |
| 1,2,4-Trimethylbenzene | 20 | Not Detected | 97 | Not Detected |
| 1,3-Dichlorobenzene | 20 | Not Detected | 120 | Not Detected |
| 1,4-Dichlorobenzene | 20 | Not Detected | 120 | Not Detected |
| alpha-Chlorotoluene | 20 | Not Detected | 100 | Not Detected |
| 1,2-Dichlorobenzene | 20 | Not Detected | 120 | Not Detected |
| 1,2,4-Trichlorobenzene | 79 | Not Detected | 580 | Not Detected |
| Hexachlorobutadiene | 79 | Not Detected | 840 | Not Detected |
| Butane | 79 | 650 | 190 | 1500 |
| Isopentane | 79 | 4300 | 230 | 13000 |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| 1,2-Dichloroethane-d4 | 118 | 70-130 |
| Toluene-d8 | 104 | 70-130 |
| 4-Bromofluorobenzene | 98 | 70-130 |

eurofins | Air Toxics

**Client Sample ID: VMP-31-30-021113**

**Lab ID#: 1302278A-09A**

**EPA METHOD TO-15 GC/MS**

| | | | |
|---|---|---|---|
| **File Name:** | **14021942** | **Date of Collection:** | **2/11/13 2:33:00 PM** |
| **Dil. Factor:** | **282** | **Date of Analysis:** | **2/20/13 02:58 PM** |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 1400 | Not Detected | 7000 | Not Detected |
| Freon 114 | 1400 | Not Detected | 9800 | Not Detected |
| Chloromethane | 5600 | Not Detected | 12000 | Not Detected |
| Vinyl Chloride | 1400 | Not Detected | 3600 | Not Detected |
| 1,3-Butadiene | 1400 | Not Detected | 3100 | Not Detected |
| Bromomethane | 1400 | Not Detected | 5500 | Not Detected |
| Chloroethane | 5600 | Not Detected | 15000 | Not Detected |
| Freon 11 | 1400 | Not Detected | 7900 | Not Detected |
| Ethanol | 5600 | Not Detected | 11000 | Not Detected |
| Freon 113 | 1400 | Not Detected | 11000 | Not Detected |
| 1,1-Dichloroethene | 1400 | Not Detected | 5600 | Not Detected |
| Acetone | 5600 | Not Detected | 13000 | Not Detected |
| 2-Propanol | 5600 | Not Detected | 14000 | Not Detected |
| Carbon Disulfide | 1400 | Not Detected | 4400 | Not Detected |
| 3-Chloropropene | 5600 | Not Detected | 18000 | Not Detected |
| Methylene Chloride | 1400 | Not Detected | 4900 | Not Detected |
| Methyl tert-butyl ether | 1400 | Not Detected | 5100 | Not Detected |
| trans-1,2-Dichloroethene | 1400 | Not Detected | 5600 | Not Detected |
| Hexane | 1400 | Not Detected | 5000 | Not Detected |
| 1,1-Dichloroethane | 1400 | Not Detected | 5700 | Not Detected |
| 2-Butanone (Methyl Ethyl Ketone) | 5600 | 880 J | 17000 | 2600 J |
| cis-1,2-Dichloroethene | 1400 | Not Detected | 5600 | Not Detected |
| Tetrahydrofuran | 1400 | Not Detected | 4200 | Not Detected |
| Chloroform | 1400 | Not Detected | 6900 | Not Detected |
| 1,1,1-Trichloroethane | 1400 | Not Detected | 7700 | Not Detected |
| Cyclohexane | 1400 | Not Detected | 4800 | Not Detected |
| Carbon Tetrachloride | 1400 | Not Detected | 8900 | Not Detected |
| 2,2,4-Trimethylpentane | 1400 | 84000 | 6600 | 400000 |
| Benzene | 1400 | Not Detected | 4500 | Not Detected |
| 1,2-Dichloroethane | 1400 | Not Detected | 5700 | Not Detected |
| Heptane | 1400 | Not Detected | 5800 | Not Detected |
| Trichloroethene | 1400 | Not Detected | 7600 | Not Detected |
| 1,2-Dichloropropane | 1400 | Not Detected | 6500 | Not Detected |
| 1,4-Dioxane | 5600 | Not Detected | 20000 | Not Detected |
| Bromodichloromethane | 1400 | Not Detected | 9400 | Not Detected |
| cis-1,3-Dichloropropene | 1400 | Not Detected | 6400 | Not Detected |
| 4-Methyl-2-pentanone | 5600 | Not Detected | 23000 | Not Detected |
| Toluene | 1400 | 410 J | 5300 | 1600 J |
| trans-1,3-Dichloropropene | 1400 | Not Detected | 6400 | Not Detected |
| 1,1,2-Trichloroethane | 1400 | Not Detected | 7700 | Not Detected |
| Tetrachloroethene | 1400 | Not Detected | 9600 | Not Detected |
| 2-Hexanone | 5600 | Not Detected | 23000 | Not Detected |

eurofins | Air Toxics

**Client Sample ID: VMP-31-30-021113**

**Lab ID#: 1302278A-09A**

**EPA METHOD TO-15 GC/MS**

| | | | |
|---|---|---|---|
| **File Name:** | **14021942** | **Date of Collection: 2/11/13 2:33:00 PM** | |
| **Dil. Factor:** | **282** | **Date of Analysis: 2/20/13 02:58 PM** | |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Dibromochloromethane | 1400 | Not Detected | 12000 | Not Detected |
| 1,2-Dibromoethane (EDB) | 1400 | Not Detected | 11000 | Not Detected |
| Chlorobenzene | 1400 | Not Detected | 6500 | Not Detected |
| Ethyl Benzene | 1400 | Not Detected | 6100 | Not Detected |
| m,p-Xylene | 1400 | 490 J | 6100 | 2100 J |
| o-Xylene | 1400 | 1700 | 6100 | 7200 |
| Styrene | 1400 | Not Detected | 6000 | Not Detected |
| Bromoform | 1400 | Not Detected | 14000 | Not Detected |
| Cumene | 1400 | Not Detected | 6900 | Not Detected |
| 1,1,2,2-Tetrachloroethane | 1400 | Not Detected | 9700 | Not Detected |
| Propylbenzene | 1400 | Not Detected | 6900 | Not Detected |
| 4-Ethyltoluene | 1400 | Not Detected | 6900 | Not Detected |
| 1,3,5-Trimethylbenzene | 1400 | Not Detected | 6900 | Not Detected |
| 1,2,4-Trimethylbenzene | 1400 | Not Detected | 6900 | Not Detected |
| 1,3-Dichlorobenzene | 1400 | Not Detected | 8500 | Not Detected |
| 1,4-Dichlorobenzene | 1400 | Not Detected | 8500 | Not Detected |
| alpha-Chlorotoluene | 1400 | Not Detected | 7300 | Not Detected |
| 1,2-Dichlorobenzene | 1400 | Not Detected | 8500 | Not Detected |
| 1,2,4-Trichlorobenzene | 5600 | Not Detected | 42000 | Not Detected |
| Hexachlorobutadiene | 5600 | Not Detected | 60000 | Not Detected |
| Butane | 5600 | 440000 | 13000 | 1000000 |
| Isopentane | 5600 | 470000 | 17000 | 1400000 |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| 1,2-Dichloroethane-d4 | 105 | 70-130 |
| Toluene-d8 | 98 | 70-130 |
| 4-Bromofluorobenzene | 97 | 70-130 |

eurofins | Air Toxics

**Client Sample ID: VMP-32-30-020513**

**Lab ID#: 1302278A-10A**

**EPA METHOD TO-15 GC/MS**

| | | | |
|---|---|---|---|
| **File Name:** | **14021906** | **Date of Collection:** | **2/5/13 11:41:00 AM** |
| **Dil. Factor:** | **11.3** | **Date of Analysis:** | **2/19/13 10:41 AM** |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 56 | Not Detected | 280 | Not Detected |
| Freon 114 | 56 | Not Detected | 390 | Not Detected |
| Chloromethane | 230 | Not Detected | 470 | Not Detected |
| Vinyl Chloride | 56 | Not Detected | 140 | Not Detected |
| 1,3-Butadiene | 56 | Not Detected | 120 | Not Detected |
| Bromomethane | 56 | Not Detected | 220 | Not Detected |
| Chloroethane | 230 | Not Detected | 600 | Not Detected |
| Freon 11 | 56 | Not Detected | 320 | Not Detected |
| Ethanol | 230 | Not Detected | 420 | Not Detected |
| Freon 113 | 56 | Not Detected | 430 | Not Detected |
| 1,1-Dichloroethene | 56 | Not Detected | 220 | Not Detected |
| Acetone | 230 | Not Detected | 540 | Not Detected |
| 2-Propanol | 230 | Not Detected | 560 | Not Detected |
| Carbon Disulfide | 56 | Not Detected | 180 | Not Detected |
| 3-Chloropropene | 230 | Not Detected | 710 | Not Detected |
| Methylene Chloride | 56 | 29 J | 200 | 100 J |
| Methyl tert-butyl ether | 56 | Not Detected | 200 | Not Detected |
| trans-1,2-Dichloroethene | 56 | Not Detected | 220 | Not Detected |
| Hexane | 56 | Not Detected | 200 | Not Detected |
| 1,1-Dichloroethane | 56 | Not Detected | 230 | Not Detected |
| 2-Butanone (Methyl Ethyl Ketone) | 230 | Not Detected | 670 | Not Detected |
| cis-1,2-Dichloroethene | 56 | Not Detected | 220 | Not Detected |
| Tetrahydrofuran | 56 | Not Detected | 170 | Not Detected |
| Chloroform | 56 | Not Detected | 280 | Not Detected |
| 1,1,1-Trichloroethane | 56 | Not Detected | 310 | Not Detected |
| Cyclohexane | 56 | Not Detected | 190 | Not Detected |
| Carbon Tetrachloride | 56 | Not Detected | 360 | Not Detected |
| 2,2,4-Trimethylpentane | 56 | 30000 | 260 | 140000 |
| Benzene | 56 | Not Detected | 180 | Not Detected |
| 1,2-Dichloroethane | 56 | Not Detected | 230 | Not Detected |
| Heptane | 56 | Not Detected | 230 | Not Detected |
| Trichloroethene | 56 | Not Detected | 300 | Not Detected |
| 1,2-Dichloropropane | 56 | Not Detected | 260 | Not Detected |
| 1,4-Dioxane | 230 | Not Detected | 810 | Not Detected |
| Bromodichloromethane | 56 | Not Detected | 380 | Not Detected |
| cis-1,3-Dichloropropene | 56 | Not Detected | 260 | Not Detected |
| 4-Methyl-2-pentanone | 230 | Not Detected | 920 | Not Detected |
| Toluene | 56 | Not Detected | 210 | Not Detected |
| trans-1,3-Dichloropropene | 56 | Not Detected | 260 | Not Detected |
| 1,1,2-Trichloroethane | 56 | Not Detected | 310 | Not Detected |
| Tetrachloroethene | 56 | Not Detected | 380 | Not Detected |
| 2-Hexanone | 230 | Not Detected | 920 | Not Detected |

eurofins | Air Toxics

**Client Sample ID: VMP-32-30-020513**

**Lab ID#: 1302278A-10A**

**EPA METHOD TO-15 GC/MS**

| | | | |
|---|---|---|---|
| **File Name:** | **14021906** | **Date of Collection:** | **2/5/13 11:41:00 AM** |
| **Dil. Factor:** | **11.3** | **Date of Analysis:** | **2/19/13 10:41 AM** |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Dibromochloromethane | 56 | Not Detected | 480 | Not Detected |
| 1,2-Dibromoethane (EDB) | 56 | Not Detected | 430 | Not Detected |
| Chlorobenzene | 56 | Not Detected | 260 | Not Detected |
| Ethyl Benzene | 56 | Not Detected | 240 | Not Detected |
| m,p-Xylene | 56 | Not Detected | 240 | Not Detected |
| o-Xylene | 56 | Not Detected | 240 | Not Detected |
| Styrene | 56 | Not Detected | 240 | Not Detected |
| Bromoform | 56 | Not Detected | 580 | Not Detected |
| Cumene | 56 | Not Detected | 280 | Not Detected |
| 1,1,2,2-Tetrachloroethane | 56 | Not Detected | 390 | Not Detected |
| Propylbenzene | 56 | Not Detected | 280 | Not Detected |
| 4-Ethyltoluene | 56 | Not Detected | 280 | Not Detected |
| 1,3,5-Trimethylbenzene | 56 | Not Detected | 280 | Not Detected |
| 1,2,4-Trimethylbenzene | 56 | Not Detected | 280 | Not Detected |
| 1,3-Dichlorobenzene | 56 | Not Detected | 340 | Not Detected |
| 1,4-Dichlorobenzene | 56 | Not Detected | 340 | Not Detected |
| alpha-Chlorotoluene | 56 | Not Detected | 290 | Not Detected |
| 1,2-Dichlorobenzene | 56 | Not Detected | 340 | Not Detected |
| 1,2,4-Trichlorobenzene | 230 | Not Detected | 1700 | Not Detected |
| Hexachlorobutadiene | 230 | Not Detected | 2400 | Not Detected |
| Butane | 230 | Not Detected | 540 | Not Detected |
| Isopentane | 230 | 63 J | 670 | 180 J |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| 1,2-Dichloroethane-d4 | 118 | 70-130 |
| Toluene-d8 | 101 | 70-130 |
| 4-Bromofluorobenzene | 100 | 70-130 |

eurofins | Air Toxics

**Client Sample ID: Lab Blank**
**Lab ID#: 1302278A-11A**
**EPA METHOD TO-15 GC/MS**

| | | | |
|---|---|---|---|
| **File Name:** | **14021905a** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 2/19/13 09:49 AM** | |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 5.0 | Not Detected | 25 | Not Detected |
| Freon 114 | 5.0 | Not Detected | 35 | Not Detected |
| Chloromethane | 20 | Not Detected | 41 | Not Detected |
| Vinyl Chloride | 5.0 | Not Detected | 13 | Not Detected |
| 1,3-Butadiene | 5.0 | 0.74 J | 11 | 1.6 J |
| Bromomethane | 5.0 | Not Detected | 19 | Not Detected |
| Chloroethane | 20 | Not Detected | 53 | Not Detected |
| Freon 11 | 5.0 | Not Detected | 28 | Not Detected |
| Ethanol | 20 | Not Detected | 38 | Not Detected |
| Freon 113 | 5.0 | Not Detected | 38 | Not Detected |
| 1,1-Dichloroethene | 5.0 | Not Detected | 20 | Not Detected |
| Acetone | 20 | Not Detected | 48 | Not Detected |
| 2-Propanol | 20 | Not Detected | 49 | Not Detected |
| Carbon Disulfide | 5.0 | Not Detected | 16 | Not Detected |
| 3-Chloropropene | 20 | Not Detected | 63 | Not Detected |
| Methylene Chloride | 5.0 | 1.7 J | 17 | 6.0 J |
| Methyl tert-butyl ether | 5.0 | Not Detected | 18 | Not Detected |
| trans-1,2-Dichloroethene | 5.0 | Not Detected | 20 | Not Detected |
| Hexane | 5.0 | Not Detected | 18 | Not Detected |
| 1,1-Dichloroethane | 5.0 | Not Detected | 20 | Not Detected |
| 2-Butanone (Methyl Ethyl Ketone) | 20 | Not Detected | 59 | Not Detected |
| cis-1,2-Dichloroethene | 5.0 | Not Detected | 20 | Not Detected |
| Tetrahydrofuran | 5.0 | Not Detected | 15 | Not Detected |
| Chloroform | 5.0 | Not Detected | 24 | Not Detected |
| 1,1,1-Trichloroethane | 5.0 | Not Detected | 27 | Not Detected |
| Cyclohexane | 5.0 | Not Detected | 17 | Not Detected |
| Carbon Tetrachloride | 5.0 | Not Detected | 31 | Not Detected |
| 2,2,4-Trimethylpentane | 5.0 | Not Detected | 23 | Not Detected |
| Benzene | 5.0 | Not Detected | 16 | Not Detected |
| 1,2-Dichloroethane | 5.0 | Not Detected | 20 | Not Detected |
| Heptane | 5.0 | Not Detected | 20 | Not Detected |
| Trichloroethene | 5.0 | Not Detected | 27 | Not Detected |
| 1,2-Dichloropropane | 5.0 | Not Detected | 23 | Not Detected |
| 1,4-Dioxane | 20 | Not Detected | 72 | Not Detected |
| Bromodichloromethane | 5.0 | Not Detected | 34 | Not Detected |
| cis-1,3-Dichloropropene | 5.0 | Not Detected | 23 | Not Detected |
| 4-Methyl-2-pentanone | 20 | Not Detected | 82 | Not Detected |
| Toluene | 5.0 | Not Detected | 19 | Not Detected |
| trans-1,3-Dichloropropene | 5.0 | Not Detected | 23 | Not Detected |
| 1,1,2-Trichloroethane | 5.0 | Not Detected | 27 | Not Detected |
| Tetrachloroethene | 5.0 | Not Detected | 34 | Not Detected |
| 2-Hexanone | 20 | Not Detected | 82 | Not Detected |

eurofins | Air Toxics

**Client Sample ID: Lab Blank**
**Lab ID#: 1302278A-11A**
**EPA METHOD TO-15 GC/MS**

| | | | |
|---|---|---|---|
| **File Name:** | **14021905a** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 2/19/13 09:49 AM** | |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Dibromochloromethane | 5.0 | Not Detected | 42 | Not Detected |
| 1,2-Dibromoethane (EDB) | 5.0 | Not Detected | 38 | Not Detected |
| Chlorobenzene | 5.0 | Not Detected | 23 | Not Detected |
| Ethyl Benzene | 5.0 | Not Detected | 22 | Not Detected |
| m,p-Xylene | 5.0 | Not Detected | 22 | Not Detected |
| o-Xylene | 5.0 | Not Detected | 22 | Not Detected |
| Styrene | 5.0 | Not Detected | 21 | Not Detected |
| Bromoform | 5.0 | Not Detected | 52 | Not Detected |
| Cumene | 5.0 | Not Detected | 24 | Not Detected |
| 1,1,2,2-Tetrachloroethane | 5.0 | Not Detected | 34 | Not Detected |
| Propylbenzene | 5.0 | Not Detected | 24 | Not Detected |
| 4-Ethyltoluene | 5.0 | Not Detected | 24 | Not Detected |
| 1,3,5-Trimethylbenzene | 5.0 | Not Detected | 24 | Not Detected |
| 1,2,4-Trimethylbenzene | 5.0 | Not Detected | 24 | Not Detected |
| 1,3-Dichlorobenzene | 5.0 | Not Detected | 30 | Not Detected |
| 1,4-Dichlorobenzene | 5.0 | Not Detected | 30 | Not Detected |
| alpha-Chlorotoluene | 5.0 | Not Detected | 26 | Not Detected |
| 1,2-Dichlorobenzene | 5.0 | Not Detected | 30 | Not Detected |
| 1,2,4-Trichlorobenzene | 20 | Not Detected | 150 | Not Detected |
| Hexachlorobutadiene | 20 | Not Detected | 210 | Not Detected |
| Butane | 20 | Not Detected | 48 | Not Detected |
| Isopentane | 20 | Not Detected | 59 | Not Detected |

J = Estimated value.

**Container Type: NA - Not Applicable**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| 1,2-Dichloroethane-d4 | 104 | 70-130 |
| Toluene-d8 | 98 | 70-130 |
| 4-Bromofluorobenzene | 99 | 70-130 |

eurofins | Air Toxics

**Client Sample ID: Lab Blank**

**Lab ID#: 1302278A-11B**

**EPA METHOD TO-15 GC/MS**

| | | | |
|---|---|---|---|
| **File Name:** | **14021930a** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 2/19/13 09:28 PM** | |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 5.0 | Not Detected | 25 | Not Detected |
| Freon 114 | 5.0 | Not Detected | 35 | Not Detected |
| Chloromethane | 20 | Not Detected | 41 | Not Detected |
| Vinyl Chloride | 5.0 | Not Detected | 13 | Not Detected |
| 1,3-Butadiene | 5.0 | Not Detected | 11 | Not Detected |
| Bromomethane | 5.0 | Not Detected | 19 | Not Detected |
| Chloroethane | 20 | Not Detected | 53 | Not Detected |
| Freon 11 | 5.0 | Not Detected | 28 | Not Detected |
| Ethanol | 20 | Not Detected | 38 | Not Detected |
| Freon 113 | 5.0 | Not Detected | 38 | Not Detected |
| 1,1-Dichloroethene | 5.0 | Not Detected | 20 | Not Detected |
| Acetone | 20 | Not Detected | 48 | Not Detected |
| 2-Propanol | 20 | Not Detected | 49 | Not Detected |
| Carbon Disulfide | 5.0 | Not Detected | 16 | Not Detected |
| 3-Chloropropene | 20 | Not Detected | 63 | Not Detected |
| Methylene Chloride | 5.0 | 2.0 J | 17 | 7.1 J |
| Methyl tert-butyl ether | 5.0 | Not Detected | 18 | Not Detected |
| trans-1,2-Dichloroethene | 5.0 | Not Detected | 20 | Not Detected |
| Hexane | 5.0 | Not Detected | 18 | Not Detected |
| 1,1-Dichloroethane | 5.0 | Not Detected | 20 | Not Detected |
| 2-Butanone (Methyl Ethyl Ketone) | 20 | Not Detected | 59 | Not Detected |
| cis-1,2-Dichloroethene | 5.0 | Not Detected | 20 | Not Detected |
| Tetrahydrofuran | 5.0 | Not Detected | 15 | Not Detected |
| Chloroform | 5.0 | Not Detected | 24 | Not Detected |
| 1,1,1-Trichloroethane | 5.0 | Not Detected | 27 | Not Detected |
| Cyclohexane | 5.0 | Not Detected | 17 | Not Detected |
| Carbon Tetrachloride | 5.0 | Not Detected | 31 | Not Detected |
| 2,2,4-Trimethylpentane | 5.0 | Not Detected | 23 | Not Detected |
| Benzene | 5.0 | Not Detected | 16 | Not Detected |
| 1,2-Dichloroethane | 5.0 | Not Detected | 20 | Not Detected |
| Heptane | 5.0 | Not Detected | 20 | Not Detected |
| Trichloroethene | 5.0 | Not Detected | 27 | Not Detected |
| 1,2-Dichloropropane | 5.0 | Not Detected | 23 | Not Detected |
| 1,4-Dioxane | 20 | Not Detected | 72 | Not Detected |
| Bromodichloromethane | 5.0 | Not Detected | 34 | Not Detected |
| cis-1,3-Dichloropropene | 5.0 | Not Detected | 23 | Not Detected |
| 4-Methyl-2-pentanone | 20 | Not Detected | 82 | Not Detected |
| Toluene | 5.0 | Not Detected | 19 | Not Detected |
| trans-1,3-Dichloropropene | 5.0 | Not Detected | 23 | Not Detected |
| 1,1,2-Trichloroethane | 5.0 | Not Detected | 27 | Not Detected |
| Tetrachloroethene | 5.0 | Not Detected | 34 | Not Detected |
| 2-Hexanone | 20 | Not Detected | 82 | Not Detected |

eurofins | Air Toxics

**Client Sample ID: Lab Blank**

**Lab ID#: 1302278A-11B**

**EPA METHOD TO-15 GC/MS**

| | | | |
|---|---|---|---|
| **File Name:** | **14021930a** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 2/19/13 09:28 PM** | |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Dibromochloromethane | 5.0 | Not Detected | 42 | Not Detected |
| 1,2-Dibromoethane (EDB) | 5.0 | Not Detected | 38 | Not Detected |
| Chlorobenzene | 5.0 | Not Detected | 23 | Not Detected |
| Ethyl Benzene | 5.0 | Not Detected | 22 | Not Detected |
| m,p-Xylene | 5.0 | Not Detected | 22 | Not Detected |
| o-Xylene | 5.0 | Not Detected | 22 | Not Detected |
| Styrene | 5.0 | Not Detected | 21 | Not Detected |
| Bromoform | 5.0 | Not Detected | 52 | Not Detected |
| Cumene | 5.0 | Not Detected | 24 | Not Detected |
| 1,1,2,2-Tetrachloroethane | 5.0 | Not Detected | 34 | Not Detected |
| Propylbenzene | 5.0 | Not Detected | 24 | Not Detected |
| 4-Ethyltoluene | 5.0 | Not Detected | 24 | Not Detected |
| 1,3,5-Trimethylbenzene | 5.0 | Not Detected | 24 | Not Detected |
| 1,2,4-Trimethylbenzene | 5.0 | Not Detected | 24 | Not Detected |
| 1,3-Dichlorobenzene | 5.0 | Not Detected | 30 | Not Detected |
| 1,4-Dichlorobenzene | 5.0 | Not Detected | 30 | Not Detected |
| alpha-Chlorotoluene | 5.0 | Not Detected | 26 | Not Detected |
| 1,2-Dichlorobenzene | 5.0 | Not Detected | 30 | Not Detected |
| 1,2,4-Trichlorobenzene | 20 | Not Detected | 150 | Not Detected |
| Hexachlorobutadiene | 20 | Not Detected | 210 | Not Detected |
| Butane | 20 | Not Detected | 48 | Not Detected |
| Isopentane | 20 | Not Detected | 59 | Not Detected |

J = Estimated value.

**Container Type: NA - Not Applicable**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| 1,2-Dichloroethane-d4 | 108 | 70-130 |
| Toluene-d8 | 98 | 70-130 |
| 4-Bromofluorobenzene | 100 | 70-130 |

eurofins | Air Toxics

**Client Sample ID: Lab Blank**

**Lab ID#: 1302278A-11C**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p022106a** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 2/21/13 11:45 AM** | |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 0.50 | Not Detected | 2.5 | Not Detected |
| Freon 114 | 0.50 | Not Detected | 3.5 | Not Detected |
| Chloromethane | 5.0 | Not Detected | 10 | Not Detected |
| Vinyl Chloride | 0.50 | Not Detected | 1.3 | Not Detected |
| 1,3-Butadiene | 0.50 | Not Detected | 1.1 | Not Detected |
| Bromomethane | 5.0 | Not Detected | 19 | Not Detected |
| Chloroethane | 2.0 | Not Detected | 5.3 | Not Detected |
| Freon 11 | 0.50 | Not Detected | 2.8 | Not Detected |
| Ethanol | 2.0 | Not Detected | 3.8 | Not Detected |
| Freon 113 | 0.50 | Not Detected | 3.8 | Not Detected |
| 1,1-Dichloroethene | 0.50 | Not Detected | 2.0 | Not Detected |
| Acetone | 5.0 | Not Detected | 12 | Not Detected |
| 2-Propanol | 2.0 | Not Detected | 4.9 | Not Detected |
| Carbon Disulfide | 2.0 | 0.36 J | 6.2 | 1.1 J |
| 3-Chloropropene | 2.0 | Not Detected | 6.3 | Not Detected |
| Methylene Chloride | 5.0 | 0.066 J | 17 | 0.23 J |
| Methyl tert-butyl ether | 0.50 | Not Detected | 1.8 | Not Detected |
| trans-1,2-Dichloroethene | 0.50 | Not Detected | 2.0 | Not Detected |
| Hexane | 0.50 | Not Detected | 1.8 | Not Detected |
| 1,1-Dichloroethane | 0.50 | Not Detected | 2.0 | Not Detected |
| 2-Butanone (Methyl Ethyl Ketone) | 2.0 | Not Detected | 5.9 | Not Detected |
| cis-1,2-Dichloroethene | 0.50 | Not Detected | 2.0 | Not Detected |
| Tetrahydrofuran | 0.50 | Not Detected | 1.5 | Not Detected |
| Chloroform | 0.50 | Not Detected | 2.4 | Not Detected |
| 1,1,1-Trichloroethane | 0.50 | Not Detected | 2.7 | Not Detected |
| Cyclohexane | 0.50 | Not Detected | 1.7 | Not Detected |
| Carbon Tetrachloride | 0.50 | Not Detected | 3.1 | Not Detected |
| 2,2,4-Trimethylpentane | 0.50 | 0.064 J | 2.3 | 0.30 J |
| Benzene | 0.50 | Not Detected | 1.6 | Not Detected |
| 1,2-Dichloroethane | 0.50 | Not Detected | 2.0 | Not Detected |
| Heptane | 0.50 | Not Detected | 2.0 | Not Detected |
| Trichloroethene | 0.50 | Not Detected | 2.7 | Not Detected |
| 1,2-Dichloropropane | 0.50 | Not Detected | 2.3 | Not Detected |
| 1,4-Dioxane | 2.0 | Not Detected | 7.2 | Not Detected |
| Bromodichloromethane | 0.50 | Not Detected | 3.4 | Not Detected |
| cis-1,3-Dichloropropene | 0.50 | Not Detected | 2.3 | Not Detected |
| 4-Methyl-2-pentanone | 0.50 | Not Detected | 2.0 | Not Detected |
| Toluene | 0.50 | 0.039 J | 1.9 | 0.14 J |
| trans-1,3-Dichloropropene | 0.50 | Not Detected | 2.3 | Not Detected |
| 1,1,2-Trichloroethane | 0.50 | Not Detected | 2.7 | Not Detected |
| Tetrachloroethene | 0.50 | Not Detected | 3.4 | Not Detected |
| 2-Hexanone | 2.0 | Not Detected | 8.2 | Not Detected |

eurofins | Air Toxics

**Client Sample ID: Lab Blank**

**Lab ID#: 1302278A-11C**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p022106a** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 2/21/13 11:45 AM** | |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Dibromochloromethane | 0.50 | Not Detected | 4.2 | Not Detected |
| 1,2-Dibromoethane (EDB) | 0.50 | Not Detected | 3.8 | Not Detected |
| Chlorobenzene | 0.50 | Not Detected | 2.3 | Not Detected |
| Ethyl Benzene | 0.50 | Not Detected | 2.2 | Not Detected |
| m,p-Xylene | 0.50 | Not Detected | 2.2 | Not Detected |
| o-Xylene | 0.50 | Not Detected | 2.2 | Not Detected |
| Styrene | 0.50 | Not Detected | 2.1 | Not Detected |
| Bromoform | 0.50 | Not Detected | 5.2 | Not Detected |
| Cumene | 0.50 | Not Detected | 2.4 | Not Detected |
| 1,1,2,2-Tetrachloroethane | 0.50 | Not Detected | 3.4 | Not Detected |
| Propylbenzene | 0.50 | 0.053 J | 2.4 | 0.26 J |
| 4-Ethyltoluene | 0.50 | 0.043 J | 2.4 | 0.21 J |
| 1,3,5-Trimethylbenzene | 0.50 | Not Detected | 2.4 | Not Detected |
| 1,2,4-Trimethylbenzene | 0.50 | Not Detected | 2.4 | Not Detected |
| 1,3-Dichlorobenzene | 0.50 | 0.13 J | 3.0 | 0.79 J |
| 1,4-Dichlorobenzene | 0.50 | 0.15 J | 3.0 | 0.92 J |
| alpha-Chlorotoluene | 0.50 | Not Detected | 2.6 | Not Detected |
| 1,2-Dichlorobenzene | 0.50 | 0.10 J | 3.0 | 0.62 J |
| 1,2,4-Trichlorobenzene | 2.0 | 0.48 J | 15 | 3.6 J |
| Hexachlorobutadiene | 2.0 | 0.20 J | 21 | 2.2 J |
| Butane | 2.0 | Not Detected | 4.8 | Not Detected |
| Isopentane | 2.0 | Not Detected | 5.9 | Not Detected |

J = Estimated value.

**Container Type: NA - Not Applicable**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| Toluene-d8 | 100 | 70-130 |
| 1,2-Dichloroethane-d4 | 96 | 70-130 |
| 4-Bromofluorobenzene | 91 | 70-130 |

eurofins | Air Toxics

**Client Sample ID: CCV**
**Lab ID#: 1302278A-12A**
**EPA METHOD TO-15 GC/MS**

| | | | |
|---|---|---|---|
| **File Name:** | **14021902** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 2/19/13 08:31 AM** | |

| Compound | %Recovery |
|---|---|
| Freon 12 | 102 |
| Freon 114 | 99 |
| Chloromethane | 108 |
| Vinyl Chloride | 93 |
| 1,3-Butadiene | 90 |
| Bromomethane | 80 |
| Chloroethane | 91 |
| Freon 11 | 104 |
| Ethanol | 108 |
| Freon 113 | 93 |
| 1,1-Dichloroethene | 102 |
| Acetone | 106 |
| 2-Propanol | 106 |
| Carbon Disulfide | 90 |
| 3-Chloropropene | 92 |
| Methylene Chloride | 90 |
| Methyl tert-butyl ether | 99 |
| trans-1,2-Dichloroethene | 101 |
| Hexane | 99 |
| 1,1-Dichloroethane | 97 |
| 2-Butanone (Methyl Ethyl Ketone) | 100 |
| cis-1,2-Dichloroethene | 96 |
| Tetrahydrofuran | 125 |
| Chloroform | 100 |
| 1,1,1-Trichloroethane | 100 |
| Cyclohexane | 97 |
| Carbon Tetrachloride | 101 |
| 2,2,4-Trimethylpentane | 101 |
| Benzene | 95 |
| 1,2-Dichloroethane | 104 |
| Heptane | 104 |
| Trichloroethene | 99 |
| 1,2-Dichloropropane | 97 |
| 1,4-Dioxane | 104 |
| Bromodichloromethane | 101 |
| cis-1,3-Dichloropropene | 97 |
| 4-Methyl-2-pentanone | 101 |
| Toluene | 95 |
| trans-1,3-Dichloropropene | 102 |
| 1,1,2-Trichloroethane | 100 |
| Tetrachloroethene | 101 |
| 2-Hexanone | 110 |

eurofins | Air Toxics

**Client Sample ID: CCV**

**Lab ID#: 1302278A-12A**

**EPA METHOD TO-15 GC/MS**

| | | | |
|---|---|---|---|
| **File Name:** | **14021902** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 2/19/13 08:31 AM** | |

| Compound | %Recovery |
|---|---|
| Dibromochloromethane | 106 |
| 1,2-Dibromoethane (EDB) | 105 |
| Chlorobenzene | 98 |
| Ethyl Benzene | 102 |
| m,p-Xylene | 103 |
| o-Xylene | 103 |
| Styrene | 106 |
| Bromoform | 112 |
| Cumene | 105 |
| 1,1,2,2-Tetrachloroethane | 103 |
| Propylbenzene | 106 |
| 4-Ethyltoluene | 112 |
| 1,3,5-Trimethylbenzene | 109 |
| 1,2,4-Trimethylbenzene | 105 |
| 1,3-Dichlorobenzene | 100 |
| 1,4-Dichlorobenzene | 103 |
| alpha-Chlorotoluene | 122 |
| 1,2-Dichlorobenzene | 102 |
| 1,2,4-Trichlorobenzene | 98 |
| Hexachlorobutadiene | 95 |
| Butane | 96 |
| Isopentane | 96 |

**Container Type: NA - Not Applicable**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| 1,2-Dichloroethane-d4 | 103 | 70-130 |
| Toluene-d8 | 101 | 70-130 |
| 4-Bromofluorobenzene | 102 | 70-130 |

eurofins | Air Toxics

**Client Sample ID: CCV**
**Lab ID#: 1302278A-12B**
**EPA METHOD TO-15 GC/MS**

| | | | |
|---|---|---|---|
| **File Name:** | **14021927** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 2/19/13 08:13 PM** | |

| Compound | %Recovery |
|---|---|
| Freon 12 | 106 |
| Freon 114 | 102 |
| Chloromethane | 104 |
| Vinyl Chloride | 96 |
| 1,3-Butadiene | 93 |
| Bromomethane | 100 |
| Chloroethane | 96 |
| Freon 11 | 108 |
| Ethanol | 110 |
| Freon 113 | 95 |
| 1,1-Dichloroethene | 105 |
| Acetone | 106 |
| 2-Propanol | 103 |
| Carbon Disulfide | 89 |
| 3-Chloropropene | 91 |
| Methylene Chloride | 92 |
| Methyl tert-butyl ether | 99 |
| trans-1,2-Dichloroethene | 102 |
| Hexane | 102 |
| 1,1-Dichloroethane | 99 |
| 2-Butanone (Methyl Ethyl Ketone) | 97 |
| cis-1,2-Dichloroethene | 99 |
| Tetrahydrofuran | 105 |
| Chloroform | 104 |
| 1,1,1-Trichloroethane | 102 |
| Cyclohexane | 100 |
| Carbon Tetrachloride | 106 |
| 2,2,4-Trimethylpentane | 103 |
| Benzene | 95 |
| 1,2-Dichloroethane | 106 |
| Heptane | 103 |
| Trichloroethene | 96 |
| 1,2-Dichloropropane | 97 |
| 1,4-Dioxane | 101 |
| Bromodichloromethane | 101 |
| cis-1,3-Dichloropropene | 93 |
| 4-Methyl-2-pentanone | 96 |
| Toluene | 96 |
| trans-1,3-Dichloropropene | 96 |
| 1,1,2-Trichloroethane | 96 |
| Tetrachloroethene | 100 |
| 2-Hexanone | 102 |

eurofins | Air Toxics

**Client Sample ID: CCV**
**Lab ID#: 1302278A-12B**
**EPA METHOD TO-15 GC/MS**

| | | | |
|---|---|---|---|
| **File Name:** | **14021927** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 2/19/13 08:13 PM** | |

| Compound | %Recovery |
|---|---|
| Dibromochloromethane | 103 |
| 1,2-Dibromoethane (EDB) | 101 |
| Chlorobenzene | 96 |
| Ethyl Benzene | 98 |
| m,p-Xylene | 101 |
| o-Xylene | 99 |
| Styrene | 102 |
| Bromoform | 104 |
| Cumene | 102 |
| 1,1,2,2-Tetrachloroethane | 99 |
| Propylbenzene | 100 |
| 4-Ethyltoluene | 104 |
| 1,3,5-Trimethylbenzene | 104 |
| 1,2,4-Trimethylbenzene | 100 |
| 1,3-Dichlorobenzene | 93 |
| 1,4-Dichlorobenzene | 96 |
| alpha-Chlorotoluene | 105 |
| 1,2-Dichlorobenzene | 92 |
| 1,2,4-Trichlorobenzene | 87 |
| Hexachlorobutadiene | 87 |
| Butane | 97 |
| Isopentane | 101 |

**Container Type: NA - Not Applicable**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| 1,2-Dichloroethane-d4 | 108 | 70-130 |
| Toluene-d8 | 102 | 70-130 |
| 4-Bromofluorobenzene | 101 | 70-130 |

eurofins | Air Toxics

**Client Sample ID: CCV**

**Lab ID#: 1302278A-12C**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p022102** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 2/21/13 09:30 AM** | |

| Compound | %Recovery |
|---|---|
| Freon 12 | 104 |
| Freon 114 | 106 |
| Chloromethane | 100 |
| Vinyl Chloride | 107 |
| 1,3-Butadiene | 104 |
| Bromomethane | 104 |
| Chloroethane | 104 |
| Freon 11 | 105 |
| Ethanol | 104 |
| Freon 113 | 106 |
| 1,1-Dichloroethene | 106 |
| Acetone | 108 |
| 2-Propanol | 104 |
| Carbon Disulfide | 103 |
| 3-Chloropropene | 110 |
| Methylene Chloride | 104 |
| Methyl tert-butyl ether | 116 |
| trans-1,2-Dichloroethene | 110 |
| Hexane | 110 |
| 1,1-Dichloroethane | 106 |
| 2-Butanone (Methyl Ethyl Ketone) | 103 |
| cis-1,2-Dichloroethene | 113 |
| Tetrahydrofuran | 112 |
| Chloroform | 105 |
| 1,1,1-Trichloroethane | 107 |
| Cyclohexane | 118 |
| Carbon Tetrachloride | 106 |
| 2,2,4-Trimethylpentane | 114 |
| Benzene | 107 |
| 1,2-Dichloroethane | 105 |
| Heptane | 120 |
| Trichloroethene | 88 |
| 1,2-Dichloropropane | 107 |
| 1,4-Dioxane | 114 |
| Bromodichloromethane | 104 |
| cis-1,3-Dichloropropene | 107 |
| 4-Methyl-2-pentanone | 119 |
| Toluene | 105 |
| trans-1,3-Dichloropropene | 115 |
| 1,1,2-Trichloroethane | 108 |
| Tetrachloroethene | 106 |
| 2-Hexanone | 115 |

eurofins | Air Toxics

**Client Sample ID: CCV**

**Lab ID#: 1302278A-12C**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p022102** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 2/21/13 09:30 AM** | |

| Compound | %Recovery |
|---|---|
| Dibromochloromethane | 113 |
| 1,2-Dibromoethane (EDB) | 109 |
| Chlorobenzene | 101 |
| Ethyl Benzene | 115 |
| m,p-Xylene | 117 |
| o-Xylene | 119 |
| Styrene | 125 |
| Bromoform | 112 |
| Cumene | 122 |
| 1,1,2,2-Tetrachloroethane | 119 |
| Propylbenzene | 116 |
| 4-Ethyltoluene | 121 |
| 1,3,5-Trimethylbenzene | 123 |
| 1,2,4-Trimethylbenzene | 121 |
| 1,3-Dichlorobenzene | 110 |
| 1,4-Dichlorobenzene | 109 |
| alpha-Chlorotoluene | 118 |
| 1,2-Dichlorobenzene | 112 |
| 1,2,4-Trichlorobenzene | 105 |
| Hexachlorobutadiene | 106 |
| Butane | 100 |
| Isopentane | 108 |

**Container Type: NA - Not Applicable**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| Toluene-d8 | 104 | 70-130 |
| 1,2-Dichloroethane-d4 | 103 | 70-130 |
| 4-Bromofluorobenzene | 99 | 70-130 |

eurofins | Air Toxics

**Client Sample ID: LCS**
**Lab ID#: 1302278A-13A**
**EPA METHOD TO-15 GC/MS**

| | | | |
|---|---|---|---|
| **File Name:** | **14021903** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 2/19/13 08:56 AM** | |

| Compound | %Recovery |
|---|---|
| Freon 12 | 89 |
| Freon 114 | 88 |
| Chloromethane | 91 |
| Vinyl Chloride | 82 |
| 1,3-Butadiene | 80 |
| Bromomethane | 80 |
| Chloroethane | 74 |
| Freon 11 | 90 |
| Ethanol | 92 |
| Freon 113 | 79 |
| 1,1-Dichloroethene | 100 |
| Acetone | 95 |
| 2-Propanol | 81 |
| Carbon Disulfide | 95 |
| 3-Chloropropene | 85 |
| Methylene Chloride | 79 |
| Methyl tert-butyl ether | 85 |
| trans-1,2-Dichloroethene | 100 |
| Hexane | 82 |
| 1,1-Dichloroethane | 84 |
| 2-Butanone (Methyl Ethyl Ketone) | 81 |
| cis-1,2-Dichloroethene | 85 |
| Tetrahydrofuran | 81 |
| Chloroform | 90 |
| 1,1,1-Trichloroethane | 88 |
| Cyclohexane | 82 |
| Carbon Tetrachloride | 89 |
| 2,2,4-Trimethylpentane | 83 |
| Benzene | 82 |
| 1,2-Dichloroethane | 88 |
| Heptane | 88 |
| Trichloroethene | 85 |
| 1,2-Dichloropropane | 82 |
| 1,4-Dioxane | 77 |
| Bromodichloromethane | 84 |
| cis-1,3-Dichloropropene | 78 |
| 4-Methyl-2-pentanone | 73 |
| Toluene | 82 |
| trans-1,3-Dichloropropene | 81 |
| 1,1,2-Trichloroethane | 85 |
| Tetrachloroethene | 87 |
| 2-Hexanone | 69 Q |

eurofins | Air Toxics

**Client Sample ID: LCS**
**Lab ID#: 1302278A-13A**
**EPA METHOD TO-15 GC/MS**

| | | | |
|---|---|---|---|
| **File Name:** | **14021903** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 2/19/13 08:56 AM** | |

| Compound | %Recovery |
|---|---|
| Dibromochloromethane | 82 |
| 1,2-Dibromoethane (EDB) | 86 |
| Chlorobenzene | 86 |
| Ethyl Benzene | 88 |
| m,p-Xylene | 85 |
| o-Xylene | 84 |
| Styrene | 78 |
| Bromoform | 85 |
| Cumene | 89 |
| 1,1,2,2-Tetrachloroethane | 92 |
| Propylbenzene | 92 |
| 4-Ethyltoluene | 88 |
| 1,3,5-Trimethylbenzene | 92 |
| 1,2,4-Trimethylbenzene | 85 |
| 1,3-Dichlorobenzene | 92 |
| 1,4-Dichlorobenzene | 91 |
| alpha-Chlorotoluene | 93 |
| 1,2-Dichlorobenzene | 92 |
| 1,2,4-Trichlorobenzene | 94 |
| Hexachlorobutadiene | 101 |
| Butane | 81 |
| Isopentane | 86 |

Q = Exceeds Quality Control limits.
**Container Type: NA - Not Applicable**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| 1,2-Dichloroethane-d4 | 104 | 70-130 |
| Toluene-d8 | 100 | 70-130 |
| 4-Bromofluorobenzene | 103 | 70-130 |

eurofins | Air Toxics

**Client Sample ID: LCSD**
**Lab ID#: 1302278A-13AA**
**EPA METHOD TO-15 GC/MS**

| | | | |
|---|---|---|---|
| **File Name:** | **14021904** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 2/19/13 09:15 AM** | |

| Compound | %Recovery |
|---|---|
| Freon 12 | 92 |
| Freon 114 | 90 |
| Chloromethane | 94 |
| Vinyl Chloride | 84 |
| 1,3-Butadiene | 80 |
| Bromomethane | 82 |
| Chloroethane | 75 |
| Freon 11 | 93 |
| Ethanol | 89 |
| Freon 113 | 87 |
| 1,1-Dichloroethene | 98 |
| Acetone | 100 |
| 2-Propanol | 82 |
| Carbon Disulfide | 95 |
| 3-Chloropropene | 86 |
| Methylene Chloride | 80 |
| Methyl tert-butyl ether | 86 |
| trans-1,2-Dichloroethene | 99 |
| Hexane | 82 |
| 1,1-Dichloroethane | 83 |
| 2-Butanone (Methyl Ethyl Ketone) | 83 |
| cis-1,2-Dichloroethene | 84 |
| Tetrahydrofuran | 81 |
| Chloroform | 91 |
| 1,1,1-Trichloroethane | 89 |
| Cyclohexane | 84 |
| Carbon Tetrachloride | 88 |
| 2,2,4-Trimethylpentane | 84 |
| Benzene | 80 |
| 1,2-Dichloroethane | 88 |
| Heptane | 87 |
| Trichloroethene | 82 |
| 1,2-Dichloropropane | 83 |
| 1,4-Dioxane | 81 |
| Bromodichloromethane | 82 |
| cis-1,3-Dichloropropene | 79 |
| 4-Methyl-2-pentanone | 75 |
| Toluene | 82 |
| trans-1,3-Dichloropropene | 81 |
| 1,1,2-Trichloroethane | 84 |
| Tetrachloroethene | 84 |
| 2-Hexanone | 67 Q |

eurofins | Air Toxics

**Client Sample ID: LCSD**
**Lab ID#: 1302278A-13AA**
**EPA METHOD TO-15 GC/MS**

| | | | |
|---|---|---|---|
| **File Name:** | **14021904** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 2/19/13 09:15 AM** | |

| Compound | %Recovery |
|---|---|
| Dibromochloromethane | 84 |
| 1,2-Dibromoethane (EDB) | 88 |
| Chlorobenzene | 85 |
| Ethyl Benzene | 81 |
| m,p-Xylene | 84 |
| o-Xylene | 82 |
| Styrene | 75 |
| Bromoform | 82 |
| Cumene | 87 |
| 1,1,2,2-Tetrachloroethane | 89 |
| Propylbenzene | 89 |
| 4-Ethyltoluene | 87 |
| 1,3,5-Trimethylbenzene | 90 |
| 1,2,4-Trimethylbenzene | 81 |
| 1,3-Dichlorobenzene | 88 |
| 1,4-Dichlorobenzene | 87 |
| alpha-Chlorotoluene | 88 |
| 1,2-Dichlorobenzene | 87 |
| 1,2,4-Trichlorobenzene | 100 |
| Hexachlorobutadiene | 95 |
| Butane | 80 |
| Isopentane | 86 |

Q = Exceeds Quality Control limits.
**Container Type: NA - Not Applicable**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| 1,2-Dichloroethane-d4 | 105 | 70-130 |
| Toluene-d8 | 100 | 70-130 |
| 4-Bromofluorobenzene | 102 | 70-130 |

eurofins | Air Toxics

**Client Sample ID: LCS**
**Lab ID#: 1302278A-13B**
**EPA METHOD TO-15 GC/MS**

| | | | |
|---|---|---|---|
| **File Name:** | **14021928** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 2/19/13 08:35 PM** | |

| Compound | %Recovery |
|---|---|
| Freon 12 | 91 |
| Freon 114 | 87 |
| Chloromethane | 91 |
| Vinyl Chloride | 79 |
| 1,3-Butadiene | 78 |
| Bromomethane | 83 |
| Chloroethane | 73 |
| Freon 11 | 90 |
| Ethanol | 86 |
| Freon 113 | 82 |
| 1,1-Dichloroethene | 97 |
| Acetone | 90 |
| 2-Propanol | 81 |
| Carbon Disulfide | 93 |
| 3-Chloropropene | 84 |
| Methylene Chloride | 80 |
| Methyl tert-butyl ether | 81 |
| trans-1,2-Dichloroethene | 96 |
| Hexane | 81 |
| 1,1-Dichloroethane | 83 |
| 2-Butanone (Methyl Ethyl Ketone) | 78 |
| cis-1,2-Dichloroethene | 81 |
| Tetrahydrofuran | 80 |
| Chloroform | 88 |
| 1,1,1-Trichloroethane | 85 |
| Cyclohexane | 83 |
| Carbon Tetrachloride | 88 |
| 2,2,4-Trimethylpentane | 83 |
| Benzene | 80 |
| 1,2-Dichloroethane | 90 |
| Heptane | 84 |
| Trichloroethene | 86 |
| 1,2-Dichloropropane | 82 |
| 1,4-Dioxane | 73 |
| Bromodichloromethane | 84 |
| cis-1,3-Dichloropropene | 74 |
| 4-Methyl-2-pentanone | 68 Q |
| Toluene | 80 |
| trans-1,3-Dichloropropene | 76 |
| 1,1,2-Trichloroethane | 83 |
| Tetrachloroethene | 84 |
| 2-Hexanone | 66 Q |

eurofins | Air Toxics

**Client Sample ID: LCS**
**Lab ID#: 1302278A-13B**
**EPA METHOD TO-15 GC/MS**

| | | | |
|---|---|---|---|
| **File Name:** | **14021928** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 2/19/13 08:35 PM** | |

| Compound | %Recovery |
|---|---|
| Dibromochloromethane | 81 |
| 1,2-Dibromoethane (EDB) | 85 |
| Chlorobenzene | 84 |
| Ethyl Benzene | 80 |
| m,p-Xylene | 81 |
| o-Xylene | 80 |
| Styrene | 75 |
| Bromoform | 80 |
| Cumene | 83 |
| 1,1,2,2-Tetrachloroethane | 83 |
| Propylbenzene | 84 |
| 4-Ethyltoluene | 81 |
| 1,3,5-Trimethylbenzene | 83 |
| 1,2,4-Trimethylbenzene | 74 |
| 1,3-Dichlorobenzene | 83 |
| 1,4-Dichlorobenzene | 82 |
| alpha-Chlorotoluene | 78 |
| 1,2-Dichlorobenzene | 81 |
| 1,2,4-Trichlorobenzene | 78 |
| Hexachlorobutadiene | 84 |
| Butane | 80 |
| Isopentane | 85 |

Q = Exceeds Quality Control limits.

**Container Type: NA - Not Applicable**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| 1,2-Dichloroethane-d4 | 106 | 70-130 |
| Toluene-d8 | 100 | 70-130 |
| 4-Bromofluorobenzene | 103 | 70-130 |

eurofins | Air Toxics

**Client Sample ID: LCSD**
**Lab ID#: 1302278A-13BB**
**EPA METHOD TO-15 GC/MS**

| | | | |
|---|---|---|---|
| **File Name:** | **14021929** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 2/19/13 09:00 PM** | |

| Compound | %Recovery |
|---|---|
| Freon 12 | 92 |
| Freon 114 | 85 |
| Chloromethane | 91 |
| Vinyl Chloride | 81 |
| 1,3-Butadiene | 79 |
| Bromomethane | 85 |
| Chloroethane | 71 |
| Freon 11 | 91 |
| Ethanol | 83 |
| Freon 113 | 81 |
| 1,1-Dichloroethene | 98 |
| Acetone | 88 |
| 2-Propanol | 79 |
| Carbon Disulfide | 92 |
| 3-Chloropropene | 83 |
| Methylene Chloride | 78 |
| Methyl tert-butyl ether | 80 |
| trans-1,2-Dichloroethene | 95 |
| Hexane | 79 |
| 1,1-Dichloroethane | 82 |
| 2-Butanone (Methyl Ethyl Ketone) | 80 |
| cis-1,2-Dichloroethene | 81 |
| Tetrahydrofuran | 78 |
| Chloroform | 87 |
| 1,1,1-Trichloroethane | 84 |
| Cyclohexane | 81 |
| Carbon Tetrachloride | 88 |
| 2,2,4-Trimethylpentane | 81 |
| Benzene | 80 |
| 1,2-Dichloroethane | 89 |
| Heptane | 81 |
| Trichloroethene | 82 |
| 1,2-Dichloropropane | 80 |
| 1,4-Dioxane | 71 |
| Bromodichloromethane | 81 |
| cis-1,3-Dichloropropene | 73 |
| 4-Methyl-2-pentanone | 68 Q |
| Toluene | 80 |
| trans-1,3-Dichloropropene | 74 |
| 1,1,2-Trichloroethane | 83 |
| Tetrachloroethene | 84 |
| 2-Hexanone | 61 Q |

eurofins | Air Toxics

**Client Sample ID: LCSD**
**Lab ID#: 1302278A-13BB**
**EPA METHOD TO-15 GC/MS**

| | | | |
|---|---|---|---|
| **File Name:** | **14021929** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 2/19/13 09:00 PM** | |

| Compound | %Recovery |
|---|---|
| Dibromochloromethane | 83 |
| 1,2-Dibromoethane (EDB) | 83 |
| Chlorobenzene | 82 |
| Ethyl Benzene | 79 |
| m,p-Xylene | 81 |
| o-Xylene | 80 |
| Styrene | 73 |
| Bromoform | 79 |
| Cumene | 83 |
| 1,1,2,2-Tetrachloroethane | 85 |
| Propylbenzene | 84 |
| 4-Ethyltoluene | 81 |
| 1,3,5-Trimethylbenzene | 84 |
| 1,2,4-Trimethylbenzene | 78 |
| 1,3-Dichlorobenzene | 81 |
| 1,4-Dichlorobenzene | 80 |
| alpha-Chlorotoluene | 76 |
| 1,2-Dichlorobenzene | 80 |
| 1,2,4-Trichlorobenzene | 83 |
| Hexachlorobutadiene | 81 |
| Butane | 81 |
| Isopentane | 84 |

Q = Exceeds Quality Control limits.
**Container Type: NA - Not Applicable**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| 1,2-Dichloroethane-d4 | 104 | 70-130 |
| Toluene-d8 | 100 | 70-130 |
| 4-Bromofluorobenzene | 102 | 70-130 |

eurofins | Air Toxics

**Client Sample ID: LCS**

**Lab ID#: 1302278A-13C**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p022103** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 2/21/13 10:03 AM** | |

| Compound | %Recovery |
|---|---|
| Freon 12 | 102 |
| Freon 114 | 102 |
| Chloromethane | 106 |
| Vinyl Chloride | 107 |
| 1,3-Butadiene | 104 |
| Bromomethane | 102 |
| Chloroethane | 104 |
| Freon 11 | 101 |
| Ethanol | 77 |
| Freon 113 | 104 |
| 1,1-Dichloroethene | 110 |
| Acetone | 106 |
| 2-Propanol | 102 |
| Carbon Disulfide | 124 |
| 3-Chloropropene | 121 |
| Methylene Chloride | 102 |
| Methyl tert-butyl ether | 110 |
| trans-1,2-Dichloroethene | 120 |
| Hexane | 108 |
| 1,1-Dichloroethane | 101 |
| 2-Butanone (Methyl Ethyl Ketone) | 102 |
| cis-1,2-Dichloroethene | 106 |
| Tetrahydrofuran | 106 |
| Chloroform | 102 |
| 1,1,1-Trichloroethane | 106 |
| Cyclohexane | 117 |
| Carbon Tetrachloride | 101 |
| 2,2,4-Trimethylpentane | 112 |
| Benzene | 106 |
| 1,2-Dichloroethane | 100 |
| Heptane | 113 |
| Trichloroethene | 88 |
| 1,2-Dichloropropane | 104 |
| 1,4-Dioxane | 110 |
| Bromodichloromethane | 101 |
| cis-1,3-Dichloropropene | 105 |
| 4-Methyl-2-pentanone | 116 |
| Toluene | 102 |
| trans-1,3-Dichloropropene | 109 |
| 1,1,2-Trichloroethane | 106 |
| Tetrachloroethene | 103 |
| 2-Hexanone | 107 |

eurofins | Air Toxics

**Client Sample ID: LCS**
**Lab ID#: 1302278A-13C**
**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p022103** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 2/21/13 10:03 AM** | |

| Compound | %Recovery |
|---|---|
| Dibromochloromethane | 107 |
| 1,2-Dibromoethane (EDB) | 106 |
| Chlorobenzene | 100 |
| Ethyl Benzene | 112 |
| m,p-Xylene | 116 |
| o-Xylene | 117 |
| Styrene | 119 |
| Bromoform | 105 |
| Cumene | 118 |
| 1,1,2,2-Tetrachloroethane | 117 |
| Propylbenzene | 113 |
| 4-Ethyltoluene | 114 |
| 1,3,5-Trimethylbenzene | 118 |
| 1,2,4-Trimethylbenzene | 116 |
| 1,3-Dichlorobenzene | 108 |
| 1,4-Dichlorobenzene | 107 |
| alpha-Chlorotoluene | 110 |
| 1,2-Dichlorobenzene | 112 |
| 1,2,4-Trichlorobenzene | 114 |
| Hexachlorobutadiene | 108 |
| Butane | 97 |
| Isopentane | 103 |

**Container Type: NA - Not Applicable**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| Toluene-d8 | 103 | 70-130 |
| 1,2-Dichloroethane-d4 | 98 | 70-130 |
| 4-Bromofluorobenzene | 97 | 70-130 |

eurofins | Air Toxics

**Client Sample ID: LCSD**

**Lab ID#: 1302278A-13CC**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p022104** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 2/21/13 10:33 AM** | |

| Compound | %Recovery |
|---|---|
| Freon 12 | 98 |
| Freon 114 | 100 |
| Chloromethane | 105 |
| Vinyl Chloride | 105 |
| 1,3-Butadiene | 104 |
| Bromomethane | 99 |
| Chloroethane | 102 |
| Freon 11 | 96 |
| Ethanol | 79 |
| Freon 113 | 100 |
| 1,1-Dichloroethene | 106 |
| Acetone | 108 |
| 2-Propanol | 100 |
| Carbon Disulfide | 120 |
| 3-Chloropropene | 122 |
| Methylene Chloride | 97 |
| Methyl tert-butyl ether | 109 |
| trans-1,2-Dichloroethene | 118 |
| Hexane | 105 |
| 1,1-Dichloroethane | 99 |
| 2-Butanone (Methyl Ethyl Ketone) | 99 |
| cis-1,2-Dichloroethene | 107 |
| Tetrahydrofuran | 104 |
| Chloroform | 99 |
| 1,1,1-Trichloroethane | 101 |
| Cyclohexane | 115 |
| Carbon Tetrachloride | 98 |
| 2,2,4-Trimethylpentane | 109 |
| Benzene | 106 |
| 1,2-Dichloroethane | 99 |
| Heptane | 113 |
| Trichloroethene | 88 |
| 1,2-Dichloropropane | 103 |
| 1,4-Dioxane | 111 |
| Bromodichloromethane | 100 |
| cis-1,3-Dichloropropene | 108 |
| 4-Methyl-2-pentanone | 114 |
| Toluene | 102 |
| trans-1,3-Dichloropropene | 111 |
| 1,1,2-Trichloroethane | 106 |
| Tetrachloroethene | 103 |
| 2-Hexanone | 107 |

eurofins | Air Toxics

**Client Sample ID: LCSD**

**Lab ID#: 1302278A-13CC**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p022104** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 2/21/13 10:33 AM** | |

| Compound | %Recovery |
|---|---|
| Dibromochloromethane | 105 |
| 1,2-Dibromoethane (EDB) | 105 |
| Chlorobenzene | 100 |
| Ethyl Benzene | 111 |
| m,p-Xylene | 118 |
| o-Xylene | 117 |
| Styrene | 119 |
| Bromoform | 104 |
| Cumene | 119 |
| 1,1,2,2-Tetrachloroethane | 118 |
| Propylbenzene | 113 |
| 4-Ethyltoluene | 110 |
| 1,3,5-Trimethylbenzene | 119 |
| 1,2,4-Trimethylbenzene | 115 |
| 1,3-Dichlorobenzene | 109 |
| 1,4-Dichlorobenzene | 106 |
| alpha-Chlorotoluene | 111 |
| 1,2-Dichlorobenzene | 110 |
| 1,2,4-Trichlorobenzene | 115 |
| Hexachlorobutadiene | 108 |
| Butane | 93 |
| Isopentane | 103 |

**Container Type: NA - Not Applicable**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| Toluene-d8 | 103 | 70-130 |
| 1,2-Dichloroethane-d4 | 95 | 70-130 |
| 4-Bromofluorobenzene | 98 | 70-130 |

# Shell Oil Products Chain Of Custody Record

1302278 URS

Air Toxics LTD.
Project Name: Roxana Soil Vapor
Project # 21562850.04001
Lab Vendor #

Please Check Appropriate Box:
☑ ENV. SERVICES ☐ MOTIVA RETAIL ☐ SHELL RETAIL
☐ MOTIVA SD&CH ☐ CONSULTANT ☐ LUBES
☐ SHELL PIPELINE ☐ OTHER

Print Bill To Contact Name: Robert Mooshegian
INCIDENT # (ENV SERVICES): 9 7 2 1 6 6 4 0 ☐ CHECK IF NO INCIDENT # APPLIES
DATE: 02/14/13
PO #:
SAP #: 3 4 0 0 6 1
PAGE: 1 of 1

LOG CODE:
SAMPLING COMPANY: URS CORPORATION
SITE ADDRESS: Street and City: 900 SOUTH CENTRAL AVE – ROXANA
State: IL
GLOBAL ID NO.:
ADDRESS: 1001 HIGHLANDS PLAZA DRIVE WEST - SUITE 300; ST. LOUIS, MO 63110
Laboratory Address: Air Toxics, LTD 180 Blue Ravine Road, Suite B, Folsom, CA 95630-4719
SEND REPORT TO/ATTN: Elizabeth Kunkel, URS, St. Louis
PHONE NO.: 314-743-4179
E-MAIL: Elizabeth.Kunkel@URSCorp.com
CONSULTANT PROJECT NAME #: Roxana Soil Vapor
TEL PHONE: 314-429-0100
FAX: 314-429-0462
Bill To Contact E-MAIL: Robert.Mooshegian@urs.com
COPY TO: L. Rathnow, B. Lehan, C. Kretzer, D. Mattingly, C. Williams

TURNAROUND TIME (CALENDAR DAYS):
☑ STANDARD (14 DAY) ☐ 5 DAYS ☐ 3 DAYS ☐ 2 DAYS ☐ 24 HOURS ☐ RESULTS NEEDED ON WEEKEND

REQUESTED ANALYSIS

☐ LA - RWQCB REPORT FORMAT ☑ UST AGENCY:
DELIVERABLES: ☐ LEVEL 1 ☐ LEVEL 2 ☐ LEVEL 3 ☑ LEVEL 4 ☐ OTHER (SPECIFY)

☑ SHELL CONTRACT RATE APPLIES
☐ STATE REIMBURSEMENT RATE APPLIES
☐ EDD NOT NEEDED
☑ RECEIPT VERIFICATION REQUESTED

Turn Around Time: ☑ Normal ☐ Rush ☐ Specify

Lab Use Only
Pressurized by:
Date:
Pressurization Gas: N2 He

| Lab Use Only | Field Sample Identification | SAMPLING DATE | SAMPLING TIME | Canister Number | Canister Pressure/Vacuum Initial | Final | Receipt | Final (psi) | Modified TO-15 + Butane & Isopentane | ASTM D-1946 + Helium | ASTM D-1946 | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| 01A | VMP-3-31.5-020713 | 02/07/13 | 1005-1035 | 14527 | -30 | -7.5 | | | X | X | | | | | | |
| 02A | VMP-3-39-021213 | 02/12/13 | 1029-1059 | 34169 | -30 | -7.5 | | | X | X | | | | | | |
| 03A | VMP-4-23.5-020713 | 02/07/13 | 1052-1122 | 3056 | -30 | -9 | | | X | X | | | | | | |
| 04A | VMP-4-39-020713 | 02/07/13 | 1313-1343 | 1363 | -29.5 | -8.5 | | | X | X | | | | | | |
| 05A | VMP-15-21.5-020713 | 02/07/13 | 1457-1527 | 36410 | -30 | -8.5 | | | X | X | | | | | | |
| 06A | VMP-15-25.5-021213 | 02/12/13 | 1419-1449 | 1358 | -30 | -8.5 | | | X | X | | | | | | |
| 07A | VMP-15-29-021213 | 02/12/13 | 1507-1537 | 34086 | -30 | -8.5 | | | X | X | | | | | | |
| 08A | VMP-31-20-021113 | 02/11/13 | 1133-1205 | 22963 | -30 | -9 | | | X | X | | | | | | |
| 09A | VMP-31-30-021113 | 02/11/13 | 1403-1433 | 38472 | -30 | -10.5 | | | X | X | | | | | | |
| 10A | VMP-32-30-020513 | 02/05/13 | 1111-1141 | 34135 | -30 | -8.5 | | | X | X | | | | | | |

ADDITIONAL NOTES:
- 14 day hold time
- Report results between MDL and RL
- Level IV ECVP

| | Received by: (Signature) | Date | Time |
|---|---|---|---|
| Relinquished by: (Signature) | FEDEX | 2/14/13 | 1730 |
| Relinquished by: (Signature) | 2/15/13 | 0945 | |
| Relinquished by: (Signature) | | | |

05/2008 Revision

Custody Seal Intact?
Y N None Temp N/A

eurofins | Air Toxics

3/1/2013
Ms. Elizabeth Kunkel
URS Corporation
1001 Highlands Plaza Dr. West
Suite 300
St. Louis MO 63110

Project Name: Roxana Soil Vapor
Project #: 21562850.04001
Workorder #: 1302278B

Dear Ms. Elizabeth Kunkel

The following report includes the data for the above referenced project for sample(s) received on 2/15/2013 at Air Toxics Ltd.

The data and associated QC analyzed by Modified ASTM D-1946 are compliant with the project requirements or laboratory criteria with the exception of the deviations noted in the attached case narrative.

Thank you for choosing Air Toxics Ltd. for your air analysis needs. Air Toxics Ltd. is committed to providing accurate data of the highest quality. Please feel free to contact the Project Manager: Kelly Buettner at 916-985-1000 if you have any questions regarding the data in this report.

Regards,

Kelly Buettner

Kelly Buettner
Project Manager

REVIEWED
ON
3/25/13

eurofins | Air Toxics

# WORK ORDER #: 1302278B

Work Order Summary

| | | | |
|---|---|---|---|
| **CLIENT:** | Ms. Elizabeth Kunkel<br>URS Corporation<br>1001 Highlands Plaza Dr. West<br>Suite 300<br>St. Louis, MO 63110 | **BILL TO:** | Accounts Payable Austin<br>URS Corporation<br>P.O. BOX 203970<br>Austin, TX 78720-1088 |
| **PHONE:** | 314-743-4179 | **P.O. #** | 21562735.00013 |
| **FAX:** | | **PROJECT #** | 21562850.04001 Roxana Soil Vapor |
| **DATE RECEIVED:** | 02/15/2013 | **CONTACT:** | Kelly Buettner |
| **DATE COMPLETED:** | 03/01/2013 | | |

| FRACTION # | NAME | TEST | RECEIPT VAC./PRES. | FINAL PRESSURE |
|---|---|---|---|---|
| 01A | VMP-3-31.5-020713 | Modified ASTM D-1946 | 6.5 "Hg | 15 psi |
| 02A | VMP-3-39-021213 | Modified ASTM D-1946 | 7.0 "Hg | 15 psi |
| 03A | VMP-4-23.5-020713 | Modified ASTM D-1946 | 7.0 "Hg | 15 psi |
| 04A | VMP-4-39-020713 | Modified ASTM D-1946 | 7.5 "Hg | 15 psi |
| 05A | VMP-15-21.5-020713 | Modified ASTM D-1946 | 8.0 "Hg | 15 psi |
| 06A | VMP-15-25.5-021213 | Modified ASTM D-1946 | 7.5 "Hg | 15 psi |
| 07A | VMP-15-29-021213 | Modified ASTM D-1946 | 7.5 "Hg | 15 psi |
| 08A | VMP-31-20-021113 | Modified ASTM D-1946 | 8.0 "Hg | 15 psi |
| 09A | VMP-31-30-021113 | Modified ASTM D-1946 | 8.5 "Hg | 15 psi |
| 10A | VMP-32-30-020513 | Modified ASTM D-1946 | 8.5 "Hg | 15 psi |
| 11A | Lab Blank | Modified ASTM D-1946 | NA | NA |
| 11B | Lab Blank | Modified ASTM D-1946 | NA | NA |
| 12A | LCS | Modified ASTM D-1946 | NA | NA |
| 12AA | LCSD | Modified ASTM D-1946 | NA | NA |

CERTIFIED BY: Heidi Hayes

Technical Director

DATE: 03/01/13

Certification numbers: AZ Licensure AZ0775, CA NELAP - 12282CA, NY NELAP - 11291,
TX NELAP - T104704434-12-4, UT NELAP CA009332012-3, WA NELAP - C935
Name of Accrediting Agency: NELAP/ORELAP (Oregon Environmental Laboratory Accreditation Program)
Accreditation number: CA300005, Effective date: 10/18/2012, Expiration date: 10/17/2013.
Eurofins Air Toxics Ltd. certifies that the test results contained in this report meet all requirements of the NELAC standards

This report shall not be reproduced, except in full, without the written approval of Eurofins Air Toxics, Inc.

180 BLUE RAVINE ROAD, SUITE B FOLSOM, CA - 9563
(916) 985-1000 . (800) 985-5955 . FAX (916) 985-1020

**LABORATORY NARRATIVE**
**Modified ASTM D-1946**
**URS Corporation**
**Workorder# 1302278B**

Ten 1 Liter Summa Canister samples were received on February 15, 2013. The laboratory performed analysis via Modified ASTM Method D-1946 for Methane and fixed gases in air using GC/FID or GC/TCD. The method involves direct injection of 1.0 mL of sample.

On the analytical column employed for this analysis, Oxygen coelutes with Argon. The corresponding peak is quantitated as Oxygen.

Since Nitrogen is used to pressurize samples, the reported Nitrogen values are calculated by adding all the sample components and subtracting from 100%.

Method modifications taken to run these samples are summarized in the table below. Specific project requirements may over-ride the ATL modifications.

| *Requirement* | *ASTM D-1946* | *ATL Modifications* |
|---|---|---|
| Calibration | A single point calibration is performed using a reference standard closely matching the composition of the unknown. | A 3-point calibration curve is performed. Quantitation is based on a daily calibration standard which may or may not resemble the composition of the associated samples. |
| Reference Standard | The composition of any reference standard must be known to within 0.01 mol % for any component. | The standards used by ATL are blended to a >/= 95% accuracy. |
| Sample Injection Volume | Components whose concentrations are in excess of 5 % should not be analyzed by using sample volumes greater than 0.5 mL. | The sample container is connected directly to a fixed volume sample loop of 1.0 mL on the GC. Linear range is defined by the calibration curve. Bags are loaded by vacuum. |
| Normalization | Normalize the mole percent values by multiplying each value by 100 and dividing by the sum of the original values. The sum of the original values should not differ from 100% by more than 1.0%. | Results are not normalized. The sum of the reported values can differ from 100% by as much as 15%, either due to analytical variability or an unusual sample matrix. |
| Precision | Precision requirements established at each concentration level. | Duplicates should agree within 25% RPD for detections > 5 X's the RL. |

**Receiving Notes**

The Chain of Custody (COC) information for sample VMP-31-20-021113 did not match the information on the canister with regard to canister identification. The client was notified of the discrepancy and the information on the canister was used to process and report the sample.

**Analytical Notes**

As per project specific client request the laboratory has reported estimated values for target compound hits that are below the Reporting Limit but greater than the Method Detection Limit. Concentrations that are below the level at which the canister was certified may be false positives.

The reporting limit for Carbon Monoxide was raised from 0.010% to 0.050%.

**Definition of Data Qualifying Flags**

Seven qualifiers may have been used on the data analysis sheets and indicate as follows:
B - Compound present in laboratory blank greater than reporting limit.
J - Estimated value.
E - Exceeds instrument calibration range.
S - Saturated peak.
Q - Exceeds quality control limits.
U - Compound analyzed for but not detected above the detection limit.
M - Reported value may be biased due to apparent matrix interferences.
File extensions may have been used on the data analysis sheets and indicates as follows:
a-File was requantified
b-File was quantified by a second column and detector
r1-File was requantified for the purpose of reissue

eurofins | Air Toxics

# Summary of Detected Compounds
# NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1946

**Client Sample ID: VMP-3-31.5-020713**

**Lab ID#: 1302278B-01A**

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.26 | 1.5 |
| Nitrogen | 0.26 | 85 |
| Methane | 0.00026 | 2.9 |
| Carbon Dioxide | 0.026 | 9.9 |
| Ethane | 0.0026 | 0.00060 J |

**Client Sample ID: VMP-3-39-021213**

**Lab ID#: 1302278B-02A**

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.26 | 1.5 |
| Nitrogen | 0.26 | 80 |
| Methane | 0.00026 | 6.7 |
| Carbon Dioxide | 0.026 | 9.5 |
| Ethane | 0.0026 | 0.0023 J |

**Client Sample ID: VMP-4-23.5-020713**

**Lab ID#: 1302278B-03A**

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.26 | 14 |
| Nitrogen | 0.26 | 80 |
| Methane | 0.00026 | 0.060 |
| Carbon Dioxide | 0.026 | 6.2 |

**Client Sample ID: VMP-4-39-020713**

**Lab ID#: 1302278B-04A**

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.27 | 12 |
| Nitrogen | 0.27 | 76 |
| Methane | 0.00027 | 1.6 |

eurofins | Air Toxics

# Summary of Detected Compounds
# NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1946

**Client Sample ID: VMP-4-39-020713**

**Lab ID#: 1302278B-04A**

| | | |
|---|---|---|
| Carbon Dioxide | 0.027 | 9.1 |
| Ethane | 0.0027 | 0.00024 J |
| Ethene | 0.0027 | 0.00012 J |
| Helium | 0.13 | 0.072 J |

**Client Sample ID: VMP-15-21.5-020713**

**Lab ID#: 1302278B-05A**

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.28 | 1.8 |
| Nitrogen | 0.28 | 83 |
| Methane | 0.00028 | 0.044 |
| Carbon Dioxide | 0.028 | 15 |
| Helium | 0.14 | 0.14 |

**Client Sample ID: VMP-15-25.5-021213**

**Lab ID#: 1302278B-06A**

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.27 | 1.6 |
| Nitrogen | 0.27 | 81 |
| Methane | 0.00027 | 0.87 |
| Carbon Dioxide | 0.027 | 16 |
| Ethane | 0.0027 | 0.00051 J |

**Client Sample ID: VMP-15-29-021213**

**Lab ID#: 1302278B-07A**

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.27 | 4.1 |
| Nitrogen | 0.27 | 82 |
| Methane | 0.00027 | 0.64 |
| Carbon Dioxide | 0.027 | 13 |
| Ethane | 0.0027 | 0.00039 J |

eurofins | Air Toxics

# Summary of Detected Compounds
# NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1946

**Client Sample ID: VMP-15-29-021213**

**Lab ID#: 1302278B-07A**

| | | |
|---|---|---|
| Helium | 0.13 | 0.20 |

**Client Sample ID: VMP-31-20-021113**

**Lab ID#: 1302278B-08A**

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.28 | 18 |
| Nitrogen | 0.28 | 78 |
| Methane | 0.00028 | 0.0044 |
| Carbon Dioxide | 0.028 | 3.6 |

**Client Sample ID: VMP-31-30-021113**

**Lab ID#: 1302278B-09A**

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.28 | 5.6 |
| Nitrogen | 0.28 | 83 |
| Methane | 0.00028 | 0.0088 |
| Carbon Dioxide | 0.028 | 11 |

**Client Sample ID: VMP-32-30-020513**

**Lab ID#: 1302278B-10A**

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.28 | 4.3 |
| Nitrogen | 0.28 | 82 |
| Methane | 0.00028 | 0.00075 |
| Carbon Dioxide | 0.028 | 14 |

eurofins | Air Toxics

**Client Sample ID: VMP-3-31.5-020713**

**Lab ID#: 1302278B-01A**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1946**

| | | | |
|---|---|---|---|
| **File Name:** | **9021916** | **Date of Collection: 2/7/13 10:35:00 AM** | |
| **Dil. Factor:** | **2.58** | **Date of Analysis: 2/19/13 04:19 PM** | |

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.26 | 1.5 |
| Nitrogen | 0.26 | 85 |
| Carbon Monoxide | 0.13 | Not Detected |
| Methane | 0.00026 | 2.9 |
| Carbon Dioxide | 0.026 | 9.9 |
| Ethane | 0.0026 | 0.00060 J |
| Ethene | 0.0026 | Not Detected |
| Helium | 0.13 | Not Detected |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

eurofins | Air Toxics

**Client Sample ID: VMP-3-39-021213**

**Lab ID#: 1302278B-02A**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1946**

| | | | |
|---|---|---|---|
| **File Name:** | **9021917** | **Date of Collection:** | **2/12/13 10:59:00 AM** |
| **Dil. Factor:** | **2.64** | **Date of Analysis:** | **2/19/13 05:12 PM** |

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.26 | 1.5 |
| Nitrogen | 0.26 | 80 |
| Carbon Monoxide | 0.13 | Not Detected |
| Methane | 0.00026 | 6.7 |
| Carbon Dioxide | 0.026 | 9.5 |
| Ethane | 0.0026 | 0.0023 J |
| Ethene | 0.0026 | Not Detected |
| Helium | 0.13 | Not Detected |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

eurofins | Air Toxics

**Client Sample ID: VMP-4-23.5-020713**

**Lab ID#: 1302278B-03A**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1946**

| | | | |
|---|---|---|---|
| **File Name:** | **9021919** | **Date of Collection:** | **2/7/13 11:22:00 AM** |
| **Dil. Factor:** | **2.64** | **Date of Analysis:** | **2/19/13 06:04 PM** |

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.26 | 14 |
| Nitrogen | 0.26 | 80 |
| Carbon Monoxide | 0.13 | Not Detected |
| Methane | 0.00026 | 0.060 |
| Carbon Dioxide | 0.026 | 6.2 |
| Ethane | 0.0026 | Not Detected |
| Ethene | 0.0026 | Not Detected |
| Helium | 0.13 | Not Detected |

**Container Type: 1 Liter Summa Canister**

eurofins | Air Toxics

**Client Sample ID: VMP-4-39-020713**

**Lab ID#: 1302278B-04A**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1946**

| | | | |
|---|---|---|---|
| **File Name:** | **9021920** | **Date of Collection: 2/7/13 1:43:00 PM** | |
| **Dil. Factor:** | **2.69** | **Date of Analysis: 2/19/13 06:40 PM** | |

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.27 | 12 |
| Nitrogen | 0.27 | 76 |
| Carbon Monoxide | 0.13 | Not Detected |
| Methane | 0.00027 | 1.6 |
| Carbon Dioxide | 0.027 | 9.1 |
| Ethane | 0.0027 | 0.00024 J |
| Ethene | 0.0027 | 0.00012 J |
| Helium | 0.13 | 0.072 J |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

eurofins | Air Toxics

**Client Sample ID: VMP-15-21.5-020713**

**Lab ID#: 1302278B-05A**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1946**

| | | | |
|---|---|---|---|
| **File Name:** | **9021922** | **Date of Collection: 2/7/13 3:27:00 PM** | |
| **Dil. Factor:** | **2.76** | **Date of Analysis: 2/19/13 07:55 PM** | |

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.28 | 1.8 |
| Nitrogen | 0.28 | 83 |
| Carbon Monoxide | 0.14 | Not Detected |
| Methane | 0.00028 | 0.044 |
| Carbon Dioxide | 0.028 | 15 |
| Ethane | 0.0028 | Not Detected |
| Ethene | 0.0028 | Not Detected |
| Helium | 0.14 | 0.14 |

**Container Type: 1 Liter Summa Canister**

eurofins | Air Toxics

**Client Sample ID: VMP-15-25.5-021213**

**Lab ID#: 1302278B-06A**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1946**

| | | | |
|---|---|---|---|
| **File Name:** | **9021923** | **Date of Collection: 2/12/13 2:49:00 PM** | |
| **Dil. Factor:** | **2.69** | **Date of Analysis: 2/19/13 08:18 PM** | |

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.27 | 1.6 |
| Nitrogen | 0.27 | 81 |
| Carbon Monoxide | 0.13 | Not Detected |
| Methane | 0.00027 | 0.87 |
| Carbon Dioxide | 0.027 | 16 |
| Ethane | 0.0027 | 0.00051 J |
| Ethene | 0.0027 | Not Detected |
| Helium | 0.13 | Not Detected |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

eurofins | Air Toxics

**Client Sample ID: VMP-15-29-021213**

**Lab ID#: 1302278B-07A**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1946**

| | | | |
|---|---|---|---|
| **File Name:** | **9021914** | **Date of Collection: 2/12/13 3:37:00 PM** | |
| **Dil. Factor:** | **2.69** | **Date of Analysis: 2/19/13 03:22 PM** | |

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.27 | 4.1 |
| Nitrogen | 0.27 | 82 |
| Carbon Monoxide | 0.13 | Not Detected |
| Methane | 0.00027 | 0.64 |
| Carbon Dioxide | 0.027 | 13 |
| Ethane | 0.0027 | 0.00039 J |
| Ethene | 0.0027 | Not Detected |
| Helium | 0.13 | 0.20 |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

eurofins | Air Toxics

**Client Sample ID: VMP-31-20-021113**

**Lab ID#: 1302278B-08A**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1946**

| | | | |
|---|---|---|---|
| **File Name:** | **9021915** | **Date of Collection:** | **2/11/13 12:05:00 PM** |
| **Dil. Factor:** | **2.76** | **Date of Analysis:** | **2/19/13 03:47 PM** |

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.28 | 18 |
| Nitrogen | 0.28 | 78 |
| Carbon Monoxide | 0.14 | Not Detected |
| Methane | 0.00028 | 0.0044 |
| Carbon Dioxide | 0.028 | 3.6 |
| Ethane | 0.0028 | Not Detected |
| Ethene | 0.0028 | Not Detected |
| Helium | 0.14 | Not Detected |

**Container Type: 1 Liter Summa Canister**

eurofins | Air Toxics

**Client Sample ID: VMP-31-30-021113**

**Lab ID#: 1302278B-09A**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1946**

| | | | |
|---|---|---|---|
| **File Name:** | **9021924** | **Date of Collection: 2/11/13 2:33:00 PM** | |
| **Dil. Factor:** | **2.82** | **Date of Analysis: 2/19/13 08:41 PM** | |

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.28 | 5.6 |
| Nitrogen | 0.28 | 83 |
| Carbon Monoxide | 0.14 | Not Detected |
| Methane | 0.00028 | 0.0088 |
| Carbon Dioxide | 0.028 | 11 |
| Ethane | 0.0028 | Not Detected |
| Ethene | 0.0028 | Not Detected |
| Helium | 0.14 | Not Detected |

**Container Type: 1 Liter Summa Canister**

eurofins | Air Toxics

**Client Sample ID: VMP-32-30-020513**

**Lab ID#: 1302278B-10A**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1946**

| | | | |
|---|---|---|---|
| **File Name:** | **9021925** | **Date of Collection: 2/5/13 11:41:00 AM** | |
| **Dil. Factor:** | **2.82** | **Date of Analysis: 2/19/13 09:03 PM** | |

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.28 | 4.3 |
| Nitrogen | 0.28 | 82 |
| Carbon Monoxide | 0.14 | Not Detected |
| Methane | 0.00028 | 0.00075 |
| Carbon Dioxide | 0.028 | 14 |
| Ethane | 0.0028 | Not Detected |
| Ethene | 0.0028 | Not Detected |
| Helium | 0.14 | Not Detected |

**Container Type: 1 Liter Summa Canister**

eurofins | Air Toxics

**Client Sample ID: Lab Blank**

**Lab ID#: 1302278B-11A**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1946**

| | | | |
|---|---|---|---|
| **File Name:** | **9021904a** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 2/19/13 10:22 AM** | |

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.10 | Not Detected |
| Nitrogen | 0.10 | 0.057 J |
| Carbon Monoxide | 0.050 | Not Detected |
| Methane | 0.00010 | Not Detected |
| Carbon Dioxide | 0.010 | Not Detected |
| Ethane | 0.0010 | Not Detected |
| Ethene | 0.0010 | Not Detected |

J = Estimated value.

**Container Type: NA - Not Applicable**

eurofins | Air Toxics

**Client Sample ID: Lab Blank**

**Lab ID#: 1302278B-11B**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1946**

| | | | |
|---|---|---|---|
| **File Name:** | **9021903b** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 2/19/13 09:55 AM** | |

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Helium | 0.050 | Not Detected |

**Container Type: NA - Not Applicable**

eurofins | Air Toxics

**Client Sample ID: LCS**

**Lab ID#: 1302278B-12A**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1946**

| | | | |
|---|---|---|---|
| **File Name:** | **9021902** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 2/19/13 09:23 AM** | |

| Compound | %Recovery |
|---|---|
| Oxygen | 100 |
| Nitrogen | 101 |
| Carbon Monoxide | 97 |
| Methane | 97 |
| Carbon Dioxide | 100 |
| Ethane | 98 |
| Ethene | 96 |
| Helium | 99 |

**Container Type: NA - Not Applicable**

eurofins | Air Toxics

**Client Sample ID: LCSD**

**Lab ID#: 1302278B-12AA**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1946**

| | | | |
|---|---|---|---|
| **File Name:** | **9021928** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 2/19/13 10:15 PM** | |

| Compound | %Recovery |
|---|---|
| Oxygen | 100 |
| Nitrogen | 100 |
| Carbon Monoxide | 98 |
| Methane | 95 |
| Carbon Dioxide | 99 |
| Ethane | 97 |
| Ethene | 94 |
| Helium | 98 |

**Container Type: NA - Not Applicable**

# Shell Oil Products Chain Of Custody Record

1302278 URS

Air Toxics LTD.
Project Name: Roxana Soil Vapor
Project # 21562850.04001
Lab Vendor #

Please Check Appropriate Box: ☑ ENV. SERVICES ☐ MOTIVA RETAIL ☐ SHELL RETAIL ☐ MOTIVA SD&CN ☐ CONSULTANT ☐ LUBES ☐ SHELL PIPELINE ☐ OTHER

Print Bill To Contact Name: Robert Mooshegian
INCIDENT # (ENV SERVICES): 9 7 2 1 6 6 4 0
☐ CHECK IF NO INCIDENT # APPLIES
DATE: 02/14/13
PAGE 1 of 1
PO #:
SAP #: 3 4 0 0 6 1
LOG CODE:

SAMPLING COMPANY: URS CORPORATION
ADDRESS: 1001 HIGHLANDS PLAZA DRIVE WEST - SUITE 300; ST. LOUIS, MO 63110
Laboratory Address: Air Toxics, LTD 180 Blue Ravine Road, Suite B, Folsom, CA 95630-4719
TELEPHONE: 314-429-0100
FAX: 314-429-0462
BILL To Contact E-MAIL: RobertL.Mooshegian@urs.com
SITE ADDRESS: Street and City: 900 SOUTH CENTRAL AVE – ROXANA
State: IL
GLOBAL ID NO.:
PHONE NO: 314-743-4179
E-MAIL: Elizabeth.Kunkel@URSCorp.com
CONSULTANT PROJECT NAME #: Roxana Soil Vapor
E-DELIVERABLE TO (Name, Company, Office Location): Elizabeth Kunkel, URS, St. Louis
L. Rathnow, B. Lehan, C. Kretzer, D. Mattingly, C. Williams

TURNAROUND TIME (CALENDAR DAYS): ☑ STANDARD (14 DAY) ☐ 5 DAYS ☐ 3 DAYS ☐ 2 DAYS ☐ 24 HOURS ☐ RESULTS NEEDED ON WEEKEND

☐ LA - RWQCB REPORT FORMAT ☑ UST AGENCY:

DELIVERABLES: ☐ LEVEL 1 ☐ LEVEL 2 ☐ LEVEL 3 ☑ LEVEL 4 ☐ OTHER (SPECIFY)

☑ SHELL CONTRACT RATE APPLIES
☐ STATE REIMBURSEMENT RATE APPLIES
☐ EDD NOT NEEDED
☑ RECEIPT VERIFICATION REQUESTED

REQUESTED ANALYSIS

Turn Around Time: ☑ Normal ☐ Rush ☐ Specify

Lab Use Only
Pressurized by:
Date:
Pressurization Gas: N2 He

| Lab Use Only | Field Sample Identification | SAMPLING DATE | SAMPLING TIME | Canister Number | Canister Pressure/Vacuum Initial | Final | Receipt | Final (psi) | Modified TO-15 + Butane & Isopentane | ASTM D-1946 + Helium | ASTM D-1946 | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| 01A | VMP-3-31.5-020713 | 02/07/13 | 1005-1035 | 14527 | -30 | -7.5 | | | X | X | | | | | | |
| 02A | VMP-3-39-021213 | 02/12/13 | 1029-1059 | 34189 | -30 | -7.5 | | | X | X | | | | | | |
| 03A | VMP-4-23.5-020713 | 02/07/13 | 1052-1122 | 3056 | -30 | -9 | | | X | X | | | | | | |
| 04A | VMP-4-39-020713 | 02/07/13 | 1313-1343 | 1363 | -29.5 | -8.5 | | | X | X | | | | | | |
| 05A | VMP-15-21.5-020713 | 02/07/13 | 1457-1527 | 36410 | -30 | -8.5 | | | X | X | | | | | | |
| 06A | VMP-15-25.5-021213 | 02/12/13 | 1419-1449 | 1358 | -30 | -8.5 | | | X | X | | | | | | |
| 07A | VMP-15-29-021213 | 02/12/13 | 1507-1537 | 34086 | -30 | -8.5 | | | X | X | | | | | | |
| 08A | VMP-31-20-021113 | 02/11/13 | 1133-1205 | 22963 | -30 | -9 | | | X | X | | | | | | |
| 09A | VMP-31-30-021113 | 02/11/13 | 1403-1433 | 36472 | -30 | -10.5 | | | X | X | | | | | | |
| 10A | VMP-32-30-020513 | 02/05/13 | 1111-1141 | 34135 | -30 | -8.5 | | | X | X | | | | | | |

ADDITIONAL NOTES:
- 14 day hold time
- Report results between MDL and RL
- Level IV ECVP

| | Relinquished by (Signature) | Received by (Signature) | Date | Time |
|---|---|---|---|---|
| | | FEDEX | 2/14/13 | 1730 |
| | | | 2/14/13 | |
| | | | 2/15/13 | 0945 |
| | | | | |

05/2008 Revision

Custody Seal Intact?
Y N None Temp NA

# Roxana Soil Vapor Quarterly – 1st Quarter 2013 Data Review

**Laboratory SDG: 1302355A,B**

**Data Reviewer: Alan Fleisher**

**Peer Reviewer: Elizabeth Kunkel**

**Date Reviewed: 3/25/2013**

**Guidance: USEPA National Functional Guidelines for Superfund Organic Methods Data Review 2008**

| Sample Identification | Sample Identification |
|---|---|
| VMP-12-021513 | VMP-12-39-021513 |
| VMP-16-5-021413 | VMP-16-13.5-021413 |
| VMP-16-19-021413 | VMP-16-31-021813 |
| VMP-55-20-021513 | |

## 1.0 Data Package Completeness

*Were all items delivered as specified in the QAPP and COC as appropriate?*

Yes.

## 2.0 Laboratory Case Narrative \ Cooler Receipt Form

*Were problems noted in the laboratory case narrative or cooler receipt form?*

Yes, the laboratory case narrative indicated samples VMP-16-13.5-021413 and VMP-16-19-021413 were diluted and re-analyzed to bring the highest level target analytes with the calibration range of the instrument. Results for the highest level target analytes were reported from the re-analysis diluted runs and the remaining compounds were reported from the original analyses. All samples were diluted due to high levels of target analytes. Although not indicated in the laboratory case narrative, analytes were detected in the method blank. These issues are addressed further in the appropriate sections below.

No issues or discrepancies were noted in the cooler receipt form.

## 3.0 Holding Times

*Were samples extracted/analyzed within applicable limits?*

Yes

## 4.0 Blank Contamination

*Were any analytes detected in the Blanks?*

Yes

| Blank ID | Parameter | Analyte | Concentration/ Amount |
|---|---|---|---|
| 1302355A-08A | TO-15 | Methylene chloride | 2.2 ppbv / 7.6 µg/m$^3$ |
| 1302355A-08B | TO-15 | Ethanol | 11 ppbv / 22 µg/m$^3$ |
| 1302355A-08B | TO-15 | Methylene chloride | 1.4 ppbv / 4.9 µg/m$^3$ |
| 1302355A-08B | TO-15 | alpha-Chlorotoluene | 1.1 ppbv / 5.8 µg/m$^3$ |

| Blank ID | Parameter | Analyte | Concentration/ Amount |
|---|---|---|---|
| 1302083B-17A | Natural gases | Oxygene | 0.034% |
| 1302083B-17A | Natural gases | Nitrogen | 0.064% |

Analytical data reported non-detect or at concentrations greater than five times (5X) the associated blank concentration did not require qualification. No qualification of data was required.

## 5.0 Laboratory Control Sample

*Were LCS recoveries within evaluation criteria?*

No

| LCS/LCSD ID | Parameter | Analyte | LCS/LCSD Recovery | LCS/ LCSD RPD | LCS/LCSD /RPD Criteria |
|---|---|---|---|---|---|
| 1302355A-10B/BB | TO-15 | alpha-Chlorotoluene | **139/**120 | 15 | 70-130/25 |
| 1302355A-10B/BB | TO-15 | 1,2,4-Trichlorobenzene | 119/85 | **33** | 70-130/25 |
| 1302355A-10B/BB | TO-15 | Hexachlorobutadiene | 112/84 | **29** | 70-130/25 |

Analytical data reported as non-detect and associated with LCS recoveries above evaluation criteria, indicating a possible high bias, did not require qualification. Analytical data associated with LCS/LCSD RPD alone outside evaluation criteria did not require qualification; LCS/LCSD recoveries were within evaluation criteria. No qualification of data was required.

## 6.0 Surrogate Recoveries

*Were surrogate recoveries within evaluation criteria?*

No

| Sample ID | Parameter | Surrogate | Surrogate Recovery | Surrogate Recovery Criteria |
|---|---|---|---|---|
| VMP-12-25-021513 | TO-15 | 1,2-Dichloroethane-d4 | **135** | 70-130 |
| VMP-16-5-021413 | TO-15 | 1,2-Dichloroethane-d4 | **132** | 70-130 |
| VMP-16-13.5-021413 | TO-15 | 1,2-Dichloroethane-d4 | **147** | 70-130 |
| VMP-16-19-021413 | TO-15 | 1,2-Dichloroethane-d4 | **160** | 70-130 |

Analytical data that required qualification based on surrogate recovery data are included in the table below. Analytical data reported as non-detect and associated with surrogate recoveries above evaluation criteria, indicating a possible high bias, did not require qualification.

| Sample ID | Parameter | Analyte | Qualification |
|---|---|---|---|
| VMP-12-25-021513 | TO-15 | VOC detects | **J** |
| VMP-16-5-021413 | TO-15 | VOC detects | **J** |
| VMP-16-13.5-021413 | TO-15 | VOC detects | **J** |
| VMP-16-19-021413 | TO-15 | VOC detects | **J** |

## 7.0 Matrix Spike and Matrix Spike Duplicate Recoveries

*Were MS/MSD samples analyzed as part of this SDG?*

MS/MSD samples are not applicable for vapor samples, due to the inability to spike the samples.

## 8.0 Laboratory Duplicate Results

No

## 9.0 Field Duplicate Results

*Were field duplicate samples collected as part of this SDG?*

No

## 10.0 Sample Dilutions

*For samples that were diluted and nondetect, were undiluted results also reported?*

Not applicable; analytes were detected in samples that were diluted.

## 11.0 Additional Qualifications

*Were additional qualifications applied?*

No

eurofins | Air Toxics

3/7/2013
Ms. Elizabeth Kunkel
URS Corporation
1001 Highlands Plaza Dr. West
Suite 300
St. Louis MO 63110

Project Name: Roxana Soil Vapor
Project #: 21562850.04001
Workorder #: 1302355A

Dear Ms. Elizabeth Kunkel

The following report includes the data for the above referenced project for sample(s) received on 2/20/2013 at Air Toxics Ltd.

The data and associated QC analyzed by Modified TO-15 are compliant with the project requirements or laboratory criteria with the exception of the deviations noted in the attached case narrative.

Thank you for choosing Air Toxics Ltd. for your air analysis needs. Air Toxics Ltd. is committed to providing accurate data of the highest quality. Please feel free to contact the Project Manager: Kelly Buettner at 916-985-1000 if you have any questions regarding the data in this report.

Regards,

Kelly Buettner

Project Manager

REVIEWED
ON
3/22/13

eurofins | Air Toxics

# WORK ORDER #: 1302355A

Work Order Summary

| | | | |
|---|---|---|---|
| **CLIENT:** | Ms. Elizabeth Kunkel<br>URS Corporation<br>1001 Highlands Plaza Dr. West<br>Suite 300<br>St. Louis, MO 63110 | **BILL TO:** | Accounts Payable Austin<br>URS Corporation<br>P.O. BOX 203970<br>Austin, TX 78720-1088 |
| **PHONE:** | 314-743-4179 | **P.O. #** | 21562735.00013 |
| **FAX:** | | **PROJECT #** | 21562850.04001 Roxana Soil Vapor |
| **DATE RECEIVED:** | 02/20/2013 | **CONTACT:** | Kelly Buettner |
| **DATE COMPLETED:** | 03/07/2013 | | |

| FRACTION # | NAME | TEST | RECEIPT VAC./PRES. | FINAL PRESSURE |
|---|---|---|---|---|
| 01A | VMP-12-25-021513 | Modified TO-15 | 6.5 "Hg | 15 psi |
| 02A | VMP-12-39-021513 | Modified TO-15 | 5.0 "Hg | 15 psi |
| 03A | VMP-16-5-021413 | Modified TO-15 | 7.0 "Hg | 15 psi |
| 04A | VMP-16-13.5-021413 | Modified TO-15 | 7.5 "Hg | 15 psi |
| 04B | VMP-16-13.5-021413 | Modified TO-15 | 7.5 "Hg | 15 psi |
| 05A | VMP-16-19-021413 | Modified TO-15 | 7.0 "Hg | 15 psi |
| 05B | VMP-16-19-021413 | Modified TO-15 | 7.0 "Hg | 15 psi |
| 06A | VMP-16-31-021813 | Modified TO-15 | 11.0 "Hg | 15 psi |
| 07A | VMP-55-20-021513 | Modified TO-15 | 8.0 "Hg | 15 psi |
| 08A | Lab Blank | Modified TO-15 | NA | NA |
| 08B | Lab Blank | Modified TO-15 | NA | NA |
| 09A | CCV | Modified TO-15 | NA | NA |
| 09B | CCV | Modified TO-15 | NA | NA |
| 10A | LCS | Modified TO-15 | NA | NA |
| 10AA | LCSD | Modified TO-15 | NA | NA |
| 10B | LCS | Modified TO-15 | NA | NA |
| 10BB | LCSD | Modified TO-15 | NA | NA |

CERTIFIED BY: Heidi Hayes DATE: 03/07/13

Technical Director

Certfication numbers: AZ Licensure AZ0775, CA NELAP - 12282CA, NY NELAP - 11291,
TX NELAP - T104704434-12-5, UT NELAP CA009332012-3, WA NELAP - C935
Name of Accrediting Agency: NELAP/ORELAP (Oregon Environmental Laboratory Accreditation Program)
Accreditation number: CA300005, Effective date: 10/18/2011, Expiration date: 10/17/2012.
Eurofins Air Toxics Ltd. certifies that the test results contained in this report meet all requirements of the NELAC standards

This report shall not be reproduced, except in full, without the written approval of Eurofins Air Toxics, Inc

180 BLUE RAVINE ROAD, SUITE B FOLSOM, CA - 9563
(916) 985-1000 . (800) 985-5955 . FAX (916) 985-1020

**LABORATORY NARRATIVE**
**EPA Method TO-15**
**URS Corporation**
**Workorder# 1302355A**

Seven 1 Liter Summa Canister samples were received on February 20, 2013. The laboratory performed analysis via EPA Method TO-15 using GC/MS in the full scan mode.

This workorder was independently validated prior to submittal using 'USEPA National Functional Guidelines' as generally applied to the analysis of volatile organic compounds in air. A rules-based, logic driven, independent validation engine was employed to assess completeness, evaluate pass/fail of relevant project quality control requirements and verification of all quantified amounts.

**Receiving Notes**

There were no receiving discrepancies.

**Analytical Notes**

As per client project requirements, the laboratory has reported estimated values for target compound hits that are below the Reporting Limit but greater than the Method Detection Limit. Concentrations that are below the level at which the canister was certified may be false positives.

Dilution was performed on all of the samples due to the presence of high level target species.

Due to high-level target compounds, samples VMP-16-13.5-021413 and VMP-16-19-021413 were analyzed twice. In the "A" fraction, the sample was diluted to bring the highest-level compounds within the calibration range. The "B" fraction is also reported by client request and may be reported with "E" flags indicating the compound exceeds the calibration range. Both runs and associated QC are reported.

The Relative Percent Difference (RPD) of the LCS/LCSD performed on 02/28/2013 exceeded acceptance limits for 1,2,4-Trichlorobenzene and Hexachlorobutadiene.

The recovery of surrogate 1,2-Dichloroethane-d4 in samples VMP-12-25-021513, VMP-16-5-021413, VMP-16-13.5-021413, and VMP-16-19-021413 "B" fraction was outside laboratory control limits due to high level hydrocarbon matrix interference. The surrogate recovery is flagged.

All Quality Control Limit exceedances and affected sample results are noted by flags. Each flag is defined at the bottom of this Case Narrative and on each Sample Result Summary page.

Due to the linear calibration range of the instrument, the reporting limit for 4-Methyl-2-pentanone was raised from 5.0 ppbv to 20 ppbv.

**Definition of Data Qualifying Flags**

Eight qualifiers may have been used on the data analysis sheets and indicates as follows:

B - Compound present in laboratory blank greater than reporting limit (background subtraction not performed).

J - Estimated value.

E - Exceeds instrument calibration range.

S - Saturated peak.
Q - Exceeds quality control limits.
U - Compound analyzed for but not detected above the reporting limit.
UJ- Non-detected compound associated with low bias in the CCV and/or LCS.
N - The identification is based on presumptive evidence.

File extensions may have been used on the data analysis sheets and indicates as follows:
a-File was requantified
b-File was quantified by a second column and detector
r1-File was requantified for the purpose of reissue

eurofins | Air Toxics

# Summary of Detected Compounds
# EPA METHOD TO-15 GC/MS

**Client Sample ID: VMP-12-25-021513**

**Lab ID#: 1302355A-01A**

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Acetone | 3200 | 390 J | 7600 | 930 J |
| Methylene Chloride | 800 | 520 J | 2800 | 1800 J |
| Hexane | 800 | 1900 | 2800 | 6600 |
| Cyclohexane | 800 | 5800 | 2800 | 20000 |
| 2,2,4-Trimethylpentane | 800 | 250000 | 3800 | 1200000 |
| Benzene | 800 | 1800 | 2600 | 5800 |
| Trichloroethene | 800 | 400 J | 4300 | 2100 J |
| 1,2-Dichloropropane | 800 | 3000 | 3700 | 14000 |
| Butane | 3200 | 22000 | 7600 | 53000 |
| Isopentane | 3200 | 480000 | 9500 | 1400000 |

**Client Sample ID: VMP-12-39-021513**

**Lab ID#: 1302355A-02A**

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Chloroethane | 9700 | 840 J | 26000 | 2200 J |
| 1,1-Dichloroethene | 2400 | 260 J | 9600 | 1000 J |
| Methylene Chloride | 2400 | 2700 | 8400 | 9500 |
| Hexane | 2400 | 64000 | 8500 | 220000 |
| Cyclohexane | 2400 | 52000 | 8300 | 180000 |
| 2,2,4-Trimethylpentane | 2400 | 780000 | 11000 | 3600000 |
| Benzene | 2400 | 1300000 | 7700 | 4100000 |
| Heptane | 2400 | 19000 | 9900 | 78000 |
| Trichloroethene | 2400 | 1200 J | 13000 | 6400 J |
| 1,2-Dichloropropane | 2400 | 4500 | 11000 | 21000 |
| Toluene | 2400 | 810 J | 9100 | 3100 J |
| Ethyl Benzene | 2400 | 9500 | 10000 | 41000 |
| m,p-Xylene | 2400 | 4800 | 10000 | 21000 |
| Cumene | 2400 | 3400 | 12000 | 17000 |
| Propylbenzene | 2400 | 4000 | 12000 | 20000 |
| 4-Ethyltoluene | 2400 | 1900 J | 12000 | 9200 J |
| 1,2,4-Trimethylbenzene | 2400 | 3200 | 12000 | 16000 |
| Butane | 9700 | 140000 | 23000 | 320000 |

eurofins | Air Toxics

# Summary of Detected Compounds
# EPA METHOD TO-15 GC/MS

**Client Sample ID: VMP-12-39-021513**

**Lab ID#: 1302355A-02A**

| | | | | |
|---|---|---|---|---|
| Isopentane | 9700 | 1400000 | 28000 | 4100000 |

**Client Sample ID: VMP-16-5-021413**

**Lab ID#: 1302355A-03A**

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Methylene Chloride | 110 | 69 J J | 380 | 240 J J |
| Cyclohexane | 110 | 70 J J | 380 | 240 J J |
| 2,2,4-Trimethylpentane | 110 | 63000 J | 510 | 290000 J |
| Benzene | 110 | 54 J J | 350 | 170 J J |
| Trichloroethene | 110 | 44 J J | 590 | 240 J J |
| 1,2-Dichloropropane | 110 | 660 J | 510 | 3100 J |
| Isopentane | 440 | 1800 J | 1300 | 5400 J |

* USE THIS DATA ONLY. ALL OTHER DATA REPORTED IN 448X DILUTION ANALYSIS.

**Client Sample ID: VMP-16-13.5-021413**

**Lab ID#: 1302355A-04A** DF: 672X

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Chloromethane | 13000 | 2400 J | 28000 | 4900 J |
| Ethanol | 13000 | 1600 J | 25000 | 3100 J |
| Acetone | 13000 | 2600 J | 32000 | 6300 J |
| Carbon Disulfide | 3400 | 570 J | 10000 | 1800 J |
| Methylene Chloride | 3400 | 2800 J | 12000 | 9600 J |
| Methyl tert-butyl ether | 3400 | 620 J | 12000 | 2200 J |
| Hexane | 3400 | 980 J | 12000 | 3400 J |
| Cyclohexane | 3400 | 40000 | 12000 | 140000 |
| 2,2,4-Trimethylpentane | 3400 | 2400000 | 16000 | 11000000 |
| Benzene | 3400 | 5900 | 11000 | 19000 |
| Trichloroethene | 3400 | 940 J | 18000 | 5100 J |
| 1,2-Dichloropropane | 3400 | 5600 | 16000 | 26000 |
| Toluene | 3400 | 410 J | 13000 | 1500 J |
| Ethyl Benzene | 3400 | 640 J | 14000 | 2800 J |
| Cumene | 3400 | 670 J | 16000 | 3300 J |
| Propylbenzene | 3400 | 1300 J | 16000 | 6500 J |

eurofins | Air Toxics

# Summary of Detected Compounds
# EPA METHOD TO-15 GC/MS

**Client Sample ID: VMP-16-13.5-021413**

**Lab ID#: 1302355A-04A**

| | | | | |
|---|---|---|---|---|
| Butane | 13000 | 33000 | 32000 | 79000 |
| Isopentane | 13000 | 580000 | 40000 | 1700000 |

**Client Sample ID: VMP-16-13.5-021413**

* DO NOT USE THIS DATA. USE ALL OTHER DATA

**Lab ID#: 1302355A-04B** DF = 448 X

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 113 | 2200 | 390 J | 17000 | 3000 J |
| 1,1-Dichloroethene | 2200 | 430 J | 8900 | 1700 J |
| Acetone | 9000 | 2200 J | 21000 | 5300 J |
| Carbon Disulfide | 2200 | 740 J | 7000 | 2300 J |
| Methylene Chloride | 2200 | 3400 J | 7800 | 12000 J |
| Methyl tert-butyl ether | 2200 | 590 J | 8100 | 2100 J |
| Hexane | 2200 | 1700 J | 7900 | 6100 J |
| Cyclohexane | 2200 | 38000 J | 7700 | 130000 J |
| ~~2,2,4-Trimethylpentane~~ | ~~2200~~ | ~~2400000 E~~ | ~~10000~~ | ~~11000000 E~~ |
| Benzene | 2200 | 6600 J | 7200 | 21000 J |
| Trichloroethene | 2200 | 3400 | 12000 | 18000 |
| 1,2-Dichloropropane | 2200 | 10000 | 10000 | 48000 |
| Toluene | 2200 | 740 J | 8400 | 2800 J |
| Ethyl Benzene | 2200 | 920 J | 9700 | 4000 J |
| m,p-Xylene | 2200 | 500 J | 9700 | 2200 J |
| Cumene | 2200 | 820 J | 11000 | 4000 J |
| Propylbenzene | 2200 | 1600 J | 11000 | 7800 J |
| Butane | 9000 | 39000 | 21000 | 92000 |
| Isopentane | 9000 | 610000 | 26000 | 1800000 |

**Client Sample ID: VMP-16-19-021413**

**Lab ID#: 1302355A-05A**

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Chloromethane | 16000 | 4100 J | 34000 | 8500 J |
| Acetone | 16000 | 3100 J | 39000 | 7300 J |
| Carbon Disulfide | 4100 | 750 J | 13000 | 2300 J |

eurofins | Air Toxics

# Summary of Detected Compounds
# EPA METHOD TO-15 GC/MS

**Client Sample ID: VMP-16-19-021413**

* USE THIS RESULT ONLY. ALL OTHER DATA REPORTED IN 264 X DILUTION ANALYSIS.

**Lab ID#: 1302355A-05A** DF = 8.24 X

| | | | | |
|---|---|---|---|---|
| Methylene Chloride | 4100 | 3000 J | 14000 | 10000 J |
| Methyl tert-butyl ether | 4100 | 1100 J | 15000 | 4000 J |
| Hexane | 4100 | 740 J | 14000 | 2600 J |
| Cyclohexane | 4100 | 53000 | 14000 | 180000 |
| * 2,2,4-Trimethylpentane | 4100 | 2400000 | 19000 | 11000000 |
| Benzene | 4100 | 4900 | 13000 | 16000 |
| Trichloroethene | 4100 | 1500 J | 22000 | 8000 J |
| 1,2-Dichloropropane | 4100 | 6000 | 19000 | 28000 |
| Ethyl Benzene | 4100 | 17000 | 18000 | 76000 |
| m,p-Xylene | 4100 | 6300 | 18000 | 28000 |
| Cumene | 4100 | 5600 | 20000 | 28000 |
| Propylbenzene | 4100 | 11000 | 20000 | 52000 |
| 4-Ethyltoluene | 4100 | 2500 J | 20000 | 12000 J |
| 1,2,4-Trimethylbenzene | 4100 | 3600 J | 20000 | 18000 J |
| Butane | 16000 | 96000 | 39000 | 230000 |
| Isopentane | 16000 | 1200000 | 49000 | 3600000 |

**Client Sample ID: VMP-16-19-021413**

* DO NOT USE THIS DATA. USE ALL OTHER DATA.

**Lab ID#: 1302355A-05B** DF = 264 X

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Methylene Chloride | 1300 | 990 J | 4600 | 3400 J |
| Methyl tert-butyl ether | 1300 | 1200 J | 4800 | 4500 J |
| Hexane | 1300 | 1100 J | 4600 | 4000 J |
| Cyclohexane | 1300 | 61000 | 4500 | 210000 |
| * ~~2,2,4-Trimethylpentane~~ | ~~1300~~ | ~~2700000 E~~ | ~~6200~~ | ~~13000000 E~~ |
| Benzene | 1300 | 5300 | 4200 | 17000 |
| 1,2-Dichloropropane | 1300 | 4600 | 6100 | 21000 |
| Toluene | 1300 | 220 J | 5000 | 830 J |
| Ethyl Benzene | 1300 | 20000 | 5700 | 88000 |
| m,p-Xylene | 1300 | 6000 | 5700 | 26000 |
| o-Xylene | 1300 | 150 J | 5700 | 640 J |
| Cumene | 1300 | 5500 | 6500 | 27000 |
| Propylbenzene | 1300 | 9200 | 6500 | 45000 |
| 4-Ethyltoluene | 1300 | 1800 | 6500 | 8800 |

eurofins | Air Toxics

# Summary of Detected Compounds
# EPA METHOD TO-15 GC/MS

**Client Sample ID: VMP-16-19-021413**

**Lab ID#: 1302355A-05B**

| | | | | | |
|---|---|---|---|---|---|
| 1,3,5-Trimethylbenzene | 1300 | 800 J | 6500 | 3900 J | |
| 1,2,4-Trimethylbenzene | 1300 | 2600 | 6500 | 13000 | |
| Butane | 5300 | 100000 | 12000 | 240000 | |
| Isopentane | 5300 | 1300000 | 16000 | 3800000 | |

**Client Sample ID: VMP-16-31-021813**

**Lab ID#: 1302355A-06A**

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Methylene Chloride | 5000 | 3600 J | 17000 | 12000 J |
| Methyl tert-butyl ether | 5000 | 1100 J | 18000 | 4100 J |
| Hexane | 5000 | 860 J | 18000 | 3000 J |
| Cyclohexane | 5000 | 75000 | 17000 | 260000 |
| 2,2,4-Trimethylpentane | 5000 | 2700000 | 23000 | 13000000 |
| Benzene | 5000 | 9000 | 16000 | 29000 |
| 1,2-Dichloropropane | 5000 | 5400 | 23000 | 25000 |
| Ethyl Benzene | 5000 | 9900 | 22000 | 43000 |
| Cumene | 5000 | 4200 J | 24000 | 21000 J |
| Propylbenzene | 5000 | 7400 | 24000 | 36000 |
| Butane | 20000 | 120000 | 47000 | 290000 |
| Isopentane | 20000 | 1500000 | 59000 | 4600000 |

**Client Sample ID: VMP-55-20-021513**

**Lab ID#: 1302355A-07A**

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Methylene Chloride | 3400 | 4100 | 12000 | 14000 |
| Hexane | 3400 | 12000 | 12000 | 42000 |
| Cyclohexane | 3400 | 66000 | 12000 | 230000 |
| 2,2,4-Trimethylpentane | 3400 | 79000 | 16000 | 370000 |
| Benzene | 3400 | 410 J | 11000 | 1300 J |
| Trichloroethene | 3400 | 1000 J | 18000 | 5500 J |
| 1,2-Dichloropropane | 3400 | 4200 | 16000 | 19000 |
| Butane | 14000 | 1200000 | 33000 | 2900000 |

eurofins | Air Toxics

# Summary of Detected Compounds
# EPA METHOD TO-15 GC/MS

**Client Sample ID: VMP-55-20-021513**

**Lab ID#: 1302355A-07A**

| | | | | |
|---|---|---|---|---|
| Isopentane | 14000 | 1500000 | 41000 | 4500000 |

eurofins | Air Toxics

**Client Sample ID: VMP-12-25-021513**

**Lab ID#: 1302355A-01A**

**EPA METHOD TO-15 GC/MS**

| | | | |
|---|---|---|---|
| **File Name:** | **14022730** | **Date of Collection:** | **2/15/13 11:53:00 AM** |
| **Dil. Factor:** | **161** | **Date of Analysis:** | **2/28/13 07:09 AM** |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 800 | Not Detected | 4000 | Not Detected |
| Freon 114 | 800 | Not Detected | 5600 | Not Detected |
| Chloromethane | 3200 | Not Detected | 6600 | Not Detected |
| Vinyl Chloride | 800 | Not Detected | 2000 | Not Detected |
| 1,3-Butadiene | 800 | Not Detected | 1800 | Not Detected |
| Bromomethane | 800 | Not Detected | 3100 | Not Detected |
| Chloroethane | 3200 | Not Detected | 8500 | Not Detected |
| Freon 11 | 800 | Not Detected | 4500 | Not Detected |
| Ethanol | 3200 | Not Detected | 6100 | Not Detected |
| Freon 113 | 800 | Not Detected | 6200 | Not Detected |
| 1,1-Dichloroethene | 800 | Not Detected | 3200 | Not Detected |
| Acetone | 3200 | 390 J | 7600 | 930 J |
| 2-Propanol | 3200 | Not Detected | 7900 | Not Detected |
| Carbon Disulfide | 800 | Not Detected | 2500 | Not Detected |
| 3-Chloropropene | 3200 | Not Detected | 10000 | Not Detected |
| Methylene Chloride | 800 | 520 J J | 2800 | 1800 J J |
| Methyl tert-butyl ether | 800 | Not Detected | 2900 | Not Detected |
| trans-1,2-Dichloroethene | 800 | Not Detected | 3200 | Not Detected |
| Hexane | 800 | 1900 | 2800 | 6600 |
| 1,1-Dichloroethane | 800 | Not Detected | 3200 | Not Detected |
| 2-Butanone (Methyl Ethyl Ketone) | 3200 | Not Detected | 9500 | Not Detected |
| cis-1,2-Dichloroethene | 800 | Not Detected | 3200 | Not Detected |
| Tetrahydrofuran | 800 | Not Detected | 2400 | Not Detected |
| Chloroform | 800 | Not Detected | 3900 | Not Detected |
| 1,1,1-Trichloroethane | 800 | Not Detected | 4400 | Not Detected |
| Cyclohexane | 800 | 5800 | 2800 | 20000 |
| Carbon Tetrachloride | 800 | Not Detected | 5100 | Not Detected |
| 2,2,4-Trimethylpentane | 800 | 250000 | 3800 | 1200000 |
| Benzene | 800 | 1800 | 2600 | 5800 |
| 1,2-Dichloroethane | 800 | Not Detected | 3200 | Not Detected |
| Heptane | 800 | Not Detected | 3300 | Not Detected |
| Trichloroethene | 800 | 400 J | 4300 | 2100 J |
| 1,2-Dichloropropane | 800 | 3000 | 3700 | 14000 |
| 1,4-Dioxane | 3200 | Not Detected | 12000 | Not Detected |
| Bromodichloromethane | 800 | Not Detected | 5400 | Not Detected |
| cis-1,3-Dichloropropene | 800 | Not Detected | 3600 | Not Detected |
| 4-Methyl-2-pentanone | 3200 | Not Detected | 13000 | Not Detected |
| Toluene | 800 | Not Detected | 3000 | Not Detected |
| trans-1,3-Dichloropropene | 800 | Not Detected | 3600 | Not Detected |
| 1,1,2-Trichloroethane | 800 | Not Detected | 4400 | Not Detected |
| Tetrachloroethene | 800 | Not Detected | 5500 | Not Detected |
| 2-Hexanone | 3200 | Not Detected | 13000 | Not Detected |

eurofins | Air Toxics

**Client Sample ID: VMP-12-25-021513**

**Lab ID#: 1302355A-01A**

**EPA METHOD TO-15 GC/MS**

| | | | |
|---|---|---|---|
| **File Name:** | **14022730** | **Date of Collection: 2/15/13 11:53:00 AM** | |
| **Dil. Factor:** | **161** | **Date of Analysis: 2/28/13 07:09 AM** | |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Dibromochloromethane | 800 | Not Detected | 6800 | Not Detected |
| 1,2-Dibromoethane (EDB) | 800 | Not Detected | 6200 | Not Detected |
| Chlorobenzene | 800 | Not Detected | 3700 | Not Detected |
| Ethyl Benzene | 800 | Not Detected | 3500 | Not Detected |
| m,p-Xylene | 800 | Not Detected | 3500 | Not Detected |
| o-Xylene | 800 | Not Detected | 3500 | Not Detected |
| Styrene | 800 | Not Detected | 3400 | Not Detected |
| Bromoform | 800 | Not Detected | 8300 | Not Detected |
| Cumene | 800 | Not Detected | 4000 | Not Detected |
| 1,1,2,2-Tetrachloroethane | 800 | Not Detected | 5500 | Not Detected |
| Propylbenzene | 800 | Not Detected | 4000 | Not Detected |
| 4-Ethyltoluene | 800 | Not Detected | 4000 | Not Detected |
| 1,3,5-Trimethylbenzene | 800 | Not Detected | 4000 | Not Detected |
| 1,2,4-Trimethylbenzene | 800 | Not Detected | 4000 | Not Detected |
| 1,3-Dichlorobenzene | 800 | Not Detected | 4800 | Not Detected |
| 1,4-Dichlorobenzene | 800 | Not Detected | 4800 | Not Detected |
| alpha-Chlorotoluene | 800 | Not Detected | 4200 | Not Detected |
| 1,2-Dichlorobenzene | 800 | Not Detected | 4800 | Not Detected |
| 1,2,4-Trichlorobenzene | 3200 | Not Detected | 24000 | Not Detected |
| Hexachlorobutadiene | 3200 | Not Detected | 34000 | Not Detected |
| Butane | 3200 | 22000 | 7600 | 53000 |
| Isopentane | 3200 | 480000 | 9500 | 1400000 |

J = Estimated value.
Q = Exceeds Quality Control limits of 70% to 130%, due to matrix effects.
**Container Type: 1 Liter Summa Canister**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| 1,2-Dichloroethane-d4 | 135 Q | 70-130 |
| Toluene-d8 | 102 | 70-130 |
| 4-Bromofluorobenzene | 101 | 70-130 |

eurofins | Air Toxics

**Client Sample ID: VMP-12-39-021513**

**Lab ID#: 1302355A-02A**

**EPA METHOD TO-15 GC/MS**

| | | | |
|---|---|---|---|
| **File Name:** | **14022810** | **Date of Collection: 2/15/13 10:56:00 AM** | |
| **Dil. Factor:** | **484** | **Date of Analysis: 2/28/13 01:57 PM** | |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 2400 | Not Detected | 12000 | Not Detected |
| Freon 114 | 2400 | Not Detected | 17000 | Not Detected |
| Chloromethane | 9700 | Not Detected | 20000 | Not Detected |
| Vinyl Chloride | 2400 | Not Detected | 6200 | Not Detected |
| 1,3-Butadiene | 2400 | Not Detected | 5400 | Not Detected |
| Bromomethane | 2400 | Not Detected | 9400 | Not Detected |
| Chloroethane | 9700 | 840 J | 26000 | 2200 J |
| Freon 11 | 2400 | Not Detected | 14000 | Not Detected |
| Ethanol | 9700 | Not Detected | 18000 | Not Detected |
| Freon 113 | 2400 | Not Detected | 18000 | Not Detected |
| 1,1-Dichloroethene | 2400 | 260 J | 9600 | 1000 J |
| Acetone | 9700 | Not Detected | 23000 | Not Detected |
| 2-Propanol | 9700 | Not Detected | 24000 | Not Detected |
| Carbon Disulfide | 2400 | Not Detected | 7500 | Not Detected |
| 3-Chloropropene | 9700 | Not Detected | 30000 | Not Detected |
| Methylene Chloride | 2400 | 2700 | 8400 | 9500 |
| Methyl tert-butyl ether | 2400 | Not Detected | 8700 | Not Detected |
| trans-1,2-Dichloroethene | 2400 | Not Detected | 9600 | Not Detected |
| Hexane | 2400 | 64000 | 8500 | 220000 |
| 1,1-Dichloroethane | 2400 | Not Detected | 9800 | Not Detected |
| 2-Butanone (Methyl Ethyl Ketone) | 9700 | Not Detected | 28000 | Not Detected |
| cis-1,2-Dichloroethene | 2400 | Not Detected | 9600 | Not Detected |
| Tetrahydrofuran | 2400 | Not Detected | 7100 | Not Detected |
| Chloroform | 2400 | Not Detected | 12000 | Not Detected |
| 1,1,1-Trichloroethane | 2400 | Not Detected | 13000 | Not Detected |
| Cyclohexane | 2400 | 52000 | 8300 | 180000 |
| Carbon Tetrachloride | 2400 | Not Detected | 15000 | Not Detected |
| 2,2,4-Trimethylpentane | 2400 | 780000 | 11000 | 3600000 |
| Benzene | 2400 | 1300000 | 7700 | 4100000 |
| 1,2-Dichloroethane | 2400 | Not Detected | 9800 | Not Detected |
| Heptane | 2400 | 19000 | 9900 | 78000 |
| Trichloroethene | 2400 | 1200 J | 13000 | 6400 J |
| 1,2-Dichloropropane | 2400 | 4500 | 11000 | 21000 |
| 1,4-Dioxane | 9700 | Not Detected | 35000 | Not Detected |
| Bromodichloromethane | 2400 | Not Detected | 16000 | Not Detected |
| cis-1,3-Dichloropropene | 2400 | Not Detected | 11000 | Not Detected |
| 4-Methyl-2-pentanone | 9700 | Not Detected | 40000 | Not Detected |
| Toluene | 2400 | 810 J | 9100 | 3100 J |
| trans-1,3-Dichloropropene | 2400 | Not Detected | 11000 | Not Detected |
| 1,1,2-Trichloroethane | 2400 | Not Detected | 13000 | Not Detected |
| Tetrachloroethene | 2400 | Not Detected | 16000 | Not Detected |
| 2-Hexanone | 9700 | Not Detected | 40000 | Not Detected |

**Client Sample ID: VMP-12-39-021513**

**Lab ID#: 1302355A-02A**

**EPA METHOD TO-15 GC/MS**

| | | | |
|---|---|---|---|
| **File Name:** | **14022810** | **Date of Collection: 2/15/13 10:56:00 AM** | |
| **Dil. Factor:** | **484** | **Date of Analysis: 2/28/13 01:57 PM** | |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Dibromochloromethane | 2400 | Not Detected | 21000 | Not Detected |
| 1,2-Dibromoethane (EDB) | 2400 | Not Detected | 18000 | Not Detected |
| Chlorobenzene | 2400 | Not Detected | 11000 | Not Detected |
| Ethyl Benzene | 2400 | 9500 | 10000 | 41000 |
| m,p-Xylene | 2400 | 4800 | 10000 | 21000 |
| o-Xylene | 2400 | Not Detected | 10000 | Not Detected |
| Styrene | 2400 | Not Detected | 10000 | Not Detected |
| Bromoform | 2400 | Not Detected | 25000 | Not Detected |
| Cumene | 2400 | 3400 | 12000 | 17000 |
| 1,1,2,2-Tetrachloroethane | 2400 | Not Detected | 17000 | Not Detected |
| Propylbenzene | 2400 | 4000 | 12000 | 20000 |
| 4-Ethyltoluene | 2400 | 1900 J | 12000 | 9200 J |
| 1,3,5-Trimethylbenzene | 2400 | Not Detected | 12000 | Not Detected |
| 1,2,4-Trimethylbenzene | 2400 | 3200 | 12000 | 16000 |
| 1,3-Dichlorobenzene | 2400 | Not Detected | 14000 | Not Detected |
| 1,4-Dichlorobenzene | 2400 | Not Detected | 14000 | Not Detected |
| alpha-Chlorotoluene | 2400 | Not Detected | 12000 | Not Detected |
| 1,2-Dichlorobenzene | 2400 | Not Detected | 14000 | Not Detected |
| 1,2,4-Trichlorobenzene | 9700 | Not Detected | 72000 | Not Detected |
| Hexachlorobutadiene | 9700 | Not Detected | 100000 | Not Detected |
| Butane | 9700 | 140000 | 23000 | 320000 |
| Isopentane | 9700 | 1400000 | 28000 | 4100000 |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| 1,2-Dichloroethane-d4 | 128 | 70-130 |
| Toluene-d8 | 101 | 70-130 |
| 4-Bromofluorobenzene | 98 | 70-130 |

eurofins | Air Toxics

**Client Sample ID: VMP-16-5-021413**

**Lab ID#: 1302355A-03A**

**EPA METHOD TO-15 GC/MS**

| | | | |
|---|---|---|---|
| **File Name:** | **14022731** | **Date of Collection:** | **2/14/13 10:44:00 AM** |
| **Dil. Factor:** | **22.0** | **Date of Analysis:** | **2/28/13 07:46 AM** |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 110 | Not Detected | 540 | Not Detected |
| Freon 114 | 110 | Not Detected | 770 | Not Detected |
| Chloromethane | 440 | Not Detected | 910 | Not Detected |
| Vinyl Chloride | 110 | Not Detected | 280 | Not Detected |
| 1,3-Butadiene | 110 | Not Detected | 240 | Not Detected |
| Bromomethane | 110 | Not Detected | 430 | Not Detected |
| Chloroethane | 440 | Not Detected | 1200 | Not Detected |
| Freon 11 | 110 | Not Detected | 620 | Not Detected |
| Ethanol | 440 | Not Detected | 830 | Not Detected |
| Freon 113 | 110 | Not Detected | 840 | Not Detected |
| 1,1-Dichloroethene | 110 | Not Detected | 440 | Not Detected |
| Acetone | 440 | Not Detected | 1000 | Not Detected |
| 2-Propanol | 440 | Not Detected | 1100 | Not Detected |
| Carbon Disulfide | 110 | Not Detected | 340 | Not Detected |
| 3-Chloropropene | 440 | Not Detected | 1400 | Not Detected |
| Methylene Chloride | 110 | 69 J J | 380 | 240 J J |
| Methyl tert-butyl ether | 110 | Not Detected | 400 | Not Detected |
| trans-1,2-Dichloroethene | 110 | Not Detected | 440 | Not Detected |
| Hexane | 110 | Not Detected | 390 | Not Detected |
| 1,1-Dichloroethane | 110 | Not Detected | 440 | Not Detected |
| 2-Butanone (Methyl Ethyl Ketone) | 440 | Not Detected | 1300 | Not Detected |
| cis-1,2-Dichloroethene | 110 | Not Detected | 440 | Not Detected |
| Tetrahydrofuran | 110 | Not Detected | 320 | Not Detected |
| Chloroform | 110 | Not Detected | 540 | Not Detected |
| 1,1,1-Trichloroethane | 110 | Not Detected | 600 | Not Detected |
| Cyclohexane | 110 | 70 J | 380 | 240 J |
| Carbon Tetrachloride | 110 | Not Detected | 690 | Not Detected |
| 2,2,4-Trimethylpentane | 110 | 63000 | 510 | 290000 |
| Benzene | 110 | 54 J | 350 | 170 J |
| 1,2-Dichloroethane | 110 | Not Detected | 440 | Not Detected |
| Heptane | 110 | Not Detected | 450 | Not Detected |
| Trichloroethene | 110 | 44 J | 590 | 240 J |
| 1,2-Dichloropropane | 110 | 660 | 510 | 3100 |
| 1,4-Dioxane | 440 | Not Detected | 1600 | Not Detected |
| Bromodichloromethane | 110 | Not Detected | 740 | Not Detected |
| cis-1,3-Dichloropropene | 110 | Not Detected | 500 | Not Detected |
| 4-Methyl-2-pentanone | 440 | Not Detected | 1800 | Not Detected |
| Toluene | 110 | Not Detected | 410 | Not Detected |
| trans-1,3-Dichloropropene | 110 | Not Detected | 500 | Not Detected |
| 1,1,2-Trichloroethane | 110 | Not Detected | 600 | Not Detected |
| Tetrachloroethene | 110 | Not Detected | 750 | Not Detected |
| 2-Hexanone | 440 | Not Detected | 1800 | Not Detected |

eurofins | Air Toxics

**Client Sample ID: VMP-16-5-021413**

**Lab ID#: 1302355A-03A**

**EPA METHOD TO-15 GC/MS**

| | | | |
|---|---|---|---|
| **File Name:** | 14022731 | **Date of Collection:** | **2/14/13 10:44:00 AM** |
| **Dil. Factor:** | 22.0 | **Date of Analysis:** | **2/28/13 07:46 AM** |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Dibromochloromethane | 110 | Not Detected | 940 | Not Detected |
| 1,2-Dibromoethane (EDB) | 110 | Not Detected | 840 | Not Detected |
| Chlorobenzene | 110 | Not Detected | 510 | Not Detected |
| Ethyl Benzene | 110 | Not Detected | 480 | Not Detected |
| m,p-Xylene | 110 | Not Detected | 480 | Not Detected |
| o-Xylene | 110 | Not Detected | 480 | Not Detected |
| Styrene | 110 | Not Detected | 470 | Not Detected |
| Bromoform | 110 | Not Detected | 1100 | Not Detected |
| Cumene | 110 | Not Detected | 540 | Not Detected |
| 1,1,2,2-Tetrachloroethane | 110 | Not Detected | 760 | Not Detected |
| Propylbenzene | 110 | Not Detected | 540 | Not Detected |
| 4-Ethyltoluene | 110 | Not Detected | 540 | Not Detected |
| 1,3,5-Trimethylbenzene | 110 | Not Detected | 540 | Not Detected |
| 1,2,4-Trimethylbenzene | 110 | Not Detected | 540 | Not Detected |
| 1,3-Dichlorobenzene | 110 | Not Detected | 660 | Not Detected |
| 1,4-Dichlorobenzene | 110 | Not Detected | 660 | Not Detected |
| alpha-Chlorotoluene | 110 | Not Detected | 570 | Not Detected |
| 1,2-Dichlorobenzene | 110 | Not Detected | 660 | Not Detected |
| 1,2,4-Trichlorobenzene | 440 | Not Detected | 3300 | Not Detected |
| Hexachlorobutadiene | 440 | Not Detected | 4700 | Not Detected |
| Butane | 440 | Not Detected | 1000 | Not Detected |
| Isopentane | 440 | 1800 | 1300 | 5400 |

J = Estimated value.
Q = Exceeds Quality Control limits of 70% to 130%, due to matrix effects.
**Container Type: 1 Liter Summa Canister**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| 1,2-Dichloroethane-d4 | 132 Q | 70-130 |
| Toluene-d8 | 102 | 70-130 |
| 4-Bromofluorobenzene | 99 | 70-130 |

eurofins | Air Toxics

* USE THIS RESULT ONLY. ALL OTHER DATA REPORTED IN 4X DILUTION ANALYSIS.

**Client Sample ID: VMP-16-13.5-021413**
**Lab ID#: 1302355A-04A**
**EPA METHOD TO-15 GC/MS**

| | | | |
|---|---|---|---|
| **File Name:** | **14022807** | **Date of Collection: 2/14/13 11:43:00 AM** | |
| **Dil. Factor:** | **672** | **Date of Analysis: 2/28/13 12:16 PM** | |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 3400 | Not Detected | 17000 | Not Detected |
| Freon 114 | 3400 | Not Detected | 23000 | Not Detected |
| Chloromethane | 13000 | 2400 J | 28000 | 4900 J |
| Vinyl Chloride | 3400 | Not Detected | 8600 | Not Detected |
| 1,3-Butadiene | 3400 | Not Detected | 7400 | Not Detected |
| Bromomethane | 3400 | Not Detected | 13000 | Not Detected |
| Chloroethane | 13000 | Not Detected | 35000 | Not Detected |
| Freon 11 | 3400 | Not Detected | 19000 | Not Detected |
| Ethanol | 13000 | 1600 J | 25000 | 3100 J |
| Freon 113 | 3400 | Not Detected | 26000 | Not Detected |
| 1,1-Dichloroethene | 3400 | Not Detected | 13000 | Not Detected |
| Acetone | 13000 | 2600 J | 32000 | 6300 J |
| 2-Propanol | 13000 | Not Detected | 33000 | Not Detected |
| Carbon Disulfide | 3400 | 570 J | 10000 | 1800 J |
| 3-Chloropropene | 13000 | Not Detected | 42000 | Not Detected |
| Methylene Chloride | 3400 | 2800 J | 12000 | 9600 J |
| Methyl tert-butyl ether | 3400 | 620 J | 12000 | 2200 J |
| trans-1,2-Dichloroethene | 3400 | Not Detected | 13000 | Not Detected |
| Hexane | 3400 | 980 J | 12000 | 3400 J |
| 1,1-Dichloroethane | 3400 | Not Detected | 14000 | Not Detected |
| 2-Butanone (Methyl Ethyl Ketone) | 13000 | Not Detected | 40000 | Not Detected |
| cis-1,2-Dichloroethene | 3400 | Not Detected | 13000 | Not Detected |
| Tetrahydrofuran | 3400 | Not Detected | 9900 | Not Detected |
| Chloroform | 3400 | Not Detected | 16000 | Not Detected |
| 1,1,1-Trichloroethane | 3400 | Not Detected | 18000 | Not Detected |
| Cyclohexane | 3400 | 40000 | 12000 | 140000 |
| Carbon Tetrachloride | 3400 | Not Detected | 21000 | Not Detected |
| * 2,2,4-Trimethylpentane | 3400 | 2400000 | 16000 | 11000000 |
| Benzene | 3400 | 5900 | 11000 | 19000 |
| 1,2-Dichloroethane | 3400 | Not Detected | 14000 | Not Detected |
| Heptane | 3400 | Not Detected | 14000 | Not Detected |
| Trichloroethene | 3400 | 940 J | 18000 | 5100 J |
| 1,2-Dichloropropane | 3400 | 5600 | 16000 | 26000 |
| 1,4-Dioxane | 13000 | Not Detected | 48000 | Not Detected |
| Bromodichloromethane | 3400 | Not Detected | 22000 | Not Detected |
| cis-1,3-Dichloropropene | 3400 | Not Detected | 15000 | Not Detected |
| 4-Methyl-2-pentanone | 13000 | Not Detected | 55000 | Not Detected |
| Toluene | 3400 | 410 J | 13000 | 1500 J |
| trans-1,3-Dichloropropene | 3400 | Not Detected | 15000 | Not Detected |
| 1,1,2-Trichloroethane | 3400 | Not Detected | 18000 | Not Detected |
| Tetrachloroethene | 3400 | Not Detected | 23000 | Not Detected |
| 2-Hexanone | 13000 | Not Detected | 55000 | Not Detected |

eurofins | Air Toxics

**Client Sample ID: VMP-16-13.5-021413**

**Lab ID#: 1302355A-04A**

**EPA METHOD TO-15 GC/MS**

| | | | |
|---|---|---|---|
| **File Name:** | **14022807** | **Date of Collection:** | **2/14/13 11:43:00 AM** |
| **Dil. Factor:** | **672** | **Date of Analysis:** | **2/28/13 12:16 PM** |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Dibromochloromethane | 3400 | Not Detected | 29000 | Not Detected |
| 1,2-Dibromoethane (EDB) | 3400 | Not Detected | 26000 | Not Detected |
| Chlorobenzene | 3400 | Not Detected | 15000 | Not Detected |
| Ethyl Benzene | 3400 | 640 J | 14000 | 2800 J |
| m,p-Xylene | 3400 | Not Detected | 14000 | Not Detected |
| o-Xylene | 3400 | Not Detected | 14000 | Not Detected |
| Styrene | 3400 | Not Detected | 14000 | Not Detected |
| Bromoform | 3400 | Not Detected | 35000 | Not Detected |
| Cumene | 3400 | 670 J | 16000 | 3300 J |
| 1,1,2,2-Tetrachloroethane | 3400 | Not Detected | 23000 | Not Detected |
| Propylbenzene | 3400 | 1300 J | 16000 | 6500 J |
| 4-Ethyltoluene | 3400 | Not Detected | 16000 | Not Detected |
| 1,3,5-Trimethylbenzene | 3400 | Not Detected | 16000 | Not Detected |
| 1,2,4-Trimethylbenzene | 3400 | Not Detected | 16000 | Not Detected |
| 1,3-Dichlorobenzene | 3400 | Not Detected | 20000 | Not Detected |
| 1,4-Dichlorobenzene | 3400 | Not Detected | 20000 | Not Detected |
| alpha-Chlorotoluene | 3400 | Not Detected | 17000 | Not Detected |
| 1,2-Dichlorobenzene | 3400 | Not Detected | 20000 | Not Detected |
| 1,2,4-Trichlorobenzene | 13000 | Not Detected | 100000 | Not Detected |
| Hexachlorobutadiene | 13000 | Not Detected | 140000 | Not Detected |
| Butane | 13000 | 33000 | 32000 | 79000 |
| Isopentane | 13000 | 580000 | 40000 | 1700000 |

J = Estimated value.
Q = Exceeds Quality Control limits of 70% to 130%, due to matrix effects.
**Container Type: 1 Liter Summa Canister**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| 1,2-Dichloroethane-d4 | 132 Q | 70-130 |
| Toluene-d8 | 101 | 70-130 |
| 4-Bromofluorobenzene | 99 | 70-130 |

eurofins | Air Toxics

**Client Sample ID: VMP-16-13.5-021413**

* DO NOT USE THIS DATA. USE ALL OTHER DATA.

**Lab ID#: 1302355A-04B**

**EPA METHOD TO-15 GC/MS**

| | | | |
|---|---|---|---|
| **File Name:** | **14022733** | **Date of Collection: 2/14/13 11:43:00 AM** | |
| **Dil. Factor:** | **448** | **Date of Analysis: 2/28/13 08:36 AM** | |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 2200 | Not Detected | 11000 | Not Detected |
| Freon 114 | 2200 | Not Detected | 16000 | Not Detected |
| Chloromethane | 9000 | Not Detected | 18000 | Not Detected |
| Vinyl Chloride | 2200 | Not Detected | 5700 | Not Detected |
| 1,3-Butadiene | 2200 | Not Detected | 5000 | Not Detected |
| Bromomethane | 2200 | Not Detected | 8700 | Not Detected |
| Chloroethane | 9000 | Not Detected | 24000 | Not Detected |
| Freon 11 | 2200 | Not Detected | 12000 | Not Detected |
| Ethanol | 9000 | Not Detected | 17000 | Not Detected |
| Freon 113 | 2200 | 390 J | 17000 | 3000 J |
| 1,1-Dichloroethene | 2200 | 430 J | 8900 | 1700 J |
| Acetone | 9000 | 2200 J | 21000 | 5300 J |
| 2-Propanol | 9000 | Not Detected | 22000 | Not Detected |
| Carbon Disulfide | 2200 | 740 J | 7000 | 2300 J |
| 3-Chloropropene | 9000 | Not Detected | 28000 | Not Detected |
| Methylene Chloride | 2200 | 3400 J | 7800 | 12000 J |
| Methyl tert-butyl ether | 2200 | 590 J | 8100 | 2100 J |
| trans-1,2-Dichloroethene | 2200 | Not Detected | 8900 | Not Detected |
| Hexane | 2200 | 1700 J | 7900 | 6100 J |
| 1,1-Dichloroethane | 2200 | Not Detected | 9100 | Not Detected |
| 2-Butanone (Methyl Ethyl Ketone) | 9000 | Not Detected | 26000 | Not Detected |
| cis-1,2-Dichloroethene | 2200 | Not Detected | 8900 | Not Detected |
| Tetrahydrofuran | 2200 | Not Detected | 6600 | Not Detected |
| Chloroform | 2200 | Not Detected | 11000 | Not Detected |
| 1,1,1-Trichloroethane | 2200 | Not Detected | 12000 | Not Detected |
| Cyclohexane | 2200 | 38000 | 7700 | 130000 |
| Carbon Tetrachloride | 2200 | Not Detected | 14000 | Not Detected |
| * ~~2,2,4-Trimethylpentane~~ | ~~2200~~ | ~~2400000 E~~ | ~~10000~~ | ~~11000000 E~~ |
| Benzene | 2200 | 6600 | 7200 | 21000 |
| 1,2-Dichloroethane | 2200 | Not Detected | 9100 | Not Detected |
| Heptane | 2200 | Not Detected | 9200 | Not Detected |
| Trichloroethene | 2200 | 3400 | 12000 | 18000 |
| 1,2-Dichloropropane | 2200 | 10000 | 10000 | 48000 |
| 1,4-Dioxane | 9000 | Not Detected | 32000 | Not Detected |
| Bromodichloromethane | 2200 | Not Detected | 15000 | Not Detected |
| cis-1,3-Dichloropropene | 2200 | Not Detected | 10000 | Not Detected |
| 4-Methyl-2-pentanone | 9000 | Not Detected | 37000 | Not Detected |
| Toluene | 2200 | 740 J | 8400 | 2800 J |
| trans-1,3-Dichloropropene | 2200 | Not Detected | 10000 | Not Detected |
| 1,1,2-Trichloroethane | 2200 | Not Detected | 12000 | Not Detected |
| Tetrachloroethene | 2200 | Not Detected | 15000 | Not Detected |
| 2-Hexanone | 9000 | Not Detected | 37000 | Not Detected |

eurofins | Air Toxics

**Client Sample ID: VMP-16-13.5-021413**

**Lab ID#: 1302355A-04B**

**EPA METHOD TO-15 GC/MS**

| | | | |
|---|---|---|---|
| **File Name:** | **14022733** | **Date of Collection:** | **2/14/13 11:43:00 AM** |
| **Dil. Factor:** | **448** | **Date of Analysis:** | **2/28/13 08:36 AM** |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Dibromochloromethane | 2200 | Not Detected | 19000 | Not Detected |
| 1,2-Dibromoethane (EDB) | 2200 | Not Detected | 17000 | Not Detected |
| Chlorobenzene | 2200 | Not Detected | 10000 | Not Detected |
| Ethyl Benzene | 2200 | 920 J | 9700 | 4000 J |
| m,p-Xylene | 2200 | 500 J | 9700 | 2200 J |
| o-Xylene | 2200 | Not Detected | 9700 | Not Detected |
| Styrene | 2200 | Not Detected | 9500 | Not Detected |
| Bromoform | 2200 | Not Detected | 23000 | Not Detected |
| Cumene | 2200 | 820 J | 11000 | 4000 J |
| 1,1,2,2-Tetrachloroethane | 2200 | Not Detected | 15000 | Not Detected |
| Propylbenzene | 2200 | 1600 J | 11000 | 7800 J |
| 4-Ethyltoluene | 2200 | Not Detected | 11000 | Not Detected |
| 1,3,5-Trimethylbenzene | 2200 | Not Detected | 11000 | Not Detected |
| 1,2,4-Trimethylbenzene | 2200 | Not Detected | 11000 | Not Detected |
| 1,3-Dichlorobenzene | 2200 | Not Detected | 13000 | Not Detected |
| 1,4-Dichlorobenzene | 2200 | Not Detected | 13000 | Not Detected |
| alpha-Chlorotoluene | 2200 | Not Detected | 12000 | Not Detected |
| 1,2-Dichlorobenzene | 2200 | Not Detected | 13000 | Not Detected |
| 1,2,4-Trichlorobenzene | 9000 | Not Detected | 66000 | Not Detected |
| Hexachlorobutadiene | 9000 | Not Detected | 96000 | Not Detected |
| Butane | 9000 | 39000 | 21000 | 92000 |
| Isopentane | 9000 | 610000 | 26000 | 1800000 |

J = Estimated value.
E = Exceeds instrument calibration range.
Q = Exceeds Quality Control limits of 70% to 130%, due to matrix effects.
**Container Type: 1 Liter Summa Canister**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| 1,2-Dichloroethane-d4 | 147 Q | 70-130 |
| Toluene-d8 | 102 | 70-130 |
| 4-Bromofluorobenzene | 98 | 70-130 |

eurofins | Air Toxics

**Client Sample ID: VMP-16-19-021413**
**Lab ID#: 1302355A-05A**
**EPA METHOD TO-15 GC/MS**

* USE THIS DATA ONLY. ALL OTHER DATA REPORTED IN 264X DILUTION ANALYSIS.

| | | | |
|---|---|---|---|
| **File Name:** | **14022808** | **Date of Collection:** | **2/14/13 2:20:00 PM** |
| **Dil. Factor:** | **825** | **Date of Analysis:** | **2/28/13 12:47 PM** |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 4100 | Not Detected | 20000 | Not Detected |
| Freon 114 | 4100 | Not Detected | 29000 | Not Detected |
| Chloromethane | 16000 | 4100 J | 34000 | 8500 J |
| Vinyl Chloride | 4100 | Not Detected | 10000 | Not Detected |
| 1,3-Butadiene | 4100 | Not Detected | 9100 | Not Detected |
| Bromomethane | 4100 | Not Detected | 16000 | Not Detected |
| Chloroethane | 16000 | Not Detected | 44000 | Not Detected |
| Freon 11 | 4100 | Not Detected | 23000 | Not Detected |
| Ethanol | 16000 | Not Detected | 31000 | Not Detected |
| Freon 113 | 4100 | Not Detected | 32000 | Not Detected |
| 1,1-Dichloroethene | 4100 | Not Detected | 16000 | Not Detected |
| Acetone | 16000 | 3100 J | 39000 | 7300 J |
| 2-Propanol | 16000 | Not Detected | 40000 | Not Detected |
| Carbon Disulfide | 4100 | 750 J | 13000 | 2300 J |
| 3-Chloropropene | 16000 | Not Detected | 52000 | Not Detected |
| Methylene Chloride | 4100 | 3000 J | 14000 | 10000 J |
| Methyl tert-butyl ether | 4100 | 1100 J | 15000 | 4000 J |
| trans-1,2-Dichloroethene | 4100 | Not Detected | 16000 | Not Detected |
| Hexane | 4100 | 740 J | 14000 | 2600 J |
| 1,1-Dichloroethane | 4100 | Not Detected | 17000 | Not Detected |
| 2-Butanone (Methyl Ethyl Ketone) | 16000 | Not Detected | 49000 | Not Detected |
| cis-1,2-Dichloroethene | 4100 | Not Detected | 16000 | Not Detected |
| Tetrahydrofuran | 4100 | Not Detected | 12000 | Not Detected |
| Chloroform | 4100 | Not Detected | 20000 | Not Detected |
| 1,1,1-Trichloroethane | 4100 | Not Detected | 22000 | Not Detected |
| Cyclohexane | 4100 | 53000 | 14000 | 180000 |
| Carbon Tetrachloride | 4100 | Not Detected | 26000 | Not Detected |
| 2,2,4-Trimethylpentane | 4100 | 2400000 | 19000 | 11000000 |
| Benzene | 4100 | 4900 | 13000 | 16000 |
| 1,2-Dichloroethane | 4100 | Not Detected | 17000 | Not Detected |
| Heptane | 4100 | Not Detected | 17000 | Not Detected |
| Trichloroethene | 4100 | 1500 J | 22000 | 8000 J |
| 1,2-Dichloropropane | 4100 | 6000 | 19000 | 28000 |
| 1,4-Dioxane | 16000 | Not Detected | 59000 | Not Detected |
| Bromodichloromethane | 4100 | Not Detected | 28000 | Not Detected |
| cis-1,3-Dichloropropene | 4100 | Not Detected | 19000 | Not Detected |
| 4-Methyl-2-pentanone | 16000 | Not Detected | 68000 | Not Detected |
| Toluene | 4100 | Not Detected | 16000 | Not Detected |
| trans-1,3-Dichloropropene | 4100 | Not Detected | 19000 | Not Detected |
| 1,1,2-Trichloroethane | 4100 | Not Detected | 22000 | Not Detected |
| Tetrachloroethene | 4100 | Not Detected | 28000 | Not Detected |
| 2-Hexanone | 16000 | Not Detected | 68000 | Not Detected |

**Client Sample ID: VMP-16-19-021413**

**Lab ID#: 1302355A-05A**

**EPA METHOD TO-15 GC/MS**

| | | | |
|---|---|---|---|
| **File Name:** | **14022808** | **Date of Collection:** | **2/14/13 2:20:00 PM** |
| **Dil. Factor:** | **825** | **Date of Analysis:** | **2/28/13 12:47 PM** |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Dibromochloromethane | 4100 | Not Detected | 35000 | Not Detected |
| 1,2-Dibromoethane (EDB) | 4100 | Not Detected | 32000 | Not Detected |
| Chlorobenzene | 4100 | Not Detected | 19000 | Not Detected |
| Ethyl Benzene | 4100 | 17000 | 18000 | 76000 |
| m,p-Xylene | 4100 | 6300 | 18000 | 28000 |
| o-Xylene | 4100 | Not Detected | 18000 | Not Detected |
| Styrene | 4100 | Not Detected | 18000 | Not Detected |
| Bromoform | 4100 | Not Detected | 43000 | Not Detected |
| Cumene | 4100 | 5600 | 20000 | 28000 |
| 1,1,2,2-Tetrachloroethane | 4100 | Not Detected | 28000 | Not Detected |
| Propylbenzene | 4100 | 11000 | 20000 | 52000 |
| 4-Ethyltoluene | 4100 | 2500 J | 20000 | 12000 J |
| 1,3,5-Trimethylbenzene | 4100 | Not Detected | 20000 | Not Detected |
| 1,2,4-Trimethylbenzene | 4100 | 3600 J | 20000 | 18000 J |
| 1,3-Dichlorobenzene | 4100 | Not Detected | 25000 | Not Detected |
| 1,4-Dichlorobenzene | 4100 | Not Detected | 25000 | Not Detected |
| alpha-Chlorotoluene | 4100 | Not Detected | 21000 | Not Detected |
| 1,2-Dichlorobenzene | 4100 | Not Detected | 25000 | Not Detected |
| 1,2,4-Trichlorobenzene | 16000 | Not Detected | 120000 | Not Detected |
| Hexachlorobutadiene | 16000 | Not Detected | 180000 | Not Detected |
| Butane | 16000 | 96000 | 39000 | 230000 |
| Isopentane | 16000 | 1200000 | 49000 | 3600000 |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| 1,2-Dichloroethane-d4 | 129 | 70-130 |
| Toluene-d8 | 102 | 70-130 |
| 4-Bromofluorobenzene | 97 | 70-130 |

eurofins | Air Toxics

**Client Sample ID: VMP-16-19-021413** DO NOT USE THIS DATA, USE ALL OTHER DATA.

**Lab ID#: 1302355A-05B**

**EPA METHOD TO-15 GC/MS**

| | | | |
|---|---|---|---|
| **File Name:** | **14022732** | **Date of Collection: 2/14/13 2:20:00 PM** | |
| **Dil. Factor:** | **264** | **Date of Analysis: 2/28/13 08:10 AM** | |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 1300 | Not Detected | 6500 | Not Detected |
| Freon 114 | 1300 | Not Detected | 9200 | Not Detected |
| Chloromethane | 5300 | Not Detected | 11000 | Not Detected |
| Vinyl Chloride | 1300 | Not Detected | 3400 | Not Detected |
| 1,3-Butadiene | 1300 | Not Detected | 2900 | Not Detected |
| Bromomethane | 1300 | Not Detected | 5100 | Not Detected |
| Chloroethane | 5300 | Not Detected | 14000 | Not Detected |
| Freon 11 | 1300 | Not Detected | 7400 | Not Detected |
| Ethanol | 5300 | Not Detected | 9900 | Not Detected |
| Freon 113 | 1300 | Not Detected | 10000 | Not Detected |
| 1,1-Dichloroethene | 1300 | Not Detected | 5200 | Not Detected |
| Acetone | 5300 | Not Detected | 12000 | Not Detected |
| 2-Propanol | 5300 | Not Detected | 13000 | Not Detected |
| Carbon Disulfide | 1300 | Not Detected | 4100 | Not Detected |
| 3-Chloropropene | 5300 | Not Detected | 16000 | Not Detected |
| Methylene Chloride | 1300 | 990 J | 4600 | 3400 J |
| Methyl tert-butyl ether | 1300 | 1200 J | 4800 | 4500 J |
| trans-1,2-Dichloroethene | 1300 | Not Detected | 5200 | Not Detected |
| Hexane | 1300 | 1100 J | 4600 | 4000 J |
| 1,1-Dichloroethane | 1300 | Not Detected | 5300 | Not Detected |
| 2-Butanone (Methyl Ethyl Ketone) | 5300 | Not Detected | 16000 | Not Detected |
| cis-1,2-Dichloroethene | 1300 | Not Detected | 5200 | Not Detected |
| Tetrahydrofuran | 1300 | Not Detected | 3900 | Not Detected |
| Chloroform | 1300 | Not Detected | 6400 | Not Detected |
| 1,1,1-Trichloroethane | 1300 | Not Detected | 7200 | Not Detected |
| Cyclohexane | 1300 | 61000 J | 4500 | 210000 J |
| Carbon Tetrachloride | 1300 | Not Detected | 8300 | Not Detected |
| ~~2,2,4-Trimethylpentane~~ | ~~1300~~ | ~~2700000 E~~ | ~~6200~~ | ~~13000000 E~~ |
| Benzene | 1300 | 5300 J | 4200 | 17000 J |
| 1,2-Dichloroethane | 1300 | Not Detected | 5300 | Not Detected |
| Heptane | 1300 | Not Detected | 5400 | Not Detected |
| Trichloroethene | 1300 | Not Detected | 7100 | Not Detected |
| 1,2-Dichloropropane | 1300 | 4600 J | 6100 | 21000 J |
| 1,4-Dioxane | 5300 | Not Detected | 19000 | Not Detected |
| Bromodichloromethane | 1300 | Not Detected | 8800 | Not Detected |
| cis-1,3-Dichloropropene | 1300 | Not Detected | 6000 | Not Detected |
| 4-Methyl-2-pentanone | 5300 | Not Detected | 22000 | Not Detected |
| Toluene | 1300 | 220 J | 5000 | 830 J |
| trans-1,3-Dichloropropene | 1300 | Not Detected | 6000 | Not Detected |
| 1,1,2-Trichloroethane | 1300 | Not Detected | 7200 | Not Detected |
| Tetrachloroethene | 1300 | Not Detected | 9000 | Not Detected |
| 2-Hexanone | 5300 | Not Detected | 22000 | Not Detected |

eurofins | Air Toxics

**Client Sample ID: VMP-16-19-021413**

**Lab ID#: 1302355A-05B**

**EPA METHOD TO-15 GC/MS**

| | | | |
|---|---|---|---|
| **File Name:** | **14022732** | **Date of Collection: 2/14/13 2:20:00 PM** | |
| **Dil. Factor:** | **264** | **Date of Analysis: 2/28/13 08:10 AM** | |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Dibromochloromethane | 1300 | Not Detected | 11000 | Not Detected |
| 1,2-Dibromoethane (EDB) | 1300 | Not Detected | 10000 | Not Detected |
| Chlorobenzene | 1300 | Not Detected | 6100 | Not Detected |
| Ethyl Benzene | 1300 | 20000 J | 5700 | 88000 J |
| m,p-Xylene | 1300 | 6000 J | 5700 | 26000 J |
| o-Xylene | 1300 | 150 J J | 5700 | 640 J J |
| Styrene | 1300 | Not Detected | 5600 | Not Detected |
| Bromoform | 1300 | Not Detected | 14000 | Not Detected |
| Cumene | 1300 | 5500 J | 6500 | 27000 J |
| 1,1,2,2-Tetrachloroethane | 1300 | Not Detected | 9100 | Not Detected |
| Propylbenzene | 1300 | 9200 J J | 6500 | 45000 J J |
| 4-Ethyltoluene | 1300 | 1800 J J | 6500 | 8800 J J |
| 1,3,5-Trimethylbenzene | 1300 | 800 J J | 6500 | 3900 J J |
| 1,2,4-Trimethylbenzene | 1300 | 2600 J J | 6500 | 13000 J J |
| 1,3-Dichlorobenzene | 1300 | Not Detected | 7900 | Not Detected |
| 1,4-Dichlorobenzene | 1300 | Not Detected | 7900 | Not Detected |
| alpha-Chlorotoluene | 1300 | Not Detected | 6800 | Not Detected |
| 1,2-Dichlorobenzene | 1300 | Not Detected | 7900 | Not Detected |
| 1,2,4-Trichlorobenzene | 5300 | Not Detected | 39000 | Not Detected |
| Hexachlorobutadiene | 5300 | Not Detected | 56000 | Not Detected |
| Butane | 5300 | 100000 J | 12000 | 240000 J |
| Isopentane | 5300 | 1300000 J | 16000 | 3800000 J |

J = Estimated value.
E = Exceeds instrument calibration range.
Q = Exceeds Quality Control limits of 70% to 130%, due to matrix effects.
**Container Type: 1 Liter Summa Canister**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| 1,2-Dichloroethane-d4 | 160 Q | 70-130 |
| Toluene-d8 | 102 | 70-130 |
| 4-Bromofluorobenzene | 101 | 70-130 |

eurofins | Air Toxics

**Client Sample ID: VMP-16-31-021813**

**Lab ID#: 1302355A-06A**

**EPA METHOD TO-15 GC/MS**

| | | | |
|---|---|---|---|
| **File Name:** | **14022811** | **Date of Collection:** | **2/18/13 3:02:00 PM** |
| **Dil. Factor:** | **997** | **Date of Analysis:** | **2/28/13 02:23 PM** |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 5000 | Not Detected | 25000 | Not Detected |
| Freon 114 | 5000 | Not Detected | 35000 | Not Detected |
| Chloromethane | 20000 | Not Detected | 41000 | Not Detected |
| Vinyl Chloride | 5000 | Not Detected | 13000 | Not Detected |
| 1,3-Butadiene | 5000 | Not Detected | 11000 | Not Detected |
| Bromomethane | 5000 | Not Detected | 19000 | Not Detected |
| Chloroethane | 20000 | Not Detected | 53000 | Not Detected |
| Freon 11 | 5000 | Not Detected | 28000 | Not Detected |
| Ethanol | 20000 | Not Detected | 38000 | Not Detected |
| Freon 113 | 5000 | Not Detected | 38000 | Not Detected |
| 1,1-Dichloroethene | 5000 | Not Detected | 20000 | Not Detected |
| Acetone | 20000 | Not Detected | 47000 | Not Detected |
| 2-Propanol | 20000 | Not Detected | 49000 | Not Detected |
| Carbon Disulfide | 5000 | Not Detected | 16000 | Not Detected |
| 3-Chloropropene | 20000 | Not Detected | 62000 | Not Detected |
| Methylene Chloride | 5000 | 3600 J | 17000 | 12000 J |
| Methyl tert-butyl ether | 5000 | 1100 J | 18000 | 4100 J |
| trans-1,2-Dichloroethene | 5000 | Not Detected | 20000 | Not Detected |
| Hexane | 5000 | 860 J | 18000 | 3000 J |
| 1,1-Dichloroethane | 5000 | Not Detected | 20000 | Not Detected |
| 2-Butanone (Methyl Ethyl Ketone) | 20000 | Not Detected | 59000 | Not Detected |
| cis-1,2-Dichloroethene | 5000 | Not Detected | 20000 | Not Detected |
| Tetrahydrofuran | 5000 | Not Detected | 15000 | Not Detected |
| Chloroform | 5000 | Not Detected | 24000 | Not Detected |
| 1,1,1-Trichloroethane | 5000 | Not Detected | 27000 | Not Detected |
| Cyclohexane | 5000 | 75000 | 17000 | 260000 |
| Carbon Tetrachloride | 5000 | Not Detected | 31000 | Not Detected |
| 2,2,4-Trimethylpentane | 5000 | 2700000 | 23000 | 13000000 |
| Benzene | 5000 | 9000 | 16000 | 29000 |
| 1,2-Dichloroethane | 5000 | Not Detected | 20000 | Not Detected |
| Heptane | 5000 | Not Detected | 20000 | Not Detected |
| Trichloroethene | 5000 | Not Detected | 27000 | Not Detected |
| 1,2-Dichloropropane | 5000 | 5400 | 23000 | 25000 |
| 1,4-Dioxane | 20000 | Not Detected | 72000 | Not Detected |
| Bromodichloromethane | 5000 | Not Detected | 33000 | Not Detected |
| cis-1,3-Dichloropropene | 5000 | Not Detected | 23000 | Not Detected |
| 4-Methyl-2-pentanone | 20000 | Not Detected | 82000 | Not Detected |
| Toluene | 5000 | Not Detected | 19000 | Not Detected |
| trans-1,3-Dichloropropene | 5000 | Not Detected | 23000 | Not Detected |
| 1,1,2-Trichloroethane | 5000 | Not Detected | 27000 | Not Detected |
| Tetrachloroethene | 5000 | Not Detected | 34000 | Not Detected |
| 2-Hexanone | 20000 | Not Detected | 82000 | Not Detected |

eurofins | Air Toxics

**Client Sample ID: VMP-16-31-021813**

**Lab ID#: 1302355A-06A**

**EPA METHOD TO-15 GC/MS**

| | | | |
|---|---|---|---|
| **File Name:** | **14022811** | **Date of Collection: 2/18/13 3:02:00 PM** | |
| **Dil. Factor:** | **997** | **Date of Analysis: 2/28/13 02:23 PM** | |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Dibromochloromethane | 5000 | Not Detected | 42000 | Not Detected |
| 1,2-Dibromoethane (EDB) | 5000 | Not Detected | 38000 | Not Detected |
| Chlorobenzene | 5000 | Not Detected | 23000 | Not Detected |
| Ethyl Benzene | 5000 | 9900 | 22000 | 43000 |
| m,p-Xylene | 5000 | Not Detected | 22000 | Not Detected |
| o-Xylene | 5000 | Not Detected | 22000 | Not Detected |
| Styrene | 5000 | Not Detected | 21000 | Not Detected |
| Bromoform | 5000 | Not Detected | 52000 | Not Detected |
| Cumene | 5000 | 4200 J | 24000 | 21000 J |
| 1,1,2,2-Tetrachloroethane | 5000 | Not Detected | 34000 | Not Detected |
| Propylbenzene | 5000 | 7400 | 24000 | 36000 |
| 4-Ethyltoluene | 5000 | Not Detected | 24000 | Not Detected |
| 1,3,5-Trimethylbenzene | 5000 | Not Detected | 24000 | Not Detected |
| 1,2,4-Trimethylbenzene | 5000 | Not Detected | 24000 | Not Detected |
| 1,3-Dichlorobenzene | 5000 | Not Detected | 30000 | Not Detected |
| 1,4-Dichlorobenzene | 5000 | Not Detected | 30000 | Not Detected |
| alpha-Chlorotoluene | 5000 | Not Detected | 26000 | Not Detected |
| 1,2-Dichlorobenzene | 5000 | Not Detected | 30000 | Not Detected |
| 1,2,4-Trichlorobenzene | 20000 | Not Detected | 150000 | Not Detected |
| Hexachlorobutadiene | 20000 | Not Detected | 210000 | Not Detected |
| Butane | 20000 | 120000 | 47000 | 290000 |
| Isopentane | 20000 | 1500000 | 59000 | 4600000 |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| 1,2-Dichloroethane-d4 | 129 | 70-130 |
| Toluene-d8 | 100 | 70-130 |
| 4-Bromofluorobenzene | 98 | 70-130 |

eurofins | Air Toxics

**Client Sample ID: VMP-55-20-021513**

**Lab ID#: 1302355A-07A**

**EPA METHOD TO-15 GC/MS**

| | | | |
|---|---|---|---|
| **File Name:** | **14022809** | **Date of Collection:** | **2/15/13 10:45:00 AM** |
| **Dil. Factor:** | **690** | **Date of Analysis:** | **2/26/13 01:30 PM** |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 3400 | Not Detected | 17000 | Not Detected |
| Freon 114 | 3400 | Not Detected | 24000 | Not Detected |
| Chloromethane | 14000 | Not Detected | 28000 | Not Detected |
| Vinyl Chloride | 3400 | Not Detected | 8800 | Not Detected |
| 1,3-Butadiene | 3400 | Not Detected | 7600 | Not Detected |
| Bromomethane | 3400 | Not Detected | 13000 | Not Detected |
| Chloroethane | 14000 | Not Detected | 36000 | Not Detected |
| Freon 11 | 3400 | Not Detected | 19000 | Not Detected |
| Ethanol | 14000 | Not Detected | 26000 | Not Detected |
| Freon 113 | 3400 | Not Detected | 26000 | Not Detected |
| 1,1-Dichloroethene | 3400 | Not Detected | 14000 | Not Detected |
| Acetone | 14000 | Not Detected | 33000 | Not Detected |
| 2-Propanol | 14000 | Not Detected | 34000 | Not Detected |
| Carbon Disulfide | 3400 | Not Detected | 11000 | Not Detected |
| 3-Chloropropene | 14000 | Not Detected | 43000 | Not Detected |
| Methylene Chloride | 3400 | 4100 | 12000 | 14000 |
| Methyl tert-butyl ether | 3400 | Not Detected | 12000 | Not Detected |
| trans-1,2-Dichloroethene | 3400 | Not Detected | 14000 | Not Detected |
| Hexane | 3400 | 12000 | 12000 | 42000 |
| 1,1-Dichloroethane | 3400 | Not Detected | 14000 | Not Detected |
| 2-Butanone (Methyl Ethyl Ketone) | 14000 | Not Detected | 41000 | Not Detected |
| cis-1,2-Dichloroethene | 3400 | Not Detected | 14000 | Not Detected |
| Tetrahydrofuran | 3400 | Not Detected | 10000 | Not Detected |
| Chloroform | 3400 | Not Detected | 17000 | Not Detected |
| 1,1,1-Trichloroethane | 3400 | Not Detected | 19000 | Not Detected |
| Cyclohexane | 3400 | 66000 | 12000 | 230000 |
| Carbon Tetrachloride | 3400 | Not Detected | 22000 | Not Detected |
| 2,2,4-Trimethylpentane | 3400 | 79000 | 16000 | 370000 |
| Benzene | 3400 | 410 J | 11000 | 1300 J |
| 1,2-Dichloroethane | 3400 | Not Detected | 14000 | Not Detected |
| Heptane | 3400 | Not Detected | 14000 | Not Detected |
| Trichloroethene | 3400 | 1000 J | 18000 | 5500 J |
| 1,2-Dichloropropane | 3400 | 4200 | 16000 | 19000 |
| 1,4-Dioxane | 14000 | Not Detected | 50000 | Not Detected |
| Bromodichloromethane | 3400 | Not Detected | 23000 | Not Detected |
| cis-1,3-Dichloropropene | 3400 | Not Detected | 16000 | Not Detected |
| 4-Methyl-2-pentanone | 14000 | Not Detected | 56000 | Not Detected |
| Toluene | 3400 | Not Detected | 13000 | Not Detected |
| trans-1,3-Dichloropropene | 3400 | Not Detected | 16000 | Not Detected |
| 1,1,2-Trichloroethane | 3400 | Not Detected | 19000 | Not Detected |
| Tetrachloroethene | 3400 | Not Detected | 23000 | Not Detected |
| 2-Hexanone | 14000 | Not Detected | 56000 | Not Detected |

**Client Sample ID: VMP-55-20-021513**

**Lab ID#: 1302355A-07A**

**EPA METHOD TO-15 GC/MS**

| | | | |
|---|---|---|---|
| **File Name:** | **14022809** | **Date of Collection:** | **2/15/13 10:45:00 AM** |
| **Dil. Factor:** | **690** | **Date of Analysis:** | **2/28/13 01:30 PM** |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Dibromochloromethane | 3400 | Not Detected | 29000 | Not Detected |
| 1,2-Dibromoethane (EDB) | 3400 | Not Detected | 26000 | Not Detected |
| Chlorobenzene | 3400 | Not Detected | 16000 | Not Detected |
| Ethyl Benzene | 3400 | Not Detected | 15000 | Not Detected |
| m,p-Xylene | 3400 | Not Detected | 15000 | Not Detected |
| o-Xylene | 3400 | Not Detected | 15000 | Not Detected |
| Styrene | 3400 | Not Detected | 15000 | Not Detected |
| Bromoform | 3400 | Not Detected | 36000 | Not Detected |
| Cumene | 3400 | Not Detected | 17000 | Not Detected |
| 1,1,2,2-Tetrachloroethane | 3400 | Not Detected | 24000 | Not Detected |
| Propylbenzene | 3400 | Not Detected | 17000 | Not Detected |
| 4-Ethyltoluene | 3400 | Not Detected | 17000 | Not Detected |
| 1,3,5-Trimethylbenzene | 3400 | Not Detected | 17000 | Not Detected |
| 1,2,4-Trimethylbenzene | 3400 | Not Detected | 17000 | Not Detected |
| 1,3-Dichlorobenzene | 3400 | Not Detected | 21000 | Not Detected |
| 1,4-Dichlorobenzene | 3400 | Not Detected | 21000 | Not Detected |
| alpha-Chlorotoluene | 3400 | Not Detected | 18000 | Not Detected |
| 1,2-Dichlorobenzene | 3400 | Not Detected | 21000 | Not Detected |
| 1,2,4-Trichlorobenzene | 14000 | Not Detected | 100000 | Not Detected |
| Hexachlorobutadiene | 14000 | Not Detected | 150000 | Not Detected |
| Butane | 14000 | 1200000 | 33000 | 2900000 |
| Isopentane | 14000 | 1500000 | 41000 | 4500000 |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| 1,2-Dichloroethane-d4 | 118 | 70-130 |
| Toluene-d8 | 100 | 70-130 |
| 4-Bromofluorobenzene | 98 | 70-130 |

**Client Sample ID: Lab Blank**

**Lab ID#: 1302355A-08A**

**EPA METHOD TO-15 GC/MS**

| | | | |
|---|---|---|---|
| **File Name:** | **14022706a** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 2/27/13 10:39 AM** | |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 5.0 | Not Detected | 25 | Not Detected |
| Freon 114 | 5.0 | Not Detected | 35 | Not Detected |
| Chloromethane | 20 | Not Detected | 41 | Not Detected |
| Vinyl Chloride | 5.0 | Not Detected | 13 | Not Detected |
| 1,3-Butadiene | 5.0 | Not Detected | 11 | Not Detected |
| Bromomethane | 5.0 | Not Detected | 19 | Not Detected |
| Chloroethane | 20 | Not Detected | 53 | Not Detected |
| Freon 11 | 5.0 | Not Detected | 28 | Not Detected |
| Ethanol | 20 | Not Detected | 38 | Not Detected |
| Freon 113 | 5.0 | Not Detected | 38 | Not Detected |
| 1,1-Dichloroethene | 5.0 | Not Detected | 20 | Not Detected |
| Acetone | 20 | Not Detected | 48 | Not Detected |
| 2-Propanol | 20 | Not Detected | 49 | Not Detected |
| Carbon Disulfide | 5.0 | Not Detected | 16 | Not Detected |
| 3-Chloropropene | 20 | Not Detected | 63 | Not Detected |
| Methylene Chloride | 5.0 | 2.2 J | 17 | 7.6 J |
| Methyl tert-butyl ether | 5.0 | Not Detected | 18 | Not Detected |
| trans-1,2-Dichloroethene | 5.0 | Not Detected | 20 | Not Detected |
| Hexane | 5.0 | Not Detected | 18 | Not Detected |
| 1,1-Dichloroethane | 5.0 | Not Detected | 20 | Not Detected |
| 2-Butanone (Methyl Ethyl Ketone) | 20 | Not Detected | 59 | Not Detected |
| cis-1,2-Dichloroethene | 5.0 | Not Detected | 20 | Not Detected |
| Tetrahydrofuran | 5.0 | Not Detected | 15 | Not Detected |
| Chloroform | 5.0 | Not Detected | 24 | Not Detected |
| 1,1,1-Trichloroethane | 5.0 | Not Detected | 27 | Not Detected |
| Cyclohexane | 5.0 | Not Detected | 17 | Not Detected |
| Carbon Tetrachloride | 5.0 | Not Detected | 31 | Not Detected |
| 2,2,4-Trimethylpentane | 5.0 | Not Detected | 23 | Not Detected |
| Benzene | 5.0 | Not Detected | 16 | Not Detected |
| 1,2-Dichloroethane | 5.0 | Not Detected | 20 | Not Detected |
| Heptane | 5.0 | Not Detected | 20 | Not Detected |
| Trichloroethene | 5.0 | Not Detected | 27 | Not Detected |
| 1,2-Dichloropropane | 5.0 | Not Detected | 23 | Not Detected |
| 1,4-Dioxane | 20 | Not Detected | 72 | Not Detected |
| Bromodichloromethane | 5.0 | Not Detected | 34 | Not Detected |
| cis-1,3-Dichloropropene | 5.0 | Not Detected | 23 | Not Detected |
| 4-Methyl-2-pentanone | 20 | Not Detected | 82 | Not Detected |
| Toluene | 5.0 | Not Detected | 19 | Not Detected |
| trans-1,3-Dichloropropene | 5.0 | Not Detected | 23 | Not Detected |
| 1,1,2-Trichloroethane | 5.0 | Not Detected | 27 | Not Detected |
| Tetrachloroethene | 5.0 | Not Detected | 34 | Not Detected |
| 2-Hexanone | 20 | Not Detected | 82 | Not Detected |

**Client Sample ID: Lab Blank**

**Lab ID#: 1302355A-08A**

**EPA METHOD TO-15 GC/MS**

| | | | |
|---|---|---|---|
| **File Name:** | **14022706a** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 2/27/13 10:39 AM** | |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Dibromochloromethane | 5.0 | Not Detected | 42 | Not Detected |
| 1,2-Dibromoethane (EDB) | 5.0 | Not Detected | 38 | Not Detected |
| Chlorobenzene | 5.0 | Not Detected | 23 | Not Detected |
| Ethyl Benzene | 5.0 | Not Detected | 22 | Not Detected |
| m,p-Xylene | 5.0 | Not Detected | 22 | Not Detected |
| o-Xylene | 5.0 | Not Detected | 22 | Not Detected |
| Styrene | 5.0 | Not Detected | 21 | Not Detected |
| Bromoform | 5.0 | Not Detected | 52 | Not Detected |
| Cumene | 5.0 | Not Detected | 24 | Not Detected |
| 1,1,2,2-Tetrachloroethane | 5.0 | Not Detected | 34 | Not Detected |
| Propylbenzene | 5.0 | Not Detected | 24 | Not Detected |
| 4-Ethyltoluene | 5.0 | Not Detected | 24 | Not Detected |
| 1,3,5-Trimethylbenzene | 5.0 | Not Detected | 24 | Not Detected |
| 1,2,4-Trimethylbenzene | 5.0 | Not Detected | 24 | Not Detected |
| 1,3-Dichlorobenzene | 5.0 | Not Detected | 30 | Not Detected |
| 1,4-Dichlorobenzene | 5.0 | Not Detected | 30 | Not Detected |
| alpha-Chlorotoluene | 5.0 | Not Detected | 26 | Not Detected |
| 1,2-Dichlorobenzene | 5.0 | Not Detected | 30 | Not Detected |
| 1,2,4-Trichlorobenzene | 20 | Not Detected | 150 | Not Detected |
| Hexachlorobutadiene | 20 | Not Detected | 210 | Not Detected |
| Butane | 20 | Not Detected | 48 | Not Detected |
| Isopentane | 20 | Not Detected | 59 | Not Detected |

J = Estimated value.

**Container Type: NA - Not Applicable**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| 1,2-Dichloroethane-d4 | 113 | 70-130 |
| Toluene-d8 | 98 | 70-130 |
| 4-Bromofluorobenzene | 100 | 70-130 |

**Client Sample ID: Lab Blank**

**Lab ID#: 1302355A-08B**

**EPA METHOD TO-15 GC/MS**

| | | | |
|---|---|---|---|
| **File Name:** | **14022806c** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 2/28/13 11:46 AM** | |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 5.0 | Not Detected | 25 | Not Detected |
| Freon 114 | 5.0 | Not Detected | 35 | Not Detected |
| Chloromethane | 20 | Not Detected | 41 | Not Detected |
| Vinyl Chloride | 5.0 | Not Detected | 13 | Not Detected |
| 1,3-Butadiene | 5.0 | Not Detected | 11 | Not Detected |
| Bromomethane | 5.0 | Not Detected | 19 | Not Detected |
| Chloroethane | 20 | Not Detected | 53 | Not Detected |
| Freon 11 | 5.0 | Not Detected | 28 | Not Detected |
| Ethanol | 20 | 11 J | 38 | 22 J |
| Freon 113 | 5.0 | Not Detected | 38 | Not Detected |
| 1,1-Dichloroethene | 5.0 | Not Detected | 20 | Not Detected |
| Acetone | 20 | Not Detected | 48 | Not Detected |
| 2-Propanol | 20 | Not Detected | 49 | Not Detected |
| Carbon Disulfide | 5.0 | Not Detected | 16 | Not Detected |
| 3-Chloropropene | 20 | Not Detected | 63 | Not Detected |
| Methylene Chloride | 5.0 | 1.4 J | 17 | 4.9 J |
| Methyl tert-butyl ether | 5.0 | Not Detected | 18 | Not Detected |
| trans-1,2-Dichloroethene | 5.0 | Not Detected | 20 | Not Detected |
| Hexane | 5.0 | Not Detected | 18 | Not Detected |
| 1,1-Dichloroethane | 5.0 | Not Detected | 20 | Not Detected |
| 2-Butanone (Methyl Ethyl Ketone) | 20 | Not Detected | 59 | Not Detected |
| cis-1,2-Dichloroethene | 5.0 | Not Detected | 20 | Not Detected |
| Tetrahydrofuran | 5.0 | Not Detected | 15 | Not Detected |
| Chloroform | 5.0 | Not Detected | 24 | Not Detected |
| 1,1,1-Trichloroethane | 5.0 | Not Detected | 27 | Not Detected |
| Cyclohexane | 5.0 | Not Detected | 17 | Not Detected |
| Carbon Tetrachloride | 5.0 | Not Detected | 31 | Not Detected |
| 2,2,4-Trimethylpentane | 5.0 | Not Detected | 23 | Not Detected |
| Benzene | 5.0 | Not Detected | 16 | Not Detected |
| 1,2-Dichloroethane | 5.0 | Not Detected | 20 | Not Detected |
| Heptane | 5.0 | Not Detected | 20 | Not Detected |
| Trichloroethene | 5.0 | Not Detected | 27 | Not Detected |
| 1,2-Dichloropropane | 5.0 | Not Detected | 23 | Not Detected |
| 1,4-Dioxane | 20 | Not Detected | 72 | Not Detected |
| Bromodichloromethane | 5.0 | Not Detected | 34 | Not Detected |
| cis-1,3-Dichloropropene | 5.0 | Not Detected | 23 | Not Detected |
| 4-Methyl-2-pentanone | 20 | Not Detected | 82 | Not Detected |
| Toluene | 5.0 | Not Detected | 19 | Not Detected |
| trans-1,3-Dichloropropene | 5.0 | Not Detected | 23 | Not Detected |
| 1,1,2-Trichloroethane | 5.0 | Not Detected | 27 | Not Detected |
| Tetrachloroethene | 5.0 | Not Detected | 34 | Not Detected |
| 2-Hexanone | 20 | Not Detected | 82 | Not Detected |

eurofins | Air Toxics

**Client Sample ID: Lab Blank**

**Lab ID#: 1302355A-08B**

**EPA METHOD TO-15 GC/MS**

| | | | |
|---|---|---|---|
| **File Name:** | **14022806c** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 2/28/13 11:46 AM** | |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Dibromochloromethane | 5.0 | Not Detected | 42 | Not Detected |
| 1,2-Dibromoethane (EDB) | 5.0 | Not Detected | 38 | Not Detected |
| Chlorobenzene | 5.0 | Not Detected | 23 | Not Detected |
| Ethyl Benzene | 5.0 | Not Detected | 22 | Not Detected |
| m,p-Xylene | 5.0 | Not Detected | 22 | Not Detected |
| o-Xylene | 5.0 | Not Detected | 22 | Not Detected |
| Styrene | 5.0 | Not Detected | 21 | Not Detected |
| Bromoform | 5.0 | Not Detected | 52 | Not Detected |
| Cumene | 5.0 | Not Detected | 24 | Not Detected |
| 1,1,2,2-Tetrachloroethane | 5.0 | Not Detected | 34 | Not Detected |
| Propylbenzene | 5.0 | Not Detected | 24 | Not Detected |
| 4-Ethyltoluene | 5.0 | Not Detected | 24 | Not Detected |
| 1,3,5-Trimethylbenzene | 5.0 | Not Detected | 24 | Not Detected |
| 1,2,4-Trimethylbenzene | 5.0 | Not Detected | 24 | Not Detected |
| 1,3-Dichlorobenzene | 5.0 | Not Detected | 30 | Not Detected |
| 1,4-Dichlorobenzene | 5.0 | Not Detected | 30 | Not Detected |
| alpha-Chlorotoluene | 5.0 | 1.1 J | 26 | 5.8 J |
| 1,2-Dichlorobenzene | 5.0 | Not Detected | 30 | Not Detected |
| 1,2,4-Trichlorobenzene | 20 | Not Detected | 150 | Not Detected |
| Hexachlorobutediene | 20 | Not Detected | 210 | Not Detected |
| Butane | 20 | Not Detected | 48 | Not Detected |
| Isopentane | 20 | Not Detected | 59 | Not Detected |

J = Estimated value.

**Container Type: NA - Not Applicable**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| 1,2-Dichloroethane-d4 | 117 | 70-130 |
| Toluene-d8 | 100 | 70-130 |
| 4-Bromofluorobenzene | 98 | 70-130 |

eurofins | Air Toxics

**Client Sample ID: CCV**
**Lab ID#: 1302355A-09A**
**EPA METHOD TO-15 GC/MS**

| | | | |
|---|---|---|---|
| **File Name:** | **14022702** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 2/27/13 08:56 AM** | |

| Compound | %Recovery |
|---|---|
| Freon 12 | 103 |
| Freon 114 | 98 |
| Chloromethane | 102 |
| Vinyl Chloride | 95 |
| 1,3-Butadiene | 94 |
| Bromomethane | 87 |
| Chloroethane | 98 |
| Freon 11 | 107 |
| Ethanol | 102 |
| Freon 113 | 90 |
| 1,1-Dichloroethene | 103 |
| Acetone | 97 |
| 2-Propanol | 100 |
| Carbon Disulfide | 87 |
| 3-Chloropropene | 90 |
| Methylene Chloride | 90 |
| Methyl tert-butyl ether | 98 |
| trans-1,2-Dichloroethene | 98 |
| Hexane | 97 |
| 1,1-Dichloroethane | 95 |
| 2-Butanone (Methyl Ethyl Ketone) | 95 |
| cis-1,2-Dichloroethene | 96 |
| Tetrahydrofuran | 102 |
| Chloroform | 103 |
| 1,1,1-Trichloroethane | 107 |
| Cyclohexane | 94 |
| Carbon Tetrachloride | 107 |
| 2,2,4-Trimethylpentane | 96 |
| Benzene | 90 |
| 1,2-Dichloroethane | 107 |
| Heptane | 98 |
| Trichloroethene | 96 |
| 1,2-Dichloropropane | 92 |
| 1,4-Dioxane | 96 |
| Bromodichloromethane | 107 |
| cis-1,3-Dichloropropene | 98 |
| 4-Methyl-2-pentanone | 100 |
| Toluene | 91 |
| trans-1,3-Dichloropropene | 106 |
| 1,1,2-Trichloroethane | 98 |
| Tetrachloroethene | 99 |
| 2-Hexanone | 105 |

eurofins | Air Toxics

**Client Sample ID: CCV**
**Lab ID#: 1302355A-09A**
**EPA METHOD TO-15 GC/MS**

| | | | |
|---|---|---|---|
| **File Name:** | **14022702** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 2/27/13 08:56 AM** | |

| Compound | %Recovery |
|---|---|
| Dibromochloromethane | 110 |
| 1,2-Dibromoethane (EDB) | 103 |
| Chlorobenzene | 93 |
| Ethyl Benzene | 97 |
| m,p-Xylene | 101 |
| o-Xylene | 101 |
| Styrene | 106 |
| Bromoform | 115 |
| Cumene | 105 |
| 1,1,2,2-Tetrachloroethane | 98 |
| Propylbenzene | 102 |
| 4-Ethyltoluene | 108 |
| 1,3,5-Trimethylbenzene | 107 |
| 1,2,4-Trimethylbenzene | 105 |
| 1,3-Dichlorobenzene | 97 |
| 1,4-Dichlorobenzene | 96 |
| alpha-Chlorotoluene | 124 |
| 1,2-Dichlorobenzene | 96 |
| 1,2,4-Trichlorobenzene | 101 |
| Hexachlorobutadiene | 97 |
| Butane | 98 |
| Isopentane | 94 |

**Container Type: NA - Not Applicable**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| 1,2-Dichloroethane-d4 | 108 | 70-130 |
| Toluene-d8 | 100 | 70-130 |
| 4-Bromofluorobenzene | 103 | 70-130 |

eurofins | Air Toxics

**Client Sample ID: CCV**
**Lab ID#: 1302355A-09B**
**EPA METHOD TO-15 GC/MS**

| | | | |
|---|---|---|---|
| File Name: | 14022802 | Date of Collection: NA | |
| Dil. Factor: | 1.00 | Date of Analysis: 2/28/13 09:33 AM | |

| Compound | %Recovery |
|---|---|
| Freon 12 | 104 |
| Freon 114 | 97 |
| Chloromethane | 102 |
| Vinyl Chloride | 92 |
| 1,3-Butadiene | 94 |
| Bromomethane | 88 |
| Chloroethane | 93 |
| Freon 11 | 110 |
| Ethanol | 105 |
| Freon 113 | 90 |
| 1,1-Dichloroethene | 101 |
| Acetone | 98 |
| 2-Propanol | 100 |
| Carbon Disulfide | 83 |
| 3-Chloropropene | 82 |
| Methylene Chloride | 90 |
| Methyl tert-butyl ether | 100 |
| trans-1,2-Dichloroethene | 96 |
| Hexane | 95 |
| 1,1-Dichloroethane | 97 |
| 2-Butanone (Methyl Ethyl Ketone) | 91 |
| cis-1,2-Dichloroethene | 97 |
| Tetrahydrofuran | 101 |
| Chloroform | 103 |
| 1,1,1-Trichloroethane | 107 |
| Cyclohexane | 94 |
| Carbon Tetrachloride | 109 |
| 2,2,4-Trimethylpentane | 99 |
| Benzene | 91 |
| 1,2-Dichloroethane | 111 |
| Heptane | 97 |
| Trichloroethene | 95 |
| 1,2-Dichloropropane | 94 |
| 1,4-Dioxane | 100 |
| Bromodichloromethane | 103 |
| cis-1,3-Dichloropropene | 94 |
| 4-Methyl-2-pentanone | 100 |
| Toluene | 93 |
| trans-1,3-Dichloropropene | 101 |
| 1,1,2-Trichloroethane | 96 |
| Tetrachloroethene | 99 |
| 2-Hexanone | 105 |

eurofins | Air Toxics

**Client Sample ID: CCV**
**Lab ID#: 1302355A-09B**
**EPA METHOD TO-15 GC/MS**

| | | | |
|---|---|---|---|
| **File Name:** | **14022802** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 2/28/13 09:33 AM** | |

| Compound | %Recovery |
|---|---|
| Dibromochloromethane | 107 |
| 1,2-Dibromoethane (EDB) | 102 |
| Chlorobenzene | 93 |
| Ethyl Benzene | 97 |
| m,p-Xylene | 98 |
| o-Xylene | 98 |
| Styrene | 99 |
| Bromoform | 107 |
| Cumene | 105 |
| 1,1,2,2-Tetrachloroethane | 98 |
| Propylbenzene | 104 |
| 4-Ethyltoluene | 106 |
| 1,3,5-Trimethylbenzene | 105 |
| 1,2,4-Trimethylbenzene | 102 |
| 1,3-Dichlorobenzene | 94 |
| 1,4-Dichlorobenzene | 98 |
| alpha-Chlorotoluene | 116 |
| 1,2-Dichlorobenzene | 95 |
| 1,2,4-Trichlorobenzene | 92 |
| Hexachlorobutadiene | 99 |
| Butane | 97 |
| Isopentane | 96 |

**Container Type: NA - Not Applicable**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| 1,2-Dichloroethane-d4 | 113 | 70-130 |
| Toluene-d8 | 102 | 70-130 |
| 4-Bromofluorobenzene | 102 | 70-130 |

eurofins | Air Toxics

**Client Sample ID: LCS**

**Lab ID#: 1302355A-10A**

**EPA METHOD TO-15 GC/MS**

| | | | |
|---|---|---|---|
| **File Name:** | **14022703** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 2/27/13 09:23 AM** | |

| Compound | %Recovery |
|---|---|
| Freon 12 | 121 |
| Freon 114 | 108 |
| Chloromethane | 123 |
| Vinyl Chloride | 106 |
| 1,3-Butadiene | 109 |
| Bromomethane | 94 |
| Chloroethane | 97 |
| Freon 11 | 122 |
| Ethanol | 118 |
| Freon 113 | 98 |
| 1,1-Dichloroethene | 124 |
| Acetone | 105 |
| 2-Propanol | 110 |
| Carbon Disulfide | 114 |
| 3-Chloropropene | 105 |
| Methylene Chloride | 98 |
| Methyl tert-butyl ether | 107 |
| trans-1,2-Dichloroethene | 122 |
| Hexane | 102 |
| 1,1-Dichloroethane | 106 |
| 2-Butanone (Methyl Ethyl Ketone) | 99 |
| cis-1,2-Dichloroethene | 104 |
| Tetrahydrofuran | 105 |
| Chloroform | 114 |
| 1,1,1-Trichloroethane | 117 |
| Cyclohexane | 102 |
| Carbon Tetrachloride | 117 |
| 2,2,4-Trimethylpentane | 103 |
| Benzene | 101 |
| 1,2-Dichloroethane | 116 |
| Heptane | 101 |
| Trichloroethene | 107 |
| 1,2-Dichloropropane | 101 |
| 1,4-Dioxane | 103 |
| Bromodichloromethane | 112 |
| cis-1,3-Dichloropropene | 98 |
| 4-Methyl-2-pentanone | 96 |
| Toluene | 99 |
| trans-1,3-Dichloropropene | 102 |
| 1,1,2-Trichloroethane | 101 |
| Tetrachloroethene | 104 |
| 2-Hexanone | 97 |

eurofins | Air Toxics

**Client Sample ID: LCS**
**Lab ID#: 1302355A-10A**
**EPA METHOD TO-15 GC/MS**

| | | | |
|---|---|---|---|
| **File Name:** | **14022703** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 2/27/13 09:23 AM** | |

| Compound | %Recovery |
|---|---|
| Dibromochloromethane | 111 |
| 1,2-Dibromoethane (EDB) | 105 |
| Chlorobenzene | 101 |
| Ethyl Benzene | 99 |
| m,p-Xylene | 100 |
| o-Xylene | 100 |
| Styrene | 102 |
| Bromoform | 105 |
| Cumene | 105 |
| 1,1,2,2-Tetrachloroethane | 102 |
| Propylbenzene | 103 |
| 4-Ethyltoluene | 103 |
| 1,3,5-Trimethylbenzene | 107 |
| 1,2,4-Trimethylbenzene | 98 |
| 1,3-Dichlorobenzene | 96 |
| 1,4-Dichlorobenzene | 96 |
| alpha-Chlorotoluene | 105 |
| 1,2-Dichlorobenzene | 94 |
| 1,2,4-Trichlorobenzene | 86 |
| Hexachlorobutadiene | 89 |
| Butane | 103 |
| Isopentane | 106 |

**Container Type: NA - Not Applicable**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| 1,2-Dichloroethane-d4 | 113 | 70-130 |
| Toluene-d8 | 100 | 70-130 |
| 4-Bromofluorobenzene | 102 | 70-130 |

eurofins | Air Toxics

**Client Sample ID: LCSD**
**Lab ID#: 1302355A-10AA**
**EPA METHOD TO-15 GC/MS**

| | | | |
|---|---|---|---|
| **File Name:** | **14022704** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 2/27/13 09:42 AM** | |

| Compound | %Recovery |
|---|---|
| Freon 12 | 120 |
| Freon 114 | 110 |
| Chloromethane | 121 |
| Vinyl Chloride | 106 |
| 1,3-Butadiene | 106 |
| Bromomethane | 100 |
| Chloroethane | 104 |
| Freon 11 | 123 |
| Ethanol | 118 |
| Freon 113 | 102 |
| 1,1-Dichloroethene | 131 Q |
| Acetone | 108 |
| 2-Propanol | 113 |
| Carbon Disulfide | 119 |
| 3-Chloropropene | 108 |
| Methylene Chloride | 102 |
| Methyl tert-butyl ether | 107 |
| trans-1,2-Dichloroethene | 126 |
| Hexane | 104 |
| 1,1-Dichloroethane | 107 |
| 2-Butanone (Methyl Ethyl Ketone) | 101 |
| cis-1,2-Dichloroethene | 108 |
| Tetrahydrofuran | 106 |
| Chloroform | 117 |
| 1,1,1-Trichloroethane | 118 |
| Cyclohexane | 106 |
| Carbon Tetrachloride | 122 |
| 2,2,4-Trimethylpentane | 105 |
| Benzene | 99 |
| 1,2-Dichloroethane | 115 |
| Heptane | 103 |
| Trichloroethene | 106 |
| 1,2-Dichloropropane | 102 |
| 1,4-Dioxane | 104 |
| Bromodichloromethane | 110 |
| cis-1,3-Dichloropropene | 99 |
| 4-Methyl-2-pentanone | 103 |
| Toluene | 100 |
| trans-1,3-Dichloropropene | 102 |
| 1,1,2-Trichloroethane | 101 |
| Tetrachloroethene | 106 |
| 2-Hexanone | 98 |

eurofins | Air Toxics

**Client Sample ID: LCSD**
**Lab ID#: 1302355A-10AA**
**EPA METHOD TO-15 GC/MS**

| | | | |
|---|---|---|---|
| **File Name:** | **14022704** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 2/27/13 09:42 AM** | |

| Compound | %Recovery |
|---|---|
| Dibromochloromethane | 110 |
| 1,2-Dibromoethane (EDB) | 106 |
| Chlorobenzene | 101 |
| Ethyl Benzene | 104 |
| m,p-Xylene | 103 |
| o-Xylene | 99 |
| Styrene | 105 |
| Bromoform | 109 |
| Cumene | 109 |
| 1,1,2,2-Tetrachloroethane | 107 |
| Propylbenzene | 107 |
| 4-Ethyltoluene | 105 |
| 1,3,5-Trimethylbenzene | 111 |
| 1,2,4-Trimethylbenzene | 101 |
| 1,3-Dichlorobenzene | 100 |
| 1,4-Dichlorobenzene | 102 |
| alpha-Chlorotoluene | 107 |
| 1,2-Dichlorobenzene | 98 |
| 1,2,4-Trichlorobenzene | 93 |
| Hexachlorobutadiene | 92 |
| Butane | 106 |
| Isopentane | 110 |

Q = Exceeds Quality Control limits.

**Container Type: NA - Not Applicable**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| 1,2-Dichloroethane-d4 | 112 | 70-130 |
| Toluene-d8 | 100 | 70-130 |
| 4-Bromofluorobenzene | 103 | 70-130 |

**Client Sample ID: LCS**

**Lab ID#: 1302355A-10B**

**EPA METHOD TO-15 GC/MS**

| | | | |
|---|---|---|---|
| **File Name:** | **14022803** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 2/28/13 10:00 AM** | |

| Compound | %Recovery |
|---|---|
| Freon 12 | 124 |
| Freon 114 | 111 |
| Chloromethane | 124 |
| Vinyl Chloride | 109 |
| 1,3-Butadiene | 105 |
| Bromomethane | 91 |
| Chloroethane | 108 |
| Freon 11 | 130 |
| Ethanol | 122 |
| Freon 113 | 101 |
| 1,1-Dichloroethene | 129 |
| Acetone | 111 |
| 2-Propanol | 121 |
| Carbon Disulfide | 119 |
| 3-Chloropropene | 112 |
| Methylene Chloride | 103 |
| Methyl tert-butyl ether | 116 |
| trans-1,2-Dichloroethene | 127 |
| Hexane | 109 |
| 1,1-Dichloroethane | 110 |
| 2-Butanone (Methyl Ethyl Ketone) | 106 |
| cis-1,2-Dichloroethene | 111 |
| Tetrahydrofuran | 115 |
| Chloroform | 122 |
| 1,1,1-Trichloroethane | 126 |
| Cyclohexane | 106 |
| Carbon Tetrachloride | 129 |
| 2,2,4-Trimethylpentane | 110 |
| Benzene | 104 |
| 1,2-Dichloroethane | 126 |
| Heptane | 110 |
| Trichloroethene | 113 |
| 1,2-Dichloropropane | 110 |
| 1,4-Dioxane | 115 |
| Bromodichloromethane | 121 |
| cis-1,3-Dichloropropene | 108 |
| 4-Methyl-2-pentanone | 113 |
| Toluene | 106 |
| trans-1,3-Dichloropropene | 117 |
| 1,1,2-Trichloroethane | 112 |
| Tetrachloroethene | 110 |
| 2-Hexanone | 122 |

eurofins | Air Toxics

**Client Sample ID: LCS**
**Lab ID#: 1302355A-10B**
**EPA METHOD TO-15 GC/MS**

| | | | |
|---|---|---|---|
| **File Name:** | **14022803** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 2/28/13 10:00 AM** | |

| Compound | %Recovery |
|---|---|
| Dibromochloromethane | 120 |
| 1,2-Dibromoethane (EDB) | 118 |
| Chlorobenzene | 109 |
| Ethyl Benzene | 110 |
| m,p-Xylene | 116 |
| o-Xylene | 113 |
| Styrene | 120 |
| Bromoform | 126 |
| Cumene | 121 |
| 1,1,2,2-Tetrachloroethane | 115 |
| Propylbenzene | 120 |
| 4-Ethyltoluene | 119 |
| 1,3,5-Trimethylbenzene | 122 |
| 1,2,4-Trimethylbenzene | 120 |
| 1,3-Dichlorobenzene | 112 |
| 1,4-Dichlorobenzene | 114 |
| alpha-Chlorotoluene | 139 Q |
| 1,2-Dichlorobenzene | 113 |
| 1,2,4-Trichlorobenzene | 119 |
| Hexachlorobutadiene | 112 |
| Butane | 104 |
| Isopentane | 116 |

Q = Exceeds Quality Control limits.

**Container Type: NA - Not Applicable**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| 1,2-Dichloroethane-d4 | 115 | 70-130 |
| Toluene-d8 | 101 | 70-130 |
| 4-Bromofluorobenzene | 104 | 70-130 |

eurofins | Air Toxics

**Client Sample ID: LCSD**
**Lab ID#: 1302355A-10BB**
**EPA METHOD TO-15 GC/MS**

| | | | |
|---|---|---|---|
| **File Name:** | **14022804** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 2/28/13 10:39 AM** | |

| Compound | %Recovery |
|---|---|
| Freon 12 | 125 |
| Freon 114 | 114 |
| Chloromethane | 123 |
| Vinyl Chloride | 109 |
| 1,3-Butadiene | 112 |
| Bromomethane | 98 |
| Chloroethane | 109 |
| Freon 11 | 131 Q |
| Ethanol | 121 |
| Freon 113 | 105 |
| 1,1-Dichloroethene | 130 |
| Acetone | 111 |
| 2-Propanol | 123 |
| Carbon Disulfide | 121 |
| 3-Chloropropene | 112 |
| Methylene Chloride | 103 |
| Methyl tert-butyl ether | 116 |
| trans-1,2-Dichloroethene | 125 |
| Hexane | 110 |
| 1,1-Dichloroethane | 113 |
| 2-Butanone (Methyl Ethyl Ketone) | 108 |
| cis-1,2-Dichloroethene | 110 |
| Tetrahydrofuran | 113 |
| Chloroform | 121 |
| 1,1,1-Trichloroethane | 126 |
| Cyclohexane | 108 |
| Carbon Tetrachloride | 129 |
| 2,2,4-Trimethylpentane | 110 |
| Benzene | 105 |
| 1,2-Dichloroethane | 128 |
| Heptane | 114 |
| Trichloroethene | 111 |
| 1,2-Dichloropropane | 111 |
| 1,4-Dioxane | 117 |
| Bromodichloromethane | 122 |
| cis-1,3-Dichloropropene | 111 |
| 4-Methyl-2-pentanone | 112 |
| Toluene | 106 |
| trans-1,3-Dichloropropene | 117 |
| 1,1,2-Trichloroethane | 111 |
| Tetrachloroethene | 110 |
| 2-Hexanone | 120 |

eurofins | Air Toxics

**Client Sample ID: LCSD**
**Lab ID#: 1302355A-10BB**
**EPA METHOD TO-15 GC/MS**

| | | | |
|---|---|---|---|
| **File Name:** | **14022804** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 2/28/13 10:39 AM** | |

| Compound | %Recovery |
|---|---|
| Dibromochloromethane | 119 |
| 1,2-Dibromoethane (EDB) | 116 |
| Chlorobenzene | 108 |
| Ethyl Benzene | 108 |
| m,p-Xylene | 112 |
| o-Xylene | 111 |
| Styrene | 114 |
| Bromoform | 119 |
| Cumene | 115 |
| 1,1,2,2-Tetrachloroethane | 110 |
| Propylbenzene | 114 |
| 4-Ethyltoluene | 114 |
| 1,3,5-Trimethylbenzene | 114 |
| 1,2,4-Trimethylbenzene | 112 |
| 1,3-Dichlorobenzene | 101 |
| 1,4-Dichlorobenzene | 104 |
| alpha-Chlorotoluene | 122 |
| 1,2-Dichlorobenzene | 100 |
| 1,2,4-Trichlorobenzene | 85 |
| Hexachlorobutadiene | 84 |
| Butane | 112 |
| Isopentane | 116 |

Q = Exceeds Quality Control limits.

**Container Type: NA - Not Applicable**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| 1,2-Dichloroethane-d4 | 113 | 70-130 |
| Toluene-d8 | 101 | 70-130 |
| 4-Bromofluorobenzene | 103 | 70-130 |

1302355

# Shell Oil Products Chain Of Custody Record

URS

Air Toxics LTD.
Project Name: Roxana Soil Vapor
Project # 21562850.04001
Lab Vendor #

Please Check Appropriate Box: ☑ ENV. SERVICES ☐ MOTIVA RETAIL ☐ SHELL RETAIL ☐ MOTIVA MARCH ☐ CONSULTANT ☐ LUBES ☐ SHELL PIPELINE ☐ OTHER

Print Bill To Contact Name: Robert Moosheglan

INCIDENT # (ENV SERVICES): 9 7 2 1 6 8 3 0

☐ CHECK IF NO INCIDENT # APPLIES

DATE 02/19/13

PAGE: 1 of 1

PO #:

SAP #: 3 4 0 0 8 1

URS CORPORATION

1001 HIGHLANDS PLAZA DRIVE WEST - SUITE 300; ST. LOUIS, MO 63110

Air Toxics, LTD 180 Blue Ravine Road, Suite B, Folsom CA 95630-4719

314-429-0100 | 314-429-0462 | Robert.Moosheglan@urs.com

SITE ADDRESS: Street and City: 900 SOUTH CENTRAL AVE -- ROXANA

State: IL

Zip Code:

Elizabeth Kunkel, URS, St. Louis | 314-743-4179

Consultant Project Number: Roxana Soil Vapor

C. Kretzer, D. Mattingly, T. Carroll, C. Williams, M. Currier, B. Lehan, L. Rathnow.

TURNAROUND TIME (CALENDAR DAYS):
☑ STANDARD (14 DAY) ☐ 5 DAYS ☐ 3 DAYS ☐ 2 DAYS ☐ 24 HOURS ☐ RESULTS NEEDED ON WEEKEND

☐ LA - RWQCB REPORT FORMAT ☑ UST AGENCY:

DELIVERABLES: ☐ LEVEL 1 ☐ LEVEL 2 ☐ LEVEL 3 ☑ LEVEL 4 ☐ OTHER (SPECIFY)

☑ SHELL CONTRACT RATE APPLIES
☐ STATE REIMBURSEMENT RATE APPLIES
☐ EDD NOT NEEDED
☑ RECEIPT VERIFICATION REQUESTED

REQUESTED ANALYSIS

| Lab Use Only | Field Sample Identification | Sampling Date | Sampling Time | Canister Number | Canister Pressure/Vacuum Initial | Canister Pressure/Vacuum Final | Canister Pressure/Vacuum Receipt | Canister Pressure/Vacuum Final (psi) | Modified TO-15 + Butane & Isopentane | ASTM D-1946 + Helium | ASTM D-1946 | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| 01A | VMP-12-25-021513 | 02/15/13 | 1123-1163 | 22966 | -30 | -7.5 | | | X | X | | | | | | |
| 02A | VMP-12-38-021513 | 02/15/13 | 1026-1056 | 37320 | -30 | -6 | | | X | X | | | | | | |
| 03A | VMP-18-5-021413 | 02/14/13 | 1014-1044 | 24395 | -29 | -8 | | | X | X | | | | | | |
| 04A | VMP-18-13.5-021413 | 02/14/13 | 1113-1143 | 3788* | -30 | -7.5 | | | X | X | | | | | | |
| 05A | VMP-18-19-021413 | 02/14/13 | 1350-1420 | 37736 | -30 | -7 | | | X | X | | | | | | |
| 06A | VMP-18-31-021813 | 02/18/13 | 1432-1502 | 12285 | -28.5 | -12 | | | X | X | | | | | | |
| 07A | VMP-SS-20-021513 | 02/15/13 | 1003-1045 | 12284 | -30 | -11.5 | | | X | X | | | | | | |

Turn Around Time: ☑ Normal ☐ Rush ☐ Specify

Lab Use Only
Pressurized by:
Date:
Pressurization Gas: $N_2$ He

ADDITIONAL NOTES:

- 14 day hold time
- Report results between MDL and RL
- Level IV ECVP
- DNA CANISTER 15723 - High helium

FedEx
Custody Seal Intact?
(Y) N None Temp NA

| Relinquished by: (Signature) | Received by: (Signature) | Date | Time |
|---|---|---|---|
| | FEDEX | 2/19/13 | 1730 |
| Relinquished by: (Signature) | Received by: (Signature) Kathi Dacy ATC | 02/20/13 | 1000 |
| Relinquished by: (Signature) | Received by: (Signature) | Date | Time |

eurofins

Air Toxics

3/14/2013
Ms. Elizabeth Kunkel
URS Corporation
1001 Highlands Plaza Dr. West
Suite 300
St. Louis MO 63110

Project Name: Roxana Soil Vapor
Project #: 21562850.04001
Workorder #: 1302355B

Dear Ms. Elizabeth Kunkel

The following report includes the data for the above referenced project for sample(s) received on 2/20/2013 at Air Toxics Ltd.

The data and associated QC analyzed by Modified ASTM D-1946 are compliant with the project requirements or laboratory criteria with the exception of the deviations noted in the attached case narrative.

Thank you for choosing Air Toxics Ltd. for your air analysis needs. Air Toxics Ltd. is committed to providing accurate data of the highest quality. Please feel free to contact the Project Manager: Kelly Buettner at 916-985-1000 if you have any questions regarding the data in this report.

Regards,

Kelly Buettner

Project Manager

REVIEWED
ON
3/25/13

eurofins | Air Toxics

# WORK ORDER #: 1302355B

Work Order Summary

| | | | |
|---|---|---|---|
| **CLIENT:** | Ms. Elizabeth Kunkel<br>URS Corporation<br>1001 Highlands Plaza Dr. West<br>Suite 300<br>St. Louis, MO 63110 | **BILL TO:** | Accounts Payable Austin<br>URS Corporation<br>P.O. BOX 203970<br>Austin, TX 78720-1088 |
| **PHONE:** | 314-743-4179 | **P.O. #** | 21562735.00013 |
| **FAX:** | | **PROJECT #** | 21562850.04001 Roxana Soil Vapor |
| **DATE RECEIVED:** | 02/20/2013 | **CONTACT:** | Kelly Buettner |
| **DATE COMPLETED:** | 03/14/2013 | | |

| FRACTION # | NAME | TEST | RECEIPT VAC./PRES. | FINAL PRESSURE |
|---|---|---|---|---|
| 01A | VMP-12-25-021513 | Modified ASTM D-1946 | 6.5 "Hg | 15 psi |
| 02A | VMP-12-39-021513 | Modified ASTM D-1946 | 5.0 "Hg | 15 psi |
| 03A | VMP-16-5-021413 | Modified ASTM D-1946 | 7.0 "Hg | 15 psi |
| 04A | VMP-16-13.5-021413 | Modified ASTM D-1946 | 7.5 "Hg | 15 psi |
| 05A | VMP-16-19-021413 | Modified ASTM D-1946 | 7.0 "Hg | 15 psi |
| 06A | VMP-16-31-021813 | Modified ASTM D-1946 | 11.0 "Hg | 15 psi |
| 07A | VMP-55-20-021513 | Modified ASTM D-1946 | 8.0 "Hg | 15 psi |
| 08A | Lab Blank | Modified ASTM D-1946 | NA | NA |
| 08B | Lab Blank | Modified ASTM D-1946 | NA | NA |
| 09A | LCS | Modified ASTM D-1946 | NA | NA |
| 09AA | LCSD | Modified ASTM D-1946 | NA | NA |

CERTIFIED BY: Heidi Hayes DATE: 03/14/13

Technical Director

Certification numbers: AZ Licensure AZ0775, CA NELAP - 12282CA, NY NELAP - 11291,
TX NELAP - T104704434-12-4, UT NELAP CA009332012-3, WA NELAP - C935
Name of Accrediting Agency: NELAP/ORELAP (Oregon Environmental Laboratory Accreditation Program)
Accreditation number: CA300005, Effective date: 10/18/2012, Expiration date: 10/17/2013.
Eurofins Air Toxics Ltd. certifies that the test results contained in this report meet all requirements of the NELAC standards

This report shall not be reproduced, except in full, without the written approval of Eurofins Air Toxics, Inc.

180 BLUE RAVINE ROAD, SUITE B FOLSOM, CA - 9563
(916) 985-1000 . (800) 985-5955 . FAX (916) 985-1020

**LABORATORY NARRATIVE**
**Modified ASTM D-1946**
**URS Corporation**
**Workorder# 1302355B**

Seven 1 Liter Summa Canister samples were received on February 20, 2013. The laboratory performed analysis via Modified ASTM Method D-1946 for Methane and fixed gases in air using GC/FID or GC/TCD. The method involves direct injection of 1.0 mL of sample.

On the analytical column employed for this analysis, Oxygen coelutes with Argon. The corresponding peak is quantitated as Oxygen.

Since Nitrogen is used to pressurize samples, the reported Nitrogen values are calculated by adding all the sample components and subtracting from 100%.

Method modifications taken to run these samples are summarized in the table below. Specific project requirements may over-ride the ATL modifications.

| *Requirement* | *ASTM D-1946* | *ATL Modifications* |
|---|---|---|
| Calibration | A single point calibration is performed using a reference standard closely matching the composition of the unknown. | A 3-point calibration curve is performed. Quantitation is based on a daily calibration standard which may or may not resemble the composition of the associated samples. |
| Reference Standard | The composition of any reference standard must be known to within 0.01 mol % for any component. | The standards used by ATL are blended to a >/= 95% accuracy. |
| Sample Injection Volume | Components whose concentrations are in excess of 5 % should not be analyzed by using sample volumes greater than 0.5 mL. | The sample container is connected directly to a fixed volume sample loop of 1.0 mL on the GC. Linear range is defined by the calibration curve. Bags are loaded by vacuum. |
| Normalization | Normalize the mole percent values by multiplying each value by 100 and dividing by the sum of the original values. The sum of the original values should not differ from 100% by more than 1.0%. | Results are not normalized. The sum of the reported values can differ from 100% by as much as 15%, either due to analytical variability or an unusual sample matrix. |
| Precision | Precision requirements established at each concentration level. | Duplicates should agree within 25% RPD for detections > 5 X's the RL. |

**Receiving Notes**

There were no receiving discrepancies.

**Analytical Notes**

As per project specific client request the laboratory has reported estimated values for target compound hits that are below the Reporting Limit but greater than the Method Detection Limit. Concentrations that are below the level at which the canister was certified may be false positives.

The reporting limit for Carbon Monoxide was raised from 0.010% to 0.050%.

**Definition of Data Qualifying Flags**

Seven qualifiers may have been used on the data analysis sheets and indicate as follows:
B - Compound present in laboratory blank greater than reporting limit.
J - Estimated value.
E - Exceeds instrument calibration range.
S - Saturated peak.
Q - Exceeds quality control limits.
U - Compound analyzed for but not detected above the detection limit.
M - Reported value may be biased due to apparent matrix interferences.
File extensions may have been used on the data analysis sheets and indicates as follows:
a-File was requantified
b-File was quantified by a second column and detector
r1-File was requantified for the purpose of reissue

eurofins | Air Toxics

# Summary of Detected Compounds
# NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1946

**Client Sample ID: VMP-12-25-021513**

**Lab ID#: 1302355B-01A**

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.26 | 1.4 |
| Nitrogen | 0.26 | 74 |
| Methane | 0.00026 | 12 |
| Carbon Dioxide | 0.026 | 12 |
| Ethane | 0.0026 | 0.00025 J |

**Client Sample ID: VMP-12-39-021513**

**Lab ID#: 1302355B-02A**

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.24 | 1.5 |
| Nitrogen | 0.24 | 58 |
| Methane | 0.00024 | 26 |
| Carbon Dioxide | 0.024 | 14 |
| Ethane | 0.0024 | 0.00064 J |

**Client Sample ID: VMP-16-5-021413**

**Lab ID#: 1302355B-03A**

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.26 | 16 |
| Nitrogen | 0.26 | 80 |
| Methane | 0.00026 | 0.00010 J |
| Carbon Dioxide | 0.026 | 4.1 |
| Helium | 0.13 | 0.26 |

**Client Sample ID: VMP-16-13.5-021413**

**Lab ID#: 1302355B-04A**

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.27 | 1.3 |
| Nitrogen | 0.27 | 76 |

eurofins | Air Toxics

# Summary of Detected Compounds
# NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1946

**Client Sample ID: VMP-16-13.5-021413**

**Lab ID#: 1302355B-04A**

| | | |
|---|---|---|
| Methane | 0.00027 | 9.2 |
| Carbon Dioxide | 0.027 | 13 |
| Ethane | 0.0027 | 0.00030 J |

**Client Sample ID: VMP-16-19-021413**

**Lab ID#: 1302355B-05A**

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.26 | 1.2 |
| Nitrogen | 0.26 | 59 |
| Methane | 0.00026 | 26 |
| Carbon Dioxide | 0.026 | 14 |
| Ethane | 0.0026 | 0.00076 J |

**Client Sample ID: VMP-16-31-021813**

**Lab ID#: 1302355B-06A**

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.32 | 0.97 |
| Nitrogen | 0.32 | 54 |
| Methane | 0.00032 | 30 |
| Carbon Dioxide | 0.032 | 15 |
| Ethane | 0.0032 | 0.00089 J |

**Client Sample ID: VMP-55-20-021513**

**Lab ID#: 1302355B-07A**

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.28 | 3.2 |
| Nitrogen | 0.28 | 69 |
| Methane | 0.00028 | 11 |
| Carbon Dioxide | 0.028 | 16 |
| Ethane | 0.0028 | 0.0046 |
| Helium | 0.14 | 0.17 |

eurofins | Air Toxics

**Client Sample ID: VMP-12-25-021513**

**Lab ID#: 1302355B-01A**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1946**

| | | | |
|---|---|---|---|
| **File Name:** | **9022808** | **Date of Collection:** | **2/15/13 11:53:00 AM** |
| **Dil. Factor:** | **2.58** | **Date of Analysis:** | **2/28/13 11:16 AM** |

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.26 | 1.4 |
| Nitrogen | 0.26 | 74 |
| Carbon Monoxide | 0.13 | Not Detected |
| Methane | 0.00026 | 12 |
| Carbon Dioxide | 0.026 | 12 |
| Ethane | 0.0026 | 0.00025 J |
| Ethene | 0.0026 | Not Detected |
| Helium | 0.13 | Not Detected |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

eurofins | Air Toxics

**Client Sample ID: VMP-12-39-021513**

**Lab ID#: 1302355B-02A**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1946**

| | | | |
|---|---|---|---|
| **File Name:** | **9022811** | **Date of Collection:** | **2/15/13 10:56:00 AM** |
| **Dil. Factor:** | **2.42** | **Date of Analysis:** | **2/28/13 12:39 PM** |

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.24 | 1.5 |
| Nitrogen | 0.24 | 58 |
| Carbon Monoxide | 0.12 | Not Detected |
| Methane | 0.00024 | 26 |
| Carbon Dioxide | 0.024 | 14 |
| Ethane | 0.0024 | 0.00064 J |
| Ethene | 0.0024 | Not Detected |
| Helium | 0.12 | Not Detected |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

eurofins | Air Toxics

**Client Sample ID: VMP-16-5-021413**

**Lab ID#: 1302355B-03A**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1946**

| | | | |
|---|---|---|---|
| **File Name:** | **9022806** | **Date of Collection:** | **2/14/13 10:44:00 AM** |
| **Dil. Factor:** | **2.64** | **Date of Analysis:** | **2/28/13 10:13 AM** |

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.26 | 16 |
| Nitrogen | 0.26 | 80 |
| Carbon Monoxide | 0.13 | Not Detected |
| Methane | 0.00026 | 0.00010 J |
| Carbon Dioxide | 0.026 | 4.1 |
| Ethane | 0.0026 | Not Detected |
| Ethene | 0.0026 | Not Detected |
| Helium | 0.13 | 0.26 |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

eurofins | Air Toxics

**Client Sample ID: VMP-16-13.5-021413**

**Lab ID#: 1302355B-04A**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1946**

| | | | |
|---|---|---|---|
| **File Name:** | **9022810** | **Date of Collection:** | **2/14/13 11:43:00 AM** |
| **Dil. Factor:** | **2.69** | **Date of Analysis:** | **2/28/13 12:11 PM** |

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.27 | 1.3 |
| Nitrogen | 0.27 | 76 |
| Carbon Monoxide | 0.13 | Not Detected |
| Methane | 0.00027 | 9.2 |
| Carbon Dioxide | 0.027 | 13 |
| Ethane | 0.0027 | 0.00030 J |
| Ethene | 0.0027 | Not Detected |
| Helium | 0.13 | Not Detected |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

eurofins | Air Toxics

**Client Sample ID: VMP-16-19-021413**

**Lab ID#: 1302355B-05A**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1946**

| | | | |
|---|---|---|---|
| **File Name:** | **9022812** | **Date of Collection:** | **2/14/13 2:20:00 PM** |
| **Dil. Factor:** | **2.64** | **Date of Analysis:** | **2/28/13 01:29 PM** |

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.26 | 1.2 |
| Nitrogen | 0.26 | 59 |
| Carbon Monoxide | 0.13 | Not Detected |
| Methane | 0.00026 | 26 |
| Carbon Dioxide | 0.026 | 14 |
| Ethane | 0.0026 | 0.00076 J |
| Ethene | 0.0026 | Not Detected |
| Helium | 0.13 | Not Detected |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

eurofins | Air Toxics

**Client Sample ID: VMP-16-31-021813**

**Lab ID#: 1302355B-06A**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1946**

| | | | |
|---|---|---|---|
| **File Name:** | **9022813** | **Date of Collection:** | **2/18/13 3:02:00 PM** |
| **Dil. Factor:** | **3.19** | **Date of Analysis:** | **2/28/13 01:54 PM** |

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.32 | 0.97 |
| Nitrogen | 0.32 | 54 |
| Carbon Monoxide | 0.16 | Not Detected |
| Methane | 0.00032 | 30 |
| Carbon Dioxide | 0.032 | 15 |
| Ethane | 0.0032 | 0.00089 J |
| Ethene | 0.0032 | Not Detected |
| Helium | 0.16 | Not Detected |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

eurofins | Air Toxics

**Client Sample ID: VMP-55-20-021513**

**Lab ID#: 1302355B-07A**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1946**

| | | | |
|---|---|---|---|
| **File Name:** | **9022809** | **Date of Collection:** | **2/15/13 10:45:00 AM** |
| **Dil. Factor:** | **2.76** | **Date of Analysis:** | **2/28/13 11:44 AM** |

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.28 | 3.2 |
| Nitrogen | 0.28 | 69 |
| Carbon Monoxide | 0.14 | Not Detected |
| Methane | 0.00028 | 11 |
| Carbon Dioxide | 0.028 | 16 |
| Ethane | 0.0028 | 0.0046 |
| Ethene | 0.0028 | Not Detected |
| Helium | 0.14 | 0.17 |

**Container Type: 1 Liter Summa Canister**

eurofins | Air Toxics

**Client Sample ID: Lab Blank**

**Lab ID#: 1302355B-08A**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1946**

| | | | |
|---|---|---|---|
| **File Name:** | **9022805a** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 2/28/13 09:41 AM** | |

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.10 | 0.034 J |
| Nitrogen | 0.10 | 0.064 J |
| Carbon Monoxide | 0.050 | Not Detected |
| Methane | 0.00010 | Not Detected |
| Carbon Dioxide | 0.010 | Not Detected |
| Ethane | 0.0010 | Not Detected |
| Ethene | 0.0010 | Not Detected |

J = Estimated value.

**Container Type: NA - Not Applicable**

eurofins | Air Toxics

**Client Sample ID: Lab Blank**

**Lab ID#: 1302355B-08B**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1946**

| | | | |
|---|---|---|---|
| **File Name:** | **9022804b** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 2/28/13 09:19 AM** | |

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Helium | 0.050 | Not Detected |

**Container Type: NA - Not Applicable**

eurofins | Air Toxics

**Client Sample ID: LCS**

**Lab ID#: 1302355B-09A**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1946**

| | | | |
|---|---|---|---|
| **File Name:** | **9022802** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 2/28/13 08:23 AM** | |

| Compound | %Recovery |
|---|---|
| Oxygen | 101 |
| Nitrogen | 101 |
| Carbon Monoxide | 100 |
| Methane | 99 |
| Carbon Dioxide | 102 |
| Ethane | 101 |
| Ethene | 98 |
| Helium | 102 |

**Container Type: NA - Not Applicable**

eurofins | Air Toxics

**Client Sample ID: LCSD**

**Lab ID#: 1302355B-09AA**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1946**

| | | | |
|---|---|---|---|
| **File Name:** | **9022816** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 2/28/13 03:17 PM** | |

| Compound | %Recovery |
|---|---|
| Oxygen | 100 |
| Nitrogen | 99 |
| Carbon Monoxide | 98 |
| Methane | 99 |
| Carbon Dioxide | 101 |
| Ethane | 100 |
| Ethene | 98 |
| Helium | 100 |

**Container Type: NA - Not Applicable**

1302355

# Shell Oil Products Chain Of Custody Record

URS

Air Toxics LTD.
Project Name: Roxana Soil Vapor
Project # 21562850.04001
Lab Vendor #

Please Check Appropriate Box:
☑ ENV. SERVICES ☐ MOTIVA RETAIL ☐ SHELL RETAIL
☐ MOTIVA SOA/CM ☐ CONSULTANT ☐ Lubes
☐ SHELL PIPELINE ☐ OTHER

Print Bill To Contact Name: Robert Mooshegian

INCIDENT # (ENV SERVICES): 9 7 2 1 6 6 4 0
RQ #:
SAP #: 3 4 0 0 8 1

☐ CHECK IF NO INCIDENT # APPLIES
DATE 02/18/13
PAGE ___1___ of ___1___

SAMPLING COMPANY: URS CORPORATION
ADDRESS: 1031 HIGHLANDS PLAZA DRIVE WEST - SUITE 300; ST. LOUIS, MO 63110
LOCATION ADDRESS: Air Toxics, LTD 180 Blue Ravine Road, Suite B, Folsom, CA 95630-4719
TELEPHONE: 314-429-0100
FAX: 314-429-0462
BILL TO CONTACT EMAIL: Robert.Mooshegian@urs.com

SITE ADDRESS (Street and City): 900 SOUTH CENTRAL AVE – ROXANA
STATE: IL
GLOBAL ID NO.:
CONSULTANT/CONTACT NAME: Elizabeth Kunkel, URS, St. Louis
PHONE NO.: 314-743-4179
E-MAIL: Elizabeth.Kunkel@URS.com
CONSULTANT/CONTACT MANAGER: Roxana Soil Vapor
C. Kreitzer, D. Mattingly, T. Carroll, C. Williams, M. Currier, B. Lahan, L. Rathnow.

TURNAROUND TIME (CALENDAR DAYS):
☑ STANDARD (14 DAY) ☐ 5 DAYS ☐ 3 DAYS ☐ 2 DAYS ☐ 24 HOURS ☐ RESULTS NEEDED ON WEEKEND

☐ LA - RWQCB REPORT FORMAT ☑ UST AGENCY:

DELIVERABLES: ☐ LEVEL 1 ☐ LEVEL 2 ☐ LEVEL 3 ☑ LEVEL 4 ☐ OTHER (SPECIFY)

☑ SHELL CONTRACT RATE APPLIES
☐ STATE REIMBURSEMENT RATE APPLIES
☐ ROD NOT NEEDED
☑ RECEIPT VERIFICATION REQUESTED

REQUESTED ANALYSIS

| Lab Use Only | Field Sample Identification | Sampling Date | Sampling Time | Canister Number | Canister Pressure/Vacuum: Initial | Final | Receipt | Final (psig) | Modified TO-15 + Butane & isopentane | ASTM D-1946 + Helium | ASTM D-1945 | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| 01A | VMP-12-25-021513 | 02/15/13 | 1123-1153 | 22966 | -30 | -7.5 | | | X | X | | | | | | |
| 02A | VMP-12-38-021513 | 02/15/13 | 1026-1056 | 37320 | -30 | -6 | | | X | X | | | | | | |
| 03A | VMP-16-5-021413 | 02/14/13 | 1014-1044 | 24395 | -29 | -9 | | | X | X | | | | | | |
| 04A | VMP-16-13.5-021413 | 02/14/13 | 1113-1143 | 3766* | -30 | -7.5 | | | X | X | | | | | | |
| 05A | VMP-16-19-021413 | 02/14/13 | 1350-1420 | 37735 | -30 | -7 | | | X | X | | | | | | |
| 06A | VMP-16-31-021813 | 02/18/13 | 1432-1502 | 12285 | -28.5 | -12 | | | X | X | | | | | | |
| 07A | VMP-55-20-021513 | 02/15/13 | 1003-1045 | 12264 | -30 | -11.5 | | | X | X | | | | | | |

Turn Around Time:
☑ Normal
☐ Rush
Specify

Lab Use Only
Pressurized by:
Date:
Pressurization Gas: N2 He

ADDITIONAL NOTES:
- 14 day hold time
- Report results between MDL and RL
- Level IV ECVP
- DNA CANISTER 15723 - High helium

FedEx
Custody Seal Intact?
(Y) N None Temp NA

| Relinquished by: (Signature) | Received by: (Signature) | Date | Time |
|---|---|---|---|
| | FEDEX | 2/19/13 | 1730 |
| Relinquished by: (Signature) | Received by: (Signature) | Date | Time |
| | Rachel Jacky ATC | 02/20/13 | 1000 |
| Relinquished by: (Signature) | Received by: (Signature) | Date | Time |
| | | | |

# Roxana Soil Vapor Quarterly – 1st Quarter 2013 Data Review

**Laboratory SDG: 1302356A,B**

**Data Reviewer: Alan Fleisher**

**Peer Reviewer: Elizabeth Kunkel**

**Date Reviewed: 3/25/2013**

**Guidance: USEPA National Functional Guidelines for Superfund Organic Methods Data Review 2008**

| Sample Identification | Sample Identification |
|---|---|
| VMP-9-5-021513 | VMP-12-5-021813 |
| VMP-12-11.5-021813 | VMP-31-10-021313 |
| VMP-51-20-021513-R | |

## 1.0 Data Package Completeness

*Were all items delivered as specified in the QAPP and COC as appropriate?*

Yes

## 2.0 Laboratory Case Narrative \ Cooler Receipt Form

*Were problems noted in the laboratory case narrative or cooler receipt form?*

Sample VMP-31-10-021313 was logged incorrectly by the laboratory. The sample ID was manually changed by the data reviewer. Although not indicated in the laboratory case narrative, analytes were detected in the method blank. The TO-15 LCS/LCSD recoveries for 1,2,4-trichlorobenzene were outside evaluation criteria. CCV recoveries for 1,2,4-trimethylbenzene were outside evaluation criteria. These issues are addressed further in the appropriate sections below.

No issues or discrepancies were noted in the cooler receipt form.

## 3.0 Holding Times

*Were samples extracted/analyzed within applicable limits?*

Yes

## 4.0 Blank Contamination

*Were any analytes detected in the Blanks?*

Yes

| Blank ID | Parameter | Analyte | Concentration/ Amount |
|---|---|---|---|
| 1302356A-06A | TO-15 | Bromomethane | 0.35 ppbv / 1.4 µg/m$^3$ |
| 1302356A-06A | TO-15 | Methylene chloride | 0.077 ppbv / 0.27 µg/m$^3$ |
| 1302356A-06A | TO-15 | Trans-1,3-Dichloropropene | 0.071 ppbv / 0.32 µg/m$^3$ |
| 1302356A-06A | TO-15 | 1,4-Dichlorobenzene | 0.068 ppbv / 0.41 µg/m$^3$ |
| 1302356B-06A | Natural gases | Nitrogen | 0.045% |

Qualifications due to blank contamination are included in the table below. Analytical data that were reported non-detect or at concentrations greater than five times (5X) the associated blank concentration did not require qualification.

| Sample ID | Parameter | Analyte | New Reporting Limit (RL) | Qualification |
|---|---|---|---|---|
| VMP-9-5-021513 | TO-15 | 1,4-Dichlorobenzene | - | **U** |
| VMP-9-5-021513 | TO-15 | Trans-1,3-Dichloropropene | - | **U** |
| VMP-12-5-021813 | TO-15 | 1,4-Dichlorobenzene | - | **U** |
| VMP-12-5-021813 | TO-15 | Trans-1,3-Dichloropropene | - | **U** |
| VMP-31-10-021313 | TO-15 | Methylene chloride | - | **U** |
| VMP-31-10-021313 | TO-15 | Trans-1,3-Dichloropropene | - | **U** |
| VMP-31-10-021313 | TO-15 | 1,4-Dichlorobenzene | - | **U** |
| VMP-51-20-021513-R | TO-15 | Methylene chloride | - | **U** |
| VMP-51-20-021513-R | TO-15 | 1,4-Dichlorobenzene | - | **U** |

## 5.0 Laboratory Control Sample

*Were LCS recoveries within evaluation criteria?*

No

| LCS/LCSD ID | Parameter | Analyte | LCS/LCSD Recovery | LCS/ LCSD RPD | LCS/LCSD /RPD Criteria |
|---|---|---|---|---|---|
| 1302356A-08A/AA | TO-15 | 1,2,4-Trichlorobenzene | **132/135** | 2 | 70-130/25 |

Analytical data reported as non-detect and associated with LCS recoveries above evaluation criteria, indicating a possible high bias, did not require qualification. Associated positive detections were previously qualified based on CCV recoveries; further action was not required.

## 6.0 Surrogate Recoveries

*Were surrogate recoveries within evaluation criteria?*

Yes

## 7.0 Matrix Spike and Matrix Spike Duplicate Recoveries

*Were MS/MSD samples analyzed as part of this SDG?*

MS/MSD samples are not applicable for vapor samples, due to the inability to spike the samples.

## 8.0 Laboratory Duplicate Results

No

## 9.0 Field Duplicate Results

*Were field duplicate samples collected as part of this SDG?*

No

## 10.0 Sample Dilutions

*For samples that were diluted and nondetect, were undiluted results also reported?*

Not applicable; analytes were detected in samples that were diluted.

## 11.0 Additional Qualifications

*Were additional qualifications applied?*

Yes, continuing calibration verification (CCV) recoveries listed in the table below were above evaluation criteria.

| CCV ID | Parameter | Analyte | CCV Recovery | CCV Criteria |
|---|---|---|---|---|
| 1302356A-07A | TO-15 | 1,2,4-Trimethylbenzene | **131** | 70-130 |

Analytical data that required qualification based on CCV data are included in the table below. Analytical data reported as non-detect and associated with CCV recoveries above evaluation criteria, indicating a possible high bias, did not require qualification.

| Field ID | Parameter | Analyte | Qualification |
|---|---|---|---|
| VMP-9-5-021513 | TO-15 | 1,2,4-Trimethylbenzene | **J** |
| VMP-12-5-021813 | TO-15 | 1,2,4-Trimethylbenzene | **J** |
| VMP-31-10-021313 | TO-15 | 1,2,4-Trimethylbenzene | **J** |
| VMP-51-20-021513-R | TO-15 | 1,2,4-Trimethylbenzene | **J** |

eurofins | Air Toxics

3/5/2013
Ms. Elizabeth Kunkel
URS Corporation
1001 Highlands Plaza Dr. West
Suite 300
St. Louis MO 63110

Project Name: Roxana Soil Vapor
Project #: 21562850.04001
Workorder #: 1302356A

Dear Ms. Elizabeth Kunkel

The following report includes the data for the above referenced project for sample(s) received on 2/20/2013 at Air Toxics Ltd.

The data and associated QC analyzed by Modified TO-15 are compliant with the project requirements or laboratory criteria with the exception of the deviations noted in the attached case narrative.

Thank you for choosing Air Toxics Ltd. for your air analysis needs. Air Toxics Ltd. is committed to providing accurate data of the highest quality. Please feel free to contact the Project Manager: Kelly Buettner at 916-985-1000 if you have any questions regarding the data in this report.

REVIEWED
ON
3/25/13

Regards,

Kelly Buettner

Kelly Buettner
Project Manager

eurofins | Air Toxics

# WORK ORDER #: 1302356A

Work Order Summary

| | | | |
|---|---|---|---|
| **CLIENT:** | Ms. Elizabeth Kunkel<br>URS Corporation<br>1001 Highlands Plaza Dr. West<br>Suite 300<br>St. Louis, MO 63110 | **BILL TO:** | Accounts Payable Austin<br>URS Corporation<br>P.O. BOX 203970<br>Austin, TX 78720-1088 |
| **PHONE:** | 314-743-4179 | **P.O. #** | 21562735.00013 |
| **FAX:** | | **PROJECT #** | 21562850.04001 Roxana Soil Vapor |
| **DATE RECEIVED:** | 02/20/2013 | **CONTACT:** | Kelly Buettner |
| **DATE COMPLETED:** | 03/05/2013 | | |

| FRACTION # | NAME | TEST | RECEIPT VAC./PRES. | FINAL PRESSURE |
|---|---|---|---|---|
| 01A | VMP-9-5-021513 | Modified TO-15 | 8.0 "Hg | 15 psi |
| 02A | VMP-12-5-021813 | Modified TO-15 | 7.5 "Hg | 15 psi |
| 03A | VMP-12-11.5-021813 | Modified TO-15 | 9.0 "Hg | 15 psi |
| 04A | ~~VMP-31-10-021313~~ | Modified TO-15 | 8.5 "Hg | 15 psi |
| 05A | VMP-51-20-021513-R | Modified TO-15 | 7.0 "Hg | 15 psi |
| 06A | Lab Blank | Modified TO-15 | NA | NA |
| 07A | CCV | Modified TO-15 | NA | NA |
| 08A | LCS | Modified TO-15 | NA | NA |
| 08AA | LCSD | Modified TO-15 | NA | NA |

VMP-31-10-021313 (AF)

CERTIFIED BY: Heidi Mayo DATE: 03/05/13

Technical Director

Certfication numbers: AZ Licensure AZ0775, CA NELAP - 12282CA, NY NELAP - 11291,
TX NELAP - T104704434-12-5, UT NELAP CA009332012-3, WA NELAP - C935
Name of Accrediting Agency: NELAP/ORELAP (Oregon Environmental Laboratory Accreditation Program)
Accreditation number: CA300005, Effective date: 10/18/2011, Expiration date: 10/17/2012.
Eurofins Air Toxics Ltd. certifies that the test results contained in this report meet all requirements of the NELAC standards

This report shall not be reproduced, except in full, without the written approval of Eurofins Air Toxics, Inc.

180 BLUE RAVINE ROAD, SUITE B FOLSOM, CA - 9563
(916) 985-1000 . (800) 985-5955 . FAX (916) 985-1020

**LABORATORY NARRATIVE**
**EPA Method TO-15**
**URS Corporation**
**Workorder# 1302356A**

Five 1 Liter Summa Canister samples were received on February 20, 2013. The laboratory performed analysis via EPA Method TO-15 using GC/MS in the full scan mode.

This workorder was independently validated prior to submittal using 'USEPA National Functional Guidelines' as generally applied to the analysis of volatile organic compounds in air. A rules-based, logic driven, independent validation engine was employed to assess completeness, evaluate pass/fail of relevant project quality control requirements and verification of all quantified amounts.

**Receiving Notes**

There were no receiving discrepancies.

**Analytical Notes**

As per client project requirements, the laboratory has reported estimated values for target compound hits that are below the Reporting Limit but greater than the Method Detection Limit. Concentrations that are below the level at which the canister was certified (0.2 ppbv for compounds reported at 0.5 ppbv and 0.8 ppbv for compounds reported at 2.0 ppbv) may be false positives.

All Quality Control Limit exceedances and affected sample results are noted by flags. Each flag is defined at the bottom of this Case Narrative and on each Sample Result Summary page. Target compound non-detects in the samples that are associated with high bias in QC analyses have not been flagged.

**Definition of Data Qualifying Flags**

Eight qualifiers may have been used on the data analysis sheets and indicates as follows:

B - Compound present in laboratory blank greater than reporting limit (background subtraction not performed).
J - Estimated value.
E - Exceeds instrument calibration range.
S - Saturated peak.
Q - Exceeds quality control limits.
U - Compound analyzed for but not detected above the reporting limit.
UJ- Non-detected compound associated with low bias in the CCV and/or LCS.
N - The identification is based on presumptive evidence.

File extensions may have been used on the data analysis sheets and indicates as follows:
a-File was requantified
b-File was quantified by a second column and detector
r1-File was requantified for the purpose of reissue

eurofins | Air Toxics

# Summary of Detected Compounds
# EPA METHOD TO-15 GC/MS FULL SCAN

**Client Sample ID: VMP-9-5-021513**

**Lab ID#: 1302356A-01A**

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 1.4 | 0.46 J | 6.8 | 2.3 J |
| Freon 11 | 1.4 | 0.24 J | 7.8 | 1.4 J |
| Acetone | 14 | 3.3 J | 33 | 7.8 J |
| 2-Propanol | 5.5 | 6.7 | 14 | 16 |
| Methyl tert-butyl ether | 1.4 | 0.32 J | 5.0 | 1.2 J |
| Hexane | 1.4 | 1.1 J | 4.9 | 4.0 J |
| Cyclohexane | 1.4 | 0.86 J | 4.8 | 3.0 J |
| 2,2,4-Trimethylpentane | 1.4 | 44 | 6.4 | 210 |
| Benzene | 1.4 | 3.7 | 4.4 | 12 |
| Toluene | 1.4 | 0.22 J | 5.2 | 0.82 J |
| trans-1,3-Dichloropropene | 1.4 | ~~0.22 J~~ U | 6.3 | ~~0.98 J~~ U |
| Ethyl Benzene | 1.4 | 0.62 J | 6.0 | 2.7 J |
| m,p-Xylene | 1.4 | 0.35 J | 6.0 | 1.5 J |
| Cumene | 1.4 | 0.65 J | 6.8 | 3.2 J |
| Propylbenzene | 1.4 | 1.6 | 6.8 | 7.6 |
| 4-Ethyltoluene | 1.4 | 0.66 J | 6.8 | 3.2 J |
| 1,2,4-Trimethylbenzene | 1.4 | 2.8 J J | 6.8 | 14 J J |
| 1,4-Dichlorobenzene | 1.4 | ~~0.24 J~~ U | 8.3 | ~~1.4 J~~ U |
| Butane | 5.5 | 4.1 J | 13 | 9.8 J |
| Isopentane | 5.5 | 15 | 16 | 44 |

**Client Sample ID: VMP-12-5-021813**

**Lab ID#: 1302356A-02A**

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 1.3 | 0.57 J | 6.6 | 2.8 J |
| Freon 11 | 1.3 | 0.25 J | 7.6 | 1.4 J |
| Ethanol | 5.4 | 2.2 J | 10 | 4.2 J |
| Acetone | 13 | 4.0 J | 32 | 9.6 J |
| 2-Propanol | 5.4 | 4.8 J | 13 | 12 J |
| Methylene Chloride | 13 | 0.55 J | 47 | 1.9 J |
| Hexane | 1.3 | 0.98 J | 4.7 | 3.4 J |
| 2-Butanone (Methyl Ethyl Ketone) | 5.4 | 1.3 J | 16 | 3.8 J |

eurofins | Air Toxics

# Summary of Detected Compounds
# EPA METHOD TO-15 GC/MS FULL SCAN

**Client Sample ID: VMP-12-5-021813**

**Lab ID#: 1302356A-02A**

| | | | | |
|---|---|---|---|---|
| Cyclohexane | 1.3 | 0.64 J | 4.6 | 2.2 J |
| 2,2,4-Trimethylpentane | 1.3 | 23 | 6.3 | 110 |
| Benzene | 1.3 | 3.7 | 4.3 | 12 |
| 4-Methyl-2-pentanone | 1.3 | 2.0 | 5.5 | 8.1 |
| Toluene | 1.3 | 0.56 J | 5.1 | 2.1 J |
| trans-1,3-Dichloropropene | 1.3 | ~~0.21 J~~ U | 6.1 | ~~0.97 J~~ U |
| m,p-Xylene | 1.3 | 0.28 J | 5.8 | 1.2 J |
| Cumene | 1.3 | 0.35 J | 6.6 | 1.7 J |
| Propylbenzene | 1.3 | 0.40 J | 6.6 | 2.0 J |
| 1,2,4-Trimethylbenzene | 1.3 | 0.42 J J | 6.6 | 2.1 J J |
| 1,4-Dichlorobenzene | 1.3 | ~~0.22 J~~ U | 8.1 | ~~1.4 J~~ U |
| Butane | 5.4 | 3.1 J | 13 | 7.4 J |
| Isopentane | 5.4 | 8.7 | 16 | 26 |

**Client Sample ID: VMP-12-11.5-021813**

**Lab ID#: 1302356A-03A**

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 1.4 | 0.47 J | 7.1 | 2.3 J |
| Acetone | 14 | 4.1 J | 34 | 9.7 J |
| 2-Propanol | 5.8 | 5.4 J | 14 | 13 J |
| Hexane | 1.4 | 0.28 J | 5.1 | 0.98 J |
| 2,2,4-Trimethylpentane | 1.4 | 0.34 J | 6.8 | 1.6 J |
| Benzene | 1.4 | 0.25 J | 4.6 | 0.80 J |
| Trichloroethene | 1.4 | 0.36 J | 7.8 | 1.9 J |
| Toluene | 1.4 | 0.25 J | 5.4 | 0.94 J |

**Client Sample ID: VMP--31-10-021313**

**Lab ID#: 1302356A-04A**

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 1.4 | 0.42 J | 7.0 | 2.1 J |
| Bromomethane | 14 | 1.0 J | 55 | 3.9 J |
| Ethanol | 5.6 | 4.2 J | 11 | 7.9 J |

eurofins | Air Toxics

# Summary of Detected Compounds
# EPA METHOD TO-15 GC/MS FULL SCAN

VMP-31-10-021313 (AF)

**Client Sample ID: ~~VMP-31-10-021313~~**

**Lab ID#: 1302356A-04A**

| | | | | |
|---|---|---|---|---|
| Acetone | 14 | 7.5 J | 33 | 18 J |
| Methylene Chloride | 14 | ~~0.23 J~~ U | 49 | ~~0.82 J~~ U |
| Hexane | 1.4 | 4.6 | 5.0 | 16 |
| 2-Butanone (Methyl Ethyl Ketone) | 5.6 | 1.2 J | 17 | 3.7 J |
| Cyclohexane | 1.4 | 1.2 J | 4.8 | 4.0 J |
| 2,2,4-Trimethylpentane | 1.4 | 11 | 6.6 | 50 |
| Benzene | 1.4 | 7.4 | 4.5 | 24 |
| Heptane | 1.4 | 1.8 | 5.8 | 7.5 |
| 4-Methyl-2-pentanone | 1.4 | 0.82 J | 5.8 | 3.3 J |
| Toluene | 1.4 | 4.1 | 5.3 | 16 |
| trans-1,3-Dichloropropene | 1.4 | ~~0.21 J~~ U | 6.4 | ~~0.97 J~~ U |
| Ethyl Benzene | 1.4 | 3.0 | 6.1 | 13 |
| m,p-Xylene | 1.4 | 9.4 | 6.1 | 41 |
| o-Xylene | 1.4 | 3.6 | 6.1 | 16 |
| Cumene | 1.4 | 0.52 J | 6.9 | 2.6 J |
| Propylbenzene | 1.4 | 0.85 J | 6.9 | 4.2 J |
| 4-Ethyltoluene | 1.4 | 2.4 | 6.9 | 12 |
| 1,3,5-Trimethylbenzene | 1.4 | 0.73 J | 6.9 | 3.6 J |
| 1,2,4-Trimethylbenzene | 1.4 | 1.6 J J | 6.9 | 8.0 J J |
| 1,4-Dichlorobenzene | 1.4 | ~~0.17 J~~ U | 8.5 | ~~1.0 J~~ U |
| Butane | 5.6 | 44 | 13 | 100 |
| Isopentane | 5.6 | 39 | 17 | 120 |

**Client Sample ID: VMP-51-20-021513-R**

**Lab ID#: 1302356A-05A**

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 1.3 | 0.52 J | 6.5 | 2.6 J |
| Freon 11 | 1.3 | 0.24 J | 7.4 | 1.3 J |
| Ethanol | 5.3 | 2.9 J | 9.9 | 5.4 J |
| Acetone | 13 | 5.3 J | 31 | 13 J |
| 2-Propanol | 5.3 | 4.6 J | 13 | 11 J |
| Methylene Chloride | 13 | ~~0.25 J~~ U | 46 | ~~0.87 J~~ U |
| Hexane | 1.3 | 0.33 J | 4.6 | 1.2 J |
| Chloroform | 1.3 | 4.2 | 6.4 | 20 |

eurofins | Air Toxics

# Summary of Detected Compounds
# EPA METHOD TO-15 GC/MS FULL SCAN

**Client Sample ID: VMP-51-20-021513-R**

**Lab ID#: 1302356A-05A**

| | | | | |
|---|---|---|---|---|
| Cyclohexane | 1.3 | 0.40 J | 4.5 | 1.4 J |
| 2,2,4-Trimethylpentane | 1.3 | 17 | 6.2 | 78 |
| Benzene | 1.3 | 1.6 | 4.2 | 5.3 |
| Toluene | 1.3 | 0.17 J | 5.0 | 0.65 J |
| Tetrachloroethene | 1.3 | 0.18 J | 9.0 | 1.2 J |
| Ethyl Benzene | 1.3 | 1.0 J | 5.7 | 4.5 J |
| m,p-Xylene | 1.3 | 0.52 J | 5.7 | 2.2 J |
| Cumene | 1.3 | 0.57 J | 6.5 | 2.8 J |
| Propylbenzene | 1.3 | 1.5 | 6.5 | 7.4 |
| 4-Ethyltoluene | 1.3 | 0.38 J | 6.5 | 1.9 J |
| 1,2,4-Trimethylbenzene | 1.3 | 0.99 J J | 6.5 | 4.9 J J |
| 1,4-Dichlorobenzene | 1.3 | ~~0.20 J~~ U | 7.9 | ~~1.2 J~~ U |
| Isopentane | 5.3 | 2.9 J | 16 | 8.6 J |

eurofins | Air Toxics

**Client Sample ID: VMP-9-5-021513**

**Lab ID#: 1302356A-01A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **3022613** | **Date of Collection:** | **2/15/13 11:53:00 AM** |
| **Dil. Factor:** | **2.76** | **Date of Analysis:** | **2/26/13 05:17 PM** |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 1.4 | 0.46 J | 6.8 | 2.3 J |
| Freon 114 | 1.4 | Not Detected | 9.6 | Not Detected |
| Chloromethane | 14 | Not Detected | 28 | Not Detected |
| Vinyl Chloride | 1.4 | Not Detected | 3.5 | Not Detected |
| 1,3-Butadiene | 1.4 | Not Detected | 3.0 | Not Detected |
| Bromomethane | 14 | Not Detected | 54 | Not Detected |
| Chloroethane | 5.5 | Not Detected | 14 | Not Detected |
| Freon 11 | 1.4 | 0.24 J | 7.8 | 1.4 J |
| Ethanol | 5.5 | Not Detected | 10 | Not Detected |
| Freon 113 | 1.4 | Not Detected | 10 | Not Detected |
| 1,1-Dichloroethene | 1.4 | Not Detected | 5.5 | Not Detected |
| Acetone | 14 | 3.3 J | 33 | 7.8 J |
| 2-Propanol | 5.5 | 6.7 | 14 | 16 |
| Carbon Disulfide | 5.5 | Not Detected | 17 | Not Detected |
| 3-Chloropropene | 5.5 | Not Detected | 17 | Not Detected |
| Methylene Chloride | 14 | Not Detected | 48 | Not Detected |
| Methyl tert-butyl ether | 1.4 | 0.32 J | 5.0 | 1.2 J |
| trans-1,2-Dichloroethene | 1.4 | Not Detected | 5.5 | Not Detected |
| Hexane | 1.4 | 1.1 J | 4.9 | 4.0 J |
| 1,1-Dichloroethane | 1.4 | Not Detected | 5.6 | Not Detected |
| 2-Butanone (Methyl Ethyl Ketone) | 5.5 | Not Detected | 16 | Not Detected |
| cis-1,2-Dichloroethene | 1.4 | Not Detected | 5.5 | Not Detected |
| Tetrahydrofuran | 1.4 | Not Detected | 4.1 | Not Detected |
| Chloroform | 1.4 | Not Detected | 6.7 | Not Detected |
| 1,1,1-Trichloroethane | 1.4 | Not Detected | 7.5 | Not Detected |
| Cyclohexane | 1.4 | 0.86 J | 4.8 | 3.0 J |
| Carbon Tetrachloride | 1.4 | Not Detected | 8.7 | Not Detected |
| 2,2,4-Trimethylpentane | 1.4 | 44 | 6.4 | 210 |
| Benzene | 1.4 | 3.7 | 4.4 | 12 |
| 1,2-Dichloroethane | 1.4 | Not Detected | 5.6 | Not Detected |
| Heptane | 1.4 | Not Detected | 5.6 | Not Detected |
| Trichloroethene | 1.4 | Not Detected | 7.4 | Not Detected |
| 1,2-Dichloropropane | 1.4 | Not Detected | 6.4 | Not Detected |
| 1,4-Dioxane | 5.5 | Not Detected | 20 | Not Detected |
| Bromodichloromethane | 1.4 | Not Detected | 9.2 | Not Detected |
| cis-1,3-Dichloropropene | 1.4 | Not Detected | 6.3 | Not Detected |
| 4-Methyl-2-pentanone | 1.4 | Not Detected | 5.6 | Not Detected |
| Toluene | 1.4 | 0.22 J | 5.2 | 0.82 J |
| trans-1,3-Dichloropropene | 1.4 | ~~0.22 J~~ | 6.3 | ~~0.98 J~~ |
| 1,1,2-Trichloroethane | 1.4 | Not Detected | 7.5 | Not Detected |
| Tetrachloroethene | 1.4 | Not Detected | 9.4 | Not Detected |
| 2-Hexanone | 5.5 | Not Detected | 23 | Not Detected |

eurofins | Air Toxics

**Client Sample ID: VMP-9-5-021513**

**Lab ID#: 1302356A-01A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **3022613** | **Date of Collection:** | **2/15/13 11:53:00 AM** |
| **Dil. Factor:** | **2.76** | **Date of Analysis:** | **2/26/13 05:17 PM** |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Dibromochloromethane | 1.4 | Not Detected | 12 | Not Detected |
| 1,2-Dibromoethane (EDB) | 1.4 | Not Detected | 11 | Not Detected |
| Chlorobenzene | 1.4 | Not Detected | 6.4 | Not Detected |
| Ethyl Benzene | 1.4 | 0.62 J | 6.0 | 2.7 J |
| m,p-Xylene | 1.4 | 0.35 J | 6.0 | 1.5 J |
| o-Xylene | 1.4 | Not Detected | 6.0 | Not Detected |
| Styrene | 1.4 | Not Detected | 5.9 | Not Detected |
| Bromoform | 1.4 | Not Detected | 14 | Not Detected |
| Cumene | 1.4 | 0.65 J | 6.8 | 3.2 J |
| 1,1,2,2-Tetrachloroethane | 1.4 | Not Detected | 9.5 | Not Detected |
| Propylbenzene | 1.4 | 1.6 | 6.8 | 7.6 |
| 4-Ethyltoluene | 1.4 | 0.66 J | 6.8 | 3.2 J |
| 1,3,5-Trimethylbenzene | 1.4 | Not Detected | 6.8 | Not Detected |
| 1,2,4-Trimethylbenzene | 1.4 | 2.8 J J | 6.8 | 14 J J |
| 1,3-Dichlorobenzene | 1.4 | Not Detected | 8.3 | Not Detected |
| 1,4-Dichlorobenzene | 1.4 | ~~0.24 J~~ U | 8.3 | ~~1.4 J~~ U |
| alpha-Chlorotoluene | 1.4 | Not Detected | 7.1 | Not Detected |
| 1,2-Dichlorobenzene | 1.4 | Not Detected | 8.3 | Not Detected |
| 1,2,4-Trichlorobenzene | 5.5 | Not Detected | 41 | Not Detected |
| Hexachlorobutadiene | 5.5 | Not Detected | 59 | Not Detected |
| Butane | 5.5 | 4.1 J | 13 | 9.8 J |
| Isopentane | 5.5 | 15 | 16 | 44 |

J = Estimated value.
J = Estimated value due to bias in the CCV.
**Container Type: 1 Liter Summa Canister**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| Toluene-d8 | 104 | 70-130 |
| 1,2-Dichloroethane-d4 | 94 | 70-130 |
| 4-Bromofluorobenzene | 94 | 70-130 |

eurofins | Air Toxics

**Client Sample ID: VMP-12-5-021813**

**Lab ID#: 1302356A-02A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **3022612** | **Date of Collection:** | **2/18/13 10:25:00 AM** |
| **Dil. Factor:** | **2.69** | **Date of Analysis:** | **2/26/13 04:46 PM** |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 1.3 | 0.57 J | 6.6 | 2.8 J |
| Freon 114 | 1.3 | Not Detected | 9.4 | Not Detected |
| Chloromethane | 13 | Not Detected | 28 | Not Detected |
| Vinyl Chloride | 1.3 | Not Detected | 3.4 | Not Detected |
| 1,3-Butadiene | 1.3 | Not Detected | 3.0 | Not Detected |
| Bromomethane | 13 | Not Detected | 52 | Not Detected |
| Chloroethane | 5.4 | Not Detected | 14 | Not Detected |
| Freon 11 | 1.3 | 0.25 J | 7.6 | 1.4 J |
| Ethanol | 5.4 | 2.2 J | 10 | 4.2 J |
| Freon 113 | 1.3 | Not Detected | 10 | Not Detected |
| 1,1-Dichloroethene | 1.3 | Not Detected | 5.3 | Not Detected |
| Acetone | 13 | 4.0 J | 32 | 9.6 J |
| 2-Propanol | 5.4 | 4.8 J | 13 | 12 J |
| Carbon Disulfide | 5.4 | Not Detected | 17 | Not Detected |
| 3-Chloropropene | 5.4 | Not Detected | 17 | Not Detected |
| Methylene Chloride | 13 | 0.55 J | 47 | 1.9 J |
| Methyl tert-butyl ether | 1.3 | Not Detected | 4.8 | Not Detected |
| trans-1,2-Dichloroethene | 1.3 | Not Detected | 5.3 | Not Detected |
| Hexane | 1.3 | 0.98 J | 4.7 | 3.4 J |
| 1,1-Dichloroethane | 1.3 | Not Detected | 5.4 | Not Detected |
| 2-Butanone (Methyl Ethyl Ketone) | 5.4 | 1.3 J | 16 | 3.8 J |
| cis-1,2-Dichloroethene | 1.3 | Not Detected | 5.3 | Not Detected |
| Tetrahydrofuran | 1.3 | Not Detected | 4.0 | Not Detected |
| Chloroform | 1.3 | Not Detected | 6.6 | Not Detected |
| 1,1,1-Trichloroethane | 1.3 | Not Detected | 7.3 | Not Detected |
| Cyclohexane | 1.3 | 0.64 J | 4.6 | 2.2 J |
| Carbon Tetrachloride | 1.3 | Not Detected | 8.5 | Not Detected |
| 2,2,4-Trimethylpentane | 1.3 | 23 | 6.3 | 110 |
| Benzene | 1.3 | 3.7 | 4.3 | 12 |
| 1,2-Dichloroethane | 1.3 | Not Detected | 5.4 | Not Detected |
| Heptane | 1.3 | Not Detected | 5.5 | Not Detected |
| Trichloroethene | 1.3 | Not Detected | 7.2 | Not Detected |
| 1,2-Dichloropropane | 1.3 | Not Detected | 6.2 | Not Detected |
| 1,4-Dioxane | 5.4 | Not Detected | 19 | Not Detected |
| Bromodichloromethane | 1.3 | Not Detected | 9.0 | Not Detected |
| cis-1,3-Dichloropropene | 1.3 | Not Detected | 6.1 | Not Detected |
| 4-Methyl-2-pentanone | 1.3 | 2.0 | 5.5 | 8.1 |
| Toluene | 1.3 | 0.56 J | 5.1 | 2.1 J |
| trans-1,3-Dichloropropene | 1.3 | ~~0.21 J~~ | 6.1 | ~~0.97 J~~ |
| 1,1,2-Trichloroethane | 1.3 | Not Detected | 7.3 | Not Detected |
| Tetrachloroethene | 1.3 | Not Detected | 9.1 | Not Detected |
| 2-Hexanone | 5.4 | Not Detected | 22 | Not Detected |

eurofins | Air Toxics

**Client Sample ID: VMP-12-5-021813**

**Lab ID#: 1302356A-02A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **3022612** | **Date of Collection:** | **2/18/13 10:25:00 AM** |
| **Dil. Factor:** | **2.69** | **Date of Analysis:** | **2/26/13 04:46 PM** |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Dibromochloromethane | 1.3 | Not Detected | 11 | Not Detected |
| 1,2-Dibromoethane (EDB) | 1.3 | Not Detected | 10 | Not Detected |
| Chlorobenzene | 1.3 | Not Detected | 6.2 | Not Detected |
| Ethyl Benzene | 1.3 | Not Detected | 5.8 | Not Detected |
| m,p-Xylene | 1.3 | 0.28 J | 5.8 | 1.2 J |
| o-Xylene | 1.3 | Not Detected | 5.8 | Not Detected |
| Styrene | 1.3 | Not Detected | 5.7 | Not Detected |
| Bromoform | 1.3 | Not Detected | 14 | Not Detected |
| Cumene | 1.3 | 0.35 J | 6.6 | 1.7 J |
| 1,1,2,2-Tetrachloroethane | 1.3 | Not Detected | 9.2 | Not Detected |
| Propylbenzene | 1.3 | 0.40 J | 6.6 | 2.0 J |
| 4-Ethyltoluene | 1.3 | Not Detected | 6.6 | Not Detected |
| 1,3,5-Trimethylbenzene | 1.3 | Not Detected | 6.6 | Not Detected |
| 1,2,4-Trimethylbenzene | 1.3 | 0.42 J J | 6.6 | 2.1 J J |
| 1,3-Dichlorobenzene | 1.3 | Not Detected | 8.1 | Not Detected |
| 1,4-Dichlorobenzene | 1.3 | ~~0.22 J~~ U | 8.1 | ~~1.4 J~~ U |
| alpha-Chlorotoluene | 1.3 | Not Detected | 7.0 | Not Detected |
| 1,2-Dichlorobenzene | 1.3 | Not Detected | 8.1 | Not Detected |
| 1,2,4-Trichlorobenzene | 5.4 | Not Detected | 40 | Not Detected |
| Hexachlorobutadiene | 5.4 | Not Detected | 57 | Not Detected |
| Butane | 5.4 | 3.1 J | 13 | 7.4 J |
| Isopentane | 5.4 | 8.7 | 16 | 26 |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| Toluene-d8 | 103 | 70-130 |
| 1,2-Dichloroethane-d4 | 99 | 70-130 |
| 4-Bromofluorobenzene | 93 | 70-130 |

eurofins | Air Toxics

**Client Sample ID: VMP-12-11.5-021813**

**Lab ID#: 1302356A-03A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **3022611** | **Date of Collection:** | **2/18/13 11:25:00 AM** |
| **Dil. Factor:** | **2.89** | **Date of Analysis:** | **2/26/13 04:19 PM** |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 1.4 | 0.47 J | 7.1 | 2.3 J |
| Freon 114 | 1.4 | Not Detected | 10 | Not Detected |
| Chloromethane | 14 | Not Detected | 30 | Not Detected |
| Vinyl Chloride | 1.4 | Not Detected | 3.7 | Not Detected |
| 1,3-Butadiene | 1.4 | Not Detected | 3.2 | Not Detected |
| Bromomethane | 14 | Not Detected | 56 | Not Detected |
| Chloroethane | 5.8 | Not Detected | 15 | Not Detected |
| Freon 11 | 1.4 | Not Detected | 8.1 | Not Detected |
| Ethanol | 5.8 | Not Detected | 11 | Not Detected |
| Freon 113 | 1.4 | Not Detected | 11 | Not Detected |
| 1,1-Dichloroethene | 1.4 | Not Detected | 5.7 | Not Detected |
| Acetone | 14 | 4.1 J | 34 | 9.7 J |
| 2-Propanol | 5.8 | 5.4 J | 14 | 13 J |
| Carbon Disulfide | 5.8 | Not Detected | 18 | Not Detected |
| 3-Chloropropene | 5.8 | Not Detected | 18 | Not Detected |
| Methylene Chloride | 14 | Not Detected | 50 | Not Detected |
| Methyl tert-butyl ether | 1.4 | Not Detected | 5.2 | Not Detected |
| trans-1,2-Dichloroethene | 1.4 | Not Detected | 5.7 | Not Detected |
| Hexane | 1.4 | 0.28 J | 5.1 | 0.98 J |
| 1,1-Dichloroethane | 1.4 | Not Detected | 5.8 | Not Detected |
| 2-Butanone (Methyl Ethyl Ketone) | 5.8 | Not Detected | 17 | Not Detected |
| cis-1,2-Dichloroethene | 1.4 | Not Detected | 5.7 | Not Detected |
| Tetrahydrofuran | 1.4 | Not Detected | 4.3 | Not Detected |
| Chloroform | 1.4 | Not Detected | 7.0 | Not Detected |
| 1,1,1-Trichloroethane | 1.4 | Not Detected | 7.9 | Not Detected |
| Cyclohexane | 1.4 | Not Detected | 5.0 | Not Detected |
| Carbon Tetrachloride | 1.4 | Not Detected | 9.1 | Not Detected |
| 2,2,4-Trimethylpentane | 1.4 | 0.34 J | 6.8 | 1.6 J |
| Benzene | 1.4 | 0.25 J | 4.6 | 0.80 J |
| 1,2-Dichloroethane | 1.4 | Not Detected | 5.8 | Not Detected |
| Heptane | 1.4 | Not Detected | 5.9 | Not Detected |
| Trichloroethene | 1.4 | 0.36 J | 7.8 | 1.9 J |
| 1,2-Dichloropropane | 1.4 | Not Detected | 6.7 | Not Detected |
| 1,4-Dioxane | 5.8 | Not Detected | 21 | Not Detected |
| Bromodichloromethane | 1.4 | Not Detected | 9.7 | Not Detected |
| cis-1,3-Dichloropropene | 1.4 | Not Detected | 6.6 | Not Detected |
| 4-Methyl-2-pentanone | 1.4 | Not Detected | 5.9 | Not Detected |
| Toluene | 1.4 | 0.25 J | 5.4 | 0.94 J |
| trans-1,3-Dichloropropene | 1.4 | Not Detected | 6.6 | Not Detected |
| 1,1,2-Trichloroethane | 1.4 | Not Detected | 7.9 | Not Detected |
| Tetrachloroethene | 1.4 | Not Detected | 9.8 | Not Detected |
| 2-Hexanone | 5.8 | Not Detected | 24 | Not Detected |

eurofins | Air Toxics

**Client Sample ID: VMP-12-11.5-021813**

**Lab ID#: 1302356A-03A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **3022611** | **Date of Collection:** | **2/18/13 11:25:00 AM** |
| **Dil. Factor:** | **2.89** | **Date of Analysis:** | **2/26/13 04:19 PM** |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Dibromochloromethane | 1.4 | Not Detected | 12 | Not Detected |
| 1,2-Dibromoethane (EDB) | 1.4 | Not Detected | 11 | Not Detected |
| Chlorobenzene | 1.4 | Not Detected | 6.6 | Not Detected |
| Ethyl Benzene | 1.4 | Not Detected | 6.3 | Not Detected |
| m,p-Xylene | 1.4 | Not Detected | 6.3 | Not Detected |
| o-Xylene | 1.4 | Not Detected | 6.3 | Not Detected |
| Styrene | 1.4 | Not Detected | 6.2 | Not Detected |
| Bromoform | 1.4 | Not Detected | 15 | Not Detected |
| Cumene | 1.4 | Not Detected | 7.1 | Not Detected |
| 1,1,2,2-Tetrachloroethane | 1.4 | Not Detected | 9.9 | Not Detected |
| Propylbenzene | 1.4 | Not Detected | 7.1 | Not Detected |
| 4-Ethyltoluene | 1.4 | Not Detected | 7.1 | Not Detected |
| 1,3,5-Trimethylbenzene | 1.4 | Not Detected | 7.1 | Not Detected |
| 1,2,4-Trimethylbenzene | 1.4 | Not Detected | 7.1 | Not Detected |
| 1,3-Dichlorobenzene | 1.4 | Not Detected | 8.7 | Not Detected |
| 1,4-Dichlorobenzene | 1.4 | Not Detected | 8.7 | Not Detected |
| alpha-Chlorotoluene | 1.4 | Not Detected | 7.5 | Not Detected |
| 1,2-Dichlorobenzene | 1.4 | Not Detected | 8.7 | Not Detected |
| 1,2,4-Trichlorobenzene | 5.8 | Not Detected | 43 | Not Detected |
| Hexachlorobutadiene | 5.8 | Not Detected | 62 | Not Detected |
| Butane | 5.8 | Not Detected | 14 | Not Detected |
| Isopentane | 5.8 | Not Detected | 17 | Not Detected |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| Toluene-d8 | 101 | 70-130 |
| 1,2-Dichloroethane-d4 | 90 | 70-130 |
| 4-Bromofluorobenzene | 94 | 70-130 |

eurofins | Air Toxics

VMP-31-10-021313 (AF)

**Client Sample ID: ~~VMP-31-10-021313~~**

**Lab ID#: 1302356A-04A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **3022610** | **Date of Collection:** | **2/13/13 2:08:00 PM** |
| **Dil. Factor:** | **2.82** | **Date of Analysis:** | **2/26/13 03:58 PM** |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 1.4 | 0.42 J | 7.0 | 2.1 J |
| Freon 114 | 1.4 | Not Detected | 9.8 | Not Detected |
| Chloromethane | 14 | Not Detected | 29 | Not Detected |
| Vinyl Chloride | 1.4 | Not Detected | 3.6 | Not Detected |
| 1,3-Butadiene | 1.4 | Not Detected | 3.1 | Not Detected |
| Bromomethane | 14 | 1.0 J | 55 | 3.9 J |
| Chloroethane | 5.6 | Not Detected | 15 | Not Detected |
| Freon 11 | 1.4 | Not Detected | 7.9 | Not Detected |
| Ethanol | 5.6 | 4.2 J | 11 | 7.9 J |
| Freon 113 | 1.4 | Not Detected | 11 | Not Detected |
| 1,1-Dichloroethene | 1.4 | Not Detected | 5.6 | Not Detected |
| Acetone | 14 | 7.5 J | 33 | 18 J |
| 2-Propanol | 5.6 | Not Detected | 14 | Not Detected |
| Carbon Disulfide | 5.6 | Not Detected | 18 | Not Detected |
| 3-Chloropropene | 5.6 | Not Detected | 18 | Not Detected |
| Methylene Chloride | 14 | ~~0.23 J~~ | 49 | ~~0.82 J~~ |
| Methyl tert-butyl ether | 1.4 | Not Detected | 5.1 | Not Detected |
| trans-1,2-Dichloroethene | 1.4 | Not Detected | 5.6 | Not Detected |
| Hexane | 1.4 | 4.6 | 5.0 | 16 |
| 1,1-Dichloroethane | 1.4 | Not Detected | 5.7 | Not Detected |
| 2-Butanone (Methyl Ethyl Ketone) | 5.6 | 1.2 J | 17 | 3.7 J |
| cis-1,2-Dichloroethene | 1.4 | Not Detected | 5.6 | Not Detected |
| Tetrahydrofuran | 1.4 | Not Detected | 4.2 | Not Detected |
| Chloroform | 1.4 | Not Detected | 6.9 | Not Detected |
| 1,1,1-Trichloroethane | 1.4 | Not Detected | 7.7 | Not Detected |
| Cyclohexane | 1.4 | 1.2 J | 4.8 | 4.0 J |
| Carbon Tetrachloride | 1.4 | Not Detected | 8.9 | Not Detected |
| 2,2,4-Trimethylpentane | 1.4 | 11 | 6.6 | 50 |
| Benzene | 1.4 | 7.4 | 4.5 | 24 |
| 1,2-Dichloroethane | 1.4 | Not Detected | 5.7 | Not Detected |
| Heptane | 1.4 | 1.8 | 5.8 | 7.5 |
| Trichloroethene | 1.4 | Not Detected | 7.6 | Not Detected |
| 1,2-Dichloropropane | 1.4 | Not Detected | 6.5 | Not Detected |
| 1,4-Dioxane | 5.6 | Not Detected | 20 | Not Detected |
| Bromodichloromethane | 1.4 | Not Detected | 9.4 | Not Detected |
| cis-1,3-Dichloropropene | 1.4 | Not Detected | 6.4 | Not Detected |
| 4-Methyl-2-pentanone | 1.4 | 0.82 J | 5.8 | 3.3 J |
| Toluene | 1.4 | 4.1 | 5.3 | 16 |
| trans-1,3-Dichloropropene | 1.4 | ~~0.21 J~~ | 6.4 | ~~0.97 J~~ |
| 1,1,2-Trichloroethane | 1.4 | Not Detected | 7.7 | Not Detected |
| Tetrachloroethene | 1.4 | Not Detected | 9.6 | Not Detected |
| 2-Hexanone | 5.6 | Not Detected | 23 | Not Detected |

eurofins | Air Toxics

VMP-31-10-021313 (AF)

**Client Sample ID: ~~VMP-31-10-021313~~**

**Lab ID#: 1302356A-04A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **3022610** | **Date of Collection:** | **2/13/13 2:08:00 PM** |
| **Dil. Factor:** | **2.82** | **Date of Analysis:** | **2/26/13 03:58 PM** |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Dibromochloromethane | 1.4 | Not Detected | 12 | Not Detected |
| 1,2-Dibromoethane (EDB) | 1.4 | Not Detected | 11 | Not Detected |
| Chlorobenzene | 1.4 | Not Detected | 6.5 | Not Detected |
| Ethyl Benzene | 1.4 | 3.0 | 6.1 | 13 |
| m,p-Xylene | 1.4 | 9.4 | 6.1 | 41 |
| o-Xylene | 1.4 | 3.6 | 6.1 | 16 |
| Styrene | 1.4 | Not Detected | 6.0 | Not Detected |
| Bromoform | 1.4 | Not Detected | 14 | Not Detected |
| Cumene | 1.4 | 0.52 J | 6.9 | 2.6 J |
| 1,1,2,2-Tetrachloroethane | 1.4 | Not Detected | 9.7 | Not Detected |
| Propylbenzene | 1.4 | 0.85 J | 6.9 | 4.2 J |
| 4-Ethyltoluene | 1.4 | 2.4 | 6.9 | 12 |
| 1,3,5-Trimethylbenzene | 1.4 | 0.73 J | 6.9 | 3.6 J |
| 1,2,4-Trimethylbenzene | 1.4 | 1.6 J J | 6.9 | 8.0 J J |
| 1,3-Dichlorobenzene | 1.4 | Not Detected | 8.5 | Not Detected |
| 1,4-Dichlorobenzene | 1.4 | ~~0.17 J~~ U | 8.5 | ~~1.0 J~~ U |
| alpha-Chlorotoluene | 1.4 | Not Detected | 7.3 | Not Detected |
| 1,2-Dichlorobenzene | 1.4 | Not Detected | 8.5 | Not Detected |
| 1,2,4-Trichlorobenzene | 5.6 | Not Detected | 42 | Not Detected |
| Hexachlorobutadiene | 5.6 | Not Detected | 60 | Not Detected |
| Butane | 5.6 | 44 | 13 | 100 |
| Isopentane | 5.6 | 39 | 17 | 120 |

J = Estimated value.
J = Estimated value due to bias in the CCV.
**Container Type: 1 Liter Summa Canister**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| Toluene-d8 | 102 | 70-130 |
| 1,2-Dichloroethane-d4 | 93 | 70-130 |
| 4-Bromofluorobenzene | 92 | 70-130 |

eurofins | Air Toxics

**Client Sample ID: VMP-51-20-021513-R**

**Lab ID#: 1302356A-05A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **3022609** | **Date of Collection: 2/15/13 3:29:00 PM** | |
| **Dil. Factor:** | **2.64** | **Date of Analysis: 2/26/13 03:21 PM** | |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 1.3 | 0.52 J | 6.5 | 2.6 J |
| Freon 114 | 1.3 | Not Detected | 9.2 | Not Detected |
| Chloromethane | 13 | Not Detected | 27 | Not Detected |
| Vinyl Chloride | 1.3 | Not Detected | 3.4 | Not Detected |
| 1,3-Butadiene | 1.3 | Not Detected | 2.9 | Not Detected |
| Bromomethane | 13 | Not Detected | 51 | Not Detected |
| Chloroethane | 5.3 | Not Detected | 14 | Not Detected |
| Freon 11 | 1.3 | 0.24 J | 7.4 | 1.3 J |
| Ethanol | 5.3 | 2.9 J | 9.9 | 5.4 J |
| Freon 113 | 1.3 | Not Detected | 10 | Not Detected |
| 1,1-Dichloroethene | 1.3 | Not Detected | 5.2 | Not Detected |
| Acetone | 13 | 5.3 J | 31 | 13 J |
| 2-Propanol | 5.3 | 4.6 J | 13 | 11 J |
| Carbon Disulfide | 5.3 | Not Detected | 16 | Not Detected |
| 3-Chloropropene | 5.3 | Not Detected | 16 | Not Detected |
| Methylene Chloride | 13 | ~~0.25 J~~ U | 46 | ~~0.87 J~~ U |
| Methyl tert-butyl ether | 1.3 | Not Detected | 4.8 | Not Detected |
| trans-1,2-Dichloroethene | 1.3 | Not Detected | 5.2 | Not Detected |
| Hexane | 1.3 | 0.33 J | 4.6 | 1.2 J |
| 1,1-Dichloroethane | 1.3 | Not Detected | 5.3 | Not Detected |
| 2-Butanone (Methyl Ethyl Ketone) | 5.3 | Not Detected | 16 | Not Detected |
| cis-1,2-Dichloroethene | 1.3 | Not Detected | 5.2 | Not Detected |
| Tetrahydrofuran | 1.3 | Not Detected | 3.9 | Not Detected |
| Chloroform | 1.3 | 4.2 | 6.4 | 20 |
| 1,1,1-Trichloroethane | 1.3 | Not Detected | 7.2 | Not Detected |
| Cyclohexane | 1.3 | 0.40 J | 4.5 | 1.4 J |
| Carbon Tetrachloride | 1.3 | Not Detected | 8.3 | Not Detected |
| 2,2,4-Trimethylpentane | 1.3 | 17 | 6.2 | 78 |
| Benzene | 1.3 | 1.6 | 4.2 | 5.3 |
| 1,2-Dichloroethane | 1.3 | Not Detected | 5.3 | Not Detected |
| Heptane | 1.3 | Not Detected | 5.4 | Not Detected |
| Trichloroethene | 1.3 | Not Detected | 7.1 | Not Detected |
| 1,2-Dichloropropane | 1.3 | Not Detected | 6.1 | Not Detected |
| 1,4-Dioxane | 5.3 | Not Detected | 19 | Not Detected |
| Bromodichloromethane | 1.3 | Not Detected | 8.8 | Not Detected |
| cis-1,3-Dichloropropene | 1.3 | Not Detected | 6.0 | Not Detected |
| 4-Methyl-2-pentanone | 1.3 | Not Detected | 5.4 | Not Detected |
| Toluene | 1.3 | 0.17 J | 5.0 | 0.65 J |
| trans-1,3-Dichloropropene | 1.3 | Not Detected | 6.0 | Not Detected |
| 1,1,2-Trichloroethane | 1.3 | Not Detected | 7.2 | Not Detected |
| Tetrachloroethene | 1.3 | 0.18 J | 9.0 | 1.2 J |
| 2-Hexanone | 5.3 | Not Detected | 22 | Not Detected |

eurofins | Air Toxics

**Client Sample ID: VMP-51-20-021513-R**

**Lab ID#: 1302356A-05A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **3022609** | **Date of Collection:** | **2/15/13 3:29:00 PM** |
| **Dil. Factor:** | **2.64** | **Date of Analysis:** | **2/26/13 03:21 PM** |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Dibromochloromethane | 1.3 | Not Detected | 11 | Not Detected |
| 1,2-Dibromoethane (EDB) | 1.3 | Not Detected | 10 | Not Detected |
| Chlorobenzene | 1.3 | Not Detected | 6.1 | Not Detected |
| Ethyl Benzene | 1.3 | 1.0 J | 5.7 | 4.5 J |
| m,p-Xylene | 1.3 | 0.52 J | 5.7 | 2.2 J |
| o-Xylene | 1.3 | Not Detected | 5.7 | Not Detected |
| Styrene | 1.3 | Not Detected | 5.6 | Not Detected |
| Bromoform | 1.3 | Not Detected | 14 | Not Detected |
| Cumene | 1.3 | 0.57 J | 6.5 | 2.8 J |
| 1,1,2,2-Tetrachloroethane | 1.3 | Not Detected | 9.1 | Not Detected |
| Propylbenzene | 1.3 | 1.5 | 6.5 | 7.4 |
| 4-Ethyltoluene | 1.3 | 0.38 J | 6.5 | 1.9 J |
| 1,3,5-Trimethylbenzene | 1.3 | Not Detected | 6.5 | Not Detected |
| 1,2,4-Trimethylbenzene | 1.3 | 0.99 J J | 6.5 | 4.9 J J |
| 1,3-Dichlorobenzene | 1.3 | Not Detected | 7.9 | Not Detected |
| 1,4-Dichlorobenzene | 1.3 | ~~0.20 J~~ U | 7.9 | ~~1.2 J~~ U |
| alpha-Chlorotoluene | 1.3 | Not Detected | 6.8 | Not Detected |
| 1,2-Dichlorobenzene | 1.3 | Not Detected | 7.9 | Not Detected |
| 1,2,4-Trichlorobenzene | 5.3 | Not Detected | 39 | Not Detected |
| Hexachlorobutadiene | 5.3 | Not Detected | 56 | Not Detected |
| Butane | 5.3 | Not Detected | 12 | Not Detected |
| Isopentane | 5.3 | 2.9 J | 16 | 8.6 J |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| Toluene-d8 | 95 | 70-130 |
| 1,2-Dichloroethane-d4 | 93 | 70-130 |
| 4-Bromofluorobenzene | 95 | 70-130 |

eurofins | Air Toxics

**Client Sample ID: Lab Blank**

**Lab ID#: 1302356A-06A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **3022608d** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 2/26/13 02:33 PM** | |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 0.50 | Not Detected | 2.5 | Not Detected |
| Freon 114 | 0.50 | Not Detected | 3.5 | Not Detected |
| Chloromethane | 5.0 | Not Detected | 10 | Not Detected |
| Vinyl Chloride | 0.50 | Not Detected | 1.3 | Not Detected |
| 1,3-Butadiene | 0.50 | Not Detected | 1.1 | Not Detected |
| Bromomethane | 5.0 | 0.35 J | 19 | 1.4 J |
| Chloroethane | 2.0 | Not Detected | 5.3 | Not Detected |
| Freon 11 | 0.50 | Not Detected | 2.8 | Not Detected |
| Ethanol | 2.0 | Not Detected | 3.8 | Not Detected |
| Freon 113 | 0.50 | Not Detected | 3.8 | Not Detected |
| 1,1-Dichloroethene | 0.50 | Not Detected | 2.0 | Not Detected |
| Acetone | 5.0 | Not Detected | 12 | Not Detected |
| 2-Propanol | 2.0 | Not Detected | 4.9 | Not Detected |
| Carbon Disulfide | 2.0 | Not Detected | 6.2 | Not Detected |
| 3-Chloropropene | 2.0 | Not Detected | 6.3 | Not Detected |
| Methylene Chloride | 5.0 | 0.077 J | 17 | 0.27 J |
| Methyl tert-butyl ether | 0.50 | Not Detected | 1.8 | Not Detected |
| trans-1,2-Dichloroethene | 0.50 | Not Detected | 2.0 | Not Detected |
| Hexane | 0.50 | Not Detected | 1.8 | Not Detected |
| 1,1-Dichloroethane | 0.50 | Not Detected | 2.0 | Not Detected |
| 2-Butanone (Methyl Ethyl Ketone) | 2.0 | Not Detected | 5.9 | Not Detected |
| cis-1,2-Dichloroethene | 0.50 | Not Detected | 2.0 | Not Detected |
| Tetrahydrofuran | 0.50 | Not Detected | 1.5 | Not Detected |
| Chloroform | 0.50 | Not Detected | 2.4 | Not Detected |
| 1,1,1-Trichloroethane | 0.50 | Not Detected | 2.7 | Not Detected |
| Cyclohexane | 0.50 | Not Detected | 1.7 | Not Detected |
| Carbon Tetrachloride | 0.50 | Not Detected | 3.1 | Not Detected |
| 2,2,4-Trimethylpentane | 0.50 | Not Detected | 2.3 | Not Detected |
| Benzene | 0.50 | Not Detected | 1.6 | Not Detected |
| 1,2-Dichloroethane | 0.50 | Not Detected | 2.0 | Not Detected |
| Heptane | 0.50 | Not Detected | 2.0 | Not Detected |
| Trichloroethene | 0.50 | Not Detected | 2.7 | Not Detected |
| 1,2-Dichloropropane | 0.50 | Not Detected | 2.3 | Not Detected |
| 1,4-Dioxane | 2.0 | Not Detected | 7.2 | Not Detected |
| Bromodichloromethane | 0.50 | Not Detected | 3.4 | Not Detected |
| cis-1,3-Dichloropropene | 0.50 | Not Detected | 2.3 | Not Detected |
| 4-Methyl-2-pentanone | 0.50 | Not Detected | 2.0 | Not Detected |
| Toluene | 0.50 | Not Detected | 1.9 | Not Detected |
| trans-1,3-Dichloropropene | 0.50 | 0.071 J | 2.3 | 0.32 J |
| 1,1,2-Trichloroethane | 0.50 | Not Detected | 2.7 | Not Detected |
| Tetrachloroethene | 0.50 | Not Detected | 3.4 | Not Detected |
| 2-Hexanone | 2.0 | Not Detected | 8.2 | Not Detected |

eurofins | Air Toxics

**Client Sample ID: Lab Blank**

**Lab ID#: 1302356A-06A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **3022608d** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 2/26/13 02:33 PM** | |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Dibromochloromethane | 0.50 | Not Detected | 4.2 | Not Detected |
| 1,2-Dibromoethane (EDB) | 0.50 | Not Detected | 3.8 | Not Detected |
| Chlorobenzene | 0.50 | Not Detected | 2.3 | Not Detected |
| Ethyl Benzene | 0.50 | Not Detected | 2.2 | Not Detected |
| m,p-Xylene | 0.50 | Not Detected | 2.2 | Not Detected |
| o-Xylene | 0.50 | Not Detected | 2.2 | Not Detected |
| Styrene | 0.50 | Not Detected | 2.1 | Not Detected |
| Bromoform | 0.50 | Not Detected | 5.2 | Not Detected |
| Cumene | 0.50 | Not Detected | 2.4 | Not Detected |
| 1,1,2,2-Tetrachloroethane | 0.50 | Not Detected | 3.4 | Not Detected |
| Propylbenzene | 0.50 | Not Detected | 2.4 | Not Detected |
| 4-Ethyltoluene | 0.50 | Not Detected | 2.4 | Not Detected |
| 1,3,5-Trimethylbenzene | 0.50 | Not Detected | 2.4 | Not Detected |
| 1,2,4-Trimethylbenzene | 0.50 | Not Detected | 2.4 | Not Detected |
| 1,3-Dichlorobenzene | 0.50 | Not Detected | 3.0 | Not Detected |
| 1,4-Dichlorobenzene | 0.50 | 0.068 J | 3.0 | 0.41 J |
| alpha-Chlorotoluene | 0.50 | Not Detected | 2.6 | Not Detected |
| 1,2-Dichlorobenzene | 0.50 | Not Detected | 3.0 | Not Detected |
| 1,2,4-Trichlorobenzene | 2.0 | Not Detected | 15 | Not Detected |
| Hexachlorobutadiene | 2.0 | Not Detected | 21 | Not Detected |
| Butane | 2.0 | Not Detected | 4.8 | Not Detected |
| Isopentane | 2.0 | Not Detected | 5.9 | Not Detected |

J = Estimated value.

**Container Type: NA - Not Applicable**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| Toluene-d8 | 101 | 70-130 |
| 1,2-Dichloroethane-d4 | 92 | 70-130 |
| 4-Bromofluorobenzene | 91 | 70-130 |

eurofins | Air Toxics

**Client Sample ID: CCV**

**Lab ID#: 1302356A-07A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **3022602** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 2/26/13 11:31 AM** | |

| Compound | %Recovery |
|---|---|
| Freon 12 | 101 |
| Freon 114 | 108 |
| Chloromethane | 86 |
| Vinyl Chloride | 98 |
| 1,3-Butadiene | 101 |
| Bromomethane | 107 |
| Chloroethane | 99 |
| Freon 11 | 102 |
| Ethanol | 96 |
| Freon 113 | 105 |
| 1,1-Dichloroethene | 108 |
| Acetone | 99 |
| 2-Propanol | 95 |
| Carbon Disulfide | 101 |
| 3-Chloropropene | 107 |
| Methylene Chloride | 92 |
| Methyl tert-butyl ether | 111 |
| trans-1,2-Dichloroethene | 102 |
| Hexane | 108 |
| 1,1-Dichloroethane | 98 |
| 2-Butanone (Methyl Ethyl Ketone) | 104 |
| cis-1,2-Dichloroethene | 102 |
| Tetrahydrofuran | 114 |
| Chloroform | 102 |
| 1,1,1-Trichloroethane | 102 |
| Cyclohexane | 112 |
| Carbon Tetrachloride | 104 |
| 2,2,4-Trimethylpentane | 116 |
| Benzene | 101 |
| 1,2-Dichloroethane | 99 |
| Heptane | 113 |
| Trichloroethene | 88 |
| 1,2-Dichloropropane | 102 |
| 1,4-Dioxane | 105 |
| Bromodichloromethane | 103 |
| cis-1,3-Dichloropropene | 107 |
| 4-Methyl-2-pentanone | 120 |
| Toluene | 105 |
| trans-1,3-Dichloropropene | 105 |
| 1,1,2-Trichloroethane | 100 |
| Tetrachloroethene | 98 |
| 2-Hexanone | 124 |

eurofins | Air Toxics

**Client Sample ID: CCV**

**Lab ID#: 1302356A-07A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **3022602** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 2/26/13 11:31 AM** | |

| Compound | %Recovery |
|---|---|
| Dibromochloromethane | 104 |
| 1,2-Dibromoethane (EDB) | 104 |
| Chlorobenzene | 96 |
| Ethyl Benzene | 110 |
| m,p-Xylene | 114 |
| o-Xylene | 115 |
| Styrene | 118 |
| Bromoform | 106 |
| Cumene | 119 |
| 1,1,2,2-Tetrachloroethane | 114 |
| Propylbenzene | 112 |
| 4-Ethyltoluene | 116 |
| 1,3,5-Trimethylbenzene | 123 |
| 1,2,4-Trimethylbenzene | 131 Q |
| 1,3-Dichlorobenzene | 109 |
| 1,4-Dichlorobenzene | 111 |
| alpha-Chlorotoluene | 116 |
| 1,2-Dichlorobenzene | 108 |
| 1,2,4-Trichlorobenzene | 111 |
| Hexachlorobutadiene | 108 |
| Butane | 97 |
| Isopentane | 95 |

Q = Exceeds Quality Control limits.

**Container Type: NA - Not Applicable**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| Toluene-d8 | 106 | 70-130 |
| 1,2-Dichloroethane-d4 | 106 | 70-130 |
| 4-Bromofluorobenzene | 102 | 70-130 |

eurofins | Air Toxics

**Client Sample ID: LCS**

**Lab ID#: 1302356A-08A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **3022603** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 2/26/13 12:02 PM** | |

| Compound | %Recovery |
|---|---|
| Freon 12 | 102 |
| Freon 114 | 111 |
| Chloromethane | 84 |
| Vinyl Chloride | 100 |
| 1,3-Butadiene | 101 |
| Bromomethane | 106 |
| Chloroethane | 99 |
| Freon 11 | 100 |
| Ethanol | 93 |
| Freon 113 | 109 |
| 1,1-Dichloroethene | 116 |
| Acetone | 97 |
| 2-Propanol | 99 |
| Carbon Disulfide | 125 |
| 3-Chloropropene | 119 |
| Methylene Chloride | 91 |
| Methyl tert-butyl ether | 107 |
| trans-1,2-Dichloroethene | 114 |
| Hexane | 106 |
| 1,1-Dichloroethane | 95 |
| 2-Butanone (Methyl Ethyl Ketone) | 106 |
| cis-1,2-Dichloroethene | 100 |
| Tetrahydrofuran | 108 |
| Chloroform | 102 |
| 1,1,1-Trichloroethane | 103 |
| Cyclohexane | 113 |
| Carbon Tetrachloride | 104 |
| 2,2,4-Trimethylpentane | 114 |
| Benzene | 102 |
| 1,2-Dichloroethane | 96 |
| Heptane | 114 |
| Trichloroethene | 92 |
| 1,2-Dichloropropane | 104 |
| 1,4-Dioxane | 114 |
| Bromodichloromethane | 104 |
| cis-1,3-Dichloropropene | 110 |
| 4-Methyl-2-pentanone | 121 |
| Toluene | 104 |
| trans-1,3-Dichloropropene | 110 |
| 1,1,2-Trichloroethane | 104 |
| Tetrachloroethene | 100 |
| 2-Hexanone | 128 |

eurofins | Air Toxics

**Client Sample ID: LCS**

**Lab ID#: 1302356A-08A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **3022603** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 2/26/13 12:02 PM** | |

| Compound | %Recovery |
|---|---|
| Dibromochloromethane | 106 |
| 1,2-Dibromoethane (EDB) | 107 |
| Chlorobenzene | 98 |
| Ethyl Benzene | 111 |
| m,p-Xylene | 119 |
| o-Xylene | 118 |
| Styrene | 125 |
| Bromoform | 109 |
| Cumene | 122 |
| 1,1,2,2-Tetrachloroethane | 118 |
| Propylbenzene | 114 |
| 4-Ethyltoluene | 113 |
| 1,3,5-Trimethylbenzene | 125 |
| 1,2,4-Trimethylbenzene | 132 Q |
| 1,3-Dichlorobenzene | 110 |
| 1,4-Dichlorobenzene | 111 |
| alpha-Chlorotoluene | 121 |
| 1,2-Dichlorobenzene | 111 |
| 1,2,4-Trichlorobenzene | 112 |
| Hexachlorobutadiene | 107 |
| Butane | 92 |
| Isopentane | 94 |

Q = Exceeds Quality Control limits.

**Container Type: NA - Not Applicable**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| Toluene-d8 | 103 | 70-130 |
| 1,2-Dichloroethane-d4 | 95 | 70-130 |
| 4-Bromofluorobenzene | 98 | 70-130 |

eurofins | Air Toxics

**Client Sample ID: LCSD**

**Lab ID#: 1302356A-08AA**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **3022604** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 2/26/13 12:20 PM** | |

| Compound | %Recovery |
|---|---|
| Freon 12 | 103 |
| Freon 114 | 111 |
| Chloromethane | 88 |
| Vinyl Chloride | 103 |
| 1,3-Butadiene | 102 |
| Bromomethane | 109 |
| Chloroethane | 100 |
| Freon 11 | 99 |
| Ethanol | 98 |
| Freon 113 | 103 |
| 1,1-Dichloroethene | 112 |
| Acetone | 98 |
| 2-Propanol | 100 |
| Carbon Disulfide | 121 |
| 3-Chloropropene | 120 |
| Methylene Chloride | 93 |
| Methyl tert-butyl ether | 109 |
| trans-1,2-Dichloroethene | 115 |
| Hexane | 109 |
| 1,1-Dichloroethane | 98 |
| 2-Butanone (Methyl Ethyl Ketone) | 106 |
| cis-1,2-Dichloroethene | 103 |
| Tetrahydrofuran | 111 |
| Chloroform | 103 |
| 1,1,1-Trichloroethane | 105 |
| Cyclohexane | 116 |
| Carbon Tetrachloride | 105 |
| 2,2,4-Trimethylpentane | 120 |
| Benzene | 104 |
| 1,2-Dichloroethane | 97 |
| Heptane | 114 |
| Trichloroethene | 92 |
| 1,2-Dichloropropane | 106 |
| 1,4-Dioxane | 107 |
| Bromodichloromethane | 104 |
| cis-1,3-Dichloropropene | 109 |
| 4-Methyl-2-pentanone | 119 |
| Toluene | 107 |
| trans-1,3-Dichloropropene | 107 |
| 1,1,2-Trichloroethane | 103 |
| Tetrachloroethene | 101 |
| 2-Hexanone | 124 |

eurofins | Air Toxics

**Client Sample ID: LCSD**

**Lab ID#: 1302356A-08AA**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **3022604** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 2/26/13 12:20 PM** | |

| Compound | %Recovery |
|---|---|
| Dibromochloromethane | 104 |
| 1,2-Dibromoethane (EDB) | 108 |
| Chlorobenzene | 99 |
| Ethyl Benzene | 111 |
| m,p-Xylene | 118 |
| o-Xylene | 119 |
| Styrene | 124 |
| Bromoform | 106 |
| Cumene | 124 |
| 1,1,2,2-Tetrachloroethane | 120 |
| Propylbenzene | 116 |
| 4-Ethyltoluene | 115 |
| 1,3,5-Trimethylbenzene | 127 |
| 1,2,4-Trimethylbenzene | 135 Q |
| 1,3-Dichlorobenzene | 113 |
| 1,4-Dichlorobenzene | 115 |
| alpha-Chlorotoluene | 120 |
| 1,2-Dichlorobenzene | 114 |
| 1,2,4-Trichlorobenzene | 117 |
| Hexachlorobutadiene | 113 |
| Butane | 95 |
| Isopentane | 94 |

Q = Exceeds Quality Control limits.

**Container Type: NA - Not Applicable**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| Toluene-d8 | 104 | 70-130 |
| 1,2-Dichloroethane-d4 | 102 | 70-130 |
| 4-Bromofluorobenzene | 101 | 70-130 |

1302356

# Shell Oil Products Chain Of Custody Record

URS

Air Toxics LTD.
Project Name: Roxana Soil Vapor
Project # 21562850.04001
Lab Vendor #

Please Check Appropriate Box:
☑ ENV. SERVICES ☐ MOTIVA RETAIL ☐ SHELL RETAIL
☐ MOTIVA SD&OM ☐ CONSULTANT ☐ LUBES
☐ SHELL PIPELINE ☐ OTHER

Print Bill To Contact Name: Robert Mooshegian
PO #:
INCIDENT # (ENV SERVICES): 9 7 2 1 6 6 4 0
SAP #: 3 4 0 0 6 1
☐ CHECK IF NO INCIDENT # APPLIES
DATE: 02/19/13
PAGE: 1 of 1

SAMPLING COMPANY: URS CORPORATION
LOCODE:
SITE ADDRESS: Street and City: 900 SOUTH CENTRAL AVE – ROXANA
State: IL
GLOBAL ID NO.:
ADDRESS: 1001 HIGHLANDS PLAZA DRIVE WEST - SUITE 300; ST. LOUIS, MO 63110
FOR DELIVERABLE TO Name, Company, Office Location: Elizabeth Kunkel, URS, St. Louis
PHONE NO.: 314-743-4179
E-MAIL: Elizabeth_Kunkel@URSCorp.com
CONSULTANT PROJECT NAME#: Roxana Soil Vapor
Laboratory Address: Air Toxics, LTD 180 Blue Ravine Road, Suite B, Folsom, CA 95630-4719
C. Kretzer, D. Mattingly, T. Carroll, C. Williams, M. Currier, B. Lehan, L. Rathnow.
TELEPHONE: 314-429-0100
FAX: 314-429-0462
Bill To Contact E-MAIL: Robert.Mooshegian@urs.com

TURNAROUND TIME (CALENDAR DAYS):
☑ STANDARD (14 DAY) ☐ 5 DAYS ☐ 3 DAYS ☐ 2 DAYS ☐ 24 HOURS ☐ RESULTS NEEDED ON WEEKEND

REQUESTED ANALYSIS

☐ LA - RWQCB REPORT FORMAT ☑ UST AGENCY:
DELIVERABLES: ☐ LEVEL 1 ☐ LEVEL 2 ☐ LEVEL 3 ☑ LEVEL 4 ☐ OTHER (SPECIFY)

☑ SHELL CONTRACT RATE APPLIES
☐ STATE REIMBURSEMENT RATE APPLIES
☐ EDD NOT NEEDED
☑ RECEIPT VERIFICATION REQUESTED

Turn Around Time: ☑ Normal ☐ Rush
Specify

Lab Use Only
Pressurized by:
Date:
Pressurization Gas: $N_2$ He

| LAB USE ONLY | Field Sample Identification | SAMPLING DATE | SAMPLING TIME | Canister Number | Canister Pressure/Vacuum Initial | Final | Receipt | Final (psi) | Modified TO-15 + Butane & Isopentane | ASTM D-1946 + Helium | ASTM D-1946 | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| 01A | VMP-9-5-021513 | 02/15/13 | 1120-1153 | 36511 | -30 | -10 | | | X | X | | | | | | |
| 02A | VMP-12-5-021813 | 02/18/13 | 0955-1025 | 33400 | -29 | -7.5 | | | X | X | | | | | | |
| 03A | VMP-12-11.5-021813 | 02/18/13 | 1055-1125 | 34684 | -29 | -9.5 | | | X | X | | | | | | |
| 04A | VMP-31-10-021313 | 02/13/13 | 1338-1408 | 35614 | -30 | -9 | | | X | X | | | | | | |
| 05A | VMP-51-20-021513-R | 02/15/13 | 1459-1529 | 35613 | -30 | -9 | | | X | X | | | | | | |

ADDITIONAL NOTES:
- 14 day hold time
- Report results between MDL and RL
- Level IV ECVP

FedEx
Custody Seal Intact?
Y N None Temp NA

| | | Date | Time |
|---|---|---|---|
| Relinquished by: (Signature) | Received by: (Signature) FEDEX | 2/19/13 | 1730 |
| Relinquished by: (Signature) | Received by: (Signature) Katie Deck ATL | 02/20/13 | 1000 |
| Relinquished by: (Signature) | Received by: (Signature) | | |

05/2008 Revision

eurofins | Air Toxics

3/14/2013
Ms. Elizabeth Kunkel
URS Corporation
1001 Highlands Plaza Dr. West
Suite 300
St. Louis MO 63110

Project Name: Roxana Soil Vapor
Project #: 21562850.04001
Workorder #: 1302356B

Dear Ms. Elizabeth Kunkel

The following report includes the data for the above referenced project for sample(s) received on 2/20/2013 at Air Toxics Ltd.

The data and associated QC analyzed by Modified ASTM D-1946 are compliant with the project requirements or laboratory criteria with the exception of the deviations noted in the attached case narrative.

Thank you for choosing Air Toxics Ltd. for your air analysis needs. Air Toxics Ltd. is committed to providing accurate data of the highest quality. Please feel free to contact the Project Manager: Kelly Buettner at 916-985-1000 if you have any questions regarding the data in this report.

Regards,

Kelly Buettner

Project Manager

REVIEWED
ON
3/25/13

eurofins | Air Toxics

# WORK ORDER #: 1302356B

Work Order Summary

| | | | |
|---|---|---|---|
| **CLIENT:** | Ms. Elizabeth Kunkel<br>URS Corporation<br>1001 Highlands Plaza Dr. West<br>Suite 300<br>St. Louis, MO 63110 | **BILL TO:** | Accounts Payable Austin<br>URS Corporation<br>P.O. BOX 203970<br>Austin, TX 78720-1088 |
| **PHONE:** | 314-743-4179 | **P.O. #** | 21562735.00013 |
| **FAX:** | | **PROJECT #** | 21562850.04001 Roxana Soil Vapor |
| **DATE RECEIVED:** | 02/20/2013 | **CONTACT:** | Kelly Buettner |
| **DATE COMPLETED:** | 03/14/2013 | | |

| FRACTION # | NAME | TEST | RECEIPT VAC./PRES. | FINAL PRESSURE |
|---|---|---|---|---|
| 01A | VMP-9-5-021513 | Modified ASTM D-1946 | 8.0 "Hg | 15 psi |
| 02A | VMP-12-5-021813 | Modified ASTM D-1946 | 7.5 "Hg | 15 psi |
| 03A | VMP-12-11.5-021813 | Modified ASTM D-1946 | 9.0 "Hg | 15 psi |
| 04A | ~~VMP-31-10-021313~~ | Modified ASTM D-1946 | 8.5 "Hg | 15 psi |
| 05A | VMP-51-20-021513-R | Modified ASTM D-1946 | 7.0 "Hg | 15 psi |
| 06A | Lab Blank | Modified ASTM D-1946 | NA | NA |
| 06B | Lab Blank | Modified ASTM D-1946 | NA | NA |
| 07A | LCS | Modified ASTM D-1946 | NA | NA |
| 07AA | LCSD | Modified ASTM D-1946 | NA | NA |

VMP-31-10-021313 (AF)

CERTIFIED BY: Heidi Hayes DATE: 03/14/13

Technical Director

Certification numbers: AZ Licensure AZ0775, CA NELAP - 12282CA, NY NELAP - 11291,
TX NELAP - T104704434-12-4, UT NELAP CA009332012-3, WA NELAP - C935
Name of Accrediting Agency: NELAP/ORELAP (Oregon Environmental Laboratory Accreditation Program)
Accreditation number: CA300005, Effective date: 10/18/2012, Expiration date: 10/17/2013.
Eurofins Air Toxics Ltd. certifies that the test results contained in this report meet all requirements of the NELAC standards

This report shall not be reproduced, except in full, without the written approval of Eurofins Air Toxics, Inc.

180 BLUE RAVINE ROAD, SUITE B FOLSOM, CA - 9563
(916) 985-1000 . (800) 985-5955 . FAX (916) 985-1020

**LABORATORY NARRATIVE**
**Modified ASTM D-1946**
**URS Corporation**
**Workorder# 1302356B**

Five 1 Liter Summa Canister samples were received on February 20, 2013. The laboratory performed analysis via Modified ASTM Method D-1946 for Methane and fixed gases in air using GC/FID or GC/TCD. The method involves direct injection of 1.0 mL of sample.

On the analytical column employed for this analysis, Oxygen coelutes with Argon. The corresponding peak is quantitated as Oxygen.

Since Nitrogen is used to pressurize samples, the reported Nitrogen values are calculated by adding all the sample components and subtracting from 100%.

Method modifications taken to run these samples are summarized in the table below. Specific project requirements may over-ride the ATL modifications.

| *Requirement* | *ASTM D-1946* | *ATL Modifications* |
|---|---|---|
| Calibration | A single point calibration is performed using a reference standard closely matching the composition of the unknown. | A 3-point calibration curve is performed. Quantitation is based on a daily calibration standard which may or may not resemble the composition of the associated samples. |
| Reference Standard | The composition of any reference standard must be known to within 0.01 mol % for any component. | The standards used by ATL are blended to a >/= 95% accuracy. |
| Sample Injection Volume | Components whose concentrations are in excess of 5 % should not be analyzed by using sample volumes greater than 0.5 mL. | The sample container is connected directly to a fixed volume sample loop of 1.0 mL on the GC. Linear range is defined by the calibration curve. Bags are loaded by vacuum. |
| Normalization | Normalize the mole percent values by multiplying each value by 100 and dividing by the sum of the original values. The sum of the original values should not differ from 100% by more than 1.0%. | Results are not normalized. The sum of the reported values can differ from 100% by as much as 15%, either due to analytical variability or an unusual sample matrix. |
| Precision | Precision requirements established at each concentration level. | Duplicates should agree within 25% RPD for detections > 5 X's the RL. |

**Receiving Notes**

There were no receiving discrepancies.

**Analytical Notes**

As per project specific client request the laboratory has reported estimated values for target compound hits that are below the Reporting Limit but greater than the Method Detection Limit. Concentrations that are below the level at which the canister was certified may be false positives.

The reporting limit for Carbon Monoxide was raised from 0.010% to 0.050%.

**Definition of Data Qualifying Flags**

Seven qualifiers may have been used on the data analysis sheets and indicate as follows:
B - Compound present in laboratory blank greater than reporting limit.
J - Estimated value.
E - Exceeds instrument calibration range.
S - Saturated peak.
Q - Exceeds quality control limits.
U - Compound analyzed for but not detected above the detection limit.
M - Reported value may be biased due to apparent matrix interferences.
File extensions may have been used on the data analysis sheets and indicates as follows:
a-File was requantified
b-File was quantified by a second column and detector
r1-File was requantified for the purpose of reissue

eurofins | Air Toxics

# Summary of Detected Compounds
# NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1946

**Client Sample ID: VMP-9-5-021513**

**Lab ID#: 1302356B-01A**

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.28 | 21 |
| Nitrogen | 0.28 | 79 |
| Methane | 0.00028 | 0.00013 J |
| Carbon Dioxide | 0.028 | 0.16 |

**Client Sample ID: VMP-12-5-021813**

**Lab ID#: 1302356B-02A**

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.27 | 21 |
| Nitrogen | 0.27 | 78 |
| Methane | 0.00027 | 0.000044 J |
| Carbon Dioxide | 0.027 | 0.089 |
| Helium | 0.13 | 0.34 |

**Client Sample ID: VMP-12-11.5-021813**

**Lab ID#: 1302356B-03A**

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.29 | 20 |
| Nitrogen | 0.29 | 80 |
| Methane | 0.00029 | 0.000079 J |
| Carbon Dioxide | 0.029 | 0.13 |
| Helium | 0.14 | 0.10 J |

**Client Sample ID: ~~VMP-31-10-021313~~** VMP-31-10-021313 (AF)

**Lab ID#: 1302356B-04A**

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.28 | 21 |
| Nitrogen | 0.28 | 78 |
| Methane | 0.00028 | 0.00015 J |

eurofins | Air Toxics

# Summary of Detected Compounds
# NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1946

**Client Sample ID: ~~VMP-31-10-021313~~** VMP-31-10-021313 (AF)

**Lab ID#: 1302356B-04A**

| | | |
|---|---|---|
| Carbon Dioxide | 0.028 | 0.18 |
| Helium | 0.14 | 0.32 |

**Client Sample ID: VMP-51-20-021513-R**

**Lab ID#: 1302356B-05A**

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.26 | 19 |
| Nitrogen | 0.26 | 78 |
| Carbon Dioxide | 0.026 | 2.9 |

eurofins | Air Toxics

**Client Sample ID: VMP-9-5-021513**

**Lab ID#: 1302356B-01A**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1946**

| | | | |
|---|---|---|---|
| **File Name:** | **9022525** | **Date of Collection:** | **2/15/13 11:53:00 AM** |
| **Dil. Factor:** | **2.76** | **Date of Analysis:** | **2/26/13 08:26 AM** |

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.28 | 21 |
| Nitrogen | 0.28 | 79 |
| Carbon Monoxide | 0.14 | Not Detected |
| Methane | 0.00028 | 0.00013 J |
| Carbon Dioxide | 0.028 | 0.16 |
| Ethane | 0.0028 | Not Detected |
| Ethene | 0.0028 | Not Detected |
| Helium | 0.14 | Not Detected |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

eurofins | Air Toxics

**Client Sample ID: VMP-12-5-021813**

**Lab ID#: 1302356B-02A**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1946**

| | | | |
|---|---|---|---|
| **File Name:** | **9022526** | **Date of Collection:** | **2/18/13 10:25:00 AM** |
| **Dil. Factor:** | **2.69** | **Date of Analysis:** | **2/26/13 08:59 AM** |

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.27 | 21 |
| Nitrogen | 0.27 | 78 |
| Carbon Monoxide | 0.13 | Not Detected |
| Methane | 0.00027 | 0.000044 J |
| Carbon Dioxide | 0.027 | 0.089 |
| Ethane | 0.0027 | Not Detected |
| Ethene | 0.0027 | Not Detected |
| Helium | 0.13 | 0.34 |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

eurofins | Air Toxics

**Client Sample ID: VMP-12-11.5-021813**

**Lab ID#: 1302356B-03A**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1946**

| | | | |
|---|---|---|---|
| **File Name:** | **9022527** | **Date of Collection:** | **2/18/13 11:25:00 AM** |
| **Dil. Factor:** | **2.89** | **Date of Analysis:** | **2/26/13 09:24 AM** |

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.29 | 20 |
| Nitrogen | 0.29 | 80 |
| Carbon Monoxide | 0.14 | Not Detected |
| Methane | 0.00029 | 0.000079 J |
| Carbon Dioxide | 0.029 | 0.13 |
| Ethane | 0.0029 | Not Detected |
| Ethene | 0.0029 | Not Detected |
| Helium | 0.14 | 0.10 J |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

eurofins | Air Toxics

VMP-31-10-021313 (AF)

**Client Sample ID: ~~VMP-31-10-021313~~**

**Lab ID#: 1302356B-04A**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1946**

| | | | |
|---|---|---|---|
| **File Name:** | **9022528** | **Date of Collection:** | **2/13/13 2:08:00 PM** |
| **Dil. Factor:** | **2.82** | **Date of Analysis:** | **2/26/13 09:49 AM** |

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.28 | 21 |
| Nitrogen | 0.28 | 78 |
| Carbon Monoxide | 0.14 | Not Detected |
| Methane | 0.00028 | 0.00015 J |
| Carbon Dioxide | 0.028 | 0.18 |
| Ethane | 0.0028 | Not Detected |
| Ethene | 0.0028 | Not Detected |
| Helium | 0.14 | 0.32 |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

eurofins | Air Toxics

**Client Sample ID: VMP-51-20-021513-R**

**Lab ID#: 1302356B-05A**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1946**

| | | | |
|---|---|---|---|
| **File Name:** | **9022529** | **Date of Collection:** | **2/15/13 3:29:00 PM** |
| **Dil. Factor:** | **2.64** | **Date of Analysis:** | **2/26/13 10:16 AM** |

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.26 | 19 |
| Nitrogen | 0.26 | 78 |
| Carbon Monoxide | 0.13 | Not Detected |
| Methane | 0.00026 | Not Detected |
| Carbon Dioxide | 0.026 | 2.9 |
| Ethane | 0.0026 | Not Detected |
| Ethene | 0.0026 | Not Detected |
| Helium | 0.13 | Not Detected |

**Container Type: 1 Liter Summa Canister**

eurofins | Air Toxics

**Client Sample ID: Lab Blank**

**Lab ID#: 1302356B-06A**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1946**

| | | | |
|---|---|---|---|
| **File Name:** | **9022512a** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 2/25/13 04:44 PM** | |

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.10 | Not Detected |
| Nitrogen | 0.10 | 0.045 J |
| Carbon Monoxide | 0.050 | Not Detected |
| Methane | 0.00010 | Not Detected |
| Carbon Dioxide | 0.010 | Not Detected |
| Ethane | 0.0010 | Not Detected |
| Ethene | 0.0010 | Not Detected |

J = Estimated value.

**Container Type: NA - Not Applicable**

eurofins | Air Toxics

**Client Sample ID: Lab Blank**

**Lab ID#: 1302356B-06B**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1946**

| | | | |
|---|---|---|---|
| **File Name:** | **9022511b** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 2/25/13 04:07 PM** | |

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Helium | 0.050 | Not Detected |

**Container Type: NA - Not Applicable**

eurofins | Air Toxics

**Client Sample ID: LCS**

**Lab ID#: 1302356B-07A**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1946**

| | | | |
|---|---|---|---|
| **File Name:** | **9022510** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 2/25/13 03:33 PM** | |

| Compound | %Recovery |
|---|---|
| Oxygen | 102 |
| Nitrogen | 101 |
| Carbon Monoxide | 109 |
| Methane | 99 |
| Carbon Dioxide | 100 |
| Ethane | 100 |
| Ethene | 97 |
| Helium | 100 |

**Container Type: NA - Not Applicable**

eurofins | Air Toxics

**Client Sample ID: LCSD**

**Lab ID#: 1302356B-07AA**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1946**

| | | | |
|---|---|---|---|
| **File Name:** | **9022534** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 2/26/13 12:35 PM** | |

| Compound | %Recovery |
|---|---|
| Oxygen | 104 |
| Nitrogen | 102 |
| Carbon Monoxide | 119 |
| Methane | 98 |
| Carbon Dioxide | 99 |
| Ethane | 100 |
| Ethene | 97 |
| Helium | 102 |

**Container Type: NA - Not Applicable**

1302356

# Shell Oil Products Chain Of Custody Record

URS

Air Toxics LTD.
**Project Name: Roxana Soil Vapor**
**Project # 21562850.04001**
Lab Vendor #

Please Check Appropriate Box: ☑ ENV. SERVICES ☐ MOTIVA RETAIL ☐ SHELL RETAIL ☐ MOTIVA SD&CM ☐ CONSULTANT ☐ LUBES ☐ SHELL PIPELINE ☐ OTHER

Print Bill To Contact Name: Robert Mooshegian
PO #:

INCIDENT # (ENV SERVICES): 9 7 2 1 6 8 4 0 ☐ CHECK IF NO INCIDENT # APPLIES
SAP #: 3 4 0 0 6 1
DATE: 02/19/13
PAGE: 1 of 1

SAMPLING COMPANY: URS CORPORATION
COC CREW:
ADDRESS: 1001 HIGHLANDS PLAZA DRIVE WEST - SUITE 300; ST. LOUIS, MO 63110
Laboratory Address: Air Toxics, LTD 180 Blue Ravine Road, Suite B, Folsom, CA 95630-4719
TELEPHONE: 314-429-0100
FAX: 314-429-0462
Bill To Contact E-MAIL: Robert.Mooshegian@urs.com

SITE ADDRESS: Street and City: 900 SOUTH CENTRAL AVE -- ROXANA
State: IL
GLOBAL ID NO:
PDF DELIVERABLE TO Name, Company, Office Location: Elizabeth Kunkel, URS, St. Louis
PHONE NO.: 314-743-4179
E-MAIL: Elizabeth_Kunkel@URSCorp.com
CONSULTANT PROJECT NUMBER: Roxana Soil Vapor
C. Kretzer, D. Mattingly, T. Carroll, C. Williams, M. Currier, B. Lehan, L. Rathnow

TURNAROUND TIME (CALENDAR DAYS): ☑ STANDARD (14 DAY) ☐ 5 DAYS ☐ 3 DAYS ☐ 2 DAYS ☐ 24 HOURS ☐ RESULTS NEEDED ON WEEKEND

☐ LA - RWQCB REPORT FORMAT ☑ UST AGENCY:

DELIVERABLES: ☐ LEVEL 1 ☐ LEVEL 2 ☐ LEVEL 3 ☑ LEVEL 4 ☐ OTHER (SPECIFY)

☑ SHELL CONTRACT RATE APPLIES
☐ STATE REIMBURSEMENT RATE APPLIES
☐ EDD NOT NEEDED
☑ RECEIPT VERIFICATION REQUESTED

REQUESTED ANALYSIS

| Lab Use Only | Field Sample Identification | Sampling Date | Sampling Time | Canister Number | Canister Pressure/Vacuum Initial | Canister Pressure/Vacuum Final | Canister Pressure/Vacuum Receipt | Canister Pressure/Vacuum Final (psi) | Modified TO-15 + Butane & Isopentane | ASTM D-1946 + Helium | ASTM D-1946 |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 01A | VMP-9-5-021513 | 02/15/13 | 1120-1153 | 36511 | -30 | -10 | | | X | X | |
| 02A | VMP-12-5-021813 | 02/18/13 | 0955-1025 | 33400 | -29 | -7.5 | | | X | X | |
| 03A | VMP-12-11.5-021813 | 02/18/13 | 1055-1125 | 34664 | -29 | -9.5 | | | X | X | |
| 04A | VMP-31-10-021313 | 02/13/13 | 1338-1408 | 35814 | -30 | -9 | | | X | X | |
| 05A | VMP-51-20-021513-R | 02/15/13 | 1459-1529 | 35813 | -30 | -9 | | | X | X | |

Turn Around Time: ☑ Normal ☐ Rush
Specify

Lab Use Only
Pressurized by:
Date:
Pressurization Gas: $N_2$ He

ADDITIONAL NOTES:
- 14 day hold time
- Report results between MDL and RL
- Level IV ECVP

FedEx
Custody Seal Intact?
Y N None Temp NA

| Relinquished by: (Signature) | Received by: (Signature) | Date | Time |
|---|---|---|---|
| | FEDEX | 2/19/13 | 1730 |
| Relinquished by: (Signature) | Received by: (Signature) Katie Deck ATL | 02/20/13 | 1000 |
| Relinquished by: (Signature) | Received by: (Signature) | Date: | Time: |

05/2008 Revision

# SVE System O&M 2013 Data Review

**Laboratory SDG: 1302458A,B,C**

**Data Reviewer: Elizabeth Kunkel**

**Peer Reviewer: Steve Gragert**

**Date Reviewed: 3/18/2013**

**Guidance: USEPA National Functional Guidelines for Superfund Organic Methods Data Review 2008**

| Sample Identification | Sample Identification |
|---|---|
| EXH-SVE-02202013 | MainHeader-SVE-02202013 |
| PWHeader-SVE-02202013 | |

## 1.0 Data Package Completeness

*Were all items delivered as specified in the QAPP and COC as appropriate?*

Yes

## 2.0 Laboratory Case Narrative \ Cooler Receipt Form

*Were problems noted in the laboratory case narrative or cooler receipt form?*

Yes, the laboratory case narrative indicated samples EXH-SVE-02202013, MainHeadrer-SVE-02202013, and PWHeader-SVE-02202013 were diluted due to high levels of target analytes. Recovery of the surrogate fluorobenzene was outside evaluation criteria for TPH sample MainHeader-SVE-02202013 due to high levels of hydrocarbon matrix interference. Although not indicated in the laboratory case narrative, analytes were detected in the method blank. The CCV recovery for bromomethane was outside evaluation criteria. These issues are addressed further in the appropriate sections below. The reporting limit for 4-methyl-2-pentanone was raised from 5.0 ppbv to 20 ppbv; 4-methyl-2-pentanone was not detected in samples for this SDG. For purposes of compliance monitoring, concentrations of non-detects are calculated as being equal to half of the reporting limit.

The cooler receipt form did not indicate any problems.

## 3.0 Holding Times

*Were samples extracted/analyzed within applicable limits?*

Yes

## 4.0 Blank Contamination

*Were any analytes detected in the Blanks?*

Yes

| Blank ID | Parameter | Analyte | Concentration/Amount |
|---|---|---|---|
| 1302458A-04A | TO-15 | Ethanol | 12 ppbv / 23 µg/$m^3$ |
| 1302458A-04A | TO-15 | Methylene chloride | 1.7 ppbv / 5.9 µg/$m^3$ |
| 1302458A-04A | TO-15 | alpha-Chlorotoluene | 1.0 ppbv / 5.5 µg/$m^3$ |

| Blank ID | Parameter | Analyte | Concentration/Amount |
|---|---|---|---|
| 1302458A-04A | TO-15 | Isopentane | 3.9 ppbv / 11 µg/$m^3$ |
| 1302458B-04A | TO-3 | TPH (C2-C10) | 0.012 ppmv/ 0.049 µg/L |
| 1302458C-04A | ASTM D-1945 | Nitrogen | 0.076% |

Analytical data that were reported non-detect or at concentrations greater than five times (5X) the associated blank concentration did not require qualification. No qualification of data was required.

## 5.0 Laboratory Control Sample

*Were LCS recoveries within evaluation criteria?*

No

| LCS/ LCSD ID | Parameter | Analyte | LCS/LCSD Recovery | RPD | LCS/LCSD /RPD Criteria |
|---|---|---|---|---|---|
| 1302458A-06A/AA | TO-15 | trans-1,2-Dichloroethene | 127**/133** | 5 | 70-130/25 |

Analytical data reported as non-detect and associated with LCS recoveries above evaluation criteria, indicating a possible high bias, did not require qualification. No qualification of data was required.

## 6.0 Surrogate Recoveries

*Were surrogate recoveries within evaluation criteria?*

No

| Sample ID | Parameter | Surrogate | Recovery (%) | Criteria (%) |
|---|---|---|---|---|
| MainHeader-SVE-02202013 | TO-3 | Fluorobenzene | **214** | 75-150 |

Analytical data that required qualification based on surrogate data are included in the table below.

| Sample ID | Parameter | Analyte | Qualification |
|---|---|---|---|
| MainHeader-SVE-02202013 | TO-3 | TPH (C2-C10) ref. to gasoline | **J** |

## 7.0 Matrix Spike and Matrix Spike Duplicate Recoveries

*Were MS/MSD samples analyzed as part of this SDG?*

MS/MSD samples are not applicable for vapor samples due to the inability to spike the samples in summa canisters.

## 8.0 Laboratory Duplicate Results

*Were laboratory duplicate samples collected as part of this SDG?*

No

## 9.0 Field Duplicate Results

*Were field duplicate samples collected as part of this SDG?*

No

## 10.0 Sample Dilutions

*For samples that were diluted and nondetect, were undiluted results also reported?*

Not applicable; analytes were detected in samples that were diluted.

## 11.0 Additional Qualifications

*Were additional qualifications applied?*

Yes, continuing calibration verification (CCV) recoveries listed in the table below were below evaluation criteria.

| CCV ID | Parameter | Analyte | CCV Recovery | CCV Criteria |
|---|---|---|---|---|
| 1302458A-05A | TO-15 | Bromomethane | **69** | 70-130 |

Analytical data that required qualification based on CCV data are included in the table below.

| Field ID | Parameter | Analyte | Qualification |
|---|---|---|---|
| EXH-SVE-02202013 | TO-15 | Bromomethane | **UJ** |
| MainHeader-SVE-02202013 | TO-15 | Bromomethane | **UJ** |
| PWHeader-SVE-02202013 | TO-15 | Bromomethane | **UJ** |

eurofins | Air Toxics

3/11/2013
Ms. Elizabeth Kunkel
URS Corporation
1001 Highlands Plaza Dr. West
Suite 300
St. Louis MO 63110

Project Name: Roxana SVE O&M
Project #: 21562850.05000
Workorder #: 1302458A

Dear Ms. Elizabeth Kunkel

The following report includes the data for the above referenced project for sample(s) received on 2/25/2013 at Air Toxics Ltd.

The data and associated QC analyzed by Modified TO-15 are compliant with the project requirements or laboratory criteria with the exception of the deviations noted in the attached case narrative.

Thank you for choosing Air Toxics Ltd. for your air analysis needs. Air Toxics Ltd. is committed to providing accurate data of the highest quality. Please feel free to contact the Project Manager: Kelly Buettner at 916-985-1000 if you have any questions regarding the data in this report.

Regards,

Kelly Buettner

Project Manager

Reviewed
on
3/18/2013

eurofins | Air Toxics

# WORK ORDER #: 1302458A

Work Order Summary

| | | | |
|---|---|---|---|
| **CLIENT:** | Ms. Elizabeth Kunkel<br>URS Corporation<br>1001 Highlands Plaza Dr. West<br>Suite 300<br>St. Louis, MO 63110 | **BILL TO:** | Accounts Payable Austin<br>URS Corporation<br>P.O. BOX 203970<br>Austin, TX 78720-1088 |
| **PHONE:** | 314-743-4179 | **P.O. #** | |
| **FAX:** | | **PROJECT #** | 21562850.05000 Roxana SVE O&M |
| **DATE RECEIVED:** | 02/25/2013 | **CONTACT:** | Kelly Buettner |
| **DATE COMPLETED:** | 03/11/2013 | | |

| FRACTION # | NAME | TEST | RECEIPT VAC./PRES. | FINAL PRESSURE |
|---|---|---|---|---|
| 01A | EXH-SVE-02202013 | Modified TO-15 | 9.0 "Hg | 15 psi |
| 02A | MainHeader-SVE-02202013 | Modified TO-15 | 9.0 "Hg | 15 psi |
| 03A | PWHeader-SVE-02202013 | Modified TO-15 | 8.5 "Hg | 15 psi |
| 04A | Lab Blank | Modified TO-15 | NA | NA |
| 05A | CCV | Modified TO-15 | NA | NA |
| 06A | LCS | Modified TO-15 | NA | NA |
| 06AA | LCSD | Modified TO-15 | NA | NA |

CERTIFIED BY: Heidi Hayes DATE: 03/11/13

Technical Director

Certfication numbers: AZ Licensure AZ0775, CA NELAP - 12282CA, NY NELAP - 11291,
TX NELAP - T104704434-12-5, UT NELAP CA009332012-3, WA NELAP - C935
Name of Accrediting Agency: NELAP/ORELAP (Oregon Environmental Laboratory Accreditation Program)
Accreditation number: CA300005, Effective date: 10/18/2011, Expiration date: 10/17/2012.
Eurofins Air Toxics Ltd. certifies that the test results contained in this report meet all requirements of the NELAC standards

This report shall not be reproduced, except in full, without the written approval of Eurofins Air Toxics, Inc.

180 BLUE RAVINE ROAD, SUITE B FOLSOM, CA - 9563
(916) 985-1000 . (800) 985-5955 . FAX (916) 985-1020

**LABORATORY NARRATIVE**
**EPA Method TO-15**
**URS Corporation**
**Workorder# 1302458A**

Three 1 Liter Summa Canister samples were received on February 25, 2013. The laboratory performed analysis via EPA Method TO-15 using GC/MS in the full scan mode.

This workorder was independently validated prior to submittal using 'USEPA National Functional Guidelines' as generally applied to the analysis of volatile organic compounds in air. A rules-based, logic driven, independent validation engine was employed to assess completeness, evaluate pass/fail of relevant project quality control requirements and verification of all quantified amounts.

**Receiving Notes**

There were no receiving discrepancies.

**Analytical Notes**

As per client project requirements, the laboratory has reported estimated values for target compound hits that are below the Reporting Limit but greater than the Method Detection Limit. Concentrations that are below the level at which the canister was certified may be false positives.

Dilution was performed on all of the samples due to the presence of high level target species.

All Quality Control Limit exceedances and affected sample results are noted by flags. Each flag is defined at the bottom of this Case Narrative and on each Sample Result Summary page.

Due to the linear calibration range of the instrument, the reporting limit for 4-Methyl-2-pentanone was raised from 5.0 ppbv to 20 ppbv.

**Definition of Data Qualifying Flags**

Eight qualifiers may have been used on the data analysis sheets and indicates as follows:

B - Compound present in laboratory blank greater than reporting limit (background subtraction not performed).
J - Estimated value.
E - Exceeds instrument calibration range.
S - Saturated peak.
Q - Exceeds quality control limits.
U - Compound analyzed for but not detected above the reporting limit.
UJ- Non-detected compound associated with low bias in the CCV and/or LCS.
N - The identification is based on presumptive evidence.

File extensions may have been used on the data analysis sheets and indicates as follows:
a-File was requantified
b-File was quantified by a second column and detector
r1-File was requantified for the purpose of reissue

eurofins | Air Toxics

# Summary of Detected Compounds
# EPA METHOD TO-15 GC/MS

**Client Sample ID: EXH-SVE-02202013**

**Lab ID#: 1302458A-01A**

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Acetone | 72 | 17 J | 170 | 41 J |
| Methylene Chloride | 18 | 8.7 J | 63 | 30 J |
| Hexane | 18 | 3100 | 64 | 11000 |
| Cyclohexane | 18 | 640 | 62 | 2200 |
| 2,2,4-Trimethylpentane | 18 | 2300 | 84 | 11000 |
| Benzene | 18 | 1700 | 58 | 5400 |
| Heptane | 18 | 670 | 74 | 2800 |
| Toluene | 18 | 150 | 68 | 580 |
| Ethyl Benzene | 18 | 24 | 78 | 100 |
| m,p-Xylene | 18 | 33 | 78 | 140 |
| o-Xylene | 18 | 3.1 J | 78 | 13 J |
| Butane | 72 | 8000 | 170 | 19000 |
| Isopentane | 72 | 10000 | 210 | 31000 |

**Client Sample ID: MainHeader-SVE-02202013**

**Lab ID#: 1302458A-02A**

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| 2-Propanol | 18000 | 1500 J | 44000 | 3800 J |
| Methylene Chloride | 4500 | 2600 J | 16000 | 8900 J |
| Hexane | 4500 | 550000 | 16000 | 2000000 |
| Cyclohexane | 4500 | 110000 | 16000 | 380000 |
| 2,2,4-Trimethylpentane | 4500 | 420000 | 21000 | 2000000 |
| Benzene | 4500 | 29000 | 14000 | 94000 |
| Heptane | 4500 | 120000 | 18000 | 490000 |
| Toluene | 4500 | 31000 | 17000 | 120000 |
| Ethyl Benzene | 4500 | 5100 | 20000 | 22000 |
| m,p-Xylene | 4500 | 11000 | 20000 | 48000 |
| o-Xylene | 4500 | 2700 J | 20000 | 12000 J |
| 4-Ethyltoluene | 4500 | 1900 J | 22000 | 9300 J |
| 1,2,4-Trimethylbenzene | 4500 | 1300 J | 22000 | 6500 J |
| Butane | 18000 | 1500000 | 43000 | 3500000 |
| Isopentane | 18000 | 1800000 | 53000 | 5200000 |

eurofins | Air Toxics

# Summary of Detected Compounds
# EPA METHOD TO-15 GC/MS

**Client Sample ID: PWHeader-SVE-02202013**

**Lab ID#: 1302458A-03A**

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Methylene Chloride | 1400 | 620 J | 4900 | 2200 J |
| Hexane | 1400 | 75000 | 5000 | 260000 |
| Cyclohexane | 1400 | 18000 | 4800 | 64000 |
| 2,2,4-Trimethylpentane | 1400 | 52000 | 6600 | 240000 |
| Benzene | 1400 | 420000 | 4500 | 1300000 |
| Heptane | 1400 | 9800 | 5800 | 40000 |
| Toluene | 1400 | 2000 | 5300 | 7400 |
| Ethyl Benzene | 1400 | 490 J | 6100 | 2100 J |
| m,p-Xylene | 1400 | 710 J | 6100 | 3100 J |
| o-Xylene | 1400 | 230 J | 6100 | 990 J |
| 1,2,4-Trimethylbenzene | 1400 | 330 J | 6900 | 1600 J |
| Butane | 5600 | 370000 | 13000 | 880000 |
| Isopentane | 5600 | 730000 | 17000 | 2200000 |

eurofins | Air Toxics

**Client Sample ID: EXH-SVE-02202013**

**Lab ID#: 1302458A-01A**

**EPA METHOD TO-15 GC/MS**

| | | | |
|---|---|---|---|
| **File Name:** | **14030123** | **Date of Collection: 2/20/13 12:30:00 PM** | |
| **Dil. Factor:** | **3.61** | **Date of Analysis: 3/1/13 05:31 PM** | |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 18 | Not Detected | 89 | Not Detected |
| Freon 114 | 18 | Not Detected | 130 | Not Detected |
| Chloromethane | 72 | Not Detected | 150 | Not Detected |
| Vinyl Chloride | 18 | Not Detected | 46 | Not Detected |
| 1,3-Butadiene | 18 | Not Detected | 40 | Not Detected |
| Bromomethane | 18 | Not Detected UJ UJ | 70 | Not Detected UJ UJ |
| Chloroethane | 72 | Not Detected | 190 | Not Detected |
| Freon 11 | 18 | Not Detected | 100 | Not Detected |
| Ethanol | 72 | Not Detected | 140 | Not Detected |
| Freon 113 | 18 | Not Detected | 140 | Not Detected |
| 1,1-Dichloroethene | 18 | Not Detected | 72 | Not Detected |
| Acetone | 72 | 17 J | 170 | 41 J |
| 2-Propanol | 72 | Not Detected | 180 | Not Detected |
| Carbon Disulfide | 18 | Not Detected | 56 | Not Detected |
| 3-Chloropropene | 72 | Not Detected | 220 | Not Detected |
| Methylene Chloride | 18 | 8.7 J | 63 | 30 J |
| Methyl tert-butyl ether | 18 | Not Detected | 65 | Not Detected |
| trans-1,2-Dichloroethene | 18 | Not Detected | 72 | Not Detected |
| Hexane | 18 | 3100 | 64 | 11000 |
| 1,1-Dichloroethane | 18 | Not Detected | 73 | Not Detected |
| 2-Butanone (Methyl Ethyl Ketone) | 72 | Not Detected | 210 | Not Detected |
| cis-1,2-Dichloroethene | 18 | Not Detected | 72 | Not Detected |
| Tetrahydrofuran | 18 | Not Detected | 53 | Not Detected |
| Chloroform | 18 | Not Detected | 88 | Not Detected |
| 1,1,1-Trichloroethane | 18 | Not Detected | 98 | Not Detected |
| Cyclohexane | 18 | 640 | 62 | 2200 |
| Carbon Tetrachloride | 18 | Not Detected | 110 | Not Detected |
| 2,2,4-Trimethylpentane | 18 | 2300 | 84 | 11000 |
| Benzene | 18 | 1700 | 58 | 5400 |
| 1,2-Dichloroethane | 18 | Not Detected | 73 | Not Detected |
| Heptane | 18 | 670 | 74 | 2800 |
| Trichloroethene | 18 | Not Detected | 97 | Not Detected |
| 1,2-Dichloropropane | 18 | Not Detected | 83 | Not Detected |
| 1,4-Dioxane | 72 | Not Detected | 260 | Not Detected |
| Bromodichloromethane | 18 | Not Detected | 120 | Not Detected |
| cis-1,3-Dichloropropene | 18 | Not Detected | 82 | Not Detected |
| 4-Methyl-2-pentanone | 72 | Not Detected | 300 | Not Detected |
| Toluene | 18 | 150 | 68 | 580 |
| trans-1,3-Dichloropropene | 18 | Not Detected | 82 | Not Detected |
| 1,1,2-Trichloroethane | 18 | Not Detected | 98 | Not Detected |
| Tetrachloroethene | 18 | Not Detected | 120 | Not Detected |
| 2-Hexanone | 72 | Not Detected | 300 | Not Detected |

eurofins | Air Toxics

**Client Sample ID: EXH-SVE-02202013**

**Lab ID#: 1302458A-01A**

**EPA METHOD TO-15 GC/MS**

| | | | |
|---|---|---|---|
| **File Name:** | **14030123** | **Date of Collection: 2/20/13 12:30:00 PM** | |
| **Dil. Factor:** | **3.61** | **Date of Analysis: 3/1/13 05:31 PM** | |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Dibromochloromethane | 18 | Not Detected | 150 | Not Detected |
| 1,2-Dibromoethane (EDB) | 18 | Not Detected | 140 | Not Detected |
| Chlorobenzene | 18 | Not Detected | 83 | Not Detected |
| Ethyl Benzene | 18 | 24 | 78 | 100 |
| m,p-Xylene | 18 | 33 | 78 | 140 |
| o-Xylene | 18 | 3.1 J | 78 | 13 J |
| Styrene | 18 | Not Detected | 77 | Not Detected |
| Bromoform | 18 | Not Detected | 190 | Not Detected |
| Cumene | 18 | Not Detected | 89 | Not Detected |
| 1,1,2,2-Tetrachloroethane | 18 | Not Detected | 120 | Not Detected |
| Propylbenzene | 18 | Not Detected | 89 | Not Detected |
| 4-Ethyltoluene | 18 | Not Detected | 89 | Not Detected |
| 1,3,5-Trimethylbenzene | 18 | Not Detected | 89 | Not Detected |
| 1,2,4-Trimethylbenzene | 18 | Not Detected | 89 | Not Detected |
| 1,3-Dichlorobenzene | 18 | Not Detected | 110 | Not Detected |
| 1,4-Dichlorobenzene | 18 | Not Detected | 110 | Not Detected |
| alpha-Chlorotoluene | 18 | Not Detected | 93 | Not Detected |
| 1,2-Dichlorobenzene | 18 | Not Detected | 110 | Not Detected |
| 1,2,4-Trichlorobenzene | 72 | Not Detected | 540 | Not Detected |
| Hexachlorobutadiene | 72 | Not Detected | 770 | Not Detected |
| Butane | 72 | 8000 | 170 | 19000 |
| Isopentane | 72 | 10000 | 210 | 31000 |

UJ = Non-detected compound associated with low bias in the CCV and/or LCS.
J = Estimated value.
**Container Type: 1 Liter Summa Canister**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| 1,2-Dichloroethane-d4 | 116 | 70-130 |
| Toluene-d8 | 100 | 70-130 |
| 4-Bromofluorobenzene | 99 | 70-130 |

eurofins | Air Toxics

**Client Sample ID: MainHeader-SVE-02202013**

**Lab ID#: 1302458A-02A**

**EPA METHOD TO-15 GC/MS**

| | | | |
|---|---|---|---|
| **File Name:** | 14030124 | **Date of Collection:** | 2/20/13 12:50:00 PM |
| **Dil. Factor:** | 903 | **Date of Analysis:** | 3/1/13 05:57 PM |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 4500 | Not Detected | 22000 | Not Detected |
| Freon 114 | 4500 | Not Detected | 32000 | Not Detected |
| Chloromethane | 18000 | Not Detected | 37000 | Not Detected |
| Vinyl Chloride | 4500 | Not Detected | 12000 | Not Detected |
| 1,3-Butadiene | 4500 | Not Detected | 10000 | Not Detected |
| Bromomethane | 4500 | Not Detected UJ | 18000 | Not Detected UJ |
| Chloroethane | 18000 | Not Detected | 48000 | Not Detected |
| Freon 11 | 4500 | Not Detected | 25000 | Not Detected |
| Ethanol | 18000 | Not Detected | 34000 | Not Detected |
| Freon 113 | 4500 | Not Detected | 35000 | Not Detected |
| 1,1-Dichloroethene | 4500 | Not Detected | 18000 | Not Detected |
| Acetone | 18000 | Not Detected | 43000 | Not Detected |
| 2-Propanol | 18000 | 1500 J | 44000 | 3800 J |
| Carbon Disulfide | 4500 | Not Detected | 14000 | Not Detected |
| 3-Chloropropene | 18000 | Not Detected | 56000 | Not Detected |
| Methylene Chloride | 4500 | 2600 J | 16000 | 8900 J |
| Methyl tert-butyl ether | 4500 | Not Detected | 16000 | Not Detected |
| trans-1,2-Dichloroethene | 4500 | Not Detected | 18000 | Not Detected |
| Hexane | 4500 | 550000 | 16000 | 2000000 |
| 1,1-Dichloroethane | 4500 | Not Detected | 18000 | Not Detected |
| 2-Butanone (Methyl Ethyl Ketone) | 18000 | Not Detected | 53000 | Not Detected |
| cis-1,2-Dichloroethene | 4500 | Not Detected | 18000 | Not Detected |
| Tetrahydrofuran | 4500 | Not Detected | 13000 | Not Detected |
| Chloroform | 4500 | Not Detected | 22000 | Not Detected |
| 1,1,1-Trichloroethane | 4500 | Not Detected | 25000 | Not Detected |
| Cyclohexane | 4500 | 110000 | 16000 | 380000 |
| Carbon Tetrachloride | 4500 | Not Detected | 28000 | Not Detected |
| 2,2,4-Trimethylpentane | 4500 | 420000 | 21000 | 2000000 |
| Benzene | 4500 | 29000 | 14000 | 94000 |
| 1,2-Dichloroethane | 4500 | Not Detected | 18000 | Not Detected |
| Heptane | 4500 | 120000 | 18000 | 490000 |
| Trichloroethene | 4500 | Not Detected | 24000 | Not Detected |
| 1,2-Dichloropropane | 4500 | Not Detected | 21000 | Not Detected |
| 1,4-Dioxane | 18000 | Not Detected | 65000 | Not Detected |
| Bromodichloromethane | 4500 | Not Detected | 30000 | Not Detected |
| cis-1,3-Dichloropropene | 4500 | Not Detected | 20000 | Not Detected |
| 4-Methyl-2-pentanone | 18000 | Not Detected | 74000 | Not Detected |
| Toluene | 4500 | 31000 | 17000 | 120000 |
| trans-1,3-Dichloropropene | 4500 | Not Detected | 20000 | Not Detected |
| 1,1,2-Trichloroethane | 4500 | Not Detected | 25000 | Not Detected |
| Tetrachloroethene | 4500 | Not Detected | 31000 | Not Detected |
| 2-Hexanone | 18000 | Not Detected | 74000 | Not Detected |

eurofins | Air Toxics

**Client Sample ID: MainHeader-SVE-02202013**

**Lab ID#: 1302458A-02A**

**EPA METHOD TO-15 GC/MS**

| | | | |
|---|---|---|---|
| **File Name:** | **14030124** | **Date of Collection: 2/20/13 12:50:00 PM** | |
| **Dil. Factor:** | **903** | **Date of Analysis: 3/1/13 05:57 PM** | |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Dibromochloromethane | 4500 | Not Detected | 38000 | Not Detected |
| 1,2-Dibromoethane (EDB) | 4500 | Not Detected | 35000 | Not Detected |
| Chlorobenzene | 4500 | Not Detected | 21000 | Not Detected |
| Ethyl Benzene | 4500 | 5100 | 20000 | 22000 |
| m,p-Xylene | 4500 | 11000 | 20000 | 48000 |
| o-Xylene | 4500 | 2700 J | 20000 | 12000 J |
| Styrene | 4500 | Not Detected | 19000 | Not Detected |
| Bromoform | 4500 | Not Detected | 47000 | Not Detected |
| Cumene | 4500 | Not Detected | 22000 | Not Detected |
| 1,1,2,2-Tetrachloroethane | 4500 | Not Detected | 31000 | Not Detected |
| Propylbenzene | 4500 | Not Detected | 22000 | Not Detected |
| 4-Ethyltoluene | 4500 | 1900 J | 22000 | 9300 J |
| 1,3,5-Trimethylbenzene | 4500 | Not Detected | 22000 | Not Detected |
| 1,2,4-Trimethylbenzene | 4500 | 1300 J | 22000 | 6500 J |
| 1,3-Dichlorobenzene | 4500 | Not Detected | 27000 | Not Detected |
| 1,4-Dichlorobenzene | 4500 | Not Detected | 27000 | Not Detected |
| alpha-Chlorotoluene | 4500 | Not Detected | 23000 | Not Detected |
| 1,2-Dichlorobenzene | 4500 | Not Detected | 27000 | Not Detected |
| 1,2,4-Trichlorobenzene | 18000 | Not Detected | 130000 | Not Detected |
| Hexachlorobutadiene | 18000 | Not Detected | 190000 | Not Detected |
| Butane | 18000 | 1500000 | 43000 | 3500000 |
| Isopentane | 18000 | 1800000 | 53000 | 5200000 |

UJ = Non-detected compound associated with low bias in the CCV and/or LCS.
J = Estimated value.

**Container Type: 1 Liter Summa Canister**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| 1,2-Dichloroethane-d4 | 115 | 70-130 |
| Toluene-d8 | 98 | 70-130 |
| 4-Bromofluorobenzene | 97 | 70-130 |

eurofins | Air Toxics

**Client Sample ID: PWHeader-SVE-02202013**

**Lab ID#: 1302458A-03A**

**EPA METHOD TO-15 GC/MS**

| | | | |
|---|---|---|---|
| **File Name:** | **14030125** | **Date of Collection:** | **2/20/13 1:05:00 PM** |
| **Dil. Factor:** | **282** | **Date of Analysis:** | **3/1/13 06:30 PM** |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 1400 | Not Detected | 7000 | Not Detected |
| Freon 114 | 1400 | Not Detected | 9800 | Not Detected |
| Chloromethane | 5600 | Not Detected | 12000 | Not Detected |
| Vinyl Chloride | 1400 | Not Detected | 3600 | Not Detected |
| 1,3-Butadiene | 1400 | Not Detected | 3100 | Not Detected |
| Bromomethane | 1400 | Not Detected UJ UJ | 5500 | Not Detected UJ UJ |
| Chloroethane | 5600 | Not Detected | 15000 | Not Detected |
| Freon 11 | 1400 | Not Detected | 7900 | Not Detected |
| Ethanol | 5600 | Not Detected | 11000 | Not Detected |
| Freon 113 | 1400 | Not Detected | 11000 | Not Detected |
| 1,1-Dichloroethene | 1400 | Not Detected | 5600 | Not Detected |
| Acetone | 5600 | Not Detected | 13000 | Not Detected |
| 2-Propanol | 5600 | Not Detected | 14000 | Not Detected |
| Carbon Disulfide | 1400 | Not Detected | 4400 | Not Detected |
| 3-Chloropropene | 5600 | Not Detected | 18000 | Not Detected |
| Methylene Chloride | 1400 | 620 J | 4900 | 2200 J |
| Methyl tert-butyl ether | 1400 | Not Detected | 5100 | Not Detected |
| trans-1,2-Dichloroethene | 1400 | Not Detected | 5600 | Not Detected |
| Hexane | 1400 | 75000 | 5000 | 260000 |
| 1,1-Dichloroethane | 1400 | Not Detected | 5700 | Not Detected |
| 2-Butanone (Methyl Ethyl Ketone) | 5600 | Not Detected | 17000 | Not Detected |
| cis-1,2-Dichloroethene | 1400 | Not Detected | 5600 | Not Detected |
| Tetrahydrofuran | 1400 | Not Detected | 4200 | Not Detected |
| Chloroform | 1400 | Not Detected | 6900 | Not Detected |
| 1,1,1-Trichloroethane | 1400 | Not Detected | 7700 | Not Detected |
| Cyclohexane | 1400 | 18000 | 4800 | 64000 |
| Carbon Tetrachloride | 1400 | Not Detected | 8900 | Not Detected |
| 2,2,4-Trimethylpentane | 1400 | 52000 | 6600 | 240000 |
| Benzene | 1400 | 420000 | 4500 | 1300000 |
| 1,2-Dichloroethane | 1400 | Not Detected | 5700 | Not Detected |
| Heptane | 1400 | 9800 | 5800 | 40000 |
| Trichloroethene | 1400 | Not Detected | 7600 | Not Detected |
| 1,2-Dichloropropane | 1400 | Not Detected | 6500 | Not Detected |
| 1,4-Dioxane | 5600 | Not Detected | 20000 | Not Detected |
| Bromodichloromethane | 1400 | Not Detected | 9400 | Not Detected |
| cis-1,3-Dichloropropene | 1400 | Not Detected | 6400 | Not Detected |
| 4-Methyl-2-pentanone | 5600 | Not Detected | 23000 | Not Detected |
| Toluene | 1400 | 2000 | 5300 | 7400 |
| trans-1,3-Dichloropropene | 1400 | Not Detected | 6400 | Not Detected |
| 1,1,2-Trichloroethane | 1400 | Not Detected | 7700 | Not Detected |
| Tetrachloroethene | 1400 | Not Detected | 9600 | Not Detected |
| 2-Hexanone | 5600 | Not Detected | 23000 | Not Detected |

eurofins | Air Toxics

**Client Sample ID: PWHeader-SVE-02202013**

**Lab ID#: 1302458A-03A**

**EPA METHOD TO-15 GC/MS**

| | | | |
|---|---|---|---|
| **File Name:** | **14030125** | **Date of Collection: 2/20/13 1:05:00 PM** | |
| **Dil. Factor:** | **282** | **Date of Analysis: 3/1/13 06:30 PM** | |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Dibromochloromethane | 1400 | Not Detected | 12000 | Not Detected |
| 1,2-Dibromoethane (EDB) | 1400 | Not Detected | 11000 | Not Detected |
| Chlorobenzene | 1400 | Not Detected | 6500 | Not Detected |
| Ethyl Benzene | 1400 | 490 J | 6100 | 2100 J |
| m,p-Xylene | 1400 | 710 J | 6100 | 3100 J |
| o-Xylene | 1400 | 230 J | 6100 | 990 J |
| Styrene | 1400 | Not Detected | 6000 | Not Detected |
| Bromoform | 1400 | Not Detected | 14000 | Not Detected |
| Cumene | 1400 | Not Detected | 6900 | Not Detected |
| 1,1,2,2-Tetrachloroethane | 1400 | Not Detected | 9700 | Not Detected |
| Propylbenzene | 1400 | Not Detected | 6900 | Not Detected |
| 4-Ethyltoluene | 1400 | Not Detected | 6900 | Not Detected |
| 1,3,5-Trimethylbenzene | 1400 | Not Detected | 6900 | Not Detected |
| 1,2,4-Trimethylbenzene | 1400 | 330 J | 6900 | 1600 J |
| 1,3-Dichlorobenzene | 1400 | Not Detected | 8500 | Not Detected |
| 1,4-Dichlorobenzene | 1400 | Not Detected | 8500 | Not Detected |
| alpha-Chlorotoluene | 1400 | Not Detected | 7300 | Not Detected |
| 1,2-Dichlorobenzene | 1400 | Not Detected | 8500 | Not Detected |
| 1,2,4-Trichlorobenzene | 5600 | Not Detected | 42000 | Not Detected |
| Hexachlorobutadiene | 5600 | Not Detected | 60000 | Not Detected |
| Butane | 5600 | 370000 | 13000 | 880000 |
| Isopentane | 5600 | 730000 | 17000 | 2200000 |

UJ = Non-detected compound associated with low bias in the CCV and/or LCS.
J = Estimated value.
**Container Type: 1 Liter Summa Canister**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| 1,2-Dichloroethane-d4 | 114 | 70-130 |
| Toluene-d8 | 97 | 70-130 |
| 4-Bromofluorobenzene | 100 | 70-130 |

eurofins | Air Toxics

**Client Sample ID: Lab Blank**

**Lab ID#: 1302458A-04A**

**EPA METHOD TO-15 GC/MS**

| | | | |
|---|---|---|---|
| **File Name:** | **14030106a** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 3/1/13 09:21 AM** | |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 5.0 | Not Detected | 25 | Not Detected |
| Freon 114 | 5.0 | Not Detected | 35 | Not Detected |
| Chloromethane | 20 | Not Detected | 41 | Not Detected |
| Vinyl Chloride | 5.0 | Not Detected | 13 | Not Detected |
| 1,3-Butadiene | 5.0 | Not Detected | 11 | Not Detected |
| Bromomethane | 5.0 | Not Detected UJ | 19 | Not Detected UJ |
| Chloroethane | 20 | Not Detected | 53 | Not Detected |
| Freon 11 | 5.0 | Not Detected | 28 | Not Detected |
| Ethanol | 20 | 12 J | 38 | 23 J |
| Freon 113 | 5.0 | Not Detected | 38 | Not Detected |
| 1,1-Dichloroethene | 5.0 | Not Detected | 20 | Not Detected |
| Acetone | 20 | Not Detected | 48 | Not Detected |
| 2-Propanol | 20 | Not Detected | 49 | Not Detected |
| Carbon Disulfide | 5.0 | Not Detected | 16 | Not Detected |
| 3-Chloropropene | 20 | Not Detected | 63 | Not Detected |
| Methylene Chloride | 5.0 | 1.7 J | 17 | 5.9 J |
| Methyl tert-butyl ether | 5.0 | Not Detected | 18 | Not Detected |
| trans-1,2-Dichloroethene | 5.0 | Not Detected | 20 | Not Detected |
| Hexane | 5.0 | Not Detected | 18 | Not Detected |
| 1,1-Dichloroethane | 5.0 | Not Detected | 20 | Not Detected |
| 2-Butanone (Methyl Ethyl Ketone) | 20 | Not Detected | 59 | Not Detected |
| cis-1,2-Dichloroethene | 5.0 | Not Detected | 20 | Not Detected |
| Tetrahydrofuran | 5.0 | Not Detected | 15 | Not Detected |
| Chloroform | 5.0 | Not Detected | 24 | Not Detected |
| 1,1,1-Trichloroethane | 5.0 | Not Detected | 27 | Not Detected |
| Cyclohexane | 5.0 | Not Detected | 17 | Not Detected |
| Carbon Tetrachloride | 5.0 | Not Detected | 31 | Not Detected |
| 2,2,4-Trimethylpentane | 5.0 | Not Detected | 23 | Not Detected |
| Benzene | 5.0 | Not Detected | 16 | Not Detected |
| 1,2-Dichloroethane | 5.0 | Not Detected | 20 | Not Detected |
| Heptane | 5.0 | Not Detected | 20 | Not Detected |
| Trichloroethene | 5.0 | Not Detected | 27 | Not Detected |
| 1,2-Dichloropropane | 5.0 | Not Detected | 23 | Not Detected |
| 1,4-Dioxane | 20 | Not Detected | 72 | Not Detected |
| Bromodichloromethane | 5.0 | Not Detected | 34 | Not Detected |
| cis-1,3-Dichloropropene | 5.0 | Not Detected | 23 | Not Detected |
| 4-Methyl-2-pentanone | 20 | Not Detected | 82 | Not Detected |
| Toluene | 5.0 | Not Detected | 19 | Not Detected |
| trans-1,3-Dichloropropene | 5.0 | Not Detected | 23 | Not Detected |
| 1,1,2-Trichloroethane | 5.0 | Not Detected | 27 | Not Detected |
| Tetrachloroethene | 5.0 | Not Detected | 34 | Not Detected |
| 2-Hexanone | 20 | Not Detected | 82 | Not Detected |

eurofins | Air Toxics

**Client Sample ID: Lab Blank**

**Lab ID#: 1302458A-04A**

**EPA METHOD TO-15 GC/MS**

| | | | |
|---|---|---|---|
| **File Name:** | **14030106a** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 3/1/13 09:21 AM** | |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Dibromochloromethane | 5.0 | Not Detected | 42 | Not Detected |
| 1,2-Dibromoethane (EDB) | 5.0 | Not Detected | 38 | Not Detected |
| Chlorobenzene | 5.0 | Not Detected | 23 | Not Detected |
| Ethyl Benzene | 5.0 | Not Detected | 22 | Not Detected |
| m,p-Xylene | 5.0 | Not Detected | 22 | Not Detected |
| o-Xylene | 5.0 | Not Detected | 22 | Not Detected |
| Styrene | 5.0 | Not Detected | 21 | Not Detected |
| Bromoform | 5.0 | Not Detected | 52 | Not Detected |
| Cumene | 5.0 | Not Detected | 24 | Not Detected |
| 1,1,2,2-Tetrachloroethane | 5.0 | Not Detected | 34 | Not Detected |
| Propylbenzene | 5.0 | Not Detected | 24 | Not Detected |
| 4-Ethyltoluene | 5.0 | Not Detected | 24 | Not Detected |
| 1,3,5-Trimethylbenzene | 5.0 | Not Detected | 24 | Not Detected |
| 1,2,4-Trimethylbenzene | 5.0 | Not Detected | 24 | Not Detected |
| 1,3-Dichlorobenzene | 5.0 | Not Detected | 30 | Not Detected |
| 1,4-Dichlorobenzene | 5.0 | Not Detected | 30 | Not Detected |
| alpha-Chlorotoluene | 5.0 | 1.0 J | 26 | 5.5 J |
| 1,2-Dichlorobenzene | 5.0 | Not Detected | 30 | Not Detected |
| 1,2,4-Trichlorobenzene | 20 | Not Detected | 150 | Not Detected |
| Hexachlorobutadiene | 20 | Not Detected | 210 | Not Detected |
| Butane | 20 | Not Detected | 48 | Not Detected |
| Isopentane | 20 | 3.9 J | 59 | 11 J |

UJ = Non-detected compound associated with low bias in the CCV and/or LCS.
J = Estimated value.
**Container Type: NA - Not Applicable**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| 1,2-Dichloroethane-d4 | 107 | 70-130 |
| Toluene-d8 | 100 | 70-130 |
| 4-Bromofluorobenzene | 101 | 70-130 |

**Client Sample ID: CCV**

**Lab ID#: 1302458A-05A**

**EPA METHOD TO-15 GC/MS**

| | | | |
|---|---|---|---|
| **File Name:** | **14030102** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 3/1/13 07:47 AM** | |

| Compound | %Recovery |
|---|---|
| Freon 12 | 118 |
| Freon 114 | 116 |
| Chloromethane | 105 |
| Vinyl Chloride | 98 |
| 1,3-Butadiene | 94 |
| Bromomethane | 69 Q |
| Chloroethane | 97 |
| Freon 11 | 114 |
| Ethanol | 113 |
| Freon 113 | 102 |
| 1,1-Dichloroethene | 117 |
| Acetone | 112 |
| 2-Propanol | 115 |
| Carbon Disulfide | 97 |
| 3-Chloropropene | 101 |
| Methylene Chloride | 94 |
| Methyl tert-butyl ether | 122 |
| trans-1,2-Dichloroethene | 120 |
| Hexane | 113 |
| 1,1-Dichloroethane | 112 |
| 2-Butanone (Methyl Ethyl Ketone) | 116 |
| cis-1,2-Dichloroethene | 110 |
| Tetrahydrofuran | 112 |
| Chloroform | 119 |
| 1,1,1-Trichloroethane | 119 |
| Cyclohexane | 116 |
| Carbon Tetrachloride | 117 |
| 2,2,4-Trimethylpentane | 113 |
| Benzene | 106 |
| 1,2-Dichloroethane | 110 |
| Heptane | 117 |
| Trichloroethene | 109 |
| 1,2-Dichloropropane | 104 |
| 1,4-Dioxane | 116 |
| Bromodichloromethane | 111 |
| cis-1,3-Dichloropropene | 110 |
| 4-Methyl-2-pentanone | 120 |
| Toluene | 106 |
| trans-1,3-Dichloropropene | 113 |
| 1,1,2-Trichloroethane | 107 |
| Tetrachloroethene | 114 |
| 2-Hexanone | 122 |

eurofins | Air Toxics

**Client Sample ID: CCV**

**Lab ID#: 1302458A-05A**

**EPA METHOD TO-15 GC/MS**

| | | | |
|---|---|---|---|
| **File Name:** | **14030102** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 3/1/13 07:47 AM** | |

| Compound | %Recovery |
|---|---|
| Dibromochloromethane | 113 |
| 1,2-Dibromoethane (EDB) | 113 |
| Chlorobenzene | 106 |
| Ethyl Benzene | 109 |
| m,p-Xylene | 112 |
| o-Xylene | 113 |
| Styrene | 116 |
| Bromoform | 113 |
| Cumene | 114 |
| 1,1,2,2-Tetrachloroethane | 109 |
| Propylbenzene | 112 |
| 4-Ethyltoluene | 116 |
| 1,3,5-Trimethylbenzene | 115 |
| 1,2,4-Trimethylbenzene | 115 |
| 1,3-Dichlorobenzene | 103 |
| 1,4-Dichlorobenzene | 104 |
| alpha-Chlorotoluene | 126 |
| 1,2-Dichlorobenzene | 103 |
| 1,2,4-Trichlorobenzene | 112 |
| Hexachlorobutadiene | 102 |
| Butane | 101 |
| Isopentane | 91 |

Q = Exceeds Quality Control limits.

**Container Type: NA - Not Applicable**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| 1,2-Dichloroethane-d4 | 106 | 70-130 |
| Toluene-d8 | 100 | 70-130 |
| 4-Bromofluorobenzene | 100 | 70-130 |

eurofins | Air Toxics

**Client Sample ID: LCS**

**Lab ID#: 1302458A-06A**

**EPA METHOD TO-15 GC/MS**

| | | | |
|---|---|---|---|
| **File Name:** | **14030103** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 3/1/13 08:10 AM** | |

| Compound | %Recovery |
|---|---|
| Freon 12 | 113 |
| Freon 114 | 111 |
| Chloromethane | 104 |
| Vinyl Chloride | 103 |
| 1,3-Butadiene | 97 |
| Bromomethane | 98 |
| Chloroethane | 103 |
| Freon 11 | 119 |
| Ethanol | 109 |
| Freon 113 | 101 |
| 1,1-Dichloroethene | 122 |
| Acetone | 105 |
| 2-Propanol | 114 |
| Carbon Disulfide | 119 |
| 3-Chloropropene | 113 |
| Methylene Chloride | 93 |
| Methyl tert-butyl ether | 118 |
| trans-1,2-Dichloroethene | 127 |
| Hexane | 106 |
| 1,1-Dichloroethane | 108 |
| 2-Butanone (Methyl Ethyl Ketone) | 112 |
| cis-1,2-Dichloroethene | 108 |
| Tetrahydrofuran | 105 |
| Chloroform | 117 |
| 1,1,1-Trichloroethane | 120 |
| Cyclohexane | 112 |
| Carbon Tetrachloride | 118 |
| 2,2,4-Trimethylpentane | 106 |
| Benzene | 104 |
| 1,2-Dichloroethane | 113 |
| Heptane | 110 |
| Trichloroethene | 107 |
| 1,2-Dichloropropane | 104 |
| 1,4-Dioxane | 113 |
| Bromodichloromethane | 111 |
| cis-1,3-Dichloropropene | 110 |
| 4-Methyl-2-pentanone | 114 |
| Toluene | 105 |
| trans-1,3-Dichloropropene | 113 |
| 1,1,2-Trichloroethane | 109 |
| Tetrachloroethene | 108 |
| 2-Hexanone | 116 |

eurofins | Air Toxics

**Client Sample ID: LCS**

**Lab ID#: 1302458A-06A**

**EPA METHOD TO-15 GC/MS**

| | | | |
|---|---|---|---|
| **File Name:** | **14030103** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 3/1/13 08:10 AM** | |

| Compound | %Recovery |
|---|---|
| Dibromochloromethane | 112 |
| 1,2-Dibromoethane (EDB) | 114 |
| Chlorobenzene | 105 |
| Ethyl Benzene | 104 |
| m,p-Xylene | 110 |
| o-Xylene | 109 |
| Styrene | 113 |
| Bromoform | 113 |
| Cumene | 115 |
| 1,1,2,2-Tetrachloroethane | 108 |
| Propylbenzene | 111 |
| 4-Ethyltoluene | 110 |
| 1,3,5-Trimethylbenzene | 113 |
| 1,2,4-Trimethylbenzene | 110 |
| 1,3-Dichlorobenzene | 102 |
| 1,4-Dichlorobenzene | 101 |
| alpha-Chlorotoluene | 123 |
| 1,2-Dichlorobenzene | 101 |
| 1,2,4-Trichlorobenzene | 102 |
| Hexachlorobutadiene | 94 |
| Butane | 95 |
| Isopentane | 104 |

**Container Type: NA - Not Applicable**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| 1,2-Dichloroethane-d4 | 103 | 70-130 |
| Toluene-d8 | 100 | 70-130 |
| 4-Bromofluorobenzene | 101 | 70-130 |

eurofins | Air Toxics

**Client Sample ID: LCSD**

**Lab ID#: 1302458A-06AA**

**EPA METHOD TO-15 GC/MS**

| | | | |
|---|---|---|---|
| **File Name:** | **14030104** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 3/1/13 08:31 AM** | |

| Compound | %Recovery |
|---|---|
| Freon 12 | 123 |
| Freon 114 | 116 |
| Chloromethane | 110 |
| Vinyl Chloride | 109 |
| 1,3-Butadiene | 103 |
| Bromomethane | 104 |
| Chloroethane | 107 |
| Freon 11 | 124 |
| Ethanol | 116 |
| Freon 113 | 106 |
| 1,1-Dichloroethene | 125 |
| Acetone | 112 |
| 2-Propanol | 119 |
| Carbon Disulfide | 124 |
| 3-Chloropropene | 118 |
| Methylene Chloride | 97 |
| Methyl tert-butyl ether | 124 |
| trans-1,2-Dichloroethene | 133 Q |
| Hexane | 111 |
| 1,1-Dichloroethane | 112 |
| 2-Butanone (Methyl Ethyl Ketone) | 117 |
| cis-1,2-Dichloroethene | 111 |
| Tetrahydrofuran | 107 |
| Chloroform | 123 |
| 1,1,1-Trichloroethane | 126 |
| Cyclohexane | 114 |
| Carbon Tetrachloride | 125 |
| 2,2,4-Trimethylpentane | 110 |
| Benzene | 106 |
| 1,2-Dichloroethane | 117 |
| Heptane | 113 |
| Trichloroethene | 112 |
| 1,2-Dichloropropane | 104 |
| 1,4-Dioxane | 115 |
| Bromodichloromethane | 115 |
| cis-1,3-Dichloropropene | 110 |
| 4-Methyl-2-pentanone | 117 |
| Toluene | 106 |
| trans-1,3-Dichloropropene | 116 |
| 1,1,2-Trichloroethane | 111 |
| Tetrachloroethene | 109 |
| 2-Hexanone | 119 |

**Client Sample ID: LCSD**
**Lab ID#: 1302458A-06AA**
**EPA METHOD TO-15 GC/MS**

| | | | |
|---|---|---|---|
| **File Name:** | **14030104** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 3/1/13 08:31 AM** | |

| Compound | %Recovery |
|---|---|
| Dibromochloromethane | 117 |
| 1,2-Dibromoethane (EDB) | 116 |
| Chlorobenzene | 106 |
| Ethyl Benzene | 107 |
| m,p-Xylene | 113 |
| o-Xylene | 110 |
| Styrene | 116 |
| Bromoform | 118 |
| Cumene | 118 |
| 1,1,2,2-Tetrachloroethane | 109 |
| Propylbenzene | 114 |
| 4-Ethyltoluene | 112 |
| 1,3,5-Trimethylbenzene | 115 |
| 1,2,4-Trimethylbenzene | 112 |
| 1,3-Dichlorobenzene | 103 |
| 1,4-Dichlorobenzene | 101 |
| alpha-Chlorotoluene | 125 |
| 1,2-Dichlorobenzene | 101 |
| 1,2,4-Trichlorobenzene | 107 |
| Hexachlorobutadiene | 94 |
| Butane | 104 |
| Isopentane | 110 |

Q = Exceeds Quality Control limits.

**Container Type: NA - Not Applicable**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| 1,2-Dichloroethane-d4 | 110 | 70-130 |
| Toluene-d8 | 101 | 70-130 |
| 4-Bromofluorobenzene | 101 | 70-130 |

# Shell Oil Products Chain Of Custody Record

URS

Air Toxics LTD.
**Project Name: Roxana SVE O&M**
**Project # 21562850.05000**
Lab Vendor #

Please Check Appropriate Box:
☑ ENV. SERVICES ☐ MOTIVA RETAIL ☐ SHELL RETAIL
☐ MOTIVA SC&CH ☐ CONSULTANT ☐ LUBES
☐ SHELL PIPELINE ☐ OTHER

Print Bill To Contact Name: Robert Mooshogian
PO #:
INCIDENT # (ENV. SERVICES): 9 7 2 1 6 6 4 0
☐ CHECK IF NO INCIDENT # APPLIES
SAP #: 3 4 0 0 6 1
DATE: 22-Feb-13
PAGE: 1 of 1

SAMPLING COMPANY: URS CORPORATION
SITE ADDRESS: Street and City: 900 SOUTH CENTRAL AVE – ROXANA
State: IL
ADDRESS: 1001 HIGHLANDS PLAZA DRIVE WEST - SUITE 300; ST. LOUIS, MO 63110
EDF DELIVERABLE TO (Name, Company, Office Location): Elizabeth Kunkel, URS, St. Louis
PHONE NO: 314-743-4179
E-MAIL:
CONSULTANT PROJECT NAME#: Roxana SVE O&M
Laboratory Address: Air Toxics, LTD 180 Blue Ravine Road, Suite B, Folsom, CA 95630-4719
SAMPLER NAME(S) (Print): B Wiefer, M. Currier
TELEPHONE: 314-429-0100
FAX: 314-429-0452
ATTN To (Contact E-MAIL): dave.palmer@urs.com

TURNAROUND TIME (CALENDAR DAYS):
☑ STANDARD (14 DAY) ☐ 5 DAYS ☐ 3 DAYS ☐ 2 DAYS ☐ 24 HOURS ☐ RESULTS NEEDED ON WEEKEND

REQUESTED ANALYSIS

☐ EA - RWQCB REPORT FORMAT ☑ UST AGENCY:
DELIVERABLES: ☐ LEVEL 1 ☐ LEVEL 2 ☐ LEVEL 3 ☑ LEVEL 4 ☐ OTHER (SPECIFY)

☑ SHELL CONTRACT RATE APPLIES
☐ STATE REIMBURSEMENT RATE APPLIES
☐ EDD NOT NEEDED
☑ RECEIPT VERIFICATION REQUESTED

| LAB USE ONLY | Field Sample Identification | SAMPLING DATE | SAMPLING TIME | Canister Number | Canister Pressure/Vacuum Initial | Final | Receipt | Final (psi) | Modified TO-15 + Butane & Isopentane | Modified ASTM D-1945 + BTU | Modified TO-3 (Sh)-TPHg | | Sample PID (ppm) |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| 01A | EXH-SVE-02202013 | 2/20/13 | 1230 | 3008 | -28.5 | -9 | | | X | X | X | | |
| 02A | MainHeader-SVE-02202013 | 2/20/13 | 1250 | 9314 | -29 | -9 | | | X | X | X | | |
| 03A | PWIleader-SVE-02202013 | 2/20/13 | 1305 | 9350 | -29.5 | -9 | | | X | X | X | | |

Turn Around Time: ☑ Normal ☐ Rush
Specify
*Lab Use Only*
Pressurized by:
Date:
Pressurization Gas: $N_2$ He

ADDITIONAL NOTES:
- 14 day hold time
- Report results between MDL and RL
- Level IV ECVP

| | | | |
|---|---|---|---|
| Relinquished by: (Signature) | Received by: (Signature) FEDEX | Date: 2/22/13 | Time: 1700 |
| Relinquished by: (Signature) | Received by: (Signature) | Date: | Time: |
| Relinquished by: (Signature) | Received by: (Signature) | Date: | Time: |

Custody Seal Intact?
Y N None Temp

08/2006 Revision

1302458

eurofins

Air Toxics

3/7/2013
Ms. Elizabeth Kunkel
URS Corporation
1001 Highlands Plaza Dr. West
Suite 300
St. Louis MO 63110

Project Name: Roxana SVE O&M
Project #: 21562850.05000
Workorder #: 1302458B

Dear Ms. Elizabeth Kunkel

The following report includes the data for the above referenced project for sample(s) received on 2/25/2013 at Air Toxics Ltd.

The data and associated QC analyzed by Modified TO-3 are compliant with the project requirements or laboratory criteria with the exception of the deviations noted in the attached case narrative.

Thank you for choosing Air Toxics Ltd. for your air analysis needs. Air Toxics Ltd. is committed to providing accurate data of the highest quality. Please feel free to contact the Project Manager: Kelly Buettner at 916-985-1000 if you have any questions regarding the data in this report.

Regards,

Kelly Buettner

Project Manager

Reviewed
on
3/18/2013

eurofins | Air Toxics

# WORK ORDER #: 1302458B

Work Order Summary

| | | | |
|---|---|---|---|
| **CLIENT:** | Ms. Elizabeth Kunkel<br>URS Corporation<br>1001 Highlands Plaza Dr. West<br>Suite 300<br>St. Louis, MO 63110 | **BILL TO:** | Accounts Payable Austin<br>URS Corporation<br>P.O. BOX 203970<br>Austin, TX 78720-1088 |
| **PHONE:** | 314-743-4179 | **P.O. #** | |
| **FAX:** | | **PROJECT #** | 21562850.05000 Roxana SVE O&M |
| **DATE RECEIVED:** | 02/25/2013 | **CONTACT:** | Kelly Buettner |
| **DATE COMPLETED:** | 03/07/2013 | | |

| FRACTION # | NAME | TEST | RECEIPT VAC./PRES. | FINAL PRESSURE |
|---|---|---|---|---|
| 01A | EXH-SVE-02202013 | Modified TO-3 | 9.0 "Hg | 15 psi |
| 02A | MainHeader-SVE-02202013 | Modified TO-3 | 9.0 "Hg | 15 psi |
| 03A | PWHeader-SVE-02202013 | Modified TO-3 | 8.5 "Hg | 15 psi |
| 04A | Lab Blank | Modified TO-3 | NA | NA |
| 05A | LCS | Modified TO-3 | NA | NA |
| 05AA | LCSD | Modified TO-3 | NA | NA |

CERTIFIED BY: Heidi Hayes DATE: 03/07/13

Technical Director

Certification numbers: AZ Licensure AZ0775, CA NELAP - 12282CA, NY NELAP - 11291,
TX NELAP - T104704434-12-5, UT NELAP CA009332012-3, WA NELAP - C935
Name of Accrediting Agency: NELAP/ORELAP (Oregon Environmental Laboratory Accreditation Program)
Accreditation number: CA300005, Effective date: 10/18/2011, Expiration date: 10/17/2012.
Eurofins Air Toxics Ltd. certifies that the test results contained in this report meet all requirements of the NELAC standards

This report shall not be reproduced, except in full, without the written approval of Eurofins Air Toxics, Inc.

180 BLUE RAVINE ROAD, SUITE B FOLSOM, CA - 9563
(916) 985-1000 . (800) 985-5955 . FAX (916) 985-1020

**LABORATORY NARRATIVE**
**Modified TO-3**
**URS Corporation**
**Workorder# 1302458B**

Three 1 Liter Summa Canister samples were received on February 25, 2013. The laboratory performed analysis for volatile organic compounds in air via modified EPA Method TO-3 using gas chromatography with flame ionization detection. The TPH results are calculated using the response of Gasoline. A molecular weight of 100 is used to convert the TPH ppmv result to ug/L. The method involves concentrating up to 200 mL of sample. The concentrated aliquot is then dry purged to remove water vapor prior to entering the chromatographic system.

Method modifications taken to run these samples are summarized in the table below. Specific project requirements may over-ride the ATL modifications.

| *Requirement* | *TO-3* | *ATL Modifications* |
|---|---|---|
| Daily Calibration Standard Frequency | Prior to sample analysis and every 4 - 6 hrs | Prior to sample analysis and after the analytical batch </= 20 samples. |
| Initial Calibration Calculation | 4-point calibration using a linear regression model | 5-point calibration using average Response Factor |
| Initial Calibration Frequency | Weekly | When daily calibration standard recovery is outside 75 - 125 %, or upon significant changes to procedure or instrumentation |
| Moisture Control | Nafion system | Sorbent system |
| Minimum Detection Limit (MDL) | Calculated using the equation DL = A+3.3S, where A is intercept of calibration line and S is the standard deviation of at least 3 reps of low level standard | 40 CFR Pt. 136 App. B |
| Preparation of Standards | Levels achieved through dilution of gas mixture | Levels achieved through loading various volumes of the gas mixture |

**Recciving Notes**

There were no receiving discrepancies.

**Analytical Notes**

As per project specific client request the laboratory has reported estimated values for target compound hits that are below the Reporting Limit but greater than the Method Detection Limit. Concentrations that are below the level at which the canister was certified may be false positives.

The recovery of surrogate Fluorobenzene in sample MainHeader-SVE-02202013 was outside control limits due to high level hydrocarbon matrix interference. Data is reported as qualified.

**Definition of Data Qualifying Flags**

Seven qualifiers may have been used on the data analysis sheets and indicate as follows:
B - Compound present in laboratory blank greater than reporting limit.
J - Estimated value.
E - Exceeds instrument calibration range.
S - Saturated peak.
Q - Exceeds quality control limits.
U - Compound analyzed for but not detected above the detection limit.
M - Reported value may be biased due to apparent matrix interferences.

File extensions may have been used on the data analysis sheets and indicates as follows:
a-File was requantified
b-File was quantified by a second column and detector
r1-File was requantified for the purpose of reissue

eurofins | Air Toxics

# Summary of Detected Compounds
# MODIFIED EPA METHOD TO-3 GC/FID

**Client Sample ID: EXH-SVE-02202013**

**Lab ID#: 1302458B-01A**

| Compound | Rpt. Limit (ppmv) | Rpt. Limit (ug/L) | Amount (ppmv) | Amount (ug/L) |
|---|---|---|---|---|
| TPH (C2-C10) ref. to Gasoline MW=100 | 0.29 | 1.2 | 89 | 360 |

**Client Sample ID: MainHeader-SVE-02202013**

**Lab ID#: 1302458B-02A**

| Compound | Rpt. Limit (ppmv) | Rpt. Limit (ug/L) | Amount (ppmv) | Amount (ug/L) |
|---|---|---|---|---|
| TPH (C2-C10) ref. to Gasoline MW=100 | 14 | 59 | 13000 | 54000 |

**Client Sample ID: PWHeader-SVE-02202013**

**Lab ID#: 1302458B-03A**

| Compound | Rpt. Limit (ppmv) | Rpt. Limit (ug/L) | Amount (ppmv) | Amount (ug/L) |
|---|---|---|---|---|
| TPH (C2-C10) ref. to Gasoline MW=100 | 28 | 120 | 3600 | 15000 |

eurofins | Air Toxics

**Client Sample ID: EXH-SVE-02202013**

**Lab ID#: 1302458B-01A**

**MODIFIED EPA METHOD TO-3 GC/FID**

| | | | |
|---|---|---|---|
| File Name: | d022710 | Date of Collection: | 2/20/13 12:30:00 PM |
| Dil. Factor: | 11.6 | Date of Analysis: | 2/27/13 04:51 PM |

| Compound | Rpt. Limit (ppmv) | Rpt. Limit (ug/L) | Amount (ppmv) | Amount (ug/L) |
|---|---|---|---|---|
| TPH (C2-C10) ref. to Gasoline MW=100 | 0.29 | 1.2 | 89 | 360 |

**Container Type: 1 Liter Summa Canister**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| Fluorobenzene (FID) | 129 | 75-150 |

eurofins | Air Toxics

**Client Sample ID: MainHeader-SVE-02202013**

**Lab ID#: 1302458B-02A**

**MODIFIED EPA METHOD TO-3 GC/FID**

| | | | |
|---|---|---|---|
| **File Name:** | **d022711** | **Date of Collection: 2/20/13 12:50:00 PM** | |
| **Dil. Factor:** | **578** | **Date of Analysis: 2/27/13 05:28 PM** | |

| Compound | Rpt. Limit (ppmv) | Rpt. Limit (ug/L) | Amount (ppmv) | Amount (ug/L) |
|---|---|---|---|---|
| TPH (C2-C10) ref. to Gasoline MW=100 | 14 | 59 | 13000 | 54000 |

Q = Exceeds Quality Control limits, possibly due to matrix effects.

**Container Type: 1 Liter Summa Canister**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| Fluorobenzene (FID) | 214 Q | 75-150 |

eurofins | Air Toxics

**Client Sample ID: PWHeader-SVE-02202013**

**Lab ID#: 1302458B-03A**

**MODIFIED EPA METHOD TO-3 GC/FID**

| | | | |
|---|---|---|---|
| File Name: | d022712 | Date of Collection: | 2/20/13 1:05:00 PM |
| Dil. Factor: | 1130 | Date of Analysis: | 2/27/13 06:09 PM |

| Compound | Rpt. Limit (ppmv) | Rpt. Limit (ug/L) | Amount (ppmv) | Amount (ug/L) |
|---|---|---|---|---|
| TPH (C2-C10) ref. to Gasoline MW=100 | 28 | 120 | 3600 | 15000 |

**Container Type: 1 Liter Summa Canister**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| Fluorobenzene (FID) | 112 | 75-150 |

eurofins | Air Toxics

**Client Sample ID: Lab Blank**

**Lab ID#: 1302458B-04A**

**MODIFIED EPA METHOD TO-3 GC/FID**

| | | | |
|---|---|---|---|
| **File Name:** | **d022704a** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 2/27/13 10:19 AM** | |

| Compound | Rpt. Limit (ppmv) | Rpt. Limit (ug/L) | Amount (ppmv) | Amount (ug/L) |
|---|---|---|---|---|
| TPH (C2-C10) ref. to Gasoline MW=100 | 0.025 | 0.10 | 0.012 J | 0.049 J |

J = Estimated value.

**Container Type: NA - Not Applicable**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| Fluorobenzene (FID) | 95 | 75-150 |

eurofins | Air Toxics

**Client Sample ID: LCS**

**Lab ID#: 1302458B-05A**

**MODIFIED EPA METHOD TO-3 GC/FID**

| | | | |
|---|---|---|---|
| **File Name:** | **d022702** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 2/27/13 08:42 AM** | |

| **Compound** | **%Recovery** |
|---|---|
| TPH (C2-C10) ref. to Gasoline MW=100 | 94 |

**Container Type: NA - Not Applicable**

| **Surrogates** | **%Recovery** | **Method Limits** |
|---|---|---|
| Fluorobenzene (FID) | 96 | 75-150 |

eurofins | Air Toxics

**Client Sample ID: LCSD**

**Lab ID#: 1302458B-05AA**

**MODIFIED EPA METHOD TO-3 GC/FID**

| | | | |
|---|---|---|---|
| **File Name:** | **d022715** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 2/27/13 08:29 PM** | |

| **Compound** | **%Recovery** |
|---|---|
| TPH (C2-C10) ref. to Gasoline MW=100 | 92 |

**Container Type: NA - Not Applicable**

| **Surrogates** | **%Recovery** | **Method Limits** |
|---|---|---|
| Fluorobenzene (FID) | 112 | 75-150 |

# Shell Oil Products Chain Of Custody Record

URS

Air Toxics LTD.
Project Name: Roxana SVE O&M
Project # 21562850.05000
Lab Vendor #

Please Check Appropriate Box:
☑ ENV. SERVICES ☐ MOTIVA RETAIL ☐ SHELL RETAIL
☐ MOTIVA SD&CH ☐ CONSULTANT ☐ LUBES
☐ SHELL PIPELINE ☐ OTHER

Print Bill To Contact Name: Robert Mcoshogan
PO #:
INCIDENT # (ENV SERVICES): 9 7 2 1 6 6 4 0
☐ CHECK IF NO INCIDENT # APPLIES
SAP #: 3 4 0 0 6 1
DATE: 22-Feb-13
PAGE: 1 of 1

SAMPLING COMPANY: URS CORPORATION
LAB CODE:
SITE ADDRESS: Street and City: 900 SOUTH CENTRAL AVE – ROXANA
State: IL
GLOBAL ID NO.:
ADDRESS: 1001 HIGHLANDS PLAZA DRIVE WEST - SUITE 300; ST. LOUIS, MO 63110
EDF DELIVERABLE TO (Name, Company, Office Location): Elizabeth Kunkel, URS, St. Louis
PHONE NO.: 314-743-4179
E-MAIL:
CONSULTANT PROJECT NAME#: Roxana SVE O&M
LAB COURIER: Air Toxics, LTD 180 Blue Ravine Road, Suite B, Folsom, CA 95630-4719
SAMPLER NAME(S) (PRINT): S. Wisher, M. Currier
TELEPHONE: 314-429-0100
FAX: 314-429-0462
EDF To Contact E-MAIL: dave.palmer@urs.com

TURNAROUND TIME (CALENDAR DAYS):
☑ STANDARD (14 DAY) ☐ 5 DAYS ☐ 3 DAYS ☐ 2 DAYS ☐ 24 HOURS ☐ RESULTS NEEDED ON WEEKEND

☐ 1A - RWQCB REPORT FORMAT ☑ UST AGENCY:

DELIVERABLES ☐ LEVEL 1 ☐ LEVEL 2 ☐ LEVEL 3 ☑ LEVEL 4 ☐ OTHER (SPECIFY)

☑ SHELL CONTRACT RATE APPLIES
☐ STATE REIMBURSEMENT RATE APPLIES
☐ EDD NOT NEEDED
☑ RECEIPT VERIFICATION REQUESTED

REQUESTED ANALYSIS

| LAB USE ONLY | Field Sample Identification | SAMPLING DATE | SAMPLING TIME | Canister Number | Canister Pressure/Vacuum Initial | Final | Receipt | Final (psi) | Modified TO-15 + Butane & Isopentane | Modified ASTM D-1945 + BTU | Modified TO-3 (Sh)-TPHg | | Sample PID (ppm) |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| 01 | EXH-SVE-02202013 | 2/20/13 | 1230 | 3008 | -28.5 | -9 | | | X | X | X | | |
| 02 | MainHeader-SVE-02202013 | 2/20/13 | 1250 | 9314 | -29 | -9 | | | X | X | X | | |
| 03 | PWHeader-SVE-02202013 | 2/20/13 | 1305 | 9350 | -29.5 | -9 | | | X | X | X | | |

Turn Around Time: ☑ Normal ☐ Rush Specify
Lab Use Only: Pressurized by: Date: Pressurization Gas: $N_2$ He

ADDITIONAL NOTES:
- 14 day hold time
- Report results between MDL and RL
- Level IV ECVP

2/22/13

| | | | |
|---|---|---|---|
| Relinquished by: (Signature) | Received by: (Signature) FEDEX | Date: 2/22/13 | Time: 1700 |
| Relinquished by: (Signature) | Received by: (Signature) AR 2/25/13 0930 | Date: | Time: |
| Relinquished by: (Signature) | Received by: (Signature) | Date: | Time: |

Custody Seal Intact?
Y N None Temp

06/2005 Revision

1302458

eurofins | Air Toxics

3/14/2013
Ms. Elizabeth Kunkel
URS Corporation
1001 Highlands Plaza Dr. West
Suite 300
St. Louis MO 63110

Project Name: Roxana SVE O&M
Project #: 21562850.05000
Workorder #: 1302458C

Dear Ms. Elizabeth Kunkel

The following report includes the data for the above referenced project for sample(s) received on 2/25/2013 at Air Toxics Ltd.

The data and associated QC analyzed by Modified ASTM D-1945 are compliant with the project requirements or laboratory criteria with the exception of the deviations noted in the attached case narrative.

Thank you for choosing Air Toxics Ltd. for your air analysis needs. Air Toxics Ltd. is committed to providing accurate data of the highest quality. Please feel free to contact the Project Manager: Kelly Buettner at 916-985-1000 if you have any questions regarding the data in this report.

Regards,

Kelly Buettner

Project Manager

Reviewed
on
3/18/2013

eurofins | Air Toxics

# WORK ORDER #: 1302458C

Work Order Summary

| | | | |
|---|---|---|---|
| **CLIENT:** | Ms. Elizabeth Kunkel<br>URS Corporation<br>1001 Highlands Plaza Dr. West<br>Suite 300<br>St. Louis, MO 63110 | **BILL TO:** | Accounts Payable Austin<br>URS Corporation<br>P.O. BOX 203970<br>Austin, TX 78720-1088 |
| **PHONE:** | 314-743-4179 | **P.O. #** | |
| **FAX:** | | **PROJECT #** | 21562850.05000 Roxana SVE O&M |
| **DATE RECEIVED:** | 02/25/2013 | **CONTACT:** | Kelly Buettner |
| **DATE COMPLETED:** | 03/08/2013 | | |

| FRACTION # | NAME | TEST | RECEIPT VAC./PRES. | FINAL PRESSURE |
|---|---|---|---|---|
| 01A | EXH-SVE-02202013 | Modified ASTM D-1945 | 9.0 "Hg | 15 psi |
| 02A | MainHeader-SVE-02202013 | Modified ASTM D-1945 | 9.0 "Hg | 15 psi |
| 03A | PWHeader-SVE-02202013 | Modified ASTM D-1945 | 8.5 "Hg | 15 psi |
| 04A | Lab Blank | Modified ASTM D-1945 | NA | NA |
| 04B | Lab Blank | Modified ASTM D-1945 | NA | NA |
| 05A | LCS | Modified ASTM D-1945 | NA | NA |
| 05AA | LCSD | Modified ASTM D-1945 | NA | NA |
| 05B | LCS | Modified ASTM D-1945 | NA | NA |
| 05BB | LCSD | Modified ASTM D-1945 | NA | NA |

CERTIFIED BY: Heidi Rogers DATE: 03/14/13

Technical Director

Certification numbers: AZ Licensure AZ0775, CA NELAP - 12282CA, NY NELAP - 11291,
TX NELAP - T104704434-12-4, UT NELAP CA009332012-3, WA NELAP - C935
Name of Accrediting Agency: NELAP/ORELAP (Oregon Environmental Laboratory Accreditation Program)
Accreditation number: CA300005, Effective date: 10/18/2012, Expiration date: 10/17/2013.
Eurofins Air Toxies Ltd. certifies that the test results contained in this report meet all requirements of the NELAC standards

This report shall not be reproduced, except in full, without the written approval of Eurofins Air Toxics, Inc.

180 BLUE RAVINE ROAD, SUITE B FOLSOM, CA - 9563
(916) 985-1000 . (800) 985-5955 . FAX (916) 985-1020

**LABORATORY NARRATIVE**
**Modified ASTM D-1945**
**URS Corporation**
**Workorder# 1302458C**

Three 1 Liter Summa Canister samples were received on February 25, 2013. The laboratory performed analysis via modified ASTM Method D-1945 for Methane and fixed gases in natural gas using GC/FID or GC/TCD. The method involves direct injection of 1.0 mL of sample.

On the analytical column employed for this analysis, Oxygen coelutes with Argon. The corresponding peak is quantitated as Oxygen.

Method modifications taken to run these samples are summarized in the table below. Specific project requirements may over-ride the ATL modifications.

| *Requirement* | *ASTM D-1945* | *ATL Modifications* |
|---|---|---|
| Normalization | Sum of original values should not differ from 100.0% by more than 1.0%. | Sum of original values may range between 85-115%. Normalization of data not performed. |
| Sample analysis | Equilibrate samples to 20-50° F. above source temperature at field sampling | No heating of samples is performed. |
| Sample calculation | Response factor is calculated using peak height for C5 and lighter compounds. | Peak areas are used for all target analytes to quantitate concentrations. |
| Reference Standard | Concentration should not be < half of nor differ by more than 2 X the concentration of the sample. Run 2 consecutive checks; must agree within 1%. | A minimum 3-point linear calibration is performed. The acceptance criterion is %RSD </= 15%. All target analytes must be within the linear range of ealibration (with the exception of O2, N2, and C6+ Hydrocarbons). |
| Sample Injection Volume | 0.50 mL to achieve Methane linearity. | 1.0 mL. |

**Receiving Notes**

There were no receiving discrepancies.

**Analytical Notes**

Since Nitrogen is used to pressurize samples, the Nitrogen values are calculated by adding all the sample components and subtracting from 100%.

As per project specific client request the laboratory has reported estimated values for target compound hits that are below the Reporting Limit but greater than the Method Detection Limit. Concentrations that are below the level at which the canister was certified may be false positives.

The reporting limit for Carbon Monoxide was raised from 0.01% to 0.05%.

**Definition of Data Qualifying Flags**

Six qualifiers may have been used on the data analysis sheets and indicate as follows:
J - Estimated value.
E - Exceeds instrument calibration range.
S - Saturated peak.
Q - Exceeds quality control limits.
U - Compound analyzed for but not detected above the detection limit.
M - Reported value may be biased due to apparent matrix interferences.

File extensions may have been used on the data analysis sheets and indicates as follows:
a-File was requantified
b-File was quantified by a second column and detector
r1-File was requantified for the purpose of reissue

eurofins | Air Toxics

# Summary of Detected Compounds
# NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1945

**Client Sample ID: EXH-SVE-02202013**

**Lab ID#: 1302458C-01A**

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.58 | 21 |
| Nitrogen | 0.58 | 78 |
| Methane | 0.00058 | 0.021 |
| Carbon Dioxide | 0.058 | 0.71 |
| Isobutane | 0.0058 | 0.000095 J |
| Butane | 0.0058 | 0.00082 J |
| Isopentane | 0.0058 | 0.0011 J |
| Pentane | 0.0058 | 0.00043 J |
| C6+ | 0.058 | 0.0026 J |

**Client Sample ID: MainHeader-SVE-02202013**

**Lab ID#: 1302458C-02A**

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.29 | 11 |
| Nitrogen | 0.29 | 78 |
| Methane | 0.00029 | 2.8 |
| Carbon Dioxide | 0.029 | 6.6 |
| Ethane | 0.0029 | 0.00076 J |
| Propane | 0.0029 | 0.0012 J |
| Isobutane | 0.0029 | 0.018 |
| Butane | 0.0029 | 0.16 |
| Neopentane | 0.0029 | 0.00081 J |
| Isopentane | 0.0029 | 0.20 |
| Pentane | 0.0029 | 0.077 |
| C6+ | 0.029 | 0.59 |

**Client Sample ID: PWHeader-SVE-02202013**

**Lab ID#: 1302458C-03A**

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.28 | 12 |
| Nitrogen | 0.28 | 78 |

eurofins | Air Toxics

# Summary of Detected Compounds
# NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1945

**Client Sample ID: PWHeader-SVE-02202013**

**Lab ID#: 1302458C-03A**

| | | |
|---|---|---|
| Methane | 0.00028 | 3.9 |
| Carbon Dioxide | 0.028 | 6.0 |
| Ethane | 0.0028 | 0.00023 J |
| Propane | 0.0028 | 0.00011 J |
| Isobutane | 0.0028 | 0.0042 |
| Butane | 0.0028 | 0.038 |
| Neopentane | 0.0028 | 0.00029 J |
| Isopentane | 0.0028 | 0.084 |
| Pentane | 0.0028 | 0.035 |
| C6+ | 0.028 | 0.15 |

eurofins | Air Toxics

**Client Sample ID: EXH-SVE-02202013**

**Lab ID#: 1302458C-01A**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1945**

| | | | |
|---|---|---|---|
| **File Name:** | **9030611** | **Date of Collection:** | **2/20/13 12:30:00 PM** |
| **Dil. Factor:** | **5.84** | **Date of Analysis:** | **3/6/13 02:06 PM** |

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.58 | 21 |
| Nitrogen | 0.58 | 78 |
| Carbon Monoxide | 0.29 | Not Detected |
| Methane | 0.00058 | 0.021 |
| Carbon Dioxide | 0.058 | 0.71 |
| Ethane | 0.0058 | Not Detected |
| Ethene | 0.0058 | Not Detected |
| Acetylene | 0.0058 | Not Detected |
| Propane | 0.0058 | Not Detected |
| Isobutane | 0.0058 | 0.000095 J |
| Butane | 0.0058 | 0.00082 J |
| Neopentane | 0.0058 | Not Detected |
| Isopentane | 0.0058 | 0.0011 J |
| Pentane | 0.0058 | 0.00043 J |
| C6+ | 0.058 | 0.0026 J |
| Hydrogen | 0.058 | Not Detected |

J = Estimated value.

Total BTU/Cu.F. = 0.43

Total Sp. Gravity = 1.0

**Container Type: 1 Liter Summa Canister**

eurofins | Air Toxics

**Client Sample ID: MainHeader-SVE-02202013**

**Lab ID#: 1302458C-02A**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1945**

| | | | |
|---|---|---|---|
| **File Name:** | **9030614** | **Date of Collection:** | **2/20/13 12:50:00 PM** |
| **Dil. Factor:** | **2.89** | **Date of Analysis:** | **3/6/13 03:36 PM** |

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.29 | 11 |
| Nitrogen | 0.29 | 78 |
| Carbon Monoxide | 0.14 | Not Detected |
| Methane | 0.00029 | 2.8 |
| Carbon Dioxide | 0.029 | 6.6 |
| Ethane | 0.0029 | 0.00076 J |
| Ethene | 0.0029 | Not Detected |
| Acetylene | 0.0029 | Not Detected |
| Propane | 0.0029 | 0.0012 J |
| Isobutane | 0.0029 | 0.018 |
| Butane | 0.0029 | 0.16 |
| Neopentane | 0.0029 | 0.00081 J |
| Isopentane | 0.0029 | 0.20 |
| Pentane | 0.0029 | 0.077 |
| C6+ | 0.029 | 0.59 |
| Hydrogen | 0.029 | Not Detected |

J = Estimated value.

Total BTU/Cu.F. = 73

Total Sp. Gravity = 1.0

**Container Type: 1 Liter Summa Canister**

eurofins | Air Toxics

**Client Sample ID: PWHeader-SVE-02202013**

**Lab ID#: 1302458C-03A**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1945**

| | | | |
|---|---|---|---|
| **File Name:** | **9030613** | **Date of Collection:** | **2/20/13 1:05:00 PM** |
| **Dil. Factor:** | **2.82** | **Date of Analysis:** | **3/6/13 02:58 PM** |

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.28 | 12 |
| Nitrogen | 0.28 | 78 |
| Carbon Monoxide | 0.14 | Not Detected |
| Methane | 0.00028 | 3.9 |
| Carbon Dioxide | 0.028 | 6.0 |
| Ethane | 0.0028 | 0.00023 J |
| Ethene | 0.0028 | Not Detected |
| Acetylene | 0.0028 | Not Detected |
| Propane | 0.0028 | 0.00011 J |
| Isobutane | 0.0028 | 0.0042 |
| Butane | 0.0028 | 0.038 |
| Neopentane | 0.0028 | 0.00029 J |
| Isopentane | 0.0028 | 0.084 |
| Pentane | 0.0028 | 0.035 |
| C6+ | 0.028 | 0.15 |
| Hydrogen | 0.028 | Not Detected |

J = Estimated value.

Total BTU/Cu.F. = 53

Total Sp. Gravity = 1.0

**Container Type: 1 Liter Summa Canister**

eurofins | Air Toxics

**Client Sample ID: Lab Blank**

**Lab ID#: 1302458C-04A**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1945**

| | | | |
|---|---|---|---|
| **File Name:** | **9030609a** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 3/6/13 12:52 PM** | |

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.10 | Not Detected |
| Nitrogen | 0.10 | 0.076 J |
| Carbon Monoxide | 0.050 | Not Detected |
| Methane | 0.00010 | Not Detected |
| Carbon Dioxide | 0.010 | Not Detected |
| Ethane | 0.0010 | Not Detected |
| Ethene | 0.0010 | Not Detected |
| Acetylene | 0.0010 | Not Detected |
| Propane | 0.0010 | Not Detected |
| Isobutane | 0.0010 | Not Detected |
| Butane | 0.0010 | Not Detected |
| Neopentane | 0.0010 | Not Detected |
| Isopentane | 0.0010 | Not Detected |
| Pentane | 0.0010 | Not Detected |
| C6+ | 0.010 | Not Detected |

J = Estimated value.

**Container Type: NA - Not Applicable**

eurofins | Air Toxics

**Client Sample ID: Lab Blank**

**Lab ID#: 1302458C-04B**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1945**

| | | | |
|---|---|---|---|
| **File Name:** | **9030608ba** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 3/6/13 12:30 PM** | |

| **Compound** | **Rpt. Limit (%)** | **Amount (%)** |
|---|---|---|
| Hydrogen | 0.010 | Not Detected |

**Container Type: NA - Not Applicable**

eurofins | Air Toxics

**Client Sample ID: LCS**

**Lab ID#: 1302458C-05A**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1945**

| | | | |
|---|---|---|---|
| **File Name:** | **9030606** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 3/6/13 11:37 AM** | |

| Compound | %Recovery |
|---|---|
| Oxygen | 100 |
| Nitrogen | 100 |
| Carbon Monoxide | 101 |
| Methane | 97 |
| Carbon Dioxide | 101 |
| Ethane | 99 |
| Ethene | 96 |
| Acetylene | 98 |
| Propane | 101 |
| Isobutane | 102 |
| Butane | 100 |
| Neopentane | 101 |
| Isopentane | 100 |
| Pentane | 100 |
| C6+ | 100 |

**Container Type: NA - Not Applicable**

eurofins | Air Toxics

**Client Sample ID: LCSD**

**Lab ID#: 1302458C-05AA**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1945**

| | | | |
|---|---|---|---|
| **File Name:** | **9030625** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 3/6/13 09:21 PM** | |

| Compound | %Recovery |
|---|---|
| Oxygen | 100 |
| Nitrogen | 99 |
| Carbon Monoxide | 99 |
| Methane | 97 |
| Carbon Dioxide | 100 |
| Ethane | 99 |
| Ethene | 96 |
| Acetylene | 98 |
| Propane | 101 |
| Isobutane | 102 |
| Butane | 101 |
| Neopentane | 101 |
| Isopentane | 100 |
| Pentane | 100 |
| C6+ | 101 |

**Container Type: NA - Not Applicable**

eurofins | Air Toxics

**Client Sample ID: LCS**

**Lab ID#: 1302458C-05B**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1945**

| | | | |
|---|---|---|---|
| **File Name:** | **9030626b** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 3/6/13 09:43 PM** | |

| Compound | %Recovery |
|---|---|
| Hydrogen | 96 |

**Container Type: NA - Not Applicable**

eurofins | Air Toxics

**Client Sample ID: LCSD**

**Lab ID#: 1302458C-05BB**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1945**

| | | | |
|---|---|---|---|
| File Name: | 9030627b | Date of Collection: NA | |
| Dil. Factor: | 1.00 | Date of Analysis: 3/6/13 10:06 PM | |

| Compound | %Recovery |
|---|---|
| Hydrogen | 96 |

**Container Type: NA - Not Applicable**

# Shell Oil Products Chain Of Custody Record

URS

Air Toxics LTD.
**Project Name: Roxana SVE O&M**
**Project # 21562850.05000**
Lab Vendor #

Please Check Appropriate Box:
☑ ENV. SERVICES ☐ MOTIVA RETAIL ☐ SHELL RETAIL
☐ MOTIVA SD&CM ☐ CONSULTANT ☐ LUBES
☐ SHELL PIPELINE ☐ OTHER

Print Bill To Contact Name: Robert Mooshegian

INCIDENT # (ENV SERVICES): 9 7 2 1 5 6 4 0 ☐ CHECK IF NO INCIDENT # APPLIES

DATE: 22-Feb-13

PAGE: 1 of 1

PO #:

SAP #: 3 4 0 0 6 1

SAMPLING COMPANY: URS CORPORATION

LAB CODE:

SITE ADDRESS: Street and City: 900 SOUTH CENTRAL AVE – ROXANA

State: IL

GLOBAL ID NO.:

ADDRESS: 1001 HIGHLANDS PLAZA DRIVE WEST - SUITE 300; ST. LOUIS, MO 63110

EDF DELIVERABLE TO (Name, Company, Office Location): Elizabeth Kunkel, URS, St. Louis

PHONE NO: 314-743-4179

E-MAIL:

CONSULTANT PROJECT NAME#: Roxana SVE O&M

Lab Mgr Address: Air Toxics, LTD 180 Blue Ravine Road, Suite B, Folsom, CA 95630-4719

SAMPLER NAME(S) (Print): S. Wiefer, M. Currier

TELEPHONE: 314-429-0100

FAX: 314-429-0462

Bill To Contact E-Mail: dave.palmer@urs.com

TURNAROUND TIME (CALENDAR DAYS)
☑ STANDARD (14 DAY) ☐ 5 DAYS ☐ 3 DAYS ☐ 2 DAYS ☐ 24 HOURS ☐ RESULTS NEEDED ON WEEKEND

REQUESTED ANALYSIS

☐ 1A - RWQCB REPORT FORMAT ☑ UST AGENCY:

DELIVERABLES ☐ LEVEL 1 ☐ LEVEL 2 ☐ LEVEL 3 ☑ LEVEL 4 ☐ OTHER (SPECIFY)

☑ SHELL CONTRACT RATE APPLIES
☐ STATE REIMBURSEMENT RATE APPLIES
☐ EDD NOT NEEDED
☑ RECEIPT VERIFICATION REQUESTED

| LAB USE ONLY | Field Sample Identification | SAMPLING DATE | SAMPLING TIME | Canister Number | Canister Pressure/Vacuum Initial | Canister Pressure/Vacuum Final | Canister Pressure/Vacuum Receipt | Canister Pressure/Vacuum Final (psi) | Modified TO-15 + Butane & Isopentane | Modified ASTM D-1945 + BTU | Modified TO-3 (Sh)-TPHg | Sample PID (ppm) |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| 01A | EXH-SVE-02202013 | 2/20/13 | 1230 | 3008 | -28.5 | -9 | | | X | X | X | |
| 02A | MainHeader-SVE-02202013 | 2/20/13 | 1250 | 9314 | -29 | -9 | | | X | X | X | |
| 03A | PWHeader-SVE-02202013 | 2/20/13 | 1305 | 9350 | -29.5 | -9 | | | X | X | X | |

Turn Around Time: ☑ Normal ☐ Rush Specify

Lab Use Only
Pressurized by:
Date:
Pressurization Gas: $N_2$ He

ADDITIONAL NOTES:
- 14 day hold time
- Report results between MDL and RL
- Level IV ECVP

Relinquished by: (Signature) — Received by: (Signature): FEDEX — Date: 2/22/13 — Time: 1700

Relinquished by: (Signature) — Received by: (Signature): AR 2/25/13 0930 — Date: — Time:

Relinquished by: (Signature) — Received by: (Signature) — Date: — Time:

Custody Seal Intact?
Y N None Temp: NA

05/2008 Revision

1372458

# SVE System O&M 2013 Data Review

**Laboratory SDG: 1303139A,B,C**

**Data Reviewer: Elizabeth Kunkel**

**Peer Reviewer: Steve Gragert**

**Date Reviewed: 3/25/2013**

**Guidance: USEPA National Functional Guidelines for Superfund Organic Methods Data Review 2008**

| Sample Identification | Sample Identification |
|---|---|
| EXH-SVE-03012013 | Main Header-SVE-03012013 |
| PWHeader-SVE-03012013 | |

## 1.0 Data Package Completeness

*Were all items delivered as specified in the QAPP and COC as appropriate?*

Yes

## 2.0 Laboratory Case Narrative \ Cooler Receipt Form

*Were problems noted in the laboratory case narrative or cooler receipt form?*

Yes, the laboratory case narrative indicated samples were diluted due to high levels of target analytes. Recovery of the surrogate fluorobenzene was outside evaluation criteria for TPH samples EXH-SVE-03012013 and Main Header-SVE-03012013 due to high levels of hydrocarbon matrix interference. ASTM D-1945 samples EXH-SVE-03012013, Main Header-SVE-03012013, and PWHeader-SVE-03012013 were analyzed 5 days outside the project requested holding time (14 days), but within the method required holding time (30 days). Although not indicated in the laboratory case narrative, analytes were detected in the method blank. LCS recoveries for 3-chloropropene, 4-methyl-2-pentanone, and alpha-chlorotoluene were outside evaluation criteria. These issues are addressed further in the appropriate sections below.

The cooler receipt form did not indicate any problems.

## 3.0 Holding Times

*Were samples extracted/analyzed within applicable limits?*

Yes, however ASTM D-1945 samples EXH-SVE-03012013, Main Header-SVE-03012013, and PWHeader-SVE-03012013 were analyzed 5 days outside the project requested holding time (14 days), but within the method required holding time (30 days). No qualification of data was required.

## 4.0 Blank Contamination

*Were any analytes detected in the Blanks?*

Yes

| Blank ID | Parameter | Analyte | Concentration/Amount |
|---|---|---|---|
| 1303139A-04A | TO-15 | Bromomethane | 0.28 ppbv / 1.1 µg/m$^3$ |

| Blank ID | Parameter | Analyte | Concentration/Amount |
|---|---|---|---|
| 1303139A-04A | TO-15 | Carbon disulfide | 0.50 ppbv / 1.5 µg/m$^3$ |
| 1303139A-04A | TO-15 | Methylene chloride | 0.14 ppbv / 0.49 µg/m$^3$ |
| 1303139A-04A | TO-15 | Toluene | 0.036 ppbv / 0.14 µg/m$^3$ |
| 1303139A-04A | TO-15 | Chlorobenzene | 0.071 ppbv / 0.33 µg/m$^3$ |
| 1303139A-04A | TO-15 | Propylbenzene | 0.077 ppbv / 0.38 µg/m$^3$ |
| 1303139A-04A | TO-15 | 4-Ethyltoluene | 0.087 ppbv / 0.43 µg/m$^3$ |
| 1303139A-04A | TO-15 | 1,3,5-Trimethylbenzene | 0.14 ppbv / 0.69 µg/m$^3$ |
| 1303139A-04A | TO-15 | 1,2,4-Trimethylbenzene | 0.13 ppbv / 0.64 µg/m$^3$ |
| 1303139A-04A | TO-15 | 1,3-Dichlorobenzene | 0.24 ppbv / 1.4 µg/m$^3$ |
| 1303139A-04A | TO-15 | 1,4-Dichlorobenzene | 0.26 ppbv / 1.5 µg/m$^3$ |
| 1303139A-04A | TO-15 | alpha-Chlorotoluene | 0.15 ppbv / 0.77 µg/m$^3$ |
| 1303139A-04A | TO-15 | 1,2-Dichlorobenzene | 0.24 ppbv / 1.4 µg/m$^3$ |
| 1303139A-04A | TO-15 | 1,2,4-Trichlorobenzene | 1.0 ppbv / 7.4 µg/m$^3$ |
| 1303139A-04A | TO-15 | Hexachlorobutadiene | 0.57 ppbv / 6.1 µg/m$^3$ |
| 1303139B-04A | ASTM D-1945 | Methane | 0.000030% |
| 1303139B-04A | ASTM D-1945 | Oxygen | 0.016% |
| 1303139B-04A | ASTM D-1945 | Nitrogen | 0.098% |
| 1303139C-04A | TO-3 | TPH (C2-C10) ref. to gasoline | 0.010 ppmv/0.043 µg/L |

Analytical data that were reported non-detect or at concentrations greater than five times (5X) the associated blank concentration did not require qualification. No qualification of data was required.

## 5.0 Laboratory Control Sample

*Were LCS recoveries within evaluation criteria?*

No

| LCS/ LCSD ID | Parameter | Analyte | LCS/LCSD Recovery | RPD | LCS/LCSD /RPD Criteria |
|---|---|---|---|---|---|
| 1303139A-06A/AA | TO-15 | 3-Chloropropene | **139**/116 | 18 | 70-130/25 |
| 1303139A-06A/AA | TO-15 | 4-Methyl-2-pentanone | **136**/129 | 5 | 70-130/25 |
| 1303139A-06A/AA | TO-15 | alpha-Chlorotoluene | **132**/123 | 7 | 70-130/25 |

Analytical data reported as non-detect and associated with LCS recoveries above evaluation criteria, indicating a possible high bias, did not require qualification. No qualification of data was required.

## 6.0 Surrogate Recoveries

*Were surrogate recoveries within evaluation criteria?*

No

| Sample ID | Parameter | Surrogate | Recovery (%) | Criteria (%) |
|---|---|---|---|---|
| EXH-SVE-03012013 | TO-3 | Fluorobenzene | **165** | 75-150 |
| Main Header-SVE-03012013 | TO-3 | Fluorobenzene | **226** | 75-150 |

Analytical data that required qualification based on surrogate data are included in the table below.

| Sample ID | Parameter | Analyte | Qualification |
|---|---|---|---|
| EXH-SVE-03012013 | TO-3 | TPH (C2-C10) ref. to gasoline | **J** |
| Main Header-SVE-03012013 | TO-3 | TPH (C2-C10) ref. to gasoline | **J** |

## 7.0 Matrix Spike and Matrix Spike Duplicate Recoveries

*Were MS/MSD samples analyzed as part of this SDG?*

MS/MSD samples are not applicable for vapor samples due to the inability to spike the samples in summa canisters.

## 8.0 Laboratory Duplicate Results

*Were laboratory duplicate samples collected as part of this SDG?*

No

## 9.0 Field Duplicate Results

*Were field duplicate samples collected as part of this SDG?*

No

## 10.0 Sample Dilutions

*For samples that were diluted and nondetect, were undiluted results also reported?*

Not applicable; analytes were detected in samples that were diluted.

## 11.0 Additional Qualifications

*Were additional qualifications applied?*

No

eurofins | Air Toxics

3/20/2013
Ms. Elizabeth Kunkel
URS Corporation
1001 Highlands Plaza Dr. West
Suite 300
St. Louis MO 63110

Project Name: Roxana SVE O&M
Project #: 21562850.05000
Workorder #: 1303139A

Dear Ms. Elizabeth Kunkel

The following report includes the data for the above referenced project for sample(s) received on 3/7/2013 at Air Toxics Ltd.

The data and associated QC analyzed by Modified TO-15 are compliant with the project requirements or laboratory criteria with the exception of the deviations noted in the attached case narrative.

Thank you for choosing Air Toxics Ltd. for your air analysis needs. Air Toxics Ltd. is committed to providing accurate data of the highest quality. Please feel free to contact the Project Manager: Kelly Buettner at 916-985-1000 if you have any questions regarding the data in this report.

Regards,

Kelly Buettner

Project Manager

Reviewed
on
3/22/2013

eurofins | Air Toxics

# WORK ORDER #: 1303139A

Work Order Summary

| | | | |
|---|---|---|---|
| **CLIENT:** | Ms. Elizabeth Kunkel<br>URS Corporation<br>1001 Highlands Plaza Dr. West<br>Suite 300<br>St. Louis, MO 63110 | **BILL TO:** | Accounts Payable Austin<br>URS Corporation<br>P.O. BOX 203970<br>Austin, TX 78720-1088 |
| **PHONE:** | 314-743-4179 | **P.O. #** | |
| **FAX:** | | **PROJECT #** | 21562850.05000 Roxana SVE O&M |
| **DATE RECEIVED:** | 03/07/2013 | **CONTACT:** | Kelly Buettner |
| **DATE COMPLETED:** | 03/15/2013 | | |

| FRACTION # | NAME | TEST | RECEIPT VAC./PRES. | FINAL PRESSURE |
|---|---|---|---|---|
| 01A | EXH-SVE-03012013 | Modified TO-15 | 8.8 "Hg | 14.8 psi |
| 02A | MainHeader-SVE-03012013 | Modified TO-15 | 9.2 "Hg | 14.8 psi |
| 03A | PWHeader-SVE-03012013 | Modified TO-15 | 9 "Hg | 14.8 psi |
| 04A | Lab Blank | Modified TO-15 | NA | NA |
| 05A | CCV | Modified TO-15 | NA | NA |
| 06A | LCS | Modified TO-15 | NA | NA |
| 06AA | LCSD | Modified TO-15 | NA | NA |

CERTIFIED BY: Heidi Hayes DATE: 03/20/13

Technical Director

Certfication numbers: AZ Licensure AZ0775, CA NELAP - 12282CA, NY NELAP - 11291,
TX NELAP - T104704434-12-5, UT NELAP CA009332012-3, WA NELAP - C935
Name of Accrediting Agency: NELAP/ORELAP (Oregon Environmental Laboratory Accreditation Program)
Accreditation number: CA300005, Effective date: 10/18/2011, Expiration date: 10/17/2012.
Eurofins Air Toxics Ltd. certifies that the test results contained in this report meet all requirements of the NELAC standards

This report shall not be reproduced, except in full, without the written approval of Eurofins Air Toxics, Inc.

180 BLUE RAVINE ROAD, SUITE B FOLSOM, CA - 9563
(916) 985-1000 . (800) 985-5955 . FAX (916) 985-1020

**LABORATORY NARRATIVE**
**EPA Method TO-15**
**URS Corporation**
**Workorder# 1303139A**

Three 1 Liter Summa Canister samples were received on March 07, 2013. The laboratory performed analysis via EPA Method TO-15 using GC/MS in the full scan mode.

This workorder was independently validated prior to submittal using 'USEPA National Functional Guidelines' as generally applied to the analysis of volatile organic compounds in air. A rules-based, logic driven, independent validation engine was employed to assess completeness, evaluate pass/fail of relevant project quality control requirements and verification of all quantified amounts.

**Receiving Notes**

There were no receiving discrepancies.

**Analytical Notes**

As per client project requirements, the laboratory has reported estimated values for target compound hits that are below the Reporting Limit but greater than the Method Detection Limit. Concentrations that are below the level at which the canister was certified (0.2 ppbv for compounds reported at 0.5 ppbv and 0.8 ppbv for compounds reported at 2.0 ppbv) may be false positives.

Dilution was performed on all of the samples due to the presence of high level target species.

All Quality Control Limit exceedances and affected sample results are noted by flags. Each flag is defined at the bottom of this Case Narrative and on each Sample Result Summary page.

**Definition of Data Qualifying Flags**

Eight qualifiers may have been used on the data analysis sheets and indicates as follows:

B - Compound present in laboratory blank greater than reporting limit (background subtraction not performed).

J - Estimated value.

E - Exceeds instrument calibration range.

S - Saturated peak.

Q - Exceeds quality control limits.

U - Compound analyzed for but not detected above the reporting limit.

UJ- Non-detected compound associated with low bias in the CCV and/or LCS.

N - The identification is based on presumptive evidence.

File extensions may have been used on the data analysis sheets and indicates as follows:

a-File was requantified

b-File was quantified by a second column and detector

r1-File was requantified for the purpose of reissue

# Summary of Detected Compounds
# EPA METHOD TO-15 GC/MS FULL SCAN

**Client Sample ID: EXH-SVE-03012013**

**Lab ID#: 1303139A-01A**

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Acetone | 360 | 64 J | 840 | 150 J |
| Carbon Disulfide | 140 | 44 J | 440 | 140 J |
| Methylene Chloride | 360 | 7.8 J | 1200 | 27 J |
| Hexane | 36 | 3400 | 120 | 12000 |
| Cyclohexane | 36 | 760 | 120 | 2600 |
| 2,2,4-Trimethylpentane | 36 | 2600 | 160 | 12000 |
| Benzene | 36 | 2100 | 110 | 6600 |
| Heptane | 36 | 670 | 140 | 2800 |
| Toluene | 36 | 180 | 130 | 670 |
| Tetrachloroethene | 36 | 8.7 J | 240 | 59 J |
| Ethyl Benzene | 36 | 58 | 150 | 250 |
| m,p-Xylene | 36 | 120 | 150 | 530 |
| o-Xylene | 36 | 25 J | 150 | 110 J |
| Propylbenzene | 36 | 3.9 J | 170 | 19 J |
| Butane | 140 | 10000 | 340 | 24000 |
| Isopentane | 140 | 12000 | 420 | 36000 |

**Client Sample ID: MainHeader-SVE-03012013**

**Lab ID#: 1303139A-02A**

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Acetone | 58000 | 8100 J | 140000 | 19000 J |
| Carbon Disulfide | 23000 | 7900 J | 72000 | 25000 J |
| Methylene Chloride | 58000 | 1500 J | 200000 | 5200 J |
| Hexane | 5800 | 650000 | 20000 | 2300000 |
| Cyclohexane | 5800 | 130000 | 20000 | 440000 |
| 2,2,4-Trimethylpentane | 5800 | 460000 | 27000 | 2200000 |
| Benzene | 5800 | 30000 | 18000 | 97000 |
| Heptane | 5800 | 98000 | 24000 | 400000 |
| Toluene | 5800 | 26000 | 22000 | 97000 |
| Ethyl Benzene | 5800 | 8100 | 25000 | 35000 |
| m,p-Xylene | 5800 | 16000 | 25000 | 71000 |
| o-Xylene | 5800 | 3400 J | 25000 | 15000 J |

# Summary of Detected Compounds
# EPA METHOD TO-15 GC/MS FULL SCAN

**Client Sample ID: MainHeader-SVE-03012013**

**Lab ID#: 1303139A-02A**

| | | | | |
|---|---|---|---|---|
| Butane | 23000 | 1800000 | 55000 | 4400000 |
| Isopentane | 23000 | 2000000 | 68000 | 5800000 |

**Client Sample ID: PWHeader-SVE-03012013**

**Lab ID#: 1303139A-03A**

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Acetone | 29000 | 5900 J | 68000 | 14000 J |
| Carbon Disulfide | 11000 | 6900 J | 36000 | 22000 J |
| Methylene Chloride | 29000 | 940 J | 99000 | 3300 J |
| Hexane | 2900 | 75000 | 10000 | 260000 |
| Cyclohexane | 2900 | 18000 | 9800 | 60000 |
| 2,2,4-Trimethylpentane | 2900 | 55000 | 13000 | 260000 |
| Benzene | 2900 | 510000 | 9100 | 1600000 |
| Heptane | 2900 | 9800 | 12000 | 40000 |
| Toluene | 2900 | 880 J | 11000 | 3300 J |
| Ethyl Benzene | 2900 | 690 J | 12000 | 3000 J |
| m,p-Xylene | 2900 | 690 J | 12000 | 3000 J |
| 1,2,4-Trichlorobenzene | 11000 | 750 J | 85000 | 5600 J |
| Butane | 11000 | 380000 | 27000 | 890000 |
| Isopentane | 11000 | 840000 | 34000 | 2500000 |

eurofins | Air Toxics

**Client Sample ID: EXH-SVE-03012013**

**Lab ID#: 1303139A-01A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p031413** | **Date of Collection:** | **3/1/13 10:40:00 AM** |
| **Dil. Factor:** | **71.0** | **Date of Analysis:** | **3/14/13 05:22 PM** |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 36 | Not Detected | 180 | Not Detected |
| Freon 114 | 36 | Not Detected | 250 | Not Detected |
| Chloromethane | 360 | Not Detected | 730 | Not Detected |
| Vinyl Chloride | 36 | Not Detected | 91 | Not Detected |
| 1,3-Butadiene | 36 | Not Detected | 78 | Not Detected |
| Bromomethane | 360 | Not Detected | 1400 | Not Detected |
| Chloroethane | 140 | Not Detected | 370 | Not Detected |
| Freon 11 | 36 | Not Detected | 200 | Not Detected |
| Ethanol | 140 | Not Detected | 270 | Not Detected |
| Freon 113 | 36 | Not Detected | 270 | Not Detected |
| 1,1-Dichloroethene | 36 | Not Detected | 140 | Not Detected |
| Acetone | 360 | 64 J | 840 | 150 J |
| 2-Propanol | 140 | Not Detected | 350 | Not Detected |
| Carbon Disulfide | 140 | 44 J | 440 | 140 J |
| 3-Chloropropene | 140 | Not Detected | 440 | Not Detected |
| Methylene Chloride | 360 | 7.8 J | 1200 | 27 J |
| Methyl tert-butyl ether | 36 | Not Detected | 130 | Not Detected |
| trans-1,2-Dichloroethene | 36 | Not Detected | 140 | Not Detected |
| Hexane | 36 | 3400 | 120 | 12000 |
| 1,1-Dichloroethane | 36 | Not Detected | 140 | Not Detected |
| 2-Butanone (Methyl Ethyl Ketone) | 140 | Not Detected | 420 | Not Detected |
| cis-1,2-Dichloroethene | 36 | Not Detected | 140 | Not Detected |
| Tetrahydrofuran | 36 | Not Detected | 100 | Not Detected |
| Chloroform | 36 | Not Detected | 170 | Not Detected |
| 1,1,1-Trichloroethane | 36 | Not Detected | 190 | Not Detected |
| Cyclohexane | 36 | 760 | 120 | 2600 |
| Carbon Tetrachloride | 36 | Not Detected | 220 | Not Detected |
| 2,2,4-Trimethylpentane | 36 | 2600 | 160 | 12000 |
| Benzene | 36 | 2100 | 110 | 6600 |
| 1,2-Dichloroethane | 36 | Not Detected | 140 | Not Detected |
| Heptane | 36 | 670 | 140 | 2800 |
| Trichloroethene | 36 | Not Detected | 190 | Not Detected |
| 1,2-Dichloropropane | 36 | Not Detected | 160 | Not Detected |
| 1,4-Dioxane | 140 | Not Detected | 510 | Not Detected |
| Bromodichloromethane | 36 | Not Detected | 240 | Not Detected |
| cis-1,3-Dichloropropene | 36 | Not Detected | 160 | Not Detected |
| 4-Methyl-2-pentanone | 36 | Not Detected | 140 | Not Detected |
| Toluene | 36 | 180 | 130 | 670 |
| trans-1,3-Dichloropropene | 36 | Not Detected | 160 | Not Detected |
| 1,1,2-Trichloroethane | 36 | Not Detected | 190 | Not Detected |
| Tetrachloroethene | 36 | 8.7 J | 240 | 59 J |
| 2-Hexanone | 140 | Not Detected | 580 | Not Detected |

eurofins | Air Toxics

**Client Sample ID: EXH-SVE-03012013**

**Lab ID#: 1303139A-01A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p031413** | **Date of Collection: 3/1/13 10:40:00 AM** | |
| **Dil. Factor:** | **71.0** | **Date of Analysis: 3/14/13 05:22 PM** | |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Dibromochloromethane | 36 | Not Detected | 300 | Not Detected |
| 1,2-Dibromoethane (EDB) | 36 | Not Detected | 270 | Not Detected |
| Chlorobenzene | 36 | Not Detected | 160 | Not Detected |
| Ethyl Benzene | 36 | 58 | 150 | 250 |
| m,p-Xylene | 36 | 120 | 150 | 530 |
| o-Xylene | 36 | 25 J | 150 | 110 J |
| Styrene | 36 | Not Detected | 150 | Not Detected |
| Bromoform | 36 | Not Detected | 370 | Not Detected |
| Cumene | 36 | Not Detected | 170 | Not Detected |
| 1,1,2,2-Tetrachloroethane | 36 | Not Detected | 240 | Not Detected |
| Propylbenzene | 36 | 3.9 J | 170 | 19 J |
| 4-Ethyltoluene | 36 | Not Detected | 170 | Not Detected |
| 1,3,5-Trimethylbenzene | 36 | Not Detected | 170 | Not Detected |
| 1,2,4-Trimethylbenzene | 36 | Not Detected | 170 | Not Detected |
| 1,3-Dichlorobenzene | 36 | Not Detected | 210 | Not Detected |
| 1,4-Dichlorobenzene | 36 | Not Detected | 210 | Not Detected |
| alpha-Chlorotoluene | 36 | Not Detected | 180 | Not Detected |
| 1,2-Dichlorobenzene | 36 | Not Detected | 210 | Not Detected |
| 1,2,4-Trichlorobenzene | 140 | Not Detected | 1000 | Not Detected |
| Hexachlorobutadiene | 140 | Not Detected | 1500 | Not Detected |
| Butane | 140 | 10000 | 340 | 24000 |
| Isopentane | 140 | 12000 | 420 | 36000 |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| Toluene-d8 | 98 | 70-130 |
| 1,2-Dichloroethane-d4 | 92 | 70-130 |
| 4-Bromofluorobenzene | 105 | 70-130 |

eurofins | Air Toxics

**Client Sample ID: MainHeader-SVE-03012013**

**Lab ID#: 1303139A-02A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p031414** | **Date of Collection: 3/1/13 10:50:00 AM** | |
| **Dil. Factor:** | **11600** | **Date of Analysis: 3/14/13 06:17 PM** | |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 5800 | Not Detected | 29000 | Not Detected |
| Freon 114 | 5800 | Not Detected | 40000 | Not Detected |
| Chloromethane | 58000 | Not Detected | 120000 | Not Detected |
| Vinyl Chloride | 5800 | Not Detected | 15000 | Not Detected |
| 1,3-Butadiene | 5800 | Not Detected | 13000 | Not Detected |
| Bromomethane | 58000 | Not Detected | 220000 | Not Detected |
| Chloroethane | 23000 | Not Detected | 61000 | Not Detected |
| Freon 11 | 5800 | Not Detected | 32000 | Not Detected |
| Ethanol | 23000 | Not Detected | 44000 | Not Detected |
| Freon 113 | 5800 | Not Detected | 44000 | Not Detected |
| 1,1-Dichloroethene | 5800 | Not Detected | 23000 | Not Detected |
| Acetone | 58000 | 8100 J | 140000 | 19000 J |
| 2-Propanol | 23000 | Not Detected | 57000 | Not Detected |
| Carbon Disulfide | 23000 | 7900 J | 72000 | 25000 J |
| 3-Chloropropene | 23000 | Not Detected | 73000 | Not Detected |
| Methylene Chloride | 58000 | 1500 J | 200000 | 5200 J |
| Methyl tert-butyl ether | 5800 | Not Detected | 21000 | Not Detected |
| trans-1,2-Dichloroethene | 5800 | Not Detected | 23000 | Not Detected |
| Hexane | 5800 | 650000 | 20000 | 2300000 |
| 1,1-Dichloroethane | 5800 | Not Detected | 23000 | Not Detected |
| 2-Butanone (Methyl Ethyl Ketone) | 23000 | Not Detected | 68000 | Not Detected |
| cis-1,2-Dichloroethene | 5800 | Not Detected | 23000 | Not Detected |
| Tetrahydrofuran | 5800 | Not Detected | 17000 | Not Detected |
| Chloroform | 5800 | Not Detected | 28000 | Not Detected |
| 1,1,1-Trichloroethane | 5800 | Not Detected | 32000 | Not Detected |
| Cyclohexane | 5800 | 130000 | 20000 | 440000 |
| Carbon Tetrachloride | 5800 | Not Detected | 36000 | Not Detected |
| 2,2,4-Trimethylpentane | 5800 | 460000 | 27000 | 2200000 |
| Benzene | 5800 | 30000 | 18000 | 97000 |
| 1,2-Dichloroethane | 5800 | Not Detected | 23000 | Not Detected |
| Heptane | 5800 | 98000 | 24000 | 400000 |
| Trichloroethene | 5800 | Not Detected | 31000 | Not Detected |
| 1,2-Dichloropropane | 5800 | Not Detected | 27000 | Not Detected |
| 1,4-Dioxane | 23000 | Not Detected | 84000 | Not Detected |
| Bromodichloromethane | 5800 | Not Detected | 39000 | Not Detected |
| cis-1,3-Dichloropropene | 5800 | Not Detected | 26000 | Not Detected |
| 4-Methyl-2-pentanone | 5800 | Not Detected | 24000 | Not Detected |
| Toluene | 5800 | 26000 | 22000 | 97000 |
| trans-1,3-Dichloropropene | 5800 | Not Detected | 26000 | Not Detected |
| 1,1,2-Trichloroethane | 5800 | Not Detected | 32000 | Not Detected |
| Tetrachloroethene | 5800 | Not Detected | 39000 | Not Detected |
| 2-Hexanone | 23000 | Not Detected | 95000 | Not Detected |

**Client Sample ID: MainHeader-SVE-03012013**

**Lab ID#: 1303139A-02A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p031414** | **Date of Collection:** | **3/1/13 10:50:00 AM** |
| **Dil. Factor:** | **11600** | **Date of Analysis:** | **3/14/13 06:17 PM** |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Dibromochloromethane | 5800 | Not Detected | 49000 | Not Detected |
| 1,2-Dibromoethane (EDB) | 5800 | Not Detected | 44000 | Not Detected |
| Chlorobenzene | 5800 | Not Detected | 27000 | Not Detected |
| Ethyl Benzene | 5800 | 8100 | 25000 | 35000 |
| m,p-Xylene | 5800 | 16000 | 25000 | 71000 |
| o-Xylene | 5800 | 3400 J | 25000 | 15000 J |
| Styrene | 5800 | Not Detected | 25000 | Not Detected |
| Bromoform | 5800 | Not Detected | 60000 | Not Detected |
| Cumene | 5800 | Not Detected | 28000 | Not Detected |
| 1,1,2,2-Tetrachloroethane | 5800 | Not Detected | 40000 | Not Detected |
| Propylbenzene | 5800 | Not Detected | 28000 | Not Detected |
| 4-Ethyltoluene | 5800 | Not Detected | 28000 | Not Detected |
| 1,3,5-Trimethylbenzene | 5800 | Not Detected | 28000 | Not Detected |
| 1,2,4-Trimethylbenzene | 5800 | Not Detected | 28000 | Not Detected |
| 1,3-Dichlorobenzene | 5800 | Not Detected | 35000 | Not Detected |
| 1,4-Dichlorobenzene | 5800 | Not Detected | 35000 | Not Detected |
| alpha-Chlorotoluene | 5800 | Not Detected | 30000 | Not Detected |
| 1,2-Dichlorobenzene | 5800 | Not Detected | 35000 | Not Detected |
| 1,2,4-Trichlorobenzene | 23000 | Not Detected | 170000 | Not Detected |
| Hexachlorobutadiene | 23000 | Not Detected | 250000 | Not Detected |
| Butane | 23000 | 1800000 | 55000 | 4400000 |
| Isopentane | 23000 | 2000000 | 68000 | 5800000 |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| Toluene-d8 | 90 | 70-130 |
| 1,2-Dichloroethane-d4 | 100 | 70-130 |
| 4-Bromofluorobenzene | 102 | 70-130 |

eurofins | Air Toxics

**Client Sample ID: PWHeader-SVE-03012013**

**Lab ID#: 1303139A-03A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p031415** | **Date of Collection: 3/1/13 11:05:00 AM** | |
| **Dil. Factor:** | **5720** | **Date of Analysis: 3/14/13 06:57 PM** | |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 2900 | Not Detected | 14000 | Not Detected |
| Freon 114 | 2900 | Not Detected | 20000 | Not Detected |
| Chloromethane | 29000 | Not Detected | 59000 | Not Detected |
| Vinyl Chloride | 2900 | Not Detected | 7300 | Not Detected |
| 1,3-Butadiene | 2900 | Not Detected | 6300 | Not Detected |
| Bromomethane | 29000 | Not Detected | 110000 | Not Detected |
| Chloroethane | 11000 | Not Detected | 30000 | Not Detected |
| Freon 11 | 2900 | Not Detected | 16000 | Not Detected |
| Ethanol | 11000 | Not Detected | 22000 | Not Detected |
| Freon 113 | 2900 | Not Detected | 22000 | Not Detected |
| 1,1-Dichloroethene | 2900 | Not Detected | 11000 | Not Detected |
| Acetone | 29000 | 5900 J | 68000 | 14000 J |
| 2-Propanol | 11000 | Not Detected | 28000 | Not Detected |
| Carbon Disulfide | 11000 | 6900 J | 36000 | 22000 J |
| 3-Chloropropene | 11000 | Not Detected | 36000 | Not Detected |
| Methylene Chloride | 29000 | 940 J | 99000 | 3300 J |
| Methyl tert-butyl ether | 2900 | Not Detected | 10000 | Not Detected |
| trans-1,2-Dichloroethene | 2900 | Not Detected | 11000 | Not Detected |
| Hexane | 2900 | 75000 | 10000 | 260000 |
| 1,1-Dichloroethane | 2900 | Not Detected | 12000 | Not Detected |
| 2-Butanone (Methyl Ethyl Ketone) | 11000 | Not Detected | 34000 | Not Detected |
| cis-1,2-Dichloroethene | 2900 | Not Detected | 11000 | Not Detected |
| Tetrahydrofuran | 2900 | Not Detected | 8400 | Not Detected |
| Chloroform | 2900 | Not Detected | 14000 | Not Detected |
| 1,1,1-Trichloroethane | 2900 | Not Detected | 16000 | Not Detected |
| Cyclohexane | 2900 | 18000 | 9800 | 60000 |
| Carbon Tetrachloride | 2900 | Not Detected | 18000 | Not Detected |
| 2,2,4-Trimethylpentane | 2900 | 55000 | 13000 | 260000 |
| Benzene | 2900 | 510000 | 9100 | 1600000 |
| 1,2-Dichloroethane | 2900 | Not Detected | 12000 | Not Detected |
| Heptane | 2900 | 9800 | 12000 | 40000 |
| Trichloroethene | 2900 | Not Detected | 15000 | Not Detected |
| 1,2-Dichloropropane | 2900 | Not Detected | 13000 | Not Detected |
| 1,4-Dioxane | 11000 | Not Detected | 41000 | Not Detected |
| Bromodichloromethane | 2900 | Not Detected | 19000 | Not Detected |
| cis-1,3-Dichloropropene | 2900 | Not Detected | 13000 | Not Detected |
| 4-Methyl-2-pentanone | 2900 | Not Detected | 12000 | Not Detected |
| Toluene | 2900 | 880 J | 11000 | 3300 J |
| trans-1,3-Dichloropropene | 2900 | Not Detected | 13000 | Not Detected |
| 1,1,2-Trichloroethane | 2900 | Not Detected | 16000 | Not Detected |
| Tetrachloroethene | 2900 | Not Detected | 19000 | Not Detected |
| 2-Hexanone | 11000 | Not Detected | 47000 | Not Detected |

eurofins | Air Toxics

**Client Sample ID: PWHeader-SVE-03012013**

**Lab ID#: 1303139A-03A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p031415** | **Date of Collection: 3/1/13 11:05:00 AM** | |
| **Dil. Factor:** | **5720** | **Date of Analysis: 3/14/13 06:57 PM** | |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Dibromochloromethane | 2900 | Not Detected | 24000 | Not Detected |
| 1,2-Dibromoethane (EDB) | 2900 | Not Detected | 22000 | Not Detected |
| Chlorobenzene | 2900 | Not Detected | 13000 | Not Detected |
| Ethyl Benzene | 2900 | 690 J | 12000 | 3000 J |
| m,p-Xylene | 2900 | 690 J | 12000 | 3000 J |
| o-Xylene | 2900 | Not Detected | 12000 | Not Detected |
| Styrene | 2900 | Not Detected | 12000 | Not Detected |
| Bromoform | 2900 | Not Detected | 30000 | Not Detected |
| Cumene | 2900 | Not Detected | 14000 | Not Detected |
| 1,1,2,2-Tetrachloroethane | 2900 | Not Detected | 20000 | Not Detected |
| Propylbenzene | 2900 | Not Detected | 14000 | Not Detected |
| 4-Ethyltoluene | 2900 | Not Detected | 14000 | Not Detected |
| 1,3,5-Trimethylbenzene | 2900 | Not Detected | 14000 | Not Detected |
| 1,2,4-Trimethylbenzene | 2900 | Not Detected | 14000 | Not Detected |
| 1,3-Dichlorobenzene | 2900 | Not Detected | 17000 | Not Detected |
| 1,4-Dichlorobenzene | 2900 | Not Detected | 17000 | Not Detected |
| alpha-Chlorotoluene | 2900 | Not Detected | 15000 | Not Detected |
| 1,2-Dichlorobenzene | 2900 | Not Detected | 17000 | Not Detected |
| 1,2,4-Trichlorobenzene | 11000 | 750 J | 85000 | 5600 J |
| Hexachlorobutadiene | 11000 | Not Detected | 120000 | Not Detected |
| Butane | 11000 | 380000 | 27000 | 890000 |
| Isopentane | 11000 | 840000 | 34000 | 2500000 |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| Toluene-d8 | 96 | 70-130 |
| 1,2-Dichloroethane-d4 | 98 | 70-130 |
| 4-Bromofluorobenzene | 106 | 70-130 |

**Client Sample ID: Lab Blank**

**Lab ID#: 1303139A-04A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p031406a** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 3/14/13 12:12 PM** | |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 0.50 | Not Detected | 2.5 | Not Detected |
| Freon 114 | 0.50 | Not Detected | 3.5 | Not Detected |
| Chloromethane | 5.0 | Not Detected | 10 | Not Detected |
| Vinyl Chloride | 0.50 | Not Detected | 1.3 | Not Detected |
| 1,3-Butadiene | 0.50 | Not Detected | 1.1 | Not Detected |
| Bromomethane | 5.0 | 0.28 J | 19 | 1.1 J |
| Chloroethane | 2.0 | Not Detected | 5.3 | Not Detected |
| Freon 11 | 0.50 | Not Detected | 2.8 | Not Detected |
| Ethanol | 2.0 | Not Detected | 3.8 | Not Detected |
| Freon 113 | 0.50 | Not Detected | 3.8 | Not Detected |
| 1,1-Dichloroethene | 0.50 | Not Detected | 2.0 | Not Detected |
| Acetone | 5.0 | Not Detected | 12 | Not Detected |
| 2-Propanol | 2.0 | Not Detected | 4.9 | Not Detected |
| Carbon Disulfide | 2.0 | 0.50 J | 6.2 | 1.5 J |
| 3-Chloropropene | 2.0 | Not Detected | 6.3 | Not Detected |
| Methylene Chloride | 5.0 | 0.14 J | 17 | 0.49 J |
| Methyl tert-butyl ether | 0.50 | Not Detected | 1.8 | Not Detected |
| trans-1,2-Dichloroethene | 0.50 | Not Detected | 2.0 | Not Detected |
| Hexane | 0.50 | Not Detected | 1.8 | Not Detected |
| 1,1-Dichloroethane | 0.50 | Not Detected | 2.0 | Not Detected |
| 2-Butanone (Methyl Ethyl Ketone) | 2.0 | Not Detected | 5.9 | Not Detected |
| cis-1,2-Dichloroethene | 0.50 | Not Detected | 2.0 | Not Detected |
| Tetrahydrofuran | 0.50 | Not Detected | 1.5 | Not Detected |
| Chloroform | 0.50 | Not Detected | 2.4 | Not Detected |
| 1,1,1-Trichloroethane | 0.50 | Not Detected | 2.7 | Not Detected |
| Cyclohexane | 0.50 | Not Detected | 1.7 | Not Detected |
| Carbon Tetrachloride | 0.50 | Not Detected | 3.1 | Not Detected |
| 2,2,4-Trimethylpentane | 0.50 | Not Detected | 2.3 | Not Detected |
| Benzene | 0.50 | Not Detected | 1.6 | Not Detected |
| 1,2-Dichloroethane | 0.50 | Not Detected | 2.0 | Not Detected |
| Heptane | 0.50 | Not Detected | 2.0 | Not Detected |
| Trichloroethene | 0.50 | Not Detected | 2.7 | Not Detected |
| 1,2-Dichloropropane | 0.50 | Not Detected | 2.3 | Not Detected |
| 1,4-Dioxane | 2.0 | Not Detected | 7.2 | Not Detected |
| Bromodichloromethane | 0.50 | Not Detected | 3.4 | Not Detected |
| cis-1,3-Dichloropropene | 0.50 | Not Detected | 2.3 | Not Detected |
| 4-Methyl-2-pentanone | 0.50 | Not Detected | 2.0 | Not Detected |
| Toluene | 0.50 | 0.036 J | 1.9 | 0.14 J |
| trans-1,3-Dichloropropene | 0.50 | Not Detected | 2.3 | Not Detected |
| 1,1,2-Trichloroethane | 0.50 | Not Detected | 2.7 | Not Detected |
| Tetrachloroethene | 0.50 | Not Detected | 3.4 | Not Detected |
| 2-Hexanone | 2.0 | Not Detected | 8.2 | Not Detected |

eurofins | Air Toxics

**Client Sample ID: Lab Blank**

**Lab ID#: 1303139A-04A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p031406a** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 3/14/13 12:12 PM** | |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Dibromochloromethane | 0.50 | Not Detected | 4.2 | Not Detected |
| 1,2-Dibromoethane (EDB) | 0.50 | Not Detected | 3.8 | Not Detected |
| Chlorobenzene | 0.50 | 0.071 J | 2.3 | 0.33 J |
| Ethyl Benzene | 0.50 | Not Detected | 2.2 | Not Detected |
| m,p-Xylene | 0.50 | Not Detected | 2.2 | Not Detected |
| o-Xylene | 0.50 | Not Detected | 2.2 | Not Detected |
| Styrene | 0.50 | Not Detected | 2.1 | Not Detected |
| Bromoform | 0.50 | Not Detected | 5.2 | Not Detected |
| Cumene | 0.50 | Not Detected | 2.4 | Not Detected |
| 1,1,2,2-Tetrachloroethane | 0.50 | Not Detected | 3.4 | Not Detected |
| Propylbenzene | 0.50 | 0.077 J | 2.4 | 0.38 J |
| 4-Ethyltoluene | 0.50 | 0.087 J | 2.4 | 0.43 J |
| 1,3,5-Trimethylbenzene | 0.50 | 0.14 J | 2.4 | 0.69 J |
| 1,2,4-Trimethylbenzene | 0.50 | 0.13 J | 2.4 | 0.64 J |
| 1,3-Dichlorobenzene | 0.50 | 0.24 J | 3.0 | 1.4 J |
| 1,4-Dichlorobenzene | 0.50 | 0.26 J | 3.0 | 1.5 J |
| alpha-Chlorotoluene | 0.50 | 0.15 J | 2.6 | 0.77 J |
| 1,2-Dichlorobenzene | 0.50 | 0.24 J | 3.0 | 1.4 J |
| 1,2,4-Trichlorobenzene | 2.0 | 1.0 J | 15 | 7.4 J |
| Hexachlorobutadiene | 2.0 | 0.57 J | 21 | 6.1 J |
| Butane | 2.0 | Not Detected | 4.8 | Not Detected |
| Isopentane | 2.0 | Not Detected | 5.9 | Not Detected |

J = Estimated value.

**Container Type: NA - Not Applicable**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| Toluene-d8 | 105 | 70-130 |
| 1,2-Dichloroethane-d4 | 94 | 70-130 |
| 4-Bromofluorobenzene | 98 | 70-130 |

eurofins | Air Toxics

**Client Sample ID: CCV**

**Lab ID#: 1303139A-05A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p031402** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 3/14/13 09:04 AM** | |

| Compound | %Recovery |
|---|---|
| Freon 12 | 105 |
| Freon 114 | 108 |
| Chloromethane | 101 |
| Vinyl Chloride | 114 |
| 1,3-Butadiene | 111 |
| Bromomethane | 113 |
| Chloroethane | 105 |
| Freon 11 | 98 |
| Ethanol | 98 |
| Freon 113 | 101 |
| 1,1-Dichloroethene | 97 |
| Acetone | 97 |
| 2-Propanol | 89 |
| Carbon Disulfide | 93 |
| 3-Chloropropene | 96 |
| Methylene Chloride | 93 |
| Methyl tert-butyl ether | 98 |
| trans-1,2-Dichloroethene | 100 |
| Hexane | 106 |
| 1,1-Dichloroethane | 108 |
| 2-Butanone (Methyl Ethyl Ketone) | 98 |
| cis-1,2-Dichloroethene | 103 |
| Tetrahydrofuran | 94 |
| Chloroform | 96 |
| 1,1,1-Trichloroethane | 101 |
| Cyclohexane | 109 |
| Carbon Tetrachloride | 100 |
| 2,2,4-Trimethylpentane | 102 |
| Benzene | 89 |
| 1,2-Dichloroethane | 88 |
| Heptane | 98 |
| Trichloroethene | 79 |
| 1,2-Dichloropropane | 87 |
| 1,4-Dioxane | 94 |
| Bromodichloromethane | 88 |
| cis-1,3-Dichloropropene | 103 |
| 4-Methyl-2-pentanone | 107 |
| Toluene | 103 |
| trans-1,3-Dichloropropene | 121 |
| 1,1,2-Trichloroethane | 101 |
| Tetrachloroethene | 103 |
| 2-Hexanone | 96 |

eurofins | Air Toxics

**Client Sample ID: CCV**

**Lab ID#: 1303139A-05A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p031402** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 3/14/13 09:04 AM** | |

| Compound | %Recovery |
|---|---|
| Dibromochloromethane | 109 |
| 1,2-Dibromoethane (EDB) | 102 |
| Chlorobenzene | 96 |
| Ethyl Benzene | 108 |
| m,p-Xylene | 111 |
| o-Xylene | 112 |
| Styrene | 117 |
| Bromoform | 110 |
| Cumene | 115 |
| 1,1,2,2-Tetrachloroethane | 112 |
| Propylbenzene | 109 |
| 4-Ethyltoluene | 114 |
| 1,3,5-Trimethylbenzene | 117 |
| 1,2,4-Trimethylbenzene | 114 |
| 1,3-Dichlorobenzene | 119 |
| 1,4-Dichlorobenzene | 124 |
| alpha-Chlorotoluene | 129 |
| 1,2-Dichlorobenzene | 126 |
| 1,2,4-Trichlorobenzene | 109 |
| Hexachlorobutadiene | 110 |
| Butane | 109 |
| Isopentane | 103 |

**Container Type: NA - Not Applicable**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| Toluene-d8 | 106 | 70-130 |
| 1,2-Dichloroethane-d4 | 100 | 70-130 |
| 4-Bromofluorobenzene | 104 | 70-130 |

**Client Sample ID: LCS**

**Lab ID#: 1303139A-06A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p031404** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 3/14/13 10:21 AM** | |

| Compound | %Recovery |
|---|---|
| Freon 12 | 109 |
| Freon 114 | 115 |
| Chloromethane | 104 |
| Vinyl Chloride | 124 |
| 1,3-Butadiene | 116 |
| Bromomethane | 117 |
| Chloroethane | 118 |
| Freon 11 | 106 |
| Ethanol | 77 |
| Freon 113 | 105 |
| 1,1-Dichloroethene | 107 |
| Acetone | 100 |
| 2-Propanol | 100 |
| Carbon Disulfide | 121 |
| 3-Chloropropene | 139 Q |
| Methylene Chloride | 112 |
| Methyl tert-butyl ether | 111 |
| trans-1,2-Dichloroethene | 126 |
| Hexane | 104 |
| 1,1-Dichloroethane | 98 |
| 2-Butanone (Methyl Ethyl Ketone) | 104 |
| cis-1,2-Dichloroethene | 107 |
| Tetrahydrofuran | 105 |
| Chloroform | 102 |
| 1,1,1-Trichloroethane | 113 |
| Cyclohexane | 128 |
| Carbon Tetrachloride | 113 |
| 2,2,4-Trimethylpentane | 107 |
| Benzene | 105 |
| 1,2-Dichloroethane | 100 |
| Heptane | 113 |
| Trichloroethene | 104 |
| 1,2-Dichloropropane | 103 |
| 1,4-Dioxane | 112 |
| Bromodichloromethane | 101 |
| cis-1,3-Dichloropropene | 126 |
| 4-Methyl-2-pentanone | 136 Q |
| Toluene | 120 |
| trans-1,3-Dichloropropene | 124 |
| 1,1,2-Trichloroethane | 113 |
| Tetrachloroethene | 111 |
| 2-Hexanone | 107 |

**Client Sample ID: LCS**

**Lab ID#: 1303139A-06A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p031404** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 3/14/13 10:21 AM** | |

| Compound | %Recovery |
|---|---|
| Dibromochloromethane | 107 |
| 1,2-Dibromoethane (EDB) | 105 |
| Chlorobenzene | 100 |
| Ethyl Benzene | 111 |
| m,p-Xylene | 116 |
| o-Xylene | 118 |
| Styrene | 124 |
| Bromoform | 107 |
| Cumene | 119 |
| 1,1,2,2-Tetrachloroethane | 95 |
| Propylbenzene | 112 |
| 4-Ethyltoluene | 114 |
| 1,3,5-Trimethylbenzene | 123 |
| 1,2,4-Trimethylbenzene | 120 |
| 1,3-Dichlorobenzene | 126 |
| 1,4-Dichlorobenzene | 124 |
| alpha-Chlorotoluene | 132 Q |
| 1,2-Dichlorobenzene | 130 |
| 1,2,4-Trichlorobenzene | 116 |
| Hexachlorobutadiene | 111 |
| Butane | 110 |
| Isopentane | 114 |

Q = Exceeds Quality Control limits.

**Container Type: NA - Not Applicable**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| Toluene-d8 | 120 | 70-130 |
| 1,2-Dichloroethane-d4 | 97 | 70-130 |
| 4-Bromofluorobenzene | 102 | 70-130 |

**Client Sample ID: LCSD**

**Lab ID#: 1303139A-06AA**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p031405** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 3/14/13 11:19 AM** | |

| Compound | %Recovery |
|---|---|
| Freon 12 | 104 |
| Freon 114 | 108 |
| Chloromethane | 100 |
| Vinyl Chloride | 115 |
| 1,3-Butadiene | 108 |
| Bromomethane | 103 |
| Chloroethane | 98 |
| Freon 11 | 94 |
| Ethanol | 75 |
| Freon 113 | 105 |
| 1,1-Dichloroethene | 111 |
| Acetone | 103 |
| 2-Propanol | 94 |
| Carbon Disulfide | 114 |
| 3-Chloropropene | 116 |
| Methylene Chloride | 100 |
| Methyl tert-butyl ether | 99 |
| trans-1,2-Dichloroethene | 114 |
| Hexane | 98 |
| 1,1-Dichloroethane | 94 |
| 2-Butanone (Methyl Ethyl Ketone) | 99 |
| cis-1,2-Dichloroethene | 103 |
| Tetrahydrofuran | 95 |
| Chloroform | 94 |
| 1,1,1-Trichloroethane | 99 |
| Cyclohexane | 110 |
| Carbon Tetrachloride | 96 |
| 2,2,4-Trimethylpentane | 103 |
| Benzene | 106 |
| 1,2-Dichloroethane | 93 |
| Heptane | 108 |
| Trichloroethene | 99 |
| 1,2-Dichloropropane | 103 |
| 1,4-Dioxane | 127 |
| Bromodichloromethane | 110 |
| cis-1,3-Dichloropropene | 119 |
| 4-Methyl-2-pentanone | 129 |
| Toluene | 114 |
| trans-1,3-Dichloropropene | 121 |
| 1,1,2-Trichloroethane | 114 |
| Tetrachloroethene | 110 |
| 2-Hexanone | 113 |

**Client Sample ID: LCSD**

**Lab ID#: 1303139A-06AA**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p031405** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 3/14/13 11:19 AM** | |

| Compound | %Recovery |
|---|---|
| Dibromochloromethane | 103 |
| 1,2-Dibromoethane (EDB) | 101 |
| Chlorobenzene | 97 |
| Ethyl Benzene | 107 |
| m,p-Xylene | 112 |
| o-Xylene | 119 |
| Styrene | 120 |
| Bromoform | 103 |
| Cumene | 114 |
| 1,1,2,2-Tetrachloroethane | 92 |
| Propylbenzene | 107 |
| 4-Ethyltoluene | 111 |
| 1,3,5-Trimethylbenzene | 115 |
| 1,2,4-Trimethylbenzene | 113 |
| 1,3-Dichlorobenzene | 119 |
| 1,4-Dichlorobenzene | 117 |
| alpha-Chlorotoluene | 123 |
| 1,2-Dichlorobenzene | 115 |
| 1,2,4-Trichlorobenzene | 111 |
| Hexachlorobutadiene | 105 |
| Butane | 103 |
| Isopentane | 95 |

**Container Type: NA - Not Applicable**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| Toluene-d8 | 119 | 70-130 |
| 1,2-Dichloroethane-d4 | 94 | 70-130 |
| 4-Bromofluorobenzene | 101 | 70-130 |

1303139

# Shell Oil Products Chain Of Custody Record

URS

Air Toxics LTD.
**Project Name: Roxana SVE O&M**
**Project # 21562850.05000**
Lab Vendor #

Please Check Appropriate Box: ☑ ENV. SERVICES ☐ MOTIVA RETAIL ☐ SHELL RETAIL ☐ MOTIVA SD&CM ☐ CONSULTANT ☐ LUBES ☐ SHELL PIPELINE ☐ OTHER

Print Bill To Contact Name: Robert Moosheglan

INCIDENT # (ENV. SERVICES): 9 7 2 - 8 6 4 0 ☐ CHECK IF NO INCIDENT # APPLIES

PO #:

SAP #: 3 4 0 0 6 1

DATE: 5-Mar-13

PAGE: 1 of 1

SAMPLING COMPANY: URS CORPORATION

LOG CODE:

SITE ADDRESS: Street and City: 900 SOUTH CENTRAL AVE – ROXANA

State: IL

GLOBAL ID NO.:

ADDRESS: 1001 HIGHLANDS PLAZA DRIVE WEST - SUITE 300, ST. LOUIS, MO 63110

EDF DELIVERABLE TO (Name, Company, Office Location): Elizabeth Kunkel, URS, St. Louis

PHONE NO.: 314-743-4179

E-MAIL: elizabeth_kunkel@urs.com

CONSULTANT PROJECT NAME#: Roxana SVE O&M

Laboratory Address: Air Toxics, LTD 180 Blue Ravine Road, Suite B, Folsom, CA 95630-4719

SAMPLER NAME(S) (Print): S. Wipfler, M. Currier

TELEPHONE: 314-429-0100

FAX: 314-429-0452

Bill To Contact E-MAIL: dave.palmer@urs.com

TURNAROUND TIME (CALENDAR DAYS): ☑ STANDARD (14 DAY) ☐ 5 DAYS ☐ 3 DAYS ☐ 2 DAYS ☐ 24 HOURS ☐ RESULTS NEEDED ON WEEKEND

☐ LA - RWQCB REPORT FORMAT ☑ UST AGENCY:

DELIVERABLES ☐ LEVEL 1 ☐ LEVEL 2 ☐ LEVEL 3 ☑ LEVEL 4 ☐ OTHER (SPECIFY) _____

☑ SHELL CONTRACT RATE APPLIES
☐ STATE REIMBURSEMENT RATE APPLIES
☐ EDD NOT NEEDED
☑ RECEIPT VERIFICATION REQUESTED

REQUESTED ANALYSIS

| LAB USE ONLY | Field Sample Identification | SAMPLING DATE | SAMPLING TIME | Canister Number | Canister Pressure/Vacuum Initial | Final | Receipt | Final (psi) | Modified TO-15 + Butane & Isopentane | Modified ASTM D-1945 + BTU | Modified TO-3 (Sh)-TPHg | | Sample PID (ppm) |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| 01A | EXH-SVE-03012013 | 3/1/13 | 1040 | 37365 | -29 | -9 | | | X | X | X | | |
| 02A | MainHeader-SVE-03012013 | 3/1/13 | 1050 | 2106 | -29 | -9 | | | X | X | X | | |
| 03A | PWHeader-SVE-03012013 | 3/1/13 | 1105 | 37799 | -29 | -9 | | | X | X | X | | |

Turn Around Time: ☑ Normal ☐ Rush Specify

Lab Use Only
Pressurized by:
Date:
Pressurization Gas: $N_2$ He

ADDITIONAL NOTES:
- 14 day hold time
- Report results between MDL and RL
- Level IV ECVP

FedEx
Custody Seal Intact? (Y) N None Temp N/A

| | Relinquished by: (Signature) | Received by: (Signature) | Date | Time |
|---|---|---|---|---|
| | | FEDEX | 3/5/13 | 1700 |
| | Relinquished by: (Signature) | Received by: (Signature) Kristi Decker ATL | 03/07/13 | 0930 |
| | Relinquished by: (Signature) | Received by: (Signature) | Date | Time |

05/2/05 Revision

eurofins | Air Toxics

3/26/2013
Ms. Elizabeth Kunkel
URS Corporation
1001 Highlands Plaza Dr. West
Suite 300
St. Louis MO 63110

Project Name: Roxana SVE O&M
Project #: 21562850.05000
Workorder #: 1303139B

Dear Ms. Elizabeth Kunkel

The following report includes the data for the above referenced project for sample(s) received on 3/7/2013 at Air Toxics Ltd.

The data and associated QC analyzed by Modified ASTM D-1945 are compliant with the project requirements or laboratory criteria with the exception of the deviations noted in the attached case narrative.

Thank you for choosing Air Toxics Ltd. for your air analysis needs. Air Toxics Ltd. is committed to providing accurate data of the highest quality. Please feel free to contact the Project Manager: Kelly Buettner at 916-985-1000 if you have any questions regarding the data in this report.

Regards,

Kelly Buettner

Project Manager

Reviewed
on
3/27/2013

eurofins | Air Toxics

# WORK ORDER #: 1303139B

Work Order Summary

| | | | |
|---|---|---|---|
| **CLIENT:** | Ms. Elizabeth Kunkel<br>URS Corporation<br>1001 Highlands Plaza Dr. West<br>Suite 300<br>St. Louis, MO 63110 | **BILL TO:** | Accounts Payable Austin<br>URS Corporation<br>P.O. BOX 203970<br>Austin, TX 78720-1088 |
| **PHONE:** | 314-743-4179 | **P.O. #** | |
| **FAX:** | | **PROJECT #** | 21562850.05000 Roxana SVE O&M |
| **DATE RECEIVED:** | 03/07/2013 | **CONTACT:** | Kelly Buettner |
| **DATE COMPLETED:** | 03/26/2013 | | |

| FRACTION # | NAME | TEST | RECEIPT VAC./PRES. | FINAL PRESSURE |
|---|---|---|---|---|
| 01A | EXH-SVE-03012013 | Modified ASTM D-1945 | 8.8 "Hg | 14.8 psi |
| 02A | MainHeader-SVE-03012013 | Modified ASTM D-1945 | 9.2 "Hg | 14.8 psi |
| 03A | PWHeader-SVE-03012013 | Modified ASTM D-1945 | 9 "Hg | 14.8 psi |
| 04A | Lab Blank | Modified ASTM D-1945 | NA | NA |
| 04B | Lab Blank | Modified ASTM D-1945 | NA | NA |
| 04C | Lab Blank | Modified ASTM D-1945 | NA | NA |
| 05A | LCS | Modified ASTM D-1945 | NA | NA |
| 05AA | LCSD | Modified ASTM D-1945 | NA | NA |
| 05B | LCS | Modified ASTM D-1945 | NA | NA |
| 05BB | LCSD | Modified ASTM D-1945 | NA | NA |
| 05C | LCS | Modified ASTM D-1945 | NA | NA |
| 05CC | LCSD | Modified ASTM D-1945 | NA | NA |

CERTIFIED BY: Heidi Jorgens DATE: 03/26/13

Technical Director

Certification numbers: AZ Licensure AZ0775, CA NELAP - 12282CA, NY NELAP - 11291, TX NELAP - T104704434-12-4, UT NELAP CA009332012-3, WA NELAP - C935
Name of Accrediting Agency: NELAP/ORELAP (Oregon Environmental Laboratory Accreditation Program)
Accreditation number: CA300005, Effective date: 10/18/2012, Expiration date: 10/17/2013.
Eurofins Air Toxics Ltd. certifies that the test results contained in this report meet all requirements of the NELAC standards

This report shall not be reproduced, except in full, without the written approval of Eurofins Air Toxics, Inc.

180 BLUE RAVINE ROAD, SUITE B FOLSOM, CA - 9563
(916) 985-1000 , (800) 985-5955 , FAX (916) 985-1020

**LABORATORY NARRATIVE**
**Modified ASTM D-1946**
**URS Corporation**
**Workorder# 1303139B**

Three 1 Liter Summa Canister samples were received on March 07, 2013. The laboratory performed analysis via Modified ASTM Method D-1946 for Methane and fixed gases in air using GC/FID or GC/TCD. The method involves direct injection of 1.0 mL of sample.

On the analytical column employed for this analysis, Oxygen coelutes with Argon. The corresponding peak is quantitated as Oxygen.

Since Nitrogen is used to pressurize samples, the reported Nitrogen values are calculated by adding all the sample components and subtracting from 100%.

Method modifications taken to run these samples are summarized in the table below. Specific project requirements may over-ride the ATL modifications.

| *Requirement* | *ASTM D-1946* | *ATL Modifications* |
|---|---|---|
| Calibration | A single point calibration is performed using a reference standard closely matching the composition of the unknown. | A 3-point calibration curve is performed. Quantitation is based on a daily calibration standard which may or may not resemble the composition of the associated samples. |
| Reference Standard | The composition of any reference standard must be known to within 0.01 mol % for any component. | The standards used by ATL are blended to a >/= 95% accuracy. |
| Sample Injection Volume | Components whose concentrations are in excess of 5 % should not be analyzed by using sample volumes greater than 0.5 mL. | The sample container is connected directly to a fixed volume sample loop of 1.0 mL on the GC. Linear range is defined by the calibration curve. Bags are loaded by vacuum. |
| Normalization | Normalize the mole percent values by multiplying each value by 100 and dividing by the sum of the original values. The sum of the original values should not differ from 100% by more than 1.0%. | Results are not normalized. The sum of the reported values can differ from 100% by as much as 15%, either due to analytical variability or an unusual sample matrix. |
| Precision | Precision requirements established at each concentration level. | Duplicates should agree within 25% RPD for detections > 5 X's the RL. |

**Receiving Notes**

There were no receiving discrepancies.

**Analytical Notes**

As per project specific client request the laboratory has reported estimated values for target compound hits that are below the Reporting Limit but greater than the Method Detection Limit. Concentrations that are below the level at which the canister was certified may be false positives.

Samples EXH-SVE-03012013, MainHeader-SVE-03012013 and PWHeader-SVE-03012013 were analyzed past the project specified 14-day hold time, but within the method required 30-day hold time.

The reported Samples for each daily batch may be derived from more than one analytical file.
The reporting limit for Nitrogen was raised from 0.10% to 0.50%.

The associated comprehensive validation package provided at a later date shows the time of analysis in GMT in the raw data files. Due to software limitations the time can not be adjusted however, the time on the final PDF and EDD reports is provided in PST.

**Definition of Data Qualifying Flags**

Seven qualifiers may have been used on the data analysis sheets and indicate as follows:
B - Compound present in laboratory blank greater than reporting limit.
J - Estimated value.
E - Exceeds instrument calibration range.
S - Saturated peak.
Q - Exceeds quality control limits.
U - Compound analyzed for but not detected above the detection limit.
M - Reported value may be biased due to apparent matrix interferences.
File extensions may have been used on the data analysis sheets and indicates as follows:
a-File was requantified
b-File was quantified by a second column and detector
r1-File was requantified for the purpose of reissue

eurofins | Air Toxics

# Summary of Detected Compounds
# NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1945

**Client Sample ID: EXH-SVE-03012013**

**Lab ID#: 1303139B-01A**

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.28 | 21 |
| Nitrogen | 1.4 | 78 |
| Methane | 0.00028 | 0.022 |
| Carbon Dioxide | 0.028 | 0.73 |
| Isobutane | 0.0028 | 0.000094 J |
| Butane | 0.0028 | 0.00085 J |
| Isopentane | 0.0028 | 0.0011 J |
| Pentane | 0.0028 | 0.00043 J |
| C6+ | 0.028 | 0.0028 J |

**Client Sample ID: MainHeader-SVE-03012013**

**Lab ID#: 1303139B-02A**

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.29 | 12 |
| Nitrogen | 1.4 | 77 |
| Methane | 0.00029 | 3.1 |
| Carbon Dioxide | 0.029 | 7.0 |
| Ethane | 0.0029 | 0.00084 J |
| Propane | 0.0029 | 0.0013 J |
| Isobutane | 0.0029 | 0.021 |
| Butane | 0.0029 | 0.19 |
| Neopentane | 0.0029 | 0.00081 J |
| Isopentane | 0.0029 | 0.22 |
| Pentane | 0.0029 | 0.084 |
| C6+ | 0.029 | 0.63 |

**Client Sample ID: PWHeader-SVE-03012013**

**Lab ID#: 1303139B-03A**

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.29 | 14 |
| Nitrogen | 1.4 | 75 |

eurofins | Air Toxics

# Summary of Detected Compounds
# NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1945

**Client Sample ID: PWHeader-SVE-03012013**

**Lab ID#: 1303139B-03A**

| | | |
|---|---|---|
| Methane | 0.00029 | 4.3 |
| Carbon Dioxide | 0.029 | 6.3 |
| Ethane | 0.0029 | 0.00027 J |
| Propane | 0.0029 | 0.00013 J |
| Isobutane | 0.0029 | 0.0045 |
| Butane | 0.0029 | 0.041 |
| Neopentane | 0.0029 | 0.00025 J |
| Isopentane | 0.0029 | 0.093 |
| Pentane | 0.0029 | 0.039 |
| C6+ | 0.029 | 0.18 |

eurofins | Air Toxics

**Client Sample ID: EXH-SVE-03012013**

**Lab ID#: 1303139B-01A**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1945**

| | | | |
|---|---|---|---|
| **File Name:** | **9031943** | **Date of Collection: 3/1/13 10:40:00 AM** | |
| **Dil. Factor:** | **2.84** | **Date of Analysis: 3/20/13 09:00 AM** | |

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.28 | 21 |
| Nitrogen | 1.4 | 78 |
| Carbon Monoxide | 0.028 | Not Detected |
| Methane | 0.00028 | 0.022 |
| Carbon Dioxide | 0.028 | 0.73 |
| Ethane | 0.0028 | Not Detected |
| Ethene | 0.0028 | Not Detected |
| Acetylene | 0.0028 | Not Detected |
| Propane | 0.0028 | Not Detected |
| Isobutane | 0.0028 | 0.000094 J |
| Butane | 0.0028 | 0.00085 J |
| Neopentane | 0.0028 | Not Detected |
| Isopentane | 0.0028 | 0.0011 J |
| Pentane | 0.0028 | 0.00043 J |
| C6+ | 0.028 | 0.0028 J |
| Hydrogen | 0.028 | Not Detected |

J = Estimated value.

Total BTU/Cu.F. = 0.45

Total Sp. Gravity = 1.0

**Container Type: 1 Liter Summa Canister**

eurofins | Air Toxics

**Client Sample ID: MainHeader-SVE-03012013**

**Lab ID#: 1303139B-02A**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1945**

| | | | |
|---|---|---|---|
| **File Name:** | **9031944** | **Date of Collection:** | **3/1/13 10:50:00 AM** |
| **Dil. Factor:** | **2.89** | **Date of Analysis:** | **3/20/13 09:27 AM** |

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.29 | 12 |
| Nitrogen | 1.4 | 77 |
| Carbon Monoxide | 0.029 | Not Detected |
| Methane | 0.00029 | 3.1 |
| Carbon Dioxide | 0.029 | 7.0 |
| Ethane | 0.0029 | 0.00084 J |
| Ethene | 0.0029 | Not Detected |
| Acetylene | 0.0029 | Not Detected |
| Propane | 0.0029 | 0.0013 J |
| Isobutane | 0.0029 | 0.021 |
| Butane | 0.0029 | 0.19 |
| Neopentane | 0.0029 | 0.00081 J |
| Isopentane | 0.0029 | 0.22 |
| Pentane | 0.0029 | 0.084 |
| C6+ | 0.029 | 0.63 |
| Hydrogen | 0.029 | Not Detected |

J = Estimated value.

Total BTU/Cu.F. = 80

Total Sp. Gravity = 1.0

**Container Type: 1 Liter Summa Canister**

eurofins | Air Toxics

**Client Sample ID: PWHeader-SVE-03012013**

**Lab ID#: 1303139B-03A**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1945**

| | | | |
|---|---|---|---|
| **File Name:** | **9031945** | **Date of Collection:** | **3/1/13 11:05:00 AM** |
| **Dil. Factor:** | **2.86** | **Date of Analysis:** | **3/20/13 09:56 AM** |

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.29 | 14 |
| Nitrogen | 1.4 | 75 |
| Carbon Monoxide | 0.029 | Not Detected |
| Methane | 0.00029 | 4.3 |
| Carbon Dioxide | 0.029 | 6.3 |
| Ethane | 0.0029 | 0.00027 J |
| Ethene | 0.0029 | Not Detected |
| Acetylene | 0.0029 | Not Detected |
| Propane | 0.0029 | 0.00013 J |
| Isobutane | 0.0029 | 0.0045 |
| Butane | 0.0029 | 0.041 |
| Neopentane | 0.0029 | 0.00025 J |
| Isopentane | 0.0029 | 0.093 |
| Pentane | 0.0029 | 0.039 |
| C6+ | 0.029 | 0.18 |
| Hydrogen | 0.029 | Not Detected |

J = Estimated value.

Total BTU/Cu.F. = 59

Total Sp. Gravity = 1.0

**Container Type: 1 Liter Summa Canister**

eurofins | Air Toxics

**Client Sample ID: Lab Blank**

**Lab ID#: 1303139B-04A**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1945**

| | | | |
|---|---|---|---|
| **File Name:** | **9031928a** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 3/19/13 09:05 PM** | |

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Methane | 0.00010 | 0.000030 J |
| Ethane | 0.0010 | Not Detected |
| Ethene | 0.0010 | Not Detected |
| Acetylene | 0.0010 | Not Detected |
| Propane | 0.0010 | Not Detected |
| Isobutane | 0.0010 | Not Detected |
| Butane | 0.0010 | Not Detected |
| Neopentane | 0.0010 | Not Detected |
| Isopentane | 0.0010 | Not Detected |
| Pentane | 0.0010 | Not Detected |
| C6+ | 0.010 | Not Detected |

J = Estimated value.

**Container Type: NA - Not Applicable**

eurofins | Air Toxics

**Client Sample ID: Lab Blank**

**Lab ID#: 1303139B-04B**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1945**

| | | | |
|---|---|---|---|
| **File Name:** | **10032005Ba** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 3/20/13 01:11 PM** | |

| **Compound** | **Rpt. Limit (%)** | **Amount (%)** |
|---|---|---|
| Oxygen | 0.10 | 0.016 J |
| Nitrogen | 0.50 | 0.098 J |
| Carbon Monoxide | 0.010 | Not Detected |
| Carbon Dioxide | 0.010 | Not Detected |

J = Estimated value.

**Container Type: NA - Not Applicable**

eurofins | Air Toxics

**Client Sample ID: Lab Blank**

**Lab ID#: 1303139B-04C**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1945**

| | | | |
|---|---|---|---|
| **File Name:** | **10032004C** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 3/20/13 12:47 PM** | |

| **Compound** | **Rpt. Limit (%)** | **Amount (%)** |
|---|---|---|
| Hydrogen | 0.010 | Not Detected |

**Container Type: NA - Not Applicable**

eurofins | Air Toxics

**Client Sample ID: LCS**

**Lab ID#: 1303139B-05A**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1945**

| | | | |
|---|---|---|---|
| **File Name:** | **9031927** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 3/19/13 08:44 PM** | |

| Compound | %Recovery |
|---|---|
| Methane | 99 |
| Ethane | 101 |
| Ethene | 100 |
| Acetylene | 97 |
| Propane | 100 |
| Isobutane | 103 |
| Butane | 101 |
| Neopentane | 100 |
| Isopentane | 100 |
| Pentane | 99 |
| C6+ | 96 |

**Container Type: NA - Not Applicable**

eurofins | Air Toxics

**Client Sample ID: LCSD**

**Lab ID#: 1303139B-05AA**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1945**

| | | | |
|---|---|---|---|
| **File Name:** | **9031953** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 3/20/13 02:40 PM** | |

| Compound | %Recovery |
|---|---|
| Methane | 99 |
| Ethane | 101 |
| Ethene | 100 |
| Acetylene | 97 |
| Propane | 100 |
| Isobutane | 103 |
| Butane | 101 |
| Neopentane | 100 |
| Isopentane | 100 |
| Pentane | 99 |
| C6+ | 100 |

**Container Type: NA - Not Applicable**

eurofins | Air Toxics

**Client Sample ID: LCS**

**Lab ID#: 1303139B-05B**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1945**

| | | | |
|---|---|---|---|
| **File Name:** | **10032002Ba** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 3/20/13 07:02 PM** | |

| Compound | %Recovery |
|---|---|
| Oxygen | 101 |
| Nitrogen | 100 |
| Carbon Monoxide | 100 |
| Carbon Dioxide | 101 |

**Container Type: NA - Not Applicable**

eurofins | Air Toxics

**Client Sample ID: LCSD**

**Lab ID#: 1303139B-05BB**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1945**

| | | | |
|---|---|---|---|
| **File Name:** | **10032029Ba** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 3/21/13 02:56 AM** | |

| Compound | %Recovery |
|---|---|
| Oxygen | 101 |
| Nitrogen | 100 |
| Carbon Monoxide | 100 |
| Carbon Dioxide | 100 |

**Container Type: NA - Not Applicable**

eurofins | Air Toxics

**Client Sample ID: LCS**

**Lab ID#: 1303139B-05C**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1945**

| | | | |
|---|---|---|---|
| **File Name:** | **10032030C** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 3/21/13 03:20 AM** | |

| Compound | %Recovery |
|---|---|
| Hydrogen | 100 |

**Container Type: NA - Not Applicable**

eurofins | Air Toxics

**Client Sample ID: LCSD**

**Lab ID#: 1303139B-05CC**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1945**

| | | | |
|---|---|---|---|
| **File Name:** | **10032031C** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 3/21/13 04:10 AM** | |

| Compound | %Recovery |
|---|---|
| Hydrogen | 100 |

**Container Type: NA - Not Applicable**

1303139

# Shell Oil Products Chain Of Custody Record

URS

Air Toxics LTD.
**Project Name: Roxana SVE O&M**
**Project # 21562860.05000**
Lab Vendor #

Please Check Appropriate Box:
☑ ENV. SERVICES ☐ MOTIVA RETAIL ☐ SHELL RETAIL
☐ MOTIVA S/B&CN ☐ CONSULTANT ☐ LUBES
☐ SHELL PIPELINE ☐ OTHER _____

Print Bill To Contact Name: Robert Mooshegian
PO #:
INCIDENT # (ENV SERVICES): 9 7 2 1 6 6 4 0
SAP #: 3 4 0 0 6 1
☐ CHECK IF NO INCIDENT # APPLIES
DATE: 5-Mar-13
PAGE: 1 of 1

SAMPLING COMPANY: URS CORPORATION
LOG CODE:
SITE ADDRESS: Street and City: 900 SOUTH CENTRAL AVE – ROXANA
State: IL
GLOBAL SITE #:

ADDRESS: 1001 HIGHLANDS PLAZA DRIVE WEST - SUITE 300, ST. LOUIS, MO 63110
EDF DELIVERABLE TO (Name, Company, Office Location): Elizabeth Kunkel, URS, St. Louis
PHONE NO: 314-743-4179
EMAIL:
CONSULTANT PROJECT NAME#: Roxana SVE O&M

Laboratory Address: Air Toxics, LTD 180 Blue Ravine Road, Suite B, Folsom, CA 95630-4719
SAMPLER NAME(S) (Print): S. Wipfler, M. Currier

TELEPHONE: 314-429-0100
FAX: 314-429-0452
Bill To Contact E-MAIL: dave.palmer@urs.com

TURNAROUND TIME (CALENDAR DAYS):
☑ STANDARD (14 DAY) ☐ 5 DAYS ☐ 3 DAYS ☐ 2 DAYS ☐ 24 HOURS ☐ RESULTS NEEDED ON WEEKEND

REQUESTED ANALYSIS

☐ JA - RWQCB REPORT FORMAT ☑ UST AGENCY:

DELIVERABLES ☐ LEVEL 1 ☐ LEVEL 2 ☐ LEVEL 3 ☑ LEVEL 4 ☐ OTHER (SPECIFY) _____

☑ SHELL CONTRACT RATE APPLIES
☐ STATE REIMBURSEMENT RATE APPLIES
☐ EDD NOT NEEDED
☑ RECEIPT VERIFICATION REQUESTED

Turn Around Time: ☑ Normal ☐ Rush ____ Specify

*Lab Use Only*
Pressurized by:
Date:
Pressurization Gas: $N_2$ He

| Lab Use Only | Field Sample Identification | SAMPLING DATE | SAMPLING TIME | Canister Number | Canister Pressure/Vacuum Initial | Final | Receipt | Final (psi) | Modified TO-15 + Butane & Isopentane | Modified ASTM D-1945 + BTU | Modified TO-3 (Sh)-TPHg | | Sample PID (ppm) |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| 01A | EXH-SVE-03012013 | 3/1/13 | 1040 | 37365 | -29 | -9 | | | X | X | X | | |
| 02A | MainHeader-SVE-03012013 | 3/1/13 | 1050 | 2106 | -29 | -9 | | | X | X | X | | |
| 03A | PWHeader-SVE-03012013 | 3/1/13 | 1105 | 37799 | -29 | -9 | | | X | X | X | | |

ADDITIONAL NOTES:
- 14 day hold time
- Report results between MDL and RL
- Level IV ECVP

FedEx
Custody Seal Intact?
(Y) N None Temp N/A

| | | Date | Time |
|---|---|---|---|
| Relinquished by: (Signature) | Received by: (Signature) FEDEX | 3/5/13 | 1700 |
| Relinquished by: (Signature) | Received by: (Signature) Kathy Becker ATL | 03/07/13 | 0930 |
| Relinquished by: (Signature) | Received by: (Signature) | Date | Time |

05/08 Revision

eurofins | Air Toxics

3/21/2013
Ms. Elizabeth Kunkel
URS Corporation
1001 Highlands Plaza Dr. West
Suite 300
St. Louis MO 63110

Project Name: Roxana SVE O&M
Project #: 21562850.05000
Workorder #: 1303139C

Dear Ms. Elizabeth Kunkel

The following report includes the data for the above referenced project for sample(s) received on 3/7/2013 at Air Toxics Ltd.

The data and associated QC analyzed by Modified TO-3 are compliant with the project requirements or laboratory criteria with the exception of the deviations noted in the attached case narrative.

Thank you for choosing Air Toxics Ltd. for your air analysis needs. Air Toxics Ltd. is committed to providing accurate data of the highest quality. Please feel free to contact the Project Manager: Kelly Buettner at 916-985-1000 if you have any questions regarding the data in this report.

Regards,

Kelly Buettner
Project Manager

Reviewed
on
3/26/2013

eurofins | Air Toxics

# WORK ORDER #: 1303139C

Work Order Summary

| | | | |
|---|---|---|---|
| **CLIENT:** | Ms. Elizabeth Kunkel<br>URS Corporation<br>1001 Highlands Plaza Dr. West<br>Suite 300<br>St. Louis, MO 63110 | **BILL TO:** | Accounts Payable Austin<br>URS Corporation<br>P.O. BOX 203970<br>Austin, TX 78720-1088 |
| **PHONE:** | 314-743-4179 | **P.O. #** | |
| **FAX:** | | **PROJECT #** | 21562850.05000 Roxana SVE O&M |
| **DATE RECEIVED:** | 03/07/2013 | **CONTACT:** | Kelly Buettner |
| **DATE COMPLETED:** | 03/21/2013 | | |

| FRACTION # | NAME | TEST | RECEIPT VAC./PRES. | FINAL PRESSURE |
|---|---|---|---|---|
| 01A | EXH-SVE-03012013 | Modified TO-3 | 8.8 "Hg | 14.8 psi |
| 02A | MainHeader-SVE-03012013 | Modified TO-3 | 9.2 "Hg | 14.8 psi |
| 03A | PWHeader-SVE-03012013 | Modified TO-3 | 9 "Hg | 14.8 psi |
| 04A | Lab Blank | Modified TO-3 | NA | NA |
| 05A | LCS | Modified TO-3 | NA | NA |
| 05AA | LCSD | Modified TO-3 | NA | NA |

CERTIFIED BY: Heidi Hayes DATE: 03/21/13

Technical Director

Certification numbers: AZ Licensure AZ0775, CA NELAP - 12282CA, NY NELAP - 11291,
TX NELAP - T104704434-12-4, UT NELAP CA009332012-3, WA NELAP - C935
Name of Accrediting Agency: NELAP/ORELAP (Oregon Environmental Laboratory Accreditation Program)
Accreditation number: CA300005, Effective date: 10/18/2012, Expiration date: 10/17/2013.
Eurofins Air Toxics Ltd. certifies that the test results contained in this report meet all requirements of the NELAC standards

This report shall not be reproduced, except in full, without the written approval of Eurofins Air Toxics, Inc.

180 BLUE RAVINE ROAD, SUITE B FOLSOM, CA - 9563
(916) 985-1000 . (800) 985-5955 . FAX (916) 985-1020

**LABORATORY NARRATIVE**
**Modified TO-3**
**URS Corporation**
**Workorder# 1303139C**

Three 1 Liter Summa Canister samples were received on March 07, 2013. The laboratory performed analysis for volatile organic compounds in air via modified EPA Method TO-3 using gas chromatography with flame ionization detection. The TPH results are calculated using the response of Gasoline. A molecular weight of 100 is used to convert the TPH ppmv result to ug/L. The method involves concentrating up to 200 mL of sample. The concentrated aliquot is then dry purged to remove water vapor prior to entering the chromatographic system.

Method modifications taken to run these samples are summarized in the table below. Specific project requirements may over-ride the ATL modifications.

| *Requirement* | *TO-3* | *ATL Modifications* |
|---|---|---|
| Daily Calibration Standard Frequency | Prior to sample analysis and every 4 - 6 hrs | Prior to sample analysis and after the analytical batch </= 20 samples. |
| Initial Calibration Calculation | 4-point calibration using a linear regression model | 5-point calibration using avcrage Response Factor |
| Initial Calibration Frequency | Weekly | When daily calibration standard recovery is outside 75 - 125 %, or upon significant changes to procedure or instrumentation |
| Moisture Control | Nafion system | Sorbent system |
| Minimum Detection Limit (MDL) | Calculated using the equation DL = A+3.3S, where A is intercept of calibration line and S is the standard deviation of at least 3 reps of low level standard | 40 CFR Pt. 136 App. B |
| Preparation of Standards | Levels aehieved through dilution of gas mixture | Levels achieved through loading various volumes of the gas mixture |

**Receiving Notes**

There were no receiving discrepancies.

**Analytical Notes**

The recovery of surrogate Fluorobenzene in samples EXH-SVE-03012013 and MainHeader-SVE-03012013 was outside control limits due to high level hydrocarbon matrix interference. Data is reported as qualified.

As per project specific client request the laboratory has reported estimated values for target compound hits that are below the Reporting Limit but greater than the Method Detection Limit. Concentrations

that are below the level at which the canister was certified may be false positives.

**Definition of Data Qualifying Flags**

Seven qualifiers may have been used on the data analysis sheets and indicate as follows:
B - Compound present in laboratory blank greater than reporting limit.
J - Estimated value.
E - Exceeds instrument calibration range.
S - Saturated peak.
Q - Exceeds quality control limits.
U - Compound analyzed for but not detected above the detection limit.
M - Reported value may be biased due to apparent matrix interferences.

File extensions may have been used on the data analysis sheets and indicates as follows:
a-File was requantified
b-File was quantified by a second column and detector
r1-File was requantified for the purpose of reissue

eurofins | Air Toxics

# Summary of Detected Compounds
# MODIFIED EPA METHOD TO-3 GC/FID

**Client Sample ID: EXH-SVE-03012013**

**Lab ID#: 1303139C-01A**

| Compound | Rpt. Limit (ppmv) | Rpt. Limit (ug/L) | Amount (ppmv) | Amount (ug/L) |
|---|---|---|---|---|
| TPH (C2-C10) ref. to Gasoline MW=100 | 0.14 | 0.58 | 84 J | 340 J |

**Client Sample ID: MainHeader-SVE-03012013**

**Lab ID#: 1303139C-02A**

| Compound | Rpt. Limit (ppmv) | Rpt. Limit (ug/L) | Amount (ppmv) | Amount (ug/L) |
|---|---|---|---|---|
| TPH (C2-C10) ref. to Gasoline MW=100 | 14 | 59 | 14000 J | 55000 J |

**Client Sample ID: PWHeader-SVE-03012013**

**Lab ID#: 1303139C-03A**

| Compound | Rpt. Limit (ppmv) | Rpt. Limit (ug/L) | Amount (ppmv) | Amount (ug/L) |
|---|---|---|---|---|
| TPH (C2-C10) ref. to Gasoline MW=100 | 28 | 120 | 3800 | 16000 |

eurofins | Air Toxics

**Client Sample ID: EXH-SVE-03012013**

**Lab ID#: 1303139C-01A**

**MODIFIED EPA METHOD TO-3 GC/FID**

| | | | |
|---|---|---|---|
| **File Name:** | **d031507** | **Date of Collection: 3/1/13 10:40:00 AM** | |
| **Dil. Factor:** | **5.68** | **Date of Analysis: 3/15/13 02:28 PM** | |

| Compound | Rpt. Limit (ppmv) | Rpt. Limit (ug/L) | Amount (ppmv) | Amount (ug/L) |
|---|---|---|---|---|
| TPH (C2-C10) ref. to Gasoline MW=100 | 0.14 | 0.58 | 84 J | 340 J |

Q = Exceeds Quality Control limits, due to matrix effects. Matrix effects confirmed by re-analysis.

**Container Type: 1 Liter Summa Canister**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| Fluorobenzene (FID) | 165 Q | 75-150 |

eurofins | Air Toxics

**Client Sample ID: MainHeader-SVE-03012013**

**Lab ID#: 1303139C-02A**

**MODIFIED EPA METHOD TO-3 GC/FID**

| | | | |
|---|---|---|---|
| **File Name:** | **d031508** | **Date of Collection: 3/1/13 10:50:00 AM** | |
| **Dil. Factor:** | **578** | **Date of Analysis: 3/15/13 03:41 PM** | |

| Compound | Rpt. Limit (ppmv) | Rpt. Limit (ug/L) | Amount (ppmv) | Amount (ug/L) |
|---|---|---|---|---|
| TPH (C2-C10) ref. to Gasoline MW=100 | 14 | 59 | 14000 J | 55000 J |

Q = Exceeds Quality Control limits, possibly due to matrix effects.

**Container Type: 1 Liter Summa Canister**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| Fluorobenzene (FID) | 226 Q | 75-150 |

eurofins | Air Toxics

**Client Sample ID: PWHeader-SVE-03012013**

**Lab ID#: 1303139C-03A**

**MODIFIED EPA METHOD TO-3 GC/FID**

| | | | |
|---|---|---|---|
| **File Name:** | **d031509** | **Date of Collection: 3/1/13 11:05:00 AM** | |
| **Dil. Factor:** | **1140** | **Date of Analysis: 3/15/13 04:58 PM** | |

| Compound | Rpt. Limit (ppmv) | Rpt. Limit (ug/L) | Amount (ppmv) | Amount (ug/L) |
|---|---|---|---|---|
| TPH (C2-C10) ref. to Gasoline MW=100 | 28 | 120 | 3800 | 16000 |

**Container Type: 1 Liter Summa Canister**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| Fluorobenzene (FID) | 121 | 75-150 |

eurofins | Air Toxics

**Client Sample ID: Lab Blank**

**Lab ID#: 1303139C-04A**

**MODIFIED EPA METHOD TO-3 GC/FID**

| | | | |
|---|---|---|---|
| **File Name:** | **d031505** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 3/15/13 12:06 PM** | |

| Compound | Rpt. Limit (ppmv) | Rpt. Limit (ug/L) | Amount (ppmv) | Amount (ug/L) |
|---|---|---|---|---|
| TPH (C2-C10) ref. to Gasoline MW=100 | 0.025 | 0.10 | 0.010 J | 0.043 J |

J = Estimated value.

**Container Type: NA - Not Applicable**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| Fluorobenzene (FID) | 100 | 75-150 |

eurofins | Air Toxics

**Client Sample ID: LCS**

**Lab ID#: 1303139C-05A**

**MODIFIED EPA METHOD TO-3 GC/FID**

| | | | |
|---|---|---|---|
| **File Name:** | **d031502** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 3/15/13 10:31 AM** | |

| **Compound** | **%Recovery** |
|---|---|
| TPH (C2+ Hydrocarbons) ref. to Gasoline | 94 |

**Container Type: NA - Not Applicable**

| **Surrogates** | **%Recovery** | **Method Limits** |
|---|---|---|
| Fluorobenzene (FID) | 119 | 75-150 |

eurofins | Air Toxics

**Client Sample ID: LCSD**

**Lab ID#: 1303139C-05AA**

**MODIFIED EPA METHOD TO-3 GC/FID**

| | | | |
|---|---|---|---|
| **File Name:** | **d031510** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 3/15/13 05:50 PM** | |

| **Compound** | **%Recovery** |
|---|---|
| TPH (C2+ Hydrocarbons) ref. to Gasoline | 97 |

**Container Type: NA - Not Applicable**

| **Surrogates** | **%Recovery** | **Method Limits** |
|---|---|---|
| Fluorobenzene (FID) | 110 | 75-150 |

1303139

# Shell Oil Products Chain Of Custody Record

URS

Air Toxics LTD.
**Project Name: Roxana SVE O&M**
**Project # 21562850.05000**
Lab Vendor #

Please Check Appropriate Box: ☑ ENV. SERVICES ☐ MOTIVA RETAIL ☐ SHELL RETAIL ☐ MOTIVA SD&CN ☐ CONSULTANT ☐ LUBES ☐ SHELL PIPELINE ☐ OTHER

Print Bill To Contact Name: Robert Moshegian

INCIDENT # (ENV SERVICES): 9 7 2 1 6 6 4 0 ☐ CHECK IF NO INCIDENT # APPLIES

PO #:

SAP #: 3 4 0 0 6 1

DATE: 5-Mar-13

PAGE: 1 of 1

SAMPLING COMPANY: URS CORPORATION

LOG CODE:

SITE ADDRESS: Street and City: 900 SOUTH CENTRAL AVE – ROXANA

State: IL

GLOBAL ID NO:

ADDRESS: 1001 HIGHLANDS PLAZA DRIVE WEST - SUITE 300, ST. LOUIS, MO 63110

EDF DELIVERABLE TO (Name, Company, Office Location): Elizabeth Kunkel, URS, St. Louis

PHONE NO: 314-743-4179

E-MAIL: elizabeth_kunkel@urs.com

CONSULTANT PROJECT NAME#: Roxana SVE O&M

Laboratory Address: Air Toxics, LTD 180 Blue Ravine Road, Suite B, Folsom, CA 95630-4719

SAMPLER NAME(S) (Print): S. Wipfler, M. Currier

TELEPHONE: 314-429-0100

FAX: 314-429-0462

EDF To Contact E-MAIL: dave.palmer@urs.com

TURNAROUND TIME (CALENDAR DAYS): ☑ STANDARD (14 DAY) ☐ 5 DAYS ☐ 3 DAYS ☐ 7 DAYS ☐ 24 HOURS ☐ RESULTS NEEDED ON WEEKEND

REQUESTED ANALYSIS

☐ LA - RWQCB REPORT FORMAT ☑ UST AGENCY:

DELIVERABLES: ☐ LEVEL 1 ☐ LEVEL 2 ☐ LEVEL 3 ☑ LEVEL 4 ☐ OTHER (SPECIFY)

☑ SHELL CONTRACT RATE APPLIES
☐ STATE REIMBURSEMENT RATE APPLIES
☐ EDD NOT NEEDED
☑ RECEIPT VERIFICATION REQUESTED

Turn Around Time: ☑ Normal ☐ Rush Specify

Lab Use Only
Pressurized by:
Date:
Pressurization Gas: $N_2$ He

| LAB USE ONLY | Field Sample Identification | SAMPLING DATE | SAMPLING TIME | Canister Number | Canister Pressure/Vacuum Initial | Final | Receipt | Final (psi) | Modified TO-15 + Butane & Isopentane | Modified ASTM D-1945 + BTU | Modified TO-3 (Sh)-TPHg | | Sample PID (ppm) |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| 01A | EXH-SVE-03012013 | 3/1/13 | 1040 | 37365 | -29 | -9 | | | X | X | X | | |
| 02A | MainHeader-SVE-03012013 | 3/1/13 | 1050 | 2106 | -29 | -9 | | | X | X | X | | |
| 03A | PWHeader-SVE-03012013 | 3/1/13 | 1105 | 37799 | -29 | -9 | | | X | X | X | | |

ADDITIONAL NOTES:
- 14 day hold time
- Report results between MDL and RL
- Level IV ECVP

Custody Seal Intact? Y N None Temp NA

| | | | |
|---|---|---|---|
| Relinquished by: (Signature) | Received by: (Signature) FEDEX | Date: 3/5/13 | Time: 1700 |
| Relinquished by: (Signature) | Received by: (Signature) Kristi Decker ATL | Date: 03/07/13 | Time: 0930 |
| Relinquished by: (Signature) | Received by: (Signature) | Date: | Time: |

05/2006 Revision

# Roxana Soil Vapor Quarterly – 1st Quarter 2013 Data Review

**Laboratory SDG: 1303140A,B**

**Data Reviewer: Elizabeth Kunkel**

**Peer Reviewer: Steve Gragert**

**Date Reviewed: 3/26/2013**

**Guidance: USEPA National Functional Guidelines for Superfund Organic Methods Data Review 2008**

| Sample Identification | Sample Identification |
|---|---|
| VMP-25-5-030613 | VMP-25-21-030613 |
| VMP-25-31-030613 | |

## 1.0 Data Package Completeness

*Were all items delivered as specified in the QAPP and COC as appropriate?*

Yes

## 2.0 Laboratory Case Narrative \ Cooler Receipt Form

*Were problems noted in the laboratory case narrative or cooler receipt form?*

Yes, the laboratory case narrative indicated sample VMP-25-21-030613 was diluted and re-analyzed to bring the highest level target analytes within the calibration range of the instrument. Results for the highest level target analytes were reported from the re-analysis diluted runs and the remaining compounds were reported from the original analyses. Sample VMP-25-31-030613 was diluted due to high levels of target analytes. TO-15 LCS/LCSD recoveries and one LCS/LCSD RPD were outside evaluation criteria. CCV recovery for 2,2,4-trimethylpentane was outside evaluation criteria. Although not indicated in the laboratory case narrative, analytes were detected in the method blank. These issues are addressed further in the appropriate sections below.

No issues or discrepancies were noted in the cooler receipt form.

## 3.0 Holding Times

*Were samples extracted/analyzed within applicable limits?*

Yes

## 4.0 Blank Contamination

*Were any analytes detected in the Blanks?*

Yes

| Blank ID | Parameter | Analyte | Concentration/ Amount |
|---|---|---|---|
| 1303140A-04A | TO-15 | Carbon disulfide | 0.44 ppbv / 1.4 µg/m$^3$ |
| 1303140A-04A | TO-15 | Methylene chloride | 0.12 ppbv / 0.44 µg/m$^3$ |
| 1303140A-04A | TO-15 | trans-1,3-Dichloropropene | 0.14 ppbv / 0.63 µg/m$^3$ |
| 1303140A-04A | TO-15 | Tetrachloroethene | 0.074 ppbv / 0.50 µg/m$^3$ |
| 1303140A-04A | TO-15 | Chlorobenzene | 0.095 ppbv / 0.44 µg/m$^3$ |

| Blank ID | Parameter | Analyte | Concentration/ Amount |
|---|---|---|---|
| 1303140A-04A | TO-15 | Propylbenzene | 0.072 ppbv / 0.35 µg/m$^3$ |
| 1303140A-04A | TO-15 | 4-Ethyltoluene | 0.040 ppbv / 0.19 µg/m$^3$ |
| 1303140A-04A | TO-15 | 1,3,5-Trimethylbenzene | 0.10 ppbv / 0.51 µg/m$^3$ |
| 1303140A-04A | TO-15 | 1,3-Dichlorobenzene | 0.24 ppbv / 1.4 µg/m$^3$ |
| 1303140A-04A | TO-15 | 1,4-Dichlorobenzene | 0.26 ppbv / 1.6 µg/m$^3$ |
| 1303140A-04A | TO-15 | alpha-Chlorotoluene | 0.13 ppbv / 0.70 µg/m$^3$ |
| 1303140A-04A | TO-15 | 1,2-Dichlorobenzene | 0.21 ppbv / 1.3 µg/m$^3$ |
| 1303140A-04A | TO-15 | 1,2,4-Trichlorobenzene | 0.91 ppbv / 6.8 µg/m$^3$ |
| 1303140A-04A | TO-15 | Hexachlorobutadiene | 0.36 ppbv / 3.8 µg/m$^3$ |
| 1303140A-04B | TO-15 | Ethanol | 8.9 ppbv / 17 µg/m$^3$ |
| 1303140A-04B | TO-15 | Methylene chloride | 1.5 ppbv / 5.1 µg/m$^3$ |
| 1303140B-04A | Natural gases | Oxygen | 0.016% |
| 1303140B-04A | Natural gases | Nitrogen | 0.098% |
| 1303140B-04C | Natural gases | Methane | 0.000032 |

Qualifications due to blank contamination are included in the following table. Analytical data that were reported non-detect or at concentrations greater than five times (5X) the associated blank concentration did not require qualification.

| Sample ID | Parameter | Analyte | New Reporting Limit (RL) | Qualification |
|---|---|---|---|---|
| VMP-25-5-030613 | TO-15 | Carbon disulfide | - | **U** |
| VMP-25-5-030613 | TO-15 | Methylene chloride | - | **U** |
| VMP-25-5-030613 | TO-15 | trans-1,3-Dichloropropene | - | **U** |
| VMP-25-5-030613 | TO-15 | Tetrachloroethene | - | **U** |
| VMP-25-5-030613 | TO-15 | Chlorobenzene | - | **U** |
| VMP-25-5-030613 | TO-15 | 1,3-Dichlorobenzene | - | **U** |
| VMP-25-5-030613 | TO-15 | 1,4-Dichlorobenzene | - | **U** |
| VMP-25-5-030613 | TO-15 | alpha-Chlorotoluene | - | **U** |
| VMP-25-5-030613 | TO-15 | 1,2-Dichlorobenzene | - | **U** |
| VMP-25-5-030613 | TO-15 | 1,2,4-Trichlorobenzene | - | **U** |

## 5.0 Laboratory Control Sample

*Were LCS recoveries within evaluation criteria?*

No

| LCS/LCSD ID | Parameter | Analyte | LCS/LCSD Recovery | LCS/ LCSD RPD | LCS/LCSD /RPD Criteria |
|---|---|---|---|---|---|
| 1303140A-06A/AA | TO-15 | Cyclohexane | **155**/116 | **29** | 70-130/25 |
| 1303140A-06A/AA | TO-15 | 2,2,4-Trimethylpentane | **131**/105 | 22 | 70-130/25 |
| 1303140A-06A/AA | TO-15 | 1,1,2,2-Tetrachloroethane | **65/**70 | 7 | 70-130/25 |

| LCS/LCSD ID | Parameter | Analyte | LCS/LCSD Recovery | LCS/ LCSD RPD | LCS/LCSD /RPD Criteria |
|---|---|---|---|---|---|
| 1303140A-06A/AA | TO-15 | cis-1,2-Dichloroethene | 112/**132** | 16 | 70-130/25 |

Analytical data that required qualification based on LCS data are included in the table below. Analytical data reported as non-detect and associated with LCS recoveries above evaluation criteria, indicating a possible high bias, did not require qualification.

| Sample ID | Parameter | Analyte | Qualification |
|---|---|---|---|
| VMP-25-5-030613 | TO-15 | Cyclohexane | **J** |
| VMP-25-5-030613 | TO-15 | 2,2,4-Trimethylpentane | **J** |
| VMP-25-5-030613 | TO-15 | 1,1,2,2-Tetrachloroethane | **UJ** |
| VMP-25-21-030613 | TO-15 | Cyclohexane | **J** |
| VMP-25-21-030613 | TO-15 | 2,2,4-Trimethylpentane | **J** |
| VMP-25-21-030613 | TO-15 | 1,1,2,2-Tetrachloroethane | **UJ** |

## 6.0 Surrogate Recoveries

*Were surrogate recoveries within evaluation criteria?*

Yes

## 7.0 Matrix Spike and Matrix Spike Duplicate Recoveries

*Were MS/MSD samples analyzed as part of this SDG?*

MS/MSD samples are not applicable for vapor samples, due to the inability to spike the samples.

## 8.0 Laboratory Duplicate Results

*Were laboratory duplicate samples collected as part of this SDG?*

No

## 9.0 Field Duplicate Results

*Were field duplicate samples collected as part of this SDG?*

No

## 10.0 Sample Dilutions

*For samples that were diluted and nondetect, were undiluted results also reported?*

Not applicable; analytes were detected in samples that were diluted.

## 11.0 Additional Qualifications

*Were additional qualifications applied?*

Yes, continuing calibration verification (CCV) recoveries listed in the following table were above evaluation criteria.

| CCV ID | Parameter | Analyte | CCV Recovery | CCV Criteria |
|---|---|---|---|---|
| 1303140A-05A | TO-15 | 2,2,4-Trimethylpentane | **136** | 70-130 |

Analytical data that required qualification based on CCV data are included in the table below. Analytical data reported as non-detect and associated with CCV recoveries above evaluation criteria, indicating a possible high bias, did not require qualification.

| Field ID | Parameter | Analyte | Qualification |
|---|---|---|---|
| VMP-25-5-030613 | TO-15 | 2,2,4-Trimethylpentane | **J** |
| VMP-25-21-030613 | TO-15 | 2,2,4-Trimethylpentane | **J** |

eurofins | Air Toxics

3/22/2013
Ms. Elizabeth Kunkel
URS Corporation
1001 Highlands Plaza Dr. West
Suite 300
St. Louis MO 63110

Project Name: Roxana Soil Vapor
Project #: 21562850.04001
Workorder #: 1303140A

Dear Ms. Elizabeth Kunkel

The following report includes the data for the above referenced project for sample(s) received on 3/7/2013 at Air Toxics Ltd.

The data and associated QC analyzed by Modified TO-15 are compliant with the project requirements or laboratory criteria with the exception of the deviations noted in the attached case narrative.

Thank you for choosing Air Toxics Ltd. for your air analysis needs. Air Toxics Ltd. is committed to providing accurate data of the highest quality. Please feel free to contact the Project Manager: Kelly Buettner at 916-985-1000 if you have any questions regarding the data in this report.

Regards,

Kelly Buettner

Project Manager

Reviewed
on
3/26/2013

# WORK ORDER #: 1303140A

Work Order Summary

| | | | |
|---|---|---|---|
| **CLIENT:** | Ms. Elizabeth Kunkel<br>URS Corporation<br>1001 Highlands Plaza Dr. West<br>Suite 300<br>St. Louis, MO 63110 | **BILL TO:** | Accounts Payable Austin<br>URS Corporation<br>P.O. BOX 203970<br>Austin, TX 78720-1088 |
| **PHONE:** | 314-743-4179 | **P.O. #** | 21562735.00013 |
| **FAX:** | | **PROJECT #** | 21562850.04001 Roxana Soil Vapor |
| **DATE RECEIVED:** | 03/07/2013 | **CONTACT:** | Kelly Buettner |
| **DATE COMPLETED:** | 03/22/2013 | | |

| FRACTION # | NAME | TEST | RECEIPT VAC./PRES. | FINAL PRESSURE |
|---|---|---|---|---|
| 01A | VMP-25-5-030613 | Modified TO-15 | 6.3 "Hg | 15.1 psi |
| 02A | VMP-25-21-030613 | Modified TO-15 | 4.8 "Hg | 15 psi |
| 02B | VMP-25-21-030613 | Modified TO-15 | 4.8 "Hg | 15 psi |
| 03A | VMP-25-31-030613 | Modified TO-15 | 5.3 "Hg | 14.8 psi |
| 04A | Lab Blank | Modified TO-15 | NA | NA |
| 04B | Lab Blank | Modified TO-15 | NA | NA |
| 05A | CCV | Modified TO-15 | NA | NA |
| 05B | CCV | Modified TO-15 | NA | NA |
| 06A | LCS | Modified TO-15 | NA | NA |
| 06AA | LCSD | Modified TO-15 | NA | NA |
| 06B | LCS | Modified TO-15 | NA | NA |
| 06BB | LCSD | Modified TO-15 | NA | NA |

CERTIFIED BY: Heidi Jaeger DATE: 03/22/13

Technical Director

Certification numbers: AZ Licensure AZ0775, CA NELAP - 12282CA, NY NELAP - 11291,
TX NELAP - T104704434-12-5, UT NELAP CA009332012-3, WA NELAP - C935
Name of Accrediting Agency: NELAP/ORELAP (Oregon Environmental Laboratory Accreditation Program)
Accreditation number: CA300005, Effective date: 10/18/2011, Expiration date: 10/17/2012.
Eurofins Air Toxics Ltd. certifies that the test results contained in this report meet all requirements of the NELAC standards

This report shall not be reproduced, except in full, without the written approval of Eurofins Air Toxics, Inc.

180 BLUE RAVINE ROAD, SUITE B FOLSOM, CA - 9563
(916) 985-1000 . (800) 985-5955 . FAX (916) 985-1020

**LABORATORY NARRATIVE**
**EPA Method TO-15**
**URS Corporation**
**Workorder# 1303140A**

Three 1 Liter Summa Canister samples were received on March 07, 2013. The laboratory performed analysis via EPA Method TO-15 using GC/MS in the full scan mode.

This workorder was independently validated prior to submittal using 'USEPA National Functional Guidelines' as generally applied to the analysis of volatile organic compounds in air. A rules-based, logic driven, independent validation engine was employed to assess completeness, evaluate pass/fail of relevant project quality control requirements and verification of all quantified amounts.

**Receiving Notes**

There were no receiving discrepancies.

**Analytical Notes**

As per client project requirements, the laboratory has reported estimated values for target compound hits that are below the Reporting Limit but greater than the Method Detection Limit. Concentrations that are below the level at which the canister was certified may be false positives.

Due to high-level target compounds, sample VMP-25-21-030613 was analyzed twice. In the "A" fraction, the sample was diluted to bring the highest-level compounds within the calibration range. The "B" fraction is also reported by client request and may be reported with "E" flags indicating the compound exceeds the calibration range. Both runs and associated QC are reported.

Dilution was performed on sample VMP-25-31-030613 due to the presence of high level target species.

The recovery of 155% for Cyclohexane in the LCS was outside method and laboratory acceptance criteria and the RPD of 29% between the LCS and LCSD was also outside the method criteria of 25% RPD. Associated Cyclohexane detections from the analytical batch performed on instrument MSD-P were flagged as estimated values.

All Quality Control Limit exceedances and affected sample results are noted by flags. Each flag is defined at the bottom of this Case Narrative and on each Sample Result Summary page.

**Definition of Data Qualifying Flags**

Eight qualifiers may have been used on the data analysis sheets and indicates as follows:

B - Compound present in laboratory blank greater than reporting limit (background subtraction not performed).
J - Estimated value.
E - Exceeds instrument calibration range.
S - Saturated peak.
Q - Exceeds quality control limits.
U - Compound analyzed for but not detected above the reporting limit.
UJ- Non-detected compound associated with low bias in the CCV and/or LCS.
N - The identification is based on presumptive evidence.

File extensions may have been used on the data analysis sheets and indicates as follows:

a-File was requantified
b-File was quantified by a second column and detector
r1-File was requantified for the purpose of reissue

eurofins | Air Toxics

# Summary of Detected Compounds
# EPA METHOD TO-15 GC/MS FULL SCAN

**Client Sample ID: VMP-25-5-030613**

**Lab ID#: 1303140A-01A**

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 1.3 | 0.35 J | 6.4 | 1.7 J |
| Freon 11 | 1.3 | 0.17 J | 7.2 | 0.96 J |
| Ethanol | 5.1 | 3.7 J | 9.7 | 6.9 J |
| Acetone | 13 | 7.4 J | 30 | 18 J |
| 2-Propanol | 5.1 | 8.8 | 13 | 22 |
| Carbon Disulfide | 5.1 | ~~0.84 J~~ U | 16 | ~~2.6 J~~ U |
| Methylene Chloride | 13 | ~~0.35 J~~ U | 45 | ~~1.2 J~~ U |
| Hexane | 1.3 | 0.65 J | 4.5 | 2.3 J |
| 2-Butanone (Methyl Ethyl Ketone) | 5.1 | 1.8 J | 15 | 5.4 J |
| Tetrahydrofuran | 1.3 | 0.27 J | 3.8 | 0.80 J |
| Cyclohexane | 1.3 | 1.2 J J | 4.4 | 4.2 J J |
| 2,2,4-Trimethylpentane | 1.3 | 15 J J | 6.0 | 72 J J |
| Benzene | 1.3 | 1.5 | 4.1 | 4.8 |
| Toluene | 1.3 | 1.4 | 4.8 | 5.3 |
| trans-1,3-Dichloropropene | 1.3 | ~~0.33 J~~ U | 5.8 | ~~1.5 J~~ U |
| Tetrachloroethene | 1.3 | ~~0.22 J~~ U | 8.7 | ~~1.5 J~~ U |
| Chlorobenzene | 1.3 | ~~0.16 J~~ U | 5.9 | ~~0.76 J~~ U |
| Ethyl Benzene | 1.3 | 0.53 J | 5.6 | 2.3 J |
| Cumene | 1.3 | 0.54 J | 6.3 | 2.6 J |
| Propylbenzene | 1.3 | 1.5 | 6.3 | 7.5 |
| 4-Ethyltoluene | 1.3 | 0.37 J | 6.3 | 1.8 J |
| 1,2,4-Trimethylbenzene | 1.3 | 0.70 J | 6.3 | 3.4 J |
| 1,3-Dichlorobenzene | 1.3 | ~~0.40 J~~ U | 7.7 | ~~2.4 J~~ U |
| 1,4-Dichlorobenzene | 1.3 | ~~0.59 J~~ U | 7.7 | ~~3.5 J~~ U |
| alpha-Chlorotoluene | 1.3 | ~~0.28 J~~ U | 6.6 | ~~1.5 J~~ U |
| 1,2-Dichlorobenzene | 1.3 | ~~0.32 J~~ U | 7.7 | ~~1.9 J~~ U |
| 1,2,4-Trichlorobenzene | 5.1 | ~~1.1 J~~ U | 38 | ~~8.5 J~~ U |
| Butane | 5.1 | 6.5 | 12 | 16 |
| Isopentane | 5.1 | 9.8 | 15 | 29 |

**Client Sample ID: VMP-25-21-030613**

**Lab ID#: 1303140A-02A**

eurofins | Air Toxics

# Summary of Detected Compounds
# EPA METHOD TO-15 GC/MS FULL SCAN

**Client Sample ID: VMP-25-21-030613** * Use these results only. All other data was reported from the 19200X dilution analysis.
**Lab ID#: 1303140A-02A** DF = 48000X

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Acetone | 240000 | 65000 J | 570000 | 150000 J |
| Carbon Disulfide | 96000 | 14000 J | 300000 | 44000 J |
| Methylene Chloride | 240000 | 15000 J | 830000 | 51000 J |
| Hexane | 24000 | 440000 | 84000 | 1500000 |
| 1,1-Dichloroethane | 24000 | 6700 J | 97000 | 27000 J |
| Chloroform | 24000 | 10000 J | 120000 | 51000 J |
| Cyclohexane | 24000 | 440000 J J | 83000 | 1500000 J J |
| 2,2,4-Trimethylpentane | 24000 | 49000 J J | 110000 | 230000 J J |
| Benzene | 24000 | 27000 | 77000 | 87000 |
| Heptane | 24000 | 93000 | 98000 | 380000 |
| Toluene | 24000 | 23000 J | 90000 | 87000 J |
| Tetrachloroethene | 24000 | 7400 J | 160000 | 50000 J |
| * Butane | 96000 | 5000000 | 230000 | 12000000 |
| * Isopentane | 96000 | 6900000 | 280000 | 20000000 |

**Client Sample ID: VMP-25-21-030613** ** Do not use this data. Use all other data.
**Lab ID#: 1303140A-02B** DF = 19200X

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Carbon Disulfide | 38000 | 10000 J | 120000 | 31000 J |
| Methylene Chloride | 96000 | 2600 J | 330000 | 9100 J |
| Hexane | 9600 | 630000 | 34000 | 2200000 |
| 1,1-Dichloroethane | 9600 | 1900 J | 39000 | 7700 J |
| Cyclohexane | 9600 | 670000 J | 33000 | 2300000 J |
| 2,2,4-Trimethylpentane | 9600 | 85000 J J | 45000 | 400000 J J |
| Benzene | 9600 | 30000 | 31000 | 95000 |
| Heptane | 9600 | 130000 | 39000 | 530000 |
| Toluene | 9600 | 1100 J | 36000 | 4200 J |
| ~~** Butane~~ | ~~38000~~ | ~~6300000 E~~ | ~~91000~~ | ~~15000000 E~~ |
| ~~** Isopentane~~ | ~~38000~~ | ~~7100000 E~~ | ~~110000~~ | ~~21000000 E~~ |

# Summary of Detected Compounds
# EPA METHOD TO-15 GC/MS

**Client Sample ID: VMP-25-31-030613**

**Lab ID#: 1303140A-03A**

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Chloroethane | 51000 | 4200 J | 130000 | 11000 J |
| Ethanol | 51000 | 8000 J | 96000 | 15000 J |
| 2-Propanol | 51000 | 2300 J | 120000 | 5600 J |
| Methylene Chloride | 13000 | 8800 J | 44000 | 30000 J |
| Methyl tert-butyl ether | 13000 | 2000 J | 46000 | 7400 J |
| Hexane | 13000 | 79000 | 45000 | 280000 |
| Chloroform | 13000 | 1500 J | 62000 | 7300 J |
| Cyclohexane | 13000 | 170000 | 44000 | 580000 |
| 2,2,4-Trimethylpentane | 13000 | 210000 | 59000 | 990000 |
| Benzene | 13000 | 28000 | 40000 | 90000 |
| Heptane | 13000 | 15000 | 52000 | 60000 |
| Trichloroethene | 13000 | 2100 J | 68000 | 11000 J |
| Toluene | 13000 | 3200 J | 48000 | 12000 J |
| Tetrachloroethene | 13000 | 1600 J | 86000 | 10000 J |
| m,p-Xylene | 13000 | 1600 J | 55000 | 7000 J |
| o-Xylene | 13000 | 1700 J | 55000 | 7300 J |
| Butane | 51000 | 2600000 | 120000 | 6200000 |
| Isopentane | 51000 | 7800000 | 150000 | 23000000 |

eurofins | Air Toxics

**Client Sample ID: VMP-25-5-030613**

**Lab ID#: 1303140A-01A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p031816** | **Date of Collection: 3/6/13 9:55:00 AM** | |
| **Dil. Factor:** | **2.57** | **Date of Analysis: 3/18/13 07:30 PM** | |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 1.3 | 0.35 J | 6.4 | 1.7 J |
| Freon 114 | 1.3 | Not Detected | 9.0 | Not Detected |
| Chloromethane | 13 | Not Detected | 26 | Not Detected |
| Vinyl Chloride | 1.3 | Not Detected | 3.3 | Not Detected |
| 1,3-Butadiene | 1.3 | Not Detected | 2.8 | Not Detected |
| Bromomethane | 13 | Not Detected | 50 | Not Detected |
| Chloroethane | 5.1 | Not Detected | 14 | Not Detected |
| Freon 11 | 1.3 | 0.17 J | 7.2 | 0.96 J |
| Ethanol | 5.1 | 3.7 J | 9.7 | 6.9 J |
| Freon 113 | 1.3 | Not Detected | 9.8 | Not Detected |
| 1,1-Dichloroethene | 1.3 | Not Detected | 5.1 | Not Detected |
| Acetone | 13 | 7.4 J | 30 | 18 J |
| 2-Propanol | 5.1 | 8.8 | 13 | 22 |
| Carbon Disulfide | 5.1 | ~~0.84 J~~ U | 16 | ~~2.6 J~~ U |
| 3-Chloropropene | 5.1 | Not Detected | 16 | Not Detected |
| Methylene Chloride | 13 | ~~0.35 J~~ U | 45 | ~~1.2 J~~ U |
| Methyl tert-butyl ether | 1.3 | Not Detected | 4.6 | Not Detected |
| trans-1,2-Dichloroethene | 1.3 | Not Detected | 5.1 | Not Detected |
| Hexane | 1.3 | 0.65 J | 4.5 | 2.3 J |
| 1,1-Dichloroethane | 1.3 | Not Detected | 5.2 | Not Detected |
| 2-Butanone (Methyl Ethyl Ketone) | 5.1 | 1.8 J | 15 | 5.4 J |
| cis-1,2-Dichloroethene | 1.3 | Not Detected | 5.1 | Not Detected |
| Tetrahydrofuran | 1.3 | 0.27 J | 3.8 | 0.80 J |
| Chloroform | 1.3 | Not Detected | 6.3 | Not Detected |
| 1,1,1-Trichloroethane | 1.3 | Not Detected | 7.0 | Not Detected |
| Cyclohexane | 1.3 | 1.2 J J | 4.4 | 4.2 J J |
| Carbon Tetrachloride | 1.3 | Not Detected | 8.1 | Not Detected |
| 2,2,4-Trimethylpentane | 1.3 | 15 J J | 6.0 | 72 J J |
| Benzene | 1.3 | 1.5 | 4.1 | 4.8 |
| 1,2-Dichloroethane | 1.3 | Not Detected | 5.2 | Not Detected |
| Heptane | 1.3 | Not Detected | 5.3 | Not Detected |
| Trichloroethene | 1.3 | Not Detected | 6.9 | Not Detected |
| 1,2-Dichloropropane | 1.3 | Not Detected | 5.9 | Not Detected |
| 1,4-Dioxane | 5.1 | Not Detected | 18 | Not Detected |
| Bromodichloromethane | 1.3 | Not Detected | 8.6 | Not Detected |
| cis-1,3-Dichloropropene | 1.3 | Not Detected | 5.8 | Not Detected |
| 4-Methyl-2-pentanone | 1.3 | Not Detected | 5.3 | Not Detected |
| Toluene | 1.3 | 1.4 | 4.8 | 5.3 |
| trans-1,3-Dichloropropene | 1.3 | ~~0.33 J~~ U | 5.8 | ~~1.5 J~~ U |
| 1,1,2-Trichloroethane | 1.3 | Not Detected | 7.0 | Not Detected |
| Tetrachloroethene | 1.3 | ~~0.22 J~~ U | 8.7 | ~~1.5 J~~ U |
| 2-Hexanone | 5.1 | Not Detected | 21 | Not Detected |

eurofins | Air Toxics

**Client Sample ID: VMP-25-5-030613**

**Lab ID#: 1303140A-01A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p031816** | **Date of Collection: 3/6/13 9:55:00 AM** | |
| **Dil. Factor:** | **2.57** | **Date of Analysis: 3/18/13 07:30 PM** | |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Dibromochloromethane | 1.3 | Not Detected | 11 | Not Detected |
| 1,2-Dibromoethane (EDB) | 1.3 | Not Detected | 9.9 | Not Detected |
| Chlorobenzene | 1.3 | ~~0.16 J~~ U | 5.9 | ~~0.76 J~~ U |
| Ethyl Benzene | 1.3 | 0.53 J | 5.6 | 2.3 J |
| m,p-Xylene | 1.3 | Not Detected | 5.6 | Not Detected |
| o-Xylene | 1.3 | Not Detected | 5.6 | Not Detected |
| Styrene | 1.3 | Not Detected | 5.5 | Not Detected |
| Bromoform | 1.3 | Not Detected | 13 | Not Detected |
| Cumene | 1.3 | 0.54 J | 6.3 | 2.6 J |
| 1,1,2,2-Tetrachloroethane | 1.3 | Not Detected UJ | 8.8 | Not Detected UJ |
| Propylbenzene | 1.3 | 1.5 | 6.3 | 7.5 |
| 4-Ethyltoluene | 1.3 | 0.37 J | 6.3 | 1.8 J |
| 1,3,5-Trimethylbenzene | 1.3 | Not Detected | 6.3 | Not Detected |
| 1,2,4-Trimethylbenzene | 1.3 | 0.70 J | 6.3 | 3.4 J |
| 1,3-Dichlorobenzene | 1.3 | ~~0.40 J~~ U | 7.7 | ~~2.4 J~~ U |
| 1,4-Dichlorobenzene | 1.3 | ~~0.59 J~~ U | 7.7 | ~~3.5 J~~ U |
| alpha-Chlorotoluene | 1.3 | ~~0.28 J~~ U | 6.6 | ~~1.5 J~~ U |
| 1,2-Dichlorobenzene | 1.3 | ~~0.32 J~~ U | 7.7 | ~~1.9 J~~ U |
| 1,2,4-Trichlorobenzene | 5.1 | ~~1.1 J~~ U | 38 | ~~8.5 J~~ U |
| Hexachlorobutadiene | 5.1 | Not Detected | 55 | Not Detected |
| Butane | 5.1 | 6.5 | 12 | 16 |
| Isopentane | 5.1 | 9.8 | 15 | 29 |

J = Estimated value.
J = Estimated value due to bias in the CCV.
**Container Type: 1 Liter Summa Canister**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| Toluene-d8 | 97 | 70-130 |
| 1,2-Dichloroethane-d4 | 75 | 70-130 |
| 4-Bromofluorobenzene | 103 | 70-130 |

eurofins | Air Toxics

**Client Sample ID: VMP-25-21-030613** ✱ Use these results
**Lab ID#: 1303140A-02A** only. All other data was
**EPA METHOD TO-15 GC/MS FULL SCAN** reported from the 19200X dilution analysis.

| | | | |
|---|---|---|---|
| **File Name:** | **p031830** | **Date of Collection: 3/6/13 11:23:00 AM** | |
| **Dil. Factor:** | **48000** | **Date of Analysis: 3/19/13 12:42 PM** | |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 24000 | Not Detected | 120000 | Not Detected |
| Freon 114 | 24000 | Not Detected | 170000 | Not Detected |
| Chloromethane | 240000 | Not Detected | 500000 | Not Detected |
| Vinyl Chloride | 24000 | Not Detected | 61000 | Not Detected |
| 1,3-Butadiene | 24000 | Not Detected | 53000 | Not Detected |
| Bromomethane | 240000 | Not Detected | 930000 | Not Detected |
| Chloroethane | 96000 | Not Detected | 250000 | Not Detected |
| Freon 11 | 24000 | Not Detected | 130000 | Not Detected |
| Ethanol | 96000 | Not Detected | 180000 | Not Detected |
| Freon 113 | 24000 | Not Detected | 180000 | Not Detected |
| 1,1-Dichloroethene | 24000 | Not Detected | 95000 | Not Detected |
| Acetone | 240000 | 65000 J | 570000 | 150000 J |
| 2-Propanol | 96000 | Not Detected | 240000 | Not Detected |
| Carbon Disulfide | 96000 | 14000 J | 300000 | 44000 J |
| 3-Chloropropene | 96000 | Not Detected | 300000 | Not Detected |
| Methylene Chloride | 240000 | 15000 J | 830000 | 51000 J |
| Methyl tert-butyl ether | 24000 | Not Detected | 86000 | Not Detected |
| trans-1,2-Dichloroethene | 24000 | Not Detected | 95000 | Not Detected |
| Hexane | 24000 | 440000 | 84000 | 1500000 |
| 1,1-Dichloroethane | 24000 | 6700 J | 97000 | 27000 J |
| 2-Butanone (Methyl Ethyl Ketone) | 96000 | Not Detected | 280000 | Not Detected |
| cis-1,2-Dichloroethene | 24000 | Not Detected | 95000 | Not Detected |
| Tetrahydrofuran | 24000 | Not Detected | 71000 | Not Detected |
| Chloroform | 24000 | 10000 J | 120000 | 51000 J |
| 1,1,1-Trichloroethane | 24000 | Not Detected | 130000 | Not Detected |
| Cyclohexane | 24000 | 440000 J J | 83000 | 1500000 J J |
| Carbon Tetrachloride | 24000 | Not Detected | 150000 | Not Detected |
| 2,2,4-Trimethylpentane | 24000 | 49000 J J | 110000 | 230000 J J |
| Benzene | 24000 | 27000 | 77000 | 87000 |
| 1,2-Dichloroethane | 24000 | Not Detected | 97000 | Not Detected |
| Heptane | 24000 | 93000 | 98000 | 380000 |
| Trichloroethene | 24000 | Not Detected | 130000 | Not Detected |
| 1,2-Dichloropropane | 24000 | Not Detected | 110000 | Not Detected |
| 1,4-Dioxane | 96000 | Not Detected | 340000 | Not Detected |
| Bromodichloromethane | 24000 | Not Detected | 160000 | Not Detected |
| cis-1,3-Dichloropropene | 24000 | Not Detected | 110000 | Not Detected |
| 4-Methyl-2-pentanone | 24000 | Not Detected | 98000 | Not Detected |
| Toluene | 24000 | 23000 J | 90000 | 87000 J |
| trans-1,3-Dichloropropene | 24000 | Not Detected | 110000 | Not Detected |
| 1,1,2-Trichloroethane | 24000 | Not Detected | 130000 | Not Detected |
| Tetrachloroethene | 24000 | 7400 J | 160000 | 50000 J |
| 2-Hexanone | 96000 | Not Detected | 390000 | Not Detected |

eurofins | Air Toxics

**Client Sample ID: VMP-25-21-030613**

**Lab ID#: 1303140A-02A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p031830** | **Date of Collection: 3/6/13 11:23:00 AM** | |
| **Dil. Factor:** | **48000** | **Date of Analysis: 3/19/13 12:42 PM** | |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Dibromochloromethane | 24000 | Not Detected | 200000 | Not Detected |
| 1,2-Dibromoethane (EDB) | 24000 | Not Detected | 180000 | Not Detected |
| Chlorobenzene | 24000 | Not Detected | 110000 | Not Detected |
| Ethyl Benzene | 24000 | Not Detected | 100000 | Not Detected |
| m,p-Xylene | 24000 | Not Detected | 100000 | Not Detected |
| o-Xylene | 24000 | Not Detected | 100000 | Not Detected |
| Styrene | 24000 | Not Detected | 100000 | Not Detected |
| Bromoform | 24000 | Not Detected | 250000 | Not Detected |
| Cumene | 24000 | Not Detected | 120000 | Not Detected |
| 1,1,2,2-Tetrachloroethane | 24000 | Not Detected UJ | 160000 | Not Detected UJ |
| Propylbenzene | 24000 | Not Detected | 120000 | Not Detected |
| 4-Ethyltoluene | 24000 | Not Detected | 120000 | Not Detected |
| 1,3,5-Trimethylbenzene | 24000 | Not Detected | 120000 | Not Detected |
| 1,2,4-Trimethylbenzene | 24000 | Not Detected | 120000 | Not Detected |
| 1,3-Dichlorobenzene | 24000 | Not Detected | 140000 | Not Detected |
| 1,4-Dichlorobenzene | 24000 | Not Detected | 140000 | Not Detected |
| alpha-Chlorotoluene | 24000 | Not Detected | 120000 | Not Detected |
| 1,2-Dichlorobenzene | 24000 | Not Detected | 140000 | Not Detected |
| 1,2,4-Trichlorobenzene | 96000 | Not Detected | 710000 | Not Detected |
| Hexachlorobutadiene | 96000 | Not Detected | 1000000 | Not Detected |
| Butane | 96000 | 5000000 | 230000 | 12000000 |
| Isopentane | 96000 | 6900000 | 280000 | 20000000 |

J = Estimated value.
J = Estimated value due to bias in the CCV.
**Container Type: 1 Liter Summa Canister**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| Toluene-d8 | 95 | 70-130 |
| 1,2-Dichloroethane-d4 | 87 | 70-130 |
| 4-Bromofluorobenzene | 109 | 70-130 |

eurofins | Air Toxics

**Client Sample ID: VMP-25-21-030613** ** Do not use this
**Lab ID#: 1303140A-02B** data. Use all other
**EPA METHOD TO-15 GC/MS FULL SCAN** data.

| | | | |
|---|---|---|---|
| **File Name:** | **p031817** | **Date of Collection: 3/6/13 11:23:00 AM** | |
| **Dil. Factor:** | **19200** | **Date of Analysis: 3/18/13 08:21 PM** | |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 9600 | Not Detected | 47000 | Not Detected |
| Freon 114 | 9600 | Not Detected | 67000 | Not Detected |
| Chloromethane | 96000 | Not Detected | 200000 | Not Detected |
| Vinyl Chloride | 9600 | Not Detected | 24000 | Not Detected |
| 1,3-Butadiene | 9600 | Not Detected | 21000 | Not Detected |
| Bromomethane | 96000 | Not Detected | 370000 | Not Detected |
| Chloroethane | 38000 | Not Detected | 100000 | Not Detected |
| Freon 11 | 9600 | Not Detected | 54000 | Not Detected |
| Ethanol | 38000 | Not Detected | 72000 | Not Detected |
| Freon 113 | 9600 | Not Detected | 74000 | Not Detected |
| 1,1-Dichloroethene | 9600 | Not Detected | 38000 | Not Detected |
| Acetone | 96000 | Not Detected | 230000 | Not Detected |
| 2-Propanol | 38000 | Not Detected | 94000 | Not Detected |
| Carbon Disulfide | 38000 | 10000 J | 120000 | 31000 J |
| 3-Chloropropene | 38000 | Not Detected | 120000 | Not Detected |
| Methylene Chloride | 96000 | 2600 J | 330000 | 9100 J |
| Methyl tert-butyl ether | 9600 | Not Detected | 35000 | Not Detected |
| trans-1,2-Dichloroethene | 9600 | Not Detected | 38000 | Not Detected |
| Hexane | 9600 | 630000 | 34000 | 2200000 |
| 1,1-Dichloroethane | 9600 | 1900 J | 39000 | 7700 J |
| 2-Butanone (Methyl Ethyl Ketone) | 38000 | Not Detected | 110000 | Not Detected |
| cis-1,2-Dichloroethene | 9600 | Not Detected | 38000 | Not Detected |
| Tetrahydrofuran | 9600 | Not Detected | 28000 | Not Detected |
| Chloroform | 9600 | Not Detected | 47000 | Not Detected |
| 1,1,1-Trichloroethane | 9600 | Not Detected | 52000 | Not Detected |
| Cyclohexane | 9600 | 670000 J | 33000 | 2300000 J |
| Carbon Tetrachloride | 9600 | Not Detected | 60000 | Not Detected |
| 2,2,4-Trimethylpentane | 9600 | 85000 J | 45000 | 400000 J |
| Benzene | 9600 | 30000 | 31000 | 95000 |
| 1,2-Dichloroethane | 9600 | Not Detected | 39000 | Not Detected |
| Heptane | 9600 | 130000 | 39000 | 530000 |
| Trichloroethene | 9600 | Not Detected | 52000 | Not Detected |
| 1,2-Dichloropropane | 9600 | Not Detected | 44000 | Not Detected |
| 1,4-Dioxane | 38000 | Not Detected | 140000 | Not Detected |
| Bromodichloromethane | 9600 | Not Detected | 64000 | Not Detected |
| cis-1,3-Dichloropropene | 9600 | Not Detected | 44000 | Not Detected |
| 4-Methyl-2-pentanone | 9600 | Not Detected | 39000 | Not Detected |
| Toluene | 9600 | 1100 J | 36000 | 4200 J |
| trans-1,3-Dichloropropene | 9600 | Not Detected | 44000 | Not Detected |
| 1,1,2-Trichloroethane | 9600 | Not Detected | 52000 | Not Detected |
| Tetrachloroethene | 9600 | Not Detected | 65000 | Not Detected |
| 2-Hexanone | 38000 | Not Detected | 160000 | Not Detected |

eurofins | Air Toxics

**Client Sample ID: VMP-25-21-030613**

**Lab ID#: 1303140A-02B**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p031817** | **Date of Collection: 3/6/13 11:23:00 AM** | |
| **Dil. Factor:** | **19200** | **Date of Analysis: 3/18/13 08:21 PM** | |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Dibromochloromethane | 9600 | Not Detected | 82000 | Not Detected |
| 1,2-Dibromoethane (EDB) | 9600 | Not Detected | 74000 | Not Detected |
| Chlorobenzene | 9600 | Not Detected | 44000 | Not Detected |
| Ethyl Benzene | 9600 | Not Detected | 42000 | Not Detected |
| m,p-Xylene | 9600 | Not Detected | 42000 | Not Detected |
| o-Xylene | 9600 | Not Detected | 42000 | Not Detected |
| Styrene | 9600 | Not Detected | 41000 | Not Detected |
| Bromoform | 9600 | Not Detected | 99000 | Not Detected |
| Cumene | 9600 | Not Detected | 47000 | Not Detected |
| 1,1,2,2-Tetrachloroethane | 9600 | Not Detected | 66000 | Not Detected |
| Propylbenzene | 9600 | Not Detected | 47000 | Not Detected |
| 4-Ethyltoluene | 9600 | Not Detected | 47000 | Not Detected |
| 1,3,5-Trimethylbenzene | 9600 | Not Detected | 47000 | Not Detected |
| 1,2,4-Trimethylbenzene | 9600 | Not Detected | 47000 | Not Detected |
| 1,3-Dichlorobenzene | 9600 | Not Detected | 58000 | Not Detected |
| 1,4-Dichlorobenzene | 9600 | Not Detected | 58000 | Not Detected |
| alpha-Chlorotoluene | 9600 | Not Detected | 50000 | Not Detected |
| 1,2-Dichlorobenzene | 9600 | Not Detected | 58000 | Not Detected |
| 1,2,4-Trichlorobenzene | 38000 | Not Detected | 280000 | Not Detected |
| Hexachlorobutadiene | 38000 | Not Detected | 410000 | Not Detected |
| ~~Butane~~ | ~~38000~~ | ~~6300000 E~~ | ~~91000~~ | ~~15000000 E~~ |
| ~~Isopentane~~ | ~~38000~~ | ~~7100000 E~~ | ~~110000~~ | ~~21000000 E~~ |

J = Estimated value.
J = Estimated value due to bias in the CCV.
E = Exceeds instrument calibration range.
**Container Type: 1 Liter Summa Canister**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| Toluene-d8 | 105 | 70-130 |
| 1,2-Dichloroethane-d4 | 101 | 70-130 |
| 4-Bromofluorobenzene | 98 | 70-130 |

eurofins | Air Toxics

**Client Sample ID: VMP-25-31-030613**

**Lab ID#: 1303140A-03A**

**EPA METHOD TO-15 GC/MS**

| | | | |
|---|---|---|---|
| **File Name:** | **14031922** | **Date of Collection: 3/6/13 12:16:00 PM** | |
| **Dil. Factor:** | **2540** | **Date of Analysis: 3/19/13 07:20 PM** | |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 13000 | Not Detected | 63000 | Not Detected |
| Freon 114 | 13000 | Not Detected | 89000 | Not Detected |
| Chloromethane | 51000 | Not Detected | 100000 | Not Detected |
| Vinyl Chloride | 13000 | Not Detected | 32000 | Not Detected |
| 1,3-Butadiene | 13000 | Not Detected | 28000 | Not Detected |
| Bromomethane | 13000 | Not Detected | 49000 | Not Detected |
| Chloroethane | 51000 | 4200 J | 130000 | 11000 J |
| Freon 11 | 13000 | Not Detected | 71000 | Not Detected |
| Ethanol | 51000 | 8000 J | 96000 | 15000 J |
| Freon 113 | 13000 | Not Detected | 97000 | Not Detected |
| 1,1-Dichloroethene | 13000 | Not Detected | 50000 | Not Detected |
| Acetone | 51000 | Not Detected | 120000 | Not Detected |
| 2-Propanol | 51000 | 2300 J | 120000 | 5600 J |
| Carbon Disulfide | 13000 | Not Detected | 40000 | Not Detected |
| 3-Chloropropene | 51000 | Not Detected | 160000 | Not Detected |
| Methylene Chloride | 13000 | 8800 J | 44000 | 30000 J |
| Methyl tert-butyl ether | 13000 | 2000 J | 46000 | 7400 J |
| trans-1,2-Dichloroethene | 13000 | Not Detected | 50000 | Not Detected |
| Hexane | 13000 | 79000 | 45000 | 280000 |
| 1,1-Dichloroethane | 13000 | Not Detected | 51000 | Not Detected |
| 2-Butanone (Methyl Ethyl Ketone) | 51000 | Not Detected | 150000 | Not Detected |
| cis-1,2-Dichloroethene | 13000 | Not Detected | 50000 | Not Detected |
| Tetrahydrofuran | 13000 | Not Detected | 37000 | Not Detected |
| Chloroform | 13000 | 1500 J | 62000 | 7300 J |
| 1,1,1-Trichloroethane | 13000 | Not Detected | 69000 | Not Detected |
| Cyclohexane | 13000 | 170000 | 44000 | 580000 |
| Carbon Tetrachloride | 13000 | Not Detected | 80000 | Not Detected |
| 2,2,4-Trimethylpentane | 13000 | 210000 | 59000 | 990000 |
| Benzene | 13000 | 28000 | 40000 | 90000 |
| 1,2-Dichloroethane | 13000 | Not Detected | 51000 | Not Detected |
| Heptane | 13000 | 15000 | 52000 | 60000 |
| Trichloroethene | 13000 | 2100 J | 68000 | 11000 J |
| 1,2-Dichloropropane | 13000 | Not Detected | 59000 | Not Detected |
| 1,4-Dioxane | 51000 | Not Detected | 180000 | Not Detected |
| Bromodichloromethane | 13000 | Not Detected | 85000 | Not Detected |
| cis-1,3-Dichloropropene | 13000 | Not Detected | 58000 | Not Detected |
| 4-Methyl-2-pentanone | 13000 | Not Detected | 52000 | Not Detected |
| Toluene | 13000 | 3200 J | 48000 | 12000 J |
| trans-1,3-Dichloropropene | 13000 | Not Detected | 58000 | Not Detected |
| 1,1,2-Trichloroethane | 13000 | Not Detected | 69000 | Not Detected |
| Tetrachloroethene | 13000 | 1600 J | 86000 | 10000 J |
| 2-Hexanone | 51000 | Not Detected | 210000 | Not Detected |

**Client Sample ID: VMP-25-31-030613**

**Lab ID#: 1303140A-03A**

**EPA METHOD TO-15 GC/MS**

| | | | |
|---|---|---|---|
| **File Name:** | **14031922** | **Date of Collection: 3/6/13 12:16:00 PM** | |
| **Dil. Factor:** | **2540** | **Date of Analysis: 3/19/13 07:20 PM** | |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Dibromochloromethane | 13000 | Not Detected | 110000 | Not Detected |
| 1,2-Dibromoethane (EDB) | 13000 | Not Detected | 98000 | Not Detected |
| Chlorobenzene | 13000 | Not Detected | 58000 | Not Detected |
| Ethyl Benzene | 13000 | Not Detected | 55000 | Not Detected |
| m,p-Xylene | 13000 | 1600 J | 55000 | 7000 J |
| o-Xylene | 13000 | 1700 J | 55000 | 7300 J |
| Styrene | 13000 | Not Detected | 54000 | Not Detected |
| Bromoform | 13000 | Not Detected | 130000 | Not Detected |
| Cumene | 13000 | Not Detected | 62000 | Not Detected |
| 1,1,2,2-Tetrachloroethane | 13000 | Not Detected | 87000 | Not Detected |
| Propylbenzene | 13000 | Not Detected | 62000 | Not Detected |
| 4-Ethyltoluene | 13000 | Not Detected | 62000 | Not Detected |
| 1,3,5-Trimethylbenzene | 13000 | Not Detected | 62000 | Not Detected |
| 1,2,4-Trimethylbenzene | 13000 | Not Detected | 62000 | Not Detected |
| 1,3-Dichlorobenzene | 13000 | Not Detected | 76000 | Not Detected |
| 1,4-Dichlorobenzene | 13000 | Not Detected | 76000 | Not Detected |
| alpha-Chlorotoluene | 13000 | Not Detected | 66000 | Not Detected |
| 1,2-Dichlorobenzene | 13000 | Not Detected | 76000 | Not Detected |
| 1,2,4-Trichlorobenzene | 51000 | Not Detected | 380000 | Not Detected |
| Hexachlorobutadiene | 51000 | Not Detected | 540000 | Not Detected |
| Butane | 51000 | 2600000 | 120000 | 6200000 |
| Isopentane | 51000 | 7800000 | 150000 | 23000000 |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| 1,2-Dichloroethane-d4 | 102 | 70-130 |
| Toluene-d8 | 100 | 70-130 |
| 4-Bromofluorobenzene | 99 | 70-130 |

eurofins | Air Toxics

**Client Sample ID: Lab Blank**

**Lab ID#: 1303140A-04A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p031812d** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 3/18/13 04:45 PM** | |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 0.50 | Not Detected | 2.5 | Not Detected |
| Freon 114 | 0.50 | Not Detected | 3.5 | Not Detected |
| Chloromethane | 5.0 | Not Detected | 10 | Not Detected |
| Vinyl Chloride | 0.50 | Not Detected | 1.3 | Not Detected |
| 1,3-Butadiene | 0.50 | Not Detected | 1.1 | Not Detected |
| Bromomethane | 5.0 | Not Detected | 19 | Not Detected |
| Chloroethane | 2.0 | Not Detected | 5.3 | Not Detected |
| Freon 11 | 0.50 | Not Detected | 2.8 | Not Detected |
| Ethanol | 2.0 | Not Detected | 3.8 | Not Detected |
| Freon 113 | 0.50 | Not Detected | 3.8 | Not Detected |
| 1,1-Dichloroethene | 0.50 | Not Detected | 2.0 | Not Detected |
| Acetone | 5.0 | Not Detected | 12 | Not Detected |
| 2-Propanol | 2.0 | Not Detected | 4.9 | Not Detected |
| Carbon Disulfide | 2.0 | 0.44 J | 6.2 | 1.4 J |
| 3-Chloropropene | 2.0 | Not Detected | 6.3 | Not Detected |
| Methylene Chloride | 5.0 | 0.12 J | 17 | 0.44 J |
| Methyl tert-butyl ether | 0.50 | Not Detected | 1.8 | Not Detected |
| trans-1,2-Dichloroethene | 0.50 | Not Detected | 2.0 | Not Detected |
| Hexane | 0.50 | Not Detected | 1.8 | Not Detected |
| 1,1-Dichloroethane | 0.50 | Not Detected | 2.0 | Not Detected |
| 2-Butanone (Methyl Ethyl Ketone) | 2.0 | Not Detected | 5.9 | Not Detected |
| cis-1,2-Dichloroethene | 0.50 | Not Detected | 2.0 | Not Detected |
| Tetrahydrofuran | 0.50 | Not Detected | 1.5 | Not Detected |
| Chloroform | 0.50 | Not Detected | 2.4 | Not Detected |
| 1,1,1-Trichloroethane | 0.50 | Not Detected | 2.7 | Not Detected |
| Cyclohexane | 0.50 | Not Detected | 1.7 | Not Detected |
| Carbon Tetrachloride | 0.50 | Not Detected | 3.1 | Not Detected |
| 2,2,4-Trimethylpentane | 0.50 | Not Detected | 2.3 | Not Detected |
| Benzene | 0.50 | Not Detected | 1.6 | Not Detected |
| 1,2-Dichloroethane | 0.50 | Not Detected | 2.0 | Not Detected |
| Heptane | 0.50 | Not Detected | 2.0 | Not Detected |
| Trichloroethene | 0.50 | Not Detected | 2.7 | Not Detected |
| 1,2-Dichloropropane | 0.50 | Not Detected | 2.3 | Not Detected |
| 1,4-Dioxane | 2.0 | Not Detected | 7.2 | Not Detected |
| Bromodichloromethane | 0.50 | Not Detected | 3.4 | Not Detected |
| cis-1,3-Dichloropropene | 0.50 | Not Detected | 2.3 | Not Detected |
| 4-Methyl-2-pentanone | 0.50 | Not Detected | 2.0 | Not Detected |
| Toluene | 0.50 | Not Detected | 1.9 | Not Detected |
| trans-1,3-Dichloropropene | 0.50 | 0.14 J | 2.3 | 0.63 J |
| 1,1,2-Trichloroethane | 0.50 | Not Detected | 2.7 | Not Detected |
| Tetrachloroethene | 0.50 | 0.074 J | 3.4 | 0.50 J |
| 2-Hexanone | 2.0 | Not Detected | 8.2 | Not Detected |

eurofins | Air Toxics

**Client Sample ID: Lab Blank**

**Lab ID#: 1303140A-04A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p031812d** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 3/18/13 04:45 PM** | |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Dibromochloromethane | 0.50 | Not Detected | 4.2 | Not Detected |
| 1,2-Dibromoethane (EDB) | 0.50 | Not Detected | 3.8 | Not Detected |
| Chlorobenzene | 0.50 | 0.095 J | 2.3 | 0.44 J |
| Ethyl Benzene | 0.50 | Not Detected | 2.2 | Not Detected |
| m,p-Xylene | 0.50 | Not Detected | 2.2 | Not Detected |
| o-Xylene | 0.50 | Not Detected | 2.2 | Not Detected |
| Styrene | 0.50 | Not Detected | 2.1 | Not Detected |
| Bromoform | 0.50 | Not Detected | 5.2 | Not Detected |
| Cumene | 0.50 | Not Detected | 2.4 | Not Detected |
| 1,1,2,2-Tetrachloroethane | 0.50 | Not Detected | 3.4 | Not Detected |
| Propylbenzene | 0.50 | 0.072 J | 2.4 | 0.35 J |
| 4-Ethyltoluene | 0.50 | 0.040 J | 2.4 | 0.19 J |
| 1,3,5-Trimethylbenzene | 0.50 | 0.10 J | 2.4 | 0.51 J |
| 1,2,4-Trimethylbenzene | 0.50 | Not Detected | 2.4 | Not Detected |
| 1,3-Dichlorobenzene | 0.50 | 0.24 J | 3.0 | 1.4 J |
| 1,4-Dichlorobenzene | 0.50 | 0.26 J | 3.0 | 1.6 J |
| alpha-Chlorotoluene | 0.50 | 0.13 J | 2.6 | 0.70 J |
| 1,2-Dichlorobenzene | 0.50 | 0.21 J | 3.0 | 1.3 J |
| 1,2,4-Trichlorobenzene | 2.0 | 0.91 J | 15 | 6.8 J |
| Hexachlorobutadiene | 2.0 | 0.36 J | 21 | 3.8 J |
| Butane | 2.0 | Not Detected | 4.8 | Not Detected |
| Isopentane | 2.0 | Not Detected | 5.9 | Not Detected |

J = Estimated value.

**Container Type: NA - Not Applicable**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| Toluene-d8 | 96 | 70-130 |
| 1,2-Dichloroethane-d4 | 84 | 70-130 |
| 4-Bromofluorobenzene | 96 | 70-130 |

eurofins | Air Toxics

**Client Sample ID: Lab Blank**

**Lab ID#: 1303140A-04B**

**EPA METHOD TO-15 GC/MS**

| | | | |
|---|---|---|---|
| **File Name:** | **14031920a** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 3/19/13 06:01 PM** | |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Freon 12 | 5.0 | Not Detected | 25 | Not Detected |
| Freon 114 | 5.0 | Not Detected | 35 | Not Detected |
| Chloromethane | 20 | Not Detected | 41 | Not Detected |
| Vinyl Chloride | 5.0 | Not Detected | 13 | Not Detected |
| 1,3-Butadiene | 5.0 | Not Detected | 11 | Not Detected |
| Bromomethane | 5.0 | Not Detected | 19 | Not Detected |
| Chloroethane | 20 | Not Detected | 53 | Not Detected |
| Freon 11 | 5.0 | Not Detected | 28 | Not Detected |
| Ethanol | 20 | 8.9 J | 38 | 17 J |
| Freon 113 | 5.0 | Not Detected | 38 | Not Detected |
| 1,1-Dichloroethene | 5.0 | Not Detected | 20 | Not Detected |
| Acetone | 20 | Not Detected | 48 | Not Detected |
| 2-Propanol | 20 | Not Detected | 49 | Not Detected |
| Carbon Disulfide | 5.0 | Not Detected | 16 | Not Detected |
| 3-Chloropropene | 20 | Not Detected | 63 | Not Detected |
| Methylene Chloride | 5.0 | 1.5 J | 17 | 5.1 J |
| Methyl tert-butyl ether | 5.0 | Not Detected | 18 | Not Detected |
| trans-1,2-Dichloroethene | 5.0 | Not Detected | 20 | Not Detected |
| Hexane | 5.0 | Not Detected | 18 | Not Detected |
| 1,1-Dichloroethane | 5.0 | Not Detected | 20 | Not Detected |
| 2-Butanone (Methyl Ethyl Ketone) | 20 | Not Detected | 59 | Not Detected |
| cis-1,2-Dichloroethene | 5.0 | Not Detected | 20 | Not Detected |
| Tetrahydrofuran | 5.0 | Not Detected | 15 | Not Detected |
| Chloroform | 5.0 | Not Detected | 24 | Not Detected |
| 1,1,1-Trichloroethane | 5.0 | Not Detected | 27 | Not Detected |
| Cyclohexane | 5.0 | Not Detected | 17 | Not Detected |
| Carbon Tetrachloride | 5.0 | Not Detected | 31 | Not Detected |
| 2,2,4-Trimethylpentane | 5.0 | Not Detected | 23 | Not Detected |
| Benzene | 5.0 | Not Detected | 16 | Not Detected |
| 1,2-Dichloroethane | 5.0 | Not Detected | 20 | Not Detected |
| Heptane | 5.0 | Not Detected | 20 | Not Detected |
| Trichloroethene | 5.0 | Not Detected | 27 | Not Detected |
| 1,2-Dichloropropane | 5.0 | Not Detected | 23 | Not Detected |
| 1,4-Dioxane | 20 | Not Detected | 72 | Not Detected |
| Bromodichloromethane | 5.0 | Not Detected | 34 | Not Detected |
| cis-1,3-Dichloropropene | 5.0 | Not Detected | 23 | Not Detected |
| 4-Methyl-2-pentanone | 5.0 | Not Detected | 20 | Not Detected |
| Toluene | 5.0 | Not Detected | 19 | Not Detected |
| trans-1,3-Dichloropropene | 5.0 | Not Detected | 23 | Not Detected |
| 1,1,2-Trichloroethane | 5.0 | Not Detected | 27 | Not Detected |
| Tetrachloroethene | 5.0 | Not Detected | 34 | Not Detected |
| 2-Hexanone | 20 | Not Detected | 82 | Not Detected |

**Client Sample ID: Lab Blank**

**Lab ID#: 1303140A-04B**

**EPA METHOD TO-15 GC/MS**

| | | | |
|---|---|---|---|
| **File Name:** | **14031920a** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 3/19/13 06:01 PM** | |

| Compound | Rpt. Limit (ppbv) | Amount (ppbv) | Rpt. Limit (ug/m3) | Amount (ug/m3) |
|---|---|---|---|---|
| Dibromochloromethane | 5.0 | Not Detected | 42 | Not Detected |
| 1,2-Dibromoethane (EDB) | 5.0 | Not Detected | 38 | Not Detected |
| Chlorobenzene | 5.0 | Not Detected | 23 | Not Detected |
| Ethyl Benzene | 5.0 | Not Detected | 22 | Not Detected |
| m,p-Xylene | 5.0 | Not Detected | 22 | Not Detected |
| o-Xylene | 5.0 | Not Detected | 22 | Not Detected |
| Styrene | 5.0 | Not Detected | 21 | Not Detected |
| Bromoform | 5.0 | Not Detected | 52 | Not Detected |
| Cumene | 5.0 | Not Detected | 24 | Not Detected |
| 1,1,2,2-Tetrachloroethane | 5.0 | Not Detected | 34 | Not Detected |
| Propylbenzene | 5.0 | Not Detected | 24 | Not Detected |
| 4-Ethyltoluene | 5.0 | Not Detected | 24 | Not Detected |
| 1,3,5-Trimethylbenzene | 5.0 | Not Detected | 24 | Not Detected |
| 1,2,4-Trimethylbenzene | 5.0 | Not Detected | 24 | Not Detected |
| 1,3-Dichlorobenzene | 5.0 | Not Detected | 30 | Not Detected |
| 1,4-Dichlorobenzene | 5.0 | Not Detected | 30 | Not Detected |
| alpha-Chlorotoluene | 5.0 | Not Detected | 26 | Not Detected |
| 1,2-Dichlorobenzene | 5.0 | Not Detected | 30 | Not Detected |
| 1,2,4-Trichlorobenzene | 20 | Not Detected | 150 | Not Detected |
| Hexachlorobutadiene | 20 | Not Detected | 210 | Not Detected |
| Butane | 20 | Not Detected | 48 | Not Detected |
| Isopentane | 20 | Not Detected | 59 | Not Detected |

J = Estimated value.

**Container Type: NA - Not Applicable**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| 1,2-Dichloroethane-d4 | 100 | 70-130 |
| Toluene-d8 | 100 | 70-130 |
| 4-Bromofluorobenzene | 99 | 70-130 |

**Client Sample ID: CCV**

**Lab ID#: 1303140A-05A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p031808** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 3/18/13 01:58 PM** | |

| Compound | %Recovery |
|---|---|
| Freon 12 | 97 |
| Freon 114 | 110 |
| Chloromethane | 104 |
| Vinyl Chloride | 110 |
| 1,3-Butadiene | 95 |
| Bromomethane | 102 |
| Chloroethane | 96 |
| Freon 11 | 91 |
| Ethanol | 103 |
| Freon 113 | 98 |
| 1,1-Dichloroethene | 104 |
| Acetone | 95 |
| 2-Propanol | 95 |
| Carbon Disulfide | 95 |
| 3-Chloropropene | 102 |
| Methylene Chloride | 90 |
| Methyl tert-butyl ether | 103 |
| trans-1,2-Dichloroethene | 103 |
| Hexane | 103 |
| 1,1-Dichloroethane | 93 |
| 2-Butanone (Methyl Ethyl Ketone) | 101 |
| cis-1,2-Dichloroethene | 109 |
| Tetrahydrofuran | 101 |
| Chloroform | 93 |
| 1,1,1-Trichloroethane | 97 |
| Cyclohexane | 114 |
| Carbon Tetrachloride | 111 |
| 2,2,4-Trimethylpentane | 136 Q |
| Benzene | 127 |
| 1,2-Dichloroethane | 100 |
| Heptane | 112 |
| Trichloroethene | 82 |
| 1,2-Dichloropropane | 96 |
| 1,4-Dioxane | 110 |
| Bromodichloromethane | 90 |
| cis-1,3-Dichloropropene | 105 |
| 4-Methyl-2-pentanone | 110 |
| Toluene | 99 |
| trans-1,3-Dichloropropene | 82 |
| 1,1,2-Trichloroethane | 78 |
| Tetrachloroethene | 78 |
| 2-Hexanone | 105 |

eurofins | Air Toxics

**Client Sample ID: CCV**

**Lab ID#: 1303140A-05A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p031808** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 3/18/13 01:58 PM** | |

| Compound | %Recovery |
|---|---|
| Dibromochloromethane | 97 |
| 1,2-Dibromoethane (EDB) | 102 |
| Chlorobenzene | 97 |
| Ethyl Benzene | 107 |
| m,p-Xylene | 110 |
| o-Xylene | 92 |
| Styrene | 94 |
| Bromoform | 81 |
| Cumene | 88 |
| 1,1,2,2-Tetrachloroethane | 85 |
| Propylbenzene | 82 |
| 4-Ethyltoluene | 88 |
| 1,3,5-Trimethylbenzene | 90 |
| 1,2,4-Trimethylbenzene | 90 |
| 1,3-Dichlorobenzene | 81 |
| 1,4-Dichlorobenzene | 82 |
| alpha-Chlorotoluene | 86 |
| 1,2-Dichlorobenzene | 83 |
| 1,2,4-Trichlorobenzene | 85 |
| Hexachlorobutadiene | 81 |
| Butane | 113 |
| Isopentane | 93 |

Q = Exceeds Quality Control limits.

**Container Type: NA - Not Applicable**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| Toluene-d8 | 99 | 70-130 |
| 1,2-Dichloroethane-d4 | 108 | 70-130 |
| 4-Bromofluorobenzene | 78 | 70-130 |

**Client Sample ID: CCV**
**Lab ID#: 1303140A-05B**
**EPA METHOD TO-15 GC/MS**

| | | | |
|---|---|---|---|
| **File Name:** | **14031908a** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 3/19/13 12:04 PM** | |

| Compound | %Recovery |
|---|---|
| Freon 12 | 100 |
| Freon 114 | 104 |
| Chloromethane | 100 |
| Vinyl Chloride | 101 |
| 1,3-Butadiene | 106 |
| Bromomethane | 98 |
| Chloroethane | 95 |
| Freon 11 | 102 |
| Ethanol | 105 |
| Freon 113 | 96 |
| 1,1-Dichloroethene | 100 |
| Acetone | 102 |
| 2-Propanol | 98 |
| Carbon Disulfide | 93 |
| 3-Chloropropene | 98 |
| Methylene Chloride | 95 |
| Methyl tert-butyl ether | 100 |
| trans-1,2-Dichloroethene | 100 |
| Hexane | 96 |
| 1,1-Dichloroethane | 98 |
| 2-Butanone (Methyl Ethyl Ketone) | 101 |
| cis-1,2-Dichloroethene | 94 |
| Tetrahydrofuran | 97 |
| Chloroform | 98 |
| 1,1,1-Trichloroethane | 98 |
| Cyclohexane | 98 |
| Carbon Tetrachloride | 99 |
| 2,2,4-Trimethylpentane | 98 |
| Benzene | 96 |
| 1,2-Dichloroethane | 100 |
| Heptane | 99 |
| Trichloroethene | 98 |
| 1,2-Dichloropropane | 96 |
| 1,4-Dioxane | 102 |
| Bromodichloromethane | 98 |
| cis-1,3-Dichloropropene | 100 |
| 4-Methyl-2-pentanone | 104 |
| Toluene | 98 |
| trans-1,3-Dichloropropene | 98 |
| 1,1,2-Trichloroethane | 100 |
| Tetrachloroethene | 102 |
| 2-Hexanone | 97 |

eurofins | Air Toxics

**Client Sample ID: CCV**
**Lab ID#: 1303140A-05B**
**EPA METHOD TO-15 GC/MS**

| | | | |
|---|---|---|---|
| **File Name:** | **14031908a** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 3/19/13 12:04 PM** | |

| Compound | %Recovery |
|---|---|
| Dibromochloromethane | 101 |
| 1,2-Dibromoethane (EDB) | 100 |
| Chlorobenzene | 101 |
| Ethyl Benzene | 101 |
| m,p-Xylene | 101 |
| o-Xylene | 100 |
| Styrene | 101 |
| Bromoform | 104 |
| Cumene | 102 |
| 1,1,2,2-Tetrachloroethane | 97 |
| Propylbenzene | 103 |
| 4-Ethyltoluene | 104 |
| 1,3,5-Trimethylbenzene | 99 |
| 1,2,4-Trimethylbenzene | 97 |
| 1,3-Dichlorobenzene | 100 |
| 1,4-Dichlorobenzene | 100 |
| alpha-Chlorotoluene | 100 |
| 1,2-Dichlorobenzene | 98 |
| 1,2,4-Trichlorobenzene | 111 |
| Hexachlorobutadiene | 119 |
| Butane | 88 |
| Isopentane | 96 |

**Container Type: NA - Not Applicable**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| 1,2-Dichloroethane-d4 | 96 | 70-130 |
| Toluene-d8 | 100 | 70-130 |
| 4-Bromofluorobenzene | 102 | 70-130 |

eurofins | Air Toxics

**Client Sample ID: LCS**

**Lab ID#: 1303140A-06A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p031809** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 3/18/13 02:51 PM** | |

| Compound | %Recovery |
|---|---|
| Freon 12 | 94 |
| Freon 114 | 116 |
| Chloromethane | 116 |
| Vinyl Chloride | 118 |
| 1,3-Butadiene | 99 |
| Bromomethane | 102 |
| Chloroethane | 100 |
| Freon 11 | 92 |
| Ethanol | 77 |
| Freon 113 | 100 |
| 1,1-Dichloroethene | 111 |
| Acetone | 99 |
| 2-Propanol | 101 |
| Carbon Disulfide | 119 |
| 3-Chloropropene | 122 |
| Methylene Chloride | 92 |
| Methyl tert-butyl ether | 108 |
| trans-1,2-Dichloroethene | 121 |
| Hexane | 104 |
| 1,1-Dichloroethane | 96 |
| 2-Butanone (Methyl Ethyl Ketone) | 106 |
| cis-1,2-Dichloroethene | 112 |
| Tetrahydrofuran | 101 |
| Chloroform | 96 |
| 1,1,1-Trichloroethane | 121 |
| Cyclohexane | 155 Q |
| Carbon Tetrachloride | 109 |
| 2,2,4-Trimethylpentane | 131 Q |
| Benzene | 122 |
| 1,2-Dichloroethane | 97 |
| Heptane | 121 |
| Trichloroethene | 106 |
| 1,2-Dichloropropane | 99 |
| 1,4-Dioxane | 110 |
| Bromodichloromethane | 92 |
| cis-1,3-Dichloropropene | 106 |
| 4-Methyl-2-pentanone | 110 |
| Toluene | 101 |
| trans-1,3-Dichloropropene | 82 |
| 1,1,2-Trichloroethane | 79 |
| Tetrachloroethene | 79 |
| 2-Hexanone | 83 |

eurofins | Air Toxics

**Client Sample ID: LCS**

**Lab ID#: 1303140A-06A**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p031809** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 3/18/13 02:51 PM** | |

| Compound | %Recovery |
|---|---|
| Dibromochloromethane | 80 |
| 1,2-Dibromoethane (EDB) | 82 |
| Chlorobenzene | 100 |
| Ethyl Benzene | 106 |
| m,p-Xylene | 109 |
| o-Xylene | 111 |
| Styrene | 114 |
| Bromoform | 87 |
| Cumene | 91 |
| 1,1,2,2-Tetrachloroethane | 65 Q |
| Propylbenzene | 86 |
| 4-Ethyltoluene | 88 |
| 1,3,5-Trimethylbenzene | 93 |
| 1,2,4-Trimethylbenzene | 92 |
| 1,3-Dichlorobenzene | 85 |
| 1,4-Dichlorobenzene | 83 |
| alpha-Chlorotoluene | 88 |
| 1,2-Dichlorobenzene | 86 |
| 1,2,4-Trichlorobenzene | 93 |
| Hexachlorobutadiene | 84 |
| Butane | 114 |
| Isopentane | 98 |

Q = Exceeds Quality Control limits.

**Container Type: NA - Not Applicable**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| Toluene-d8 | 100 | 70-130 |
| 1,2-Dichloroethane-d4 | 100 | 70-130 |
| 4-Bromofluorobenzene | 80 | 70-130 |

eurofins | Air Toxics

**Client Sample ID: LCSD**

**Lab ID#: 1303140A-06AA**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p031810** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 3/18/13 03:22 PM** | |

| Compound | %Recovery |
|---|---|
| Freon 12 | 98 |
| Freon 114 | 113 |
| Chloromethane | 107 |
| Vinyl Chloride | 129 |
| 1,3-Butadiene | 121 |
| Bromomethane | 102 |
| Chloroethane | 96 |
| Freon 11 | 88 |
| Ethanol | 74 |
| Freon 113 | 98 |
| 1,1-Dichloroethene | 108 |
| Acetone | 97 |
| 2-Propanol | 97 |
| Carbon Disulfide | 118 |
| 3-Chloropropene | 120 |
| Methylene Chloride | 90 |
| Methyl tert-butyl ether | 105 |
| trans-1,2-Dichloroethene | 116 |
| Hexane | 103 |
| 1,1-Dichloroethane | 93 |
| 2-Butanone (Methyl Ethyl Ketone) | 123 |
| cis-1,2-Dichloroethene | 132 Q |
| Tetrahydrofuran | 101 |
| Chloroform | 93 |
| 1,1,1-Trichloroethane | 95 |
| Cyclohexane | 116 |
| Carbon Tetrachloride | 93 |
| 2,2,4-Trimethylpentane | 105 |
| Benzene | 101 |
| 1,2-Dichloroethane | 84 |
| Heptane | 109 |
| Trichloroethene | 104 |
| 1,2-Dichloropropane | 97 |
| 1,4-Dioxane | 109 |
| Bromodichloromethane | 90 |
| cis-1,3-Dichloropropene | 105 |
| 4-Methyl-2-pentanone | 112 |
| Toluene | 99 |
| trans-1,3-Dichloropropene | 80 |
| 1,1,2-Trichloroethane | 77 |
| Tetrachloroethene | 78 |
| 2-Hexanone | 80 |

**Client Sample ID: LCSD**

**Lab ID#: 1303140A-06AA**

**EPA METHOD TO-15 GC/MS FULL SCAN**

| | | | |
|---|---|---|---|
| **File Name:** | **p031810** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 3/18/13 03:22 PM** | |

| Compound | %Recovery |
|---|---|
| Dibromochloromethane | 94 |
| 1,2-Dibromoethane (EDB) | 93 |
| Chlorobenzene | 99 |
| Ethyl Benzene | 108 |
| m,p-Xylene | 115 |
| o-Xylene | 113 |
| Styrene | 118 |
| Bromoform | 94 |
| Cumene | 104 |
| 1,1,2,2-Tetrachloroethane | 70 |
| Propylbenzene | 89 |
| 4-Ethyltoluene | 85 |
| 1,3,5-Trimethylbenzene | 90 |
| 1,2,4-Trimethylbenzene | 90 |
| 1,3-Dichlorobenzene | 83 |
| 1,4-Dichlorobenzene | 82 |
| alpha-Chlorotoluene | 85 |
| 1,2-Dichlorobenzene | 84 |
| 1,2,4-Trichlorobenzene | 90 |
| Hexachlorobutadiene | 82 |
| Butane | 114 |
| Isopentane | 93 |

Q = Exceeds Quality Control limits.

**Container Type: NA - Not Applicable**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| Toluene-d8 | 98 | 70-130 |
| 1,2-Dichloroethane-d4 | 84 | 70-130 |
| 4-Bromofluorobenzene | 95 | 70-130 |

**Client Sample ID: LCS**

**Lab ID#: 1303140A-06B**

**EPA METHOD TO-15 GC/MS**

| | | | |
|---|---|---|---|
| **File Name:** | **14031917e** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 3/19/13 03:51 PM** | |

| Compound | %Recovery |
|---|---|
| Freon 12 | 93 |
| Freon 114 | 95 |
| Chloromethane | 96 |
| Vinyl Chloride | 92 |
| 1,3-Butadiene | 97 |
| Bromomethane | 89 |
| Chloroethane | 87 |
| Freon 11 | 93 |
| Ethanol | 92 |
| Freon 113 | 89 |
| 1,1-Dichloroethene | 98 |
| Acetone | 87 |
| 2-Propanol | 87 |
| Carbon Disulfide | 104 |
| 3-Chloropropene | 97 |
| Methylene Chloride | 87 |
| Methyl tert-butyl ether | 89 |
| trans-1,2-Dichloroethene | 103 |
| Hexane | 86 |
| 1,1-Dichloroethane | 90 |
| 2-Butanone (Methyl Ethyl Ketone) | 93 |
| cis-1,2-Dichloroethene | 88 |
| Tetrahydrofuran | 86 |
| Chloroform | 91 |
| 1,1,1-Trichloroethane | 90 |
| Cyclohexane | 90 |
| Carbon Tetrachloride | 94 |
| 2,2,4-Trimethylpentane | 88 |
| Benzene | 88 |
| 1,2-Dichloroethane | 90 |
| Heptane | 89 |
| Trichloroethene | 89 |
| 1,2-Dichloropropane | 88 |
| 1,4-Dioxane | 91 |
| Bromodichloromethane | 88 |
| cis-1,3-Dichloropropene | 88 |
| 4-Methyl-2-pentanone | 92 |
| Toluene | 89 |
| trans-1,3-Dichloropropene | 85 |
| 1,1,2-Trichloroethane | 92 |
| Tetrachloroethene | 91 |
| 2-Hexanone | 91 |

eurofins | Air Toxics

**Client Sample ID: LCS**

**Lab ID#: 1303140A-06B**

**EPA METHOD TO-15 GC/MS**

| | | | |
|---|---|---|---|
| **File Name:** | **14031917e** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 3/19/13 03:51 PM** | |

| Compound | %Recovery |
|---|---|
| Dibromochloromethane | 90 |
| 1,2-Dibromoethane (EDB) | 93 |
| Chlorobenzene | 92 |
| Ethyl Benzene | 91 |
| m,p-Xylene | 93 |
| o-Xylene | 92 |
| Styrene | 96 |
| Bromoform | 91 |
| Cumene | 94 |
| 1,1,2,2-Tetrachloroethane | 92 |
| Propylbenzene | 96 |
| 4-Ethyltoluene | 94 |
| 1,3,5-Trimethylbenzene | 93 |
| 1,2,4-Trimethylbenzene | 90 |
| 1,3-Dichlorobenzene | 94 |
| 1,4-Dichlorobenzene | 94 |
| alpha-Chlorotoluene | 84 |
| 1,2-Dichlorobenzene | 93 |
| 1,2,4-Trichlorobenzene | 108 |
| Hexachlorobutadiene | 96 |
| Butane | 82 |
| Isopentane | 87 |

**Container Type: NA - Not Applicable**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| 1,2-Dichloroethane-d4 | 98 | 70-130 |
| Toluene-d8 | 100 | 70-130 |
| 4-Bromofluorobenzene | 99 | 70-130 |

eurofins | Air Toxics

**Client Sample ID: LCSD**

**Lab ID#: 1303140A-06BB**

**EPA METHOD TO-15 GC/MS**

| | | | |
|---|---|---|---|
| **File Name:** | **14031918** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 3/19/13 04:20 PM** | |

| Compound | %Recovery |
|---|---|
| Freon 12 | 93 |
| Freon 114 | 95 |
| Chloromethane | 97 |
| Vinyl Chloride | 93 |
| 1,3-Butadiene | 97 |
| Bromomethane | 89 |
| Chloroethane | 86 |
| Freon 11 | 92 |
| Ethanol | 96 |
| Freon 113 | 89 |
| 1,1-Dichloroethene | 98 |
| Acetone | 86 |
| 2-Propanol | 89 |
| Carbon Disulfide | 104 |
| 3-Chloropropene | 95 |
| Methylene Chloride | 89 |
| Methyl tert-butyl ether | 90 |
| trans-1,2-Dichloroethene | 104 |
| Hexane | 87 |
| 1,1-Dichloroethane | 90 |
| 2-Butanone (Methyl Ethyl Ketone) | 91 |
| cis-1,2-Dichloroethene | 87 |
| Tetrahydrofuran | 87 |
| Chloroform | 91 |
| 1,1,1-Trichloroethane | 90 |
| Cyclohexane | 91 |
| Carbon Tetrachloride | 92 |
| 2,2,4-Trimethylpentane | 88 |
| Benzene | 89 |
| 1,2-Dichloroethane | 90 |
| Heptane | 88 |
| Trichloroethene | 91 |
| 1,2-Dichloropropane | 88 |
| 1,4-Dioxane | 90 |
| Bromodichloromethane | 90 |
| cis-1,3-Dichloropropene | 88 |
| 4-Methyl-2-pentanone | 94 |
| Toluene | 88 |
| trans-1,3-Dichloropropene | 86 |
| 1,1,2-Trichloroethane | 90 |
| Tetrachloroethene | 91 |
| 2-Hexanone | 91 |

eurofins | Air Toxics

**Client Sample ID: LCSD**

**Lab ID#: 1303140A-06BB**

**EPA METHOD TO-15 GC/MS**

| | | | |
|---|---|---|---|
| **File Name:** | **14031918** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 3/19/13 04:20 PM** | |

| Compound | %Recovery |
|---|---|
| Dibromochloromethane | 91 |
| 1,2-Dibromoethane (EDB) | 92 |
| Chlorobenzene | 92 |
| Ethyl Benzene | 91 |
| m,p-Xylene | 92 |
| o-Xylene | 93 |
| Styrene | 94 |
| Bromoform | 91 |
| Cumene | 94 |
| 1,1,2,2-Tetrachloroethane | 92 |
| Propylbenzene | 97 |
| 4-Ethyltoluene | 93 |
| 1,3,5-Trimethylbenzene | 92 |
| 1,2,4-Trimethylbenzene | 89 |
| 1,3-Dichlorobenzene | 93 |
| 1,4-Dichlorobenzene | 93 |
| alpha-Chlorotoluene | 88 |
| 1,2-Dichlorobenzene | 94 |
| 1,2,4-Trichlorobenzene | 111 |
| Hexachlorobutadiene | 100 |
| Butane | 74 |
| Isopentane | 89 |

**Container Type: NA - Not Applicable**

| Surrogates | %Recovery | Method Limits |
|---|---|---|
| 1,2-Dichloroethane-d4 | 98 | 70-130 |
| Toluene-d8 | 101 | 70-130 |
| 4-Bromofluorobenzene | 99 | 70-130 |

1303140

# Shell Oil Products Chain Of Custody Record

URS

Air Toxics LTD.
**Project Name: Roxana Soil Vapor**
**Project # 21562850.04001**
Lab Vendor #

Please Check Appropriate Box:
☑ ENV. SERVICES ☐ MOTIVA RETAIL ☐ SHELL RETAIL
☐ MOTIVA SD&CM ☐ CONSULTANT ☐ LUBES
☐ SHELL PIPELINE ☐ OTHER _____

Print Bill To Contact Name: Robert Moosheglan

INCIDENT # (ENV SERVICES): 9 7 2 1 6 6 4 0 ☐ CHECK IF NO INCIDENT # APPLIES

PO #:

SAP #: 3 4 0 0 6 1

DATE: 03/06/13

PAGE: 1 of 1

SAMPLING COMPANY: URS CORPORATION

LOG CODE:

SITE ADDRESS: Street and City: 900 SOUTH CENTRAL AVE – ROXANA

State: IL

GLOBAL ID NO.:

ADDRESS: 1001 HIGHLANDS PLAZA DRIVE WEST - SUITE 300, ST LOUIS, MO 63110

EDF DELIVERABLE TO (Name, Company, Office Location): Elizabeth Kunkel, URS, St. Louis

PHONE NO.: 314-743-4179

E-MAIL: Elizabeth_Kunkel@URSCorp.com

CONSULTANT PROJECT MANAGER: Roxana Soil Vapor

Laboratory Address: Air Toxics, LTD 180 Blue Ravine Road, Suite B, Folsom, CA 95630-4719

TELEPHONE:

FAX: 314-429-0462

EDF To Contact E-MAIL: Robert.Moosheglan@urs.com

E. Arthur, M. Corbett

TURNAROUND TIME (CALENDAR DAYS)
☑ STANDARD (14 DAY) ☐ 5 DAYS ☐ 3 DAYS ☐ 2 DAYS ☐ 24 HOURS ☐ RESULTS NEEDED ON WEEKEND

REQUESTED ANALYSIS

☐ LA - RWQCB REPORT FORMAT ☑ UST AGENCY:

DELIVERABLES ☐ LEVEL 1 ☐ LEVEL 2 ☐ LEVEL 3 ☑ LEVEL 4 ☐ OTHER (SPECIFY): _____

☑ SHELL CONTRACT RATE APPLIES
☐ STATE REIMBURSEMENT RATE APPLIES
☐ EDD NOT NEEDED
☑ RECEIPT VERIFICATION REQUESTED

Turn Around Time: ☑ Normal ☐ Rush ☐ Specify

*Lab Use Only*
Pressurized by:
Date:
Pressurization Gas: $N_2$ He

| LAB USE ONLY | Field Sample Identification | SAMPLING DATE | SAMPLING TIME | Canister Number | Canister Pressure/Vacuum Initial | Final | Receipt | Final (psi) | Modified TO-15 + Butane & Isopentane | ASTM D-1946 + Helium | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| CA | VMP-25-5-030613 | 03/06/13 | 825-855 | 15721 | -28 | -8.5 | | | X | X | | | | | | |
| CA | VMP-25-21-030613 | 03/06/13 | 1053-1123 | 2092 | -30 | -6.5 | | | X | X | | | | | | |
| CA | VMP-25-31-030613 | 03/06/13 | 1148-1218 | 34642 | -30 | -6 | | | X | X | | | | | | |
| | | | | | | | | | X | X | | | | | | |
| | | | | | | | | | X | X | | | | | | |
| | | | | | | | | | X | X | | | | | | |
| | | | | | | | | | X | X | | | | | | |
| | | | | | | | | | X | X | | | | | | |
| | | | | | | | | | X | X | | | | | | |
| | | | | | | | | | X | X | | | | | | |

ADDITIONAL NOTES:

- 14 day hold time
- Report results between MDL and RL
- Level IV ECVP

Custody Seal Intact?
(Y) N None Temp NA

| Relinquished by: (Signature) | Received by: (Signature) | Date | Time |
|---|---|---|---|
| | FEDEX | 3/6/13 | 1700 |
| Relinquished by: (Signature) | Received by: (Signature) | 3/07/13 | 0930 |
| Relinquished by: (Signature) | Received by: (Signature) | Date | Time |

05/2006 Revision

eurofins | Air Toxics

3/27/2013
Ms. Elizabeth Kunkel
URS Corporation
1001 Highlands Plaza Dr. West
Suite 300
St. Louis MO 63110

Project Name: Roxana Soil Vapor
Project #: 21562850.04001
Workorder #: 1303140B

Dear Ms. Elizabeth Kunkel

The following report includes the data for the above referenced project for sample(s) received on 3/7/2013 at Air Toxics Ltd.

The data and associated QC analyzed by Modified ASTM D-1946 are compliant with the project requirements or laboratory criteria with the exception of the deviations noted in the attached case narrative.

Thank you for choosing Air Toxics Ltd. for your air analysis needs. Air Toxics Ltd. is committed to providing accurate data of the highest quality. Please feel free to contact the Project Manager: Kelly Buettner at 916-985-1000 if you have any questions regarding the data in this report.

Regards,

Kelly Buettner

Project Manager

Reviewed
on
3/28/2013

eurofins | Air Toxics

# WORK ORDER #: 1303140B

Work Order Summary

| | | | |
|---|---|---|---|
| **CLIENT:** | Ms. Elizabeth Kunkel<br>URS Corporation<br>1001 Highlands Plaza Dr. West<br>Suite 300<br>St. Louis, MO 63110 | **BILL TO:** | Accounts Payable Austin<br>URS Corporation<br>P.O. BOX 203970<br>Austin, TX 78720-1088 |
| **PHONE:** | 314-743-4179 | **P.O. #** | 21562735.00013 |
| **FAX:** | | **PROJECT #** | 21562850.04001 Roxana Soil Vapor |
| **DATE RECEIVED:** | 03/07/2013 | **CONTACT:** | Kelly Buettner |
| **DATE COMPLETED:** | 03/27/2013 | | |

| FRACTION # | NAME | TEST | RECEIPT VAC./PRES. | FINAL PRESSURE |
|---|---|---|---|---|
| 01A | VMP-25-5-030613 | Modified ASTM D-1946 | 6.3 "Hg | 15.1 psi |
| 02A | VMP-25-21-030613 | Modified ASTM D-1946 | 4.8 "Hg | 15 psi |
| 03A | VMP-25-31-030613 | Modified ASTM D-1946 | 5.3 "Hg | 14.8 psi |
| 04A | Lab Blank | Modified ASTM D-1946 | NA | NA |
| 04B | Lab Blank | Modified ASTM D-1946 | NA | NA |
| 04C | Lab Blank | Modified ASTM D-1946 | NA | NA |
| 05A | LCS | Modified ASTM D-1946 | NA | NA |
| 05AA | LCSD | Modified ASTM D-1946 | NA | NA |
| 05B | LCS | Modified ASTM D-1946 | NA | NA |
| 05BB | LCSD | Modified ASTM D-1946 | NA | NA |
| 05C | LCS | Modified ASTM D-1946 | NA | NA |
| 05CC | LCSD | Modified ASTM D-1946 | NA | NA |

CERTIFIED BY: Heidi Rooyes DATE: 03/27/13

Technical Director

Certification numbers: AZ Licensure AZ0775, CA NELAP - 12282CA, NY NELAP - 11291,
TX NELAP - T104704434-12-4, UT NELAP CA009332012-3, WA NELAP - C935
Name of Accrediting Agency: NELAP/ORELAP (Oregon Environmental Laboratory Accreditation Program)
Accreditation number: CA300005, Effective date: 10/18/2012, Expiration date: 10/17/2013.
Eurofins Air Toxics Ltd. certifies that the test results contained in this report meet all requirements of the NELAC standards

This report shall not be reproduced, except in full, without the written approval of Eurofins Air Toxics, Inc.

180 BLUE RAVINE ROAD, SUITE B FOLSOM, CA - 9563
(916) 985-1000 . (800) 985-5955 . FAX (916) 985-1020

**LABORATORY NARRATIVE**
**Modified ASTM D-1946**
**URS Corporation**
**Workorder# 1303140B**

Three 1 Liter Summa Canister samples were received on March 07, 2013. The laboratory performed analysis via Modified ASTM Method D-1946 for Methane and fixed gases in air using GC/FID or GC/TCD. The method involves direct injection of 1.0 mL of sample.

On the analytical column employed for this analysis, Oxygen coelutes with Argon. The corresponding peak is quantitated as Oxygen.

Since Nitrogen is used to pressurize samples, the reported Nitrogen values are calculated by adding all the sample components and subtracting from 100%.

Method modifications taken to run these samples are summarized in the table below. Specific project requirements may over-ride the ATL modifications.

| *Requirement* | *ASTM D-1946* | *ATL Modifications* |
|---|---|---|
| Calibration | A single point calibration is performed using a reference standard closely matching the composition of the unknown. | A 3-point calibration curve is performed. Quantitation is based on a daily calibration standard which may or may not resemble the composition of the associated samples. |
| Reference Standard | The composition of any reference standard must be known to within 0.01 mol % for any component. | The standards used by ATL are blended to a >/= 95% accuracy. |
| Sample Injection Volume | Components whose concentrations are in excess of 5 % should not be analyzed by using sample volumes greater than 0.5 mL. | The sample container is connected directly to a fixed volume sample loop of 1.0 mL on the GC. Linear range is defined by the calibration curve. Bags are loaded by vacuum. |
| Normalization | Normalize the mole percent values by multiplying each value by 100 and dividing by the sum of the original values. The sum of the original values should not differ from 100% by more than 1.0%. | Results are not normalized. The sum of the reported values can differ from 100% by as much as 15%, either due to analytical variability or an unusual sample matrix. |
| Precision | Precision requirements established at each concentration level. | Duplicates should agree within 25% RPD for detections > 5 X's the RL. |

**Receiving Notes**

There were no receiving discrepancies.

**Analytical Notes**

As per project specific client request the laboratory has reported estimated values for target compound hits that are below the Reporting Limit but greater than the Method Detection Limit. Concentrations that are below the level at which the canister was certified may be false positives.

The associated comprehensive validation package provided at a later date shows the time of analysis in GMT in the raw data files. Due to software limitations the time can not be adjusted however, the time on the final PDF and EDD reports is provided in PST.

The reported Samples for each daily batch may be derived from more than one analytical file.
The reporting limit for Nitrogen was raised from 0.10% to 0.50%.

**Definition of Data Qualifying Flags**

Seven qualifiers may have been used on the data analysis sheets and indicate as follows:
B - Compound present in laboratory blank greater than reporting limit.
J - Estimated value.
E - Exceeds instrument calibration range.
S - Saturated peak.
Q - Exceeds quality control limits.
U - Compound analyzed for but not detected above the detection limit.
M - Reported value may be biased due to apparent matrix interferences.
File extensions may have been used on the data analysis sheets and indicates as follows:
a-File was requantified
b-File was quantified by a second column and detector
r1-File was requantified for the purpose of reissue

eurofins | Air Toxics

# Summary of Detected Compounds
# NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1946

**Client Sample ID: VMP-25-5-030613**

**Lab ID#: 1303140B-01A**

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.26 | 17 |
| Nitrogen | 1.3 | 81 |
| Methane | 0.00026 | 0.00025 J |
| Carbon Dioxide | 0.026 | 1.9 |

**Client Sample ID: VMP-25-21-030613**

**Lab ID#: 1303140B-02A**

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.24 | 3.9 |
| Nitrogen | 1.2 | 48 |
| Methane | 0.00024 | 31 |
| Carbon Dioxide | 0.024 | 12 |
| Ethane | 0.0024 | 0.021 |
| Helium | 0.12 | 1.7 |

**Client Sample ID: VMP-25-31-030613**

**Lab ID#: 1303140B-03A**

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.24 | 2.2 |
| Nitrogen | 1.2 | 57 |
| Methane | 0.00024 | 26 |
| Carbon Dioxide | 0.024 | 12 |
| Ethane | 0.0024 | 0.035 |

eurofins | Air Toxics

**Client Sample ID: VMP-25-5-030613**

**Lab ID#: 1303140B-01A**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1946**

| | | | |
|---|---|---|---|
| **File Name:** | **10032019B** | **Date of Collection:** | **3/6/13 9:55:00 AM** |
| **Dil. Factor:** | **2.57** | **Date of Analysis:** | **3/20/13 08:36 PM** |

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.26 | 17 |
| Nitrogen | 1.3 | 81 |
| Carbon Monoxide | 0.026 | Not Detected |
| Methane | 0.00026 | 0.00025 J |
| Carbon Dioxide | 0.026 | 1.9 |
| Ethane | 0.0026 | Not Detected |
| Ethene | 0.0026 | Not Detected |
| Helium | 0.13 | Not Detected |

J = Estimated value.

**Container Type: 1 Liter Summa Canister**

eurofins | Air Toxics

**Client Sample ID: VMP-25-21-030613**

**Lab ID#: 1303140B-02A**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1946**

| | | | |
|---|---|---|---|
| **File Name:** | **10032020B** | **Date of Collection:** | **3/6/13 11:23:00 AM** |
| **Dil. Factor:** | **2.40** | **Date of Analysis:** | **3/20/13 09:15 PM** |

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.24 | 3.9 |
| Nitrogen | 1.2 | 48 |
| Carbon Monoxide | 0.024 | Not Detected |
| Methane | 0.00024 | 31 |
| Carbon Dioxide | 0.024 | 12 |
| Ethane | 0.0024 | 0.021 |
| Ethene | 0.0024 | Not Detected |
| Helium | 0.12 | 1.7 |

**Container Type: 1 Liter Summa Canister**

eurofins | Air Toxics

**Client Sample ID: VMP-25-31-030613**

**Lab ID#: 1303140B-03A**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1946**

| | | | |
|---|---|---|---|
| **File Name:** | **10032021B** | **Date of Collection:** | **3/6/13 12:16:00 PM** |
| **Dil. Factor:** | **2.44** | **Date of Analysis:** | **3/20/13 10:24 PM** |

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.24 | 2.2 |
| Nitrogen | 1.2 | 57 |
| Carbon Monoxide | 0.024 | Not Detected |
| Methane | 0.00024 | 26 |
| Carbon Dioxide | 0.024 | 12 |
| Ethane | 0.0024 | 0.035 |
| Ethene | 0.0024 | Not Detected |
| Helium | 0.12 | Not Detected |

**Container Type: 1 Liter Summa Canister**

eurofins | Air Toxics

**Client Sample ID: Lab Blank**

**Lab ID#: 1303140B-04A**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1946**

| | | | |
|---|---|---|---|
| **File Name:** | **10032005Ba** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 3/20/13 01:11 PM** | |

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Oxygen | 0.10 | 0.016 J |
| Nitrogen | 0.50 | 0.098 J |
| Carbon Monoxide | 0.010 | Not Detected |
| Carbon Dioxide | 0.010 | Not Detected |

J = Estimated value.

**Container Type: NA - Not Applicable**

eurofins | Air Toxics

**Client Sample ID: Lab Blank**

**Lab ID#: 1303140B-04B**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1946**

| | | | |
|---|---|---|---|
| **File Name:** | **10032004C** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 3/20/13 12:47 PM** | |

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Helium | 0.050 | Not Detected |

**Container Type: NA - Not Applicable**

eurofins | Air Toxics

**Client Sample ID: Lab Blank**

**Lab ID#: 1303140B-04C**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1946**

| | | | |
|---|---|---|---|
| **File Name:** | **9031903a** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 3/19/13 05:58 AM** | |

| Compound | Rpt. Limit (%) | Amount (%) |
|---|---|---|
| Methane | 0.00010 | 0.000032 J |
| Ethane | 0.0010 | Not Detected |
| Ethene | 0.0010 | Not Detected |

J = Estimated value.

**Container Type: NA - Not Applicable**

eurofins | Air Toxics

**Client Sample ID: LCS**

**Lab ID#: 1303140B-05A**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1946**

| | | | |
|---|---|---|---|
| **File Name:** | **10032002Ba** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 3/20/13 07:02 PM** | |

| Compound | %Recovery |
|---|---|
| Oxygen | 101 |
| Nitrogen | 100 |
| Carbon Monoxide | 100 |
| Carbon Dioxide | 101 |

**Container Type: NA - Not Applicable**

eurofins | Air Toxics

**Client Sample ID: LCSD**

**Lab ID#: 1303140B-05AA**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1946**

| | | | |
|---|---|---|---|
| **File Name:** | **10032029Ba** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 3/21/13 02:56 AM** | |

| Compound | %Recovery |
|---|---|
| Oxygen | 101 |
| Nitrogen | 100 |
| Carbon Monoxide | 100 |
| Carbon Dioxide | 100 |

**Container Type: NA - Not Applicable**

eurofins | Air Toxics

**Client Sample ID: LCS**

**Lab ID#: 1303140B-05B**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1946**

| | | | |
|---|---|---|---|
| **File Name:** | **10032002Ca** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 3/20/13 07:02 PM** | |

| Compound | %Recovery |
|---|---|
| Helium | 100 |

**Container Type: NA - Not Applicable**

eurofins | Air Toxics

**Client Sample ID: LCSD**

**Lab ID#: 1303140B-05BB**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1946**

| | | | |
|---|---|---|---|
| **File Name:** | **10032029Ca** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 3/21/13 02:56 AM** | |

| Compound | %Recovery |
|---|---|
| Helium | 100 |

**Container Type: NA - Not Applicable**

eurofins | Air Toxics

**Client Sample ID: LCS**

**Lab ID#: 1303140B-05C**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1946**

| | | | |
|---|---|---|---|
| **File Name:** | **9031902** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 3/19/13 05:36 AM** | |

| Compound | %Recovery |
|---|---|
| Methane | 98 |
| Ethane | 100 |
| Ethene | 99 |

**Container Type: NA - Not Applicable**

eurofins | Air Toxics

**Client Sample ID: LCSD**

**Lab ID#: 1303140B-05CC**

**NATURAL GAS ANALYSIS BY MODIFIED ASTM D-1946**

| | | | |
|---|---|---|---|
| **File Name:** | **9031925** | **Date of Collection: NA** | |
| **Dil. Factor:** | **1.00** | **Date of Analysis: 3/19/13 07:15 PM** | |

| Compound | %Recovery |
|---|---|
| Methane | 98 |
| Ethane | 101 |
| Ethene | 100 |

**Container Type: NA - Not Applicable**

1303140

# Shell Oil Products Chain Of Custody Record

URS

Air Toxics LTD.
**Project Name: Roxana Soil Vapor**
**Project # 21562850.04001**
Lab Vendor #

Please Check Appropriate Box:
☑ ENV. SERVICES ☐ MOTIVA RETAIL ☐ SHELL RETAIL
☐ MOTIVA S/B&CM ☐ CONSULTANT ☐ LUBES
☐ SHELL PIPELINE ☐ OTHER

Print Bill To Contact Name: Robert Moosnegian
INCIDENT # (ENV SERVICES): 9 7 2 1 6 6 4 0 ☐ CHECK IF NO INCIDENT # APPLIES
PO #:
SAP #: 3 4 0 0 6 1
DATE: 03/06/13
PAGE: 1 of 1

SAMPLING COMPANY: URS CORPORATION
LOG CODE:
SITE ADDRESS: Street and City: 900 SOUTH CENTRAL AVE – ROXANA
State: IL
GLOBAL ID NO:
ADDRESS: 1001 HIGHLANDS PLAZA DRIVE WEST - SUITE 300, ST LOUIS, MO 63110
EDF DELIVERABLE TO (Name, Company, Office Location): Elizabeth Kunkel, URS, St. Louis
PHONE NO.: 314-743-4179
E-MAIL: Elizabeth_Kunkel@URSCorp.com
CONSULTANT PROJECT NAME#: Roxana Soil Vapor
Laboratory Address: Air Toxics, LTD 180 Blue Ravine Road, Suite B, Folsom, CA 95630-4719
E. Arthur, M. Corbett
TELEPHONE:
FAX: 314-429-0462
Bill To Contact E-MAIL: Robert.Moosnegian@urs.com

TURNAROUND TIME (CALENDAR DAYS):
☑ STANDARD (14 DAY) ☐ 5 DAYS ☐ 3 DAYS ☐ 2 DAYS ☐ 24 HOURS ☐ RESULTS NEEDED ON WEEKEND

☐ LA - RWQCB REPORT FORMAT ☑ UST AGENCY:

DELIVERABLES: ☐ LEVEL 1 ☐ LEVEL 2 ☐ LEVEL 3 ☑ LEVEL 4 ☐ OTHER (SPECIFY):

☑ SHELL CONTRACT RATE APPLIES
☐ STATE REIMBURSEMENT RATE APPLIES
☐ EDD NOT NEEDED
☑ RECEIPT VERIFICATION REQUESTED

REQUESTED ANALYSIS

| Lab Use Only | Field Sample Identification | SAMPLING DATE | SAMPLING TIME | Canister Number | Canister Pressure/Vacuum Initial | Final | Receipt | Final (psi) | Modified TO-15 + Butane & Isopentane | ASTM D-1946 + Helium |
|---|---|---|---|---|---|---|---|---|---|---|
| 01A | VMP-25-5-030613 | 03/06/13 | 825-935 | 16721 | -28 | -8.5 | | | X | X |
| 02A | VMP-25-21-030613 | 03/06/13 | 1053-1123 | 2062 | -30 | -6.5 | | | X | X |
| 03A | VMP-25-31-030613 | 03/06/13 | 1145-1218 | 34642 | -30 | -8 | | | X | X |
| | | | | | | | | | X | X |
| | | | | | | | | | X | X |
| | | | | | | | | | X | X |
| | | | | | | | | | X | X |
| | | | | | | | | | X | X |
| | | | | | | | | | X | X |
| | | | | | | | | | X | X |

Turn Around Time: ☑ Normal ☐ Rush ☐ Specify

Lab Use Only
Pressurized by:
Date:
Pressurization Gas: $N_2$ He

ADDITIONAL NOTES:
- 14 day hold time
- Report results between MDL and RL
- Level IV ECVP

FedEx
Custody Seal Intact?
(Y) N None Temp NA

| Relinquished by: (Signature) | Received by: (Signature) | Date | Time |
|---|---|---|---|
| | FEDEX | 3/6/13 | 1700 |
| Relinquished by: (Signature) | Received by: (Signature) | Date | Time |
| | | 3/07/13 | 0930 |
| Relinquished by: (Signature) | Received by: (Signature) | Date | Time |
| | | | |

05/2006 Revision

**APPENDIX B**

**SVE SYSTEM LEG FLOW RATES**

| Date | Red Leg Flow (SCFM) | Blue Leg Flow (SCFM) | Green Leg Flow (SCFM) | Teal Leg Flow (SCFM) | Purple Leg Flow (SCFM) | Brown Leg Flow (SCFM) |
|---|---|---|---|---|---|---|
| 04/12/12 | 32 | 38 | 101 | 41 | 48 | 44 |
| 04/19/12 | 24 | 28 | 67 | 34 | 37 | 33 |
| 04/26/12 | 29 | 31 | 53 | 35 | 39 | 36 |
| 05/03/12 | 23 | 29 | 87 | 35 | 40 | 40 |
| 05/10/12 | 31 | 34 | 98 | 35 | 43 | 43 |
| 05/17/12 | 31 | 39 | 103 | 43 | 50 | 47 |
| 05/24/12 | 28 | 35 | 93 | 37 | 49 | 45 |
| 06/07/12 | 31 | 32 | 92 | 43 | 47 | 46 |
| 06/14/12 | 33 | 22 | 95 | 48 | 48 | 48 |
| 06/21/12 | 32 | 26 | 105 | 43 | 56 | 49 |
| 06/28/12 | 24 | 28 | 100 | 125 | 50 | 43 |
| 07/05/12 | 26 | 37 | 100 | 41 | 47 | 43 |
| 07/12/12 | 36 | 47 | 113 | 46 | 52 | 51 |
| 07/19/12 | 31 | 44 | 110 | 44 | 52 | 48 |
| 07/26/12 | 28 | 43 | 112 | 40 | 54 | 49 |
| 08/02/12 | 34 | 46 | 119 | 47 | 56 | 51 |
| 08/09/12 | 35 | 46 | 116 | 43 | 56 | 51 |
| 08/23/12 | 38 | 50 | 126 | 55 | 59 | 59 |
| 08/30/12 | 41 | 55 | 134 | 57 | 66 | 64 |
| 09/06/12 | 38 | 53 | 129 | 56 | 63 | 64 |
| 09/13/12 | 43 | 56 | 134 | 65 | 67 | 71 |
| 09/20/12 | 53 | 77 | 128 | 86 | 88 | 93 |
| 09/27/12 | 56 | 79 | 179 | 91 | 93 | 95 |
| 10/11/12 | 67 | 54 | 190 | 33 | 112 | 113 |
| 10/18/12 | 60 | 46 | 164 | 28 | 100 | 102 |
| 10/26/12 | 45 | 32 | 152 | 14 | 71 | 79 |
| 11/01/12 | 55 | 79 | 180 | 125 | 93 | 94 |
| 11/16/12 | 52 | 71 | 170 | 236 | 93 | 90 |
| 11/29/12 | 51 | 73 | 172 | 115 | 53 | 87 |
| 12/04/12 | 29 | 37 | 81 | 54 | 41 | 42 |
| 01/10/13 | 36 | 46 | 99 | 82 | 59 | 52 |
| 01/17/13 | 31 | 25 | 94 | 37 | 48 | 46 |
| 01/24/13 | 27 | 16 | 101 | 96 | 65 | 46 |
| 02/07/13 | 31 | 37 | 75 | 104 | 51 | 53 |
| 02/14/13 | 29 | 33 | 67 | 100 | 47 | 49 |
| 02/20/13 | 27 | 33 | 66 | 102 | 47 | 46 |
| 02/25/13 | 31 | 38 | 78 | 92 | 55 | 52 |
| 02/28/13 | 27 | 32 | 70 | 100 | 44 | 43 |
| 03/01/13 | 27 | 33 | 72 | 103 | 49 | 50 |
| 03/07/13 | 38 | 47 | 102 | 127 | 60 | 59 |

**APPENDIX B**

**SVE SYSTEM LEG FLOW RATES**

| Date | Red Leg Flow (SCFM) | Blue Leg Flow (SCFM) | Green Leg Flow (SCFM) | Teal Leg Flow (SCFM) | Purple Leg Flow (SCFM) | Brown Leg Flow (SCFM) |
|---|---|---|---|---|---|---|
| 03/14/13 | 59 | 70 | 173 | 157 | 94 | 94 |
| 03/21/13 | 56 | 69 | 53 | 136 | 114 | 94 |
| 03/28/13 | 35 | 41 | 107 | 124 | 64 | 67 |

**APPENDIX C**
**TOTAL HEADER HYDROCARBON CONCENTRATIONS**

| Date | West Fenceline Concentration (ppmv) | Public Works Concentration (ppmv) |
|---|---|---|
| 4/12/2012 | 134,000 | 517,000 |
| 4/19/2012 | 59,300 | 611,000 |
| 4/26/2012 | 113,000 | 476,000 |
| 5/3/2012 | 87,400 | 340,000 |
| 5/10/2012 | 165,000 | 410,000 |
| 5/17/2012 | 132,000 | 350,000 |
| 5/24/2012 | 115,000 | 352,000 |
| 6/7/2012 | 101,000 | 203,000 |
| 6/14/2012 | 101,000 | 176,000 |
| 6/21/2012 | 117,000 | 239,000 |
| 6/28/2012 | 106,000 | 292,000 |
| 7/5/2012 | 98,100 | 212,000 |
| 7/12/2012 | 85,150 | 127,000 |
| 7/19/2012 | 105,000 | 225,000 |
| 7/26/2012 | 103,000 | 195,000 |
| 8/2/2012 | 103,000 | 202,000 |
| 8/9/2012 | 95,600 | 154,000 |
| 8/23/2012 | 53,800 | 120,000 |
| 8/30/2012 | 76,200 | 140,000 |
| 9/6/2012 | 102,000 | 181,000 |
| 9/13/2012 | 67,200 | 143,000 |
| 9/20/2012 | 68,100 | 205,000 |
| 9/27/2012 | 62,600 | 156,000 |
| 10/11/2012 | 79,900 | 205,000 |
| 10/18/2012 | 47,600 | 185,000 |
| 10/26/2012 | 21,400 | 176,000 |
| 11/1/2012 | 20,200 | 215,000 |
| 11/16/2012 | 25,900 | 103,000 |
| 11/29/2012 | 17,600 | 191,000 |
| 12/6/2012 | 64,300 | 170,000 |
| 01/10/13 | 69,600 | 58,500 |
| 01/17/13 | 64,500 | 40,000 |
| 01/24/13 | 63,000 | 5,700 |
| 02/07/13 | 53,400 | 56,200 |
| 02/14/13 | 55,900 | 41,000 |
| 02/20/13 | 54,900 | 49,800 |
| 02/25/13 | 60,000 | 51,600 |
| 02/28/13 | 54,500 | 40,700 |
| 03/01/13 | 51,600 | 55,800 |

**APPENDIX C**
**TOTAL HEADER HYDROCARBON CONCENTRATIONS**

| Date | West Fenceline Concentration (ppmv) | Public Works Concentration (ppmv) |
|---|---|---|
| 03/07/13 | 62,800 | 58,600 |
| 03/14/13 | 59,170 | 61,600 |
| 03/21/13 | 50,900 | 58,400 |
| 03/28/13 | 43,600 | 14,900 |

**APPENDIX D**
**SVE SYSTEM FLOW RATES**

| Date | West Fenceline Header (SCFM) | Public Works Header (SCFM) |
|---|---|---|
| 4/12/2012 | 262 | 41 |
| 4/19/2012 | 189 | 34 |
| 4/26/2012 | 765 | 35 |
| 5/3/2012 | 772 | 35 |
| 5/10/2012 | 251 | 35 |
| 5/17/2012 | 270 | 43 |
| 5/24/2012 | 352 | 37 |
| 6/7/2012 | 570 | 43 |
| 6/14/2012 | 334 | 48 |
| 6/21/2012 | 355 | 43 |
| 6/28/2012 | 333 | 125 |
| 7/5/2012 | 340 | 41 |
| 7/12/2012 | 361 | 46 |
| 7/19/2012 | 348 | 44 |
| 7/26/2012 | 349 | 40 |
| 8/2/2012 | 307 | 47 |
| 8/9/2012 | 305 | 43 |
| 8/23/2012 | 333 | 55 |
| 8/30/2012 | 359 | 57 |
| 9/6/2012 | 347 | 56 |
| 9/13/2012 | 371 | 65 |
| 9/20/2012 | 439 | 86 |
| 9/27/2012 | 501 | 91 |
| 10/11/2012 | 958 | 33 |
| 10/18/2012 | 894 | 28 |
| 10/26/2012 | 467 | 14 |
| 11/1/2012 | 588 | 125 |
| 11/16/2012 | 477 | 236 |
| 11/29/2012 | 436 | 115 |
| 12/4/2012 | 230 | 54 |
| 01/10/13 | 292 | 82 |
| 01/17/13 | 244 | 37 |
| 01/24/13 | 255 | 96 |
| 02/07/13 | 247 | 104 |
| 02/14/13 | 224 | 100 |
| 02/20/13 | 219 | 102 |
| 02/25/13 | 254 | 92 |
| 02/28/13 | 216 | 100 |
| 03/01/13 | 231 | 103 |
| 03/07/13 | 306 | 127 |
| 03/14/13 | 490 | 157 |

**APPENDIX D**

**SVE SYSTEM FLOW RATES**

| Date | West Fenceline Header (SCFM) | Public Works Header (SCFM) |
|---|---|---|
| 03/21/13 | 385 | 136 |
| 03/28/13 | 314 | 124 |