



ILLINOIS ENVIRONMENTAL PROTECTION AGENCY

1021 NORTH GRAND AVENUE EAST, P.O. BOX 19276, SPRINGFIELD, ILLINOIS 62794-9276 • (217) 782-3397

BRUCE RAUNER, GOVERNOR

ALEC MESSINA, DIRECTOR

217/524-3300

OCT 12 2017

October 10, 2017

CERTIFIED MAIL
7014 2120 0002 3286 4349
7014 2120 0002 3286 4356

BY: _____

Shell Oil Products US
Attn: Kevin Dyer
17 Junction Drive
PMB #399
Glen Carbon, Illinois 62304

WRB Refining LLC Wood River Refinery
Attn: Brian Wulf
900 South Central Avenue
P.O. Box 76
Roxana, Illinois 62084

Re: 1191150002—Madison County
Equilon Enterprises d/b/a Shell Oil Products US
ILD 080 012 305
Log No. B-43R-CA-82, 88, 94 and 97
Received: July 7, 2014, August 3, 2015, April 5, 2017 and June 30, 2017
RCRA Permit
Permits CA

Dear Mr. Dyer and Mr. Wulf:

This is in response to the July 3, 2014, August 3, 2015, April 4, 2017 and June 29, 2017 submittals from AECOM made on your behalf regarding certain aspects of the RCRA corrective action activities and groundwater monitoring/remediation efforts being carried out by Shell Oil Products US (Shell) at the above-referenced RCRA permitted facility. This facility is located at 900 South Central Avenue, Roxana, Illinois; the RCRA permit for this facility was renewed on October 28, 2010 and last revised on July 29, 2015.

The specific submittals being responded to herein are as follows:

Submittal No. 1 – The submittal entitled “Routine Updates to Previously Submitted Standard Operating Procedures” is dated July 3, 2014, and was received by the Illinois EPA on July 7, 2014.

Submittal No. 2 – The submittal entitled “Routine Updates to Previously Submitted Standard Operating Procedures” is dated August 3, 2015 and was received by the Illinois EPA on August 6, 2015.

Submittal No. 3 – The submittal entitled “Routine Updates to Previously Submitted Standard Operating Procedures” is dated April 4, 2017 and was received by the Illinois EPA on April 5, 2017.

Submittal No. 4—The subject submittal entitled “Routine Updates to Previously Submitted Standard Operating Procedures”, is dated June 29, 2017 and was received by the Illinois EPA on June 30, 2017.


As their names imply, each of the above submittals contain certain updated standard operating procedures used in carrying out the RCRA corrective action efforts, groundwater monitoring and groundwater remediation efforts required to be implemented by the subject facility's RCRA permit. These submittals were handled as modification requests to the approved corrective action RCRA program being carried out at the above-referenced facility and are hereby approved subject to the following conditions and modifications:

1. Within ninety (90) days, must submit, as a Class 1* permit modification request, revised pages to Section C.7.5 of the Approved Permit Renewal Application to refer to the most current SOPs. A completed LPCPA-23 form must accompany this submittal.
2. Corrective action activities at the subject facility must be carried out in accordance with: (1) 35 Ill. Adm. Code 620, 724 and 742; (2) the facility's RCRA permit; and (3) Illinois EPA letters regarding such activities.
3. A completed RCRA Corrective Action Certification form must accompany all information submitted to Illinois EPA regarding RCRA corrective action activities at the subject facility.

Work required by this letter, your submittal, or the regulations may also be subject to other laws governing professional services, such as the Illinois Professional Land Surveyor Act of 1989, the Professional Engineering Act of 1989, the Professional Geologist Licensing Act and the Structural Engineering Act of 1989. This letter does not relieve anyone from compliance with these laws. All work that falls within the scope and definition of these laws must be performed in compliance with them. The Illinois EPA may refer any discovered violation to the appropriate regulating authority.

Should you have any questions regarding groundwater related aspects of the corrective action being carried out at this facility, please contact Amy Boley at 217/558-4716. If you have questions regarding other aspects of corrective action, please contact William T. Sinnott, II at 217/524-3310.

Sincerely,



Theodore J. Dragovich, P.E., Acting Manager
Permit Section
Division of Land Pollution Control
Bureau of Land

TJD:WTS:1191150002-RCRA-B43R-CA-82, 88, 94, and 97

JKM AMB-TBM